



Normal

Unit ID: 1112 Asset ID: 50203172

Description: **Cat 775F Trans**

Account Information

ID: 402009

Name: **Greer Lime**

Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US

Parent Account: MATTHEWS LUBRICANTS, INC.

Sample Information

Sample ID: 25296470038

Service Level: **Essential**

Bottle ID: **a037322651**

Tested Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 30

Equipment Information

Asset Class: **Transmission**





Manufacturer:

Model:

Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY
TRANS FLUID 30

Sample Data & Trends

Sample Info	Report Status	Alert	Alert	Alert	Alert	Normal
	Sample ID	21245357015	22124148056	24010131035	24281148047	25296470038
	Service Level	Essential	Essential	Essential	Essential	Essential
	Bottle ID	a004755536	a023870504	a030128522	a033571134	a037322651
	Tested Lubricant	MOBILTRANS HD 30	MOBILTRANS HD 30	MOBILTRANS HD 30	MOBILTRANS HD 30	MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 30
	Sampled	26 Jul 2021	21 Apr 2022	27 Dec 2023	27 Sep 2024	13 Oct 2025
	Reported	07 Sep 2021	12 May 2022	15 Jan 2024	10 Oct 2024	24 Oct 2025
	Equipment Age	23838	24967	28106	29624	31400
	Equipment UOM	Hours	Hours	Hours	Hours	Hours
	Oil Age					
	Make-up Volume					
	Oil Changed		No	Yes	Yes	No
Filter Changed	Yes	Yes	Yes	Yes	Yes	
Lubricant	Contamination Rating	Normal	Normal	Normal	Normal	Normal
	Equipment Rating	Alert	Alert	Alert	Alert	Normal
	Lubricant Rating	Normal	Normal	Normal	Normal	Normal
	Visc@100C (cSt)	10.7	10.9	11.0	10.7	10.7
	Oxidation (Ab/cm)	2	3	6	3	3
	Water (Vol.%)	NotDetected	NotDetected	NotDetected	NotDetected	NotDetected
Wear (ppm)	Ag (Silver)	1	1	1	0	0
	Al (Aluminum)	1	2	2	1	1
	Cr (Chromium)	0	0	0	0	0
	Cu (Copper)	57	67	381	89	30
	Fe (Iron)	10	14	27	27	6
	Mo (Molybdenum)	0	1	1	2	1
	Ni (Nickel)	0	0	0	0	1
	Pb (Lead)	6	6	5	2	5
Contaminant (ppm)	Sn (Tin)	1	2	3	6	0
	K (Potassium)	2	1	2	3	0
	Na (Sodium)	6	7	11	3	1
Additive (ppm)	Si (Silicon)	5	5	6	8	6
	B (Boron)	3	3	3	5	3
	Ba (Barium)	0	0	0	0	0
	Ca (Calcium)	2832	3020	3169	3312	3847
	Mg (Magnesium)	23	23	25	18	15
	P (Phosphorus)	1032	1026	1077	1014	1064
Zn (Zinc)	1097	1185	1204	1076	1173	



	Normal	
	Unit ID: 1112	Asset ID: 50203172
	Description: Cat 775F Trans	
Account Information	Sample Information	Equipment Information
ID: 402009 Name: Greer Lime Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US Parent Account: MATTHEWS LUBRICANTS, INC.	Sample ID: 25296470038 Service Level: Essential Bottle ID: a037322651 Tested Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 30	Asset Class: Transmission Manufacturer: Model: Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 30

Continued

Recommendation/Comments

NO ACTION REQUIRED ON OIL OR EQUIPMENT. Results indicate that all levels are within acceptable ranges. Examine progressive changes and monitor results for changing trends. Sample at next scheduled interval. Contact your ExxonMobil representative for further assistance if necessary.

Sample Timeline

- 13 Oct 2025 3:13 PM UTC - Josh Simmons - In Service Oil Sample Comments: Photo: