



Normal

Unit ID: 1212 Asset ID: 51414386

Description: **transmission**

Account Information

ID: 402009

Name: **Greer Lime**

Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US

Parent Account: MATTHEWS LUBRICANTS, INC.

Sample Information

Sample ID: **25296470037**

Service Level: **Essential**

Bottle ID: **a037322765**

Tested Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 30

Equipment Information

Asset Class: **Transmission**





Manufacturer: **CATERPILLAR**

Model:

Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY
TRANS FLUID 30

Sample Data & Trends

Sample Info	Report Status	Normal	Normal	Normal	Normal	Normal
	Sample ID	24010131053	24122146009	25059237023	25111382019	25296470037
	Service Level	Essential	Essential	Essential	Essential	Essential
	Bottle ID	a030120307	a029199077	a033569453	a033668717	a037322765
	Tested Lubricant	MOBILTRANS HD 30	MOBILTRANS HD 30	MOBILTRANS HD 30	MOBILTRANS HD 30	MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 30
	Sampled	04 Jan 2024	25 Apr 2024	11 Dec 2024	02 Apr 2025	13 Oct 2025
	Reported	15 Jan 2024	08 May 2024	04 Mar 2025	23 Apr 2025	24 Oct 2025
	Equipment Age	10738		13369	14245	15726
	Equipment UOM	Hours		Hours	Hours	Hours
	Oil Age					
	Make-up Volume					
	Oil Changed	No	Yes	Yes	No	Yes
Filter Changed	Yes	No	Yes	Yes	Yes	
Lubricant	Contamination Rating	Normal	Normal	Normal	Normal	Normal
	Equipment Rating	Normal	Normal	Normal	Normal	Normal
	Lubricant Rating	Normal	Normal	Normal	Normal	Normal
	Visc@100C (cSt)	11.0	10.8	10.6	10.6	10.7
	Oxidation (Ab/cm)	2	2	2	2	2
	Water (Vol.%)	NotDetected	NotDetected	NotDetected	NotDetected	NotDetected
Wear (ppm)	Ag (Silver)	0	0	0	0	0
	Al (Aluminum)	1	1	1	1	1
	Cr (Chromium)	0	0	0	0	0
	Cu (Copper)	2	2	3	3	3
	Fe (Iron)	8	9	28	16	15
	Mo (Molybdenum)	1	1	1	1	2
	Ni (Nickel)	0	0	0	0	1
	Pb (Lead)	0	1	0	0	1
	Sn (Tin)	1	2	0	0	1
Contaminant (ppm)	K (Potassium)	0	0	1	0	0
	Na (Sodium)	1	3	1	1	0
	Si (Silicon)	5	4	5	5	7
Additive (ppm)	B (Boron)	2	3	1	2	3
	Ba (Barium)	0	1	0	0	0
	Ca (Calcium)	3309	3311	3413	3511	3776
	Mg (Magnesium)	14	13	12	14	26
	P (Phosphorus)	966	961	933	1005	1070
	Zn (Zinc)	1105	1054	1046	1132	1147



	Normal	
	Unit ID: 1212	Asset ID: 51414386
	Description: transmission	
Account Information	Sample Information	Equipment Information
ID: 402009 Name: Greer Lime Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US Parent Account: MATTHEWS LUBRICANTS, INC.	Sample ID: 25296470037 Service Level: Essential Bottle ID: a037322765 Tested Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 30	Asset Class: Transmission Manufacturer: CATERPILLAR Model: Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 30

Continued

Recommendation/Comments

NO ACTION REQUIRED ON OIL OR EQUIPMENT. Results indicate that all levels are within acceptable ranges. Examine progressive changes and monitor results for changing trends. Sample at next scheduled interval. Contact your ExxonMobil representative for further assistance if necessary.

Sample Timeline

- 13 Oct 2025 3:25 PM UTC - Josh Simmons - In Service Oil Sample Comments: Photo: