


|                                                                         |                  |                                                            |
|-------------------------------------------------------------------------|------------------|------------------------------------------------------------|
| <div>Mobil™</div>                                                       | Normal           |                                                            |
|                                                                         | Unit ID: 1196    | Asset ID: 52166369                                         |
|                                                                         | Description: hyd |                                                            |
| Account Information                                                     |                  | Equipment Information                                      |
| ID: 402009                                                              |                  | Asset Class: Hydraulic                                     |
| Name: Greer Lime                                                        |                  | Manufacturer: CATERPILLAR                                  |
| Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US |                  | Model:                                                     |
| Parent Account: MATTHEWS LUBRICANTS, INC.                               |                  | Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 10W |
| Sample Information                                                      |                  |                                                            |
| Sample ID: 25296470060                                                  |                  |                                                            |
| Service Level: Essential                                                |                  |                                                            |
| Bottle ID: a037062559                                                   |                  |                                                            |
| Tested Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 10W       |                  |                                                            |


## Sample Data & Trends

|                   |                      |                                                 |
|-------------------|----------------------|-------------------------------------------------|
| Sample Info       | Report Status        | Normal                                          |
|                   | Sample ID            | 25296470060                                     |
|                   | Service Level        | Essential                                       |
|                   | Bottle ID            | a037062559                                      |
|                   | Tested Lubricant     | MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 10W |
|                   | Sampled              | 10 Sep 2025                                     |
|                   | Reported             | 24 Oct 2025                                     |
|                   | Equipment Age        |                                                 |
|                   | Oil Age              |                                                 |
|                   | Make-up Volume       |                                                 |
|                   | Oil Changed          | No                                              |
|                   | Filter Changed       | No                                              |
| Lubricant         | Contamination Rating | Normal                                          |
|                   | Equipment Rating     | Normal                                          |
|                   | Lubricant Rating     | Normal                                          |
|                   | Visc@100C (cSt)      | 5.9                                             |
|                   | Oxidation (Ab/cm)    | 2                                               |
| Wear (ppm)        | Water (Vol.%)        | NotDetected                                     |
|                   | Ag (Silver)          | 0                                               |
|                   | Al (Aluminum)        | 1                                               |
|                   | Cr (Chromium)        | 0                                               |
|                   | Cu (Copper)          | 1                                               |
|                   | Fe (Iron)            | 5                                               |
|                   | Mo (Molybdenum)      | 1                                               |
|                   | Ni (Nickel)          | 0                                               |
|                   | Pb (Lead)            | 0                                               |
| Contaminant (ppm) | Sn (Tin)             | 0                                               |
|                   | K (Potassium)        | 1                                               |
|                   | Na (Sodium)          | 1                                               |
|                   | Si (Silicon)         | 11                                              |
| Additive (ppm)    | B (Boron)            | 5                                               |
|                   | Ba (Barium)          | 0                                               |
|                   | Ca (Calcium)         | 3679                                            |
|                   | Mg (Magnesium)       | 15                                              |
|                   | P (Phosphorus)       | 1021                                            |
|                   | Zn (Zinc)            | 1098                                            |


### Viscosity




### Wear



### Contaminants



### Physical Properties



|                                                                         | Normal                                                                                                                                           |                                                                                                                             |
|--------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------|
|                                                                                                                                                        | Unit ID: 1196                                                                                                                                    | Asset ID: 52166369                                                                                                          |
|                                                                                                                                                        | Description: hyd                                                                                                                                 |                                                                                                                             |
| Account Information                                                                                                                                    | Sample Information                                                                                                                               | Equipment Information                                                                                                       |
| ID: 402009<br>Name: Greer Lime<br>Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US<br>Parent Account: MATTHEWS LUBRICANTS, INC. | Sample ID: 25296470060<br>Service Level: Essential<br>Bottle ID: a037062559<br>Tested Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 10W | Asset Class: Hydraulic<br>Manufacturer: CATERPILLAR<br>Model:<br>Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 10W |

Continued

Recommendation/Comments

NO ACTION REQUIRED ON OIL OR EQUIPMENT. Results indicate that all levels are within acceptable ranges. Examine progressive changes and monitor results for changing trends. Sample at next scheduled interval. Contact your ExxonMobil representative for further assistance if necessary.

Sample Timeline

- 10 Sep 2025 3:29 PM UTC - Josh Simmons - In Service Oil Sample    Comments: Photo: