

Mobil™

Unit ID: 5-BM-2

Asset ID: 50074753

Description: Kiln 1 Ball Mill Gear Box

Account Information

Sample Information

Equipment Information

ID: 402009

Name: Greer Lime

Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US

Parent Account: MATTHEWS LUBRICANTS, INC.

Sample ID: 25308280023

Service Level: Essential

Bottle ID: a003623520

Tested Lubricant: MOBIL SHC GEAR 220

Asset Class: Gear Drive





Manufacturer: FALK (REXNORD)

Model: 1090FC2

Lubricant: MOBIL SHC GEAR 220

Sample Data & Trends

Sample Info	Report Status	Alert	Caution	Normal	Caution	Normal
	Sample ID	24068404075	24162579019	24330183020	25147288013	25308280023
	Service Level	Essential	Essential	Essential	Essential	Essential
	Bottle ID	a022174320	a003623010	a033582515	a030135393	a003623520
	Tested Lubricant	MOBIL SHC GEAR 220	MOBIL SHC GEAR 220	MOBIL SHC GEAR 220	MOBIL SHC GEAR 220	MOBIL SHC GEAR 220
	Sampled	28 Feb 2024	03 Jun 2024	13 Nov 2024	18 May 2025	17 Jul 2025
	Reported	15 Mar 2024	18 Jun 2024	27 Nov 2024	29 May 2025	06 Nov 2025
	Equipment Age					
	Oil Age					
	Make-up Volume					
	Oil Changed					
	Filter Changed					
Lubricant	Contamination Rating	Normal	Normal	Normal	Normal	Normal
	Equipment Rating	Normal	Normal	Normal	Normal	Normal
	Lubricant Rating	Alert	Caution	Normal	Caution	Normal
	Visc@40C (cSt)	363.5	248.2	235.8	242.2	238.5
	TAN (mg KOH/g)	2.28	0.40	0.10	0.41	0.36
Wear (ppm)	Water (Hot Plate)	NotDetected	NotDetected	NotDetected	NotDetected	NotDetected
	Ag (Silver)	0	0	0	0	0
	Al (Aluminum)	0	0	0	0	0
	Cr (Chromium)	0	0	0	0	0
	Cu (Copper)	0	1	0	0	0
	Fe (Iron)	13	0	1	0	2
	Mo (Molybdenum)	3	2	0	0	0
	Ni (Nickel)	0	0	0	0	0
	Pb (Lead)	0	1	0	0	1
Contaminant (ppm)	Sn (Tin)	0	2	0	0	2
	K (Potassium)	1	0	0	0	0
	Na (Sodium)	0	0	0	0	1
Additive (ppm)	Si (Silicon)	1	0	2	0	1
	B (Boron)	0	1	0	1	1
	Ba (Barium)	1	0	0	0	0
	Ca (Calcium)	93	3	4	3	1
	Mg (Magnesium)	1	0	0	0	0
	P (Phosphorus)	407	345	378	346	327
	Zn (Zinc)	423	6	1	7	2



	Normal	
	Unit ID: 5-BM-2	Asset ID: 50074753
	Description: Kiln 1 Ball Mill Gear Box	
Account Information	Sample Information	Equipment Information
ID: 402009 Name: Greer Lime Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US Parent Account: MATTHEWS LUBRICANTS, INC.	Sample ID: 25308280023 Service Level: Essential Bottle ID: a003623520 Tested Lubricant: MOBIL SHC GEAR 220	Asset Class: Gear Drive Manufacturer: FALK (REXNORD) Model: 1090FC2 Lubricant: MOBIL SHC GEAR 220

Continued

Recommendation/Comments

NO ACTION REQUIRED ON OIL OR EQUIPMENT. Results indicate that all levels are within acceptable ranges. Examine progressive changes and monitor results for changing trends. Sample at next scheduled interval. Contact your ExxonMobil representative for further assistance if necessary.

Sample Timeline

- 17 Jul 2025 7:29 PM UTC - Brad Roy - In Service Oil Sample Comments: Photo: