

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

Cooling Tower Fan Motor • Utility Yard

79% HEALTH (GOOD)

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

Signals Monitored

6

Threshold Breaches

0

Excursion Events

2

System Alerts

1


DIAGNOSTIC & ENGINEERING INSIGHTS

- Operating Health Score is evaluated at 79% (Good).
- Identified 1 critical severity alert(s) during the period requiring priority maintenance intervention.
- All monitored telemetry channels remained within manufacturer engineering boundaries.

TELEMETRY SIGNALS SUMMARY & STATISTICAL LIMITS

Signal / Channel	Unit	Safe Limits	Min	Max	Mean	Samples	Status
Winding_Temp_U	°C	10 - 130	56.2	75.8	66.1	20,161	NORMAL
Winding_Temp_V	°C	10 - 130	68.0	85.2	76.5	20,161	NORMAL
Winding_Temp_W	°C	10 - 130	64.9	85.3	75.2	20,161	NORMAL
Bearing_Temp_DE	°C	10 - 95	42.4	54.6	48.5	20,161	NORMAL
Bearing_Temp_NDE	°C	10 - 95	41.7	57.0	49.4	20,161	NORMAL
Ambient_Temp	°C	0 - 50	23.5	32.3	28.0	20,161	NORMAL

SIGNAL TREND OVERVIEW (UNAGGREGATED PROFILES)



EXCURSION EVENTS LOG (2 Recorded)

Signal	Type	Start (UTC)	Duration	Peak	Limit
Active_Power	HIGH_EXCURSION	2026-09-20 01:58	79.0 m	78.5	75.0
Vib_Acc_NDE_V	HIGH_EXCURSION	2026-09-16 16:56	83.0 m	11.2	10.0

SYSTEM ALERTS AUDIT (1 Recorded)

Signal	Severity	Triggered At	Trigger Val	Threshold	Status
Torque	CRITICAL	2026-09-24 08:53	611.4	600.0	ACKNOWLEDGED

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

RAW TELEMETRY READINGS LOG (UNAGGREGATED)

Chronological sequence of unaggregated sensor measurements. Each value is presented exactly as recorded in signal_data.

Signal: Winding_Temp_U (°C)				All 20,161 Raw Readings			
Operating Limits: [10.0 to 130.0] • Observed: Min 56.19, Max 75.83, Mean 66.12							
#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1	2026-09-10 10:35	59.31	OK	2	2026-09-10 10:36	57.74	OK
3	2026-09-10 10:37	60.22	OK	4	2026-09-10 10:38	57.36	OK
5	2026-09-10 10:39	60.04	OK	6	2026-09-10 10:40	57.01	OK
7	2026-09-10 10:41	62.35	OK	8	2026-09-10 10:42	58.33	OK
9	2026-09-10 10:43	58.72	OK	10	2026-09-10 10:44	60.75	OK
11	2026-09-10 10:45	58.82	OK	12	2026-09-10 10:46	58.63	OK
13	2026-09-10 10:47	59.10	OK	14	2026-09-10 10:48	60.01	OK
15	2026-09-10 10:49	58.29	OK	16	2026-09-10 10:50	58.73	OK
17	2026-09-10 10:51	60.38	OK	18	2026-09-10 10:52	61.13	OK
19	2026-09-10 10:53	58.47	OK	20	2026-09-10 10:54	60.49	OK
21	2026-09-10 10:55	59.39	OK	22	2026-09-10 10:56	58.26	OK
23	2026-09-10 10:57	60.67	OK	24	2026-09-10 10:58	58.60	OK
25	2026-09-10 10:59	58.99	OK	26	2026-09-10 11:00	60.42	OK
27	2026-09-10 11:01	59.24	OK	28	2026-09-10 11:02	58.02	OK
29	2026-09-10 11:03	58.25	OK	30	2026-09-10 11:04	61.37	OK
31	2026-09-10 11:05	59.11	OK	32	2026-09-10 11:06	61.31	OK
33	2026-09-10 11:07	60.47	OK	34	2026-09-10 11:08	62.08	OK
35	2026-09-10 11:09	59.89	OK	36	2026-09-10 11:10	58.48	OK
37	2026-09-10 11:11	59.80	OK	38	2026-09-10 11:12	58.17	OK
39	2026-09-10 11:13	58.86	OK	40	2026-09-10 11:14	59.35	OK
41	2026-09-10 11:15	61.60	OK	42	2026-09-10 11:16	60.63	OK
43	2026-09-10 11:17	59.89	OK	44	2026-09-10 11:18	60.15	OK
45	2026-09-10 11:19	58.64	OK	46	2026-09-10 11:20	58.94	OK
47	2026-09-10 11:21	58.94	OK	48	2026-09-10 11:22	58.68	OK
49	2026-09-10 11:23	58.87	OK	50	2026-09-10 11:24	59.11	OK
51	2026-09-10 11:25	61.49	OK	52	2026-09-10 11:26	58.49	OK
53	2026-09-10 11:27	57.49	OK	54	2026-09-10 11:28	57.67	OK
55	2026-09-10 11:29	58.38	OK	56	2026-09-10 11:30	57.61	OK
57	2026-09-10 11:31	58.88	OK	58	2026-09-10 11:32	57.05	OK
59	2026-09-10 11:33	57.91	OK	60	2026-09-10 11:34	60.76	OK
61	2026-09-10 11:35	61.58	OK	62	2026-09-10 11:36	61.41	OK
63	2026-09-10 11:37	59.14	OK	64	2026-09-10 11:38	58.00	OK
65	2026-09-10 11:39	61.88	OK	66	2026-09-10 11:40	58.92	OK
67	2026-09-10 11:41	60.90	OK	68	2026-09-10 11:42	59.96	OK
69	2026-09-10 11:43	58.77	OK	70	2026-09-10 11:44	59.92	OK
71	2026-09-10 11:45	59.97	OK	72	2026-09-10 11:46	60.30	OK
73	2026-09-10 11:47	58.85	OK	74	2026-09-10 11:48	60.54	OK
75	2026-09-10 11:49	60.92	OK	76	2026-09-10 11:50	60.76	OK
77	2026-09-10 11:51	59.49	OK	78	2026-09-10 11:52	58.02	OK
79	2026-09-10 11:53	60.15	OK	80	2026-09-10 11:54	60.27	OK
81	2026-09-10 11:55	59.82	OK	82	2026-09-10 11:56	57.26	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
83	2026-09-10 11:57	58.94	OK	84	2026-09-10 11:58	58.43	OK
85	2026-09-10 11:59	60.29	OK	86	2026-09-10 12:00	59.84	OK
87	2026-09-10 12:01	59.61	OK	88	2026-09-10 12:02	61.34	OK
89	2026-09-10 12:03	59.97	OK	90	2026-09-10 12:04	59.13	OK
91	2026-09-10 12:05	62.27	OK	92	2026-09-10 12:06	59.88	OK
93	2026-09-10 12:07	59.44	OK	94	2026-09-10 12:08	58.54	OK
95	2026-09-10 12:09	61.77	OK	96	2026-09-10 12:10	60.02	OK
97	2026-09-10 12:11	60.24	OK	98	2026-09-10 12:12	57.34	OK
99	2026-09-10 12:13	60.91	OK	100	2026-09-10 12:14	61.93	OK
101	2026-09-10 12:15	62.02	OK	102	2026-09-10 12:16	58.98	OK
103	2026-09-10 12:17	60.29	OK	104	2026-09-10 12:18	59.21	OK
105	2026-09-10 12:19	62.28	OK	106	2026-09-10 12:20	62.19	OK
107	2026-09-10 12:21	58.66	OK	108	2026-09-10 12:22	58.92	OK
109	2026-09-10 12:23	58.47	OK	110	2026-09-10 12:24	61.60	OK
111	2026-09-10 12:25	59.62	OK	112	2026-09-10 12:26	60.44	OK
113	2026-09-10 12:27	60.63	OK	114	2026-09-10 12:28	61.09	OK
115	2026-09-10 12:29	59.23	OK	116	2026-09-10 12:30	60.02	OK
117	2026-09-10 12:31	58.93	OK	118	2026-09-10 12:32	59.61	OK
119	2026-09-10 12:33	60.79	OK	120	2026-09-10 12:34	60.55	OK
121	2026-09-10 12:35	61.20	OK	122	2026-09-10 12:36	60.68	OK
123	2026-09-10 12:37	61.25	OK	124	2026-09-10 12:38	57.47	OK
125	2026-09-10 12:39	62.47	OK	126	2026-09-10 12:40	59.93	OK
127	2026-09-10 12:41	61.83	OK	128	2026-09-10 12:42	61.07	OK
129	2026-09-10 12:43	61.66	OK	130	2026-09-10 12:44	59.95	OK
131	2026-09-10 12:45	62.25	OK	132	2026-09-10 12:46	61.65	OK
133	2026-09-10 12:47	60.18	OK	134	2026-09-10 12:48	61.16	OK
135	2026-09-10 12:49	58.76	OK	136	2026-09-10 12:50	59.92	OK
137	2026-09-10 12:51	58.08	OK	138	2026-09-10 12:52	62.63	OK
139	2026-09-10 12:53	60.88	OK	140	2026-09-10 12:54	61.90	OK
141	2026-09-10 12:55	62.58	OK	142	2026-09-10 12:56	58.07	OK
143	2026-09-10 12:57	59.72	OK	144	2026-09-10 12:58	62.15	OK
145	2026-09-10 12:59	60.97	OK	146	2026-09-10 13:00	61.11	OK
147	2026-09-10 13:01	61.46	OK	148	2026-09-10 13:02	58.57	OK
149	2026-09-10 13:03	62.01	OK	150	2026-09-10 13:04	62.18	OK
151	2026-09-10 13:05	60.05	OK	152	2026-09-10 13:06	59.30	OK
153	2026-09-10 13:07	61.10	OK	154	2026-09-10 13:08	60.77	OK
155	2026-09-10 13:09	60.67	OK	156	2026-09-10 13:10	60.79	OK
157	2026-09-10 13:11	57.43	OK	158	2026-09-10 13:12	62.05	OK
159	2026-09-10 13:13	60.43	OK	160	2026-09-10 13:14	60.37	OK
161	2026-09-10 13:15	60.02	OK	162	2026-09-10 13:16	61.16	OK
163	2026-09-10 13:17	62.38	OK	164	2026-09-10 13:18	61.66	OK
165	2026-09-10 13:19	63.58	OK	166	2026-09-10 13:20	61.76	OK
167	2026-09-10 13:21	60.05	OK	168	2026-09-10 13:22	61.43	OK
169	2026-09-10 13:23	61.67	OK	170	2026-09-10 13:24	60.45	OK
171	2026-09-10 13:25	60.54	OK	172	2026-09-10 13:26	63.23	OK
173	2026-09-10 13:27	61.93	OK	174	2026-09-10 13:28	60.15	OK
175	2026-09-10 13:29	63.50	OK	176	2026-09-10 13:30	62.15	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
177	2026-09-10 13:31	62.76	OK	178	2026-09-10 13:32	61.32	OK
179	2026-09-10 13:33	59.91	OK	180	2026-09-10 13:34	60.59	OK
181	2026-09-10 13:35	63.09	OK	182	2026-09-10 13:36	62.15	OK
183	2026-09-10 13:37	60.85	OK	184	2026-09-10 13:38	63.92	OK
185	2026-09-10 13:39	61.39	OK	186	2026-09-10 13:40	63.31	OK
187	2026-09-10 13:41	60.92	OK	188	2026-09-10 13:42	61.43	OK
189	2026-09-10 13:43	60.86	OK	190	2026-09-10 13:44	60.75	OK
191	2026-09-10 13:45	60.72	OK	192	2026-09-10 13:46	61.95	OK
193	2026-09-10 13:47	59.28	OK	194	2026-09-10 13:48	60.93	OK
195	2026-09-10 13:49	63.78	OK	196	2026-09-10 13:50	59.91	OK
197	2026-09-10 13:51	62.37	OK	198	2026-09-10 13:52	61.78	OK
199	2026-09-10 13:53	61.61	OK	200	2026-09-10 13:54	62.28	OK
201	2026-09-10 13:55	60.69	OK	202	2026-09-10 13:56	61.15	OK
203	2026-09-10 13:57	63.58	OK	204	2026-09-10 13:58	61.26	OK
205	2026-09-10 13:59	63.53	OK	206	2026-09-10 14:00	61.80	OK
207	2026-09-10 14:01	62.94	OK	208	2026-09-10 14:02	60.59	OK
209	2026-09-10 14:03	63.82	OK	210	2026-09-10 14:04	62.16	OK
211	2026-09-10 14:05	61.96	OK	212	2026-09-10 14:06	63.58	OK
213	2026-09-10 14:07	63.06	OK	214	2026-09-10 14:08	62.50	OK
215	2026-09-10 14:09	61.36	OK	216	2026-09-10 14:10	62.86	OK
217	2026-09-10 14:11	61.27	OK	218	2026-09-10 14:12	60.89	OK
219	2026-09-10 14:13	60.72	OK	220	2026-09-10 14:14	61.63	OK
221	2026-09-10 14:15	61.43	OK	222	2026-09-10 14:16	60.82	OK
223	2026-09-10 14:17	62.44	OK	224	2026-09-10 14:18	62.45	OK
225	2026-09-10 14:19	63.91	OK	226	2026-09-10 14:20	61.15	OK
227	2026-09-10 14:21	62.16	OK	228	2026-09-10 14:22	64.77	OK
229	2026-09-10 14:23	60.95	OK	230	2026-09-10 14:24	63.01	OK
231	2026-09-10 14:25	61.82	OK	232	2026-09-10 14:26	61.91	OK
233	2026-09-10 14:27	62.10	OK	234	2026-09-10 14:28	61.78	OK
235	2026-09-10 14:29	62.36	OK	236	2026-09-10 14:30	62.46	OK
237	2026-09-10 14:31	62.06	OK	238	2026-09-10 14:32	64.09	OK
239	2026-09-10 14:33	60.69	OK	240	2026-09-10 14:34	63.75	OK
241	2026-09-10 14:35	63.39	OK	242	2026-09-10 14:36	63.71	OK
243	2026-09-10 14:37	63.28	OK	244	2026-09-10 14:38	63.43	OK
245	2026-09-10 14:39	63.20	OK	246	2026-09-10 14:40	60.96	OK
247	2026-09-10 14:41	62.16	OK	248	2026-09-10 14:42	61.92	OK
249	2026-09-10 14:43	62.69	OK	250	2026-09-10 14:44	62.51	OK
251	2026-09-10 14:45	62.65	OK	252	2026-09-10 14:46	62.55	OK
253	2026-09-10 14:47	62.33	OK	254	2026-09-10 14:48	62.07	OK
255	2026-09-10 14:49	63.63	OK	256	2026-09-10 14:50	62.53	OK
257	2026-09-10 14:51	62.54	OK	258	2026-09-10 14:52	62.93	OK
259	2026-09-10 14:53	62.89	OK	260	2026-09-10 14:54	62.31	OK
261	2026-09-10 14:55	64.84	OK	262	2026-09-10 14:56	61.90	OK
263	2026-09-10 14:57	63.76	OK	264	2026-09-10 14:58	62.76	OK
265	2026-09-10 14:59	64.54	OK	266	2026-09-10 15:00	63.79	OK
267	2026-09-10 15:01	64.39	OK	268	2026-09-10 15:02	64.02	OK
269	2026-09-10 15:03	62.67	OK	270	2026-09-10 15:04	62.49	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
271	2026-09-10 15:05	63.50	OK	272	2026-09-10 15:06	63.60	OK
273	2026-09-10 15:07	61.30	OK	274	2026-09-10 15:08	62.94	OK
275	2026-09-10 15:09	62.86	OK	276	2026-09-10 15:10	62.83	OK
277	2026-09-10 15:11	61.14	OK	278	2026-09-10 15:12	63.54	OK
279	2026-09-10 15:13	63.63	OK	280	2026-09-10 15:14	61.39	OK
281	2026-09-10 15:15	63.40	OK	282	2026-09-10 15:16	62.13	OK
283	2026-09-10 15:17	63.41	OK	284	2026-09-10 15:18	63.33	OK
285	2026-09-10 15:19	63.43	OK	286	2026-09-10 15:20	63.93	OK
287	2026-09-10 15:21	64.95	OK	288	2026-09-10 15:22	65.29	OK
289	2026-09-10 15:23	63.35	OK	290	2026-09-10 15:24	64.68	OK
291	2026-09-10 15:25	65.78	OK	292	2026-09-10 15:26	63.86	OK
293	2026-09-10 15:27	64.74	OK	294	2026-09-10 15:28	63.47	OK
295	2026-09-10 15:29	65.59	OK	296	2026-09-10 15:30	65.98	OK
297	2026-09-10 15:31	60.80	OK	298	2026-09-10 15:32	64.44	OK
299	2026-09-10 15:33	65.24	OK	300	2026-09-10 15:34	63.95	OK
301	2026-09-10 15:35	63.29	OK	302	2026-09-10 15:36	65.06	OK
303	2026-09-10 15:37	64.66	OK	304	2026-09-10 15:38	61.97	OK
305	2026-09-10 15:39	62.91	OK	306	2026-09-10 15:40	65.91	OK
307	2026-09-10 15:41	65.63	OK	308	2026-09-10 15:42	61.67	OK
309	2026-09-10 15:43	65.05	OK	310	2026-09-10 15:44	65.09	OK
311	2026-09-10 15:45	64.04	OK	312	2026-09-10 15:46	62.24	OK
313	2026-09-10 15:47	64.63	OK	314	2026-09-10 15:48	64.54	OK
315	2026-09-10 15:49	64.72	OK	316	2026-09-10 15:50	64.12	OK
317	2026-09-10 15:51	63.93	OK	318	2026-09-10 15:52	66.45	OK
319	2026-09-10 15:53	64.34	OK	320	2026-09-10 15:54	65.62	OK
321	2026-09-10 15:55	67.00	OK	322	2026-09-10 15:56	66.25	OK
323	2026-09-10 15:57	64.16	OK	324	2026-09-10 15:58	62.06	OK
325	2026-09-10 15:59	65.04	OK	326	2026-09-10 16:00	63.09	OK
327	2026-09-10 16:01	66.89	OK	328	2026-09-10 16:02	66.25	OK
329	2026-09-10 16:03	65.68	OK	330	2026-09-10 16:04	67.72	OK
331	2026-09-10 16:05	64.07	OK	332	2026-09-10 16:06	64.70	OK
333	2026-09-10 16:07	66.05	OK	334	2026-09-10 16:08	63.29	OK
335	2026-09-10 16:09	65.60	OK	336	2026-09-10 16:10	64.84	OK
337	2026-09-10 16:11	63.29	OK	338	2026-09-10 16:12	66.50	OK
339	2026-09-10 16:13	68.40	OK	340	2026-09-10 16:14	63.55	OK
341	2026-09-10 16:15	66.75	OK	342	2026-09-10 16:16	63.63	OK
343	2026-09-10 16:17	66.69	OK	344	2026-09-10 16:18	67.50	OK
345	2026-09-10 16:19	66.39	OK	346	2026-09-10 16:20	64.73	OK
347	2026-09-10 16:21	65.38	OK	348	2026-09-10 16:22	63.94	OK
349	2026-09-10 16:23	67.08	OK	350	2026-09-10 16:24	65.99	OK
351	2026-09-10 16:25	67.68	OK	352	2026-09-10 16:26	65.67	OK
353	2026-09-10 16:27	64.89	OK	354	2026-09-10 16:28	66.45	OK
355	2026-09-10 16:29	66.60	OK	356	2026-09-10 16:30	64.79	OK
357	2026-09-10 16:31	64.60	OK	358	2026-09-10 16:32	65.24	OK
359	2026-09-10 16:33	65.00	OK	360	2026-09-10 16:34	66.10	OK
361	2026-09-10 16:35	64.79	OK	362	2026-09-10 16:36	65.49	OK
363	2026-09-10 16:37	67.87	OK	364	2026-09-10 16:38	63.55	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
365	2026-09-10 16:39	66.46	OK	366	2026-09-10 16:40	65.05	OK
367	2026-09-10 16:41	65.52	OK	368	2026-09-10 16:42	67.61	OK
369	2026-09-10 16:43	66.42	OK	370	2026-09-10 16:44	68.06	OK
371	2026-09-10 16:45	65.09	OK	372	2026-09-10 16:46	67.28	OK
373	2026-09-10 16:47	67.02	OK	374	2026-09-10 16:48	64.83	OK
375	2026-09-10 16:49	67.28	OK	376	2026-09-10 16:50	66.29	OK
377	2026-09-10 16:51	67.39	OK	378	2026-09-10 16:52	66.19	OK
379	2026-09-10 16:53	64.85	OK	380	2026-09-10 16:54	65.83	OK
381	2026-09-10 16:55	65.06	OK	382	2026-09-10 16:56	65.37	OK
383	2026-09-10 16:57	67.24	OK	384	2026-09-10 16:58	68.55	OK
385	2026-09-10 16:59	65.27	OK	386	2026-09-10 17:00	64.14	OK
387	2026-09-10 17:01	68.30	OK	388	2026-09-10 17:02	65.18	OK
389	2026-09-10 17:03	65.68	OK	390	2026-09-10 17:04	65.65	OK
391	2026-09-10 17:05	64.90	OK	392	2026-09-10 17:06	67.73	OK
393	2026-09-10 17:07	67.38	OK	394	2026-09-10 17:08	65.43	OK
395	2026-09-10 17:09	65.71	OK	396	2026-09-10 17:10	69.19	OK
397	2026-09-10 17:11	65.99	OK	398	2026-09-10 17:12	66.27	OK
399	2026-09-10 17:13	67.43	OK	400	2026-09-10 17:14	66.21	OK
401	2026-09-10 17:15	66.06	OK	402	2026-09-10 17:16	69.52	OK
403	2026-09-10 17:17	69.98	OK	404	2026-09-10 17:18	66.28	OK
405	2026-09-10 17:19	68.45	OK	406	2026-09-10 17:20	67.10	OK
407	2026-09-10 17:21	67.38	OK	408	2026-09-10 17:22	65.80	OK
409	2026-09-10 17:23	68.79	OK	410	2026-09-10 17:24	64.74	OK
411	2026-09-10 17:25	67.87	OK	412	2026-09-10 17:26	67.00	OK
413	2026-09-10 17:27	65.37	OK	414	2026-09-10 17:28	66.82	OK
415	2026-09-10 17:29	66.12	OK	416	2026-09-10 17:30	67.22	OK
417	2026-09-10 17:31	70.71	OK	418	2026-09-10 17:32	65.63	OK
419	2026-09-10 17:33	67.49	OK	420	2026-09-10 17:34	68.35	OK
421	2026-09-10 17:35	68.93	OK	422	2026-09-10 17:36	67.20	OK
423	2026-09-10 17:37	70.27	OK	424	2026-09-10 17:38	69.36	OK
425	2026-09-10 17:39	69.09	OK	426	2026-09-10 17:40	66.35	OK
427	2026-09-10 17:41	68.92	OK	428	2026-09-10 17:42	70.79	OK
429	2026-09-10 17:43	66.77	OK	430	2026-09-10 17:44	66.75	OK
431	2026-09-10 17:45	68.83	OK	432	2026-09-10 17:46	67.26	OK
433	2026-09-10 17:47	66.00	OK	434	2026-09-10 17:48	66.17	OK
435	2026-09-10 17:49	67.32	OK	436	2026-09-10 17:50	69.53	OK
437	2026-09-10 17:51	66.48	OK	438	2026-09-10 17:52	65.68	OK
439	2026-09-10 17:53	67.45	OK	440	2026-09-10 17:54	68.11	OK
441	2026-09-10 17:55	67.85	OK	442	2026-09-10 17:56	68.57	OK
443	2026-09-10 17:57	69.98	OK	444	2026-09-10 17:58	70.23	OK
445	2026-09-10 17:59	69.11	OK	446	2026-09-10 18:00	68.33	OK
447	2026-09-10 18:01	67.69	OK	448	2026-09-10 18:02	69.95	OK
449	2026-09-10 18:03	68.11	OK	450	2026-09-10 18:04	71.39	OK
451	2026-09-10 18:05	67.93	OK	452	2026-09-10 18:06	69.76	OK
453	2026-09-10 18:07	69.94	OK	454	2026-09-10 18:08	69.25	OK
455	2026-09-10 18:09	68.53	OK	456	2026-09-10 18:10	68.53	OK
457	2026-09-10 18:11	69.58	OK	458	2026-09-10 18:12	69.42	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
459	2026-09-10 18:13	67.93	OK	460	2026-09-10 18:14	70.40	OK
461	2026-09-10 18:15	67.31	OK	462	2026-09-10 18:16	69.24	OK
463	2026-09-10 18:17	68.06	OK	464	2026-09-10 18:18	69.35	OK
465	2026-09-10 18:19	69.37	OK	466	2026-09-10 18:20	69.52	OK
467	2026-09-10 18:21	67.12	OK	468	2026-09-10 18:22	69.68	OK
469	2026-09-10 18:23	69.29	OK	470	2026-09-10 18:24	69.13	OK
471	2026-09-10 18:25	67.42	OK	472	2026-09-10 18:26	69.45	OK
473	2026-09-10 18:27	70.37	OK	474	2026-09-10 18:28	68.00	OK
475	2026-09-10 18:29	70.10	OK	476	2026-09-10 18:30	70.08	OK
477	2026-09-10 18:31	68.97	OK	478	2026-09-10 18:32	68.47	OK
479	2026-09-10 18:33	68.75	OK	480	2026-09-10 18:34	69.72	OK
481	2026-09-10 18:35	70.62	OK	482	2026-09-10 18:36	69.32	OK
483	2026-09-10 18:37	70.71	OK	484	2026-09-10 18:38	68.87	OK
485	2026-09-10 18:39	69.97	OK	486	2026-09-10 18:40	69.36	OK
487	2026-09-10 18:41	68.15	OK	488	2026-09-10 18:42	68.14	OK
489	2026-09-10 18:43	70.15	OK	490	2026-09-10 18:44	69.35	OK
491	2026-09-10 18:45	70.10	OK	492	2026-09-10 18:46	68.24	OK
493	2026-09-10 18:47	70.29	OK	494	2026-09-10 18:48	69.49	OK
495	2026-09-10 18:49	70.80	OK	496	2026-09-10 18:50	67.94	OK
497	2026-09-10 18:51	70.75	OK	498	2026-09-10 18:52	68.49	OK
499	2026-09-10 18:53	71.63	OK	500	2026-09-10 18:54	70.30	OK
501	2026-09-10 18:55	68.37	OK	502	2026-09-10 18:56	69.87	OK
503	2026-09-10 18:57	68.62	OK	504	2026-09-10 18:58	67.33	OK
505	2026-09-10 18:59	68.65	OK	506	2026-09-10 19:00	71.00	OK
507	2026-09-10 19:01	67.02	OK	508	2026-09-10 19:02	70.07	OK
509	2026-09-10 19:03	70.20	OK	510	2026-09-10 19:04	72.47	OK
511	2026-09-10 19:05	71.48	OK	512	2026-09-10 19:06	67.26	OK
513	2026-09-10 19:07	68.66	OK	514	2026-09-10 19:08	70.81	OK
515	2026-09-10 19:09	69.35	OK	516	2026-09-10 19:10	68.61	OK
517	2026-09-10 19:11	69.67	OK	518	2026-09-10 19:12	71.19	OK
519	2026-09-10 19:13	70.52	OK	520	2026-09-10 19:14	68.66	OK
521	2026-09-10 19:15	71.44	OK	522	2026-09-10 19:16	71.08	OK
523	2026-09-10 19:17	68.57	OK	524	2026-09-10 19:18	72.48	OK
525	2026-09-10 19:19	72.90	OK	526	2026-09-10 19:20	70.37	OK
527	2026-09-10 19:21	69.63	OK	528	2026-09-10 19:22	70.21	OK
529	2026-09-10 19:23	71.18	OK	530	2026-09-10 19:24	72.00	OK
531	2026-09-10 19:25	70.10	OK	532	2026-09-10 19:26	69.85	OK
533	2026-09-10 19:27	72.78	OK	534	2026-09-10 19:28	70.82	OK
535	2026-09-10 19:29	72.19	OK	536	2026-09-10 19:30	70.42	OK
537	2026-09-10 19:31	72.98	OK	538	2026-09-10 19:32	69.42	OK
539	2026-09-10 19:33	68.43	OK	540	2026-09-10 19:34	70.49	OK
541	2026-09-10 19:35	69.50	OK	542	2026-09-10 19:36	67.93	OK
543	2026-09-10 19:37	71.60	OK	544	2026-09-10 19:38	71.79	OK
545	2026-09-10 19:39	71.22	OK	546	2026-09-10 19:40	70.77	OK
547	2026-09-10 19:41	69.17	OK	548	2026-09-10 19:42	71.77	OK
549	2026-09-10 19:43	68.75	OK	550	2026-09-10 19:44	69.26	OK
551	2026-09-10 19:45	70.32	OK	552	2026-09-10 19:46	71.04	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
553	2026-09-10 19:47	69.32	OK	554	2026-09-10 19:48	70.06	OK
555	2026-09-10 19:49	70.53	OK	556	2026-09-10 19:50	68.95	OK
557	2026-09-10 19:51	69.92	OK	558	2026-09-10 19:52	73.09	OK
559	2026-09-10 19:53	70.06	OK	560	2026-09-10 19:54	68.82	OK
561	2026-09-10 19:55	68.88	OK	562	2026-09-10 19:56	74.06	OK
563	2026-09-10 19:57	71.61	OK	564	2026-09-10 19:58	72.14	OK
565	2026-09-10 19:59	70.47	OK	566	2026-09-10 20:00	71.99	OK
567	2026-09-10 20:01	70.47	OK	568	2026-09-10 20:02	69.09	OK
569	2026-09-10 20:03	72.62	OK	570	2026-09-10 20:04	71.57	OK
571	2026-09-10 20:05	71.90	OK	572	2026-09-10 20:06	73.77	OK
573	2026-09-10 20:07	72.13	OK	574	2026-09-10 20:08	71.58	OK
575	2026-09-10 20:09	72.03	OK	576	2026-09-10 20:10	72.38	OK
577	2026-09-10 20:11	70.41	OK	578	2026-09-10 20:12	70.31	OK
579	2026-09-10 20:13	72.03	OK	580	2026-09-10 20:14	69.44	OK
581	2026-09-10 20:15	71.16	OK	582	2026-09-10 20:16	73.18	OK
583	2026-09-10 20:17	69.96	OK	584	2026-09-10 20:18	70.64	OK
585	2026-09-10 20:19	69.25	OK	586	2026-09-10 20:20	70.67	OK
587	2026-09-10 20:21	69.18	OK	588	2026-09-10 20:22	72.44	OK
589	2026-09-10 20:23	70.63	OK	590	2026-09-10 20:24	73.54	OK
591	2026-09-10 20:25	71.40	OK	592	2026-09-10 20:26	72.32	OK
593	2026-09-10 20:27	72.49	OK	594	2026-09-10 20:28	69.46	OK
595	2026-09-10 20:29	71.58	OK	596	2026-09-10 20:30	72.34	OK
597	2026-09-10 20:31	69.84	OK	598	2026-09-10 20:32	72.89	OK
599	2026-09-10 20:33	71.41	OK	600	2026-09-10 20:34	72.11	OK
601	2026-09-10 20:35	73.04	OK	602	2026-09-10 20:36	72.00	OK
603	2026-09-10 20:37	70.02	OK	604	2026-09-10 20:38	71.80	OK
605	2026-09-10 20:39	70.59	OK	606	2026-09-10 20:40	70.79	OK
607	2026-09-10 20:41	70.49	OK	608	2026-09-10 20:42	73.12	OK
609	2026-09-10 20:43	71.44	OK	610	2026-09-10 20:44	71.67	OK
611	2026-09-10 20:45	72.11	OK	612	2026-09-10 20:46	70.27	OK
613	2026-09-10 20:47	73.61	OK	614	2026-09-10 20:48	72.58	OK
615	2026-09-10 20:49	71.28	OK	616	2026-09-10 20:50	74.03	OK
617	2026-09-10 20:51	71.66	OK	618	2026-09-10 20:52	69.20	OK
619	2026-09-10 20:53	71.46	OK	620	2026-09-10 20:54	71.50	OK
621	2026-09-10 20:55	71.18	OK	622	2026-09-10 20:56	71.42	OK
623	2026-09-10 20:57	71.15	OK	624	2026-09-10 20:58	70.22	OK
625	2026-09-10 20:59	71.94	OK	626	2026-09-10 21:00	71.22	OK
627	2026-09-10 21:01	74.17	OK	628	2026-09-10 21:02	73.67	OK
629	2026-09-10 21:03	71.74	OK	630	2026-09-10 21:04	70.20	OK
631	2026-09-10 21:05	72.29	OK	632	2026-09-10 21:06	72.15	OK
633	2026-09-10 21:07	72.87	OK	634	2026-09-10 21:08	71.46	OK
635	2026-09-10 21:09	70.14	OK	636	2026-09-10 21:10	73.93	OK
637	2026-09-10 21:11	71.74	OK	638	2026-09-10 21:12	73.26	OK
639	2026-09-10 21:13	72.58	OK	640	2026-09-10 21:14	70.76	OK
641	2026-09-10 21:15	72.47	OK	642	2026-09-10 21:16	71.81	OK
643	2026-09-10 21:17	70.28	OK	644	2026-09-10 21:18	70.09	OK
645	2026-09-10 21:19	70.50	OK	646	2026-09-10 21:20	74.78	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
647	2026-09-10 21:21	73.50	OK	648	2026-09-10 21:22	73.56	OK
649	2026-09-10 21:23	70.23	OK	650	2026-09-10 21:24	72.32	OK
651	2026-09-10 21:25	71.48	OK	652	2026-09-10 21:26	71.28	OK
653	2026-09-10 21:27	72.06	OK	654	2026-09-10 21:28	71.58	OK
655	2026-09-10 21:29	71.82	OK	656	2026-09-10 21:30	73.13	OK
657	2026-09-10 21:31	74.62	OK	658	2026-09-10 21:32	73.71	OK
659	2026-09-10 21:33	73.20	OK	660	2026-09-10 21:34	70.48	OK
661	2026-09-10 21:35	73.57	OK	662	2026-09-10 21:36	70.71	OK
663	2026-09-10 21:37	71.14	OK	664	2026-09-10 21:38	74.32	OK
665	2026-09-10 21:39	73.10	OK	666	2026-09-10 21:40	72.46	OK
667	2026-09-10 21:41	72.70	OK	668	2026-09-10 21:42	72.70	OK
669	2026-09-10 21:43	71.81	OK	670	2026-09-10 21:44	72.63	OK
671	2026-09-10 21:45	71.58	OK	672	2026-09-10 21:46	71.99	OK
673	2026-09-10 21:47	73.44	OK	674	2026-09-10 21:48	75.09	OK
675	2026-09-10 21:49	72.40	OK	676	2026-09-10 21:50	71.10	OK
677	2026-09-10 21:51	72.86	OK	678	2026-09-10 21:52	74.94	OK
679	2026-09-10 21:53	71.28	OK	680	2026-09-10 21:54	73.50	OK
681	2026-09-10 21:55	72.74	OK	682	2026-09-10 21:56	73.29	OK
683	2026-09-10 21:57	72.60	OK	684	2026-09-10 21:58	74.21	OK
685	2026-09-10 21:59	71.50	OK	686	2026-09-10 22:00	72.04	OK
687	2026-09-10 22:01	72.05	OK	688	2026-09-10 22:02	71.72	OK
689	2026-09-10 22:03	73.73	OK	690	2026-09-10 22:04	72.41	OK
691	2026-09-10 22:05	73.24	OK	692	2026-09-10 22:06	72.36	OK
693	2026-09-10 22:07	72.62	OK	694	2026-09-10 22:08	71.93	OK
695	2026-09-10 22:09	72.32	OK	696	2026-09-10 22:10	72.67	OK
697	2026-09-10 22:11	70.41	OK	698	2026-09-10 22:12	74.54	OK
699	2026-09-10 22:13	70.18	OK	700	2026-09-10 22:14	72.69	OK
701	2026-09-10 22:15	73.18	OK	702	2026-09-10 22:16	70.92	OK
703	2026-09-10 22:17	71.42	OK	704	2026-09-10 22:18	71.82	OK
705	2026-09-10 22:19	72.32	OK	706	2026-09-10 22:20	72.76	OK
707	2026-09-10 22:21	71.50	OK	708	2026-09-10 22:22	74.89	OK
709	2026-09-10 22:23	73.58	OK	710	2026-09-10 22:24	72.35	OK
711	2026-09-10 22:25	74.22	OK	712	2026-09-10 22:26	72.55	OK
713	2026-09-10 22:27	74.53	OK	714	2026-09-10 22:28	75.16	OK
715	2026-09-10 22:29	71.20	OK	716	2026-09-10 22:30	74.71	OK
717	2026-09-10 22:31	72.29	OK	718	2026-09-10 22:32	72.78	OK
719	2026-09-10 22:33	73.15	OK	720	2026-09-10 22:34	71.08	OK
721	2026-09-10 22:35	72.49	OK	722	2026-09-10 22:36	71.01	OK
723	2026-09-10 22:37	73.05	OK	724	2026-09-10 22:38	72.76	OK
725	2026-09-10 22:39	71.62	OK	726	2026-09-10 22:40	74.52	OK
727	2026-09-10 22:41	73.41	OK	728	2026-09-10 22:42	73.43	OK
729	2026-09-10 22:43	72.11	OK	730	2026-09-10 22:44	71.29	OK
731	2026-09-10 22:45	71.34	OK	732	2026-09-10 22:46	71.66	OK
733	2026-09-10 22:47	72.68	OK	734	2026-09-10 22:48	71.72	OK
735	2026-09-10 22:49	71.99	OK	736	2026-09-10 22:50	71.24	OK
737	2026-09-10 22:51	72.63	OK	738	2026-09-10 22:52	71.03	OK
739	2026-09-10 22:53	70.95	OK	740	2026-09-10 22:54	72.43	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
741	2026-09-10 22:55	73.63	OK	742	2026-09-10 22:56	72.61	OK
743	2026-09-10 22:57	72.38	OK	744	2026-09-10 22:58	73.81	OK
745	2026-09-10 22:59	72.32	OK	746	2026-09-10 23:00	72.00	OK
747	2026-09-10 23:01	72.24	OK	748	2026-09-10 23:02	72.99	OK
749	2026-09-10 23:03	75.57	OK	750	2026-09-10 23:04	73.03	OK
751	2026-09-10 23:05	71.38	OK	752	2026-09-10 23:06	72.66	OK
753	2026-09-10 23:07	73.53	OK	754	2026-09-10 23:08	70.63	OK
755	2026-09-10 23:09	72.80	OK	756	2026-09-10 23:10	73.93	OK
757	2026-09-10 23:11	73.43	OK	758	2026-09-10 23:12	71.85	OK
759	2026-09-10 23:13	71.55	OK	760	2026-09-10 23:14	73.97	OK
761	2026-09-10 23:15	73.11	OK	762	2026-09-10 23:16	73.80	OK
763	2026-09-10 23:17	70.31	OK	764	2026-09-10 23:18	71.12	OK
765	2026-09-10 23:19	73.47	OK	766	2026-09-10 23:20	72.08	OK
767	2026-09-10 23:21	71.17	OK	768	2026-09-10 23:22	75.42	OK
769	2026-09-10 23:23	73.05	OK	770	2026-09-10 23:24	73.05	OK
771	2026-09-10 23:25	70.04	OK	772	2026-09-10 23:26	73.63	OK
773	2026-09-10 23:27	73.88	OK	774	2026-09-10 23:28	73.37	OK
775	2026-09-10 23:29	71.21	OK	776	2026-09-10 23:30	72.47	OK
777	2026-09-10 23:31	70.71	OK	778	2026-09-10 23:32	72.78	OK
779	2026-09-10 23:33	73.85	OK	780	2026-09-10 23:34	72.48	OK
781	2026-09-10 23:35	71.45	OK	782	2026-09-10 23:36	74.28	OK
783	2026-09-10 23:37	73.68	OK	784	2026-09-10 23:38	73.47	OK
785	2026-09-10 23:39	73.46	OK	786	2026-09-10 23:40	74.50	OK
787	2026-09-10 23:41	73.29	OK	788	2026-09-10 23:42	69.60	OK
789	2026-09-10 23:43	71.82	OK	790	2026-09-10 23:44	72.43	OK
791	2026-09-10 23:45	74.08	OK	792	2026-09-10 23:46	72.85	OK
793	2026-09-10 23:47	72.83	OK	794	2026-09-10 23:48	70.80	OK
795	2026-09-10 23:49	72.63	OK	796	2026-09-10 23:50	72.46	OK
797	2026-09-10 23:51	71.95	OK	798	2026-09-10 23:52	72.83	OK
799	2026-09-10 23:53	73.44	OK	800	2026-09-10 23:54	71.24	OK
801	2026-09-10 23:55	73.99	OK	802	2026-09-10 23:56	69.64	OK
803	2026-09-10 23:57	70.43	OK	804	2026-09-10 23:58	73.19	OK
805	2026-09-10 23:59	73.16	OK	806	2026-09-11 00:00	70.57	OK
807	2026-09-11 00:01	72.55	OK	808	2026-09-11 00:02	69.50	OK
809	2026-09-11 00:03	73.28	OK	810	2026-09-11 00:04	70.43	OK
811	2026-09-11 00:05	73.03	OK	812	2026-09-11 00:06	73.26	OK
813	2026-09-11 00:07	70.90	OK	814	2026-09-11 00:08	72.97	OK
815	2026-09-11 00:09	70.10	OK	816	2026-09-11 00:10	70.12	OK
817	2026-09-11 00:11	70.78	OK	818	2026-09-11 00:12	71.64	OK
819	2026-09-11 00:13	69.15	OK	820	2026-09-11 00:14	71.81	OK
821	2026-09-11 00:15	72.41	OK	822	2026-09-11 00:16	73.09	OK
823	2026-09-11 00:17	70.03	OK	824	2026-09-11 00:18	73.17	OK
825	2026-09-11 00:19	69.64	OK	826	2026-09-11 00:20	72.92	OK
827	2026-09-11 00:21	71.04	OK	828	2026-09-11 00:22	71.22	OK
829	2026-09-11 00:23	72.69	OK	830	2026-09-11 00:24	71.98	OK
831	2026-09-11 00:25	73.33	OK	832	2026-09-11 00:26	73.57	OK
833	2026-09-11 00:27	69.91	OK	834	2026-09-11 00:28	70.83	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
835	2026-09-11 00:29	74.15	OK	836	2026-09-11 00:30	74.22	OK
837	2026-09-11 00:31	73.69	OK	838	2026-09-11 00:32	71.51	OK
839	2026-09-11 00:33	69.95	OK	840	2026-09-11 00:34	73.75	OK
841	2026-09-11 00:35	70.20	OK	842	2026-09-11 00:36	74.07	OK
843	2026-09-11 00:37	71.56	OK	844	2026-09-11 00:38	73.36	OK
845	2026-09-11 00:39	73.19	OK	846	2026-09-11 00:40	71.02	OK
847	2026-09-11 00:41	71.81	OK	848	2026-09-11 00:42	73.13	OK
849	2026-09-11 00:43	73.01	OK	850	2026-09-11 00:44	70.29	OK
851	2026-09-11 00:45	74.23	OK	852	2026-09-11 00:46	71.95	OK
853	2026-09-11 00:47	72.26	OK	854	2026-09-11 00:48	71.45	OK
855	2026-09-11 00:49	69.56	OK	856	2026-09-11 00:50	73.98	OK
857	2026-09-11 00:51	72.09	OK	858	2026-09-11 00:52	71.03	OK
859	2026-09-11 00:53	74.25	OK	860	2026-09-11 00:54	72.26	OK
861	2026-09-11 00:55	72.82	OK	862	2026-09-11 00:56	68.92	OK
863	2026-09-11 00:57	70.90	OK	864	2026-09-11 00:58	72.79	OK
865	2026-09-11 00:59	72.49	OK	866	2026-09-11 01:00	69.85	OK
867	2026-09-11 01:01	72.80	OK	868	2026-09-11 01:02	71.26	OK
869	2026-09-11 01:03	70.90	OK	870	2026-09-11 01:04	72.35	OK
871	2026-09-11 01:05	72.24	OK	872	2026-09-11 01:06	72.55	OK
873	2026-09-11 01:07	71.34	OK	874	2026-09-11 01:08	74.00	OK
875	2026-09-11 01:09	69.72	OK	876	2026-09-11 01:10	71.27	OK
877	2026-09-11 01:11	73.62	OK	878	2026-09-11 01:12	70.87	OK
879	2026-09-11 01:13	71.78	OK	880	2026-09-11 01:14	71.54	OK
881	2026-09-11 01:15	70.15	OK	882	2026-09-11 01:16	72.15	OK
883	2026-09-11 01:17	71.93	OK	884	2026-09-11 01:18	69.10	OK
885	2026-09-11 01:19	72.04	OK	886	2026-09-11 01:20	70.33	OK
887	2026-09-11 01:21	72.10	OK	888	2026-09-11 01:22	72.00	OK
889	2026-09-11 01:23	72.06	OK	890	2026-09-11 01:24	69.86	OK
891	2026-09-11 01:25	71.32	OK	892	2026-09-11 01:26	71.48	OK
893	2026-09-11 01:27	71.68	OK	894	2026-09-11 01:28	71.99	OK
895	2026-09-11 01:29	71.89	OK	896	2026-09-11 01:30	72.66	OK
897	2026-09-11 01:31	68.52	OK	898	2026-09-11 01:32	71.42	OK
899	2026-09-11 01:33	70.61	OK	900	2026-09-11 01:34	72.36	OK
901	2026-09-11 01:35	70.27	OK	902	2026-09-11 01:36	70.13	OK
903	2026-09-11 01:37	69.15	OK	904	2026-09-11 01:38	71.83	OK
905	2026-09-11 01:39	72.11	OK	906	2026-09-11 01:40	67.52	OK
907	2026-09-11 01:41	72.43	OK	908	2026-09-11 01:42	72.31	OK
909	2026-09-11 01:43	72.68	OK	910	2026-09-11 01:44	71.87	OK
911	2026-09-11 01:45	71.58	OK	912	2026-09-11 01:46	72.38	OK
913	2026-09-11 01:47	71.87	OK	914	2026-09-11 01:48	69.03	OK
915	2026-09-11 01:49	71.20	OK	916	2026-09-11 01:50	70.02	OK
917	2026-09-11 01:51	67.82	OK	918	2026-09-11 01:52	71.68	OK
919	2026-09-11 01:53	68.99	OK	920	2026-09-11 01:54	71.19	OK
921	2026-09-11 01:55	71.12	OK	922	2026-09-11 01:56	69.01	OK
923	2026-09-11 01:57	71.26	OK	924	2026-09-11 01:58	69.75	OK
925	2026-09-11 01:59	69.53	OK	926	2026-09-11 02:00	71.82	OK
927	2026-09-11 02:01	68.69	OK	928	2026-09-11 02:02	69.75	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
929	2026-09-11 02:03	70.06	OK	930	2026-09-11 02:04	69.42	OK
931	2026-09-11 02:05	72.88	OK	932	2026-09-11 02:06	70.88	OK
933	2026-09-11 02:07	70.26	OK	934	2026-09-11 02:08	71.25	OK
935	2026-09-11 02:09	71.01	OK	936	2026-09-11 02:10	71.46	OK
937	2026-09-11 02:11	67.20	OK	938	2026-09-11 02:12	71.14	OK
939	2026-09-11 02:13	69.75	OK	940	2026-09-11 02:14	68.24	OK
941	2026-09-11 02:15	70.75	OK	942	2026-09-11 02:16	69.91	OK
943	2026-09-11 02:17	70.34	OK	944	2026-09-11 02:18	69.56	OK
945	2026-09-11 02:19	68.50	OK	946	2026-09-11 02:20	70.39	OK
947	2026-09-11 02:21	71.39	OK	948	2026-09-11 02:22	70.55	OK
949	2026-09-11 02:23	69.77	OK	950	2026-09-11 02:24	70.98	OK
951	2026-09-11 02:25	70.66	OK	952	2026-09-11 02:26	67.44	OK
953	2026-09-11 02:27	70.30	OK	954	2026-09-11 02:28	69.16	OK
955	2026-09-11 02:29	69.35	OK	956	2026-09-11 02:30	70.25	OK
957	2026-09-11 02:31	70.54	OK	958	2026-09-11 02:32	68.26	OK
959	2026-09-11 02:33	68.22	OK	960	2026-09-11 02:34	68.06	OK
961	2026-09-11 02:35	68.50	OK	962	2026-09-11 02:36	70.91	OK
963	2026-09-11 02:37	70.11	OK	964	2026-09-11 02:38	68.43	OK
965	2026-09-11 02:39	66.78	OK	966	2026-09-11 02:40	68.94	OK
967	2026-09-11 02:41	67.15	OK	968	2026-09-11 02:42	68.09	OK
969	2026-09-11 02:43	69.75	OK	970	2026-09-11 02:44	68.29	OK
971	2026-09-11 02:45	67.65	OK	972	2026-09-11 02:46	71.01	OK
973	2026-09-11 02:47	68.65	OK	974	2026-09-11 02:48	70.91	OK
975	2026-09-11 02:49	67.77	OK	976	2026-09-11 02:50	68.71	OK
977	2026-09-11 02:51	68.38	OK	978	2026-09-11 02:52	68.79	OK
979	2026-09-11 02:53	71.13	OK	980	2026-09-11 02:54	69.65	OK
981	2026-09-11 02:55	66.26	OK	982	2026-09-11 02:56	70.71	OK
983	2026-09-11 02:57	69.04	OK	984	2026-09-11 02:58	68.62	OK
985	2026-09-11 02:59	69.24	OK	986	2026-09-11 03:00	68.53	OK
987	2026-09-11 03:01	68.99	OK	988	2026-09-11 03:02	66.88	OK
989	2026-09-11 03:03	68.61	OK	990	2026-09-11 03:04	66.95	OK
991	2026-09-11 03:05	67.63	OK	992	2026-09-11 03:06	68.78	OK
993	2026-09-11 03:07	69.47	OK	994	2026-09-11 03:08	65.89	OK
995	2026-09-11 03:09	69.75	OK	996	2026-09-11 03:10	68.70	OK
997	2026-09-11 03:11	71.05	OK	998	2026-09-11 03:12	67.77	OK
999	2026-09-11 03:13	70.02	OK	1000	2026-09-11 03:14	66.26	OK
1001	2026-09-11 03:15	68.49	OK	1002	2026-09-11 03:16	66.09	OK
1003	2026-09-11 03:17	69.00	OK	1004	2026-09-11 03:18	68.56	OK
1005	2026-09-11 03:19	68.36	OK	1006	2026-09-11 03:20	68.11	OK
1007	2026-09-11 03:21	69.15	OK	1008	2026-09-11 03:22	70.62	OK
1009	2026-09-11 03:23	69.82	OK	1010	2026-09-11 03:24	65.52	OK
1011	2026-09-11 03:25	66.74	OK	1012	2026-09-11 03:26	69.43	OK
1013	2026-09-11 03:27	66.00	OK	1014	2026-09-11 03:28	70.33	OK
1015	2026-09-11 03:29	67.93	OK	1016	2026-09-11 03:30	69.26	OK
1017	2026-09-11 03:31	69.81	OK	1018	2026-09-11 03:32	69.33	OK
1019	2026-09-11 03:33	67.75	OK	1020	2026-09-11 03:34	67.57	OK
1021	2026-09-11 03:35	65.83	OK	1022	2026-09-11 03:36	70.15	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1023	2026-09-11 03:37	68.74	OK	1024	2026-09-11 03:38	66.95	OK
1025	2026-09-11 03:39	67.48	OK	1026	2026-09-11 03:40	67.81	OK
1027	2026-09-11 03:41	68.46	OK	1028	2026-09-11 03:42	67.45	OK
1029	2026-09-11 03:43	69.73	OK	1030	2026-09-11 03:44	66.83	OK
1031	2026-09-11 03:45	66.91	OK	1032	2026-09-11 03:46	67.77	OK
1033	2026-09-11 03:47	69.35	OK	1034	2026-09-11 03:48	67.21	OK
1035	2026-09-11 03:49	67.25	OK	1036	2026-09-11 03:50	67.82	OK
1037	2026-09-11 03:51	68.55	OK	1038	2026-09-11 03:52	66.50	OK
1039	2026-09-11 03:53	66.64	OK	1040	2026-09-11 03:54	66.58	OK
1041	2026-09-11 03:55	67.11	OK	1042	2026-09-11 03:56	69.69	OK
1043	2026-09-11 03:57	67.75	OK	1044	2026-09-11 03:58	70.34	OK
1045	2026-09-11 03:59	67.41	OK	1046	2026-09-11 04:00	67.59	OK
1047	2026-09-11 04:01	66.42	OK	1048	2026-09-11 04:02	65.00	OK
1049	2026-09-11 04:03	66.50	OK	1050	2026-09-11 04:04	65.43	OK
1051	2026-09-11 04:05	68.03	OK	1052	2026-09-11 04:06	64.99	OK
1053	2026-09-11 04:07	68.29	OK	1054	2026-09-11 04:08	66.02	OK
1055	2026-09-11 04:09	66.86	OK	1056	2026-09-11 04:10	67.46	OK
1057	2026-09-11 04:11	68.23	OK	1058	2026-09-11 04:12	68.87	OK
1059	2026-09-11 04:13	66.85	OK	1060	2026-09-11 04:14	68.47	OK
1061	2026-09-11 04:15	68.59	OK	1062	2026-09-11 04:16	68.06	OK
1063	2026-09-11 04:17	65.25	OK	1064	2026-09-11 04:18	68.31	OK
1065	2026-09-11 04:19	65.84	OK	1066	2026-09-11 04:20	67.34	OK
1067	2026-09-11 04:21	66.64	OK	1068	2026-09-11 04:22	66.96	OK
1069	2026-09-11 04:23	65.52	OK	1070	2026-09-11 04:24	65.71	OK
1071	2026-09-11 04:25	66.54	OK	1072	2026-09-11 04:26	64.77	OK
1073	2026-09-11 04:27	65.09	OK	1074	2026-09-11 04:28	68.77	OK
1075	2026-09-11 04:29	67.18	OK	1076	2026-09-11 04:30	69.41	OK
1077	2026-09-11 04:31	65.24	OK	1078	2026-09-11 04:32	68.65	OK
1079	2026-09-11 04:33	66.22	OK	1080	2026-09-11 04:34	65.00	OK
1081	2026-09-11 04:35	66.56	OK	1082	2026-09-11 04:36	65.34	OK
1083	2026-09-11 04:37	68.09	OK	1084	2026-09-11 04:38	67.90	OK
1085	2026-09-11 04:39	68.21	OK	1086	2026-09-11 04:40	68.13	OK
1087	2026-09-11 04:41	65.21	OK	1088	2026-09-11 04:42	65.27	OK
1089	2026-09-11 04:43	66.26	OK	1090	2026-09-11 04:44	65.99	OK
1091	2026-09-11 04:45	67.50	OK	1092	2026-09-11 04:46	66.21	OK
1093	2026-09-11 04:47	66.73	OK	1094	2026-09-11 04:48	66.92	OK
1095	2026-09-11 04:49	65.86	OK	1096	2026-09-11 04:50	65.41	OK
1097	2026-09-11 04:51	64.84	OK	1098	2026-09-11 04:52	65.79	OK
1099	2026-09-11 04:53	65.56	OK	1100	2026-09-11 04:54	67.76	OK
1101	2026-09-11 04:55	68.79	OK	1102	2026-09-11 04:56	63.18	OK
1103	2026-09-11 04:57	65.06	OK	1104	2026-09-11 04:58	66.71	OK
1105	2026-09-11 04:59	66.74	OK	1106	2026-09-11 05:00	66.72	OK
1107	2026-09-11 05:01	65.54	OK	1108	2026-09-11 05:02	65.27	OK
1109	2026-09-11 05:03	64.72	OK	1110	2026-09-11 05:04	66.38	OK
1111	2026-09-11 05:05	66.72	OK	1112	2026-09-11 05:06	65.63	OK
1113	2026-09-11 05:07	62.28	OK	1114	2026-09-11 05:08	63.35	OK
1115	2026-09-11 05:09	64.47	OK	1116	2026-09-11 05:10	68.52	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1117	2026-09-11 05:11	64.97	OK	1118	2026-09-11 05:12	63.67	OK
1119	2026-09-11 05:13	65.70	OK	1120	2026-09-11 05:14	64.66	OK
1121	2026-09-11 05:15	65.91	OK	1122	2026-09-11 05:16	64.70	OK
1123	2026-09-11 05:17	63.36	OK	1124	2026-09-11 05:18	66.57	OK
1125	2026-09-11 05:19	66.67	OK	1126	2026-09-11 05:20	64.84	OK
1127	2026-09-11 05:21	64.58	OK	1128	2026-09-11 05:22	65.72	OK
1129	2026-09-11 05:23	66.65	OK	1130	2026-09-11 05:24	64.09	OK
1131	2026-09-11 05:25	65.38	OK	1132	2026-09-11 05:26	64.40	OK
1133	2026-09-11 05:27	66.22	OK	1134	2026-09-11 05:28	67.54	OK
1135	2026-09-11 05:29	64.71	OK	1136	2026-09-11 05:30	64.34	OK
1137	2026-09-11 05:31	66.03	OK	1138	2026-09-11 05:32	63.23	OK
1139	2026-09-11 05:33	65.30	OK	1140	2026-09-11 05:34	64.28	OK
1141	2026-09-11 05:35	67.25	OK	1142	2026-09-11 05:36	64.73	OK
1143	2026-09-11 05:37	62.76	OK	1144	2026-09-11 05:38	64.72	OK
1145	2026-09-11 05:39	64.61	OK	1146	2026-09-11 05:40	63.79	OK
1147	2026-09-11 05:41	64.73	OK	1148	2026-09-11 05:42	64.56	OK
1149	2026-09-11 05:43	64.36	OK	1150	2026-09-11 05:44	65.31	OK
1151	2026-09-11 05:45	64.49	OK	1152	2026-09-11 05:46	66.65	OK
1153	2026-09-11 05:47	65.03	OK	1154	2026-09-11 05:48	62.42	OK
1155	2026-09-11 05:49	65.90	OK	1156	2026-09-11 05:50	62.85	OK
1157	2026-09-11 05:51	63.96	OK	1158	2026-09-11 05:52	64.05	OK
1159	2026-09-11 05:53	63.34	OK	1160	2026-09-11 05:54	62.85	OK
1161	2026-09-11 05:55	63.46	OK	1162	2026-09-11 05:56	62.67	OK
1163	2026-09-11 05:57	61.67	OK	1164	2026-09-11 05:58	65.39	OK
1165	2026-09-11 05:59	63.46	OK	1166	2026-09-11 06:00	63.44	OK
1167	2026-09-11 06:01	64.97	OK	1168	2026-09-11 06:02	63.70	OK
1169	2026-09-11 06:03	66.08	OK	1170	2026-09-11 06:04	62.17	OK
1171	2026-09-11 06:05	63.11	OK	1172	2026-09-11 06:06	65.99	OK
1173	2026-09-11 06:07	64.64	OK	1174	2026-09-11 06:08	63.04	OK
1175	2026-09-11 06:09	63.40	OK	1176	2026-09-11 06:10	63.64	OK
1177	2026-09-11 06:11	63.63	OK	1178	2026-09-11 06:12	64.57	OK
1179	2026-09-11 06:13	63.29	OK	1180	2026-09-11 06:14	62.62	OK
1181	2026-09-11 06:15	63.58	OK	1182	2026-09-11 06:16	61.77	OK
1183	2026-09-11 06:17	60.84	OK	1184	2026-09-11 06:18	63.65	OK
1185	2026-09-11 06:19	63.17	OK	1186	2026-09-11 06:20	63.97	OK
1187	2026-09-11 06:21	63.95	OK	1188	2026-09-11 06:22	61.41	OK
1189	2026-09-11 06:23	63.84	OK	1190	2026-09-11 06:24	64.56	OK
1191	2026-09-11 06:25	64.41	OK	1192	2026-09-11 06:26	62.50	OK
1193	2026-09-11 06:27	63.69	OK	1194	2026-09-11 06:28	62.38	OK
1195	2026-09-11 06:29	62.40	OK	1196	2026-09-11 06:30	63.77	OK
1197	2026-09-11 06:31	64.09	OK	1198	2026-09-11 06:32	64.14	OK
1199	2026-09-11 06:33	63.27	OK	1200	2026-09-11 06:34	62.39	OK
1201	2026-09-11 06:35	65.14	OK	1202	2026-09-11 06:36	60.79	OK
1203	2026-09-11 06:37	64.94	OK	1204	2026-09-11 06:38	63.20	OK
1205	2026-09-11 06:39	64.42	OK	1206	2026-09-11 06:40	60.28	OK
1207	2026-09-11 06:41	62.07	OK	1208	2026-09-11 06:42	62.71	OK
1209	2026-09-11 06:43	62.06	OK	1210	2026-09-11 06:44	65.25	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1211	2026-09-11 06:45	61.52	OK	1212	2026-09-11 06:46	61.51	OK
1213	2026-09-11 06:47	63.32	OK	1214	2026-09-11 06:48	63.43	OK
1215	2026-09-11 06:49	60.47	OK	1216	2026-09-11 06:50	61.45	OK
1217	2026-09-11 06:51	62.30	OK	1218	2026-09-11 06:52	62.17	OK
1219	2026-09-11 06:53	64.40	OK	1220	2026-09-11 06:54	61.93	OK
1221	2026-09-11 06:55	62.54	OK	1222	2026-09-11 06:56	62.80	OK
1223	2026-09-11 06:57	61.63	OK	1224	2026-09-11 06:58	63.10	OK
1225	2026-09-11 06:59	63.78	OK	1226	2026-09-11 07:00	61.85	OK
1227	2026-09-11 07:01	62.25	OK	1228	2026-09-11 07:02	62.83	OK
1229	2026-09-11 07:03	63.53	OK	1230	2026-09-11 07:04	63.73	OK
1231	2026-09-11 07:05	62.93	OK	1232	2026-09-11 07:06	61.45	OK
1233	2026-09-11 07:07	61.71	OK	1234	2026-09-11 07:08	63.27	OK
1235	2026-09-11 07:09	62.25	OK	1236	2026-09-11 07:10	62.44	OK
1237	2026-09-11 07:11	62.21	OK	1238	2026-09-11 07:12	61.73	OK
1239	2026-09-11 07:13	61.65	OK	1240	2026-09-11 07:14	60.29	OK
1241	2026-09-11 07:15	61.00	OK	1242	2026-09-11 07:16	61.15	OK
1243	2026-09-11 07:17	64.25	OK	1244	2026-09-11 07:18	63.65	OK
1245	2026-09-11 07:19	64.61	OK	1246	2026-09-11 07:20	63.38	OK
1247	2026-09-11 07:21	61.83	OK	1248	2026-09-11 07:22	60.70	OK
1249	2026-09-11 07:23	62.57	OK	1250	2026-09-11 07:24	61.31	OK
1251	2026-09-11 07:25	60.75	OK	1252	2026-09-11 07:26	63.01	OK
1253	2026-09-11 07:27	63.12	OK	1254	2026-09-11 07:28	59.27	OK
1255	2026-09-11 07:29	62.30	OK	1256	2026-09-11 07:30	63.48	OK
1257	2026-09-11 07:31	61.78	OK	1258	2026-09-11 07:32	62.34	OK
1259	2026-09-11 07:33	61.87	OK	1260	2026-09-11 07:34	59.87	OK
1261	2026-09-11 07:35	59.98	OK	1262	2026-09-11 07:36	60.50	OK
1263	2026-09-11 07:37	62.93	OK	1264	2026-09-11 07:38	62.12	OK
1265	2026-09-11 07:39	63.16	OK	1266	2026-09-11 07:40	62.61	OK
1267	2026-09-11 07:41	62.20	OK	1268	2026-09-11 07:42	63.23	OK
1269	2026-09-11 07:43	60.82	OK	1270	2026-09-11 07:44	60.12	OK
1271	2026-09-11 07:45	58.29	OK	1272	2026-09-11 07:46	61.89	OK
1273	2026-09-11 07:47	62.42	OK	1274	2026-09-11 07:48	61.76	OK
1275	2026-09-11 07:49	58.67	OK	1276	2026-09-11 07:50	60.85	OK
1277	2026-09-11 07:51	62.07	OK	1278	2026-09-11 07:52	63.00	OK
1279	2026-09-11 07:53	59.97	OK	1280	2026-09-11 07:54	60.49	OK
1281	2026-09-11 07:55	61.71	OK	1282	2026-09-11 07:56	61.56	OK
1283	2026-09-11 07:57	62.40	OK	1284	2026-09-11 07:58	62.28	OK
1285	2026-09-11 07:59	62.65	OK	1286	2026-09-11 08:00	61.79	OK
1287	2026-09-11 08:01	62.40	OK	1288	2026-09-11 08:02	59.65	OK
1289	2026-09-11 08:03	60.40	OK	1290	2026-09-11 08:04	60.18	OK
1291	2026-09-11 08:05	58.31	OK	1292	2026-09-11 08:06	60.14	OK
1293	2026-09-11 08:07	59.55	OK	1294	2026-09-11 08:08	60.37	OK
1295	2026-09-11 08:09	61.11	OK	1296	2026-09-11 08:10	59.12	OK
1297	2026-09-11 08:11	58.91	OK	1298	2026-09-11 08:12	61.08	OK
1299	2026-09-11 08:13	62.25	OK	1300	2026-09-11 08:14	60.67	OK
1301	2026-09-11 08:15	62.81	OK	1302	2026-09-11 08:16	61.74	OK
1303	2026-09-11 08:17	61.66	OK	1304	2026-09-11 08:18	62.11	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1305	2026-09-11 08:19	60.46	OK	1306	2026-09-11 08:20	60.66	OK
1307	2026-09-11 08:21	59.24	OK	1308	2026-09-11 08:22	62.04	OK
1309	2026-09-11 08:23	59.10	OK	1310	2026-09-11 08:24	61.14	OK
1311	2026-09-11 08:25	62.67	OK	1312	2026-09-11 08:26	61.28	OK
1313	2026-09-11 08:27	61.30	OK	1314	2026-09-11 08:28	59.06	OK
1315	2026-09-11 08:29	58.41	OK	1316	2026-09-11 08:30	61.72	OK
1317	2026-09-11 08:31	62.44	OK	1318	2026-09-11 08:32	60.23	OK
1319	2026-09-11 08:33	58.85	OK	1320	2026-09-11 08:34	60.25	OK
1321	2026-09-11 08:35	61.68	OK	1322	2026-09-11 08:36	60.87	OK
1323	2026-09-11 08:37	60.43	OK	1324	2026-09-11 08:38	61.05	OK
1325	2026-09-11 08:39	58.75	OK	1326	2026-09-11 08:40	60.48	OK
1327	2026-09-11 08:41	60.93	OK	1328	2026-09-11 08:42	61.26	OK
1329	2026-09-11 08:43	59.33	OK	1330	2026-09-11 08:44	59.80	OK
1331	2026-09-11 08:45	59.70	OK	1332	2026-09-11 08:46	60.40	OK
1333	2026-09-11 08:47	58.83	OK	1334	2026-09-11 08:48	60.17	OK
1335	2026-09-11 08:49	61.51	OK	1336	2026-09-11 08:50	60.23	OK
1337	2026-09-11 08:51	60.80	OK	1338	2026-09-11 08:52	58.17	OK
1339	2026-09-11 08:53	61.53	OK	1340	2026-09-11 08:54	60.41	OK
1341	2026-09-11 08:55	60.61	OK	1342	2026-09-11 08:56	59.09	OK
1343	2026-09-11 08:57	58.07	OK	1344	2026-09-11 08:58	60.83	OK
1345	2026-09-11 08:59	59.11	OK	1346	2026-09-11 09:00	60.08	OK
1347	2026-09-11 09:01	59.92	OK	1348	2026-09-11 09:02	61.50	OK
1349	2026-09-11 09:03	61.18	OK	1350	2026-09-11 09:04	57.97	OK
1351	2026-09-11 09:05	59.29	OK	1352	2026-09-11 09:06	60.33	OK
1353	2026-09-11 09:07	59.10	OK	1354	2026-09-11 09:08	61.60	OK
1355	2026-09-11 09:09	59.23	OK	1356	2026-09-11 09:10	59.30	OK
1357	2026-09-11 09:11	62.11	OK	1358	2026-09-11 09:12	62.01	OK
1359	2026-09-11 09:13	59.80	OK	1360	2026-09-11 09:14	58.54	OK
1361	2026-09-11 09:15	61.46	OK	1362	2026-09-11 09:16	60.64	OK
1363	2026-09-11 09:17	59.67	OK	1364	2026-09-11 09:18	63.45	OK
1365	2026-09-11 09:19	60.20	OK	1366	2026-09-11 09:20	59.76	OK
1367	2026-09-11 09:21	60.90	OK	1368	2026-09-11 09:22	60.12	OK
1369	2026-09-11 09:23	58.83	OK	1370	2026-09-11 09:24	59.21	OK
1371	2026-09-11 09:25	59.80	OK	1372	2026-09-11 09:26	60.61	OK
1373	2026-09-11 09:27	59.45	OK	1374	2026-09-11 09:28	59.56	OK
1375	2026-09-11 09:29	59.98	OK	1376	2026-09-11 09:30	58.13	OK
1377	2026-09-11 09:31	60.53	OK	1378	2026-09-11 09:32	60.93	OK
1379	2026-09-11 09:33	57.82	OK	1380	2026-09-11 09:34	58.00	OK
1381	2026-09-11 09:35	58.46	OK	1382	2026-09-11 09:36	61.07	OK
1383	2026-09-11 09:37	61.72	OK	1384	2026-09-11 09:38	58.36	OK
1385	2026-09-11 09:39	59.50	OK	1386	2026-09-11 09:40	61.72	OK
1387	2026-09-11 09:41	59.88	OK	1388	2026-09-11 09:42	58.12	OK
1389	2026-09-11 09:43	60.40	OK	1390	2026-09-11 09:44	62.64	OK
1391	2026-09-11 09:45	59.52	OK	1392	2026-09-11 09:46	59.49	OK
1393	2026-09-11 09:47	58.16	OK	1394	2026-09-11 09:48	60.50	OK
1395	2026-09-11 09:49	58.67	OK	1396	2026-09-11 09:50	61.51	OK
1397	2026-09-11 09:51	60.05	OK	1398	2026-09-11 09:52	58.43	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1399	2026-09-11 09:53	62.68	OK	1400	2026-09-11 09:54	60.10	OK
1401	2026-09-11 09:55	58.89	OK	1402	2026-09-11 09:56	59.51	OK
1403	2026-09-11 09:57	61.77	OK	1404	2026-09-11 09:58	60.14	OK
1405	2026-09-11 09:59	57.36	OK	1406	2026-09-11 10:00	60.32	OK
1407	2026-09-11 10:01	58.89	OK	1408	2026-09-11 10:02	60.96	OK
1409	2026-09-11 10:03	59.00	OK	1410	2026-09-11 10:04	58.38	OK
1411	2026-09-11 10:05	60.17	OK	1412	2026-09-11 10:06	60.14	OK
1413	2026-09-11 10:07	58.40	OK	1414	2026-09-11 10:08	61.51	OK
1415	2026-09-11 10:09	62.45	OK	1416	2026-09-11 10:10	57.21	OK
1417	2026-09-11 10:11	60.31	OK	1418	2026-09-11 10:12	59.02	OK
1419	2026-09-11 10:13	59.29	OK	1420	2026-09-11 10:14	58.53	OK
1421	2026-09-11 10:15	58.97	OK	1422	2026-09-11 10:16	61.01	OK
1423	2026-09-11 10:17	60.58	OK	1424	2026-09-11 10:18	57.65	OK
1425	2026-09-11 10:19	60.91	OK	1426	2026-09-11 10:20	60.36	OK
1427	2026-09-11 10:21	59.15	OK	1428	2026-09-11 10:22	60.24	OK
1429	2026-09-11 10:23	57.72	OK	1430	2026-09-11 10:24	58.14	OK
1431	2026-09-11 10:25	59.51	OK	1432	2026-09-11 10:26	57.27	OK
1433	2026-09-11 10:27	60.65	OK	1434	2026-09-11 10:28	59.42	OK
1435	2026-09-11 10:29	62.24	OK	1436	2026-09-11 10:30	59.31	OK
1437	2026-09-11 10:31	58.30	OK	1438	2026-09-11 10:32	58.56	OK
1439	2026-09-11 10:33	59.51	OK	1440	2026-09-11 10:34	58.16	OK
1441	2026-09-11 10:35	61.98	OK	1442	2026-09-11 10:36	59.28	OK
1443	2026-09-11 10:37	59.54	OK	1444	2026-09-11 10:38	57.60	OK
1445	2026-09-11 10:39	58.84	OK	1446	2026-09-11 10:40	58.69	OK
1447	2026-09-11 10:41	56.88	OK	1448	2026-09-11 10:42	59.34	OK
1449	2026-09-11 10:43	59.38	OK	1450	2026-09-11 10:44	59.64	OK
1451	2026-09-11 10:45	59.74	OK	1452	2026-09-11 10:46	59.86	OK
1453	2026-09-11 10:47	59.87	OK	1454	2026-09-11 10:48	58.28	OK
1455	2026-09-11 10:49	58.57	OK	1456	2026-09-11 10:50	57.76	OK
1457	2026-09-11 10:51	58.17	OK	1458	2026-09-11 10:52	60.20	OK
1459	2026-09-11 10:53	60.25	OK	1460	2026-09-11 10:54	58.17	OK
1461	2026-09-11 10:55	61.35	OK	1462	2026-09-11 10:56	60.28	OK
1463	2026-09-11 10:57	60.11	OK	1464	2026-09-11 10:58	58.04	OK
1465	2026-09-11 10:59	57.70	OK	1466	2026-09-11 11:00	57.36	OK
1467	2026-09-11 11:01	60.74	OK	1468	2026-09-11 11:02	61.62	OK
1469	2026-09-11 11:03	58.07	OK	1470	2026-09-11 11:04	58.52	OK
1471	2026-09-11 11:05	59.35	OK	1472	2026-09-11 11:06	58.64	OK
1473	2026-09-11 11:07	59.81	OK	1474	2026-09-11 11:08	58.28	OK
1475	2026-09-11 11:09	60.74	OK	1476	2026-09-11 11:10	58.23	OK
1477	2026-09-11 11:11	56.63	OK	1478	2026-09-11 11:12	58.50	OK
1479	2026-09-11 11:13	58.05	OK	1480	2026-09-11 11:14	59.76	OK
1481	2026-09-11 11:15	59.67	OK	1482	2026-09-11 11:16	58.02	OK
1483	2026-09-11 11:17	61.46	OK	1484	2026-09-11 11:18	58.74	OK
1485	2026-09-11 11:19	59.29	OK	1486	2026-09-11 11:20	61.96	OK
1487	2026-09-11 11:21	60.67	OK	1488	2026-09-11 11:22	59.89	OK
1489	2026-09-11 11:23	60.36	OK	1490	2026-09-11 11:24	62.45	OK
1491	2026-09-11 11:25	59.60	OK	1492	2026-09-11 11:26	60.62	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1493	2026-09-11 11:27	60.44	OK	1494	2026-09-11 11:28	56.35	OK
1495	2026-09-11 11:29	57.76	OK	1496	2026-09-11 11:30	59.84	OK
1497	2026-09-11 11:31	61.18	OK	1498	2026-09-11 11:32	58.49	OK
1499	2026-09-11 11:33	60.14	OK	1500	2026-09-11 11:34	61.46	OK
1501	2026-09-11 11:35	60.83	OK	1502	2026-09-11 11:36	59.75	OK
1503	2026-09-11 11:37	60.41	OK	1504	2026-09-11 11:38	58.57	OK
1505	2026-09-11 11:39	58.43	OK	1506	2026-09-11 11:40	60.02	OK
1507	2026-09-11 11:41	59.15	OK	1508	2026-09-11 11:42	59.41	OK
1509	2026-09-11 11:43	57.85	OK	1510	2026-09-11 11:44	57.71	OK
1511	2026-09-11 11:45	58.64	OK	1512	2026-09-11 11:46	59.79	OK
1513	2026-09-11 11:47	60.40	OK	1514	2026-09-11 11:48	59.83	OK
1515	2026-09-11 11:49	59.85	OK	1516	2026-09-11 11:50	61.61	OK
1517	2026-09-11 11:51	59.64	OK	1518	2026-09-11 11:52	60.89	OK
1519	2026-09-11 11:53	58.34	OK	1520	2026-09-11 11:54	58.84	OK
1521	2026-09-11 11:55	59.33	OK	1522	2026-09-11 11:56	61.62	OK
1523	2026-09-11 11:57	59.83	OK	1524	2026-09-11 11:58	58.35	OK
1525	2026-09-11 11:59	59.24	OK	1526	2026-09-11 12:00	61.18	OK
1527	2026-09-11 12:01	61.67	OK	1528	2026-09-11 12:02	60.21	OK
1529	2026-09-11 12:03	59.19	OK	1530	2026-09-11 12:04	57.98	OK
1531	2026-09-11 12:05	58.26	OK	1532	2026-09-11 12:06	61.66	OK
1533	2026-09-11 12:07	58.84	OK	1534	2026-09-11 12:08	59.12	OK
1535	2026-09-11 12:09	61.00	OK	1536	2026-09-11 12:10	62.24	OK
1537	2026-09-11 12:11	60.82	OK	1538	2026-09-11 12:12	60.10	OK
1539	2026-09-11 12:13	61.68	OK	1540	2026-09-11 12:14	58.68	OK
1541	2026-09-11 12:15	60.47	OK	1542	2026-09-11 12:16	59.81	OK
1543	2026-09-11 12:17	59.13	OK	1544	2026-09-11 12:18	58.55	OK
1545	2026-09-11 12:19	60.13	OK	1546	2026-09-11 12:20	61.55	OK
1547	2026-09-11 12:21	61.45	OK	1548	2026-09-11 12:22	59.99	OK
1549	2026-09-11 12:23	59.63	OK	1550	2026-09-11 12:24	58.47	OK
1551	2026-09-11 12:25	60.57	OK	1552	2026-09-11 12:26	59.92	OK
1553	2026-09-11 12:27	58.86	OK	1554	2026-09-11 12:28	61.41	OK
1555	2026-09-11 12:29	59.55	OK	1556	2026-09-11 12:30	61.67	OK
1557	2026-09-11 12:31	60.67	OK	1558	2026-09-11 12:32	61.31	OK
1559	2026-09-11 12:33	61.55	OK	1560	2026-09-11 12:34	59.22	OK
1561	2026-09-11 12:35	61.81	OK	1562	2026-09-11 12:36	63.34	OK
1563	2026-09-11 12:37	61.29	OK	1564	2026-09-11 12:38	59.13	OK
1565	2026-09-11 12:39	60.54	OK	1566	2026-09-11 12:40	60.50	OK
1567	2026-09-11 12:41	59.04	OK	1568	2026-09-11 12:42	61.57	OK
1569	2026-09-11 12:43	61.70	OK	1570	2026-09-11 12:44	60.40	OK
1571	2026-09-11 12:45	58.15	OK	1572	2026-09-11 12:46	60.17	OK
1573	2026-09-11 12:47	61.97	OK	1574	2026-09-11 12:48	61.50	OK
1575	2026-09-11 12:49	62.30	OK	1576	2026-09-11 12:50	61.22	OK
1577	2026-09-11 12:51	59.35	OK	1578	2026-09-11 12:52	57.26	OK
1579	2026-09-11 12:53	59.01	OK	1580	2026-09-11 12:54	60.49	OK
1581	2026-09-11 12:55	60.19	OK	1582	2026-09-11 12:56	58.83	OK
1583	2026-09-11 12:57	61.27	OK	1584	2026-09-11 12:58	60.23	OK
1585	2026-09-11 12:59	61.13	OK	1586	2026-09-11 13:00	59.36	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1587	2026-09-11 13:01	59.45	OK	1588	2026-09-11 13:02	61.47	OK
1589	2026-09-11 13:03	61.65	OK	1590	2026-09-11 13:04	62.43	OK
1591	2026-09-11 13:05	60.67	OK	1592	2026-09-11 13:06	60.36	OK
1593	2026-09-11 13:07	60.53	OK	1594	2026-09-11 13:08	60.42	OK
1595	2026-09-11 13:09	61.10	OK	1596	2026-09-11 13:10	61.90	OK
1597	2026-09-11 13:11	61.77	OK	1598	2026-09-11 13:12	59.63	OK
1599	2026-09-11 13:13	60.00	OK	1600	2026-09-11 13:14	62.28	OK
1601	2026-09-11 13:15	59.89	OK	1602	2026-09-11 13:16	60.46	OK
1603	2026-09-11 13:17	59.81	OK	1604	2026-09-11 13:18	60.50	OK
1605	2026-09-11 13:19	61.18	OK	1606	2026-09-11 13:20	60.45	OK
1607	2026-09-11 13:21	61.57	OK	1608	2026-09-11 13:22	63.81	OK
1609	2026-09-11 13:23	61.91	OK	1610	2026-09-11 13:24	61.06	OK
1611	2026-09-11 13:25	62.57	OK	1612	2026-09-11 13:26	59.55	OK
1613	2026-09-11 13:27	59.57	OK	1614	2026-09-11 13:28	60.47	OK
1615	2026-09-11 13:29	62.44	OK	1616	2026-09-11 13:30	61.87	OK
1617	2026-09-11 13:31	59.85	OK	1618	2026-09-11 13:32	59.10	OK
1619	2026-09-11 13:33	62.82	OK	1620	2026-09-11 13:34	61.33	OK
1621	2026-09-11 13:35	62.60	OK	1622	2026-09-11 13:36	59.86	OK
1623	2026-09-11 13:37	63.32	OK	1624	2026-09-11 13:38	61.67	OK
1625	2026-09-11 13:39	62.28	OK	1626	2026-09-11 13:40	60.64	OK
1627	2026-09-11 13:41	60.60	OK	1628	2026-09-11 13:42	62.64	OK
1629	2026-09-11 13:43	59.82	OK	1630	2026-09-11 13:44	63.11	OK
1631	2026-09-11 13:45	60.52	OK	1632	2026-09-11 13:46	61.09	OK
1633	2026-09-11 13:47	61.27	OK	1634	2026-09-11 13:48	61.25	OK
1635	2026-09-11 13:49	62.20	OK	1636	2026-09-11 13:50	61.53	OK
1637	2026-09-11 13:51	63.09	OK	1638	2026-09-11 13:52	60.67	OK
1639	2026-09-11 13:53	60.44	OK	1640	2026-09-11 13:54	60.77	OK
1641	2026-09-11 13:55	61.03	OK	1642	2026-09-11 13:56	61.03	OK
1643	2026-09-11 13:57	61.67	OK	1644	2026-09-11 13:58	62.30	OK
1645	2026-09-11 13:59	62.46	OK	1646	2026-09-11 14:00	62.53	OK
1647	2026-09-11 14:01	60.52	OK	1648	2026-09-11 14:02	61.02	OK
1649	2026-09-11 14:03	61.54	OK	1650	2026-09-11 14:04	65.29	OK
1651	2026-09-11 14:05	61.80	OK	1652	2026-09-11 14:06	63.29	OK
1653	2026-09-11 14:07	62.86	OK	1654	2026-09-11 14:08	62.63	OK
1655	2026-09-11 14:09	62.45	OK	1656	2026-09-11 14:10	63.14	OK
1657	2026-09-11 14:11	61.25	OK	1658	2026-09-11 14:12	61.74	OK
1659	2026-09-11 14:13	63.02	OK	1660	2026-09-11 14:14	64.26	OK
1661	2026-09-11 14:15	62.89	OK	1662	2026-09-11 14:16	62.96	OK
1663	2026-09-11 14:17	62.03	OK	1664	2026-09-11 14:18	61.68	OK
1665	2026-09-11 14:19	63.53	OK	1666	2026-09-11 14:20	62.29	OK
1667	2026-09-11 14:21	60.65	OK	1668	2026-09-11 14:22	63.94	OK
1669	2026-09-11 14:23	62.70	OK	1670	2026-09-11 14:24	62.79	OK
1671	2026-09-11 14:25	64.45	OK	1672	2026-09-11 14:26	59.95	OK
1673	2026-09-11 14:27	61.58	OK	1674	2026-09-11 14:28	62.34	OK
1675	2026-09-11 14:29	62.46	OK	1676	2026-09-11 14:30	61.69	OK
1677	2026-09-11 14:31	61.87	OK	1678	2026-09-11 14:32	62.65	OK
1679	2026-09-11 14:33	62.24	OK	1680	2026-09-11 14:34	62.10	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1681	2026-09-11 14:35	61.71	OK	1682	2026-09-11 14:36	61.92	OK
1683	2026-09-11 14:37	64.42	OK	1684	2026-09-11 14:38	61.30	OK
1685	2026-09-11 14:39	61.99	OK	1686	2026-09-11 14:40	61.64	OK
1687	2026-09-11 14:41	63.84	OK	1688	2026-09-11 14:42	63.07	OK
1689	2026-09-11 14:43	63.11	OK	1690	2026-09-11 14:44	63.25	OK
1691	2026-09-11 14:45	62.83	OK	1692	2026-09-11 14:46	64.59	OK
1693	2026-09-11 14:47	62.67	OK	1694	2026-09-11 14:48	61.28	OK
1695	2026-09-11 14:49	63.38	OK	1696	2026-09-11 14:50	62.59	OK
1697	2026-09-11 14:51	64.32	OK	1698	2026-09-11 14:52	62.46	OK
1699	2026-09-11 14:53	61.46	OK	1700	2026-09-11 14:54	63.48	OK
1701	2026-09-11 14:55	62.00	OK	1702	2026-09-11 14:56	62.83	OK
1703	2026-09-11 14:57	63.40	OK	1704	2026-09-11 14:58	63.82	OK
1705	2026-09-11 14:59	64.33	OK	1706	2026-09-11 15:00	63.87	OK
1707	2026-09-11 15:01	65.68	OK	1708	2026-09-11 15:02	61.53	OK
1709	2026-09-11 15:03	62.80	OK	1710	2026-09-11 15:04	62.16	OK
1711	2026-09-11 15:05	62.54	OK	1712	2026-09-11 15:06	63.37	OK
1713	2026-09-11 15:07	66.12	OK	1714	2026-09-11 15:08	65.52	OK
1715	2026-09-11 15:09	63.86	OK	1716	2026-09-11 15:10	63.21	OK
1717	2026-09-11 15:11	63.21	OK	1718	2026-09-11 15:12	62.09	OK
1719	2026-09-11 15:13	64.37	OK	1720	2026-09-11 15:14	63.40	OK
1721	2026-09-11 15:15	63.71	OK	1722	2026-09-11 15:16	64.09	OK
1723	2026-09-11 15:17	65.30	OK	1724	2026-09-11 15:18	64.63	OK
1725	2026-09-11 15:19	64.24	OK	1726	2026-09-11 15:20	65.01	OK
1727	2026-09-11 15:21	66.12	OK	1728	2026-09-11 15:22	64.11	OK
1729	2026-09-11 15:23	64.73	OK	1730	2026-09-11 15:24	64.22	OK
1731	2026-09-11 15:25	63.98	OK	1732	2026-09-11 15:26	64.80	OK
1733	2026-09-11 15:27	64.90	OK	1734	2026-09-11 15:28	64.96	OK
1735	2026-09-11 15:29	63.74	OK	1736	2026-09-11 15:30	64.00	OK
1737	2026-09-11 15:31	62.96	OK	1738	2026-09-11 15:32	65.27	OK
1739	2026-09-11 15:33	65.14	OK	1740	2026-09-11 15:34	66.72	OK
1741	2026-09-11 15:35	65.15	OK	1742	2026-09-11 15:36	66.55	OK
1743	2026-09-11 15:37	62.64	OK	1744	2026-09-11 15:38	63.72	OK
1745	2026-09-11 15:39	65.94	OK	1746	2026-09-11 15:40	66.20	OK
1747	2026-09-11 15:41	65.25	OK	1748	2026-09-11 15:42	63.67	OK
1749	2026-09-11 15:43	65.27	OK	1750	2026-09-11 15:44	63.76	OK
1751	2026-09-11 15:45	63.83	OK	1752	2026-09-11 15:46	65.28	OK
1753	2026-09-11 15:47	64.17	OK	1754	2026-09-11 15:48	63.98	OK
1755	2026-09-11 15:49	63.63	OK	1756	2026-09-11 15:50	64.10	OK
1757	2026-09-11 15:51	63.67	OK	1758	2026-09-11 15:52	65.58	OK
1759	2026-09-11 15:53	65.20	OK	1760	2026-09-11 15:54	65.04	OK
1761	2026-09-11 15:55	65.64	OK	1762	2026-09-11 15:56	64.63	OK
1763	2026-09-11 15:57	62.74	OK	1764	2026-09-11 15:58	66.14	OK
1765	2026-09-11 15:59	65.81	OK	1766	2026-09-11 16:00	63.03	OK
1767	2026-09-11 16:01	64.95	OK	1768	2026-09-11 16:02	63.23	OK
1769	2026-09-11 16:03	66.79	OK	1770	2026-09-11 16:04	64.12	OK
1771	2026-09-11 16:05	65.44	OK	1772	2026-09-11 16:06	65.80	OK
1773	2026-09-11 16:07	63.21	OK	1774	2026-09-11 16:08	63.97	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1775	2026-09-11 16:09	65.01	OK	1776	2026-09-11 16:10	63.36	OK
1777	2026-09-11 16:11	67.51	OK	1778	2026-09-11 16:12	63.86	OK
1779	2026-09-11 16:13	64.14	OK	1780	2026-09-11 16:14	64.17	OK
1781	2026-09-11 16:15	63.69	OK	1782	2026-09-11 16:16	64.15	OK
1783	2026-09-11 16:17	66.54	OK	1784	2026-09-11 16:18	63.96	OK
1785	2026-09-11 16:19	66.16	OK	1786	2026-09-11 16:20	63.93	OK
1787	2026-09-11 16:21	63.87	OK	1788	2026-09-11 16:22	66.73	OK
1789	2026-09-11 16:23	64.83	OK	1790	2026-09-11 16:24	64.90	OK
1791	2026-09-11 16:25	65.17	OK	1792	2026-09-11 16:26	65.46	OK
1793	2026-09-11 16:27	64.68	OK	1794	2026-09-11 16:28	65.19	OK
1795	2026-09-11 16:29	66.57	OK	1796	2026-09-11 16:30	64.38	OK
1797	2026-09-11 16:31	64.67	OK	1798	2026-09-11 16:32	68.96	OK
1799	2026-09-11 16:33	63.64	OK	1800	2026-09-11 16:34	67.01	OK
1801	2026-09-11 16:35	67.32	OK	1802	2026-09-11 16:36	64.75	OK
1803	2026-09-11 16:37	64.47	OK	1804	2026-09-11 16:38	68.50	OK
1805	2026-09-11 16:39	66.82	OK	1806	2026-09-11 16:40	63.89	OK
1807	2026-09-11 16:41	64.38	OK	1808	2026-09-11 16:42	64.66	OK
1809	2026-09-11 16:43	64.57	OK	1810	2026-09-11 16:44	68.29	OK
1811	2026-09-11 16:45	65.09	OK	1812	2026-09-11 16:46	65.98	OK
1813	2026-09-11 16:47	67.52	OK	1814	2026-09-11 16:48	66.96	OK
1815	2026-09-11 16:49	63.35	OK	1816	2026-09-11 16:50	67.69	OK
1817	2026-09-11 16:51	68.03	OK	1818	2026-09-11 16:52	66.59	OK
1819	2026-09-11 16:53	66.90	OK	1820	2026-09-11 16:54	64.12	OK
1821	2026-09-11 16:55	66.45	OK	1822	2026-09-11 16:56	67.81	OK
1823	2026-09-11 16:57	68.80	OK	1824	2026-09-11 16:58	65.45	OK
1825	2026-09-11 16:59	68.97	OK	1826	2026-09-11 17:00	68.39	OK
1827	2026-09-11 17:01	67.28	OK	1828	2026-09-11 17:02	63.47	OK
1829	2026-09-11 17:03	67.23	OK	1830	2026-09-11 17:04	66.76	OK
1831	2026-09-11 17:05	66.58	OK	1832	2026-09-11 17:06	66.22	OK
1833	2026-09-11 17:07	67.19	OK	1834	2026-09-11 17:08	65.76	OK
1835	2026-09-11 17:09	66.60	OK	1836	2026-09-11 17:10	66.47	OK
1837	2026-09-11 17:11	65.45	OK	1838	2026-09-11 17:12	69.13	OK
1839	2026-09-11 17:13	67.66	OK	1840	2026-09-11 17:14	68.80	OK
1841	2026-09-11 17:15	69.52	OK	1842	2026-09-11 17:16	67.22	OK
1843	2026-09-11 17:17	67.37	OK	1844	2026-09-11 17:18	67.81	OK
1845	2026-09-11 17:19	68.76	OK	1846	2026-09-11 17:20	70.02	OK
1847	2026-09-11 17:21	67.14	OK	1848	2026-09-11 17:22	65.08	OK
1849	2026-09-11 17:23	67.98	OK	1850	2026-09-11 17:24	65.72	OK
1851	2026-09-11 17:25	67.12	OK	1852	2026-09-11 17:26	65.43	OK
1853	2026-09-11 17:27	67.58	OK	1854	2026-09-11 17:28	66.48	OK
1855	2026-09-11 17:29	66.37	OK	1856	2026-09-11 17:30	69.15	OK
1857	2026-09-11 17:31	67.30	OK	1858	2026-09-11 17:32	66.79	OK
1859	2026-09-11 17:33	67.89	OK	1860	2026-09-11 17:34	68.92	OK
1861	2026-09-11 17:35	66.85	OK	1862	2026-09-11 17:36	67.18	OK
1863	2026-09-11 17:37	69.57	OK	1864	2026-09-11 17:38	66.90	OK
1865	2026-09-11 17:39	69.08	OK	1866	2026-09-11 17:40	66.26	OK
1867	2026-09-11 17:41	69.21	OK	1868	2026-09-11 17:42	68.29	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1869	2026-09-11 17:43	67.73	OK	1870	2026-09-11 17:44	67.01	OK
1871	2026-09-11 17:45	68.81	OK	1872	2026-09-11 17:46	66.26	OK
1873	2026-09-11 17:47	67.64	OK	1874	2026-09-11 17:48	67.05	OK
1875	2026-09-11 17:49	69.10	OK	1876	2026-09-11 17:50	68.65	OK
1877	2026-09-11 17:51	65.66	OK	1878	2026-09-11 17:52	69.57	OK
1879	2026-09-11 17:53	70.49	OK	1880	2026-09-11 17:54	68.23	OK
1881	2026-09-11 17:55	69.01	OK	1882	2026-09-11 17:56	68.54	OK
1883	2026-09-11 17:57	68.41	OK	1884	2026-09-11 17:58	67.20	OK
1885	2026-09-11 17:59	66.40	OK	1886	2026-09-11 18:00	68.79	OK
1887	2026-09-11 18:01	67.49	OK	1888	2026-09-11 18:02	67.42	OK
1889	2026-09-11 18:03	69.70	OK	1890	2026-09-11 18:04	70.69	OK
1891	2026-09-11 18:05	69.56	OK	1892	2026-09-11 18:06	71.07	OK
1893	2026-09-11 18:07	68.60	OK	1894	2026-09-11 18:08	67.51	OK
1895	2026-09-11 18:09	67.51	OK	1896	2026-09-11 18:10	69.44	OK
1897	2026-09-11 18:11	66.82	OK	1898	2026-09-11 18:12	66.55	OK
1899	2026-09-11 18:13	69.15	OK	1900	2026-09-11 18:14	68.06	OK
1901	2026-09-11 18:15	68.05	OK	1902	2026-09-11 18:16	69.18	OK
1903	2026-09-11 18:17	68.38	OK	1904	2026-09-11 18:18	67.07	OK
1905	2026-09-11 18:19	68.80	OK	1906	2026-09-11 18:20	67.61	OK
1907	2026-09-11 18:21	68.19	OK	1908	2026-09-11 18:22	67.76	OK
1909	2026-09-11 18:23	67.06	OK	1910	2026-09-11 18:24	66.89	OK
1911	2026-09-11 18:25	69.24	OK	1912	2026-09-11 18:26	68.54	OK
1913	2026-09-11 18:27	67.03	OK	1914	2026-09-11 18:28	69.24	OK
1915	2026-09-11 18:29	70.19	OK	1916	2026-09-11 18:30	68.83	OK
1917	2026-09-11 18:31	69.88	OK	1918	2026-09-11 18:32	72.06	OK
1919	2026-09-11 18:33	68.00	OK	1920	2026-09-11 18:34	69.26	OK
1921	2026-09-11 18:35	69.96	OK	1922	2026-09-11 18:36	71.95	OK
1923	2026-09-11 18:37	69.64	OK	1924	2026-09-11 18:38	69.78	OK
1925	2026-09-11 18:39	66.48	OK	1926	2026-09-11 18:40	69.52	OK
1927	2026-09-11 18:41	66.69	OK	1928	2026-09-11 18:42	68.54	OK
1929	2026-09-11 18:43	67.99	OK	1930	2026-09-11 18:44	70.79	OK
1931	2026-09-11 18:45	70.10	OK	1932	2026-09-11 18:46	70.93	OK
1933	2026-09-11 18:47	71.80	OK	1934	2026-09-11 18:48	70.55	OK
1935	2026-09-11 18:49	71.44	OK	1936	2026-09-11 18:50	70.31	OK
1937	2026-09-11 18:51	69.36	OK	1938	2026-09-11 18:52	69.27	OK
1939	2026-09-11 18:53	69.23	OK	1940	2026-09-11 18:54	67.81	OK
1941	2026-09-11 18:55	68.45	OK	1942	2026-09-11 18:56	70.28	OK
1943	2026-09-11 18:57	69.49	OK	1944	2026-09-11 18:58	70.39	OK
1945	2026-09-11 18:59	70.36	OK	1946	2026-09-11 19:00	71.87	OK
1947	2026-09-11 19:01	71.40	OK	1948	2026-09-11 19:02	68.67	OK
1949	2026-09-11 19:03	70.22	OK	1950	2026-09-11 19:04	69.56	OK
1951	2026-09-11 19:05	69.01	OK	1952	2026-09-11 19:06	69.35	OK
1953	2026-09-11 19:07	69.90	OK	1954	2026-09-11 19:08	70.60	OK
1955	2026-09-11 19:09	70.40	OK	1956	2026-09-11 19:10	69.09	OK
1957	2026-09-11 19:11	70.57	OK	1958	2026-09-11 19:12	69.97	OK
1959	2026-09-11 19:13	71.07	OK	1960	2026-09-11 19:14	71.49	OK
1961	2026-09-11 19:15	70.21	OK	1962	2026-09-11 19:16	69.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1963	2026-09-11 19:17	70.49	OK	1964	2026-09-11 19:18	70.66	OK
1965	2026-09-11 19:19	69.38	OK	1966	2026-09-11 19:20	70.81	OK
1967	2026-09-11 19:21	71.25	OK	1968	2026-09-11 19:22	72.48	OK
1969	2026-09-11 19:23	69.75	OK	1970	2026-09-11 19:24	71.50	OK
1971	2026-09-11 19:25	67.15	OK	1972	2026-09-11 19:26	70.09	OK
1973	2026-09-11 19:27	71.59	OK	1974	2026-09-11 19:28	69.07	OK
1975	2026-09-11 19:29	69.37	OK	1976	2026-09-11 19:30	72.73	OK
1977	2026-09-11 19:31	67.60	OK	1978	2026-09-11 19:32	69.49	OK
1979	2026-09-11 19:33	71.18	OK	1980	2026-09-11 19:34	71.29	OK
1981	2026-09-11 19:35	73.03	OK	1982	2026-09-11 19:36	70.04	OK
1983	2026-09-11 19:37	69.39	OK	1984	2026-09-11 19:38	70.52	OK
1985	2026-09-11 19:39	72.44	OK	1986	2026-09-11 19:40	70.05	OK
1987	2026-09-11 19:41	70.65	OK	1988	2026-09-11 19:42	73.46	OK
1989	2026-09-11 19:43	71.22	OK	1990	2026-09-11 19:44	71.04	OK
1991	2026-09-11 19:45	71.13	OK	1992	2026-09-11 19:46	71.92	OK
1993	2026-09-11 19:47	70.54	OK	1994	2026-09-11 19:48	69.96	OK
1995	2026-09-11 19:49	72.02	OK	1996	2026-09-11 19:50	70.72	OK
1997	2026-09-11 19:51	70.83	OK	1998	2026-09-11 19:52	70.90	OK
1999	2026-09-11 19:53	72.14	OK	2000	2026-09-11 19:54	69.22	OK
2001	2026-09-11 19:55	68.83	OK	2002	2026-09-11 19:56	69.00	OK
2003	2026-09-11 19:57	71.25	OK	2004	2026-09-11 19:58	73.11	OK
2005	2026-09-11 19:59	68.70	OK	2006	2026-09-11 20:00	70.71	OK
2007	2026-09-11 20:01	70.02	OK	2008	2026-09-11 20:02	72.73	OK
2009	2026-09-11 20:03	71.27	OK	2010	2026-09-11 20:04	69.26	OK
2011	2026-09-11 20:05	70.49	OK	2012	2026-09-11 20:06	73.68	OK
2013	2026-09-11 20:07	70.35	OK	2014	2026-09-11 20:08	71.96	OK
2015	2026-09-11 20:09	71.23	OK	2016	2026-09-11 20:10	70.48	OK
2017	2026-09-11 20:11	69.84	OK	2018	2026-09-11 20:12	73.27	OK
2019	2026-09-11 20:13	72.54	OK	2020	2026-09-11 20:14	71.80	OK
2021	2026-09-11 20:15	72.07	OK	2022	2026-09-11 20:16	72.10	OK
2023	2026-09-11 20:17	71.76	OK	2024	2026-09-11 20:18	70.51	OK
2025	2026-09-11 20:19	68.61	OK	2026	2026-09-11 20:20	71.26	OK
2027	2026-09-11 20:21	71.83	OK	2028	2026-09-11 20:22	72.02	OK
2029	2026-09-11 20:23	71.27	OK	2030	2026-09-11 20:24	69.00	OK
2031	2026-09-11 20:25	70.60	OK	2032	2026-09-11 20:26	70.36	OK
2033	2026-09-11 20:27	72.25	OK	2034	2026-09-11 20:28	71.16	OK
2035	2026-09-11 20:29	72.34	OK	2036	2026-09-11 20:30	71.95	OK
2037	2026-09-11 20:31	72.57	OK	2038	2026-09-11 20:32	70.33	OK
2039	2026-09-11 20:33	70.93	OK	2040	2026-09-11 20:34	72.99	OK
2041	2026-09-11 20:35	71.82	OK	2042	2026-09-11 20:36	75.06	OK
2043	2026-09-11 20:37	72.33	OK	2044	2026-09-11 20:38	71.66	OK
2045	2026-09-11 20:39	73.11	OK	2046	2026-09-11 20:40	70.88	OK
2047	2026-09-11 20:41	72.44	OK	2048	2026-09-11 20:42	71.96	OK
2049	2026-09-11 20:43	73.62	OK	2050	2026-09-11 20:44	70.26	OK
2051	2026-09-11 20:45	72.05	OK	2052	2026-09-11 20:46	72.83	OK
2053	2026-09-11 20:47	69.44	OK	2054	2026-09-11 20:48	71.86	OK
2055	2026-09-11 20:49	72.24	OK	2056	2026-09-11 20:50	71.23	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2057	2026-09-11 20:51	71.51	OK	2058	2026-09-11 20:52	71.51	OK
2059	2026-09-11 20:53	71.44	OK	2060	2026-09-11 20:54	70.74	OK
2061	2026-09-11 20:55	70.52	OK	2062	2026-09-11 20:56	71.24	OK
2063	2026-09-11 20:57	70.18	OK	2064	2026-09-11 20:58	73.09	OK
2065	2026-09-11 20:59	71.20	OK	2066	2026-09-11 21:00	71.87	OK
2067	2026-09-11 21:01	72.64	OK	2068	2026-09-11 21:02	70.08	OK
2069	2026-09-11 21:03	71.81	OK	2070	2026-09-11 21:04	70.64	OK
2071	2026-09-11 21:05	71.60	OK	2072	2026-09-11 21:06	71.44	OK
2073	2026-09-11 21:07	72.28	OK	2074	2026-09-11 21:08	72.20	OK
2075	2026-09-11 21:09	72.84	OK	2076	2026-09-11 21:10	71.74	OK
2077	2026-09-11 21:11	71.62	OK	2078	2026-09-11 21:12	73.57	OK
2079	2026-09-11 21:13	71.83	OK	2080	2026-09-11 21:14	74.09	OK
2081	2026-09-11 21:15	72.56	OK	2082	2026-09-11 21:16	74.67	OK
2083	2026-09-11 21:17	72.21	OK	2084	2026-09-11 21:18	73.02	OK
2085	2026-09-11 21:19	71.17	OK	2086	2026-09-11 21:20	70.85	OK
2087	2026-09-11 21:21	73.48	OK	2088	2026-09-11 21:22	74.38	OK
2089	2026-09-11 21:23	70.78	OK	2090	2026-09-11 21:24	73.70	OK
2091	2026-09-11 21:25	72.86	OK	2092	2026-09-11 21:26	72.76	OK
2093	2026-09-11 21:27	73.64	OK	2094	2026-09-11 21:28	73.80	OK
2095	2026-09-11 21:29	71.36	OK	2096	2026-09-11 21:30	71.84	OK
2097	2026-09-11 21:31	70.52	OK	2098	2026-09-11 21:32	69.98	OK
2099	2026-09-11 21:33	71.53	OK	2100	2026-09-11 21:34	72.05	OK
2101	2026-09-11 21:35	71.12	OK	2102	2026-09-11 21:36	71.93	OK
2103	2026-09-11 21:37	71.44	OK	2104	2026-09-11 21:38	71.89	OK
2105	2026-09-11 21:39	72.32	OK	2106	2026-09-11 21:40	73.24	OK
2107	2026-09-11 21:41	72.35	OK	2108	2026-09-11 21:42	72.46	OK
2109	2026-09-11 21:43	73.09	OK	2110	2026-09-11 21:44	72.43	OK
2111	2026-09-11 21:45	73.73	OK	2112	2026-09-11 21:46	71.77	OK
2113	2026-09-11 21:47	70.46	OK	2114	2026-09-11 21:48	73.60	OK
2115	2026-09-11 21:49	71.48	OK	2116	2026-09-11 21:50	71.49	OK
2117	2026-09-11 21:51	73.05	OK	2118	2026-09-11 21:52	71.62	OK
2119	2026-09-11 21:53	74.12	OK	2120	2026-09-11 21:54	70.78	OK
2121	2026-09-11 21:55	72.13	OK	2122	2026-09-11 21:56	70.50	OK
2123	2026-09-11 21:57	73.28	OK	2124	2026-09-11 21:58	70.80	OK
2125	2026-09-11 21:59	72.24	OK	2126	2026-09-11 22:00	71.31	OK
2127	2026-09-11 22:01	72.13	OK	2128	2026-09-11 22:02	73.19	OK
2129	2026-09-11 22:03	72.98	OK	2130	2026-09-11 22:04	70.15	OK
2131	2026-09-11 22:05	72.12	OK	2132	2026-09-11 22:06	72.28	OK
2133	2026-09-11 22:07	72.27	OK	2134	2026-09-11 22:08	74.23	OK
2135	2026-09-11 22:09	74.75	OK	2136	2026-09-11 22:10	70.92	OK
2137	2026-09-11 22:11	74.76	OK	2138	2026-09-11 22:12	72.09	OK
2139	2026-09-11 22:13	72.63	OK	2140	2026-09-11 22:14	74.09	OK
2141	2026-09-11 22:15	72.93	OK	2142	2026-09-11 22:16	71.70	OK
2143	2026-09-11 22:17	73.87	OK	2144	2026-09-11 22:18	71.77	OK
2145	2026-09-11 22:19	71.70	OK	2146	2026-09-11 22:20	71.95	OK
2147	2026-09-11 22:21	73.76	OK	2148	2026-09-11 22:22	70.72	OK
2149	2026-09-11 22:23	71.09	OK	2150	2026-09-11 22:24	74.88	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2151	2026-09-11 22:25	71.76	OK	2152	2026-09-11 22:26	71.70	OK
2153	2026-09-11 22:27	71.93	OK	2154	2026-09-11 22:28	72.26	OK
2155	2026-09-11 22:29	74.15	OK	2156	2026-09-11 22:30	69.71	OK
2157	2026-09-11 22:31	73.76	OK	2158	2026-09-11 22:32	72.90	OK
2159	2026-09-11 22:33	72.57	OK	2160	2026-09-11 22:34	72.13	OK
2161	2026-09-11 22:35	72.02	OK	2162	2026-09-11 22:36	74.20	OK
2163	2026-09-11 22:37	72.05	OK	2164	2026-09-11 22:38	73.35	OK
2165	2026-09-11 22:39	71.76	OK	2166	2026-09-11 22:40	73.27	OK
2167	2026-09-11 22:41	72.18	OK	2168	2026-09-11 22:42	73.78	OK
2169	2026-09-11 22:43	72.99	OK	2170	2026-09-11 22:44	74.46	OK
2171	2026-09-11 22:45	71.27	OK	2172	2026-09-11 22:46	72.45	OK
2173	2026-09-11 22:47	72.50	OK	2174	2026-09-11 22:48	72.18	OK
2175	2026-09-11 22:49	71.92	OK	2176	2026-09-11 22:50	74.56	OK
2177	2026-09-11 22:51	72.76	OK	2178	2026-09-11 22:52	74.60	OK
2179	2026-09-11 22:53	72.42	OK	2180	2026-09-11 22:54	74.43	OK
2181	2026-09-11 22:55	71.06	OK	2182	2026-09-11 22:56	73.55	OK
2183	2026-09-11 22:57	74.36	OK	2184	2026-09-11 22:58	71.19	OK
2185	2026-09-11 22:59	70.84	OK	2186	2026-09-11 23:00	71.90	OK
2187	2026-09-11 23:01	72.98	OK	2188	2026-09-11 23:02	72.97	OK
2189	2026-09-11 23:03	74.43	OK	2190	2026-09-11 23:04	74.60	OK
2191	2026-09-11 23:05	74.10	OK	2192	2026-09-11 23:06	73.04	OK
2193	2026-09-11 23:07	75.47	OK	2194	2026-09-11 23:08	74.46	OK
2195	2026-09-11 23:09	73.92	OK	2196	2026-09-11 23:10	73.95	OK
2197	2026-09-11 23:11	72.60	OK	2198	2026-09-11 23:12	74.26	OK
2199	2026-09-11 23:13	71.17	OK	2200	2026-09-11 23:14	72.46	OK
2201	2026-09-11 23:15	70.87	OK	2202	2026-09-11 23:16	74.82	OK
2203	2026-09-11 23:17	72.29	OK	2204	2026-09-11 23:18	73.73	OK
2205	2026-09-11 23:19	70.44	OK	2206	2026-09-11 23:20	71.51	OK
2207	2026-09-11 23:21	71.09	OK	2208	2026-09-11 23:22	73.74	OK
2209	2026-09-11 23:23	73.60	OK	2210	2026-09-11 23:24	70.84	OK
2211	2026-09-11 23:25	73.93	OK	2212	2026-09-11 23:26	73.13	OK
2213	2026-09-11 23:27	74.65	OK	2214	2026-09-11 23:28	74.22	OK
2215	2026-09-11 23:29	70.91	OK	2216	2026-09-11 23:30	71.55	OK
2217	2026-09-11 23:31	69.84	OK	2218	2026-09-11 23:32	74.30	OK
2219	2026-09-11 23:33	70.78	OK	2220	2026-09-11 23:34	71.39	OK
2221	2026-09-11 23:35	73.17	OK	2222	2026-09-11 23:36	72.49	OK
2223	2026-09-11 23:37	71.98	OK	2224	2026-09-11 23:38	72.10	OK
2225	2026-09-11 23:39	69.89	OK	2226	2026-09-11 23:40	73.11	OK
2227	2026-09-11 23:41	70.93	OK	2228	2026-09-11 23:42	72.32	OK
2229	2026-09-11 23:43	71.90	OK	2230	2026-09-11 23:44	69.06	OK
2231	2026-09-11 23:45	72.59	OK	2232	2026-09-11 23:46	72.05	OK
2233	2026-09-11 23:47	74.00	OK	2234	2026-09-11 23:48	74.78	OK
2235	2026-09-11 23:49	73.63	OK	2236	2026-09-11 23:50	71.35	OK
2237	2026-09-11 23:51	71.79	OK	2238	2026-09-11 23:52	74.34	OK
2239	2026-09-11 23:53	74.24	OK	2240	2026-09-11 23:54	71.63	OK
2241	2026-09-11 23:55	74.72	OK	2242	2026-09-11 23:56	74.10	OK
2243	2026-09-11 23:57	70.80	OK	2244	2026-09-11 23:58	70.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2245	2026-09-11 23:59	71.94	OK	2246	2026-09-12 00:00	71.66	OK
2247	2026-09-12 00:01	73.08	OK	2248	2026-09-12 00:02	71.91	OK
2249	2026-09-12 00:03	71.21	OK	2250	2026-09-12 00:04	72.78	OK
2251	2026-09-12 00:05	72.87	OK	2252	2026-09-12 00:06	71.26	OK
2253	2026-09-12 00:07	72.59	OK	2254	2026-09-12 00:08	72.38	OK
2255	2026-09-12 00:09	71.42	OK	2256	2026-09-12 00:10	71.32	OK
2257	2026-09-12 00:11	73.02	OK	2258	2026-09-12 00:12	73.48	OK
2259	2026-09-12 00:13	71.75	OK	2260	2026-09-12 00:14	73.73	OK
2261	2026-09-12 00:15	71.25	OK	2262	2026-09-12 00:16	72.80	OK
2263	2026-09-12 00:17	72.71	OK	2264	2026-09-12 00:18	71.82	OK
2265	2026-09-12 00:19	72.30	OK	2266	2026-09-12 00:20	73.18	OK
2267	2026-09-12 00:21	71.40	OK	2268	2026-09-12 00:22	71.67	OK
2269	2026-09-12 00:23	71.56	OK	2270	2026-09-12 00:24	71.34	OK
2271	2026-09-12 00:25	73.60	OK	2272	2026-09-12 00:26	73.45	OK
2273	2026-09-12 00:27	72.71	OK	2274	2026-09-12 00:28	72.96	OK
2275	2026-09-12 00:29	73.64	OK	2276	2026-09-12 00:30	70.50	OK
2277	2026-09-12 00:31	73.20	OK	2278	2026-09-12 00:32	72.54	OK
2279	2026-09-12 00:33	74.19	OK	2280	2026-09-12 00:34	72.04	OK
2281	2026-09-12 00:35	72.07	OK	2282	2026-09-12 00:36	70.26	OK
2283	2026-09-12 00:37	71.11	OK	2284	2026-09-12 00:38	70.58	OK
2285	2026-09-12 00:39	72.12	OK	2286	2026-09-12 00:40	72.05	OK
2287	2026-09-12 00:41	71.17	OK	2288	2026-09-12 00:42	70.70	OK
2289	2026-09-12 00:43	71.17	OK	2290	2026-09-12 00:44	73.72	OK
2291	2026-09-12 00:45	71.08	OK	2292	2026-09-12 00:46	72.45	OK
2293	2026-09-12 00:47	73.35	OK	2294	2026-09-12 00:48	72.69	OK
2295	2026-09-12 00:49	71.28	OK	2296	2026-09-12 00:50	71.16	OK
2297	2026-09-12 00:51	73.23	OK	2298	2026-09-12 00:52	70.59	OK
2299	2026-09-12 00:53	72.24	OK	2300	2026-09-12 00:54	71.40	OK
2301	2026-09-12 00:55	71.60	OK	2302	2026-09-12 00:56	73.01	OK
2303	2026-09-12 00:57	72.71	OK	2304	2026-09-12 00:58	71.87	OK
2305	2026-09-12 00:59	74.62	OK	2306	2026-09-12 01:00	71.99	OK
2307	2026-09-12 01:01	69.99	OK	2308	2026-09-12 01:02	70.83	OK
2309	2026-09-12 01:03	72.60	OK	2310	2026-09-12 01:04	71.38	OK
2311	2026-09-12 01:05	73.22	OK	2312	2026-09-12 01:06	71.49	OK
2313	2026-09-12 01:07	72.28	OK	2314	2026-09-12 01:08	70.80	OK
2315	2026-09-12 01:09	70.79	OK	2316	2026-09-12 01:10	71.30	OK
2317	2026-09-12 01:11	71.11	OK	2318	2026-09-12 01:12	69.32	OK
2319	2026-09-12 01:13	72.53	OK	2320	2026-09-12 01:14	70.53	OK
2321	2026-09-12 01:15	71.78	OK	2322	2026-09-12 01:16	72.01	OK
2323	2026-09-12 01:17	70.89	OK	2324	2026-09-12 01:18	70.35	OK
2325	2026-09-12 01:19	72.14	OK	2326	2026-09-12 01:20	71.16	OK
2327	2026-09-12 01:21	70.42	OK	2328	2026-09-12 01:22	70.38	OK
2329	2026-09-12 01:23	69.59	OK	2330	2026-09-12 01:24	73.58	OK
2331	2026-09-12 01:25	72.08	OK	2332	2026-09-12 01:26	70.54	OK
2333	2026-09-12 01:27	70.90	OK	2334	2026-09-12 01:28	71.38	OK
2335	2026-09-12 01:29	70.62	OK	2336	2026-09-12 01:30	70.97	OK
2337	2026-09-12 01:31	72.08	OK	2338	2026-09-12 01:32	71.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2339	2026-09-12 01:33	71.50	OK	2340	2026-09-12 01:34	70.85	OK
2341	2026-09-12 01:35	73.45	OK	2342	2026-09-12 01:36	69.58	OK
2343	2026-09-12 01:37	72.03	OK	2344	2026-09-12 01:38	71.06	OK
2345	2026-09-12 01:39	73.38	OK	2346	2026-09-12 01:40	72.45	OK
2347	2026-09-12 01:41	72.40	OK	2348	2026-09-12 01:42	71.55	OK
2349	2026-09-12 01:43	71.92	OK	2350	2026-09-12 01:44	70.15	OK
2351	2026-09-12 01:45	70.57	OK	2352	2026-09-12 01:46	71.96	OK
2353	2026-09-12 01:47	67.39	OK	2354	2026-09-12 01:48	70.38	OK
2355	2026-09-12 01:49	72.92	OK	2356	2026-09-12 01:50	72.06	OK
2357	2026-09-12 01:51	69.30	OK	2358	2026-09-12 01:52	71.58	OK
2359	2026-09-12 01:53	69.80	OK	2360	2026-09-12 01:54	71.17	OK
2361	2026-09-12 01:55	71.95	OK	2362	2026-09-12 01:56	71.94	OK
2363	2026-09-12 01:57	72.00	OK	2364	2026-09-12 01:58	71.15	OK
2365	2026-09-12 01:59	69.24	OK	2366	2026-09-12 02:00	69.06	OK
2367	2026-09-12 02:01	70.91	OK	2368	2026-09-12 02:02	69.56	OK
2369	2026-09-12 02:03	70.12	OK	2370	2026-09-12 02:04	71.61	OK
2371	2026-09-12 02:05	69.92	OK	2372	2026-09-12 02:06	68.25	OK
2373	2026-09-12 02:07	72.03	OK	2374	2026-09-12 02:08	69.89	OK
2375	2026-09-12 02:09	72.02	OK	2376	2026-09-12 02:10	71.72	OK
2377	2026-09-12 02:11	71.54	OK	2378	2026-09-12 02:12	69.04	OK
2379	2026-09-12 02:13	71.21	OK	2380	2026-09-12 02:14	70.08	OK
2381	2026-09-12 02:15	70.49	OK	2382	2026-09-12 02:16	68.83	OK
2383	2026-09-12 02:17	70.90	OK	2384	2026-09-12 02:18	71.19	OK
2385	2026-09-12 02:19	69.36	OK	2386	2026-09-12 02:20	70.81	OK
2387	2026-09-12 02:21	67.42	OK	2388	2026-09-12 02:22	70.64	OK
2389	2026-09-12 02:23	71.35	OK	2390	2026-09-12 02:24	69.46	OK
2391	2026-09-12 02:25	70.69	OK	2392	2026-09-12 02:26	69.94	OK
2393	2026-09-12 02:27	68.21	OK	2394	2026-09-12 02:28	70.05	OK
2395	2026-09-12 02:29	71.57	OK	2396	2026-09-12 02:30	72.29	OK
2397	2026-09-12 02:31	71.13	OK	2398	2026-09-12 02:32	71.02	OK
2399	2026-09-12 02:33	70.45	OK	2400	2026-09-12 02:34	67.97	OK
2401	2026-09-12 02:35	71.54	OK	2402	2026-09-12 02:36	68.75	OK
2403	2026-09-12 02:37	69.54	OK	2404	2026-09-12 02:38	69.76	OK
2405	2026-09-12 02:39	69.33	OK	2406	2026-09-12 02:40	69.53	OK
2407	2026-09-12 02:41	70.06	OK	2408	2026-09-12 02:42	70.21	OK
2409	2026-09-12 02:43	71.75	OK	2410	2026-09-12 02:44	67.79	OK
2411	2026-09-12 02:45	69.55	OK	2412	2026-09-12 02:46	67.41	OK
2413	2026-09-12 02:47	72.20	OK	2414	2026-09-12 02:48	68.68	OK
2415	2026-09-12 02:49	70.38	OK	2416	2026-09-12 02:50	70.00	OK
2417	2026-09-12 02:51	70.53	OK	2418	2026-09-12 02:52	67.24	OK
2419	2026-09-12 02:53	68.51	OK	2420	2026-09-12 02:54	70.10	OK
2421	2026-09-12 02:55	66.30	OK	2422	2026-09-12 02:56	70.45	OK
2423	2026-09-12 02:57	70.22	OK	2424	2026-09-12 02:58	69.82	OK
2425	2026-09-12 02:59	70.75	OK	2426	2026-09-12 03:00	68.11	OK
2427	2026-09-12 03:01	68.53	OK	2428	2026-09-12 03:02	69.75	OK
2429	2026-09-12 03:03	68.72	OK	2430	2026-09-12 03:04	66.79	OK
2431	2026-09-12 03:05	67.27	OK	2432	2026-09-12 03:06	66.22	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2433	2026-09-12 03:07	69.30	OK	2434	2026-09-12 03:08	70.21	OK
2435	2026-09-12 03:09	67.31	OK	2436	2026-09-12 03:10	72.13	OK
2437	2026-09-12 03:11	67.21	OK	2438	2026-09-12 03:12	68.99	OK
2439	2026-09-12 03:13	68.64	OK	2440	2026-09-12 03:14	67.80	OK
2441	2026-09-12 03:15	68.06	OK	2442	2026-09-12 03:16	67.96	OK
2443	2026-09-12 03:17	68.99	OK	2444	2026-09-12 03:18	68.01	OK
2445	2026-09-12 03:19	68.37	OK	2446	2026-09-12 03:20	66.69	OK
2447	2026-09-12 03:21	66.92	OK	2448	2026-09-12 03:22	68.17	OK
2449	2026-09-12 03:23	68.41	OK	2450	2026-09-12 03:24	67.22	OK
2451	2026-09-12 03:25	66.76	OK	2452	2026-09-12 03:26	69.20	OK
2453	2026-09-12 03:27	67.05	OK	2454	2026-09-12 03:28	67.84	OK
2455	2026-09-12 03:29	68.13	OK	2456	2026-09-12 03:30	67.73	OK
2457	2026-09-12 03:31	68.14	OK	2458	2026-09-12 03:32	69.06	OK
2459	2026-09-12 03:33	67.50	OK	2460	2026-09-12 03:34	67.01	OK
2461	2026-09-12 03:35	67.60	OK	2462	2026-09-12 03:36	67.97	OK
2463	2026-09-12 03:37	68.02	OK	2464	2026-09-12 03:38	69.00	OK
2465	2026-09-12 03:39	66.88	OK	2466	2026-09-12 03:40	68.77	OK
2467	2026-09-12 03:41	65.69	OK	2468	2026-09-12 03:42	68.70	OK
2469	2026-09-12 03:43	66.44	OK	2470	2026-09-12 03:44	70.12	OK
2471	2026-09-12 03:45	68.08	OK	2472	2026-09-12 03:46	67.85	OK
2473	2026-09-12 03:47	68.38	OK	2474	2026-09-12 03:48	66.16	OK
2475	2026-09-12 03:49	68.64	OK	2476	2026-09-12 03:50	66.49	OK
2477	2026-09-12 03:51	67.35	OK	2478	2026-09-12 03:52	69.48	OK
2479	2026-09-12 03:53	67.81	OK	2480	2026-09-12 03:54	66.33	OK
2481	2026-09-12 03:55	65.63	OK	2482	2026-09-12 03:56	65.96	OK
2483	2026-09-12 03:57	68.95	OK	2484	2026-09-12 03:58	65.60	OK
2485	2026-09-12 03:59	67.02	OK	2486	2026-09-12 04:00	66.76	OK
2487	2026-09-12 04:01	67.44	OK	2488	2026-09-12 04:02	65.94	OK
2489	2026-09-12 04:03	69.78	OK	2490	2026-09-12 04:04	65.77	OK
2491	2026-09-12 04:05	68.12	OK	2492	2026-09-12 04:06	65.99	OK
2493	2026-09-12 04:07	67.26	OK	2494	2026-09-12 04:08	66.83	OK
2495	2026-09-12 04:09	68.68	OK	2496	2026-09-12 04:10	67.41	OK
2497	2026-09-12 04:11	67.39	OK	2498	2026-09-12 04:12	67.66	OK
2499	2026-09-12 04:13	64.73	OK	2500	2026-09-12 04:14	65.33	OK
2501	2026-09-12 04:15	67.22	OK	2502	2026-09-12 04:16	65.77	OK
2503	2026-09-12 04:17	68.18	OK	2504	2026-09-12 04:18	68.77	OK
2505	2026-09-12 04:19	69.45	OK	2506	2026-09-12 04:20	65.54	OK
2507	2026-09-12 04:21	67.51	OK	2508	2026-09-12 04:22	65.44	OK
2509	2026-09-12 04:23	67.62	OK	2510	2026-09-12 04:24	67.13	OK
2511	2026-09-12 04:25	66.19	OK	2512	2026-09-12 04:26	65.06	OK
2513	2026-09-12 04:27	65.61	OK	2514	2026-09-12 04:28	67.47	OK
2515	2026-09-12 04:29	67.21	OK	2516	2026-09-12 04:30	64.51	OK
2517	2026-09-12 04:31	66.67	OK	2518	2026-09-12 04:32	66.23	OK
2519	2026-09-12 04:33	64.69	OK	2520	2026-09-12 04:34	67.58	OK
2521	2026-09-12 04:35	64.75	OK	2522	2026-09-12 04:36	65.84	OK
2523	2026-09-12 04:37	67.07	OK	2524	2026-09-12 04:38	66.48	OK
2525	2026-09-12 04:39	65.07	OK	2526	2026-09-12 04:40	67.73	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2527	2026-09-12 04:41	66.47	OK	2528	2026-09-12 04:42	65.79	OK
2529	2026-09-12 04:43	68.96	OK	2530	2026-09-12 04:44	66.58	OK
2531	2026-09-12 04:45	64.99	OK	2532	2026-09-12 04:46	65.37	OK
2533	2026-09-12 04:47	66.02	OK	2534	2026-09-12 04:48	67.40	OK
2535	2026-09-12 04:49	65.68	OK	2536	2026-09-12 04:50	65.86	OK
2537	2026-09-12 04:51	64.26	OK	2538	2026-09-12 04:52	66.97	OK
2539	2026-09-12 04:53	63.02	OK	2540	2026-09-12 04:54	65.72	OK
2541	2026-09-12 04:55	65.89	OK	2542	2026-09-12 04:56	66.94	OK
2543	2026-09-12 04:57	64.45	OK	2544	2026-09-12 04:58	65.99	OK
2545	2026-09-12 04:59	66.30	OK	2546	2026-09-12 05:00	65.52	OK
2547	2026-09-12 05:01	66.57	OK	2548	2026-09-12 05:02	65.46	OK
2549	2026-09-12 05:03	66.11	OK	2550	2026-09-12 05:04	66.83	OK
2551	2026-09-12 05:05	65.48	OK	2552	2026-09-12 05:06	64.51	OK
2553	2026-09-12 05:07	63.07	OK	2554	2026-09-12 05:08	65.31	OK
2555	2026-09-12 05:09	65.49	OK	2556	2026-09-12 05:10	64.35	OK
2557	2026-09-12 05:11	63.49	OK	2558	2026-09-12 05:12	62.30	OK
2559	2026-09-12 05:13	64.91	OK	2560	2026-09-12 05:14	65.23	OK
2561	2026-09-12 05:15	64.72	OK	2562	2026-09-12 05:16	67.64	OK
2563	2026-09-12 05:17	64.95	OK	2564	2026-09-12 05:18	65.61	OK
2565	2026-09-12 05:19	63.08	OK	2566	2026-09-12 05:20	64.62	OK
2567	2026-09-12 05:21	66.42	OK	2568	2026-09-12 05:22	63.40	OK
2569	2026-09-12 05:23	63.09	OK	2570	2026-09-12 05:24	64.13	OK
2571	2026-09-12 05:25	67.73	OK	2572	2026-09-12 05:26	65.50	OK
2573	2026-09-12 05:27	62.13	OK	2574	2026-09-12 05:28	63.81	OK
2575	2026-09-12 05:29	63.35	OK	2576	2026-09-12 05:30	62.48	OK
2577	2026-09-12 05:31	66.08	OK	2578	2026-09-12 05:32	63.60	OK
2579	2026-09-12 05:33	63.47	OK	2580	2026-09-12 05:34	65.73	OK
2581	2026-09-12 05:35	63.87	OK	2582	2026-09-12 05:36	64.54	OK
2583	2026-09-12 05:37	63.91	OK	2584	2026-09-12 05:38	63.69	OK
2585	2026-09-12 05:39	63.05	OK	2586	2026-09-12 05:40	65.76	OK
2587	2026-09-12 05:41	63.42	OK	2588	2026-09-12 05:42	63.74	OK
2589	2026-09-12 05:43	66.37	OK	2590	2026-09-12 05:44	65.40	OK
2591	2026-09-12 05:45	65.43	OK	2592	2026-09-12 05:46	62.98	OK
2593	2026-09-12 05:47	63.53	OK	2594	2026-09-12 05:48	65.41	OK
2595	2026-09-12 05:49	64.47	OK	2596	2026-09-12 05:50	63.88	OK
2597	2026-09-12 05:51	65.03	OK	2598	2026-09-12 05:52	64.36	OK
2599	2026-09-12 05:53	62.25	OK	2600	2026-09-12 05:54	62.90	OK
2601	2026-09-12 05:55	63.42	OK	2602	2026-09-12 05:56	63.77	OK
2603	2026-09-12 05:57	63.93	OK	2604	2026-09-12 05:58	62.55	OK
2605	2026-09-12 05:59	65.82	OK	2606	2026-09-12 06:00	64.53	OK
2607	2026-09-12 06:01	61.78	OK	2608	2026-09-12 06:02	64.30	OK
2609	2026-09-12 06:03	63.21	OK	2610	2026-09-12 06:04	65.28	OK
2611	2026-09-12 06:05	62.45	OK	2612	2026-09-12 06:06	62.64	OK
2613	2026-09-12 06:07	61.70	OK	2614	2026-09-12 06:08	61.72	OK
2615	2026-09-12 06:09	64.37	OK	2616	2026-09-12 06:10	62.59	OK
2617	2026-09-12 06:11	62.52	OK	2618	2026-09-12 06:12	65.11	OK
2619	2026-09-12 06:13	64.62	OK	2620	2026-09-12 06:14	63.88	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2621	2026-09-12 06:15	62.53	OK	2622	2026-09-12 06:16	63.00	OK
2623	2026-09-12 06:17	63.32	OK	2624	2026-09-12 06:18	64.35	OK
2625	2026-09-12 06:19	61.85	OK	2626	2026-09-12 06:20	63.87	OK
2627	2026-09-12 06:21	60.93	OK	2628	2026-09-12 06:22	63.98	OK
2629	2026-09-12 06:23	60.89	OK	2630	2026-09-12 06:24	62.32	OK
2631	2026-09-12 06:25	65.22	OK	2632	2026-09-12 06:26	60.81	OK
2633	2026-09-12 06:27	65.57	OK	2634	2026-09-12 06:28	61.75	OK
2635	2026-09-12 06:29	62.09	OK	2636	2026-09-12 06:30	60.95	OK
2637	2026-09-12 06:31	63.27	OK	2638	2026-09-12 06:32	61.50	OK
2639	2026-09-12 06:33	63.74	OK	2640	2026-09-12 06:34	60.41	OK
2641	2026-09-12 06:35	59.78	OK	2642	2026-09-12 06:36	62.43	OK
2643	2026-09-12 06:37	63.59	OK	2644	2026-09-12 06:38	63.07	OK
2645	2026-09-12 06:39	62.26	OK	2646	2026-09-12 06:40	62.60	OK
2647	2026-09-12 06:41	61.71	OK	2648	2026-09-12 06:42	63.95	OK
2649	2026-09-12 06:43	61.62	OK	2650	2026-09-12 06:44	61.69	OK
2651	2026-09-12 06:45	63.50	OK	2652	2026-09-12 06:46	63.85	OK
2653	2026-09-12 06:47	62.11	OK	2654	2026-09-12 06:48	63.61	OK
2655	2026-09-12 06:49	63.77	OK	2656	2026-09-12 06:50	60.71	OK
2657	2026-09-12 06:51	65.24	OK	2658	2026-09-12 06:52	64.26	OK
2659	2026-09-12 06:53	62.74	OK	2660	2026-09-12 06:54	61.59	OK
2661	2026-09-12 06:55	63.66	OK	2662	2026-09-12 06:56	63.70	OK
2663	2026-09-12 06:57	62.61	OK	2664	2026-09-12 06:58	63.23	OK
2665	2026-09-12 06:59	63.95	OK	2666	2026-09-12 07:00	64.74	OK
2667	2026-09-12 07:01	62.00	OK	2668	2026-09-12 07:02	64.37	OK
2669	2026-09-12 07:03	62.98	OK	2670	2026-09-12 07:04	60.44	OK
2671	2026-09-12 07:05	63.58	OK	2672	2026-09-12 07:06	61.15	OK
2673	2026-09-12 07:07	62.73	OK	2674	2026-09-12 07:08	61.48	OK
2675	2026-09-12 07:09	61.09	OK	2676	2026-09-12 07:10	62.94	OK
2677	2026-09-12 07:11	62.71	OK	2678	2026-09-12 07:12	61.91	OK
2679	2026-09-12 07:13	63.57	OK	2680	2026-09-12 07:14	61.32	OK
2681	2026-09-12 07:15	63.54	OK	2682	2026-09-12 07:16	62.43	OK
2683	2026-09-12 07:17	61.84	OK	2684	2026-09-12 07:18	62.90	OK
2685	2026-09-12 07:19	64.21	OK	2686	2026-09-12 07:20	61.75	OK
2687	2026-09-12 07:21	59.93	OK	2688	2026-09-12 07:22	63.32	OK
2689	2026-09-12 07:23	63.68	OK	2690	2026-09-12 07:24	62.79	OK
2691	2026-09-12 07:25	60.85	OK	2692	2026-09-12 07:26	62.96	OK
2693	2026-09-12 07:27	63.65	OK	2694	2026-09-12 07:28	61.82	OK
2695	2026-09-12 07:29	60.39	OK	2696	2026-09-12 07:30	63.13	OK
2697	2026-09-12 07:31	63.72	OK	2698	2026-09-12 07:32	61.20	OK
2699	2026-09-12 07:33	62.68	OK	2700	2026-09-12 07:34	62.24	OK
2701	2026-09-12 07:35	61.98	OK	2702	2026-09-12 07:36	60.06	OK
2703	2026-09-12 07:37	60.76	OK	2704	2026-09-12 07:38	61.72	OK
2705	2026-09-12 07:39	60.39	OK	2706	2026-09-12 07:40	61.46	OK
2707	2026-09-12 07:41	61.60	OK	2708	2026-09-12 07:42	63.22	OK
2709	2026-09-12 07:43	60.50	OK	2710	2026-09-12 07:44	62.06	OK
2711	2026-09-12 07:45	62.05	OK	2712	2026-09-12 07:46	61.31	OK
2713	2026-09-12 07:47	61.34	OK	2714	2026-09-12 07:48	59.71	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2715	2026-09-12 07:49	62.15	OK	2716	2026-09-12 07:50	62.06	OK
2717	2026-09-12 07:51	58.46	OK	2718	2026-09-12 07:52	59.30	OK
2719	2026-09-12 07:53	59.57	OK	2720	2026-09-12 07:54	60.71	OK
2721	2026-09-12 07:55	61.83	OK	2722	2026-09-12 07:56	62.01	OK
2723	2026-09-12 07:57	63.18	OK	2724	2026-09-12 07:58	63.46	OK
2725	2026-09-12 07:59	60.92	OK	2726	2026-09-12 08:00	58.50	OK
2727	2026-09-12 08:01	61.80	OK	2728	2026-09-12 08:02	61.58	OK
2729	2026-09-12 08:03	62.37	OK	2730	2026-09-12 08:04	62.31	OK
2731	2026-09-12 08:05	61.51	OK	2732	2026-09-12 08:06	60.49	OK
2733	2026-09-12 08:07	62.41	OK	2734	2026-09-12 08:08	59.62	OK
2735	2026-09-12 08:09	62.19	OK	2736	2026-09-12 08:10	58.98	OK
2737	2026-09-12 08:11	60.04	OK	2738	2026-09-12 08:12	63.31	OK
2739	2026-09-12 08:13	60.90	OK	2740	2026-09-12 08:14	60.36	OK
2741	2026-09-12 08:15	61.70	OK	2742	2026-09-12 08:16	61.95	OK
2743	2026-09-12 08:17	59.08	OK	2744	2026-09-12 08:18	59.82	OK
2745	2026-09-12 08:19	58.60	OK	2746	2026-09-12 08:20	61.07	OK
2747	2026-09-12 08:21	62.08	OK	2748	2026-09-12 08:22	59.04	OK
2749	2026-09-12 08:23	60.89	OK	2750	2026-09-12 08:24	60.69	OK
2751	2026-09-12 08:25	59.52	OK	2752	2026-09-12 08:26	62.11	OK
2753	2026-09-12 08:27	61.42	OK	2754	2026-09-12 08:28	60.93	OK
2755	2026-09-12 08:29	60.11	OK	2756	2026-09-12 08:30	60.59	OK
2757	2026-09-12 08:31	59.16	OK	2758	2026-09-12 08:32	60.06	OK
2759	2026-09-12 08:33	58.54	OK	2760	2026-09-12 08:34	58.11	OK
2761	2026-09-12 08:35	61.16	OK	2762	2026-09-12 08:36	59.59	OK
2763	2026-09-12 08:37	61.10	OK	2764	2026-09-12 08:38	62.12	OK
2765	2026-09-12 08:39	61.15	OK	2766	2026-09-12 08:40	59.51	OK
2767	2026-09-12 08:41	59.44	OK	2768	2026-09-12 08:42	59.56	OK
2769	2026-09-12 08:43	59.90	OK	2770	2026-09-12 08:44	60.09	OK
2771	2026-09-12 08:45	61.39	OK	2772	2026-09-12 08:46	60.26	OK
2773	2026-09-12 08:47	58.85	OK	2774	2026-09-12 08:48	61.90	OK
2775	2026-09-12 08:49	61.88	OK	2776	2026-09-12 08:50	59.78	OK
2777	2026-09-12 08:51	60.31	OK	2778	2026-09-12 08:52	61.40	OK
2779	2026-09-12 08:53	58.85	OK	2780	2026-09-12 08:54	61.35	OK
2781	2026-09-12 08:55	60.36	OK	2782	2026-09-12 08:56	62.69	OK
2783	2026-09-12 08:57	57.95	OK	2784	2026-09-12 08:58	60.05	OK
2785	2026-09-12 08:59	59.79	OK	2786	2026-09-12 09:00	60.04	OK
2787	2026-09-12 09:01	59.40	OK	2788	2026-09-12 09:02	58.29	OK
2789	2026-09-12 09:03	60.34	OK	2790	2026-09-12 09:04	60.24	OK
2791	2026-09-12 09:05	59.62	OK	2792	2026-09-12 09:06	59.69	OK
2793	2026-09-12 09:07	59.41	OK	2794	2026-09-12 09:08	59.46	OK
2795	2026-09-12 09:09	60.29	OK	2796	2026-09-12 09:10	62.15	OK
2797	2026-09-12 09:11	59.01	OK	2798	2026-09-12 09:12	61.09	OK
2799	2026-09-12 09:13	60.52	OK	2800	2026-09-12 09:14	59.30	OK
2801	2026-09-12 09:15	60.16	OK	2802	2026-09-12 09:16	62.28	OK
2803	2026-09-12 09:17	59.63	OK	2804	2026-09-12 09:18	57.09	OK
2805	2026-09-12 09:19	60.43	OK	2806	2026-09-12 09:20	59.97	OK
2807	2026-09-12 09:21	58.15	OK	2808	2026-09-12 09:22	62.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2809	2026-09-12 09:23	59.55	OK	2810	2026-09-12 09:24	59.39	OK
2811	2026-09-12 09:25	62.12	OK	2812	2026-09-12 09:26	61.97	OK
2813	2026-09-12 09:27	58.41	OK	2814	2026-09-12 09:28	59.82	OK
2815	2026-09-12 09:29	61.62	OK	2816	2026-09-12 09:30	57.72	OK
2817	2026-09-12 09:31	60.41	OK	2818	2026-09-12 09:32	60.11	OK
2819	2026-09-12 09:33	60.62	OK	2820	2026-09-12 09:34	59.74	OK
2821	2026-09-12 09:35	61.15	OK	2822	2026-09-12 09:36	59.31	OK
2823	2026-09-12 09:37	59.48	OK	2824	2026-09-12 09:38	60.81	OK
2825	2026-09-12 09:39	61.29	OK	2826	2026-09-12 09:40	58.43	OK
2827	2026-09-12 09:41	58.44	OK	2828	2026-09-12 09:42	59.13	OK
2829	2026-09-12 09:43	59.92	OK	2830	2026-09-12 09:44	57.23	OK
2831	2026-09-12 09:45	59.69	OK	2832	2026-09-12 09:46	61.58	OK
2833	2026-09-12 09:47	61.73	OK	2834	2026-09-12 09:48	58.53	OK
2835	2026-09-12 09:49	59.49	OK	2836	2026-09-12 09:50	59.00	OK
2837	2026-09-12 09:51	59.97	OK	2838	2026-09-12 09:52	58.77	OK
2839	2026-09-12 09:53	58.98	OK	2840	2026-09-12 09:54	59.42	OK
2841	2026-09-12 09:55	59.67	OK	2842	2026-09-12 09:56	59.61	OK
2843	2026-09-12 09:57	60.89	OK	2844	2026-09-12 09:58	61.22	OK
2845	2026-09-12 09:59	59.95	OK	2846	2026-09-12 10:00	61.09	OK
2847	2026-09-12 10:01	58.85	OK	2848	2026-09-12 10:02	61.44	OK
2849	2026-09-12 10:03	58.83	OK	2850	2026-09-12 10:04	61.33	OK
2851	2026-09-12 10:05	58.51	OK	2852	2026-09-12 10:06	58.24	OK
2853	2026-09-12 10:07	60.04	OK	2854	2026-09-12 10:08	58.71	OK
2855	2026-09-12 10:09	60.41	OK	2856	2026-09-12 10:10	60.64	OK
2857	2026-09-12 10:11	58.20	OK	2858	2026-09-12 10:12	59.65	OK
2859	2026-09-12 10:13	59.90	OK	2860	2026-09-12 10:14	58.80	OK
2861	2026-09-12 10:15	57.81	OK	2862	2026-09-12 10:16	56.95	OK
2863	2026-09-12 10:17	60.62	OK	2864	2026-09-12 10:18	60.21	OK
2865	2026-09-12 10:19	60.58	OK	2866	2026-09-12 10:20	62.15	OK
2867	2026-09-12 10:21	57.69	OK	2868	2026-09-12 10:22	60.56	OK
2869	2026-09-12 10:23	61.64	OK	2870	2026-09-12 10:24	57.37	OK
2871	2026-09-12 10:25	58.73	OK	2872	2026-09-12 10:26	58.98	OK
2873	2026-09-12 10:27	57.62	OK	2874	2026-09-12 10:28	58.48	OK
2875	2026-09-12 10:29	60.17	OK	2876	2026-09-12 10:30	60.43	OK
2877	2026-09-12 10:31	60.01	OK	2878	2026-09-12 10:32	60.92	OK
2879	2026-09-12 10:33	61.73	OK	2880	2026-09-12 10:34	60.75	OK
2881	2026-09-12 10:35	58.61	OK	2882	2026-09-12 10:36	61.73	OK
2883	2026-09-12 10:37	58.26	OK	2884	2026-09-12 10:38	59.77	OK
2885	2026-09-12 10:39	59.77	OK	2886	2026-09-12 10:40	58.11	OK
2887	2026-09-12 10:41	61.25	OK	2888	2026-09-12 10:42	59.99	OK
2889	2026-09-12 10:43	61.39	OK	2890	2026-09-12 10:44	60.11	OK
2891	2026-09-12 10:45	60.92	OK	2892	2026-09-12 10:46	57.74	OK
2893	2026-09-12 10:47	60.26	OK	2894	2026-09-12 10:48	57.52	OK
2895	2026-09-12 10:49	59.74	OK	2896	2026-09-12 10:50	57.71	OK
2897	2026-09-12 10:51	57.17	OK	2898	2026-09-12 10:52	61.33	OK
2899	2026-09-12 10:53	59.27	OK	2900	2026-09-12 10:54	58.42	OK
2901	2026-09-12 10:55	59.25	OK	2902	2026-09-12 10:56	59.99	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2903	2026-09-12 10:57	61.42	OK	2904	2026-09-12 10:58	57.37	OK
2905	2026-09-12 10:59	59.69	OK	2906	2026-09-12 11:00	59.31	OK
2907	2026-09-12 11:01	58.42	OK	2908	2026-09-12 11:02	59.18	OK
2909	2026-09-12 11:03	59.42	OK	2910	2026-09-12 11:04	58.37	OK
2911	2026-09-12 11:05	60.82	OK	2912	2026-09-12 11:06	59.30	OK
2913	2026-09-12 11:07	59.90	OK	2914	2026-09-12 11:08	58.44	OK
2915	2026-09-12 11:09	60.51	OK	2916	2026-09-12 11:10	61.27	OK
2917	2026-09-12 11:11	59.79	OK	2918	2026-09-12 11:12	56.33	OK
2919	2026-09-12 11:13	58.68	OK	2920	2026-09-12 11:14	59.58	OK
2921	2026-09-12 11:15	60.66	OK	2922	2026-09-12 11:16	60.41	OK
2923	2026-09-12 11:17	59.24	OK	2924	2026-09-12 11:18	58.69	OK
2925	2026-09-12 11:19	59.34	OK	2926	2026-09-12 11:20	57.61	OK
2927	2026-09-12 11:21	59.90	OK	2928	2026-09-12 11:22	57.97	OK
2929	2026-09-12 11:23	61.10	OK	2930	2026-09-12 11:24	57.67	OK
2931	2026-09-12 11:25	60.39	OK	2932	2026-09-12 11:26	59.84	OK
2933	2026-09-12 11:27	59.88	OK	2934	2026-09-12 11:28	59.66	OK
2935	2026-09-12 11:29	58.72	OK	2936	2026-09-12 11:30	60.88	OK
2937	2026-09-12 11:31	58.07	OK	2938	2026-09-12 11:32	58.40	OK
2939	2026-09-12 11:33	59.85	OK	2940	2026-09-12 11:34	61.24	OK
2941	2026-09-12 11:35	60.66	OK	2942	2026-09-12 11:36	60.15	OK
2943	2026-09-12 11:37	58.05	OK	2944	2026-09-12 11:38	60.21	OK
2945	2026-09-12 11:39	59.06	OK	2946	2026-09-12 11:40	61.58	OK
2947	2026-09-12 11:41	58.67	OK	2948	2026-09-12 11:42	57.50	OK
2949	2026-09-12 11:43	58.28	OK	2950	2026-09-12 11:44	60.76	OK
2951	2026-09-12 11:45	59.41	OK	2952	2026-09-12 11:46	58.43	OK
2953	2026-09-12 11:47	59.21	OK	2954	2026-09-12 11:48	58.89	OK
2955	2026-09-12 11:49	57.76	OK	2956	2026-09-12 11:50	61.15	OK
2957	2026-09-12 11:51	59.07	OK	2958	2026-09-12 11:52	56.99	OK
2959	2026-09-12 11:53	59.41	OK	2960	2026-09-12 11:54	58.44	OK
2961	2026-09-12 11:55	58.18	OK	2962	2026-09-12 11:56	60.24	OK
2963	2026-09-12 11:57	57.10	OK	2964	2026-09-12 11:58	61.12	OK
2965	2026-09-12 11:59	59.00	OK	2966	2026-09-12 12:00	59.45	OK
2967	2026-09-12 12:01	61.01	OK	2968	2026-09-12 12:02	58.57	OK
2969	2026-09-12 12:03	59.00	OK	2970	2026-09-12 12:04	62.08	OK
2971	2026-09-12 12:05	60.12	OK	2972	2026-09-12 12:06	59.50	OK
2973	2026-09-12 12:07	60.91	OK	2974	2026-09-12 12:08	60.95	OK
2975	2026-09-12 12:09	60.40	OK	2976	2026-09-12 12:10	60.11	OK
2977	2026-09-12 12:11	60.70	OK	2978	2026-09-12 12:12	60.62	OK
2979	2026-09-12 12:13	60.46	OK	2980	2026-09-12 12:14	58.33	OK
2981	2026-09-12 12:15	58.78	OK	2982	2026-09-12 12:16	60.72	OK
2983	2026-09-12 12:17	58.56	OK	2984	2026-09-12 12:18	59.70	OK
2985	2026-09-12 12:19	59.05	OK	2986	2026-09-12 12:20	62.08	OK
2987	2026-09-12 12:21	59.87	OK	2988	2026-09-12 12:22	61.35	OK
2989	2026-09-12 12:23	59.84	OK	2990	2026-09-12 12:24	58.96	OK
2991	2026-09-12 12:25	59.70	OK	2992	2026-09-12 12:26	62.30	OK
2993	2026-09-12 12:27	58.21	OK	2994	2026-09-12 12:28	61.43	OK
2995	2026-09-12 12:29	59.27	OK	2996	2026-09-12 12:30	60.57	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2997	2026-09-12 12:31	62.94	OK	2998	2026-09-12 12:32	59.34	OK
2999	2026-09-12 12:33	61.21	OK	3000	2026-09-12 12:34	61.52	OK
3001	2026-09-12 12:35	58.93	OK	3002	2026-09-12 12:36	59.63	OK
3003	2026-09-12 12:37	60.19	OK	3004	2026-09-12 12:38	60.81	OK
3005	2026-09-12 12:39	59.32	OK	3006	2026-09-12 12:40	60.11	OK
3007	2026-09-12 12:41	59.04	OK	3008	2026-09-12 12:42	59.54	OK
3009	2026-09-12 12:43	58.28	OK	3010	2026-09-12 12:44	61.78	OK
3011	2026-09-12 12:45	57.99	OK	3012	2026-09-12 12:46	59.13	OK
3013	2026-09-12 12:47	60.86	OK	3014	2026-09-12 12:48	58.31	OK
3015	2026-09-12 12:49	59.82	OK	3016	2026-09-12 12:50	58.55	OK
3017	2026-09-12 12:51	59.84	OK	3018	2026-09-12 12:52	61.38	OK
3019	2026-09-12 12:53	60.66	OK	3020	2026-09-12 12:54	60.89	OK
3021	2026-09-12 12:55	59.50	OK	3022	2026-09-12 12:56	61.70	OK
3023	2026-09-12 12:57	61.76	OK	3024	2026-09-12 12:58	60.86	OK
3025	2026-09-12 12:59	59.93	OK	3026	2026-09-12 13:00	58.87	OK
3027	2026-09-12 13:01	59.53	OK	3028	2026-09-12 13:02	61.28	OK
3029	2026-09-12 13:03	61.90	OK	3030	2026-09-12 13:04	59.66	OK
3031	2026-09-12 13:05	59.72	OK	3032	2026-09-12 13:06	60.64	OK
3033	2026-09-12 13:07	61.48	OK	3034	2026-09-12 13:08	59.55	OK
3035	2026-09-12 13:09	61.70	OK	3036	2026-09-12 13:10	62.36	OK
3037	2026-09-12 13:11	58.65	OK	3038	2026-09-12 13:12	61.87	OK
3039	2026-09-12 13:13	61.60	OK	3040	2026-09-12 13:14	60.88	OK
3041	2026-09-12 13:15	61.92	OK	3042	2026-09-12 13:16	60.42	OK
3043	2026-09-12 13:17	59.60	OK	3044	2026-09-12 13:18	62.95	OK
3045	2026-09-12 13:19	61.35	OK	3046	2026-09-12 13:20	60.96	OK
3047	2026-09-12 13:21	63.27	OK	3048	2026-09-12 13:22	61.73	OK
3049	2026-09-12 13:23	59.80	OK	3050	2026-09-12 13:24	60.51	OK
3051	2026-09-12 13:25	61.18	OK	3052	2026-09-12 13:26	59.63	OK
3053	2026-09-12 13:27	62.97	OK	3054	2026-09-12 13:28	60.79	OK
3055	2026-09-12 13:29	61.70	OK	3056	2026-09-12 13:30	63.07	OK
3057	2026-09-12 13:31	63.18	OK	3058	2026-09-12 13:32	58.75	OK
3059	2026-09-12 13:33	62.78	OK	3060	2026-09-12 13:34	60.29	OK
3061	2026-09-12 13:35	63.12	OK	3062	2026-09-12 13:36	60.03	OK
3063	2026-09-12 13:37	60.57	OK	3064	2026-09-12 13:38	61.19	OK
3065	2026-09-12 13:39	60.93	OK	3066	2026-09-12 13:40	62.20	OK
3067	2026-09-12 13:41	61.56	OK	3068	2026-09-12 13:42	60.23	OK
3069	2026-09-12 13:43	59.97	OK	3070	2026-09-12 13:44	62.88	OK
3071	2026-09-12 13:45	60.90	OK	3072	2026-09-12 13:46	60.19	OK
3073	2026-09-12 13:47	60.47	OK	3074	2026-09-12 13:48	61.42	OK
3075	2026-09-12 13:49	60.61	OK	3076	2026-09-12 13:50	62.47	OK
3077	2026-09-12 13:51	60.85	OK	3078	2026-09-12 13:52	61.86	OK
3079	2026-09-12 13:53	60.92	OK	3080	2026-09-12 13:54	63.66	OK
3081	2026-09-12 13:55	63.64	OK	3082	2026-09-12 13:56	62.74	OK
3083	2026-09-12 13:57	63.93	OK	3084	2026-09-12 13:58	62.78	OK
3085	2026-09-12 13:59	59.81	OK	3086	2026-09-12 14:00	60.79	OK
3087	2026-09-12 14:01	62.49	OK	3088	2026-09-12 14:02	62.43	OK
3089	2026-09-12 14:03	61.35	OK	3090	2026-09-12 14:04	60.79	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3091	2026-09-12 14:05	59.69	OK	3092	2026-09-12 14:06	62.22	OK
3093	2026-09-12 14:07	61.48	OK	3094	2026-09-12 14:08	63.98	OK
3095	2026-09-12 14:09	60.83	OK	3096	2026-09-12 14:10	62.98	OK
3097	2026-09-12 14:11	60.53	OK	3098	2026-09-12 14:12	62.87	OK
3099	2026-09-12 14:13	62.35	OK	3100	2026-09-12 14:14	62.87	OK
3101	2026-09-12 14:15	63.69	OK	3102	2026-09-12 14:16	61.83	OK
3103	2026-09-12 14:17	60.38	OK	3104	2026-09-12 14:18	63.18	OK
3105	2026-09-12 14:19	60.11	OK	3106	2026-09-12 14:20	61.40	OK
3107	2026-09-12 14:21	64.12	OK	3108	2026-09-12 14:22	62.71	OK
3109	2026-09-12 14:23	62.34	OK	3110	2026-09-12 14:24	61.19	OK
3111	2026-09-12 14:25	62.43	OK	3112	2026-09-12 14:26	62.83	OK
3113	2026-09-12 14:27	62.26	OK	3114	2026-09-12 14:28	61.95	OK
3115	2026-09-12 14:29	61.83	OK	3116	2026-09-12 14:30	63.70	OK
3117	2026-09-12 14:31	62.49	OK	3118	2026-09-12 14:32	62.32	OK
3119	2026-09-12 14:33	61.86	OK	3120	2026-09-12 14:34	63.79	OK
3121	2026-09-12 14:35	63.32	OK	3122	2026-09-12 14:36	61.47	OK
3123	2026-09-12 14:37	62.64	OK	3124	2026-09-12 14:38	64.82	OK
3125	2026-09-12 14:39	63.32	OK	3126	2026-09-12 14:40	64.91	OK
3127	2026-09-12 14:41	62.60	OK	3128	2026-09-12 14:42	62.50	OK
3129	2026-09-12 14:43	61.55	OK	3130	2026-09-12 14:44	62.15	OK
3131	2026-09-12 14:45	61.55	OK	3132	2026-09-12 14:46	62.71	OK
3133	2026-09-12 14:47	62.06	OK	3134	2026-09-12 14:48	61.82	OK
3135	2026-09-12 14:49	61.60	OK	3136	2026-09-12 14:50	62.03	OK
3137	2026-09-12 14:51	63.13	OK	3138	2026-09-12 14:52	64.57	OK
3139	2026-09-12 14:53	64.55	OK	3140	2026-09-12 14:54	61.81	OK
3141	2026-09-12 14:55	62.65	OK	3142	2026-09-12 14:56	61.85	OK
3143	2026-09-12 14:57	61.96	OK	3144	2026-09-12 14:58	62.87	OK
3145	2026-09-12 14:59	62.90	OK	3146	2026-09-12 15:00	63.97	OK
3147	2026-09-12 15:01	61.46	OK	3148	2026-09-12 15:02	65.31	OK
3149	2026-09-12 15:03	63.93	OK	3150	2026-09-12 15:04	63.28	OK
3151	2026-09-12 15:05	64.29	OK	3152	2026-09-12 15:06	65.97	OK
3153	2026-09-12 15:07	63.98	OK	3154	2026-09-12 15:08	63.35	OK
3155	2026-09-12 15:09	62.62	OK	3156	2026-09-12 15:10	60.96	OK
3157	2026-09-12 15:11	65.82	OK	3158	2026-09-12 15:12	61.64	OK
3159	2026-09-12 15:13	62.54	OK	3160	2026-09-12 15:14	62.35	OK
3161	2026-09-12 15:15	62.29	OK	3162	2026-09-12 15:16	61.95	OK
3163	2026-09-12 15:17	63.77	OK	3164	2026-09-12 15:18	63.59	OK
3165	2026-09-12 15:19	63.67	OK	3166	2026-09-12 15:20	63.61	OK
3167	2026-09-12 15:21	64.61	OK	3168	2026-09-12 15:22	66.60	OK
3169	2026-09-12 15:23	65.50	OK	3170	2026-09-12 15:24	66.69	OK
3171	2026-09-12 15:25	64.66	OK	3172	2026-09-12 15:26	64.76	OK
3173	2026-09-12 15:27	64.07	OK	3174	2026-09-12 15:28	65.47	OK
3175	2026-09-12 15:29	64.49	OK	3176	2026-09-12 15:30	64.09	OK
3177	2026-09-12 15:31	63.64	OK	3178	2026-09-12 15:32	65.24	OK
3179	2026-09-12 15:33	65.59	OK	3180	2026-09-12 15:34	62.02	OK
3181	2026-09-12 15:35	63.69	OK	3182	2026-09-12 15:36	66.24	OK
3183	2026-09-12 15:37	61.87	OK	3184	2026-09-12 15:38	61.26	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3185	2026-09-12 15:39	63.98	OK	3186	2026-09-12 15:40	64.91	OK
3187	2026-09-12 15:41	64.06	OK	3188	2026-09-12 15:42	66.01	OK
3189	2026-09-12 15:43	64.18	OK	3190	2026-09-12 15:44	66.14	OK
3191	2026-09-12 15:45	64.89	OK	3192	2026-09-12 15:46	65.40	OK
3193	2026-09-12 15:47	64.52	OK	3194	2026-09-12 15:48	67.13	OK
3195	2026-09-12 15:49	63.79	OK	3196	2026-09-12 15:50	63.33	OK
3197	2026-09-12 15:51	62.76	OK	3198	2026-09-12 15:52	65.71	OK
3199	2026-09-12 15:53	66.01	OK	3200	2026-09-12 15:54	64.10	OK
3201	2026-09-12 15:55	65.02	OK	3202	2026-09-12 15:56	64.22	OK
3203	2026-09-12 15:57	66.64	OK	3204	2026-09-12 15:58	65.98	OK
3205	2026-09-12 15:59	64.03	OK	3206	2026-09-12 16:00	64.21	OK
3207	2026-09-12 16:01	63.73	OK	3208	2026-09-12 16:02	64.76	OK
3209	2026-09-12 16:03	63.55	OK	3210	2026-09-12 16:04	64.14	OK
3211	2026-09-12 16:05	62.94	OK	3212	2026-09-12 16:06	63.66	OK
3213	2026-09-12 16:07	65.29	OK	3214	2026-09-12 16:08	66.19	OK
3215	2026-09-12 16:09	66.39	OK	3216	2026-09-12 16:10	65.25	OK
3217	2026-09-12 16:11	65.91	OK	3218	2026-09-12 16:12	66.22	OK
3219	2026-09-12 16:13	65.85	OK	3220	2026-09-12 16:14	62.82	OK
3221	2026-09-12 16:15	67.11	OK	3222	2026-09-12 16:16	67.26	OK
3223	2026-09-12 16:17	65.22	OK	3224	2026-09-12 16:18	65.40	OK
3225	2026-09-12 16:19	64.86	OK	3226	2026-09-12 16:20	65.25	OK
3227	2026-09-12 16:21	65.21	OK	3228	2026-09-12 16:22	68.26	OK
3229	2026-09-12 16:23	66.60	OK	3230	2026-09-12 16:24	64.56	OK
3231	2026-09-12 16:25	66.18	OK	3232	2026-09-12 16:26	66.70	OK
3233	2026-09-12 16:27	64.10	OK	3234	2026-09-12 16:28	63.94	OK
3235	2026-09-12 16:29	66.61	OK	3236	2026-09-12 16:30	64.61	OK
3237	2026-09-12 16:31	65.10	OK	3238	2026-09-12 16:32	65.30	OK
3239	2026-09-12 16:33	66.05	OK	3240	2026-09-12 16:34	67.09	OK
3241	2026-09-12 16:35	62.99	OK	3242	2026-09-12 16:36	66.13	OK
3243	2026-09-12 16:37	66.99	OK	3244	2026-09-12 16:38	65.54	OK
3245	2026-09-12 16:39	68.33	OK	3246	2026-09-12 16:40	65.38	OK
3247	2026-09-12 16:41	67.21	OK	3248	2026-09-12 16:42	67.04	OK
3249	2026-09-12 16:43	67.52	OK	3250	2026-09-12 16:44	66.86	OK
3251	2026-09-12 16:45	64.70	OK	3252	2026-09-12 16:46	65.30	OK
3253	2026-09-12 16:47	66.04	OK	3254	2026-09-12 16:48	65.17	OK
3255	2026-09-12 16:49	65.11	OK	3256	2026-09-12 16:50	66.46	OK
3257	2026-09-12 16:51	65.59	OK	3258	2026-09-12 16:52	68.50	OK
3259	2026-09-12 16:53	66.56	OK	3260	2026-09-12 16:54	67.92	OK
3261	2026-09-12 16:55	66.32	OK	3262	2026-09-12 16:56	66.58	OK
3263	2026-09-12 16:57	66.80	OK	3264	2026-09-12 16:58	67.33	OK
3265	2026-09-12 16:59	67.29	OK	3266	2026-09-12 17:00	64.94	OK
3267	2026-09-12 17:01	66.64	OK	3268	2026-09-12 17:02	64.58	OK
3269	2026-09-12 17:03	66.58	OK	3270	2026-09-12 17:04	65.70	OK
3271	2026-09-12 17:05	67.09	OK	3272	2026-09-12 17:06	67.76	OK
3273	2026-09-12 17:07	67.23	OK	3274	2026-09-12 17:08	66.73	OK
3275	2026-09-12 17:09	65.40	OK	3276	2026-09-12 17:10	65.61	OK
3277	2026-09-12 17:11	65.69	OK	3278	2026-09-12 17:12	66.99	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3279	2026-09-12 17:13	65.92	OK	3280	2026-09-12 17:14	66.26	OK
3281	2026-09-12 17:15	67.64	OK	3282	2026-09-12 17:16	68.08	OK
3283	2026-09-12 17:17	66.64	OK	3284	2026-09-12 17:18	68.03	OK
3285	2026-09-12 17:19	67.34	OK	3286	2026-09-12 17:20	64.36	OK
3287	2026-09-12 17:21	66.94	OK	3288	2026-09-12 17:22	66.71	OK
3289	2026-09-12 17:23	66.96	OK	3290	2026-09-12 17:24	67.59	OK
3291	2026-09-12 17:25	66.88	OK	3292	2026-09-12 17:26	68.84	OK
3293	2026-09-12 17:27	66.43	OK	3294	2026-09-12 17:28	66.93	OK
3295	2026-09-12 17:29	66.68	OK	3296	2026-09-12 17:30	66.95	OK
3297	2026-09-12 17:31	65.96	OK	3298	2026-09-12 17:32	67.22	OK
3299	2026-09-12 17:33	67.45	OK	3300	2026-09-12 17:34	68.82	OK
3301	2026-09-12 17:35	67.67	OK	3302	2026-09-12 17:36	68.56	OK
3303	2026-09-12 17:37	69.66	OK	3304	2026-09-12 17:38	67.81	OK
3305	2026-09-12 17:39	69.87	OK	3306	2026-09-12 17:40	65.16	OK
3307	2026-09-12 17:41	65.50	OK	3308	2026-09-12 17:42	68.41	OK
3309	2026-09-12 17:43	68.32	OK	3310	2026-09-12 17:44	70.89	OK
3311	2026-09-12 17:45	68.54	OK	3312	2026-09-12 17:46	69.04	OK
3313	2026-09-12 17:47	67.25	OK	3314	2026-09-12 17:48	66.54	OK
3315	2026-09-12 17:49	67.38	OK	3316	2026-09-12 17:50	68.20	OK
3317	2026-09-12 17:51	69.43	OK	3318	2026-09-12 17:52	68.80	OK
3319	2026-09-12 17:53	67.97	OK	3320	2026-09-12 17:54	67.31	OK
3321	2026-09-12 17:55	66.20	OK	3322	2026-09-12 17:56	69.72	OK
3323	2026-09-12 17:57	68.16	OK	3324	2026-09-12 17:58	67.64	OK
3325	2026-09-12 17:59	67.61	OK	3326	2026-09-12 18:00	69.47	OK
3327	2026-09-12 18:01	70.91	OK	3328	2026-09-12 18:02	71.81	OK
3329	2026-09-12 18:03	70.55	OK	3330	2026-09-12 18:04	68.30	OK
3331	2026-09-12 18:05	70.24	OK	3332	2026-09-12 18:06	67.88	OK
3333	2026-09-12 18:07	68.15	OK	3334	2026-09-12 18:08	68.93	OK
3335	2026-09-12 18:09	69.55	OK	3336	2026-09-12 18:10	68.87	OK
3337	2026-09-12 18:11	70.20	OK	3338	2026-09-12 18:12	68.99	OK
3339	2026-09-12 18:13	69.20	OK	3340	2026-09-12 18:14	68.59	OK
3341	2026-09-12 18:15	65.67	OK	3342	2026-09-12 18:16	68.78	OK
3343	2026-09-12 18:17	71.43	OK	3344	2026-09-12 18:18	67.67	OK
3345	2026-09-12 18:19	66.91	OK	3346	2026-09-12 18:20	68.05	OK
3347	2026-09-12 18:21	67.65	OK	3348	2026-09-12 18:22	68.94	OK
3349	2026-09-12 18:23	68.87	OK	3350	2026-09-12 18:24	70.46	OK
3351	2026-09-12 18:25	70.72	OK	3352	2026-09-12 18:26	66.23	OK
3353	2026-09-12 18:27	67.34	OK	3354	2026-09-12 18:28	69.21	OK
3355	2026-09-12 18:29	69.12	OK	3356	2026-09-12 18:30	69.89	OK
3357	2026-09-12 18:31	69.36	OK	3358	2026-09-12 18:32	69.23	OK
3359	2026-09-12 18:33	71.69	OK	3360	2026-09-12 18:34	66.99	OK
3361	2026-09-12 18:35	67.57	OK	3362	2026-09-12 18:36	70.56	OK
3363	2026-09-12 18:37	69.25	OK	3364	2026-09-12 18:38	69.94	OK
3365	2026-09-12 18:39	70.13	OK	3366	2026-09-12 18:40	67.84	OK
3367	2026-09-12 18:41	69.97	OK	3368	2026-09-12 18:42	68.54	OK
3369	2026-09-12 18:43	68.30	OK	3370	2026-09-12 18:44	67.74	OK
3371	2026-09-12 18:45	71.45	OK	3372	2026-09-12 18:46	69.22	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3373	2026-09-12 18:47	70.10	OK	3374	2026-09-12 18:48	69.94	OK
3375	2026-09-12 18:49	71.24	OK	3376	2026-09-12 18:50	70.00	OK
3377	2026-09-12 18:51	69.60	OK	3378	2026-09-12 18:52	70.80	OK
3379	2026-09-12 18:53	70.16	OK	3380	2026-09-12 18:54	70.34	OK
3381	2026-09-12 18:55	68.25	OK	3382	2026-09-12 18:56	68.80	OK
3383	2026-09-12 18:57	70.26	OK	3384	2026-09-12 18:58	68.54	OK
3385	2026-09-12 18:59	70.42	OK	3386	2026-09-12 19:00	70.82	OK
3387	2026-09-12 19:01	71.42	OK	3388	2026-09-12 19:02	70.08	OK
3389	2026-09-12 19:03	71.19	OK	3390	2026-09-12 19:04	69.76	OK
3391	2026-09-12 19:05	70.43	OK	3392	2026-09-12 19:06	71.19	OK
3393	2026-09-12 19:07	69.64	OK	3394	2026-09-12 19:08	69.22	OK
3395	2026-09-12 19:09	67.77	OK	3396	2026-09-12 19:10	70.45	OK
3397	2026-09-12 19:11	71.46	OK	3398	2026-09-12 19:12	70.15	OK
3399	2026-09-12 19:13	71.97	OK	3400	2026-09-12 19:14	71.02	OK
3401	2026-09-12 19:15	72.20	OK	3402	2026-09-12 19:16	70.32	OK
3403	2026-09-12 19:17	69.80	OK	3404	2026-09-12 19:18	68.59	OK
3405	2026-09-12 19:19	72.81	OK	3406	2026-09-12 19:20	70.75	OK
3407	2026-09-12 19:21	72.03	OK	3408	2026-09-12 19:22	69.36	OK
3409	2026-09-12 19:23	69.88	OK	3410	2026-09-12 19:24	70.57	OK
3411	2026-09-12 19:25	70.27	OK	3412	2026-09-12 19:26	69.26	OK
3413	2026-09-12 19:27	68.78	OK	3414	2026-09-12 19:28	70.94	OK
3415	2026-09-12 19:29	70.99	OK	3416	2026-09-12 19:30	71.46	OK
3417	2026-09-12 19:31	70.33	OK	3418	2026-09-12 19:32	69.57	OK
3419	2026-09-12 19:33	69.33	OK	3420	2026-09-12 19:34	70.78	OK
3421	2026-09-12 19:35	70.33	OK	3422	2026-09-12 19:36	71.39	OK
3423	2026-09-12 19:37	70.99	OK	3424	2026-09-12 19:38	71.60	OK
3425	2026-09-12 19:39	67.59	OK	3426	2026-09-12 19:40	71.52	OK
3427	2026-09-12 19:41	69.20	OK	3428	2026-09-12 19:42	67.60	OK
3429	2026-09-12 19:43	69.80	OK	3430	2026-09-12 19:44	72.06	OK
3431	2026-09-12 19:45	69.78	OK	3432	2026-09-12 19:46	68.76	OK
3433	2026-09-12 19:47	69.65	OK	3434	2026-09-12 19:48	70.70	OK
3435	2026-09-12 19:49	72.19	OK	3436	2026-09-12 19:50	70.42	OK
3437	2026-09-12 19:51	70.66	OK	3438	2026-09-12 19:52	69.30	OK
3439	2026-09-12 19:53	71.77	OK	3440	2026-09-12 19:54	70.51	OK
3441	2026-09-12 19:55	69.25	OK	3442	2026-09-12 19:56	70.67	OK
3443	2026-09-12 19:57	70.20	OK	3444	2026-09-12 19:58	72.40	OK
3445	2026-09-12 19:59	72.63	OK	3446	2026-09-12 20:00	71.74	OK
3447	2026-09-12 20:01	72.43	OK	3448	2026-09-12 20:02	71.02	OK
3449	2026-09-12 20:03	71.31	OK	3450	2026-09-12 20:04	71.59	OK
3451	2026-09-12 20:05	71.94	OK	3452	2026-09-12 20:06	71.39	OK
3453	2026-09-12 20:07	73.37	OK	3454	2026-09-12 20:08	72.06	OK
3455	2026-09-12 20:09	72.66	OK	3456	2026-09-12 20:10	69.96	OK
3457	2026-09-12 20:11	71.26	OK	3458	2026-09-12 20:12	72.46	OK
3459	2026-09-12 20:13	71.51	OK	3460	2026-09-12 20:14	71.62	OK
3461	2026-09-12 20:15	69.70	OK	3462	2026-09-12 20:16	68.59	OK
3463	2026-09-12 20:17	73.66	OK	3464	2026-09-12 20:18	71.16	OK
3465	2026-09-12 20:19	71.74	OK	3466	2026-09-12 20:20	73.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3467	2026-09-12 20:21	69.72	OK	3468	2026-09-12 20:22	70.58	OK
3469	2026-09-12 20:23	74.28	OK	3470	2026-09-12 20:24	70.35	OK
3471	2026-09-12 20:25	72.25	OK	3472	2026-09-12 20:26	72.80	OK
3473	2026-09-12 20:27	72.55	OK	3474	2026-09-12 20:28	72.90	OK
3475	2026-09-12 20:29	70.23	OK	3476	2026-09-12 20:30	72.86	OK
3477	2026-09-12 20:31	73.46	OK	3478	2026-09-12 20:32	71.36	OK
3479	2026-09-12 20:33	72.49	OK	3480	2026-09-12 20:34	72.32	OK
3481	2026-09-12 20:35	71.81	OK	3482	2026-09-12 20:36	72.27	OK
3483	2026-09-12 20:37	72.22	OK	3484	2026-09-12 20:38	71.59	OK
3485	2026-09-12 20:39	71.48	OK	3486	2026-09-12 20:40	71.82	OK
3487	2026-09-12 20:41	72.08	OK	3488	2026-09-12 20:42	72.24	OK
3489	2026-09-12 20:43	71.65	OK	3490	2026-09-12 20:44	72.87	OK
3491	2026-09-12 20:45	71.11	OK	3492	2026-09-12 20:46	69.23	OK
3493	2026-09-12 20:47	72.08	OK	3494	2026-09-12 20:48	73.41	OK
3495	2026-09-12 20:49	72.57	OK	3496	2026-09-12 20:50	73.22	OK
3497	2026-09-12 20:51	71.91	OK	3498	2026-09-12 20:52	72.04	OK
3499	2026-09-12 20:53	73.98	OK	3500	2026-09-12 20:54	72.70	OK
3501	2026-09-12 20:55	73.65	OK	3502	2026-09-12 20:56	70.46	OK
3503	2026-09-12 20:57	72.07	OK	3504	2026-09-12 20:58	72.35	OK
3505	2026-09-12 20:59	70.01	OK	3506	2026-09-12 21:00	71.35	OK
3507	2026-09-12 21:01	69.53	OK	3508	2026-09-12 21:02	72.37	OK
3509	2026-09-12 21:03	70.97	OK	3510	2026-09-12 21:04	75.41	OK
3511	2026-09-12 21:05	72.04	OK	3512	2026-09-12 21:06	70.65	OK
3513	2026-09-12 21:07	71.44	OK	3514	2026-09-12 21:08	73.01	OK
3515	2026-09-12 21:09	73.00	OK	3516	2026-09-12 21:10	72.07	OK
3517	2026-09-12 21:11	72.52	OK	3518	2026-09-12 21:12	72.95	OK
3519	2026-09-12 21:13	71.30	OK	3520	2026-09-12 21:14	71.27	OK
3521	2026-09-12 21:15	73.33	OK	3522	2026-09-12 21:16	72.91	OK
3523	2026-09-12 21:17	71.43	OK	3524	2026-09-12 21:18	72.75	OK
3525	2026-09-12 21:19	70.95	OK	3526	2026-09-12 21:20	70.45	OK
3527	2026-09-12 21:21	72.15	OK	3528	2026-09-12 21:22	69.90	OK
3529	2026-09-12 21:23	70.88	OK	3530	2026-09-12 21:24	71.39	OK
3531	2026-09-12 21:25	73.00	OK	3532	2026-09-12 21:26	70.92	OK
3533	2026-09-12 21:27	73.27	OK	3534	2026-09-12 21:28	72.86	OK
3535	2026-09-12 21:29	73.61	OK	3536	2026-09-12 21:30	74.54	OK
3537	2026-09-12 21:31	71.80	OK	3538	2026-09-12 21:32	71.17	OK
3539	2026-09-12 21:33	71.48	OK	3540	2026-09-12 21:34	73.59	OK
3541	2026-09-12 21:35	73.11	OK	3542	2026-09-12 21:36	72.80	OK
3543	2026-09-12 21:37	72.67	OK	3544	2026-09-12 21:38	72.01	OK
3545	2026-09-12 21:39	73.84	OK	3546	2026-09-12 21:40	72.20	OK
3547	2026-09-12 21:41	73.61	OK	3548	2026-09-12 21:42	73.60	OK
3549	2026-09-12 21:43	73.66	OK	3550	2026-09-12 21:44	73.82	OK
3551	2026-09-12 21:45	73.05	OK	3552	2026-09-12 21:46	72.76	OK
3553	2026-09-12 21:47	71.11	OK	3554	2026-09-12 21:48	73.26	OK
3555	2026-09-12 21:49	73.22	OK	3556	2026-09-12 21:50	70.74	OK
3557	2026-09-12 21:51	72.04	OK	3558	2026-09-12 21:52	73.95	OK
3559	2026-09-12 21:53	72.88	OK	3560	2026-09-12 21:54	71.82	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3561	2026-09-12 21:55	72.46	OK	3562	2026-09-12 21:56	74.24	OK
3563	2026-09-12 21:57	71.60	OK	3564	2026-09-12 21:58	73.21	OK
3565	2026-09-12 21:59	73.55	OK	3566	2026-09-12 22:00	71.48	OK
3567	2026-09-12 22:01	70.58	OK	3568	2026-09-12 22:02	72.46	OK
3569	2026-09-12 22:03	72.04	OK	3570	2026-09-12 22:04	72.43	OK
3571	2026-09-12 22:05	74.70	OK	3572	2026-09-12 22:06	71.18	OK
3573	2026-09-12 22:07	72.41	OK	3574	2026-09-12 22:08	75.33	OK
3575	2026-09-12 22:09	72.29	OK	3576	2026-09-12 22:10	74.03	OK
3577	2026-09-12 22:11	71.01	OK	3578	2026-09-12 22:12	73.47	OK
3579	2026-09-12 22:13	73.01	OK	3580	2026-09-12 22:14	73.45	OK
3581	2026-09-12 22:15	74.77	OK	3582	2026-09-12 22:16	73.49	OK
3583	2026-09-12 22:17	72.36	OK	3584	2026-09-12 22:18	70.14	OK
3585	2026-09-12 22:19	74.05	OK	3586	2026-09-12 22:20	70.96	OK
3587	2026-09-12 22:21	73.88	OK	3588	2026-09-12 22:22	74.59	OK
3589	2026-09-12 22:23	74.15	OK	3590	2026-09-12 22:24	72.04	OK
3591	2026-09-12 22:25	73.75	OK	3592	2026-09-12 22:26	71.94	OK
3593	2026-09-12 22:27	73.93	OK	3594	2026-09-12 22:28	71.05	OK
3595	2026-09-12 22:29	70.83	OK	3596	2026-09-12 22:30	71.38	OK
3597	2026-09-12 22:31	72.63	OK	3598	2026-09-12 22:32	73.54	OK
3599	2026-09-12 22:33	72.46	OK	3600	2026-09-12 22:34	70.75	OK
3601	2026-09-12 22:35	70.28	OK	3602	2026-09-12 22:36	70.73	OK
3603	2026-09-12 22:37	73.04	OK	3604	2026-09-12 22:38	73.90	OK
3605	2026-09-12 22:39	74.53	OK	3606	2026-09-12 22:40	72.57	OK
3607	2026-09-12 22:41	71.93	OK	3608	2026-09-12 22:42	73.83	OK
3609	2026-09-12 22:43	70.54	OK	3610	2026-09-12 22:44	71.80	OK
3611	2026-09-12 22:45	70.92	OK	3612	2026-09-12 22:46	72.06	OK
3613	2026-09-12 22:47	71.41	OK	3614	2026-09-12 22:48	75.56	OK
3615	2026-09-12 22:49	73.82	OK	3616	2026-09-12 22:50	71.21	OK
3617	2026-09-12 22:51	73.10	OK	3618	2026-09-12 22:52	72.61	OK
3619	2026-09-12 22:53	72.37	OK	3620	2026-09-12 22:54	69.93	OK
3621	2026-09-12 22:55	70.02	OK	3622	2026-09-12 22:56	74.36	OK
3623	2026-09-12 22:57	73.48	OK	3624	2026-09-12 22:58	72.75	OK
3625	2026-09-12 22:59	69.86	OK	3626	2026-09-12 23:00	72.04	OK
3627	2026-09-12 23:01	70.74	OK	3628	2026-09-12 23:02	71.98	OK
3629	2026-09-12 23:03	73.64	OK	3630	2026-09-12 23:04	71.24	OK
3631	2026-09-12 23:05	72.42	OK	3632	2026-09-12 23:06	70.55	OK
3633	2026-09-12 23:07	72.62	OK	3634	2026-09-12 23:08	73.47	OK
3635	2026-09-12 23:09	74.01	OK	3636	2026-09-12 23:10	72.81	OK
3637	2026-09-12 23:11	72.63	OK	3638	2026-09-12 23:12	71.00	OK
3639	2026-09-12 23:13	70.93	OK	3640	2026-09-12 23:14	71.96	OK
3641	2026-09-12 23:15	74.39	OK	3642	2026-09-12 23:16	73.55	OK
3643	2026-09-12 23:17	72.70	OK	3644	2026-09-12 23:18	74.19	OK
3645	2026-09-12 23:19	73.08	OK	3646	2026-09-12 23:20	73.22	OK
3647	2026-09-12 23:21	72.92	OK	3648	2026-09-12 23:22	74.81	OK
3649	2026-09-12 23:23	71.66	OK	3650	2026-09-12 23:24	72.78	OK
3651	2026-09-12 23:25	73.21	OK	3652	2026-09-12 23:26	73.11	OK
3653	2026-09-12 23:27	71.40	OK	3654	2026-09-12 23:28	72.15	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3655	2026-09-12 23:29	72.10	OK	3656	2026-09-12 23:30	74.07	OK
3657	2026-09-12 23:31	73.76	OK	3658	2026-09-12 23:32	72.70	OK
3659	2026-09-12 23:33	72.33	OK	3660	2026-09-12 23:34	72.06	OK
3661	2026-09-12 23:35	72.83	OK	3662	2026-09-12 23:36	73.11	OK
3663	2026-09-12 23:37	72.87	OK	3664	2026-09-12 23:38	70.22	OK
3665	2026-09-12 23:39	71.88	OK	3666	2026-09-12 23:40	72.39	OK
3667	2026-09-12 23:41	74.62	OK	3668	2026-09-12 23:42	72.97	OK
3669	2026-09-12 23:43	72.42	OK	3670	2026-09-12 23:44	72.87	OK
3671	2026-09-12 23:45	72.16	OK	3672	2026-09-12 23:46	72.43	OK
3673	2026-09-12 23:47	72.53	OK	3674	2026-09-12 23:48	70.82	OK
3675	2026-09-12 23:49	70.15	OK	3676	2026-09-12 23:50	70.49	OK
3677	2026-09-12 23:51	74.70	OK	3678	2026-09-12 23:52	72.08	OK
3679	2026-09-12 23:53	72.24	OK	3680	2026-09-12 23:54	70.60	OK
3681	2026-09-12 23:55	70.41	OK	3682	2026-09-12 23:56	71.32	OK
3683	2026-09-12 23:57	71.14	OK	3684	2026-09-12 23:58	72.49	OK
3685	2026-09-12 23:59	70.52	OK	3686	2026-09-13 00:00	71.52	OK
3687	2026-09-13 00:01	72.65	OK	3688	2026-09-13 00:02	70.72	OK
3689	2026-09-13 00:03	75.06	OK	3690	2026-09-13 00:04	73.45	OK
3691	2026-09-13 00:05	71.61	OK	3692	2026-09-13 00:06	71.57	OK
3693	2026-09-13 00:07	70.61	OK	3694	2026-09-13 00:08	71.62	OK
3695	2026-09-13 00:09	70.37	OK	3696	2026-09-13 00:10	73.50	OK
3697	2026-09-13 00:11	72.24	OK	3698	2026-09-13 00:12	69.76	OK
3699	2026-09-13 00:13	75.52	OK	3700	2026-09-13 00:14	70.82	OK
3701	2026-09-13 00:15	72.93	OK	3702	2026-09-13 00:16	70.80	OK
3703	2026-09-13 00:17	73.25	OK	3704	2026-09-13 00:18	72.86	OK
3705	2026-09-13 00:19	72.66	OK	3706	2026-09-13 00:20	73.37	OK
3707	2026-09-13 00:21	73.14	OK	3708	2026-09-13 00:22	72.02	OK
3709	2026-09-13 00:23	71.62	OK	3710	2026-09-13 00:24	71.30	OK
3711	2026-09-13 00:25	72.28	OK	3712	2026-09-13 00:26	71.61	OK
3713	2026-09-13 00:27	71.29	OK	3714	2026-09-13 00:28	71.83	OK
3715	2026-09-13 00:29	70.09	OK	3716	2026-09-13 00:30	71.40	OK
3717	2026-09-13 00:31	71.24	OK	3718	2026-09-13 00:32	73.19	OK
3719	2026-09-13 00:33	72.56	OK	3720	2026-09-13 00:34	71.17	OK
3721	2026-09-13 00:35	69.29	OK	3722	2026-09-13 00:36	71.36	OK
3723	2026-09-13 00:37	71.33	OK	3724	2026-09-13 00:38	69.41	OK
3725	2026-09-13 00:39	70.49	OK	3726	2026-09-13 00:40	73.74	OK
3727	2026-09-13 00:41	72.45	OK	3728	2026-09-13 00:42	71.65	OK
3729	2026-09-13 00:43	72.19	OK	3730	2026-09-13 00:44	71.04	OK
3731	2026-09-13 00:45	71.89	OK	3732	2026-09-13 00:46	71.54	OK
3733	2026-09-13 00:47	71.42	OK	3734	2026-09-13 00:48	70.74	OK
3735	2026-09-13 00:49	70.52	OK	3736	2026-09-13 00:50	72.89	OK
3737	2026-09-13 00:51	71.81	OK	3738	2026-09-13 00:52	70.75	OK
3739	2026-09-13 00:53	71.52	OK	3740	2026-09-13 00:54	69.83	OK
3741	2026-09-13 00:55	72.63	OK	3742	2026-09-13 00:56	70.24	OK
3743	2026-09-13 00:57	72.15	OK	3744	2026-09-13 00:58	73.54	OK
3745	2026-09-13 00:59	72.53	OK	3746	2026-09-13 01:00	70.47	OK
3747	2026-09-13 01:01	70.55	OK	3748	2026-09-13 01:02	68.80	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3749	2026-09-13 01:03	72.66	OK	3750	2026-09-13 01:04	71.62	OK
3751	2026-09-13 01:05	73.35	OK	3752	2026-09-13 01:06	73.40	OK
3753	2026-09-13 01:07	71.48	OK	3754	2026-09-13 01:08	70.94	OK
3755	2026-09-13 01:09	71.26	OK	3756	2026-09-13 01:10	71.29	OK
3757	2026-09-13 01:11	72.09	OK	3758	2026-09-13 01:12	72.36	OK
3759	2026-09-13 01:13	69.48	OK	3760	2026-09-13 01:14	70.04	OK
3761	2026-09-13 01:15	71.16	OK	3762	2026-09-13 01:16	72.77	OK
3763	2026-09-13 01:17	68.59	OK	3764	2026-09-13 01:18	70.30	OK
3765	2026-09-13 01:19	71.08	OK	3766	2026-09-13 01:20	69.84	OK
3767	2026-09-13 01:21	68.53	OK	3768	2026-09-13 01:22	71.29	OK
3769	2026-09-13 01:23	70.17	OK	3770	2026-09-13 01:24	69.76	OK
3771	2026-09-13 01:25	72.28	OK	3772	2026-09-13 01:26	71.27	OK
3773	2026-09-13 01:27	72.53	OK	3774	2026-09-13 01:28	70.88	OK
3775	2026-09-13 01:29	71.23	OK	3776	2026-09-13 01:30	71.07	OK
3777	2026-09-13 01:31	69.23	OK	3778	2026-09-13 01:32	70.60	OK
3779	2026-09-13 01:33	72.17	OK	3780	2026-09-13 01:34	70.47	OK
3781	2026-09-13 01:35	70.27	OK	3782	2026-09-13 01:36	69.86	OK
3783	2026-09-13 01:37	70.66	OK	3784	2026-09-13 01:38	70.59	OK
3785	2026-09-13 01:39	69.57	OK	3786	2026-09-13 01:40	70.91	OK
3787	2026-09-13 01:41	68.19	OK	3788	2026-09-13 01:42	68.40	OK
3789	2026-09-13 01:43	70.18	OK	3790	2026-09-13 01:44	68.10	OK
3791	2026-09-13 01:45	71.94	OK	3792	2026-09-13 01:46	71.76	OK
3793	2026-09-13 01:47	70.09	OK	3794	2026-09-13 01:48	69.53	OK
3795	2026-09-13 01:49	70.51	OK	3796	2026-09-13 01:50	69.09	OK
3797	2026-09-13 01:51	70.73	OK	3798	2026-09-13 01:52	71.27	OK
3799	2026-09-13 01:53	70.69	OK	3800	2026-09-13 01:54	70.43	OK
3801	2026-09-13 01:55	68.75	OK	3802	2026-09-13 01:56	69.42	OK
3803	2026-09-13 01:57	70.47	OK	3804	2026-09-13 01:58	68.35	OK
3805	2026-09-13 01:59	71.02	OK	3806	2026-09-13 02:00	71.66	OK
3807	2026-09-13 02:01	71.07	OK	3808	2026-09-13 02:02	71.00	OK
3809	2026-09-13 02:03	71.27	OK	3810	2026-09-13 02:04	68.41	OK
3811	2026-09-13 02:05	70.65	OK	3812	2026-09-13 02:06	70.85	OK
3813	2026-09-13 02:07	71.30	OK	3814	2026-09-13 02:08	69.45	OK
3815	2026-09-13 02:09	70.96	OK	3816	2026-09-13 02:10	70.05	OK
3817	2026-09-13 02:11	71.48	OK	3818	2026-09-13 02:12	70.78	OK
3819	2026-09-13 02:13	70.49	OK	3820	2026-09-13 02:14	70.11	OK
3821	2026-09-13 02:15	70.50	OK	3822	2026-09-13 02:16	69.44	OK
3823	2026-09-13 02:17	71.71	OK	3824	2026-09-13 02:18	69.53	OK
3825	2026-09-13 02:19	67.68	OK	3826	2026-09-13 02:20	71.22	OK
3827	2026-09-13 02:21	71.44	OK	3828	2026-09-13 02:22	70.63	OK
3829	2026-09-13 02:23	70.07	OK	3830	2026-09-13 02:24	70.22	OK
3831	2026-09-13 02:25	71.00	OK	3832	2026-09-13 02:26	67.27	OK
3833	2026-09-13 02:27	68.98	OK	3834	2026-09-13 02:28	68.91	OK
3835	2026-09-13 02:29	68.48	OK	3836	2026-09-13 02:30	69.98	OK
3837	2026-09-13 02:31	70.12	OK	3838	2026-09-13 02:32	70.66	OK
3839	2026-09-13 02:33	67.05	OK	3840	2026-09-13 02:34	71.06	OK
3841	2026-09-13 02:35	69.24	OK	3842	2026-09-13 02:36	68.93	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3843	2026-09-13 02:37	69.41	OK	3844	2026-09-13 02:38	68.08	OK
3845	2026-09-13 02:39	70.06	OK	3846	2026-09-13 02:40	70.72	OK
3847	2026-09-13 02:41	69.39	OK	3848	2026-09-13 02:42	69.64	OK
3849	2026-09-13 02:43	66.74	OK	3850	2026-09-13 02:44	69.84	OK
3851	2026-09-13 02:45	70.64	OK	3852	2026-09-13 02:46	70.25	OK
3853	2026-09-13 02:47	67.00	OK	3854	2026-09-13 02:48	69.63	OK
3855	2026-09-13 02:49	69.55	OK	3856	2026-09-13 02:50	67.25	OK
3857	2026-09-13 02:51	65.86	OK	3858	2026-09-13 02:52	69.18	OK
3859	2026-09-13 02:53	67.92	OK	3860	2026-09-13 02:54	69.13	OK
3861	2026-09-13 02:55	66.57	OK	3862	2026-09-13 02:56	68.91	OK
3863	2026-09-13 02:57	70.48	OK	3864	2026-09-13 02:58	67.57	OK
3865	2026-09-13 02:59	67.94	OK	3866	2026-09-13 03:00	67.39	OK
3867	2026-09-13 03:01	67.85	OK	3868	2026-09-13 03:02	70.05	OK
3869	2026-09-13 03:03	69.46	OK	3870	2026-09-13 03:04	71.14	OK
3871	2026-09-13 03:05	69.32	OK	3872	2026-09-13 03:06	68.16	OK
3873	2026-09-13 03:07	67.31	OK	3874	2026-09-13 03:08	68.89	OK
3875	2026-09-13 03:09	69.09	OK	3876	2026-09-13 03:10	68.06	OK
3877	2026-09-13 03:11	68.09	OK	3878	2026-09-13 03:12	69.48	OK
3879	2026-09-13 03:13	68.51	OK	3880	2026-09-13 03:14	68.63	OK
3881	2026-09-13 03:15	68.04	OK	3882	2026-09-13 03:16	66.86	OK
3883	2026-09-13 03:17	68.25	OK	3884	2026-09-13 03:18	68.38	OK
3885	2026-09-13 03:19	69.43	OK	3886	2026-09-13 03:20	68.24	OK
3887	2026-09-13 03:21	67.19	OK	3888	2026-09-13 03:22	68.38	OK
3889	2026-09-13 03:23	66.29	OK	3890	2026-09-13 03:24	67.59	OK
3891	2026-09-13 03:25	69.51	OK	3892	2026-09-13 03:26	69.04	OK
3893	2026-09-13 03:27	68.53	OK	3894	2026-09-13 03:28	71.17	OK
3895	2026-09-13 03:29	68.49	OK	3896	2026-09-13 03:30	69.33	OK
3897	2026-09-13 03:31	69.03	OK	3898	2026-09-13 03:32	69.51	OK
3899	2026-09-13 03:33	69.17	OK	3900	2026-09-13 03:34	67.61	OK
3901	2026-09-13 03:35	66.55	OK	3902	2026-09-13 03:36	68.80	OK
3903	2026-09-13 03:37	70.04	OK	3904	2026-09-13 03:38	67.16	OK
3905	2026-09-13 03:39	68.05	OK	3906	2026-09-13 03:40	68.93	OK
3907	2026-09-13 03:41	69.06	OK	3908	2026-09-13 03:42	69.01	OK
3909	2026-09-13 03:43	67.48	OK	3910	2026-09-13 03:44	68.21	OK
3911	2026-09-13 03:45	64.47	OK	3912	2026-09-13 03:46	69.17	OK
3913	2026-09-13 03:47	67.12	OK	3914	2026-09-13 03:48	67.90	OK
3915	2026-09-13 03:49	67.87	OK	3916	2026-09-13 03:50	66.63	OK
3917	2026-09-13 03:51	69.53	OK	3918	2026-09-13 03:52	66.73	OK
3919	2026-09-13 03:53	67.97	OK	3920	2026-09-13 03:54	66.08	OK
3921	2026-09-13 03:55	66.00	OK	3922	2026-09-13 03:56	68.49	OK
3923	2026-09-13 03:57	69.12	OK	3924	2026-09-13 03:58	67.67	OK
3925	2026-09-13 03:59	67.89	OK	3926	2026-09-13 04:00	68.10	OK
3927	2026-09-13 04:01	68.29	OK	3928	2026-09-13 04:02	68.82	OK
3929	2026-09-13 04:03	67.38	OK	3930	2026-09-13 04:04	70.11	OK
3931	2026-09-13 04:05	66.69	OK	3932	2026-09-13 04:06	66.86	OK
3933	2026-09-13 04:07	67.28	OK	3934	2026-09-13 04:08	65.32	OK
3935	2026-09-13 04:09	66.64	OK	3936	2026-09-13 04:10	65.91	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3937	2026-09-13 04:11	65.33	OK	3938	2026-09-13 04:12	66.40	OK
3939	2026-09-13 04:13	65.77	OK	3940	2026-09-13 04:14	68.14	OK
3941	2026-09-13 04:15	68.00	OK	3942	2026-09-13 04:16	67.94	OK
3943	2026-09-13 04:17	64.33	OK	3944	2026-09-13 04:18	65.44	OK
3945	2026-09-13 04:19	67.72	OK	3946	2026-09-13 04:20	68.38	OK
3947	2026-09-13 04:21	66.75	OK	3948	2026-09-13 04:22	66.16	OK
3949	2026-09-13 04:23	66.08	OK	3950	2026-09-13 04:24	67.25	OK
3951	2026-09-13 04:25	67.30	OK	3952	2026-09-13 04:26	66.78	OK
3953	2026-09-13 04:27	67.07	OK	3954	2026-09-13 04:28	66.61	OK
3955	2026-09-13 04:29	67.99	OK	3956	2026-09-13 04:30	66.78	OK
3957	2026-09-13 04:31	65.57	OK	3958	2026-09-13 04:32	66.36	OK
3959	2026-09-13 04:33	66.57	OK	3960	2026-09-13 04:34	68.29	OK
3961	2026-09-13 04:35	68.30	OK	3962	2026-09-13 04:36	66.65	OK
3963	2026-09-13 04:37	67.51	OK	3964	2026-09-13 04:38	67.86	OK
3965	2026-09-13 04:39	66.20	OK	3966	2026-09-13 04:40	64.09	OK
3967	2026-09-13 04:41	67.44	OK	3968	2026-09-13 04:42	68.25	OK
3969	2026-09-13 04:43	66.10	OK	3970	2026-09-13 04:44	66.11	OK
3971	2026-09-13 04:45	67.21	OK	3972	2026-09-13 04:46	64.66	OK
3973	2026-09-13 04:47	64.53	OK	3974	2026-09-13 04:48	67.50	OK
3975	2026-09-13 04:49	66.01	OK	3976	2026-09-13 04:50	66.53	OK
3977	2026-09-13 04:51	63.51	OK	3978	2026-09-13 04:52	64.49	OK
3979	2026-09-13 04:53	64.49	OK	3980	2026-09-13 04:54	64.60	OK
3981	2026-09-13 04:55	67.74	OK	3982	2026-09-13 04:56	67.51	OK
3983	2026-09-13 04:57	64.94	OK	3984	2026-09-13 04:58	66.05	OK
3985	2026-09-13 04:59	65.86	OK	3986	2026-09-13 05:00	64.49	OK
3987	2026-09-13 05:01	65.13	OK	3988	2026-09-13 05:02	65.76	OK
3989	2026-09-13 05:03	64.51	OK	3990	2026-09-13 05:04	63.51	OK
3991	2026-09-13 05:05	66.10	OK	3992	2026-09-13 05:06	66.70	OK
3993	2026-09-13 05:07	66.53	OK	3994	2026-09-13 05:08	66.44	OK
3995	2026-09-13 05:09	67.50	OK	3996	2026-09-13 05:10	64.57	OK
3997	2026-09-13 05:11	65.28	OK	3998	2026-09-13 05:12	66.72	OK
3999	2026-09-13 05:13	66.25	OK	4000	2026-09-13 05:14	63.73	OK
4001	2026-09-13 05:15	66.31	OK	4002	2026-09-13 05:16	66.83	OK
4003	2026-09-13 05:17	67.53	OK	4004	2026-09-13 05:18	64.32	OK
4005	2026-09-13 05:19	64.22	OK	4006	2026-09-13 05:20	64.90	OK
4007	2026-09-13 05:21	66.00	OK	4008	2026-09-13 05:22	65.16	OK
4009	2026-09-13 05:23	64.93	OK	4010	2026-09-13 05:24	63.91	OK
4011	2026-09-13 05:25	68.03	OK	4012	2026-09-13 05:26	64.42	OK
4013	2026-09-13 05:27	66.86	OK	4014	2026-09-13 05:28	65.09	OK
4015	2026-09-13 05:29	65.04	OK	4016	2026-09-13 05:30	63.70	OK
4017	2026-09-13 05:31	62.98	OK	4018	2026-09-13 05:32	64.52	OK
4019	2026-09-13 05:33	62.36	OK	4020	2026-09-13 05:34	65.73	OK
4021	2026-09-13 05:35	64.42	OK	4022	2026-09-13 05:36	63.81	OK
4023	2026-09-13 05:37	65.42	OK	4024	2026-09-13 05:38	62.30	OK
4025	2026-09-13 05:39	64.56	OK	4026	2026-09-13 05:40	64.06	OK
4027	2026-09-13 05:41	64.61	OK	4028	2026-09-13 05:42	65.31	OK
4029	2026-09-13 05:43	63.08	OK	4030	2026-09-13 05:44	64.01	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4031	2026-09-13 05:45	63.79	OK	4032	2026-09-13 05:46	65.56	OK
4033	2026-09-13 05:47	63.09	OK	4034	2026-09-13 05:48	63.75	OK
4035	2026-09-13 05:49	66.33	OK	4036	2026-09-13 05:50	63.17	OK
4037	2026-09-13 05:51	63.84	OK	4038	2026-09-13 05:52	64.88	OK
4039	2026-09-13 05:53	63.45	OK	4040	2026-09-13 05:54	63.50	OK
4041	2026-09-13 05:55	65.57	OK	4042	2026-09-13 05:56	62.69	OK
4043	2026-09-13 05:57	64.05	OK	4044	2026-09-13 05:58	63.45	OK
4045	2026-09-13 05:59	63.64	OK	4046	2026-09-13 06:00	65.92	OK
4047	2026-09-13 06:01	63.39	OK	4048	2026-09-13 06:02	63.34	OK
4049	2026-09-13 06:03	63.47	OK	4050	2026-09-13 06:04	62.85	OK
4051	2026-09-13 06:05	62.67	OK	4052	2026-09-13 06:06	62.42	OK
4053	2026-09-13 06:07	62.66	OK	4054	2026-09-13 06:08	61.75	OK
4055	2026-09-13 06:09	62.94	OK	4056	2026-09-13 06:10	63.63	OK
4057	2026-09-13 06:11	62.48	OK	4058	2026-09-13 06:12	63.81	OK
4059	2026-09-13 06:13	61.87	OK	4060	2026-09-13 06:14	65.63	OK
4061	2026-09-13 06:15	62.94	OK	4062	2026-09-13 06:16	64.57	OK
4063	2026-09-13 06:17	65.63	OK	4064	2026-09-13 06:18	63.09	OK
4065	2026-09-13 06:19	64.21	OK	4066	2026-09-13 06:20	61.41	OK
4067	2026-09-13 06:21	64.56	OK	4068	2026-09-13 06:22	64.05	OK
4069	2026-09-13 06:23	63.65	OK	4070	2026-09-13 06:24	64.88	OK
4071	2026-09-13 06:25	63.50	OK	4072	2026-09-13 06:26	63.55	OK
4073	2026-09-13 06:27	62.07	OK	4074	2026-09-13 06:28	63.90	OK
4075	2026-09-13 06:29	65.14	OK	4076	2026-09-13 06:30	64.03	OK
4077	2026-09-13 06:31	63.74	OK	4078	2026-09-13 06:32	62.81	OK
4079	2026-09-13 06:33	62.16	OK	4080	2026-09-13 06:34	62.15	OK
4081	2026-09-13 06:35	63.27	OK	4082	2026-09-13 06:36	64.78	OK
4083	2026-09-13 06:37	63.34	OK	4084	2026-09-13 06:38	64.62	OK
4085	2026-09-13 06:39	61.55	OK	4086	2026-09-13 06:40	62.18	OK
4087	2026-09-13 06:41	60.53	OK	4088	2026-09-13 06:42	61.19	OK
4089	2026-09-13 06:43	61.95	OK	4090	2026-09-13 06:44	63.68	OK
4091	2026-09-13 06:45	62.26	OK	4092	2026-09-13 06:46	62.45	OK
4093	2026-09-13 06:47	61.22	OK	4094	2026-09-13 06:48	60.75	OK
4095	2026-09-13 06:49	61.37	OK	4096	2026-09-13 06:50	61.91	OK
4097	2026-09-13 06:51	65.01	OK	4098	2026-09-13 06:52	63.35	OK
4099	2026-09-13 06:53	62.52	OK	4100	2026-09-13 06:54	62.31	OK
4101	2026-09-13 06:55	62.57	OK	4102	2026-09-13 06:56	61.39	OK
4103	2026-09-13 06:57	64.93	OK	4104	2026-09-13 06:58	64.69	OK
4105	2026-09-13 06:59	63.70	OK	4106	2026-09-13 07:00	62.73	OK
4107	2026-09-13 07:01	63.01	OK	4108	2026-09-13 07:02	62.72	OK
4109	2026-09-13 07:03	62.60	OK	4110	2026-09-13 07:04	59.24	OK
4111	2026-09-13 07:05	62.35	OK	4112	2026-09-13 07:06	62.90	OK
4113	2026-09-13 07:07	62.12	OK	4114	2026-09-13 07:08	62.06	OK
4115	2026-09-13 07:09	62.16	OK	4116	2026-09-13 07:10	62.64	OK
4117	2026-09-13 07:11	61.83	OK	4118	2026-09-13 07:12	61.21	OK
4119	2026-09-13 07:13	59.28	OK	4120	2026-09-13 07:14	62.88	OK
4121	2026-09-13 07:15	63.07	OK	4122	2026-09-13 07:16	61.83	OK
4123	2026-09-13 07:17	63.65	OK	4124	2026-09-13 07:18	62.06	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4125	2026-09-13 07:19	63.22	OK	4126	2026-09-13 07:20	62.64	OK
4127	2026-09-13 07:21	60.32	OK	4128	2026-09-13 07:22	59.50	OK
4129	2026-09-13 07:23	61.73	OK	4130	2026-09-13 07:24	62.29	OK
4131	2026-09-13 07:25	60.32	OK	4132	2026-09-13 07:26	59.66	OK
4133	2026-09-13 07:27	61.34	OK	4134	2026-09-13 07:28	61.06	OK
4135	2026-09-13 07:29	62.98	OK	4136	2026-09-13 07:30	63.68	OK
4137	2026-09-13 07:31	62.40	OK	4138	2026-09-13 07:32	61.27	OK
4139	2026-09-13 07:33	62.79	OK	4140	2026-09-13 07:34	60.57	OK
4141	2026-09-13 07:35	64.06	OK	4142	2026-09-13 07:36	62.17	OK
4143	2026-09-13 07:37	63.28	OK	4144	2026-09-13 07:38	58.61	OK
4145	2026-09-13 07:39	61.26	OK	4146	2026-09-13 07:40	60.82	OK
4147	2026-09-13 07:41	62.02	OK	4148	2026-09-13 07:42	62.53	OK
4149	2026-09-13 07:43	60.95	OK	4150	2026-09-13 07:44	61.93	OK
4151	2026-09-13 07:45	62.53	OK	4152	2026-09-13 07:46	62.24	OK
4153	2026-09-13 07:47	61.24	OK	4154	2026-09-13 07:48	62.90	OK
4155	2026-09-13 07:49	59.40	OK	4156	2026-09-13 07:50	60.24	OK
4157	2026-09-13 07:51	61.34	OK	4158	2026-09-13 07:52	61.48	OK
4159	2026-09-13 07:53	60.81	OK	4160	2026-09-13 07:54	63.03	OK
4161	2026-09-13 07:55	62.77	OK	4162	2026-09-13 07:56	59.21	OK
4163	2026-09-13 07:57	61.42	OK	4164	2026-09-13 07:58	61.50	OK
4165	2026-09-13 07:59	60.08	OK	4166	2026-09-13 08:00	63.23	OK
4167	2026-09-13 08:01	61.36	OK	4168	2026-09-13 08:02	61.89	OK
4169	2026-09-13 08:03	62.87	OK	4170	2026-09-13 08:04	61.48	OK
4171	2026-09-13 08:05	60.58	OK	4172	2026-09-13 08:06	60.87	OK
4173	2026-09-13 08:07	59.07	OK	4174	2026-09-13 08:08	59.73	OK
4175	2026-09-13 08:09	60.68	OK	4176	2026-09-13 08:10	60.75	OK
4177	2026-09-13 08:11	61.05	OK	4178	2026-09-13 08:12	62.17	OK
4179	2026-09-13 08:13	59.58	OK	4180	2026-09-13 08:14	62.59	OK
4181	2026-09-13 08:15	60.52	OK	4182	2026-09-13 08:16	60.08	OK
4183	2026-09-13 08:17	58.50	OK	4184	2026-09-13 08:18	60.75	OK
4185	2026-09-13 08:19	60.94	OK	4186	2026-09-13 08:20	61.13	OK
4187	2026-09-13 08:21	60.20	OK	4188	2026-09-13 08:22	60.86	OK
4189	2026-09-13 08:23	62.38	OK	4190	2026-09-13 08:24	58.39	OK
4191	2026-09-13 08:25	58.78	OK	4192	2026-09-13 08:26	61.76	OK
4193	2026-09-13 08:27	61.76	OK	4194	2026-09-13 08:28	62.05	OK
4195	2026-09-13 08:29	60.34	OK	4196	2026-09-13 08:30	60.89	OK
4197	2026-09-13 08:31	61.04	OK	4198	2026-09-13 08:32	59.69	OK
4199	2026-09-13 08:33	58.76	OK	4200	2026-09-13 08:34	61.09	OK
4201	2026-09-13 08:35	60.48	OK	4202	2026-09-13 08:36	61.99	OK
4203	2026-09-13 08:37	59.35	OK	4204	2026-09-13 08:38	60.36	OK
4205	2026-09-13 08:39	63.10	OK	4206	2026-09-13 08:40	58.84	OK
4207	2026-09-13 08:41	59.31	OK	4208	2026-09-13 08:42	59.25	OK
4209	2026-09-13 08:43	60.77	OK	4210	2026-09-13 08:44	59.06	OK
4211	2026-09-13 08:45	59.95	OK	4212	2026-09-13 08:46	60.13	OK
4213	2026-09-13 08:47	62.08	OK	4214	2026-09-13 08:48	60.37	OK
4215	2026-09-13 08:49	60.20	OK	4216	2026-09-13 08:50	60.86	OK
4217	2026-09-13 08:51	59.38	OK	4218	2026-09-13 08:52	62.34	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4219	2026-09-13 08:53	61.35	OK	4220	2026-09-13 08:54	60.53	OK
4221	2026-09-13 08:55	60.39	OK	4222	2026-09-13 08:56	62.32	OK
4223	2026-09-13 08:57	59.68	OK	4224	2026-09-13 08:58	59.84	OK
4225	2026-09-13 08:59	59.91	OK	4226	2026-09-13 09:00	60.07	OK
4227	2026-09-13 09:01	59.66	OK	4228	2026-09-13 09:02	59.95	OK
4229	2026-09-13 09:03	59.77	OK	4230	2026-09-13 09:04	60.10	OK
4231	2026-09-13 09:05	59.95	OK	4232	2026-09-13 09:06	60.88	OK
4233	2026-09-13 09:07	58.34	OK	4234	2026-09-13 09:08	60.51	OK
4235	2026-09-13 09:09	61.07	OK	4236	2026-09-13 09:10	62.62	OK
4237	2026-09-13 09:11	60.67	OK	4238	2026-09-13 09:12	60.80	OK
4239	2026-09-13 09:13	59.61	OK	4240	2026-09-13 09:14	59.10	OK
4241	2026-09-13 09:15	57.83	OK	4242	2026-09-13 09:16	59.53	OK
4243	2026-09-13 09:17	58.19	OK	4244	2026-09-13 09:18	58.28	OK
4245	2026-09-13 09:19	58.22	OK	4246	2026-09-13 09:20	60.45	OK
4247	2026-09-13 09:21	62.27	OK	4248	2026-09-13 09:22	62.42	OK
4249	2026-09-13 09:23	61.09	OK	4250	2026-09-13 09:24	60.87	OK
4251	2026-09-13 09:25	60.17	OK	4252	2026-09-13 09:26	58.81	OK
4253	2026-09-13 09:27	61.35	OK	4254	2026-09-13 09:28	58.86	OK
4255	2026-09-13 09:29	62.40	OK	4256	2026-09-13 09:30	60.38	OK
4257	2026-09-13 09:31	61.17	OK	4258	2026-09-13 09:32	60.09	OK
4259	2026-09-13 09:33	58.67	OK	4260	2026-09-13 09:34	61.00	OK
4261	2026-09-13 09:35	61.43	OK	4262	2026-09-13 09:36	59.93	OK
4263	2026-09-13 09:37	59.16	OK	4264	2026-09-13 09:38	59.20	OK
4265	2026-09-13 09:39	57.20	OK	4266	2026-09-13 09:40	59.01	OK
4267	2026-09-13 09:41	58.82	OK	4268	2026-09-13 09:42	58.87	OK
4269	2026-09-13 09:43	58.89	OK	4270	2026-09-13 09:44	59.99	OK
4271	2026-09-13 09:45	60.30	OK	4272	2026-09-13 09:46	59.32	OK
4273	2026-09-13 09:47	57.80	OK	4274	2026-09-13 09:48	58.07	OK
4275	2026-09-13 09:49	59.44	OK	4276	2026-09-13 09:50	58.39	OK
4277	2026-09-13 09:51	59.86	OK	4278	2026-09-13 09:52	61.49	OK
4279	2026-09-13 09:53	59.81	OK	4280	2026-09-13 09:54	59.93	OK
4281	2026-09-13 09:55	59.41	OK	4282	2026-09-13 09:56	59.69	OK
4283	2026-09-13 09:57	58.35	OK	4284	2026-09-13 09:58	59.99	OK
4285	2026-09-13 09:59	60.13	OK	4286	2026-09-13 10:00	61.78	OK
4287	2026-09-13 10:01	60.67	OK	4288	2026-09-13 10:02	58.82	OK
4289	2026-09-13 10:03	60.68	OK	4290	2026-09-13 10:04	58.78	OK
4291	2026-09-13 10:05	59.47	OK	4292	2026-09-13 10:06	59.94	OK
4293	2026-09-13 10:07	58.98	OK	4294	2026-09-13 10:08	62.00	OK
4295	2026-09-13 10:09	58.83	OK	4296	2026-09-13 10:10	59.88	OK
4297	2026-09-13 10:11	61.84	OK	4298	2026-09-13 10:12	61.19	OK
4299	2026-09-13 10:13	59.20	OK	4300	2026-09-13 10:14	62.15	OK
4301	2026-09-13 10:15	57.42	OK	4302	2026-09-13 10:16	58.84	OK
4303	2026-09-13 10:17	61.16	OK	4304	2026-09-13 10:18	59.43	OK
4305	2026-09-13 10:19	60.38	OK	4306	2026-09-13 10:20	60.69	OK
4307	2026-09-13 10:21	60.24	OK	4308	2026-09-13 10:22	60.00	OK
4309	2026-09-13 10:23	60.32	OK	4310	2026-09-13 10:24	57.60	OK
4311	2026-09-13 10:25	60.85	OK	4312	2026-09-13 10:26	58.26	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4313	2026-09-13 10:27	58.26	OK	4314	2026-09-13 10:28	60.01	OK
4315	2026-09-13 10:29	59.38	OK	4316	2026-09-13 10:30	56.69	OK
4317	2026-09-13 10:31	56.49	OK	4318	2026-09-13 10:32	58.45	OK
4319	2026-09-13 10:33	58.98	OK	4320	2026-09-13 10:34	59.26	OK
4321	2026-09-13 10:35	58.28	OK	4322	2026-09-13 10:36	60.04	OK
4323	2026-09-13 10:37	60.26	OK	4324	2026-09-13 10:38	59.00	OK
4325	2026-09-13 10:39	57.90	OK	4326	2026-09-13 10:40	59.18	OK
4327	2026-09-13 10:41	59.74	OK	4328	2026-09-13 10:42	57.12	OK
4329	2026-09-13 10:43	58.50	OK	4330	2026-09-13 10:44	58.55	OK
4331	2026-09-13 10:45	58.78	OK	4332	2026-09-13 10:46	61.67	OK
4333	2026-09-13 10:47	60.37	OK	4334	2026-09-13 10:48	58.80	OK
4335	2026-09-13 10:49	61.72	OK	4336	2026-09-13 10:50	60.81	OK
4337	2026-09-13 10:51	58.98	OK	4338	2026-09-13 10:52	59.63	OK
4339	2026-09-13 10:53	60.53	OK	4340	2026-09-13 10:54	59.57	OK
4341	2026-09-13 10:55	58.04	OK	4342	2026-09-13 10:56	58.37	OK
4343	2026-09-13 10:57	59.07	OK	4344	2026-09-13 10:58	60.11	OK
4345	2026-09-13 10:59	59.24	OK	4346	2026-09-13 11:00	61.26	OK
4347	2026-09-13 11:01	60.73	OK	4348	2026-09-13 11:02	60.41	OK
4349	2026-09-13 11:03	58.86	OK	4350	2026-09-13 11:04	59.57	OK
4351	2026-09-13 11:05	61.51	OK	4352	2026-09-13 11:06	59.31	OK
4353	2026-09-13 11:07	60.50	OK	4354	2026-09-13 11:08	61.38	OK
4355	2026-09-13 11:09	56.98	OK	4356	2026-09-13 11:10	59.94	OK
4357	2026-09-13 11:11	61.47	OK	4358	2026-09-13 11:12	60.91	OK
4359	2026-09-13 11:13	60.00	OK	4360	2026-09-13 11:14	58.63	OK
4361	2026-09-13 11:15	60.94	OK	4362	2026-09-13 11:16	57.33	OK
4363	2026-09-13 11:17	61.70	OK	4364	2026-09-13 11:18	58.50	OK
4365	2026-09-13 11:19	58.89	OK	4366	2026-09-13 11:20	60.63	OK
4367	2026-09-13 11:21	60.12	OK	4368	2026-09-13 11:22	60.91	OK
4369	2026-09-13 11:23	59.47	OK	4370	2026-09-13 11:24	59.82	OK
4371	2026-09-13 11:25	60.07	OK	4372	2026-09-13 11:26	61.01	OK
4373	2026-09-13 11:27	58.35	OK	4374	2026-09-13 11:28	59.37	OK
4375	2026-09-13 11:29	59.63	OK	4376	2026-09-13 11:30	61.12	OK
4377	2026-09-13 11:31	60.02	OK	4378	2026-09-13 11:32	58.62	OK
4379	2026-09-13 11:33	58.96	OK	4380	2026-09-13 11:34	59.90	OK
4381	2026-09-13 11:35	59.68	OK	4382	2026-09-13 11:36	58.95	OK
4383	2026-09-13 11:37	60.17	OK	4384	2026-09-13 11:38	58.02	OK
4385	2026-09-13 11:39	58.83	OK	4386	2026-09-13 11:40	61.33	OK
4387	2026-09-13 11:41	59.13	OK	4388	2026-09-13 11:42	61.40	OK
4389	2026-09-13 11:43	59.62	OK	4390	2026-09-13 11:44	58.75	OK
4391	2026-09-13 11:45	60.31	OK	4392	2026-09-13 11:46	60.33	OK
4393	2026-09-13 11:47	61.66	OK	4394	2026-09-13 11:48	61.87	OK
4395	2026-09-13 11:49	59.80	OK	4396	2026-09-13 11:50	59.24	OK
4397	2026-09-13 11:51	59.23	OK	4398	2026-09-13 11:52	60.14	OK
4399	2026-09-13 11:53	56.67	OK	4400	2026-09-13 11:54	60.91	OK
4401	2026-09-13 11:55	58.45	OK	4402	2026-09-13 11:56	58.21	OK
4403	2026-09-13 11:57	59.57	OK	4404	2026-09-13 11:58	61.20	OK
4405	2026-09-13 11:59	63.45	OK	4406	2026-09-13 12:00	60.55	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4407	2026-09-13 12:01	60.09	OK	4408	2026-09-13 12:02	58.62	OK
4409	2026-09-13 12:03	60.66	OK	4410	2026-09-13 12:04	60.19	OK
4411	2026-09-13 12:05	60.82	OK	4412	2026-09-13 12:06	62.19	OK
4413	2026-09-13 12:07	60.58	OK	4414	2026-09-13 12:08	61.72	OK
4415	2026-09-13 12:09	60.26	OK	4416	2026-09-13 12:10	59.89	OK
4417	2026-09-13 12:11	61.79	OK	4418	2026-09-13 12:12	56.86	OK
4419	2026-09-13 12:13	61.33	OK	4420	2026-09-13 12:14	58.87	OK
4421	2026-09-13 12:15	62.25	OK	4422	2026-09-13 12:16	58.37	OK
4423	2026-09-13 12:17	60.89	OK	4424	2026-09-13 12:18	57.91	OK
4425	2026-09-13 12:19	61.81	OK	4426	2026-09-13 12:20	60.26	OK
4427	2026-09-13 12:21	58.90	OK	4428	2026-09-13 12:22	61.53	OK
4429	2026-09-13 12:23	59.21	OK	4430	2026-09-13 12:24	59.93	OK
4431	2026-09-13 12:25	59.60	OK	4432	2026-09-13 12:26	59.60	OK
4433	2026-09-13 12:27	58.65	OK	4434	2026-09-13 12:28	59.06	OK
4435	2026-09-13 12:29	59.46	OK	4436	2026-09-13 12:30	61.25	OK
4437	2026-09-13 12:31	61.04	OK	4438	2026-09-13 12:32	58.97	OK
4439	2026-09-13 12:33	61.12	OK	4440	2026-09-13 12:34	60.96	OK
4441	2026-09-13 12:35	58.96	OK	4442	2026-09-13 12:36	62.99	OK
4443	2026-09-13 12:37	60.01	OK	4444	2026-09-13 12:38	60.26	OK
4445	2026-09-13 12:39	60.11	OK	4446	2026-09-13 12:40	61.21	OK
4447	2026-09-13 12:41	61.81	OK	4448	2026-09-13 12:42	59.95	OK
4449	2026-09-13 12:43	61.26	OK	4450	2026-09-13 12:44	61.72	OK
4451	2026-09-13 12:45	61.08	OK	4452	2026-09-13 12:46	59.93	OK
4453	2026-09-13 12:47	59.82	OK	4454	2026-09-13 12:48	59.71	OK
4455	2026-09-13 12:49	60.72	OK	4456	2026-09-13 12:50	61.53	OK
4457	2026-09-13 12:51	60.86	OK	4458	2026-09-13 12:52	61.11	OK
4459	2026-09-13 12:53	60.87	OK	4460	2026-09-13 12:54	59.77	OK
4461	2026-09-13 12:55	61.33	OK	4462	2026-09-13 12:56	60.59	OK
4463	2026-09-13 12:57	59.88	OK	4464	2026-09-13 12:58	61.13	OK
4465	2026-09-13 12:59	61.70	OK	4466	2026-09-13 13:00	59.69	OK
4467	2026-09-13 13:01	61.83	OK	4468	2026-09-13 13:02	62.47	OK
4469	2026-09-13 13:03	59.34	OK	4470	2026-09-13 13:04	58.47	OK
4471	2026-09-13 13:05	61.40	OK	4472	2026-09-13 13:06	61.24	OK
4473	2026-09-13 13:07	62.53	OK	4474	2026-09-13 13:08	58.80	OK
4475	2026-09-13 13:09	60.74	OK	4476	2026-09-13 13:10	59.42	OK
4477	2026-09-13 13:11	62.07	OK	4478	2026-09-13 13:12	60.96	OK
4479	2026-09-13 13:13	60.43	OK	4480	2026-09-13 13:14	60.03	OK
4481	2026-09-13 13:15	61.29	OK	4482	2026-09-13 13:16	59.49	OK
4483	2026-09-13 13:17	61.48	OK	4484	2026-09-13 13:18	62.55	OK
4485	2026-09-13 13:19	62.91	OK	4486	2026-09-13 13:20	61.20	OK
4487	2026-09-13 13:21	59.32	OK	4488	2026-09-13 13:22	58.77	OK
4489	2026-09-13 13:23	61.69	OK	4490	2026-09-13 13:24	61.58	OK
4491	2026-09-13 13:25	60.67	OK	4492	2026-09-13 13:26	61.17	OK
4493	2026-09-13 13:27	62.09	OK	4494	2026-09-13 13:28	63.68	OK
4495	2026-09-13 13:29	61.76	OK	4496	2026-09-13 13:30	60.15	OK
4497	2026-09-13 13:31	64.23	OK	4498	2026-09-13 13:32	61.95	OK
4499	2026-09-13 13:33	60.05	OK	4500	2026-09-13 13:34	61.83	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4501	2026-09-13 13:35	59.88	OK	4502	2026-09-13 13:36	61.04	OK
4503	2026-09-13 13:37	62.58	OK	4504	2026-09-13 13:38	62.44	OK
4505	2026-09-13 13:39	60.66	OK	4506	2026-09-13 13:40	59.76	OK
4507	2026-09-13 13:41	62.54	OK	4508	2026-09-13 13:42	61.01	OK
4509	2026-09-13 13:43	61.02	OK	4510	2026-09-13 13:44	60.68	OK
4511	2026-09-13 13:45	63.04	OK	4512	2026-09-13 13:46	63.18	OK
4513	2026-09-13 13:47	63.18	OK	4514	2026-09-13 13:48	61.06	OK
4515	2026-09-13 13:49	59.92	OK	4516	2026-09-13 13:50	60.93	OK
4517	2026-09-13 13:51	63.20	OK	4518	2026-09-13 13:52	62.34	OK
4519	2026-09-13 13:53	62.25	OK	4520	2026-09-13 13:54	59.89	OK
4521	2026-09-13 13:55	61.77	OK	4522	2026-09-13 13:56	61.14	OK
4523	2026-09-13 13:57	61.05	OK	4524	2026-09-13 13:58	61.79	OK
4525	2026-09-13 13:59	64.92	OK	4526	2026-09-13 14:00	64.03	OK
4527	2026-09-13 14:01	64.34	OK	4528	2026-09-13 14:02	61.24	OK
4529	2026-09-13 14:03	65.27	OK	4530	2026-09-13 14:04	62.88	OK
4531	2026-09-13 14:05	62.42	OK	4532	2026-09-13 14:06	61.88	OK
4533	2026-09-13 14:07	60.32	OK	4534	2026-09-13 14:08	61.57	OK
4535	2026-09-13 14:09	60.90	OK	4536	2026-09-13 14:10	60.36	OK
4537	2026-09-13 14:11	61.04	OK	4538	2026-09-13 14:12	62.51	OK
4539	2026-09-13 14:13	63.22	OK	4540	2026-09-13 14:14	62.61	OK
4541	2026-09-13 14:15	60.91	OK	4542	2026-09-13 14:16	62.17	OK
4543	2026-09-13 14:17	63.16	OK	4544	2026-09-13 14:18	62.69	OK
4545	2026-09-13 14:19	63.84	OK	4546	2026-09-13 14:20	60.35	OK
4547	2026-09-13 14:21	59.26	OK	4548	2026-09-13 14:22	62.91	OK
4549	2026-09-13 14:23	60.71	OK	4550	2026-09-13 14:24	61.10	OK
4551	2026-09-13 14:25	62.91	OK	4552	2026-09-13 14:26	64.15	OK
4553	2026-09-13 14:27	63.48	OK	4554	2026-09-13 14:28	61.37	OK
4555	2026-09-13 14:29	61.96	OK	4556	2026-09-13 14:30	63.58	OK
4557	2026-09-13 14:31	63.23	OK	4558	2026-09-13 14:32	61.88	OK
4559	2026-09-13 14:33	61.89	OK	4560	2026-09-13 14:34	62.68	OK
4561	2026-09-13 14:35	63.35	OK	4562	2026-09-13 14:36	62.93	OK
4563	2026-09-13 14:37	63.28	OK	4564	2026-09-13 14:38	63.32	OK
4565	2026-09-13 14:39	61.77	OK	4566	2026-09-13 14:40	61.00	OK
4567	2026-09-13 14:41	62.53	OK	4568	2026-09-13 14:42	65.25	OK
4569	2026-09-13 14:43	62.10	OK	4570	2026-09-13 14:44	63.27	OK
4571	2026-09-13 14:45	64.68	OK	4572	2026-09-13 14:46	62.96	OK
4573	2026-09-13 14:47	63.69	OK	4574	2026-09-13 14:48	61.71	OK
4575	2026-09-13 14:49	63.98	OK	4576	2026-09-13 14:50	62.69	OK
4577	2026-09-13 14:51	63.02	OK	4578	2026-09-13 14:52	61.64	OK
4579	2026-09-13 14:53	62.76	OK	4580	2026-09-13 14:54	61.06	OK
4581	2026-09-13 14:55	62.09	OK	4582	2026-09-13 14:56	64.45	OK
4583	2026-09-13 14:57	63.62	OK	4584	2026-09-13 14:58	65.16	OK
4585	2026-09-13 14:59	64.96	OK	4586	2026-09-13 15:00	62.39	OK
4587	2026-09-13 15:01	63.42	OK	4588	2026-09-13 15:02	63.18	OK
4589	2026-09-13 15:03	63.26	OK	4590	2026-09-13 15:04	62.71	OK
4591	2026-09-13 15:05	63.29	OK	4592	2026-09-13 15:06	61.00	OK
4593	2026-09-13 15:07	63.64	OK	4594	2026-09-13 15:08	64.54	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4595	2026-09-13 15:09	62.97	OK	4596	2026-09-13 15:10	64.13	OK
4597	2026-09-13 15:11	64.45	OK	4598	2026-09-13 15:12	65.44	OK
4599	2026-09-13 15:13	64.36	OK	4600	2026-09-13 15:14	64.31	OK
4601	2026-09-13 15:15	66.41	OK	4602	2026-09-13 15:16	62.15	OK
4603	2026-09-13 15:17	63.65	OK	4604	2026-09-13 15:18	65.40	OK
4605	2026-09-13 15:19	63.84	OK	4606	2026-09-13 15:20	66.84	OK
4607	2026-09-13 15:21	64.99	OK	4608	2026-09-13 15:22	63.30	OK
4609	2026-09-13 15:23	63.49	OK	4610	2026-09-13 15:24	61.97	OK
4611	2026-09-13 15:25	64.09	OK	4612	2026-09-13 15:26	66.62	OK
4613	2026-09-13 15:27	63.39	OK	4614	2026-09-13 15:28	65.83	OK
4615	2026-09-13 15:29	65.43	OK	4616	2026-09-13 15:30	66.10	OK
4617	2026-09-13 15:31	65.72	OK	4618	2026-09-13 15:32	62.12	OK
4619	2026-09-13 15:33	66.33	OK	4620	2026-09-13 15:34	63.70	OK
4621	2026-09-13 15:35	63.17	OK	4622	2026-09-13 15:36	66.56	OK
4623	2026-09-13 15:37	65.40	OK	4624	2026-09-13 15:38	65.11	OK
4625	2026-09-13 15:39	63.31	OK	4626	2026-09-13 15:40	63.68	OK
4627	2026-09-13 15:41	66.21	OK	4628	2026-09-13 15:42	66.88	OK
4629	2026-09-13 15:43	65.35	OK	4630	2026-09-13 15:44	61.81	OK
4631	2026-09-13 15:45	65.74	OK	4632	2026-09-13 15:46	63.71	OK
4633	2026-09-13 15:47	66.08	OK	4634	2026-09-13 15:48	65.08	OK
4635	2026-09-13 15:49	63.19	OK	4636	2026-09-13 15:50	67.28	OK
4637	2026-09-13 15:51	62.32	OK	4638	2026-09-13 15:52	65.60	OK
4639	2026-09-13 15:53	65.92	OK	4640	2026-09-13 15:54	63.41	OK
4641	2026-09-13 15:55	64.45	OK	4642	2026-09-13 15:56	64.06	OK
4643	2026-09-13 15:57	64.85	OK	4644	2026-09-13 15:58	63.34	OK
4645	2026-09-13 15:59	63.83	OK	4646	2026-09-13 16:00	64.60	OK
4647	2026-09-13 16:01	63.75	OK	4648	2026-09-13 16:02	65.58	OK
4649	2026-09-13 16:03	65.36	OK	4650	2026-09-13 16:04	63.71	OK
4651	2026-09-13 16:05	65.10	OK	4652	2026-09-13 16:06	65.86	OK
4653	2026-09-13 16:07	63.89	OK	4654	2026-09-13 16:08	65.51	OK
4655	2026-09-13 16:09	63.89	OK	4656	2026-09-13 16:10	63.89	OK
4657	2026-09-13 16:11	63.95	OK	4658	2026-09-13 16:12	65.46	OK
4659	2026-09-13 16:13	64.64	OK	4660	2026-09-13 16:14	66.40	OK
4661	2026-09-13 16:15	62.40	OK	4662	2026-09-13 16:16	63.54	OK
4663	2026-09-13 16:17	63.94	OK	4664	2026-09-13 16:18	67.81	OK
4665	2026-09-13 16:19	63.78	OK	4666	2026-09-13 16:20	68.61	OK
4667	2026-09-13 16:21	65.84	OK	4668	2026-09-13 16:22	68.03	OK
4669	2026-09-13 16:23	65.35	OK	4670	2026-09-13 16:24	63.89	OK
4671	2026-09-13 16:25	65.47	OK	4672	2026-09-13 16:26	64.71	OK
4673	2026-09-13 16:27	65.54	OK	4674	2026-09-13 16:28	64.32	OK
4675	2026-09-13 16:29	67.64	OK	4676	2026-09-13 16:30	65.86	OK
4677	2026-09-13 16:31	65.38	OK	4678	2026-09-13 16:32	65.11	OK
4679	2026-09-13 16:33	64.59	OK	4680	2026-09-13 16:34	67.19	OK
4681	2026-09-13 16:35	65.77	OK	4682	2026-09-13 16:36	66.48	OK
4683	2026-09-13 16:37	64.68	OK	4684	2026-09-13 16:38	63.89	OK
4685	2026-09-13 16:39	69.30	OK	4686	2026-09-13 16:40	66.89	OK
4687	2026-09-13 16:41	67.31	OK	4688	2026-09-13 16:42	66.22	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4689	2026-09-13 16:43	67.02	OK	4690	2026-09-13 16:44	67.03	OK
4691	2026-09-13 16:45	66.21	OK	4692	2026-09-13 16:46	66.55	OK
4693	2026-09-13 16:47	66.48	OK	4694	2026-09-13 16:48	68.07	OK
4695	2026-09-13 16:49	68.73	OK	4696	2026-09-13 16:50	67.34	OK
4697	2026-09-13 16:51	67.64	OK	4698	2026-09-13 16:52	65.90	OK
4699	2026-09-13 16:53	67.62	OK	4700	2026-09-13 16:54	64.70	OK
4701	2026-09-13 16:55	66.30	OK	4702	2026-09-13 16:56	66.72	OK
4703	2026-09-13 16:57	67.69	OK	4704	2026-09-13 16:58	67.11	OK
4705	2026-09-13 16:59	65.11	OK	4706	2026-09-13 17:00	68.07	OK
4707	2026-09-13 17:01	65.19	OK	4708	2026-09-13 17:02	67.85	OK
4709	2026-09-13 17:03	67.81	OK	4710	2026-09-13 17:04	67.94	OK
4711	2026-09-13 17:05	67.17	OK	4712	2026-09-13 17:06	63.65	OK
4713	2026-09-13 17:07	68.33	OK	4714	2026-09-13 17:08	68.18	OK
4715	2026-09-13 17:09	66.17	OK	4716	2026-09-13 17:10	67.97	OK
4717	2026-09-13 17:11	66.26	OK	4718	2026-09-13 17:12	66.23	OK
4719	2026-09-13 17:13	66.03	OK	4720	2026-09-13 17:14	65.50	OK
4721	2026-09-13 17:15	66.45	OK	4722	2026-09-13 17:16	66.14	OK
4723	2026-09-13 17:17	66.64	OK	4724	2026-09-13 17:18	66.53	OK
4725	2026-09-13 17:19	66.45	OK	4726	2026-09-13 17:20	67.82	OK
4727	2026-09-13 17:21	68.23	OK	4728	2026-09-13 17:22	68.24	OK
4729	2026-09-13 17:23	66.73	OK	4730	2026-09-13 17:24	67.73	OK
4731	2026-09-13 17:25	65.08	OK	4732	2026-09-13 17:26	67.70	OK
4733	2026-09-13 17:27	66.24	OK	4734	2026-09-13 17:28	68.15	OK
4735	2026-09-13 17:29	65.19	OK	4736	2026-09-13 17:30	67.00	OK
4737	2026-09-13 17:31	68.87	OK	4738	2026-09-13 17:32	68.46	OK
4739	2026-09-13 17:33	69.74	OK	4740	2026-09-13 17:34	66.64	OK
4741	2026-09-13 17:35	68.37	OK	4742	2026-09-13 17:36	69.60	OK
4743	2026-09-13 17:37	67.72	OK	4744	2026-09-13 17:38	66.69	OK
4745	2026-09-13 17:39	69.38	OK	4746	2026-09-13 17:40	68.42	OK
4747	2026-09-13 17:41	67.91	OK	4748	2026-09-13 17:42	66.80	OK
4749	2026-09-13 17:43	68.34	OK	4750	2026-09-13 17:44	67.63	OK
4751	2026-09-13 17:45	65.13	OK	4752	2026-09-13 17:46	67.16	OK
4753	2026-09-13 17:47	68.40	OK	4754	2026-09-13 17:48	67.72	OK
4755	2026-09-13 17:49	68.50	OK	4756	2026-09-13 17:50	67.13	OK
4757	2026-09-13 17:51	68.70	OK	4758	2026-09-13 17:52	65.92	OK
4759	2026-09-13 17:53	67.12	OK	4760	2026-09-13 17:54	69.81	OK
4761	2026-09-13 17:55	68.04	OK	4762	2026-09-13 17:56	66.56	OK
4763	2026-09-13 17:57	66.56	OK	4764	2026-09-13 17:58	68.01	OK
4765	2026-09-13 17:59	69.74	OK	4766	2026-09-13 18:00	67.31	OK
4767	2026-09-13 18:01	67.15	OK	4768	2026-09-13 18:02	66.61	OK
4769	2026-09-13 18:03	68.55	OK	4770	2026-09-13 18:04	70.30	OK
4771	2026-09-13 18:05	67.26	OK	4772	2026-09-13 18:06	67.63	OK
4773	2026-09-13 18:07	71.01	OK	4774	2026-09-13 18:08	67.65	OK
4775	2026-09-13 18:09	68.22	OK	4776	2026-09-13 18:10	67.11	OK
4777	2026-09-13 18:11	69.54	OK	4778	2026-09-13 18:12	68.54	OK
4779	2026-09-13 18:13	69.91	OK	4780	2026-09-13 18:14	69.42	OK
4781	2026-09-13 18:15	69.31	OK	4782	2026-09-13 18:16	70.65	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4783	2026-09-13 18:17	65.91	OK	4784	2026-09-13 18:18	68.13	OK
4785	2026-09-13 18:19	70.57	OK	4786	2026-09-13 18:20	71.49	OK
4787	2026-09-13 18:21	69.19	OK	4788	2026-09-13 18:22	71.07	OK
4789	2026-09-13 18:23	69.15	OK	4790	2026-09-13 18:24	68.85	OK
4791	2026-09-13 18:25	68.09	OK	4792	2026-09-13 18:26	70.71	OK
4793	2026-09-13 18:27	69.37	OK	4794	2026-09-13 18:28	67.74	OK
4795	2026-09-13 18:29	68.75	OK	4796	2026-09-13 18:30	68.85	OK
4797	2026-09-13 18:31	68.63	OK	4798	2026-09-13 18:32	66.59	OK
4799	2026-09-13 18:33	68.49	OK	4800	2026-09-13 18:34	69.52	OK
4801	2026-09-13 18:35	66.29	OK	4802	2026-09-13 18:36	69.33	OK
4803	2026-09-13 18:37	67.99	OK	4804	2026-09-13 18:38	67.06	OK
4805	2026-09-13 18:39	69.64	OK	4806	2026-09-13 18:40	71.57	OK
4807	2026-09-13 18:41	69.80	OK	4808	2026-09-13 18:42	71.53	OK
4809	2026-09-13 18:43	69.90	OK	4810	2026-09-13 18:44	68.54	OK
4811	2026-09-13 18:45	70.40	OK	4812	2026-09-13 18:46	70.27	OK
4813	2026-09-13 18:47	68.14	OK	4814	2026-09-13 18:48	68.11	OK
4815	2026-09-13 18:49	70.01	OK	4816	2026-09-13 18:50	71.56	OK
4817	2026-09-13 18:51	70.64	OK	4818	2026-09-13 18:52	68.42	OK
4819	2026-09-13 18:53	71.16	OK	4820	2026-09-13 18:54	71.61	OK
4821	2026-09-13 18:55	71.59	OK	4822	2026-09-13 18:56	67.87	OK
4823	2026-09-13 18:57	69.88	OK	4824	2026-09-13 18:58	69.41	OK
4825	2026-09-13 18:59	68.54	OK	4826	2026-09-13 19:00	67.52	OK
4827	2026-09-13 19:01	71.57	OK	4828	2026-09-13 19:02	70.84	OK
4829	2026-09-13 19:03	68.99	OK	4830	2026-09-13 19:04	68.39	OK
4831	2026-09-13 19:05	70.14	OK	4832	2026-09-13 19:06	71.15	OK
4833	2026-09-13 19:07	67.76	OK	4834	2026-09-13 19:08	70.65	OK
4835	2026-09-13 19:09	67.94	OK	4836	2026-09-13 19:10	69.93	OK
4837	2026-09-13 19:11	69.88	OK	4838	2026-09-13 19:12	67.25	OK
4839	2026-09-13 19:13	70.66	OK	4840	2026-09-13 19:14	67.98	OK
4841	2026-09-13 19:15	69.83	OK	4842	2026-09-13 19:16	67.88	OK
4843	2026-09-13 19:17	69.40	OK	4844	2026-09-13 19:18	72.49	OK
4845	2026-09-13 19:19	70.04	OK	4846	2026-09-13 19:20	72.07	OK
4847	2026-09-13 19:21	70.38	OK	4848	2026-09-13 19:22	68.75	OK
4849	2026-09-13 19:23	69.20	OK	4850	2026-09-13 19:24	70.16	OK
4851	2026-09-13 19:25	70.17	OK	4852	2026-09-13 19:26	70.85	OK
4853	2026-09-13 19:27	71.14	OK	4854	2026-09-13 19:28	70.22	OK
4855	2026-09-13 19:29	71.56	OK	4856	2026-09-13 19:30	69.93	OK
4857	2026-09-13 19:31	72.44	OK	4858	2026-09-13 19:32	69.69	OK
4859	2026-09-13 19:33	69.96	OK	4860	2026-09-13 19:34	67.49	OK
4861	2026-09-13 19:35	68.17	OK	4862	2026-09-13 19:36	71.87	OK
4863	2026-09-13 19:37	70.35	OK	4864	2026-09-13 19:38	70.61	OK
4865	2026-09-13 19:39	69.48	OK	4866	2026-09-13 19:40	69.57	OK
4867	2026-09-13 19:41	70.42	OK	4868	2026-09-13 19:42	70.29	OK
4869	2026-09-13 19:43	70.68	OK	4870	2026-09-13 19:44	71.27	OK
4871	2026-09-13 19:45	73.55	OK	4872	2026-09-13 19:46	68.58	OK
4873	2026-09-13 19:47	71.70	OK	4874	2026-09-13 19:48	70.88	OK
4875	2026-09-13 19:49	71.11	OK	4876	2026-09-13 19:50	73.37	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4877	2026-09-13 19:51	70.16	OK	4878	2026-09-13 19:52	68.40	OK
4879	2026-09-13 19:53	68.48	OK	4880	2026-09-13 19:54	69.66	OK
4881	2026-09-13 19:55	72.86	OK	4882	2026-09-13 19:56	72.26	OK
4883	2026-09-13 19:57	70.09	OK	4884	2026-09-13 19:58	68.72	OK
4885	2026-09-13 19:59	70.69	OK	4886	2026-09-13 20:00	68.85	OK
4887	2026-09-13 20:01	73.40	OK	4888	2026-09-13 20:02	71.42	OK
4889	2026-09-13 20:03	69.82	OK	4890	2026-09-13 20:04	71.50	OK
4891	2026-09-13 20:05	70.34	OK	4892	2026-09-13 20:06	73.73	OK
4893	2026-09-13 20:07	71.57	OK	4894	2026-09-13 20:08	70.71	OK
4895	2026-09-13 20:09	72.22	OK	4896	2026-09-13 20:10	70.78	OK
4897	2026-09-13 20:11	70.23	OK	4898	2026-09-13 20:12	71.36	OK
4899	2026-09-13 20:13	71.13	OK	4900	2026-09-13 20:14	71.29	OK
4901	2026-09-13 20:15	71.77	OK	4902	2026-09-13 20:16	73.22	OK
4903	2026-09-13 20:17	69.46	OK	4904	2026-09-13 20:18	71.52	OK
4905	2026-09-13 20:19	70.20	OK	4906	2026-09-13 20:20	69.52	OK
4907	2026-09-13 20:21	72.36	OK	4908	2026-09-13 20:22	71.18	OK
4909	2026-09-13 20:23	68.54	OK	4910	2026-09-13 20:24	71.90	OK
4911	2026-09-13 20:25	72.11	OK	4912	2026-09-13 20:26	71.30	OK
4913	2026-09-13 20:27	71.43	OK	4914	2026-09-13 20:28	72.05	OK
4915	2026-09-13 20:29	71.87	OK	4916	2026-09-13 20:30	72.86	OK
4917	2026-09-13 20:31	71.94	OK	4918	2026-09-13 20:32	71.60	OK
4919	2026-09-13 20:33	74.26	OK	4920	2026-09-13 20:34	70.67	OK
4921	2026-09-13 20:35	71.14	OK	4922	2026-09-13 20:36	74.04	OK
4923	2026-09-13 20:37	73.17	OK	4924	2026-09-13 20:38	71.31	OK
4925	2026-09-13 20:39	71.59	OK	4926	2026-09-13 20:40	68.25	OK
4927	2026-09-13 20:41	71.39	OK	4928	2026-09-13 20:42	72.98	OK
4929	2026-09-13 20:43	70.46	OK	4930	2026-09-13 20:44	73.68	OK
4931	2026-09-13 20:45	70.90	OK	4932	2026-09-13 20:46	73.08	OK
4933	2026-09-13 20:47	71.31	OK	4934	2026-09-13 20:48	72.12	OK
4935	2026-09-13 20:49	71.16	OK	4936	2026-09-13 20:50	73.26	OK
4937	2026-09-13 20:51	73.82	OK	4938	2026-09-13 20:52	74.47	OK
4939	2026-09-13 20:53	72.39	OK	4940	2026-09-13 20:54	69.05	OK
4941	2026-09-13 20:55	71.78	OK	4942	2026-09-13 20:56	70.40	OK
4943	2026-09-13 20:57	72.86	OK	4944	2026-09-13 20:58	74.13	OK
4945	2026-09-13 20:59	69.70	OK	4946	2026-09-13 21:00	71.55	OK
4947	2026-09-13 21:01	70.75	OK	4948	2026-09-13 21:02	71.47	OK
4949	2026-09-13 21:03	73.66	OK	4950	2026-09-13 21:04	70.75	OK
4951	2026-09-13 21:05	71.44	OK	4952	2026-09-13 21:06	70.84	OK
4953	2026-09-13 21:07	71.09	OK	4954	2026-09-13 21:08	71.20	OK
4955	2026-09-13 21:09	72.76	OK	4956	2026-09-13 21:10	69.77	OK
4957	2026-09-13 21:11	73.09	OK	4958	2026-09-13 21:12	73.03	OK
4959	2026-09-13 21:13	71.93	OK	4960	2026-09-13 21:14	72.68	OK
4961	2026-09-13 21:15	74.45	OK	4962	2026-09-13 21:16	70.52	OK
4963	2026-09-13 21:17	72.19	OK	4964	2026-09-13 21:18	71.40	OK
4965	2026-09-13 21:19	72.18	OK	4966	2026-09-13 21:20	70.71	OK
4967	2026-09-13 21:21	72.21	OK	4968	2026-09-13 21:22	72.10	OK
4969	2026-09-13 21:23	71.78	OK	4970	2026-09-13 21:24	73.67	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4971	2026-09-13 21:25	73.14	OK	4972	2026-09-13 21:26	72.61	OK
4973	2026-09-13 21:27	72.15	OK	4974	2026-09-13 21:28	73.17	OK
4975	2026-09-13 21:29	70.83	OK	4976	2026-09-13 21:30	72.80	OK
4977	2026-09-13 21:31	73.57	OK	4978	2026-09-13 21:32	71.53	OK
4979	2026-09-13 21:33	71.46	OK	4980	2026-09-13 21:34	72.20	OK
4981	2026-09-13 21:35	71.59	OK	4982	2026-09-13 21:36	71.91	OK
4983	2026-09-13 21:37	72.89	OK	4984	2026-09-13 21:38	72.52	OK
4985	2026-09-13 21:39	70.52	OK	4986	2026-09-13 21:40	70.25	OK
4987	2026-09-13 21:41	69.75	OK	4988	2026-09-13 21:42	70.63	OK
4989	2026-09-13 21:43	71.94	OK	4990	2026-09-13 21:44	73.43	OK
4991	2026-09-13 21:45	72.32	OK	4992	2026-09-13 21:46	69.80	OK
4993	2026-09-13 21:47	71.38	OK	4994	2026-09-13 21:48	74.92	OK
4995	2026-09-13 21:49	71.84	OK	4996	2026-09-13 21:50	71.58	OK
4997	2026-09-13 21:51	75.23	OK	4998	2026-09-13 21:52	72.62	OK
4999	2026-09-13 21:53	73.50	OK	5000	2026-09-13 21:54	73.22	OK
5001	2026-09-13 21:55	72.18	OK	5002	2026-09-13 21:56	71.27	OK
5003	2026-09-13 21:57	72.67	OK	5004	2026-09-13 21:58	73.58	OK
5005	2026-09-13 21:59	70.64	OK	5006	2026-09-13 22:00	71.85	OK
5007	2026-09-13 22:01	72.24	OK	5008	2026-09-13 22:02	72.69	OK
5009	2026-09-13 22:03	71.88	OK	5010	2026-09-13 22:04	72.16	OK
5011	2026-09-13 22:05	73.52	OK	5012	2026-09-13 22:06	72.27	OK
5013	2026-09-13 22:07	72.67	OK	5014	2026-09-13 22:08	73.66	OK
5015	2026-09-13 22:09	71.59	OK	5016	2026-09-13 22:10	71.53	OK
5017	2026-09-13 22:11	73.21	OK	5018	2026-09-13 22:12	74.17	OK
5019	2026-09-13 22:13	72.47	OK	5020	2026-09-13 22:14	72.80	OK
5021	2026-09-13 22:15	73.27	OK	5022	2026-09-13 22:16	71.90	OK
5023	2026-09-13 22:17	72.91	OK	5024	2026-09-13 22:18	71.23	OK
5025	2026-09-13 22:19	74.79	OK	5026	2026-09-13 22:20	74.08	OK
5027	2026-09-13 22:21	73.35	OK	5028	2026-09-13 22:22	73.58	OK
5029	2026-09-13 22:23	73.71	OK	5030	2026-09-13 22:24	72.30	OK
5031	2026-09-13 22:25	72.66	OK	5032	2026-09-13 22:26	73.05	OK
5033	2026-09-13 22:27	73.87	OK	5034	2026-09-13 22:28	71.10	OK
5035	2026-09-13 22:29	74.42	OK	5036	2026-09-13 22:30	72.60	OK
5037	2026-09-13 22:31	74.33	OK	5038	2026-09-13 22:32	73.21	OK
5039	2026-09-13 22:33	72.22	OK	5040	2026-09-13 22:34	71.40	OK
5041	2026-09-13 22:35	73.30	OK	5042	2026-09-13 22:36	71.43	OK
5043	2026-09-13 22:37	73.09	OK	5044	2026-09-13 22:38	75.14	OK
5045	2026-09-13 22:39	73.65	OK	5046	2026-09-13 22:40	75.21	OK
5047	2026-09-13 22:41	72.20	OK	5048	2026-09-13 22:42	73.74	OK
5049	2026-09-13 22:43	71.38	OK	5050	2026-09-13 22:44	73.88	OK
5051	2026-09-13 22:45	74.17	OK	5052	2026-09-13 22:46	74.25	OK
5053	2026-09-13 22:47	72.48	OK	5054	2026-09-13 22:48	73.37	OK
5055	2026-09-13 22:49	74.90	OK	5056	2026-09-13 22:50	72.51	OK
5057	2026-09-13 22:51	71.47	OK	5058	2026-09-13 22:52	72.61	OK
5059	2026-09-13 22:53	74.67	OK	5060	2026-09-13 22:54	74.79	OK
5061	2026-09-13 22:55	73.20	OK	5062	2026-09-13 22:56	72.80	OK
5063	2026-09-13 22:57	72.88	OK	5064	2026-09-13 22:58	70.57	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5065	2026-09-13 22:59	71.84	OK	5066	2026-09-13 23:00	72.69	OK
5067	2026-09-13 23:01	72.27	OK	5068	2026-09-13 23:02	72.02	OK
5069	2026-09-13 23:03	71.41	OK	5070	2026-09-13 23:04	71.58	OK
5071	2026-09-13 23:05	71.06	OK	5072	2026-09-13 23:06	74.69	OK
5073	2026-09-13 23:07	73.83	OK	5074	2026-09-13 23:08	71.32	OK
5075	2026-09-13 23:09	74.43	OK	5076	2026-09-13 23:10	72.65	OK
5077	2026-09-13 23:11	71.92	OK	5078	2026-09-13 23:12	70.90	OK
5079	2026-09-13 23:13	73.54	OK	5080	2026-09-13 23:14	73.64	OK
5081	2026-09-13 23:15	71.86	OK	5082	2026-09-13 23:16	70.36	OK
5083	2026-09-13 23:17	71.30	OK	5084	2026-09-13 23:18	71.58	OK
5085	2026-09-13 23:19	71.40	OK	5086	2026-09-13 23:20	70.67	OK
5087	2026-09-13 23:21	71.54	OK	5088	2026-09-13 23:22	73.92	OK
5089	2026-09-13 23:23	72.51	OK	5090	2026-09-13 23:24	73.07	OK
5091	2026-09-13 23:25	74.24	OK	5092	2026-09-13 23:26	71.02	OK
5093	2026-09-13 23:27	74.59	OK	5094	2026-09-13 23:28	71.20	OK
5095	2026-09-13 23:29	73.28	OK	5096	2026-09-13 23:30	73.65	OK
5097	2026-09-13 23:31	72.42	OK	5098	2026-09-13 23:32	74.44	OK
5099	2026-09-13 23:33	72.76	OK	5100	2026-09-13 23:34	71.71	OK
5101	2026-09-13 23:35	71.09	OK	5102	2026-09-13 23:36	71.29	OK
5103	2026-09-13 23:37	73.44	OK	5104	2026-09-13 23:38	73.14	OK
5105	2026-09-13 23:39	71.79	OK	5106	2026-09-13 23:40	71.40	OK
5107	2026-09-13 23:41	70.67	OK	5108	2026-09-13 23:42	73.60	OK
5109	2026-09-13 23:43	74.50	OK	5110	2026-09-13 23:44	72.15	OK
5111	2026-09-13 23:45	74.96	OK	5112	2026-09-13 23:46	71.84	OK
5113	2026-09-13 23:47	70.82	OK	5114	2026-09-13 23:48	72.15	OK
5115	2026-09-13 23:49	74.71	OK	5116	2026-09-13 23:50	71.06	OK
5117	2026-09-13 23:51	69.38	OK	5118	2026-09-13 23:52	72.36	OK
5119	2026-09-13 23:53	69.94	OK	5120	2026-09-13 23:54	70.60	OK
5121	2026-09-13 23:55	70.72	OK	5122	2026-09-13 23:56	74.55	OK
5123	2026-09-13 23:57	74.13	OK	5124	2026-09-13 23:58	71.15	OK
5125	2026-09-13 23:59	71.56	OK	5126	2026-09-14 00:00	70.98	OK
5127	2026-09-14 00:01	70.66	OK	5128	2026-09-14 00:02	74.23	OK
5129	2026-09-14 00:03	71.53	OK	5130	2026-09-14 00:04	71.02	OK
5131	2026-09-14 00:05	69.47	OK	5132	2026-09-14 00:06	71.60	OK
5133	2026-09-14 00:07	72.12	OK	5134	2026-09-14 00:08	71.43	OK
5135	2026-09-14 00:09	70.81	OK	5136	2026-09-14 00:10	72.16	OK
5137	2026-09-14 00:11	69.54	OK	5138	2026-09-14 00:12	72.36	OK
5139	2026-09-14 00:13	73.18	OK	5140	2026-09-14 00:14	70.63	OK
5141	2026-09-14 00:15	72.28	OK	5142	2026-09-14 00:16	73.79	OK
5143	2026-09-14 00:17	71.85	OK	5144	2026-09-14 00:18	73.10	OK
5145	2026-09-14 00:19	73.05	OK	5146	2026-09-14 00:20	70.53	OK
5147	2026-09-14 00:21	73.01	OK	5148	2026-09-14 00:22	69.64	OK
5149	2026-09-14 00:23	70.43	OK	5150	2026-09-14 00:24	70.86	OK
5151	2026-09-14 00:25	74.06	OK	5152	2026-09-14 00:26	72.63	OK
5153	2026-09-14 00:27	72.92	OK	5154	2026-09-14 00:28	69.92	OK
5155	2026-09-14 00:29	71.86	OK	5156	2026-09-14 00:30	71.92	OK
5157	2026-09-14 00:31	70.27	OK	5158	2026-09-14 00:32	72.25	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5159	2026-09-14 00:33	74.04	OK	5160	2026-09-14 00:34	73.28	OK
5161	2026-09-14 00:35	72.74	OK	5162	2026-09-14 00:36	69.92	OK
5163	2026-09-14 00:37	70.06	OK	5164	2026-09-14 00:38	72.12	OK
5165	2026-09-14 00:39	71.13	OK	5166	2026-09-14 00:40	72.62	OK
5167	2026-09-14 00:41	73.79	OK	5168	2026-09-14 00:42	74.47	OK
5169	2026-09-14 00:43	69.39	OK	5170	2026-09-14 00:44	70.68	OK
5171	2026-09-14 00:45	71.75	OK	5172	2026-09-14 00:46	70.74	OK
5173	2026-09-14 00:47	70.42	OK	5174	2026-09-14 00:48	72.31	OK
5175	2026-09-14 00:49	72.78	OK	5176	2026-09-14 00:50	69.75	OK
5177	2026-09-14 00:51	69.74	OK	5178	2026-09-14 00:52	72.36	OK
5179	2026-09-14 00:53	70.74	OK	5180	2026-09-14 00:54	71.66	OK
5181	2026-09-14 00:55	72.07	OK	5182	2026-09-14 00:56	71.45	OK
5183	2026-09-14 00:57	74.19	OK	5184	2026-09-14 00:58	71.64	OK
5185	2026-09-14 00:59	69.34	OK	5186	2026-09-14 01:00	72.16	OK
5187	2026-09-14 01:01	71.60	OK	5188	2026-09-14 01:02	70.57	OK
5189	2026-09-14 01:03	69.93	OK	5190	2026-09-14 01:04	71.93	OK
5191	2026-09-14 01:05	70.29	OK	5192	2026-09-14 01:06	73.27	OK
5193	2026-09-14 01:07	71.18	OK	5194	2026-09-14 01:08	71.10	OK
5195	2026-09-14 01:09	70.57	OK	5196	2026-09-14 01:10	68.80	OK
5197	2026-09-14 01:11	71.95	OK	5198	2026-09-14 01:12	70.71	OK
5199	2026-09-14 01:13	70.20	OK	5200	2026-09-14 01:14	71.10	OK
5201	2026-09-14 01:15	71.26	OK	5202	2026-09-14 01:16	71.36	OK
5203	2026-09-14 01:17	70.09	OK	5204	2026-09-14 01:18	72.29	OK
5205	2026-09-14 01:19	71.27	OK	5206	2026-09-14 01:20	72.09	OK
5207	2026-09-14 01:21	70.82	OK	5208	2026-09-14 01:22	71.14	OK
5209	2026-09-14 01:23	70.97	OK	5210	2026-09-14 01:24	69.76	OK
5211	2026-09-14 01:25	71.89	OK	5212	2026-09-14 01:26	71.84	OK
5213	2026-09-14 01:27	69.41	OK	5214	2026-09-14 01:28	68.83	OK
5215	2026-09-14 01:29	69.95	OK	5216	2026-09-14 01:30	69.95	OK
5217	2026-09-14 01:31	71.74	OK	5218	2026-09-14 01:32	70.95	OK
5219	2026-09-14 01:33	70.34	OK	5220	2026-09-14 01:34	71.78	OK
5221	2026-09-14 01:35	69.75	OK	5222	2026-09-14 01:36	69.63	OK
5223	2026-09-14 01:37	71.01	OK	5224	2026-09-14 01:38	70.07	OK
5225	2026-09-14 01:39	70.64	OK	5226	2026-09-14 01:40	71.00	OK
5227	2026-09-14 01:41	70.28	OK	5228	2026-09-14 01:42	70.07	OK
5229	2026-09-14 01:43	72.38	OK	5230	2026-09-14 01:44	69.73	OK
5231	2026-09-14 01:45	70.25	OK	5232	2026-09-14 01:46	71.24	OK
5233	2026-09-14 01:47	70.27	OK	5234	2026-09-14 01:48	72.32	OK
5235	2026-09-14 01:49	67.42	OK	5236	2026-09-14 01:50	71.76	OK
5237	2026-09-14 01:51	70.89	OK	5238	2026-09-14 01:52	70.20	OK
5239	2026-09-14 01:53	72.98	OK	5240	2026-09-14 01:54	70.41	OK
5241	2026-09-14 01:55	72.53	OK	5242	2026-09-14 01:56	68.64	OK
5243	2026-09-14 01:57	70.37	OK	5244	2026-09-14 01:58	68.98	OK
5245	2026-09-14 01:59	71.87	OK	5246	2026-09-14 02:00	69.28	OK
5247	2026-09-14 02:01	72.85	OK	5248	2026-09-14 02:02	69.79	OK
5249	2026-09-14 02:03	71.49	OK	5250	2026-09-14 02:04	70.41	OK
5251	2026-09-14 02:05	70.44	OK	5252	2026-09-14 02:06	70.00	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5253	2026-09-14 02:07	70.69	OK	5254	2026-09-14 02:08	71.78	OK
5255	2026-09-14 02:09	70.11	OK	5256	2026-09-14 02:10	71.71	OK
5257	2026-09-14 02:11	68.16	OK	5258	2026-09-14 02:12	71.20	OK
5259	2026-09-14 02:13	71.89	OK	5260	2026-09-14 02:14	69.20	OK
5261	2026-09-14 02:15	68.34	OK	5262	2026-09-14 02:16	70.82	OK
5263	2026-09-14 02:17	69.35	OK	5264	2026-09-14 02:18	70.53	OK
5265	2026-09-14 02:19	72.50	OK	5266	2026-09-14 02:20	70.92	OK
5267	2026-09-14 02:21	70.57	OK	5268	2026-09-14 02:22	68.69	OK
5269	2026-09-14 02:23	69.32	OK	5270	2026-09-14 02:24	72.64	OK
5271	2026-09-14 02:25	69.59	OK	5272	2026-09-14 02:26	68.43	OK
5273	2026-09-14 02:27	70.17	OK	5274	2026-09-14 02:28	68.85	OK
5275	2026-09-14 02:29	70.86	OK	5276	2026-09-14 02:30	68.10	OK
5277	2026-09-14 02:31	70.40	OK	5278	2026-09-14 02:32	69.98	OK
5279	2026-09-14 02:33	71.79	OK	5280	2026-09-14 02:34	68.89	OK
5281	2026-09-14 02:35	68.38	OK	5282	2026-09-14 02:36	68.81	OK
5283	2026-09-14 02:37	68.75	OK	5284	2026-09-14 02:38	70.16	OK
5285	2026-09-14 02:39	70.40	OK	5286	2026-09-14 02:40	68.74	OK
5287	2026-09-14 02:41	70.76	OK	5288	2026-09-14 02:42	68.48	OK
5289	2026-09-14 02:43	71.44	OK	5290	2026-09-14 02:44	71.30	OK
5291	2026-09-14 02:45	70.20	OK	5292	2026-09-14 02:46	69.94	OK
5293	2026-09-14 02:47	70.73	OK	5294	2026-09-14 02:48	68.30	OK
5295	2026-09-14 02:49	69.69	OK	5296	2026-09-14 02:50	68.42	OK
5297	2026-09-14 02:51	72.51	OK	5298	2026-09-14 02:52	68.82	OK
5299	2026-09-14 02:53	69.21	OK	5300	2026-09-14 02:54	69.09	OK
5301	2026-09-14 02:55	67.99	OK	5302	2026-09-14 02:56	70.34	OK
5303	2026-09-14 02:57	68.58	OK	5304	2026-09-14 02:58	68.14	OK
5305	2026-09-14 02:59	67.57	OK	5306	2026-09-14 03:00	67.82	OK
5307	2026-09-14 03:01	68.89	OK	5308	2026-09-14 03:02	67.01	OK
5309	2026-09-14 03:03	70.44	OK	5310	2026-09-14 03:04	66.13	OK
5311	2026-09-14 03:05	66.84	OK	5312	2026-09-14 03:06	69.92	OK
5313	2026-09-14 03:07	69.11	OK	5314	2026-09-14 03:08	66.54	OK
5315	2026-09-14 03:09	68.24	OK	5316	2026-09-14 03:10	67.55	OK
5317	2026-09-14 03:11	69.52	OK	5318	2026-09-14 03:12	69.10	OK
5319	2026-09-14 03:13	69.81	OK	5320	2026-09-14 03:14	67.32	OK
5321	2026-09-14 03:15	70.10	OK	5322	2026-09-14 03:16	69.51	OK
5323	2026-09-14 03:17	66.74	OK	5324	2026-09-14 03:18	67.60	OK
5325	2026-09-14 03:19	68.46	OK	5326	2026-09-14 03:20	70.38	OK
5327	2026-09-14 03:21	69.90	OK	5328	2026-09-14 03:22	69.69	OK
5329	2026-09-14 03:23	68.33	OK	5330	2026-09-14 03:24	67.55	OK
5331	2026-09-14 03:25	69.16	OK	5332	2026-09-14 03:26	71.30	OK
5333	2026-09-14 03:27	67.05	OK	5334	2026-09-14 03:28	67.07	OK
5335	2026-09-14 03:29	69.62	OK	5336	2026-09-14 03:30	67.84	OK
5337	2026-09-14 03:31	69.00	OK	5338	2026-09-14 03:32	67.57	OK
5339	2026-09-14 03:33	69.33	OK	5340	2026-09-14 03:34	67.70	OK
5341	2026-09-14 03:35	68.21	OK	5342	2026-09-14 03:36	69.64	OK
5343	2026-09-14 03:37	69.76	OK	5344	2026-09-14 03:38	66.75	OK
5345	2026-09-14 03:39	68.68	OK	5346	2026-09-14 03:40	69.27	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5347	2026-09-14 03:41	69.16	OK	5348	2026-09-14 03:42	65.84	OK
5349	2026-09-14 03:43	66.41	OK	5350	2026-09-14 03:44	65.08	OK
5351	2026-09-14 03:45	69.52	OK	5352	2026-09-14 03:46	68.78	OK
5353	2026-09-14 03:47	67.52	OK	5354	2026-09-14 03:48	69.60	OK
5355	2026-09-14 03:49	66.76	OK	5356	2026-09-14 03:50	67.49	OK
5357	2026-09-14 03:51	68.09	OK	5358	2026-09-14 03:52	66.49	OK
5359	2026-09-14 03:53	67.41	OK	5360	2026-09-14 03:54	67.48	OK
5361	2026-09-14 03:55	66.48	OK	5362	2026-09-14 03:56	67.66	OK
5363	2026-09-14 03:57	66.33	OK	5364	2026-09-14 03:58	66.95	OK
5365	2026-09-14 03:59	67.28	OK	5366	2026-09-14 04:00	66.89	OK
5367	2026-09-14 04:01	65.34	OK	5368	2026-09-14 04:02	67.45	OK
5369	2026-09-14 04:03	67.21	OK	5370	2026-09-14 04:04	68.62	OK
5371	2026-09-14 04:05	65.70	OK	5372	2026-09-14 04:06	67.41	OK
5373	2026-09-14 04:07	67.59	OK	5374	2026-09-14 04:08	64.05	OK
5375	2026-09-14 04:09	66.92	OK	5376	2026-09-14 04:10	66.01	OK
5377	2026-09-14 04:11	65.11	OK	5378	2026-09-14 04:12	67.44	OK
5379	2026-09-14 04:13	65.47	OK	5380	2026-09-14 04:14	67.96	OK
5381	2026-09-14 04:15	67.30	OK	5382	2026-09-14 04:16	66.80	OK
5383	2026-09-14 04:17	68.57	OK	5384	2026-09-14 04:18	65.13	OK
5385	2026-09-14 04:19	65.96	OK	5386	2026-09-14 04:20	67.10	OK
5387	2026-09-14 04:21	68.71	OK	5388	2026-09-14 04:22	66.51	OK
5389	2026-09-14 04:23	68.81	OK	5390	2026-09-14 04:24	64.84	OK
5391	2026-09-14 04:25	65.92	OK	5392	2026-09-14 04:26	67.21	OK
5393	2026-09-14 04:27	67.59	OK	5394	2026-09-14 04:28	68.22	OK
5395	2026-09-14 04:29	66.14	OK	5396	2026-09-14 04:30	64.15	OK
5397	2026-09-14 04:31	65.42	OK	5398	2026-09-14 04:32	66.92	OK
5399	2026-09-14 04:33	65.36	OK	5400	2026-09-14 04:34	65.10	OK
5401	2026-09-14 04:35	64.19	OK	5402	2026-09-14 04:36	67.63	OK
5403	2026-09-14 04:37	66.68	OK	5404	2026-09-14 04:38	64.26	OK
5405	2026-09-14 04:39	64.58	OK	5406	2026-09-14 04:40	66.01	OK
5407	2026-09-14 04:41	67.77	OK	5408	2026-09-14 04:42	63.95	OK
5409	2026-09-14 04:43	63.71	OK	5410	2026-09-14 04:44	66.46	OK
5411	2026-09-14 04:45	68.36	OK	5412	2026-09-14 04:46	65.25	OK
5413	2026-09-14 04:47	65.59	OK	5414	2026-09-14 04:48	65.00	OK
5415	2026-09-14 04:49	68.29	OK	5416	2026-09-14 04:50	65.96	OK
5417	2026-09-14 04:51	66.97	OK	5418	2026-09-14 04:52	65.18	OK
5419	2026-09-14 04:53	65.30	OK	5420	2026-09-14 04:54	65.64	OK
5421	2026-09-14 04:55	64.41	OK	5422	2026-09-14 04:56	66.57	OK
5423	2026-09-14 04:57	66.10	OK	5424	2026-09-14 04:58	64.93	OK
5425	2026-09-14 04:59	65.50	OK	5426	2026-09-14 05:00	64.62	OK
5427	2026-09-14 05:01	63.70	OK	5428	2026-09-14 05:02	66.56	OK
5429	2026-09-14 05:03	65.72	OK	5430	2026-09-14 05:04	65.70	OK
5431	2026-09-14 05:05	66.23	OK	5432	2026-09-14 05:06	64.15	OK
5433	2026-09-14 05:07	66.25	OK	5434	2026-09-14 05:08	65.65	OK
5435	2026-09-14 05:09	65.74	OK	5436	2026-09-14 05:10	64.62	OK
5437	2026-09-14 05:11	62.61	OK	5438	2026-09-14 05:12	66.50	OK
5439	2026-09-14 05:13	67.21	OK	5440	2026-09-14 05:14	64.49	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5441	2026-09-14 05:15	65.72	OK	5442	2026-09-14 05:16	65.15	OK
5443	2026-09-14 05:17	65.29	OK	5444	2026-09-14 05:18	65.79	OK
5445	2026-09-14 05:19	65.71	OK	5446	2026-09-14 05:20	64.73	OK
5447	2026-09-14 05:21	66.87	OK	5448	2026-09-14 05:22	66.38	OK
5449	2026-09-14 05:23	63.66	OK	5450	2026-09-14 05:24	65.90	OK
5451	2026-09-14 05:25	65.19	OK	5452	2026-09-14 05:26	66.78	OK
5453	2026-09-14 05:27	63.14	OK	5454	2026-09-14 05:28	64.30	OK
5455	2026-09-14 05:29	64.48	OK	5456	2026-09-14 05:30	63.48	OK
5457	2026-09-14 05:31	63.94	OK	5458	2026-09-14 05:32	66.30	OK
5459	2026-09-14 05:33	65.40	OK	5460	2026-09-14 05:34	66.03	OK
5461	2026-09-14 05:35	65.72	OK	5462	2026-09-14 05:36	66.26	OK
5463	2026-09-14 05:37	62.86	OK	5464	2026-09-14 05:38	62.55	OK
5465	2026-09-14 05:39	64.98	OK	5466	2026-09-14 05:40	63.64	OK
5467	2026-09-14 05:41	64.78	OK	5468	2026-09-14 05:42	63.49	OK
5469	2026-09-14 05:43	64.00	OK	5470	2026-09-14 05:44	62.99	OK
5471	2026-09-14 05:45	67.24	OK	5472	2026-09-14 05:46	63.23	OK
5473	2026-09-14 05:47	65.65	OK	5474	2026-09-14 05:48	64.18	OK
5475	2026-09-14 05:49	63.20	OK	5476	2026-09-14 05:50	64.36	OK
5477	2026-09-14 05:51	62.44	OK	5478	2026-09-14 05:52	63.27	OK
5479	2026-09-14 05:53	62.35	OK	5480	2026-09-14 05:54	62.72	OK
5481	2026-09-14 05:55	64.88	OK	5482	2026-09-14 05:56	63.94	OK
5483	2026-09-14 05:57	64.85	OK	5484	2026-09-14 05:58	66.01	OK
5485	2026-09-14 05:59	65.73	OK	5486	2026-09-14 06:00	63.77	OK
5487	2026-09-14 06:01	63.20	OK	5488	2026-09-14 06:02	64.58	OK
5489	2026-09-14 06:03	64.29	OK	5490	2026-09-14 06:04	63.72	OK
5491	2026-09-14 06:05	64.28	OK	5492	2026-09-14 06:06	63.46	OK
5493	2026-09-14 06:07	64.11	OK	5494	2026-09-14 06:08	62.79	OK
5495	2026-09-14 06:09	63.16	OK	5496	2026-09-14 06:10	63.62	OK
5497	2026-09-14 06:11	62.99	OK	5498	2026-09-14 06:12	64.56	OK
5499	2026-09-14 06:13	63.54	OK	5500	2026-09-14 06:14	60.27	OK
5501	2026-09-14 06:15	65.47	OK	5502	2026-09-14 06:16	65.61	OK
5503	2026-09-14 06:17	63.62	OK	5504	2026-09-14 06:18	64.82	OK
5505	2026-09-14 06:19	63.69	OK	5506	2026-09-14 06:20	66.00	OK
5507	2026-09-14 06:21	62.86	OK	5508	2026-09-14 06:22	65.66	OK
5509	2026-09-14 06:23	65.04	OK	5510	2026-09-14 06:24	62.18	OK
5511	2026-09-14 06:25	62.87	OK	5512	2026-09-14 06:26	62.58	OK
5513	2026-09-14 06:27	62.68	OK	5514	2026-09-14 06:28	61.94	OK
5515	2026-09-14 06:29	62.45	OK	5516	2026-09-14 06:30	63.45	OK
5517	2026-09-14 06:31	61.22	OK	5518	2026-09-14 06:32	61.79	OK
5519	2026-09-14 06:33	62.51	OK	5520	2026-09-14 06:34	63.07	OK
5521	2026-09-14 06:35	62.82	OK	5522	2026-09-14 06:36	62.82	OK
5523	2026-09-14 06:37	63.17	OK	5524	2026-09-14 06:38	61.13	OK
5525	2026-09-14 06:39	62.87	OK	5526	2026-09-14 06:40	63.27	OK
5527	2026-09-14 06:41	61.97	OK	5528	2026-09-14 06:42	62.14	OK
5529	2026-09-14 06:43	64.52	OK	5530	2026-09-14 06:44	61.78	OK
5531	2026-09-14 06:45	63.28	OK	5532	2026-09-14 06:46	66.00	OK
5533	2026-09-14 06:47	62.94	OK	5534	2026-09-14 06:48	63.15	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5535	2026-09-14 06:49	64.08	OK	5536	2026-09-14 06:50	64.21	OK
5537	2026-09-14 06:51	61.85	OK	5538	2026-09-14 06:52	63.04	OK
5539	2026-09-14 06:53	62.40	OK	5540	2026-09-14 06:54	62.68	OK
5541	2026-09-14 06:55	64.45	OK	5542	2026-09-14 06:56	62.53	OK
5543	2026-09-14 06:57	63.49	OK	5544	2026-09-14 06:58	62.70	OK
5545	2026-09-14 06:59	61.91	OK	5546	2026-09-14 07:00	63.38	OK
5547	2026-09-14 07:01	62.78	OK	5548	2026-09-14 07:02	62.15	OK
5549	2026-09-14 07:03	64.06	OK	5550	2026-09-14 07:04	64.33	OK
5551	2026-09-14 07:05	62.77	OK	5552	2026-09-14 07:06	61.38	OK
5553	2026-09-14 07:07	63.73	OK	5554	2026-09-14 07:08	61.44	OK
5555	2026-09-14 07:09	63.00	OK	5556	2026-09-14 07:10	62.73	OK
5557	2026-09-14 07:11	62.59	OK	5558	2026-09-14 07:12	63.48	OK
5559	2026-09-14 07:13	60.59	OK	5560	2026-09-14 07:14	60.53	OK
5561	2026-09-14 07:15	60.98	OK	5562	2026-09-14 07:16	61.42	OK
5563	2026-09-14 07:17	61.44	OK	5564	2026-09-14 07:18	62.49	OK
5565	2026-09-14 07:19	63.66	OK	5566	2026-09-14 07:20	61.62	OK
5567	2026-09-14 07:21	62.97	OK	5568	2026-09-14 07:22	61.40	OK
5569	2026-09-14 07:23	61.50	OK	5570	2026-09-14 07:24	61.16	OK
5571	2026-09-14 07:25	62.73	OK	5572	2026-09-14 07:26	62.77	OK
5573	2026-09-14 07:27	58.68	OK	5574	2026-09-14 07:28	61.11	OK
5575	2026-09-14 07:29	62.27	OK	5576	2026-09-14 07:30	63.61	OK
5577	2026-09-14 07:31	59.65	OK	5578	2026-09-14 07:32	62.03	OK
5579	2026-09-14 07:33	63.20	OK	5580	2026-09-14 07:34	59.86	OK
5581	2026-09-14 07:35	62.41	OK	5582	2026-09-14 07:36	62.88	OK
5583	2026-09-14 07:37	59.78	OK	5584	2026-09-14 07:38	60.95	OK
5585	2026-09-14 07:39	62.61	OK	5586	2026-09-14 07:40	60.30	OK
5587	2026-09-14 07:41	61.02	OK	5588	2026-09-14 07:42	61.39	OK
5589	2026-09-14 07:43	61.84	OK	5590	2026-09-14 07:44	59.56	OK
5591	2026-09-14 07:45	60.38	OK	5592	2026-09-14 07:46	59.74	OK
5593	2026-09-14 07:47	59.28	OK	5594	2026-09-14 07:48	62.02	OK
5595	2026-09-14 07:49	62.70	OK	5596	2026-09-14 07:50	61.69	OK
5597	2026-09-14 07:51	61.53	OK	5598	2026-09-14 07:52	59.96	OK
5599	2026-09-14 07:53	62.08	OK	5600	2026-09-14 07:54	62.54	OK
5601	2026-09-14 07:55	58.75	OK	5602	2026-09-14 07:56	58.84	OK
5603	2026-09-14 07:57	61.70	OK	5604	2026-09-14 07:58	61.33	OK
5605	2026-09-14 07:59	60.36	OK	5606	2026-09-14 08:00	63.49	OK
5607	2026-09-14 08:01	60.95	OK	5608	2026-09-14 08:02	61.92	OK
5609	2026-09-14 08:03	60.40	OK	5610	2026-09-14 08:04	63.18	OK
5611	2026-09-14 08:05	62.95	OK	5612	2026-09-14 08:06	60.03	OK
5613	2026-09-14 08:07	62.30	OK	5614	2026-09-14 08:08	59.16	OK
5615	2026-09-14 08:09	60.67	OK	5616	2026-09-14 08:10	61.31	OK
5617	2026-09-14 08:11	58.26	OK	5618	2026-09-14 08:12	60.41	OK
5619	2026-09-14 08:13	60.93	OK	5620	2026-09-14 08:14	60.78	OK
5621	2026-09-14 08:15	61.54	OK	5622	2026-09-14 08:16	57.58	OK
5623	2026-09-14 08:17	60.89	OK	5624	2026-09-14 08:18	62.18	OK
5625	2026-09-14 08:19	60.15	OK	5626	2026-09-14 08:20	61.65	OK
5627	2026-09-14 08:21	62.40	OK	5628	2026-09-14 08:22	62.13	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5629	2026-09-14 08:23	62.10	OK	5630	2026-09-14 08:24	62.67	OK
5631	2026-09-14 08:25	60.85	OK	5632	2026-09-14 08:26	61.96	OK
5633	2026-09-14 08:27	59.32	OK	5634	2026-09-14 08:28	60.51	OK
5635	2026-09-14 08:29	60.37	OK	5636	2026-09-14 08:30	62.95	OK
5637	2026-09-14 08:31	59.51	OK	5638	2026-09-14 08:32	60.95	OK
5639	2026-09-14 08:33	59.80	OK	5640	2026-09-14 08:34	60.60	OK
5641	2026-09-14 08:35	61.83	OK	5642	2026-09-14 08:36	61.09	OK
5643	2026-09-14 08:37	59.80	OK	5644	2026-09-14 08:38	60.76	OK
5645	2026-09-14 08:39	61.39	OK	5646	2026-09-14 08:40	60.55	OK
5647	2026-09-14 08:41	59.75	OK	5648	2026-09-14 08:42	61.35	OK
5649	2026-09-14 08:43	60.41	OK	5650	2026-09-14 08:44	58.99	OK
5651	2026-09-14 08:45	58.80	OK	5652	2026-09-14 08:46	58.64	OK
5653	2026-09-14 08:47	62.11	OK	5654	2026-09-14 08:48	61.31	OK
5655	2026-09-14 08:49	61.31	OK	5656	2026-09-14 08:50	61.07	OK
5657	2026-09-14 08:51	60.21	OK	5658	2026-09-14 08:52	61.58	OK
5659	2026-09-14 08:53	60.08	OK	5660	2026-09-14 08:54	62.82	OK
5661	2026-09-14 08:55	59.28	OK	5662	2026-09-14 08:56	58.70	OK
5663	2026-09-14 08:57	59.05	OK	5664	2026-09-14 08:58	58.80	OK
5665	2026-09-14 08:59	58.91	OK	5666	2026-09-14 09:00	60.30	OK
5667	2026-09-14 09:01	60.15	OK	5668	2026-09-14 09:02	62.78	OK
5669	2026-09-14 09:03	61.11	OK	5670	2026-09-14 09:04	58.84	OK
5671	2026-09-14 09:05	61.61	OK	5672	2026-09-14 09:06	60.33	OK
5673	2026-09-14 09:07	59.49	OK	5674	2026-09-14 09:08	57.94	OK
5675	2026-09-14 09:09	60.54	OK	5676	2026-09-14 09:10	59.44	OK
5677	2026-09-14 09:11	57.47	OK	5678	2026-09-14 09:12	59.99	OK
5679	2026-09-14 09:13	62.86	OK	5680	2026-09-14 09:14	58.80	OK
5681	2026-09-14 09:15	58.81	OK	5682	2026-09-14 09:16	59.13	OK
5683	2026-09-14 09:17	59.39	OK	5684	2026-09-14 09:18	61.85	OK
5685	2026-09-14 09:19	60.25	OK	5686	2026-09-14 09:20	60.81	OK
5687	2026-09-14 09:21	60.37	OK	5688	2026-09-14 09:22	60.01	OK
5689	2026-09-14 09:23	60.38	OK	5690	2026-09-14 09:24	60.02	OK
5691	2026-09-14 09:25	58.80	OK	5692	2026-09-14 09:26	59.25	OK
5693	2026-09-14 09:27	58.49	OK	5694	2026-09-14 09:28	61.02	OK
5695	2026-09-14 09:29	59.64	OK	5696	2026-09-14 09:30	60.68	OK
5697	2026-09-14 09:31	60.31	OK	5698	2026-09-14 09:32	60.79	OK
5699	2026-09-14 09:33	59.87	OK	5700	2026-09-14 09:34	60.25	OK
5701	2026-09-14 09:35	59.58	OK	5702	2026-09-14 09:36	60.47	OK
5703	2026-09-14 09:37	59.39	OK	5704	2026-09-14 09:38	59.29	OK
5705	2026-09-14 09:39	60.69	OK	5706	2026-09-14 09:40	58.86	OK
5707	2026-09-14 09:41	60.07	OK	5708	2026-09-14 09:42	60.37	OK
5709	2026-09-14 09:43	60.26	OK	5710	2026-09-14 09:44	58.52	OK
5711	2026-09-14 09:45	58.88	OK	5712	2026-09-14 09:46	59.37	OK
5713	2026-09-14 09:47	58.62	OK	5714	2026-09-14 09:48	58.59	OK
5715	2026-09-14 09:49	60.13	OK	5716	2026-09-14 09:50	60.00	OK
5717	2026-09-14 09:51	60.70	OK	5718	2026-09-14 09:52	59.73	OK
5719	2026-09-14 09:53	59.75	OK	5720	2026-09-14 09:54	61.28	OK
5721	2026-09-14 09:55	62.08	OK	5722	2026-09-14 09:56	60.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5723	2026-09-14 09:57	57.76	OK	5724	2026-09-14 09:58	58.81	OK
5725	2026-09-14 09:59	58.53	OK	5726	2026-09-14 10:00	57.47	OK
5727	2026-09-14 10:01	60.41	OK	5728	2026-09-14 10:02	60.64	OK
5729	2026-09-14 10:03	58.48	OK	5730	2026-09-14 10:04	59.22	OK
5731	2026-09-14 10:05	59.38	OK	5732	2026-09-14 10:06	61.92	OK
5733	2026-09-14 10:07	60.44	OK	5734	2026-09-14 10:08	60.21	OK
5735	2026-09-14 10:09	59.61	OK	5736	2026-09-14 10:10	58.72	OK
5737	2026-09-14 10:11	61.32	OK	5738	2026-09-14 10:12	58.15	OK
5739	2026-09-14 10:13	59.33	OK	5740	2026-09-14 10:14	59.16	OK
5741	2026-09-14 10:15	58.56	OK	5742	2026-09-14 10:16	58.86	OK
5743	2026-09-14 10:17	58.42	OK	5744	2026-09-14 10:18	59.42	OK
5745	2026-09-14 10:19	61.01	OK	5746	2026-09-14 10:20	57.96	OK
5747	2026-09-14 10:21	58.66	OK	5748	2026-09-14 10:22	60.78	OK
5749	2026-09-14 10:23	59.81	OK	5750	2026-09-14 10:24	58.32	OK
5751	2026-09-14 10:25	59.04	OK	5752	2026-09-14 10:26	60.47	OK
5753	2026-09-14 10:27	60.66	OK	5754	2026-09-14 10:28	58.75	OK
5755	2026-09-14 10:29	61.84	OK	5756	2026-09-14 10:30	58.70	OK
5757	2026-09-14 10:31	60.29	OK	5758	2026-09-14 10:32	58.80	OK
5759	2026-09-14 10:33	60.12	OK	5760	2026-09-14 10:34	58.31	OK
5761	2026-09-14 10:35	58.66	OK	5762	2026-09-14 10:36	59.39	OK
5763	2026-09-14 10:37	59.36	OK	5764	2026-09-14 10:38	59.70	OK
5765	2026-09-14 10:39	56.63	OK	5766	2026-09-14 10:40	60.61	OK
5767	2026-09-14 10:41	61.39	OK	5768	2026-09-14 10:42	59.35	OK
5769	2026-09-14 10:43	57.02	OK	5770	2026-09-14 10:44	59.98	OK
5771	2026-09-14 10:45	58.72	OK	5772	2026-09-14 10:46	57.87	OK
5773	2026-09-14 10:47	61.26	OK	5774	2026-09-14 10:48	59.36	OK
5775	2026-09-14 10:49	60.10	OK	5776	2026-09-14 10:50	60.62	OK
5777	2026-09-14 10:51	61.17	OK	5778	2026-09-14 10:52	59.62	OK
5779	2026-09-14 10:53	59.49	OK	5780	2026-09-14 10:54	59.22	OK
5781	2026-09-14 10:55	59.87	OK	5782	2026-09-14 10:56	57.82	OK
5783	2026-09-14 10:57	60.73	OK	5784	2026-09-14 10:58	57.33	OK
5785	2026-09-14 10:59	60.73	OK	5786	2026-09-14 11:00	60.99	OK
5787	2026-09-14 11:01	61.30	OK	5788	2026-09-14 11:02	58.59	OK
5789	2026-09-14 11:03	58.12	OK	5790	2026-09-14 11:04	59.52	OK
5791	2026-09-14 11:05	60.90	OK	5792	2026-09-14 11:06	57.73	OK
5793	2026-09-14 11:07	60.03	OK	5794	2026-09-14 11:08	61.41	OK
5795	2026-09-14 11:09	57.13	OK	5796	2026-09-14 11:10	61.43	OK
5797	2026-09-14 11:11	59.72	OK	5798	2026-09-14 11:12	59.28	OK
5799	2026-09-14 11:13	59.46	OK	5800	2026-09-14 11:14	58.26	OK
5801	2026-09-14 11:15	58.85	OK	5802	2026-09-14 11:16	58.80	OK
5803	2026-09-14 11:17	59.29	OK	5804	2026-09-14 11:18	59.89	OK
5805	2026-09-14 11:19	60.50	OK	5806	2026-09-14 11:20	59.96	OK
5807	2026-09-14 11:21	59.09	OK	5808	2026-09-14 11:22	57.52	OK
5809	2026-09-14 11:23	62.08	OK	5810	2026-09-14 11:24	59.42	OK
5811	2026-09-14 11:25	59.01	OK	5812	2026-09-14 11:26	59.17	OK
5813	2026-09-14 11:27	60.38	OK	5814	2026-09-14 11:28	58.75	OK
5815	2026-09-14 11:29	60.56	OK	5816	2026-09-14 11:30	59.49	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5817	2026-09-14 11:31	62.43	OK	5818	2026-09-14 11:32	58.62	OK
5819	2026-09-14 11:33	59.78	OK	5820	2026-09-14 11:34	56.68	OK
5821	2026-09-14 11:35	59.05	OK	5822	2026-09-14 11:36	58.82	OK
5823	2026-09-14 11:37	58.90	OK	5824	2026-09-14 11:38	57.61	OK
5825	2026-09-14 11:39	59.43	OK	5826	2026-09-14 11:40	58.68	OK
5827	2026-09-14 11:41	59.84	OK	5828	2026-09-14 11:42	60.20	OK
5829	2026-09-14 11:43	59.99	OK	5830	2026-09-14 11:44	59.25	OK
5831	2026-09-14 11:45	59.40	OK	5832	2026-09-14 11:46	60.07	OK
5833	2026-09-14 11:47	59.74	OK	5834	2026-09-14 11:48	61.24	OK
5835	2026-09-14 11:49	59.99	OK	5836	2026-09-14 11:50	58.93	OK
5837	2026-09-14 11:51	58.81	OK	5838	2026-09-14 11:52	58.69	OK
5839	2026-09-14 11:53	58.96	OK	5840	2026-09-14 11:54	57.18	OK
5841	2026-09-14 11:55	58.25	OK	5842	2026-09-14 11:56	59.39	OK
5843	2026-09-14 11:57	59.44	OK	5844	2026-09-14 11:58	59.68	OK
5845	2026-09-14 11:59	58.92	OK	5846	2026-09-14 12:00	60.87	OK
5847	2026-09-14 12:01	59.11	OK	5848	2026-09-14 12:02	58.77	OK
5849	2026-09-14 12:03	58.55	OK	5850	2026-09-14 12:04	57.73	OK
5851	2026-09-14 12:05	59.97	OK	5852	2026-09-14 12:06	58.96	OK
5853	2026-09-14 12:07	61.33	OK	5854	2026-09-14 12:08	60.33	OK
5855	2026-09-14 12:09	60.81	OK	5856	2026-09-14 12:10	60.07	OK
5857	2026-09-14 12:11	58.23	OK	5858	2026-09-14 12:12	61.41	OK
5859	2026-09-14 12:13	60.14	OK	5860	2026-09-14 12:14	60.51	OK
5861	2026-09-14 12:15	60.28	OK	5862	2026-09-14 12:16	60.70	OK
5863	2026-09-14 12:17	59.90	OK	5864	2026-09-14 12:18	59.22	OK
5865	2026-09-14 12:19	58.29	OK	5866	2026-09-14 12:20	61.72	OK
5867	2026-09-14 12:21	59.79	OK	5868	2026-09-14 12:22	59.44	OK
5869	2026-09-14 12:23	61.36	OK	5870	2026-09-14 12:24	58.59	OK
5871	2026-09-14 12:25	59.08	OK	5872	2026-09-14 12:26	59.45	OK
5873	2026-09-14 12:27	60.15	OK	5874	2026-09-14 12:28	61.83	OK
5875	2026-09-14 12:29	60.03	OK	5876	2026-09-14 12:30	59.29	OK
5877	2026-09-14 12:31	60.43	OK	5878	2026-09-14 12:32	60.05	OK
5879	2026-09-14 12:33	59.89	OK	5880	2026-09-14 12:34	60.00	OK
5881	2026-09-14 12:35	57.93	OK	5882	2026-09-14 12:36	60.13	OK
5883	2026-09-14 12:37	62.90	OK	5884	2026-09-14 12:38	59.02	OK
5885	2026-09-14 12:39	60.51	OK	5886	2026-09-14 12:40	59.27	OK
5887	2026-09-14 12:41	60.09	OK	5888	2026-09-14 12:42	60.58	OK
5889	2026-09-14 12:43	60.33	OK	5890	2026-09-14 12:44	61.98	OK
5891	2026-09-14 12:45	61.81	OK	5892	2026-09-14 12:46	60.14	OK
5893	2026-09-14 12:47	60.87	OK	5894	2026-09-14 12:48	57.82	OK
5895	2026-09-14 12:49	60.19	OK	5896	2026-09-14 12:50	59.68	OK
5897	2026-09-14 12:51	61.60	OK	5898	2026-09-14 12:52	62.19	OK
5899	2026-09-14 12:53	58.98	OK	5900	2026-09-14 12:54	61.78	OK
5901	2026-09-14 12:55	59.42	OK	5902	2026-09-14 12:56	59.20	OK
5903	2026-09-14 12:57	61.69	OK	5904	2026-09-14 12:58	60.39	OK
5905	2026-09-14 12:59	60.06	OK	5906	2026-09-14 13:00	59.95	OK
5907	2026-09-14 13:01	62.00	OK	5908	2026-09-14 13:02	59.91	OK
5909	2026-09-14 13:03	58.56	OK	5910	2026-09-14 13:04	60.70	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5911	2026-09-14 13:05	61.22	OK	5912	2026-09-14 13:06	61.56	OK
5913	2026-09-14 13:07	59.70	OK	5914	2026-09-14 13:08	61.46	OK
5915	2026-09-14 13:09	59.99	OK	5916	2026-09-14 13:10	59.42	OK
5917	2026-09-14 13:11	62.56	OK	5918	2026-09-14 13:12	59.15	OK
5919	2026-09-14 13:13	60.49	OK	5920	2026-09-14 13:14	59.99	OK
5921	2026-09-14 13:15	60.11	OK	5922	2026-09-14 13:16	60.31	OK
5923	2026-09-14 13:17	60.95	OK	5924	2026-09-14 13:18	64.07	OK
5925	2026-09-14 13:19	61.06	OK	5926	2026-09-14 13:20	58.32	OK
5927	2026-09-14 13:21	62.13	OK	5928	2026-09-14 13:22	61.48	OK
5929	2026-09-14 13:23	61.39	OK	5930	2026-09-14 13:24	61.18	OK
5931	2026-09-14 13:25	60.22	OK	5932	2026-09-14 13:26	59.04	OK
5933	2026-09-14 13:27	59.03	OK	5934	2026-09-14 13:28	60.65	OK
5935	2026-09-14 13:29	58.33	OK	5936	2026-09-14 13:30	63.03	OK
5937	2026-09-14 13:31	61.66	OK	5938	2026-09-14 13:32	61.63	OK
5939	2026-09-14 13:33	58.75	OK	5940	2026-09-14 13:34	62.61	OK
5941	2026-09-14 13:35	61.57	OK	5942	2026-09-14 13:36	59.72	OK
5943	2026-09-14 13:37	62.24	OK	5944	2026-09-14 13:38	60.64	OK
5945	2026-09-14 13:39	64.38	OK	5946	2026-09-14 13:40	63.58	OK
5947	2026-09-14 13:41	62.58	OK	5948	2026-09-14 13:42	63.13	OK
5949	2026-09-14 13:43	60.70	OK	5950	2026-09-14 13:44	59.92	OK
5951	2026-09-14 13:45	60.95	OK	5952	2026-09-14 13:46	60.73	OK
5953	2026-09-14 13:47	60.63	OK	5954	2026-09-14 13:48	62.33	OK
5955	2026-09-14 13:49	62.33	OK	5956	2026-09-14 13:50	62.09	OK
5957	2026-09-14 13:51	61.12	OK	5958	2026-09-14 13:52	62.24	OK
5959	2026-09-14 13:53	60.93	OK	5960	2026-09-14 13:54	62.46	OK
5961	2026-09-14 13:55	61.00	OK	5962	2026-09-14 13:56	59.95	OK
5963	2026-09-14 13:57	61.06	OK	5964	2026-09-14 13:58	60.67	OK
5965	2026-09-14 13:59	62.95	OK	5966	2026-09-14 14:00	59.58	OK
5967	2026-09-14 14:01	61.20	OK	5968	2026-09-14 14:02	60.78	OK
5969	2026-09-14 14:03	63.26	OK	5970	2026-09-14 14:04	62.90	OK
5971	2026-09-14 14:05	62.38	OK	5972	2026-09-14 14:06	61.65	OK
5973	2026-09-14 14:07	63.05	OK	5974	2026-09-14 14:08	62.31	OK
5975	2026-09-14 14:09	61.13	OK	5976	2026-09-14 14:10	61.49	OK
5977	2026-09-14 14:11	61.76	OK	5978	2026-09-14 14:12	62.57	OK
5979	2026-09-14 14:13	61.76	OK	5980	2026-09-14 14:14	61.45	OK
5981	2026-09-14 14:15	60.35	OK	5982	2026-09-14 14:16	62.77	OK
5983	2026-09-14 14:17	60.94	OK	5984	2026-09-14 14:18	59.84	OK
5985	2026-09-14 14:19	64.88	OK	5986	2026-09-14 14:20	64.71	OK
5987	2026-09-14 14:21	62.71	OK	5988	2026-09-14 14:22	62.13	OK
5989	2026-09-14 14:23	62.68	OK	5990	2026-09-14 14:24	60.17	OK
5991	2026-09-14 14:25	62.82	OK	5992	2026-09-14 14:26	60.52	OK
5993	2026-09-14 14:27	61.32	OK	5994	2026-09-14 14:28	62.70	OK
5995	2026-09-14 14:29	59.75	OK	5996	2026-09-14 14:30	60.19	OK
5997	2026-09-14 14:31	63.62	OK	5998	2026-09-14 14:32	60.68	OK
5999	2026-09-14 14:33	64.18	OK	6000	2026-09-14 14:34	62.12	OK
6001	2026-09-14 14:35	62.51	OK	6002	2026-09-14 14:36	61.16	OK
6003	2026-09-14 14:37	64.65	OK	6004	2026-09-14 14:38	65.65	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6005	2026-09-14 14:39	62.13	OK	6006	2026-09-14 14:40	61.44	OK
6007	2026-09-14 14:41	62.24	OK	6008	2026-09-14 14:42	62.60	OK
6009	2026-09-14 14:43	62.40	OK	6010	2026-09-14 14:44	63.30	OK
6011	2026-09-14 14:45	62.32	OK	6012	2026-09-14 14:46	63.69	OK
6013	2026-09-14 14:47	63.57	OK	6014	2026-09-14 14:48	64.68	OK
6015	2026-09-14 14:49	61.31	OK	6016	2026-09-14 14:50	60.86	OK
6017	2026-09-14 14:51	64.45	OK	6018	2026-09-14 14:52	65.79	OK
6019	2026-09-14 14:53	64.31	OK	6020	2026-09-14 14:54	63.90	OK
6021	2026-09-14 14:55	62.05	OK	6022	2026-09-14 14:56	64.76	OK
6023	2026-09-14 14:57	65.03	OK	6024	2026-09-14 14:58	63.70	OK
6025	2026-09-14 14:59	64.62	OK	6026	2026-09-14 15:00	62.85	OK
6027	2026-09-14 15:01	63.76	OK	6028	2026-09-14 15:02	63.48	OK
6029	2026-09-14 15:03	63.68	OK	6030	2026-09-14 15:04	62.00	OK
6031	2026-09-14 15:05	62.71	OK	6032	2026-09-14 15:06	64.83	OK
6033	2026-09-14 15:07	61.10	OK	6034	2026-09-14 15:08	60.85	OK
6035	2026-09-14 15:09	61.68	OK	6036	2026-09-14 15:10	65.29	OK
6037	2026-09-14 15:11	65.07	OK	6038	2026-09-14 15:12	63.33	OK
6039	2026-09-14 15:13	61.04	OK	6040	2026-09-14 15:14	63.73	OK
6041	2026-09-14 15:15	62.68	OK	6042	2026-09-14 15:16	64.57	OK
6043	2026-09-14 15:17	64.20	OK	6044	2026-09-14 15:18	63.81	OK
6045	2026-09-14 15:19	65.49	OK	6046	2026-09-14 15:20	64.43	OK
6047	2026-09-14 15:21	61.40	OK	6048	2026-09-14 15:22	61.27	OK
6049	2026-09-14 15:23	65.27	OK	6050	2026-09-14 15:24	63.48	OK
6051	2026-09-14 15:25	61.22	OK	6052	2026-09-14 15:26	63.49	OK
6053	2026-09-14 15:27	65.66	OK	6054	2026-09-14 15:28	65.92	OK
6055	2026-09-14 15:29	64.69	OK	6056	2026-09-14 15:30	63.75	OK
6057	2026-09-14 15:31	65.04	OK	6058	2026-09-14 15:32	65.54	OK
6059	2026-09-14 15:33	66.80	OK	6060	2026-09-14 15:34	62.70	OK
6061	2026-09-14 15:35	64.75	OK	6062	2026-09-14 15:36	64.78	OK
6063	2026-09-14 15:37	64.11	OK	6064	2026-09-14 15:38	64.58	OK
6065	2026-09-14 15:39	63.86	OK	6066	2026-09-14 15:40	63.10	OK
6067	2026-09-14 15:41	63.56	OK	6068	2026-09-14 15:42	62.52	OK
6069	2026-09-14 15:43	65.81	OK	6070	2026-09-14 15:44	63.60	OK
6071	2026-09-14 15:45	62.21	OK	6072	2026-09-14 15:46	63.14	OK
6073	2026-09-14 15:47	63.76	OK	6074	2026-09-14 15:48	63.21	OK
6075	2026-09-14 15:49	65.97	OK	6076	2026-09-14 15:50	62.61	OK
6077	2026-09-14 15:51	65.59	OK	6078	2026-09-14 15:52	63.42	OK
6079	2026-09-14 15:53	63.44	OK	6080	2026-09-14 15:54	65.97	OK
6081	2026-09-14 15:55	63.51	OK	6082	2026-09-14 15:56	64.00	OK
6083	2026-09-14 15:57	63.68	OK	6084	2026-09-14 15:58	66.64	OK
6085	2026-09-14 15:59	65.85	OK	6086	2026-09-14 16:00	67.42	OK
6087	2026-09-14 16:01	64.08	OK	6088	2026-09-14 16:02	65.80	OK
6089	2026-09-14 16:03	67.69	OK	6090	2026-09-14 16:04	63.39	OK
6091	2026-09-14 16:05	65.30	OK	6092	2026-09-14 16:06	65.78	OK
6093	2026-09-14 16:07	64.24	OK	6094	2026-09-14 16:08	65.22	OK
6095	2026-09-14 16:09	65.64	OK	6096	2026-09-14 16:10	65.16	OK
6097	2026-09-14 16:11	66.01	OK	6098	2026-09-14 16:12	62.92	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6099	2026-09-14 16:13	65.20	OK	6100	2026-09-14 16:14	64.47	OK
6101	2026-09-14 16:15	65.01	OK	6102	2026-09-14 16:16	64.33	OK
6103	2026-09-14 16:17	64.41	OK	6104	2026-09-14 16:18	66.04	OK
6105	2026-09-14 16:19	63.28	OK	6106	2026-09-14 16:20	65.78	OK
6107	2026-09-14 16:21	67.73	OK	6108	2026-09-14 16:22	66.89	OK
6109	2026-09-14 16:23	64.59	OK	6110	2026-09-14 16:24	64.56	OK
6111	2026-09-14 16:25	64.49	OK	6112	2026-09-14 16:26	63.33	OK
6113	2026-09-14 16:27	63.97	OK	6114	2026-09-14 16:28	66.78	OK
6115	2026-09-14 16:29	67.14	OK	6116	2026-09-14 16:30	68.06	OK
6117	2026-09-14 16:31	65.44	OK	6118	2026-09-14 16:32	66.88	OK
6119	2026-09-14 16:33	67.16	OK	6120	2026-09-14 16:34	65.96	OK
6121	2026-09-14 16:35	67.32	OK	6122	2026-09-14 16:36	66.89	OK
6123	2026-09-14 16:37	67.17	OK	6124	2026-09-14 16:38	64.49	OK
6125	2026-09-14 16:39	65.21	OK	6126	2026-09-14 16:40	66.28	OK
6127	2026-09-14 16:41	66.48	OK	6128	2026-09-14 16:42	65.10	OK
6129	2026-09-14 16:43	64.76	OK	6130	2026-09-14 16:44	64.89	OK
6131	2026-09-14 16:45	63.56	OK	6132	2026-09-14 16:46	66.93	OK
6133	2026-09-14 16:47	65.60	OK	6134	2026-09-14 16:48	66.80	OK
6135	2026-09-14 16:49	67.44	OK	6136	2026-09-14 16:50	66.30	OK
6137	2026-09-14 16:51	63.64	OK	6138	2026-09-14 16:52	65.26	OK
6139	2026-09-14 16:53	66.94	OK	6140	2026-09-14 16:54	66.49	OK
6141	2026-09-14 16:55	67.46	OK	6142	2026-09-14 16:56	67.42	OK
6143	2026-09-14 16:57	66.92	OK	6144	2026-09-14 16:58	65.96	OK
6145	2026-09-14 16:59	66.94	OK	6146	2026-09-14 17:00	65.66	OK
6147	2026-09-14 17:01	67.07	OK	6148	2026-09-14 17:02	65.05	OK
6149	2026-09-14 17:03	64.57	OK	6150	2026-09-14 17:04	65.51	OK
6151	2026-09-14 17:05	64.71	OK	6152	2026-09-14 17:06	65.99	OK
6153	2026-09-14 17:07	67.80	OK	6154	2026-09-14 17:08	67.13	OK
6155	2026-09-14 17:09	65.74	OK	6156	2026-09-14 17:10	65.01	OK
6157	2026-09-14 17:11	67.31	OK	6158	2026-09-14 17:12	67.91	OK
6159	2026-09-14 17:13	65.84	OK	6160	2026-09-14 17:14	69.52	OK
6161	2026-09-14 17:15	65.63	OK	6162	2026-09-14 17:16	70.04	OK
6163	2026-09-14 17:17	66.79	OK	6164	2026-09-14 17:18	66.42	OK
6165	2026-09-14 17:19	66.23	OK	6166	2026-09-14 17:20	66.45	OK
6167	2026-09-14 17:21	68.07	OK	6168	2026-09-14 17:22	67.22	OK
6169	2026-09-14 17:23	68.95	OK	6170	2026-09-14 17:24	66.43	OK
6171	2026-09-14 17:25	65.33	OK	6172	2026-09-14 17:26	68.86	OK
6173	2026-09-14 17:27	68.55	OK	6174	2026-09-14 17:28	67.71	OK
6175	2026-09-14 17:29	69.57	OK	6176	2026-09-14 17:30	68.48	OK
6177	2026-09-14 17:31	65.78	OK	6178	2026-09-14 17:32	68.18	OK
6179	2026-09-14 17:33	68.69	OK	6180	2026-09-14 17:34	66.15	OK
6181	2026-09-14 17:35	65.75	OK	6182	2026-09-14 17:36	69.40	OK
6183	2026-09-14 17:37	68.89	OK	6184	2026-09-14 17:38	66.26	OK
6185	2026-09-14 17:39	67.38	OK	6186	2026-09-14 17:40	68.89	OK
6187	2026-09-14 17:41	67.02	OK	6188	2026-09-14 17:42	68.73	OK
6189	2026-09-14 17:43	69.35	OK	6190	2026-09-14 17:44	69.06	OK
6191	2026-09-14 17:45	65.30	OK	6192	2026-09-14 17:46	66.59	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6193	2026-09-14 17:47	67.68	OK	6194	2026-09-14 17:48	66.95	OK
6195	2026-09-14 17:49	69.36	OK	6196	2026-09-14 17:50	67.68	OK
6197	2026-09-14 17:51	66.55	OK	6198	2026-09-14 17:52	66.97	OK
6199	2026-09-14 17:53	70.00	OK	6200	2026-09-14 17:54	66.74	OK
6201	2026-09-14 17:55	69.64	OK	6202	2026-09-14 17:56	69.31	OK
6203	2026-09-14 17:57	69.37	OK	6204	2026-09-14 17:58	66.49	OK
6205	2026-09-14 17:59	67.90	OK	6206	2026-09-14 18:00	69.15	OK
6207	2026-09-14 18:01	68.34	OK	6208	2026-09-14 18:02	66.22	OK
6209	2026-09-14 18:03	69.86	OK	6210	2026-09-14 18:04	68.41	OK
6211	2026-09-14 18:05	67.10	OK	6212	2026-09-14 18:06	68.03	OK
6213	2026-09-14 18:07	68.75	OK	6214	2026-09-14 18:08	70.76	OK
6215	2026-09-14 18:09	67.96	OK	6216	2026-09-14 18:10	70.22	OK
6217	2026-09-14 18:11	70.08	OK	6218	2026-09-14 18:12	69.21	OK
6219	2026-09-14 18:13	70.08	OK	6220	2026-09-14 18:14	68.66	OK
6221	2026-09-14 18:15	66.62	OK	6222	2026-09-14 18:16	67.77	OK
6223	2026-09-14 18:17	68.39	OK	6224	2026-09-14 18:18	66.95	OK
6225	2026-09-14 18:19	68.22	OK	6226	2026-09-14 18:20	67.80	OK
6227	2026-09-14 18:21	69.18	OK	6228	2026-09-14 18:22	69.67	OK
6229	2026-09-14 18:23	68.35	OK	6230	2026-09-14 18:24	69.93	OK
6231	2026-09-14 18:25	67.81	OK	6232	2026-09-14 18:26	66.74	OK
6233	2026-09-14 18:27	68.86	OK	6234	2026-09-14 18:28	68.42	OK
6235	2026-09-14 18:29	69.56	OK	6236	2026-09-14 18:30	70.36	OK
6237	2026-09-14 18:31	70.82	OK	6238	2026-09-14 18:32	69.98	OK
6239	2026-09-14 18:33	70.43	OK	6240	2026-09-14 18:34	72.25	OK
6241	2026-09-14 18:35	69.41	OK	6242	2026-09-14 18:36	68.16	OK
6243	2026-09-14 18:37	71.10	OK	6244	2026-09-14 18:38	67.72	OK
6245	2026-09-14 18:39	67.51	OK	6246	2026-09-14 18:40	69.07	OK
6247	2026-09-14 18:41	68.23	OK	6248	2026-09-14 18:42	70.21	OK
6249	2026-09-14 18:43	69.00	OK	6250	2026-09-14 18:44	69.38	OK
6251	2026-09-14 18:45	70.05	OK	6252	2026-09-14 18:46	70.41	OK
6253	2026-09-14 18:47	68.43	OK	6254	2026-09-14 18:48	68.86	OK
6255	2026-09-14 18:49	70.45	OK	6256	2026-09-14 18:50	67.78	OK
6257	2026-09-14 18:51	70.33	OK	6258	2026-09-14 18:52	68.84	OK
6259	2026-09-14 18:53	70.16	OK	6260	2026-09-14 18:54	70.74	OK
6261	2026-09-14 18:55	70.21	OK	6262	2026-09-14 18:56	67.31	OK
6263	2026-09-14 18:57	69.56	OK	6264	2026-09-14 18:58	69.70	OK
6265	2026-09-14 18:59	67.56	OK	6266	2026-09-14 19:00	69.59	OK
6267	2026-09-14 19:01	69.52	OK	6268	2026-09-14 19:02	71.30	OK
6269	2026-09-14 19:03	70.52	OK	6270	2026-09-14 19:04	68.49	OK
6271	2026-09-14 19:05	71.22	OK	6272	2026-09-14 19:06	69.31	OK
6273	2026-09-14 19:07	69.13	OK	6274	2026-09-14 19:08	68.37	OK
6275	2026-09-14 19:09	71.23	OK	6276	2026-09-14 19:10	69.70	OK
6277	2026-09-14 19:11	68.42	OK	6278	2026-09-14 19:12	69.38	OK
6279	2026-09-14 19:13	70.04	OK	6280	2026-09-14 19:14	69.99	OK
6281	2026-09-14 19:15	71.11	OK	6282	2026-09-14 19:16	69.94	OK
6283	2026-09-14 19:17	71.15	OK	6284	2026-09-14 19:18	71.27	OK
6285	2026-09-14 19:19	71.30	OK	6286	2026-09-14 19:20	68.19	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6287	2026-09-14 19:21	70.20	OK	6288	2026-09-14 19:22	72.62	OK
6289	2026-09-14 19:23	69.99	OK	6290	2026-09-14 19:24	72.27	OK
6291	2026-09-14 19:25	68.83	OK	6292	2026-09-14 19:26	72.73	OK
6293	2026-09-14 19:27	70.70	OK	6294	2026-09-14 19:28	71.72	OK
6295	2026-09-14 19:29	68.57	OK	6296	2026-09-14 19:30	71.84	OK
6297	2026-09-14 19:31	69.51	OK	6298	2026-09-14 19:32	67.48	OK
6299	2026-09-14 19:33	72.12	OK	6300	2026-09-14 19:34	70.54	OK
6301	2026-09-14 19:35	71.47	OK	6302	2026-09-14 19:36	71.85	OK
6303	2026-09-14 19:37	70.94	OK	6304	2026-09-14 19:38	72.17	OK
6305	2026-09-14 19:39	71.40	OK	6306	2026-09-14 19:40	69.66	OK
6307	2026-09-14 19:41	70.71	OK	6308	2026-09-14 19:42	72.35	OK
6309	2026-09-14 19:43	70.76	OK	6310	2026-09-14 19:44	69.10	OK
6311	2026-09-14 19:45	70.38	OK	6312	2026-09-14 19:46	70.09	OK
6313	2026-09-14 19:47	71.30	OK	6314	2026-09-14 19:48	69.91	OK
6315	2026-09-14 19:49	71.65	OK	6316	2026-09-14 19:50	72.12	OK
6317	2026-09-14 19:51	69.84	OK	6318	2026-09-14 19:52	69.83	OK
6319	2026-09-14 19:53	69.55	OK	6320	2026-09-14 19:54	71.04	OK
6321	2026-09-14 19:55	69.53	OK	6322	2026-09-14 19:56	72.55	OK
6323	2026-09-14 19:57	69.61	OK	6324	2026-09-14 19:58	70.58	OK
6325	2026-09-14 19:59	73.24	OK	6326	2026-09-14 20:00	68.88	OK
6327	2026-09-14 20:01	70.74	OK	6328	2026-09-14 20:02	70.56	OK
6329	2026-09-14 20:03	72.24	OK	6330	2026-09-14 20:04	71.25	OK
6331	2026-09-14 20:05	72.73	OK	6332	2026-09-14 20:06	68.81	OK
6333	2026-09-14 20:07	71.60	OK	6334	2026-09-14 20:08	70.87	OK
6335	2026-09-14 20:09	71.52	OK	6336	2026-09-14 20:10	72.48	OK
6337	2026-09-14 20:11	69.61	OK	6338	2026-09-14 20:12	72.09	OK
6339	2026-09-14 20:13	72.72	OK	6340	2026-09-14 20:14	70.03	OK
6341	2026-09-14 20:15	68.53	OK	6342	2026-09-14 20:16	69.40	OK
6343	2026-09-14 20:17	71.89	OK	6344	2026-09-14 20:18	71.04	OK
6345	2026-09-14 20:19	71.82	OK	6346	2026-09-14 20:20	71.57	OK
6347	2026-09-14 20:21	70.55	OK	6348	2026-09-14 20:22	70.97	OK
6349	2026-09-14 20:23	71.24	OK	6350	2026-09-14 20:24	69.67	OK
6351	2026-09-14 20:25	71.32	OK	6352	2026-09-14 20:26	71.79	OK
6353	2026-09-14 20:27	71.29	OK	6354	2026-09-14 20:28	70.42	OK
6355	2026-09-14 20:29	71.65	OK	6356	2026-09-14 20:30	69.63	OK
6357	2026-09-14 20:31	71.60	OK	6358	2026-09-14 20:32	72.82	OK
6359	2026-09-14 20:33	68.90	OK	6360	2026-09-14 20:34	69.25	OK
6361	2026-09-14 20:35	70.44	OK	6362	2026-09-14 20:36	70.75	OK
6363	2026-09-14 20:37	71.69	OK	6364	2026-09-14 20:38	70.95	OK
6365	2026-09-14 20:39	71.38	OK	6366	2026-09-14 20:40	71.18	OK
6367	2026-09-14 20:41	71.29	OK	6368	2026-09-14 20:42	72.17	OK
6369	2026-09-14 20:43	71.68	OK	6370	2026-09-14 20:44	70.68	OK
6371	2026-09-14 20:45	71.31	OK	6372	2026-09-14 20:46	73.39	OK
6373	2026-09-14 20:47	72.66	OK	6374	2026-09-14 20:48	70.90	OK
6375	2026-09-14 20:49	71.37	OK	6376	2026-09-14 20:50	71.00	OK
6377	2026-09-14 20:51	72.94	OK	6378	2026-09-14 20:52	73.03	OK
6379	2026-09-14 20:53	71.99	OK	6380	2026-09-14 20:54	72.97	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6381	2026-09-14 20:55	70.21	OK	6382	2026-09-14 20:56	70.22	OK
6383	2026-09-14 20:57	71.15	OK	6384	2026-09-14 20:58	72.03	OK
6385	2026-09-14 20:59	71.51	OK	6386	2026-09-14 21:00	71.92	OK
6387	2026-09-14 21:01	73.07	OK	6388	2026-09-14 21:02	69.96	OK
6389	2026-09-14 21:03	71.49	OK	6390	2026-09-14 21:04	69.51	OK
6391	2026-09-14 21:05	73.17	OK	6392	2026-09-14 21:06	73.38	OK
6393	2026-09-14 21:07	71.47	OK	6394	2026-09-14 21:08	72.08	OK
6395	2026-09-14 21:09	71.07	OK	6396	2026-09-14 21:10	73.85	OK
6397	2026-09-14 21:11	72.14	OK	6398	2026-09-14 21:12	72.38	OK
6399	2026-09-14 21:13	73.70	OK	6400	2026-09-14 21:14	70.26	OK
6401	2026-09-14 21:15	71.48	OK	6402	2026-09-14 21:16	72.64	OK
6403	2026-09-14 21:17	73.36	OK	6404	2026-09-14 21:18	72.92	OK
6405	2026-09-14 21:19	73.55	OK	6406	2026-09-14 21:20	70.29	OK
6407	2026-09-14 21:21	71.69	OK	6408	2026-09-14 21:22	74.32	OK
6409	2026-09-14 21:23	71.82	OK	6410	2026-09-14 21:24	70.58	OK
6411	2026-09-14 21:25	72.48	OK	6412	2026-09-14 21:26	71.17	OK
6413	2026-09-14 21:27	71.89	OK	6414	2026-09-14 21:28	70.09	OK
6415	2026-09-14 21:29	70.06	OK	6416	2026-09-14 21:30	71.21	OK
6417	2026-09-14 21:31	71.40	OK	6418	2026-09-14 21:32	71.47	OK
6419	2026-09-14 21:33	72.39	OK	6420	2026-09-14 21:34	71.52	OK
6421	2026-09-14 21:35	71.56	OK	6422	2026-09-14 21:36	72.68	OK
6423	2026-09-14 21:37	73.47	OK	6424	2026-09-14 21:38	72.89	OK
6425	2026-09-14 21:39	72.77	OK	6426	2026-09-14 21:40	70.41	OK
6427	2026-09-14 21:41	70.04	OK	6428	2026-09-14 21:42	74.63	OK
6429	2026-09-14 21:43	70.09	OK	6430	2026-09-14 21:44	72.80	OK
6431	2026-09-14 21:45	72.99	OK	6432	2026-09-14 21:46	74.15	OK
6433	2026-09-14 21:47	72.27	OK	6434	2026-09-14 21:48	71.75	OK
6435	2026-09-14 21:49	73.34	OK	6436	2026-09-14 21:50	75.30	OK
6437	2026-09-14 21:51	74.33	OK	6438	2026-09-14 21:52	71.08	OK
6439	2026-09-14 21:53	73.28	OK	6440	2026-09-14 21:54	72.15	OK
6441	2026-09-14 21:55	73.92	OK	6442	2026-09-14 21:56	71.06	OK
6443	2026-09-14 21:57	73.09	OK	6444	2026-09-14 21:58	73.56	OK
6445	2026-09-14 21:59	73.56	OK	6446	2026-09-14 22:00	71.44	OK
6447	2026-09-14 22:01	70.78	OK	6448	2026-09-14 22:02	73.16	OK
6449	2026-09-14 22:03	70.49	OK	6450	2026-09-14 22:04	72.02	OK
6451	2026-09-14 22:05	72.38	OK	6452	2026-09-14 22:06	71.46	OK
6453	2026-09-14 22:07	71.88	OK	6454	2026-09-14 22:08	71.67	OK
6455	2026-09-14 22:09	74.90	OK	6456	2026-09-14 22:10	74.00	OK
6457	2026-09-14 22:11	74.43	OK	6458	2026-09-14 22:12	72.59	OK
6459	2026-09-14 22:13	72.34	OK	6460	2026-09-14 22:14	74.60	OK
6461	2026-09-14 22:15	71.25	OK	6462	2026-09-14 22:16	73.52	OK
6463	2026-09-14 22:17	72.00	OK	6464	2026-09-14 22:18	70.99	OK
6465	2026-09-14 22:19	71.91	OK	6466	2026-09-14 22:20	74.11	OK
6467	2026-09-14 22:21	73.11	OK	6468	2026-09-14 22:22	70.69	OK
6469	2026-09-14 22:23	72.72	OK	6470	2026-09-14 22:24	74.02	OK
6471	2026-09-14 22:25	73.82	OK	6472	2026-09-14 22:26	72.00	OK
6473	2026-09-14 22:27	72.02	OK	6474	2026-09-14 22:28	73.97	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6475	2026-09-14 22:29	71.36	OK	6476	2026-09-14 22:30	74.22	OK
6477	2026-09-14 22:31	71.02	OK	6478	2026-09-14 22:32	71.71	OK
6479	2026-09-14 22:33	72.06	OK	6480	2026-09-14 22:34	71.60	OK
6481	2026-09-14 22:35	72.30	OK	6482	2026-09-14 22:36	72.48	OK
6483	2026-09-14 22:37	70.44	OK	6484	2026-09-14 22:38	72.92	OK
6485	2026-09-14 22:39	72.66	OK	6486	2026-09-14 22:40	72.95	OK
6487	2026-09-14 22:41	72.47	OK	6488	2026-09-14 22:42	71.82	OK
6489	2026-09-14 22:43	70.13	OK	6490	2026-09-14 22:44	71.69	OK
6491	2026-09-14 22:45	72.96	OK	6492	2026-09-14 22:46	75.18	OK
6493	2026-09-14 22:47	74.58	OK	6494	2026-09-14 22:48	73.23	OK
6495	2026-09-14 22:49	71.32	OK	6496	2026-09-14 22:50	72.22	OK
6497	2026-09-14 22:51	72.95	OK	6498	2026-09-14 22:52	69.96	OK
6499	2026-09-14 22:53	73.23	OK	6500	2026-09-14 22:54	73.39	OK
6501	2026-09-14 22:55	73.67	OK	6502	2026-09-14 22:56	72.86	OK
6503	2026-09-14 22:57	70.70	OK	6504	2026-09-14 22:58	72.75	OK
6505	2026-09-14 22:59	71.42	OK	6506	2026-09-14 23:00	73.04	OK
6507	2026-09-14 23:01	72.52	OK	6508	2026-09-14 23:02	73.39	OK
6509	2026-09-14 23:03	72.38	OK	6510	2026-09-14 23:04	70.99	OK
6511	2026-09-14 23:05	70.69	OK	6512	2026-09-14 23:06	73.63	OK
6513	2026-09-14 23:07	72.85	OK	6514	2026-09-14 23:08	73.77	OK
6515	2026-09-14 23:09	74.29	OK	6516	2026-09-14 23:10	70.27	OK
6517	2026-09-14 23:11	73.52	OK	6518	2026-09-14 23:12	73.06	OK
6519	2026-09-14 23:13	71.10	OK	6520	2026-09-14 23:14	73.88	OK
6521	2026-09-14 23:15	73.04	OK	6522	2026-09-14 23:16	72.62	OK
6523	2026-09-14 23:17	71.71	OK	6524	2026-09-14 23:18	72.83	OK
6525	2026-09-14 23:19	74.07	OK	6526	2026-09-14 23:20	73.51	OK
6527	2026-09-14 23:21	73.23	OK	6528	2026-09-14 23:22	73.33	OK
6529	2026-09-14 23:23	72.42	OK	6530	2026-09-14 23:24	73.59	OK
6531	2026-09-14 23:25	73.12	OK	6532	2026-09-14 23:26	70.64	OK
6533	2026-09-14 23:27	73.90	OK	6534	2026-09-14 23:28	74.54	OK
6535	2026-09-14 23:29	73.69	OK	6536	2026-09-14 23:30	73.20	OK
6537	2026-09-14 23:31	74.44	OK	6538	2026-09-14 23:32	70.42	OK
6539	2026-09-14 23:33	71.99	OK	6540	2026-09-14 23:34	71.98	OK
6541	2026-09-14 23:35	72.01	OK	6542	2026-09-14 23:36	72.88	OK
6543	2026-09-14 23:37	73.82	OK	6544	2026-09-14 23:38	72.32	OK
6545	2026-09-14 23:39	73.39	OK	6546	2026-09-14 23:40	72.12	OK
6547	2026-09-14 23:41	72.83	OK	6548	2026-09-14 23:42	74.32	OK
6549	2026-09-14 23:43	74.17	OK	6550	2026-09-14 23:44	70.76	OK
6551	2026-09-14 23:45	72.57	OK	6552	2026-09-14 23:46	74.34	OK
6553	2026-09-14 23:47	72.86	OK	6554	2026-09-14 23:48	71.23	OK
6555	2026-09-14 23:49	73.50	OK	6556	2026-09-14 23:50	72.53	OK
6557	2026-09-14 23:51	73.96	OK	6558	2026-09-14 23:52	73.36	OK
6559	2026-09-14 23:53	71.54	OK	6560	2026-09-14 23:54	71.15	OK
6561	2026-09-14 23:55	72.26	OK	6562	2026-09-14 23:56	71.55	OK
6563	2026-09-14 23:57	73.85	OK	6564	2026-09-14 23:58	73.61	OK
6565	2026-09-14 23:59	73.14	OK	6566	2026-09-15 00:00	72.31	OK
6567	2026-09-15 00:01	72.19	OK	6568	2026-09-15 00:02	71.68	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6569	2026-09-15 00:03	71.58	OK	6570	2026-09-15 00:04	72.70	OK
6571	2026-09-15 00:05	72.76	OK	6572	2026-09-15 00:06	72.39	OK
6573	2026-09-15 00:07	73.59	OK	6574	2026-09-15 00:08	70.18	OK
6575	2026-09-15 00:09	69.33	OK	6576	2026-09-15 00:10	72.40	OK
6577	2026-09-15 00:11	69.99	OK	6578	2026-09-15 00:12	69.21	OK
6579	2026-09-15 00:13	71.97	OK	6580	2026-09-15 00:14	73.26	OK
6581	2026-09-15 00:15	72.41	OK	6582	2026-09-15 00:16	74.79	OK
6583	2026-09-15 00:17	73.77	OK	6584	2026-09-15 00:18	70.65	OK
6585	2026-09-15 00:19	70.40	OK	6586	2026-09-15 00:20	71.51	OK
6587	2026-09-15 00:21	73.48	OK	6588	2026-09-15 00:22	72.08	OK
6589	2026-09-15 00:23	71.44	OK	6590	2026-09-15 00:24	72.56	OK
6591	2026-09-15 00:25	70.85	OK	6592	2026-09-15 00:26	71.54	OK
6593	2026-09-15 00:27	71.59	OK	6594	2026-09-15 00:28	70.76	OK
6595	2026-09-15 00:29	73.63	OK	6596	2026-09-15 00:30	73.24	OK
6597	2026-09-15 00:31	73.43	OK	6598	2026-09-15 00:32	69.02	OK
6599	2026-09-15 00:33	71.61	OK	6600	2026-09-15 00:34	71.20	OK
6601	2026-09-15 00:35	73.93	OK	6602	2026-09-15 00:36	70.17	OK
6603	2026-09-15 00:37	71.50	OK	6604	2026-09-15 00:38	73.13	OK
6605	2026-09-15 00:39	72.42	OK	6606	2026-09-15 00:40	71.13	OK
6607	2026-09-15 00:41	73.43	OK	6608	2026-09-15 00:42	69.37	OK
6609	2026-09-15 00:43	73.85	OK	6610	2026-09-15 00:44	70.96	OK
6611	2026-09-15 00:45	71.56	OK	6612	2026-09-15 00:46	70.48	OK
6613	2026-09-15 00:47	71.46	OK	6614	2026-09-15 00:48	70.22	OK
6615	2026-09-15 00:49	70.69	OK	6616	2026-09-15 00:50	70.29	OK
6617	2026-09-15 00:51	69.38	OK	6618	2026-09-15 00:52	71.88	OK
6619	2026-09-15 00:53	71.83	OK	6620	2026-09-15 00:54	69.79	OK
6621	2026-09-15 00:55	71.05	OK	6622	2026-09-15 00:56	72.63	OK
6623	2026-09-15 00:57	71.71	OK	6624	2026-09-15 00:58	71.55	OK
6625	2026-09-15 00:59	71.32	OK	6626	2026-09-15 01:00	69.91	OK
6627	2026-09-15 01:01	71.61	OK	6628	2026-09-15 01:02	71.45	OK
6629	2026-09-15 01:03	72.98	OK	6630	2026-09-15 01:04	70.76	OK
6631	2026-09-15 01:05	71.31	OK	6632	2026-09-15 01:06	68.91	OK
6633	2026-09-15 01:07	71.13	OK	6634	2026-09-15 01:08	71.14	OK
6635	2026-09-15 01:09	70.68	OK	6636	2026-09-15 01:10	70.26	OK
6637	2026-09-15 01:11	72.54	OK	6638	2026-09-15 01:12	73.26	OK
6639	2026-09-15 01:13	71.85	OK	6640	2026-09-15 01:14	70.69	OK
6641	2026-09-15 01:15	70.03	OK	6642	2026-09-15 01:16	72.02	OK
6643	2026-09-15 01:17	71.36	OK	6644	2026-09-15 01:18	69.73	OK
6645	2026-09-15 01:19	71.38	OK	6646	2026-09-15 01:20	71.87	OK
6647	2026-09-15 01:21	71.99	OK	6648	2026-09-15 01:22	71.01	OK
6649	2026-09-15 01:23	71.87	OK	6650	2026-09-15 01:24	71.85	OK
6651	2026-09-15 01:25	73.64	OK	6652	2026-09-15 01:26	70.76	OK
6653	2026-09-15 01:27	70.52	OK	6654	2026-09-15 01:28	71.06	OK
6655	2026-09-15 01:29	69.43	OK	6656	2026-09-15 01:30	69.87	OK
6657	2026-09-15 01:31	70.26	OK	6658	2026-09-15 01:32	72.47	OK
6659	2026-09-15 01:33	73.13	OK	6660	2026-09-15 01:34	72.70	OK
6661	2026-09-15 01:35	72.28	OK	6662	2026-09-15 01:36	69.41	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6663	2026-09-15 01:37	70.36	OK	6664	2026-09-15 01:38	72.27	OK
6665	2026-09-15 01:39	70.81	OK	6666	2026-09-15 01:40	72.21	OK
6667	2026-09-15 01:41	71.81	OK	6668	2026-09-15 01:42	70.09	OK
6669	2026-09-15 01:43	71.01	OK	6670	2026-09-15 01:44	70.62	OK
6671	2026-09-15 01:45	69.89	OK	6672	2026-09-15 01:46	70.84	OK
6673	2026-09-15 01:47	71.80	OK	6674	2026-09-15 01:48	71.87	OK
6675	2026-09-15 01:49	67.31	OK	6676	2026-09-15 01:50	69.31	OK
6677	2026-09-15 01:51	70.52	OK	6678	2026-09-15 01:52	70.71	OK
6679	2026-09-15 01:53	71.40	OK	6680	2026-09-15 01:54	69.85	OK
6681	2026-09-15 01:55	69.33	OK	6682	2026-09-15 01:56	71.84	OK
6683	2026-09-15 01:57	70.27	OK	6684	2026-09-15 01:58	70.82	OK
6685	2026-09-15 01:59	68.59	OK	6686	2026-09-15 02:00	71.11	OK
6687	2026-09-15 02:01	71.12	OK	6688	2026-09-15 02:02	69.09	OK
6689	2026-09-15 02:03	69.26	OK	6690	2026-09-15 02:04	69.05	OK
6691	2026-09-15 02:05	68.31	OK	6692	2026-09-15 02:06	71.68	OK
6693	2026-09-15 02:07	70.29	OK	6694	2026-09-15 02:08	71.99	OK
6695	2026-09-15 02:09	69.02	OK	6696	2026-09-15 02:10	70.29	OK
6697	2026-09-15 02:11	69.09	OK	6698	2026-09-15 02:12	68.56	OK
6699	2026-09-15 02:13	68.79	OK	6700	2026-09-15 02:14	71.14	OK
6701	2026-09-15 02:15	69.64	OK	6702	2026-09-15 02:16	70.42	OK
6703	2026-09-15 02:17	69.56	OK	6704	2026-09-15 02:18	68.93	OK
6705	2026-09-15 02:19	71.73	OK	6706	2026-09-15 02:20	67.63	OK
6707	2026-09-15 02:21	70.88	OK	6708	2026-09-15 02:22	69.70	OK
6709	2026-09-15 02:23	69.21	OK	6710	2026-09-15 02:24	68.84	OK
6711	2026-09-15 02:25	68.74	OK	6712	2026-09-15 02:26	68.51	OK
6713	2026-09-15 02:27	68.54	OK	6714	2026-09-15 02:28	70.90	OK
6715	2026-09-15 02:29	69.74	OK	6716	2026-09-15 02:30	68.53	OK
6717	2026-09-15 02:31	70.63	OK	6718	2026-09-15 02:32	68.97	OK
6719	2026-09-15 02:33	66.75	OK	6720	2026-09-15 02:34	70.89	OK
6721	2026-09-15 02:35	70.49	OK	6722	2026-09-15 02:36	68.02	OK
6723	2026-09-15 02:37	70.86	OK	6724	2026-09-15 02:38	70.72	OK
6725	2026-09-15 02:39	69.57	OK	6726	2026-09-15 02:40	68.77	OK
6727	2026-09-15 02:41	67.91	OK	6728	2026-09-15 02:42	69.35	OK
6729	2026-09-15 02:43	69.96	OK	6730	2026-09-15 02:44	67.70	OK
6731	2026-09-15 02:45	69.08	OK	6732	2026-09-15 02:46	68.08	OK
6733	2026-09-15 02:47	67.99	OK	6734	2026-09-15 02:48	71.98	OK
6735	2026-09-15 02:49	69.28	OK	6736	2026-09-15 02:50	69.26	OK
6737	2026-09-15 02:51	68.83	OK	6738	2026-09-15 02:52	69.27	OK
6739	2026-09-15 02:53	71.56	OK	6740	2026-09-15 02:54	68.28	OK
6741	2026-09-15 02:55	69.41	OK	6742	2026-09-15 02:56	71.57	OK
6743	2026-09-15 02:57	69.30	OK	6744	2026-09-15 02:58	68.78	OK
6745	2026-09-15 02:59	68.60	OK	6746	2026-09-15 03:00	68.70	OK
6747	2026-09-15 03:01	68.41	OK	6748	2026-09-15 03:02	67.83	OK
6749	2026-09-15 03:03	69.93	OK	6750	2026-09-15 03:04	69.14	OK
6751	2026-09-15 03:05	69.64	OK	6752	2026-09-15 03:06	68.21	OK
6753	2026-09-15 03:07	67.76	OK	6754	2026-09-15 03:08	67.39	OK
6755	2026-09-15 03:09	65.96	OK	6756	2026-09-15 03:10	69.54	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6757	2026-09-15 03:11	68.52	OK	6758	2026-09-15 03:12	69.26	OK
6759	2026-09-15 03:13	68.31	OK	6760	2026-09-15 03:14	68.42	OK
6761	2026-09-15 03:15	71.52	OK	6762	2026-09-15 03:16	65.64	OK
6763	2026-09-15 03:17	67.97	OK	6764	2026-09-15 03:18	67.07	OK
6765	2026-09-15 03:19	69.17	OK	6766	2026-09-15 03:20	68.36	OK
6767	2026-09-15 03:21	67.02	OK	6768	2026-09-15 03:22	69.08	OK
6769	2026-09-15 03:23	67.04	OK	6770	2026-09-15 03:24	68.17	OK
6771	2026-09-15 03:25	67.52	OK	6772	2026-09-15 03:26	67.31	OK
6773	2026-09-15 03:27	69.90	OK	6774	2026-09-15 03:28	69.63	OK
6775	2026-09-15 03:29	69.49	OK	6776	2026-09-15 03:30	69.16	OK
6777	2026-09-15 03:31	67.74	OK	6778	2026-09-15 03:32	67.40	OK
6779	2026-09-15 03:33	67.68	OK	6780	2026-09-15 03:34	69.05	OK
6781	2026-09-15 03:35	67.46	OK	6782	2026-09-15 03:36	66.87	OK
6783	2026-09-15 03:37	66.04	OK	6784	2026-09-15 03:38	66.70	OK
6785	2026-09-15 03:39	68.46	OK	6786	2026-09-15 03:40	67.87	OK
6787	2026-09-15 03:41	67.79	OK	6788	2026-09-15 03:42	70.25	OK
6789	2026-09-15 03:43	68.39	OK	6790	2026-09-15 03:44	68.28	OK
6791	2026-09-15 03:45	65.83	OK	6792	2026-09-15 03:46	68.23	OK
6793	2026-09-15 03:47	67.89	OK	6794	2026-09-15 03:48	68.08	OK
6795	2026-09-15 03:49	68.65	OK	6796	2026-09-15 03:50	67.96	OK
6797	2026-09-15 03:51	66.41	OK	6798	2026-09-15 03:52	66.59	OK
6799	2026-09-15 03:53	65.68	OK	6800	2026-09-15 03:54	69.14	OK
6801	2026-09-15 03:55	67.83	OK	6802	2026-09-15 03:56	66.73	OK
6803	2026-09-15 03:57	67.18	OK	6804	2026-09-15 03:58	67.26	OK
6805	2026-09-15 03:59	69.06	OK	6806	2026-09-15 04:00	66.25	OK
6807	2026-09-15 04:01	65.86	OK	6808	2026-09-15 04:02	67.53	OK
6809	2026-09-15 04:03	65.28	OK	6810	2026-09-15 04:04	67.27	OK
6811	2026-09-15 04:05	69.40	OK	6812	2026-09-15 04:06	69.09	OK
6813	2026-09-15 04:07	66.66	OK	6814	2026-09-15 04:08	67.97	OK
6815	2026-09-15 04:09	66.57	OK	6816	2026-09-15 04:10	69.17	OK
6817	2026-09-15 04:11	68.63	OK	6818	2026-09-15 04:12	66.93	OK
6819	2026-09-15 04:13	64.99	OK	6820	2026-09-15 04:14	66.65	OK
6821	2026-09-15 04:15	65.42	OK	6822	2026-09-15 04:16	64.75	OK
6823	2026-09-15 04:17	68.52	OK	6824	2026-09-15 04:18	67.85	OK
6825	2026-09-15 04:19	68.25	OK	6826	2026-09-15 04:20	64.84	OK
6827	2026-09-15 04:21	64.98	OK	6828	2026-09-15 04:22	64.66	OK
6829	2026-09-15 04:23	66.41	OK	6830	2026-09-15 04:24	66.53	OK
6831	2026-09-15 04:25	65.83	OK	6832	2026-09-15 04:26	64.59	OK
6833	2026-09-15 04:27	66.07	OK	6834	2026-09-15 04:28	66.51	OK
6835	2026-09-15 04:29	64.60	OK	6836	2026-09-15 04:30	64.81	OK
6837	2026-09-15 04:31	68.54	OK	6838	2026-09-15 04:32	64.84	OK
6839	2026-09-15 04:33	66.27	OK	6840	2026-09-15 04:34	67.46	OK
6841	2026-09-15 04:35	65.85	OK	6842	2026-09-15 04:36	68.21	OK
6843	2026-09-15 04:37	67.28	OK	6844	2026-09-15 04:38	64.66	OK
6845	2026-09-15 04:39	67.11	OK	6846	2026-09-15 04:40	64.98	OK
6847	2026-09-15 04:41	67.45	OK	6848	2026-09-15 04:42	64.69	OK
6849	2026-09-15 04:43	66.65	OK	6850	2026-09-15 04:44	65.56	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6851	2026-09-15 04:45	66.49	OK	6852	2026-09-15 04:46	65.83	OK
6853	2026-09-15 04:47	67.94	OK	6854	2026-09-15 04:48	64.23	OK
6855	2026-09-15 04:49	67.49	OK	6856	2026-09-15 04:50	64.02	OK
6857	2026-09-15 04:51	63.81	OK	6858	2026-09-15 04:52	65.98	OK
6859	2026-09-15 04:53	64.76	OK	6860	2026-09-15 04:54	66.77	OK
6861	2026-09-15 04:55	65.33	OK	6862	2026-09-15 04:56	66.02	OK
6863	2026-09-15 04:57	67.50	OK	6864	2026-09-15 04:58	64.31	OK
6865	2026-09-15 04:59	66.43	OK	6866	2026-09-15 05:00	65.56	OK
6867	2026-09-15 05:01	64.76	OK	6868	2026-09-15 05:02	66.08	OK
6869	2026-09-15 05:03	67.32	OK	6870	2026-09-15 05:04	65.93	OK
6871	2026-09-15 05:05	64.99	OK	6872	2026-09-15 05:06	65.15	OK
6873	2026-09-15 05:07	65.12	OK	6874	2026-09-15 05:08	66.17	OK
6875	2026-09-15 05:09	67.06	OK	6876	2026-09-15 05:10	66.05	OK
6877	2026-09-15 05:11	63.12	OK	6878	2026-09-15 05:12	64.28	OK
6879	2026-09-15 05:13	64.83	OK	6880	2026-09-15 05:14	65.70	OK
6881	2026-09-15 05:15	64.64	OK	6882	2026-09-15 05:16	64.70	OK
6883	2026-09-15 05:17	63.89	OK	6884	2026-09-15 05:18	66.06	OK
6885	2026-09-15 05:19	65.55	OK	6886	2026-09-15 05:20	63.94	OK
6887	2026-09-15 05:21	65.70	OK	6888	2026-09-15 05:22	64.79	OK
6889	2026-09-15 05:23	64.86	OK	6890	2026-09-15 05:24	66.44	OK
6891	2026-09-15 05:25	64.00	OK	6892	2026-09-15 05:26	65.27	OK
6893	2026-09-15 05:27	62.69	OK	6894	2026-09-15 05:28	66.12	OK
6895	2026-09-15 05:29	65.68	OK	6896	2026-09-15 05:30	66.25	OK
6897	2026-09-15 05:31	64.62	OK	6898	2026-09-15 05:32	65.57	OK
6899	2026-09-15 05:33	64.00	OK	6900	2026-09-15 05:34	63.87	OK
6901	2026-09-15 05:35	64.64	OK	6902	2026-09-15 05:36	62.15	OK
6903	2026-09-15 05:37	66.65	OK	6904	2026-09-15 05:38	65.27	OK
6905	2026-09-15 05:39	63.91	OK	6906	2026-09-15 05:40	65.91	OK
6907	2026-09-15 05:41	62.71	OK	6908	2026-09-15 05:42	60.88	OK
6909	2026-09-15 05:43	63.43	OK	6910	2026-09-15 05:44	64.21	OK
6911	2026-09-15 05:45	64.81	OK	6912	2026-09-15 05:46	63.77	OK
6913	2026-09-15 05:47	63.46	OK	6914	2026-09-15 05:48	62.05	OK
6915	2026-09-15 05:49	63.93	OK	6916	2026-09-15 05:50	64.71	OK
6917	2026-09-15 05:51	65.63	OK	6918	2026-09-15 05:52	64.19	OK
6919	2026-09-15 05:53	64.20	OK	6920	2026-09-15 05:54	62.48	OK
6921	2026-09-15 05:55	63.64	OK	6922	2026-09-15 05:56	63.91	OK
6923	2026-09-15 05:57	64.26	OK	6924	2026-09-15 05:58	63.34	OK
6925	2026-09-15 05:59	63.80	OK	6926	2026-09-15 06:00	65.86	OK
6927	2026-09-15 06:01	63.49	OK	6928	2026-09-15 06:02	63.97	OK
6929	2026-09-15 06:03	65.12	OK	6930	2026-09-15 06:04	61.92	OK
6931	2026-09-15 06:05	63.56	OK	6932	2026-09-15 06:06	63.90	OK
6933	2026-09-15 06:07	62.74	OK	6934	2026-09-15 06:08	62.72	OK
6935	2026-09-15 06:09	62.97	OK	6936	2026-09-15 06:10	63.44	OK
6937	2026-09-15 06:11	63.40	OK	6938	2026-09-15 06:12	64.64	OK
6939	2026-09-15 06:13	65.36	OK	6940	2026-09-15 06:14	64.07	OK
6941	2026-09-15 06:15	61.81	OK	6942	2026-09-15 06:16	63.22	OK
6943	2026-09-15 06:17	64.38	OK	6944	2026-09-15 06:18	63.46	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6945	2026-09-15 06:19	61.63	OK	6946	2026-09-15 06:20	63.28	OK
6947	2026-09-15 06:21	62.80	OK	6948	2026-09-15 06:22	64.09	OK
6949	2026-09-15 06:23	63.37	OK	6950	2026-09-15 06:24	64.42	OK
6951	2026-09-15 06:25	63.37	OK	6952	2026-09-15 06:26	61.65	OK
6953	2026-09-15 06:27	61.40	OK	6954	2026-09-15 06:28	62.01	OK
6955	2026-09-15 06:29	62.69	OK	6956	2026-09-15 06:30	61.13	OK
6957	2026-09-15 06:31	59.64	OK	6958	2026-09-15 06:32	62.21	OK
6959	2026-09-15 06:33	62.37	OK	6960	2026-09-15 06:34	63.50	OK
6961	2026-09-15 06:35	62.39	OK	6962	2026-09-15 06:36	63.38	OK
6963	2026-09-15 06:37	64.33	OK	6964	2026-09-15 06:38	63.16	OK
6965	2026-09-15 06:39	63.74	OK	6966	2026-09-15 06:40	62.77	OK
6967	2026-09-15 06:41	62.72	OK	6968	2026-09-15 06:42	65.22	OK
6969	2026-09-15 06:43	61.59	OK	6970	2026-09-15 06:44	62.70	OK
6971	2026-09-15 06:45	62.61	OK	6972	2026-09-15 06:46	63.97	OK
6973	2026-09-15 06:47	64.38	OK	6974	2026-09-15 06:48	62.20	OK
6975	2026-09-15 06:49	62.21	OK	6976	2026-09-15 06:50	63.47	OK
6977	2026-09-15 06:51	63.44	OK	6978	2026-09-15 06:52	63.25	OK
6979	2026-09-15 06:53	61.19	OK	6980	2026-09-15 06:54	62.40	OK
6981	2026-09-15 06:55	62.28	OK	6982	2026-09-15 06:56	64.03	OK
6983	2026-09-15 06:57	63.46	OK	6984	2026-09-15 06:58	62.27	OK
6985	2026-09-15 06:59	61.04	OK	6986	2026-09-15 07:00	62.86	OK
6987	2026-09-15 07:01	61.32	OK	6988	2026-09-15 07:02	61.11	OK
6989	2026-09-15 07:03	62.21	OK	6990	2026-09-15 07:04	63.22	OK
6991	2026-09-15 07:05	63.07	OK	6992	2026-09-15 07:06	61.52	OK
6993	2026-09-15 07:07	63.66	OK	6994	2026-09-15 07:08	62.05	OK
6995	2026-09-15 07:09	64.66	OK	6996	2026-09-15 07:10	60.22	OK
6997	2026-09-15 07:11	63.46	OK	6998	2026-09-15 07:12	60.25	OK
6999	2026-09-15 07:13	61.26	OK	7000	2026-09-15 07:14	61.38	OK
7001	2026-09-15 07:15	62.62	OK	7002	2026-09-15 07:16	61.65	OK
7003	2026-09-15 07:17	63.24	OK	7004	2026-09-15 07:18	61.74	OK
7005	2026-09-15 07:19	61.52	OK	7006	2026-09-15 07:20	60.57	OK
7007	2026-09-15 07:21	61.46	OK	7008	2026-09-15 07:22	61.53	OK
7009	2026-09-15 07:23	59.30	OK	7010	2026-09-15 07:24	62.71	OK
7011	2026-09-15 07:25	60.55	OK	7012	2026-09-15 07:26	61.14	OK
7013	2026-09-15 07:27	59.02	OK	7014	2026-09-15 07:28	61.70	OK
7015	2026-09-15 07:29	61.45	OK	7016	2026-09-15 07:30	61.22	OK
7017	2026-09-15 07:31	60.74	OK	7018	2026-09-15 07:32	60.85	OK
7019	2026-09-15 07:33	62.32	OK	7020	2026-09-15 07:34	60.34	OK
7021	2026-09-15 07:35	60.40	OK	7022	2026-09-15 07:36	61.77	OK
7023	2026-09-15 07:37	58.54	OK	7024	2026-09-15 07:38	62.06	OK
7025	2026-09-15 07:39	59.95	OK	7026	2026-09-15 07:40	59.82	OK
7027	2026-09-15 07:41	62.19	OK	7028	2026-09-15 07:42	61.77	OK
7029	2026-09-15 07:43	61.13	OK	7030	2026-09-15 07:44	59.60	OK
7031	2026-09-15 07:45	61.46	OK	7032	2026-09-15 07:46	62.88	OK
7033	2026-09-15 07:47	62.29	OK	7034	2026-09-15 07:48	61.69	OK
7035	2026-09-15 07:49	61.52	OK	7036	2026-09-15 07:50	60.42	OK
7037	2026-09-15 07:51	60.61	OK	7038	2026-09-15 07:52	60.76	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7039	2026-09-15 07:53	60.39	OK	7040	2026-09-15 07:54	62.10	OK
7041	2026-09-15 07:55	59.39	OK	7042	2026-09-15 07:56	58.22	OK
7043	2026-09-15 07:57	62.42	OK	7044	2026-09-15 07:58	59.94	OK
7045	2026-09-15 07:59	60.87	OK	7046	2026-09-15 08:00	61.34	OK
7047	2026-09-15 08:01	63.95	OK	7048	2026-09-15 08:02	61.31	OK
7049	2026-09-15 08:03	59.83	OK	7050	2026-09-15 08:04	61.54	OK
7051	2026-09-15 08:05	58.76	OK	7052	2026-09-15 08:06	59.24	OK
7053	2026-09-15 08:07	59.47	OK	7054	2026-09-15 08:08	58.50	OK
7055	2026-09-15 08:09	63.15	OK	7056	2026-09-15 08:10	61.33	OK
7057	2026-09-15 08:11	60.60	OK	7058	2026-09-15 08:12	61.29	OK
7059	2026-09-15 08:13	60.23	OK	7060	2026-09-15 08:14	59.54	OK
7061	2026-09-15 08:15	61.88	OK	7062	2026-09-15 08:16	60.16	OK
7063	2026-09-15 08:17	60.49	OK	7064	2026-09-15 08:18	61.64	OK
7065	2026-09-15 08:19	60.76	OK	7066	2026-09-15 08:20	60.86	OK
7067	2026-09-15 08:21	60.77	OK	7068	2026-09-15 08:22	58.09	OK
7069	2026-09-15 08:23	60.45	OK	7070	2026-09-15 08:24	61.11	OK
7071	2026-09-15 08:25	60.04	OK	7072	2026-09-15 08:26	60.61	OK
7073	2026-09-15 08:27	61.16	OK	7074	2026-09-15 08:28	63.41	OK
7075	2026-09-15 08:29	62.10	OK	7076	2026-09-15 08:30	62.19	OK
7077	2026-09-15 08:31	60.23	OK	7078	2026-09-15 08:32	60.20	OK
7079	2026-09-15 08:33	60.53	OK	7080	2026-09-15 08:34	59.05	OK
7081	2026-09-15 08:35	61.13	OK	7082	2026-09-15 08:36	61.46	OK
7083	2026-09-15 08:37	58.07	OK	7084	2026-09-15 08:38	59.41	OK
7085	2026-09-15 08:39	59.16	OK	7086	2026-09-15 08:40	59.45	OK
7087	2026-09-15 08:41	60.35	OK	7088	2026-09-15 08:42	59.74	OK
7089	2026-09-15 08:43	59.90	OK	7090	2026-09-15 08:44	58.74	OK
7091	2026-09-15 08:45	58.43	OK	7092	2026-09-15 08:46	59.07	OK
7093	2026-09-15 08:47	63.07	OK	7094	2026-09-15 08:48	59.37	OK
7095	2026-09-15 08:49	60.18	OK	7096	2026-09-15 08:50	61.17	OK
7097	2026-09-15 08:51	59.24	OK	7098	2026-09-15 08:52	62.38	OK
7099	2026-09-15 08:53	60.21	OK	7100	2026-09-15 08:54	58.50	OK
7101	2026-09-15 08:55	62.22	OK	7102	2026-09-15 08:56	62.29	OK
7103	2026-09-15 08:57	60.35	OK	7104	2026-09-15 08:58	60.09	OK
7105	2026-09-15 08:59	58.61	OK	7106	2026-09-15 09:00	59.72	OK
7107	2026-09-15 09:01	60.38	OK	7108	2026-09-15 09:02	60.37	OK
7109	2026-09-15 09:03	60.78	OK	7110	2026-09-15 09:04	59.50	OK
7111	2026-09-15 09:05	61.70	OK	7112	2026-09-15 09:06	59.63	OK
7113	2026-09-15 09:07	61.02	OK	7114	2026-09-15 09:08	59.58	OK
7115	2026-09-15 09:09	59.24	OK	7116	2026-09-15 09:10	61.79	OK
7117	2026-09-15 09:11	59.82	OK	7118	2026-09-15 09:12	60.90	OK
7119	2026-09-15 09:13	62.65	OK	7120	2026-09-15 09:14	62.80	OK
7121	2026-09-15 09:15	60.59	OK	7122	2026-09-15 09:16	60.10	OK
7123	2026-09-15 09:17	59.25	OK	7124	2026-09-15 09:18	60.80	OK
7125	2026-09-15 09:19	57.64	OK	7126	2026-09-15 09:20	59.09	OK
7127	2026-09-15 09:21	62.26	OK	7128	2026-09-15 09:22	62.15	OK
7129	2026-09-15 09:23	60.17	OK	7130	2026-09-15 09:24	59.72	OK
7131	2026-09-15 09:25	60.76	OK	7132	2026-09-15 09:26	59.62	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7133	2026-09-15 09:27	60.22	OK	7134	2026-09-15 09:28	62.48	OK
7135	2026-09-15 09:29	57.21	OK	7136	2026-09-15 09:30	57.96	OK
7137	2026-09-15 09:31	60.49	OK	7138	2026-09-15 09:32	58.53	OK
7139	2026-09-15 09:33	59.58	OK	7140	2026-09-15 09:34	58.45	OK
7141	2026-09-15 09:35	58.64	OK	7142	2026-09-15 09:36	60.46	OK
7143	2026-09-15 09:37	60.65	OK	7144	2026-09-15 09:38	60.63	OK
7145	2026-09-15 09:39	56.92	OK	7146	2026-09-15 09:40	58.95	OK
7147	2026-09-15 09:41	59.28	OK	7148	2026-09-15 09:42	59.30	OK
7149	2026-09-15 09:43	59.87	OK	7150	2026-09-15 09:44	62.49	OK
7151	2026-09-15 09:45	60.87	OK	7152	2026-09-15 09:46	59.62	OK
7153	2026-09-15 09:47	58.72	OK	7154	2026-09-15 09:48	60.22	OK
7155	2026-09-15 09:49	61.15	OK	7156	2026-09-15 09:50	57.91	OK
7157	2026-09-15 09:51	59.07	OK	7158	2026-09-15 09:52	62.98	OK
7159	2026-09-15 09:53	61.21	OK	7160	2026-09-15 09:54	58.82	OK
7161	2026-09-15 09:55	57.82	OK	7162	2026-09-15 09:56	58.46	OK
7163	2026-09-15 09:57	58.06	OK	7164	2026-09-15 09:58	58.61	OK
7165	2026-09-15 09:59	61.46	OK	7166	2026-09-15 10:00	58.70	OK
7167	2026-09-15 10:01	60.83	OK	7168	2026-09-15 10:02	58.14	OK
7169	2026-09-15 10:03	59.31	OK	7170	2026-09-15 10:04	60.86	OK
7171	2026-09-15 10:05	59.75	OK	7172	2026-09-15 10:06	62.02	OK
7173	2026-09-15 10:07	60.29	OK	7174	2026-09-15 10:08	62.90	OK
7175	2026-09-15 10:09	61.88	OK	7176	2026-09-15 10:10	57.61	OK
7177	2026-09-15 10:11	59.50	OK	7178	2026-09-15 10:12	58.34	OK
7179	2026-09-15 10:13	58.93	OK	7180	2026-09-15 10:14	57.49	OK
7181	2026-09-15 10:15	59.53	OK	7182	2026-09-15 10:16	59.35	OK
7183	2026-09-15 10:17	60.04	OK	7184	2026-09-15 10:18	61.72	OK
7185	2026-09-15 10:19	59.02	OK	7186	2026-09-15 10:20	58.38	OK
7187	2026-09-15 10:21	60.27	OK	7188	2026-09-15 10:22	58.73	OK
7189	2026-09-15 10:23	61.83	OK	7190	2026-09-15 10:24	61.11	OK
7191	2026-09-15 10:25	61.44	OK	7192	2026-09-15 10:26	57.04	OK
7193	2026-09-15 10:27	57.78	OK	7194	2026-09-15 10:28	60.15	OK
7195	2026-09-15 10:29	57.74	OK	7196	2026-09-15 10:30	57.58	OK
7197	2026-09-15 10:31	59.24	OK	7198	2026-09-15 10:32	59.24	OK
7199	2026-09-15 10:33	60.98	OK	7200	2026-09-15 10:34	61.98	OK
7201	2026-09-15 10:35	59.83	OK	7202	2026-09-15 10:36	59.49	OK
7203	2026-09-15 10:37	59.93	OK	7204	2026-09-15 10:38	59.27	OK
7205	2026-09-15 10:39	60.56	OK	7206	2026-09-15 10:40	58.28	OK
7207	2026-09-15 10:41	59.53	OK	7208	2026-09-15 10:42	60.43	OK
7209	2026-09-15 10:43	58.71	OK	7210	2026-09-15 10:44	57.18	OK
7211	2026-09-15 10:45	59.12	OK	7212	2026-09-15 10:46	59.01	OK
7213	2026-09-15 10:47	61.69	OK	7214	2026-09-15 10:48	59.10	OK
7215	2026-09-15 10:49	59.22	OK	7216	2026-09-15 10:50	58.84	OK
7217	2026-09-15 10:51	59.62	OK	7218	2026-09-15 10:52	61.70	OK
7219	2026-09-15 10:53	58.11	OK	7220	2026-09-15 10:54	57.65	OK
7221	2026-09-15 10:55	61.84	OK	7222	2026-09-15 10:56	58.83	OK
7223	2026-09-15 10:57	58.91	OK	7224	2026-09-15 10:58	57.12	OK
7225	2026-09-15 10:59	61.83	OK	7226	2026-09-15 11:00	59.36	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7227	2026-09-15 11:01	60.17	OK	7228	2026-09-15 11:02	57.80	OK
7229	2026-09-15 11:03	58.41	OK	7230	2026-09-15 11:04	59.74	OK
7231	2026-09-15 11:05	59.98	OK	7232	2026-09-15 11:06	59.92	OK
7233	2026-09-15 11:07	58.55	OK	7234	2026-09-15 11:08	59.92	OK
7235	2026-09-15 11:09	58.56	OK	7236	2026-09-15 11:10	59.89	OK
7237	2026-09-15 11:11	57.94	OK	7238	2026-09-15 11:12	61.85	OK
7239	2026-09-15 11:13	60.64	OK	7240	2026-09-15 11:14	61.98	OK
7241	2026-09-15 11:15	59.36	OK	7242	2026-09-15 11:16	59.11	OK
7243	2026-09-15 11:17	61.49	OK	7244	2026-09-15 11:18	60.62	OK
7245	2026-09-15 11:19	60.79	OK	7246	2026-09-15 11:20	58.00	OK
7247	2026-09-15 11:21	60.43	OK	7248	2026-09-15 11:22	60.97	OK
7249	2026-09-15 11:23	61.70	OK	7250	2026-09-15 11:24	57.86	OK
7251	2026-09-15 11:25	60.80	OK	7252	2026-09-15 11:26	60.31	OK
7253	2026-09-15 11:27	59.21	OK	7254	2026-09-15 11:28	62.51	OK
7255	2026-09-15 11:29	59.85	OK	7256	2026-09-15 11:30	57.84	OK
7257	2026-09-15 11:31	61.11	OK	7258	2026-09-15 11:32	61.46	OK
7259	2026-09-15 11:33	57.56	OK	7260	2026-09-15 11:34	60.24	OK
7261	2026-09-15 11:35	59.58	OK	7262	2026-09-15 11:36	60.17	OK
7263	2026-09-15 11:37	61.49	OK	7264	2026-09-15 11:38	57.51	OK
7265	2026-09-15 11:39	58.44	OK	7266	2026-09-15 11:40	60.61	OK
7267	2026-09-15 11:41	59.09	OK	7268	2026-09-15 11:42	57.92	OK
7269	2026-09-15 11:43	59.24	OK	7270	2026-09-15 11:44	59.06	OK
7271	2026-09-15 11:45	60.01	OK	7272	2026-09-15 11:46	59.99	OK
7273	2026-09-15 11:47	59.98	OK	7274	2026-09-15 11:48	58.55	OK
7275	2026-09-15 11:49	61.83	OK	7276	2026-09-15 11:50	59.42	OK
7277	2026-09-15 11:51	59.39	OK	7278	2026-09-15 11:52	61.96	OK
7279	2026-09-15 11:53	59.74	OK	7280	2026-09-15 11:54	58.88	OK
7281	2026-09-15 11:55	59.86	OK	7282	2026-09-15 11:56	58.71	OK
7283	2026-09-15 11:57	60.23	OK	7284	2026-09-15 11:58	59.21	OK
7285	2026-09-15 11:59	58.59	OK	7286	2026-09-15 12:00	62.00	OK
7287	2026-09-15 12:01	60.93	OK	7288	2026-09-15 12:02	61.21	OK
7289	2026-09-15 12:03	62.18	OK	7290	2026-09-15 12:04	59.54	OK
7291	2026-09-15 12:05	60.41	OK	7292	2026-09-15 12:06	60.54	OK
7293	2026-09-15 12:07	60.63	OK	7294	2026-09-15 12:08	59.15	OK
7295	2026-09-15 12:09	59.10	OK	7296	2026-09-15 12:10	61.07	OK
7297	2026-09-15 12:11	61.72	OK	7298	2026-09-15 12:12	60.78	OK
7299	2026-09-15 12:13	61.39	OK	7300	2026-09-15 12:14	60.08	OK
7301	2026-09-15 12:15	62.84	OK	7302	2026-09-15 12:16	62.80	OK
7303	2026-09-15 12:17	60.33	OK	7304	2026-09-15 12:18	60.43	OK
7305	2026-09-15 12:19	58.51	OK	7306	2026-09-15 12:20	59.02	OK
7307	2026-09-15 12:21	61.57	OK	7308	2026-09-15 12:22	59.98	OK
7309	2026-09-15 12:23	60.00	OK	7310	2026-09-15 12:24	60.04	OK
7311	2026-09-15 12:25	59.00	OK	7312	2026-09-15 12:26	59.75	OK
7313	2026-09-15 12:27	59.41	OK	7314	2026-09-15 12:28	61.49	OK
7315	2026-09-15 12:29	60.44	OK	7316	2026-09-15 12:30	60.13	OK
7317	2026-09-15 12:31	60.60	OK	7318	2026-09-15 12:32	60.87	OK
7319	2026-09-15 12:33	60.26	OK	7320	2026-09-15 12:34	59.45	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7321	2026-09-15 12:35	60.71	OK	7322	2026-09-15 12:36	60.53	OK
7323	2026-09-15 12:37	59.20	OK	7324	2026-09-15 12:38	61.36	OK
7325	2026-09-15 12:39	60.01	OK	7326	2026-09-15 12:40	60.15	OK
7327	2026-09-15 12:41	60.31	OK	7328	2026-09-15 12:42	60.77	OK
7329	2026-09-15 12:43	63.07	OK	7330	2026-09-15 12:44	60.34	OK
7331	2026-09-15 12:45	58.77	OK	7332	2026-09-15 12:46	61.31	OK
7333	2026-09-15 12:47	60.12	OK	7334	2026-09-15 12:48	59.21	OK
7335	2026-09-15 12:49	60.96	OK	7336	2026-09-15 12:50	58.52	OK
7337	2026-09-15 12:51	59.68	OK	7338	2026-09-15 12:52	62.62	OK
7339	2026-09-15 12:53	58.27	OK	7340	2026-09-15 12:54	63.00	OK
7341	2026-09-15 12:55	59.62	OK	7342	2026-09-15 12:56	61.28	OK
7343	2026-09-15 12:57	61.79	OK	7344	2026-09-15 12:58	60.58	OK
7345	2026-09-15 12:59	61.17	OK	7346	2026-09-15 13:00	61.71	OK
7347	2026-09-15 13:01	62.95	OK	7348	2026-09-15 13:02	62.10	OK
7349	2026-09-15 13:03	62.41	OK	7350	2026-09-15 13:04	60.61	OK
7351	2026-09-15 13:05	60.68	OK	7352	2026-09-15 13:06	60.65	OK
7353	2026-09-15 13:07	59.18	OK	7354	2026-09-15 13:08	60.78	OK
7355	2026-09-15 13:09	59.62	OK	7356	2026-09-15 13:10	59.43	OK
7357	2026-09-15 13:11	60.88	OK	7358	2026-09-15 13:12	62.21	OK
7359	2026-09-15 13:13	63.40	OK	7360	2026-09-15 13:14	58.75	OK
7361	2026-09-15 13:15	61.81	OK	7362	2026-09-15 13:16	63.56	OK
7363	2026-09-15 13:17	60.01	OK	7364	2026-09-15 13:18	58.80	OK
7365	2026-09-15 13:19	59.67	OK	7366	2026-09-15 13:20	60.79	OK
7367	2026-09-15 13:21	63.44	OK	7368	2026-09-15 13:22	63.85	OK
7369	2026-09-15 13:23	59.78	OK	7370	2026-09-15 13:24	61.21	OK
7371	2026-09-15 13:25	61.32	OK	7372	2026-09-15 13:26	62.74	OK
7373	2026-09-15 13:27	63.00	OK	7374	2026-09-15 13:28	60.84	OK
7375	2026-09-15 13:29	61.76	OK	7376	2026-09-15 13:30	60.55	OK
7377	2026-09-15 13:31	58.91	OK	7378	2026-09-15 13:32	61.48	OK
7379	2026-09-15 13:33	63.33	OK	7380	2026-09-15 13:34	61.00	OK
7381	2026-09-15 13:35	61.15	OK	7382	2026-09-15 13:36	60.97	OK
7383	2026-09-15 13:37	62.22	OK	7384	2026-09-15 13:38	61.12	OK
7385	2026-09-15 13:39	62.42	OK	7386	2026-09-15 13:40	61.17	OK
7387	2026-09-15 13:41	61.95	OK	7388	2026-09-15 13:42	62.93	OK
7389	2026-09-15 13:43	62.90	OK	7390	2026-09-15 13:44	62.66	OK
7391	2026-09-15 13:45	60.00	OK	7392	2026-09-15 13:46	61.54	OK
7393	2026-09-15 13:47	62.02	OK	7394	2026-09-15 13:48	59.95	OK
7395	2026-09-15 13:49	60.92	OK	7396	2026-09-15 13:50	60.32	OK
7397	2026-09-15 13:51	60.40	OK	7398	2026-09-15 13:52	62.19	OK
7399	2026-09-15 13:53	62.02	OK	7400	2026-09-15 13:54	59.72	OK
7401	2026-09-15 13:55	61.42	OK	7402	2026-09-15 13:56	63.00	OK
7403	2026-09-15 13:57	59.78	OK	7404	2026-09-15 13:58	59.91	OK
7405	2026-09-15 13:59	61.17	OK	7406	2026-09-15 14:00	62.03	OK
7407	2026-09-15 14:01	60.63	OK	7408	2026-09-15 14:02	61.44	OK
7409	2026-09-15 14:03	61.58	OK	7410	2026-09-15 14:04	63.34	OK
7411	2026-09-15 14:05	60.62	OK	7412	2026-09-15 14:06	60.70	OK
7413	2026-09-15 14:07	61.46	OK	7414	2026-09-15 14:08	63.52	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7415	2026-09-15 14:09	61.16	OK	7416	2026-09-15 14:10	60.95	OK
7417	2026-09-15 14:11	60.68	OK	7418	2026-09-15 14:12	60.54	OK
7419	2026-09-15 14:13	62.21	OK	7420	2026-09-15 14:14	62.69	OK
7421	2026-09-15 14:15	61.91	OK	7422	2026-09-15 14:16	61.82	OK
7423	2026-09-15 14:17	62.95	OK	7424	2026-09-15 14:18	61.61	OK
7425	2026-09-15 14:19	60.37	OK	7426	2026-09-15 14:20	61.31	OK
7427	2026-09-15 14:21	60.36	OK	7428	2026-09-15 14:22	60.07	OK
7429	2026-09-15 14:23	61.83	OK	7430	2026-09-15 14:24	63.27	OK
7431	2026-09-15 14:25	61.86	OK	7432	2026-09-15 14:26	63.44	OK
7433	2026-09-15 14:27	63.68	OK	7434	2026-09-15 14:28	62.70	OK
7435	2026-09-15 14:29	61.89	OK	7436	2026-09-15 14:30	61.97	OK
7437	2026-09-15 14:31	62.37	OK	7438	2026-09-15 14:32	63.12	OK
7439	2026-09-15 14:33	61.79	OK	7440	2026-09-15 14:34	62.42	OK
7441	2026-09-15 14:35	62.74	OK	7442	2026-09-15 14:36	61.34	OK
7443	2026-09-15 14:37	63.35	OK	7444	2026-09-15 14:38	64.07	OK
7445	2026-09-15 14:39	62.15	OK	7446	2026-09-15 14:40	62.28	OK
7447	2026-09-15 14:41	61.55	OK	7448	2026-09-15 14:42	63.96	OK
7449	2026-09-15 14:43	61.42	OK	7450	2026-09-15 14:44	63.62	OK
7451	2026-09-15 14:45	64.86	OK	7452	2026-09-15 14:46	64.22	OK
7453	2026-09-15 14:47	65.36	OK	7454	2026-09-15 14:48	64.33	OK
7455	2026-09-15 14:49	64.07	OK	7456	2026-09-15 14:50	63.65	OK
7457	2026-09-15 14:51	62.40	OK	7458	2026-09-15 14:52	62.92	OK
7459	2026-09-15 14:53	63.79	OK	7460	2026-09-15 14:54	65.16	OK
7461	2026-09-15 14:55	63.68	OK	7462	2026-09-15 14:56	62.75	OK
7463	2026-09-15 14:57	62.17	OK	7464	2026-09-15 14:58	63.48	OK
7465	2026-09-15 14:59	61.19	OK	7466	2026-09-15 15:00	60.99	OK
7467	2026-09-15 15:01	63.85	OK	7468	2026-09-15 15:02	62.90	OK
7469	2026-09-15 15:03	64.79	OK	7470	2026-09-15 15:04	62.05	OK
7471	2026-09-15 15:05	63.96	OK	7472	2026-09-15 15:06	64.75	OK
7473	2026-09-15 15:07	64.90	OK	7474	2026-09-15 15:08	64.08	OK
7475	2026-09-15 15:09	65.43	OK	7476	2026-09-15 15:10	66.56	OK
7477	2026-09-15 15:11	65.15	OK	7478	2026-09-15 15:12	63.35	OK
7479	2026-09-15 15:13	61.02	OK	7480	2026-09-15 15:14	63.15	OK
7481	2026-09-15 15:15	64.02	OK	7482	2026-09-15 15:16	63.81	OK
7483	2026-09-15 15:17	60.81	OK	7484	2026-09-15 15:18	64.13	OK
7485	2026-09-15 15:19	65.61	OK	7486	2026-09-15 15:20	63.50	OK
7487	2026-09-15 15:21	62.38	OK	7488	2026-09-15 15:22	65.17	OK
7489	2026-09-15 15:23	63.82	OK	7490	2026-09-15 15:24	65.88	OK
7491	2026-09-15 15:25	63.81	OK	7492	2026-09-15 15:26	65.64	OK
7493	2026-09-15 15:27	65.14	OK	7494	2026-09-15 15:28	65.51	OK
7495	2026-09-15 15:29	65.94	OK	7496	2026-09-15 15:30	65.27	OK
7497	2026-09-15 15:31	63.73	OK	7498	2026-09-15 15:32	64.13	OK
7499	2026-09-15 15:33	64.70	OK	7500	2026-09-15 15:34	61.96	OK
7501	2026-09-15 15:35	64.16	OK	7502	2026-09-15 15:36	65.02	OK
7503	2026-09-15 15:37	64.12	OK	7504	2026-09-15 15:38	62.21	OK
7505	2026-09-15 15:39	64.08	OK	7506	2026-09-15 15:40	64.87	OK
7507	2026-09-15 15:41	63.57	OK	7508	2026-09-15 15:42	64.26	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7509	2026-09-15 15:43	64.38	OK	7510	2026-09-15 15:44	66.79	OK
7511	2026-09-15 15:45	62.87	OK	7512	2026-09-15 15:46	64.92	OK
7513	2026-09-15 15:47	65.21	OK	7514	2026-09-15 15:48	63.58	OK
7515	2026-09-15 15:49	65.17	OK	7516	2026-09-15 15:50	66.95	OK
7517	2026-09-15 15:51	65.54	OK	7518	2026-09-15 15:52	65.33	OK
7519	2026-09-15 15:53	64.05	OK	7520	2026-09-15 15:54	64.44	OK
7521	2026-09-15 15:55	64.23	OK	7522	2026-09-15 15:56	63.16	OK
7523	2026-09-15 15:57	63.54	OK	7524	2026-09-15 15:58	63.34	OK
7525	2026-09-15 15:59	66.09	OK	7526	2026-09-15 16:00	68.21	OK
7527	2026-09-15 16:01	63.49	OK	7528	2026-09-15 16:02	66.47	OK
7529	2026-09-15 16:03	64.95	OK	7530	2026-09-15 16:04	65.95	OK
7531	2026-09-15 16:05	63.53	OK	7532	2026-09-15 16:06	65.17	OK
7533	2026-09-15 16:07	64.35	OK	7534	2026-09-15 16:08	66.15	OK
7535	2026-09-15 16:09	63.83	OK	7536	2026-09-15 16:10	65.96	OK
7537	2026-09-15 16:11	65.92	OK	7538	2026-09-15 16:12	65.08	OK
7539	2026-09-15 16:13	65.88	OK	7540	2026-09-15 16:14	65.97	OK
7541	2026-09-15 16:15	64.62	OK	7542	2026-09-15 16:16	68.32	OK
7543	2026-09-15 16:17	63.47	OK	7544	2026-09-15 16:18	66.44	OK
7545	2026-09-15 16:19	65.93	OK	7546	2026-09-15 16:20	64.90	OK
7547	2026-09-15 16:21	65.78	OK	7548	2026-09-15 16:22	66.41	OK
7549	2026-09-15 16:23	66.10	OK	7550	2026-09-15 16:24	65.83	OK
7551	2026-09-15 16:25	67.56	OK	7552	2026-09-15 16:26	66.25	OK
7553	2026-09-15 16:27	67.10	OK	7554	2026-09-15 16:28	64.62	OK
7555	2026-09-15 16:29	64.34	OK	7556	2026-09-15 16:30	67.92	OK
7557	2026-09-15 16:31	66.70	OK	7558	2026-09-15 16:32	65.60	OK
7559	2026-09-15 16:33	66.57	OK	7560	2026-09-15 16:34	65.68	OK
7561	2026-09-15 16:35	67.38	OK	7562	2026-09-15 16:36	63.48	OK
7563	2026-09-15 16:37	64.84	OK	7564	2026-09-15 16:38	66.91	OK
7565	2026-09-15 16:39	67.14	OK	7566	2026-09-15 16:40	66.52	OK
7567	2026-09-15 16:41	66.40	OK	7568	2026-09-15 16:42	66.00	OK
7569	2026-09-15 16:43	66.10	OK	7570	2026-09-15 16:44	67.35	OK
7571	2026-09-15 16:45	67.14	OK	7572	2026-09-15 16:46	65.91	OK
7573	2026-09-15 16:47	64.95	OK	7574	2026-09-15 16:48	64.81	OK
7575	2026-09-15 16:49	66.60	OK	7576	2026-09-15 16:50	67.42	OK
7577	2026-09-15 16:51	68.46	OK	7578	2026-09-15 16:52	65.24	OK
7579	2026-09-15 16:53	66.26	OK	7580	2026-09-15 16:54	68.95	OK
7581	2026-09-15 16:55	64.99	OK	7582	2026-09-15 16:56	64.91	OK
7583	2026-09-15 16:57	64.87	OK	7584	2026-09-15 16:58	67.52	OK
7585	2026-09-15 16:59	67.07	OK	7586	2026-09-15 17:00	67.69	OK
7587	2026-09-15 17:01	67.58	OK	7588	2026-09-15 17:02	66.08	OK
7589	2026-09-15 17:03	69.00	OK	7590	2026-09-15 17:04	65.50	OK
7591	2026-09-15 17:05	64.99	OK	7592	2026-09-15 17:06	66.99	OK
7593	2026-09-15 17:07	68.11	OK	7594	2026-09-15 17:08	65.50	OK
7595	2026-09-15 17:09	66.51	OK	7596	2026-09-15 17:10	66.92	OK
7597	2026-09-15 17:11	65.90	OK	7598	2026-09-15 17:12	69.13	OK
7599	2026-09-15 17:13	68.09	OK	7600	2026-09-15 17:14	68.04	OK
7601	2026-09-15 17:15	64.69	OK	7602	2026-09-15 17:16	67.40	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7603	2026-09-15 17:17	68.10	OK	7604	2026-09-15 17:18	68.09	OK
7605	2026-09-15 17:19	67.85	OK	7606	2026-09-15 17:20	67.56	OK
7607	2026-09-15 17:21	65.59	OK	7608	2026-09-15 17:22	67.17	OK
7609	2026-09-15 17:23	65.13	OK	7610	2026-09-15 17:24	68.60	OK
7611	2026-09-15 17:25	66.77	OK	7612	2026-09-15 17:26	68.32	OK
7613	2026-09-15 17:27	68.69	OK	7614	2026-09-15 17:28	67.35	OK
7615	2026-09-15 17:29	65.37	OK	7616	2026-09-15 17:30	66.62	OK
7617	2026-09-15 17:31	66.88	OK	7618	2026-09-15 17:32	65.97	OK
7619	2026-09-15 17:33	67.32	OK	7620	2026-09-15 17:34	66.13	OK
7621	2026-09-15 17:35	68.92	OK	7622	2026-09-15 17:36	68.09	OK
7623	2026-09-15 17:37	67.42	OK	7624	2026-09-15 17:38	69.23	OK
7625	2026-09-15 17:39	67.53	OK	7626	2026-09-15 17:40	68.28	OK
7627	2026-09-15 17:41	69.29	OK	7628	2026-09-15 17:42	68.40	OK
7629	2026-09-15 17:43	69.18	OK	7630	2026-09-15 17:44	67.42	OK
7631	2026-09-15 17:45	68.51	OK	7632	2026-09-15 17:46	68.87	OK
7633	2026-09-15 17:47	69.97	OK	7634	2026-09-15 17:48	66.20	OK
7635	2026-09-15 17:49	67.14	OK	7636	2026-09-15 17:50	67.56	OK
7637	2026-09-15 17:51	67.66	OK	7638	2026-09-15 17:52	69.45	OK
7639	2026-09-15 17:53	68.13	OK	7640	2026-09-15 17:54	68.23	OK
7641	2026-09-15 17:55	65.73	OK	7642	2026-09-15 17:56	67.01	OK
7643	2026-09-15 17:57	66.91	OK	7644	2026-09-15 17:58	68.00	OK
7645	2026-09-15 17:59	68.03	OK	7646	2026-09-15 18:00	65.80	OK
7647	2026-09-15 18:01	69.61	OK	7648	2026-09-15 18:02	67.88	OK
7649	2026-09-15 18:03	66.25	OK	7650	2026-09-15 18:04	69.10	OK
7651	2026-09-15 18:05	68.98	OK	7652	2026-09-15 18:06	65.63	OK
7653	2026-09-15 18:07	67.81	OK	7654	2026-09-15 18:08	67.77	OK
7655	2026-09-15 18:09	70.68	OK	7656	2026-09-15 18:10	69.58	OK
7657	2026-09-15 18:11	70.06	OK	7658	2026-09-15 18:12	70.72	OK
7659	2026-09-15 18:13	67.96	OK	7660	2026-09-15 18:14	69.27	OK
7661	2026-09-15 18:15	68.71	OK	7662	2026-09-15 18:16	68.31	OK
7663	2026-09-15 18:17	68.20	OK	7664	2026-09-15 18:18	68.84	OK
7665	2026-09-15 18:19	67.25	OK	7666	2026-09-15 18:20	69.75	OK
7667	2026-09-15 18:21	68.52	OK	7668	2026-09-15 18:22	69.27	OK
7669	2026-09-15 18:23	69.12	OK	7670	2026-09-15 18:24	66.50	OK
7671	2026-09-15 18:25	70.04	OK	7672	2026-09-15 18:26	71.00	OK
7673	2026-09-15 18:27	69.39	OK	7674	2026-09-15 18:28	70.22	OK
7675	2026-09-15 18:29	67.39	OK	7676	2026-09-15 18:30	69.97	OK
7677	2026-09-15 18:31	68.85	OK	7678	2026-09-15 18:32	69.93	OK
7679	2026-09-15 18:33	68.62	OK	7680	2026-09-15 18:34	67.37	OK
7681	2026-09-15 18:35	70.78	OK	7682	2026-09-15 18:36	68.48	OK
7683	2026-09-15 18:37	72.23	OK	7684	2026-09-15 18:38	69.33	OK
7685	2026-09-15 18:39	67.85	OK	7686	2026-09-15 18:40	71.71	OK
7687	2026-09-15 18:41	69.17	OK	7688	2026-09-15 18:42	69.39	OK
7689	2026-09-15 18:43	69.17	OK	7690	2026-09-15 18:44	68.17	OK
7691	2026-09-15 18:45	71.37	OK	7692	2026-09-15 18:46	67.88	OK
7693	2026-09-15 18:47	70.18	OK	7694	2026-09-15 18:48	70.28	OK
7695	2026-09-15 18:49	69.82	OK	7696	2026-09-15 18:50	70.26	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7697	2026-09-15 18:51	70.36	OK	7698	2026-09-15 18:52	68.70	OK
7699	2026-09-15 18:53	69.28	OK	7700	2026-09-15 18:54	71.33	OK
7701	2026-09-15 18:55	70.90	OK	7702	2026-09-15 18:56	71.15	OK
7703	2026-09-15 18:57	71.98	OK	7704	2026-09-15 18:58	69.08	OK
7705	2026-09-15 18:59	69.60	OK	7706	2026-09-15 19:00	70.29	OK
7707	2026-09-15 19:01	70.05	OK	7708	2026-09-15 19:02	69.83	OK
7709	2026-09-15 19:03	69.85	OK	7710	2026-09-15 19:04	69.02	OK
7711	2026-09-15 19:05	70.38	OK	7712	2026-09-15 19:06	70.96	OK
7713	2026-09-15 19:07	66.76	OK	7714	2026-09-15 19:08	71.26	OK
7715	2026-09-15 19:09	68.49	OK	7716	2026-09-15 19:10	68.90	OK
7717	2026-09-15 19:11	71.27	OK	7718	2026-09-15 19:12	68.10	OK
7719	2026-09-15 19:13	72.79	OK	7720	2026-09-15 19:14	69.73	OK
7721	2026-09-15 19:15	71.33	OK	7722	2026-09-15 19:16	70.11	OK
7723	2026-09-15 19:17	68.00	OK	7724	2026-09-15 19:18	72.37	OK
7725	2026-09-15 19:19	70.62	OK	7726	2026-09-15 19:20	68.18	OK
7727	2026-09-15 19:21	72.49	OK	7728	2026-09-15 19:22	72.24	OK
7729	2026-09-15 19:23	71.10	OK	7730	2026-09-15 19:24	70.43	OK
7731	2026-09-15 19:25	71.96	OK	7732	2026-09-15 19:26	72.77	OK
7733	2026-09-15 19:27	70.40	OK	7734	2026-09-15 19:28	71.57	OK
7735	2026-09-15 19:29	72.31	OK	7736	2026-09-15 19:30	70.04	OK
7737	2026-09-15 19:31	68.33	OK	7738	2026-09-15 19:32	71.05	OK
7739	2026-09-15 19:33	72.25	OK	7740	2026-09-15 19:34	70.16	OK
7741	2026-09-15 19:35	71.25	OK	7742	2026-09-15 19:36	70.87	OK
7743	2026-09-15 19:37	70.64	OK	7744	2026-09-15 19:38	71.12	OK
7745	2026-09-15 19:39	69.89	OK	7746	2026-09-15 19:40	70.20	OK
7747	2026-09-15 19:41	68.63	OK	7748	2026-09-15 19:42	72.06	OK
7749	2026-09-15 19:43	71.32	OK	7750	2026-09-15 19:44	68.64	OK
7751	2026-09-15 19:45	71.65	OK	7752	2026-09-15 19:46	70.60	OK
7753	2026-09-15 19:47	72.39	OK	7754	2026-09-15 19:48	70.12	OK
7755	2026-09-15 19:49	71.02	OK	7756	2026-09-15 19:50	70.09	OK
7757	2026-09-15 19:51	72.75	OK	7758	2026-09-15 19:52	69.18	OK
7759	2026-09-15 19:53	69.77	OK	7760	2026-09-15 19:54	71.39	OK
7761	2026-09-15 19:55	72.78	OK	7762	2026-09-15 19:56	70.92	OK
7763	2026-09-15 19:57	72.62	OK	7764	2026-09-15 19:58	71.69	OK
7765	2026-09-15 19:59	71.05	OK	7766	2026-09-15 20:00	70.41	OK
7767	2026-09-15 20:01	69.04	OK	7768	2026-09-15 20:02	69.60	OK
7769	2026-09-15 20:03	70.41	OK	7770	2026-09-15 20:04	70.75	OK
7771	2026-09-15 20:05	70.40	OK	7772	2026-09-15 20:06	72.53	OK
7773	2026-09-15 20:07	71.63	OK	7774	2026-09-15 20:08	73.16	OK
7775	2026-09-15 20:09	70.54	OK	7776	2026-09-15 20:10	70.05	OK
7777	2026-09-15 20:11	70.24	OK	7778	2026-09-15 20:12	71.76	OK
7779	2026-09-15 20:13	70.85	OK	7780	2026-09-15 20:14	70.68	OK
7781	2026-09-15 20:15	70.00	OK	7782	2026-09-15 20:16	74.13	OK
7783	2026-09-15 20:17	73.85	OK	7784	2026-09-15 20:18	69.89	OK
7785	2026-09-15 20:19	70.22	OK	7786	2026-09-15 20:20	72.22	OK
7787	2026-09-15 20:21	71.37	OK	7788	2026-09-15 20:22	73.24	OK
7789	2026-09-15 20:23	69.90	OK	7790	2026-09-15 20:24	73.91	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7791	2026-09-15 20:25	71.71	OK	7792	2026-09-15 20:26	69.70	OK
7793	2026-09-15 20:27	73.08	OK	7794	2026-09-15 20:28	71.74	OK
7795	2026-09-15 20:29	71.63	OK	7796	2026-09-15 20:30	72.79	OK
7797	2026-09-15 20:31	72.88	OK	7798	2026-09-15 20:32	73.78	OK
7799	2026-09-15 20:33	72.02	OK	7800	2026-09-15 20:34	72.59	OK
7801	2026-09-15 20:35	70.18	OK	7802	2026-09-15 20:36	69.64	OK
7803	2026-09-15 20:37	72.62	OK	7804	2026-09-15 20:38	72.51	OK
7805	2026-09-15 20:39	71.45	OK	7806	2026-09-15 20:40	72.72	OK
7807	2026-09-15 20:41	69.00	OK	7808	2026-09-15 20:42	70.59	OK
7809	2026-09-15 20:43	71.00	OK	7810	2026-09-15 20:44	71.81	OK
7811	2026-09-15 20:45	70.04	OK	7812	2026-09-15 20:46	73.11	OK
7813	2026-09-15 20:47	73.20	OK	7814	2026-09-15 20:48	70.83	OK
7815	2026-09-15 20:49	70.71	OK	7816	2026-09-15 20:50	73.51	OK
7817	2026-09-15 20:51	73.65	OK	7818	2026-09-15 20:52	73.26	OK
7819	2026-09-15 20:53	71.14	OK	7820	2026-09-15 20:54	72.19	OK
7821	2026-09-15 20:55	73.41	OK	7822	2026-09-15 20:56	71.07	OK
7823	2026-09-15 20:57	73.31	OK	7824	2026-09-15 20:58	72.35	OK
7825	2026-09-15 20:59	71.29	OK	7826	2026-09-15 21:00	71.55	OK
7827	2026-09-15 21:01	73.28	OK	7828	2026-09-15 21:02	74.84	OK
7829	2026-09-15 21:03	70.75	OK	7830	2026-09-15 21:04	71.43	OK
7831	2026-09-15 21:05	72.02	OK	7832	2026-09-15 21:06	69.93	OK
7833	2026-09-15 21:07	72.25	OK	7834	2026-09-15 21:08	72.57	OK
7835	2026-09-15 21:09	73.41	OK	7836	2026-09-15 21:10	71.98	OK
7837	2026-09-15 21:11	72.21	OK	7838	2026-09-15 21:12	72.81	OK
7839	2026-09-15 21:13	70.61	OK	7840	2026-09-15 21:14	70.70	OK
7841	2026-09-15 21:15	73.18	OK	7842	2026-09-15 21:16	74.02	OK
7843	2026-09-15 21:17	72.35	OK	7844	2026-09-15 21:18	71.60	OK
7845	2026-09-15 21:19	70.74	OK	7846	2026-09-15 21:20	71.48	OK
7847	2026-09-15 21:21	71.14	OK	7848	2026-09-15 21:22	71.25	OK
7849	2026-09-15 21:23	71.65	OK	7850	2026-09-15 21:24	72.02	OK
7851	2026-09-15 21:25	73.00	OK	7852	2026-09-15 21:26	70.92	OK
7853	2026-09-15 21:27	72.63	OK	7854	2026-09-15 21:28	72.17	OK
7855	2026-09-15 21:29	70.89	OK	7856	2026-09-15 21:30	71.07	OK
7857	2026-09-15 21:31	71.65	OK	7858	2026-09-15 21:32	71.54	OK
7859	2026-09-15 21:33	72.76	OK	7860	2026-09-15 21:34	71.56	OK
7861	2026-09-15 21:35	71.80	OK	7862	2026-09-15 21:36	72.38	OK
7863	2026-09-15 21:37	72.53	OK	7864	2026-09-15 21:38	70.72	OK
7865	2026-09-15 21:39	74.55	OK	7866	2026-09-15 21:40	75.41	OK
7867	2026-09-15 21:41	72.43	OK	7868	2026-09-15 21:42	71.83	OK
7869	2026-09-15 21:43	72.25	OK	7870	2026-09-15 21:44	73.05	OK
7871	2026-09-15 21:45	71.75	OK	7872	2026-09-15 21:46	72.77	OK
7873	2026-09-15 21:47	73.25	OK	7874	2026-09-15 21:48	71.70	OK
7875	2026-09-15 21:49	73.18	OK	7876	2026-09-15 21:50	72.03	OK
7877	2026-09-15 21:51	72.61	OK	7878	2026-09-15 21:52	70.36	OK
7879	2026-09-15 21:53	73.08	OK	7880	2026-09-15 21:54	72.02	OK
7881	2026-09-15 21:55	72.27	OK	7882	2026-09-15 21:56	72.66	OK
7883	2026-09-15 21:57	72.55	OK	7884	2026-09-15 21:58	73.28	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7885	2026-09-15 21:59	73.57	OK	7886	2026-09-15 22:00	73.35	OK
7887	2026-09-15 22:01	71.55	OK	7888	2026-09-15 22:02	73.10	OK
7889	2026-09-15 22:03	75.44	OK	7890	2026-09-15 22:04	72.92	OK
7891	2026-09-15 22:05	71.02	OK	7892	2026-09-15 22:06	73.29	OK
7893	2026-09-15 22:07	72.86	OK	7894	2026-09-15 22:08	73.93	OK
7895	2026-09-15 22:09	72.97	OK	7896	2026-09-15 22:10	71.72	OK
7897	2026-09-15 22:11	72.15	OK	7898	2026-09-15 22:12	72.33	OK
7899	2026-09-15 22:13	72.48	OK	7900	2026-09-15 22:14	73.61	OK
7901	2026-09-15 22:15	71.68	OK	7902	2026-09-15 22:16	72.02	OK
7903	2026-09-15 22:17	74.19	OK	7904	2026-09-15 22:18	75.13	OK
7905	2026-09-15 22:19	74.18	OK	7906	2026-09-15 22:20	74.81	OK
7907	2026-09-15 22:21	73.52	OK	7908	2026-09-15 22:22	71.51	OK
7909	2026-09-15 22:23	71.29	OK	7910	2026-09-15 22:24	73.11	OK
7911	2026-09-15 22:25	73.67	OK	7912	2026-09-15 22:26	72.30	OK
7913	2026-09-15 22:27	70.77	OK	7914	2026-09-15 22:28	73.35	OK
7915	2026-09-15 22:29	74.85	OK	7916	2026-09-15 22:30	73.48	OK
7917	2026-09-15 22:31	73.34	OK	7918	2026-09-15 22:32	71.94	OK
7919	2026-09-15 22:33	72.90	OK	7920	2026-09-15 22:34	72.68	OK
7921	2026-09-15 22:35	69.63	OK	7922	2026-09-15 22:36	73.28	OK
7923	2026-09-15 22:37	72.49	OK	7924	2026-09-15 22:38	75.41	OK
7925	2026-09-15 22:39	69.40	OK	7926	2026-09-15 22:40	70.40	OK
7927	2026-09-15 22:41	71.28	OK	7928	2026-09-15 22:42	70.91	OK
7929	2026-09-15 22:43	70.89	OK	7930	2026-09-15 22:44	72.09	OK
7931	2026-09-15 22:45	75.45	OK	7932	2026-09-15 22:46	73.49	OK
7933	2026-09-15 22:47	73.82	OK	7934	2026-09-15 22:48	73.48	OK
7935	2026-09-15 22:49	73.47	OK	7936	2026-09-15 22:50	72.90	OK
7937	2026-09-15 22:51	72.53	OK	7938	2026-09-15 22:52	69.95	OK
7939	2026-09-15 22:53	71.53	OK	7940	2026-09-15 22:54	74.18	OK
7941	2026-09-15 22:55	71.97	OK	7942	2026-09-15 22:56	73.14	OK
7943	2026-09-15 22:57	73.59	OK	7944	2026-09-15 22:58	73.09	OK
7945	2026-09-15 22:59	73.85	OK	7946	2026-09-15 23:00	72.50	OK
7947	2026-09-15 23:01	72.37	OK	7948	2026-09-15 23:02	71.54	OK
7949	2026-09-15 23:03	72.78	OK	7950	2026-09-15 23:04	74.00	OK
7951	2026-09-15 23:05	73.04	OK	7952	2026-09-15 23:06	73.55	OK
7953	2026-09-15 23:07	73.92	OK	7954	2026-09-15 23:08	72.72	OK
7955	2026-09-15 23:09	74.17	OK	7956	2026-09-15 23:10	74.25	OK
7957	2026-09-15 23:11	73.89	OK	7958	2026-09-15 23:12	72.05	OK
7959	2026-09-15 23:13	75.29	OK	7960	2026-09-15 23:14	72.80	OK
7961	2026-09-15 23:15	70.40	OK	7962	2026-09-15 23:16	72.62	OK
7963	2026-09-15 23:17	72.77	OK	7964	2026-09-15 23:18	72.43	OK
7965	2026-09-15 23:19	70.55	OK	7966	2026-09-15 23:20	75.53	OK
7967	2026-09-15 23:21	71.02	OK	7968	2026-09-15 23:22	72.21	OK
7969	2026-09-15 23:23	73.05	OK	7970	2026-09-15 23:24	73.77	OK
7971	2026-09-15 23:25	74.18	OK	7972	2026-09-15 23:26	71.72	OK
7973	2026-09-15 23:27	71.96	OK	7974	2026-09-15 23:28	70.64	OK
7975	2026-09-15 23:29	71.08	OK	7976	2026-09-15 23:30	72.89	OK
7977	2026-09-15 23:31	70.34	OK	7978	2026-09-15 23:32	73.20	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7979	2026-09-15 23:33	73.50	OK	7980	2026-09-15 23:34	72.28	OK
7981	2026-09-15 23:35	73.36	OK	7982	2026-09-15 23:36	73.35	OK
7983	2026-09-15 23:37	72.03	OK	7984	2026-09-15 23:38	74.87	OK
7985	2026-09-15 23:39	70.79	OK	7986	2026-09-15 23:40	72.01	OK
7987	2026-09-15 23:41	72.18	OK	7988	2026-09-15 23:42	72.44	OK
7989	2026-09-15 23:43	71.25	OK	7990	2026-09-15 23:44	70.65	OK
7991	2026-09-15 23:45	73.19	OK	7992	2026-09-15 23:46	73.03	OK
7993	2026-09-15 23:47	72.08	OK	7994	2026-09-15 23:48	70.12	OK
7995	2026-09-15 23:49	73.16	OK	7996	2026-09-15 23:50	73.38	OK
7997	2026-09-15 23:51	74.45	OK	7998	2026-09-15 23:52	74.91	OK
7999	2026-09-15 23:53	73.61	OK	8000	2026-09-15 23:54	73.61	OK
8001	2026-09-15 23:55	71.39	OK	8002	2026-09-15 23:56	69.65	OK
8003	2026-09-15 23:57	69.62	OK	8004	2026-09-15 23:58	72.15	OK
8005	2026-09-15 23:59	74.52	OK	8006	2026-09-16 00:00	73.72	OK
8007	2026-09-16 00:01	71.93	OK	8008	2026-09-16 00:02	70.69	OK
8009	2026-09-16 00:03	71.86	OK	8010	2026-09-16 00:04	70.53	OK
8011	2026-09-16 00:05	72.26	OK	8012	2026-09-16 00:06	72.03	OK
8013	2026-09-16 00:07	72.87	OK	8014	2026-09-16 00:08	71.44	OK
8015	2026-09-16 00:09	71.69	OK	8016	2026-09-16 00:10	70.28	OK
8017	2026-09-16 00:11	72.65	OK	8018	2026-09-16 00:12	70.24	OK
8019	2026-09-16 00:13	73.26	OK	8020	2026-09-16 00:14	71.83	OK
8021	2026-09-16 00:15	71.77	OK	8022	2026-09-16 00:16	71.26	OK
8023	2026-09-16 00:17	74.90	OK	8024	2026-09-16 00:18	73.51	OK
8025	2026-09-16 00:19	71.62	OK	8026	2026-09-16 00:20	69.00	OK
8027	2026-09-16 00:21	72.22	OK	8028	2026-09-16 00:22	71.50	OK
8029	2026-09-16 00:23	71.95	OK	8030	2026-09-16 00:24	70.42	OK
8031	2026-09-16 00:25	71.34	OK	8032	2026-09-16 00:26	72.12	OK
8033	2026-09-16 00:27	71.33	OK	8034	2026-09-16 00:28	71.56	OK
8035	2026-09-16 00:29	72.15	OK	8036	2026-09-16 00:30	72.80	OK
8037	2026-09-16 00:31	70.79	OK	8038	2026-09-16 00:32	72.76	OK
8039	2026-09-16 00:33	70.65	OK	8040	2026-09-16 00:34	73.01	OK
8041	2026-09-16 00:35	71.89	OK	8042	2026-09-16 00:36	72.36	OK
8043	2026-09-16 00:37	70.19	OK	8044	2026-09-16 00:38	71.75	OK
8045	2026-09-16 00:39	72.80	OK	8046	2026-09-16 00:40	70.50	OK
8047	2026-09-16 00:41	72.68	OK	8048	2026-09-16 00:42	69.66	OK
8049	2026-09-16 00:43	69.46	OK	8050	2026-09-16 00:44	70.07	OK
8051	2026-09-16 00:45	71.26	OK	8052	2026-09-16 00:46	73.06	OK
8053	2026-09-16 00:47	70.39	OK	8054	2026-09-16 00:48	70.71	OK
8055	2026-09-16 00:49	71.84	OK	8056	2026-09-16 00:50	69.23	OK
8057	2026-09-16 00:51	70.99	OK	8058	2026-09-16 00:52	70.58	OK
8059	2026-09-16 00:53	72.08	OK	8060	2026-09-16 00:54	70.82	OK
8061	2026-09-16 00:55	71.89	OK	8062	2026-09-16 00:56	70.65	OK
8063	2026-09-16 00:57	72.50	OK	8064	2026-09-16 00:58	70.75	OK
8065	2026-09-16 00:59	73.73	OK	8066	2026-09-16 01:00	71.72	OK
8067	2026-09-16 01:01	69.98	OK	8068	2026-09-16 01:02	71.38	OK
8069	2026-09-16 01:03	72.96	OK	8070	2026-09-16 01:04	71.66	OK
8071	2026-09-16 01:05	73.76	OK	8072	2026-09-16 01:06	72.67	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8073	2026-09-16 01:07	70.89	OK	8074	2026-09-16 01:08	69.51	OK
8075	2026-09-16 01:09	72.16	OK	8076	2026-09-16 01:10	70.67	OK
8077	2026-09-16 01:11	71.33	OK	8078	2026-09-16 01:12	72.54	OK
8079	2026-09-16 01:13	70.57	OK	8080	2026-09-16 01:14	73.25	OK
8081	2026-09-16 01:15	71.97	OK	8082	2026-09-16 01:16	72.58	OK
8083	2026-09-16 01:17	70.13	OK	8084	2026-09-16 01:18	68.63	OK
8085	2026-09-16 01:19	71.44	OK	8086	2026-09-16 01:20	70.71	OK
8087	2026-09-16 01:21	71.10	OK	8088	2026-09-16 01:22	71.89	OK
8089	2026-09-16 01:23	72.31	OK	8090	2026-09-16 01:24	72.16	OK
8091	2026-09-16 01:25	71.96	OK	8092	2026-09-16 01:26	70.80	OK
8093	2026-09-16 01:27	72.58	OK	8094	2026-09-16 01:28	71.81	OK
8095	2026-09-16 01:29	73.07	OK	8096	2026-09-16 01:30	69.85	OK
8097	2026-09-16 01:31	71.22	OK	8098	2026-09-16 01:32	68.97	OK
8099	2026-09-16 01:33	72.30	OK	8100	2026-09-16 01:34	71.75	OK
8101	2026-09-16 01:35	69.65	OK	8102	2026-09-16 01:36	69.23	OK
8103	2026-09-16 01:37	71.54	OK	8104	2026-09-16 01:38	71.14	OK
8105	2026-09-16 01:39	69.70	OK	8106	2026-09-16 01:40	69.20	OK
8107	2026-09-16 01:41	71.78	OK	8108	2026-09-16 01:42	71.64	OK
8109	2026-09-16 01:43	71.55	OK	8110	2026-09-16 01:44	68.87	OK
8111	2026-09-16 01:45	70.84	OK	8112	2026-09-16 01:46	71.55	OK
8113	2026-09-16 01:47	70.84	OK	8114	2026-09-16 01:48	70.34	OK
8115	2026-09-16 01:49	68.80	OK	8116	2026-09-16 01:50	68.81	OK
8117	2026-09-16 01:51	70.72	OK	8118	2026-09-16 01:52	70.21	OK
8119	2026-09-16 01:53	70.25	OK	8120	2026-09-16 01:54	72.88	OK
8121	2026-09-16 01:55	69.45	OK	8122	2026-09-16 01:56	70.10	OK
8123	2026-09-16 01:57	70.53	OK	8124	2026-09-16 01:58	69.38	OK
8125	2026-09-16 01:59	73.11	OK	8126	2026-09-16 02:00	70.02	OK
8127	2026-09-16 02:01	72.06	OK	8128	2026-09-16 02:02	70.30	OK
8129	2026-09-16 02:03	68.26	OK	8130	2026-09-16 02:04	71.35	OK
8131	2026-09-16 02:05	70.62	OK	8132	2026-09-16 02:06	73.11	OK
8133	2026-09-16 02:07	70.23	OK	8134	2026-09-16 02:08	69.03	OK
8135	2026-09-16 02:09	68.93	OK	8136	2026-09-16 02:10	71.29	OK
8137	2026-09-16 02:11	72.24	OK	8138	2026-09-16 02:12	72.44	OK
8139	2026-09-16 02:13	71.94	OK	8140	2026-09-16 02:14	70.36	OK
8141	2026-09-16 02:15	69.48	OK	8142	2026-09-16 02:16	69.25	OK
8143	2026-09-16 02:17	71.67	OK	8144	2026-09-16 02:18	69.04	OK
8145	2026-09-16 02:19	69.87	OK	8146	2026-09-16 02:20	69.68	OK
8147	2026-09-16 02:21	69.83	OK	8148	2026-09-16 02:22	70.66	OK
8149	2026-09-16 02:23	71.18	OK	8150	2026-09-16 02:24	70.17	OK
8151	2026-09-16 02:25	69.72	OK	8152	2026-09-16 02:26	73.02	OK
8153	2026-09-16 02:27	69.98	OK	8154	2026-09-16 02:28	71.16	OK
8155	2026-09-16 02:29	68.92	OK	8156	2026-09-16 02:30	71.49	OK
8157	2026-09-16 02:31	68.05	OK	8158	2026-09-16 02:32	71.20	OK
8159	2026-09-16 02:33	68.78	OK	8160	2026-09-16 02:34	70.63	OK
8161	2026-09-16 02:35	68.67	OK	8162	2026-09-16 02:36	70.65	OK
8163	2026-09-16 02:37	71.17	OK	8164	2026-09-16 02:38	69.35	OK
8165	2026-09-16 02:39	71.53	OK	8166	2026-09-16 02:40	68.04	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8167	2026-09-16 02:41	67.84	OK	8168	2026-09-16 02:42	70.43	OK
8169	2026-09-16 02:43	68.19	OK	8170	2026-09-16 02:44	68.50	OK
8171	2026-09-16 02:45	67.79	OK	8172	2026-09-16 02:46	68.77	OK
8173	2026-09-16 02:47	70.43	OK	8174	2026-09-16 02:48	70.16	OK
8175	2026-09-16 02:49	67.16	OK	8176	2026-09-16 02:50	70.03	OK
8177	2026-09-16 02:51	68.99	OK	8178	2026-09-16 02:52	70.92	OK
8179	2026-09-16 02:53	68.49	OK	8180	2026-09-16 02:54	68.55	OK
8181	2026-09-16 02:55	67.23	OK	8182	2026-09-16 02:56	69.35	OK
8183	2026-09-16 02:57	65.90	OK	8184	2026-09-16 02:58	70.80	OK
8185	2026-09-16 02:59	67.36	OK	8186	2026-09-16 03:00	68.01	OK
8187	2026-09-16 03:01	70.37	OK	8188	2026-09-16 03:02	70.91	OK
8189	2026-09-16 03:03	68.39	OK	8190	2026-09-16 03:04	71.31	OK
8191	2026-09-16 03:05	68.00	OK	8192	2026-09-16 03:06	69.11	OK
8193	2026-09-16 03:07	69.00	OK	8194	2026-09-16 03:08	69.43	OK
8195	2026-09-16 03:09	69.28	OK	8196	2026-09-16 03:10	70.23	OK
8197	2026-09-16 03:11	67.62	OK	8198	2026-09-16 03:12	71.30	OK
8199	2026-09-16 03:13	69.04	OK	8200	2026-09-16 03:14	69.19	OK
8201	2026-09-16 03:15	68.37	OK	8202	2026-09-16 03:16	68.83	OK
8203	2026-09-16 03:17	68.67	OK	8204	2026-09-16 03:18	67.78	OK
8205	2026-09-16 03:19	68.62	OK	8206	2026-09-16 03:20	68.64	OK
8207	2026-09-16 03:21	66.02	OK	8208	2026-09-16 03:22	68.44	OK
8209	2026-09-16 03:23	66.03	OK	8210	2026-09-16 03:24	69.01	OK
8211	2026-09-16 03:25	68.96	OK	8212	2026-09-16 03:26	69.33	OK
8213	2026-09-16 03:27	67.96	OK	8214	2026-09-16 03:28	66.49	OK
8215	2026-09-16 03:29	67.85	OK	8216	2026-09-16 03:30	68.94	OK
8217	2026-09-16 03:31	70.25	OK	8218	2026-09-16 03:32	68.90	OK
8219	2026-09-16 03:33	66.61	OK	8220	2026-09-16 03:34	66.90	OK
8221	2026-09-16 03:35	69.11	OK	8222	2026-09-16 03:36	67.32	OK
8223	2026-09-16 03:37	68.55	OK	8224	2026-09-16 03:38	68.43	OK
8225	2026-09-16 03:39	67.23	OK	8226	2026-09-16 03:40	66.68	OK
8227	2026-09-16 03:41	70.16	OK	8228	2026-09-16 03:42	68.86	OK
8229	2026-09-16 03:43	67.75	OK	8230	2026-09-16 03:44	66.60	OK
8231	2026-09-16 03:45	67.17	OK	8232	2026-09-16 03:46	67.01	OK
8233	2026-09-16 03:47	67.64	OK	8234	2026-09-16 03:48	67.69	OK
8235	2026-09-16 03:49	68.61	OK	8236	2026-09-16 03:50	69.91	OK
8237	2026-09-16 03:51	69.22	OK	8238	2026-09-16 03:52	69.06	OK
8239	2026-09-16 03:53	67.82	OK	8240	2026-09-16 03:54	66.42	OK
8241	2026-09-16 03:55	67.86	OK	8242	2026-09-16 03:56	65.64	OK
8243	2026-09-16 03:57	67.93	OK	8244	2026-09-16 03:58	67.78	OK
8245	2026-09-16 03:59	67.22	OK	8246	2026-09-16 04:00	64.97	OK
8247	2026-09-16 04:01	67.21	OK	8248	2026-09-16 04:02	66.93	OK
8249	2026-09-16 04:03	66.86	OK	8250	2026-09-16 04:04	66.24	OK
8251	2026-09-16 04:05	66.41	OK	8252	2026-09-16 04:06	67.38	OK
8253	2026-09-16 04:07	65.98	OK	8254	2026-09-16 04:08	66.65	OK
8255	2026-09-16 04:09	68.47	OK	8256	2026-09-16 04:10	67.44	OK
8257	2026-09-16 04:11	69.93	OK	8258	2026-09-16 04:12	66.22	OK
8259	2026-09-16 04:13	66.64	OK	8260	2026-09-16 04:14	66.67	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8261	2026-09-16 04:15	64.34	OK	8262	2026-09-16 04:16	68.36	OK
8263	2026-09-16 04:17	66.89	OK	8264	2026-09-16 04:18	66.57	OK
8265	2026-09-16 04:19	66.52	OK	8266	2026-09-16 04:20	65.18	OK
8267	2026-09-16 04:21	67.25	OK	8268	2026-09-16 04:22	66.62	OK
8269	2026-09-16 04:23	65.02	OK	8270	2026-09-16 04:24	68.78	OK
8271	2026-09-16 04:25	65.22	OK	8272	2026-09-16 04:26	66.85	OK
8273	2026-09-16 04:27	67.73	OK	8274	2026-09-16 04:28	67.37	OK
8275	2026-09-16 04:29	67.91	OK	8276	2026-09-16 04:30	66.52	OK
8277	2026-09-16 04:31	67.14	OK	8278	2026-09-16 04:32	65.25	OK
8279	2026-09-16 04:33	68.88	OK	8280	2026-09-16 04:34	65.99	OK
8281	2026-09-16 04:35	64.01	OK	8282	2026-09-16 04:36	67.12	OK
8283	2026-09-16 04:37	65.97	OK	8284	2026-09-16 04:38	66.74	OK
8285	2026-09-16 04:39	65.30	OK	8286	2026-09-16 04:40	65.35	OK
8287	2026-09-16 04:41	64.27	OK	8288	2026-09-16 04:42	65.59	OK
8289	2026-09-16 04:43	67.76	OK	8290	2026-09-16 04:44	65.31	OK
8291	2026-09-16 04:45	64.19	OK	8292	2026-09-16 04:46	67.30	OK
8293	2026-09-16 04:47	66.62	OK	8294	2026-09-16 04:48	68.63	OK
8295	2026-09-16 04:49	64.37	OK	8296	2026-09-16 04:50	68.01	OK
8297	2026-09-16 04:51	66.18	OK	8298	2026-09-16 04:52	63.74	OK
8299	2026-09-16 04:53	65.89	OK	8300	2026-09-16 04:54	66.30	OK
8301	2026-09-16 04:55	65.70	OK	8302	2026-09-16 04:56	64.46	OK
8303	2026-09-16 04:57	65.07	OK	8304	2026-09-16 04:58	65.94	OK
8305	2026-09-16 04:59	63.44	OK	8306	2026-09-16 05:00	66.69	OK
8307	2026-09-16 05:01	65.81	OK	8308	2026-09-16 05:02	64.92	OK
8309	2026-09-16 05:03	65.08	OK	8310	2026-09-16 05:04	63.16	OK
8311	2026-09-16 05:05	63.50	OK	8312	2026-09-16 05:06	65.15	OK
8313	2026-09-16 05:07	64.98	OK	8314	2026-09-16 05:08	66.35	OK
8315	2026-09-16 05:09	65.26	OK	8316	2026-09-16 05:10	65.48	OK
8317	2026-09-16 05:11	65.63	OK	8318	2026-09-16 05:12	65.55	OK
8319	2026-09-16 05:13	63.86	OK	8320	2026-09-16 05:14	62.42	OK
8321	2026-09-16 05:15	64.26	OK	8322	2026-09-16 05:16	64.65	OK
8323	2026-09-16 05:17	63.90	OK	8324	2026-09-16 05:18	66.55	OK
8325	2026-09-16 05:19	64.06	OK	8326	2026-09-16 05:20	62.95	OK
8327	2026-09-16 05:21	65.88	OK	8328	2026-09-16 05:22	64.42	OK
8329	2026-09-16 05:23	67.13	OK	8330	2026-09-16 05:24	65.20	OK
8331	2026-09-16 05:25	64.62	OK	8332	2026-09-16 05:26	64.04	OK
8333	2026-09-16 05:27	62.45	OK	8334	2026-09-16 05:28	64.02	OK
8335	2026-09-16 05:29	65.43	OK	8336	2026-09-16 05:30	63.21	OK
8337	2026-09-16 05:31	64.59	OK	8338	2026-09-16 05:32	65.15	OK
8339	2026-09-16 05:33	64.94	OK	8340	2026-09-16 05:34	63.11	OK
8341	2026-09-16 05:35	66.12	OK	8342	2026-09-16 05:36	65.72	OK
8343	2026-09-16 05:37	64.44	OK	8344	2026-09-16 05:38	66.12	OK
8345	2026-09-16 05:39	64.37	OK	8346	2026-09-16 05:40	65.87	OK
8347	2026-09-16 05:41	64.13	OK	8348	2026-09-16 05:42	64.81	OK
8349	2026-09-16 05:43	62.77	OK	8350	2026-09-16 05:44	63.55	OK
8351	2026-09-16 05:45	65.50	OK	8352	2026-09-16 05:46	62.90	OK
8353	2026-09-16 05:47	63.93	OK	8354	2026-09-16 05:48	63.56	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8355	2026-09-16 05:49	67.52	OK	8356	2026-09-16 05:50	64.47	OK
8357	2026-09-16 05:51	66.74	OK	8358	2026-09-16 05:52	64.88	OK
8359	2026-09-16 05:53	63.95	OK	8360	2026-09-16 05:54	66.47	OK
8361	2026-09-16 05:55	65.74	OK	8362	2026-09-16 05:56	64.28	OK
8363	2026-09-16 05:57	63.22	OK	8364	2026-09-16 05:58	63.66	OK
8365	2026-09-16 05:59	62.76	OK	8366	2026-09-16 06:00	63.98	OK
8367	2026-09-16 06:01	64.19	OK	8368	2026-09-16 06:02	64.01	OK
8369	2026-09-16 06:03	62.48	OK	8370	2026-09-16 06:04	64.45	OK
8371	2026-09-16 06:05	63.81	OK	8372	2026-09-16 06:06	64.28	OK
8373	2026-09-16 06:07	63.29	OK	8374	2026-09-16 06:08	62.47	OK
8375	2026-09-16 06:09	61.25	OK	8376	2026-09-16 06:10	63.27	OK
8377	2026-09-16 06:11	63.63	OK	8378	2026-09-16 06:12	62.85	OK
8379	2026-09-16 06:13	62.87	OK	8380	2026-09-16 06:14	63.59	OK
8381	2026-09-16 06:15	64.33	OK	8382	2026-09-16 06:16	62.03	OK
8383	2026-09-16 06:17	64.15	OK	8384	2026-09-16 06:18	63.29	OK
8385	2026-09-16 06:19	64.24	OK	8386	2026-09-16 06:20	64.54	OK
8387	2026-09-16 06:21	64.29	OK	8388	2026-09-16 06:22	61.72	OK
8389	2026-09-16 06:23	64.33	OK	8390	2026-09-16 06:24	63.65	OK
8391	2026-09-16 06:25	63.19	OK	8392	2026-09-16 06:26	62.65	OK
8393	2026-09-16 06:27	62.81	OK	8394	2026-09-16 06:28	61.81	OK
8395	2026-09-16 06:29	62.82	OK	8396	2026-09-16 06:30	61.91	OK
8397	2026-09-16 06:31	65.01	OK	8398	2026-09-16 06:32	64.07	OK
8399	2026-09-16 06:33	62.01	OK	8400	2026-09-16 06:34	63.95	OK
8401	2026-09-16 06:35	64.55	OK	8402	2026-09-16 06:36	60.98	OK
8403	2026-09-16 06:37	65.40	OK	8404	2026-09-16 06:38	63.04	OK
8405	2026-09-16 06:39	64.52	OK	8406	2026-09-16 06:40	62.92	OK
8407	2026-09-16 06:41	65.16	OK	8408	2026-09-16 06:42	64.31	OK
8409	2026-09-16 06:43	61.57	OK	8410	2026-09-16 06:44	61.69	OK
8411	2026-09-16 06:45	63.99	OK	8412	2026-09-16 06:46	65.04	OK
8413	2026-09-16 06:47	63.41	OK	8414	2026-09-16 06:48	62.56	OK
8415	2026-09-16 06:49	63.14	OK	8416	2026-09-16 06:50	62.29	OK
8417	2026-09-16 06:51	63.90	OK	8418	2026-09-16 06:52	62.99	OK
8419	2026-09-16 06:53	64.28	OK	8420	2026-09-16 06:54	63.12	OK
8421	2026-09-16 06:55	62.07	OK	8422	2026-09-16 06:56	61.74	OK
8423	2026-09-16 06:57	61.18	OK	8424	2026-09-16 06:58	62.99	OK
8425	2026-09-16 06:59	63.43	OK	8426	2026-09-16 07:00	59.95	OK
8427	2026-09-16 07:01	63.63	OK	8428	2026-09-16 07:02	63.10	OK
8429	2026-09-16 07:03	61.56	OK	8430	2026-09-16 07:04	61.68	OK
8431	2026-09-16 07:05	62.16	OK	8432	2026-09-16 07:06	59.16	OK
8433	2026-09-16 07:07	59.36	OK	8434	2026-09-16 07:08	63.71	OK
8435	2026-09-16 07:09	62.23	OK	8436	2026-09-16 07:10	62.23	OK
8437	2026-09-16 07:11	62.66	OK	8438	2026-09-16 07:12	60.87	OK
8439	2026-09-16 07:13	62.50	OK	8440	2026-09-16 07:14	62.68	OK
8441	2026-09-16 07:15	60.33	OK	8442	2026-09-16 07:16	62.14	OK
8443	2026-09-16 07:17	61.09	OK	8444	2026-09-16 07:18	62.51	OK
8445	2026-09-16 07:19	63.81	OK	8446	2026-09-16 07:20	62.53	OK
8447	2026-09-16 07:21	61.04	OK	8448	2026-09-16 07:22	61.28	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8449	2026-09-16 07:23	61.21	OK	8450	2026-09-16 07:24	63.83	OK
8451	2026-09-16 07:25	63.54	OK	8452	2026-09-16 07:26	60.18	OK
8453	2026-09-16 07:27	61.98	OK	8454	2026-09-16 07:28	62.93	OK
8455	2026-09-16 07:29	62.23	OK	8456	2026-09-16 07:30	62.01	OK
8457	2026-09-16 07:31	60.34	OK	8458	2026-09-16 07:32	62.42	OK
8459	2026-09-16 07:33	61.03	OK	8460	2026-09-16 07:34	60.70	OK
8461	2026-09-16 07:35	61.41	OK	8462	2026-09-16 07:36	61.36	OK
8463	2026-09-16 07:37	61.91	OK	8464	2026-09-16 07:38	61.43	OK
8465	2026-09-16 07:39	61.38	OK	8466	2026-09-16 07:40	60.72	OK
8467	2026-09-16 07:41	61.32	OK	8468	2026-09-16 07:42	61.64	OK
8469	2026-09-16 07:43	61.20	OK	8470	2026-09-16 07:44	61.49	OK
8471	2026-09-16 07:45	62.10	OK	8472	2026-09-16 07:46	61.24	OK
8473	2026-09-16 07:47	60.54	OK	8474	2026-09-16 07:48	61.68	OK
8475	2026-09-16 07:49	61.82	OK	8476	2026-09-16 07:50	59.31	OK
8477	2026-09-16 07:51	63.36	OK	8478	2026-09-16 07:52	62.01	OK
8479	2026-09-16 07:53	59.23	OK	8480	2026-09-16 07:54	61.20	OK
8481	2026-09-16 07:55	61.03	OK	8482	2026-09-16 07:56	61.92	OK
8483	2026-09-16 07:57	62.47	OK	8484	2026-09-16 07:58	59.82	OK
8485	2026-09-16 07:59	61.43	OK	8486	2026-09-16 08:00	59.63	OK
8487	2026-09-16 08:01	60.53	OK	8488	2026-09-16 08:02	62.70	OK
8489	2026-09-16 08:03	62.06	OK	8490	2026-09-16 08:04	60.33	OK
8491	2026-09-16 08:05	61.57	OK	8492	2026-09-16 08:06	58.58	OK
8493	2026-09-16 08:07	61.25	OK	8494	2026-09-16 08:08	60.74	OK
8495	2026-09-16 08:09	61.52	OK	8496	2026-09-16 08:10	61.32	OK
8497	2026-09-16 08:11	60.89	OK	8498	2026-09-16 08:12	62.84	OK
8499	2026-09-16 08:13	60.60	OK	8500	2026-09-16 08:14	61.09	OK
8501	2026-09-16 08:15	61.42	OK	8502	2026-09-16 08:16	59.55	OK
8503	2026-09-16 08:17	60.52	OK	8504	2026-09-16 08:18	59.25	OK
8505	2026-09-16 08:19	61.98	OK	8506	2026-09-16 08:20	61.10	OK
8507	2026-09-16 08:21	61.42	OK	8508	2026-09-16 08:22	60.33	OK
8509	2026-09-16 08:23	62.58	OK	8510	2026-09-16 08:24	57.91	OK
8511	2026-09-16 08:25	62.70	OK	8512	2026-09-16 08:26	61.13	OK
8513	2026-09-16 08:27	62.32	OK	8514	2026-09-16 08:28	60.01	OK
8515	2026-09-16 08:29	58.47	OK	8516	2026-09-16 08:30	62.18	OK
8517	2026-09-16 08:31	57.71	OK	8518	2026-09-16 08:32	59.91	OK
8519	2026-09-16 08:33	62.02	OK	8520	2026-09-16 08:34	60.49	OK
8521	2026-09-16 08:35	62.53	OK	8522	2026-09-16 08:36	63.67	OK
8523	2026-09-16 08:37	61.12	OK	8524	2026-09-16 08:38	59.45	OK
8525	2026-09-16 08:39	61.31	OK	8526	2026-09-16 08:40	59.38	OK
8527	2026-09-16 08:41	57.60	OK	8528	2026-09-16 08:42	60.19	OK
8529	2026-09-16 08:43	59.07	OK	8530	2026-09-16 08:44	59.19	OK
8531	2026-09-16 08:45	60.19	OK	8532	2026-09-16 08:46	58.39	OK
8533	2026-09-16 08:47	61.15	OK	8534	2026-09-16 08:48	62.22	OK
8535	2026-09-16 08:49	59.27	OK	8536	2026-09-16 08:50	62.02	OK
8537	2026-09-16 08:51	60.05	OK	8538	2026-09-16 08:52	60.92	OK
8539	2026-09-16 08:53	58.96	OK	8540	2026-09-16 08:54	61.79	OK
8541	2026-09-16 08:55	58.57	OK	8542	2026-09-16 08:56	61.20	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8543	2026-09-16 08:57	60.33	OK	8544	2026-09-16 08:58	60.69	OK
8545	2026-09-16 08:59	61.64	OK	8546	2026-09-16 09:00	58.49	OK
8547	2026-09-16 09:01	60.23	OK	8548	2026-09-16 09:02	60.20	OK
8549	2026-09-16 09:03	58.44	OK	8550	2026-09-16 09:04	57.63	OK
8551	2026-09-16 09:05	59.98	OK	8552	2026-09-16 09:06	57.77	OK
8553	2026-09-16 09:07	60.99	OK	8554	2026-09-16 09:08	61.63	OK
8555	2026-09-16 09:09	58.40	OK	8556	2026-09-16 09:10	59.97	OK
8557	2026-09-16 09:11	61.10	OK	8558	2026-09-16 09:12	61.25	OK
8559	2026-09-16 09:13	57.47	OK	8560	2026-09-16 09:14	59.07	OK
8561	2026-09-16 09:15	60.97	OK	8562	2026-09-16 09:16	58.71	OK
8563	2026-09-16 09:17	59.34	OK	8564	2026-09-16 09:18	59.60	OK
8565	2026-09-16 09:19	62.59	OK	8566	2026-09-16 09:20	59.72	OK
8567	2026-09-16 09:21	59.91	OK	8568	2026-09-16 09:22	60.10	OK
8569	2026-09-16 09:23	57.54	OK	8570	2026-09-16 09:24	59.04	OK
8571	2026-09-16 09:25	60.38	OK	8572	2026-09-16 09:26	59.42	OK
8573	2026-09-16 09:27	58.95	OK	8574	2026-09-16 09:28	59.89	OK
8575	2026-09-16 09:29	59.89	OK	8576	2026-09-16 09:30	61.09	OK
8577	2026-09-16 09:31	60.46	OK	8578	2026-09-16 09:32	60.71	OK
8579	2026-09-16 09:33	57.60	OK	8580	2026-09-16 09:34	59.39	OK
8581	2026-09-16 09:35	61.10	OK	8582	2026-09-16 09:36	59.41	OK
8583	2026-09-16 09:37	59.18	OK	8584	2026-09-16 09:38	57.87	OK
8585	2026-09-16 09:39	61.27	OK	8586	2026-09-16 09:40	60.46	OK
8587	2026-09-16 09:41	60.22	OK	8588	2026-09-16 09:42	60.95	OK
8589	2026-09-16 09:43	59.10	OK	8590	2026-09-16 09:44	59.29	OK
8591	2026-09-16 09:45	60.45	OK	8592	2026-09-16 09:46	61.97	OK
8593	2026-09-16 09:47	59.56	OK	8594	2026-09-16 09:48	59.31	OK
8595	2026-09-16 09:49	57.53	OK	8596	2026-09-16 09:50	61.12	OK
8597	2026-09-16 09:51	60.52	OK	8598	2026-09-16 09:52	61.38	OK
8599	2026-09-16 09:53	62.11	OK	8600	2026-09-16 09:54	62.04	OK
8601	2026-09-16 09:55	61.29	OK	8602	2026-09-16 09:56	58.37	OK
8603	2026-09-16 09:57	57.99	OK	8604	2026-09-16 09:58	59.35	OK
8605	2026-09-16 09:59	57.28	OK	8606	2026-09-16 10:00	59.88	OK
8607	2026-09-16 10:01	59.16	OK	8608	2026-09-16 10:02	58.75	OK
8609	2026-09-16 10:03	62.02	OK	8610	2026-09-16 10:04	61.96	OK
8611	2026-09-16 10:05	59.09	OK	8612	2026-09-16 10:06	56.53	OK
8613	2026-09-16 10:07	61.52	OK	8614	2026-09-16 10:08	60.54	OK
8615	2026-09-16 10:09	59.44	OK	8616	2026-09-16 10:10	57.62	OK
8617	2026-09-16 10:11	60.33	OK	8618	2026-09-16 10:12	59.51	OK
8619	2026-09-16 10:13	59.23	OK	8620	2026-09-16 10:14	59.10	OK
8621	2026-09-16 10:15	57.36	OK	8622	2026-09-16 10:16	61.08	OK
8623	2026-09-16 10:17	59.82	OK	8624	2026-09-16 10:18	58.63	OK
8625	2026-09-16 10:19	56.80	OK	8626	2026-09-16 10:20	58.18	OK
8627	2026-09-16 10:21	58.88	OK	8628	2026-09-16 10:22	60.31	OK
8629	2026-09-16 10:23	60.00	OK	8630	2026-09-16 10:24	60.71	OK
8631	2026-09-16 10:25	59.16	OK	8632	2026-09-16 10:26	58.37	OK
8633	2026-09-16 10:27	60.78	OK	8634	2026-09-16 10:28	59.55	OK
8635	2026-09-16 10:29	58.32	OK	8636	2026-09-16 10:30	59.36	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8637	2026-09-16 10:31	59.98	OK	8638	2026-09-16 10:32	60.52	OK
8639	2026-09-16 10:33	60.46	OK	8640	2026-09-16 10:34	57.73	OK
8641	2026-09-16 10:35	58.07	OK	8642	2026-09-16 10:36	58.24	OK
8643	2026-09-16 10:37	60.44	OK	8644	2026-09-16 10:38	58.59	OK
8645	2026-09-16 10:39	59.12	OK	8646	2026-09-16 10:40	61.08	OK
8647	2026-09-16 10:41	58.55	OK	8648	2026-09-16 10:42	58.18	OK
8649	2026-09-16 10:43	58.04	OK	8650	2026-09-16 10:44	57.76	OK
8651	2026-09-16 10:45	60.30	OK	8652	2026-09-16 10:46	61.02	OK
8653	2026-09-16 10:47	60.60	OK	8654	2026-09-16 10:48	60.58	OK
8655	2026-09-16 10:49	59.34	OK	8656	2026-09-16 10:50	60.49	OK
8657	2026-09-16 10:51	59.93	OK	8658	2026-09-16 10:52	59.44	OK
8659	2026-09-16 10:53	60.34	OK	8660	2026-09-16 10:54	60.13	OK
8661	2026-09-16 10:55	58.91	OK	8662	2026-09-16 10:56	57.74	OK
8663	2026-09-16 10:57	59.49	OK	8664	2026-09-16 10:58	61.44	OK
8665	2026-09-16 10:59	60.64	OK	8666	2026-09-16 11:00	60.77	OK
8667	2026-09-16 11:01	61.08	OK	8668	2026-09-16 11:02	58.29	OK
8669	2026-09-16 11:03	59.54	OK	8670	2026-09-16 11:04	58.21	OK
8671	2026-09-16 11:05	60.84	OK	8672	2026-09-16 11:06	61.72	OK
8673	2026-09-16 11:07	56.79	OK	8674	2026-09-16 11:08	58.31	OK
8675	2026-09-16 11:09	60.58	OK	8676	2026-09-16 11:10	59.44	OK
8677	2026-09-16 11:11	61.65	OK	8678	2026-09-16 11:12	61.41	OK
8679	2026-09-16 11:13	58.17	OK	8680	2026-09-16 11:14	60.82	OK
8681	2026-09-16 11:15	61.30	OK	8682	2026-09-16 11:16	56.75	OK
8683	2026-09-16 11:17	59.66	OK	8684	2026-09-16 11:18	59.45	OK
8685	2026-09-16 11:19	59.85	OK	8686	2026-09-16 11:20	59.39	OK
8687	2026-09-16 11:21	58.65	OK	8688	2026-09-16 11:22	58.24	OK
8689	2026-09-16 11:23	59.48	OK	8690	2026-09-16 11:24	60.48	OK
8691	2026-09-16 11:25	59.77	OK	8692	2026-09-16 11:26	60.66	OK
8693	2026-09-16 11:27	58.82	OK	8694	2026-09-16 11:28	60.23	OK
8695	2026-09-16 11:29	60.15	OK	8696	2026-09-16 11:30	60.99	OK
8697	2026-09-16 11:31	61.17	OK	8698	2026-09-16 11:32	60.42	OK
8699	2026-09-16 11:33	58.61	OK	8700	2026-09-16 11:34	59.45	OK
8701	2026-09-16 11:35	60.17	OK	8702	2026-09-16 11:36	59.42	OK
8703	2026-09-16 11:37	60.88	OK	8704	2026-09-16 11:38	59.63	OK
8705	2026-09-16 11:39	59.24	OK	8706	2026-09-16 11:40	58.41	OK
8707	2026-09-16 11:41	60.53	OK	8708	2026-09-16 11:42	58.93	OK
8709	2026-09-16 11:43	58.48	OK	8710	2026-09-16 11:44	58.93	OK
8711	2026-09-16 11:45	60.66	OK	8712	2026-09-16 11:46	59.35	OK
8713	2026-09-16 11:47	62.17	OK	8714	2026-09-16 11:48	60.51	OK
8715	2026-09-16 11:49	60.17	OK	8716	2026-09-16 11:50	58.13	OK
8717	2026-09-16 11:51	59.75	OK	8718	2026-09-16 11:52	59.28	OK
8719	2026-09-16 11:53	59.48	OK	8720	2026-09-16 11:54	60.15	OK
8721	2026-09-16 11:55	60.46	OK	8722	2026-09-16 11:56	59.43	OK
8723	2026-09-16 11:57	58.71	OK	8724	2026-09-16 11:58	57.70	OK
8725	2026-09-16 11:59	60.55	OK	8726	2026-09-16 12:00	61.66	OK
8727	2026-09-16 12:01	61.94	OK	8728	2026-09-16 12:02	59.94	OK
8729	2026-09-16 12:03	60.42	OK	8730	2026-09-16 12:04	57.85	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8731	2026-09-16 12:05	60.75	OK	8732	2026-09-16 12:06	60.94	OK
8733	2026-09-16 12:07	58.99	OK	8734	2026-09-16 12:08	59.78	OK
8735	2026-09-16 12:09	58.53	OK	8736	2026-09-16 12:10	58.96	OK
8737	2026-09-16 12:11	62.36	OK	8738	2026-09-16 12:12	60.95	OK
8739	2026-09-16 12:13	60.61	OK	8740	2026-09-16 12:14	61.89	OK
8741	2026-09-16 12:15	60.62	OK	8742	2026-09-16 12:16	59.76	OK
8743	2026-09-16 12:17	59.37	OK	8744	2026-09-16 12:18	59.33	OK
8745	2026-09-16 12:19	59.53	OK	8746	2026-09-16 12:20	62.33	OK
8747	2026-09-16 12:21	60.32	OK	8748	2026-09-16 12:22	58.39	OK
8749	2026-09-16 12:23	59.28	OK	8750	2026-09-16 12:24	60.45	OK
8751	2026-09-16 12:25	60.62	OK	8752	2026-09-16 12:26	61.78	OK
8753	2026-09-16 12:27	61.56	OK	8754	2026-09-16 12:28	58.26	OK
8755	2026-09-16 12:29	58.61	OK	8756	2026-09-16 12:30	61.11	OK
8757	2026-09-16 12:31	58.96	OK	8758	2026-09-16 12:32	61.03	OK
8759	2026-09-16 12:33	59.60	OK	8760	2026-09-16 12:34	60.21	OK
8761	2026-09-16 12:35	62.60	OK	8762	2026-09-16 12:36	60.81	OK
8763	2026-09-16 12:37	60.32	OK	8764	2026-09-16 12:38	58.02	OK
8765	2026-09-16 12:39	63.76	OK	8766	2026-09-16 12:40	61.23	OK
8767	2026-09-16 12:41	57.75	OK	8768	2026-09-16 12:42	60.88	OK
8769	2026-09-16 12:43	59.28	OK	8770	2026-09-16 12:44	60.20	OK
8771	2026-09-16 12:45	62.94	OK	8772	2026-09-16 12:46	62.54	OK
8773	2026-09-16 12:47	61.31	OK	8774	2026-09-16 12:48	60.19	OK
8775	2026-09-16 12:49	62.65	OK	8776	2026-09-16 12:50	60.95	OK
8777	2026-09-16 12:51	61.74	OK	8778	2026-09-16 12:52	60.90	OK
8779	2026-09-16 12:53	60.70	OK	8780	2026-09-16 12:54	63.28	OK
8781	2026-09-16 12:55	61.10	OK	8782	2026-09-16 12:56	62.03	OK
8783	2026-09-16 12:57	61.52	OK	8784	2026-09-16 12:58	58.38	OK
8785	2026-09-16 12:59	59.12	OK	8786	2026-09-16 13:00	62.40	OK
8787	2026-09-16 13:01	61.64	OK	8788	2026-09-16 13:02	60.99	OK
8789	2026-09-16 13:03	62.51	OK	8790	2026-09-16 13:04	58.36	OK
8791	2026-09-16 13:05	60.57	OK	8792	2026-09-16 13:06	60.78	OK
8793	2026-09-16 13:07	60.04	OK	8794	2026-09-16 13:08	60.06	OK
8795	2026-09-16 13:09	61.00	OK	8796	2026-09-16 13:10	59.65	OK
8797	2026-09-16 13:11	61.73	OK	8798	2026-09-16 13:12	60.16	OK
8799	2026-09-16 13:13	60.30	OK	8800	2026-09-16 13:14	59.96	OK
8801	2026-09-16 13:15	62.23	OK	8802	2026-09-16 13:16	58.34	OK
8803	2026-09-16 13:17	61.55	OK	8804	2026-09-16 13:18	61.14	OK
8805	2026-09-16 13:19	62.18	OK	8806	2026-09-16 13:20	58.56	OK
8807	2026-09-16 13:21	61.62	OK	8808	2026-09-16 13:22	60.68	OK
8809	2026-09-16 13:23	62.21	OK	8810	2026-09-16 13:24	62.15	OK
8811	2026-09-16 13:25	60.31	OK	8812	2026-09-16 13:26	61.01	OK
8813	2026-09-16 13:27	59.14	OK	8814	2026-09-16 13:28	58.77	OK
8815	2026-09-16 13:29	61.75	OK	8816	2026-09-16 13:30	60.05	OK
8817	2026-09-16 13:31	60.36	OK	8818	2026-09-16 13:32	59.97	OK
8819	2026-09-16 13:33	61.05	OK	8820	2026-09-16 13:34	63.54	OK
8821	2026-09-16 13:35	61.16	OK	8822	2026-09-16 13:36	63.19	OK
8823	2026-09-16 13:37	63.22	OK	8824	2026-09-16 13:38	61.00	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8825	2026-09-16 13:39	59.70	OK	8826	2026-09-16 13:40	59.28	OK
8827	2026-09-16 13:41	62.85	OK	8828	2026-09-16 13:42	63.48	OK
8829	2026-09-16 13:43	64.85	OK	8830	2026-09-16 13:44	62.24	OK
8831	2026-09-16 13:45	59.75	OK	8832	2026-09-16 13:46	63.03	OK
8833	2026-09-16 13:47	60.81	OK	8834	2026-09-16 13:48	61.83	OK
8835	2026-09-16 13:49	60.52	OK	8836	2026-09-16 13:50	59.99	OK
8837	2026-09-16 13:51	62.00	OK	8838	2026-09-16 13:52	61.96	OK
8839	2026-09-16 13:53	62.78	OK	8840	2026-09-16 13:54	60.22	OK
8841	2026-09-16 13:55	61.97	OK	8842	2026-09-16 13:56	59.69	OK
8843	2026-09-16 13:57	64.06	OK	8844	2026-09-16 13:58	63.13	OK
8845	2026-09-16 13:59	60.76	OK	8846	2026-09-16 14:00	61.80	OK
8847	2026-09-16 14:01	59.82	OK	8848	2026-09-16 14:02	63.12	OK
8849	2026-09-16 14:03	61.42	OK	8850	2026-09-16 14:04	59.08	OK
8851	2026-09-16 14:05	62.63	OK	8852	2026-09-16 14:06	61.38	OK
8853	2026-09-16 14:07	60.82	OK	8854	2026-09-16 14:08	63.40	OK
8855	2026-09-16 14:09	61.75	OK	8856	2026-09-16 14:10	61.49	OK
8857	2026-09-16 14:11	64.58	OK	8858	2026-09-16 14:12	62.09	OK
8859	2026-09-16 14:13	61.55	OK	8860	2026-09-16 14:14	62.62	OK
8861	2026-09-16 14:15	62.05	OK	8862	2026-09-16 14:16	62.31	OK
8863	2026-09-16 14:17	62.24	OK	8864	2026-09-16 14:18	62.94	OK
8865	2026-09-16 14:19	63.21	OK	8866	2026-09-16 14:20	64.10	OK
8867	2026-09-16 14:21	64.25	OK	8868	2026-09-16 14:22	61.67	OK
8869	2026-09-16 14:23	64.21	OK	8870	2026-09-16 14:24	60.70	OK
8871	2026-09-16 14:25	64.37	OK	8872	2026-09-16 14:26	61.67	OK
8873	2026-09-16 14:27	63.60	OK	8874	2026-09-16 14:28	62.22	OK
8875	2026-09-16 14:29	61.05	OK	8876	2026-09-16 14:30	63.03	OK
8877	2026-09-16 14:31	62.90	OK	8878	2026-09-16 14:32	59.62	OK
8879	2026-09-16 14:33	61.13	OK	8880	2026-09-16 14:34	61.41	OK
8881	2026-09-16 14:35	60.90	OK	8882	2026-09-16 14:36	62.57	OK
8883	2026-09-16 14:37	61.72	OK	8884	2026-09-16 14:38	61.67	OK
8885	2026-09-16 14:39	61.63	OK	8886	2026-09-16 14:40	62.81	OK
8887	2026-09-16 14:41	62.07	OK	8888	2026-09-16 14:42	64.11	OK
8889	2026-09-16 14:43	62.38	OK	8890	2026-09-16 14:44	61.44	OK
8891	2026-09-16 14:45	63.62	OK	8892	2026-09-16 14:46	64.38	OK
8893	2026-09-16 14:47	65.26	OK	8894	2026-09-16 14:48	62.87	OK
8895	2026-09-16 14:49	63.78	OK	8896	2026-09-16 14:50	62.59	OK
8897	2026-09-16 14:51	62.72	OK	8898	2026-09-16 14:52	65.30	OK
8899	2026-09-16 14:53	64.86	OK	8900	2026-09-16 14:54	61.78	OK
8901	2026-09-16 14:55	61.05	OK	8902	2026-09-16 14:56	63.19	OK
8903	2026-09-16 14:57	64.08	OK	8904	2026-09-16 14:58	64.34	OK
8905	2026-09-16 14:59	62.31	OK	8906	2026-09-16 15:00	62.88	OK
8907	2026-09-16 15:01	62.96	OK	8908	2026-09-16 15:02	61.55	OK
8909	2026-09-16 15:03	64.34	OK	8910	2026-09-16 15:04	62.51	OK
8911	2026-09-16 15:05	60.97	OK	8912	2026-09-16 15:06	62.33	OK
8913	2026-09-16 15:07	63.14	OK	8914	2026-09-16 15:08	63.59	OK
8915	2026-09-16 15:09	60.71	OK	8916	2026-09-16 15:10	63.05	OK
8917	2026-09-16 15:11	61.91	OK	8918	2026-09-16 15:12	62.78	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8919	2026-09-16 15:13	66.23	OK	8920	2026-09-16 15:14	63.27	OK
8921	2026-09-16 15:15	62.60	OK	8922	2026-09-16 15:16	64.52	OK
8923	2026-09-16 15:17	65.14	OK	8924	2026-09-16 15:18	62.91	OK
8925	2026-09-16 15:19	64.07	OK	8926	2026-09-16 15:20	65.61	OK
8927	2026-09-16 15:21	63.27	OK	8928	2026-09-16 15:22	62.50	OK
8929	2026-09-16 15:23	64.11	OK	8930	2026-09-16 15:24	62.29	OK
8931	2026-09-16 15:25	62.76	OK	8932	2026-09-16 15:26	64.90	OK
8933	2026-09-16 15:27	63.59	OK	8934	2026-09-16 15:28	66.72	OK
8935	2026-09-16 15:29	62.49	OK	8936	2026-09-16 15:30	62.54	OK
8937	2026-09-16 15:31	64.85	OK	8938	2026-09-16 15:32	63.94	OK
8939	2026-09-16 15:33	64.86	OK	8940	2026-09-16 15:34	64.55	OK
8941	2026-09-16 15:35	63.63	OK	8942	2026-09-16 15:36	64.24	OK
8943	2026-09-16 15:37	66.31	OK	8944	2026-09-16 15:38	63.84	OK
8945	2026-09-16 15:39	63.13	OK	8946	2026-09-16 15:40	65.79	OK
8947	2026-09-16 15:41	64.26	OK	8948	2026-09-16 15:42	65.30	OK
8949	2026-09-16 15:43	66.67	OK	8950	2026-09-16 15:44	62.17	OK
8951	2026-09-16 15:45	64.56	OK	8952	2026-09-16 15:46	63.25	OK
8953	2026-09-16 15:47	63.74	OK	8954	2026-09-16 15:48	65.65	OK
8955	2026-09-16 15:49	64.96	OK	8956	2026-09-16 15:50	64.80	OK
8957	2026-09-16 15:51	63.26	OK	8958	2026-09-16 15:52	65.32	OK
8959	2026-09-16 15:53	67.24	OK	8960	2026-09-16 15:54	65.02	OK
8961	2026-09-16 15:55	64.65	OK	8962	2026-09-16 15:56	64.72	OK
8963	2026-09-16 15:57	64.75	OK	8964	2026-09-16 15:58	62.76	OK
8965	2026-09-16 15:59	63.36	OK	8966	2026-09-16 16:00	64.02	OK
8967	2026-09-16 16:01	65.13	OK	8968	2026-09-16 16:02	65.35	OK
8969	2026-09-16 16:03	62.53	OK	8970	2026-09-16 16:04	66.90	OK
8971	2026-09-16 16:05	66.17	OK	8972	2026-09-16 16:06	62.64	OK
8973	2026-09-16 16:07	67.45	OK	8974	2026-09-16 16:08	64.62	OK
8975	2026-09-16 16:09	66.32	OK	8976	2026-09-16 16:10	64.74	OK
8977	2026-09-16 16:11	66.87	OK	8978	2026-09-16 16:12	66.04	OK
8979	2026-09-16 16:13	67.08	OK	8980	2026-09-16 16:14	66.24	OK
8981	2026-09-16 16:15	65.67	OK	8982	2026-09-16 16:16	65.52	OK
8983	2026-09-16 16:17	64.70	OK	8984	2026-09-16 16:18	67.40	OK
8985	2026-09-16 16:19	67.43	OK	8986	2026-09-16 16:20	66.39	OK
8987	2026-09-16 16:21	64.54	OK	8988	2026-09-16 16:22	63.85	OK
8989	2026-09-16 16:23	64.33	OK	8990	2026-09-16 16:24	66.26	OK
8991	2026-09-16 16:25	64.71	OK	8992	2026-09-16 16:26	65.42	OK
8993	2026-09-16 16:27	66.38	OK	8994	2026-09-16 16:28	66.34	OK
8995	2026-09-16 16:29	64.40	OK	8996	2026-09-16 16:30	66.57	OK
8997	2026-09-16 16:31	66.73	OK	8998	2026-09-16 16:32	63.56	OK
8999	2026-09-16 16:33	67.38	OK	9000	2026-09-16 16:34	64.70	OK
9001	2026-09-16 16:35	63.52	OK	9002	2026-09-16 16:36	65.55	OK
9003	2026-09-16 16:37	65.33	OK	9004	2026-09-16 16:38	65.99	OK
9005	2026-09-16 16:39	67.76	OK	9006	2026-09-16 16:40	66.66	OK
9007	2026-09-16 16:41	69.60	OK	9008	2026-09-16 16:42	68.41	OK
9009	2026-09-16 16:43	65.35	OK	9010	2026-09-16 16:44	66.16	OK
9011	2026-09-16 16:45	67.18	OK	9012	2026-09-16 16:46	65.77	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9013	2026-09-16 16:47	68.93	OK	9014	2026-09-16 16:48	68.31	OK
9015	2026-09-16 16:49	64.10	OK	9016	2026-09-16 16:50	69.55	OK
9017	2026-09-16 16:51	67.75	OK	9018	2026-09-16 16:52	66.94	OK
9019	2026-09-16 16:53	65.86	OK	9020	2026-09-16 16:54	66.84	OK
9021	2026-09-16 16:55	66.17	OK	9022	2026-09-16 16:56	64.53	OK
9023	2026-09-16 16:57	66.26	OK	9024	2026-09-16 16:58	67.27	OK
9025	2026-09-16 16:59	67.54	OK	9026	2026-09-16 17:00	66.57	OK
9027	2026-09-16 17:01	66.05	OK	9028	2026-09-16 17:02	65.35	OK
9029	2026-09-16 17:03	66.92	OK	9030	2026-09-16 17:04	64.88	OK
9031	2026-09-16 17:05	63.98	OK	9032	2026-09-16 17:06	66.40	OK
9033	2026-09-16 17:07	64.53	OK	9034	2026-09-16 17:08	64.83	OK
9035	2026-09-16 17:09	64.34	OK	9036	2026-09-16 17:10	68.36	OK
9037	2026-09-16 17:11	67.48	OK	9038	2026-09-16 17:12	66.86	OK
9039	2026-09-16 17:13	68.61	OK	9040	2026-09-16 17:14	68.39	OK
9041	2026-09-16 17:15	66.68	OK	9042	2026-09-16 17:16	67.15	OK
9043	2026-09-16 17:17	68.62	OK	9044	2026-09-16 17:18	66.89	OK
9045	2026-09-16 17:19	67.60	OK	9046	2026-09-16 17:20	69.16	OK
9047	2026-09-16 17:21	68.42	OK	9048	2026-09-16 17:22	68.88	OK
9049	2026-09-16 17:23	67.82	OK	9050	2026-09-16 17:24	67.03	OK
9051	2026-09-16 17:25	66.96	OK	9052	2026-09-16 17:26	65.86	OK
9053	2026-09-16 17:27	68.04	OK	9054	2026-09-16 17:28	66.56	OK
9055	2026-09-16 17:29	65.95	OK	9056	2026-09-16 17:30	68.18	OK
9057	2026-09-16 17:31	66.71	OK	9058	2026-09-16 17:32	67.85	OK
9059	2026-09-16 17:33	67.82	OK	9060	2026-09-16 17:34	69.17	OK
9061	2026-09-16 17:35	67.98	OK	9062	2026-09-16 17:36	66.22	OK
9063	2026-09-16 17:37	68.37	OK	9064	2026-09-16 17:38	68.83	OK
9065	2026-09-16 17:39	68.34	OK	9066	2026-09-16 17:40	68.92	OK
9067	2026-09-16 17:41	69.85	OK	9068	2026-09-16 17:42	68.88	OK
9069	2026-09-16 17:43	70.22	OK	9070	2026-09-16 17:44	69.19	OK
9071	2026-09-16 17:45	66.37	OK	9072	2026-09-16 17:46	68.04	OK
9073	2026-09-16 17:47	66.12	OK	9074	2026-09-16 17:48	67.73	OK
9075	2026-09-16 17:49	68.59	OK	9076	2026-09-16 17:50	66.35	OK
9077	2026-09-16 17:51	68.98	OK	9078	2026-09-16 17:52	67.87	OK
9079	2026-09-16 17:53	67.82	OK	9080	2026-09-16 17:54	68.63	OK
9081	2026-09-16 17:55	68.63	OK	9082	2026-09-16 17:56	68.18	OK
9083	2026-09-16 17:57	66.21	OK	9084	2026-09-16 17:58	69.47	OK
9085	2026-09-16 17:59	69.51	OK	9086	2026-09-16 18:00	70.21	OK
9087	2026-09-16 18:01	68.33	OK	9088	2026-09-16 18:02	67.58	OK
9089	2026-09-16 18:03	68.99	OK	9090	2026-09-16 18:04	68.04	OK
9091	2026-09-16 18:05	69.04	OK	9092	2026-09-16 18:06	67.89	OK
9093	2026-09-16 18:07	69.07	OK	9094	2026-09-16 18:08	66.98	OK
9095	2026-09-16 18:09	69.47	OK	9096	2026-09-16 18:10	68.68	OK
9097	2026-09-16 18:11	69.42	OK	9098	2026-09-16 18:12	66.37	OK
9099	2026-09-16 18:13	70.10	OK	9100	2026-09-16 18:14	69.11	OK
9101	2026-09-16 18:15	68.60	OK	9102	2026-09-16 18:16	70.08	OK
9103	2026-09-16 18:17	66.58	OK	9104	2026-09-16 18:18	70.79	OK
9105	2026-09-16 18:19	70.62	OK	9106	2026-09-16 18:20	69.14	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9107	2026-09-16 18:21	68.95	OK	9108	2026-09-16 18:22	67.25	OK
9109	2026-09-16 18:23	67.60	OK	9110	2026-09-16 18:24	69.45	OK
9111	2026-09-16 18:25	67.59	OK	9112	2026-09-16 18:26	68.20	OK
9113	2026-09-16 18:27	65.84	OK	9114	2026-09-16 18:28	68.42	OK
9115	2026-09-16 18:29	67.81	OK	9116	2026-09-16 18:30	69.36	OK
9117	2026-09-16 18:31	70.01	OK	9118	2026-09-16 18:32	68.17	OK
9119	2026-09-16 18:33	69.51	OK	9120	2026-09-16 18:34	67.68	OK
9121	2026-09-16 18:35	69.67	OK	9122	2026-09-16 18:36	68.34	OK
9123	2026-09-16 18:37	67.35	OK	9124	2026-09-16 18:38	68.67	OK
9125	2026-09-16 18:39	68.82	OK	9126	2026-09-16 18:40	67.86	OK
9127	2026-09-16 18:41	69.94	OK	9128	2026-09-16 18:42	70.15	OK
9129	2026-09-16 18:43	66.75	OK	9130	2026-09-16 18:44	69.58	OK
9131	2026-09-16 18:45	70.20	OK	9132	2026-09-16 18:46	69.27	OK
9133	2026-09-16 18:47	67.30	OK	9134	2026-09-16 18:48	69.00	OK
9135	2026-09-16 18:49	70.52	OK	9136	2026-09-16 18:50	70.24	OK
9137	2026-09-16 18:51	70.61	OK	9138	2026-09-16 18:52	69.07	OK
9139	2026-09-16 18:53	69.03	OK	9140	2026-09-16 18:54	68.57	OK
9141	2026-09-16 18:55	68.32	OK	9142	2026-09-16 18:56	69.08	OK
9143	2026-09-16 18:57	70.86	OK	9144	2026-09-16 18:58	68.83	OK
9145	2026-09-16 18:59	72.12	OK	9146	2026-09-16 19:00	67.38	OK
9147	2026-09-16 19:01	70.62	OK	9148	2026-09-16 19:02	68.86	OK
9149	2026-09-16 19:03	68.67	OK	9150	2026-09-16 19:04	70.88	OK
9151	2026-09-16 19:05	67.35	OK	9152	2026-09-16 19:06	68.51	OK
9153	2026-09-16 19:07	68.98	OK	9154	2026-09-16 19:08	71.66	OK
9155	2026-09-16 19:09	69.61	OK	9156	2026-09-16 19:10	69.32	OK
9157	2026-09-16 19:11	70.62	OK	9158	2026-09-16 19:12	69.67	OK
9159	2026-09-16 19:13	70.40	OK	9160	2026-09-16 19:14	69.77	OK
9161	2026-09-16 19:15	71.45	OK	9162	2026-09-16 19:16	70.80	OK
9163	2026-09-16 19:17	69.13	OK	9164	2026-09-16 19:18	70.09	OK
9165	2026-09-16 19:19	69.14	OK	9166	2026-09-16 19:20	70.34	OK
9167	2026-09-16 19:21	69.65	OK	9168	2026-09-16 19:22	68.32	OK
9169	2026-09-16 19:23	68.84	OK	9170	2026-09-16 19:24	70.07	OK
9171	2026-09-16 19:25	71.41	OK	9172	2026-09-16 19:26	69.64	OK
9173	2026-09-16 19:27	69.30	OK	9174	2026-09-16 19:28	70.74	OK
9175	2026-09-16 19:29	70.85	OK	9176	2026-09-16 19:30	69.10	OK
9177	2026-09-16 19:31	71.17	OK	9178	2026-09-16 19:32	70.06	OK
9179	2026-09-16 19:33	71.44	OK	9180	2026-09-16 19:34	72.24	OK
9181	2026-09-16 19:35	69.67	OK	9182	2026-09-16 19:36	70.62	OK
9183	2026-09-16 19:37	72.14	OK	9184	2026-09-16 19:38	72.10	OK
9185	2026-09-16 19:39	71.74	OK	9186	2026-09-16 19:40	71.76	OK
9187	2026-09-16 19:41	71.94	OK	9188	2026-09-16 19:42	72.29	OK
9189	2026-09-16 19:43	70.56	OK	9190	2026-09-16 19:44	70.18	OK
9191	2026-09-16 19:45	71.96	OK	9192	2026-09-16 19:46	72.38	OK
9193	2026-09-16 19:47	69.36	OK	9194	2026-09-16 19:48	70.94	OK
9195	2026-09-16 19:49	72.63	OK	9196	2026-09-16 19:50	71.74	OK
9197	2026-09-16 19:51	70.05	OK	9198	2026-09-16 19:52	71.26	OK
9199	2026-09-16 19:53	73.42	OK	9200	2026-09-16 19:54	70.37	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9201	2026-09-16 19:55	70.13	OK	9202	2026-09-16 19:56	71.64	OK
9203	2026-09-16 19:57	67.82	OK	9204	2026-09-16 19:58	72.26	OK
9205	2026-09-16 19:59	71.59	OK	9206	2026-09-16 20:00	71.90	OK
9207	2026-09-16 20:01	71.19	OK	9208	2026-09-16 20:02	72.18	OK
9209	2026-09-16 20:03	70.90	OK	9210	2026-09-16 20:04	70.48	OK
9211	2026-09-16 20:05	71.66	OK	9212	2026-09-16 20:06	68.21	OK
9213	2026-09-16 20:07	72.04	OK	9214	2026-09-16 20:08	71.90	OK
9215	2026-09-16 20:09	71.73	OK	9216	2026-09-16 20:10	71.21	OK
9217	2026-09-16 20:11	71.53	OK	9218	2026-09-16 20:12	74.50	OK
9219	2026-09-16 20:13	68.88	OK	9220	2026-09-16 20:14	69.75	OK
9221	2026-09-16 20:15	69.63	OK	9222	2026-09-16 20:16	70.86	OK
9223	2026-09-16 20:17	71.47	OK	9224	2026-09-16 20:18	69.20	OK
9225	2026-09-16 20:19	70.10	OK	9226	2026-09-16 20:20	69.39	OK
9227	2026-09-16 20:21	69.79	OK	9228	2026-09-16 20:22	72.14	OK
9229	2026-09-16 20:23	74.43	OK	9230	2026-09-16 20:24	72.21	OK
9231	2026-09-16 20:25	71.39	OK	9232	2026-09-16 20:26	72.12	OK
9233	2026-09-16 20:27	72.18	OK	9234	2026-09-16 20:28	71.90	OK
9235	2026-09-16 20:29	70.23	OK	9236	2026-09-16 20:30	70.17	OK
9237	2026-09-16 20:31	69.15	OK	9238	2026-09-16 20:32	73.94	OK
9239	2026-09-16 20:33	71.81	OK	9240	2026-09-16 20:34	70.78	OK
9241	2026-09-16 20:35	70.35	OK	9242	2026-09-16 20:36	70.33	OK
9243	2026-09-16 20:37	71.75	OK	9244	2026-09-16 20:38	72.76	OK
9245	2026-09-16 20:39	72.26	OK	9246	2026-09-16 20:40	72.86	OK
9247	2026-09-16 20:41	71.40	OK	9248	2026-09-16 20:42	70.39	OK
9249	2026-09-16 20:43	71.81	OK	9250	2026-09-16 20:44	72.72	OK
9251	2026-09-16 20:45	71.85	OK	9252	2026-09-16 20:46	70.53	OK
9253	2026-09-16 20:47	72.58	OK	9254	2026-09-16 20:48	71.58	OK
9255	2026-09-16 20:49	70.90	OK	9256	2026-09-16 20:50	69.93	OK
9257	2026-09-16 20:51	72.11	OK	9258	2026-09-16 20:52	72.89	OK
9259	2026-09-16 20:53	71.95	OK	9260	2026-09-16 20:54	71.38	OK
9261	2026-09-16 20:55	71.15	OK	9262	2026-09-16 20:56	72.08	OK
9263	2026-09-16 20:57	71.89	OK	9264	2026-09-16 20:58	71.61	OK
9265	2026-09-16 20:59	73.12	OK	9266	2026-09-16 21:00	73.94	OK
9267	2026-09-16 21:01	71.56	OK	9268	2026-09-16 21:02	71.65	OK
9269	2026-09-16 21:03	68.96	OK	9270	2026-09-16 21:04	73.79	OK
9271	2026-09-16 21:05	70.86	OK	9272	2026-09-16 21:06	72.13	OK
9273	2026-09-16 21:07	71.07	OK	9274	2026-09-16 21:08	73.17	OK
9275	2026-09-16 21:09	70.65	OK	9276	2026-09-16 21:10	70.83	OK
9277	2026-09-16 21:11	72.84	OK	9278	2026-09-16 21:12	73.39	OK
9279	2026-09-16 21:13	72.33	OK	9280	2026-09-16 21:14	73.72	OK
9281	2026-09-16 21:15	73.38	OK	9282	2026-09-16 21:16	72.70	OK
9283	2026-09-16 21:17	73.37	OK	9284	2026-09-16 21:18	73.24	OK
9285	2026-09-16 21:19	72.45	OK	9286	2026-09-16 21:20	74.08	OK
9287	2026-09-16 21:21	72.87	OK	9288	2026-09-16 21:22	71.59	OK
9289	2026-09-16 21:23	73.09	OK	9290	2026-09-16 21:24	74.11	OK
9291	2026-09-16 21:25	69.92	OK	9292	2026-09-16 21:26	71.34	OK
9293	2026-09-16 21:27	73.37	OK	9294	2026-09-16 21:28	73.68	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9295	2026-09-16 21:29	69.18	OK	9296	2026-09-16 21:30	72.11	OK
9297	2026-09-16 21:31	73.03	OK	9298	2026-09-16 21:32	71.17	OK
9299	2026-09-16 21:33	74.26	OK	9300	2026-09-16 21:34	75.29	OK
9301	2026-09-16 21:35	73.33	OK	9302	2026-09-16 21:36	73.82	OK
9303	2026-09-16 21:37	72.37	OK	9304	2026-09-16 21:38	72.25	OK
9305	2026-09-16 21:39	72.45	OK	9306	2026-09-16 21:40	73.05	OK
9307	2026-09-16 21:41	73.36	OK	9308	2026-09-16 21:42	70.55	OK
9309	2026-09-16 21:43	73.07	OK	9310	2026-09-16 21:44	72.23	OK
9311	2026-09-16 21:45	73.61	OK	9312	2026-09-16 21:46	74.22	OK
9313	2026-09-16 21:47	71.99	OK	9314	2026-09-16 21:48	72.81	OK
9315	2026-09-16 21:49	74.19	OK	9316	2026-09-16 21:50	72.26	OK
9317	2026-09-16 21:51	72.89	OK	9318	2026-09-16 21:52	73.75	OK
9319	2026-09-16 21:53	72.93	OK	9320	2026-09-16 21:54	71.44	OK
9321	2026-09-16 21:55	72.29	OK	9322	2026-09-16 21:56	71.35	OK
9323	2026-09-16 21:57	71.74	OK	9324	2026-09-16 21:58	72.59	OK
9325	2026-09-16 21:59	73.70	OK	9326	2026-09-16 22:00	71.40	OK
9327	2026-09-16 22:01	73.28	OK	9328	2026-09-16 22:02	73.28	OK
9329	2026-09-16 22:03	70.37	OK	9330	2026-09-16 22:04	72.35	OK
9331	2026-09-16 22:05	75.14	OK	9332	2026-09-16 22:06	71.80	OK
9333	2026-09-16 22:07	74.02	OK	9334	2026-09-16 22:08	72.46	OK
9335	2026-09-16 22:09	72.11	OK	9336	2026-09-16 22:10	70.36	OK
9337	2026-09-16 22:11	71.23	OK	9338	2026-09-16 22:12	73.34	OK
9339	2026-09-16 22:13	73.52	OK	9340	2026-09-16 22:14	72.82	OK
9341	2026-09-16 22:15	73.59	OK	9342	2026-09-16 22:16	74.19	OK
9343	2026-09-16 22:17	71.60	OK	9344	2026-09-16 22:18	74.04	OK
9345	2026-09-16 22:19	71.00	OK	9346	2026-09-16 22:20	71.42	OK
9347	2026-09-16 22:21	71.93	OK	9348	2026-09-16 22:22	75.31	OK
9349	2026-09-16 22:23	72.82	OK	9350	2026-09-16 22:24	71.56	OK
9351	2026-09-16 22:25	74.09	OK	9352	2026-09-16 22:26	73.84	OK
9353	2026-09-16 22:27	71.95	OK	9354	2026-09-16 22:28	72.19	OK
9355	2026-09-16 22:29	71.81	OK	9356	2026-09-16 22:30	69.73	OK
9357	2026-09-16 22:31	72.56	OK	9358	2026-09-16 22:32	73.75	OK
9359	2026-09-16 22:33	73.91	OK	9360	2026-09-16 22:34	69.85	OK
9361	2026-09-16 22:35	72.88	OK	9362	2026-09-16 22:36	73.61	OK
9363	2026-09-16 22:37	72.98	OK	9364	2026-09-16 22:38	72.49	OK
9365	2026-09-16 22:39	73.49	OK	9366	2026-09-16 22:40	73.73	OK
9367	2026-09-16 22:41	72.14	OK	9368	2026-09-16 22:42	72.86	OK
9369	2026-09-16 22:43	73.02	OK	9370	2026-09-16 22:44	72.65	OK
9371	2026-09-16 22:45	74.36	OK	9372	2026-09-16 22:46	72.57	OK
9373	2026-09-16 22:47	71.14	OK	9374	2026-09-16 22:48	71.47	OK
9375	2026-09-16 22:49	70.86	OK	9376	2026-09-16 22:50	73.50	OK
9377	2026-09-16 22:51	71.62	OK	9378	2026-09-16 22:52	70.39	OK
9379	2026-09-16 22:53	73.84	OK	9380	2026-09-16 22:54	72.85	OK
9381	2026-09-16 22:55	71.21	OK	9382	2026-09-16 22:56	70.86	OK
9383	2026-09-16 22:57	73.16	OK	9384	2026-09-16 22:58	72.99	OK
9385	2026-09-16 22:59	70.97	OK	9386	2026-09-16 23:00	72.37	OK
9387	2026-09-16 23:01	70.92	OK	9388	2026-09-16 23:02	71.52	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9389	2026-09-16 23:03	74.08	OK	9390	2026-09-16 23:04	73.20	OK
9391	2026-09-16 23:05	71.85	OK	9392	2026-09-16 23:06	73.44	OK
9393	2026-09-16 23:07	71.36	OK	9394	2026-09-16 23:08	72.13	OK
9395	2026-09-16 23:09	73.20	OK	9396	2026-09-16 23:10	75.65	OK
9397	2026-09-16 23:11	71.44	OK	9398	2026-09-16 23:12	73.76	OK
9399	2026-09-16 23:13	74.06	OK	9400	2026-09-16 23:14	71.05	OK
9401	2026-09-16 23:15	72.88	OK	9402	2026-09-16 23:16	73.25	OK
9403	2026-09-16 23:17	73.25	OK	9404	2026-09-16 23:18	72.35	OK
9405	2026-09-16 23:19	70.52	OK	9406	2026-09-16 23:20	69.82	OK
9407	2026-09-16 23:21	69.51	OK	9408	2026-09-16 23:22	74.56	OK
9409	2026-09-16 23:23	72.59	OK	9410	2026-09-16 23:24	72.76	OK
9411	2026-09-16 23:25	74.29	OK	9412	2026-09-16 23:26	73.71	OK
9413	2026-09-16 23:27	71.85	OK	9414	2026-09-16 23:28	73.90	OK
9415	2026-09-16 23:29	72.26	OK	9416	2026-09-16 23:30	74.21	OK
9417	2026-09-16 23:31	74.66	OK	9418	2026-09-16 23:32	73.01	OK
9419	2026-09-16 23:33	71.52	OK	9420	2026-09-16 23:34	73.28	OK
9421	2026-09-16 23:35	72.05	OK	9422	2026-09-16 23:36	74.23	OK
9423	2026-09-16 23:37	72.47	OK	9424	2026-09-16 23:38	71.83	OK
9425	2026-09-16 23:39	72.63	OK	9426	2026-09-16 23:40	73.74	OK
9427	2026-09-16 23:41	73.09	OK	9428	2026-09-16 23:42	72.67	OK
9429	2026-09-16 23:43	74.59	OK	9430	2026-09-16 23:44	75.50	OK
9431	2026-09-16 23:45	71.56	OK	9432	2026-09-16 23:46	73.63	OK
9433	2026-09-16 23:47	71.55	OK	9434	2026-09-16 23:48	72.09	OK
9435	2026-09-16 23:49	72.94	OK	9436	2026-09-16 23:50	72.02	OK
9437	2026-09-16 23:51	72.25	OK	9438	2026-09-16 23:52	71.43	OK
9439	2026-09-16 23:53	72.25	OK	9440	2026-09-16 23:54	69.42	OK
9441	2026-09-16 23:55	73.66	OK	9442	2026-09-16 23:56	71.73	OK
9443	2026-09-16 23:57	72.93	OK	9444	2026-09-16 23:58	72.16	OK
9445	2026-09-16 23:59	71.66	OK	9446	2026-09-17 00:00	73.10	OK
9447	2026-09-17 00:01	73.79	OK	9448	2026-09-17 00:02	73.88	OK
9449	2026-09-17 00:03	72.29	OK	9450	2026-09-17 00:04	74.45	OK
9451	2026-09-17 00:05	75.25	OK	9452	2026-09-17 00:06	73.13	OK
9453	2026-09-17 00:07	71.64	OK	9454	2026-09-17 00:08	73.11	OK
9455	2026-09-17 00:09	72.16	OK	9456	2026-09-17 00:10	74.35	OK
9457	2026-09-17 00:11	72.98	OK	9458	2026-09-17 00:12	71.03	OK
9459	2026-09-17 00:13	73.70	OK	9460	2026-09-17 00:14	72.16	OK
9461	2026-09-17 00:15	71.12	OK	9462	2026-09-17 00:16	70.52	OK
9463	2026-09-17 00:17	71.25	OK	9464	2026-09-17 00:18	69.97	OK
9465	2026-09-17 00:19	70.27	OK	9466	2026-09-17 00:20	71.67	OK
9467	2026-09-17 00:21	73.35	OK	9468	2026-09-17 00:22	70.71	OK
9469	2026-09-17 00:23	73.50	OK	9470	2026-09-17 00:24	72.16	OK
9471	2026-09-17 00:25	72.85	OK	9472	2026-09-17 00:26	70.85	OK
9473	2026-09-17 00:27	70.70	OK	9474	2026-09-17 00:28	70.19	OK
9475	2026-09-17 00:29	71.61	OK	9476	2026-09-17 00:30	73.79	OK
9477	2026-09-17 00:31	73.63	OK	9478	2026-09-17 00:32	71.19	OK
9479	2026-09-17 00:33	71.15	OK	9480	2026-09-17 00:34	73.38	OK
9481	2026-09-17 00:35	71.31	OK	9482	2026-09-17 00:36	69.87	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9483	2026-09-17 00:37	71.53	OK	9484	2026-09-17 00:38	72.04	OK
9485	2026-09-17 00:39	74.37	OK	9486	2026-09-17 00:40	73.60	OK
9487	2026-09-17 00:41	72.61	OK	9488	2026-09-17 00:42	70.84	OK
9489	2026-09-17 00:43	71.73	OK	9490	2026-09-17 00:44	73.06	OK
9491	2026-09-17 00:45	70.44	OK	9492	2026-09-17 00:46	70.83	OK
9493	2026-09-17 00:47	72.68	OK	9494	2026-09-17 00:48	72.31	OK
9495	2026-09-17 00:49	73.42	OK	9496	2026-09-17 00:50	73.18	OK
9497	2026-09-17 00:51	71.91	OK	9498	2026-09-17 00:52	72.92	OK
9499	2026-09-17 00:53	70.48	OK	9500	2026-09-17 00:54	71.39	OK
9501	2026-09-17 00:55	72.03	OK	9502	2026-09-17 00:56	71.66	OK
9503	2026-09-17 00:57	71.94	OK	9504	2026-09-17 00:58	72.29	OK
9505	2026-09-17 00:59	71.43	OK	9506	2026-09-17 01:00	70.53	OK
9507	2026-09-17 01:01	73.60	OK	9508	2026-09-17 01:02	68.83	OK
9509	2026-09-17 01:03	69.59	OK	9510	2026-09-17 01:04	72.90	OK
9511	2026-09-17 01:05	72.93	OK	9512	2026-09-17 01:06	70.47	OK
9513	2026-09-17 01:07	69.94	OK	9514	2026-09-17 01:08	70.75	OK
9515	2026-09-17 01:09	69.19	OK	9516	2026-09-17 01:10	70.66	OK
9517	2026-09-17 01:11	71.07	OK	9518	2026-09-17 01:12	70.59	OK
9519	2026-09-17 01:13	72.59	OK	9520	2026-09-17 01:14	71.22	OK
9521	2026-09-17 01:15	71.74	OK	9522	2026-09-17 01:16	70.82	OK
9523	2026-09-17 01:17	72.18	OK	9524	2026-09-17 01:18	72.12	OK
9525	2026-09-17 01:19	70.67	OK	9526	2026-09-17 01:20	70.96	OK
9527	2026-09-17 01:21	72.50	OK	9528	2026-09-17 01:22	73.06	OK
9529	2026-09-17 01:23	71.43	OK	9530	2026-09-17 01:24	72.51	OK
9531	2026-09-17 01:25	70.38	OK	9532	2026-09-17 01:26	70.30	OK
9533	2026-09-17 01:27	70.85	OK	9534	2026-09-17 01:28	73.51	OK
9535	2026-09-17 01:29	71.43	OK	9536	2026-09-17 01:30	70.34	OK
9537	2026-09-17 01:31	71.14	OK	9538	2026-09-17 01:32	70.22	OK
9539	2026-09-17 01:33	70.67	OK	9540	2026-09-17 01:34	71.91	OK
9541	2026-09-17 01:35	69.11	OK	9542	2026-09-17 01:36	70.69	OK
9543	2026-09-17 01:37	70.48	OK	9544	2026-09-17 01:38	70.84	OK
9545	2026-09-17 01:39	70.58	OK	9546	2026-09-17 01:40	71.45	OK
9547	2026-09-17 01:41	73.15	OK	9548	2026-09-17 01:42	72.78	OK
9549	2026-09-17 01:43	68.74	OK	9550	2026-09-17 01:44	70.71	OK
9551	2026-09-17 01:45	71.42	OK	9552	2026-09-17 01:46	71.33	OK
9553	2026-09-17 01:47	71.59	OK	9554	2026-09-17 01:48	70.17	OK
9555	2026-09-17 01:49	71.36	OK	9556	2026-09-17 01:50	69.94	OK
9557	2026-09-17 01:51	70.44	OK	9558	2026-09-17 01:52	69.19	OK
9559	2026-09-17 01:53	71.12	OK	9560	2026-09-17 01:54	72.03	OK
9561	2026-09-17 01:55	70.58	OK	9562	2026-09-17 01:56	70.83	OK
9563	2026-09-17 01:57	71.75	OK	9564	2026-09-17 01:58	71.28	OK
9565	2026-09-17 01:59	69.18	OK	9566	2026-09-17 02:00	71.05	OK
9567	2026-09-17 02:01	70.57	OK	9568	2026-09-17 02:02	71.65	OK
9569	2026-09-17 02:03	69.81	OK	9570	2026-09-17 02:04	68.62	OK
9571	2026-09-17 02:05	69.92	OK	9572	2026-09-17 02:06	71.82	OK
9573	2026-09-17 02:07	72.03	OK	9574	2026-09-17 02:08	70.38	OK
9575	2026-09-17 02:09	70.43	OK	9576	2026-09-17 02:10	70.25	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9577	2026-09-17 02:11	71.78	OK	9578	2026-09-17 02:12	71.46	OK
9579	2026-09-17 02:13	68.93	OK	9580	2026-09-17 02:14	69.74	OK
9581	2026-09-17 02:15	68.59	OK	9582	2026-09-17 02:16	69.68	OK
9583	2026-09-17 02:17	69.81	OK	9584	2026-09-17 02:18	70.41	OK
9585	2026-09-17 02:19	70.10	OK	9586	2026-09-17 02:20	69.42	OK
9587	2026-09-17 02:21	70.87	OK	9588	2026-09-17 02:22	69.44	OK
9589	2026-09-17 02:23	70.18	OK	9590	2026-09-17 02:24	71.26	OK
9591	2026-09-17 02:25	69.48	OK	9592	2026-09-17 02:26	71.41	OK
9593	2026-09-17 02:27	68.73	OK	9594	2026-09-17 02:28	68.96	OK
9595	2026-09-17 02:29	71.04	OK	9596	2026-09-17 02:30	70.80	OK
9597	2026-09-17 02:31	68.82	OK	9598	2026-09-17 02:32	69.52	OK
9599	2026-09-17 02:33	70.21	OK	9600	2026-09-17 02:34	70.58	OK
9601	2026-09-17 02:35	68.08	OK	9602	2026-09-17 02:36	68.97	OK
9603	2026-09-17 02:37	70.04	OK	9604	2026-09-17 02:38	68.43	OK
9605	2026-09-17 02:39	68.85	OK	9606	2026-09-17 02:40	70.01	OK
9607	2026-09-17 02:41	69.59	OK	9608	2026-09-17 02:42	72.21	OK
9609	2026-09-17 02:43	68.96	OK	9610	2026-09-17 02:44	70.91	OK
9611	2026-09-17 02:45	71.66	OK	9612	2026-09-17 02:46	69.21	OK
9613	2026-09-17 02:47	68.75	OK	9614	2026-09-17 02:48	67.91	OK
9615	2026-09-17 02:49	72.51	OK	9616	2026-09-17 02:50	70.40	OK
9617	2026-09-17 02:51	68.08	OK	9618	2026-09-17 02:52	67.39	OK
9619	2026-09-17 02:53	70.03	OK	9620	2026-09-17 02:54	69.76	OK
9621	2026-09-17 02:55	66.95	OK	9622	2026-09-17 02:56	69.37	OK
9623	2026-09-17 02:57	69.45	OK	9624	2026-09-17 02:58	67.34	OK
9625	2026-09-17 02:59	68.53	OK	9626	2026-09-17 03:00	67.08	OK
9627	2026-09-17 03:01	67.48	OK	9628	2026-09-17 03:02	68.69	OK
9629	2026-09-17 03:03	67.36	OK	9630	2026-09-17 03:04	68.25	OK
9631	2026-09-17 03:05	69.31	OK	9632	2026-09-17 03:06	68.10	OK
9633	2026-09-17 03:07	66.55	OK	9634	2026-09-17 03:08	68.93	OK
9635	2026-09-17 03:09	67.94	OK	9636	2026-09-17 03:10	69.15	OK
9637	2026-09-17 03:11	68.80	OK	9638	2026-09-17 03:12	68.79	OK
9639	2026-09-17 03:13	68.13	OK	9640	2026-09-17 03:14	68.36	OK
9641	2026-09-17 03:15	68.63	OK	9642	2026-09-17 03:16	70.27	OK
9643	2026-09-17 03:17	70.87	OK	9644	2026-09-17 03:18	68.29	OK
9645	2026-09-17 03:19	69.70	OK	9646	2026-09-17 03:20	68.29	OK
9647	2026-09-17 03:21	69.30	OK	9648	2026-09-17 03:22	69.12	OK
9649	2026-09-17 03:23	70.50	OK	9650	2026-09-17 03:24	70.84	OK
9651	2026-09-17 03:25	70.67	OK	9652	2026-09-17 03:26	69.19	OK
9653	2026-09-17 03:27	69.97	OK	9654	2026-09-17 03:28	68.49	OK
9655	2026-09-17 03:29	69.11	OK	9656	2026-09-17 03:30	67.78	OK
9657	2026-09-17 03:31	68.69	OK	9658	2026-09-17 03:32	68.04	OK
9659	2026-09-17 03:33	67.15	OK	9660	2026-09-17 03:34	67.13	OK
9661	2026-09-17 03:35	66.90	OK	9662	2026-09-17 03:36	67.21	OK
9663	2026-09-17 03:37	67.18	OK	9664	2026-09-17 03:38	70.28	OK
9665	2026-09-17 03:39	69.27	OK	9666	2026-09-17 03:40	67.74	OK
9667	2026-09-17 03:41	70.35	OK	9668	2026-09-17 03:42	68.80	OK
9669	2026-09-17 03:43	69.11	OK	9670	2026-09-17 03:44	67.24	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9671	2026-09-17 03:45	68.29	OK	9672	2026-09-17 03:46	69.72	OK
9673	2026-09-17 03:47	64.65	OK	9674	2026-09-17 03:48	68.43	OK
9675	2026-09-17 03:49	67.12	OK	9676	2026-09-17 03:50	66.78	OK
9677	2026-09-17 03:51	66.53	OK	9678	2026-09-17 03:52	67.79	OK
9679	2026-09-17 03:53	67.05	OK	9680	2026-09-17 03:54	68.37	OK
9681	2026-09-17 03:55	68.17	OK	9682	2026-09-17 03:56	64.60	OK
9683	2026-09-17 03:57	68.07	OK	9684	2026-09-17 03:58	68.17	OK
9685	2026-09-17 03:59	68.03	OK	9686	2026-09-17 04:00	68.99	OK
9687	2026-09-17 04:01	65.97	OK	9688	2026-09-17 04:02	68.32	OK
9689	2026-09-17 04:03	67.43	OK	9690	2026-09-17 04:04	67.06	OK
9691	2026-09-17 04:05	66.17	OK	9692	2026-09-17 04:06	66.07	OK
9693	2026-09-17 04:07	67.24	OK	9694	2026-09-17 04:08	66.57	OK
9695	2026-09-17 04:09	66.50	OK	9696	2026-09-17 04:10	67.29	OK
9697	2026-09-17 04:11	66.13	OK	9698	2026-09-17 04:12	65.42	OK
9699	2026-09-17 04:13	67.56	OK	9700	2026-09-17 04:14	68.47	OK
9701	2026-09-17 04:15	66.13	OK	9702	2026-09-17 04:16	68.46	OK
9703	2026-09-17 04:17	65.61	OK	9704	2026-09-17 04:18	67.49	OK
9705	2026-09-17 04:19	67.50	OK	9706	2026-09-17 04:20	65.41	OK
9707	2026-09-17 04:21	64.07	OK	9708	2026-09-17 04:22	68.70	OK
9709	2026-09-17 04:23	65.67	OK	9710	2026-09-17 04:24	65.37	OK
9711	2026-09-17 04:25	65.64	OK	9712	2026-09-17 04:26	67.55	OK
9713	2026-09-17 04:27	66.55	OK	9714	2026-09-17 04:28	64.31	OK
9715	2026-09-17 04:29	65.27	OK	9716	2026-09-17 04:30	64.33	OK
9717	2026-09-17 04:31	66.04	OK	9718	2026-09-17 04:32	68.92	OK
9719	2026-09-17 04:33	67.92	OK	9720	2026-09-17 04:34	66.87	OK
9721	2026-09-17 04:35	65.12	OK	9722	2026-09-17 04:36	68.60	OK
9723	2026-09-17 04:37	67.94	OK	9724	2026-09-17 04:38	67.87	OK
9725	2026-09-17 04:39	66.90	OK	9726	2026-09-17 04:40	66.27	OK
9727	2026-09-17 04:41	67.46	OK	9728	2026-09-17 04:42	64.01	OK
9729	2026-09-17 04:43	66.45	OK	9730	2026-09-17 04:44	64.31	OK
9731	2026-09-17 04:45	67.44	OK	9732	2026-09-17 04:46	66.62	OK
9733	2026-09-17 04:47	65.37	OK	9734	2026-09-17 04:48	67.01	OK
9735	2026-09-17 04:49	67.11	OK	9736	2026-09-17 04:50	68.78	OK
9737	2026-09-17 04:51	66.74	OK	9738	2026-09-17 04:52	67.25	OK
9739	2026-09-17 04:53	66.35	OK	9740	2026-09-17 04:54	66.97	OK
9741	2026-09-17 04:55	65.49	OK	9742	2026-09-17 04:56	66.64	OK
9743	2026-09-17 04:57	66.46	OK	9744	2026-09-17 04:58	65.89	OK
9745	2026-09-17 04:59	64.31	OK	9746	2026-09-17 05:00	67.07	OK
9747	2026-09-17 05:01	66.69	OK	9748	2026-09-17 05:02	67.33	OK
9749	2026-09-17 05:03	67.85	OK	9750	2026-09-17 05:04	64.24	OK
9751	2026-09-17 05:05	66.18	OK	9752	2026-09-17 05:06	65.36	OK
9753	2026-09-17 05:07	65.41	OK	9754	2026-09-17 05:08	65.23	OK
9755	2026-09-17 05:09	64.70	OK	9756	2026-09-17 05:10	63.40	OK
9757	2026-09-17 05:11	66.46	OK	9758	2026-09-17 05:12	65.03	OK
9759	2026-09-17 05:13	65.88	OK	9760	2026-09-17 05:14	66.15	OK
9761	2026-09-17 05:15	63.91	OK	9762	2026-09-17 05:16	64.78	OK
9763	2026-09-17 05:17	62.99	OK	9764	2026-09-17 05:18	64.08	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9765	2026-09-17 05:19	64.71	OK	9766	2026-09-17 05:20	64.97	OK
9767	2026-09-17 05:21	65.52	OK	9768	2026-09-17 05:22	65.40	OK
9769	2026-09-17 05:23	64.84	OK	9770	2026-09-17 05:24	65.44	OK
9771	2026-09-17 05:25	66.28	OK	9772	2026-09-17 05:26	66.18	OK
9773	2026-09-17 05:27	65.92	OK	9774	2026-09-17 05:28	63.37	OK
9775	2026-09-17 05:29	64.37	OK	9776	2026-09-17 05:30	64.78	OK
9777	2026-09-17 05:31	63.87	OK	9778	2026-09-17 05:32	64.56	OK
9779	2026-09-17 05:33	63.90	OK	9780	2026-09-17 05:34	65.52	OK
9781	2026-09-17 05:35	67.22	OK	9782	2026-09-17 05:36	63.92	OK
9783	2026-09-17 05:37	62.36	OK	9784	2026-09-17 05:38	62.80	OK
9785	2026-09-17 05:39	63.60	OK	9786	2026-09-17 05:40	64.19	OK
9787	2026-09-17 05:41	66.14	OK	9788	2026-09-17 05:42	63.95	OK
9789	2026-09-17 05:43	63.26	OK	9790	2026-09-17 05:44	66.53	OK
9791	2026-09-17 05:45	63.20	OK	9792	2026-09-17 05:46	64.47	OK
9793	2026-09-17 05:47	64.50	OK	9794	2026-09-17 05:48	63.78	OK
9795	2026-09-17 05:49	65.04	OK	9796	2026-09-17 05:50	65.51	OK
9797	2026-09-17 05:51	64.83	OK	9798	2026-09-17 05:52	65.34	OK
9799	2026-09-17 05:53	63.72	OK	9800	2026-09-17 05:54	64.35	OK
9801	2026-09-17 05:55	64.77	OK	9802	2026-09-17 05:56	64.02	OK
9803	2026-09-17 05:57	66.40	OK	9804	2026-09-17 05:58	61.55	OK
9805	2026-09-17 05:59	63.22	OK	9806	2026-09-17 06:00	63.41	OK
9807	2026-09-17 06:01	63.09	OK	9808	2026-09-17 06:02	63.06	OK
9809	2026-09-17 06:03	64.84	OK	9810	2026-09-17 06:04	64.29	OK
9811	2026-09-17 06:05	64.37	OK	9812	2026-09-17 06:06	63.57	OK
9813	2026-09-17 06:07	61.93	OK	9814	2026-09-17 06:08	64.05	OK
9815	2026-09-17 06:09	65.51	OK	9816	2026-09-17 06:10	62.42	OK
9817	2026-09-17 06:11	63.18	OK	9818	2026-09-17 06:12	64.38	OK
9819	2026-09-17 06:13	62.65	OK	9820	2026-09-17 06:14	63.77	OK
9821	2026-09-17 06:15	65.29	OK	9822	2026-09-17 06:16	61.85	OK
9823	2026-09-17 06:17	61.74	OK	9824	2026-09-17 06:18	60.57	OK
9825	2026-09-17 06:19	65.85	OK	9826	2026-09-17 06:20	65.19	OK
9827	2026-09-17 06:21	63.52	OK	9828	2026-09-17 06:22	62.30	OK
9829	2026-09-17 06:23	62.18	OK	9830	2026-09-17 06:24	64.16	OK
9831	2026-09-17 06:25	63.96	OK	9832	2026-09-17 06:26	63.55	OK
9833	2026-09-17 06:27	64.69	OK	9834	2026-09-17 06:28	62.32	OK
9835	2026-09-17 06:29	65.43	OK	9836	2026-09-17 06:30	64.76	OK
9837	2026-09-17 06:31	62.35	OK	9838	2026-09-17 06:32	61.69	OK
9839	2026-09-17 06:33	63.64	OK	9840	2026-09-17 06:34	63.92	OK
9841	2026-09-17 06:35	63.75	OK	9842	2026-09-17 06:36	65.78	OK
9843	2026-09-17 06:37	63.81	OK	9844	2026-09-17 06:38	63.77	OK
9845	2026-09-17 06:39	64.81	OK	9846	2026-09-17 06:40	64.22	OK
9847	2026-09-17 06:41	62.35	OK	9848	2026-09-17 06:42	61.72	OK
9849	2026-09-17 06:43	62.73	OK	9850	2026-09-17 06:44	60.45	OK
9851	2026-09-17 06:45	60.22	OK	9852	2026-09-17 06:46	63.83	OK
9853	2026-09-17 06:47	63.67	OK	9854	2026-09-17 06:48	64.32	OK
9855	2026-09-17 06:49	62.08	OK	9856	2026-09-17 06:50	64.00	OK
9857	2026-09-17 06:51	63.12	OK	9858	2026-09-17 06:52	63.63	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9859	2026-09-17 06:53	62.23	OK	9860	2026-09-17 06:54	60.86	OK
9861	2026-09-17 06:55	62.93	OK	9862	2026-09-17 06:56	60.50	OK
9863	2026-09-17 06:57	64.99	OK	9864	2026-09-17 06:58	61.74	OK
9865	2026-09-17 06:59	60.98	OK	9866	2026-09-17 07:00	61.67	OK
9867	2026-09-17 07:01	62.31	OK	9868	2026-09-17 07:02	60.75	OK
9869	2026-09-17 07:03	60.89	OK	9870	2026-09-17 07:04	62.19	OK
9871	2026-09-17 07:05	61.72	OK	9872	2026-09-17 07:06	61.71	OK
9873	2026-09-17 07:07	61.11	OK	9874	2026-09-17 07:08	60.02	OK
9875	2026-09-17 07:09	62.83	OK	9876	2026-09-17 07:10	61.76	OK
9877	2026-09-17 07:11	62.37	OK	9878	2026-09-17 07:12	61.88	OK
9879	2026-09-17 07:13	63.00	OK	9880	2026-09-17 07:14	63.88	OK
9881	2026-09-17 07:15	62.92	OK	9882	2026-09-17 07:16	62.02	OK
9883	2026-09-17 07:17	61.30	OK	9884	2026-09-17 07:18	63.25	OK
9885	2026-09-17 07:19	63.58	OK	9886	2026-09-17 07:20	61.59	OK
9887	2026-09-17 07:21	60.61	OK	9888	2026-09-17 07:22	62.89	OK
9889	2026-09-17 07:23	62.24	OK	9890	2026-09-17 07:24	62.79	OK
9891	2026-09-17 07:25	61.18	OK	9892	2026-09-17 07:26	61.23	OK
9893	2026-09-17 07:27	61.66	OK	9894	2026-09-17 07:28	64.51	OK
9895	2026-09-17 07:29	63.90	OK	9896	2026-09-17 07:30	62.05	OK
9897	2026-09-17 07:31	63.84	OK	9898	2026-09-17 07:32	61.11	OK
9899	2026-09-17 07:33	63.46	OK	9900	2026-09-17 07:34	62.68	OK
9901	2026-09-17 07:35	64.57	OK	9902	2026-09-17 07:36	64.35	OK
9903	2026-09-17 07:37	60.99	OK	9904	2026-09-17 07:38	63.26	OK
9905	2026-09-17 07:39	61.63	OK	9906	2026-09-17 07:40	60.89	OK
9907	2026-09-17 07:41	61.83	OK	9908	2026-09-17 07:42	61.27	OK
9909	2026-09-17 07:43	60.12	OK	9910	2026-09-17 07:44	63.99	OK
9911	2026-09-17 07:45	62.97	OK	9912	2026-09-17 07:46	60.08	OK
9913	2026-09-17 07:47	60.56	OK	9914	2026-09-17 07:48	60.74	OK
9915	2026-09-17 07:49	60.64	OK	9916	2026-09-17 07:50	62.08	OK
9917	2026-09-17 07:51	63.20	OK	9918	2026-09-17 07:52	59.18	OK
9919	2026-09-17 07:53	62.54	OK	9920	2026-09-17 07:54	60.65	OK
9921	2026-09-17 07:55	59.56	OK	9922	2026-09-17 07:56	61.07	OK
9923	2026-09-17 07:57	61.01	OK	9924	2026-09-17 07:58	62.08	OK
9925	2026-09-17 07:59	62.34	OK	9926	2026-09-17 08:00	61.85	OK
9927	2026-09-17 08:01	59.65	OK	9928	2026-09-17 08:02	59.76	OK
9929	2026-09-17 08:03	61.85	OK	9930	2026-09-17 08:04	62.45	OK
9931	2026-09-17 08:05	57.35	OK	9932	2026-09-17 08:06	61.15	OK
9933	2026-09-17 08:07	60.96	OK	9934	2026-09-17 08:08	60.90	OK
9935	2026-09-17 08:09	61.20	OK	9936	2026-09-17 08:10	62.10	OK
9937	2026-09-17 08:11	61.47	OK	9938	2026-09-17 08:12	60.98	OK
9939	2026-09-17 08:13	60.24	OK	9940	2026-09-17 08:14	59.81	OK
9941	2026-09-17 08:15	58.97	OK	9942	2026-09-17 08:16	59.19	OK
9943	2026-09-17 08:17	61.01	OK	9944	2026-09-17 08:18	60.91	OK
9945	2026-09-17 08:19	61.29	OK	9946	2026-09-17 08:20	62.05	OK
9947	2026-09-17 08:21	59.71	OK	9948	2026-09-17 08:22	60.95	OK
9949	2026-09-17 08:23	61.21	OK	9950	2026-09-17 08:24	60.72	OK
9951	2026-09-17 08:25	60.02	OK	9952	2026-09-17 08:26	61.35	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9953	2026-09-17 08:27	61.38	OK	9954	2026-09-17 08:28	62.81	OK
9955	2026-09-17 08:29	60.94	OK	9956	2026-09-17 08:30	59.63	OK
9957	2026-09-17 08:31	63.70	OK	9958	2026-09-17 08:32	57.78	OK
9959	2026-09-17 08:33	61.00	OK	9960	2026-09-17 08:34	59.56	OK
9961	2026-09-17 08:35	58.95	OK	9962	2026-09-17 08:36	63.01	OK
9963	2026-09-17 08:37	60.48	OK	9964	2026-09-17 08:38	60.01	OK
9965	2026-09-17 08:39	59.38	OK	9966	2026-09-17 08:40	59.49	OK
9967	2026-09-17 08:41	59.83	OK	9968	2026-09-17 08:42	59.13	OK
9969	2026-09-17 08:43	58.69	OK	9970	2026-09-17 08:44	62.11	OK
9971	2026-09-17 08:45	59.42	OK	9972	2026-09-17 08:46	57.33	OK
9973	2026-09-17 08:47	61.41	OK	9974	2026-09-17 08:48	60.87	OK
9975	2026-09-17 08:49	58.37	OK	9976	2026-09-17 08:50	59.38	OK
9977	2026-09-17 08:51	58.32	OK	9978	2026-09-17 08:52	62.17	OK
9979	2026-09-17 08:53	61.05	OK	9980	2026-09-17 08:54	61.06	OK
9981	2026-09-17 08:55	60.12	OK	9982	2026-09-17 08:56	60.28	OK
9983	2026-09-17 08:57	61.59	OK	9984	2026-09-17 08:58	59.37	OK
9985	2026-09-17 08:59	60.38	OK	9986	2026-09-17 09:00	59.52	OK
9987	2026-09-17 09:01	60.77	OK	9988	2026-09-17 09:02	59.06	OK
9989	2026-09-17 09:03	60.78	OK	9990	2026-09-17 09:04	59.63	OK
9991	2026-09-17 09:05	61.17	OK	9992	2026-09-17 09:06	60.81	OK
9993	2026-09-17 09:07	60.91	OK	9994	2026-09-17 09:08	58.88	OK
9995	2026-09-17 09:09	57.62	OK	9996	2026-09-17 09:10	57.45	OK
9997	2026-09-17 09:11	57.72	OK	9998	2026-09-17 09:12	59.47	OK
9999	2026-09-17 09:13	57.19	OK	1000	2026-09-17 09:14	59.22	OK
1000	2026-09-17 09:15	58.23	OK	1000	2026-09-17 09:16	61.97	OK
1000	2026-09-17 09:17	60.40	OK	1000	2026-09-17 09:18	59.53	OK
1000	2026-09-17 09:19	60.49	OK	1000	2026-09-17 09:20	58.46	OK
1000	2026-09-17 09:21	60.97	OK	1000	2026-09-17 09:22	58.33	OK
1000	2026-09-17 09:23	60.16	OK	1001	2026-09-17 09:24	61.51	OK
1001	2026-09-17 09:25	62.93	OK	1001	2026-09-17 09:26	58.50	OK
1001	2026-09-17 09:27	61.56	OK	1001	2026-09-17 09:28	59.73	OK
1001	2026-09-17 09:29	62.27	OK	1001	2026-09-17 09:30	59.02	OK
1001	2026-09-17 09:31	59.72	OK	1001	2026-09-17 09:32	61.20	OK
1001	2026-09-17 09:33	60.44	OK	1002	2026-09-17 09:34	58.97	OK
1002	2026-09-17 09:35	59.40	OK	1002	2026-09-17 09:36	58.92	OK
1002	2026-09-17 09:37	60.44	OK	1002	2026-09-17 09:38	59.02	OK
1002	2026-09-17 09:39	59.22	OK	1002	2026-09-17 09:40	59.12	OK
1002	2026-09-17 09:41	58.55	OK	1002	2026-09-17 09:42	58.92	OK
1002	2026-09-17 09:43	59.88	OK	1003	2026-09-17 09:44	58.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
10031	2026-09-17 09:45	57.89	OK	10032	2026-09-17 09:46	56.57	OK
10033	2026-09-17 09:47	60.38	OK	10034	2026-09-17 09:48	60.54	OK
10035	2026-09-17 09:49	60.96	OK	10036	2026-09-17 09:50	61.63	OK
10037	2026-09-17 09:51	60.77	OK	10038	2026-09-17 09:52	58.64	OK
10039	2026-09-17 09:53	59.39	OK	10040	2026-09-17 09:54	61.47	OK
10041	2026-09-17 09:55	60.85	OK	10042	2026-09-17 09:56	61.39	OK
10043	2026-09-17 09:57	57.40	OK	10044	2026-09-17 09:58	59.74	OK
10045	2026-09-17 09:59	57.14	OK	10046	2026-09-17 10:00	60.05	OK
10047	2026-09-17 10:01	58.45	OK	10048	2026-09-17 10:02	57.45	OK
10049	2026-09-17 10:03	57.64	OK	10050	2026-09-17 10:04	59.48	OK
10051	2026-09-17 10:05	57.72	OK	10052	2026-09-17 10:06	60.93	OK
10053	2026-09-17 10:07	59.10	OK	10054	2026-09-17 10:08	59.85	OK
10055	2026-09-17 10:09	58.19	OK	10056	2026-09-17 10:10	59.80	OK
10057	2026-09-17 10:11	59.73	OK	10058	2026-09-17 10:12	60.35	OK
10059	2026-09-17 10:13	57.77	OK	10060	2026-09-17 10:14	61.47	OK
10061	2026-09-17 10:15	60.69	OK	10062	2026-09-17 10:16	60.07	OK
10063	2026-09-17 10:17	58.66	OK	10064	2026-09-17 10:18	59.19	OK
10065	2026-09-17 10:19	61.86	OK	10066	2026-09-17 10:20	58.79	OK
10067	2026-09-17 10:21	60.19	OK	10068	2026-09-17 10:22	60.24	OK
10069	2026-09-17 10:23	61.45	OK	10070	2026-09-17 10:24	59.49	OK
10071	2026-09-17 10:25	61.42	OK	10072	2026-09-17 10:26	57.52	OK
10073	2026-09-17 10:27	60.14	OK	10074	2026-09-17 10:28	61.34	OK
10075	2026-09-17 10:29	57.40	OK	10076	2026-09-17 10:30	58.09	OK
10077	2026-09-17 10:31	59.08	OK	10078	2026-09-17 10:32	59.32	OK
10079	2026-09-17 10:33	59.34	OK	10080	2026-09-17 10:34	61.26	OK
10081	2026-09-17 10:35	60.38	OK	10082	2026-09-17 10:36	58.92	OK
10083	2026-09-17 10:37	60.11	OK	10084	2026-09-17 10:38	56.79	OK
10085	2026-09-17 10:39	59.46	OK	10086	2026-09-17 10:40	60.19	OK
10087	2026-09-17 10:41	60.38	OK	10088	2026-09-17 10:42	57.11	OK
1008	2026-09-17 10:43	61.51	OK	1009	2026-09-17 10:44	60.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
10091	2026-09-17 10:45	59.47	OK	10092	2026-09-17 10:46	60.87	OK
10093	2026-09-17 10:47	57.94	OK	10094	2026-09-17 10:48	60.50	OK
10095	2026-09-17 10:49	59.49	OK	10096	2026-09-17 10:50	62.00	OK
10097	2026-09-17 10:51	60.99	OK	10098	2026-09-17 10:52	59.93	OK
10099	2026-09-17 10:53	59.49	OK	10100	2026-09-17 10:54	60.62	OK
10101	2026-09-17 10:55	59.75	OK	10102	2026-09-17 10:56	59.94	OK
10103	2026-09-17 10:57	59.73	OK	10104	2026-09-17 10:58	58.29	OK
10105	2026-09-17 10:59	61.63	OK	10106	2026-09-17 11:00	56.72	OK
10107	2026-09-17 11:01	60.37	OK	10108	2026-09-17 11:02	60.62	OK
10109	2026-09-17 11:03	59.47	OK	10110	2026-09-17 11:04	60.42	OK
10111	2026-09-17 11:05	58.55	OK	10112	2026-09-17 11:06	58.55	OK
10113	2026-09-17 11:07	58.64	OK	10114	2026-09-17 11:08	60.90	OK
10115	2026-09-17 11:09	57.24	OK	10116	2026-09-17 11:10	58.87	OK
10117	2026-09-17 11:11	59.36	OK	10118	2026-09-17 11:12	61.96	OK
10119	2026-09-17 11:13	61.01	OK	10120	2026-09-17 11:14	61.54	OK
10121	2026-09-17 11:15	61.26	OK	10122	2026-09-17 11:16	58.04	OK
10123	2026-09-17 11:17	59.20	OK	10124	2026-09-17 11:18	60.91	OK
10125	2026-09-17 11:19	60.23	OK	10126	2026-09-17 11:20	59.42	OK
10127	2026-09-17 11:21	60.08	OK	10128	2026-09-17 11:22	61.29	OK
10129	2026-09-17 11:23	58.72	OK	10130	2026-09-17 11:24	59.15	OK
10131	2026-09-17 11:25	61.37	OK	10132	2026-09-17 11:26	58.48	OK
10133	2026-09-17 11:27	60.23	OK	10134	2026-09-17 11:28	59.44	OK
10135	2026-09-17 11:29	57.77	OK	10136	2026-09-17 11:30	61.39	OK
10137	2026-09-17 11:31	60.65	OK	10138	2026-09-17 11:32	61.36	OK
10139	2026-09-17 11:33	59.33	OK	10140	2026-09-17 11:34	61.12	OK
10141	2026-09-17 11:35	61.77	OK	10142	2026-09-17 11:36	59.25	OK
10143	2026-09-17 11:37	57.97	OK	10144	2026-09-17 11:38	61.93	OK
10145	2026-09-17 11:39	58.52	OK	10146	2026-09-17 11:40	58.24	OK
10147	2026-09-17 11:41	59.98	OK	10148	2026-09-17 11:42	58.67	OK
1014	2026-09-17 11:43	61.04	OK	1015	2026-09-17 11:44	60.34	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
10151	2026-09-17 11:45	60.72	OK	10152	2026-09-17 11:46	58.93	OK
10153	2026-09-17 11:47	62.18	OK	10154	2026-09-17 11:48	60.46	OK
10155	2026-09-17 11:49	60.02	OK	10156	2026-09-17 11:50	59.46	OK
10157	2026-09-17 11:51	60.25	OK	10158	2026-09-17 11:52	57.46	OK
10159	2026-09-17 11:53	59.89	OK	10160	2026-09-17 11:54	60.84	OK
10161	2026-09-17 11:55	57.93	OK	10162	2026-09-17 11:56	61.68	OK
10163	2026-09-17 11:57	62.57	OK	10164	2026-09-17 11:58	61.54	OK
10165	2026-09-17 11:59	59.24	OK	10166	2026-09-17 12:00	60.80	OK
10167	2026-09-17 12:01	59.36	OK	10168	2026-09-17 12:02	60.74	OK
10169	2026-09-17 12:03	61.10	OK	10170	2026-09-17 12:04	58.98	OK
10171	2026-09-17 12:05	60.70	OK	10172	2026-09-17 12:06	59.49	OK
10173	2026-09-17 12:07	61.69	OK	10174	2026-09-17 12:08	60.74	OK
10175	2026-09-17 12:09	60.79	OK	10176	2026-09-17 12:10	61.93	OK
10177	2026-09-17 12:11	60.09	OK	10178	2026-09-17 12:12	60.38	OK
10179	2026-09-17 12:13	59.07	OK	10180	2026-09-17 12:14	61.33	OK
10181	2026-09-17 12:15	62.15	OK	10182	2026-09-17 12:16	58.33	OK
10183	2026-09-17 12:17	59.17	OK	10184	2026-09-17 12:18	58.83	OK
10185	2026-09-17 12:19	60.61	OK	10186	2026-09-17 12:20	60.30	OK
10187	2026-09-17 12:21	60.04	OK	10188	2026-09-17 12:22	60.72	OK
10189	2026-09-17 12:23	59.86	OK	10190	2026-09-17 12:24	60.61	OK
10191	2026-09-17 12:25	60.58	OK	10192	2026-09-17 12:26	59.08	OK
10193	2026-09-17 12:27	61.86	OK	10194	2026-09-17 12:28	61.00	OK
10195	2026-09-17 12:29	61.36	OK	10196	2026-09-17 12:30	60.95	OK
10197	2026-09-17 12:31	61.44	OK	10198	2026-09-17 12:32	61.28	OK
10199	2026-09-17 12:33	58.30	OK	10200	2026-09-17 12:34	60.08	OK
10201	2026-09-17 12:35	61.05	OK	10202	2026-09-17 12:36	59.82	OK
10203	2026-09-17 12:37	62.67	OK	10204	2026-09-17 12:38	59.11	OK
10205	2026-09-17 12:39	61.92	OK	10206	2026-09-17 12:40	59.23	OK
10207	2026-09-17 12:41	62.18	OK	10208	2026-09-17 12:42	61.29	OK
1020	2026-09-17 12:43	59.39	OK	1021	2026-09-17 12:44	58.86	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
10211	2026-09-17 12:45	60.73	OK	10212	2026-09-17 12:46	61.17	OK
10213	2026-09-17 12:47	62.32	OK	10214	2026-09-17 12:48	61.08	OK
10215	2026-09-17 12:49	60.74	OK	10216	2026-09-17 12:50	58.74	OK
10217	2026-09-17 12:51	59.70	OK	10218	2026-09-17 12:52	58.80	OK
10219	2026-09-17 12:53	60.42	OK	10220	2026-09-17 12:54	61.91	OK
10221	2026-09-17 12:55	61.21	OK	10222	2026-09-17 12:56	61.70	OK
10223	2026-09-17 12:57	62.68	OK	10224	2026-09-17 12:58	61.90	OK
10225	2026-09-17 12:59	61.94	OK	10226	2026-09-17 13:00	62.23	OK
10227	2026-09-17 13:01	59.50	OK	10228	2026-09-17 13:02	60.01	OK
10229	2026-09-17 13:03	61.51	OK	10230	2026-09-17 13:04	62.20	OK
10231	2026-09-17 13:05	61.30	OK	10232	2026-09-17 13:06	62.65	OK
10233	2026-09-17 13:07	61.52	OK	10234	2026-09-17 13:08	59.10	OK
10235	2026-09-17 13:09	60.68	OK	10236	2026-09-17 13:10	60.44	OK
10237	2026-09-17 13:11	59.49	OK	10238	2026-09-17 13:12	60.08	OK
10239	2026-09-17 13:13	59.64	OK	10240	2026-09-17 13:14	59.33	OK
10241	2026-09-17 13:15	60.32	OK	10242	2026-09-17 13:16	61.76	OK
10243	2026-09-17 13:17	61.58	OK	10244	2026-09-17 13:18	62.85	OK
10245	2026-09-17 13:19	63.44	OK	10246	2026-09-17 13:20	59.20	OK
10247	2026-09-17 13:21	61.88	OK	10248	2026-09-17 13:22	61.59	OK
10249	2026-09-17 13:23	60.59	OK	10250	2026-09-17 13:24	60.36	OK
10251	2026-09-17 13:25	62.70	OK	10252	2026-09-17 13:26	60.37	OK
10253	2026-09-17 13:27	59.36	OK	10254	2026-09-17 13:28	61.26	OK
10255	2026-09-17 13:29	62.91	OK	10256	2026-09-17 13:30	63.20	OK
10257	2026-09-17 13:31	60.42	OK	10258	2026-09-17 13:32	61.39	OK
10259	2026-09-17 13:33	59.04	OK	10260	2026-09-17 13:34	61.50	OK
10261	2026-09-17 13:35	60.42	OK	10262	2026-09-17 13:36	62.80	OK
10263	2026-09-17 13:37	61.34	OK	10264	2026-09-17 13:38	63.14	OK
10265	2026-09-17 13:39	60.03	OK	10266	2026-09-17 13:40	62.13	OK
10267	2026-09-17 13:41	62.55	OK	10268	2026-09-17 13:42	59.87	OK
1026	2026-09-17 13:43	62.81	OK	1027	2026-09-17 13:44	62.47	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
10271	2026-09-17 13:45	63.01	OK	10272	2026-09-17 13:46	62.46	OK
10273	2026-09-17 13:47	61.89	OK	10274	2026-09-17 13:48	62.14	OK
10275	2026-09-17 13:49	62.24	OK	10276	2026-09-17 13:50	62.19	OK
10277	2026-09-17 13:51	62.34	OK	10278	2026-09-17 13:52	63.07	OK
10279	2026-09-17 13:53	59.08	OK	10280	2026-09-17 13:54	62.52	OK
10281	2026-09-17 13:55	62.15	OK	10282	2026-09-17 13:56	60.26	OK
10283	2026-09-17 13:57	63.18	OK	10284	2026-09-17 13:58	59.88	OK
10285	2026-09-17 13:59	60.69	OK	10286	2026-09-17 14:00	63.75	OK
10287	2026-09-17 14:01	60.81	OK	10288	2026-09-17 14:02	61.78	OK
10289	2026-09-17 14:03	61.44	OK	10290	2026-09-17 14:04	59.90	OK
10291	2026-09-17 14:05	60.64	OK	10292	2026-09-17 14:06	63.98	OK
10293	2026-09-17 14:07	61.91	OK	10294	2026-09-17 14:08	61.58	OK
10295	2026-09-17 14:09	63.27	OK	10296	2026-09-17 14:10	61.01	OK
10297	2026-09-17 14:11	63.32	OK	10298	2026-09-17 14:12	61.62	OK
10299	2026-09-17 14:13	61.68	OK	10300	2026-09-17 14:14	64.26	OK
10301	2026-09-17 14:15	61.68	OK	10302	2026-09-17 14:16	60.37	OK
10303	2026-09-17 14:17	61.52	OK	10304	2026-09-17 14:18	63.09	OK
10305	2026-09-17 14:19	62.71	OK	10306	2026-09-17 14:20	59.85	OK
10307	2026-09-17 14:21	62.34	OK	10308	2026-09-17 14:22	60.52	OK
10309	2026-09-17 14:23	62.90	OK	10310	2026-09-17 14:24	62.28	OK
10311	2026-09-17 14:25	64.39	OK	10312	2026-09-17 14:26	60.81	OK
10313	2026-09-17 14:27	62.15	OK	10314	2026-09-17 14:28	63.14	OK
10315	2026-09-17 14:29	60.85	OK	10316	2026-09-17 14:30	60.87	OK
10317	2026-09-17 14:31	61.67	OK	10318	2026-09-17 14:32	62.52	OK
10319	2026-09-17 14:33	63.99	OK	10320	2026-09-17 14:34	61.50	OK
10321	2026-09-17 14:35	61.76	OK	10322	2026-09-17 14:36	62.23	OK
10323	2026-09-17 14:37	62.90	OK	10324	2026-09-17 14:38	62.73	OK
10325	2026-09-17 14:39	62.79	OK	10326	2026-09-17 14:40	62.90	OK
10327	2026-09-17 14:41	63.49	OK	10328	2026-09-17 14:42	64.82	OK
10329	2026-09-17 14:43	60.26	OK	10330	2026-09-17 14:44	63.09	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
10331	2026-09-17 14:45	61.06	OK	10332	2026-09-17 14:46	63.57	OK
10333	2026-09-17 14:47	65.33	OK	10334	2026-09-17 14:48	64.33	OK
10335	2026-09-17 14:49	63.53	OK	10336	2026-09-17 14:50	61.31	OK
10337	2026-09-17 14:51	63.03	OK	10338	2026-09-17 14:52	63.77	OK
10339	2026-09-17 14:53	64.09	OK	10340	2026-09-17 14:54	63.49	OK
10341	2026-09-17 14:55	64.47	OK	10342	2026-09-17 14:56	62.56	OK
10343	2026-09-17 14:57	63.72	OK	10344	2026-09-17 14:58	63.40	OK
10345	2026-09-17 14:59	63.61	OK	10346	2026-09-17 15:00	64.00	OK
10347	2026-09-17 15:01	62.02	OK	10348	2026-09-17 15:02	63.18	OK
10349	2026-09-17 15:03	63.65	OK	10350	2026-09-17 15:04	63.36	OK
10351	2026-09-17 15:05	62.94	OK	10352	2026-09-17 15:06	63.98	OK
10353	2026-09-17 15:07	64.28	OK	10354	2026-09-17 15:08	64.71	OK
10355	2026-09-17 15:09	64.08	OK	10356	2026-09-17 15:10	64.65	OK
10357	2026-09-17 15:11	63.20	OK	10358	2026-09-17 15:12	66.39	OK
10359	2026-09-17 15:13	64.64	OK	10360	2026-09-17 15:14	62.47	OK
10361	2026-09-17 15:15	64.22	OK	10362	2026-09-17 15:16	62.78	OK
10363	2026-09-17 15:17	64.44	OK	10364	2026-09-17 15:18	65.66	OK
10365	2026-09-17 15:19	64.34	OK	10366	2026-09-17 15:20	64.52	OK
10367	2026-09-17 15:21	63.20	OK	10368	2026-09-17 15:22	64.22	OK
10369	2026-09-17 15:23	63.83	OK	10370	2026-09-17 15:24	61.87	OK
10371	2026-09-17 15:25	63.03	OK	10372	2026-09-17 15:26	63.29	OK
10373	2026-09-17 15:27	64.43	OK	10374	2026-09-17 15:28	66.38	OK
10375	2026-09-17 15:29	62.54	OK	10376	2026-09-17 15:30	65.55	OK
10377	2026-09-17 15:31	62.30	OK	10378	2026-09-17 15:32	60.69	OK
10379	2026-09-17 15:33	64.78	OK	10380	2026-09-17 15:34	64.76	OK
10381	2026-09-17 15:35	64.56	OK	10382	2026-09-17 15:36	65.36	OK
10383	2026-09-17 15:37	64.60	OK	10384	2026-09-17 15:38	63.59	OK
10385	2026-09-17 15:39	65.86	OK	10386	2026-09-17 15:40	64.93	OK
10387	2026-09-17 15:41	64.70	OK	10388	2026-09-17 15:42	63.36	OK
1038	2026-09-17 15:43	66.45	OK	1039	2026-09-17 15:44	66.38	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
10391	2026-09-17 15:45	65.70	OK	10392	2026-09-17 15:46	65.35	OK
10393	2026-09-17 15:47	65.29	OK	10394	2026-09-17 15:48	64.45	OK
10395	2026-09-17 15:49	64.50	OK	10396	2026-09-17 15:50	64.21	OK
10397	2026-09-17 15:51	64.66	OK	10398	2026-09-17 15:52	64.57	OK
10399	2026-09-17 15:53	66.69	OK	10400	2026-09-17 15:54	64.61	OK
10401	2026-09-17 15:55	66.90	OK	10402	2026-09-17 15:56	64.47	OK
10403	2026-09-17 15:57	65.90	OK	10404	2026-09-17 15:58	65.27	OK
10405	2026-09-17 15:59	66.91	OK	10406	2026-09-17 16:00	67.77	OK
10407	2026-09-17 16:01	65.31	OK	10408	2026-09-17 16:02	66.37	OK
10409	2026-09-17 16:03	63.93	OK	10410	2026-09-17 16:04	66.09	OK
10411	2026-09-17 16:05	64.22	OK	10412	2026-09-17 16:06	66.28	OK
10413	2026-09-17 16:07	66.13	OK	10414	2026-09-17 16:08	65.49	OK
10415	2026-09-17 16:09	63.36	OK	10416	2026-09-17 16:10	67.20	OK
10417	2026-09-17 16:11	67.38	OK	10418	2026-09-17 16:12	67.09	OK
10419	2026-09-17 16:13	67.19	OK	10420	2026-09-17 16:14	66.62	OK
10421	2026-09-17 16:15	64.83	OK	10422	2026-09-17 16:16	64.75	OK
10423	2026-09-17 16:17	63.94	OK	10424	2026-09-17 16:18	65.63	OK
10425	2026-09-17 16:19	63.91	OK	10426	2026-09-17 16:20	66.12	OK
10427	2026-09-17 16:21	64.57	OK	10428	2026-09-17 16:22	65.60	OK
10429	2026-09-17 16:23	67.76	OK	10430	2026-09-17 16:24	64.20	OK
10431	2026-09-17 16:25	65.91	OK	10432	2026-09-17 16:26	65.16	OK
10433	2026-09-17 16:27	65.25	OK	10434	2026-09-17 16:28	65.12	OK
10435	2026-09-17 16:29	63.69	OK	10436	2026-09-17 16:30	64.30	OK
10437	2026-09-17 16:31	63.98	OK	10438	2026-09-17 16:32	63.38	OK
10439	2026-09-17 16:33	66.84	OK	10440	2026-09-17 16:34	66.55	OK
10441	2026-09-17 16:35	65.04	OK	10442	2026-09-17 16:36	67.24	OK
10443	2026-09-17 16:37	64.84	OK	10444	2026-09-17 16:38	65.11	OK
10445	2026-09-17 16:39	65.23	OK	10446	2026-09-17 16:40	63.33	OK
10447	2026-09-17 16:41	66.69	OK	10448	2026-09-17 16:42	66.71	OK
10449	2026-09-17 16:43	67.38	OK	1045	2026-09-17 16:44	64.60	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
10451	2026-09-17 16:45	64.66	OK	10452	2026-09-17 16:46	65.89	OK
10453	2026-09-17 16:47	64.19	OK	10454	2026-09-17 16:48	66.66	OK
10455	2026-09-17 16:49	66.56	OK	10456	2026-09-17 16:50	65.17	OK
10457	2026-09-17 16:51	66.60	OK	10458	2026-09-17 16:52	64.89	OK
10459	2026-09-17 16:53	66.93	OK	10460	2026-09-17 16:54	65.37	OK
10461	2026-09-17 16:55	64.49	OK	10462	2026-09-17 16:56	66.03	OK
10463	2026-09-17 16:57	67.78	OK	10464	2026-09-17 16:58	65.92	OK
10465	2026-09-17 16:59	66.33	OK	10466	2026-09-17 17:00	65.77	OK
10467	2026-09-17 17:01	68.45	OK	10468	2026-09-17 17:02	65.35	OK
10469	2026-09-17 17:03	67.40	OK	10470	2026-09-17 17:04	68.63	OK
10471	2026-09-17 17:05	65.51	OK	10472	2026-09-17 17:06	66.56	OK
10473	2026-09-17 17:07	65.54	OK	10474	2026-09-17 17:08	68.30	OK
10475	2026-09-17 17:09	67.60	OK	10476	2026-09-17 17:10	65.05	OK
10477	2026-09-17 17:11	67.03	OK	10478	2026-09-17 17:12	68.71	OK
10479	2026-09-17 17:13	68.07	OK	10480	2026-09-17 17:14	69.10	OK
10481	2026-09-17 17:15	68.05	OK	10482	2026-09-17 17:16	67.20	OK
10483	2026-09-17 17:17	65.12	OK	10484	2026-09-17 17:18	67.08	OK
10485	2026-09-17 17:19	67.30	OK	10486	2026-09-17 17:20	67.39	OK
10487	2026-09-17 17:21	66.91	OK	10488	2026-09-17 17:22	68.24	OK
10489	2026-09-17 17:23	65.67	OK	10490	2026-09-17 17:24	68.26	OK
10491	2026-09-17 17:25	69.01	OK	10492	2026-09-17 17:26	66.92	OK
10493	2026-09-17 17:27	66.91	OK	10494	2026-09-17 17:28	66.71	OK
10495	2026-09-17 17:29	66.70	OK	10496	2026-09-17 17:30	68.76	OK
10497	2026-09-17 17:31	66.54	OK	10498	2026-09-17 17:32	69.90	OK
10499	2026-09-17 17:33	68.18	OK	10500	2026-09-17 17:34	65.47	OK
10501	2026-09-17 17:35	68.95	OK	10502	2026-09-17 17:36	68.05	OK
10503	2026-09-17 17:37	68.29	OK	10504	2026-09-17 17:38	66.62	OK
10505	2026-09-17 17:39	67.82	OK	10506	2026-09-17 17:40	68.51	OK
10507	2026-09-17 17:41	66.16	OK	10508	2026-09-17 17:42	66.67	OK
10509	2026-09-17 17:43	70.57	OK	10510	2026-09-17 17:44	67.08	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
10511	2026-09-17 17:45	67.80	OK	10512	2026-09-17 17:46	67.07	OK
10513	2026-09-17 17:47	66.52	OK	10514	2026-09-17 17:48	70.53	OK
10515	2026-09-17 17:49	69.68	OK	10516	2026-09-17 17:50	69.06	OK
10517	2026-09-17 17:51	69.35	OK	10518	2026-09-17 17:52	67.79	OK
10519	2026-09-17 17:53	66.81	OK	10520	2026-09-17 17:54	69.48	OK
10521	2026-09-17 17:55	66.36	OK	10522	2026-09-17 17:56	66.97	OK
10523	2026-09-17 17:57	69.08	OK	10524	2026-09-17 17:58	68.36	OK
10525	2026-09-17 17:59	69.09	OK	10526	2026-09-17 18:00	69.78	OK
10527	2026-09-17 18:01	66.70	OK	10528	2026-09-17 18:02	70.16	OK
10529	2026-09-17 18:03	70.25	OK	10530	2026-09-17 18:04	70.28	OK
10531	2026-09-17 18:05	67.91	OK	10532	2026-09-17 18:06	67.01	OK
10533	2026-09-17 18:07	65.66	OK	10534	2026-09-17 18:08	68.75	OK
10535	2026-09-17 18:09	69.75	OK	10536	2026-09-17 18:10	68.35	OK
10537	2026-09-17 18:11	69.37	OK	10538	2026-09-17 18:12	70.32	OK
10539	2026-09-17 18:13	71.24	OK	10540	2026-09-17 18:14	69.08	OK
10541	2026-09-17 18:15	68.98	OK	10542	2026-09-17 18:16	66.44	OK
10543	2026-09-17 18:17	69.91	OK	10544	2026-09-17 18:18	65.88	OK
10545	2026-09-17 18:19	68.38	OK	10546	2026-09-17 18:20	69.08	OK
10547	2026-09-17 18:21	69.83	OK	10548	2026-09-17 18:22	70.23	OK
10549	2026-09-17 18:23	68.92	OK	10550	2026-09-17 18:24	67.72	OK
10551	2026-09-17 18:25	66.69	OK	10552	2026-09-17 18:26	70.39	OK
10553	2026-09-17 18:27	68.55	OK	10554	2026-09-17 18:28	69.13	OK
10555	2026-09-17 18:29	68.17	OK	10556	2026-09-17 18:30	69.25	OK
10557	2026-09-17 18:31	68.88	OK	10558	2026-09-17 18:32	67.11	OK
10559	2026-09-17 18:33	69.09	OK	10560	2026-09-17 18:34	69.89	OK
10561	2026-09-17 18:35	70.52	OK	10562	2026-09-17 18:36	67.41	OK
10563	2026-09-17 18:37	70.14	OK	10564	2026-09-17 18:38	70.01	OK
10565	2026-09-17 18:39	69.67	OK	10566	2026-09-17 18:40	70.36	OK
10567	2026-09-17 18:41	69.52	OK	10568	2026-09-17 18:42	70.88	OK
1056	2026-09-17 18:43	69.46	OK	1057	2026-09-17 18:44	68.00	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
10571	2026-09-17 18:45	69.84	OK	10572	2026-09-17 18:46	70.10	OK
10573	2026-09-17 18:47	68.96	OK	10574	2026-09-17 18:48	71.41	OK
10575	2026-09-17 18:49	67.88	OK	10576	2026-09-17 18:50	67.88	OK
10577	2026-09-17 18:51	69.54	OK	10578	2026-09-17 18:52	68.51	OK
10579	2026-09-17 18:53	71.45	OK	10580	2026-09-17 18:54	72.40	OK
10581	2026-09-17 18:55	66.70	OK	10582	2026-09-17 18:56	69.02	OK
10583	2026-09-17 18:57	68.53	OK	10584	2026-09-17 18:58	69.92	OK
10585	2026-09-17 18:59	68.73	OK	10586	2026-09-17 19:00	68.84	OK
10587	2026-09-17 19:01	69.02	OK	10588	2026-09-17 19:02	70.46	OK
10589	2026-09-17 19:03	69.24	OK	10590	2026-09-17 19:04	68.74	OK
10591	2026-09-17 19:05	70.73	OK	10592	2026-09-17 19:06	67.90	OK
10593	2026-09-17 19:07	69.06	OK	10594	2026-09-17 19:08	69.49	OK
10595	2026-09-17 19:09	72.32	OK	10596	2026-09-17 19:10	70.07	OK
10597	2026-09-17 19:11	71.13	OK	10598	2026-09-17 19:12	68.22	OK
10599	2026-09-17 19:13	69.54	OK	10600	2026-09-17 19:14	69.19	OK
10601	2026-09-17 19:15	71.78	OK	10602	2026-09-17 19:16	68.90	OK
10603	2026-09-17 19:17	71.39	OK	10604	2026-09-17 19:18	71.58	OK
10605	2026-09-17 19:19	69.38	OK	10606	2026-09-17 19:20	69.80	OK
10607	2026-09-17 19:21	69.19	OK	10608	2026-09-17 19:22	71.36	OK
10609	2026-09-17 19:23	67.92	OK	10610	2026-09-17 19:24	71.25	OK
10611	2026-09-17 19:25	71.44	OK	10612	2026-09-17 19:26	70.45	OK
10613	2026-09-17 19:27	71.95	OK	10614	2026-09-17 19:28	69.99	OK
10615	2026-09-17 19:29	71.07	OK	10616	2026-09-17 19:30	73.20	OK
10617	2026-09-17 19:31	67.93	OK	10618	2026-09-17 19:32	69.86	OK
10619	2026-09-17 19:33	71.11	OK	10620	2026-09-17 19:34	70.93	OK
10621	2026-09-17 19:35	73.47	OK	10622	2026-09-17 19:36	72.93	OK
10623	2026-09-17 19:37	71.66	OK	10624	2026-09-17 19:38	67.79	OK
10625	2026-09-17 19:39	68.55	OK	10626	2026-09-17 19:40	69.11	OK
10627	2026-09-17 19:41	69.22	OK	10628	2026-09-17 19:42	71.13	OK
1062	2026-09-17 19:43	74.31	OK	1063	2026-09-17 19:44	68.02	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
10631	2026-09-17 19:45	72.09	OK	10632	2026-09-17 19:46	69.68	OK
10633	2026-09-17 19:47	71.49	OK	10634	2026-09-17 19:48	70.01	OK
10635	2026-09-17 19:49	70.66	OK	10636	2026-09-17 19:50	68.91	OK
10637	2026-09-17 19:51	70.93	OK	10638	2026-09-17 19:52	69.31	OK
10639	2026-09-17 19:53	71.34	OK	10640	2026-09-17 19:54	71.04	OK
10641	2026-09-17 19:55	73.27	OK	10642	2026-09-17 19:56	73.45	OK
10643	2026-09-17 19:57	73.27	OK	10644	2026-09-17 19:58	72.40	OK
10645	2026-09-17 19:59	73.14	OK	10646	2026-09-17 20:00	71.08	OK
10647	2026-09-17 20:01	68.75	OK	10648	2026-09-17 20:02	69.54	OK
10649	2026-09-17 20:03	70.86	OK	10650	2026-09-17 20:04	73.24	OK
10651	2026-09-17 20:05	72.88	OK	10652	2026-09-17 20:06	71.22	OK
10653	2026-09-17 20:07	71.92	OK	10654	2026-09-17 20:08	72.24	OK
10655	2026-09-17 20:09	70.77	OK	10656	2026-09-17 20:10	72.45	OK
10657	2026-09-17 20:11	69.18	OK	10658	2026-09-17 20:12	68.96	OK
10659	2026-09-17 20:13	70.69	OK	10660	2026-09-17 20:14	71.90	OK
10661	2026-09-17 20:15	70.32	OK	10662	2026-09-17 20:16	70.98	OK
10663	2026-09-17 20:17	70.96	OK	10664	2026-09-17 20:18	71.91	OK
10665	2026-09-17 20:19	69.95	OK	10666	2026-09-17 20:20	71.20	OK
10667	2026-09-17 20:21	71.01	OK	10668	2026-09-17 20:22	71.05	OK
10669	2026-09-17 20:23	71.25	OK	10670	2026-09-17 20:24	71.91	OK
10671	2026-09-17 20:25	68.60	OK	10672	2026-09-17 20:26	73.22	OK
10673	2026-09-17 20:27	70.19	OK	10674	2026-09-17 20:28	69.93	OK
10675	2026-09-17 20:29	70.60	OK	10676	2026-09-17 20:30	72.92	OK
10677	2026-09-17 20:31	70.97	OK	10678	2026-09-17 20:32	71.46	OK
10679	2026-09-17 20:33	73.92	OK	10680	2026-09-17 20:34	71.92	OK
10681	2026-09-17 20:35	72.75	OK	10682	2026-09-17 20:36	70.00	OK
10683	2026-09-17 20:37	70.13	OK	10684	2026-09-17 20:38	72.19	OK
10685	2026-09-17 20:39	73.32	OK	10686	2026-09-17 20:40	70.10	OK
10687	2026-09-17 20:41	69.17	OK	10688	2026-09-17 20:42	70.52	OK
1068	2026-09-17 20:43	69.89	OK	1069	2026-09-17 20:44	73.31	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
10691	2026-09-17 20:45	71.71	OK	10692	2026-09-17 20:46	73.58	OK
10693	2026-09-17 20:47	72.76	OK	10694	2026-09-17 20:48	69.68	OK
10695	2026-09-17 20:49	72.69	OK	10696	2026-09-17 20:50	71.60	OK
10697	2026-09-17 20:51	72.19	OK	10698	2026-09-17 20:52	69.93	OK
10699	2026-09-17 20:53	72.62	OK	10700	2026-09-17 20:54	70.78	OK
10701	2026-09-17 20:55	70.80	OK	10702	2026-09-17 20:56	70.11	OK
10703	2026-09-17 20:57	71.78	OK	10704	2026-09-17 20:58	72.54	OK
10705	2026-09-17 20:59	70.49	OK	10706	2026-09-17 21:00	71.44	OK
10707	2026-09-17 21:01	71.82	OK	10708	2026-09-17 21:02	73.17	OK
10709	2026-09-17 21:03	71.54	OK	10710	2026-09-17 21:04	73.43	OK
10711	2026-09-17 21:05	72.27	OK	10712	2026-09-17 21:06	71.52	OK
10713	2026-09-17 21:07	72.87	OK	10714	2026-09-17 21:08	70.70	OK
10715	2026-09-17 21:09	73.67	OK	10716	2026-09-17 21:10	71.17	OK
10717	2026-09-17 21:11	73.16	OK	10718	2026-09-17 21:12	70.26	OK
10719	2026-09-17 21:13	72.35	OK	10720	2026-09-17 21:14	72.05	OK
10721	2026-09-17 21:15	70.93	OK	10722	2026-09-17 21:16	72.30	OK
10723	2026-09-17 21:17	70.43	OK	10724	2026-09-17 21:18	71.64	OK
10725	2026-09-17 21:19	72.29	OK	10726	2026-09-17 21:20	74.02	OK
10727	2026-09-17 21:21	70.89	OK	10728	2026-09-17 21:22	71.00	OK
10729	2026-09-17 21:23	73.14	OK	10730	2026-09-17 21:24	72.68	OK
10731	2026-09-17 21:25	70.63	OK	10732	2026-09-17 21:26	72.83	OK
10733	2026-09-17 21:27	74.23	OK	10734	2026-09-17 21:28	70.87	OK
10735	2026-09-17 21:29	69.43	OK	10736	2026-09-17 21:30	72.38	OK
10737	2026-09-17 21:31	72.34	OK	10738	2026-09-17 21:32	71.76	OK
10739	2026-09-17 21:33	74.50	OK	10740	2026-09-17 21:34	75.07	OK
10741	2026-09-17 21:35	71.68	OK	10742	2026-09-17 21:36	73.52	OK
10743	2026-09-17 21:37	73.62	OK	10744	2026-09-17 21:38	73.01	OK
10745	2026-09-17 21:39	71.21	OK	10746	2026-09-17 21:40	73.02	OK
10747	2026-09-17 21:41	72.18	OK	10748	2026-09-17 21:42	72.70	OK
1074	2026-09-17 21:43	70.66	OK	1075	2026-09-17 21:44	69.28	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
10751	2026-09-17 21:45	72.12	OK	10752	2026-09-17 21:46	70.65	OK
10753	2026-09-17 21:47	70.76	OK	10754	2026-09-17 21:48	72.28	OK
10755	2026-09-17 21:49	71.82	OK	10756	2026-09-17 21:50	73.12	OK
10757	2026-09-17 21:51	71.75	OK	10758	2026-09-17 21:52	72.62	OK
10759	2026-09-17 21:53	71.32	OK	10760	2026-09-17 21:54	73.84	OK
10761	2026-09-17 21:55	72.45	OK	10762	2026-09-17 21:56	71.73	OK
10763	2026-09-17 21:57	71.41	OK	10764	2026-09-17 21:58	71.31	OK
10765	2026-09-17 21:59	72.50	OK	10766	2026-09-17 22:00	71.60	OK
10767	2026-09-17 22:01	71.24	OK	10768	2026-09-17 22:02	73.37	OK
10769	2026-09-17 22:03	71.96	OK	10770	2026-09-17 22:04	74.54	OK
10771	2026-09-17 22:05	74.76	OK	10772	2026-09-17 22:06	73.95	OK
10773	2026-09-17 22:07	72.48	OK	10774	2026-09-17 22:08	74.19	OK
10775	2026-09-17 22:09	72.80	OK	10776	2026-09-17 22:10	70.36	OK
10777	2026-09-17 22:11	72.28	OK	10778	2026-09-17 22:12	71.41	OK
10779	2026-09-17 22:13	74.24	OK	10780	2026-09-17 22:14	74.00	OK
10781	2026-09-17 22:15	74.49	OK	10782	2026-09-17 22:16	73.41	OK
10783	2026-09-17 22:17	73.70	OK	10784	2026-09-17 22:18	71.45	OK
10785	2026-09-17 22:19	73.22	OK	10786	2026-09-17 22:20	71.25	OK
10787	2026-09-17 22:21	71.85	OK	10788	2026-09-17 22:22	74.29	OK
10789	2026-09-17 22:23	75.01	OK	10790	2026-09-17 22:24	71.86	OK
10791	2026-09-17 22:25	75.39	OK	10792	2026-09-17 22:26	70.85	OK
10793	2026-09-17 22:27	72.39	OK	10794	2026-09-17 22:28	71.87	OK
10795	2026-09-17 22:29	74.52	OK	10796	2026-09-17 22:30	71.04	OK
10797	2026-09-17 22:31	71.82	OK	10798	2026-09-17 22:32	70.44	OK
10799	2026-09-17 22:33	74.80	OK	10800	2026-09-17 22:34	73.09	OK
10801	2026-09-17 22:35	72.25	OK	10802	2026-09-17 22:36	73.19	OK
10803	2026-09-17 22:37	72.10	OK	10804	2026-09-17 22:38	74.42	OK
10805	2026-09-17 22:39	73.09	OK	10806	2026-09-17 22:40	73.89	OK
10807	2026-09-17 22:41	71.45	OK	10808	2026-09-17 22:42	73.64	OK
1080	2026-09-17 22:43	70.61	OK	1081	2026-09-17 22:44	71.72	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
10811	2026-09-17 22:45	74.07	OK	10812	2026-09-17 22:46	73.42	OK
10813	2026-09-17 22:47	71.11	OK	10814	2026-09-17 22:48	73.98	OK
10815	2026-09-17 22:49	73.17	OK	10816	2026-09-17 22:50	71.18	OK
10817	2026-09-17 22:51	72.70	OK	10818	2026-09-17 22:52	74.88	OK
10819	2026-09-17 22:53	73.69	OK	10820	2026-09-17 22:54	72.14	OK
10821	2026-09-17 22:55	72.57	OK	10822	2026-09-17 22:56	72.84	OK
10823	2026-09-17 22:57	74.76	OK	10824	2026-09-17 22:58	72.29	OK
10825	2026-09-17 22:59	71.32	OK	10826	2026-09-17 23:00	72.23	OK
10827	2026-09-17 23:01	73.72	OK	10828	2026-09-17 23:02	71.41	OK
10829	2026-09-17 23:03	71.27	OK	10830	2026-09-17 23:04	72.04	OK
10831	2026-09-17 23:05	72.25	OK	10832	2026-09-17 23:06	73.79	OK
10833	2026-09-17 23:07	73.45	OK	10834	2026-09-17 23:08	71.87	OK
10835	2026-09-17 23:09	74.59	OK	10836	2026-09-17 23:10	71.04	OK
10837	2026-09-17 23:11	72.52	OK	10838	2026-09-17 23:12	73.50	OK
10839	2026-09-17 23:13	75.22	OK	10840	2026-09-17 23:14	70.79	OK
10841	2026-09-17 23:15	73.15	OK	10842	2026-09-17 23:16	71.58	OK
10843	2026-09-17 23:17	71.08	OK	10844	2026-09-17 23:18	72.46	OK
10845	2026-09-17 23:19	72.51	OK	10846	2026-09-17 23:20	72.92	OK
10847	2026-09-17 23:21	72.71	OK	10848	2026-09-17 23:22	71.24	OK
10849	2026-09-17 23:23	73.00	OK	10850	2026-09-17 23:24	72.30	OK
10851	2026-09-17 23:25	74.41	OK	10852	2026-09-17 23:26	71.82	OK
10853	2026-09-17 23:27	71.68	OK	10854	2026-09-17 23:28	75.39	OK
10855	2026-09-17 23:29	71.88	OK	10856	2026-09-17 23:30	72.32	OK
10857	2026-09-17 23:31	71.88	OK	10858	2026-09-17 23:32	73.26	OK
10859	2026-09-17 23:33	70.73	OK	10860	2026-09-17 23:34	71.33	OK
10861	2026-09-17 23:35	73.13	OK	10862	2026-09-17 23:36	74.16	OK
10863	2026-09-17 23:37	75.77	OK	10864	2026-09-17 23:38	70.92	OK
10865	2026-09-17 23:39	70.80	OK	10866	2026-09-17 23:40	71.36	OK
10867	2026-09-17 23:41	70.88	OK	10868	2026-09-17 23:42	72.17	OK
1086	2026-09-17 23:43	72.53	OK	1087	2026-09-17 23:44	72.41	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
10871	2026-09-17 23:45	71.10	OK	10872	2026-09-17 23:46	73.31	OK
10873	2026-09-17 23:47	71.47	OK	10874	2026-09-17 23:48	71.28	OK
10875	2026-09-17 23:49	72.84	OK	10876	2026-09-17 23:50	74.38	OK
10877	2026-09-17 23:51	72.74	OK	10878	2026-09-17 23:52	71.28	OK
10879	2026-09-17 23:53	71.57	OK	10880	2026-09-17 23:54	72.93	OK
10881	2026-09-17 23:55	71.36	OK	10882	2026-09-17 23:56	70.68	OK
10883	2026-09-17 23:57	71.86	OK	10884	2026-09-17 23:58	70.89	OK
10885	2026-09-17 23:59	70.34	OK	10886	2026-09-18 00:00	71.88	OK
10887	2026-09-18 00:01	72.97	OK	10888	2026-09-18 00:02	73.05	OK
10889	2026-09-18 00:03	72.60	OK	10890	2026-09-18 00:04	73.59	OK
10891	2026-09-18 00:05	72.83	OK	10892	2026-09-18 00:06	73.82	OK
10893	2026-09-18 00:07	71.09	OK	10894	2026-09-18 00:08	73.69	OK
10895	2026-09-18 00:09	72.00	OK	10896	2026-09-18 00:10	72.41	OK
10897	2026-09-18 00:11	70.49	OK	10898	2026-09-18 00:12	72.22	OK
10899	2026-09-18 00:13	70.77	OK	10900	2026-09-18 00:14	73.23	OK
10901	2026-09-18 00:15	71.37	OK	10902	2026-09-18 00:16	73.04	OK
10903	2026-09-18 00:17	71.73	OK	10904	2026-09-18 00:18	70.64	OK
10905	2026-09-18 00:19	73.48	OK	10906	2026-09-18 00:20	72.76	OK
10907	2026-09-18 00:21	73.35	OK	10908	2026-09-18 00:22	72.20	OK
10909	2026-09-18 00:23	73.90	OK	10910	2026-09-18 00:24	74.92	OK
10911	2026-09-18 00:25	70.95	OK	10912	2026-09-18 00:26	74.03	OK
10913	2026-09-18 00:27	72.99	OK	10914	2026-09-18 00:28	72.56	OK
10915	2026-09-18 00:29	71.31	OK	10916	2026-09-18 00:30	73.03	OK
10917	2026-09-18 00:31	72.24	OK	10918	2026-09-18 00:32	72.45	OK
10919	2026-09-18 00:33	71.52	OK	10920	2026-09-18 00:34	71.29	OK
10921	2026-09-18 00:35	73.33	OK	10922	2026-09-18 00:36	73.39	OK
10923	2026-09-18 00:37	71.86	OK	10924	2026-09-18 00:38	70.56	OK
10925	2026-09-18 00:39	72.24	OK	10926	2026-09-18 00:40	73.92	OK
10927	2026-09-18 00:41	71.67	OK	10928	2026-09-18 00:42	72.42	OK
10929	2026-09-18 00:43	73.42	OK	10930	2026-09-18 00:44	71.40	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
10931	2026-09-18 00:45	72.66	OK	10932	2026-09-18 00:46	72.94	OK
10933	2026-09-18 00:47	72.58	OK	10934	2026-09-18 00:48	71.06	OK
10935	2026-09-18 00:49	71.88	OK	10936	2026-09-18 00:50	72.80	OK
10937	2026-09-18 00:51	71.73	OK	10938	2026-09-18 00:52	70.34	OK
10939	2026-09-18 00:53	72.99	OK	10940	2026-09-18 00:54	73.92	OK
10941	2026-09-18 00:55	69.28	OK	10942	2026-09-18 00:56	71.76	OK
10943	2026-09-18 00:57	69.20	OK	10944	2026-09-18 00:58	71.41	OK
10945	2026-09-18 00:59	71.71	OK	10946	2026-09-18 01:00	70.10	OK
10947	2026-09-18 01:01	74.73	OK	10948	2026-09-18 01:02	71.06	OK
10949	2026-09-18 01:03	71.68	OK	10950	2026-09-18 01:04	71.56	OK
10951	2026-09-18 01:05	72.14	OK	10952	2026-09-18 01:06	71.41	OK
10953	2026-09-18 01:07	71.62	OK	10954	2026-09-18 01:08	69.31	OK
10955	2026-09-18 01:09	72.95	OK	10956	2026-09-18 01:10	70.39	OK
10957	2026-09-18 01:11	72.11	OK	10958	2026-09-18 01:12	69.22	OK
10959	2026-09-18 01:13	71.32	OK	10960	2026-09-18 01:14	73.35	OK
10961	2026-09-18 01:15	70.00	OK	10962	2026-09-18 01:16	69.87	OK
10963	2026-09-18 01:17	68.33	OK	10964	2026-09-18 01:18	70.41	OK
10965	2026-09-18 01:19	71.35	OK	10966	2026-09-18 01:20	71.80	OK
10967	2026-09-18 01:21	71.66	OK	10968	2026-09-18 01:22	72.21	OK
10969	2026-09-18 01:23	69.45	OK	10970	2026-09-18 01:24	71.81	OK
10971	2026-09-18 01:25	71.58	OK	10972	2026-09-18 01:26	71.46	OK
10973	2026-09-18 01:27	68.96	OK	10974	2026-09-18 01:28	70.45	OK
10975	2026-09-18 01:29	71.58	OK	10976	2026-09-18 01:30	69.75	OK
10977	2026-09-18 01:31	71.41	OK	10978	2026-09-18 01:32	70.33	OK
10979	2026-09-18 01:33	69.97	OK	10980	2026-09-18 01:34	70.32	OK
10981	2026-09-18 01:35	71.35	OK	10982	2026-09-18 01:36	67.96	OK
10983	2026-09-18 01:37	70.68	OK	10984	2026-09-18 01:38	70.92	OK
10985	2026-09-18 01:39	71.01	OK	10986	2026-09-18 01:40	69.76	OK
10987	2026-09-18 01:41	68.67	OK	10988	2026-09-18 01:42	70.54	OK
1098	2026-09-18 01:43	69.90	OK	1099	2026-09-18 01:44	70.56	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
10991	2026-09-18 01:45	72.02	OK	10992	2026-09-18 01:46	72.55	OK
10993	2026-09-18 01:47	72.27	OK	10994	2026-09-18 01:48	70.69	OK
10995	2026-09-18 01:49	72.50	OK	10996	2026-09-18 01:50	67.59	OK
10997	2026-09-18 01:51	70.03	OK	10998	2026-09-18 01:52	70.76	OK
10999	2026-09-18 01:53	71.26	OK	11000	2026-09-18 01:54	70.01	OK
11001	2026-09-18 01:55	71.09	OK	11002	2026-09-18 01:56	72.25	OK
11003	2026-09-18 01:57	70.21	OK	11004	2026-09-18 01:58	71.32	OK
11005	2026-09-18 01:59	71.27	OK	11006	2026-09-18 02:00	71.88	OK
11007	2026-09-18 02:01	69.33	OK	11008	2026-09-18 02:02	70.50	OK
11009	2026-09-18 02:03	71.62	OK	11010	2026-09-18 02:04	72.95	OK
11011	2026-09-18 02:05	69.99	OK	11012	2026-09-18 02:06	69.96	OK
11013	2026-09-18 02:07	69.41	OK	11014	2026-09-18 02:08	67.30	OK
11015	2026-09-18 02:09	68.18	OK	11016	2026-09-18 02:10	70.11	OK
11017	2026-09-18 02:11	69.54	OK	11018	2026-09-18 02:12	70.90	OK
11019	2026-09-18 02:13	68.38	OK	11020	2026-09-18 02:14	69.90	OK
11021	2026-09-18 02:15	70.27	OK	11022	2026-09-18 02:16	71.05	OK
11023	2026-09-18 02:17	69.27	OK	11024	2026-09-18 02:18	71.14	OK
11025	2026-09-18 02:19	69.28	OK	11026	2026-09-18 02:20	71.72	OK
11027	2026-09-18 02:21	69.61	OK	11028	2026-09-18 02:22	68.61	OK
11029	2026-09-18 02:23	69.94	OK	11030	2026-09-18 02:24	69.95	OK
11031	2026-09-18 02:25	68.59	OK	11032	2026-09-18 02:26	67.40	OK
11033	2026-09-18 02:27	71.99	OK	11034	2026-09-18 02:28	67.89	OK
11035	2026-09-18 02:29	69.64	OK	11036	2026-09-18 02:30	69.68	OK
11037	2026-09-18 02:31	69.16	OK	11038	2026-09-18 02:32	69.76	OK
11039	2026-09-18 02:33	69.21	OK	11040	2026-09-18 02:34	69.92	OK
11041	2026-09-18 02:35	71.51	OK	11042	2026-09-18 02:36	68.27	OK
11043	2026-09-18 02:37	69.65	OK	11044	2026-09-18 02:38	68.71	OK
11045	2026-09-18 02:39	70.76	OK	11046	2026-09-18 02:40	68.52	OK
11047	2026-09-18 02:41	69.77	OK	11048	2026-09-18 02:42	69.46	OK
1104	2026-09-18 02:43	70.11	OK	1105	2026-09-18 02:44	71.09	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
11051	2026-09-18 02:45	66.80	OK	11052	2026-09-18 02:46	70.14	OK
11053	2026-09-18 02:47	69.28	OK	11054	2026-09-18 02:48	67.87	OK
11055	2026-09-18 02:49	70.60	OK	11056	2026-09-18 02:50	68.62	OK
11057	2026-09-18 02:51	69.02	OK	11058	2026-09-18 02:52	68.89	OK
11059	2026-09-18 02:53	67.78	OK	11060	2026-09-18 02:54	70.04	OK
11061	2026-09-18 02:55	68.24	OK	11062	2026-09-18 02:56	68.19	OK
11063	2026-09-18 02:57	69.08	OK	11064	2026-09-18 02:58	70.39	OK
11065	2026-09-18 02:59	67.99	OK	11066	2026-09-18 03:00	69.54	OK
11067	2026-09-18 03:01	68.43	OK	11068	2026-09-18 03:02	68.96	OK
11069	2026-09-18 03:03	68.68	OK	11070	2026-09-18 03:04	65.92	OK
11071	2026-09-18 03:05	68.73	OK	11072	2026-09-18 03:06	68.42	OK
11073	2026-09-18 03:07	69.12	OK	11074	2026-09-18 03:08	69.83	OK
11075	2026-09-18 03:09	68.79	OK	11076	2026-09-18 03:10	65.78	OK
11077	2026-09-18 03:11	68.62	OK	11078	2026-09-18 03:12	69.41	OK
11079	2026-09-18 03:13	68.11	OK	11080	2026-09-18 03:14	68.86	OK
11081	2026-09-18 03:15	69.10	OK	11082	2026-09-18 03:16	70.52	OK
11083	2026-09-18 03:17	68.44	OK	11084	2026-09-18 03:18	68.60	OK
11085	2026-09-18 03:19	68.89	OK	11086	2026-09-18 03:20	68.54	OK
11087	2026-09-18 03:21	67.87	OK	11088	2026-09-18 03:22	68.55	OK
11089	2026-09-18 03:23	68.28	OK	11090	2026-09-18 03:24	66.13	OK
11091	2026-09-18 03:25	67.16	OK	11092	2026-09-18 03:26	68.60	OK
11093	2026-09-18 03:27	66.46	OK	11094	2026-09-18 03:28	66.15	OK
11095	2026-09-18 03:29	68.27	OK	11096	2026-09-18 03:30	66.30	OK
11097	2026-09-18 03:31	70.07	OK	11098	2026-09-18 03:32	69.34	OK
11099	2026-09-18 03:33	69.23	OK	11100	2026-09-18 03:34	66.57	OK
11101	2026-09-18 03:35	67.33	OK	11102	2026-09-18 03:36	68.44	OK
11103	2026-09-18 03:37	67.01	OK	11104	2026-09-18 03:38	66.98	OK
11105	2026-09-18 03:39	67.03	OK	11106	2026-09-18 03:40	66.49	OK
11107	2026-09-18 03:41	68.17	OK	11108	2026-09-18 03:42	66.94	OK
1110	2026-09-18 03:43	66.68	OK	1111	2026-09-18 03:44	65.57	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
11111	2026-09-18 03:45	67.50	OK	11112	2026-09-18 03:46	66.01	OK
11113	2026-09-18 03:47	68.33	OK	11114	2026-09-18 03:48	67.80	OK
11115	2026-09-18 03:49	67.06	OK	11116	2026-09-18 03:50	67.11	OK
11117	2026-09-18 03:51	68.52	OK	11118	2026-09-18 03:52	67.71	OK
11119	2026-09-18 03:53	67.26	OK	11120	2026-09-18 03:54	68.22	OK
11121	2026-09-18 03:55	68.03	OK	11122	2026-09-18 03:56	67.54	OK
11123	2026-09-18 03:57	66.33	OK	11124	2026-09-18 03:58	67.30	OK
11125	2026-09-18 03:59	64.71	OK	11126	2026-09-18 04:00	66.70	OK
11127	2026-09-18 04:01	67.02	OK	11128	2026-09-18 04:02	66.30	OK
11129	2026-09-18 04:03	69.25	OK	11130	2026-09-18 04:04	68.08	OK
11131	2026-09-18 04:05	66.40	OK	11132	2026-09-18 04:06	66.54	OK
11133	2026-09-18 04:07	68.70	OK	11134	2026-09-18 04:08	68.60	OK
11135	2026-09-18 04:09	69.44	OK	11136	2026-09-18 04:10	67.10	OK
11137	2026-09-18 04:11	66.23	OK	11138	2026-09-18 04:12	66.45	OK
11139	2026-09-18 04:13	68.67	OK	11140	2026-09-18 04:14	68.48	OK
11141	2026-09-18 04:15	67.12	OK	11142	2026-09-18 04:16	68.80	OK
11143	2026-09-18 04:17	65.41	OK	11144	2026-09-18 04:18	67.55	OK
11145	2026-09-18 04:19	64.45	OK	11146	2026-09-18 04:20	65.71	OK
11147	2026-09-18 04:21	64.66	OK	11148	2026-09-18 04:22	64.02	OK
11149	2026-09-18 04:23	63.29	OK	11150	2026-09-18 04:24	67.70	OK
11151	2026-09-18 04:25	65.42	OK	11152	2026-09-18 04:26	65.04	OK
11153	2026-09-18 04:27	66.73	OK	11154	2026-09-18 04:28	68.68	OK
11155	2026-09-18 04:29	64.67	OK	11156	2026-09-18 04:30	64.77	OK
11157	2026-09-18 04:31	66.35	OK	11158	2026-09-18 04:32	67.49	OK
11159	2026-09-18 04:33	67.05	OK	11160	2026-09-18 04:34	68.28	OK
11161	2026-09-18 04:35	65.39	OK	11162	2026-09-18 04:36	67.03	OK
11163	2026-09-18 04:37	68.31	OK	11164	2026-09-18 04:38	66.83	OK
11165	2026-09-18 04:39	68.51	OK	11166	2026-09-18 04:40	65.83	OK
11167	2026-09-18 04:41	64.43	OK	11168	2026-09-18 04:42	65.16	OK
11169	2026-09-18 04:43	64.47	OK	11170	2026-09-18 04:44	67.05	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
11171	2026-09-18 04:45	66.18	OK	11172	2026-09-18 04:46	67.06	OK
11173	2026-09-18 04:47	66.46	OK	11174	2026-09-18 04:48	65.53	OK
11175	2026-09-18 04:49	65.73	OK	11176	2026-09-18 04:50	67.69	OK
11177	2026-09-18 04:51	65.39	OK	11178	2026-09-18 04:52	65.03	OK
11179	2026-09-18 04:53	63.96	OK	11180	2026-09-18 04:54	64.43	OK
11181	2026-09-18 04:55	63.69	OK	11182	2026-09-18 04:56	65.85	OK
11183	2026-09-18 04:57	67.25	OK	11184	2026-09-18 04:58	65.08	OK
11185	2026-09-18 04:59	65.96	OK	11186	2026-09-18 05:00	67.10	OK
11187	2026-09-18 05:01	65.00	OK	11188	2026-09-18 05:02	65.45	OK
11189	2026-09-18 05:03	65.51	OK	11190	2026-09-18 05:04	66.06	OK
11191	2026-09-18 05:05	65.19	OK	11192	2026-09-18 05:06	63.34	OK
11193	2026-09-18 05:07	65.39	OK	11194	2026-09-18 05:08	66.95	OK
11195	2026-09-18 05:09	64.02	OK	11196	2026-09-18 05:10	66.14	OK
11197	2026-09-18 05:11	64.14	OK	11198	2026-09-18 05:12	67.71	OK
11199	2026-09-18 05:13	66.49	OK	11200	2026-09-18 05:14	66.05	OK
11201	2026-09-18 05:15	63.99	OK	11202	2026-09-18 05:16	65.69	OK
11203	2026-09-18 05:17	64.50	OK	11204	2026-09-18 05:18	64.03	OK
11205	2026-09-18 05:19	65.99	OK	11206	2026-09-18 05:20	62.71	OK
11207	2026-09-18 05:21	65.32	OK	11208	2026-09-18 05:22	64.11	OK
11209	2026-09-18 05:23	63.59	OK	11210	2026-09-18 05:24	64.47	OK
11211	2026-09-18 05:25	62.56	OK	11212	2026-09-18 05:26	64.51	OK
11213	2026-09-18 05:27	64.69	OK	11214	2026-09-18 05:28	65.28	OK
11215	2026-09-18 05:29	64.11	OK	11216	2026-09-18 05:30	66.34	OK
11217	2026-09-18 05:31	62.80	OK	11218	2026-09-18 05:32	65.49	OK
11219	2026-09-18 05:33	62.54	OK	11220	2026-09-18 05:34	62.20	OK
11221	2026-09-18 05:35	65.07	OK	11222	2026-09-18 05:36	63.61	OK
11223	2026-09-18 05:37	68.01	OK	11224	2026-09-18 05:38	64.02	OK
11225	2026-09-18 05:39	65.82	OK	11226	2026-09-18 05:40	64.57	OK
11227	2026-09-18 05:41	64.42	OK	11228	2026-09-18 05:42	62.67	OK
11229	2026-09-18 05:43	64.98	OK	1123	2026-09-18 05:44	65.22	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
11231	2026-09-18 05:45	64.13	OK	11232	2026-09-18 05:46	63.55	OK
11233	2026-09-18 05:47	67.68	OK	11234	2026-09-18 05:48	63.47	OK
11235	2026-09-18 05:49	65.77	OK	11236	2026-09-18 05:50	63.94	OK
11237	2026-09-18 05:51	66.40	OK	11238	2026-09-18 05:52	65.30	OK
11239	2026-09-18 05:53	65.65	OK	11240	2026-09-18 05:54	64.87	OK
11241	2026-09-18 05:55	65.40	OK	11242	2026-09-18 05:56	62.89	OK
11243	2026-09-18 05:57	63.71	OK	11244	2026-09-18 05:58	65.21	OK
11245	2026-09-18 05:59	64.81	OK	11246	2026-09-18 06:00	65.40	OK
11247	2026-09-18 06:01	63.91	OK	11248	2026-09-18 06:02	65.64	OK
11249	2026-09-18 06:03	62.09	OK	11250	2026-09-18 06:04	61.91	OK
11251	2026-09-18 06:05	65.59	OK	11252	2026-09-18 06:06	61.88	OK
11253	2026-09-18 06:07	63.57	OK	11254	2026-09-18 06:08	62.31	OK
11255	2026-09-18 06:09	63.79	OK	11256	2026-09-18 06:10	65.72	OK
11257	2026-09-18 06:11	63.89	OK	11258	2026-09-18 06:12	61.98	OK
11259	2026-09-18 06:13	65.58	OK	11260	2026-09-18 06:14	64.59	OK
11261	2026-09-18 06:15	64.72	OK	11262	2026-09-18 06:16	61.38	OK
11263	2026-09-18 06:17	62.87	OK	11264	2026-09-18 06:18	65.02	OK
11265	2026-09-18 06:19	64.63	OK	11266	2026-09-18 06:20	63.64	OK
11267	2026-09-18 06:21	60.09	OK	11268	2026-09-18 06:22	64.46	OK
11269	2026-09-18 06:23	62.88	OK	11270	2026-09-18 06:24	60.55	OK
11271	2026-09-18 06:25	63.19	OK	11272	2026-09-18 06:26	62.50	OK
11273	2026-09-18 06:27	62.74	OK	11274	2026-09-18 06:28	61.36	OK
11275	2026-09-18 06:29	64.62	OK	11276	2026-09-18 06:30	64.49	OK
11277	2026-09-18 06:31	62.09	OK	11278	2026-09-18 06:32	61.67	OK
11279	2026-09-18 06:33	61.94	OK	11280	2026-09-18 06:34	62.07	OK
11281	2026-09-18 06:35	63.90	OK	11282	2026-09-18 06:36	64.40	OK
11283	2026-09-18 06:37	64.02	OK	11284	2026-09-18 06:38	62.68	OK
11285	2026-09-18 06:39	63.82	OK	11286	2026-09-18 06:40	61.91	OK
11287	2026-09-18 06:41	64.12	OK	11288	2026-09-18 06:42	61.75	OK
1128	2026-09-18 06:43	65.18	OK	1129	2026-09-18 06:44	63.26	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
11291	2026-09-18 06:45	64.15	OK	11292	2026-09-18 06:46	64.69	OK
11293	2026-09-18 06:47	62.69	OK	11294	2026-09-18 06:48	61.25	OK
11295	2026-09-18 06:49	62.17	OK	11296	2026-09-18 06:50	60.83	OK
11297	2026-09-18 06:51	62.44	OK	11298	2026-09-18 06:52	61.19	OK
11299	2026-09-18 06:53	61.96	OK	11300	2026-09-18 06:54	61.60	OK
11301	2026-09-18 06:55	61.51	OK	11302	2026-09-18 06:56	63.23	OK
11303	2026-09-18 06:57	61.44	OK	11304	2026-09-18 06:58	63.73	OK
11305	2026-09-18 06:59	63.84	OK	11306	2026-09-18 07:00	60.95	OK
11307	2026-09-18 07:01	64.22	OK	11308	2026-09-18 07:02	60.50	OK
11309	2026-09-18 07:03	61.04	OK	11310	2026-09-18 07:04	61.79	OK
11311	2026-09-18 07:05	63.37	OK	11312	2026-09-18 07:06	61.81	OK
11313	2026-09-18 07:07	64.76	OK	11314	2026-09-18 07:08	62.04	OK
11315	2026-09-18 07:09	59.37	OK	11316	2026-09-18 07:10	61.64	OK
11317	2026-09-18 07:11	61.49	OK	11318	2026-09-18 07:12	62.18	OK
11319	2026-09-18 07:13	63.26	OK	11320	2026-09-18 07:14	61.78	OK
11321	2026-09-18 07:15	64.46	OK	11322	2026-09-18 07:16	62.46	OK
11323	2026-09-18 07:17	60.40	OK	11324	2026-09-18 07:18	60.19	OK
11325	2026-09-18 07:19	61.66	OK	11326	2026-09-18 07:20	62.32	OK
11327	2026-09-18 07:21	63.25	OK	11328	2026-09-18 07:22	62.13	OK
11329	2026-09-18 07:23	60.03	OK	11330	2026-09-18 07:24	61.74	OK
11331	2026-09-18 07:25	62.54	OK	11332	2026-09-18 07:26	62.17	OK
11333	2026-09-18 07:27	62.29	OK	11334	2026-09-18 07:28	61.23	OK
11335	2026-09-18 07:29	60.76	OK	11336	2026-09-18 07:30	61.74	OK
11337	2026-09-18 07:31	60.98	OK	11338	2026-09-18 07:32	63.89	OK
11339	2026-09-18 07:33	62.21	OK	11340	2026-09-18 07:34	63.04	OK
11341	2026-09-18 07:35	63.29	OK	11342	2026-09-18 07:36	62.23	OK
11343	2026-09-18 07:37	60.29	OK	11344	2026-09-18 07:38	60.06	OK
11345	2026-09-18 07:39	63.32	OK	11346	2026-09-18 07:40	62.39	OK
11347	2026-09-18 07:41	62.02	OK	11348	2026-09-18 07:42	60.89	OK
1134	2026-09-18 07:43	61.19	OK	1135	2026-09-18 07:44	60.95	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
11351	2026-09-18 07:45	61.26	OK	11352	2026-09-18 07:46	61.68	OK
11353	2026-09-18 07:47	59.49	OK	11354	2026-09-18 07:48	61.61	OK
11355	2026-09-18 07:49	60.39	OK	11356	2026-09-18 07:50	59.34	OK
11357	2026-09-18 07:51	60.94	OK	11358	2026-09-18 07:52	58.86	OK
11359	2026-09-18 07:53	59.27	OK	11360	2026-09-18 07:54	63.11	OK
11361	2026-09-18 07:55	62.44	OK	11362	2026-09-18 07:56	61.65	OK
11363	2026-09-18 07:57	60.62	OK	11364	2026-09-18 07:58	62.21	OK
11365	2026-09-18 07:59	61.15	OK	11366	2026-09-18 08:00	60.76	OK
11367	2026-09-18 08:01	60.93	OK	11368	2026-09-18 08:02	60.89	OK
11369	2026-09-18 08:03	62.48	OK	11370	2026-09-18 08:04	59.33	OK
11371	2026-09-18 08:05	58.61	OK	11372	2026-09-18 08:06	60.00	OK
11373	2026-09-18 08:07	63.15	OK	11374	2026-09-18 08:08	61.95	OK
11375	2026-09-18 08:09	59.87	OK	11376	2026-09-18 08:10	58.27	OK
11377	2026-09-18 08:11	62.35	OK	11378	2026-09-18 08:12	61.43	OK
11379	2026-09-18 08:13	59.61	OK	11380	2026-09-18 08:14	62.13	OK
11381	2026-09-18 08:15	61.22	OK	11382	2026-09-18 08:16	60.23	OK
11383	2026-09-18 08:17	62.46	OK	11384	2026-09-18 08:18	62.99	OK
11385	2026-09-18 08:19	57.46	OK	11386	2026-09-18 08:20	62.01	OK
11387	2026-09-18 08:21	61.00	OK	11388	2026-09-18 08:22	60.35	OK
11389	2026-09-18 08:23	57.85	OK	11390	2026-09-18 08:24	62.97	OK
11391	2026-09-18 08:25	59.76	OK	11392	2026-09-18 08:26	60.97	OK
11393	2026-09-18 08:27	59.74	OK	11394	2026-09-18 08:28	60.26	OK
11395	2026-09-18 08:29	61.64	OK	11396	2026-09-18 08:30	62.08	OK
11397	2026-09-18 08:31	59.27	OK	11398	2026-09-18 08:32	61.02	OK
11399	2026-09-18 08:33	61.01	OK	11400	2026-09-18 08:34	58.70	OK
11401	2026-09-18 08:35	61.99	OK	11402	2026-09-18 08:36	60.86	OK
11403	2026-09-18 08:37	60.44	OK	11404	2026-09-18 08:38	59.03	OK
11405	2026-09-18 08:39	60.09	OK	11406	2026-09-18 08:40	61.83	OK
11407	2026-09-18 08:41	61.65	OK	11408	2026-09-18 08:42	60.03	OK
1140	2026-09-18 08:43	59.85	OK	1141	2026-09-18 08:44	61.10	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
11411	2026-09-18 08:45	60.21	OK	11412	2026-09-18 08:46	62.93	OK
11413	2026-09-18 08:47	62.46	OK	11414	2026-09-18 08:48	60.08	OK
11415	2026-09-18 08:49	59.59	OK	11416	2026-09-18 08:50	59.37	OK
11417	2026-09-18 08:51	61.87	OK	11418	2026-09-18 08:52	60.61	OK
11419	2026-09-18 08:53	60.33	OK	11420	2026-09-18 08:54	59.97	OK
11421	2026-09-18 08:55	59.35	OK	11422	2026-09-18 08:56	57.13	OK
11423	2026-09-18 08:57	58.87	OK	11424	2026-09-18 08:58	61.32	OK
11425	2026-09-18 08:59	59.87	OK	11426	2026-09-18 09:00	62.87	OK
11427	2026-09-18 09:01	60.05	OK	11428	2026-09-18 09:02	59.58	OK
11429	2026-09-18 09:03	60.96	OK	11430	2026-09-18 09:04	58.22	OK
11431	2026-09-18 09:05	60.18	OK	11432	2026-09-18 09:06	60.28	OK
11433	2026-09-18 09:07	58.28	OK	11434	2026-09-18 09:08	61.84	OK
11435	2026-09-18 09:09	59.86	OK	11436	2026-09-18 09:10	58.80	OK
11437	2026-09-18 09:11	62.09	OK	11438	2026-09-18 09:12	61.03	OK
11439	2026-09-18 09:13	62.73	OK	11440	2026-09-18 09:14	60.84	OK
11441	2026-09-18 09:15	60.52	OK	11442	2026-09-18 09:16	59.31	OK
11443	2026-09-18 09:17	60.07	OK	11444	2026-09-18 09:18	59.84	OK
11445	2026-09-18 09:19	60.38	OK	11446	2026-09-18 09:20	59.69	OK
11447	2026-09-18 09:21	61.44	OK	11448	2026-09-18 09:22	60.70	OK
11449	2026-09-18 09:23	60.50	OK	11450	2026-09-18 09:24	59.58	OK
11451	2026-09-18 09:25	60.11	OK	11452	2026-09-18 09:26	59.29	OK
11453	2026-09-18 09:27	60.78	OK	11454	2026-09-18 09:28	60.22	OK
11455	2026-09-18 09:29	59.43	OK	11456	2026-09-18 09:30	59.06	OK
11457	2026-09-18 09:31	60.74	OK	11458	2026-09-18 09:32	60.56	OK
11459	2026-09-18 09:33	60.76	OK	11460	2026-09-18 09:34	58.24	OK
11461	2026-09-18 09:35	60.23	OK	11462	2026-09-18 09:36	62.42	OK
11463	2026-09-18 09:37	59.16	OK	11464	2026-09-18 09:38	59.53	OK
11465	2026-09-18 09:39	60.43	OK	11466	2026-09-18 09:40	59.39	OK
11467	2026-09-18 09:41	60.16	OK	11468	2026-09-18 09:42	61.05	OK
11469	2026-09-18 09:43	58.70	OK	11470	2026-09-18 09:44	58.51	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
11471	2026-09-18 09:45	59.50	OK	11472	2026-09-18 09:46	59.98	OK
11473	2026-09-18 09:47	62.67	OK	11474	2026-09-18 09:48	60.11	OK
11475	2026-09-18 09:49	58.71	OK	11476	2026-09-18 09:50	58.99	OK
11477	2026-09-18 09:51	57.31	OK	11478	2026-09-18 09:52	59.62	OK
11479	2026-09-18 09:53	60.50	OK	11480	2026-09-18 09:54	62.41	OK
11481	2026-09-18 09:55	60.43	OK	11482	2026-09-18 09:56	59.18	OK
11483	2026-09-18 09:57	61.72	OK	11484	2026-09-18 09:58	59.04	OK
11485	2026-09-18 09:59	58.75	OK	11486	2026-09-18 10:00	62.04	OK
11487	2026-09-18 10:01	57.90	OK	11488	2026-09-18 10:02	60.72	OK
11489	2026-09-18 10:03	60.52	OK	11490	2026-09-18 10:04	59.48	OK
11491	2026-09-18 10:05	59.71	OK	11492	2026-09-18 10:06	58.45	OK
11493	2026-09-18 10:07	61.43	OK	11494	2026-09-18 10:08	58.77	OK
11495	2026-09-18 10:09	59.67	OK	11496	2026-09-18 10:10	60.08	OK
11497	2026-09-18 10:11	61.22	OK	11498	2026-09-18 10:12	59.26	OK
11499	2026-09-18 10:13	57.64	OK	11500	2026-09-18 10:14	60.42	OK
11501	2026-09-18 10:15	59.86	OK	11502	2026-09-18 10:16	59.05	OK
11503	2026-09-18 10:17	60.29	OK	11504	2026-09-18 10:18	60.21	OK
11505	2026-09-18 10:19	59.03	OK	11506	2026-09-18 10:20	59.48	OK
11507	2026-09-18 10:21	61.04	OK	11508	2026-09-18 10:22	59.65	OK
11509	2026-09-18 10:23	56.98	OK	11510	2026-09-18 10:24	60.20	OK
11511	2026-09-18 10:25	58.76	OK	11512	2026-09-18 10:26	61.49	OK
11513	2026-09-18 10:27	59.26	OK	11514	2026-09-18 10:28	58.67	OK
11515	2026-09-18 10:29	59.19	OK	11516	2026-09-18 10:30	57.74	OK
11517	2026-09-18 10:31	60.71	OK	11518	2026-09-18 10:32	60.42	OK
11519	2026-09-18 10:33	57.48	OK	11520	2026-09-18 10:34	61.14	OK
11521	2026-09-18 10:35	58.33	OK	11522	2026-09-18 10:36	58.03	OK
11523	2026-09-18 10:37	58.92	OK	11524	2026-09-18 10:38	59.72	OK
11525	2026-09-18 10:39	59.74	OK	11526	2026-09-18 10:40	61.63	OK
11527	2026-09-18 10:41	60.11	OK	11528	2026-09-18 10:42	62.17	OK
1152	2026-09-18 10:43	59.49	OK	1153	2026-09-18 10:44	59.47	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
11531	2026-09-18 10:45	60.57	OK	11532	2026-09-18 10:46	60.13	OK
11533	2026-09-18 10:47	57.83	OK	11534	2026-09-18 10:48	59.73	OK
11535	2026-09-18 10:49	58.47	OK	11536	2026-09-18 10:50	62.15	OK
11537	2026-09-18 10:51	59.73	OK	11538	2026-09-18 10:52	60.07	OK
11539	2026-09-18 10:53	60.64	OK	11540	2026-09-18 10:54	57.51	OK
11541	2026-09-18 10:55	60.46	OK	11542	2026-09-18 10:56	59.57	OK
11543	2026-09-18 10:57	60.08	OK	11544	2026-09-18 10:58	58.89	OK
11545	2026-09-18 10:59	59.96	OK	11546	2026-09-18 11:00	60.26	OK
11547	2026-09-18 11:01	58.27	OK	11548	2026-09-18 11:02	60.25	OK
11549	2026-09-18 11:03	61.25	OK	11550	2026-09-18 11:04	61.56	OK
11551	2026-09-18 11:05	59.61	OK	11552	2026-09-18 11:06	60.33	OK
11553	2026-09-18 11:07	59.94	OK	11554	2026-09-18 11:08	60.49	OK
11555	2026-09-18 11:09	58.77	OK	11556	2026-09-18 11:10	58.36	OK
11557	2026-09-18 11:11	59.03	OK	11558	2026-09-18 11:12	57.39	OK
11559	2026-09-18 11:13	59.87	OK	11560	2026-09-18 11:14	59.00	OK
11561	2026-09-18 11:15	59.97	OK	11562	2026-09-18 11:16	57.91	OK
11563	2026-09-18 11:17	59.46	OK	11564	2026-09-18 11:18	59.87	OK
11565	2026-09-18 11:19	58.82	OK	11566	2026-09-18 11:20	59.01	OK
11567	2026-09-18 11:21	59.13	OK	11568	2026-09-18 11:22	61.66	OK
11569	2026-09-18 11:23	59.05	OK	11570	2026-09-18 11:24	59.95	OK
11571	2026-09-18 11:25	59.50	OK	11572	2026-09-18 11:26	59.33	OK
11573	2026-09-18 11:27	62.09	OK	11574	2026-09-18 11:28	59.54	OK
11575	2026-09-18 11:29	60.66	OK	11576	2026-09-18 11:30	59.62	OK
11577	2026-09-18 11:31	57.37	OK	11578	2026-09-18 11:32	59.77	OK
11579	2026-09-18 11:33	58.67	OK	11580	2026-09-18 11:34	59.13	OK
11581	2026-09-18 11:35	59.94	OK	11582	2026-09-18 11:36	58.85	OK
11583	2026-09-18 11:37	59.22	OK	11584	2026-09-18 11:38	62.56	OK
11585	2026-09-18 11:39	61.41	OK	11586	2026-09-18 11:40	59.48	OK
11587	2026-09-18 11:41	59.83	OK	11588	2026-09-18 11:42	58.98	OK
1158	2026-09-18 11:43	60.91	OK	1159	2026-09-18 11:44	59.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
11591	2026-09-18 11:45	60.60	OK	11592	2026-09-18 11:46	60.57	OK
11593	2026-09-18 11:47	58.45	OK	11594	2026-09-18 11:48	61.04	OK
11595	2026-09-18 11:49	60.13	OK	11596	2026-09-18 11:50	58.01	OK
11597	2026-09-18 11:51	60.86	OK	11598	2026-09-18 11:52	58.44	OK
11599	2026-09-18 11:53	60.47	OK	11600	2026-09-18 11:54	59.72	OK
11601	2026-09-18 11:55	58.66	OK	11602	2026-09-18 11:56	59.19	OK
11603	2026-09-18 11:57	61.23	OK	11604	2026-09-18 11:58	62.23	OK
11605	2026-09-18 11:59	59.78	OK	11606	2026-09-18 12:00	60.45	OK
11607	2026-09-18 12:01	59.88	OK	11608	2026-09-18 12:02	60.66	OK
11609	2026-09-18 12:03	59.33	OK	11610	2026-09-18 12:04	60.56	OK
11611	2026-09-18 12:05	60.05	OK	11612	2026-09-18 12:06	58.43	OK
11613	2026-09-18 12:07	58.42	OK	11614	2026-09-18 12:08	61.46	OK
11615	2026-09-18 12:09	60.14	OK	11616	2026-09-18 12:10	61.03	OK
11617	2026-09-18 12:11	60.07	OK	11618	2026-09-18 12:12	57.89	OK
11619	2026-09-18 12:13	60.44	OK	11620	2026-09-18 12:14	57.83	OK
11621	2026-09-18 12:15	60.42	OK	11622	2026-09-18 12:16	62.39	OK
11623	2026-09-18 12:17	59.08	OK	11624	2026-09-18 12:18	60.10	OK
11625	2026-09-18 12:19	61.21	OK	11626	2026-09-18 12:20	60.48	OK
11627	2026-09-18 12:21	61.92	OK	11628	2026-09-18 12:22	59.77	OK
11629	2026-09-18 12:23	61.19	OK	11630	2026-09-18 12:24	60.44	OK
11631	2026-09-18 12:25	60.06	OK	11632	2026-09-18 12:26	61.37	OK
11633	2026-09-18 12:27	60.80	OK	11634	2026-09-18 12:28	60.90	OK
11635	2026-09-18 12:29	58.09	OK	11636	2026-09-18 12:30	62.43	OK
11637	2026-09-18 12:31	58.06	OK	11638	2026-09-18 12:32	60.91	OK
11639	2026-09-18 12:33	58.57	OK	11640	2026-09-18 12:34	59.93	OK
11641	2026-09-18 12:35	61.10	OK	11642	2026-09-18 12:36	62.72	OK
11643	2026-09-18 12:37	59.99	OK	11644	2026-09-18 12:38	59.72	OK
11645	2026-09-18 12:39	59.43	OK	11646	2026-09-18 12:40	62.50	OK
11647	2026-09-18 12:41	61.29	OK	11648	2026-09-18 12:42	60.22	OK
1164	2026-09-18 12:43	61.17	OK	1165	2026-09-18 12:44	58.57	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
11651	2026-09-18 12:45	60.07	OK	11652	2026-09-18 12:46	59.91	OK
11653	2026-09-18 12:47	60.26	OK	11654	2026-09-18 12:48	59.95	OK
11655	2026-09-18 12:49	60.13	OK	11656	2026-09-18 12:50	63.00	OK
11657	2026-09-18 12:51	59.77	OK	11658	2026-09-18 12:52	59.38	OK
11659	2026-09-18 12:53	60.89	OK	11660	2026-09-18 12:54	61.80	OK
11661	2026-09-18 12:55	59.84	OK	11662	2026-09-18 12:56	60.43	OK
11663	2026-09-18 12:57	59.00	OK	11664	2026-09-18 12:58	59.21	OK
11665	2026-09-18 12:59	60.13	OK	11666	2026-09-18 13:00	60.73	OK
11667	2026-09-18 13:01	61.60	OK	11668	2026-09-18 13:02	59.16	OK
11669	2026-09-18 13:03	59.49	OK	11670	2026-09-18 13:04	60.29	OK
11671	2026-09-18 13:05	59.85	OK	11672	2026-09-18 13:06	58.95	OK
11673	2026-09-18 13:07	62.80	OK	11674	2026-09-18 13:08	60.62	OK
11675	2026-09-18 13:09	61.56	OK	11676	2026-09-18 13:10	61.72	OK
11677	2026-09-18 13:11	61.63	OK	11678	2026-09-18 13:12	62.07	OK
11679	2026-09-18 13:13	59.60	OK	11680	2026-09-18 13:14	59.87	OK
11681	2026-09-18 13:15	61.03	OK	11682	2026-09-18 13:16	60.33	OK
11683	2026-09-18 13:17	62.29	OK	11684	2026-09-18 13:18	61.27	OK
11685	2026-09-18 13:19	62.20	OK	11686	2026-09-18 13:20	60.34	OK
11687	2026-09-18 13:21	58.56	OK	11688	2026-09-18 13:22	62.04	OK
11689	2026-09-18 13:23	61.23	OK	11690	2026-09-18 13:24	62.72	OK
11691	2026-09-18 13:25	60.98	OK	11692	2026-09-18 13:26	60.78	OK
11693	2026-09-18 13:27	62.93	OK	11694	2026-09-18 13:28	62.85	OK
11695	2026-09-18 13:29	58.43	OK	11696	2026-09-18 13:30	61.43	OK
11697	2026-09-18 13:31	60.87	OK	11698	2026-09-18 13:32	63.00	OK
11699	2026-09-18 13:33	63.82	OK	11700	2026-09-18 13:34	61.92	OK
11701	2026-09-18 13:35	61.00	OK	11702	2026-09-18 13:36	61.76	OK
11703	2026-09-18 13:37	61.54	OK	11704	2026-09-18 13:38	60.70	OK
11705	2026-09-18 13:39	60.25	OK	11706	2026-09-18 13:40	60.17	OK
11707	2026-09-18 13:41	61.85	OK	11708	2026-09-18 13:42	61.57	OK
1170	2026-09-18 13:43	60.44	OK	1171	2026-09-18 13:44	61.62	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
11711	2026-09-18 13:45	58.79	OK	11712	2026-09-18 13:46	62.01	OK
11713	2026-09-18 13:47	59.46	OK	11714	2026-09-18 13:48	62.78	OK
11715	2026-09-18 13:49	59.39	OK	11716	2026-09-18 13:50	62.04	OK
11717	2026-09-18 13:51	63.54	OK	11718	2026-09-18 13:52	61.76	OK
11719	2026-09-18 13:53	60.65	OK	11720	2026-09-18 13:54	61.76	OK
11721	2026-09-18 13:55	59.87	OK	11722	2026-09-18 13:56	60.57	OK
11723	2026-09-18 13:57	62.03	OK	11724	2026-09-18 13:58	62.27	OK
11725	2026-09-18 13:59	59.21	OK	11726	2026-09-18 14:00	62.32	OK
11727	2026-09-18 14:01	62.64	OK	11728	2026-09-18 14:02	59.66	OK
11729	2026-09-18 14:03	61.42	OK	11730	2026-09-18 14:04	61.55	OK
11731	2026-09-18 14:05	58.91	OK	11732	2026-09-18 14:06	61.59	OK
11733	2026-09-18 14:07	61.48	OK	11734	2026-09-18 14:08	61.09	OK
11735	2026-09-18 14:09	62.61	OK	11736	2026-09-18 14:10	62.70	OK
11737	2026-09-18 14:11	61.92	OK	11738	2026-09-18 14:12	62.20	OK
11739	2026-09-18 14:13	63.96	OK	11740	2026-09-18 14:14	62.60	OK
11741	2026-09-18 14:15	60.74	OK	11742	2026-09-18 14:16	61.45	OK
11743	2026-09-18 14:17	62.13	OK	11744	2026-09-18 14:18	63.01	OK
11745	2026-09-18 14:19	63.18	OK	11746	2026-09-18 14:20	62.26	OK
11747	2026-09-18 14:21	61.99	OK	11748	2026-09-18 14:22	60.87	OK
11749	2026-09-18 14:23	60.09	OK	11750	2026-09-18 14:24	61.53	OK
11751	2026-09-18 14:25	63.34	OK	11752	2026-09-18 14:26	62.93	OK
11753	2026-09-18 14:27	64.07	OK	11754	2026-09-18 14:28	62.18	OK
11755	2026-09-18 14:29	61.54	OK	11756	2026-09-18 14:30	63.63	OK
11757	2026-09-18 14:31	60.32	OK	11758	2026-09-18 14:32	62.98	OK
11759	2026-09-18 14:33	63.37	OK	11760	2026-09-18 14:34	64.68	OK
11761	2026-09-18 14:35	62.21	OK	11762	2026-09-18 14:36	62.07	OK
11763	2026-09-18 14:37	60.74	OK	11764	2026-09-18 14:38	62.19	OK
11765	2026-09-18 14:39	64.87	OK	11766	2026-09-18 14:40	62.42	OK
11767	2026-09-18 14:41	61.45	OK	11768	2026-09-18 14:42	62.48	OK
1176	2026-09-18 14:43	62.92	OK	1177	2026-09-18 14:44	64.44	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
11771	2026-09-18 14:45	63.78	OK	11772	2026-09-18 14:46	61.22	OK
11773	2026-09-18 14:47	60.80	OK	11774	2026-09-18 14:48	62.00	OK
11775	2026-09-18 14:49	64.57	OK	11776	2026-09-18 14:50	64.11	OK
11777	2026-09-18 14:51	64.09	OK	11778	2026-09-18 14:52	64.33	OK
11779	2026-09-18 14:53	64.88	OK	11780	2026-09-18 14:54	62.86	OK
11781	2026-09-18 14:55	61.20	OK	11782	2026-09-18 14:56	62.63	OK
11783	2026-09-18 14:57	61.43	OK	11784	2026-09-18 14:58	62.77	OK
11785	2026-09-18 14:59	62.00	OK	11786	2026-09-18 15:00	62.13	OK
11787	2026-09-18 15:01	63.81	OK	11788	2026-09-18 15:02	64.24	OK
11789	2026-09-18 15:03	63.11	OK	11790	2026-09-18 15:04	65.25	OK
11791	2026-09-18 15:05	61.81	OK	11792	2026-09-18 15:06	64.55	OK
11793	2026-09-18 15:07	63.68	OK	11794	2026-09-18 15:08	64.90	OK
11795	2026-09-18 15:09	61.72	OK	11796	2026-09-18 15:10	63.15	OK
11797	2026-09-18 15:11	65.15	OK	11798	2026-09-18 15:12	65.04	OK
11799	2026-09-18 15:13	63.32	OK	11800	2026-09-18 15:14	66.22	OK
11801	2026-09-18 15:15	63.05	OK	11802	2026-09-18 15:16	64.32	OK
11803	2026-09-18 15:17	65.41	OK	11804	2026-09-18 15:18	62.85	OK
11805	2026-09-18 15:19	65.00	OK	11806	2026-09-18 15:20	62.24	OK
11807	2026-09-18 15:21	65.81	OK	11808	2026-09-18 15:22	61.08	OK
11809	2026-09-18 15:23	64.23	OK	11810	2026-09-18 15:24	64.13	OK
11811	2026-09-18 15:25	64.03	OK	11812	2026-09-18 15:26	62.73	OK
11813	2026-09-18 15:27	63.40	OK	11814	2026-09-18 15:28	64.20	OK
11815	2026-09-18 15:29	61.36	OK	11816	2026-09-18 15:30	64.82	OK
11817	2026-09-18 15:31	65.61	OK	11818	2026-09-18 15:32	64.94	OK
11819	2026-09-18 15:33	64.01	OK	11820	2026-09-18 15:34	63.84	OK
11821	2026-09-18 15:35	65.16	OK	11822	2026-09-18 15:36	62.62	OK
11823	2026-09-18 15:37	64.40	OK	11824	2026-09-18 15:38	64.74	OK
11825	2026-09-18 15:39	65.20	OK	11826	2026-09-18 15:40	63.65	OK
11827	2026-09-18 15:41	64.80	OK	11828	2026-09-18 15:42	65.57	OK
1182	2026-09-18 15:43	62.36	OK	1183	2026-09-18 15:44	62.67	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
11831	2026-09-18 15:45	63.98	OK	11832	2026-09-18 15:46	64.85	OK
11833	2026-09-18 15:47	65.64	OK	11834	2026-09-18 15:48	64.67	OK
11835	2026-09-18 15:49	65.45	OK	11836	2026-09-18 15:50	66.98	OK
11837	2026-09-18 15:51	64.12	OK	11838	2026-09-18 15:52	65.39	OK
11839	2026-09-18 15:53	63.78	OK	11840	2026-09-18 15:54	66.60	OK
11841	2026-09-18 15:55	67.30	OK	11842	2026-09-18 15:56	62.98	OK
11843	2026-09-18 15:57	64.11	OK	11844	2026-09-18 15:58	62.80	OK
11845	2026-09-18 15:59	65.62	OK	11846	2026-09-18 16:00	64.27	OK
11847	2026-09-18 16:01	64.20	OK	11848	2026-09-18 16:02	65.76	OK
11849	2026-09-18 16:03	65.53	OK	11850	2026-09-18 16:04	65.49	OK
11851	2026-09-18 16:05	65.74	OK	11852	2026-09-18 16:06	64.88	OK
11853	2026-09-18 16:07	65.32	OK	11854	2026-09-18 16:08	63.44	OK
11855	2026-09-18 16:09	64.29	OK	11856	2026-09-18 16:10	62.94	OK
11857	2026-09-18 16:11	64.52	OK	11858	2026-09-18 16:12	63.51	OK
11859	2026-09-18 16:13	63.72	OK	11860	2026-09-18 16:14	66.01	OK
11861	2026-09-18 16:15	65.16	OK	11862	2026-09-18 16:16	68.35	OK
11863	2026-09-18 16:17	64.82	OK	11864	2026-09-18 16:18	64.53	OK
11865	2026-09-18 16:19	65.25	OK	11866	2026-09-18 16:20	67.86	OK
11867	2026-09-18 16:21	64.23	OK	11868	2026-09-18 16:22	65.74	OK
11869	2026-09-18 16:23	66.15	OK	11870	2026-09-18 16:24	64.40	OK
11871	2026-09-18 16:25	66.10	OK	11872	2026-09-18 16:26	64.31	OK
11873	2026-09-18 16:27	64.64	OK	11874	2026-09-18 16:28	66.31	OK
11875	2026-09-18 16:29	66.23	OK	11876	2026-09-18 16:30	63.13	OK
11877	2026-09-18 16:31	66.61	OK	11878	2026-09-18 16:32	64.46	OK
11879	2026-09-18 16:33	65.88	OK	11880	2026-09-18 16:34	65.37	OK
11881	2026-09-18 16:35	67.82	OK	11882	2026-09-18 16:36	65.71	OK
11883	2026-09-18 16:37	66.71	OK	11884	2026-09-18 16:38	66.07	OK
11885	2026-09-18 16:39	66.06	OK	11886	2026-09-18 16:40	66.11	OK
11887	2026-09-18 16:41	67.82	OK	11888	2026-09-18 16:42	68.63	OK
1188	2026-09-18 16:43	66.71	OK	1189	2026-09-18 16:44	69.30	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
11891	2026-09-18 16:45	64.68	OK	11892	2026-09-18 16:46	65.66	OK
11893	2026-09-18 16:47	65.81	OK	11894	2026-09-18 16:48	65.75	OK
11895	2026-09-18 16:49	65.13	OK	11896	2026-09-18 16:50	66.47	OK
11897	2026-09-18 16:51	65.24	OK	11898	2026-09-18 16:52	68.05	OK
11899	2026-09-18 16:53	65.72	OK	11900	2026-09-18 16:54	64.52	OK
11901	2026-09-18 16:55	64.32	OK	11902	2026-09-18 16:56	67.71	OK
11903	2026-09-18 16:57	65.75	OK	11904	2026-09-18 16:58	67.19	OK
11905	2026-09-18 16:59	63.94	OK	11906	2026-09-18 17:00	65.62	OK
11907	2026-09-18 17:01	66.80	OK	11908	2026-09-18 17:02	67.46	OK
11909	2026-09-18 17:03	65.25	OK	11910	2026-09-18 17:04	68.25	OK
11911	2026-09-18 17:05	65.09	OK	11912	2026-09-18 17:06	65.61	OK
11913	2026-09-18 17:07	64.30	OK	11914	2026-09-18 17:08	66.08	OK
11915	2026-09-18 17:09	67.88	OK	11916	2026-09-18 17:10	67.29	OK
11917	2026-09-18 17:11	67.27	OK	11918	2026-09-18 17:12	68.59	OK
11919	2026-09-18 17:13	68.11	OK	11920	2026-09-18 17:14	66.31	OK
11921	2026-09-18 17:15	66.82	OK	11922	2026-09-18 17:16	66.60	OK
11923	2026-09-18 17:17	67.20	OK	11924	2026-09-18 17:18	68.12	OK
11925	2026-09-18 17:19	70.54	OK	11926	2026-09-18 17:20	66.25	OK
11927	2026-09-18 17:21	66.91	OK	11928	2026-09-18 17:22	66.75	OK
11929	2026-09-18 17:23	65.46	OK	11930	2026-09-18 17:24	67.57	OK
11931	2026-09-18 17:25	69.00	OK	11932	2026-09-18 17:26	65.76	OK
11933	2026-09-18 17:27	68.00	OK	11934	2026-09-18 17:28	67.25	OK
11935	2026-09-18 17:29	64.55	OK	11936	2026-09-18 17:30	69.11	OK
11937	2026-09-18 17:31	65.43	OK	11938	2026-09-18 17:32	66.79	OK
11939	2026-09-18 17:33	68.30	OK	11940	2026-09-18 17:34	66.62	OK
11941	2026-09-18 17:35	67.70	OK	11942	2026-09-18 17:36	66.94	OK
11943	2026-09-18 17:37	68.55	OK	11944	2026-09-18 17:38	68.65	OK
11945	2026-09-18 17:39	66.61	OK	11946	2026-09-18 17:40	66.50	OK
11947	2026-09-18 17:41	65.48	OK	11948	2026-09-18 17:42	67.28	OK
11949	2026-09-18 17:43	68.98	OK	11950	2026-09-18 17:44	67.56	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
11951	2026-09-18 17:45	69.00	OK	11952	2026-09-18 17:46	67.76	OK
11953	2026-09-18 17:47	68.65	OK	11954	2026-09-18 17:48	67.74	OK
11955	2026-09-18 17:49	69.07	OK	11956	2026-09-18 17:50	68.87	OK
11957	2026-09-18 17:51	66.89	OK	11958	2026-09-18 17:52	68.26	OK
11959	2026-09-18 17:53	67.46	OK	11960	2026-09-18 17:54	69.49	OK
11961	2026-09-18 17:55	68.45	OK	11962	2026-09-18 17:56	69.19	OK
11963	2026-09-18 17:57	66.82	OK	11964	2026-09-18 17:58	69.63	OK
11965	2026-09-18 17:59	67.39	OK	11966	2026-09-18 18:00	66.17	OK
11967	2026-09-18 18:01	69.90	OK	11968	2026-09-18 18:02	68.25	OK
11969	2026-09-18 18:03	69.13	OK	11970	2026-09-18 18:04	69.09	OK
11971	2026-09-18 18:05	67.36	OK	11972	2026-09-18 18:06	68.64	OK
11973	2026-09-18 18:07	67.18	OK	11974	2026-09-18 18:08	68.51	OK
11975	2026-09-18 18:09	69.43	OK	11976	2026-09-18 18:10	68.94	OK
11977	2026-09-18 18:11	70.29	OK	11978	2026-09-18 18:12	69.03	OK
11979	2026-09-18 18:13	69.27	OK	11980	2026-09-18 18:14	67.07	OK
11981	2026-09-18 18:15	68.70	OK	11982	2026-09-18 18:16	69.31	OK
11983	2026-09-18 18:17	70.28	OK	11984	2026-09-18 18:18	68.13	OK
11985	2026-09-18 18:19	70.30	OK	11986	2026-09-18 18:20	70.17	OK
11987	2026-09-18 18:21	67.96	OK	11988	2026-09-18 18:22	68.43	OK
11989	2026-09-18 18:23	68.23	OK	11990	2026-09-18 18:24	71.51	OK
11991	2026-09-18 18:25	69.99	OK	11992	2026-09-18 18:26	69.90	OK
11993	2026-09-18 18:27	69.85	OK	11994	2026-09-18 18:28	67.69	OK
11995	2026-09-18 18:29	68.53	OK	11996	2026-09-18 18:30	69.86	OK
11997	2026-09-18 18:31	68.10	OK	11998	2026-09-18 18:32	66.77	OK
11999	2026-09-18 18:33	70.22	OK	12000	2026-09-18 18:34	68.94	OK
12001	2026-09-18 18:35	69.19	OK	12002	2026-09-18 18:36	67.83	OK
12003	2026-09-18 18:37	70.10	OK	12004	2026-09-18 18:38	71.17	OK
12005	2026-09-18 18:39	70.44	OK	12006	2026-09-18 18:40	66.55	OK
12007	2026-09-18 18:41	70.20	OK	12008	2026-09-18 18:42	68.51	OK
1200	2026-09-18 18:43	68.62	OK	1201	2026-09-18 18:44	71.59	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
12011	2026-09-18 18:45	70.96	OK	12012	2026-09-18 18:46	70.62	OK
12013	2026-09-18 18:47	70.27	OK	12014	2026-09-18 18:48	67.91	OK
12015	2026-09-18 18:49	69.45	OK	12016	2026-09-18 18:50	68.35	OK
12017	2026-09-18 18:51	69.13	OK	12018	2026-09-18 18:52	69.15	OK
12019	2026-09-18 18:53	70.04	OK	12020	2026-09-18 18:54	69.10	OK
12021	2026-09-18 18:55	68.29	OK	12022	2026-09-18 18:56	67.17	OK
12023	2026-09-18 18:57	69.45	OK	12024	2026-09-18 18:58	69.13	OK
12025	2026-09-18 18:59	70.39	OK	12026	2026-09-18 19:00	70.09	OK
12027	2026-09-18 19:01	68.01	OK	12028	2026-09-18 19:02	68.48	OK
12029	2026-09-18 19:03	69.82	OK	12030	2026-09-18 19:04	68.90	OK
12031	2026-09-18 19:05	71.22	OK	12032	2026-09-18 19:06	69.98	OK
12033	2026-09-18 19:07	71.23	OK	12034	2026-09-18 19:08	68.45	OK
12035	2026-09-18 19:09	69.57	OK	12036	2026-09-18 19:10	70.53	OK
12037	2026-09-18 19:11	70.51	OK	12038	2026-09-18 19:12	69.33	OK
12039	2026-09-18 19:13	71.50	OK	12040	2026-09-18 19:14	70.81	OK
12041	2026-09-18 19:15	70.03	OK	12042	2026-09-18 19:16	71.06	OK
12043	2026-09-18 19:17	71.19	OK	12044	2026-09-18 19:18	70.19	OK
12045	2026-09-18 19:19	69.35	OK	12046	2026-09-18 19:20	70.09	OK
12047	2026-09-18 19:21	69.39	OK	12048	2026-09-18 19:22	72.41	OK
12049	2026-09-18 19:23	69.31	OK	12050	2026-09-18 19:24	70.22	OK
12051	2026-09-18 19:25	70.86	OK	12052	2026-09-18 19:26	70.09	OK
12053	2026-09-18 19:27	71.43	OK	12054	2026-09-18 19:28	71.35	OK
12055	2026-09-18 19:29	72.83	OK	12056	2026-09-18 19:30	71.16	OK
12057	2026-09-18 19:31	70.85	OK	12058	2026-09-18 19:32	70.30	OK
12059	2026-09-18 19:33	70.25	OK	12060	2026-09-18 19:34	70.51	OK
12061	2026-09-18 19:35	69.63	OK	12062	2026-09-18 19:36	72.31	OK
12063	2026-09-18 19:37	69.38	OK	12064	2026-09-18 19:38	69.19	OK
12065	2026-09-18 19:39	72.76	OK	12066	2026-09-18 19:40	70.44	OK
12067	2026-09-18 19:41	71.84	OK	12068	2026-09-18 19:42	72.42	OK
1206	2026-09-18 19:43	69.62	OK	1207	2026-09-18 19:44	69.97	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
12071	2026-09-18 19:45	69.12	OK	12072	2026-09-18 19:46	69.91	OK
12073	2026-09-18 19:47	71.63	OK	12074	2026-09-18 19:48	71.57	OK
12075	2026-09-18 19:49	69.03	OK	12076	2026-09-18 19:50	70.69	OK
12077	2026-09-18 19:51	72.86	OK	12078	2026-09-18 19:52	69.39	OK
12079	2026-09-18 19:53	71.84	OK	12080	2026-09-18 19:54	71.50	OK
12081	2026-09-18 19:55	71.73	OK	12082	2026-09-18 19:56	67.73	OK
12083	2026-09-18 19:57	71.51	OK	12084	2026-09-18 19:58	71.96	OK
12085	2026-09-18 19:59	71.82	OK	12086	2026-09-18 20:00	72.25	OK
12087	2026-09-18 20:01	70.33	OK	12088	2026-09-18 20:02	68.74	OK
12089	2026-09-18 20:03	68.37	OK	12090	2026-09-18 20:04	69.62	OK
12091	2026-09-18 20:05	71.40	OK	12092	2026-09-18 20:06	71.57	OK
12093	2026-09-18 20:07	71.70	OK	12094	2026-09-18 20:08	72.77	OK
12095	2026-09-18 20:09	73.78	OK	12096	2026-09-18 20:10	70.45	OK
12097	2026-09-18 20:11	70.65	OK	12098	2026-09-18 20:12	70.55	OK
12099	2026-09-18 20:13	73.13	OK	12100	2026-09-18 20:14	68.69	OK
12101	2026-09-18 20:15	71.72	OK	12102	2026-09-18 20:16	69.29	OK
12103	2026-09-18 20:17	70.55	OK	12104	2026-09-18 20:18	69.59	OK
12105	2026-09-18 20:19	69.54	OK	12106	2026-09-18 20:20	69.62	OK
12107	2026-09-18 20:21	71.59	OK	12108	2026-09-18 20:22	72.34	OK
12109	2026-09-18 20:23	72.91	OK	12110	2026-09-18 20:24	72.01	OK
12111	2026-09-18 20:25	71.97	OK	12112	2026-09-18 20:26	69.76	OK
12113	2026-09-18 20:27	72.01	OK	12114	2026-09-18 20:28	73.01	OK
12115	2026-09-18 20:29	74.02	OK	12116	2026-09-18 20:30	70.44	OK
12117	2026-09-18 20:31	72.71	OK	12118	2026-09-18 20:32	71.03	OK
12119	2026-09-18 20:33	69.92	OK	12120	2026-09-18 20:34	73.25	OK
12121	2026-09-18 20:35	69.97	OK	12122	2026-09-18 20:36	72.08	OK
12123	2026-09-18 20:37	71.93	OK	12124	2026-09-18 20:38	70.67	OK
12125	2026-09-18 20:39	72.35	OK	12126	2026-09-18 20:40	71.88	OK
12127	2026-09-18 20:41	72.92	OK	12128	2026-09-18 20:42	73.27	OK
1212	2026-09-18 20:43	71.53	OK	1213	2026-09-18 20:44	71.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
12131	2026-09-18 20:45	71.98	OK	12132	2026-09-18 20:46	72.38	OK
12133	2026-09-18 20:47	72.39	OK	12134	2026-09-18 20:48	71.45	OK
12135	2026-09-18 20:49	71.82	OK	12136	2026-09-18 20:50	72.67	OK
12137	2026-09-18 20:51	71.02	OK	12138	2026-09-18 20:52	73.14	OK
12139	2026-09-18 20:53	72.37	OK	12140	2026-09-18 20:54	72.83	OK
12141	2026-09-18 20:55	71.86	OK	12142	2026-09-18 20:56	72.51	OK
12143	2026-09-18 20:57	72.70	OK	12144	2026-09-18 20:58	71.36	OK
12145	2026-09-18 20:59	72.11	OK	12146	2026-09-18 21:00	72.92	OK
12147	2026-09-18 21:01	71.24	OK	12148	2026-09-18 21:02	70.96	OK
12149	2026-09-18 21:03	70.92	OK	12150	2026-09-18 21:04	71.50	OK
12151	2026-09-18 21:05	71.04	OK	12152	2026-09-18 21:06	72.34	OK
12153	2026-09-18 21:07	70.70	OK	12154	2026-09-18 21:08	71.51	OK
12155	2026-09-18 21:09	70.25	OK	12156	2026-09-18 21:10	70.55	OK
12157	2026-09-18 21:11	72.21	OK	12158	2026-09-18 21:12	70.32	OK
12159	2026-09-18 21:13	69.91	OK	12160	2026-09-18 21:14	73.16	OK
12161	2026-09-18 21:15	71.93	OK	12162	2026-09-18 21:16	71.66	OK
12163	2026-09-18 21:17	72.22	OK	12164	2026-09-18 21:18	71.76	OK
12165	2026-09-18 21:19	72.10	OK	12166	2026-09-18 21:20	70.73	OK
12167	2026-09-18 21:21	71.05	OK	12168	2026-09-18 21:22	70.12	OK
12169	2026-09-18 21:23	70.71	OK	12170	2026-09-18 21:24	69.88	OK
12171	2026-09-18 21:25	72.69	OK	12172	2026-09-18 21:26	70.76	OK
12173	2026-09-18 21:27	71.60	OK	12174	2026-09-18 21:28	71.98	OK
12175	2026-09-18 21:29	73.63	OK	12176	2026-09-18 21:30	73.50	OK
12177	2026-09-18 21:31	71.70	OK	12178	2026-09-18 21:32	71.07	OK
12179	2026-09-18 21:33	71.46	OK	12180	2026-09-18 21:34	72.52	OK
12181	2026-09-18 21:35	71.63	OK	12182	2026-09-18 21:36	72.17	OK
12183	2026-09-18 21:37	73.64	OK	12184	2026-09-18 21:38	72.98	OK
12185	2026-09-18 21:39	73.26	OK	12186	2026-09-18 21:40	75.01	OK
12187	2026-09-18 21:41	72.67	OK	12188	2026-09-18 21:42	72.09	OK
1218	2026-09-18 21:43	74.86	OK	1219	2026-09-18 21:44	73.11	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
12191	2026-09-18 21:45	71.59	OK	12192	2026-09-18 21:46	70.39	OK
12193	2026-09-18 21:47	71.81	OK	12194	2026-09-18 21:48	74.09	OK
12195	2026-09-18 21:49	69.20	OK	12196	2026-09-18 21:50	73.78	OK
12197	2026-09-18 21:51	72.84	OK	12198	2026-09-18 21:52	72.90	OK
12199	2026-09-18 21:53	73.42	OK	12200	2026-09-18 21:54	72.31	OK
12201	2026-09-18 21:55	71.73	OK	12202	2026-09-18 21:56	73.80	OK
12203	2026-09-18 21:57	71.99	OK	12204	2026-09-18 21:58	71.21	OK
12205	2026-09-18 21:59	73.36	OK	12206	2026-09-18 22:00	73.21	OK
12207	2026-09-18 22:01	74.30	OK	12208	2026-09-18 22:02	72.39	OK
12209	2026-09-18 22:03	74.84	OK	12210	2026-09-18 22:04	71.58	OK
12211	2026-09-18 22:05	74.65	OK	12212	2026-09-18 22:06	71.74	OK
12213	2026-09-18 22:07	73.39	OK	12214	2026-09-18 22:08	73.15	OK
12215	2026-09-18 22:09	70.67	OK	12216	2026-09-18 22:10	73.78	OK
12217	2026-09-18 22:11	74.82	OK	12218	2026-09-18 22:12	72.71	OK
12219	2026-09-18 22:13	72.79	OK	12220	2026-09-18 22:14	73.13	OK
12221	2026-09-18 22:15	72.02	OK	12222	2026-09-18 22:16	73.33	OK
12223	2026-09-18 22:17	74.36	OK	12224	2026-09-18 22:18	73.46	OK
12225	2026-09-18 22:19	71.82	OK	12226	2026-09-18 22:20	73.64	OK
12227	2026-09-18 22:21	73.04	OK	12228	2026-09-18 22:22	72.43	OK
12229	2026-09-18 22:23	72.05	OK	12230	2026-09-18 22:24	70.33	OK
12231	2026-09-18 22:25	73.55	OK	12232	2026-09-18 22:26	72.04	OK
12233	2026-09-18 22:27	72.60	OK	12234	2026-09-18 22:28	73.32	OK
12235	2026-09-18 22:29	73.10	OK	12236	2026-09-18 22:30	73.92	OK
12237	2026-09-18 22:31	71.88	OK	12238	2026-09-18 22:32	75.44	OK
12239	2026-09-18 22:33	70.81	OK	12240	2026-09-18 22:34	73.56	OK
12241	2026-09-18 22:35	72.27	OK	12242	2026-09-18 22:36	73.38	OK
12243	2026-09-18 22:37	73.70	OK	12244	2026-09-18 22:38	75.06	OK
12245	2026-09-18 22:39	71.45	OK	12246	2026-09-18 22:40	72.42	OK
12247	2026-09-18 22:41	72.64	OK	12248	2026-09-18 22:42	73.24	OK
12249	2026-09-18 22:43	71.87	OK	12250	2026-09-18 22:44	72.83	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
12251	2026-09-18 22:45	72.11	OK	12252	2026-09-18 22:46	73.40	OK
12253	2026-09-18 22:47	73.50	OK	12254	2026-09-18 22:48	73.68	OK
12255	2026-09-18 22:49	73.14	OK	12256	2026-09-18 22:50	73.58	OK
12257	2026-09-18 22:51	72.96	OK	12258	2026-09-18 22:52	73.67	OK
12259	2026-09-18 22:53	73.44	OK	12260	2026-09-18 22:54	73.73	OK
12261	2026-09-18 22:55	70.58	OK	12262	2026-09-18 22:56	73.30	OK
12263	2026-09-18 22:57	74.58	OK	12264	2026-09-18 22:58	73.81	OK
12265	2026-09-18 22:59	72.83	OK	12266	2026-09-18 23:00	71.77	OK
12267	2026-09-18 23:01	72.64	OK	12268	2026-09-18 23:02	74.03	OK
12269	2026-09-18 23:03	71.83	OK	12270	2026-09-18 23:04	74.53	OK
12271	2026-09-18 23:05	73.63	OK	12272	2026-09-18 23:06	72.50	OK
12273	2026-09-18 23:07	71.85	OK	12274	2026-09-18 23:08	71.96	OK
12275	2026-09-18 23:09	73.58	OK	12276	2026-09-18 23:10	74.42	OK
12277	2026-09-18 23:11	71.85	OK	12278	2026-09-18 23:12	73.20	OK
12279	2026-09-18 23:13	71.73	OK	12280	2026-09-18 23:14	73.79	OK
12281	2026-09-18 23:15	74.35	OK	12282	2026-09-18 23:16	74.79	OK
12283	2026-09-18 23:17	72.89	OK	12284	2026-09-18 23:18	74.15	OK
12285	2026-09-18 23:19	72.18	OK	12286	2026-09-18 23:20	72.54	OK
12287	2026-09-18 23:21	71.91	OK	12288	2026-09-18 23:22	73.11	OK
12289	2026-09-18 23:23	73.09	OK	12290	2026-09-18 23:24	73.81	OK
12291	2026-09-18 23:25	70.69	OK	12292	2026-09-18 23:26	72.86	OK
12293	2026-09-18 23:27	71.02	OK	12294	2026-09-18 23:28	71.79	OK
12295	2026-09-18 23:29	73.19	OK	12296	2026-09-18 23:30	71.53	OK
12297	2026-09-18 23:31	72.41	OK	12298	2026-09-18 23:32	70.75	OK
12299	2026-09-18 23:33	74.46	OK	12300	2026-09-18 23:34	72.32	OK
12301	2026-09-18 23:35	73.20	OK	12302	2026-09-18 23:36	72.70	OK
12303	2026-09-18 23:37	72.97	OK	12304	2026-09-18 23:38	73.63	OK
12305	2026-09-18 23:39	72.47	OK	12306	2026-09-18 23:40	71.67	OK
12307	2026-09-18 23:41	72.85	OK	12308	2026-09-18 23:42	71.92	OK
1230	2026-09-18 23:43	75.34	OK	1231	2026-09-18 23:44	74.79	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
12311	2026-09-18 23:45	73.26	OK	12312	2026-09-18 23:46	72.92	OK
12313	2026-09-18 23:47	72.31	OK	12314	2026-09-18 23:48	72.89	OK
12315	2026-09-18 23:49	73.17	OK	12316	2026-09-18 23:50	74.84	OK
12317	2026-09-18 23:51	73.31	OK	12318	2026-09-18 23:52	74.04	OK
12319	2026-09-18 23:53	71.29	OK	12320	2026-09-18 23:54	69.88	OK
12321	2026-09-18 23:55	73.29	OK	12322	2026-09-18 23:56	73.22	OK
12323	2026-09-18 23:57	70.20	OK	12324	2026-09-18 23:58	71.81	OK
12325	2026-09-18 23:59	71.25	OK	12326	2026-09-19 00:00	72.30	OK
12327	2026-09-19 00:01	73.52	OK	12328	2026-09-19 00:02	74.35	OK
12329	2026-09-19 00:03	73.77	OK	12330	2026-09-19 00:04	73.59	OK
12331	2026-09-19 00:05	74.27	OK	12332	2026-09-19 00:06	72.84	OK
12333	2026-09-19 00:07	72.72	OK	12334	2026-09-19 00:08	71.77	OK
12335	2026-09-19 00:09	73.91	OK	12336	2026-09-19 00:10	71.99	OK
12337	2026-09-19 00:11	70.34	OK	12338	2026-09-19 00:12	73.63	OK
12339	2026-09-19 00:13	73.53	OK	12340	2026-09-19 00:14	74.15	OK
12341	2026-09-19 00:15	71.19	OK	12342	2026-09-19 00:16	72.94	OK
12343	2026-09-19 00:17	70.30	OK	12344	2026-09-19 00:18	72.65	OK
12345	2026-09-19 00:19	73.75	OK	12346	2026-09-19 00:20	74.70	OK
12347	2026-09-19 00:21	71.94	OK	12348	2026-09-19 00:22	72.64	OK
12349	2026-09-19 00:23	70.84	OK	12350	2026-09-19 00:24	71.98	OK
12351	2026-09-19 00:25	73.15	OK	12352	2026-09-19 00:26	74.13	OK
12353	2026-09-19 00:27	71.96	OK	12354	2026-09-19 00:28	69.87	OK
12355	2026-09-19 00:29	70.07	OK	12356	2026-09-19 00:30	71.82	OK
12357	2026-09-19 00:31	70.33	OK	12358	2026-09-19 00:32	72.25	OK
12359	2026-09-19 00:33	72.99	OK	12360	2026-09-19 00:34	70.73	OK
12361	2026-09-19 00:35	72.03	OK	12362	2026-09-19 00:36	70.77	OK
12363	2026-09-19 00:37	72.70	OK	12364	2026-09-19 00:38	72.56	OK
12365	2026-09-19 00:39	72.42	OK	12366	2026-09-19 00:40	70.11	OK
12367	2026-09-19 00:41	71.96	OK	12368	2026-09-19 00:42	72.10	OK
1236	2026-09-19 00:43	72.73	OK	1237	2026-09-19 00:44	68.99	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
12371	2026-09-19 00:45	69.98	OK	12372	2026-09-19 00:46	70.37	OK
12373	2026-09-19 00:47	69.88	OK	12374	2026-09-19 00:48	71.87	OK
12375	2026-09-19 00:49	70.57	OK	12376	2026-09-19 00:50	70.64	OK
12377	2026-09-19 00:51	71.53	OK	12378	2026-09-19 00:52	72.69	OK
12379	2026-09-19 00:53	69.85	OK	12380	2026-09-19 00:54	70.93	OK
12381	2026-09-19 00:55	73.88	OK	12382	2026-09-19 00:56	70.50	OK
12383	2026-09-19 00:57	71.80	OK	12384	2026-09-19 00:58	72.40	OK
12385	2026-09-19 00:59	74.42	OK	12386	2026-09-19 01:00	70.96	OK
12387	2026-09-19 01:01	72.24	OK	12388	2026-09-19 01:02	71.55	OK
12389	2026-09-19 01:03	71.89	OK	12390	2026-09-19 01:04	70.78	OK
12391	2026-09-19 01:05	71.00	OK	12392	2026-09-19 01:06	71.29	OK
12393	2026-09-19 01:07	69.73	OK	12394	2026-09-19 01:08	72.29	OK
12395	2026-09-19 01:09	73.72	OK	12396	2026-09-19 01:10	72.09	OK
12397	2026-09-19 01:11	69.82	OK	12398	2026-09-19 01:12	72.09	OK
12399	2026-09-19 01:13	71.97	OK	12400	2026-09-19 01:14	69.46	OK
12401	2026-09-19 01:15	70.42	OK	12402	2026-09-19 01:16	71.87	OK
12403	2026-09-19 01:17	69.94	OK	12404	2026-09-19 01:18	70.11	OK
12405	2026-09-19 01:19	73.35	OK	12406	2026-09-19 01:20	73.76	OK
12407	2026-09-19 01:21	72.12	OK	12408	2026-09-19 01:22	68.43	OK
12409	2026-09-19 01:23	71.18	OK	12410	2026-09-19 01:24	69.83	OK
12411	2026-09-19 01:25	72.18	OK	12412	2026-09-19 01:26	69.99	OK
12413	2026-09-19 01:27	71.46	OK	12414	2026-09-19 01:28	71.35	OK
12415	2026-09-19 01:29	70.74	OK	12416	2026-09-19 01:30	72.48	OK
12417	2026-09-19 01:31	69.77	OK	12418	2026-09-19 01:32	72.08	OK
12419	2026-09-19 01:33	69.49	OK	12420	2026-09-19 01:34	69.83	OK
12421	2026-09-19 01:35	70.40	OK	12422	2026-09-19 01:36	69.40	OK
12423	2026-09-19 01:37	73.26	OK	12424	2026-09-19 01:38	69.36	OK
12425	2026-09-19 01:39	71.34	OK	12426	2026-09-19 01:40	70.46	OK
12427	2026-09-19 01:41	69.31	OK	12428	2026-09-19 01:42	69.35	OK
1242	2026-09-19 01:43	72.10	OK	1243	2026-09-19 01:44	71.90	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
12431	2026-09-19 01:45	71.04	OK	12432	2026-09-19 01:46	70.34	OK
12433	2026-09-19 01:47	69.79	OK	12434	2026-09-19 01:48	71.57	OK
12435	2026-09-19 01:49	72.16	OK	12436	2026-09-19 01:50	69.58	OK
12437	2026-09-19 01:51	72.10	OK	12438	2026-09-19 01:52	69.93	OK
12439	2026-09-19 01:53	68.49	OK	12440	2026-09-19 01:54	70.23	OK
12441	2026-09-19 01:55	70.77	OK	12442	2026-09-19 01:56	69.09	OK
12443	2026-09-19 01:57	71.49	OK	12444	2026-09-19 01:58	69.20	OK
12445	2026-09-19 01:59	71.51	OK	12446	2026-09-19 02:00	73.82	OK
12447	2026-09-19 02:01	71.85	OK	12448	2026-09-19 02:02	69.04	OK
12449	2026-09-19 02:03	71.47	OK	12450	2026-09-19 02:04	69.73	OK
12451	2026-09-19 02:05	69.95	OK	12452	2026-09-19 02:06	70.45	OK
12453	2026-09-19 02:07	71.77	OK	12454	2026-09-19 02:08	71.13	OK
12455	2026-09-19 02:09	71.65	OK	12456	2026-09-19 02:10	71.60	OK
12457	2026-09-19 02:11	69.52	OK	12458	2026-09-19 02:12	68.10	OK
12459	2026-09-19 02:13	71.53	OK	12460	2026-09-19 02:14	69.02	OK
12461	2026-09-19 02:15	70.99	OK	12462	2026-09-19 02:16	67.89	OK
12463	2026-09-19 02:17	71.99	OK	12464	2026-09-19 02:18	70.07	OK
12465	2026-09-19 02:19	71.04	OK	12466	2026-09-19 02:20	69.22	OK
12467	2026-09-19 02:21	68.79	OK	12468	2026-09-19 02:22	68.31	OK
12469	2026-09-19 02:23	71.33	OK	12470	2026-09-19 02:24	70.06	OK
12471	2026-09-19 02:25	69.95	OK	12472	2026-09-19 02:26	71.49	OK
12473	2026-09-19 02:27	70.44	OK	12474	2026-09-19 02:28	69.63	OK
12475	2026-09-19 02:29	67.32	OK	12476	2026-09-19 02:30	70.47	OK
12477	2026-09-19 02:31	68.67	OK	12478	2026-09-19 02:32	68.77	OK
12479	2026-09-19 02:33	68.99	OK	12480	2026-09-19 02:34	70.72	OK
12481	2026-09-19 02:35	69.21	OK	12482	2026-09-19 02:36	70.94	OK
12483	2026-09-19 02:37	68.97	OK	12484	2026-09-19 02:38	69.02	OK
12485	2026-09-19 02:39	67.87	OK	12486	2026-09-19 02:40	68.39	OK
12487	2026-09-19 02:41	69.37	OK	12488	2026-09-19 02:42	70.52	OK
1248	2026-09-19 02:43	71.03	OK	1249	2026-09-19 02:44	66.82	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
12491	2026-09-19 02:45	67.90	OK	12492	2026-09-19 02:46	70.16	OK
12493	2026-09-19 02:47	68.54	OK	12494	2026-09-19 02:48	65.85	OK
12495	2026-09-19 02:49	69.30	OK	12496	2026-09-19 02:50	69.94	OK
12497	2026-09-19 02:51	71.69	OK	12498	2026-09-19 02:52	68.42	OK
12499	2026-09-19 02:53	67.15	OK	12500	2026-09-19 02:54	67.63	OK
12501	2026-09-19 02:55	68.34	OK	12502	2026-09-19 02:56	67.68	OK
12503	2026-09-19 02:57	68.62	OK	12504	2026-09-19 02:58	66.52	OK
12505	2026-09-19 02:59	67.67	OK	12506	2026-09-19 03:00	68.28	OK
12507	2026-09-19 03:01	68.87	OK	12508	2026-09-19 03:02	70.90	OK
12509	2026-09-19 03:03	68.47	OK	12510	2026-09-19 03:04	71.78	OK
12511	2026-09-19 03:05	69.66	OK	12512	2026-09-19 03:06	70.51	OK
12513	2026-09-19 03:07	67.66	OK	12514	2026-09-19 03:08	66.76	OK
12515	2026-09-19 03:09	67.91	OK	12516	2026-09-19 03:10	69.35	OK
12517	2026-09-19 03:11	68.25	OK	12518	2026-09-19 03:12	69.79	OK
12519	2026-09-19 03:13	68.22	OK	12520	2026-09-19 03:14	68.80	OK
12521	2026-09-19 03:15	67.52	OK	12522	2026-09-19 03:16	68.43	OK
12523	2026-09-19 03:17	68.60	OK	12524	2026-09-19 03:18	67.16	OK
12525	2026-09-19 03:19	65.89	OK	12526	2026-09-19 03:20	70.31	OK
12527	2026-09-19 03:21	69.93	OK	12528	2026-09-19 03:22	68.13	OK
12529	2026-09-19 03:23	69.01	OK	12530	2026-09-19 03:24	69.17	OK
12531	2026-09-19 03:25	69.41	OK	12532	2026-09-19 03:26	69.62	OK
12533	2026-09-19 03:27	68.67	OK	12534	2026-09-19 03:28	69.89	OK
12535	2026-09-19 03:29	67.96	OK	12536	2026-09-19 03:30	70.79	OK
12537	2026-09-19 03:31	66.41	OK	12538	2026-09-19 03:32	66.44	OK
12539	2026-09-19 03:33	69.53	OK	12540	2026-09-19 03:34	68.03	OK
12541	2026-09-19 03:35	66.01	OK	12542	2026-09-19 03:36	68.60	OK
12543	2026-09-19 03:37	68.31	OK	12544	2026-09-19 03:38	69.87	OK
12545	2026-09-19 03:39	66.95	OK	12546	2026-09-19 03:40	67.76	OK
12547	2026-09-19 03:41	67.43	OK	12548	2026-09-19 03:42	66.08	OK
1254	2026-09-19 03:43	68.99	OK	1255	2026-09-19 03:44	67.78	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
12551	2026-09-19 03:45	68.21	OK	12552	2026-09-19 03:46	67.32	OK
12553	2026-09-19 03:47	66.82	OK	12554	2026-09-19 03:48	66.23	OK
12555	2026-09-19 03:49	67.93	OK	12556	2026-09-19 03:50	67.64	OK
12557	2026-09-19 03:51	69.16	OK	12558	2026-09-19 03:52	67.88	OK
12559	2026-09-19 03:53	67.61	OK	12560	2026-09-19 03:54	64.72	OK
12561	2026-09-19 03:55	67.32	OK	12562	2026-09-19 03:56	64.89	OK
12563	2026-09-19 03:57	68.77	OK	12564	2026-09-19 03:58	67.56	OK
12565	2026-09-19 03:59	69.59	OK	12566	2026-09-19 04:00	66.90	OK
12567	2026-09-19 04:01	66.55	OK	12568	2026-09-19 04:02	66.17	OK
12569	2026-09-19 04:03	67.68	OK	12570	2026-09-19 04:04	65.49	OK
12571	2026-09-19 04:05	65.64	OK	12572	2026-09-19 04:06	65.04	OK
12573	2026-09-19 04:07	65.81	OK	12574	2026-09-19 04:08	66.05	OK
12575	2026-09-19 04:09	66.05	OK	12576	2026-09-19 04:10	68.28	OK
12577	2026-09-19 04:11	66.19	OK	12578	2026-09-19 04:12	64.84	OK
12579	2026-09-19 04:13	66.37	OK	12580	2026-09-19 04:14	68.08	OK
12581	2026-09-19 04:15	67.26	OK	12582	2026-09-19 04:16	67.33	OK
12583	2026-09-19 04:17	66.63	OK	12584	2026-09-19 04:18	66.97	OK
12585	2026-09-19 04:19	67.51	OK	12586	2026-09-19 04:20	67.88	OK
12587	2026-09-19 04:21	67.08	OK	12588	2026-09-19 04:22	67.31	OK
12589	2026-09-19 04:23	66.00	OK	12590	2026-09-19 04:24	65.55	OK
12591	2026-09-19 04:25	64.55	OK	12592	2026-09-19 04:26	67.58	OK
12593	2026-09-19 04:27	63.24	OK	12594	2026-09-19 04:28	68.19	OK
12595	2026-09-19 04:29	64.79	OK	12596	2026-09-19 04:30	63.99	OK
12597	2026-09-19 04:31	66.74	OK	12598	2026-09-19 04:32	65.66	OK
12599	2026-09-19 04:33	66.34	OK	12600	2026-09-19 04:34	68.21	OK
12601	2026-09-19 04:35	67.79	OK	12602	2026-09-19 04:36	65.65	OK
12603	2026-09-19 04:37	66.45	OK	12604	2026-09-19 04:38	65.84	OK
12605	2026-09-19 04:39	69.19	OK	12606	2026-09-19 04:40	67.58	OK
12607	2026-09-19 04:41	67.24	OK	12608	2026-09-19 04:42	67.22	OK
1260	2026-09-19 04:43	67.17	OK	1261	2026-09-19 04:44	65.81	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
12611	2026-09-19 04:45	64.75	OK	12612	2026-09-19 04:46	64.52	OK
12613	2026-09-19 04:47	65.12	OK	12614	2026-09-19 04:48	64.11	OK
12615	2026-09-19 04:49	65.58	OK	12616	2026-09-19 04:50	65.58	OK
12617	2026-09-19 04:51	63.56	OK	12618	2026-09-19 04:52	65.49	OK
12619	2026-09-19 04:53	66.61	OK	12620	2026-09-19 04:54	68.63	OK
12621	2026-09-19 04:55	64.56	OK	12622	2026-09-19 04:56	62.86	OK
12623	2026-09-19 04:57	67.04	OK	12624	2026-09-19 04:58	65.08	OK
12625	2026-09-19 04:59	65.14	OK	12626	2026-09-19 05:00	64.42	OK
12627	2026-09-19 05:01	63.33	OK	12628	2026-09-19 05:02	65.76	OK
12629	2026-09-19 05:03	66.71	OK	12630	2026-09-19 05:04	64.88	OK
12631	2026-09-19 05:05	67.71	OK	12632	2026-09-19 05:06	64.25	OK
12633	2026-09-19 05:07	67.67	OK	12634	2026-09-19 05:08	65.75	OK
12635	2026-09-19 05:09	66.68	OK	12636	2026-09-19 05:10	65.42	OK
12637	2026-09-19 05:11	66.21	OK	12638	2026-09-19 05:12	65.87	OK
12639	2026-09-19 05:13	64.11	OK	12640	2026-09-19 05:14	66.83	OK
12641	2026-09-19 05:15	65.51	OK	12642	2026-09-19 05:16	65.37	OK
12643	2026-09-19 05:17	67.58	OK	12644	2026-09-19 05:18	66.05	OK
12645	2026-09-19 05:19	63.59	OK	12646	2026-09-19 05:20	65.65	OK
12647	2026-09-19 05:21	65.86	OK	12648	2026-09-19 05:22	65.02	OK
12649	2026-09-19 05:23	64.62	OK	12650	2026-09-19 05:24	66.01	OK
12651	2026-09-19 05:25	66.04	OK	12652	2026-09-19 05:26	64.93	OK
12653	2026-09-19 05:27	65.16	OK	12654	2026-09-19 05:28	63.18	OK
12655	2026-09-19 05:29	64.22	OK	12656	2026-09-19 05:30	63.69	OK
12657	2026-09-19 05:31	65.32	OK	12658	2026-09-19 05:32	64.92	OK
12659	2026-09-19 05:33	64.32	OK	12660	2026-09-19 05:34	65.98	OK
12661	2026-09-19 05:35	66.23	OK	12662	2026-09-19 05:36	65.92	OK
12663	2026-09-19 05:37	63.42	OK	12664	2026-09-19 05:38	63.42	OK
12665	2026-09-19 05:39	67.04	OK	12666	2026-09-19 05:40	65.62	OK
12667	2026-09-19 05:41	65.45	OK	12668	2026-09-19 05:42	65.85	OK
12669	2026-09-19 05:43	64.50	OK	12670	2026-09-19 05:44	63.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
12671	2026-09-19 05:45	63.41	OK	12672	2026-09-19 05:46	65.03	OK
12673	2026-09-19 05:47	63.97	OK	12674	2026-09-19 05:48	63.84	OK
12675	2026-09-19 05:49	63.02	OK	12676	2026-09-19 05:50	64.70	OK
12677	2026-09-19 05:51	63.48	OK	12678	2026-09-19 05:52	66.49	OK
12679	2026-09-19 05:53	62.25	OK	12680	2026-09-19 05:54	63.49	OK
12681	2026-09-19 05:55	65.18	OK	12682	2026-09-19 05:56	64.35	OK
12683	2026-09-19 05:57	64.80	OK	12684	2026-09-19 05:58	62.71	OK
12685	2026-09-19 05:59	64.83	OK	12686	2026-09-19 06:00	64.05	OK
12687	2026-09-19 06:01	63.42	OK	12688	2026-09-19 06:02	64.81	OK
12689	2026-09-19 06:03	64.75	OK	12690	2026-09-19 06:04	63.13	OK
12691	2026-09-19 06:05	65.20	OK	12692	2026-09-19 06:06	62.54	OK
12693	2026-09-19 06:07	62.83	OK	12694	2026-09-19 06:08	62.40	OK
12695	2026-09-19 06:09	65.67	OK	12696	2026-09-19 06:10	63.28	OK
12697	2026-09-19 06:11	64.37	OK	12698	2026-09-19 06:12	63.54	OK
12699	2026-09-19 06:13	60.66	OK	12700	2026-09-19 06:14	63.17	OK
12701	2026-09-19 06:15	64.39	OK	12702	2026-09-19 06:16	63.12	OK
12703	2026-09-19 06:17	63.95	OK	12704	2026-09-19 06:18	63.21	OK
12705	2026-09-19 06:19	63.66	OK	12706	2026-09-19 06:20	61.07	OK
12707	2026-09-19 06:21	63.41	OK	12708	2026-09-19 06:22	61.54	OK
12709	2026-09-19 06:23	63.61	OK	12710	2026-09-19 06:24	61.98	OK
12711	2026-09-19 06:25	62.13	OK	12712	2026-09-19 06:26	63.67	OK
12713	2026-09-19 06:27	64.08	OK	12714	2026-09-19 06:28	64.98	OK
12715	2026-09-19 06:29	61.49	OK	12716	2026-09-19 06:30	63.66	OK
12717	2026-09-19 06:31	63.11	OK	12718	2026-09-19 06:32	63.95	OK
12719	2026-09-19 06:33	64.29	OK	12720	2026-09-19 06:34	63.16	OK
12721	2026-09-19 06:35	63.06	OK	12722	2026-09-19 06:36	63.90	OK
12723	2026-09-19 06:37	64.14	OK	12724	2026-09-19 06:38	63.70	OK
12725	2026-09-19 06:39	62.82	OK	12726	2026-09-19 06:40	61.99	OK
12727	2026-09-19 06:41	64.61	OK	12728	2026-09-19 06:42	65.01	OK
12729	2026-09-19 06:43	63.01	OK	12730	2026-09-19 06:44	63.64	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
12731	2026-09-19 06:45	62.70	OK	12732	2026-09-19 06:46	62.33	OK
12733	2026-09-19 06:47	62.77	OK	12734	2026-09-19 06:48	61.63	OK
12735	2026-09-19 06:49	62.87	OK	12736	2026-09-19 06:50	62.99	OK
12737	2026-09-19 06:51	62.74	OK	12738	2026-09-19 06:52	64.04	OK
12739	2026-09-19 06:53	62.97	OK	12740	2026-09-19 06:54	63.21	OK
12741	2026-09-19 06:55	62.44	OK	12742	2026-09-19 06:56	64.11	OK
12743	2026-09-19 06:57	61.55	OK	12744	2026-09-19 06:58	63.75	OK
12745	2026-09-19 06:59	64.18	OK	12746	2026-09-19 07:00	63.57	OK
12747	2026-09-19 07:01	64.42	OK	12748	2026-09-19 07:02	61.00	OK
12749	2026-09-19 07:03	61.13	OK	12750	2026-09-19 07:04	61.72	OK
12751	2026-09-19 07:05	63.50	OK	12752	2026-09-19 07:06	63.17	OK
12753	2026-09-19 07:07	63.37	OK	12754	2026-09-19 07:08	62.96	OK
12755	2026-09-19 07:09	61.66	OK	12756	2026-09-19 07:10	61.41	OK
12757	2026-09-19 07:11	59.20	OK	12758	2026-09-19 07:12	63.17	OK
12759	2026-09-19 07:13	62.17	OK	12760	2026-09-19 07:14	61.62	OK
12761	2026-09-19 07:15	62.50	OK	12762	2026-09-19 07:16	63.32	OK
12763	2026-09-19 07:17	63.13	OK	12764	2026-09-19 07:18	61.10	OK
12765	2026-09-19 07:19	62.41	OK	12766	2026-09-19 07:20	63.06	OK
12767	2026-09-19 07:21	61.19	OK	12768	2026-09-19 07:22	61.26	OK
12769	2026-09-19 07:23	63.10	OK	12770	2026-09-19 07:24	60.46	OK
12771	2026-09-19 07:25	65.13	OK	12772	2026-09-19 07:26	60.68	OK
12773	2026-09-19 07:27	60.74	OK	12774	2026-09-19 07:28	61.83	OK
12775	2026-09-19 07:29	60.80	OK	12776	2026-09-19 07:30	63.48	OK
12777	2026-09-19 07:31	62.44	OK	12778	2026-09-19 07:32	62.14	OK
12779	2026-09-19 07:33	60.95	OK	12780	2026-09-19 07:34	60.43	OK
12781	2026-09-19 07:35	62.93	OK	12782	2026-09-19 07:36	64.53	OK
12783	2026-09-19 07:37	63.37	OK	12784	2026-09-19 07:38	58.77	OK
12785	2026-09-19 07:39	62.22	OK	12786	2026-09-19 07:40	60.27	OK
12787	2026-09-19 07:41	60.75	OK	12788	2026-09-19 07:42	63.51	OK
1278	2026-09-19 07:43	61.24	OK	1279	2026-09-19 07:44	60.46	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
12791	2026-09-19 07:45	59.58	OK	12792	2026-09-19 07:46	61.10	OK
12793	2026-09-19 07:47	61.75	OK	12794	2026-09-19 07:48	59.74	OK
12795	2026-09-19 07:49	61.85	OK	12796	2026-09-19 07:50	60.57	OK
12797	2026-09-19 07:51	59.04	OK	12798	2026-09-19 07:52	60.49	OK
12799	2026-09-19 07:53	60.72	OK	12800	2026-09-19 07:54	60.94	OK
12801	2026-09-19 07:55	61.94	OK	12802	2026-09-19 07:56	61.30	OK
12803	2026-09-19 07:57	61.33	OK	12804	2026-09-19 07:58	62.83	OK
12805	2026-09-19 07:59	61.84	OK	12806	2026-09-19 08:00	62.44	OK
12807	2026-09-19 08:01	62.53	OK	12808	2026-09-19 08:02	62.17	OK
12809	2026-09-19 08:03	61.24	OK	12810	2026-09-19 08:04	59.49	OK
12811	2026-09-19 08:05	61.64	OK	12812	2026-09-19 08:06	61.14	OK
12813	2026-09-19 08:07	60.93	OK	12814	2026-09-19 08:08	62.31	OK
12815	2026-09-19 08:09	62.93	OK	12816	2026-09-19 08:10	60.31	OK
12817	2026-09-19 08:11	61.43	OK	12818	2026-09-19 08:12	61.88	OK
12819	2026-09-19 08:13	60.27	OK	12820	2026-09-19 08:14	61.05	OK
12821	2026-09-19 08:15	61.49	OK	12822	2026-09-19 08:16	61.22	OK
12823	2026-09-19 08:17	60.72	OK	12824	2026-09-19 08:18	58.49	OK
12825	2026-09-19 08:19	62.72	OK	12826	2026-09-19 08:20	60.74	OK
12827	2026-09-19 08:21	59.63	OK	12828	2026-09-19 08:22	61.88	OK
12829	2026-09-19 08:23	61.85	OK	12830	2026-09-19 08:24	61.83	OK
12831	2026-09-19 08:25	60.94	OK	12832	2026-09-19 08:26	62.48	OK
12833	2026-09-19 08:27	61.44	OK	12834	2026-09-19 08:28	59.22	OK
12835	2026-09-19 08:29	60.35	OK	12836	2026-09-19 08:30	61.47	OK
12837	2026-09-19 08:31	61.42	OK	12838	2026-09-19 08:32	62.04	OK
12839	2026-09-19 08:33	58.89	OK	12840	2026-09-19 08:34	60.90	OK
12841	2026-09-19 08:35	59.39	OK	12842	2026-09-19 08:36	61.61	OK
12843	2026-09-19 08:37	59.91	OK	12844	2026-09-19 08:38	60.82	OK
12845	2026-09-19 08:39	60.56	OK	12846	2026-09-19 08:40	62.08	OK
12847	2026-09-19 08:41	60.16	OK	12848	2026-09-19 08:42	61.18	OK
1284	2026-09-19 08:43	59.89	OK	1285	2026-09-19 08:44	60.34	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
12851	2026-09-19 08:45	58.84	OK	12852	2026-09-19 08:46	59.75	OK
12853	2026-09-19 08:47	60.01	OK	12854	2026-09-19 08:48	60.07	OK
12855	2026-09-19 08:49	60.59	OK	12856	2026-09-19 08:50	58.36	OK
12857	2026-09-19 08:51	59.62	OK	12858	2026-09-19 08:52	59.06	OK
12859	2026-09-19 08:53	59.22	OK	12860	2026-09-19 08:54	60.76	OK
12861	2026-09-19 08:55	60.08	OK	12862	2026-09-19 08:56	59.68	OK
12863	2026-09-19 08:57	61.06	OK	12864	2026-09-19 08:58	60.92	OK
12865	2026-09-19 08:59	59.68	OK	12866	2026-09-19 09:00	60.60	OK
12867	2026-09-19 09:01	59.90	OK	12868	2026-09-19 09:02	59.25	OK
12869	2026-09-19 09:03	59.12	OK	12870	2026-09-19 09:04	60.52	OK
12871	2026-09-19 09:05	61.13	OK	12872	2026-09-19 09:06	61.28	OK
12873	2026-09-19 09:07	60.03	OK	12874	2026-09-19 09:08	59.57	OK
12875	2026-09-19 09:09	59.65	OK	12876	2026-09-19 09:10	60.68	OK
12877	2026-09-19 09:11	59.51	OK	12878	2026-09-19 09:12	58.75	OK
12879	2026-09-19 09:13	61.11	OK	12880	2026-09-19 09:14	60.49	OK
12881	2026-09-19 09:15	61.01	OK	12882	2026-09-19 09:16	61.33	OK
12883	2026-09-19 09:17	59.48	OK	12884	2026-09-19 09:18	61.58	OK
12885	2026-09-19 09:19	59.29	OK	12886	2026-09-19 09:20	61.08	OK
12887	2026-09-19 09:21	58.10	OK	12888	2026-09-19 09:22	61.77	OK
12889	2026-09-19 09:23	61.75	OK	12890	2026-09-19 09:24	60.18	OK
12891	2026-09-19 09:25	58.40	OK	12892	2026-09-19 09:26	61.06	OK
12893	2026-09-19 09:27	61.71	OK	12894	2026-09-19 09:28	58.97	OK
12895	2026-09-19 09:29	60.34	OK	12896	2026-09-19 09:30	59.08	OK
12897	2026-09-19 09:31	60.14	OK	12898	2026-09-19 09:32	61.12	OK
12899	2026-09-19 09:33	60.51	OK	12900	2026-09-19 09:34	59.03	OK
12901	2026-09-19 09:35	59.13	OK	12902	2026-09-19 09:36	61.71	OK
12903	2026-09-19 09:37	58.30	OK	12904	2026-09-19 09:38	60.15	OK
12905	2026-09-19 09:39	59.14	OK	12906	2026-09-19 09:40	58.81	OK
12907	2026-09-19 09:41	60.23	OK	12908	2026-09-19 09:42	59.93	OK
12909	2026-09-19 09:43	59.22	OK	1291	2026-09-19 09:44	58.98	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
12911	2026-09-19 09:45	61.15	OK	12912	2026-09-19 09:46	60.50	OK
12913	2026-09-19 09:47	59.83	OK	12914	2026-09-19 09:48	57.29	OK
12915	2026-09-19 09:49	60.86	OK	12916	2026-09-19 09:50	57.34	OK
12917	2026-09-19 09:51	58.99	OK	12918	2026-09-19 09:52	60.21	OK
12919	2026-09-19 09:53	59.09	OK	12920	2026-09-19 09:54	59.33	OK
12921	2026-09-19 09:55	58.93	OK	12922	2026-09-19 09:56	60.05	OK
12923	2026-09-19 09:57	57.51	OK	12924	2026-09-19 09:58	57.60	OK
12925	2026-09-19 09:59	56.78	OK	12926	2026-09-19 10:00	56.91	OK
12927	2026-09-19 10:01	59.37	OK	12928	2026-09-19 10:02	61.24	OK
12929	2026-09-19 10:03	58.48	OK	12930	2026-09-19 10:04	59.64	OK
12931	2026-09-19 10:05	60.08	OK	12932	2026-09-19 10:06	59.92	OK
12933	2026-09-19 10:07	59.39	OK	12934	2026-09-19 10:08	60.06	OK
12935	2026-09-19 10:09	61.01	OK	12936	2026-09-19 10:10	57.48	OK
12937	2026-09-19 10:11	60.58	OK	12938	2026-09-19 10:12	61.03	OK
12939	2026-09-19 10:13	59.25	OK	12940	2026-09-19 10:14	59.11	OK
12941	2026-09-19 10:15	58.00	OK	12942	2026-09-19 10:16	58.40	OK
12943	2026-09-19 10:17	58.76	OK	12944	2026-09-19 10:18	59.27	OK
12945	2026-09-19 10:19	61.10	OK	12946	2026-09-19 10:20	59.41	OK
12947	2026-09-19 10:21	57.85	OK	12948	2026-09-19 10:22	59.31	OK
12949	2026-09-19 10:23	61.39	OK	12950	2026-09-19 10:24	59.28	OK
12951	2026-09-19 10:25	57.52	OK	12952	2026-09-19 10:26	59.11	OK
12953	2026-09-19 10:27	60.45	OK	12954	2026-09-19 10:28	59.93	OK
12955	2026-09-19 10:29	61.61	OK	12956	2026-09-19 10:30	59.65	OK
12957	2026-09-19 10:31	61.55	OK	12958	2026-09-19 10:32	58.46	OK
12959	2026-09-19 10:33	60.88	OK	12960	2026-09-19 10:34	62.25	OK
12961	2026-09-19 10:35	59.47	OK	12962	2026-09-19 10:36	59.94	OK
12963	2026-09-19 10:37	60.26	OK	12964	2026-09-19 10:38	59.39	OK
12965	2026-09-19 10:39	61.76	OK	12966	2026-09-19 10:40	60.62	OK
12967	2026-09-19 10:41	60.23	OK	12968	2026-09-19 10:42	60.20	OK
12969	2026-09-19 10:43	58.16	OK	12970	2026-09-19 10:44	61.14	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
12971	2026-09-19 10:45	59.78	OK	12972	2026-09-19 10:46	59.41	OK
12973	2026-09-19 10:47	58.78	OK	12974	2026-09-19 10:48	58.89	OK
12975	2026-09-19 10:49	58.97	OK	12976	2026-09-19 10:50	58.32	OK
12977	2026-09-19 10:51	59.78	OK	12978	2026-09-19 10:52	59.89	OK
12979	2026-09-19 10:53	60.78	OK	12980	2026-09-19 10:54	58.74	OK
12981	2026-09-19 10:55	59.98	OK	12982	2026-09-19 10:56	59.01	OK
12983	2026-09-19 10:57	59.72	OK	12984	2026-09-19 10:58	60.27	OK
12985	2026-09-19 10:59	58.53	OK	12986	2026-09-19 11:00	57.77	OK
12987	2026-09-19 11:01	57.00	OK	12988	2026-09-19 11:02	59.20	OK
12989	2026-09-19 11:03	59.21	OK	12990	2026-09-19 11:04	61.56	OK
12991	2026-09-19 11:05	58.58	OK	12992	2026-09-19 11:06	58.09	OK
12993	2026-09-19 11:07	61.48	OK	12994	2026-09-19 11:08	58.78	OK
12995	2026-09-19 11:09	59.37	OK	12996	2026-09-19 11:10	60.16	OK
12997	2026-09-19 11:11	60.96	OK	12998	2026-09-19 11:12	60.87	OK
12999	2026-09-19 11:13	59.07	OK	13000	2026-09-19 11:14	61.67	OK
13001	2026-09-19 11:15	58.71	OK	13002	2026-09-19 11:16	58.54	OK
13003	2026-09-19 11:17	57.65	OK	13004	2026-09-19 11:18	61.42	OK
13005	2026-09-19 11:19	59.86	OK	13006	2026-09-19 11:20	58.21	OK
13007	2026-09-19 11:21	59.86	OK	13008	2026-09-19 11:22	59.48	OK
13009	2026-09-19 11:23	59.79	OK	13010	2026-09-19 11:24	59.03	OK
13011	2026-09-19 11:25	58.82	OK	13012	2026-09-19 11:26	60.43	OK
13013	2026-09-19 11:27	60.15	OK	13014	2026-09-19 11:28	60.28	OK
13015	2026-09-19 11:29	59.02	OK	13016	2026-09-19 11:30	60.07	OK
13017	2026-09-19 11:31	59.27	OK	13018	2026-09-19 11:32	58.52	OK
13019	2026-09-19 11:33	58.99	OK	13020	2026-09-19 11:34	58.44	OK
13021	2026-09-19 11:35	61.09	OK	13022	2026-09-19 11:36	57.42	OK
13023	2026-09-19 11:37	57.70	OK	13024	2026-09-19 11:38	61.68	OK
13025	2026-09-19 11:39	59.19	OK	13026	2026-09-19 11:40	60.87	OK
13027	2026-09-19 11:41	60.09	OK	13028	2026-09-19 11:42	61.08	OK
1302	2026-09-19 11:43	57.81	OK	1303	2026-09-19 11:44	61.03	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status
9			
13031	2026-09-19 11:45	60.92	OK
13033	2026-09-19 11:47	60.96	OK
13035	2026-09-19 11:49	60.34	OK
13037	2026-09-19 11:51	62.65	OK
13039	2026-09-19 11:53	61.26	OK
13041	2026-09-19 11:55	57.26	OK
13043	2026-09-19 11:57	59.76	OK
13045	2026-09-19 11:59	60.88	OK
13047	2026-09-19 12:01	61.68	OK
13049	2026-09-19 12:03	58.75	OK
13051	2026-09-19 12:05	59.65	OK
13053	2026-09-19 12:07	60.80	OK
13055	2026-09-19 12:09	60.15	OK
13057	2026-09-19 12:11	61.65	OK
13059	2026-09-19 12:13	60.69	OK
13061	2026-09-19 12:15	60.95	OK
13063	2026-09-19 12:17	59.60	OK
13065	2026-09-19 12:19	60.38	OK
13067	2026-09-19 12:21	59.61	OK
13069	2026-09-19 12:23	58.24	OK
13071	2026-09-19 12:25	59.64	OK
13073	2026-09-19 12:27	60.15	OK
13075	2026-09-19 12:29	61.19	OK
13077	2026-09-19 12:31	58.87	OK
13079	2026-09-19 12:33	63.44	OK
13081	2026-09-19 12:35	61.49	OK
13083	2026-09-19 12:37	61.63	OK
13085	2026-09-19 12:39	60.32	OK
13087	2026-09-19 12:41	59.72	OK
1308	2026-09-19 12:43	60.22	OK

#	Time (UTC)	Value (°C)	Status
0			
13032	2026-09-19 11:46	60.87	OK
13034	2026-09-19 11:48	60.40	OK
13036	2026-09-19 11:50	59.11	OK
13038	2026-09-19 11:52	58.75	OK
13040	2026-09-19 11:54	62.77	OK
13042	2026-09-19 11:56	58.03	OK
13044	2026-09-19 11:58	58.71	OK
13046	2026-09-19 12:00	59.38	OK
13048	2026-09-19 12:02	58.90	OK
13050	2026-09-19 12:04	59.20	OK
13052	2026-09-19 12:06	59.75	OK
13054	2026-09-19 12:08	60.75	OK
13056	2026-09-19 12:10	60.00	OK
13058	2026-09-19 12:12	58.44	OK
13060	2026-09-19 12:14	61.20	OK
13062	2026-09-19 12:16	59.44	OK
13064	2026-09-19 12:18	57.92	OK
13066	2026-09-19 12:20	61.69	OK
13068	2026-09-19 12:22	61.28	OK
13070	2026-09-19 12:24	60.86	OK
13072	2026-09-19 12:26	60.12	OK
13074	2026-09-19 12:28	59.55	OK
13076	2026-09-19 12:30	57.99	OK
13078	2026-09-19 12:32	57.37	OK
13080	2026-09-19 12:34	61.24	OK
13082	2026-09-19 12:36	60.06	OK
13084	2026-09-19 12:38	60.87	OK
13086	2026-09-19 12:40	59.17	OK
13088	2026-09-19 12:42	61.23	OK
1309	2026-09-19 12:44	61.82	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
13091	2026-09-19 12:45	59.74	OK	13092	2026-09-19 12:46	63.21	OK
13093	2026-09-19 12:47	59.64	OK	13094	2026-09-19 12:48	59.36	OK
13095	2026-09-19 12:49	59.39	OK	13096	2026-09-19 12:50	59.90	OK
13097	2026-09-19 12:51	58.85	OK	13098	2026-09-19 12:52	62.54	OK
13099	2026-09-19 12:53	60.62	OK	13100	2026-09-19 12:54	62.04	OK
13101	2026-09-19 12:55	61.35	OK	13102	2026-09-19 12:56	59.07	OK
13103	2026-09-19 12:57	60.28	OK	13104	2026-09-19 12:58	62.38	OK
13105	2026-09-19 12:59	60.58	OK	13106	2026-09-19 13:00	58.53	OK
13107	2026-09-19 13:01	61.68	OK	13108	2026-09-19 13:02	62.40	OK
13109	2026-09-19 13:03	59.77	OK	13110	2026-09-19 13:04	61.08	OK
13111	2026-09-19 13:05	62.87	OK	13112	2026-09-19 13:06	61.45	OK
13113	2026-09-19 13:07	61.49	OK	13114	2026-09-19 13:08	61.48	OK
13115	2026-09-19 13:09	62.29	OK	13116	2026-09-19 13:10	59.77	OK
13117	2026-09-19 13:11	63.14	OK	13118	2026-09-19 13:12	63.41	OK
13119	2026-09-19 13:13	58.47	OK	13120	2026-09-19 13:14	62.92	OK
13121	2026-09-19 13:15	61.48	OK	13122	2026-09-19 13:16	59.94	OK
13123	2026-09-19 13:17	61.24	OK	13124	2026-09-19 13:18	61.22	OK
13125	2026-09-19 13:19	60.05	OK	13126	2026-09-19 13:20	60.48	OK
13127	2026-09-19 13:21	63.04	OK	13128	2026-09-19 13:22	59.29	OK
13129	2026-09-19 13:23	59.80	OK	13130	2026-09-19 13:24	61.73	OK
13131	2026-09-19 13:25	61.84	OK	13132	2026-09-19 13:26	60.19	OK
13133	2026-09-19 13:27	61.67	OK	13134	2026-09-19 13:28	61.29	OK
13135	2026-09-19 13:29	62.06	OK	13136	2026-09-19 13:30	62.69	OK
13137	2026-09-19 13:31	61.79	OK	13138	2026-09-19 13:32	58.51	OK
13139	2026-09-19 13:33	63.43	OK	13140	2026-09-19 13:34	62.60	OK
13141	2026-09-19 13:35	61.75	OK	13142	2026-09-19 13:36	63.23	OK
13143	2026-09-19 13:37	60.86	OK	13144	2026-09-19 13:38	62.38	OK
13145	2026-09-19 13:39	59.82	OK	13146	2026-09-19 13:40	62.32	OK
13147	2026-09-19 13:41	62.10	OK	13148	2026-09-19 13:42	60.42	OK
1314	2026-09-19 13:43	61.91	OK	1315	2026-09-19 13:44	60.98	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
13151	2026-09-19 13:45	61.34	OK	13152	2026-09-19 13:46	63.59	OK
13153	2026-09-19 13:47	62.63	OK	13154	2026-09-19 13:48	61.56	OK
13155	2026-09-19 13:49	61.97	OK	13156	2026-09-19 13:50	62.62	OK
13157	2026-09-19 13:51	61.14	OK	13158	2026-09-19 13:52	60.18	OK
13159	2026-09-19 13:53	60.03	OK	13160	2026-09-19 13:54	63.41	OK
13161	2026-09-19 13:55	61.46	OK	13162	2026-09-19 13:56	63.31	OK
13163	2026-09-19 13:57	60.77	OK	13164	2026-09-19 13:58	59.88	OK
13165	2026-09-19 13:59	61.53	OK	13166	2026-09-19 14:00	63.06	OK
13167	2026-09-19 14:01	64.34	OK	13168	2026-09-19 14:02	63.21	OK
13169	2026-09-19 14:03	61.08	OK	13170	2026-09-19 14:04	61.54	OK
13171	2026-09-19 14:05	63.64	OK	13172	2026-09-19 14:06	62.62	OK
13173	2026-09-19 14:07	62.46	OK	13174	2026-09-19 14:08	63.46	OK
13175	2026-09-19 14:09	62.66	OK	13176	2026-09-19 14:10	60.88	OK
13177	2026-09-19 14:11	62.49	OK	13178	2026-09-19 14:12	62.83	OK
13179	2026-09-19 14:13	63.72	OK	13180	2026-09-19 14:14	63.29	OK
13181	2026-09-19 14:15	63.07	OK	13182	2026-09-19 14:16	63.39	OK
13183	2026-09-19 14:17	61.63	OK	13184	2026-09-19 14:18	63.23	OK
13185	2026-09-19 14:19	62.72	OK	13186	2026-09-19 14:20	61.91	OK
13187	2026-09-19 14:21	61.74	OK	13188	2026-09-19 14:22	65.21	OK
13189	2026-09-19 14:23	62.97	OK	13190	2026-09-19 14:24	61.64	OK
13191	2026-09-19 14:25	63.79	OK	13192	2026-09-19 14:26	65.18	OK
13193	2026-09-19 14:27	65.16	OK	13194	2026-09-19 14:28	62.56	OK
13195	2026-09-19 14:29	62.70	OK	13196	2026-09-19 14:30	61.19	OK
13197	2026-09-19 14:31	61.29	OK	13198	2026-09-19 14:32	62.88	OK
13199	2026-09-19 14:33	62.83	OK	13200	2026-09-19 14:34	61.84	OK
13201	2026-09-19 14:35	63.15	OK	13202	2026-09-19 14:36	64.22	OK
13203	2026-09-19 14:37	63.10	OK	13204	2026-09-19 14:38	62.71	OK
13205	2026-09-19 14:39	59.68	OK	13206	2026-09-19 14:40	65.35	OK
13207	2026-09-19 14:41	62.13	OK	13208	2026-09-19 14:42	63.23	OK
1320	2026-09-19 14:43	62.23	OK	1321	2026-09-19 14:44	63.98	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
13211	2026-09-19 14:45	60.75	OK	13212	2026-09-19 14:46	62.44	OK
13213	2026-09-19 14:47	62.46	OK	13214	2026-09-19 14:48	64.02	OK
13215	2026-09-19 14:49	64.01	OK	13216	2026-09-19 14:50	62.47	OK
13217	2026-09-19 14:51	63.78	OK	13218	2026-09-19 14:52	63.86	OK
13219	2026-09-19 14:53	61.21	OK	13220	2026-09-19 14:54	63.97	OK
13221	2026-09-19 14:55	63.49	OK	13222	2026-09-19 14:56	63.72	OK
13223	2026-09-19 14:57	62.82	OK	13224	2026-09-19 14:58	62.63	OK
13225	2026-09-19 14:59	62.65	OK	13226	2026-09-19 15:00	64.05	OK
13227	2026-09-19 15:01	63.87	OK	13228	2026-09-19 15:02	64.21	OK
13229	2026-09-19 15:03	62.15	OK	13230	2026-09-19 15:04	61.12	OK
13231	2026-09-19 15:05	60.76	OK	13232	2026-09-19 15:06	64.16	OK
13233	2026-09-19 15:07	61.37	OK	13234	2026-09-19 15:08	62.44	OK
13235	2026-09-19 15:09	63.78	OK	13236	2026-09-19 15:10	62.06	OK
13237	2026-09-19 15:11	61.76	OK	13238	2026-09-19 15:12	64.30	OK
13239	2026-09-19 15:13	64.69	OK	13240	2026-09-19 15:14	65.37	OK
13241	2026-09-19 15:15	61.94	OK	13242	2026-09-19 15:16	63.64	OK
13243	2026-09-19 15:17	63.31	OK	13244	2026-09-19 15:18	63.92	OK
13245	2026-09-19 15:19	63.32	OK	13246	2026-09-19 15:20	63.13	OK
13247	2026-09-19 15:21	65.26	OK	13248	2026-09-19 15:22	64.78	OK
13249	2026-09-19 15:23	65.03	OK	13250	2026-09-19 15:24	65.82	OK
13251	2026-09-19 15:25	65.81	OK	13252	2026-09-19 15:26	65.72	OK
13253	2026-09-19 15:27	62.78	OK	13254	2026-09-19 15:28	63.71	OK
13255	2026-09-19 15:29	62.45	OK	13256	2026-09-19 15:30	62.51	OK
13257	2026-09-19 15:31	63.60	OK	13258	2026-09-19 15:32	65.18	OK
13259	2026-09-19 15:33	65.20	OK	13260	2026-09-19 15:34	65.59	OK
13261	2026-09-19 15:35	65.38	OK	13262	2026-09-19 15:36	61.29	OK
13263	2026-09-19 15:37	62.91	OK	13264	2026-09-19 15:38	62.92	OK
13265	2026-09-19 15:39	66.53	OK	13266	2026-09-19 15:40	62.79	OK
13267	2026-09-19 15:41	64.84	OK	13268	2026-09-19 15:42	66.05	OK
1326	2026-09-19 15:43	63.37	OK	1327	2026-09-19 15:44	64.33	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
13271	2026-09-19 15:45	65.06	OK	13272	2026-09-19 15:46	64.79	OK
13273	2026-09-19 15:47	63.60	OK	13274	2026-09-19 15:48	63.13	OK
13275	2026-09-19 15:49	66.56	OK	13276	2026-09-19 15:50	62.78	OK
13277	2026-09-19 15:51	66.36	OK	13278	2026-09-19 15:52	64.35	OK
13279	2026-09-19 15:53	63.96	OK	13280	2026-09-19 15:54	64.18	OK
13281	2026-09-19 15:55	63.11	OK	13282	2026-09-19 15:56	64.60	OK
13283	2026-09-19 15:57	63.02	OK	13284	2026-09-19 15:58	65.73	OK
13285	2026-09-19 15:59	64.42	OK	13286	2026-09-19 16:00	63.09	OK
13287	2026-09-19 16:01	64.83	OK	13288	2026-09-19 16:02	65.94	OK
13289	2026-09-19 16:03	67.38	OK	13290	2026-09-19 16:04	64.41	OK
13291	2026-09-19 16:05	65.17	OK	13292	2026-09-19 16:06	65.45	OK
13293	2026-09-19 16:07	66.61	OK	13294	2026-09-19 16:08	63.75	OK
13295	2026-09-19 16:09	64.57	OK	13296	2026-09-19 16:10	64.05	OK
13297	2026-09-19 16:11	63.15	OK	13298	2026-09-19 16:12	65.16	OK
13299	2026-09-19 16:13	66.27	OK	13300	2026-09-19 16:14	66.03	OK
13301	2026-09-19 16:15	66.03	OK	13302	2026-09-19 16:16	62.79	OK
13303	2026-09-19 16:17	65.75	OK	13304	2026-09-19 16:18	65.92	OK
13305	2026-09-19 16:19	66.26	OK	13306	2026-09-19 16:20	67.67	OK
13307	2026-09-19 16:21	65.79	OK	13308	2026-09-19 16:22	63.94	OK
13309	2026-09-19 16:23	66.29	OK	13310	2026-09-19 16:24	64.65	OK
13311	2026-09-19 16:25	65.10	OK	13312	2026-09-19 16:26	64.65	OK
13313	2026-09-19 16:27	64.51	OK	13314	2026-09-19 16:28	64.69	OK
13315	2026-09-19 16:29	67.59	OK	13316	2026-09-19 16:30	67.22	OK
13317	2026-09-19 16:31	68.52	OK	13318	2026-09-19 16:32	66.69	OK
13319	2026-09-19 16:33	64.42	OK	13320	2026-09-19 16:34	66.64	OK
13321	2026-09-19 16:35	67.60	OK	13322	2026-09-19 16:36	67.00	OK
13323	2026-09-19 16:37	63.82	OK	13324	2026-09-19 16:38	66.85	OK
13325	2026-09-19 16:39	63.71	OK	13326	2026-09-19 16:40	66.98	OK
13327	2026-09-19 16:41	67.48	OK	13328	2026-09-19 16:42	66.56	OK
1332	2026-09-19 16:43	64.26	OK	1333	2026-09-19 16:44	63.89	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
13331	2026-09-19 16:45	65.17	OK	13332	2026-09-19 16:46	66.45	OK
13333	2026-09-19 16:47	63.47	OK	13334	2026-09-19 16:48	66.03	OK
13335	2026-09-19 16:49	66.02	OK	13336	2026-09-19 16:50	66.74	OK
13337	2026-09-19 16:51	66.14	OK	13338	2026-09-19 16:52	67.33	OK
13339	2026-09-19 16:53	65.35	OK	13340	2026-09-19 16:54	65.46	OK
13341	2026-09-19 16:55	67.02	OK	13342	2026-09-19 16:56	65.91	OK
13343	2026-09-19 16:57	68.22	OK	13344	2026-09-19 16:58	65.51	OK
13345	2026-09-19 16:59	66.29	OK	13346	2026-09-19 17:00	66.04	OK
13347	2026-09-19 17:01	69.22	OK	13348	2026-09-19 17:02	66.51	OK
13349	2026-09-19 17:03	67.39	OK	13350	2026-09-19 17:04	66.66	OK
13351	2026-09-19 17:05	65.81	OK	13352	2026-09-19 17:06	66.76	OK
13353	2026-09-19 17:07	64.42	OK	13354	2026-09-19 17:08	67.34	OK
13355	2026-09-19 17:09	65.98	OK	13356	2026-09-19 17:10	67.36	OK
13357	2026-09-19 17:11	66.68	OK	13358	2026-09-19 17:12	65.60	OK
13359	2026-09-19 17:13	65.77	OK	13360	2026-09-19 17:14	67.13	OK
13361	2026-09-19 17:15	65.12	OK	13362	2026-09-19 17:16	67.26	OK
13363	2026-09-19 17:17	66.62	OK	13364	2026-09-19 17:18	68.42	OK
13365	2026-09-19 17:19	69.50	OK	13366	2026-09-19 17:20	66.89	OK
13367	2026-09-19 17:21	66.69	OK	13368	2026-09-19 17:22	69.23	OK
13369	2026-09-19 17:23	65.91	OK	13370	2026-09-19 17:24	65.70	OK
13371	2026-09-19 17:25	65.99	OK	13372	2026-09-19 17:26	66.82	OK
13373	2026-09-19 17:27	67.34	OK	13374	2026-09-19 17:28	68.33	OK
13375	2026-09-19 17:29	67.18	OK	13376	2026-09-19 17:30	67.10	OK
13377	2026-09-19 17:31	69.41	OK	13378	2026-09-19 17:32	69.58	OK
13379	2026-09-19 17:33	66.95	OK	13380	2026-09-19 17:34	64.08	OK
13381	2026-09-19 17:35	70.53	OK	13382	2026-09-19 17:36	69.85	OK
13383	2026-09-19 17:37	68.96	OK	13384	2026-09-19 17:38	70.56	OK
13385	2026-09-19 17:39	66.93	OK	13386	2026-09-19 17:40	68.11	OK
13387	2026-09-19 17:41	66.41	OK	13388	2026-09-19 17:42	66.74	OK
1338	2026-09-19 17:43	67.70	OK	1339	2026-09-19 17:44	66.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
13391	2026-09-19 17:45	67.47	OK	13392	2026-09-19 17:46	66.07	OK
13393	2026-09-19 17:47	68.39	OK	13394	2026-09-19 17:48	69.66	OK
13395	2026-09-19 17:49	65.22	OK	13396	2026-09-19 17:50	67.88	OK
13397	2026-09-19 17:51	67.68	OK	13398	2026-09-19 17:52	68.09	OK
13399	2026-09-19 17:53	68.01	OK	13400	2026-09-19 17:54	66.35	OK
13401	2026-09-19 17:55	69.46	OK	13402	2026-09-19 17:56	68.81	OK
13403	2026-09-19 17:57	66.97	OK	13404	2026-09-19 17:58	65.27	OK
13405	2026-09-19 17:59	69.82	OK	13406	2026-09-19 18:00	68.96	OK
13407	2026-09-19 18:01	68.13	OK	13408	2026-09-19 18:02	69.63	OK
13409	2026-09-19 18:03	67.22	OK	13410	2026-09-19 18:04	65.97	OK
13411	2026-09-19 18:05	66.36	OK	13412	2026-09-19 18:06	69.22	OK
13413	2026-09-19 18:07	66.79	OK	13414	2026-09-19 18:08	65.83	OK
13415	2026-09-19 18:09	68.80	OK	13416	2026-09-19 18:10	68.60	OK
13417	2026-09-19 18:11	68.91	OK	13418	2026-09-19 18:12	69.59	OK
13419	2026-09-19 18:13	69.90	OK	13420	2026-09-19 18:14	69.96	OK
13421	2026-09-19 18:15	70.90	OK	13422	2026-09-19 18:16	69.75	OK
13423	2026-09-19 18:17	70.90	OK	13424	2026-09-19 18:18	68.51	OK
13425	2026-09-19 18:19	71.84	OK	13426	2026-09-19 18:20	69.00	OK
13427	2026-09-19 18:21	70.98	OK	13428	2026-09-19 18:22	71.14	OK
13429	2026-09-19 18:23	67.82	OK	13430	2026-09-19 18:24	69.50	OK
13431	2026-09-19 18:25	69.64	OK	13432	2026-09-19 18:26	70.96	OK
13433	2026-09-19 18:27	69.57	OK	13434	2026-09-19 18:28	69.14	OK
13435	2026-09-19 18:29	68.13	OK	13436	2026-09-19 18:30	68.96	OK
13437	2026-09-19 18:31	66.75	OK	13438	2026-09-19 18:32	69.97	OK
13439	2026-09-19 18:33	69.27	OK	13440	2026-09-19 18:34	68.92	OK
13441	2026-09-19 18:35	67.28	OK	13442	2026-09-19 18:36	68.23	OK
13443	2026-09-19 18:37	70.96	OK	13444	2026-09-19 18:38	69.08	OK
13445	2026-09-19 18:39	71.18	OK	13446	2026-09-19 18:40	66.77	OK
13447	2026-09-19 18:41	68.12	OK	13448	2026-09-19 18:42	69.51	OK
13449	2026-09-19 18:43	67.56	OK	13450	2026-09-19 18:44	70.77	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
13451	2026-09-19 18:45	68.93	OK	13452	2026-09-19 18:46	68.45	OK
13453	2026-09-19 18:47	69.85	OK	13454	2026-09-19 18:48	70.35	OK
13455	2026-09-19 18:49	69.32	OK	13456	2026-09-19 18:50	68.64	OK
13457	2026-09-19 18:51	69.03	OK	13458	2026-09-19 18:52	70.60	OK
13459	2026-09-19 18:53	68.53	OK	13460	2026-09-19 18:54	72.61	OK
13461	2026-09-19 18:55	70.23	OK	13462	2026-09-19 18:56	67.55	OK
13463	2026-09-19 18:57	69.37	OK	13464	2026-09-19 18:58	69.59	OK
13465	2026-09-19 18:59	71.36	OK	13466	2026-09-19 19:00	70.44	OK
13467	2026-09-19 19:01	68.01	OK	13468	2026-09-19 19:02	72.64	OK
13469	2026-09-19 19:03	69.81	OK	13470	2026-09-19 19:04	67.68	OK
13471	2026-09-19 19:05	71.01	OK	13472	2026-09-19 19:06	68.93	OK
13473	2026-09-19 19:07	68.50	OK	13474	2026-09-19 19:08	66.82	OK
13475	2026-09-19 19:09	69.58	OK	13476	2026-09-19 19:10	71.02	OK
13477	2026-09-19 19:11	67.74	OK	13478	2026-09-19 19:12	70.47	OK
13479	2026-09-19 19:13	70.98	OK	13480	2026-09-19 19:14	72.72	OK
13481	2026-09-19 19:15	71.80	OK	13482	2026-09-19 19:16	71.78	OK
13483	2026-09-19 19:17	71.94	OK	13484	2026-09-19 19:18	68.42	OK
13485	2026-09-19 19:19	69.89	OK	13486	2026-09-19 19:20	71.21	OK
13487	2026-09-19 19:21	71.62	OK	13488	2026-09-19 19:22	69.52	OK
13489	2026-09-19 19:23	67.60	OK	13490	2026-09-19 19:24	72.36	OK
13491	2026-09-19 19:25	71.18	OK	13492	2026-09-19 19:26	72.99	OK
13493	2026-09-19 19:27	70.81	OK	13494	2026-09-19 19:28	69.42	OK
13495	2026-09-19 19:29	69.82	OK	13496	2026-09-19 19:30	71.57	OK
13497	2026-09-19 19:31	70.67	OK	13498	2026-09-19 19:32	71.38	OK
13499	2026-09-19 19:33	71.31	OK	13500	2026-09-19 19:34	70.19	OK
13501	2026-09-19 19:35	72.08	OK	13502	2026-09-19 19:36	70.67	OK
13503	2026-09-19 19:37	72.25	OK	13504	2026-09-19 19:38	71.52	OK
13505	2026-09-19 19:39	71.47	OK	13506	2026-09-19 19:40	69.07	OK
13507	2026-09-19 19:41	71.44	OK	13508	2026-09-19 19:42	70.61	OK
13509	2026-09-19 19:43	71.36	OK	13510	2026-09-19 19:44	67.69	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
13511	2026-09-19 19:45	71.04	OK	13512	2026-09-19 19:46	68.51	OK
13513	2026-09-19 19:47	70.57	OK	13514	2026-09-19 19:48	70.76	OK
13515	2026-09-19 19:49	71.53	OK	13516	2026-09-19 19:50	71.79	OK
13517	2026-09-19 19:51	71.55	OK	13518	2026-09-19 19:52	70.47	OK
13519	2026-09-19 19:53	71.58	OK	13520	2026-09-19 19:54	69.58	OK
13521	2026-09-19 19:55	67.79	OK	13522	2026-09-19 19:56	72.02	OK
13523	2026-09-19 19:57	72.09	OK	13524	2026-09-19 19:58	70.25	OK
13525	2026-09-19 19:59	71.62	OK	13526	2026-09-19 20:00	71.40	OK
13527	2026-09-19 20:01	73.05	OK	13528	2026-09-19 20:02	71.30	OK
13529	2026-09-19 20:03	68.68	OK	13530	2026-09-19 20:04	71.74	OK
13531	2026-09-19 20:05	71.20	OK	13532	2026-09-19 20:06	72.68	OK
13533	2026-09-19 20:07	69.95	OK	13534	2026-09-19 20:08	71.11	OK
13535	2026-09-19 20:09	70.34	OK	13536	2026-09-19 20:10	72.57	OK
13537	2026-09-19 20:11	69.44	OK	13538	2026-09-19 20:12	73.41	OK
13539	2026-09-19 20:13	71.79	OK	13540	2026-09-19 20:14	69.33	OK
13541	2026-09-19 20:15	71.40	OK	13542	2026-09-19 20:16	68.41	OK
13543	2026-09-19 20:17	70.04	OK	13544	2026-09-19 20:18	70.47	OK
13545	2026-09-19 20:19	73.18	OK	13546	2026-09-19 20:20	72.76	OK
13547	2026-09-19 20:21	73.71	OK	13548	2026-09-19 20:22	72.18	OK
13549	2026-09-19 20:23	70.59	OK	13550	2026-09-19 20:24	71.55	OK
13551	2026-09-19 20:25	74.13	OK	13552	2026-09-19 20:26	72.19	OK
13553	2026-09-19 20:27	71.11	OK	13554	2026-09-19 20:28	73.17	OK
13555	2026-09-19 20:29	70.82	OK	13556	2026-09-19 20:30	73.65	OK
13557	2026-09-19 20:31	73.59	OK	13558	2026-09-19 20:32	72.67	OK
13559	2026-09-19 20:33	73.53	OK	13560	2026-09-19 20:34	71.68	OK
13561	2026-09-19 20:35	73.79	OK	13562	2026-09-19 20:36	70.98	OK
13563	2026-09-19 20:37	73.05	OK	13564	2026-09-19 20:38	72.21	OK
13565	2026-09-19 20:39	71.66	OK	13566	2026-09-19 20:40	73.36	OK
13567	2026-09-19 20:41	73.14	OK	13568	2026-09-19 20:42	73.17	OK
1356	2026-09-19 20:43	70.75	OK	1357	2026-09-19 20:44	74.47	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
13571	2026-09-19 20:45	72.52	OK	13572	2026-09-19 20:46	71.71	OK
13573	2026-09-19 20:47	70.78	OK	13574	2026-09-19 20:48	73.22	OK
13575	2026-09-19 20:49	71.94	OK	13576	2026-09-19 20:50	72.08	OK
13577	2026-09-19 20:51	71.17	OK	13578	2026-09-19 20:52	72.04	OK
13579	2026-09-19 20:53	69.14	OK	13580	2026-09-19 20:54	72.34	OK
13581	2026-09-19 20:55	71.84	OK	13582	2026-09-19 20:56	71.50	OK
13583	2026-09-19 20:57	72.44	OK	13584	2026-09-19 20:58	72.08	OK
13585	2026-09-19 20:59	71.09	OK	13586	2026-09-19 21:00	74.82	OK
13587	2026-09-19 21:01	71.81	OK	13588	2026-09-19 21:02	72.25	OK
13589	2026-09-19 21:03	69.67	OK	13590	2026-09-19 21:04	72.53	OK
13591	2026-09-19 21:05	69.42	OK	13592	2026-09-19 21:06	73.01	OK
13593	2026-09-19 21:07	72.23	OK	13594	2026-09-19 21:08	70.76	OK
13595	2026-09-19 21:09	72.42	OK	13596	2026-09-19 21:10	73.25	OK
13597	2026-09-19 21:11	73.39	OK	13598	2026-09-19 21:12	71.21	OK
13599	2026-09-19 21:13	71.57	OK	13600	2026-09-19 21:14	72.87	OK
13601	2026-09-19 21:15	70.83	OK	13602	2026-09-19 21:16	70.42	OK
13603	2026-09-19 21:17	72.88	OK	13604	2026-09-19 21:18	70.30	OK
13605	2026-09-19 21:19	73.93	OK	13606	2026-09-19 21:20	73.65	OK
13607	2026-09-19 21:21	70.75	OK	13608	2026-09-19 21:22	71.98	OK
13609	2026-09-19 21:23	73.02	OK	13610	2026-09-19 21:24	71.88	OK
13611	2026-09-19 21:25	70.43	OK	13612	2026-09-19 21:26	74.70	OK
13613	2026-09-19 21:27	74.49	OK	13614	2026-09-19 21:28	71.26	OK
13615	2026-09-19 21:29	73.39	OK	13616	2026-09-19 21:30	69.79	OK
13617	2026-09-19 21:31	74.71	OK	13618	2026-09-19 21:32	73.35	OK
13619	2026-09-19 21:33	74.04	OK	13620	2026-09-19 21:34	72.16	OK
13621	2026-09-19 21:35	72.70	OK	13622	2026-09-19 21:36	73.77	OK
13623	2026-09-19 21:37	71.73	OK	13624	2026-09-19 21:38	72.44	OK
13625	2026-09-19 21:39	71.55	OK	13626	2026-09-19 21:40	73.51	OK
13627	2026-09-19 21:41	73.98	OK	13628	2026-09-19 21:42	73.61	OK
1362	2026-09-19 21:43	73.76	OK	1363	2026-09-19 21:44	73.16	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
13631	2026-09-19 21:45	74.24	OK	13632	2026-09-19 21:46	73.68	OK
13633	2026-09-19 21:47	73.78	OK	13634	2026-09-19 21:48	72.84	OK
13635	2026-09-19 21:49	71.77	OK	13636	2026-09-19 21:50	73.18	OK
13637	2026-09-19 21:51	73.15	OK	13638	2026-09-19 21:52	74.37	OK
13639	2026-09-19 21:53	72.13	OK	13640	2026-09-19 21:54	73.90	OK
13641	2026-09-19 21:55	73.02	OK	13642	2026-09-19 21:56	71.78	OK
13643	2026-09-19 21:57	69.75	OK	13644	2026-09-19 21:58	72.27	OK
13645	2026-09-19 21:59	73.23	OK	13646	2026-09-19 22:00	73.67	OK
13647	2026-09-19 22:01	71.60	OK	13648	2026-09-19 22:02	73.11	OK
13649	2026-09-19 22:03	72.10	OK	13650	2026-09-19 22:04	73.85	OK
13651	2026-09-19 22:05	71.62	OK	13652	2026-09-19 22:06	70.18	OK
13653	2026-09-19 22:07	74.26	OK	13654	2026-09-19 22:08	71.95	OK
13655	2026-09-19 22:09	71.54	OK	13656	2026-09-19 22:10	72.15	OK
13657	2026-09-19 22:11	71.78	OK	13658	2026-09-19 22:12	72.27	OK
13659	2026-09-19 22:13	71.64	OK	13660	2026-09-19 22:14	72.94	OK
13661	2026-09-19 22:15	73.68	OK	13662	2026-09-19 22:16	72.32	OK
13663	2026-09-19 22:17	72.94	OK	13664	2026-09-19 22:18	70.98	OK
13665	2026-09-19 22:19	73.24	OK	13666	2026-09-19 22:20	72.47	OK
13667	2026-09-19 22:21	71.85	OK	13668	2026-09-19 22:22	73.49	OK
13669	2026-09-19 22:23	73.33	OK	13670	2026-09-19 22:24	71.82	OK
13671	2026-09-19 22:25	70.66	OK	13672	2026-09-19 22:26	73.35	OK
13673	2026-09-19 22:27	71.59	OK	13674	2026-09-19 22:28	74.07	OK
13675	2026-09-19 22:29	72.06	OK	13676	2026-09-19 22:30	71.36	OK
13677	2026-09-19 22:31	70.43	OK	13678	2026-09-19 22:32	73.08	OK
13679	2026-09-19 22:33	73.49	OK	13680	2026-09-19 22:34	73.76	OK
13681	2026-09-19 22:35	73.29	OK	13682	2026-09-19 22:36	73.11	OK
13683	2026-09-19 22:37	71.11	OK	13684	2026-09-19 22:38	73.48	OK
13685	2026-09-19 22:39	74.52	OK	13686	2026-09-19 22:40	71.78	OK
13687	2026-09-19 22:41	74.24	OK	13688	2026-09-19 22:42	70.52	OK
1368	2026-09-19 22:43	74.76	OK	1369	2026-09-19 22:44	71.91	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
13691	2026-09-19 22:45	73.28	OK	13692	2026-09-19 22:46	74.87	OK
13693	2026-09-19 22:47	72.89	OK	13694	2026-09-19 22:48	74.52	OK
13695	2026-09-19 22:49	74.46	OK	13696	2026-09-19 22:50	72.18	OK
13697	2026-09-19 22:51	73.95	OK	13698	2026-09-19 22:52	73.25	OK
13699	2026-09-19 22:53	71.56	OK	13700	2026-09-19 22:54	72.70	OK
13701	2026-09-19 22:55	71.64	OK	13702	2026-09-19 22:56	74.30	OK
13703	2026-09-19 22:57	73.11	OK	13704	2026-09-19 22:58	71.67	OK
13705	2026-09-19 22:59	71.30	OK	13706	2026-09-19 23:00	69.64	OK
13707	2026-09-19 23:01	74.01	OK	13708	2026-09-19 23:02	71.17	OK
13709	2026-09-19 23:03	71.41	OK	13710	2026-09-19 23:04	72.79	OK
13711	2026-09-19 23:05	72.61	OK	13712	2026-09-19 23:06	73.02	OK
13713	2026-09-19 23:07	73.68	OK	13714	2026-09-19 23:08	72.40	OK
13715	2026-09-19 23:09	73.78	OK	13716	2026-09-19 23:10	72.28	OK
13717	2026-09-19 23:11	69.80	OK	13718	2026-09-19 23:12	73.54	OK
13719	2026-09-19 23:13	70.64	OK	13720	2026-09-19 23:14	72.06	OK
13721	2026-09-19 23:15	75.29	OK	13722	2026-09-19 23:16	70.92	OK
13723	2026-09-19 23:17	72.56	OK	13724	2026-09-19 23:18	71.39	OK
13725	2026-09-19 23:19	74.00	OK	13726	2026-09-19 23:20	72.64	OK
13727	2026-09-19 23:21	72.56	OK	13728	2026-09-19 23:22	71.90	OK
13729	2026-09-19 23:23	74.03	OK	13730	2026-09-19 23:24	73.73	OK
13731	2026-09-19 23:25	71.49	OK	13732	2026-09-19 23:26	74.77	OK
13733	2026-09-19 23:27	73.47	OK	13734	2026-09-19 23:28	74.04	OK
13735	2026-09-19 23:29	71.72	OK	13736	2026-09-19 23:30	71.63	OK
13737	2026-09-19 23:31	71.91	OK	13738	2026-09-19 23:32	71.72	OK
13739	2026-09-19 23:33	74.08	OK	13740	2026-09-19 23:34	74.30	OK
13741	2026-09-19 23:35	71.24	OK	13742	2026-09-19 23:36	71.53	OK
13743	2026-09-19 23:37	71.57	OK	13744	2026-09-19 23:38	72.89	OK
13745	2026-09-19 23:39	71.07	OK	13746	2026-09-19 23:40	71.18	OK
13747	2026-09-19 23:41	73.15	OK	13748	2026-09-19 23:42	71.86	OK
1374	2026-09-19 23:43	73.14	OK	1375	2026-09-19 23:44	72.49	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
13751	2026-09-19 23:45	75.19	OK	13752	2026-09-19 23:46	74.41	OK
13753	2026-09-19 23:47	71.52	OK	13754	2026-09-19 23:48	71.18	OK
13755	2026-09-19 23:49	72.37	OK	13756	2026-09-19 23:50	74.48	OK
13757	2026-09-19 23:51	71.53	OK	13758	2026-09-19 23:52	71.17	OK
13759	2026-09-19 23:53	70.58	OK	13760	2026-09-19 23:54	73.76	OK
13761	2026-09-19 23:55	72.70	OK	13762	2026-09-19 23:56	70.61	OK
13763	2026-09-19 23:57	71.41	OK	13764	2026-09-19 23:58	70.24	OK
13765	2026-09-19 23:59	72.57	OK	13766	2026-09-20 00:00	72.83	OK
13767	2026-09-20 00:01	72.32	OK	13768	2026-09-20 00:02	73.13	OK
13769	2026-09-20 00:03	72.44	OK	13770	2026-09-20 00:04	71.65	OK
13771	2026-09-20 00:05	72.59	OK	13772	2026-09-20 00:06	72.13	OK
13773	2026-09-20 00:07	72.77	OK	13774	2026-09-20 00:08	74.10	OK
13775	2026-09-20 00:09	72.11	OK	13776	2026-09-20 00:10	73.89	OK
13777	2026-09-20 00:11	72.37	OK	13778	2026-09-20 00:12	72.62	OK
13779	2026-09-20 00:13	71.46	OK	13780	2026-09-20 00:14	73.93	OK
13781	2026-09-20 00:15	72.71	OK	13782	2026-09-20 00:16	73.26	OK
13783	2026-09-20 00:17	72.07	OK	13784	2026-09-20 00:18	71.38	OK
13785	2026-09-20 00:19	72.21	OK	13786	2026-09-20 00:20	72.78	OK
13787	2026-09-20 00:21	74.32	OK	13788	2026-09-20 00:22	70.01	OK
13789	2026-09-20 00:23	74.42	OK	13790	2026-09-20 00:24	71.55	OK
13791	2026-09-20 00:25	73.44	OK	13792	2026-09-20 00:26	70.36	OK
13793	2026-09-20 00:27	71.84	OK	13794	2026-09-20 00:28	70.91	OK
13795	2026-09-20 00:29	69.56	OK	13796	2026-09-20 00:30	70.39	OK
13797	2026-09-20 00:31	71.55	OK	13798	2026-09-20 00:32	73.20	OK
13799	2026-09-20 00:33	74.37	OK	13800	2026-09-20 00:34	73.38	OK
13801	2026-09-20 00:35	72.59	OK	13802	2026-09-20 00:36	69.63	OK
13803	2026-09-20 00:37	74.35	OK	13804	2026-09-20 00:38	71.65	OK
13805	2026-09-20 00:39	74.46	OK	13806	2026-09-20 00:40	70.66	OK
13807	2026-09-20 00:41	71.00	OK	13808	2026-09-20 00:42	71.50	OK
1380	2026-09-20 00:43	71.30	OK	1381	2026-09-20 00:44	73.78	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
13811	2026-09-20 00:45	72.77	OK	13812	2026-09-20 00:46	70.50	OK
13813	2026-09-20 00:47	71.57	OK	13814	2026-09-20 00:48	72.99	OK
13815	2026-09-20 00:49	71.29	OK	13816	2026-09-20 00:50	69.15	OK
13817	2026-09-20 00:51	69.90	OK	13818	2026-09-20 00:52	74.04	OK
13819	2026-09-20 00:53	70.56	OK	13820	2026-09-20 00:54	70.33	OK
13821	2026-09-20 00:55	70.60	OK	13822	2026-09-20 00:56	70.47	OK
13823	2026-09-20 00:57	73.53	OK	13824	2026-09-20 00:58	71.62	OK
13825	2026-09-20 00:59	73.53	OK	13826	2026-09-20 01:00	71.82	OK
13827	2026-09-20 01:01	69.02	OK	13828	2026-09-20 01:02	71.30	OK
13829	2026-09-20 01:03	72.14	OK	13830	2026-09-20 01:04	69.84	OK
13831	2026-09-20 01:05	71.13	OK	13832	2026-09-20 01:06	72.02	OK
13833	2026-09-20 01:07	71.55	OK	13834	2026-09-20 01:08	69.43	OK
13835	2026-09-20 01:09	71.26	OK	13836	2026-09-20 01:10	70.40	OK
13837	2026-09-20 01:11	70.68	OK	13838	2026-09-20 01:12	70.89	OK
13839	2026-09-20 01:13	70.53	OK	13840	2026-09-20 01:14	70.03	OK
13841	2026-09-20 01:15	70.36	OK	13842	2026-09-20 01:16	69.45	OK
13843	2026-09-20 01:17	70.99	OK	13844	2026-09-20 01:18	70.76	OK
13845	2026-09-20 01:19	68.26	OK	13846	2026-09-20 01:20	72.12	OK
13847	2026-09-20 01:21	70.02	OK	13848	2026-09-20 01:22	70.43	OK
13849	2026-09-20 01:23	73.40	OK	13850	2026-09-20 01:24	72.96	OK
13851	2026-09-20 01:25	73.97	OK	13852	2026-09-20 01:26	69.07	OK
13853	2026-09-20 01:27	72.86	OK	13854	2026-09-20 01:28	70.30	OK
13855	2026-09-20 01:29	70.08	OK	13856	2026-09-20 01:30	69.35	OK
13857	2026-09-20 01:31	72.64	OK	13858	2026-09-20 01:32	73.17	OK
13859	2026-09-20 01:33	70.78	OK	13860	2026-09-20 01:34	69.90	OK
13861	2026-09-20 01:35	70.76	OK	13862	2026-09-20 01:36	72.32	OK
13863	2026-09-20 01:37	69.55	OK	13864	2026-09-20 01:38	71.68	OK
13865	2026-09-20 01:39	70.13	OK	13866	2026-09-20 01:40	70.42	OK
13867	2026-09-20 01:41	71.94	OK	13868	2026-09-20 01:42	71.27	OK
1386	2026-09-20 01:43	68.79	OK	1387	2026-09-20 01:44	69.59	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
13871	2026-09-20 01:45	71.88	OK	13872	2026-09-20 01:46	72.65	OK
13873	2026-09-20 01:47	67.62	OK	13874	2026-09-20 01:48	71.78	OK
13875	2026-09-20 01:49	69.03	OK	13876	2026-09-20 01:50	69.21	OK
13877	2026-09-20 01:51	69.67	OK	13878	2026-09-20 01:52	69.67	OK
13879	2026-09-20 01:53	71.03	OK	13880	2026-09-20 01:54	69.20	OK
13881	2026-09-20 01:55	69.52	OK	13882	2026-09-20 01:56	70.77	OK
13883	2026-09-20 01:57	72.03	OK	13884	2026-09-20 01:58	69.40	OK
13885	2026-09-20 01:59	72.93	OK	13886	2026-09-20 02:00	70.51	OK
13887	2026-09-20 02:01	68.54	OK	13888	2026-09-20 02:02	71.58	OK
13889	2026-09-20 02:03	68.68	OK	13890	2026-09-20 02:04	68.86	OK
13891	2026-09-20 02:05	70.97	OK	13892	2026-09-20 02:06	70.52	OK
13893	2026-09-20 02:07	70.76	OK	13894	2026-09-20 02:08	68.26	OK
13895	2026-09-20 02:09	70.59	OK	13896	2026-09-20 02:10	70.97	OK
13897	2026-09-20 02:11	69.37	OK	13898	2026-09-20 02:12	69.98	OK
13899	2026-09-20 02:13	70.75	OK	13900	2026-09-20 02:14	68.86	OK
13901	2026-09-20 02:15	68.93	OK	13902	2026-09-20 02:16	70.27	OK
13903	2026-09-20 02:17	68.39	OK	13904	2026-09-20 02:18	70.70	OK
13905	2026-09-20 02:19	69.95	OK	13906	2026-09-20 02:20	72.10	OK
13907	2026-09-20 02:21	67.79	OK	13908	2026-09-20 02:22	71.31	OK
13909	2026-09-20 02:23	70.65	OK	13910	2026-09-20 02:24	71.02	OK
13911	2026-09-20 02:25	69.86	OK	13912	2026-09-20 02:26	69.65	OK
13913	2026-09-20 02:27	68.45	OK	13914	2026-09-20 02:28	68.37	OK
13915	2026-09-20 02:29	67.93	OK	13916	2026-09-20 02:30	68.99	OK
13917	2026-09-20 02:31	69.60	OK	13918	2026-09-20 02:32	69.66	OK
13919	2026-09-20 02:33	70.35	OK	13920	2026-09-20 02:34	70.25	OK
13921	2026-09-20 02:35	68.15	OK	13922	2026-09-20 02:36	67.29	OK
13923	2026-09-20 02:37	69.30	OK	13924	2026-09-20 02:38	69.83	OK
13925	2026-09-20 02:39	70.61	OK	13926	2026-09-20 02:40	71.78	OK
13927	2026-09-20 02:41	69.08	OK	13928	2026-09-20 02:42	69.03	OK
13929	2026-09-20 02:43	68.43	OK	1393	2026-09-20 02:44	70.08	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
13931	2026-09-20 02:45	68.37	OK	13932	2026-09-20 02:46	69.62	OK
13933	2026-09-20 02:47	68.39	OK	13934	2026-09-20 02:48	69.05	OK
13935	2026-09-20 02:49	69.80	OK	13936	2026-09-20 02:50	68.46	OK
13937	2026-09-20 02:51	68.19	OK	13938	2026-09-20 02:52	70.01	OK
13939	2026-09-20 02:53	69.33	OK	13940	2026-09-20 02:54	70.05	OK
13941	2026-09-20 02:55	69.62	OK	13942	2026-09-20 02:56	69.52	OK
13943	2026-09-20 02:57	68.17	OK	13944	2026-09-20 02:58	68.91	OK
13945	2026-09-20 02:59	69.12	OK	13946	2026-09-20 03:00	68.36	OK
13947	2026-09-20 03:01	69.25	OK	13948	2026-09-20 03:02	70.77	OK
13949	2026-09-20 03:03	68.01	OK	13950	2026-09-20 03:04	70.49	OK
13951	2026-09-20 03:05	71.29	OK	13952	2026-09-20 03:06	70.45	OK
13953	2026-09-20 03:07	67.20	OK	13954	2026-09-20 03:08	68.29	OK
13955	2026-09-20 03:09	71.29	OK	13956	2026-09-20 03:10	67.74	OK
13957	2026-09-20 03:11	68.89	OK	13958	2026-09-20 03:12	68.71	OK
13959	2026-09-20 03:13	68.97	OK	13960	2026-09-20 03:14	68.34	OK
13961	2026-09-20 03:15	69.25	OK	13962	2026-09-20 03:16	67.38	OK
13963	2026-09-20 03:17	68.17	OK	13964	2026-09-20 03:18	68.18	OK
13965	2026-09-20 03:19	68.33	OK	13966	2026-09-20 03:20	69.10	OK
13967	2026-09-20 03:21	68.63	OK	13968	2026-09-20 03:22	66.60	OK
13969	2026-09-20 03:23	67.26	OK	13970	2026-09-20 03:24	67.44	OK
13971	2026-09-20 03:25	68.76	OK	13972	2026-09-20 03:26	66.91	OK
13973	2026-09-20 03:27	65.85	OK	13974	2026-09-20 03:28	67.90	OK
13975	2026-09-20 03:29	66.26	OK	13976	2026-09-20 03:30	68.92	OK
13977	2026-09-20 03:31	70.17	OK	13978	2026-09-20 03:32	67.25	OK
13979	2026-09-20 03:33	67.63	OK	13980	2026-09-20 03:34	68.40	OK
13981	2026-09-20 03:35	67.49	OK	13982	2026-09-20 03:36	69.14	OK
13983	2026-09-20 03:37	66.65	OK	13984	2026-09-20 03:38	65.59	OK
13985	2026-09-20 03:39	66.93	OK	13986	2026-09-20 03:40	67.37	OK
13987	2026-09-20 03:41	67.87	OK	13988	2026-09-20 03:42	70.28	OK
1398	2026-09-20 03:43	70.15	OK	1399	2026-09-20 03:44	69.61	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
13991	2026-09-20 03:45	68.00	OK	13992	2026-09-20 03:46	67.27	OK
13993	2026-09-20 03:47	67.72	OK	13994	2026-09-20 03:48	68.19	OK
13995	2026-09-20 03:49	67.00	OK	13996	2026-09-20 03:50	68.36	OK
13997	2026-09-20 03:51	68.58	OK	13998	2026-09-20 03:52	67.34	OK
13999	2026-09-20 03:53	70.02	OK	14000	2026-09-20 03:54	68.58	OK
14001	2026-09-20 03:55	65.88	OK	14002	2026-09-20 03:56	69.65	OK
14003	2026-09-20 03:57	69.04	OK	14004	2026-09-20 03:58	66.79	OK
14005	2026-09-20 03:59	66.90	OK	14006	2026-09-20 04:00	67.50	OK
14007	2026-09-20 04:01	65.10	OK	14008	2026-09-20 04:02	68.05	OK
14009	2026-09-20 04:03	67.13	OK	14010	2026-09-20 04:04	65.95	OK
14011	2026-09-20 04:05	66.16	OK	14012	2026-09-20 04:06	67.15	OK
14013	2026-09-20 04:07	67.56	OK	14014	2026-09-20 04:08	66.52	OK
14015	2026-09-20 04:09	66.48	OK	14016	2026-09-20 04:10	67.24	OK
14017	2026-09-20 04:11	66.59	OK	14018	2026-09-20 04:12	68.80	OK
14019	2026-09-20 04:13	68.67	OK	14020	2026-09-20 04:14	65.70	OK
14021	2026-09-20 04:15	67.48	OK	14022	2026-09-20 04:16	64.46	OK
14023	2026-09-20 04:17	67.01	OK	14024	2026-09-20 04:18	68.48	OK
14025	2026-09-20 04:19	66.55	OK	14026	2026-09-20 04:20	67.53	OK
14027	2026-09-20 04:21	67.43	OK	14028	2026-09-20 04:22	66.63	OK
14029	2026-09-20 04:23	65.52	OK	14030	2026-09-20 04:24	65.12	OK
14031	2026-09-20 04:25	69.20	OK	14032	2026-09-20 04:26	67.15	OK
14033	2026-09-20 04:27	65.71	OK	14034	2026-09-20 04:28	65.48	OK
14035	2026-09-20 04:29	65.56	OK	14036	2026-09-20 04:30	65.10	OK
14037	2026-09-20 04:31	66.16	OK	14038	2026-09-20 04:32	66.53	OK
14039	2026-09-20 04:33	65.43	OK	14040	2026-09-20 04:34	66.68	OK
14041	2026-09-20 04:35	66.30	OK	14042	2026-09-20 04:36	67.15	OK
14043	2026-09-20 04:37	64.13	OK	14044	2026-09-20 04:38	66.36	OK
14045	2026-09-20 04:39	66.45	OK	14046	2026-09-20 04:40	66.51	OK
14047	2026-09-20 04:41	67.19	OK	14048	2026-09-20 04:42	64.78	OK
1404	2026-09-20 04:43	67.67	OK	1405	2026-09-20 04:44	67.92	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
14051	2026-09-20 04:45	65.60	OK	14052	2026-09-20 04:46	65.93	OK
14053	2026-09-20 04:47	66.84	OK	14054	2026-09-20 04:48	64.50	OK
14055	2026-09-20 04:49	65.42	OK	14056	2026-09-20 04:50	66.04	OK
14057	2026-09-20 04:51	66.19	OK	14058	2026-09-20 04:52	65.78	OK
14059	2026-09-20 04:53	64.86	OK	14060	2026-09-20 04:54	67.01	OK
14061	2026-09-20 04:55	64.62	OK	14062	2026-09-20 04:56	63.92	OK
14063	2026-09-20 04:57	64.99	OK	14064	2026-09-20 04:58	64.61	OK
14065	2026-09-20 04:59	63.41	OK	14066	2026-09-20 05:00	65.84	OK
14067	2026-09-20 05:01	64.17	OK	14068	2026-09-20 05:02	65.64	OK
14069	2026-09-20 05:03	63.62	OK	14070	2026-09-20 05:04	62.71	OK
14071	2026-09-20 05:05	65.11	OK	14072	2026-09-20 05:06	67.05	OK
14073	2026-09-20 05:07	63.29	OK	14074	2026-09-20 05:08	66.32	OK
14075	2026-09-20 05:09	65.42	OK	14076	2026-09-20 05:10	64.17	OK
14077	2026-09-20 05:11	64.35	OK	14078	2026-09-20 05:12	68.41	OK
14079	2026-09-20 05:13	65.97	OK	14080	2026-09-20 05:14	66.11	OK
14081	2026-09-20 05:15	65.20	OK	14082	2026-09-20 05:16	65.95	OK
14083	2026-09-20 05:17	64.05	OK	14084	2026-09-20 05:18	63.41	OK
14085	2026-09-20 05:19	64.86	OK	14086	2026-09-20 05:20	65.89	OK
14087	2026-09-20 05:21	65.05	OK	14088	2026-09-20 05:22	65.33	OK
14089	2026-09-20 05:23	63.98	OK	14090	2026-09-20 05:24	65.77	OK
14091	2026-09-20 05:25	63.03	OK	14092	2026-09-20 05:26	64.80	OK
14093	2026-09-20 05:27	64.78	OK	14094	2026-09-20 05:28	63.27	OK
14095	2026-09-20 05:29	65.54	OK	14096	2026-09-20 05:30	63.98	OK
14097	2026-09-20 05:31	62.85	OK	14098	2026-09-20 05:32	64.83	OK
14099	2026-09-20 05:33	62.22	OK	14100	2026-09-20 05:34	65.00	OK
14101	2026-09-20 05:35	64.42	OK	14102	2026-09-20 05:36	62.50	OK
14103	2026-09-20 05:37	63.11	OK	14104	2026-09-20 05:38	65.79	OK
14105	2026-09-20 05:39	63.63	OK	14106	2026-09-20 05:40	63.72	OK
14107	2026-09-20 05:41	63.48	OK	14108	2026-09-20 05:42	63.18	OK
1410	2026-09-20 05:43	64.06	OK	1411	2026-09-20 05:44	61.59	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
14111	2026-09-20 05:45	62.65	OK	14112	2026-09-20 05:46	66.27	OK
14113	2026-09-20 05:47	64.40	OK	14114	2026-09-20 05:48	65.59	OK
14115	2026-09-20 05:49	64.73	OK	14116	2026-09-20 05:50	62.32	OK
14117	2026-09-20 05:51	64.96	OK	14118	2026-09-20 05:52	63.84	OK
14119	2026-09-20 05:53	63.61	OK	14120	2026-09-20 05:54	64.97	OK
14121	2026-09-20 05:55	62.25	OK	14122	2026-09-20 05:56	63.82	OK
14123	2026-09-20 05:57	63.06	OK	14124	2026-09-20 05:58	63.44	OK
14125	2026-09-20 05:59	64.52	OK	14126	2026-09-20 06:00	63.64	OK
14127	2026-09-20 06:01	64.16	OK	14128	2026-09-20 06:02	64.36	OK
14129	2026-09-20 06:03	65.97	OK	14130	2026-09-20 06:04	62.11	OK
14131	2026-09-20 06:05	63.61	OK	14132	2026-09-20 06:06	62.44	OK
14133	2026-09-20 06:07	63.38	OK	14134	2026-09-20 06:08	62.20	OK
14135	2026-09-20 06:09	64.41	OK	14136	2026-09-20 06:10	63.93	OK
14137	2026-09-20 06:11	62.68	OK	14138	2026-09-20 06:12	63.25	OK
14139	2026-09-20 06:13	65.07	OK	14140	2026-09-20 06:14	62.83	OK
14141	2026-09-20 06:15	63.30	OK	14142	2026-09-20 06:16	62.32	OK
14143	2026-09-20 06:17	62.58	OK	14144	2026-09-20 06:18	60.91	OK
14145	2026-09-20 06:19	62.09	OK	14146	2026-09-20 06:20	63.79	OK
14147	2026-09-20 06:21	64.21	OK	14148	2026-09-20 06:22	63.21	OK
14149	2026-09-20 06:23	64.44	OK	14150	2026-09-20 06:24	62.23	OK
14151	2026-09-20 06:25	64.03	OK	14152	2026-09-20 06:26	61.66	OK
14153	2026-09-20 06:27	63.55	OK	14154	2026-09-20 06:28	64.45	OK
14155	2026-09-20 06:29	64.23	OK	14156	2026-09-20 06:30	63.19	OK
14157	2026-09-20 06:31	61.05	OK	14158	2026-09-20 06:32	63.33	OK
14159	2026-09-20 06:33	64.01	OK	14160	2026-09-20 06:34	64.20	OK
14161	2026-09-20 06:35	62.91	OK	14162	2026-09-20 06:36	61.31	OK
14163	2026-09-20 06:37	60.85	OK	14164	2026-09-20 06:38	63.88	OK
14165	2026-09-20 06:39	61.48	OK	14166	2026-09-20 06:40	63.31	OK
14167	2026-09-20 06:41	62.62	OK	14168	2026-09-20 06:42	63.33	OK
1416	2026-09-20 06:43	62.14	OK	1417	2026-09-20 06:44	60.01	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
14171	2026-09-20 06:45	61.28	OK	14172	2026-09-20 06:46	62.65	OK
14173	2026-09-20 06:47	62.93	OK	14174	2026-09-20 06:48	64.32	OK
14175	2026-09-20 06:49	60.71	OK	14176	2026-09-20 06:50	64.39	OK
14177	2026-09-20 06:51	62.32	OK	14178	2026-09-20 06:52	62.50	OK
14179	2026-09-20 06:53	63.13	OK	14180	2026-09-20 06:54	63.50	OK
14181	2026-09-20 06:55	61.52	OK	14182	2026-09-20 06:56	63.48	OK
14183	2026-09-20 06:57	61.04	OK	14184	2026-09-20 06:58	59.86	OK
14185	2026-09-20 06:59	63.02	OK	14186	2026-09-20 07:00	62.50	OK
14187	2026-09-20 07:01	62.50	OK	14188	2026-09-20 07:02	63.45	OK
14189	2026-09-20 07:03	62.69	OK	14190	2026-09-20 07:04	63.85	OK
14191	2026-09-20 07:05	59.98	OK	14192	2026-09-20 07:06	60.56	OK
14193	2026-09-20 07:07	61.05	OK	14194	2026-09-20 07:08	61.92	OK
14195	2026-09-20 07:09	61.48	OK	14196	2026-09-20 07:10	60.19	OK
14197	2026-09-20 07:11	61.63	OK	14198	2026-09-20 07:12	62.83	OK
14199	2026-09-20 07:13	62.83	OK	14200	2026-09-20 07:14	62.23	OK
14201	2026-09-20 07:15	63.02	OK	14202	2026-09-20 07:16	59.99	OK
14203	2026-09-20 07:17	61.74	OK	14204	2026-09-20 07:18	62.31	OK
14205	2026-09-20 07:19	63.65	OK	14206	2026-09-20 07:20	61.86	OK
14207	2026-09-20 07:21	60.24	OK	14208	2026-09-20 07:22	60.29	OK
14209	2026-09-20 07:23	61.28	OK	14210	2026-09-20 07:24	63.72	OK
14211	2026-09-20 07:25	61.65	OK	14212	2026-09-20 07:26	61.34	OK
14213	2026-09-20 07:27	60.11	OK	14214	2026-09-20 07:28	62.04	OK
14215	2026-09-20 07:29	60.98	OK	14216	2026-09-20 07:30	59.69	OK
14217	2026-09-20 07:31	61.41	OK	14218	2026-09-20 07:32	62.67	OK
14219	2026-09-20 07:33	62.11	OK	14220	2026-09-20 07:34	60.31	OK
14221	2026-09-20 07:35	61.37	OK	14222	2026-09-20 07:36	61.29	OK
14223	2026-09-20 07:37	61.91	OK	14224	2026-09-20 07:38	62.45	OK
14225	2026-09-20 07:39	61.83	OK	14226	2026-09-20 07:40	62.10	OK
14227	2026-09-20 07:41	62.14	OK	14228	2026-09-20 07:42	61.69	OK
1422	2026-09-20 07:43	62.45	OK	1423	2026-09-20 07:44	59.37	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
14231	2026-09-20 07:45	62.12	OK	14232	2026-09-20 07:46	60.12	OK
14233	2026-09-20 07:47	63.81	OK	14234	2026-09-20 07:48	61.35	OK
14235	2026-09-20 07:49	60.38	OK	14236	2026-09-20 07:50	60.71	OK
14237	2026-09-20 07:51	62.18	OK	14238	2026-09-20 07:52	61.20	OK
14239	2026-09-20 07:53	61.55	OK	14240	2026-09-20 07:54	62.47	OK
14241	2026-09-20 07:55	59.95	OK	14242	2026-09-20 07:56	61.26	OK
14243	2026-09-20 07:57	60.46	OK	14244	2026-09-20 07:58	59.85	OK
14245	2026-09-20 07:59	61.33	OK	14246	2026-09-20 08:00	59.35	OK
14247	2026-09-20 08:01	59.42	OK	14248	2026-09-20 08:02	61.61	OK
14249	2026-09-20 08:03	59.61	OK	14250	2026-09-20 08:04	61.25	OK
14251	2026-09-20 08:05	61.55	OK	14252	2026-09-20 08:06	60.93	OK
14253	2026-09-20 08:07	60.58	OK	14254	2026-09-20 08:08	62.56	OK
14255	2026-09-20 08:09	59.94	OK	14256	2026-09-20 08:10	62.55	OK
14257	2026-09-20 08:11	60.19	OK	14258	2026-09-20 08:12	60.17	OK
14259	2026-09-20 08:13	59.42	OK	14260	2026-09-20 08:14	60.63	OK
14261	2026-09-20 08:15	63.43	OK	14262	2026-09-20 08:16	60.02	OK
14263	2026-09-20 08:17	61.29	OK	14264	2026-09-20 08:18	59.77	OK
14265	2026-09-20 08:19	62.60	OK	14266	2026-09-20 08:20	58.36	OK
14267	2026-09-20 08:21	58.82	OK	14268	2026-09-20 08:22	59.42	OK
14269	2026-09-20 08:23	63.66	OK	14270	2026-09-20 08:24	61.54	OK
14271	2026-09-20 08:25	59.06	OK	14272	2026-09-20 08:26	60.42	OK
14273	2026-09-20 08:27	62.19	OK	14274	2026-09-20 08:28	59.04	OK
14275	2026-09-20 08:29	57.54	OK	14276	2026-09-20 08:30	60.96	OK
14277	2026-09-20 08:31	60.55	OK	14278	2026-09-20 08:32	60.05	OK
14279	2026-09-20 08:33	60.44	OK	14280	2026-09-20 08:34	58.48	OK
14281	2026-09-20 08:35	60.06	OK	14282	2026-09-20 08:36	61.73	OK
14283	2026-09-20 08:37	60.81	OK	14284	2026-09-20 08:38	62.06	OK
14285	2026-09-20 08:39	60.65	OK	14286	2026-09-20 08:40	59.62	OK
14287	2026-09-20 08:41	60.80	OK	14288	2026-09-20 08:42	61.18	OK
1428	2026-09-20 08:43	60.30	OK	1429	2026-09-20 08:44	58.59	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
14291	2026-09-20 08:45	60.16	OK	14292	2026-09-20 08:46	59.95	OK
14293	2026-09-20 08:47	61.78	OK	14294	2026-09-20 08:48	60.83	OK
14295	2026-09-20 08:49	60.75	OK	14296	2026-09-20 08:50	59.94	OK
14297	2026-09-20 08:51	60.11	OK	14298	2026-09-20 08:52	61.29	OK
14299	2026-09-20 08:53	62.39	OK	14300	2026-09-20 08:54	60.10	OK
14301	2026-09-20 08:55	57.83	OK	14302	2026-09-20 08:56	58.75	OK
14303	2026-09-20 08:57	61.34	OK	14304	2026-09-20 08:58	61.97	OK
14305	2026-09-20 08:59	60.38	OK	14306	2026-09-20 09:00	62.55	OK
14307	2026-09-20 09:01	59.82	OK	14308	2026-09-20 09:02	60.42	OK
14309	2026-09-20 09:03	60.26	OK	14310	2026-09-20 09:04	59.99	OK
14311	2026-09-20 09:05	58.75	OK	14312	2026-09-20 09:06	57.17	OK
14313	2026-09-20 09:07	60.69	OK	14314	2026-09-20 09:08	58.70	OK
14315	2026-09-20 09:09	60.67	OK	14316	2026-09-20 09:10	60.55	OK
14317	2026-09-20 09:11	60.20	OK	14318	2026-09-20 09:12	60.67	OK
14319	2026-09-20 09:13	60.58	OK	14320	2026-09-20 09:14	59.38	OK
14321	2026-09-20 09:15	61.95	OK	14322	2026-09-20 09:16	61.91	OK
14323	2026-09-20 09:17	60.49	OK	14324	2026-09-20 09:18	61.63	OK
14325	2026-09-20 09:19	60.53	OK	14326	2026-09-20 09:20	58.72	OK
14327	2026-09-20 09:21	59.99	OK	14328	2026-09-20 09:22	60.46	OK
14329	2026-09-20 09:23	57.87	OK	14330	2026-09-20 09:24	60.39	OK
14331	2026-09-20 09:25	58.79	OK	14332	2026-09-20 09:26	61.08	OK
14333	2026-09-20 09:27	62.27	OK	14334	2026-09-20 09:28	58.91	OK
14335	2026-09-20 09:29	57.94	OK	14336	2026-09-20 09:30	59.17	OK
14337	2026-09-20 09:31	61.53	OK	14338	2026-09-20 09:32	59.57	OK
14339	2026-09-20 09:33	60.31	OK	14340	2026-09-20 09:34	59.50	OK
14341	2026-09-20 09:35	60.64	OK	14342	2026-09-20 09:36	62.45	OK
14343	2026-09-20 09:37	58.87	OK	14344	2026-09-20 09:38	58.84	OK
14345	2026-09-20 09:39	62.30	OK	14346	2026-09-20 09:40	62.30	OK
14347	2026-09-20 09:41	61.26	OK	14348	2026-09-20 09:42	62.11	OK
14349	2026-09-20 09:43	60.71	OK	14350	2026-09-20 09:44	57.90	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
14351	2026-09-20 09:45	61.47	OK	14352	2026-09-20 09:46	57.89	OK
14353	2026-09-20 09:47	62.02	OK	14354	2026-09-20 09:48	60.13	OK
14355	2026-09-20 09:49	59.35	OK	14356	2026-09-20 09:50	58.14	OK
14357	2026-09-20 09:51	59.62	OK	14358	2026-09-20 09:52	60.97	OK
14359	2026-09-20 09:53	58.73	OK	14360	2026-09-20 09:54	59.86	OK
14361	2026-09-20 09:55	61.65	OK	14362	2026-09-20 09:56	60.03	OK
14363	2026-09-20 09:57	60.29	OK	14364	2026-09-20 09:58	60.28	OK
14365	2026-09-20 09:59	58.72	OK	14366	2026-09-20 10:00	57.63	OK
14367	2026-09-20 10:01	59.14	OK	14368	2026-09-20 10:02	58.35	OK
14369	2026-09-20 10:03	59.04	OK	14370	2026-09-20 10:04	59.28	OK
14371	2026-09-20 10:05	60.45	OK	14372	2026-09-20 10:06	61.46	OK
14373	2026-09-20 10:07	58.81	OK	14374	2026-09-20 10:08	61.41	OK
14375	2026-09-20 10:09	61.50	OK	14376	2026-09-20 10:10	58.84	OK
14377	2026-09-20 10:11	62.57	OK	14378	2026-09-20 10:12	58.29	OK
14379	2026-09-20 10:13	58.08	OK	14380	2026-09-20 10:14	58.78	OK
14381	2026-09-20 10:15	59.60	OK	14382	2026-09-20 10:16	58.61	OK
14383	2026-09-20 10:17	60.03	OK	14384	2026-09-20 10:18	59.96	OK
14385	2026-09-20 10:19	60.84	OK	14386	2026-09-20 10:20	58.83	OK
14387	2026-09-20 10:21	58.90	OK	14388	2026-09-20 10:22	60.07	OK
14389	2026-09-20 10:23	61.11	OK	14390	2026-09-20 10:24	60.04	OK
14391	2026-09-20 10:25	57.66	OK	14392	2026-09-20 10:26	60.98	OK
14393	2026-09-20 10:27	60.01	OK	14394	2026-09-20 10:28	59.47	OK
14395	2026-09-20 10:29	59.53	OK	14396	2026-09-20 10:30	61.28	OK
14397	2026-09-20 10:31	60.68	OK	14398	2026-09-20 10:32	60.20	OK
14399	2026-09-20 10:33	58.85	OK	14400	2026-09-20 10:34	60.13	OK
14401	2026-09-20 10:35	59.45	OK	14402	2026-09-20 10:36	59.18	OK
14403	2026-09-20 10:37	58.08	OK	14404	2026-09-20 10:38	60.09	OK
14405	2026-09-20 10:39	58.54	OK	14406	2026-09-20 10:40	60.70	OK
14407	2026-09-20 10:41	57.94	OK	14408	2026-09-20 10:42	58.40	OK
1440	2026-09-20 10:43	59.08	OK	1441	2026-09-20 10:44	60.22	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
14411	2026-09-20 10:45	58.49	OK	14412	2026-09-20 10:46	58.79	OK
14413	2026-09-20 10:47	59.31	OK	14414	2026-09-20 10:48	61.59	OK
14415	2026-09-20 10:49	57.90	OK	14416	2026-09-20 10:50	60.22	OK
14417	2026-09-20 10:51	58.83	OK	14418	2026-09-20 10:52	61.51	OK
14419	2026-09-20 10:53	59.11	OK	14420	2026-09-20 10:54	61.32	OK
14421	2026-09-20 10:55	57.38	OK	14422	2026-09-20 10:56	58.05	OK
14423	2026-09-20 10:57	60.00	OK	14424	2026-09-20 10:58	58.76	OK
14425	2026-09-20 10:59	57.20	OK	14426	2026-09-20 11:00	57.22	OK
14427	2026-09-20 11:01	59.99	OK	14428	2026-09-20 11:02	57.60	OK
14429	2026-09-20 11:03	61.57	OK	14430	2026-09-20 11:04	59.87	OK
14431	2026-09-20 11:05	60.94	OK	14432	2026-09-20 11:06	58.91	OK
14433	2026-09-20 11:07	59.62	OK	14434	2026-09-20 11:08	57.02	OK
14435	2026-09-20 11:09	57.36	OK	14436	2026-09-20 11:10	60.26	OK
14437	2026-09-20 11:11	59.55	OK	14438	2026-09-20 11:12	58.99	OK
14439	2026-09-20 11:13	58.76	OK	14440	2026-09-20 11:14	60.80	OK
14441	2026-09-20 11:15	59.55	OK	14442	2026-09-20 11:16	58.33	OK
14443	2026-09-20 11:17	59.32	OK	14444	2026-09-20 11:18	59.73	OK
14445	2026-09-20 11:19	60.42	OK	14446	2026-09-20 11:20	60.67	OK
14447	2026-09-20 11:21	59.82	OK	14448	2026-09-20 11:22	59.65	OK
14449	2026-09-20 11:23	58.54	OK	14450	2026-09-20 11:24	57.83	OK
14451	2026-09-20 11:25	58.78	OK	14452	2026-09-20 11:26	60.12	OK
14453	2026-09-20 11:27	59.35	OK	14454	2026-09-20 11:28	59.92	OK
14455	2026-09-20 11:29	60.67	OK	14456	2026-09-20 11:30	59.88	OK
14457	2026-09-20 11:31	60.82	OK	14458	2026-09-20 11:32	61.73	OK
14459	2026-09-20 11:33	61.48	OK	14460	2026-09-20 11:34	59.22	OK
14461	2026-09-20 11:35	60.42	OK	14462	2026-09-20 11:36	60.50	OK
14463	2026-09-20 11:37	60.44	OK	14464	2026-09-20 11:38	59.70	OK
14465	2026-09-20 11:39	59.13	OK	14466	2026-09-20 11:40	57.82	OK
14467	2026-09-20 11:41	57.74	OK	14468	2026-09-20 11:42	57.44	OK
14469	2026-09-20 11:43	60.28	OK	14470	2026-09-20 11:44	60.35	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
14471	2026-09-20 11:45	60.46	OK	14472	2026-09-20 11:46	59.30	OK
14473	2026-09-20 11:47	59.35	OK	14474	2026-09-20 11:48	59.88	OK
14475	2026-09-20 11:49	59.69	OK	14476	2026-09-20 11:50	61.16	OK
14477	2026-09-20 11:51	61.14	OK	14478	2026-09-20 11:52	59.94	OK
14479	2026-09-20 11:53	60.07	OK	14480	2026-09-20 11:54	59.77	OK
14481	2026-09-20 11:55	58.32	OK	14482	2026-09-20 11:56	60.16	OK
14483	2026-09-20 11:57	58.64	OK	14484	2026-09-20 11:58	59.86	OK
14485	2026-09-20 11:59	61.27	OK	14486	2026-09-20 12:00	58.85	OK
14487	2026-09-20 12:01	59.97	OK	14488	2026-09-20 12:02	60.05	OK
14489	2026-09-20 12:03	61.09	OK	14490	2026-09-20 12:04	59.47	OK
14491	2026-09-20 12:05	58.71	OK	14492	2026-09-20 12:06	56.80	OK
14493	2026-09-20 12:07	58.07	OK	14494	2026-09-20 12:08	59.82	OK
14495	2026-09-20 12:09	58.59	OK	14496	2026-09-20 12:10	58.22	OK
14497	2026-09-20 12:11	59.29	OK	14498	2026-09-20 12:12	58.40	OK
14499	2026-09-20 12:13	57.76	OK	14500	2026-09-20 12:14	60.64	OK
14501	2026-09-20 12:15	58.03	OK	14502	2026-09-20 12:16	57.88	OK
14503	2026-09-20 12:17	59.25	OK	14504	2026-09-20 12:18	58.83	OK
14505	2026-09-20 12:19	59.04	OK	14506	2026-09-20 12:20	61.26	OK
14507	2026-09-20 12:21	62.97	OK	14508	2026-09-20 12:22	60.10	OK
14509	2026-09-20 12:23	62.96	OK	14510	2026-09-20 12:24	58.67	OK
14511	2026-09-20 12:25	57.94	OK	14512	2026-09-20 12:26	60.07	OK
14513	2026-09-20 12:27	59.26	OK	14514	2026-09-20 12:28	60.27	OK
14515	2026-09-20 12:29	57.78	OK	14516	2026-09-20 12:30	62.16	OK
14517	2026-09-20 12:31	61.34	OK	14518	2026-09-20 12:32	61.34	OK
14519	2026-09-20 12:33	58.85	OK	14520	2026-09-20 12:34	61.16	OK
14521	2026-09-20 12:35	61.22	OK	14522	2026-09-20 12:36	61.53	OK
14523	2026-09-20 12:37	60.21	OK	14524	2026-09-20 12:38	60.06	OK
14525	2026-09-20 12:39	60.57	OK	14526	2026-09-20 12:40	60.09	OK
14527	2026-09-20 12:41	60.32	OK	14528	2026-09-20 12:42	59.75	OK
14529	2026-09-20 12:43	58.96	OK	14530	2026-09-20 12:44	60.34	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
14531	2026-09-20 12:45	58.50	OK	14532	2026-09-20 12:46	62.30	OK
14533	2026-09-20 12:47	61.09	OK	14534	2026-09-20 12:48	61.43	OK
14535	2026-09-20 12:49	61.84	OK	14536	2026-09-20 12:50	59.80	OK
14537	2026-09-20 12:51	59.86	OK	14538	2026-09-20 12:52	60.05	OK
14539	2026-09-20 12:53	60.91	OK	14540	2026-09-20 12:54	61.36	OK
14541	2026-09-20 12:55	59.90	OK	14542	2026-09-20 12:56	60.52	OK
14543	2026-09-20 12:57	60.41	OK	14544	2026-09-20 12:58	61.73	OK
14545	2026-09-20 12:59	60.03	OK	14546	2026-09-20 13:00	61.48	OK
14547	2026-09-20 13:01	60.33	OK	14548	2026-09-20 13:02	60.75	OK
14549	2026-09-20 13:03	58.82	OK	14550	2026-09-20 13:04	59.65	OK
14551	2026-09-20 13:05	60.27	OK	14552	2026-09-20 13:06	60.60	OK
14553	2026-09-20 13:07	59.86	OK	14554	2026-09-20 13:08	60.34	OK
14555	2026-09-20 13:09	60.72	OK	14556	2026-09-20 13:10	59.95	OK
14557	2026-09-20 13:11	59.38	OK	14558	2026-09-20 13:12	61.02	OK
14559	2026-09-20 13:13	59.39	OK	14560	2026-09-20 13:14	61.01	OK
14561	2026-09-20 13:15	61.93	OK	14562	2026-09-20 13:16	59.05	OK
14563	2026-09-20 13:17	60.59	OK	14564	2026-09-20 13:18	61.49	OK
14565	2026-09-20 13:19	62.52	OK	14566	2026-09-20 13:20	63.28	OK
14567	2026-09-20 13:21	59.23	OK	14568	2026-09-20 13:22	60.83	OK
14569	2026-09-20 13:23	60.80	OK	14570	2026-09-20 13:24	60.27	OK
14571	2026-09-20 13:25	61.94	OK	14572	2026-09-20 13:26	60.60	OK
14573	2026-09-20 13:27	60.59	OK	14574	2026-09-20 13:28	60.05	OK
14575	2026-09-20 13:29	61.21	OK	14576	2026-09-20 13:30	62.28	OK
14577	2026-09-20 13:31	61.03	OK	14578	2026-09-20 13:32	60.83	OK
14579	2026-09-20 13:33	61.74	OK	14580	2026-09-20 13:34	61.35	OK
14581	2026-09-20 13:35	62.28	OK	14582	2026-09-20 13:36	60.93	OK
14583	2026-09-20 13:37	62.00	OK	14584	2026-09-20 13:38	62.26	OK
14585	2026-09-20 13:39	60.73	OK	14586	2026-09-20 13:40	60.32	OK
14587	2026-09-20 13:41	61.38	OK	14588	2026-09-20 13:42	62.49	OK
1458	2026-09-20 13:43	60.28	OK	1459	2026-09-20 13:44	61.45	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
1459 1	2026-09-20 13:45	59.70	OK	1459 2	2026-09-20 13:46	63.80	OK
1459 3	2026-09-20 13:47	60.66	OK	1459 4	2026-09-20 13:48	59.56	OK
1459 5	2026-09-20 13:49	62.30	OK	1459 6	2026-09-20 13:50	64.68	OK
1459 7	2026-09-20 13:51	61.66	OK	1459 8	2026-09-20 13:52	61.84	OK
1459 9	2026-09-20 13:53	64.42	OK	1460 0	2026-09-20 13:54	59.68	OK
1460 1	2026-09-20 13:55	60.52	OK	1460 2	2026-09-20 13:56	63.14	OK
1460 3	2026-09-20 13:57	63.15	OK	1460 4	2026-09-20 13:58	61.01	OK
1460 5	2026-09-20 13:59	61.12	OK	1460 6	2026-09-20 14:00	60.47	OK
1460 7	2026-09-20 14:01	64.43	OK	1460 8	2026-09-20 14:02	62.46	OK
1460 9	2026-09-20 14:03	63.95	OK	1461 0	2026-09-20 14:04	61.92	OK
1461 1	2026-09-20 14:05	60.45	OK	1461 2	2026-09-20 14:06	62.76	OK
1461 3	2026-09-20 14:07	61.19	OK	1461 4	2026-09-20 14:08	61.84	OK
1461 5	2026-09-20 14:09	62.69	OK	1461 6	2026-09-20 14:10	63.11	OK
1461 7	2026-09-20 14:11	63.39	OK	1461 8	2026-09-20 14:12	63.41	OK
1461 9	2026-09-20 14:13	63.31	OK	1462 0	2026-09-20 14:14	62.57	OK
1462 1	2026-09-20 14:15	63.61	OK	1462 2	2026-09-20 14:16	59.87	OK
1462 3	2026-09-20 14:17	60.30	OK	1462 4	2026-09-20 14:18	61.03	OK
1462 5	2026-09-20 14:19	61.29	OK	1462 6	2026-09-20 14:20	63.40	OK
1462 7	2026-09-20 14:21	61.29	OK	1462 8	2026-09-20 14:22	61.45	OK
1462 9	2026-09-20 14:23	64.00	OK	1463 0	2026-09-20 14:24	62.86	OK
1463 1	2026-09-20 14:25	61.45	OK	1463 2	2026-09-20 14:26	61.21	OK
1463 3	2026-09-20 14:27	63.35	OK	1463 4	2026-09-20 14:28	63.23	OK
1463 5	2026-09-20 14:29	62.06	OK	1463 6	2026-09-20 14:30	63.46	OK
1463 7	2026-09-20 14:31	61.52	OK	1463 8	2026-09-20 14:32	63.44	OK
1463 9	2026-09-20 14:33	60.76	OK	1464 0	2026-09-20 14:34	61.66	OK
1464 1	2026-09-20 14:35	64.07	OK	1464 2	2026-09-20 14:36	63.04	OK
1464 3	2026-09-20 14:37	62.85	OK	1464 4	2026-09-20 14:38	62.90	OK
1464 5	2026-09-20 14:39	62.69	OK	1464 6	2026-09-20 14:40	61.87	OK
1464 7	2026-09-20 14:41	62.16	OK	1464 8	2026-09-20 14:42	63.95	OK
1464	2026-09-20 14:43	62.77	OK	1465	2026-09-20 14:44	61.62	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
14651	2026-09-20 14:45	61.79	OK	14652	2026-09-20 14:46	62.82	OK
14653	2026-09-20 14:47	62.58	OK	14654	2026-09-20 14:48	65.09	OK
14655	2026-09-20 14:49	63.35	OK	14656	2026-09-20 14:50	62.54	OK
14657	2026-09-20 14:51	64.82	OK	14658	2026-09-20 14:52	64.56	OK
14659	2026-09-20 14:53	63.45	OK	14660	2026-09-20 14:54	65.11	OK
14661	2026-09-20 14:55	65.45	OK	14662	2026-09-20 14:56	63.49	OK
14663	2026-09-20 14:57	64.05	OK	14664	2026-09-20 14:58	62.00	OK
14665	2026-09-20 14:59	63.97	OK	14666	2026-09-20 15:00	65.02	OK
14667	2026-09-20 15:01	62.53	OK	14668	2026-09-20 15:02	61.59	OK
14669	2026-09-20 15:03	66.07	OK	14670	2026-09-20 15:04	63.07	OK
14671	2026-09-20 15:05	62.94	OK	14672	2026-09-20 15:06	63.28	OK
14673	2026-09-20 15:07	63.98	OK	14674	2026-09-20 15:08	64.92	OK
14675	2026-09-20 15:09	64.16	OK	14676	2026-09-20 15:10	60.62	OK
14677	2026-09-20 15:11	62.93	OK	14678	2026-09-20 15:12	63.48	OK
14679	2026-09-20 15:13	63.90	OK	14680	2026-09-20 15:14	62.04	OK
14681	2026-09-20 15:15	62.60	OK	14682	2026-09-20 15:16	64.81	OK
14683	2026-09-20 15:17	66.35	OK	14684	2026-09-20 15:18	62.85	OK
14685	2026-09-20 15:19	66.81	OK	14686	2026-09-20 15:20	63.65	OK
14687	2026-09-20 15:21	65.19	OK	14688	2026-09-20 15:22	63.64	OK
14689	2026-09-20 15:23	64.71	OK	14690	2026-09-20 15:24	62.57	OK
14691	2026-09-20 15:25	64.14	OK	14692	2026-09-20 15:26	63.40	OK
14693	2026-09-20 15:27	63.90	OK	14694	2026-09-20 15:28	63.05	OK
14695	2026-09-20 15:29	64.02	OK	14696	2026-09-20 15:30	63.18	OK
14697	2026-09-20 15:31	63.22	OK	14698	2026-09-20 15:32	64.39	OK
14699	2026-09-20 15:33	64.56	OK	14700	2026-09-20 15:34	62.49	OK
14701	2026-09-20 15:35	64.25	OK	14702	2026-09-20 15:36	63.39	OK
14703	2026-09-20 15:37	64.98	OK	14704	2026-09-20 15:38	63.93	OK
14705	2026-09-20 15:39	65.94	OK	14706	2026-09-20 15:40	65.47	OK
14707	2026-09-20 15:41	63.43	OK	14708	2026-09-20 15:42	65.49	OK
1470	2026-09-20 15:43	64.50	OK	1471	2026-09-20 15:44	65.62	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
14711	2026-09-20 15:45	63.01	OK	14712	2026-09-20 15:46	65.71	OK
14713	2026-09-20 15:47	64.15	OK	14714	2026-09-20 15:48	62.28	OK
14715	2026-09-20 15:49	64.67	OK	14716	2026-09-20 15:50	64.53	OK
14717	2026-09-20 15:51	63.66	OK	14718	2026-09-20 15:52	65.32	OK
14719	2026-09-20 15:53	64.24	OK	14720	2026-09-20 15:54	65.08	OK
14721	2026-09-20 15:55	64.26	OK	14722	2026-09-20 15:56	64.89	OK
14723	2026-09-20 15:57	63.42	OK	14724	2026-09-20 15:58	64.81	OK
14725	2026-09-20 15:59	65.91	OK	14726	2026-09-20 16:00	64.61	OK
14727	2026-09-20 16:01	65.26	OK	14728	2026-09-20 16:02	65.32	OK
14729	2026-09-20 16:03	64.05	OK	14730	2026-09-20 16:04	64.59	OK
14731	2026-09-20 16:05	66.64	OK	14732	2026-09-20 16:06	66.34	OK
14733	2026-09-20 16:07	64.81	OK	14734	2026-09-20 16:08	65.98	OK
14735	2026-09-20 16:09	67.14	OK	14736	2026-09-20 16:10	64.86	OK
14737	2026-09-20 16:11	67.49	OK	14738	2026-09-20 16:12	63.24	OK
14739	2026-09-20 16:13	66.11	OK	14740	2026-09-20 16:14	64.23	OK
14741	2026-09-20 16:15	66.03	OK	14742	2026-09-20 16:16	66.72	OK
14743	2026-09-20 16:17	67.48	OK	14744	2026-09-20 16:18	64.44	OK
14745	2026-09-20 16:19	66.78	OK	14746	2026-09-20 16:20	66.64	OK
14747	2026-09-20 16:21	66.84	OK	14748	2026-09-20 16:22	64.58	OK
14749	2026-09-20 16:23	65.75	OK	14750	2026-09-20 16:24	64.48	OK
14751	2026-09-20 16:25	65.11	OK	14752	2026-09-20 16:26	63.76	OK
14753	2026-09-20 16:27	65.14	OK	14754	2026-09-20 16:28	64.82	OK
14755	2026-09-20 16:29	64.40	OK	14756	2026-09-20 16:30	66.71	OK
14757	2026-09-20 16:31	65.06	OK	14758	2026-09-20 16:32	63.41	OK
14759	2026-09-20 16:33	66.77	OK	14760	2026-09-20 16:34	64.79	OK
14761	2026-09-20 16:35	64.18	OK	14762	2026-09-20 16:36	65.60	OK
14763	2026-09-20 16:37	65.18	OK	14764	2026-09-20 16:38	68.05	OK
14765	2026-09-20 16:39	65.98	OK	14766	2026-09-20 16:40	63.92	OK
14767	2026-09-20 16:41	67.45	OK	14768	2026-09-20 16:42	66.39	OK
1476	2026-09-20 16:43	65.51	OK	1477	2026-09-20 16:44	65.63	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
14771	2026-09-20 16:45	66.49	OK	14772	2026-09-20 16:46	67.19	OK
14773	2026-09-20 16:47	67.88	OK	14774	2026-09-20 16:48	65.81	OK
14775	2026-09-20 16:49	66.33	OK	14776	2026-09-20 16:50	65.48	OK
14777	2026-09-20 16:51	65.77	OK	14778	2026-09-20 16:52	64.74	OK
14779	2026-09-20 16:53	66.92	OK	14780	2026-09-20 16:54	66.48	OK
14781	2026-09-20 16:55	66.97	OK	14782	2026-09-20 16:56	67.57	OK
14783	2026-09-20 16:57	63.42	OK	14784	2026-09-20 16:58	67.86	OK
14785	2026-09-20 16:59	64.84	OK	14786	2026-09-20 17:00	68.64	OK
14787	2026-09-20 17:01	65.71	OK	14788	2026-09-20 17:02	66.08	OK
14789	2026-09-20 17:03	66.90	OK	14790	2026-09-20 17:04	66.37	OK
14791	2026-09-20 17:05	68.25	OK	14792	2026-09-20 17:06	66.75	OK
14793	2026-09-20 17:07	66.98	OK	14794	2026-09-20 17:08	66.65	OK
14795	2026-09-20 17:09	66.19	OK	14796	2026-09-20 17:10	65.44	OK
14797	2026-09-20 17:11	67.36	OK	14798	2026-09-20 17:12	68.63	OK
14799	2026-09-20 17:13	68.79	OK	14800	2026-09-20 17:14	66.02	OK
14801	2026-09-20 17:15	68.03	OK	14802	2026-09-20 17:16	66.35	OK
14803	2026-09-20 17:17	68.21	OK	14804	2026-09-20 17:18	68.46	OK
14805	2026-09-20 17:19	65.80	OK	14806	2026-09-20 17:20	67.17	OK
14807	2026-09-20 17:21	65.83	OK	14808	2026-09-20 17:22	68.92	OK
14809	2026-09-20 17:23	69.20	OK	14810	2026-09-20 17:24	68.96	OK
14811	2026-09-20 17:25	68.10	OK	14812	2026-09-20 17:26	68.83	OK
14813	2026-09-20 17:27	69.29	OK	14814	2026-09-20 17:28	68.45	OK
14815	2026-09-20 17:29	65.92	OK	14816	2026-09-20 17:30	68.22	OK
14817	2026-09-20 17:31	65.75	OK	14818	2026-09-20 17:32	69.06	OK
14819	2026-09-20 17:33	66.17	OK	14820	2026-09-20 17:34	65.66	OK
14821	2026-09-20 17:35	68.45	OK	14822	2026-09-20 17:36	69.26	OK
14823	2026-09-20 17:37	69.43	OK	14824	2026-09-20 17:38	65.61	OK
14825	2026-09-20 17:39	69.21	OK	14826	2026-09-20 17:40	66.21	OK
14827	2026-09-20 17:41	67.20	OK	14828	2026-09-20 17:42	65.78	OK
1482	2026-09-20 17:43	67.83	OK	1483	2026-09-20 17:44	68.79	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
14831	2026-09-20 17:45	68.51	OK	14832	2026-09-20 17:46	69.34	OK
14833	2026-09-20 17:47	69.36	OK	14834	2026-09-20 17:48	67.50	OK
14835	2026-09-20 17:49	69.00	OK	14836	2026-09-20 17:50	67.06	OK
14837	2026-09-20 17:51	67.17	OK	14838	2026-09-20 17:52	67.81	OK
14839	2026-09-20 17:53	68.89	OK	14840	2026-09-20 17:54	67.20	OK
14841	2026-09-20 17:55	68.00	OK	14842	2026-09-20 17:56	68.94	OK
14843	2026-09-20 17:57	70.00	OK	14844	2026-09-20 17:58	67.60	OK
14845	2026-09-20 17:59	67.64	OK	14846	2026-09-20 18:00	67.73	OK
14847	2026-09-20 18:01	68.09	OK	14848	2026-09-20 18:02	68.13	OK
14849	2026-09-20 18:03	67.96	OK	14850	2026-09-20 18:04	69.55	OK
14851	2026-09-20 18:05	68.03	OK	14852	2026-09-20 18:06	69.20	OK
14853	2026-09-20 18:07	66.71	OK	14854	2026-09-20 18:08	69.22	OK
14855	2026-09-20 18:09	68.76	OK	14856	2026-09-20 18:10	67.62	OK
14857	2026-09-20 18:11	69.15	OK	14858	2026-09-20 18:12	67.74	OK
14859	2026-09-20 18:13	67.43	OK	14860	2026-09-20 18:14	70.76	OK
14861	2026-09-20 18:15	69.92	OK	14862	2026-09-20 18:16	68.79	OK
14863	2026-09-20 18:17	69.18	OK	14864	2026-09-20 18:18	68.78	OK
14865	2026-09-20 18:19	69.48	OK	14866	2026-09-20 18:20	69.23	OK
14867	2026-09-20 18:21	70.33	OK	14868	2026-09-20 18:22	68.36	OK
14869	2026-09-20 18:23	70.60	OK	14870	2026-09-20 18:24	69.02	OK
14871	2026-09-20 18:25	68.92	OK	14872	2026-09-20 18:26	69.52	OK
14873	2026-09-20 18:27	69.19	OK	14874	2026-09-20 18:28	67.63	OK
14875	2026-09-20 18:29	69.21	OK	14876	2026-09-20 18:30	71.20	OK
14877	2026-09-20 18:31	69.09	OK	14878	2026-09-20 18:32	71.14	OK
14879	2026-09-20 18:33	71.29	OK	14880	2026-09-20 18:34	70.25	OK
14881	2026-09-20 18:35	68.59	OK	14882	2026-09-20 18:36	68.71	OK
14883	2026-09-20 18:37	67.88	OK	14884	2026-09-20 18:38	69.73	OK
14885	2026-09-20 18:39	68.40	OK	14886	2026-09-20 18:40	71.80	OK
14887	2026-09-20 18:41	68.66	OK	14888	2026-09-20 18:42	68.12	OK
1488	2026-09-20 18:43	71.39	OK	1489	2026-09-20 18:44	70.49	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
14891	2026-09-20 18:45	69.67	OK	14892	2026-09-20 18:46	71.48	OK
14893	2026-09-20 18:47	68.77	OK	14894	2026-09-20 18:48	68.68	OK
14895	2026-09-20 18:49	69.90	OK	14896	2026-09-20 18:50	70.54	OK
14897	2026-09-20 18:51	70.42	OK	14898	2026-09-20 18:52	70.63	OK
14899	2026-09-20 18:53	69.44	OK	14900	2026-09-20 18:54	71.36	OK
14901	2026-09-20 18:55	70.19	OK	14902	2026-09-20 18:56	71.87	OK
14903	2026-09-20 18:57	69.14	OK	14904	2026-09-20 18:58	68.29	OK
14905	2026-09-20 18:59	72.30	OK	14906	2026-09-20 19:00	69.21	OK
14907	2026-09-20 19:01	67.47	OK	14908	2026-09-20 19:02	71.69	OK
14909	2026-09-20 19:03	68.92	OK	14910	2026-09-20 19:04	70.67	OK
14911	2026-09-20 19:05	67.91	OK	14912	2026-09-20 19:06	71.04	OK
14913	2026-09-20 19:07	70.97	OK	14914	2026-09-20 19:08	69.61	OK
14915	2026-09-20 19:09	72.85	OK	14916	2026-09-20 19:10	69.99	OK
14917	2026-09-20 19:11	70.99	OK	14918	2026-09-20 19:12	72.55	OK
14919	2026-09-20 19:13	69.63	OK	14920	2026-09-20 19:14	72.38	OK
14921	2026-09-20 19:15	71.04	OK	14922	2026-09-20 19:16	72.95	OK
14923	2026-09-20 19:17	71.61	OK	14924	2026-09-20 19:18	69.91	OK
14925	2026-09-20 19:19	69.61	OK	14926	2026-09-20 19:20	70.15	OK
14927	2026-09-20 19:21	70.11	OK	14928	2026-09-20 19:22	70.85	OK
14929	2026-09-20 19:23	68.08	OK	14930	2026-09-20 19:24	69.40	OK
14931	2026-09-20 19:25	72.61	OK	14932	2026-09-20 19:26	70.47	OK
14933	2026-09-20 19:27	71.22	OK	14934	2026-09-20 19:28	69.87	OK
14935	2026-09-20 19:29	70.97	OK	14936	2026-09-20 19:30	68.47	OK
14937	2026-09-20 19:31	70.03	OK	14938	2026-09-20 19:32	71.70	OK
14939	2026-09-20 19:33	71.97	OK	14940	2026-09-20 19:34	68.51	OK
14941	2026-09-20 19:35	69.75	OK	14942	2026-09-20 19:36	70.97	OK
14943	2026-09-20 19:37	71.57	OK	14944	2026-09-20 19:38	71.42	OK
14945	2026-09-20 19:39	71.65	OK	14946	2026-09-20 19:40	69.69	OK
14947	2026-09-20 19:41	68.84	OK	14948	2026-09-20 19:42	70.45	OK
14949	2026-09-20 19:43	71.95	OK	14950	2026-09-20 19:44	68.36	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
14951	2026-09-20 19:45	71.03	OK	14952	2026-09-20 19:46	70.97	OK
14953	2026-09-20 19:47	72.12	OK	14954	2026-09-20 19:48	68.94	OK
14955	2026-09-20 19:49	71.33	OK	14956	2026-09-20 19:50	70.58	OK
14957	2026-09-20 19:51	72.22	OK	14958	2026-09-20 19:52	71.02	OK
14959	2026-09-20 19:53	72.33	OK	14960	2026-09-20 19:54	69.02	OK
14961	2026-09-20 19:55	71.73	OK	14962	2026-09-20 19:56	71.13	OK
14963	2026-09-20 19:57	69.57	OK	14964	2026-09-20 19:58	72.41	OK
14965	2026-09-20 19:59	74.13	OK	14966	2026-09-20 20:00	70.16	OK
14967	2026-09-20 20:01	71.33	OK	14968	2026-09-20 20:02	71.21	OK
14969	2026-09-20 20:03	72.69	OK	14970	2026-09-20 20:04	72.04	OK
14971	2026-09-20 20:05	72.61	OK	14972	2026-09-20 20:06	71.17	OK
14973	2026-09-20 20:07	72.27	OK	14974	2026-09-20 20:08	71.35	OK
14975	2026-09-20 20:09	73.07	OK	14976	2026-09-20 20:10	70.42	OK
14977	2026-09-20 20:11	70.79	OK	14978	2026-09-20 20:12	71.07	OK
14979	2026-09-20 20:13	71.04	OK	14980	2026-09-20 20:14	70.55	OK
14981	2026-09-20 20:15	70.96	OK	14982	2026-09-20 20:16	72.62	OK
14983	2026-09-20 20:17	71.60	OK	14984	2026-09-20 20:18	73.21	OK
14985	2026-09-20 20:19	68.96	OK	14986	2026-09-20 20:20	71.73	OK
14987	2026-09-20 20:21	69.75	OK	14988	2026-09-20 20:22	70.74	OK
14989	2026-09-20 20:23	69.97	OK	14990	2026-09-20 20:24	73.48	OK
14991	2026-09-20 20:25	72.42	OK	14992	2026-09-20 20:26	71.70	OK
14993	2026-09-20 20:27	72.83	OK	14994	2026-09-20 20:28	73.35	OK
14995	2026-09-20 20:29	72.07	OK	14996	2026-09-20 20:30	71.30	OK
14997	2026-09-20 20:31	72.31	OK	14998	2026-09-20 20:32	72.01	OK
14999	2026-09-20 20:33	72.14	OK	15000	2026-09-20 20:34	72.57	OK
15001	2026-09-20 20:35	71.76	OK	15002	2026-09-20 20:36	71.30	OK
15003	2026-09-20 20:37	73.78	OK	15004	2026-09-20 20:38	70.18	OK
15005	2026-09-20 20:39	72.57	OK	15006	2026-09-20 20:40	71.52	OK
15007	2026-09-20 20:41	70.99	OK	15008	2026-09-20 20:42	73.47	OK
15009	2026-09-20 20:43	69.53	OK	15010	2026-09-20 20:44	73.65	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
15011	2026-09-20 20:45	72.47	OK	15012	2026-09-20 20:46	73.06	OK
15013	2026-09-20 20:47	73.09	OK	15014	2026-09-20 20:48	73.92	OK
15015	2026-09-20 20:49	71.07	OK	15016	2026-09-20 20:50	71.16	OK
15017	2026-09-20 20:51	70.98	OK	15018	2026-09-20 20:52	72.88	OK
15019	2026-09-20 20:53	70.76	OK	15020	2026-09-20 20:54	72.00	OK
15021	2026-09-20 20:55	72.31	OK	15022	2026-09-20 20:56	71.52	OK
15023	2026-09-20 20:57	71.79	OK	15024	2026-09-20 20:58	72.39	OK
15025	2026-09-20 20:59	72.76	OK	15026	2026-09-20 21:00	72.22	OK
15027	2026-09-20 21:01	73.66	OK	15028	2026-09-20 21:02	72.81	OK
15029	2026-09-20 21:03	72.35	OK	15030	2026-09-20 21:04	70.98	OK
15031	2026-09-20 21:05	71.37	OK	15032	2026-09-20 21:06	72.89	OK
15033	2026-09-20 21:07	72.23	OK	15034	2026-09-20 21:08	68.90	OK
15035	2026-09-20 21:09	69.78	OK	15036	2026-09-20 21:10	71.91	OK
15037	2026-09-20 21:11	70.60	OK	15038	2026-09-20 21:12	72.67	OK
15039	2026-09-20 21:13	71.61	OK	15040	2026-09-20 21:14	70.89	OK
15041	2026-09-20 21:15	74.09	OK	15042	2026-09-20 21:16	71.29	OK
15043	2026-09-20 21:17	70.69	OK	15044	2026-09-20 21:18	74.71	OK
15045	2026-09-20 21:19	73.10	OK	15046	2026-09-20 21:20	72.27	OK
15047	2026-09-20 21:21	71.99	OK	15048	2026-09-20 21:22	71.60	OK
15049	2026-09-20 21:23	73.09	OK	15050	2026-09-20 21:24	72.37	OK
15051	2026-09-20 21:25	72.99	OK	15052	2026-09-20 21:26	71.81	OK
15053	2026-09-20 21:27	70.85	OK	15054	2026-09-20 21:28	70.70	OK
15055	2026-09-20 21:29	71.48	OK	15056	2026-09-20 21:30	70.64	OK
15057	2026-09-20 21:31	72.21	OK	15058	2026-09-20 21:32	70.30	OK
15059	2026-09-20 21:33	72.83	OK	15060	2026-09-20 21:34	74.91	OK
15061	2026-09-20 21:35	70.09	OK	15062	2026-09-20 21:36	71.01	OK
15063	2026-09-20 21:37	72.05	OK	15064	2026-09-20 21:38	72.74	OK
15065	2026-09-20 21:39	72.67	OK	15066	2026-09-20 21:40	71.63	OK
15067	2026-09-20 21:41	72.21	OK	15068	2026-09-20 21:42	72.61	OK
1506	2026-09-20 21:43	73.05	OK	1507	2026-09-20 21:44	72.77	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
15071	2026-09-20 21:45	74.65	OK	15072	2026-09-20 21:46	70.26	OK
15073	2026-09-20 21:47	73.10	OK	15074	2026-09-20 21:48	72.09	OK
15075	2026-09-20 21:49	73.31	OK	15076	2026-09-20 21:50	73.15	OK
15077	2026-09-20 21:51	73.33	OK	15078	2026-09-20 21:52	73.26	OK
15079	2026-09-20 21:53	74.27	OK	15080	2026-09-20 21:54	72.80	OK
15081	2026-09-20 21:55	73.26	OK	15082	2026-09-20 21:56	73.69	OK
15083	2026-09-20 21:57	72.96	OK	15084	2026-09-20 21:58	71.99	OK
15085	2026-09-20 21:59	74.16	OK	15086	2026-09-20 22:00	75.54	OK
15087	2026-09-20 22:01	71.73	OK	15088	2026-09-20 22:02	70.88	OK
15089	2026-09-20 22:03	73.84	OK	15090	2026-09-20 22:04	73.98	OK
15091	2026-09-20 22:05	73.85	OK	15092	2026-09-20 22:06	69.98	OK
15093	2026-09-20 22:07	74.70	OK	15094	2026-09-20 22:08	73.51	OK
15095	2026-09-20 22:09	73.56	OK	15096	2026-09-20 22:10	73.72	OK
15097	2026-09-20 22:11	73.90	OK	15098	2026-09-20 22:12	72.97	OK
15099	2026-09-20 22:13	71.80	OK	15100	2026-09-20 22:14	73.57	OK
15101	2026-09-20 22:15	73.07	OK	15102	2026-09-20 22:16	73.66	OK
15103	2026-09-20 22:17	70.28	OK	15104	2026-09-20 22:18	73.43	OK
15105	2026-09-20 22:19	72.56	OK	15106	2026-09-20 22:20	72.72	OK
15107	2026-09-20 22:21	73.41	OK	15108	2026-09-20 22:22	73.37	OK
15109	2026-09-20 22:23	71.88	OK	15110	2026-09-20 22:24	72.40	OK
15111	2026-09-20 22:25	71.33	OK	15112	2026-09-20 22:26	71.47	OK
15113	2026-09-20 22:27	73.35	OK	15114	2026-09-20 22:28	72.74	OK
15115	2026-09-20 22:29	72.79	OK	15116	2026-09-20 22:30	72.25	OK
15117	2026-09-20 22:31	72.86	OK	15118	2026-09-20 22:32	72.49	OK
15119	2026-09-20 22:33	70.07	OK	15120	2026-09-20 22:34	70.58	OK
15121	2026-09-20 22:35	74.37	OK	15122	2026-09-20 22:36	72.47	OK
15123	2026-09-20 22:37	71.14	OK	15124	2026-09-20 22:38	72.47	OK
15125	2026-09-20 22:39	72.53	OK	15126	2026-09-20 22:40	74.42	OK
15127	2026-09-20 22:41	72.69	OK	15128	2026-09-20 22:42	74.39	OK
1512	2026-09-20 22:43	71.99	OK	1513	2026-09-20 22:44	75.19	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
15131	2026-09-20 22:45	71.73	OK	15132	2026-09-20 22:46	73.86	OK
15133	2026-09-20 22:47	71.98	OK	15134	2026-09-20 22:48	73.83	OK
15135	2026-09-20 22:49	71.31	OK	15136	2026-09-20 22:50	69.78	OK
15137	2026-09-20 22:51	73.09	OK	15138	2026-09-20 22:52	72.18	OK
15139	2026-09-20 22:53	71.57	OK	15140	2026-09-20 22:54	74.30	OK
15141	2026-09-20 22:55	73.54	OK	15142	2026-09-20 22:56	71.63	OK
15143	2026-09-20 22:57	71.52	OK	15144	2026-09-20 22:58	70.10	OK
15145	2026-09-20 22:59	70.11	OK	15146	2026-09-20 23:00	73.63	OK
15147	2026-09-20 23:01	73.82	OK	15148	2026-09-20 23:02	74.56	OK
15149	2026-09-20 23:03	72.43	OK	15150	2026-09-20 23:04	72.57	OK
15151	2026-09-20 23:05	74.49	OK	15152	2026-09-20 23:06	72.69	OK
15153	2026-09-20 23:07	74.22	OK	15154	2026-09-20 23:08	72.61	OK
15155	2026-09-20 23:09	73.79	OK	15156	2026-09-20 23:10	72.49	OK
15157	2026-09-20 23:11	73.25	OK	15158	2026-09-20 23:12	74.08	OK
15159	2026-09-20 23:13	70.77	OK	15160	2026-09-20 23:14	72.80	OK
15161	2026-09-20 23:15	73.04	OK	15162	2026-09-20 23:16	70.33	OK
15163	2026-09-20 23:17	71.82	OK	15164	2026-09-20 23:18	75.13	OK
15165	2026-09-20 23:19	72.16	OK	15166	2026-09-20 23:20	72.48	OK
15167	2026-09-20 23:21	73.59	OK	15168	2026-09-20 23:22	73.52	OK
15169	2026-09-20 23:23	70.99	OK	15170	2026-09-20 23:24	73.75	OK
15171	2026-09-20 23:25	71.35	OK	15172	2026-09-20 23:26	72.85	OK
15173	2026-09-20 23:27	72.30	OK	15174	2026-09-20 23:28	72.25	OK
15175	2026-09-20 23:29	71.65	OK	15176	2026-09-20 23:30	73.75	OK
15177	2026-09-20 23:31	72.94	OK	15178	2026-09-20 23:32	71.79	OK
15179	2026-09-20 23:33	73.05	OK	15180	2026-09-20 23:34	72.14	OK
15181	2026-09-20 23:35	72.03	OK	15182	2026-09-20 23:36	74.46	OK
15183	2026-09-20 23:37	74.59	OK	15184	2026-09-20 23:38	71.71	OK
15185	2026-09-20 23:39	71.09	OK	15186	2026-09-20 23:40	70.69	OK
15187	2026-09-20 23:41	70.42	OK	15188	2026-09-20 23:42	71.87	OK
1518	2026-09-20 23:43	71.26	OK	1519	2026-09-20 23:44	72.30	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
15191	2026-09-20 23:45	72.12	OK	15192	2026-09-20 23:46	73.85	OK
15193	2026-09-20 23:47	72.10	OK	15194	2026-09-20 23:48	72.57	OK
15195	2026-09-20 23:49	71.67	OK	15196	2026-09-20 23:50	72.42	OK
15197	2026-09-20 23:51	71.71	OK	15198	2026-09-20 23:52	72.46	OK
15199	2026-09-20 23:53	74.86	OK	15200	2026-09-20 23:54	73.43	OK
15201	2026-09-20 23:55	71.84	OK	15202	2026-09-20 23:56	72.60	OK
15203	2026-09-20 23:57	73.13	OK	15204	2026-09-20 23:58	71.98	OK
15205	2026-09-20 23:59	73.53	OK	15206	2026-09-21 00:00	71.12	OK
15207	2026-09-21 00:01	72.70	OK	15208	2026-09-21 00:02	71.52	OK
15209	2026-09-21 00:03	70.83	OK	15210	2026-09-21 00:04	72.37	OK
15211	2026-09-21 00:05	72.04	OK	15212	2026-09-21 00:06	74.71	OK
15213	2026-09-21 00:07	70.52	OK	15214	2026-09-21 00:08	70.26	OK
15215	2026-09-21 00:09	73.47	OK	15216	2026-09-21 00:10	70.37	OK
15217	2026-09-21 00:11	73.43	OK	15218	2026-09-21 00:12	73.33	OK
15219	2026-09-21 00:13	71.09	OK	15220	2026-09-21 00:14	72.77	OK
15221	2026-09-21 00:15	70.49	OK	15222	2026-09-21 00:16	73.95	OK
15223	2026-09-21 00:17	73.21	OK	15224	2026-09-21 00:18	69.43	OK
15225	2026-09-21 00:19	71.92	OK	15226	2026-09-21 00:20	69.61	OK
15227	2026-09-21 00:21	73.72	OK	15228	2026-09-21 00:22	72.75	OK
15229	2026-09-21 00:23	74.35	OK	15230	2026-09-21 00:24	72.93	OK
15231	2026-09-21 00:25	73.44	OK	15232	2026-09-21 00:26	70.53	OK
15233	2026-09-21 00:27	71.82	OK	15234	2026-09-21 00:28	70.22	OK
15235	2026-09-21 00:29	72.77	OK	15236	2026-09-21 00:30	71.33	OK
15237	2026-09-21 00:31	71.82	OK	15238	2026-09-21 00:32	72.98	OK
15239	2026-09-21 00:33	70.92	OK	15240	2026-09-21 00:34	71.76	OK
15241	2026-09-21 00:35	71.82	OK	15242	2026-09-21 00:36	73.27	OK
15243	2026-09-21 00:37	72.00	OK	15244	2026-09-21 00:38	69.88	OK
15245	2026-09-21 00:39	71.36	OK	15246	2026-09-21 00:40	71.59	OK
15247	2026-09-21 00:41	72.96	OK	15248	2026-09-21 00:42	72.74	OK
1524	2026-09-21 00:43	73.85	OK	1525	2026-09-21 00:44	70.80	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
15251	2026-09-21 00:45	73.09	OK	15252	2026-09-21 00:46	71.90	OK
15253	2026-09-21 00:47	71.62	OK	15254	2026-09-21 00:48	71.33	OK
15255	2026-09-21 00:49	72.06	OK	15256	2026-09-21 00:50	73.68	OK
15257	2026-09-21 00:51	73.05	OK	15258	2026-09-21 00:52	70.69	OK
15259	2026-09-21 00:53	72.66	OK	15260	2026-09-21 00:54	72.85	OK
15261	2026-09-21 00:55	68.74	OK	15262	2026-09-21 00:56	71.96	OK
15263	2026-09-21 00:57	70.44	OK	15264	2026-09-21 00:58	69.46	OK
15265	2026-09-21 00:59	70.00	OK	15266	2026-09-21 01:00	71.18	OK
15267	2026-09-21 01:01	71.69	OK	15268	2026-09-21 01:02	71.69	OK
15269	2026-09-21 01:03	73.36	OK	15270	2026-09-21 01:04	70.80	OK
15271	2026-09-21 01:05	70.68	OK	15272	2026-09-21 01:06	73.08	OK
15273	2026-09-21 01:07	72.39	OK	15274	2026-09-21 01:08	73.58	OK
15275	2026-09-21 01:09	72.71	OK	15276	2026-09-21 01:10	70.82	OK
15277	2026-09-21 01:11	71.96	OK	15278	2026-09-21 01:12	72.05	OK
15279	2026-09-21 01:13	71.50	OK	15280	2026-09-21 01:14	70.24	OK
15281	2026-09-21 01:15	69.74	OK	15282	2026-09-21 01:16	70.87	OK
15283	2026-09-21 01:17	72.87	OK	15284	2026-09-21 01:18	70.87	OK
15285	2026-09-21 01:19	70.00	OK	15286	2026-09-21 01:20	72.75	OK
15287	2026-09-21 01:21	72.74	OK	15288	2026-09-21 01:22	71.96	OK
15289	2026-09-21 01:23	70.64	OK	15290	2026-09-21 01:24	71.19	OK
15291	2026-09-21 01:25	73.40	OK	15292	2026-09-21 01:26	69.81	OK
15293	2026-09-21 01:27	72.86	OK	15294	2026-09-21 01:28	71.72	OK
15295	2026-09-21 01:29	70.04	OK	15296	2026-09-21 01:30	72.99	OK
15297	2026-09-21 01:31	70.55	OK	15298	2026-09-21 01:32	72.96	OK
15299	2026-09-21 01:33	71.31	OK	15300	2026-09-21 01:34	71.68	OK
15301	2026-09-21 01:35	70.63	OK	15302	2026-09-21 01:36	70.42	OK
15303	2026-09-21 01:37	69.18	OK	15304	2026-09-21 01:38	72.73	OK
15305	2026-09-21 01:39	72.24	OK	15306	2026-09-21 01:40	73.60	OK
15307	2026-09-21 01:41	71.35	OK	15308	2026-09-21 01:42	70.25	OK
1530	2026-09-21 01:43	70.57	OK	1531	2026-09-21 01:44	69.76	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
15311	2026-09-21 01:45	70.68	OK	15312	2026-09-21 01:46	70.17	OK
15313	2026-09-21 01:47	68.95	OK	15314	2026-09-21 01:48	70.52	OK
15315	2026-09-21 01:49	68.46	OK	15316	2026-09-21 01:50	71.60	OK
15317	2026-09-21 01:51	67.60	OK	15318	2026-09-21 01:52	71.47	OK
15319	2026-09-21 01:53	72.05	OK	15320	2026-09-21 01:54	72.03	OK
15321	2026-09-21 01:55	72.12	OK	15322	2026-09-21 01:56	72.00	OK
15323	2026-09-21 01:57	70.57	OK	15324	2026-09-21 01:58	70.00	OK
15325	2026-09-21 01:59	70.17	OK	15326	2026-09-21 02:00	71.21	OK
15327	2026-09-21 02:01	71.21	OK	15328	2026-09-21 02:02	71.13	OK
15329	2026-09-21 02:03	70.85	OK	15330	2026-09-21 02:04	68.02	OK
15331	2026-09-21 02:05	71.64	OK	15332	2026-09-21 02:06	69.22	OK
15333	2026-09-21 02:07	67.36	OK	15334	2026-09-21 02:08	68.08	OK
15335	2026-09-21 02:09	70.78	OK	15336	2026-09-21 02:10	70.44	OK
15337	2026-09-21 02:11	70.91	OK	15338	2026-09-21 02:12	71.77	OK
15339	2026-09-21 02:13	67.77	OK	15340	2026-09-21 02:14	67.82	OK
15341	2026-09-21 02:15	70.72	OK	15342	2026-09-21 02:16	71.05	OK
15343	2026-09-21 02:17	68.59	OK	15344	2026-09-21 02:18	71.57	OK
15345	2026-09-21 02:19	70.02	OK	15346	2026-09-21 02:20	70.41	OK
15347	2026-09-21 02:21	70.10	OK	15348	2026-09-21 02:22	70.44	OK
15349	2026-09-21 02:23	70.83	OK	15350	2026-09-21 02:24	70.64	OK
15351	2026-09-21 02:25	71.64	OK	15352	2026-09-21 02:26	68.64	OK
15353	2026-09-21 02:27	70.99	OK	15354	2026-09-21 02:28	71.18	OK
15355	2026-09-21 02:29	69.06	OK	15356	2026-09-21 02:30	70.01	OK
15357	2026-09-21 02:31	70.49	OK	15358	2026-09-21 02:32	67.85	OK
15359	2026-09-21 02:33	71.99	OK	15360	2026-09-21 02:34	68.19	OK
15361	2026-09-21 02:35	67.82	OK	15362	2026-09-21 02:36	69.93	OK
15363	2026-09-21 02:37	69.46	OK	15364	2026-09-21 02:38	70.05	OK
15365	2026-09-21 02:39	71.00	OK	15366	2026-09-21 02:40	69.46	OK
15367	2026-09-21 02:41	66.88	OK	15368	2026-09-21 02:42	71.03	OK
1536	2026-09-21 02:43	68.48	OK	1537	2026-09-21 02:44	69.26	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
15371	2026-09-21 02:45	67.93	OK	15372	2026-09-21 02:46	68.50	OK
15373	2026-09-21 02:47	66.42	OK	15374	2026-09-21 02:48	70.64	OK
15375	2026-09-21 02:49	70.57	OK	15376	2026-09-21 02:50	69.49	OK
15377	2026-09-21 02:51	71.45	OK	15378	2026-09-21 02:52	69.13	OK
15379	2026-09-21 02:53	69.37	OK	15380	2026-09-21 02:54	68.61	OK
15381	2026-09-21 02:55	67.52	OK	15382	2026-09-21 02:56	69.31	OK
15383	2026-09-21 02:57	68.21	OK	15384	2026-09-21 02:58	68.44	OK
15385	2026-09-21 02:59	69.27	OK	15386	2026-09-21 03:00	68.10	OK
15387	2026-09-21 03:01	69.33	OK	15388	2026-09-21 03:02	69.43	OK
15389	2026-09-21 03:03	67.24	OK	15390	2026-09-21 03:04	69.58	OK
15391	2026-09-21 03:05	69.64	OK	15392	2026-09-21 03:06	67.47	OK
15393	2026-09-21 03:07	66.84	OK	15394	2026-09-21 03:08	68.60	OK
15395	2026-09-21 03:09	68.14	OK	15396	2026-09-21 03:10	68.31	OK
15397	2026-09-21 03:11	67.59	OK	15398	2026-09-21 03:12	66.60	OK
15399	2026-09-21 03:13	68.62	OK	15400	2026-09-21 03:14	69.86	OK
15401	2026-09-21 03:15	68.46	OK	15402	2026-09-21 03:16	68.31	OK
15403	2026-09-21 03:17	68.88	OK	15404	2026-09-21 03:18	67.75	OK
15405	2026-09-21 03:19	67.65	OK	15406	2026-09-21 03:20	66.85	OK
15407	2026-09-21 03:21	66.53	OK	15408	2026-09-21 03:22	67.39	OK
15409	2026-09-21 03:23	67.02	OK	15410	2026-09-21 03:24	70.24	OK
15411	2026-09-21 03:25	67.31	OK	15412	2026-09-21 03:26	69.49	OK
15413	2026-09-21 03:27	67.25	OK	15414	2026-09-21 03:28	67.50	OK
15415	2026-09-21 03:29	66.96	OK	15416	2026-09-21 03:30	67.93	OK
15417	2026-09-21 03:31	67.97	OK	15418	2026-09-21 03:32	69.66	OK
15419	2026-09-21 03:33	66.91	OK	15420	2026-09-21 03:34	66.79	OK
15421	2026-09-21 03:35	68.12	OK	15422	2026-09-21 03:36	70.44	OK
15423	2026-09-21 03:37	68.80	OK	15424	2026-09-21 03:38	68.40	OK
15425	2026-09-21 03:39	66.84	OK	15426	2026-09-21 03:40	66.76	OK
15427	2026-09-21 03:41	67.87	OK	15428	2026-09-21 03:42	65.82	OK
1542	2026-09-21 03:43	66.08	OK	1543	2026-09-21 03:44	66.64	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
15431	2026-09-21 03:45	66.43	OK	15432	2026-09-21 03:46	69.16	OK
15433	2026-09-21 03:47	67.96	OK	15434	2026-09-21 03:48	67.12	OK
15435	2026-09-21 03:49	65.60	OK	15436	2026-09-21 03:50	68.62	OK
15437	2026-09-21 03:51	69.07	OK	15438	2026-09-21 03:52	65.46	OK
15439	2026-09-21 03:53	67.81	OK	15440	2026-09-21 03:54	65.79	OK
15441	2026-09-21 03:55	68.37	OK	15442	2026-09-21 03:56	68.64	OK
15443	2026-09-21 03:57	67.19	OK	15444	2026-09-21 03:58	69.10	OK
15445	2026-09-21 03:59	66.75	OK	15446	2026-09-21 04:00	68.96	OK
15447	2026-09-21 04:01	67.68	OK	15448	2026-09-21 04:02	66.94	OK
15449	2026-09-21 04:03	69.43	OK	15450	2026-09-21 04:04	64.72	OK
15451	2026-09-21 04:05	68.26	OK	15452	2026-09-21 04:06	66.09	OK
15453	2026-09-21 04:07	66.07	OK	15454	2026-09-21 04:08	67.02	OK
15455	2026-09-21 04:09	66.99	OK	15456	2026-09-21 04:10	66.74	OK
15457	2026-09-21 04:11	66.59	OK	15458	2026-09-21 04:12	67.85	OK
15459	2026-09-21 04:13	65.48	OK	15460	2026-09-21 04:14	69.55	OK
15461	2026-09-21 04:15	67.81	OK	15462	2026-09-21 04:16	66.25	OK
15463	2026-09-21 04:17	67.50	OK	15464	2026-09-21 04:18	66.75	OK
15465	2026-09-21 04:19	68.90	OK	15466	2026-09-21 04:20	68.24	OK
15467	2026-09-21 04:21	68.33	OK	15468	2026-09-21 04:22	64.36	OK
15469	2026-09-21 04:23	68.26	OK	15470	2026-09-21 04:24	65.88	OK
15471	2026-09-21 04:25	66.10	OK	15472	2026-09-21 04:26	66.56	OK
15473	2026-09-21 04:27	64.61	OK	15474	2026-09-21 04:28	64.19	OK
15475	2026-09-21 04:29	66.81	OK	15476	2026-09-21 04:30	67.14	OK
15477	2026-09-21 04:31	65.84	OK	15478	2026-09-21 04:32	64.98	OK
15479	2026-09-21 04:33	68.38	OK	15480	2026-09-21 04:34	66.75	OK
15481	2026-09-21 04:35	67.15	OK	15482	2026-09-21 04:36	64.83	OK
15483	2026-09-21 04:37	65.81	OK	15484	2026-09-21 04:38	65.43	OK
15485	2026-09-21 04:39	66.72	OK	15486	2026-09-21 04:40	63.78	OK
15487	2026-09-21 04:41	64.90	OK	15488	2026-09-21 04:42	65.96	OK
1548	2026-09-21 04:43	65.90	OK	1549	2026-09-21 04:44	67.12	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
15491	2026-09-21 04:45	64.89	OK	15492	2026-09-21 04:46	67.13	OK
15493	2026-09-21 04:47	67.28	OK	15494	2026-09-21 04:48	66.22	OK
15495	2026-09-21 04:49	66.97	OK	15496	2026-09-21 04:50	65.70	OK
15497	2026-09-21 04:51	66.16	OK	15498	2026-09-21 04:52	67.00	OK
15499	2026-09-21 04:53	63.91	OK	15500	2026-09-21 04:54	65.01	OK
15501	2026-09-21 04:55	65.33	OK	15502	2026-09-21 04:56	65.96	OK
15503	2026-09-21 04:57	66.97	OK	15504	2026-09-21 04:58	65.62	OK
15505	2026-09-21 04:59	62.78	OK	15506	2026-09-21 05:00	65.30	OK
15507	2026-09-21 05:01	65.63	OK	15508	2026-09-21 05:02	66.58	OK
15509	2026-09-21 05:03	64.17	OK	15510	2026-09-21 05:04	62.58	OK
15511	2026-09-21 05:05	67.05	OK	15512	2026-09-21 05:06	67.08	OK
15513	2026-09-21 05:07	67.40	OK	15514	2026-09-21 05:08	67.27	OK
15515	2026-09-21 05:09	64.71	OK	15516	2026-09-21 05:10	64.86	OK
15517	2026-09-21 05:11	64.13	OK	15518	2026-09-21 05:12	64.37	OK
15519	2026-09-21 05:13	64.99	OK	15520	2026-09-21 05:14	63.49	OK
15521	2026-09-21 05:15	65.40	OK	15522	2026-09-21 05:16	65.47	OK
15523	2026-09-21 05:17	66.29	OK	15524	2026-09-21 05:18	64.58	OK
15525	2026-09-21 05:19	65.81	OK	15526	2026-09-21 05:20	65.56	OK
15527	2026-09-21 05:21	64.39	OK	15528	2026-09-21 05:22	66.01	OK
15529	2026-09-21 05:23	64.78	OK	15530	2026-09-21 05:24	65.94	OK
15531	2026-09-21 05:25	67.32	OK	15532	2026-09-21 05:26	64.32	OK
15533	2026-09-21 05:27	65.45	OK	15534	2026-09-21 05:28	63.91	OK
15535	2026-09-21 05:29	63.77	OK	15536	2026-09-21 05:30	63.42	OK
15537	2026-09-21 05:31	64.70	OK	15538	2026-09-21 05:32	64.92	OK
15539	2026-09-21 05:33	63.34	OK	15540	2026-09-21 05:34	65.15	OK
15541	2026-09-21 05:35	66.51	OK	15542	2026-09-21 05:36	66.25	OK
15543	2026-09-21 05:37	63.63	OK	15544	2026-09-21 05:38	62.16	OK
15545	2026-09-21 05:39	62.95	OK	15546	2026-09-21 05:40	64.56	OK
15547	2026-09-21 05:41	64.59	OK	15548	2026-09-21 05:42	64.10	OK
15549	2026-09-21 05:43	63.64	OK	15550	2026-09-21 05:44	63.39	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
15551	2026-09-21 05:45	64.59	OK	15552	2026-09-21 05:46	62.30	OK
15553	2026-09-21 05:47	65.86	OK	15554	2026-09-21 05:48	63.47	OK
15555	2026-09-21 05:49	64.38	OK	15556	2026-09-21 05:50	65.94	OK
15557	2026-09-21 05:51	65.26	OK	15558	2026-09-21 05:52	62.44	OK
15559	2026-09-21 05:53	65.66	OK	15560	2026-09-21 05:54	62.89	OK
15561	2026-09-21 05:55	62.57	OK	15562	2026-09-21 05:56	63.26	OK
15563	2026-09-21 05:57	62.31	OK	15564	2026-09-21 05:58	63.69	OK
15565	2026-09-21 05:59	65.86	OK	15566	2026-09-21 06:00	62.18	OK
15567	2026-09-21 06:01	63.94	OK	15568	2026-09-21 06:02	61.35	OK
15569	2026-09-21 06:03	65.47	OK	15570	2026-09-21 06:04	66.53	OK
15571	2026-09-21 06:05	65.15	OK	15572	2026-09-21 06:06	64.66	OK
15573	2026-09-21 06:07	62.32	OK	15574	2026-09-21 06:08	63.08	OK
15575	2026-09-21 06:09	61.33	OK	15576	2026-09-21 06:10	63.29	OK
15577	2026-09-21 06:11	62.25	OK	15578	2026-09-21 06:12	65.86	OK
15579	2026-09-21 06:13	61.90	OK	15580	2026-09-21 06:14	64.35	OK
15581	2026-09-21 06:15	64.54	OK	15582	2026-09-21 06:16	61.37	OK
15583	2026-09-21 06:17	63.87	OK	15584	2026-09-21 06:18	65.85	OK
15585	2026-09-21 06:19	64.03	OK	15586	2026-09-21 06:20	63.67	OK
15587	2026-09-21 06:21	63.62	OK	15588	2026-09-21 06:22	62.42	OK
15589	2026-09-21 06:23	65.02	OK	15590	2026-09-21 06:24	64.57	OK
15591	2026-09-21 06:25	64.14	OK	15592	2026-09-21 06:26	64.40	OK
15593	2026-09-21 06:27	63.31	OK	15594	2026-09-21 06:28	63.20	OK
15595	2026-09-21 06:29	61.50	OK	15596	2026-09-21 06:30	61.87	OK
15597	2026-09-21 06:31	65.44	OK	15598	2026-09-21 06:32	63.06	OK
15599	2026-09-21 06:33	64.12	OK	15600	2026-09-21 06:34	63.37	OK
15601	2026-09-21 06:35	64.30	OK	15602	2026-09-21 06:36	63.15	OK
15603	2026-09-21 06:37	64.63	OK	15604	2026-09-21 06:38	64.11	OK
15605	2026-09-21 06:39	62.52	OK	15606	2026-09-21 06:40	62.36	OK
15607	2026-09-21 06:41	61.61	OK	15608	2026-09-21 06:42	60.39	OK
1560	2026-09-21 06:43	61.45	OK	1561	2026-09-21 06:44	61.82	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
15611	2026-09-21 06:45	61.69	OK	15612	2026-09-21 06:46	62.85	OK
15613	2026-09-21 06:47	63.66	OK	15614	2026-09-21 06:48	62.53	OK
15615	2026-09-21 06:49	63.68	OK	15616	2026-09-21 06:50	65.59	OK
15617	2026-09-21 06:51	62.01	OK	15618	2026-09-21 06:52	64.37	OK
15619	2026-09-21 06:53	61.96	OK	15620	2026-09-21 06:54	63.35	OK
15621	2026-09-21 06:55	60.12	OK	15622	2026-09-21 06:56	63.23	OK
15623	2026-09-21 06:57	61.11	OK	15624	2026-09-21 06:58	63.61	OK
15625	2026-09-21 06:59	62.76	OK	15626	2026-09-21 07:00	63.30	OK
15627	2026-09-21 07:01	62.97	OK	15628	2026-09-21 07:02	62.89	OK
15629	2026-09-21 07:03	62.66	OK	15630	2026-09-21 07:04	61.31	OK
15631	2026-09-21 07:05	58.95	OK	15632	2026-09-21 07:06	64.30	OK
15633	2026-09-21 07:07	60.67	OK	15634	2026-09-21 07:08	61.59	OK
15635	2026-09-21 07:09	62.17	OK	15636	2026-09-21 07:10	61.93	OK
15637	2026-09-21 07:11	62.66	OK	15638	2026-09-21 07:12	61.77	OK
15639	2026-09-21 07:13	61.46	OK	15640	2026-09-21 07:14	62.33	OK
15641	2026-09-21 07:15	61.79	OK	15642	2026-09-21 07:16	60.65	OK
15643	2026-09-21 07:17	61.99	OK	15644	2026-09-21 07:18	60.10	OK
15645	2026-09-21 07:19	61.56	OK	15646	2026-09-21 07:20	63.02	OK
15647	2026-09-21 07:21	60.18	OK	15648	2026-09-21 07:22	62.19	OK
15649	2026-09-21 07:23	61.52	OK	15650	2026-09-21 07:24	61.09	OK
15651	2026-09-21 07:25	61.64	OK	15652	2026-09-21 07:26	60.80	OK
15653	2026-09-21 07:27	62.85	OK	15654	2026-09-21 07:28	63.86	OK
15655	2026-09-21 07:29	61.46	OK	15656	2026-09-21 07:30	62.70	OK
15657	2026-09-21 07:31	61.65	OK	15658	2026-09-21 07:32	61.04	OK
15659	2026-09-21 07:33	59.81	OK	15660	2026-09-21 07:34	62.50	OK
15661	2026-09-21 07:35	61.68	OK	15662	2026-09-21 07:36	60.04	OK
15663	2026-09-21 07:37	62.23	OK	15664	2026-09-21 07:38	60.76	OK
15665	2026-09-21 07:39	62.62	OK	15666	2026-09-21 07:40	60.13	OK
15667	2026-09-21 07:41	59.90	OK	15668	2026-09-21 07:42	60.64	OK
1566	2026-09-21 07:43	64.22	OK	1567	2026-09-21 07:44	63.58	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
15671	2026-09-21 07:45	61.93	OK	15672	2026-09-21 07:46	62.14	OK
15673	2026-09-21 07:47	60.54	OK	15674	2026-09-21 07:48	61.02	OK
15675	2026-09-21 07:49	59.17	OK	15676	2026-09-21 07:50	60.67	OK
15677	2026-09-21 07:51	61.39	OK	15678	2026-09-21 07:52	64.26	OK
15679	2026-09-21 07:53	62.30	OK	15680	2026-09-21 07:54	60.45	OK
15681	2026-09-21 07:55	60.46	OK	15682	2026-09-21 07:56	61.41	OK
15683	2026-09-21 07:57	61.94	OK	15684	2026-09-21 07:58	61.27	OK
15685	2026-09-21 07:59	61.88	OK	15686	2026-09-21 08:00	61.98	OK
15687	2026-09-21 08:01	60.33	OK	15688	2026-09-21 08:02	59.06	OK
15689	2026-09-21 08:03	59.29	OK	15690	2026-09-21 08:04	61.94	OK
15691	2026-09-21 08:05	59.33	OK	15692	2026-09-21 08:06	62.12	OK
15693	2026-09-21 08:07	60.38	OK	15694	2026-09-21 08:08	60.38	OK
15695	2026-09-21 08:09	60.17	OK	15696	2026-09-21 08:10	62.00	OK
15697	2026-09-21 08:11	63.41	OK	15698	2026-09-21 08:12	61.20	OK
15699	2026-09-21 08:13	60.60	OK	15700	2026-09-21 08:14	62.00	OK
15701	2026-09-21 08:15	62.23	OK	15702	2026-09-21 08:16	59.76	OK
15703	2026-09-21 08:17	60.76	OK	15704	2026-09-21 08:18	62.42	OK
15705	2026-09-21 08:19	59.19	OK	15706	2026-09-21 08:20	60.82	OK
15707	2026-09-21 08:21	62.03	OK	15708	2026-09-21 08:22	58.99	OK
15709	2026-09-21 08:23	61.60	OK	15710	2026-09-21 08:24	58.33	OK
15711	2026-09-21 08:25	60.62	OK	15712	2026-09-21 08:26	59.18	OK
15713	2026-09-21 08:27	60.74	OK	15714	2026-09-21 08:28	60.13	OK
15715	2026-09-21 08:29	60.00	OK	15716	2026-09-21 08:30	63.54	OK
15717	2026-09-21 08:31	61.23	OK	15718	2026-09-21 08:32	60.59	OK
15719	2026-09-21 08:33	60.53	OK	15720	2026-09-21 08:34	61.43	OK
15721	2026-09-21 08:35	62.88	OK	15722	2026-09-21 08:36	60.47	OK
15723	2026-09-21 08:37	58.40	OK	15724	2026-09-21 08:38	62.05	OK
15725	2026-09-21 08:39	59.30	OK	15726	2026-09-21 08:40	61.94	OK
15727	2026-09-21 08:41	59.13	OK	15728	2026-09-21 08:42	61.79	OK
15729	2026-09-21 08:43	58.31	OK	15730	2026-09-21 08:44	59.35	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
15731	2026-09-21 08:45	62.19	OK	15732	2026-09-21 08:46	58.19	OK
15733	2026-09-21 08:47	59.54	OK	15734	2026-09-21 08:48	59.61	OK
15735	2026-09-21 08:49	60.83	OK	15736	2026-09-21 08:50	61.18	OK
15737	2026-09-21 08:51	59.24	OK	15738	2026-09-21 08:52	61.66	OK
15739	2026-09-21 08:53	60.83	OK	15740	2026-09-21 08:54	60.81	OK
15741	2026-09-21 08:55	59.73	OK	15742	2026-09-21 08:56	59.42	OK
15743	2026-09-21 08:57	62.37	OK	15744	2026-09-21 08:58	61.32	OK
15745	2026-09-21 08:59	57.52	OK	15746	2026-09-21 09:00	60.44	OK
15747	2026-09-21 09:01	60.89	OK	15748	2026-09-21 09:02	60.27	OK
15749	2026-09-21 09:03	62.01	OK	15750	2026-09-21 09:04	62.08	OK
15751	2026-09-21 09:05	59.82	OK	15752	2026-09-21 09:06	60.30	OK
15753	2026-09-21 09:07	61.13	OK	15754	2026-09-21 09:08	61.02	OK
15755	2026-09-21 09:09	60.14	OK	15756	2026-09-21 09:10	59.43	OK
15757	2026-09-21 09:11	59.12	OK	15758	2026-09-21 09:12	58.37	OK
15759	2026-09-21 09:13	61.22	OK	15760	2026-09-21 09:14	60.40	OK
15761	2026-09-21 09:15	58.36	OK	15762	2026-09-21 09:16	59.19	OK
15763	2026-09-21 09:17	59.55	OK	15764	2026-09-21 09:18	59.65	OK
15765	2026-09-21 09:19	57.95	OK	15766	2026-09-21 09:20	58.36	OK
15767	2026-09-21 09:21	59.63	OK	15768	2026-09-21 09:22	59.44	OK
15769	2026-09-21 09:23	57.28	OK	15770	2026-09-21 09:24	59.08	OK
15771	2026-09-21 09:25	59.54	OK	15772	2026-09-21 09:26	60.63	OK
15773	2026-09-21 09:27	58.83	OK	15774	2026-09-21 09:28	63.44	OK
15775	2026-09-21 09:29	62.02	OK	15776	2026-09-21 09:30	61.40	OK
15777	2026-09-21 09:31	60.25	OK	15778	2026-09-21 09:32	59.73	OK
15779	2026-09-21 09:33	57.04	OK	15780	2026-09-21 09:34	59.37	OK
15781	2026-09-21 09:35	58.40	OK	15782	2026-09-21 09:36	60.54	OK
15783	2026-09-21 09:37	61.62	OK	15784	2026-09-21 09:38	58.71	OK
15785	2026-09-21 09:39	59.36	OK	15786	2026-09-21 09:40	59.36	OK
15787	2026-09-21 09:41	59.25	OK	15788	2026-09-21 09:42	57.03	OK
1578	2026-09-21 09:43	58.30	OK	1579	2026-09-21 09:44	62.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
15791	2026-09-21 09:45	58.59	OK	15792	2026-09-21 09:46	58.50	OK
15793	2026-09-21 09:47	60.19	OK	15794	2026-09-21 09:48	57.30	OK
15795	2026-09-21 09:49	59.60	OK	15796	2026-09-21 09:50	59.05	OK
15797	2026-09-21 09:51	58.74	OK	15798	2026-09-21 09:52	59.44	OK
15799	2026-09-21 09:53	59.84	OK	15800	2026-09-21 09:54	57.67	OK
15801	2026-09-21 09:55	58.58	OK	15802	2026-09-21 09:56	59.19	OK
15803	2026-09-21 09:57	59.34	OK	15804	2026-09-21 09:58	60.88	OK
15805	2026-09-21 09:59	59.07	OK	15806	2026-09-21 10:00	58.06	OK
15807	2026-09-21 10:01	58.64	OK	15808	2026-09-21 10:02	60.42	OK
15809	2026-09-21 10:03	59.73	OK	15810	2026-09-21 10:04	60.67	OK
15811	2026-09-21 10:05	61.82	OK	15812	2026-09-21 10:06	61.68	OK
15813	2026-09-21 10:07	61.06	OK	15814	2026-09-21 10:08	60.59	OK
15815	2026-09-21 10:09	59.20	OK	15816	2026-09-21 10:10	59.75	OK
15817	2026-09-21 10:11	60.71	OK	15818	2026-09-21 10:12	58.28	OK
15819	2026-09-21 10:13	62.67	OK	15820	2026-09-21 10:14	59.34	OK
15821	2026-09-21 10:15	60.41	OK	15822	2026-09-21 10:16	59.64	OK
15823	2026-09-21 10:17	60.21	OK	15824	2026-09-21 10:18	57.41	OK
15825	2026-09-21 10:19	59.85	OK	15826	2026-09-21 10:20	60.69	OK
15827	2026-09-21 10:21	59.98	OK	15828	2026-09-21 10:22	60.32	OK
15829	2026-09-21 10:23	58.97	OK	15830	2026-09-21 10:24	60.00	OK
15831	2026-09-21 10:25	60.38	OK	15832	2026-09-21 10:26	57.59	OK
15833	2026-09-21 10:27	59.64	OK	15834	2026-09-21 10:28	58.50	OK
15835	2026-09-21 10:29	58.51	OK	15836	2026-09-21 10:30	58.64	OK
15837	2026-09-21 10:31	58.42	OK	15838	2026-09-21 10:32	61.59	OK
15839	2026-09-21 10:33	59.47	OK	15840	2026-09-21 10:34	61.30	OK
15841	2026-09-21 10:35	60.59	OK	15842	2026-09-21 10:36	60.62	OK
15843	2026-09-21 10:37	58.65	OK	15844	2026-09-21 10:38	59.84	OK
15845	2026-09-21 10:39	59.09	OK	15846	2026-09-21 10:40	59.88	OK
15847	2026-09-21 10:41	59.83	OK	15848	2026-09-21 10:42	60.01	OK
1584	2026-09-21 10:43	58.47	OK	1585	2026-09-21 10:44	57.86	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
15851	2026-09-21 10:45	61.91	OK	15852	2026-09-21 10:46	57.97	OK
15853	2026-09-21 10:47	60.77	OK	15854	2026-09-21 10:48	57.22	OK
15855	2026-09-21 10:49	59.51	OK	15856	2026-09-21 10:50	59.02	OK
15857	2026-09-21 10:51	60.21	OK	15858	2026-09-21 10:52	60.52	OK
15859	2026-09-21 10:53	57.80	OK	15860	2026-09-21 10:54	59.75	OK
15861	2026-09-21 10:55	57.89	OK	15862	2026-09-21 10:56	60.27	OK
15863	2026-09-21 10:57	60.70	OK	15864	2026-09-21 10:58	60.12	OK
15865	2026-09-21 10:59	59.93	OK	15866	2026-09-21 11:00	59.15	OK
15867	2026-09-21 11:01	59.86	OK	15868	2026-09-21 11:02	58.09	OK
15869	2026-09-21 11:03	57.84	OK	15870	2026-09-21 11:04	62.81	OK
15871	2026-09-21 11:05	61.41	OK	15872	2026-09-21 11:06	57.51	OK
15873	2026-09-21 11:07	59.29	OK	15874	2026-09-21 11:08	59.61	OK
15875	2026-09-21 11:09	62.21	OK	15876	2026-09-21 11:10	60.81	OK
15877	2026-09-21 11:11	59.00	OK	15878	2026-09-21 11:12	59.95	OK
15879	2026-09-21 11:13	61.16	OK	15880	2026-09-21 11:14	59.05	OK
15881	2026-09-21 11:15	58.27	OK	15882	2026-09-21 11:16	58.81	OK
15883	2026-09-21 11:17	60.21	OK	15884	2026-09-21 11:18	59.81	OK
15885	2026-09-21 11:19	60.19	OK	15886	2026-09-21 11:20	59.14	OK
15887	2026-09-21 11:21	61.11	OK	15888	2026-09-21 11:22	61.29	OK
15889	2026-09-21 11:23	61.50	OK	15890	2026-09-21 11:24	62.60	OK
15891	2026-09-21 11:25	58.74	OK	15892	2026-09-21 11:26	59.61	OK
15893	2026-09-21 11:27	60.91	OK	15894	2026-09-21 11:28	60.30	OK
15895	2026-09-21 11:29	58.81	OK	15896	2026-09-21 11:30	60.49	OK
15897	2026-09-21 11:31	58.73	OK	15898	2026-09-21 11:32	59.89	OK
15899	2026-09-21 11:33	59.07	OK	15900	2026-09-21 11:34	59.17	OK
15901	2026-09-21 11:35	58.43	OK	15902	2026-09-21 11:36	59.78	OK
15903	2026-09-21 11:37	60.33	OK	15904	2026-09-21 11:38	60.29	OK
15905	2026-09-21 11:39	57.43	OK	15906	2026-09-21 11:40	62.31	OK
15907	2026-09-21 11:41	60.05	OK	15908	2026-09-21 11:42	60.09	OK
15909	2026-09-21 11:43	57.85	OK	1591	2026-09-21 11:44	57.31	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
15911	2026-09-21 11:45	59.78	OK	15912	2026-09-21 11:46	59.25	OK
15913	2026-09-21 11:47	59.05	OK	15914	2026-09-21 11:48	61.48	OK
15915	2026-09-21 11:49	60.20	OK	15916	2026-09-21 11:50	59.26	OK
15917	2026-09-21 11:51	58.48	OK	15918	2026-09-21 11:52	58.36	OK
15919	2026-09-21 11:53	62.63	OK	15920	2026-09-21 11:54	63.14	OK
15921	2026-09-21 11:55	60.35	OK	15922	2026-09-21 11:56	59.97	OK
15923	2026-09-21 11:57	59.32	OK	15924	2026-09-21 11:58	59.65	OK
15925	2026-09-21 11:59	62.23	OK	15926	2026-09-21 12:00	58.27	OK
15927	2026-09-21 12:01	57.34	OK	15928	2026-09-21 12:02	62.31	OK
15929	2026-09-21 12:03	60.63	OK	15930	2026-09-21 12:04	61.15	OK
15931	2026-09-21 12:05	57.55	OK	15932	2026-09-21 12:06	61.54	OK
15933	2026-09-21 12:07	58.85	OK	15934	2026-09-21 12:08	60.47	OK
15935	2026-09-21 12:09	58.21	OK	15936	2026-09-21 12:10	61.26	OK
15937	2026-09-21 12:11	59.73	OK	15938	2026-09-21 12:12	61.86	OK
15939	2026-09-21 12:13	58.17	OK	15940	2026-09-21 12:14	60.93	OK
15941	2026-09-21 12:15	61.34	OK	15942	2026-09-21 12:16	60.52	OK
15943	2026-09-21 12:17	61.67	OK	15944	2026-09-21 12:18	60.35	OK
15945	2026-09-21 12:19	59.97	OK	15946	2026-09-21 12:20	61.52	OK
15947	2026-09-21 12:21	59.29	OK	15948	2026-09-21 12:22	60.91	OK
15949	2026-09-21 12:23	61.95	OK	15950	2026-09-21 12:24	59.81	OK
15951	2026-09-21 12:25	58.39	OK	15952	2026-09-21 12:26	61.50	OK
15953	2026-09-21 12:27	62.08	OK	15954	2026-09-21 12:28	58.55	OK
15955	2026-09-21 12:29	59.93	OK	15956	2026-09-21 12:30	61.04	OK
15957	2026-09-21 12:31	61.28	OK	15958	2026-09-21 12:32	58.97	OK
15959	2026-09-21 12:33	59.74	OK	15960	2026-09-21 12:34	61.78	OK
15961	2026-09-21 12:35	60.45	OK	15962	2026-09-21 12:36	62.28	OK
15963	2026-09-21 12:37	59.48	OK	15964	2026-09-21 12:38	60.54	OK
15965	2026-09-21 12:39	58.16	OK	15966	2026-09-21 12:40	59.62	OK
15967	2026-09-21 12:41	59.68	OK	15968	2026-09-21 12:42	62.93	OK
15969	2026-09-21 12:43	61.67	OK	15970	2026-09-21 12:44	57.72	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
15971	2026-09-21 12:45	59.34	OK	15972	2026-09-21 12:46	58.98	OK
15973	2026-09-21 12:47	60.87	OK	15974	2026-09-21 12:48	58.91	OK
15975	2026-09-21 12:49	59.02	OK	15976	2026-09-21 12:50	59.23	OK
15977	2026-09-21 12:51	60.61	OK	15978	2026-09-21 12:52	62.27	OK
15979	2026-09-21 12:53	61.25	OK	15980	2026-09-21 12:54	60.71	OK
15981	2026-09-21 12:55	60.76	OK	15982	2026-09-21 12:56	58.22	OK
15983	2026-09-21 12:57	59.49	OK	15984	2026-09-21 12:58	62.05	OK
15985	2026-09-21 12:59	60.28	OK	15986	2026-09-21 13:00	59.20	OK
15987	2026-09-21 13:01	63.43	OK	15988	2026-09-21 13:02	59.54	OK
15989	2026-09-21 13:03	60.76	OK	15990	2026-09-21 13:04	61.25	OK
15991	2026-09-21 13:05	61.46	OK	15992	2026-09-21 13:06	58.64	OK
15993	2026-09-21 13:07	62.74	OK	15994	2026-09-21 13:08	61.86	OK
15995	2026-09-21 13:09	60.69	OK	15996	2026-09-21 13:10	62.14	OK
15997	2026-09-21 13:11	61.45	OK	15998	2026-09-21 13:12	63.19	OK
15999	2026-09-21 13:13	59.54	OK	16000	2026-09-21 13:14	61.81	OK
16001	2026-09-21 13:15	59.81	OK	16002	2026-09-21 13:16	62.06	OK
16003	2026-09-21 13:17	61.21	OK	16004	2026-09-21 13:18	62.98	OK
16005	2026-09-21 13:19	59.07	OK	16006	2026-09-21 13:20	61.18	OK
16007	2026-09-21 13:21	60.31	OK	16008	2026-09-21 13:22	62.70	OK
16009	2026-09-21 13:23	64.21	OK	16010	2026-09-21 13:24	60.54	OK
16011	2026-09-21 13:25	61.54	OK	16012	2026-09-21 13:26	63.17	OK
16013	2026-09-21 13:27	64.08	OK	16014	2026-09-21 13:28	59.76	OK
16015	2026-09-21 13:29	59.75	OK	16016	2026-09-21 13:30	63.13	OK
16017	2026-09-21 13:31	59.56	OK	16018	2026-09-21 13:32	59.25	OK
16019	2026-09-21 13:33	63.82	OK	16020	2026-09-21 13:34	60.37	OK
16021	2026-09-21 13:35	59.87	OK	16022	2026-09-21 13:36	60.67	OK
16023	2026-09-21 13:37	62.31	OK	16024	2026-09-21 13:38	59.97	OK
16025	2026-09-21 13:39	60.34	OK	16026	2026-09-21 13:40	60.71	OK
16027	2026-09-21 13:41	63.71	OK	16028	2026-09-21 13:42	61.43	OK
1602	2026-09-21 13:43	59.34	OK	1603	2026-09-21 13:44	60.36	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
16031	2026-09-21 13:45	61.80	OK	16032	2026-09-21 13:46	61.92	OK
16033	2026-09-21 13:47	61.97	OK	16034	2026-09-21 13:48	61.80	OK
16035	2026-09-21 13:49	63.65	OK	16036	2026-09-21 13:50	63.38	OK
16037	2026-09-21 13:51	63.52	OK	16038	2026-09-21 13:52	62.33	OK
16039	2026-09-21 13:53	63.11	OK	16040	2026-09-21 13:54	62.85	OK
16041	2026-09-21 13:55	61.67	OK	16042	2026-09-21 13:56	62.82	OK
16043	2026-09-21 13:57	61.94	OK	16044	2026-09-21 13:58	61.77	OK
16045	2026-09-21 13:59	61.95	OK	16046	2026-09-21 14:00	61.53	OK
16047	2026-09-21 14:01	61.04	OK	16048	2026-09-21 14:02	63.47	OK
16049	2026-09-21 14:03	60.29	OK	16050	2026-09-21 14:04	60.40	OK
16051	2026-09-21 14:05	60.02	OK	16052	2026-09-21 14:06	62.58	OK
16053	2026-09-21 14:07	61.88	OK	16054	2026-09-21 14:08	62.70	OK
16055	2026-09-21 14:09	61.76	OK	16056	2026-09-21 14:10	61.43	OK
16057	2026-09-21 14:11	62.77	OK	16058	2026-09-21 14:12	64.99	OK
16059	2026-09-21 14:13	61.70	OK	16060	2026-09-21 14:14	63.83	OK
16061	2026-09-21 14:15	62.53	OK	16062	2026-09-21 14:16	62.58	OK
16063	2026-09-21 14:17	62.26	OK	16064	2026-09-21 14:18	60.38	OK
16065	2026-09-21 14:19	61.27	OK	16066	2026-09-21 14:20	59.83	OK
16067	2026-09-21 14:21	61.82	OK	16068	2026-09-21 14:22	60.27	OK
16069	2026-09-21 14:23	61.49	OK	16070	2026-09-21 14:24	63.80	OK
16071	2026-09-21 14:25	64.06	OK	16072	2026-09-21 14:26	60.64	OK
16073	2026-09-21 14:27	62.00	OK	16074	2026-09-21 14:28	60.17	OK
16075	2026-09-21 14:29	61.84	OK	16076	2026-09-21 14:30	63.58	OK
16077	2026-09-21 14:31	62.26	OK	16078	2026-09-21 14:32	61.26	OK
16079	2026-09-21 14:33	64.49	OK	16080	2026-09-21 14:34	61.91	OK
16081	2026-09-21 14:35	61.86	OK	16082	2026-09-21 14:36	63.66	OK
16083	2026-09-21 14:37	64.06	OK	16084	2026-09-21 14:38	63.63	OK
16085	2026-09-21 14:39	63.38	OK	16086	2026-09-21 14:40	61.98	OK
16087	2026-09-21 14:41	62.66	OK	16088	2026-09-21 14:42	62.41	OK
1608	2026-09-21 14:43	62.08	OK	1609	2026-09-21 14:44	63.47	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
16091	2026-09-21 14:45	63.73	OK	16092	2026-09-21 14:46	63.28	OK
16093	2026-09-21 14:47	62.43	OK	16094	2026-09-21 14:48	60.75	OK
16095	2026-09-21 14:49	63.66	OK	16096	2026-09-21 14:50	62.40	OK
16097	2026-09-21 14:51	63.47	OK	16098	2026-09-21 14:52	62.37	OK
16099	2026-09-21 14:53	62.68	OK	16100	2026-09-21 14:54	61.87	OK
16101	2026-09-21 14:55	62.49	OK	16102	2026-09-21 14:56	63.15	OK
16103	2026-09-21 14:57	61.73	OK	16104	2026-09-21 14:58	62.99	OK
16105	2026-09-21 14:59	63.13	OK	16106	2026-09-21 15:00	63.72	OK
16107	2026-09-21 15:01	62.99	OK	16108	2026-09-21 15:02	63.55	OK
16109	2026-09-21 15:03	62.30	OK	16110	2026-09-21 15:04	61.94	OK
16111	2026-09-21 15:05	63.62	OK	16112	2026-09-21 15:06	65.23	OK
16113	2026-09-21 15:07	63.84	OK	16114	2026-09-21 15:08	65.32	OK
16115	2026-09-21 15:09	62.02	OK	16116	2026-09-21 15:10	61.15	OK
16117	2026-09-21 15:11	64.48	OK	16118	2026-09-21 15:12	63.61	OK
16119	2026-09-21 15:13	65.62	OK	16120	2026-09-21 15:14	61.34	OK
16121	2026-09-21 15:15	62.03	OK	16122	2026-09-21 15:16	64.34	OK
16123	2026-09-21 15:17	62.01	OK	16124	2026-09-21 15:18	63.11	OK
16125	2026-09-21 15:19	63.48	OK	16126	2026-09-21 15:20	62.94	OK
16127	2026-09-21 15:21	63.83	OK	16128	2026-09-21 15:22	63.89	OK
16129	2026-09-21 15:23	65.52	OK	16130	2026-09-21 15:24	65.27	OK
16131	2026-09-21 15:25	63.92	OK	16132	2026-09-21 15:26	64.00	OK
16133	2026-09-21 15:27	66.70	OK	16134	2026-09-21 15:28	64.23	OK
16135	2026-09-21 15:29	64.76	OK	16136	2026-09-21 15:30	62.79	OK
16137	2026-09-21 15:31	63.27	OK	16138	2026-09-21 15:32	64.66	OK
16139	2026-09-21 15:33	63.36	OK	16140	2026-09-21 15:34	65.61	OK
16141	2026-09-21 15:35	64.08	OK	16142	2026-09-21 15:36	62.86	OK
16143	2026-09-21 15:37	66.44	OK	16144	2026-09-21 15:38	64.12	OK
16145	2026-09-21 15:39	62.75	OK	16146	2026-09-21 15:40	66.05	OK
16147	2026-09-21 15:41	63.82	OK	16148	2026-09-21 15:42	66.47	OK
16149	2026-09-21 15:43	64.98	OK	16150	2026-09-21 15:44	63.90	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
16151	2026-09-21 15:45	64.78	OK	16152	2026-09-21 15:46	60.98	OK
16153	2026-09-21 15:47	65.77	OK	16154	2026-09-21 15:48	63.24	OK
16155	2026-09-21 15:49	64.97	OK	16156	2026-09-21 15:50	65.11	OK
16157	2026-09-21 15:51	65.39	OK	16158	2026-09-21 15:52	65.40	OK
16159	2026-09-21 15:53	65.05	OK	16160	2026-09-21 15:54	66.50	OK
16161	2026-09-21 15:55	65.65	OK	16162	2026-09-21 15:56	65.56	OK
16163	2026-09-21 15:57	63.83	OK	16164	2026-09-21 15:58	64.04	OK
16165	2026-09-21 15:59	64.59	OK	16166	2026-09-21 16:00	64.46	OK
16167	2026-09-21 16:01	64.78	OK	16168	2026-09-21 16:02	63.27	OK
16169	2026-09-21 16:03	65.79	OK	16170	2026-09-21 16:04	63.34	OK
16171	2026-09-21 16:05	65.92	OK	16172	2026-09-21 16:06	65.02	OK
16173	2026-09-21 16:07	65.06	OK	16174	2026-09-21 16:08	64.53	OK
16175	2026-09-21 16:09	64.51	OK	16176	2026-09-21 16:10	66.20	OK
16177	2026-09-21 16:11	66.34	OK	16178	2026-09-21 16:12	63.36	OK
16179	2026-09-21 16:13	64.97	OK	16180	2026-09-21 16:14	63.78	OK
16181	2026-09-21 16:15	63.86	OK	16182	2026-09-21 16:16	62.72	OK
16183	2026-09-21 16:17	67.18	OK	16184	2026-09-21 16:18	64.91	OK
16185	2026-09-21 16:19	66.48	OK	16186	2026-09-21 16:20	64.90	OK
16187	2026-09-21 16:21	66.20	OK	16188	2026-09-21 16:22	63.01	OK
16189	2026-09-21 16:23	67.10	OK	16190	2026-09-21 16:24	67.60	OK
16191	2026-09-21 16:25	64.48	OK	16192	2026-09-21 16:26	66.25	OK
16193	2026-09-21 16:27	66.84	OK	16194	2026-09-21 16:28	65.06	OK
16195	2026-09-21 16:29	64.18	OK	16196	2026-09-21 16:30	63.76	OK
16197	2026-09-21 16:31	68.25	OK	16198	2026-09-21 16:32	68.41	OK
16199	2026-09-21 16:33	64.18	OK	16200	2026-09-21 16:34	65.86	OK
16201	2026-09-21 16:35	66.17	OK	16202	2026-09-21 16:36	65.51	OK
16203	2026-09-21 16:37	64.15	OK	16204	2026-09-21 16:38	67.96	OK
16205	2026-09-21 16:39	66.14	OK	16206	2026-09-21 16:40	65.88	OK
16207	2026-09-21 16:41	67.11	OK	16208	2026-09-21 16:42	68.33	OK
1620	2026-09-21 16:43	66.57	OK	1621	2026-09-21 16:44	64.93	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
16211	2026-09-21 16:45	66.02	OK	16212	2026-09-21 16:46	64.82	OK
16213	2026-09-21 16:47	64.13	OK	16214	2026-09-21 16:48	67.11	OK
16215	2026-09-21 16:49	67.41	OK	16216	2026-09-21 16:50	65.55	OK
16217	2026-09-21 16:51	67.02	OK	16218	2026-09-21 16:52	67.69	OK
16219	2026-09-21 16:53	67.67	OK	16220	2026-09-21 16:54	66.68	OK
16221	2026-09-21 16:55	64.27	OK	16222	2026-09-21 16:56	65.05	OK
16223	2026-09-21 16:57	63.21	OK	16224	2026-09-21 16:58	67.22	OK
16225	2026-09-21 16:59	65.97	OK	16226	2026-09-21 17:00	65.50	OK
16227	2026-09-21 17:01	68.44	OK	16228	2026-09-21 17:02	67.98	OK
16229	2026-09-21 17:03	63.79	OK	16230	2026-09-21 17:04	66.97	OK
16231	2026-09-21 17:05	67.05	OK	16232	2026-09-21 17:06	67.04	OK
16233	2026-09-21 17:07	67.36	OK	16234	2026-09-21 17:08	67.64	OK
16235	2026-09-21 17:09	66.68	OK	16236	2026-09-21 17:10	69.74	OK
16237	2026-09-21 17:11	69.61	OK	16238	2026-09-21 17:12	69.79	OK
16239	2026-09-21 17:13	67.98	OK	16240	2026-09-21 17:14	67.45	OK
16241	2026-09-21 17:15	66.19	OK	16242	2026-09-21 17:16	66.50	OK
16243	2026-09-21 17:17	65.73	OK	16244	2026-09-21 17:18	67.25	OK
16245	2026-09-21 17:19	65.94	OK	16246	2026-09-21 17:20	67.82	OK
16247	2026-09-21 17:21	68.00	OK	16248	2026-09-21 17:22	64.72	OK
16249	2026-09-21 17:23	66.52	OK	16250	2026-09-21 17:24	67.30	OK
16251	2026-09-21 17:25	66.24	OK	16252	2026-09-21 17:26	68.59	OK
16253	2026-09-21 17:27	66.21	OK	16254	2026-09-21 17:28	68.52	OK
16255	2026-09-21 17:29	64.48	OK	16256	2026-09-21 17:30	67.28	OK
16257	2026-09-21 17:31	64.99	OK	16258	2026-09-21 17:32	66.07	OK
16259	2026-09-21 17:33	69.28	OK	16260	2026-09-21 17:34	67.98	OK
16261	2026-09-21 17:35	66.18	OK	16262	2026-09-21 17:36	65.46	OK
16263	2026-09-21 17:37	67.96	OK	16264	2026-09-21 17:38	68.48	OK
16265	2026-09-21 17:39	66.58	OK	16266	2026-09-21 17:40	67.76	OK
16267	2026-09-21 17:41	66.93	OK	16268	2026-09-21 17:42	68.62	OK
1626	2026-09-21 17:43	66.38	OK	1627	2026-09-21 17:44	65.66	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
16271	2026-09-21 17:45	68.80	OK	16272	2026-09-21 17:46	66.90	OK
16273	2026-09-21 17:47	68.74	OK	16274	2026-09-21 17:48	66.93	OK
16275	2026-09-21 17:49	68.91	OK	16276	2026-09-21 17:50	68.01	OK
16277	2026-09-21 17:51	70.39	OK	16278	2026-09-21 17:52	70.46	OK
16279	2026-09-21 17:53	68.33	OK	16280	2026-09-21 17:54	68.05	OK
16281	2026-09-21 17:55	65.90	OK	16282	2026-09-21 17:56	70.02	OK
16283	2026-09-21 17:57	66.68	OK	16284	2026-09-21 17:58	68.70	OK
16285	2026-09-21 17:59	68.70	OK	16286	2026-09-21 18:00	68.85	OK
16287	2026-09-21 18:01	68.30	OK	16288	2026-09-21 18:02	68.20	OK
16289	2026-09-21 18:03	68.63	OK	16290	2026-09-21 18:04	67.08	OK
16291	2026-09-21 18:05	67.76	OK	16292	2026-09-21 18:06	67.50	OK
16293	2026-09-21 18:07	67.83	OK	16294	2026-09-21 18:08	67.85	OK
16295	2026-09-21 18:09	68.85	OK	16296	2026-09-21 18:10	68.35	OK
16297	2026-09-21 18:11	67.57	OK	16298	2026-09-21 18:12	68.03	OK
16299	2026-09-21 18:13	69.92	OK	16300	2026-09-21 18:14	71.10	OK
16301	2026-09-21 18:15	69.61	OK	16302	2026-09-21 18:16	69.95	OK
16303	2026-09-21 18:17	68.58	OK	16304	2026-09-21 18:18	68.83	OK
16305	2026-09-21 18:19	69.82	OK	16306	2026-09-21 18:20	68.58	OK
16307	2026-09-21 18:21	69.99	OK	16308	2026-09-21 18:22	71.04	OK
16309	2026-09-21 18:23	67.48	OK	16310	2026-09-21 18:24	69.77	OK
16311	2026-09-21 18:25	71.15	OK	16312	2026-09-21 18:26	67.85	OK
16313	2026-09-21 18:27	70.28	OK	16314	2026-09-21 18:28	67.72	OK
16315	2026-09-21 18:29	68.19	OK	16316	2026-09-21 18:30	69.10	OK
16317	2026-09-21 18:31	68.55	OK	16318	2026-09-21 18:32	69.97	OK
16319	2026-09-21 18:33	69.25	OK	16320	2026-09-21 18:34	68.90	OK
16321	2026-09-21 18:35	68.98	OK	16322	2026-09-21 18:36	69.48	OK
16323	2026-09-21 18:37	66.83	OK	16324	2026-09-21 18:38	68.28	OK
16325	2026-09-21 18:39	70.05	OK	16326	2026-09-21 18:40	69.91	OK
16327	2026-09-21 18:41	69.01	OK	16328	2026-09-21 18:42	71.42	OK
16329	2026-09-21 18:43	70.94	OK	16330	2026-09-21 18:44	73.01	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
16331	2026-09-21 18:45	70.20	OK	16332	2026-09-21 18:46	68.68	OK
16333	2026-09-21 18:47	70.32	OK	16334	2026-09-21 18:48	68.05	OK
16335	2026-09-21 18:49	68.35	OK	16336	2026-09-21 18:50	67.82	OK
16337	2026-09-21 18:51	70.19	OK	16338	2026-09-21 18:52	70.77	OK
16339	2026-09-21 18:53	70.71	OK	16340	2026-09-21 18:54	71.02	OK
16341	2026-09-21 18:55	70.08	OK	16342	2026-09-21 18:56	71.23	OK
16343	2026-09-21 18:57	70.68	OK	16344	2026-09-21 18:58	69.26	OK
16345	2026-09-21 18:59	70.19	OK	16346	2026-09-21 19:00	69.93	OK
16347	2026-09-21 19:01	69.37	OK	16348	2026-09-21 19:02	68.80	OK
16349	2026-09-21 19:03	70.38	OK	16350	2026-09-21 19:04	68.79	OK
16351	2026-09-21 19:05	71.28	OK	16352	2026-09-21 19:06	71.38	OK
16353	2026-09-21 19:07	70.51	OK	16354	2026-09-21 19:08	71.15	OK
16355	2026-09-21 19:09	71.51	OK	16356	2026-09-21 19:10	68.06	OK
16357	2026-09-21 19:11	68.35	OK	16358	2026-09-21 19:12	68.87	OK
16359	2026-09-21 19:13	69.59	OK	16360	2026-09-21 19:14	69.86	OK
16361	2026-09-21 19:15	69.27	OK	16362	2026-09-21 19:16	67.70	OK
16363	2026-09-21 19:17	69.92	OK	16364	2026-09-21 19:18	71.56	OK
16365	2026-09-21 19:19	69.34	OK	16366	2026-09-21 19:20	72.39	OK
16367	2026-09-21 19:21	67.78	OK	16368	2026-09-21 19:22	70.86	OK
16369	2026-09-21 19:23	71.06	OK	16370	2026-09-21 19:24	72.14	OK
16371	2026-09-21 19:25	69.38	OK	16372	2026-09-21 19:26	70.38	OK
16373	2026-09-21 19:27	70.07	OK	16374	2026-09-21 19:28	70.12	OK
16375	2026-09-21 19:29	68.96	OK	16376	2026-09-21 19:30	71.72	OK
16377	2026-09-21 19:31	70.20	OK	16378	2026-09-21 19:32	69.37	OK
16379	2026-09-21 19:33	72.63	OK	16380	2026-09-21 19:34	71.45	OK
16381	2026-09-21 19:35	69.95	OK	16382	2026-09-21 19:36	70.38	OK
16383	2026-09-21 19:37	71.87	OK	16384	2026-09-21 19:38	68.87	OK
16385	2026-09-21 19:39	71.65	OK	16386	2026-09-21 19:40	70.20	OK
16387	2026-09-21 19:41	69.75	OK	16388	2026-09-21 19:42	71.94	OK
1638	2026-09-21 19:43	69.83	OK	1639	2026-09-21 19:44	69.23	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
16391	2026-09-21 19:45	71.13	OK	16392	2026-09-21 19:46	71.07	OK
16393	2026-09-21 19:47	70.77	OK	16394	2026-09-21 19:48	67.90	OK
16395	2026-09-21 19:49	71.87	OK	16396	2026-09-21 19:50	71.16	OK
16397	2026-09-21 19:51	72.38	OK	16398	2026-09-21 19:52	72.48	OK
16399	2026-09-21 19:53	70.95	OK	16400	2026-09-21 19:54	70.31	OK
16401	2026-09-21 19:55	70.94	OK	16402	2026-09-21 19:56	71.33	OK
16403	2026-09-21 19:57	71.25	OK	16404	2026-09-21 19:58	70.77	OK
16405	2026-09-21 19:59	72.11	OK	16406	2026-09-21 20:00	71.85	OK
16407	2026-09-21 20:01	71.82	OK	16408	2026-09-21 20:02	71.32	OK
16409	2026-09-21 20:03	69.30	OK	16410	2026-09-21 20:04	70.05	OK
16411	2026-09-21 20:05	72.30	OK	16412	2026-09-21 20:06	72.07	OK
16413	2026-09-21 20:07	70.64	OK	16414	2026-09-21 20:08	70.77	OK
16415	2026-09-21 20:09	70.94	OK	16416	2026-09-21 20:10	72.62	OK
16417	2026-09-21 20:11	71.38	OK	16418	2026-09-21 20:12	70.86	OK
16419	2026-09-21 20:13	69.97	OK	16420	2026-09-21 20:14	71.11	OK
16421	2026-09-21 20:15	72.63	OK	16422	2026-09-21 20:16	69.54	OK
16423	2026-09-21 20:17	70.49	OK	16424	2026-09-21 20:18	72.34	OK
16425	2026-09-21 20:19	68.40	OK	16426	2026-09-21 20:20	70.85	OK
16427	2026-09-21 20:21	72.04	OK	16428	2026-09-21 20:22	70.57	OK
16429	2026-09-21 20:23	73.80	OK	16430	2026-09-21 20:24	69.80	OK
16431	2026-09-21 20:25	70.58	OK	16432	2026-09-21 20:26	72.36	OK
16433	2026-09-21 20:27	71.32	OK	16434	2026-09-21 20:28	70.72	OK
16435	2026-09-21 20:29	69.34	OK	16436	2026-09-21 20:30	71.28	OK
16437	2026-09-21 20:31	70.88	OK	16438	2026-09-21 20:32	71.94	OK
16439	2026-09-21 20:33	70.57	OK	16440	2026-09-21 20:34	73.88	OK
16441	2026-09-21 20:35	73.99	OK	16442	2026-09-21 20:36	73.42	OK
16443	2026-09-21 20:37	73.87	OK	16444	2026-09-21 20:38	72.61	OK
16445	2026-09-21 20:39	70.49	OK	16446	2026-09-21 20:40	73.47	OK
16447	2026-09-21 20:41	70.96	OK	16448	2026-09-21 20:42	72.05	OK
16449	2026-09-21 20:43	73.00	OK	16450	2026-09-21 20:44	72.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
16451	2026-09-21 20:45	74.92	OK	16452	2026-09-21 20:46	70.69	OK
16453	2026-09-21 20:47	71.47	OK	16454	2026-09-21 20:48	73.63	OK
16455	2026-09-21 20:49	70.62	OK	16456	2026-09-21 20:50	71.97	OK
16457	2026-09-21 20:51	72.14	OK	16458	2026-09-21 20:52	70.14	OK
16459	2026-09-21 20:53	72.94	OK	16460	2026-09-21 20:54	71.67	OK
16461	2026-09-21 20:55	72.53	OK	16462	2026-09-21 20:56	72.79	OK
16463	2026-09-21 20:57	71.92	OK	16464	2026-09-21 20:58	72.71	OK
16465	2026-09-21 20:59	70.63	OK	16466	2026-09-21 21:00	72.13	OK
16467	2026-09-21 21:01	72.05	OK	16468	2026-09-21 21:02	72.54	OK
16469	2026-09-21 21:03	70.75	OK	16470	2026-09-21 21:04	72.54	OK
16471	2026-09-21 21:05	72.32	OK	16472	2026-09-21 21:06	70.81	OK
16473	2026-09-21 21:07	70.72	OK	16474	2026-09-21 21:08	75.05	OK
16475	2026-09-21 21:09	72.19	OK	16476	2026-09-21 21:10	74.50	OK
16477	2026-09-21 21:11	71.88	OK	16478	2026-09-21 21:12	75.34	OK
16479	2026-09-21 21:13	72.78	OK	16480	2026-09-21 21:14	74.44	OK
16481	2026-09-21 21:15	71.94	OK	16482	2026-09-21 21:16	71.21	OK
16483	2026-09-21 21:17	72.44	OK	16484	2026-09-21 21:18	74.77	OK
16485	2026-09-21 21:19	69.28	OK	16486	2026-09-21 21:20	72.47	OK
16487	2026-09-21 21:21	71.01	OK	16488	2026-09-21 21:22	71.29	OK
16489	2026-09-21 21:23	72.33	OK	16490	2026-09-21 21:24	75.16	OK
16491	2026-09-21 21:25	73.65	OK	16492	2026-09-21 21:26	71.81	OK
16493	2026-09-21 21:27	72.86	OK	16494	2026-09-21 21:28	73.60	OK
16495	2026-09-21 21:29	73.01	OK	16496	2026-09-21 21:30	70.58	OK
16497	2026-09-21 21:31	73.47	OK	16498	2026-09-21 21:32	73.07	OK
16499	2026-09-21 21:33	71.44	OK	16500	2026-09-21 21:34	74.60	OK
16501	2026-09-21 21:35	71.54	OK	16502	2026-09-21 21:36	74.62	OK
16503	2026-09-21 21:37	71.47	OK	16504	2026-09-21 21:38	73.49	OK
16505	2026-09-21 21:39	70.53	OK	16506	2026-09-21 21:40	71.87	OK
16507	2026-09-21 21:41	72.84	OK	16508	2026-09-21 21:42	73.67	OK
1650	2026-09-21 21:43	74.03	OK	1651	2026-09-21 21:44	72.37	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
16511	2026-09-21 21:45	75.11	OK	16512	2026-09-21 21:46	72.20	OK
16513	2026-09-21 21:47	72.37	OK	16514	2026-09-21 21:48	71.92	OK
16515	2026-09-21 21:49	72.97	OK	16516	2026-09-21 21:50	74.96	OK
16517	2026-09-21 21:51	74.71	OK	16518	2026-09-21 21:52	72.05	OK
16519	2026-09-21 21:53	73.41	OK	16520	2026-09-21 21:54	71.70	OK
16521	2026-09-21 21:55	72.62	OK	16522	2026-09-21 21:56	72.06	OK
16523	2026-09-21 21:57	73.94	OK	16524	2026-09-21 21:58	72.46	OK
16525	2026-09-21 21:59	74.01	OK	16526	2026-09-21 22:00	74.33	OK
16527	2026-09-21 22:01	72.27	OK	16528	2026-09-21 22:02	72.69	OK
16529	2026-09-21 22:03	72.42	OK	16530	2026-09-21 22:04	72.38	OK
16531	2026-09-21 22:05	71.43	OK	16532	2026-09-21 22:06	74.07	OK
16533	2026-09-21 22:07	74.19	OK	16534	2026-09-21 22:08	72.16	OK
16535	2026-09-21 22:09	71.87	OK	16536	2026-09-21 22:10	73.53	OK
16537	2026-09-21 22:11	74.15	OK	16538	2026-09-21 22:12	73.46	OK
16539	2026-09-21 22:13	72.89	OK	16540	2026-09-21 22:14	74.01	OK
16541	2026-09-21 22:15	72.57	OK	16542	2026-09-21 22:16	71.21	OK
16543	2026-09-21 22:17	75.14	OK	16544	2026-09-21 22:18	73.22	OK
16545	2026-09-21 22:19	73.46	OK	16546	2026-09-21 22:20	70.04	OK
16547	2026-09-21 22:21	71.93	OK	16548	2026-09-21 22:22	74.10	OK
16549	2026-09-21 22:23	70.52	OK	16550	2026-09-21 22:24	73.07	OK
16551	2026-09-21 22:25	74.48	OK	16552	2026-09-21 22:26	72.72	OK
16553	2026-09-21 22:27	72.25	OK	16554	2026-09-21 22:28	72.62	OK
16555	2026-09-21 22:29	72.84	OK	16556	2026-09-21 22:30	74.53	OK
16557	2026-09-21 22:31	70.91	OK	16558	2026-09-21 22:32	75.17	OK
16559	2026-09-21 22:33	72.50	OK	16560	2026-09-21 22:34	72.68	OK
16561	2026-09-21 22:35	72.09	OK	16562	2026-09-21 22:36	72.02	OK
16563	2026-09-21 22:37	73.93	OK	16564	2026-09-21 22:38	72.11	OK
16565	2026-09-21 22:39	74.42	OK	16566	2026-09-21 22:40	74.75	OK
16567	2026-09-21 22:41	74.72	OK	16568	2026-09-21 22:42	72.26	OK
16569	2026-09-21 22:43	71.68	OK	16570	2026-09-21 22:44	75.24	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
16571	2026-09-21 22:45	74.36	OK	16572	2026-09-21 22:46	71.23	OK
16573	2026-09-21 22:47	74.60	OK	16574	2026-09-21 22:48	72.44	OK
16575	2026-09-21 22:49	71.60	OK	16576	2026-09-21 22:50	75.22	OK
16577	2026-09-21 22:51	71.76	OK	16578	2026-09-21 22:52	71.70	OK
16579	2026-09-21 22:53	75.19	OK	16580	2026-09-21 22:54	69.82	OK
16581	2026-09-21 22:55	73.42	OK	16582	2026-09-21 22:56	71.58	OK
16583	2026-09-21 22:57	73.00	OK	16584	2026-09-21 22:58	73.60	OK
16585	2026-09-21 22:59	73.60	OK	16586	2026-09-21 23:00	72.24	OK
16587	2026-09-21 23:01	75.21	OK	16588	2026-09-21 23:02	74.20	OK
16589	2026-09-21 23:03	71.20	OK	16590	2026-09-21 23:04	73.83	OK
16591	2026-09-21 23:05	72.95	OK	16592	2026-09-21 23:06	72.90	OK
16593	2026-09-21 23:07	73.38	OK	16594	2026-09-21 23:08	69.94	OK
16595	2026-09-21 23:09	72.08	OK	16596	2026-09-21 23:10	72.50	OK
16597	2026-09-21 23:11	70.61	OK	16598	2026-09-21 23:12	72.60	OK
16599	2026-09-21 23:13	70.28	OK	16600	2026-09-21 23:14	72.71	OK
16601	2026-09-21 23:15	75.32	OK	16602	2026-09-21 23:16	73.15	OK
16603	2026-09-21 23:17	70.73	OK	16604	2026-09-21 23:18	72.95	OK
16605	2026-09-21 23:19	73.39	OK	16606	2026-09-21 23:20	72.83	OK
16607	2026-09-21 23:21	72.52	OK	16608	2026-09-21 23:22	73.39	OK
16609	2026-09-21 23:23	73.29	OK	16610	2026-09-21 23:24	71.38	OK
16611	2026-09-21 23:25	72.50	OK	16612	2026-09-21 23:26	70.53	OK
16613	2026-09-21 23:27	73.68	OK	16614	2026-09-21 23:28	74.77	OK
16615	2026-09-21 23:29	74.66	OK	16616	2026-09-21 23:30	74.35	OK
16617	2026-09-21 23:31	71.98	OK	16618	2026-09-21 23:32	72.38	OK
16619	2026-09-21 23:33	72.23	OK	16620	2026-09-21 23:34	70.72	OK
16621	2026-09-21 23:35	71.81	OK	16622	2026-09-21 23:36	71.62	OK
16623	2026-09-21 23:37	72.73	OK	16624	2026-09-21 23:38	70.84	OK
16625	2026-09-21 23:39	74.44	OK	16626	2026-09-21 23:40	73.69	OK
16627	2026-09-21 23:41	71.94	OK	16628	2026-09-21 23:42	72.81	OK
1662	2026-09-21 23:43	74.82	OK	1663	2026-09-21 23:44	73.49	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
16631	2026-09-21 23:45	73.82	OK	16632	2026-09-21 23:46	74.51	OK
16633	2026-09-21 23:47	73.61	OK	16634	2026-09-21 23:48	72.98	OK
16635	2026-09-21 23:49	72.05	OK	16636	2026-09-21 23:50	72.77	OK
16637	2026-09-21 23:51	73.22	OK	16638	2026-09-21 23:52	72.38	OK
16639	2026-09-21 23:53	69.78	OK	16640	2026-09-21 23:54	74.45	OK
16641	2026-09-21 23:55	69.47	OK	16642	2026-09-21 23:56	73.02	OK
16643	2026-09-21 23:57	71.51	OK	16644	2026-09-21 23:58	72.91	OK
16645	2026-09-21 23:59	71.89	OK	16646	2026-09-22 00:00	72.75	OK
16647	2026-09-22 00:01	71.71	OK	16648	2026-09-22 00:02	72.74	OK
16649	2026-09-22 00:03	73.27	OK	16650	2026-09-22 00:04	70.05	OK
16651	2026-09-22 00:05	72.85	OK	16652	2026-09-22 00:06	71.30	OK
16653	2026-09-22 00:07	73.25	OK	16654	2026-09-22 00:08	74.04	OK
16655	2026-09-22 00:09	72.57	OK	16656	2026-09-22 00:10	72.33	OK
16657	2026-09-22 00:11	74.76	OK	16658	2026-09-22 00:12	71.78	OK
16659	2026-09-22 00:13	73.03	OK	16660	2026-09-22 00:14	72.04	OK
16661	2026-09-22 00:15	70.38	OK	16662	2026-09-22 00:16	71.92	OK
16663	2026-09-22 00:17	72.31	OK	16664	2026-09-22 00:18	71.46	OK
16665	2026-09-22 00:19	70.11	OK	16666	2026-09-22 00:20	70.55	OK
16667	2026-09-22 00:21	73.43	OK	16668	2026-09-22 00:22	70.69	OK
16669	2026-09-22 00:23	73.82	OK	16670	2026-09-22 00:24	70.17	OK
16671	2026-09-22 00:25	72.70	OK	16672	2026-09-22 00:26	71.36	OK
16673	2026-09-22 00:27	72.29	OK	16674	2026-09-22 00:28	70.44	OK
16675	2026-09-22 00:29	71.43	OK	16676	2026-09-22 00:30	73.44	OK
16677	2026-09-22 00:31	70.81	OK	16678	2026-09-22 00:32	73.01	OK
16679	2026-09-22 00:33	73.54	OK	16680	2026-09-22 00:34	71.05	OK
16681	2026-09-22 00:35	71.46	OK	16682	2026-09-22 00:36	73.15	OK
16683	2026-09-22 00:37	71.44	OK	16684	2026-09-22 00:38	73.65	OK
16685	2026-09-22 00:39	70.80	OK	16686	2026-09-22 00:40	71.36	OK
16687	2026-09-22 00:41	73.63	OK	16688	2026-09-22 00:42	69.07	OK
1668	2026-09-22 00:43	74.77	OK	1669	2026-09-22 00:44	73.06	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
16691	2026-09-22 00:45	72.40	OK	16692	2026-09-22 00:46	73.54	OK
16693	2026-09-22 00:47	73.92	OK	16694	2026-09-22 00:48	69.79	OK
16695	2026-09-22 00:49	72.80	OK	16696	2026-09-22 00:50	70.02	OK
16697	2026-09-22 00:51	72.91	OK	16698	2026-09-22 00:52	72.31	OK
16699	2026-09-22 00:53	69.19	OK	16700	2026-09-22 00:54	70.93	OK
16701	2026-09-22 00:55	71.34	OK	16702	2026-09-22 00:56	72.53	OK
16703	2026-09-22 00:57	71.61	OK	16704	2026-09-22 00:58	72.44	OK
16705	2026-09-22 00:59	73.84	OK	16706	2026-09-22 01:00	73.28	OK
16707	2026-09-22 01:01	72.46	OK	16708	2026-09-22 01:02	70.11	OK
16709	2026-09-22 01:03	68.53	OK	16710	2026-09-22 01:04	71.07	OK
16711	2026-09-22 01:05	68.65	OK	16712	2026-09-22 01:06	69.94	OK
16713	2026-09-22 01:07	72.41	OK	16714	2026-09-22 01:08	72.44	OK
16715	2026-09-22 01:09	72.13	OK	16716	2026-09-22 01:10	70.71	OK
16717	2026-09-22 01:11	72.77	OK	16718	2026-09-22 01:12	72.66	OK
16719	2026-09-22 01:13	71.30	OK	16720	2026-09-22 01:14	71.22	OK
16721	2026-09-22 01:15	68.67	OK	16722	2026-09-22 01:16	68.92	OK
16723	2026-09-22 01:17	69.86	OK	16724	2026-09-22 01:18	72.31	OK
16725	2026-09-22 01:19	69.99	OK	16726	2026-09-22 01:20	72.10	OK
16727	2026-09-22 01:21	70.36	OK	16728	2026-09-22 01:22	71.84	OK
16729	2026-09-22 01:23	71.72	OK	16730	2026-09-22 01:24	71.19	OK
16731	2026-09-22 01:25	70.19	OK	16732	2026-09-22 01:26	72.52	OK
16733	2026-09-22 01:27	71.04	OK	16734	2026-09-22 01:28	71.60	OK
16735	2026-09-22 01:29	70.32	OK	16736	2026-09-22 01:30	70.29	OK
16737	2026-09-22 01:31	70.47	OK	16738	2026-09-22 01:32	68.97	OK
16739	2026-09-22 01:33	70.32	OK	16740	2026-09-22 01:34	70.05	OK
16741	2026-09-22 01:35	71.15	OK	16742	2026-09-22 01:36	71.40	OK
16743	2026-09-22 01:37	70.86	OK	16744	2026-09-22 01:38	68.20	OK
16745	2026-09-22 01:39	73.70	OK	16746	2026-09-22 01:40	71.09	OK
16747	2026-09-22 01:41	71.16	OK	16748	2026-09-22 01:42	71.87	OK
1674	2026-09-22 01:43	71.04	OK	1675	2026-09-22 01:44	69.55	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
16751	2026-09-22 01:45	70.79	OK	16752	2026-09-22 01:46	68.75	OK
16753	2026-09-22 01:47	71.08	OK	16754	2026-09-22 01:48	71.68	OK
16755	2026-09-22 01:49	71.54	OK	16756	2026-09-22 01:50	69.02	OK
16757	2026-09-22 01:51	72.03	OK	16758	2026-09-22 01:52	70.70	OK
16759	2026-09-22 01:53	71.74	OK	16760	2026-09-22 01:54	69.72	OK
16761	2026-09-22 01:55	69.99	OK	16762	2026-09-22 01:56	71.96	OK
16763	2026-09-22 01:57	72.93	OK	16764	2026-09-22 01:58	71.06	OK
16765	2026-09-22 01:59	70.13	OK	16766	2026-09-22 02:00	72.21	OK
16767	2026-09-22 02:01	71.32	OK	16768	2026-09-22 02:02	69.09	OK
16769	2026-09-22 02:03	70.76	OK	16770	2026-09-22 02:04	71.87	OK
16771	2026-09-22 02:05	72.20	OK	16772	2026-09-22 02:06	69.22	OK
16773	2026-09-22 02:07	70.86	OK	16774	2026-09-22 02:08	70.87	OK
16775	2026-09-22 02:09	67.94	OK	16776	2026-09-22 02:10	69.40	OK
16777	2026-09-22 02:11	68.63	OK	16778	2026-09-22 02:12	70.65	OK
16779	2026-09-22 02:13	70.66	OK	16780	2026-09-22 02:14	69.36	OK
16781	2026-09-22 02:15	71.68	OK	16782	2026-09-22 02:16	70.76	OK
16783	2026-09-22 02:17	71.18	OK	16784	2026-09-22 02:18	69.70	OK
16785	2026-09-22 02:19	68.09	OK	16786	2026-09-22 02:20	68.32	OK
16787	2026-09-22 02:21	71.27	OK	16788	2026-09-22 02:22	69.88	OK
16789	2026-09-22 02:23	67.91	OK	16790	2026-09-22 02:24	68.85	OK
16791	2026-09-22 02:25	69.41	OK	16792	2026-09-22 02:26	71.82	OK
16793	2026-09-22 02:27	69.08	OK	16794	2026-09-22 02:28	70.20	OK
16795	2026-09-22 02:29	68.04	OK	16796	2026-09-22 02:30	70.98	OK
16797	2026-09-22 02:31	69.18	OK	16798	2026-09-22 02:32	69.87	OK
16799	2026-09-22 02:33	70.99	OK	16800	2026-09-22 02:34	70.39	OK
16801	2026-09-22 02:35	69.52	OK	16802	2026-09-22 02:36	71.15	OK
16803	2026-09-22 02:37	71.21	OK	16804	2026-09-22 02:38	68.90	OK
16805	2026-09-22 02:39	68.28	OK	16806	2026-09-22 02:40	70.04	OK
16807	2026-09-22 02:41	68.39	OK	16808	2026-09-22 02:42	70.48	OK
1680	2026-09-22 02:43	72.16	OK	1681	2026-09-22 02:44	72.55	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
16811	2026-09-22 02:45	69.17	OK	16812	2026-09-22 02:46	70.16	OK
16813	2026-09-22 02:47	70.15	OK	16814	2026-09-22 02:48	70.27	OK
16815	2026-09-22 02:49	70.82	OK	16816	2026-09-22 02:50	70.48	OK
16817	2026-09-22 02:51	69.80	OK	16818	2026-09-22 02:52	67.64	OK
16819	2026-09-22 02:53	69.00	OK	16820	2026-09-22 02:54	69.09	OK
16821	2026-09-22 02:55	69.86	OK	16822	2026-09-22 02:56	69.81	OK
16823	2026-09-22 02:57	67.47	OK	16824	2026-09-22 02:58	68.49	OK
16825	2026-09-22 02:59	69.71	OK	16826	2026-09-22 03:00	67.34	OK
16827	2026-09-22 03:01	68.03	OK	16828	2026-09-22 03:02	67.52	OK
16829	2026-09-22 03:03	69.57	OK	16830	2026-09-22 03:04	67.77	OK
16831	2026-09-22 03:05	69.93	OK	16832	2026-09-22 03:06	66.42	OK
16833	2026-09-22 03:07	69.83	OK	16834	2026-09-22 03:08	66.83	OK
16835	2026-09-22 03:09	67.20	OK	16836	2026-09-22 03:10	65.84	OK
16837	2026-09-22 03:11	70.83	OK	16838	2026-09-22 03:12	68.36	OK
16839	2026-09-22 03:13	67.34	OK	16840	2026-09-22 03:14	66.78	OK
16841	2026-09-22 03:15	67.99	OK	16842	2026-09-22 03:16	68.61	OK
16843	2026-09-22 03:17	68.68	OK	16844	2026-09-22 03:18	67.68	OK
16845	2026-09-22 03:19	69.76	OK	16846	2026-09-22 03:20	68.30	OK
16847	2026-09-22 03:21	68.98	OK	16848	2026-09-22 03:22	70.73	OK
16849	2026-09-22 03:23	67.21	OK	16850	2026-09-22 03:24	68.78	OK
16851	2026-09-22 03:25	67.59	OK	16852	2026-09-22 03:26	67.62	OK
16853	2026-09-22 03:27	66.15	OK	16854	2026-09-22 03:28	66.91	OK
16855	2026-09-22 03:29	68.26	OK	16856	2026-09-22 03:30	66.92	OK
16857	2026-09-22 03:31	68.68	OK	16858	2026-09-22 03:32	67.58	OK
16859	2026-09-22 03:33	67.67	OK	16860	2026-09-22 03:34	66.68	OK
16861	2026-09-22 03:35	69.81	OK	16862	2026-09-22 03:36	68.23	OK
16863	2026-09-22 03:37	66.97	OK	16864	2026-09-22 03:38	66.92	OK
16865	2026-09-22 03:39	66.83	OK	16866	2026-09-22 03:40	67.87	OK
16867	2026-09-22 03:41	67.93	OK	16868	2026-09-22 03:42	67.79	OK
1686	2026-09-22 03:43	68.31	OK	1687	2026-09-22 03:44	67.51	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
16871	2026-09-22 03:45	69.03	OK	16872	2026-09-22 03:46	67.14	OK
16873	2026-09-22 03:47	67.38	OK	16874	2026-09-22 03:48	68.17	OK
16875	2026-09-22 03:49	67.31	OK	16876	2026-09-22 03:50	66.92	OK
16877	2026-09-22 03:51	66.65	OK	16878	2026-09-22 03:52	66.79	OK
16879	2026-09-22 03:53	67.26	OK	16880	2026-09-22 03:54	67.83	OK
16881	2026-09-22 03:55	67.75	OK	16882	2026-09-22 03:56	67.00	OK
16883	2026-09-22 03:57	68.03	OK	16884	2026-09-22 03:58	67.00	OK
16885	2026-09-22 03:59	68.79	OK	16886	2026-09-22 04:00	67.27	OK
16887	2026-09-22 04:01	68.27	OK	16888	2026-09-22 04:02	68.49	OK
16889	2026-09-22 04:03	68.65	OK	16890	2026-09-22 04:04	66.42	OK
16891	2026-09-22 04:05	66.96	OK	16892	2026-09-22 04:06	66.31	OK
16893	2026-09-22 04:07	64.18	OK	16894	2026-09-22 04:08	66.93	OK
16895	2026-09-22 04:09	66.43	OK	16896	2026-09-22 04:10	67.63	OK
16897	2026-09-22 04:11	65.47	OK	16898	2026-09-22 04:12	66.69	OK
16899	2026-09-22 04:13	66.32	OK	16900	2026-09-22 04:14	68.74	OK
16901	2026-09-22 04:15	67.81	OK	16902	2026-09-22 04:16	67.59	OK
16903	2026-09-22 04:17	66.96	OK	16904	2026-09-22 04:18	67.28	OK
16905	2026-09-22 04:19	65.90	OK	16906	2026-09-22 04:20	66.13	OK
16907	2026-09-22 04:21	66.04	OK	16908	2026-09-22 04:22	68.23	OK
16909	2026-09-22 04:23	63.33	OK	16910	2026-09-22 04:24	66.84	OK
16911	2026-09-22 04:25	68.72	OK	16912	2026-09-22 04:26	66.53	OK
16913	2026-09-22 04:27	68.24	OK	16914	2026-09-22 04:28	65.75	OK
16915	2026-09-22 04:29	69.58	OK	16916	2026-09-22 04:30	67.60	OK
16917	2026-09-22 04:31	65.00	OK	16918	2026-09-22 04:32	63.50	OK
16919	2026-09-22 04:33	65.38	OK	16920	2026-09-22 04:34	66.78	OK
16921	2026-09-22 04:35	64.06	OK	16922	2026-09-22 04:36	66.24	OK
16923	2026-09-22 04:37	66.45	OK	16924	2026-09-22 04:38	67.15	OK
16925	2026-09-22 04:39	65.84	OK	16926	2026-09-22 04:40	66.02	OK
16927	2026-09-22 04:41	66.67	OK	16928	2026-09-22 04:42	63.82	OK
16929	2026-09-22 04:43	63.72	OK	16930	2026-09-22 04:44	64.98	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
16931	2026-09-22 04:45	68.84	OK	16932	2026-09-22 04:46	65.83	OK
16933	2026-09-22 04:47	68.32	OK	16934	2026-09-22 04:48	67.55	OK
16935	2026-09-22 04:49	65.97	OK	16936	2026-09-22 04:50	66.58	OK
16937	2026-09-22 04:51	65.99	OK	16938	2026-09-22 04:52	65.90	OK
16939	2026-09-22 04:53	64.72	OK	16940	2026-09-22 04:54	67.73	OK
16941	2026-09-22 04:55	67.00	OK	16942	2026-09-22 04:56	65.56	OK
16943	2026-09-22 04:57	65.65	OK	16944	2026-09-22 04:58	65.58	OK
16945	2026-09-22 04:59	65.52	OK	16946	2026-09-22 05:00	64.65	OK
16947	2026-09-22 05:01	66.78	OK	16948	2026-09-22 05:02	66.45	OK
16949	2026-09-22 05:03	66.94	OK	16950	2026-09-22 05:04	65.59	OK
16951	2026-09-22 05:05	65.11	OK	16952	2026-09-22 05:06	68.42	OK
16953	2026-09-22 05:07	64.99	OK	16954	2026-09-22 05:08	64.95	OK
16955	2026-09-22 05:09	67.04	OK	16956	2026-09-22 05:10	65.80	OK
16957	2026-09-22 05:11	65.57	OK	16958	2026-09-22 05:12	65.33	OK
16959	2026-09-22 05:13	68.74	OK	16960	2026-09-22 05:14	65.19	OK
16961	2026-09-22 05:15	64.47	OK	16962	2026-09-22 05:16	66.44	OK
16963	2026-09-22 05:17	62.65	OK	16964	2026-09-22 05:18	65.01	OK
16965	2026-09-22 05:19	66.35	OK	16966	2026-09-22 05:20	65.22	OK
16967	2026-09-22 05:21	67.69	OK	16968	2026-09-22 05:22	67.00	OK
16969	2026-09-22 05:23	65.14	OK	16970	2026-09-22 05:24	65.22	OK
16971	2026-09-22 05:25	65.24	OK	16972	2026-09-22 05:26	64.43	OK
16973	2026-09-22 05:27	66.13	OK	16974	2026-09-22 05:28	63.53	OK
16975	2026-09-22 05:29	66.29	OK	16976	2026-09-22 05:30	65.76	OK
16977	2026-09-22 05:31	65.15	OK	16978	2026-09-22 05:32	64.82	OK
16979	2026-09-22 05:33	64.63	OK	16980	2026-09-22 05:34	63.19	OK
16981	2026-09-22 05:35	65.61	OK	16982	2026-09-22 05:36	64.91	OK
16983	2026-09-22 05:37	64.60	OK	16984	2026-09-22 05:38	63.35	OK
16985	2026-09-22 05:39	63.92	OK	16986	2026-09-22 05:40	63.19	OK
16987	2026-09-22 05:41	65.46	OK	16988	2026-09-22 05:42	64.35	OK
16989	2026-09-22 05:43	65.61	OK	16990	2026-09-22 05:44	63.12	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
16991	2026-09-22 05:45	63.70	OK	16992	2026-09-22 05:46	63.72	OK
16993	2026-09-22 05:47	63.53	OK	16994	2026-09-22 05:48	64.68	OK
16995	2026-09-22 05:49	62.95	OK	16996	2026-09-22 05:50	64.35	OK
16997	2026-09-22 05:51	62.43	OK	16998	2026-09-22 05:52	64.04	OK
16999	2026-09-22 05:53	65.94	OK	17000	2026-09-22 05:54	62.69	OK
17001	2026-09-22 05:55	66.76	OK	17002	2026-09-22 05:56	63.27	OK
17003	2026-09-22 05:57	64.31	OK	17004	2026-09-22 05:58	61.53	OK
17005	2026-09-22 05:59	66.55	OK	17006	2026-09-22 06:00	65.06	OK
17007	2026-09-22 06:01	63.67	OK	17008	2026-09-22 06:02	63.86	OK
17009	2026-09-22 06:03	64.47	OK	17010	2026-09-22 06:04	62.25	OK
17011	2026-09-22 06:05	63.11	OK	17012	2026-09-22 06:06	63.10	OK
17013	2026-09-22 06:07	64.02	OK	17014	2026-09-22 06:08	66.06	OK
17015	2026-09-22 06:09	61.47	OK	17016	2026-09-22 06:10	64.68	OK
17017	2026-09-22 06:11	61.90	OK	17018	2026-09-22 06:12	63.52	OK
17019	2026-09-22 06:13	64.96	OK	17020	2026-09-22 06:14	62.08	OK
17021	2026-09-22 06:15	63.60	OK	17022	2026-09-22 06:16	65.17	OK
17023	2026-09-22 06:17	63.29	OK	17024	2026-09-22 06:18	63.54	OK
17025	2026-09-22 06:19	63.37	OK	17026	2026-09-22 06:20	65.17	OK
17027	2026-09-22 06:21	62.45	OK	17028	2026-09-22 06:22	63.80	OK
17029	2026-09-22 06:23	64.08	OK	17030	2026-09-22 06:24	61.97	OK
17031	2026-09-22 06:25	60.71	OK	17032	2026-09-22 06:26	64.54	OK
17033	2026-09-22 06:27	64.55	OK	17034	2026-09-22 06:28	62.68	OK
17035	2026-09-22 06:29	64.35	OK	17036	2026-09-22 06:30	62.52	OK
17037	2026-09-22 06:31	62.66	OK	17038	2026-09-22 06:32	65.53	OK
17039	2026-09-22 06:33	64.60	OK	17040	2026-09-22 06:34	61.18	OK
17041	2026-09-22 06:35	64.69	OK	17042	2026-09-22 06:36	64.30	OK
17043	2026-09-22 06:37	63.32	OK	17044	2026-09-22 06:38	61.84	OK
17045	2026-09-22 06:39	65.23	OK	17046	2026-09-22 06:40	61.10	OK
17047	2026-09-22 06:41	62.51	OK	17048	2026-09-22 06:42	64.04	OK
1704	2026-09-22 06:43	63.29	OK	1705	2026-09-22 06:44	63.38	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
17051	2026-09-22 06:45	60.39	OK	17052	2026-09-22 06:46	62.23	OK
17053	2026-09-22 06:47	62.20	OK	17054	2026-09-22 06:48	61.64	OK
17055	2026-09-22 06:49	62.86	OK	17056	2026-09-22 06:50	63.82	OK
17057	2026-09-22 06:51	62.78	OK	17058	2026-09-22 06:52	62.74	OK
17059	2026-09-22 06:53	61.61	OK	17060	2026-09-22 06:54	63.66	OK
17061	2026-09-22 06:55	61.71	OK	17062	2026-09-22 06:56	62.77	OK
17063	2026-09-22 06:57	63.55	OK	17064	2026-09-22 06:58	62.60	OK
17065	2026-09-22 06:59	63.71	OK	17066	2026-09-22 07:00	59.95	OK
17067	2026-09-22 07:01	62.34	OK	17068	2026-09-22 07:02	59.81	OK
17069	2026-09-22 07:03	61.80	OK	17070	2026-09-22 07:04	64.22	OK
17071	2026-09-22 07:05	62.38	OK	17072	2026-09-22 07:06	62.12	OK
17073	2026-09-22 07:07	64.51	OK	17074	2026-09-22 07:08	63.18	OK
17075	2026-09-22 07:09	64.71	OK	17076	2026-09-22 07:10	60.84	OK
17077	2026-09-22 07:11	62.76	OK	17078	2026-09-22 07:12	62.27	OK
17079	2026-09-22 07:13	59.94	OK	17080	2026-09-22 07:14	60.95	OK
17081	2026-09-22 07:15	61.72	OK	17082	2026-09-22 07:16	59.30	OK
17083	2026-09-22 07:17	59.59	OK	17084	2026-09-22 07:18	61.42	OK
17085	2026-09-22 07:19	61.07	OK	17086	2026-09-22 07:20	60.43	OK
17087	2026-09-22 07:21	60.56	OK	17088	2026-09-22 07:22	60.71	OK
17089	2026-09-22 07:23	62.36	OK	17090	2026-09-22 07:24	62.83	OK
17091	2026-09-22 07:25	61.82	OK	17092	2026-09-22 07:26	63.34	OK
17093	2026-09-22 07:27	63.35	OK	17094	2026-09-22 07:28	59.51	OK
17095	2026-09-22 07:29	62.14	OK	17096	2026-09-22 07:30	61.27	OK
17097	2026-09-22 07:31	62.61	OK	17098	2026-09-22 07:32	63.17	OK
17099	2026-09-22 07:33	63.01	OK	17100	2026-09-22 07:34	61.77	OK
17101	2026-09-22 07:35	61.20	OK	17102	2026-09-22 07:36	62.48	OK
17103	2026-09-22 07:37	62.90	OK	17104	2026-09-22 07:38	61.04	OK
17105	2026-09-22 07:39	60.69	OK	17106	2026-09-22 07:40	59.64	OK
17107	2026-09-22 07:41	58.46	OK	17108	2026-09-22 07:42	61.01	OK
1710	2026-09-22 07:43	60.73	OK	1711	2026-09-22 07:44	61.19	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
17111	2026-09-22 07:45	60.86	OK	17112	2026-09-22 07:46	61.80	OK
17113	2026-09-22 07:47	62.08	OK	17114	2026-09-22 07:48	62.29	OK
17115	2026-09-22 07:49	60.36	OK	17116	2026-09-22 07:50	62.09	OK
17117	2026-09-22 07:51	61.26	OK	17118	2026-09-22 07:52	59.21	OK
17119	2026-09-22 07:53	63.11	OK	17120	2026-09-22 07:54	63.81	OK
17121	2026-09-22 07:55	59.51	OK	17122	2026-09-22 07:56	60.37	OK
17123	2026-09-22 07:57	61.17	OK	17124	2026-09-22 07:58	61.68	OK
17125	2026-09-22 07:59	61.14	OK	17126	2026-09-22 08:00	60.53	OK
17127	2026-09-22 08:01	61.11	OK	17128	2026-09-22 08:02	62.21	OK
17129	2026-09-22 08:03	59.86	OK	17130	2026-09-22 08:04	61.43	OK
17131	2026-09-22 08:05	61.69	OK	17132	2026-09-22 08:06	62.27	OK
17133	2026-09-22 08:07	62.71	OK	17134	2026-09-22 08:08	62.98	OK
17135	2026-09-22 08:09	61.68	OK	17136	2026-09-22 08:10	60.22	OK
17137	2026-09-22 08:11	62.24	OK	17138	2026-09-22 08:12	61.92	OK
17139	2026-09-22 08:13	60.98	OK	17140	2026-09-22 08:14	62.69	OK
17141	2026-09-22 08:15	60.45	OK	17142	2026-09-22 08:16	60.72	OK
17143	2026-09-22 08:17	60.59	OK	17144	2026-09-22 08:18	61.38	OK
17145	2026-09-22 08:19	60.68	OK	17146	2026-09-22 08:20	59.67	OK
17147	2026-09-22 08:21	60.07	OK	17148	2026-09-22 08:22	60.91	OK
17149	2026-09-22 08:23	60.37	OK	17150	2026-09-22 08:24	61.83	OK
17151	2026-09-22 08:25	60.35	OK	17152	2026-09-22 08:26	62.83	OK
17153	2026-09-22 08:27	61.77	OK	17154	2026-09-22 08:28	61.17	OK
17155	2026-09-22 08:29	62.82	OK	17156	2026-09-22 08:30	60.15	OK
17157	2026-09-22 08:31	60.14	OK	17158	2026-09-22 08:32	63.25	OK
17159	2026-09-22 08:33	61.86	OK	17160	2026-09-22 08:34	59.57	OK
17161	2026-09-22 08:35	59.12	OK	17162	2026-09-22 08:36	61.20	OK
17163	2026-09-22 08:37	58.92	OK	17164	2026-09-22 08:38	60.35	OK
17165	2026-09-22 08:39	60.84	OK	17166	2026-09-22 08:40	61.26	OK
17167	2026-09-22 08:41	59.78	OK	17168	2026-09-22 08:42	61.79	OK
1716	2026-09-22 08:43	61.02	OK	1717	2026-09-22 08:44	61.88	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
17171	2026-09-22 08:45	61.18	OK	17172	2026-09-22 08:46	60.24	OK
17173	2026-09-22 08:47	62.39	OK	17174	2026-09-22 08:48	59.98	OK
17175	2026-09-22 08:49	62.54	OK	17176	2026-09-22 08:50	60.54	OK
17177	2026-09-22 08:51	58.90	OK	17178	2026-09-22 08:52	60.94	OK
17179	2026-09-22 08:53	60.18	OK	17180	2026-09-22 08:54	59.29	OK
17181	2026-09-22 08:55	61.69	OK	17182	2026-09-22 08:56	61.77	OK
17183	2026-09-22 08:57	59.69	OK	17184	2026-09-22 08:58	60.95	OK
17185	2026-09-22 08:59	59.19	OK	17186	2026-09-22 09:00	57.63	OK
17187	2026-09-22 09:01	60.51	OK	17188	2026-09-22 09:02	60.08	OK
17189	2026-09-22 09:03	61.97	OK	17190	2026-09-22 09:04	58.45	OK
17191	2026-09-22 09:05	60.16	OK	17192	2026-09-22 09:06	57.76	OK
17193	2026-09-22 09:07	59.25	OK	17194	2026-09-22 09:08	60.24	OK
17195	2026-09-22 09:09	58.90	OK	17196	2026-09-22 09:10	57.61	OK
17197	2026-09-22 09:11	60.55	OK	17198	2026-09-22 09:12	57.43	OK
17199	2026-09-22 09:13	59.63	OK	17200	2026-09-22 09:14	60.92	OK
17201	2026-09-22 09:15	59.33	OK	17202	2026-09-22 09:16	60.01	OK
17203	2026-09-22 09:17	60.50	OK	17204	2026-09-22 09:18	60.85	OK
17205	2026-09-22 09:19	62.08	OK	17206	2026-09-22 09:20	60.57	OK
17207	2026-09-22 09:21	61.58	OK	17208	2026-09-22 09:22	60.93	OK
17209	2026-09-22 09:23	59.95	OK	17210	2026-09-22 09:24	59.88	OK
17211	2026-09-22 09:25	60.60	OK	17212	2026-09-22 09:26	59.97	OK
17213	2026-09-22 09:27	59.18	OK	17214	2026-09-22 09:28	59.24	OK
17215	2026-09-22 09:29	60.54	OK	17216	2026-09-22 09:30	59.87	OK
17217	2026-09-22 09:31	58.73	OK	17218	2026-09-22 09:32	57.13	OK
17219	2026-09-22 09:33	60.02	OK	17220	2026-09-22 09:34	58.70	OK
17221	2026-09-22 09:35	61.02	OK	17222	2026-09-22 09:36	60.45	OK
17223	2026-09-22 09:37	60.14	OK	17224	2026-09-22 09:38	59.72	OK
17225	2026-09-22 09:39	57.31	OK	17226	2026-09-22 09:40	60.74	OK
17227	2026-09-22 09:41	59.40	OK	17228	2026-09-22 09:42	59.18	OK
17229	2026-09-22 09:43	59.11	OK	1723	2026-09-22 09:44	59.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
17231	2026-09-22 09:45	58.42	OK	17232	2026-09-22 09:46	60.31	OK
17233	2026-09-22 09:47	58.75	OK	17234	2026-09-22 09:48	61.52	OK
17235	2026-09-22 09:49	59.81	OK	17236	2026-09-22 09:50	58.08	OK
17237	2026-09-22 09:51	61.08	OK	17238	2026-09-22 09:52	62.12	OK
17239	2026-09-22 09:53	59.42	OK	17240	2026-09-22 09:54	58.98	OK
17241	2026-09-22 09:55	60.25	OK	17242	2026-09-22 09:56	57.51	OK
17243	2026-09-22 09:57	58.49	OK	17244	2026-09-22 09:58	60.97	OK
17245	2026-09-22 09:59	58.74	OK	17246	2026-09-22 10:00	60.15	OK
17247	2026-09-22 10:01	58.98	OK	17248	2026-09-22 10:02	58.55	OK
17249	2026-09-22 10:03	60.46	OK	17250	2026-09-22 10:04	58.56	OK
17251	2026-09-22 10:05	59.46	OK	17252	2026-09-22 10:06	61.37	OK
17253	2026-09-22 10:07	60.86	OK	17254	2026-09-22 10:08	60.39	OK
17255	2026-09-22 10:09	58.47	OK	17256	2026-09-22 10:10	57.24	OK
17257	2026-09-22 10:11	60.73	OK	17258	2026-09-22 10:12	61.24	OK
17259	2026-09-22 10:13	58.03	OK	17260	2026-09-22 10:14	59.24	OK
17261	2026-09-22 10:15	58.99	OK	17262	2026-09-22 10:16	59.65	OK
17263	2026-09-22 10:17	60.68	OK	17264	2026-09-22 10:18	60.94	OK
17265	2026-09-22 10:19	59.66	OK	17266	2026-09-22 10:20	58.59	OK
17267	2026-09-22 10:21	59.73	OK	17268	2026-09-22 10:22	57.75	OK
17269	2026-09-22 10:23	58.35	OK	17270	2026-09-22 10:24	60.06	OK
17271	2026-09-22 10:25	62.24	OK	17272	2026-09-22 10:26	61.73	OK
17273	2026-09-22 10:27	59.78	OK	17274	2026-09-22 10:28	61.22	OK
17275	2026-09-22 10:29	59.41	OK	17276	2026-09-22 10:30	60.15	OK
17277	2026-09-22 10:31	59.19	OK	17278	2026-09-22 10:32	60.56	OK
17279	2026-09-22 10:33	58.06	OK	17280	2026-09-22 10:34	56.90	OK
17281	2026-09-22 10:35	58.42	OK	17282	2026-09-22 10:36	58.51	OK
17283	2026-09-22 10:37	60.35	OK	17284	2026-09-22 10:38	60.78	OK
17285	2026-09-22 10:39	61.73	OK	17286	2026-09-22 10:40	58.48	OK
17287	2026-09-22 10:41	56.80	OK	17288	2026-09-22 10:42	60.10	OK
1728	2026-09-22 10:43	58.76	OK	1729	2026-09-22 10:44	58.47	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
17291	2026-09-22 10:45	58.36	OK	17292	2026-09-22 10:46	58.91	OK
17293	2026-09-22 10:47	57.94	OK	17294	2026-09-22 10:48	59.05	OK
17295	2026-09-22 10:49	60.85	OK	17296	2026-09-22 10:50	59.32	OK
17297	2026-09-22 10:51	59.57	OK	17298	2026-09-22 10:52	60.15	OK
17299	2026-09-22 10:53	60.99	OK	17300	2026-09-22 10:54	58.89	OK
17301	2026-09-22 10:55	59.83	OK	17302	2026-09-22 10:56	60.72	OK
17303	2026-09-22 10:57	60.18	OK	17304	2026-09-22 10:58	58.05	OK
17305	2026-09-22 10:59	59.52	OK	17306	2026-09-22 11:00	58.73	OK
17307	2026-09-22 11:01	59.78	OK	17308	2026-09-22 11:02	61.05	OK
17309	2026-09-22 11:03	61.95	OK	17310	2026-09-22 11:04	59.35	OK
17311	2026-09-22 11:05	58.60	OK	17312	2026-09-22 11:06	60.21	OK
17313	2026-09-22 11:07	61.64	OK	17314	2026-09-22 11:08	58.30	OK
17315	2026-09-22 11:09	62.36	OK	17316	2026-09-22 11:10	62.10	OK
17317	2026-09-22 11:11	60.42	OK	17318	2026-09-22 11:12	57.73	OK
17319	2026-09-22 11:13	58.07	OK	17320	2026-09-22 11:14	59.17	OK
17321	2026-09-22 11:15	60.23	OK	17322	2026-09-22 11:16	59.58	OK
17323	2026-09-22 11:17	60.94	OK	17324	2026-09-22 11:18	62.03	OK
17325	2026-09-22 11:19	60.82	OK	17326	2026-09-22 11:20	59.45	OK
17327	2026-09-22 11:21	58.56	OK	17328	2026-09-22 11:22	57.77	OK
17329	2026-09-22 11:23	58.15	OK	17330	2026-09-22 11:24	58.57	OK
17331	2026-09-22 11:25	58.77	OK	17332	2026-09-22 11:26	62.33	OK
17333	2026-09-22 11:27	58.30	OK	17334	2026-09-22 11:28	61.78	OK
17335	2026-09-22 11:29	59.54	OK	17336	2026-09-22 11:30	60.66	OK
17337	2026-09-22 11:31	61.86	OK	17338	2026-09-22 11:32	60.54	OK
17339	2026-09-22 11:33	60.40	OK	17340	2026-09-22 11:34	60.62	OK
17341	2026-09-22 11:35	58.59	OK	17342	2026-09-22 11:36	61.06	OK
17343	2026-09-22 11:37	58.15	OK	17344	2026-09-22 11:38	56.19	OK
17345	2026-09-22 11:39	61.43	OK	17346	2026-09-22 11:40	58.99	OK
17347	2026-09-22 11:41	59.84	OK	17348	2026-09-22 11:42	60.47	OK
1734	2026-09-22 11:43	60.28	OK	1735	2026-09-22 11:44	59.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
17351	2026-09-22 11:45	58.12	OK	17352	2026-09-22 11:46	60.58	OK
17353	2026-09-22 11:47	59.45	OK	17354	2026-09-22 11:48	59.79	OK
17355	2026-09-22 11:49	59.35	OK	17356	2026-09-22 11:50	59.14	OK
17357	2026-09-22 11:51	60.29	OK	17358	2026-09-22 11:52	58.27	OK
17359	2026-09-22 11:53	60.45	OK	17360	2026-09-22 11:54	60.78	OK
17361	2026-09-22 11:55	57.66	OK	17362	2026-09-22 11:56	60.15	OK
17363	2026-09-22 11:57	60.91	OK	17364	2026-09-22 11:58	60.60	OK
17365	2026-09-22 11:59	58.51	OK	17366	2026-09-22 12:00	60.68	OK
17367	2026-09-22 12:01	61.48	OK	17368	2026-09-22 12:02	60.88	OK
17369	2026-09-22 12:03	59.26	OK	17370	2026-09-22 12:04	59.12	OK
17371	2026-09-22 12:05	60.66	OK	17372	2026-09-22 12:06	60.79	OK
17373	2026-09-22 12:07	58.20	OK	17374	2026-09-22 12:08	58.30	OK
17375	2026-09-22 12:09	57.90	OK	17376	2026-09-22 12:10	61.09	OK
17377	2026-09-22 12:11	62.69	OK	17378	2026-09-22 12:12	59.79	OK
17379	2026-09-22 12:13	58.92	OK	17380	2026-09-22 12:14	58.81	OK
17381	2026-09-22 12:15	59.96	OK	17382	2026-09-22 12:16	60.09	OK
17383	2026-09-22 12:17	60.87	OK	17384	2026-09-22 12:18	57.85	OK
17385	2026-09-22 12:19	62.37	OK	17386	2026-09-22 12:20	59.07	OK
17387	2026-09-22 12:21	59.88	OK	17388	2026-09-22 12:22	58.92	OK
17389	2026-09-22 12:23	56.81	OK	17390	2026-09-22 12:24	60.28	OK
17391	2026-09-22 12:25	60.72	OK	17392	2026-09-22 12:26	61.20	OK
17393	2026-09-22 12:27	59.34	OK	17394	2026-09-22 12:28	59.38	OK
17395	2026-09-22 12:29	59.76	OK	17396	2026-09-22 12:30	59.07	OK
17397	2026-09-22 12:31	60.59	OK	17398	2026-09-22 12:32	58.90	OK
17399	2026-09-22 12:33	58.51	OK	17400	2026-09-22 12:34	60.97	OK
17401	2026-09-22 12:35	58.14	OK	17402	2026-09-22 12:36	60.20	OK
17403	2026-09-22 12:37	61.93	OK	17404	2026-09-22 12:38	60.78	OK
17405	2026-09-22 12:39	59.63	OK	17406	2026-09-22 12:40	60.43	OK
17407	2026-09-22 12:41	60.37	OK	17408	2026-09-22 12:42	60.34	OK
1740	2026-09-22 12:43	62.62	OK	1741	2026-09-22 12:44	60.58	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
17411	2026-09-22 12:45	58.86	OK	17412	2026-09-22 12:46	60.73	OK
17413	2026-09-22 12:47	59.43	OK	17414	2026-09-22 12:48	62.44	OK
17415	2026-09-22 12:49	60.10	OK	17416	2026-09-22 12:50	60.93	OK
17417	2026-09-22 12:51	61.17	OK	17418	2026-09-22 12:52	62.67	OK
17419	2026-09-22 12:53	59.90	OK	17420	2026-09-22 12:54	60.77	OK
17421	2026-09-22 12:55	59.08	OK	17422	2026-09-22 12:56	60.74	OK
17423	2026-09-22 12:57	60.68	OK	17424	2026-09-22 12:58	59.77	OK
17425	2026-09-22 12:59	63.11	OK	17426	2026-09-22 13:00	60.15	OK
17427	2026-09-22 13:01	60.50	OK	17428	2026-09-22 13:02	63.43	OK
17429	2026-09-22 13:03	60.09	OK	17430	2026-09-22 13:04	60.65	OK
17431	2026-09-22 13:05	58.59	OK	17432	2026-09-22 13:06	61.13	OK
17433	2026-09-22 13:07	63.63	OK	17434	2026-09-22 13:08	59.22	OK
17435	2026-09-22 13:09	61.77	OK	17436	2026-09-22 13:10	60.23	OK
17437	2026-09-22 13:11	60.39	OK	17438	2026-09-22 13:12	60.33	OK
17439	2026-09-22 13:13	60.85	OK	17440	2026-09-22 13:14	61.54	OK
17441	2026-09-22 13:15	61.42	OK	17442	2026-09-22 13:16	60.87	OK
17443	2026-09-22 13:17	60.71	OK	17444	2026-09-22 13:18	61.03	OK
17445	2026-09-22 13:19	62.24	OK	17446	2026-09-22 13:20	62.98	OK
17447	2026-09-22 13:21	60.50	OK	17448	2026-09-22 13:22	59.66	OK
17449	2026-09-22 13:23	60.66	OK	17450	2026-09-22 13:24	60.79	OK
17451	2026-09-22 13:25	61.26	OK	17452	2026-09-22 13:26	60.64	OK
17453	2026-09-22 13:27	61.18	OK	17454	2026-09-22 13:28	58.92	OK
17455	2026-09-22 13:29	61.97	OK	17456	2026-09-22 13:30	61.73	OK
17457	2026-09-22 13:31	61.21	OK	17458	2026-09-22 13:32	63.75	OK
17459	2026-09-22 13:33	62.64	OK	17460	2026-09-22 13:34	60.90	OK
17461	2026-09-22 13:35	61.45	OK	17462	2026-09-22 13:36	60.26	OK
17463	2026-09-22 13:37	60.77	OK	17464	2026-09-22 13:38	61.20	OK
17465	2026-09-22 13:39	61.51	OK	17466	2026-09-22 13:40	60.94	OK
17467	2026-09-22 13:41	61.41	OK	17468	2026-09-22 13:42	62.93	OK
1746	2026-09-22 13:43	59.62	OK	1747	2026-09-22 13:44	60.83	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
17471	2026-09-22 13:45	63.03	OK	17472	2026-09-22 13:46	61.92	OK
17473	2026-09-22 13:47	62.46	OK	17474	2026-09-22 13:48	61.13	OK
17475	2026-09-22 13:49	60.43	OK	17476	2026-09-22 13:50	62.32	OK
17477	2026-09-22 13:51	61.11	OK	17478	2026-09-22 13:52	61.71	OK
17479	2026-09-22 13:53	63.50	OK	17480	2026-09-22 13:54	61.51	OK
17481	2026-09-22 13:55	61.47	OK	17482	2026-09-22 13:56	62.84	OK
17483	2026-09-22 13:57	61.55	OK	17484	2026-09-22 13:58	60.26	OK
17485	2026-09-22 13:59	62.62	OK	17486	2026-09-22 14:00	59.38	OK
17487	2026-09-22 14:01	60.65	OK	17488	2026-09-22 14:02	60.88	OK
17489	2026-09-22 14:03	60.85	OK	17490	2026-09-22 14:04	61.47	OK
17491	2026-09-22 14:05	64.07	OK	17492	2026-09-22 14:06	62.64	OK
17493	2026-09-22 14:07	61.29	OK	17494	2026-09-22 14:08	61.81	OK
17495	2026-09-22 14:09	62.49	OK	17496	2026-09-22 14:10	61.28	OK
17497	2026-09-22 14:11	59.66	OK	17498	2026-09-22 14:12	63.79	OK
17499	2026-09-22 14:13	60.54	OK	17500	2026-09-22 14:14	64.82	OK
17501	2026-09-22 14:15	64.20	OK	17502	2026-09-22 14:16	61.31	OK
17503	2026-09-22 14:17	63.19	OK	17504	2026-09-22 14:18	62.69	OK
17505	2026-09-22 14:19	61.87	OK	17506	2026-09-22 14:20	61.36	OK
17507	2026-09-22 14:21	63.50	OK	17508	2026-09-22 14:22	63.15	OK
17509	2026-09-22 14:23	63.17	OK	17510	2026-09-22 14:24	63.00	OK
17511	2026-09-22 14:25	62.04	OK	17512	2026-09-22 14:26	65.11	OK
17513	2026-09-22 14:27	64.37	OK	17514	2026-09-22 14:28	63.96	OK
17515	2026-09-22 14:29	63.88	OK	17516	2026-09-22 14:30	62.08	OK
17517	2026-09-22 14:31	61.48	OK	17518	2026-09-22 14:32	63.34	OK
17519	2026-09-22 14:33	61.46	OK	17520	2026-09-22 14:34	61.87	OK
17521	2026-09-22 14:35	63.85	OK	17522	2026-09-22 14:36	63.36	OK
17523	2026-09-22 14:37	63.56	OK	17524	2026-09-22 14:38	60.70	OK
17525	2026-09-22 14:39	62.31	OK	17526	2026-09-22 14:40	62.64	OK
17527	2026-09-22 14:41	60.55	OK	17528	2026-09-22 14:42	62.11	OK
1752	2026-09-22 14:43	63.26	OK	1753	2026-09-22 14:44	64.22	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
17531	2026-09-22 14:45	62.18	OK	17532	2026-09-22 14:46	62.18	OK
17533	2026-09-22 14:47	62.72	OK	17534	2026-09-22 14:48	62.44	OK
17535	2026-09-22 14:49	61.60	OK	17536	2026-09-22 14:50	63.67	OK
17537	2026-09-22 14:51	62.91	OK	17538	2026-09-22 14:52	65.54	OK
17539	2026-09-22 14:53	64.77	OK	17540	2026-09-22 14:54	63.32	OK
17541	2026-09-22 14:55	65.27	OK	17542	2026-09-22 14:56	62.15	OK
17543	2026-09-22 14:57	63.04	OK	17544	2026-09-22 14:58	62.06	OK
17545	2026-09-22 14:59	62.87	OK	17546	2026-09-22 15:00	62.64	OK
17547	2026-09-22 15:01	62.53	OK	17548	2026-09-22 15:02	66.08	OK
17549	2026-09-22 15:03	64.79	OK	17550	2026-09-22 15:04	63.49	OK
17551	2026-09-22 15:05	63.86	OK	17552	2026-09-22 15:06	62.95	OK
17553	2026-09-22 15:07	61.35	OK	17554	2026-09-22 15:08	61.66	OK
17555	2026-09-22 15:09	65.57	OK	17556	2026-09-22 15:10	63.28	OK
17557	2026-09-22 15:11	63.37	OK	17558	2026-09-22 15:12	63.12	OK
17559	2026-09-22 15:13	64.34	OK	17560	2026-09-22 15:14	63.26	OK
17561	2026-09-22 15:15	62.50	OK	17562	2026-09-22 15:16	63.16	OK
17563	2026-09-22 15:17	64.43	OK	17564	2026-09-22 15:18	63.45	OK
17565	2026-09-22 15:19	63.18	OK	17566	2026-09-22 15:20	62.55	OK
17567	2026-09-22 15:21	62.64	OK	17568	2026-09-22 15:22	63.65	OK
17569	2026-09-22 15:23	61.96	OK	17570	2026-09-22 15:24	65.34	OK
17571	2026-09-22 15:25	64.56	OK	17572	2026-09-22 15:26	62.72	OK
17573	2026-09-22 15:27	65.14	OK	17574	2026-09-22 15:28	63.60	OK
17575	2026-09-22 15:29	63.79	OK	17576	2026-09-22 15:30	64.00	OK
17577	2026-09-22 15:31	65.14	OK	17578	2026-09-22 15:32	62.90	OK
17579	2026-09-22 15:33	64.97	OK	17580	2026-09-22 15:34	67.18	OK
17581	2026-09-22 15:35	65.53	OK	17582	2026-09-22 15:36	63.68	OK
17583	2026-09-22 15:37	63.68	OK	17584	2026-09-22 15:38	62.37	OK
17585	2026-09-22 15:39	65.58	OK	17586	2026-09-22 15:40	66.94	OK
17587	2026-09-22 15:41	65.86	OK	17588	2026-09-22 15:42	66.25	OK
1758	2026-09-22 15:43	64.31	OK	1759	2026-09-22 15:44	65.99	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
17591	2026-09-22 15:45	65.65	OK	17592	2026-09-22 15:46	63.52	OK
17593	2026-09-22 15:47	65.71	OK	17594	2026-09-22 15:48	66.50	OK
17595	2026-09-22 15:49	64.68	OK	17596	2026-09-22 15:50	64.19	OK
17597	2026-09-22 15:51	65.57	OK	17598	2026-09-22 15:52	64.66	OK
17599	2026-09-22 15:53	64.33	OK	17600	2026-09-22 15:54	64.16	OK
17601	2026-09-22 15:55	64.91	OK	17602	2026-09-22 15:56	66.14	OK
17603	2026-09-22 15:57	67.47	OK	17604	2026-09-22 15:58	65.53	OK
17605	2026-09-22 15:59	65.70	OK	17606	2026-09-22 16:00	68.28	OK
17607	2026-09-22 16:01	66.54	OK	17608	2026-09-22 16:02	65.82	OK
17609	2026-09-22 16:03	65.35	OK	17610	2026-09-22 16:04	65.48	OK
17611	2026-09-22 16:05	65.11	OK	17612	2026-09-22 16:06	66.87	OK
17613	2026-09-22 16:07	65.56	OK	17614	2026-09-22 16:08	65.67	OK
17615	2026-09-22 16:09	65.11	OK	17616	2026-09-22 16:10	66.08	OK
17617	2026-09-22 16:11	67.32	OK	17618	2026-09-22 16:12	67.52	OK
17619	2026-09-22 16:13	65.27	OK	17620	2026-09-22 16:14	62.61	OK
17621	2026-09-22 16:15	64.18	OK	17622	2026-09-22 16:16	64.75	OK
17623	2026-09-22 16:17	63.21	OK	17624	2026-09-22 16:18	66.56	OK
17625	2026-09-22 16:19	66.02	OK	17626	2026-09-22 16:20	65.53	OK
17627	2026-09-22 16:21	63.32	OK	17628	2026-09-22 16:22	66.00	OK
17629	2026-09-22 16:23	64.73	OK	17630	2026-09-22 16:24	65.55	OK
17631	2026-09-22 16:25	64.22	OK	17632	2026-09-22 16:26	66.10	OK
17633	2026-09-22 16:27	65.51	OK	17634	2026-09-22 16:28	66.92	OK
17635	2026-09-22 16:29	64.61	OK	17636	2026-09-22 16:30	67.64	OK
17637	2026-09-22 16:31	67.87	OK	17638	2026-09-22 16:32	63.41	OK
17639	2026-09-22 16:33	63.97	OK	17640	2026-09-22 16:34	64.99	OK
17641	2026-09-22 16:35	68.12	OK	17642	2026-09-22 16:36	67.51	OK
17643	2026-09-22 16:37	64.69	OK	17644	2026-09-22 16:38	66.47	OK
17645	2026-09-22 16:39	65.23	OK	17646	2026-09-22 16:40	66.38	OK
17647	2026-09-22 16:41	65.32	OK	17648	2026-09-22 16:42	65.87	OK
1764	2026-09-22 16:43	65.86	OK	1765	2026-09-22 16:44	64.08	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
17651	2026-09-22 16:45	66.98	OK	17652	2026-09-22 16:46	65.68	OK
17653	2026-09-22 16:47	67.66	OK	17654	2026-09-22 16:48	65.93	OK
17655	2026-09-22 16:49	65.39	OK	17656	2026-09-22 16:50	65.92	OK
17657	2026-09-22 16:51	67.42	OK	17658	2026-09-22 16:52	67.69	OK
17659	2026-09-22 16:53	67.48	OK	17660	2026-09-22 16:54	66.04	OK
17661	2026-09-22 16:55	64.40	OK	17662	2026-09-22 16:56	66.93	OK
17663	2026-09-22 16:57	67.28	OK	17664	2026-09-22 16:58	67.42	OK
17665	2026-09-22 16:59	64.02	OK	17666	2026-09-22 17:00	68.45	OK
17667	2026-09-22 17:01	67.51	OK	17668	2026-09-22 17:02	66.53	OK
17669	2026-09-22 17:03	68.64	OK	17670	2026-09-22 17:04	66.66	OK
17671	2026-09-22 17:05	67.64	OK	17672	2026-09-22 17:06	67.23	OK
17673	2026-09-22 17:07	65.37	OK	17674	2026-09-22 17:08	66.59	OK
17675	2026-09-22 17:09	66.46	OK	17676	2026-09-22 17:10	68.28	OK
17677	2026-09-22 17:11	68.29	OK	17678	2026-09-22 17:12	66.63	OK
17679	2026-09-22 17:13	68.57	OK	17680	2026-09-22 17:14	66.55	OK
17681	2026-09-22 17:15	68.36	OK	17682	2026-09-22 17:16	66.37	OK
17683	2026-09-22 17:17	66.96	OK	17684	2026-09-22 17:18	68.93	OK
17685	2026-09-22 17:19	66.73	OK	17686	2026-09-22 17:20	67.52	OK
17687	2026-09-22 17:21	65.72	OK	17688	2026-09-22 17:22	66.34	OK
17689	2026-09-22 17:23	66.86	OK	17690	2026-09-22 17:24	68.13	OK
17691	2026-09-22 17:25	68.02	OK	17692	2026-09-22 17:26	67.28	OK
17693	2026-09-22 17:27	69.72	OK	17694	2026-09-22 17:28	67.87	OK
17695	2026-09-22 17:29	67.47	OK	17696	2026-09-22 17:30	67.37	OK
17697	2026-09-22 17:31	66.69	OK	17698	2026-09-22 17:32	68.86	OK
17699	2026-09-22 17:33	66.37	OK	17700	2026-09-22 17:34	68.27	OK
17701	2026-09-22 17:35	70.55	OK	17702	2026-09-22 17:36	66.59	OK
17703	2026-09-22 17:37	66.62	OK	17704	2026-09-22 17:38	68.39	OK
17705	2026-09-22 17:39	68.64	OK	17706	2026-09-22 17:40	66.63	OK
17707	2026-09-22 17:41	68.98	OK	17708	2026-09-22 17:42	68.56	OK
1770	2026-09-22 17:43	67.99	OK	1771	2026-09-22 17:44	68.39	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
17711	2026-09-22 17:45	68.58	OK	17712	2026-09-22 17:46	67.49	OK
17713	2026-09-22 17:47	68.20	OK	17714	2026-09-22 17:48	66.65	OK
17715	2026-09-22 17:49	67.58	OK	17716	2026-09-22 17:50	67.32	OK
17717	2026-09-22 17:51	69.01	OK	17718	2026-09-22 17:52	68.49	OK
17719	2026-09-22 17:53	68.43	OK	17720	2026-09-22 17:54	69.00	OK
17721	2026-09-22 17:55	69.75	OK	17722	2026-09-22 17:56	67.48	OK
17723	2026-09-22 17:57	69.14	OK	17724	2026-09-22 17:58	68.99	OK
17725	2026-09-22 17:59	70.77	OK	17726	2026-09-22 18:00	64.70	OK
17727	2026-09-22 18:01	67.53	OK	17728	2026-09-22 18:02	71.08	OK
17729	2026-09-22 18:03	67.57	OK	17730	2026-09-22 18:04	67.97	OK
17731	2026-09-22 18:05	66.06	OK	17732	2026-09-22 18:06	67.56	OK
17733	2026-09-22 18:07	68.03	OK	17734	2026-09-22 18:08	66.87	OK
17735	2026-09-22 18:09	68.32	OK	17736	2026-09-22 18:10	68.97	OK
17737	2026-09-22 18:11	67.86	OK	17738	2026-09-22 18:12	69.43	OK
17739	2026-09-22 18:13	71.51	OK	17740	2026-09-22 18:14	70.16	OK
17741	2026-09-22 18:15	67.36	OK	17742	2026-09-22 18:16	69.11	OK
17743	2026-09-22 18:17	66.85	OK	17744	2026-09-22 18:18	69.28	OK
17745	2026-09-22 18:19	70.48	OK	17746	2026-09-22 18:20	67.57	OK
17747	2026-09-22 18:21	68.61	OK	17748	2026-09-22 18:22	67.86	OK
17749	2026-09-22 18:23	69.39	OK	17750	2026-09-22 18:24	71.50	OK
17751	2026-09-22 18:25	68.09	OK	17752	2026-09-22 18:26	70.04	OK
17753	2026-09-22 18:27	70.68	OK	17754	2026-09-22 18:28	69.08	OK
17755	2026-09-22 18:29	69.17	OK	17756	2026-09-22 18:30	69.26	OK
17757	2026-09-22 18:31	68.88	OK	17758	2026-09-22 18:32	69.38	OK
17759	2026-09-22 18:33	69.81	OK	17760	2026-09-22 18:34	71.03	OK
17761	2026-09-22 18:35	69.06	OK	17762	2026-09-22 18:36	68.05	OK
17763	2026-09-22 18:37	70.59	OK	17764	2026-09-22 18:38	69.39	OK
17765	2026-09-22 18:39	69.31	OK	17766	2026-09-22 18:40	69.87	OK
17767	2026-09-22 18:41	68.35	OK	17768	2026-09-22 18:42	70.35	OK
17769	2026-09-22 18:43	71.20	OK	17770	2026-09-22 18:44	66.78	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
17771	2026-09-22 18:45	69.71	OK	17772	2026-09-22 18:46	70.14	OK
17773	2026-09-22 18:47	68.53	OK	17774	2026-09-22 18:48	67.39	OK
17775	2026-09-22 18:49	71.33	OK	17776	2026-09-22 18:50	70.72	OK
17777	2026-09-22 18:51	69.18	OK	17778	2026-09-22 18:52	71.41	OK
17779	2026-09-22 18:53	72.72	OK	17780	2026-09-22 18:54	68.83	OK
17781	2026-09-22 18:55	68.38	OK	17782	2026-09-22 18:56	68.65	OK
17783	2026-09-22 18:57	69.70	OK	17784	2026-09-22 18:58	68.93	OK
17785	2026-09-22 18:59	69.22	OK	17786	2026-09-22 19:00	69.49	OK
17787	2026-09-22 19:01	70.25	OK	17788	2026-09-22 19:02	70.58	OK
17789	2026-09-22 19:03	67.75	OK	17790	2026-09-22 19:04	67.12	OK
17791	2026-09-22 19:05	69.97	OK	17792	2026-09-22 19:06	68.26	OK
17793	2026-09-22 19:07	70.21	OK	17794	2026-09-22 19:08	68.62	OK
17795	2026-09-22 19:09	70.01	OK	17796	2026-09-22 19:10	71.07	OK
17797	2026-09-22 19:11	69.93	OK	17798	2026-09-22 19:12	68.39	OK
17799	2026-09-22 19:13	70.12	OK	17800	2026-09-22 19:14	70.30	OK
17801	2026-09-22 19:15	71.79	OK	17802	2026-09-22 19:16	71.38	OK
17803	2026-09-22 19:17	72.32	OK	17804	2026-09-22 19:18	70.87	OK
17805	2026-09-22 19:19	71.46	OK	17806	2026-09-22 19:20	69.92	OK
17807	2026-09-22 19:21	71.95	OK	17808	2026-09-22 19:22	68.92	OK
17809	2026-09-22 19:23	69.74	OK	17810	2026-09-22 19:24	68.36	OK
17811	2026-09-22 19:25	71.22	OK	17812	2026-09-22 19:26	70.32	OK
17813	2026-09-22 19:27	69.10	OK	17814	2026-09-22 19:28	72.15	OK
17815	2026-09-22 19:29	70.72	OK	17816	2026-09-22 19:30	71.52	OK
17817	2026-09-22 19:31	70.57	OK	17818	2026-09-22 19:32	72.15	OK
17819	2026-09-22 19:33	70.74	OK	17820	2026-09-22 19:34	72.73	OK
17821	2026-09-22 19:35	72.96	OK	17822	2026-09-22 19:36	72.52	OK
17823	2026-09-22 19:37	70.43	OK	17824	2026-09-22 19:38	71.52	OK
17825	2026-09-22 19:39	69.29	OK	17826	2026-09-22 19:40	72.36	OK
17827	2026-09-22 19:41	71.50	OK	17828	2026-09-22 19:42	72.06	OK
1782	2026-09-22 19:43	70.86	OK	1783	2026-09-22 19:44	70.14	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
17831	2026-09-22 19:45	70.99	OK	17832	2026-09-22 19:46	73.37	OK
17833	2026-09-22 19:47	70.01	OK	17834	2026-09-22 19:48	71.25	OK
17835	2026-09-22 19:49	69.30	OK	17836	2026-09-22 19:50	70.36	OK
17837	2026-09-22 19:51	71.07	OK	17838	2026-09-22 19:52	73.09	OK
17839	2026-09-22 19:53	72.68	OK	17840	2026-09-22 19:54	70.21	OK
17841	2026-09-22 19:55	69.42	OK	17842	2026-09-22 19:56	71.26	OK
17843	2026-09-22 19:57	71.40	OK	17844	2026-09-22 19:58	71.20	OK
17845	2026-09-22 19:59	73.44	OK	17846	2026-09-22 20:00	72.24	OK
17847	2026-09-22 20:01	71.52	OK	17848	2026-09-22 20:02	71.19	OK
17849	2026-09-22 20:03	70.91	OK	17850	2026-09-22 20:04	68.83	OK
17851	2026-09-22 20:05	70.39	OK	17852	2026-09-22 20:06	70.85	OK
17853	2026-09-22 20:07	70.14	OK	17854	2026-09-22 20:08	72.65	OK
17855	2026-09-22 20:09	70.46	OK	17856	2026-09-22 20:10	72.26	OK
17857	2026-09-22 20:11	71.32	OK	17858	2026-09-22 20:12	68.32	OK
17859	2026-09-22 20:13	70.41	OK	17860	2026-09-22 20:14	72.65	OK
17861	2026-09-22 20:15	68.37	OK	17862	2026-09-22 20:16	71.18	OK
17863	2026-09-22 20:17	70.12	OK	17864	2026-09-22 20:18	71.69	OK
17865	2026-09-22 20:19	72.74	OK	17866	2026-09-22 20:20	70.05	OK
17867	2026-09-22 20:21	71.24	OK	17868	2026-09-22 20:22	69.80	OK
17869	2026-09-22 20:23	72.83	OK	17870	2026-09-22 20:24	73.44	OK
17871	2026-09-22 20:25	72.27	OK	17872	2026-09-22 20:26	73.02	OK
17873	2026-09-22 20:27	72.21	OK	17874	2026-09-22 20:28	71.91	OK
17875	2026-09-22 20:29	70.57	OK	17876	2026-09-22 20:30	71.55	OK
17877	2026-09-22 20:31	72.89	OK	17878	2026-09-22 20:32	70.30	OK
17879	2026-09-22 20:33	72.03	OK	17880	2026-09-22 20:34	73.17	OK
17881	2026-09-22 20:35	72.23	OK	17882	2026-09-22 20:36	74.90	OK
17883	2026-09-22 20:37	70.62	OK	17884	2026-09-22 20:38	72.76	OK
17885	2026-09-22 20:39	72.44	OK	17886	2026-09-22 20:40	73.41	OK
17887	2026-09-22 20:41	71.80	OK	17888	2026-09-22 20:42	70.40	OK
1788	2026-09-22 20:43	69.56	OK	1789	2026-09-22 20:44	70.76	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
1789	2026-09-22 20:45	73.23	OK	1789	2026-09-22 20:46	71.33	OK
1				2			
1789	2026-09-22 20:47	71.52	OK	1789	2026-09-22 20:48	70.48	OK
3				4			
1789	2026-09-22 20:49	73.01	OK	1789	2026-09-22 20:50	74.48	OK
5				6			
1789	2026-09-22 20:51	71.09	OK	1789	2026-09-22 20:52	71.61	OK
7				8			
1789	2026-09-22 20:53	68.41	OK	1790	2026-09-22 20:54	69.91	OK
9				0			
1790	2026-09-22 20:55	70.63	OK	1790	2026-09-22 20:56	74.50	OK
1				2			
1790	2026-09-22 20:57	72.03	OK	1790	2026-09-22 20:58	71.24	OK
3				4			
1790	2026-09-22 20:59	71.54	OK	1790	2026-09-22 21:00	71.08	OK
5				6			
1790	2026-09-22 21:01	73.23	OK	1790	2026-09-22 21:02	71.76	OK
7				8			
1790	2026-09-22 21:03	70.88	OK	1791	2026-09-22 21:04	68.89	OK
9				0			
1791	2026-09-22 21:05	72.88	OK	1791	2026-09-22 21:06	72.33	OK
1				2			
1791	2026-09-22 21:07	73.57	OK	1791	2026-09-22 21:08	72.84	OK
3				4			
1791	2026-09-22 21:09	73.13	OK	1791	2026-09-22 21:10	71.39	OK
5				6			
1791	2026-09-22 21:11	74.35	OK	1791	2026-09-22 21:12	72.24	OK
7				8			
1791	2026-09-22 21:13	74.53	OK	1792	2026-09-22 21:14	73.14	OK
9				0			
1792	2026-09-22 21:15	71.94	OK	1792	2026-09-22 21:16	73.96	OK
1				2			
1792	2026-09-22 21:17	73.49	OK	1792	2026-09-22 21:18	73.54	OK
3				4			
1792	2026-09-22 21:19	71.98	OK	1792	2026-09-22 21:20	72.74	OK
5				6			
1792	2026-09-22 21:21	74.10	OK	1792	2026-09-22 21:22	70.91	OK
7				8			
1792	2026-09-22 21:23	72.68	OK	1793	2026-09-22 21:24	74.48	OK
9				0			
1793	2026-09-22 21:25	73.77	OK	1793	2026-09-22 21:26	69.85	OK
1				2			
1793	2026-09-22 21:27	69.98	OK	1793	2026-09-22 21:28	73.01	OK
3				4			
1793	2026-09-22 21:29	73.21	OK	1793	2026-09-22 21:30	70.37	OK
5				6			
1793	2026-09-22 21:31	70.74	OK	1793	2026-09-22 21:32	70.76	OK
7				8			
1793	2026-09-22 21:33	73.09	OK	1794	2026-09-22 21:34	71.38	OK
9				0			
1794	2026-09-22 21:35	71.39	OK	1794	2026-09-22 21:36	71.40	OK
1				2			
1794	2026-09-22 21:37	73.31	OK	1794	2026-09-22 21:38	73.21	OK
3				4			
1794	2026-09-22 21:39	70.76	OK	1794	2026-09-22 21:40	70.57	OK
5				6			
1794	2026-09-22 21:41	71.74	OK	1794	2026-09-22 21:42	70.63	OK
7				8			
1794	2026-09-22 21:43	74.70	OK	1795	2026-09-22 21:44	73.10	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
17951	2026-09-22 21:45	74.02	OK	17952	2026-09-22 21:46	73.50	OK
17953	2026-09-22 21:47	71.36	OK	17954	2026-09-22 21:48	74.03	OK
17955	2026-09-22 21:49	73.71	OK	17956	2026-09-22 21:50	71.29	OK
17957	2026-09-22 21:51	71.00	OK	17958	2026-09-22 21:52	71.83	OK
17959	2026-09-22 21:53	72.60	OK	17960	2026-09-22 21:54	72.40	OK
17961	2026-09-22 21:55	73.56	OK	17962	2026-09-22 21:56	72.38	OK
17963	2026-09-22 21:57	70.44	OK	17964	2026-09-22 21:58	73.01	OK
17965	2026-09-22 21:59	73.61	OK	17966	2026-09-22 22:00	71.40	OK
17967	2026-09-22 22:01	71.57	OK	17968	2026-09-22 22:02	72.80	OK
17969	2026-09-22 22:03	73.28	OK	17970	2026-09-22 22:04	73.38	OK
17971	2026-09-22 22:05	71.45	OK	17972	2026-09-22 22:06	74.48	OK
17973	2026-09-22 22:07	72.88	OK	17974	2026-09-22 22:08	72.50	OK
17975	2026-09-22 22:09	72.95	OK	17976	2026-09-22 22:10	73.16	OK
17977	2026-09-22 22:11	72.91	OK	17978	2026-09-22 22:12	73.80	OK
17979	2026-09-22 22:13	74.56	OK	17980	2026-09-22 22:14	71.92	OK
17981	2026-09-22 22:15	72.48	OK	17982	2026-09-22 22:16	73.96	OK
17983	2026-09-22 22:17	72.54	OK	17984	2026-09-22 22:18	73.56	OK
17985	2026-09-22 22:19	73.64	OK	17986	2026-09-22 22:20	71.99	OK
17987	2026-09-22 22:21	71.65	OK	17988	2026-09-22 22:22	72.51	OK
17989	2026-09-22 22:23	72.51	OK	17990	2026-09-22 22:24	71.88	OK
17991	2026-09-22 22:25	72.59	OK	17992	2026-09-22 22:26	72.81	OK
17993	2026-09-22 22:27	70.58	OK	17994	2026-09-22 22:28	73.02	OK
17995	2026-09-22 22:29	70.41	OK	17996	2026-09-22 22:30	72.67	OK
17997	2026-09-22 22:31	73.45	OK	17998	2026-09-22 22:32	70.87	OK
17999	2026-09-22 22:33	73.88	OK	18000	2026-09-22 22:34	74.05	OK
18001	2026-09-22 22:35	72.11	OK	18002	2026-09-22 22:36	74.04	OK
18003	2026-09-22 22:37	72.62	OK	18004	2026-09-22 22:38	72.38	OK
18005	2026-09-22 22:39	75.32	OK	18006	2026-09-22 22:40	70.29	OK
18007	2026-09-22 22:41	71.85	OK	18008	2026-09-22 22:42	71.91	OK
1800	2026-09-22 22:43	73.20	OK	1801	2026-09-22 22:44	71.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
18011	2026-09-22 22:45	71.94	OK	18012	2026-09-22 22:46	71.68	OK
18013	2026-09-22 22:47	72.43	OK	18014	2026-09-22 22:48	75.70	OK
18015	2026-09-22 22:49	73.85	OK	18016	2026-09-22 22:50	74.04	OK
18017	2026-09-22 22:51	71.71	OK	18018	2026-09-22 22:52	74.30	OK
18019	2026-09-22 22:53	74.50	OK	18020	2026-09-22 22:54	74.05	OK
18021	2026-09-22 22:55	73.29	OK	18022	2026-09-22 22:56	74.97	OK
18023	2026-09-22 22:57	73.28	OK	18024	2026-09-22 22:58	72.87	OK
18025	2026-09-22 22:59	72.68	OK	18026	2026-09-22 23:00	70.67	OK
18027	2026-09-22 23:01	73.22	OK	18028	2026-09-22 23:02	72.94	OK
18029	2026-09-22 23:03	72.45	OK	18030	2026-09-22 23:04	71.11	OK
18031	2026-09-22 23:05	72.42	OK	18032	2026-09-22 23:06	72.83	OK
18033	2026-09-22 23:07	74.14	OK	18034	2026-09-22 23:08	72.54	OK
18035	2026-09-22 23:09	71.31	OK	18036	2026-09-22 23:10	73.18	OK
18037	2026-09-22 23:11	74.76	OK	18038	2026-09-22 23:12	74.03	OK
18039	2026-09-22 23:13	71.93	OK	18040	2026-09-22 23:14	71.85	OK
18041	2026-09-22 23:15	71.44	OK	18042	2026-09-22 23:16	75.83	OK
18043	2026-09-22 23:17	72.00	OK	18044	2026-09-22 23:18	72.72	OK
18045	2026-09-22 23:19	72.28	OK	18046	2026-09-22 23:20	73.27	OK
18047	2026-09-22 23:21	74.25	OK	18048	2026-09-22 23:22	74.52	OK
18049	2026-09-22 23:23	72.08	OK	18050	2026-09-22 23:24	70.10	OK
18051	2026-09-22 23:25	73.94	OK	18052	2026-09-22 23:26	72.47	OK
18053	2026-09-22 23:27	72.97	OK	18054	2026-09-22 23:28	73.74	OK
18055	2026-09-22 23:29	74.13	OK	18056	2026-09-22 23:30	73.62	OK
18057	2026-09-22 23:31	71.75	OK	18058	2026-09-22 23:32	70.61	OK
18059	2026-09-22 23:33	73.71	OK	18060	2026-09-22 23:34	71.98	OK
18061	2026-09-22 23:35	73.23	OK	18062	2026-09-22 23:36	72.24	OK
18063	2026-09-22 23:37	73.36	OK	18064	2026-09-22 23:38	69.14	OK
18065	2026-09-22 23:39	72.69	OK	18066	2026-09-22 23:40	70.85	OK
18067	2026-09-22 23:41	71.85	OK	18068	2026-09-22 23:42	73.09	OK
1806	2026-09-22 23:43	71.94	OK	1807	2026-09-22 23:44	74.31	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
18071	2026-09-22 23:45	69.74	OK	18072	2026-09-22 23:46	73.86	OK
18073	2026-09-22 23:47	72.07	OK	18074	2026-09-22 23:48	73.38	OK
18075	2026-09-22 23:49	71.36	OK	18076	2026-09-22 23:50	70.23	OK
18077	2026-09-22 23:51	73.05	OK	18078	2026-09-22 23:52	71.90	OK
18079	2026-09-22 23:53	71.01	OK	18080	2026-09-22 23:54	72.28	OK
18081	2026-09-22 23:55	69.74	OK	18082	2026-09-22 23:56	70.73	OK
18083	2026-09-22 23:57	71.72	OK	18084	2026-09-22 23:58	71.94	OK
18085	2026-09-22 23:59	73.60	OK	18086	2026-09-23 00:00	70.12	OK
18087	2026-09-23 00:01	75.32	OK	18088	2026-09-23 00:02	73.21	OK
18089	2026-09-23 00:03	72.20	OK	18090	2026-09-23 00:04	74.77	OK
18091	2026-09-23 00:05	72.54	OK	18092	2026-09-23 00:06	71.35	OK
18093	2026-09-23 00:07	72.65	OK	18094	2026-09-23 00:08	71.65	OK
18095	2026-09-23 00:09	71.94	OK	18096	2026-09-23 00:10	72.32	OK
18097	2026-09-23 00:11	71.40	OK	18098	2026-09-23 00:12	72.33	OK
18099	2026-09-23 00:13	75.25	OK	18100	2026-09-23 00:14	70.83	OK
18101	2026-09-23 00:15	73.25	OK	18102	2026-09-23 00:16	70.77	OK
18103	2026-09-23 00:17	70.71	OK	18104	2026-09-23 00:18	71.73	OK
18105	2026-09-23 00:19	72.20	OK	18106	2026-09-23 00:20	69.46	OK
18107	2026-09-23 00:21	74.21	OK	18108	2026-09-23 00:22	73.22	OK
18109	2026-09-23 00:23	74.25	OK	18110	2026-09-23 00:24	72.66	OK
18111	2026-09-23 00:25	70.70	OK	18112	2026-09-23 00:26	72.57	OK
18113	2026-09-23 00:27	71.46	OK	18114	2026-09-23 00:28	72.01	OK
18115	2026-09-23 00:29	74.59	OK	18116	2026-09-23 00:30	72.55	OK
18117	2026-09-23 00:31	70.15	OK	18118	2026-09-23 00:32	72.16	OK
18119	2026-09-23 00:33	70.97	OK	18120	2026-09-23 00:34	71.89	OK
18121	2026-09-23 00:35	71.80	OK	18122	2026-09-23 00:36	73.04	OK
18123	2026-09-23 00:37	71.34	OK	18124	2026-09-23 00:38	70.32	OK
18125	2026-09-23 00:39	71.80	OK	18126	2026-09-23 00:40	73.48	OK
18127	2026-09-23 00:41	73.73	OK	18128	2026-09-23 00:42	71.66	OK
1812	2026-09-23 00:43	73.18	OK	1813	2026-09-23 00:44	71.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
18131	2026-09-23 00:45	73.27	OK	18132	2026-09-23 00:46	72.22	OK
18133	2026-09-23 00:47	72.71	OK	18134	2026-09-23 00:48	69.77	OK
18135	2026-09-23 00:49	72.22	OK	18136	2026-09-23 00:50	73.56	OK
18137	2026-09-23 00:51	73.16	OK	18138	2026-09-23 00:52	72.78	OK
18139	2026-09-23 00:53	71.32	OK	18140	2026-09-23 00:54	70.94	OK
18141	2026-09-23 00:55	70.56	OK	18142	2026-09-23 00:56	70.18	OK
18143	2026-09-23 00:57	71.61	OK	18144	2026-09-23 00:58	73.30	OK
18145	2026-09-23 00:59	71.54	OK	18146	2026-09-23 01:00	71.48	OK
18147	2026-09-23 01:01	72.11	OK	18148	2026-09-23 01:02	69.82	OK
18149	2026-09-23 01:03	69.72	OK	18150	2026-09-23 01:04	70.43	OK
18151	2026-09-23 01:05	69.97	OK	18152	2026-09-23 01:06	71.76	OK
18153	2026-09-23 01:07	70.52	OK	18154	2026-09-23 01:08	72.79	OK
18155	2026-09-23 01:09	71.59	OK	18156	2026-09-23 01:10	72.19	OK
18157	2026-09-23 01:11	71.85	OK	18158	2026-09-23 01:12	70.85	OK
18159	2026-09-23 01:13	72.22	OK	18160	2026-09-23 01:14	71.20	OK
18161	2026-09-23 01:15	69.55	OK	18162	2026-09-23 01:16	72.85	OK
18163	2026-09-23 01:17	68.94	OK	18164	2026-09-23 01:18	73.43	OK
18165	2026-09-23 01:19	73.46	OK	18166	2026-09-23 01:20	73.18	OK
18167	2026-09-23 01:21	70.84	OK	18168	2026-09-23 01:22	73.08	OK
18169	2026-09-23 01:23	72.95	OK	18170	2026-09-23 01:24	71.71	OK
18171	2026-09-23 01:25	72.05	OK	18172	2026-09-23 01:26	70.28	OK
18173	2026-09-23 01:27	70.76	OK	18174	2026-09-23 01:28	69.99	OK
18175	2026-09-23 01:29	71.18	OK	18176	2026-09-23 01:30	72.82	OK
18177	2026-09-23 01:31	71.75	OK	18178	2026-09-23 01:32	69.96	OK
18179	2026-09-23 01:33	70.51	OK	18180	2026-09-23 01:34	70.84	OK
18181	2026-09-23 01:35	70.75	OK	18182	2026-09-23 01:36	70.71	OK
18183	2026-09-23 01:37	73.53	OK	18184	2026-09-23 01:38	69.36	OK
18185	2026-09-23 01:39	70.13	OK	18186	2026-09-23 01:40	70.77	OK
18187	2026-09-23 01:41	70.36	OK	18188	2026-09-23 01:42	70.25	OK
1818	2026-09-23 01:43	71.53	OK	1819	2026-09-23 01:44	69.57	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
18191	2026-09-23 01:45	70.53	OK	18192	2026-09-23 01:46	69.59	OK
18193	2026-09-23 01:47	71.92	OK	18194	2026-09-23 01:48	71.45	OK
18195	2026-09-23 01:49	71.90	OK	18196	2026-09-23 01:50	68.12	OK
18197	2026-09-23 01:51	72.83	OK	18198	2026-09-23 01:52	71.98	OK
18199	2026-09-23 01:53	71.62	OK	18200	2026-09-23 01:54	71.30	OK
18201	2026-09-23 01:55	69.10	OK	18202	2026-09-23 01:56	72.39	OK
18203	2026-09-23 01:57	68.57	OK	18204	2026-09-23 01:58	70.89	OK
18205	2026-09-23 01:59	72.05	OK	18206	2026-09-23 02:00	68.49	OK
18207	2026-09-23 02:01	70.37	OK	18208	2026-09-23 02:02	68.38	OK
18209	2026-09-23 02:03	68.98	OK	18210	2026-09-23 02:04	70.69	OK
18211	2026-09-23 02:05	69.21	OK	18212	2026-09-23 02:06	69.04	OK
18213	2026-09-23 02:07	71.37	OK	18214	2026-09-23 02:08	70.73	OK
18215	2026-09-23 02:09	69.82	OK	18216	2026-09-23 02:10	70.23	OK
18217	2026-09-23 02:11	71.54	OK	18218	2026-09-23 02:12	71.63	OK
18219	2026-09-23 02:13	69.11	OK	18220	2026-09-23 02:14	69.51	OK
18221	2026-09-23 02:15	71.38	OK	18222	2026-09-23 02:16	69.93	OK
18223	2026-09-23 02:17	70.19	OK	18224	2026-09-23 02:18	71.04	OK
18225	2026-09-23 02:19	71.55	OK	18226	2026-09-23 02:20	68.79	OK
18227	2026-09-23 02:21	72.53	OK	18228	2026-09-23 02:22	71.48	OK
18229	2026-09-23 02:23	71.27	OK	18230	2026-09-23 02:24	70.96	OK
18231	2026-09-23 02:25	68.65	OK	18232	2026-09-23 02:26	70.93	OK
18233	2026-09-23 02:27	70.34	OK	18234	2026-09-23 02:28	70.94	OK
18235	2026-09-23 02:29	69.08	OK	18236	2026-09-23 02:30	68.73	OK
18237	2026-09-23 02:31	70.74	OK	18238	2026-09-23 02:32	69.42	OK
18239	2026-09-23 02:33	68.52	OK	18240	2026-09-23 02:34	68.41	OK
18241	2026-09-23 02:35	69.33	OK	18242	2026-09-23 02:36	68.92	OK
18243	2026-09-23 02:37	68.57	OK	18244	2026-09-23 02:38	68.30	OK
18245	2026-09-23 02:39	69.32	OK	18246	2026-09-23 02:40	68.77	OK
18247	2026-09-23 02:41	69.28	OK	18248	2026-09-23 02:42	66.73	OK
1824	2026-09-23 02:43	67.73	OK	1825	2026-09-23 02:44	71.80	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
18251	2026-09-23 02:45	67.46	OK	18252	2026-09-23 02:46	71.79	OK
18253	2026-09-23 02:47	70.07	OK	18254	2026-09-23 02:48	69.63	OK
18255	2026-09-23 02:49	67.01	OK	18256	2026-09-23 02:50	70.44	OK
18257	2026-09-23 02:51	67.86	OK	18258	2026-09-23 02:52	66.89	OK
18259	2026-09-23 02:53	71.26	OK	18260	2026-09-23 02:54	69.32	OK
18261	2026-09-23 02:55	68.65	OK	18262	2026-09-23 02:56	70.81	OK
18263	2026-09-23 02:57	69.33	OK	18264	2026-09-23 02:58	68.74	OK
18265	2026-09-23 02:59	67.48	OK	18266	2026-09-23 03:00	67.98	OK
18267	2026-09-23 03:01	70.55	OK	18268	2026-09-23 03:02	69.87	OK
18269	2026-09-23 03:03	70.28	OK	18270	2026-09-23 03:04	68.40	OK
18271	2026-09-23 03:05	67.37	OK	18272	2026-09-23 03:06	69.52	OK
18273	2026-09-23 03:07	65.88	OK	18274	2026-09-23 03:08	69.35	OK
18275	2026-09-23 03:09	70.07	OK	18276	2026-09-23 03:10	66.89	OK
18277	2026-09-23 03:11	67.74	OK	18278	2026-09-23 03:12	65.17	OK
18279	2026-09-23 03:13	66.43	OK	18280	2026-09-23 03:14	69.73	OK
18281	2026-09-23 03:15	69.07	OK	18282	2026-09-23 03:16	68.30	OK
18283	2026-09-23 03:17	69.81	OK	18284	2026-09-23 03:18	68.51	OK
18285	2026-09-23 03:19	66.66	OK	18286	2026-09-23 03:20	70.96	OK
18287	2026-09-23 03:21	68.79	OK	18288	2026-09-23 03:22	70.58	OK
18289	2026-09-23 03:23	68.40	OK	18290	2026-09-23 03:24	67.54	OK
18291	2026-09-23 03:25	66.37	OK	18292	2026-09-23 03:26	68.32	OK
18293	2026-09-23 03:27	67.45	OK	18294	2026-09-23 03:28	67.33	OK
18295	2026-09-23 03:29	67.39	OK	18296	2026-09-23 03:30	68.46	OK
18297	2026-09-23 03:31	68.94	OK	18298	2026-09-23 03:32	69.52	OK
18299	2026-09-23 03:33	68.75	OK	18300	2026-09-23 03:34	69.63	OK
18301	2026-09-23 03:35	68.93	OK	18302	2026-09-23 03:36	67.24	OK
18303	2026-09-23 03:37	67.01	OK	18304	2026-09-23 03:38	68.30	OK
18305	2026-09-23 03:39	66.33	OK	18306	2026-09-23 03:40	66.07	OK
18307	2026-09-23 03:41	66.65	OK	18308	2026-09-23 03:42	68.93	OK
1830	2026-09-23 03:43	70.37	OK	1831	2026-09-23 03:44	69.04	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
18311	2026-09-23 03:45	68.84	OK	18312	2026-09-23 03:46	65.23	OK
18313	2026-09-23 03:47	67.71	OK	18314	2026-09-23 03:48	66.42	OK
18315	2026-09-23 03:49	68.00	OK	18316	2026-09-23 03:50	67.76	OK
18317	2026-09-23 03:51	64.30	OK	18318	2026-09-23 03:52	68.08	OK
18319	2026-09-23 03:53	68.82	OK	18320	2026-09-23 03:54	68.84	OK
18321	2026-09-23 03:55	66.20	OK	18322	2026-09-23 03:56	66.49	OK
18323	2026-09-23 03:57	68.29	OK	18324	2026-09-23 03:58	68.32	OK
18325	2026-09-23 03:59	67.38	OK	18326	2026-09-23 04:00	68.97	OK
18327	2026-09-23 04:01	68.24	OK	18328	2026-09-23 04:02	69.07	OK
18329	2026-09-23 04:03	68.57	OK	18330	2026-09-23 04:04	65.68	OK
18331	2026-09-23 04:05	66.23	OK	18332	2026-09-23 04:06	66.64	OK
18333	2026-09-23 04:07	64.71	OK	18334	2026-09-23 04:08	67.47	OK
18335	2026-09-23 04:09	66.41	OK	18336	2026-09-23 04:10	67.67	OK
18337	2026-09-23 04:11	66.74	OK	18338	2026-09-23 04:12	65.05	OK
18339	2026-09-23 04:13	69.55	OK	18340	2026-09-23 04:14	66.62	OK
18341	2026-09-23 04:15	69.08	OK	18342	2026-09-23 04:16	66.30	OK
18343	2026-09-23 04:17	65.99	OK	18344	2026-09-23 04:18	67.84	OK
18345	2026-09-23 04:19	68.10	OK	18346	2026-09-23 04:20	68.53	OK
18347	2026-09-23 04:21	65.19	OK	18348	2026-09-23 04:22	67.18	OK
18349	2026-09-23 04:23	68.91	OK	18350	2026-09-23 04:24	66.46	OK
18351	2026-09-23 04:25	68.12	OK	18352	2026-09-23 04:26	65.44	OK
18353	2026-09-23 04:27	66.30	OK	18354	2026-09-23 04:28	65.19	OK
18355	2026-09-23 04:29	65.97	OK	18356	2026-09-23 04:30	66.83	OK
18357	2026-09-23 04:31	68.57	OK	18358	2026-09-23 04:32	68.74	OK
18359	2026-09-23 04:33	64.81	OK	18360	2026-09-23 04:34	64.84	OK
18361	2026-09-23 04:35	64.70	OK	18362	2026-09-23 04:36	65.52	OK
18363	2026-09-23 04:37	65.69	OK	18364	2026-09-23 04:38	65.11	OK
18365	2026-09-23 04:39	67.18	OK	18366	2026-09-23 04:40	65.00	OK
18367	2026-09-23 04:41	65.76	OK	18368	2026-09-23 04:42	65.79	OK
1836	2026-09-23 04:43	66.16	OK	1837	2026-09-23 04:44	66.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
18371	2026-09-23 04:45	68.42	OK	18372	2026-09-23 04:46	66.87	OK
18373	2026-09-23 04:47	64.88	OK	18374	2026-09-23 04:48	67.70	OK
18375	2026-09-23 04:49	67.20	OK	18376	2026-09-23 04:50	66.40	OK
18377	2026-09-23 04:51	66.33	OK	18378	2026-09-23 04:52	65.16	OK
18379	2026-09-23 04:53	66.35	OK	18380	2026-09-23 04:54	62.18	OK
18381	2026-09-23 04:55	67.51	OK	18382	2026-09-23 04:56	67.18	OK
18383	2026-09-23 04:57	67.84	OK	18384	2026-09-23 04:58	64.74	OK
18385	2026-09-23 04:59	65.47	OK	18386	2026-09-23 05:00	65.67	OK
18387	2026-09-23 05:01	66.43	OK	18388	2026-09-23 05:02	66.90	OK
18389	2026-09-23 05:03	65.90	OK	18390	2026-09-23 05:04	67.85	OK
18391	2026-09-23 05:05	64.71	OK	18392	2026-09-23 05:06	65.86	OK
18393	2026-09-23 05:07	65.23	OK	18394	2026-09-23 05:08	67.74	OK
18395	2026-09-23 05:09	65.94	OK	18396	2026-09-23 05:10	64.24	OK
18397	2026-09-23 05:11	65.56	OK	18398	2026-09-23 05:12	64.96	OK
18399	2026-09-23 05:13	63.85	OK	18400	2026-09-23 05:14	64.84	OK
18401	2026-09-23 05:15	67.19	OK	18402	2026-09-23 05:16	65.26	OK
18403	2026-09-23 05:17	65.59	OK	18404	2026-09-23 05:18	64.72	OK
18405	2026-09-23 05:19	64.62	OK	18406	2026-09-23 05:20	64.40	OK
18407	2026-09-23 05:21	63.72	OK	18408	2026-09-23 05:22	66.95	OK
18409	2026-09-23 05:23	63.85	OK	18410	2026-09-23 05:24	66.39	OK
18411	2026-09-23 05:25	64.76	OK	18412	2026-09-23 05:26	66.33	OK
18413	2026-09-23 05:27	64.90	OK	18414	2026-09-23 05:28	65.62	OK
18415	2026-09-23 05:29	65.45	OK	18416	2026-09-23 05:30	64.20	OK
18417	2026-09-23 05:31	66.25	OK	18418	2026-09-23 05:32	66.77	OK
18419	2026-09-23 05:33	65.89	OK	18420	2026-09-23 05:34	65.24	OK
18421	2026-09-23 05:35	65.35	OK	18422	2026-09-23 05:36	61.58	OK
18423	2026-09-23 05:37	63.69	OK	18424	2026-09-23 05:38	65.47	OK
18425	2026-09-23 05:39	62.34	OK	18426	2026-09-23 05:40	63.32	OK
18427	2026-09-23 05:41	64.98	OK	18428	2026-09-23 05:42	67.25	OK
1842	2026-09-23 05:43	65.91	OK	1843	2026-09-23 05:44	65.27	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
18431	2026-09-23 05:45	61.94	OK	18432	2026-09-23 05:46	65.53	OK
18433	2026-09-23 05:47	62.15	OK	18434	2026-09-23 05:48	61.88	OK
18435	2026-09-23 05:49	65.32	OK	18436	2026-09-23 05:50	63.18	OK
18437	2026-09-23 05:51	65.69	OK	18438	2026-09-23 05:52	63.48	OK
18439	2026-09-23 05:53	61.22	OK	18440	2026-09-23 05:54	64.92	OK
18441	2026-09-23 05:55	65.09	OK	18442	2026-09-23 05:56	64.45	OK
18443	2026-09-23 05:57	64.20	OK	18444	2026-09-23 05:58	64.10	OK
18445	2026-09-23 05:59	65.94	OK	18446	2026-09-23 06:00	62.83	OK
18447	2026-09-23 06:01	62.51	OK	18448	2026-09-23 06:02	64.07	OK
18449	2026-09-23 06:03	64.66	OK	18450	2026-09-23 06:04	64.78	OK
18451	2026-09-23 06:05	64.81	OK	18452	2026-09-23 06:06	66.11	OK
18453	2026-09-23 06:07	66.24	OK	18454	2026-09-23 06:08	64.77	OK
18455	2026-09-23 06:09	65.56	OK	18456	2026-09-23 06:10	63.39	OK
18457	2026-09-23 06:11	63.80	OK	18458	2026-09-23 06:12	62.42	OK
18459	2026-09-23 06:13	65.43	OK	18460	2026-09-23 06:14	62.21	OK
18461	2026-09-23 06:15	65.50	OK	18462	2026-09-23 06:16	63.15	OK
18463	2026-09-23 06:17	61.38	OK	18464	2026-09-23 06:18	63.88	OK
18465	2026-09-23 06:19	64.46	OK	18466	2026-09-23 06:20	64.00	OK
18467	2026-09-23 06:21	62.39	OK	18468	2026-09-23 06:22	65.50	OK
18469	2026-09-23 06:23	61.90	OK	18470	2026-09-23 06:24	62.88	OK
18471	2026-09-23 06:25	64.53	OK	18472	2026-09-23 06:26	62.72	OK
18473	2026-09-23 06:27	64.09	OK	18474	2026-09-23 06:28	63.68	OK
18475	2026-09-23 06:29	63.15	OK	18476	2026-09-23 06:30	62.19	OK
18477	2026-09-23 06:31	60.88	OK	18478	2026-09-23 06:32	61.21	OK
18479	2026-09-23 06:33	64.92	OK	18480	2026-09-23 06:34	63.57	OK
18481	2026-09-23 06:35	63.15	OK	18482	2026-09-23 06:36	61.11	OK
18483	2026-09-23 06:37	64.55	OK	18484	2026-09-23 06:38	63.98	OK
18485	2026-09-23 06:39	62.13	OK	18486	2026-09-23 06:40	63.41	OK
18487	2026-09-23 06:41	63.14	OK	18488	2026-09-23 06:42	62.47	OK
1848	2026-09-23 06:43	62.70	OK	1849	2026-09-23 06:44	64.04	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
18491	2026-09-23 06:45	63.11	OK	18492	2026-09-23 06:46	64.88	OK
18493	2026-09-23 06:47	64.88	OK	18494	2026-09-23 06:48	65.06	OK
18495	2026-09-23 06:49	62.70	OK	18496	2026-09-23 06:50	62.45	OK
18497	2026-09-23 06:51	62.76	OK	18498	2026-09-23 06:52	63.90	OK
18499	2026-09-23 06:53	62.64	OK	18500	2026-09-23 06:54	62.09	OK
18501	2026-09-23 06:55	62.85	OK	18502	2026-09-23 06:56	65.17	OK
18503	2026-09-23 06:57	63.80	OK	18504	2026-09-23 06:58	62.30	OK
18505	2026-09-23 06:59	62.23	OK	18506	2026-09-23 07:00	63.37	OK
18507	2026-09-23 07:01	60.65	OK	18508	2026-09-23 07:02	62.73	OK
18509	2026-09-23 07:03	63.33	OK	18510	2026-09-23 07:04	62.93	OK
18511	2026-09-23 07:05	63.52	OK	18512	2026-09-23 07:06	62.05	OK
18513	2026-09-23 07:07	60.76	OK	18514	2026-09-23 07:08	64.27	OK
18515	2026-09-23 07:09	64.68	OK	18516	2026-09-23 07:10	61.12	OK
18517	2026-09-23 07:11	63.48	OK	18518	2026-09-23 07:12	61.44	OK
18519	2026-09-23 07:13	63.42	OK	18520	2026-09-23 07:14	59.94	OK
18521	2026-09-23 07:15	63.59	OK	18522	2026-09-23 07:16	62.34	OK
18523	2026-09-23 07:17	62.37	OK	18524	2026-09-23 07:18	60.83	OK
18525	2026-09-23 07:19	62.22	OK	18526	2026-09-23 07:20	61.98	OK
18527	2026-09-23 07:21	62.16	OK	18528	2026-09-23 07:22	64.12	OK
18529	2026-09-23 07:23	61.00	OK	18530	2026-09-23 07:24	63.06	OK
18531	2026-09-23 07:25	62.77	OK	18532	2026-09-23 07:26	62.72	OK
18533	2026-09-23 07:27	61.13	OK	18534	2026-09-23 07:28	63.67	OK
18535	2026-09-23 07:29	62.88	OK	18536	2026-09-23 07:30	65.08	OK
18537	2026-09-23 07:31	62.55	OK	18538	2026-09-23 07:32	59.99	OK
18539	2026-09-23 07:33	59.98	OK	18540	2026-09-23 07:34	61.75	OK
18541	2026-09-23 07:35	63.37	OK	18542	2026-09-23 07:36	63.39	OK
18543	2026-09-23 07:37	61.34	OK	18544	2026-09-23 07:38	61.30	OK
18545	2026-09-23 07:39	60.87	OK	18546	2026-09-23 07:40	64.30	OK
18547	2026-09-23 07:41	62.53	OK	18548	2026-09-23 07:42	58.65	OK
1854	2026-09-23 07:43	60.90	OK	1855	2026-09-23 07:44	62.92	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
18551	2026-09-23 07:45	63.78	OK	18552	2026-09-23 07:46	62.69	OK
18553	2026-09-23 07:47	59.25	OK	18554	2026-09-23 07:48	61.87	OK
18555	2026-09-23 07:49	62.22	OK	18556	2026-09-23 07:50	63.17	OK
18557	2026-09-23 07:51	62.60	OK	18558	2026-09-23 07:52	58.66	OK
18559	2026-09-23 07:53	63.29	OK	18560	2026-09-23 07:54	59.30	OK
18561	2026-09-23 07:55	61.74	OK	18562	2026-09-23 07:56	59.83	OK
18563	2026-09-23 07:57	62.58	OK	18564	2026-09-23 07:58	60.84	OK
18565	2026-09-23 07:59	63.30	OK	18566	2026-09-23 08:00	62.89	OK
18567	2026-09-23 08:01	60.47	OK	18568	2026-09-23 08:02	60.75	OK
18569	2026-09-23 08:03	58.76	OK	18570	2026-09-23 08:04	64.17	OK
18571	2026-09-23 08:05	61.12	OK	18572	2026-09-23 08:06	62.46	OK
18573	2026-09-23 08:07	59.11	OK	18574	2026-09-23 08:08	61.02	OK
18575	2026-09-23 08:09	58.67	OK	18576	2026-09-23 08:10	61.28	OK
18577	2026-09-23 08:11	59.38	OK	18578	2026-09-23 08:12	60.27	OK
18579	2026-09-23 08:13	60.18	OK	18580	2026-09-23 08:14	62.81	OK
18581	2026-09-23 08:15	61.13	OK	18582	2026-09-23 08:16	63.62	OK
18583	2026-09-23 08:17	59.69	OK	18584	2026-09-23 08:18	62.10	OK
18585	2026-09-23 08:19	59.68	OK	18586	2026-09-23 08:20	61.76	OK
18587	2026-09-23 08:21	61.63	OK	18588	2026-09-23 08:22	61.74	OK
18589	2026-09-23 08:23	59.22	OK	18590	2026-09-23 08:24	60.26	OK
18591	2026-09-23 08:25	63.09	OK	18592	2026-09-23 08:26	60.30	OK
18593	2026-09-23 08:27	60.94	OK	18594	2026-09-23 08:28	61.29	OK
18595	2026-09-23 08:29	62.55	OK	18596	2026-09-23 08:30	60.61	OK
18597	2026-09-23 08:31	59.71	OK	18598	2026-09-23 08:32	61.56	OK
18599	2026-09-23 08:33	61.44	OK	18600	2026-09-23 08:34	60.40	OK
18601	2026-09-23 08:35	58.78	OK	18602	2026-09-23 08:36	62.48	OK
18603	2026-09-23 08:37	62.81	OK	18604	2026-09-23 08:38	58.07	OK
18605	2026-09-23 08:39	62.60	OK	18606	2026-09-23 08:40	59.17	OK
18607	2026-09-23 08:41	62.84	OK	18608	2026-09-23 08:42	61.84	OK
1860	2026-09-23 08:43	58.53	OK	1861	2026-09-23 08:44	58.60	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
18611	2026-09-23 08:45	59.44	OK	18612	2026-09-23 08:46	61.56	OK
18613	2026-09-23 08:47	61.30	OK	18614	2026-09-23 08:48	57.87	OK
18615	2026-09-23 08:49	61.37	OK	18616	2026-09-23 08:50	58.72	OK
18617	2026-09-23 08:51	61.41	OK	18618	2026-09-23 08:52	59.58	OK
18619	2026-09-23 08:53	58.63	OK	18620	2026-09-23 08:54	59.92	OK
18621	2026-09-23 08:55	61.72	OK	18622	2026-09-23 08:56	62.53	OK
18623	2026-09-23 08:57	58.76	OK	18624	2026-09-23 08:58	61.96	OK
18625	2026-09-23 08:59	58.89	OK	18626	2026-09-23 09:00	60.00	OK
18627	2026-09-23 09:01	60.89	OK	18628	2026-09-23 09:02	60.92	OK
18629	2026-09-23 09:03	60.97	OK	18630	2026-09-23 09:04	62.00	OK
18631	2026-09-23 09:05	58.65	OK	18632	2026-09-23 09:06	61.41	OK
18633	2026-09-23 09:07	60.34	OK	18634	2026-09-23 09:08	60.04	OK
18635	2026-09-23 09:09	59.29	OK	18636	2026-09-23 09:10	62.41	OK
18637	2026-09-23 09:11	59.51	OK	18638	2026-09-23 09:12	58.18	OK
18639	2026-09-23 09:13	58.97	OK	18640	2026-09-23 09:14	59.61	OK
18641	2026-09-23 09:15	61.39	OK	18642	2026-09-23 09:16	59.85	OK
18643	2026-09-23 09:17	58.44	OK	18644	2026-09-23 09:18	59.79	OK
18645	2026-09-23 09:19	61.93	OK	18646	2026-09-23 09:20	60.04	OK
18647	2026-09-23 09:21	59.97	OK	18648	2026-09-23 09:22	58.49	OK
18649	2026-09-23 09:23	61.66	OK	18650	2026-09-23 09:24	59.32	OK
18651	2026-09-23 09:25	61.03	OK	18652	2026-09-23 09:26	61.36	OK
18653	2026-09-23 09:27	61.32	OK	18654	2026-09-23 09:28	61.02	OK
18655	2026-09-23 09:29	59.61	OK	18656	2026-09-23 09:30	60.04	OK
18657	2026-09-23 09:31	57.26	OK	18658	2026-09-23 09:32	59.50	OK
18659	2026-09-23 09:33	61.12	OK	18660	2026-09-23 09:34	59.30	OK
18661	2026-09-23 09:35	60.39	OK	18662	2026-09-23 09:36	61.13	OK
18663	2026-09-23 09:37	59.57	OK	18664	2026-09-23 09:38	60.18	OK
18665	2026-09-23 09:39	59.64	OK	18666	2026-09-23 09:40	59.06	OK
18667	2026-09-23 09:41	61.36	OK	18668	2026-09-23 09:42	57.99	OK
18669	2026-09-23 09:43	58.90	OK	18670	2026-09-23 09:44	61.41	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
18671	2026-09-23 09:45	58.94	OK	18672	2026-09-23 09:46	57.34	OK
18673	2026-09-23 09:47	61.61	OK	18674	2026-09-23 09:48	59.00	OK
18675	2026-09-23 09:49	57.66	OK	18676	2026-09-23 09:50	59.12	OK
18677	2026-09-23 09:51	57.43	OK	18678	2026-09-23 09:52	59.13	OK
18679	2026-09-23 09:53	59.02	OK	18680	2026-09-23 09:54	62.25	OK
18681	2026-09-23 09:55	59.60	OK	18682	2026-09-23 09:56	60.27	OK
18683	2026-09-23 09:57	59.06	OK	18684	2026-09-23 09:58	59.42	OK
18685	2026-09-23 09:59	59.16	OK	18686	2026-09-23 10:00	59.58	OK
18687	2026-09-23 10:01	60.50	OK	18688	2026-09-23 10:02	58.49	OK
18689	2026-09-23 10:03	60.42	OK	18690	2026-09-23 10:04	57.70	OK
18691	2026-09-23 10:05	60.55	OK	18692	2026-09-23 10:06	59.40	OK
18693	2026-09-23 10:07	56.83	OK	18694	2026-09-23 10:08	61.09	OK
18695	2026-09-23 10:09	56.73	OK	18696	2026-09-23 10:10	60.84	OK
18697	2026-09-23 10:11	59.58	OK	18698	2026-09-23 10:12	57.11	OK
18699	2026-09-23 10:13	60.85	OK	18700	2026-09-23 10:14	59.36	OK
18701	2026-09-23 10:15	58.65	OK	18702	2026-09-23 10:16	60.74	OK
18703	2026-09-23 10:17	60.30	OK	18704	2026-09-23 10:18	59.95	OK
18705	2026-09-23 10:19	60.09	OK	18706	2026-09-23 10:20	59.98	OK
18707	2026-09-23 10:21	61.33	OK	18708	2026-09-23 10:22	60.28	OK
18709	2026-09-23 10:23	60.85	OK	18710	2026-09-23 10:24	59.75	OK
18711	2026-09-23 10:25	58.47	OK	18712	2026-09-23 10:26	56.39	OK
18713	2026-09-23 10:27	57.95	OK	18714	2026-09-23 10:28	59.95	OK
18715	2026-09-23 10:29	61.14	OK	18716	2026-09-23 10:30	60.71	OK
18717	2026-09-23 10:31	62.26	OK	18718	2026-09-23 10:32	58.36	OK
18719	2026-09-23 10:33	59.77	OK	18720	2026-09-23 10:34	58.38	OK
18721	2026-09-23 10:35	60.01	OK	18722	2026-09-23 10:36	59.96	OK
18723	2026-09-23 10:37	59.35	OK	18724	2026-09-23 10:38	59.38	OK
18725	2026-09-23 10:39	58.03	OK	18726	2026-09-23 10:40	58.09	OK
18727	2026-09-23 10:41	59.59	OK	18728	2026-09-23 10:42	59.25	OK
1872	2026-09-23 10:43	60.05	OK	1873	2026-09-23 10:44	58.37	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
18731	2026-09-23 10:45	58.91	OK	18732	2026-09-23 10:46	59.95	OK
18733	2026-09-23 10:47	59.96	OK	18734	2026-09-23 10:48	59.42	OK
18735	2026-09-23 10:49	56.76	OK	18736	2026-09-23 10:50	61.14	OK
18737	2026-09-23 10:51	61.12	OK	18738	2026-09-23 10:52	58.70	OK
18739	2026-09-23 10:53	60.54	OK	18740	2026-09-23 10:54	60.29	OK
18741	2026-09-23 10:55	58.81	OK	18742	2026-09-23 10:56	59.36	OK
18743	2026-09-23 10:57	59.83	OK	18744	2026-09-23 10:58	60.30	OK
18745	2026-09-23 10:59	58.20	OK	18746	2026-09-23 11:00	61.79	OK
18747	2026-09-23 11:01	58.26	OK	18748	2026-09-23 11:02	60.31	OK
18749	2026-09-23 11:03	58.34	OK	18750	2026-09-23 11:04	59.92	OK
18751	2026-09-23 11:05	63.21	OK	18752	2026-09-23 11:06	58.54	OK
18753	2026-09-23 11:07	58.50	OK	18754	2026-09-23 11:08	57.32	OK
18755	2026-09-23 11:09	59.94	OK	18756	2026-09-23 11:10	58.94	OK
18757	2026-09-23 11:11	58.03	OK	18758	2026-09-23 11:12	59.90	OK
18759	2026-09-23 11:13	58.16	OK	18760	2026-09-23 11:14	59.60	OK
18761	2026-09-23 11:15	60.10	OK	18762	2026-09-23 11:16	61.31	OK
18763	2026-09-23 11:17	60.31	OK	18764	2026-09-23 11:18	59.63	OK
18765	2026-09-23 11:19	58.26	OK	18766	2026-09-23 11:20	58.37	OK
18767	2026-09-23 11:21	61.38	OK	18768	2026-09-23 11:22	59.74	OK
18769	2026-09-23 11:23	61.08	OK	18770	2026-09-23 11:24	60.39	OK
18771	2026-09-23 11:25	59.25	OK	18772	2026-09-23 11:26	60.57	OK
18773	2026-09-23 11:27	59.89	OK	18774	2026-09-23 11:28	62.04	OK
18775	2026-09-23 11:29	61.58	OK	18776	2026-09-23 11:30	59.71	OK
18777	2026-09-23 11:31	59.83	OK	18778	2026-09-23 11:32	60.91	OK
18779	2026-09-23 11:33	58.30	OK	18780	2026-09-23 11:34	59.91	OK
18781	2026-09-23 11:35	60.21	OK	18782	2026-09-23 11:36	58.50	OK
18783	2026-09-23 11:37	60.48	OK	18784	2026-09-23 11:38	61.61	OK
18785	2026-09-23 11:39	60.19	OK	18786	2026-09-23 11:40	59.58	OK
18787	2026-09-23 11:41	60.79	OK	18788	2026-09-23 11:42	61.45	OK
18788	2026-09-23 11:43	59.90	OK	1879	2026-09-23 11:44	61.02	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
18791	2026-09-23 11:45	57.58	OK	18792	2026-09-23 11:46	60.64	OK
18793	2026-09-23 11:47	59.28	OK	18794	2026-09-23 11:48	58.83	OK
18795	2026-09-23 11:49	60.05	OK	18796	2026-09-23 11:50	58.69	OK
18797	2026-09-23 11:51	61.78	OK	18798	2026-09-23 11:52	59.08	OK
18799	2026-09-23 11:53	61.35	OK	18800	2026-09-23 11:54	59.55	OK
18801	2026-09-23 11:55	61.48	OK	18802	2026-09-23 11:56	58.57	OK
18803	2026-09-23 11:57	57.89	OK	18804	2026-09-23 11:58	58.37	OK
18805	2026-09-23 11:59	59.14	OK	18806	2026-09-23 12:00	58.27	OK
18807	2026-09-23 12:01	61.24	OK	18808	2026-09-23 12:02	59.51	OK
18809	2026-09-23 12:03	57.87	OK	18810	2026-09-23 12:04	59.41	OK
18811	2026-09-23 12:05	59.53	OK	18812	2026-09-23 12:06	60.18	OK
18813	2026-09-23 12:07	58.35	OK	18814	2026-09-23 12:08	59.08	OK
18815	2026-09-23 12:09	61.94	OK	18816	2026-09-23 12:10	60.70	OK
18817	2026-09-23 12:11	60.82	OK	18818	2026-09-23 12:12	59.58	OK
18819	2026-09-23 12:13	62.65	OK	18820	2026-09-23 12:14	59.44	OK
18821	2026-09-23 12:15	61.74	OK	18822	2026-09-23 12:16	61.09	OK
18823	2026-09-23 12:17	60.76	OK	18824	2026-09-23 12:18	58.71	OK
18825	2026-09-23 12:19	57.88	OK	18826	2026-09-23 12:20	59.64	OK
18827	2026-09-23 12:21	60.29	OK	18828	2026-09-23 12:22	59.94	OK
18829	2026-09-23 12:23	59.38	OK	18830	2026-09-23 12:24	60.51	OK
18831	2026-09-23 12:25	59.85	OK	18832	2026-09-23 12:26	60.92	OK
18833	2026-09-23 12:27	60.04	OK	18834	2026-09-23 12:28	58.32	OK
18835	2026-09-23 12:29	58.56	OK	18836	2026-09-23 12:30	58.34	OK
18837	2026-09-23 12:31	58.75	OK	18838	2026-09-23 12:32	60.72	OK
18839	2026-09-23 12:33	59.88	OK	18840	2026-09-23 12:34	60.79	OK
18841	2026-09-23 12:35	58.55	OK	18842	2026-09-23 12:36	62.63	OK
18843	2026-09-23 12:37	57.36	OK	18844	2026-09-23 12:38	59.90	OK
18845	2026-09-23 12:39	59.80	OK	18846	2026-09-23 12:40	59.87	OK
18847	2026-09-23 12:41	62.71	OK	18848	2026-09-23 12:42	61.11	OK
1884	2026-09-23 12:43	61.68	OK	1885	2026-09-23 12:44	61.15	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
18851	2026-09-23 12:45	61.49	OK	18852	2026-09-23 12:46	59.70	OK
18853	2026-09-23 12:47	61.30	OK	18854	2026-09-23 12:48	62.39	OK
18855	2026-09-23 12:49	59.35	OK	18856	2026-09-23 12:50	60.15	OK
18857	2026-09-23 12:51	61.36	OK	18858	2026-09-23 12:52	59.01	OK
18859	2026-09-23 12:53	62.67	OK	18860	2026-09-23 12:54	60.13	OK
18861	2026-09-23 12:55	59.79	OK	18862	2026-09-23 12:56	63.01	OK
18863	2026-09-23 12:57	60.49	OK	18864	2026-09-23 12:58	59.07	OK
18865	2026-09-23 12:59	59.46	OK	18866	2026-09-23 13:00	60.71	OK
18867	2026-09-23 13:01	61.76	OK	18868	2026-09-23 13:02	60.74	OK
18869	2026-09-23 13:03	61.19	OK	18870	2026-09-23 13:04	61.64	OK
18871	2026-09-23 13:05	61.93	OK	18872	2026-09-23 13:06	58.93	OK
18873	2026-09-23 13:07	62.12	OK	18874	2026-09-23 13:08	60.08	OK
18875	2026-09-23 13:09	61.20	OK	18876	2026-09-23 13:10	60.92	OK
18877	2026-09-23 13:11	60.10	OK	18878	2026-09-23 13:12	61.68	OK
18879	2026-09-23 13:13	59.38	OK	18880	2026-09-23 13:14	61.56	OK
18881	2026-09-23 13:15	60.72	OK	18882	2026-09-23 13:16	61.57	OK
18883	2026-09-23 13:17	60.25	OK	18884	2026-09-23 13:18	61.83	OK
18885	2026-09-23 13:19	60.05	OK	18886	2026-09-23 13:20	61.91	OK
18887	2026-09-23 13:21	61.98	OK	18888	2026-09-23 13:22	60.51	OK
18889	2026-09-23 13:23	59.21	OK	18890	2026-09-23 13:24	62.92	OK
18891	2026-09-23 13:25	59.98	OK	18892	2026-09-23 13:26	63.05	OK
18893	2026-09-23 13:27	62.11	OK	18894	2026-09-23 13:28	60.57	OK
18895	2026-09-23 13:29	60.46	OK	18896	2026-09-23 13:30	60.93	OK
18897	2026-09-23 13:31	59.74	OK	18898	2026-09-23 13:32	60.19	OK
18899	2026-09-23 13:33	63.12	OK	18900	2026-09-23 13:34	58.94	OK
18901	2026-09-23 13:35	60.25	OK	18902	2026-09-23 13:36	63.30	OK
18903	2026-09-23 13:37	63.15	OK	18904	2026-09-23 13:38	61.27	OK
18905	2026-09-23 13:39	63.31	OK	18906	2026-09-23 13:40	61.05	OK
18907	2026-09-23 13:41	62.88	OK	18908	2026-09-23 13:42	60.58	OK
18909	2026-09-23 13:43	63.24	OK	1891	2026-09-23 13:44	61.21	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
18911	2026-09-23 13:45	61.41	OK	18912	2026-09-23 13:46	62.32	OK
18913	2026-09-23 13:47	59.00	OK	18914	2026-09-23 13:48	61.22	OK
18915	2026-09-23 13:49	60.26	OK	18916	2026-09-23 13:50	61.70	OK
18917	2026-09-23 13:51	61.58	OK	18918	2026-09-23 13:52	61.77	OK
18919	2026-09-23 13:53	63.24	OK	18920	2026-09-23 13:54	60.61	OK
18921	2026-09-23 13:55	60.84	OK	18922	2026-09-23 13:56	62.02	OK
18923	2026-09-23 13:57	60.39	OK	18924	2026-09-23 13:58	61.51	OK
18925	2026-09-23 13:59	60.48	OK	18926	2026-09-23 14:00	60.68	OK
18927	2026-09-23 14:01	61.23	OK	18928	2026-09-23 14:02	62.44	OK
18929	2026-09-23 14:03	62.49	OK	18930	2026-09-23 14:04	62.19	OK
18931	2026-09-23 14:05	60.20	OK	18932	2026-09-23 14:06	64.88	OK
18933	2026-09-23 14:07	62.70	OK	18934	2026-09-23 14:08	60.70	OK
18935	2026-09-23 14:09	61.13	OK	18936	2026-09-23 14:10	62.33	OK
18937	2026-09-23 14:11	61.40	OK	18938	2026-09-23 14:12	59.24	OK
18939	2026-09-23 14:13	61.49	OK	18940	2026-09-23 14:14	60.60	OK
18941	2026-09-23 14:15	63.46	OK	18942	2026-09-23 14:16	62.19	OK
18943	2026-09-23 14:17	62.75	OK	18944	2026-09-23 14:18	62.54	OK
18945	2026-09-23 14:19	61.43	OK	18946	2026-09-23 14:20	61.13	OK
18947	2026-09-23 14:21	61.70	OK	18948	2026-09-23 14:22	61.80	OK
18949	2026-09-23 14:23	62.15	OK	18950	2026-09-23 14:24	62.70	OK
18951	2026-09-23 14:25	62.48	OK	18952	2026-09-23 14:26	60.31	OK
18953	2026-09-23 14:27	61.22	OK	18954	2026-09-23 14:28	62.77	OK
18955	2026-09-23 14:29	63.72	OK	18956	2026-09-23 14:30	62.08	OK
18957	2026-09-23 14:31	62.44	OK	18958	2026-09-23 14:32	65.59	OK
18959	2026-09-23 14:33	63.58	OK	18960	2026-09-23 14:34	62.53	OK
18961	2026-09-23 14:35	63.08	OK	18962	2026-09-23 14:36	60.63	OK
18963	2026-09-23 14:37	62.22	OK	18964	2026-09-23 14:38	62.61	OK
18965	2026-09-23 14:39	63.24	OK	18966	2026-09-23 14:40	63.10	OK
18967	2026-09-23 14:41	62.95	OK	18968	2026-09-23 14:42	61.03	OK
18969	2026-09-23 14:43	62.93	OK	18970	2026-09-23 14:44	62.63	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
18971	2026-09-23 14:45	63.71	OK	18972	2026-09-23 14:46	60.81	OK
18973	2026-09-23 14:47	62.94	OK	18974	2026-09-23 14:48	65.41	OK
18975	2026-09-23 14:49	62.96	OK	18976	2026-09-23 14:50	62.59	OK
18977	2026-09-23 14:51	62.45	OK	18978	2026-09-23 14:52	62.64	OK
18979	2026-09-23 14:53	65.32	OK	18980	2026-09-23 14:54	63.61	OK
18981	2026-09-23 14:55	64.59	OK	18982	2026-09-23 14:56	62.14	OK
18983	2026-09-23 14:57	62.85	OK	18984	2026-09-23 14:58	63.62	OK
18985	2026-09-23 14:59	62.42	OK	18986	2026-09-23 15:00	62.83	OK
18987	2026-09-23 15:01	65.58	OK	18988	2026-09-23 15:02	61.75	OK
18989	2026-09-23 15:03	61.61	OK	18990	2026-09-23 15:04	64.90	OK
18991	2026-09-23 15:05	64.23	OK	18992	2026-09-23 15:06	64.28	OK
18993	2026-09-23 15:07	62.28	OK	18994	2026-09-23 15:08	61.58	OK
18995	2026-09-23 15:09	66.21	OK	18996	2026-09-23 15:10	63.72	OK
18997	2026-09-23 15:11	63.11	OK	18998	2026-09-23 15:12	61.40	OK
18999	2026-09-23 15:13	61.99	OK	19000	2026-09-23 15:14	63.05	OK
19001	2026-09-23 15:15	63.87	OK	19002	2026-09-23 15:16	65.43	OK
19003	2026-09-23 15:17	65.25	OK	19004	2026-09-23 15:18	61.81	OK
19005	2026-09-23 15:19	63.97	OK	19006	2026-09-23 15:20	64.11	OK
19007	2026-09-23 15:21	62.97	OK	19008	2026-09-23 15:22	63.05	OK
19009	2026-09-23 15:23	65.85	OK	19010	2026-09-23 15:24	61.08	OK
19011	2026-09-23 15:25	65.20	OK	19012	2026-09-23 15:26	64.91	OK
19013	2026-09-23 15:27	63.20	OK	19014	2026-09-23 15:28	64.79	OK
19015	2026-09-23 15:29	62.95	OK	19016	2026-09-23 15:30	63.69	OK
19017	2026-09-23 15:31	65.20	OK	19018	2026-09-23 15:32	62.95	OK
19019	2026-09-23 15:33	63.23	OK	19020	2026-09-23 15:34	66.27	OK
19021	2026-09-23 15:35	63.09	OK	19022	2026-09-23 15:36	64.19	OK
19023	2026-09-23 15:37	62.52	OK	19024	2026-09-23 15:38	64.61	OK
19025	2026-09-23 15:39	64.22	OK	19026	2026-09-23 15:40	64.75	OK
19027	2026-09-23 15:41	64.71	OK	19028	2026-09-23 15:42	64.00	OK
1902	2026-09-23 15:43	63.66	OK	1903	2026-09-23 15:44	61.80	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
19031	2026-09-23 15:45	66.14	OK	19032	2026-09-23 15:46	62.11	OK
19033	2026-09-23 15:47	64.66	OK	19034	2026-09-23 15:48	66.77	OK
19035	2026-09-23 15:49	61.84	OK	19036	2026-09-23 15:50	65.95	OK
19037	2026-09-23 15:51	63.90	OK	19038	2026-09-23 15:52	66.40	OK
19039	2026-09-23 15:53	64.90	OK	19040	2026-09-23 15:54	64.51	OK
19041	2026-09-23 15:55	65.25	OK	19042	2026-09-23 15:56	64.44	OK
19043	2026-09-23 15:57	64.17	OK	19044	2026-09-23 15:58	65.67	OK
19045	2026-09-23 15:59	65.89	OK	19046	2026-09-23 16:00	63.05	OK
19047	2026-09-23 16:01	63.10	OK	19048	2026-09-23 16:02	63.90	OK
19049	2026-09-23 16:03	64.89	OK	19050	2026-09-23 16:04	67.03	OK
19051	2026-09-23 16:05	65.16	OK	19052	2026-09-23 16:06	66.66	OK
19053	2026-09-23 16:07	64.55	OK	19054	2026-09-23 16:08	65.35	OK
19055	2026-09-23 16:09	64.75	OK	19056	2026-09-23 16:10	64.92	OK
19057	2026-09-23 16:11	62.54	OK	19058	2026-09-23 16:12	66.78	OK
19059	2026-09-23 16:13	64.09	OK	19060	2026-09-23 16:14	64.91	OK
19061	2026-09-23 16:15	67.78	OK	19062	2026-09-23 16:16	65.16	OK
19063	2026-09-23 16:17	66.22	OK	19064	2026-09-23 16:18	65.22	OK
19065	2026-09-23 16:19	65.60	OK	19066	2026-09-23 16:20	66.64	OK
19067	2026-09-23 16:21	65.85	OK	19068	2026-09-23 16:22	66.24	OK
19069	2026-09-23 16:23	65.95	OK	19070	2026-09-23 16:24	67.37	OK
19071	2026-09-23 16:25	64.16	OK	19072	2026-09-23 16:26	66.22	OK
19073	2026-09-23 16:27	65.96	OK	19074	2026-09-23 16:28	63.92	OK
19075	2026-09-23 16:29	67.16	OK	19076	2026-09-23 16:30	64.02	OK
19077	2026-09-23 16:31	66.49	OK	19078	2026-09-23 16:32	67.56	OK
19079	2026-09-23 16:33	65.94	OK	19080	2026-09-23 16:34	64.91	OK
19081	2026-09-23 16:35	65.39	OK	19082	2026-09-23 16:36	67.62	OK
19083	2026-09-23 16:37	64.89	OK	19084	2026-09-23 16:38	63.97	OK
19085	2026-09-23 16:39	65.10	OK	19086	2026-09-23 16:40	66.58	OK
19087	2026-09-23 16:41	66.31	OK	19088	2026-09-23 16:42	64.91	OK
1908	2026-09-23 16:43	64.37	OK	1909	2026-09-23 16:44	66.18	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
19091	2026-09-23 16:45	65.77	OK	19092	2026-09-23 16:46	66.02	OK
19093	2026-09-23 16:47	67.75	OK	19094	2026-09-23 16:48	66.56	OK
19095	2026-09-23 16:49	65.01	OK	19096	2026-09-23 16:50	67.80	OK
19097	2026-09-23 16:51	66.72	OK	19098	2026-09-23 16:52	66.64	OK
19099	2026-09-23 16:53	64.95	OK	19100	2026-09-23 16:54	64.70	OK
19101	2026-09-23 16:55	65.06	OK	19102	2026-09-23 16:56	64.02	OK
19103	2026-09-23 16:57	67.80	OK	19104	2026-09-23 16:58	67.60	OK
19105	2026-09-23 16:59	67.67	OK	19106	2026-09-23 17:00	68.23	OK
19107	2026-09-23 17:01	65.89	OK	19108	2026-09-23 17:02	69.36	OK
19109	2026-09-23 17:03	66.00	OK	19110	2026-09-23 17:04	66.97	OK
19111	2026-09-23 17:05	66.63	OK	19112	2026-09-23 17:06	67.77	OK
19113	2026-09-23 17:07	66.77	OK	19114	2026-09-23 17:08	65.47	OK
19115	2026-09-23 17:09	69.71	OK	19116	2026-09-23 17:10	67.53	OK
19117	2026-09-23 17:11	68.46	OK	19118	2026-09-23 17:12	64.60	OK
19119	2026-09-23 17:13	67.71	OK	19120	2026-09-23 17:14	65.07	OK
19121	2026-09-23 17:15	67.62	OK	19122	2026-09-23 17:16	67.07	OK
19123	2026-09-23 17:17	68.86	OK	19124	2026-09-23 17:18	69.39	OK
19125	2026-09-23 17:19	67.71	OK	19126	2026-09-23 17:20	69.73	OK
19127	2026-09-23 17:21	65.79	OK	19128	2026-09-23 17:22	68.79	OK
19129	2026-09-23 17:23	68.73	OK	19130	2026-09-23 17:24	67.07	OK
19131	2026-09-23 17:25	65.68	OK	19132	2026-09-23 17:26	67.69	OK
19133	2026-09-23 17:27	68.01	OK	19134	2026-09-23 17:28	67.46	OK
19135	2026-09-23 17:29	65.10	OK	19136	2026-09-23 17:30	67.38	OK
19137	2026-09-23 17:31	66.85	OK	19138	2026-09-23 17:32	68.43	OK
19139	2026-09-23 17:33	68.48	OK	19140	2026-09-23 17:34	66.51	OK
19141	2026-09-23 17:35	67.30	OK	19142	2026-09-23 17:36	64.91	OK
19143	2026-09-23 17:37	69.06	OK	19144	2026-09-23 17:38	66.86	OK
19145	2026-09-23 17:39	70.24	OK	19146	2026-09-23 17:40	68.59	OK
19147	2026-09-23 17:41	66.24	OK	19148	2026-09-23 17:42	65.38	OK
1914	2026-09-23 17:43	68.97	OK	1915	2026-09-23 17:44	68.44	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
19151	2026-09-23 17:45	68.18	OK	19152	2026-09-23 17:46	70.31	OK
19153	2026-09-23 17:47	67.47	OK	19154	2026-09-23 17:48	66.66	OK
19155	2026-09-23 17:49	69.84	OK	19156	2026-09-23 17:50	68.83	OK
19157	2026-09-23 17:51	65.54	OK	19158	2026-09-23 17:52	65.89	OK
19159	2026-09-23 17:53	69.23	OK	19160	2026-09-23 17:54	68.16	OK
19161	2026-09-23 17:55	69.18	OK	19162	2026-09-23 17:56	66.87	OK
19163	2026-09-23 17:57	67.78	OK	19164	2026-09-23 17:58	67.71	OK
19165	2026-09-23 17:59	67.31	OK	19166	2026-09-23 18:00	68.34	OK
19167	2026-09-23 18:01	68.68	OK	19168	2026-09-23 18:02	69.07	OK
19169	2026-09-23 18:03	68.22	OK	19170	2026-09-23 18:04	67.91	OK
19171	2026-09-23 18:05	67.28	OK	19172	2026-09-23 18:06	69.17	OK
19173	2026-09-23 18:07	67.50	OK	19174	2026-09-23 18:08	69.44	OK
19175	2026-09-23 18:09	68.99	OK	19176	2026-09-23 18:10	69.22	OK
19177	2026-09-23 18:11	67.87	OK	19178	2026-09-23 18:12	68.25	OK
19179	2026-09-23 18:13	70.39	OK	19180	2026-09-23 18:14	70.06	OK
19181	2026-09-23 18:15	68.81	OK	19182	2026-09-23 18:16	66.53	OK
19183	2026-09-23 18:17	67.43	OK	19184	2026-09-23 18:18	70.47	OK
19185	2026-09-23 18:19	69.06	OK	19186	2026-09-23 18:20	68.31	OK
19187	2026-09-23 18:21	70.97	OK	19188	2026-09-23 18:22	70.08	OK
19189	2026-09-23 18:23	68.31	OK	19190	2026-09-23 18:24	69.63	OK
19191	2026-09-23 18:25	69.30	OK	19192	2026-09-23 18:26	67.63	OK
19193	2026-09-23 18:27	68.88	OK	19194	2026-09-23 18:28	68.52	OK
19195	2026-09-23 18:29	68.94	OK	19196	2026-09-23 18:30	70.61	OK
19197	2026-09-23 18:31	67.82	OK	19198	2026-09-23 18:32	68.23	OK
19199	2026-09-23 18:33	67.07	OK	19200	2026-09-23 18:34	68.70	OK
19201	2026-09-23 18:35	70.00	OK	19202	2026-09-23 18:36	71.11	OK
19203	2026-09-23 18:37	69.63	OK	19204	2026-09-23 18:38	71.38	OK
19205	2026-09-23 18:39	70.17	OK	19206	2026-09-23 18:40	68.86	OK
19207	2026-09-23 18:41	71.85	OK	19208	2026-09-23 18:42	69.99	OK
19209	2026-09-23 18:43	68.82	OK	19210	2026-09-23 18:44	68.31	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
19211	2026-09-23 18:45	70.48	OK	19212	2026-09-23 18:46	68.76	OK
19213	2026-09-23 18:47	68.18	OK	19214	2026-09-23 18:48	71.44	OK
19215	2026-09-23 18:49	68.64	OK	19216	2026-09-23 18:50	71.39	OK
19217	2026-09-23 18:51	70.95	OK	19218	2026-09-23 18:52	68.83	OK
19219	2026-09-23 18:53	68.44	OK	19220	2026-09-23 18:54	66.94	OK
19221	2026-09-23 18:55	68.71	OK	19222	2026-09-23 18:56	72.10	OK
19223	2026-09-23 18:57	68.76	OK	19224	2026-09-23 18:58	69.07	OK
19225	2026-09-23 18:59	70.40	OK	19226	2026-09-23 19:00	70.12	OK
19227	2026-09-23 19:01	68.84	OK	19228	2026-09-23 19:02	68.01	OK
19229	2026-09-23 19:03	72.71	OK	19230	2026-09-23 19:04	69.91	OK
19231	2026-09-23 19:05	68.38	OK	19232	2026-09-23 19:06	71.31	OK
19233	2026-09-23 19:07	69.66	OK	19234	2026-09-23 19:08	69.49	OK
19235	2026-09-23 19:09	67.43	OK	19236	2026-09-23 19:10	70.37	OK
19237	2026-09-23 19:11	72.57	OK	19238	2026-09-23 19:12	69.25	OK
19239	2026-09-23 19:13	70.84	OK	19240	2026-09-23 19:14	70.82	OK
19241	2026-09-23 19:15	69.94	OK	19242	2026-09-23 19:16	70.12	OK
19243	2026-09-23 19:17	69.86	OK	19244	2026-09-23 19:18	70.17	OK
19245	2026-09-23 19:19	71.01	OK	19246	2026-09-23 19:20	71.32	OK
19247	2026-09-23 19:21	70.47	OK	19248	2026-09-23 19:22	71.01	OK
19249	2026-09-23 19:23	71.75	OK	19250	2026-09-23 19:24	69.94	OK
19251	2026-09-23 19:25	71.12	OK	19252	2026-09-23 19:26	72.46	OK
19253	2026-09-23 19:27	70.64	OK	19254	2026-09-23 19:28	71.34	OK
19255	2026-09-23 19:29	71.55	OK	19256	2026-09-23 19:30	70.48	OK
19257	2026-09-23 19:31	72.36	OK	19258	2026-09-23 19:32	70.98	OK
19259	2026-09-23 19:33	70.10	OK	19260	2026-09-23 19:34	69.37	OK
19261	2026-09-23 19:35	70.38	OK	19262	2026-09-23 19:36	71.57	OK
19263	2026-09-23 19:37	70.65	OK	19264	2026-09-23 19:38	71.45	OK
19265	2026-09-23 19:39	68.09	OK	19266	2026-09-23 19:40	70.77	OK
19267	2026-09-23 19:41	68.86	OK	19268	2026-09-23 19:42	71.19	OK
1926	2026-09-23 19:43	72.48	OK	1927	2026-09-23 19:44	70.78	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
19271	2026-09-23 19:45	70.13	OK	19272	2026-09-23 19:46	73.07	OK
19273	2026-09-23 19:47	72.63	OK	19274	2026-09-23 19:48	69.24	OK
19275	2026-09-23 19:49	72.54	OK	19276	2026-09-23 19:50	68.60	OK
19277	2026-09-23 19:51	71.25	OK	19278	2026-09-23 19:52	68.74	OK
19279	2026-09-23 19:53	71.69	OK	19280	2026-09-23 19:54	73.46	OK
19281	2026-09-23 19:55	70.57	OK	19282	2026-09-23 19:56	68.55	OK
19283	2026-09-23 19:57	71.86	OK	19284	2026-09-23 19:58	71.46	OK
19285	2026-09-23 19:59	72.76	OK	19286	2026-09-23 20:00	71.45	OK
19287	2026-09-23 20:01	70.89	OK	19288	2026-09-23 20:02	71.36	OK
19289	2026-09-23 20:03	68.86	OK	19290	2026-09-23 20:04	70.77	OK
19291	2026-09-23 20:05	71.38	OK	19292	2026-09-23 20:06	69.14	OK
19293	2026-09-23 20:07	71.09	OK	19294	2026-09-23 20:08	70.01	OK
19295	2026-09-23 20:09	70.62	OK	19296	2026-09-23 20:10	71.87	OK
19297	2026-09-23 20:11	71.28	OK	19298	2026-09-23 20:12	71.87	OK
19299	2026-09-23 20:13	69.70	OK	19300	2026-09-23 20:14	71.12	OK
19301	2026-09-23 20:15	72.61	OK	19302	2026-09-23 20:16	69.76	OK
19303	2026-09-23 20:17	71.48	OK	19304	2026-09-23 20:18	71.37	OK
19305	2026-09-23 20:19	70.12	OK	19306	2026-09-23 20:20	69.87	OK
19307	2026-09-23 20:21	71.06	OK	19308	2026-09-23 20:22	72.86	OK
19309	2026-09-23 20:23	69.09	OK	19310	2026-09-23 20:24	70.41	OK
19311	2026-09-23 20:25	69.84	OK	19312	2026-09-23 20:26	72.19	OK
19313	2026-09-23 20:27	69.47	OK	19314	2026-09-23 20:28	74.32	OK
19315	2026-09-23 20:29	71.16	OK	19316	2026-09-23 20:30	72.67	OK
19317	2026-09-23 20:31	72.74	OK	19318	2026-09-23 20:32	69.28	OK
19319	2026-09-23 20:33	73.47	OK	19320	2026-09-23 20:34	70.85	OK
19321	2026-09-23 20:35	73.08	OK	19322	2026-09-23 20:36	74.94	OK
19323	2026-09-23 20:37	70.92	OK	19324	2026-09-23 20:38	70.00	OK
19325	2026-09-23 20:39	72.72	OK	19326	2026-09-23 20:40	69.86	OK
19327	2026-09-23 20:41	72.06	OK	19328	2026-09-23 20:42	73.08	OK
1932	2026-09-23 20:43	70.36	OK	1933	2026-09-23 20:44	72.92	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
19331	2026-09-23 20:45	71.54	OK	19332	2026-09-23 20:46	71.23	OK
19333	2026-09-23 20:47	70.51	OK	19334	2026-09-23 20:48	71.20	OK
19335	2026-09-23 20:49	72.04	OK	19336	2026-09-23 20:50	70.70	OK
19337	2026-09-23 20:51	72.37	OK	19338	2026-09-23 20:52	72.11	OK
19339	2026-09-23 20:53	71.11	OK	19340	2026-09-23 20:54	69.80	OK
19341	2026-09-23 20:55	72.85	OK	19342	2026-09-23 20:56	70.14	OK
19343	2026-09-23 20:57	72.90	OK	19344	2026-09-23 20:58	72.70	OK
19345	2026-09-23 20:59	71.24	OK	19346	2026-09-23 21:00	71.36	OK
19347	2026-09-23 21:01	73.71	OK	19348	2026-09-23 21:02	72.40	OK
19349	2026-09-23 21:03	74.21	OK	19350	2026-09-23 21:04	73.25	OK
19351	2026-09-23 21:05	72.69	OK	19352	2026-09-23 21:06	70.56	OK
19353	2026-09-23 21:07	70.54	OK	19354	2026-09-23 21:08	73.06	OK
19355	2026-09-23 21:09	70.56	OK	19356	2026-09-23 21:10	69.81	OK
19357	2026-09-23 21:11	71.51	OK	19358	2026-09-23 21:12	72.43	OK
19359	2026-09-23 21:13	72.22	OK	19360	2026-09-23 21:14	73.50	OK
19361	2026-09-23 21:15	72.80	OK	19362	2026-09-23 21:16	71.56	OK
19363	2026-09-23 21:17	71.56	OK	19364	2026-09-23 21:18	72.84	OK
19365	2026-09-23 21:19	71.27	OK	19366	2026-09-23 21:20	71.55	OK
19367	2026-09-23 21:21	72.25	OK	19368	2026-09-23 21:22	69.87	OK
19369	2026-09-23 21:23	70.95	OK	19370	2026-09-23 21:24	73.57	OK
19371	2026-09-23 21:25	70.24	OK	19372	2026-09-23 21:26	73.66	OK
19373	2026-09-23 21:27	71.32	OK	19374	2026-09-23 21:28	72.90	OK
19375	2026-09-23 21:29	73.17	OK	19376	2026-09-23 21:30	70.93	OK
19377	2026-09-23 21:31	73.63	OK	19378	2026-09-23 21:32	72.28	OK
19379	2026-09-23 21:33	70.99	OK	19380	2026-09-23 21:34	73.54	OK
19381	2026-09-23 21:35	75.13	OK	19382	2026-09-23 21:36	71.17	OK
19383	2026-09-23 21:37	70.22	OK	19384	2026-09-23 21:38	70.69	OK
19385	2026-09-23 21:39	73.98	OK	19386	2026-09-23 21:40	72.50	OK
19387	2026-09-23 21:41	72.18	OK	19388	2026-09-23 21:42	72.73	OK
1938	2026-09-23 21:43	74.03	OK	1939	2026-09-23 21:44	72.27	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
19391	2026-09-23 21:45	71.17	OK	19392	2026-09-23 21:46	74.14	OK
19393	2026-09-23 21:47	73.63	OK	19394	2026-09-23 21:48	72.13	OK
19395	2026-09-23 21:49	71.18	OK	19396	2026-09-23 21:50	71.22	OK
19397	2026-09-23 21:51	70.89	OK	19398	2026-09-23 21:52	71.75	OK
19399	2026-09-23 21:53	74.13	OK	19400	2026-09-23 21:54	72.47	OK
19401	2026-09-23 21:55	73.74	OK	19402	2026-09-23 21:56	70.97	OK
19403	2026-09-23 21:57	72.29	OK	19404	2026-09-23 21:58	71.95	OK
19405	2026-09-23 21:59	73.03	OK	19406	2026-09-23 22:00	71.72	OK
19407	2026-09-23 22:01	72.07	OK	19408	2026-09-23 22:02	71.56	OK
19409	2026-09-23 22:03	72.27	OK	19410	2026-09-23 22:04	74.28	OK
19411	2026-09-23 22:05	72.96	OK	19412	2026-09-23 22:06	72.91	OK
19413	2026-09-23 22:07	71.54	OK	19414	2026-09-23 22:08	71.34	OK
19415	2026-09-23 22:09	74.37	OK	19416	2026-09-23 22:10	71.26	OK
19417	2026-09-23 22:11	74.75	OK	19418	2026-09-23 22:12	70.18	OK
19419	2026-09-23 22:13	73.07	OK	19420	2026-09-23 22:14	70.98	OK
19421	2026-09-23 22:15	73.77	OK	19422	2026-09-23 22:16	72.97	OK
19423	2026-09-23 22:17	70.83	OK	19424	2026-09-23 22:18	72.37	OK
19425	2026-09-23 22:19	73.09	OK	19426	2026-09-23 22:20	71.78	OK
19427	2026-09-23 22:21	74.03	OK	19428	2026-09-23 22:22	71.46	OK
19429	2026-09-23 22:23	71.00	OK	19430	2026-09-23 22:24	72.46	OK
19431	2026-09-23 22:25	75.04	OK	19432	2026-09-23 22:26	72.78	OK
19433	2026-09-23 22:27	73.19	OK	19434	2026-09-23 22:28	73.30	OK
19435	2026-09-23 22:29	71.25	OK	19436	2026-09-23 22:30	71.56	OK
19437	2026-09-23 22:31	72.89	OK	19438	2026-09-23 22:32	72.93	OK
19439	2026-09-23 22:33	72.85	OK	19440	2026-09-23 22:34	74.37	OK
19441	2026-09-23 22:35	73.48	OK	19442	2026-09-23 22:36	74.02	OK
19443	2026-09-23 22:37	72.03	OK	19444	2026-09-23 22:38	73.35	OK
19445	2026-09-23 22:39	72.61	OK	19446	2026-09-23 22:40	73.45	OK
19447	2026-09-23 22:41	70.54	OK	19448	2026-09-23 22:42	75.12	OK
19449	2026-09-23 22:43	72.30	OK	19450	2026-09-23 22:44	70.85	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
19451	2026-09-23 22:45	71.84	OK	19452	2026-09-23 22:46	71.67	OK
19453	2026-09-23 22:47	71.16	OK	19454	2026-09-23 22:48	74.45	OK
19455	2026-09-23 22:49	70.68	OK	19456	2026-09-23 22:50	73.06	OK
19457	2026-09-23 22:51	74.10	OK	19458	2026-09-23 22:52	71.69	OK
19459	2026-09-23 22:53	70.99	OK	19460	2026-09-23 22:54	74.79	OK
19461	2026-09-23 22:55	70.68	OK	19462	2026-09-23 22:56	73.39	OK
19463	2026-09-23 22:57	75.22	OK	19464	2026-09-23 22:58	73.62	OK
19465	2026-09-23 22:59	72.34	OK	19466	2026-09-23 23:00	74.25	OK
19467	2026-09-23 23:01	71.89	OK	19468	2026-09-23 23:02	72.65	OK
19469	2026-09-23 23:03	73.73	OK	19470	2026-09-23 23:04	71.79	OK
19471	2026-09-23 23:05	73.48	OK	19472	2026-09-23 23:06	72.42	OK
19473	2026-09-23 23:07	74.47	OK	19474	2026-09-23 23:08	73.82	OK
19475	2026-09-23 23:09	71.18	OK	19476	2026-09-23 23:10	74.24	OK
19477	2026-09-23 23:11	71.87	OK	19478	2026-09-23 23:12	72.44	OK
19479	2026-09-23 23:13	70.08	OK	19480	2026-09-23 23:14	70.88	OK
19481	2026-09-23 23:15	72.56	OK	19482	2026-09-23 23:16	73.83	OK
19483	2026-09-23 23:17	71.11	OK	19484	2026-09-23 23:18	73.17	OK
19485	2026-09-23 23:19	71.69	OK	19486	2026-09-23 23:20	74.08	OK
19487	2026-09-23 23:21	72.37	OK	19488	2026-09-23 23:22	72.90	OK
19489	2026-09-23 23:23	70.80	OK	19490	2026-09-23 23:24	72.69	OK
19491	2026-09-23 23:25	73.96	OK	19492	2026-09-23 23:26	71.71	OK
19493	2026-09-23 23:27	70.97	OK	19494	2026-09-23 23:28	71.00	OK
19495	2026-09-23 23:29	72.33	OK	19496	2026-09-23 23:30	74.47	OK
19497	2026-09-23 23:31	70.05	OK	19498	2026-09-23 23:32	72.61	OK
19499	2026-09-23 23:33	73.32	OK	19500	2026-09-23 23:34	75.13	OK
19501	2026-09-23 23:35	71.24	OK	19502	2026-09-23 23:36	72.64	OK
19503	2026-09-23 23:37	72.54	OK	19504	2026-09-23 23:38	74.28	OK
19505	2026-09-23 23:39	72.21	OK	19506	2026-09-23 23:40	73.66	OK
19507	2026-09-23 23:41	72.35	OK	19508	2026-09-23 23:42	71.28	OK
19509	2026-09-23 23:43	74.57	OK	19510	2026-09-23 23:44	73.95	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
19511	2026-09-23 23:45	73.50	OK	19512	2026-09-23 23:46	73.07	OK
19513	2026-09-23 23:47	73.50	OK	19514	2026-09-23 23:48	71.56	OK
19515	2026-09-23 23:49	72.27	OK	19516	2026-09-23 23:50	70.49	OK
19517	2026-09-23 23:51	72.48	OK	19518	2026-09-23 23:52	74.21	OK
19519	2026-09-23 23:53	74.21	OK	19520	2026-09-23 23:54	71.17	OK
19521	2026-09-23 23:55	73.46	OK	19522	2026-09-23 23:56	73.37	OK
19523	2026-09-23 23:57	72.50	OK	19524	2026-09-23 23:58	71.42	OK
19525	2026-09-23 23:59	72.87	OK	19526	2026-09-24 00:00	70.21	OK
19527	2026-09-24 00:01	73.34	OK	19528	2026-09-24 00:02	73.03	OK
19529	2026-09-24 00:03	71.21	OK	19530	2026-09-24 00:04	72.94	OK
19531	2026-09-24 00:05	73.42	OK	19532	2026-09-24 00:06	74.34	OK
19533	2026-09-24 00:07	72.15	OK	19534	2026-09-24 00:08	73.71	OK
19535	2026-09-24 00:09	72.51	OK	19536	2026-09-24 00:10	73.79	OK
19537	2026-09-24 00:11	73.24	OK	19538	2026-09-24 00:12	71.35	OK
19539	2026-09-24 00:13	72.93	OK	19540	2026-09-24 00:14	70.70	OK
19541	2026-09-24 00:15	74.27	OK	19542	2026-09-24 00:16	71.75	OK
19543	2026-09-24 00:17	72.74	OK	19544	2026-09-24 00:18	71.89	OK
19545	2026-09-24 00:19	73.62	OK	19546	2026-09-24 00:20	71.73	OK
19547	2026-09-24 00:21	71.80	OK	19548	2026-09-24 00:22	70.98	OK
19549	2026-09-24 00:23	72.28	OK	19550	2026-09-24 00:24	72.74	OK
19551	2026-09-24 00:25	72.92	OK	19552	2026-09-24 00:26	71.94	OK
19553	2026-09-24 00:27	70.87	OK	19554	2026-09-24 00:28	72.87	OK
19555	2026-09-24 00:29	69.60	OK	19556	2026-09-24 00:30	72.78	OK
19557	2026-09-24 00:31	72.77	OK	19558	2026-09-24 00:32	72.34	OK
19559	2026-09-24 00:33	71.53	OK	19560	2026-09-24 00:34	70.94	OK
19561	2026-09-24 00:35	69.87	OK	19562	2026-09-24 00:36	69.64	OK
19563	2026-09-24 00:37	71.67	OK	19564	2026-09-24 00:38	71.55	OK
19565	2026-09-24 00:39	73.72	OK	19566	2026-09-24 00:40	72.62	OK
19567	2026-09-24 00:41	73.35	OK	19568	2026-09-24 00:42	70.34	OK
19569	2026-09-24 00:43	72.62	OK	19570	2026-09-24 00:44	72.68	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
19571	2026-09-24 00:45	71.96	OK	19572	2026-09-24 00:46	70.54	OK
19573	2026-09-24 00:47	69.98	OK	19574	2026-09-24 00:48	69.62	OK
19575	2026-09-24 00:49	72.52	OK	19576	2026-09-24 00:50	73.05	OK
19577	2026-09-24 00:51	71.15	OK	19578	2026-09-24 00:52	70.45	OK
19579	2026-09-24 00:53	72.73	OK	19580	2026-09-24 00:54	71.66	OK
19581	2026-09-24 00:55	70.49	OK	19582	2026-09-24 00:56	70.60	OK
19583	2026-09-24 00:57	72.16	OK	19584	2026-09-24 00:58	71.71	OK
19585	2026-09-24 00:59	71.14	OK	19586	2026-09-24 01:00	72.09	OK
19587	2026-09-24 01:01	69.36	OK	19588	2026-09-24 01:02	71.05	OK
19589	2026-09-24 01:03	70.88	OK	19590	2026-09-24 01:04	71.26	OK
19591	2026-09-24 01:05	71.25	OK	19592	2026-09-24 01:06	70.43	OK
19593	2026-09-24 01:07	69.35	OK	19594	2026-09-24 01:08	71.64	OK
19595	2026-09-24 01:09	71.67	OK	19596	2026-09-24 01:10	73.04	OK
19597	2026-09-24 01:11	71.44	OK	19598	2026-09-24 01:12	70.25	OK
19599	2026-09-24 01:13	71.34	OK	19600	2026-09-24 01:14	70.73	OK
19601	2026-09-24 01:15	71.58	OK	19602	2026-09-24 01:16	72.94	OK
19603	2026-09-24 01:17	69.84	OK	19604	2026-09-24 01:18	68.89	OK
19605	2026-09-24 01:19	70.95	OK	19606	2026-09-24 01:20	70.10	OK
19607	2026-09-24 01:21	73.37	OK	19608	2026-09-24 01:22	70.87	OK
19609	2026-09-24 01:23	70.30	OK	19610	2026-09-24 01:24	72.60	OK
19611	2026-09-24 01:25	72.01	OK	19612	2026-09-24 01:26	69.42	OK
19613	2026-09-24 01:27	71.43	OK	19614	2026-09-24 01:28	69.27	OK
19615	2026-09-24 01:29	69.59	OK	19616	2026-09-24 01:30	68.63	OK
19617	2026-09-24 01:31	71.04	OK	19618	2026-09-24 01:32	69.28	OK
19619	2026-09-24 01:33	72.20	OK	19620	2026-09-24 01:34	70.57	OK
19621	2026-09-24 01:35	71.07	OK	19622	2026-09-24 01:36	72.22	OK
19623	2026-09-24 01:37	70.99	OK	19624	2026-09-24 01:38	73.42	OK
19625	2026-09-24 01:39	70.00	OK	19626	2026-09-24 01:40	71.84	OK
19627	2026-09-24 01:41	69.63	OK	19628	2026-09-24 01:42	70.97	OK
1962	2026-09-24 01:43	71.28	OK	1963	2026-09-24 01:44	71.80	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
19631	2026-09-24 01:45	70.67	OK	19632	2026-09-24 01:46	69.13	OK
19633	2026-09-24 01:47	69.41	OK	19634	2026-09-24 01:48	72.17	OK
19635	2026-09-24 01:49	68.43	OK	19636	2026-09-24 01:50	70.30	OK
19637	2026-09-24 01:51	71.34	OK	19638	2026-09-24 01:52	69.70	OK
19639	2026-09-24 01:53	72.28	OK	19640	2026-09-24 01:54	71.55	OK
19641	2026-09-24 01:55	71.37	OK	19642	2026-09-24 01:56	71.46	OK
19643	2026-09-24 01:57	71.10	OK	19644	2026-09-24 01:58	69.45	OK
19645	2026-09-24 01:59	69.33	OK	19646	2026-09-24 02:00	69.37	OK
19647	2026-09-24 02:01	67.96	OK	19648	2026-09-24 02:02	69.20	OK
19649	2026-09-24 02:03	69.08	OK	19650	2026-09-24 02:04	69.52	OK
19651	2026-09-24 02:05	69.60	OK	19652	2026-09-24 02:06	70.55	OK
19653	2026-09-24 02:07	69.95	OK	19654	2026-09-24 02:08	71.27	OK
19655	2026-09-24 02:09	71.26	OK	19656	2026-09-24 02:10	71.16	OK
19657	2026-09-24 02:11	71.13	OK	19658	2026-09-24 02:12	69.56	OK
19659	2026-09-24 02:13	72.43	OK	19660	2026-09-24 02:14	72.26	OK
19661	2026-09-24 02:15	70.67	OK	19662	2026-09-24 02:16	73.19	OK
19663	2026-09-24 02:17	70.07	OK	19664	2026-09-24 02:18	70.36	OK
19665	2026-09-24 02:19	69.51	OK	19666	2026-09-24 02:20	69.08	OK
19667	2026-09-24 02:21	68.01	OK	19668	2026-09-24 02:22	69.67	OK
19669	2026-09-24 02:23	68.59	OK	19670	2026-09-24 02:24	69.56	OK
19671	2026-09-24 02:25	69.46	OK	19672	2026-09-24 02:26	68.34	OK
19673	2026-09-24 02:27	69.11	OK	19674	2026-09-24 02:28	71.58	OK
19675	2026-09-24 02:29	68.57	OK	19676	2026-09-24 02:30	71.79	OK
19677	2026-09-24 02:31	68.12	OK	19678	2026-09-24 02:32	69.03	OK
19679	2026-09-24 02:33	70.22	OK	19680	2026-09-24 02:34	69.17	OK
19681	2026-09-24 02:35	66.70	OK	19682	2026-09-24 02:36	69.47	OK
19683	2026-09-24 02:37	69.60	OK	19684	2026-09-24 02:38	70.38	OK
19685	2026-09-24 02:39	68.61	OK	19686	2026-09-24 02:40	68.28	OK
19687	2026-09-24 02:41	66.98	OK	19688	2026-09-24 02:42	69.73	OK
1968	2026-09-24 02:43	68.63	OK	1969	2026-09-24 02:44	70.35	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
1969	2026-09-24 02:45	69.71	OK	1969	2026-09-24 02:46	68.57	OK
1				2			
1969	2026-09-24 02:47	67.82	OK	1969	2026-09-24 02:48	69.51	OK
3				4			
1969	2026-09-24 02:49	68.78	OK	1969	2026-09-24 02:50	70.12	OK
5				6			
1969	2026-09-24 02:51	67.37	OK	1969	2026-09-24 02:52	66.46	OK
7				8			
1969	2026-09-24 02:53	70.29	OK	1970	2026-09-24 02:54	67.21	OK
9				0			
1970	2026-09-24 02:55	68.67	OK	1970	2026-09-24 02:56	69.10	OK
1				2			
1970	2026-09-24 02:57	68.21	OK	1970	2026-09-24 02:58	67.25	OK
3				4			
1970	2026-09-24 02:59	70.04	OK	1970	2026-09-24 03:00	67.59	OK
5				6			
1970	2026-09-24 03:01	68.52	OK	1970	2026-09-24 03:02	70.22	OK
7				8			
1970	2026-09-24 03:03	66.65	OK	1971	2026-09-24 03:04	69.01	OK
9				0			
1971	2026-09-24 03:05	69.20	OK	1971	2026-09-24 03:06	68.06	OK
1				2			
1971	2026-09-24 03:07	67.36	OK	1971	2026-09-24 03:08	68.33	OK
3				4			
1971	2026-09-24 03:09	69.94	OK	1971	2026-09-24 03:10	68.61	OK
5				6			
1971	2026-09-24 03:11	69.47	OK	1971	2026-09-24 03:12	69.91	OK
7				8			
1971	2026-09-24 03:13	67.24	OK	1972	2026-09-24 03:14	68.05	OK
9				0			
1972	2026-09-24 03:15	66.09	OK	1972	2026-09-24 03:16	69.28	OK
1				2			
1972	2026-09-24 03:17	71.26	OK	1972	2026-09-24 03:18	70.45	OK
3				4			
1972	2026-09-24 03:19	65.77	OK	1972	2026-09-24 03:20	69.05	OK
5				6			
1972	2026-09-24 03:21	68.16	OK	1972	2026-09-24 03:22	65.39	OK
7				8			
1972	2026-09-24 03:23	70.78	OK	1973	2026-09-24 03:24	66.63	OK
9				0			
1973	2026-09-24 03:25	69.50	OK	1973	2026-09-24 03:26	68.80	OK
1				2			
1973	2026-09-24 03:27	69.86	OK	1973	2026-09-24 03:28	69.28	OK
3				4			
1973	2026-09-24 03:29	68.73	OK	1973	2026-09-24 03:30	68.22	OK
5				6			
1973	2026-09-24 03:31	67.18	OK	1973	2026-09-24 03:32	70.23	OK
7				8			
1973	2026-09-24 03:33	70.41	OK	1974	2026-09-24 03:34	65.92	OK
9				0			
1974	2026-09-24 03:35	67.12	OK	1974	2026-09-24 03:36	67.72	OK
1				2			
1974	2026-09-24 03:37	68.88	OK	1974	2026-09-24 03:38	66.93	OK
3				4			
1974	2026-09-24 03:39	65.27	OK	1974	2026-09-24 03:40	70.10	OK
5				6			
1974	2026-09-24 03:41	68.67	OK	1974	2026-09-24 03:42	68.36	OK
7				8			
1974	2026-09-24 03:43	67.84	OK	1975	2026-09-24 03:44	66.48	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
19751	2026-09-24 03:45	67.11	OK	19752	2026-09-24 03:46	66.76	OK
19753	2026-09-24 03:47	64.53	OK	19754	2026-09-24 03:48	67.98	OK
19755	2026-09-24 03:49	66.91	OK	19756	2026-09-24 03:50	66.91	OK
19757	2026-09-24 03:51	66.76	OK	19758	2026-09-24 03:52	70.47	OK
19759	2026-09-24 03:53	68.76	OK	19760	2026-09-24 03:54	66.85	OK
19761	2026-09-24 03:55	70.35	OK	19762	2026-09-24 03:56	65.95	OK
19763	2026-09-24 03:57	68.73	OK	19764	2026-09-24 03:58	66.92	OK
19765	2026-09-24 03:59	69.46	OK	19766	2026-09-24 04:00	68.35	OK
19767	2026-09-24 04:01	67.33	OK	19768	2026-09-24 04:02	66.92	OK
19769	2026-09-24 04:03	68.38	OK	19770	2026-09-24 04:04	64.96	OK
19771	2026-09-24 04:05	65.15	OK	19772	2026-09-24 04:06	68.23	OK
19773	2026-09-24 04:07	66.37	OK	19774	2026-09-24 04:08	67.10	OK
19775	2026-09-24 04:09	66.36	OK	19776	2026-09-24 04:10	66.72	OK
19777	2026-09-24 04:11	68.62	OK	19778	2026-09-24 04:12	66.07	OK
19779	2026-09-24 04:13	65.83	OK	19780	2026-09-24 04:14	66.38	OK
19781	2026-09-24 04:15	67.30	OK	19782	2026-09-24 04:16	66.09	OK
19783	2026-09-24 04:17	68.41	OK	19784	2026-09-24 04:18	67.49	OK
19785	2026-09-24 04:19	66.77	OK	19786	2026-09-24 04:20	65.92	OK
19787	2026-09-24 04:21	66.71	OK	19788	2026-09-24 04:22	65.72	OK
19789	2026-09-24 04:23	68.45	OK	19790	2026-09-24 04:24	66.40	OK
19791	2026-09-24 04:25	66.75	OK	19792	2026-09-24 04:26	66.62	OK
19793	2026-09-24 04:27	67.01	OK	19794	2026-09-24 04:28	65.91	OK
19795	2026-09-24 04:29	64.83	OK	19796	2026-09-24 04:30	68.54	OK
19797	2026-09-24 04:31	65.19	OK	19798	2026-09-24 04:32	66.04	OK
19799	2026-09-24 04:33	67.27	OK	19800	2026-09-24 04:34	64.17	OK
19801	2026-09-24 04:35	66.79	OK	19802	2026-09-24 04:36	67.71	OK
19803	2026-09-24 04:37	66.33	OK	19804	2026-09-24 04:38	68.39	OK
19805	2026-09-24 04:39	66.08	OK	19806	2026-09-24 04:40	67.34	OK
19807	2026-09-24 04:41	66.65	OK	19808	2026-09-24 04:42	64.35	OK
1980	2026-09-24 04:43	67.90	OK	1981	2026-09-24 04:44	66.12	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
19811	2026-09-24 04:45	64.60	OK	19812	2026-09-24 04:46	65.13	OK
19813	2026-09-24 04:47	67.47	OK	19814	2026-09-24 04:48	67.24	OK
19815	2026-09-24 04:49	64.62	OK	19816	2026-09-24 04:50	67.27	OK
19817	2026-09-24 04:51	63.26	OK	19818	2026-09-24 04:52	65.37	OK
19819	2026-09-24 04:53	66.85	OK	19820	2026-09-24 04:54	65.78	OK
19821	2026-09-24 04:55	65.27	OK	19822	2026-09-24 04:56	65.99	OK
19823	2026-09-24 04:57	64.43	OK	19824	2026-09-24 04:58	66.11	OK
19825	2026-09-24 04:59	65.73	OK	19826	2026-09-24 05:00	64.66	OK
19827	2026-09-24 05:01	64.65	OK	19828	2026-09-24 05:02	63.39	OK
19829	2026-09-24 05:03	66.03	OK	19830	2026-09-24 05:04	65.72	OK
19831	2026-09-24 05:05	64.51	OK	19832	2026-09-24 05:06	68.80	OK
19833	2026-09-24 05:07	64.74	OK	19834	2026-09-24 05:08	64.06	OK
19835	2026-09-24 05:09	64.34	OK	19836	2026-09-24 05:10	65.29	OK
19837	2026-09-24 05:11	64.54	OK	19838	2026-09-24 05:12	63.75	OK
19839	2026-09-24 05:13	64.45	OK	19840	2026-09-24 05:14	67.86	OK
19841	2026-09-24 05:15	65.12	OK	19842	2026-09-24 05:16	63.00	OK
19843	2026-09-24 05:17	67.13	OK	19844	2026-09-24 05:18	63.57	OK
19845	2026-09-24 05:19	68.14	OK	19846	2026-09-24 05:20	67.05	OK
19847	2026-09-24 05:21	65.82	OK	19848	2026-09-24 05:22	65.05	OK
19849	2026-09-24 05:23	64.84	OK	19850	2026-09-24 05:24	66.44	OK
19851	2026-09-24 05:25	64.80	OK	19852	2026-09-24 05:26	63.95	OK
19853	2026-09-24 05:27	65.05	OK	19854	2026-09-24 05:28	66.10	OK
19855	2026-09-24 05:29	65.16	OK	19856	2026-09-24 05:30	63.59	OK
19857	2026-09-24 05:31	62.77	OK	19858	2026-09-24 05:32	64.00	OK
19859	2026-09-24 05:33	65.64	OK	19860	2026-09-24 05:34	65.03	OK
19861	2026-09-24 05:35	65.14	OK	19862	2026-09-24 05:36	63.67	OK
19863	2026-09-24 05:37	64.65	OK	19864	2026-09-24 05:38	64.43	OK
19865	2026-09-24 05:39	63.31	OK	19866	2026-09-24 05:40	63.56	OK
19867	2026-09-24 05:41	65.42	OK	19868	2026-09-24 05:42	65.99	OK
1986	2026-09-24 05:43	65.30	OK	1987	2026-09-24 05:44	65.91	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
19871	2026-09-24 05:45	65.42	OK	19872	2026-09-24 05:46	63.20	OK
19873	2026-09-24 05:47	64.66	OK	19874	2026-09-24 05:48	66.92	OK
19875	2026-09-24 05:49	62.11	OK	19876	2026-09-24 05:50	63.95	OK
19877	2026-09-24 05:51	64.24	OK	19878	2026-09-24 05:52	62.44	OK
19879	2026-09-24 05:53	64.21	OK	19880	2026-09-24 05:54	63.16	OK
19881	2026-09-24 05:55	64.29	OK	19882	2026-09-24 05:56	62.52	OK
19883	2026-09-24 05:57	63.35	OK	19884	2026-09-24 05:58	63.84	OK
19885	2026-09-24 05:59	60.90	OK	19886	2026-09-24 06:00	64.56	OK
19887	2026-09-24 06:01	65.00	OK	19888	2026-09-24 06:02	66.12	OK
19889	2026-09-24 06:03	63.48	OK	19890	2026-09-24 06:04	64.62	OK
19891	2026-09-24 06:05	61.02	OK	19892	2026-09-24 06:06	62.89	OK
19893	2026-09-24 06:07	65.49	OK	19894	2026-09-24 06:08	65.35	OK
19895	2026-09-24 06:09	64.25	OK	19896	2026-09-24 06:10	63.68	OK
19897	2026-09-24 06:11	62.11	OK	19898	2026-09-24 06:12	63.05	OK
19899	2026-09-24 06:13	63.12	OK	19900	2026-09-24 06:14	64.07	OK
19901	2026-09-24 06:15	64.54	OK	19902	2026-09-24 06:16	61.86	OK
19903	2026-09-24 06:17	62.88	OK	19904	2026-09-24 06:18	62.48	OK
19905	2026-09-24 06:19	63.78	OK	19906	2026-09-24 06:20	62.86	OK
19907	2026-09-24 06:21	64.64	OK	19908	2026-09-24 06:22	63.79	OK
19909	2026-09-24 06:23	65.86	OK	19910	2026-09-24 06:24	61.73	OK
19911	2026-09-24 06:25	64.26	OK	19912	2026-09-24 06:26	63.52	OK
19913	2026-09-24 06:27	64.23	OK	19914	2026-09-24 06:28	61.68	OK
19915	2026-09-24 06:29	61.98	OK	19916	2026-09-24 06:30	63.42	OK
19917	2026-09-24 06:31	63.35	OK	19918	2026-09-24 06:32	62.42	OK
19919	2026-09-24 06:33	64.80	OK	19920	2026-09-24 06:34	62.82	OK
19921	2026-09-24 06:35	60.95	OK	19922	2026-09-24 06:36	61.64	OK
19923	2026-09-24 06:37	62.37	OK	19924	2026-09-24 06:38	64.12	OK
19925	2026-09-24 06:39	62.77	OK	19926	2026-09-24 06:40	61.82	OK
19927	2026-09-24 06:41	61.71	OK	19928	2026-09-24 06:42	62.89	OK
19929	2026-09-24 06:43	64.61	OK	19930	2026-09-24 06:44	61.68	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
1993 1	2026-09-24 06:45	60.50	OK	1993 2	2026-09-24 06:46	62.72	OK
1993 3	2026-09-24 06:47	60.82	OK	1993 4	2026-09-24 06:48	63.38	OK
1993 5	2026-09-24 06:49	62.78	OK	1993 6	2026-09-24 06:50	63.48	OK
1993 7	2026-09-24 06:51	63.10	OK	1993 8	2026-09-24 06:52	61.99	OK
1993 9	2026-09-24 06:53	63.04	OK	1994 0	2026-09-24 06:54	64.88	OK
1994 1	2026-09-24 06:55	60.40	OK	1994 2	2026-09-24 06:56	61.28	OK
1994 3	2026-09-24 06:57	60.06	OK	1994 4	2026-09-24 06:58	62.42	OK
1994 5	2026-09-24 06:59	62.30	OK	1994 6	2026-09-24 07:00	63.20	OK
1994 7	2026-09-24 07:01	62.56	OK	1994 8	2026-09-24 07:02	59.60	OK
1994 9	2026-09-24 07:03	61.61	OK	1995 0	2026-09-24 07:04	64.10	OK
1995 1	2026-09-24 07:05	62.15	OK	1995 2	2026-09-24 07:06	65.01	OK
1995 3	2026-09-24 07:07	61.47	OK	1995 4	2026-09-24 07:08	60.61	OK
1995 5	2026-09-24 07:09	63.07	OK	1995 6	2026-09-24 07:10	62.49	OK
1995 7	2026-09-24 07:11	63.46	OK	1995 8	2026-09-24 07:12	60.71	OK
1995 9	2026-09-24 07:13	61.85	OK	1996 0	2026-09-24 07:14	59.66	OK
1996 1	2026-09-24 07:15	61.70	OK	1996 2	2026-09-24 07:16	62.91	OK
1996 3	2026-09-24 07:17	61.17	OK	1996 4	2026-09-24 07:18	61.54	OK
1996 5	2026-09-24 07:19	63.53	OK	1996 6	2026-09-24 07:20	60.49	OK
1996 7	2026-09-24 07:21	61.71	OK	1996 8	2026-09-24 07:22	59.44	OK
1996 9	2026-09-24 07:23	62.39	OK	1997 0	2026-09-24 07:24	62.26	OK
1997 1	2026-09-24 07:25	63.30	OK	1997 2	2026-09-24 07:26	61.72	OK
1997 3	2026-09-24 07:27	62.63	OK	1997 4	2026-09-24 07:28	61.04	OK
1997 5	2026-09-24 07:29	62.50	OK	1997 6	2026-09-24 07:30	61.16	OK
1997 7	2026-09-24 07:31	59.87	OK	1997 8	2026-09-24 07:32	60.70	OK
1997 9	2026-09-24 07:33	60.44	OK	1998 0	2026-09-24 07:34	62.69	OK
1998 1	2026-09-24 07:35	63.25	OK	1998 2	2026-09-24 07:36	62.89	OK
1998 3	2026-09-24 07:37	59.96	OK	1998 4	2026-09-24 07:38	59.50	OK
1998 5	2026-09-24 07:39	61.32	OK	1998 6	2026-09-24 07:40	61.57	OK
1998 7	2026-09-24 07:41	61.64	OK	1998 8	2026-09-24 07:42	59.55	OK
1998	2026-09-24 07:43	62.65	OK	1999	2026-09-24 07:44	61.65	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
19991	2026-09-24 07:45	61.97	OK	19992	2026-09-24 07:46	63.21	OK
19993	2026-09-24 07:47	64.15	OK	19994	2026-09-24 07:48	63.99	OK
19995	2026-09-24 07:49	60.82	OK	19996	2026-09-24 07:50	60.81	OK
19997	2026-09-24 07:51	63.17	OK	19998	2026-09-24 07:52	62.63	OK
19999	2026-09-24 07:53	61.47	OK	20000	2026-09-24 07:54	61.74	OK
20001	2026-09-24 07:55	60.94	OK	20002	2026-09-24 07:56	62.34	OK
20003	2026-09-24 07:57	61.37	OK	20004	2026-09-24 07:58	61.67	OK
20005	2026-09-24 07:59	60.35	OK	20006	2026-09-24 08:00	61.31	OK
20007	2026-09-24 08:01	60.37	OK	20008	2026-09-24 08:02	61.25	OK
20009	2026-09-24 08:03	63.40	OK	20010	2026-09-24 08:04	58.99	OK
20011	2026-09-24 08:05	58.36	OK	20012	2026-09-24 08:06	62.03	OK
20013	2026-09-24 08:07	59.47	OK	20014	2026-09-24 08:08	62.51	OK
20015	2026-09-24 08:09	59.63	OK	20016	2026-09-24 08:10	62.06	OK
20017	2026-09-24 08:11	62.73	OK	20018	2026-09-24 08:12	58.43	OK
20019	2026-09-24 08:13	60.13	OK	20020	2026-09-24 08:14	62.79	OK
20021	2026-09-24 08:15	61.07	OK	20022	2026-09-24 08:16	61.30	OK
20023	2026-09-24 08:17	60.28	OK	20024	2026-09-24 08:18	60.13	OK
20025	2026-09-24 08:19	61.71	OK	20026	2026-09-24 08:20	63.52	OK
20027	2026-09-24 08:21	59.65	OK	20028	2026-09-24 08:22	62.00	OK
20029	2026-09-24 08:23	61.06	OK	20030	2026-09-24 08:24	59.46	OK
20031	2026-09-24 08:25	57.50	OK	20032	2026-09-24 08:26	63.24	OK
20033	2026-09-24 08:27	57.67	OK	20034	2026-09-24 08:28	61.03	OK
20035	2026-09-24 08:29	61.20	OK	20036	2026-09-24 08:30	62.79	OK
20037	2026-09-24 08:31	60.76	OK	20038	2026-09-24 08:32	61.86	OK
20039	2026-09-24 08:33	62.81	OK	20040	2026-09-24 08:34	60.90	OK
20041	2026-09-24 08:35	63.01	OK	20042	2026-09-24 08:36	59.89	OK
20043	2026-09-24 08:37	60.93	OK	20044	2026-09-24 08:38	59.83	OK
20045	2026-09-24 08:39	61.03	OK	20046	2026-09-24 08:40	60.00	OK
20047	2026-09-24 08:41	60.33	OK	20048	2026-09-24 08:42	59.27	OK
2004	2026-09-24 08:43	58.91	OK	2005	2026-09-24 08:44	58.47	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
20051	2026-09-24 08:45	58.48	OK	20052	2026-09-24 08:46	61.28	OK
20053	2026-09-24 08:47	61.02	OK	20054	2026-09-24 08:48	57.78	OK
20055	2026-09-24 08:49	58.52	OK	20056	2026-09-24 08:50	59.74	OK
20057	2026-09-24 08:51	61.92	OK	20058	2026-09-24 08:52	61.14	OK
20059	2026-09-24 08:53	63.10	OK	20060	2026-09-24 08:54	60.96	OK
20061	2026-09-24 08:55	59.28	OK	20062	2026-09-24 08:56	58.27	OK
20063	2026-09-24 08:57	62.47	OK	20064	2026-09-24 08:58	61.32	OK
20065	2026-09-24 08:59	61.04	OK	20066	2026-09-24 09:00	60.80	OK
20067	2026-09-24 09:01	59.12	OK	20068	2026-09-24 09:02	58.75	OK
20069	2026-09-24 09:03	61.94	OK	20070	2026-09-24 09:04	60.48	OK
20071	2026-09-24 09:05	59.12	OK	20072	2026-09-24 09:06	60.96	OK
20073	2026-09-24 09:07	59.06	OK	20074	2026-09-24 09:08	58.09	OK
20075	2026-09-24 09:09	61.66	OK	20076	2026-09-24 09:10	59.32	OK
20077	2026-09-24 09:11	60.04	OK	20078	2026-09-24 09:12	60.57	OK
20079	2026-09-24 09:13	58.32	OK	20080	2026-09-24 09:14	59.92	OK
20081	2026-09-24 09:15	60.12	OK	20082	2026-09-24 09:16	59.96	OK
20083	2026-09-24 09:17	61.17	OK	20084	2026-09-24 09:18	62.57	OK
20085	2026-09-24 09:19	59.85	OK	20086	2026-09-24 09:20	62.68	OK
20087	2026-09-24 09:21	57.23	OK	20088	2026-09-24 09:22	60.09	OK
20089	2026-09-24 09:23	57.53	OK	20090	2026-09-24 09:24	57.70	OK
20091	2026-09-24 09:25	60.43	OK	20092	2026-09-24 09:26	61.47	OK
20093	2026-09-24 09:27	59.95	OK	20094	2026-09-24 09:28	58.45	OK
20095	2026-09-24 09:29	59.33	OK	20096	2026-09-24 09:30	60.89	OK
20097	2026-09-24 09:31	59.90	OK	20098	2026-09-24 09:32	61.09	OK
20099	2026-09-24 09:33	60.62	OK	20100	2026-09-24 09:34	61.06	OK
20101	2026-09-24 09:35	60.22	OK	20102	2026-09-24 09:36	61.48	OK
20103	2026-09-24 09:37	61.77	OK	20104	2026-09-24 09:38	59.58	OK
20105	2026-09-24 09:39	60.14	OK	20106	2026-09-24 09:40	57.08	OK
20107	2026-09-24 09:41	58.47	OK	20108	2026-09-24 09:42	57.88	OK
2010	2026-09-24 09:43	56.94	OK	2011	2026-09-24 09:44	62.03	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9				0			
20111	2026-09-24 09:45	59.97	OK	20112	2026-09-24 09:46	61.77	OK
20113	2026-09-24 09:47	59.88	OK	20114	2026-09-24 09:48	59.63	OK
20115	2026-09-24 09:49	60.23	OK	20116	2026-09-24 09:50	61.56	OK
20117	2026-09-24 09:51	58.05	OK	20118	2026-09-24 09:52	58.18	OK
20119	2026-09-24 09:53	59.50	OK	20120	2026-09-24 09:54	61.19	OK
20121	2026-09-24 09:55	59.81	OK	20122	2026-09-24 09:56	60.84	OK
20123	2026-09-24 09:57	58.87	OK	20124	2026-09-24 09:58	58.05	OK
20125	2026-09-24 09:59	59.84	OK	20126	2026-09-24 10:00	58.85	OK
20127	2026-09-24 10:01	60.90	OK	20128	2026-09-24 10:02	59.63	OK
20129	2026-09-24 10:03	59.52	OK	20130	2026-09-24 10:04	61.60	OK
20131	2026-09-24 10:05	58.92	OK	20132	2026-09-24 10:06	59.54	OK
20133	2026-09-24 10:07	60.45	OK	20134	2026-09-24 10:08	58.92	OK
20135	2026-09-24 10:09	59.77	OK	20136	2026-09-24 10:10	59.60	OK
20137	2026-09-24 10:11	60.91	OK	20138	2026-09-24 10:12	60.12	OK
20139	2026-09-24 10:13	59.66	OK	20140	2026-09-24 10:14	58.41	OK
20141	2026-09-24 10:15	59.34	OK	20142	2026-09-24 10:16	59.99	OK
20143	2026-09-24 10:17	58.31	OK	20144	2026-09-24 10:18	61.03	OK
20145	2026-09-24 10:19	60.36	OK	20146	2026-09-24 10:20	59.31	OK
20147	2026-09-24 10:21	57.76	OK	20148	2026-09-24 10:22	56.84	OK
20149	2026-09-24 10:23	60.23	OK	20150	2026-09-24 10:24	60.23	OK
20151	2026-09-24 10:25	60.25	OK	20152	2026-09-24 10:26	60.41	OK
20153	2026-09-24 10:27	60.98	OK	20154	2026-09-24 10:28	59.98	OK
20155	2026-09-24 10:29	59.31	OK	20156	2026-09-24 10:30	60.58	OK
20157	2026-09-24 10:31	60.23	OK	20158	2026-09-24 10:32	60.54	OK
20159	2026-09-24 10:33	57.81	OK	20160	2026-09-24 10:34	57.76	OK
20161	2026-09-24 10:35	59.07	OK				

Signal: Winding_Temp_V (°C)
Operating Limits: [10.0 to 130.0] • Observed: Min 67.99, Max 85.22, Mean 76.54

All 20,161 Raw Readings

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1	2026-09-10 10:35	73.85	OK	2	2026-09-10 10:36	74.80	OK
3	2026-09-10 10:37	73.34	OK	4	2026-09-10 10:38	75.15	OK
5	2026-09-10 10:39	73.31	OK	6	2026-09-10 10:40	74.64	OK
7	2026-09-10 10:41	71.39	OK	8	2026-09-10 10:42	73.57	OK
9	2026-09-10 10:43	73.18	OK	10	2026-09-10 10:44	73.98	OK
11	2026-09-10 10:45	73.60	OK	12	2026-09-10 10:46	73.60	OK
13	2026-09-10 10:47	71.78	OK	14	2026-09-10 10:48	72.94	OK
15	2026-09-10 10:49	76.07	OK	16	2026-09-10 10:50	71.23	OK
17	2026-09-10 10:51	73.39	OK	18	2026-09-10 10:52	72.09	OK
19	2026-09-10 10:53	75.20	OK	20	2026-09-10 10:54	73.38	OK
21	2026-09-10 10:55	72.37	OK	22	2026-09-10 10:56	74.39	OK
23	2026-09-10 10:57	72.05	OK	24	2026-09-10 10:58	73.23	OK
25	2026-09-10 10:59	72.68	OK	26	2026-09-10 11:00	71.10	OK
27	2026-09-10 11:01	73.94	OK	28	2026-09-10 11:02	74.20	OK
29	2026-09-10 11:03	74.72	OK	30	2026-09-10 11:04	74.55	OK
31	2026-09-10 11:05	73.28	OK	32	2026-09-10 11:06	73.35	OK
33	2026-09-10 11:07	74.19	OK	34	2026-09-10 11:08	71.84	OK
35	2026-09-10 11:09	72.92	OK	36	2026-09-10 11:10	74.79	OK
37	2026-09-10 11:11	74.99	OK	38	2026-09-10 11:12	73.63	OK
39	2026-09-10 11:13	74.92	OK	40	2026-09-10 11:14	76.16	OK
41	2026-09-10 11:15	74.14	OK	42	2026-09-10 11:16	73.69	OK
43	2026-09-10 11:17	72.26	OK	44	2026-09-10 11:18	74.56	OK
45	2026-09-10 11:19	72.40	OK	46	2026-09-10 11:20	72.90	OK
47	2026-09-10 11:21	75.70	OK	48	2026-09-10 11:22	74.74	OK
49	2026-09-10 11:23	75.09	OK	50	2026-09-10 11:24	74.72	OK
51	2026-09-10 11:25	73.51	OK	52	2026-09-10 11:26	73.23	OK
53	2026-09-10 11:27	72.01	OK	54	2026-09-10 11:28	74.57	OK
55	2026-09-10 11:29	73.20	OK	56	2026-09-10 11:30	76.09	OK
57	2026-09-10 11:31	74.42	OK	58	2026-09-10 11:32	73.38	OK
59	2026-09-10 11:33	74.10	OK	60	2026-09-10 11:34	71.50	OK
61	2026-09-10 11:35	74.60	OK	62	2026-09-10 11:36	72.70	OK
63	2026-09-10 11:37	74.23	OK	64	2026-09-10 11:38	72.28	OK
65	2026-09-10 11:39	74.68	OK	66	2026-09-10 11:40	72.23	OK
67	2026-09-10 11:41	74.88	OK	68	2026-09-10 11:42	73.80	OK
69	2026-09-10 11:43	73.30	OK	70	2026-09-10 11:44	75.03	OK
71	2026-09-10 11:45	72.85	OK	72	2026-09-10 11:46	72.01	OK
73	2026-09-10 11:47	72.92	OK	74	2026-09-10 11:48	73.12	OK
75	2026-09-10 11:49	73.47	OK	76	2026-09-10 11:50	73.68	OK
77	2026-09-10 11:51	75.55	OK	78	2026-09-10 11:52	75.94	OK
79	2026-09-10 11:53	73.78	OK	80	2026-09-10 11:54	72.21	OK
81	2026-09-10 11:55	71.98	OK	82	2026-09-10 11:56	72.10	OK
83	2026-09-10 11:57	73.39	OK	84	2026-09-10 11:58	76.23	OK
85	2026-09-10 11:59	75.45	OK	86	2026-09-10 12:00	71.71	OK
87	2026-09-10 12:01	75.19	OK	88	2026-09-10 12:02	73.37	OK
89	2026-09-10 12:03	72.47	OK	90	2026-09-10 12:04	72.40	OK
91	2026-09-10 12:05	74.90	OK	92	2026-09-10 12:06	71.90	OK
93	2026-09-10 12:07	70.68	OK	94	2026-09-10 12:08	74.67	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
95	2026-09-10 12:09	72.81	OK	96	2026-09-10 12:10	73.74	OK
97	2026-09-10 12:11	72.06	OK	98	2026-09-10 12:12	72.24	OK
99	2026-09-10 12:13	75.36	OK	100	2026-09-10 12:14	74.49	OK
101	2026-09-10 12:15	71.47	OK	102	2026-09-10 12:16	72.72	OK
103	2026-09-10 12:17	72.91	OK	104	2026-09-10 12:18	70.62	OK
105	2026-09-10 12:19	71.67	OK	106	2026-09-10 12:20	73.55	OK
107	2026-09-10 12:21	72.68	OK	108	2026-09-10 12:22	73.06	OK
109	2026-09-10 12:23	70.82	OK	110	2026-09-10 12:24	74.25	OK
111	2026-09-10 12:25	73.31	OK	112	2026-09-10 12:26	74.97	OK
113	2026-09-10 12:27	74.67	OK	114	2026-09-10 12:28	73.54	OK
115	2026-09-10 12:29	71.68	OK	116	2026-09-10 12:30	71.48	OK
117	2026-09-10 12:31	71.96	OK	118	2026-09-10 12:32	69.56	OK
119	2026-09-10 12:33	72.93	OK	120	2026-09-10 12:34	74.36	OK
121	2026-09-10 12:35	72.68	OK	122	2026-09-10 12:36	71.53	OK
123	2026-09-10 12:37	70.00	OK	124	2026-09-10 12:38	70.14	OK
125	2026-09-10 12:39	70.27	OK	126	2026-09-10 12:40	72.41	OK
127	2026-09-10 12:41	75.37	OK	128	2026-09-10 12:42	73.62	OK
129	2026-09-10 12:43	71.48	OK	130	2026-09-10 12:44	72.96	OK
131	2026-09-10 12:45	71.17	OK	132	2026-09-10 12:46	71.71	OK
133	2026-09-10 12:47	71.41	OK	134	2026-09-10 12:48	70.19	OK
135	2026-09-10 12:49	69.37	OK	136	2026-09-10 12:50	70.75	OK
137	2026-09-10 12:51	73.02	OK	138	2026-09-10 12:52	71.56	OK
139	2026-09-10 12:53	74.23	OK	140	2026-09-10 12:54	72.04	OK
141	2026-09-10 12:55	73.10	OK	142	2026-09-10 12:56	72.05	OK
143	2026-09-10 12:57	71.99	OK	144	2026-09-10 12:58	71.81	OK
145	2026-09-10 12:59	70.87	OK	146	2026-09-10 13:00	70.61	OK
147	2026-09-10 13:01	72.43	OK	148	2026-09-10 13:02	72.72	OK
149	2026-09-10 13:03	70.14	OK	150	2026-09-10 13:04	69.93	OK
151	2026-09-10 13:05	71.93	OK	152	2026-09-10 13:06	72.36	OK
153	2026-09-10 13:07	73.51	OK	154	2026-09-10 13:08	70.93	OK
155	2026-09-10 13:09	73.20	OK	156	2026-09-10 13:10	70.71	OK
157	2026-09-10 13:11	69.78	OK	158	2026-09-10 13:12	71.35	OK
159	2026-09-10 13:13	73.20	OK	160	2026-09-10 13:14	71.09	OK
161	2026-09-10 13:15	71.60	OK	162	2026-09-10 13:16	72.13	OK
163	2026-09-10 13:17	73.82	OK	164	2026-09-10 13:18	73.39	OK
165	2026-09-10 13:19	73.15	OK	166	2026-09-10 13:20	74.71	OK
167	2026-09-10 13:21	71.83	OK	168	2026-09-10 13:22	73.48	OK
169	2026-09-10 13:23	70.21	OK	170	2026-09-10 13:24	72.56	OK
171	2026-09-10 13:25	74.76	OK	172	2026-09-10 13:26	72.95	OK
173	2026-09-10 13:27	70.55	OK	174	2026-09-10 13:28	73.02	OK
175	2026-09-10 13:29	69.83	OK	176	2026-09-10 13:30	73.05	OK
177	2026-09-10 13:31	70.89	OK	178	2026-09-10 13:32	72.18	OK
179	2026-09-10 13:33	71.77	OK	180	2026-09-10 13:34	70.62	OK
181	2026-09-10 13:35	72.75	OK	182	2026-09-10 13:36	70.32	OK
183	2026-09-10 13:37	70.63	OK	184	2026-09-10 13:38	72.71	OK
185	2026-09-10 13:39	71.29	OK	186	2026-09-10 13:40	73.55	OK
187	2026-09-10 13:41	72.23	OK	188	2026-09-10 13:42	72.47	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
189	2026-09-10 13:43	70.30	OK	190	2026-09-10 13:44	70.45	OK
191	2026-09-10 13:45	73.61	OK	192	2026-09-10 13:46	69.80	OK
193	2026-09-10 13:47	71.46	OK	194	2026-09-10 13:48	72.09	OK
195	2026-09-10 13:49	70.91	OK	196	2026-09-10 13:50	70.89	OK
197	2026-09-10 13:51	72.19	OK	198	2026-09-10 13:52	73.37	OK
199	2026-09-10 13:53	71.54	OK	200	2026-09-10 13:54	71.68	OK
201	2026-09-10 13:55	69.91	OK	202	2026-09-10 13:56	69.16	OK
203	2026-09-10 13:57	71.09	OK	204	2026-09-10 13:58	73.47	OK
205	2026-09-10 13:59	71.05	OK	206	2026-09-10 14:00	71.62	OK
207	2026-09-10 14:01	69.66	OK	208	2026-09-10 14:02	71.48	OK
209	2026-09-10 14:03	72.80	OK	210	2026-09-10 14:04	71.72	OK
211	2026-09-10 14:05	70.98	OK	212	2026-09-10 14:06	72.33	OK
213	2026-09-10 14:07	70.69	OK	214	2026-09-10 14:08	70.48	OK
215	2026-09-10 14:09	71.98	OK	216	2026-09-10 14:10	73.92	OK
217	2026-09-10 14:11	74.06	OK	218	2026-09-10 14:12	71.80	OK
219	2026-09-10 14:13	72.79	OK	220	2026-09-10 14:14	71.20	OK
221	2026-09-10 14:15	71.11	OK	222	2026-09-10 14:16	74.29	OK
223	2026-09-10 14:17	69.74	OK	224	2026-09-10 14:18	71.48	OK
225	2026-09-10 14:19	71.32	OK	226	2026-09-10 14:20	70.01	OK
227	2026-09-10 14:21	71.67	OK	228	2026-09-10 14:22	71.29	OK
229	2026-09-10 14:23	70.43	OK	230	2026-09-10 14:24	72.62	OK
231	2026-09-10 14:25	72.34	OK	232	2026-09-10 14:26	68.90	OK
233	2026-09-10 14:27	72.21	OK	234	2026-09-10 14:28	73.41	OK
235	2026-09-10 14:29	70.15	OK	236	2026-09-10 14:30	69.21	OK
237	2026-09-10 14:31	70.24	OK	238	2026-09-10 14:32	72.54	OK
239	2026-09-10 14:33	70.40	OK	240	2026-09-10 14:34	70.52	OK
241	2026-09-10 14:35	69.07	OK	242	2026-09-10 14:36	73.67	OK
243	2026-09-10 14:37	71.47	OK	244	2026-09-10 14:38	73.61	OK
245	2026-09-10 14:39	71.78	OK	246	2026-09-10 14:40	72.15	OK
247	2026-09-10 14:41	70.83	OK	248	2026-09-10 14:42	71.64	OK
249	2026-09-10 14:43	70.07	OK	250	2026-09-10 14:44	69.61	OK
251	2026-09-10 14:45	68.88	OK	252	2026-09-10 14:46	69.99	OK
253	2026-09-10 14:47	71.44	OK	254	2026-09-10 14:48	69.97	OK
255	2026-09-10 14:49	69.53	OK	256	2026-09-10 14:50	72.34	OK
257	2026-09-10 14:51	70.05	OK	258	2026-09-10 14:52	71.29	OK
259	2026-09-10 14:53	73.76	OK	260	2026-09-10 14:54	71.14	OK
261	2026-09-10 14:55	68.30	OK	262	2026-09-10 14:56	70.83	OK
263	2026-09-10 14:57	74.61	OK	264	2026-09-10 14:58	69.81	OK
265	2026-09-10 14:59	70.68	OK	266	2026-09-10 15:00	70.89	OK
267	2026-09-10 15:01	69.18	OK	268	2026-09-10 15:02	71.43	OK
269	2026-09-10 15:03	70.68	OK	270	2026-09-10 15:04	71.53	OK
271	2026-09-10 15:05	70.52	OK	272	2026-09-10 15:06	72.18	OK
273	2026-09-10 15:07	69.38	OK	274	2026-09-10 15:08	72.44	OK
275	2026-09-10 15:09	70.24	OK	276	2026-09-10 15:10	72.32	OK
277	2026-09-10 15:11	71.18	OK	278	2026-09-10 15:12	71.92	OK
279	2026-09-10 15:13	71.29	OK	280	2026-09-10 15:14	73.47	OK
281	2026-09-10 15:15	70.16	OK	282	2026-09-10 15:16	72.56	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
283	2026-09-10 15:17	69.99	OK	284	2026-09-10 15:18	71.07	OK
285	2026-09-10 15:19	70.70	OK	286	2026-09-10 15:20	70.12	OK
287	2026-09-10 15:21	73.22	OK	288	2026-09-10 15:22	69.51	OK
289	2026-09-10 15:23	72.85	OK	290	2026-09-10 15:24	70.46	OK
291	2026-09-10 15:25	71.58	OK	292	2026-09-10 15:26	70.85	OK
293	2026-09-10 15:27	72.02	OK	294	2026-09-10 15:28	72.32	OK
295	2026-09-10 15:29	71.43	OK	296	2026-09-10 15:30	71.92	OK
297	2026-09-10 15:31	71.92	OK	298	2026-09-10 15:32	70.78	OK
299	2026-09-10 15:33	71.62	OK	300	2026-09-10 15:34	70.65	OK
301	2026-09-10 15:35	69.41	OK	302	2026-09-10 15:36	72.44	OK
303	2026-09-10 15:37	70.30	OK	304	2026-09-10 15:38	72.19	OK
305	2026-09-10 15:39	73.05	OK	306	2026-09-10 15:40	73.15	OK
307	2026-09-10 15:41	71.65	OK	308	2026-09-10 15:42	72.32	OK
309	2026-09-10 15:43	72.59	OK	310	2026-09-10 15:44	72.48	OK
311	2026-09-10 15:45	70.95	OK	312	2026-09-10 15:46	70.60	OK
313	2026-09-10 15:47	69.72	OK	314	2026-09-10 15:48	73.10	OK
315	2026-09-10 15:49	74.23	OK	316	2026-09-10 15:50	71.90	OK
317	2026-09-10 15:51	70.94	OK	318	2026-09-10 15:52	69.77	OK
319	2026-09-10 15:53	71.35	OK	320	2026-09-10 15:54	71.30	OK
321	2026-09-10 15:55	71.76	OK	322	2026-09-10 15:56	72.01	OK
323	2026-09-10 15:57	71.74	OK	324	2026-09-10 15:58	70.18	OK
325	2026-09-10 15:59	71.07	OK	326	2026-09-10 16:00	72.01	OK
327	2026-09-10 16:01	68.74	OK	328	2026-09-10 16:02	71.97	OK
329	2026-09-10 16:03	71.21	OK	330	2026-09-10 16:04	72.41	OK
331	2026-09-10 16:05	70.97	OK	332	2026-09-10 16:06	74.82	OK
333	2026-09-10 16:07	71.76	OK	334	2026-09-10 16:08	69.44	OK
335	2026-09-10 16:09	71.98	OK	336	2026-09-10 16:10	71.81	OK
337	2026-09-10 16:11	74.37	OK	338	2026-09-10 16:12	74.69	OK
339	2026-09-10 16:13	72.44	OK	340	2026-09-10 16:14	72.75	OK
341	2026-09-10 16:15	69.07	OK	342	2026-09-10 16:16	71.37	OK
343	2026-09-10 16:17	72.85	OK	344	2026-09-10 16:18	71.08	OK
345	2026-09-10 16:19	71.17	OK	346	2026-09-10 16:20	73.17	OK
347	2026-09-10 16:21	71.04	OK	348	2026-09-10 16:22	71.03	OK
349	2026-09-10 16:23	71.83	OK	350	2026-09-10 16:24	73.32	OK
351	2026-09-10 16:25	74.51	OK	352	2026-09-10 16:26	73.61	OK
353	2026-09-10 16:27	71.63	OK	354	2026-09-10 16:28	72.29	OK
355	2026-09-10 16:29	75.14	OK	356	2026-09-10 16:30	72.86	OK
357	2026-09-10 16:31	73.86	OK	358	2026-09-10 16:32	70.45	OK
359	2026-09-10 16:33	72.80	OK	360	2026-09-10 16:34	72.19	OK
361	2026-09-10 16:35	72.90	OK	362	2026-09-10 16:36	71.52	OK
363	2026-09-10 16:37	71.46	OK	364	2026-09-10 16:38	71.52	OK
365	2026-09-10 16:39	70.66	OK	366	2026-09-10 16:40	71.21	OK
367	2026-09-10 16:41	70.46	OK	368	2026-09-10 16:42	73.05	OK
369	2026-09-10 16:43	71.90	OK	370	2026-09-10 16:44	72.96	OK
371	2026-09-10 16:45	72.27	OK	372	2026-09-10 16:46	72.35	OK
373	2026-09-10 16:47	71.15	OK	374	2026-09-10 16:48	71.50	OK
375	2026-09-10 16:49	73.34	OK	376	2026-09-10 16:50	72.39	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
377	2026-09-10 16:51	73.95	OK	378	2026-09-10 16:52	71.92	OK
379	2026-09-10 16:53	70.52	OK	380	2026-09-10 16:54	72.04	OK
381	2026-09-10 16:55	72.83	OK	382	2026-09-10 16:56	70.59	OK
383	2026-09-10 16:57	71.49	OK	384	2026-09-10 16:58	73.49	OK
385	2026-09-10 16:59	71.84	OK	386	2026-09-10 17:00	73.03	OK
387	2026-09-10 17:01	70.78	OK	388	2026-09-10 17:02	71.86	OK
389	2026-09-10 17:03	70.76	OK	390	2026-09-10 17:04	71.72	OK
391	2026-09-10 17:05	72.29	OK	392	2026-09-10 17:06	71.28	OK
393	2026-09-10 17:07	69.18	OK	394	2026-09-10 17:08	75.25	OK
395	2026-09-10 17:09	72.14	OK	396	2026-09-10 17:10	71.96	OK
397	2026-09-10 17:11	73.20	OK	398	2026-09-10 17:12	71.83	OK
399	2026-09-10 17:13	72.09	OK	400	2026-09-10 17:14	73.13	OK
401	2026-09-10 17:15	73.15	OK	402	2026-09-10 17:16	72.26	OK
403	2026-09-10 17:17	72.99	OK	404	2026-09-10 17:18	71.92	OK
405	2026-09-10 17:19	72.47	OK	406	2026-09-10 17:20	71.13	OK
407	2026-09-10 17:21	71.45	OK	408	2026-09-10 17:22	74.16	OK
409	2026-09-10 17:23	74.17	OK	410	2026-09-10 17:24	74.03	OK
411	2026-09-10 17:25	71.06	OK	412	2026-09-10 17:26	75.23	OK
413	2026-09-10 17:27	74.30	OK	414	2026-09-10 17:28	72.61	OK
415	2026-09-10 17:29	71.59	OK	416	2026-09-10 17:30	73.51	OK
417	2026-09-10 17:31	72.43	OK	418	2026-09-10 17:32	72.82	OK
419	2026-09-10 17:33	70.38	OK	420	2026-09-10 17:34	71.22	OK
421	2026-09-10 17:35	71.69	OK	422	2026-09-10 17:36	72.06	OK
423	2026-09-10 17:37	71.51	OK	424	2026-09-10 17:38	69.99	OK
425	2026-09-10 17:39	74.49	OK	426	2026-09-10 17:40	73.38	OK
427	2026-09-10 17:41	71.32	OK	428	2026-09-10 17:42	73.16	OK
429	2026-09-10 17:43	73.94	OK	430	2026-09-10 17:44	73.38	OK
431	2026-09-10 17:45	74.45	OK	432	2026-09-10 17:46	70.99	OK
433	2026-09-10 17:47	71.71	OK	434	2026-09-10 17:48	70.46	OK
435	2026-09-10 17:49	72.10	OK	436	2026-09-10 17:50	74.41	OK
437	2026-09-10 17:51	75.97	OK	438	2026-09-10 17:52	72.93	OK
439	2026-09-10 17:53	71.24	OK	440	2026-09-10 17:54	75.58	OK
441	2026-09-10 17:55	72.73	OK	442	2026-09-10 17:56	70.96	OK
443	2026-09-10 17:57	72.97	OK	444	2026-09-10 17:58	73.93	OK
445	2026-09-10 17:59	73.49	OK	446	2026-09-10 18:00	74.71	OK
447	2026-09-10 18:01	74.29	OK	448	2026-09-10 18:02	74.32	OK
449	2026-09-10 18:03	73.48	OK	450	2026-09-10 18:04	70.70	OK
451	2026-09-10 18:05	72.45	OK	452	2026-09-10 18:06	72.46	OK
453	2026-09-10 18:07	73.92	OK	454	2026-09-10 18:08	76.28	OK
455	2026-09-10 18:09	73.38	OK	456	2026-09-10 18:10	73.08	OK
457	2026-09-10 18:11	74.68	OK	458	2026-09-10 18:12	71.88	OK
459	2026-09-10 18:13	72.26	OK	460	2026-09-10 18:14	73.73	OK
461	2026-09-10 18:15	74.23	OK	462	2026-09-10 18:16	71.02	OK
463	2026-09-10 18:17	73.88	OK	464	2026-09-10 18:18	73.12	OK
465	2026-09-10 18:19	72.74	OK	466	2026-09-10 18:20	72.80	OK
467	2026-09-10 18:21	74.34	OK	468	2026-09-10 18:22	72.69	OK
469	2026-09-10 18:23	72.36	OK	470	2026-09-10 18:24	70.78	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
471	2026-09-10 18:25	72.05	OK	472	2026-09-10 18:26	72.69	OK
473	2026-09-10 18:27	72.94	OK	474	2026-09-10 18:28	74.43	OK
475	2026-09-10 18:29	72.01	OK	476	2026-09-10 18:30	71.46	OK
477	2026-09-10 18:31	73.77	OK	478	2026-09-10 18:32	74.75	OK
479	2026-09-10 18:33	73.92	OK	480	2026-09-10 18:34	71.99	OK
481	2026-09-10 18:35	73.54	OK	482	2026-09-10 18:36	73.14	OK
483	2026-09-10 18:37	72.84	OK	484	2026-09-10 18:38	73.96	OK
485	2026-09-10 18:39	75.02	OK	486	2026-09-10 18:40	73.89	OK
487	2026-09-10 18:41	73.18	OK	488	2026-09-10 18:42	71.95	OK
489	2026-09-10 18:43	75.72	OK	490	2026-09-10 18:44	74.93	OK
491	2026-09-10 18:45	72.33	OK	492	2026-09-10 18:46	73.60	OK
493	2026-09-10 18:47	73.48	OK	494	2026-09-10 18:48	72.07	OK
495	2026-09-10 18:49	71.92	OK	496	2026-09-10 18:50	74.13	OK
497	2026-09-10 18:51	70.92	OK	498	2026-09-10 18:52	76.37	OK
499	2026-09-10 18:53	73.73	OK	500	2026-09-10 18:54	75.52	OK
501	2026-09-10 18:55	74.36	OK	502	2026-09-10 18:56	73.22	OK
503	2026-09-10 18:57	75.87	OK	504	2026-09-10 18:58	73.14	OK
505	2026-09-10 18:59	73.45	OK	506	2026-09-10 19:00	73.46	OK
507	2026-09-10 19:01	72.35	OK	508	2026-09-10 19:02	73.67	OK
509	2026-09-10 19:03	73.40	OK	510	2026-09-10 19:04	73.87	OK
511	2026-09-10 19:05	72.81	OK	512	2026-09-10 19:06	74.15	OK
513	2026-09-10 19:07	72.27	OK	514	2026-09-10 19:08	72.30	OK
515	2026-09-10 19:09	74.02	OK	516	2026-09-10 19:10	71.91	OK
517	2026-09-10 19:11	74.97	OK	518	2026-09-10 19:12	71.85	OK
519	2026-09-10 19:13	74.05	OK	520	2026-09-10 19:14	73.60	OK
521	2026-09-10 19:15	74.68	OK	522	2026-09-10 19:16	73.02	OK
523	2026-09-10 19:17	76.54	OK	524	2026-09-10 19:18	73.48	OK
525	2026-09-10 19:19	73.37	OK	526	2026-09-10 19:20	72.92	OK
527	2026-09-10 19:21	75.23	OK	528	2026-09-10 19:22	73.73	OK
529	2026-09-10 19:23	75.92	OK	530	2026-09-10 19:24	72.28	OK
531	2026-09-10 19:25	75.36	OK	532	2026-09-10 19:26	73.36	OK
533	2026-09-10 19:27	76.11	OK	534	2026-09-10 19:28	73.36	OK
535	2026-09-10 19:29	76.06	OK	536	2026-09-10 19:30	72.66	OK
537	2026-09-10 19:31	76.20	OK	538	2026-09-10 19:32	75.83	OK
539	2026-09-10 19:33	74.11	OK	540	2026-09-10 19:34	75.12	OK
541	2026-09-10 19:35	75.19	OK	542	2026-09-10 19:36	75.70	OK
543	2026-09-10 19:37	74.17	OK	544	2026-09-10 19:38	76.38	OK
545	2026-09-10 19:39	73.57	OK	546	2026-09-10 19:40	74.78	OK
547	2026-09-10 19:41	72.54	OK	548	2026-09-10 19:42	76.23	OK
549	2026-09-10 19:43	76.00	OK	550	2026-09-10 19:44	75.81	OK
551	2026-09-10 19:45	78.08	OK	552	2026-09-10 19:46	75.16	OK
553	2026-09-10 19:47	74.48	OK	554	2026-09-10 19:48	73.82	OK
555	2026-09-10 19:49	72.85	OK	556	2026-09-10 19:50	77.34	OK
557	2026-09-10 19:51	74.90	OK	558	2026-09-10 19:52	75.95	OK
559	2026-09-10 19:53	75.61	OK	560	2026-09-10 19:54	76.50	OK
561	2026-09-10 19:55	76.08	OK	562	2026-09-10 19:56	74.30	OK
563	2026-09-10 19:57	74.20	OK	564	2026-09-10 19:58	73.39	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
565	2026-09-10 19:59	74.73	OK	566	2026-09-10 20:00	75.10	OK
567	2026-09-10 20:01	75.32	OK	568	2026-09-10 20:02	76.60	OK
569	2026-09-10 20:03	77.18	OK	570	2026-09-10 20:04	78.27	OK
571	2026-09-10 20:05	73.84	OK	572	2026-09-10 20:06	77.49	OK
573	2026-09-10 20:07	77.27	OK	574	2026-09-10 20:08	76.52	OK
575	2026-09-10 20:09	74.90	OK	576	2026-09-10 20:10	78.16	OK
577	2026-09-10 20:11	75.20	OK	578	2026-09-10 20:12	75.66	OK
579	2026-09-10 20:13	76.39	OK	580	2026-09-10 20:14	76.01	OK
581	2026-09-10 20:15	76.33	OK	582	2026-09-10 20:16	76.93	OK
583	2026-09-10 20:17	76.75	OK	584	2026-09-10 20:18	73.64	OK
585	2026-09-10 20:19	75.09	OK	586	2026-09-10 20:20	76.26	OK
587	2026-09-10 20:21	76.80	OK	588	2026-09-10 20:22	74.85	OK
589	2026-09-10 20:23	74.31	OK	590	2026-09-10 20:24	78.29	OK
591	2026-09-10 20:25	75.34	OK	592	2026-09-10 20:26	76.76	OK
593	2026-09-10 20:27	76.03	OK	594	2026-09-10 20:28	75.42	OK
595	2026-09-10 20:29	75.17	OK	596	2026-09-10 20:30	76.44	OK
597	2026-09-10 20:31	77.07	OK	598	2026-09-10 20:32	75.97	OK
599	2026-09-10 20:33	76.38	OK	600	2026-09-10 20:34	76.49	OK
601	2026-09-10 20:35	76.86	OK	602	2026-09-10 20:36	78.17	OK
603	2026-09-10 20:37	76.15	OK	604	2026-09-10 20:38	75.95	OK
605	2026-09-10 20:39	77.41	OK	606	2026-09-10 20:40	75.53	OK
607	2026-09-10 20:41	73.75	OK	608	2026-09-10 20:42	76.61	OK
609	2026-09-10 20:43	75.85	OK	610	2026-09-10 20:44	77.77	OK
611	2026-09-10 20:45	76.36	OK	612	2026-09-10 20:46	77.12	OK
613	2026-09-10 20:47	78.63	OK	614	2026-09-10 20:48	76.84	OK
615	2026-09-10 20:49	79.09	OK	616	2026-09-10 20:50	78.02	OK
617	2026-09-10 20:51	76.57	OK	618	2026-09-10 20:52	77.72	OK
619	2026-09-10 20:53	76.17	OK	620	2026-09-10 20:54	75.90	OK
621	2026-09-10 20:55	78.13	OK	622	2026-09-10 20:56	77.55	OK
623	2026-09-10 20:57	74.86	OK	624	2026-09-10 20:58	77.40	OK
625	2026-09-10 20:59	79.34	OK	626	2026-09-10 21:00	79.17	OK
627	2026-09-10 21:01	76.34	OK	628	2026-09-10 21:02	78.16	OK
629	2026-09-10 21:03	77.66	OK	630	2026-09-10 21:04	78.56	OK
631	2026-09-10 21:05	75.78	OK	632	2026-09-10 21:06	76.55	OK
633	2026-09-10 21:07	74.73	OK	634	2026-09-10 21:08	78.40	OK
635	2026-09-10 21:09	75.53	OK	636	2026-09-10 21:10	76.70	OK
637	2026-09-10 21:11	77.59	OK	638	2026-09-10 21:12	76.34	OK
639	2026-09-10 21:13	76.54	OK	640	2026-09-10 21:14	77.21	OK
641	2026-09-10 21:15	76.09	OK	642	2026-09-10 21:16	78.28	OK
643	2026-09-10 21:17	77.38	OK	644	2026-09-10 21:18	76.45	OK
645	2026-09-10 21:19	74.37	OK	646	2026-09-10 21:20	78.25	OK
647	2026-09-10 21:21	76.88	OK	648	2026-09-10 21:22	75.57	OK
649	2026-09-10 21:23	77.50	OK	650	2026-09-10 21:24	76.77	OK
651	2026-09-10 21:25	76.88	OK	652	2026-09-10 21:26	75.96	OK
653	2026-09-10 21:27	78.58	OK	654	2026-09-10 21:28	76.65	OK
655	2026-09-10 21:29	75.68	OK	656	2026-09-10 21:30	76.24	OK
657	2026-09-10 21:31	77.86	OK	658	2026-09-10 21:32	80.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
659	2026-09-10 21:33	76.29	OK	660	2026-09-10 21:34	75.57	OK
661	2026-09-10 21:35	79.22	OK	662	2026-09-10 21:36	76.58	OK
663	2026-09-10 21:37	76.54	OK	664	2026-09-10 21:38	74.78	OK
665	2026-09-10 21:39	78.23	OK	666	2026-09-10 21:40	78.91	OK
667	2026-09-10 21:41	78.28	OK	668	2026-09-10 21:42	80.16	OK
669	2026-09-10 21:43	77.56	OK	670	2026-09-10 21:44	78.17	OK
671	2026-09-10 21:45	77.24	OK	672	2026-09-10 21:46	80.01	OK
673	2026-09-10 21:47	77.20	OK	674	2026-09-10 21:48	76.74	OK
675	2026-09-10 21:49	79.42	OK	676	2026-09-10 21:50	76.80	OK
677	2026-09-10 21:51	78.53	OK	678	2026-09-10 21:52	78.04	OK
679	2026-09-10 21:53	79.02	OK	680	2026-09-10 21:54	78.29	OK
681	2026-09-10 21:55	77.97	OK	682	2026-09-10 21:56	80.49	OK
683	2026-09-10 21:57	77.32	OK	684	2026-09-10 21:58	76.66	OK
685	2026-09-10 21:59	76.84	OK	686	2026-09-10 22:00	78.22	OK
687	2026-09-10 22:01	79.30	OK	688	2026-09-10 22:02	79.89	OK
689	2026-09-10 22:03	77.51	OK	690	2026-09-10 22:04	79.81	OK
691	2026-09-10 22:05	76.58	OK	692	2026-09-10 22:06	76.96	OK
693	2026-09-10 22:07	80.43	OK	694	2026-09-10 22:08	79.23	OK
695	2026-09-10 22:09	76.40	OK	696	2026-09-10 22:10	79.49	OK
697	2026-09-10 22:11	76.29	OK	698	2026-09-10 22:12	77.72	OK
699	2026-09-10 22:13	76.67	OK	700	2026-09-10 22:14	78.56	OK
701	2026-09-10 22:15	77.88	OK	702	2026-09-10 22:16	77.47	OK
703	2026-09-10 22:17	80.36	OK	704	2026-09-10 22:18	78.04	OK
705	2026-09-10 22:19	78.19	OK	706	2026-09-10 22:20	80.65	OK
707	2026-09-10 22:21	77.28	OK	708	2026-09-10 22:22	78.49	OK
709	2026-09-10 22:23	78.48	OK	710	2026-09-10 22:24	78.02	OK
711	2026-09-10 22:25	80.16	OK	712	2026-09-10 22:26	79.64	OK
713	2026-09-10 22:27	80.85	OK	714	2026-09-10 22:28	79.31	OK
715	2026-09-10 22:29	77.31	OK	716	2026-09-10 22:30	79.81	OK
717	2026-09-10 22:31	79.17	OK	718	2026-09-10 22:32	80.55	OK
719	2026-09-10 22:33	79.70	OK	720	2026-09-10 22:34	80.42	OK
721	2026-09-10 22:35	78.59	OK	722	2026-09-10 22:36	80.20	OK
723	2026-09-10 22:37	78.44	OK	724	2026-09-10 22:38	81.16	OK
725	2026-09-10 22:39	81.32	OK	726	2026-09-10 22:40	79.33	OK
727	2026-09-10 22:41	78.02	OK	728	2026-09-10 22:42	77.54	OK
729	2026-09-10 22:43	79.72	OK	730	2026-09-10 22:44	79.18	OK
731	2026-09-10 22:45	79.30	OK	732	2026-09-10 22:46	80.11	OK
733	2026-09-10 22:47	77.76	OK	734	2026-09-10 22:48	78.76	OK
735	2026-09-10 22:49	81.62	OK	736	2026-09-10 22:50	80.88	OK
737	2026-09-10 22:51	78.44	OK	738	2026-09-10 22:52	76.88	OK
739	2026-09-10 22:53	79.68	OK	740	2026-09-10 22:54	77.92	OK
741	2026-09-10 22:55	79.74	OK	742	2026-09-10 22:56	77.05	OK
743	2026-09-10 22:57	80.38	OK	744	2026-09-10 22:58	80.33	OK
745	2026-09-10 22:59	79.04	OK	746	2026-09-10 23:00	76.72	OK
747	2026-09-10 23:01	80.49	OK	748	2026-09-10 23:02	80.49	OK
749	2026-09-10 23:03	79.73	OK	750	2026-09-10 23:04	79.11	OK
751	2026-09-10 23:05	79.09	OK	752	2026-09-10 23:06	80.85	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
753	2026-09-10 23:07	77.67	OK	754	2026-09-10 23:08	80.30	OK
755	2026-09-10 23:09	78.31	OK	756	2026-09-10 23:10	79.17	OK
757	2026-09-10 23:11	79.88	OK	758	2026-09-10 23:12	80.50	OK
759	2026-09-10 23:13	79.06	OK	760	2026-09-10 23:14	77.84	OK
761	2026-09-10 23:15	78.71	OK	762	2026-09-10 23:16	80.47	OK
763	2026-09-10 23:17	78.93	OK	764	2026-09-10 23:18	80.22	OK
765	2026-09-10 23:19	80.66	OK	766	2026-09-10 23:20	79.66	OK
767	2026-09-10 23:21	80.77	OK	768	2026-09-10 23:22	79.98	OK
769	2026-09-10 23:23	80.01	OK	770	2026-09-10 23:24	79.76	OK
771	2026-09-10 23:25	80.35	OK	772	2026-09-10 23:26	78.61	OK
773	2026-09-10 23:27	78.86	OK	774	2026-09-10 23:28	78.87	OK
775	2026-09-10 23:29	79.83	OK	776	2026-09-10 23:30	80.17	OK
777	2026-09-10 23:31	79.73	OK	778	2026-09-10 23:32	81.79	OK
779	2026-09-10 23:33	78.51	OK	780	2026-09-10 23:34	80.60	OK
781	2026-09-10 23:35	78.94	OK	782	2026-09-10 23:36	79.09	OK
783	2026-09-10 23:37	81.09	OK	784	2026-09-10 23:38	82.53	OK
785	2026-09-10 23:39	79.76	OK	786	2026-09-10 23:40	81.63	OK
787	2026-09-10 23:41	81.20	OK	788	2026-09-10 23:42	82.94	OK
789	2026-09-10 23:43	80.05	OK	790	2026-09-10 23:44	77.87	OK
791	2026-09-10 23:45	77.58	OK	792	2026-09-10 23:46	78.67	OK
793	2026-09-10 23:47	81.62	OK	794	2026-09-10 23:48	81.73	OK
795	2026-09-10 23:49	79.73	OK	796	2026-09-10 23:50	81.86	OK
797	2026-09-10 23:51	79.70	OK	798	2026-09-10 23:52	80.40	OK
799	2026-09-10 23:53	81.03	OK	800	2026-09-10 23:54	82.32	OK
801	2026-09-10 23:55	78.95	OK	802	2026-09-10 23:56	80.88	OK
803	2026-09-10 23:57	83.14	OK	804	2026-09-10 23:58	80.32	OK
805	2026-09-10 23:59	77.99	OK	806	2026-09-11 00:00	81.53	OK
807	2026-09-11 00:01	82.63	OK	808	2026-09-11 00:02	80.37	OK
809	2026-09-11 00:03	82.37	OK	810	2026-09-11 00:04	79.79	OK
811	2026-09-11 00:05	77.81	OK	812	2026-09-11 00:06	80.75	OK
813	2026-09-11 00:07	79.53	OK	814	2026-09-11 00:08	82.38	OK
815	2026-09-11 00:09	80.24	OK	816	2026-09-11 00:10	81.10	OK
817	2026-09-11 00:11	81.78	OK	818	2026-09-11 00:12	79.09	OK
819	2026-09-11 00:13	79.20	OK	820	2026-09-11 00:14	80.13	OK
821	2026-09-11 00:15	79.49	OK	822	2026-09-11 00:16	81.29	OK
823	2026-09-11 00:17	80.77	OK	824	2026-09-11 00:18	80.83	OK
825	2026-09-11 00:19	81.77	OK	826	2026-09-11 00:20	80.07	OK
827	2026-09-11 00:21	81.83	OK	828	2026-09-11 00:22	82.43	OK
829	2026-09-11 00:23	80.31	OK	830	2026-09-11 00:24	78.63	OK
831	2026-09-11 00:25	80.31	OK	832	2026-09-11 00:26	80.55	OK
833	2026-09-11 00:27	82.52	OK	834	2026-09-11 00:28	81.80	OK
835	2026-09-11 00:29	79.93	OK	836	2026-09-11 00:30	79.54	OK
837	2026-09-11 00:31	81.45	OK	838	2026-09-11 00:32	79.12	OK
839	2026-09-11 00:33	81.13	OK	840	2026-09-11 00:34	79.76	OK
841	2026-09-11 00:35	80.36	OK	842	2026-09-11 00:36	79.83	OK
843	2026-09-11 00:37	82.20	OK	844	2026-09-11 00:38	78.79	OK
845	2026-09-11 00:39	80.98	OK	846	2026-09-11 00:40	79.67	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
847	2026-09-11 00:41	84.02	OK	848	2026-09-11 00:42	81.48	OK
849	2026-09-11 00:43	81.04	OK	850	2026-09-11 00:44	81.86	OK
851	2026-09-11 00:45	83.02	OK	852	2026-09-11 00:46	78.78	OK
853	2026-09-11 00:47	82.39	OK	854	2026-09-11 00:48	80.96	OK
855	2026-09-11 00:49	77.78	OK	856	2026-09-11 00:50	82.19	OK
857	2026-09-11 00:51	81.22	OK	858	2026-09-11 00:52	81.71	OK
859	2026-09-11 00:53	80.19	OK	860	2026-09-11 00:54	80.19	OK
861	2026-09-11 00:55	79.68	OK	862	2026-09-11 00:56	81.14	OK
863	2026-09-11 00:57	82.71	OK	864	2026-09-11 00:58	82.05	OK
865	2026-09-11 00:59	82.71	OK	866	2026-09-11 01:00	81.65	OK
867	2026-09-11 01:01	80.62	OK	868	2026-09-11 01:02	78.96	OK
869	2026-09-11 01:03	79.02	OK	870	2026-09-11 01:04	79.49	OK
871	2026-09-11 01:05	80.31	OK	872	2026-09-11 01:06	80.58	OK
873	2026-09-11 01:07	81.58	OK	874	2026-09-11 01:08	79.68	OK
875	2026-09-11 01:09	80.78	OK	876	2026-09-11 01:10	80.93	OK
877	2026-09-11 01:11	81.79	OK	878	2026-09-11 01:12	84.02	OK
879	2026-09-11 01:13	81.41	OK	880	2026-09-11 01:14	80.48	OK
881	2026-09-11 01:15	79.66	OK	882	2026-09-11 01:16	80.22	OK
883	2026-09-11 01:17	82.18	OK	884	2026-09-11 01:18	82.28	OK
885	2026-09-11 01:19	79.71	OK	886	2026-09-11 01:20	80.87	OK
887	2026-09-11 01:21	79.80	OK	888	2026-09-11 01:22	82.75	OK
889	2026-09-11 01:23	80.60	OK	890	2026-09-11 01:24	79.97	OK
891	2026-09-11 01:25	83.26	OK	892	2026-09-11 01:26	81.57	OK
893	2026-09-11 01:27	81.81	OK	894	2026-09-11 01:28	79.64	OK
895	2026-09-11 01:29	81.97	OK	896	2026-09-11 01:30	79.76	OK
897	2026-09-11 01:31	82.65	OK	898	2026-09-11 01:32	81.29	OK
899	2026-09-11 01:33	81.67	OK	900	2026-09-11 01:34	82.22	OK
901	2026-09-11 01:35	82.41	OK	902	2026-09-11 01:36	83.00	OK
903	2026-09-11 01:37	82.81	OK	904	2026-09-11 01:38	79.35	OK
905	2026-09-11 01:39	82.81	OK	906	2026-09-11 01:40	83.78	OK
907	2026-09-11 01:41	81.85	OK	908	2026-09-11 01:42	81.63	OK
909	2026-09-11 01:43	81.64	OK	910	2026-09-11 01:44	81.01	OK
911	2026-09-11 01:45	81.46	OK	912	2026-09-11 01:46	81.19	OK
913	2026-09-11 01:47	81.99	OK	914	2026-09-11 01:48	82.05	OK
915	2026-09-11 01:49	80.77	OK	916	2026-09-11 01:50	81.23	OK
917	2026-09-11 01:51	80.42	OK	918	2026-09-11 01:52	80.66	OK
919	2026-09-11 01:53	84.30	OK	920	2026-09-11 01:54	83.79	OK
921	2026-09-11 01:55	82.84	OK	922	2026-09-11 01:56	81.07	OK
923	2026-09-11 01:57	81.53	OK	924	2026-09-11 01:58	82.31	OK
925	2026-09-11 01:59	80.97	OK	926	2026-09-11 02:00	82.84	OK
927	2026-09-11 02:01	81.84	OK	928	2026-09-11 02:02	81.15	OK
929	2026-09-11 02:03	81.43	OK	930	2026-09-11 02:04	80.95	OK
931	2026-09-11 02:05	79.68	OK	932	2026-09-11 02:06	82.59	OK
933	2026-09-11 02:07	79.59	OK	934	2026-09-11 02:08	80.31	OK
935	2026-09-11 02:09	81.37	OK	936	2026-09-11 02:10	82.94	OK
937	2026-09-11 02:11	83.67	OK	938	2026-09-11 02:12	83.41	OK
939	2026-09-11 02:13	80.14	OK	940	2026-09-11 02:14	84.38	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
941	2026-09-11 02:15	83.36	OK	942	2026-09-11 02:16	83.54	OK
943	2026-09-11 02:17	83.84	OK	944	2026-09-11 02:18	81.15	OK
945	2026-09-11 02:19	81.04	OK	946	2026-09-11 02:20	82.88	OK
947	2026-09-11 02:21	83.00	OK	948	2026-09-11 02:22	82.75	OK
949	2026-09-11 02:23	82.76	OK	950	2026-09-11 02:24	82.43	OK
951	2026-09-11 02:25	84.42	OK	952	2026-09-11 02:26	82.22	OK
953	2026-09-11 02:27	82.79	OK	954	2026-09-11 02:28	80.93	OK
955	2026-09-11 02:29	82.44	OK	956	2026-09-11 02:30	80.28	OK
957	2026-09-11 02:31	81.92	OK	958	2026-09-11 02:32	82.44	OK
959	2026-09-11 02:33	82.45	OK	960	2026-09-11 02:34	79.88	OK
961	2026-09-11 02:35	82.31	OK	962	2026-09-11 02:36	83.44	OK
963	2026-09-11 02:37	83.08	OK	964	2026-09-11 02:38	81.44	OK
965	2026-09-11 02:39	81.07	OK	966	2026-09-11 02:40	84.36	OK
967	2026-09-11 02:41	81.98	OK	968	2026-09-11 02:42	82.75	OK
969	2026-09-11 02:43	82.26	OK	970	2026-09-11 02:44	82.73	OK
971	2026-09-11 02:45	82.69	OK	972	2026-09-11 02:46	82.79	OK
973	2026-09-11 02:47	80.80	OK	974	2026-09-11 02:48	80.65	OK
975	2026-09-11 02:49	79.76	OK	976	2026-09-11 02:50	82.70	OK
977	2026-09-11 02:51	80.05	OK	978	2026-09-11 02:52	79.49	OK
979	2026-09-11 02:53	84.24	OK	980	2026-09-11 02:54	80.03	OK
981	2026-09-11 02:55	82.89	OK	982	2026-09-11 02:56	81.83	OK
983	2026-09-11 02:57	81.43	OK	984	2026-09-11 02:58	83.23	OK
985	2026-09-11 02:59	83.17	OK	986	2026-09-11 03:00	80.67	OK
987	2026-09-11 03:01	81.22	OK	988	2026-09-11 03:02	81.46	OK
989	2026-09-11 03:03	82.32	OK	990	2026-09-11 03:04	81.25	OK
991	2026-09-11 03:05	83.40	OK	992	2026-09-11 03:06	80.62	OK
993	2026-09-11 03:07	79.44	OK	994	2026-09-11 03:08	81.40	OK
995	2026-09-11 03:09	84.23	OK	996	2026-09-11 03:10	81.78	OK
997	2026-09-11 03:11	79.81	OK	998	2026-09-11 03:12	81.88	OK
999	2026-09-11 03:13	81.16	OK	1000	2026-09-11 03:14	81.47	OK
1001	2026-09-11 03:15	82.67	OK	1002	2026-09-11 03:16	81.34	OK
1003	2026-09-11 03:17	79.95	OK	1004	2026-09-11 03:18	82.72	OK
1005	2026-09-11 03:19	83.44	OK	1006	2026-09-11 03:20	82.11	OK
1007	2026-09-11 03:21	83.43	OK	1008	2026-09-11 03:22	82.12	OK
1009	2026-09-11 03:23	82.26	OK	1010	2026-09-11 03:24	82.10	OK
1011	2026-09-11 03:25	82.20	OK	1012	2026-09-11 03:26	81.50	OK
1013	2026-09-11 03:27	84.78	OK	1014	2026-09-11 03:28	85.08	OK
1015	2026-09-11 03:29	82.34	OK	1016	2026-09-11 03:30	82.80	OK
1017	2026-09-11 03:31	82.94	OK	1018	2026-09-11 03:32	80.43	OK
1019	2026-09-11 03:33	83.33	OK	1020	2026-09-11 03:34	82.24	OK
1021	2026-09-11 03:35	79.54	OK	1022	2026-09-11 03:36	82.52	OK
1023	2026-09-11 03:37	82.43	OK	1024	2026-09-11 03:38	80.89	OK
1025	2026-09-11 03:39	81.53	OK	1026	2026-09-11 03:40	81.10	OK
1027	2026-09-11 03:41	82.45	OK	1028	2026-09-11 03:42	81.96	OK
1029	2026-09-11 03:43	80.81	OK	1030	2026-09-11 03:44	83.25	OK
1031	2026-09-11 03:45	81.78	OK	1032	2026-09-11 03:46	81.57	OK
1033	2026-09-11 03:47	79.83	OK	1034	2026-09-11 03:48	80.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1035	2026-09-11 03:49	80.89	OK	1036	2026-09-11 03:50	83.44	OK
1037	2026-09-11 03:51	81.43	OK	1038	2026-09-11 03:52	80.63	OK
1039	2026-09-11 03:53	83.59	OK	1040	2026-09-11 03:54	80.68	OK
1041	2026-09-11 03:55	83.63	OK	1042	2026-09-11 03:56	81.05	OK
1043	2026-09-11 03:57	83.65	OK	1044	2026-09-11 03:58	81.27	OK
1045	2026-09-11 03:59	81.95	OK	1046	2026-09-11 04:00	81.79	OK
1047	2026-09-11 04:01	80.01	OK	1048	2026-09-11 04:02	81.76	OK
1049	2026-09-11 04:03	82.44	OK	1050	2026-09-11 04:04	81.83	OK
1051	2026-09-11 04:05	81.06	OK	1052	2026-09-11 04:06	82.61	OK
1053	2026-09-11 04:07	78.65	OK	1054	2026-09-11 04:08	80.39	OK
1055	2026-09-11 04:09	81.72	OK	1056	2026-09-11 04:10	81.48	OK
1057	2026-09-11 04:11	80.89	OK	1058	2026-09-11 04:12	82.76	OK
1059	2026-09-11 04:13	81.57	OK	1060	2026-09-11 04:14	80.25	OK
1061	2026-09-11 04:15	83.35	OK	1062	2026-09-11 04:16	83.14	OK
1063	2026-09-11 04:17	79.69	OK	1064	2026-09-11 04:18	82.62	OK
1065	2026-09-11 04:19	83.24	OK	1066	2026-09-11 04:20	82.80	OK
1067	2026-09-11 04:21	82.12	OK	1068	2026-09-11 04:22	80.71	OK
1069	2026-09-11 04:23	80.76	OK	1070	2026-09-11 04:24	80.62	OK
1071	2026-09-11 04:25	79.41	OK	1072	2026-09-11 04:26	81.67	OK
1073	2026-09-11 04:27	81.47	OK	1074	2026-09-11 04:28	80.72	OK
1075	2026-09-11 04:29	80.45	OK	1076	2026-09-11 04:30	81.04	OK
1077	2026-09-11 04:31	83.05	OK	1078	2026-09-11 04:32	82.85	OK
1079	2026-09-11 04:33	80.42	OK	1080	2026-09-11 04:34	81.50	OK
1081	2026-09-11 04:35	79.83	OK	1082	2026-09-11 04:36	80.43	OK
1083	2026-09-11 04:37	82.08	OK	1084	2026-09-11 04:38	79.44	OK
1085	2026-09-11 04:39	83.62	OK	1086	2026-09-11 04:40	80.75	OK
1087	2026-09-11 04:41	82.41	OK	1088	2026-09-11 04:42	81.21	OK
1089	2026-09-11 04:43	81.59	OK	1090	2026-09-11 04:44	81.31	OK
1091	2026-09-11 04:45	83.05	OK	1092	2026-09-11 04:46	82.65	OK
1093	2026-09-11 04:47	80.54	OK	1094	2026-09-11 04:48	80.46	OK
1095	2026-09-11 04:49	79.92	OK	1096	2026-09-11 04:50	78.81	OK
1097	2026-09-11 04:51	80.45	OK	1098	2026-09-11 04:52	80.86	OK
1099	2026-09-11 04:53	82.62	OK	1100	2026-09-11 04:54	82.18	OK
1101	2026-09-11 04:55	80.23	OK	1102	2026-09-11 04:56	80.45	OK
1103	2026-09-11 04:57	79.84	OK	1104	2026-09-11 04:58	82.84	OK
1105	2026-09-11 04:59	81.14	OK	1106	2026-09-11 05:00	83.01	OK
1107	2026-09-11 05:01	81.97	OK	1108	2026-09-11 05:02	80.36	OK
1109	2026-09-11 05:03	79.91	OK	1110	2026-09-11 05:04	80.39	OK
1111	2026-09-11 05:05	80.92	OK	1112	2026-09-11 05:06	82.00	OK
1113	2026-09-11 05:07	79.76	OK	1114	2026-09-11 05:08	82.78	OK
1115	2026-09-11 05:09	78.72	OK	1116	2026-09-11 05:10	81.97	OK
1117	2026-09-11 05:11	79.09	OK	1118	2026-09-11 05:12	81.45	OK
1119	2026-09-11 05:13	79.67	OK	1120	2026-09-11 05:14	79.41	OK
1121	2026-09-11 05:15	80.63	OK	1122	2026-09-11 05:16	80.35	OK
1123	2026-09-11 05:17	80.83	OK	1124	2026-09-11 05:18	80.28	OK
1125	2026-09-11 05:19	80.70	OK	1126	2026-09-11 05:20	78.68	OK
1127	2026-09-11 05:21	81.21	OK	1128	2026-09-11 05:22	79.81	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1129	2026-09-11 05:23	80.04	OK	1130	2026-09-11 05:24	80.74	OK
1131	2026-09-11 05:25	81.45	OK	1132	2026-09-11 05:26	78.71	OK
1133	2026-09-11 05:27	80.55	OK	1134	2026-09-11 05:28	82.63	OK
1135	2026-09-11 05:29	82.01	OK	1136	2026-09-11 05:30	80.36	OK
1137	2026-09-11 05:31	77.08	OK	1138	2026-09-11 05:32	78.22	OK
1139	2026-09-11 05:33	79.45	OK	1140	2026-09-11 05:34	83.18	OK
1141	2026-09-11 05:35	80.63	OK	1142	2026-09-11 05:36	79.47	OK
1143	2026-09-11 05:37	81.35	OK	1144	2026-09-11 05:38	79.71	OK
1145	2026-09-11 05:39	81.75	OK	1146	2026-09-11 05:40	82.95	OK
1147	2026-09-11 05:41	79.12	OK	1148	2026-09-11 05:42	80.69	OK
1149	2026-09-11 05:43	80.34	OK	1150	2026-09-11 05:44	79.78	OK
1151	2026-09-11 05:45	80.32	OK	1152	2026-09-11 05:46	81.61	OK
1153	2026-09-11 05:47	80.44	OK	1154	2026-09-11 05:48	81.30	OK
1155	2026-09-11 05:49	81.79	OK	1156	2026-09-11 05:50	80.86	OK
1157	2026-09-11 05:51	82.35	OK	1158	2026-09-11 05:52	79.64	OK
1159	2026-09-11 05:53	80.27	OK	1160	2026-09-11 05:54	79.71	OK
1161	2026-09-11 05:55	81.29	OK	1162	2026-09-11 05:56	79.58	OK
1163	2026-09-11 05:57	80.96	OK	1164	2026-09-11 05:58	82.21	OK
1165	2026-09-11 05:59	78.63	OK	1166	2026-09-11 06:00	80.29	OK
1167	2026-09-11 06:01	80.50	OK	1168	2026-09-11 06:02	79.49	OK
1169	2026-09-11 06:03	77.21	OK	1170	2026-09-11 06:04	80.07	OK
1171	2026-09-11 06:05	79.65	OK	1172	2026-09-11 06:06	79.41	OK
1173	2026-09-11 06:07	80.61	OK	1174	2026-09-11 06:08	80.30	OK
1175	2026-09-11 06:09	77.98	OK	1176	2026-09-11 06:10	79.12	OK
1177	2026-09-11 06:11	79.19	OK	1178	2026-09-11 06:12	80.98	OK
1179	2026-09-11 06:13	80.30	OK	1180	2026-09-11 06:14	79.87	OK
1181	2026-09-11 06:15	81.55	OK	1182	2026-09-11 06:16	79.25	OK
1183	2026-09-11 06:17	77.84	OK	1184	2026-09-11 06:18	81.78	OK
1185	2026-09-11 06:19	81.30	OK	1186	2026-09-11 06:20	80.19	OK
1187	2026-09-11 06:21	80.44	OK	1188	2026-09-11 06:22	77.94	OK
1189	2026-09-11 06:23	79.67	OK	1190	2026-09-11 06:24	81.29	OK
1191	2026-09-11 06:25	79.06	OK	1192	2026-09-11 06:26	76.94	OK
1193	2026-09-11 06:27	81.55	OK	1194	2026-09-11 06:28	80.06	OK
1195	2026-09-11 06:29	78.88	OK	1196	2026-09-11 06:30	80.11	OK
1197	2026-09-11 06:31	77.96	OK	1198	2026-09-11 06:32	78.29	OK
1199	2026-09-11 06:33	78.27	OK	1200	2026-09-11 06:34	80.73	OK
1201	2026-09-11 06:35	78.73	OK	1202	2026-09-11 06:36	79.96	OK
1203	2026-09-11 06:37	77.89	OK	1204	2026-09-11 06:38	78.04	OK
1205	2026-09-11 06:39	82.09	OK	1206	2026-09-11 06:40	79.19	OK
1207	2026-09-11 06:41	80.07	OK	1208	2026-09-11 06:42	77.49	OK
1209	2026-09-11 06:43	80.46	OK	1210	2026-09-11 06:44	79.33	OK
1211	2026-09-11 06:45	81.62	OK	1212	2026-09-11 06:46	79.61	OK
1213	2026-09-11 06:47	79.55	OK	1214	2026-09-11 06:48	79.39	OK
1215	2026-09-11 06:49	80.13	OK	1216	2026-09-11 06:50	78.33	OK
1217	2026-09-11 06:51	80.23	OK	1218	2026-09-11 06:52	79.23	OK
1219	2026-09-11 06:53	79.28	OK	1220	2026-09-11 06:54	81.67	OK
1221	2026-09-11 06:55	78.33	OK	1222	2026-09-11 06:56	77.98	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1223	2026-09-11 06:57	77.84	OK	1224	2026-09-11 06:58	82.14	OK
1225	2026-09-11 06:59	80.83	OK	1226	2026-09-11 07:00	80.73	OK
1227	2026-09-11 07:01	80.27	OK	1228	2026-09-11 07:02	79.57	OK
1229	2026-09-11 07:03	78.45	OK	1230	2026-09-11 07:04	80.37	OK
1231	2026-09-11 07:05	78.62	OK	1232	2026-09-11 07:06	79.96	OK
1233	2026-09-11 07:07	77.67	OK	1234	2026-09-11 07:08	78.47	OK
1235	2026-09-11 07:09	78.62	OK	1236	2026-09-11 07:10	77.19	OK
1237	2026-09-11 07:11	78.31	OK	1238	2026-09-11 07:12	79.40	OK
1239	2026-09-11 07:13	78.00	OK	1240	2026-09-11 07:14	76.45	OK
1241	2026-09-11 07:15	78.72	OK	1242	2026-09-11 07:16	78.69	OK
1243	2026-09-11 07:17	79.21	OK	1244	2026-09-11 07:18	80.97	OK
1245	2026-09-11 07:19	75.80	OK	1246	2026-09-11 07:20	79.52	OK
1247	2026-09-11 07:21	79.13	OK	1248	2026-09-11 07:22	80.52	OK
1249	2026-09-11 07:23	78.97	OK	1250	2026-09-11 07:24	77.62	OK
1251	2026-09-11 07:25	77.74	OK	1252	2026-09-11 07:26	76.80	OK
1253	2026-09-11 07:27	81.54	OK	1254	2026-09-11 07:28	79.32	OK
1255	2026-09-11 07:29	78.70	OK	1256	2026-09-11 07:30	76.55	OK
1257	2026-09-11 07:31	77.05	OK	1258	2026-09-11 07:32	79.43	OK
1259	2026-09-11 07:33	79.25	OK	1260	2026-09-11 07:34	77.37	OK
1261	2026-09-11 07:35	79.83	OK	1262	2026-09-11 07:36	77.51	OK
1263	2026-09-11 07:37	78.88	OK	1264	2026-09-11 07:38	77.74	OK
1265	2026-09-11 07:39	78.53	OK	1266	2026-09-11 07:40	79.42	OK
1267	2026-09-11 07:41	77.85	OK	1268	2026-09-11 07:42	79.10	OK
1269	2026-09-11 07:43	77.15	OK	1270	2026-09-11 07:44	77.68	OK
1271	2026-09-11 07:45	78.53	OK	1272	2026-09-11 07:46	76.48	OK
1273	2026-09-11 07:47	75.33	OK	1274	2026-09-11 07:48	77.77	OK
1275	2026-09-11 07:49	75.75	OK	1276	2026-09-11 07:50	78.61	OK
1277	2026-09-11 07:51	76.45	OK	1278	2026-09-11 07:52	78.27	OK
1279	2026-09-11 07:53	78.21	OK	1280	2026-09-11 07:54	76.74	OK
1281	2026-09-11 07:55	78.56	OK	1282	2026-09-11 07:56	77.91	OK
1283	2026-09-11 07:57	79.03	OK	1284	2026-09-11 07:58	76.98	OK
1285	2026-09-11 07:59	78.62	OK	1286	2026-09-11 08:00	78.57	OK
1287	2026-09-11 08:01	78.00	OK	1288	2026-09-11 08:02	79.56	OK
1289	2026-09-11 08:03	79.75	OK	1290	2026-09-11 08:04	77.26	OK
1291	2026-09-11 08:05	79.96	OK	1292	2026-09-11 08:06	75.25	OK
1293	2026-09-11 08:07	77.63	OK	1294	2026-09-11 08:08	75.85	OK
1295	2026-09-11 08:09	76.59	OK	1296	2026-09-11 08:10	77.24	OK
1297	2026-09-11 08:11	77.01	OK	1298	2026-09-11 08:12	78.47	OK
1299	2026-09-11 08:13	78.79	OK	1300	2026-09-11 08:14	76.89	OK
1301	2026-09-11 08:15	78.37	OK	1302	2026-09-11 08:16	77.22	OK
1303	2026-09-11 08:17	79.21	OK	1304	2026-09-11 08:18	79.51	OK
1305	2026-09-11 08:19	75.87	OK	1306	2026-09-11 08:20	77.26	OK
1307	2026-09-11 08:21	77.83	OK	1308	2026-09-11 08:22	75.76	OK
1309	2026-09-11 08:23	77.88	OK	1310	2026-09-11 08:24	78.24	OK
1311	2026-09-11 08:25	78.36	OK	1312	2026-09-11 08:26	77.56	OK
1313	2026-09-11 08:27	74.99	OK	1314	2026-09-11 08:28	77.63	OK
1315	2026-09-11 08:29	76.34	OK	1316	2026-09-11 08:30	77.53	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1317	2026-09-11 08:31	78.11	OK	1318	2026-09-11 08:32	77.74	OK
1319	2026-09-11 08:33	75.04	OK	1320	2026-09-11 08:34	77.78	OK
1321	2026-09-11 08:35	76.11	OK	1322	2026-09-11 08:36	77.23	OK
1323	2026-09-11 08:37	76.27	OK	1324	2026-09-11 08:38	76.15	OK
1325	2026-09-11 08:39	76.59	OK	1326	2026-09-11 08:40	80.02	OK
1327	2026-09-11 08:41	74.95	OK	1328	2026-09-11 08:42	75.24	OK
1329	2026-09-11 08:43	76.85	OK	1330	2026-09-11 08:44	76.18	OK
1331	2026-09-11 08:45	78.16	OK	1332	2026-09-11 08:46	76.22	OK
1333	2026-09-11 08:47	75.55	OK	1334	2026-09-11 08:48	77.43	OK
1335	2026-09-11 08:49	77.51	OK	1336	2026-09-11 08:50	76.10	OK
1337	2026-09-11 08:51	78.20	OK	1338	2026-09-11 08:52	79.11	OK
1339	2026-09-11 08:53	78.08	OK	1340	2026-09-11 08:54	76.73	OK
1341	2026-09-11 08:55	77.18	OK	1342	2026-09-11 08:56	74.53	OK
1343	2026-09-11 08:57	76.87	OK	1344	2026-09-11 08:58	78.59	OK
1345	2026-09-11 08:59	77.13	OK	1346	2026-09-11 09:00	79.40	OK
1347	2026-09-11 09:01	74.68	OK	1348	2026-09-11 09:02	78.06	OK
1349	2026-09-11 09:03	77.66	OK	1350	2026-09-11 09:04	77.17	OK
1351	2026-09-11 09:05	77.37	OK	1352	2026-09-11 09:06	75.60	OK
1353	2026-09-11 09:07	74.79	OK	1354	2026-09-11 09:08	75.88	OK
1355	2026-09-11 09:09	76.43	OK	1356	2026-09-11 09:10	75.75	OK
1357	2026-09-11 09:11	77.51	OK	1358	2026-09-11 09:12	75.34	OK
1359	2026-09-11 09:13	77.59	OK	1360	2026-09-11 09:14	77.03	OK
1361	2026-09-11 09:15	74.68	OK	1362	2026-09-11 09:16	76.79	OK
1363	2026-09-11 09:17	77.37	OK	1364	2026-09-11 09:18	76.29	OK
1365	2026-09-11 09:19	75.49	OK	1366	2026-09-11 09:20	77.25	OK
1367	2026-09-11 09:21	73.78	OK	1368	2026-09-11 09:22	73.47	OK
1369	2026-09-11 09:23	72.90	OK	1370	2026-09-11 09:24	72.97	OK
1371	2026-09-11 09:25	76.00	OK	1372	2026-09-11 09:26	76.37	OK
1373	2026-09-11 09:27	73.56	OK	1374	2026-09-11 09:28	76.20	OK
1375	2026-09-11 09:29	77.05	OK	1376	2026-09-11 09:30	75.80	OK
1377	2026-09-11 09:31	76.91	OK	1378	2026-09-11 09:32	76.93	OK
1379	2026-09-11 09:33	73.89	OK	1380	2026-09-11 09:34	73.57	OK
1381	2026-09-11 09:35	73.71	OK	1382	2026-09-11 09:36	76.99	OK
1383	2026-09-11 09:37	75.60	OK	1384	2026-09-11 09:38	76.40	OK
1385	2026-09-11 09:39	76.98	OK	1386	2026-09-11 09:40	77.63	OK
1387	2026-09-11 09:41	75.48	OK	1388	2026-09-11 09:42	75.09	OK
1389	2026-09-11 09:43	76.47	OK	1390	2026-09-11 09:44	78.70	OK
1391	2026-09-11 09:45	74.72	OK	1392	2026-09-11 09:46	75.19	OK
1393	2026-09-11 09:47	76.35	OK	1394	2026-09-11 09:48	73.65	OK
1395	2026-09-11 09:49	76.37	OK	1396	2026-09-11 09:50	77.73	OK
1397	2026-09-11 09:51	72.93	OK	1398	2026-09-11 09:52	76.92	OK
1399	2026-09-11 09:53	74.79	OK	1400	2026-09-11 09:54	76.96	OK
1401	2026-09-11 09:55	74.02	OK	1402	2026-09-11 09:56	77.13	OK
1403	2026-09-11 09:57	73.93	OK	1404	2026-09-11 09:58	76.15	OK
1405	2026-09-11 09:59	73.78	OK	1406	2026-09-11 10:00	75.04	OK
1407	2026-09-11 10:01	73.52	OK	1408	2026-09-11 10:02	73.86	OK
1409	2026-09-11 10:03	75.94	OK	1410	2026-09-11 10:04	75.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1411	2026-09-11 10:05	77.04	OK	1412	2026-09-11 10:06	74.71	OK
1413	2026-09-11 10:07	74.20	OK	1414	2026-09-11 10:08	75.83	OK
1415	2026-09-11 10:09	75.97	OK	1416	2026-09-11 10:10	75.03	OK
1417	2026-09-11 10:11	76.99	OK	1418	2026-09-11 10:12	72.92	OK
1419	2026-09-11 10:13	75.52	OK	1420	2026-09-11 10:14	75.22	OK
1421	2026-09-11 10:15	74.89	OK	1422	2026-09-11 10:16	74.78	OK
1423	2026-09-11 10:17	74.66	OK	1424	2026-09-11 10:18	72.48	OK
1425	2026-09-11 10:19	75.70	OK	1426	2026-09-11 10:20	72.68	OK
1427	2026-09-11 10:21	74.38	OK	1428	2026-09-11 10:22	73.32	OK
1429	2026-09-11 10:23	72.41	OK	1430	2026-09-11 10:24	75.84	OK
1431	2026-09-11 10:25	74.01	OK	1432	2026-09-11 10:26	74.22	OK
1433	2026-09-11 10:27	76.20	OK	1434	2026-09-11 10:28	73.17	OK
1435	2026-09-11 10:29	74.97	OK	1436	2026-09-11 10:30	73.54	OK
1437	2026-09-11 10:31	73.66	OK	1438	2026-09-11 10:32	75.65	OK
1439	2026-09-11 10:33	74.90	OK	1440	2026-09-11 10:34	75.05	OK
1441	2026-09-11 10:35	74.19	OK	1442	2026-09-11 10:36	75.55	OK
1443	2026-09-11 10:37	74.90	OK	1444	2026-09-11 10:38	73.31	OK
1445	2026-09-11 10:39	73.05	OK	1446	2026-09-11 10:40	75.11	OK
1447	2026-09-11 10:41	72.57	OK	1448	2026-09-11 10:42	73.62	OK
1449	2026-09-11 10:43	73.64	OK	1450	2026-09-11 10:44	73.81	OK
1451	2026-09-11 10:45	73.48	OK	1452	2026-09-11 10:46	74.51	OK
1453	2026-09-11 10:47	72.56	OK	1454	2026-09-11 10:48	74.70	OK
1455	2026-09-11 10:49	75.76	OK	1456	2026-09-11 10:50	74.16	OK
1457	2026-09-11 10:51	75.51	OK	1458	2026-09-11 10:52	72.11	OK
1459	2026-09-11 10:53	74.70	OK	1460	2026-09-11 10:54	73.62	OK
1461	2026-09-11 10:55	74.78	OK	1462	2026-09-11 10:56	73.89	OK
1463	2026-09-11 10:57	74.09	OK	1464	2026-09-11 10:58	75.88	OK
1465	2026-09-11 10:59	72.87	OK	1466	2026-09-11 11:00	75.85	OK
1467	2026-09-11 11:01	75.11	OK	1468	2026-09-11 11:02	75.42	OK
1469	2026-09-11 11:03	70.66	OK	1470	2026-09-11 11:04	73.67	OK
1471	2026-09-11 11:05	72.94	OK	1472	2026-09-11 11:06	73.96	OK
1473	2026-09-11 11:07	74.04	OK	1474	2026-09-11 11:08	74.47	OK
1475	2026-09-11 11:09	71.98	OK	1476	2026-09-11 11:10	74.95	OK
1477	2026-09-11 11:11	74.03	OK	1478	2026-09-11 11:12	73.96	OK
1479	2026-09-11 11:13	70.71	OK	1480	2026-09-11 11:14	75.50	OK
1481	2026-09-11 11:15	72.64	OK	1482	2026-09-11 11:16	73.50	OK
1483	2026-09-11 11:17	75.32	OK	1484	2026-09-11 11:18	70.63	OK
1485	2026-09-11 11:19	74.10	OK	1486	2026-09-11 11:20	71.91	OK
1487	2026-09-11 11:21	73.06	OK	1488	2026-09-11 11:22	72.63	OK
1489	2026-09-11 11:23	73.71	OK	1490	2026-09-11 11:24	71.68	OK
1491	2026-09-11 11:25	71.10	OK	1492	2026-09-11 11:26	73.81	OK
1493	2026-09-11 11:27	71.92	OK	1494	2026-09-11 11:28	71.88	OK
1495	2026-09-11 11:29	75.32	OK	1496	2026-09-11 11:30	73.00	OK
1497	2026-09-11 11:31	73.72	OK	1498	2026-09-11 11:32	76.29	OK
1499	2026-09-11 11:33	73.81	OK	1500	2026-09-11 11:34	74.30	OK
1501	2026-09-11 11:35	71.93	OK	1502	2026-09-11 11:36	73.10	OK
1503	2026-09-11 11:37	71.50	OK	1504	2026-09-11 11:38	71.76	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1505	2026-09-11 11:39	72.22	OK	1506	2026-09-11 11:40	74.12	OK
1507	2026-09-11 11:41	74.78	OK	1508	2026-09-11 11:42	71.96	OK
1509	2026-09-11 11:43	73.46	OK	1510	2026-09-11 11:44	73.08	OK
1511	2026-09-11 11:45	74.02	OK	1512	2026-09-11 11:46	75.09	OK
1513	2026-09-11 11:47	71.24	OK	1514	2026-09-11 11:48	74.23	OK
1515	2026-09-11 11:49	73.41	OK	1516	2026-09-11 11:50	71.30	OK
1517	2026-09-11 11:51	72.99	OK	1518	2026-09-11 11:52	70.86	OK
1519	2026-09-11 11:53	73.16	OK	1520	2026-09-11 11:54	71.39	OK
1521	2026-09-11 11:55	73.45	OK	1522	2026-09-11 11:56	70.41	OK
1523	2026-09-11 11:57	73.91	OK	1524	2026-09-11 11:58	72.22	OK
1525	2026-09-11 11:59	72.61	OK	1526	2026-09-11 12:00	73.27	OK
1527	2026-09-11 12:01	74.11	OK	1528	2026-09-11 12:02	69.87	OK
1529	2026-09-11 12:03	72.71	OK	1530	2026-09-11 12:04	73.60	OK
1531	2026-09-11 12:05	73.26	OK	1532	2026-09-11 12:06	71.80	OK
1533	2026-09-11 12:07	70.51	OK	1534	2026-09-11 12:08	73.73	OK
1535	2026-09-11 12:09	73.17	OK	1536	2026-09-11 12:10	72.91	OK
1537	2026-09-11 12:11	73.31	OK	1538	2026-09-11 12:12	72.61	OK
1539	2026-09-11 12:13	75.53	OK	1540	2026-09-11 12:14	71.75	OK
1541	2026-09-11 12:15	73.28	OK	1542	2026-09-11 12:16	71.07	OK
1543	2026-09-11 12:17	72.89	OK	1544	2026-09-11 12:18	74.07	OK
1545	2026-09-11 12:19	68.96	OK	1546	2026-09-11 12:20	74.51	OK
1547	2026-09-11 12:21	70.83	OK	1548	2026-09-11 12:22	73.63	OK
1549	2026-09-11 12:23	71.19	OK	1550	2026-09-11 12:24	71.10	OK
1551	2026-09-11 12:25	70.05	OK	1552	2026-09-11 12:26	74.34	OK
1553	2026-09-11 12:27	70.86	OK	1554	2026-09-11 12:28	70.21	OK
1555	2026-09-11 12:29	71.15	OK	1556	2026-09-11 12:30	71.40	OK
1557	2026-09-11 12:31	72.93	OK	1558	2026-09-11 12:32	74.54	OK
1559	2026-09-11 12:33	73.42	OK	1560	2026-09-11 12:34	72.53	OK
1561	2026-09-11 12:35	70.44	OK	1562	2026-09-11 12:36	68.98	OK
1563	2026-09-11 12:37	73.83	OK	1564	2026-09-11 12:38	71.61	OK
1565	2026-09-11 12:39	69.35	OK	1566	2026-09-11 12:40	73.30	OK
1567	2026-09-11 12:41	69.45	OK	1568	2026-09-11 12:42	72.87	OK
1569	2026-09-11 12:43	71.63	OK	1570	2026-09-11 12:44	69.47	OK
1571	2026-09-11 12:45	74.84	OK	1572	2026-09-11 12:46	73.94	OK
1573	2026-09-11 12:47	69.69	OK	1574	2026-09-11 12:48	74.14	OK
1575	2026-09-11 12:49	72.51	OK	1576	2026-09-11 12:50	71.58	OK
1577	2026-09-11 12:51	72.92	OK	1578	2026-09-11 12:52	70.26	OK
1579	2026-09-11 12:53	71.05	OK	1580	2026-09-11 12:54	72.04	OK
1581	2026-09-11 12:55	71.05	OK	1582	2026-09-11 12:56	70.58	OK
1583	2026-09-11 12:57	70.84	OK	1584	2026-09-11 12:58	71.78	OK
1585	2026-09-11 12:59	72.71	OK	1586	2026-09-11 13:00	75.46	OK
1587	2026-09-11 13:01	71.80	OK	1588	2026-09-11 13:02	71.34	OK
1589	2026-09-11 13:03	70.62	OK	1590	2026-09-11 13:04	72.17	OK
1591	2026-09-11 13:05	70.50	OK	1592	2026-09-11 13:06	72.53	OK
1593	2026-09-11 13:07	72.67	OK	1594	2026-09-11 13:08	73.04	OK
1595	2026-09-11 13:09	72.24	OK	1596	2026-09-11 13:10	71.18	OK
1597	2026-09-11 13:11	69.73	OK	1598	2026-09-11 13:12	70.92	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1599	2026-09-11 13:13	71.38	OK	1600	2026-09-11 13:14	71.93	OK
1601	2026-09-11 13:15	72.53	OK	1602	2026-09-11 13:16	71.48	OK
1603	2026-09-11 13:17	69.41	OK	1604	2026-09-11 13:18	71.77	OK
1605	2026-09-11 13:19	72.73	OK	1606	2026-09-11 13:20	72.18	OK
1607	2026-09-11 13:21	74.00	OK	1608	2026-09-11 13:22	73.53	OK
1609	2026-09-11 13:23	71.34	OK	1610	2026-09-11 13:24	72.92	OK
1611	2026-09-11 13:25	73.69	OK	1612	2026-09-11 13:26	71.50	OK
1613	2026-09-11 13:27	72.51	OK	1614	2026-09-11 13:28	74.55	OK
1615	2026-09-11 13:29	73.46	OK	1616	2026-09-11 13:30	68.34	OK
1617	2026-09-11 13:31	72.89	OK	1618	2026-09-11 13:32	72.56	OK
1619	2026-09-11 13:33	70.82	OK	1620	2026-09-11 13:34	71.74	OK
1621	2026-09-11 13:35	74.24	OK	1622	2026-09-11 13:36	70.67	OK
1623	2026-09-11 13:37	69.32	OK	1624	2026-09-11 13:38	70.90	OK
1625	2026-09-11 13:39	71.50	OK	1626	2026-09-11 13:40	73.49	OK
1627	2026-09-11 13:41	71.13	OK	1628	2026-09-11 13:42	72.04	OK
1629	2026-09-11 13:43	68.99	OK	1630	2026-09-11 13:44	72.73	OK
1631	2026-09-11 13:45	70.54	OK	1632	2026-09-11 13:46	70.85	OK
1633	2026-09-11 13:47	71.05	OK	1634	2026-09-11 13:48	70.56	OK
1635	2026-09-11 13:49	72.74	OK	1636	2026-09-11 13:50	72.11	OK
1637	2026-09-11 13:51	73.26	OK	1638	2026-09-11 13:52	69.18	OK
1639	2026-09-11 13:53	68.87	OK	1640	2026-09-11 13:54	71.68	OK
1641	2026-09-11 13:55	70.63	OK	1642	2026-09-11 13:56	70.77	OK
1643	2026-09-11 13:57	71.94	OK	1644	2026-09-11 13:58	72.18	OK
1645	2026-09-11 13:59	73.28	OK	1646	2026-09-11 14:00	71.07	OK
1647	2026-09-11 14:01	71.42	OK	1648	2026-09-11 14:02	70.43	OK
1649	2026-09-11 14:03	70.80	OK	1650	2026-09-11 14:04	72.10	OK
1651	2026-09-11 14:05	70.99	OK	1652	2026-09-11 14:06	73.10	OK
1653	2026-09-11 14:07	73.10	OK	1654	2026-09-11 14:08	70.06	OK
1655	2026-09-11 14:09	70.85	OK	1656	2026-09-11 14:10	69.58	OK
1657	2026-09-11 14:11	71.21	OK	1658	2026-09-11 14:12	72.54	OK
1659	2026-09-11 14:13	70.49	OK	1660	2026-09-11 14:14	74.39	OK
1661	2026-09-11 14:15	72.13	OK	1662	2026-09-11 14:16	73.30	OK
1663	2026-09-11 14:17	71.46	OK	1664	2026-09-11 14:18	70.80	OK
1665	2026-09-11 14:19	70.17	OK	1666	2026-09-11 14:20	69.55	OK
1667	2026-09-11 14:21	69.58	OK	1668	2026-09-11 14:22	71.89	OK
1669	2026-09-11 14:23	70.21	OK	1670	2026-09-11 14:24	73.36	OK
1671	2026-09-11 14:25	73.56	OK	1672	2026-09-11 14:26	69.71	OK
1673	2026-09-11 14:27	72.04	OK	1674	2026-09-11 14:28	69.81	OK
1675	2026-09-11 14:29	72.60	OK	1676	2026-09-11 14:30	72.07	OK
1677	2026-09-11 14:31	73.01	OK	1678	2026-09-11 14:32	73.23	OK
1679	2026-09-11 14:33	71.69	OK	1680	2026-09-11 14:34	73.66	OK
1681	2026-09-11 14:35	69.79	OK	1682	2026-09-11 14:36	70.30	OK
1683	2026-09-11 14:37	72.20	OK	1684	2026-09-11 14:38	71.51	OK
1685	2026-09-11 14:39	70.00	OK	1686	2026-09-11 14:40	72.48	OK
1687	2026-09-11 14:41	72.09	OK	1688	2026-09-11 14:42	68.66	OK
1689	2026-09-11 14:43	71.89	OK	1690	2026-09-11 14:44	68.70	OK
1691	2026-09-11 14:45	70.84	OK	1692	2026-09-11 14:46	71.78	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1693	2026-09-11 14:47	70.89	OK	1694	2026-09-11 14:48	70.27	OK
1695	2026-09-11 14:49	70.01	OK	1696	2026-09-11 14:50	72.04	OK
1697	2026-09-11 14:51	72.54	OK	1698	2026-09-11 14:52	72.49	OK
1699	2026-09-11 14:53	72.08	OK	1700	2026-09-11 14:54	70.36	OK
1701	2026-09-11 14:55	72.31	OK	1702	2026-09-11 14:56	71.28	OK
1703	2026-09-11 14:57	70.82	OK	1704	2026-09-11 14:58	70.09	OK
1705	2026-09-11 14:59	71.27	OK	1706	2026-09-11 15:00	70.55	OK
1707	2026-09-11 15:01	70.92	OK	1708	2026-09-11 15:02	73.08	OK
1709	2026-09-11 15:03	71.00	OK	1710	2026-09-11 15:04	71.47	OK
1711	2026-09-11 15:05	72.01	OK	1712	2026-09-11 15:06	69.07	OK
1713	2026-09-11 15:07	73.17	OK	1714	2026-09-11 15:08	70.77	OK
1715	2026-09-11 15:09	73.02	OK	1716	2026-09-11 15:10	70.01	OK
1717	2026-09-11 15:11	70.30	OK	1718	2026-09-11 15:12	70.73	OK
1719	2026-09-11 15:13	70.39	OK	1720	2026-09-11 15:14	69.43	OK
1721	2026-09-11 15:15	72.37	OK	1722	2026-09-11 15:16	70.58	OK
1723	2026-09-11 15:17	72.65	OK	1724	2026-09-11 15:18	68.76	OK
1725	2026-09-11 15:19	72.78	OK	1726	2026-09-11 15:20	71.74	OK
1727	2026-09-11 15:21	72.44	OK	1728	2026-09-11 15:22	72.35	OK
1729	2026-09-11 15:23	70.91	OK	1730	2026-09-11 15:24	71.62	OK
1731	2026-09-11 15:25	72.33	OK	1732	2026-09-11 15:26	70.44	OK
1733	2026-09-11 15:27	72.46	OK	1734	2026-09-11 15:28	72.35	OK
1735	2026-09-11 15:29	70.68	OK	1736	2026-09-11 15:30	72.38	OK
1737	2026-09-11 15:31	73.07	OK	1738	2026-09-11 15:32	70.32	OK
1739	2026-09-11 15:33	70.84	OK	1740	2026-09-11 15:34	72.22	OK
1741	2026-09-11 15:35	71.78	OK	1742	2026-09-11 15:36	69.99	OK
1743	2026-09-11 15:37	71.67	OK	1744	2026-09-11 15:38	71.13	OK
1745	2026-09-11 15:39	72.73	OK	1746	2026-09-11 15:40	71.63	OK
1747	2026-09-11 15:41	70.12	OK	1748	2026-09-11 15:42	73.98	OK
1749	2026-09-11 15:43	70.27	OK	1750	2026-09-11 15:44	69.91	OK
1751	2026-09-11 15:45	71.90	OK	1752	2026-09-11 15:46	72.55	OK
1753	2026-09-11 15:47	73.45	OK	1754	2026-09-11 15:48	70.19	OK
1755	2026-09-11 15:49	71.94	OK	1756	2026-09-11 15:50	72.42	OK
1757	2026-09-11 15:51	74.49	OK	1758	2026-09-11 15:52	70.72	OK
1759	2026-09-11 15:53	73.59	OK	1760	2026-09-11 15:54	71.06	OK
1761	2026-09-11 15:55	72.93	OK	1762	2026-09-11 15:56	70.57	OK
1763	2026-09-11 15:57	72.17	OK	1764	2026-09-11 15:58	72.19	OK
1765	2026-09-11 15:59	71.98	OK	1766	2026-09-11 16:00	69.29	OK
1767	2026-09-11 16:01	72.28	OK	1768	2026-09-11 16:02	71.14	OK
1769	2026-09-11 16:03	72.41	OK	1770	2026-09-11 16:04	72.40	OK
1771	2026-09-11 16:05	69.48	OK	1772	2026-09-11 16:06	70.53	OK
1773	2026-09-11 16:07	71.78	OK	1774	2026-09-11 16:08	71.05	OK
1775	2026-09-11 16:09	71.70	OK	1776	2026-09-11 16:10	73.46	OK
1777	2026-09-11 16:11	71.35	OK	1778	2026-09-11 16:12	69.61	OK
1779	2026-09-11 16:13	71.07	OK	1780	2026-09-11 16:14	72.72	OK
1781	2026-09-11 16:15	71.60	OK	1782	2026-09-11 16:16	71.29	OK
1783	2026-09-11 16:17	72.21	OK	1784	2026-09-11 16:18	71.77	OK
1785	2026-09-11 16:19	69.99	OK	1786	2026-09-11 16:20	72.89	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1787	2026-09-11 16:21	72.96	OK	1788	2026-09-11 16:22	72.29	OK
1789	2026-09-11 16:23	72.04	OK	1790	2026-09-11 16:24	74.23	OK
1791	2026-09-11 16:25	73.28	OK	1792	2026-09-11 16:26	71.06	OK
1793	2026-09-11 16:27	71.93	OK	1794	2026-09-11 16:28	70.58	OK
1795	2026-09-11 16:29	71.75	OK	1796	2026-09-11 16:30	74.50	OK
1797	2026-09-11 16:31	71.65	OK	1798	2026-09-11 16:32	71.50	OK
1799	2026-09-11 16:33	72.46	OK	1800	2026-09-11 16:34	71.75	OK
1801	2026-09-11 16:35	70.31	OK	1802	2026-09-11 16:36	73.61	OK
1803	2026-09-11 16:37	72.58	OK	1804	2026-09-11 16:38	71.79	OK
1805	2026-09-11 16:39	73.49	OK	1806	2026-09-11 16:40	71.24	OK
1807	2026-09-11 16:41	70.70	OK	1808	2026-09-11 16:42	71.37	OK
1809	2026-09-11 16:43	71.26	OK	1810	2026-09-11 16:44	72.09	OK
1811	2026-09-11 16:45	72.92	OK	1812	2026-09-11 16:46	73.03	OK
1813	2026-09-11 16:47	73.40	OK	1814	2026-09-11 16:48	71.50	OK
1815	2026-09-11 16:49	72.82	OK	1816	2026-09-11 16:50	71.81	OK
1817	2026-09-11 16:51	75.30	OK	1818	2026-09-11 16:52	69.81	OK
1819	2026-09-11 16:53	74.41	OK	1820	2026-09-11 16:54	72.49	OK
1821	2026-09-11 16:55	71.66	OK	1822	2026-09-11 16:56	72.76	OK
1823	2026-09-11 16:57	72.56	OK	1824	2026-09-11 16:58	71.84	OK
1825	2026-09-11 16:59	72.54	OK	1826	2026-09-11 17:00	70.71	OK
1827	2026-09-11 17:01	70.30	OK	1828	2026-09-11 17:02	71.21	OK
1829	2026-09-11 17:03	73.97	OK	1830	2026-09-11 17:04	74.00	OK
1831	2026-09-11 17:05	74.47	OK	1832	2026-09-11 17:06	74.44	OK
1833	2026-09-11 17:07	72.19	OK	1834	2026-09-11 17:08	73.54	OK
1835	2026-09-11 17:09	73.16	OK	1836	2026-09-11 17:10	71.86	OK
1837	2026-09-11 17:11	70.64	OK	1838	2026-09-11 17:12	72.35	OK
1839	2026-09-11 17:13	72.45	OK	1840	2026-09-11 17:14	72.91	OK
1841	2026-09-11 17:15	71.70	OK	1842	2026-09-11 17:16	71.07	OK
1843	2026-09-11 17:17	70.75	OK	1844	2026-09-11 17:18	72.54	OK
1845	2026-09-11 17:19	71.13	OK	1846	2026-09-11 17:20	71.38	OK
1847	2026-09-11 17:21	74.20	OK	1848	2026-09-11 17:22	73.49	OK
1849	2026-09-11 17:23	70.78	OK	1850	2026-09-11 17:24	71.04	OK
1851	2026-09-11 17:25	72.71	OK	1852	2026-09-11 17:26	72.50	OK
1853	2026-09-11 17:27	74.61	OK	1854	2026-09-11 17:28	74.59	OK
1855	2026-09-11 17:29	72.88	OK	1856	2026-09-11 17:30	71.85	OK
1857	2026-09-11 17:31	72.06	OK	1858	2026-09-11 17:32	71.56	OK
1859	2026-09-11 17:33	73.69	OK	1860	2026-09-11 17:34	73.65	OK
1861	2026-09-11 17:35	72.19	OK	1862	2026-09-11 17:36	71.29	OK
1863	2026-09-11 17:37	72.12	OK	1864	2026-09-11 17:38	71.84	OK
1865	2026-09-11 17:39	71.72	OK	1866	2026-09-11 17:40	72.86	OK
1867	2026-09-11 17:41	72.59	OK	1868	2026-09-11 17:42	74.22	OK
1869	2026-09-11 17:43	71.74	OK	1870	2026-09-11 17:44	72.06	OK
1871	2026-09-11 17:45	71.26	OK	1872	2026-09-11 17:46	71.53	OK
1873	2026-09-11 17:47	73.64	OK	1874	2026-09-11 17:48	72.29	OK
1875	2026-09-11 17:49	74.99	OK	1876	2026-09-11 17:50	74.62	OK
1877	2026-09-11 17:51	73.07	OK	1878	2026-09-11 17:52	73.58	OK
1879	2026-09-11 17:53	74.61	OK	1880	2026-09-11 17:54	73.50	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1881	2026-09-11 17:55	71.21	OK	1882	2026-09-11 17:56	71.10	OK
1883	2026-09-11 17:57	73.38	OK	1884	2026-09-11 17:58	74.01	OK
1885	2026-09-11 17:59	71.30	OK	1886	2026-09-11 18:00	73.27	OK
1887	2026-09-11 18:01	72.79	OK	1888	2026-09-11 18:02	73.39	OK
1889	2026-09-11 18:03	73.46	OK	1890	2026-09-11 18:04	72.18	OK
1891	2026-09-11 18:05	72.17	OK	1892	2026-09-11 18:06	72.23	OK
1893	2026-09-11 18:07	72.63	OK	1894	2026-09-11 18:08	75.15	OK
1895	2026-09-11 18:09	71.99	OK	1896	2026-09-11 18:10	73.49	OK
1897	2026-09-11 18:11	72.67	OK	1898	2026-09-11 18:12	72.31	OK
1899	2026-09-11 18:13	73.30	OK	1900	2026-09-11 18:14	70.71	OK
1901	2026-09-11 18:15	71.75	OK	1902	2026-09-11 18:16	71.94	OK
1903	2026-09-11 18:17	74.80	OK	1904	2026-09-11 18:18	75.39	OK
1905	2026-09-11 18:19	74.60	OK	1906	2026-09-11 18:20	73.12	OK
1907	2026-09-11 18:21	72.73	OK	1908	2026-09-11 18:22	73.56	OK
1909	2026-09-11 18:23	74.34	OK	1910	2026-09-11 18:24	74.34	OK
1911	2026-09-11 18:25	73.44	OK	1912	2026-09-11 18:26	70.71	OK
1913	2026-09-11 18:27	72.86	OK	1914	2026-09-11 18:28	75.12	OK
1915	2026-09-11 18:29	74.38	OK	1916	2026-09-11 18:30	73.55	OK
1917	2026-09-11 18:31	74.35	OK	1918	2026-09-11 18:32	71.11	OK
1919	2026-09-11 18:33	70.91	OK	1920	2026-09-11 18:34	71.05	OK
1921	2026-09-11 18:35	73.75	OK	1922	2026-09-11 18:36	73.19	OK
1923	2026-09-11 18:37	73.80	OK	1924	2026-09-11 18:38	73.04	OK
1925	2026-09-11 18:39	72.19	OK	1926	2026-09-11 18:40	73.68	OK
1927	2026-09-11 18:41	72.41	OK	1928	2026-09-11 18:42	74.61	OK
1929	2026-09-11 18:43	72.95	OK	1930	2026-09-11 18:44	72.85	OK
1931	2026-09-11 18:45	74.16	OK	1932	2026-09-11 18:46	74.95	OK
1933	2026-09-11 18:47	72.40	OK	1934	2026-09-11 18:48	74.46	OK
1935	2026-09-11 18:49	71.61	OK	1936	2026-09-11 18:50	74.14	OK
1937	2026-09-11 18:51	76.51	OK	1938	2026-09-11 18:52	75.89	OK
1939	2026-09-11 18:53	73.23	OK	1940	2026-09-11 18:54	74.77	OK
1941	2026-09-11 18:55	74.74	OK	1942	2026-09-11 18:56	73.80	OK
1943	2026-09-11 18:57	75.59	OK	1944	2026-09-11 18:58	74.27	OK
1945	2026-09-11 18:59	74.91	OK	1946	2026-09-11 19:00	73.61	OK
1947	2026-09-11 19:01	74.34	OK	1948	2026-09-11 19:02	72.83	OK
1949	2026-09-11 19:03	73.24	OK	1950	2026-09-11 19:04	74.11	OK
1951	2026-09-11 19:05	77.70	OK	1952	2026-09-11 19:06	74.25	OK
1953	2026-09-11 19:07	74.57	OK	1954	2026-09-11 19:08	73.45	OK
1955	2026-09-11 19:09	74.41	OK	1956	2026-09-11 19:10	73.37	OK
1957	2026-09-11 19:11	74.89	OK	1958	2026-09-11 19:12	74.89	OK
1959	2026-09-11 19:13	72.76	OK	1960	2026-09-11 19:14	73.21	OK
1961	2026-09-11 19:15	76.17	OK	1962	2026-09-11 19:16	75.23	OK
1963	2026-09-11 19:17	73.67	OK	1964	2026-09-11 19:18	75.10	OK
1965	2026-09-11 19:19	74.04	OK	1966	2026-09-11 19:20	74.04	OK
1967	2026-09-11 19:21	74.28	OK	1968	2026-09-11 19:22	76.07	OK
1969	2026-09-11 19:23	75.33	OK	1970	2026-09-11 19:24	73.67	OK
1971	2026-09-11 19:25	73.26	OK	1972	2026-09-11 19:26	74.52	OK
1973	2026-09-11 19:27	74.20	OK	1974	2026-09-11 19:28	74.23	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1975	2026-09-11 19:29	74.52	OK	1976	2026-09-11 19:30	74.24	OK
1977	2026-09-11 19:31	74.90	OK	1978	2026-09-11 19:32	75.24	OK
1979	2026-09-11 19:33	73.52	OK	1980	2026-09-11 19:34	74.18	OK
1981	2026-09-11 19:35	73.18	OK	1982	2026-09-11 19:36	76.77	OK
1983	2026-09-11 19:37	73.80	OK	1984	2026-09-11 19:38	75.63	OK
1985	2026-09-11 19:39	73.13	OK	1986	2026-09-11 19:40	73.15	OK
1987	2026-09-11 19:41	76.83	OK	1988	2026-09-11 19:42	74.49	OK
1989	2026-09-11 19:43	76.82	OK	1990	2026-09-11 19:44	73.24	OK
1991	2026-09-11 19:45	74.11	OK	1992	2026-09-11 19:46	74.28	OK
1993	2026-09-11 19:47	75.97	OK	1994	2026-09-11 19:48	73.82	OK
1995	2026-09-11 19:49	72.73	OK	1996	2026-09-11 19:50	76.12	OK
1997	2026-09-11 19:51	75.99	OK	1998	2026-09-11 19:52	75.16	OK
1999	2026-09-11 19:53	74.18	OK	2000	2026-09-11 19:54	77.15	OK
2001	2026-09-11 19:55	74.00	OK	2002	2026-09-11 19:56	78.63	OK
2003	2026-09-11 19:57	76.56	OK	2004	2026-09-11 19:58	74.09	OK
2005	2026-09-11 19:59	74.63	OK	2006	2026-09-11 20:00	74.81	OK
2007	2026-09-11 20:01	76.47	OK	2008	2026-09-11 20:02	74.60	OK
2009	2026-09-11 20:03	74.62	OK	2010	2026-09-11 20:04	73.87	OK
2011	2026-09-11 20:05	77.23	OK	2012	2026-09-11 20:06	74.56	OK
2013	2026-09-11 20:07	75.05	OK	2014	2026-09-11 20:08	75.26	OK
2015	2026-09-11 20:09	73.32	OK	2016	2026-09-11 20:10	75.24	OK
2017	2026-09-11 20:11	76.73	OK	2018	2026-09-11 20:12	74.37	OK
2019	2026-09-11 20:13	77.49	OK	2020	2026-09-11 20:14	77.53	OK
2021	2026-09-11 20:15	77.56	OK	2022	2026-09-11 20:16	75.31	OK
2023	2026-09-11 20:17	75.15	OK	2024	2026-09-11 20:18	79.14	OK
2025	2026-09-11 20:19	77.73	OK	2026	2026-09-11 20:20	75.94	OK
2027	2026-09-11 20:21	78.18	OK	2028	2026-09-11 20:22	78.02	OK
2029	2026-09-11 20:23	77.94	OK	2030	2026-09-11 20:24	76.77	OK
2031	2026-09-11 20:25	76.06	OK	2032	2026-09-11 20:26	77.33	OK
2033	2026-09-11 20:27	76.58	OK	2034	2026-09-11 20:28	73.56	OK
2035	2026-09-11 20:29	76.83	OK	2036	2026-09-11 20:30	76.04	OK
2037	2026-09-11 20:31	77.51	OK	2038	2026-09-11 20:32	76.42	OK
2039	2026-09-11 20:33	76.61	OK	2040	2026-09-11 20:34	76.29	OK
2041	2026-09-11 20:35	77.50	OK	2042	2026-09-11 20:36	74.49	OK
2043	2026-09-11 20:37	77.25	OK	2044	2026-09-11 20:38	75.52	OK
2045	2026-09-11 20:39	74.06	OK	2046	2026-09-11 20:40	74.53	OK
2047	2026-09-11 20:41	77.13	OK	2048	2026-09-11 20:42	76.85	OK
2049	2026-09-11 20:43	75.21	OK	2050	2026-09-11 20:44	75.34	OK
2051	2026-09-11 20:45	77.80	OK	2052	2026-09-11 20:46	79.48	OK
2053	2026-09-11 20:47	75.31	OK	2054	2026-09-11 20:48	76.63	OK
2055	2026-09-11 20:49	76.14	OK	2056	2026-09-11 20:50	75.48	OK
2057	2026-09-11 20:51	76.67	OK	2058	2026-09-11 20:52	75.39	OK
2059	2026-09-11 20:53	76.13	OK	2060	2026-09-11 20:54	75.72	OK
2061	2026-09-11 20:55	74.23	OK	2062	2026-09-11 20:56	79.10	OK
2063	2026-09-11 20:57	75.85	OK	2064	2026-09-11 20:58	76.37	OK
2065	2026-09-11 20:59	77.62	OK	2066	2026-09-11 21:00	75.62	OK
2067	2026-09-11 21:01	77.65	OK	2068	2026-09-11 21:02	77.68	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2069	2026-09-11 21:03	73.64	OK	2070	2026-09-11 21:04	77.22	OK
2071	2026-09-11 21:05	76.06	OK	2072	2026-09-11 21:06	78.99	OK
2073	2026-09-11 21:07	78.52	OK	2074	2026-09-11 21:08	77.64	OK
2075	2026-09-11 21:09	75.27	OK	2076	2026-09-11 21:10	75.64	OK
2077	2026-09-11 21:11	77.77	OK	2078	2026-09-11 21:12	75.98	OK
2079	2026-09-11 21:13	77.22	OK	2080	2026-09-11 21:14	76.61	OK
2081	2026-09-11 21:15	75.51	OK	2082	2026-09-11 21:16	75.50	OK
2083	2026-09-11 21:17	79.25	OK	2084	2026-09-11 21:18	79.52	OK
2085	2026-09-11 21:19	75.29	OK	2086	2026-09-11 21:20	77.46	OK
2087	2026-09-11 21:21	76.73	OK	2088	2026-09-11 21:22	74.76	OK
2089	2026-09-11 21:23	75.65	OK	2090	2026-09-11 21:24	77.39	OK
2091	2026-09-11 21:25	78.82	OK	2092	2026-09-11 21:26	79.35	OK
2093	2026-09-11 21:27	78.48	OK	2094	2026-09-11 21:28	74.49	OK
2095	2026-09-11 21:29	75.87	OK	2096	2026-09-11 21:30	77.64	OK
2097	2026-09-11 21:31	77.71	OK	2098	2026-09-11 21:32	78.76	OK
2099	2026-09-11 21:33	78.14	OK	2100	2026-09-11 21:34	79.45	OK
2101	2026-09-11 21:35	75.88	OK	2102	2026-09-11 21:36	77.00	OK
2103	2026-09-11 21:37	78.94	OK	2104	2026-09-11 21:38	77.09	OK
2105	2026-09-11 21:39	78.08	OK	2106	2026-09-11 21:40	78.31	OK
2107	2026-09-11 21:41	79.64	OK	2108	2026-09-11 21:42	76.14	OK
2109	2026-09-11 21:43	78.66	OK	2110	2026-09-11 21:44	78.67	OK
2111	2026-09-11 21:45	77.91	OK	2112	2026-09-11 21:46	79.63	OK
2113	2026-09-11 21:47	77.00	OK	2114	2026-09-11 21:48	78.77	OK
2115	2026-09-11 21:49	76.36	OK	2116	2026-09-11 21:50	78.26	OK
2117	2026-09-11 21:51	77.40	OK	2118	2026-09-11 21:52	78.00	OK
2119	2026-09-11 21:53	80.72	OK	2120	2026-09-11 21:54	77.23	OK
2121	2026-09-11 21:55	79.00	OK	2122	2026-09-11 21:56	78.54	OK
2123	2026-09-11 21:57	78.85	OK	2124	2026-09-11 21:58	77.63	OK
2125	2026-09-11 21:59	76.75	OK	2126	2026-09-11 22:00	78.68	OK
2127	2026-09-11 22:01	79.04	OK	2128	2026-09-11 22:02	79.85	OK
2129	2026-09-11 22:03	77.90	OK	2130	2026-09-11 22:04	77.54	OK
2131	2026-09-11 22:05	78.27	OK	2132	2026-09-11 22:06	78.17	OK
2133	2026-09-11 22:07	79.65	OK	2134	2026-09-11 22:08	76.31	OK
2135	2026-09-11 22:09	77.45	OK	2136	2026-09-11 22:10	77.30	OK
2137	2026-09-11 22:11	78.55	OK	2138	2026-09-11 22:12	77.90	OK
2139	2026-09-11 22:13	77.11	OK	2140	2026-09-11 22:14	76.10	OK
2141	2026-09-11 22:15	79.47	OK	2142	2026-09-11 22:16	76.24	OK
2143	2026-09-11 22:17	80.06	OK	2144	2026-09-11 22:18	79.48	OK
2145	2026-09-11 22:19	78.60	OK	2146	2026-09-11 22:20	78.35	OK
2147	2026-09-11 22:21	78.38	OK	2148	2026-09-11 22:22	78.01	OK
2149	2026-09-11 22:23	79.97	OK	2150	2026-09-11 22:24	78.12	OK
2151	2026-09-11 22:25	77.71	OK	2152	2026-09-11 22:26	80.44	OK
2153	2026-09-11 22:27	77.34	OK	2154	2026-09-11 22:28	79.80	OK
2155	2026-09-11 22:29	77.96	OK	2156	2026-09-11 22:30	80.35	OK
2157	2026-09-11 22:31	76.20	OK	2158	2026-09-11 22:32	79.67	OK
2159	2026-09-11 22:33	79.08	OK	2160	2026-09-11 22:34	79.18	OK
2161	2026-09-11 22:35	78.21	OK	2162	2026-09-11 22:36	79.89	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2163	2026-09-11 22:37	77.43	OK	2164	2026-09-11 22:38	78.67	OK
2165	2026-09-11 22:39	79.81	OK	2166	2026-09-11 22:40	77.43	OK
2167	2026-09-11 22:41	76.52	OK	2168	2026-09-11 22:42	78.58	OK
2169	2026-09-11 22:43	79.94	OK	2170	2026-09-11 22:44	79.41	OK
2171	2026-09-11 22:45	76.73	OK	2172	2026-09-11 22:46	79.66	OK
2173	2026-09-11 22:47	78.41	OK	2174	2026-09-11 22:48	80.03	OK
2175	2026-09-11 22:49	80.25	OK	2176	2026-09-11 22:50	79.53	OK
2177	2026-09-11 22:51	79.58	OK	2178	2026-09-11 22:52	78.46	OK
2179	2026-09-11 22:53	77.51	OK	2180	2026-09-11 22:54	80.17	OK
2181	2026-09-11 22:55	77.95	OK	2182	2026-09-11 22:56	79.35	OK
2183	2026-09-11 22:57	79.47	OK	2184	2026-09-11 22:58	78.75	OK
2185	2026-09-11 22:59	79.52	OK	2186	2026-09-11 23:00	79.39	OK
2187	2026-09-11 23:01	77.35	OK	2188	2026-09-11 23:02	77.50	OK
2189	2026-09-11 23:03	79.44	OK	2190	2026-09-11 23:04	80.54	OK
2191	2026-09-11 23:05	81.48	OK	2192	2026-09-11 23:06	80.42	OK
2193	2026-09-11 23:07	78.84	OK	2194	2026-09-11 23:08	78.17	OK
2195	2026-09-11 23:09	77.68	OK	2196	2026-09-11 23:10	80.50	OK
2197	2026-09-11 23:11	80.67	OK	2198	2026-09-11 23:12	78.18	OK
2199	2026-09-11 23:13	80.21	OK	2200	2026-09-11 23:14	78.40	OK
2201	2026-09-11 23:15	81.24	OK	2202	2026-09-11 23:16	79.63	OK
2203	2026-09-11 23:17	79.09	OK	2204	2026-09-11 23:18	79.48	OK
2205	2026-09-11 23:19	79.85	OK	2206	2026-09-11 23:20	80.17	OK
2207	2026-09-11 23:21	81.32	OK	2208	2026-09-11 23:22	80.39	OK
2209	2026-09-11 23:23	79.82	OK	2210	2026-09-11 23:24	78.74	OK
2211	2026-09-11 23:25	79.57	OK	2212	2026-09-11 23:26	80.70	OK
2213	2026-09-11 23:27	80.17	OK	2214	2026-09-11 23:28	80.26	OK
2215	2026-09-11 23:29	81.55	OK	2216	2026-09-11 23:30	77.88	OK
2217	2026-09-11 23:31	80.09	OK	2218	2026-09-11 23:32	81.89	OK
2219	2026-09-11 23:33	82.19	OK	2220	2026-09-11 23:34	80.54	OK
2221	2026-09-11 23:35	81.05	OK	2222	2026-09-11 23:36	78.60	OK
2223	2026-09-11 23:37	82.27	OK	2224	2026-09-11 23:38	78.60	OK
2225	2026-09-11 23:39	80.57	OK	2226	2026-09-11 23:40	77.90	OK
2227	2026-09-11 23:41	79.37	OK	2228	2026-09-11 23:42	79.39	OK
2229	2026-09-11 23:43	78.89	OK	2230	2026-09-11 23:44	82.56	OK
2231	2026-09-11 23:45	79.46	OK	2232	2026-09-11 23:46	80.21	OK
2233	2026-09-11 23:47	81.36	OK	2234	2026-09-11 23:48	80.55	OK
2235	2026-09-11 23:49	80.38	OK	2236	2026-09-11 23:50	78.37	OK
2237	2026-09-11 23:51	81.16	OK	2238	2026-09-11 23:52	80.68	OK
2239	2026-09-11 23:53	80.94	OK	2240	2026-09-11 23:54	81.07	OK
2241	2026-09-11 23:55	79.64	OK	2242	2026-09-11 23:56	81.74	OK
2243	2026-09-11 23:57	81.13	OK	2244	2026-09-11 23:58	81.40	OK
2245	2026-09-11 23:59	82.99	OK	2246	2026-09-12 00:00	79.21	OK
2247	2026-09-12 00:01	81.68	OK	2248	2026-09-12 00:02	82.95	OK
2249	2026-09-12 00:03	79.83	OK	2250	2026-09-12 00:04	82.30	OK
2251	2026-09-12 00:05	79.69	OK	2252	2026-09-12 00:06	81.05	OK
2253	2026-09-12 00:07	77.32	OK	2254	2026-09-12 00:08	79.54	OK
2255	2026-09-12 00:09	80.00	OK	2256	2026-09-12 00:10	78.39	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2257	2026-09-12 00:11	79.89	OK	2258	2026-09-12 00:12	81.92	OK
2259	2026-09-12 00:13	81.35	OK	2260	2026-09-12 00:14	82.79	OK
2261	2026-09-12 00:15	79.52	OK	2262	2026-09-12 00:16	80.74	OK
2263	2026-09-12 00:17	82.57	OK	2264	2026-09-12 00:18	79.34	OK
2265	2026-09-12 00:19	82.26	OK	2266	2026-09-12 00:20	82.92	OK
2267	2026-09-12 00:21	78.97	OK	2268	2026-09-12 00:22	80.11	OK
2269	2026-09-12 00:23	79.86	OK	2270	2026-09-12 00:24	79.49	OK
2271	2026-09-12 00:25	81.05	OK	2272	2026-09-12 00:26	79.79	OK
2273	2026-09-12 00:27	82.28	OK	2274	2026-09-12 00:28	78.04	OK
2275	2026-09-12 00:29	78.68	OK	2276	2026-09-12 00:30	79.02	OK
2277	2026-09-12 00:31	82.05	OK	2278	2026-09-12 00:32	82.66	OK
2279	2026-09-12 00:33	79.66	OK	2280	2026-09-12 00:34	80.76	OK
2281	2026-09-12 00:35	80.43	OK	2282	2026-09-12 00:36	81.50	OK
2283	2026-09-12 00:37	80.55	OK	2284	2026-09-12 00:38	81.34	OK
2285	2026-09-12 00:39	81.25	OK	2286	2026-09-12 00:40	79.38	OK
2287	2026-09-12 00:41	81.04	OK	2288	2026-09-12 00:42	81.24	OK
2289	2026-09-12 00:43	80.07	OK	2290	2026-09-12 00:44	81.12	OK
2291	2026-09-12 00:45	81.44	OK	2292	2026-09-12 00:46	81.77	OK
2293	2026-09-12 00:47	81.71	OK	2294	2026-09-12 00:48	79.85	OK
2295	2026-09-12 00:49	81.48	OK	2296	2026-09-12 00:50	80.26	OK
2297	2026-09-12 00:51	81.10	OK	2298	2026-09-12 00:52	79.16	OK
2299	2026-09-12 00:53	80.23	OK	2300	2026-09-12 00:54	81.44	OK
2301	2026-09-12 00:55	82.41	OK	2302	2026-09-12 00:56	81.64	OK
2303	2026-09-12 00:57	80.29	OK	2304	2026-09-12 00:58	81.53	OK
2305	2026-09-12 00:59	81.26	OK	2306	2026-09-12 01:00	80.36	OK
2307	2026-09-12 01:01	82.86	OK	2308	2026-09-12 01:02	78.98	OK
2309	2026-09-12 01:03	81.88	OK	2310	2026-09-12 01:04	82.82	OK
2311	2026-09-12 01:05	82.30	OK	2312	2026-09-12 01:06	82.91	OK
2313	2026-09-12 01:07	81.82	OK	2314	2026-09-12 01:08	80.41	OK
2315	2026-09-12 01:09	82.33	OK	2316	2026-09-12 01:10	81.34	OK
2317	2026-09-12 01:11	81.03	OK	2318	2026-09-12 01:12	80.30	OK
2319	2026-09-12 01:13	82.02	OK	2320	2026-09-12 01:14	82.36	OK
2321	2026-09-12 01:15	80.93	OK	2322	2026-09-12 01:16	82.22	OK
2323	2026-09-12 01:17	82.23	OK	2324	2026-09-12 01:18	80.83	OK
2325	2026-09-12 01:19	84.15	OK	2326	2026-09-12 01:20	79.90	OK
2327	2026-09-12 01:21	80.33	OK	2328	2026-09-12 01:22	80.86	OK
2329	2026-09-12 01:23	82.57	OK	2330	2026-09-12 01:24	82.95	OK
2331	2026-09-12 01:25	83.93	OK	2332	2026-09-12 01:26	81.19	OK
2333	2026-09-12 01:27	80.87	OK	2334	2026-09-12 01:28	81.33	OK
2335	2026-09-12 01:29	82.62	OK	2336	2026-09-12 01:30	80.69	OK
2337	2026-09-12 01:31	78.29	OK	2338	2026-09-12 01:32	79.19	OK
2339	2026-09-12 01:33	81.54	OK	2340	2026-09-12 01:34	82.17	OK
2341	2026-09-12 01:35	80.19	OK	2342	2026-09-12 01:36	81.27	OK
2343	2026-09-12 01:37	83.20	OK	2344	2026-09-12 01:38	82.78	OK
2345	2026-09-12 01:39	81.07	OK	2346	2026-09-12 01:40	79.47	OK
2347	2026-09-12 01:41	81.73	OK	2348	2026-09-12 01:42	83.07	OK
2349	2026-09-12 01:43	83.24	OK	2350	2026-09-12 01:44	83.28	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2351	2026-09-12 01:45	80.24	OK	2352	2026-09-12 01:46	81.37	OK
2353	2026-09-12 01:47	81.80	OK	2354	2026-09-12 01:48	81.73	OK
2355	2026-09-12 01:49	83.48	OK	2356	2026-09-12 01:50	83.35	OK
2357	2026-09-12 01:51	82.05	OK	2358	2026-09-12 01:52	82.49	OK
2359	2026-09-12 01:53	82.10	OK	2360	2026-09-12 01:54	81.99	OK
2361	2026-09-12 01:55	79.02	OK	2362	2026-09-12 01:56	81.69	OK
2363	2026-09-12 01:57	79.40	OK	2364	2026-09-12 01:58	80.94	OK
2365	2026-09-12 01:59	82.12	OK	2366	2026-09-12 02:00	83.66	OK
2367	2026-09-12 02:01	81.01	OK	2368	2026-09-12 02:02	83.39	OK
2369	2026-09-12 02:03	82.70	OK	2370	2026-09-12 02:04	81.44	OK
2371	2026-09-12 02:05	83.20	OK	2372	2026-09-12 02:06	82.84	OK
2373	2026-09-12 02:07	80.33	OK	2374	2026-09-12 02:08	80.15	OK
2375	2026-09-12 02:09	82.06	OK	2376	2026-09-12 02:10	80.75	OK
2377	2026-09-12 02:11	82.42	OK	2378	2026-09-12 02:12	81.63	OK
2379	2026-09-12 02:13	81.15	OK	2380	2026-09-12 02:14	81.42	OK
2381	2026-09-12 02:15	82.04	OK	2382	2026-09-12 02:16	81.98	OK
2383	2026-09-12 02:17	82.03	OK	2384	2026-09-12 02:18	80.67	OK
2385	2026-09-12 02:19	81.75	OK	2386	2026-09-12 02:20	81.13	OK
2387	2026-09-12 02:21	83.92	OK	2388	2026-09-12 02:22	81.14	OK
2389	2026-09-12 02:23	81.61	OK	2390	2026-09-12 02:24	82.55	OK
2391	2026-09-12 02:25	82.94	OK	2392	2026-09-12 02:26	82.76	OK
2393	2026-09-12 02:27	81.08	OK	2394	2026-09-12 02:28	80.91	OK
2395	2026-09-12 02:29	80.46	OK	2396	2026-09-12 02:30	84.77	OK
2397	2026-09-12 02:31	85.03	OK	2398	2026-09-12 02:32	80.15	OK
2399	2026-09-12 02:33	82.24	OK	2400	2026-09-12 02:34	82.05	OK
2401	2026-09-12 02:35	84.04	OK	2402	2026-09-12 02:36	79.28	OK
2403	2026-09-12 02:37	82.22	OK	2404	2026-09-12 02:38	83.55	OK
2405	2026-09-12 02:39	80.35	OK	2406	2026-09-12 02:40	81.20	OK
2407	2026-09-12 02:41	82.74	OK	2408	2026-09-12 02:42	84.07	OK
2409	2026-09-12 02:43	79.95	OK	2410	2026-09-12 02:44	81.49	OK
2411	2026-09-12 02:45	84.22	OK	2412	2026-09-12 02:46	82.74	OK
2413	2026-09-12 02:47	80.82	OK	2414	2026-09-12 02:48	82.58	OK
2415	2026-09-12 02:49	82.68	OK	2416	2026-09-12 02:50	80.91	OK
2417	2026-09-12 02:51	82.39	OK	2418	2026-09-12 02:52	81.55	OK
2419	2026-09-12 02:53	80.83	OK	2420	2026-09-12 02:54	81.95	OK
2421	2026-09-12 02:55	80.78	OK	2422	2026-09-12 02:56	81.99	OK
2423	2026-09-12 02:57	79.72	OK	2424	2026-09-12 02:58	80.32	OK
2425	2026-09-12 02:59	82.55	OK	2426	2026-09-12 03:00	81.16	OK
2427	2026-09-12 03:01	82.98	OK	2428	2026-09-12 03:02	82.92	OK
2429	2026-09-12 03:03	82.76	OK	2430	2026-09-12 03:04	81.89	OK
2431	2026-09-12 03:05	83.00	OK	2432	2026-09-12 03:06	81.52	OK
2433	2026-09-12 03:07	83.47	OK	2434	2026-09-12 03:08	82.92	OK
2435	2026-09-12 03:09	82.02	OK	2436	2026-09-12 03:10	81.13	OK
2437	2026-09-12 03:11	82.13	OK	2438	2026-09-12 03:12	82.24	OK
2439	2026-09-12 03:13	81.02	OK	2440	2026-09-12 03:14	79.13	OK
2441	2026-09-12 03:15	81.64	OK	2442	2026-09-12 03:16	83.03	OK
2443	2026-09-12 03:17	81.22	OK	2444	2026-09-12 03:18	83.15	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2445	2026-09-12 03:19	84.03	OK	2446	2026-09-12 03:20	81.58	OK
2447	2026-09-12 03:21	81.35	OK	2448	2026-09-12 03:22	83.36	OK
2449	2026-09-12 03:23	79.90	OK	2450	2026-09-12 03:24	81.36	OK
2451	2026-09-12 03:25	82.88	OK	2452	2026-09-12 03:26	82.93	OK
2453	2026-09-12 03:27	81.40	OK	2454	2026-09-12 03:28	81.57	OK
2455	2026-09-12 03:29	81.53	OK	2456	2026-09-12 03:30	79.41	OK
2457	2026-09-12 03:31	82.24	OK	2458	2026-09-12 03:32	80.82	OK
2459	2026-09-12 03:33	80.39	OK	2460	2026-09-12 03:34	80.21	OK
2461	2026-09-12 03:35	79.67	OK	2462	2026-09-12 03:36	80.33	OK
2463	2026-09-12 03:37	81.92	OK	2464	2026-09-12 03:38	84.40	OK
2465	2026-09-12 03:39	80.38	OK	2466	2026-09-12 03:40	81.81	OK
2467	2026-09-12 03:41	83.26	OK	2468	2026-09-12 03:42	79.58	OK
2469	2026-09-12 03:43	81.50	OK	2470	2026-09-12 03:44	83.11	OK
2471	2026-09-12 03:45	79.96	OK	2472	2026-09-12 03:46	80.51	OK
2473	2026-09-12 03:47	80.48	OK	2474	2026-09-12 03:48	82.87	OK
2475	2026-09-12 03:49	84.03	OK	2476	2026-09-12 03:50	82.82	OK
2477	2026-09-12 03:51	79.17	OK	2478	2026-09-12 03:52	82.88	OK
2479	2026-09-12 03:53	81.32	OK	2480	2026-09-12 03:54	82.75	OK
2481	2026-09-12 03:55	81.43	OK	2482	2026-09-12 03:56	82.93	OK
2483	2026-09-12 03:57	81.74	OK	2484	2026-09-12 03:58	84.33	OK
2485	2026-09-12 03:59	82.88	OK	2486	2026-09-12 04:00	79.45	OK
2487	2026-09-12 04:01	83.84	OK	2488	2026-09-12 04:02	83.14	OK
2489	2026-09-12 04:03	82.18	OK	2490	2026-09-12 04:04	83.63	OK
2491	2026-09-12 04:05	82.94	OK	2492	2026-09-12 04:06	81.97	OK
2493	2026-09-12 04:07	83.23	OK	2494	2026-09-12 04:08	81.85	OK
2495	2026-09-12 04:09	79.02	OK	2496	2026-09-12 04:10	81.40	OK
2497	2026-09-12 04:11	82.00	OK	2498	2026-09-12 04:12	81.46	OK
2499	2026-09-12 04:13	81.11	OK	2500	2026-09-12 04:14	83.33	OK
2501	2026-09-12 04:15	81.29	OK	2502	2026-09-12 04:16	81.43	OK
2503	2026-09-12 04:17	80.69	OK	2504	2026-09-12 04:18	79.65	OK
2505	2026-09-12 04:19	82.10	OK	2506	2026-09-12 04:20	80.35	OK
2507	2026-09-12 04:21	80.40	OK	2508	2026-09-12 04:22	80.18	OK
2509	2026-09-12 04:23	81.60	OK	2510	2026-09-12 04:24	82.01	OK
2511	2026-09-12 04:25	82.41	OK	2512	2026-09-12 04:26	80.77	OK
2513	2026-09-12 04:27	82.19	OK	2514	2026-09-12 04:28	81.06	OK
2515	2026-09-12 04:29	82.05	OK	2516	2026-09-12 04:30	82.64	OK
2517	2026-09-12 04:31	80.81	OK	2518	2026-09-12 04:32	83.03	OK
2519	2026-09-12 04:33	80.87	OK	2520	2026-09-12 04:34	82.16	OK
2521	2026-09-12 04:35	81.79	OK	2522	2026-09-12 04:36	81.38	OK
2523	2026-09-12 04:37	82.18	OK	2524	2026-09-12 04:38	82.02	OK
2525	2026-09-12 04:39	79.57	OK	2526	2026-09-12 04:40	81.08	OK
2527	2026-09-12 04:41	80.53	OK	2528	2026-09-12 04:42	78.69	OK
2529	2026-09-12 04:43	81.76	OK	2530	2026-09-12 04:44	81.36	OK
2531	2026-09-12 04:45	79.71	OK	2532	2026-09-12 04:46	81.75	OK
2533	2026-09-12 04:47	82.29	OK	2534	2026-09-12 04:48	82.53	OK
2535	2026-09-12 04:49	80.85	OK	2536	2026-09-12 04:50	81.76	OK
2537	2026-09-12 04:51	82.16	OK	2538	2026-09-12 04:52	80.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2539	2026-09-12 04:53	80.86	OK	2540	2026-09-12 04:54	79.81	OK
2541	2026-09-12 04:55	82.81	OK	2542	2026-09-12 04:56	81.89	OK
2543	2026-09-12 04:57	79.77	OK	2544	2026-09-12 04:58	82.25	OK
2545	2026-09-12 04:59	82.41	OK	2546	2026-09-12 05:00	79.71	OK
2547	2026-09-12 05:01	82.89	OK	2548	2026-09-12 05:02	80.63	OK
2549	2026-09-12 05:03	81.58	OK	2550	2026-09-12 05:04	82.14	OK
2551	2026-09-12 05:05	80.44	OK	2552	2026-09-12 05:06	80.22	OK
2553	2026-09-12 05:07	79.45	OK	2554	2026-09-12 05:08	83.51	OK
2555	2026-09-12 05:09	81.33	OK	2556	2026-09-12 05:10	81.61	OK
2557	2026-09-12 05:11	79.89	OK	2558	2026-09-12 05:12	78.42	OK
2559	2026-09-12 05:13	82.01	OK	2560	2026-09-12 05:14	82.48	OK
2561	2026-09-12 05:15	80.95	OK	2562	2026-09-12 05:16	81.09	OK
2563	2026-09-12 05:17	79.53	OK	2564	2026-09-12 05:18	81.10	OK
2565	2026-09-12 05:19	83.88	OK	2566	2026-09-12 05:20	80.36	OK
2567	2026-09-12 05:21	81.49	OK	2568	2026-09-12 05:22	79.60	OK
2569	2026-09-12 05:23	80.04	OK	2570	2026-09-12 05:24	79.86	OK
2571	2026-09-12 05:25	80.93	OK	2572	2026-09-12 05:26	79.69	OK
2573	2026-09-12 05:27	83.90	OK	2574	2026-09-12 05:28	81.09	OK
2575	2026-09-12 05:29	81.81	OK	2576	2026-09-12 05:30	80.51	OK
2577	2026-09-12 05:31	79.52	OK	2578	2026-09-12 05:32	79.91	OK
2579	2026-09-12 05:33	79.50	OK	2580	2026-09-12 05:34	79.93	OK
2581	2026-09-12 05:35	81.15	OK	2582	2026-09-12 05:36	80.37	OK
2583	2026-09-12 05:37	81.14	OK	2584	2026-09-12 05:38	82.70	OK
2585	2026-09-12 05:39	79.60	OK	2586	2026-09-12 05:40	82.54	OK
2587	2026-09-12 05:41	79.07	OK	2588	2026-09-12 05:42	79.51	OK
2589	2026-09-12 05:43	79.24	OK	2590	2026-09-12 05:44	82.46	OK
2591	2026-09-12 05:45	79.09	OK	2592	2026-09-12 05:46	80.01	OK
2593	2026-09-12 05:47	81.71	OK	2594	2026-09-12 05:48	79.47	OK
2595	2026-09-12 05:49	81.55	OK	2596	2026-09-12 05:50	80.09	OK
2597	2026-09-12 05:51	78.40	OK	2598	2026-09-12 05:52	79.90	OK
2599	2026-09-12 05:53	82.20	OK	2600	2026-09-12 05:54	81.56	OK
2601	2026-09-12 05:55	79.65	OK	2602	2026-09-12 05:56	81.61	OK
2603	2026-09-12 05:57	79.40	OK	2604	2026-09-12 05:58	81.96	OK
2605	2026-09-12 05:59	81.30	OK	2606	2026-09-12 06:00	80.47	OK
2607	2026-09-12 06:01	79.08	OK	2608	2026-09-12 06:02	78.60	OK
2609	2026-09-12 06:03	79.37	OK	2610	2026-09-12 06:04	82.24	OK
2611	2026-09-12 06:05	79.70	OK	2612	2026-09-12 06:06	80.31	OK
2613	2026-09-12 06:07	80.30	OK	2614	2026-09-12 06:08	83.22	OK
2615	2026-09-12 06:09	79.27	OK	2616	2026-09-12 06:10	79.76	OK
2617	2026-09-12 06:11	80.84	OK	2618	2026-09-12 06:12	82.12	OK
2619	2026-09-12 06:13	79.14	OK	2620	2026-09-12 06:14	77.59	OK
2621	2026-09-12 06:15	82.05	OK	2622	2026-09-12 06:16	79.48	OK
2623	2026-09-12 06:17	80.09	OK	2624	2026-09-12 06:18	80.47	OK
2625	2026-09-12 06:19	80.89	OK	2626	2026-09-12 06:20	80.38	OK
2627	2026-09-12 06:21	79.82	OK	2628	2026-09-12 06:22	81.62	OK
2629	2026-09-12 06:23	78.63	OK	2630	2026-09-12 06:24	79.48	OK
2631	2026-09-12 06:25	78.71	OK	2632	2026-09-12 06:26	79.27	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2633	2026-09-12 06:27	79.94	OK	2634	2026-09-12 06:28	79.00	OK
2635	2026-09-12 06:29	77.43	OK	2636	2026-09-12 06:30	76.98	OK
2637	2026-09-12 06:31	76.98	OK	2638	2026-09-12 06:32	80.68	OK
2639	2026-09-12 06:33	77.10	OK	2640	2026-09-12 06:34	77.80	OK
2641	2026-09-12 06:35	77.61	OK	2642	2026-09-12 06:36	79.56	OK
2643	2026-09-12 06:37	77.65	OK	2644	2026-09-12 06:38	78.41	OK
2645	2026-09-12 06:39	79.39	OK	2646	2026-09-12 06:40	76.68	OK
2647	2026-09-12 06:41	80.73	OK	2648	2026-09-12 06:42	78.82	OK
2649	2026-09-12 06:43	79.47	OK	2650	2026-09-12 06:44	76.65	OK
2651	2026-09-12 06:45	79.56	OK	2652	2026-09-12 06:46	79.30	OK
2653	2026-09-12 06:47	78.41	OK	2654	2026-09-12 06:48	79.53	OK
2655	2026-09-12 06:49	80.14	OK	2656	2026-09-12 06:50	76.27	OK
2657	2026-09-12 06:51	76.93	OK	2658	2026-09-12 06:52	80.16	OK
2659	2026-09-12 06:53	80.15	OK	2660	2026-09-12 06:54	78.47	OK
2661	2026-09-12 06:55	77.92	OK	2662	2026-09-12 06:56	79.53	OK
2663	2026-09-12 06:57	79.22	OK	2664	2026-09-12 06:58	80.29	OK
2665	2026-09-12 06:59	77.96	OK	2666	2026-09-12 07:00	81.36	OK
2667	2026-09-12 07:01	79.13	OK	2668	2026-09-12 07:02	78.36	OK
2669	2026-09-12 07:03	78.40	OK	2670	2026-09-12 07:04	78.24	OK
2671	2026-09-12 07:05	80.35	OK	2672	2026-09-12 07:06	77.18	OK
2673	2026-09-12 07:07	80.50	OK	2674	2026-09-12 07:08	78.74	OK
2675	2026-09-12 07:09	78.23	OK	2676	2026-09-12 07:10	78.54	OK
2677	2026-09-12 07:11	79.24	OK	2678	2026-09-12 07:12	77.92	OK
2679	2026-09-12 07:13	78.56	OK	2680	2026-09-12 07:14	79.10	OK
2681	2026-09-12 07:15	77.63	OK	2682	2026-09-12 07:16	77.82	OK
2683	2026-09-12 07:17	79.26	OK	2684	2026-09-12 07:18	78.71	OK
2685	2026-09-12 07:19	77.61	OK	2686	2026-09-12 07:20	76.92	OK
2687	2026-09-12 07:21	78.25	OK	2688	2026-09-12 07:22	77.44	OK
2689	2026-09-12 07:23	76.80	OK	2690	2026-09-12 07:24	78.99	OK
2691	2026-09-12 07:25	77.85	OK	2692	2026-09-12 07:26	76.55	OK
2693	2026-09-12 07:27	77.28	OK	2694	2026-09-12 07:28	76.27	OK
2695	2026-09-12 07:29	77.85	OK	2696	2026-09-12 07:30	79.19	OK
2697	2026-09-12 07:31	78.23	OK	2698	2026-09-12 07:32	77.79	OK
2699	2026-09-12 07:33	78.28	OK	2700	2026-09-12 07:34	80.45	OK
2701	2026-09-12 07:35	76.97	OK	2702	2026-09-12 07:36	77.49	OK
2703	2026-09-12 07:37	78.46	OK	2704	2026-09-12 07:38	77.55	OK
2705	2026-09-12 07:39	77.92	OK	2706	2026-09-12 07:40	76.44	OK
2707	2026-09-12 07:41	77.32	OK	2708	2026-09-12 07:42	77.45	OK
2709	2026-09-12 07:43	79.57	OK	2710	2026-09-12 07:44	77.25	OK
2711	2026-09-12 07:45	77.28	OK	2712	2026-09-12 07:46	76.77	OK
2713	2026-09-12 07:47	75.09	OK	2714	2026-09-12 07:48	77.23	OK
2715	2026-09-12 07:49	78.09	OK	2716	2026-09-12 07:50	77.61	OK
2717	2026-09-12 07:51	76.82	OK	2718	2026-09-12 07:52	77.29	OK
2719	2026-09-12 07:53	77.19	OK	2720	2026-09-12 07:54	76.94	OK
2721	2026-09-12 07:55	75.76	OK	2722	2026-09-12 07:56	78.40	OK
2723	2026-09-12 07:57	76.34	OK	2724	2026-09-12 07:58	78.49	OK
2725	2026-09-12 07:59	75.24	OK	2726	2026-09-12 08:00	77.55	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2727	2026-09-12 08:01	77.90	OK	2728	2026-09-12 08:02	80.82	OK
2729	2026-09-12 08:03	78.65	OK	2730	2026-09-12 08:04	78.96	OK
2731	2026-09-12 08:05	78.15	OK	2732	2026-09-12 08:06	77.28	OK
2733	2026-09-12 08:07	79.24	OK	2734	2026-09-12 08:08	77.63	OK
2735	2026-09-12 08:09	76.86	OK	2736	2026-09-12 08:10	78.02	OK
2737	2026-09-12 08:11	80.65	OK	2738	2026-09-12 08:12	77.35	OK
2739	2026-09-12 08:13	78.02	OK	2740	2026-09-12 08:14	78.57	OK
2741	2026-09-12 08:15	75.99	OK	2742	2026-09-12 08:16	77.81	OK
2743	2026-09-12 08:17	77.58	OK	2744	2026-09-12 08:18	75.86	OK
2745	2026-09-12 08:19	76.98	OK	2746	2026-09-12 08:20	79.78	OK
2747	2026-09-12 08:21	77.44	OK	2748	2026-09-12 08:22	77.11	OK
2749	2026-09-12 08:23	75.89	OK	2750	2026-09-12 08:24	76.09	OK
2751	2026-09-12 08:25	76.60	OK	2752	2026-09-12 08:26	77.12	OK
2753	2026-09-12 08:27	75.18	OK	2754	2026-09-12 08:28	75.45	OK
2755	2026-09-12 08:29	76.86	OK	2756	2026-09-12 08:30	76.82	OK
2757	2026-09-12 08:31	79.65	OK	2758	2026-09-12 08:32	75.37	OK
2759	2026-09-12 08:33	76.31	OK	2760	2026-09-12 08:34	77.08	OK
2761	2026-09-12 08:35	75.78	OK	2762	2026-09-12 08:36	77.25	OK
2763	2026-09-12 08:37	77.24	OK	2764	2026-09-12 08:38	75.42	OK
2765	2026-09-12 08:39	78.63	OK	2766	2026-09-12 08:40	75.21	OK
2767	2026-09-12 08:41	77.02	OK	2768	2026-09-12 08:42	74.79	OK
2769	2026-09-12 08:43	78.17	OK	2770	2026-09-12 08:44	74.14	OK
2771	2026-09-12 08:45	76.25	OK	2772	2026-09-12 08:46	76.03	OK
2773	2026-09-12 08:47	75.62	OK	2774	2026-09-12 08:48	76.68	OK
2775	2026-09-12 08:49	75.39	OK	2776	2026-09-12 08:50	75.69	OK
2777	2026-09-12 08:51	77.24	OK	2778	2026-09-12 08:52	77.52	OK
2779	2026-09-12 08:53	77.91	OK	2780	2026-09-12 08:54	76.42	OK
2781	2026-09-12 08:55	77.45	OK	2782	2026-09-12 08:56	77.21	OK
2783	2026-09-12 08:57	77.67	OK	2784	2026-09-12 08:58	76.46	OK
2785	2026-09-12 08:59	76.93	OK	2786	2026-09-12 09:00	77.44	OK
2787	2026-09-12 09:01	74.74	OK	2788	2026-09-12 09:02	76.21	OK
2789	2026-09-12 09:03	76.79	OK	2790	2026-09-12 09:04	75.68	OK
2791	2026-09-12 09:05	76.29	OK	2792	2026-09-12 09:06	76.20	OK
2793	2026-09-12 09:07	76.98	OK	2794	2026-09-12 09:08	76.60	OK
2795	2026-09-12 09:09	77.14	OK	2796	2026-09-12 09:10	75.87	OK
2797	2026-09-12 09:11	79.06	OK	2798	2026-09-12 09:12	76.02	OK
2799	2026-09-12 09:13	75.33	OK	2800	2026-09-12 09:14	74.94	OK
2801	2026-09-12 09:15	73.80	OK	2802	2026-09-12 09:16	74.21	OK
2803	2026-09-12 09:17	75.09	OK	2804	2026-09-12 09:18	77.17	OK
2805	2026-09-12 09:19	76.98	OK	2806	2026-09-12 09:20	76.86	OK
2807	2026-09-12 09:21	76.94	OK	2808	2026-09-12 09:22	76.26	OK
2809	2026-09-12 09:23	75.03	OK	2810	2026-09-12 09:24	77.19	OK
2811	2026-09-12 09:25	73.82	OK	2812	2026-09-12 09:26	77.09	OK
2813	2026-09-12 09:27	74.05	OK	2814	2026-09-12 09:28	77.41	OK
2815	2026-09-12 09:29	74.90	OK	2816	2026-09-12 09:30	76.62	OK
2817	2026-09-12 09:31	75.78	OK	2818	2026-09-12 09:32	74.39	OK
2819	2026-09-12 09:33	74.54	OK	2820	2026-09-12 09:34	76.23	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2821	2026-09-12 09:35	72.65	OK	2822	2026-09-12 09:36	73.23	OK
2823	2026-09-12 09:37	76.12	OK	2824	2026-09-12 09:38	74.72	OK
2825	2026-09-12 09:39	74.72	OK	2826	2026-09-12 09:40	74.75	OK
2827	2026-09-12 09:41	76.22	OK	2828	2026-09-12 09:42	75.07	OK
2829	2026-09-12 09:43	76.34	OK	2830	2026-09-12 09:44	75.40	OK
2831	2026-09-12 09:45	75.99	OK	2832	2026-09-12 09:46	75.56	OK
2833	2026-09-12 09:47	77.27	OK	2834	2026-09-12 09:48	75.51	OK
2835	2026-09-12 09:49	73.26	OK	2836	2026-09-12 09:50	74.54	OK
2837	2026-09-12 09:51	75.63	OK	2838	2026-09-12 09:52	75.84	OK
2839	2026-09-12 09:53	73.57	OK	2840	2026-09-12 09:54	74.55	OK
2841	2026-09-12 09:55	76.58	OK	2842	2026-09-12 09:56	76.16	OK
2843	2026-09-12 09:57	74.30	OK	2844	2026-09-12 09:58	74.89	OK
2845	2026-09-12 09:59	76.06	OK	2846	2026-09-12 10:00	76.17	OK
2847	2026-09-12 10:01	76.03	OK	2848	2026-09-12 10:02	74.99	OK
2849	2026-09-12 10:03	74.12	OK	2850	2026-09-12 10:04	75.24	OK
2851	2026-09-12 10:05	76.76	OK	2852	2026-09-12 10:06	76.04	OK
2853	2026-09-12 10:07	75.33	OK	2854	2026-09-12 10:08	72.91	OK
2855	2026-09-12 10:09	72.57	OK	2856	2026-09-12 10:10	76.18	OK
2857	2026-09-12 10:11	72.68	OK	2858	2026-09-12 10:12	75.75	OK
2859	2026-09-12 10:13	74.63	OK	2860	2026-09-12 10:14	77.24	OK
2861	2026-09-12 10:15	73.32	OK	2862	2026-09-12 10:16	74.21	OK
2863	2026-09-12 10:17	75.30	OK	2864	2026-09-12 10:18	76.11	OK
2865	2026-09-12 10:19	72.56	OK	2866	2026-09-12 10:20	75.37	OK
2867	2026-09-12 10:21	72.26	OK	2868	2026-09-12 10:22	74.01	OK
2869	2026-09-12 10:23	77.01	OK	2870	2026-09-12 10:24	73.96	OK
2871	2026-09-12 10:25	72.32	OK	2872	2026-09-12 10:26	73.53	OK
2873	2026-09-12 10:27	73.41	OK	2874	2026-09-12 10:28	74.80	OK
2875	2026-09-12 10:29	73.29	OK	2876	2026-09-12 10:30	73.80	OK
2877	2026-09-12 10:31	72.89	OK	2878	2026-09-12 10:32	72.36	OK
2879	2026-09-12 10:33	76.12	OK	2880	2026-09-12 10:34	72.94	OK
2881	2026-09-12 10:35	72.99	OK	2882	2026-09-12 10:36	74.88	OK
2883	2026-09-12 10:37	75.45	OK	2884	2026-09-12 10:38	73.48	OK
2885	2026-09-12 10:39	74.06	OK	2886	2026-09-12 10:40	72.59	OK
2887	2026-09-12 10:41	73.90	OK	2888	2026-09-12 10:42	73.79	OK
2889	2026-09-12 10:43	74.99	OK	2890	2026-09-12 10:44	74.93	OK
2891	2026-09-12 10:45	74.23	OK	2892	2026-09-12 10:46	73.27	OK
2893	2026-09-12 10:47	73.45	OK	2894	2026-09-12 10:48	70.78	OK
2895	2026-09-12 10:49	72.42	OK	2896	2026-09-12 10:50	72.94	OK
2897	2026-09-12 10:51	73.69	OK	2898	2026-09-12 10:52	74.08	OK
2899	2026-09-12 10:53	73.70	OK	2900	2026-09-12 10:54	74.45	OK
2901	2026-09-12 10:55	75.83	OK	2902	2026-09-12 10:56	75.95	OK
2903	2026-09-12 10:57	74.66	OK	2904	2026-09-12 10:58	74.96	OK
2905	2026-09-12 10:59	74.20	OK	2906	2026-09-12 11:00	70.45	OK
2907	2026-09-12 11:01	74.55	OK	2908	2026-09-12 11:02	70.96	OK
2909	2026-09-12 11:03	72.95	OK	2910	2026-09-12 11:04	72.67	OK
2911	2026-09-12 11:05	73.84	OK	2912	2026-09-12 11:06	72.37	OK
2913	2026-09-12 11:07	73.31	OK	2914	2026-09-12 11:08	76.22	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2915	2026-09-12 11:09	72.52	OK	2916	2026-09-12 11:10	73.55	OK
2917	2026-09-12 11:11	73.98	OK	2918	2026-09-12 11:12	73.58	OK
2919	2026-09-12 11:13	73.94	OK	2920	2026-09-12 11:14	73.44	OK
2921	2026-09-12 11:15	71.93	OK	2922	2026-09-12 11:16	73.94	OK
2923	2026-09-12 11:17	72.99	OK	2924	2026-09-12 11:18	73.03	OK
2925	2026-09-12 11:19	72.24	OK	2926	2026-09-12 11:20	73.52	OK
2927	2026-09-12 11:21	71.95	OK	2928	2026-09-12 11:22	73.36	OK
2929	2026-09-12 11:23	76.07	OK	2930	2026-09-12 11:24	72.93	OK
2931	2026-09-12 11:25	74.20	OK	2932	2026-09-12 11:26	73.64	OK
2933	2026-09-12 11:27	72.59	OK	2934	2026-09-12 11:28	73.37	OK
2935	2026-09-12 11:29	72.26	OK	2936	2026-09-12 11:30	73.52	OK
2937	2026-09-12 11:31	71.87	OK	2938	2026-09-12 11:32	70.44	OK
2939	2026-09-12 11:33	74.24	OK	2940	2026-09-12 11:34	72.06	OK
2941	2026-09-12 11:35	71.65	OK	2942	2026-09-12 11:36	72.77	OK
2943	2026-09-12 11:37	74.00	OK	2944	2026-09-12 11:38	75.92	OK
2945	2026-09-12 11:39	72.51	OK	2946	2026-09-12 11:40	73.83	OK
2947	2026-09-12 11:41	74.61	OK	2948	2026-09-12 11:42	73.68	OK
2949	2026-09-12 11:43	72.64	OK	2950	2026-09-12 11:44	71.97	OK
2951	2026-09-12 11:45	72.06	OK	2952	2026-09-12 11:46	74.24	OK
2953	2026-09-12 11:47	73.67	OK	2954	2026-09-12 11:48	73.76	OK
2955	2026-09-12 11:49	73.67	OK	2956	2026-09-12 11:50	70.58	OK
2957	2026-09-12 11:51	71.06	OK	2958	2026-09-12 11:52	73.08	OK
2959	2026-09-12 11:53	72.76	OK	2960	2026-09-12 11:54	71.74	OK
2961	2026-09-12 11:55	73.72	OK	2962	2026-09-12 11:56	72.55	OK
2963	2026-09-12 11:57	70.22	OK	2964	2026-09-12 11:58	72.73	OK
2965	2026-09-12 11:59	74.82	OK	2966	2026-09-12 12:00	72.25	OK
2967	2026-09-12 12:01	73.41	OK	2968	2026-09-12 12:02	73.21	OK
2969	2026-09-12 12:03	72.50	OK	2970	2026-09-12 12:04	71.14	OK
2971	2026-09-12 12:05	74.35	OK	2972	2026-09-12 12:06	72.96	OK
2973	2026-09-12 12:07	73.19	OK	2974	2026-09-12 12:08	72.33	OK
2975	2026-09-12 12:09	73.47	OK	2976	2026-09-12 12:10	72.23	OK
2977	2026-09-12 12:11	71.32	OK	2978	2026-09-12 12:12	72.75	OK
2979	2026-09-12 12:13	72.36	OK	2980	2026-09-12 12:14	71.89	OK
2981	2026-09-12 12:15	70.22	OK	2982	2026-09-12 12:16	72.43	OK
2983	2026-09-12 12:17	71.20	OK	2984	2026-09-12 12:18	70.94	OK
2985	2026-09-12 12:19	71.36	OK	2986	2026-09-12 12:20	72.43	OK
2987	2026-09-12 12:21	71.32	OK	2988	2026-09-12 12:22	74.47	OK
2989	2026-09-12 12:23	72.40	OK	2990	2026-09-12 12:24	71.70	OK
2991	2026-09-12 12:25	72.22	OK	2992	2026-09-12 12:26	72.25	OK
2993	2026-09-12 12:27	71.70	OK	2994	2026-09-12 12:28	72.29	OK
2995	2026-09-12 12:29	70.53	OK	2996	2026-09-12 12:30	72.98	OK
2997	2026-09-12 12:31	72.35	OK	2998	2026-09-12 12:32	71.35	OK
2999	2026-09-12 12:33	70.83	OK	3000	2026-09-12 12:34	73.08	OK
3001	2026-09-12 12:35	71.42	OK	3002	2026-09-12 12:36	68.77	OK
3003	2026-09-12 12:37	71.65	OK	3004	2026-09-12 12:38	72.25	OK
3005	2026-09-12 12:39	72.82	OK	3006	2026-09-12 12:40	73.27	OK
3007	2026-09-12 12:41	72.53	OK	3008	2026-09-12 12:42	75.52	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3009	2026-09-12 12:43	68.84	OK	3010	2026-09-12 12:44	73.31	OK
3011	2026-09-12 12:45	74.38	OK	3012	2026-09-12 12:46	71.85	OK
3013	2026-09-12 12:47	69.40	OK	3014	2026-09-12 12:48	72.71	OK
3015	2026-09-12 12:49	74.00	OK	3016	2026-09-12 12:50	69.97	OK
3017	2026-09-12 12:51	71.34	OK	3018	2026-09-12 12:52	72.53	OK
3019	2026-09-12 12:53	71.47	OK	3020	2026-09-12 12:54	71.30	OK
3021	2026-09-12 12:55	72.06	OK	3022	2026-09-12 12:56	70.99	OK
3023	2026-09-12 12:57	71.61	OK	3024	2026-09-12 12:58	73.67	OK
3025	2026-09-12 12:59	72.10	OK	3026	2026-09-12 13:00	69.12	OK
3027	2026-09-12 13:01	73.28	OK	3028	2026-09-12 13:02	72.32	OK
3029	2026-09-12 13:03	71.43	OK	3030	2026-09-12 13:04	74.35	OK
3031	2026-09-12 13:05	71.13	OK	3032	2026-09-12 13:06	69.30	OK
3033	2026-09-12 13:07	72.07	OK	3034	2026-09-12 13:08	72.11	OK
3035	2026-09-12 13:09	71.89	OK	3036	2026-09-12 13:10	73.02	OK
3037	2026-09-12 13:11	71.27	OK	3038	2026-09-12 13:12	71.64	OK
3039	2026-09-12 13:13	70.35	OK	3040	2026-09-12 13:14	73.59	OK
3041	2026-09-12 13:15	70.80	OK	3042	2026-09-12 13:16	71.95	OK
3043	2026-09-12 13:17	72.01	OK	3044	2026-09-12 13:18	71.41	OK
3045	2026-09-12 13:19	73.36	OK	3046	2026-09-12 13:20	71.10	OK
3047	2026-09-12 13:21	72.45	OK	3048	2026-09-12 13:22	70.56	OK
3049	2026-09-12 13:23	72.46	OK	3050	2026-09-12 13:24	73.85	OK
3051	2026-09-12 13:25	72.68	OK	3052	2026-09-12 13:26	73.16	OK
3053	2026-09-12 13:27	70.01	OK	3054	2026-09-12 13:28	73.75	OK
3055	2026-09-12 13:29	71.73	OK	3056	2026-09-12 13:30	73.39	OK
3057	2026-09-12 13:31	71.99	OK	3058	2026-09-12 13:32	71.47	OK
3059	2026-09-12 13:33	72.81	OK	3060	2026-09-12 13:34	74.06	OK
3061	2026-09-12 13:35	71.38	OK	3062	2026-09-12 13:36	72.04	OK
3063	2026-09-12 13:37	72.36	OK	3064	2026-09-12 13:38	70.24	OK
3065	2026-09-12 13:39	72.82	OK	3066	2026-09-12 13:40	72.17	OK
3067	2026-09-12 13:41	72.11	OK	3068	2026-09-12 13:42	69.54	OK
3069	2026-09-12 13:43	73.36	OK	3070	2026-09-12 13:44	70.90	OK
3071	2026-09-12 13:45	71.38	OK	3072	2026-09-12 13:46	71.38	OK
3073	2026-09-12 13:47	72.50	OK	3074	2026-09-12 13:48	70.56	OK
3075	2026-09-12 13:49	71.48	OK	3076	2026-09-12 13:50	73.61	OK
3077	2026-09-12 13:51	70.15	OK	3078	2026-09-12 13:52	72.58	OK
3079	2026-09-12 13:53	73.39	OK	3080	2026-09-12 13:54	68.71	OK
3081	2026-09-12 13:55	71.05	OK	3082	2026-09-12 13:56	70.48	OK
3083	2026-09-12 13:57	70.77	OK	3084	2026-09-12 13:58	71.10	OK
3085	2026-09-12 13:59	71.40	OK	3086	2026-09-12 14:00	70.00	OK
3087	2026-09-12 14:01	71.42	OK	3088	2026-09-12 14:02	72.24	OK
3089	2026-09-12 14:03	71.80	OK	3090	2026-09-12 14:04	73.54	OK
3091	2026-09-12 14:05	72.48	OK	3092	2026-09-12 14:06	73.72	OK
3093	2026-09-12 14:07	72.62	OK	3094	2026-09-12 14:08	70.94	OK
3095	2026-09-12 14:09	71.60	OK	3096	2026-09-12 14:10	72.34	OK
3097	2026-09-12 14:11	73.77	OK	3098	2026-09-12 14:12	70.64	OK
3099	2026-09-12 14:13	71.48	OK	3100	2026-09-12 14:14	73.80	OK
3101	2026-09-12 14:15	71.80	OK	3102	2026-09-12 14:16	73.38	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3103	2026-09-12 14:17	72.24	OK	3104	2026-09-12 14:18	72.30	OK
3105	2026-09-12 14:19	71.12	OK	3106	2026-09-12 14:20	72.84	OK
3107	2026-09-12 14:21	72.51	OK	3108	2026-09-12 14:22	72.81	OK
3109	2026-09-12 14:23	69.72	OK	3110	2026-09-12 14:24	72.65	OK
3111	2026-09-12 14:25	71.65	OK	3112	2026-09-12 14:26	71.79	OK
3113	2026-09-12 14:27	70.10	OK	3114	2026-09-12 14:28	71.92	OK
3115	2026-09-12 14:29	69.44	OK	3116	2026-09-12 14:30	72.28	OK
3117	2026-09-12 14:31	70.63	OK	3118	2026-09-12 14:32	72.06	OK
3119	2026-09-12 14:33	68.29	OK	3120	2026-09-12 14:34	71.86	OK
3121	2026-09-12 14:35	69.88	OK	3122	2026-09-12 14:36	69.99	OK
3123	2026-09-12 14:37	68.99	OK	3124	2026-09-12 14:38	72.52	OK
3125	2026-09-12 14:39	72.28	OK	3126	2026-09-12 14:40	71.34	OK
3127	2026-09-12 14:41	73.79	OK	3128	2026-09-12 14:42	73.36	OK
3129	2026-09-12 14:43	73.05	OK	3130	2026-09-12 14:44	71.22	OK
3131	2026-09-12 14:45	71.17	OK	3132	2026-09-12 14:46	70.49	OK
3133	2026-09-12 14:47	71.45	OK	3134	2026-09-12 14:48	69.90	OK
3135	2026-09-12 14:49	72.35	OK	3136	2026-09-12 14:50	72.11	OK
3137	2026-09-12 14:51	70.41	OK	3138	2026-09-12 14:52	71.86	OK
3139	2026-09-12 14:53	72.72	OK	3140	2026-09-12 14:54	71.93	OK
3141	2026-09-12 14:55	72.49	OK	3142	2026-09-12 14:56	72.25	OK
3143	2026-09-12 14:57	72.74	OK	3144	2026-09-12 14:58	69.40	OK
3145	2026-09-12 14:59	72.91	OK	3146	2026-09-12 15:00	69.63	OK
3147	2026-09-12 15:01	72.13	OK	3148	2026-09-12 15:02	73.28	OK
3149	2026-09-12 15:03	72.07	OK	3150	2026-09-12 15:04	70.24	OK
3151	2026-09-12 15:05	73.91	OK	3152	2026-09-12 15:06	72.64	OK
3153	2026-09-12 15:07	72.10	OK	3154	2026-09-12 15:08	71.25	OK
3155	2026-09-12 15:09	71.08	OK	3156	2026-09-12 15:10	71.84	OK
3157	2026-09-12 15:11	69.92	OK	3158	2026-09-12 15:12	69.46	OK
3159	2026-09-12 15:13	71.20	OK	3160	2026-09-12 15:14	69.62	OK
3161	2026-09-12 15:15	68.59	OK	3162	2026-09-12 15:16	72.17	OK
3163	2026-09-12 15:17	70.88	OK	3164	2026-09-12 15:18	70.85	OK
3165	2026-09-12 15:19	70.72	OK	3166	2026-09-12 15:20	72.05	OK
3167	2026-09-12 15:21	71.67	OK	3168	2026-09-12 15:22	70.39	OK
3169	2026-09-12 15:23	73.05	OK	3170	2026-09-12 15:24	70.70	OK
3171	2026-09-12 15:25	68.81	OK	3172	2026-09-12 15:26	72.05	OK
3173	2026-09-12 15:27	71.00	OK	3174	2026-09-12 15:28	72.71	OK
3175	2026-09-12 15:29	72.00	OK	3176	2026-09-12 15:30	70.72	OK
3177	2026-09-12 15:31	70.66	OK	3178	2026-09-12 15:32	70.36	OK
3179	2026-09-12 15:33	70.91	OK	3180	2026-09-12 15:34	70.96	OK
3181	2026-09-12 15:35	69.68	OK	3182	2026-09-12 15:36	72.76	OK
3183	2026-09-12 15:37	68.87	OK	3184	2026-09-12 15:38	70.89	OK
3185	2026-09-12 15:39	71.06	OK	3186	2026-09-12 15:40	70.87	OK
3187	2026-09-12 15:41	68.56	OK	3188	2026-09-12 15:42	69.59	OK
3189	2026-09-12 15:43	70.97	OK	3190	2026-09-12 15:44	73.20	OK
3191	2026-09-12 15:45	71.53	OK	3192	2026-09-12 15:46	71.75	OK
3193	2026-09-12 15:47	71.28	OK	3194	2026-09-12 15:48	70.24	OK
3195	2026-09-12 15:49	68.44	OK	3196	2026-09-12 15:50	71.08	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3197	2026-09-12 15:51	72.08	OK	3198	2026-09-12 15:52	71.78	OK
3199	2026-09-12 15:53	69.47	OK	3200	2026-09-12 15:54	72.94	OK
3201	2026-09-12 15:55	70.22	OK	3202	2026-09-12 15:56	70.91	OK
3203	2026-09-12 15:57	72.71	OK	3204	2026-09-12 15:58	72.94	OK
3205	2026-09-12 15:59	71.84	OK	3206	2026-09-12 16:00	72.43	OK
3207	2026-09-12 16:01	71.25	OK	3208	2026-09-12 16:02	72.66	OK
3209	2026-09-12 16:03	71.77	OK	3210	2026-09-12 16:04	72.50	OK
3211	2026-09-12 16:05	70.04	OK	3212	2026-09-12 16:06	71.12	OK
3213	2026-09-12 16:07	70.03	OK	3214	2026-09-12 16:08	71.77	OK
3215	2026-09-12 16:09	70.51	OK	3216	2026-09-12 16:10	69.08	OK
3217	2026-09-12 16:11	71.76	OK	3218	2026-09-12 16:12	71.38	OK
3219	2026-09-12 16:13	73.34	OK	3220	2026-09-12 16:14	71.99	OK
3221	2026-09-12 16:15	70.46	OK	3222	2026-09-12 16:16	72.28	OK
3223	2026-09-12 16:17	73.30	OK	3224	2026-09-12 16:18	73.27	OK
3225	2026-09-12 16:19	72.99	OK	3226	2026-09-12 16:20	72.65	OK
3227	2026-09-12 16:21	72.04	OK	3228	2026-09-12 16:22	71.76	OK
3229	2026-09-12 16:23	70.13	OK	3230	2026-09-12 16:24	70.16	OK
3231	2026-09-12 16:25	70.89	OK	3232	2026-09-12 16:26	74.01	OK
3233	2026-09-12 16:27	70.93	OK	3234	2026-09-12 16:28	70.05	OK
3235	2026-09-12 16:29	71.06	OK	3236	2026-09-12 16:30	72.32	OK
3237	2026-09-12 16:31	71.09	OK	3238	2026-09-12 16:32	72.15	OK
3239	2026-09-12 16:33	71.27	OK	3240	2026-09-12 16:34	71.49	OK
3241	2026-09-12 16:35	71.76	OK	3242	2026-09-12 16:36	70.93	OK
3243	2026-09-12 16:37	71.28	OK	3244	2026-09-12 16:38	71.65	OK
3245	2026-09-12 16:39	74.58	OK	3246	2026-09-12 16:40	70.89	OK
3247	2026-09-12 16:41	69.48	OK	3248	2026-09-12 16:42	70.17	OK
3249	2026-09-12 16:43	72.81	OK	3250	2026-09-12 16:44	74.00	OK
3251	2026-09-12 16:45	70.71	OK	3252	2026-09-12 16:46	75.24	OK
3253	2026-09-12 16:47	71.89	OK	3254	2026-09-12 16:48	72.44	OK
3255	2026-09-12 16:49	72.77	OK	3256	2026-09-12 16:50	70.51	OK
3257	2026-09-12 16:51	73.68	OK	3258	2026-09-12 16:52	72.73	OK
3259	2026-09-12 16:53	71.05	OK	3260	2026-09-12 16:54	69.96	OK
3261	2026-09-12 16:55	73.31	OK	3262	2026-09-12 16:56	72.70	OK
3263	2026-09-12 16:57	74.17	OK	3264	2026-09-12 16:58	71.31	OK
3265	2026-09-12 16:59	70.00	OK	3266	2026-09-12 17:00	71.77	OK
3267	2026-09-12 17:01	72.61	OK	3268	2026-09-12 17:02	70.19	OK
3269	2026-09-12 17:03	73.21	OK	3270	2026-09-12 17:04	71.90	OK
3271	2026-09-12 17:05	71.40	OK	3272	2026-09-12 17:06	70.83	OK
3273	2026-09-12 17:07	71.46	OK	3274	2026-09-12 17:08	72.76	OK
3275	2026-09-12 17:09	73.01	OK	3276	2026-09-12 17:10	73.51	OK
3277	2026-09-12 17:11	69.24	OK	3278	2026-09-12 17:12	72.09	OK
3279	2026-09-12 17:13	68.95	OK	3280	2026-09-12 17:14	71.31	OK
3281	2026-09-12 17:15	75.12	OK	3282	2026-09-12 17:16	72.63	OK
3283	2026-09-12 17:17	71.71	OK	3284	2026-09-12 17:18	72.06	OK
3285	2026-09-12 17:19	73.86	OK	3286	2026-09-12 17:20	73.90	OK
3287	2026-09-12 17:21	74.02	OK	3288	2026-09-12 17:22	73.46	OK
3289	2026-09-12 17:23	73.11	OK	3290	2026-09-12 17:24	74.64	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3291	2026-09-12 17:25	72.38	OK	3292	2026-09-12 17:26	71.34	OK
3293	2026-09-12 17:27	72.57	OK	3294	2026-09-12 17:28	70.36	OK
3295	2026-09-12 17:29	74.13	OK	3296	2026-09-12 17:30	72.54	OK
3297	2026-09-12 17:31	71.92	OK	3298	2026-09-12 17:32	70.37	OK
3299	2026-09-12 17:33	71.32	OK	3300	2026-09-12 17:34	72.97	OK
3301	2026-09-12 17:35	74.27	OK	3302	2026-09-12 17:36	72.53	OK
3303	2026-09-12 17:37	73.71	OK	3304	2026-09-12 17:38	71.11	OK
3305	2026-09-12 17:39	71.68	OK	3306	2026-09-12 17:40	74.10	OK
3307	2026-09-12 17:41	72.90	OK	3308	2026-09-12 17:42	70.98	OK
3309	2026-09-12 17:43	72.33	OK	3310	2026-09-12 17:44	74.17	OK
3311	2026-09-12 17:45	70.19	OK	3312	2026-09-12 17:46	75.63	OK
3313	2026-09-12 17:47	72.81	OK	3314	2026-09-12 17:48	73.58	OK
3315	2026-09-12 17:49	75.06	OK	3316	2026-09-12 17:50	72.17	OK
3317	2026-09-12 17:51	71.35	OK	3318	2026-09-12 17:52	72.48	OK
3319	2026-09-12 17:53	73.01	OK	3320	2026-09-12 17:54	73.28	OK
3321	2026-09-12 17:55	74.52	OK	3322	2026-09-12 17:56	74.28	OK
3323	2026-09-12 17:57	71.51	OK	3324	2026-09-12 17:58	73.85	OK
3325	2026-09-12 17:59	72.76	OK	3326	2026-09-12 18:00	75.33	OK
3327	2026-09-12 18:01	73.82	OK	3328	2026-09-12 18:02	73.29	OK
3329	2026-09-12 18:03	72.03	OK	3330	2026-09-12 18:04	71.16	OK
3331	2026-09-12 18:05	73.53	OK	3332	2026-09-12 18:06	74.46	OK
3333	2026-09-12 18:07	73.28	OK	3334	2026-09-12 18:08	72.46	OK
3335	2026-09-12 18:09	71.77	OK	3336	2026-09-12 18:10	72.63	OK
3337	2026-09-12 18:11	71.91	OK	3338	2026-09-12 18:12	72.45	OK
3339	2026-09-12 18:13	72.32	OK	3340	2026-09-12 18:14	70.60	OK
3341	2026-09-12 18:15	73.37	OK	3342	2026-09-12 18:16	71.66	OK
3343	2026-09-12 18:17	72.06	OK	3344	2026-09-12 18:18	73.57	OK
3345	2026-09-12 18:19	71.59	OK	3346	2026-09-12 18:20	72.53	OK
3347	2026-09-12 18:21	74.62	OK	3348	2026-09-12 18:22	76.18	OK
3349	2026-09-12 18:23	72.71	OK	3350	2026-09-12 18:24	73.17	OK
3351	2026-09-12 18:25	73.01	OK	3352	2026-09-12 18:26	74.14	OK
3353	2026-09-12 18:27	74.50	OK	3354	2026-09-12 18:28	75.61	OK
3355	2026-09-12 18:29	74.48	OK	3356	2026-09-12 18:30	74.79	OK
3357	2026-09-12 18:31	73.63	OK	3358	2026-09-12 18:32	74.60	OK
3359	2026-09-12 18:33	73.81	OK	3360	2026-09-12 18:34	74.11	OK
3361	2026-09-12 18:35	72.00	OK	3362	2026-09-12 18:36	72.24	OK
3363	2026-09-12 18:37	76.09	OK	3364	2026-09-12 18:38	74.78	OK
3365	2026-09-12 18:39	73.39	OK	3366	2026-09-12 18:40	74.39	OK
3367	2026-09-12 18:41	73.57	OK	3368	2026-09-12 18:42	74.28	OK
3369	2026-09-12 18:43	73.54	OK	3370	2026-09-12 18:44	72.55	OK
3371	2026-09-12 18:45	74.75	OK	3372	2026-09-12 18:46	73.77	OK
3373	2026-09-12 18:47	74.80	OK	3374	2026-09-12 18:48	74.36	OK
3375	2026-09-12 18:49	73.35	OK	3376	2026-09-12 18:50	71.17	OK
3377	2026-09-12 18:51	74.16	OK	3378	2026-09-12 18:52	73.69	OK
3379	2026-09-12 18:53	72.27	OK	3380	2026-09-12 18:54	73.87	OK
3381	2026-09-12 18:55	71.61	OK	3382	2026-09-12 18:56	74.51	OK
3383	2026-09-12 18:57	73.35	OK	3384	2026-09-12 18:58	75.90	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3385	2026-09-12 18:59	75.45	OK	3386	2026-09-12 19:00	73.15	OK
3387	2026-09-12 19:01	75.47	OK	3388	2026-09-12 19:02	73.87	OK
3389	2026-09-12 19:03	73.18	OK	3390	2026-09-12 19:04	75.15	OK
3391	2026-09-12 19:05	75.12	OK	3392	2026-09-12 19:06	74.51	OK
3393	2026-09-12 19:07	76.69	OK	3394	2026-09-12 19:08	74.28	OK
3395	2026-09-12 19:09	72.58	OK	3396	2026-09-12 19:10	74.28	OK
3397	2026-09-12 19:11	74.33	OK	3398	2026-09-12 19:12	73.96	OK
3399	2026-09-12 19:13	72.75	OK	3400	2026-09-12 19:14	74.64	OK
3401	2026-09-12 19:15	75.72	OK	3402	2026-09-12 19:16	73.96	OK
3403	2026-09-12 19:17	73.42	OK	3404	2026-09-12 19:18	76.04	OK
3405	2026-09-12 19:19	73.80	OK	3406	2026-09-12 19:20	74.79	OK
3407	2026-09-12 19:21	75.40	OK	3408	2026-09-12 19:22	75.49	OK
3409	2026-09-12 19:23	75.56	OK	3410	2026-09-12 19:24	75.39	OK
3411	2026-09-12 19:25	74.44	OK	3412	2026-09-12 19:26	75.54	OK
3413	2026-09-12 19:27	74.31	OK	3414	2026-09-12 19:28	75.04	OK
3415	2026-09-12 19:29	73.96	OK	3416	2026-09-12 19:30	76.40	OK
3417	2026-09-12 19:31	74.48	OK	3418	2026-09-12 19:32	73.39	OK
3419	2026-09-12 19:33	75.40	OK	3420	2026-09-12 19:34	75.36	OK
3421	2026-09-12 19:35	73.81	OK	3422	2026-09-12 19:36	74.29	OK
3423	2026-09-12 19:37	73.33	OK	3424	2026-09-12 19:38	75.58	OK
3425	2026-09-12 19:39	73.30	OK	3426	2026-09-12 19:40	73.76	OK
3427	2026-09-12 19:41	75.14	OK	3428	2026-09-12 19:42	74.19	OK
3429	2026-09-12 19:43	73.57	OK	3430	2026-09-12 19:44	75.14	OK
3431	2026-09-12 19:45	75.65	OK	3432	2026-09-12 19:46	76.95	OK
3433	2026-09-12 19:47	73.72	OK	3434	2026-09-12 19:48	76.32	OK
3435	2026-09-12 19:49	76.17	OK	3436	2026-09-12 19:50	74.02	OK
3437	2026-09-12 19:51	76.39	OK	3438	2026-09-12 19:52	75.23	OK
3439	2026-09-12 19:53	74.12	OK	3440	2026-09-12 19:54	75.96	OK
3441	2026-09-12 19:55	74.92	OK	3442	2026-09-12 19:56	75.88	OK
3443	2026-09-12 19:57	74.14	OK	3444	2026-09-12 19:58	74.78	OK
3445	2026-09-12 19:59	76.51	OK	3446	2026-09-12 20:00	76.26	OK
3447	2026-09-12 20:01	76.37	OK	3448	2026-09-12 20:02	75.88	OK
3449	2026-09-12 20:03	73.93	OK	3450	2026-09-12 20:04	76.49	OK
3451	2026-09-12 20:05	74.46	OK	3452	2026-09-12 20:06	75.89	OK
3453	2026-09-12 20:07	74.83	OK	3454	2026-09-12 20:08	75.56	OK
3455	2026-09-12 20:09	75.12	OK	3456	2026-09-12 20:10	77.39	OK
3457	2026-09-12 20:11	75.88	OK	3458	2026-09-12 20:12	73.56	OK
3459	2026-09-12 20:13	76.13	OK	3460	2026-09-12 20:14	75.33	OK
3461	2026-09-12 20:15	75.51	OK	3462	2026-09-12 20:16	76.52	OK
3463	2026-09-12 20:17	76.00	OK	3464	2026-09-12 20:18	74.48	OK
3465	2026-09-12 20:19	75.01	OK	3466	2026-09-12 20:20	75.24	OK
3467	2026-09-12 20:21	76.01	OK	3468	2026-09-12 20:22	74.70	OK
3469	2026-09-12 20:23	75.43	OK	3470	2026-09-12 20:24	76.13	OK
3471	2026-09-12 20:25	76.93	OK	3472	2026-09-12 20:26	75.55	OK
3473	2026-09-12 20:27	77.76	OK	3474	2026-09-12 20:28	75.70	OK
3475	2026-09-12 20:29	75.49	OK	3476	2026-09-12 20:30	75.73	OK
3477	2026-09-12 20:31	76.89	OK	3478	2026-09-12 20:32	75.71	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3479	2026-09-12 20:33	76.81	OK	3480	2026-09-12 20:34	76.62	OK
3481	2026-09-12 20:35	77.26	OK	3482	2026-09-12 20:36	77.83	OK
3483	2026-09-12 20:37	76.37	OK	3484	2026-09-12 20:38	74.98	OK
3485	2026-09-12 20:39	76.48	OK	3486	2026-09-12 20:40	77.43	OK
3487	2026-09-12 20:41	76.96	OK	3488	2026-09-12 20:42	76.38	OK
3489	2026-09-12 20:43	75.65	OK	3490	2026-09-12 20:44	77.25	OK
3491	2026-09-12 20:45	75.86	OK	3492	2026-09-12 20:46	75.92	OK
3493	2026-09-12 20:47	77.54	OK	3494	2026-09-12 20:48	77.66	OK
3495	2026-09-12 20:49	75.40	OK	3496	2026-09-12 20:50	75.02	OK
3497	2026-09-12 20:51	78.28	OK	3498	2026-09-12 20:52	75.21	OK
3499	2026-09-12 20:53	77.89	OK	3500	2026-09-12 20:54	76.16	OK
3501	2026-09-12 20:55	78.83	OK	3502	2026-09-12 20:56	75.60	OK
3503	2026-09-12 20:57	76.11	OK	3504	2026-09-12 20:58	74.18	OK
3505	2026-09-12 20:59	78.03	OK	3506	2026-09-12 21:00	79.39	OK
3507	2026-09-12 21:01	76.06	OK	3508	2026-09-12 21:02	74.72	OK
3509	2026-09-12 21:03	76.27	OK	3510	2026-09-12 21:04	76.07	OK
3511	2026-09-12 21:05	78.63	OK	3512	2026-09-12 21:06	78.27	OK
3513	2026-09-12 21:07	78.04	OK	3514	2026-09-12 21:08	78.29	OK
3515	2026-09-12 21:09	78.28	OK	3516	2026-09-12 21:10	76.28	OK
3517	2026-09-12 21:11	75.52	OK	3518	2026-09-12 21:12	76.41	OK
3519	2026-09-12 21:13	74.64	OK	3520	2026-09-12 21:14	78.57	OK
3521	2026-09-12 21:15	75.26	OK	3522	2026-09-12 21:16	78.63	OK
3523	2026-09-12 21:17	78.11	OK	3524	2026-09-12 21:18	77.44	OK
3525	2026-09-12 21:19	77.18	OK	3526	2026-09-12 21:20	77.92	OK
3527	2026-09-12 21:21	75.34	OK	3528	2026-09-12 21:22	79.02	OK
3529	2026-09-12 21:23	74.57	OK	3530	2026-09-12 21:24	78.93	OK
3531	2026-09-12 21:25	77.65	OK	3532	2026-09-12 21:26	75.00	OK
3533	2026-09-12 21:27	76.36	OK	3534	2026-09-12 21:28	78.89	OK
3535	2026-09-12 21:29	76.64	OK	3536	2026-09-12 21:30	79.22	OK
3537	2026-09-12 21:31	78.83	OK	3538	2026-09-12 21:32	78.03	OK
3539	2026-09-12 21:33	78.50	OK	3540	2026-09-12 21:34	77.12	OK
3541	2026-09-12 21:35	76.62	OK	3542	2026-09-12 21:36	76.78	OK
3543	2026-09-12 21:37	78.45	OK	3544	2026-09-12 21:38	75.07	OK
3545	2026-09-12 21:39	80.06	OK	3546	2026-09-12 21:40	78.21	OK
3547	2026-09-12 21:41	79.42	OK	3548	2026-09-12 21:42	76.05	OK
3549	2026-09-12 21:43	78.84	OK	3550	2026-09-12 21:44	78.67	OK
3551	2026-09-12 21:45	75.85	OK	3552	2026-09-12 21:46	77.03	OK
3553	2026-09-12 21:47	78.44	OK	3554	2026-09-12 21:48	78.28	OK
3555	2026-09-12 21:49	77.09	OK	3556	2026-09-12 21:50	77.75	OK
3557	2026-09-12 21:51	78.63	OK	3558	2026-09-12 21:52	78.96	OK
3559	2026-09-12 21:53	76.84	OK	3560	2026-09-12 21:54	77.05	OK
3561	2026-09-12 21:55	78.12	OK	3562	2026-09-12 21:56	78.82	OK
3563	2026-09-12 21:57	79.16	OK	3564	2026-09-12 21:58	76.42	OK
3565	2026-09-12 21:59	78.65	OK	3566	2026-09-12 22:00	76.68	OK
3567	2026-09-12 22:01	78.51	OK	3568	2026-09-12 22:02	77.40	OK
3569	2026-09-12 22:03	78.24	OK	3570	2026-09-12 22:04	77.61	OK
3571	2026-09-12 22:05	77.50	OK	3572	2026-09-12 22:06	77.36	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3573	2026-09-12 22:07	79.66	OK	3574	2026-09-12 22:08	78.12	OK
3575	2026-09-12 22:09	77.39	OK	3576	2026-09-12 22:10	76.13	OK
3577	2026-09-12 22:11	77.11	OK	3578	2026-09-12 22:12	80.24	OK
3579	2026-09-12 22:13	80.12	OK	3580	2026-09-12 22:14	78.08	OK
3581	2026-09-12 22:15	76.74	OK	3582	2026-09-12 22:16	79.80	OK
3583	2026-09-12 22:17	79.10	OK	3584	2026-09-12 22:18	77.62	OK
3585	2026-09-12 22:19	75.95	OK	3586	2026-09-12 22:20	76.02	OK
3587	2026-09-12 22:21	77.70	OK	3588	2026-09-12 22:22	78.10	OK
3589	2026-09-12 22:23	78.20	OK	3590	2026-09-12 22:24	77.00	OK
3591	2026-09-12 22:25	80.58	OK	3592	2026-09-12 22:26	76.95	OK
3593	2026-09-12 22:27	78.46	OK	3594	2026-09-12 22:28	77.95	OK
3595	2026-09-12 22:29	79.40	OK	3596	2026-09-12 22:30	79.84	OK
3597	2026-09-12 22:31	78.54	OK	3598	2026-09-12 22:32	78.24	OK
3599	2026-09-12 22:33	78.74	OK	3600	2026-09-12 22:34	77.71	OK
3601	2026-09-12 22:35	80.13	OK	3602	2026-09-12 22:36	80.07	OK
3603	2026-09-12 22:37	79.62	OK	3604	2026-09-12 22:38	80.00	OK
3605	2026-09-12 22:39	76.46	OK	3606	2026-09-12 22:40	79.13	OK
3607	2026-09-12 22:41	77.47	OK	3608	2026-09-12 22:42	79.58	OK
3609	2026-09-12 22:43	78.33	OK	3610	2026-09-12 22:44	80.58	OK
3611	2026-09-12 22:45	81.06	OK	3612	2026-09-12 22:46	78.33	OK
3613	2026-09-12 22:47	80.96	OK	3614	2026-09-12 22:48	78.16	OK
3615	2026-09-12 22:49	80.44	OK	3616	2026-09-12 22:50	79.37	OK
3617	2026-09-12 22:51	79.66	OK	3618	2026-09-12 22:52	77.81	OK
3619	2026-09-12 22:53	79.24	OK	3620	2026-09-12 22:54	79.06	OK
3621	2026-09-12 22:55	79.99	OK	3622	2026-09-12 22:56	79.37	OK
3623	2026-09-12 22:57	76.67	OK	3624	2026-09-12 22:58	76.98	OK
3625	2026-09-12 22:59	81.44	OK	3626	2026-09-12 23:00	79.97	OK
3627	2026-09-12 23:01	82.23	OK	3628	2026-09-12 23:02	77.06	OK
3629	2026-09-12 23:03	81.46	OK	3630	2026-09-12 23:04	80.11	OK
3631	2026-09-12 23:05	80.29	OK	3632	2026-09-12 23:06	81.15	OK
3633	2026-09-12 23:07	80.44	OK	3634	2026-09-12 23:08	81.41	OK
3635	2026-09-12 23:09	80.57	OK	3636	2026-09-12 23:10	79.30	OK
3637	2026-09-12 23:11	79.54	OK	3638	2026-09-12 23:12	80.88	OK
3639	2026-09-12 23:13	79.12	OK	3640	2026-09-12 23:14	79.10	OK
3641	2026-09-12 23:15	77.40	OK	3642	2026-09-12 23:16	78.53	OK
3643	2026-09-12 23:17	80.61	OK	3644	2026-09-12 23:18	80.90	OK
3645	2026-09-12 23:19	79.22	OK	3646	2026-09-12 23:20	77.85	OK
3647	2026-09-12 23:21	79.86	OK	3648	2026-09-12 23:22	78.58	OK
3649	2026-09-12 23:23	79.39	OK	3650	2026-09-12 23:24	82.39	OK
3651	2026-09-12 23:25	81.66	OK	3652	2026-09-12 23:26	78.48	OK
3653	2026-09-12 23:27	81.12	OK	3654	2026-09-12 23:28	80.47	OK
3655	2026-09-12 23:29	77.34	OK	3656	2026-09-12 23:30	81.76	OK
3657	2026-09-12 23:31	79.87	OK	3658	2026-09-12 23:32	79.24	OK
3659	2026-09-12 23:33	79.28	OK	3660	2026-09-12 23:34	79.31	OK
3661	2026-09-12 23:35	80.62	OK	3662	2026-09-12 23:36	80.87	OK
3663	2026-09-12 23:37	79.35	OK	3664	2026-09-12 23:38	78.91	OK
3665	2026-09-12 23:39	78.99	OK	3666	2026-09-12 23:40	79.94	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3667	2026-09-12 23:41	81.09	OK	3668	2026-09-12 23:42	78.00	OK
3669	2026-09-12 23:43	77.64	OK	3670	2026-09-12 23:44	79.74	OK
3671	2026-09-12 23:45	81.28	OK	3672	2026-09-12 23:46	78.50	OK
3673	2026-09-12 23:47	80.56	OK	3674	2026-09-12 23:48	80.96	OK
3675	2026-09-12 23:49	81.87	OK	3676	2026-09-12 23:50	77.10	OK
3677	2026-09-12 23:51	81.09	OK	3678	2026-09-12 23:52	80.41	OK
3679	2026-09-12 23:53	79.60	OK	3680	2026-09-12 23:54	79.66	OK
3681	2026-09-12 23:55	81.76	OK	3682	2026-09-12 23:56	81.24	OK
3683	2026-09-12 23:57	80.00	OK	3684	2026-09-12 23:58	79.81	OK
3685	2026-09-12 23:59	81.45	OK	3686	2026-09-13 00:00	80.47	OK
3687	2026-09-13 00:01	78.07	OK	3688	2026-09-13 00:02	78.54	OK
3689	2026-09-13 00:03	80.58	OK	3690	2026-09-13 00:04	82.81	OK
3691	2026-09-13 00:05	80.31	OK	3692	2026-09-13 00:06	78.87	OK
3693	2026-09-13 00:07	78.72	OK	3694	2026-09-13 00:08	79.03	OK
3695	2026-09-13 00:09	81.88	OK	3696	2026-09-13 00:10	80.85	OK
3697	2026-09-13 00:11	79.81	OK	3698	2026-09-13 00:12	79.28	OK
3699	2026-09-13 00:13	81.49	OK	3700	2026-09-13 00:14	81.11	OK
3701	2026-09-13 00:15	81.55	OK	3702	2026-09-13 00:16	79.28	OK
3703	2026-09-13 00:17	81.21	OK	3704	2026-09-13 00:18	80.65	OK
3705	2026-09-13 00:19	82.80	OK	3706	2026-09-13 00:20	81.59	OK
3707	2026-09-13 00:21	81.89	OK	3708	2026-09-13 00:22	81.21	OK
3709	2026-09-13 00:23	79.45	OK	3710	2026-09-13 00:24	77.93	OK
3711	2026-09-13 00:25	80.91	OK	3712	2026-09-13 00:26	82.78	OK
3713	2026-09-13 00:27	82.68	OK	3714	2026-09-13 00:28	81.18	OK
3715	2026-09-13 00:29	82.08	OK	3716	2026-09-13 00:30	80.49	OK
3717	2026-09-13 00:31	81.09	OK	3718	2026-09-13 00:32	83.73	OK
3719	2026-09-13 00:33	79.91	OK	3720	2026-09-13 00:34	80.13	OK
3721	2026-09-13 00:35	81.39	OK	3722	2026-09-13 00:36	82.16	OK
3723	2026-09-13 00:37	81.34	OK	3724	2026-09-13 00:38	82.01	OK
3725	2026-09-13 00:39	83.19	OK	3726	2026-09-13 00:40	80.20	OK
3727	2026-09-13 00:41	80.62	OK	3728	2026-09-13 00:42	79.68	OK
3729	2026-09-13 00:43	80.76	OK	3730	2026-09-13 00:44	79.68	OK
3731	2026-09-13 00:45	80.04	OK	3732	2026-09-13 00:46	79.82	OK
3733	2026-09-13 00:47	80.07	OK	3734	2026-09-13 00:48	81.38	OK
3735	2026-09-13 00:49	80.91	OK	3736	2026-09-13 00:50	82.62	OK
3737	2026-09-13 00:51	79.63	OK	3738	2026-09-13 00:52	82.00	OK
3739	2026-09-13 00:53	84.40	OK	3740	2026-09-13 00:54	82.87	OK
3741	2026-09-13 00:55	80.24	OK	3742	2026-09-13 00:56	82.16	OK
3743	2026-09-13 00:57	80.67	OK	3744	2026-09-13 00:58	81.32	OK
3745	2026-09-13 00:59	81.97	OK	3746	2026-09-13 01:00	82.84	OK
3747	2026-09-13 01:01	82.23	OK	3748	2026-09-13 01:02	82.16	OK
3749	2026-09-13 01:03	80.87	OK	3750	2026-09-13 01:04	80.06	OK
3751	2026-09-13 01:05	82.96	OK	3752	2026-09-13 01:06	79.93	OK
3753	2026-09-13 01:07	80.71	OK	3754	2026-09-13 01:08	82.82	OK
3755	2026-09-13 01:09	82.45	OK	3756	2026-09-13 01:10	81.69	OK
3757	2026-09-13 01:11	80.62	OK	3758	2026-09-13 01:12	79.09	OK
3759	2026-09-13 01:13	83.17	OK	3760	2026-09-13 01:14	82.13	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3761	2026-09-13 01:15	80.16	OK	3762	2026-09-13 01:16	79.71	OK
3763	2026-09-13 01:17	79.15	OK	3764	2026-09-13 01:18	81.40	OK
3765	2026-09-13 01:19	81.12	OK	3766	2026-09-13 01:20	81.08	OK
3767	2026-09-13 01:21	80.81	OK	3768	2026-09-13 01:22	80.63	OK
3769	2026-09-13 01:23	80.17	OK	3770	2026-09-13 01:24	81.65	OK
3771	2026-09-13 01:25	79.77	OK	3772	2026-09-13 01:26	80.42	OK
3773	2026-09-13 01:27	80.93	OK	3774	2026-09-13 01:28	82.13	OK
3775	2026-09-13 01:29	80.91	OK	3776	2026-09-13 01:30	80.16	OK
3777	2026-09-13 01:31	80.54	OK	3778	2026-09-13 01:32	81.33	OK
3779	2026-09-13 01:33	80.88	OK	3780	2026-09-13 01:34	82.02	OK
3781	2026-09-13 01:35	82.55	OK	3782	2026-09-13 01:36	81.02	OK
3783	2026-09-13 01:37	82.18	OK	3784	2026-09-13 01:38	82.86	OK
3785	2026-09-13 01:39	81.35	OK	3786	2026-09-13 01:40	81.34	OK
3787	2026-09-13 01:41	81.39	OK	3788	2026-09-13 01:42	81.98	OK
3789	2026-09-13 01:43	82.47	OK	3790	2026-09-13 01:44	79.49	OK
3791	2026-09-13 01:45	82.35	OK	3792	2026-09-13 01:46	80.57	OK
3793	2026-09-13 01:47	82.12	OK	3794	2026-09-13 01:48	80.70	OK
3795	2026-09-13 01:49	82.75	OK	3796	2026-09-13 01:50	81.84	OK
3797	2026-09-13 01:51	81.86	OK	3798	2026-09-13 01:52	80.22	OK
3799	2026-09-13 01:53	80.69	OK	3800	2026-09-13 01:54	79.98	OK
3801	2026-09-13 01:55	80.44	OK	3802	2026-09-13 01:56	80.63	OK
3803	2026-09-13 01:57	82.41	OK	3804	2026-09-13 01:58	79.07	OK
3805	2026-09-13 01:59	83.43	OK	3806	2026-09-13 02:00	81.76	OK
3807	2026-09-13 02:01	80.47	OK	3808	2026-09-13 02:02	79.26	OK
3809	2026-09-13 02:03	80.83	OK	3810	2026-09-13 02:04	80.84	OK
3811	2026-09-13 02:05	81.58	OK	3812	2026-09-13 02:06	81.44	OK
3813	2026-09-13 02:07	82.37	OK	3814	2026-09-13 02:08	80.78	OK
3815	2026-09-13 02:09	81.87	OK	3816	2026-09-13 02:10	82.89	OK
3817	2026-09-13 02:11	80.40	OK	3818	2026-09-13 02:12	80.72	OK
3819	2026-09-13 02:13	83.20	OK	3820	2026-09-13 02:14	82.76	OK
3821	2026-09-13 02:15	81.35	OK	3822	2026-09-13 02:16	79.96	OK
3823	2026-09-13 02:17	82.56	OK	3824	2026-09-13 02:18	82.72	OK
3825	2026-09-13 02:19	84.10	OK	3826	2026-09-13 02:20	81.85	OK
3827	2026-09-13 02:21	80.80	OK	3828	2026-09-13 02:22	83.68	OK
3829	2026-09-13 02:23	83.01	OK	3830	2026-09-13 02:24	81.70	OK
3831	2026-09-13 02:25	83.76	OK	3832	2026-09-13 02:26	81.38	OK
3833	2026-09-13 02:27	85.01	OK	3834	2026-09-13 02:28	83.40	OK
3835	2026-09-13 02:29	81.15	OK	3836	2026-09-13 02:30	81.54	OK
3837	2026-09-13 02:31	83.24	OK	3838	2026-09-13 02:32	83.66	OK
3839	2026-09-13 02:33	83.26	OK	3840	2026-09-13 02:34	82.99	OK
3841	2026-09-13 02:35	80.18	OK	3842	2026-09-13 02:36	82.83	OK
3843	2026-09-13 02:37	79.91	OK	3844	2026-09-13 02:38	82.49	OK
3845	2026-09-13 02:39	80.59	OK	3846	2026-09-13 02:40	84.10	OK
3847	2026-09-13 02:41	81.45	OK	3848	2026-09-13 02:42	81.23	OK
3849	2026-09-13 02:43	81.89	OK	3850	2026-09-13 02:44	82.78	OK
3851	2026-09-13 02:45	82.27	OK	3852	2026-09-13 02:46	81.50	OK
3853	2026-09-13 02:47	83.65	OK	3854	2026-09-13 02:48	84.28	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3855	2026-09-13 02:49	82.39	OK	3856	2026-09-13 02:50	81.83	OK
3857	2026-09-13 02:51	80.64	OK	3858	2026-09-13 02:52	82.14	OK
3859	2026-09-13 02:53	80.91	OK	3860	2026-09-13 02:54	81.79	OK
3861	2026-09-13 02:55	83.02	OK	3862	2026-09-13 02:56	80.84	OK
3863	2026-09-13 02:57	83.21	OK	3864	2026-09-13 02:58	82.73	OK
3865	2026-09-13 02:59	81.26	OK	3866	2026-09-13 03:00	83.71	OK
3867	2026-09-13 03:01	82.32	OK	3868	2026-09-13 03:02	82.90	OK
3869	2026-09-13 03:03	81.68	OK	3870	2026-09-13 03:04	82.24	OK
3871	2026-09-13 03:05	83.79	OK	3872	2026-09-13 03:06	83.74	OK
3873	2026-09-13 03:07	83.54	OK	3874	2026-09-13 03:08	80.53	OK
3875	2026-09-13 03:09	84.20	OK	3876	2026-09-13 03:10	80.78	OK
3877	2026-09-13 03:11	82.04	OK	3878	2026-09-13 03:12	84.29	OK
3879	2026-09-13 03:13	80.67	OK	3880	2026-09-13 03:14	82.32	OK
3881	2026-09-13 03:15	82.19	OK	3882	2026-09-13 03:16	81.29	OK
3883	2026-09-13 03:17	80.62	OK	3884	2026-09-13 03:18	82.36	OK
3885	2026-09-13 03:19	79.75	OK	3886	2026-09-13 03:20	81.01	OK
3887	2026-09-13 03:21	83.19	OK	3888	2026-09-13 03:22	83.91	OK
3889	2026-09-13 03:23	82.83	OK	3890	2026-09-13 03:24	79.39	OK
3891	2026-09-13 03:25	81.45	OK	3892	2026-09-13 03:26	85.19	OK
3893	2026-09-13 03:27	79.26	OK	3894	2026-09-13 03:28	79.20	OK
3895	2026-09-13 03:29	83.16	OK	3896	2026-09-13 03:30	81.38	OK
3897	2026-09-13 03:31	81.53	OK	3898	2026-09-13 03:32	82.42	OK
3899	2026-09-13 03:33	83.10	OK	3900	2026-09-13 03:34	82.32	OK
3901	2026-09-13 03:35	81.78	OK	3902	2026-09-13 03:36	80.09	OK
3903	2026-09-13 03:37	82.20	OK	3904	2026-09-13 03:38	83.56	OK
3905	2026-09-13 03:39	82.16	OK	3906	2026-09-13 03:40	78.90	OK
3907	2026-09-13 03:41	81.31	OK	3908	2026-09-13 03:42	80.29	OK
3909	2026-09-13 03:43	78.89	OK	3910	2026-09-13 03:44	82.57	OK
3911	2026-09-13 03:45	80.84	OK	3912	2026-09-13 03:46	83.24	OK
3913	2026-09-13 03:47	82.52	OK	3914	2026-09-13 03:48	83.25	OK
3915	2026-09-13 03:49	82.89	OK	3916	2026-09-13 03:50	81.42	OK
3917	2026-09-13 03:51	79.93	OK	3918	2026-09-13 03:52	81.30	OK
3919	2026-09-13 03:53	82.74	OK	3920	2026-09-13 03:54	80.72	OK
3921	2026-09-13 03:55	83.09	OK	3922	2026-09-13 03:56	84.01	OK
3923	2026-09-13 03:57	80.68	OK	3924	2026-09-13 03:58	82.50	OK
3925	2026-09-13 03:59	80.35	OK	3926	2026-09-13 04:00	82.58	OK
3927	2026-09-13 04:01	82.19	OK	3928	2026-09-13 04:02	80.70	OK
3929	2026-09-13 04:03	82.79	OK	3930	2026-09-13 04:04	81.71	OK
3931	2026-09-13 04:05	82.01	OK	3932	2026-09-13 04:06	79.77	OK
3933	2026-09-13 04:07	83.66	OK	3934	2026-09-13 04:08	79.77	OK
3935	2026-09-13 04:09	82.61	OK	3936	2026-09-13 04:10	81.50	OK
3937	2026-09-13 04:11	81.04	OK	3938	2026-09-13 04:12	82.11	OK
3939	2026-09-13 04:13	82.62	OK	3940	2026-09-13 04:14	83.19	OK
3941	2026-09-13 04:15	81.59	OK	3942	2026-09-13 04:16	81.37	OK
3943	2026-09-13 04:17	81.24	OK	3944	2026-09-13 04:18	80.08	OK
3945	2026-09-13 04:19	81.79	OK	3946	2026-09-13 04:20	82.14	OK
3947	2026-09-13 04:21	78.73	OK	3948	2026-09-13 04:22	81.77	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3949	2026-09-13 04:23	81.97	OK	3950	2026-09-13 04:24	83.18	OK
3951	2026-09-13 04:25	79.70	OK	3952	2026-09-13 04:26	79.82	OK
3953	2026-09-13 04:27	79.98	OK	3954	2026-09-13 04:28	82.63	OK
3955	2026-09-13 04:29	81.14	OK	3956	2026-09-13 04:30	80.23	OK
3957	2026-09-13 04:31	83.87	OK	3958	2026-09-13 04:32	80.69	OK
3959	2026-09-13 04:33	82.22	OK	3960	2026-09-13 04:34	79.66	OK
3961	2026-09-13 04:35	84.59	OK	3962	2026-09-13 04:36	83.17	OK
3963	2026-09-13 04:37	80.70	OK	3964	2026-09-13 04:38	81.56	OK
3965	2026-09-13 04:39	80.40	OK	3966	2026-09-13 04:40	80.73	OK
3967	2026-09-13 04:41	78.98	OK	3968	2026-09-13 04:42	81.82	OK
3969	2026-09-13 04:43	81.40	OK	3970	2026-09-13 04:44	82.05	OK
3971	2026-09-13 04:45	80.27	OK	3972	2026-09-13 04:46	80.36	OK
3973	2026-09-13 04:47	80.41	OK	3974	2026-09-13 04:48	81.20	OK
3975	2026-09-13 04:49	81.96	OK	3976	2026-09-13 04:50	80.30	OK
3977	2026-09-13 04:51	81.82	OK	3978	2026-09-13 04:52	79.27	OK
3979	2026-09-13 04:53	80.58	OK	3980	2026-09-13 04:54	80.35	OK
3981	2026-09-13 04:55	80.21	OK	3982	2026-09-13 04:56	80.38	OK
3983	2026-09-13 04:57	79.17	OK	3984	2026-09-13 04:58	79.72	OK
3985	2026-09-13 04:59	81.90	OK	3986	2026-09-13 05:00	79.92	OK
3987	2026-09-13 05:01	81.52	OK	3988	2026-09-13 05:02	81.30	OK
3989	2026-09-13 05:03	81.59	OK	3990	2026-09-13 05:04	82.64	OK
3991	2026-09-13 05:05	81.45	OK	3992	2026-09-13 05:06	81.36	OK
3993	2026-09-13 05:07	79.78	OK	3994	2026-09-13 05:08	82.26	OK
3995	2026-09-13 05:09	78.45	OK	3996	2026-09-13 05:10	80.98	OK
3997	2026-09-13 05:11	80.03	OK	3998	2026-09-13 05:12	79.96	OK
3999	2026-09-13 05:13	79.37	OK	4000	2026-09-13 05:14	79.84	OK
4001	2026-09-13 05:15	80.27	OK	4002	2026-09-13 05:16	79.86	OK
4003	2026-09-13 05:17	81.14	OK	4004	2026-09-13 05:18	81.84	OK
4005	2026-09-13 05:19	79.71	OK	4006	2026-09-13 05:20	81.51	OK
4007	2026-09-13 05:21	80.43	OK	4008	2026-09-13 05:22	79.74	OK
4009	2026-09-13 05:23	78.12	OK	4010	2026-09-13 05:24	81.24	OK
4011	2026-09-13 05:25	81.00	OK	4012	2026-09-13 05:26	81.62	OK
4013	2026-09-13 05:27	79.66	OK	4014	2026-09-13 05:28	81.29	OK
4015	2026-09-13 05:29	81.80	OK	4016	2026-09-13 05:30	81.19	OK
4017	2026-09-13 05:31	80.56	OK	4018	2026-09-13 05:32	78.78	OK
4019	2026-09-13 05:33	79.14	OK	4020	2026-09-13 05:34	81.70	OK
4021	2026-09-13 05:35	81.14	OK	4022	2026-09-13 05:36	78.14	OK
4023	2026-09-13 05:37	80.48	OK	4024	2026-09-13 05:38	80.81	OK
4025	2026-09-13 05:39	78.18	OK	4026	2026-09-13 05:40	80.31	OK
4027	2026-09-13 05:41	80.09	OK	4028	2026-09-13 05:42	79.69	OK
4029	2026-09-13 05:43	81.26	OK	4030	2026-09-13 05:44	79.84	OK
4031	2026-09-13 05:45	80.07	OK	4032	2026-09-13 05:46	80.33	OK
4033	2026-09-13 05:47	78.65	OK	4034	2026-09-13 05:48	78.65	OK
4035	2026-09-13 05:49	78.60	OK	4036	2026-09-13 05:50	80.95	OK
4037	2026-09-13 05:51	80.54	OK	4038	2026-09-13 05:52	80.05	OK
4039	2026-09-13 05:53	81.14	OK	4040	2026-09-13 05:54	81.11	OK
4041	2026-09-13 05:55	80.70	OK	4042	2026-09-13 05:56	80.60	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4043	2026-09-13 05:57	79.49	OK	4044	2026-09-13 05:58	82.20	OK
4045	2026-09-13 05:59	78.88	OK	4046	2026-09-13 06:00	77.93	OK
4047	2026-09-13 06:01	81.39	OK	4048	2026-09-13 06:02	80.48	OK
4049	2026-09-13 06:03	78.31	OK	4050	2026-09-13 06:04	80.16	OK
4051	2026-09-13 06:05	81.46	OK	4052	2026-09-13 06:06	80.03	OK
4053	2026-09-13 06:07	81.09	OK	4054	2026-09-13 06:08	81.57	OK
4055	2026-09-13 06:09	81.78	OK	4056	2026-09-13 06:10	78.73	OK
4057	2026-09-13 06:11	79.98	OK	4058	2026-09-13 06:12	81.62	OK
4059	2026-09-13 06:13	80.47	OK	4060	2026-09-13 06:14	80.90	OK
4061	2026-09-13 06:15	82.17	OK	4062	2026-09-13 06:16	78.33	OK
4063	2026-09-13 06:17	82.76	OK	4064	2026-09-13 06:18	81.90	OK
4065	2026-09-13 06:19	79.79	OK	4066	2026-09-13 06:20	79.68	OK
4067	2026-09-13 06:21	79.98	OK	4068	2026-09-13 06:22	79.64	OK
4069	2026-09-13 06:23	80.90	OK	4070	2026-09-13 06:24	78.88	OK
4071	2026-09-13 06:25	79.67	OK	4072	2026-09-13 06:26	79.25	OK
4073	2026-09-13 06:27	79.56	OK	4074	2026-09-13 06:28	81.39	OK
4075	2026-09-13 06:29	81.85	OK	4076	2026-09-13 06:30	77.85	OK
4077	2026-09-13 06:31	82.02	OK	4078	2026-09-13 06:32	80.87	OK
4079	2026-09-13 06:33	78.76	OK	4080	2026-09-13 06:34	81.19	OK
4081	2026-09-13 06:35	80.67	OK	4082	2026-09-13 06:36	79.45	OK
4083	2026-09-13 06:37	79.30	OK	4084	2026-09-13 06:38	80.75	OK
4085	2026-09-13 06:39	79.59	OK	4086	2026-09-13 06:40	76.92	OK
4087	2026-09-13 06:41	80.62	OK	4088	2026-09-13 06:42	78.88	OK
4089	2026-09-13 06:43	79.01	OK	4090	2026-09-13 06:44	77.55	OK
4091	2026-09-13 06:45	77.58	OK	4092	2026-09-13 06:46	79.19	OK
4093	2026-09-13 06:47	78.29	OK	4094	2026-09-13 06:48	78.65	OK
4095	2026-09-13 06:49	77.46	OK	4096	2026-09-13 06:50	78.68	OK
4097	2026-09-13 06:51	79.94	OK	4098	2026-09-13 06:52	78.61	OK
4099	2026-09-13 06:53	77.00	OK	4100	2026-09-13 06:54	78.19	OK
4101	2026-09-13 06:55	79.20	OK	4102	2026-09-13 06:56	80.72	OK
4103	2026-09-13 06:57	79.03	OK	4104	2026-09-13 06:58	78.51	OK
4105	2026-09-13 06:59	80.24	OK	4106	2026-09-13 07:00	79.80	OK
4107	2026-09-13 07:01	78.04	OK	4108	2026-09-13 07:02	77.41	OK
4109	2026-09-13 07:03	79.98	OK	4110	2026-09-13 07:04	77.68	OK
4111	2026-09-13 07:05	77.72	OK	4112	2026-09-13 07:06	78.32	OK
4113	2026-09-13 07:07	79.57	OK	4114	2026-09-13 07:08	76.45	OK
4115	2026-09-13 07:09	79.44	OK	4116	2026-09-13 07:10	78.00	OK
4117	2026-09-13 07:11	78.06	OK	4118	2026-09-13 07:12	78.54	OK
4119	2026-09-13 07:13	77.82	OK	4120	2026-09-13 07:14	80.30	OK
4121	2026-09-13 07:15	77.55	OK	4122	2026-09-13 07:16	77.91	OK
4123	2026-09-13 07:17	76.16	OK	4124	2026-09-13 07:18	79.59	OK
4125	2026-09-13 07:19	79.18	OK	4126	2026-09-13 07:20	78.90	OK
4127	2026-09-13 07:21	80.92	OK	4128	2026-09-13 07:22	77.12	OK
4129	2026-09-13 07:23	79.04	OK	4130	2026-09-13 07:24	77.36	OK
4131	2026-09-13 07:25	77.43	OK	4132	2026-09-13 07:26	77.21	OK
4133	2026-09-13 07:27	80.02	OK	4134	2026-09-13 07:28	78.81	OK
4135	2026-09-13 07:29	77.09	OK	4136	2026-09-13 07:30	78.18	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4137	2026-09-13 07:31	78.38	OK	4138	2026-09-13 07:32	78.68	OK
4139	2026-09-13 07:33	79.60	OK	4140	2026-09-13 07:34	78.04	OK
4141	2026-09-13 07:35	76.43	OK	4142	2026-09-13 07:36	78.28	OK
4143	2026-09-13 07:37	77.90	OK	4144	2026-09-13 07:38	77.84	OK
4145	2026-09-13 07:39	78.04	OK	4146	2026-09-13 07:40	80.62	OK
4147	2026-09-13 07:41	76.96	OK	4148	2026-09-13 07:42	78.59	OK
4149	2026-09-13 07:43	77.55	OK	4150	2026-09-13 07:44	78.32	OK
4151	2026-09-13 07:45	80.34	OK	4152	2026-09-13 07:46	78.00	OK
4153	2026-09-13 07:47	77.22	OK	4154	2026-09-13 07:48	77.53	OK
4155	2026-09-13 07:49	79.67	OK	4156	2026-09-13 07:50	76.28	OK
4157	2026-09-13 07:51	76.53	OK	4158	2026-09-13 07:52	77.89	OK
4159	2026-09-13 07:53	76.78	OK	4160	2026-09-13 07:54	74.93	OK
4161	2026-09-13 07:55	80.23	OK	4162	2026-09-13 07:56	80.27	OK
4163	2026-09-13 07:57	77.03	OK	4164	2026-09-13 07:58	76.46	OK
4165	2026-09-13 07:59	77.86	OK	4166	2026-09-13 08:00	78.55	OK
4167	2026-09-13 08:01	77.68	OK	4168	2026-09-13 08:02	78.91	OK
4169	2026-09-13 08:03	78.38	OK	4170	2026-09-13 08:04	75.54	OK
4171	2026-09-13 08:05	74.47	OK	4172	2026-09-13 08:06	78.79	OK
4173	2026-09-13 08:07	78.36	OK	4174	2026-09-13 08:08	78.45	OK
4175	2026-09-13 08:09	75.35	OK	4176	2026-09-13 08:10	78.04	OK
4177	2026-09-13 08:11	79.55	OK	4178	2026-09-13 08:12	75.13	OK
4179	2026-09-13 08:13	79.73	OK	4180	2026-09-13 08:14	77.02	OK
4181	2026-09-13 08:15	77.42	OK	4182	2026-09-13 08:16	78.53	OK
4183	2026-09-13 08:17	77.76	OK	4184	2026-09-13 08:18	75.87	OK
4185	2026-09-13 08:19	77.17	OK	4186	2026-09-13 08:20	75.69	OK
4187	2026-09-13 08:21	78.47	OK	4188	2026-09-13 08:22	75.72	OK
4189	2026-09-13 08:23	77.12	OK	4190	2026-09-13 08:24	76.82	OK
4191	2026-09-13 08:25	78.35	OK	4192	2026-09-13 08:26	75.06	OK
4193	2026-09-13 08:27	79.21	OK	4194	2026-09-13 08:28	78.52	OK
4195	2026-09-13 08:29	79.06	OK	4196	2026-09-13 08:30	78.78	OK
4197	2026-09-13 08:31	76.34	OK	4198	2026-09-13 08:32	76.68	OK
4199	2026-09-13 08:33	78.24	OK	4200	2026-09-13 08:34	74.06	OK
4201	2026-09-13 08:35	78.95	OK	4202	2026-09-13 08:36	78.68	OK
4203	2026-09-13 08:37	76.66	OK	4204	2026-09-13 08:38	77.58	OK
4205	2026-09-13 08:39	77.42	OK	4206	2026-09-13 08:40	74.69	OK
4207	2026-09-13 08:41	77.91	OK	4208	2026-09-13 08:42	76.66	OK
4209	2026-09-13 08:43	75.53	OK	4210	2026-09-13 08:44	77.19	OK
4211	2026-09-13 08:45	76.65	OK	4212	2026-09-13 08:46	76.90	OK
4213	2026-09-13 08:47	77.50	OK	4214	2026-09-13 08:48	74.84	OK
4215	2026-09-13 08:49	77.58	OK	4216	2026-09-13 08:50	79.03	OK
4217	2026-09-13 08:51	74.01	OK	4218	2026-09-13 08:52	76.30	OK
4219	2026-09-13 08:53	77.15	OK	4220	2026-09-13 08:54	77.94	OK
4221	2026-09-13 08:55	75.79	OK	4222	2026-09-13 08:56	79.38	OK
4223	2026-09-13 08:57	77.79	OK	4224	2026-09-13 08:58	77.20	OK
4225	2026-09-13 08:59	74.96	OK	4226	2026-09-13 09:00	75.01	OK
4227	2026-09-13 09:01	75.69	OK	4228	2026-09-13 09:02	74.00	OK
4229	2026-09-13 09:03	76.74	OK	4230	2026-09-13 09:04	77.31	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4231	2026-09-13 09:05	76.91	OK	4232	2026-09-13 09:06	75.82	OK
4233	2026-09-13 09:07	77.13	OK	4234	2026-09-13 09:08	76.65	OK
4235	2026-09-13 09:09	77.15	OK	4236	2026-09-13 09:10	73.07	OK
4237	2026-09-13 09:11	76.46	OK	4238	2026-09-13 09:12	78.72	OK
4239	2026-09-13 09:13	75.55	OK	4240	2026-09-13 09:14	73.71	OK
4241	2026-09-13 09:15	75.13	OK	4242	2026-09-13 09:16	76.36	OK
4243	2026-09-13 09:17	77.10	OK	4244	2026-09-13 09:18	74.29	OK
4245	2026-09-13 09:19	74.58	OK	4246	2026-09-13 09:20	77.65	OK
4247	2026-09-13 09:21	77.29	OK	4248	2026-09-13 09:22	75.17	OK
4249	2026-09-13 09:23	76.55	OK	4250	2026-09-13 09:24	76.84	OK
4251	2026-09-13 09:25	79.01	OK	4252	2026-09-13 09:26	75.25	OK
4253	2026-09-13 09:27	75.49	OK	4254	2026-09-13 09:28	76.15	OK
4255	2026-09-13 09:29	75.47	OK	4256	2026-09-13 09:30	73.89	OK
4257	2026-09-13 09:31	77.10	OK	4258	2026-09-13 09:32	74.89	OK
4259	2026-09-13 09:33	74.52	OK	4260	2026-09-13 09:34	73.98	OK
4261	2026-09-13 09:35	74.23	OK	4262	2026-09-13 09:36	76.37	OK
4263	2026-09-13 09:37	77.74	OK	4264	2026-09-13 09:38	74.81	OK
4265	2026-09-13 09:39	77.54	OK	4266	2026-09-13 09:40	74.60	OK
4267	2026-09-13 09:41	75.30	OK	4268	2026-09-13 09:42	75.74	OK
4269	2026-09-13 09:43	76.15	OK	4270	2026-09-13 09:44	74.75	OK
4271	2026-09-13 09:45	76.68	OK	4272	2026-09-13 09:46	76.04	OK
4273	2026-09-13 09:47	75.67	OK	4274	2026-09-13 09:48	74.62	OK
4275	2026-09-13 09:49	74.76	OK	4276	2026-09-13 09:50	74.68	OK
4277	2026-09-13 09:51	76.98	OK	4278	2026-09-13 09:52	73.99	OK
4279	2026-09-13 09:53	74.04	OK	4280	2026-09-13 09:54	76.72	OK
4281	2026-09-13 09:55	75.10	OK	4282	2026-09-13 09:56	76.99	OK
4283	2026-09-13 09:57	76.96	OK	4284	2026-09-13 09:58	76.25	OK
4285	2026-09-13 09:59	74.33	OK	4286	2026-09-13 10:00	74.20	OK
4287	2026-09-13 10:01	74.87	OK	4288	2026-09-13 10:02	74.19	OK
4289	2026-09-13 10:03	74.81	OK	4290	2026-09-13 10:04	77.04	OK
4291	2026-09-13 10:05	73.93	OK	4292	2026-09-13 10:06	76.22	OK
4293	2026-09-13 10:07	75.76	OK	4294	2026-09-13 10:08	75.09	OK
4295	2026-09-13 10:09	75.98	OK	4296	2026-09-13 10:10	74.79	OK
4297	2026-09-13 10:11	76.11	OK	4298	2026-09-13 10:12	74.47	OK
4299	2026-09-13 10:13	75.80	OK	4300	2026-09-13 10:14	73.28	OK
4301	2026-09-13 10:15	75.91	OK	4302	2026-09-13 10:16	75.16	OK
4303	2026-09-13 10:17	75.15	OK	4304	2026-09-13 10:18	76.51	OK
4305	2026-09-13 10:19	74.77	OK	4306	2026-09-13 10:20	75.02	OK
4307	2026-09-13 10:21	74.67	OK	4308	2026-09-13 10:22	74.46	OK
4309	2026-09-13 10:23	76.29	OK	4310	2026-09-13 10:24	75.24	OK
4311	2026-09-13 10:25	72.82	OK	4312	2026-09-13 10:26	73.82	OK
4313	2026-09-13 10:27	76.47	OK	4314	2026-09-13 10:28	74.41	OK
4315	2026-09-13 10:29	74.10	OK	4316	2026-09-13 10:30	73.04	OK
4317	2026-09-13 10:31	73.99	OK	4318	2026-09-13 10:32	75.14	OK
4319	2026-09-13 10:33	75.88	OK	4320	2026-09-13 10:34	72.13	OK
4321	2026-09-13 10:35	73.28	OK	4322	2026-09-13 10:36	74.73	OK
4323	2026-09-13 10:37	75.18	OK	4324	2026-09-13 10:38	74.48	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4325	2026-09-13 10:39	74.77	OK	4326	2026-09-13 10:40	74.31	OK
4327	2026-09-13 10:41	73.12	OK	4328	2026-09-13 10:42	73.22	OK
4329	2026-09-13 10:43	73.64	OK	4330	2026-09-13 10:44	74.12	OK
4331	2026-09-13 10:45	76.23	OK	4332	2026-09-13 10:46	72.31	OK
4333	2026-09-13 10:47	74.44	OK	4334	2026-09-13 10:48	75.58	OK
4335	2026-09-13 10:49	72.70	OK	4336	2026-09-13 10:50	75.15	OK
4337	2026-09-13 10:51	76.39	OK	4338	2026-09-13 10:52	72.67	OK
4339	2026-09-13 10:53	74.07	OK	4340	2026-09-13 10:54	72.58	OK
4341	2026-09-13 10:55	74.53	OK	4342	2026-09-13 10:56	75.55	OK
4343	2026-09-13 10:57	73.33	OK	4344	2026-09-13 10:58	73.68	OK
4345	2026-09-13 10:59	72.66	OK	4346	2026-09-13 11:00	75.72	OK
4347	2026-09-13 11:01	75.84	OK	4348	2026-09-13 11:02	74.08	OK
4349	2026-09-13 11:03	75.53	OK	4350	2026-09-13 11:04	71.75	OK
4351	2026-09-13 11:05	71.68	OK	4352	2026-09-13 11:06	71.27	OK
4353	2026-09-13 11:07	75.43	OK	4354	2026-09-13 11:08	74.41	OK
4355	2026-09-13 11:09	75.84	OK	4356	2026-09-13 11:10	70.79	OK
4357	2026-09-13 11:11	72.32	OK	4358	2026-09-13 11:12	74.18	OK
4359	2026-09-13 11:13	73.07	OK	4360	2026-09-13 11:14	72.94	OK
4361	2026-09-13 11:15	73.26	OK	4362	2026-09-13 11:16	71.40	OK
4363	2026-09-13 11:17	74.34	OK	4364	2026-09-13 11:18	74.69	OK
4365	2026-09-13 11:19	74.79	OK	4366	2026-09-13 11:20	73.00	OK
4367	2026-09-13 11:21	71.38	OK	4368	2026-09-13 11:22	75.80	OK
4369	2026-09-13 11:23	73.93	OK	4370	2026-09-13 11:24	74.88	OK
4371	2026-09-13 11:25	71.76	OK	4372	2026-09-13 11:26	72.70	OK
4373	2026-09-13 11:27	71.26	OK	4374	2026-09-13 11:28	73.08	OK
4375	2026-09-13 11:29	72.09	OK	4376	2026-09-13 11:30	73.75	OK
4377	2026-09-13 11:31	72.80	OK	4378	2026-09-13 11:32	72.52	OK
4379	2026-09-13 11:33	73.22	OK	4380	2026-09-13 11:34	73.87	OK
4381	2026-09-13 11:35	73.73	OK	4382	2026-09-13 11:36	72.48	OK
4383	2026-09-13 11:37	71.58	OK	4384	2026-09-13 11:38	72.01	OK
4385	2026-09-13 11:39	70.75	OK	4386	2026-09-13 11:40	71.91	OK
4387	2026-09-13 11:41	72.06	OK	4388	2026-09-13 11:42	70.81	OK
4389	2026-09-13 11:43	75.38	OK	4390	2026-09-13 11:44	71.59	OK
4391	2026-09-13 11:45	70.79	OK	4392	2026-09-13 11:46	73.71	OK
4393	2026-09-13 11:47	73.60	OK	4394	2026-09-13 11:48	70.89	OK
4395	2026-09-13 11:49	70.55	OK	4396	2026-09-13 11:50	72.76	OK
4397	2026-09-13 11:51	72.45	OK	4398	2026-09-13 11:52	76.05	OK
4399	2026-09-13 11:53	72.34	OK	4400	2026-09-13 11:54	71.58	OK
4401	2026-09-13 11:55	71.99	OK	4402	2026-09-13 11:56	72.82	OK
4403	2026-09-13 11:57	72.63	OK	4404	2026-09-13 11:58	71.44	OK
4405	2026-09-13 11:59	74.47	OK	4406	2026-09-13 12:00	73.34	OK
4407	2026-09-13 12:01	74.64	OK	4408	2026-09-13 12:02	73.84	OK
4409	2026-09-13 12:03	71.41	OK	4410	2026-09-13 12:04	71.29	OK
4411	2026-09-13 12:05	72.38	OK	4412	2026-09-13 12:06	72.81	OK
4413	2026-09-13 12:07	73.11	OK	4414	2026-09-13 12:08	73.92	OK
4415	2026-09-13 12:09	74.49	OK	4416	2026-09-13 12:10	72.54	OK
4417	2026-09-13 12:11	70.18	OK	4418	2026-09-13 12:12	71.23	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4419	2026-09-13 12:13	72.38	OK	4420	2026-09-13 12:14	75.61	OK
4421	2026-09-13 12:15	71.59	OK	4422	2026-09-13 12:16	72.95	OK
4423	2026-09-13 12:17	70.64	OK	4424	2026-09-13 12:18	73.26	OK
4425	2026-09-13 12:19	71.33	OK	4426	2026-09-13 12:20	73.55	OK
4427	2026-09-13 12:21	71.80	OK	4428	2026-09-13 12:22	74.13	OK
4429	2026-09-13 12:23	73.15	OK	4430	2026-09-13 12:24	72.56	OK
4431	2026-09-13 12:25	73.97	OK	4432	2026-09-13 12:26	70.04	OK
4433	2026-09-13 12:27	70.53	OK	4434	2026-09-13 12:28	73.75	OK
4435	2026-09-13 12:29	73.29	OK	4436	2026-09-13 12:30	72.58	OK
4437	2026-09-13 12:31	73.41	OK	4438	2026-09-13 12:32	73.61	OK
4439	2026-09-13 12:33	70.48	OK	4440	2026-09-13 12:34	73.20	OK
4441	2026-09-13 12:35	73.40	OK	4442	2026-09-13 12:36	73.06	OK
4443	2026-09-13 12:37	71.87	OK	4444	2026-09-13 12:38	71.51	OK
4445	2026-09-13 12:39	73.00	OK	4446	2026-09-13 12:40	73.62	OK
4447	2026-09-13 12:41	73.48	OK	4448	2026-09-13 12:42	69.70	OK
4449	2026-09-13 12:43	73.77	OK	4450	2026-09-13 12:44	70.72	OK
4451	2026-09-13 12:45	71.15	OK	4452	2026-09-13 12:46	72.25	OK
4453	2026-09-13 12:47	74.00	OK	4454	2026-09-13 12:48	71.79	OK
4455	2026-09-13 12:49	72.30	OK	4456	2026-09-13 12:50	72.16	OK
4457	2026-09-13 12:51	71.24	OK	4458	2026-09-13 12:52	71.48	OK
4459	2026-09-13 12:53	71.93	OK	4460	2026-09-13 12:54	72.34	OK
4461	2026-09-13 12:55	71.59	OK	4462	2026-09-13 12:56	72.32	OK
4463	2026-09-13 12:57	70.13	OK	4464	2026-09-13 12:58	69.09	OK
4465	2026-09-13 12:59	71.57	OK	4466	2026-09-13 13:00	70.64	OK
4467	2026-09-13 13:01	72.08	OK	4468	2026-09-13 13:02	72.91	OK
4469	2026-09-13 13:03	69.86	OK	4470	2026-09-13 13:04	73.00	OK
4471	2026-09-13 13:05	72.05	OK	4472	2026-09-13 13:06	74.82	OK
4473	2026-09-13 13:07	71.56	OK	4474	2026-09-13 13:08	72.25	OK
4475	2026-09-13 13:09	72.90	OK	4476	2026-09-13 13:10	68.82	OK
4477	2026-09-13 13:11	69.97	OK	4478	2026-09-13 13:12	71.72	OK
4479	2026-09-13 13:13	70.37	OK	4480	2026-09-13 13:14	75.04	OK
4481	2026-09-13 13:15	70.21	OK	4482	2026-09-13 13:16	74.79	OK
4483	2026-09-13 13:17	71.52	OK	4484	2026-09-13 13:18	73.12	OK
4485	2026-09-13 13:19	69.98	OK	4486	2026-09-13 13:20	70.90	OK
4487	2026-09-13 13:21	72.16	OK	4488	2026-09-13 13:22	73.31	OK
4489	2026-09-13 13:23	71.19	OK	4490	2026-09-13 13:24	72.03	OK
4491	2026-09-13 13:25	72.47	OK	4492	2026-09-13 13:26	71.20	OK
4493	2026-09-13 13:27	71.21	OK	4494	2026-09-13 13:28	72.68	OK
4495	2026-09-13 13:29	72.00	OK	4496	2026-09-13 13:30	73.93	OK
4497	2026-09-13 13:31	72.99	OK	4498	2026-09-13 13:32	72.69	OK
4499	2026-09-13 13:33	73.62	OK	4500	2026-09-13 13:34	70.81	OK
4501	2026-09-13 13:35	71.83	OK	4502	2026-09-13 13:36	72.10	OK
4503	2026-09-13 13:37	71.01	OK	4504	2026-09-13 13:38	72.46	OK
4505	2026-09-13 13:39	73.14	OK	4506	2026-09-13 13:40	73.70	OK
4507	2026-09-13 13:41	72.19	OK	4508	2026-09-13 13:42	70.70	OK
4509	2026-09-13 13:43	72.62	OK	4510	2026-09-13 13:44	70.12	OK
4511	2026-09-13 13:45	71.41	OK	4512	2026-09-13 13:46	68.49	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4513	2026-09-13 13:47	73.91	OK	4514	2026-09-13 13:48	71.96	OK
4515	2026-09-13 13:49	71.01	OK	4516	2026-09-13 13:50	72.49	OK
4517	2026-09-13 13:51	70.18	OK	4518	2026-09-13 13:52	72.13	OK
4519	2026-09-13 13:53	72.11	OK	4520	2026-09-13 13:54	71.33	OK
4521	2026-09-13 13:55	70.12	OK	4522	2026-09-13 13:56	71.13	OK
4523	2026-09-13 13:57	71.06	OK	4524	2026-09-13 13:58	69.58	OK
4525	2026-09-13 13:59	69.56	OK	4526	2026-09-13 14:00	70.88	OK
4527	2026-09-13 14:01	70.44	OK	4528	2026-09-13 14:02	71.94	OK
4529	2026-09-13 14:03	69.81	OK	4530	2026-09-13 14:04	72.18	OK
4531	2026-09-13 14:05	70.96	OK	4532	2026-09-13 14:06	72.24	OK
4533	2026-09-13 14:07	70.14	OK	4534	2026-09-13 14:08	71.62	OK
4535	2026-09-13 14:09	73.54	OK	4536	2026-09-13 14:10	70.01	OK
4537	2026-09-13 14:11	71.36	OK	4538	2026-09-13 14:12	69.09	OK
4539	2026-09-13 14:13	70.50	OK	4540	2026-09-13 14:14	71.69	OK
4541	2026-09-13 14:15	70.48	OK	4542	2026-09-13 14:16	70.39	OK
4543	2026-09-13 14:17	72.15	OK	4544	2026-09-13 14:18	70.21	OK
4545	2026-09-13 14:19	71.37	OK	4546	2026-09-13 14:20	70.72	OK
4547	2026-09-13 14:21	71.55	OK	4548	2026-09-13 14:22	70.98	OK
4549	2026-09-13 14:23	72.68	OK	4550	2026-09-13 14:24	71.65	OK
4551	2026-09-13 14:25	74.48	OK	4552	2026-09-13 14:26	69.88	OK
4553	2026-09-13 14:27	70.50	OK	4554	2026-09-13 14:28	69.31	OK
4555	2026-09-13 14:29	71.64	OK	4556	2026-09-13 14:30	72.17	OK
4557	2026-09-13 14:31	69.13	OK	4558	2026-09-13 14:32	71.14	OK
4559	2026-09-13 14:33	70.44	OK	4560	2026-09-13 14:34	70.12	OK
4561	2026-09-13 14:35	71.08	OK	4562	2026-09-13 14:36	71.02	OK
4563	2026-09-13 14:37	69.47	OK	4564	2026-09-13 14:38	70.58	OK
4565	2026-09-13 14:39	70.28	OK	4566	2026-09-13 14:40	70.05	OK
4567	2026-09-13 14:41	70.82	OK	4568	2026-09-13 14:42	70.49	OK
4569	2026-09-13 14:43	68.99	OK	4570	2026-09-13 14:44	72.60	OK
4571	2026-09-13 14:45	72.87	OK	4572	2026-09-13 14:46	73.09	OK
4573	2026-09-13 14:47	72.48	OK	4574	2026-09-13 14:48	71.64	OK
4575	2026-09-13 14:49	71.39	OK	4576	2026-09-13 14:50	72.40	OK
4577	2026-09-13 14:51	72.22	OK	4578	2026-09-13 14:52	69.81	OK
4579	2026-09-13 14:53	70.72	OK	4580	2026-09-13 14:54	74.20	OK
4581	2026-09-13 14:55	71.87	OK	4582	2026-09-13 14:56	69.74	OK
4583	2026-09-13 14:57	71.00	OK	4584	2026-09-13 14:58	71.83	OK
4585	2026-09-13 14:59	72.24	OK	4586	2026-09-13 15:00	72.03	OK
4587	2026-09-13 15:01	70.65	OK	4588	2026-09-13 15:02	71.26	OK
4589	2026-09-13 15:03	71.98	OK	4590	2026-09-13 15:04	70.94	OK
4591	2026-09-13 15:05	71.28	OK	4592	2026-09-13 15:06	71.96	OK
4593	2026-09-13 15:07	69.44	OK	4594	2026-09-13 15:08	70.44	OK
4595	2026-09-13 15:09	69.91	OK	4596	2026-09-13 15:10	71.16	OK
4597	2026-09-13 15:11	72.40	OK	4598	2026-09-13 15:12	69.87	OK
4599	2026-09-13 15:13	69.37	OK	4600	2026-09-13 15:14	70.06	OK
4601	2026-09-13 15:15	71.63	OK	4602	2026-09-13 15:16	71.29	OK
4603	2026-09-13 15:17	71.48	OK	4604	2026-09-13 15:18	70.03	OK
4605	2026-09-13 15:19	69.22	OK	4606	2026-09-13 15:20	70.65	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4607	2026-09-13 15:21	72.59	OK	4608	2026-09-13 15:22	71.59	OK
4609	2026-09-13 15:23	70.42	OK	4610	2026-09-13 15:24	72.52	OK
4611	2026-09-13 15:25	71.23	OK	4612	2026-09-13 15:26	73.19	OK
4613	2026-09-13 15:27	71.80	OK	4614	2026-09-13 15:28	70.79	OK
4615	2026-09-13 15:29	70.79	OK	4616	2026-09-13 15:30	71.40	OK
4617	2026-09-13 15:31	68.54	OK	4618	2026-09-13 15:32	72.81	OK
4619	2026-09-13 15:33	72.01	OK	4620	2026-09-13 15:34	72.31	OK
4621	2026-09-13 15:35	69.58	OK	4622	2026-09-13 15:36	71.68	OK
4623	2026-09-13 15:37	71.79	OK	4624	2026-09-13 15:38	70.65	OK
4625	2026-09-13 15:39	69.79	OK	4626	2026-09-13 15:40	70.63	OK
4627	2026-09-13 15:41	72.02	OK	4628	2026-09-13 15:42	73.27	OK
4629	2026-09-13 15:43	74.11	OK	4630	2026-09-13 15:44	71.18	OK
4631	2026-09-13 15:45	71.09	OK	4632	2026-09-13 15:46	69.51	OK
4633	2026-09-13 15:47	70.76	OK	4634	2026-09-13 15:48	72.78	OK
4635	2026-09-13 15:49	70.69	OK	4636	2026-09-13 15:50	72.05	OK
4637	2026-09-13 15:51	71.40	OK	4638	2026-09-13 15:52	70.24	OK
4639	2026-09-13 15:53	70.02	OK	4640	2026-09-13 15:54	72.40	OK
4641	2026-09-13 15:55	73.31	OK	4642	2026-09-13 15:56	71.14	OK
4643	2026-09-13 15:57	70.97	OK	4644	2026-09-13 15:58	70.88	OK
4645	2026-09-13 15:59	72.98	OK	4646	2026-09-13 16:00	73.76	OK
4647	2026-09-13 16:01	72.09	OK	4648	2026-09-13 16:02	70.15	OK
4649	2026-09-13 16:03	74.28	OK	4650	2026-09-13 16:04	71.87	OK
4651	2026-09-13 16:05	73.05	OK	4652	2026-09-13 16:06	71.38	OK
4653	2026-09-13 16:07	73.01	OK	4654	2026-09-13 16:08	70.88	OK
4655	2026-09-13 16:09	72.59	OK	4656	2026-09-13 16:10	71.95	OK
4657	2026-09-13 16:11	69.27	OK	4658	2026-09-13 16:12	73.45	OK
4659	2026-09-13 16:13	70.13	OK	4660	2026-09-13 16:14	70.87	OK
4661	2026-09-13 16:15	71.33	OK	4662	2026-09-13 16:16	72.06	OK
4663	2026-09-13 16:17	72.52	OK	4664	2026-09-13 16:18	73.87	OK
4665	2026-09-13 16:19	73.87	OK	4666	2026-09-13 16:20	70.03	OK
4667	2026-09-13 16:21	70.70	OK	4668	2026-09-13 16:22	69.61	OK
4669	2026-09-13 16:23	71.85	OK	4670	2026-09-13 16:24	71.97	OK
4671	2026-09-13 16:25	70.46	OK	4672	2026-09-13 16:26	73.15	OK
4673	2026-09-13 16:27	72.65	OK	4674	2026-09-13 16:28	72.51	OK
4675	2026-09-13 16:29	71.66	OK	4676	2026-09-13 16:30	70.78	OK
4677	2026-09-13 16:31	73.37	OK	4678	2026-09-13 16:32	71.43	OK
4679	2026-09-13 16:33	72.38	OK	4680	2026-09-13 16:34	71.29	OK
4681	2026-09-13 16:35	71.54	OK	4682	2026-09-13 16:36	70.28	OK
4683	2026-09-13 16:37	71.65	OK	4684	2026-09-13 16:38	71.79	OK
4685	2026-09-13 16:39	72.87	OK	4686	2026-09-13 16:40	72.11	OK
4687	2026-09-13 16:41	70.02	OK	4688	2026-09-13 16:42	73.78	OK
4689	2026-09-13 16:43	71.57	OK	4690	2026-09-13 16:44	71.76	OK
4691	2026-09-13 16:45	75.01	OK	4692	2026-09-13 16:46	72.80	OK
4693	2026-09-13 16:47	69.66	OK	4694	2026-09-13 16:48	70.54	OK
4695	2026-09-13 16:49	73.30	OK	4696	2026-09-13 16:50	71.67	OK
4697	2026-09-13 16:51	71.15	OK	4698	2026-09-13 16:52	73.58	OK
4699	2026-09-13 16:53	71.62	OK	4700	2026-09-13 16:54	72.61	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4701	2026-09-13 16:55	71.82	OK	4702	2026-09-13 16:56	71.81	OK
4703	2026-09-13 16:57	70.92	OK	4704	2026-09-13 16:58	71.79	OK
4705	2026-09-13 16:59	73.10	OK	4706	2026-09-13 17:00	71.24	OK
4707	2026-09-13 17:01	71.77	OK	4708	2026-09-13 17:02	73.10	OK
4709	2026-09-13 17:03	70.56	OK	4710	2026-09-13 17:04	72.06	OK
4711	2026-09-13 17:05	73.40	OK	4712	2026-09-13 17:06	74.63	OK
4713	2026-09-13 17:07	70.57	OK	4714	2026-09-13 17:08	71.02	OK
4715	2026-09-13 17:09	70.51	OK	4716	2026-09-13 17:10	71.17	OK
4717	2026-09-13 17:11	72.21	OK	4718	2026-09-13 17:12	71.57	OK
4719	2026-09-13 17:13	71.06	OK	4720	2026-09-13 17:14	73.00	OK
4721	2026-09-13 17:15	73.72	OK	4722	2026-09-13 17:16	70.90	OK
4723	2026-09-13 17:17	71.90	OK	4724	2026-09-13 17:18	72.45	OK
4725	2026-09-13 17:19	72.90	OK	4726	2026-09-13 17:20	70.53	OK
4727	2026-09-13 17:21	74.05	OK	4728	2026-09-13 17:22	70.58	OK
4729	2026-09-13 17:23	69.37	OK	4730	2026-09-13 17:24	74.48	OK
4731	2026-09-13 17:25	71.55	OK	4732	2026-09-13 17:26	71.25	OK
4733	2026-09-13 17:27	72.58	OK	4734	2026-09-13 17:28	72.40	OK
4735	2026-09-13 17:29	72.73	OK	4736	2026-09-13 17:30	74.30	OK
4737	2026-09-13 17:31	71.68	OK	4738	2026-09-13 17:32	73.09	OK
4739	2026-09-13 17:33	72.38	OK	4740	2026-09-13 17:34	73.48	OK
4741	2026-09-13 17:35	72.35	OK	4742	2026-09-13 17:36	73.49	OK
4743	2026-09-13 17:37	72.70	OK	4744	2026-09-13 17:38	72.22	OK
4745	2026-09-13 17:39	74.04	OK	4746	2026-09-13 17:40	71.25	OK
4747	2026-09-13 17:41	74.39	OK	4748	2026-09-13 17:42	72.49	OK
4749	2026-09-13 17:43	73.82	OK	4750	2026-09-13 17:44	74.68	OK
4751	2026-09-13 17:45	71.81	OK	4752	2026-09-13 17:46	72.49	OK
4753	2026-09-13 17:47	71.56	OK	4754	2026-09-13 17:48	73.12	OK
4755	2026-09-13 17:49	70.32	OK	4756	2026-09-13 17:50	71.67	OK
4757	2026-09-13 17:51	73.36	OK	4758	2026-09-13 17:52	75.21	OK
4759	2026-09-13 17:53	72.37	OK	4760	2026-09-13 17:54	73.03	OK
4761	2026-09-13 17:55	73.54	OK	4762	2026-09-13 17:56	70.34	OK
4763	2026-09-13 17:57	72.72	OK	4764	2026-09-13 17:58	73.32	OK
4765	2026-09-13 17:59	74.35	OK	4766	2026-09-13 18:00	73.48	OK
4767	2026-09-13 18:01	71.95	OK	4768	2026-09-13 18:02	72.75	OK
4769	2026-09-13 18:03	71.65	OK	4770	2026-09-13 18:04	71.41	OK
4771	2026-09-13 18:05	70.59	OK	4772	2026-09-13 18:06	73.34	OK
4773	2026-09-13 18:07	72.82	OK	4774	2026-09-13 18:08	71.93	OK
4775	2026-09-13 18:09	72.18	OK	4776	2026-09-13 18:10	73.39	OK
4777	2026-09-13 18:11	71.56	OK	4778	2026-09-13 18:12	71.54	OK
4779	2026-09-13 18:13	70.78	OK	4780	2026-09-13 18:14	70.48	OK
4781	2026-09-13 18:15	71.95	OK	4782	2026-09-13 18:16	72.66	OK
4783	2026-09-13 18:17	72.54	OK	4784	2026-09-13 18:18	72.04	OK
4785	2026-09-13 18:19	74.73	OK	4786	2026-09-13 18:20	72.31	OK
4787	2026-09-13 18:21	73.17	OK	4788	2026-09-13 18:22	70.51	OK
4789	2026-09-13 18:23	72.27	OK	4790	2026-09-13 18:24	70.04	OK
4791	2026-09-13 18:25	75.32	OK	4792	2026-09-13 18:26	72.93	OK
4793	2026-09-13 18:27	74.35	OK	4794	2026-09-13 18:28	72.68	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4795	2026-09-13 18:29	74.98	OK	4796	2026-09-13 18:30	76.69	OK
4797	2026-09-13 18:31	75.24	OK	4798	2026-09-13 18:32	74.49	OK
4799	2026-09-13 18:33	75.31	OK	4800	2026-09-13 18:34	73.58	OK
4801	2026-09-13 18:35	73.49	OK	4802	2026-09-13 18:36	74.64	OK
4803	2026-09-13 18:37	75.16	OK	4804	2026-09-13 18:38	73.79	OK
4805	2026-09-13 18:39	69.92	OK	4806	2026-09-13 18:40	74.14	OK
4807	2026-09-13 18:41	73.39	OK	4808	2026-09-13 18:42	72.06	OK
4809	2026-09-13 18:43	72.11	OK	4810	2026-09-13 18:44	73.65	OK
4811	2026-09-13 18:45	73.22	OK	4812	2026-09-13 18:46	74.66	OK
4813	2026-09-13 18:47	74.04	OK	4814	2026-09-13 18:48	71.85	OK
4815	2026-09-13 18:49	74.38	OK	4816	2026-09-13 18:50	75.44	OK
4817	2026-09-13 18:51	73.31	OK	4818	2026-09-13 18:52	72.24	OK
4819	2026-09-13 18:53	75.96	OK	4820	2026-09-13 18:54	74.67	OK
4821	2026-09-13 18:55	74.21	OK	4822	2026-09-13 18:56	73.55	OK
4823	2026-09-13 18:57	74.52	OK	4824	2026-09-13 18:58	73.11	OK
4825	2026-09-13 18:59	74.19	OK	4826	2026-09-13 19:00	76.01	OK
4827	2026-09-13 19:01	72.92	OK	4828	2026-09-13 19:02	73.14	OK
4829	2026-09-13 19:03	74.60	OK	4830	2026-09-13 19:04	73.20	OK
4831	2026-09-13 19:05	73.11	OK	4832	2026-09-13 19:06	74.41	OK
4833	2026-09-13 19:07	75.13	OK	4834	2026-09-13 19:08	73.35	OK
4835	2026-09-13 19:09	73.18	OK	4836	2026-09-13 19:10	74.88	OK
4837	2026-09-13 19:11	73.74	OK	4838	2026-09-13 19:12	73.43	OK
4839	2026-09-13 19:13	71.90	OK	4840	2026-09-13 19:14	73.85	OK
4841	2026-09-13 19:15	74.94	OK	4842	2026-09-13 19:16	73.34	OK
4843	2026-09-13 19:17	77.28	OK	4844	2026-09-13 19:18	75.06	OK
4845	2026-09-13 19:19	72.89	OK	4846	2026-09-13 19:20	73.36	OK
4847	2026-09-13 19:21	75.45	OK	4848	2026-09-13 19:22	75.29	OK
4849	2026-09-13 19:23	76.59	OK	4850	2026-09-13 19:24	73.39	OK
4851	2026-09-13 19:25	74.32	OK	4852	2026-09-13 19:26	73.44	OK
4853	2026-09-13 19:27	73.66	OK	4854	2026-09-13 19:28	74.01	OK
4855	2026-09-13 19:29	74.58	OK	4856	2026-09-13 19:30	72.60	OK
4857	2026-09-13 19:31	76.26	OK	4858	2026-09-13 19:32	74.76	OK
4859	2026-09-13 19:33	75.71	OK	4860	2026-09-13 19:34	77.01	OK
4861	2026-09-13 19:35	75.70	OK	4862	2026-09-13 19:36	75.24	OK
4863	2026-09-13 19:37	75.90	OK	4864	2026-09-13 19:38	76.11	OK
4865	2026-09-13 19:39	73.61	OK	4866	2026-09-13 19:40	74.12	OK
4867	2026-09-13 19:41	75.06	OK	4868	2026-09-13 19:42	75.97	OK
4869	2026-09-13 19:43	78.15	OK	4870	2026-09-13 19:44	75.74	OK
4871	2026-09-13 19:45	77.25	OK	4872	2026-09-13 19:46	76.00	OK
4873	2026-09-13 19:47	73.17	OK	4874	2026-09-13 19:48	74.96	OK
4875	2026-09-13 19:49	75.40	OK	4876	2026-09-13 19:50	73.86	OK
4877	2026-09-13 19:51	76.70	OK	4878	2026-09-13 19:52	75.46	OK
4879	2026-09-13 19:53	75.62	OK	4880	2026-09-13 19:54	76.56	OK
4881	2026-09-13 19:55	75.36	OK	4882	2026-09-13 19:56	75.31	OK
4883	2026-09-13 19:57	73.89	OK	4884	2026-09-13 19:58	74.62	OK
4885	2026-09-13 19:59	76.06	OK	4886	2026-09-13 20:00	75.33	OK
4887	2026-09-13 20:01	74.01	OK	4888	2026-09-13 20:02	72.60	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4889	2026-09-13 20:03	74.31	OK	4890	2026-09-13 20:04	74.25	OK
4891	2026-09-13 20:05	75.99	OK	4892	2026-09-13 20:06	76.84	OK
4893	2026-09-13 20:07	74.00	OK	4894	2026-09-13 20:08	73.92	OK
4895	2026-09-13 20:09	76.55	OK	4896	2026-09-13 20:10	76.95	OK
4897	2026-09-13 20:11	75.74	OK	4898	2026-09-13 20:12	74.79	OK
4899	2026-09-13 20:13	76.57	OK	4900	2026-09-13 20:14	74.68	OK
4901	2026-09-13 20:15	76.63	OK	4902	2026-09-13 20:16	75.89	OK
4903	2026-09-13 20:17	76.42	OK	4904	2026-09-13 20:18	74.01	OK
4905	2026-09-13 20:19	76.85	OK	4906	2026-09-13 20:20	75.74	OK
4907	2026-09-13 20:21	77.61	OK	4908	2026-09-13 20:22	74.75	OK
4909	2026-09-13 20:23	74.82	OK	4910	2026-09-13 20:24	76.28	OK
4911	2026-09-13 20:25	75.16	OK	4912	2026-09-13 20:26	77.18	OK
4913	2026-09-13 20:27	74.91	OK	4914	2026-09-13 20:28	77.02	OK
4915	2026-09-13 20:29	77.17	OK	4916	2026-09-13 20:30	74.25	OK
4917	2026-09-13 20:31	76.28	OK	4918	2026-09-13 20:32	74.80	OK
4919	2026-09-13 20:33	74.82	OK	4920	2026-09-13 20:34	77.64	OK
4921	2026-09-13 20:35	76.54	OK	4922	2026-09-13 20:36	78.48	OK
4923	2026-09-13 20:37	77.53	OK	4924	2026-09-13 20:38	77.90	OK
4925	2026-09-13 20:39	75.26	OK	4926	2026-09-13 20:40	73.78	OK
4927	2026-09-13 20:41	75.39	OK	4928	2026-09-13 20:42	73.90	OK
4929	2026-09-13 20:43	78.09	OK	4930	2026-09-13 20:44	76.84	OK
4931	2026-09-13 20:45	74.65	OK	4932	2026-09-13 20:46	77.64	OK
4933	2026-09-13 20:47	77.66	OK	4934	2026-09-13 20:48	75.65	OK
4935	2026-09-13 20:49	78.36	OK	4936	2026-09-13 20:50	74.40	OK
4937	2026-09-13 20:51	78.22	OK	4938	2026-09-13 20:52	74.91	OK
4939	2026-09-13 20:53	76.47	OK	4940	2026-09-13 20:54	75.38	OK
4941	2026-09-13 20:55	77.32	OK	4942	2026-09-13 20:56	75.08	OK
4943	2026-09-13 20:57	77.69	OK	4944	2026-09-13 20:58	76.39	OK
4945	2026-09-13 20:59	76.08	OK	4946	2026-09-13 21:00	76.63	OK
4947	2026-09-13 21:01	78.18	OK	4948	2026-09-13 21:02	75.92	OK
4949	2026-09-13 21:03	76.56	OK	4950	2026-09-13 21:04	76.39	OK
4951	2026-09-13 21:05	78.40	OK	4952	2026-09-13 21:06	77.20	OK
4953	2026-09-13 21:07	77.44	OK	4954	2026-09-13 21:08	76.14	OK
4955	2026-09-13 21:09	76.34	OK	4956	2026-09-13 21:10	79.05	OK
4957	2026-09-13 21:11	78.10	OK	4958	2026-09-13 21:12	75.96	OK
4959	2026-09-13 21:13	76.29	OK	4960	2026-09-13 21:14	77.59	OK
4961	2026-09-13 21:15	77.89	OK	4962	2026-09-13 21:16	79.39	OK
4963	2026-09-13 21:17	76.20	OK	4964	2026-09-13 21:18	77.72	OK
4965	2026-09-13 21:19	76.52	OK	4966	2026-09-13 21:20	78.40	OK
4967	2026-09-13 21:21	76.44	OK	4968	2026-09-13 21:22	78.07	OK
4969	2026-09-13 21:23	77.84	OK	4970	2026-09-13 21:24	77.98	OK
4971	2026-09-13 21:25	79.17	OK	4972	2026-09-13 21:26	79.04	OK
4973	2026-09-13 21:27	75.68	OK	4974	2026-09-13 21:28	77.87	OK
4975	2026-09-13 21:29	78.31	OK	4976	2026-09-13 21:30	77.15	OK
4977	2026-09-13 21:31	78.46	OK	4978	2026-09-13 21:32	74.59	OK
4979	2026-09-13 21:33	76.43	OK	4980	2026-09-13 21:34	77.79	OK
4981	2026-09-13 21:35	76.44	OK	4982	2026-09-13 21:36	79.60	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4983	2026-09-13 21:37	77.82	OK	4984	2026-09-13 21:38	76.11	OK
4985	2026-09-13 21:39	77.66	OK	4986	2026-09-13 21:40	77.50	OK
4987	2026-09-13 21:41	76.74	OK	4988	2026-09-13 21:42	76.09	OK
4989	2026-09-13 21:43	79.42	OK	4990	2026-09-13 21:44	77.33	OK
4991	2026-09-13 21:45	78.07	OK	4992	2026-09-13 21:46	78.10	OK
4993	2026-09-13 21:47	77.77	OK	4994	2026-09-13 21:48	78.26	OK
4995	2026-09-13 21:49	77.54	OK	4996	2026-09-13 21:50	77.55	OK
4997	2026-09-13 21:51	77.42	OK	4998	2026-09-13 21:52	78.43	OK
4999	2026-09-13 21:53	77.49	OK	5000	2026-09-13 21:54	77.17	OK
5001	2026-09-13 21:55	79.60	OK	5002	2026-09-13 21:56	77.32	OK
5003	2026-09-13 21:57	78.73	OK	5004	2026-09-13 21:58	78.72	OK
5005	2026-09-13 21:59	81.28	OK	5006	2026-09-13 22:00	78.75	OK
5007	2026-09-13 22:01	75.74	OK	5008	2026-09-13 22:02	79.26	OK
5009	2026-09-13 22:03	77.36	OK	5010	2026-09-13 22:04	76.74	OK
5011	2026-09-13 22:05	77.87	OK	5012	2026-09-13 22:06	78.69	OK
5013	2026-09-13 22:07	78.09	OK	5014	2026-09-13 22:08	77.16	OK
5015	2026-09-13 22:09	76.57	OK	5016	2026-09-13 22:10	77.43	OK
5017	2026-09-13 22:11	77.63	OK	5018	2026-09-13 22:12	77.67	OK
5019	2026-09-13 22:13	78.01	OK	5020	2026-09-13 22:14	78.85	OK
5021	2026-09-13 22:15	77.51	OK	5022	2026-09-13 22:16	77.14	OK
5023	2026-09-13 22:17	78.24	OK	5024	2026-09-13 22:18	80.93	OK
5025	2026-09-13 22:19	80.19	OK	5026	2026-09-13 22:20	78.59	OK
5027	2026-09-13 22:21	77.67	OK	5028	2026-09-13 22:22	78.07	OK
5029	2026-09-13 22:23	77.73	OK	5030	2026-09-13 22:24	78.74	OK
5031	2026-09-13 22:25	79.50	OK	5032	2026-09-13 22:26	78.39	OK
5033	2026-09-13 22:27	80.59	OK	5034	2026-09-13 22:28	79.76	OK
5035	2026-09-13 22:29	80.93	OK	5036	2026-09-13 22:30	77.15	OK
5037	2026-09-13 22:31	78.75	OK	5038	2026-09-13 22:32	79.91	OK
5039	2026-09-13 22:33	78.84	OK	5040	2026-09-13 22:34	80.12	OK
5041	2026-09-13 22:35	76.27	OK	5042	2026-09-13 22:36	78.23	OK
5043	2026-09-13 22:37	78.56	OK	5044	2026-09-13 22:38	80.24	OK
5045	2026-09-13 22:39	78.28	OK	5046	2026-09-13 22:40	77.69	OK
5047	2026-09-13 22:41	77.12	OK	5048	2026-09-13 22:42	79.91	OK
5049	2026-09-13 22:43	78.63	OK	5050	2026-09-13 22:44	79.13	OK
5051	2026-09-13 22:45	80.57	OK	5052	2026-09-13 22:46	78.23	OK
5053	2026-09-13 22:47	77.44	OK	5054	2026-09-13 22:48	79.37	OK
5055	2026-09-13 22:49	80.12	OK	5056	2026-09-13 22:50	78.24	OK
5057	2026-09-13 22:51	79.17	OK	5058	2026-09-13 22:52	78.22	OK
5059	2026-09-13 22:53	78.52	OK	5060	2026-09-13 22:54	79.46	OK
5061	2026-09-13 22:55	80.78	OK	5062	2026-09-13 22:56	78.53	OK
5063	2026-09-13 22:57	78.87	OK	5064	2026-09-13 22:58	79.41	OK
5065	2026-09-13 22:59	80.14	OK	5066	2026-09-13 23:00	76.77	OK
5067	2026-09-13 23:01	79.66	OK	5068	2026-09-13 23:02	79.25	OK
5069	2026-09-13 23:03	80.73	OK	5070	2026-09-13 23:04	81.61	OK
5071	2026-09-13 23:05	80.79	OK	5072	2026-09-13 23:06	80.52	OK
5073	2026-09-13 23:07	77.46	OK	5074	2026-09-13 23:08	79.89	OK
5075	2026-09-13 23:09	79.11	OK	5076	2026-09-13 23:10	80.50	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5077	2026-09-13 23:11	80.46	OK	5078	2026-09-13 23:12	77.44	OK
5079	2026-09-13 23:13	80.38	OK	5080	2026-09-13 23:14	79.43	OK
5081	2026-09-13 23:15	79.90	OK	5082	2026-09-13 23:16	77.70	OK
5083	2026-09-13 23:17	79.45	OK	5084	2026-09-13 23:18	79.91	OK
5085	2026-09-13 23:19	78.99	OK	5086	2026-09-13 23:20	81.04	OK
5087	2026-09-13 23:21	81.72	OK	5088	2026-09-13 23:22	79.57	OK
5089	2026-09-13 23:23	79.81	OK	5090	2026-09-13 23:24	79.65	OK
5091	2026-09-13 23:25	79.98	OK	5092	2026-09-13 23:26	80.95	OK
5093	2026-09-13 23:27	78.49	OK	5094	2026-09-13 23:28	79.23	OK
5095	2026-09-13 23:29	81.23	OK	5096	2026-09-13 23:30	81.51	OK
5097	2026-09-13 23:31	81.66	OK	5098	2026-09-13 23:32	78.01	OK
5099	2026-09-13 23:33	80.80	OK	5100	2026-09-13 23:34	78.12	OK
5101	2026-09-13 23:35	80.14	OK	5102	2026-09-13 23:36	81.42	OK
5103	2026-09-13 23:37	78.38	OK	5104	2026-09-13 23:38	81.08	OK
5105	2026-09-13 23:39	80.82	OK	5106	2026-09-13 23:40	80.45	OK
5107	2026-09-13 23:41	82.46	OK	5108	2026-09-13 23:42	78.97	OK
5109	2026-09-13 23:43	78.66	OK	5110	2026-09-13 23:44	81.22	OK
5111	2026-09-13 23:45	80.32	OK	5112	2026-09-13 23:46	81.56	OK
5113	2026-09-13 23:47	78.78	OK	5114	2026-09-13 23:48	80.45	OK
5115	2026-09-13 23:49	80.39	OK	5116	2026-09-13 23:50	81.09	OK
5117	2026-09-13 23:51	80.02	OK	5118	2026-09-13 23:52	82.34	OK
5119	2026-09-13 23:53	81.09	OK	5120	2026-09-13 23:54	79.45	OK
5121	2026-09-13 23:55	80.32	OK	5122	2026-09-13 23:56	81.64	OK
5123	2026-09-13 23:57	80.08	OK	5124	2026-09-13 23:58	82.94	OK
5125	2026-09-13 23:59	81.89	OK	5126	2026-09-14 00:00	80.58	OK
5127	2026-09-14 00:01	80.44	OK	5128	2026-09-14 00:02	81.11	OK
5129	2026-09-14 00:03	78.95	OK	5130	2026-09-14 00:04	83.23	OK
5131	2026-09-14 00:05	81.40	OK	5132	2026-09-14 00:06	80.00	OK
5133	2026-09-14 00:07	79.20	OK	5134	2026-09-14 00:08	79.69	OK
5135	2026-09-14 00:09	78.27	OK	5136	2026-09-14 00:10	80.49	OK
5137	2026-09-14 00:11	78.62	OK	5138	2026-09-14 00:12	78.75	OK
5139	2026-09-14 00:13	80.36	OK	5140	2026-09-14 00:14	80.81	OK
5141	2026-09-14 00:15	78.48	OK	5142	2026-09-14 00:16	80.61	OK
5143	2026-09-14 00:17	80.96	OK	5144	2026-09-14 00:18	81.71	OK
5145	2026-09-14 00:19	80.82	OK	5146	2026-09-14 00:20	79.95	OK
5147	2026-09-14 00:21	81.38	OK	5148	2026-09-14 00:22	81.77	OK
5149	2026-09-14 00:23	82.53	OK	5150	2026-09-14 00:24	80.88	OK
5151	2026-09-14 00:25	82.72	OK	5152	2026-09-14 00:26	80.28	OK
5153	2026-09-14 00:27	79.32	OK	5154	2026-09-14 00:28	78.62	OK
5155	2026-09-14 00:29	80.82	OK	5156	2026-09-14 00:30	80.45	OK
5157	2026-09-14 00:31	80.15	OK	5158	2026-09-14 00:32	80.13	OK
5159	2026-09-14 00:33	78.81	OK	5160	2026-09-14 00:34	81.60	OK
5161	2026-09-14 00:35	80.21	OK	5162	2026-09-14 00:36	82.84	OK
5163	2026-09-14 00:37	81.49	OK	5164	2026-09-14 00:38	77.99	OK
5165	2026-09-14 00:39	81.46	OK	5166	2026-09-14 00:40	83.06	OK
5167	2026-09-14 00:41	78.37	OK	5168	2026-09-14 00:42	81.58	OK
5169	2026-09-14 00:43	82.08	OK	5170	2026-09-14 00:44	81.59	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5171	2026-09-14 00:45	81.22	OK	5172	2026-09-14 00:46	80.91	OK
5173	2026-09-14 00:47	81.55	OK	5174	2026-09-14 00:48	82.09	OK
5175	2026-09-14 00:49	80.72	OK	5176	2026-09-14 00:50	83.26	OK
5177	2026-09-14 00:51	78.83	OK	5178	2026-09-14 00:52	79.66	OK
5179	2026-09-14 00:53	81.60	OK	5180	2026-09-14 00:54	81.06	OK
5181	2026-09-14 00:55	80.94	OK	5182	2026-09-14 00:56	81.00	OK
5183	2026-09-14 00:57	80.92	OK	5184	2026-09-14 00:58	80.68	OK
5185	2026-09-14 00:59	81.88	OK	5186	2026-09-14 01:00	80.52	OK
5187	2026-09-14 01:01	81.49	OK	5188	2026-09-14 01:02	80.15	OK
5189	2026-09-14 01:03	82.48	OK	5190	2026-09-14 01:04	83.31	OK
5191	2026-09-14 01:05	81.45	OK	5192	2026-09-14 01:06	82.82	OK
5193	2026-09-14 01:07	81.15	OK	5194	2026-09-14 01:08	81.84	OK
5195	2026-09-14 01:09	79.15	OK	5196	2026-09-14 01:10	80.42	OK
5197	2026-09-14 01:11	81.37	OK	5198	2026-09-14 01:12	81.90	OK
5199	2026-09-14 01:13	80.24	OK	5200	2026-09-14 01:14	81.10	OK
5201	2026-09-14 01:15	81.53	OK	5202	2026-09-14 01:16	82.44	OK
5203	2026-09-14 01:17	80.98	OK	5204	2026-09-14 01:18	80.50	OK
5205	2026-09-14 01:19	82.67	OK	5206	2026-09-14 01:20	80.91	OK
5207	2026-09-14 01:21	83.17	OK	5208	2026-09-14 01:22	80.73	OK
5209	2026-09-14 01:23	81.61	OK	5210	2026-09-14 01:24	79.23	OK
5211	2026-09-14 01:25	82.33	OK	5212	2026-09-14 01:26	81.86	OK
5213	2026-09-14 01:27	82.95	OK	5214	2026-09-14 01:28	81.66	OK
5215	2026-09-14 01:29	82.58	OK	5216	2026-09-14 01:30	81.93	OK
5217	2026-09-14 01:31	82.74	OK	5218	2026-09-14 01:32	81.15	OK
5219	2026-09-14 01:33	81.82	OK	5220	2026-09-14 01:34	81.44	OK
5221	2026-09-14 01:35	81.10	OK	5222	2026-09-14 01:36	81.35	OK
5223	2026-09-14 01:37	81.08	OK	5224	2026-09-14 01:38	82.25	OK
5225	2026-09-14 01:39	81.42	OK	5226	2026-09-14 01:40	80.33	OK
5227	2026-09-14 01:41	83.30	OK	5228	2026-09-14 01:42	81.63	OK
5229	2026-09-14 01:43	82.41	OK	5230	2026-09-14 01:44	79.89	OK
5231	2026-09-14 01:45	81.96	OK	5232	2026-09-14 01:46	81.72	OK
5233	2026-09-14 01:47	82.59	OK	5234	2026-09-14 01:48	81.24	OK
5235	2026-09-14 01:49	82.77	OK	5236	2026-09-14 01:50	82.62	OK
5237	2026-09-14 01:51	84.71	OK	5238	2026-09-14 01:52	81.67	OK
5239	2026-09-14 01:53	83.04	OK	5240	2026-09-14 01:54	82.00	OK
5241	2026-09-14 01:55	83.58	OK	5242	2026-09-14 01:56	81.35	OK
5243	2026-09-14 01:57	80.11	OK	5244	2026-09-14 01:58	83.94	OK
5245	2026-09-14 01:59	82.79	OK	5246	2026-09-14 02:00	84.05	OK
5247	2026-09-14 02:01	80.32	OK	5248	2026-09-14 02:02	82.27	OK
5249	2026-09-14 02:03	80.27	OK	5250	2026-09-14 02:04	83.75	OK
5251	2026-09-14 02:05	83.61	OK	5252	2026-09-14 02:06	84.46	OK
5253	2026-09-14 02:07	83.31	OK	5254	2026-09-14 02:08	83.87	OK
5255	2026-09-14 02:09	81.21	OK	5256	2026-09-14 02:10	82.04	OK
5257	2026-09-14 02:11	84.13	OK	5258	2026-09-14 02:12	81.86	OK
5259	2026-09-14 02:13	82.64	OK	5260	2026-09-14 02:14	81.65	OK
5261	2026-09-14 02:15	83.09	OK	5262	2026-09-14 02:16	83.81	OK
5263	2026-09-14 02:17	81.78	OK	5264	2026-09-14 02:18	81.05	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5265	2026-09-14 02:19	81.55	OK	5266	2026-09-14 02:20	82.83	OK
5267	2026-09-14 02:21	84.12	OK	5268	2026-09-14 02:22	82.33	OK
5269	2026-09-14 02:23	81.38	OK	5270	2026-09-14 02:24	82.90	OK
5271	2026-09-14 02:25	82.95	OK	5272	2026-09-14 02:26	80.73	OK
5273	2026-09-14 02:27	80.98	OK	5274	2026-09-14 02:28	81.17	OK
5275	2026-09-14 02:29	80.06	OK	5276	2026-09-14 02:30	82.78	OK
5277	2026-09-14 02:31	81.95	OK	5278	2026-09-14 02:32	83.20	OK
5279	2026-09-14 02:33	81.08	OK	5280	2026-09-14 02:34	81.69	OK
5281	2026-09-14 02:35	81.09	OK	5282	2026-09-14 02:36	82.46	OK
5283	2026-09-14 02:37	80.97	OK	5284	2026-09-14 02:38	79.15	OK
5285	2026-09-14 02:39	82.34	OK	5286	2026-09-14 02:40	82.11	OK
5287	2026-09-14 02:41	80.33	OK	5288	2026-09-14 02:42	79.69	OK
5289	2026-09-14 02:43	81.81	OK	5290	2026-09-14 02:44	82.82	OK
5291	2026-09-14 02:45	81.57	OK	5292	2026-09-14 02:46	79.60	OK
5293	2026-09-14 02:47	83.24	OK	5294	2026-09-14 02:48	79.61	OK
5295	2026-09-14 02:49	81.21	OK	5296	2026-09-14 02:50	82.74	OK
5297	2026-09-14 02:51	81.12	OK	5298	2026-09-14 02:52	80.37	OK
5299	2026-09-14 02:53	82.39	OK	5300	2026-09-14 02:54	80.30	OK
5301	2026-09-14 02:55	83.21	OK	5302	2026-09-14 02:56	83.87	OK
5303	2026-09-14 02:57	79.90	OK	5304	2026-09-14 02:58	81.62	OK
5305	2026-09-14 02:59	79.88	OK	5306	2026-09-14 03:00	81.39	OK
5307	2026-09-14 03:01	82.10	OK	5308	2026-09-14 03:02	82.72	OK
5309	2026-09-14 03:03	79.27	OK	5310	2026-09-14 03:04	81.92	OK
5311	2026-09-14 03:05	81.05	OK	5312	2026-09-14 03:06	82.72	OK
5313	2026-09-14 03:07	81.33	OK	5314	2026-09-14 03:08	81.97	OK
5315	2026-09-14 03:09	79.83	OK	5316	2026-09-14 03:10	80.70	OK
5317	2026-09-14 03:11	83.03	OK	5318	2026-09-14 03:12	84.38	OK
5319	2026-09-14 03:13	83.51	OK	5320	2026-09-14 03:14	83.31	OK
5321	2026-09-14 03:15	80.59	OK	5322	2026-09-14 03:16	81.27	OK
5323	2026-09-14 03:17	82.54	OK	5324	2026-09-14 03:18	82.22	OK
5325	2026-09-14 03:19	81.66	OK	5326	2026-09-14 03:20	80.84	OK
5327	2026-09-14 03:21	84.59	OK	5328	2026-09-14 03:22	83.82	OK
5329	2026-09-14 03:23	80.82	OK	5330	2026-09-14 03:24	81.05	OK
5331	2026-09-14 03:25	81.64	OK	5332	2026-09-14 03:26	81.48	OK
5333	2026-09-14 03:27	83.51	OK	5334	2026-09-14 03:28	81.48	OK
5335	2026-09-14 03:29	80.58	OK	5336	2026-09-14 03:30	81.58	OK
5337	2026-09-14 03:31	79.24	OK	5338	2026-09-14 03:32	82.86	OK
5339	2026-09-14 03:33	80.98	OK	5340	2026-09-14 03:34	81.89	OK
5341	2026-09-14 03:35	81.59	OK	5342	2026-09-14 03:36	82.10	OK
5343	2026-09-14 03:37	82.42	OK	5344	2026-09-14 03:38	83.49	OK
5345	2026-09-14 03:39	82.12	OK	5346	2026-09-14 03:40	81.82	OK
5347	2026-09-14 03:41	81.84	OK	5348	2026-09-14 03:42	80.07	OK
5349	2026-09-14 03:43	80.57	OK	5350	2026-09-14 03:44	80.92	OK
5351	2026-09-14 03:45	83.09	OK	5352	2026-09-14 03:46	83.16	OK
5353	2026-09-14 03:47	81.97	OK	5354	2026-09-14 03:48	83.86	OK
5355	2026-09-14 03:49	83.47	OK	5356	2026-09-14 03:50	81.09	OK
5357	2026-09-14 03:51	81.92	OK	5358	2026-09-14 03:52	81.84	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5359	2026-09-14 03:53	81.46	OK	5360	2026-09-14 03:54	81.57	OK
5361	2026-09-14 03:55	81.87	OK	5362	2026-09-14 03:56	80.00	OK
5363	2026-09-14 03:57	81.00	OK	5364	2026-09-14 03:58	80.85	OK
5365	2026-09-14 03:59	80.27	OK	5366	2026-09-14 04:00	83.54	OK
5367	2026-09-14 04:01	80.20	OK	5368	2026-09-14 04:02	79.50	OK
5369	2026-09-14 04:03	82.06	OK	5370	2026-09-14 04:04	81.64	OK
5371	2026-09-14 04:05	79.80	OK	5372	2026-09-14 04:06	82.70	OK
5373	2026-09-14 04:07	80.79	OK	5374	2026-09-14 04:08	80.09	OK
5375	2026-09-14 04:09	80.49	OK	5376	2026-09-14 04:10	81.50	OK
5377	2026-09-14 04:11	83.55	OK	5378	2026-09-14 04:12	80.66	OK
5379	2026-09-14 04:13	80.28	OK	5380	2026-09-14 04:14	80.20	OK
5381	2026-09-14 04:15	80.43	OK	5382	2026-09-14 04:16	82.32	OK
5383	2026-09-14 04:17	78.81	OK	5384	2026-09-14 04:18	80.87	OK
5385	2026-09-14 04:19	81.59	OK	5386	2026-09-14 04:20	80.81	OK
5387	2026-09-14 04:21	80.61	OK	5388	2026-09-14 04:22	82.89	OK
5389	2026-09-14 04:23	79.91	OK	5390	2026-09-14 04:24	82.48	OK
5391	2026-09-14 04:25	81.02	OK	5392	2026-09-14 04:26	81.74	OK
5393	2026-09-14 04:27	81.40	OK	5394	2026-09-14 04:28	81.32	OK
5395	2026-09-14 04:29	83.55	OK	5396	2026-09-14 04:30	79.83	OK
5397	2026-09-14 04:31	81.21	OK	5398	2026-09-14 04:32	79.32	OK
5399	2026-09-14 04:33	81.34	OK	5400	2026-09-14 04:34	82.93	OK
5401	2026-09-14 04:35	83.17	OK	5402	2026-09-14 04:36	81.87	OK
5403	2026-09-14 04:37	79.58	OK	5404	2026-09-14 04:38	80.83	OK
5405	2026-09-14 04:39	80.31	OK	5406	2026-09-14 04:40	80.92	OK
5407	2026-09-14 04:41	78.65	OK	5408	2026-09-14 04:42	80.06	OK
5409	2026-09-14 04:43	83.47	OK	5410	2026-09-14 04:44	78.27	OK
5411	2026-09-14 04:45	80.67	OK	5412	2026-09-14 04:46	81.08	OK
5413	2026-09-14 04:47	82.19	OK	5414	2026-09-14 04:48	81.14	OK
5415	2026-09-14 04:49	81.98	OK	5416	2026-09-14 04:50	82.24	OK
5417	2026-09-14 04:51	80.00	OK	5418	2026-09-14 04:52	80.87	OK
5419	2026-09-14 04:53	82.89	OK	5420	2026-09-14 04:54	80.55	OK
5421	2026-09-14 04:55	81.36	OK	5422	2026-09-14 04:56	83.49	OK
5423	2026-09-14 04:57	82.32	OK	5424	2026-09-14 04:58	81.57	OK
5425	2026-09-14 04:59	80.77	OK	5426	2026-09-14 05:00	81.21	OK
5427	2026-09-14 05:01	81.41	OK	5428	2026-09-14 05:02	80.75	OK
5429	2026-09-14 05:03	80.12	OK	5430	2026-09-14 05:04	81.06	OK
5431	2026-09-14 05:05	80.09	OK	5432	2026-09-14 05:06	81.22	OK
5433	2026-09-14 05:07	81.51	OK	5434	2026-09-14 05:08	81.33	OK
5435	2026-09-14 05:09	80.00	OK	5436	2026-09-14 05:10	81.20	OK
5437	2026-09-14 05:11	83.47	OK	5438	2026-09-14 05:12	79.69	OK
5439	2026-09-14 05:13	79.72	OK	5440	2026-09-14 05:14	79.62	OK
5441	2026-09-14 05:15	78.27	OK	5442	2026-09-14 05:16	80.60	OK
5443	2026-09-14 05:17	80.48	OK	5444	2026-09-14 05:18	81.84	OK
5445	2026-09-14 05:19	83.04	OK	5446	2026-09-14 05:20	80.39	OK
5447	2026-09-14 05:21	79.74	OK	5448	2026-09-14 05:22	79.36	OK
5449	2026-09-14 05:23	80.93	OK	5450	2026-09-14 05:24	80.74	OK
5451	2026-09-14 05:25	78.31	OK	5452	2026-09-14 05:26	78.72	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5453	2026-09-14 05:27	80.23	OK	5454	2026-09-14 05:28	82.32	OK
5455	2026-09-14 05:29	81.89	OK	5456	2026-09-14 05:30	81.63	OK
5457	2026-09-14 05:31	78.69	OK	5458	2026-09-14 05:32	82.00	OK
5459	2026-09-14 05:33	77.34	OK	5460	2026-09-14 05:34	80.52	OK
5461	2026-09-14 05:35	79.93	OK	5462	2026-09-14 05:36	80.97	OK
5463	2026-09-14 05:37	79.76	OK	5464	2026-09-14 05:38	82.32	OK
5465	2026-09-14 05:39	79.12	OK	5466	2026-09-14 05:40	80.53	OK
5467	2026-09-14 05:41	78.57	OK	5468	2026-09-14 05:42	81.35	OK
5469	2026-09-14 05:43	82.13	OK	5470	2026-09-14 05:44	79.13	OK
5471	2026-09-14 05:45	80.48	OK	5472	2026-09-14 05:46	82.70	OK
5473	2026-09-14 05:47	79.85	OK	5474	2026-09-14 05:48	81.40	OK
5475	2026-09-14 05:49	81.29	OK	5476	2026-09-14 05:50	81.12	OK
5477	2026-09-14 05:51	79.41	OK	5478	2026-09-14 05:52	82.88	OK
5479	2026-09-14 05:53	81.57	OK	5480	2026-09-14 05:54	78.97	OK
5481	2026-09-14 05:55	80.64	OK	5482	2026-09-14 05:56	81.84	OK
5483	2026-09-14 05:57	77.67	OK	5484	2026-09-14 05:58	79.83	OK
5485	2026-09-14 05:59	80.47	OK	5486	2026-09-14 06:00	79.97	OK
5487	2026-09-14 06:01	79.27	OK	5488	2026-09-14 06:02	82.15	OK
5489	2026-09-14 06:03	80.24	OK	5490	2026-09-14 06:04	78.65	OK
5491	2026-09-14 06:05	80.62	OK	5492	2026-09-14 06:06	79.75	OK
5493	2026-09-14 06:07	80.83	OK	5494	2026-09-14 06:08	81.95	OK
5495	2026-09-14 06:09	79.78	OK	5496	2026-09-14 06:10	77.47	OK
5497	2026-09-14 06:11	79.93	OK	5498	2026-09-14 06:12	81.33	OK
5499	2026-09-14 06:13	77.80	OK	5500	2026-09-14 06:14	81.40	OK
5501	2026-09-14 06:15	78.86	OK	5502	2026-09-14 06:16	80.78	OK
5503	2026-09-14 06:17	78.40	OK	5504	2026-09-14 06:18	78.89	OK
5505	2026-09-14 06:19	79.88	OK	5506	2026-09-14 06:20	80.00	OK
5507	2026-09-14 06:21	79.49	OK	5508	2026-09-14 06:22	80.12	OK
5509	2026-09-14 06:23	77.02	OK	5510	2026-09-14 06:24	78.26	OK
5511	2026-09-14 06:25	80.71	OK	5512	2026-09-14 06:26	77.99	OK
5513	2026-09-14 06:27	77.93	OK	5514	2026-09-14 06:28	81.71	OK
5515	2026-09-14 06:29	78.64	OK	5516	2026-09-14 06:30	77.39	OK
5517	2026-09-14 06:31	79.12	OK	5518	2026-09-14 06:32	79.03	OK
5519	2026-09-14 06:33	79.29	OK	5520	2026-09-14 06:34	78.74	OK
5521	2026-09-14 06:35	81.47	OK	5522	2026-09-14 06:36	79.69	OK
5523	2026-09-14 06:37	79.22	OK	5524	2026-09-14 06:38	79.29	OK
5525	2026-09-14 06:39	79.57	OK	5526	2026-09-14 06:40	79.76	OK
5527	2026-09-14 06:41	79.60	OK	5528	2026-09-14 06:42	76.86	OK
5529	2026-09-14 06:43	78.75	OK	5530	2026-09-14 06:44	78.25	OK
5531	2026-09-14 06:45	80.67	OK	5532	2026-09-14 06:46	76.82	OK
5533	2026-09-14 06:47	79.20	OK	5534	2026-09-14 06:48	80.12	OK
5535	2026-09-14 06:49	79.09	OK	5536	2026-09-14 06:50	81.95	OK
5537	2026-09-14 06:51	77.91	OK	5538	2026-09-14 06:52	80.25	OK
5539	2026-09-14 06:53	77.96	OK	5540	2026-09-14 06:54	80.05	OK
5541	2026-09-14 06:55	76.05	OK	5542	2026-09-14 06:56	78.01	OK
5543	2026-09-14 06:57	77.66	OK	5544	2026-09-14 06:58	81.41	OK
5545	2026-09-14 06:59	78.00	OK	5546	2026-09-14 07:00	80.56	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5547	2026-09-14 07:01	76.99	OK	5548	2026-09-14 07:02	76.96	OK
5549	2026-09-14 07:03	79.36	OK	5550	2026-09-14 07:04	78.20	OK
5551	2026-09-14 07:05	78.49	OK	5552	2026-09-14 07:06	79.75	OK
5553	2026-09-14 07:07	78.29	OK	5554	2026-09-14 07:08	78.41	OK
5555	2026-09-14 07:09	79.74	OK	5556	2026-09-14 07:10	79.18	OK
5557	2026-09-14 07:11	78.54	OK	5558	2026-09-14 07:12	80.45	OK
5559	2026-09-14 07:13	81.27	OK	5560	2026-09-14 07:14	81.02	OK
5561	2026-09-14 07:15	79.21	OK	5562	2026-09-14 07:16	77.25	OK
5563	2026-09-14 07:17	79.40	OK	5564	2026-09-14 07:18	80.01	OK
5565	2026-09-14 07:19	76.48	OK	5566	2026-09-14 07:20	77.07	OK
5567	2026-09-14 07:21	76.19	OK	5568	2026-09-14 07:22	79.61	OK
5569	2026-09-14 07:23	76.41	OK	5570	2026-09-14 07:24	76.29	OK
5571	2026-09-14 07:25	78.18	OK	5572	2026-09-14 07:26	78.26	OK
5573	2026-09-14 07:27	79.57	OK	5574	2026-09-14 07:28	79.72	OK
5575	2026-09-14 07:29	77.60	OK	5576	2026-09-14 07:30	79.90	OK
5577	2026-09-14 07:31	78.10	OK	5578	2026-09-14 07:32	76.88	OK
5579	2026-09-14 07:33	76.89	OK	5580	2026-09-14 07:34	79.98	OK
5581	2026-09-14 07:35	78.39	OK	5582	2026-09-14 07:36	80.46	OK
5583	2026-09-14 07:37	79.96	OK	5584	2026-09-14 07:38	78.32	OK
5585	2026-09-14 07:39	78.42	OK	5586	2026-09-14 07:40	79.10	OK
5587	2026-09-14 07:41	79.33	OK	5588	2026-09-14 07:42	78.44	OK
5589	2026-09-14 07:43	76.12	OK	5590	2026-09-14 07:44	77.20	OK
5591	2026-09-14 07:45	79.17	OK	5592	2026-09-14 07:46	78.91	OK
5593	2026-09-14 07:47	80.29	OK	5594	2026-09-14 07:48	79.56	OK
5595	2026-09-14 07:49	78.13	OK	5596	2026-09-14 07:50	77.78	OK
5597	2026-09-14 07:51	78.56	OK	5598	2026-09-14 07:52	76.82	OK
5599	2026-09-14 07:53	78.81	OK	5600	2026-09-14 07:54	77.85	OK
5601	2026-09-14 07:55	77.17	OK	5602	2026-09-14 07:56	74.85	OK
5603	2026-09-14 07:57	78.54	OK	5604	2026-09-14 07:58	75.61	OK
5605	2026-09-14 07:59	74.42	OK	5606	2026-09-14 08:00	78.83	OK
5607	2026-09-14 08:01	75.81	OK	5608	2026-09-14 08:02	75.93	OK
5609	2026-09-14 08:03	76.94	OK	5610	2026-09-14 08:04	76.42	OK
5611	2026-09-14 08:05	76.27	OK	5612	2026-09-14 08:06	75.38	OK
5613	2026-09-14 08:07	74.34	OK	5614	2026-09-14 08:08	78.12	OK
5615	2026-09-14 08:09	77.51	OK	5616	2026-09-14 08:10	78.20	OK
5617	2026-09-14 08:11	76.30	OK	5618	2026-09-14 08:12	78.81	OK
5619	2026-09-14 08:13	77.61	OK	5620	2026-09-14 08:14	79.65	OK
5621	2026-09-14 08:15	76.48	OK	5622	2026-09-14 08:16	79.30	OK
5623	2026-09-14 08:17	77.89	OK	5624	2026-09-14 08:18	76.76	OK
5625	2026-09-14 08:19	77.05	OK	5626	2026-09-14 08:20	75.63	OK
5627	2026-09-14 08:21	76.91	OK	5628	2026-09-14 08:22	78.31	OK
5629	2026-09-14 08:23	77.56	OK	5630	2026-09-14 08:24	79.14	OK
5631	2026-09-14 08:25	77.72	OK	5632	2026-09-14 08:26	78.17	OK
5633	2026-09-14 08:27	77.81	OK	5634	2026-09-14 08:28	79.08	OK
5635	2026-09-14 08:29	78.31	OK	5636	2026-09-14 08:30	79.39	OK
5637	2026-09-14 08:31	77.80	OK	5638	2026-09-14 08:32	77.59	OK
5639	2026-09-14 08:33	76.54	OK	5640	2026-09-14 08:34	75.88	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5641	2026-09-14 08:35	75.01	OK	5642	2026-09-14 08:36	77.44	OK
5643	2026-09-14 08:37	75.14	OK	5644	2026-09-14 08:38	73.82	OK
5645	2026-09-14 08:39	76.50	OK	5646	2026-09-14 08:40	77.35	OK
5647	2026-09-14 08:41	77.32	OK	5648	2026-09-14 08:42	76.71	OK
5649	2026-09-14 08:43	77.21	OK	5650	2026-09-14 08:44	76.05	OK
5651	2026-09-14 08:45	77.46	OK	5652	2026-09-14 08:46	77.53	OK
5653	2026-09-14 08:47	76.37	OK	5654	2026-09-14 08:48	76.73	OK
5655	2026-09-14 08:49	77.64	OK	5656	2026-09-14 08:50	76.40	OK
5657	2026-09-14 08:51	75.36	OK	5658	2026-09-14 08:52	74.71	OK
5659	2026-09-14 08:53	78.80	OK	5660	2026-09-14 08:54	77.67	OK
5661	2026-09-14 08:55	77.01	OK	5662	2026-09-14 08:56	77.83	OK
5663	2026-09-14 08:57	73.12	OK	5664	2026-09-14 08:58	77.87	OK
5665	2026-09-14 08:59	75.50	OK	5666	2026-09-14 09:00	76.90	OK
5667	2026-09-14 09:01	74.43	OK	5668	2026-09-14 09:02	76.35	OK
5669	2026-09-14 09:03	75.34	OK	5670	2026-09-14 09:04	77.88	OK
5671	2026-09-14 09:05	74.07	OK	5672	2026-09-14 09:06	76.43	OK
5673	2026-09-14 09:07	77.21	OK	5674	2026-09-14 09:08	76.86	OK
5675	2026-09-14 09:09	74.69	OK	5676	2026-09-14 09:10	75.44	OK
5677	2026-09-14 09:11	76.89	OK	5678	2026-09-14 09:12	79.15	OK
5679	2026-09-14 09:13	77.52	OK	5680	2026-09-14 09:14	76.08	OK
5681	2026-09-14 09:15	77.63	OK	5682	2026-09-14 09:16	76.13	OK
5683	2026-09-14 09:17	72.65	OK	5684	2026-09-14 09:18	77.34	OK
5685	2026-09-14 09:19	76.76	OK	5686	2026-09-14 09:20	77.36	OK
5687	2026-09-14 09:21	77.29	OK	5688	2026-09-14 09:22	75.15	OK
5689	2026-09-14 09:23	76.23	OK	5690	2026-09-14 09:24	77.16	OK
5691	2026-09-14 09:25	76.08	OK	5692	2026-09-14 09:26	76.55	OK
5693	2026-09-14 09:27	75.28	OK	5694	2026-09-14 09:28	73.56	OK
5695	2026-09-14 09:29	76.57	OK	5696	2026-09-14 09:30	75.69	OK
5697	2026-09-14 09:31	76.99	OK	5698	2026-09-14 09:32	72.95	OK
5699	2026-09-14 09:33	76.88	OK	5700	2026-09-14 09:34	74.42	OK
5701	2026-09-14 09:35	77.65	OK	5702	2026-09-14 09:36	74.88	OK
5703	2026-09-14 09:37	75.66	OK	5704	2026-09-14 09:38	74.29	OK
5705	2026-09-14 09:39	75.14	OK	5706	2026-09-14 09:40	75.31	OK
5707	2026-09-14 09:41	73.39	OK	5708	2026-09-14 09:42	77.69	OK
5709	2026-09-14 09:43	75.11	OK	5710	2026-09-14 09:44	74.56	OK
5711	2026-09-14 09:45	73.89	OK	5712	2026-09-14 09:46	75.83	OK
5713	2026-09-14 09:47	74.98	OK	5714	2026-09-14 09:48	73.22	OK
5715	2026-09-14 09:49	75.67	OK	5716	2026-09-14 09:50	76.60	OK
5717	2026-09-14 09:51	74.49	OK	5718	2026-09-14 09:52	73.05	OK
5719	2026-09-14 09:53	75.80	OK	5720	2026-09-14 09:54	73.98	OK
5721	2026-09-14 09:55	77.32	OK	5722	2026-09-14 09:56	75.09	OK
5723	2026-09-14 09:57	71.89	OK	5724	2026-09-14 09:58	77.98	OK
5725	2026-09-14 09:59	76.54	OK	5726	2026-09-14 10:00	74.01	OK
5727	2026-09-14 10:01	73.71	OK	5728	2026-09-14 10:02	75.23	OK
5729	2026-09-14 10:03	73.82	OK	5730	2026-09-14 10:04	76.65	OK
5731	2026-09-14 10:05	75.30	OK	5732	2026-09-14 10:06	73.86	OK
5733	2026-09-14 10:07	72.84	OK	5734	2026-09-14 10:08	74.60	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5735	2026-09-14 10:09	74.49	OK	5736	2026-09-14 10:10	73.70	OK
5737	2026-09-14 10:11	74.26	OK	5738	2026-09-14 10:12	72.36	OK
5739	2026-09-14 10:13	73.18	OK	5740	2026-09-14 10:14	74.99	OK
5741	2026-09-14 10:15	76.53	OK	5742	2026-09-14 10:16	74.85	OK
5743	2026-09-14 10:17	75.10	OK	5744	2026-09-14 10:18	74.55	OK
5745	2026-09-14 10:19	73.02	OK	5746	2026-09-14 10:20	72.84	OK
5747	2026-09-14 10:21	74.21	OK	5748	2026-09-14 10:22	74.34	OK
5749	2026-09-14 10:23	74.47	OK	5750	2026-09-14 10:24	74.64	OK
5751	2026-09-14 10:25	73.30	OK	5752	2026-09-14 10:26	74.94	OK
5753	2026-09-14 10:27	72.90	OK	5754	2026-09-14 10:28	74.72	OK
5755	2026-09-14 10:29	73.17	OK	5756	2026-09-14 10:30	73.70	OK
5757	2026-09-14 10:31	73.15	OK	5758	2026-09-14 10:32	73.88	OK
5759	2026-09-14 10:33	74.53	OK	5760	2026-09-14 10:34	74.87	OK
5761	2026-09-14 10:35	74.46	OK	5762	2026-09-14 10:36	73.84	OK
5763	2026-09-14 10:37	76.24	OK	5764	2026-09-14 10:38	75.63	OK
5765	2026-09-14 10:39	74.59	OK	5766	2026-09-14 10:40	75.45	OK
5767	2026-09-14 10:41	74.49	OK	5768	2026-09-14 10:42	72.71	OK
5769	2026-09-14 10:43	74.16	OK	5770	2026-09-14 10:44	74.68	OK
5771	2026-09-14 10:45	73.31	OK	5772	2026-09-14 10:46	75.89	OK
5773	2026-09-14 10:47	74.25	OK	5774	2026-09-14 10:48	75.29	OK
5775	2026-09-14 10:49	72.97	OK	5776	2026-09-14 10:50	73.14	OK
5777	2026-09-14 10:51	73.78	OK	5778	2026-09-14 10:52	75.37	OK
5779	2026-09-14 10:53	75.46	OK	5780	2026-09-14 10:54	73.96	OK
5781	2026-09-14 10:55	75.58	OK	5782	2026-09-14 10:56	73.41	OK
5783	2026-09-14 10:57	70.90	OK	5784	2026-09-14 10:58	70.52	OK
5785	2026-09-14 10:59	73.67	OK	5786	2026-09-14 11:00	75.38	OK
5787	2026-09-14 11:01	74.11	OK	5788	2026-09-14 11:02	75.05	OK
5789	2026-09-14 11:03	73.45	OK	5790	2026-09-14 11:04	73.89	OK
5791	2026-09-14 11:05	72.06	OK	5792	2026-09-14 11:06	73.98	OK
5793	2026-09-14 11:07	75.39	OK	5794	2026-09-14 11:08	74.79	OK
5795	2026-09-14 11:09	73.66	OK	5796	2026-09-14 11:10	73.32	OK
5797	2026-09-14 11:11	74.84	OK	5798	2026-09-14 11:12	73.02	OK
5799	2026-09-14 11:13	73.66	OK	5800	2026-09-14 11:14	74.45	OK
5801	2026-09-14 11:15	73.70	OK	5802	2026-09-14 11:16	71.60	OK
5803	2026-09-14 11:17	73.55	OK	5804	2026-09-14 11:18	72.33	OK
5805	2026-09-14 11:19	75.06	OK	5806	2026-09-14 11:20	71.44	OK
5807	2026-09-14 11:21	71.99	OK	5808	2026-09-14 11:22	73.27	OK
5809	2026-09-14 11:23	74.45	OK	5810	2026-09-14 11:24	74.38	OK
5811	2026-09-14 11:25	72.02	OK	5812	2026-09-14 11:26	73.39	OK
5813	2026-09-14 11:27	73.08	OK	5814	2026-09-14 11:28	73.90	OK
5815	2026-09-14 11:29	73.92	OK	5816	2026-09-14 11:30	73.84	OK
5817	2026-09-14 11:31	72.39	OK	5818	2026-09-14 11:32	74.57	OK
5819	2026-09-14 11:33	72.37	OK	5820	2026-09-14 11:34	73.79	OK
5821	2026-09-14 11:35	73.85	OK	5822	2026-09-14 11:36	71.97	OK
5823	2026-09-14 11:37	76.25	OK	5824	2026-09-14 11:38	74.54	OK
5825	2026-09-14 11:39	73.43	OK	5826	2026-09-14 11:40	70.61	OK
5827	2026-09-14 11:41	70.61	OK	5828	2026-09-14 11:42	72.14	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5829	2026-09-14 11:43	74.72	OK	5830	2026-09-14 11:44	72.68	OK
5831	2026-09-14 11:45	74.10	OK	5832	2026-09-14 11:46	73.05	OK
5833	2026-09-14 11:47	73.22	OK	5834	2026-09-14 11:48	75.53	OK
5835	2026-09-14 11:49	73.21	OK	5836	2026-09-14 11:50	74.61	OK
5837	2026-09-14 11:51	71.49	OK	5838	2026-09-14 11:52	72.91	OK
5839	2026-09-14 11:53	71.59	OK	5840	2026-09-14 11:54	71.09	OK
5841	2026-09-14 11:55	72.62	OK	5842	2026-09-14 11:56	75.67	OK
5843	2026-09-14 11:57	74.52	OK	5844	2026-09-14 11:58	72.19	OK
5845	2026-09-14 11:59	70.37	OK	5846	2026-09-14 12:00	71.81	OK
5847	2026-09-14 12:01	73.07	OK	5848	2026-09-14 12:02	71.68	OK
5849	2026-09-14 12:03	72.64	OK	5850	2026-09-14 12:04	74.30	OK
5851	2026-09-14 12:05	71.48	OK	5852	2026-09-14 12:06	74.19	OK
5853	2026-09-14 12:07	70.02	OK	5854	2026-09-14 12:08	73.13	OK
5855	2026-09-14 12:09	73.65	OK	5856	2026-09-14 12:10	71.85	OK
5857	2026-09-14 12:11	70.42	OK	5858	2026-09-14 12:12	69.75	OK
5859	2026-09-14 12:13	72.12	OK	5860	2026-09-14 12:14	72.10	OK
5861	2026-09-14 12:15	73.08	OK	5862	2026-09-14 12:16	71.74	OK
5863	2026-09-14 12:17	72.13	OK	5864	2026-09-14 12:18	70.48	OK
5865	2026-09-14 12:19	72.47	OK	5866	2026-09-14 12:20	72.06	OK
5867	2026-09-14 12:21	73.77	OK	5868	2026-09-14 12:22	72.12	OK
5869	2026-09-14 12:23	70.59	OK	5870	2026-09-14 12:24	73.04	OK
5871	2026-09-14 12:25	73.65	OK	5872	2026-09-14 12:26	75.22	OK
5873	2026-09-14 12:27	72.94	OK	5874	2026-09-14 12:28	72.78	OK
5875	2026-09-14 12:29	71.21	OK	5876	2026-09-14 12:30	73.66	OK
5877	2026-09-14 12:31	72.49	OK	5878	2026-09-14 12:32	72.12	OK
5879	2026-09-14 12:33	72.68	OK	5880	2026-09-14 12:34	70.99	OK
5881	2026-09-14 12:35	72.22	OK	5882	2026-09-14 12:36	72.23	OK
5883	2026-09-14 12:37	70.91	OK	5884	2026-09-14 12:38	72.15	OK
5885	2026-09-14 12:39	71.60	OK	5886	2026-09-14 12:40	71.94	OK
5887	2026-09-14 12:41	73.74	OK	5888	2026-09-14 12:42	72.12	OK
5889	2026-09-14 12:43	71.92	OK	5890	2026-09-14 12:44	72.21	OK
5891	2026-09-14 12:45	71.33	OK	5892	2026-09-14 12:46	73.55	OK
5893	2026-09-14 12:47	72.88	OK	5894	2026-09-14 12:48	74.37	OK
5895	2026-09-14 12:49	68.62	OK	5896	2026-09-14 12:50	72.05	OK
5897	2026-09-14 12:51	72.03	OK	5898	2026-09-14 12:52	73.36	OK
5899	2026-09-14 12:53	70.88	OK	5900	2026-09-14 12:54	73.14	OK
5901	2026-09-14 12:55	73.00	OK	5902	2026-09-14 12:56	72.23	OK
5903	2026-09-14 12:57	73.05	OK	5904	2026-09-14 12:58	70.24	OK
5905	2026-09-14 12:59	71.11	OK	5906	2026-09-14 13:00	71.58	OK
5907	2026-09-14 13:01	74.41	OK	5908	2026-09-14 13:02	72.35	OK
5909	2026-09-14 13:03	71.39	OK	5910	2026-09-14 13:04	70.90	OK
5911	2026-09-14 13:05	72.45	OK	5912	2026-09-14 13:06	72.88	OK
5913	2026-09-14 13:07	73.35	OK	5914	2026-09-14 13:08	70.70	OK
5915	2026-09-14 13:09	73.16	OK	5916	2026-09-14 13:10	72.28	OK
5917	2026-09-14 13:11	69.55	OK	5918	2026-09-14 13:12	73.19	OK
5919	2026-09-14 13:13	72.37	OK	5920	2026-09-14 13:14	70.58	OK
5921	2026-09-14 13:15	73.03	OK	5922	2026-09-14 13:16	72.69	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5923	2026-09-14 13:17	71.45	OK	5924	2026-09-14 13:18	69.72	OK
5925	2026-09-14 13:19	72.85	OK	5926	2026-09-14 13:20	72.47	OK
5927	2026-09-14 13:21	71.68	OK	5928	2026-09-14 13:22	71.95	OK
5929	2026-09-14 13:23	68.42	OK	5930	2026-09-14 13:24	74.50	OK
5931	2026-09-14 13:25	68.69	OK	5932	2026-09-14 13:26	72.31	OK
5933	2026-09-14 13:27	73.76	OK	5934	2026-09-14 13:28	71.78	OK
5935	2026-09-14 13:29	71.04	OK	5936	2026-09-14 13:30	72.55	OK
5937	2026-09-14 13:31	71.13	OK	5938	2026-09-14 13:32	71.30	OK
5939	2026-09-14 13:33	69.73	OK	5940	2026-09-14 13:34	70.34	OK
5941	2026-09-14 13:35	73.65	OK	5942	2026-09-14 13:36	71.28	OK
5943	2026-09-14 13:37	71.04	OK	5944	2026-09-14 13:38	71.46	OK
5945	2026-09-14 13:39	69.83	OK	5946	2026-09-14 13:40	71.03	OK
5947	2026-09-14 13:41	72.77	OK	5948	2026-09-14 13:42	72.95	OK
5949	2026-09-14 13:43	72.39	OK	5950	2026-09-14 13:44	71.90	OK
5951	2026-09-14 13:45	72.16	OK	5952	2026-09-14 13:46	70.51	OK
5953	2026-09-14 13:47	72.18	OK	5954	2026-09-14 13:48	70.39	OK
5955	2026-09-14 13:49	69.56	OK	5956	2026-09-14 13:50	72.85	OK
5957	2026-09-14 13:51	71.06	OK	5958	2026-09-14 13:52	69.17	OK
5959	2026-09-14 13:53	72.36	OK	5960	2026-09-14 13:54	70.47	OK
5961	2026-09-14 13:55	70.30	OK	5962	2026-09-14 13:56	74.46	OK
5963	2026-09-14 13:57	72.42	OK	5964	2026-09-14 13:58	69.34	OK
5965	2026-09-14 13:59	71.72	OK	5966	2026-09-14 14:00	70.86	OK
5967	2026-09-14 14:01	72.40	OK	5968	2026-09-14 14:02	69.98	OK
5969	2026-09-14 14:03	68.45	OK	5970	2026-09-14 14:04	71.24	OK
5971	2026-09-14 14:05	69.62	OK	5972	2026-09-14 14:06	72.58	OK
5973	2026-09-14 14:07	70.90	OK	5974	2026-09-14 14:08	73.38	OK
5975	2026-09-14 14:09	72.72	OK	5976	2026-09-14 14:10	69.39	OK
5977	2026-09-14 14:11	70.22	OK	5978	2026-09-14 14:12	72.44	OK
5979	2026-09-14 14:13	73.10	OK	5980	2026-09-14 14:14	71.16	OK
5981	2026-09-14 14:15	70.44	OK	5982	2026-09-14 14:16	71.39	OK
5983	2026-09-14 14:17	73.40	OK	5984	2026-09-14 14:18	69.56	OK
5985	2026-09-14 14:19	71.97	OK	5986	2026-09-14 14:20	69.94	OK
5987	2026-09-14 14:21	71.89	OK	5988	2026-09-14 14:22	71.70	OK
5989	2026-09-14 14:23	72.06	OK	5990	2026-09-14 14:24	72.67	OK
5991	2026-09-14 14:25	72.76	OK	5992	2026-09-14 14:26	71.22	OK
5993	2026-09-14 14:27	71.79	OK	5994	2026-09-14 14:28	72.07	OK
5995	2026-09-14 14:29	73.80	OK	5996	2026-09-14 14:30	73.27	OK
5997	2026-09-14 14:31	72.08	OK	5998	2026-09-14 14:32	72.86	OK
5999	2026-09-14 14:33	70.45	OK	6000	2026-09-14 14:34	68.04	OK
6001	2026-09-14 14:35	69.29	OK	6002	2026-09-14 14:36	68.11	OK
6003	2026-09-14 14:37	73.73	OK	6004	2026-09-14 14:38	71.63	OK
6005	2026-09-14 14:39	70.08	OK	6006	2026-09-14 14:40	71.51	OK
6007	2026-09-14 14:41	69.61	OK	6008	2026-09-14 14:42	69.95	OK
6009	2026-09-14 14:43	69.53	OK	6010	2026-09-14 14:44	71.95	OK
6011	2026-09-14 14:45	73.02	OK	6012	2026-09-14 14:46	70.97	OK
6013	2026-09-14 14:47	72.21	OK	6014	2026-09-14 14:48	72.89	OK
6015	2026-09-14 14:49	72.02	OK	6016	2026-09-14 14:50	69.06	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6017	2026-09-14 14:51	72.15	OK	6018	2026-09-14 14:52	70.80	OK
6019	2026-09-14 14:53	71.11	OK	6020	2026-09-14 14:54	69.68	OK
6021	2026-09-14 14:55	72.21	OK	6022	2026-09-14 14:56	71.95	OK
6023	2026-09-14 14:57	69.72	OK	6024	2026-09-14 14:58	71.39	OK
6025	2026-09-14 14:59	69.75	OK	6026	2026-09-14 15:00	70.62	OK
6027	2026-09-14 15:01	72.54	OK	6028	2026-09-14 15:02	73.10	OK
6029	2026-09-14 15:03	70.32	OK	6030	2026-09-14 15:04	71.36	OK
6031	2026-09-14 15:05	69.65	OK	6032	2026-09-14 15:06	73.01	OK
6033	2026-09-14 15:07	72.72	OK	6034	2026-09-14 15:08	71.37	OK
6035	2026-09-14 15:09	71.11	OK	6036	2026-09-14 15:10	70.66	OK
6037	2026-09-14 15:11	72.40	OK	6038	2026-09-14 15:12	72.81	OK
6039	2026-09-14 15:13	69.35	OK	6040	2026-09-14 15:14	70.91	OK
6041	2026-09-14 15:15	71.22	OK	6042	2026-09-14 15:16	71.87	OK
6043	2026-09-14 15:17	70.60	OK	6044	2026-09-14 15:18	71.05	OK
6045	2026-09-14 15:19	70.39	OK	6046	2026-09-14 15:20	72.34	OK
6047	2026-09-14 15:21	72.08	OK	6048	2026-09-14 15:22	71.95	OK
6049	2026-09-14 15:23	70.58	OK	6050	2026-09-14 15:24	73.07	OK
6051	2026-09-14 15:25	71.55	OK	6052	2026-09-14 15:26	69.15	OK
6053	2026-09-14 15:27	68.18	OK	6054	2026-09-14 15:28	71.59	OK
6055	2026-09-14 15:29	70.16	OK	6056	2026-09-14 15:30	72.83	OK
6057	2026-09-14 15:31	71.57	OK	6058	2026-09-14 15:32	68.75	OK
6059	2026-09-14 15:33	71.85	OK	6060	2026-09-14 15:34	70.72	OK
6061	2026-09-14 15:35	70.72	OK	6062	2026-09-14 15:36	72.38	OK
6063	2026-09-14 15:37	72.37	OK	6064	2026-09-14 15:38	70.24	OK
6065	2026-09-14 15:39	70.54	OK	6066	2026-09-14 15:40	70.05	OK
6067	2026-09-14 15:41	71.83	OK	6068	2026-09-14 15:42	68.88	OK
6069	2026-09-14 15:43	71.59	OK	6070	2026-09-14 15:44	71.33	OK
6071	2026-09-14 15:45	71.93	OK	6072	2026-09-14 15:46	72.06	OK
6073	2026-09-14 15:47	69.29	OK	6074	2026-09-14 15:48	73.91	OK
6075	2026-09-14 15:49	70.39	OK	6076	2026-09-14 15:50	72.50	OK
6077	2026-09-14 15:51	70.41	OK	6078	2026-09-14 15:52	72.94	OK
6079	2026-09-14 15:53	71.49	OK	6080	2026-09-14 15:54	69.23	OK
6081	2026-09-14 15:55	70.07	OK	6082	2026-09-14 15:56	74.29	OK
6083	2026-09-14 15:57	73.25	OK	6084	2026-09-14 15:58	71.71	OK
6085	2026-09-14 15:59	74.41	OK	6086	2026-09-14 16:00	72.50	OK
6087	2026-09-14 16:01	73.08	OK	6088	2026-09-14 16:02	69.58	OK
6089	2026-09-14 16:03	70.84	OK	6090	2026-09-14 16:04	73.09	OK
6091	2026-09-14 16:05	70.57	OK	6092	2026-09-14 16:06	72.87	OK
6093	2026-09-14 16:07	72.93	OK	6094	2026-09-14 16:08	72.68	OK
6095	2026-09-14 16:09	69.92	OK	6096	2026-09-14 16:10	70.57	OK
6097	2026-09-14 16:11	71.28	OK	6098	2026-09-14 16:12	73.17	OK
6099	2026-09-14 16:13	71.30	OK	6100	2026-09-14 16:14	73.32	OK
6101	2026-09-14 16:15	69.28	OK	6102	2026-09-14 16:16	71.14	OK
6103	2026-09-14 16:17	72.90	OK	6104	2026-09-14 16:18	71.41	OK
6105	2026-09-14 16:19	74.18	OK	6106	2026-09-14 16:20	73.48	OK
6107	2026-09-14 16:21	72.76	OK	6108	2026-09-14 16:22	72.66	OK
6109	2026-09-14 16:23	71.01	OK	6110	2026-09-14 16:24	72.65	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6111	2026-09-14 16:25	71.64	OK	6112	2026-09-14 16:26	71.15	OK
6113	2026-09-14 16:27	72.62	OK	6114	2026-09-14 16:28	71.78	OK
6115	2026-09-14 16:29	71.55	OK	6116	2026-09-14 16:30	71.25	OK
6117	2026-09-14 16:31	73.83	OK	6118	2026-09-14 16:32	71.52	OK
6119	2026-09-14 16:33	72.21	OK	6120	2026-09-14 16:34	71.04	OK
6121	2026-09-14 16:35	71.00	OK	6122	2026-09-14 16:36	72.83	OK
6123	2026-09-14 16:37	73.32	OK	6124	2026-09-14 16:38	73.69	OK
6125	2026-09-14 16:39	70.23	OK	6126	2026-09-14 16:40	71.50	OK
6127	2026-09-14 16:41	72.68	OK	6128	2026-09-14 16:42	70.18	OK
6129	2026-09-14 16:43	73.31	OK	6130	2026-09-14 16:44	70.78	OK
6131	2026-09-14 16:45	71.67	OK	6132	2026-09-14 16:46	72.11	OK
6133	2026-09-14 16:47	70.21	OK	6134	2026-09-14 16:48	68.81	OK
6135	2026-09-14 16:49	71.14	OK	6136	2026-09-14 16:50	72.67	OK
6137	2026-09-14 16:51	69.48	OK	6138	2026-09-14 16:52	72.97	OK
6139	2026-09-14 16:53	72.91	OK	6140	2026-09-14 16:54	72.74	OK
6141	2026-09-14 16:55	72.88	OK	6142	2026-09-14 16:56	74.22	OK
6143	2026-09-14 16:57	72.40	OK	6144	2026-09-14 16:58	72.14	OK
6145	2026-09-14 16:59	73.45	OK	6146	2026-09-14 17:00	71.57	OK
6147	2026-09-14 17:01	70.92	OK	6148	2026-09-14 17:02	70.83	OK
6149	2026-09-14 17:03	71.61	OK	6150	2026-09-14 17:04	69.52	OK
6151	2026-09-14 17:05	71.47	OK	6152	2026-09-14 17:06	73.85	OK
6153	2026-09-14 17:07	72.39	OK	6154	2026-09-14 17:08	72.76	OK
6155	2026-09-14 17:09	70.96	OK	6156	2026-09-14 17:10	74.87	OK
6157	2026-09-14 17:11	72.98	OK	6158	2026-09-14 17:12	71.05	OK
6159	2026-09-14 17:13	71.98	OK	6160	2026-09-14 17:14	70.79	OK
6161	2026-09-14 17:15	72.56	OK	6162	2026-09-14 17:16	73.76	OK
6163	2026-09-14 17:17	72.59	OK	6164	2026-09-14 17:18	71.05	OK
6165	2026-09-14 17:19	71.16	OK	6166	2026-09-14 17:20	71.29	OK
6167	2026-09-14 17:21	70.45	OK	6168	2026-09-14 17:22	73.00	OK
6169	2026-09-14 17:23	71.83	OK	6170	2026-09-14 17:24	70.42	OK
6171	2026-09-14 17:25	70.60	OK	6172	2026-09-14 17:26	71.08	OK
6173	2026-09-14 17:27	72.63	OK	6174	2026-09-14 17:28	72.06	OK
6175	2026-09-14 17:29	71.23	OK	6176	2026-09-14 17:30	70.33	OK
6177	2026-09-14 17:31	72.52	OK	6178	2026-09-14 17:32	71.54	OK
6179	2026-09-14 17:33	70.52	OK	6180	2026-09-14 17:34	72.52	OK
6181	2026-09-14 17:35	74.00	OK	6182	2026-09-14 17:36	70.69	OK
6183	2026-09-14 17:37	71.70	OK	6184	2026-09-14 17:38	72.87	OK
6185	2026-09-14 17:39	71.43	OK	6186	2026-09-14 17:40	72.20	OK
6187	2026-09-14 17:41	72.32	OK	6188	2026-09-14 17:42	73.64	OK
6189	2026-09-14 17:43	72.91	OK	6190	2026-09-14 17:44	73.68	OK
6191	2026-09-14 17:45	71.95	OK	6192	2026-09-14 17:46	71.94	OK
6193	2026-09-14 17:47	71.49	OK	6194	2026-09-14 17:48	74.82	OK
6195	2026-09-14 17:49	73.02	OK	6196	2026-09-14 17:50	71.60	OK
6197	2026-09-14 17:51	73.65	OK	6198	2026-09-14 17:52	75.51	OK
6199	2026-09-14 17:53	72.64	OK	6200	2026-09-14 17:54	72.25	OK
6201	2026-09-14 17:55	72.80	OK	6202	2026-09-14 17:56	71.86	OK
6203	2026-09-14 17:57	73.24	OK	6204	2026-09-14 17:58	74.44	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6205	2026-09-14 17:59	73.62	OK	6206	2026-09-14 18:00	74.81	OK
6207	2026-09-14 18:01	74.55	OK	6208	2026-09-14 18:02	71.92	OK
6209	2026-09-14 18:03	73.44	OK	6210	2026-09-14 18:04	73.55	OK
6211	2026-09-14 18:05	71.29	OK	6212	2026-09-14 18:06	74.95	OK
6213	2026-09-14 18:07	74.34	OK	6214	2026-09-14 18:08	72.96	OK
6215	2026-09-14 18:09	73.86	OK	6216	2026-09-14 18:10	74.55	OK
6217	2026-09-14 18:11	72.07	OK	6218	2026-09-14 18:12	71.56	OK
6219	2026-09-14 18:13	72.66	OK	6220	2026-09-14 18:14	73.05	OK
6221	2026-09-14 18:15	75.32	OK	6222	2026-09-14 18:16	71.35	OK
6223	2026-09-14 18:17	72.87	OK	6224	2026-09-14 18:18	73.35	OK
6225	2026-09-14 18:19	73.88	OK	6226	2026-09-14 18:20	71.57	OK
6227	2026-09-14 18:21	74.46	OK	6228	2026-09-14 18:22	71.03	OK
6229	2026-09-14 18:23	74.05	OK	6230	2026-09-14 18:24	75.35	OK
6231	2026-09-14 18:25	74.12	OK	6232	2026-09-14 18:26	71.68	OK
6233	2026-09-14 18:27	72.92	OK	6234	2026-09-14 18:28	73.96	OK
6235	2026-09-14 18:29	73.74	OK	6236	2026-09-14 18:30	72.98	OK
6237	2026-09-14 18:31	73.49	OK	6238	2026-09-14 18:32	72.98	OK
6239	2026-09-14 18:33	73.26	OK	6240	2026-09-14 18:34	75.03	OK
6241	2026-09-14 18:35	74.05	OK	6242	2026-09-14 18:36	73.70	OK
6243	2026-09-14 18:37	75.36	OK	6244	2026-09-14 18:38	73.58	OK
6245	2026-09-14 18:39	76.24	OK	6246	2026-09-14 18:40	74.24	OK
6247	2026-09-14 18:41	73.43	OK	6248	2026-09-14 18:42	73.57	OK
6249	2026-09-14 18:43	74.05	OK	6250	2026-09-14 18:44	74.69	OK
6251	2026-09-14 18:45	74.75	OK	6252	2026-09-14 18:46	73.34	OK
6253	2026-09-14 18:47	76.62	OK	6254	2026-09-14 18:48	73.21	OK
6255	2026-09-14 18:49	71.67	OK	6256	2026-09-14 18:50	75.87	OK
6257	2026-09-14 18:51	74.19	OK	6258	2026-09-14 18:52	74.42	OK
6259	2026-09-14 18:53	73.75	OK	6260	2026-09-14 18:54	74.68	OK
6261	2026-09-14 18:55	76.08	OK	6262	2026-09-14 18:56	75.03	OK
6263	2026-09-14 18:57	75.19	OK	6264	2026-09-14 18:58	73.20	OK
6265	2026-09-14 18:59	75.11	OK	6266	2026-09-14 19:00	73.53	OK
6267	2026-09-14 19:01	76.29	OK	6268	2026-09-14 19:02	73.38	OK
6269	2026-09-14 19:03	76.24	OK	6270	2026-09-14 19:04	74.59	OK
6271	2026-09-14 19:05	74.54	OK	6272	2026-09-14 19:06	71.55	OK
6273	2026-09-14 19:07	71.73	OK	6274	2026-09-14 19:08	75.91	OK
6275	2026-09-14 19:09	74.95	OK	6276	2026-09-14 19:10	74.61	OK
6277	2026-09-14 19:11	73.39	OK	6278	2026-09-14 19:12	74.62	OK
6279	2026-09-14 19:13	74.56	OK	6280	2026-09-14 19:14	72.56	OK
6281	2026-09-14 19:15	73.76	OK	6282	2026-09-14 19:16	74.66	OK
6283	2026-09-14 19:17	74.34	OK	6284	2026-09-14 19:18	74.92	OK
6285	2026-09-14 19:19	73.60	OK	6286	2026-09-14 19:20	75.65	OK
6287	2026-09-14 19:21	74.34	OK	6288	2026-09-14 19:22	74.62	OK
6289	2026-09-14 19:23	74.59	OK	6290	2026-09-14 19:24	77.63	OK
6291	2026-09-14 19:25	74.84	OK	6292	2026-09-14 19:26	73.97	OK
6293	2026-09-14 19:27	75.40	OK	6294	2026-09-14 19:28	75.32	OK
6295	2026-09-14 19:29	76.97	OK	6296	2026-09-14 19:30	76.62	OK
6297	2026-09-14 19:31	73.83	OK	6298	2026-09-14 19:32	73.06	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6299	2026-09-14 19:33	75.94	OK	6300	2026-09-14 19:34	74.56	OK
6301	2026-09-14 19:35	74.03	OK	6302	2026-09-14 19:36	72.65	OK
6303	2026-09-14 19:37	73.96	OK	6304	2026-09-14 19:38	73.71	OK
6305	2026-09-14 19:39	75.13	OK	6306	2026-09-14 19:40	73.28	OK
6307	2026-09-14 19:41	73.98	OK	6308	2026-09-14 19:42	73.72	OK
6309	2026-09-14 19:43	76.93	OK	6310	2026-09-14 19:44	74.76	OK
6311	2026-09-14 19:45	75.68	OK	6312	2026-09-14 19:46	75.21	OK
6313	2026-09-14 19:47	75.54	OK	6314	2026-09-14 19:48	72.48	OK
6315	2026-09-14 19:49	77.52	OK	6316	2026-09-14 19:50	73.70	OK
6317	2026-09-14 19:51	75.37	OK	6318	2026-09-14 19:52	77.60	OK
6319	2026-09-14 19:53	74.02	OK	6320	2026-09-14 19:54	74.77	OK
6321	2026-09-14 19:55	75.94	OK	6322	2026-09-14 19:56	74.25	OK
6323	2026-09-14 19:57	77.08	OK	6324	2026-09-14 19:58	76.09	OK
6325	2026-09-14 19:59	76.77	OK	6326	2026-09-14 20:00	75.57	OK
6327	2026-09-14 20:01	76.33	OK	6328	2026-09-14 20:02	76.50	OK
6329	2026-09-14 20:03	74.68	OK	6330	2026-09-14 20:04	74.04	OK
6331	2026-09-14 20:05	74.37	OK	6332	2026-09-14 20:06	77.19	OK
6333	2026-09-14 20:07	75.78	OK	6334	2026-09-14 20:08	75.25	OK
6335	2026-09-14 20:09	75.75	OK	6336	2026-09-14 20:10	75.34	OK
6337	2026-09-14 20:11	77.24	OK	6338	2026-09-14 20:12	75.56	OK
6339	2026-09-14 20:13	73.59	OK	6340	2026-09-14 20:14	73.36	OK
6341	2026-09-14 20:15	76.26	OK	6342	2026-09-14 20:16	77.21	OK
6343	2026-09-14 20:17	74.08	OK	6344	2026-09-14 20:18	74.92	OK
6345	2026-09-14 20:19	76.50	OK	6346	2026-09-14 20:20	74.99	OK
6347	2026-09-14 20:21	74.20	OK	6348	2026-09-14 20:22	74.73	OK
6349	2026-09-14 20:23	76.76	OK	6350	2026-09-14 20:24	74.40	OK
6351	2026-09-14 20:25	76.52	OK	6352	2026-09-14 20:26	76.41	OK
6353	2026-09-14 20:27	75.20	OK	6354	2026-09-14 20:28	76.11	OK
6355	2026-09-14 20:29	77.96	OK	6356	2026-09-14 20:30	76.76	OK
6357	2026-09-14 20:31	75.24	OK	6358	2026-09-14 20:32	73.40	OK
6359	2026-09-14 20:33	74.82	OK	6360	2026-09-14 20:34	76.21	OK
6361	2026-09-14 20:35	78.12	OK	6362	2026-09-14 20:36	76.70	OK
6363	2026-09-14 20:37	76.11	OK	6364	2026-09-14 20:38	75.38	OK
6365	2026-09-14 20:39	75.99	OK	6366	2026-09-14 20:40	74.49	OK
6367	2026-09-14 20:41	76.62	OK	6368	2026-09-14 20:42	76.36	OK
6369	2026-09-14 20:43	76.13	OK	6370	2026-09-14 20:44	75.92	OK
6371	2026-09-14 20:45	78.66	OK	6372	2026-09-14 20:46	76.08	OK
6373	2026-09-14 20:47	78.90	OK	6374	2026-09-14 20:48	75.86	OK
6375	2026-09-14 20:49	76.50	OK	6376	2026-09-14 20:50	76.21	OK
6377	2026-09-14 20:51	76.70	OK	6378	2026-09-14 20:52	76.37	OK
6379	2026-09-14 20:53	76.72	OK	6380	2026-09-14 20:54	76.23	OK
6381	2026-09-14 20:55	76.59	OK	6382	2026-09-14 20:56	74.57	OK
6383	2026-09-14 20:57	75.29	OK	6384	2026-09-14 20:58	76.35	OK
6385	2026-09-14 20:59	74.73	OK	6386	2026-09-14 21:00	76.09	OK
6387	2026-09-14 21:01	75.14	OK	6388	2026-09-14 21:02	76.23	OK
6389	2026-09-14 21:03	75.71	OK	6390	2026-09-14 21:04	75.99	OK
6391	2026-09-14 21:05	78.71	OK	6392	2026-09-14 21:06	78.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6393	2026-09-14 21:07	76.06	OK	6394	2026-09-14 21:08	79.46	OK
6395	2026-09-14 21:09	75.20	OK	6396	2026-09-14 21:10	79.10	OK
6397	2026-09-14 21:11	75.56	OK	6398	2026-09-14 21:12	75.37	OK
6399	2026-09-14 21:13	74.83	OK	6400	2026-09-14 21:14	75.74	OK
6401	2026-09-14 21:15	77.11	OK	6402	2026-09-14 21:16	77.06	OK
6403	2026-09-14 21:17	78.35	OK	6404	2026-09-14 21:18	78.07	OK
6405	2026-09-14 21:19	78.05	OK	6406	2026-09-14 21:20	77.48	OK
6407	2026-09-14 21:21	77.32	OK	6408	2026-09-14 21:22	78.06	OK
6409	2026-09-14 21:23	79.48	OK	6410	2026-09-14 21:24	78.85	OK
6411	2026-09-14 21:25	77.46	OK	6412	2026-09-14 21:26	76.57	OK
6413	2026-09-14 21:27	79.97	OK	6414	2026-09-14 21:28	78.20	OK
6415	2026-09-14 21:29	77.69	OK	6416	2026-09-14 21:30	76.72	OK
6417	2026-09-14 21:31	75.35	OK	6418	2026-09-14 21:32	76.78	OK
6419	2026-09-14 21:33	77.08	OK	6420	2026-09-14 21:34	77.62	OK
6421	2026-09-14 21:35	77.60	OK	6422	2026-09-14 21:36	77.68	OK
6423	2026-09-14 21:37	77.11	OK	6424	2026-09-14 21:38	76.94	OK
6425	2026-09-14 21:39	77.08	OK	6426	2026-09-14 21:40	77.24	OK
6427	2026-09-14 21:41	79.02	OK	6428	2026-09-14 21:42	80.42	OK
6429	2026-09-14 21:43	76.90	OK	6430	2026-09-14 21:44	75.28	OK
6431	2026-09-14 21:45	78.34	OK	6432	2026-09-14 21:46	76.87	OK
6433	2026-09-14 21:47	78.76	OK	6434	2026-09-14 21:48	74.85	OK
6435	2026-09-14 21:49	77.83	OK	6436	2026-09-14 21:50	78.06	OK
6437	2026-09-14 21:51	75.87	OK	6438	2026-09-14 21:52	76.82	OK
6439	2026-09-14 21:53	76.85	OK	6440	2026-09-14 21:54	80.32	OK
6441	2026-09-14 21:55	78.46	OK	6442	2026-09-14 21:56	78.81	OK
6443	2026-09-14 21:57	77.40	OK	6444	2026-09-14 21:58	79.71	OK
6445	2026-09-14 21:59	77.85	OK	6446	2026-09-14 22:00	75.48	OK
6447	2026-09-14 22:01	80.12	OK	6448	2026-09-14 22:02	78.42	OK
6449	2026-09-14 22:03	78.66	OK	6450	2026-09-14 22:04	78.83	OK
6451	2026-09-14 22:05	78.38	OK	6452	2026-09-14 22:06	79.39	OK
6453	2026-09-14 22:07	78.39	OK	6454	2026-09-14 22:08	79.49	OK
6455	2026-09-14 22:09	78.12	OK	6456	2026-09-14 22:10	79.72	OK
6457	2026-09-14 22:11	77.66	OK	6458	2026-09-14 22:12	77.33	OK
6459	2026-09-14 22:13	78.51	OK	6460	2026-09-14 22:14	78.45	OK
6461	2026-09-14 22:15	76.63	OK	6462	2026-09-14 22:16	79.24	OK
6463	2026-09-14 22:17	78.67	OK	6464	2026-09-14 22:18	79.03	OK
6465	2026-09-14 22:19	79.22	OK	6466	2026-09-14 22:20	77.46	OK
6467	2026-09-14 22:21	78.59	OK	6468	2026-09-14 22:22	78.16	OK
6469	2026-09-14 22:23	78.00	OK	6470	2026-09-14 22:24	80.95	OK
6471	2026-09-14 22:25	78.47	OK	6472	2026-09-14 22:26	79.03	OK
6473	2026-09-14 22:27	77.24	OK	6474	2026-09-14 22:28	79.09	OK
6475	2026-09-14 22:29	78.95	OK	6476	2026-09-14 22:30	77.42	OK
6477	2026-09-14 22:31	79.27	OK	6478	2026-09-14 22:32	76.92	OK
6479	2026-09-14 22:33	80.27	OK	6480	2026-09-14 22:34	79.27	OK
6481	2026-09-14 22:35	78.70	OK	6482	2026-09-14 22:36	77.92	OK
6483	2026-09-14 22:37	75.43	OK	6484	2026-09-14 22:38	79.77	OK
6485	2026-09-14 22:39	77.49	OK	6486	2026-09-14 22:40	78.49	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6487	2026-09-14 22:41	78.60	OK	6488	2026-09-14 22:42	79.39	OK
6489	2026-09-14 22:43	79.62	OK	6490	2026-09-14 22:44	77.60	OK
6491	2026-09-14 22:45	76.33	OK	6492	2026-09-14 22:46	78.55	OK
6493	2026-09-14 22:47	80.37	OK	6494	2026-09-14 22:48	79.66	OK
6495	2026-09-14 22:49	79.17	OK	6496	2026-09-14 22:50	78.67	OK
6497	2026-09-14 22:51	77.87	OK	6498	2026-09-14 22:52	79.07	OK
6499	2026-09-14 22:53	82.52	OK	6500	2026-09-14 22:54	79.76	OK
6501	2026-09-14 22:55	80.11	OK	6502	2026-09-14 22:56	77.26	OK
6503	2026-09-14 22:57	79.85	OK	6504	2026-09-14 22:58	78.67	OK
6505	2026-09-14 22:59	79.75	OK	6506	2026-09-14 23:00	78.56	OK
6507	2026-09-14 23:01	80.07	OK	6508	2026-09-14 23:02	78.35	OK
6509	2026-09-14 23:03	80.03	OK	6510	2026-09-14 23:04	80.04	OK
6511	2026-09-14 23:05	80.16	OK	6512	2026-09-14 23:06	81.67	OK
6513	2026-09-14 23:07	79.56	OK	6514	2026-09-14 23:08	82.07	OK
6515	2026-09-14 23:09	78.78	OK	6516	2026-09-14 23:10	77.84	OK
6517	2026-09-14 23:11	81.34	OK	6518	2026-09-14 23:12	81.53	OK
6519	2026-09-14 23:13	80.41	OK	6520	2026-09-14 23:14	80.52	OK
6521	2026-09-14 23:15	79.30	OK	6522	2026-09-14 23:16	79.65	OK
6523	2026-09-14 23:17	79.13	OK	6524	2026-09-14 23:18	80.92	OK
6525	2026-09-14 23:19	80.21	OK	6526	2026-09-14 23:20	79.70	OK
6527	2026-09-14 23:21	79.86	OK	6528	2026-09-14 23:22	81.57	OK
6529	2026-09-14 23:23	81.97	OK	6530	2026-09-14 23:24	80.66	OK
6531	2026-09-14 23:25	77.88	OK	6532	2026-09-14 23:26	80.59	OK
6533	2026-09-14 23:27	78.01	OK	6534	2026-09-14 23:28	80.99	OK
6535	2026-09-14 23:29	81.14	OK	6536	2026-09-14 23:30	79.87	OK
6537	2026-09-14 23:31	78.74	OK	6538	2026-09-14 23:32	78.70	OK
6539	2026-09-14 23:33	81.14	OK	6540	2026-09-14 23:34	79.61	OK
6541	2026-09-14 23:35	81.26	OK	6542	2026-09-14 23:36	80.80	OK
6543	2026-09-14 23:37	81.40	OK	6544	2026-09-14 23:38	82.32	OK
6545	2026-09-14 23:39	81.16	OK	6546	2026-09-14 23:40	82.70	OK
6547	2026-09-14 23:41	77.48	OK	6548	2026-09-14 23:42	79.85	OK
6549	2026-09-14 23:43	78.32	OK	6550	2026-09-14 23:44	80.52	OK
6551	2026-09-14 23:45	79.42	OK	6552	2026-09-14 23:46	80.30	OK
6553	2026-09-14 23:47	79.26	OK	6554	2026-09-14 23:48	81.37	OK
6555	2026-09-14 23:49	80.39	OK	6556	2026-09-14 23:50	80.56	OK
6557	2026-09-14 23:51	81.31	OK	6558	2026-09-14 23:52	79.76	OK
6559	2026-09-14 23:53	81.43	OK	6560	2026-09-14 23:54	79.85	OK
6561	2026-09-14 23:55	80.11	OK	6562	2026-09-14 23:56	80.63	OK
6563	2026-09-14 23:57	80.36	OK	6564	2026-09-14 23:58	81.87	OK
6565	2026-09-14 23:59	82.77	OK	6566	2026-09-15 00:00	80.84	OK
6567	2026-09-15 00:01	79.43	OK	6568	2026-09-15 00:02	82.09	OK
6569	2026-09-15 00:03	80.21	OK	6570	2026-09-15 00:04	80.99	OK
6571	2026-09-15 00:05	81.26	OK	6572	2026-09-15 00:06	80.76	OK
6573	2026-09-15 00:07	78.34	OK	6574	2026-09-15 00:08	81.84	OK
6575	2026-09-15 00:09	81.64	OK	6576	2026-09-15 00:10	82.00	OK
6577	2026-09-15 00:11	79.48	OK	6578	2026-09-15 00:12	81.18	OK
6579	2026-09-15 00:13	82.08	OK	6580	2026-09-15 00:14	79.01	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6581	2026-09-15 00:15	78.68	OK	6582	2026-09-15 00:16	79.99	OK
6583	2026-09-15 00:17	80.66	OK	6584	2026-09-15 00:18	79.74	OK
6585	2026-09-15 00:19	79.32	OK	6586	2026-09-15 00:20	78.34	OK
6587	2026-09-15 00:21	81.12	OK	6588	2026-09-15 00:22	80.12	OK
6589	2026-09-15 00:23	78.00	OK	6590	2026-09-15 00:24	81.31	OK
6591	2026-09-15 00:25	81.11	OK	6592	2026-09-15 00:26	82.70	OK
6593	2026-09-15 00:27	78.68	OK	6594	2026-09-15 00:28	80.25	OK
6595	2026-09-15 00:29	80.67	OK	6596	2026-09-15 00:30	81.91	OK
6597	2026-09-15 00:31	78.07	OK	6598	2026-09-15 00:32	80.90	OK
6599	2026-09-15 00:33	80.85	OK	6600	2026-09-15 00:34	80.59	OK
6601	2026-09-15 00:35	80.96	OK	6602	2026-09-15 00:36	82.59	OK
6603	2026-09-15 00:37	81.89	OK	6604	2026-09-15 00:38	82.31	OK
6605	2026-09-15 00:39	81.60	OK	6606	2026-09-15 00:40	81.03	OK
6607	2026-09-15 00:41	81.78	OK	6608	2026-09-15 00:42	81.19	OK
6609	2026-09-15 00:43	79.01	OK	6610	2026-09-15 00:44	83.19	OK
6611	2026-09-15 00:45	80.33	OK	6612	2026-09-15 00:46	79.24	OK
6613	2026-09-15 00:47	81.31	OK	6614	2026-09-15 00:48	80.54	OK
6615	2026-09-15 00:49	84.51	OK	6616	2026-09-15 00:50	83.68	OK
6617	2026-09-15 00:51	82.28	OK	6618	2026-09-15 00:52	81.99	OK
6619	2026-09-15 00:53	81.53	OK	6620	2026-09-15 00:54	81.62	OK
6621	2026-09-15 00:55	79.09	OK	6622	2026-09-15 00:56	80.58	OK
6623	2026-09-15 00:57	81.14	OK	6624	2026-09-15 00:58	81.37	OK
6625	2026-09-15 00:59	80.32	OK	6626	2026-09-15 01:00	81.16	OK
6627	2026-09-15 01:01	78.71	OK	6628	2026-09-15 01:02	83.25	OK
6629	2026-09-15 01:03	84.26	OK	6630	2026-09-15 01:04	81.59	OK
6631	2026-09-15 01:05	80.94	OK	6632	2026-09-15 01:06	81.56	OK
6633	2026-09-15 01:07	80.65	OK	6634	2026-09-15 01:08	82.14	OK
6635	2026-09-15 01:09	80.11	OK	6636	2026-09-15 01:10	80.51	OK
6637	2026-09-15 01:11	83.20	OK	6638	2026-09-15 01:12	80.82	OK
6639	2026-09-15 01:13	81.06	OK	6640	2026-09-15 01:14	81.03	OK
6641	2026-09-15 01:15	79.29	OK	6642	2026-09-15 01:16	81.66	OK
6643	2026-09-15 01:17	82.72	OK	6644	2026-09-15 01:18	79.27	OK
6645	2026-09-15 01:19	81.37	OK	6646	2026-09-15 01:20	83.99	OK
6647	2026-09-15 01:21	81.06	OK	6648	2026-09-15 01:22	81.40	OK
6649	2026-09-15 01:23	80.51	OK	6650	2026-09-15 01:24	82.41	OK
6651	2026-09-15 01:25	81.22	OK	6652	2026-09-15 01:26	80.74	OK
6653	2026-09-15 01:27	82.05	OK	6654	2026-09-15 01:28	83.17	OK
6655	2026-09-15 01:29	81.04	OK	6656	2026-09-15 01:30	82.83	OK
6657	2026-09-15 01:31	80.74	OK	6658	2026-09-15 01:32	83.00	OK
6659	2026-09-15 01:33	79.71	OK	6660	2026-09-15 01:34	82.13	OK
6661	2026-09-15 01:35	81.79	OK	6662	2026-09-15 01:36	82.68	OK
6663	2026-09-15 01:37	80.94	OK	6664	2026-09-15 01:38	82.24	OK
6665	2026-09-15 01:39	80.30	OK	6666	2026-09-15 01:40	81.57	OK
6667	2026-09-15 01:41	82.77	OK	6668	2026-09-15 01:42	83.58	OK
6669	2026-09-15 01:43	84.61	OK	6670	2026-09-15 01:44	82.96	OK
6671	2026-09-15 01:45	82.19	OK	6672	2026-09-15 01:46	81.60	OK
6673	2026-09-15 01:47	80.91	OK	6674	2026-09-15 01:48	81.02	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6675	2026-09-15 01:49	82.58	OK	6676	2026-09-15 01:50	81.31	OK
6677	2026-09-15 01:51	81.68	OK	6678	2026-09-15 01:52	81.06	OK
6679	2026-09-15 01:53	81.48	OK	6680	2026-09-15 01:54	80.96	OK
6681	2026-09-15 01:55	81.97	OK	6682	2026-09-15 01:56	80.53	OK
6683	2026-09-15 01:57	82.38	OK	6684	2026-09-15 01:58	82.46	OK
6685	2026-09-15 01:59	79.86	OK	6686	2026-09-15 02:00	82.82	OK
6687	2026-09-15 02:01	82.82	OK	6688	2026-09-15 02:02	81.60	OK
6689	2026-09-15 02:03	84.07	OK	6690	2026-09-15 02:04	81.06	OK
6691	2026-09-15 02:05	80.31	OK	6692	2026-09-15 02:06	83.40	OK
6693	2026-09-15 02:07	79.96	OK	6694	2026-09-15 02:08	80.25	OK
6695	2026-09-15 02:09	81.15	OK	6696	2026-09-15 02:10	80.77	OK
6697	2026-09-15 02:11	82.88	OK	6698	2026-09-15 02:12	81.89	OK
6699	2026-09-15 02:13	80.53	OK	6700	2026-09-15 02:14	82.07	OK
6701	2026-09-15 02:15	78.86	OK	6702	2026-09-15 02:16	81.96	OK
6703	2026-09-15 02:17	82.93	OK	6704	2026-09-15 02:18	82.61	OK
6705	2026-09-15 02:19	79.40	OK	6706	2026-09-15 02:20	81.74	OK
6707	2026-09-15 02:21	82.06	OK	6708	2026-09-15 02:22	81.26	OK
6709	2026-09-15 02:23	82.23	OK	6710	2026-09-15 02:24	80.93	OK
6711	2026-09-15 02:25	82.14	OK	6712	2026-09-15 02:26	82.99	OK
6713	2026-09-15 02:27	79.36	OK	6714	2026-09-15 02:28	81.19	OK
6715	2026-09-15 02:29	81.39	OK	6716	2026-09-15 02:30	80.58	OK
6717	2026-09-15 02:31	79.72	OK	6718	2026-09-15 02:32	82.97	OK
6719	2026-09-15 02:33	82.85	OK	6720	2026-09-15 02:34	82.08	OK
6721	2026-09-15 02:35	84.34	OK	6722	2026-09-15 02:36	79.54	OK
6723	2026-09-15 02:37	82.15	OK	6724	2026-09-15 02:38	81.46	OK
6725	2026-09-15 02:39	82.18	OK	6726	2026-09-15 02:40	81.09	OK
6727	2026-09-15 02:41	79.81	OK	6728	2026-09-15 02:42	81.89	OK
6729	2026-09-15 02:43	82.55	OK	6730	2026-09-15 02:44	83.18	OK
6731	2026-09-15 02:45	80.09	OK	6732	2026-09-15 02:46	83.78	OK
6733	2026-09-15 02:47	82.89	OK	6734	2026-09-15 02:48	83.02	OK
6735	2026-09-15 02:49	82.30	OK	6736	2026-09-15 02:50	84.17	OK
6737	2026-09-15 02:51	81.88	OK	6738	2026-09-15 02:52	82.45	OK
6739	2026-09-15 02:53	81.09	OK	6740	2026-09-15 02:54	82.41	OK
6741	2026-09-15 02:55	81.68	OK	6742	2026-09-15 02:56	80.35	OK
6743	2026-09-15 02:57	80.78	OK	6744	2026-09-15 02:58	84.61	OK
6745	2026-09-15 02:59	79.19	OK	6746	2026-09-15 03:00	80.21	OK
6747	2026-09-15 03:01	82.79	OK	6748	2026-09-15 03:02	82.00	OK
6749	2026-09-15 03:03	81.89	OK	6750	2026-09-15 03:04	81.85	OK
6751	2026-09-15 03:05	80.81	OK	6752	2026-09-15 03:06	80.72	OK
6753	2026-09-15 03:07	81.49	OK	6754	2026-09-15 03:08	81.53	OK
6755	2026-09-15 03:09	81.59	OK	6756	2026-09-15 03:10	83.75	OK
6757	2026-09-15 03:11	80.92	OK	6758	2026-09-15 03:12	80.20	OK
6759	2026-09-15 03:13	81.00	OK	6760	2026-09-15 03:14	81.51	OK
6761	2026-09-15 03:15	81.98	OK	6762	2026-09-15 03:16	82.00	OK
6763	2026-09-15 03:17	82.52	OK	6764	2026-09-15 03:18	80.60	OK
6765	2026-09-15 03:19	82.20	OK	6766	2026-09-15 03:20	83.03	OK
6767	2026-09-15 03:21	80.89	OK	6768	2026-09-15 03:22	79.08	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6769	2026-09-15 03:23	83.19	OK	6770	2026-09-15 03:24	80.91	OK
6771	2026-09-15 03:25	82.21	OK	6772	2026-09-15 03:26	81.54	OK
6773	2026-09-15 03:27	82.14	OK	6774	2026-09-15 03:28	82.87	OK
6775	2026-09-15 03:29	81.28	OK	6776	2026-09-15 03:30	80.59	OK
6777	2026-09-15 03:31	80.07	OK	6778	2026-09-15 03:32	81.85	OK
6779	2026-09-15 03:33	82.99	OK	6780	2026-09-15 03:34	79.38	OK
6781	2026-09-15 03:35	81.29	OK	6782	2026-09-15 03:36	79.71	OK
6783	2026-09-15 03:37	81.61	OK	6784	2026-09-15 03:38	82.05	OK
6785	2026-09-15 03:39	82.62	OK	6786	2026-09-15 03:40	80.71	OK
6787	2026-09-15 03:41	80.31	OK	6788	2026-09-15 03:42	82.54	OK
6789	2026-09-15 03:43	81.78	OK	6790	2026-09-15 03:44	80.97	OK
6791	2026-09-15 03:45	82.55	OK	6792	2026-09-15 03:46	83.93	OK
6793	2026-09-15 03:47	82.32	OK	6794	2026-09-15 03:48	82.06	OK
6795	2026-09-15 03:49	81.42	OK	6796	2026-09-15 03:50	80.98	OK
6797	2026-09-15 03:51	80.21	OK	6798	2026-09-15 03:52	80.96	OK
6799	2026-09-15 03:53	79.99	OK	6800	2026-09-15 03:54	81.61	OK
6801	2026-09-15 03:55	84.32	OK	6802	2026-09-15 03:56	82.06	OK
6803	2026-09-15 03:57	81.41	OK	6804	2026-09-15 03:58	83.06	OK
6805	2026-09-15 03:59	79.98	OK	6806	2026-09-15 04:00	80.89	OK
6807	2026-09-15 04:01	81.16	OK	6808	2026-09-15 04:02	78.85	OK
6809	2026-09-15 04:03	79.47	OK	6810	2026-09-15 04:04	81.34	OK
6811	2026-09-15 04:05	81.53	OK	6812	2026-09-15 04:06	81.85	OK
6813	2026-09-15 04:07	80.10	OK	6814	2026-09-15 04:08	82.15	OK
6815	2026-09-15 04:09	82.69	OK	6816	2026-09-15 04:10	80.09	OK
6817	2026-09-15 04:11	80.97	OK	6818	2026-09-15 04:12	82.39	OK
6819	2026-09-15 04:13	83.20	OK	6820	2026-09-15 04:14	81.24	OK
6821	2026-09-15 04:15	79.87	OK	6822	2026-09-15 04:16	79.69	OK
6823	2026-09-15 04:17	80.39	OK	6824	2026-09-15 04:18	81.43	OK
6825	2026-09-15 04:19	79.36	OK	6826	2026-09-15 04:20	80.70	OK
6827	2026-09-15 04:21	81.77	OK	6828	2026-09-15 04:22	80.89	OK
6829	2026-09-15 04:23	81.17	OK	6830	2026-09-15 04:24	80.53	OK
6831	2026-09-15 04:25	81.54	OK	6832	2026-09-15 04:26	78.62	OK
6833	2026-09-15 04:27	82.38	OK	6834	2026-09-15 04:28	81.93	OK
6835	2026-09-15 04:29	80.82	OK	6836	2026-09-15 04:30	82.10	OK
6837	2026-09-15 04:31	81.26	OK	6838	2026-09-15 04:32	81.32	OK
6839	2026-09-15 04:33	84.08	OK	6840	2026-09-15 04:34	81.72	OK
6841	2026-09-15 04:35	81.90	OK	6842	2026-09-15 04:36	82.40	OK
6843	2026-09-15 04:37	83.04	OK	6844	2026-09-15 04:38	81.69	OK
6845	2026-09-15 04:39	80.55	OK	6846	2026-09-15 04:40	82.68	OK
6847	2026-09-15 04:41	80.49	OK	6848	2026-09-15 04:42	82.30	OK
6849	2026-09-15 04:43	81.93	OK	6850	2026-09-15 04:44	79.01	OK
6851	2026-09-15 04:45	81.05	OK	6852	2026-09-15 04:46	82.39	OK
6853	2026-09-15 04:47	79.93	OK	6854	2026-09-15 04:48	80.95	OK
6855	2026-09-15 04:49	78.97	OK	6856	2026-09-15 04:50	82.52	OK
6857	2026-09-15 04:51	82.62	OK	6858	2026-09-15 04:52	83.21	OK
6859	2026-09-15 04:53	80.49	OK	6860	2026-09-15 04:54	80.44	OK
6861	2026-09-15 04:55	81.07	OK	6862	2026-09-15 04:56	81.20	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6863	2026-09-15 04:57	80.50	OK	6864	2026-09-15 04:58	81.18	OK
6865	2026-09-15 04:59	79.10	OK	6866	2026-09-15 05:00	81.27	OK
6867	2026-09-15 05:01	81.13	OK	6868	2026-09-15 05:02	80.16	OK
6869	2026-09-15 05:03	80.01	OK	6870	2026-09-15 05:04	79.04	OK
6871	2026-09-15 05:05	79.22	OK	6872	2026-09-15 05:06	81.89	OK
6873	2026-09-15 05:07	81.61	OK	6874	2026-09-15 05:08	82.18	OK
6875	2026-09-15 05:09	80.76	OK	6876	2026-09-15 05:10	80.51	OK
6877	2026-09-15 05:11	82.09	OK	6878	2026-09-15 05:12	80.53	OK
6879	2026-09-15 05:13	81.65	OK	6880	2026-09-15 05:14	81.42	OK
6881	2026-09-15 05:15	81.00	OK	6882	2026-09-15 05:16	83.38	OK
6883	2026-09-15 05:17	81.23	OK	6884	2026-09-15 05:18	81.25	OK
6885	2026-09-15 05:19	80.69	OK	6886	2026-09-15 05:20	81.45	OK
6887	2026-09-15 05:21	81.02	OK	6888	2026-09-15 05:22	78.52	OK
6889	2026-09-15 05:23	80.73	OK	6890	2026-09-15 05:24	82.64	OK
6891	2026-09-15 05:25	77.93	OK	6892	2026-09-15 05:26	80.12	OK
6893	2026-09-15 05:27	80.76	OK	6894	2026-09-15 05:28	80.49	OK
6895	2026-09-15 05:29	81.35	OK	6896	2026-09-15 05:30	78.97	OK
6897	2026-09-15 05:31	78.84	OK	6898	2026-09-15 05:32	80.74	OK
6899	2026-09-15 05:33	80.91	OK	6900	2026-09-15 05:34	80.06	OK
6901	2026-09-15 05:35	79.79	OK	6902	2026-09-15 05:36	79.05	OK
6903	2026-09-15 05:37	79.16	OK	6904	2026-09-15 05:38	83.22	OK
6905	2026-09-15 05:39	79.04	OK	6906	2026-09-15 05:40	82.01	OK
6907	2026-09-15 05:41	80.07	OK	6908	2026-09-15 05:42	77.10	OK
6909	2026-09-15 05:43	80.74	OK	6910	2026-09-15 05:44	81.63	OK
6911	2026-09-15 05:45	83.33	OK	6912	2026-09-15 05:46	80.31	OK
6913	2026-09-15 05:47	79.57	OK	6914	2026-09-15 05:48	79.56	OK
6915	2026-09-15 05:49	81.38	OK	6916	2026-09-15 05:50	78.95	OK
6917	2026-09-15 05:51	81.84	OK	6918	2026-09-15 05:52	78.25	OK
6919	2026-09-15 05:53	79.74	OK	6920	2026-09-15 05:54	80.48	OK
6921	2026-09-15 05:55	79.79	OK	6922	2026-09-15 05:56	78.24	OK
6923	2026-09-15 05:57	78.71	OK	6924	2026-09-15 05:58	79.49	OK
6925	2026-09-15 05:59	80.15	OK	6926	2026-09-15 06:00	78.37	OK
6927	2026-09-15 06:01	80.57	OK	6928	2026-09-15 06:02	79.77	OK
6929	2026-09-15 06:03	79.16	OK	6930	2026-09-15 06:04	78.57	OK
6931	2026-09-15 06:05	79.18	OK	6932	2026-09-15 06:06	79.84	OK
6933	2026-09-15 06:07	79.80	OK	6934	2026-09-15 06:08	79.17	OK
6935	2026-09-15 06:09	79.89	OK	6936	2026-09-15 06:10	79.11	OK
6937	2026-09-15 06:11	78.44	OK	6938	2026-09-15 06:12	78.37	OK
6939	2026-09-15 06:13	79.94	OK	6940	2026-09-15 06:14	80.00	OK
6941	2026-09-15 06:15	78.72	OK	6942	2026-09-15 06:16	80.15	OK
6943	2026-09-15 06:17	78.27	OK	6944	2026-09-15 06:18	80.52	OK
6945	2026-09-15 06:19	80.77	OK	6946	2026-09-15 06:20	78.23	OK
6947	2026-09-15 06:21	78.75	OK	6948	2026-09-15 06:22	78.94	OK
6949	2026-09-15 06:23	80.87	OK	6950	2026-09-15 06:24	79.90	OK
6951	2026-09-15 06:25	81.69	OK	6952	2026-09-15 06:26	79.65	OK
6953	2026-09-15 06:27	81.09	OK	6954	2026-09-15 06:28	77.47	OK
6955	2026-09-15 06:29	78.05	OK	6956	2026-09-15 06:30	78.22	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6957	2026-09-15 06:31	79.22	OK	6958	2026-09-15 06:32	80.49	OK
6959	2026-09-15 06:33	81.48	OK	6960	2026-09-15 06:34	78.20	OK
6961	2026-09-15 06:35	80.09	OK	6962	2026-09-15 06:36	81.14	OK
6963	2026-09-15 06:37	80.39	OK	6964	2026-09-15 06:38	80.45	OK
6965	2026-09-15 06:39	79.71	OK	6966	2026-09-15 06:40	82.44	OK
6967	2026-09-15 06:41	80.86	OK	6968	2026-09-15 06:42	80.49	OK
6969	2026-09-15 06:43	80.70	OK	6970	2026-09-15 06:44	80.83	OK
6971	2026-09-15 06:45	78.85	OK	6972	2026-09-15 06:46	79.86	OK
6973	2026-09-15 06:47	77.06	OK	6974	2026-09-15 06:48	78.36	OK
6975	2026-09-15 06:49	79.87	OK	6976	2026-09-15 06:50	81.57	OK
6977	2026-09-15 06:51	80.60	OK	6978	2026-09-15 06:52	80.39	OK
6979	2026-09-15 06:53	77.62	OK	6980	2026-09-15 06:54	77.32	OK
6981	2026-09-15 06:55	80.32	OK	6982	2026-09-15 06:56	78.81	OK
6983	2026-09-15 06:57	79.02	OK	6984	2026-09-15 06:58	77.48	OK
6985	2026-09-15 06:59	78.51	OK	6986	2026-09-15 07:00	79.20	OK
6987	2026-09-15 07:01	78.82	OK	6988	2026-09-15 07:02	79.60	OK
6989	2026-09-15 07:03	77.58	OK	6990	2026-09-15 07:04	79.81	OK
6991	2026-09-15 07:05	78.31	OK	6992	2026-09-15 07:06	80.30	OK
6993	2026-09-15 07:07	80.37	OK	6994	2026-09-15 07:08	78.12	OK
6995	2026-09-15 07:09	78.58	OK	6996	2026-09-15 07:10	77.00	OK
6997	2026-09-15 07:11	77.76	OK	6998	2026-09-15 07:12	78.11	OK
6999	2026-09-15 07:13	77.32	OK	7000	2026-09-15 07:14	78.05	OK
7001	2026-09-15 07:15	78.54	OK	7002	2026-09-15 07:16	77.01	OK
7003	2026-09-15 07:17	80.61	OK	7004	2026-09-15 07:18	79.98	OK
7005	2026-09-15 07:19	80.48	OK	7006	2026-09-15 07:20	77.85	OK
7007	2026-09-15 07:21	77.59	OK	7008	2026-09-15 07:22	79.76	OK
7009	2026-09-15 07:23	80.21	OK	7010	2026-09-15 07:24	77.14	OK
7011	2026-09-15 07:25	78.68	OK	7012	2026-09-15 07:26	78.33	OK
7013	2026-09-15 07:27	80.98	OK	7014	2026-09-15 07:28	78.40	OK
7015	2026-09-15 07:29	79.69	OK	7016	2026-09-15 07:30	80.31	OK
7017	2026-09-15 07:31	79.14	OK	7018	2026-09-15 07:32	79.56	OK
7019	2026-09-15 07:33	76.79	OK	7020	2026-09-15 07:34	78.56	OK
7021	2026-09-15 07:35	76.34	OK	7022	2026-09-15 07:36	78.20	OK
7023	2026-09-15 07:37	79.63	OK	7024	2026-09-15 07:38	77.47	OK
7025	2026-09-15 07:39	79.88	OK	7026	2026-09-15 07:40	77.85	OK
7027	2026-09-15 07:41	78.94	OK	7028	2026-09-15 07:42	79.51	OK
7029	2026-09-15 07:43	80.78	OK	7030	2026-09-15 07:44	81.10	OK
7031	2026-09-15 07:45	78.02	OK	7032	2026-09-15 07:46	76.95	OK
7033	2026-09-15 07:47	77.79	OK	7034	2026-09-15 07:48	76.71	OK
7035	2026-09-15 07:49	79.18	OK	7036	2026-09-15 07:50	77.09	OK
7037	2026-09-15 07:51	77.88	OK	7038	2026-09-15 07:52	78.57	OK
7039	2026-09-15 07:53	77.51	OK	7040	2026-09-15 07:54	75.85	OK
7041	2026-09-15 07:55	78.71	OK	7042	2026-09-15 07:56	77.20	OK
7043	2026-09-15 07:57	77.21	OK	7044	2026-09-15 07:58	78.32	OK
7045	2026-09-15 07:59	75.05	OK	7046	2026-09-15 08:00	77.44	OK
7047	2026-09-15 08:01	77.62	OK	7048	2026-09-15 08:02	78.30	OK
7049	2026-09-15 08:03	76.47	OK	7050	2026-09-15 08:04	80.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7051	2026-09-15 08:05	78.44	OK	7052	2026-09-15 08:06	80.09	OK
7053	2026-09-15 08:07	79.14	OK	7054	2026-09-15 08:08	75.92	OK
7055	2026-09-15 08:09	75.61	OK	7056	2026-09-15 08:10	79.34	OK
7057	2026-09-15 08:11	78.93	OK	7058	2026-09-15 08:12	78.69	OK
7059	2026-09-15 08:13	76.99	OK	7060	2026-09-15 08:14	78.39	OK
7061	2026-09-15 08:15	77.14	OK	7062	2026-09-15 08:16	77.23	OK
7063	2026-09-15 08:17	77.62	OK	7064	2026-09-15 08:18	76.53	OK
7065	2026-09-15 08:19	76.41	OK	7066	2026-09-15 08:20	79.49	OK
7067	2026-09-15 08:21	77.43	OK	7068	2026-09-15 08:22	76.61	OK
7069	2026-09-15 08:23	75.64	OK	7070	2026-09-15 08:24	74.50	OK
7071	2026-09-15 08:25	77.02	OK	7072	2026-09-15 08:26	79.31	OK
7073	2026-09-15 08:27	79.22	OK	7074	2026-09-15 08:28	76.50	OK
7075	2026-09-15 08:29	76.97	OK	7076	2026-09-15 08:30	78.85	OK
7077	2026-09-15 08:31	77.70	OK	7078	2026-09-15 08:32	76.48	OK
7079	2026-09-15 08:33	78.27	OK	7080	2026-09-15 08:34	76.14	OK
7081	2026-09-15 08:35	78.72	OK	7082	2026-09-15 08:36	78.13	OK
7083	2026-09-15 08:37	76.26	OK	7084	2026-09-15 08:38	75.64	OK
7085	2026-09-15 08:39	77.42	OK	7086	2026-09-15 08:40	75.98	OK
7087	2026-09-15 08:41	77.60	OK	7088	2026-09-15 08:42	76.41	OK
7089	2026-09-15 08:43	76.21	OK	7090	2026-09-15 08:44	77.78	OK
7091	2026-09-15 08:45	77.24	OK	7092	2026-09-15 08:46	77.11	OK
7093	2026-09-15 08:47	77.69	OK	7094	2026-09-15 08:48	77.71	OK
7095	2026-09-15 08:49	75.74	OK	7096	2026-09-15 08:50	76.81	OK
7097	2026-09-15 08:51	76.19	OK	7098	2026-09-15 08:52	76.74	OK
7099	2026-09-15 08:53	77.20	OK	7100	2026-09-15 08:54	75.21	OK
7101	2026-09-15 08:55	74.41	OK	7102	2026-09-15 08:56	78.23	OK
7103	2026-09-15 08:57	76.33	OK	7104	2026-09-15 08:58	74.46	OK
7105	2026-09-15 08:59	74.76	OK	7106	2026-09-15 09:00	75.83	OK
7107	2026-09-15 09:01	78.05	OK	7108	2026-09-15 09:02	77.81	OK
7109	2026-09-15 09:03	75.25	OK	7110	2026-09-15 09:04	76.65	OK
7111	2026-09-15 09:05	74.93	OK	7112	2026-09-15 09:06	77.02	OK
7113	2026-09-15 09:07	76.42	OK	7114	2026-09-15 09:08	75.91	OK
7115	2026-09-15 09:09	77.20	OK	7116	2026-09-15 09:10	78.16	OK
7117	2026-09-15 09:11	76.78	OK	7118	2026-09-15 09:12	75.97	OK
7119	2026-09-15 09:13	74.95	OK	7120	2026-09-15 09:14	74.31	OK
7121	2026-09-15 09:15	75.44	OK	7122	2026-09-15 09:16	76.28	OK
7123	2026-09-15 09:17	75.63	OK	7124	2026-09-15 09:18	73.86	OK
7125	2026-09-15 09:19	74.67	OK	7126	2026-09-15 09:20	75.63	OK
7127	2026-09-15 09:21	76.86	OK	7128	2026-09-15 09:22	73.60	OK
7129	2026-09-15 09:23	76.57	OK	7130	2026-09-15 09:24	73.37	OK
7131	2026-09-15 09:25	74.86	OK	7132	2026-09-15 09:26	74.61	OK
7133	2026-09-15 09:27	78.66	OK	7134	2026-09-15 09:28	76.15	OK
7135	2026-09-15 09:29	74.61	OK	7136	2026-09-15 09:30	75.15	OK
7137	2026-09-15 09:31	72.94	OK	7138	2026-09-15 09:32	76.00	OK
7139	2026-09-15 09:33	72.66	OK	7140	2026-09-15 09:34	75.84	OK
7141	2026-09-15 09:35	75.29	OK	7142	2026-09-15 09:36	76.03	OK
7143	2026-09-15 09:37	75.23	OK	7144	2026-09-15 09:38	75.53	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7145	2026-09-15 09:39	77.79	OK	7146	2026-09-15 09:40	75.38	OK
7147	2026-09-15 09:41	75.89	OK	7148	2026-09-15 09:42	75.93	OK
7149	2026-09-15 09:43	74.59	OK	7150	2026-09-15 09:44	76.46	OK
7151	2026-09-15 09:45	77.62	OK	7152	2026-09-15 09:46	75.32	OK
7153	2026-09-15 09:47	75.89	OK	7154	2026-09-15 09:48	77.45	OK
7155	2026-09-15 09:49	74.47	OK	7156	2026-09-15 09:50	76.62	OK
7157	2026-09-15 09:51	77.78	OK	7158	2026-09-15 09:52	76.41	OK
7159	2026-09-15 09:53	73.33	OK	7160	2026-09-15 09:54	74.68	OK
7161	2026-09-15 09:55	77.14	OK	7162	2026-09-15 09:56	78.15	OK
7163	2026-09-15 09:57	77.37	OK	7164	2026-09-15 09:58	75.55	OK
7165	2026-09-15 09:59	75.46	OK	7166	2026-09-15 10:00	77.01	OK
7167	2026-09-15 10:01	74.50	OK	7168	2026-09-15 10:02	77.20	OK
7169	2026-09-15 10:03	74.37	OK	7170	2026-09-15 10:04	74.57	OK
7171	2026-09-15 10:05	77.08	OK	7172	2026-09-15 10:06	77.01	OK
7173	2026-09-15 10:07	76.44	OK	7174	2026-09-15 10:08	73.12	OK
7175	2026-09-15 10:09	74.22	OK	7176	2026-09-15 10:10	75.00	OK
7177	2026-09-15 10:11	75.36	OK	7178	2026-09-15 10:12	75.76	OK
7179	2026-09-15 10:13	77.03	OK	7180	2026-09-15 10:14	72.55	OK
7181	2026-09-15 10:15	74.88	OK	7182	2026-09-15 10:16	76.86	OK
7183	2026-09-15 10:17	73.11	OK	7184	2026-09-15 10:18	75.47	OK
7185	2026-09-15 10:19	76.32	OK	7186	2026-09-15 10:20	75.59	OK
7187	2026-09-15 10:21	73.98	OK	7188	2026-09-15 10:22	73.93	OK
7189	2026-09-15 10:23	75.65	OK	7190	2026-09-15 10:24	73.40	OK
7191	2026-09-15 10:25	72.95	OK	7192	2026-09-15 10:26	72.23	OK
7193	2026-09-15 10:27	76.19	OK	7194	2026-09-15 10:28	73.17	OK
7195	2026-09-15 10:29	71.79	OK	7196	2026-09-15 10:30	74.72	OK
7197	2026-09-15 10:31	73.87	OK	7198	2026-09-15 10:32	74.56	OK
7199	2026-09-15 10:33	75.25	OK	7200	2026-09-15 10:34	73.42	OK
7201	2026-09-15 10:35	72.62	OK	7202	2026-09-15 10:36	75.93	OK
7203	2026-09-15 10:37	71.27	OK	7204	2026-09-15 10:38	76.62	OK
7205	2026-09-15 10:39	75.14	OK	7206	2026-09-15 10:40	75.10	OK
7207	2026-09-15 10:41	74.21	OK	7208	2026-09-15 10:42	75.88	OK
7209	2026-09-15 10:43	73.69	OK	7210	2026-09-15 10:44	73.60	OK
7211	2026-09-15 10:45	72.98	OK	7212	2026-09-15 10:46	72.30	OK
7213	2026-09-15 10:47	73.73	OK	7214	2026-09-15 10:48	74.31	OK
7215	2026-09-15 10:49	74.24	OK	7216	2026-09-15 10:50	74.69	OK
7217	2026-09-15 10:51	73.37	OK	7218	2026-09-15 10:52	76.52	OK
7219	2026-09-15 10:53	72.16	OK	7220	2026-09-15 10:54	75.45	OK
7221	2026-09-15 10:55	73.70	OK	7222	2026-09-15 10:56	75.37	OK
7223	2026-09-15 10:57	74.67	OK	7224	2026-09-15 10:58	73.72	OK
7225	2026-09-15 10:59	75.70	OK	7226	2026-09-15 11:00	73.51	OK
7227	2026-09-15 11:01	72.86	OK	7228	2026-09-15 11:02	71.34	OK
7229	2026-09-15 11:03	73.61	OK	7230	2026-09-15 11:04	74.54	OK
7231	2026-09-15 11:05	73.31	OK	7232	2026-09-15 11:06	72.27	OK
7233	2026-09-15 11:07	76.65	OK	7234	2026-09-15 11:08	71.77	OK
7235	2026-09-15 11:09	73.69	OK	7236	2026-09-15 11:10	71.88	OK
7237	2026-09-15 11:11	74.86	OK	7238	2026-09-15 11:12	73.27	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7239	2026-09-15 11:13	74.37	OK	7240	2026-09-15 11:14	72.95	OK
7241	2026-09-15 11:15	75.21	OK	7242	2026-09-15 11:16	72.94	OK
7243	2026-09-15 11:17	75.21	OK	7244	2026-09-15 11:18	74.88	OK
7245	2026-09-15 11:19	73.50	OK	7246	2026-09-15 11:20	73.81	OK
7247	2026-09-15 11:21	73.78	OK	7248	2026-09-15 11:22	74.96	OK
7249	2026-09-15 11:23	72.50	OK	7250	2026-09-15 11:24	75.92	OK
7251	2026-09-15 11:25	74.68	OK	7252	2026-09-15 11:26	72.04	OK
7253	2026-09-15 11:27	71.16	OK	7254	2026-09-15 11:28	71.80	OK
7255	2026-09-15 11:29	73.75	OK	7256	2026-09-15 11:30	73.10	OK
7257	2026-09-15 11:31	71.78	OK	7258	2026-09-15 11:32	74.15	OK
7259	2026-09-15 11:33	71.05	OK	7260	2026-09-15 11:34	75.01	OK
7261	2026-09-15 11:35	73.98	OK	7262	2026-09-15 11:36	72.03	OK
7263	2026-09-15 11:37	73.56	OK	7264	2026-09-15 11:38	71.61	OK
7265	2026-09-15 11:39	74.97	OK	7266	2026-09-15 11:40	72.12	OK
7267	2026-09-15 11:41	72.34	OK	7268	2026-09-15 11:42	71.75	OK
7269	2026-09-15 11:43	73.53	OK	7270	2026-09-15 11:44	70.48	OK
7271	2026-09-15 11:45	72.46	OK	7272	2026-09-15 11:46	75.37	OK
7273	2026-09-15 11:47	73.11	OK	7274	2026-09-15 11:48	71.92	OK
7275	2026-09-15 11:49	72.48	OK	7276	2026-09-15 11:50	74.41	OK
7277	2026-09-15 11:51	73.44	OK	7278	2026-09-15 11:52	71.88	OK
7279	2026-09-15 11:53	74.24	OK	7280	2026-09-15 11:54	73.35	OK
7281	2026-09-15 11:55	73.61	OK	7282	2026-09-15 11:56	74.71	OK
7283	2026-09-15 11:57	71.21	OK	7284	2026-09-15 11:58	72.19	OK
7285	2026-09-15 11:59	75.77	OK	7286	2026-09-15 12:00	71.83	OK
7287	2026-09-15 12:01	72.29	OK	7288	2026-09-15 12:02	71.94	OK
7289	2026-09-15 12:03	70.04	OK	7290	2026-09-15 12:04	73.28	OK
7291	2026-09-15 12:05	69.79	OK	7292	2026-09-15 12:06	73.09	OK
7293	2026-09-15 12:07	72.37	OK	7294	2026-09-15 12:08	72.56	OK
7295	2026-09-15 12:09	73.17	OK	7296	2026-09-15 12:10	72.81	OK
7297	2026-09-15 12:11	72.19	OK	7298	2026-09-15 12:12	74.66	OK
7299	2026-09-15 12:13	72.26	OK	7300	2026-09-15 12:14	69.75	OK
7301	2026-09-15 12:15	72.79	OK	7302	2026-09-15 12:16	70.67	OK
7303	2026-09-15 12:17	71.84	OK	7304	2026-09-15 12:18	70.40	OK
7305	2026-09-15 12:19	70.42	OK	7306	2026-09-15 12:20	71.04	OK
7307	2026-09-15 12:21	72.74	OK	7308	2026-09-15 12:22	72.23	OK
7309	2026-09-15 12:23	72.09	OK	7310	2026-09-15 12:24	73.70	OK
7311	2026-09-15 12:25	69.94	OK	7312	2026-09-15 12:26	73.32	OK
7313	2026-09-15 12:27	73.84	OK	7314	2026-09-15 12:28	73.68	OK
7315	2026-09-15 12:29	72.37	OK	7316	2026-09-15 12:30	71.13	OK
7317	2026-09-15 12:31	74.52	OK	7318	2026-09-15 12:32	72.75	OK
7319	2026-09-15 12:33	72.18	OK	7320	2026-09-15 12:34	72.70	OK
7321	2026-09-15 12:35	73.80	OK	7322	2026-09-15 12:36	70.09	OK
7323	2026-09-15 12:37	69.44	OK	7324	2026-09-15 12:38	72.10	OK
7325	2026-09-15 12:39	72.48	OK	7326	2026-09-15 12:40	72.38	OK
7327	2026-09-15 12:41	73.66	OK	7328	2026-09-15 12:42	72.82	OK
7329	2026-09-15 12:43	71.70	OK	7330	2026-09-15 12:44	71.25	OK
7331	2026-09-15 12:45	71.62	OK	7332	2026-09-15 12:46	69.98	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7333	2026-09-15 12:47	73.62	OK	7334	2026-09-15 12:48	73.07	OK
7335	2026-09-15 12:49	72.49	OK	7336	2026-09-15 12:50	71.13	OK
7337	2026-09-15 12:51	71.98	OK	7338	2026-09-15 12:52	70.37	OK
7339	2026-09-15 12:53	71.04	OK	7340	2026-09-15 12:54	73.50	OK
7341	2026-09-15 12:55	73.61	OK	7342	2026-09-15 12:56	71.94	OK
7343	2026-09-15 12:57	73.58	OK	7344	2026-09-15 12:58	73.18	OK
7345	2026-09-15 12:59	72.12	OK	7346	2026-09-15 13:00	72.86	OK
7347	2026-09-15 13:01	75.11	OK	7348	2026-09-15 13:02	70.73	OK
7349	2026-09-15 13:03	73.44	OK	7350	2026-09-15 13:04	69.25	OK
7351	2026-09-15 13:05	70.44	OK	7352	2026-09-15 13:06	73.02	OK
7353	2026-09-15 13:07	70.15	OK	7354	2026-09-15 13:08	72.71	OK
7355	2026-09-15 13:09	69.78	OK	7356	2026-09-15 13:10	71.21	OK
7357	2026-09-15 13:11	72.18	OK	7358	2026-09-15 13:12	71.40	OK
7359	2026-09-15 13:13	69.81	OK	7360	2026-09-15 13:14	70.36	OK
7361	2026-09-15 13:15	72.71	OK	7362	2026-09-15 13:16	72.81	OK
7363	2026-09-15 13:17	72.55	OK	7364	2026-09-15 13:18	70.78	OK
7365	2026-09-15 13:19	70.57	OK	7366	2026-09-15 13:20	71.19	OK
7367	2026-09-15 13:21	73.64	OK	7368	2026-09-15 13:22	71.60	OK
7369	2026-09-15 13:23	70.57	OK	7370	2026-09-15 13:24	71.92	OK
7371	2026-09-15 13:25	72.43	OK	7372	2026-09-15 13:26	72.16	OK
7373	2026-09-15 13:27	71.25	OK	7374	2026-09-15 13:28	71.99	OK
7375	2026-09-15 13:29	74.02	OK	7376	2026-09-15 13:30	70.55	OK
7377	2026-09-15 13:31	71.93	OK	7378	2026-09-15 13:32	71.95	OK
7379	2026-09-15 13:33	69.78	OK	7380	2026-09-15 13:34	71.46	OK
7381	2026-09-15 13:35	73.58	OK	7382	2026-09-15 13:36	70.92	OK
7383	2026-09-15 13:37	71.26	OK	7384	2026-09-15 13:38	69.33	OK
7385	2026-09-15 13:39	72.17	OK	7386	2026-09-15 13:40	70.76	OK
7387	2026-09-15 13:41	70.41	OK	7388	2026-09-15 13:42	71.59	OK
7389	2026-09-15 13:43	72.41	OK	7390	2026-09-15 13:44	70.07	OK
7391	2026-09-15 13:45	72.92	OK	7392	2026-09-15 13:46	71.88	OK
7393	2026-09-15 13:47	72.38	OK	7394	2026-09-15 13:48	70.23	OK
7395	2026-09-15 13:49	72.02	OK	7396	2026-09-15 13:50	73.37	OK
7397	2026-09-15 13:51	72.59	OK	7398	2026-09-15 13:52	70.90	OK
7399	2026-09-15 13:53	70.55	OK	7400	2026-09-15 13:54	70.46	OK
7401	2026-09-15 13:55	70.52	OK	7402	2026-09-15 13:56	71.25	OK
7403	2026-09-15 13:57	72.07	OK	7404	2026-09-15 13:58	70.43	OK
7405	2026-09-15 13:59	70.74	OK	7406	2026-09-15 14:00	71.22	OK
7407	2026-09-15 14:01	73.42	OK	7408	2026-09-15 14:02	69.28	OK
7409	2026-09-15 14:03	71.52	OK	7410	2026-09-15 14:04	73.19	OK
7411	2026-09-15 14:05	68.61	OK	7412	2026-09-15 14:06	71.20	OK
7413	2026-09-15 14:07	70.37	OK	7414	2026-09-15 14:08	71.78	OK
7415	2026-09-15 14:09	72.54	OK	7416	2026-09-15 14:10	70.32	OK
7417	2026-09-15 14:11	71.18	OK	7418	2026-09-15 14:12	69.87	OK
7419	2026-09-15 14:13	72.41	OK	7420	2026-09-15 14:14	71.87	OK
7421	2026-09-15 14:15	70.24	OK	7422	2026-09-15 14:16	71.03	OK
7423	2026-09-15 14:17	69.11	OK	7424	2026-09-15 14:18	73.00	OK
7425	2026-09-15 14:19	70.05	OK	7426	2026-09-15 14:20	72.30	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7427	2026-09-15 14:21	68.42	OK	7428	2026-09-15 14:22	70.62	OK
7429	2026-09-15 14:23	73.79	OK	7430	2026-09-15 14:24	70.89	OK
7431	2026-09-15 14:25	69.18	OK	7432	2026-09-15 14:26	68.81	OK
7433	2026-09-15 14:27	72.56	OK	7434	2026-09-15 14:28	71.41	OK
7435	2026-09-15 14:29	70.37	OK	7436	2026-09-15 14:30	70.75	OK
7437	2026-09-15 14:31	68.89	OK	7438	2026-09-15 14:32	72.10	OK
7439	2026-09-15 14:33	72.80	OK	7440	2026-09-15 14:34	73.54	OK
7441	2026-09-15 14:35	70.36	OK	7442	2026-09-15 14:36	71.52	OK
7443	2026-09-15 14:37	73.61	OK	7444	2026-09-15 14:38	70.91	OK
7445	2026-09-15 14:39	70.96	OK	7446	2026-09-15 14:40	71.45	OK
7447	2026-09-15 14:41	70.50	OK	7448	2026-09-15 14:42	70.99	OK
7449	2026-09-15 14:43	69.96	OK	7450	2026-09-15 14:44	70.26	OK
7451	2026-09-15 14:45	71.77	OK	7452	2026-09-15 14:46	70.31	OK
7453	2026-09-15 14:47	70.29	OK	7454	2026-09-15 14:48	69.55	OK
7455	2026-09-15 14:49	73.60	OK	7456	2026-09-15 14:50	70.10	OK
7457	2026-09-15 14:51	71.98	OK	7458	2026-09-15 14:52	70.10	OK
7459	2026-09-15 14:53	72.73	OK	7460	2026-09-15 14:54	70.50	OK
7461	2026-09-15 14:55	71.67	OK	7462	2026-09-15 14:56	70.75	OK
7463	2026-09-15 14:57	70.41	OK	7464	2026-09-15 14:58	72.54	OK
7465	2026-09-15 14:59	72.08	OK	7466	2026-09-15 15:00	69.54	OK
7467	2026-09-15 15:01	71.10	OK	7468	2026-09-15 15:02	70.27	OK
7469	2026-09-15 15:03	70.97	OK	7470	2026-09-15 15:04	69.59	OK
7471	2026-09-15 15:05	72.01	OK	7472	2026-09-15 15:06	71.48	OK
7473	2026-09-15 15:07	72.19	OK	7474	2026-09-15 15:08	70.64	OK
7475	2026-09-15 15:09	70.60	OK	7476	2026-09-15 15:10	71.55	OK
7477	2026-09-15 15:11	72.28	OK	7478	2026-09-15 15:12	71.91	OK
7479	2026-09-15 15:13	71.40	OK	7480	2026-09-15 15:14	72.21	OK
7481	2026-09-15 15:15	69.80	OK	7482	2026-09-15 15:16	71.35	OK
7483	2026-09-15 15:17	71.29	OK	7484	2026-09-15 15:18	72.61	OK
7485	2026-09-15 15:19	69.94	OK	7486	2026-09-15 15:20	72.24	OK
7487	2026-09-15 15:21	69.22	OK	7488	2026-09-15 15:22	69.53	OK
7489	2026-09-15 15:23	71.09	OK	7490	2026-09-15 15:24	72.67	OK
7491	2026-09-15 15:25	70.66	OK	7492	2026-09-15 15:26	73.37	OK
7493	2026-09-15 15:27	71.49	OK	7494	2026-09-15 15:28	71.51	OK
7495	2026-09-15 15:29	71.60	OK	7496	2026-09-15 15:30	72.84	OK
7497	2026-09-15 15:31	70.98	OK	7498	2026-09-15 15:32	74.61	OK
7499	2026-09-15 15:33	74.48	OK	7500	2026-09-15 15:34	70.78	OK
7501	2026-09-15 15:35	70.67	OK	7502	2026-09-15 15:36	73.35	OK
7503	2026-09-15 15:37	70.77	OK	7504	2026-09-15 15:38	70.88	OK
7505	2026-09-15 15:39	71.85	OK	7506	2026-09-15 15:40	70.77	OK
7507	2026-09-15 15:41	71.04	OK	7508	2026-09-15 15:42	70.65	OK
7509	2026-09-15 15:43	69.99	OK	7510	2026-09-15 15:44	70.80	OK
7511	2026-09-15 15:45	72.10	OK	7512	2026-09-15 15:46	69.93	OK
7513	2026-09-15 15:47	72.44	OK	7514	2026-09-15 15:48	71.54	OK
7515	2026-09-15 15:49	72.91	OK	7516	2026-09-15 15:50	69.78	OK
7517	2026-09-15 15:51	71.82	OK	7518	2026-09-15 15:52	71.33	OK
7519	2026-09-15 15:53	71.59	OK	7520	2026-09-15 15:54	69.28	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7521	2026-09-15 15:55	71.15	OK	7522	2026-09-15 15:56	70.65	OK
7523	2026-09-15 15:57	70.68	OK	7524	2026-09-15 15:58	69.00	OK
7525	2026-09-15 15:59	71.97	OK	7526	2026-09-15 16:00	71.86	OK
7527	2026-09-15 16:01	71.96	OK	7528	2026-09-15 16:02	71.48	OK
7529	2026-09-15 16:03	71.98	OK	7530	2026-09-15 16:04	72.45	OK
7531	2026-09-15 16:05	72.40	OK	7532	2026-09-15 16:06	72.40	OK
7533	2026-09-15 16:07	74.08	OK	7534	2026-09-15 16:08	74.48	OK
7535	2026-09-15 16:09	72.32	OK	7536	2026-09-15 16:10	72.42	OK
7537	2026-09-15 16:11	70.27	OK	7538	2026-09-15 16:12	71.98	OK
7539	2026-09-15 16:13	70.43	OK	7540	2026-09-15 16:14	70.43	OK
7541	2026-09-15 16:15	71.02	OK	7542	2026-09-15 16:16	72.55	OK
7543	2026-09-15 16:17	71.97	OK	7544	2026-09-15 16:18	70.94	OK
7545	2026-09-15 16:19	70.57	OK	7546	2026-09-15 16:20	71.46	OK
7547	2026-09-15 16:21	72.36	OK	7548	2026-09-15 16:22	71.28	OK
7549	2026-09-15 16:23	71.23	OK	7550	2026-09-15 16:24	71.96	OK
7551	2026-09-15 16:25	74.38	OK	7552	2026-09-15 16:26	72.34	OK
7553	2026-09-15 16:27	69.39	OK	7554	2026-09-15 16:28	73.10	OK
7555	2026-09-15 16:29	71.38	OK	7556	2026-09-15 16:30	72.63	OK
7557	2026-09-15 16:31	71.41	OK	7558	2026-09-15 16:32	73.36	OK
7559	2026-09-15 16:33	71.30	OK	7560	2026-09-15 16:34	71.28	OK
7561	2026-09-15 16:35	70.86	OK	7562	2026-09-15 16:36	72.35	OK
7563	2026-09-15 16:37	71.45	OK	7564	2026-09-15 16:38	72.21	OK
7565	2026-09-15 16:39	70.32	OK	7566	2026-09-15 16:40	70.03	OK
7567	2026-09-15 16:41	72.24	OK	7568	2026-09-15 16:42	72.07	OK
7569	2026-09-15 16:43	70.29	OK	7570	2026-09-15 16:44	73.16	OK
7571	2026-09-15 16:45	73.87	OK	7572	2026-09-15 16:46	72.53	OK
7573	2026-09-15 16:47	71.11	OK	7574	2026-09-15 16:48	70.39	OK
7575	2026-09-15 16:49	71.79	OK	7576	2026-09-15 16:50	70.44	OK
7577	2026-09-15 16:51	69.58	OK	7578	2026-09-15 16:52	74.75	OK
7579	2026-09-15 16:53	70.80	OK	7580	2026-09-15 16:54	73.83	OK
7581	2026-09-15 16:55	72.20	OK	7582	2026-09-15 16:56	73.41	OK
7583	2026-09-15 16:57	72.14	OK	7584	2026-09-15 16:58	73.89	OK
7585	2026-09-15 16:59	73.07	OK	7586	2026-09-15 17:00	73.57	OK
7587	2026-09-15 17:01	72.58	OK	7588	2026-09-15 17:02	72.04	OK
7589	2026-09-15 17:03	70.09	OK	7590	2026-09-15 17:04	71.92	OK
7591	2026-09-15 17:05	70.16	OK	7592	2026-09-15 17:06	71.18	OK
7593	2026-09-15 17:07	71.46	OK	7594	2026-09-15 17:08	74.03	OK
7595	2026-09-15 17:09	73.49	OK	7596	2026-09-15 17:10	73.10	OK
7597	2026-09-15 17:11	72.68	OK	7598	2026-09-15 17:12	71.93	OK
7599	2026-09-15 17:13	72.36	OK	7600	2026-09-15 17:14	71.07	OK
7601	2026-09-15 17:15	72.80	OK	7602	2026-09-15 17:16	74.21	OK
7603	2026-09-15 17:17	73.35	OK	7604	2026-09-15 17:18	71.88	OK
7605	2026-09-15 17:19	70.26	OK	7606	2026-09-15 17:20	71.55	OK
7607	2026-09-15 17:21	70.49	OK	7608	2026-09-15 17:22	73.81	OK
7609	2026-09-15 17:23	71.73	OK	7610	2026-09-15 17:24	72.38	OK
7611	2026-09-15 17:25	72.57	OK	7612	2026-09-15 17:26	69.79	OK
7613	2026-09-15 17:27	73.02	OK	7614	2026-09-15 17:28	73.47	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7615	2026-09-15 17:29	73.25	OK	7616	2026-09-15 17:30	72.74	OK
7617	2026-09-15 17:31	72.98	OK	7618	2026-09-15 17:32	74.26	OK
7619	2026-09-15 17:33	72.10	OK	7620	2026-09-15 17:34	70.53	OK
7621	2026-09-15 17:35	72.85	OK	7622	2026-09-15 17:36	71.55	OK
7623	2026-09-15 17:37	72.60	OK	7624	2026-09-15 17:38	73.17	OK
7625	2026-09-15 17:39	69.15	OK	7626	2026-09-15 17:40	73.53	OK
7627	2026-09-15 17:41	72.45	OK	7628	2026-09-15 17:42	71.78	OK
7629	2026-09-15 17:43	74.68	OK	7630	2026-09-15 17:44	72.44	OK
7631	2026-09-15 17:45	71.46	OK	7632	2026-09-15 17:46	73.08	OK
7633	2026-09-15 17:47	74.06	OK	7634	2026-09-15 17:48	71.70	OK
7635	2026-09-15 17:49	72.31	OK	7636	2026-09-15 17:50	74.15	OK
7637	2026-09-15 17:51	73.14	OK	7638	2026-09-15 17:52	73.10	OK
7639	2026-09-15 17:53	72.52	OK	7640	2026-09-15 17:54	73.03	OK
7641	2026-09-15 17:55	71.73	OK	7642	2026-09-15 17:56	73.54	OK
7643	2026-09-15 17:57	71.39	OK	7644	2026-09-15 17:58	73.58	OK
7645	2026-09-15 17:59	73.82	OK	7646	2026-09-15 18:00	73.36	OK
7647	2026-09-15 18:01	73.37	OK	7648	2026-09-15 18:02	73.08	OK
7649	2026-09-15 18:03	73.36	OK	7650	2026-09-15 18:04	72.91	OK
7651	2026-09-15 18:05	75.82	OK	7652	2026-09-15 18:06	75.23	OK
7653	2026-09-15 18:07	73.53	OK	7654	2026-09-15 18:08	72.72	OK
7655	2026-09-15 18:09	74.02	OK	7656	2026-09-15 18:10	71.11	OK
7657	2026-09-15 18:11	71.73	OK	7658	2026-09-15 18:12	75.68	OK
7659	2026-09-15 18:13	73.57	OK	7660	2026-09-15 18:14	74.80	OK
7661	2026-09-15 18:15	75.00	OK	7662	2026-09-15 18:16	73.65	OK
7663	2026-09-15 18:17	74.39	OK	7664	2026-09-15 18:18	73.13	OK
7665	2026-09-15 18:19	73.05	OK	7666	2026-09-15 18:20	73.28	OK
7667	2026-09-15 18:21	75.50	OK	7668	2026-09-15 18:22	75.72	OK
7669	2026-09-15 18:23	75.69	OK	7670	2026-09-15 18:24	73.71	OK
7671	2026-09-15 18:25	73.45	OK	7672	2026-09-15 18:26	74.31	OK
7673	2026-09-15 18:27	74.96	OK	7674	2026-09-15 18:28	75.72	OK
7675	2026-09-15 18:29	72.55	OK	7676	2026-09-15 18:30	73.01	OK
7677	2026-09-15 18:31	72.56	OK	7678	2026-09-15 18:32	73.94	OK
7679	2026-09-15 18:33	71.61	OK	7680	2026-09-15 18:34	72.74	OK
7681	2026-09-15 18:35	72.59	OK	7682	2026-09-15 18:36	75.29	OK
7683	2026-09-15 18:37	74.00	OK	7684	2026-09-15 18:38	74.26	OK
7685	2026-09-15 18:39	74.86	OK	7686	2026-09-15 18:40	73.66	OK
7687	2026-09-15 18:41	75.60	OK	7688	2026-09-15 18:42	72.76	OK
7689	2026-09-15 18:43	73.34	OK	7690	2026-09-15 18:44	73.42	OK
7691	2026-09-15 18:45	72.47	OK	7692	2026-09-15 18:46	73.72	OK
7693	2026-09-15 18:47	73.56	OK	7694	2026-09-15 18:48	74.82	OK
7695	2026-09-15 18:49	74.55	OK	7696	2026-09-15 18:50	73.12	OK
7697	2026-09-15 18:51	76.39	OK	7698	2026-09-15 18:52	74.41	OK
7699	2026-09-15 18:53	76.40	OK	7700	2026-09-15 18:54	74.55	OK
7701	2026-09-15 18:55	73.50	OK	7702	2026-09-15 18:56	76.57	OK
7703	2026-09-15 18:57	74.70	OK	7704	2026-09-15 18:58	74.92	OK
7705	2026-09-15 18:59	77.03	OK	7706	2026-09-15 19:00	75.31	OK
7707	2026-09-15 19:01	73.73	OK	7708	2026-09-15 19:02	75.49	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7709	2026-09-15 19:03	72.29	OK	7710	2026-09-15 19:04	73.88	OK
7711	2026-09-15 19:05	75.41	OK	7712	2026-09-15 19:06	73.28	OK
7713	2026-09-15 19:07	72.99	OK	7714	2026-09-15 19:08	76.65	OK
7715	2026-09-15 19:09	72.65	OK	7716	2026-09-15 19:10	77.22	OK
7717	2026-09-15 19:11	74.32	OK	7718	2026-09-15 19:12	76.01	OK
7719	2026-09-15 19:13	73.55	OK	7720	2026-09-15 19:14	73.65	OK
7721	2026-09-15 19:15	76.71	OK	7722	2026-09-15 19:16	74.36	OK
7723	2026-09-15 19:17	73.10	OK	7724	2026-09-15 19:18	73.27	OK
7725	2026-09-15 19:19	74.03	OK	7726	2026-09-15 19:20	74.10	OK
7727	2026-09-15 19:21	75.67	OK	7728	2026-09-15 19:22	72.52	OK
7729	2026-09-15 19:23	73.62	OK	7730	2026-09-15 19:24	74.04	OK
7731	2026-09-15 19:25	75.19	OK	7732	2026-09-15 19:26	75.34	OK
7733	2026-09-15 19:27	77.12	OK	7734	2026-09-15 19:28	77.04	OK
7735	2026-09-15 19:29	73.33	OK	7736	2026-09-15 19:30	75.50	OK
7737	2026-09-15 19:31	76.19	OK	7738	2026-09-15 19:32	73.91	OK
7739	2026-09-15 19:33	74.22	OK	7740	2026-09-15 19:34	72.78	OK
7741	2026-09-15 19:35	73.64	OK	7742	2026-09-15 19:36	75.65	OK
7743	2026-09-15 19:37	75.58	OK	7744	2026-09-15 19:38	75.41	OK
7745	2026-09-15 19:39	74.01	OK	7746	2026-09-15 19:40	75.70	OK
7747	2026-09-15 19:41	75.81	OK	7748	2026-09-15 19:42	74.32	OK
7749	2026-09-15 19:43	74.38	OK	7750	2026-09-15 19:44	75.49	OK
7751	2026-09-15 19:45	74.66	OK	7752	2026-09-15 19:46	76.82	OK
7753	2026-09-15 19:47	75.70	OK	7754	2026-09-15 19:48	74.59	OK
7755	2026-09-15 19:49	73.41	OK	7756	2026-09-15 19:50	75.14	OK
7757	2026-09-15 19:51	75.74	OK	7758	2026-09-15 19:52	75.29	OK
7759	2026-09-15 19:53	74.84	OK	7760	2026-09-15 19:54	77.34	OK
7761	2026-09-15 19:55	76.20	OK	7762	2026-09-15 19:56	75.32	OK
7763	2026-09-15 19:57	73.87	OK	7764	2026-09-15 19:58	74.95	OK
7765	2026-09-15 19:59	76.66	OK	7766	2026-09-15 20:00	75.21	OK
7767	2026-09-15 20:01	77.19	OK	7768	2026-09-15 20:02	73.89	OK
7769	2026-09-15 20:03	76.53	OK	7770	2026-09-15 20:04	75.77	OK
7771	2026-09-15 20:05	76.24	OK	7772	2026-09-15 20:06	77.63	OK
7773	2026-09-15 20:07	77.35	OK	7774	2026-09-15 20:08	74.01	OK
7775	2026-09-15 20:09	74.60	OK	7776	2026-09-15 20:10	73.32	OK
7777	2026-09-15 20:11	74.51	OK	7778	2026-09-15 20:12	77.01	OK
7779	2026-09-15 20:13	75.65	OK	7780	2026-09-15 20:14	74.84	OK
7781	2026-09-15 20:15	77.57	OK	7782	2026-09-15 20:16	79.15	OK
7783	2026-09-15 20:17	76.37	OK	7784	2026-09-15 20:18	74.26	OK
7785	2026-09-15 20:19	74.65	OK	7786	2026-09-15 20:20	75.79	OK
7787	2026-09-15 20:21	74.00	OK	7788	2026-09-15 20:22	76.72	OK
7789	2026-09-15 20:23	76.50	OK	7790	2026-09-15 20:24	76.54	OK
7791	2026-09-15 20:25	74.92	OK	7792	2026-09-15 20:26	74.95	OK
7793	2026-09-15 20:27	75.70	OK	7794	2026-09-15 20:28	74.51	OK
7795	2026-09-15 20:29	77.16	OK	7796	2026-09-15 20:30	75.74	OK
7797	2026-09-15 20:31	76.57	OK	7798	2026-09-15 20:32	76.62	OK
7799	2026-09-15 20:33	77.85	OK	7800	2026-09-15 20:34	75.72	OK
7801	2026-09-15 20:35	76.43	OK	7802	2026-09-15 20:36	74.59	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7803	2026-09-15 20:37	74.32	OK	7804	2026-09-15 20:38	77.70	OK
7805	2026-09-15 20:39	74.19	OK	7806	2026-09-15 20:40	74.93	OK
7807	2026-09-15 20:41	76.39	OK	7808	2026-09-15 20:42	77.55	OK
7809	2026-09-15 20:43	73.41	OK	7810	2026-09-15 20:44	76.34	OK
7811	2026-09-15 20:45	77.36	OK	7812	2026-09-15 20:46	76.64	OK
7813	2026-09-15 20:47	75.44	OK	7814	2026-09-15 20:48	76.86	OK
7815	2026-09-15 20:49	76.08	OK	7816	2026-09-15 20:50	77.63	OK
7817	2026-09-15 20:51	77.21	OK	7818	2026-09-15 20:52	75.14	OK
7819	2026-09-15 20:53	77.19	OK	7820	2026-09-15 20:54	76.13	OK
7821	2026-09-15 20:55	77.01	OK	7822	2026-09-15 20:56	75.54	OK
7823	2026-09-15 20:57	79.43	OK	7824	2026-09-15 20:58	74.37	OK
7825	2026-09-15 20:59	76.67	OK	7826	2026-09-15 21:00	76.85	OK
7827	2026-09-15 21:01	75.00	OK	7828	2026-09-15 21:02	76.54	OK
7829	2026-09-15 21:03	76.20	OK	7830	2026-09-15 21:04	75.56	OK
7831	2026-09-15 21:05	76.05	OK	7832	2026-09-15 21:06	76.47	OK
7833	2026-09-15 21:07	76.08	OK	7834	2026-09-15 21:08	77.59	OK
7835	2026-09-15 21:09	76.96	OK	7836	2026-09-15 21:10	76.64	OK
7837	2026-09-15 21:11	76.07	OK	7838	2026-09-15 21:12	78.97	OK
7839	2026-09-15 21:13	75.17	OK	7840	2026-09-15 21:14	78.55	OK
7841	2026-09-15 21:15	78.97	OK	7842	2026-09-15 21:16	75.23	OK
7843	2026-09-15 21:17	78.35	OK	7844	2026-09-15 21:18	78.82	OK
7845	2026-09-15 21:19	76.07	OK	7846	2026-09-15 21:20	75.50	OK
7847	2026-09-15 21:21	77.89	OK	7848	2026-09-15 21:22	77.68	OK
7849	2026-09-15 21:23	77.45	OK	7850	2026-09-15 21:24	76.63	OK
7851	2026-09-15 21:25	77.96	OK	7852	2026-09-15 21:26	76.27	OK
7853	2026-09-15 21:27	78.01	OK	7854	2026-09-15 21:28	78.08	OK
7855	2026-09-15 21:29	76.56	OK	7856	2026-09-15 21:30	76.08	OK
7857	2026-09-15 21:31	77.61	OK	7858	2026-09-15 21:32	79.05	OK
7859	2026-09-15 21:33	78.65	OK	7860	2026-09-15 21:34	79.38	OK
7861	2026-09-15 21:35	76.97	OK	7862	2026-09-15 21:36	74.78	OK
7863	2026-09-15 21:37	80.05	OK	7864	2026-09-15 21:38	78.09	OK
7865	2026-09-15 21:39	79.35	OK	7866	2026-09-15 21:40	79.78	OK
7867	2026-09-15 21:41	76.21	OK	7868	2026-09-15 21:42	78.36	OK
7869	2026-09-15 21:43	77.09	OK	7870	2026-09-15 21:44	77.68	OK
7871	2026-09-15 21:45	76.65	OK	7872	2026-09-15 21:46	78.94	OK
7873	2026-09-15 21:47	76.21	OK	7874	2026-09-15 21:48	77.91	OK
7875	2026-09-15 21:49	80.57	OK	7876	2026-09-15 21:50	80.67	OK
7877	2026-09-15 21:51	76.41	OK	7878	2026-09-15 21:52	77.80	OK
7879	2026-09-15 21:53	77.30	OK	7880	2026-09-15 21:54	77.98	OK
7881	2026-09-15 21:55	78.68	OK	7882	2026-09-15 21:56	79.04	OK
7883	2026-09-15 21:57	76.73	OK	7884	2026-09-15 21:58	79.55	OK
7885	2026-09-15 21:59	77.59	OK	7886	2026-09-15 22:00	79.69	OK
7887	2026-09-15 22:01	75.35	OK	7888	2026-09-15 22:02	79.41	OK
7889	2026-09-15 22:03	76.16	OK	7890	2026-09-15 22:04	79.22	OK
7891	2026-09-15 22:05	78.04	OK	7892	2026-09-15 22:06	79.44	OK
7893	2026-09-15 22:07	79.58	OK	7894	2026-09-15 22:08	78.40	OK
7895	2026-09-15 22:09	77.01	OK	7896	2026-09-15 22:10	76.08	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7897	2026-09-15 22:11	78.17	OK	7898	2026-09-15 22:12	75.82	OK
7899	2026-09-15 22:13	79.24	OK	7900	2026-09-15 22:14	78.36	OK
7901	2026-09-15 22:15	76.59	OK	7902	2026-09-15 22:16	76.90	OK
7903	2026-09-15 22:17	78.45	OK	7904	2026-09-15 22:18	77.83	OK
7905	2026-09-15 22:19	76.98	OK	7906	2026-09-15 22:20	78.39	OK
7907	2026-09-15 22:21	76.47	OK	7908	2026-09-15 22:22	77.94	OK
7909	2026-09-15 22:23	77.18	OK	7910	2026-09-15 22:24	79.64	OK
7911	2026-09-15 22:25	80.57	OK	7912	2026-09-15 22:26	80.56	OK
7913	2026-09-15 22:27	79.78	OK	7914	2026-09-15 22:28	77.39	OK
7915	2026-09-15 22:29	77.66	OK	7916	2026-09-15 22:30	79.84	OK
7917	2026-09-15 22:31	77.67	OK	7918	2026-09-15 22:32	77.33	OK
7919	2026-09-15 22:33	80.63	OK	7920	2026-09-15 22:34	78.03	OK
7921	2026-09-15 22:35	78.72	OK	7922	2026-09-15 22:36	79.56	OK
7923	2026-09-15 22:37	79.23	OK	7924	2026-09-15 22:38	81.09	OK
7925	2026-09-15 22:39	78.97	OK	7926	2026-09-15 22:40	80.96	OK
7927	2026-09-15 22:41	80.40	OK	7928	2026-09-15 22:42	78.75	OK
7929	2026-09-15 22:43	78.57	OK	7930	2026-09-15 22:44	78.43	OK
7931	2026-09-15 22:45	77.20	OK	7932	2026-09-15 22:46	78.97	OK
7933	2026-09-15 22:47	78.09	OK	7934	2026-09-15 22:48	79.96	OK
7935	2026-09-15 22:49	76.94	OK	7936	2026-09-15 22:50	77.99	OK
7937	2026-09-15 22:51	79.88	OK	7938	2026-09-15 22:52	81.98	OK
7939	2026-09-15 22:53	80.82	OK	7940	2026-09-15 22:54	80.69	OK
7941	2026-09-15 22:55	80.13	OK	7942	2026-09-15 22:56	79.30	OK
7943	2026-09-15 22:57	78.85	OK	7944	2026-09-15 22:58	77.41	OK
7945	2026-09-15 22:59	78.37	OK	7946	2026-09-15 23:00	80.97	OK
7947	2026-09-15 23:01	79.40	OK	7948	2026-09-15 23:02	80.50	OK
7949	2026-09-15 23:03	79.49	OK	7950	2026-09-15 23:04	81.77	OK
7951	2026-09-15 23:05	76.86	OK	7952	2026-09-15 23:06	80.51	OK
7953	2026-09-15 23:07	76.69	OK	7954	2026-09-15 23:08	79.45	OK
7955	2026-09-15 23:09	78.93	OK	7956	2026-09-15 23:10	77.61	OK
7957	2026-09-15 23:11	77.99	OK	7958	2026-09-15 23:12	79.94	OK
7959	2026-09-15 23:13	78.87	OK	7960	2026-09-15 23:14	80.14	OK
7961	2026-09-15 23:15	78.39	OK	7962	2026-09-15 23:16	77.21	OK
7963	2026-09-15 23:17	80.93	OK	7964	2026-09-15 23:18	79.78	OK
7965	2026-09-15 23:19	79.78	OK	7966	2026-09-15 23:20	79.50	OK
7967	2026-09-15 23:21	78.65	OK	7968	2026-09-15 23:22	81.07	OK
7969	2026-09-15 23:23	82.09	OK	7970	2026-09-15 23:24	77.54	OK
7971	2026-09-15 23:25	80.75	OK	7972	2026-09-15 23:26	80.20	OK
7973	2026-09-15 23:27	78.25	OK	7974	2026-09-15 23:28	82.64	OK
7975	2026-09-15 23:29	82.43	OK	7976	2026-09-15 23:30	79.49	OK
7977	2026-09-15 23:31	79.84	OK	7978	2026-09-15 23:32	78.56	OK
7979	2026-09-15 23:33	79.99	OK	7980	2026-09-15 23:34	80.20	OK
7981	2026-09-15 23:35	79.07	OK	7982	2026-09-15 23:36	79.12	OK
7983	2026-09-15 23:37	79.66	OK	7984	2026-09-15 23:38	80.83	OK
7985	2026-09-15 23:39	82.50	OK	7986	2026-09-15 23:40	80.27	OK
7987	2026-09-15 23:41	80.27	OK	7988	2026-09-15 23:42	78.72	OK
7989	2026-09-15 23:43	79.06	OK	7990	2026-09-15 23:44	82.35	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7991	2026-09-15 23:45	79.98	OK	7992	2026-09-15 23:46	78.86	OK
7993	2026-09-15 23:47	81.62	OK	7994	2026-09-15 23:48	80.44	OK
7995	2026-09-15 23:49	79.39	OK	7996	2026-09-15 23:50	80.24	OK
7997	2026-09-15 23:51	79.00	OK	7998	2026-09-15 23:52	81.02	OK
7999	2026-09-15 23:53	78.86	OK	8000	2026-09-15 23:54	79.83	OK
8001	2026-09-15 23:55	81.68	OK	8002	2026-09-15 23:56	78.11	OK
8003	2026-09-15 23:57	79.89	OK	8004	2026-09-15 23:58	81.14	OK
8005	2026-09-15 23:59	81.09	OK	8006	2026-09-16 00:00	80.16	OK
8007	2026-09-16 00:01	80.14	OK	8008	2026-09-16 00:02	82.03	OK
8009	2026-09-16 00:03	80.45	OK	8010	2026-09-16 00:04	80.60	OK
8011	2026-09-16 00:05	80.61	OK	8012	2026-09-16 00:06	82.04	OK
8013	2026-09-16 00:07	77.48	OK	8014	2026-09-16 00:08	80.53	OK
8015	2026-09-16 00:09	81.33	OK	8016	2026-09-16 00:10	77.72	OK
8017	2026-09-16 00:11	80.76	OK	8018	2026-09-16 00:12	79.73	OK
8019	2026-09-16 00:13	83.21	OK	8020	2026-09-16 00:14	81.31	OK
8021	2026-09-16 00:15	78.81	OK	8022	2026-09-16 00:16	80.04	OK
8023	2026-09-16 00:17	79.48	OK	8024	2026-09-16 00:18	77.94	OK
8025	2026-09-16 00:19	77.11	OK	8026	2026-09-16 00:20	80.99	OK
8027	2026-09-16 00:21	81.71	OK	8028	2026-09-16 00:22	80.66	OK
8029	2026-09-16 00:23	82.48	OK	8030	2026-09-16 00:24	82.56	OK
8031	2026-09-16 00:25	80.29	OK	8032	2026-09-16 00:26	81.38	OK
8033	2026-09-16 00:27	80.06	OK	8034	2026-09-16 00:28	81.51	OK
8035	2026-09-16 00:29	80.13	OK	8036	2026-09-16 00:30	78.66	OK
8037	2026-09-16 00:31	81.65	OK	8038	2026-09-16 00:32	81.09	OK
8039	2026-09-16 00:33	81.20	OK	8040	2026-09-16 00:34	81.92	OK
8041	2026-09-16 00:35	80.35	OK	8042	2026-09-16 00:36	80.79	OK
8043	2026-09-16 00:37	81.67	OK	8044	2026-09-16 00:38	79.22	OK
8045	2026-09-16 00:39	80.00	OK	8046	2026-09-16 00:40	81.02	OK
8047	2026-09-16 00:41	80.97	OK	8048	2026-09-16 00:42	80.02	OK
8049	2026-09-16 00:43	82.26	OK	8050	2026-09-16 00:44	83.96	OK
8051	2026-09-16 00:45	77.85	OK	8052	2026-09-16 00:46	80.04	OK
8053	2026-09-16 00:47	83.77	OK	8054	2026-09-16 00:48	81.73	OK
8055	2026-09-16 00:49	82.99	OK	8056	2026-09-16 00:50	82.25	OK
8057	2026-09-16 00:51	82.07	OK	8058	2026-09-16 00:52	81.38	OK
8059	2026-09-16 00:53	79.58	OK	8060	2026-09-16 00:54	82.48	OK
8061	2026-09-16 00:55	79.94	OK	8062	2026-09-16 00:56	80.80	OK
8063	2026-09-16 00:57	82.19	OK	8064	2026-09-16 00:58	81.78	OK
8065	2026-09-16 00:59	82.43	OK	8066	2026-09-16 01:00	81.84	OK
8067	2026-09-16 01:01	82.43	OK	8068	2026-09-16 01:02	80.44	OK
8069	2026-09-16 01:03	81.52	OK	8070	2026-09-16 01:04	81.70	OK
8071	2026-09-16 01:05	80.41	OK	8072	2026-09-16 01:06	79.59	OK
8073	2026-09-16 01:07	79.45	OK	8074	2026-09-16 01:08	81.94	OK
8075	2026-09-16 01:09	81.39	OK	8076	2026-09-16 01:10	79.06	OK
8077	2026-09-16 01:11	79.84	OK	8078	2026-09-16 01:12	79.71	OK
8079	2026-09-16 01:13	83.23	OK	8080	2026-09-16 01:14	82.45	OK
8081	2026-09-16 01:15	83.30	OK	8082	2026-09-16 01:16	80.97	OK
8083	2026-09-16 01:17	82.35	OK	8084	2026-09-16 01:18	80.81	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8085	2026-09-16 01:19	82.20	OK	8086	2026-09-16 01:20	80.04	OK
8087	2026-09-16 01:21	82.60	OK	8088	2026-09-16 01:22	81.39	OK
8089	2026-09-16 01:23	80.58	OK	8090	2026-09-16 01:24	79.74	OK
8091	2026-09-16 01:25	82.07	OK	8092	2026-09-16 01:26	81.48	OK
8093	2026-09-16 01:27	84.16	OK	8094	2026-09-16 01:28	80.64	OK
8095	2026-09-16 01:29	80.74	OK	8096	2026-09-16 01:30	81.03	OK
8097	2026-09-16 01:31	80.77	OK	8098	2026-09-16 01:32	80.70	OK
8099	2026-09-16 01:33	82.90	OK	8100	2026-09-16 01:34	80.69	OK
8101	2026-09-16 01:35	78.84	OK	8102	2026-09-16 01:36	80.56	OK
8103	2026-09-16 01:37	81.76	OK	8104	2026-09-16 01:38	81.02	OK
8105	2026-09-16 01:39	81.45	OK	8106	2026-09-16 01:40	80.15	OK
8107	2026-09-16 01:41	80.30	OK	8108	2026-09-16 01:42	81.18	OK
8109	2026-09-16 01:43	81.92	OK	8110	2026-09-16 01:44	80.89	OK
8111	2026-09-16 01:45	82.28	OK	8112	2026-09-16 01:46	81.08	OK
8113	2026-09-16 01:47	81.69	OK	8114	2026-09-16 01:48	82.73	OK
8115	2026-09-16 01:49	80.27	OK	8116	2026-09-16 01:50	78.97	OK
8117	2026-09-16 01:51	81.75	OK	8118	2026-09-16 01:52	78.77	OK
8119	2026-09-16 01:53	80.99	OK	8120	2026-09-16 01:54	80.98	OK
8121	2026-09-16 01:55	84.88	OK	8122	2026-09-16 01:56	82.42	OK
8123	2026-09-16 01:57	81.69	OK	8124	2026-09-16 01:58	83.18	OK
8125	2026-09-16 01:59	82.02	OK	8126	2026-09-16 02:00	83.21	OK
8127	2026-09-16 02:01	81.51	OK	8128	2026-09-16 02:02	83.32	OK
8129	2026-09-16 02:03	81.94	OK	8130	2026-09-16 02:04	83.46	OK
8131	2026-09-16 02:05	80.54	OK	8132	2026-09-16 02:06	81.68	OK
8133	2026-09-16 02:07	81.35	OK	8134	2026-09-16 02:08	82.92	OK
8135	2026-09-16 02:09	83.24	OK	8136	2026-09-16 02:10	80.52	OK
8137	2026-09-16 02:11	79.70	OK	8138	2026-09-16 02:12	83.47	OK
8139	2026-09-16 02:13	80.87	OK	8140	2026-09-16 02:14	80.94	OK
8141	2026-09-16 02:15	81.56	OK	8142	2026-09-16 02:16	80.09	OK
8143	2026-09-16 02:17	79.34	OK	8144	2026-09-16 02:18	81.35	OK
8145	2026-09-16 02:19	83.00	OK	8146	2026-09-16 02:20	80.11	OK
8147	2026-09-16 02:21	81.31	OK	8148	2026-09-16 02:22	81.38	OK
8149	2026-09-16 02:23	82.50	OK	8150	2026-09-16 02:24	79.80	OK
8151	2026-09-16 02:25	80.85	OK	8152	2026-09-16 02:26	80.69	OK
8153	2026-09-16 02:27	82.16	OK	8154	2026-09-16 02:28	81.93	OK
8155	2026-09-16 02:29	81.07	OK	8156	2026-09-16 02:30	83.76	OK
8157	2026-09-16 02:31	79.77	OK	8158	2026-09-16 02:32	83.68	OK
8159	2026-09-16 02:33	81.27	OK	8160	2026-09-16 02:34	79.44	OK
8161	2026-09-16 02:35	82.35	OK	8162	2026-09-16 02:36	80.21	OK
8163	2026-09-16 02:37	79.34	OK	8164	2026-09-16 02:38	84.62	OK
8165	2026-09-16 02:39	83.82	OK	8166	2026-09-16 02:40	82.36	OK
8167	2026-09-16 02:41	82.16	OK	8168	2026-09-16 02:42	80.92	OK
8169	2026-09-16 02:43	82.35	OK	8170	2026-09-16 02:44	82.30	OK
8171	2026-09-16 02:45	81.52	OK	8172	2026-09-16 02:46	82.31	OK
8173	2026-09-16 02:47	82.39	OK	8174	2026-09-16 02:48	82.54	OK
8175	2026-09-16 02:49	82.98	OK	8176	2026-09-16 02:50	83.35	OK
8177	2026-09-16 02:51	81.29	OK	8178	2026-09-16 02:52	80.44	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8179	2026-09-16 02:53	79.83	OK	8180	2026-09-16 02:54	79.65	OK
8181	2026-09-16 02:55	83.62	OK	8182	2026-09-16 02:56	82.73	OK
8183	2026-09-16 02:57	80.31	OK	8184	2026-09-16 02:58	81.72	OK
8185	2026-09-16 02:59	81.01	OK	8186	2026-09-16 03:00	79.99	OK
8187	2026-09-16 03:01	80.18	OK	8188	2026-09-16 03:02	82.35	OK
8189	2026-09-16 03:03	80.08	OK	8190	2026-09-16 03:04	82.49	OK
8191	2026-09-16 03:05	83.47	OK	8192	2026-09-16 03:06	80.96	OK
8193	2026-09-16 03:07	81.48	OK	8194	2026-09-16 03:08	79.77	OK
8195	2026-09-16 03:09	81.08	OK	8196	2026-09-16 03:10	81.80	OK
8197	2026-09-16 03:11	80.37	OK	8198	2026-09-16 03:12	84.57	OK
8199	2026-09-16 03:13	82.66	OK	8200	2026-09-16 03:14	82.24	OK
8201	2026-09-16 03:15	81.04	OK	8202	2026-09-16 03:16	79.60	OK
8203	2026-09-16 03:17	81.92	OK	8204	2026-09-16 03:18	80.76	OK
8205	2026-09-16 03:19	83.43	OK	8206	2026-09-16 03:20	84.11	OK
8207	2026-09-16 03:21	81.49	OK	8208	2026-09-16 03:22	80.26	OK
8209	2026-09-16 03:23	82.84	OK	8210	2026-09-16 03:24	80.43	OK
8211	2026-09-16 03:25	81.74	OK	8212	2026-09-16 03:26	81.84	OK
8213	2026-09-16 03:27	80.94	OK	8214	2026-09-16 03:28	80.36	OK
8215	2026-09-16 03:29	81.60	OK	8216	2026-09-16 03:30	81.35	OK
8217	2026-09-16 03:31	81.90	OK	8218	2026-09-16 03:32	81.08	OK
8219	2026-09-16 03:33	81.76	OK	8220	2026-09-16 03:34	82.45	OK
8221	2026-09-16 03:35	80.78	OK	8222	2026-09-16 03:36	84.20	OK
8223	2026-09-16 03:37	80.78	OK	8224	2026-09-16 03:38	81.15	OK
8225	2026-09-16 03:39	81.06	OK	8226	2026-09-16 03:40	82.35	OK
8227	2026-09-16 03:41	81.72	OK	8228	2026-09-16 03:42	83.98	OK
8229	2026-09-16 03:43	83.59	OK	8230	2026-09-16 03:44	82.82	OK
8231	2026-09-16 03:45	79.76	OK	8232	2026-09-16 03:46	80.49	OK
8233	2026-09-16 03:47	83.58	OK	8234	2026-09-16 03:48	82.80	OK
8235	2026-09-16 03:49	84.83	OK	8236	2026-09-16 03:50	83.00	OK
8237	2026-09-16 03:51	82.64	OK	8238	2026-09-16 03:52	83.25	OK
8239	2026-09-16 03:53	79.83	OK	8240	2026-09-16 03:54	81.08	OK
8241	2026-09-16 03:55	80.65	OK	8242	2026-09-16 03:56	82.23	OK
8243	2026-09-16 03:57	81.46	OK	8244	2026-09-16 03:58	80.43	OK
8245	2026-09-16 03:59	81.28	OK	8246	2026-09-16 04:00	82.88	OK
8247	2026-09-16 04:01	82.22	OK	8248	2026-09-16 04:02	80.66	OK
8249	2026-09-16 04:03	81.56	OK	8250	2026-09-16 04:04	80.49	OK
8251	2026-09-16 04:05	82.57	OK	8252	2026-09-16 04:06	79.97	OK
8253	2026-09-16 04:07	80.05	OK	8254	2026-09-16 04:08	84.05	OK
8255	2026-09-16 04:09	81.28	OK	8256	2026-09-16 04:10	82.19	OK
8257	2026-09-16 04:11	81.47	OK	8258	2026-09-16 04:12	80.79	OK
8259	2026-09-16 04:13	83.06	OK	8260	2026-09-16 04:14	82.88	OK
8261	2026-09-16 04:15	82.42	OK	8262	2026-09-16 04:16	80.23	OK
8263	2026-09-16 04:17	80.19	OK	8264	2026-09-16 04:18	81.23	OK
8265	2026-09-16 04:19	80.16	OK	8266	2026-09-16 04:20	79.50	OK
8267	2026-09-16 04:21	81.25	OK	8268	2026-09-16 04:22	82.51	OK
8269	2026-09-16 04:23	81.34	OK	8270	2026-09-16 04:24	79.57	OK
8271	2026-09-16 04:25	79.39	OK	8272	2026-09-16 04:26	81.11	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8273	2026-09-16 04:27	82.04	OK	8274	2026-09-16 04:28	82.59	OK
8275	2026-09-16 04:29	80.51	OK	8276	2026-09-16 04:30	81.41	OK
8277	2026-09-16 04:31	80.26	OK	8278	2026-09-16 04:32	82.19	OK
8279	2026-09-16 04:33	80.04	OK	8280	2026-09-16 04:34	80.30	OK
8281	2026-09-16 04:35	80.30	OK	8282	2026-09-16 04:36	81.85	OK
8283	2026-09-16 04:37	79.03	OK	8284	2026-09-16 04:38	80.79	OK
8285	2026-09-16 04:39	80.79	OK	8286	2026-09-16 04:40	82.74	OK
8287	2026-09-16 04:41	82.03	OK	8288	2026-09-16 04:42	80.48	OK
8289	2026-09-16 04:43	82.44	OK	8290	2026-09-16 04:44	80.46	OK
8291	2026-09-16 04:45	83.55	OK	8292	2026-09-16 04:46	81.27	OK
8293	2026-09-16 04:47	79.79	OK	8294	2026-09-16 04:48	81.58	OK
8295	2026-09-16 04:49	81.65	OK	8296	2026-09-16 04:50	81.27	OK
8297	2026-09-16 04:51	80.91	OK	8298	2026-09-16 04:52	79.60	OK
8299	2026-09-16 04:53	80.17	OK	8300	2026-09-16 04:54	81.21	OK
8301	2026-09-16 04:55	82.17	OK	8302	2026-09-16 04:56	80.46	OK
8303	2026-09-16 04:57	83.06	OK	8304	2026-09-16 04:58	81.05	OK
8305	2026-09-16 04:59	77.96	OK	8306	2026-09-16 05:00	81.04	OK
8307	2026-09-16 05:01	78.62	OK	8308	2026-09-16 05:02	79.70	OK
8309	2026-09-16 05:03	82.72	OK	8310	2026-09-16 05:04	81.39	OK
8311	2026-09-16 05:05	78.05	OK	8312	2026-09-16 05:06	79.36	OK
8313	2026-09-16 05:07	82.32	OK	8314	2026-09-16 05:08	78.85	OK
8315	2026-09-16 05:09	80.13	OK	8316	2026-09-16 05:10	79.85	OK
8317	2026-09-16 05:11	80.36	OK	8318	2026-09-16 05:12	79.28	OK
8319	2026-09-16 05:13	80.52	OK	8320	2026-09-16 05:14	78.34	OK
8321	2026-09-16 05:15	79.02	OK	8322	2026-09-16 05:16	79.67	OK
8323	2026-09-16 05:17	79.38	OK	8324	2026-09-16 05:18	80.65	OK
8325	2026-09-16 05:19	80.99	OK	8326	2026-09-16 05:20	80.89	OK
8327	2026-09-16 05:21	81.97	OK	8328	2026-09-16 05:22	80.51	OK
8329	2026-09-16 05:23	82.33	OK	8330	2026-09-16 05:24	80.39	OK
8331	2026-09-16 05:25	78.74	OK	8332	2026-09-16 05:26	81.98	OK
8333	2026-09-16 05:27	78.46	OK	8334	2026-09-16 05:28	79.40	OK
8335	2026-09-16 05:29	81.51	OK	8336	2026-09-16 05:30	79.24	OK
8337	2026-09-16 05:31	81.30	OK	8338	2026-09-16 05:32	82.17	OK
8339	2026-09-16 05:33	81.55	OK	8340	2026-09-16 05:34	79.15	OK
8341	2026-09-16 05:35	81.11	OK	8342	2026-09-16 05:36	82.00	OK
8343	2026-09-16 05:37	80.07	OK	8344	2026-09-16 05:38	80.93	OK
8345	2026-09-16 05:39	80.79	OK	8346	2026-09-16 05:40	78.99	OK
8347	2026-09-16 05:41	78.98	OK	8348	2026-09-16 05:42	80.25	OK
8349	2026-09-16 05:43	77.44	OK	8350	2026-09-16 05:44	79.97	OK
8351	2026-09-16 05:45	79.69	OK	8352	2026-09-16 05:46	80.81	OK
8353	2026-09-16 05:47	78.75	OK	8354	2026-09-16 05:48	80.38	OK
8355	2026-09-16 05:49	80.61	OK	8356	2026-09-16 05:50	80.62	OK
8357	2026-09-16 05:51	81.16	OK	8358	2026-09-16 05:52	79.24	OK
8359	2026-09-16 05:53	80.73	OK	8360	2026-09-16 05:54	78.95	OK
8361	2026-09-16 05:55	79.37	OK	8362	2026-09-16 05:56	83.04	OK
8363	2026-09-16 05:57	78.21	OK	8364	2026-09-16 05:58	80.84	OK
8365	2026-09-16 05:59	80.83	OK	8366	2026-09-16 06:00	80.38	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8367	2026-09-16 06:01	78.24	OK	8368	2026-09-16 06:02	80.25	OK
8369	2026-09-16 06:03	79.19	OK	8370	2026-09-16 06:04	80.32	OK
8371	2026-09-16 06:05	81.68	OK	8372	2026-09-16 06:06	79.81	OK
8373	2026-09-16 06:07	79.19	OK	8374	2026-09-16 06:08	81.74	OK
8375	2026-09-16 06:09	80.08	OK	8376	2026-09-16 06:10	80.34	OK
8377	2026-09-16 06:11	79.97	OK	8378	2026-09-16 06:12	79.98	OK
8379	2026-09-16 06:13	77.81	OK	8380	2026-09-16 06:14	80.05	OK
8381	2026-09-16 06:15	80.33	OK	8382	2026-09-16 06:16	82.25	OK
8383	2026-09-16 06:17	82.23	OK	8384	2026-09-16 06:18	79.53	OK
8385	2026-09-16 06:19	78.89	OK	8386	2026-09-16 06:20	82.35	OK
8387	2026-09-16 06:21	78.52	OK	8388	2026-09-16 06:22	82.10	OK
8389	2026-09-16 06:23	80.11	OK	8390	2026-09-16 06:24	77.76	OK
8391	2026-09-16 06:25	79.88	OK	8392	2026-09-16 06:26	79.26	OK
8393	2026-09-16 06:27	79.79	OK	8394	2026-09-16 06:28	78.46	OK
8395	2026-09-16 06:29	77.49	OK	8396	2026-09-16 06:30	79.99	OK
8397	2026-09-16 06:31	76.23	OK	8398	2026-09-16 06:32	80.41	OK
8399	2026-09-16 06:33	79.03	OK	8400	2026-09-16 06:34	80.00	OK
8401	2026-09-16 06:35	78.11	OK	8402	2026-09-16 06:36	79.41	OK
8403	2026-09-16 06:37	78.86	OK	8404	2026-09-16 06:38	79.23	OK
8405	2026-09-16 06:39	80.14	OK	8406	2026-09-16 06:40	76.39	OK
8407	2026-09-16 06:41	81.24	OK	8408	2026-09-16 06:42	77.81	OK
8409	2026-09-16 06:43	79.16	OK	8410	2026-09-16 06:44	79.92	OK
8411	2026-09-16 06:45	80.66	OK	8412	2026-09-16 06:46	78.14	OK
8413	2026-09-16 06:47	79.93	OK	8414	2026-09-16 06:48	77.54	OK
8415	2026-09-16 06:49	79.01	OK	8416	2026-09-16 06:50	79.65	OK
8417	2026-09-16 06:51	77.93	OK	8418	2026-09-16 06:52	78.86	OK
8419	2026-09-16 06:53	77.43	OK	8420	2026-09-16 06:54	80.98	OK
8421	2026-09-16 06:55	79.16	OK	8422	2026-09-16 06:56	81.11	OK
8423	2026-09-16 06:57	77.69	OK	8424	2026-09-16 06:58	78.11	OK
8425	2026-09-16 06:59	78.48	OK	8426	2026-09-16 07:00	80.14	OK
8427	2026-09-16 07:01	79.04	OK	8428	2026-09-16 07:02	78.85	OK
8429	2026-09-16 07:03	79.21	OK	8430	2026-09-16 07:04	79.44	OK
8431	2026-09-16 07:05	78.24	OK	8432	2026-09-16 07:06	77.80	OK
8433	2026-09-16 07:07	78.99	OK	8434	2026-09-16 07:08	79.79	OK
8435	2026-09-16 07:09	79.29	OK	8436	2026-09-16 07:10	78.70	OK
8437	2026-09-16 07:11	79.33	OK	8438	2026-09-16 07:12	76.94	OK
8439	2026-09-16 07:13	78.97	OK	8440	2026-09-16 07:14	79.38	OK
8441	2026-09-16 07:15	76.42	OK	8442	2026-09-16 07:16	77.21	OK
8443	2026-09-16 07:17	79.78	OK	8444	2026-09-16 07:18	77.00	OK
8445	2026-09-16 07:19	79.87	OK	8446	2026-09-16 07:20	77.82	OK
8447	2026-09-16 07:21	76.53	OK	8448	2026-09-16 07:22	78.99	OK
8449	2026-09-16 07:23	78.00	OK	8450	2026-09-16 07:24	79.11	OK
8451	2026-09-16 07:25	79.35	OK	8452	2026-09-16 07:26	78.19	OK
8453	2026-09-16 07:27	78.04	OK	8454	2026-09-16 07:28	79.27	OK
8455	2026-09-16 07:29	76.90	OK	8456	2026-09-16 07:30	79.64	OK
8457	2026-09-16 07:31	76.40	OK	8458	2026-09-16 07:32	77.90	OK
8459	2026-09-16 07:33	77.04	OK	8460	2026-09-16 07:34	78.00	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8461	2026-09-16 07:35	77.40	OK	8462	2026-09-16 07:36	77.74	OK
8463	2026-09-16 07:37	80.49	OK	8464	2026-09-16 07:38	80.56	OK
8465	2026-09-16 07:39	79.19	OK	8466	2026-09-16 07:40	78.87	OK
8467	2026-09-16 07:41	80.17	OK	8468	2026-09-16 07:42	77.76	OK
8469	2026-09-16 07:43	78.24	OK	8470	2026-09-16 07:44	79.29	OK
8471	2026-09-16 07:45	77.38	OK	8472	2026-09-16 07:46	76.88	OK
8473	2026-09-16 07:47	78.34	OK	8474	2026-09-16 07:48	79.29	OK
8475	2026-09-16 07:49	77.74	OK	8476	2026-09-16 07:50	77.52	OK
8477	2026-09-16 07:51	78.17	OK	8478	2026-09-16 07:52	75.51	OK
8479	2026-09-16 07:53	78.33	OK	8480	2026-09-16 07:54	77.83	OK
8481	2026-09-16 07:55	78.74	OK	8482	2026-09-16 07:56	77.76	OK
8483	2026-09-16 07:57	75.81	OK	8484	2026-09-16 07:58	76.76	OK
8485	2026-09-16 07:59	79.26	OK	8486	2026-09-16 08:00	77.66	OK
8487	2026-09-16 08:01	76.81	OK	8488	2026-09-16 08:02	77.44	OK
8489	2026-09-16 08:03	79.50	OK	8490	2026-09-16 08:04	75.38	OK
8491	2026-09-16 08:05	76.40	OK	8492	2026-09-16 08:06	78.20	OK
8493	2026-09-16 08:07	76.79	OK	8494	2026-09-16 08:08	76.77	OK
8495	2026-09-16 08:09	78.36	OK	8496	2026-09-16 08:10	77.08	OK
8497	2026-09-16 08:11	77.15	OK	8498	2026-09-16 08:12	78.34	OK
8499	2026-09-16 08:13	78.70	OK	8500	2026-09-16 08:14	74.79	OK
8501	2026-09-16 08:15	79.26	OK	8502	2026-09-16 08:16	77.32	OK
8503	2026-09-16 08:17	78.56	OK	8504	2026-09-16 08:18	78.85	OK
8505	2026-09-16 08:19	79.88	OK	8506	2026-09-16 08:20	75.40	OK
8507	2026-09-16 08:21	78.33	OK	8508	2026-09-16 08:22	74.74	OK
8509	2026-09-16 08:23	78.01	OK	8510	2026-09-16 08:24	77.32	OK
8511	2026-09-16 08:25	78.60	OK	8512	2026-09-16 08:26	79.63	OK
8513	2026-09-16 08:27	75.15	OK	8514	2026-09-16 08:28	78.89	OK
8515	2026-09-16 08:29	76.08	OK	8516	2026-09-16 08:30	77.18	OK
8517	2026-09-16 08:31	79.22	OK	8518	2026-09-16 08:32	77.88	OK
8519	2026-09-16 08:33	77.33	OK	8520	2026-09-16 08:34	78.26	OK
8521	2026-09-16 08:35	76.26	OK	8522	2026-09-16 08:36	77.11	OK
8523	2026-09-16 08:37	74.80	OK	8524	2026-09-16 08:38	77.69	OK
8525	2026-09-16 08:39	77.64	OK	8526	2026-09-16 08:40	77.90	OK
8527	2026-09-16 08:41	77.91	OK	8528	2026-09-16 08:42	77.62	OK
8529	2026-09-16 08:43	75.62	OK	8530	2026-09-16 08:44	76.32	OK
8531	2026-09-16 08:45	75.32	OK	8532	2026-09-16 08:46	76.54	OK
8533	2026-09-16 08:47	75.91	OK	8534	2026-09-16 08:48	76.42	OK
8535	2026-09-16 08:49	76.42	OK	8536	2026-09-16 08:50	76.91	OK
8537	2026-09-16 08:51	75.81	OK	8538	2026-09-16 08:52	78.25	OK
8539	2026-09-16 08:53	76.88	OK	8540	2026-09-16 08:54	78.89	OK
8541	2026-09-16 08:55	77.74	OK	8542	2026-09-16 08:56	76.27	OK
8543	2026-09-16 08:57	75.73	OK	8544	2026-09-16 08:58	75.58	OK
8545	2026-09-16 08:59	76.95	OK	8546	2026-09-16 09:00	76.18	OK
8547	2026-09-16 09:01	75.35	OK	8548	2026-09-16 09:02	76.61	OK
8549	2026-09-16 09:03	76.51	OK	8550	2026-09-16 09:04	77.12	OK
8551	2026-09-16 09:05	76.46	OK	8552	2026-09-16 09:06	74.88	OK
8553	2026-09-16 09:07	76.91	OK	8554	2026-09-16 09:08	75.63	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8555	2026-09-16 09:09	74.17	OK	8556	2026-09-16 09:10	74.74	OK
8557	2026-09-16 09:11	77.35	OK	8558	2026-09-16 09:12	76.45	OK
8559	2026-09-16 09:13	75.40	OK	8560	2026-09-16 09:14	77.01	OK
8561	2026-09-16 09:15	74.63	OK	8562	2026-09-16 09:16	74.64	OK
8563	2026-09-16 09:17	76.01	OK	8564	2026-09-16 09:18	77.11	OK
8565	2026-09-16 09:19	76.14	OK	8566	2026-09-16 09:20	75.87	OK
8567	2026-09-16 09:21	75.85	OK	8568	2026-09-16 09:22	72.65	OK
8569	2026-09-16 09:23	74.19	OK	8570	2026-09-16 09:24	75.09	OK
8571	2026-09-16 09:25	75.50	OK	8572	2026-09-16 09:26	77.64	OK
8573	2026-09-16 09:27	75.89	OK	8574	2026-09-16 09:28	74.40	OK
8575	2026-09-16 09:29	76.70	OK	8576	2026-09-16 09:30	75.10	OK
8577	2026-09-16 09:31	76.46	OK	8578	2026-09-16 09:32	75.88	OK
8579	2026-09-16 09:33	74.54	OK	8580	2026-09-16 09:34	74.96	OK
8581	2026-09-16 09:35	75.07	OK	8582	2026-09-16 09:36	75.98	OK
8583	2026-09-16 09:37	74.07	OK	8584	2026-09-16 09:38	75.82	OK
8585	2026-09-16 09:39	77.20	OK	8586	2026-09-16 09:40	74.81	OK
8587	2026-09-16 09:41	76.44	OK	8588	2026-09-16 09:42	73.64	OK
8589	2026-09-16 09:43	76.68	OK	8590	2026-09-16 09:44	77.11	OK
8591	2026-09-16 09:45	77.20	OK	8592	2026-09-16 09:46	72.98	OK
8593	2026-09-16 09:47	74.60	OK	8594	2026-09-16 09:48	75.37	OK
8595	2026-09-16 09:49	73.11	OK	8596	2026-09-16 09:50	77.56	OK
8597	2026-09-16 09:51	77.62	OK	8598	2026-09-16 09:52	71.92	OK
8599	2026-09-16 09:53	75.49	OK	8600	2026-09-16 09:54	74.45	OK
8601	2026-09-16 09:55	75.18	OK	8602	2026-09-16 09:56	77.11	OK
8603	2026-09-16 09:57	76.95	OK	8604	2026-09-16 09:58	74.34	OK
8605	2026-09-16 09:59	77.54	OK	8606	2026-09-16 10:00	76.51	OK
8607	2026-09-16 10:01	76.14	OK	8608	2026-09-16 10:02	75.08	OK
8609	2026-09-16 10:03	72.64	OK	8610	2026-09-16 10:04	71.43	OK
8611	2026-09-16 10:05	74.49	OK	8612	2026-09-16 10:06	74.43	OK
8613	2026-09-16 10:07	73.70	OK	8614	2026-09-16 10:08	77.15	OK
8615	2026-09-16 10:09	74.48	OK	8616	2026-09-16 10:10	76.40	OK
8617	2026-09-16 10:11	75.21	OK	8618	2026-09-16 10:12	74.74	OK
8619	2026-09-16 10:13	73.70	OK	8620	2026-09-16 10:14	72.66	OK
8621	2026-09-16 10:15	74.65	OK	8622	2026-09-16 10:16	74.04	OK
8623	2026-09-16 10:17	74.91	OK	8624	2026-09-16 10:18	76.09	OK
8625	2026-09-16 10:19	73.50	OK	8626	2026-09-16 10:20	75.02	OK
8627	2026-09-16 10:21	74.33	OK	8628	2026-09-16 10:22	75.81	OK
8629	2026-09-16 10:23	74.77	OK	8630	2026-09-16 10:24	73.68	OK
8631	2026-09-16 10:25	76.59	OK	8632	2026-09-16 10:26	74.24	OK
8633	2026-09-16 10:27	76.27	OK	8634	2026-09-16 10:28	73.97	OK
8635	2026-09-16 10:29	75.00	OK	8636	2026-09-16 10:30	74.39	OK
8637	2026-09-16 10:31	73.77	OK	8638	2026-09-16 10:32	74.00	OK
8639	2026-09-16 10:33	71.69	OK	8640	2026-09-16 10:34	75.36	OK
8641	2026-09-16 10:35	76.04	OK	8642	2026-09-16 10:36	74.15	OK
8643	2026-09-16 10:37	75.46	OK	8644	2026-09-16 10:38	73.19	OK
8645	2026-09-16 10:39	74.27	OK	8646	2026-09-16 10:40	72.32	OK
8647	2026-09-16 10:41	74.87	OK	8648	2026-09-16 10:42	75.01	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8649	2026-09-16 10:43	74.37	OK	8650	2026-09-16 10:44	72.73	OK
8651	2026-09-16 10:45	71.39	OK	8652	2026-09-16 10:46	77.32	OK
8653	2026-09-16 10:47	71.64	OK	8654	2026-09-16 10:48	71.62	OK
8655	2026-09-16 10:49	73.66	OK	8656	2026-09-16 10:50	71.03	OK
8657	2026-09-16 10:51	74.41	OK	8658	2026-09-16 10:52	72.96	OK
8659	2026-09-16 10:53	74.34	OK	8660	2026-09-16 10:54	73.25	OK
8661	2026-09-16 10:55	73.41	OK	8662	2026-09-16 10:56	70.90	OK
8663	2026-09-16 10:57	72.44	OK	8664	2026-09-16 10:58	74.29	OK
8665	2026-09-16 10:59	71.45	OK	8666	2026-09-16 11:00	73.61	OK
8667	2026-09-16 11:01	75.47	OK	8668	2026-09-16 11:02	72.60	OK
8669	2026-09-16 11:03	72.64	OK	8670	2026-09-16 11:04	73.22	OK
8671	2026-09-16 11:05	72.81	OK	8672	2026-09-16 11:06	72.84	OK
8673	2026-09-16 11:07	73.69	OK	8674	2026-09-16 11:08	72.35	OK
8675	2026-09-16 11:09	72.34	OK	8676	2026-09-16 11:10	72.10	OK
8677	2026-09-16 11:11	73.23	OK	8678	2026-09-16 11:12	75.31	OK
8679	2026-09-16 11:13	72.90	OK	8680	2026-09-16 11:14	74.38	OK
8681	2026-09-16 11:15	75.39	OK	8682	2026-09-16 11:16	74.96	OK
8683	2026-09-16 11:17	73.36	OK	8684	2026-09-16 11:18	74.52	OK
8685	2026-09-16 11:19	72.51	OK	8686	2026-09-16 11:20	70.00	OK
8687	2026-09-16 11:21	74.20	OK	8688	2026-09-16 11:22	72.74	OK
8689	2026-09-16 11:23	71.04	OK	8690	2026-09-16 11:24	71.98	OK
8691	2026-09-16 11:25	72.46	OK	8692	2026-09-16 11:26	74.09	OK
8693	2026-09-16 11:27	72.68	OK	8694	2026-09-16 11:28	75.26	OK
8695	2026-09-16 11:29	73.73	OK	8696	2026-09-16 11:30	72.32	OK
8697	2026-09-16 11:31	72.39	OK	8698	2026-09-16 11:32	73.77	OK
8699	2026-09-16 11:33	70.37	OK	8700	2026-09-16 11:34	74.05	OK
8701	2026-09-16 11:35	74.17	OK	8702	2026-09-16 11:36	73.22	OK
8703	2026-09-16 11:37	73.49	OK	8704	2026-09-16 11:38	72.82	OK
8705	2026-09-16 11:39	71.60	OK	8706	2026-09-16 11:40	71.46	OK
8707	2026-09-16 11:41	72.46	OK	8708	2026-09-16 11:42	73.72	OK
8709	2026-09-16 11:43	73.10	OK	8710	2026-09-16 11:44	73.10	OK
8711	2026-09-16 11:45	73.20	OK	8712	2026-09-16 11:46	72.65	OK
8713	2026-09-16 11:47	71.64	OK	8714	2026-09-16 11:48	73.50	OK
8715	2026-09-16 11:49	73.39	OK	8716	2026-09-16 11:50	72.47	OK
8717	2026-09-16 11:51	70.44	OK	8718	2026-09-16 11:52	71.24	OK
8719	2026-09-16 11:53	72.69	OK	8720	2026-09-16 11:54	72.40	OK
8721	2026-09-16 11:55	72.82	OK	8722	2026-09-16 11:56	72.75	OK
8723	2026-09-16 11:57	72.23	OK	8724	2026-09-16 11:58	72.54	OK
8725	2026-09-16 11:59	71.59	OK	8726	2026-09-16 12:00	72.06	OK
8727	2026-09-16 12:01	73.98	OK	8728	2026-09-16 12:02	72.98	OK
8729	2026-09-16 12:03	72.17	OK	8730	2026-09-16 12:04	74.90	OK
8731	2026-09-16 12:05	73.40	OK	8732	2026-09-16 12:06	72.69	OK
8733	2026-09-16 12:07	73.91	OK	8734	2026-09-16 12:08	71.92	OK
8735	2026-09-16 12:09	71.95	OK	8736	2026-09-16 12:10	71.42	OK
8737	2026-09-16 12:11	72.52	OK	8738	2026-09-16 12:12	72.03	OK
8739	2026-09-16 12:13	74.72	OK	8740	2026-09-16 12:14	74.35	OK
8741	2026-09-16 12:15	72.93	OK	8742	2026-09-16 12:16	73.21	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8743	2026-09-16 12:17	72.66	OK	8744	2026-09-16 12:18	72.86	OK
8745	2026-09-16 12:19	72.00	OK	8746	2026-09-16 12:20	72.68	OK
8747	2026-09-16 12:21	74.29	OK	8748	2026-09-16 12:22	71.87	OK
8749	2026-09-16 12:23	73.12	OK	8750	2026-09-16 12:24	72.19	OK
8751	2026-09-16 12:25	72.44	OK	8752	2026-09-16 12:26	69.85	OK
8753	2026-09-16 12:27	69.39	OK	8754	2026-09-16 12:28	72.04	OK
8755	2026-09-16 12:29	73.14	OK	8756	2026-09-16 12:30	72.83	OK
8757	2026-09-16 12:31	71.95	OK	8758	2026-09-16 12:32	72.96	OK
8759	2026-09-16 12:33	70.68	OK	8760	2026-09-16 12:34	71.94	OK
8761	2026-09-16 12:35	71.98	OK	8762	2026-09-16 12:36	71.40	OK
8763	2026-09-16 12:37	72.51	OK	8764	2026-09-16 12:38	71.16	OK
8765	2026-09-16 12:39	70.50	OK	8766	2026-09-16 12:40	72.07	OK
8767	2026-09-16 12:41	71.39	OK	8768	2026-09-16 12:42	72.05	OK
8769	2026-09-16 12:43	70.15	OK	8770	2026-09-16 12:44	71.01	OK
8771	2026-09-16 12:45	71.80	OK	8772	2026-09-16 12:46	74.30	OK
8773	2026-09-16 12:47	70.44	OK	8774	2026-09-16 12:48	70.78	OK
8775	2026-09-16 12:49	72.48	OK	8776	2026-09-16 12:50	72.12	OK
8777	2026-09-16 12:51	73.94	OK	8778	2026-09-16 12:52	70.23	OK
8779	2026-09-16 12:53	73.25	OK	8780	2026-09-16 12:54	70.82	OK
8781	2026-09-16 12:55	71.65	OK	8782	2026-09-16 12:56	70.94	OK
8783	2026-09-16 12:57	71.15	OK	8784	2026-09-16 12:58	72.41	OK
8785	2026-09-16 12:59	73.38	OK	8786	2026-09-16 13:00	69.80	OK
8787	2026-09-16 13:01	73.67	OK	8788	2026-09-16 13:02	71.26	OK
8789	2026-09-16 13:03	70.81	OK	8790	2026-09-16 13:04	70.42	OK
8791	2026-09-16 13:05	73.04	OK	8792	2026-09-16 13:06	73.16	OK
8793	2026-09-16 13:07	71.03	OK	8794	2026-09-16 13:08	71.52	OK
8795	2026-09-16 13:09	72.22	OK	8796	2026-09-16 13:10	70.62	OK
8797	2026-09-16 13:11	72.18	OK	8798	2026-09-16 13:12	71.79	OK
8799	2026-09-16 13:13	69.17	OK	8800	2026-09-16 13:14	73.28	OK
8801	2026-09-16 13:15	71.83	OK	8802	2026-09-16 13:16	70.61	OK
8803	2026-09-16 13:17	71.17	OK	8804	2026-09-16 13:18	71.28	OK
8805	2026-09-16 13:19	70.21	OK	8806	2026-09-16 13:20	71.53	OK
8807	2026-09-16 13:21	72.82	OK	8808	2026-09-16 13:22	73.43	OK
8809	2026-09-16 13:23	72.43	OK	8810	2026-09-16 13:24	69.33	OK
8811	2026-09-16 13:25	71.24	OK	8812	2026-09-16 13:26	71.78	OK
8813	2026-09-16 13:27	72.57	OK	8814	2026-09-16 13:28	72.58	OK
8815	2026-09-16 13:29	73.67	OK	8816	2026-09-16 13:30	71.02	OK
8817	2026-09-16 13:31	71.76	OK	8818	2026-09-16 13:32	68.63	OK
8819	2026-09-16 13:33	71.78	OK	8820	2026-09-16 13:34	72.76	OK
8821	2026-09-16 13:35	71.66	OK	8822	2026-09-16 13:36	70.72	OK
8823	2026-09-16 13:37	71.90	OK	8824	2026-09-16 13:38	72.55	OK
8825	2026-09-16 13:39	71.10	OK	8826	2026-09-16 13:40	70.93	OK
8827	2026-09-16 13:41	70.02	OK	8828	2026-09-16 13:42	69.99	OK
8829	2026-09-16 13:43	70.77	OK	8830	2026-09-16 13:44	70.66	OK
8831	2026-09-16 13:45	70.96	OK	8832	2026-09-16 13:46	73.38	OK
8833	2026-09-16 13:47	71.39	OK	8834	2026-09-16 13:48	70.59	OK
8835	2026-09-16 13:49	73.06	OK	8836	2026-09-16 13:50	69.80	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8837	2026-09-16 13:51	71.06	OK	8838	2026-09-16 13:52	71.87	OK
8839	2026-09-16 13:53	72.17	OK	8840	2026-09-16 13:54	72.41	OK
8841	2026-09-16 13:55	69.80	OK	8842	2026-09-16 13:56	72.27	OK
8843	2026-09-16 13:57	72.70	OK	8844	2026-09-16 13:58	71.48	OK
8845	2026-09-16 13:59	71.20	OK	8846	2026-09-16 14:00	71.48	OK
8847	2026-09-16 14:01	71.31	OK	8848	2026-09-16 14:02	71.43	OK
8849	2026-09-16 14:03	69.83	OK	8850	2026-09-16 14:04	71.85	OK
8851	2026-09-16 14:05	72.07	OK	8852	2026-09-16 14:06	70.06	OK
8853	2026-09-16 14:07	72.36	OK	8854	2026-09-16 14:08	72.96	OK
8855	2026-09-16 14:09	71.87	OK	8856	2026-09-16 14:10	70.83	OK
8857	2026-09-16 14:11	71.39	OK	8858	2026-09-16 14:12	72.37	OK
8859	2026-09-16 14:13	71.68	OK	8860	2026-09-16 14:14	70.26	OK
8861	2026-09-16 14:15	72.25	OK	8862	2026-09-16 14:16	72.44	OK
8863	2026-09-16 14:17	73.23	OK	8864	2026-09-16 14:18	72.32	OK
8865	2026-09-16 14:19	70.61	OK	8866	2026-09-16 14:20	69.23	OK
8867	2026-09-16 14:21	70.45	OK	8868	2026-09-16 14:22	71.98	OK
8869	2026-09-16 14:23	71.51	OK	8870	2026-09-16 14:24	71.49	OK
8871	2026-09-16 14:25	71.33	OK	8872	2026-09-16 14:26	70.71	OK
8873	2026-09-16 14:27	68.22	OK	8874	2026-09-16 14:28	71.66	OK
8875	2026-09-16 14:29	70.39	OK	8876	2026-09-16 14:30	71.98	OK
8877	2026-09-16 14:31	70.84	OK	8878	2026-09-16 14:32	71.38	OK
8879	2026-09-16 14:33	74.21	OK	8880	2026-09-16 14:34	69.40	OK
8881	2026-09-16 14:35	68.84	OK	8882	2026-09-16 14:36	71.28	OK
8883	2026-09-16 14:37	72.29	OK	8884	2026-09-16 14:38	70.14	OK
8885	2026-09-16 14:39	71.39	OK	8886	2026-09-16 14:40	72.91	OK
8887	2026-09-16 14:41	70.69	OK	8888	2026-09-16 14:42	71.33	OK
8889	2026-09-16 14:43	73.02	OK	8890	2026-09-16 14:44	70.63	OK
8891	2026-09-16 14:45	69.19	OK	8892	2026-09-16 14:46	73.42	OK
8893	2026-09-16 14:47	70.80	OK	8894	2026-09-16 14:48	72.20	OK
8895	2026-09-16 14:49	69.40	OK	8896	2026-09-16 14:50	72.78	OK
8897	2026-09-16 14:51	68.84	OK	8898	2026-09-16 14:52	70.22	OK
8899	2026-09-16 14:53	73.25	OK	8900	2026-09-16 14:54	71.27	OK
8901	2026-09-16 14:55	72.01	OK	8902	2026-09-16 14:56	72.62	OK
8903	2026-09-16 14:57	72.99	OK	8904	2026-09-16 14:58	73.38	OK
8905	2026-09-16 14:59	70.97	OK	8906	2026-09-16 15:00	70.13	OK
8907	2026-09-16 15:01	71.28	OK	8908	2026-09-16 15:02	68.97	OK
8909	2026-09-16 15:03	69.62	OK	8910	2026-09-16 15:04	69.77	OK
8911	2026-09-16 15:05	73.91	OK	8912	2026-09-16 15:06	73.88	OK
8913	2026-09-16 15:07	74.48	OK	8914	2026-09-16 15:08	71.83	OK
8915	2026-09-16 15:09	69.22	OK	8916	2026-09-16 15:10	71.04	OK
8917	2026-09-16 15:11	71.10	OK	8918	2026-09-16 15:12	72.77	OK
8919	2026-09-16 15:13	70.46	OK	8920	2026-09-16 15:14	72.35	OK
8921	2026-09-16 15:15	68.15	OK	8922	2026-09-16 15:16	71.45	OK
8923	2026-09-16 15:17	72.04	OK	8924	2026-09-16 15:18	68.95	OK
8925	2026-09-16 15:19	71.95	OK	8926	2026-09-16 15:20	70.87	OK
8927	2026-09-16 15:21	71.59	OK	8928	2026-09-16 15:22	72.60	OK
8929	2026-09-16 15:23	71.83	OK	8930	2026-09-16 15:24	69.41	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8931	2026-09-16 15:25	72.80	OK	8932	2026-09-16 15:26	70.12	OK
8933	2026-09-16 15:27	71.73	OK	8934	2026-09-16 15:28	70.56	OK
8935	2026-09-16 15:29	72.06	OK	8936	2026-09-16 15:30	70.15	OK
8937	2026-09-16 15:31	71.02	OK	8938	2026-09-16 15:32	71.40	OK
8939	2026-09-16 15:33	71.10	OK	8940	2026-09-16 15:34	71.08	OK
8941	2026-09-16 15:35	71.33	OK	8942	2026-09-16 15:36	70.41	OK
8943	2026-09-16 15:37	70.67	OK	8944	2026-09-16 15:38	70.09	OK
8945	2026-09-16 15:39	73.68	OK	8946	2026-09-16 15:40	72.17	OK
8947	2026-09-16 15:41	71.53	OK	8948	2026-09-16 15:42	69.52	OK
8949	2026-09-16 15:43	72.14	OK	8950	2026-09-16 15:44	72.37	OK
8951	2026-09-16 15:45	73.45	OK	8952	2026-09-16 15:46	72.35	OK
8953	2026-09-16 15:47	72.46	OK	8954	2026-09-16 15:48	72.76	OK
8955	2026-09-16 15:49	71.89	OK	8956	2026-09-16 15:50	70.51	OK
8957	2026-09-16 15:51	72.72	OK	8958	2026-09-16 15:52	71.54	OK
8959	2026-09-16 15:53	69.86	OK	8960	2026-09-16 15:54	70.04	OK
8961	2026-09-16 15:55	69.92	OK	8962	2026-09-16 15:56	71.44	OK
8963	2026-09-16 15:57	72.51	OK	8964	2026-09-16 15:58	71.59	OK
8965	2026-09-16 15:59	72.19	OK	8966	2026-09-16 16:00	71.72	OK
8967	2026-09-16 16:01	72.85	OK	8968	2026-09-16 16:02	73.01	OK
8969	2026-09-16 16:03	69.00	OK	8970	2026-09-16 16:04	73.47	OK
8971	2026-09-16 16:05	72.30	OK	8972	2026-09-16 16:06	71.27	OK
8973	2026-09-16 16:07	72.93	OK	8974	2026-09-16 16:08	69.82	OK
8975	2026-09-16 16:09	73.00	OK	8976	2026-09-16 16:10	72.17	OK
8977	2026-09-16 16:11	71.92	OK	8978	2026-09-16 16:12	69.26	OK
8979	2026-09-16 16:13	70.24	OK	8980	2026-09-16 16:14	69.25	OK
8981	2026-09-16 16:15	72.35	OK	8982	2026-09-16 16:16	71.08	OK
8983	2026-09-16 16:17	72.03	OK	8984	2026-09-16 16:18	73.51	OK
8985	2026-09-16 16:19	72.49	OK	8986	2026-09-16 16:20	73.16	OK
8987	2026-09-16 16:21	70.79	OK	8988	2026-09-16 16:22	71.39	OK
8989	2026-09-16 16:23	70.19	OK	8990	2026-09-16 16:24	71.74	OK
8991	2026-09-16 16:25	70.62	OK	8992	2026-09-16 16:26	69.58	OK
8993	2026-09-16 16:27	72.42	OK	8994	2026-09-16 16:28	73.49	OK
8995	2026-09-16 16:29	72.35	OK	8996	2026-09-16 16:30	70.62	OK
8997	2026-09-16 16:31	74.60	OK	8998	2026-09-16 16:32	71.06	OK
8999	2026-09-16 16:33	70.10	OK	9000	2026-09-16 16:34	71.67	OK
9001	2026-09-16 16:35	72.39	OK	9002	2026-09-16 16:36	70.46	OK
9003	2026-09-16 16:37	69.66	OK	9004	2026-09-16 16:38	69.69	OK
9005	2026-09-16 16:39	72.30	OK	9006	2026-09-16 16:40	69.66	OK
9007	2026-09-16 16:41	69.99	OK	9008	2026-09-16 16:42	71.22	OK
9009	2026-09-16 16:43	71.11	OK	9010	2026-09-16 16:44	70.55	OK
9011	2026-09-16 16:45	70.44	OK	9012	2026-09-16 16:46	72.14	OK
9013	2026-09-16 16:47	72.81	OK	9014	2026-09-16 16:48	70.29	OK
9015	2026-09-16 16:49	72.62	OK	9016	2026-09-16 16:50	71.28	OK
9017	2026-09-16 16:51	72.98	OK	9018	2026-09-16 16:52	72.88	OK
9019	2026-09-16 16:53	72.08	OK	9020	2026-09-16 16:54	71.83	OK
9021	2026-09-16 16:55	70.67	OK	9022	2026-09-16 16:56	71.69	OK
9023	2026-09-16 16:57	72.82	OK	9024	2026-09-16 16:58	71.69	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9025	2026-09-16 16:59	72.39	OK	9026	2026-09-16 17:00	71.17	OK
9027	2026-09-16 17:01	71.23	OK	9028	2026-09-16 17:02	72.40	OK
9029	2026-09-16 17:03	72.40	OK	9030	2026-09-16 17:04	72.11	OK
9031	2026-09-16 17:05	70.85	OK	9032	2026-09-16 17:06	71.45	OK
9033	2026-09-16 17:07	72.95	OK	9034	2026-09-16 17:08	72.94	OK
9035	2026-09-16 17:09	69.70	OK	9036	2026-09-16 17:10	73.49	OK
9037	2026-09-16 17:11	70.12	OK	9038	2026-09-16 17:12	71.56	OK
9039	2026-09-16 17:13	72.76	OK	9040	2026-09-16 17:14	72.14	OK
9041	2026-09-16 17:15	72.12	OK	9042	2026-09-16 17:16	71.52	OK
9043	2026-09-16 17:17	71.23	OK	9044	2026-09-16 17:18	71.37	OK
9045	2026-09-16 17:19	72.09	OK	9046	2026-09-16 17:20	72.69	OK
9047	2026-09-16 17:21	71.25	OK	9048	2026-09-16 17:22	72.95	OK
9049	2026-09-16 17:23	73.08	OK	9050	2026-09-16 17:24	70.28	OK
9051	2026-09-16 17:25	71.29	OK	9052	2026-09-16 17:26	75.66	OK
9053	2026-09-16 17:27	72.61	OK	9054	2026-09-16 17:28	71.40	OK
9055	2026-09-16 17:29	71.19	OK	9056	2026-09-16 17:30	70.91	OK
9057	2026-09-16 17:31	71.54	OK	9058	2026-09-16 17:32	73.01	OK
9059	2026-09-16 17:33	72.28	OK	9060	2026-09-16 17:34	72.98	OK
9061	2026-09-16 17:35	71.93	OK	9062	2026-09-16 17:36	72.24	OK
9063	2026-09-16 17:37	73.27	OK	9064	2026-09-16 17:38	73.03	OK
9065	2026-09-16 17:39	71.25	OK	9066	2026-09-16 17:40	71.52	OK
9067	2026-09-16 17:41	73.10	OK	9068	2026-09-16 17:42	72.28	OK
9069	2026-09-16 17:43	74.68	OK	9070	2026-09-16 17:44	72.87	OK
9071	2026-09-16 17:45	72.16	OK	9072	2026-09-16 17:46	72.96	OK
9073	2026-09-16 17:47	69.63	OK	9074	2026-09-16 17:48	72.47	OK
9075	2026-09-16 17:49	73.84	OK	9076	2026-09-16 17:50	73.67	OK
9077	2026-09-16 17:51	70.98	OK	9078	2026-09-16 17:52	71.50	OK
9079	2026-09-16 17:53	71.51	OK	9080	2026-09-16 17:54	73.04	OK
9081	2026-09-16 17:55	72.85	OK	9082	2026-09-16 17:56	73.87	OK
9083	2026-09-16 17:57	73.78	OK	9084	2026-09-16 17:58	74.96	OK
9085	2026-09-16 17:59	73.21	OK	9086	2026-09-16 18:00	71.61	OK
9087	2026-09-16 18:01	72.21	OK	9088	2026-09-16 18:02	73.29	OK
9089	2026-09-16 18:03	71.41	OK	9090	2026-09-16 18:04	72.53	OK
9091	2026-09-16 18:05	74.57	OK	9092	2026-09-16 18:06	70.89	OK
9093	2026-09-16 18:07	73.09	OK	9094	2026-09-16 18:08	71.60	OK
9095	2026-09-16 18:09	71.45	OK	9096	2026-09-16 18:10	72.22	OK
9097	2026-09-16 18:11	72.44	OK	9098	2026-09-16 18:12	71.07	OK
9099	2026-09-16 18:13	74.38	OK	9100	2026-09-16 18:14	73.53	OK
9101	2026-09-16 18:15	74.25	OK	9102	2026-09-16 18:16	73.09	OK
9103	2026-09-16 18:17	72.66	OK	9104	2026-09-16 18:18	76.57	OK
9105	2026-09-16 18:19	74.59	OK	9106	2026-09-16 18:20	73.86	OK
9107	2026-09-16 18:21	74.30	OK	9108	2026-09-16 18:22	74.86	OK
9109	2026-09-16 18:23	72.69	OK	9110	2026-09-16 18:24	74.84	OK
9111	2026-09-16 18:25	74.36	OK	9112	2026-09-16 18:26	75.11	OK
9113	2026-09-16 18:27	73.73	OK	9114	2026-09-16 18:28	74.88	OK
9115	2026-09-16 18:29	70.90	OK	9116	2026-09-16 18:30	73.42	OK
9117	2026-09-16 18:31	70.74	OK	9118	2026-09-16 18:32	74.81	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9119	2026-09-16 18:33	73.61	OK	9120	2026-09-16 18:34	71.55	OK
9121	2026-09-16 18:35	74.25	OK	9122	2026-09-16 18:36	74.84	OK
9123	2026-09-16 18:37	73.57	OK	9124	2026-09-16 18:38	71.89	OK
9125	2026-09-16 18:39	74.90	OK	9126	2026-09-16 18:40	73.02	OK
9127	2026-09-16 18:41	73.28	OK	9128	2026-09-16 18:42	75.39	OK
9129	2026-09-16 18:43	74.18	OK	9130	2026-09-16 18:44	75.64	OK
9131	2026-09-16 18:45	72.58	OK	9132	2026-09-16 18:46	75.77	OK
9133	2026-09-16 18:47	72.95	OK	9134	2026-09-16 18:48	74.96	OK
9135	2026-09-16 18:49	75.56	OK	9136	2026-09-16 18:50	73.59	OK
9137	2026-09-16 18:51	72.77	OK	9138	2026-09-16 18:52	73.22	OK
9139	2026-09-16 18:53	74.81	OK	9140	2026-09-16 18:54	74.98	OK
9141	2026-09-16 18:55	74.51	OK	9142	2026-09-16 18:56	73.82	OK
9143	2026-09-16 18:57	74.90	OK	9144	2026-09-16 18:58	71.11	OK
9145	2026-09-16 18:59	74.17	OK	9146	2026-09-16 19:00	74.94	OK
9147	2026-09-16 19:01	73.78	OK	9148	2026-09-16 19:02	75.73	OK
9149	2026-09-16 19:03	73.45	OK	9150	2026-09-16 19:04	74.20	OK
9151	2026-09-16 19:05	71.36	OK	9152	2026-09-16 19:06	74.49	OK
9153	2026-09-16 19:07	74.65	OK	9154	2026-09-16 19:08	73.65	OK
9155	2026-09-16 19:09	75.38	OK	9156	2026-09-16 19:10	74.02	OK
9157	2026-09-16 19:11	74.48	OK	9158	2026-09-16 19:12	76.09	OK
9159	2026-09-16 19:13	73.28	OK	9160	2026-09-16 19:14	75.54	OK
9161	2026-09-16 19:15	72.66	OK	9162	2026-09-16 19:16	75.39	OK
9163	2026-09-16 19:17	74.67	OK	9164	2026-09-16 19:18	73.83	OK
9165	2026-09-16 19:19	74.95	OK	9166	2026-09-16 19:20	74.39	OK
9167	2026-09-16 19:21	74.39	OK	9168	2026-09-16 19:22	72.19	OK
9169	2026-09-16 19:23	76.40	OK	9170	2026-09-16 19:24	75.77	OK
9171	2026-09-16 19:25	71.65	OK	9172	2026-09-16 19:26	74.68	OK
9173	2026-09-16 19:27	76.86	OK	9174	2026-09-16 19:28	72.06	OK
9175	2026-09-16 19:29	74.58	OK	9176	2026-09-16 19:30	75.36	OK
9177	2026-09-16 19:31	77.07	OK	9178	2026-09-16 19:32	73.14	OK
9179	2026-09-16 19:33	73.11	OK	9180	2026-09-16 19:34	76.05	OK
9181	2026-09-16 19:35	74.91	OK	9182	2026-09-16 19:36	74.65	OK
9183	2026-09-16 19:37	75.72	OK	9184	2026-09-16 19:38	75.24	OK
9185	2026-09-16 19:39	76.75	OK	9186	2026-09-16 19:40	74.94	OK
9187	2026-09-16 19:41	73.14	OK	9188	2026-09-16 19:42	73.78	OK
9189	2026-09-16 19:43	75.13	OK	9190	2026-09-16 19:44	75.21	OK
9191	2026-09-16 19:45	71.78	OK	9192	2026-09-16 19:46	73.96	OK
9193	2026-09-16 19:47	77.84	OK	9194	2026-09-16 19:48	75.41	OK
9195	2026-09-16 19:49	75.92	OK	9196	2026-09-16 19:50	75.31	OK
9197	2026-09-16 19:51	75.48	OK	9198	2026-09-16 19:52	74.87	OK
9199	2026-09-16 19:53	75.62	OK	9200	2026-09-16 19:54	75.13	OK
9201	2026-09-16 19:55	75.96	OK	9202	2026-09-16 19:56	78.31	OK
9203	2026-09-16 19:57	76.95	OK	9204	2026-09-16 19:58	72.38	OK
9205	2026-09-16 19:59	76.21	OK	9206	2026-09-16 20:00	74.48	OK
9207	2026-09-16 20:01	75.59	OK	9208	2026-09-16 20:02	74.80	OK
9209	2026-09-16 20:03	75.16	OK	9210	2026-09-16 20:04	74.74	OK
9211	2026-09-16 20:05	76.04	OK	9212	2026-09-16 20:06	75.62	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9213	2026-09-16 20:07	75.57	OK	9214	2026-09-16 20:08	76.05	OK
9215	2026-09-16 20:09	78.52	OK	9216	2026-09-16 20:10	72.62	OK
9217	2026-09-16 20:11	76.16	OK	9218	2026-09-16 20:12	76.15	OK
9219	2026-09-16 20:13	74.66	OK	9220	2026-09-16 20:14	77.78	OK
9221	2026-09-16 20:15	74.27	OK	9222	2026-09-16 20:16	76.36	OK
9223	2026-09-16 20:17	75.86	OK	9224	2026-09-16 20:18	77.53	OK
9225	2026-09-16 20:19	74.27	OK	9226	2026-09-16 20:20	75.95	OK
9227	2026-09-16 20:21	73.51	OK	9228	2026-09-16 20:22	77.68	OK
9229	2026-09-16 20:23	74.38	OK	9230	2026-09-16 20:24	76.06	OK
9231	2026-09-16 20:25	75.73	OK	9232	2026-09-16 20:26	76.71	OK
9233	2026-09-16 20:27	76.28	OK	9234	2026-09-16 20:28	75.51	OK
9235	2026-09-16 20:29	77.92	OK	9236	2026-09-16 20:30	73.62	OK
9237	2026-09-16 20:31	77.67	OK	9238	2026-09-16 20:32	74.82	OK
9239	2026-09-16 20:33	74.01	OK	9240	2026-09-16 20:34	77.54	OK
9241	2026-09-16 20:35	77.97	OK	9242	2026-09-16 20:36	77.95	OK
9243	2026-09-16 20:37	75.19	OK	9244	2026-09-16 20:38	74.65	OK
9245	2026-09-16 20:39	77.05	OK	9246	2026-09-16 20:40	78.25	OK
9247	2026-09-16 20:41	76.39	OK	9248	2026-09-16 20:42	77.16	OK
9249	2026-09-16 20:43	74.29	OK	9250	2026-09-16 20:44	74.07	OK
9251	2026-09-16 20:45	78.20	OK	9252	2026-09-16 20:46	76.81	OK
9253	2026-09-16 20:47	77.31	OK	9254	2026-09-16 20:48	75.59	OK
9255	2026-09-16 20:49	76.63	OK	9256	2026-09-16 20:50	77.34	OK
9257	2026-09-16 20:51	77.67	OK	9258	2026-09-16 20:52	75.30	OK
9259	2026-09-16 20:53	76.81	OK	9260	2026-09-16 20:54	78.18	OK
9261	2026-09-16 20:55	77.13	OK	9262	2026-09-16 20:56	76.31	OK
9263	2026-09-16 20:57	75.47	OK	9264	2026-09-16 20:58	74.08	OK
9265	2026-09-16 20:59	74.16	OK	9266	2026-09-16 21:00	75.56	OK
9267	2026-09-16 21:01	76.64	OK	9268	2026-09-16 21:02	74.47	OK
9269	2026-09-16 21:03	77.41	OK	9270	2026-09-16 21:04	76.02	OK
9271	2026-09-16 21:05	75.94	OK	9272	2026-09-16 21:06	77.04	OK
9273	2026-09-16 21:07	77.81	OK	9274	2026-09-16 21:08	78.41	OK
9275	2026-09-16 21:09	76.53	OK	9276	2026-09-16 21:10	74.23	OK
9277	2026-09-16 21:11	76.19	OK	9278	2026-09-16 21:12	76.29	OK
9279	2026-09-16 21:13	77.52	OK	9280	2026-09-16 21:14	77.58	OK
9281	2026-09-16 21:15	78.48	OK	9282	2026-09-16 21:16	76.10	OK
9283	2026-09-16 21:17	74.33	OK	9284	2026-09-16 21:18	74.83	OK
9285	2026-09-16 21:19	78.45	OK	9286	2026-09-16 21:20	76.85	OK
9287	2026-09-16 21:21	76.38	OK	9288	2026-09-16 21:22	78.81	OK
9289	2026-09-16 21:23	75.81	OK	9290	2026-09-16 21:24	78.39	OK
9291	2026-09-16 21:25	78.84	OK	9292	2026-09-16 21:26	79.00	OK
9293	2026-09-16 21:27	76.19	OK	9294	2026-09-16 21:28	78.66	OK
9295	2026-09-16 21:29	79.89	OK	9296	2026-09-16 21:30	78.09	OK
9297	2026-09-16 21:31	75.67	OK	9298	2026-09-16 21:32	78.96	OK
9299	2026-09-16 21:33	77.90	OK	9300	2026-09-16 21:34	79.22	OK
9301	2026-09-16 21:35	79.06	OK	9302	2026-09-16 21:36	79.54	OK
9303	2026-09-16 21:37	76.00	OK	9304	2026-09-16 21:38	76.67	OK
9305	2026-09-16 21:39	76.79	OK	9306	2026-09-16 21:40	78.30	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9307	2026-09-16 21:41	78.99	OK	9308	2026-09-16 21:42	76.65	OK
9309	2026-09-16 21:43	78.58	OK	9310	2026-09-16 21:44	76.11	OK
9311	2026-09-16 21:45	78.37	OK	9312	2026-09-16 21:46	76.99	OK
9313	2026-09-16 21:47	76.84	OK	9314	2026-09-16 21:48	78.25	OK
9315	2026-09-16 21:49	79.16	OK	9316	2026-09-16 21:50	78.00	OK
9317	2026-09-16 21:51	78.04	OK	9318	2026-09-16 21:52	78.24	OK
9319	2026-09-16 21:53	77.01	OK	9320	2026-09-16 21:54	80.28	OK
9321	2026-09-16 21:55	79.03	OK	9322	2026-09-16 21:56	76.15	OK
9323	2026-09-16 21:57	76.35	OK	9324	2026-09-16 21:58	79.78	OK
9325	2026-09-16 21:59	77.20	OK	9326	2026-09-16 22:00	77.20	OK
9327	2026-09-16 22:01	78.27	OK	9328	2026-09-16 22:02	77.39	OK
9329	2026-09-16 22:03	78.98	OK	9330	2026-09-16 22:04	78.62	OK
9331	2026-09-16 22:05	77.84	OK	9332	2026-09-16 22:06	79.44	OK
9333	2026-09-16 22:07	79.52	OK	9334	2026-09-16 22:08	78.49	OK
9335	2026-09-16 22:09	80.01	OK	9336	2026-09-16 22:10	76.34	OK
9337	2026-09-16 22:11	78.40	OK	9338	2026-09-16 22:12	78.53	OK
9339	2026-09-16 22:13	79.87	OK	9340	2026-09-16 22:14	80.03	OK
9341	2026-09-16 22:15	78.01	OK	9342	2026-09-16 22:16	80.04	OK
9343	2026-09-16 22:17	77.19	OK	9344	2026-09-16 22:18	78.09	OK
9345	2026-09-16 22:19	75.48	OK	9346	2026-09-16 22:20	78.68	OK
9347	2026-09-16 22:21	78.55	OK	9348	2026-09-16 22:22	78.07	OK
9349	2026-09-16 22:23	76.28	OK	9350	2026-09-16 22:24	77.60	OK
9351	2026-09-16 22:25	77.10	OK	9352	2026-09-16 22:26	78.88	OK
9353	2026-09-16 22:27	75.74	OK	9354	2026-09-16 22:28	80.98	OK
9355	2026-09-16 22:29	77.15	OK	9356	2026-09-16 22:30	80.19	OK
9357	2026-09-16 22:31	80.51	OK	9358	2026-09-16 22:32	79.32	OK
9359	2026-09-16 22:33	79.06	OK	9360	2026-09-16 22:34	76.89	OK
9361	2026-09-16 22:35	78.65	OK	9362	2026-09-16 22:36	79.79	OK
9363	2026-09-16 22:37	78.26	OK	9364	2026-09-16 22:38	80.25	OK
9365	2026-09-16 22:39	79.94	OK	9366	2026-09-16 22:40	76.54	OK
9367	2026-09-16 22:41	81.55	OK	9368	2026-09-16 22:42	80.35	OK
9369	2026-09-16 22:43	78.88	OK	9370	2026-09-16 22:44	78.54	OK
9371	2026-09-16 22:45	78.69	OK	9372	2026-09-16 22:46	78.60	OK
9373	2026-09-16 22:47	78.94	OK	9374	2026-09-16 22:48	79.98	OK
9375	2026-09-16 22:49	81.19	OK	9376	2026-09-16 22:50	81.37	OK
9377	2026-09-16 22:51	77.95	OK	9378	2026-09-16 22:52	77.87	OK
9379	2026-09-16 22:53	81.47	OK	9380	2026-09-16 22:54	78.30	OK
9381	2026-09-16 22:55	76.90	OK	9382	2026-09-16 22:56	78.29	OK
9383	2026-09-16 22:57	80.76	OK	9384	2026-09-16 22:58	82.12	OK
9385	2026-09-16 22:59	81.19	OK	9386	2026-09-16 23:00	78.61	OK
9387	2026-09-16 23:01	79.73	OK	9388	2026-09-16 23:02	81.49	OK
9389	2026-09-16 23:03	79.31	OK	9390	2026-09-16 23:04	77.07	OK
9391	2026-09-16 23:05	77.99	OK	9392	2026-09-16 23:06	79.11	OK
9393	2026-09-16 23:07	80.44	OK	9394	2026-09-16 23:08	78.15	OK
9395	2026-09-16 23:09	81.73	OK	9396	2026-09-16 23:10	78.15	OK
9397	2026-09-16 23:11	81.91	OK	9398	2026-09-16 23:12	80.20	OK
9399	2026-09-16 23:13	82.22	OK	9400	2026-09-16 23:14	78.50	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9401	2026-09-16 23:15	79.24	OK	9402	2026-09-16 23:16	80.13	OK
9403	2026-09-16 23:17	81.59	OK	9404	2026-09-16 23:18	80.56	OK
9405	2026-09-16 23:19	82.44	OK	9406	2026-09-16 23:20	79.09	OK
9407	2026-09-16 23:21	80.21	OK	9408	2026-09-16 23:22	77.59	OK
9409	2026-09-16 23:23	77.89	OK	9410	2026-09-16 23:24	78.48	OK
9411	2026-09-16 23:25	79.35	OK	9412	2026-09-16 23:26	78.92	OK
9413	2026-09-16 23:27	78.99	OK	9414	2026-09-16 23:28	78.95	OK
9415	2026-09-16 23:29	81.12	OK	9416	2026-09-16 23:30	79.79	OK
9417	2026-09-16 23:31	81.73	OK	9418	2026-09-16 23:32	79.38	OK
9419	2026-09-16 23:33	80.75	OK	9420	2026-09-16 23:34	82.02	OK
9421	2026-09-16 23:35	81.16	OK	9422	2026-09-16 23:36	78.67	OK
9423	2026-09-16 23:37	80.97	OK	9424	2026-09-16 23:38	79.34	OK
9425	2026-09-16 23:39	78.21	OK	9426	2026-09-16 23:40	80.07	OK
9427	2026-09-16 23:41	79.20	OK	9428	2026-09-16 23:42	79.96	OK
9429	2026-09-16 23:43	80.52	OK	9430	2026-09-16 23:44	81.32	OK
9431	2026-09-16 23:45	80.09	OK	9432	2026-09-16 23:46	81.10	OK
9433	2026-09-16 23:47	79.93	OK	9434	2026-09-16 23:48	79.64	OK
9435	2026-09-16 23:49	80.88	OK	9436	2026-09-16 23:50	81.34	OK
9437	2026-09-16 23:51	79.74	OK	9438	2026-09-16 23:52	80.20	OK
9439	2026-09-16 23:53	79.93	OK	9440	2026-09-16 23:54	80.13	OK
9441	2026-09-16 23:55	79.49	OK	9442	2026-09-16 23:56	83.56	OK
9443	2026-09-16 23:57	82.23	OK	9444	2026-09-16 23:58	81.24	OK
9445	2026-09-16 23:59	81.75	OK	9446	2026-09-17 00:00	80.78	OK
9447	2026-09-17 00:01	82.43	OK	9448	2026-09-17 00:02	80.40	OK
9449	2026-09-17 00:03	79.32	OK	9450	2026-09-17 00:04	79.96	OK
9451	2026-09-17 00:05	78.88	OK	9452	2026-09-17 00:06	79.57	OK
9453	2026-09-17 00:07	79.28	OK	9454	2026-09-17 00:08	79.60	OK
9455	2026-09-17 00:09	79.98	OK	9456	2026-09-17 00:10	79.90	OK
9457	2026-09-17 00:11	80.25	OK	9458	2026-09-17 00:12	80.19	OK
9459	2026-09-17 00:13	80.19	OK	9460	2026-09-17 00:14	80.16	OK
9461	2026-09-17 00:15	78.85	OK	9462	2026-09-17 00:16	79.00	OK
9463	2026-09-17 00:17	79.68	OK	9464	2026-09-17 00:18	79.63	OK
9465	2026-09-17 00:19	80.17	OK	9466	2026-09-17 00:20	81.08	OK
9467	2026-09-17 00:21	81.92	OK	9468	2026-09-17 00:22	79.01	OK
9469	2026-09-17 00:23	79.57	OK	9470	2026-09-17 00:24	80.90	OK
9471	2026-09-17 00:25	82.00	OK	9472	2026-09-17 00:26	81.32	OK
9473	2026-09-17 00:27	81.07	OK	9474	2026-09-17 00:28	81.95	OK
9475	2026-09-17 00:29	81.57	OK	9476	2026-09-17 00:30	82.62	OK
9477	2026-09-17 00:31	79.99	OK	9478	2026-09-17 00:32	81.90	OK
9479	2026-09-17 00:33	82.14	OK	9480	2026-09-17 00:34	78.55	OK
9481	2026-09-17 00:35	79.02	OK	9482	2026-09-17 00:36	81.28	OK
9483	2026-09-17 00:37	80.12	OK	9484	2026-09-17 00:38	80.66	OK
9485	2026-09-17 00:39	78.08	OK	9486	2026-09-17 00:40	83.35	OK
9487	2026-09-17 00:41	81.65	OK	9488	2026-09-17 00:42	80.85	OK
9489	2026-09-17 00:43	79.51	OK	9490	2026-09-17 00:44	78.99	OK
9491	2026-09-17 00:45	81.76	OK	9492	2026-09-17 00:46	80.38	OK
9493	2026-09-17 00:47	82.37	OK	9494	2026-09-17 00:48	80.61	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9495	2026-09-17 00:49	83.36	OK	9496	2026-09-17 00:50	81.38	OK
9497	2026-09-17 00:51	80.17	OK	9498	2026-09-17 00:52	81.48	OK
9499	2026-09-17 00:53	81.63	OK	9500	2026-09-17 00:54	81.96	OK
9501	2026-09-17 00:55	83.71	OK	9502	2026-09-17 00:56	78.80	OK
9503	2026-09-17 00:57	82.46	OK	9504	2026-09-17 00:58	78.49	OK
9505	2026-09-17 00:59	80.79	OK	9506	2026-09-17 01:00	81.43	OK
9507	2026-09-17 01:01	80.05	OK	9508	2026-09-17 01:02	82.35	OK
9509	2026-09-17 01:03	79.74	OK	9510	2026-09-17 01:04	79.10	OK
9511	2026-09-17 01:05	82.52	OK	9512	2026-09-17 01:06	80.96	OK
9513	2026-09-17 01:07	80.77	OK	9514	2026-09-17 01:08	81.46	OK
9515	2026-09-17 01:09	79.73	OK	9516	2026-09-17 01:10	83.12	OK
9517	2026-09-17 01:11	81.83	OK	9518	2026-09-17 01:12	79.36	OK
9519	2026-09-17 01:13	81.15	OK	9520	2026-09-17 01:14	81.52	OK
9521	2026-09-17 01:15	81.12	OK	9522	2026-09-17 01:16	81.63	OK
9523	2026-09-17 01:17	80.32	OK	9524	2026-09-17 01:18	81.15	OK
9525	2026-09-17 01:19	81.92	OK	9526	2026-09-17 01:20	79.24	OK
9527	2026-09-17 01:21	83.07	OK	9528	2026-09-17 01:22	84.40	OK
9529	2026-09-17 01:23	83.04	OK	9530	2026-09-17 01:24	80.81	OK
9531	2026-09-17 01:25	79.98	OK	9532	2026-09-17 01:26	82.31	OK
9533	2026-09-17 01:27	79.83	OK	9534	2026-09-17 01:28	82.33	OK
9535	2026-09-17 01:29	82.66	OK	9536	2026-09-17 01:30	79.90	OK
9537	2026-09-17 01:31	81.51	OK	9538	2026-09-17 01:32	83.89	OK
9539	2026-09-17 01:33	81.43	OK	9540	2026-09-17 01:34	80.22	OK
9541	2026-09-17 01:35	81.69	OK	9542	2026-09-17 01:36	81.42	OK
9543	2026-09-17 01:37	80.89	OK	9544	2026-09-17 01:38	81.34	OK
9545	2026-09-17 01:39	82.65	OK	9546	2026-09-17 01:40	80.53	OK
9547	2026-09-17 01:41	80.33	OK	9548	2026-09-17 01:42	81.23	OK
9549	2026-09-17 01:43	80.94	OK	9550	2026-09-17 01:44	79.95	OK
9551	2026-09-17 01:45	80.15	OK	9552	2026-09-17 01:46	81.74	OK
9553	2026-09-17 01:47	82.51	OK	9554	2026-09-17 01:48	81.21	OK
9555	2026-09-17 01:49	81.10	OK	9556	2026-09-17 01:50	83.38	OK
9557	2026-09-17 01:51	81.74	OK	9558	2026-09-17 01:52	81.96	OK
9559	2026-09-17 01:53	82.43	OK	9560	2026-09-17 01:54	81.52	OK
9561	2026-09-17 01:55	81.95	OK	9562	2026-09-17 01:56	81.89	OK
9563	2026-09-17 01:57	82.90	OK	9564	2026-09-17 01:58	82.46	OK
9565	2026-09-17 01:59	79.25	OK	9566	2026-09-17 02:00	81.07	OK
9567	2026-09-17 02:01	80.40	OK	9568	2026-09-17 02:02	81.47	OK
9569	2026-09-17 02:03	82.61	OK	9570	2026-09-17 02:04	80.52	OK
9571	2026-09-17 02:05	79.82	OK	9572	2026-09-17 02:06	80.66	OK
9573	2026-09-17 02:07	83.85	OK	9574	2026-09-17 02:08	82.59	OK
9575	2026-09-17 02:09	80.87	OK	9576	2026-09-17 02:10	81.26	OK
9577	2026-09-17 02:11	82.39	OK	9578	2026-09-17 02:12	81.66	OK
9579	2026-09-17 02:13	80.64	OK	9580	2026-09-17 02:14	81.57	OK
9581	2026-09-17 02:15	81.00	OK	9582	2026-09-17 02:16	81.03	OK
9583	2026-09-17 02:17	82.71	OK	9584	2026-09-17 02:18	79.60	OK
9585	2026-09-17 02:19	81.69	OK	9586	2026-09-17 02:20	82.19	OK
9587	2026-09-17 02:21	81.14	OK	9588	2026-09-17 02:22	81.35	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9589	2026-09-17 02:23	81.62	OK	9590	2026-09-17 02:24	82.48	OK
9591	2026-09-17 02:25	81.46	OK	9592	2026-09-17 02:26	81.48	OK
9593	2026-09-17 02:27	82.18	OK	9594	2026-09-17 02:28	81.61	OK
9595	2026-09-17 02:29	83.47	OK	9596	2026-09-17 02:30	81.32	OK
9597	2026-09-17 02:31	81.03	OK	9598	2026-09-17 02:32	81.60	OK
9599	2026-09-17 02:33	81.19	OK	9600	2026-09-17 02:34	81.32	OK
9601	2026-09-17 02:35	82.05	OK	9602	2026-09-17 02:36	82.78	OK
9603	2026-09-17 02:37	79.44	OK	9604	2026-09-17 02:38	80.65	OK
9605	2026-09-17 02:39	83.24	OK	9606	2026-09-17 02:40	83.08	OK
9607	2026-09-17 02:41	80.88	OK	9608	2026-09-17 02:42	82.14	OK
9609	2026-09-17 02:43	82.06	OK	9610	2026-09-17 02:44	83.15	OK
9611	2026-09-17 02:45	82.44	OK	9612	2026-09-17 02:46	79.19	OK
9613	2026-09-17 02:47	84.28	OK	9614	2026-09-17 02:48	80.52	OK
9615	2026-09-17 02:49	81.44	OK	9616	2026-09-17 02:50	80.34	OK
9617	2026-09-17 02:51	80.83	OK	9618	2026-09-17 02:52	80.66	OK
9619	2026-09-17 02:53	79.41	OK	9620	2026-09-17 02:54	81.26	OK
9621	2026-09-17 02:55	83.52	OK	9622	2026-09-17 02:56	82.08	OK
9623	2026-09-17 02:57	81.87	OK	9624	2026-09-17 02:58	80.89	OK
9625	2026-09-17 02:59	80.75	OK	9626	2026-09-17 03:00	81.89	OK
9627	2026-09-17 03:01	82.14	OK	9628	2026-09-17 03:02	80.24	OK
9629	2026-09-17 03:03	81.58	OK	9630	2026-09-17 03:04	81.31	OK
9631	2026-09-17 03:05	81.86	OK	9632	2026-09-17 03:06	81.61	OK
9633	2026-09-17 03:07	80.76	OK	9634	2026-09-17 03:08	80.86	OK
9635	2026-09-17 03:09	81.05	OK	9636	2026-09-17 03:10	81.93	OK
9637	2026-09-17 03:11	82.56	OK	9638	2026-09-17 03:12	81.84	OK
9639	2026-09-17 03:13	81.22	OK	9640	2026-09-17 03:14	83.10	OK
9641	2026-09-17 03:15	80.09	OK	9642	2026-09-17 03:16	81.64	OK
9643	2026-09-17 03:17	81.15	OK	9644	2026-09-17 03:18	79.89	OK
9645	2026-09-17 03:19	80.78	OK	9646	2026-09-17 03:20	82.71	OK
9647	2026-09-17 03:21	83.92	OK	9648	2026-09-17 03:22	81.29	OK
9649	2026-09-17 03:23	84.05	OK	9650	2026-09-17 03:24	83.44	OK
9651	2026-09-17 03:25	81.92	OK	9652	2026-09-17 03:26	79.68	OK
9653	2026-09-17 03:27	82.65	OK	9654	2026-09-17 03:28	80.41	OK
9655	2026-09-17 03:29	81.10	OK	9656	2026-09-17 03:30	80.81	OK
9657	2026-09-17 03:31	81.59	OK	9658	2026-09-17 03:32	79.83	OK
9659	2026-09-17 03:33	83.40	OK	9660	2026-09-17 03:34	80.35	OK
9661	2026-09-17 03:35	80.41	OK	9662	2026-09-17 03:36	82.23	OK
9663	2026-09-17 03:37	81.61	OK	9664	2026-09-17 03:38	81.78	OK
9665	2026-09-17 03:39	81.52	OK	9666	2026-09-17 03:40	82.38	OK
9667	2026-09-17 03:41	82.65	OK	9668	2026-09-17 03:42	81.85	OK
9669	2026-09-17 03:43	80.09	OK	9670	2026-09-17 03:44	81.29	OK
9671	2026-09-17 03:45	83.91	OK	9672	2026-09-17 03:46	79.88	OK
9673	2026-09-17 03:47	82.13	OK	9674	2026-09-17 03:48	81.23	OK
9675	2026-09-17 03:49	80.93	OK	9676	2026-09-17 03:50	80.05	OK
9677	2026-09-17 03:51	81.52	OK	9678	2026-09-17 03:52	82.78	OK
9679	2026-09-17 03:53	82.71	OK	9680	2026-09-17 03:54	81.66	OK
9681	2026-09-17 03:55	79.40	OK	9682	2026-09-17 03:56	83.98	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9683	2026-09-17 03:57	83.87	OK	9684	2026-09-17 03:58	83.84	OK
9685	2026-09-17 03:59	80.05	OK	9686	2026-09-17 04:00	81.21	OK
9687	2026-09-17 04:01	81.92	OK	9688	2026-09-17 04:02	82.60	OK
9689	2026-09-17 04:03	81.53	OK	9690	2026-09-17 04:04	83.05	OK
9691	2026-09-17 04:05	79.66	OK	9692	2026-09-17 04:06	80.01	OK
9693	2026-09-17 04:07	82.55	OK	9694	2026-09-17 04:08	82.20	OK
9695	2026-09-17 04:09	80.00	OK	9696	2026-09-17 04:10	81.39	OK
9697	2026-09-17 04:11	81.10	OK	9698	2026-09-17 04:12	81.39	OK
9699	2026-09-17 04:13	82.66	OK	9700	2026-09-17 04:14	82.10	OK
9701	2026-09-17 04:15	80.75	OK	9702	2026-09-17 04:16	80.41	OK
9703	2026-09-17 04:17	81.04	OK	9704	2026-09-17 04:18	82.47	OK
9705	2026-09-17 04:19	80.72	OK	9706	2026-09-17 04:20	81.60	OK
9707	2026-09-17 04:21	80.44	OK	9708	2026-09-17 04:22	83.45	OK
9709	2026-09-17 04:23	82.87	OK	9710	2026-09-17 04:24	83.31	OK
9711	2026-09-17 04:25	82.36	OK	9712	2026-09-17 04:26	80.53	OK
9713	2026-09-17 04:27	80.67	OK	9714	2026-09-17 04:28	82.43	OK
9715	2026-09-17 04:29	80.59	OK	9716	2026-09-17 04:30	82.32	OK
9717	2026-09-17 04:31	82.03	OK	9718	2026-09-17 04:32	82.64	OK
9719	2026-09-17 04:33	81.03	OK	9720	2026-09-17 04:34	81.14	OK
9721	2026-09-17 04:35	82.67	OK	9722	2026-09-17 04:36	81.43	OK
9723	2026-09-17 04:37	82.85	OK	9724	2026-09-17 04:38	82.97	OK
9725	2026-09-17 04:39	82.17	OK	9726	2026-09-17 04:40	80.87	OK
9727	2026-09-17 04:41	81.37	OK	9728	2026-09-17 04:42	80.94	OK
9729	2026-09-17 04:43	82.00	OK	9730	2026-09-17 04:44	80.66	OK
9731	2026-09-17 04:45	79.33	OK	9732	2026-09-17 04:46	81.77	OK
9733	2026-09-17 04:47	80.20	OK	9734	2026-09-17 04:48	82.97	OK
9735	2026-09-17 04:49	79.20	OK	9736	2026-09-17 04:50	81.76	OK
9737	2026-09-17 04:51	82.24	OK	9738	2026-09-17 04:52	79.64	OK
9739	2026-09-17 04:53	80.47	OK	9740	2026-09-17 04:54	79.55	OK
9741	2026-09-17 04:55	79.73	OK	9742	2026-09-17 04:56	79.98	OK
9743	2026-09-17 04:57	80.49	OK	9744	2026-09-17 04:58	82.00	OK
9745	2026-09-17 04:59	81.85	OK	9746	2026-09-17 05:00	81.75	OK
9747	2026-09-17 05:01	80.99	OK	9748	2026-09-17 05:02	80.93	OK
9749	2026-09-17 05:03	78.35	OK	9750	2026-09-17 05:04	80.89	OK
9751	2026-09-17 05:05	78.75	OK	9752	2026-09-17 05:06	82.25	OK
9753	2026-09-17 05:07	78.80	OK	9754	2026-09-17 05:08	79.10	OK
9755	2026-09-17 05:09	81.25	OK	9756	2026-09-17 05:10	81.60	OK
9757	2026-09-17 05:11	81.00	OK	9758	2026-09-17 05:12	82.43	OK
9759	2026-09-17 05:13	80.52	OK	9760	2026-09-17 05:14	80.22	OK
9761	2026-09-17 05:15	82.20	OK	9762	2026-09-17 05:16	78.55	OK
9763	2026-09-17 05:17	82.00	OK	9764	2026-09-17 05:18	83.36	OK
9765	2026-09-17 05:19	82.01	OK	9766	2026-09-17 05:20	81.50	OK
9767	2026-09-17 05:21	78.34	OK	9768	2026-09-17 05:22	80.55	OK
9769	2026-09-17 05:23	79.82	OK	9770	2026-09-17 05:24	80.99	OK
9771	2026-09-17 05:25	81.40	OK	9772	2026-09-17 05:26	78.27	OK
9773	2026-09-17 05:27	82.42	OK	9774	2026-09-17 05:28	80.87	OK
9775	2026-09-17 05:29	82.29	OK	9776	2026-09-17 05:30	82.71	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9777	2026-09-17 05:31	79.17	OK	9778	2026-09-17 05:32	81.11	OK
9779	2026-09-17 05:33	82.48	OK	9780	2026-09-17 05:34	80.56	OK
9781	2026-09-17 05:35	80.75	OK	9782	2026-09-17 05:36	79.58	OK
9783	2026-09-17 05:37	77.78	OK	9784	2026-09-17 05:38	81.03	OK
9785	2026-09-17 05:39	81.59	OK	9786	2026-09-17 05:40	79.02	OK
9787	2026-09-17 05:41	81.76	OK	9788	2026-09-17 05:42	82.11	OK
9789	2026-09-17 05:43	80.92	OK	9790	2026-09-17 05:44	82.24	OK
9791	2026-09-17 05:45	81.42	OK	9792	2026-09-17 05:46	82.56	OK
9793	2026-09-17 05:47	80.58	OK	9794	2026-09-17 05:48	79.35	OK
9795	2026-09-17 05:49	79.11	OK	9796	2026-09-17 05:50	80.33	OK
9797	2026-09-17 05:51	83.19	OK	9798	2026-09-17 05:52	79.43	OK
9799	2026-09-17 05:53	80.83	OK	9800	2026-09-17 05:54	80.97	OK
9801	2026-09-17 05:55	80.68	OK	9802	2026-09-17 05:56	82.30	OK
9803	2026-09-17 05:57	82.51	OK	9804	2026-09-17 05:58	79.73	OK
9805	2026-09-17 05:59	78.48	OK	9806	2026-09-17 06:00	82.00	OK
9807	2026-09-17 06:01	79.88	OK	9808	2026-09-17 06:02	80.21	OK
9809	2026-09-17 06:03	81.23	OK	9810	2026-09-17 06:04	82.94	OK
9811	2026-09-17 06:05	76.86	OK	9812	2026-09-17 06:06	78.09	OK
9813	2026-09-17 06:07	81.48	OK	9814	2026-09-17 06:08	81.18	OK
9815	2026-09-17 06:09	81.39	OK	9816	2026-09-17 06:10	80.63	OK
9817	2026-09-17 06:11	78.57	OK	9818	2026-09-17 06:12	81.10	OK
9819	2026-09-17 06:13	78.86	OK	9820	2026-09-17 06:14	78.46	OK
9821	2026-09-17 06:15	79.54	OK	9822	2026-09-17 06:16	83.36	OK
9823	2026-09-17 06:17	78.81	OK	9824	2026-09-17 06:18	78.98	OK
9825	2026-09-17 06:19	79.28	OK	9826	2026-09-17 06:20	80.97	OK
9827	2026-09-17 06:21	81.78	OK	9828	2026-09-17 06:22	81.98	OK
9829	2026-09-17 06:23	79.78	OK	9830	2026-09-17 06:24	80.09	OK
9831	2026-09-17 06:25	78.40	OK	9832	2026-09-17 06:26	79.14	OK
9833	2026-09-17 06:27	78.92	OK	9834	2026-09-17 06:28	80.45	OK
9835	2026-09-17 06:29	77.92	OK	9836	2026-09-17 06:30	79.45	OK
9837	2026-09-17 06:31	80.28	OK	9838	2026-09-17 06:32	79.42	OK
9839	2026-09-17 06:33	80.52	OK	9840	2026-09-17 06:34	80.93	OK
9841	2026-09-17 06:35	79.52	OK	9842	2026-09-17 06:36	80.60	OK
9843	2026-09-17 06:37	79.14	OK	9844	2026-09-17 06:38	78.52	OK
9845	2026-09-17 06:39	80.58	OK	9846	2026-09-17 06:40	79.49	OK
9847	2026-09-17 06:41	78.49	OK	9848	2026-09-17 06:42	77.86	OK
9849	2026-09-17 06:43	79.90	OK	9850	2026-09-17 06:44	79.79	OK
9851	2026-09-17 06:45	79.90	OK	9852	2026-09-17 06:46	81.14	OK
9853	2026-09-17 06:47	80.10	OK	9854	2026-09-17 06:48	81.14	OK
9855	2026-09-17 06:49	80.41	OK	9856	2026-09-17 06:50	79.04	OK
9857	2026-09-17 06:51	80.89	OK	9858	2026-09-17 06:52	80.95	OK
9859	2026-09-17 06:53	81.26	OK	9860	2026-09-17 06:54	78.39	OK
9861	2026-09-17 06:55	78.73	OK	9862	2026-09-17 06:56	78.42	OK
9863	2026-09-17 06:57	80.18	OK	9864	2026-09-17 06:58	80.26	OK
9865	2026-09-17 06:59	79.03	OK	9866	2026-09-17 07:00	78.06	OK
9867	2026-09-17 07:01	79.17	OK	9868	2026-09-17 07:02	80.51	OK
9869	2026-09-17 07:03	81.15	OK	9870	2026-09-17 07:04	80.54	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9871	2026-09-17 07:05	77.30	OK	9872	2026-09-17 07:06	76.83	OK
9873	2026-09-17 07:07	78.45	OK	9874	2026-09-17 07:08	78.66	OK
9875	2026-09-17 07:09	77.02	OK	9876	2026-09-17 07:10	80.83	OK
9877	2026-09-17 07:11	79.48	OK	9878	2026-09-17 07:12	79.32	OK
9879	2026-09-17 07:13	80.06	OK	9880	2026-09-17 07:14	79.68	OK
9881	2026-09-17 07:15	79.65	OK	9882	2026-09-17 07:16	78.31	OK
9883	2026-09-17 07:17	77.97	OK	9884	2026-09-17 07:18	79.76	OK
9885	2026-09-17 07:19	77.53	OK	9886	2026-09-17 07:20	77.32	OK
9887	2026-09-17 07:21	78.52	OK	9888	2026-09-17 07:22	77.83	OK
9889	2026-09-17 07:23	76.77	OK	9890	2026-09-17 07:24	77.72	OK
9891	2026-09-17 07:25	77.99	OK	9892	2026-09-17 07:26	78.22	OK
9893	2026-09-17 07:27	78.19	OK	9894	2026-09-17 07:28	75.54	OK
9895	2026-09-17 07:29	76.81	OK	9896	2026-09-17 07:30	80.62	OK
9897	2026-09-17 07:31	76.73	OK	9898	2026-09-17 07:32	80.33	OK
9899	2026-09-17 07:33	77.62	OK	9900	2026-09-17 07:34	79.66	OK
9901	2026-09-17 07:35	79.30	OK	9902	2026-09-17 07:36	77.65	OK
9903	2026-09-17 07:37	80.05	OK	9904	2026-09-17 07:38	77.01	OK
9905	2026-09-17 07:39	80.60	OK	9906	2026-09-17 07:40	77.59	OK
9907	2026-09-17 07:41	76.83	OK	9908	2026-09-17 07:42	77.21	OK
9909	2026-09-17 07:43	77.43	OK	9910	2026-09-17 07:44	79.32	OK
9911	2026-09-17 07:45	76.84	OK	9912	2026-09-17 07:46	79.37	OK
9913	2026-09-17 07:47	75.45	OK	9914	2026-09-17 07:48	78.14	OK
9915	2026-09-17 07:49	78.47	OK	9916	2026-09-17 07:50	79.53	OK
9917	2026-09-17 07:51	77.73	OK	9918	2026-09-17 07:52	78.64	OK
9919	2026-09-17 07:53	77.60	OK	9920	2026-09-17 07:54	79.99	OK
9921	2026-09-17 07:55	77.21	OK	9922	2026-09-17 07:56	78.87	OK
9923	2026-09-17 07:57	80.11	OK	9924	2026-09-17 07:58	78.53	OK
9925	2026-09-17 07:59	76.20	OK	9926	2026-09-17 08:00	77.80	OK
9927	2026-09-17 08:01	75.31	OK	9928	2026-09-17 08:02	78.10	OK
9929	2026-09-17 08:03	78.70	OK	9930	2026-09-17 08:04	76.80	OK
9931	2026-09-17 08:05	78.13	OK	9932	2026-09-17 08:06	75.43	OK
9933	2026-09-17 08:07	77.40	OK	9934	2026-09-17 08:08	79.24	OK
9935	2026-09-17 08:09	77.47	OK	9936	2026-09-17 08:10	75.35	OK
9937	2026-09-17 08:11	78.72	OK	9938	2026-09-17 08:12	75.00	OK
9939	2026-09-17 08:13	75.33	OK	9940	2026-09-17 08:14	76.36	OK
9941	2026-09-17 08:15	75.69	OK	9942	2026-09-17 08:16	77.74	OK
9943	2026-09-17 08:17	77.34	OK	9944	2026-09-17 08:18	77.43	OK
9945	2026-09-17 08:19	78.46	OK	9946	2026-09-17 08:20	78.87	OK
9947	2026-09-17 08:21	78.06	OK	9948	2026-09-17 08:22	76.99	OK
9949	2026-09-17 08:23	77.24	OK	9950	2026-09-17 08:24	77.27	OK
9951	2026-09-17 08:25	74.63	OK	9952	2026-09-17 08:26	75.97	OK
9953	2026-09-17 08:27	76.25	OK	9954	2026-09-17 08:28	78.26	OK
9955	2026-09-17 08:29	76.95	OK	9956	2026-09-17 08:30	74.33	OK
9957	2026-09-17 08:31	76.95	OK	9958	2026-09-17 08:32	76.95	OK
9959	2026-09-17 08:33	76.53	OK	9960	2026-09-17 08:34	78.50	OK
9961	2026-09-17 08:35	76.21	OK	9962	2026-09-17 08:36	75.77	OK
9963	2026-09-17 08:37	73.50	OK	9964	2026-09-17 08:38	77.86	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9965	2026-09-17 08:39	78.62	OK	9966	2026-09-17 08:40	75.80	OK
9967	2026-09-17 08:41	78.55	OK	9968	2026-09-17 08:42	77.41	OK
9969	2026-09-17 08:43	75.58	OK	9970	2026-09-17 08:44	77.52	OK
9971	2026-09-17 08:45	74.48	OK	9972	2026-09-17 08:46	76.30	OK
9973	2026-09-17 08:47	78.30	OK	9974	2026-09-17 08:48	74.55	OK
9975	2026-09-17 08:49	76.93	OK	9976	2026-09-17 08:50	74.23	OK
9977	2026-09-17 08:51	75.92	OK	9978	2026-09-17 08:52	77.04	OK
9979	2026-09-17 08:53	78.20	OK	9980	2026-09-17 08:54	75.47	OK
9981	2026-09-17 08:55	73.57	OK	9982	2026-09-17 08:56	77.03	OK
9983	2026-09-17 08:57	75.05	OK	9984	2026-09-17 08:58	78.11	OK
9985	2026-09-17 08:59	77.80	OK	9986	2026-09-17 09:00	75.43	OK
9987	2026-09-17 09:01	77.13	OK	9988	2026-09-17 09:02	75.95	OK
9989	2026-09-17 09:03	78.45	OK	9990	2026-09-17 09:04	77.85	OK
9991	2026-09-17 09:05	77.44	OK	9992	2026-09-17 09:06	76.39	OK
9993	2026-09-17 09:07	75.70	OK	9994	2026-09-17 09:08	76.93	OK
9995	2026-09-17 09:09	75.98	OK	9996	2026-09-17 09:10	75.88	OK
9997	2026-09-17 09:11	77.65	OK	9998	2026-09-17 09:12	76.14	OK
9999	2026-09-17 09:13	74.65	OK	10000	2026-09-17 09:14	76.42	OK
10001	2026-09-17 09:15	74.81	OK	10002	2026-09-17 09:16	75.92	OK
10003	2026-09-17 09:17	75.17	OK	10004	2026-09-17 09:18	74.90	OK
10005	2026-09-17 09:19	74.19	OK	10006	2026-09-17 09:20	76.20	OK
10007	2026-09-17 09:21	75.71	OK	10008	2026-09-17 09:22	76.12	OK
10009	2026-09-17 09:23	75.76	OK	10010	2026-09-17 09:24	74.60	OK
10011	2026-09-17 09:25	78.49	OK	10012	2026-09-17 09:26	75.59	OK
10013	2026-09-17 09:27	77.09	OK	10014	2026-09-17 09:28	73.86	OK
10015	2026-09-17 09:29	76.56	OK	10016	2026-09-17 09:30	74.58	OK
10017	2026-09-17 09:31	75.89	OK	10018	2026-09-17 09:32	73.69	OK
10019	2026-09-17 09:33	76.01	OK	10020	2026-09-17 09:34	76.50	OK
10021	2026-09-17 09:35	76.22	OK	10022	2026-09-17 09:36	75.02	OK
10023	2026-09-17 09:37	76.22	OK	10024	2026-09-17 09:38	73.70	OK
10025	2026-09-17 09:39	74.43	OK	10026	2026-09-17 09:40	76.48	OK
10027	2026-09-17 09:41	77.17	OK	10028	2026-09-17 09:42	74.50	OK
10029	2026-09-17 09:43	73.47	OK	10030	2026-09-17 09:44	77.14	OK
10031	2026-09-17 09:45	77.84	OK	10032	2026-09-17 09:46	76.99	OK
10033	2026-09-17 09:47	74.74	OK	10034	2026-09-17 09:48	76.81	OK
10035	2026-09-17 09:49	75.36	OK	10036	2026-09-17 09:50	74.60	OK
1003	2026-09-17 09:51	74.29	OK	1003	2026-09-17 09:52	74.18	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
10039	2026-09-17 09:53	74.51	OK	10040	2026-09-17 09:54	74.90	OK
10041	2026-09-17 09:55	72.77	OK	10042	2026-09-17 09:56	74.94	OK
10043	2026-09-17 09:57	73.07	OK	10044	2026-09-17 09:58	76.64	OK
10045	2026-09-17 09:59	73.50	OK	10046	2026-09-17 10:00	75.40	OK
10047	2026-09-17 10:01	73.32	OK	10048	2026-09-17 10:02	75.61	OK
10049	2026-09-17 10:03	74.76	OK	10050	2026-09-17 10:04	75.28	OK
10051	2026-09-17 10:05	76.67	OK	10052	2026-09-17 10:06	77.05	OK
10053	2026-09-17 10:07	74.14	OK	10054	2026-09-17 10:08	75.86	OK
10055	2026-09-17 10:09	74.51	OK	10056	2026-09-17 10:10	73.48	OK
10057	2026-09-17 10:11	74.86	OK	10058	2026-09-17 10:12	75.06	OK
10059	2026-09-17 10:13	75.33	OK	10060	2026-09-17 10:14	74.01	OK
10061	2026-09-17 10:15	74.77	OK	10062	2026-09-17 10:16	75.99	OK
10063	2026-09-17 10:17	71.80	OK	10064	2026-09-17 10:18	73.47	OK
10065	2026-09-17 10:19	75.38	OK	10066	2026-09-17 10:20	72.86	OK
10067	2026-09-17 10:21	72.20	OK	10068	2026-09-17 10:22	74.17	OK
10069	2026-09-17 10:23	73.26	OK	10070	2026-09-17 10:24	74.63	OK
10071	2026-09-17 10:25	75.12	OK	10072	2026-09-17 10:26	75.39	OK
10073	2026-09-17 10:27	74.64	OK	10074	2026-09-17 10:28	76.05	OK
10075	2026-09-17 10:29	75.89	OK	10076	2026-09-17 10:30	75.86	OK
10077	2026-09-17 10:31	74.18	OK	10078	2026-09-17 10:32	75.12	OK
10079	2026-09-17 10:33	74.23	OK	10080	2026-09-17 10:34	76.29	OK
10081	2026-09-17 10:35	73.19	OK	10082	2026-09-17 10:36	75.26	OK
10083	2026-09-17 10:37	74.69	OK	10084	2026-09-17 10:38	75.12	OK
10085	2026-09-17 10:39	75.08	OK	10086	2026-09-17 10:40	74.66	OK
10087	2026-09-17 10:41	73.82	OK	10088	2026-09-17 10:42	74.35	OK
10089	2026-09-17 10:43	75.60	OK	10090	2026-09-17 10:44	73.16	OK
10091	2026-09-17 10:45	74.49	OK	10092	2026-09-17 10:46	74.48	OK
10093	2026-09-17 10:47	72.95	OK	10094	2026-09-17 10:48	74.53	OK
10095	2026-09-17 10:49	75.08	OK	10096	2026-09-17 10:50	73.97	OK
1009	2026-09-17 10:51	73.45	OK	1009	2026-09-17 10:52	75.01	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
10099	2026-09-17 10:53	74.42	OK	10100	2026-09-17 10:54	73.70	OK
10101	2026-09-17 10:55	75.86	OK	10102	2026-09-17 10:56	72.44	OK
10103	2026-09-17 10:57	73.22	OK	10104	2026-09-17 10:58	73.53	OK
10105	2026-09-17 10:59	71.99	OK	10106	2026-09-17 11:00	76.46	OK
10107	2026-09-17 11:01	73.92	OK	10108	2026-09-17 11:02	74.42	OK
10109	2026-09-17 11:03	73.95	OK	10110	2026-09-17 11:04	74.70	OK
10111	2026-09-17 11:05	74.49	OK	10112	2026-09-17 11:06	72.00	OK
10113	2026-09-17 11:07	71.48	OK	10114	2026-09-17 11:08	74.74	OK
10115	2026-09-17 11:09	72.40	OK	10116	2026-09-17 11:10	70.94	OK
10117	2026-09-17 11:11	72.85	OK	10118	2026-09-17 11:12	71.55	OK
10119	2026-09-17 11:13	72.34	OK	10120	2026-09-17 11:14	72.70	OK
10121	2026-09-17 11:15	71.02	OK	10122	2026-09-17 11:16	74.44	OK
10123	2026-09-17 11:17	72.69	OK	10124	2026-09-17 11:18	71.25	OK
10125	2026-09-17 11:19	74.45	OK	10126	2026-09-17 11:20	72.29	OK
10127	2026-09-17 11:21	72.03	OK	10128	2026-09-17 11:22	71.76	OK
10129	2026-09-17 11:23	74.77	OK	10130	2026-09-17 11:24	76.15	OK
10131	2026-09-17 11:25	72.87	OK	10132	2026-09-17 11:26	72.22	OK
10133	2026-09-17 11:27	73.47	OK	10134	2026-09-17 11:28	72.23	OK
10135	2026-09-17 11:29	73.45	OK	10136	2026-09-17 11:30	75.72	OK
10137	2026-09-17 11:31	71.63	OK	10138	2026-09-17 11:32	73.67	OK
10139	2026-09-17 11:33	74.36	OK	10140	2026-09-17 11:34	72.17	OK
10141	2026-09-17 11:35	73.78	OK	10142	2026-09-17 11:36	72.65	OK
10143	2026-09-17 11:37	71.80	OK	10144	2026-09-17 11:38	72.98	OK
10145	2026-09-17 11:39	73.06	OK	10146	2026-09-17 11:40	74.46	OK
10147	2026-09-17 11:41	74.40	OK	10148	2026-09-17 11:42	69.75	OK
10149	2026-09-17 11:43	72.53	OK	10150	2026-09-17 11:44	74.69	OK
10151	2026-09-17 11:45	71.66	OK	10152	2026-09-17 11:46	73.97	OK
10153	2026-09-17 11:47	70.58	OK	10154	2026-09-17 11:48	74.94	OK
10155	2026-09-17 11:49	73.09	OK	10156	2026-09-17 11:50	71.79	OK
1015	2026-09-17 11:51	71.96	OK	1015	2026-09-17 11:52	72.43	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
10159	2026-09-17 11:53	73.94	OK	10160	2026-09-17 11:54	73.72	OK
10161	2026-09-17 11:55	70.06	OK	10162	2026-09-17 11:56	70.73	OK
10163	2026-09-17 11:57	73.11	OK	10164	2026-09-17 11:58	72.78	OK
10165	2026-09-17 11:59	74.36	OK	10166	2026-09-17 12:00	73.11	OK
10167	2026-09-17 12:01	72.54	OK	10168	2026-09-17 12:02	74.97	OK
10169	2026-09-17 12:03	74.92	OK	10170	2026-09-17 12:04	72.18	OK
10171	2026-09-17 12:05	72.46	OK	10172	2026-09-17 12:06	71.90	OK
10173	2026-09-17 12:07	72.55	OK	10174	2026-09-17 12:08	75.43	OK
10175	2026-09-17 12:09	70.29	OK	10176	2026-09-17 12:10	71.83	OK
10177	2026-09-17 12:11	72.40	OK	10178	2026-09-17 12:12	74.32	OK
10179	2026-09-17 12:13	73.19	OK	10180	2026-09-17 12:14	72.42	OK
10181	2026-09-17 12:15	75.24	OK	10182	2026-09-17 12:16	71.88	OK
10183	2026-09-17 12:17	73.55	OK	10184	2026-09-17 12:18	74.03	OK
10185	2026-09-17 12:19	72.19	OK	10186	2026-09-17 12:20	74.61	OK
10187	2026-09-17 12:21	72.09	OK	10188	2026-09-17 12:22	71.91	OK
10189	2026-09-17 12:23	73.10	OK	10190	2026-09-17 12:24	72.09	OK
10191	2026-09-17 12:25	73.48	OK	10192	2026-09-17 12:26	73.27	OK
10193	2026-09-17 12:27	70.21	OK	10194	2026-09-17 12:28	72.99	OK
10195	2026-09-17 12:29	72.74	OK	10196	2026-09-17 12:30	71.23	OK
10197	2026-09-17 12:31	72.45	OK	10198	2026-09-17 12:32	69.77	OK
10199	2026-09-17 12:33	72.84	OK	10200	2026-09-17 12:34	72.90	OK
10201	2026-09-17 12:35	74.28	OK	10202	2026-09-17 12:36	72.02	OK
10203	2026-09-17 12:37	71.82	OK	10204	2026-09-17 12:38	71.76	OK
10205	2026-09-17 12:39	72.19	OK	10206	2026-09-17 12:40	74.95	OK
10207	2026-09-17 12:41	72.19	OK	10208	2026-09-17 12:42	71.84	OK
10209	2026-09-17 12:43	71.21	OK	10210	2026-09-17 12:44	73.88	OK
10211	2026-09-17 12:45	70.48	OK	10212	2026-09-17 12:46	72.69	OK
10213	2026-09-17 12:47	75.29	OK	10214	2026-09-17 12:48	71.23	OK
10215	2026-09-17 12:49	71.57	OK	10216	2026-09-17 12:50	73.07	OK
1021	2026-09-17 12:51	73.06	OK	1021	2026-09-17 12:52	73.09	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
10219	2026-09-17 12:53	71.21	OK	10220	2026-09-17 12:54	71.89	OK
10221	2026-09-17 12:55	68.97	OK	10222	2026-09-17 12:56	73.57	OK
10223	2026-09-17 12:57	72.98	OK	10224	2026-09-17 12:58	72.16	OK
10225	2026-09-17 12:59	71.98	OK	10226	2026-09-17 13:00	69.60	OK
10227	2026-09-17 13:01	72.39	OK	10228	2026-09-17 13:02	71.55	OK
10229	2026-09-17 13:03	71.91	OK	10230	2026-09-17 13:04	71.55	OK
10231	2026-09-17 13:05	75.27	OK	10232	2026-09-17 13:06	71.64	OK
10233	2026-09-17 13:07	72.85	OK	10234	2026-09-17 13:08	71.49	OK
10235	2026-09-17 13:09	71.80	OK	10236	2026-09-17 13:10	71.83	OK
10237	2026-09-17 13:11	69.91	OK	10238	2026-09-17 13:12	71.61	OK
10239	2026-09-17 13:13	71.81	OK	10240	2026-09-17 13:14	71.01	OK
10241	2026-09-17 13:15	73.47	OK	10242	2026-09-17 13:16	72.74	OK
10243	2026-09-17 13:17	71.79	OK	10244	2026-09-17 13:18	71.89	OK
10245	2026-09-17 13:19	70.70	OK	10246	2026-09-17 13:20	71.64	OK
10247	2026-09-17 13:21	72.75	OK	10248	2026-09-17 13:22	73.63	OK
10249	2026-09-17 13:23	72.78	OK	10250	2026-09-17 13:24	71.73	OK
10251	2026-09-17 13:25	72.69	OK	10252	2026-09-17 13:26	72.25	OK
10253	2026-09-17 13:27	70.90	OK	10254	2026-09-17 13:28	71.93	OK
10255	2026-09-17 13:29	73.16	OK	10256	2026-09-17 13:30	70.54	OK
10257	2026-09-17 13:31	68.82	OK	10258	2026-09-17 13:32	69.67	OK
10259	2026-09-17 13:33	71.57	OK	10260	2026-09-17 13:34	73.78	OK
10261	2026-09-17 13:35	70.83	OK	10262	2026-09-17 13:36	72.11	OK
10263	2026-09-17 13:37	71.28	OK	10264	2026-09-17 13:38	72.48	OK
10265	2026-09-17 13:39	72.72	OK	10266	2026-09-17 13:40	71.77	OK
10267	2026-09-17 13:41	71.51	OK	10268	2026-09-17 13:42	71.44	OK
10269	2026-09-17 13:43	72.88	OK	10270	2026-09-17 13:44	70.90	OK
10271	2026-09-17 13:45	71.74	OK	10272	2026-09-17 13:46	71.90	OK
10273	2026-09-17 13:47	72.95	OK	10274	2026-09-17 13:48	72.07	OK
10275	2026-09-17 13:49	71.67	OK	10276	2026-09-17 13:50	69.68	OK
1027	2026-09-17 13:51	70.84	OK	1027	2026-09-17 13:52	70.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
10279	2026-09-17 13:53	72.61	OK	10280	2026-09-17 13:54	70.13	OK
10281	2026-09-17 13:55	71.47	OK	10282	2026-09-17 13:56	69.68	OK
10283	2026-09-17 13:57	70.21	OK	10284	2026-09-17 13:58	72.08	OK
10285	2026-09-17 13:59	72.67	OK	10286	2026-09-17 14:00	71.25	OK
10287	2026-09-17 14:01	71.35	OK	10288	2026-09-17 14:02	70.49	OK
10289	2026-09-17 14:03	73.84	OK	10290	2026-09-17 14:04	71.18	OK
10291	2026-09-17 14:05	72.69	OK	10292	2026-09-17 14:06	70.71	OK
10293	2026-09-17 14:07	72.05	OK	10294	2026-09-17 14:08	72.74	OK
10295	2026-09-17 14:09	70.55	OK	10296	2026-09-17 14:10	71.35	OK
10297	2026-09-17 14:11	71.46	OK	10298	2026-09-17 14:12	70.54	OK
10299	2026-09-17 14:13	70.54	OK	10300	2026-09-17 14:14	73.20	OK
10301	2026-09-17 14:15	72.10	OK	10302	2026-09-17 14:16	72.50	OK
10303	2026-09-17 14:17	72.53	OK	10304	2026-09-17 14:18	71.45	OK
10305	2026-09-17 14:19	68.99	OK	10306	2026-09-17 14:20	72.36	OK
10307	2026-09-17 14:21	71.57	OK	10308	2026-09-17 14:22	71.91	OK
10309	2026-09-17 14:23	70.35	OK	10310	2026-09-17 14:24	70.14	OK
10311	2026-09-17 14:25	70.75	OK	10312	2026-09-17 14:26	71.38	OK
10313	2026-09-17 14:27	72.12	OK	10314	2026-09-17 14:28	70.66	OK
10315	2026-09-17 14:29	70.14	OK	10316	2026-09-17 14:30	71.43	OK
10317	2026-09-17 14:31	69.96	OK	10318	2026-09-17 14:32	68.50	OK
10319	2026-09-17 14:33	69.85	OK	10320	2026-09-17 14:34	70.13	OK
10321	2026-09-17 14:35	72.23	OK	10322	2026-09-17 14:36	69.63	OK
10323	2026-09-17 14:37	71.32	OK	10324	2026-09-17 14:38	71.32	OK
10325	2026-09-17 14:39	72.64	OK	10326	2026-09-17 14:40	71.76	OK
10327	2026-09-17 14:41	72.79	OK	10328	2026-09-17 14:42	71.42	OK
10329	2026-09-17 14:43	72.07	OK	10330	2026-09-17 14:44	71.23	OK
10331	2026-09-17 14:45	70.22	OK	10332	2026-09-17 14:46	71.42	OK
10333	2026-09-17 14:47	72.21	OK	10334	2026-09-17 14:48	69.14	OK
10335	2026-09-17 14:49	71.89	OK	10336	2026-09-17 14:50	70.28	OK
1033	2026-09-17 14:51	70.74	OK	1033	2026-09-17 14:52	71.68	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
10339	2026-09-17 14:53	72.33	OK	10340	2026-09-17 14:54	70.02	OK
10341	2026-09-17 14:55	71.56	OK	10342	2026-09-17 14:56	70.52	OK
10343	2026-09-17 14:57	71.85	OK	10344	2026-09-17 14:58	69.75	OK
10345	2026-09-17 14:59	69.81	OK	10346	2026-09-17 15:00	71.59	OK
10347	2026-09-17 15:01	71.80	OK	10348	2026-09-17 15:02	73.02	OK
10349	2026-09-17 15:03	72.85	OK	10350	2026-09-17 15:04	71.00	OK
10351	2026-09-17 15:05	70.53	OK	10352	2026-09-17 15:06	73.20	OK
10353	2026-09-17 15:07	71.50	OK	10354	2026-09-17 15:08	70.18	OK
10355	2026-09-17 15:09	70.21	OK	10356	2026-09-17 15:10	71.12	OK
10357	2026-09-17 15:11	71.94	OK	10358	2026-09-17 15:12	70.69	OK
10359	2026-09-17 15:13	73.73	OK	10360	2026-09-17 15:14	70.36	OK
10361	2026-09-17 15:15	71.39	OK	10362	2026-09-17 15:16	72.44	OK
10363	2026-09-17 15:17	71.37	OK	10364	2026-09-17 15:18	71.85	OK
10365	2026-09-17 15:19	71.30	OK	10366	2026-09-17 15:20	70.62	OK
10367	2026-09-17 15:21	72.20	OK	10368	2026-09-17 15:22	72.81	OK
10369	2026-09-17 15:23	70.45	OK	10370	2026-09-17 15:24	69.88	OK
10371	2026-09-17 15:25	72.84	OK	10372	2026-09-17 15:26	70.63	OK
10373	2026-09-17 15:27	72.37	OK	10374	2026-09-17 15:28	71.06	OK
10375	2026-09-17 15:29	70.39	OK	10376	2026-09-17 15:30	69.37	OK
10377	2026-09-17 15:31	70.90	OK	10378	2026-09-17 15:32	71.96	OK
10379	2026-09-17 15:33	72.25	OK	10380	2026-09-17 15:34	73.39	OK
10381	2026-09-17 15:35	69.28	OK	10382	2026-09-17 15:36	69.92	OK
10383	2026-09-17 15:37	68.71	OK	10384	2026-09-17 15:38	70.36	OK
10385	2026-09-17 15:39	70.65	OK	10386	2026-09-17 15:40	70.86	OK
10387	2026-09-17 15:41	69.46	OK	10388	2026-09-17 15:42	71.81	OK
10389	2026-09-17 15:43	71.20	OK	10390	2026-09-17 15:44	74.13	OK
10391	2026-09-17 15:45	71.18	OK	10392	2026-09-17 15:46	71.05	OK
10393	2026-09-17 15:47	71.82	OK	10394	2026-09-17 15:48	69.43	OK
10395	2026-09-17 15:49	71.37	OK	10396	2026-09-17 15:50	72.19	OK
1039	2026-09-17 15:51	69.74	OK	1039	2026-09-17 15:52	71.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
10399	2026-09-17 15:53	70.47	OK	10400	2026-09-17 15:54	72.75	OK
10401	2026-09-17 15:55	70.96	OK	10402	2026-09-17 15:56	72.69	OK
10403	2026-09-17 15:57	75.06	OK	10404	2026-09-17 15:58	68.89	OK
10405	2026-09-17 15:59	72.88	OK	10406	2026-09-17 16:00	72.90	OK
10407	2026-09-17 16:01	70.88	OK	10408	2026-09-17 16:02	73.11	OK
10409	2026-09-17 16:03	70.48	OK	10410	2026-09-17 16:04	73.20	OK
10411	2026-09-17 16:05	71.02	OK	10412	2026-09-17 16:06	70.88	OK
10413	2026-09-17 16:07	72.65	OK	10414	2026-09-17 16:08	70.03	OK
10415	2026-09-17 16:09	68.87	OK	10416	2026-09-17 16:10	70.34	OK
10417	2026-09-17 16:11	73.68	OK	10418	2026-09-17 16:12	71.44	OK
10419	2026-09-17 16:13	72.95	OK	10420	2026-09-17 16:14	72.73	OK
10421	2026-09-17 16:15	73.09	OK	10422	2026-09-17 16:16	72.72	OK
10423	2026-09-17 16:17	69.69	OK	10424	2026-09-17 16:18	70.33	OK
10425	2026-09-17 16:19	71.57	OK	10426	2026-09-17 16:20	69.62	OK
10427	2026-09-17 16:21	71.38	OK	10428	2026-09-17 16:22	73.87	OK
10429	2026-09-17 16:23	72.86	OK	10430	2026-09-17 16:24	70.91	OK
10431	2026-09-17 16:25	73.02	OK	10432	2026-09-17 16:26	70.41	OK
10433	2026-09-17 16:27	71.28	OK	10434	2026-09-17 16:28	71.19	OK
10435	2026-09-17 16:29	73.25	OK	10436	2026-09-17 16:30	71.85	OK
10437	2026-09-17 16:31	71.99	OK	10438	2026-09-17 16:32	72.56	OK
10439	2026-09-17 16:33	72.14	OK	10440	2026-09-17 16:34	73.25	OK
10441	2026-09-17 16:35	70.26	OK	10442	2026-09-17 16:36	71.83	OK
10443	2026-09-17 16:37	72.93	OK	10444	2026-09-17 16:38	70.11	OK
10445	2026-09-17 16:39	74.34	OK	10446	2026-09-17 16:40	72.98	OK
10447	2026-09-17 16:41	70.73	OK	10448	2026-09-17 16:42	73.69	OK
10449	2026-09-17 16:43	71.55	OK	10450	2026-09-17 16:44	72.97	OK
10451	2026-09-17 16:45	70.92	OK	10452	2026-09-17 16:46	70.70	OK
10453	2026-09-17 16:47	71.42	OK	10454	2026-09-17 16:48	71.53	OK
10455	2026-09-17 16:49	72.55	OK	10456	2026-09-17 16:50	73.21	OK
1045	2026-09-17 16:51	73.08	OK	1045	2026-09-17 16:52	73.21	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
10459	2026-09-17 16:53	70.06	OK	10460	2026-09-17 16:54	71.32	OK
10461	2026-09-17 16:55	70.95	OK	10462	2026-09-17 16:56	72.34	OK
10463	2026-09-17 16:57	74.05	OK	10464	2026-09-17 16:58	71.23	OK
10465	2026-09-17 16:59	72.79	OK	10466	2026-09-17 17:00	72.55	OK
10467	2026-09-17 17:01	73.35	OK	10468	2026-09-17 17:02	73.21	OK
10469	2026-09-17 17:03	73.16	OK	10470	2026-09-17 17:04	72.57	OK
10471	2026-09-17 17:05	71.81	OK	10472	2026-09-17 17:06	72.51	OK
10473	2026-09-17 17:07	71.91	OK	10474	2026-09-17 17:08	71.79	OK
10475	2026-09-17 17:09	74.40	OK	10476	2026-09-17 17:10	73.14	OK
10477	2026-09-17 17:11	70.76	OK	10478	2026-09-17 17:12	71.14	OK
10479	2026-09-17 17:13	71.66	OK	10480	2026-09-17 17:14	71.36	OK
10481	2026-09-17 17:15	71.08	OK	10482	2026-09-17 17:16	71.27	OK
10483	2026-09-17 17:17	71.73	OK	10484	2026-09-17 17:18	69.50	OK
10485	2026-09-17 17:19	72.86	OK	10486	2026-09-17 17:20	72.29	OK
10487	2026-09-17 17:21	69.72	OK	10488	2026-09-17 17:22	70.77	OK
10489	2026-09-17 17:23	70.97	OK	10490	2026-09-17 17:24	74.36	OK
10491	2026-09-17 17:25	73.21	OK	10492	2026-09-17 17:26	73.28	OK
10493	2026-09-17 17:27	70.17	OK	10494	2026-09-17 17:28	72.90	OK
10495	2026-09-17 17:29	72.68	OK	10496	2026-09-17 17:30	71.77	OK
10497	2026-09-17 17:31	74.38	OK	10498	2026-09-17 17:32	74.78	OK
10499	2026-09-17 17:33	73.36	OK	10500	2026-09-17 17:34	72.41	OK
10501	2026-09-17 17:35	72.85	OK	10502	2026-09-17 17:36	73.20	OK
10503	2026-09-17 17:37	72.69	OK	10504	2026-09-17 17:38	71.11	OK
10505	2026-09-17 17:39	75.11	OK	10506	2026-09-17 17:40	71.99	OK
10507	2026-09-17 17:41	72.67	OK	10508	2026-09-17 17:42	74.93	OK
10509	2026-09-17 17:43	71.04	OK	10510	2026-09-17 17:44	71.73	OK
10511	2026-09-17 17:45	72.04	OK	10512	2026-09-17 17:46	71.55	OK
10513	2026-09-17 17:47	73.23	OK	10514	2026-09-17 17:48	72.25	OK
10515	2026-09-17 17:49	74.46	OK	10516	2026-09-17 17:50	72.97	OK
1051	2026-09-17 17:51	71.28	OK	1051	2026-09-17 17:52	74.28	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
10519	2026-09-17 17:53	75.50	OK	10520	2026-09-17 17:54	74.29	OK
10521	2026-09-17 17:55	73.19	OK	10522	2026-09-17 17:56	73.42	OK
10523	2026-09-17 17:57	72.07	OK	10524	2026-09-17 17:58	70.72	OK
10525	2026-09-17 17:59	74.14	OK	10526	2026-09-17 18:00	74.03	OK
10527	2026-09-17 18:01	71.63	OK	10528	2026-09-17 18:02	73.25	OK
10529	2026-09-17 18:03	71.75	OK	10530	2026-09-17 18:04	72.22	OK
10531	2026-09-17 18:05	71.87	OK	10532	2026-09-17 18:06	73.21	OK
10533	2026-09-17 18:07	75.04	OK	10534	2026-09-17 18:08	72.66	OK
10535	2026-09-17 18:09	72.80	OK	10536	2026-09-17 18:10	74.51	OK
10537	2026-09-17 18:11	72.15	OK	10538	2026-09-17 18:12	74.55	OK
10539	2026-09-17 18:13	75.13	OK	10540	2026-09-17 18:14	72.29	OK
10541	2026-09-17 18:15	72.79	OK	10542	2026-09-17 18:16	72.31	OK
10543	2026-09-17 18:17	74.85	OK	10544	2026-09-17 18:18	73.16	OK
10545	2026-09-17 18:19	74.19	OK	10546	2026-09-17 18:20	71.48	OK
10547	2026-09-17 18:21	72.41	OK	10548	2026-09-17 18:22	74.07	OK
10549	2026-09-17 18:23	72.23	OK	10550	2026-09-17 18:24	72.07	OK
10551	2026-09-17 18:25	72.64	OK	10552	2026-09-17 18:26	72.01	OK
10553	2026-09-17 18:27	74.22	OK	10554	2026-09-17 18:28	74.06	OK
10555	2026-09-17 18:29	71.19	OK	10556	2026-09-17 18:30	74.53	OK
10557	2026-09-17 18:31	75.06	OK	10558	2026-09-17 18:32	72.23	OK
10559	2026-09-17 18:33	72.46	OK	10560	2026-09-17 18:34	73.34	OK
10561	2026-09-17 18:35	73.68	OK	10562	2026-09-17 18:36	72.12	OK
10563	2026-09-17 18:37	75.28	OK	10564	2026-09-17 18:38	75.66	OK
10565	2026-09-17 18:39	73.88	OK	10566	2026-09-17 18:40	71.15	OK
10567	2026-09-17 18:41	75.78	OK	10568	2026-09-17 18:42	74.41	OK
10569	2026-09-17 18:43	73.73	OK	10570	2026-09-17 18:44	71.56	OK
10571	2026-09-17 18:45	73.27	OK	10572	2026-09-17 18:46	72.78	OK
10573	2026-09-17 18:47	75.92	OK	10574	2026-09-17 18:48	75.17	OK
10575	2026-09-17 18:49	74.23	OK	10576	2026-09-17 18:50	75.21	OK
1057	2026-09-17 18:51	73.71	OK	1057	2026-09-17 18:52	74.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
10579	2026-09-17 18:53	75.61	OK	10580	2026-09-17 18:54	73.80	OK
10581	2026-09-17 18:55	72.75	OK	10582	2026-09-17 18:56	73.63	OK
10583	2026-09-17 18:57	73.23	OK	10584	2026-09-17 18:58	74.88	OK
10585	2026-09-17 18:59	75.11	OK	10586	2026-09-17 19:00	76.02	OK
10587	2026-09-17 19:01	73.98	OK	10588	2026-09-17 19:02	73.49	OK
10589	2026-09-17 19:03	75.34	OK	10590	2026-09-17 19:04	73.07	OK
10591	2026-09-17 19:05	74.03	OK	10592	2026-09-17 19:06	74.41	OK
10593	2026-09-17 19:07	73.84	OK	10594	2026-09-17 19:08	75.18	OK
10595	2026-09-17 19:09	72.60	OK	10596	2026-09-17 19:10	73.89	OK
10597	2026-09-17 19:11	72.87	OK	10598	2026-09-17 19:12	74.24	OK
10599	2026-09-17 19:13	73.53	OK	10600	2026-09-17 19:14	73.94	OK
10601	2026-09-17 19:15	72.49	OK	10602	2026-09-17 19:16	73.33	OK
10603	2026-09-17 19:17	75.46	OK	10604	2026-09-17 19:18	73.45	OK
10605	2026-09-17 19:19	74.82	OK	10606	2026-09-17 19:20	76.00	OK
10607	2026-09-17 19:21	74.35	OK	10608	2026-09-17 19:22	74.65	OK
10609	2026-09-17 19:23	75.52	OK	10610	2026-09-17 19:24	76.43	OK
10611	2026-09-17 19:25	71.69	OK	10612	2026-09-17 19:26	75.64	OK
10613	2026-09-17 19:27	77.64	OK	10614	2026-09-17 19:28	74.13	OK
10615	2026-09-17 19:29	74.94	OK	10616	2026-09-17 19:30	76.58	OK
10617	2026-09-17 19:31	73.66	OK	10618	2026-09-17 19:32	73.95	OK
10619	2026-09-17 19:33	74.36	OK	10620	2026-09-17 19:34	75.16	OK
10621	2026-09-17 19:35	76.03	OK	10622	2026-09-17 19:36	74.42	OK
10623	2026-09-17 19:37	74.90	OK	10624	2026-09-17 19:38	72.39	OK
10625	2026-09-17 19:39	74.73	OK	10626	2026-09-17 19:40	73.21	OK
10627	2026-09-17 19:41	75.30	OK	10628	2026-09-17 19:42	74.95	OK
10629	2026-09-17 19:43	75.60	OK	10630	2026-09-17 19:44	73.49	OK
10631	2026-09-17 19:45	72.84	OK	10632	2026-09-17 19:46	74.27	OK
10633	2026-09-17 19:47	77.00	OK	10634	2026-09-17 19:48	74.28	OK
10635	2026-09-17 19:49	76.71	OK	10636	2026-09-17 19:50	73.54	OK
1063	2026-09-17 19:51	74.88	OK	1063	2026-09-17 19:52	77.38	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
10639	2026-09-17 19:53	76.54	OK	10640	2026-09-17 19:54	75.46	OK
10641	2026-09-17 19:55	75.77	OK	10642	2026-09-17 19:56	74.87	OK
10643	2026-09-17 19:57	73.89	OK	10644	2026-09-17 19:58	72.09	OK
10645	2026-09-17 19:59	74.47	OK	10646	2026-09-17 20:00	74.73	OK
10647	2026-09-17 20:01	72.74	OK	10648	2026-09-17 20:02	76.61	OK
10649	2026-09-17 20:03	77.03	OK	10650	2026-09-17 20:04	74.34	OK
10651	2026-09-17 20:05	75.39	OK	10652	2026-09-17 20:06	75.76	OK
10653	2026-09-17 20:07	75.98	OK	10654	2026-09-17 20:08	77.12	OK
10655	2026-09-17 20:09	74.00	OK	10656	2026-09-17 20:10	75.82	OK
10657	2026-09-17 20:11	75.27	OK	10658	2026-09-17 20:12	77.34	OK
10659	2026-09-17 20:13	78.19	OK	10660	2026-09-17 20:14	77.54	OK
10661	2026-09-17 20:15	73.35	OK	10662	2026-09-17 20:16	76.05	OK
10663	2026-09-17 20:17	74.05	OK	10664	2026-09-17 20:18	74.23	OK
10665	2026-09-17 20:19	76.82	OK	10666	2026-09-17 20:20	76.64	OK
10667	2026-09-17 20:21	75.93	OK	10668	2026-09-17 20:22	76.62	OK
10669	2026-09-17 20:23	76.60	OK	10670	2026-09-17 20:24	76.61	OK
10671	2026-09-17 20:25	78.35	OK	10672	2026-09-17 20:26	77.10	OK
10673	2026-09-17 20:27	74.06	OK	10674	2026-09-17 20:28	74.16	OK
10675	2026-09-17 20:29	75.11	OK	10676	2026-09-17 20:30	73.87	OK
10677	2026-09-17 20:31	73.41	OK	10678	2026-09-17 20:32	77.06	OK
10679	2026-09-17 20:33	76.23	OK	10680	2026-09-17 20:34	73.92	OK
10681	2026-09-17 20:35	75.39	OK	10682	2026-09-17 20:36	76.93	OK
10683	2026-09-17 20:37	77.03	OK	10684	2026-09-17 20:38	77.30	OK
10685	2026-09-17 20:39	75.69	OK	10686	2026-09-17 20:40	76.33	OK
10687	2026-09-17 20:41	77.60	OK	10688	2026-09-17 20:42	75.64	OK
10689	2026-09-17 20:43	77.04	OK	10690	2026-09-17 20:44	73.41	OK
10691	2026-09-17 20:45	74.93	OK	10692	2026-09-17 20:46	77.86	OK
10693	2026-09-17 20:47	76.71	OK	10694	2026-09-17 20:48	76.12	OK
10695	2026-09-17 20:49	75.42	OK	10696	2026-09-17 20:50	77.77	OK
1069	2026-09-17 20:51	75.09	OK	1069	2026-09-17 20:52	77.79	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
10699	2026-09-17 20:53	77.32	OK	10700	2026-09-17 20:54	74.69	OK
10701	2026-09-17 20:55	75.79	OK	10702	2026-09-17 20:56	77.73	OK
10703	2026-09-17 20:57	75.85	OK	10704	2026-09-17 20:58	76.80	OK
10705	2026-09-17 20:59	75.35	OK	10706	2026-09-17 21:00	76.45	OK
10707	2026-09-17 21:01	76.24	OK	10708	2026-09-17 21:02	76.73	OK
10709	2026-09-17 21:03	77.03	OK	10710	2026-09-17 21:04	76.88	OK
10711	2026-09-17 21:05	78.00	OK	10712	2026-09-17 21:06	75.84	OK
10713	2026-09-17 21:07	79.91	OK	10714	2026-09-17 21:08	75.69	OK
10715	2026-09-17 21:09	76.22	OK	10716	2026-09-17 21:10	77.96	OK
10717	2026-09-17 21:11	74.59	OK	10718	2026-09-17 21:12	77.16	OK
10719	2026-09-17 21:13	77.03	OK	10720	2026-09-17 21:14	77.86	OK
10721	2026-09-17 21:15	77.23	OK	10722	2026-09-17 21:16	78.60	OK
10723	2026-09-17 21:17	78.51	OK	10724	2026-09-17 21:18	74.76	OK
10725	2026-09-17 21:19	77.31	OK	10726	2026-09-17 21:20	78.05	OK
10727	2026-09-17 21:21	77.02	OK	10728	2026-09-17 21:22	74.94	OK
10729	2026-09-17 21:23	78.47	OK	10730	2026-09-17 21:24	76.57	OK
10731	2026-09-17 21:25	75.78	OK	10732	2026-09-17 21:26	78.57	OK
10733	2026-09-17 21:27	79.65	OK	10734	2026-09-17 21:28	76.53	OK
10735	2026-09-17 21:29	79.21	OK	10736	2026-09-17 21:30	77.02	OK
10737	2026-09-17 21:31	77.01	OK	10738	2026-09-17 21:32	78.71	OK
10739	2026-09-17 21:33	75.39	OK	10740	2026-09-17 21:34	79.89	OK
10741	2026-09-17 21:35	77.58	OK	10742	2026-09-17 21:36	77.05	OK
10743	2026-09-17 21:37	77.27	OK	10744	2026-09-17 21:38	78.51	OK
10745	2026-09-17 21:39	76.52	OK	10746	2026-09-17 21:40	79.63	OK
10747	2026-09-17 21:41	78.69	OK	10748	2026-09-17 21:42	76.49	OK
10749	2026-09-17 21:43	77.92	OK	10750	2026-09-17 21:44	77.81	OK
10751	2026-09-17 21:45	76.93	OK	10752	2026-09-17 21:46	78.16	OK
10753	2026-09-17 21:47	78.11	OK	10754	2026-09-17 21:48	76.70	OK
10755	2026-09-17 21:49	78.78	OK	10756	2026-09-17 21:50	77.10	OK
1075	2026-09-17 21:51	79.45	OK	1075	2026-09-17 21:52	78.86	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
10759	2026-09-17 21:53	78.39	OK	10760	2026-09-17 21:54	79.23	OK
10761	2026-09-17 21:55	78.55	OK	10762	2026-09-17 21:56	78.55	OK
10763	2026-09-17 21:57	77.01	OK	10764	2026-09-17 21:58	78.02	OK
10765	2026-09-17 21:59	78.78	OK	10766	2026-09-17 22:00	78.55	OK
10767	2026-09-17 22:01	77.93	OK	10768	2026-09-17 22:02	78.58	OK
10769	2026-09-17 22:03	78.47	OK	10770	2026-09-17 22:04	77.26	OK
10771	2026-09-17 22:05	78.66	OK	10772	2026-09-17 22:06	81.17	OK
10773	2026-09-17 22:07	78.80	OK	10774	2026-09-17 22:08	77.86	OK
10775	2026-09-17 22:09	77.49	OK	10776	2026-09-17 22:10	78.64	OK
10777	2026-09-17 22:11	76.62	OK	10778	2026-09-17 22:12	76.53	OK
10779	2026-09-17 22:13	76.16	OK	10780	2026-09-17 22:14	79.15	OK
10781	2026-09-17 22:15	77.65	OK	10782	2026-09-17 22:16	76.71	OK
10783	2026-09-17 22:17	78.34	OK	10784	2026-09-17 22:18	78.89	OK
10785	2026-09-17 22:19	79.36	OK	10786	2026-09-17 22:20	79.01	OK
10787	2026-09-17 22:21	80.12	OK	10788	2026-09-17 22:22	79.37	OK
10789	2026-09-17 22:23	79.71	OK	10790	2026-09-17 22:24	81.71	OK
10791	2026-09-17 22:25	79.35	OK	10792	2026-09-17 22:26	79.29	OK
10793	2026-09-17 22:27	78.41	OK	10794	2026-09-17 22:28	78.79	OK
10795	2026-09-17 22:29	80.66	OK	10796	2026-09-17 22:30	80.11	OK
10797	2026-09-17 22:31	76.46	OK	10798	2026-09-17 22:32	79.98	OK
10799	2026-09-17 22:33	77.70	OK	10800	2026-09-17 22:34	78.16	OK
10801	2026-09-17 22:35	78.09	OK	10802	2026-09-17 22:36	79.70	OK
10803	2026-09-17 22:37	79.62	OK	10804	2026-09-17 22:38	78.70	OK
10805	2026-09-17 22:39	79.03	OK	10806	2026-09-17 22:40	80.17	OK
10807	2026-09-17 22:41	78.06	OK	10808	2026-09-17 22:42	78.47	OK
10809	2026-09-17 22:43	79.64	OK	10810	2026-09-17 22:44	77.17	OK
10811	2026-09-17 22:45	77.68	OK	10812	2026-09-17 22:46	77.43	OK
10813	2026-09-17 22:47	78.72	OK	10814	2026-09-17 22:48	78.25	OK
10815	2026-09-17 22:49	79.40	OK	10816	2026-09-17 22:50	77.81	OK
1081	2026-09-17 22:51	81.38	OK	1081	2026-09-17 22:52	78.27	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
10819	2026-09-17 22:53	79.99	OK	10820	2026-09-17 22:54	80.45	OK
10821	2026-09-17 22:55	79.36	OK	10822	2026-09-17 22:56	80.18	OK
10823	2026-09-17 22:57	77.47	OK	10824	2026-09-17 22:58	80.67	OK
10825	2026-09-17 22:59	76.69	OK	10826	2026-09-17 23:00	79.57	OK
10827	2026-09-17 23:01	78.84	OK	10828	2026-09-17 23:02	79.18	OK
10829	2026-09-17 23:03	81.37	OK	10830	2026-09-17 23:04	79.29	OK
10831	2026-09-17 23:05	78.35	OK	10832	2026-09-17 23:06	79.56	OK
10833	2026-09-17 23:07	81.60	OK	10834	2026-09-17 23:08	81.36	OK
10835	2026-09-17 23:09	78.28	OK	10836	2026-09-17 23:10	78.98	OK
10837	2026-09-17 23:11	78.79	OK	10838	2026-09-17 23:12	78.35	OK
10839	2026-09-17 23:13	77.62	OK	10840	2026-09-17 23:14	79.43	OK
10841	2026-09-17 23:15	78.60	OK	10842	2026-09-17 23:16	80.66	OK
10843	2026-09-17 23:17	79.03	OK	10844	2026-09-17 23:18	80.34	OK
10845	2026-09-17 23:19	80.01	OK	10846	2026-09-17 23:20	81.19	OK
10847	2026-09-17 23:21	77.87	OK	10848	2026-09-17 23:22	79.20	OK
10849	2026-09-17 23:23	80.05	OK	10850	2026-09-17 23:24	79.40	OK
10851	2026-09-17 23:25	79.23	OK	10852	2026-09-17 23:26	81.46	OK
10853	2026-09-17 23:27	80.01	OK	10854	2026-09-17 23:28	82.52	OK
10855	2026-09-17 23:29	79.97	OK	10856	2026-09-17 23:30	79.11	OK
10857	2026-09-17 23:31	80.16	OK	10858	2026-09-17 23:32	80.95	OK
10859	2026-09-17 23:33	82.15	OK	10860	2026-09-17 23:34	79.13	OK
10861	2026-09-17 23:35	82.28	OK	10862	2026-09-17 23:36	79.45	OK
10863	2026-09-17 23:37	81.05	OK	10864	2026-09-17 23:38	77.56	OK
10865	2026-09-17 23:39	80.25	OK	10866	2026-09-17 23:40	81.37	OK
10867	2026-09-17 23:41	79.34	OK	10868	2026-09-17 23:42	79.77	OK
10869	2026-09-17 23:43	79.32	OK	10870	2026-09-17 23:44	78.80	OK
10871	2026-09-17 23:45	79.00	OK	10872	2026-09-17 23:46	80.65	OK
10873	2026-09-17 23:47	79.15	OK	10874	2026-09-17 23:48	79.43	OK
10875	2026-09-17 23:49	79.09	OK	10876	2026-09-17 23:50	81.82	OK
1087	2026-09-17 23:51	81.23	OK	1087	2026-09-17 23:52	79.82	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
10879	2026-09-17 23:53	82.18	OK	10880	2026-09-17 23:54	80.05	OK
10881	2026-09-17 23:55	81.03	OK	10882	2026-09-17 23:56	80.78	OK
10883	2026-09-17 23:57	78.44	OK	10884	2026-09-17 23:58	78.63	OK
10885	2026-09-17 23:59	81.34	OK	10886	2026-09-18 00:00	81.19	OK
10887	2026-09-18 00:01	80.77	OK	10888	2026-09-18 00:02	82.43	OK
10889	2026-09-18 00:03	79.48	OK	10890	2026-09-18 00:04	82.82	OK
10891	2026-09-18 00:05	80.62	OK	10892	2026-09-18 00:06	78.51	OK
10893	2026-09-18 00:07	83.40	OK	10894	2026-09-18 00:08	79.13	OK
10895	2026-09-18 00:09	80.49	OK	10896	2026-09-18 00:10	81.57	OK
10897	2026-09-18 00:11	77.16	OK	10898	2026-09-18 00:12	81.50	OK
10899	2026-09-18 00:13	80.04	OK	10900	2026-09-18 00:14	80.15	OK
10901	2026-09-18 00:15	79.70	OK	10902	2026-09-18 00:16	81.72	OK
10903	2026-09-18 00:17	78.33	OK	10904	2026-09-18 00:18	79.58	OK
10905	2026-09-18 00:19	82.30	OK	10906	2026-09-18 00:20	80.92	OK
10907	2026-09-18 00:21	81.46	OK	10908	2026-09-18 00:22	80.80	OK
10909	2026-09-18 00:23	82.26	OK	10910	2026-09-18 00:24	81.90	OK
10911	2026-09-18 00:25	79.60	OK	10912	2026-09-18 00:26	79.28	OK
10913	2026-09-18 00:27	80.40	OK	10914	2026-09-18 00:28	79.86	OK
10915	2026-09-18 00:29	81.08	OK	10916	2026-09-18 00:30	80.99	OK
10917	2026-09-18 00:31	81.06	OK	10918	2026-09-18 00:32	82.11	OK
10919	2026-09-18 00:33	78.78	OK	10920	2026-09-18 00:34	81.21	OK
10921	2026-09-18 00:35	80.64	OK	10922	2026-09-18 00:36	80.25	OK
10923	2026-09-18 00:37	81.06	OK	10924	2026-09-18 00:38	78.55	OK
10925	2026-09-18 00:39	82.03	OK	10926	2026-09-18 00:40	81.26	OK
10927	2026-09-18 00:41	82.67	OK	10928	2026-09-18 00:42	81.71	OK
10929	2026-09-18 00:43	80.93	OK	10930	2026-09-18 00:44	80.54	OK
10931	2026-09-18 00:45	78.55	OK	10932	2026-09-18 00:46	80.78	OK
10933	2026-09-18 00:47	80.42	OK	10934	2026-09-18 00:48	81.32	OK
10935	2026-09-18 00:49	80.04	OK	10936	2026-09-18 00:50	81.71	OK
1093	2026-09-18 00:51	81.91	OK	1093	2026-09-18 00:52	80.79	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
10939	2026-09-18 00:53	82.41	OK	10940	2026-09-18 00:54	81.17	OK
10941	2026-09-18 00:55	81.67	OK	10942	2026-09-18 00:56	81.79	OK
10943	2026-09-18 00:57	79.70	OK	10944	2026-09-18 00:58	81.54	OK
10945	2026-09-18 00:59	79.91	OK	10946	2026-09-18 01:00	81.85	OK
10947	2026-09-18 01:01	81.87	OK	10948	2026-09-18 01:02	80.11	OK
10949	2026-09-18 01:03	79.30	OK	10950	2026-09-18 01:04	82.55	OK
10951	2026-09-18 01:05	82.58	OK	10952	2026-09-18 01:06	82.24	OK
10953	2026-09-18 01:07	80.99	OK	10954	2026-09-18 01:08	81.49	OK
10955	2026-09-18 01:09	81.23	OK	10956	2026-09-18 01:10	81.25	OK
10957	2026-09-18 01:11	81.06	OK	10958	2026-09-18 01:12	80.95	OK
10959	2026-09-18 01:13	80.06	OK	10960	2026-09-18 01:14	82.51	OK
10961	2026-09-18 01:15	80.40	OK	10962	2026-09-18 01:16	81.47	OK
10963	2026-09-18 01:17	79.98	OK	10964	2026-09-18 01:18	81.73	OK
10965	2026-09-18 01:19	80.16	OK	10966	2026-09-18 01:20	80.45	OK
10967	2026-09-18 01:21	83.12	OK	10968	2026-09-18 01:22	80.79	OK
10969	2026-09-18 01:23	82.90	OK	10970	2026-09-18 01:24	82.49	OK
10971	2026-09-18 01:25	78.90	OK	10972	2026-09-18 01:26	80.20	OK
10973	2026-09-18 01:27	80.24	OK	10974	2026-09-18 01:28	80.14	OK
10975	2026-09-18 01:29	81.35	OK	10976	2026-09-18 01:30	81.60	OK
10977	2026-09-18 01:31	81.56	OK	10978	2026-09-18 01:32	81.86	OK
10979	2026-09-18 01:33	79.87	OK	10980	2026-09-18 01:34	81.07	OK
10981	2026-09-18 01:35	79.66	OK	10982	2026-09-18 01:36	79.11	OK
10983	2026-09-18 01:37	79.98	OK	10984	2026-09-18 01:38	79.38	OK
10985	2026-09-18 01:39	80.58	OK	10986	2026-09-18 01:40	82.28	OK
10987	2026-09-18 01:41	82.83	OK	10988	2026-09-18 01:42	82.99	OK
10989	2026-09-18 01:43	80.18	OK	10990	2026-09-18 01:44	82.14	OK
10991	2026-09-18 01:45	81.45	OK	10992	2026-09-18 01:46	80.62	OK
10993	2026-09-18 01:47	82.14	OK	10994	2026-09-18 01:48	82.51	OK
10995	2026-09-18 01:49	81.05	OK	10996	2026-09-18 01:50	80.11	OK
1099	2026-09-18 01:51	80.71	OK	1099	2026-09-18 01:52	82.63	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
10999	2026-09-18 01:53	83.85	OK	11000	2026-09-18 01:54	82.63	OK
11001	2026-09-18 01:55	83.10	OK	11002	2026-09-18 01:56	82.23	OK
11003	2026-09-18 01:57	82.22	OK	11004	2026-09-18 01:58	81.46	OK
11005	2026-09-18 01:59	81.59	OK	11006	2026-09-18 02:00	80.51	OK
11007	2026-09-18 02:01	82.66	OK	11008	2026-09-18 02:02	82.54	OK
11009	2026-09-18 02:03	81.60	OK	11010	2026-09-18 02:04	83.97	OK
11011	2026-09-18 02:05	79.58	OK	11012	2026-09-18 02:06	82.90	OK
11013	2026-09-18 02:07	80.28	OK	11014	2026-09-18 02:08	78.67	OK
11015	2026-09-18 02:09	82.93	OK	11016	2026-09-18 02:10	82.20	OK
11017	2026-09-18 02:11	80.95	OK	11018	2026-09-18 02:12	80.90	OK
11019	2026-09-18 02:13	81.10	OK	11020	2026-09-18 02:14	81.72	OK
11021	2026-09-18 02:15	81.52	OK	11022	2026-09-18 02:16	81.06	OK
11023	2026-09-18 02:17	80.10	OK	11024	2026-09-18 02:18	82.09	OK
11025	2026-09-18 02:19	80.47	OK	11026	2026-09-18 02:20	81.39	OK
11027	2026-09-18 02:21	78.89	OK	11028	2026-09-18 02:22	82.56	OK
11029	2026-09-18 02:23	81.12	OK	11030	2026-09-18 02:24	81.25	OK
11031	2026-09-18 02:25	79.61	OK	11032	2026-09-18 02:26	80.99	OK
11033	2026-09-18 02:27	80.08	OK	11034	2026-09-18 02:28	82.40	OK
11035	2026-09-18 02:29	83.17	OK	11036	2026-09-18 02:30	83.13	OK
11037	2026-09-18 02:31	78.77	OK	11038	2026-09-18 02:32	78.89	OK
11039	2026-09-18 02:33	83.11	OK	11040	2026-09-18 02:34	82.24	OK
11041	2026-09-18 02:35	81.29	OK	11042	2026-09-18 02:36	81.66	OK
11043	2026-09-18 02:37	81.10	OK	11044	2026-09-18 02:38	82.49	OK
11045	2026-09-18 02:39	81.93	OK	11046	2026-09-18 02:40	83.71	OK
11047	2026-09-18 02:41	80.36	OK	11048	2026-09-18 02:42	83.35	OK
11049	2026-09-18 02:43	82.55	OK	11050	2026-09-18 02:44	81.05	OK
11051	2026-09-18 02:45	83.45	OK	11052	2026-09-18 02:46	81.94	OK
11053	2026-09-18 02:47	84.37	OK	11054	2026-09-18 02:48	81.17	OK
11055	2026-09-18 02:49	81.71	OK	11056	2026-09-18 02:50	81.45	OK
1105	2026-09-18 02:51	80.01	OK	1105	2026-09-18 02:52	79.95	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
11059	2026-09-18 02:53	81.83	OK	11060	2026-09-18 02:54	83.64	OK
11061	2026-09-18 02:55	82.99	OK	11062	2026-09-18 02:56	80.62	OK
11063	2026-09-18 02:57	82.46	OK	11064	2026-09-18 02:58	79.89	OK
11065	2026-09-18 02:59	80.74	OK	11066	2026-09-18 03:00	81.88	OK
11067	2026-09-18 03:01	80.82	OK	11068	2026-09-18 03:02	81.09	OK
11069	2026-09-18 03:03	80.69	OK	11070	2026-09-18 03:04	82.06	OK
11071	2026-09-18 03:05	84.43	OK	11072	2026-09-18 03:06	82.17	OK
11073	2026-09-18 03:07	82.71	OK	11074	2026-09-18 03:08	82.11	OK
11075	2026-09-18 03:09	80.58	OK	11076	2026-09-18 03:10	81.35	OK
11077	2026-09-18 03:11	80.83	OK	11078	2026-09-18 03:12	82.65	OK
11079	2026-09-18 03:13	82.69	OK	11080	2026-09-18 03:14	82.74	OK
11081	2026-09-18 03:15	82.46	OK	11082	2026-09-18 03:16	82.72	OK
11083	2026-09-18 03:17	80.92	OK	11084	2026-09-18 03:18	83.28	OK
11085	2026-09-18 03:19	82.25	OK	11086	2026-09-18 03:20	81.16	OK
11087	2026-09-18 03:21	80.86	OK	11088	2026-09-18 03:22	81.66	OK
11089	2026-09-18 03:23	82.37	OK	11090	2026-09-18 03:24	81.31	OK
11091	2026-09-18 03:25	84.21	OK	11092	2026-09-18 03:26	83.42	OK
11093	2026-09-18 03:27	81.31	OK	11094	2026-09-18 03:28	82.37	OK
11095	2026-09-18 03:29	82.61	OK	11096	2026-09-18 03:30	81.05	OK
11097	2026-09-18 03:31	78.34	OK	11098	2026-09-18 03:32	79.32	OK
11099	2026-09-18 03:33	80.04	OK	11100	2026-09-18 03:34	80.85	OK
11101	2026-09-18 03:35	82.55	OK	11102	2026-09-18 03:36	83.43	OK
11103	2026-09-18 03:37	83.38	OK	11104	2026-09-18 03:38	80.90	OK
11105	2026-09-18 03:39	79.55	OK	11106	2026-09-18 03:40	82.18	OK
11107	2026-09-18 03:41	80.06	OK	11108	2026-09-18 03:42	83.27	OK
11109	2026-09-18 03:43	81.71	OK	11110	2026-09-18 03:44	83.54	OK
11111	2026-09-18 03:45	81.57	OK	11112	2026-09-18 03:46	81.53	OK
11113	2026-09-18 03:47	82.35	OK	11114	2026-09-18 03:48	80.72	OK
11115	2026-09-18 03:49	81.67	OK	11116	2026-09-18 03:50	83.39	OK
11117	2026-09-18 03:51	82.26	OK	11118	2026-09-18 03:52	81.60	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
11119	2026-09-18 03:53	81.31	OK	11120	2026-09-18 03:54	80.64	OK
11121	2026-09-18 03:55	83.71	OK	11122	2026-09-18 03:56	82.97	OK
11123	2026-09-18 03:57	80.85	OK	11124	2026-09-18 03:58	81.78	OK
11125	2026-09-18 03:59	82.31	OK	11126	2026-09-18 04:00	80.25	OK
11127	2026-09-18 04:01	81.58	OK	11128	2026-09-18 04:02	80.90	OK
11129	2026-09-18 04:03	81.71	OK	11130	2026-09-18 04:04	81.61	OK
11131	2026-09-18 04:05	83.02	OK	11132	2026-09-18 04:06	80.11	OK
11133	2026-09-18 04:07	82.87	OK	11134	2026-09-18 04:08	83.89	OK
11135	2026-09-18 04:09	81.96	OK	11136	2026-09-18 04:10	81.88	OK
11137	2026-09-18 04:11	79.99	OK	11138	2026-09-18 04:12	80.61	OK
11139	2026-09-18 04:13	81.05	OK	11140	2026-09-18 04:14	79.61	OK
11141	2026-09-18 04:15	80.70	OK	11142	2026-09-18 04:16	80.06	OK
11143	2026-09-18 04:17	80.29	OK	11144	2026-09-18 04:18	81.25	OK
11145	2026-09-18 04:19	79.83	OK	11146	2026-09-18 04:20	78.98	OK
11147	2026-09-18 04:21	82.83	OK	11148	2026-09-18 04:22	77.73	OK
11149	2026-09-18 04:23	80.74	OK	11150	2026-09-18 04:24	81.58	OK
11151	2026-09-18 04:25	79.89	OK	11152	2026-09-18 04:26	80.37	OK
11153	2026-09-18 04:27	80.47	OK	11154	2026-09-18 04:28	82.00	OK
11155	2026-09-18 04:29	82.76	OK	11156	2026-09-18 04:30	83.44	OK
11157	2026-09-18 04:31	81.53	OK	11158	2026-09-18 04:32	78.52	OK
11159	2026-09-18 04:33	82.84	OK	11160	2026-09-18 04:34	79.23	OK
11161	2026-09-18 04:35	82.75	OK	11162	2026-09-18 04:36	82.42	OK
11163	2026-09-18 04:37	79.66	OK	11164	2026-09-18 04:38	82.74	OK
11165	2026-09-18 04:39	78.79	OK	11166	2026-09-18 04:40	80.95	OK
11167	2026-09-18 04:41	79.47	OK	11168	2026-09-18 04:42	79.54	OK
11169	2026-09-18 04:43	80.56	OK	11170	2026-09-18 04:44	81.56	OK
11171	2026-09-18 04:45	81.47	OK	11172	2026-09-18 04:46	81.63	OK
11173	2026-09-18 04:47	83.56	OK	11174	2026-09-18 04:48	80.98	OK
11175	2026-09-18 04:49	81.58	OK	11176	2026-09-18 04:50	79.89	OK
1117	2026-09-18 04:51	81.23	OK	1117	2026-09-18 04:52	82.48	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
11179	2026-09-18 04:53	81.87	OK	11180	2026-09-18 04:54	79.12	OK
11181	2026-09-18 04:55	82.61	OK	11182	2026-09-18 04:56	79.75	OK
11183	2026-09-18 04:57	83.25	OK	11184	2026-09-18 04:58	81.16	OK
11185	2026-09-18 04:59	83.08	OK	11186	2026-09-18 05:00	81.07	OK
11187	2026-09-18 05:01	81.56	OK	11188	2026-09-18 05:02	80.30	OK
11189	2026-09-18 05:03	79.58	OK	11190	2026-09-18 05:04	80.52	OK
11191	2026-09-18 05:05	80.93	OK	11192	2026-09-18 05:06	82.16	OK
11193	2026-09-18 05:07	81.75	OK	11194	2026-09-18 05:08	81.19	OK
11195	2026-09-18 05:09	81.31	OK	11196	2026-09-18 05:10	80.98	OK
11197	2026-09-18 05:11	78.84	OK	11198	2026-09-18 05:12	80.93	OK
11199	2026-09-18 05:13	82.56	OK	11200	2026-09-18 05:14	81.40	OK
11201	2026-09-18 05:15	80.99	OK	11202	2026-09-18 05:16	82.31	OK
11203	2026-09-18 05:17	81.05	OK	11204	2026-09-18 05:18	83.54	OK
11205	2026-09-18 05:19	80.30	OK	11206	2026-09-18 05:20	80.95	OK
11207	2026-09-18 05:21	82.18	OK	11208	2026-09-18 05:22	81.57	OK
11209	2026-09-18 05:23	79.90	OK	11210	2026-09-18 05:24	79.95	OK
11211	2026-09-18 05:25	80.31	OK	11212	2026-09-18 05:26	82.23	OK
11213	2026-09-18 05:27	82.62	OK	11214	2026-09-18 05:28	78.33	OK
11215	2026-09-18 05:29	80.86	OK	11216	2026-09-18 05:30	79.82	OK
11217	2026-09-18 05:31	81.10	OK	11218	2026-09-18 05:32	82.23	OK
11219	2026-09-18 05:33	80.39	OK	11220	2026-09-18 05:34	82.30	OK
11221	2026-09-18 05:35	81.97	OK	11222	2026-09-18 05:36	80.15	OK
11223	2026-09-18 05:37	78.47	OK	11224	2026-09-18 05:38	77.31	OK
11225	2026-09-18 05:39	80.18	OK	11226	2026-09-18 05:40	83.27	OK
11227	2026-09-18 05:41	83.97	OK	11228	2026-09-18 05:42	79.22	OK
11229	2026-09-18 05:43	80.43	OK	11230	2026-09-18 05:44	81.15	OK
11231	2026-09-18 05:45	79.13	OK	11232	2026-09-18 05:46	78.92	OK
11233	2026-09-18 05:47	81.24	OK	11234	2026-09-18 05:48	78.75	OK
11235	2026-09-18 05:49	81.07	OK	11236	2026-09-18 05:50	80.19	OK
1123	2026-09-18 05:51	79.89	OK	1123	2026-09-18 05:52	79.30	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
11239	2026-09-18 05:53	81.49	OK	11240	2026-09-18 05:54	81.21	OK
11241	2026-09-18 05:55	79.58	OK	11242	2026-09-18 05:56	79.99	OK
11243	2026-09-18 05:57	79.73	OK	11244	2026-09-18 05:58	78.39	OK
11245	2026-09-18 05:59	78.96	OK	11246	2026-09-18 06:00	80.29	OK
11247	2026-09-18 06:01	78.51	OK	11248	2026-09-18 06:02	80.07	OK
11249	2026-09-18 06:03	79.38	OK	11250	2026-09-18 06:04	78.50	OK
11251	2026-09-18 06:05	80.40	OK	11252	2026-09-18 06:06	79.31	OK
11253	2026-09-18 06:07	78.64	OK	11254	2026-09-18 06:08	79.47	OK
11255	2026-09-18 06:09	81.88	OK	11256	2026-09-18 06:10	76.96	OK
11257	2026-09-18 06:11	78.96	OK	11258	2026-09-18 06:12	82.01	OK
11259	2026-09-18 06:13	80.60	OK	11260	2026-09-18 06:14	80.37	OK
11261	2026-09-18 06:15	80.06	OK	11262	2026-09-18 06:16	78.92	OK
11263	2026-09-18 06:17	77.19	OK	11264	2026-09-18 06:18	79.45	OK
11265	2026-09-18 06:19	79.73	OK	11266	2026-09-18 06:20	79.04	OK
11267	2026-09-18 06:21	81.28	OK	11268	2026-09-18 06:22	79.14	OK
11269	2026-09-18 06:23	78.00	OK	11270	2026-09-18 06:24	78.95	OK
11271	2026-09-18 06:25	79.37	OK	11272	2026-09-18 06:26	77.74	OK
11273	2026-09-18 06:27	77.66	OK	11274	2026-09-18 06:28	77.77	OK
11275	2026-09-18 06:29	79.99	OK	11276	2026-09-18 06:30	81.54	OK
11277	2026-09-18 06:31	77.78	OK	11278	2026-09-18 06:32	79.64	OK
11279	2026-09-18 06:33	80.55	OK	11280	2026-09-18 06:34	79.99	OK
11281	2026-09-18 06:35	76.86	OK	11282	2026-09-18 06:36	79.52	OK
11283	2026-09-18 06:37	81.47	OK	11284	2026-09-18 06:38	81.42	OK
11285	2026-09-18 06:39	78.78	OK	11286	2026-09-18 06:40	80.67	OK
11287	2026-09-18 06:41	77.76	OK	11288	2026-09-18 06:42	78.24	OK
11289	2026-09-18 06:43	80.81	OK	11290	2026-09-18 06:44	80.22	OK
11291	2026-09-18 06:45	75.95	OK	11292	2026-09-18 06:46	79.24	OK
11293	2026-09-18 06:47	77.84	OK	11294	2026-09-18 06:48	79.75	OK
11295	2026-09-18 06:49	79.81	OK	11296	2026-09-18 06:50	79.47	OK
1129	2026-09-18 06:51	80.62	OK	1129	2026-09-18 06:52	78.70	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
11299	2026-09-18 06:53	80.09	OK	11300	2026-09-18 06:54	79.28	OK
11301	2026-09-18 06:55	80.74	OK	11302	2026-09-18 06:56	81.58	OK
11303	2026-09-18 06:57	76.11	OK	11304	2026-09-18 06:58	79.35	OK
11305	2026-09-18 06:59	78.98	OK	11306	2026-09-18 07:00	79.20	OK
11307	2026-09-18 07:01	77.76	OK	11308	2026-09-18 07:02	78.84	OK
11309	2026-09-18 07:03	80.23	OK	11310	2026-09-18 07:04	78.46	OK
11311	2026-09-18 07:05	79.04	OK	11312	2026-09-18 07:06	79.46	OK
11313	2026-09-18 07:07	79.44	OK	11314	2026-09-18 07:08	80.05	OK
11315	2026-09-18 07:09	78.09	OK	11316	2026-09-18 07:10	79.75	OK
11317	2026-09-18 07:11	77.06	OK	11318	2026-09-18 07:12	79.06	OK
11319	2026-09-18 07:13	78.51	OK	11320	2026-09-18 07:14	75.73	OK
11321	2026-09-18 07:15	77.41	OK	11322	2026-09-18 07:16	80.99	OK
11323	2026-09-18 07:17	78.70	OK	11324	2026-09-18 07:18	78.72	OK
11325	2026-09-18 07:19	77.15	OK	11326	2026-09-18 07:20	79.61	OK
11327	2026-09-18 07:21	78.30	OK	11328	2026-09-18 07:22	77.05	OK
11329	2026-09-18 07:23	77.97	OK	11330	2026-09-18 07:24	78.69	OK
11331	2026-09-18 07:25	77.94	OK	11332	2026-09-18 07:26	79.06	OK
11333	2026-09-18 07:27	79.82	OK	11334	2026-09-18 07:28	79.64	OK
11335	2026-09-18 07:29	80.29	OK	11336	2026-09-18 07:30	78.82	OK
11337	2026-09-18 07:31	79.06	OK	11338	2026-09-18 07:32	79.94	OK
11339	2026-09-18 07:33	75.37	OK	11340	2026-09-18 07:34	78.00	OK
11341	2026-09-18 07:35	76.97	OK	11342	2026-09-18 07:36	77.68	OK
11343	2026-09-18 07:37	76.80	OK	11344	2026-09-18 07:38	75.90	OK
11345	2026-09-18 07:39	77.65	OK	11346	2026-09-18 07:40	78.44	OK
11347	2026-09-18 07:41	78.20	OK	11348	2026-09-18 07:42	78.48	OK
11349	2026-09-18 07:43	78.83	OK	11350	2026-09-18 07:44	79.95	OK
11351	2026-09-18 07:45	78.47	OK	11352	2026-09-18 07:46	78.41	OK
11353	2026-09-18 07:47	78.77	OK	11354	2026-09-18 07:48	76.88	OK
11355	2026-09-18 07:49	78.85	OK	11356	2026-09-18 07:50	79.14	OK
1135	2026-09-18 07:51	80.33	OK	1135	2026-09-18 07:52	77.12	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
11359	2026-09-18 07:53	78.14	OK	11360	2026-09-18 07:54	77.59	OK
11361	2026-09-18 07:55	75.18	OK	11362	2026-09-18 07:56	80.06	OK
11363	2026-09-18 07:57	78.43	OK	11364	2026-09-18 07:58	78.73	OK
11365	2026-09-18 07:59	77.65	OK	11366	2026-09-18 08:00	77.82	OK
11367	2026-09-18 08:01	76.78	OK	11368	2026-09-18 08:02	78.25	OK
11369	2026-09-18 08:03	76.46	OK	11370	2026-09-18 08:04	77.34	OK
11371	2026-09-18 08:05	75.66	OK	11372	2026-09-18 08:06	80.53	OK
11373	2026-09-18 08:07	76.59	OK	11374	2026-09-18 08:08	77.52	OK
11375	2026-09-18 08:09	78.28	OK	11376	2026-09-18 08:10	76.38	OK
11377	2026-09-18 08:11	75.83	OK	11378	2026-09-18 08:12	77.27	OK
11379	2026-09-18 08:13	75.01	OK	11380	2026-09-18 08:14	75.92	OK
11381	2026-09-18 08:15	76.13	OK	11382	2026-09-18 08:16	75.24	OK
11383	2026-09-18 08:17	76.07	OK	11384	2026-09-18 08:18	75.36	OK
11385	2026-09-18 08:19	74.22	OK	11386	2026-09-18 08:20	76.62	OK
11387	2026-09-18 08:21	77.62	OK	11388	2026-09-18 08:22	76.43	OK
11389	2026-09-18 08:23	74.71	OK	11390	2026-09-18 08:24	79.25	OK
11391	2026-09-18 08:25	75.66	OK	11392	2026-09-18 08:26	76.36	OK
11393	2026-09-18 08:27	76.60	OK	11394	2026-09-18 08:28	77.74	OK
11395	2026-09-18 08:29	76.77	OK	11396	2026-09-18 08:30	77.08	OK
11397	2026-09-18 08:31	77.41	OK	11398	2026-09-18 08:32	76.53	OK
11399	2026-09-18 08:33	76.16	OK	11400	2026-09-18 08:34	76.18	OK
11401	2026-09-18 08:35	76.08	OK	11402	2026-09-18 08:36	76.79	OK
11403	2026-09-18 08:37	76.81	OK	11404	2026-09-18 08:38	76.28	OK
11405	2026-09-18 08:39	75.48	OK	11406	2026-09-18 08:40	74.16	OK
11407	2026-09-18 08:41	78.10	OK	11408	2026-09-18 08:42	75.92	OK
11409	2026-09-18 08:43	76.47	OK	11410	2026-09-18 08:44	76.75	OK
11411	2026-09-18 08:45	75.90	OK	11412	2026-09-18 08:46	77.36	OK
11413	2026-09-18 08:47	77.86	OK	11414	2026-09-18 08:48	76.25	OK
11415	2026-09-18 08:49	74.58	OK	11416	2026-09-18 08:50	75.58	OK
11417	2026-09-18 08:51	75.26	OK	11418	2026-09-18 08:52	74.76	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
11419	2026-09-18 08:53	75.37	OK	11420	2026-09-18 08:54	77.05	OK
11421	2026-09-18 08:55	76.39	OK	11422	2026-09-18 08:56	78.04	OK
11423	2026-09-18 08:57	74.91	OK	11424	2026-09-18 08:58	77.19	OK
11425	2026-09-18 08:59	75.60	OK	11426	2026-09-18 09:00	74.73	OK
11427	2026-09-18 09:01	76.34	OK	11428	2026-09-18 09:02	79.17	OK
11429	2026-09-18 09:03	77.20	OK	11430	2026-09-18 09:04	75.49	OK
11431	2026-09-18 09:05	77.55	OK	11432	2026-09-18 09:06	75.13	OK
11433	2026-09-18 09:07	76.83	OK	11434	2026-09-18 09:08	77.28	OK
11435	2026-09-18 09:09	75.77	OK	11436	2026-09-18 09:10	77.13	OK
11437	2026-09-18 09:11	76.81	OK	11438	2026-09-18 09:12	76.01	OK
11439	2026-09-18 09:13	75.53	OK	11440	2026-09-18 09:14	76.06	OK
11441	2026-09-18 09:15	76.03	OK	11442	2026-09-18 09:16	75.23	OK
11443	2026-09-18 09:17	75.94	OK	11444	2026-09-18 09:18	76.73	OK
11445	2026-09-18 09:19	74.54	OK	11446	2026-09-18 09:20	76.74	OK
11447	2026-09-18 09:21	75.23	OK	11448	2026-09-18 09:22	73.23	OK
11449	2026-09-18 09:23	73.81	OK	11450	2026-09-18 09:24	75.37	OK
11451	2026-09-18 09:25	77.76	OK	11452	2026-09-18 09:26	76.32	OK
11453	2026-09-18 09:27	75.34	OK	11454	2026-09-18 09:28	75.21	OK
11455	2026-09-18 09:29	74.60	OK	11456	2026-09-18 09:30	75.18	OK
11457	2026-09-18 09:31	77.44	OK	11458	2026-09-18 09:32	77.37	OK
11459	2026-09-18 09:33	76.78	OK	11460	2026-09-18 09:34	75.26	OK
11461	2026-09-18 09:35	76.67	OK	11462	2026-09-18 09:36	76.23	OK
11463	2026-09-18 09:37	75.37	OK	11464	2026-09-18 09:38	73.96	OK
11465	2026-09-18 09:39	77.25	OK	11466	2026-09-18 09:40	75.05	OK
11467	2026-09-18 09:41	75.23	OK	11468	2026-09-18 09:42	76.27	OK
11469	2026-09-18 09:43	74.29	OK	11470	2026-09-18 09:44	74.77	OK
11471	2026-09-18 09:45	76.36	OK	11472	2026-09-18 09:46	75.22	OK
11473	2026-09-18 09:47	74.74	OK	11474	2026-09-18 09:48	74.48	OK
11475	2026-09-18 09:49	74.84	OK	11476	2026-09-18 09:50	75.41	OK
1147	2026-09-18 09:51	72.98	OK	1147	2026-09-18 09:52	75.67	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
11479	2026-09-18 09:53	74.51	OK	11480	2026-09-18 09:54	73.32	OK
11481	2026-09-18 09:55	75.23	OK	11482	2026-09-18 09:56	74.78	OK
11483	2026-09-18 09:57	75.37	OK	11484	2026-09-18 09:58	74.55	OK
11485	2026-09-18 09:59	74.53	OK	11486	2026-09-18 10:00	76.71	OK
11487	2026-09-18 10:01	74.94	OK	11488	2026-09-18 10:02	74.86	OK
11489	2026-09-18 10:03	74.50	OK	11490	2026-09-18 10:04	75.17	OK
11491	2026-09-18 10:05	77.40	OK	11492	2026-09-18 10:06	76.46	OK
11493	2026-09-18 10:07	73.30	OK	11494	2026-09-18 10:08	75.90	OK
11495	2026-09-18 10:09	75.18	OK	11496	2026-09-18 10:10	72.87	OK
11497	2026-09-18 10:11	74.44	OK	11498	2026-09-18 10:12	74.44	OK
11499	2026-09-18 10:13	77.13	OK	11500	2026-09-18 10:14	72.64	OK
11501	2026-09-18 10:15	72.85	OK	11502	2026-09-18 10:16	77.11	OK
11503	2026-09-18 10:17	76.18	OK	11504	2026-09-18 10:18	72.89	OK
11505	2026-09-18 10:19	73.97	OK	11506	2026-09-18 10:20	74.85	OK
11507	2026-09-18 10:21	73.12	OK	11508	2026-09-18 10:22	75.68	OK
11509	2026-09-18 10:23	73.60	OK	11510	2026-09-18 10:24	74.84	OK
11511	2026-09-18 10:25	74.44	OK	11512	2026-09-18 10:26	73.10	OK
11513	2026-09-18 10:27	76.99	OK	11514	2026-09-18 10:28	74.89	OK
11515	2026-09-18 10:29	74.81	OK	11516	2026-09-18 10:30	74.48	OK
11517	2026-09-18 10:31	73.31	OK	11518	2026-09-18 10:32	74.23	OK
11519	2026-09-18 10:33	75.23	OK	11520	2026-09-18 10:34	74.79	OK
11521	2026-09-18 10:35	73.14	OK	11522	2026-09-18 10:36	73.81	OK
11523	2026-09-18 10:37	74.16	OK	11524	2026-09-18 10:38	74.85	OK
11525	2026-09-18 10:39	75.94	OK	11526	2026-09-18 10:40	73.85	OK
11527	2026-09-18 10:41	75.00	OK	11528	2026-09-18 10:42	77.07	OK
11529	2026-09-18 10:43	73.05	OK	11530	2026-09-18 10:44	74.17	OK
11531	2026-09-18 10:45	72.60	OK	11532	2026-09-18 10:46	73.78	OK
11533	2026-09-18 10:47	72.74	OK	11534	2026-09-18 10:48	73.88	OK
11535	2026-09-18 10:49	73.73	OK	11536	2026-09-18 10:50	76.09	OK
1153	2026-09-18 10:51	73.11	OK	1153	2026-09-18 10:52	74.48	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
11539	2026-09-18 10:53	75.04	OK	11540	2026-09-18 10:54	72.71	OK
11541	2026-09-18 10:55	74.85	OK	11542	2026-09-18 10:56	72.35	OK
11543	2026-09-18 10:57	70.83	OK	11544	2026-09-18 10:58	73.96	OK
11545	2026-09-18 10:59	73.00	OK	11546	2026-09-18 11:00	75.17	OK
11547	2026-09-18 11:01	74.35	OK	11548	2026-09-18 11:02	71.86	OK
11549	2026-09-18 11:03	73.06	OK	11550	2026-09-18 11:04	75.26	OK
11551	2026-09-18 11:05	73.16	OK	11552	2026-09-18 11:06	71.39	OK
11553	2026-09-18 11:07	71.15	OK	11554	2026-09-18 11:08	75.47	OK
11555	2026-09-18 11:09	74.39	OK	11556	2026-09-18 11:10	75.48	OK
11557	2026-09-18 11:11	71.52	OK	11558	2026-09-18 11:12	73.15	OK
11559	2026-09-18 11:13	73.50	OK	11560	2026-09-18 11:14	74.19	OK
11561	2026-09-18 11:15	73.73	OK	11562	2026-09-18 11:16	71.86	OK
11563	2026-09-18 11:17	76.18	OK	11564	2026-09-18 11:18	72.86	OK
11565	2026-09-18 11:19	74.98	OK	11566	2026-09-18 11:20	74.65	OK
11567	2026-09-18 11:21	70.83	OK	11568	2026-09-18 11:22	74.96	OK
11569	2026-09-18 11:23	74.46	OK	11570	2026-09-18 11:24	72.76	OK
11571	2026-09-18 11:25	72.17	OK	11572	2026-09-18 11:26	71.90	OK
11573	2026-09-18 11:27	74.88	OK	11574	2026-09-18 11:28	70.65	OK
11575	2026-09-18 11:29	71.94	OK	11576	2026-09-18 11:30	73.67	OK
11577	2026-09-18 11:31	75.99	OK	11578	2026-09-18 11:32	74.59	OK
11579	2026-09-18 11:33	72.16	OK	11580	2026-09-18 11:34	71.84	OK
11581	2026-09-18 11:35	73.76	OK	11582	2026-09-18 11:36	74.39	OK
11583	2026-09-18 11:37	73.10	OK	11584	2026-09-18 11:38	72.90	OK
11585	2026-09-18 11:39	72.24	OK	11586	2026-09-18 11:40	72.36	OK
11587	2026-09-18 11:41	71.97	OK	11588	2026-09-18 11:42	72.85	OK
11589	2026-09-18 11:43	74.03	OK	11590	2026-09-18 11:44	71.43	OK
11591	2026-09-18 11:45	74.88	OK	11592	2026-09-18 11:46	74.08	OK
11593	2026-09-18 11:47	71.38	OK	11594	2026-09-18 11:48	71.31	OK
11595	2026-09-18 11:49	73.86	OK	11596	2026-09-18 11:50	75.94	OK
1159	2026-09-18 11:51	71.74	OK	1159	2026-09-18 11:52	71.89	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
11599	2026-09-18 11:53	73.67	OK	11600	2026-09-18 11:54	71.55	OK
11601	2026-09-18 11:55	72.82	OK	11602	2026-09-18 11:56	72.45	OK
11603	2026-09-18 11:57	71.51	OK	11604	2026-09-18 11:58	73.01	OK
11605	2026-09-18 11:59	72.31	OK	11606	2026-09-18 12:00	73.83	OK
11607	2026-09-18 12:01	72.11	OK	11608	2026-09-18 12:02	71.97	OK
11609	2026-09-18 12:03	71.33	OK	11610	2026-09-18 12:04	72.22	OK
11611	2026-09-18 12:05	70.34	OK	11612	2026-09-18 12:06	72.80	OK
11613	2026-09-18 12:07	72.70	OK	11614	2026-09-18 12:08	74.00	OK
11615	2026-09-18 12:09	73.75	OK	11616	2026-09-18 12:10	72.01	OK
11617	2026-09-18 12:11	70.57	OK	11618	2026-09-18 12:12	72.06	OK
11619	2026-09-18 12:13	72.42	OK	11620	2026-09-18 12:14	72.14	OK
11621	2026-09-18 12:15	71.96	OK	11622	2026-09-18 12:16	73.41	OK
11623	2026-09-18 12:17	72.89	OK	11624	2026-09-18 12:18	74.19	OK
11625	2026-09-18 12:19	73.57	OK	11626	2026-09-18 12:20	74.44	OK
11627	2026-09-18 12:21	73.63	OK	11628	2026-09-18 12:22	71.62	OK
11629	2026-09-18 12:23	73.61	OK	11630	2026-09-18 12:24	70.52	OK
11631	2026-09-18 12:25	73.91	OK	11632	2026-09-18 12:26	73.78	OK
11633	2026-09-18 12:27	75.24	OK	11634	2026-09-18 12:28	70.78	OK
11635	2026-09-18 12:29	70.13	OK	11636	2026-09-18 12:30	71.55	OK
11637	2026-09-18 12:31	74.08	OK	11638	2026-09-18 12:32	71.74	OK
11639	2026-09-18 12:33	72.70	OK	11640	2026-09-18 12:34	73.08	OK
11641	2026-09-18 12:35	73.59	OK	11642	2026-09-18 12:36	71.60	OK
11643	2026-09-18 12:37	72.53	OK	11644	2026-09-18 12:38	71.38	OK
11645	2026-09-18 12:39	69.54	OK	11646	2026-09-18 12:40	70.92	OK
11647	2026-09-18 12:41	74.61	OK	11648	2026-09-18 12:42	70.99	OK
11649	2026-09-18 12:43	71.71	OK	11650	2026-09-18 12:44	70.75	OK
11651	2026-09-18 12:45	74.99	OK	11652	2026-09-18 12:46	73.47	OK
11653	2026-09-18 12:47	70.91	OK	11654	2026-09-18 12:48	71.34	OK
11655	2026-09-18 12:49	69.37	OK	11656	2026-09-18 12:50	70.80	OK
1165	2026-09-18 12:51	71.69	OK	1165	2026-09-18 12:52	73.58	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
11659	2026-09-18 12:53	71.70	OK	11660	2026-09-18 12:54	72.39	OK
11661	2026-09-18 12:55	73.21	OK	11662	2026-09-18 12:56	69.49	OK
11663	2026-09-18 12:57	74.12	OK	11664	2026-09-18 12:58	72.63	OK
11665	2026-09-18 12:59	69.63	OK	11666	2026-09-18 13:00	71.46	OK
11667	2026-09-18 13:01	74.38	OK	11668	2026-09-18 13:02	72.63	OK
11669	2026-09-18 13:03	71.83	OK	11670	2026-09-18 13:04	71.51	OK
11671	2026-09-18 13:05	72.75	OK	11672	2026-09-18 13:06	73.55	OK
11673	2026-09-18 13:07	72.67	OK	11674	2026-09-18 13:08	71.58	OK
11675	2026-09-18 13:09	70.49	OK	11676	2026-09-18 13:10	72.27	OK
11677	2026-09-18 13:11	71.73	OK	11678	2026-09-18 13:12	72.10	OK
11679	2026-09-18 13:13	72.59	OK	11680	2026-09-18 13:14	72.77	OK
11681	2026-09-18 13:15	69.57	OK	11682	2026-09-18 13:16	71.89	OK
11683	2026-09-18 13:17	73.06	OK	11684	2026-09-18 13:18	72.22	OK
11685	2026-09-18 13:19	72.40	OK	11686	2026-09-18 13:20	70.84	OK
11687	2026-09-18 13:21	72.31	OK	11688	2026-09-18 13:22	73.42	OK
11689	2026-09-18 13:23	69.64	OK	11690	2026-09-18 13:24	71.10	OK
11691	2026-09-18 13:25	70.05	OK	11692	2026-09-18 13:26	68.87	OK
11693	2026-09-18 13:27	72.54	OK	11694	2026-09-18 13:28	73.15	OK
11695	2026-09-18 13:29	68.73	OK	11696	2026-09-18 13:30	70.83	OK
11697	2026-09-18 13:31	70.67	OK	11698	2026-09-18 13:32	73.58	OK
11699	2026-09-18 13:33	70.18	OK	11700	2026-09-18 13:34	71.58	OK
11701	2026-09-18 13:35	70.99	OK	11702	2026-09-18 13:36	71.40	OK
11703	2026-09-18 13:37	72.70	OK	11704	2026-09-18 13:38	71.20	OK
11705	2026-09-18 13:39	70.14	OK	11706	2026-09-18 13:40	73.32	OK
11707	2026-09-18 13:41	72.18	OK	11708	2026-09-18 13:42	70.39	OK
11709	2026-09-18 13:43	69.60	OK	11710	2026-09-18 13:44	70.46	OK
11711	2026-09-18 13:45	71.09	OK	11712	2026-09-18 13:46	72.94	OK
11713	2026-09-18 13:47	73.69	OK	11714	2026-09-18 13:48	72.13	OK
11715	2026-09-18 13:49	70.74	OK	11716	2026-09-18 13:50	70.25	OK
11717	2026-09-18 13:51	70.32	OK	11717	2026-09-18 13:52	71.91	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
11719	2026-09-18 13:53	71.12	OK	11720	2026-09-18 13:54	70.30	OK
11721	2026-09-18 13:55	72.72	OK	11722	2026-09-18 13:56	71.48	OK
11723	2026-09-18 13:57	71.19	OK	11724	2026-09-18 13:58	74.91	OK
11725	2026-09-18 13:59	72.62	OK	11726	2026-09-18 14:00	71.51	OK
11727	2026-09-18 14:01	70.55	OK	11728	2026-09-18 14:02	71.47	OK
11729	2026-09-18 14:03	72.35	OK	11730	2026-09-18 14:04	69.61	OK
11731	2026-09-18 14:05	69.56	OK	11732	2026-09-18 14:06	73.99	OK
11733	2026-09-18 14:07	71.54	OK	11734	2026-09-18 14:08	69.44	OK
11735	2026-09-18 14:09	70.56	OK	11736	2026-09-18 14:10	71.83	OK
11737	2026-09-18 14:11	70.72	OK	11738	2026-09-18 14:12	70.81	OK
11739	2026-09-18 14:13	73.18	OK	11740	2026-09-18 14:14	74.19	OK
11741	2026-09-18 14:15	71.50	OK	11742	2026-09-18 14:16	72.50	OK
11743	2026-09-18 14:17	71.28	OK	11744	2026-09-18 14:18	70.54	OK
11745	2026-09-18 14:19	70.51	OK	11746	2026-09-18 14:20	70.23	OK
11747	2026-09-18 14:21	72.26	OK	11748	2026-09-18 14:22	73.35	OK
11749	2026-09-18 14:23	70.25	OK	11750	2026-09-18 14:24	69.39	OK
11751	2026-09-18 14:25	71.06	OK	11752	2026-09-18 14:26	70.44	OK
11753	2026-09-18 14:27	69.84	OK	11754	2026-09-18 14:28	72.45	OK
11755	2026-09-18 14:29	72.03	OK	11756	2026-09-18 14:30	70.48	OK
11757	2026-09-18 14:31	70.94	OK	11758	2026-09-18 14:32	71.64	OK
11759	2026-09-18 14:33	71.90	OK	11760	2026-09-18 14:34	71.45	OK
11761	2026-09-18 14:35	71.88	OK	11762	2026-09-18 14:36	72.93	OK
11763	2026-09-18 14:37	71.23	OK	11764	2026-09-18 14:38	70.83	OK
11765	2026-09-18 14:39	70.60	OK	11766	2026-09-18 14:40	72.83	OK
11767	2026-09-18 14:41	73.15	OK	11768	2026-09-18 14:42	72.45	OK
11769	2026-09-18 14:43	71.03	OK	11770	2026-09-18 14:44	71.82	OK
11771	2026-09-18 14:45	69.99	OK	11772	2026-09-18 14:46	70.17	OK
11773	2026-09-18 14:47	71.95	OK	11774	2026-09-18 14:48	72.63	OK
11775	2026-09-18 14:49	69.53	OK	11776	2026-09-18 14:50	71.66	OK
11777	2026-09-18 14:51	71.13	OK	11777	2026-09-18 14:52	70.64	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
11779	2026-09-18 14:53	70.32	OK	11780	2026-09-18 14:54	70.13	OK
11781	2026-09-18 14:55	70.92	OK	11782	2026-09-18 14:56	70.72	OK
11783	2026-09-18 14:57	69.99	OK	11784	2026-09-18 14:58	70.66	OK
11785	2026-09-18 14:59	73.23	OK	11786	2026-09-18 15:00	70.42	OK
11787	2026-09-18 15:01	72.17	OK	11788	2026-09-18 15:02	70.60	OK
11789	2026-09-18 15:03	70.97	OK	11790	2026-09-18 15:04	68.41	OK
11791	2026-09-18 15:05	70.22	OK	11792	2026-09-18 15:06	72.57	OK
11793	2026-09-18 15:07	71.40	OK	11794	2026-09-18 15:08	72.72	OK
11795	2026-09-18 15:09	71.50	OK	11796	2026-09-18 15:10	71.41	OK
11797	2026-09-18 15:11	71.74	OK	11798	2026-09-18 15:12	70.63	OK
11799	2026-09-18 15:13	70.53	OK	11800	2026-09-18 15:14	70.81	OK
11801	2026-09-18 15:15	71.73	OK	11802	2026-09-18 15:16	70.90	OK
11803	2026-09-18 15:17	68.97	OK	11804	2026-09-18 15:18	73.35	OK
11805	2026-09-18 15:19	71.60	OK	11806	2026-09-18 15:20	71.85	OK
11807	2026-09-18 15:21	73.31	OK	11808	2026-09-18 15:22	71.98	OK
11809	2026-09-18 15:23	69.28	OK	11810	2026-09-18 15:24	69.59	OK
11811	2026-09-18 15:25	73.97	OK	11812	2026-09-18 15:26	70.79	OK
11813	2026-09-18 15:27	70.80	OK	11814	2026-09-18 15:28	71.61	OK
11815	2026-09-18 15:29	70.72	OK	11816	2026-09-18 15:30	70.84	OK
11817	2026-09-18 15:31	73.34	OK	11818	2026-09-18 15:32	72.63	OK
11819	2026-09-18 15:33	69.61	OK	11820	2026-09-18 15:34	72.06	OK
11821	2026-09-18 15:35	74.36	OK	11822	2026-09-18 15:36	71.10	OK
11823	2026-09-18 15:37	72.27	OK	11824	2026-09-18 15:38	72.91	OK
11825	2026-09-18 15:39	72.65	OK	11826	2026-09-18 15:40	71.91	OK
11827	2026-09-18 15:41	70.85	OK	11828	2026-09-18 15:42	73.29	OK
11829	2026-09-18 15:43	71.53	OK	11830	2026-09-18 15:44	72.25	OK
11831	2026-09-18 15:45	70.45	OK	11832	2026-09-18 15:46	71.11	OK
11833	2026-09-18 15:47	73.54	OK	11834	2026-09-18 15:48	73.59	OK
11835	2026-09-18 15:49	70.57	OK	11836	2026-09-18 15:50	74.22	OK
1183	2026-09-18 15:51	73.36	OK	1183	2026-09-18 15:52	70.82	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
11839	2026-09-18 15:53	69.66	OK	11840	2026-09-18 15:54	71.84	OK
11841	2026-09-18 15:55	71.95	OK	11842	2026-09-18 15:56	72.89	OK
11843	2026-09-18 15:57	73.26	OK	11844	2026-09-18 15:58	70.03	OK
11845	2026-09-18 15:59	69.38	OK	11846	2026-09-18 16:00	70.31	OK
11847	2026-09-18 16:01	71.80	OK	11848	2026-09-18 16:02	71.51	OK
11849	2026-09-18 16:03	69.81	OK	11850	2026-09-18 16:04	70.50	OK
11851	2026-09-18 16:05	73.37	OK	11852	2026-09-18 16:06	72.94	OK
11853	2026-09-18 16:07	71.59	OK	11854	2026-09-18 16:08	71.81	OK
11855	2026-09-18 16:09	71.77	OK	11856	2026-09-18 16:10	71.29	OK
11857	2026-09-18 16:11	72.33	OK	11858	2026-09-18 16:12	73.40	OK
11859	2026-09-18 16:13	72.65	OK	11860	2026-09-18 16:14	70.06	OK
11861	2026-09-18 16:15	69.52	OK	11862	2026-09-18 16:16	71.39	OK
11863	2026-09-18 16:17	73.57	OK	11864	2026-09-18 16:18	70.97	OK
11865	2026-09-18 16:19	71.94	OK	11866	2026-09-18 16:20	71.54	OK
11867	2026-09-18 16:21	71.47	OK	11868	2026-09-18 16:22	72.22	OK
11869	2026-09-18 16:23	70.55	OK	11870	2026-09-18 16:24	72.68	OK
11871	2026-09-18 16:25	72.27	OK	11872	2026-09-18 16:26	70.96	OK
11873	2026-09-18 16:27	73.22	OK	11874	2026-09-18 16:28	71.46	OK
11875	2026-09-18 16:29	69.50	OK	11876	2026-09-18 16:30	73.03	OK
11877	2026-09-18 16:31	71.28	OK	11878	2026-09-18 16:32	71.28	OK
11879	2026-09-18 16:33	71.00	OK	11880	2026-09-18 16:34	69.53	OK
11881	2026-09-18 16:35	71.14	OK	11882	2026-09-18 16:36	72.84	OK
11883	2026-09-18 16:37	72.00	OK	11884	2026-09-18 16:38	69.24	OK
11885	2026-09-18 16:39	71.54	OK	11886	2026-09-18 16:40	68.66	OK
11887	2026-09-18 16:41	71.93	OK	11888	2026-09-18 16:42	71.98	OK
11889	2026-09-18 16:43	73.25	OK	11890	2026-09-18 16:44	71.01	OK
11891	2026-09-18 16:45	72.22	OK	11892	2026-09-18 16:46	72.30	OK
11893	2026-09-18 16:47	69.21	OK	11894	2026-09-18 16:48	71.69	OK
11895	2026-09-18 16:49	72.41	OK	11896	2026-09-18 16:50	70.48	OK
1189	2026-09-18 16:51	71.80	OK	1189	2026-09-18 16:52	69.64	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
11899	2026-09-18 16:53	72.60	OK	11900	2026-09-18 16:54	74.26	OK
11901	2026-09-18 16:55	71.19	OK	11902	2026-09-18 16:56	69.66	OK
11903	2026-09-18 16:57	72.40	OK	11904	2026-09-18 16:58	72.86	OK
11905	2026-09-18 16:59	71.42	OK	11906	2026-09-18 17:00	71.55	OK
11907	2026-09-18 17:01	71.12	OK	11908	2026-09-18 17:02	72.93	OK
11909	2026-09-18 17:03	72.04	OK	11910	2026-09-18 17:04	71.92	OK
11911	2026-09-18 17:05	73.67	OK	11912	2026-09-18 17:06	74.20	OK
11913	2026-09-18 17:07	72.09	OK	11914	2026-09-18 17:08	71.26	OK
11915	2026-09-18 17:09	71.01	OK	11916	2026-09-18 17:10	71.68	OK
11917	2026-09-18 17:11	74.88	OK	11918	2026-09-18 17:12	73.23	OK
11919	2026-09-18 17:13	72.10	OK	11920	2026-09-18 17:14	74.56	OK
11921	2026-09-18 17:15	71.96	OK	11922	2026-09-18 17:16	73.85	OK
11923	2026-09-18 17:17	73.83	OK	11924	2026-09-18 17:18	72.66	OK
11925	2026-09-18 17:19	74.33	OK	11926	2026-09-18 17:20	71.91	OK
11927	2026-09-18 17:21	71.74	OK	11928	2026-09-18 17:22	70.07	OK
11929	2026-09-18 17:23	71.09	OK	11930	2026-09-18 17:24	71.97	OK
11931	2026-09-18 17:25	71.84	OK	11932	2026-09-18 17:26	71.91	OK
11933	2026-09-18 17:27	74.04	OK	11934	2026-09-18 17:28	71.92	OK
11935	2026-09-18 17:29	70.56	OK	11936	2026-09-18 17:30	69.75	OK
11937	2026-09-18 17:31	73.49	OK	11938	2026-09-18 17:32	73.14	OK
11939	2026-09-18 17:33	72.61	OK	11940	2026-09-18 17:34	71.67	OK
11941	2026-09-18 17:35	74.58	OK	11942	2026-09-18 17:36	72.61	OK
11943	2026-09-18 17:37	73.81	OK	11944	2026-09-18 17:38	73.64	OK
11945	2026-09-18 17:39	71.50	OK	11946	2026-09-18 17:40	71.77	OK
11947	2026-09-18 17:41	71.54	OK	11948	2026-09-18 17:42	73.37	OK
11949	2026-09-18 17:43	71.58	OK	11950	2026-09-18 17:44	72.88	OK
11951	2026-09-18 17:45	72.52	OK	11952	2026-09-18 17:46	73.39	OK
11953	2026-09-18 17:47	74.55	OK	11954	2026-09-18 17:48	75.87	OK
11955	2026-09-18 17:49	71.00	OK	11956	2026-09-18 17:50	72.93	OK
1195	2026-09-18 17:51	75.41	OK	1195	2026-09-18 17:52	72.70	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
11959	2026-09-18 17:53	72.49	OK	11960	2026-09-18 17:54	72.72	OK
11961	2026-09-18 17:55	73.94	OK	11962	2026-09-18 17:56	72.93	OK
11963	2026-09-18 17:57	73.44	OK	11964	2026-09-18 17:58	72.91	OK
11965	2026-09-18 17:59	71.63	OK	11966	2026-09-18 18:00	71.68	OK
11967	2026-09-18 18:01	72.11	OK	11968	2026-09-18 18:02	69.88	OK
11969	2026-09-18 18:03	74.14	OK	11970	2026-09-18 18:04	72.78	OK
11971	2026-09-18 18:05	74.60	OK	11972	2026-09-18 18:06	74.46	OK
11973	2026-09-18 18:07	74.52	OK	11974	2026-09-18 18:08	74.71	OK
11975	2026-09-18 18:09	73.36	OK	11976	2026-09-18 18:10	71.08	OK
11977	2026-09-18 18:11	73.66	OK	11978	2026-09-18 18:12	71.39	OK
11979	2026-09-18 18:13	72.30	OK	11980	2026-09-18 18:14	74.86	OK
11981	2026-09-18 18:15	72.94	OK	11982	2026-09-18 18:16	72.21	OK
11983	2026-09-18 18:17	73.44	OK	11984	2026-09-18 18:18	73.42	OK
11985	2026-09-18 18:19	72.32	OK	11986	2026-09-18 18:20	73.85	OK
11987	2026-09-18 18:21	74.97	OK	11988	2026-09-18 18:22	72.80	OK
11989	2026-09-18 18:23	71.75	OK	11990	2026-09-18 18:24	72.17	OK
11991	2026-09-18 18:25	73.23	OK	11992	2026-09-18 18:26	72.35	OK
11993	2026-09-18 18:27	74.04	OK	11994	2026-09-18 18:28	73.29	OK
11995	2026-09-18 18:29	73.18	OK	11996	2026-09-18 18:30	70.83	OK
11997	2026-09-18 18:31	76.19	OK	11998	2026-09-18 18:32	73.91	OK
11999	2026-09-18 18:33	75.09	OK	12000	2026-09-18 18:34	75.27	OK
12001	2026-09-18 18:35	73.36	OK	12002	2026-09-18 18:36	74.20	OK
12003	2026-09-18 18:37	72.82	OK	12004	2026-09-18 18:38	72.99	OK
12005	2026-09-18 18:39	72.57	OK	12006	2026-09-18 18:40	73.70	OK
12007	2026-09-18 18:41	73.44	OK	12008	2026-09-18 18:42	73.93	OK
12009	2026-09-18 18:43	76.56	OK	12010	2026-09-18 18:44	73.21	OK
12011	2026-09-18 18:45	76.77	OK	12012	2026-09-18 18:46	74.44	OK
12013	2026-09-18 18:47	74.17	OK	12014	2026-09-18 18:48	73.52	OK
12015	2026-09-18 18:49	71.70	OK	12016	2026-09-18 18:50	75.37	OK
1201	2026-09-18 18:51	72.45	OK	1201	2026-09-18 18:52	74.54	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
12019	2026-09-18 18:53	72.31	OK	12020	2026-09-18 18:54	75.23	OK
12021	2026-09-18 18:55	72.19	OK	12022	2026-09-18 18:56	73.71	OK
12023	2026-09-18 18:57	73.96	OK	12024	2026-09-18 18:58	74.88	OK
12025	2026-09-18 18:59	73.57	OK	12026	2026-09-18 19:00	76.09	OK
12027	2026-09-18 19:01	73.07	OK	12028	2026-09-18 19:02	73.63	OK
12029	2026-09-18 19:03	75.20	OK	12030	2026-09-18 19:04	74.32	OK
12031	2026-09-18 19:05	71.18	OK	12032	2026-09-18 19:06	75.59	OK
12033	2026-09-18 19:07	73.66	OK	12034	2026-09-18 19:08	75.52	OK
12035	2026-09-18 19:09	72.16	OK	12036	2026-09-18 19:10	75.23	OK
12037	2026-09-18 19:11	74.54	OK	12038	2026-09-18 19:12	74.61	OK
12039	2026-09-18 19:13	74.67	OK	12040	2026-09-18 19:14	73.67	OK
12041	2026-09-18 19:15	74.28	OK	12042	2026-09-18 19:16	72.77	OK
12043	2026-09-18 19:17	76.67	OK	12044	2026-09-18 19:18	74.71	OK
12045	2026-09-18 19:19	75.55	OK	12046	2026-09-18 19:20	74.39	OK
12047	2026-09-18 19:21	76.97	OK	12048	2026-09-18 19:22	75.08	OK
12049	2026-09-18 19:23	74.67	OK	12050	2026-09-18 19:24	76.93	OK
12051	2026-09-18 19:25	75.42	OK	12052	2026-09-18 19:26	74.33	OK
12053	2026-09-18 19:27	75.30	OK	12054	2026-09-18 19:28	74.52	OK
12055	2026-09-18 19:29	76.30	OK	12056	2026-09-18 19:30	72.94	OK
12057	2026-09-18 19:31	77.20	OK	12058	2026-09-18 19:32	77.00	OK
12059	2026-09-18 19:33	76.56	OK	12060	2026-09-18 19:34	74.62	OK
12061	2026-09-18 19:35	75.44	OK	12062	2026-09-18 19:36	74.75	OK
12063	2026-09-18 19:37	74.65	OK	12064	2026-09-18 19:38	74.75	OK
12065	2026-09-18 19:39	73.42	OK	12066	2026-09-18 19:40	76.25	OK
12067	2026-09-18 19:41	72.78	OK	12068	2026-09-18 19:42	75.91	OK
12069	2026-09-18 19:43	72.99	OK	12070	2026-09-18 19:44	76.55	OK
12071	2026-09-18 19:45	73.84	OK	12072	2026-09-18 19:46	73.40	OK
12073	2026-09-18 19:47	74.56	OK	12074	2026-09-18 19:48	74.91	OK
12075	2026-09-18 19:49	74.48	OK	12076	2026-09-18 19:50	75.86	OK
1207	2026-09-18 19:51	75.31	OK	1207	2026-09-18 19:52	75.85	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
12079	2026-09-18 19:53	76.99	OK	12080	2026-09-18 19:54	75.58	OK
12081	2026-09-18 19:55	75.97	OK	12082	2026-09-18 19:56	77.46	OK
12083	2026-09-18 19:57	72.93	OK	12084	2026-09-18 19:58	76.04	OK
12085	2026-09-18 19:59	75.10	OK	12086	2026-09-18 20:00	74.67	OK
12087	2026-09-18 20:01	75.63	OK	12088	2026-09-18 20:02	76.02	OK
12089	2026-09-18 20:03	77.53	OK	12090	2026-09-18 20:04	74.85	OK
12091	2026-09-18 20:05	75.61	OK	12092	2026-09-18 20:06	75.30	OK
12093	2026-09-18 20:07	76.59	OK	12094	2026-09-18 20:08	75.23	OK
12095	2026-09-18 20:09	76.62	OK	12096	2026-09-18 20:10	76.77	OK
12097	2026-09-18 20:11	76.23	OK	12098	2026-09-18 20:12	76.56	OK
12099	2026-09-18 20:13	76.51	OK	12100	2026-09-18 20:14	72.52	OK
12101	2026-09-18 20:15	73.41	OK	12102	2026-09-18 20:16	75.84	OK
12103	2026-09-18 20:17	76.68	OK	12104	2026-09-18 20:18	74.76	OK
12105	2026-09-18 20:19	76.48	OK	12106	2026-09-18 20:20	77.90	OK
12107	2026-09-18 20:21	75.83	OK	12108	2026-09-18 20:22	75.48	OK
12109	2026-09-18 20:23	77.19	OK	12110	2026-09-18 20:24	75.05	OK
12111	2026-09-18 20:25	74.42	OK	12112	2026-09-18 20:26	76.15	OK
12113	2026-09-18 20:27	76.61	OK	12114	2026-09-18 20:28	74.80	OK
12115	2026-09-18 20:29	73.71	OK	12116	2026-09-18 20:30	76.66	OK
12117	2026-09-18 20:31	76.97	OK	12118	2026-09-18 20:32	78.42	OK
12119	2026-09-18 20:33	74.30	OK	12120	2026-09-18 20:34	76.00	OK
12121	2026-09-18 20:35	77.76	OK	12122	2026-09-18 20:36	75.22	OK
12123	2026-09-18 20:37	75.66	OK	12124	2026-09-18 20:38	74.46	OK
12125	2026-09-18 20:39	75.39	OK	12126	2026-09-18 20:40	76.50	OK
12127	2026-09-18 20:41	74.65	OK	12128	2026-09-18 20:42	76.76	OK
12129	2026-09-18 20:43	76.11	OK	12130	2026-09-18 20:44	73.69	OK
12131	2026-09-18 20:45	78.64	OK	12132	2026-09-18 20:46	77.28	OK
12133	2026-09-18 20:47	77.17	OK	12134	2026-09-18 20:48	78.27	OK
12135	2026-09-18 20:49	76.19	OK	12136	2026-09-18 20:50	78.66	OK
1213	2026-09-18 20:51	75.09	OK	1213	2026-09-18 20:52	74.75	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
12139	2026-09-18 20:53	79.91	OK	12140	2026-09-18 20:54	76.68	OK
12141	2026-09-18 20:55	77.90	OK	12142	2026-09-18 20:56	76.74	OK
12143	2026-09-18 20:57	77.71	OK	12144	2026-09-18 20:58	77.24	OK
12145	2026-09-18 20:59	77.81	OK	12146	2026-09-18 21:00	79.38	OK
12147	2026-09-18 21:01	76.68	OK	12148	2026-09-18 21:02	75.18	OK
12149	2026-09-18 21:03	77.24	OK	12150	2026-09-18 21:04	76.25	OK
12151	2026-09-18 21:05	77.07	OK	12152	2026-09-18 21:06	77.06	OK
12153	2026-09-18 21:07	78.20	OK	12154	2026-09-18 21:08	77.18	OK
12155	2026-09-18 21:09	75.34	OK	12156	2026-09-18 21:10	76.26	OK
12157	2026-09-18 21:11	76.18	OK	12158	2026-09-18 21:12	78.86	OK
12159	2026-09-18 21:13	78.81	OK	12160	2026-09-18 21:14	77.54	OK
12161	2026-09-18 21:15	77.65	OK	12162	2026-09-18 21:16	78.12	OK
12163	2026-09-18 21:17	74.73	OK	12164	2026-09-18 21:18	78.97	OK
12165	2026-09-18 21:19	79.55	OK	12166	2026-09-18 21:20	78.56	OK
12167	2026-09-18 21:21	76.71	OK	12168	2026-09-18 21:22	76.46	OK
12169	2026-09-18 21:23	76.03	OK	12170	2026-09-18 21:24	77.93	OK
12171	2026-09-18 21:25	80.04	OK	12172	2026-09-18 21:26	77.91	OK
12173	2026-09-18 21:27	76.09	OK	12174	2026-09-18 21:28	76.30	OK
12175	2026-09-18 21:29	75.73	OK	12176	2026-09-18 21:30	74.74	OK
12177	2026-09-18 21:31	76.05	OK	12178	2026-09-18 21:32	78.57	OK
12179	2026-09-18 21:33	78.12	OK	12180	2026-09-18 21:34	78.04	OK
12181	2026-09-18 21:35	78.52	OK	12182	2026-09-18 21:36	79.35	OK
12183	2026-09-18 21:37	75.13	OK	12184	2026-09-18 21:38	75.36	OK
12185	2026-09-18 21:39	77.30	OK	12186	2026-09-18 21:40	78.29	OK
12187	2026-09-18 21:41	78.04	OK	12188	2026-09-18 21:42	78.32	OK
12189	2026-09-18 21:43	75.90	OK	12190	2026-09-18 21:44	76.36	OK
12191	2026-09-18 21:45	77.82	OK	12192	2026-09-18 21:46	77.19	OK
12193	2026-09-18 21:47	77.76	OK	12194	2026-09-18 21:48	76.62	OK
12195	2026-09-18 21:49	78.48	OK	12196	2026-09-18 21:50	81.17	OK
1219	2026-09-18 21:51	77.20	OK	1219	2026-09-18 21:52	79.38	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
12199	2026-09-18 21:53	76.05	OK	12200	2026-09-18 21:54	78.78	OK
12201	2026-09-18 21:55	78.45	OK	12202	2026-09-18 21:56	75.94	OK
12203	2026-09-18 21:57	76.90	OK	12204	2026-09-18 21:58	78.26	OK
12205	2026-09-18 21:59	77.73	OK	12206	2026-09-18 22:00	76.35	OK
12207	2026-09-18 22:01	77.34	OK	12208	2026-09-18 22:02	80.37	OK
12209	2026-09-18 22:03	75.52	OK	12210	2026-09-18 22:04	76.02	OK
12211	2026-09-18 22:05	78.32	OK	12212	2026-09-18 22:06	78.96	OK
12213	2026-09-18 22:07	78.84	OK	12214	2026-09-18 22:08	78.45	OK
12215	2026-09-18 22:09	80.34	OK	12216	2026-09-18 22:10	78.87	OK
12217	2026-09-18 22:11	79.30	OK	12218	2026-09-18 22:12	77.17	OK
12219	2026-09-18 22:13	78.84	OK	12220	2026-09-18 22:14	77.05	OK
12221	2026-09-18 22:15	76.37	OK	12222	2026-09-18 22:16	78.95	OK
12223	2026-09-18 22:17	76.70	OK	12224	2026-09-18 22:18	78.89	OK
12225	2026-09-18 22:19	79.20	OK	12226	2026-09-18 22:20	77.98	OK
12227	2026-09-18 22:21	78.40	OK	12228	2026-09-18 22:22	78.18	OK
12229	2026-09-18 22:23	80.02	OK	12230	2026-09-18 22:24	77.36	OK
12231	2026-09-18 22:25	77.74	OK	12232	2026-09-18 22:26	77.98	OK
12233	2026-09-18 22:27	78.52	OK	12234	2026-09-18 22:28	79.38	OK
12235	2026-09-18 22:29	79.13	OK	12236	2026-09-18 22:30	78.29	OK
12237	2026-09-18 22:31	79.03	OK	12238	2026-09-18 22:32	78.66	OK
12239	2026-09-18 22:33	80.72	OK	12240	2026-09-18 22:34	80.45	OK
12241	2026-09-18 22:35	79.75	OK	12242	2026-09-18 22:36	77.75	OK
12243	2026-09-18 22:37	79.26	OK	12244	2026-09-18 22:38	78.06	OK
12245	2026-09-18 22:39	76.60	OK	12246	2026-09-18 22:40	80.58	OK
12247	2026-09-18 22:41	80.10	OK	12248	2026-09-18 22:42	78.28	OK
12249	2026-09-18 22:43	79.08	OK	12250	2026-09-18 22:44	76.31	OK
12251	2026-09-18 22:45	77.05	OK	12252	2026-09-18 22:46	78.32	OK
12253	2026-09-18 22:47	79.28	OK	12254	2026-09-18 22:48	78.58	OK
12255	2026-09-18 22:49	80.17	OK	12256	2026-09-18 22:50	80.21	OK
1225	2026-09-18 22:51	79.62	OK	1225	2026-09-18 22:52	80.45	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
12259	2026-09-18 22:53	81.51	OK	12260	2026-09-18 22:54	79.60	OK
12261	2026-09-18 22:55	80.01	OK	12262	2026-09-18 22:56	77.62	OK
12263	2026-09-18 22:57	78.72	OK	12264	2026-09-18 22:58	81.45	OK
12265	2026-09-18 22:59	77.71	OK	12266	2026-09-18 23:00	79.42	OK
12267	2026-09-18 23:01	78.83	OK	12268	2026-09-18 23:02	77.06	OK
12269	2026-09-18 23:03	79.04	OK	12270	2026-09-18 23:04	79.15	OK
12271	2026-09-18 23:05	81.34	OK	12272	2026-09-18 23:06	79.93	OK
12273	2026-09-18 23:07	77.47	OK	12274	2026-09-18 23:08	80.76	OK
12275	2026-09-18 23:09	77.11	OK	12276	2026-09-18 23:10	78.38	OK
12277	2026-09-18 23:11	78.57	OK	12278	2026-09-18 23:12	78.84	OK
12279	2026-09-18 23:13	80.10	OK	12280	2026-09-18 23:14	81.75	OK
12281	2026-09-18 23:15	79.72	OK	12282	2026-09-18 23:16	78.21	OK
12283	2026-09-18 23:17	81.73	OK	12284	2026-09-18 23:18	77.94	OK
12285	2026-09-18 23:19	79.90	OK	12286	2026-09-18 23:20	80.16	OK
12287	2026-09-18 23:21	77.80	OK	12288	2026-09-18 23:22	80.16	OK
12289	2026-09-18 23:23	81.63	OK	12290	2026-09-18 23:24	80.30	OK
12291	2026-09-18 23:25	78.75	OK	12292	2026-09-18 23:26	80.29	OK
12293	2026-09-18 23:27	81.87	OK	12294	2026-09-18 23:28	81.09	OK
12295	2026-09-18 23:29	77.88	OK	12296	2026-09-18 23:30	80.06	OK
12297	2026-09-18 23:31	78.47	OK	12298	2026-09-18 23:32	79.02	OK
12299	2026-09-18 23:33	79.56	OK	12300	2026-09-18 23:34	78.97	OK
12301	2026-09-18 23:35	80.58	OK	12302	2026-09-18 23:36	78.19	OK
12303	2026-09-18 23:37	82.66	OK	12304	2026-09-18 23:38	79.39	OK
12305	2026-09-18 23:39	78.43	OK	12306	2026-09-18 23:40	77.22	OK
12307	2026-09-18 23:41	80.63	OK	12308	2026-09-18 23:42	80.62	OK
12309	2026-09-18 23:43	79.73	OK	12310	2026-09-18 23:44	80.09	OK
12311	2026-09-18 23:45	79.63	OK	12312	2026-09-18 23:46	79.86	OK
12313	2026-09-18 23:47	79.02	OK	12314	2026-09-18 23:48	78.84	OK
12315	2026-09-18 23:49	80.11	OK	12316	2026-09-18 23:50	79.96	OK
1231	2026-09-18 23:51	82.55	OK	1231	2026-09-18 23:52	79.35	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
12319	2026-09-18 23:53	81.08	OK	12320	2026-09-18 23:54	82.36	OK
12321	2026-09-18 23:55	80.31	OK	12322	2026-09-18 23:56	81.13	OK
12323	2026-09-18 23:57	80.17	OK	12324	2026-09-18 23:58	81.43	OK
12325	2026-09-18 23:59	79.62	OK	12326	2026-09-19 00:00	80.49	OK
12327	2026-09-19 00:01	80.81	OK	12328	2026-09-19 00:02	80.36	OK
12329	2026-09-19 00:03	80.84	OK	12330	2026-09-19 00:04	79.84	OK
12331	2026-09-19 00:05	80.11	OK	12332	2026-09-19 00:06	79.13	OK
12333	2026-09-19 00:07	83.41	OK	12334	2026-09-19 00:08	82.23	OK
12335	2026-09-19 00:09	82.23	OK	12336	2026-09-19 00:10	81.43	OK
12337	2026-09-19 00:11	79.89	OK	12338	2026-09-19 00:12	80.66	OK
12339	2026-09-19 00:13	81.64	OK	12340	2026-09-19 00:14	79.31	OK
12341	2026-09-19 00:15	81.15	OK	12342	2026-09-19 00:16	82.14	OK
12343	2026-09-19 00:17	79.19	OK	12344	2026-09-19 00:18	80.11	OK
12345	2026-09-19 00:19	80.24	OK	12346	2026-09-19 00:20	78.84	OK
12347	2026-09-19 00:21	80.95	OK	12348	2026-09-19 00:22	81.51	OK
12349	2026-09-19 00:23	81.80	OK	12350	2026-09-19 00:24	81.81	OK
12351	2026-09-19 00:25	80.72	OK	12352	2026-09-19 00:26	80.14	OK
12353	2026-09-19 00:27	82.04	OK	12354	2026-09-19 00:28	81.75	OK
12355	2026-09-19 00:29	81.10	OK	12356	2026-09-19 00:30	79.54	OK
12357	2026-09-19 00:31	80.65	OK	12358	2026-09-19 00:32	78.82	OK
12359	2026-09-19 00:33	80.07	OK	12360	2026-09-19 00:34	81.13	OK
12361	2026-09-19 00:35	81.94	OK	12362	2026-09-19 00:36	79.61	OK
12363	2026-09-19 00:37	83.04	OK	12364	2026-09-19 00:38	79.18	OK
12365	2026-09-19 00:39	81.76	OK	12366	2026-09-19 00:40	81.04	OK
12367	2026-09-19 00:41	81.00	OK	12368	2026-09-19 00:42	81.37	OK
12369	2026-09-19 00:43	81.14	OK	12370	2026-09-19 00:44	82.22	OK
12371	2026-09-19 00:45	79.75	OK	12372	2026-09-19 00:46	78.53	OK
12373	2026-09-19 00:47	79.06	OK	12374	2026-09-19 00:48	79.66	OK
12375	2026-09-19 00:49	81.51	OK	12376	2026-09-19 00:50	81.96	OK
1237	2026-09-19 00:51	79.98	OK	1237	2026-09-19 00:52	81.44	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
12379	2026-09-19 00:53	80.07	OK	12380	2026-09-19 00:54	81.26	OK
12381	2026-09-19 00:55	82.00	OK	12382	2026-09-19 00:56	81.26	OK
12383	2026-09-19 00:57	81.04	OK	12384	2026-09-19 00:58	80.93	OK
12385	2026-09-19 00:59	80.28	OK	12386	2026-09-19 01:00	81.62	OK
12387	2026-09-19 01:01	81.73	OK	12388	2026-09-19 01:02	81.16	OK
12389	2026-09-19 01:03	80.99	OK	12390	2026-09-19 01:04	82.60	OK
12391	2026-09-19 01:05	80.70	OK	12392	2026-09-19 01:06	82.33	OK
12393	2026-09-19 01:07	84.35	OK	12394	2026-09-19 01:08	82.05	OK
12395	2026-09-19 01:09	81.89	OK	12396	2026-09-19 01:10	82.49	OK
12397	2026-09-19 01:11	83.76	OK	12398	2026-09-19 01:12	81.45	OK
12399	2026-09-19 01:13	81.27	OK	12400	2026-09-19 01:14	81.19	OK
12401	2026-09-19 01:15	80.80	OK	12402	2026-09-19 01:16	81.03	OK
12403	2026-09-19 01:17	82.36	OK	12404	2026-09-19 01:18	83.39	OK
12405	2026-09-19 01:19	81.28	OK	12406	2026-09-19 01:20	81.92	OK
12407	2026-09-19 01:21	79.97	OK	12408	2026-09-19 01:22	81.62	OK
12409	2026-09-19 01:23	82.35	OK	12410	2026-09-19 01:24	81.78	OK
12411	2026-09-19 01:25	81.11	OK	12412	2026-09-19 01:26	81.89	OK
12413	2026-09-19 01:27	80.73	OK	12414	2026-09-19 01:28	81.54	OK
12415	2026-09-19 01:29	82.20	OK	12416	2026-09-19 01:30	80.63	OK
12417	2026-09-19 01:31	83.06	OK	12418	2026-09-19 01:32	82.75	OK
12419	2026-09-19 01:33	82.94	OK	12420	2026-09-19 01:34	82.60	OK
12421	2026-09-19 01:35	80.92	OK	12422	2026-09-19 01:36	83.45	OK
12423	2026-09-19 01:37	80.70	OK	12424	2026-09-19 01:38	81.18	OK
12425	2026-09-19 01:39	80.73	OK	12426	2026-09-19 01:40	80.83	OK
12427	2026-09-19 01:41	79.92	OK	12428	2026-09-19 01:42	83.12	OK
12429	2026-09-19 01:43	81.70	OK	12430	2026-09-19 01:44	80.95	OK
12431	2026-09-19 01:45	82.78	OK	12432	2026-09-19 01:46	80.70	OK
12433	2026-09-19 01:47	82.11	OK	12434	2026-09-19 01:48	81.85	OK
12435	2026-09-19 01:49	83.51	OK	12436	2026-09-19 01:50	81.44	OK
1243	2026-09-19 01:51	80.32	OK	1243	2026-09-19 01:52	79.72	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
12439	2026-09-19 01:53	80.71	OK	12440	2026-09-19 01:54	81.06	OK
12441	2026-09-19 01:55	80.57	OK	12442	2026-09-19 01:56	80.19	OK
12443	2026-09-19 01:57	82.23	OK	12444	2026-09-19 01:58	82.38	OK
12445	2026-09-19 01:59	82.11	OK	12446	2026-09-19 02:00	81.16	OK
12447	2026-09-19 02:01	82.00	OK	12448	2026-09-19 02:02	80.94	OK
12449	2026-09-19 02:03	80.18	OK	12450	2026-09-19 02:04	80.05	OK
12451	2026-09-19 02:05	81.85	OK	12452	2026-09-19 02:06	81.08	OK
12453	2026-09-19 02:07	80.18	OK	12454	2026-09-19 02:08	81.34	OK
12455	2026-09-19 02:09	81.47	OK	12456	2026-09-19 02:10	82.87	OK
12457	2026-09-19 02:11	82.61	OK	12458	2026-09-19 02:12	82.89	OK
12459	2026-09-19 02:13	81.83	OK	12460	2026-09-19 02:14	84.48	OK
12461	2026-09-19 02:15	80.87	OK	12462	2026-09-19 02:16	83.10	OK
12463	2026-09-19 02:17	80.65	OK	12464	2026-09-19 02:18	83.59	OK
12465	2026-09-19 02:19	82.84	OK	12466	2026-09-19 02:20	81.81	OK
12467	2026-09-19 02:21	81.60	OK	12468	2026-09-19 02:22	82.21	OK
12469	2026-09-19 02:23	80.24	OK	12470	2026-09-19 02:24	82.78	OK
12471	2026-09-19 02:25	83.50	OK	12472	2026-09-19 02:26	83.00	OK
12473	2026-09-19 02:27	80.53	OK	12474	2026-09-19 02:28	82.76	OK
12475	2026-09-19 02:29	83.26	OK	12476	2026-09-19 02:30	81.33	OK
12477	2026-09-19 02:31	81.09	OK	12478	2026-09-19 02:32	81.13	OK
12479	2026-09-19 02:33	80.64	OK	12480	2026-09-19 02:34	79.51	OK
12481	2026-09-19 02:35	81.97	OK	12482	2026-09-19 02:36	82.93	OK
12483	2026-09-19 02:37	84.19	OK	12484	2026-09-19 02:38	81.11	OK
12485	2026-09-19 02:39	80.25	OK	12486	2026-09-19 02:40	79.95	OK
12487	2026-09-19 02:41	78.98	OK	12488	2026-09-19 02:42	82.10	OK
12489	2026-09-19 02:43	80.67	OK	12490	2026-09-19 02:44	82.57	OK
12491	2026-09-19 02:45	80.73	OK	12492	2026-09-19 02:46	81.71	OK
12493	2026-09-19 02:47	82.27	OK	12494	2026-09-19 02:48	81.43	OK
12495	2026-09-19 02:49	83.11	OK	12496	2026-09-19 02:50	83.14	OK
1249	2026-09-19 02:51	81.57	OK	1249	2026-09-19 02:52	85.22	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
12499	2026-09-19 02:53	79.70	OK	12500	2026-09-19 02:54	82.80	OK
12501	2026-09-19 02:55	80.11	OK	12502	2026-09-19 02:56	80.30	OK
12503	2026-09-19 02:57	81.91	OK	12504	2026-09-19 02:58	82.19	OK
12505	2026-09-19 02:59	83.14	OK	12506	2026-09-19 03:00	82.62	OK
12507	2026-09-19 03:01	81.07	OK	12508	2026-09-19 03:02	81.07	OK
12509	2026-09-19 03:03	81.23	OK	12510	2026-09-19 03:04	80.47	OK
12511	2026-09-19 03:05	81.49	OK	12512	2026-09-19 03:06	81.11	OK
12513	2026-09-19 03:07	82.00	OK	12514	2026-09-19 03:08	83.19	OK
12515	2026-09-19 03:09	81.53	OK	12516	2026-09-19 03:10	83.19	OK
12517	2026-09-19 03:11	82.87	OK	12518	2026-09-19 03:12	81.75	OK
12519	2026-09-19 03:13	80.76	OK	12520	2026-09-19 03:14	82.45	OK
12521	2026-09-19 03:15	83.03	OK	12522	2026-09-19 03:16	79.93	OK
12523	2026-09-19 03:17	82.99	OK	12524	2026-09-19 03:18	82.17	OK
12525	2026-09-19 03:19	80.06	OK	12526	2026-09-19 03:20	82.66	OK
12527	2026-09-19 03:21	83.16	OK	12528	2026-09-19 03:22	82.05	OK
12529	2026-09-19 03:23	81.01	OK	12530	2026-09-19 03:24	80.48	OK
12531	2026-09-19 03:25	82.48	OK	12532	2026-09-19 03:26	81.26	OK
12533	2026-09-19 03:27	82.47	OK	12534	2026-09-19 03:28	80.69	OK
12535	2026-09-19 03:29	81.53	OK	12536	2026-09-19 03:30	81.97	OK
12537	2026-09-19 03:31	80.73	OK	12538	2026-09-19 03:32	80.27	OK
12539	2026-09-19 03:33	79.30	OK	12540	2026-09-19 03:34	82.35	OK
12541	2026-09-19 03:35	82.38	OK	12542	2026-09-19 03:36	83.63	OK
12543	2026-09-19 03:37	80.28	OK	12544	2026-09-19 03:38	79.13	OK
12545	2026-09-19 03:39	82.81	OK	12546	2026-09-19 03:40	81.25	OK
12547	2026-09-19 03:41	80.59	OK	12548	2026-09-19 03:42	80.70	OK
12549	2026-09-19 03:43	81.19	OK	12550	2026-09-19 03:44	80.36	OK
12551	2026-09-19 03:45	81.49	OK	12552	2026-09-19 03:46	82.89	OK
12553	2026-09-19 03:47	79.72	OK	12554	2026-09-19 03:48	79.83	OK
12555	2026-09-19 03:49	79.87	OK	12556	2026-09-19 03:50	80.41	OK
1255	2026-09-19 03:51	83.16	OK	1255	2026-09-19 03:52	80.64	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
12559	2026-09-19 03:53	82.36	OK	12560	2026-09-19 03:54	83.18	OK
12561	2026-09-19 03:55	80.03	OK	12562	2026-09-19 03:56	80.50	OK
12563	2026-09-19 03:57	83.27	OK	12564	2026-09-19 03:58	83.45	OK
12565	2026-09-19 03:59	81.55	OK	12566	2026-09-19 04:00	80.43	OK
12567	2026-09-19 04:01	82.71	OK	12568	2026-09-19 04:02	79.75	OK
12569	2026-09-19 04:03	82.11	OK	12570	2026-09-19 04:04	82.69	OK
12571	2026-09-19 04:05	81.10	OK	12572	2026-09-19 04:06	81.61	OK
12573	2026-09-19 04:07	80.51	OK	12574	2026-09-19 04:08	81.82	OK
12575	2026-09-19 04:09	82.21	OK	12576	2026-09-19 04:10	80.60	OK
12577	2026-09-19 04:11	83.84	OK	12578	2026-09-19 04:12	83.05	OK
12579	2026-09-19 04:13	82.39	OK	12580	2026-09-19 04:14	79.29	OK
12581	2026-09-19 04:15	81.79	OK	12582	2026-09-19 04:16	83.25	OK
12583	2026-09-19 04:17	80.79	OK	12584	2026-09-19 04:18	83.04	OK
12585	2026-09-19 04:19	81.70	OK	12586	2026-09-19 04:20	82.47	OK
12587	2026-09-19 04:21	81.87	OK	12588	2026-09-19 04:22	81.04	OK
12589	2026-09-19 04:23	80.90	OK	12590	2026-09-19 04:24	82.71	OK
12591	2026-09-19 04:25	80.97	OK	12592	2026-09-19 04:26	81.41	OK
12593	2026-09-19 04:27	82.86	OK	12594	2026-09-19 04:28	80.00	OK
12595	2026-09-19 04:29	79.25	OK	12596	2026-09-19 04:30	80.77	OK
12597	2026-09-19 04:31	82.49	OK	12598	2026-09-19 04:32	82.00	OK
12599	2026-09-19 04:33	81.80	OK	12600	2026-09-19 04:34	80.21	OK
12601	2026-09-19 04:35	81.66	OK	12602	2026-09-19 04:36	79.68	OK
12603	2026-09-19 04:37	81.30	OK	12604	2026-09-19 04:38	82.78	OK
12605	2026-09-19 04:39	82.44	OK	12606	2026-09-19 04:40	80.96	OK
12607	2026-09-19 04:41	81.31	OK	12608	2026-09-19 04:42	84.87	OK
12609	2026-09-19 04:43	79.36	OK	12610	2026-09-19 04:44	81.56	OK
12611	2026-09-19 04:45	79.60	OK	12612	2026-09-19 04:46	80.15	OK
12613	2026-09-19 04:47	81.56	OK	12614	2026-09-19 04:48	83.65	OK
12615	2026-09-19 04:49	78.56	OK	12616	2026-09-19 04:50	80.54	OK
1261	2026-09-19 04:51	79.78	OK	1261	2026-09-19 04:52	80.68	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
12619	2026-09-19 04:53	81.15	OK	12620	2026-09-19 04:54	80.35	OK
12621	2026-09-19 04:55	82.63	OK	12622	2026-09-19 04:56	80.61	OK
12623	2026-09-19 04:57	79.86	OK	12624	2026-09-19 04:58	80.76	OK
12625	2026-09-19 04:59	78.92	OK	12626	2026-09-19 05:00	80.56	OK
12627	2026-09-19 05:01	80.26	OK	12628	2026-09-19 05:02	82.03	OK
12629	2026-09-19 05:03	82.56	OK	12630	2026-09-19 05:04	79.13	OK
12631	2026-09-19 05:05	79.37	OK	12632	2026-09-19 05:06	83.24	OK
12633	2026-09-19 05:07	81.57	OK	12634	2026-09-19 05:08	80.88	OK
12635	2026-09-19 05:09	80.48	OK	12636	2026-09-19 05:10	79.38	OK
12637	2026-09-19 05:11	81.85	OK	12638	2026-09-19 05:12	80.66	OK
12639	2026-09-19 05:13	79.25	OK	12640	2026-09-19 05:14	80.34	OK
12641	2026-09-19 05:15	81.08	OK	12642	2026-09-19 05:16	79.38	OK
12643	2026-09-19 05:17	80.43	OK	12644	2026-09-19 05:18	79.77	OK
12645	2026-09-19 05:19	80.15	OK	12646	2026-09-19 05:20	78.16	OK
12647	2026-09-19 05:21	80.04	OK	12648	2026-09-19 05:22	80.25	OK
12649	2026-09-19 05:23	79.07	OK	12650	2026-09-19 05:24	82.31	OK
12651	2026-09-19 05:25	82.63	OK	12652	2026-09-19 05:26	80.75	OK
12653	2026-09-19 05:27	80.49	OK	12654	2026-09-19 05:28	80.60	OK
12655	2026-09-19 05:29	79.33	OK	12656	2026-09-19 05:30	79.73	OK
12657	2026-09-19 05:31	80.37	OK	12658	2026-09-19 05:32	81.71	OK
12659	2026-09-19 05:33	80.58	OK	12660	2026-09-19 05:34	81.37	OK
12661	2026-09-19 05:35	82.03	OK	12662	2026-09-19 05:36	79.22	OK
12663	2026-09-19 05:37	81.46	OK	12664	2026-09-19 05:38	80.22	OK
12665	2026-09-19 05:39	80.22	OK	12666	2026-09-19 05:40	82.80	OK
12667	2026-09-19 05:41	78.77	OK	12668	2026-09-19 05:42	79.33	OK
12669	2026-09-19 05:43	78.86	OK	12670	2026-09-19 05:44	80.14	OK
12671	2026-09-19 05:45	81.90	OK	12672	2026-09-19 05:46	79.57	OK
12673	2026-09-19 05:47	80.61	OK	12674	2026-09-19 05:48	83.88	OK
12675	2026-09-19 05:49	80.33	OK	12676	2026-09-19 05:50	81.15	OK
1267	2026-09-19 05:51	78.92	OK	1267	2026-09-19 05:52	80.20	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
12679	2026-09-19 05:53	82.92	OK	12680	2026-09-19 05:54	79.40	OK
12681	2026-09-19 05:55	80.56	OK	12682	2026-09-19 05:56	80.36	OK
12683	2026-09-19 05:57	82.08	OK	12684	2026-09-19 05:58	81.06	OK
12685	2026-09-19 05:59	79.08	OK	12686	2026-09-19 06:00	78.51	OK
12687	2026-09-19 06:01	77.98	OK	12688	2026-09-19 06:02	80.85	OK
12689	2026-09-19 06:03	77.85	OK	12690	2026-09-19 06:04	79.20	OK
12691	2026-09-19 06:05	82.43	OK	12692	2026-09-19 06:06	79.02	OK
12693	2026-09-19 06:07	79.71	OK	12694	2026-09-19 06:08	79.09	OK
12695	2026-09-19 06:09	80.62	OK	12696	2026-09-19 06:10	79.03	OK
12697	2026-09-19 06:11	80.69	OK	12698	2026-09-19 06:12	80.50	OK
12699	2026-09-19 06:13	79.60	OK	12700	2026-09-19 06:14	78.62	OK
12701	2026-09-19 06:15	81.75	OK	12702	2026-09-19 06:16	79.61	OK
12703	2026-09-19 06:17	82.56	OK	12704	2026-09-19 06:18	77.64	OK
12705	2026-09-19 06:19	77.23	OK	12706	2026-09-19 06:20	80.06	OK
12707	2026-09-19 06:21	78.81	OK	12708	2026-09-19 06:22	78.35	OK
12709	2026-09-19 06:23	80.03	OK	12710	2026-09-19 06:24	80.69	OK
12711	2026-09-19 06:25	80.71	OK	12712	2026-09-19 06:26	80.04	OK
12713	2026-09-19 06:27	79.66	OK	12714	2026-09-19 06:28	77.86	OK
12715	2026-09-19 06:29	78.63	OK	12716	2026-09-19 06:30	80.54	OK
12717	2026-09-19 06:31	80.07	OK	12718	2026-09-19 06:32	80.05	OK
12719	2026-09-19 06:33	79.48	OK	12720	2026-09-19 06:34	78.04	OK
12721	2026-09-19 06:35	80.26	OK	12722	2026-09-19 06:36	79.84	OK
12723	2026-09-19 06:37	79.37	OK	12724	2026-09-19 06:38	77.94	OK
12725	2026-09-19 06:39	77.23	OK	12726	2026-09-19 06:40	80.36	OK
12727	2026-09-19 06:41	81.73	OK	12728	2026-09-19 06:42	79.72	OK
12729	2026-09-19 06:43	79.86	OK	12730	2026-09-19 06:44	79.49	OK
12731	2026-09-19 06:45	78.59	OK	12732	2026-09-19 06:46	79.14	OK
12733	2026-09-19 06:47	78.72	OK	12734	2026-09-19 06:48	77.48	OK
12735	2026-09-19 06:49	78.52	OK	12736	2026-09-19 06:50	79.79	OK
1273	2026-09-19 06:51	76.81	OK	1273	2026-09-19 06:52	78.34	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
12739	2026-09-19 06:53	80.35	OK	12740	2026-09-19 06:54	77.73	OK
12741	2026-09-19 06:55	79.25	OK	12742	2026-09-19 06:56	78.35	OK
12743	2026-09-19 06:57	80.92	OK	12744	2026-09-19 06:58	78.84	OK
12745	2026-09-19 06:59	79.58	OK	12746	2026-09-19 07:00	79.58	OK
12747	2026-09-19 07:01	78.46	OK	12748	2026-09-19 07:02	82.02	OK
12749	2026-09-19 07:03	77.67	OK	12750	2026-09-19 07:04	79.43	OK
12751	2026-09-19 07:05	76.95	OK	12752	2026-09-19 07:06	78.69	OK
12753	2026-09-19 07:07	80.47	OK	12754	2026-09-19 07:08	78.49	OK
12755	2026-09-19 07:09	77.04	OK	12756	2026-09-19 07:10	78.56	OK
12757	2026-09-19 07:11	79.41	OK	12758	2026-09-19 07:12	78.05	OK
12759	2026-09-19 07:13	78.19	OK	12760	2026-09-19 07:14	80.60	OK
12761	2026-09-19 07:15	77.61	OK	12762	2026-09-19 07:16	79.18	OK
12763	2026-09-19 07:17	76.63	OK	12764	2026-09-19 07:18	80.40	OK
12765	2026-09-19 07:19	79.81	OK	12766	2026-09-19 07:20	76.30	OK
12767	2026-09-19 07:21	78.53	OK	12768	2026-09-19 07:22	79.91	OK
12769	2026-09-19 07:23	80.46	OK	12770	2026-09-19 07:24	79.45	OK
12771	2026-09-19 07:25	80.78	OK	12772	2026-09-19 07:26	79.73	OK
12773	2026-09-19 07:27	77.21	OK	12774	2026-09-19 07:28	78.85	OK
12775	2026-09-19 07:29	79.26	OK	12776	2026-09-19 07:30	78.00	OK
12777	2026-09-19 07:31	78.60	OK	12778	2026-09-19 07:32	79.06	OK
12779	2026-09-19 07:33	77.07	OK	12780	2026-09-19 07:34	77.71	OK
12781	2026-09-19 07:35	78.78	OK	12782	2026-09-19 07:36	78.02	OK
12783	2026-09-19 07:37	77.17	OK	12784	2026-09-19 07:38	77.21	OK
12785	2026-09-19 07:39	78.45	OK	12786	2026-09-19 07:40	77.89	OK
12787	2026-09-19 07:41	78.70	OK	12788	2026-09-19 07:42	79.64	OK
12789	2026-09-19 07:43	77.19	OK	12790	2026-09-19 07:44	76.79	OK
12791	2026-09-19 07:45	80.49	OK	12792	2026-09-19 07:46	80.16	OK
12793	2026-09-19 07:47	78.12	OK	12794	2026-09-19 07:48	78.88	OK
12795	2026-09-19 07:49	77.03	OK	12796	2026-09-19 07:50	78.28	OK
1279	2026-09-19 07:51	77.59	OK	1279	2026-09-19 07:52	78.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
12799	2026-09-19 07:53	80.13	OK	12800	2026-09-19 07:54	76.39	OK
12801	2026-09-19 07:55	80.56	OK	12802	2026-09-19 07:56	76.34	OK
12803	2026-09-19 07:57	76.12	OK	12804	2026-09-19 07:58	74.80	OK
12805	2026-09-19 07:59	79.27	OK	12806	2026-09-19 08:00	77.51	OK
12807	2026-09-19 08:01	80.48	OK	12808	2026-09-19 08:02	79.27	OK
12809	2026-09-19 08:03	76.62	OK	12810	2026-09-19 08:04	78.76	OK
12811	2026-09-19 08:05	79.35	OK	12812	2026-09-19 08:06	74.47	OK
12813	2026-09-19 08:07	78.94	OK	12814	2026-09-19 08:08	80.27	OK
12815	2026-09-19 08:09	78.02	OK	12816	2026-09-19 08:10	79.06	OK
12817	2026-09-19 08:11	78.17	OK	12818	2026-09-19 08:12	76.71	OK
12819	2026-09-19 08:13	77.36	OK	12820	2026-09-19 08:14	77.19	OK
12821	2026-09-19 08:15	77.47	OK	12822	2026-09-19 08:16	77.75	OK
12823	2026-09-19 08:17	76.21	OK	12824	2026-09-19 08:18	76.42	OK
12825	2026-09-19 08:19	78.37	OK	12826	2026-09-19 08:20	75.42	OK
12827	2026-09-19 08:21	77.88	OK	12828	2026-09-19 08:22	77.86	OK
12829	2026-09-19 08:23	78.46	OK	12830	2026-09-19 08:24	77.03	OK
12831	2026-09-19 08:25	76.47	OK	12832	2026-09-19 08:26	76.96	OK
12833	2026-09-19 08:27	76.65	OK	12834	2026-09-19 08:28	77.61	OK
12835	2026-09-19 08:29	77.64	OK	12836	2026-09-19 08:30	77.40	OK
12837	2026-09-19 08:31	77.59	OK	12838	2026-09-19 08:32	75.95	OK
12839	2026-09-19 08:33	77.61	OK	12840	2026-09-19 08:34	77.30	OK
12841	2026-09-19 08:35	78.35	OK	12842	2026-09-19 08:36	76.31	OK
12843	2026-09-19 08:37	75.96	OK	12844	2026-09-19 08:38	79.70	OK
12845	2026-09-19 08:39	76.45	OK	12846	2026-09-19 08:40	76.37	OK
12847	2026-09-19 08:41	78.01	OK	12848	2026-09-19 08:42	77.65	OK
12849	2026-09-19 08:43	75.38	OK	12850	2026-09-19 08:44	77.31	OK
12851	2026-09-19 08:45	77.69	OK	12852	2026-09-19 08:46	78.89	OK
12853	2026-09-19 08:47	76.52	OK	12854	2026-09-19 08:48	74.95	OK
12855	2026-09-19 08:49	78.02	OK	12856	2026-09-19 08:50	75.44	OK
1285	2026-09-19 08:51	79.10	OK	1285	2026-09-19 08:52	73.62	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
12859	2026-09-19 08:53	77.17	OK	12860	2026-09-19 08:54	77.69	OK
12861	2026-09-19 08:55	76.56	OK	12862	2026-09-19 08:56	75.45	OK
12863	2026-09-19 08:57	75.64	OK	12864	2026-09-19 08:58	76.00	OK
12865	2026-09-19 08:59	74.72	OK	12866	2026-09-19 09:00	76.11	OK
12867	2026-09-19 09:01	76.11	OK	12868	2026-09-19 09:02	75.69	OK
12869	2026-09-19 09:03	77.31	OK	12870	2026-09-19 09:04	75.33	OK
12871	2026-09-19 09:05	76.22	OK	12872	2026-09-19 09:06	74.88	OK
12873	2026-09-19 09:07	78.46	OK	12874	2026-09-19 09:08	74.81	OK
12875	2026-09-19 09:09	77.70	OK	12876	2026-09-19 09:10	76.60	OK
12877	2026-09-19 09:11	74.66	OK	12878	2026-09-19 09:12	76.64	OK
12879	2026-09-19 09:13	75.23	OK	12880	2026-09-19 09:14	75.38	OK
12881	2026-09-19 09:15	74.38	OK	12882	2026-09-19 09:16	75.62	OK
12883	2026-09-19 09:17	73.15	OK	12884	2026-09-19 09:18	74.74	OK
12885	2026-09-19 09:19	75.24	OK	12886	2026-09-19 09:20	74.19	OK
12887	2026-09-19 09:21	76.07	OK	12888	2026-09-19 09:22	77.41	OK
12889	2026-09-19 09:23	76.10	OK	12890	2026-09-19 09:24	75.38	OK
12891	2026-09-19 09:25	77.88	OK	12892	2026-09-19 09:26	76.36	OK
12893	2026-09-19 09:27	74.71	OK	12894	2026-09-19 09:28	74.78	OK
12895	2026-09-19 09:29	75.22	OK	12896	2026-09-19 09:30	77.17	OK
12897	2026-09-19 09:31	75.20	OK	12898	2026-09-19 09:32	73.14	OK
12899	2026-09-19 09:33	75.12	OK	12900	2026-09-19 09:34	75.99	OK
12901	2026-09-19 09:35	75.03	OK	12902	2026-09-19 09:36	74.46	OK
12903	2026-09-19 09:37	76.38	OK	12904	2026-09-19 09:38	73.86	OK
12905	2026-09-19 09:39	74.78	OK	12906	2026-09-19 09:40	76.66	OK
12907	2026-09-19 09:41	75.73	OK	12908	2026-09-19 09:42	76.43	OK
12909	2026-09-19 09:43	74.13	OK	12910	2026-09-19 09:44	75.67	OK
12911	2026-09-19 09:45	76.10	OK	12912	2026-09-19 09:46	75.62	OK
12913	2026-09-19 09:47	75.73	OK	12914	2026-09-19 09:48	73.28	OK
12915	2026-09-19 09:49	75.90	OK	12916	2026-09-19 09:50	75.96	OK
12917	2026-09-19 09:51	73.04	OK	12918	2026-09-19 09:52	75.51	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
12919	2026-09-19 09:53	76.43	OK	12920	2026-09-19 09:54	76.22	OK
12921	2026-09-19 09:55	75.37	OK	12922	2026-09-19 09:56	76.72	OK
12923	2026-09-19 09:57	73.40	OK	12924	2026-09-19 09:58	74.72	OK
12925	2026-09-19 09:59	74.35	OK	12926	2026-09-19 10:00	75.53	OK
12927	2026-09-19 10:01	75.16	OK	12928	2026-09-19 10:02	77.59	OK
12929	2026-09-19 10:03	76.26	OK	12930	2026-09-19 10:04	73.99	OK
12931	2026-09-19 10:05	76.27	OK	12932	2026-09-19 10:06	73.29	OK
12933	2026-09-19 10:07	75.43	OK	12934	2026-09-19 10:08	72.30	OK
12935	2026-09-19 10:09	73.29	OK	12936	2026-09-19 10:10	74.71	OK
12937	2026-09-19 10:11	73.36	OK	12938	2026-09-19 10:12	75.77	OK
12939	2026-09-19 10:13	74.53	OK	12940	2026-09-19 10:14	71.78	OK
12941	2026-09-19 10:15	74.85	OK	12942	2026-09-19 10:16	73.75	OK
12943	2026-09-19 10:17	74.34	OK	12944	2026-09-19 10:18	73.84	OK
12945	2026-09-19 10:19	73.57	OK	12946	2026-09-19 10:20	74.98	OK
12947	2026-09-19 10:21	75.18	OK	12948	2026-09-19 10:22	76.76	OK
12949	2026-09-19 10:23	75.17	OK	12950	2026-09-19 10:24	75.10	OK
12951	2026-09-19 10:25	73.56	OK	12952	2026-09-19 10:26	75.27	OK
12953	2026-09-19 10:27	73.77	OK	12954	2026-09-19 10:28	73.97	OK
12955	2026-09-19 10:29	74.94	OK	12956	2026-09-19 10:30	76.30	OK
12957	2026-09-19 10:31	77.18	OK	12958	2026-09-19 10:32	75.02	OK
12959	2026-09-19 10:33	72.59	OK	12960	2026-09-19 10:34	76.27	OK
12961	2026-09-19 10:35	72.22	OK	12962	2026-09-19 10:36	72.97	OK
12963	2026-09-19 10:37	75.50	OK	12964	2026-09-19 10:38	74.79	OK
12965	2026-09-19 10:39	75.30	OK	12966	2026-09-19 10:40	73.36	OK
12967	2026-09-19 10:41	74.65	OK	12968	2026-09-19 10:42	74.81	OK
12969	2026-09-19 10:43	75.85	OK	12970	2026-09-19 10:44	76.38	OK
12971	2026-09-19 10:45	74.41	OK	12972	2026-09-19 10:46	75.12	OK
12973	2026-09-19 10:47	74.95	OK	12974	2026-09-19 10:48	73.75	OK
12975	2026-09-19 10:49	71.35	OK	12976	2026-09-19 10:50	74.44	OK
12977	2026-09-19 10:51	70.79	OK	12977	2026-09-19 10:52	75.73	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
12979	2026-09-19 10:53	71.78	OK	12980	2026-09-19 10:54	73.58	OK
12981	2026-09-19 10:55	74.70	OK	12982	2026-09-19 10:56	72.82	OK
12983	2026-09-19 10:57	75.63	OK	12984	2026-09-19 10:58	73.94	OK
12985	2026-09-19 10:59	74.50	OK	12986	2026-09-19 11:00	71.73	OK
12987	2026-09-19 11:01	71.21	OK	12988	2026-09-19 11:02	71.87	OK
12989	2026-09-19 11:03	72.30	OK	12990	2026-09-19 11:04	74.38	OK
12991	2026-09-19 11:05	73.01	OK	12992	2026-09-19 11:06	73.03	OK
12993	2026-09-19 11:07	73.90	OK	12994	2026-09-19 11:08	73.85	OK
12995	2026-09-19 11:09	73.00	OK	12996	2026-09-19 11:10	73.41	OK
12997	2026-09-19 11:11	74.30	OK	12998	2026-09-19 11:12	71.60	OK
12999	2026-09-19 11:13	74.68	OK	13000	2026-09-19 11:14	71.85	OK
13001	2026-09-19 11:15	72.70	OK	13002	2026-09-19 11:16	72.63	OK
13003	2026-09-19 11:17	72.16	OK	13004	2026-09-19 11:18	72.94	OK
13005	2026-09-19 11:19	72.12	OK	13006	2026-09-19 11:20	72.69	OK
13007	2026-09-19 11:21	72.44	OK	13008	2026-09-19 11:22	73.24	OK
13009	2026-09-19 11:23	74.43	OK	13010	2026-09-19 11:24	72.75	OK
13011	2026-09-19 11:25	74.83	OK	13012	2026-09-19 11:26	72.47	OK
13013	2026-09-19 11:27	74.01	OK	13014	2026-09-19 11:28	72.44	OK
13015	2026-09-19 11:29	76.10	OK	13016	2026-09-19 11:30	73.91	OK
13017	2026-09-19 11:31	73.13	OK	13018	2026-09-19 11:32	71.18	OK
13019	2026-09-19 11:33	70.70	OK	13020	2026-09-19 11:34	73.46	OK
13021	2026-09-19 11:35	71.09	OK	13022	2026-09-19 11:36	72.80	OK
13023	2026-09-19 11:37	74.16	OK	13024	2026-09-19 11:38	73.73	OK
13025	2026-09-19 11:39	72.44	OK	13026	2026-09-19 11:40	73.27	OK
13027	2026-09-19 11:41	69.97	OK	13028	2026-09-19 11:42	71.16	OK
13029	2026-09-19 11:43	72.76	OK	13030	2026-09-19 11:44	74.23	OK
13031	2026-09-19 11:45	71.67	OK	13032	2026-09-19 11:46	73.41	OK
13033	2026-09-19 11:47	72.68	OK	13034	2026-09-19 11:48	74.10	OK
13035	2026-09-19 11:49	71.99	OK	13036	2026-09-19 11:50	71.14	OK
1303	2026-09-19 11:51	73.18	OK	1303	2026-09-19 11:52	73.96	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
13039	2026-09-19 11:53	72.20	OK	13040	2026-09-19 11:54	72.37	OK
13041	2026-09-19 11:55	73.40	OK	13042	2026-09-19 11:56	73.41	OK
13043	2026-09-19 11:57	72.05	OK	13044	2026-09-19 11:58	74.07	OK
13045	2026-09-19 11:59	73.26	OK	13046	2026-09-19 12:00	74.97	OK
13047	2026-09-19 12:01	70.13	OK	13048	2026-09-19 12:02	72.16	OK
13049	2026-09-19 12:03	74.58	OK	13050	2026-09-19 12:04	72.98	OK
13051	2026-09-19 12:05	71.88	OK	13052	2026-09-19 12:06	70.79	OK
13053	2026-09-19 12:07	71.57	OK	13054	2026-09-19 12:08	71.90	OK
13055	2026-09-19 12:09	72.61	OK	13056	2026-09-19 12:10	72.52	OK
13057	2026-09-19 12:11	73.35	OK	13058	2026-09-19 12:12	72.53	OK
13059	2026-09-19 12:13	75.03	OK	13060	2026-09-19 12:14	73.01	OK
13061	2026-09-19 12:15	71.49	OK	13062	2026-09-19 12:16	71.81	OK
13063	2026-09-19 12:17	71.00	OK	13064	2026-09-19 12:18	71.78	OK
13065	2026-09-19 12:19	73.96	OK	13066	2026-09-19 12:20	70.68	OK
13067	2026-09-19 12:21	72.00	OK	13068	2026-09-19 12:22	71.77	OK
13069	2026-09-19 12:23	71.89	OK	13070	2026-09-19 12:24	73.73	OK
13071	2026-09-19 12:25	74.09	OK	13072	2026-09-19 12:26	70.51	OK
13073	2026-09-19 12:27	71.95	OK	13074	2026-09-19 12:28	71.23	OK
13075	2026-09-19 12:29	72.44	OK	13076	2026-09-19 12:30	74.21	OK
13077	2026-09-19 12:31	72.61	OK	13078	2026-09-19 12:32	72.20	OK
13079	2026-09-19 12:33	73.04	OK	13080	2026-09-19 12:34	71.86	OK
13081	2026-09-19 12:35	71.01	OK	13082	2026-09-19 12:36	74.09	OK
13083	2026-09-19 12:37	71.22	OK	13084	2026-09-19 12:38	71.51	OK
13085	2026-09-19 12:39	71.60	OK	13086	2026-09-19 12:40	72.62	OK
13087	2026-09-19 12:41	71.16	OK	13088	2026-09-19 12:42	74.32	OK
13089	2026-09-19 12:43	71.81	OK	13090	2026-09-19 12:44	72.56	OK
13091	2026-09-19 12:45	74.52	OK	13092	2026-09-19 12:46	69.77	OK
13093	2026-09-19 12:47	73.80	OK	13094	2026-09-19 12:48	71.56	OK
13095	2026-09-19 12:49	71.75	OK	13096	2026-09-19 12:50	72.26	OK
1309	2026-09-19 12:51	71.86	OK	1309	2026-09-19 12:52	70.49	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
13099	2026-09-19 12:53	71.40	OK	13100	2026-09-19 12:54	71.29	OK
13101	2026-09-19 12:55	71.64	OK	13102	2026-09-19 12:56	72.03	OK
13103	2026-09-19 12:57	71.80	OK	13104	2026-09-19 12:58	73.41	OK
13105	2026-09-19 12:59	69.51	OK	13106	2026-09-19 13:00	71.16	OK
13107	2026-09-19 13:01	72.47	OK	13108	2026-09-19 13:02	71.25	OK
13109	2026-09-19 13:03	73.37	OK	13110	2026-09-19 13:04	72.24	OK
13111	2026-09-19 13:05	70.80	OK	13112	2026-09-19 13:06	72.21	OK
13113	2026-09-19 13:07	70.79	OK	13114	2026-09-19 13:08	70.52	OK
13115	2026-09-19 13:09	70.75	OK	13116	2026-09-19 13:10	73.57	OK
13117	2026-09-19 13:11	71.77	OK	13118	2026-09-19 13:12	70.76	OK
13119	2026-09-19 13:13	71.25	OK	13120	2026-09-19 13:14	71.64	OK
13121	2026-09-19 13:15	73.44	OK	13122	2026-09-19 13:16	71.72	OK
13123	2026-09-19 13:17	73.05	OK	13124	2026-09-19 13:18	72.94	OK
13125	2026-09-19 13:19	73.26	OK	13126	2026-09-19 13:20	70.57	OK
13127	2026-09-19 13:21	71.18	OK	13128	2026-09-19 13:22	70.45	OK
13129	2026-09-19 13:23	74.06	OK	13130	2026-09-19 13:24	71.68	OK
13131	2026-09-19 13:25	70.52	OK	13132	2026-09-19 13:26	70.89	OK
13133	2026-09-19 13:27	71.46	OK	13134	2026-09-19 13:28	70.80	OK
13135	2026-09-19 13:29	71.82	OK	13136	2026-09-19 13:30	72.47	OK
13137	2026-09-19 13:31	71.95	OK	13138	2026-09-19 13:32	71.73	OK
13139	2026-09-19 13:33	70.87	OK	13140	2026-09-19 13:34	71.79	OK
13141	2026-09-19 13:35	70.59	OK	13142	2026-09-19 13:36	72.23	OK
13143	2026-09-19 13:37	70.44	OK	13144	2026-09-19 13:38	70.77	OK
13145	2026-09-19 13:39	70.05	OK	13146	2026-09-19 13:40	71.52	OK
13147	2026-09-19 13:41	72.23	OK	13148	2026-09-19 13:42	69.77	OK
13149	2026-09-19 13:43	68.39	OK	13150	2026-09-19 13:44	70.33	OK
13151	2026-09-19 13:45	71.42	OK	13152	2026-09-19 13:46	73.67	OK
13153	2026-09-19 13:47	71.69	OK	13154	2026-09-19 13:48	71.27	OK
13155	2026-09-19 13:49	74.07	OK	13156	2026-09-19 13:50	70.59	OK
1315	2026-09-19 13:51	72.49	OK	1315	2026-09-19 13:52	70.51	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
13159	2026-09-19 13:53	71.36	OK	13160	2026-09-19 13:54	70.44	OK
13161	2026-09-19 13:55	73.03	OK	13162	2026-09-19 13:56	69.94	OK
13163	2026-09-19 13:57	71.39	OK	13164	2026-09-19 13:58	73.99	OK
13165	2026-09-19 13:59	71.02	OK	13166	2026-09-19 14:00	70.57	OK
13167	2026-09-19 14:01	71.84	OK	13168	2026-09-19 14:02	70.90	OK
13169	2026-09-19 14:03	72.29	OK	13170	2026-09-19 14:04	68.79	OK
13171	2026-09-19 14:05	71.80	OK	13172	2026-09-19 14:06	72.11	OK
13173	2026-09-19 14:07	74.34	OK	13174	2026-09-19 14:08	71.41	OK
13175	2026-09-19 14:09	69.95	OK	13176	2026-09-19 14:10	73.48	OK
13177	2026-09-19 14:11	70.39	OK	13178	2026-09-19 14:12	73.56	OK
13179	2026-09-19 14:13	71.66	OK	13180	2026-09-19 14:14	69.59	OK
13181	2026-09-19 14:15	71.57	OK	13182	2026-09-19 14:16	70.34	OK
13183	2026-09-19 14:17	71.30	OK	13184	2026-09-19 14:18	69.73	OK
13185	2026-09-19 14:19	71.85	OK	13186	2026-09-19 14:20	71.29	OK
13187	2026-09-19 14:21	72.95	OK	13188	2026-09-19 14:22	70.98	OK
13189	2026-09-19 14:23	71.68	OK	13190	2026-09-19 14:24	69.89	OK
13191	2026-09-19 14:25	70.70	OK	13192	2026-09-19 14:26	72.03	OK
13193	2026-09-19 14:27	70.67	OK	13194	2026-09-19 14:28	74.13	OK
13195	2026-09-19 14:29	71.39	OK	13196	2026-09-19 14:30	72.22	OK
13197	2026-09-19 14:31	72.61	OK	13198	2026-09-19 14:32	71.90	OK
13199	2026-09-19 14:33	69.80	OK	13200	2026-09-19 14:34	71.83	OK
13201	2026-09-19 14:35	72.25	OK	13202	2026-09-19 14:36	68.70	OK
13203	2026-09-19 14:37	71.61	OK	13204	2026-09-19 14:38	71.36	OK
13205	2026-09-19 14:39	72.21	OK	13206	2026-09-19 14:40	70.64	OK
13207	2026-09-19 14:41	73.80	OK	13208	2026-09-19 14:42	74.35	OK
13209	2026-09-19 14:43	74.24	OK	13210	2026-09-19 14:44	69.47	OK
13211	2026-09-19 14:45	71.16	OK	13212	2026-09-19 14:46	70.40	OK
13213	2026-09-19 14:47	73.86	OK	13214	2026-09-19 14:48	72.97	OK
13215	2026-09-19 14:49	71.94	OK	13216	2026-09-19 14:50	73.27	OK
1321	2026-09-19 14:51	70.36	OK	1321	2026-09-19 14:52	71.12	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
13219	2026-09-19 14:53	72.09	OK	13220	2026-09-19 14:54	69.71	OK
13221	2026-09-19 14:55	71.74	OK	13222	2026-09-19 14:56	72.47	OK
13223	2026-09-19 14:57	73.30	OK	13224	2026-09-19 14:58	71.31	OK
13225	2026-09-19 14:59	69.89	OK	13226	2026-09-19 15:00	72.56	OK
13227	2026-09-19 15:01	71.99	OK	13228	2026-09-19 15:02	72.93	OK
13229	2026-09-19 15:03	70.75	OK	13230	2026-09-19 15:04	72.14	OK
13231	2026-09-19 15:05	72.34	OK	13232	2026-09-19 15:06	71.54	OK
13233	2026-09-19 15:07	72.82	OK	13234	2026-09-19 15:08	71.19	OK
13235	2026-09-19 15:09	71.77	OK	13236	2026-09-19 15:10	71.86	OK
13237	2026-09-19 15:11	71.31	OK	13238	2026-09-19 15:12	70.15	OK
13239	2026-09-19 15:13	73.36	OK	13240	2026-09-19 15:14	71.99	OK
13241	2026-09-19 15:15	72.09	OK	13242	2026-09-19 15:16	71.51	OK
13243	2026-09-19 15:17	71.27	OK	13244	2026-09-19 15:18	69.74	OK
13245	2026-09-19 15:19	69.84	OK	13246	2026-09-19 15:20	70.48	OK
13247	2026-09-19 15:21	70.98	OK	13248	2026-09-19 15:22	72.95	OK
13249	2026-09-19 15:23	70.41	OK	13250	2026-09-19 15:24	72.24	OK
13251	2026-09-19 15:25	70.73	OK	13252	2026-09-19 15:26	69.58	OK
13253	2026-09-19 15:27	72.00	OK	13254	2026-09-19 15:28	71.62	OK
13255	2026-09-19 15:29	71.07	OK	13256	2026-09-19 15:30	73.04	OK
13257	2026-09-19 15:31	70.53	OK	13258	2026-09-19 15:32	71.17	OK
13259	2026-09-19 15:33	70.36	OK	13260	2026-09-19 15:34	72.56	OK
13261	2026-09-19 15:35	72.31	OK	13262	2026-09-19 15:36	71.11	OK
13263	2026-09-19 15:37	72.20	OK	13264	2026-09-19 15:38	70.71	OK
13265	2026-09-19 15:39	70.11	OK	13266	2026-09-19 15:40	72.15	OK
13267	2026-09-19 15:41	72.24	OK	13268	2026-09-19 15:42	69.74	OK
13269	2026-09-19 15:43	71.43	OK	13270	2026-09-19 15:44	70.75	OK
13271	2026-09-19 15:45	70.95	OK	13272	2026-09-19 15:46	72.04	OK
13273	2026-09-19 15:47	72.46	OK	13274	2026-09-19 15:48	71.73	OK
13275	2026-09-19 15:49	72.12	OK	13276	2026-09-19 15:50	68.79	OK
1327	2026-09-19 15:51	73.43	OK	1327	2026-09-19 15:52	70.79	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
13279	2026-09-19 15:53	75.00	OK	13280	2026-09-19 15:54	72.85	OK
13281	2026-09-19 15:55	71.66	OK	13282	2026-09-19 15:56	71.09	OK
13283	2026-09-19 15:57	71.64	OK	13284	2026-09-19 15:58	73.67	OK
13285	2026-09-19 15:59	71.07	OK	13286	2026-09-19 16:00	71.92	OK
13287	2026-09-19 16:01	71.05	OK	13288	2026-09-19 16:02	72.03	OK
13289	2026-09-19 16:03	70.76	OK	13290	2026-09-19 16:04	71.24	OK
13291	2026-09-19 16:05	71.06	OK	13292	2026-09-19 16:06	71.81	OK
13293	2026-09-19 16:07	73.83	OK	13294	2026-09-19 16:08	70.46	OK
13295	2026-09-19 16:09	71.55	OK	13296	2026-09-19 16:10	72.44	OK
13297	2026-09-19 16:11	71.80	OK	13298	2026-09-19 16:12	71.22	OK
13299	2026-09-19 16:13	69.00	OK	13300	2026-09-19 16:14	72.64	OK
13301	2026-09-19 16:15	72.22	OK	13302	2026-09-19 16:16	69.63	OK
13303	2026-09-19 16:17	72.25	OK	13304	2026-09-19 16:18	73.28	OK
13305	2026-09-19 16:19	72.25	OK	13306	2026-09-19 16:20	72.46	OK
13307	2026-09-19 16:21	70.53	OK	13308	2026-09-19 16:22	70.27	OK
13309	2026-09-19 16:23	73.88	OK	13310	2026-09-19 16:24	70.19	OK
13311	2026-09-19 16:25	73.35	OK	13312	2026-09-19 16:26	72.23	OK
13313	2026-09-19 16:27	72.27	OK	13314	2026-09-19 16:28	71.13	OK
13315	2026-09-19 16:29	71.20	OK	13316	2026-09-19 16:30	71.28	OK
13317	2026-09-19 16:31	72.15	OK	13318	2026-09-19 16:32	68.74	OK
13319	2026-09-19 16:33	71.55	OK	13320	2026-09-19 16:34	74.81	OK
13321	2026-09-19 16:35	70.39	OK	13322	2026-09-19 16:36	74.46	OK
13323	2026-09-19 16:37	72.62	OK	13324	2026-09-19 16:38	73.89	OK
13325	2026-09-19 16:39	69.90	OK	13326	2026-09-19 16:40	70.06	OK
13327	2026-09-19 16:41	73.78	OK	13328	2026-09-19 16:42	70.59	OK
13329	2026-09-19 16:43	72.44	OK	13330	2026-09-19 16:44	73.44	OK
13331	2026-09-19 16:45	72.36	OK	13332	2026-09-19 16:46	71.16	OK
13333	2026-09-19 16:47	72.27	OK	13334	2026-09-19 16:48	73.90	OK
13335	2026-09-19 16:49	70.24	OK	13336	2026-09-19 16:50	72.81	OK
1333	2026-09-19 16:51	71.32	OK	1333	2026-09-19 16:52	72.22	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
13339	2026-09-19 16:53	73.00	OK	13340	2026-09-19 16:54	72.38	OK
13341	2026-09-19 16:55	69.68	OK	13342	2026-09-19 16:56	69.73	OK
13343	2026-09-19 16:57	72.25	OK	13344	2026-09-19 16:58	73.85	OK
13345	2026-09-19 16:59	72.20	OK	13346	2026-09-19 17:00	72.19	OK
13347	2026-09-19 17:01	73.27	OK	13348	2026-09-19 17:02	72.91	OK
13349	2026-09-19 17:03	72.35	OK	13350	2026-09-19 17:04	72.07	OK
13351	2026-09-19 17:05	71.91	OK	13352	2026-09-19 17:06	72.63	OK
13353	2026-09-19 17:07	72.28	OK	13354	2026-09-19 17:08	72.34	OK
13355	2026-09-19 17:09	72.14	OK	13356	2026-09-19 17:10	72.22	OK
13357	2026-09-19 17:11	73.52	OK	13358	2026-09-19 17:12	71.83	OK
13359	2026-09-19 17:13	71.66	OK	13360	2026-09-19 17:14	71.29	OK
13361	2026-09-19 17:15	72.24	OK	13362	2026-09-19 17:16	71.08	OK
13363	2026-09-19 17:17	71.11	OK	13364	2026-09-19 17:18	74.44	OK
13365	2026-09-19 17:19	70.88	OK	13366	2026-09-19 17:20	71.97	OK
13367	2026-09-19 17:21	73.07	OK	13368	2026-09-19 17:22	73.81	OK
13369	2026-09-19 17:23	72.76	OK	13370	2026-09-19 17:24	72.92	OK
13371	2026-09-19 17:25	71.20	OK	13372	2026-09-19 17:26	72.80	OK
13373	2026-09-19 17:27	69.91	OK	13374	2026-09-19 17:28	71.67	OK
13375	2026-09-19 17:29	74.84	OK	13376	2026-09-19 17:30	73.54	OK
13377	2026-09-19 17:31	73.62	OK	13378	2026-09-19 17:32	70.23	OK
13379	2026-09-19 17:33	74.29	OK	13380	2026-09-19 17:34	74.52	OK
13381	2026-09-19 17:35	73.26	OK	13382	2026-09-19 17:36	71.40	OK
13383	2026-09-19 17:37	73.97	OK	13384	2026-09-19 17:38	74.44	OK
13385	2026-09-19 17:39	74.09	OK	13386	2026-09-19 17:40	71.70	OK
13387	2026-09-19 17:41	71.78	OK	13388	2026-09-19 17:42	69.16	OK
13389	2026-09-19 17:43	71.85	OK	13390	2026-09-19 17:44	73.64	OK
13391	2026-09-19 17:45	73.23	OK	13392	2026-09-19 17:46	71.61	OK
13393	2026-09-19 17:47	71.37	OK	13394	2026-09-19 17:48	74.02	OK
13395	2026-09-19 17:49	73.72	OK	13396	2026-09-19 17:50	72.10	OK
1339	2026-09-19 17:51	74.68	OK	1339	2026-09-19 17:52	71.79	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
13399	2026-09-19 17:53	71.34	OK	13400	2026-09-19 17:54	72.83	OK
13401	2026-09-19 17:55	75.68	OK	13402	2026-09-19 17:56	71.88	OK
13403	2026-09-19 17:57	72.44	OK	13404	2026-09-19 17:58	73.78	OK
13405	2026-09-19 17:59	73.18	OK	13406	2026-09-19 18:00	73.83	OK
13407	2026-09-19 18:01	70.27	OK	13408	2026-09-19 18:02	75.35	OK
13409	2026-09-19 18:03	71.88	OK	13410	2026-09-19 18:04	74.88	OK
13411	2026-09-19 18:05	72.68	OK	13412	2026-09-19 18:06	74.11	OK
13413	2026-09-19 18:07	73.83	OK	13414	2026-09-19 18:08	74.06	OK
13415	2026-09-19 18:09	72.39	OK	13416	2026-09-19 18:10	72.33	OK
13417	2026-09-19 18:11	73.24	OK	13418	2026-09-19 18:12	72.08	OK
13419	2026-09-19 18:13	73.78	OK	13420	2026-09-19 18:14	72.43	OK
13421	2026-09-19 18:15	72.48	OK	13422	2026-09-19 18:16	74.25	OK
13423	2026-09-19 18:17	73.16	OK	13424	2026-09-19 18:18	72.84	OK
13425	2026-09-19 18:19	71.36	OK	13426	2026-09-19 18:20	72.82	OK
13427	2026-09-19 18:21	72.71	OK	13428	2026-09-19 18:22	72.51	OK
13429	2026-09-19 18:23	73.74	OK	13430	2026-09-19 18:24	73.18	OK
13431	2026-09-19 18:25	72.51	OK	13432	2026-09-19 18:26	72.63	OK
13433	2026-09-19 18:27	73.09	OK	13434	2026-09-19 18:28	73.99	OK
13435	2026-09-19 18:29	72.69	OK	13436	2026-09-19 18:30	74.43	OK
13437	2026-09-19 18:31	72.97	OK	13438	2026-09-19 18:32	76.04	OK
13439	2026-09-19 18:33	74.94	OK	13440	2026-09-19 18:34	73.94	OK
13441	2026-09-19 18:35	74.52	OK	13442	2026-09-19 18:36	74.50	OK
13443	2026-09-19 18:37	73.62	OK	13444	2026-09-19 18:38	75.55	OK
13445	2026-09-19 18:39	73.15	OK	13446	2026-09-19 18:40	75.05	OK
13447	2026-09-19 18:41	74.20	OK	13448	2026-09-19 18:42	72.55	OK
13449	2026-09-19 18:43	74.16	OK	13450	2026-09-19 18:44	72.28	OK
13451	2026-09-19 18:45	73.88	OK	13452	2026-09-19 18:46	74.52	OK
13453	2026-09-19 18:47	75.32	OK	13454	2026-09-19 18:48	74.09	OK
13455	2026-09-19 18:49	72.29	OK	13456	2026-09-19 18:50	73.24	OK
1345	2026-09-19 18:51	72.78	OK	1345	2026-09-19 18:52	73.02	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
13459	2026-09-19 18:53	73.01	OK	13460	2026-09-19 18:54	73.06	OK
13461	2026-09-19 18:55	75.04	OK	13462	2026-09-19 18:56	75.96	OK
13463	2026-09-19 18:57	73.08	OK	13464	2026-09-19 18:58	75.05	OK
13465	2026-09-19 18:59	73.10	OK	13466	2026-09-19 19:00	75.76	OK
13467	2026-09-19 19:01	73.87	OK	13468	2026-09-19 19:02	74.03	OK
13469	2026-09-19 19:03	74.36	OK	13470	2026-09-19 19:04	77.51	OK
13471	2026-09-19 19:05	73.13	OK	13472	2026-09-19 19:06	73.51	OK
13473	2026-09-19 19:07	74.76	OK	13474	2026-09-19 19:08	75.26	OK
13475	2026-09-19 19:09	75.55	OK	13476	2026-09-19 19:10	73.13	OK
13477	2026-09-19 19:11	75.57	OK	13478	2026-09-19 19:12	74.07	OK
13479	2026-09-19 19:13	72.43	OK	13480	2026-09-19 19:14	76.18	OK
13481	2026-09-19 19:15	73.88	OK	13482	2026-09-19 19:16	71.99	OK
13483	2026-09-19 19:17	74.53	OK	13484	2026-09-19 19:18	76.54	OK
13485	2026-09-19 19:19	71.56	OK	13486	2026-09-19 19:20	73.56	OK
13487	2026-09-19 19:21	76.38	OK	13488	2026-09-19 19:22	75.39	OK
13489	2026-09-19 19:23	75.22	OK	13490	2026-09-19 19:24	72.71	OK
13491	2026-09-19 19:25	74.51	OK	13492	2026-09-19 19:26	75.59	OK
13493	2026-09-19 19:27	75.38	OK	13494	2026-09-19 19:28	74.29	OK
13495	2026-09-19 19:29	73.69	OK	13496	2026-09-19 19:30	74.66	OK
13497	2026-09-19 19:31	76.51	OK	13498	2026-09-19 19:32	73.87	OK
13499	2026-09-19 19:33	74.28	OK	13500	2026-09-19 19:34	74.15	OK
13501	2026-09-19 19:35	73.39	OK	13502	2026-09-19 19:36	74.53	OK
13503	2026-09-19 19:37	76.96	OK	13504	2026-09-19 19:38	74.03	OK
13505	2026-09-19 19:39	73.94	OK	13506	2026-09-19 19:40	75.02	OK
13507	2026-09-19 19:41	75.50	OK	13508	2026-09-19 19:42	72.64	OK
13509	2026-09-19 19:43	74.44	OK	13510	2026-09-19 19:44	74.49	OK
13511	2026-09-19 19:45	77.08	OK	13512	2026-09-19 19:46	73.89	OK
13513	2026-09-19 19:47	74.80	OK	13514	2026-09-19 19:48	74.28	OK
13515	2026-09-19 19:49	75.68	OK	13516	2026-09-19 19:50	74.27	OK
1351	2026-09-19 19:51	75.24	OK	1351	2026-09-19 19:52	75.96	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
13519	2026-09-19 19:53	78.23	OK	13520	2026-09-19 19:54	76.73	OK
13521	2026-09-19 19:55	76.02	OK	13522	2026-09-19 19:56	74.56	OK
13523	2026-09-19 19:57	75.55	OK	13524	2026-09-19 19:58	73.86	OK
13525	2026-09-19 19:59	74.68	OK	13526	2026-09-19 20:00	75.46	OK
13527	2026-09-19 20:01	75.51	OK	13528	2026-09-19 20:02	76.09	OK
13529	2026-09-19 20:03	73.48	OK	13530	2026-09-19 20:04	75.58	OK
13531	2026-09-19 20:05	76.47	OK	13532	2026-09-19 20:06	75.10	OK
13533	2026-09-19 20:07	77.85	OK	13534	2026-09-19 20:08	73.02	OK
13535	2026-09-19 20:09	75.98	OK	13536	2026-09-19 20:10	75.83	OK
13537	2026-09-19 20:11	76.63	OK	13538	2026-09-19 20:12	76.25	OK
13539	2026-09-19 20:13	75.61	OK	13540	2026-09-19 20:14	73.61	OK
13541	2026-09-19 20:15	77.61	OK	13542	2026-09-19 20:16	74.53	OK
13543	2026-09-19 20:17	76.24	OK	13544	2026-09-19 20:18	75.23	OK
13545	2026-09-19 20:19	73.79	OK	13546	2026-09-19 20:20	79.03	OK
13547	2026-09-19 20:21	75.52	OK	13548	2026-09-19 20:22	77.01	OK
13549	2026-09-19 20:23	74.91	OK	13550	2026-09-19 20:24	76.15	OK
13551	2026-09-19 20:25	77.12	OK	13552	2026-09-19 20:26	75.67	OK
13553	2026-09-19 20:27	75.79	OK	13554	2026-09-19 20:28	76.83	OK
13555	2026-09-19 20:29	76.79	OK	13556	2026-09-19 20:30	76.71	OK
13557	2026-09-19 20:31	76.52	OK	13558	2026-09-19 20:32	76.99	OK
13559	2026-09-19 20:33	75.17	OK	13560	2026-09-19 20:34	75.93	OK
13561	2026-09-19 20:35	76.22	OK	13562	2026-09-19 20:36	76.14	OK
13563	2026-09-19 20:37	75.41	OK	13564	2026-09-19 20:38	75.04	OK
13565	2026-09-19 20:39	75.00	OK	13566	2026-09-19 20:40	76.23	OK
13567	2026-09-19 20:41	76.54	OK	13568	2026-09-19 20:42	76.53	OK
13569	2026-09-19 20:43	76.05	OK	13570	2026-09-19 20:44	75.18	OK
13571	2026-09-19 20:45	75.84	OK	13572	2026-09-19 20:46	76.64	OK
13573	2026-09-19 20:47	75.82	OK	13574	2026-09-19 20:48	78.44	OK
13575	2026-09-19 20:49	79.53	OK	13576	2026-09-19 20:50	76.29	OK
1357	2026-09-19 20:51	75.83	OK	1357	2026-09-19 20:52	74.61	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
13579	2026-09-19 20:53	75.02	OK	13580	2026-09-19 20:54	76.37	OK
13581	2026-09-19 20:55	75.53	OK	13582	2026-09-19 20:56	78.98	OK
13583	2026-09-19 20:57	74.92	OK	13584	2026-09-19 20:58	74.94	OK
13585	2026-09-19 20:59	76.83	OK	13586	2026-09-19 21:00	76.80	OK
13587	2026-09-19 21:01	75.87	OK	13588	2026-09-19 21:02	75.08	OK
13589	2026-09-19 21:03	75.44	OK	13590	2026-09-19 21:04	77.21	OK
13591	2026-09-19 21:05	75.20	OK	13592	2026-09-19 21:06	75.24	OK
13593	2026-09-19 21:07	76.97	OK	13594	2026-09-19 21:08	76.97	OK
13595	2026-09-19 21:09	79.53	OK	13596	2026-09-19 21:10	76.09	OK
13597	2026-09-19 21:11	75.51	OK	13598	2026-09-19 21:12	76.81	OK
13599	2026-09-19 21:13	76.39	OK	13600	2026-09-19 21:14	78.07	OK
13601	2026-09-19 21:15	76.52	OK	13602	2026-09-19 21:16	78.45	OK
13603	2026-09-19 21:17	77.66	OK	13604	2026-09-19 21:18	77.97	OK
13605	2026-09-19 21:19	75.53	OK	13606	2026-09-19 21:20	76.93	OK
13607	2026-09-19 21:21	76.04	OK	13608	2026-09-19 21:22	76.53	OK
13609	2026-09-19 21:23	76.68	OK	13610	2026-09-19 21:24	77.35	OK
13611	2026-09-19 21:25	73.76	OK	13612	2026-09-19 21:26	77.42	OK
13613	2026-09-19 21:27	80.37	OK	13614	2026-09-19 21:28	77.10	OK
13615	2026-09-19 21:29	77.05	OK	13616	2026-09-19 21:30	76.22	OK
13617	2026-09-19 21:31	77.04	OK	13618	2026-09-19 21:32	77.12	OK
13619	2026-09-19 21:33	77.62	OK	13620	2026-09-19 21:34	77.58	OK
13621	2026-09-19 21:35	77.83	OK	13622	2026-09-19 21:36	77.97	OK
13623	2026-09-19 21:37	76.97	OK	13624	2026-09-19 21:38	76.96	OK
13625	2026-09-19 21:39	76.60	OK	13626	2026-09-19 21:40	79.26	OK
13627	2026-09-19 21:41	78.45	OK	13628	2026-09-19 21:42	77.73	OK
13629	2026-09-19 21:43	76.98	OK	13630	2026-09-19 21:44	75.27	OK
13631	2026-09-19 21:45	76.97	OK	13632	2026-09-19 21:46	79.47	OK
13633	2026-09-19 21:47	77.43	OK	13634	2026-09-19 21:48	79.57	OK
13635	2026-09-19 21:49	78.75	OK	13636	2026-09-19 21:50	78.16	OK
1363	2026-09-19 21:51	77.73	OK	1363	2026-09-19 21:52	78.38	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
13639	2026-09-19 21:53	79.19	OK	13640	2026-09-19 21:54	75.38	OK
13641	2026-09-19 21:55	77.04	OK	13642	2026-09-19 21:56	80.14	OK
13643	2026-09-19 21:57	78.78	OK	13644	2026-09-19 21:58	79.92	OK
13645	2026-09-19 21:59	76.63	OK	13646	2026-09-19 22:00	78.39	OK
13647	2026-09-19 22:01	80.10	OK	13648	2026-09-19 22:02	77.04	OK
13649	2026-09-19 22:03	77.22	OK	13650	2026-09-19 22:04	78.13	OK
13651	2026-09-19 22:05	79.50	OK	13652	2026-09-19 22:06	78.05	OK
13653	2026-09-19 22:07	78.30	OK	13654	2026-09-19 22:08	79.29	OK
13655	2026-09-19 22:09	76.81	OK	13656	2026-09-19 22:10	79.89	OK
13657	2026-09-19 22:11	76.14	OK	13658	2026-09-19 22:12	76.42	OK
13659	2026-09-19 22:13	78.48	OK	13660	2026-09-19 22:14	77.90	OK
13661	2026-09-19 22:15	77.66	OK	13662	2026-09-19 22:16	78.22	OK
13663	2026-09-19 22:17	78.62	OK	13664	2026-09-19 22:18	79.77	OK
13665	2026-09-19 22:19	77.83	OK	13666	2026-09-19 22:20	79.00	OK
13667	2026-09-19 22:21	76.31	OK	13668	2026-09-19 22:22	76.57	OK
13669	2026-09-19 22:23	78.13	OK	13670	2026-09-19 22:24	79.80	OK
13671	2026-09-19 22:25	80.33	OK	13672	2026-09-19 22:26	80.66	OK
13673	2026-09-19 22:27	80.42	OK	13674	2026-09-19 22:28	81.15	OK
13675	2026-09-19 22:29	77.72	OK	13676	2026-09-19 22:30	80.59	OK
13677	2026-09-19 22:31	78.17	OK	13678	2026-09-19 22:32	78.89	OK
13679	2026-09-19 22:33	77.45	OK	13680	2026-09-19 22:34	79.66	OK
13681	2026-09-19 22:35	76.65	OK	13682	2026-09-19 22:36	79.38	OK
13683	2026-09-19 22:37	78.01	OK	13684	2026-09-19 22:38	80.47	OK
13685	2026-09-19 22:39	79.38	OK	13686	2026-09-19 22:40	80.97	OK
13687	2026-09-19 22:41	79.16	OK	13688	2026-09-19 22:42	80.89	OK
13689	2026-09-19 22:43	77.82	OK	13690	2026-09-19 22:44	78.18	OK
13691	2026-09-19 22:45	79.32	OK	13692	2026-09-19 22:46	76.40	OK
13693	2026-09-19 22:47	79.52	OK	13694	2026-09-19 22:48	80.08	OK
13695	2026-09-19 22:49	77.62	OK	13696	2026-09-19 22:50	78.99	OK
1369	2026-09-19 22:51	79.91	OK	1369	2026-09-19 22:52	77.29	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
13699	2026-09-19 22:53	78.75	OK	13700	2026-09-19 22:54	80.14	OK
13701	2026-09-19 22:55	80.29	OK	13702	2026-09-19 22:56	77.58	OK
13703	2026-09-19 22:57	79.79	OK	13704	2026-09-19 22:58	79.92	OK
13705	2026-09-19 22:59	78.00	OK	13706	2026-09-19 23:00	79.60	OK
13707	2026-09-19 23:01	80.57	OK	13708	2026-09-19 23:02	79.63	OK
13709	2026-09-19 23:03	77.97	OK	13710	2026-09-19 23:04	78.13	OK
13711	2026-09-19 23:05	78.04	OK	13712	2026-09-19 23:06	80.28	OK
13713	2026-09-19 23:07	81.11	OK	13714	2026-09-19 23:08	80.31	OK
13715	2026-09-19 23:09	78.69	OK	13716	2026-09-19 23:10	81.63	OK
13717	2026-09-19 23:11	78.22	OK	13718	2026-09-19 23:12	78.01	OK
13719	2026-09-19 23:13	78.89	OK	13720	2026-09-19 23:14	78.69	OK
13721	2026-09-19 23:15	78.35	OK	13722	2026-09-19 23:16	80.95	OK
13723	2026-09-19 23:17	77.16	OK	13724	2026-09-19 23:18	79.71	OK
13725	2026-09-19 23:19	77.82	OK	13726	2026-09-19 23:20	77.77	OK
13727	2026-09-19 23:21	77.42	OK	13728	2026-09-19 23:22	80.96	OK
13729	2026-09-19 23:23	80.67	OK	13730	2026-09-19 23:24	78.90	OK
13731	2026-09-19 23:25	80.71	OK	13732	2026-09-19 23:26	79.14	OK
13733	2026-09-19 23:27	79.13	OK	13734	2026-09-19 23:28	78.61	OK
13735	2026-09-19 23:29	79.35	OK	13736	2026-09-19 23:30	79.04	OK
13737	2026-09-19 23:31	79.40	OK	13738	2026-09-19 23:32	78.31	OK
13739	2026-09-19 23:33	79.26	OK	13740	2026-09-19 23:34	80.16	OK
13741	2026-09-19 23:35	79.48	OK	13742	2026-09-19 23:36	81.27	OK
13743	2026-09-19 23:37	81.49	OK	13744	2026-09-19 23:38	78.37	OK
13745	2026-09-19 23:39	80.90	OK	13746	2026-09-19 23:40	79.57	OK
13747	2026-09-19 23:41	78.74	OK	13748	2026-09-19 23:42	80.09	OK
13749	2026-09-19 23:43	81.03	OK	13750	2026-09-19 23:44	81.16	OK
13751	2026-09-19 23:45	81.22	OK	13752	2026-09-19 23:46	80.36	OK
13753	2026-09-19 23:47	79.44	OK	13754	2026-09-19 23:48	80.73	OK
13755	2026-09-19 23:49	81.83	OK	13756	2026-09-19 23:50	79.77	OK
1375	2026-09-19 23:51	79.22	OK	1375	2026-09-19 23:52	77.45	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
13759	2026-09-19 23:53	78.63	OK	13760	2026-09-19 23:54	81.94	OK
13761	2026-09-19 23:55	79.50	OK	13762	2026-09-19 23:56	80.32	OK
13763	2026-09-19 23:57	80.49	OK	13764	2026-09-19 23:58	81.00	OK
13765	2026-09-19 23:59	79.10	OK	13766	2026-09-20 00:00	82.49	OK
13767	2026-09-20 00:01	83.28	OK	13768	2026-09-20 00:02	79.13	OK
13769	2026-09-20 00:03	83.30	OK	13770	2026-09-20 00:04	78.83	OK
13771	2026-09-20 00:05	81.42	OK	13772	2026-09-20 00:06	81.34	OK
13773	2026-09-20 00:07	81.86	OK	13774	2026-09-20 00:08	82.73	OK
13775	2026-09-20 00:09	81.90	OK	13776	2026-09-20 00:10	78.37	OK
13777	2026-09-20 00:11	82.14	OK	13778	2026-09-20 00:12	81.19	OK
13779	2026-09-20 00:13	79.07	OK	13780	2026-09-20 00:14	79.91	OK
13781	2026-09-20 00:15	80.75	OK	13782	2026-09-20 00:16	81.74	OK
13783	2026-09-20 00:17	81.12	OK	13784	2026-09-20 00:18	82.68	OK
13785	2026-09-20 00:19	79.45	OK	13786	2026-09-20 00:20	81.09	OK
13787	2026-09-20 00:21	79.84	OK	13788	2026-09-20 00:22	79.09	OK
13789	2026-09-20 00:23	81.94	OK	13790	2026-09-20 00:24	80.29	OK
13791	2026-09-20 00:25	78.35	OK	13792	2026-09-20 00:26	78.67	OK
13793	2026-09-20 00:27	79.38	OK	13794	2026-09-20 00:28	80.46	OK
13795	2026-09-20 00:29	81.15	OK	13796	2026-09-20 00:30	82.14	OK
13797	2026-09-20 00:31	80.12	OK	13798	2026-09-20 00:32	82.18	OK
13799	2026-09-20 00:33	80.76	OK	13800	2026-09-20 00:34	82.26	OK
13801	2026-09-20 00:35	83.53	OK	13802	2026-09-20 00:36	81.82	OK
13803	2026-09-20 00:37	80.08	OK	13804	2026-09-20 00:38	81.45	OK
13805	2026-09-20 00:39	79.41	OK	13806	2026-09-20 00:40	80.97	OK
13807	2026-09-20 00:41	81.09	OK	13808	2026-09-20 00:42	79.37	OK
13809	2026-09-20 00:43	82.43	OK	13810	2026-09-20 00:44	82.28	OK
13811	2026-09-20 00:45	83.32	OK	13812	2026-09-20 00:46	81.58	OK
13813	2026-09-20 00:47	81.25	OK	13814	2026-09-20 00:48	80.72	OK
13815	2026-09-20 00:49	78.36	OK	13816	2026-09-20 00:50	78.87	OK
1381	2026-09-20 00:51	81.55	OK	1381	2026-09-20 00:52	83.01	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
13819	2026-09-20 00:53	81.53	OK	13820	2026-09-20 00:54	81.44	OK
13821	2026-09-20 00:55	81.63	OK	13822	2026-09-20 00:56	82.25	OK
13823	2026-09-20 00:57	80.64	OK	13824	2026-09-20 00:58	82.57	OK
13825	2026-09-20 00:59	82.30	OK	13826	2026-09-20 01:00	80.54	OK
13827	2026-09-20 01:01	80.06	OK	13828	2026-09-20 01:02	80.64	OK
13829	2026-09-20 01:03	81.21	OK	13830	2026-09-20 01:04	82.27	OK
13831	2026-09-20 01:05	80.68	OK	13832	2026-09-20 01:06	80.75	OK
13833	2026-09-20 01:07	80.23	OK	13834	2026-09-20 01:08	81.66	OK
13835	2026-09-20 01:09	80.40	OK	13836	2026-09-20 01:10	80.80	OK
13837	2026-09-20 01:11	81.47	OK	13838	2026-09-20 01:12	80.26	OK
13839	2026-09-20 01:13	81.94	OK	13840	2026-09-20 01:14	81.19	OK
13841	2026-09-20 01:15	80.47	OK	13842	2026-09-20 01:16	81.84	OK
13843	2026-09-20 01:17	82.87	OK	13844	2026-09-20 01:18	78.52	OK
13845	2026-09-20 01:19	82.06	OK	13846	2026-09-20 01:20	81.73	OK
13847	2026-09-20 01:21	84.42	OK	13848	2026-09-20 01:22	81.25	OK
13849	2026-09-20 01:23	81.75	OK	13850	2026-09-20 01:24	79.66	OK
13851	2026-09-20 01:25	81.92	OK	13852	2026-09-20 01:26	81.51	OK
13853	2026-09-20 01:27	83.56	OK	13854	2026-09-20 01:28	83.97	OK
13855	2026-09-20 01:29	79.45	OK	13856	2026-09-20 01:30	81.35	OK
13857	2026-09-20 01:31	78.98	OK	13858	2026-09-20 01:32	82.67	OK
13859	2026-09-20 01:33	82.24	OK	13860	2026-09-20 01:34	80.32	OK
13861	2026-09-20 01:35	82.62	OK	13862	2026-09-20 01:36	80.68	OK
13863	2026-09-20 01:37	81.02	OK	13864	2026-09-20 01:38	80.45	OK
13865	2026-09-20 01:39	83.94	OK	13866	2026-09-20 01:40	83.75	OK
13867	2026-09-20 01:41	79.14	OK	13868	2026-09-20 01:42	83.39	OK
13869	2026-09-20 01:43	79.23	OK	13870	2026-09-20 01:44	80.36	OK
13871	2026-09-20 01:45	82.74	OK	13872	2026-09-20 01:46	83.69	OK
13873	2026-09-20 01:47	81.58	OK	13874	2026-09-20 01:48	80.46	OK
13875	2026-09-20 01:49	81.80	OK	13876	2026-09-20 01:50	80.51	OK
1387	2026-09-20 01:51	82.56	OK	1387	2026-09-20 01:52	80.87	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
13879	2026-09-20 01:53	81.01	OK	13880	2026-09-20 01:54	82.86	OK
13881	2026-09-20 01:55	80.72	OK	13882	2026-09-20 01:56	81.58	OK
13883	2026-09-20 01:57	81.15	OK	13884	2026-09-20 01:58	82.55	OK
13885	2026-09-20 01:59	79.98	OK	13886	2026-09-20 02:00	80.39	OK
13887	2026-09-20 02:01	83.64	OK	13888	2026-09-20 02:02	80.70	OK
13889	2026-09-20 02:03	80.81	OK	13890	2026-09-20 02:04	79.59	OK
13891	2026-09-20 02:05	79.94	OK	13892	2026-09-20 02:06	82.10	OK
13893	2026-09-20 02:07	82.11	OK	13894	2026-09-20 02:08	80.71	OK
13895	2026-09-20 02:09	79.47	OK	13896	2026-09-20 02:10	82.58	OK
13897	2026-09-20 02:11	80.58	OK	13898	2026-09-20 02:12	81.85	OK
13899	2026-09-20 02:13	81.00	OK	13900	2026-09-20 02:14	83.15	OK
13901	2026-09-20 02:15	82.22	OK	13902	2026-09-20 02:16	81.90	OK
13903	2026-09-20 02:17	82.38	OK	13904	2026-09-20 02:18	81.85	OK
13905	2026-09-20 02:19	82.58	OK	13906	2026-09-20 02:20	82.84	OK
13907	2026-09-20 02:21	80.65	OK	13908	2026-09-20 02:22	82.00	OK
13909	2026-09-20 02:23	82.90	OK	13910	2026-09-20 02:24	81.12	OK
13911	2026-09-20 02:25	83.04	OK	13912	2026-09-20 02:26	80.52	OK
13913	2026-09-20 02:27	82.05	OK	13914	2026-09-20 02:28	79.98	OK
13915	2026-09-20 02:29	79.96	OK	13916	2026-09-20 02:30	80.79	OK
13917	2026-09-20 02:31	83.11	OK	13918	2026-09-20 02:32	83.00	OK
13919	2026-09-20 02:33	80.85	OK	13920	2026-09-20 02:34	81.98	OK
13921	2026-09-20 02:35	83.59	OK	13922	2026-09-20 02:36	82.47	OK
13923	2026-09-20 02:37	82.30	OK	13924	2026-09-20 02:38	82.66	OK
13925	2026-09-20 02:39	82.19	OK	13926	2026-09-20 02:40	80.93	OK
13927	2026-09-20 02:41	80.64	OK	13928	2026-09-20 02:42	84.34	OK
13929	2026-09-20 02:43	80.32	OK	13930	2026-09-20 02:44	82.68	OK
13931	2026-09-20 02:45	81.58	OK	13932	2026-09-20 02:46	81.63	OK
13933	2026-09-20 02:47	83.09	OK	13934	2026-09-20 02:48	84.93	OK
13935	2026-09-20 02:49	81.25	OK	13936	2026-09-20 02:50	82.68	OK
1393	2026-09-20 02:51	82.95	OK	1393	2026-09-20 02:52	81.06	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
13939	2026-09-20 02:53	82.95	OK	13940	2026-09-20 02:54	80.25	OK
13941	2026-09-20 02:55	80.63	OK	13942	2026-09-20 02:56	83.04	OK
13943	2026-09-20 02:57	82.85	OK	13944	2026-09-20 02:58	81.43	OK
13945	2026-09-20 02:59	83.12	OK	13946	2026-09-20 03:00	80.57	OK
13947	2026-09-20 03:01	80.64	OK	13948	2026-09-20 03:02	81.21	OK
13949	2026-09-20 03:03	82.60	OK	13950	2026-09-20 03:04	81.83	OK
13951	2026-09-20 03:05	81.35	OK	13952	2026-09-20 03:06	82.31	OK
13953	2026-09-20 03:07	80.13	OK	13954	2026-09-20 03:08	81.10	OK
13955	2026-09-20 03:09	81.99	OK	13956	2026-09-20 03:10	83.22	OK
13957	2026-09-20 03:11	82.76	OK	13958	2026-09-20 03:12	79.59	OK
13959	2026-09-20 03:13	81.69	OK	13960	2026-09-20 03:14	80.22	OK
13961	2026-09-20 03:15	81.20	OK	13962	2026-09-20 03:16	79.77	OK
13963	2026-09-20 03:17	81.13	OK	13964	2026-09-20 03:18	81.18	OK
13965	2026-09-20 03:19	81.04	OK	13966	2026-09-20 03:20	82.45	OK
13967	2026-09-20 03:21	81.72	OK	13968	2026-09-20 03:22	82.46	OK
13969	2026-09-20 03:23	82.11	OK	13970	2026-09-20 03:24	81.28	OK
13971	2026-09-20 03:25	80.45	OK	13972	2026-09-20 03:26	82.45	OK
13973	2026-09-20 03:27	81.78	OK	13974	2026-09-20 03:28	81.32	OK
13975	2026-09-20 03:29	82.49	OK	13976	2026-09-20 03:30	81.18	OK
13977	2026-09-20 03:31	81.98	OK	13978	2026-09-20 03:32	78.57	OK
13979	2026-09-20 03:33	82.41	OK	13980	2026-09-20 03:34	80.38	OK
13981	2026-09-20 03:35	81.08	OK	13982	2026-09-20 03:36	78.96	OK
13983	2026-09-20 03:37	83.77	OK	13984	2026-09-20 03:38	80.65	OK
13985	2026-09-20 03:39	81.40	OK	13986	2026-09-20 03:40	82.98	OK
13987	2026-09-20 03:41	79.80	OK	13988	2026-09-20 03:42	81.67	OK
13989	2026-09-20 03:43	81.35	OK	13990	2026-09-20 03:44	80.92	OK
13991	2026-09-20 03:45	81.74	OK	13992	2026-09-20 03:46	82.69	OK
13993	2026-09-20 03:47	83.56	OK	13994	2026-09-20 03:48	80.09	OK
13995	2026-09-20 03:49	78.82	OK	13996	2026-09-20 03:50	80.40	OK
13997	2026-09-20 03:51	80.98	OK	13997	2026-09-20 03:52	82.25	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
13999	2026-09-20 03:53	80.30	OK	14000	2026-09-20 03:54	81.20	OK
14001	2026-09-20 03:55	82.71	OK	14002	2026-09-20 03:56	80.71	OK
14003	2026-09-20 03:57	82.06	OK	14004	2026-09-20 03:58	82.51	OK
14005	2026-09-20 03:59	82.81	OK	14006	2026-09-20 04:00	83.31	OK
14007	2026-09-20 04:01	82.39	OK	14008	2026-09-20 04:02	82.54	OK
14009	2026-09-20 04:03	83.01	OK	14010	2026-09-20 04:04	82.25	OK
14011	2026-09-20 04:05	81.65	OK	14012	2026-09-20 04:06	79.62	OK
14013	2026-09-20 04:07	80.97	OK	14014	2026-09-20 04:08	83.00	OK
14015	2026-09-20 04:09	82.46	OK	14016	2026-09-20 04:10	80.54	OK
14017	2026-09-20 04:11	84.87	OK	14018	2026-09-20 04:12	81.11	OK
14019	2026-09-20 04:13	83.02	OK	14020	2026-09-20 04:14	81.11	OK
14021	2026-09-20 04:15	82.29	OK	14022	2026-09-20 04:16	81.46	OK
14023	2026-09-20 04:17	79.41	OK	14024	2026-09-20 04:18	82.21	OK
14025	2026-09-20 04:19	81.10	OK	14026	2026-09-20 04:20	82.64	OK
14027	2026-09-20 04:21	80.49	OK	14028	2026-09-20 04:22	83.38	OK
14029	2026-09-20 04:23	81.14	OK	14030	2026-09-20 04:24	81.15	OK
14031	2026-09-20 04:25	83.14	OK	14032	2026-09-20 04:26	80.99	OK
14033	2026-09-20 04:27	82.47	OK	14034	2026-09-20 04:28	81.97	OK
14035	2026-09-20 04:29	81.32	OK	14036	2026-09-20 04:30	81.44	OK
14037	2026-09-20 04:31	80.96	OK	14038	2026-09-20 04:32	82.04	OK
14039	2026-09-20 04:33	80.36	OK	14040	2026-09-20 04:34	82.75	OK
14041	2026-09-20 04:35	82.35	OK	14042	2026-09-20 04:36	81.23	OK
14043	2026-09-20 04:37	83.14	OK	14044	2026-09-20 04:38	80.82	OK
14045	2026-09-20 04:39	80.46	OK	14046	2026-09-20 04:40	79.59	OK
14047	2026-09-20 04:41	80.42	OK	14048	2026-09-20 04:42	80.47	OK
14049	2026-09-20 04:43	80.46	OK	14050	2026-09-20 04:44	78.18	OK
14051	2026-09-20 04:45	82.07	OK	14052	2026-09-20 04:46	81.17	OK
14053	2026-09-20 04:47	80.26	OK	14054	2026-09-20 04:48	79.34	OK
14055	2026-09-20 04:49	79.36	OK	14056	2026-09-20 04:50	83.90	OK
1405	2026-09-20 04:51	80.50	OK	1405	2026-09-20 04:52	80.18	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
14059	2026-09-20 04:53	79.64	OK	14060	2026-09-20 04:54	82.22	OK
14061	2026-09-20 04:55	81.39	OK	14062	2026-09-20 04:56	83.49	OK
14063	2026-09-20 04:57	81.08	OK	14064	2026-09-20 04:58	80.24	OK
14065	2026-09-20 04:59	82.83	OK	14066	2026-09-20 05:00	80.77	OK
14067	2026-09-20 05:01	79.02	OK	14068	2026-09-20 05:02	79.72	OK
14069	2026-09-20 05:03	79.13	OK	14070	2026-09-20 05:04	79.06	OK
14071	2026-09-20 05:05	82.26	OK	14072	2026-09-20 05:06	81.30	OK
14073	2026-09-20 05:07	80.05	OK	14074	2026-09-20 05:08	80.65	OK
14075	2026-09-20 05:09	80.70	OK	14076	2026-09-20 05:10	81.67	OK
14077	2026-09-20 05:11	80.44	OK	14078	2026-09-20 05:12	81.01	OK
14079	2026-09-20 05:13	82.88	OK	14080	2026-09-20 05:14	81.98	OK
14081	2026-09-20 05:15	83.35	OK	14082	2026-09-20 05:16	83.24	OK
14083	2026-09-20 05:17	80.92	OK	14084	2026-09-20 05:18	79.85	OK
14085	2026-09-20 05:19	82.27	OK	14086	2026-09-20 05:20	80.19	OK
14087	2026-09-20 05:21	81.16	OK	14088	2026-09-20 05:22	81.15	OK
14089	2026-09-20 05:23	81.68	OK	14090	2026-09-20 05:24	83.40	OK
14091	2026-09-20 05:25	80.96	OK	14092	2026-09-20 05:26	81.28	OK
14093	2026-09-20 05:27	81.44	OK	14094	2026-09-20 05:28	79.84	OK
14095	2026-09-20 05:29	82.50	OK	14096	2026-09-20 05:30	81.88	OK
14097	2026-09-20 05:31	80.59	OK	14098	2026-09-20 05:32	81.33	OK
14099	2026-09-20 05:33	81.30	OK	14100	2026-09-20 05:34	78.67	OK
14101	2026-09-20 05:35	79.74	OK	14102	2026-09-20 05:36	80.93	OK
14103	2026-09-20 05:37	80.77	OK	14104	2026-09-20 05:38	78.13	OK
14105	2026-09-20 05:39	78.46	OK	14106	2026-09-20 05:40	80.78	OK
14107	2026-09-20 05:41	81.14	OK	14108	2026-09-20 05:42	79.69	OK
14109	2026-09-20 05:43	78.45	OK	14110	2026-09-20 05:44	79.66	OK
14111	2026-09-20 05:45	81.29	OK	14112	2026-09-20 05:46	80.29	OK
14113	2026-09-20 05:47	80.06	OK	14114	2026-09-20 05:48	81.07	OK
14115	2026-09-20 05:49	80.14	OK	14116	2026-09-20 05:50	79.19	OK
14117	2026-09-20 05:51	80.30	OK	14118	2026-09-20 05:52	79.88	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
14119	2026-09-20 05:53	81.08	OK	14120	2026-09-20 05:54	79.16	OK
14121	2026-09-20 05:55	80.71	OK	14122	2026-09-20 05:56	78.31	OK
14123	2026-09-20 05:57	77.57	OK	14124	2026-09-20 05:58	80.52	OK
14125	2026-09-20 05:59	78.59	OK	14126	2026-09-20 06:00	80.78	OK
14127	2026-09-20 06:01	81.23	OK	14128	2026-09-20 06:02	79.03	OK
14129	2026-09-20 06:03	82.11	OK	14130	2026-09-20 06:04	77.60	OK
14131	2026-09-20 06:05	79.95	OK	14132	2026-09-20 06:06	81.70	OK
14133	2026-09-20 06:07	79.76	OK	14134	2026-09-20 06:08	77.71	OK
14135	2026-09-20 06:09	78.81	OK	14136	2026-09-20 06:10	78.86	OK
14137	2026-09-20 06:11	78.40	OK	14138	2026-09-20 06:12	79.13	OK
14139	2026-09-20 06:13	81.52	OK	14140	2026-09-20 06:14	80.51	OK
14141	2026-09-20 06:15	79.65	OK	14142	2026-09-20 06:16	77.58	OK
14143	2026-09-20 06:17	80.28	OK	14144	2026-09-20 06:18	82.47	OK
14145	2026-09-20 06:19	80.54	OK	14146	2026-09-20 06:20	78.73	OK
14147	2026-09-20 06:21	78.11	OK	14148	2026-09-20 06:22	78.56	OK
14149	2026-09-20 06:23	81.26	OK	14150	2026-09-20 06:24	80.61	OK
14151	2026-09-20 06:25	79.05	OK	14152	2026-09-20 06:26	80.07	OK
14153	2026-09-20 06:27	78.14	OK	14154	2026-09-20 06:28	80.58	OK
14155	2026-09-20 06:29	79.40	OK	14156	2026-09-20 06:30	81.19	OK
14157	2026-09-20 06:31	79.02	OK	14158	2026-09-20 06:32	79.46	OK
14159	2026-09-20 06:33	79.37	OK	14160	2026-09-20 06:34	80.30	OK
14161	2026-09-20 06:35	79.94	OK	14162	2026-09-20 06:36	80.94	OK
14163	2026-09-20 06:37	78.80	OK	14164	2026-09-20 06:38	80.34	OK
14165	2026-09-20 06:39	81.53	OK	14166	2026-09-20 06:40	78.63	OK
14167	2026-09-20 06:41	81.21	OK	14168	2026-09-20 06:42	78.09	OK
14169	2026-09-20 06:43	80.74	OK	14170	2026-09-20 06:44	79.54	OK
14171	2026-09-20 06:45	78.89	OK	14172	2026-09-20 06:46	79.03	OK
14173	2026-09-20 06:47	81.31	OK	14174	2026-09-20 06:48	79.36	OK
14175	2026-09-20 06:49	78.00	OK	14176	2026-09-20 06:50	80.13	OK
1417	2026-09-20 06:51	81.46	OK	1417	2026-09-20 06:52	79.26	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
14179	2026-09-20 06:53	78.28	OK	14180	2026-09-20 06:54	78.49	OK
14181	2026-09-20 06:55	79.98	OK	14182	2026-09-20 06:56	78.72	OK
14183	2026-09-20 06:57	77.29	OK	14184	2026-09-20 06:58	77.55	OK
14185	2026-09-20 06:59	78.87	OK	14186	2026-09-20 07:00	79.56	OK
14187	2026-09-20 07:01	79.75	OK	14188	2026-09-20 07:02	76.33	OK
14189	2026-09-20 07:03	79.05	OK	14190	2026-09-20 07:04	79.81	OK
14191	2026-09-20 07:05	80.54	OK	14192	2026-09-20 07:06	80.35	OK
14193	2026-09-20 07:07	80.71	OK	14194	2026-09-20 07:08	79.27	OK
14195	2026-09-20 07:09	79.25	OK	14196	2026-09-20 07:10	78.81	OK
14197	2026-09-20 07:11	80.64	OK	14198	2026-09-20 07:12	78.04	OK
14199	2026-09-20 07:13	80.52	OK	14200	2026-09-20 07:14	80.21	OK
14201	2026-09-20 07:15	79.47	OK	14202	2026-09-20 07:16	78.94	OK
14203	2026-09-20 07:17	81.91	OK	14204	2026-09-20 07:18	77.17	OK
14205	2026-09-20 07:19	76.29	OK	14206	2026-09-20 07:20	78.64	OK
14207	2026-09-20 07:21	76.77	OK	14208	2026-09-20 07:22	77.58	OK
14209	2026-09-20 07:23	79.41	OK	14210	2026-09-20 07:24	77.39	OK
14211	2026-09-20 07:25	77.22	OK	14212	2026-09-20 07:26	78.47	OK
14213	2026-09-20 07:27	77.94	OK	14214	2026-09-20 07:28	77.89	OK
14215	2026-09-20 07:29	77.02	OK	14216	2026-09-20 07:30	80.00	OK
14217	2026-09-20 07:31	77.21	OK	14218	2026-09-20 07:32	80.11	OK
14219	2026-09-20 07:33	77.91	OK	14220	2026-09-20 07:34	77.92	OK
14221	2026-09-20 07:35	77.90	OK	14222	2026-09-20 07:36	80.10	OK
14223	2026-09-20 07:37	77.53	OK	14224	2026-09-20 07:38	75.54	OK
14225	2026-09-20 07:39	80.24	OK	14226	2026-09-20 07:40	77.89	OK
14227	2026-09-20 07:41	79.97	OK	14228	2026-09-20 07:42	79.10	OK
14229	2026-09-20 07:43	79.22	OK	14230	2026-09-20 07:44	77.96	OK
14231	2026-09-20 07:45	79.91	OK	14232	2026-09-20 07:46	77.52	OK
14233	2026-09-20 07:47	78.64	OK	14234	2026-09-20 07:48	79.04	OK
14235	2026-09-20 07:49	78.02	OK	14236	2026-09-20 07:50	78.18	OK
1423	2026-09-20 07:51	78.80	OK	1423	2026-09-20 07:52	78.64	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
14239	2026-09-20 07:53	78.51	OK	14240	2026-09-20 07:54	77.67	OK
14241	2026-09-20 07:55	79.08	OK	14242	2026-09-20 07:56	77.61	OK
14243	2026-09-20 07:57	79.08	OK	14244	2026-09-20 07:58	78.76	OK
14245	2026-09-20 07:59	78.84	OK	14246	2026-09-20 08:00	78.02	OK
14247	2026-09-20 08:01	76.54	OK	14248	2026-09-20 08:02	77.72	OK
14249	2026-09-20 08:03	79.36	OK	14250	2026-09-20 08:04	79.48	OK
14251	2026-09-20 08:05	77.64	OK	14252	2026-09-20 08:06	79.09	OK
14253	2026-09-20 08:07	78.02	OK	14254	2026-09-20 08:08	77.51	OK
14255	2026-09-20 08:09	77.53	OK	14256	2026-09-20 08:10	78.75	OK
14257	2026-09-20 08:11	77.55	OK	14258	2026-09-20 08:12	76.33	OK
14259	2026-09-20 08:13	76.54	OK	14260	2026-09-20 08:14	76.72	OK
14261	2026-09-20 08:15	76.30	OK	14262	2026-09-20 08:16	76.61	OK
14263	2026-09-20 08:17	79.06	OK	14264	2026-09-20 08:18	73.62	OK
14265	2026-09-20 08:19	77.37	OK	14266	2026-09-20 08:20	78.02	OK
14267	2026-09-20 08:21	75.80	OK	14268	2026-09-20 08:22	75.19	OK
14269	2026-09-20 08:23	77.50	OK	14270	2026-09-20 08:24	78.65	OK
14271	2026-09-20 08:25	78.06	OK	14272	2026-09-20 08:26	76.63	OK
14273	2026-09-20 08:27	77.21	OK	14274	2026-09-20 08:28	78.60	OK
14275	2026-09-20 08:29	76.10	OK	14276	2026-09-20 08:30	74.25	OK
14277	2026-09-20 08:31	76.42	OK	14278	2026-09-20 08:32	78.39	OK
14279	2026-09-20 08:33	75.92	OK	14280	2026-09-20 08:34	76.92	OK
14281	2026-09-20 08:35	76.73	OK	14282	2026-09-20 08:36	76.51	OK
14283	2026-09-20 08:37	76.34	OK	14284	2026-09-20 08:38	76.36	OK
14285	2026-09-20 08:39	75.68	OK	14286	2026-09-20 08:40	75.01	OK
14287	2026-09-20 08:41	75.30	OK	14288	2026-09-20 08:42	76.89	OK
14289	2026-09-20 08:43	75.37	OK	14290	2026-09-20 08:44	77.46	OK
14291	2026-09-20 08:45	77.13	OK	14292	2026-09-20 08:46	76.77	OK
14293	2026-09-20 08:47	77.53	OK	14294	2026-09-20 08:48	77.66	OK
14295	2026-09-20 08:49	77.17	OK	14296	2026-09-20 08:50	76.13	OK
1429	2026-09-20 08:51	78.05	OK	1429	2026-09-20 08:52	74.09	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
14299	2026-09-20 08:53	76.09	OK	14300	2026-09-20 08:54	77.22	OK
14301	2026-09-20 08:55	75.26	OK	14302	2026-09-20 08:56	75.52	OK
14303	2026-09-20 08:57	74.67	OK	14304	2026-09-20 08:58	73.68	OK
14305	2026-09-20 08:59	75.08	OK	14306	2026-09-20 09:00	76.83	OK
14307	2026-09-20 09:01	76.03	OK	14308	2026-09-20 09:02	76.33	OK
14309	2026-09-20 09:03	77.48	OK	14310	2026-09-20 09:04	76.52	OK
14311	2026-09-20 09:05	74.31	OK	14312	2026-09-20 09:06	75.39	OK
14313	2026-09-20 09:07	76.35	OK	14314	2026-09-20 09:08	76.79	OK
14315	2026-09-20 09:09	73.51	OK	14316	2026-09-20 09:10	74.06	OK
14317	2026-09-20 09:11	76.64	OK	14318	2026-09-20 09:12	75.50	OK
14319	2026-09-20 09:13	75.64	OK	14320	2026-09-20 09:14	78.33	OK
14321	2026-09-20 09:15	78.23	OK	14322	2026-09-20 09:16	74.55	OK
14323	2026-09-20 09:17	74.55	OK	14324	2026-09-20 09:18	76.94	OK
14325	2026-09-20 09:19	74.69	OK	14326	2026-09-20 09:20	76.54	OK
14327	2026-09-20 09:21	75.90	OK	14328	2026-09-20 09:22	74.09	OK
14329	2026-09-20 09:23	78.08	OK	14330	2026-09-20 09:24	76.69	OK
14331	2026-09-20 09:25	75.46	OK	14332	2026-09-20 09:26	76.73	OK
14333	2026-09-20 09:27	73.94	OK	14334	2026-09-20 09:28	75.09	OK
14335	2026-09-20 09:29	78.48	OK	14336	2026-09-20 09:30	74.53	OK
14337	2026-09-20 09:31	76.21	OK	14338	2026-09-20 09:32	74.65	OK
14339	2026-09-20 09:33	76.34	OK	14340	2026-09-20 09:34	75.64	OK
14341	2026-09-20 09:35	75.06	OK	14342	2026-09-20 09:36	76.32	OK
14343	2026-09-20 09:37	73.97	OK	14344	2026-09-20 09:38	73.82	OK
14345	2026-09-20 09:39	74.79	OK	14346	2026-09-20 09:40	74.63	OK
14347	2026-09-20 09:41	74.34	OK	14348	2026-09-20 09:42	75.40	OK
14349	2026-09-20 09:43	75.52	OK	14350	2026-09-20 09:44	78.18	OK
14351	2026-09-20 09:45	76.12	OK	14352	2026-09-20 09:46	77.76	OK
14353	2026-09-20 09:47	72.60	OK	14354	2026-09-20 09:48	78.01	OK
14355	2026-09-20 09:49	73.78	OK	14356	2026-09-20 09:50	72.59	OK
1435	2026-09-20 09:51	75.93	OK	1435	2026-09-20 09:52	73.97	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
14359	2026-09-20 09:53	75.27	OK	14360	2026-09-20 09:54	76.02	OK
14361	2026-09-20 09:55	74.73	OK	14362	2026-09-20 09:56	75.39	OK
14363	2026-09-20 09:57	75.06	OK	14364	2026-09-20 09:58	75.11	OK
14365	2026-09-20 09:59	74.17	OK	14366	2026-09-20 10:00	77.16	OK
14367	2026-09-20 10:01	75.62	OK	14368	2026-09-20 10:02	73.00	OK
14369	2026-09-20 10:03	75.64	OK	14370	2026-09-20 10:04	76.42	OK
14371	2026-09-20 10:05	73.68	OK	14372	2026-09-20 10:06	74.77	OK
14373	2026-09-20 10:07	73.20	OK	14374	2026-09-20 10:08	72.60	OK
14375	2026-09-20 10:09	74.36	OK	14376	2026-09-20 10:10	74.88	OK
14377	2026-09-20 10:11	72.89	OK	14378	2026-09-20 10:12	75.63	OK
14379	2026-09-20 10:13	72.28	OK	14380	2026-09-20 10:14	75.83	OK
14381	2026-09-20 10:15	72.84	OK	14382	2026-09-20 10:16	74.52	OK
14383	2026-09-20 10:17	76.83	OK	14384	2026-09-20 10:18	75.78	OK
14385	2026-09-20 10:19	72.74	OK	14386	2026-09-20 10:20	74.47	OK
14387	2026-09-20 10:21	73.88	OK	14388	2026-09-20 10:22	74.28	OK
14389	2026-09-20 10:23	74.77	OK	14390	2026-09-20 10:24	74.35	OK
14391	2026-09-20 10:25	74.46	OK	14392	2026-09-20 10:26	72.37	OK
14393	2026-09-20 10:27	75.04	OK	14394	2026-09-20 10:28	76.86	OK
14395	2026-09-20 10:29	75.66	OK	14396	2026-09-20 10:30	73.85	OK
14397	2026-09-20 10:31	73.21	OK	14398	2026-09-20 10:32	73.58	OK
14399	2026-09-20 10:33	75.74	OK	14400	2026-09-20 10:34	73.91	OK
14401	2026-09-20 10:35	75.86	OK	14402	2026-09-20 10:36	76.85	OK
14403	2026-09-20 10:37	72.62	OK	14404	2026-09-20 10:38	70.58	OK
14405	2026-09-20 10:39	76.16	OK	14406	2026-09-20 10:40	75.04	OK
14407	2026-09-20 10:41	72.04	OK	14408	2026-09-20 10:42	73.47	OK
14409	2026-09-20 10:43	71.90	OK	14410	2026-09-20 10:44	74.45	OK
14411	2026-09-20 10:45	71.90	OK	14412	2026-09-20 10:46	76.18	OK
14413	2026-09-20 10:47	71.89	OK	14414	2026-09-20 10:48	74.52	OK
14415	2026-09-20 10:49	72.58	OK	14416	2026-09-20 10:50	76.59	OK
1441	2026-09-20 10:51	73.12	OK	1441	2026-09-20 10:52	72.73	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
14419	2026-09-20 10:53	74.47	OK	14420	2026-09-20 10:54	76.80	OK
14421	2026-09-20 10:55	72.92	OK	14422	2026-09-20 10:56	72.86	OK
14423	2026-09-20 10:57	73.56	OK	14424	2026-09-20 10:58	73.52	OK
14425	2026-09-20 10:59	72.18	OK	14426	2026-09-20 11:00	72.54	OK
14427	2026-09-20 11:01	73.52	OK	14428	2026-09-20 11:02	70.96	OK
14429	2026-09-20 11:03	73.80	OK	14430	2026-09-20 11:04	71.29	OK
14431	2026-09-20 11:05	73.09	OK	14432	2026-09-20 11:06	71.79	OK
14433	2026-09-20 11:07	72.71	OK	14434	2026-09-20 11:08	73.05	OK
14435	2026-09-20 11:09	72.88	OK	14436	2026-09-20 11:10	73.53	OK
14437	2026-09-20 11:11	73.23	OK	14438	2026-09-20 11:12	71.79	OK
14439	2026-09-20 11:13	71.72	OK	14440	2026-09-20 11:14	73.22	OK
14441	2026-09-20 11:15	72.02	OK	14442	2026-09-20 11:16	70.82	OK
14443	2026-09-20 11:17	75.31	OK	14444	2026-09-20 11:18	74.64	OK
14445	2026-09-20 11:19	71.80	OK	14446	2026-09-20 11:20	72.89	OK
14447	2026-09-20 11:21	73.89	OK	14448	2026-09-20 11:22	71.63	OK
14449	2026-09-20 11:23	71.82	OK	14450	2026-09-20 11:24	73.16	OK
14451	2026-09-20 11:25	74.31	OK	14452	2026-09-20 11:26	72.05	OK
14453	2026-09-20 11:27	73.91	OK	14454	2026-09-20 11:28	72.25	OK
14455	2026-09-20 11:29	72.77	OK	14456	2026-09-20 11:30	71.34	OK
14457	2026-09-20 11:31	72.40	OK	14458	2026-09-20 11:32	71.74	OK
14459	2026-09-20 11:33	74.49	OK	14460	2026-09-20 11:34	73.04	OK
14461	2026-09-20 11:35	70.88	OK	14462	2026-09-20 11:36	76.00	OK
14463	2026-09-20 11:37	71.53	OK	14464	2026-09-20 11:38	71.45	OK
14465	2026-09-20 11:39	72.87	OK	14466	2026-09-20 11:40	71.94	OK
14467	2026-09-20 11:41	72.59	OK	14468	2026-09-20 11:42	73.33	OK
14469	2026-09-20 11:43	72.54	OK	14470	2026-09-20 11:44	70.45	OK
14471	2026-09-20 11:45	71.26	OK	14472	2026-09-20 11:46	72.25	OK
14473	2026-09-20 11:47	73.94	OK	14474	2026-09-20 11:48	73.01	OK
14475	2026-09-20 11:49	71.50	OK	14476	2026-09-20 11:50	70.23	OK
1447	2026-09-20 11:51	72.08	OK	1447	2026-09-20 11:52	75.33	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
14479	2026-09-20 11:53	72.90	OK	14480	2026-09-20 11:54	73.46	OK
14481	2026-09-20 11:55	72.92	OK	14482	2026-09-20 11:56	72.74	OK
14483	2026-09-20 11:57	74.02	OK	14484	2026-09-20 11:58	70.79	OK
14485	2026-09-20 11:59	72.49	OK	14486	2026-09-20 12:00	71.75	OK
14487	2026-09-20 12:01	73.79	OK	14488	2026-09-20 12:02	71.38	OK
14489	2026-09-20 12:03	71.48	OK	14490	2026-09-20 12:04	72.88	OK
14491	2026-09-20 12:05	74.46	OK	14492	2026-09-20 12:06	71.09	OK
14493	2026-09-20 12:07	72.71	OK	14494	2026-09-20 12:08	72.93	OK
14495	2026-09-20 12:09	71.90	OK	14496	2026-09-20 12:10	70.96	OK
14497	2026-09-20 12:11	71.01	OK	14498	2026-09-20 12:12	72.43	OK
14499	2026-09-20 12:13	70.80	OK	14500	2026-09-20 12:14	71.07	OK
14501	2026-09-20 12:15	72.36	OK	14502	2026-09-20 12:16	73.37	OK
14503	2026-09-20 12:17	72.45	OK	14504	2026-09-20 12:18	73.33	OK
14505	2026-09-20 12:19	72.87	OK	14506	2026-09-20 12:20	73.34	OK
14507	2026-09-20 12:21	72.81	OK	14508	2026-09-20 12:22	73.10	OK
14509	2026-09-20 12:23	75.54	OK	14510	2026-09-20 12:24	73.37	OK
14511	2026-09-20 12:25	71.42	OK	14512	2026-09-20 12:26	73.52	OK
14513	2026-09-20 12:27	72.71	OK	14514	2026-09-20 12:28	73.09	OK
14515	2026-09-20 12:29	71.28	OK	14516	2026-09-20 12:30	73.78	OK
14517	2026-09-20 12:31	72.66	OK	14518	2026-09-20 12:32	71.39	OK
14519	2026-09-20 12:33	73.90	OK	14520	2026-09-20 12:34	72.69	OK
14521	2026-09-20 12:35	71.55	OK	14522	2026-09-20 12:36	72.64	OK
14523	2026-09-20 12:37	71.86	OK	14524	2026-09-20 12:38	69.94	OK
14525	2026-09-20 12:39	70.74	OK	14526	2026-09-20 12:40	73.54	OK
14527	2026-09-20 12:41	72.39	OK	14528	2026-09-20 12:42	74.46	OK
14529	2026-09-20 12:43	71.92	OK	14530	2026-09-20 12:44	73.20	OK
14531	2026-09-20 12:45	71.60	OK	14532	2026-09-20 12:46	72.80	OK
14533	2026-09-20 12:47	74.03	OK	14534	2026-09-20 12:48	72.47	OK
14535	2026-09-20 12:49	70.88	OK	14536	2026-09-20 12:50	70.71	OK
1453	2026-09-20 12:51	70.40	OK	1453	2026-09-20 12:52	71.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
14539	2026-09-20 12:53	71.96	OK	14540	2026-09-20 12:54	71.05	OK
14541	2026-09-20 12:55	73.22	OK	14542	2026-09-20 12:56	73.47	OK
14543	2026-09-20 12:57	73.18	OK	14544	2026-09-20 12:58	72.91	OK
14545	2026-09-20 12:59	69.81	OK	14546	2026-09-20 13:00	73.25	OK
14547	2026-09-20 13:01	70.33	OK	14548	2026-09-20 13:02	69.17	OK
14549	2026-09-20 13:03	72.39	OK	14550	2026-09-20 13:04	73.09	OK
14551	2026-09-20 13:05	72.47	OK	14552	2026-09-20 13:06	71.77	OK
14553	2026-09-20 13:07	71.48	OK	14554	2026-09-20 13:08	72.41	OK
14555	2026-09-20 13:09	69.84	OK	14556	2026-09-20 13:10	69.06	OK
14557	2026-09-20 13:11	72.77	OK	14558	2026-09-20 13:12	73.49	OK
14559	2026-09-20 13:13	71.25	OK	14560	2026-09-20 13:14	72.99	OK
14561	2026-09-20 13:15	73.93	OK	14562	2026-09-20 13:16	72.39	OK
14563	2026-09-20 13:17	72.86	OK	14564	2026-09-20 13:18	73.89	OK
14565	2026-09-20 13:19	71.88	OK	14566	2026-09-20 13:20	71.50	OK
14567	2026-09-20 13:21	71.85	OK	14568	2026-09-20 13:22	70.29	OK
14569	2026-09-20 13:23	71.75	OK	14570	2026-09-20 13:24	71.13	OK
14571	2026-09-20 13:25	71.64	OK	14572	2026-09-20 13:26	72.79	OK
14573	2026-09-20 13:27	71.60	OK	14574	2026-09-20 13:28	74.96	OK
14575	2026-09-20 13:29	71.57	OK	14576	2026-09-20 13:30	73.22	OK
14577	2026-09-20 13:31	71.46	OK	14578	2026-09-20 13:32	71.82	OK
14579	2026-09-20 13:33	70.02	OK	14580	2026-09-20 13:34	72.37	OK
14581	2026-09-20 13:35	68.86	OK	14582	2026-09-20 13:36	71.22	OK
14583	2026-09-20 13:37	68.98	OK	14584	2026-09-20 13:38	72.36	OK
14585	2026-09-20 13:39	72.74	OK	14586	2026-09-20 13:40	71.38	OK
14587	2026-09-20 13:41	69.82	OK	14588	2026-09-20 13:42	73.81	OK
14589	2026-09-20 13:43	70.93	OK	14590	2026-09-20 13:44	72.14	OK
14591	2026-09-20 13:45	71.36	OK	14592	2026-09-20 13:46	70.63	OK
14593	2026-09-20 13:47	70.02	OK	14594	2026-09-20 13:48	72.54	OK
14595	2026-09-20 13:49	71.57	OK	14596	2026-09-20 13:50	70.14	OK
1459	2026-09-20 13:51	72.68	OK	1459	2026-09-20 13:52	72.91	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
14599	2026-09-20 13:53	70.86	OK	14600	2026-09-20 13:54	70.23	OK
14601	2026-09-20 13:55	72.79	OK	14602	2026-09-20 13:56	71.98	OK
14603	2026-09-20 13:57	71.28	OK	14604	2026-09-20 13:58	71.76	OK
14605	2026-09-20 13:59	69.70	OK	14606	2026-09-20 14:00	70.35	OK
14607	2026-09-20 14:01	71.14	OK	14608	2026-09-20 14:02	72.45	OK
14609	2026-09-20 14:03	71.89	OK	14610	2026-09-20 14:04	72.88	OK
14611	2026-09-20 14:05	69.68	OK	14612	2026-09-20 14:06	72.30	OK
14613	2026-09-20 14:07	71.01	OK	14614	2026-09-20 14:08	71.59	OK
14615	2026-09-20 14:09	70.06	OK	14616	2026-09-20 14:10	71.09	OK
14617	2026-09-20 14:11	70.81	OK	14618	2026-09-20 14:12	70.02	OK
14619	2026-09-20 14:13	73.17	OK	14620	2026-09-20 14:14	70.26	OK
14621	2026-09-20 14:15	71.12	OK	14622	2026-09-20 14:16	70.49	OK
14623	2026-09-20 14:17	73.87	OK	14624	2026-09-20 14:18	70.33	OK
14625	2026-09-20 14:19	73.43	OK	14626	2026-09-20 14:20	71.61	OK
14627	2026-09-20 14:21	72.50	OK	14628	2026-09-20 14:22	71.66	OK
14629	2026-09-20 14:23	71.07	OK	14630	2026-09-20 14:24	72.12	OK
14631	2026-09-20 14:25	68.69	OK	14632	2026-09-20 14:26	72.76	OK
14633	2026-09-20 14:27	70.58	OK	14634	2026-09-20 14:28	71.81	OK
14635	2026-09-20 14:29	72.81	OK	14636	2026-09-20 14:30	71.39	OK
14637	2026-09-20 14:31	72.21	OK	14638	2026-09-20 14:32	70.43	OK
14639	2026-09-20 14:33	71.92	OK	14640	2026-09-20 14:34	71.95	OK
14641	2026-09-20 14:35	71.89	OK	14642	2026-09-20 14:36	72.27	OK
14643	2026-09-20 14:37	71.35	OK	14644	2026-09-20 14:38	72.10	OK
14645	2026-09-20 14:39	68.83	OK	14646	2026-09-20 14:40	71.06	OK
14647	2026-09-20 14:41	70.88	OK	14648	2026-09-20 14:42	71.83	OK
14649	2026-09-20 14:43	69.63	OK	14650	2026-09-20 14:44	71.91	OK
14651	2026-09-20 14:45	72.09	OK	14652	2026-09-20 14:46	72.51	OK
14653	2026-09-20 14:47	72.08	OK	14654	2026-09-20 14:48	71.47	OK
14655	2026-09-20 14:49	69.70	OK	14656	2026-09-20 14:50	70.98	OK
1465	2026-09-20 14:51	73.60	OK	1465	2026-09-20 14:52	73.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
14659	2026-09-20 14:53	71.85	OK	14660	2026-09-20 14:54	72.65	OK
14661	2026-09-20 14:55	71.17	OK	14662	2026-09-20 14:56	69.47	OK
14663	2026-09-20 14:57	70.45	OK	14664	2026-09-20 14:58	69.94	OK
14665	2026-09-20 14:59	69.55	OK	14666	2026-09-20 15:00	69.82	OK
14667	2026-09-20 15:01	72.68	OK	14668	2026-09-20 15:02	72.71	OK
14669	2026-09-20 15:03	72.15	OK	14670	2026-09-20 15:04	69.63	OK
14671	2026-09-20 15:05	71.87	OK	14672	2026-09-20 15:06	71.02	OK
14673	2026-09-20 15:07	71.32	OK	14674	2026-09-20 15:08	69.00	OK
14675	2026-09-20 15:09	67.99	OK	14676	2026-09-20 15:10	71.49	OK
14677	2026-09-20 15:11	71.03	OK	14678	2026-09-20 15:12	71.90	OK
14679	2026-09-20 15:13	71.63	OK	14680	2026-09-20 15:14	71.28	OK
14681	2026-09-20 15:15	70.51	OK	14682	2026-09-20 15:16	70.96	OK
14683	2026-09-20 15:17	70.22	OK	14684	2026-09-20 15:18	69.98	OK
14685	2026-09-20 15:19	71.25	OK	14686	2026-09-20 15:20	73.16	OK
14687	2026-09-20 15:21	68.57	OK	14688	2026-09-20 15:22	72.32	OK
14689	2026-09-20 15:23	69.62	OK	14690	2026-09-20 15:24	71.64	OK
14691	2026-09-20 15:25	71.64	OK	14692	2026-09-20 15:26	73.94	OK
14693	2026-09-20 15:27	69.98	OK	14694	2026-09-20 15:28	73.24	OK
14695	2026-09-20 15:29	72.66	OK	14696	2026-09-20 15:30	72.18	OK
14697	2026-09-20 15:31	71.42	OK	14698	2026-09-20 15:32	71.01	OK
14699	2026-09-20 15:33	70.58	OK	14700	2026-09-20 15:34	72.04	OK
14701	2026-09-20 15:35	71.30	OK	14702	2026-09-20 15:36	70.38	OK
14703	2026-09-20 15:37	70.37	OK	14704	2026-09-20 15:38	70.93	OK
14705	2026-09-20 15:39	71.93	OK	14706	2026-09-20 15:40	70.35	OK
14707	2026-09-20 15:41	72.23	OK	14708	2026-09-20 15:42	71.58	OK
14709	2026-09-20 15:43	69.37	OK	14710	2026-09-20 15:44	73.27	OK
14711	2026-09-20 15:45	72.02	OK	14712	2026-09-20 15:46	70.72	OK
14713	2026-09-20 15:47	70.00	OK	14714	2026-09-20 15:48	70.86	OK
14715	2026-09-20 15:49	71.34	OK	14716	2026-09-20 15:50	70.50	OK
14717	2026-09-20 15:51	71.25	OK	14717	2026-09-20 15:52	73.36	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
14719	2026-09-20 15:53	70.96	OK	14720	2026-09-20 15:54	69.92	OK
14721	2026-09-20 15:55	73.01	OK	14722	2026-09-20 15:56	70.08	OK
14723	2026-09-20 15:57	69.49	OK	14724	2026-09-20 15:58	70.81	OK
14725	2026-09-20 15:59	72.08	OK	14726	2026-09-20 16:00	69.85	OK
14727	2026-09-20 16:01	71.37	OK	14728	2026-09-20 16:02	71.90	OK
14729	2026-09-20 16:03	68.45	OK	14730	2026-09-20 16:04	71.10	OK
14731	2026-09-20 16:05	70.61	OK	14732	2026-09-20 16:06	71.09	OK
14733	2026-09-20 16:07	72.32	OK	14734	2026-09-20 16:08	70.31	OK
14735	2026-09-20 16:09	72.26	OK	14736	2026-09-20 16:10	72.28	OK
14737	2026-09-20 16:11	71.22	OK	14738	2026-09-20 16:12	71.80	OK
14739	2026-09-20 16:13	72.14	OK	14740	2026-09-20 16:14	70.33	OK
14741	2026-09-20 16:15	74.55	OK	14742	2026-09-20 16:16	70.62	OK
14743	2026-09-20 16:17	71.55	OK	14744	2026-09-20 16:18	71.02	OK
14745	2026-09-20 16:19	70.31	OK	14746	2026-09-20 16:20	71.31	OK
14747	2026-09-20 16:21	70.92	OK	14748	2026-09-20 16:22	71.65	OK
14749	2026-09-20 16:23	72.65	OK	14750	2026-09-20 16:24	72.53	OK
14751	2026-09-20 16:25	72.68	OK	14752	2026-09-20 16:26	72.57	OK
14753	2026-09-20 16:27	74.57	OK	14754	2026-09-20 16:28	72.96	OK
14755	2026-09-20 16:29	70.99	OK	14756	2026-09-20 16:30	71.92	OK
14757	2026-09-20 16:31	70.90	OK	14758	2026-09-20 16:32	71.88	OK
14759	2026-09-20 16:33	71.32	OK	14760	2026-09-20 16:34	71.52	OK
14761	2026-09-20 16:35	70.31	OK	14762	2026-09-20 16:36	73.49	OK
14763	2026-09-20 16:37	72.25	OK	14764	2026-09-20 16:38	71.57	OK
14765	2026-09-20 16:39	72.32	OK	14766	2026-09-20 16:40	71.23	OK
14767	2026-09-20 16:41	72.72	OK	14768	2026-09-20 16:42	72.09	OK
14769	2026-09-20 16:43	69.25	OK	14770	2026-09-20 16:44	74.64	OK
14771	2026-09-20 16:45	72.81	OK	14772	2026-09-20 16:46	73.55	OK
14773	2026-09-20 16:47	72.44	OK	14774	2026-09-20 16:48	70.74	OK
14775	2026-09-20 16:49	74.52	OK	14776	2026-09-20 16:50	72.16	OK
14777	2026-09-20 16:51	71.53	OK	14777	2026-09-20 16:52	69.76	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
14779	2026-09-20 16:53	73.47	OK	14780	2026-09-20 16:54	74.35	OK
14781	2026-09-20 16:55	70.61	OK	14782	2026-09-20 16:56	71.49	OK
14783	2026-09-20 16:57	72.09	OK	14784	2026-09-20 16:58	70.92	OK
14785	2026-09-20 16:59	71.43	OK	14786	2026-09-20 17:00	71.80	OK
14787	2026-09-20 17:01	71.73	OK	14788	2026-09-20 17:02	72.28	OK
14789	2026-09-20 17:03	71.74	OK	14790	2026-09-20 17:04	75.63	OK
14791	2026-09-20 17:05	72.36	OK	14792	2026-09-20 17:06	73.06	OK
14793	2026-09-20 17:07	72.30	OK	14794	2026-09-20 17:08	70.25	OK
14795	2026-09-20 17:09	70.64	OK	14796	2026-09-20 17:10	71.92	OK
14797	2026-09-20 17:11	72.47	OK	14798	2026-09-20 17:12	71.70	OK
14799	2026-09-20 17:13	72.23	OK	14800	2026-09-20 17:14	73.50	OK
14801	2026-09-20 17:15	71.17	OK	14802	2026-09-20 17:16	71.00	OK
14803	2026-09-20 17:17	71.13	OK	14804	2026-09-20 17:18	74.49	OK
14805	2026-09-20 17:19	73.24	OK	14806	2026-09-20 17:20	71.72	OK
14807	2026-09-20 17:21	73.62	OK	14808	2026-09-20 17:22	71.24	OK
14809	2026-09-20 17:23	72.14	OK	14810	2026-09-20 17:24	72.20	OK
14811	2026-09-20 17:25	74.10	OK	14812	2026-09-20 17:26	72.37	OK
14813	2026-09-20 17:27	72.36	OK	14814	2026-09-20 17:28	72.15	OK
14815	2026-09-20 17:29	71.53	OK	14816	2026-09-20 17:30	69.89	OK
14817	2026-09-20 17:31	73.52	OK	14818	2026-09-20 17:32	73.74	OK
14819	2026-09-20 17:33	72.35	OK	14820	2026-09-20 17:34	70.42	OK
14821	2026-09-20 17:35	74.05	OK	14822	2026-09-20 17:36	72.78	OK
14823	2026-09-20 17:37	72.10	OK	14824	2026-09-20 17:38	72.65	OK
14825	2026-09-20 17:39	71.94	OK	14826	2026-09-20 17:40	70.84	OK
14827	2026-09-20 17:41	72.60	OK	14828	2026-09-20 17:42	72.67	OK
14829	2026-09-20 17:43	73.56	OK	14830	2026-09-20 17:44	74.76	OK
14831	2026-09-20 17:45	73.74	OK	14832	2026-09-20 17:46	74.60	OK
14833	2026-09-20 17:47	74.11	OK	14834	2026-09-20 17:48	72.58	OK
14835	2026-09-20 17:49	73.28	OK	14836	2026-09-20 17:50	73.11	OK
1483	2026-09-20 17:51	71.72	OK	1483	2026-09-20 17:52	73.82	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
14839	2026-09-20 17:53	71.42	OK	14840	2026-09-20 17:54	73.04	OK
14841	2026-09-20 17:55	72.19	OK	14842	2026-09-20 17:56	72.77	OK
14843	2026-09-20 17:57	71.63	OK	14844	2026-09-20 17:58	72.71	OK
14845	2026-09-20 17:59	70.66	OK	14846	2026-09-20 18:00	75.05	OK
14847	2026-09-20 18:01	75.96	OK	14848	2026-09-20 18:02	74.36	OK
14849	2026-09-20 18:03	74.59	OK	14850	2026-09-20 18:04	72.22	OK
14851	2026-09-20 18:05	74.00	OK	14852	2026-09-20 18:06	72.51	OK
14853	2026-09-20 18:07	73.85	OK	14854	2026-09-20 18:08	72.60	OK
14855	2026-09-20 18:09	70.52	OK	14856	2026-09-20 18:10	75.68	OK
14857	2026-09-20 18:11	75.20	OK	14858	2026-09-20 18:12	73.98	OK
14859	2026-09-20 18:13	72.74	OK	14860	2026-09-20 18:14	74.11	OK
14861	2026-09-20 18:15	71.51	OK	14862	2026-09-20 18:16	72.83	OK
14863	2026-09-20 18:17	73.07	OK	14864	2026-09-20 18:18	73.28	OK
14865	2026-09-20 18:19	72.29	OK	14866	2026-09-20 18:20	73.84	OK
14867	2026-09-20 18:21	74.79	OK	14868	2026-09-20 18:22	73.04	OK
14869	2026-09-20 18:23	74.20	OK	14870	2026-09-20 18:24	72.85	OK
14871	2026-09-20 18:25	74.77	OK	14872	2026-09-20 18:26	73.23	OK
14873	2026-09-20 18:27	73.88	OK	14874	2026-09-20 18:28	73.67	OK
14875	2026-09-20 18:29	73.84	OK	14876	2026-09-20 18:30	74.55	OK
14877	2026-09-20 18:31	70.87	OK	14878	2026-09-20 18:32	73.77	OK
14879	2026-09-20 18:33	73.09	OK	14880	2026-09-20 18:34	72.12	OK
14881	2026-09-20 18:35	74.04	OK	14882	2026-09-20 18:36	73.87	OK
14883	2026-09-20 18:37	72.39	OK	14884	2026-09-20 18:38	73.43	OK
14885	2026-09-20 18:39	72.33	OK	14886	2026-09-20 18:40	72.13	OK
14887	2026-09-20 18:41	74.14	OK	14888	2026-09-20 18:42	72.92	OK
14889	2026-09-20 18:43	73.93	OK	14890	2026-09-20 18:44	72.06	OK
14891	2026-09-20 18:45	72.79	OK	14892	2026-09-20 18:46	73.19	OK
14893	2026-09-20 18:47	73.65	OK	14894	2026-09-20 18:48	74.55	OK
14895	2026-09-20 18:49	75.44	OK	14896	2026-09-20 18:50	73.54	OK
1489	2026-09-20 18:51	72.16	OK	1489	2026-09-20 18:52	72.33	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
14899	2026-09-20 18:53	73.76	OK	14900	2026-09-20 18:54	76.25	OK
14901	2026-09-20 18:55	75.65	OK	14902	2026-09-20 18:56	74.18	OK
14903	2026-09-20 18:57	73.17	OK	14904	2026-09-20 18:58	74.25	OK
14905	2026-09-20 18:59	75.07	OK	14906	2026-09-20 19:00	75.33	OK
14907	2026-09-20 19:01	74.30	OK	14908	2026-09-20 19:02	72.98	OK
14909	2026-09-20 19:03	73.17	OK	14910	2026-09-20 19:04	73.73	OK
14911	2026-09-20 19:05	74.55	OK	14912	2026-09-20 19:06	75.55	OK
14913	2026-09-20 19:07	74.80	OK	14914	2026-09-20 19:08	73.54	OK
14915	2026-09-20 19:09	74.87	OK	14916	2026-09-20 19:10	75.04	OK
14917	2026-09-20 19:11	75.92	OK	14918	2026-09-20 19:12	72.82	OK
14919	2026-09-20 19:13	74.34	OK	14920	2026-09-20 19:14	74.15	OK
14921	2026-09-20 19:15	76.39	OK	14922	2026-09-20 19:16	73.99	OK
14923	2026-09-20 19:17	76.72	OK	14924	2026-09-20 19:18	73.17	OK
14925	2026-09-20 19:19	75.18	OK	14926	2026-09-20 19:20	73.95	OK
14927	2026-09-20 19:21	74.27	OK	14928	2026-09-20 19:22	74.37	OK
14929	2026-09-20 19:23	75.51	OK	14930	2026-09-20 19:24	75.50	OK
14931	2026-09-20 19:25	76.54	OK	14932	2026-09-20 19:26	76.12	OK
14933	2026-09-20 19:27	73.47	OK	14934	2026-09-20 19:28	73.94	OK
14935	2026-09-20 19:29	74.99	OK	14936	2026-09-20 19:30	77.22	OK
14937	2026-09-20 19:31	72.96	OK	14938	2026-09-20 19:32	74.99	OK
14939	2026-09-20 19:33	76.58	OK	14940	2026-09-20 19:34	73.49	OK
14941	2026-09-20 19:35	73.35	OK	14942	2026-09-20 19:36	73.90	OK
14943	2026-09-20 19:37	75.34	OK	14944	2026-09-20 19:38	74.58	OK
14945	2026-09-20 19:39	76.52	OK	14946	2026-09-20 19:40	72.99	OK
14947	2026-09-20 19:41	77.12	OK	14948	2026-09-20 19:42	73.76	OK
14949	2026-09-20 19:43	77.06	OK	14950	2026-09-20 19:44	75.67	OK
14951	2026-09-20 19:45	74.94	OK	14952	2026-09-20 19:46	74.21	OK
14953	2026-09-20 19:47	75.72	OK	14954	2026-09-20 19:48	76.05	OK
14955	2026-09-20 19:49	75.80	OK	14956	2026-09-20 19:50	74.57	OK
1495	2026-09-20 19:51	74.76	OK	1495	2026-09-20 19:52	75.85	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
14959	2026-09-20 19:53	75.15	OK	14960	2026-09-20 19:54	77.56	OK
14961	2026-09-20 19:55	73.80	OK	14962	2026-09-20 19:56	74.77	OK
14963	2026-09-20 19:57	76.62	OK	14964	2026-09-20 19:58	77.95	OK
14965	2026-09-20 19:59	75.26	OK	14966	2026-09-20 20:00	77.48	OK
14967	2026-09-20 20:01	75.42	OK	14968	2026-09-20 20:02	76.13	OK
14969	2026-09-20 20:03	73.24	OK	14970	2026-09-20 20:04	76.03	OK
14971	2026-09-20 20:05	77.03	OK	14972	2026-09-20 20:06	76.90	OK
14973	2026-09-20 20:07	77.14	OK	14974	2026-09-20 20:08	77.44	OK
14975	2026-09-20 20:09	74.27	OK	14976	2026-09-20 20:10	78.23	OK
14977	2026-09-20 20:11	75.70	OK	14978	2026-09-20 20:12	75.93	OK
14979	2026-09-20 20:13	76.64	OK	14980	2026-09-20 20:14	73.41	OK
14981	2026-09-20 20:15	75.21	OK	14982	2026-09-20 20:16	76.67	OK
14983	2026-09-20 20:17	74.33	OK	14984	2026-09-20 20:18	75.84	OK
14985	2026-09-20 20:19	74.31	OK	14986	2026-09-20 20:20	76.23	OK
14987	2026-09-20 20:21	76.26	OK	14988	2026-09-20 20:22	76.75	OK
14989	2026-09-20 20:23	78.11	OK	14990	2026-09-20 20:24	76.08	OK
14991	2026-09-20 20:25	74.78	OK	14992	2026-09-20 20:26	74.41	OK
14993	2026-09-20 20:27	75.87	OK	14994	2026-09-20 20:28	77.17	OK
14995	2026-09-20 20:29	76.80	OK	14996	2026-09-20 20:30	77.56	OK
14997	2026-09-20 20:31	73.82	OK	14998	2026-09-20 20:32	79.05	OK
14999	2026-09-20 20:33	75.74	OK	15000	2026-09-20 20:34	77.21	OK
15001	2026-09-20 20:35	77.51	OK	15002	2026-09-20 20:36	76.47	OK
15003	2026-09-20 20:37	77.21	OK	15004	2026-09-20 20:38	77.88	OK
15005	2026-09-20 20:39	73.22	OK	15006	2026-09-20 20:40	77.82	OK
15007	2026-09-20 20:41	77.28	OK	15008	2026-09-20 20:42	77.52	OK
15009	2026-09-20 20:43	78.19	OK	15010	2026-09-20 20:44	75.96	OK
15011	2026-09-20 20:45	76.08	OK	15012	2026-09-20 20:46	75.93	OK
15013	2026-09-20 20:47	74.51	OK	15014	2026-09-20 20:48	78.79	OK
15015	2026-09-20 20:49	74.69	OK	15016	2026-09-20 20:50	77.60	OK
1501	2026-09-20 20:51	73.96	OK	1501	2026-09-20 20:52	76.44	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
15019	2026-09-20 20:53	74.12	OK	15020	2026-09-20 20:54	77.60	OK
15021	2026-09-20 20:55	75.94	OK	15022	2026-09-20 20:56	76.60	OK
15023	2026-09-20 20:57	76.32	OK	15024	2026-09-20 20:58	78.75	OK
15025	2026-09-20 20:59	77.33	OK	15026	2026-09-20 21:00	78.22	OK
15027	2026-09-20 21:01	78.78	OK	15028	2026-09-20 21:02	77.43	OK
15029	2026-09-20 21:03	79.75	OK	15030	2026-09-20 21:04	75.12	OK
15031	2026-09-20 21:05	77.37	OK	15032	2026-09-20 21:06	77.67	OK
15033	2026-09-20 21:07	78.39	OK	15034	2026-09-20 21:08	77.00	OK
15035	2026-09-20 21:09	75.05	OK	15036	2026-09-20 21:10	75.11	OK
15037	2026-09-20 21:11	77.28	OK	15038	2026-09-20 21:12	75.99	OK
15039	2026-09-20 21:13	77.63	OK	15040	2026-09-20 21:14	78.59	OK
15041	2026-09-20 21:15	75.19	OK	15042	2026-09-20 21:16	74.73	OK
15043	2026-09-20 21:17	76.54	OK	15044	2026-09-20 21:18	76.36	OK
15045	2026-09-20 21:19	77.43	OK	15046	2026-09-20 21:20	77.96	OK
15047	2026-09-20 21:21	77.05	OK	15048	2026-09-20 21:22	76.16	OK
15049	2026-09-20 21:23	75.95	OK	15050	2026-09-20 21:24	76.13	OK
15051	2026-09-20 21:25	76.89	OK	15052	2026-09-20 21:26	78.11	OK
15053	2026-09-20 21:27	77.56	OK	15054	2026-09-20 21:28	74.73	OK
15055	2026-09-20 21:29	76.79	OK	15056	2026-09-20 21:30	78.46	OK
15057	2026-09-20 21:31	77.19	OK	15058	2026-09-20 21:32	76.77	OK
15059	2026-09-20 21:33	77.17	OK	15060	2026-09-20 21:34	78.28	OK
15061	2026-09-20 21:35	77.86	OK	15062	2026-09-20 21:36	76.79	OK
15063	2026-09-20 21:37	78.78	OK	15064	2026-09-20 21:38	78.29	OK
15065	2026-09-20 21:39	77.47	OK	15066	2026-09-20 21:40	75.19	OK
15067	2026-09-20 21:41	78.21	OK	15068	2026-09-20 21:42	79.07	OK
15069	2026-09-20 21:43	77.10	OK	15070	2026-09-20 21:44	78.02	OK
15071	2026-09-20 21:45	76.59	OK	15072	2026-09-20 21:46	76.71	OK
15073	2026-09-20 21:47	77.45	OK	15074	2026-09-20 21:48	78.27	OK
15075	2026-09-20 21:49	79.79	OK	15076	2026-09-20 21:50	77.41	OK
1507	2026-09-20 21:51	78.75	OK	1507	2026-09-20 21:52	80.45	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
15079	2026-09-20 21:53	75.47	OK	15080	2026-09-20 21:54	78.43	OK
15081	2026-09-20 21:55	78.29	OK	15082	2026-09-20 21:56	77.44	OK
15083	2026-09-20 21:57	78.41	OK	15084	2026-09-20 21:58	80.28	OK
15085	2026-09-20 21:59	77.01	OK	15086	2026-09-20 22:00	80.21	OK
15087	2026-09-20 22:01	77.40	OK	15088	2026-09-20 22:02	77.36	OK
15089	2026-09-20 22:03	78.80	OK	15090	2026-09-20 22:04	78.89	OK
15091	2026-09-20 22:05	78.30	OK	15092	2026-09-20 22:06	77.64	OK
15093	2026-09-20 22:07	76.57	OK	15094	2026-09-20 22:08	77.25	OK
15095	2026-09-20 22:09	79.23	OK	15096	2026-09-20 22:10	78.36	OK
15097	2026-09-20 22:11	80.02	OK	15098	2026-09-20 22:12	79.73	OK
15099	2026-09-20 22:13	76.65	OK	15100	2026-09-20 22:14	76.57	OK
15101	2026-09-20 22:15	78.63	OK	15102	2026-09-20 22:16	78.08	OK
15103	2026-09-20 22:17	79.61	OK	15104	2026-09-20 22:18	79.28	OK
15105	2026-09-20 22:19	79.53	OK	15106	2026-09-20 22:20	78.98	OK
15107	2026-09-20 22:21	77.56	OK	15108	2026-09-20 22:22	79.86	OK
15109	2026-09-20 22:23	77.88	OK	15110	2026-09-20 22:24	77.16	OK
15111	2026-09-20 22:25	76.52	OK	15112	2026-09-20 22:26	78.70	OK
15113	2026-09-20 22:27	77.39	OK	15114	2026-09-20 22:28	79.88	OK
15115	2026-09-20 22:29	78.27	OK	15116	2026-09-20 22:30	81.03	OK
15117	2026-09-20 22:31	78.30	OK	15118	2026-09-20 22:32	80.43	OK
15119	2026-09-20 22:33	81.87	OK	15120	2026-09-20 22:34	80.30	OK
15121	2026-09-20 22:35	77.44	OK	15122	2026-09-20 22:36	77.49	OK
15123	2026-09-20 22:37	81.93	OK	15124	2026-09-20 22:38	79.24	OK
15125	2026-09-20 22:39	77.31	OK	15126	2026-09-20 22:40	79.68	OK
15127	2026-09-20 22:41	78.21	OK	15128	2026-09-20 22:42	78.26	OK
15129	2026-09-20 22:43	80.44	OK	15130	2026-09-20 22:44	80.56	OK
15131	2026-09-20 22:45	79.77	OK	15132	2026-09-20 22:46	80.65	OK
15133	2026-09-20 22:47	79.01	OK	15134	2026-09-20 22:48	80.95	OK
15135	2026-09-20 22:49	77.99	OK	15136	2026-09-20 22:50	79.24	OK
1513	2026-09-20 22:51	78.55	OK	1513	2026-09-20 22:52	79.41	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
15139	2026-09-20 22:53	78.96	OK	15140	2026-09-20 22:54	79.57	OK
15141	2026-09-20 22:55	80.07	OK	15142	2026-09-20 22:56	79.51	OK
15143	2026-09-20 22:57	80.36	OK	15144	2026-09-20 22:58	77.68	OK
15145	2026-09-20 22:59	80.08	OK	15146	2026-09-20 23:00	79.54	OK
15147	2026-09-20 23:01	80.57	OK	15148	2026-09-20 23:02	79.19	OK
15149	2026-09-20 23:03	79.45	OK	15150	2026-09-20 23:04	79.47	OK
15151	2026-09-20 23:05	81.14	OK	15152	2026-09-20 23:06	79.31	OK
15153	2026-09-20 23:07	76.64	OK	15154	2026-09-20 23:08	78.66	OK
15155	2026-09-20 23:09	80.99	OK	15156	2026-09-20 23:10	81.19	OK
15157	2026-09-20 23:11	76.50	OK	15158	2026-09-20 23:12	79.61	OK
15159	2026-09-20 23:13	78.18	OK	15160	2026-09-20 23:14	81.21	OK
15161	2026-09-20 23:15	80.00	OK	15162	2026-09-20 23:16	80.95	OK
15163	2026-09-20 23:17	78.78	OK	15164	2026-09-20 23:18	80.42	OK
15165	2026-09-20 23:19	77.76	OK	15166	2026-09-20 23:20	81.32	OK
15167	2026-09-20 23:21	78.62	OK	15168	2026-09-20 23:22	80.32	OK
15169	2026-09-20 23:23	79.42	OK	15170	2026-09-20 23:24	81.32	OK
15171	2026-09-20 23:25	78.02	OK	15172	2026-09-20 23:26	80.96	OK
15173	2026-09-20 23:27	81.82	OK	15174	2026-09-20 23:28	78.65	OK
15175	2026-09-20 23:29	79.74	OK	15176	2026-09-20 23:30	81.62	OK
15177	2026-09-20 23:31	79.90	OK	15178	2026-09-20 23:32	77.97	OK
15179	2026-09-20 23:33	80.16	OK	15180	2026-09-20 23:34	79.32	OK
15181	2026-09-20 23:35	78.59	OK	15182	2026-09-20 23:36	81.22	OK
15183	2026-09-20 23:37	82.73	OK	15184	2026-09-20 23:38	81.21	OK
15185	2026-09-20 23:39	77.23	OK	15186	2026-09-20 23:40	81.27	OK
15187	2026-09-20 23:41	80.28	OK	15188	2026-09-20 23:42	78.82	OK
15189	2026-09-20 23:43	79.06	OK	15190	2026-09-20 23:44	79.65	OK
15191	2026-09-20 23:45	80.50	OK	15192	2026-09-20 23:46	80.06	OK
15193	2026-09-20 23:47	80.15	OK	15194	2026-09-20 23:48	82.17	OK
15195	2026-09-20 23:49	77.59	OK	15196	2026-09-20 23:50	78.66	OK
1519	2026-09-20 23:51	76.84	OK	1519	2026-09-20 23:52	81.81	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
15199	2026-09-20 23:53	78.55	OK	15200	2026-09-20 23:54	81.54	OK
15201	2026-09-20 23:55	79.25	OK	15202	2026-09-20 23:56	80.04	OK
15203	2026-09-20 23:57	78.44	OK	15204	2026-09-20 23:58	80.59	OK
15205	2026-09-20 23:59	79.55	OK	15206	2026-09-21 00:00	81.59	OK
15207	2026-09-21 00:01	80.09	OK	15208	2026-09-21 00:02	81.17	OK
15209	2026-09-21 00:03	78.58	OK	15210	2026-09-21 00:04	82.30	OK
15211	2026-09-21 00:05	79.56	OK	15212	2026-09-21 00:06	79.76	OK
15213	2026-09-21 00:07	80.18	OK	15214	2026-09-21 00:08	81.39	OK
15215	2026-09-21 00:09	79.71	OK	15216	2026-09-21 00:10	81.22	OK
15217	2026-09-21 00:11	81.72	OK	15218	2026-09-21 00:12	80.84	OK
15219	2026-09-21 00:13	81.07	OK	15220	2026-09-21 00:14	81.25	OK
15221	2026-09-21 00:15	80.41	OK	15222	2026-09-21 00:16	79.02	OK
15223	2026-09-21 00:17	82.22	OK	15224	2026-09-21 00:18	80.57	OK
15225	2026-09-21 00:19	82.18	OK	15226	2026-09-21 00:20	81.11	OK
15227	2026-09-21 00:21	82.25	OK	15228	2026-09-21 00:22	82.32	OK
15229	2026-09-21 00:23	81.26	OK	15230	2026-09-21 00:24	79.51	OK
15231	2026-09-21 00:25	81.00	OK	15232	2026-09-21 00:26	80.63	OK
15233	2026-09-21 00:27	80.37	OK	15234	2026-09-21 00:28	80.60	OK
15235	2026-09-21 00:29	78.72	OK	15236	2026-09-21 00:30	80.26	OK
15237	2026-09-21 00:31	81.49	OK	15238	2026-09-21 00:32	79.13	OK
15239	2026-09-21 00:33	79.49	OK	15240	2026-09-21 00:34	82.26	OK
15241	2026-09-21 00:35	79.86	OK	15242	2026-09-21 00:36	82.30	OK
15243	2026-09-21 00:37	82.09	OK	15244	2026-09-21 00:38	79.42	OK
15245	2026-09-21 00:39	80.35	OK	15246	2026-09-21 00:40	81.28	OK
15247	2026-09-21 00:41	77.35	OK	15248	2026-09-21 00:42	83.21	OK
15249	2026-09-21 00:43	81.20	OK	15250	2026-09-21 00:44	80.97	OK
15251	2026-09-21 00:45	80.00	OK	15252	2026-09-21 00:46	82.71	OK
15253	2026-09-21 00:47	79.44	OK	15254	2026-09-21 00:48	80.45	OK
15255	2026-09-21 00:49	81.83	OK	15256	2026-09-21 00:50	84.36	OK
1525	2026-09-21 00:51	81.81	OK	1525	2026-09-21 00:52	81.89	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
15259	2026-09-21 00:53	81.50	OK	15260	2026-09-21 00:54	80.83	OK
15261	2026-09-21 00:55	79.88	OK	15262	2026-09-21 00:56	80.14	OK
15263	2026-09-21 00:57	81.89	OK	15264	2026-09-21 00:58	80.57	OK
15265	2026-09-21 00:59	83.03	OK	15266	2026-09-21 01:00	81.10	OK
15267	2026-09-21 01:01	81.22	OK	15268	2026-09-21 01:02	82.03	OK
15269	2026-09-21 01:03	81.02	OK	15270	2026-09-21 01:04	81.92	OK
15271	2026-09-21 01:05	84.54	OK	15272	2026-09-21 01:06	80.88	OK
15273	2026-09-21 01:07	82.94	OK	15274	2026-09-21 01:08	80.87	OK
15275	2026-09-21 01:09	82.57	OK	15276	2026-09-21 01:10	80.00	OK
15277	2026-09-21 01:11	79.42	OK	15278	2026-09-21 01:12	82.48	OK
15279	2026-09-21 01:13	81.61	OK	15280	2026-09-21 01:14	80.06	OK
15281	2026-09-21 01:15	80.95	OK	15282	2026-09-21 01:16	81.43	OK
15283	2026-09-21 01:17	81.69	OK	15284	2026-09-21 01:18	81.32	OK
15285	2026-09-21 01:19	81.62	OK	15286	2026-09-21 01:20	83.54	OK
15287	2026-09-21 01:21	82.50	OK	15288	2026-09-21 01:22	80.73	OK
15289	2026-09-21 01:23	80.99	OK	15290	2026-09-21 01:24	80.97	OK
15291	2026-09-21 01:25	81.78	OK	15292	2026-09-21 01:26	79.88	OK
15293	2026-09-21 01:27	79.41	OK	15294	2026-09-21 01:28	82.86	OK
15295	2026-09-21 01:29	81.23	OK	15296	2026-09-21 01:30	79.05	OK
15297	2026-09-21 01:31	81.90	OK	15298	2026-09-21 01:32	82.57	OK
15299	2026-09-21 01:33	79.82	OK	15300	2026-09-21 01:34	83.18	OK
15301	2026-09-21 01:35	82.08	OK	15302	2026-09-21 01:36	81.97	OK
15303	2026-09-21 01:37	80.47	OK	15304	2026-09-21 01:38	79.81	OK
15305	2026-09-21 01:39	82.48	OK	15306	2026-09-21 01:40	82.36	OK
15307	2026-09-21 01:41	83.34	OK	15308	2026-09-21 01:42	82.72	OK
15309	2026-09-21 01:43	81.01	OK	15310	2026-09-21 01:44	81.01	OK
15311	2026-09-21 01:45	80.83	OK	15312	2026-09-21 01:46	81.23	OK
15313	2026-09-21 01:47	83.48	OK	15314	2026-09-21 01:48	83.15	OK
15315	2026-09-21 01:49	82.12	OK	15316	2026-09-21 01:50	79.33	OK
1531	2026-09-21 01:51	83.04	OK	1531	2026-09-21 01:52	79.58	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
15319	2026-09-21 01:53	80.63	OK	15320	2026-09-21 01:54	83.46	OK
15321	2026-09-21 01:55	79.80	OK	15322	2026-09-21 01:56	79.96	OK
15323	2026-09-21 01:57	79.73	OK	15324	2026-09-21 01:58	81.38	OK
15325	2026-09-21 01:59	83.45	OK	15326	2026-09-21 02:00	83.70	OK
15327	2026-09-21 02:01	81.08	OK	15328	2026-09-21 02:02	82.58	OK
15329	2026-09-21 02:03	81.41	OK	15330	2026-09-21 02:04	80.86	OK
15331	2026-09-21 02:05	84.25	OK	15332	2026-09-21 02:06	85.22	OK
15333	2026-09-21 02:07	80.32	OK	15334	2026-09-21 02:08	80.43	OK
15335	2026-09-21 02:09	80.45	OK	15336	2026-09-21 02:10	82.28	OK
15337	2026-09-21 02:11	80.92	OK	15338	2026-09-21 02:12	83.02	OK
15339	2026-09-21 02:13	80.63	OK	15340	2026-09-21 02:14	79.00	OK
15341	2026-09-21 02:15	81.26	OK	15342	2026-09-21 02:16	80.06	OK
15343	2026-09-21 02:17	81.65	OK	15344	2026-09-21 02:18	82.32	OK
15345	2026-09-21 02:19	79.79	OK	15346	2026-09-21 02:20	81.64	OK
15347	2026-09-21 02:21	82.25	OK	15348	2026-09-21 02:22	83.14	OK
15349	2026-09-21 02:23	81.43	OK	15350	2026-09-21 02:24	80.76	OK
15351	2026-09-21 02:25	81.40	OK	15352	2026-09-21 02:26	82.28	OK
15353	2026-09-21 02:27	82.80	OK	15354	2026-09-21 02:28	81.27	OK
15355	2026-09-21 02:29	84.46	OK	15356	2026-09-21 02:30	83.09	OK
15357	2026-09-21 02:31	81.00	OK	15358	2026-09-21 02:32	84.63	OK
15359	2026-09-21 02:33	81.07	OK	15360	2026-09-21 02:34	82.74	OK
15361	2026-09-21 02:35	83.89	OK	15362	2026-09-21 02:36	81.25	OK
15363	2026-09-21 02:37	80.46	OK	15364	2026-09-21 02:38	83.44	OK
15365	2026-09-21 02:39	82.60	OK	15366	2026-09-21 02:40	80.93	OK
15367	2026-09-21 02:41	80.97	OK	15368	2026-09-21 02:42	80.35	OK
15369	2026-09-21 02:43	81.44	OK	15370	2026-09-21 02:44	82.44	OK
15371	2026-09-21 02:45	83.43	OK	15372	2026-09-21 02:46	82.75	OK
15373	2026-09-21 02:47	80.56	OK	15374	2026-09-21 02:48	81.02	OK
15375	2026-09-21 02:49	81.69	OK	15376	2026-09-21 02:50	82.66	OK
1537	2026-09-21 02:51	81.81	OK	1537	2026-09-21 02:52	83.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
15379	2026-09-21 02:53	81.38	OK	15380	2026-09-21 02:54	82.97	OK
15381	2026-09-21 02:55	82.65	OK	15382	2026-09-21 02:56	81.14	OK
15383	2026-09-21 02:57	81.64	OK	15384	2026-09-21 02:58	80.66	OK
15385	2026-09-21 02:59	82.88	OK	15386	2026-09-21 03:00	80.15	OK
15387	2026-09-21 03:01	81.08	OK	15388	2026-09-21 03:02	80.41	OK
15389	2026-09-21 03:03	80.32	OK	15390	2026-09-21 03:04	83.26	OK
15391	2026-09-21 03:05	80.91	OK	15392	2026-09-21 03:06	81.99	OK
15393	2026-09-21 03:07	83.28	OK	15394	2026-09-21 03:08	80.98	OK
15395	2026-09-21 03:09	82.72	OK	15396	2026-09-21 03:10	81.72	OK
15397	2026-09-21 03:11	80.32	OK	15398	2026-09-21 03:12	80.45	OK
15399	2026-09-21 03:13	82.42	OK	15400	2026-09-21 03:14	79.05	OK
15401	2026-09-21 03:15	81.20	OK	15402	2026-09-21 03:16	82.05	OK
15403	2026-09-21 03:17	81.65	OK	15404	2026-09-21 03:18	83.15	OK
15405	2026-09-21 03:19	81.38	OK	15406	2026-09-21 03:20	81.43	OK
15407	2026-09-21 03:21	82.64	OK	15408	2026-09-21 03:22	83.75	OK
15409	2026-09-21 03:23	82.96	OK	15410	2026-09-21 03:24	82.59	OK
15411	2026-09-21 03:25	80.69	OK	15412	2026-09-21 03:26	79.89	OK
15413	2026-09-21 03:27	80.81	OK	15414	2026-09-21 03:28	83.93	OK
15415	2026-09-21 03:29	82.00	OK	15416	2026-09-21 03:30	81.04	OK
15417	2026-09-21 03:31	81.03	OK	15418	2026-09-21 03:32	82.30	OK
15419	2026-09-21 03:33	82.29	OK	15420	2026-09-21 03:34	79.99	OK
15421	2026-09-21 03:35	83.21	OK	15422	2026-09-21 03:36	83.17	OK
15423	2026-09-21 03:37	82.41	OK	15424	2026-09-21 03:38	80.72	OK
15425	2026-09-21 03:39	79.64	OK	15426	2026-09-21 03:40	79.08	OK
15427	2026-09-21 03:41	81.44	OK	15428	2026-09-21 03:42	82.90	OK
15429	2026-09-21 03:43	82.47	OK	15430	2026-09-21 03:44	82.41	OK
15431	2026-09-21 03:45	82.16	OK	15432	2026-09-21 03:46	84.20	OK
15433	2026-09-21 03:47	82.29	OK	15434	2026-09-21 03:48	80.25	OK
15435	2026-09-21 03:49	81.25	OK	15436	2026-09-21 03:50	80.96	OK
1543	2026-09-21 03:51	82.05	OK	1543	2026-09-21 03:52	81.88	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
15439	2026-09-21 03:53	80.39	OK	15440	2026-09-21 03:54	82.45	OK
15441	2026-09-21 03:55	83.00	OK	15442	2026-09-21 03:56	82.06	OK
15443	2026-09-21 03:57	82.39	OK	15444	2026-09-21 03:58	81.36	OK
15445	2026-09-21 03:59	83.20	OK	15446	2026-09-21 04:00	80.01	OK
15447	2026-09-21 04:01	81.42	OK	15448	2026-09-21 04:02	82.68	OK
15449	2026-09-21 04:03	82.88	OK	15450	2026-09-21 04:04	80.56	OK
15451	2026-09-21 04:05	83.97	OK	15452	2026-09-21 04:06	80.85	OK
15453	2026-09-21 04:07	80.91	OK	15454	2026-09-21 04:08	82.28	OK
15455	2026-09-21 04:09	82.63	OK	15456	2026-09-21 04:10	81.51	OK
15457	2026-09-21 04:11	84.45	OK	15458	2026-09-21 04:12	81.80	OK
15459	2026-09-21 04:13	82.45	OK	15460	2026-09-21 04:14	81.29	OK
15461	2026-09-21 04:15	79.12	OK	15462	2026-09-21 04:16	79.85	OK
15463	2026-09-21 04:17	79.69	OK	15464	2026-09-21 04:18	81.37	OK
15465	2026-09-21 04:19	78.80	OK	15466	2026-09-21 04:20	80.21	OK
15467	2026-09-21 04:21	81.09	OK	15468	2026-09-21 04:22	81.54	OK
15469	2026-09-21 04:23	82.99	OK	15470	2026-09-21 04:24	81.78	OK
15471	2026-09-21 04:25	82.72	OK	15472	2026-09-21 04:26	81.81	OK
15473	2026-09-21 04:27	82.01	OK	15474	2026-09-21 04:28	82.39	OK
15475	2026-09-21 04:29	80.18	OK	15476	2026-09-21 04:30	83.69	OK
15477	2026-09-21 04:31	80.01	OK	15478	2026-09-21 04:32	82.70	OK
15479	2026-09-21 04:33	80.94	OK	15480	2026-09-21 04:34	81.09	OK
15481	2026-09-21 04:35	81.43	OK	15482	2026-09-21 04:36	79.86	OK
15483	2026-09-21 04:37	84.25	OK	15484	2026-09-21 04:38	83.67	OK
15485	2026-09-21 04:39	80.58	OK	15486	2026-09-21 04:40	80.93	OK
15487	2026-09-21 04:41	79.12	OK	15488	2026-09-21 04:42	82.05	OK
15489	2026-09-21 04:43	79.62	OK	15490	2026-09-21 04:44	82.02	OK
15491	2026-09-21 04:45	79.64	OK	15492	2026-09-21 04:46	82.28	OK
15493	2026-09-21 04:47	82.87	OK	15494	2026-09-21 04:48	81.24	OK
15495	2026-09-21 04:49	82.92	OK	15496	2026-09-21 04:50	80.65	OK
1549	2026-09-21 04:51	81.11	OK	1549	2026-09-21 04:52	81.91	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
15499	2026-09-21 04:53	79.55	OK	15500	2026-09-21 04:54	81.92	OK
15501	2026-09-21 04:55	83.59	OK	15502	2026-09-21 04:56	83.61	OK
15503	2026-09-21 04:57	80.63	OK	15504	2026-09-21 04:58	80.20	OK
15505	2026-09-21 04:59	80.87	OK	15506	2026-09-21 05:00	82.29	OK
15507	2026-09-21 05:01	80.67	OK	15508	2026-09-21 05:02	82.57	OK
15509	2026-09-21 05:03	81.26	OK	15510	2026-09-21 05:04	80.39	OK
15511	2026-09-21 05:05	79.58	OK	15512	2026-09-21 05:06	82.47	OK
15513	2026-09-21 05:07	80.47	OK	15514	2026-09-21 05:08	83.78	OK
15515	2026-09-21 05:09	79.53	OK	15516	2026-09-21 05:10	82.01	OK
15517	2026-09-21 05:11	79.75	OK	15518	2026-09-21 05:12	81.39	OK
15519	2026-09-21 05:13	81.34	OK	15520	2026-09-21 05:14	81.28	OK
15521	2026-09-21 05:15	79.03	OK	15522	2026-09-21 05:16	80.36	OK
15523	2026-09-21 05:17	81.38	OK	15524	2026-09-21 05:18	78.83	OK
15525	2026-09-21 05:19	82.84	OK	15526	2026-09-21 05:20	80.71	OK
15527	2026-09-21 05:21	79.14	OK	15528	2026-09-21 05:22	80.91	OK
15529	2026-09-21 05:23	78.86	OK	15530	2026-09-21 05:24	82.87	OK
15531	2026-09-21 05:25	81.84	OK	15532	2026-09-21 05:26	82.55	OK
15533	2026-09-21 05:27	79.22	OK	15534	2026-09-21 05:28	81.43	OK
15535	2026-09-21 05:29	80.46	OK	15536	2026-09-21 05:30	82.60	OK
15537	2026-09-21 05:31	80.28	OK	15538	2026-09-21 05:32	78.50	OK
15539	2026-09-21 05:33	80.70	OK	15540	2026-09-21 05:34	83.40	OK
15541	2026-09-21 05:35	81.42	OK	15542	2026-09-21 05:36	80.00	OK
15543	2026-09-21 05:37	80.61	OK	15544	2026-09-21 05:38	80.84	OK
15545	2026-09-21 05:39	79.28	OK	15546	2026-09-21 05:40	79.08	OK
15547	2026-09-21 05:41	77.97	OK	15548	2026-09-21 05:42	80.47	OK
15549	2026-09-21 05:43	77.94	OK	15550	2026-09-21 05:44	80.15	OK
15551	2026-09-21 05:45	80.05	OK	15552	2026-09-21 05:46	78.67	OK
15553	2026-09-21 05:47	81.16	OK	15554	2026-09-21 05:48	79.22	OK
15555	2026-09-21 05:49	79.57	OK	15556	2026-09-21 05:50	81.70	OK
1555	2026-09-21 05:51	79.81	OK	1555	2026-09-21 05:52	81.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
15559	2026-09-21 05:53	79.65	OK	15560	2026-09-21 05:54	78.20	OK
15561	2026-09-21 05:55	79.10	OK	15562	2026-09-21 05:56	79.78	OK
15563	2026-09-21 05:57	79.81	OK	15564	2026-09-21 05:58	79.41	OK
15565	2026-09-21 05:59	80.73	OK	15566	2026-09-21 06:00	80.97	OK
15567	2026-09-21 06:01	79.23	OK	15568	2026-09-21 06:02	79.42	OK
15569	2026-09-21 06:03	80.09	OK	15570	2026-09-21 06:04	80.30	OK
15571	2026-09-21 06:05	80.35	OK	15572	2026-09-21 06:06	80.88	OK
15573	2026-09-21 06:07	80.63	OK	15574	2026-09-21 06:08	79.39	OK
15575	2026-09-21 06:09	81.86	OK	15576	2026-09-21 06:10	80.93	OK
15577	2026-09-21 06:11	77.87	OK	15578	2026-09-21 06:12	80.03	OK
15579	2026-09-21 06:13	80.58	OK	15580	2026-09-21 06:14	80.32	OK
15581	2026-09-21 06:15	80.49	OK	15582	2026-09-21 06:16	79.62	OK
15583	2026-09-21 06:17	79.03	OK	15584	2026-09-21 06:18	80.61	OK
15585	2026-09-21 06:19	80.40	OK	15586	2026-09-21 06:20	80.28	OK
15587	2026-09-21 06:21	80.71	OK	15588	2026-09-21 06:22	77.80	OK
15589	2026-09-21 06:23	80.27	OK	15590	2026-09-21 06:24	81.03	OK
15591	2026-09-21 06:25	78.18	OK	15592	2026-09-21 06:26	77.40	OK
15593	2026-09-21 06:27	80.85	OK	15594	2026-09-21 06:28	79.36	OK
15595	2026-09-21 06:29	79.92	OK	15596	2026-09-21 06:30	80.66	OK
15597	2026-09-21 06:31	78.03	OK	15598	2026-09-21 06:32	79.92	OK
15599	2026-09-21 06:33	81.11	OK	15600	2026-09-21 06:34	78.48	OK
15601	2026-09-21 06:35	80.58	OK	15602	2026-09-21 06:36	79.53	OK
15603	2026-09-21 06:37	76.74	OK	15604	2026-09-21 06:38	79.27	OK
15605	2026-09-21 06:39	80.67	OK	15606	2026-09-21 06:40	80.03	OK
15607	2026-09-21 06:41	79.77	OK	15608	2026-09-21 06:42	78.87	OK
15609	2026-09-21 06:43	78.09	OK	15610	2026-09-21 06:44	78.41	OK
15611	2026-09-21 06:45	82.67	OK	15612	2026-09-21 06:46	77.09	OK
15613	2026-09-21 06:47	79.52	OK	15614	2026-09-21 06:48	78.82	OK
15615	2026-09-21 06:49	80.39	OK	15616	2026-09-21 06:50	79.85	OK
1561	2026-09-21 06:51	76.45	OK	1561	2026-09-21 06:52	80.12	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
15619	2026-09-21 06:53	79.10	OK	15620	2026-09-21 06:54	79.47	OK
15621	2026-09-21 06:55	78.02	OK	15622	2026-09-21 06:56	78.87	OK
15623	2026-09-21 06:57	79.21	OK	15624	2026-09-21 06:58	78.00	OK
15625	2026-09-21 06:59	80.14	OK	15626	2026-09-21 07:00	78.15	OK
15627	2026-09-21 07:01	79.04	OK	15628	2026-09-21 07:02	78.62	OK
15629	2026-09-21 07:03	79.43	OK	15630	2026-09-21 07:04	79.10	OK
15631	2026-09-21 07:05	78.14	OK	15632	2026-09-21 07:06	80.10	OK
15633	2026-09-21 07:07	77.82	OK	15634	2026-09-21 07:08	78.56	OK
15635	2026-09-21 07:09	79.92	OK	15636	2026-09-21 07:10	78.13	OK
15637	2026-09-21 07:11	79.03	OK	15638	2026-09-21 07:12	77.60	OK
15639	2026-09-21 07:13	79.22	OK	15640	2026-09-21 07:14	77.89	OK
15641	2026-09-21 07:15	78.37	OK	15642	2026-09-21 07:16	77.86	OK
15643	2026-09-21 07:17	78.08	OK	15644	2026-09-21 07:18	76.99	OK
15645	2026-09-21 07:19	79.52	OK	15646	2026-09-21 07:20	78.37	OK
15647	2026-09-21 07:21	77.61	OK	15648	2026-09-21 07:22	79.31	OK
15649	2026-09-21 07:23	80.80	OK	15650	2026-09-21 07:24	77.14	OK
15651	2026-09-21 07:25	78.80	OK	15652	2026-09-21 07:26	79.13	OK
15653	2026-09-21 07:27	79.24	OK	15654	2026-09-21 07:28	77.23	OK
15655	2026-09-21 07:29	79.98	OK	15656	2026-09-21 07:30	77.29	OK
15657	2026-09-21 07:31	78.44	OK	15658	2026-09-21 07:32	76.58	OK
15659	2026-09-21 07:33	77.08	OK	15660	2026-09-21 07:34	77.95	OK
15661	2026-09-21 07:35	78.56	OK	15662	2026-09-21 07:36	80.04	OK
15663	2026-09-21 07:37	79.04	OK	15664	2026-09-21 07:38	78.15	OK
15665	2026-09-21 07:39	79.79	OK	15666	2026-09-21 07:40	75.74	OK
15667	2026-09-21 07:41	78.50	OK	15668	2026-09-21 07:42	78.50	OK
15669	2026-09-21 07:43	78.13	OK	15670	2026-09-21 07:44	79.25	OK
15671	2026-09-21 07:45	78.65	OK	15672	2026-09-21 07:46	76.03	OK
15673	2026-09-21 07:47	78.04	OK	15674	2026-09-21 07:48	78.22	OK
15675	2026-09-21 07:49	78.79	OK	15676	2026-09-21 07:50	78.38	OK
1567	2026-09-21 07:51	78.14	OK	1567	2026-09-21 07:52	75.45	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
15679	2026-09-21 07:53	80.09	OK	15680	2026-09-21 07:54	75.02	OK
15681	2026-09-21 07:55	77.03	OK	15682	2026-09-21 07:56	80.02	OK
15683	2026-09-21 07:57	79.09	OK	15684	2026-09-21 07:58	75.57	OK
15685	2026-09-21 07:59	75.70	OK	15686	2026-09-21 08:00	78.68	OK
15687	2026-09-21 08:01	78.67	OK	15688	2026-09-21 08:02	77.91	OK
15689	2026-09-21 08:03	78.66	OK	15690	2026-09-21 08:04	77.21	OK
15691	2026-09-21 08:05	78.00	OK	15692	2026-09-21 08:06	78.11	OK
15693	2026-09-21 08:07	78.67	OK	15694	2026-09-21 08:08	79.12	OK
15695	2026-09-21 08:09	77.92	OK	15696	2026-09-21 08:10	76.63	OK
15697	2026-09-21 08:11	77.67	OK	15698	2026-09-21 08:12	76.15	OK
15699	2026-09-21 08:13	76.91	OK	15700	2026-09-21 08:14	77.43	OK
15701	2026-09-21 08:15	77.13	OK	15702	2026-09-21 08:16	78.60	OK
15703	2026-09-21 08:17	78.76	OK	15704	2026-09-21 08:18	75.36	OK
15705	2026-09-21 08:19	75.83	OK	15706	2026-09-21 08:20	78.15	OK
15707	2026-09-21 08:21	74.33	OK	15708	2026-09-21 08:22	75.87	OK
15709	2026-09-21 08:23	76.81	OK	15710	2026-09-21 08:24	75.91	OK
15711	2026-09-21 08:25	76.95	OK	15712	2026-09-21 08:26	77.37	OK
15713	2026-09-21 08:27	76.82	OK	15714	2026-09-21 08:28	76.47	OK
15715	2026-09-21 08:29	77.75	OK	15716	2026-09-21 08:30	75.72	OK
15717	2026-09-21 08:31	76.91	OK	15718	2026-09-21 08:32	77.18	OK
15719	2026-09-21 08:33	77.92	OK	15720	2026-09-21 08:34	77.63	OK
15721	2026-09-21 08:35	75.65	OK	15722	2026-09-21 08:36	76.47	OK
15723	2026-09-21 08:37	76.06	OK	15724	2026-09-21 08:38	76.91	OK
15725	2026-09-21 08:39	78.28	OK	15726	2026-09-21 08:40	76.01	OK
15727	2026-09-21 08:41	74.79	OK	15728	2026-09-21 08:42	73.94	OK
15729	2026-09-21 08:43	76.35	OK	15730	2026-09-21 08:44	76.64	OK
15731	2026-09-21 08:45	77.10	OK	15732	2026-09-21 08:46	76.81	OK
15733	2026-09-21 08:47	74.89	OK	15734	2026-09-21 08:48	74.51	OK
15735	2026-09-21 08:49	76.67	OK	15736	2026-09-21 08:50	78.28	OK
1573	2026-09-21 08:51	74.46	OK	1573	2026-09-21 08:52	75.29	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
15739	2026-09-21 08:53	78.13	OK	15740	2026-09-21 08:54	74.87	OK
15741	2026-09-21 08:55	77.29	OK	15742	2026-09-21 08:56	76.95	OK
15743	2026-09-21 08:57	75.24	OK	15744	2026-09-21 08:58	74.10	OK
15745	2026-09-21 08:59	76.49	OK	15746	2026-09-21 09:00	77.97	OK
15747	2026-09-21 09:01	76.62	OK	15748	2026-09-21 09:02	75.36	OK
15749	2026-09-21 09:03	76.25	OK	15750	2026-09-21 09:04	78.95	OK
15751	2026-09-21 09:05	75.14	OK	15752	2026-09-21 09:06	77.20	OK
15753	2026-09-21 09:07	79.03	OK	15754	2026-09-21 09:08	75.64	OK
15755	2026-09-21 09:09	75.35	OK	15756	2026-09-21 09:10	76.22	OK
15757	2026-09-21 09:11	77.11	OK	15758	2026-09-21 09:12	73.96	OK
15759	2026-09-21 09:13	75.64	OK	15760	2026-09-21 09:14	76.95	OK
15761	2026-09-21 09:15	76.23	OK	15762	2026-09-21 09:16	76.22	OK
15763	2026-09-21 09:17	74.74	OK	15764	2026-09-21 09:18	75.17	OK
15765	2026-09-21 09:19	76.33	OK	15766	2026-09-21 09:20	75.46	OK
15767	2026-09-21 09:21	75.79	OK	15768	2026-09-21 09:22	77.50	OK
15769	2026-09-21 09:23	76.95	OK	15770	2026-09-21 09:24	76.28	OK
15771	2026-09-21 09:25	74.84	OK	15772	2026-09-21 09:26	75.76	OK
15773	2026-09-21 09:27	77.57	OK	15774	2026-09-21 09:28	75.75	OK
15775	2026-09-21 09:29	73.72	OK	15776	2026-09-21 09:30	76.51	OK
15777	2026-09-21 09:31	76.10	OK	15778	2026-09-21 09:32	77.70	OK
15779	2026-09-21 09:33	76.35	OK	15780	2026-09-21 09:34	75.55	OK
15781	2026-09-21 09:35	76.63	OK	15782	2026-09-21 09:36	74.57	OK
15783	2026-09-21 09:37	74.27	OK	15784	2026-09-21 09:38	74.95	OK
15785	2026-09-21 09:39	75.20	OK	15786	2026-09-21 09:40	76.27	OK
15787	2026-09-21 09:41	77.65	OK	15788	2026-09-21 09:42	75.08	OK
15789	2026-09-21 09:43	74.02	OK	15790	2026-09-21 09:44	75.82	OK
15791	2026-09-21 09:45	74.66	OK	15792	2026-09-21 09:46	76.76	OK
15793	2026-09-21 09:47	74.68	OK	15794	2026-09-21 09:48	74.62	OK
15795	2026-09-21 09:49	75.83	OK	15796	2026-09-21 09:50	77.68	OK
15797	2026-09-21 09:51	74.71	OK	15797	2026-09-21 09:52	72.18	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
15799	2026-09-21 09:53	75.61	OK	15800	2026-09-21 09:54	75.11	OK
15801	2026-09-21 09:55	74.96	OK	15802	2026-09-21 09:56	74.26	OK
15803	2026-09-21 09:57	74.43	OK	15804	2026-09-21 09:58	74.52	OK
15805	2026-09-21 09:59	74.49	OK	15806	2026-09-21 10:00	75.27	OK
15807	2026-09-21 10:01	74.44	OK	15808	2026-09-21 10:02	75.43	OK
15809	2026-09-21 10:03	74.86	OK	15810	2026-09-21 10:04	73.32	OK
15811	2026-09-21 10:05	75.76	OK	15812	2026-09-21 10:06	74.16	OK
15813	2026-09-21 10:07	74.45	OK	15814	2026-09-21 10:08	75.54	OK
15815	2026-09-21 10:09	76.27	OK	15816	2026-09-21 10:10	73.81	OK
15817	2026-09-21 10:11	75.31	OK	15818	2026-09-21 10:12	75.87	OK
15819	2026-09-21 10:13	75.08	OK	15820	2026-09-21 10:14	76.24	OK
15821	2026-09-21 10:15	75.43	OK	15822	2026-09-21 10:16	76.37	OK
15823	2026-09-21 10:17	73.94	OK	15824	2026-09-21 10:18	75.24	OK
15825	2026-09-21 10:19	77.48	OK	15826	2026-09-21 10:20	76.21	OK
15827	2026-09-21 10:21	75.28	OK	15828	2026-09-21 10:22	74.73	OK
15829	2026-09-21 10:23	74.55	OK	15830	2026-09-21 10:24	76.15	OK
15831	2026-09-21 10:25	72.65	OK	15832	2026-09-21 10:26	74.34	OK
15833	2026-09-21 10:27	76.58	OK	15834	2026-09-21 10:28	74.77	OK
15835	2026-09-21 10:29	74.68	OK	15836	2026-09-21 10:30	73.60	OK
15837	2026-09-21 10:31	74.11	OK	15838	2026-09-21 10:32	72.35	OK
15839	2026-09-21 10:33	73.93	OK	15840	2026-09-21 10:34	74.38	OK
15841	2026-09-21 10:35	75.41	OK	15842	2026-09-21 10:36	74.83	OK
15843	2026-09-21 10:37	74.62	OK	15844	2026-09-21 10:38	74.18	OK
15845	2026-09-21 10:39	71.54	OK	15846	2026-09-21 10:40	73.27	OK
15847	2026-09-21 10:41	73.19	OK	15848	2026-09-21 10:42	73.49	OK
15849	2026-09-21 10:43	74.30	OK	15850	2026-09-21 10:44	76.07	OK
15851	2026-09-21 10:45	73.60	OK	15852	2026-09-21 10:46	73.64	OK
15853	2026-09-21 10:47	71.69	OK	15854	2026-09-21 10:48	74.64	OK
15855	2026-09-21 10:49	73.50	OK	15856	2026-09-21 10:50	72.96	OK
1585	2026-09-21 10:51	73.45	OK	1585	2026-09-21 10:52	73.84	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
15859	2026-09-21 10:53	74.80	OK	15860	2026-09-21 10:54	75.93	OK
15861	2026-09-21 10:55	76.19	OK	15862	2026-09-21 10:56	72.24	OK
15863	2026-09-21 10:57	74.35	OK	15864	2026-09-21 10:58	74.01	OK
15865	2026-09-21 10:59	74.17	OK	15866	2026-09-21 11:00	73.52	OK
15867	2026-09-21 11:01	74.52	OK	15868	2026-09-21 11:02	74.66	OK
15869	2026-09-21 11:03	72.87	OK	15870	2026-09-21 11:04	72.06	OK
15871	2026-09-21 11:05	75.10	OK	15872	2026-09-21 11:06	74.53	OK
15873	2026-09-21 11:07	73.63	OK	15874	2026-09-21 11:08	74.60	OK
15875	2026-09-21 11:09	71.68	OK	15876	2026-09-21 11:10	72.51	OK
15877	2026-09-21 11:11	75.88	OK	15878	2026-09-21 11:12	73.81	OK
15879	2026-09-21 11:13	74.79	OK	15880	2026-09-21 11:14	71.14	OK
15881	2026-09-21 11:15	72.39	OK	15882	2026-09-21 11:16	74.74	OK
15883	2026-09-21 11:17	72.85	OK	15884	2026-09-21 11:18	72.20	OK
15885	2026-09-21 11:19	73.93	OK	15886	2026-09-21 11:20	72.21	OK
15887	2026-09-21 11:21	71.48	OK	15888	2026-09-21 11:22	71.02	OK
15889	2026-09-21 11:23	74.32	OK	15890	2026-09-21 11:24	75.33	OK
15891	2026-09-21 11:25	75.48	OK	15892	2026-09-21 11:26	73.79	OK
15893	2026-09-21 11:27	73.41	OK	15894	2026-09-21 11:28	73.17	OK
15895	2026-09-21 11:29	72.45	OK	15896	2026-09-21 11:30	73.33	OK
15897	2026-09-21 11:31	72.59	OK	15898	2026-09-21 11:32	71.72	OK
15899	2026-09-21 11:33	73.12	OK	15900	2026-09-21 11:34	71.82	OK
15901	2026-09-21 11:35	72.91	OK	15902	2026-09-21 11:36	72.82	OK
15903	2026-09-21 11:37	74.24	OK	15904	2026-09-21 11:38	71.70	OK
15905	2026-09-21 11:39	72.87	OK	15906	2026-09-21 11:40	74.81	OK
15907	2026-09-21 11:41	72.63	OK	15908	2026-09-21 11:42	74.86	OK
15909	2026-09-21 11:43	73.39	OK	15910	2026-09-21 11:44	72.01	OK
15911	2026-09-21 11:45	73.23	OK	15912	2026-09-21 11:46	71.75	OK
15913	2026-09-21 11:47	73.78	OK	15914	2026-09-21 11:48	72.15	OK
15915	2026-09-21 11:49	70.62	OK	15916	2026-09-21 11:50	72.02	OK
1591	2026-09-21 11:51	73.42	OK	1591	2026-09-21 11:52	72.39	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
15919	2026-09-21 11:53	72.61	OK	15920	2026-09-21 11:54	72.85	OK
15921	2026-09-21 11:55	74.86	OK	15922	2026-09-21 11:56	71.61	OK
15923	2026-09-21 11:57	71.37	OK	15924	2026-09-21 11:58	71.97	OK
15925	2026-09-21 11:59	75.06	OK	15926	2026-09-21 12:00	72.86	OK
15927	2026-09-21 12:01	72.87	OK	15928	2026-09-21 12:02	72.80	OK
15929	2026-09-21 12:03	72.55	OK	15930	2026-09-21 12:04	72.53	OK
15931	2026-09-21 12:05	74.19	OK	15932	2026-09-21 12:06	70.57	OK
15933	2026-09-21 12:07	73.07	OK	15934	2026-09-21 12:08	74.42	OK
15935	2026-09-21 12:09	74.21	OK	15936	2026-09-21 12:10	71.38	OK
15937	2026-09-21 12:11	72.64	OK	15938	2026-09-21 12:12	74.46	OK
15939	2026-09-21 12:13	71.48	OK	15940	2026-09-21 12:14	71.52	OK
15941	2026-09-21 12:15	70.76	OK	15942	2026-09-21 12:16	73.09	OK
15943	2026-09-21 12:17	70.45	OK	15944	2026-09-21 12:18	71.58	OK
15945	2026-09-21 12:19	74.23	OK	15946	2026-09-21 12:20	73.23	OK
15947	2026-09-21 12:21	72.84	OK	15948	2026-09-21 12:22	72.82	OK
15949	2026-09-21 12:23	70.56	OK	15950	2026-09-21 12:24	74.48	OK
15951	2026-09-21 12:25	70.39	OK	15952	2026-09-21 12:26	70.95	OK
15953	2026-09-21 12:27	71.91	OK	15954	2026-09-21 12:28	72.49	OK
15955	2026-09-21 12:29	71.51	OK	15956	2026-09-21 12:30	71.71	OK
15957	2026-09-21 12:31	73.47	OK	15958	2026-09-21 12:32	73.28	OK
15959	2026-09-21 12:33	72.33	OK	15960	2026-09-21 12:34	70.61	OK
15961	2026-09-21 12:35	71.62	OK	15962	2026-09-21 12:36	71.62	OK
15963	2026-09-21 12:37	74.57	OK	15964	2026-09-21 12:38	74.64	OK
15965	2026-09-21 12:39	69.17	OK	15966	2026-09-21 12:40	69.83	OK
15967	2026-09-21 12:41	71.38	OK	15968	2026-09-21 12:42	72.49	OK
15969	2026-09-21 12:43	70.05	OK	15970	2026-09-21 12:44	72.47	OK
15971	2026-09-21 12:45	69.71	OK	15972	2026-09-21 12:46	71.55	OK
15973	2026-09-21 12:47	73.18	OK	15974	2026-09-21 12:48	73.60	OK
15975	2026-09-21 12:49	73.19	OK	15976	2026-09-21 12:50	72.27	OK
15977	2026-09-21 12:51	70.21	OK	15977	2026-09-21 12:52	73.77	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
15979	2026-09-21 12:53	71.46	OK	15980	2026-09-21 12:54	71.31	OK
15981	2026-09-21 12:55	72.14	OK	15982	2026-09-21 12:56	72.90	OK
15983	2026-09-21 12:57	73.06	OK	15984	2026-09-21 12:58	73.32	OK
15985	2026-09-21 12:59	73.24	OK	15986	2026-09-21 13:00	72.70	OK
15987	2026-09-21 13:01	71.09	OK	15988	2026-09-21 13:02	73.45	OK
15989	2026-09-21 13:03	73.17	OK	15990	2026-09-21 13:04	71.31	OK
15991	2026-09-21 13:05	70.26	OK	15992	2026-09-21 13:06	70.08	OK
15993	2026-09-21 13:07	69.89	OK	15994	2026-09-21 13:08	72.00	OK
15995	2026-09-21 13:09	72.92	OK	15996	2026-09-21 13:10	72.65	OK
15997	2026-09-21 13:11	70.19	OK	15998	2026-09-21 13:12	74.71	OK
15999	2026-09-21 13:13	69.27	OK	16000	2026-09-21 13:14	69.14	OK
16001	2026-09-21 13:15	72.99	OK	16002	2026-09-21 13:16	73.65	OK
16003	2026-09-21 13:17	70.27	OK	16004	2026-09-21 13:18	69.33	OK
16005	2026-09-21 13:19	70.68	OK	16006	2026-09-21 13:20	70.77	OK
16007	2026-09-21 13:21	74.59	OK	16008	2026-09-21 13:22	71.10	OK
16009	2026-09-21 13:23	71.26	OK	16010	2026-09-21 13:24	71.99	OK
16011	2026-09-21 13:25	69.85	OK	16012	2026-09-21 13:26	72.90	OK
16013	2026-09-21 13:27	71.85	OK	16014	2026-09-21 13:28	71.56	OK
16015	2026-09-21 13:29	73.18	OK	16016	2026-09-21 13:30	72.89	OK
16017	2026-09-21 13:31	71.13	OK	16018	2026-09-21 13:32	68.65	OK
16019	2026-09-21 13:33	72.91	OK	16020	2026-09-21 13:34	73.17	OK
16021	2026-09-21 13:35	69.96	OK	16022	2026-09-21 13:36	71.14	OK
16023	2026-09-21 13:37	73.06	OK	16024	2026-09-21 13:38	71.53	OK
16025	2026-09-21 13:39	71.07	OK	16026	2026-09-21 13:40	68.87	OK
16027	2026-09-21 13:41	71.39	OK	16028	2026-09-21 13:42	70.43	OK
16029	2026-09-21 13:43	69.87	OK	16030	2026-09-21 13:44	72.40	OK
16031	2026-09-21 13:45	71.06	OK	16032	2026-09-21 13:46	72.91	OK
16033	2026-09-21 13:47	71.44	OK	16034	2026-09-21 13:48	70.86	OK
16035	2026-09-21 13:49	69.44	OK	16036	2026-09-21 13:50	69.19	OK
1603	2026-09-21 13:51	69.77	OK	1603	2026-09-21 13:52	70.18	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
16039	2026-09-21 13:53	72.86	OK	16040	2026-09-21 13:54	72.66	OK
16041	2026-09-21 13:55	70.26	OK	16042	2026-09-21 13:56	70.09	OK
16043	2026-09-21 13:57	74.17	OK	16044	2026-09-21 13:58	71.21	OK
16045	2026-09-21 13:59	74.29	OK	16046	2026-09-21 14:00	70.76	OK
16047	2026-09-21 14:01	73.33	OK	16048	2026-09-21 14:02	71.77	OK
16049	2026-09-21 14:03	70.21	OK	16050	2026-09-21 14:04	70.75	OK
16051	2026-09-21 14:05	70.01	OK	16052	2026-09-21 14:06	70.67	OK
16053	2026-09-21 14:07	71.62	OK	16054	2026-09-21 14:08	70.47	OK
16055	2026-09-21 14:09	72.59	OK	16056	2026-09-21 14:10	71.87	OK
16057	2026-09-21 14:11	71.85	OK	16058	2026-09-21 14:12	70.28	OK
16059	2026-09-21 14:13	70.85	OK	16060	2026-09-21 14:14	73.13	OK
16061	2026-09-21 14:15	70.40	OK	16062	2026-09-21 14:16	74.10	OK
16063	2026-09-21 14:17	70.66	OK	16064	2026-09-21 14:18	69.65	OK
16065	2026-09-21 14:19	72.77	OK	16066	2026-09-21 14:20	68.98	OK
16067	2026-09-21 14:21	72.84	OK	16068	2026-09-21 14:22	71.72	OK
16069	2026-09-21 14:23	71.91	OK	16070	2026-09-21 14:24	70.39	OK
16071	2026-09-21 14:25	74.07	OK	16072	2026-09-21 14:26	69.96	OK
16073	2026-09-21 14:27	69.80	OK	16074	2026-09-21 14:28	70.96	OK
16075	2026-09-21 14:29	70.90	OK	16076	2026-09-21 14:30	71.82	OK
16077	2026-09-21 14:31	69.32	OK	16078	2026-09-21 14:32	70.17	OK
16079	2026-09-21 14:33	71.98	OK	16080	2026-09-21 14:34	70.58	OK
16081	2026-09-21 14:35	70.79	OK	16082	2026-09-21 14:36	70.87	OK
16083	2026-09-21 14:37	70.65	OK	16084	2026-09-21 14:38	70.24	OK
16085	2026-09-21 14:39	72.06	OK	16086	2026-09-21 14:40	71.18	OK
16087	2026-09-21 14:41	70.13	OK	16088	2026-09-21 14:42	69.75	OK
16089	2026-09-21 14:43	71.09	OK	16090	2026-09-21 14:44	70.98	OK
16091	2026-09-21 14:45	73.73	OK	16092	2026-09-21 14:46	70.55	OK
16093	2026-09-21 14:47	70.72	OK	16094	2026-09-21 14:48	72.35	OK
16095	2026-09-21 14:49	72.29	OK	16096	2026-09-21 14:50	71.41	OK
1609	2026-09-21 14:51	71.66	OK	1609	2026-09-21 14:52	71.83	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
16099	2026-09-21 14:53	70.60	OK	16100	2026-09-21 14:54	72.70	OK
16101	2026-09-21 14:55	71.40	OK	16102	2026-09-21 14:56	70.28	OK
16103	2026-09-21 14:57	72.57	OK	16104	2026-09-21 14:58	72.22	OK
16105	2026-09-21 14:59	71.64	OK	16106	2026-09-21 15:00	73.60	OK
16107	2026-09-21 15:01	70.83	OK	16108	2026-09-21 15:02	69.96	OK
16109	2026-09-21 15:03	72.27	OK	16110	2026-09-21 15:04	73.44	OK
16111	2026-09-21 15:05	73.79	OK	16112	2026-09-21 15:06	70.90	OK
16113	2026-09-21 15:07	68.67	OK	16114	2026-09-21 15:08	71.43	OK
16115	2026-09-21 15:09	71.86	OK	16116	2026-09-21 15:10	69.74	OK
16117	2026-09-21 15:11	71.81	OK	16118	2026-09-21 15:12	70.74	OK
16119	2026-09-21 15:13	70.39	OK	16120	2026-09-21 15:14	71.61	OK
16121	2026-09-21 15:15	72.22	OK	16122	2026-09-21 15:16	72.53	OK
16123	2026-09-21 15:17	71.16	OK	16124	2026-09-21 15:18	72.43	OK
16125	2026-09-21 15:19	69.48	OK	16126	2026-09-21 15:20	70.75	OK
16127	2026-09-21 15:21	70.92	OK	16128	2026-09-21 15:22	71.50	OK
16129	2026-09-21 15:23	72.58	OK	16130	2026-09-21 15:24	69.99	OK
16131	2026-09-21 15:25	72.08	OK	16132	2026-09-21 15:26	72.01	OK
16133	2026-09-21 15:27	68.73	OK	16134	2026-09-21 15:28	71.49	OK
16135	2026-09-21 15:29	71.42	OK	16136	2026-09-21 15:30	72.19	OK
16137	2026-09-21 15:31	71.75	OK	16138	2026-09-21 15:32	71.00	OK
16139	2026-09-21 15:33	71.40	OK	16140	2026-09-21 15:34	71.35	OK
16141	2026-09-21 15:35	72.39	OK	16142	2026-09-21 15:36	68.77	OK
16143	2026-09-21 15:37	70.55	OK	16144	2026-09-21 15:38	71.42	OK
16145	2026-09-21 15:39	70.57	OK	16146	2026-09-21 15:40	71.99	OK
16147	2026-09-21 15:41	72.26	OK	16148	2026-09-21 15:42	70.37	OK
16149	2026-09-21 15:43	73.45	OK	16150	2026-09-21 15:44	71.99	OK
16151	2026-09-21 15:45	70.44	OK	16152	2026-09-21 15:46	70.70	OK
16153	2026-09-21 15:47	71.22	OK	16154	2026-09-21 15:48	69.61	OK
16155	2026-09-21 15:49	71.07	OK	16156	2026-09-21 15:50	71.29	OK
1615	2026-09-21 15:51	70.48	OK	1615	2026-09-21 15:52	68.56	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
16159	2026-09-21 15:53	72.55	OK	16160	2026-09-21 15:54	71.41	OK
16161	2026-09-21 15:55	71.06	OK	16162	2026-09-21 15:56	72.41	OK
16163	2026-09-21 15:57	71.79	OK	16164	2026-09-21 15:58	70.81	OK
16165	2026-09-21 15:59	69.47	OK	16166	2026-09-21 16:00	73.34	OK
16167	2026-09-21 16:01	72.68	OK	16168	2026-09-21 16:02	73.43	OK
16169	2026-09-21 16:03	72.14	OK	16170	2026-09-21 16:04	72.95	OK
16171	2026-09-21 16:05	72.10	OK	16172	2026-09-21 16:06	69.22	OK
16173	2026-09-21 16:07	73.85	OK	16174	2026-09-21 16:08	71.17	OK
16175	2026-09-21 16:09	71.01	OK	16176	2026-09-21 16:10	71.48	OK
16177	2026-09-21 16:11	70.55	OK	16178	2026-09-21 16:12	72.27	OK
16179	2026-09-21 16:13	71.46	OK	16180	2026-09-21 16:14	71.29	OK
16181	2026-09-21 16:15	71.37	OK	16182	2026-09-21 16:16	72.18	OK
16183	2026-09-21 16:17	72.39	OK	16184	2026-09-21 16:18	72.49	OK
16185	2026-09-21 16:19	70.84	OK	16186	2026-09-21 16:20	74.59	OK
16187	2026-09-21 16:21	72.24	OK	16188	2026-09-21 16:22	71.45	OK
16189	2026-09-21 16:23	74.55	OK	16190	2026-09-21 16:24	73.29	OK
16191	2026-09-21 16:25	71.42	OK	16192	2026-09-21 16:26	70.42	OK
16193	2026-09-21 16:27	71.24	OK	16194	2026-09-21 16:28	70.98	OK
16195	2026-09-21 16:29	70.78	OK	16196	2026-09-21 16:30	69.73	OK
16197	2026-09-21 16:31	74.11	OK	16198	2026-09-21 16:32	70.82	OK
16199	2026-09-21 16:33	72.96	OK	16200	2026-09-21 16:34	71.20	OK
16201	2026-09-21 16:35	70.34	OK	16202	2026-09-21 16:36	70.07	OK
16203	2026-09-21 16:37	73.42	OK	16204	2026-09-21 16:38	71.91	OK
16205	2026-09-21 16:39	70.65	OK	16206	2026-09-21 16:40	72.15	OK
16207	2026-09-21 16:41	70.96	OK	16208	2026-09-21 16:42	72.97	OK
16209	2026-09-21 16:43	73.94	OK	16210	2026-09-21 16:44	72.02	OK
16211	2026-09-21 16:45	69.68	OK	16212	2026-09-21 16:46	71.61	OK
16213	2026-09-21 16:47	72.38	OK	16214	2026-09-21 16:48	71.99	OK
16215	2026-09-21 16:49	70.15	OK	16216	2026-09-21 16:50	72.21	OK
1621	2026-09-21 16:51	73.17	OK	1621	2026-09-21 16:52	73.41	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
16219	2026-09-21 16:53	72.37	OK	16220	2026-09-21 16:54	74.12	OK
16221	2026-09-21 16:55	72.05	OK	16222	2026-09-21 16:56	75.03	OK
16223	2026-09-21 16:57	71.29	OK	16224	2026-09-21 16:58	74.55	OK
16225	2026-09-21 16:59	72.45	OK	16226	2026-09-21 17:00	70.91	OK
16227	2026-09-21 17:01	71.85	OK	16228	2026-09-21 17:02	71.64	OK
16229	2026-09-21 17:03	71.15	OK	16230	2026-09-21 17:04	70.27	OK
16231	2026-09-21 17:05	72.89	OK	16232	2026-09-21 17:06	71.48	OK
16233	2026-09-21 17:07	71.26	OK	16234	2026-09-21 17:08	72.06	OK
16235	2026-09-21 17:09	73.90	OK	16236	2026-09-21 17:10	72.45	OK
16237	2026-09-21 17:11	71.24	OK	16238	2026-09-21 17:12	69.84	OK
16239	2026-09-21 17:13	72.72	OK	16240	2026-09-21 17:14	74.41	OK
16241	2026-09-21 17:15	74.83	OK	16242	2026-09-21 17:16	74.10	OK
16243	2026-09-21 17:17	72.33	OK	16244	2026-09-21 17:18	71.66	OK
16245	2026-09-21 17:19	71.77	OK	16246	2026-09-21 17:20	71.34	OK
16247	2026-09-21 17:21	72.25	OK	16248	2026-09-21 17:22	70.11	OK
16249	2026-09-21 17:23	73.63	OK	16250	2026-09-21 17:24	71.13	OK
16251	2026-09-21 17:25	72.86	OK	16252	2026-09-21 17:26	71.22	OK
16253	2026-09-21 17:27	73.50	OK	16254	2026-09-21 17:28	71.85	OK
16255	2026-09-21 17:29	71.46	OK	16256	2026-09-21 17:30	73.51	OK
16257	2026-09-21 17:31	72.32	OK	16258	2026-09-21 17:32	71.83	OK
16259	2026-09-21 17:33	70.69	OK	16260	2026-09-21 17:34	71.78	OK
16261	2026-09-21 17:35	70.11	OK	16262	2026-09-21 17:36	71.80	OK
16263	2026-09-21 17:37	72.49	OK	16264	2026-09-21 17:38	70.17	OK
16265	2026-09-21 17:39	70.99	OK	16266	2026-09-21 17:40	70.28	OK
16267	2026-09-21 17:41	74.69	OK	16268	2026-09-21 17:42	72.24	OK
16269	2026-09-21 17:43	73.97	OK	16270	2026-09-21 17:44	71.37	OK
16271	2026-09-21 17:45	71.20	OK	16272	2026-09-21 17:46	73.76	OK
16273	2026-09-21 17:47	72.40	OK	16274	2026-09-21 17:48	71.09	OK
16275	2026-09-21 17:49	73.31	OK	16276	2026-09-21 17:50	71.20	OK
1627	2026-09-21 17:51	73.25	OK	1627	2026-09-21 17:52	71.99	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
16279	2026-09-21 17:53	72.88	OK	16280	2026-09-21 17:54	70.90	OK
16281	2026-09-21 17:55	72.73	OK	16282	2026-09-21 17:56	72.18	OK
16283	2026-09-21 17:57	71.51	OK	16284	2026-09-21 17:58	72.38	OK
16285	2026-09-21 17:59	71.98	OK	16286	2026-09-21 18:00	71.33	OK
16287	2026-09-21 18:01	72.89	OK	16288	2026-09-21 18:02	72.19	OK
16289	2026-09-21 18:03	75.68	OK	16290	2026-09-21 18:04	72.15	OK
16291	2026-09-21 18:05	72.94	OK	16292	2026-09-21 18:06	74.51	OK
16293	2026-09-21 18:07	71.89	OK	16294	2026-09-21 18:08	74.80	OK
16295	2026-09-21 18:09	73.17	OK	16296	2026-09-21 18:10	74.18	OK
16297	2026-09-21 18:11	72.78	OK	16298	2026-09-21 18:12	72.07	OK
16299	2026-09-21 18:13	73.94	OK	16300	2026-09-21 18:14	71.65	OK
16301	2026-09-21 18:15	70.86	OK	16302	2026-09-21 18:16	73.35	OK
16303	2026-09-21 18:17	72.98	OK	16304	2026-09-21 18:18	73.89	OK
16305	2026-09-21 18:19	71.84	OK	16306	2026-09-21 18:20	71.97	OK
16307	2026-09-21 18:21	72.75	OK	16308	2026-09-21 18:22	73.28	OK
16309	2026-09-21 18:23	73.31	OK	16310	2026-09-21 18:24	74.97	OK
16311	2026-09-21 18:25	73.40	OK	16312	2026-09-21 18:26	72.90	OK
16313	2026-09-21 18:27	73.70	OK	16314	2026-09-21 18:28	73.84	OK
16315	2026-09-21 18:29	72.51	OK	16316	2026-09-21 18:30	73.49	OK
16317	2026-09-21 18:31	73.99	OK	16318	2026-09-21 18:32	74.56	OK
16319	2026-09-21 18:33	72.45	OK	16320	2026-09-21 18:34	76.21	OK
16321	2026-09-21 18:35	73.11	OK	16322	2026-09-21 18:36	75.71	OK
16323	2026-09-21 18:37	75.47	OK	16324	2026-09-21 18:38	72.39	OK
16325	2026-09-21 18:39	73.72	OK	16326	2026-09-21 18:40	72.93	OK
16327	2026-09-21 18:41	72.01	OK	16328	2026-09-21 18:42	74.73	OK
16329	2026-09-21 18:43	73.52	OK	16330	2026-09-21 18:44	73.66	OK
16331	2026-09-21 18:45	71.32	OK	16332	2026-09-21 18:46	75.29	OK
16333	2026-09-21 18:47	73.45	OK	16334	2026-09-21 18:48	73.69	OK
16335	2026-09-21 18:49	75.79	OK	16336	2026-09-21 18:50	75.21	OK
1633	2026-09-21 18:51	76.41	OK	1633	2026-09-21 18:52	74.71	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
16339	2026-09-21 18:53	73.45	OK	16340	2026-09-21 18:54	75.00	OK
16341	2026-09-21 18:55	74.66	OK	16342	2026-09-21 18:56	74.90	OK
16343	2026-09-21 18:57	74.56	OK	16344	2026-09-21 18:58	73.94	OK
16345	2026-09-21 18:59	75.35	OK	16346	2026-09-21 19:00	74.25	OK
16347	2026-09-21 19:01	73.19	OK	16348	2026-09-21 19:02	74.56	OK
16349	2026-09-21 19:03	75.55	OK	16350	2026-09-21 19:04	73.24	OK
16351	2026-09-21 19:05	76.50	OK	16352	2026-09-21 19:06	72.95	OK
16353	2026-09-21 19:07	74.03	OK	16354	2026-09-21 19:08	74.08	OK
16355	2026-09-21 19:09	75.80	OK	16356	2026-09-21 19:10	75.28	OK
16357	2026-09-21 19:11	72.97	OK	16358	2026-09-21 19:12	72.30	OK
16359	2026-09-21 19:13	74.10	OK	16360	2026-09-21 19:14	74.52	OK
16361	2026-09-21 19:15	73.69	OK	16362	2026-09-21 19:16	75.18	OK
16363	2026-09-21 19:17	74.01	OK	16364	2026-09-21 19:18	75.94	OK
16365	2026-09-21 19:19	77.14	OK	16366	2026-09-21 19:20	76.12	OK
16367	2026-09-21 19:21	72.87	OK	16368	2026-09-21 19:22	75.01	OK
16369	2026-09-21 19:23	73.44	OK	16370	2026-09-21 19:24	75.85	OK
16371	2026-09-21 19:25	75.34	OK	16372	2026-09-21 19:26	75.47	OK
16373	2026-09-21 19:27	73.66	OK	16374	2026-09-21 19:28	73.96	OK
16375	2026-09-21 19:29	75.41	OK	16376	2026-09-21 19:30	75.43	OK
16377	2026-09-21 19:31	72.91	OK	16378	2026-09-21 19:32	75.54	OK
16379	2026-09-21 19:33	77.08	OK	16380	2026-09-21 19:34	74.98	OK
16381	2026-09-21 19:35	75.00	OK	16382	2026-09-21 19:36	76.11	OK
16383	2026-09-21 19:37	74.95	OK	16384	2026-09-21 19:38	75.41	OK
16385	2026-09-21 19:39	74.96	OK	16386	2026-09-21 19:40	76.13	OK
16387	2026-09-21 19:41	76.34	OK	16388	2026-09-21 19:42	75.98	OK
16389	2026-09-21 19:43	73.03	OK	16390	2026-09-21 19:44	77.19	OK
16391	2026-09-21 19:45	75.18	OK	16392	2026-09-21 19:46	75.48	OK
16393	2026-09-21 19:47	77.58	OK	16394	2026-09-21 19:48	74.65	OK
16395	2026-09-21 19:49	74.14	OK	16396	2026-09-21 19:50	75.59	OK
1639	2026-09-21 19:51	76.77	OK	1639	2026-09-21 19:52	75.31	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
16399	2026-09-21 19:53	76.84	OK	16400	2026-09-21 19:54	74.43	OK
16401	2026-09-21 19:55	76.21	OK	16402	2026-09-21 19:56	75.10	OK
16403	2026-09-21 19:57	76.53	OK	16404	2026-09-21 19:58	76.36	OK
16405	2026-09-21 19:59	76.54	OK	16406	2026-09-21 20:00	77.40	OK
16407	2026-09-21 20:01	75.32	OK	16408	2026-09-21 20:02	76.50	OK
16409	2026-09-21 20:03	74.85	OK	16410	2026-09-21 20:04	74.06	OK
16411	2026-09-21 20:05	76.34	OK	16412	2026-09-21 20:06	76.57	OK
16413	2026-09-21 20:07	74.70	OK	16414	2026-09-21 20:08	78.05	OK
16415	2026-09-21 20:09	76.47	OK	16416	2026-09-21 20:10	77.33	OK
16417	2026-09-21 20:11	76.30	OK	16418	2026-09-21 20:12	75.99	OK
16419	2026-09-21 20:13	74.02	OK	16420	2026-09-21 20:14	73.49	OK
16421	2026-09-21 20:15	76.95	OK	16422	2026-09-21 20:16	76.73	OK
16423	2026-09-21 20:17	75.75	OK	16424	2026-09-21 20:18	76.97	OK
16425	2026-09-21 20:19	77.08	OK	16426	2026-09-21 20:20	77.34	OK
16427	2026-09-21 20:21	73.52	OK	16428	2026-09-21 20:22	76.49	OK
16429	2026-09-21 20:23	76.05	OK	16430	2026-09-21 20:24	76.44	OK
16431	2026-09-21 20:25	74.80	OK	16432	2026-09-21 20:26	78.84	OK
16433	2026-09-21 20:27	74.33	OK	16434	2026-09-21 20:28	76.39	OK
16435	2026-09-21 20:29	75.55	OK	16436	2026-09-21 20:30	75.61	OK
16437	2026-09-21 20:31	78.09	OK	16438	2026-09-21 20:32	74.89	OK
16439	2026-09-21 20:33	76.48	OK	16440	2026-09-21 20:34	74.93	OK
16441	2026-09-21 20:35	76.41	OK	16442	2026-09-21 20:36	78.19	OK
16443	2026-09-21 20:37	75.48	OK	16444	2026-09-21 20:38	79.07	OK
16445	2026-09-21 20:39	75.09	OK	16446	2026-09-21 20:40	74.44	OK
16447	2026-09-21 20:41	74.88	OK	16448	2026-09-21 20:42	75.88	OK
16449	2026-09-21 20:43	75.53	OK	16450	2026-09-21 20:44	77.91	OK
16451	2026-09-21 20:45	78.24	OK	16452	2026-09-21 20:46	75.67	OK
16453	2026-09-21 20:47	75.56	OK	16454	2026-09-21 20:48	78.89	OK
16455	2026-09-21 20:49	74.75	OK	16456	2026-09-21 20:50	78.01	OK
1645	2026-09-21 20:51	75.56	OK	1645	2026-09-21 20:52	76.39	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
16459	2026-09-21 20:53	74.40	OK	16460	2026-09-21 20:54	74.65	OK
16461	2026-09-21 20:55	77.62	OK	16462	2026-09-21 20:56	77.46	OK
16463	2026-09-21 20:57	76.07	OK	16464	2026-09-21 20:58	75.95	OK
16465	2026-09-21 20:59	77.12	OK	16466	2026-09-21 21:00	75.02	OK
16467	2026-09-21 21:01	75.45	OK	16468	2026-09-21 21:02	76.57	OK
16469	2026-09-21 21:03	77.65	OK	16470	2026-09-21 21:04	76.74	OK
16471	2026-09-21 21:05	75.67	OK	16472	2026-09-21 21:06	76.59	OK
16473	2026-09-21 21:07	76.92	OK	16474	2026-09-21 21:08	77.88	OK
16475	2026-09-21 21:09	78.19	OK	16476	2026-09-21 21:10	77.87	OK
16477	2026-09-21 21:11	77.74	OK	16478	2026-09-21 21:12	75.30	OK
16479	2026-09-21 21:13	76.85	OK	16480	2026-09-21 21:14	76.96	OK
16481	2026-09-21 21:15	75.11	OK	16482	2026-09-21 21:16	77.54	OK
16483	2026-09-21 21:17	79.87	OK	16484	2026-09-21 21:18	74.76	OK
16485	2026-09-21 21:19	79.38	OK	16486	2026-09-21 21:20	78.29	OK
16487	2026-09-21 21:21	77.90	OK	16488	2026-09-21 21:22	78.55	OK
16489	2026-09-21 21:23	78.69	OK	16490	2026-09-21 21:24	78.32	OK
16491	2026-09-21 21:25	75.78	OK	16492	2026-09-21 21:26	77.72	OK
16493	2026-09-21 21:27	74.87	OK	16494	2026-09-21 21:28	78.69	OK
16495	2026-09-21 21:29	78.24	OK	16496	2026-09-21 21:30	77.07	OK
16497	2026-09-21 21:31	75.76	OK	16498	2026-09-21 21:32	77.82	OK
16499	2026-09-21 21:33	74.82	OK	16500	2026-09-21 21:34	78.86	OK
16501	2026-09-21 21:35	76.01	OK	16502	2026-09-21 21:36	80.10	OK
16503	2026-09-21 21:37	76.61	OK	16504	2026-09-21 21:38	77.83	OK
16505	2026-09-21 21:39	77.83	OK	16506	2026-09-21 21:40	75.92	OK
16507	2026-09-21 21:41	78.53	OK	16508	2026-09-21 21:42	77.72	OK
16509	2026-09-21 21:43	75.19	OK	16510	2026-09-21 21:44	75.50	OK
16511	2026-09-21 21:45	76.28	OK	16512	2026-09-21 21:46	77.17	OK
16513	2026-09-21 21:47	77.35	OK	16514	2026-09-21 21:48	78.74	OK
16515	2026-09-21 21:49	76.80	OK	16516	2026-09-21 21:50	80.35	OK
1651	2026-09-21 21:51	78.81	OK	1651	2026-09-21 21:52	79.31	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
16519	2026-09-21 21:53	77.44	OK	16520	2026-09-21 21:54	77.96	OK
16521	2026-09-21 21:55	75.81	OK	16522	2026-09-21 21:56	79.47	OK
16523	2026-09-21 21:57	78.00	OK	16524	2026-09-21 21:58	79.31	OK
16525	2026-09-21 21:59	78.22	OK	16526	2026-09-21 22:00	77.88	OK
16527	2026-09-21 22:01	77.32	OK	16528	2026-09-21 22:02	77.69	OK
16529	2026-09-21 22:03	78.19	OK	16530	2026-09-21 22:04	79.72	OK
16531	2026-09-21 22:05	77.82	OK	16532	2026-09-21 22:06	76.50	OK
16533	2026-09-21 22:07	79.84	OK	16534	2026-09-21 22:08	78.39	OK
16535	2026-09-21 22:09	77.88	OK	16536	2026-09-21 22:10	79.75	OK
16537	2026-09-21 22:11	77.02	OK	16538	2026-09-21 22:12	78.41	OK
16539	2026-09-21 22:13	79.29	OK	16540	2026-09-21 22:14	77.47	OK
16541	2026-09-21 22:15	77.15	OK	16542	2026-09-21 22:16	78.21	OK
16543	2026-09-21 22:17	78.85	OK	16544	2026-09-21 22:18	79.21	OK
16545	2026-09-21 22:19	77.05	OK	16546	2026-09-21 22:20	78.77	OK
16547	2026-09-21 22:21	79.25	OK	16548	2026-09-21 22:22	77.96	OK
16549	2026-09-21 22:23	79.88	OK	16550	2026-09-21 22:24	77.25	OK
16551	2026-09-21 22:25	78.95	OK	16552	2026-09-21 22:26	77.58	OK
16553	2026-09-21 22:27	77.18	OK	16554	2026-09-21 22:28	79.75	OK
16555	2026-09-21 22:29	77.54	OK	16556	2026-09-21 22:30	80.30	OK
16557	2026-09-21 22:31	79.08	OK	16558	2026-09-21 22:32	77.98	OK
16559	2026-09-21 22:33	80.31	OK	16560	2026-09-21 22:34	79.76	OK
16561	2026-09-21 22:35	78.10	OK	16562	2026-09-21 22:36	78.01	OK
16563	2026-09-21 22:37	80.29	OK	16564	2026-09-21 22:38	79.53	OK
16565	2026-09-21 22:39	77.38	OK	16566	2026-09-21 22:40	80.90	OK
16567	2026-09-21 22:41	78.68	OK	16568	2026-09-21 22:42	79.16	OK
16569	2026-09-21 22:43	80.17	OK	16570	2026-09-21 22:44	79.48	OK
16571	2026-09-21 22:45	78.70	OK	16572	2026-09-21 22:46	80.35	OK
16573	2026-09-21 22:47	80.21	OK	16574	2026-09-21 22:48	78.46	OK
16575	2026-09-21 22:49	78.10	OK	16576	2026-09-21 22:50	76.73	OK
1657	2026-09-21 22:51	78.08	OK	1657	2026-09-21 22:52	77.19	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
16579	2026-09-21 22:53	78.34	OK	16580	2026-09-21 22:54	79.90	OK
16581	2026-09-21 22:55	78.94	OK	16582	2026-09-21 22:56	78.49	OK
16583	2026-09-21 22:57	79.97	OK	16584	2026-09-21 22:58	80.71	OK
16585	2026-09-21 22:59	78.83	OK	16586	2026-09-21 23:00	78.89	OK
16587	2026-09-21 23:01	76.97	OK	16588	2026-09-21 23:02	79.13	OK
16589	2026-09-21 23:03	77.84	OK	16590	2026-09-21 23:04	80.25	OK
16591	2026-09-21 23:05	78.87	OK	16592	2026-09-21 23:06	81.47	OK
16593	2026-09-21 23:07	79.16	OK	16594	2026-09-21 23:08	80.21	OK
16595	2026-09-21 23:09	80.49	OK	16596	2026-09-21 23:10	80.18	OK
16597	2026-09-21 23:11	77.24	OK	16598	2026-09-21 23:12	79.32	OK
16599	2026-09-21 23:13	79.22	OK	16600	2026-09-21 23:14	80.78	OK
16601	2026-09-21 23:15	79.76	OK	16602	2026-09-21 23:16	78.65	OK
16603	2026-09-21 23:17	80.21	OK	16604	2026-09-21 23:18	80.78	OK
16605	2026-09-21 23:19	80.30	OK	16606	2026-09-21 23:20	79.42	OK
16607	2026-09-21 23:21	79.82	OK	16608	2026-09-21 23:22	81.02	OK
16609	2026-09-21 23:23	79.07	OK	16610	2026-09-21 23:24	80.15	OK
16611	2026-09-21 23:25	79.31	OK	16612	2026-09-21 23:26	78.45	OK
16613	2026-09-21 23:27	81.46	OK	16614	2026-09-21 23:28	81.09	OK
16615	2026-09-21 23:29	81.14	OK	16616	2026-09-21 23:30	80.41	OK
16617	2026-09-21 23:31	79.56	OK	16618	2026-09-21 23:32	78.61	OK
16619	2026-09-21 23:33	79.02	OK	16620	2026-09-21 23:34	81.75	OK
16621	2026-09-21 23:35	81.47	OK	16622	2026-09-21 23:36	79.96	OK
16623	2026-09-21 23:37	79.42	OK	16624	2026-09-21 23:38	79.41	OK
16625	2026-09-21 23:39	79.84	OK	16626	2026-09-21 23:40	80.48	OK
16627	2026-09-21 23:41	80.20	OK	16628	2026-09-21 23:42	80.85	OK
16629	2026-09-21 23:43	81.79	OK	16630	2026-09-21 23:44	80.20	OK
16631	2026-09-21 23:45	81.76	OK	16632	2026-09-21 23:46	77.99	OK
16633	2026-09-21 23:47	79.41	OK	16634	2026-09-21 23:48	82.98	OK
16635	2026-09-21 23:49	80.52	OK	16636	2026-09-21 23:50	79.52	OK
1663	2026-09-21 23:51	82.10	OK	1663	2026-09-21 23:52	76.98	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
16639	2026-09-21 23:53	80.55	OK	16640	2026-09-21 23:54	81.19	OK
16641	2026-09-21 23:55	80.36	OK	16642	2026-09-21 23:56	79.33	OK
16643	2026-09-21 23:57	81.31	OK	16644	2026-09-21 23:58	77.99	OK
16645	2026-09-21 23:59	80.81	OK	16646	2026-09-22 00:00	81.25	OK
16647	2026-09-22 00:01	81.51	OK	16648	2026-09-22 00:02	79.15	OK
16649	2026-09-22 00:03	79.35	OK	16650	2026-09-22 00:04	79.33	OK
16651	2026-09-22 00:05	83.72	OK	16652	2026-09-22 00:06	81.08	OK
16653	2026-09-22 00:07	81.29	OK	16654	2026-09-22 00:08	81.78	OK
16655	2026-09-22 00:09	82.87	OK	16656	2026-09-22 00:10	79.02	OK
16657	2026-09-22 00:11	78.07	OK	16658	2026-09-22 00:12	79.94	OK
16659	2026-09-22 00:13	81.40	OK	16660	2026-09-22 00:14	80.68	OK
16661	2026-09-22 00:15	81.48	OK	16662	2026-09-22 00:16	79.56	OK
16663	2026-09-22 00:17	81.78	OK	16664	2026-09-22 00:18	80.75	OK
16665	2026-09-22 00:19	81.44	OK	16666	2026-09-22 00:20	81.44	OK
16667	2026-09-22 00:21	82.69	OK	16668	2026-09-22 00:22	80.48	OK
16669	2026-09-22 00:23	81.57	OK	16670	2026-09-22 00:24	78.59	OK
16671	2026-09-22 00:25	81.46	OK	16672	2026-09-22 00:26	81.62	OK
16673	2026-09-22 00:27	79.94	OK	16674	2026-09-22 00:28	79.18	OK
16675	2026-09-22 00:29	79.77	OK	16676	2026-09-22 00:30	80.72	OK
16677	2026-09-22 00:31	81.21	OK	16678	2026-09-22 00:32	80.22	OK
16679	2026-09-22 00:33	82.85	OK	16680	2026-09-22 00:34	83.78	OK
16681	2026-09-22 00:35	79.90	OK	16682	2026-09-22 00:36	81.93	OK
16683	2026-09-22 00:37	82.52	OK	16684	2026-09-22 00:38	79.83	OK
16685	2026-09-22 00:39	82.34	OK	16686	2026-09-22 00:40	81.76	OK
16687	2026-09-22 00:41	82.47	OK	16688	2026-09-22 00:42	80.47	OK
16689	2026-09-22 00:43	80.96	OK	16690	2026-09-22 00:44	80.86	OK
16691	2026-09-22 00:45	81.14	OK	16692	2026-09-22 00:46	80.34	OK
16693	2026-09-22 00:47	82.22	OK	16694	2026-09-22 00:48	80.68	OK
16695	2026-09-22 00:49	80.60	OK	16696	2026-09-22 00:50	80.95	OK
16697	2026-09-22 00:51	82.03	OK	16697	2026-09-22 00:52	80.30	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
16699	2026-09-22 00:53	83.10	OK	16700	2026-09-22 00:54	81.32	OK
16701	2026-09-22 00:55	83.74	OK	16702	2026-09-22 00:56	80.18	OK
16703	2026-09-22 00:57	82.30	OK	16704	2026-09-22 00:58	81.49	OK
16705	2026-09-22 00:59	79.57	OK	16706	2026-09-22 01:00	78.60	OK
16707	2026-09-22 01:01	82.10	OK	16708	2026-09-22 01:02	81.12	OK
16709	2026-09-22 01:03	80.59	OK	16710	2026-09-22 01:04	79.70	OK
16711	2026-09-22 01:05	81.66	OK	16712	2026-09-22 01:06	78.49	OK
16713	2026-09-22 01:07	82.40	OK	16714	2026-09-22 01:08	82.44	OK
16715	2026-09-22 01:09	81.00	OK	16716	2026-09-22 01:10	83.15	OK
16717	2026-09-22 01:11	82.93	OK	16718	2026-09-22 01:12	81.74	OK
16719	2026-09-22 01:13	83.10	OK	16720	2026-09-22 01:14	80.71	OK
16721	2026-09-22 01:15	82.52	OK	16722	2026-09-22 01:16	80.91	OK
16723	2026-09-22 01:17	81.69	OK	16724	2026-09-22 01:18	83.03	OK
16725	2026-09-22 01:19	80.63	OK	16726	2026-09-22 01:20	83.07	OK
16727	2026-09-22 01:21	80.58	OK	16728	2026-09-22 01:22	81.13	OK
16729	2026-09-22 01:23	83.08	OK	16730	2026-09-22 01:24	82.81	OK
16731	2026-09-22 01:25	82.12	OK	16732	2026-09-22 01:26	80.23	OK
16733	2026-09-22 01:27	81.06	OK	16734	2026-09-22 01:28	82.71	OK
16735	2026-09-22 01:29	83.29	OK	16736	2026-09-22 01:30	84.38	OK
16737	2026-09-22 01:31	81.74	OK	16738	2026-09-22 01:32	81.53	OK
16739	2026-09-22 01:33	81.64	OK	16740	2026-09-22 01:34	81.62	OK
16741	2026-09-22 01:35	82.54	OK	16742	2026-09-22 01:36	83.94	OK
16743	2026-09-22 01:37	81.43	OK	16744	2026-09-22 01:38	82.02	OK
16745	2026-09-22 01:39	80.86	OK	16746	2026-09-22 01:40	80.51	OK
16747	2026-09-22 01:41	82.20	OK	16748	2026-09-22 01:42	80.81	OK
16749	2026-09-22 01:43	82.21	OK	16750	2026-09-22 01:44	81.01	OK
16751	2026-09-22 01:45	79.99	OK	16752	2026-09-22 01:46	83.31	OK
16753	2026-09-22 01:47	82.14	OK	16754	2026-09-22 01:48	79.60	OK
16755	2026-09-22 01:49	80.48	OK	16756	2026-09-22 01:50	80.55	OK
1675	2026-09-22 01:51	78.66	OK	1675	2026-09-22 01:52	83.71	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
16759	2026-09-22 01:53	80.04	OK	16760	2026-09-22 01:54	80.32	OK
16761	2026-09-22 01:55	84.21	OK	16762	2026-09-22 01:56	81.54	OK
16763	2026-09-22 01:57	80.91	OK	16764	2026-09-22 01:58	83.09	OK
16765	2026-09-22 01:59	81.57	OK	16766	2026-09-22 02:00	81.30	OK
16767	2026-09-22 02:01	81.64	OK	16768	2026-09-22 02:02	84.53	OK
16769	2026-09-22 02:03	83.93	OK	16770	2026-09-22 02:04	82.87	OK
16771	2026-09-22 02:05	80.83	OK	16772	2026-09-22 02:06	82.71	OK
16773	2026-09-22 02:07	81.09	OK	16774	2026-09-22 02:08	80.88	OK
16775	2026-09-22 02:09	82.22	OK	16776	2026-09-22 02:10	78.53	OK
16777	2026-09-22 02:11	81.07	OK	16778	2026-09-22 02:12	79.70	OK
16779	2026-09-22 02:13	80.91	OK	16780	2026-09-22 02:14	83.17	OK
16781	2026-09-22 02:15	79.34	OK	16782	2026-09-22 02:16	82.73	OK
16783	2026-09-22 02:17	81.02	OK	16784	2026-09-22 02:18	82.07	OK
16785	2026-09-22 02:19	81.87	OK	16786	2026-09-22 02:20	80.73	OK
16787	2026-09-22 02:21	81.42	OK	16788	2026-09-22 02:22	82.64	OK
16789	2026-09-22 02:23	82.53	OK	16790	2026-09-22 02:24	80.10	OK
16791	2026-09-22 02:25	81.30	OK	16792	2026-09-22 02:26	80.95	OK
16793	2026-09-22 02:27	82.06	OK	16794	2026-09-22 02:28	83.15	OK
16795	2026-09-22 02:29	78.89	OK	16796	2026-09-22 02:30	80.25	OK
16797	2026-09-22 02:31	81.62	OK	16798	2026-09-22 02:32	81.65	OK
16799	2026-09-22 02:33	80.26	OK	16800	2026-09-22 02:34	80.22	OK
16801	2026-09-22 02:35	81.60	OK	16802	2026-09-22 02:36	83.06	OK
16803	2026-09-22 02:37	82.58	OK	16804	2026-09-22 02:38	79.06	OK
16805	2026-09-22 02:39	81.25	OK	16806	2026-09-22 02:40	82.78	OK
16807	2026-09-22 02:41	81.71	OK	16808	2026-09-22 02:42	83.64	OK
16809	2026-09-22 02:43	80.56	OK	16810	2026-09-22 02:44	83.64	OK
16811	2026-09-22 02:45	80.46	OK	16812	2026-09-22 02:46	83.08	OK
16813	2026-09-22 02:47	80.18	OK	16814	2026-09-22 02:48	83.43	OK
16815	2026-09-22 02:49	80.13	OK	16816	2026-09-22 02:50	82.63	OK
1681	2026-09-22 02:51	82.07	OK	1681	2026-09-22 02:52	82.05	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
16819	2026-09-22 02:53	81.67	OK	16820	2026-09-22 02:54	80.02	OK
16821	2026-09-22 02:55	80.93	OK	16822	2026-09-22 02:56	84.45	OK
16823	2026-09-22 02:57	82.52	OK	16824	2026-09-22 02:58	82.19	OK
16825	2026-09-22 02:59	80.95	OK	16826	2026-09-22 03:00	80.63	OK
16827	2026-09-22 03:01	80.06	OK	16828	2026-09-22 03:02	84.10	OK
16829	2026-09-22 03:03	80.53	OK	16830	2026-09-22 03:04	81.43	OK
16831	2026-09-22 03:05	82.00	OK	16832	2026-09-22 03:06	79.03	OK
16833	2026-09-22 03:07	82.40	OK	16834	2026-09-22 03:08	79.70	OK
16835	2026-09-22 03:09	79.90	OK	16836	2026-09-22 03:10	81.98	OK
16837	2026-09-22 03:11	81.47	OK	16838	2026-09-22 03:12	83.52	OK
16839	2026-09-22 03:13	82.65	OK	16840	2026-09-22 03:14	82.90	OK
16841	2026-09-22 03:15	78.94	OK	16842	2026-09-22 03:16	82.87	OK
16843	2026-09-22 03:17	79.75	OK	16844	2026-09-22 03:18	81.61	OK
16845	2026-09-22 03:19	83.48	OK	16846	2026-09-22 03:20	83.87	OK
16847	2026-09-22 03:21	83.15	OK	16848	2026-09-22 03:22	80.71	OK
16849	2026-09-22 03:23	80.97	OK	16850	2026-09-22 03:24	82.00	OK
16851	2026-09-22 03:25	78.45	OK	16852	2026-09-22 03:26	81.89	OK
16853	2026-09-22 03:27	81.77	OK	16854	2026-09-22 03:28	83.70	OK
16855	2026-09-22 03:29	80.41	OK	16856	2026-09-22 03:30	81.49	OK
16857	2026-09-22 03:31	79.64	OK	16858	2026-09-22 03:32	81.65	OK
16859	2026-09-22 03:33	80.76	OK	16860	2026-09-22 03:34	82.79	OK
16861	2026-09-22 03:35	81.21	OK	16862	2026-09-22 03:36	82.74	OK
16863	2026-09-22 03:37	84.08	OK	16864	2026-09-22 03:38	80.40	OK
16865	2026-09-22 03:39	83.02	OK	16866	2026-09-22 03:40	78.74	OK
16867	2026-09-22 03:41	81.89	OK	16868	2026-09-22 03:42	81.81	OK
16869	2026-09-22 03:43	81.40	OK	16870	2026-09-22 03:44	83.49	OK
16871	2026-09-22 03:45	82.05	OK	16872	2026-09-22 03:46	81.47	OK
16873	2026-09-22 03:47	82.24	OK	16874	2026-09-22 03:48	80.51	OK
16875	2026-09-22 03:49	79.72	OK	16876	2026-09-22 03:50	83.06	OK
1687	2026-09-22 03:51	80.83	OK	1687	2026-09-22 03:52	82.50	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
16879	2026-09-22 03:53	81.22	OK	16880	2026-09-22 03:54	80.30	OK
16881	2026-09-22 03:55	80.39	OK	16882	2026-09-22 03:56	81.03	OK
16883	2026-09-22 03:57	79.52	OK	16884	2026-09-22 03:58	82.19	OK
16885	2026-09-22 03:59	80.21	OK	16886	2026-09-22 04:00	82.01	OK
16887	2026-09-22 04:01	82.46	OK	16888	2026-09-22 04:02	82.38	OK
16889	2026-09-22 04:03	79.80	OK	16890	2026-09-22 04:04	81.03	OK
16891	2026-09-22 04:05	82.70	OK	16892	2026-09-22 04:06	80.14	OK
16893	2026-09-22 04:07	79.65	OK	16894	2026-09-22 04:08	82.24	OK
16895	2026-09-22 04:09	81.14	OK	16896	2026-09-22 04:10	79.44	OK
16897	2026-09-22 04:11	82.40	OK	16898	2026-09-22 04:12	82.05	OK
16899	2026-09-22 04:13	81.60	OK	16900	2026-09-22 04:14	80.74	OK
16901	2026-09-22 04:15	82.94	OK	16902	2026-09-22 04:16	79.95	OK
16903	2026-09-22 04:17	81.98	OK	16904	2026-09-22 04:18	80.79	OK
16905	2026-09-22 04:19	82.05	OK	16906	2026-09-22 04:20	80.75	OK
16907	2026-09-22 04:21	84.36	OK	16908	2026-09-22 04:22	78.80	OK
16909	2026-09-22 04:23	82.04	OK	16910	2026-09-22 04:24	82.39	OK
16911	2026-09-22 04:25	81.73	OK	16912	2026-09-22 04:26	82.08	OK
16913	2026-09-22 04:27	83.55	OK	16914	2026-09-22 04:28	81.85	OK
16915	2026-09-22 04:29	79.27	OK	16916	2026-09-22 04:30	80.59	OK
16917	2026-09-22 04:31	81.18	OK	16918	2026-09-22 04:32	81.78	OK
16919	2026-09-22 04:33	80.88	OK	16920	2026-09-22 04:34	82.39	OK
16921	2026-09-22 04:35	83.28	OK	16922	2026-09-22 04:36	80.46	OK
16923	2026-09-22 04:37	82.07	OK	16924	2026-09-22 04:38	83.00	OK
16925	2026-09-22 04:39	82.45	OK	16926	2026-09-22 04:40	80.31	OK
16927	2026-09-22 04:41	80.62	OK	16928	2026-09-22 04:42	83.78	OK
16929	2026-09-22 04:43	82.03	OK	16930	2026-09-22 04:44	79.68	OK
16931	2026-09-22 04:45	81.49	OK	16932	2026-09-22 04:46	79.15	OK
16933	2026-09-22 04:47	80.23	OK	16934	2026-09-22 04:48	81.78	OK
16935	2026-09-22 04:49	81.27	OK	16936	2026-09-22 04:50	80.71	OK
1693	2026-09-22 04:51	81.38	OK	1693	2026-09-22 04:52	81.04	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
16939	2026-09-22 04:53	80.40	OK	16940	2026-09-22 04:54	80.86	OK
16941	2026-09-22 04:55	81.82	OK	16942	2026-09-22 04:56	78.01	OK
16943	2026-09-22 04:57	81.05	OK	16944	2026-09-22 04:58	82.10	OK
16945	2026-09-22 04:59	80.21	OK	16946	2026-09-22 05:00	81.94	OK
16947	2026-09-22 05:01	80.29	OK	16948	2026-09-22 05:02	80.61	OK
16949	2026-09-22 05:03	81.20	OK	16950	2026-09-22 05:04	81.20	OK
16951	2026-09-22 05:05	83.75	OK	16952	2026-09-22 05:06	80.92	OK
16953	2026-09-22 05:07	80.82	OK	16954	2026-09-22 05:08	80.71	OK
16955	2026-09-22 05:09	80.09	OK	16956	2026-09-22 05:10	78.90	OK
16957	2026-09-22 05:11	82.18	OK	16958	2026-09-22 05:12	81.50	OK
16959	2026-09-22 05:13	81.87	OK	16960	2026-09-22 05:14	82.56	OK
16961	2026-09-22 05:15	78.93	OK	16962	2026-09-22 05:16	78.99	OK
16963	2026-09-22 05:17	78.33	OK	16964	2026-09-22 05:18	80.92	OK
16965	2026-09-22 05:19	80.21	OK	16966	2026-09-22 05:20	80.84	OK
16967	2026-09-22 05:21	79.72	OK	16968	2026-09-22 05:22	79.41	OK
16969	2026-09-22 05:23	81.59	OK	16970	2026-09-22 05:24	78.07	OK
16971	2026-09-22 05:25	80.04	OK	16972	2026-09-22 05:26	77.68	OK
16973	2026-09-22 05:27	81.41	OK	16974	2026-09-22 05:28	80.89	OK
16975	2026-09-22 05:29	82.60	OK	16976	2026-09-22 05:30	82.60	OK
16977	2026-09-22 05:31	79.78	OK	16978	2026-09-22 05:32	80.22	OK
16979	2026-09-22 05:33	81.70	OK	16980	2026-09-22 05:34	79.55	OK
16981	2026-09-22 05:35	79.44	OK	16982	2026-09-22 05:36	80.19	OK
16983	2026-09-22 05:37	81.17	OK	16984	2026-09-22 05:38	81.07	OK
16985	2026-09-22 05:39	78.90	OK	16986	2026-09-22 05:40	79.91	OK
16987	2026-09-22 05:41	81.96	OK	16988	2026-09-22 05:42	79.90	OK
16989	2026-09-22 05:43	83.88	OK	16990	2026-09-22 05:44	79.02	OK
16991	2026-09-22 05:45	81.45	OK	16992	2026-09-22 05:46	80.98	OK
16993	2026-09-22 05:47	81.47	OK	16994	2026-09-22 05:48	80.32	OK
16995	2026-09-22 05:49	80.56	OK	16996	2026-09-22 05:50	78.47	OK
16997	2026-09-22 05:51	78.95	OK	16997	2026-09-22 05:52	80.33	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
16999	2026-09-22 05:53	80.01	OK	17000	2026-09-22 05:54	81.59	OK
17001	2026-09-22 05:55	82.34	OK	17002	2026-09-22 05:56	79.92	OK
17003	2026-09-22 05:57	81.52	OK	17004	2026-09-22 05:58	78.22	OK
17005	2026-09-22 05:59	80.76	OK	17006	2026-09-22 06:00	79.07	OK
17007	2026-09-22 06:01	79.89	OK	17008	2026-09-22 06:02	79.70	OK
17009	2026-09-22 06:03	80.42	OK	17010	2026-09-22 06:04	80.94	OK
17011	2026-09-22 06:05	79.93	OK	17012	2026-09-22 06:06	79.29	OK
17013	2026-09-22 06:07	80.17	OK	17014	2026-09-22 06:08	79.08	OK
17015	2026-09-22 06:09	80.41	OK	17016	2026-09-22 06:10	79.88	OK
17017	2026-09-22 06:11	81.87	OK	17018	2026-09-22 06:12	78.96	OK
17019	2026-09-22 06:13	79.99	OK	17020	2026-09-22 06:14	78.30	OK
17021	2026-09-22 06:15	82.32	OK	17022	2026-09-22 06:16	81.43	OK
17023	2026-09-22 06:17	81.94	OK	17024	2026-09-22 06:18	77.91	OK
17025	2026-09-22 06:19	79.05	OK	17026	2026-09-22 06:20	81.18	OK
17027	2026-09-22 06:21	80.39	OK	17028	2026-09-22 06:22	76.96	OK
17029	2026-09-22 06:23	79.46	OK	17030	2026-09-22 06:24	81.42	OK
17031	2026-09-22 06:25	79.36	OK	17032	2026-09-22 06:26	78.61	OK
17033	2026-09-22 06:27	78.33	OK	17034	2026-09-22 06:28	81.62	OK
17035	2026-09-22 06:29	78.17	OK	17036	2026-09-22 06:30	79.60	OK
17037	2026-09-22 06:31	79.49	OK	17038	2026-09-22 06:32	81.04	OK
17039	2026-09-22 06:33	80.32	OK	17040	2026-09-22 06:34	81.05	OK
17041	2026-09-22 06:35	80.24	OK	17042	2026-09-22 06:36	79.63	OK
17043	2026-09-22 06:37	79.49	OK	17044	2026-09-22 06:38	78.66	OK
17045	2026-09-22 06:39	80.26	OK	17046	2026-09-22 06:40	80.53	OK
17047	2026-09-22 06:41	79.34	OK	17048	2026-09-22 06:42	82.30	OK
17049	2026-09-22 06:43	78.13	OK	17050	2026-09-22 06:44	80.83	OK
17051	2026-09-22 06:45	80.16	OK	17052	2026-09-22 06:46	79.46	OK
17053	2026-09-22 06:47	79.28	OK	17054	2026-09-22 06:48	79.67	OK
17055	2026-09-22 06:49	80.62	OK	17056	2026-09-22 06:50	80.11	OK
1705	2026-09-22 06:51	78.33	OK	1705	2026-09-22 06:52	78.14	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
17059	2026-09-22 06:53	79.91	OK	17060	2026-09-22 06:54	80.63	OK
17061	2026-09-22 06:55	81.54	OK	17062	2026-09-22 06:56	79.25	OK
17063	2026-09-22 06:57	79.79	OK	17064	2026-09-22 06:58	77.73	OK
17065	2026-09-22 06:59	80.54	OK	17066	2026-09-22 07:00	77.63	OK
17067	2026-09-22 07:01	79.68	OK	17068	2026-09-22 07:02	77.30	OK
17069	2026-09-22 07:03	78.33	OK	17070	2026-09-22 07:04	78.38	OK
17071	2026-09-22 07:05	76.06	OK	17072	2026-09-22 07:06	76.15	OK
17073	2026-09-22 07:07	78.96	OK	17074	2026-09-22 07:08	77.96	OK
17075	2026-09-22 07:09	77.01	OK	17076	2026-09-22 07:10	79.14	OK
17077	2026-09-22 07:11	80.00	OK	17078	2026-09-22 07:12	79.59	OK
17079	2026-09-22 07:13	79.30	OK	17080	2026-09-22 07:14	79.99	OK
17081	2026-09-22 07:15	77.70	OK	17082	2026-09-22 07:16	78.61	OK
17083	2026-09-22 07:17	80.16	OK	17084	2026-09-22 07:18	78.59	OK
17085	2026-09-22 07:19	76.06	OK	17086	2026-09-22 07:20	78.21	OK
17087	2026-09-22 07:21	77.94	OK	17088	2026-09-22 07:22	77.59	OK
17089	2026-09-22 07:23	77.97	OK	17090	2026-09-22 07:24	78.80	OK
17091	2026-09-22 07:25	77.81	OK	17092	2026-09-22 07:26	79.52	OK
17093	2026-09-22 07:27	78.23	OK	17094	2026-09-22 07:28	77.16	OK
17095	2026-09-22 07:29	78.38	OK	17096	2026-09-22 07:30	78.98	OK
17097	2026-09-22 07:31	76.87	OK	17098	2026-09-22 07:32	78.22	OK
17099	2026-09-22 07:33	79.92	OK	17100	2026-09-22 07:34	77.56	OK
17101	2026-09-22 07:35	79.65	OK	17102	2026-09-22 07:36	78.29	OK
17103	2026-09-22 07:37	78.07	OK	17104	2026-09-22 07:38	78.92	OK
17105	2026-09-22 07:39	75.80	OK	17106	2026-09-22 07:40	80.06	OK
17107	2026-09-22 07:41	79.24	OK	17108	2026-09-22 07:42	79.08	OK
17109	2026-09-22 07:43	76.65	OK	17110	2026-09-22 07:44	78.34	OK
17111	2026-09-22 07:45	77.18	OK	17112	2026-09-22 07:46	78.13	OK
17113	2026-09-22 07:47	77.30	OK	17114	2026-09-22 07:48	76.93	OK
17115	2026-09-22 07:49	81.24	OK	17116	2026-09-22 07:50	79.69	OK
17117	2026-09-22 07:51	78.52	OK	17118	2026-09-22 07:52	79.57	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
17119	2026-09-22 07:53	77.92	OK	17120	2026-09-22 07:54	78.51	OK
17121	2026-09-22 07:55	75.75	OK	17122	2026-09-22 07:56	79.00	OK
17123	2026-09-22 07:57	75.48	OK	17124	2026-09-22 07:58	77.96	OK
17125	2026-09-22 07:59	76.79	OK	17126	2026-09-22 08:00	78.79	OK
17127	2026-09-22 08:01	78.19	OK	17128	2026-09-22 08:02	77.72	OK
17129	2026-09-22 08:03	78.12	OK	17130	2026-09-22 08:04	75.78	OK
17131	2026-09-22 08:05	80.15	OK	17132	2026-09-22 08:06	79.00	OK
17133	2026-09-22 08:07	77.57	OK	17134	2026-09-22 08:08	77.65	OK
17135	2026-09-22 08:09	77.02	OK	17136	2026-09-22 08:10	77.24	OK
17137	2026-09-22 08:11	77.54	OK	17138	2026-09-22 08:12	75.30	OK
17139	2026-09-22 08:13	77.82	OK	17140	2026-09-22 08:14	79.73	OK
17141	2026-09-22 08:15	78.46	OK	17142	2026-09-22 08:16	78.58	OK
17143	2026-09-22 08:17	75.96	OK	17144	2026-09-22 08:18	76.36	OK
17145	2026-09-22 08:19	79.30	OK	17146	2026-09-22 08:20	76.23	OK
17147	2026-09-22 08:21	79.23	OK	17148	2026-09-22 08:22	77.67	OK
17149	2026-09-22 08:23	75.85	OK	17150	2026-09-22 08:24	76.80	OK
17151	2026-09-22 08:25	78.11	OK	17152	2026-09-22 08:26	77.88	OK
17153	2026-09-22 08:27	75.11	OK	17154	2026-09-22 08:28	76.93	OK
17155	2026-09-22 08:29	77.10	OK	17156	2026-09-22 08:30	77.10	OK
17157	2026-09-22 08:31	77.48	OK	17158	2026-09-22 08:32	78.49	OK
17159	2026-09-22 08:33	75.63	OK	17160	2026-09-22 08:34	75.65	OK
17161	2026-09-22 08:35	76.12	OK	17162	2026-09-22 08:36	75.66	OK
17163	2026-09-22 08:37	77.14	OK	17164	2026-09-22 08:38	76.82	OK
17165	2026-09-22 08:39	75.92	OK	17166	2026-09-22 08:40	77.53	OK
17167	2026-09-22 08:41	75.70	OK	17168	2026-09-22 08:42	75.39	OK
17169	2026-09-22 08:43	77.34	OK	17170	2026-09-22 08:44	74.95	OK
17171	2026-09-22 08:45	76.30	OK	17172	2026-09-22 08:46	77.01	OK
17173	2026-09-22 08:47	78.03	OK	17174	2026-09-22 08:48	75.88	OK
17175	2026-09-22 08:49	77.63	OK	17176	2026-09-22 08:50	76.40	OK
17177	2026-09-22 08:51	77.55	OK	17177	2026-09-22 08:52	75.59	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
17179	2026-09-22 08:53	73.90	OK	17180	2026-09-22 08:54	74.65	OK
17181	2026-09-22 08:55	77.19	OK	17182	2026-09-22 08:56	74.57	OK
17183	2026-09-22 08:57	76.41	OK	17184	2026-09-22 08:58	77.52	OK
17185	2026-09-22 08:59	75.58	OK	17186	2026-09-22 09:00	78.90	OK
17187	2026-09-22 09:01	74.18	OK	17188	2026-09-22 09:02	75.33	OK
17189	2026-09-22 09:03	74.37	OK	17190	2026-09-22 09:04	75.19	OK
17191	2026-09-22 09:05	75.28	OK	17192	2026-09-22 09:06	78.43	OK
17193	2026-09-22 09:07	75.78	OK	17194	2026-09-22 09:08	76.36	OK
17195	2026-09-22 09:09	76.76	OK	17196	2026-09-22 09:10	77.88	OK
17197	2026-09-22 09:11	77.83	OK	17198	2026-09-22 09:12	78.44	OK
17199	2026-09-22 09:13	74.50	OK	17200	2026-09-22 09:14	75.99	OK
17201	2026-09-22 09:15	74.49	OK	17202	2026-09-22 09:16	73.35	OK
17203	2026-09-22 09:17	77.01	OK	17204	2026-09-22 09:18	76.91	OK
17205	2026-09-22 09:19	75.11	OK	17206	2026-09-22 09:20	76.63	OK
17207	2026-09-22 09:21	79.07	OK	17208	2026-09-22 09:22	76.48	OK
17209	2026-09-22 09:23	75.90	OK	17210	2026-09-22 09:24	76.93	OK
17211	2026-09-22 09:25	75.45	OK	17212	2026-09-22 09:26	75.71	OK
17213	2026-09-22 09:27	77.51	OK	17214	2026-09-22 09:28	75.11	OK
17215	2026-09-22 09:29	76.00	OK	17216	2026-09-22 09:30	73.62	OK
17217	2026-09-22 09:31	75.67	OK	17218	2026-09-22 09:32	74.99	OK
17219	2026-09-22 09:33	75.24	OK	17220	2026-09-22 09:34	77.51	OK
17221	2026-09-22 09:35	77.49	OK	17222	2026-09-22 09:36	76.15	OK
17223	2026-09-22 09:37	77.21	OK	17224	2026-09-22 09:38	73.65	OK
17225	2026-09-22 09:39	74.26	OK	17226	2026-09-22 09:40	74.55	OK
17227	2026-09-22 09:41	75.37	OK	17228	2026-09-22 09:42	74.88	OK
17229	2026-09-22 09:43	73.57	OK	17230	2026-09-22 09:44	76.63	OK
17231	2026-09-22 09:45	73.95	OK	17232	2026-09-22 09:46	75.83	OK
17233	2026-09-22 09:47	76.86	OK	17234	2026-09-22 09:48	75.33	OK
17235	2026-09-22 09:49	75.04	OK	17236	2026-09-22 09:50	74.84	OK
1723	2026-09-22 09:51	74.13	OK	1723	2026-09-22 09:52	77.45	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
17239	2026-09-22 09:53	74.75	OK	17240	2026-09-22 09:54	76.29	OK
17241	2026-09-22 09:55	73.20	OK	17242	2026-09-22 09:56	74.06	OK
17243	2026-09-22 09:57	74.78	OK	17244	2026-09-22 09:58	74.18	OK
17245	2026-09-22 09:59	75.81	OK	17246	2026-09-22 10:00	73.78	OK
17247	2026-09-22 10:01	77.45	OK	17248	2026-09-22 10:02	75.24	OK
17249	2026-09-22 10:03	75.31	OK	17250	2026-09-22 10:04	75.13	OK
17251	2026-09-22 10:05	74.87	OK	17252	2026-09-22 10:06	74.02	OK
17253	2026-09-22 10:07	75.31	OK	17254	2026-09-22 10:08	74.01	OK
17255	2026-09-22 10:09	73.66	OK	17256	2026-09-22 10:10	76.11	OK
17257	2026-09-22 10:11	72.66	OK	17258	2026-09-22 10:12	73.76	OK
17259	2026-09-22 10:13	73.92	OK	17260	2026-09-22 10:14	72.31	OK
17261	2026-09-22 10:15	74.88	OK	17262	2026-09-22 10:16	74.24	OK
17263	2026-09-22 10:17	75.99	OK	17264	2026-09-22 10:18	75.06	OK
17265	2026-09-22 10:19	74.22	OK	17266	2026-09-22 10:20	76.75	OK
17267	2026-09-22 10:21	75.69	OK	17268	2026-09-22 10:22	75.61	OK
17269	2026-09-22 10:23	75.45	OK	17270	2026-09-22 10:24	75.24	OK
17271	2026-09-22 10:25	74.22	OK	17272	2026-09-22 10:26	74.29	OK
17273	2026-09-22 10:27	73.94	OK	17274	2026-09-22 10:28	74.16	OK
17275	2026-09-22 10:29	74.49	OK	17276	2026-09-22 10:30	72.93	OK
17277	2026-09-22 10:31	75.07	OK	17278	2026-09-22 10:32	76.50	OK
17279	2026-09-22 10:33	72.36	OK	17280	2026-09-22 10:34	75.46	OK
17281	2026-09-22 10:35	73.98	OK	17282	2026-09-22 10:36	73.08	OK
17283	2026-09-22 10:37	75.13	OK	17284	2026-09-22 10:38	76.03	OK
17285	2026-09-22 10:39	74.54	OK	17286	2026-09-22 10:40	71.94	OK
17287	2026-09-22 10:41	72.41	OK	17288	2026-09-22 10:42	74.88	OK
17289	2026-09-22 10:43	74.96	OK	17290	2026-09-22 10:44	74.78	OK
17291	2026-09-22 10:45	72.29	OK	17292	2026-09-22 10:46	74.23	OK
17293	2026-09-22 10:47	73.29	OK	17294	2026-09-22 10:48	74.34	OK
17295	2026-09-22 10:49	76.04	OK	17296	2026-09-22 10:50	76.13	OK
1729	2026-09-22 10:51	71.57	OK	1729	2026-09-22 10:52	73.03	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
17299	2026-09-22 10:53	74.64	OK	17300	2026-09-22 10:54	76.02	OK
17301	2026-09-22 10:55	74.90	OK	17302	2026-09-22 10:56	73.21	OK
17303	2026-09-22 10:57	72.18	OK	17304	2026-09-22 10:58	72.90	OK
17305	2026-09-22 10:59	74.09	OK	17306	2026-09-22 11:00	73.93	OK
17307	2026-09-22 11:01	73.83	OK	17308	2026-09-22 11:02	73.59	OK
17309	2026-09-22 11:03	75.29	OK	17310	2026-09-22 11:04	72.66	OK
17311	2026-09-22 11:05	71.91	OK	17312	2026-09-22 11:06	71.61	OK
17313	2026-09-22 11:07	73.88	OK	17314	2026-09-22 11:08	75.14	OK
17315	2026-09-22 11:09	72.93	OK	17316	2026-09-22 11:10	71.85	OK
17317	2026-09-22 11:11	72.20	OK	17318	2026-09-22 11:12	73.65	OK
17319	2026-09-22 11:13	76.02	OK	17320	2026-09-22 11:14	73.98	OK
17321	2026-09-22 11:15	74.12	OK	17322	2026-09-22 11:16	74.16	OK
17323	2026-09-22 11:17	72.04	OK	17324	2026-09-22 11:18	72.53	OK
17325	2026-09-22 11:19	75.68	OK	17326	2026-09-22 11:20	72.08	OK
17327	2026-09-22 11:21	71.97	OK	17328	2026-09-22 11:22	73.02	OK
17329	2026-09-22 11:23	74.48	OK	17330	2026-09-22 11:24	72.18	OK
17331	2026-09-22 11:25	71.81	OK	17332	2026-09-22 11:26	70.48	OK
17333	2026-09-22 11:27	74.00	OK	17334	2026-09-22 11:28	74.55	OK
17335	2026-09-22 11:29	72.14	OK	17336	2026-09-22 11:30	74.53	OK
17337	2026-09-22 11:31	72.31	OK	17338	2026-09-22 11:32	72.91	OK
17339	2026-09-22 11:33	71.75	OK	17340	2026-09-22 11:34	72.21	OK
17341	2026-09-22 11:35	72.36	OK	17342	2026-09-22 11:36	71.78	OK
17343	2026-09-22 11:37	72.41	OK	17344	2026-09-22 11:38	72.26	OK
17345	2026-09-22 11:39	72.64	OK	17346	2026-09-22 11:40	75.04	OK
17347	2026-09-22 11:41	71.54	OK	17348	2026-09-22 11:42	71.47	OK
17349	2026-09-22 11:43	72.21	OK	17350	2026-09-22 11:44	75.63	OK
17351	2026-09-22 11:45	74.31	OK	17352	2026-09-22 11:46	74.21	OK
17353	2026-09-22 11:47	72.77	OK	17354	2026-09-22 11:48	70.99	OK
17355	2026-09-22 11:49	72.31	OK	17356	2026-09-22 11:50	73.35	OK
1735	2026-09-22 11:51	73.65	OK	1735	2026-09-22 11:52	72.83	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
17359	2026-09-22 11:53	73.00	OK	17360	2026-09-22 11:54	74.60	OK
17361	2026-09-22 11:55	74.10	OK	17362	2026-09-22 11:56	73.76	OK
17363	2026-09-22 11:57	73.90	OK	17364	2026-09-22 11:58	71.79	OK
17365	2026-09-22 11:59	74.92	OK	17366	2026-09-22 12:00	71.89	OK
17367	2026-09-22 12:01	72.80	OK	17368	2026-09-22 12:02	70.80	OK
17369	2026-09-22 12:03	70.18	OK	17370	2026-09-22 12:04	69.15	OK
17371	2026-09-22 12:05	74.09	OK	17372	2026-09-22 12:06	73.07	OK
17373	2026-09-22 12:07	72.27	OK	17374	2026-09-22 12:08	71.85	OK
17375	2026-09-22 12:09	73.51	OK	17376	2026-09-22 12:10	71.59	OK
17377	2026-09-22 12:11	75.60	OK	17378	2026-09-22 12:12	72.85	OK
17379	2026-09-22 12:13	73.55	OK	17380	2026-09-22 12:14	73.52	OK
17381	2026-09-22 12:15	70.28	OK	17382	2026-09-22 12:16	72.79	OK
17383	2026-09-22 12:17	72.56	OK	17384	2026-09-22 12:18	72.88	OK
17385	2026-09-22 12:19	72.07	OK	17386	2026-09-22 12:20	74.75	OK
17387	2026-09-22 12:21	72.10	OK	17388	2026-09-22 12:22	71.52	OK
17389	2026-09-22 12:23	71.50	OK	17390	2026-09-22 12:24	72.00	OK
17391	2026-09-22 12:25	72.28	OK	17392	2026-09-22 12:26	71.92	OK
17393	2026-09-22 12:27	72.26	OK	17394	2026-09-22 12:28	73.33	OK
17395	2026-09-22 12:29	70.84	OK	17396	2026-09-22 12:30	71.17	OK
17397	2026-09-22 12:31	70.98	OK	17398	2026-09-22 12:32	72.79	OK
17399	2026-09-22 12:33	72.73	OK	17400	2026-09-22 12:34	72.99	OK
17401	2026-09-22 12:35	72.77	OK	17402	2026-09-22 12:36	71.93	OK
17403	2026-09-22 12:37	70.88	OK	17404	2026-09-22 12:38	72.64	OK
17405	2026-09-22 12:39	71.55	OK	17406	2026-09-22 12:40	73.52	OK
17407	2026-09-22 12:41	73.58	OK	17408	2026-09-22 12:42	69.68	OK
17409	2026-09-22 12:43	73.06	OK	17410	2026-09-22 12:44	70.52	OK
17411	2026-09-22 12:45	73.55	OK	17412	2026-09-22 12:46	73.87	OK
17413	2026-09-22 12:47	73.42	OK	17414	2026-09-22 12:48	73.93	OK
17415	2026-09-22 12:49	72.12	OK	17416	2026-09-22 12:50	71.91	OK
1741	2026-09-22 12:51	71.78	OK	1741	2026-09-22 12:52	70.01	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
17419	2026-09-22 12:53	72.35	OK	17420	2026-09-22 12:54	73.25	OK
17421	2026-09-22 12:55	72.83	OK	17422	2026-09-22 12:56	71.66	OK
17423	2026-09-22 12:57	71.93	OK	17424	2026-09-22 12:58	69.56	OK
17425	2026-09-22 12:59	72.97	OK	17426	2026-09-22 13:00	71.16	OK
17427	2026-09-22 13:01	72.45	OK	17428	2026-09-22 13:02	72.00	OK
17429	2026-09-22 13:03	71.61	OK	17430	2026-09-22 13:04	73.56	OK
17431	2026-09-22 13:05	71.16	OK	17432	2026-09-22 13:06	72.21	OK
17433	2026-09-22 13:07	70.15	OK	17434	2026-09-22 13:08	70.25	OK
17435	2026-09-22 13:09	71.28	OK	17436	2026-09-22 13:10	71.29	OK
17437	2026-09-22 13:11	69.76	OK	17438	2026-09-22 13:12	70.72	OK
17439	2026-09-22 13:13	71.51	OK	17440	2026-09-22 13:14	71.75	OK
17441	2026-09-22 13:15	69.77	OK	17442	2026-09-22 13:16	68.98	OK
17443	2026-09-22 13:17	70.76	OK	17444	2026-09-22 13:18	71.86	OK
17445	2026-09-22 13:19	73.33	OK	17446	2026-09-22 13:20	71.48	OK
17447	2026-09-22 13:21	72.85	OK	17448	2026-09-22 13:22	72.00	OK
17449	2026-09-22 13:23	73.86	OK	17450	2026-09-22 13:24	69.16	OK
17451	2026-09-22 13:25	73.15	OK	17452	2026-09-22 13:26	72.53	OK
17453	2026-09-22 13:27	73.07	OK	17454	2026-09-22 13:28	71.44	OK
17455	2026-09-22 13:29	72.05	OK	17456	2026-09-22 13:30	69.11	OK
17457	2026-09-22 13:31	73.26	OK	17458	2026-09-22 13:32	71.28	OK
17459	2026-09-22 13:33	71.17	OK	17460	2026-09-22 13:34	70.63	OK
17461	2026-09-22 13:35	71.10	OK	17462	2026-09-22 13:36	73.77	OK
17463	2026-09-22 13:37	71.70	OK	17464	2026-09-22 13:38	73.88	OK
17465	2026-09-22 13:39	72.68	OK	17466	2026-09-22 13:40	72.25	OK
17467	2026-09-22 13:41	69.94	OK	17468	2026-09-22 13:42	69.80	OK
17469	2026-09-22 13:43	73.05	OK	17470	2026-09-22 13:44	71.58	OK
17471	2026-09-22 13:45	69.59	OK	17472	2026-09-22 13:46	70.98	OK
17473	2026-09-22 13:47	72.45	OK	17474	2026-09-22 13:48	73.10	OK
17475	2026-09-22 13:49	69.49	OK	17476	2026-09-22 13:50	71.15	OK
17477	2026-09-22 13:51	71.43	OK	17477	2026-09-22 13:52	71.04	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
17479	2026-09-22 13:53	70.82	OK	17480	2026-09-22 13:54	69.68	OK
17481	2026-09-22 13:55	71.23	OK	17482	2026-09-22 13:56	70.50	OK
17483	2026-09-22 13:57	70.41	OK	17484	2026-09-22 13:58	69.02	OK
17485	2026-09-22 13:59	70.38	OK	17486	2026-09-22 14:00	69.94	OK
17487	2026-09-22 14:01	70.89	OK	17488	2026-09-22 14:02	69.89	OK
17489	2026-09-22 14:03	69.91	OK	17490	2026-09-22 14:04	69.76	OK
17491	2026-09-22 14:05	72.73	OK	17492	2026-09-22 14:06	68.95	OK
17493	2026-09-22 14:07	70.91	OK	17494	2026-09-22 14:08	70.18	OK
17495	2026-09-22 14:09	69.95	OK	17496	2026-09-22 14:10	73.02	OK
17497	2026-09-22 14:11	71.84	OK	17498	2026-09-22 14:12	70.86	OK
17499	2026-09-22 14:13	73.14	OK	17500	2026-09-22 14:14	68.87	OK
17501	2026-09-22 14:15	72.91	OK	17502	2026-09-22 14:16	71.08	OK
17503	2026-09-22 14:17	68.90	OK	17504	2026-09-22 14:18	72.31	OK
17505	2026-09-22 14:19	71.44	OK	17506	2026-09-22 14:20	71.33	OK
17507	2026-09-22 14:21	73.66	OK	17508	2026-09-22 14:22	71.85	OK
17509	2026-09-22 14:23	72.10	OK	17510	2026-09-22 14:24	71.06	OK
17511	2026-09-22 14:25	70.01	OK	17512	2026-09-22 14:26	70.21	OK
17513	2026-09-22 14:27	69.83	OK	17514	2026-09-22 14:28	69.48	OK
17515	2026-09-22 14:29	72.37	OK	17516	2026-09-22 14:30	73.17	OK
17517	2026-09-22 14:31	72.06	OK	17518	2026-09-22 14:32	70.58	OK
17519	2026-09-22 14:33	70.65	OK	17520	2026-09-22 14:34	68.37	OK
17521	2026-09-22 14:35	69.83	OK	17522	2026-09-22 14:36	70.85	OK
17523	2026-09-22 14:37	72.03	OK	17524	2026-09-22 14:38	72.50	OK
17525	2026-09-22 14:39	73.68	OK	17526	2026-09-22 14:40	71.67	OK
17527	2026-09-22 14:41	68.05	OK	17528	2026-09-22 14:42	70.15	OK
17529	2026-09-22 14:43	72.50	OK	17530	2026-09-22 14:44	72.75	OK
17531	2026-09-22 14:45	70.33	OK	17532	2026-09-22 14:46	72.37	OK
17533	2026-09-22 14:47	72.96	OK	17534	2026-09-22 14:48	73.47	OK
17535	2026-09-22 14:49	71.99	OK	17536	2026-09-22 14:50	72.05	OK
1753	2026-09-22 14:51	72.93	OK	1753	2026-09-22 14:52	69.99	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
17539	2026-09-22 14:53	72.52	OK	17540	2026-09-22 14:54	72.42	OK
17541	2026-09-22 14:55	69.30	OK	17542	2026-09-22 14:56	72.26	OK
17543	2026-09-22 14:57	72.66	OK	17544	2026-09-22 14:58	68.95	OK
17545	2026-09-22 14:59	70.61	OK	17546	2026-09-22 15:00	69.62	OK
17547	2026-09-22 15:01	70.03	OK	17548	2026-09-22 15:02	70.07	OK
17549	2026-09-22 15:03	72.86	OK	17550	2026-09-22 15:04	72.09	OK
17551	2026-09-22 15:05	74.04	OK	17552	2026-09-22 15:06	69.35	OK
17553	2026-09-22 15:07	71.60	OK	17554	2026-09-22 15:08	72.75	OK
17555	2026-09-22 15:09	71.32	OK	17556	2026-09-22 15:10	73.44	OK
17557	2026-09-22 15:11	73.82	OK	17558	2026-09-22 15:12	72.28	OK
17559	2026-09-22 15:13	73.16	OK	17560	2026-09-22 15:14	69.85	OK
17561	2026-09-22 15:15	71.36	OK	17562	2026-09-22 15:16	71.06	OK
17563	2026-09-22 15:17	72.36	OK	17564	2026-09-22 15:18	70.11	OK
17565	2026-09-22 15:19	72.35	OK	17566	2026-09-22 15:20	72.68	OK
17567	2026-09-22 15:21	72.32	OK	17568	2026-09-22 15:22	71.70	OK
17569	2026-09-22 15:23	71.14	OK	17570	2026-09-22 15:24	70.39	OK
17571	2026-09-22 15:25	70.59	OK	17572	2026-09-22 15:26	70.07	OK
17573	2026-09-22 15:27	70.35	OK	17574	2026-09-22 15:28	71.02	OK
17575	2026-09-22 15:29	71.75	OK	17576	2026-09-22 15:30	72.19	OK
17577	2026-09-22 15:31	71.89	OK	17578	2026-09-22 15:32	71.42	OK
17579	2026-09-22 15:33	71.81	OK	17580	2026-09-22 15:34	70.03	OK
17581	2026-09-22 15:35	70.50	OK	17582	2026-09-22 15:36	72.65	OK
17583	2026-09-22 15:37	71.51	OK	17584	2026-09-22 15:38	70.91	OK
17585	2026-09-22 15:39	72.09	OK	17586	2026-09-22 15:40	71.35	OK
17587	2026-09-22 15:41	70.36	OK	17588	2026-09-22 15:42	69.35	OK
17589	2026-09-22 15:43	70.85	OK	17590	2026-09-22 15:44	71.13	OK
17591	2026-09-22 15:45	72.71	OK	17592	2026-09-22 15:46	69.09	OK
17593	2026-09-22 15:47	70.91	OK	17594	2026-09-22 15:48	69.90	OK
17595	2026-09-22 15:49	70.42	OK	17596	2026-09-22 15:50	69.38	OK
1759	2026-09-22 15:51	71.37	OK	1759	2026-09-22 15:52	71.96	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
17599	2026-09-22 15:53	71.41	OK	17600	2026-09-22 15:54	72.93	OK
17601	2026-09-22 15:55	70.15	OK	17602	2026-09-22 15:56	70.16	OK
17603	2026-09-22 15:57	70.17	OK	17604	2026-09-22 15:58	69.81	OK
17605	2026-09-22 15:59	72.29	OK	17606	2026-09-22 16:00	73.07	OK
17607	2026-09-22 16:01	71.75	OK	17608	2026-09-22 16:02	73.96	OK
17609	2026-09-22 16:03	71.76	OK	17610	2026-09-22 16:04	71.63	OK
17611	2026-09-22 16:05	70.55	OK	17612	2026-09-22 16:06	70.37	OK
17613	2026-09-22 16:07	71.80	OK	17614	2026-09-22 16:08	72.53	OK
17615	2026-09-22 16:09	70.87	OK	17616	2026-09-22 16:10	73.70	OK
17617	2026-09-22 16:11	73.15	OK	17618	2026-09-22 16:12	72.32	OK
17619	2026-09-22 16:13	72.96	OK	17620	2026-09-22 16:14	73.83	OK
17621	2026-09-22 16:15	72.13	OK	17622	2026-09-22 16:16	71.48	OK
17623	2026-09-22 16:17	71.12	OK	17624	2026-09-22 16:18	71.52	OK
17625	2026-09-22 16:19	70.58	OK	17626	2026-09-22 16:20	72.49	OK
17627	2026-09-22 16:21	71.47	OK	17628	2026-09-22 16:22	70.56	OK
17629	2026-09-22 16:23	71.31	OK	17630	2026-09-22 16:24	72.04	OK
17631	2026-09-22 16:25	71.50	OK	17632	2026-09-22 16:26	71.62	OK
17633	2026-09-22 16:27	70.92	OK	17634	2026-09-22 16:28	71.92	OK
17635	2026-09-22 16:29	72.94	OK	17636	2026-09-22 16:30	71.64	OK
17637	2026-09-22 16:31	72.87	OK	17638	2026-09-22 16:32	73.56	OK
17639	2026-09-22 16:33	72.57	OK	17640	2026-09-22 16:34	71.08	OK
17641	2026-09-22 16:35	70.52	OK	17642	2026-09-22 16:36	73.38	OK
17643	2026-09-22 16:37	72.43	OK	17644	2026-09-22 16:38	73.86	OK
17645	2026-09-22 16:39	70.09	OK	17646	2026-09-22 16:40	73.01	OK
17647	2026-09-22 16:41	72.74	OK	17648	2026-09-22 16:42	72.92	OK
17649	2026-09-22 16:43	70.55	OK	17650	2026-09-22 16:44	69.38	OK
17651	2026-09-22 16:45	71.90	OK	17652	2026-09-22 16:46	72.67	OK
17653	2026-09-22 16:47	73.20	OK	17654	2026-09-22 16:48	71.77	OK
17655	2026-09-22 16:49	70.69	OK	17656	2026-09-22 16:50	70.14	OK
1765	2026-09-22 16:51	73.49	OK	1765	2026-09-22 16:52	72.86	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
17659	2026-09-22 16:53	72.45	OK	17660	2026-09-22 16:54	73.27	OK
17661	2026-09-22 16:55	69.51	OK	17662	2026-09-22 16:56	71.81	OK
17663	2026-09-22 16:57	71.86	OK	17664	2026-09-22 16:58	72.29	OK
17665	2026-09-22 16:59	71.70	OK	17666	2026-09-22 17:00	71.08	OK
17667	2026-09-22 17:01	71.22	OK	17668	2026-09-22 17:02	72.23	OK
17669	2026-09-22 17:03	73.11	OK	17670	2026-09-22 17:04	72.84	OK
17671	2026-09-22 17:05	70.84	OK	17672	2026-09-22 17:06	73.07	OK
17673	2026-09-22 17:07	72.73	OK	17674	2026-09-22 17:08	72.87	OK
17675	2026-09-22 17:09	73.61	OK	17676	2026-09-22 17:10	74.51	OK
17677	2026-09-22 17:11	71.74	OK	17678	2026-09-22 17:12	70.42	OK
17679	2026-09-22 17:13	71.60	OK	17680	2026-09-22 17:14	71.96	OK
17681	2026-09-22 17:15	71.72	OK	17682	2026-09-22 17:16	74.93	OK
17683	2026-09-22 17:17	70.75	OK	17684	2026-09-22 17:18	74.10	OK
17685	2026-09-22 17:19	72.83	OK	17686	2026-09-22 17:20	71.67	OK
17687	2026-09-22 17:21	73.07	OK	17688	2026-09-22 17:22	71.36	OK
17689	2026-09-22 17:23	70.34	OK	17690	2026-09-22 17:24	73.96	OK
17691	2026-09-22 17:25	70.93	OK	17692	2026-09-22 17:26	73.74	OK
17693	2026-09-22 17:27	72.71	OK	17694	2026-09-22 17:28	72.13	OK
17695	2026-09-22 17:29	72.32	OK	17696	2026-09-22 17:30	71.97	OK
17697	2026-09-22 17:31	70.64	OK	17698	2026-09-22 17:32	72.55	OK
17699	2026-09-22 17:33	70.71	OK	17700	2026-09-22 17:34	72.95	OK
17701	2026-09-22 17:35	72.08	OK	17702	2026-09-22 17:36	71.90	OK
17703	2026-09-22 17:37	70.01	OK	17704	2026-09-22 17:38	71.01	OK
17705	2026-09-22 17:39	72.30	OK	17706	2026-09-22 17:40	73.55	OK
17707	2026-09-22 17:41	72.14	OK	17708	2026-09-22 17:42	74.21	OK
17709	2026-09-22 17:43	73.67	OK	17710	2026-09-22 17:44	73.63	OK
17711	2026-09-22 17:45	71.97	OK	17712	2026-09-22 17:46	74.14	OK
17713	2026-09-22 17:47	72.71	OK	17714	2026-09-22 17:48	73.11	OK
17715	2026-09-22 17:49	73.11	OK	17716	2026-09-22 17:50	72.00	OK
17717	2026-09-22 17:51	72.23	OK	17717	2026-09-22 17:52	72.84	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
17719	2026-09-22 17:53	72.49	OK	17720	2026-09-22 17:54	71.61	OK
17721	2026-09-22 17:55	70.95	OK	17722	2026-09-22 17:56	71.42	OK
17723	2026-09-22 17:57	70.07	OK	17724	2026-09-22 17:58	71.98	OK
17725	2026-09-22 17:59	73.95	OK	17726	2026-09-22 18:00	73.74	OK
17727	2026-09-22 18:01	75.73	OK	17728	2026-09-22 18:02	74.15	OK
17729	2026-09-22 18:03	71.40	OK	17730	2026-09-22 18:04	71.84	OK
17731	2026-09-22 18:05	72.08	OK	17732	2026-09-22 18:06	73.39	OK
17733	2026-09-22 18:07	71.44	OK	17734	2026-09-22 18:08	74.12	OK
17735	2026-09-22 18:09	73.42	OK	17736	2026-09-22 18:10	71.29	OK
17737	2026-09-22 18:11	71.73	OK	17738	2026-09-22 18:12	71.81	OK
17739	2026-09-22 18:13	70.93	OK	17740	2026-09-22 18:14	74.29	OK
17741	2026-09-22 18:15	74.23	OK	17742	2026-09-22 18:16	72.14	OK
17743	2026-09-22 18:17	72.32	OK	17744	2026-09-22 18:18	72.03	OK
17745	2026-09-22 18:19	72.46	OK	17746	2026-09-22 18:20	73.96	OK
17747	2026-09-22 18:21	71.18	OK	17748	2026-09-22 18:22	74.60	OK
17749	2026-09-22 18:23	70.98	OK	17750	2026-09-22 18:24	73.27	OK
17751	2026-09-22 18:25	74.07	OK	17752	2026-09-22 18:26	74.98	OK
17753	2026-09-22 18:27	75.88	OK	17754	2026-09-22 18:28	74.74	OK
17755	2026-09-22 18:29	73.87	OK	17756	2026-09-22 18:30	72.13	OK
17757	2026-09-22 18:31	72.13	OK	17758	2026-09-22 18:32	72.73	OK
17759	2026-09-22 18:33	75.29	OK	17760	2026-09-22 18:34	72.92	OK
17761	2026-09-22 18:35	75.82	OK	17762	2026-09-22 18:36	71.79	OK
17763	2026-09-22 18:37	72.12	OK	17764	2026-09-22 18:38	75.50	OK
17765	2026-09-22 18:39	72.75	OK	17766	2026-09-22 18:40	73.97	OK
17767	2026-09-22 18:41	74.31	OK	17768	2026-09-22 18:42	72.57	OK
17769	2026-09-22 18:43	74.14	OK	17770	2026-09-22 18:44	75.57	OK
17771	2026-09-22 18:45	75.25	OK	17772	2026-09-22 18:46	72.91	OK
17773	2026-09-22 18:47	74.74	OK	17774	2026-09-22 18:48	72.43	OK
17775	2026-09-22 18:49	76.11	OK	17776	2026-09-22 18:50	74.75	OK
17777	2026-09-22 18:51	74.06	OK	17777	2026-09-22 18:52	75.52	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
17779	2026-09-22 18:53	74.73	OK	17780	2026-09-22 18:54	75.36	OK
17781	2026-09-22 18:55	71.91	OK	17782	2026-09-22 18:56	73.97	OK
17783	2026-09-22 18:57	74.40	OK	17784	2026-09-22 18:58	74.44	OK
17785	2026-09-22 18:59	76.30	OK	17786	2026-09-22 19:00	75.78	OK
17787	2026-09-22 19:01	76.05	OK	17788	2026-09-22 19:02	73.68	OK
17789	2026-09-22 19:03	73.87	OK	17790	2026-09-22 19:04	75.47	OK
17791	2026-09-22 19:05	73.92	OK	17792	2026-09-22 19:06	72.54	OK
17793	2026-09-22 19:07	72.18	OK	17794	2026-09-22 19:08	72.67	OK
17795	2026-09-22 19:09	75.54	OK	17796	2026-09-22 19:10	74.64	OK
17797	2026-09-22 19:11	75.52	OK	17798	2026-09-22 19:12	76.35	OK
17799	2026-09-22 19:13	75.58	OK	17800	2026-09-22 19:14	75.05	OK
17801	2026-09-22 19:15	77.25	OK	17802	2026-09-22 19:16	77.14	OK
17803	2026-09-22 19:17	74.32	OK	17804	2026-09-22 19:18	74.04	OK
17805	2026-09-22 19:19	77.69	OK	17806	2026-09-22 19:20	73.94	OK
17807	2026-09-22 19:21	72.23	OK	17808	2026-09-22 19:22	73.97	OK
17809	2026-09-22 19:23	73.62	OK	17810	2026-09-22 19:24	75.04	OK
17811	2026-09-22 19:25	73.23	OK	17812	2026-09-22 19:26	75.72	OK
17813	2026-09-22 19:27	75.25	OK	17814	2026-09-22 19:28	74.50	OK
17815	2026-09-22 19:29	77.78	OK	17816	2026-09-22 19:30	75.63	OK
17817	2026-09-22 19:31	76.29	OK	17818	2026-09-22 19:32	74.99	OK
17819	2026-09-22 19:33	74.69	OK	17820	2026-09-22 19:34	73.46	OK
17821	2026-09-22 19:35	73.01	OK	17822	2026-09-22 19:36	73.78	OK
17823	2026-09-22 19:37	75.20	OK	17824	2026-09-22 19:38	74.68	OK
17825	2026-09-22 19:39	75.38	OK	17826	2026-09-22 19:40	74.87	OK
17827	2026-09-22 19:41	73.71	OK	17828	2026-09-22 19:42	74.25	OK
17829	2026-09-22 19:43	74.93	OK	17830	2026-09-22 19:44	75.78	OK
17831	2026-09-22 19:45	77.09	OK	17832	2026-09-22 19:46	74.60	OK
17833	2026-09-22 19:47	74.81	OK	17834	2026-09-22 19:48	75.65	OK
17835	2026-09-22 19:49	75.53	OK	17836	2026-09-22 19:50	75.32	OK
1783	2026-09-22 19:51	74.42	OK	1783	2026-09-22 19:52	76.13	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
17839	2026-09-22 19:53	75.30	OK	17840	2026-09-22 19:54	77.04	OK
17841	2026-09-22 19:55	74.34	OK	17842	2026-09-22 19:56	75.95	OK
17843	2026-09-22 19:57	77.76	OK	17844	2026-09-22 19:58	76.11	OK
17845	2026-09-22 19:59	75.46	OK	17846	2026-09-22 20:00	76.05	OK
17847	2026-09-22 20:01	75.83	OK	17848	2026-09-22 20:02	74.73	OK
17849	2026-09-22 20:03	76.20	OK	17850	2026-09-22 20:04	76.75	OK
17851	2026-09-22 20:05	76.02	OK	17852	2026-09-22 20:06	75.25	OK
17853	2026-09-22 20:07	72.20	OK	17854	2026-09-22 20:08	75.94	OK
17855	2026-09-22 20:09	75.30	OK	17856	2026-09-22 20:10	76.04	OK
17857	2026-09-22 20:11	74.51	OK	17858	2026-09-22 20:12	76.04	OK
17859	2026-09-22 20:13	76.09	OK	17860	2026-09-22 20:14	73.48	OK
17861	2026-09-22 20:15	75.41	OK	17862	2026-09-22 20:16	73.92	OK
17863	2026-09-22 20:17	74.42	OK	17864	2026-09-22 20:18	73.92	OK
17865	2026-09-22 20:19	76.81	OK	17866	2026-09-22 20:20	75.09	OK
17867	2026-09-22 20:21	75.32	OK	17868	2026-09-22 20:22	73.66	OK
17869	2026-09-22 20:23	76.02	OK	17870	2026-09-22 20:24	76.61	OK
17871	2026-09-22 20:25	73.11	OK	17872	2026-09-22 20:26	75.36	OK
17873	2026-09-22 20:27	75.57	OK	17874	2026-09-22 20:28	74.27	OK
17875	2026-09-22 20:29	73.96	OK	17876	2026-09-22 20:30	75.75	OK
17877	2026-09-22 20:31	74.93	OK	17878	2026-09-22 20:32	76.28	OK
17879	2026-09-22 20:33	78.16	OK	17880	2026-09-22 20:34	77.05	OK
17881	2026-09-22 20:35	75.82	OK	17882	2026-09-22 20:36	75.18	OK
17883	2026-09-22 20:37	75.53	OK	17884	2026-09-22 20:38	77.21	OK
17885	2026-09-22 20:39	77.93	OK	17886	2026-09-22 20:40	73.65	OK
17887	2026-09-22 20:41	74.68	OK	17888	2026-09-22 20:42	77.81	OK
17889	2026-09-22 20:43	76.85	OK	17890	2026-09-22 20:44	78.31	OK
17891	2026-09-22 20:45	75.59	OK	17892	2026-09-22 20:46	79.40	OK
17893	2026-09-22 20:47	77.42	OK	17894	2026-09-22 20:48	75.61	OK
17895	2026-09-22 20:49	77.72	OK	17896	2026-09-22 20:50	76.21	OK
1789	2026-09-22 20:51	76.37	OK	1789	2026-09-22 20:52	74.05	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
17899	2026-09-22 20:53	75.04	OK	17900	2026-09-22 20:54	75.07	OK
17901	2026-09-22 20:55	75.44	OK	17902	2026-09-22 20:56	75.98	OK
17903	2026-09-22 20:57	77.59	OK	17904	2026-09-22 20:58	75.83	OK
17905	2026-09-22 20:59	76.41	OK	17906	2026-09-22 21:00	76.30	OK
17907	2026-09-22 21:01	78.83	OK	17908	2026-09-22 21:02	74.76	OK
17909	2026-09-22 21:03	77.16	OK	17910	2026-09-22 21:04	78.36	OK
17911	2026-09-22 21:05	75.45	OK	17912	2026-09-22 21:06	75.91	OK
17913	2026-09-22 21:07	77.68	OK	17914	2026-09-22 21:08	76.32	OK
17915	2026-09-22 21:09	79.01	OK	17916	2026-09-22 21:10	74.90	OK
17917	2026-09-22 21:11	78.04	OK	17918	2026-09-22 21:12	77.50	OK
17919	2026-09-22 21:13	78.65	OK	17920	2026-09-22 21:14	75.14	OK
17921	2026-09-22 21:15	78.44	OK	17922	2026-09-22 21:16	74.45	OK
17923	2026-09-22 21:17	80.00	OK	17924	2026-09-22 21:18	76.30	OK
17925	2026-09-22 21:19	77.98	OK	17926	2026-09-22 21:20	76.24	OK
17927	2026-09-22 21:21	79.33	OK	17928	2026-09-22 21:22	79.70	OK
17929	2026-09-22 21:23	75.34	OK	17930	2026-09-22 21:24	74.88	OK
17931	2026-09-22 21:25	78.42	OK	17932	2026-09-22 21:26	76.35	OK
17933	2026-09-22 21:27	77.51	OK	17934	2026-09-22 21:28	75.51	OK
17935	2026-09-22 21:29	77.65	OK	17936	2026-09-22 21:30	79.05	OK
17937	2026-09-22 21:31	77.47	OK	17938	2026-09-22 21:32	78.99	OK
17939	2026-09-22 21:33	76.31	OK	17940	2026-09-22 21:34	77.18	OK
17941	2026-09-22 21:35	77.11	OK	17942	2026-09-22 21:36	78.23	OK
17943	2026-09-22 21:37	78.31	OK	17944	2026-09-22 21:38	75.19	OK
17945	2026-09-22 21:39	77.33	OK	17946	2026-09-22 21:40	78.07	OK
17947	2026-09-22 21:41	78.86	OK	17948	2026-09-22 21:42	78.27	OK
17949	2026-09-22 21:43	78.82	OK	17950	2026-09-22 21:44	81.24	OK
17951	2026-09-22 21:45	78.33	OK	17952	2026-09-22 21:46	75.67	OK
17953	2026-09-22 21:47	78.24	OK	17954	2026-09-22 21:48	77.73	OK
17955	2026-09-22 21:49	79.17	OK	17956	2026-09-22 21:50	77.49	OK
1795	2026-09-22 21:51	79.01	OK	1795	2026-09-22 21:52	77.27	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
17959	2026-09-22 21:53	79.15	OK	17960	2026-09-22 21:54	75.41	OK
17961	2026-09-22 21:55	76.74	OK	17962	2026-09-22 21:56	76.06	OK
17963	2026-09-22 21:57	79.07	OK	17964	2026-09-22 21:58	76.27	OK
17965	2026-09-22 21:59	78.71	OK	17966	2026-09-22 22:00	77.31	OK
17967	2026-09-22 22:01	80.02	OK	17968	2026-09-22 22:02	77.32	OK
17969	2026-09-22 22:03	77.52	OK	17970	2026-09-22 22:04	78.02	OK
17971	2026-09-22 22:05	78.37	OK	17972	2026-09-22 22:06	75.77	OK
17973	2026-09-22 22:07	77.56	OK	17974	2026-09-22 22:08	78.74	OK
17975	2026-09-22 22:09	78.99	OK	17976	2026-09-22 22:10	78.55	OK
17977	2026-09-22 22:11	79.25	OK	17978	2026-09-22 22:12	76.73	OK
17979	2026-09-22 22:13	76.36	OK	17980	2026-09-22 22:14	78.96	OK
17981	2026-09-22 22:15	78.16	OK	17982	2026-09-22 22:16	79.91	OK
17983	2026-09-22 22:17	80.57	OK	17984	2026-09-22 22:18	77.39	OK
17985	2026-09-22 22:19	80.30	OK	17986	2026-09-22 22:20	78.61	OK
17987	2026-09-22 22:21	78.10	OK	17988	2026-09-22 22:22	77.86	OK
17989	2026-09-22 22:23	77.82	OK	17990	2026-09-22 22:24	77.42	OK
17991	2026-09-22 22:25	79.04	OK	17992	2026-09-22 22:26	79.88	OK
17993	2026-09-22 22:27	78.19	OK	17994	2026-09-22 22:28	81.30	OK
17995	2026-09-22 22:29	79.10	OK	17996	2026-09-22 22:30	76.18	OK
17997	2026-09-22 22:31	78.48	OK	17998	2026-09-22 22:32	79.14	OK
17999	2026-09-22 22:33	78.88	OK	18000	2026-09-22 22:34	76.34	OK
18001	2026-09-22 22:35	77.88	OK	18002	2026-09-22 22:36	79.50	OK
18003	2026-09-22 22:37	78.31	OK	18004	2026-09-22 22:38	78.17	OK
18005	2026-09-22 22:39	78.06	OK	18006	2026-09-22 22:40	78.29	OK
18007	2026-09-22 22:41	78.07	OK	18008	2026-09-22 22:42	78.93	OK
18009	2026-09-22 22:43	78.41	OK	18010	2026-09-22 22:44	77.88	OK
18011	2026-09-22 22:45	78.54	OK	18012	2026-09-22 22:46	80.38	OK
18013	2026-09-22 22:47	80.12	OK	18014	2026-09-22 22:48	78.27	OK
18015	2026-09-22 22:49	79.73	OK	18016	2026-09-22 22:50	80.32	OK
1801	2026-09-22 22:51	79.62	OK	1801	2026-09-22 22:52	78.79	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
18019	2026-09-22 22:53	79.74	OK	18020	2026-09-22 22:54	79.34	OK
18021	2026-09-22 22:55	80.48	OK	18022	2026-09-22 22:56	81.36	OK
18023	2026-09-22 22:57	78.26	OK	18024	2026-09-22 22:58	81.96	OK
18025	2026-09-22 22:59	77.40	OK	18026	2026-09-22 23:00	80.08	OK
18027	2026-09-22 23:01	81.29	OK	18028	2026-09-22 23:02	80.82	OK
18029	2026-09-22 23:03	79.65	OK	18030	2026-09-22 23:04	78.76	OK
18031	2026-09-22 23:05	78.97	OK	18032	2026-09-22 23:06	78.50	OK
18033	2026-09-22 23:07	81.69	OK	18034	2026-09-22 23:08	80.65	OK
18035	2026-09-22 23:09	77.45	OK	18036	2026-09-22 23:10	78.40	OK
18037	2026-09-22 23:11	78.21	OK	18038	2026-09-22 23:12	79.02	OK
18039	2026-09-22 23:13	78.82	OK	18040	2026-09-22 23:14	79.98	OK
18041	2026-09-22 23:15	79.77	OK	18042	2026-09-22 23:16	80.07	OK
18043	2026-09-22 23:17	79.00	OK	18044	2026-09-22 23:18	78.65	OK
18045	2026-09-22 23:19	81.52	OK	18046	2026-09-22 23:20	80.16	OK
18047	2026-09-22 23:21	80.92	OK	18048	2026-09-22 23:22	80.87	OK
18049	2026-09-22 23:23	78.77	OK	18050	2026-09-22 23:24	80.08	OK
18051	2026-09-22 23:25	83.17	OK	18052	2026-09-22 23:26	79.05	OK
18053	2026-09-22 23:27	79.60	OK	18054	2026-09-22 23:28	80.81	OK
18055	2026-09-22 23:29	81.23	OK	18056	2026-09-22 23:30	78.23	OK
18057	2026-09-22 23:31	78.29	OK	18058	2026-09-22 23:32	79.82	OK
18059	2026-09-22 23:33	79.63	OK	18060	2026-09-22 23:34	81.18	OK
18061	2026-09-22 23:35	79.26	OK	18062	2026-09-22 23:36	81.56	OK
18063	2026-09-22 23:37	78.39	OK	18064	2026-09-22 23:38	78.66	OK
18065	2026-09-22 23:39	81.77	OK	18066	2026-09-22 23:40	80.34	OK
18067	2026-09-22 23:41	82.58	OK	18068	2026-09-22 23:42	80.43	OK
18069	2026-09-22 23:43	80.23	OK	18070	2026-09-22 23:44	79.98	OK
18071	2026-09-22 23:45	80.68	OK	18072	2026-09-22 23:46	80.46	OK
18073	2026-09-22 23:47	81.95	OK	18074	2026-09-22 23:48	80.50	OK
18075	2026-09-22 23:49	78.76	OK	18076	2026-09-22 23:50	80.89	OK
1807	2026-09-22 23:51	81.10	OK	1807	2026-09-22 23:52	81.53	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
18079	2026-09-22 23:53	81.16	OK	18080	2026-09-22 23:54	79.59	OK
18081	2026-09-22 23:55	82.05	OK	18082	2026-09-22 23:56	80.73	OK
18083	2026-09-22 23:57	82.84	OK	18084	2026-09-22 23:58	82.17	OK
18085	2026-09-22 23:59	79.26	OK	18086	2026-09-23 00:00	78.39	OK
18087	2026-09-23 00:01	82.48	OK	18088	2026-09-23 00:02	79.39	OK
18089	2026-09-23 00:03	80.94	OK	18090	2026-09-23 00:04	78.41	OK
18091	2026-09-23 00:05	78.47	OK	18092	2026-09-23 00:06	80.10	OK
18093	2026-09-23 00:07	79.36	OK	18094	2026-09-23 00:08	79.79	OK
18095	2026-09-23 00:09	81.53	OK	18096	2026-09-23 00:10	79.32	OK
18097	2026-09-23 00:11	78.88	OK	18098	2026-09-23 00:12	81.31	OK
18099	2026-09-23 00:13	81.62	OK	18100	2026-09-23 00:14	78.57	OK
18101	2026-09-23 00:15	81.22	OK	18102	2026-09-23 00:16	78.65	OK
18103	2026-09-23 00:17	81.32	OK	18104	2026-09-23 00:18	81.44	OK
18105	2026-09-23 00:19	79.20	OK	18106	2026-09-23 00:20	80.95	OK
18107	2026-09-23 00:21	81.07	OK	18108	2026-09-23 00:22	82.22	OK
18109	2026-09-23 00:23	81.93	OK	18110	2026-09-23 00:24	80.09	OK
18111	2026-09-23 00:25	81.76	OK	18112	2026-09-23 00:26	81.03	OK
18113	2026-09-23 00:27	81.21	OK	18114	2026-09-23 00:28	82.08	OK
18115	2026-09-23 00:29	78.11	OK	18116	2026-09-23 00:30	81.02	OK
18117	2026-09-23 00:31	81.45	OK	18118	2026-09-23 00:32	79.24	OK
18119	2026-09-23 00:33	80.70	OK	18120	2026-09-23 00:34	79.01	OK
18121	2026-09-23 00:35	80.11	OK	18122	2026-09-23 00:36	81.58	OK
18123	2026-09-23 00:37	82.76	OK	18124	2026-09-23 00:38	82.17	OK
18125	2026-09-23 00:39	80.79	OK	18126	2026-09-23 00:40	80.12	OK
18127	2026-09-23 00:41	80.99	OK	18128	2026-09-23 00:42	81.64	OK
18129	2026-09-23 00:43	80.03	OK	18130	2026-09-23 00:44	79.51	OK
18131	2026-09-23 00:45	80.95	OK	18132	2026-09-23 00:46	82.73	OK
18133	2026-09-23 00:47	81.35	OK	18134	2026-09-23 00:48	79.91	OK
18135	2026-09-23 00:49	81.07	OK	18136	2026-09-23 00:50	80.08	OK
1813	2026-09-23 00:51	81.88	OK	1813	2026-09-23 00:52	82.44	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
18139	2026-09-23 00:53	82.99	OK	18140	2026-09-23 00:54	80.04	OK
18141	2026-09-23 00:55	82.45	OK	18142	2026-09-23 00:56	80.17	OK
18143	2026-09-23 00:57	80.60	OK	18144	2026-09-23 00:58	80.35	OK
18145	2026-09-23 00:59	79.96	OK	18146	2026-09-23 01:00	81.64	OK
18147	2026-09-23 01:01	83.05	OK	18148	2026-09-23 01:02	81.10	OK
18149	2026-09-23 01:03	80.97	OK	18150	2026-09-23 01:04	84.56	OK
18151	2026-09-23 01:05	82.61	OK	18152	2026-09-23 01:06	80.68	OK
18153	2026-09-23 01:07	80.35	OK	18154	2026-09-23 01:08	83.50	OK
18155	2026-09-23 01:09	79.62	OK	18156	2026-09-23 01:10	83.37	OK
18157	2026-09-23 01:11	83.03	OK	18158	2026-09-23 01:12	80.27	OK
18159	2026-09-23 01:13	84.65	OK	18160	2026-09-23 01:14	79.50	OK
18161	2026-09-23 01:15	80.04	OK	18162	2026-09-23 01:16	82.20	OK
18163	2026-09-23 01:17	81.34	OK	18164	2026-09-23 01:18	81.34	OK
18165	2026-09-23 01:19	80.38	OK	18166	2026-09-23 01:20	79.70	OK
18167	2026-09-23 01:21	82.76	OK	18168	2026-09-23 01:22	82.69	OK
18169	2026-09-23 01:23	79.18	OK	18170	2026-09-23 01:24	81.99	OK
18171	2026-09-23 01:25	81.44	OK	18172	2026-09-23 01:26	81.25	OK
18173	2026-09-23 01:27	80.69	OK	18174	2026-09-23 01:28	80.41	OK
18175	2026-09-23 01:29	81.81	OK	18176	2026-09-23 01:30	83.34	OK
18177	2026-09-23 01:31	80.24	OK	18178	2026-09-23 01:32	81.48	OK
18179	2026-09-23 01:33	80.92	OK	18180	2026-09-23 01:34	80.61	OK
18181	2026-09-23 01:35	80.18	OK	18182	2026-09-23 01:36	81.58	OK
18183	2026-09-23 01:37	82.55	OK	18184	2026-09-23 01:38	79.50	OK
18185	2026-09-23 01:39	80.64	OK	18186	2026-09-23 01:40	81.81	OK
18187	2026-09-23 01:41	82.01	OK	18188	2026-09-23 01:42	79.97	OK
18189	2026-09-23 01:43	81.93	OK	18190	2026-09-23 01:44	80.25	OK
18191	2026-09-23 01:45	81.11	OK	18192	2026-09-23 01:46	79.31	OK
18193	2026-09-23 01:47	78.74	OK	18194	2026-09-23 01:48	81.78	OK
18195	2026-09-23 01:49	80.42	OK	18196	2026-09-23 01:50	82.06	OK
1819	2026-09-23 01:51	80.18	OK	1819	2026-09-23 01:52	81.95	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
18199	2026-09-23 01:53	81.06	OK	18200	2026-09-23 01:54	79.55	OK
18201	2026-09-23 01:55	81.41	OK	18202	2026-09-23 01:56	81.88	OK
18203	2026-09-23 01:57	81.38	OK	18204	2026-09-23 01:58	84.83	OK
18205	2026-09-23 01:59	83.02	OK	18206	2026-09-23 02:00	81.98	OK
18207	2026-09-23 02:01	83.02	OK	18208	2026-09-23 02:02	82.11	OK
18209	2026-09-23 02:03	83.58	OK	18210	2026-09-23 02:04	83.38	OK
18211	2026-09-23 02:05	81.69	OK	18212	2026-09-23 02:06	80.87	OK
18213	2026-09-23 02:07	83.63	OK	18214	2026-09-23 02:08	80.65	OK
18215	2026-09-23 02:09	80.98	OK	18216	2026-09-23 02:10	80.38	OK
18217	2026-09-23 02:11	82.64	OK	18218	2026-09-23 02:12	82.01	OK
18219	2026-09-23 02:13	81.62	OK	18220	2026-09-23 02:14	80.78	OK
18221	2026-09-23 02:15	80.93	OK	18222	2026-09-23 02:16	83.01	OK
18223	2026-09-23 02:17	83.18	OK	18224	2026-09-23 02:18	84.89	OK
18225	2026-09-23 02:19	84.74	OK	18226	2026-09-23 02:20	81.69	OK
18227	2026-09-23 02:21	82.28	OK	18228	2026-09-23 02:22	82.72	OK
18229	2026-09-23 02:23	79.36	OK	18230	2026-09-23 02:24	81.37	OK
18231	2026-09-23 02:25	83.21	OK	18232	2026-09-23 02:26	82.77	OK
18233	2026-09-23 02:27	81.19	OK	18234	2026-09-23 02:28	81.77	OK
18235	2026-09-23 02:29	81.13	OK	18236	2026-09-23 02:30	81.29	OK
18237	2026-09-23 02:31	79.30	OK	18238	2026-09-23 02:32	82.60	OK
18239	2026-09-23 02:33	81.78	OK	18240	2026-09-23 02:34	80.52	OK
18241	2026-09-23 02:35	81.89	OK	18242	2026-09-23 02:36	83.66	OK
18243	2026-09-23 02:37	83.23	OK	18244	2026-09-23 02:38	80.23	OK
18245	2026-09-23 02:39	80.45	OK	18246	2026-09-23 02:40	82.27	OK
18247	2026-09-23 02:41	82.17	OK	18248	2026-09-23 02:42	83.96	OK
18249	2026-09-23 02:43	81.56	OK	18250	2026-09-23 02:44	81.95	OK
18251	2026-09-23 02:45	80.54	OK	18252	2026-09-23 02:46	79.55	OK
18253	2026-09-23 02:47	81.86	OK	18254	2026-09-23 02:48	81.13	OK
18255	2026-09-23 02:49	84.85	OK	18256	2026-09-23 02:50	81.95	OK
1825	2026-09-23 02:51	80.78	OK	1825	2026-09-23 02:52	82.46	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
18259	2026-09-23 02:53	83.38	OK	18260	2026-09-23 02:54	81.47	OK
18261	2026-09-23 02:55	82.55	OK	18262	2026-09-23 02:56	83.93	OK
18263	2026-09-23 02:57	81.69	OK	18264	2026-09-23 02:58	83.69	OK
18265	2026-09-23 02:59	79.98	OK	18266	2026-09-23 03:00	80.66	OK
18267	2026-09-23 03:01	81.34	OK	18268	2026-09-23 03:02	82.85	OK
18269	2026-09-23 03:03	81.95	OK	18270	2026-09-23 03:04	82.70	OK
18271	2026-09-23 03:05	82.71	OK	18272	2026-09-23 03:06	79.53	OK
18273	2026-09-23 03:07	80.09	OK	18274	2026-09-23 03:08	81.91	OK
18275	2026-09-23 03:09	80.62	OK	18276	2026-09-23 03:10	82.93	OK
18277	2026-09-23 03:11	81.77	OK	18278	2026-09-23 03:12	82.36	OK
18279	2026-09-23 03:13	80.74	OK	18280	2026-09-23 03:14	81.89	OK
18281	2026-09-23 03:15	82.63	OK	18282	2026-09-23 03:16	79.92	OK
18283	2026-09-23 03:17	80.32	OK	18284	2026-09-23 03:18	79.62	OK
18285	2026-09-23 03:19	82.23	OK	18286	2026-09-23 03:20	81.34	OK
18287	2026-09-23 03:21	79.53	OK	18288	2026-09-23 03:22	81.82	OK
18289	2026-09-23 03:23	81.04	OK	18290	2026-09-23 03:24	81.72	OK
18291	2026-09-23 03:25	79.15	OK	18292	2026-09-23 03:26	82.33	OK
18293	2026-09-23 03:27	83.60	OK	18294	2026-09-23 03:28	79.94	OK
18295	2026-09-23 03:29	82.84	OK	18296	2026-09-23 03:30	81.57	OK
18297	2026-09-23 03:31	82.24	OK	18298	2026-09-23 03:32	82.15	OK
18299	2026-09-23 03:33	82.28	OK	18300	2026-09-23 03:34	80.73	OK
18301	2026-09-23 03:35	81.80	OK	18302	2026-09-23 03:36	81.46	OK
18303	2026-09-23 03:37	80.61	OK	18304	2026-09-23 03:38	81.23	OK
18305	2026-09-23 03:39	81.05	OK	18306	2026-09-23 03:40	81.09	OK
18307	2026-09-23 03:41	82.28	OK	18308	2026-09-23 03:42	81.28	OK
18309	2026-09-23 03:43	79.74	OK	18310	2026-09-23 03:44	81.93	OK
18311	2026-09-23 03:45	81.44	OK	18312	2026-09-23 03:46	81.41	OK
18313	2026-09-23 03:47	80.43	OK	18314	2026-09-23 03:48	81.69	OK
18315	2026-09-23 03:49	80.16	OK	18316	2026-09-23 03:50	82.70	OK
1831	2026-09-23 03:51	82.89	OK	1831	2026-09-23 03:52	81.49	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
18319	2026-09-23 03:53	78.35	OK	18320	2026-09-23 03:54	79.93	OK
18321	2026-09-23 03:55	81.69	OK	18322	2026-09-23 03:56	80.35	OK
18323	2026-09-23 03:57	83.62	OK	18324	2026-09-23 03:58	80.99	OK
18325	2026-09-23 03:59	81.22	OK	18326	2026-09-23 04:00	80.13	OK
18327	2026-09-23 04:01	81.39	OK	18328	2026-09-23 04:02	82.21	OK
18329	2026-09-23 04:03	82.12	OK	18330	2026-09-23 04:04	83.51	OK
18331	2026-09-23 04:05	80.45	OK	18332	2026-09-23 04:06	81.80	OK
18333	2026-09-23 04:07	83.60	OK	18334	2026-09-23 04:08	82.10	OK
18335	2026-09-23 04:09	82.05	OK	18336	2026-09-23 04:10	80.31	OK
18337	2026-09-23 04:11	83.14	OK	18338	2026-09-23 04:12	81.70	OK
18339	2026-09-23 04:13	81.60	OK	18340	2026-09-23 04:14	79.72	OK
18341	2026-09-23 04:15	82.31	OK	18342	2026-09-23 04:16	79.71	OK
18343	2026-09-23 04:17	83.32	OK	18344	2026-09-23 04:18	80.97	OK
18345	2026-09-23 04:19	83.27	OK	18346	2026-09-23 04:20	79.55	OK
18347	2026-09-23 04:21	81.04	OK	18348	2026-09-23 04:22	83.91	OK
18349	2026-09-23 04:23	81.03	OK	18350	2026-09-23 04:24	81.58	OK
18351	2026-09-23 04:25	80.52	OK	18352	2026-09-23 04:26	84.02	OK
18353	2026-09-23 04:27	78.29	OK	18354	2026-09-23 04:28	81.63	OK
18355	2026-09-23 04:29	82.13	OK	18356	2026-09-23 04:30	79.94	OK
18357	2026-09-23 04:31	83.71	OK	18358	2026-09-23 04:32	81.83	OK
18359	2026-09-23 04:33	80.98	OK	18360	2026-09-23 04:34	82.91	OK
18361	2026-09-23 04:35	83.04	OK	18362	2026-09-23 04:36	79.41	OK
18363	2026-09-23 04:37	82.93	OK	18364	2026-09-23 04:38	82.01	OK
18365	2026-09-23 04:39	82.70	OK	18366	2026-09-23 04:40	79.57	OK
18367	2026-09-23 04:41	80.92	OK	18368	2026-09-23 04:42	80.13	OK
18369	2026-09-23 04:43	82.52	OK	18370	2026-09-23 04:44	79.11	OK
18371	2026-09-23 04:45	79.07	OK	18372	2026-09-23 04:46	81.56	OK
18373	2026-09-23 04:47	80.07	OK	18374	2026-09-23 04:48	83.43	OK
18375	2026-09-23 04:49	79.48	OK	18376	2026-09-23 04:50	80.05	OK
1837	2026-09-23 04:51	83.17	OK	1837	2026-09-23 04:52	78.93	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
18379	2026-09-23 04:53	80.97	OK	18380	2026-09-23 04:54	77.98	OK
18381	2026-09-23 04:55	80.50	OK	18382	2026-09-23 04:56	83.37	OK
18383	2026-09-23 04:57	79.60	OK	18384	2026-09-23 04:58	81.37	OK
18385	2026-09-23 04:59	81.76	OK	18386	2026-09-23 05:00	80.96	OK
18387	2026-09-23 05:01	80.73	OK	18388	2026-09-23 05:02	80.21	OK
18389	2026-09-23 05:03	82.44	OK	18390	2026-09-23 05:04	82.25	OK
18391	2026-09-23 05:05	81.07	OK	18392	2026-09-23 05:06	78.45	OK
18393	2026-09-23 05:07	82.53	OK	18394	2026-09-23 05:08	78.19	OK
18395	2026-09-23 05:09	79.91	OK	18396	2026-09-23 05:10	78.21	OK
18397	2026-09-23 05:11	81.59	OK	18398	2026-09-23 05:12	81.81	OK
18399	2026-09-23 05:13	80.30	OK	18400	2026-09-23 05:14	79.68	OK
18401	2026-09-23 05:15	79.61	OK	18402	2026-09-23 05:16	79.79	OK
18403	2026-09-23 05:17	79.40	OK	18404	2026-09-23 05:18	80.86	OK
18405	2026-09-23 05:19	80.21	OK	18406	2026-09-23 05:20	81.57	OK
18407	2026-09-23 05:21	82.25	OK	18408	2026-09-23 05:22	81.79	OK
18409	2026-09-23 05:23	81.23	OK	18410	2026-09-23 05:24	80.49	OK
18411	2026-09-23 05:25	79.40	OK	18412	2026-09-23 05:26	80.80	OK
18413	2026-09-23 05:27	81.24	OK	18414	2026-09-23 05:28	81.95	OK
18415	2026-09-23 05:29	80.90	OK	18416	2026-09-23 05:30	82.12	OK
18417	2026-09-23 05:31	80.15	OK	18418	2026-09-23 05:32	81.08	OK
18419	2026-09-23 05:33	81.13	OK	18420	2026-09-23 05:34	79.61	OK
18421	2026-09-23 05:35	80.62	OK	18422	2026-09-23 05:36	80.21	OK
18423	2026-09-23 05:37	80.54	OK	18424	2026-09-23 05:38	82.10	OK
18425	2026-09-23 05:39	81.07	OK	18426	2026-09-23 05:40	82.61	OK
18427	2026-09-23 05:41	80.36	OK	18428	2026-09-23 05:42	80.98	OK
18429	2026-09-23 05:43	81.84	OK	18430	2026-09-23 05:44	81.02	OK
18431	2026-09-23 05:45	79.47	OK	18432	2026-09-23 05:46	80.56	OK
18433	2026-09-23 05:47	78.63	OK	18434	2026-09-23 05:48	80.49	OK
18435	2026-09-23 05:49	80.03	OK	18436	2026-09-23 05:50	78.45	OK
1843	2026-09-23 05:51	81.79	OK	1843	2026-09-23 05:52	81.11	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
18439	2026-09-23 05:53	79.34	OK	18440	2026-09-23 05:54	78.95	OK
18441	2026-09-23 05:55	81.26	OK	18442	2026-09-23 05:56	80.46	OK
18443	2026-09-23 05:57	81.16	OK	18444	2026-09-23 05:58	78.85	OK
18445	2026-09-23 05:59	80.72	OK	18446	2026-09-23 06:00	80.78	OK
18447	2026-09-23 06:01	80.22	OK	18448	2026-09-23 06:02	81.35	OK
18449	2026-09-23 06:03	81.78	OK	18450	2026-09-23 06:04	81.23	OK
18451	2026-09-23 06:05	80.14	OK	18452	2026-09-23 06:06	81.50	OK
18453	2026-09-23 06:07	81.64	OK	18454	2026-09-23 06:08	81.15	OK
18455	2026-09-23 06:09	77.75	OK	18456	2026-09-23 06:10	80.00	OK
18457	2026-09-23 06:11	78.46	OK	18458	2026-09-23 06:12	79.31	OK
18459	2026-09-23 06:13	80.00	OK	18460	2026-09-23 06:14	80.41	OK
18461	2026-09-23 06:15	76.73	OK	18462	2026-09-23 06:16	80.34	OK
18463	2026-09-23 06:17	80.44	OK	18464	2026-09-23 06:18	78.85	OK
18465	2026-09-23 06:19	80.43	OK	18466	2026-09-23 06:20	80.04	OK
18467	2026-09-23 06:21	79.54	OK	18468	2026-09-23 06:22	78.03	OK
18469	2026-09-23 06:23	79.19	OK	18470	2026-09-23 06:24	78.60	OK
18471	2026-09-23 06:25	80.88	OK	18472	2026-09-23 06:26	79.04	OK
18473	2026-09-23 06:27	77.79	OK	18474	2026-09-23 06:28	79.39	OK
18475	2026-09-23 06:29	82.35	OK	18476	2026-09-23 06:30	79.21	OK
18477	2026-09-23 06:31	78.50	OK	18478	2026-09-23 06:32	79.55	OK
18479	2026-09-23 06:33	80.09	OK	18480	2026-09-23 06:34	77.90	OK
18481	2026-09-23 06:35	77.80	OK	18482	2026-09-23 06:36	77.64	OK
18483	2026-09-23 06:37	78.34	OK	18484	2026-09-23 06:38	80.11	OK
18485	2026-09-23 06:39	77.66	OK	18486	2026-09-23 06:40	82.49	OK
18487	2026-09-23 06:41	78.69	OK	18488	2026-09-23 06:42	77.94	OK
18489	2026-09-23 06:43	79.17	OK	18490	2026-09-23 06:44	80.20	OK
18491	2026-09-23 06:45	79.01	OK	18492	2026-09-23 06:46	80.20	OK
18493	2026-09-23 06:47	78.90	OK	18494	2026-09-23 06:48	77.64	OK
18495	2026-09-23 06:49	80.19	OK	18496	2026-09-23 06:50	78.06	OK
1849	2026-09-23 06:51	76.78	OK	1849	2026-09-23 06:52	80.45	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
18499	2026-09-23 06:53	77.08	OK	18500	2026-09-23 06:54	80.24	OK
18501	2026-09-23 06:55	80.28	OK	18502	2026-09-23 06:56	81.37	OK
18503	2026-09-23 06:57	78.17	OK	18504	2026-09-23 06:58	81.36	OK
18505	2026-09-23 06:59	79.92	OK	18506	2026-09-23 07:00	79.50	OK
18507	2026-09-23 07:01	80.16	OK	18508	2026-09-23 07:02	78.82	OK
18509	2026-09-23 07:03	77.58	OK	18510	2026-09-23 07:04	81.18	OK
18511	2026-09-23 07:05	78.53	OK	18512	2026-09-23 07:06	77.04	OK
18513	2026-09-23 07:07	78.88	OK	18514	2026-09-23 07:08	79.22	OK
18515	2026-09-23 07:09	80.09	OK	18516	2026-09-23 07:10	79.90	OK
18517	2026-09-23 07:11	79.89	OK	18518	2026-09-23 07:12	77.67	OK
18519	2026-09-23 07:13	78.96	OK	18520	2026-09-23 07:14	77.58	OK
18521	2026-09-23 07:15	77.54	OK	18522	2026-09-23 07:16	77.39	OK
18523	2026-09-23 07:17	79.34	OK	18524	2026-09-23 07:18	80.96	OK
18525	2026-09-23 07:19	76.75	OK	18526	2026-09-23 07:20	79.33	OK
18527	2026-09-23 07:21	77.00	OK	18528	2026-09-23 07:22	78.93	OK
18529	2026-09-23 07:23	75.50	OK	18530	2026-09-23 07:24	77.04	OK
18531	2026-09-23 07:25	77.71	OK	18532	2026-09-23 07:26	77.33	OK
18533	2026-09-23 07:27	76.22	OK	18534	2026-09-23 07:28	79.09	OK
18535	2026-09-23 07:29	77.72	OK	18536	2026-09-23 07:30	79.63	OK
18537	2026-09-23 07:31	76.32	OK	18538	2026-09-23 07:32	79.53	OK
18539	2026-09-23 07:33	76.78	OK	18540	2026-09-23 07:34	78.85	OK
18541	2026-09-23 07:35	79.75	OK	18542	2026-09-23 07:36	78.36	OK
18543	2026-09-23 07:37	78.27	OK	18544	2026-09-23 07:38	77.40	OK
18545	2026-09-23 07:39	77.71	OK	18546	2026-09-23 07:40	78.89	OK
18547	2026-09-23 07:41	78.96	OK	18548	2026-09-23 07:42	75.92	OK
18549	2026-09-23 07:43	76.17	OK	18550	2026-09-23 07:44	75.85	OK
18551	2026-09-23 07:45	79.55	OK	18552	2026-09-23 07:46	77.03	OK
18553	2026-09-23 07:47	76.56	OK	18554	2026-09-23 07:48	80.02	OK
18555	2026-09-23 07:49	76.67	OK	18556	2026-09-23 07:50	79.08	OK
1855	2026-09-23 07:51	78.47	OK	1855	2026-09-23 07:52	78.06	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
18559	2026-09-23 07:53	78.22	OK	18560	2026-09-23 07:54	76.88	OK
18561	2026-09-23 07:55	76.49	OK	18562	2026-09-23 07:56	80.46	OK
18563	2026-09-23 07:57	77.91	OK	18564	2026-09-23 07:58	77.02	OK
18565	2026-09-23 07:59	78.79	OK	18566	2026-09-23 08:00	77.63	OK
18567	2026-09-23 08:01	79.00	OK	18568	2026-09-23 08:02	77.62	OK
18569	2026-09-23 08:03	76.22	OK	18570	2026-09-23 08:04	77.49	OK
18571	2026-09-23 08:05	77.47	OK	18572	2026-09-23 08:06	77.47	OK
18573	2026-09-23 08:07	76.74	OK	18574	2026-09-23 08:08	77.23	OK
18575	2026-09-23 08:09	75.75	OK	18576	2026-09-23 08:10	79.84	OK
18577	2026-09-23 08:11	79.02	OK	18578	2026-09-23 08:12	78.11	OK
18579	2026-09-23 08:13	75.46	OK	18580	2026-09-23 08:14	76.07	OK
18581	2026-09-23 08:15	76.59	OK	18582	2026-09-23 08:16	78.09	OK
18583	2026-09-23 08:17	77.57	OK	18584	2026-09-23 08:18	76.14	OK
18585	2026-09-23 08:19	76.16	OK	18586	2026-09-23 08:20	77.06	OK
18587	2026-09-23 08:21	76.74	OK	18588	2026-09-23 08:22	76.16	OK
18589	2026-09-23 08:23	77.70	OK	18590	2026-09-23 08:24	77.10	OK
18591	2026-09-23 08:25	76.08	OK	18592	2026-09-23 08:26	75.77	OK
18593	2026-09-23 08:27	77.78	OK	18594	2026-09-23 08:28	75.90	OK
18595	2026-09-23 08:29	77.53	OK	18596	2026-09-23 08:30	75.16	OK
18597	2026-09-23 08:31	78.70	OK	18598	2026-09-23 08:32	77.23	OK
18599	2026-09-23 08:33	75.89	OK	18600	2026-09-23 08:34	77.84	OK
18601	2026-09-23 08:35	78.94	OK	18602	2026-09-23 08:36	77.58	OK
18603	2026-09-23 08:37	75.96	OK	18604	2026-09-23 08:38	77.70	OK
18605	2026-09-23 08:39	75.07	OK	18606	2026-09-23 08:40	77.20	OK
18607	2026-09-23 08:41	77.20	OK	18608	2026-09-23 08:42	77.88	OK
18609	2026-09-23 08:43	75.96	OK	18610	2026-09-23 08:44	73.55	OK
18611	2026-09-23 08:45	76.05	OK	18612	2026-09-23 08:46	75.31	OK
18613	2026-09-23 08:47	77.36	OK	18614	2026-09-23 08:48	75.05	OK
18615	2026-09-23 08:49	77.31	OK	18616	2026-09-23 08:50	77.59	OK
1861	2026-09-23 08:51	75.92	OK	1861	2026-09-23 08:52	77.28	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
18619	2026-09-23 08:53	75.61	OK	18620	2026-09-23 08:54	76.58	OK
18621	2026-09-23 08:55	76.07	OK	18622	2026-09-23 08:56	75.18	OK
18623	2026-09-23 08:57	74.61	OK	18624	2026-09-23 08:58	76.01	OK
18625	2026-09-23 08:59	75.39	OK	18626	2026-09-23 09:00	76.60	OK
18627	2026-09-23 09:01	78.63	OK	18628	2026-09-23 09:02	75.39	OK
18629	2026-09-23 09:03	76.02	OK	18630	2026-09-23 09:04	75.50	OK
18631	2026-09-23 09:05	73.48	OK	18632	2026-09-23 09:06	77.40	OK
18633	2026-09-23 09:07	75.27	OK	18634	2026-09-23 09:08	76.12	OK
18635	2026-09-23 09:09	75.37	OK	18636	2026-09-23 09:10	75.38	OK
18637	2026-09-23 09:11	75.89	OK	18638	2026-09-23 09:12	73.84	OK
18639	2026-09-23 09:13	76.64	OK	18640	2026-09-23 09:14	75.50	OK
18641	2026-09-23 09:15	77.09	OK	18642	2026-09-23 09:16	76.23	OK
18643	2026-09-23 09:17	77.18	OK	18644	2026-09-23 09:18	75.22	OK
18645	2026-09-23 09:19	75.33	OK	18646	2026-09-23 09:20	76.21	OK
18647	2026-09-23 09:21	75.61	OK	18648	2026-09-23 09:22	75.49	OK
18649	2026-09-23 09:23	75.74	OK	18650	2026-09-23 09:24	74.38	OK
18651	2026-09-23 09:25	75.83	OK	18652	2026-09-23 09:26	74.75	OK
18653	2026-09-23 09:27	74.97	OK	18654	2026-09-23 09:28	75.86	OK
18655	2026-09-23 09:29	73.95	OK	18656	2026-09-23 09:30	75.26	OK
18657	2026-09-23 09:31	75.02	OK	18658	2026-09-23 09:32	75.10	OK
18659	2026-09-23 09:33	75.86	OK	18660	2026-09-23 09:34	73.62	OK
18661	2026-09-23 09:35	72.34	OK	18662	2026-09-23 09:36	75.43	OK
18663	2026-09-23 09:37	74.93	OK	18664	2026-09-23 09:38	75.32	OK
18665	2026-09-23 09:39	76.03	OK	18666	2026-09-23 09:40	76.97	OK
18667	2026-09-23 09:41	76.21	OK	18668	2026-09-23 09:42	77.16	OK
18669	2026-09-23 09:43	76.65	OK	18670	2026-09-23 09:44	76.24	OK
18671	2026-09-23 09:45	75.53	OK	18672	2026-09-23 09:46	75.74	OK
18673	2026-09-23 09:47	77.43	OK	18674	2026-09-23 09:48	74.75	OK
18675	2026-09-23 09:49	75.96	OK	18676	2026-09-23 09:50	78.02	OK
1867	2026-09-23 09:51	73.56	OK	1867	2026-09-23 09:52	75.45	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
18679	2026-09-23 09:53	74.09	OK	18680	2026-09-23 09:54	75.17	OK
18681	2026-09-23 09:55	73.97	OK	18682	2026-09-23 09:56	74.28	OK
18683	2026-09-23 09:57	75.44	OK	18684	2026-09-23 09:58	73.89	OK
18685	2026-09-23 09:59	74.49	OK	18686	2026-09-23 10:00	73.38	OK
18687	2026-09-23 10:01	75.95	OK	18688	2026-09-23 10:02	73.92	OK
18689	2026-09-23 10:03	73.28	OK	18690	2026-09-23 10:04	76.93	OK
18691	2026-09-23 10:05	73.99	OK	18692	2026-09-23 10:06	77.30	OK
18693	2026-09-23 10:07	74.81	OK	18694	2026-09-23 10:08	75.19	OK
18695	2026-09-23 10:09	76.32	OK	18696	2026-09-23 10:10	77.12	OK
18697	2026-09-23 10:11	73.30	OK	18698	2026-09-23 10:12	75.96	OK
18699	2026-09-23 10:13	73.71	OK	18700	2026-09-23 10:14	74.35	OK
18701	2026-09-23 10:15	74.14	OK	18702	2026-09-23 10:16	73.77	OK
18703	2026-09-23 10:17	75.78	OK	18704	2026-09-23 10:18	76.50	OK
18705	2026-09-23 10:19	72.87	OK	18706	2026-09-23 10:20	75.16	OK
18707	2026-09-23 10:21	74.16	OK	18708	2026-09-23 10:22	75.35	OK
18709	2026-09-23 10:23	74.91	OK	18710	2026-09-23 10:24	72.75	OK
18711	2026-09-23 10:25	74.69	OK	18712	2026-09-23 10:26	73.08	OK
18713	2026-09-23 10:27	76.90	OK	18714	2026-09-23 10:28	76.17	OK
18715	2026-09-23 10:29	73.03	OK	18716	2026-09-23 10:30	73.59	OK
18717	2026-09-23 10:31	73.08	OK	18718	2026-09-23 10:32	72.50	OK
18719	2026-09-23 10:33	73.22	OK	18720	2026-09-23 10:34	73.63	OK
18721	2026-09-23 10:35	74.27	OK	18722	2026-09-23 10:36	73.29	OK
18723	2026-09-23 10:37	71.20	OK	18724	2026-09-23 10:38	73.19	OK
18725	2026-09-23 10:39	74.73	OK	18726	2026-09-23 10:40	74.13	OK
18727	2026-09-23 10:41	74.26	OK	18728	2026-09-23 10:42	75.49	OK
18729	2026-09-23 10:43	72.72	OK	18730	2026-09-23 10:44	73.33	OK
18731	2026-09-23 10:45	72.91	OK	18732	2026-09-23 10:46	74.33	OK
18733	2026-09-23 10:47	75.57	OK	18734	2026-09-23 10:48	72.06	OK
18735	2026-09-23 10:49	73.62	OK	18736	2026-09-23 10:50	73.56	OK
1873	2026-09-23 10:51	74.21	OK	1873	2026-09-23 10:52	74.70	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
18739	2026-09-23 10:53	72.78	OK	18740	2026-09-23 10:54	74.98	OK
18741	2026-09-23 10:55	73.71	OK	18742	2026-09-23 10:56	75.66	OK
18743	2026-09-23 10:57	73.98	OK	18744	2026-09-23 10:58	72.85	OK
18745	2026-09-23 10:59	73.76	OK	18746	2026-09-23 11:00	73.53	OK
18747	2026-09-23 11:01	74.17	OK	18748	2026-09-23 11:02	74.04	OK
18749	2026-09-23 11:03	74.86	OK	18750	2026-09-23 11:04	72.14	OK
18751	2026-09-23 11:05	74.36	OK	18752	2026-09-23 11:06	74.20	OK
18753	2026-09-23 11:07	73.02	OK	18754	2026-09-23 11:08	72.37	OK
18755	2026-09-23 11:09	76.54	OK	18756	2026-09-23 11:10	73.86	OK
18757	2026-09-23 11:11	74.15	OK	18758	2026-09-23 11:12	76.09	OK
18759	2026-09-23 11:13	74.72	OK	18760	2026-09-23 11:14	74.31	OK
18761	2026-09-23 11:15	73.91	OK	18762	2026-09-23 11:16	73.74	OK
18763	2026-09-23 11:17	73.46	OK	18764	2026-09-23 11:18	74.33	OK
18765	2026-09-23 11:19	71.46	OK	18766	2026-09-23 11:20	74.02	OK
18767	2026-09-23 11:21	71.37	OK	18768	2026-09-23 11:22	72.31	OK
18769	2026-09-23 11:23	70.67	OK	18770	2026-09-23 11:24	72.85	OK
18771	2026-09-23 11:25	73.18	OK	18772	2026-09-23 11:26	74.85	OK
18773	2026-09-23 11:27	73.94	OK	18774	2026-09-23 11:28	74.51	OK
18775	2026-09-23 11:29	72.25	OK	18776	2026-09-23 11:30	72.68	OK
18777	2026-09-23 11:31	72.40	OK	18778	2026-09-23 11:32	72.68	OK
18779	2026-09-23 11:33	72.57	OK	18780	2026-09-23 11:34	74.71	OK
18781	2026-09-23 11:35	72.90	OK	18782	2026-09-23 11:36	73.85	OK
18783	2026-09-23 11:37	71.77	OK	18784	2026-09-23 11:38	74.10	OK
18785	2026-09-23 11:39	73.24	OK	18786	2026-09-23 11:40	70.01	OK
18787	2026-09-23 11:41	72.61	OK	18788	2026-09-23 11:42	72.19	OK
18789	2026-09-23 11:43	72.67	OK	18790	2026-09-23 11:44	74.50	OK
18791	2026-09-23 11:45	73.25	OK	18792	2026-09-23 11:46	72.21	OK
18793	2026-09-23 11:47	73.00	OK	18794	2026-09-23 11:48	74.62	OK
18795	2026-09-23 11:49	71.29	OK	18796	2026-09-23 11:50	72.80	OK
18797	2026-09-23 11:51	73.39	OK	18797	2026-09-23 11:52	71.72	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
18799	2026-09-23 11:53	72.52	OK	18800	2026-09-23 11:54	72.28	OK
18801	2026-09-23 11:55	73.63	OK	18802	2026-09-23 11:56	73.82	OK
18803	2026-09-23 11:57	74.15	OK	18804	2026-09-23 11:58	73.18	OK
18805	2026-09-23 11:59	74.82	OK	18806	2026-09-23 12:00	71.63	OK
18807	2026-09-23 12:01	70.37	OK	18808	2026-09-23 12:02	74.60	OK
18809	2026-09-23 12:03	72.04	OK	18810	2026-09-23 12:04	73.22	OK
18811	2026-09-23 12:05	69.88	OK	18812	2026-09-23 12:06	72.34	OK
18813	2026-09-23 12:07	73.39	OK	18814	2026-09-23 12:08	72.11	OK
18815	2026-09-23 12:09	72.86	OK	18816	2026-09-23 12:10	71.02	OK
18817	2026-09-23 12:11	70.22	OK	18818	2026-09-23 12:12	71.88	OK
18819	2026-09-23 12:13	71.38	OK	18820	2026-09-23 12:14	73.26	OK
18821	2026-09-23 12:15	73.43	OK	18822	2026-09-23 12:16	70.59	OK
18823	2026-09-23 12:17	73.55	OK	18824	2026-09-23 12:18	70.77	OK
18825	2026-09-23 12:19	70.54	OK	18826	2026-09-23 12:20	70.95	OK
18827	2026-09-23 12:21	70.10	OK	18828	2026-09-23 12:22	73.70	OK
18829	2026-09-23 12:23	74.28	OK	18830	2026-09-23 12:24	70.52	OK
18831	2026-09-23 12:25	69.49	OK	18832	2026-09-23 12:26	73.27	OK
18833	2026-09-23 12:27	71.25	OK	18834	2026-09-23 12:28	71.97	OK
18835	2026-09-23 12:29	73.54	OK	18836	2026-09-23 12:30	71.95	OK
18837	2026-09-23 12:31	72.39	OK	18838	2026-09-23 12:32	72.59	OK
18839	2026-09-23 12:33	73.68	OK	18840	2026-09-23 12:34	74.24	OK
18841	2026-09-23 12:35	72.27	OK	18842	2026-09-23 12:36	72.19	OK
18843	2026-09-23 12:37	70.80	OK	18844	2026-09-23 12:38	72.43	OK
18845	2026-09-23 12:39	72.69	OK	18846	2026-09-23 12:40	72.14	OK
18847	2026-09-23 12:41	71.64	OK	18848	2026-09-23 12:42	72.62	OK
18849	2026-09-23 12:43	71.39	OK	18850	2026-09-23 12:44	73.04	OK
18851	2026-09-23 12:45	70.66	OK	18852	2026-09-23 12:46	71.04	OK
18853	2026-09-23 12:47	72.71	OK	18854	2026-09-23 12:48	71.61	OK
18855	2026-09-23 12:49	71.75	OK	18856	2026-09-23 12:50	73.22	OK
1885	2026-09-23 12:51	72.05	OK	1885	2026-09-23 12:52	70.82	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
18859	2026-09-23 12:53	71.02	OK	18860	2026-09-23 12:54	74.32	OK
18861	2026-09-23 12:55	70.37	OK	18862	2026-09-23 12:56	71.38	OK
18863	2026-09-23 12:57	72.80	OK	18864	2026-09-23 12:58	73.27	OK
18865	2026-09-23 12:59	69.37	OK	18866	2026-09-23 13:00	69.27	OK
18867	2026-09-23 13:01	71.04	OK	18868	2026-09-23 13:02	71.22	OK
18869	2026-09-23 13:03	71.19	OK	18870	2026-09-23 13:04	69.83	OK
18871	2026-09-23 13:05	71.69	OK	18872	2026-09-23 13:06	72.35	OK
18873	2026-09-23 13:07	71.80	OK	18874	2026-09-23 13:08	71.03	OK
18875	2026-09-23 13:09	73.68	OK	18876	2026-09-23 13:10	71.11	OK
18877	2026-09-23 13:11	72.69	OK	18878	2026-09-23 13:12	71.94	OK
18879	2026-09-23 13:13	72.81	OK	18880	2026-09-23 13:14	70.94	OK
18881	2026-09-23 13:15	72.07	OK	18882	2026-09-23 13:16	72.48	OK
18883	2026-09-23 13:17	71.70	OK	18884	2026-09-23 13:18	71.67	OK
18885	2026-09-23 13:19	72.23	OK	18886	2026-09-23 13:20	71.90	OK
18887	2026-09-23 13:21	69.82	OK	18888	2026-09-23 13:22	71.18	OK
18889	2026-09-23 13:23	72.36	OK	18890	2026-09-23 13:24	70.18	OK
18891	2026-09-23 13:25	71.87	OK	18892	2026-09-23 13:26	70.95	OK
18893	2026-09-23 13:27	72.05	OK	18894	2026-09-23 13:28	73.14	OK
18895	2026-09-23 13:29	71.27	OK	18896	2026-09-23 13:30	72.85	OK
18897	2026-09-23 13:31	70.43	OK	18898	2026-09-23 13:32	68.38	OK
18899	2026-09-23 13:33	73.01	OK	18900	2026-09-23 13:34	70.72	OK
18901	2026-09-23 13:35	70.15	OK	18902	2026-09-23 13:36	70.92	OK
18903	2026-09-23 13:37	70.81	OK	18904	2026-09-23 13:38	70.98	OK
18905	2026-09-23 13:39	70.19	OK	18906	2026-09-23 13:40	70.20	OK
18907	2026-09-23 13:41	73.76	OK	18908	2026-09-23 13:42	72.06	OK
18909	2026-09-23 13:43	74.00	OK	18910	2026-09-23 13:44	71.88	OK
18911	2026-09-23 13:45	71.73	OK	18912	2026-09-23 13:46	72.62	OK
18913	2026-09-23 13:47	71.46	OK	18914	2026-09-23 13:48	73.57	OK
18915	2026-09-23 13:49	70.37	OK	18916	2026-09-23 13:50	71.88	OK
18917	2026-09-23 13:51	73.54	OK	18918	2026-09-23 13:52	71.68	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
18919	2026-09-23 13:53	72.14	OK	18920	2026-09-23 13:54	72.93	OK
18921	2026-09-23 13:55	69.31	OK	18922	2026-09-23 13:56	72.47	OK
18923	2026-09-23 13:57	71.92	OK	18924	2026-09-23 13:58	71.46	OK
18925	2026-09-23 13:59	73.54	OK	18926	2026-09-23 14:00	72.90	OK
18927	2026-09-23 14:01	70.59	OK	18928	2026-09-23 14:02	74.02	OK
18929	2026-09-23 14:03	71.72	OK	18930	2026-09-23 14:04	70.28	OK
18931	2026-09-23 14:05	73.42	OK	18932	2026-09-23 14:06	70.43	OK
18933	2026-09-23 14:07	70.81	OK	18934	2026-09-23 14:08	72.46	OK
18935	2026-09-23 14:09	73.29	OK	18936	2026-09-23 14:10	71.20	OK
18937	2026-09-23 14:11	72.57	OK	18938	2026-09-23 14:12	73.59	OK
18939	2026-09-23 14:13	70.13	OK	18940	2026-09-23 14:14	70.05	OK
18941	2026-09-23 14:15	69.64	OK	18942	2026-09-23 14:16	72.51	OK
18943	2026-09-23 14:17	74.16	OK	18944	2026-09-23 14:18	71.61	OK
18945	2026-09-23 14:19	69.94	OK	18946	2026-09-23 14:20	71.48	OK
18947	2026-09-23 14:21	73.77	OK	18948	2026-09-23 14:22	74.07	OK
18949	2026-09-23 14:23	72.68	OK	18950	2026-09-23 14:24	71.22	OK
18951	2026-09-23 14:25	68.11	OK	18952	2026-09-23 14:26	72.96	OK
18953	2026-09-23 14:27	73.42	OK	18954	2026-09-23 14:28	71.38	OK
18955	2026-09-23 14:29	70.42	OK	18956	2026-09-23 14:30	71.31	OK
18957	2026-09-23 14:31	71.72	OK	18958	2026-09-23 14:32	73.83	OK
18959	2026-09-23 14:33	71.21	OK	18960	2026-09-23 14:34	72.41	OK
18961	2026-09-23 14:35	70.76	OK	18962	2026-09-23 14:36	70.38	OK
18963	2026-09-23 14:37	70.96	OK	18964	2026-09-23 14:38	71.23	OK
18965	2026-09-23 14:39	73.60	OK	18966	2026-09-23 14:40	72.01	OK
18967	2026-09-23 14:41	71.58	OK	18968	2026-09-23 14:42	70.01	OK
18969	2026-09-23 14:43	73.03	OK	18970	2026-09-23 14:44	72.56	OK
18971	2026-09-23 14:45	69.05	OK	18972	2026-09-23 14:46	72.10	OK
18973	2026-09-23 14:47	70.19	OK	18974	2026-09-23 14:48	71.75	OK
18975	2026-09-23 14:49	72.10	OK	18976	2026-09-23 14:50	72.15	OK
18977	2026-09-23 14:51	72.16	OK	18977	2026-09-23 14:52	71.05	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
18979	2026-09-23 14:53	70.69	OK	18980	2026-09-23 14:54	69.54	OK
18981	2026-09-23 14:55	73.94	OK	18982	2026-09-23 14:56	72.28	OK
18983	2026-09-23 14:57	71.16	OK	18984	2026-09-23 14:58	71.46	OK
18985	2026-09-23 14:59	71.02	OK	18986	2026-09-23 15:00	72.17	OK
18987	2026-09-23 15:01	73.09	OK	18988	2026-09-23 15:02	71.37	OK
18989	2026-09-23 15:03	71.39	OK	18990	2026-09-23 15:04	70.55	OK
18991	2026-09-23 15:05	70.40	OK	18992	2026-09-23 15:06	72.18	OK
18993	2026-09-23 15:07	73.23	OK	18994	2026-09-23 15:08	73.00	OK
18995	2026-09-23 15:09	72.09	OK	18996	2026-09-23 15:10	72.39	OK
18997	2026-09-23 15:11	68.08	OK	18998	2026-09-23 15:12	70.85	OK
18999	2026-09-23 15:13	70.38	OK	19000	2026-09-23 15:14	69.48	OK
19001	2026-09-23 15:15	71.63	OK	19002	2026-09-23 15:16	71.21	OK
19003	2026-09-23 15:17	68.76	OK	19004	2026-09-23 15:18	73.28	OK
19005	2026-09-23 15:19	69.49	OK	19006	2026-09-23 15:20	71.81	OK
19007	2026-09-23 15:21	70.68	OK	19008	2026-09-23 15:22	73.51	OK
19009	2026-09-23 15:23	71.09	OK	19010	2026-09-23 15:24	72.26	OK
19011	2026-09-23 15:25	71.10	OK	19012	2026-09-23 15:26	73.57	OK
19013	2026-09-23 15:27	70.14	OK	19014	2026-09-23 15:28	70.52	OK
19015	2026-09-23 15:29	72.51	OK	19016	2026-09-23 15:30	72.29	OK
19017	2026-09-23 15:31	68.54	OK	19018	2026-09-23 15:32	71.52	OK
19019	2026-09-23 15:33	73.06	OK	19020	2026-09-23 15:34	69.72	OK
19021	2026-09-23 15:35	70.44	OK	19022	2026-09-23 15:36	72.36	OK
19023	2026-09-23 15:37	73.55	OK	19024	2026-09-23 15:38	71.34	OK
19025	2026-09-23 15:39	70.33	OK	19026	2026-09-23 15:40	68.73	OK
19027	2026-09-23 15:41	70.28	OK	19028	2026-09-23 15:42	69.53	OK
19029	2026-09-23 15:43	68.66	OK	19030	2026-09-23 15:44	71.61	OK
19031	2026-09-23 15:45	68.95	OK	19032	2026-09-23 15:46	73.48	OK
19033	2026-09-23 15:47	71.57	OK	19034	2026-09-23 15:48	71.16	OK
19035	2026-09-23 15:49	71.84	OK	19036	2026-09-23 15:50	69.55	OK
1903	2026-09-23 15:51	71.04	OK	1903	2026-09-23 15:52	72.75	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
19039	2026-09-23 15:53	70.72	OK	19040	2026-09-23 15:54	70.30	OK
19041	2026-09-23 15:55	71.73	OK	19042	2026-09-23 15:56	72.39	OK
19043	2026-09-23 15:57	70.79	OK	19044	2026-09-23 15:58	70.68	OK
19045	2026-09-23 15:59	74.55	OK	19046	2026-09-23 16:00	73.36	OK
19047	2026-09-23 16:01	69.23	OK	19048	2026-09-23 16:02	71.55	OK
19049	2026-09-23 16:03	73.18	OK	19050	2026-09-23 16:04	72.62	OK
19051	2026-09-23 16:05	71.28	OK	19052	2026-09-23 16:06	71.09	OK
19053	2026-09-23 16:07	70.66	OK	19054	2026-09-23 16:08	73.75	OK
19055	2026-09-23 16:09	69.57	OK	19056	2026-09-23 16:10	72.41	OK
19057	2026-09-23 16:11	71.52	OK	19058	2026-09-23 16:12	73.07	OK
19059	2026-09-23 16:13	71.80	OK	19060	2026-09-23 16:14	71.82	OK
19061	2026-09-23 16:15	70.09	OK	19062	2026-09-23 16:16	72.31	OK
19063	2026-09-23 16:17	71.24	OK	19064	2026-09-23 16:18	74.34	OK
19065	2026-09-23 16:19	69.89	OK	19066	2026-09-23 16:20	73.80	OK
19067	2026-09-23 16:21	72.18	OK	19068	2026-09-23 16:22	72.22	OK
19069	2026-09-23 16:23	71.75	OK	19070	2026-09-23 16:24	71.14	OK
19071	2026-09-23 16:25	73.32	OK	19072	2026-09-23 16:26	71.49	OK
19073	2026-09-23 16:27	72.53	OK	19074	2026-09-23 16:28	72.01	OK
19075	2026-09-23 16:29	71.79	OK	19076	2026-09-23 16:30	72.13	OK
19077	2026-09-23 16:31	71.56	OK	19078	2026-09-23 16:32	70.23	OK
19079	2026-09-23 16:33	73.46	OK	19080	2026-09-23 16:34	71.75	OK
19081	2026-09-23 16:35	74.08	OK	19082	2026-09-23 16:36	70.78	OK
19083	2026-09-23 16:37	72.42	OK	19084	2026-09-23 16:38	69.66	OK
19085	2026-09-23 16:39	72.58	OK	19086	2026-09-23 16:40	72.41	OK
19087	2026-09-23 16:41	73.03	OK	19088	2026-09-23 16:42	70.15	OK
19089	2026-09-23 16:43	71.14	OK	19090	2026-09-23 16:44	72.74	OK
19091	2026-09-23 16:45	72.12	OK	19092	2026-09-23 16:46	71.57	OK
19093	2026-09-23 16:47	70.82	OK	19094	2026-09-23 16:48	72.06	OK
19095	2026-09-23 16:49	71.60	OK	19096	2026-09-23 16:50	72.23	OK
1909	2026-09-23 16:51	71.65	OK	1909	2026-09-23 16:52	72.77	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
19099	2026-09-23 16:53	71.27	OK	19100	2026-09-23 16:54	71.45	OK
19101	2026-09-23 16:55	73.70	OK	19102	2026-09-23 16:56	68.89	OK
19103	2026-09-23 16:57	71.58	OK	19104	2026-09-23 16:58	70.92	OK
19105	2026-09-23 16:59	70.27	OK	19106	2026-09-23 17:00	72.58	OK
19107	2026-09-23 17:01	73.42	OK	19108	2026-09-23 17:02	72.11	OK
19109	2026-09-23 17:03	72.81	OK	19110	2026-09-23 17:04	74.79	OK
19111	2026-09-23 17:05	70.92	OK	19112	2026-09-23 17:06	73.86	OK
19113	2026-09-23 17:07	72.29	OK	19114	2026-09-23 17:08	70.18	OK
19115	2026-09-23 17:09	72.51	OK	19116	2026-09-23 17:10	73.32	OK
19117	2026-09-23 17:11	74.07	OK	19118	2026-09-23 17:12	73.02	OK
19119	2026-09-23 17:13	72.42	OK	19120	2026-09-23 17:14	71.04	OK
19121	2026-09-23 17:15	70.76	OK	19122	2026-09-23 17:16	71.66	OK
19123	2026-09-23 17:17	72.71	OK	19124	2026-09-23 17:18	71.23	OK
19125	2026-09-23 17:19	72.53	OK	19126	2026-09-23 17:20	75.47	OK
19127	2026-09-23 17:21	74.38	OK	19128	2026-09-23 17:22	73.32	OK
19129	2026-09-23 17:23	70.51	OK	19130	2026-09-23 17:24	71.94	OK
19131	2026-09-23 17:25	70.89	OK	19132	2026-09-23 17:26	70.62	OK
19133	2026-09-23 17:27	72.55	OK	19134	2026-09-23 17:28	73.25	OK
19135	2026-09-23 17:29	70.79	OK	19136	2026-09-23 17:30	70.63	OK
19137	2026-09-23 17:31	71.38	OK	19138	2026-09-23 17:32	73.79	OK
19139	2026-09-23 17:33	72.52	OK	19140	2026-09-23 17:34	73.05	OK
19141	2026-09-23 17:35	72.17	OK	19142	2026-09-23 17:36	71.92	OK
19143	2026-09-23 17:37	73.10	OK	19144	2026-09-23 17:38	75.01	OK
19145	2026-09-23 17:39	72.45	OK	19146	2026-09-23 17:40	75.66	OK
19147	2026-09-23 17:41	72.27	OK	19148	2026-09-23 17:42	71.75	OK
19149	2026-09-23 17:43	75.41	OK	19150	2026-09-23 17:44	70.09	OK
19151	2026-09-23 17:45	71.88	OK	19152	2026-09-23 17:46	74.54	OK
19153	2026-09-23 17:47	71.97	OK	19154	2026-09-23 17:48	72.68	OK
19155	2026-09-23 17:49	75.44	OK	19156	2026-09-23 17:50	73.70	OK
1915	2026-09-23 17:51	73.02	OK	1915	2026-09-23 17:52	72.29	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
19159	2026-09-23 17:53	73.57	OK	19160	2026-09-23 17:54	73.04	OK
19161	2026-09-23 17:55	72.13	OK	19162	2026-09-23 17:56	74.14	OK
19163	2026-09-23 17:57	72.95	OK	19164	2026-09-23 17:58	73.43	OK
19165	2026-09-23 17:59	74.04	OK	19166	2026-09-23 18:00	73.07	OK
19167	2026-09-23 18:01	73.61	OK	19168	2026-09-23 18:02	75.46	OK
19169	2026-09-23 18:03	72.86	OK	19170	2026-09-23 18:04	73.85	OK
19171	2026-09-23 18:05	69.77	OK	19172	2026-09-23 18:06	73.65	OK
19173	2026-09-23 18:07	72.23	OK	19174	2026-09-23 18:08	71.73	OK
19175	2026-09-23 18:09	71.03	OK	19176	2026-09-23 18:10	71.66	OK
19177	2026-09-23 18:11	73.29	OK	19178	2026-09-23 18:12	74.60	OK
19179	2026-09-23 18:13	73.48	OK	19180	2026-09-23 18:14	71.60	OK
19181	2026-09-23 18:15	72.39	OK	19182	2026-09-23 18:16	72.94	OK
19183	2026-09-23 18:17	72.02	OK	19184	2026-09-23 18:18	75.89	OK
19185	2026-09-23 18:19	73.54	OK	19186	2026-09-23 18:20	72.65	OK
19187	2026-09-23 18:21	73.08	OK	19188	2026-09-23 18:22	72.63	OK
19189	2026-09-23 18:23	76.23	OK	19190	2026-09-23 18:24	72.48	OK
19191	2026-09-23 18:25	72.42	OK	19192	2026-09-23 18:26	74.68	OK
19193	2026-09-23 18:27	73.24	OK	19194	2026-09-23 18:28	73.96	OK
19195	2026-09-23 18:29	73.35	OK	19196	2026-09-23 18:30	74.55	OK
19197	2026-09-23 18:31	73.08	OK	19198	2026-09-23 18:32	72.22	OK
19199	2026-09-23 18:33	71.86	OK	19200	2026-09-23 18:34	72.94	OK
19201	2026-09-23 18:35	72.84	OK	19202	2026-09-23 18:36	73.12	OK
19203	2026-09-23 18:37	73.88	OK	19204	2026-09-23 18:38	73.14	OK
19205	2026-09-23 18:39	73.76	OK	19206	2026-09-23 18:40	73.57	OK
19207	2026-09-23 18:41	74.25	OK	19208	2026-09-23 18:42	73.63	OK
19209	2026-09-23 18:43	74.42	OK	19210	2026-09-23 18:44	74.29	OK
19211	2026-09-23 18:45	74.75	OK	19212	2026-09-23 18:46	73.21	OK
19213	2026-09-23 18:47	73.99	OK	19214	2026-09-23 18:48	73.37	OK
19215	2026-09-23 18:49	74.12	OK	19216	2026-09-23 18:50	74.62	OK
19217	2026-09-23 18:51	72.96	OK	19218	2026-09-23 18:52	74.70	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
19219	2026-09-23 18:53	71.57	OK	19220	2026-09-23 18:54	76.19	OK
19221	2026-09-23 18:55	74.56	OK	19222	2026-09-23 18:56	72.06	OK
19223	2026-09-23 18:57	74.75	OK	19224	2026-09-23 18:58	74.77	OK
19225	2026-09-23 18:59	74.95	OK	19226	2026-09-23 19:00	73.13	OK
19227	2026-09-23 19:01	73.27	OK	19228	2026-09-23 19:02	73.47	OK
19229	2026-09-23 19:03	75.87	OK	19230	2026-09-23 19:04	77.00	OK
19231	2026-09-23 19:05	73.95	OK	19232	2026-09-23 19:06	77.46	OK
19233	2026-09-23 19:07	72.98	OK	19234	2026-09-23 19:08	71.80	OK
19235	2026-09-23 19:09	73.78	OK	19236	2026-09-23 19:10	75.44	OK
19237	2026-09-23 19:11	74.01	OK	19238	2026-09-23 19:12	73.09	OK
19239	2026-09-23 19:13	74.01	OK	19240	2026-09-23 19:14	73.73	OK
19241	2026-09-23 19:15	72.71	OK	19242	2026-09-23 19:16	76.19	OK
19243	2026-09-23 19:17	75.98	OK	19244	2026-09-23 19:18	73.96	OK
19245	2026-09-23 19:19	73.89	OK	19246	2026-09-23 19:20	74.63	OK
19247	2026-09-23 19:21	75.04	OK	19248	2026-09-23 19:22	74.88	OK
19249	2026-09-23 19:23	75.01	OK	19250	2026-09-23 19:24	73.46	OK
19251	2026-09-23 19:25	72.77	OK	19252	2026-09-23 19:26	74.63	OK
19253	2026-09-23 19:27	75.12	OK	19254	2026-09-23 19:28	74.09	OK
19255	2026-09-23 19:29	74.79	OK	19256	2026-09-23 19:30	75.45	OK
19257	2026-09-23 19:31	73.80	OK	19258	2026-09-23 19:32	73.72	OK
19259	2026-09-23 19:33	74.96	OK	19260	2026-09-23 19:34	75.51	OK
19261	2026-09-23 19:35	76.01	OK	19262	2026-09-23 19:36	73.81	OK
19263	2026-09-23 19:37	74.43	OK	19264	2026-09-23 19:38	74.75	OK
19265	2026-09-23 19:39	72.78	OK	19266	2026-09-23 19:40	75.40	OK
19267	2026-09-23 19:41	74.87	OK	19268	2026-09-23 19:42	76.07	OK
19269	2026-09-23 19:43	75.92	OK	19270	2026-09-23 19:44	73.58	OK
19271	2026-09-23 19:45	74.29	OK	19272	2026-09-23 19:46	75.84	OK
19273	2026-09-23 19:47	74.49	OK	19274	2026-09-23 19:48	76.42	OK
19275	2026-09-23 19:49	73.11	OK	19276	2026-09-23 19:50	76.06	OK
1927	2026-09-23 19:51	75.63	OK	1927	2026-09-23 19:52	75.80	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
19279	2026-09-23 19:53	73.87	OK	19280	2026-09-23 19:54	76.08	OK
19281	2026-09-23 19:55	75.87	OK	19282	2026-09-23 19:56	76.65	OK
19283	2026-09-23 19:57	75.38	OK	19284	2026-09-23 19:58	75.39	OK
19285	2026-09-23 19:59	75.53	OK	19286	2026-09-23 20:00	75.25	OK
19287	2026-09-23 20:01	76.46	OK	19288	2026-09-23 20:02	74.17	OK
19289	2026-09-23 20:03	74.55	OK	19290	2026-09-23 20:04	74.99	OK
19291	2026-09-23 20:05	73.99	OK	19292	2026-09-23 20:06	74.96	OK
19293	2026-09-23 20:07	75.12	OK	19294	2026-09-23 20:08	79.13	OK
19295	2026-09-23 20:09	73.41	OK	19296	2026-09-23 20:10	76.71	OK
19297	2026-09-23 20:11	75.13	OK	19298	2026-09-23 20:12	76.67	OK
19299	2026-09-23 20:13	77.73	OK	19300	2026-09-23 20:14	77.33	OK
19301	2026-09-23 20:15	74.61	OK	19302	2026-09-23 20:16	77.02	OK
19303	2026-09-23 20:17	74.19	OK	19304	2026-09-23 20:18	74.98	OK
19305	2026-09-23 20:19	75.03	OK	19306	2026-09-23 20:20	74.56	OK
19307	2026-09-23 20:21	76.85	OK	19308	2026-09-23 20:22	74.95	OK
19309	2026-09-23 20:23	74.57	OK	19310	2026-09-23 20:24	77.76	OK
19311	2026-09-23 20:25	74.81	OK	19312	2026-09-23 20:26	74.67	OK
19313	2026-09-23 20:27	73.99	OK	19314	2026-09-23 20:28	74.91	OK
19315	2026-09-23 20:29	75.59	OK	19316	2026-09-23 20:30	76.65	OK
19317	2026-09-23 20:31	78.00	OK	19318	2026-09-23 20:32	78.11	OK
19319	2026-09-23 20:33	76.75	OK	19320	2026-09-23 20:34	77.52	OK
19321	2026-09-23 20:35	75.42	OK	19322	2026-09-23 20:36	74.56	OK
19323	2026-09-23 20:37	76.15	OK	19324	2026-09-23 20:38	78.46	OK
19325	2026-09-23 20:39	77.45	OK	19326	2026-09-23 20:40	76.88	OK
19327	2026-09-23 20:41	76.15	OK	19328	2026-09-23 20:42	75.33	OK
19329	2026-09-23 20:43	77.47	OK	19330	2026-09-23 20:44	74.49	OK
19331	2026-09-23 20:45	75.72	OK	19332	2026-09-23 20:46	76.22	OK
19333	2026-09-23 20:47	76.12	OK	19334	2026-09-23 20:48	76.04	OK
19335	2026-09-23 20:49	77.33	OK	19336	2026-09-23 20:50	76.74	OK
1933	2026-09-23 20:51	76.52	OK	1933	2026-09-23 20:52	76.84	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
19339	2026-09-23 20:53	77.92	OK	19340	2026-09-23 20:54	76.90	OK
19341	2026-09-23 20:55	76.64	OK	19342	2026-09-23 20:56	77.80	OK
19343	2026-09-23 20:57	78.21	OK	19344	2026-09-23 20:58	78.50	OK
19345	2026-09-23 20:59	78.26	OK	19346	2026-09-23 21:00	76.23	OK
19347	2026-09-23 21:01	75.43	OK	19348	2026-09-23 21:02	77.22	OK
19349	2026-09-23 21:03	78.54	OK	19350	2026-09-23 21:04	75.85	OK
19351	2026-09-23 21:05	77.72	OK	19352	2026-09-23 21:06	77.18	OK
19353	2026-09-23 21:07	77.73	OK	19354	2026-09-23 21:08	74.80	OK
19355	2026-09-23 21:09	79.66	OK	19356	2026-09-23 21:10	76.04	OK
19357	2026-09-23 21:11	77.77	OK	19358	2026-09-23 21:12	77.82	OK
19359	2026-09-23 21:13	77.22	OK	19360	2026-09-23 21:14	78.42	OK
19361	2026-09-23 21:15	75.00	OK	19362	2026-09-23 21:16	78.73	OK
19363	2026-09-23 21:17	76.24	OK	19364	2026-09-23 21:18	77.02	OK
19365	2026-09-23 21:19	77.51	OK	19366	2026-09-23 21:20	78.43	OK
19367	2026-09-23 21:21	75.27	OK	19368	2026-09-23 21:22	76.75	OK
19369	2026-09-23 21:23	76.62	OK	19370	2026-09-23 21:24	77.10	OK
19371	2026-09-23 21:25	78.19	OK	19372	2026-09-23 21:26	78.85	OK
19373	2026-09-23 21:27	77.45	OK	19374	2026-09-23 21:28	78.58	OK
19375	2026-09-23 21:29	78.93	OK	19376	2026-09-23 21:30	78.07	OK
19377	2026-09-23 21:31	78.82	OK	19378	2026-09-23 21:32	77.55	OK
19379	2026-09-23 21:33	76.06	OK	19380	2026-09-23 21:34	76.35	OK
19381	2026-09-23 21:35	77.62	OK	19382	2026-09-23 21:36	75.87	OK
19383	2026-09-23 21:37	77.71	OK	19384	2026-09-23 21:38	75.03	OK
19385	2026-09-23 21:39	77.12	OK	19386	2026-09-23 21:40	78.80	OK
19387	2026-09-23 21:41	76.21	OK	19388	2026-09-23 21:42	78.60	OK
19389	2026-09-23 21:43	78.16	OK	19390	2026-09-23 21:44	77.41	OK
19391	2026-09-23 21:45	78.45	OK	19392	2026-09-23 21:46	75.63	OK
19393	2026-09-23 21:47	79.49	OK	19394	2026-09-23 21:48	79.29	OK
19395	2026-09-23 21:49	80.60	OK	19396	2026-09-23 21:50	77.28	OK
1939	2026-09-23 21:51	80.58	OK	1939	2026-09-23 21:52	78.30	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
19399	2026-09-23 21:53	79.53	OK	19400	2026-09-23 21:54	78.55	OK
19401	2026-09-23 21:55	76.41	OK	19402	2026-09-23 21:56	77.83	OK
19403	2026-09-23 21:57	79.34	OK	19404	2026-09-23 21:58	78.43	OK
19405	2026-09-23 21:59	77.25	OK	19406	2026-09-23 22:00	76.85	OK
19407	2026-09-23 22:01	77.91	OK	19408	2026-09-23 22:02	78.55	OK
19409	2026-09-23 22:03	78.09	OK	19410	2026-09-23 22:04	78.36	OK
19411	2026-09-23 22:05	78.59	OK	19412	2026-09-23 22:06	78.13	OK
19413	2026-09-23 22:07	78.30	OK	19414	2026-09-23 22:08	79.14	OK
19415	2026-09-23 22:09	80.34	OK	19416	2026-09-23 22:10	79.36	OK
19417	2026-09-23 22:11	78.84	OK	19418	2026-09-23 22:12	78.87	OK
19419	2026-09-23 22:13	78.87	OK	19420	2026-09-23 22:14	77.63	OK
19421	2026-09-23 22:15	77.23	OK	19422	2026-09-23 22:16	76.95	OK
19423	2026-09-23 22:17	80.10	OK	19424	2026-09-23 22:18	80.59	OK
19425	2026-09-23 22:19	77.41	OK	19426	2026-09-23 22:20	79.12	OK
19427	2026-09-23 22:21	76.09	OK	19428	2026-09-23 22:22	78.39	OK
19429	2026-09-23 22:23	75.50	OK	19430	2026-09-23 22:24	79.70	OK
19431	2026-09-23 22:25	76.66	OK	19432	2026-09-23 22:26	80.06	OK
19433	2026-09-23 22:27	78.47	OK	19434	2026-09-23 22:28	79.10	OK
19435	2026-09-23 22:29	76.88	OK	19436	2026-09-23 22:30	78.12	OK
19437	2026-09-23 22:31	81.31	OK	19438	2026-09-23 22:32	77.78	OK
19439	2026-09-23 22:33	81.85	OK	19440	2026-09-23 22:34	78.42	OK
19441	2026-09-23 22:35	79.44	OK	19442	2026-09-23 22:36	78.59	OK
19443	2026-09-23 22:37	77.36	OK	19444	2026-09-23 22:38	81.72	OK
19445	2026-09-23 22:39	79.05	OK	19446	2026-09-23 22:40	81.21	OK
19447	2026-09-23 22:41	77.82	OK	19448	2026-09-23 22:42	76.53	OK
19449	2026-09-23 22:43	81.53	OK	19450	2026-09-23 22:44	79.45	OK
19451	2026-09-23 22:45	80.34	OK	19452	2026-09-23 22:46	78.64	OK
19453	2026-09-23 22:47	79.64	OK	19454	2026-09-23 22:48	80.28	OK
19455	2026-09-23 22:49	78.57	OK	19456	2026-09-23 22:50	78.41	OK
1945	2026-09-23 22:51	78.86	OK	1945	2026-09-23 22:52	78.60	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
19459	2026-09-23 22:53	76.16	OK	19460	2026-09-23 22:54	77.74	OK
19461	2026-09-23 22:55	78.68	OK	19462	2026-09-23 22:56	78.32	OK
19463	2026-09-23 22:57	79.50	OK	19464	2026-09-23 22:58	78.39	OK
19465	2026-09-23 22:59	79.65	OK	19466	2026-09-23 23:00	78.24	OK
19467	2026-09-23 23:01	77.59	OK	19468	2026-09-23 23:02	81.27	OK
19469	2026-09-23 23:03	78.51	OK	19470	2026-09-23 23:04	80.25	OK
19471	2026-09-23 23:05	78.60	OK	19472	2026-09-23 23:06	79.75	OK
19473	2026-09-23 23:07	79.07	OK	19474	2026-09-23 23:08	80.88	OK
19475	2026-09-23 23:09	81.31	OK	19476	2026-09-23 23:10	79.38	OK
19477	2026-09-23 23:11	80.48	OK	19478	2026-09-23 23:12	78.70	OK
19479	2026-09-23 23:13	79.18	OK	19480	2026-09-23 23:14	79.56	OK
19481	2026-09-23 23:15	78.39	OK	19482	2026-09-23 23:16	82.81	OK
19483	2026-09-23 23:17	79.77	OK	19484	2026-09-23 23:18	79.84	OK
19485	2026-09-23 23:19	80.56	OK	19486	2026-09-23 23:20	78.53	OK
19487	2026-09-23 23:21	81.88	OK	19488	2026-09-23 23:22	80.43	OK
19489	2026-09-23 23:23	81.73	OK	19490	2026-09-23 23:24	79.41	OK
19491	2026-09-23 23:25	79.62	OK	19492	2026-09-23 23:26	80.56	OK
19493	2026-09-23 23:27	80.65	OK	19494	2026-09-23 23:28	80.26	OK
19495	2026-09-23 23:29	79.44	OK	19496	2026-09-23 23:30	78.61	OK
19497	2026-09-23 23:31	78.44	OK	19498	2026-09-23 23:32	81.50	OK
19499	2026-09-23 23:33	77.38	OK	19500	2026-09-23 23:34	78.22	OK
19501	2026-09-23 23:35	78.62	OK	19502	2026-09-23 23:36	81.19	OK
19503	2026-09-23 23:37	80.69	OK	19504	2026-09-23 23:38	79.55	OK
19505	2026-09-23 23:39	82.50	OK	19506	2026-09-23 23:40	79.86	OK
19507	2026-09-23 23:41	79.45	OK	19508	2026-09-23 23:42	81.87	OK
19509	2026-09-23 23:43	77.93	OK	19510	2026-09-23 23:44	78.05	OK
19511	2026-09-23 23:45	81.49	OK	19512	2026-09-23 23:46	81.60	OK
19513	2026-09-23 23:47	79.83	OK	19514	2026-09-23 23:48	81.99	OK
19515	2026-09-23 23:49	82.41	OK	19516	2026-09-23 23:50	82.28	OK
1951	2026-09-23 23:51	78.42	OK	1951	2026-09-23 23:52	79.47	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
19519	2026-09-23 23:53	79.76	OK	19520	2026-09-23 23:54	81.76	OK
19521	2026-09-23 23:55	78.18	OK	19522	2026-09-23 23:56	79.44	OK
19523	2026-09-23 23:57	80.31	OK	19524	2026-09-23 23:58	81.16	OK
19525	2026-09-23 23:59	79.88	OK	19526	2026-09-24 00:00	81.80	OK
19527	2026-09-24 00:01	81.92	OK	19528	2026-09-24 00:02	79.51	OK
19529	2026-09-24 00:03	79.15	OK	19530	2026-09-24 00:04	79.00	OK
19531	2026-09-24 00:05	77.57	OK	19532	2026-09-24 00:06	80.08	OK
19533	2026-09-24 00:07	77.59	OK	19534	2026-09-24 00:08	79.20	OK
19535	2026-09-24 00:09	79.78	OK	19536	2026-09-24 00:10	80.59	OK
19537	2026-09-24 00:11	79.91	OK	19538	2026-09-24 00:12	79.78	OK
19539	2026-09-24 00:13	81.72	OK	19540	2026-09-24 00:14	80.36	OK
19541	2026-09-24 00:15	78.11	OK	19542	2026-09-24 00:16	82.95	OK
19543	2026-09-24 00:17	79.84	OK	19544	2026-09-24 00:18	80.38	OK
19545	2026-09-24 00:19	79.66	OK	19546	2026-09-24 00:20	82.87	OK
19547	2026-09-24 00:21	81.97	OK	19548	2026-09-24 00:22	78.13	OK
19549	2026-09-24 00:23	81.08	OK	19550	2026-09-24 00:24	81.42	OK
19551	2026-09-24 00:25	79.90	OK	19552	2026-09-24 00:26	80.49	OK
19553	2026-09-24 00:27	81.46	OK	19554	2026-09-24 00:28	81.41	OK
19555	2026-09-24 00:29	80.66	OK	19556	2026-09-24 00:30	81.90	OK
19557	2026-09-24 00:31	78.92	OK	19558	2026-09-24 00:32	81.23	OK
19559	2026-09-24 00:33	79.86	OK	19560	2026-09-24 00:34	79.66	OK
19561	2026-09-24 00:35	77.86	OK	19562	2026-09-24 00:36	82.79	OK
19563	2026-09-24 00:37	83.80	OK	19564	2026-09-24 00:38	81.65	OK
19565	2026-09-24 00:39	83.31	OK	19566	2026-09-24 00:40	79.92	OK
19567	2026-09-24 00:41	80.02	OK	19568	2026-09-24 00:42	82.01	OK
19569	2026-09-24 00:43	81.84	OK	19570	2026-09-24 00:44	80.49	OK
19571	2026-09-24 00:45	78.82	OK	19572	2026-09-24 00:46	79.60	OK
19573	2026-09-24 00:47	81.66	OK	19574	2026-09-24 00:48	80.28	OK
19575	2026-09-24 00:49	80.62	OK	19576	2026-09-24 00:50	82.08	OK
1957	2026-09-24 00:51	80.76	OK	1957	2026-09-24 00:52	82.16	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
19579	2026-09-24 00:53	78.50	OK	19580	2026-09-24 00:54	80.85	OK
19581	2026-09-24 00:55	78.23	OK	19582	2026-09-24 00:56	81.30	OK
19583	2026-09-24 00:57	80.69	OK	19584	2026-09-24 00:58	80.91	OK
19585	2026-09-24 00:59	78.32	OK	19586	2026-09-24 01:00	80.61	OK
19587	2026-09-24 01:01	82.27	OK	19588	2026-09-24 01:02	81.61	OK
19589	2026-09-24 01:03	82.92	OK	19590	2026-09-24 01:04	81.28	OK
19591	2026-09-24 01:05	81.36	OK	19592	2026-09-24 01:06	79.61	OK
19593	2026-09-24 01:07	78.17	OK	19594	2026-09-24 01:08	81.45	OK
19595	2026-09-24 01:09	83.64	OK	19596	2026-09-24 01:10	79.66	OK
19597	2026-09-24 01:11	81.82	OK	19598	2026-09-24 01:12	81.98	OK
19599	2026-09-24 01:13	83.46	OK	19600	2026-09-24 01:14	83.54	OK
19601	2026-09-24 01:15	80.54	OK	19602	2026-09-24 01:16	81.64	OK
19603	2026-09-24 01:17	80.19	OK	19604	2026-09-24 01:18	80.70	OK
19605	2026-09-24 01:19	81.68	OK	19606	2026-09-24 01:20	82.78	OK
19607	2026-09-24 01:21	80.04	OK	19608	2026-09-24 01:22	81.26	OK
19609	2026-09-24 01:23	81.94	OK	19610	2026-09-24 01:24	80.31	OK
19611	2026-09-24 01:25	83.38	OK	19612	2026-09-24 01:26	81.03	OK
19613	2026-09-24 01:27	81.71	OK	19614	2026-09-24 01:28	81.48	OK
19615	2026-09-24 01:29	81.85	OK	19616	2026-09-24 01:30	83.58	OK
19617	2026-09-24 01:31	81.53	OK	19618	2026-09-24 01:32	83.03	OK
19619	2026-09-24 01:33	82.07	OK	19620	2026-09-24 01:34	81.60	OK
19621	2026-09-24 01:35	80.52	OK	19622	2026-09-24 01:36	79.75	OK
19623	2026-09-24 01:37	81.79	OK	19624	2026-09-24 01:38	82.24	OK
19625	2026-09-24 01:39	82.14	OK	19626	2026-09-24 01:40	83.73	OK
19627	2026-09-24 01:41	79.00	OK	19628	2026-09-24 01:42	83.38	OK
19629	2026-09-24 01:43	82.78	OK	19630	2026-09-24 01:44	84.01	OK
19631	2026-09-24 01:45	80.88	OK	19632	2026-09-24 01:46	82.08	OK
19633	2026-09-24 01:47	82.59	OK	19634	2026-09-24 01:48	82.51	OK
19635	2026-09-24 01:49	78.76	OK	19636	2026-09-24 01:50	81.44	OK
1963	2026-09-24 01:51	82.79	OK	1963	2026-09-24 01:52	80.49	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
19639	2026-09-24 01:53	80.25	OK	19640	2026-09-24 01:54	83.19	OK
19641	2026-09-24 01:55	82.74	OK	19642	2026-09-24 01:56	82.68	OK
19643	2026-09-24 01:57	80.60	OK	19644	2026-09-24 01:58	80.54	OK
19645	2026-09-24 01:59	79.47	OK	19646	2026-09-24 02:00	82.87	OK
19647	2026-09-24 02:01	80.04	OK	19648	2026-09-24 02:02	79.49	OK
19649	2026-09-24 02:03	80.11	OK	19650	2026-09-24 02:04	80.99	OK
19651	2026-09-24 02:05	80.98	OK	19652	2026-09-24 02:06	80.85	OK
19653	2026-09-24 02:07	81.04	OK	19654	2026-09-24 02:08	82.83	OK
19655	2026-09-24 02:09	81.07	OK	19656	2026-09-24 02:10	81.37	OK
19657	2026-09-24 02:11	81.98	OK	19658	2026-09-24 02:12	82.85	OK
19659	2026-09-24 02:13	81.45	OK	19660	2026-09-24 02:14	80.70	OK
19661	2026-09-24 02:15	81.95	OK	19662	2026-09-24 02:16	81.50	OK
19663	2026-09-24 02:17	83.88	OK	19664	2026-09-24 02:18	79.66	OK
19665	2026-09-24 02:19	83.49	OK	19666	2026-09-24 02:20	79.92	OK
19667	2026-09-24 02:21	81.82	OK	19668	2026-09-24 02:22	83.93	OK
19669	2026-09-24 02:23	84.34	OK	19670	2026-09-24 02:24	82.79	OK
19671	2026-09-24 02:25	79.61	OK	19672	2026-09-24 02:26	79.14	OK
19673	2026-09-24 02:27	80.58	OK	19674	2026-09-24 02:28	78.63	OK
19675	2026-09-24 02:29	82.10	OK	19676	2026-09-24 02:30	81.89	OK
19677	2026-09-24 02:31	81.29	OK	19678	2026-09-24 02:32	82.52	OK
19679	2026-09-24 02:33	83.01	OK	19680	2026-09-24 02:34	83.46	OK
19681	2026-09-24 02:35	82.07	OK	19682	2026-09-24 02:36	82.39	OK
19683	2026-09-24 02:37	79.17	OK	19684	2026-09-24 02:38	83.00	OK
19685	2026-09-24 02:39	82.63	OK	19686	2026-09-24 02:40	82.99	OK
19687	2026-09-24 02:41	81.61	OK	19688	2026-09-24 02:42	82.64	OK
19689	2026-09-24 02:43	78.99	OK	19690	2026-09-24 02:44	79.98	OK
19691	2026-09-24 02:45	83.43	OK	19692	2026-09-24 02:46	82.83	OK
19693	2026-09-24 02:47	82.87	OK	19694	2026-09-24 02:48	81.49	OK
19695	2026-09-24 02:49	81.56	OK	19696	2026-09-24 02:50	81.59	OK
19697	2026-09-24 02:51	80.40	OK	19697	2026-09-24 02:52	83.51	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
19699	2026-09-24 02:53	80.76	OK	19700	2026-09-24 02:54	83.31	OK
19701	2026-09-24 02:55	82.74	OK	19702	2026-09-24 02:56	83.09	OK
19703	2026-09-24 02:57	80.33	OK	19704	2026-09-24 02:58	82.31	OK
19705	2026-09-24 02:59	80.56	OK	19706	2026-09-24 03:00	81.90	OK
19707	2026-09-24 03:01	81.74	OK	19708	2026-09-24 03:02	84.11	OK
19709	2026-09-24 03:03	81.62	OK	19710	2026-09-24 03:04	81.92	OK
19711	2026-09-24 03:05	80.86	OK	19712	2026-09-24 03:06	82.08	OK
19713	2026-09-24 03:07	80.75	OK	19714	2026-09-24 03:08	79.96	OK
19715	2026-09-24 03:09	79.14	OK	19716	2026-09-24 03:10	82.84	OK
19717	2026-09-24 03:11	80.87	OK	19718	2026-09-24 03:12	81.65	OK
19719	2026-09-24 03:13	81.35	OK	19720	2026-09-24 03:14	82.63	OK
19721	2026-09-24 03:15	79.83	OK	19722	2026-09-24 03:16	81.23	OK
19723	2026-09-24 03:17	81.31	OK	19724	2026-09-24 03:18	82.86	OK
19725	2026-09-24 03:19	82.48	OK	19726	2026-09-24 03:20	82.32	OK
19727	2026-09-24 03:21	82.83	OK	19728	2026-09-24 03:22	80.67	OK
19729	2026-09-24 03:23	81.72	OK	19730	2026-09-24 03:24	84.74	OK
19731	2026-09-24 03:25	83.20	OK	19732	2026-09-24 03:26	80.40	OK
19733	2026-09-24 03:27	79.84	OK	19734	2026-09-24 03:28	80.80	OK
19735	2026-09-24 03:29	81.76	OK	19736	2026-09-24 03:30	84.25	OK
19737	2026-09-24 03:31	81.09	OK	19738	2026-09-24 03:32	80.33	OK
19739	2026-09-24 03:33	82.09	OK	19740	2026-09-24 03:34	82.04	OK
19741	2026-09-24 03:35	80.75	OK	19742	2026-09-24 03:36	84.26	OK
19743	2026-09-24 03:37	79.96	OK	19744	2026-09-24 03:38	81.05	OK
19745	2026-09-24 03:39	81.93	OK	19746	2026-09-24 03:40	79.88	OK
19747	2026-09-24 03:41	82.71	OK	19748	2026-09-24 03:42	81.23	OK
19749	2026-09-24 03:43	81.22	OK	19750	2026-09-24 03:44	82.07	OK
19751	2026-09-24 03:45	82.55	OK	19752	2026-09-24 03:46	84.25	OK
19753	2026-09-24 03:47	83.09	OK	19754	2026-09-24 03:48	83.50	OK
19755	2026-09-24 03:49	81.52	OK	19756	2026-09-24 03:50	80.66	OK
19757	2026-09-24 03:51	82.13	OK	19757	2026-09-24 03:52	82.14	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
19759	2026-09-24 03:53	84.26	OK	19760	2026-09-24 03:54	79.38	OK
19761	2026-09-24 03:55	80.16	OK	19762	2026-09-24 03:56	81.51	OK
19763	2026-09-24 03:57	81.66	OK	19764	2026-09-24 03:58	80.97	OK
19765	2026-09-24 03:59	79.66	OK	19766	2026-09-24 04:00	81.78	OK
19767	2026-09-24 04:01	82.20	OK	19768	2026-09-24 04:02	82.06	OK
19769	2026-09-24 04:03	82.42	OK	19770	2026-09-24 04:04	83.02	OK
19771	2026-09-24 04:05	82.21	OK	19772	2026-09-24 04:06	82.87	OK
19773	2026-09-24 04:07	83.06	OK	19774	2026-09-24 04:08	81.85	OK
19775	2026-09-24 04:09	83.04	OK	19776	2026-09-24 04:10	82.99	OK
19777	2026-09-24 04:11	82.25	OK	19778	2026-09-24 04:12	80.95	OK
19779	2026-09-24 04:13	80.59	OK	19780	2026-09-24 04:14	79.68	OK
19781	2026-09-24 04:15	80.82	OK	19782	2026-09-24 04:16	80.31	OK
19783	2026-09-24 04:17	79.63	OK	19784	2026-09-24 04:18	79.00	OK
19785	2026-09-24 04:19	80.32	OK	19786	2026-09-24 04:20	82.62	OK
19787	2026-09-24 04:21	84.13	OK	19788	2026-09-24 04:22	80.25	OK
19789	2026-09-24 04:23	82.34	OK	19790	2026-09-24 04:24	80.56	OK
19791	2026-09-24 04:25	78.45	OK	19792	2026-09-24 04:26	80.09	OK
19793	2026-09-24 04:27	80.86	OK	19794	2026-09-24 04:28	79.42	OK
19795	2026-09-24 04:29	79.83	OK	19796	2026-09-24 04:30	82.43	OK
19797	2026-09-24 04:31	81.01	OK	19798	2026-09-24 04:32	81.98	OK
19799	2026-09-24 04:33	82.04	OK	19800	2026-09-24 04:34	80.79	OK
19801	2026-09-24 04:35	80.43	OK	19802	2026-09-24 04:36	79.76	OK
19803	2026-09-24 04:37	80.52	OK	19804	2026-09-24 04:38	81.56	OK
19805	2026-09-24 04:39	79.97	OK	19806	2026-09-24 04:40	79.23	OK
19807	2026-09-24 04:41	81.27	OK	19808	2026-09-24 04:42	79.72	OK
19809	2026-09-24 04:43	82.14	OK	19810	2026-09-24 04:44	80.39	OK
19811	2026-09-24 04:45	81.02	OK	19812	2026-09-24 04:46	80.76	OK
19813	2026-09-24 04:47	80.58	OK	19814	2026-09-24 04:48	82.44	OK
19815	2026-09-24 04:49	81.38	OK	19816	2026-09-24 04:50	78.73	OK
1981	2026-09-24 04:51	80.55	OK	1981	2026-09-24 04:52	80.61	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
19819	2026-09-24 04:53	82.80	OK	19820	2026-09-24 04:54	83.88	OK
19821	2026-09-24 04:55	80.24	OK	19822	2026-09-24 04:56	79.86	OK
19823	2026-09-24 04:57	80.00	OK	19824	2026-09-24 04:58	83.69	OK
19825	2026-09-24 04:59	78.75	OK	19826	2026-09-24 05:00	82.95	OK
19827	2026-09-24 05:01	82.15	OK	19828	2026-09-24 05:02	80.35	OK
19829	2026-09-24 05:03	81.70	OK	19830	2026-09-24 05:04	81.50	OK
19831	2026-09-24 05:05	81.02	OK	19832	2026-09-24 05:06	78.20	OK
19833	2026-09-24 05:07	81.61	OK	19834	2026-09-24 05:08	79.56	OK
19835	2026-09-24 05:09	79.76	OK	19836	2026-09-24 05:10	80.98	OK
19837	2026-09-24 05:11	80.72	OK	19838	2026-09-24 05:12	79.88	OK
19839	2026-09-24 05:13	81.89	OK	19840	2026-09-24 05:14	80.70	OK
19841	2026-09-24 05:15	79.88	OK	19842	2026-09-24 05:16	78.30	OK
19843	2026-09-24 05:17	79.03	OK	19844	2026-09-24 05:18	82.18	OK
19845	2026-09-24 05:19	82.58	OK	19846	2026-09-24 05:20	82.58	OK
19847	2026-09-24 05:21	82.43	OK	19848	2026-09-24 05:22	81.48	OK
19849	2026-09-24 05:23	78.52	OK	19850	2026-09-24 05:24	79.67	OK
19851	2026-09-24 05:25	79.52	OK	19852	2026-09-24 05:26	79.39	OK
19853	2026-09-24 05:27	79.31	OK	19854	2026-09-24 05:28	78.93	OK
19855	2026-09-24 05:29	81.28	OK	19856	2026-09-24 05:30	80.38	OK
19857	2026-09-24 05:31	79.80	OK	19858	2026-09-24 05:32	79.90	OK
19859	2026-09-24 05:33	81.19	OK	19860	2026-09-24 05:34	78.75	OK
19861	2026-09-24 05:35	79.65	OK	19862	2026-09-24 05:36	82.53	OK
19863	2026-09-24 05:37	80.30	OK	19864	2026-09-24 05:38	81.01	OK
19865	2026-09-24 05:39	81.50	OK	19866	2026-09-24 05:40	81.60	OK
19867	2026-09-24 05:41	80.93	OK	19868	2026-09-24 05:42	79.92	OK
19869	2026-09-24 05:43	78.43	OK	19870	2026-09-24 05:44	80.23	OK
19871	2026-09-24 05:45	79.26	OK	19872	2026-09-24 05:46	81.61	OK
19873	2026-09-24 05:47	79.75	OK	19874	2026-09-24 05:48	78.20	OK
19875	2026-09-24 05:49	81.40	OK	19876	2026-09-24 05:50	80.11	OK
1987	2026-09-24 05:51	81.35	OK	1987	2026-09-24 05:52	78.27	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
19879	2026-09-24 05:53	81.34	OK	19880	2026-09-24 05:54	79.89	OK
19881	2026-09-24 05:55	79.26	OK	19882	2026-09-24 05:56	80.43	OK
19883	2026-09-24 05:57	80.88	OK	19884	2026-09-24 05:58	78.57	OK
19885	2026-09-24 05:59	81.25	OK	19886	2026-09-24 06:00	80.49	OK
19887	2026-09-24 06:01	77.69	OK	19888	2026-09-24 06:02	79.90	OK
19889	2026-09-24 06:03	81.72	OK	19890	2026-09-24 06:04	79.22	OK
19891	2026-09-24 06:05	79.17	OK	19892	2026-09-24 06:06	78.77	OK
19893	2026-09-24 06:07	80.03	OK	19894	2026-09-24 06:08	81.79	OK
19895	2026-09-24 06:09	78.32	OK	19896	2026-09-24 06:10	81.13	OK
19897	2026-09-24 06:11	78.84	OK	19898	2026-09-24 06:12	81.88	OK
19899	2026-09-24 06:13	79.03	OK	19900	2026-09-24 06:14	77.42	OK
19901	2026-09-24 06:15	80.68	OK	19902	2026-09-24 06:16	81.18	OK
19903	2026-09-24 06:17	78.92	OK	19904	2026-09-24 06:18	79.61	OK
19905	2026-09-24 06:19	82.55	OK	19906	2026-09-24 06:20	77.85	OK
19907	2026-09-24 06:21	79.12	OK	19908	2026-09-24 06:22	78.97	OK
19909	2026-09-24 06:23	78.99	OK	19910	2026-09-24 06:24	81.52	OK
19911	2026-09-24 06:25	80.69	OK	19912	2026-09-24 06:26	79.85	OK
19913	2026-09-24 06:27	80.38	OK	19914	2026-09-24 06:28	78.24	OK
19915	2026-09-24 06:29	80.57	OK	19916	2026-09-24 06:30	78.56	OK
19917	2026-09-24 06:31	77.24	OK	19918	2026-09-24 06:32	79.64	OK
19919	2026-09-24 06:33	79.64	OK	19920	2026-09-24 06:34	76.21	OK
19921	2026-09-24 06:35	77.22	OK	19922	2026-09-24 06:36	78.05	OK
19923	2026-09-24 06:37	79.46	OK	19924	2026-09-24 06:38	80.15	OK
19925	2026-09-24 06:39	80.99	OK	19926	2026-09-24 06:40	79.14	OK
19927	2026-09-24 06:41	79.06	OK	19928	2026-09-24 06:42	80.19	OK
19929	2026-09-24 06:43	81.37	OK	19930	2026-09-24 06:44	79.27	OK
19931	2026-09-24 06:45	77.88	OK	19932	2026-09-24 06:46	79.75	OK
19933	2026-09-24 06:47	79.84	OK	19934	2026-09-24 06:48	77.48	OK
19935	2026-09-24 06:49	78.50	OK	19936	2026-09-24 06:50	79.65	OK
1993	2026-09-24 06:51	79.22	OK	1993	2026-09-24 06:52	77.70	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
19939	2026-09-24 06:53	80.85	OK	19940	2026-09-24 06:54	81.03	OK
19941	2026-09-24 06:55	78.38	OK	19942	2026-09-24 06:56	79.49	OK
19943	2026-09-24 06:57	76.64	OK	19944	2026-09-24 06:58	76.48	OK
19945	2026-09-24 06:59	78.90	OK	19946	2026-09-24 07:00	78.45	OK
19947	2026-09-24 07:01	77.06	OK	19948	2026-09-24 07:02	80.34	OK
19949	2026-09-24 07:03	80.43	OK	19950	2026-09-24 07:04	79.56	OK
19951	2026-09-24 07:05	80.29	OK	19952	2026-09-24 07:06	77.06	OK
19953	2026-09-24 07:07	76.91	OK	19954	2026-09-24 07:08	79.06	OK
19955	2026-09-24 07:09	76.00	OK	19956	2026-09-24 07:10	75.53	OK
19957	2026-09-24 07:11	80.57	OK	19958	2026-09-24 07:12	78.96	OK
19959	2026-09-24 07:13	76.49	OK	19960	2026-09-24 07:14	75.58	OK
19961	2026-09-24 07:15	77.20	OK	19962	2026-09-24 07:16	80.88	OK
19963	2026-09-24 07:17	76.94	OK	19964	2026-09-24 07:18	78.90	OK
19965	2026-09-24 07:19	79.12	OK	19966	2026-09-24 07:20	79.40	OK
19967	2026-09-24 07:21	81.50	OK	19968	2026-09-24 07:22	80.71	OK
19969	2026-09-24 07:23	78.85	OK	19970	2026-09-24 07:24	77.90	OK
19971	2026-09-24 07:25	78.29	OK	19972	2026-09-24 07:26	76.87	OK
19973	2026-09-24 07:27	77.86	OK	19974	2026-09-24 07:28	78.68	OK
19975	2026-09-24 07:29	79.61	OK	19976	2026-09-24 07:30	79.10	OK
19977	2026-09-24 07:31	75.77	OK	19978	2026-09-24 07:32	77.10	OK
19979	2026-09-24 07:33	79.46	OK	19980	2026-09-24 07:34	77.85	OK
19981	2026-09-24 07:35	76.53	OK	19982	2026-09-24 07:36	75.55	OK
19983	2026-09-24 07:37	78.26	OK	19984	2026-09-24 07:38	77.35	OK
19985	2026-09-24 07:39	78.77	OK	19986	2026-09-24 07:40	78.22	OK
19987	2026-09-24 07:41	78.03	OK	19988	2026-09-24 07:42	79.10	OK
19989	2026-09-24 07:43	77.66	OK	19990	2026-09-24 07:44	76.91	OK
19991	2026-09-24 07:45	78.66	OK	19992	2026-09-24 07:46	77.06	OK
19993	2026-09-24 07:47	77.42	OK	19994	2026-09-24 07:48	79.39	OK
19995	2026-09-24 07:49	78.06	OK	19996	2026-09-24 07:50	78.96	OK
1999	2026-09-24 07:51	79.53	OK	1999	2026-09-24 07:52	78.34	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
19999	2026-09-24 07:53	79.45	OK	20000	2026-09-24 07:54	78.45	OK
20001	2026-09-24 07:55	77.53	OK	20002	2026-09-24 07:56	77.12	OK
20003	2026-09-24 07:57	76.39	OK	20004	2026-09-24 07:58	77.22	OK
20005	2026-09-24 07:59	76.57	OK	20006	2026-09-24 08:00	78.45	OK
20007	2026-09-24 08:01	78.76	OK	20008	2026-09-24 08:02	77.13	OK
20009	2026-09-24 08:03	77.29	OK	20010	2026-09-24 08:04	79.83	OK
20011	2026-09-24 08:05	78.44	OK	20012	2026-09-24 08:06	75.42	OK
20013	2026-09-24 08:07	78.99	OK	20014	2026-09-24 08:08	77.15	OK
20015	2026-09-24 08:09	75.49	OK	20016	2026-09-24 08:10	77.07	OK
20017	2026-09-24 08:11	76.74	OK	20018	2026-09-24 08:12	77.55	OK
20019	2026-09-24 08:13	78.67	OK	20020	2026-09-24 08:14	77.10	OK
20021	2026-09-24 08:15	76.93	OK	20022	2026-09-24 08:16	74.96	OK
20023	2026-09-24 08:17	76.82	OK	20024	2026-09-24 08:18	75.74	OK
20025	2026-09-24 08:19	76.67	OK	20026	2026-09-24 08:20	79.38	OK
20027	2026-09-24 08:21	75.36	OK	20028	2026-09-24 08:22	76.92	OK
20029	2026-09-24 08:23	78.88	OK	20030	2026-09-24 08:24	78.57	OK
20031	2026-09-24 08:25	75.24	OK	20032	2026-09-24 08:26	78.01	OK
20033	2026-09-24 08:27	76.69	OK	20034	2026-09-24 08:28	78.92	OK
20035	2026-09-24 08:29	76.82	OK	20036	2026-09-24 08:30	76.35	OK
20037	2026-09-24 08:31	74.36	OK	20038	2026-09-24 08:32	79.61	OK
20039	2026-09-24 08:33	76.29	OK	20040	2026-09-24 08:34	77.79	OK
20041	2026-09-24 08:35	74.86	OK	20042	2026-09-24 08:36	77.95	OK
20043	2026-09-24 08:37	76.38	OK	20044	2026-09-24 08:38	73.56	OK
20045	2026-09-24 08:39	75.18	OK	20046	2026-09-24 08:40	75.69	OK
20047	2026-09-24 08:41	77.59	OK	20048	2026-09-24 08:42	77.65	OK
20049	2026-09-24 08:43	77.93	OK	20050	2026-09-24 08:44	75.84	OK
20051	2026-09-24 08:45	76.17	OK	20052	2026-09-24 08:46	79.50	OK
20053	2026-09-24 08:47	77.10	OK	20054	2026-09-24 08:48	76.29	OK
20055	2026-09-24 08:49	78.90	OK	20056	2026-09-24 08:50	76.93	OK
2005	2026-09-24 08:51	74.86	OK	2005	2026-09-24 08:52	73.86	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
20059	2026-09-24 08:53	74.49	OK	20060	2026-09-24 08:54	76.30	OK
20061	2026-09-24 08:55	77.24	OK	20062	2026-09-24 08:56	75.56	OK
20063	2026-09-24 08:57	77.85	OK	20064	2026-09-24 08:58	75.97	OK
20065	2026-09-24 08:59	75.93	OK	20066	2026-09-24 09:00	73.52	OK
20067	2026-09-24 09:01	74.92	OK	20068	2026-09-24 09:02	76.40	OK
20069	2026-09-24 09:03	77.36	OK	20070	2026-09-24 09:04	73.99	OK
20071	2026-09-24 09:05	76.36	OK	20072	2026-09-24 09:06	76.52	OK
20073	2026-09-24 09:07	75.55	OK	20074	2026-09-24 09:08	76.26	OK
20075	2026-09-24 09:09	77.38	OK	20076	2026-09-24 09:10	76.58	OK
20077	2026-09-24 09:11	74.51	OK	20078	2026-09-24 09:12	74.88	OK
20079	2026-09-24 09:13	75.78	OK	20080	2026-09-24 09:14	75.67	OK
20081	2026-09-24 09:15	77.70	OK	20082	2026-09-24 09:16	74.24	OK
20083	2026-09-24 09:17	76.83	OK	20084	2026-09-24 09:18	78.09	OK
20085	2026-09-24 09:19	75.72	OK	20086	2026-09-24 09:20	75.41	OK
20087	2026-09-24 09:21	75.23	OK	20088	2026-09-24 09:22	78.03	OK
20089	2026-09-24 09:23	77.25	OK	20090	2026-09-24 09:24	78.32	OK
20091	2026-09-24 09:25	76.35	OK	20092	2026-09-24 09:26	75.56	OK
20093	2026-09-24 09:27	75.54	OK	20094	2026-09-24 09:28	76.46	OK
20095	2026-09-24 09:29	75.49	OK	20096	2026-09-24 09:30	74.49	OK
20097	2026-09-24 09:31	76.32	OK	20098	2026-09-24 09:32	74.16	OK
20099	2026-09-24 09:33	76.40	OK	20100	2026-09-24 09:34	77.14	OK
20101	2026-09-24 09:35	75.36	OK	20102	2026-09-24 09:36	75.89	OK
20103	2026-09-24 09:37	76.92	OK	20104	2026-09-24 09:38	75.06	OK
20105	2026-09-24 09:39	75.40	OK	20106	2026-09-24 09:40	75.31	OK
20107	2026-09-24 09:41	76.43	OK	20108	2026-09-24 09:42	72.93	OK
20109	2026-09-24 09:43	73.97	OK	20110	2026-09-24 09:44	77.46	OK
20111	2026-09-24 09:45	74.66	OK	20112	2026-09-24 09:46	75.79	OK
20113	2026-09-24 09:47	75.28	OK	20114	2026-09-24 09:48	73.24	OK
20115	2026-09-24 09:49	74.90	OK	20116	2026-09-24 09:50	77.25	OK
20117	2026-09-24 09:51	77.18	OK	20118	2026-09-24 09:52	75.29	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7				8			
20119	2026-09-24 09:53	76.11	OK	20120	2026-09-24 09:54	75.59	OK
20121	2026-09-24 09:55	76.19	OK	20122	2026-09-24 09:56	75.77	OK
20123	2026-09-24 09:57	77.15	OK	20124	2026-09-24 09:58	75.28	OK
20125	2026-09-24 09:59	74.63	OK	20126	2026-09-24 10:00	75.77	OK
20127	2026-09-24 10:01	76.02	OK	20128	2026-09-24 10:02	73.76	OK
20129	2026-09-24 10:03	75.61	OK	20130	2026-09-24 10:04	76.45	OK
20131	2026-09-24 10:05	74.91	OK	20132	2026-09-24 10:06	76.57	OK
20133	2026-09-24 10:07	75.87	OK	20134	2026-09-24 10:08	74.97	OK
20135	2026-09-24 10:09	72.26	OK	20136	2026-09-24 10:10	75.53	OK
20137	2026-09-24 10:11	75.18	OK	20138	2026-09-24 10:12	73.97	OK
20139	2026-09-24 10:13	73.70	OK	20140	2026-09-24 10:14	74.64	OK
20141	2026-09-24 10:15	76.04	OK	20142	2026-09-24 10:16	74.54	OK
20143	2026-09-24 10:17	74.14	OK	20144	2026-09-24 10:18	73.25	OK
20145	2026-09-24 10:19	74.65	OK	20146	2026-09-24 10:20	76.15	OK
20147	2026-09-24 10:21	75.01	OK	20148	2026-09-24 10:22	74.76	OK
20149	2026-09-24 10:23	74.69	OK	20150	2026-09-24 10:24	75.06	OK
20151	2026-09-24 10:25	73.84	OK	20152	2026-09-24 10:26	74.70	OK
20153	2026-09-24 10:27	73.05	OK	20154	2026-09-24 10:28	74.54	OK
20155	2026-09-24 10:29	74.79	OK	20156	2026-09-24 10:30	71.93	OK
20157	2026-09-24 10:31	74.52	OK	20158	2026-09-24 10:32	74.24	OK
20159	2026-09-24 10:33	76.92	OK	20160	2026-09-24 10:34	74.16	OK
20161	2026-09-24 10:35	74.17	OK				

Signal: Winding_Temp_W (°C)

All 20,161 Raw Readings

Operating Limits: [10.0 to 130.0] • Observed: Min 64.87, Max 85.27, Mean 75.18

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1	2026-09-10 10:35	80.23	OK	2	2026-09-10 10:36	79.70	OK
3	2026-09-10 10:37	77.02	OK	4	2026-09-10 10:38	82.04	OK
5	2026-09-10 10:39	79.98	OK	6	2026-09-10 10:40	80.63	OK
7	2026-09-10 10:41	78.14	OK	8	2026-09-10 10:42	80.79	OK
9	2026-09-10 10:43	80.16	OK	10	2026-09-10 10:44	77.43	OK
11	2026-09-10 10:45	79.43	OK	12	2026-09-10 10:46	79.30	OK
13	2026-09-10 10:47	79.36	OK	14	2026-09-10 10:48	80.10	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15	2026-09-10 10:49	80.46	OK	16	2026-09-10 10:50	79.56	OK
17	2026-09-10 10:51	78.24	OK	18	2026-09-10 10:52	81.73	OK
19	2026-09-10 10:53	78.65	OK	20	2026-09-10 10:54	80.83	OK
21	2026-09-10 10:55	80.64	OK	22	2026-09-10 10:56	80.63	OK
23	2026-09-10 10:57	80.54	OK	24	2026-09-10 10:58	78.74	OK
25	2026-09-10 10:59	79.61	OK	26	2026-09-10 11:00	79.12	OK
27	2026-09-10 11:01	78.04	OK	28	2026-09-10 11:02	80.02	OK
29	2026-09-10 11:03	78.69	OK	30	2026-09-10 11:04	82.64	OK
31	2026-09-10 11:05	81.69	OK	32	2026-09-10 11:06	77.96	OK
33	2026-09-10 11:07	78.78	OK	34	2026-09-10 11:08	81.07	OK
35	2026-09-10 11:09	78.68	OK	36	2026-09-10 11:10	81.30	OK
37	2026-09-10 11:11	78.61	OK	38	2026-09-10 11:12	78.99	OK
39	2026-09-10 11:13	82.41	OK	40	2026-09-10 11:14	79.21	OK
41	2026-09-10 11:15	84.09	OK	42	2026-09-10 11:16	78.43	OK
43	2026-09-10 11:17	78.46	OK	44	2026-09-10 11:18	79.68	OK
45	2026-09-10 11:19	81.90	OK	46	2026-09-10 11:20	83.17	OK
47	2026-09-10 11:21	80.25	OK	48	2026-09-10 11:22	77.53	OK
49	2026-09-10 11:23	82.03	OK	50	2026-09-10 11:24	81.10	OK
51	2026-09-10 11:25	82.74	OK	52	2026-09-10 11:26	77.76	OK
53	2026-09-10 11:27	83.36	OK	54	2026-09-10 11:28	78.94	OK
55	2026-09-10 11:29	79.02	OK	56	2026-09-10 11:30	79.87	OK
57	2026-09-10 11:31	79.69	OK	58	2026-09-10 11:32	79.37	OK
59	2026-09-10 11:33	79.08	OK	60	2026-09-10 11:34	83.19	OK
61	2026-09-10 11:35	79.45	OK	62	2026-09-10 11:36	80.63	OK
63	2026-09-10 11:37	81.54	OK	64	2026-09-10 11:38	82.98	OK
65	2026-09-10 11:39	80.19	OK	66	2026-09-10 11:40	77.77	OK
67	2026-09-10 11:41	79.23	OK	68	2026-09-10 11:42	77.71	OK
69	2026-09-10 11:43	80.41	OK	70	2026-09-10 11:44	82.82	OK
71	2026-09-10 11:45	80.27	OK	72	2026-09-10 11:46	81.05	OK
73	2026-09-10 11:47	83.33	OK	74	2026-09-10 11:48	84.28	OK
75	2026-09-10 11:49	81.64	OK	76	2026-09-10 11:50	79.95	OK
77	2026-09-10 11:51	78.92	OK	78	2026-09-10 11:52	82.99	OK
79	2026-09-10 11:53	79.12	OK	80	2026-09-10 11:54	78.81	OK
81	2026-09-10 11:55	83.83	OK	82	2026-09-10 11:56	82.53	OK
83	2026-09-10 11:57	81.14	OK	84	2026-09-10 11:58	77.82	OK
85	2026-09-10 11:59	84.14	OK	86	2026-09-10 12:00	83.31	OK
87	2026-09-10 12:01	77.85	OK	88	2026-09-10 12:02	77.91	OK
89	2026-09-10 12:03	79.42	OK	90	2026-09-10 12:04	79.36	OK
91	2026-09-10 12:05	82.86	OK	92	2026-09-10 12:06	83.28	OK
93	2026-09-10 12:07	81.03	OK	94	2026-09-10 12:08	81.44	OK
95	2026-09-10 12:09	80.85	OK	96	2026-09-10 12:10	84.09	OK
97	2026-09-10 12:11	81.92	OK	98	2026-09-10 12:12	80.15	OK
99	2026-09-10 12:13	81.94	OK	100	2026-09-10 12:14	82.13	OK
101	2026-09-10 12:15	81.38	OK	102	2026-09-10 12:16	79.57	OK
103	2026-09-10 12:17	79.15	OK	104	2026-09-10 12:18	77.61	OK
105	2026-09-10 12:19	82.22	OK	106	2026-09-10 12:20	80.91	OK
107	2026-09-10 12:21	82.71	OK	108	2026-09-10 12:22	82.54	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
109	2026-09-10 12:23	81.42	OK	110	2026-09-10 12:24	81.82	OK
111	2026-09-10 12:25	78.42	OK	112	2026-09-10 12:26	82.97	OK
113	2026-09-10 12:27	80.92	OK	114	2026-09-10 12:28	80.34	OK
115	2026-09-10 12:29	79.41	OK	116	2026-09-10 12:30	80.00	OK
117	2026-09-10 12:31	79.81	OK	118	2026-09-10 12:32	79.40	OK
119	2026-09-10 12:33	79.74	OK	120	2026-09-10 12:34	82.97	OK
121	2026-09-10 12:35	78.39	OK	122	2026-09-10 12:36	84.19	OK
123	2026-09-10 12:37	82.66	OK	124	2026-09-10 12:38	80.91	OK
125	2026-09-10 12:39	80.22	OK	126	2026-09-10 12:40	83.33	OK
127	2026-09-10 12:41	81.04	OK	128	2026-09-10 12:42	79.48	OK
129	2026-09-10 12:43	79.08	OK	130	2026-09-10 12:44	80.07	OK
131	2026-09-10 12:45	79.71	OK	132	2026-09-10 12:46	80.85	OK
133	2026-09-10 12:47	80.21	OK	134	2026-09-10 12:48	81.66	OK
135	2026-09-10 12:49	80.38	OK	136	2026-09-10 12:50	82.11	OK
137	2026-09-10 12:51	82.63	OK	138	2026-09-10 12:52	81.90	OK
139	2026-09-10 12:53	81.78	OK	140	2026-09-10 12:54	80.64	OK
141	2026-09-10 12:55	77.04	OK	142	2026-09-10 12:56	81.44	OK
143	2026-09-10 12:57	82.47	OK	144	2026-09-10 12:58	80.94	OK
145	2026-09-10 12:59	79.22	OK	146	2026-09-10 13:00	79.40	OK
147	2026-09-10 13:01	80.69	OK	148	2026-09-10 13:02	80.77	OK
149	2026-09-10 13:03	83.34	OK	150	2026-09-10 13:04	79.52	OK
151	2026-09-10 13:05	79.44	OK	152	2026-09-10 13:06	81.62	OK
153	2026-09-10 13:07	84.42	OK	154	2026-09-10 13:08	80.21	OK
155	2026-09-10 13:09	79.60	OK	156	2026-09-10 13:10	84.04	OK
157	2026-09-10 13:11	79.99	OK	158	2026-09-10 13:12	82.80	OK
159	2026-09-10 13:13	83.94	OK	160	2026-09-10 13:14	82.14	OK
161	2026-09-10 13:15	81.08	OK	162	2026-09-10 13:16	81.18	OK
163	2026-09-10 13:17	82.01	OK	164	2026-09-10 13:18	79.28	OK
165	2026-09-10 13:19	81.20	OK	166	2026-09-10 13:20	77.65	OK
167	2026-09-10 13:21	80.00	OK	168	2026-09-10 13:22	79.39	OK
169	2026-09-10 13:23	80.08	OK	170	2026-09-10 13:24	81.98	OK
171	2026-09-10 13:25	81.87	OK	172	2026-09-10 13:26	83.14	OK
173	2026-09-10 13:27	81.33	OK	174	2026-09-10 13:28	80.69	OK
175	2026-09-10 13:29	81.61	OK	176	2026-09-10 13:30	78.19	OK
177	2026-09-10 13:31	79.41	OK	178	2026-09-10 13:32	83.31	OK
179	2026-09-10 13:33	82.74	OK	180	2026-09-10 13:34	81.90	OK
181	2026-09-10 13:35	80.97	OK	182	2026-09-10 13:36	82.24	OK
183	2026-09-10 13:37	81.52	OK	184	2026-09-10 13:38	80.47	OK
185	2026-09-10 13:39	83.03	OK	186	2026-09-10 13:40	81.17	OK
187	2026-09-10 13:41	80.93	OK	188	2026-09-10 13:42	80.26	OK
189	2026-09-10 13:43	78.06	OK	190	2026-09-10 13:44	82.74	OK
191	2026-09-10 13:45	79.95	OK	192	2026-09-10 13:46	79.35	OK
193	2026-09-10 13:47	81.81	OK	194	2026-09-10 13:48	78.48	OK
195	2026-09-10 13:49	79.17	OK	196	2026-09-10 13:50	82.35	OK
197	2026-09-10 13:51	81.14	OK	198	2026-09-10 13:52	82.24	OK
199	2026-09-10 13:53	81.22	OK	200	2026-09-10 13:54	80.96	OK
201	2026-09-10 13:55	83.45	OK	202	2026-09-10 13:56	80.23	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
203	2026-09-10 13:57	78.67	OK	204	2026-09-10 13:58	80.58	OK
205	2026-09-10 13:59	80.25	OK	206	2026-09-10 14:00	77.83	OK
207	2026-09-10 14:01	80.94	OK	208	2026-09-10 14:02	81.28	OK
209	2026-09-10 14:03	82.35	OK	210	2026-09-10 14:04	80.64	OK
211	2026-09-10 14:05	78.58	OK	212	2026-09-10 14:06	81.62	OK
213	2026-09-10 14:07	81.65	OK	214	2026-09-10 14:08	79.33	OK
215	2026-09-10 14:09	82.10	OK	216	2026-09-10 14:10	80.51	OK
217	2026-09-10 14:11	80.16	OK	218	2026-09-10 14:12	79.88	OK
219	2026-09-10 14:13	82.01	OK	220	2026-09-10 14:14	82.37	OK
221	2026-09-10 14:15	81.01	OK	222	2026-09-10 14:16	83.26	OK
223	2026-09-10 14:17	80.30	OK	224	2026-09-10 14:18	78.61	OK
225	2026-09-10 14:19	77.03	OK	226	2026-09-10 14:20	81.37	OK
227	2026-09-10 14:21	81.62	OK	228	2026-09-10 14:22	81.39	OK
229	2026-09-10 14:23	79.09	OK	230	2026-09-10 14:24	81.55	OK
231	2026-09-10 14:25	81.03	OK	232	2026-09-10 14:26	82.15	OK
233	2026-09-10 14:27	82.25	OK	234	2026-09-10 14:28	81.23	OK
235	2026-09-10 14:29	80.30	OK	236	2026-09-10 14:30	77.48	OK
237	2026-09-10 14:31	81.81	OK	238	2026-09-10 14:32	78.41	OK
239	2026-09-10 14:33	81.87	OK	240	2026-09-10 14:34	79.70	OK
241	2026-09-10 14:35	80.33	OK	242	2026-09-10 14:36	80.46	OK
243	2026-09-10 14:37	77.26	OK	244	2026-09-10 14:38	82.27	OK
245	2026-09-10 14:39	79.84	OK	246	2026-09-10 14:40	80.99	OK
247	2026-09-10 14:41	80.76	OK	248	2026-09-10 14:42	80.01	OK
249	2026-09-10 14:43	79.41	OK	250	2026-09-10 14:44	77.63	OK
251	2026-09-10 14:45	80.87	OK	252	2026-09-10 14:46	78.33	OK
253	2026-09-10 14:47	80.86	OK	254	2026-09-10 14:48	76.65	OK
255	2026-09-10 14:49	83.14	OK	256	2026-09-10 14:50	77.02	OK
257	2026-09-10 14:51	82.17	OK	258	2026-09-10 14:52	81.13	OK
259	2026-09-10 14:53	82.33	OK	260	2026-09-10 14:54	79.73	OK
261	2026-09-10 14:55	79.45	OK	262	2026-09-10 14:56	81.53	OK
263	2026-09-10 14:57	82.35	OK	264	2026-09-10 14:58	83.23	OK
265	2026-09-10 14:59	80.56	OK	266	2026-09-10 15:00	77.02	OK
267	2026-09-10 15:01	84.31	OK	268	2026-09-10 15:02	80.38	OK
269	2026-09-10 15:03	82.62	OK	270	2026-09-10 15:04	78.23	OK
271	2026-09-10 15:05	79.10	OK	272	2026-09-10 15:06	79.99	OK
273	2026-09-10 15:07	77.36	OK	274	2026-09-10 15:08	81.86	OK
275	2026-09-10 15:09	76.80	OK	276	2026-09-10 15:10	82.32	OK
277	2026-09-10 15:11	80.48	OK	278	2026-09-10 15:12	77.52	OK
279	2026-09-10 15:13	80.68	OK	280	2026-09-10 15:14	79.52	OK
281	2026-09-10 15:15	81.77	OK	282	2026-09-10 15:16	82.53	OK
283	2026-09-10 15:17	81.62	OK	284	2026-09-10 15:18	81.75	OK
285	2026-09-10 15:19	77.97	OK	286	2026-09-10 15:20	79.00	OK
287	2026-09-10 15:21	77.98	OK	288	2026-09-10 15:22	81.20	OK
289	2026-09-10 15:23	77.99	OK	290	2026-09-10 15:24	81.16	OK
291	2026-09-10 15:25	79.72	OK	292	2026-09-10 15:26	81.14	OK
293	2026-09-10 15:27	78.83	OK	294	2026-09-10 15:28	80.21	OK
295	2026-09-10 15:29	78.80	OK	296	2026-09-10 15:30	79.08	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
297	2026-09-10 15:31	78.43	OK	298	2026-09-10 15:32	79.02	OK
299	2026-09-10 15:33	80.73	OK	300	2026-09-10 15:34	81.10	OK
301	2026-09-10 15:35	79.87	OK	302	2026-09-10 15:36	81.08	OK
303	2026-09-10 15:37	78.85	OK	304	2026-09-10 15:38	79.54	OK
305	2026-09-10 15:39	80.31	OK	306	2026-09-10 15:40	79.84	OK
307	2026-09-10 15:41	78.35	OK	308	2026-09-10 15:42	80.02	OK
309	2026-09-10 15:43	76.86	OK	310	2026-09-10 15:44	82.31	OK
311	2026-09-10 15:45	79.92	OK	312	2026-09-10 15:46	81.26	OK
313	2026-09-10 15:47	80.52	OK	314	2026-09-10 15:48	80.36	OK
315	2026-09-10 15:49	79.64	OK	316	2026-09-10 15:50	79.21	OK
317	2026-09-10 15:51	80.39	OK	318	2026-09-10 15:52	79.54	OK
319	2026-09-10 15:53	77.86	OK	320	2026-09-10 15:54	76.86	OK
321	2026-09-10 15:55	81.76	OK	322	2026-09-10 15:56	79.22	OK
323	2026-09-10 15:57	78.02	OK	324	2026-09-10 15:58	78.42	OK
325	2026-09-10 15:59	78.58	OK	326	2026-09-10 16:00	79.49	OK
327	2026-09-10 16:01	78.59	OK	328	2026-09-10 16:02	80.00	OK
329	2026-09-10 16:03	77.07	OK	330	2026-09-10 16:04	79.75	OK
331	2026-09-10 16:05	79.11	OK	332	2026-09-10 16:06	77.11	OK
333	2026-09-10 16:07	79.11	OK	334	2026-09-10 16:08	78.66	OK
335	2026-09-10 16:09	79.74	OK	336	2026-09-10 16:10	80.96	OK
337	2026-09-10 16:11	79.70	OK	338	2026-09-10 16:12	79.37	OK
339	2026-09-10 16:13	75.86	OK	340	2026-09-10 16:14	77.79	OK
341	2026-09-10 16:15	78.81	OK	342	2026-09-10 16:16	79.16	OK
343	2026-09-10 16:17	79.64	OK	344	2026-09-10 16:18	78.56	OK
345	2026-09-10 16:19	80.49	OK	346	2026-09-10 16:20	80.21	OK
347	2026-09-10 16:21	78.21	OK	348	2026-09-10 16:22	82.22	OK
349	2026-09-10 16:23	75.82	OK	350	2026-09-10 16:24	77.92	OK
351	2026-09-10 16:25	82.62	OK	352	2026-09-10 16:26	79.02	OK
353	2026-09-10 16:27	80.57	OK	354	2026-09-10 16:28	78.21	OK
355	2026-09-10 16:29	77.23	OK	356	2026-09-10 16:30	81.23	OK
357	2026-09-10 16:31	75.22	OK	358	2026-09-10 16:32	76.77	OK
359	2026-09-10 16:33	80.28	OK	360	2026-09-10 16:34	76.29	OK
361	2026-09-10 16:35	78.71	OK	362	2026-09-10 16:36	77.64	OK
363	2026-09-10 16:37	79.36	OK	364	2026-09-10 16:38	77.17	OK
365	2026-09-10 16:39	79.70	OK	366	2026-09-10 16:40	78.30	OK
367	2026-09-10 16:41	80.67	OK	368	2026-09-10 16:42	77.38	OK
369	2026-09-10 16:43	78.55	OK	370	2026-09-10 16:44	79.33	OK
371	2026-09-10 16:45	81.61	OK	372	2026-09-10 16:46	79.06	OK
373	2026-09-10 16:47	77.34	OK	374	2026-09-10 16:48	80.04	OK
375	2026-09-10 16:49	77.16	OK	376	2026-09-10 16:50	75.41	OK
377	2026-09-10 16:51	78.89	OK	378	2026-09-10 16:52	77.26	OK
379	2026-09-10 16:53	77.54	OK	380	2026-09-10 16:54	77.62	OK
381	2026-09-10 16:55	78.75	OK	382	2026-09-10 16:56	78.11	OK
383	2026-09-10 16:57	79.20	OK	384	2026-09-10 16:58	79.33	OK
385	2026-09-10 16:59	78.01	OK	386	2026-09-10 17:00	79.99	OK
387	2026-09-10 17:01	78.55	OK	388	2026-09-10 17:02	75.38	OK
389	2026-09-10 17:03	79.15	OK	390	2026-09-10 17:04	76.72	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
391	2026-09-10 17:05	80.06	OK	392	2026-09-10 17:06	76.35	OK
393	2026-09-10 17:07	77.12	OK	394	2026-09-10 17:08	76.30	OK
395	2026-09-10 17:09	79.23	OK	396	2026-09-10 17:10	79.96	OK
397	2026-09-10 17:11	78.93	OK	398	2026-09-10 17:12	74.07	OK
399	2026-09-10 17:13	78.85	OK	400	2026-09-10 17:14	80.29	OK
401	2026-09-10 17:15	75.01	OK	402	2026-09-10 17:16	78.51	OK
403	2026-09-10 17:17	76.56	OK	404	2026-09-10 17:18	76.01	OK
405	2026-09-10 17:19	77.33	OK	406	2026-09-10 17:20	76.31	OK
407	2026-09-10 17:21	78.22	OK	408	2026-09-10 17:22	75.61	OK
409	2026-09-10 17:23	77.33	OK	410	2026-09-10 17:24	78.97	OK
411	2026-09-10 17:25	77.70	OK	412	2026-09-10 17:26	81.15	OK
413	2026-09-10 17:27	79.84	OK	414	2026-09-10 17:28	77.83	OK
415	2026-09-10 17:29	75.33	OK	416	2026-09-10 17:30	78.06	OK
417	2026-09-10 17:31	76.37	OK	418	2026-09-10 17:32	80.11	OK
419	2026-09-10 17:33	77.85	OK	420	2026-09-10 17:34	79.08	OK
421	2026-09-10 17:35	73.42	OK	422	2026-09-10 17:36	77.04	OK
423	2026-09-10 17:37	78.07	OK	424	2026-09-10 17:38	74.07	OK
425	2026-09-10 17:39	76.24	OK	426	2026-09-10 17:40	76.10	OK
427	2026-09-10 17:41	74.98	OK	428	2026-09-10 17:42	76.79	OK
429	2026-09-10 17:43	77.44	OK	430	2026-09-10 17:44	74.92	OK
431	2026-09-10 17:45	79.08	OK	432	2026-09-10 17:46	78.31	OK
433	2026-09-10 17:47	78.85	OK	434	2026-09-10 17:48	75.41	OK
435	2026-09-10 17:49	78.09	OK	436	2026-09-10 17:50	80.20	OK
437	2026-09-10 17:51	75.67	OK	438	2026-09-10 17:52	74.76	OK
439	2026-09-10 17:53	76.86	OK	440	2026-09-10 17:54	76.44	OK
441	2026-09-10 17:55	77.68	OK	442	2026-09-10 17:56	75.16	OK
443	2026-09-10 17:57	75.00	OK	444	2026-09-10 17:58	77.75	OK
445	2026-09-10 17:59	77.51	OK	446	2026-09-10 18:00	76.50	OK
447	2026-09-10 18:01	77.47	OK	448	2026-09-10 18:02	79.29	OK
449	2026-09-10 18:03	77.08	OK	450	2026-09-10 18:04	75.38	OK
451	2026-09-10 18:05	77.22	OK	452	2026-09-10 18:06	75.21	OK
453	2026-09-10 18:07	76.15	OK	454	2026-09-10 18:08	74.66	OK
455	2026-09-10 18:09	75.12	OK	456	2026-09-10 18:10	76.98	OK
457	2026-09-10 18:11	75.29	OK	458	2026-09-10 18:12	74.98	OK
459	2026-09-10 18:13	73.85	OK	460	2026-09-10 18:14	74.71	OK
461	2026-09-10 18:15	72.98	OK	462	2026-09-10 18:16	75.93	OK
463	2026-09-10 18:17	75.75	OK	464	2026-09-10 18:18	76.46	OK
465	2026-09-10 18:19	75.53	OK	466	2026-09-10 18:20	77.47	OK
467	2026-09-10 18:21	77.83	OK	468	2026-09-10 18:22	74.51	OK
469	2026-09-10 18:23	74.23	OK	470	2026-09-10 18:24	77.74	OK
471	2026-09-10 18:25	76.60	OK	472	2026-09-10 18:26	77.17	OK
473	2026-09-10 18:27	76.25	OK	474	2026-09-10 18:28	78.16	OK
475	2026-09-10 18:29	78.69	OK	476	2026-09-10 18:30	73.71	OK
477	2026-09-10 18:31	77.01	OK	478	2026-09-10 18:32	73.02	OK
479	2026-09-10 18:33	77.28	OK	480	2026-09-10 18:34	77.58	OK
481	2026-09-10 18:35	74.45	OK	482	2026-09-10 18:36	74.46	OK
483	2026-09-10 18:37	78.09	OK	484	2026-09-10 18:38	77.35	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
485	2026-09-10 18:39	75.42	OK	486	2026-09-10 18:40	75.90	OK
487	2026-09-10 18:41	74.37	OK	488	2026-09-10 18:42	75.15	OK
489	2026-09-10 18:43	74.02	OK	490	2026-09-10 18:44	77.16	OK
491	2026-09-10 18:45	75.95	OK	492	2026-09-10 18:46	74.01	OK
493	2026-09-10 18:47	76.64	OK	494	2026-09-10 18:48	77.76	OK
495	2026-09-10 18:49	76.04	OK	496	2026-09-10 18:50	78.73	OK
497	2026-09-10 18:51	73.78	OK	498	2026-09-10 18:52	75.20	OK
499	2026-09-10 18:53	76.93	OK	500	2026-09-10 18:54	75.61	OK
501	2026-09-10 18:55	73.42	OK	502	2026-09-10 18:56	72.70	OK
503	2026-09-10 18:57	74.92	OK	504	2026-09-10 18:58	74.36	OK
505	2026-09-10 18:59	75.15	OK	506	2026-09-10 19:00	76.33	OK
507	2026-09-10 19:01	76.19	OK	508	2026-09-10 19:02	74.96	OK
509	2026-09-10 19:03	77.81	OK	510	2026-09-10 19:04	73.87	OK
511	2026-09-10 19:05	74.24	OK	512	2026-09-10 19:06	73.32	OK
513	2026-09-10 19:07	75.87	OK	514	2026-09-10 19:08	73.67	OK
515	2026-09-10 19:09	75.02	OK	516	2026-09-10 19:10	72.42	OK
517	2026-09-10 19:11	74.45	OK	518	2026-09-10 19:12	74.23	OK
519	2026-09-10 19:13	75.23	OK	520	2026-09-10 19:14	74.45	OK
521	2026-09-10 19:15	74.39	OK	522	2026-09-10 19:16	71.52	OK
523	2026-09-10 19:17	75.13	OK	524	2026-09-10 19:18	72.90	OK
525	2026-09-10 19:19	73.27	OK	526	2026-09-10 19:20	73.21	OK
527	2026-09-10 19:21	72.23	OK	528	2026-09-10 19:22	73.52	OK
529	2026-09-10 19:23	74.65	OK	530	2026-09-10 19:24	73.62	OK
531	2026-09-10 19:25	74.11	OK	532	2026-09-10 19:26	74.09	OK
533	2026-09-10 19:27	76.27	OK	534	2026-09-10 19:28	78.47	OK
535	2026-09-10 19:29	74.06	OK	536	2026-09-10 19:30	74.55	OK
537	2026-09-10 19:31	72.15	OK	538	2026-09-10 19:32	74.15	OK
539	2026-09-10 19:33	76.71	OK	540	2026-09-10 19:34	73.17	OK
541	2026-09-10 19:35	71.82	OK	542	2026-09-10 19:36	75.08	OK
543	2026-09-10 19:37	74.56	OK	544	2026-09-10 19:38	75.61	OK
545	2026-09-10 19:39	74.08	OK	546	2026-09-10 19:40	74.48	OK
547	2026-09-10 19:41	73.95	OK	548	2026-09-10 19:42	73.49	OK
549	2026-09-10 19:43	74.39	OK	550	2026-09-10 19:44	73.10	OK
551	2026-09-10 19:45	74.59	OK	552	2026-09-10 19:46	75.16	OK
553	2026-09-10 19:47	71.71	OK	554	2026-09-10 19:48	72.72	OK
555	2026-09-10 19:49	74.11	OK	556	2026-09-10 19:50	75.45	OK
557	2026-09-10 19:51	76.74	OK	558	2026-09-10 19:52	73.12	OK
559	2026-09-10 19:53	72.02	OK	560	2026-09-10 19:54	75.00	OK
561	2026-09-10 19:55	74.54	OK	562	2026-09-10 19:56	72.56	OK
563	2026-09-10 19:57	72.81	OK	564	2026-09-10 19:58	73.58	OK
565	2026-09-10 19:59	73.00	OK	566	2026-09-10 20:00	74.15	OK
567	2026-09-10 20:01	73.71	OK	568	2026-09-10 20:02	77.11	OK
569	2026-09-10 20:03	72.65	OK	570	2026-09-10 20:04	73.23	OK
571	2026-09-10 20:05	70.51	OK	572	2026-09-10 20:06	72.46	OK
573	2026-09-10 20:07	71.82	OK	574	2026-09-10 20:08	71.49	OK
575	2026-09-10 20:09	75.19	OK	576	2026-09-10 20:10	74.91	OK
577	2026-09-10 20:11	72.15	OK	578	2026-09-10 20:12	76.66	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
579	2026-09-10 20:13	72.36	OK	580	2026-09-10 20:14	69.74	OK
581	2026-09-10 20:15	73.91	OK	582	2026-09-10 20:16	74.54	OK
583	2026-09-10 20:17	70.60	OK	584	2026-09-10 20:18	71.74	OK
585	2026-09-10 20:19	74.20	OK	586	2026-09-10 20:20	73.95	OK
587	2026-09-10 20:21	72.64	OK	588	2026-09-10 20:22	71.62	OK
589	2026-09-10 20:23	72.95	OK	590	2026-09-10 20:24	70.82	OK
591	2026-09-10 20:25	70.83	OK	592	2026-09-10 20:26	71.43	OK
593	2026-09-10 20:27	75.99	OK	594	2026-09-10 20:28	71.36	OK
595	2026-09-10 20:29	70.86	OK	596	2026-09-10 20:30	73.81	OK
597	2026-09-10 20:31	74.19	OK	598	2026-09-10 20:32	73.14	OK
599	2026-09-10 20:33	74.50	OK	600	2026-09-10 20:34	71.62	OK
601	2026-09-10 20:35	72.17	OK	602	2026-09-10 20:36	75.64	OK
603	2026-09-10 20:37	73.54	OK	604	2026-09-10 20:38	72.54	OK
605	2026-09-10 20:39	72.65	OK	606	2026-09-10 20:40	71.31	OK
607	2026-09-10 20:41	75.77	OK	608	2026-09-10 20:42	74.91	OK
609	2026-09-10 20:43	71.37	OK	610	2026-09-10 20:44	73.21	OK
611	2026-09-10 20:45	72.30	OK	612	2026-09-10 20:46	74.73	OK
613	2026-09-10 20:47	71.17	OK	614	2026-09-10 20:48	70.51	OK
615	2026-09-10 20:49	68.47	OK	616	2026-09-10 20:50	70.55	OK
617	2026-09-10 20:51	72.94	OK	618	2026-09-10 20:52	72.59	OK
619	2026-09-10 20:53	72.84	OK	620	2026-09-10 20:54	70.79	OK
621	2026-09-10 20:55	71.00	OK	622	2026-09-10 20:56	72.50	OK
623	2026-09-10 20:57	73.63	OK	624	2026-09-10 20:58	71.97	OK
625	2026-09-10 20:59	73.10	OK	626	2026-09-10 21:00	70.82	OK
627	2026-09-10 21:01	71.50	OK	628	2026-09-10 21:02	71.63	OK
629	2026-09-10 21:03	74.36	OK	630	2026-09-10 21:04	70.96	OK
631	2026-09-10 21:05	71.62	OK	632	2026-09-10 21:06	72.55	OK
633	2026-09-10 21:07	71.35	OK	634	2026-09-10 21:08	71.35	OK
635	2026-09-10 21:09	71.29	OK	636	2026-09-10 21:10	72.65	OK
637	2026-09-10 21:11	71.12	OK	638	2026-09-10 21:12	71.89	OK
639	2026-09-10 21:13	70.66	OK	640	2026-09-10 21:14	69.93	OK
641	2026-09-10 21:15	69.15	OK	642	2026-09-10 21:16	70.29	OK
643	2026-09-10 21:17	69.24	OK	644	2026-09-10 21:18	74.32	OK
645	2026-09-10 21:19	71.26	OK	646	2026-09-10 21:20	70.61	OK
647	2026-09-10 21:21	70.35	OK	648	2026-09-10 21:22	72.71	OK
649	2026-09-10 21:23	70.60	OK	650	2026-09-10 21:24	72.98	OK
651	2026-09-10 21:25	72.87	OK	652	2026-09-10 21:26	70.86	OK
653	2026-09-10 21:27	73.33	OK	654	2026-09-10 21:28	70.86	OK
655	2026-09-10 21:29	72.54	OK	656	2026-09-10 21:30	73.09	OK
657	2026-09-10 21:31	71.28	OK	658	2026-09-10 21:32	71.54	OK
659	2026-09-10 21:33	71.15	OK	660	2026-09-10 21:34	71.47	OK
661	2026-09-10 21:35	72.51	OK	662	2026-09-10 21:36	69.58	OK
663	2026-09-10 21:37	68.50	OK	664	2026-09-10 21:38	72.70	OK
665	2026-09-10 21:39	71.09	OK	666	2026-09-10 21:40	71.60	OK
667	2026-09-10 21:41	70.09	OK	668	2026-09-10 21:42	72.50	OK
669	2026-09-10 21:43	68.17	OK	670	2026-09-10 21:44	71.79	OK
671	2026-09-10 21:45	73.24	OK	672	2026-09-10 21:46	72.43	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
673	2026-09-10 21:47	70.67	OK	674	2026-09-10 21:48	69.39	OK
675	2026-09-10 21:49	72.47	OK	676	2026-09-10 21:50	73.21	OK
677	2026-09-10 21:51	72.05	OK	678	2026-09-10 21:52	71.13	OK
679	2026-09-10 21:53	72.72	OK	680	2026-09-10 21:54	68.75	OK
681	2026-09-10 21:55	68.47	OK	682	2026-09-10 21:56	69.67	OK
683	2026-09-10 21:57	73.32	OK	684	2026-09-10 21:58	70.76	OK
685	2026-09-10 21:59	69.56	OK	686	2026-09-10 22:00	70.50	OK
687	2026-09-10 22:01	71.70	OK	688	2026-09-10 22:02	71.97	OK
689	2026-09-10 22:03	70.09	OK	690	2026-09-10 22:04	74.81	OK
691	2026-09-10 22:05	73.82	OK	692	2026-09-10 22:06	69.08	OK
693	2026-09-10 22:07	73.11	OK	694	2026-09-10 22:08	75.05	OK
695	2026-09-10 22:09	72.64	OK	696	2026-09-10 22:10	69.14	OK
697	2026-09-10 22:11	71.78	OK	698	2026-09-10 22:12	70.29	OK
699	2026-09-10 22:13	72.53	OK	700	2026-09-10 22:14	71.82	OK
701	2026-09-10 22:15	68.38	OK	702	2026-09-10 22:16	70.30	OK
703	2026-09-10 22:17	68.78	OK	704	2026-09-10 22:18	69.06	OK
705	2026-09-10 22:19	70.65	OK	706	2026-09-10 22:20	69.39	OK
707	2026-09-10 22:21	74.78	OK	708	2026-09-10 22:22	68.42	OK
709	2026-09-10 22:23	70.94	OK	710	2026-09-10 22:24	71.64	OK
711	2026-09-10 22:25	70.31	OK	712	2026-09-10 22:26	71.40	OK
713	2026-09-10 22:27	68.92	OK	714	2026-09-10 22:28	73.14	OK
715	2026-09-10 22:29	65.94	OK	716	2026-09-10 22:30	71.29	OK
717	2026-09-10 22:31	69.16	OK	718	2026-09-10 22:32	71.52	OK
719	2026-09-10 22:33	69.51	OK	720	2026-09-10 22:34	69.77	OK
721	2026-09-10 22:35	68.02	OK	722	2026-09-10 22:36	71.41	OK
723	2026-09-10 22:37	71.52	OK	724	2026-09-10 22:38	71.01	OK
725	2026-09-10 22:39	71.67	OK	726	2026-09-10 22:40	72.85	OK
727	2026-09-10 22:41	69.65	OK	728	2026-09-10 22:42	68.16	OK
729	2026-09-10 22:43	71.19	OK	730	2026-09-10 22:44	71.35	OK
731	2026-09-10 22:45	69.51	OK	732	2026-09-10 22:46	70.19	OK
733	2026-09-10 22:47	72.30	OK	734	2026-09-10 22:48	72.42	OK
735	2026-09-10 22:49	69.10	OK	736	2026-09-10 22:50	72.90	OK
737	2026-09-10 22:51	70.05	OK	738	2026-09-10 22:52	69.99	OK
739	2026-09-10 22:53	70.22	OK	740	2026-09-10 22:54	68.80	OK
741	2026-09-10 22:55	70.66	OK	742	2026-09-10 22:56	69.01	OK
743	2026-09-10 22:57	70.39	OK	744	2026-09-10 22:58	70.32	OK
745	2026-09-10 22:59	69.29	OK	746	2026-09-10 23:00	68.57	OK
747	2026-09-10 23:01	68.63	OK	748	2026-09-10 23:02	70.84	OK
749	2026-09-10 23:03	71.59	OK	750	2026-09-10 23:04	72.36	OK
751	2026-09-10 23:05	72.09	OK	752	2026-09-10 23:06	71.43	OK
753	2026-09-10 23:07	68.46	OK	754	2026-09-10 23:08	68.40	OK
755	2026-09-10 23:09	70.67	OK	756	2026-09-10 23:10	70.74	OK
757	2026-09-10 23:11	68.23	OK	758	2026-09-10 23:12	69.15	OK
759	2026-09-10 23:13	68.33	OK	760	2026-09-10 23:14	70.09	OK
761	2026-09-10 23:15	69.90	OK	762	2026-09-10 23:16	69.55	OK
763	2026-09-10 23:17	69.89	OK	764	2026-09-10 23:18	71.95	OK
765	2026-09-10 23:19	71.86	OK	766	2026-09-10 23:20	69.05	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
767	2026-09-10 23:21	73.16	OK	768	2026-09-10 23:22	70.33	OK
769	2026-09-10 23:23	68.30	OK	770	2026-09-10 23:24	69.54	OK
771	2026-09-10 23:25	70.70	OK	772	2026-09-10 23:26	70.43	OK
773	2026-09-10 23:27	71.59	OK	774	2026-09-10 23:28	66.84	OK
775	2026-09-10 23:29	67.09	OK	776	2026-09-10 23:30	73.21	OK
777	2026-09-10 23:31	72.82	OK	778	2026-09-10 23:32	69.43	OK
779	2026-09-10 23:33	70.82	OK	780	2026-09-10 23:34	70.28	OK
781	2026-09-10 23:35	67.81	OK	782	2026-09-10 23:36	70.95	OK
783	2026-09-10 23:37	70.60	OK	784	2026-09-10 23:38	66.80	OK
785	2026-09-10 23:39	69.97	OK	786	2026-09-10 23:40	70.02	OK
787	2026-09-10 23:41	68.55	OK	788	2026-09-10 23:42	70.12	OK
789	2026-09-10 23:43	71.14	OK	790	2026-09-10 23:44	71.50	OK
791	2026-09-10 23:45	69.49	OK	792	2026-09-10 23:46	66.84	OK
793	2026-09-10 23:47	70.17	OK	794	2026-09-10 23:48	69.94	OK
795	2026-09-10 23:49	68.42	OK	796	2026-09-10 23:50	72.26	OK
797	2026-09-10 23:51	70.10	OK	798	2026-09-10 23:52	71.53	OK
799	2026-09-10 23:53	67.83	OK	800	2026-09-10 23:54	70.72	OK
801	2026-09-10 23:55	71.57	OK	802	2026-09-10 23:56	67.59	OK
803	2026-09-10 23:57	70.90	OK	804	2026-09-10 23:58	69.39	OK
805	2026-09-10 23:59	69.57	OK	806	2026-09-11 00:00	66.58	OK
807	2026-09-11 00:01	70.31	OK	808	2026-09-11 00:02	72.81	OK
809	2026-09-11 00:03	70.06	OK	810	2026-09-11 00:04	69.28	OK
811	2026-09-11 00:05	71.27	OK	812	2026-09-11 00:06	71.04	OK
813	2026-09-11 00:07	68.94	OK	814	2026-09-11 00:08	68.14	OK
815	2026-09-11 00:09	70.15	OK	816	2026-09-11 00:10	68.95	OK
817	2026-09-11 00:11	70.74	OK	818	2026-09-11 00:12	72.27	OK
819	2026-09-11 00:13	68.12	OK	820	2026-09-11 00:14	68.72	OK
821	2026-09-11 00:15	69.41	OK	822	2026-09-11 00:16	71.36	OK
823	2026-09-11 00:17	69.64	OK	824	2026-09-11 00:18	67.13	OK
825	2026-09-11 00:19	69.42	OK	826	2026-09-11 00:20	70.40	OK
827	2026-09-11 00:21	68.03	OK	828	2026-09-11 00:22	70.94	OK
829	2026-09-11 00:23	68.68	OK	830	2026-09-11 00:24	67.51	OK
831	2026-09-11 00:25	68.10	OK	832	2026-09-11 00:26	71.03	OK
833	2026-09-11 00:27	68.54	OK	834	2026-09-11 00:28	70.17	OK
835	2026-09-11 00:29	71.83	OK	836	2026-09-11 00:30	69.29	OK
837	2026-09-11 00:31	68.51	OK	838	2026-09-11 00:32	71.95	OK
839	2026-09-11 00:33	70.30	OK	840	2026-09-11 00:34	66.41	OK
841	2026-09-11 00:35	66.93	OK	842	2026-09-11 00:36	71.03	OK
843	2026-09-11 00:37	67.55	OK	844	2026-09-11 00:38	69.24	OK
845	2026-09-11 00:39	71.37	OK	846	2026-09-11 00:40	70.23	OK
847	2026-09-11 00:41	68.12	OK	848	2026-09-11 00:42	71.46	OK
849	2026-09-11 00:43	70.02	OK	850	2026-09-11 00:44	68.68	OK
851	2026-09-11 00:45	68.35	OK	852	2026-09-11 00:46	69.98	OK
853	2026-09-11 00:47	68.57	OK	854	2026-09-11 00:48	70.51	OK
855	2026-09-11 00:49	66.67	OK	856	2026-09-11 00:50	72.18	OK
857	2026-09-11 00:51	70.58	OK	858	2026-09-11 00:52	67.26	OK
859	2026-09-11 00:53	72.85	OK	860	2026-09-11 00:54	70.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
861	2026-09-11 00:55	65.81	OK	862	2026-09-11 00:56	68.30	OK
863	2026-09-11 00:57	70.94	OK	864	2026-09-11 00:58	69.10	OK
865	2026-09-11 00:59	70.40	OK	866	2026-09-11 01:00	70.69	OK
867	2026-09-11 01:01	70.72	OK	868	2026-09-11 01:02	67.63	OK
869	2026-09-11 01:03	68.97	OK	870	2026-09-11 01:04	67.79	OK
871	2026-09-11 01:05	67.56	OK	872	2026-09-11 01:06	69.59	OK
873	2026-09-11 01:07	72.05	OK	874	2026-09-11 01:08	69.53	OK
875	2026-09-11 01:09	68.24	OK	876	2026-09-11 01:10	67.39	OK
877	2026-09-11 01:11	69.32	OK	878	2026-09-11 01:12	70.39	OK
879	2026-09-11 01:13	69.14	OK	880	2026-09-11 01:14	70.09	OK
881	2026-09-11 01:15	68.28	OK	882	2026-09-11 01:16	68.78	OK
883	2026-09-11 01:17	69.66	OK	884	2026-09-11 01:18	70.21	OK
885	2026-09-11 01:19	69.32	OK	886	2026-09-11 01:20	67.49	OK
887	2026-09-11 01:21	68.38	OK	888	2026-09-11 01:22	69.50	OK
889	2026-09-11 01:23	70.19	OK	890	2026-09-11 01:24	68.91	OK
891	2026-09-11 01:25	70.44	OK	892	2026-09-11 01:26	69.72	OK
893	2026-09-11 01:27	67.06	OK	894	2026-09-11 01:28	69.63	OK
895	2026-09-11 01:29	68.86	OK	896	2026-09-11 01:30	69.24	OK
897	2026-09-11 01:31	70.74	OK	898	2026-09-11 01:32	68.50	OK
899	2026-09-11 01:33	70.13	OK	900	2026-09-11 01:34	73.08	OK
901	2026-09-11 01:35	70.69	OK	902	2026-09-11 01:36	67.28	OK
903	2026-09-11 01:37	67.50	OK	904	2026-09-11 01:38	69.18	OK
905	2026-09-11 01:39	70.40	OK	906	2026-09-11 01:40	70.14	OK
907	2026-09-11 01:41	68.13	OK	908	2026-09-11 01:42	72.71	OK
909	2026-09-11 01:43	71.75	OK	910	2026-09-11 01:44	67.49	OK
911	2026-09-11 01:45	66.38	OK	912	2026-09-11 01:46	69.16	OK
913	2026-09-11 01:47	71.46	OK	914	2026-09-11 01:48	68.58	OK
915	2026-09-11 01:49	69.62	OK	916	2026-09-11 01:50	70.00	OK
917	2026-09-11 01:51	68.35	OK	918	2026-09-11 01:52	68.01	OK
919	2026-09-11 01:53	72.16	OK	920	2026-09-11 01:54	69.42	OK
921	2026-09-11 01:55	71.68	OK	922	2026-09-11 01:56	71.22	OK
923	2026-09-11 01:57	68.40	OK	924	2026-09-11 01:58	66.18	OK
925	2026-09-11 01:59	67.81	OK	926	2026-09-11 02:00	71.69	OK
927	2026-09-11 02:01	71.51	OK	928	2026-09-11 02:02	72.31	OK
929	2026-09-11 02:03	71.25	OK	930	2026-09-11 02:04	68.93	OK
931	2026-09-11 02:05	70.37	OK	932	2026-09-11 02:06	70.31	OK
933	2026-09-11 02:07	69.32	OK	934	2026-09-11 02:08	67.92	OK
935	2026-09-11 02:09	67.51	OK	936	2026-09-11 02:10	71.71	OK
937	2026-09-11 02:11	68.82	OK	938	2026-09-11 02:12	68.18	OK
939	2026-09-11 02:13	72.77	OK	940	2026-09-11 02:14	71.12	OK
941	2026-09-11 02:15	69.54	OK	942	2026-09-11 02:16	70.13	OK
943	2026-09-11 02:17	69.27	OK	944	2026-09-11 02:18	69.84	OK
945	2026-09-11 02:19	70.42	OK	946	2026-09-11 02:20	71.21	OK
947	2026-09-11 02:21	71.11	OK	948	2026-09-11 02:22	69.27	OK
949	2026-09-11 02:23	69.51	OK	950	2026-09-11 02:24	72.25	OK
951	2026-09-11 02:25	69.70	OK	952	2026-09-11 02:26	68.16	OK
953	2026-09-11 02:27	68.53	OK	954	2026-09-11 02:28	69.70	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
955	2026-09-11 02:29	66.35	OK	956	2026-09-11 02:30	67.30	OK
957	2026-09-11 02:31	70.20	OK	958	2026-09-11 02:32	71.79	OK
959	2026-09-11 02:33	70.52	OK	960	2026-09-11 02:34	68.68	OK
961	2026-09-11 02:35	69.18	OK	962	2026-09-11 02:36	71.41	OK
963	2026-09-11 02:37	72.77	OK	964	2026-09-11 02:38	67.39	OK
965	2026-09-11 02:39	70.33	OK	966	2026-09-11 02:40	68.21	OK
967	2026-09-11 02:41	70.44	OK	968	2026-09-11 02:42	72.80	OK
969	2026-09-11 02:43	70.44	OK	970	2026-09-11 02:44	69.43	OK
971	2026-09-11 02:45	70.97	OK	972	2026-09-11 02:46	71.68	OK
973	2026-09-11 02:47	69.10	OK	974	2026-09-11 02:48	68.21	OK
975	2026-09-11 02:49	69.64	OK	976	2026-09-11 02:50	71.76	OK
977	2026-09-11 02:51	69.48	OK	978	2026-09-11 02:52	72.28	OK
979	2026-09-11 02:53	72.52	OK	980	2026-09-11 02:54	69.35	OK
981	2026-09-11 02:55	72.81	OK	982	2026-09-11 02:56	70.29	OK
983	2026-09-11 02:57	71.04	OK	984	2026-09-11 02:58	71.56	OK
985	2026-09-11 02:59	69.77	OK	986	2026-09-11 03:00	68.85	OK
987	2026-09-11 03:01	68.31	OK	988	2026-09-11 03:02	71.84	OK
989	2026-09-11 03:03	70.78	OK	990	2026-09-11 03:04	69.28	OK
991	2026-09-11 03:05	72.00	OK	992	2026-09-11 03:06	66.42	OK
993	2026-09-11 03:07	71.55	OK	994	2026-09-11 03:08	72.04	OK
995	2026-09-11 03:09	70.04	OK	996	2026-09-11 03:10	67.67	OK
997	2026-09-11 03:11	69.84	OK	998	2026-09-11 03:12	68.30	OK
999	2026-09-11 03:13	70.15	OK	1000	2026-09-11 03:14	70.31	OK
1001	2026-09-11 03:15	71.76	OK	1002	2026-09-11 03:16	67.14	OK
1003	2026-09-11 03:17	72.75	OK	1004	2026-09-11 03:18	71.07	OK
1005	2026-09-11 03:19	68.90	OK	1006	2026-09-11 03:20	69.78	OK
1007	2026-09-11 03:21	70.14	OK	1008	2026-09-11 03:22	71.22	OK
1009	2026-09-11 03:23	71.06	OK	1010	2026-09-11 03:24	73.83	OK
1011	2026-09-11 03:25	70.02	OK	1012	2026-09-11 03:26	71.17	OK
1013	2026-09-11 03:27	69.45	OK	1014	2026-09-11 03:28	71.03	OK
1015	2026-09-11 03:29	70.13	OK	1016	2026-09-11 03:30	69.32	OK
1017	2026-09-11 03:31	69.26	OK	1018	2026-09-11 03:32	71.17	OK
1019	2026-09-11 03:33	68.70	OK	1020	2026-09-11 03:34	69.24	OK
1021	2026-09-11 03:35	69.31	OK	1022	2026-09-11 03:36	69.24	OK
1023	2026-09-11 03:37	71.79	OK	1024	2026-09-11 03:38	70.72	OK
1025	2026-09-11 03:39	69.18	OK	1026	2026-09-11 03:40	72.54	OK
1027	2026-09-11 03:41	68.56	OK	1028	2026-09-11 03:42	68.91	OK
1029	2026-09-11 03:43	70.36	OK	1030	2026-09-11 03:44	73.74	OK
1031	2026-09-11 03:45	71.49	OK	1032	2026-09-11 03:46	71.27	OK
1033	2026-09-11 03:47	70.07	OK	1034	2026-09-11 03:48	73.00	OK
1035	2026-09-11 03:49	69.90	OK	1036	2026-09-11 03:50	68.20	OK
1037	2026-09-11 03:51	73.04	OK	1038	2026-09-11 03:52	74.28	OK
1039	2026-09-11 03:53	71.30	OK	1040	2026-09-11 03:54	70.71	OK
1041	2026-09-11 03:55	73.29	OK	1042	2026-09-11 03:56	74.39	OK
1043	2026-09-11 03:57	69.38	OK	1044	2026-09-11 03:58	72.84	OK
1045	2026-09-11 03:59	73.91	OK	1046	2026-09-11 04:00	72.39	OK
1047	2026-09-11 04:01	69.01	OK	1048	2026-09-11 04:02	74.03	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1049	2026-09-11 04:03	72.94	OK	1050	2026-09-11 04:04	71.75	OK
1051	2026-09-11 04:05	67.95	OK	1052	2026-09-11 04:06	70.54	OK
1053	2026-09-11 04:07	72.02	OK	1054	2026-09-11 04:08	73.81	OK
1055	2026-09-11 04:09	70.37	OK	1056	2026-09-11 04:10	72.72	OK
1057	2026-09-11 04:11	71.34	OK	1058	2026-09-11 04:12	70.89	OK
1059	2026-09-11 04:13	70.53	OK	1060	2026-09-11 04:14	73.16	OK
1061	2026-09-11 04:15	75.13	OK	1062	2026-09-11 04:16	69.10	OK
1063	2026-09-11 04:17	70.42	OK	1064	2026-09-11 04:18	69.35	OK
1065	2026-09-11 04:19	70.75	OK	1066	2026-09-11 04:20	70.60	OK
1067	2026-09-11 04:21	71.74	OK	1068	2026-09-11 04:22	73.63	OK
1069	2026-09-11 04:23	71.29	OK	1070	2026-09-11 04:24	70.47	OK
1071	2026-09-11 04:25	72.55	OK	1072	2026-09-11 04:26	72.12	OK
1073	2026-09-11 04:27	71.20	OK	1074	2026-09-11 04:28	72.53	OK
1075	2026-09-11 04:29	72.68	OK	1076	2026-09-11 04:30	69.86	OK
1077	2026-09-11 04:31	74.24	OK	1078	2026-09-11 04:32	69.87	OK
1079	2026-09-11 04:33	71.78	OK	1080	2026-09-11 04:34	74.27	OK
1081	2026-09-11 04:35	71.14	OK	1082	2026-09-11 04:36	70.09	OK
1083	2026-09-11 04:37	71.57	OK	1084	2026-09-11 04:38	71.22	OK
1085	2026-09-11 04:39	71.34	OK	1086	2026-09-11 04:40	72.73	OK
1087	2026-09-11 04:41	72.34	OK	1088	2026-09-11 04:42	70.15	OK
1089	2026-09-11 04:43	70.79	OK	1090	2026-09-11 04:44	70.43	OK
1091	2026-09-11 04:45	75.36	OK	1092	2026-09-11 04:46	70.23	OK
1093	2026-09-11 04:47	72.12	OK	1094	2026-09-11 04:48	71.40	OK
1095	2026-09-11 04:49	70.27	OK	1096	2026-09-11 04:50	69.38	OK
1097	2026-09-11 04:51	72.52	OK	1098	2026-09-11 04:52	74.07	OK
1099	2026-09-11 04:53	73.65	OK	1100	2026-09-11 04:54	72.78	OK
1101	2026-09-11 04:55	71.45	OK	1102	2026-09-11 04:56	72.23	OK
1103	2026-09-11 04:57	71.24	OK	1104	2026-09-11 04:58	69.02	OK
1105	2026-09-11 04:59	72.31	OK	1106	2026-09-11 05:00	74.62	OK
1107	2026-09-11 05:01	70.93	OK	1108	2026-09-11 05:02	72.31	OK
1109	2026-09-11 05:03	70.82	OK	1110	2026-09-11 05:04	75.92	OK
1111	2026-09-11 05:05	73.16	OK	1112	2026-09-11 05:06	72.20	OK
1113	2026-09-11 05:07	72.69	OK	1114	2026-09-11 05:08	68.74	OK
1115	2026-09-11 05:09	73.64	OK	1116	2026-09-11 05:10	72.21	OK
1117	2026-09-11 05:11	69.85	OK	1118	2026-09-11 05:12	70.93	OK
1119	2026-09-11 05:13	71.35	OK	1120	2026-09-11 05:14	73.39	OK
1121	2026-09-11 05:15	75.98	OK	1122	2026-09-11 05:16	70.87	OK
1123	2026-09-11 05:17	71.39	OK	1124	2026-09-11 05:18	72.63	OK
1125	2026-09-11 05:19	74.00	OK	1126	2026-09-11 05:20	70.49	OK
1127	2026-09-11 05:21	71.88	OK	1128	2026-09-11 05:22	72.62	OK
1129	2026-09-11 05:23	71.74	OK	1130	2026-09-11 05:24	70.67	OK
1131	2026-09-11 05:25	69.53	OK	1132	2026-09-11 05:26	71.83	OK
1133	2026-09-11 05:27	70.68	OK	1134	2026-09-11 05:28	74.79	OK
1135	2026-09-11 05:29	73.42	OK	1136	2026-09-11 05:30	72.85	OK
1137	2026-09-11 05:31	73.83	OK	1138	2026-09-11 05:32	75.36	OK
1139	2026-09-11 05:33	76.27	OK	1140	2026-09-11 05:34	73.20	OK
1141	2026-09-11 05:35	74.02	OK	1142	2026-09-11 05:36	72.75	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1143	2026-09-11 05:37	73.49	OK	1144	2026-09-11 05:38	71.48	OK
1145	2026-09-11 05:39	69.63	OK	1146	2026-09-11 05:40	70.64	OK
1147	2026-09-11 05:41	72.41	OK	1148	2026-09-11 05:42	72.79	OK
1149	2026-09-11 05:43	74.69	OK	1150	2026-09-11 05:44	72.71	OK
1151	2026-09-11 05:45	74.38	OK	1152	2026-09-11 05:46	73.50	OK
1153	2026-09-11 05:47	75.51	OK	1154	2026-09-11 05:48	72.41	OK
1155	2026-09-11 05:49	71.80	OK	1156	2026-09-11 05:50	72.90	OK
1157	2026-09-11 05:51	72.72	OK	1158	2026-09-11 05:52	73.78	OK
1159	2026-09-11 05:53	69.81	OK	1160	2026-09-11 05:54	71.66	OK
1161	2026-09-11 05:55	71.48	OK	1162	2026-09-11 05:56	70.24	OK
1163	2026-09-11 05:57	70.69	OK	1164	2026-09-11 05:58	74.47	OK
1165	2026-09-11 05:59	72.25	OK	1166	2026-09-11 06:00	75.53	OK
1167	2026-09-11 06:01	73.15	OK	1168	2026-09-11 06:02	72.17	OK
1169	2026-09-11 06:03	75.32	OK	1170	2026-09-11 06:04	73.59	OK
1171	2026-09-11 06:05	74.32	OK	1172	2026-09-11 06:06	74.92	OK
1173	2026-09-11 06:07	70.44	OK	1174	2026-09-11 06:08	74.75	OK
1175	2026-09-11 06:09	74.10	OK	1176	2026-09-11 06:10	72.88	OK
1177	2026-09-11 06:11	72.88	OK	1178	2026-09-11 06:12	71.96	OK
1179	2026-09-11 06:13	74.61	OK	1180	2026-09-11 06:14	74.70	OK
1181	2026-09-11 06:15	71.96	OK	1182	2026-09-11 06:16	72.07	OK
1183	2026-09-11 06:17	73.42	OK	1184	2026-09-11 06:18	74.92	OK
1185	2026-09-11 06:19	74.80	OK	1186	2026-09-11 06:20	74.59	OK
1187	2026-09-11 06:21	73.96	OK	1188	2026-09-11 06:22	77.91	OK
1189	2026-09-11 06:23	73.56	OK	1190	2026-09-11 06:24	72.00	OK
1191	2026-09-11 06:25	75.17	OK	1192	2026-09-11 06:26	71.38	OK
1193	2026-09-11 06:27	75.07	OK	1194	2026-09-11 06:28	76.58	OK
1195	2026-09-11 06:29	75.78	OK	1196	2026-09-11 06:30	74.77	OK
1197	2026-09-11 06:31	77.02	OK	1198	2026-09-11 06:32	73.48	OK
1199	2026-09-11 06:33	77.30	OK	1200	2026-09-11 06:34	77.01	OK
1201	2026-09-11 06:35	78.43	OK	1202	2026-09-11 06:36	75.54	OK
1203	2026-09-11 06:37	76.35	OK	1204	2026-09-11 06:38	76.14	OK
1205	2026-09-11 06:39	74.65	OK	1206	2026-09-11 06:40	74.04	OK
1207	2026-09-11 06:41	75.68	OK	1208	2026-09-11 06:42	76.88	OK
1209	2026-09-11 06:43	76.21	OK	1210	2026-09-11 06:44	75.70	OK
1211	2026-09-11 06:45	74.69	OK	1212	2026-09-11 06:46	73.88	OK
1213	2026-09-11 06:47	74.55	OK	1214	2026-09-11 06:48	73.19	OK
1215	2026-09-11 06:49	75.93	OK	1216	2026-09-11 06:50	72.12	OK
1217	2026-09-11 06:51	73.97	OK	1218	2026-09-11 06:52	74.72	OK
1219	2026-09-11 06:53	76.08	OK	1220	2026-09-11 06:54	73.87	OK
1221	2026-09-11 06:55	72.59	OK	1222	2026-09-11 06:56	74.28	OK
1223	2026-09-11 06:57	74.41	OK	1224	2026-09-11 06:58	72.81	OK
1225	2026-09-11 06:59	75.34	OK	1226	2026-09-11 07:00	75.29	OK
1227	2026-09-11 07:01	74.47	OK	1228	2026-09-11 07:02	77.70	OK
1229	2026-09-11 07:03	74.14	OK	1230	2026-09-11 07:04	74.31	OK
1231	2026-09-11 07:05	75.31	OK	1232	2026-09-11 07:06	76.20	OK
1233	2026-09-11 07:07	75.05	OK	1234	2026-09-11 07:08	78.51	OK
1235	2026-09-11 07:09	73.84	OK	1236	2026-09-11 07:10	76.99	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1237	2026-09-11 07:11	74.48	OK	1238	2026-09-11 07:12	74.95	OK
1239	2026-09-11 07:13	72.85	OK	1240	2026-09-11 07:14	72.58	OK
1241	2026-09-11 07:15	75.36	OK	1242	2026-09-11 07:16	74.46	OK
1243	2026-09-11 07:17	74.24	OK	1244	2026-09-11 07:18	76.08	OK
1245	2026-09-11 07:19	74.73	OK	1246	2026-09-11 07:20	77.58	OK
1247	2026-09-11 07:21	75.76	OK	1248	2026-09-11 07:22	74.60	OK
1249	2026-09-11 07:23	79.04	OK	1250	2026-09-11 07:24	78.05	OK
1251	2026-09-11 07:25	75.87	OK	1252	2026-09-11 07:26	76.54	OK
1253	2026-09-11 07:27	73.54	OK	1254	2026-09-11 07:28	72.05	OK
1255	2026-09-11 07:29	73.60	OK	1256	2026-09-11 07:30	77.21	OK
1257	2026-09-11 07:31	74.29	OK	1258	2026-09-11 07:32	72.75	OK
1259	2026-09-11 07:33	76.18	OK	1260	2026-09-11 07:34	76.84	OK
1261	2026-09-11 07:35	72.41	OK	1262	2026-09-11 07:36	75.29	OK
1263	2026-09-11 07:37	76.44	OK	1264	2026-09-11 07:38	76.05	OK
1265	2026-09-11 07:39	76.52	OK	1266	2026-09-11 07:40	79.12	OK
1267	2026-09-11 07:41	75.60	OK	1268	2026-09-11 07:42	79.43	OK
1269	2026-09-11 07:43	76.77	OK	1270	2026-09-11 07:44	77.32	OK
1271	2026-09-11 07:45	76.78	OK	1272	2026-09-11 07:46	77.00	OK
1273	2026-09-11 07:47	73.91	OK	1274	2026-09-11 07:48	73.04	OK
1275	2026-09-11 07:49	75.44	OK	1276	2026-09-11 07:50	78.93	OK
1277	2026-09-11 07:51	78.87	OK	1278	2026-09-11 07:52	77.17	OK
1279	2026-09-11 07:53	75.14	OK	1280	2026-09-11 07:54	74.87	OK
1281	2026-09-11 07:55	74.76	OK	1282	2026-09-11 07:56	79.24	OK
1283	2026-09-11 07:57	76.52	OK	1284	2026-09-11 07:58	76.46	OK
1285	2026-09-11 07:59	75.92	OK	1286	2026-09-11 08:00	76.45	OK
1287	2026-09-11 08:01	78.08	OK	1288	2026-09-11 08:02	77.26	OK
1289	2026-09-11 08:03	78.41	OK	1290	2026-09-11 08:04	77.79	OK
1291	2026-09-11 08:05	76.27	OK	1292	2026-09-11 08:06	77.43	OK
1293	2026-09-11 08:07	77.79	OK	1294	2026-09-11 08:08	78.08	OK
1295	2026-09-11 08:09	78.48	OK	1296	2026-09-11 08:10	77.54	OK
1297	2026-09-11 08:11	77.18	OK	1298	2026-09-11 08:12	79.18	OK
1299	2026-09-11 08:13	78.06	OK	1300	2026-09-11 08:14	80.34	OK
1301	2026-09-11 08:15	78.09	OK	1302	2026-09-11 08:16	76.03	OK
1303	2026-09-11 08:17	76.37	OK	1304	2026-09-11 08:18	78.00	OK
1305	2026-09-11 08:19	76.20	OK	1306	2026-09-11 08:20	77.45	OK
1307	2026-09-11 08:21	79.14	OK	1308	2026-09-11 08:22	78.11	OK
1309	2026-09-11 08:23	75.14	OK	1310	2026-09-11 08:24	75.65	OK
1311	2026-09-11 08:25	73.40	OK	1312	2026-09-11 08:26	78.15	OK
1313	2026-09-11 08:27	79.45	OK	1314	2026-09-11 08:28	76.04	OK
1315	2026-09-11 08:29	75.89	OK	1316	2026-09-11 08:30	76.50	OK
1317	2026-09-11 08:31	74.24	OK	1318	2026-09-11 08:32	77.11	OK
1319	2026-09-11 08:33	76.97	OK	1320	2026-09-11 08:34	78.97	OK
1321	2026-09-11 08:35	78.94	OK	1322	2026-09-11 08:36	78.26	OK
1323	2026-09-11 08:37	77.13	OK	1324	2026-09-11 08:38	79.48	OK
1325	2026-09-11 08:39	75.91	OK	1326	2026-09-11 08:40	80.56	OK
1327	2026-09-11 08:41	80.56	OK	1328	2026-09-11 08:42	78.32	OK
1329	2026-09-11 08:43	79.59	OK	1330	2026-09-11 08:44	80.84	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1331	2026-09-11 08:45	79.60	OK	1332	2026-09-11 08:46	77.62	OK
1333	2026-09-11 08:47	75.45	OK	1334	2026-09-11 08:48	76.07	OK
1335	2026-09-11 08:49	79.07	OK	1336	2026-09-11 08:50	75.16	OK
1337	2026-09-11 08:51	77.29	OK	1338	2026-09-11 08:52	77.79	OK
1339	2026-09-11 08:53	75.23	OK	1340	2026-09-11 08:54	78.43	OK
1341	2026-09-11 08:55	77.46	OK	1342	2026-09-11 08:56	76.72	OK
1343	2026-09-11 08:57	75.79	OK	1344	2026-09-11 08:58	78.77	OK
1345	2026-09-11 08:59	81.17	OK	1346	2026-09-11 09:00	78.84	OK
1347	2026-09-11 09:01	75.44	OK	1348	2026-09-11 09:02	78.54	OK
1349	2026-09-11 09:03	78.68	OK	1350	2026-09-11 09:04	80.24	OK
1351	2026-09-11 09:05	77.27	OK	1352	2026-09-11 09:06	77.43	OK
1353	2026-09-11 09:07	79.62	OK	1354	2026-09-11 09:08	78.96	OK
1355	2026-09-11 09:09	78.73	OK	1356	2026-09-11 09:10	81.32	OK
1357	2026-09-11 09:11	80.37	OK	1358	2026-09-11 09:12	80.00	OK
1359	2026-09-11 09:13	78.67	OK	1360	2026-09-11 09:14	76.88	OK
1361	2026-09-11 09:15	77.97	OK	1362	2026-09-11 09:16	80.75	OK
1363	2026-09-11 09:17	77.31	OK	1364	2026-09-11 09:18	76.62	OK
1365	2026-09-11 09:19	75.67	OK	1366	2026-09-11 09:20	79.30	OK
1367	2026-09-11 09:21	75.83	OK	1368	2026-09-11 09:22	78.57	OK
1369	2026-09-11 09:23	79.11	OK	1370	2026-09-11 09:24	77.82	OK
1371	2026-09-11 09:25	78.44	OK	1372	2026-09-11 09:26	78.39	OK
1373	2026-09-11 09:27	80.62	OK	1374	2026-09-11 09:28	78.22	OK
1375	2026-09-11 09:29	80.05	OK	1376	2026-09-11 09:30	75.16	OK
1377	2026-09-11 09:31	81.38	OK	1378	2026-09-11 09:32	79.89	OK
1379	2026-09-11 09:33	76.35	OK	1380	2026-09-11 09:34	77.00	OK
1381	2026-09-11 09:35	79.60	OK	1382	2026-09-11 09:36	75.98	OK
1383	2026-09-11 09:37	79.13	OK	1384	2026-09-11 09:38	78.22	OK
1385	2026-09-11 09:39	79.33	OK	1386	2026-09-11 09:40	77.80	OK
1387	2026-09-11 09:41	78.54	OK	1388	2026-09-11 09:42	82.15	OK
1389	2026-09-11 09:43	76.80	OK	1390	2026-09-11 09:44	80.89	OK
1391	2026-09-11 09:45	81.27	OK	1392	2026-09-11 09:46	80.05	OK
1393	2026-09-11 09:47	78.70	OK	1394	2026-09-11 09:48	78.79	OK
1395	2026-09-11 09:49	79.47	OK	1396	2026-09-11 09:50	78.81	OK
1397	2026-09-11 09:51	79.55	OK	1398	2026-09-11 09:52	78.75	OK
1399	2026-09-11 09:53	80.86	OK	1400	2026-09-11 09:54	82.68	OK
1401	2026-09-11 09:55	77.49	OK	1402	2026-09-11 09:56	79.38	OK
1403	2026-09-11 09:57	80.58	OK	1404	2026-09-11 09:58	81.51	OK
1405	2026-09-11 09:59	80.51	OK	1406	2026-09-11 10:00	80.76	OK
1407	2026-09-11 10:01	80.61	OK	1408	2026-09-11 10:02	78.84	OK
1409	2026-09-11 10:03	79.55	OK	1410	2026-09-11 10:04	80.96	OK
1411	2026-09-11 10:05	76.88	OK	1412	2026-09-11 10:06	81.62	OK
1413	2026-09-11 10:07	81.67	OK	1414	2026-09-11 10:08	82.61	OK
1415	2026-09-11 10:09	75.92	OK	1416	2026-09-11 10:10	78.23	OK
1417	2026-09-11 10:11	77.56	OK	1418	2026-09-11 10:12	78.25	OK
1419	2026-09-11 10:13	77.85	OK	1420	2026-09-11 10:14	78.31	OK
1421	2026-09-11 10:15	76.50	OK	1422	2026-09-11 10:16	80.62	OK
1423	2026-09-11 10:17	78.95	OK	1424	2026-09-11 10:18	77.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1425	2026-09-11 10:19	78.22	OK	1426	2026-09-11 10:20	80.99	OK
1427	2026-09-11 10:21	81.79	OK	1428	2026-09-11 10:22	81.48	OK
1429	2026-09-11 10:23	82.58	OK	1430	2026-09-11 10:24	80.35	OK
1431	2026-09-11 10:25	79.41	OK	1432	2026-09-11 10:26	80.32	OK
1433	2026-09-11 10:27	79.45	OK	1434	2026-09-11 10:28	80.91	OK
1435	2026-09-11 10:29	82.12	OK	1436	2026-09-11 10:30	81.86	OK
1437	2026-09-11 10:31	80.07	OK	1438	2026-09-11 10:32	78.58	OK
1439	2026-09-11 10:33	81.35	OK	1440	2026-09-11 10:34	80.84	OK
1441	2026-09-11 10:35	81.45	OK	1442	2026-09-11 10:36	80.93	OK
1443	2026-09-11 10:37	79.06	OK	1444	2026-09-11 10:38	81.33	OK
1445	2026-09-11 10:39	81.94	OK	1446	2026-09-11 10:40	81.04	OK
1447	2026-09-11 10:41	80.70	OK	1448	2026-09-11 10:42	78.61	OK
1449	2026-09-11 10:43	83.64	OK	1450	2026-09-11 10:44	81.33	OK
1451	2026-09-11 10:45	78.57	OK	1452	2026-09-11 10:46	79.73	OK
1453	2026-09-11 10:47	79.01	OK	1454	2026-09-11 10:48	81.81	OK
1455	2026-09-11 10:49	77.08	OK	1456	2026-09-11 10:50	77.33	OK
1457	2026-09-11 10:51	78.59	OK	1458	2026-09-11 10:52	79.00	OK
1459	2026-09-11 10:53	82.66	OK	1460	2026-09-11 10:54	76.42	OK
1461	2026-09-11 10:55	78.13	OK	1462	2026-09-11 10:56	79.33	OK
1463	2026-09-11 10:57	80.49	OK	1464	2026-09-11 10:58	79.87	OK
1465	2026-09-11 10:59	76.98	OK	1466	2026-09-11 11:00	80.03	OK
1467	2026-09-11 11:01	80.92	OK	1468	2026-09-11 11:02	78.53	OK
1469	2026-09-11 11:03	78.44	OK	1470	2026-09-11 11:04	79.31	OK
1471	2026-09-11 11:05	78.28	OK	1472	2026-09-11 11:06	79.82	OK
1473	2026-09-11 11:07	81.28	OK	1474	2026-09-11 11:08	80.57	OK
1475	2026-09-11 11:09	77.35	OK	1476	2026-09-11 11:10	80.29	OK
1477	2026-09-11 11:11	83.93	OK	1478	2026-09-11 11:12	80.18	OK
1479	2026-09-11 11:13	81.42	OK	1480	2026-09-11 11:14	80.24	OK
1481	2026-09-11 11:15	79.45	OK	1482	2026-09-11 11:16	79.42	OK
1483	2026-09-11 11:17	81.96	OK	1484	2026-09-11 11:18	78.49	OK
1485	2026-09-11 11:19	81.63	OK	1486	2026-09-11 11:20	80.77	OK
1487	2026-09-11 11:21	78.11	OK	1488	2026-09-11 11:22	78.22	OK
1489	2026-09-11 11:23	81.19	OK	1490	2026-09-11 11:24	81.19	OK
1491	2026-09-11 11:25	78.19	OK	1492	2026-09-11 11:26	81.99	OK
1493	2026-09-11 11:27	78.73	OK	1494	2026-09-11 11:28	81.22	OK
1495	2026-09-11 11:29	81.69	OK	1496	2026-09-11 11:30	81.68	OK
1497	2026-09-11 11:31	78.48	OK	1498	2026-09-11 11:32	80.84	OK
1499	2026-09-11 11:33	78.84	OK	1500	2026-09-11 11:34	81.97	OK
1501	2026-09-11 11:35	80.41	OK	1502	2026-09-11 11:36	78.35	OK
1503	2026-09-11 11:37	81.30	OK	1504	2026-09-11 11:38	82.14	OK
1505	2026-09-11 11:39	81.91	OK	1506	2026-09-11 11:40	80.07	OK
1507	2026-09-11 11:41	80.69	OK	1508	2026-09-11 11:42	78.99	OK
1509	2026-09-11 11:43	80.62	OK	1510	2026-09-11 11:44	79.39	OK
1511	2026-09-11 11:45	77.17	OK	1512	2026-09-11 11:46	83.13	OK
1513	2026-09-11 11:47	82.22	OK	1514	2026-09-11 11:48	79.83	OK
1515	2026-09-11 11:49	79.62	OK	1516	2026-09-11 11:50	79.83	OK
1517	2026-09-11 11:51	81.78	OK	1518	2026-09-11 11:52	82.11	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1519	2026-09-11 11:53	84.24	OK	1520	2026-09-11 11:54	80.12	OK
1521	2026-09-11 11:55	78.08	OK	1522	2026-09-11 11:56	81.07	OK
1523	2026-09-11 11:57	80.83	OK	1524	2026-09-11 11:58	82.70	OK
1525	2026-09-11 11:59	80.52	OK	1526	2026-09-11 12:00	79.51	OK
1527	2026-09-11 12:01	82.49	OK	1528	2026-09-11 12:02	78.59	OK
1529	2026-09-11 12:03	80.89	OK	1530	2026-09-11 12:04	80.63	OK
1531	2026-09-11 12:05	79.25	OK	1532	2026-09-11 12:06	80.02	OK
1533	2026-09-11 12:07	78.50	OK	1534	2026-09-11 12:08	78.77	OK
1535	2026-09-11 12:09	82.19	OK	1536	2026-09-11 12:10	79.90	OK
1537	2026-09-11 12:11	78.42	OK	1538	2026-09-11 12:12	82.46	OK
1539	2026-09-11 12:13	81.89	OK	1540	2026-09-11 12:14	80.61	OK
1541	2026-09-11 12:15	79.62	OK	1542	2026-09-11 12:16	82.14	OK
1543	2026-09-11 12:17	81.88	OK	1544	2026-09-11 12:18	80.28	OK
1545	2026-09-11 12:19	80.82	OK	1546	2026-09-11 12:20	81.09	OK
1547	2026-09-11 12:21	80.92	OK	1548	2026-09-11 12:22	78.84	OK
1549	2026-09-11 12:23	82.72	OK	1550	2026-09-11 12:24	83.60	OK
1551	2026-09-11 12:25	79.56	OK	1552	2026-09-11 12:26	81.46	OK
1553	2026-09-11 12:27	82.82	OK	1554	2026-09-11 12:28	81.01	OK
1555	2026-09-11 12:29	79.22	OK	1556	2026-09-11 12:30	80.12	OK
1557	2026-09-11 12:31	80.79	OK	1558	2026-09-11 12:32	80.05	OK
1559	2026-09-11 12:33	81.06	OK	1560	2026-09-11 12:34	83.28	OK
1561	2026-09-11 12:35	80.71	OK	1562	2026-09-11 12:36	82.78	OK
1563	2026-09-11 12:37	81.28	OK	1564	2026-09-11 12:38	79.85	OK
1565	2026-09-11 12:39	80.18	OK	1566	2026-09-11 12:40	80.12	OK
1567	2026-09-11 12:41	82.63	OK	1568	2026-09-11 12:42	80.45	OK
1569	2026-09-11 12:43	79.70	OK	1570	2026-09-11 12:44	79.61	OK
1571	2026-09-11 12:45	80.56	OK	1572	2026-09-11 12:46	77.38	OK
1573	2026-09-11 12:47	80.19	OK	1574	2026-09-11 12:48	82.22	OK
1575	2026-09-11 12:49	78.16	OK	1576	2026-09-11 12:50	81.95	OK
1577	2026-09-11 12:51	79.80	OK	1578	2026-09-11 12:52	79.12	OK
1579	2026-09-11 12:53	81.15	OK	1580	2026-09-11 12:54	80.75	OK
1581	2026-09-11 12:55	83.73	OK	1582	2026-09-11 12:56	79.79	OK
1583	2026-09-11 12:57	80.57	OK	1584	2026-09-11 12:58	78.91	OK
1585	2026-09-11 12:59	83.96	OK	1586	2026-09-11 13:00	82.77	OK
1587	2026-09-11 13:01	79.71	OK	1588	2026-09-11 13:02	81.18	OK
1589	2026-09-11 13:03	78.45	OK	1590	2026-09-11 13:04	82.54	OK
1591	2026-09-11 13:05	80.83	OK	1592	2026-09-11 13:06	78.46	OK
1593	2026-09-11 13:07	83.24	OK	1594	2026-09-11 13:08	81.94	OK
1595	2026-09-11 13:09	82.88	OK	1596	2026-09-11 13:10	81.19	OK
1597	2026-09-11 13:11	79.05	OK	1598	2026-09-11 13:12	83.47	OK
1599	2026-09-11 13:13	82.53	OK	1600	2026-09-11 13:14	79.21	OK
1601	2026-09-11 13:15	79.73	OK	1602	2026-09-11 13:16	81.45	OK
1603	2026-09-11 13:17	80.81	OK	1604	2026-09-11 13:18	82.23	OK
1605	2026-09-11 13:19	79.46	OK	1606	2026-09-11 13:20	78.95	OK
1607	2026-09-11 13:21	81.87	OK	1608	2026-09-11 13:22	79.76	OK
1609	2026-09-11 13:23	82.54	OK	1610	2026-09-11 13:24	79.51	OK
1611	2026-09-11 13:25	77.47	OK	1612	2026-09-11 13:26	82.08	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1613	2026-09-11 13:27	78.38	OK	1614	2026-09-11 13:28	80.84	OK
1615	2026-09-11 13:29	80.57	OK	1616	2026-09-11 13:30	81.58	OK
1617	2026-09-11 13:31	80.85	OK	1618	2026-09-11 13:32	80.06	OK
1619	2026-09-11 13:33	80.51	OK	1620	2026-09-11 13:34	78.25	OK
1621	2026-09-11 13:35	82.44	OK	1622	2026-09-11 13:36	80.02	OK
1623	2026-09-11 13:37	82.31	OK	1624	2026-09-11 13:38	83.18	OK
1625	2026-09-11 13:39	81.75	OK	1626	2026-09-11 13:40	82.96	OK
1627	2026-09-11 13:41	81.34	OK	1628	2026-09-11 13:42	80.22	OK
1629	2026-09-11 13:43	79.61	OK	1630	2026-09-11 13:44	81.48	OK
1631	2026-09-11 13:45	82.08	OK	1632	2026-09-11 13:46	80.63	OK
1633	2026-09-11 13:47	80.95	OK	1634	2026-09-11 13:48	80.95	OK
1635	2026-09-11 13:49	82.69	OK	1636	2026-09-11 13:50	78.64	OK
1637	2026-09-11 13:51	80.66	OK	1638	2026-09-11 13:52	78.79	OK
1639	2026-09-11 13:53	82.52	OK	1640	2026-09-11 13:54	80.36	OK
1641	2026-09-11 13:55	83.54	OK	1642	2026-09-11 13:56	81.39	OK
1643	2026-09-11 13:57	79.33	OK	1644	2026-09-11 13:58	79.01	OK
1645	2026-09-11 13:59	83.12	OK	1646	2026-09-11 14:00	82.50	OK
1647	2026-09-11 14:01	79.11	OK	1648	2026-09-11 14:02	81.98	OK
1649	2026-09-11 14:03	82.33	OK	1650	2026-09-11 14:04	78.37	OK
1651	2026-09-11 14:05	79.73	OK	1652	2026-09-11 14:06	80.26	OK
1653	2026-09-11 14:07	81.27	OK	1654	2026-09-11 14:08	80.27	OK
1655	2026-09-11 14:09	81.45	OK	1656	2026-09-11 14:10	81.04	OK
1657	2026-09-11 14:11	84.42	OK	1658	2026-09-11 14:12	81.65	OK
1659	2026-09-11 14:13	83.36	OK	1660	2026-09-11 14:14	79.72	OK
1661	2026-09-11 14:15	81.75	OK	1662	2026-09-11 14:16	79.75	OK
1663	2026-09-11 14:17	81.40	OK	1664	2026-09-11 14:18	79.51	OK
1665	2026-09-11 14:19	78.47	OK	1666	2026-09-11 14:20	83.24	OK
1667	2026-09-11 14:21	81.70	OK	1668	2026-09-11 14:22	78.47	OK
1669	2026-09-11 14:23	82.61	OK	1670	2026-09-11 14:24	81.06	OK
1671	2026-09-11 14:25	80.95	OK	1672	2026-09-11 14:26	77.75	OK
1673	2026-09-11 14:27	79.15	OK	1674	2026-09-11 14:28	80.90	OK
1675	2026-09-11 14:29	80.49	OK	1676	2026-09-11 14:30	79.72	OK
1677	2026-09-11 14:31	82.34	OK	1678	2026-09-11 14:32	81.63	OK
1679	2026-09-11 14:33	79.17	OK	1680	2026-09-11 14:34	80.91	OK
1681	2026-09-11 14:35	80.16	OK	1682	2026-09-11 14:36	79.16	OK
1683	2026-09-11 14:37	81.74	OK	1684	2026-09-11 14:38	80.71	OK
1685	2026-09-11 14:39	83.19	OK	1686	2026-09-11 14:40	81.54	OK
1687	2026-09-11 14:41	80.41	OK	1688	2026-09-11 14:42	81.35	OK
1689	2026-09-11 14:43	80.17	OK	1690	2026-09-11 14:44	81.37	OK
1691	2026-09-11 14:45	81.78	OK	1692	2026-09-11 14:46	82.73	OK
1693	2026-09-11 14:47	80.71	OK	1694	2026-09-11 14:48	81.18	OK
1695	2026-09-11 14:49	81.13	OK	1696	2026-09-11 14:50	78.56	OK
1697	2026-09-11 14:51	80.35	OK	1698	2026-09-11 14:52	80.76	OK
1699	2026-09-11 14:53	77.15	OK	1700	2026-09-11 14:54	79.36	OK
1701	2026-09-11 14:55	81.75	OK	1702	2026-09-11 14:56	78.61	OK
1703	2026-09-11 14:57	82.06	OK	1704	2026-09-11 14:58	78.82	OK
1705	2026-09-11 14:59	81.22	OK	1706	2026-09-11 15:00	78.75	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1707	2026-09-11 15:01	78.93	OK	1708	2026-09-11 15:02	80.60	OK
1709	2026-09-11 15:03	81.86	OK	1710	2026-09-11 15:04	77.23	OK
1711	2026-09-11 15:05	82.45	OK	1712	2026-09-11 15:06	82.07	OK
1713	2026-09-11 15:07	79.68	OK	1714	2026-09-11 15:08	80.86	OK
1715	2026-09-11 15:09	80.35	OK	1716	2026-09-11 15:10	77.31	OK
1717	2026-09-11 15:11	81.28	OK	1718	2026-09-11 15:12	79.45	OK
1719	2026-09-11 15:13	78.55	OK	1720	2026-09-11 15:14	81.77	OK
1721	2026-09-11 15:15	82.09	OK	1722	2026-09-11 15:16	81.47	OK
1723	2026-09-11 15:17	80.63	OK	1724	2026-09-11 15:18	81.90	OK
1725	2026-09-11 15:19	78.84	OK	1726	2026-09-11 15:20	80.74	OK
1727	2026-09-11 15:21	78.18	OK	1728	2026-09-11 15:22	80.36	OK
1729	2026-09-11 15:23	83.21	OK	1730	2026-09-11 15:24	76.81	OK
1731	2026-09-11 15:25	80.39	OK	1732	2026-09-11 15:26	78.23	OK
1733	2026-09-11 15:27	80.15	OK	1734	2026-09-11 15:28	80.41	OK
1735	2026-09-11 15:29	80.39	OK	1736	2026-09-11 15:30	80.39	OK
1737	2026-09-11 15:31	76.20	OK	1738	2026-09-11 15:32	80.84	OK
1739	2026-09-11 15:33	79.07	OK	1740	2026-09-11 15:34	82.56	OK
1741	2026-09-11 15:35	78.38	OK	1742	2026-09-11 15:36	81.04	OK
1743	2026-09-11 15:37	79.99	OK	1744	2026-09-11 15:38	82.15	OK
1745	2026-09-11 15:39	77.33	OK	1746	2026-09-11 15:40	82.64	OK
1747	2026-09-11 15:41	79.54	OK	1748	2026-09-11 15:42	80.72	OK
1749	2026-09-11 15:43	81.10	OK	1750	2026-09-11 15:44	83.47	OK
1751	2026-09-11 15:45	79.70	OK	1752	2026-09-11 15:46	79.07	OK
1753	2026-09-11 15:47	79.19	OK	1754	2026-09-11 15:48	77.59	OK
1755	2026-09-11 15:49	80.87	OK	1756	2026-09-11 15:50	82.41	OK
1757	2026-09-11 15:51	78.93	OK	1758	2026-09-11 15:52	81.41	OK
1759	2026-09-11 15:53	78.80	OK	1760	2026-09-11 15:54	78.45	OK
1761	2026-09-11 15:55	81.61	OK	1762	2026-09-11 15:56	79.75	OK
1763	2026-09-11 15:57	80.42	OK	1764	2026-09-11 15:58	78.72	OK
1765	2026-09-11 15:59	76.50	OK	1766	2026-09-11 16:00	80.41	OK
1767	2026-09-11 16:01	78.80	OK	1768	2026-09-11 16:02	82.26	OK
1769	2026-09-11 16:03	79.59	OK	1770	2026-09-11 16:04	78.83	OK
1771	2026-09-11 16:05	78.80	OK	1772	2026-09-11 16:06	79.73	OK
1773	2026-09-11 16:07	79.69	OK	1774	2026-09-11 16:08	75.88	OK
1775	2026-09-11 16:09	81.54	OK	1776	2026-09-11 16:10	78.60	OK
1777	2026-09-11 16:11	80.36	OK	1778	2026-09-11 16:12	76.81	OK
1779	2026-09-11 16:13	76.89	OK	1780	2026-09-11 16:14	77.92	OK
1781	2026-09-11 16:15	78.14	OK	1782	2026-09-11 16:16	80.04	OK
1783	2026-09-11 16:17	79.52	OK	1784	2026-09-11 16:18	79.13	OK
1785	2026-09-11 16:19	75.04	OK	1786	2026-09-11 16:20	80.39	OK
1787	2026-09-11 16:21	77.61	OK	1788	2026-09-11 16:22	76.66	OK
1789	2026-09-11 16:23	81.03	OK	1790	2026-09-11 16:24	78.30	OK
1791	2026-09-11 16:25	78.33	OK	1792	2026-09-11 16:26	80.80	OK
1793	2026-09-11 16:27	81.13	OK	1794	2026-09-11 16:28	79.32	OK
1795	2026-09-11 16:29	77.46	OK	1796	2026-09-11 16:30	78.16	OK
1797	2026-09-11 16:31	79.66	OK	1798	2026-09-11 16:32	73.90	OK
1799	2026-09-11 16:33	75.98	OK	1800	2026-09-11 16:34	79.57	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1801	2026-09-11 16:35	76.86	OK	1802	2026-09-11 16:36	75.56	OK
1803	2026-09-11 16:37	76.26	OK	1804	2026-09-11 16:38	78.91	OK
1805	2026-09-11 16:39	77.63	OK	1806	2026-09-11 16:40	75.33	OK
1807	2026-09-11 16:41	80.78	OK	1808	2026-09-11 16:42	78.56	OK
1809	2026-09-11 16:43	75.02	OK	1810	2026-09-11 16:44	77.74	OK
1811	2026-09-11 16:45	79.49	OK	1812	2026-09-11 16:46	78.10	OK
1813	2026-09-11 16:47	78.18	OK	1814	2026-09-11 16:48	77.58	OK
1815	2026-09-11 16:49	78.50	OK	1816	2026-09-11 16:50	78.83	OK
1817	2026-09-11 16:51	80.88	OK	1818	2026-09-11 16:52	78.68	OK
1819	2026-09-11 16:53	77.22	OK	1820	2026-09-11 16:54	77.80	OK
1821	2026-09-11 16:55	80.01	OK	1822	2026-09-11 16:56	78.35	OK
1823	2026-09-11 16:57	80.43	OK	1824	2026-09-11 16:58	77.06	OK
1825	2026-09-11 16:59	78.58	OK	1826	2026-09-11 17:00	76.02	OK
1827	2026-09-11 17:01	78.17	OK	1828	2026-09-11 17:02	74.92	OK
1829	2026-09-11 17:03	77.53	OK	1830	2026-09-11 17:04	76.41	OK
1831	2026-09-11 17:05	79.63	OK	1832	2026-09-11 17:06	78.55	OK
1833	2026-09-11 17:07	75.54	OK	1834	2026-09-11 17:08	77.54	OK
1835	2026-09-11 17:09	79.20	OK	1836	2026-09-11 17:10	77.55	OK
1837	2026-09-11 17:11	76.52	OK	1838	2026-09-11 17:12	78.58	OK
1839	2026-09-11 17:13	79.00	OK	1840	2026-09-11 17:14	77.81	OK
1841	2026-09-11 17:15	79.86	OK	1842	2026-09-11 17:16	76.65	OK
1843	2026-09-11 17:17	78.82	OK	1844	2026-09-11 17:18	76.87	OK
1845	2026-09-11 17:19	76.14	OK	1846	2026-09-11 17:20	75.29	OK
1847	2026-09-11 17:21	75.49	OK	1848	2026-09-11 17:22	76.10	OK
1849	2026-09-11 17:23	76.07	OK	1850	2026-09-11 17:24	77.16	OK
1851	2026-09-11 17:25	78.46	OK	1852	2026-09-11 17:26	76.96	OK
1853	2026-09-11 17:27	78.19	OK	1854	2026-09-11 17:28	75.55	OK
1855	2026-09-11 17:29	79.29	OK	1856	2026-09-11 17:30	76.04	OK
1857	2026-09-11 17:31	74.78	OK	1858	2026-09-11 17:32	78.67	OK
1859	2026-09-11 17:33	77.08	OK	1860	2026-09-11 17:34	79.35	OK
1861	2026-09-11 17:35	79.06	OK	1862	2026-09-11 17:36	75.50	OK
1863	2026-09-11 17:37	75.98	OK	1864	2026-09-11 17:38	75.67	OK
1865	2026-09-11 17:39	75.69	OK	1866	2026-09-11 17:40	79.61	OK
1867	2026-09-11 17:41	76.39	OK	1868	2026-09-11 17:42	76.73	OK
1869	2026-09-11 17:43	76.65	OK	1870	2026-09-11 17:44	77.55	OK
1871	2026-09-11 17:45	76.07	OK	1872	2026-09-11 17:46	78.08	OK
1873	2026-09-11 17:47	78.72	OK	1874	2026-09-11 17:48	77.00	OK
1875	2026-09-11 17:49	76.73	OK	1876	2026-09-11 17:50	78.28	OK
1877	2026-09-11 17:51	77.14	OK	1878	2026-09-11 17:52	75.65	OK
1879	2026-09-11 17:53	79.05	OK	1880	2026-09-11 17:54	80.06	OK
1881	2026-09-11 17:55	73.72	OK	1882	2026-09-11 17:56	79.79	OK
1883	2026-09-11 17:57	74.63	OK	1884	2026-09-11 17:58	75.73	OK
1885	2026-09-11 17:59	72.67	OK	1886	2026-09-11 18:00	75.03	OK
1887	2026-09-11 18:01	75.73	OK	1888	2026-09-11 18:02	77.51	OK
1889	2026-09-11 18:03	76.20	OK	1890	2026-09-11 18:04	76.99	OK
1891	2026-09-11 18:05	78.44	OK	1892	2026-09-11 18:06	79.08	OK
1893	2026-09-11 18:07	76.82	OK	1894	2026-09-11 18:08	75.03	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1895	2026-09-11 18:09	76.56	OK	1896	2026-09-11 18:10	75.83	OK
1897	2026-09-11 18:11	74.38	OK	1898	2026-09-11 18:12	75.13	OK
1899	2026-09-11 18:13	79.16	OK	1900	2026-09-11 18:14	73.80	OK
1901	2026-09-11 18:15	74.20	OK	1902	2026-09-11 18:16	73.40	OK
1903	2026-09-11 18:17	75.87	OK	1904	2026-09-11 18:18	76.50	OK
1905	2026-09-11 18:19	76.25	OK	1906	2026-09-11 18:20	78.62	OK
1907	2026-09-11 18:21	76.48	OK	1908	2026-09-11 18:22	75.42	OK
1909	2026-09-11 18:23	76.72	OK	1910	2026-09-11 18:24	77.20	OK
1911	2026-09-11 18:25	76.94	OK	1912	2026-09-11 18:26	74.64	OK
1913	2026-09-11 18:27	75.23	OK	1914	2026-09-11 18:28	77.79	OK
1915	2026-09-11 18:29	78.87	OK	1916	2026-09-11 18:30	76.52	OK
1917	2026-09-11 18:31	75.91	OK	1918	2026-09-11 18:32	74.81	OK
1919	2026-09-11 18:33	75.51	OK	1920	2026-09-11 18:34	73.25	OK
1921	2026-09-11 18:35	75.80	OK	1922	2026-09-11 18:36	77.53	OK
1923	2026-09-11 18:37	77.98	OK	1924	2026-09-11 18:38	76.79	OK
1925	2026-09-11 18:39	77.09	OK	1926	2026-09-11 18:40	77.02	OK
1927	2026-09-11 18:41	72.17	OK	1928	2026-09-11 18:42	75.40	OK
1929	2026-09-11 18:43	76.87	OK	1930	2026-09-11 18:44	74.81	OK
1931	2026-09-11 18:45	76.35	OK	1932	2026-09-11 18:46	72.93	OK
1933	2026-09-11 18:47	78.15	OK	1934	2026-09-11 18:48	75.46	OK
1935	2026-09-11 18:49	77.04	OK	1936	2026-09-11 18:50	75.17	OK
1937	2026-09-11 18:51	72.29	OK	1938	2026-09-11 18:52	75.92	OK
1939	2026-09-11 18:53	72.48	OK	1940	2026-09-11 18:54	76.68	OK
1941	2026-09-11 18:55	73.66	OK	1942	2026-09-11 18:56	76.03	OK
1943	2026-09-11 18:57	74.00	OK	1944	2026-09-11 18:58	76.71	OK
1945	2026-09-11 18:59	75.50	OK	1946	2026-09-11 19:00	75.94	OK
1947	2026-09-11 19:01	73.91	OK	1948	2026-09-11 19:02	74.52	OK
1949	2026-09-11 19:03	73.01	OK	1950	2026-09-11 19:04	76.23	OK
1951	2026-09-11 19:05	74.76	OK	1952	2026-09-11 19:06	75.01	OK
1953	2026-09-11 19:07	72.60	OK	1954	2026-09-11 19:08	75.03	OK
1955	2026-09-11 19:09	75.90	OK	1956	2026-09-11 19:10	73.23	OK
1957	2026-09-11 19:11	73.68	OK	1958	2026-09-11 19:12	74.21	OK
1959	2026-09-11 19:13	73.40	OK	1960	2026-09-11 19:14	75.76	OK
1961	2026-09-11 19:15	74.66	OK	1962	2026-09-11 19:16	71.28	OK
1963	2026-09-11 19:17	75.27	OK	1964	2026-09-11 19:18	74.61	OK
1965	2026-09-11 19:19	73.33	OK	1966	2026-09-11 19:20	73.88	OK
1967	2026-09-11 19:21	75.78	OK	1968	2026-09-11 19:22	76.55	OK
1969	2026-09-11 19:23	75.69	OK	1970	2026-09-11 19:24	72.68	OK
1971	2026-09-11 19:25	74.78	OK	1972	2026-09-11 19:26	72.03	OK
1973	2026-09-11 19:27	74.08	OK	1974	2026-09-11 19:28	75.81	OK
1975	2026-09-11 19:29	76.20	OK	1976	2026-09-11 19:30	74.39	OK
1977	2026-09-11 19:31	73.10	OK	1978	2026-09-11 19:32	73.50	OK
1979	2026-09-11 19:33	74.56	OK	1980	2026-09-11 19:34	73.31	OK
1981	2026-09-11 19:35	77.83	OK	1982	2026-09-11 19:36	75.73	OK
1983	2026-09-11 19:37	75.83	OK	1984	2026-09-11 19:38	74.94	OK
1985	2026-09-11 19:39	73.29	OK	1986	2026-09-11 19:40	71.33	OK
1987	2026-09-11 19:41	73.37	OK	1988	2026-09-11 19:42	73.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1989	2026-09-11 19:43	74.76	OK	1990	2026-09-11 19:44	73.17	OK
1991	2026-09-11 19:45	74.97	OK	1992	2026-09-11 19:46	74.18	OK
1993	2026-09-11 19:47	71.44	OK	1994	2026-09-11 19:48	72.92	OK
1995	2026-09-11 19:49	73.31	OK	1996	2026-09-11 19:50	73.40	OK
1997	2026-09-11 19:51	77.28	OK	1998	2026-09-11 19:52	72.54	OK
1999	2026-09-11 19:53	74.96	OK	2000	2026-09-11 19:54	73.88	OK
2001	2026-09-11 19:55	76.31	OK	2002	2026-09-11 19:56	72.74	OK
2003	2026-09-11 19:57	73.91	OK	2004	2026-09-11 19:58	73.79	OK
2005	2026-09-11 19:59	73.01	OK	2006	2026-09-11 20:00	74.01	OK
2007	2026-09-11 20:01	71.38	OK	2008	2026-09-11 20:02	74.27	OK
2009	2026-09-11 20:03	72.42	OK	2010	2026-09-11 20:04	76.29	OK
2011	2026-09-11 20:05	71.23	OK	2012	2026-09-11 20:06	72.99	OK
2013	2026-09-11 20:07	73.96	OK	2014	2026-09-11 20:08	72.50	OK
2015	2026-09-11 20:09	72.27	OK	2016	2026-09-11 20:10	73.01	OK
2017	2026-09-11 20:11	73.58	OK	2018	2026-09-11 20:12	75.81	OK
2019	2026-09-11 20:13	71.48	OK	2020	2026-09-11 20:14	77.49	OK
2021	2026-09-11 20:15	70.95	OK	2022	2026-09-11 20:16	71.67	OK
2023	2026-09-11 20:17	71.20	OK	2024	2026-09-11 20:18	72.62	OK
2025	2026-09-11 20:19	75.13	OK	2026	2026-09-11 20:20	72.87	OK
2027	2026-09-11 20:21	74.84	OK	2028	2026-09-11 20:22	74.33	OK
2029	2026-09-11 20:23	74.54	OK	2030	2026-09-11 20:24	72.43	OK
2031	2026-09-11 20:25	74.67	OK	2032	2026-09-11 20:26	74.90	OK
2033	2026-09-11 20:27	70.06	OK	2034	2026-09-11 20:28	70.80	OK
2035	2026-09-11 20:29	75.11	OK	2036	2026-09-11 20:30	75.40	OK
2037	2026-09-11 20:31	75.69	OK	2038	2026-09-11 20:32	68.79	OK
2039	2026-09-11 20:33	72.97	OK	2040	2026-09-11 20:34	69.87	OK
2041	2026-09-11 20:35	74.82	OK	2042	2026-09-11 20:36	72.47	OK
2043	2026-09-11 20:37	69.98	OK	2044	2026-09-11 20:38	71.35	OK
2045	2026-09-11 20:39	72.87	OK	2046	2026-09-11 20:40	71.44	OK
2047	2026-09-11 20:41	73.44	OK	2048	2026-09-11 20:42	73.30	OK
2049	2026-09-11 20:43	74.57	OK	2050	2026-09-11 20:44	74.23	OK
2051	2026-09-11 20:45	69.82	OK	2052	2026-09-11 20:46	72.32	OK
2053	2026-09-11 20:47	72.96	OK	2054	2026-09-11 20:48	72.31	OK
2055	2026-09-11 20:49	73.51	OK	2056	2026-09-11 20:50	71.84	OK
2057	2026-09-11 20:51	73.38	OK	2058	2026-09-11 20:52	71.31	OK
2059	2026-09-11 20:53	72.88	OK	2060	2026-09-11 20:54	74.07	OK
2061	2026-09-11 20:55	70.84	OK	2062	2026-09-11 20:56	73.38	OK
2063	2026-09-11 20:57	70.20	OK	2064	2026-09-11 20:58	73.44	OK
2065	2026-09-11 20:59	75.96	OK	2066	2026-09-11 21:00	71.42	OK
2067	2026-09-11 21:01	73.49	OK	2068	2026-09-11 21:02	70.90	OK
2069	2026-09-11 21:03	75.66	OK	2070	2026-09-11 21:04	74.79	OK
2071	2026-09-11 21:05	71.47	OK	2072	2026-09-11 21:06	70.49	OK
2073	2026-09-11 21:07	72.16	OK	2074	2026-09-11 21:08	73.28	OK
2075	2026-09-11 21:09	72.70	OK	2076	2026-09-11 21:10	70.43	OK
2077	2026-09-11 21:11	69.76	OK	2078	2026-09-11 21:12	74.99	OK
2079	2026-09-11 21:13	72.39	OK	2080	2026-09-11 21:14	73.06	OK
2081	2026-09-11 21:15	72.54	OK	2082	2026-09-11 21:16	72.61	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2083	2026-09-11 21:17	69.89	OK	2084	2026-09-11 21:18	70.88	OK
2085	2026-09-11 21:19	73.40	OK	2086	2026-09-11 21:20	72.42	OK
2087	2026-09-11 21:21	72.65	OK	2088	2026-09-11 21:22	73.44	OK
2089	2026-09-11 21:23	74.67	OK	2090	2026-09-11 21:24	71.39	OK
2091	2026-09-11 21:25	73.08	OK	2092	2026-09-11 21:26	71.81	OK
2093	2026-09-11 21:27	71.61	OK	2094	2026-09-11 21:28	74.15	OK
2095	2026-09-11 21:29	70.36	OK	2096	2026-09-11 21:30	71.63	OK
2097	2026-09-11 21:31	72.39	OK	2098	2026-09-11 21:32	74.77	OK
2099	2026-09-11 21:33	72.03	OK	2100	2026-09-11 21:34	71.44	OK
2101	2026-09-11 21:35	69.49	OK	2102	2026-09-11 21:36	73.30	OK
2103	2026-09-11 21:37	70.71	OK	2104	2026-09-11 21:38	69.04	OK
2105	2026-09-11 21:39	73.69	OK	2106	2026-09-11 21:40	72.65	OK
2107	2026-09-11 21:41	70.91	OK	2108	2026-09-11 21:42	72.14	OK
2109	2026-09-11 21:43	74.07	OK	2110	2026-09-11 21:44	73.85	OK
2111	2026-09-11 21:45	71.34	OK	2112	2026-09-11 21:46	70.70	OK
2113	2026-09-11 21:47	70.76	OK	2114	2026-09-11 21:48	70.06	OK
2115	2026-09-11 21:49	72.17	OK	2116	2026-09-11 21:50	72.39	OK
2117	2026-09-11 21:51	73.63	OK	2118	2026-09-11 21:52	74.42	OK
2119	2026-09-11 21:53	69.41	OK	2120	2026-09-11 21:54	70.76	OK
2121	2026-09-11 21:55	74.41	OK	2122	2026-09-11 21:56	73.29	OK
2123	2026-09-11 21:57	72.18	OK	2124	2026-09-11 21:58	69.31	OK
2125	2026-09-11 21:59	70.47	OK	2126	2026-09-11 22:00	72.53	OK
2127	2026-09-11 22:01	74.28	OK	2128	2026-09-11 22:02	72.07	OK
2129	2026-09-11 22:03	71.15	OK	2130	2026-09-11 22:04	69.91	OK
2131	2026-09-11 22:05	72.45	OK	2132	2026-09-11 22:06	70.90	OK
2133	2026-09-11 22:07	71.10	OK	2134	2026-09-11 22:08	71.41	OK
2135	2026-09-11 22:09	71.69	OK	2136	2026-09-11 22:10	68.72	OK
2137	2026-09-11 22:11	72.14	OK	2138	2026-09-11 22:12	71.70	OK
2139	2026-09-11 22:13	73.58	OK	2140	2026-09-11 22:14	69.54	OK
2141	2026-09-11 22:15	70.62	OK	2142	2026-09-11 22:16	69.31	OK
2143	2026-09-11 22:17	69.58	OK	2144	2026-09-11 22:18	71.27	OK
2145	2026-09-11 22:19	70.65	OK	2146	2026-09-11 22:20	69.91	OK
2147	2026-09-11 22:21	68.09	OK	2148	2026-09-11 22:22	72.83	OK
2149	2026-09-11 22:23	72.70	OK	2150	2026-09-11 22:24	68.67	OK
2151	2026-09-11 22:25	67.87	OK	2152	2026-09-11 22:26	72.42	OK
2153	2026-09-11 22:27	69.07	OK	2154	2026-09-11 22:28	73.77	OK
2155	2026-09-11 22:29	72.29	OK	2156	2026-09-11 22:30	70.27	OK
2157	2026-09-11 22:31	69.13	OK	2158	2026-09-11 22:32	70.09	OK
2159	2026-09-11 22:33	74.25	OK	2160	2026-09-11 22:34	69.52	OK
2161	2026-09-11 22:35	72.63	OK	2162	2026-09-11 22:36	69.09	OK
2163	2026-09-11 22:37	72.85	OK	2164	2026-09-11 22:38	73.79	OK
2165	2026-09-11 22:39	71.55	OK	2166	2026-09-11 22:40	72.89	OK
2167	2026-09-11 22:41	71.17	OK	2168	2026-09-11 22:42	70.04	OK
2169	2026-09-11 22:43	70.27	OK	2170	2026-09-11 22:44	69.59	OK
2171	2026-09-11 22:45	69.10	OK	2172	2026-09-11 22:46	66.30	OK
2173	2026-09-11 22:47	71.07	OK	2174	2026-09-11 22:48	68.69	OK
2175	2026-09-11 22:49	70.02	OK	2176	2026-09-11 22:50	70.64	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2177	2026-09-11 22:51	71.62	OK	2178	2026-09-11 22:52	67.08	OK
2179	2026-09-11 22:53	70.59	OK	2180	2026-09-11 22:54	69.30	OK
2181	2026-09-11 22:55	71.43	OK	2182	2026-09-11 22:56	69.93	OK
2183	2026-09-11 22:57	71.52	OK	2184	2026-09-11 22:58	67.66	OK
2185	2026-09-11 22:59	68.01	OK	2186	2026-09-11 23:00	73.07	OK
2187	2026-09-11 23:01	69.67	OK	2188	2026-09-11 23:02	71.01	OK
2189	2026-09-11 23:03	69.43	OK	2190	2026-09-11 23:04	69.70	OK
2191	2026-09-11 23:05	69.25	OK	2192	2026-09-11 23:06	70.14	OK
2193	2026-09-11 23:07	70.19	OK	2194	2026-09-11 23:08	68.88	OK
2195	2026-09-11 23:09	70.17	OK	2196	2026-09-11 23:10	72.37	OK
2197	2026-09-11 23:11	71.62	OK	2198	2026-09-11 23:12	69.33	OK
2199	2026-09-11 23:13	69.48	OK	2200	2026-09-11 23:14	69.16	OK
2201	2026-09-11 23:15	70.27	OK	2202	2026-09-11 23:16	70.18	OK
2203	2026-09-11 23:17	70.93	OK	2204	2026-09-11 23:18	73.69	OK
2205	2026-09-11 23:19	68.55	OK	2206	2026-09-11 23:20	72.82	OK
2207	2026-09-11 23:21	71.40	OK	2208	2026-09-11 23:22	68.78	OK
2209	2026-09-11 23:23	69.21	OK	2210	2026-09-11 23:24	69.58	OK
2211	2026-09-11 23:25	69.92	OK	2212	2026-09-11 23:26	71.94	OK
2213	2026-09-11 23:27	69.69	OK	2214	2026-09-11 23:28	67.80	OK
2215	2026-09-11 23:29	67.43	OK	2216	2026-09-11 23:30	72.81	OK
2217	2026-09-11 23:31	68.02	OK	2218	2026-09-11 23:32	69.62	OK
2219	2026-09-11 23:33	67.72	OK	2220	2026-09-11 23:34	70.95	OK
2221	2026-09-11 23:35	73.84	OK	2222	2026-09-11 23:36	68.63	OK
2223	2026-09-11 23:37	70.00	OK	2224	2026-09-11 23:38	68.36	OK
2225	2026-09-11 23:39	69.55	OK	2226	2026-09-11 23:40	71.53	OK
2227	2026-09-11 23:41	69.40	OK	2228	2026-09-11 23:42	65.81	OK
2229	2026-09-11 23:43	68.38	OK	2230	2026-09-11 23:44	69.89	OK
2231	2026-09-11 23:45	67.24	OK	2232	2026-09-11 23:46	71.83	OK
2233	2026-09-11 23:47	69.43	OK	2234	2026-09-11 23:48	70.87	OK
2235	2026-09-11 23:49	70.69	OK	2236	2026-09-11 23:50	69.09	OK
2237	2026-09-11 23:51	69.37	OK	2238	2026-09-11 23:52	73.36	OK
2239	2026-09-11 23:53	70.43	OK	2240	2026-09-11 23:54	69.07	OK
2241	2026-09-11 23:55	68.33	OK	2242	2026-09-11 23:56	73.58	OK
2243	2026-09-11 23:57	67.59	OK	2244	2026-09-11 23:58	68.72	OK
2245	2026-09-11 23:59	71.85	OK	2246	2026-09-12 00:00	69.30	OK
2247	2026-09-12 00:01	67.66	OK	2248	2026-09-12 00:02	69.57	OK
2249	2026-09-12 00:03	68.47	OK	2250	2026-09-12 00:04	70.57	OK
2251	2026-09-12 00:05	65.75	OK	2252	2026-09-12 00:06	70.40	OK
2253	2026-09-12 00:07	72.29	OK	2254	2026-09-12 00:08	70.13	OK
2255	2026-09-12 00:09	71.85	OK	2256	2026-09-12 00:10	68.82	OK
2257	2026-09-12 00:11	69.47	OK	2258	2026-09-12 00:12	69.38	OK
2259	2026-09-12 00:13	68.07	OK	2260	2026-09-12 00:14	68.39	OK
2261	2026-09-12 00:15	67.98	OK	2262	2026-09-12 00:16	68.52	OK
2263	2026-09-12 00:17	68.97	OK	2264	2026-09-12 00:18	66.15	OK
2265	2026-09-12 00:19	71.17	OK	2266	2026-09-12 00:20	68.21	OK
2267	2026-09-12 00:21	68.46	OK	2268	2026-09-12 00:22	68.15	OK
2269	2026-09-12 00:23	68.76	OK	2270	2026-09-12 00:24	69.26	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2271	2026-09-12 00:25	67.63	OK	2272	2026-09-12 00:26	68.97	OK
2273	2026-09-12 00:27	69.94	OK	2274	2026-09-12 00:28	71.94	OK
2275	2026-09-12 00:29	69.69	OK	2276	2026-09-12 00:30	69.53	OK
2277	2026-09-12 00:31	70.66	OK	2278	2026-09-12 00:32	69.38	OK
2279	2026-09-12 00:33	68.00	OK	2280	2026-09-12 00:34	70.55	OK
2281	2026-09-12 00:35	71.22	OK	2282	2026-09-12 00:36	67.93	OK
2283	2026-09-12 00:37	70.15	OK	2284	2026-09-12 00:38	67.54	OK
2285	2026-09-12 00:39	68.58	OK	2286	2026-09-12 00:40	70.34	OK
2287	2026-09-12 00:41	67.75	OK	2288	2026-09-12 00:42	69.63	OK
2289	2026-09-12 00:43	69.24	OK	2290	2026-09-12 00:44	70.30	OK
2291	2026-09-12 00:45	70.92	OK	2292	2026-09-12 00:46	69.75	OK
2293	2026-09-12 00:47	71.79	OK	2294	2026-09-12 00:48	68.24	OK
2295	2026-09-12 00:49	68.03	OK	2296	2026-09-12 00:50	69.91	OK
2297	2026-09-12 00:51	70.02	OK	2298	2026-09-12 00:52	72.36	OK
2299	2026-09-12 00:53	66.55	OK	2300	2026-09-12 00:54	69.45	OK
2301	2026-09-12 00:55	67.92	OK	2302	2026-09-12 00:56	69.70	OK
2303	2026-09-12 00:57	68.11	OK	2304	2026-09-12 00:58	68.85	OK
2305	2026-09-12 00:59	69.56	OK	2306	2026-09-12 01:00	69.55	OK
2307	2026-09-12 01:01	68.26	OK	2308	2026-09-12 01:02	70.82	OK
2309	2026-09-12 01:03	69.29	OK	2310	2026-09-12 01:04	67.88	OK
2311	2026-09-12 01:05	70.93	OK	2312	2026-09-12 01:06	70.08	OK
2313	2026-09-12 01:07	69.37	OK	2314	2026-09-12 01:08	68.81	OK
2315	2026-09-12 01:09	67.95	OK	2316	2026-09-12 01:10	68.16	OK
2317	2026-09-12 01:11	71.43	OK	2318	2026-09-12 01:12	67.86	OK
2319	2026-09-12 01:13	70.98	OK	2320	2026-09-12 01:14	67.66	OK
2321	2026-09-12 01:15	70.86	OK	2322	2026-09-12 01:16	70.24	OK
2323	2026-09-12 01:17	70.82	OK	2324	2026-09-12 01:18	73.13	OK
2325	2026-09-12 01:19	68.01	OK	2326	2026-09-12 01:20	66.37	OK
2327	2026-09-12 01:21	70.23	OK	2328	2026-09-12 01:22	67.11	OK
2329	2026-09-12 01:23	70.45	OK	2330	2026-09-12 01:24	68.81	OK
2331	2026-09-12 01:25	71.88	OK	2332	2026-09-12 01:26	67.76	OK
2333	2026-09-12 01:27	71.72	OK	2334	2026-09-12 01:28	68.54	OK
2335	2026-09-12 01:29	71.07	OK	2336	2026-09-12 01:30	69.08	OK
2337	2026-09-12 01:31	68.56	OK	2338	2026-09-12 01:32	70.96	OK
2339	2026-09-12 01:33	69.19	OK	2340	2026-09-12 01:34	72.87	OK
2341	2026-09-12 01:35	67.95	OK	2342	2026-09-12 01:36	68.58	OK
2343	2026-09-12 01:37	69.45	OK	2344	2026-09-12 01:38	67.73	OK
2345	2026-09-12 01:39	70.57	OK	2346	2026-09-12 01:40	69.29	OK
2347	2026-09-12 01:41	69.16	OK	2348	2026-09-12 01:42	68.92	OK
2349	2026-09-12 01:43	69.68	OK	2350	2026-09-12 01:44	70.51	OK
2351	2026-09-12 01:45	69.99	OK	2352	2026-09-12 01:46	69.44	OK
2353	2026-09-12 01:47	68.56	OK	2354	2026-09-12 01:48	68.14	OK
2355	2026-09-12 01:49	67.28	OK	2356	2026-09-12 01:50	65.90	OK
2357	2026-09-12 01:51	68.29	OK	2358	2026-09-12 01:52	69.34	OK
2359	2026-09-12 01:53	70.20	OK	2360	2026-09-12 01:54	68.28	OK
2361	2026-09-12 01:55	70.91	OK	2362	2026-09-12 01:56	67.97	OK
2363	2026-09-12 01:57	71.19	OK	2364	2026-09-12 01:58	69.12	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2365	2026-09-12 01:59	68.06	OK	2366	2026-09-12 02:00	68.53	OK
2367	2026-09-12 02:01	70.02	OK	2368	2026-09-12 02:02	70.58	OK
2369	2026-09-12 02:03	68.04	OK	2370	2026-09-12 02:04	69.51	OK
2371	2026-09-12 02:05	68.18	OK	2372	2026-09-12 02:06	71.01	OK
2373	2026-09-12 02:07	67.79	OK	2374	2026-09-12 02:08	70.28	OK
2375	2026-09-12 02:09	66.16	OK	2376	2026-09-12 02:10	66.86	OK
2377	2026-09-12 02:11	67.82	OK	2378	2026-09-12 02:12	70.03	OK
2379	2026-09-12 02:13	70.42	OK	2380	2026-09-12 02:14	67.71	OK
2381	2026-09-12 02:15	70.93	OK	2382	2026-09-12 02:16	67.54	OK
2383	2026-09-12 02:17	71.73	OK	2384	2026-09-12 02:18	69.48	OK
2385	2026-09-12 02:19	69.48	OK	2386	2026-09-12 02:20	71.38	OK
2387	2026-09-12 02:21	69.90	OK	2388	2026-09-12 02:22	69.65	OK
2389	2026-09-12 02:23	69.20	OK	2390	2026-09-12 02:24	68.84	OK
2391	2026-09-12 02:25	69.06	OK	2392	2026-09-12 02:26	73.02	OK
2393	2026-09-12 02:27	71.38	OK	2394	2026-09-12 02:28	71.20	OK
2395	2026-09-12 02:29	69.20	OK	2396	2026-09-12 02:30	70.36	OK
2397	2026-09-12 02:31	70.59	OK	2398	2026-09-12 02:32	70.69	OK
2399	2026-09-12 02:33	70.31	OK	2400	2026-09-12 02:34	69.36	OK
2401	2026-09-12 02:35	68.30	OK	2402	2026-09-12 02:36	67.65	OK
2403	2026-09-12 02:37	71.96	OK	2404	2026-09-12 02:38	71.22	OK
2405	2026-09-12 02:39	71.95	OK	2406	2026-09-12 02:40	68.01	OK
2407	2026-09-12 02:41	69.31	OK	2408	2026-09-12 02:42	69.90	OK
2409	2026-09-12 02:43	67.83	OK	2410	2026-09-12 02:44	73.24	OK
2411	2026-09-12 02:45	70.65	OK	2412	2026-09-12 02:46	71.63	OK
2413	2026-09-12 02:47	69.06	OK	2414	2026-09-12 02:48	68.33	OK
2415	2026-09-12 02:49	73.16	OK	2416	2026-09-12 02:50	68.33	OK
2417	2026-09-12 02:51	70.34	OK	2418	2026-09-12 02:52	68.77	OK
2419	2026-09-12 02:53	71.15	OK	2420	2026-09-12 02:54	73.50	OK
2421	2026-09-12 02:55	70.09	OK	2422	2026-09-12 02:56	70.08	OK
2423	2026-09-12 02:57	69.48	OK	2424	2026-09-12 02:58	73.41	OK
2425	2026-09-12 02:59	70.99	OK	2426	2026-09-12 03:00	69.78	OK
2427	2026-09-12 03:01	70.92	OK	2428	2026-09-12 03:02	71.05	OK
2429	2026-09-12 03:03	69.08	OK	2430	2026-09-12 03:04	70.10	OK
2431	2026-09-12 03:05	66.55	OK	2432	2026-09-12 03:06	72.15	OK
2433	2026-09-12 03:07	71.12	OK	2434	2026-09-12 03:08	70.24	OK
2435	2026-09-12 03:09	72.50	OK	2436	2026-09-12 03:10	72.74	OK
2437	2026-09-12 03:11	71.42	OK	2438	2026-09-12 03:12	70.39	OK
2439	2026-09-12 03:13	66.11	OK	2440	2026-09-12 03:14	71.97	OK
2441	2026-09-12 03:15	69.44	OK	2442	2026-09-12 03:16	71.07	OK
2443	2026-09-12 03:17	70.99	OK	2444	2026-09-12 03:18	72.24	OK
2445	2026-09-12 03:19	73.78	OK	2446	2026-09-12 03:20	70.70	OK
2447	2026-09-12 03:21	71.20	OK	2448	2026-09-12 03:22	69.20	OK
2449	2026-09-12 03:23	68.41	OK	2450	2026-09-12 03:24	71.34	OK
2451	2026-09-12 03:25	70.75	OK	2452	2026-09-12 03:26	73.08	OK
2453	2026-09-12 03:27	72.14	OK	2454	2026-09-12 03:28	69.65	OK
2455	2026-09-12 03:29	71.76	OK	2456	2026-09-12 03:30	68.56	OK
2457	2026-09-12 03:31	69.46	OK	2458	2026-09-12 03:32	69.30	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2459	2026-09-12 03:33	71.03	OK	2460	2026-09-12 03:34	70.66	OK
2461	2026-09-12 03:35	69.67	OK	2462	2026-09-12 03:36	72.61	OK
2463	2026-09-12 03:37	69.06	OK	2464	2026-09-12 03:38	69.57	OK
2465	2026-09-12 03:39	72.09	OK	2466	2026-09-12 03:40	72.15	OK
2467	2026-09-12 03:41	71.05	OK	2468	2026-09-12 03:42	70.04	OK
2469	2026-09-12 03:43	71.14	OK	2470	2026-09-12 03:44	70.48	OK
2471	2026-09-12 03:45	71.24	OK	2472	2026-09-12 03:46	69.21	OK
2473	2026-09-12 03:47	70.52	OK	2474	2026-09-12 03:48	71.79	OK
2475	2026-09-12 03:49	68.15	OK	2476	2026-09-12 03:50	70.53	OK
2477	2026-09-12 03:51	70.31	OK	2478	2026-09-12 03:52	70.41	OK
2479	2026-09-12 03:53	70.89	OK	2480	2026-09-12 03:54	68.94	OK
2481	2026-09-12 03:55	70.86	OK	2482	2026-09-12 03:56	72.17	OK
2483	2026-09-12 03:57	70.91	OK	2484	2026-09-12 03:58	70.85	OK
2485	2026-09-12 03:59	71.39	OK	2486	2026-09-12 04:00	68.52	OK
2487	2026-09-12 04:01	72.01	OK	2488	2026-09-12 04:02	69.27	OK
2489	2026-09-12 04:03	72.99	OK	2490	2026-09-12 04:04	73.47	OK
2491	2026-09-12 04:05	67.87	OK	2492	2026-09-12 04:06	71.34	OK
2493	2026-09-12 04:07	69.27	OK	2494	2026-09-12 04:08	72.27	OK
2495	2026-09-12 04:09	73.75	OK	2496	2026-09-12 04:10	71.83	OK
2497	2026-09-12 04:11	71.93	OK	2498	2026-09-12 04:12	73.84	OK
2499	2026-09-12 04:13	68.97	OK	2500	2026-09-12 04:14	73.75	OK
2501	2026-09-12 04:15	73.02	OK	2502	2026-09-12 04:16	72.03	OK
2503	2026-09-12 04:17	72.72	OK	2504	2026-09-12 04:18	71.73	OK
2505	2026-09-12 04:19	74.28	OK	2506	2026-09-12 04:20	72.37	OK
2507	2026-09-12 04:21	70.41	OK	2508	2026-09-12 04:22	73.44	OK
2509	2026-09-12 04:23	70.87	OK	2510	2026-09-12 04:24	70.57	OK
2511	2026-09-12 04:25	74.33	OK	2512	2026-09-12 04:26	71.56	OK
2513	2026-09-12 04:27	69.01	OK	2514	2026-09-12 04:28	74.85	OK
2515	2026-09-12 04:29	71.23	OK	2516	2026-09-12 04:30	75.00	OK
2517	2026-09-12 04:31	74.14	OK	2518	2026-09-12 04:32	74.90	OK
2519	2026-09-12 04:33	69.44	OK	2520	2026-09-12 04:34	72.92	OK
2521	2026-09-12 04:35	71.48	OK	2522	2026-09-12 04:36	73.85	OK
2523	2026-09-12 04:37	68.99	OK	2524	2026-09-12 04:38	71.30	OK
2525	2026-09-12 04:39	70.58	OK	2526	2026-09-12 04:40	71.04	OK
2527	2026-09-12 04:41	70.01	OK	2528	2026-09-12 04:42	73.12	OK
2529	2026-09-12 04:43	70.49	OK	2530	2026-09-12 04:44	73.50	OK
2531	2026-09-12 04:45	72.46	OK	2532	2026-09-12 04:46	73.23	OK
2533	2026-09-12 04:47	70.98	OK	2534	2026-09-12 04:48	74.10	OK
2535	2026-09-12 04:49	69.27	OK	2536	2026-09-12 04:50	73.31	OK
2537	2026-09-12 04:51	72.59	OK	2538	2026-09-12 04:52	72.03	OK
2539	2026-09-12 04:53	69.39	OK	2540	2026-09-12 04:54	71.74	OK
2541	2026-09-12 04:55	71.82	OK	2542	2026-09-12 04:56	70.38	OK
2543	2026-09-12 04:57	72.29	OK	2544	2026-09-12 04:58	72.82	OK
2545	2026-09-12 04:59	71.61	OK	2546	2026-09-12 05:00	76.05	OK
2547	2026-09-12 05:01	75.10	OK	2548	2026-09-12 05:02	72.03	OK
2549	2026-09-12 05:03	73.15	OK	2550	2026-09-12 05:04	71.24	OK
2551	2026-09-12 05:05	75.02	OK	2552	2026-09-12 05:06	70.49	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2553	2026-09-12 05:07	73.43	OK	2554	2026-09-12 05:08	70.06	OK
2555	2026-09-12 05:09	70.50	OK	2556	2026-09-12 05:10	73.37	OK
2557	2026-09-12 05:11	72.88	OK	2558	2026-09-12 05:12	72.51	OK
2559	2026-09-12 05:13	75.05	OK	2560	2026-09-12 05:14	73.01	OK
2561	2026-09-12 05:15	70.59	OK	2562	2026-09-12 05:16	73.21	OK
2563	2026-09-12 05:17	72.28	OK	2564	2026-09-12 05:18	72.10	OK
2565	2026-09-12 05:19	72.60	OK	2566	2026-09-12 05:20	72.88	OK
2567	2026-09-12 05:21	72.65	OK	2568	2026-09-12 05:22	72.81	OK
2569	2026-09-12 05:23	74.30	OK	2570	2026-09-12 05:24	73.59	OK
2571	2026-09-12 05:25	74.54	OK	2572	2026-09-12 05:26	75.15	OK
2573	2026-09-12 05:27	72.69	OK	2574	2026-09-12 05:28	73.21	OK
2575	2026-09-12 05:29	73.79	OK	2576	2026-09-12 05:30	73.59	OK
2577	2026-09-12 05:31	72.78	OK	2578	2026-09-12 05:32	73.75	OK
2579	2026-09-12 05:33	72.34	OK	2580	2026-09-12 05:34	71.59	OK
2581	2026-09-12 05:35	75.11	OK	2582	2026-09-12 05:36	73.79	OK
2583	2026-09-12 05:37	72.86	OK	2584	2026-09-12 05:38	72.44	OK
2585	2026-09-12 05:39	72.75	OK	2586	2026-09-12 05:40	76.06	OK
2587	2026-09-12 05:41	75.38	OK	2588	2026-09-12 05:42	72.97	OK
2589	2026-09-12 05:43	74.27	OK	2590	2026-09-12 05:44	72.67	OK
2591	2026-09-12 05:45	73.40	OK	2592	2026-09-12 05:46	72.99	OK
2593	2026-09-12 05:47	74.86	OK	2594	2026-09-12 05:48	74.57	OK
2595	2026-09-12 05:49	74.34	OK	2596	2026-09-12 05:50	70.52	OK
2597	2026-09-12 05:51	73.57	OK	2598	2026-09-12 05:52	71.64	OK
2599	2026-09-12 05:53	72.36	OK	2600	2026-09-12 05:54	74.79	OK
2601	2026-09-12 05:55	72.12	OK	2602	2026-09-12 05:56	75.02	OK
2603	2026-09-12 05:57	75.57	OK	2604	2026-09-12 05:58	74.03	OK
2605	2026-09-12 05:59	73.61	OK	2606	2026-09-12 06:00	71.77	OK
2607	2026-09-12 06:01	75.53	OK	2608	2026-09-12 06:02	74.48	OK
2609	2026-09-12 06:03	76.62	OK	2610	2026-09-12 06:04	73.60	OK
2611	2026-09-12 06:05	75.78	OK	2612	2026-09-12 06:06	72.63	OK
2613	2026-09-12 06:07	76.41	OK	2614	2026-09-12 06:08	71.82	OK
2615	2026-09-12 06:09	75.27	OK	2616	2026-09-12 06:10	73.64	OK
2617	2026-09-12 06:11	73.29	OK	2618	2026-09-12 06:12	73.83	OK
2619	2026-09-12 06:13	73.19	OK	2620	2026-09-12 06:14	74.87	OK
2621	2026-09-12 06:15	71.96	OK	2622	2026-09-12 06:16	72.13	OK
2623	2026-09-12 06:17	75.04	OK	2624	2026-09-12 06:18	73.49	OK
2625	2026-09-12 06:19	73.07	OK	2626	2026-09-12 06:20	74.14	OK
2627	2026-09-12 06:21	74.32	OK	2628	2026-09-12 06:22	74.30	OK
2629	2026-09-12 06:23	74.20	OK	2630	2026-09-12 06:24	76.04	OK
2631	2026-09-12 06:25	74.16	OK	2632	2026-09-12 06:26	75.67	OK
2633	2026-09-12 06:27	76.82	OK	2634	2026-09-12 06:28	75.10	OK
2635	2026-09-12 06:29	71.87	OK	2636	2026-09-12 06:30	74.66	OK
2637	2026-09-12 06:31	71.60	OK	2638	2026-09-12 06:32	75.23	OK
2639	2026-09-12 06:33	71.64	OK	2640	2026-09-12 06:34	71.56	OK
2641	2026-09-12 06:35	72.97	OK	2642	2026-09-12 06:36	75.68	OK
2643	2026-09-12 06:37	76.87	OK	2644	2026-09-12 06:38	72.11	OK
2645	2026-09-12 06:39	74.77	OK	2646	2026-09-12 06:40	72.46	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2647	2026-09-12 06:41	75.49	OK	2648	2026-09-12 06:42	75.93	OK
2649	2026-09-12 06:43	76.66	OK	2650	2026-09-12 06:44	75.89	OK
2651	2026-09-12 06:45	71.89	OK	2652	2026-09-12 06:46	74.36	OK
2653	2026-09-12 06:47	76.95	OK	2654	2026-09-12 06:48	76.32	OK
2655	2026-09-12 06:49	73.72	OK	2656	2026-09-12 06:50	75.07	OK
2657	2026-09-12 06:51	74.31	OK	2658	2026-09-12 06:52	73.08	OK
2659	2026-09-12 06:53	72.61	OK	2660	2026-09-12 06:54	71.25	OK
2661	2026-09-12 06:55	74.49	OK	2662	2026-09-12 06:56	74.83	OK
2663	2026-09-12 06:57	74.11	OK	2664	2026-09-12 06:58	74.38	OK
2665	2026-09-12 06:59	75.52	OK	2666	2026-09-12 07:00	74.19	OK
2667	2026-09-12 07:01	75.81	OK	2668	2026-09-12 07:02	75.17	OK
2669	2026-09-12 07:03	73.30	OK	2670	2026-09-12 07:04	77.11	OK
2671	2026-09-12 07:05	73.83	OK	2672	2026-09-12 07:06	77.36	OK
2673	2026-09-12 07:07	75.73	OK	2674	2026-09-12 07:08	77.09	OK
2675	2026-09-12 07:09	79.14	OK	2676	2026-09-12 07:10	76.88	OK
2677	2026-09-12 07:11	76.33	OK	2678	2026-09-12 07:12	75.11	OK
2679	2026-09-12 07:13	73.36	OK	2680	2026-09-12 07:14	76.15	OK
2681	2026-09-12 07:15	74.25	OK	2682	2026-09-12 07:16	76.96	OK
2683	2026-09-12 07:17	77.79	OK	2684	2026-09-12 07:18	78.08	OK
2685	2026-09-12 07:19	73.78	OK	2686	2026-09-12 07:20	77.71	OK
2687	2026-09-12 07:21	77.54	OK	2688	2026-09-12 07:22	76.56	OK
2689	2026-09-12 07:23	74.96	OK	2690	2026-09-12 07:24	80.05	OK
2691	2026-09-12 07:25	75.87	OK	2692	2026-09-12 07:26	76.51	OK
2693	2026-09-12 07:27	75.58	OK	2694	2026-09-12 07:28	78.17	OK
2695	2026-09-12 07:29	75.91	OK	2696	2026-09-12 07:30	77.17	OK
2697	2026-09-12 07:31	76.40	OK	2698	2026-09-12 07:32	78.94	OK
2699	2026-09-12 07:33	75.31	OK	2700	2026-09-12 07:34	74.46	OK
2701	2026-09-12 07:35	76.99	OK	2702	2026-09-12 07:36	76.64	OK
2703	2026-09-12 07:37	72.62	OK	2704	2026-09-12 07:38	77.52	OK
2705	2026-09-12 07:39	76.05	OK	2706	2026-09-12 07:40	77.03	OK
2707	2026-09-12 07:41	75.55	OK	2708	2026-09-12 07:42	76.46	OK
2709	2026-09-12 07:43	76.90	OK	2710	2026-09-12 07:44	75.55	OK
2711	2026-09-12 07:45	78.52	OK	2712	2026-09-12 07:46	78.05	OK
2713	2026-09-12 07:47	74.61	OK	2714	2026-09-12 07:48	72.90	OK
2715	2026-09-12 07:49	76.24	OK	2716	2026-09-12 07:50	75.17	OK
2717	2026-09-12 07:51	76.93	OK	2718	2026-09-12 07:52	77.11	OK
2719	2026-09-12 07:53	77.15	OK	2720	2026-09-12 07:54	77.83	OK
2721	2026-09-12 07:55	77.14	OK	2722	2026-09-12 07:56	75.26	OK
2723	2026-09-12 07:57	74.82	OK	2724	2026-09-12 07:58	77.29	OK
2725	2026-09-12 07:59	76.31	OK	2726	2026-09-12 08:00	79.24	OK
2727	2026-09-12 08:01	75.53	OK	2728	2026-09-12 08:02	77.22	OK
2729	2026-09-12 08:03	77.18	OK	2730	2026-09-12 08:04	75.94	OK
2731	2026-09-12 08:05	77.83	OK	2732	2026-09-12 08:06	78.29	OK
2733	2026-09-12 08:07	76.19	OK	2734	2026-09-12 08:08	78.53	OK
2735	2026-09-12 08:09	79.02	OK	2736	2026-09-12 08:10	77.84	OK
2737	2026-09-12 08:11	78.13	OK	2738	2026-09-12 08:12	75.39	OK
2739	2026-09-12 08:13	75.87	OK	2740	2026-09-12 08:14	80.43	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2741	2026-09-12 08:15	77.69	OK	2742	2026-09-12 08:16	76.99	OK
2743	2026-09-12 08:17	76.67	OK	2744	2026-09-12 08:18	75.42	OK
2745	2026-09-12 08:19	74.98	OK	2746	2026-09-12 08:20	75.59	OK
2747	2026-09-12 08:21	78.06	OK	2748	2026-09-12 08:22	75.82	OK
2749	2026-09-12 08:23	76.49	OK	2750	2026-09-12 08:24	77.54	OK
2751	2026-09-12 08:25	77.28	OK	2752	2026-09-12 08:26	80.12	OK
2753	2026-09-12 08:27	77.67	OK	2754	2026-09-12 08:28	77.01	OK
2755	2026-09-12 08:29	76.55	OK	2756	2026-09-12 08:30	75.47	OK
2757	2026-09-12 08:31	81.17	OK	2758	2026-09-12 08:32	76.21	OK
2759	2026-09-12 08:33	77.04	OK	2760	2026-09-12 08:34	77.98	OK
2761	2026-09-12 08:35	74.68	OK	2762	2026-09-12 08:36	77.78	OK
2763	2026-09-12 08:37	77.39	OK	2764	2026-09-12 08:38	77.32	OK
2765	2026-09-12 08:39	76.70	OK	2766	2026-09-12 08:40	78.59	OK
2767	2026-09-12 08:41	76.47	OK	2768	2026-09-12 08:42	75.68	OK
2769	2026-09-12 08:43	78.33	OK	2770	2026-09-12 08:44	77.35	OK
2771	2026-09-12 08:45	78.48	OK	2772	2026-09-12 08:46	78.03	OK
2773	2026-09-12 08:47	77.03	OK	2774	2026-09-12 08:48	78.75	OK
2775	2026-09-12 08:49	77.58	OK	2776	2026-09-12 08:50	77.93	OK
2777	2026-09-12 08:51	78.99	OK	2778	2026-09-12 08:52	80.93	OK
2779	2026-09-12 08:53	79.05	OK	2780	2026-09-12 08:54	76.23	OK
2781	2026-09-12 08:55	76.09	OK	2782	2026-09-12 08:56	79.10	OK
2783	2026-09-12 08:57	79.05	OK	2784	2026-09-12 08:58	78.90	OK
2785	2026-09-12 08:59	79.23	OK	2786	2026-09-12 09:00	77.29	OK
2787	2026-09-12 09:01	80.03	OK	2788	2026-09-12 09:02	77.55	OK
2789	2026-09-12 09:03	78.51	OK	2790	2026-09-12 09:04	79.28	OK
2791	2026-09-12 09:05	79.96	OK	2792	2026-09-12 09:06	75.70	OK
2793	2026-09-12 09:07	77.17	OK	2794	2026-09-12 09:08	75.73	OK
2795	2026-09-12 09:09	76.27	OK	2796	2026-09-12 09:10	78.59	OK
2797	2026-09-12 09:11	79.94	OK	2798	2026-09-12 09:12	76.67	OK
2799	2026-09-12 09:13	82.10	OK	2800	2026-09-12 09:14	78.49	OK
2801	2026-09-12 09:15	78.32	OK	2802	2026-09-12 09:16	79.78	OK
2803	2026-09-12 09:17	77.87	OK	2804	2026-09-12 09:18	79.20	OK
2805	2026-09-12 09:19	77.65	OK	2806	2026-09-12 09:20	78.43	OK
2807	2026-09-12 09:21	78.31	OK	2808	2026-09-12 09:22	78.16	OK
2809	2026-09-12 09:23	79.61	OK	2810	2026-09-12 09:24	78.04	OK
2811	2026-09-12 09:25	79.44	OK	2812	2026-09-12 09:26	75.51	OK
2813	2026-09-12 09:27	78.94	OK	2814	2026-09-12 09:28	75.70	OK
2815	2026-09-12 09:29	77.57	OK	2816	2026-09-12 09:30	78.83	OK
2817	2026-09-12 09:31	80.24	OK	2818	2026-09-12 09:32	78.63	OK
2819	2026-09-12 09:33	76.20	OK	2820	2026-09-12 09:34	79.50	OK
2821	2026-09-12 09:35	78.65	OK	2822	2026-09-12 09:36	79.46	OK
2823	2026-09-12 09:37	81.46	OK	2824	2026-09-12 09:38	78.24	OK
2825	2026-09-12 09:39	77.58	OK	2826	2026-09-12 09:40	76.60	OK
2827	2026-09-12 09:41	78.31	OK	2828	2026-09-12 09:42	79.79	OK
2829	2026-09-12 09:43	79.64	OK	2830	2026-09-12 09:44	79.65	OK
2831	2026-09-12 09:45	78.58	OK	2832	2026-09-12 09:46	75.70	OK
2833	2026-09-12 09:47	78.21	OK	2834	2026-09-12 09:48	77.70	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2835	2026-09-12 09:49	82.90	OK	2836	2026-09-12 09:50	78.91	OK
2837	2026-09-12 09:51	79.16	OK	2838	2026-09-12 09:52	80.43	OK
2839	2026-09-12 09:53	78.80	OK	2840	2026-09-12 09:54	77.25	OK
2841	2026-09-12 09:55	80.99	OK	2842	2026-09-12 09:56	80.90	OK
2843	2026-09-12 09:57	79.39	OK	2844	2026-09-12 09:58	80.18	OK
2845	2026-09-12 09:59	80.98	OK	2846	2026-09-12 10:00	79.63	OK
2847	2026-09-12 10:01	78.39	OK	2848	2026-09-12 10:02	77.07	OK
2849	2026-09-12 10:03	80.33	OK	2850	2026-09-12 10:04	79.24	OK
2851	2026-09-12 10:05	78.20	OK	2852	2026-09-12 10:06	78.62	OK
2853	2026-09-12 10:07	78.80	OK	2854	2026-09-12 10:08	80.47	OK
2855	2026-09-12 10:09	79.37	OK	2856	2026-09-12 10:10	77.98	OK
2857	2026-09-12 10:11	77.69	OK	2858	2026-09-12 10:12	81.80	OK
2859	2026-09-12 10:13	78.88	OK	2860	2026-09-12 10:14	78.37	OK
2861	2026-09-12 10:15	77.97	OK	2862	2026-09-12 10:16	81.02	OK
2863	2026-09-12 10:17	79.45	OK	2864	2026-09-12 10:18	79.70	OK
2865	2026-09-12 10:19	79.54	OK	2866	2026-09-12 10:20	76.84	OK
2867	2026-09-12 10:21	81.58	OK	2868	2026-09-12 10:22	78.44	OK
2869	2026-09-12 10:23	77.59	OK	2870	2026-09-12 10:24	79.87	OK
2871	2026-09-12 10:25	79.80	OK	2872	2026-09-12 10:26	79.60	OK
2873	2026-09-12 10:27	80.43	OK	2874	2026-09-12 10:28	81.25	OK
2875	2026-09-12 10:29	78.96	OK	2876	2026-09-12 10:30	82.11	OK
2877	2026-09-12 10:31	83.01	OK	2878	2026-09-12 10:32	83.80	OK
2879	2026-09-12 10:33	83.44	OK	2880	2026-09-12 10:34	83.15	OK
2881	2026-09-12 10:35	79.56	OK	2882	2026-09-12 10:36	79.89	OK
2883	2026-09-12 10:37	80.49	OK	2884	2026-09-12 10:38	80.32	OK
2885	2026-09-12 10:39	80.36	OK	2886	2026-09-12 10:40	75.95	OK
2887	2026-09-12 10:41	77.85	OK	2888	2026-09-12 10:42	79.65	OK
2889	2026-09-12 10:43	78.38	OK	2890	2026-09-12 10:44	81.55	OK
2891	2026-09-12 10:45	82.49	OK	2892	2026-09-12 10:46	78.19	OK
2893	2026-09-12 10:47	76.98	OK	2894	2026-09-12 10:48	81.29	OK
2895	2026-09-12 10:49	80.16	OK	2896	2026-09-12 10:50	80.62	OK
2897	2026-09-12 10:51	80.56	OK	2898	2026-09-12 10:52	80.51	OK
2899	2026-09-12 10:53	79.77	OK	2900	2026-09-12 10:54	80.52	OK
2901	2026-09-12 10:55	79.93	OK	2902	2026-09-12 10:56	79.73	OK
2903	2026-09-12 10:57	77.43	OK	2904	2026-09-12 10:58	81.20	OK
2905	2026-09-12 10:59	83.20	OK	2906	2026-09-12 11:00	78.95	OK
2907	2026-09-12 11:01	81.19	OK	2908	2026-09-12 11:02	81.15	OK
2909	2026-09-12 11:03	78.49	OK	2910	2026-09-12 11:04	80.57	OK
2911	2026-09-12 11:05	80.19	OK	2912	2026-09-12 11:06	77.81	OK
2913	2026-09-12 11:07	80.15	OK	2914	2026-09-12 11:08	78.27	OK
2915	2026-09-12 11:09	80.71	OK	2916	2026-09-12 11:10	76.06	OK
2917	2026-09-12 11:11	82.43	OK	2918	2026-09-12 11:12	78.41	OK
2919	2026-09-12 11:13	81.31	OK	2920	2026-09-12 11:14	81.64	OK
2921	2026-09-12 11:15	79.39	OK	2922	2026-09-12 11:16	77.30	OK
2923	2026-09-12 11:17	83.10	OK	2924	2026-09-12 11:18	83.14	OK
2925	2026-09-12 11:19	80.36	OK	2926	2026-09-12 11:20	78.59	OK
2927	2026-09-12 11:21	81.82	OK	2928	2026-09-12 11:22	78.57	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2929	2026-09-12 11:23	82.84	OK	2930	2026-09-12 11:24	82.23	OK
2931	2026-09-12 11:25	81.24	OK	2932	2026-09-12 11:26	82.29	OK
2933	2026-09-12 11:27	82.55	OK	2934	2026-09-12 11:28	81.46	OK
2935	2026-09-12 11:29	77.26	OK	2936	2026-09-12 11:30	78.37	OK
2937	2026-09-12 11:31	75.82	OK	2938	2026-09-12 11:32	80.02	OK
2939	2026-09-12 11:33	78.11	OK	2940	2026-09-12 11:34	79.51	OK
2941	2026-09-12 11:35	80.19	OK	2942	2026-09-12 11:36	82.08	OK
2943	2026-09-12 11:37	82.54	OK	2944	2026-09-12 11:38	81.84	OK
2945	2026-09-12 11:39	81.46	OK	2946	2026-09-12 11:40	80.38	OK
2947	2026-09-12 11:41	79.27	OK	2948	2026-09-12 11:42	81.67	OK
2949	2026-09-12 11:43	79.13	OK	2950	2026-09-12 11:44	80.30	OK
2951	2026-09-12 11:45	83.62	OK	2952	2026-09-12 11:46	80.79	OK
2953	2026-09-12 11:47	79.89	OK	2954	2026-09-12 11:48	78.48	OK
2955	2026-09-12 11:49	79.42	OK	2956	2026-09-12 11:50	83.30	OK
2957	2026-09-12 11:51	82.27	OK	2958	2026-09-12 11:52	80.75	OK
2959	2026-09-12 11:53	82.58	OK	2960	2026-09-12 11:54	83.54	OK
2961	2026-09-12 11:55	80.00	OK	2962	2026-09-12 11:56	80.74	OK
2963	2026-09-12 11:57	79.90	OK	2964	2026-09-12 11:58	83.44	OK
2965	2026-09-12 11:59	78.11	OK	2966	2026-09-12 12:00	78.52	OK
2967	2026-09-12 12:01	80.24	OK	2968	2026-09-12 12:02	81.42	OK
2969	2026-09-12 12:03	78.73	OK	2970	2026-09-12 12:04	81.12	OK
2971	2026-09-12 12:05	78.00	OK	2972	2026-09-12 12:06	80.45	OK
2973	2026-09-12 12:07	79.34	OK	2974	2026-09-12 12:08	81.10	OK
2975	2026-09-12 12:09	81.22	OK	2976	2026-09-12 12:10	82.81	OK
2977	2026-09-12 12:11	77.35	OK	2978	2026-09-12 12:12	79.77	OK
2979	2026-09-12 12:13	80.53	OK	2980	2026-09-12 12:14	80.09	OK
2981	2026-09-12 12:15	83.38	OK	2982	2026-09-12 12:16	80.96	OK
2983	2026-09-12 12:17	78.99	OK	2984	2026-09-12 12:18	78.39	OK
2985	2026-09-12 12:19	80.09	OK	2986	2026-09-12 12:20	80.23	OK
2987	2026-09-12 12:21	78.34	OK	2988	2026-09-12 12:22	79.23	OK
2989	2026-09-12 12:23	83.24	OK	2990	2026-09-12 12:24	81.03	OK
2991	2026-09-12 12:25	84.39	OK	2992	2026-09-12 12:26	77.10	OK
2993	2026-09-12 12:27	85.27	OK	2994	2026-09-12 12:28	80.76	OK
2995	2026-09-12 12:29	83.48	OK	2996	2026-09-12 12:30	82.58	OK
2997	2026-09-12 12:31	84.38	OK	2998	2026-09-12 12:32	81.98	OK
2999	2026-09-12 12:33	78.03	OK	3000	2026-09-12 12:34	80.78	OK
3001	2026-09-12 12:35	82.15	OK	3002	2026-09-12 12:36	81.15	OK
3003	2026-09-12 12:37	81.51	OK	3004	2026-09-12 12:38	79.35	OK
3005	2026-09-12 12:39	81.04	OK	3006	2026-09-12 12:40	81.63	OK
3007	2026-09-12 12:41	81.00	OK	3008	2026-09-12 12:42	81.58	OK
3009	2026-09-12 12:43	78.50	OK	3010	2026-09-12 12:44	83.07	OK
3011	2026-09-12 12:45	83.66	OK	3012	2026-09-12 12:46	80.38	OK
3013	2026-09-12 12:47	81.08	OK	3014	2026-09-12 12:48	81.43	OK
3015	2026-09-12 12:49	81.76	OK	3016	2026-09-12 12:50	82.43	OK
3017	2026-09-12 12:51	80.04	OK	3018	2026-09-12 12:52	81.28	OK
3019	2026-09-12 12:53	80.68	OK	3020	2026-09-12 12:54	80.35	OK
3021	2026-09-12 12:55	80.90	OK	3022	2026-09-12 12:56	78.33	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3023	2026-09-12 12:57	79.61	OK	3024	2026-09-12 12:58	78.70	OK
3025	2026-09-12 12:59	82.69	OK	3026	2026-09-12 13:00	83.69	OK
3027	2026-09-12 13:01	82.79	OK	3028	2026-09-12 13:02	81.51	OK
3029	2026-09-12 13:03	80.94	OK	3030	2026-09-12 13:04	79.28	OK
3031	2026-09-12 13:05	83.70	OK	3032	2026-09-12 13:06	82.75	OK
3033	2026-09-12 13:07	77.69	OK	3034	2026-09-12 13:08	82.29	OK
3035	2026-09-12 13:09	78.37	OK	3036	2026-09-12 13:10	80.02	OK
3037	2026-09-12 13:11	80.08	OK	3038	2026-09-12 13:12	82.87	OK
3039	2026-09-12 13:13	80.80	OK	3040	2026-09-12 13:14	80.11	OK
3041	2026-09-12 13:15	80.98	OK	3042	2026-09-12 13:16	81.93	OK
3043	2026-09-12 13:17	81.39	OK	3044	2026-09-12 13:18	78.18	OK
3045	2026-09-12 13:19	79.66	OK	3046	2026-09-12 13:20	82.83	OK
3047	2026-09-12 13:21	82.03	OK	3048	2026-09-12 13:22	82.15	OK
3049	2026-09-12 13:23	81.34	OK	3050	2026-09-12 13:24	80.89	OK
3051	2026-09-12 13:25	82.96	OK	3052	2026-09-12 13:26	78.56	OK
3053	2026-09-12 13:27	78.87	OK	3054	2026-09-12 13:28	79.65	OK
3055	2026-09-12 13:29	83.01	OK	3056	2026-09-12 13:30	80.87	OK
3057	2026-09-12 13:31	81.18	OK	3058	2026-09-12 13:32	80.09	OK
3059	2026-09-12 13:33	82.37	OK	3060	2026-09-12 13:34	83.17	OK
3061	2026-09-12 13:35	79.45	OK	3062	2026-09-12 13:36	79.99	OK
3063	2026-09-12 13:37	82.86	OK	3064	2026-09-12 13:38	80.32	OK
3065	2026-09-12 13:39	80.17	OK	3066	2026-09-12 13:40	79.09	OK
3067	2026-09-12 13:41	83.39	OK	3068	2026-09-12 13:42	83.95	OK
3069	2026-09-12 13:43	80.40	OK	3070	2026-09-12 13:44	81.84	OK
3071	2026-09-12 13:45	78.20	OK	3072	2026-09-12 13:46	80.49	OK
3073	2026-09-12 13:47	80.58	OK	3074	2026-09-12 13:48	82.88	OK
3075	2026-09-12 13:49	77.32	OK	3076	2026-09-12 13:50	79.49	OK
3077	2026-09-12 13:51	83.69	OK	3078	2026-09-12 13:52	81.41	OK
3079	2026-09-12 13:53	84.43	OK	3080	2026-09-12 13:54	82.88	OK
3081	2026-09-12 13:55	80.22	OK	3082	2026-09-12 13:56	81.48	OK
3083	2026-09-12 13:57	80.15	OK	3084	2026-09-12 13:58	78.97	OK
3085	2026-09-12 13:59	77.58	OK	3086	2026-09-12 14:00	81.39	OK
3087	2026-09-12 14:01	79.64	OK	3088	2026-09-12 14:02	83.45	OK
3089	2026-09-12 14:03	82.90	OK	3090	2026-09-12 14:04	80.73	OK
3091	2026-09-12 14:05	78.03	OK	3092	2026-09-12 14:06	81.56	OK
3093	2026-09-12 14:07	81.29	OK	3094	2026-09-12 14:08	79.94	OK
3095	2026-09-12 14:09	78.77	OK	3096	2026-09-12 14:10	82.42	OK
3097	2026-09-12 14:11	82.34	OK	3098	2026-09-12 14:12	80.19	OK
3099	2026-09-12 14:13	79.98	OK	3100	2026-09-12 14:14	82.11	OK
3101	2026-09-12 14:15	81.43	OK	3102	2026-09-12 14:16	79.61	OK
3103	2026-09-12 14:17	80.99	OK	3104	2026-09-12 14:18	80.90	OK
3105	2026-09-12 14:19	80.41	OK	3106	2026-09-12 14:20	79.34	OK
3107	2026-09-12 14:21	81.63	OK	3108	2026-09-12 14:22	82.91	OK
3109	2026-09-12 14:23	80.49	OK	3110	2026-09-12 14:24	82.22	OK
3111	2026-09-12 14:25	80.51	OK	3112	2026-09-12 14:26	79.36	OK
3113	2026-09-12 14:27	79.14	OK	3114	2026-09-12 14:28	83.09	OK
3115	2026-09-12 14:29	76.61	OK	3116	2026-09-12 14:30	77.01	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3117	2026-09-12 14:31	79.08	OK	3118	2026-09-12 14:32	83.44	OK
3119	2026-09-12 14:33	82.52	OK	3120	2026-09-12 14:34	82.61	OK
3121	2026-09-12 14:35	77.50	OK	3122	2026-09-12 14:36	79.15	OK
3123	2026-09-12 14:37	81.96	OK	3124	2026-09-12 14:38	80.03	OK
3125	2026-09-12 14:39	77.88	OK	3126	2026-09-12 14:40	82.03	OK
3127	2026-09-12 14:41	79.48	OK	3128	2026-09-12 14:42	82.36	OK
3129	2026-09-12 14:43	82.52	OK	3130	2026-09-12 14:44	81.46	OK
3131	2026-09-12 14:45	84.02	OK	3132	2026-09-12 14:46	81.14	OK
3133	2026-09-12 14:47	83.08	OK	3134	2026-09-12 14:48	79.37	OK
3135	2026-09-12 14:49	81.30	OK	3136	2026-09-12 14:50	81.42	OK
3137	2026-09-12 14:51	81.54	OK	3138	2026-09-12 14:52	80.38	OK
3139	2026-09-12 14:53	79.62	OK	3140	2026-09-12 14:54	80.23	OK
3141	2026-09-12 14:55	80.69	OK	3142	2026-09-12 14:56	77.29	OK
3143	2026-09-12 14:57	80.23	OK	3144	2026-09-12 14:58	76.86	OK
3145	2026-09-12 14:59	78.89	OK	3146	2026-09-12 15:00	80.12	OK
3147	2026-09-12 15:01	79.27	OK	3148	2026-09-12 15:02	79.92	OK
3149	2026-09-12 15:03	77.62	OK	3150	2026-09-12 15:04	77.60	OK
3151	2026-09-12 15:05	82.36	OK	3152	2026-09-12 15:06	79.23	OK
3153	2026-09-12 15:07	79.74	OK	3154	2026-09-12 15:08	83.00	OK
3155	2026-09-12 15:09	79.78	OK	3156	2026-09-12 15:10	81.82	OK
3157	2026-09-12 15:11	77.11	OK	3158	2026-09-12 15:12	79.10	OK
3159	2026-09-12 15:13	79.80	OK	3160	2026-09-12 15:14	80.29	OK
3161	2026-09-12 15:15	80.83	OK	3162	2026-09-12 15:16	78.13	OK
3163	2026-09-12 15:17	82.38	OK	3164	2026-09-12 15:18	81.77	OK
3165	2026-09-12 15:19	79.85	OK	3166	2026-09-12 15:20	79.79	OK
3167	2026-09-12 15:21	79.20	OK	3168	2026-09-12 15:22	82.63	OK
3169	2026-09-12 15:23	79.45	OK	3170	2026-09-12 15:24	78.60	OK
3171	2026-09-12 15:25	78.83	OK	3172	2026-09-12 15:26	81.17	OK
3173	2026-09-12 15:27	79.79	OK	3174	2026-09-12 15:28	81.37	OK
3175	2026-09-12 15:29	79.18	OK	3176	2026-09-12 15:30	77.67	OK
3177	2026-09-12 15:31	79.49	OK	3178	2026-09-12 15:32	78.62	OK
3179	2026-09-12 15:33	80.78	OK	3180	2026-09-12 15:34	83.19	OK
3181	2026-09-12 15:35	77.02	OK	3182	2026-09-12 15:36	81.69	OK
3183	2026-09-12 15:37	78.44	OK	3184	2026-09-12 15:38	79.19	OK
3185	2026-09-12 15:39	77.48	OK	3186	2026-09-12 15:40	76.58	OK
3187	2026-09-12 15:41	78.25	OK	3188	2026-09-12 15:42	81.92	OK
3189	2026-09-12 15:43	78.56	OK	3190	2026-09-12 15:44	77.96	OK
3191	2026-09-12 15:45	80.26	OK	3192	2026-09-12 15:46	78.93	OK
3193	2026-09-12 15:47	77.81	OK	3194	2026-09-12 15:48	79.35	OK
3195	2026-09-12 15:49	79.08	OK	3196	2026-09-12 15:50	80.40	OK
3197	2026-09-12 15:51	78.09	OK	3198	2026-09-12 15:52	78.94	OK
3199	2026-09-12 15:53	79.31	OK	3200	2026-09-12 15:54	77.70	OK
3201	2026-09-12 15:55	81.12	OK	3202	2026-09-12 15:56	79.35	OK
3203	2026-09-12 15:57	77.60	OK	3204	2026-09-12 15:58	78.29	OK
3205	2026-09-12 15:59	78.30	OK	3206	2026-09-12 16:00	79.47	OK
3207	2026-09-12 16:01	79.28	OK	3208	2026-09-12 16:02	77.52	OK
3209	2026-09-12 16:03	79.83	OK	3210	2026-09-12 16:04	77.30	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3211	2026-09-12 16:05	78.05	OK	3212	2026-09-12 16:06	78.51	OK
3213	2026-09-12 16:07	80.81	OK	3214	2026-09-12 16:08	78.12	OK
3215	2026-09-12 16:09	77.85	OK	3216	2026-09-12 16:10	78.41	OK
3217	2026-09-12 16:11	78.18	OK	3218	2026-09-12 16:12	79.92	OK
3219	2026-09-12 16:13	79.74	OK	3220	2026-09-12 16:14	80.59	OK
3221	2026-09-12 16:15	79.55	OK	3222	2026-09-12 16:16	79.98	OK
3223	2026-09-12 16:17	80.56	OK	3224	2026-09-12 16:18	79.81	OK
3225	2026-09-12 16:19	78.45	OK	3226	2026-09-12 16:20	77.94	OK
3227	2026-09-12 16:21	77.68	OK	3228	2026-09-12 16:22	75.15	OK
3229	2026-09-12 16:23	77.00	OK	3230	2026-09-12 16:24	77.94	OK
3231	2026-09-12 16:25	79.41	OK	3232	2026-09-12 16:26	80.96	OK
3233	2026-09-12 16:27	78.99	OK	3234	2026-09-12 16:28	77.50	OK
3235	2026-09-12 16:29	78.97	OK	3236	2026-09-12 16:30	75.67	OK
3237	2026-09-12 16:31	81.59	OK	3238	2026-09-12 16:32	77.46	OK
3239	2026-09-12 16:33	76.83	OK	3240	2026-09-12 16:34	77.99	OK
3241	2026-09-12 16:35	75.97	OK	3242	2026-09-12 16:36	76.97	OK
3243	2026-09-12 16:37	78.41	OK	3244	2026-09-12 16:38	79.35	OK
3245	2026-09-12 16:39	77.43	OK	3246	2026-09-12 16:40	79.73	OK
3247	2026-09-12 16:41	76.99	OK	3248	2026-09-12 16:42	80.57	OK
3249	2026-09-12 16:43	76.64	OK	3250	2026-09-12 16:44	78.23	OK
3251	2026-09-12 16:45	77.19	OK	3252	2026-09-12 16:46	77.30	OK
3253	2026-09-12 16:47	75.12	OK	3254	2026-09-12 16:48	77.76	OK
3255	2026-09-12 16:49	74.85	OK	3256	2026-09-12 16:50	77.91	OK
3257	2026-09-12 16:51	78.90	OK	3258	2026-09-12 16:52	76.08	OK
3259	2026-09-12 16:53	78.49	OK	3260	2026-09-12 16:54	80.47	OK
3261	2026-09-12 16:55	78.26	OK	3262	2026-09-12 16:56	78.55	OK
3263	2026-09-12 16:57	78.42	OK	3264	2026-09-12 16:58	74.62	OK
3265	2026-09-12 16:59	76.43	OK	3266	2026-09-12 17:00	80.32	OK
3267	2026-09-12 17:01	79.37	OK	3268	2026-09-12 17:02	78.99	OK
3269	2026-09-12 17:03	78.60	OK	3270	2026-09-12 17:04	79.06	OK
3271	2026-09-12 17:05	78.57	OK	3272	2026-09-12 17:06	78.24	OK
3273	2026-09-12 17:07	79.06	OK	3274	2026-09-12 17:08	79.04	OK
3275	2026-09-12 17:09	77.11	OK	3276	2026-09-12 17:10	75.85	OK
3277	2026-09-12 17:11	76.26	OK	3278	2026-09-12 17:12	77.45	OK
3279	2026-09-12 17:13	78.69	OK	3280	2026-09-12 17:14	74.99	OK
3281	2026-09-12 17:15	79.72	OK	3282	2026-09-12 17:16	79.33	OK
3283	2026-09-12 17:17	77.04	OK	3284	2026-09-12 17:18	77.06	OK
3285	2026-09-12 17:19	77.31	OK	3286	2026-09-12 17:20	77.87	OK
3287	2026-09-12 17:21	79.86	OK	3288	2026-09-12 17:22	79.23	OK
3289	2026-09-12 17:23	76.64	OK	3290	2026-09-12 17:24	77.30	OK
3291	2026-09-12 17:25	75.48	OK	3292	2026-09-12 17:26	74.79	OK
3293	2026-09-12 17:27	75.12	OK	3294	2026-09-12 17:28	80.47	OK
3295	2026-09-12 17:29	74.82	OK	3296	2026-09-12 17:30	77.71	OK
3297	2026-09-12 17:31	77.72	OK	3298	2026-09-12 17:32	77.62	OK
3299	2026-09-12 17:33	75.23	OK	3300	2026-09-12 17:34	77.39	OK
3301	2026-09-12 17:35	77.40	OK	3302	2026-09-12 17:36	77.66	OK
3303	2026-09-12 17:37	80.01	OK	3304	2026-09-12 17:38	78.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3305	2026-09-12 17:39	76.06	OK	3306	2026-09-12 17:40	78.23	OK
3307	2026-09-12 17:41	77.81	OK	3308	2026-09-12 17:42	79.39	OK
3309	2026-09-12 17:43	76.78	OK	3310	2026-09-12 17:44	77.20	OK
3311	2026-09-12 17:45	73.56	OK	3312	2026-09-12 17:46	79.61	OK
3313	2026-09-12 17:47	77.93	OK	3314	2026-09-12 17:48	77.28	OK
3315	2026-09-12 17:49	76.16	OK	3316	2026-09-12 17:50	78.09	OK
3317	2026-09-12 17:51	74.73	OK	3318	2026-09-12 17:52	79.46	OK
3319	2026-09-12 17:53	77.98	OK	3320	2026-09-12 17:54	76.72	OK
3321	2026-09-12 17:55	76.17	OK	3322	2026-09-12 17:56	78.59	OK
3323	2026-09-12 17:57	77.87	OK	3324	2026-09-12 17:58	77.69	OK
3325	2026-09-12 17:59	76.02	OK	3326	2026-09-12 18:00	75.38	OK
3327	2026-09-12 18:01	77.45	OK	3328	2026-09-12 18:02	77.67	OK
3329	2026-09-12 18:03	76.34	OK	3330	2026-09-12 18:04	75.28	OK
3331	2026-09-12 18:05	76.00	OK	3332	2026-09-12 18:06	76.93	OK
3333	2026-09-12 18:07	76.34	OK	3334	2026-09-12 18:08	76.21	OK
3335	2026-09-12 18:09	78.78	OK	3336	2026-09-12 18:10	77.04	OK
3337	2026-09-12 18:11	74.34	OK	3338	2026-09-12 18:12	77.81	OK
3339	2026-09-12 18:13	79.24	OK	3340	2026-09-12 18:14	75.18	OK
3341	2026-09-12 18:15	75.68	OK	3342	2026-09-12 18:16	75.94	OK
3343	2026-09-12 18:17	76.73	OK	3344	2026-09-12 18:18	75.88	OK
3345	2026-09-12 18:19	76.49	OK	3346	2026-09-12 18:20	77.30	OK
3347	2026-09-12 18:21	78.34	OK	3348	2026-09-12 18:22	73.77	OK
3349	2026-09-12 18:23	77.66	OK	3350	2026-09-12 18:24	74.66	OK
3351	2026-09-12 18:25	76.68	OK	3352	2026-09-12 18:26	76.19	OK
3353	2026-09-12 18:27	77.81	OK	3354	2026-09-12 18:28	79.00	OK
3355	2026-09-12 18:29	79.11	OK	3356	2026-09-12 18:30	75.95	OK
3357	2026-09-12 18:31	74.08	OK	3358	2026-09-12 18:32	71.52	OK
3359	2026-09-12 18:33	74.20	OK	3360	2026-09-12 18:34	74.62	OK
3361	2026-09-12 18:35	74.57	OK	3362	2026-09-12 18:36	74.20	OK
3363	2026-09-12 18:37	78.46	OK	3364	2026-09-12 18:38	75.32	OK
3365	2026-09-12 18:39	76.92	OK	3366	2026-09-12 18:40	76.50	OK
3367	2026-09-12 18:41	77.05	OK	3368	2026-09-12 18:42	77.99	OK
3369	2026-09-12 18:43	73.68	OK	3370	2026-09-12 18:44	75.39	OK
3371	2026-09-12 18:45	76.73	OK	3372	2026-09-12 18:46	76.71	OK
3373	2026-09-12 18:47	77.10	OK	3374	2026-09-12 18:48	74.72	OK
3375	2026-09-12 18:49	71.16	OK	3376	2026-09-12 18:50	75.10	OK
3377	2026-09-12 18:51	74.64	OK	3378	2026-09-12 18:52	74.92	OK
3379	2026-09-12 18:53	76.35	OK	3380	2026-09-12 18:54	73.03	OK
3381	2026-09-12 18:55	78.42	OK	3382	2026-09-12 18:56	75.50	OK
3383	2026-09-12 18:57	76.97	OK	3384	2026-09-12 18:58	76.07	OK
3385	2026-09-12 18:59	74.72	OK	3386	2026-09-12 19:00	75.86	OK
3387	2026-09-12 19:01	73.67	OK	3388	2026-09-12 19:02	74.25	OK
3389	2026-09-12 19:03	74.39	OK	3390	2026-09-12 19:04	74.93	OK
3391	2026-09-12 19:05	75.03	OK	3392	2026-09-12 19:06	76.16	OK
3393	2026-09-12 19:07	75.49	OK	3394	2026-09-12 19:08	73.68	OK
3395	2026-09-12 19:09	76.75	OK	3396	2026-09-12 19:10	73.93	OK
3397	2026-09-12 19:11	76.19	OK	3398	2026-09-12 19:12	74.49	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3399	2026-09-12 19:13	74.67	OK	3400	2026-09-12 19:14	71.95	OK
3401	2026-09-12 19:15	74.78	OK	3402	2026-09-12 19:16	74.52	OK
3403	2026-09-12 19:17	74.70	OK	3404	2026-09-12 19:18	75.61	OK
3405	2026-09-12 19:19	75.29	OK	3406	2026-09-12 19:20	77.54	OK
3407	2026-09-12 19:21	74.76	OK	3408	2026-09-12 19:22	76.42	OK
3409	2026-09-12 19:23	76.79	OK	3410	2026-09-12 19:24	73.26	OK
3411	2026-09-12 19:25	74.22	OK	3412	2026-09-12 19:26	75.18	OK
3413	2026-09-12 19:27	72.75	OK	3414	2026-09-12 19:28	72.94	OK
3415	2026-09-12 19:29	73.12	OK	3416	2026-09-12 19:30	70.51	OK
3417	2026-09-12 19:31	73.86	OK	3418	2026-09-12 19:32	72.21	OK
3419	2026-09-12 19:33	77.13	OK	3420	2026-09-12 19:34	77.94	OK
3421	2026-09-12 19:35	73.10	OK	3422	2026-09-12 19:36	76.27	OK
3423	2026-09-12 19:37	71.59	OK	3424	2026-09-12 19:38	73.90	OK
3425	2026-09-12 19:39	75.45	OK	3426	2026-09-12 19:40	74.11	OK
3427	2026-09-12 19:41	74.67	OK	3428	2026-09-12 19:42	72.31	OK
3429	2026-09-12 19:43	78.59	OK	3430	2026-09-12 19:44	75.03	OK
3431	2026-09-12 19:45	74.45	OK	3432	2026-09-12 19:46	73.88	OK
3433	2026-09-12 19:47	76.30	OK	3434	2026-09-12 19:48	70.51	OK
3435	2026-09-12 19:49	76.53	OK	3436	2026-09-12 19:50	74.19	OK
3437	2026-09-12 19:51	75.66	OK	3438	2026-09-12 19:52	73.21	OK
3439	2026-09-12 19:53	73.37	OK	3440	2026-09-12 19:54	72.97	OK
3441	2026-09-12 19:55	73.36	OK	3442	2026-09-12 19:56	73.85	OK
3443	2026-09-12 19:57	73.81	OK	3444	2026-09-12 19:58	73.92	OK
3445	2026-09-12 19:59	76.55	OK	3446	2026-09-12 20:00	72.15	OK
3447	2026-09-12 20:01	70.91	OK	3448	2026-09-12 20:02	72.47	OK
3449	2026-09-12 20:03	73.60	OK	3450	2026-09-12 20:04	71.14	OK
3451	2026-09-12 20:05	73.06	OK	3452	2026-09-12 20:06	73.85	OK
3453	2026-09-12 20:07	75.06	OK	3454	2026-09-12 20:08	72.25	OK
3455	2026-09-12 20:09	74.87	OK	3456	2026-09-12 20:10	74.55	OK
3457	2026-09-12 20:11	72.13	OK	3458	2026-09-12 20:12	76.61	OK
3459	2026-09-12 20:13	73.86	OK	3460	2026-09-12 20:14	71.62	OK
3461	2026-09-12 20:15	76.62	OK	3462	2026-09-12 20:16	76.03	OK
3463	2026-09-12 20:17	70.03	OK	3464	2026-09-12 20:18	74.12	OK
3465	2026-09-12 20:19	75.89	OK	3466	2026-09-12 20:20	75.43	OK
3467	2026-09-12 20:21	71.75	OK	3468	2026-09-12 20:22	71.68	OK
3469	2026-09-12 20:23	73.77	OK	3470	2026-09-12 20:24	71.56	OK
3471	2026-09-12 20:25	72.17	OK	3472	2026-09-12 20:26	70.32	OK
3473	2026-09-12 20:27	74.40	OK	3474	2026-09-12 20:28	73.73	OK
3475	2026-09-12 20:29	73.44	OK	3476	2026-09-12 20:30	74.55	OK
3477	2026-09-12 20:31	73.34	OK	3478	2026-09-12 20:32	71.47	OK
3479	2026-09-12 20:33	73.93	OK	3480	2026-09-12 20:34	72.42	OK
3481	2026-09-12 20:35	73.37	OK	3482	2026-09-12 20:36	70.00	OK
3483	2026-09-12 20:37	74.11	OK	3484	2026-09-12 20:38	71.43	OK
3485	2026-09-12 20:39	73.37	OK	3486	2026-09-12 20:40	74.19	OK
3487	2026-09-12 20:41	72.78	OK	3488	2026-09-12 20:42	72.32	OK
3489	2026-09-12 20:43	72.15	OK	3490	2026-09-12 20:44	74.05	OK
3491	2026-09-12 20:45	73.33	OK	3492	2026-09-12 20:46	71.76	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3493	2026-09-12 20:47	71.59	OK	3494	2026-09-12 20:48	70.97	OK
3495	2026-09-12 20:49	71.96	OK	3496	2026-09-12 20:50	71.01	OK
3497	2026-09-12 20:51	72.69	OK	3498	2026-09-12 20:52	74.19	OK
3499	2026-09-12 20:53	72.11	OK	3500	2026-09-12 20:54	71.33	OK
3501	2026-09-12 20:55	72.28	OK	3502	2026-09-12 20:56	71.88	OK
3503	2026-09-12 20:57	71.34	OK	3504	2026-09-12 20:58	73.03	OK
3505	2026-09-12 20:59	71.66	OK	3506	2026-09-12 21:00	70.41	OK
3507	2026-09-12 21:01	73.11	OK	3508	2026-09-12 21:02	70.74	OK
3509	2026-09-12 21:03	72.74	OK	3510	2026-09-12 21:04	72.13	OK
3511	2026-09-12 21:05	72.40	OK	3512	2026-09-12 21:06	71.76	OK
3513	2026-09-12 21:07	71.95	OK	3514	2026-09-12 21:08	72.64	OK
3515	2026-09-12 21:09	73.12	OK	3516	2026-09-12 21:10	71.81	OK
3517	2026-09-12 21:11	74.94	OK	3518	2026-09-12 21:12	69.17	OK
3519	2026-09-12 21:13	74.75	OK	3520	2026-09-12 21:14	68.80	OK
3521	2026-09-12 21:15	75.04	OK	3522	2026-09-12 21:16	68.56	OK
3523	2026-09-12 21:17	73.23	OK	3524	2026-09-12 21:18	69.79	OK
3525	2026-09-12 21:19	72.42	OK	3526	2026-09-12 21:20	74.15	OK
3527	2026-09-12 21:21	72.25	OK	3528	2026-09-12 21:22	71.80	OK
3529	2026-09-12 21:23	71.61	OK	3530	2026-09-12 21:24	72.45	OK
3531	2026-09-12 21:25	68.99	OK	3532	2026-09-12 21:26	73.18	OK
3533	2026-09-12 21:27	75.15	OK	3534	2026-09-12 21:28	72.85	OK
3535	2026-09-12 21:29	71.14	OK	3536	2026-09-12 21:30	70.46	OK
3537	2026-09-12 21:31	69.92	OK	3538	2026-09-12 21:32	73.30	OK
3539	2026-09-12 21:33	71.62	OK	3540	2026-09-12 21:34	70.71	OK
3541	2026-09-12 21:35	70.92	OK	3542	2026-09-12 21:36	69.23	OK
3543	2026-09-12 21:37	70.18	OK	3544	2026-09-12 21:38	71.06	OK
3545	2026-09-12 21:39	70.47	OK	3546	2026-09-12 21:40	73.25	OK
3547	2026-09-12 21:41	71.55	OK	3548	2026-09-12 21:42	73.69	OK
3549	2026-09-12 21:43	72.04	OK	3550	2026-09-12 21:44	70.52	OK
3551	2026-09-12 21:45	73.28	OK	3552	2026-09-12 21:46	74.38	OK
3553	2026-09-12 21:47	73.78	OK	3554	2026-09-12 21:48	70.58	OK
3555	2026-09-12 21:49	68.07	OK	3556	2026-09-12 21:50	69.88	OK
3557	2026-09-12 21:51	69.92	OK	3558	2026-09-12 21:52	72.46	OK
3559	2026-09-12 21:53	71.27	OK	3560	2026-09-12 21:54	72.34	OK
3561	2026-09-12 21:55	69.68	OK	3562	2026-09-12 21:56	69.82	OK
3563	2026-09-12 21:57	70.78	OK	3564	2026-09-12 21:58	69.37	OK
3565	2026-09-12 21:59	69.38	OK	3566	2026-09-12 22:00	71.64	OK
3567	2026-09-12 22:01	71.68	OK	3568	2026-09-12 22:02	69.69	OK
3569	2026-09-12 22:03	67.46	OK	3570	2026-09-12 22:04	73.90	OK
3571	2026-09-12 22:05	69.74	OK	3572	2026-09-12 22:06	74.75	OK
3573	2026-09-12 22:07	68.99	OK	3574	2026-09-12 22:08	70.59	OK
3575	2026-09-12 22:09	71.18	OK	3576	2026-09-12 22:10	69.94	OK
3577	2026-09-12 22:11	69.68	OK	3578	2026-09-12 22:12	69.96	OK
3579	2026-09-12 22:13	69.65	OK	3580	2026-09-12 22:14	71.21	OK
3581	2026-09-12 22:15	72.66	OK	3582	2026-09-12 22:16	70.75	OK
3583	2026-09-12 22:17	71.06	OK	3584	2026-09-12 22:18	70.70	OK
3585	2026-09-12 22:19	71.51	OK	3586	2026-09-12 22:20	70.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3587	2026-09-12 22:21	72.09	OK	3588	2026-09-12 22:22	69.83	OK
3589	2026-09-12 22:23	70.06	OK	3590	2026-09-12 22:24	70.27	OK
3591	2026-09-12 22:25	67.08	OK	3592	2026-09-12 22:26	70.95	OK
3593	2026-09-12 22:27	72.00	OK	3594	2026-09-12 22:28	70.03	OK
3595	2026-09-12 22:29	71.93	OK	3596	2026-09-12 22:30	70.86	OK
3597	2026-09-12 22:31	70.56	OK	3598	2026-09-12 22:32	69.62	OK
3599	2026-09-12 22:33	70.75	OK	3600	2026-09-12 22:34	71.79	OK
3601	2026-09-12 22:35	70.04	OK	3602	2026-09-12 22:36	72.04	OK
3603	2026-09-12 22:37	70.27	OK	3604	2026-09-12 22:38	67.82	OK
3605	2026-09-12 22:39	68.93	OK	3606	2026-09-12 22:40	72.20	OK
3607	2026-09-12 22:41	72.28	OK	3608	2026-09-12 22:42	69.67	OK
3609	2026-09-12 22:43	71.06	OK	3610	2026-09-12 22:44	68.10	OK
3611	2026-09-12 22:45	70.26	OK	3612	2026-09-12 22:46	69.49	OK
3613	2026-09-12 22:47	69.83	OK	3614	2026-09-12 22:48	70.63	OK
3615	2026-09-12 22:49	69.50	OK	3616	2026-09-12 22:50	72.22	OK
3617	2026-09-12 22:51	66.99	OK	3618	2026-09-12 22:52	69.97	OK
3619	2026-09-12 22:53	71.42	OK	3620	2026-09-12 22:54	70.27	OK
3621	2026-09-12 22:55	68.70	OK	3622	2026-09-12 22:56	68.53	OK
3623	2026-09-12 22:57	69.11	OK	3624	2026-09-12 22:58	70.40	OK
3625	2026-09-12 22:59	71.37	OK	3626	2026-09-12 23:00	66.46	OK
3627	2026-09-12 23:01	70.50	OK	3628	2026-09-12 23:02	73.06	OK
3629	2026-09-12 23:03	69.32	OK	3630	2026-09-12 23:04	68.30	OK
3631	2026-09-12 23:05	69.52	OK	3632	2026-09-12 23:06	68.62	OK
3633	2026-09-12 23:07	73.45	OK	3634	2026-09-12 23:08	67.75	OK
3635	2026-09-12 23:09	69.80	OK	3636	2026-09-12 23:10	69.86	OK
3637	2026-09-12 23:11	69.36	OK	3638	2026-09-12 23:12	71.41	OK
3639	2026-09-12 23:13	70.83	OK	3640	2026-09-12 23:14	72.16	OK
3641	2026-09-12 23:15	66.56	OK	3642	2026-09-12 23:16	73.59	OK
3643	2026-09-12 23:17	68.76	OK	3644	2026-09-12 23:18	69.87	OK
3645	2026-09-12 23:19	69.79	OK	3646	2026-09-12 23:20	69.98	OK
3647	2026-09-12 23:21	68.29	OK	3648	2026-09-12 23:22	69.18	OK
3649	2026-09-12 23:23	72.76	OK	3650	2026-09-12 23:24	67.97	OK
3651	2026-09-12 23:25	68.44	OK	3652	2026-09-12 23:26	70.61	OK
3653	2026-09-12 23:27	69.38	OK	3654	2026-09-12 23:28	69.96	OK
3655	2026-09-12 23:29	67.25	OK	3656	2026-09-12 23:30	71.00	OK
3657	2026-09-12 23:31	73.44	OK	3658	2026-09-12 23:32	70.01	OK
3659	2026-09-12 23:33	68.52	OK	3660	2026-09-12 23:34	71.67	OK
3661	2026-09-12 23:35	69.56	OK	3662	2026-09-12 23:36	66.87	OK
3663	2026-09-12 23:37	68.32	OK	3664	2026-09-12 23:38	68.50	OK
3665	2026-09-12 23:39	68.81	OK	3666	2026-09-12 23:40	69.69	OK
3667	2026-09-12 23:41	67.42	OK	3668	2026-09-12 23:42	69.15	OK
3669	2026-09-12 23:43	71.95	OK	3670	2026-09-12 23:44	67.17	OK
3671	2026-09-12 23:45	71.60	OK	3672	2026-09-12 23:46	73.98	OK
3673	2026-09-12 23:47	67.92	OK	3674	2026-09-12 23:48	69.09	OK
3675	2026-09-12 23:49	71.60	OK	3676	2026-09-12 23:50	66.54	OK
3677	2026-09-12 23:51	68.54	OK	3678	2026-09-12 23:52	70.00	OK
3679	2026-09-12 23:53	67.13	OK	3680	2026-09-12 23:54	70.97	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3681	2026-09-12 23:55	67.44	OK	3682	2026-09-12 23:56	71.80	OK
3683	2026-09-12 23:57	70.86	OK	3684	2026-09-12 23:58	71.15	OK
3685	2026-09-12 23:59	69.78	OK	3686	2026-09-13 00:00	67.54	OK
3687	2026-09-13 00:01	67.67	OK	3688	2026-09-13 00:02	68.40	OK
3689	2026-09-13 00:03	68.67	OK	3690	2026-09-13 00:04	68.46	OK
3691	2026-09-13 00:05	66.68	OK	3692	2026-09-13 00:06	69.12	OK
3693	2026-09-13 00:07	68.33	OK	3694	2026-09-13 00:08	72.22	OK
3695	2026-09-13 00:09	71.63	OK	3696	2026-09-13 00:10	67.67	OK
3697	2026-09-13 00:11	67.62	OK	3698	2026-09-13 00:12	67.55	OK
3699	2026-09-13 00:13	69.78	OK	3700	2026-09-13 00:14	70.80	OK
3701	2026-09-13 00:15	68.18	OK	3702	2026-09-13 00:16	69.81	OK
3703	2026-09-13 00:17	69.87	OK	3704	2026-09-13 00:18	71.11	OK
3705	2026-09-13 00:19	68.81	OK	3706	2026-09-13 00:20	68.43	OK
3707	2026-09-13 00:21	66.49	OK	3708	2026-09-13 00:22	69.42	OK
3709	2026-09-13 00:23	70.31	OK	3710	2026-09-13 00:24	70.61	OK
3711	2026-09-13 00:25	69.58	OK	3712	2026-09-13 00:26	67.85	OK
3713	2026-09-13 00:27	68.83	OK	3714	2026-09-13 00:28	70.89	OK
3715	2026-09-13 00:29	71.25	OK	3716	2026-09-13 00:30	70.77	OK
3717	2026-09-13 00:31	65.95	OK	3718	2026-09-13 00:32	67.06	OK
3719	2026-09-13 00:33	70.73	OK	3720	2026-09-13 00:34	70.16	OK
3721	2026-09-13 00:35	69.41	OK	3722	2026-09-13 00:36	68.75	OK
3723	2026-09-13 00:37	69.21	OK	3724	2026-09-13 00:38	68.45	OK
3725	2026-09-13 00:39	68.63	OK	3726	2026-09-13 00:40	71.41	OK
3727	2026-09-13 00:41	66.32	OK	3728	2026-09-13 00:42	69.41	OK
3729	2026-09-13 00:43	68.72	OK	3730	2026-09-13 00:44	69.14	OK
3731	2026-09-13 00:45	68.99	OK	3732	2026-09-13 00:46	68.19	OK
3733	2026-09-13 00:47	69.66	OK	3734	2026-09-13 00:48	69.66	OK
3735	2026-09-13 00:49	66.45	OK	3736	2026-09-13 00:50	69.77	OK
3737	2026-09-13 00:51	68.70	OK	3738	2026-09-13 00:52	70.01	OK
3739	2026-09-13 00:53	69.69	OK	3740	2026-09-13 00:54	66.73	OK
3741	2026-09-13 00:55	67.69	OK	3742	2026-09-13 00:56	72.72	OK
3743	2026-09-13 00:57	70.93	OK	3744	2026-09-13 00:58	70.90	OK
3745	2026-09-13 00:59	66.77	OK	3746	2026-09-13 01:00	68.53	OK
3747	2026-09-13 01:01	71.26	OK	3748	2026-09-13 01:02	68.38	OK
3749	2026-09-13 01:03	69.87	OK	3750	2026-09-13 01:04	68.78	OK
3751	2026-09-13 01:05	67.90	OK	3752	2026-09-13 01:06	70.00	OK
3753	2026-09-13 01:07	69.49	OK	3754	2026-09-13 01:08	66.31	OK
3755	2026-09-13 01:09	69.28	OK	3756	2026-09-13 01:10	70.30	OK
3757	2026-09-13 01:11	69.30	OK	3758	2026-09-13 01:12	69.42	OK
3759	2026-09-13 01:13	70.92	OK	3760	2026-09-13 01:14	73.32	OK
3761	2026-09-13 01:15	69.42	OK	3762	2026-09-13 01:16	71.38	OK
3763	2026-09-13 01:17	67.73	OK	3764	2026-09-13 01:18	70.06	OK
3765	2026-09-13 01:19	70.90	OK	3766	2026-09-13 01:20	70.27	OK
3767	2026-09-13 01:21	72.16	OK	3768	2026-09-13 01:22	70.47	OK
3769	2026-09-13 01:23	68.13	OK	3770	2026-09-13 01:24	68.22	OK
3771	2026-09-13 01:25	67.01	OK	3772	2026-09-13 01:26	70.52	OK
3773	2026-09-13 01:27	68.80	OK	3774	2026-09-13 01:28	68.82	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3775	2026-09-13 01:29	69.40	OK	3776	2026-09-13 01:30	71.50	OK
3777	2026-09-13 01:31	69.29	OK	3778	2026-09-13 01:32	69.05	OK
3779	2026-09-13 01:33	69.69	OK	3780	2026-09-13 01:34	70.48	OK
3781	2026-09-13 01:35	69.54	OK	3782	2026-09-13 01:36	69.28	OK
3783	2026-09-13 01:37	66.99	OK	3784	2026-09-13 01:38	68.09	OK
3785	2026-09-13 01:39	72.31	OK	3786	2026-09-13 01:40	66.23	OK
3787	2026-09-13 01:41	72.47	OK	3788	2026-09-13 01:42	68.66	OK
3789	2026-09-13 01:43	69.50	OK	3790	2026-09-13 01:44	70.45	OK
3791	2026-09-13 01:45	69.52	OK	3792	2026-09-13 01:46	71.51	OK
3793	2026-09-13 01:47	70.31	OK	3794	2026-09-13 01:48	71.54	OK
3795	2026-09-13 01:49	72.41	OK	3796	2026-09-13 01:50	72.88	OK
3797	2026-09-13 01:51	70.38	OK	3798	2026-09-13 01:52	68.86	OK
3799	2026-09-13 01:53	66.82	OK	3800	2026-09-13 01:54	66.20	OK
3801	2026-09-13 01:55	67.58	OK	3802	2026-09-13 01:56	68.47	OK
3803	2026-09-13 01:57	70.70	OK	3804	2026-09-13 01:58	70.40	OK
3805	2026-09-13 01:59	70.26	OK	3806	2026-09-13 02:00	70.38	OK
3807	2026-09-13 02:01	69.12	OK	3808	2026-09-13 02:02	70.48	OK
3809	2026-09-13 02:03	69.77	OK	3810	2026-09-13 02:04	68.70	OK
3811	2026-09-13 02:05	72.08	OK	3812	2026-09-13 02:06	69.77	OK
3813	2026-09-13 02:07	69.66	OK	3814	2026-09-13 02:08	66.78	OK
3815	2026-09-13 02:09	70.58	OK	3816	2026-09-13 02:10	71.14	OK
3817	2026-09-13 02:11	70.37	OK	3818	2026-09-13 02:12	72.01	OK
3819	2026-09-13 02:13	71.51	OK	3820	2026-09-13 02:14	70.62	OK
3821	2026-09-13 02:15	69.09	OK	3822	2026-09-13 02:16	70.00	OK
3823	2026-09-13 02:17	72.09	OK	3824	2026-09-13 02:18	70.78	OK
3825	2026-09-13 02:19	70.78	OK	3826	2026-09-13 02:20	70.23	OK
3827	2026-09-13 02:21	71.63	OK	3828	2026-09-13 02:22	68.28	OK
3829	2026-09-13 02:23	69.54	OK	3830	2026-09-13 02:24	69.50	OK
3831	2026-09-13 02:25	69.96	OK	3832	2026-09-13 02:26	72.92	OK
3833	2026-09-13 02:27	70.81	OK	3834	2026-09-13 02:28	70.46	OK
3835	2026-09-13 02:29	70.13	OK	3836	2026-09-13 02:30	71.72	OK
3837	2026-09-13 02:31	70.55	OK	3838	2026-09-13 02:32	67.77	OK
3839	2026-09-13 02:33	69.49	OK	3840	2026-09-13 02:34	68.95	OK
3841	2026-09-13 02:35	70.91	OK	3842	2026-09-13 02:36	68.19	OK
3843	2026-09-13 02:37	67.33	OK	3844	2026-09-13 02:38	70.16	OK
3845	2026-09-13 02:39	72.53	OK	3846	2026-09-13 02:40	69.96	OK
3847	2026-09-13 02:41	69.76	OK	3848	2026-09-13 02:42	68.30	OK
3849	2026-09-13 02:43	72.98	OK	3850	2026-09-13 02:44	72.69	OK
3851	2026-09-13 02:45	69.43	OK	3852	2026-09-13 02:46	71.18	OK
3853	2026-09-13 02:47	70.90	OK	3854	2026-09-13 02:48	70.03	OK
3855	2026-09-13 02:49	72.01	OK	3856	2026-09-13 02:50	72.15	OK
3857	2026-09-13 02:51	70.06	OK	3858	2026-09-13 02:52	69.08	OK
3859	2026-09-13 02:53	67.12	OK	3860	2026-09-13 02:54	69.01	OK
3861	2026-09-13 02:55	70.85	OK	3862	2026-09-13 02:56	66.24	OK
3863	2026-09-13 02:57	70.26	OK	3864	2026-09-13 02:58	72.92	OK
3865	2026-09-13 02:59	69.90	OK	3866	2026-09-13 03:00	71.22	OK
3867	2026-09-13 03:01	69.74	OK	3868	2026-09-13 03:02	69.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3869	2026-09-13 03:03	70.26	OK	3870	2026-09-13 03:04	68.88	OK
3871	2026-09-13 03:05	68.86	OK	3872	2026-09-13 03:06	71.17	OK
3873	2026-09-13 03:07	71.36	OK	3874	2026-09-13 03:08	70.32	OK
3875	2026-09-13 03:09	72.22	OK	3876	2026-09-13 03:10	70.06	OK
3877	2026-09-13 03:11	69.47	OK	3878	2026-09-13 03:12	72.32	OK
3879	2026-09-13 03:13	67.22	OK	3880	2026-09-13 03:14	68.90	OK
3881	2026-09-13 03:15	69.09	OK	3882	2026-09-13 03:16	69.51	OK
3883	2026-09-13 03:17	72.87	OK	3884	2026-09-13 03:18	70.37	OK
3885	2026-09-13 03:19	70.11	OK	3886	2026-09-13 03:20	71.70	OK
3887	2026-09-13 03:21	69.40	OK	3888	2026-09-13 03:22	69.21	OK
3889	2026-09-13 03:23	70.65	OK	3890	2026-09-13 03:24	69.14	OK
3891	2026-09-13 03:25	66.99	OK	3892	2026-09-13 03:26	69.85	OK
3893	2026-09-13 03:27	70.59	OK	3894	2026-09-13 03:28	70.29	OK
3895	2026-09-13 03:29	72.33	OK	3896	2026-09-13 03:30	70.95	OK
3897	2026-09-13 03:31	72.76	OK	3898	2026-09-13 03:32	69.07	OK
3899	2026-09-13 03:33	70.41	OK	3900	2026-09-13 03:34	69.12	OK
3901	2026-09-13 03:35	67.35	OK	3902	2026-09-13 03:36	73.71	OK
3903	2026-09-13 03:37	69.03	OK	3904	2026-09-13 03:38	67.76	OK
3905	2026-09-13 03:39	67.73	OK	3906	2026-09-13 03:40	69.75	OK
3907	2026-09-13 03:41	69.36	OK	3908	2026-09-13 03:42	70.99	OK
3909	2026-09-13 03:43	68.13	OK	3910	2026-09-13 03:44	71.80	OK
3911	2026-09-13 03:45	71.22	OK	3912	2026-09-13 03:46	70.67	OK
3913	2026-09-13 03:47	71.26	OK	3914	2026-09-13 03:48	69.70	OK
3915	2026-09-13 03:49	72.38	OK	3916	2026-09-13 03:50	74.34	OK
3917	2026-09-13 03:51	70.99	OK	3918	2026-09-13 03:52	69.27	OK
3919	2026-09-13 03:53	69.36	OK	3920	2026-09-13 03:54	70.40	OK
3921	2026-09-13 03:55	71.51	OK	3922	2026-09-13 03:56	71.95	OK
3923	2026-09-13 03:57	72.24	OK	3924	2026-09-13 03:58	68.14	OK
3925	2026-09-13 03:59	67.03	OK	3926	2026-09-13 04:00	75.29	OK
3927	2026-09-13 04:01	68.13	OK	3928	2026-09-13 04:02	68.99	OK
3929	2026-09-13 04:03	73.23	OK	3930	2026-09-13 04:04	69.91	OK
3931	2026-09-13 04:05	72.63	OK	3932	2026-09-13 04:06	70.92	OK
3933	2026-09-13 04:07	72.30	OK	3934	2026-09-13 04:08	69.96	OK
3935	2026-09-13 04:09	72.18	OK	3936	2026-09-13 04:10	71.64	OK
3937	2026-09-13 04:11	71.97	OK	3938	2026-09-13 04:12	71.98	OK
3939	2026-09-13 04:13	70.17	OK	3940	2026-09-13 04:14	68.31	OK
3941	2026-09-13 04:15	71.50	OK	3942	2026-09-13 04:16	72.08	OK
3943	2026-09-13 04:17	73.84	OK	3944	2026-09-13 04:18	72.07	OK
3945	2026-09-13 04:19	69.48	OK	3946	2026-09-13 04:20	70.43	OK
3947	2026-09-13 04:21	72.14	OK	3948	2026-09-13 04:22	72.46	OK
3949	2026-09-13 04:23	73.81	OK	3950	2026-09-13 04:24	71.66	OK
3951	2026-09-13 04:25	71.63	OK	3952	2026-09-13 04:26	73.73	OK
3953	2026-09-13 04:27	71.62	OK	3954	2026-09-13 04:28	69.15	OK
3955	2026-09-13 04:29	72.12	OK	3956	2026-09-13 04:30	70.48	OK
3957	2026-09-13 04:31	69.03	OK	3958	2026-09-13 04:32	71.10	OK
3959	2026-09-13 04:33	69.39	OK	3960	2026-09-13 04:34	71.84	OK
3961	2026-09-13 04:35	72.08	OK	3962	2026-09-13 04:36	70.31	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3963	2026-09-13 04:37	72.31	OK	3964	2026-09-13 04:38	74.66	OK
3965	2026-09-13 04:39	71.50	OK	3966	2026-09-13 04:40	72.15	OK
3967	2026-09-13 04:41	71.84	OK	3968	2026-09-13 04:42	72.40	OK
3969	2026-09-13 04:43	69.50	OK	3970	2026-09-13 04:44	74.48	OK
3971	2026-09-13 04:45	72.65	OK	3972	2026-09-13 04:46	70.98	OK
3973	2026-09-13 04:47	74.69	OK	3974	2026-09-13 04:48	72.00	OK
3975	2026-09-13 04:49	75.98	OK	3976	2026-09-13 04:50	70.96	OK
3977	2026-09-13 04:51	72.31	OK	3978	2026-09-13 04:52	73.21	OK
3979	2026-09-13 04:53	72.99	OK	3980	2026-09-13 04:54	72.10	OK
3981	2026-09-13 04:55	69.92	OK	3982	2026-09-13 04:56	72.14	OK
3983	2026-09-13 04:57	70.94	OK	3984	2026-09-13 04:58	70.24	OK
3985	2026-09-13 04:59	74.27	OK	3986	2026-09-13 05:00	72.04	OK
3987	2026-09-13 05:01	73.05	OK	3988	2026-09-13 05:02	73.06	OK
3989	2026-09-13 05:03	73.95	OK	3990	2026-09-13 05:04	70.63	OK
3991	2026-09-13 05:05	73.97	OK	3992	2026-09-13 05:06	73.33	OK
3993	2026-09-13 05:07	72.07	OK	3994	2026-09-13 05:08	70.27	OK
3995	2026-09-13 05:09	71.82	OK	3996	2026-09-13 05:10	73.56	OK
3997	2026-09-13 05:11	72.30	OK	3998	2026-09-13 05:12	70.56	OK
3999	2026-09-13 05:13	73.57	OK	4000	2026-09-13 05:14	75.70	OK
4001	2026-09-13 05:15	72.85	OK	4002	2026-09-13 05:16	73.23	OK
4003	2026-09-13 05:17	72.42	OK	4004	2026-09-13 05:18	71.21	OK
4005	2026-09-13 05:19	71.33	OK	4006	2026-09-13 05:20	71.96	OK
4007	2026-09-13 05:21	73.12	OK	4008	2026-09-13 05:22	71.55	OK
4009	2026-09-13 05:23	73.30	OK	4010	2026-09-13 05:24	72.92	OK
4011	2026-09-13 05:25	72.40	OK	4012	2026-09-13 05:26	69.32	OK
4013	2026-09-13 05:27	73.20	OK	4014	2026-09-13 05:28	74.13	OK
4015	2026-09-13 05:29	72.80	OK	4016	2026-09-13 05:30	74.86	OK
4017	2026-09-13 05:31	72.81	OK	4018	2026-09-13 05:32	73.22	OK
4019	2026-09-13 05:33	71.30	OK	4020	2026-09-13 05:34	74.05	OK
4021	2026-09-13 05:35	72.33	OK	4022	2026-09-13 05:36	74.27	OK
4023	2026-09-13 05:37	74.34	OK	4024	2026-09-13 05:38	74.61	OK
4025	2026-09-13 05:39	72.14	OK	4026	2026-09-13 05:40	71.47	OK
4027	2026-09-13 05:41	72.19	OK	4028	2026-09-13 05:42	71.73	OK
4029	2026-09-13 05:43	69.84	OK	4030	2026-09-13 05:44	73.96	OK
4031	2026-09-13 05:45	72.20	OK	4032	2026-09-13 05:46	72.13	OK
4033	2026-09-13 05:47	72.63	OK	4034	2026-09-13 05:48	75.15	OK
4035	2026-09-13 05:49	73.91	OK	4036	2026-09-13 05:50	73.06	OK
4037	2026-09-13 05:51	70.59	OK	4038	2026-09-13 05:52	71.97	OK
4039	2026-09-13 05:53	74.03	OK	4040	2026-09-13 05:54	70.83	OK
4041	2026-09-13 05:55	72.68	OK	4042	2026-09-13 05:56	74.84	OK
4043	2026-09-13 05:57	75.10	OK	4044	2026-09-13 05:58	76.04	OK
4045	2026-09-13 05:59	73.60	OK	4046	2026-09-13 06:00	73.84	OK
4047	2026-09-13 06:01	71.18	OK	4048	2026-09-13 06:02	72.84	OK
4049	2026-09-13 06:03	74.79	OK	4050	2026-09-13 06:04	77.71	OK
4051	2026-09-13 06:05	72.31	OK	4052	2026-09-13 06:06	73.10	OK
4053	2026-09-13 06:07	77.00	OK	4054	2026-09-13 06:08	74.31	OK
4055	2026-09-13 06:09	75.84	OK	4056	2026-09-13 06:10	73.76	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4057	2026-09-13 06:11	72.17	OK	4058	2026-09-13 06:12	73.44	OK
4059	2026-09-13 06:13	75.37	OK	4060	2026-09-13 06:14	73.15	OK
4061	2026-09-13 06:15	74.90	OK	4062	2026-09-13 06:16	75.37	OK
4063	2026-09-13 06:17	73.07	OK	4064	2026-09-13 06:18	74.71	OK
4065	2026-09-13 06:19	74.43	OK	4066	2026-09-13 06:20	76.31	OK
4067	2026-09-13 06:21	74.32	OK	4068	2026-09-13 06:22	72.44	OK
4069	2026-09-13 06:23	77.37	OK	4070	2026-09-13 06:24	73.79	OK
4071	2026-09-13 06:25	70.84	OK	4072	2026-09-13 06:26	75.71	OK
4073	2026-09-13 06:27	75.46	OK	4074	2026-09-13 06:28	76.27	OK
4075	2026-09-13 06:29	71.94	OK	4076	2026-09-13 06:30	76.62	OK
4077	2026-09-13 06:31	74.59	OK	4078	2026-09-13 06:32	74.85	OK
4079	2026-09-13 06:33	73.65	OK	4080	2026-09-13 06:34	73.49	OK
4081	2026-09-13 06:35	73.03	OK	4082	2026-09-13 06:36	75.72	OK
4083	2026-09-13 06:37	74.14	OK	4084	2026-09-13 06:38	74.80	OK
4085	2026-09-13 06:39	71.21	OK	4086	2026-09-13 06:40	75.16	OK
4087	2026-09-13 06:41	72.50	OK	4088	2026-09-13 06:42	75.49	OK
4089	2026-09-13 06:43	73.85	OK	4090	2026-09-13 06:44	72.84	OK
4091	2026-09-13 06:45	72.70	OK	4092	2026-09-13 06:46	77.16	OK
4093	2026-09-13 06:47	76.72	OK	4094	2026-09-13 06:48	74.21	OK
4095	2026-09-13 06:49	75.68	OK	4096	2026-09-13 06:50	75.53	OK
4097	2026-09-13 06:51	75.59	OK	4098	2026-09-13 06:52	73.98	OK
4099	2026-09-13 06:53	75.83	OK	4100	2026-09-13 06:54	79.12	OK
4101	2026-09-13 06:55	75.47	OK	4102	2026-09-13 06:56	73.41	OK
4103	2026-09-13 06:57	75.88	OK	4104	2026-09-13 06:58	76.65	OK
4105	2026-09-13 06:59	74.62	OK	4106	2026-09-13 07:00	77.61	OK
4107	2026-09-13 07:01	73.85	OK	4108	2026-09-13 07:02	75.26	OK
4109	2026-09-13 07:03	72.07	OK	4110	2026-09-13 07:04	75.14	OK
4111	2026-09-13 07:05	76.19	OK	4112	2026-09-13 07:06	74.13	OK
4113	2026-09-13 07:07	74.40	OK	4114	2026-09-13 07:08	75.13	OK
4115	2026-09-13 07:09	73.59	OK	4116	2026-09-13 07:10	76.19	OK
4117	2026-09-13 07:11	74.63	OK	4118	2026-09-13 07:12	74.52	OK
4119	2026-09-13 07:13	75.83	OK	4120	2026-09-13 07:14	76.71	OK
4121	2026-09-13 07:15	76.12	OK	4122	2026-09-13 07:16	77.41	OK
4123	2026-09-13 07:17	73.44	OK	4124	2026-09-13 07:18	78.10	OK
4125	2026-09-13 07:19	77.59	OK	4126	2026-09-13 07:20	72.44	OK
4127	2026-09-13 07:21	75.26	OK	4128	2026-09-13 07:22	74.65	OK
4129	2026-09-13 07:23	74.31	OK	4130	2026-09-13 07:24	75.36	OK
4131	2026-09-13 07:25	76.92	OK	4132	2026-09-13 07:26	75.58	OK
4133	2026-09-13 07:27	75.07	OK	4134	2026-09-13 07:28	73.45	OK
4135	2026-09-13 07:29	75.58	OK	4136	2026-09-13 07:30	74.64	OK
4137	2026-09-13 07:31	74.29	OK	4138	2026-09-13 07:32	74.91	OK
4139	2026-09-13 07:33	77.61	OK	4140	2026-09-13 07:34	76.14	OK
4141	2026-09-13 07:35	74.39	OK	4142	2026-09-13 07:36	77.90	OK
4143	2026-09-13 07:37	72.58	OK	4144	2026-09-13 07:38	74.32	OK
4145	2026-09-13 07:39	73.52	OK	4146	2026-09-13 07:40	77.51	OK
4147	2026-09-13 07:41	74.31	OK	4148	2026-09-13 07:42	76.09	OK
4149	2026-09-13 07:43	75.78	OK	4150	2026-09-13 07:44	77.28	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4151	2026-09-13 07:45	77.46	OK	4152	2026-09-13 07:46	77.75	OK
4153	2026-09-13 07:47	75.00	OK	4154	2026-09-13 07:48	75.11	OK
4155	2026-09-13 07:49	76.80	OK	4156	2026-09-13 07:50	78.51	OK
4157	2026-09-13 07:51	77.69	OK	4158	2026-09-13 07:52	76.41	OK
4159	2026-09-13 07:53	75.51	OK	4160	2026-09-13 07:54	78.79	OK
4161	2026-09-13 07:55	76.97	OK	4162	2026-09-13 07:56	77.81	OK
4163	2026-09-13 07:57	73.07	OK	4164	2026-09-13 07:58	76.34	OK
4165	2026-09-13 07:59	76.84	OK	4166	2026-09-13 08:00	77.58	OK
4167	2026-09-13 08:01	77.53	OK	4168	2026-09-13 08:02	75.71	OK
4169	2026-09-13 08:03	76.92	OK	4170	2026-09-13 08:04	76.14	OK
4171	2026-09-13 08:05	75.25	OK	4172	2026-09-13 08:06	74.86	OK
4173	2026-09-13 08:07	76.50	OK	4174	2026-09-13 08:08	77.55	OK
4175	2026-09-13 08:09	77.64	OK	4176	2026-09-13 08:10	77.02	OK
4177	2026-09-13 08:11	75.86	OK	4178	2026-09-13 08:12	77.42	OK
4179	2026-09-13 08:13	73.46	OK	4180	2026-09-13 08:14	76.20	OK
4181	2026-09-13 08:15	75.84	OK	4182	2026-09-13 08:16	80.05	OK
4183	2026-09-13 08:17	79.77	OK	4184	2026-09-13 08:18	79.31	OK
4185	2026-09-13 08:19	75.29	OK	4186	2026-09-13 08:20	78.64	OK
4187	2026-09-13 08:21	75.22	OK	4188	2026-09-13 08:22	77.51	OK
4189	2026-09-13 08:23	76.37	OK	4190	2026-09-13 08:24	81.62	OK
4191	2026-09-13 08:25	74.74	OK	4192	2026-09-13 08:26	80.46	OK
4193	2026-09-13 08:27	79.44	OK	4194	2026-09-13 08:28	79.60	OK
4195	2026-09-13 08:29	79.74	OK	4196	2026-09-13 08:30	77.64	OK
4197	2026-09-13 08:31	77.46	OK	4198	2026-09-13 08:32	80.92	OK
4199	2026-09-13 08:33	76.39	OK	4200	2026-09-13 08:34	78.45	OK
4201	2026-09-13 08:35	80.33	OK	4202	2026-09-13 08:36	77.22	OK
4203	2026-09-13 08:37	78.35	OK	4204	2026-09-13 08:38	80.24	OK
4205	2026-09-13 08:39	78.28	OK	4206	2026-09-13 08:40	75.30	OK
4207	2026-09-13 08:41	77.00	OK	4208	2026-09-13 08:42	79.23	OK
4209	2026-09-13 08:43	74.80	OK	4210	2026-09-13 08:44	78.25	OK
4211	2026-09-13 08:45	77.99	OK	4212	2026-09-13 08:46	79.67	OK
4213	2026-09-13 08:47	77.59	OK	4214	2026-09-13 08:48	81.84	OK
4215	2026-09-13 08:49	73.94	OK	4216	2026-09-13 08:50	76.80	OK
4217	2026-09-13 08:51	79.48	OK	4218	2026-09-13 08:52	80.25	OK
4219	2026-09-13 08:53	75.94	OK	4220	2026-09-13 08:54	79.58	OK
4221	2026-09-13 08:55	79.24	OK	4222	2026-09-13 08:56	77.44	OK
4223	2026-09-13 08:57	78.99	OK	4224	2026-09-13 08:58	79.15	OK
4225	2026-09-13 08:59	80.09	OK	4226	2026-09-13 09:00	78.15	OK
4227	2026-09-13 09:01	79.01	OK	4228	2026-09-13 09:02	76.34	OK
4229	2026-09-13 09:03	77.48	OK	4230	2026-09-13 09:04	78.10	OK
4231	2026-09-13 09:05	75.89	OK	4232	2026-09-13 09:06	78.48	OK
4233	2026-09-13 09:07	75.66	OK	4234	2026-09-13 09:08	78.34	OK
4235	2026-09-13 09:09	80.09	OK	4236	2026-09-13 09:10	80.66	OK
4237	2026-09-13 09:11	75.51	OK	4238	2026-09-13 09:12	78.70	OK
4239	2026-09-13 09:13	78.30	OK	4240	2026-09-13 09:14	78.50	OK
4241	2026-09-13 09:15	80.72	OK	4242	2026-09-13 09:16	79.71	OK
4243	2026-09-13 09:17	78.23	OK	4244	2026-09-13 09:18	76.15	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4245	2026-09-13 09:19	79.38	OK	4246	2026-09-13 09:20	77.51	OK
4247	2026-09-13 09:21	77.70	OK	4248	2026-09-13 09:22	78.24	OK
4249	2026-09-13 09:23	78.55	OK	4250	2026-09-13 09:24	78.75	OK
4251	2026-09-13 09:25	79.01	OK	4252	2026-09-13 09:26	78.13	OK
4253	2026-09-13 09:27	79.33	OK	4254	2026-09-13 09:28	78.87	OK
4255	2026-09-13 09:29	77.56	OK	4256	2026-09-13 09:30	76.96	OK
4257	2026-09-13 09:31	79.83	OK	4258	2026-09-13 09:32	80.58	OK
4259	2026-09-13 09:33	79.47	OK	4260	2026-09-13 09:34	77.55	OK
4261	2026-09-13 09:35	80.59	OK	4262	2026-09-13 09:36	78.17	OK
4263	2026-09-13 09:37	77.84	OK	4264	2026-09-13 09:38	79.34	OK
4265	2026-09-13 09:39	77.85	OK	4266	2026-09-13 09:40	77.18	OK
4267	2026-09-13 09:41	77.11	OK	4268	2026-09-13 09:42	80.09	OK
4269	2026-09-13 09:43	76.54	OK	4270	2026-09-13 09:44	80.28	OK
4271	2026-09-13 09:45	78.44	OK	4272	2026-09-13 09:46	76.75	OK
4273	2026-09-13 09:47	81.51	OK	4274	2026-09-13 09:48	80.06	OK
4275	2026-09-13 09:49	83.13	OK	4276	2026-09-13 09:50	81.02	OK
4277	2026-09-13 09:51	80.04	OK	4278	2026-09-13 09:52	78.83	OK
4279	2026-09-13 09:53	80.33	OK	4280	2026-09-13 09:54	80.48	OK
4281	2026-09-13 09:55	80.08	OK	4282	2026-09-13 09:56	79.38	OK
4283	2026-09-13 09:57	81.37	OK	4284	2026-09-13 09:58	82.41	OK
4285	2026-09-13 09:59	77.32	OK	4286	2026-09-13 10:00	76.68	OK
4287	2026-09-13 10:01	83.63	OK	4288	2026-09-13 10:02	78.97	OK
4289	2026-09-13 10:03	79.04	OK	4290	2026-09-13 10:04	78.79	OK
4291	2026-09-13 10:05	78.86	OK	4292	2026-09-13 10:06	81.20	OK
4293	2026-09-13 10:07	78.37	OK	4294	2026-09-13 10:08	78.27	OK
4295	2026-09-13 10:09	80.09	OK	4296	2026-09-13 10:10	80.67	OK
4297	2026-09-13 10:11	80.80	OK	4298	2026-09-13 10:12	78.04	OK
4299	2026-09-13 10:13	78.16	OK	4300	2026-09-13 10:14	83.04	OK
4301	2026-09-13 10:15	79.31	OK	4302	2026-09-13 10:16	80.54	OK
4303	2026-09-13 10:17	78.46	OK	4304	2026-09-13 10:18	78.46	OK
4305	2026-09-13 10:19	76.89	OK	4306	2026-09-13 10:20	78.88	OK
4307	2026-09-13 10:21	78.53	OK	4308	2026-09-13 10:22	78.92	OK
4309	2026-09-13 10:23	78.30	OK	4310	2026-09-13 10:24	78.59	OK
4311	2026-09-13 10:25	76.59	OK	4312	2026-09-13 10:26	80.00	OK
4313	2026-09-13 10:27	79.38	OK	4314	2026-09-13 10:28	80.01	OK
4315	2026-09-13 10:29	77.47	OK	4316	2026-09-13 10:30	78.33	OK
4317	2026-09-13 10:31	81.58	OK	4318	2026-09-13 10:32	79.42	OK
4319	2026-09-13 10:33	79.72	OK	4320	2026-09-13 10:34	81.53	OK
4321	2026-09-13 10:35	81.75	OK	4322	2026-09-13 10:36	82.31	OK
4323	2026-09-13 10:37	82.41	OK	4324	2026-09-13 10:38	79.96	OK
4325	2026-09-13 10:39	78.64	OK	4326	2026-09-13 10:40	78.79	OK
4327	2026-09-13 10:41	81.63	OK	4328	2026-09-13 10:42	81.49	OK
4329	2026-09-13 10:43	77.69	OK	4330	2026-09-13 10:44	78.97	OK
4331	2026-09-13 10:45	80.37	OK	4332	2026-09-13 10:46	80.53	OK
4333	2026-09-13 10:47	81.71	OK	4334	2026-09-13 10:48	80.71	OK
4335	2026-09-13 10:49	82.35	OK	4336	2026-09-13 10:50	79.46	OK
4337	2026-09-13 10:51	80.36	OK	4338	2026-09-13 10:52	83.83	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4339	2026-09-13 10:53	79.86	OK	4340	2026-09-13 10:54	78.88	OK
4341	2026-09-13 10:55	80.96	OK	4342	2026-09-13 10:56	76.59	OK
4343	2026-09-13 10:57	77.80	OK	4344	2026-09-13 10:58	80.96	OK
4345	2026-09-13 10:59	81.99	OK	4346	2026-09-13 11:00	80.61	OK
4347	2026-09-13 11:01	83.48	OK	4348	2026-09-13 11:02	79.53	OK
4349	2026-09-13 11:03	82.83	OK	4350	2026-09-13 11:04	80.03	OK
4351	2026-09-13 11:05	78.42	OK	4352	2026-09-13 11:06	81.00	OK
4353	2026-09-13 11:07	80.01	OK	4354	2026-09-13 11:08	80.11	OK
4355	2026-09-13 11:09	81.32	OK	4356	2026-09-13 11:10	82.96	OK
4357	2026-09-13 11:11	81.73	OK	4358	2026-09-13 11:12	79.81	OK
4359	2026-09-13 11:13	78.06	OK	4360	2026-09-13 11:14	83.27	OK
4361	2026-09-13 11:15	79.33	OK	4362	2026-09-13 11:16	79.78	OK
4363	2026-09-13 11:17	81.54	OK	4364	2026-09-13 11:18	80.40	OK
4365	2026-09-13 11:19	82.03	OK	4366	2026-09-13 11:20	83.43	OK
4367	2026-09-13 11:21	78.51	OK	4368	2026-09-13 11:22	84.47	OK
4369	2026-09-13 11:23	80.74	OK	4370	2026-09-13 11:24	81.72	OK
4371	2026-09-13 11:25	80.08	OK	4372	2026-09-13 11:26	81.97	OK
4373	2026-09-13 11:27	79.74	OK	4374	2026-09-13 11:28	77.98	OK
4375	2026-09-13 11:29	79.03	OK	4376	2026-09-13 11:30	79.45	OK
4377	2026-09-13 11:31	81.66	OK	4378	2026-09-13 11:32	79.62	OK
4379	2026-09-13 11:33	81.53	OK	4380	2026-09-13 11:34	78.39	OK
4381	2026-09-13 11:35	79.75	OK	4382	2026-09-13 11:36	81.76	OK
4383	2026-09-13 11:37	79.23	OK	4384	2026-09-13 11:38	80.75	OK
4385	2026-09-13 11:39	79.92	OK	4386	2026-09-13 11:40	81.89	OK
4387	2026-09-13 11:41	83.36	OK	4388	2026-09-13 11:42	80.81	OK
4389	2026-09-13 11:43	83.66	OK	4390	2026-09-13 11:44	81.10	OK
4391	2026-09-13 11:45	81.71	OK	4392	2026-09-13 11:46	80.71	OK
4393	2026-09-13 11:47	81.81	OK	4394	2026-09-13 11:48	81.62	OK
4395	2026-09-13 11:49	82.58	OK	4396	2026-09-13 11:50	80.32	OK
4397	2026-09-13 11:51	82.84	OK	4398	2026-09-13 11:52	81.99	OK
4399	2026-09-13 11:53	81.13	OK	4400	2026-09-13 11:54	82.36	OK
4401	2026-09-13 11:55	80.92	OK	4402	2026-09-13 11:56	81.55	OK
4403	2026-09-13 11:57	81.62	OK	4404	2026-09-13 11:58	81.12	OK
4405	2026-09-13 11:59	81.19	OK	4406	2026-09-13 12:00	79.89	OK
4407	2026-09-13 12:01	81.65	OK	4408	2026-09-13 12:02	82.27	OK
4409	2026-09-13 12:03	82.94	OK	4410	2026-09-13 12:04	82.17	OK
4411	2026-09-13 12:05	81.11	OK	4412	2026-09-13 12:06	81.98	OK
4413	2026-09-13 12:07	83.00	OK	4414	2026-09-13 12:08	79.22	OK
4415	2026-09-13 12:09	81.59	OK	4416	2026-09-13 12:10	78.66	OK
4417	2026-09-13 12:11	76.65	OK	4418	2026-09-13 12:12	84.81	OK
4419	2026-09-13 12:13	79.03	OK	4420	2026-09-13 12:14	82.66	OK
4421	2026-09-13 12:15	83.92	OK	4422	2026-09-13 12:16	81.76	OK
4423	2026-09-13 12:17	81.69	OK	4424	2026-09-13 12:18	80.36	OK
4425	2026-09-13 12:19	82.33	OK	4426	2026-09-13 12:20	82.39	OK
4427	2026-09-13 12:21	82.56	OK	4428	2026-09-13 12:22	82.42	OK
4429	2026-09-13 12:23	81.40	OK	4430	2026-09-13 12:24	82.00	OK
4431	2026-09-13 12:25	81.81	OK	4432	2026-09-13 12:26	79.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4433	2026-09-13 12:27	79.47	OK	4434	2026-09-13 12:28	81.72	OK
4435	2026-09-13 12:29	84.15	OK	4436	2026-09-13 12:30	79.04	OK
4437	2026-09-13 12:31	84.49	OK	4438	2026-09-13 12:32	80.53	OK
4439	2026-09-13 12:33	76.99	OK	4440	2026-09-13 12:34	81.62	OK
4441	2026-09-13 12:35	81.43	OK	4442	2026-09-13 12:36	82.97	OK
4443	2026-09-13 12:37	80.65	OK	4444	2026-09-13 12:38	80.30	OK
4445	2026-09-13 12:39	80.96	OK	4446	2026-09-13 12:40	79.45	OK
4447	2026-09-13 12:41	80.49	OK	4448	2026-09-13 12:42	82.37	OK
4449	2026-09-13 12:43	80.95	OK	4450	2026-09-13 12:44	81.00	OK
4451	2026-09-13 12:45	83.88	OK	4452	2026-09-13 12:46	79.42	OK
4453	2026-09-13 12:47	80.09	OK	4454	2026-09-13 12:48	83.23	OK
4455	2026-09-13 12:49	82.71	OK	4456	2026-09-13 12:50	79.69	OK
4457	2026-09-13 12:51	80.47	OK	4458	2026-09-13 12:52	81.99	OK
4459	2026-09-13 12:53	82.39	OK	4460	2026-09-13 12:54	80.95	OK
4461	2026-09-13 12:55	77.84	OK	4462	2026-09-13 12:56	83.33	OK
4463	2026-09-13 12:57	82.71	OK	4464	2026-09-13 12:58	82.84	OK
4465	2026-09-13 12:59	80.11	OK	4466	2026-09-13 13:00	79.73	OK
4467	2026-09-13 13:01	79.05	OK	4468	2026-09-13 13:02	84.27	OK
4469	2026-09-13 13:03	79.52	OK	4470	2026-09-13 13:04	82.98	OK
4471	2026-09-13 13:05	80.62	OK	4472	2026-09-13 13:06	79.20	OK
4473	2026-09-13 13:07	80.29	OK	4474	2026-09-13 13:08	81.99	OK
4475	2026-09-13 13:09	82.15	OK	4476	2026-09-13 13:10	83.84	OK
4477	2026-09-13 13:11	81.29	OK	4478	2026-09-13 13:12	82.27	OK
4479	2026-09-13 13:13	79.72	OK	4480	2026-09-13 13:14	81.18	OK
4481	2026-09-13 13:15	77.95	OK	4482	2026-09-13 13:16	81.88	OK
4483	2026-09-13 13:17	82.14	OK	4484	2026-09-13 13:18	82.72	OK
4485	2026-09-13 13:19	77.16	OK	4486	2026-09-13 13:20	82.56	OK
4487	2026-09-13 13:21	82.88	OK	4488	2026-09-13 13:22	77.01	OK
4489	2026-09-13 13:23	81.69	OK	4490	2026-09-13 13:24	79.24	OK
4491	2026-09-13 13:25	80.59	OK	4492	2026-09-13 13:26	82.43	OK
4493	2026-09-13 13:27	81.99	OK	4494	2026-09-13 13:28	78.95	OK
4495	2026-09-13 13:29	82.99	OK	4496	2026-09-13 13:30	80.38	OK
4497	2026-09-13 13:31	80.23	OK	4498	2026-09-13 13:32	80.82	OK
4499	2026-09-13 13:33	80.19	OK	4500	2026-09-13 13:34	79.47	OK
4501	2026-09-13 13:35	83.37	OK	4502	2026-09-13 13:36	81.51	OK
4503	2026-09-13 13:37	81.27	OK	4504	2026-09-13 13:38	84.02	OK
4505	2026-09-13 13:39	79.00	OK	4506	2026-09-13 13:40	80.67	OK
4507	2026-09-13 13:41	82.24	OK	4508	2026-09-13 13:42	82.66	OK
4509	2026-09-13 13:43	79.78	OK	4510	2026-09-13 13:44	77.66	OK
4511	2026-09-13 13:45	80.55	OK	4512	2026-09-13 13:46	78.44	OK
4513	2026-09-13 13:47	80.81	OK	4514	2026-09-13 13:48	80.32	OK
4515	2026-09-13 13:49	79.70	OK	4516	2026-09-13 13:50	81.17	OK
4517	2026-09-13 13:51	79.30	OK	4518	2026-09-13 13:52	81.08	OK
4519	2026-09-13 13:53	83.14	OK	4520	2026-09-13 13:54	76.67	OK
4521	2026-09-13 13:55	79.28	OK	4522	2026-09-13 13:56	78.91	OK
4523	2026-09-13 13:57	83.05	OK	4524	2026-09-13 13:58	81.03	OK
4525	2026-09-13 13:59	80.31	OK	4526	2026-09-13 14:00	80.14	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4527	2026-09-13 14:01	78.56	OK	4528	2026-09-13 14:02	80.41	OK
4529	2026-09-13 14:03	80.33	OK	4530	2026-09-13 14:04	80.51	OK
4531	2026-09-13 14:05	80.65	OK	4532	2026-09-13 14:06	82.93	OK
4533	2026-09-13 14:07	78.65	OK	4534	2026-09-13 14:08	80.19	OK
4535	2026-09-13 14:09	82.79	OK	4536	2026-09-13 14:10	80.86	OK
4537	2026-09-13 14:11	78.00	OK	4538	2026-09-13 14:12	82.79	OK
4539	2026-09-13 14:13	79.47	OK	4540	2026-09-13 14:14	79.95	OK
4541	2026-09-13 14:15	79.20	OK	4542	2026-09-13 14:16	79.06	OK
4543	2026-09-13 14:17	83.24	OK	4544	2026-09-13 14:18	81.69	OK
4545	2026-09-13 14:19	80.41	OK	4546	2026-09-13 14:20	81.45	OK
4547	2026-09-13 14:21	79.93	OK	4548	2026-09-13 14:22	81.17	OK
4549	2026-09-13 14:23	83.81	OK	4550	2026-09-13 14:24	80.47	OK
4551	2026-09-13 14:25	82.15	OK	4552	2026-09-13 14:26	77.33	OK
4553	2026-09-13 14:27	79.65	OK	4554	2026-09-13 14:28	79.22	OK
4555	2026-09-13 14:29	80.12	OK	4556	2026-09-13 14:30	77.87	OK
4557	2026-09-13 14:31	79.51	OK	4558	2026-09-13 14:32	79.02	OK
4559	2026-09-13 14:33	82.30	OK	4560	2026-09-13 14:34	79.00	OK
4561	2026-09-13 14:35	82.30	OK	4562	2026-09-13 14:36	84.33	OK
4563	2026-09-13 14:37	78.60	OK	4564	2026-09-13 14:38	81.56	OK
4565	2026-09-13 14:39	82.36	OK	4566	2026-09-13 14:40	79.89	OK
4567	2026-09-13 14:41	81.96	OK	4568	2026-09-13 14:42	81.81	OK
4569	2026-09-13 14:43	81.34	OK	4570	2026-09-13 14:44	78.84	OK
4571	2026-09-13 14:45	80.58	OK	4572	2026-09-13 14:46	80.50	OK
4573	2026-09-13 14:47	81.00	OK	4574	2026-09-13 14:48	78.63	OK
4575	2026-09-13 14:49	80.60	OK	4576	2026-09-13 14:50	81.42	OK
4577	2026-09-13 14:51	80.49	OK	4578	2026-09-13 14:52	81.43	OK
4579	2026-09-13 14:53	78.64	OK	4580	2026-09-13 14:54	79.78	OK
4581	2026-09-13 14:55	80.88	OK	4582	2026-09-13 14:56	78.08	OK
4583	2026-09-13 14:57	80.52	OK	4584	2026-09-13 14:58	77.21	OK
4585	2026-09-13 14:59	78.99	OK	4586	2026-09-13 15:00	80.56	OK
4587	2026-09-13 15:01	78.89	OK	4588	2026-09-13 15:02	78.95	OK
4589	2026-09-13 15:03	81.76	OK	4590	2026-09-13 15:04	80.44	OK
4591	2026-09-13 15:05	82.86	OK	4592	2026-09-13 15:06	80.06	OK
4593	2026-09-13 15:07	81.11	OK	4594	2026-09-13 15:08	80.62	OK
4595	2026-09-13 15:09	79.83	OK	4596	2026-09-13 15:10	78.40	OK
4597	2026-09-13 15:11	76.70	OK	4598	2026-09-13 15:12	78.70	OK
4599	2026-09-13 15:13	78.33	OK	4600	2026-09-13 15:14	80.07	OK
4601	2026-09-13 15:15	78.27	OK	4602	2026-09-13 15:16	79.10	OK
4603	2026-09-13 15:17	81.26	OK	4604	2026-09-13 15:18	79.74	OK
4605	2026-09-13 15:19	82.68	OK	4606	2026-09-13 15:20	82.01	OK
4607	2026-09-13 15:21	80.89	OK	4608	2026-09-13 15:22	80.95	OK
4609	2026-09-13 15:23	80.90	OK	4610	2026-09-13 15:24	79.08	OK
4611	2026-09-13 15:25	80.52	OK	4612	2026-09-13 15:26	77.89	OK
4613	2026-09-13 15:27	81.39	OK	4614	2026-09-13 15:28	77.92	OK
4615	2026-09-13 15:29	81.04	OK	4616	2026-09-13 15:30	79.29	OK
4617	2026-09-13 15:31	81.44	OK	4618	2026-09-13 15:32	80.67	OK
4619	2026-09-13 15:33	79.58	OK	4620	2026-09-13 15:34	78.79	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4621	2026-09-13 15:35	81.23	OK	4622	2026-09-13 15:36	77.81	OK
4623	2026-09-13 15:37	80.93	OK	4624	2026-09-13 15:38	79.18	OK
4625	2026-09-13 15:39	78.79	OK	4626	2026-09-13 15:40	80.21	OK
4627	2026-09-13 15:41	81.10	OK	4628	2026-09-13 15:42	78.60	OK
4629	2026-09-13 15:43	78.89	OK	4630	2026-09-13 15:44	79.48	OK
4631	2026-09-13 15:45	79.41	OK	4632	2026-09-13 15:46	79.69	OK
4633	2026-09-13 15:47	79.19	OK	4634	2026-09-13 15:48	78.03	OK
4635	2026-09-13 15:49	77.08	OK	4636	2026-09-13 15:50	80.51	OK
4637	2026-09-13 15:51	78.19	OK	4638	2026-09-13 15:52	75.46	OK
4639	2026-09-13 15:53	80.14	OK	4640	2026-09-13 15:54	79.46	OK
4641	2026-09-13 15:55	78.66	OK	4642	2026-09-13 15:56	80.20	OK
4643	2026-09-13 15:57	81.37	OK	4644	2026-09-13 15:58	81.19	OK
4645	2026-09-13 15:59	81.01	OK	4646	2026-09-13 16:00	79.64	OK
4647	2026-09-13 16:01	80.02	OK	4648	2026-09-13 16:02	81.24	OK
4649	2026-09-13 16:03	77.32	OK	4650	2026-09-13 16:04	79.75	OK
4651	2026-09-13 16:05	75.17	OK	4652	2026-09-13 16:06	78.98	OK
4653	2026-09-13 16:07	78.80	OK	4654	2026-09-13 16:08	78.56	OK
4655	2026-09-13 16:09	79.99	OK	4656	2026-09-13 16:10	79.29	OK
4657	2026-09-13 16:11	81.25	OK	4658	2026-09-13 16:12	78.91	OK
4659	2026-09-13 16:13	78.54	OK	4660	2026-09-13 16:14	76.50	OK
4661	2026-09-13 16:15	79.63	OK	4662	2026-09-13 16:16	78.30	OK
4663	2026-09-13 16:17	75.84	OK	4664	2026-09-13 16:18	78.31	OK
4665	2026-09-13 16:19	77.16	OK	4666	2026-09-13 16:20	78.42	OK
4667	2026-09-13 16:21	79.34	OK	4668	2026-09-13 16:22	80.51	OK
4669	2026-09-13 16:23	80.67	OK	4670	2026-09-13 16:24	82.22	OK
4671	2026-09-13 16:25	79.05	OK	4672	2026-09-13 16:26	77.49	OK
4673	2026-09-13 16:27	75.23	OK	4674	2026-09-13 16:28	80.07	OK
4675	2026-09-13 16:29	75.02	OK	4676	2026-09-13 16:30	78.13	OK
4677	2026-09-13 16:31	78.97	OK	4678	2026-09-13 16:32	81.28	OK
4679	2026-09-13 16:33	76.40	OK	4680	2026-09-13 16:34	79.80	OK
4681	2026-09-13 16:35	77.63	OK	4682	2026-09-13 16:36	78.71	OK
4683	2026-09-13 16:37	77.98	OK	4684	2026-09-13 16:38	77.55	OK
4685	2026-09-13 16:39	81.17	OK	4686	2026-09-13 16:40	77.64	OK
4687	2026-09-13 16:41	78.48	OK	4688	2026-09-13 16:42	75.16	OK
4689	2026-09-13 16:43	80.08	OK	4690	2026-09-13 16:44	80.28	OK
4691	2026-09-13 16:45	77.11	OK	4692	2026-09-13 16:46	76.76	OK
4693	2026-09-13 16:47	79.13	OK	4694	2026-09-13 16:48	81.55	OK
4695	2026-09-13 16:49	78.12	OK	4696	2026-09-13 16:50	76.24	OK
4697	2026-09-13 16:51	78.24	OK	4698	2026-09-13 16:52	79.30	OK
4699	2026-09-13 16:53	77.37	OK	4700	2026-09-13 16:54	77.85	OK
4701	2026-09-13 16:55	76.82	OK	4702	2026-09-13 16:56	75.90	OK
4703	2026-09-13 16:57	79.36	OK	4704	2026-09-13 16:58	79.22	OK
4705	2026-09-13 16:59	75.66	OK	4706	2026-09-13 17:00	75.76	OK
4707	2026-09-13 17:01	79.94	OK	4708	2026-09-13 17:02	79.34	OK
4709	2026-09-13 17:03	80.37	OK	4710	2026-09-13 17:04	80.84	OK
4711	2026-09-13 17:05	78.83	OK	4712	2026-09-13 17:06	78.76	OK
4713	2026-09-13 17:07	77.07	OK	4714	2026-09-13 17:08	78.56	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4715	2026-09-13 17:09	78.68	OK	4716	2026-09-13 17:10	76.28	OK
4717	2026-09-13 17:11	79.93	OK	4718	2026-09-13 17:12	76.14	OK
4719	2026-09-13 17:13	78.31	OK	4720	2026-09-13 17:14	80.09	OK
4721	2026-09-13 17:15	78.10	OK	4722	2026-09-13 17:16	79.51	OK
4723	2026-09-13 17:17	79.57	OK	4724	2026-09-13 17:18	73.26	OK
4725	2026-09-13 17:19	76.37	OK	4726	2026-09-13 17:20	79.20	OK
4727	2026-09-13 17:21	75.82	OK	4728	2026-09-13 17:22	78.33	OK
4729	2026-09-13 17:23	79.12	OK	4730	2026-09-13 17:24	77.53	OK
4731	2026-09-13 17:25	78.43	OK	4732	2026-09-13 17:26	78.55	OK
4733	2026-09-13 17:27	75.86	OK	4734	2026-09-13 17:28	78.13	OK
4735	2026-09-13 17:29	74.87	OK	4736	2026-09-13 17:30	78.09	OK
4737	2026-09-13 17:31	78.14	OK	4738	2026-09-13 17:32	76.13	OK
4739	2026-09-13 17:33	77.38	OK	4740	2026-09-13 17:34	76.82	OK
4741	2026-09-13 17:35	75.69	OK	4742	2026-09-13 17:36	74.06	OK
4743	2026-09-13 17:37	77.07	OK	4744	2026-09-13 17:38	75.87	OK
4745	2026-09-13 17:39	75.40	OK	4746	2026-09-13 17:40	75.71	OK
4747	2026-09-13 17:41	78.56	OK	4748	2026-09-13 17:42	76.65	OK
4749	2026-09-13 17:43	76.07	OK	4750	2026-09-13 17:44	77.51	OK
4751	2026-09-13 17:45	76.40	OK	4752	2026-09-13 17:46	77.77	OK
4753	2026-09-13 17:47	76.10	OK	4754	2026-09-13 17:48	77.69	OK
4755	2026-09-13 17:49	76.65	OK	4756	2026-09-13 17:50	73.89	OK
4757	2026-09-13 17:51	77.94	OK	4758	2026-09-13 17:52	78.23	OK
4759	2026-09-13 17:53	77.49	OK	4760	2026-09-13 17:54	76.54	OK
4761	2026-09-13 17:55	74.21	OK	4762	2026-09-13 17:56	76.80	OK
4763	2026-09-13 17:57	80.35	OK	4764	2026-09-13 17:58	76.08	OK
4765	2026-09-13 17:59	77.62	OK	4766	2026-09-13 18:00	73.35	OK
4767	2026-09-13 18:01	76.31	OK	4768	2026-09-13 18:02	75.56	OK
4769	2026-09-13 18:03	78.60	OK	4770	2026-09-13 18:04	74.38	OK
4771	2026-09-13 18:05	75.79	OK	4772	2026-09-13 18:06	77.69	OK
4773	2026-09-13 18:07	75.07	OK	4774	2026-09-13 18:08	77.35	OK
4775	2026-09-13 18:09	75.26	OK	4776	2026-09-13 18:10	74.21	OK
4777	2026-09-13 18:11	76.79	OK	4778	2026-09-13 18:12	78.13	OK
4779	2026-09-13 18:13	75.94	OK	4780	2026-09-13 18:14	73.18	OK
4781	2026-09-13 18:15	77.89	OK	4782	2026-09-13 18:16	75.81	OK
4783	2026-09-13 18:17	74.54	OK	4784	2026-09-13 18:18	74.81	OK
4785	2026-09-13 18:19	76.50	OK	4786	2026-09-13 18:20	75.83	OK
4787	2026-09-13 18:21	74.77	OK	4788	2026-09-13 18:22	77.67	OK
4789	2026-09-13 18:23	73.20	OK	4790	2026-09-13 18:24	77.26	OK
4791	2026-09-13 18:25	77.04	OK	4792	2026-09-13 18:26	74.43	OK
4793	2026-09-13 18:27	77.11	OK	4794	2026-09-13 18:28	74.11	OK
4795	2026-09-13 18:29	75.70	OK	4796	2026-09-13 18:30	75.16	OK
4797	2026-09-13 18:31	75.16	OK	4798	2026-09-13 18:32	77.22	OK
4799	2026-09-13 18:33	75.75	OK	4800	2026-09-13 18:34	73.31	OK
4801	2026-09-13 18:35	75.39	OK	4802	2026-09-13 18:36	74.26	OK
4803	2026-09-13 18:37	76.48	OK	4804	2026-09-13 18:38	76.26	OK
4805	2026-09-13 18:39	78.71	OK	4806	2026-09-13 18:40	74.94	OK
4807	2026-09-13 18:41	73.51	OK	4808	2026-09-13 18:42	76.98	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4809	2026-09-13 18:43	73.39	OK	4810	2026-09-13 18:44	73.77	OK
4811	2026-09-13 18:45	74.98	OK	4812	2026-09-13 18:46	76.32	OK
4813	2026-09-13 18:47	74.11	OK	4814	2026-09-13 18:48	77.84	OK
4815	2026-09-13 18:49	74.41	OK	4816	2026-09-13 18:50	76.14	OK
4817	2026-09-13 18:51	73.71	OK	4818	2026-09-13 18:52	75.19	OK
4819	2026-09-13 18:53	74.04	OK	4820	2026-09-13 18:54	77.43	OK
4821	2026-09-13 18:55	77.26	OK	4822	2026-09-13 18:56	73.17	OK
4823	2026-09-13 18:57	73.91	OK	4824	2026-09-13 18:58	75.22	OK
4825	2026-09-13 18:59	75.17	OK	4826	2026-09-13 19:00	76.69	OK
4827	2026-09-13 19:01	73.38	OK	4828	2026-09-13 19:02	74.83	OK
4829	2026-09-13 19:03	75.22	OK	4830	2026-09-13 19:04	74.10	OK
4831	2026-09-13 19:05	77.53	OK	4832	2026-09-13 19:06	72.76	OK
4833	2026-09-13 19:07	75.71	OK	4834	2026-09-13 19:08	76.95	OK
4835	2026-09-13 19:09	73.74	OK	4836	2026-09-13 19:10	76.02	OK
4837	2026-09-13 19:11	74.40	OK	4838	2026-09-13 19:12	73.05	OK
4839	2026-09-13 19:13	72.74	OK	4840	2026-09-13 19:14	75.09	OK
4841	2026-09-13 19:15	74.04	OK	4842	2026-09-13 19:16	72.04	OK
4843	2026-09-13 19:17	73.33	OK	4844	2026-09-13 19:18	73.48	OK
4845	2026-09-13 19:19	77.20	OK	4846	2026-09-13 19:20	76.74	OK
4847	2026-09-13 19:21	75.04	OK	4848	2026-09-13 19:22	74.50	OK
4849	2026-09-13 19:23	74.15	OK	4850	2026-09-13 19:24	75.51	OK
4851	2026-09-13 19:25	77.32	OK	4852	2026-09-13 19:26	74.65	OK
4853	2026-09-13 19:27	76.46	OK	4854	2026-09-13 19:28	75.78	OK
4855	2026-09-13 19:29	74.45	OK	4856	2026-09-13 19:30	73.54	OK
4857	2026-09-13 19:31	73.84	OK	4858	2026-09-13 19:32	73.80	OK
4859	2026-09-13 19:33	76.26	OK	4860	2026-09-13 19:34	75.58	OK
4861	2026-09-13 19:35	75.90	OK	4862	2026-09-13 19:36	74.91	OK
4863	2026-09-13 19:37	73.28	OK	4864	2026-09-13 19:38	73.20	OK
4865	2026-09-13 19:39	71.64	OK	4866	2026-09-13 19:40	74.97	OK
4867	2026-09-13 19:41	74.20	OK	4868	2026-09-13 19:42	72.57	OK
4869	2026-09-13 19:43	74.42	OK	4870	2026-09-13 19:44	71.55	OK
4871	2026-09-13 19:45	74.61	OK	4872	2026-09-13 19:46	73.49	OK
4873	2026-09-13 19:47	74.13	OK	4874	2026-09-13 19:48	74.92	OK
4875	2026-09-13 19:49	73.31	OK	4876	2026-09-13 19:50	71.64	OK
4877	2026-09-13 19:51	71.33	OK	4878	2026-09-13 19:52	73.64	OK
4879	2026-09-13 19:53	74.31	OK	4880	2026-09-13 19:54	75.93	OK
4881	2026-09-13 19:55	72.81	OK	4882	2026-09-13 19:56	73.08	OK
4883	2026-09-13 19:57	75.15	OK	4884	2026-09-13 19:58	72.21	OK
4885	2026-09-13 19:59	74.19	OK	4886	2026-09-13 20:00	72.75	OK
4887	2026-09-13 20:01	72.48	OK	4888	2026-09-13 20:02	74.59	OK
4889	2026-09-13 20:03	75.58	OK	4890	2026-09-13 20:04	76.05	OK
4891	2026-09-13 20:05	73.18	OK	4892	2026-09-13 20:06	71.80	OK
4893	2026-09-13 20:07	72.65	OK	4894	2026-09-13 20:08	76.90	OK
4895	2026-09-13 20:09	74.08	OK	4896	2026-09-13 20:10	75.61	OK
4897	2026-09-13 20:11	72.92	OK	4898	2026-09-13 20:12	75.46	OK
4899	2026-09-13 20:13	73.63	OK	4900	2026-09-13 20:14	71.62	OK
4901	2026-09-13 20:15	75.20	OK	4902	2026-09-13 20:16	71.20	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4903	2026-09-13 20:17	75.05	OK	4904	2026-09-13 20:18	74.67	OK
4905	2026-09-13 20:19	72.21	OK	4906	2026-09-13 20:20	75.07	OK
4907	2026-09-13 20:21	71.82	OK	4908	2026-09-13 20:22	72.53	OK
4909	2026-09-13 20:23	74.32	OK	4910	2026-09-13 20:24	71.11	OK
4911	2026-09-13 20:25	74.50	OK	4912	2026-09-13 20:26	70.99	OK
4913	2026-09-13 20:27	70.96	OK	4914	2026-09-13 20:28	70.52	OK
4915	2026-09-13 20:29	73.29	OK	4916	2026-09-13 20:30	71.17	OK
4917	2026-09-13 20:31	74.59	OK	4918	2026-09-13 20:32	70.38	OK
4919	2026-09-13 20:33	74.72	OK	4920	2026-09-13 20:34	71.04	OK
4921	2026-09-13 20:35	73.22	OK	4922	2026-09-13 20:36	72.91	OK
4923	2026-09-13 20:37	72.68	OK	4924	2026-09-13 20:38	75.12	OK
4925	2026-09-13 20:39	73.68	OK	4926	2026-09-13 20:40	71.90	OK
4927	2026-09-13 20:41	70.71	OK	4928	2026-09-13 20:42	71.25	OK
4929	2026-09-13 20:43	71.61	OK	4930	2026-09-13 20:44	70.97	OK
4931	2026-09-13 20:45	73.30	OK	4932	2026-09-13 20:46	73.22	OK
4933	2026-09-13 20:47	76.74	OK	4934	2026-09-13 20:48	73.78	OK
4935	2026-09-13 20:49	73.07	OK	4936	2026-09-13 20:50	72.63	OK
4937	2026-09-13 20:51	74.08	OK	4938	2026-09-13 20:52	69.82	OK
4939	2026-09-13 20:53	72.60	OK	4940	2026-09-13 20:54	72.03	OK
4941	2026-09-13 20:55	70.43	OK	4942	2026-09-13 20:56	73.88	OK
4943	2026-09-13 20:57	71.80	OK	4944	2026-09-13 20:58	72.96	OK
4945	2026-09-13 20:59	71.63	OK	4946	2026-09-13 21:00	73.15	OK
4947	2026-09-13 21:01	72.52	OK	4948	2026-09-13 21:02	70.99	OK
4949	2026-09-13 21:03	71.52	OK	4950	2026-09-13 21:04	72.23	OK
4951	2026-09-13 21:05	68.32	OK	4952	2026-09-13 21:06	71.42	OK
4953	2026-09-13 21:07	73.22	OK	4954	2026-09-13 21:08	74.39	OK
4955	2026-09-13 21:09	70.48	OK	4956	2026-09-13 21:10	71.36	OK
4957	2026-09-13 21:11	75.28	OK	4958	2026-09-13 21:12	70.36	OK
4959	2026-09-13 21:13	71.50	OK	4960	2026-09-13 21:14	68.65	OK
4961	2026-09-13 21:15	73.08	OK	4962	2026-09-13 21:16	73.23	OK
4963	2026-09-13 21:17	72.15	OK	4964	2026-09-13 21:18	69.99	OK
4965	2026-09-13 21:19	70.32	OK	4966	2026-09-13 21:20	71.25	OK
4967	2026-09-13 21:21	69.62	OK	4968	2026-09-13 21:22	72.21	OK
4969	2026-09-13 21:23	68.84	OK	4970	2026-09-13 21:24	72.25	OK
4971	2026-09-13 21:25	72.10	OK	4972	2026-09-13 21:26	68.72	OK
4973	2026-09-13 21:27	73.01	OK	4974	2026-09-13 21:28	69.97	OK
4975	2026-09-13 21:29	74.61	OK	4976	2026-09-13 21:30	70.14	OK
4977	2026-09-13 21:31	70.56	OK	4978	2026-09-13 21:32	68.28	OK
4979	2026-09-13 21:33	73.67	OK	4980	2026-09-13 21:34	73.09	OK
4981	2026-09-13 21:35	70.14	OK	4982	2026-09-13 21:36	70.80	OK
4983	2026-09-13 21:37	69.82	OK	4984	2026-09-13 21:38	71.40	OK
4985	2026-09-13 21:39	72.65	OK	4986	2026-09-13 21:40	70.03	OK
4987	2026-09-13 21:41	72.91	OK	4988	2026-09-13 21:42	72.90	OK
4989	2026-09-13 21:43	67.55	OK	4990	2026-09-13 21:44	70.11	OK
4991	2026-09-13 21:45	72.50	OK	4992	2026-09-13 21:46	69.57	OK
4993	2026-09-13 21:47	73.04	OK	4994	2026-09-13 21:48	72.96	OK
4995	2026-09-13 21:49	74.08	OK	4996	2026-09-13 21:50	69.70	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4997	2026-09-13 21:51	73.89	OK	4998	2026-09-13 21:52	71.85	OK
4999	2026-09-13 21:53	72.57	OK	5000	2026-09-13 21:54	73.90	OK
5001	2026-09-13 21:55	71.45	OK	5002	2026-09-13 21:56	72.56	OK
5003	2026-09-13 21:57	69.48	OK	5004	2026-09-13 21:58	69.75	OK
5005	2026-09-13 21:59	71.53	OK	5006	2026-09-13 22:00	72.10	OK
5007	2026-09-13 22:01	71.32	OK	5008	2026-09-13 22:02	70.60	OK
5009	2026-09-13 22:03	71.40	OK	5010	2026-09-13 22:04	69.87	OK
5011	2026-09-13 22:05	68.27	OK	5012	2026-09-13 22:06	70.04	OK
5013	2026-09-13 22:07	70.55	OK	5014	2026-09-13 22:08	71.80	OK
5015	2026-09-13 22:09	70.36	OK	5016	2026-09-13 22:10	73.22	OK
5017	2026-09-13 22:11	72.62	OK	5018	2026-09-13 22:12	69.78	OK
5019	2026-09-13 22:13	71.69	OK	5020	2026-09-13 22:14	72.04	OK
5021	2026-09-13 22:15	70.69	OK	5022	2026-09-13 22:16	72.76	OK
5023	2026-09-13 22:17	68.24	OK	5024	2026-09-13 22:18	75.33	OK
5025	2026-09-13 22:19	71.66	OK	5026	2026-09-13 22:20	68.48	OK
5027	2026-09-13 22:21	71.81	OK	5028	2026-09-13 22:22	71.07	OK
5029	2026-09-13 22:23	70.89	OK	5030	2026-09-13 22:24	68.84	OK
5031	2026-09-13 22:25	73.35	OK	5032	2026-09-13 22:26	67.97	OK
5033	2026-09-13 22:27	69.60	OK	5034	2026-09-13 22:28	68.58	OK
5035	2026-09-13 22:29	71.46	OK	5036	2026-09-13 22:30	73.36	OK
5037	2026-09-13 22:31	71.91	OK	5038	2026-09-13 22:32	70.93	OK
5039	2026-09-13 22:33	69.78	OK	5040	2026-09-13 22:34	69.30	OK
5041	2026-09-13 22:35	74.42	OK	5042	2026-09-13 22:36	67.70	OK
5043	2026-09-13 22:37	67.95	OK	5044	2026-09-13 22:38	70.61	OK
5045	2026-09-13 22:39	69.14	OK	5046	2026-09-13 22:40	71.13	OK
5047	2026-09-13 22:41	71.23	OK	5048	2026-09-13 22:42	66.87	OK
5049	2026-09-13 22:43	66.87	OK	5050	2026-09-13 22:44	71.04	OK
5051	2026-09-13 22:45	69.91	OK	5052	2026-09-13 22:46	69.61	OK
5053	2026-09-13 22:47	70.41	OK	5054	2026-09-13 22:48	69.23	OK
5055	2026-09-13 22:49	67.46	OK	5056	2026-09-13 22:50	68.69	OK
5057	2026-09-13 22:51	69.65	OK	5058	2026-09-13 22:52	70.49	OK
5059	2026-09-13 22:53	71.26	OK	5060	2026-09-13 22:54	68.95	OK
5061	2026-09-13 22:55	68.46	OK	5062	2026-09-13 22:56	66.81	OK
5063	2026-09-13 22:57	68.27	OK	5064	2026-09-13 22:58	71.49	OK
5065	2026-09-13 22:59	68.00	OK	5066	2026-09-13 23:00	71.36	OK
5067	2026-09-13 23:01	66.52	OK	5068	2026-09-13 23:02	69.16	OK
5069	2026-09-13 23:03	68.12	OK	5070	2026-09-13 23:04	69.53	OK
5071	2026-09-13 23:05	71.77	OK	5072	2026-09-13 23:06	71.52	OK
5073	2026-09-13 23:07	69.05	OK	5074	2026-09-13 23:08	68.90	OK
5075	2026-09-13 23:09	68.38	OK	5076	2026-09-13 23:10	69.96	OK
5077	2026-09-13 23:11	68.78	OK	5078	2026-09-13 23:12	72.66	OK
5079	2026-09-13 23:13	71.42	OK	5080	2026-09-13 23:14	71.69	OK
5081	2026-09-13 23:15	71.42	OK	5082	2026-09-13 23:16	69.39	OK
5083	2026-09-13 23:17	70.90	OK	5084	2026-09-13 23:18	69.47	OK
5085	2026-09-13 23:19	71.40	OK	5086	2026-09-13 23:20	71.18	OK
5087	2026-09-13 23:21	70.26	OK	5088	2026-09-13 23:22	69.17	OK
5089	2026-09-13 23:23	71.27	OK	5090	2026-09-13 23:24	69.98	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5091	2026-09-13 23:25	71.15	OK	5092	2026-09-13 23:26	71.71	OK
5093	2026-09-13 23:27	68.23	OK	5094	2026-09-13 23:28	69.98	OK
5095	2026-09-13 23:29	70.10	OK	5096	2026-09-13 23:30	70.59	OK
5097	2026-09-13 23:31	69.45	OK	5098	2026-09-13 23:32	71.61	OK
5099	2026-09-13 23:33	71.12	OK	5100	2026-09-13 23:34	69.57	OK
5101	2026-09-13 23:35	67.97	OK	5102	2026-09-13 23:36	70.47	OK
5103	2026-09-13 23:37	70.77	OK	5104	2026-09-13 23:38	69.62	OK
5105	2026-09-13 23:39	69.53	OK	5106	2026-09-13 23:40	69.90	OK
5107	2026-09-13 23:41	66.51	OK	5108	2026-09-13 23:42	71.35	OK
5109	2026-09-13 23:43	69.65	OK	5110	2026-09-13 23:44	67.20	OK
5111	2026-09-13 23:45	71.21	OK	5112	2026-09-13 23:46	70.40	OK
5113	2026-09-13 23:47	68.82	OK	5114	2026-09-13 23:48	69.88	OK
5115	2026-09-13 23:49	69.79	OK	5116	2026-09-13 23:50	67.84	OK
5117	2026-09-13 23:51	70.76	OK	5118	2026-09-13 23:52	71.12	OK
5119	2026-09-13 23:53	69.46	OK	5120	2026-09-13 23:54	67.82	OK
5121	2026-09-13 23:55	70.57	OK	5122	2026-09-13 23:56	66.87	OK
5123	2026-09-13 23:57	66.99	OK	5124	2026-09-13 23:58	68.61	OK
5125	2026-09-13 23:59	68.67	OK	5126	2026-09-14 00:00	66.63	OK
5127	2026-09-14 00:01	73.09	OK	5128	2026-09-14 00:02	68.57	OK
5129	2026-09-14 00:03	70.44	OK	5130	2026-09-14 00:04	68.79	OK
5131	2026-09-14 00:05	67.92	OK	5132	2026-09-14 00:06	70.63	OK
5133	2026-09-14 00:07	66.97	OK	5134	2026-09-14 00:08	69.86	OK
5135	2026-09-14 00:09	67.19	OK	5136	2026-09-14 00:10	70.58	OK
5137	2026-09-14 00:11	70.65	OK	5138	2026-09-14 00:12	70.13	OK
5139	2026-09-14 00:13	68.68	OK	5140	2026-09-14 00:14	71.58	OK
5141	2026-09-14 00:15	68.03	OK	5142	2026-09-14 00:16	69.33	OK
5143	2026-09-14 00:17	68.60	OK	5144	2026-09-14 00:18	66.25	OK
5145	2026-09-14 00:19	69.78	OK	5146	2026-09-14 00:20	70.35	OK
5147	2026-09-14 00:21	69.01	OK	5148	2026-09-14 00:22	70.05	OK
5149	2026-09-14 00:23	68.45	OK	5150	2026-09-14 00:24	68.97	OK
5151	2026-09-14 00:25	65.50	OK	5152	2026-09-14 00:26	71.66	OK
5153	2026-09-14 00:27	68.23	OK	5154	2026-09-14 00:28	69.00	OK
5155	2026-09-14 00:29	66.01	OK	5156	2026-09-14 00:30	68.85	OK
5157	2026-09-14 00:31	68.39	OK	5158	2026-09-14 00:32	68.21	OK
5159	2026-09-14 00:33	69.99	OK	5160	2026-09-14 00:34	66.31	OK
5161	2026-09-14 00:35	70.92	OK	5162	2026-09-14 00:36	70.45	OK
5163	2026-09-14 00:37	67.40	OK	5164	2026-09-14 00:38	71.28	OK
5165	2026-09-14 00:39	67.97	OK	5166	2026-09-14 00:40	68.39	OK
5167	2026-09-14 00:41	67.47	OK	5168	2026-09-14 00:42	71.87	OK
5169	2026-09-14 00:43	69.85	OK	5170	2026-09-14 00:44	70.65	OK
5171	2026-09-14 00:45	69.14	OK	5172	2026-09-14 00:46	70.39	OK
5173	2026-09-14 00:47	69.94	OK	5174	2026-09-14 00:48	73.55	OK
5175	2026-09-14 00:49	69.10	OK	5176	2026-09-14 00:50	69.11	OK
5177	2026-09-14 00:51	68.61	OK	5178	2026-09-14 00:52	68.49	OK
5179	2026-09-14 00:53	69.00	OK	5180	2026-09-14 00:54	66.99	OK
5181	2026-09-14 00:55	68.28	OK	5182	2026-09-14 00:56	67.78	OK
5183	2026-09-14 00:57	67.32	OK	5184	2026-09-14 00:58	68.78	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5185	2026-09-14 00:59	68.68	OK	5186	2026-09-14 01:00	68.32	OK
5187	2026-09-14 01:01	70.43	OK	5188	2026-09-14 01:02	69.58	OK
5189	2026-09-14 01:03	69.10	OK	5190	2026-09-14 01:04	69.82	OK
5191	2026-09-14 01:05	70.27	OK	5192	2026-09-14 01:06	66.98	OK
5193	2026-09-14 01:07	70.83	OK	5194	2026-09-14 01:08	71.31	OK
5195	2026-09-14 01:09	67.72	OK	5196	2026-09-14 01:10	72.71	OK
5197	2026-09-14 01:11	69.29	OK	5198	2026-09-14 01:12	68.44	OK
5199	2026-09-14 01:13	69.48	OK	5200	2026-09-14 01:14	71.11	OK
5201	2026-09-14 01:15	71.75	OK	5202	2026-09-14 01:16	67.62	OK
5203	2026-09-14 01:17	69.75	OK	5204	2026-09-14 01:18	68.71	OK
5205	2026-09-14 01:19	68.02	OK	5206	2026-09-14 01:20	68.88	OK
5207	2026-09-14 01:21	68.72	OK	5208	2026-09-14 01:22	69.94	OK
5209	2026-09-14 01:23	66.64	OK	5210	2026-09-14 01:24	67.93	OK
5211	2026-09-14 01:25	65.63	OK	5212	2026-09-14 01:26	70.59	OK
5213	2026-09-14 01:27	69.30	OK	5214	2026-09-14 01:28	69.43	OK
5215	2026-09-14 01:29	71.10	OK	5216	2026-09-14 01:30	73.66	OK
5217	2026-09-14 01:31	67.08	OK	5218	2026-09-14 01:32	67.70	OK
5219	2026-09-14 01:33	71.38	OK	5220	2026-09-14 01:34	70.31	OK
5221	2026-09-14 01:35	66.87	OK	5222	2026-09-14 01:36	67.33	OK
5223	2026-09-14 01:37	71.75	OK	5224	2026-09-14 01:38	69.76	OK
5225	2026-09-14 01:39	67.98	OK	5226	2026-09-14 01:40	72.31	OK
5227	2026-09-14 01:41	69.50	OK	5228	2026-09-14 01:42	69.52	OK
5229	2026-09-14 01:43	68.22	OK	5230	2026-09-14 01:44	66.62	OK
5231	2026-09-14 01:45	70.79	OK	5232	2026-09-14 01:46	70.68	OK
5233	2026-09-14 01:47	67.81	OK	5234	2026-09-14 01:48	68.18	OK
5235	2026-09-14 01:49	68.74	OK	5236	2026-09-14 01:50	67.44	OK
5237	2026-09-14 01:51	71.22	OK	5238	2026-09-14 01:52	69.80	OK
5239	2026-09-14 01:53	69.38	OK	5240	2026-09-14 01:54	71.72	OK
5241	2026-09-14 01:55	70.01	OK	5242	2026-09-14 01:56	68.84	OK
5243	2026-09-14 01:57	72.84	OK	5244	2026-09-14 01:58	67.99	OK
5245	2026-09-14 01:59	69.33	OK	5246	2026-09-14 02:00	69.93	OK
5247	2026-09-14 02:01	68.56	OK	5248	2026-09-14 02:02	66.75	OK
5249	2026-09-14 02:03	72.71	OK	5250	2026-09-14 02:04	67.60	OK
5251	2026-09-14 02:05	70.27	OK	5252	2026-09-14 02:06	67.03	OK
5253	2026-09-14 02:07	72.27	OK	5254	2026-09-14 02:08	67.71	OK
5255	2026-09-14 02:09	65.91	OK	5256	2026-09-14 02:10	69.57	OK
5257	2026-09-14 02:11	68.37	OK	5258	2026-09-14 02:12	68.96	OK
5259	2026-09-14 02:13	70.38	OK	5260	2026-09-14 02:14	71.36	OK
5261	2026-09-14 02:15	70.83	OK	5262	2026-09-14 02:16	70.24	OK
5263	2026-09-14 02:17	72.58	OK	5264	2026-09-14 02:18	70.14	OK
5265	2026-09-14 02:19	68.59	OK	5266	2026-09-14 02:20	68.52	OK
5267	2026-09-14 02:21	70.59	OK	5268	2026-09-14 02:22	70.80	OK
5269	2026-09-14 02:23	70.52	OK	5270	2026-09-14 02:24	68.32	OK
5271	2026-09-14 02:25	66.12	OK	5272	2026-09-14 02:26	72.29	OK
5273	2026-09-14 02:27	68.61	OK	5274	2026-09-14 02:28	67.24	OK
5275	2026-09-14 02:29	66.14	OK	5276	2026-09-14 02:30	67.93	OK
5277	2026-09-14 02:31	69.81	OK	5278	2026-09-14 02:32	67.41	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5279	2026-09-14 02:33	68.41	OK	5280	2026-09-14 02:34	69.80	OK
5281	2026-09-14 02:35	69.94	OK	5282	2026-09-14 02:36	68.75	OK
5283	2026-09-14 02:37	68.49	OK	5284	2026-09-14 02:38	68.93	OK
5285	2026-09-14 02:39	70.45	OK	5286	2026-09-14 02:40	70.08	OK
5287	2026-09-14 02:41	70.96	OK	5288	2026-09-14 02:42	69.55	OK
5289	2026-09-14 02:43	69.13	OK	5290	2026-09-14 02:44	67.89	OK
5291	2026-09-14 02:45	68.04	OK	5292	2026-09-14 02:46	71.46	OK
5293	2026-09-14 02:47	70.05	OK	5294	2026-09-14 02:48	69.79	OK
5295	2026-09-14 02:49	68.74	OK	5296	2026-09-14 02:50	68.18	OK
5297	2026-09-14 02:51	73.23	OK	5298	2026-09-14 02:52	70.33	OK
5299	2026-09-14 02:53	69.91	OK	5300	2026-09-14 02:54	68.53	OK
5301	2026-09-14 02:55	70.41	OK	5302	2026-09-14 02:56	68.78	OK
5303	2026-09-14 02:57	68.73	OK	5304	2026-09-14 02:58	67.14	OK
5305	2026-09-14 02:59	72.77	OK	5306	2026-09-14 03:00	72.34	OK
5307	2026-09-14 03:01	71.10	OK	5308	2026-09-14 03:02	67.35	OK
5309	2026-09-14 03:03	71.63	OK	5310	2026-09-14 03:04	69.56	OK
5311	2026-09-14 03:05	71.81	OK	5312	2026-09-14 03:06	72.52	OK
5313	2026-09-14 03:07	69.87	OK	5314	2026-09-14 03:08	69.80	OK
5315	2026-09-14 03:09	70.53	OK	5316	2026-09-14 03:10	69.00	OK
5317	2026-09-14 03:11	67.47	OK	5318	2026-09-14 03:12	70.14	OK
5319	2026-09-14 03:13	69.05	OK	5320	2026-09-14 03:14	69.28	OK
5321	2026-09-14 03:15	69.93	OK	5322	2026-09-14 03:16	70.45	OK
5323	2026-09-14 03:17	68.55	OK	5324	2026-09-14 03:18	73.37	OK
5325	2026-09-14 03:19	70.72	OK	5326	2026-09-14 03:20	68.83	OK
5327	2026-09-14 03:21	67.60	OK	5328	2026-09-14 03:22	71.63	OK
5329	2026-09-14 03:23	70.31	OK	5330	2026-09-14 03:24	70.77	OK
5331	2026-09-14 03:25	70.35	OK	5332	2026-09-14 03:26	73.22	OK
5333	2026-09-14 03:27	68.80	OK	5334	2026-09-14 03:28	69.14	OK
5335	2026-09-14 03:29	69.82	OK	5336	2026-09-14 03:30	72.08	OK
5337	2026-09-14 03:31	67.94	OK	5338	2026-09-14 03:32	69.62	OK
5339	2026-09-14 03:33	67.28	OK	5340	2026-09-14 03:34	73.43	OK
5341	2026-09-14 03:35	68.61	OK	5342	2026-09-14 03:36	71.16	OK
5343	2026-09-14 03:37	67.97	OK	5344	2026-09-14 03:38	69.92	OK
5345	2026-09-14 03:39	70.66	OK	5346	2026-09-14 03:40	69.78	OK
5347	2026-09-14 03:41	71.35	OK	5348	2026-09-14 03:42	70.65	OK
5349	2026-09-14 03:43	69.31	OK	5350	2026-09-14 03:44	70.04	OK
5351	2026-09-14 03:45	71.45	OK	5352	2026-09-14 03:46	68.94	OK
5353	2026-09-14 03:47	69.16	OK	5354	2026-09-14 03:48	72.67	OK
5355	2026-09-14 03:49	71.65	OK	5356	2026-09-14 03:50	68.31	OK
5357	2026-09-14 03:51	70.51	OK	5358	2026-09-14 03:52	72.68	OK
5359	2026-09-14 03:53	71.60	OK	5360	2026-09-14 03:54	74.78	OK
5361	2026-09-14 03:55	71.55	OK	5362	2026-09-14 03:56	72.80	OK
5363	2026-09-14 03:57	71.38	OK	5364	2026-09-14 03:58	69.53	OK
5365	2026-09-14 03:59	72.44	OK	5366	2026-09-14 04:00	68.20	OK
5367	2026-09-14 04:01	71.67	OK	5368	2026-09-14 04:02	71.42	OK
5369	2026-09-14 04:03	74.30	OK	5370	2026-09-14 04:04	69.47	OK
5371	2026-09-14 04:05	71.99	OK	5372	2026-09-14 04:06	72.25	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5373	2026-09-14 04:07	71.72	OK	5374	2026-09-14 04:08	71.57	OK
5375	2026-09-14 04:09	70.12	OK	5376	2026-09-14 04:10	69.53	OK
5377	2026-09-14 04:11	73.01	OK	5378	2026-09-14 04:12	69.73	OK
5379	2026-09-14 04:13	70.55	OK	5380	2026-09-14 04:14	71.16	OK
5381	2026-09-14 04:15	73.00	OK	5382	2026-09-14 04:16	72.74	OK
5383	2026-09-14 04:17	72.66	OK	5384	2026-09-14 04:18	72.43	OK
5385	2026-09-14 04:19	73.94	OK	5386	2026-09-14 04:20	73.70	OK
5387	2026-09-14 04:21	68.12	OK	5388	2026-09-14 04:22	71.39	OK
5389	2026-09-14 04:23	73.24	OK	5390	2026-09-14 04:24	71.68	OK
5391	2026-09-14 04:25	75.45	OK	5392	2026-09-14 04:26	70.50	OK
5393	2026-09-14 04:27	71.62	OK	5394	2026-09-14 04:28	71.17	OK
5395	2026-09-14 04:29	73.93	OK	5396	2026-09-14 04:30	68.40	OK
5397	2026-09-14 04:31	71.25	OK	5398	2026-09-14 04:32	74.24	OK
5399	2026-09-14 04:33	69.37	OK	5400	2026-09-14 04:34	74.60	OK
5401	2026-09-14 04:35	74.17	OK	5402	2026-09-14 04:36	72.50	OK
5403	2026-09-14 04:37	73.70	OK	5404	2026-09-14 04:38	69.15	OK
5405	2026-09-14 04:39	72.59	OK	5406	2026-09-14 04:40	68.18	OK
5407	2026-09-14 04:41	71.40	OK	5408	2026-09-14 04:42	71.71	OK
5409	2026-09-14 04:43	71.60	OK	5410	2026-09-14 04:44	71.84	OK
5411	2026-09-14 04:45	74.61	OK	5412	2026-09-14 04:46	73.55	OK
5413	2026-09-14 04:47	71.09	OK	5414	2026-09-14 04:48	70.21	OK
5415	2026-09-14 04:49	72.30	OK	5416	2026-09-14 04:50	71.76	OK
5417	2026-09-14 04:51	74.58	OK	5418	2026-09-14 04:52	72.59	OK
5419	2026-09-14 04:53	72.20	OK	5420	2026-09-14 04:54	70.93	OK
5421	2026-09-14 04:55	72.23	OK	5422	2026-09-14 04:56	69.66	OK
5423	2026-09-14 04:57	76.30	OK	5424	2026-09-14 04:58	71.20	OK
5425	2026-09-14 04:59	74.59	OK	5426	2026-09-14 05:00	72.63	OK
5427	2026-09-14 05:01	71.94	OK	5428	2026-09-14 05:02	73.96	OK
5429	2026-09-14 05:03	73.29	OK	5430	2026-09-14 05:04	74.57	OK
5431	2026-09-14 05:05	75.25	OK	5432	2026-09-14 05:06	73.71	OK
5433	2026-09-14 05:07	72.66	OK	5434	2026-09-14 05:08	71.93	OK
5435	2026-09-14 05:09	72.94	OK	5436	2026-09-14 05:10	73.35	OK
5437	2026-09-14 05:11	71.46	OK	5438	2026-09-14 05:12	73.33	OK
5439	2026-09-14 05:13	74.41	OK	5440	2026-09-14 05:14	73.35	OK
5441	2026-09-14 05:15	75.24	OK	5442	2026-09-14 05:16	72.43	OK
5443	2026-09-14 05:17	71.71	OK	5444	2026-09-14 05:18	74.84	OK
5445	2026-09-14 05:19	74.96	OK	5446	2026-09-14 05:20	72.63	OK
5447	2026-09-14 05:21	72.97	OK	5448	2026-09-14 05:22	71.36	OK
5449	2026-09-14 05:23	70.63	OK	5450	2026-09-14 05:24	74.70	OK
5451	2026-09-14 05:25	71.86	OK	5452	2026-09-14 05:26	71.72	OK
5453	2026-09-14 05:27	69.49	OK	5454	2026-09-14 05:28	70.99	OK
5455	2026-09-14 05:29	72.12	OK	5456	2026-09-14 05:30	69.97	OK
5457	2026-09-14 05:31	74.08	OK	5458	2026-09-14 05:32	73.07	OK
5459	2026-09-14 05:33	72.48	OK	5460	2026-09-14 05:34	74.84	OK
5461	2026-09-14 05:35	74.15	OK	5462	2026-09-14 05:36	72.79	OK
5463	2026-09-14 05:37	76.68	OK	5464	2026-09-14 05:38	72.28	OK
5465	2026-09-14 05:39	71.00	OK	5466	2026-09-14 05:40	74.02	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5467	2026-09-14 05:41	75.63	OK	5468	2026-09-14 05:42	73.14	OK
5469	2026-09-14 05:43	74.38	OK	5470	2026-09-14 05:44	71.97	OK
5471	2026-09-14 05:45	73.47	OK	5472	2026-09-14 05:46	73.24	OK
5473	2026-09-14 05:47	74.11	OK	5474	2026-09-14 05:48	71.12	OK
5475	2026-09-14 05:49	72.80	OK	5476	2026-09-14 05:50	73.49	OK
5477	2026-09-14 05:51	72.44	OK	5478	2026-09-14 05:52	74.86	OK
5479	2026-09-14 05:53	71.95	OK	5480	2026-09-14 05:54	72.92	OK
5481	2026-09-14 05:55	74.40	OK	5482	2026-09-14 05:56	75.99	OK
5483	2026-09-14 05:57	73.17	OK	5484	2026-09-14 05:58	70.83	OK
5485	2026-09-14 05:59	73.66	OK	5486	2026-09-14 06:00	75.66	OK
5487	2026-09-14 06:01	76.81	OK	5488	2026-09-14 06:02	72.62	OK
5489	2026-09-14 06:03	75.55	OK	5490	2026-09-14 06:04	73.06	OK
5491	2026-09-14 06:05	74.95	OK	5492	2026-09-14 06:06	73.00	OK
5493	2026-09-14 06:07	73.93	OK	5494	2026-09-14 06:08	77.21	OK
5495	2026-09-14 06:09	74.62	OK	5496	2026-09-14 06:10	74.01	OK
5497	2026-09-14 06:11	75.89	OK	5498	2026-09-14 06:12	73.10	OK
5499	2026-09-14 06:13	73.78	OK	5500	2026-09-14 06:14	74.46	OK
5501	2026-09-14 06:15	73.71	OK	5502	2026-09-14 06:16	74.96	OK
5503	2026-09-14 06:17	74.29	OK	5504	2026-09-14 06:18	72.86	OK
5505	2026-09-14 06:19	71.67	OK	5506	2026-09-14 06:20	75.48	OK
5507	2026-09-14 06:21	71.13	OK	5508	2026-09-14 06:22	77.69	OK
5509	2026-09-14 06:23	75.21	OK	5510	2026-09-14 06:24	74.71	OK
5511	2026-09-14 06:25	70.33	OK	5512	2026-09-14 06:26	75.01	OK
5513	2026-09-14 06:27	74.87	OK	5514	2026-09-14 06:28	74.73	OK
5515	2026-09-14 06:29	76.25	OK	5516	2026-09-14 06:30	74.60	OK
5517	2026-09-14 06:31	77.66	OK	5518	2026-09-14 06:32	75.06	OK
5519	2026-09-14 06:33	75.94	OK	5520	2026-09-14 06:34	77.30	OK
5521	2026-09-14 06:35	74.22	OK	5522	2026-09-14 06:36	73.71	OK
5523	2026-09-14 06:37	73.47	OK	5524	2026-09-14 06:38	73.25	OK
5525	2026-09-14 06:39	73.15	OK	5526	2026-09-14 06:40	73.75	OK
5527	2026-09-14 06:41	75.27	OK	5528	2026-09-14 06:42	75.75	OK
5529	2026-09-14 06:43	75.12	OK	5530	2026-09-14 06:44	72.78	OK
5531	2026-09-14 06:45	76.37	OK	5532	2026-09-14 06:46	75.08	OK
5533	2026-09-14 06:47	76.17	OK	5534	2026-09-14 06:48	73.95	OK
5535	2026-09-14 06:49	74.10	OK	5536	2026-09-14 06:50	74.95	OK
5537	2026-09-14 06:51	76.57	OK	5538	2026-09-14 06:52	74.59	OK
5539	2026-09-14 06:53	74.63	OK	5540	2026-09-14 06:54	73.06	OK
5541	2026-09-14 06:55	76.20	OK	5542	2026-09-14 06:56	78.14	OK
5543	2026-09-14 06:57	76.32	OK	5544	2026-09-14 06:58	74.71	OK
5545	2026-09-14 06:59	74.36	OK	5546	2026-09-14 07:00	75.67	OK
5547	2026-09-14 07:01	74.58	OK	5548	2026-09-14 07:02	74.88	OK
5549	2026-09-14 07:03	78.31	OK	5550	2026-09-14 07:04	77.58	OK
5551	2026-09-14 07:05	75.87	OK	5552	2026-09-14 07:06	76.18	OK
5553	2026-09-14 07:07	76.00	OK	5554	2026-09-14 07:08	78.95	OK
5555	2026-09-14 07:09	76.07	OK	5556	2026-09-14 07:10	73.26	OK
5557	2026-09-14 07:11	75.04	OK	5558	2026-09-14 07:12	75.80	OK
5559	2026-09-14 07:13	77.42	OK	5560	2026-09-14 07:14	76.86	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5561	2026-09-14 07:15	78.50	OK	5562	2026-09-14 07:16	75.93	OK
5563	2026-09-14 07:17	75.36	OK	5564	2026-09-14 07:18	77.41	OK
5565	2026-09-14 07:19	77.81	OK	5566	2026-09-14 07:20	75.50	OK
5567	2026-09-14 07:21	74.57	OK	5568	2026-09-14 07:22	75.79	OK
5569	2026-09-14 07:23	74.24	OK	5570	2026-09-14 07:24	75.21	OK
5571	2026-09-14 07:25	76.17	OK	5572	2026-09-14 07:26	77.79	OK
5573	2026-09-14 07:27	77.24	OK	5574	2026-09-14 07:28	75.02	OK
5575	2026-09-14 07:29	74.31	OK	5576	2026-09-14 07:30	76.05	OK
5577	2026-09-14 07:31	75.78	OK	5578	2026-09-14 07:32	74.90	OK
5579	2026-09-14 07:33	77.87	OK	5580	2026-09-14 07:34	78.33	OK
5581	2026-09-14 07:35	78.39	OK	5582	2026-09-14 07:36	76.06	OK
5583	2026-09-14 07:37	73.14	OK	5584	2026-09-14 07:38	80.46	OK
5585	2026-09-14 07:39	77.52	OK	5586	2026-09-14 07:40	76.80	OK
5587	2026-09-14 07:41	78.14	OK	5588	2026-09-14 07:42	75.49	OK
5589	2026-09-14 07:43	77.72	OK	5590	2026-09-14 07:44	77.69	OK
5591	2026-09-14 07:45	78.89	OK	5592	2026-09-14 07:46	76.32	OK
5593	2026-09-14 07:47	74.93	OK	5594	2026-09-14 07:48	77.02	OK
5595	2026-09-14 07:49	76.34	OK	5596	2026-09-14 07:50	74.21	OK
5597	2026-09-14 07:51	78.28	OK	5598	2026-09-14 07:52	74.07	OK
5599	2026-09-14 07:53	77.01	OK	5600	2026-09-14 07:54	76.44	OK
5601	2026-09-14 07:55	77.73	OK	5602	2026-09-14 07:56	74.27	OK
5603	2026-09-14 07:57	75.37	OK	5604	2026-09-14 07:58	73.20	OK
5605	2026-09-14 07:59	76.51	OK	5606	2026-09-14 08:00	74.35	OK
5607	2026-09-14 08:01	76.92	OK	5608	2026-09-14 08:02	75.08	OK
5609	2026-09-14 08:03	76.88	OK	5610	2026-09-14 08:04	76.81	OK
5611	2026-09-14 08:05	80.35	OK	5612	2026-09-14 08:06	78.04	OK
5613	2026-09-14 08:07	75.11	OK	5614	2026-09-14 08:08	75.91	OK
5615	2026-09-14 08:09	75.77	OK	5616	2026-09-14 08:10	79.86	OK
5617	2026-09-14 08:11	74.36	OK	5618	2026-09-14 08:12	78.95	OK
5619	2026-09-14 08:13	77.96	OK	5620	2026-09-14 08:14	78.08	OK
5621	2026-09-14 08:15	77.82	OK	5622	2026-09-14 08:16	76.76	OK
5623	2026-09-14 08:17	76.03	OK	5624	2026-09-14 08:18	77.17	OK
5625	2026-09-14 08:19	76.27	OK	5626	2026-09-14 08:20	75.65	OK
5627	2026-09-14 08:21	78.49	OK	5628	2026-09-14 08:22	77.79	OK
5629	2026-09-14 08:23	78.36	OK	5630	2026-09-14 08:24	77.98	OK
5631	2026-09-14 08:25	76.43	OK	5632	2026-09-14 08:26	76.88	OK
5633	2026-09-14 08:27	77.85	OK	5634	2026-09-14 08:28	79.85	OK
5635	2026-09-14 08:29	77.06	OK	5636	2026-09-14 08:30	78.72	OK
5637	2026-09-14 08:31	76.65	OK	5638	2026-09-14 08:32	78.21	OK
5639	2026-09-14 08:33	75.22	OK	5640	2026-09-14 08:34	77.42	OK
5641	2026-09-14 08:35	77.86	OK	5642	2026-09-14 08:36	76.63	OK
5643	2026-09-14 08:37	80.48	OK	5644	2026-09-14 08:38	77.29	OK
5645	2026-09-14 08:39	78.36	OK	5646	2026-09-14 08:40	78.82	OK
5647	2026-09-14 08:41	76.36	OK	5648	2026-09-14 08:42	79.27	OK
5649	2026-09-14 08:43	79.39	OK	5650	2026-09-14 08:44	76.70	OK
5651	2026-09-14 08:45	78.11	OK	5652	2026-09-14 08:46	75.49	OK
5653	2026-09-14 08:47	77.61	OK	5654	2026-09-14 08:48	79.33	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5655	2026-09-14 08:49	74.66	OK	5656	2026-09-14 08:50	78.44	OK
5657	2026-09-14 08:51	77.80	OK	5658	2026-09-14 08:52	78.69	OK
5659	2026-09-14 08:53	77.88	OK	5660	2026-09-14 08:54	77.15	OK
5661	2026-09-14 08:55	77.55	OK	5662	2026-09-14 08:56	78.90	OK
5663	2026-09-14 08:57	78.15	OK	5664	2026-09-14 08:58	74.59	OK
5665	2026-09-14 08:59	79.45	OK	5666	2026-09-14 09:00	79.25	OK
5667	2026-09-14 09:01	80.02	OK	5668	2026-09-14 09:02	76.30	OK
5669	2026-09-14 09:03	78.09	OK	5670	2026-09-14 09:04	79.54	OK
5671	2026-09-14 09:05	79.13	OK	5672	2026-09-14 09:06	78.36	OK
5673	2026-09-14 09:07	76.34	OK	5674	2026-09-14 09:08	76.73	OK
5675	2026-09-14 09:09	77.58	OK	5676	2026-09-14 09:10	78.01	OK
5677	2026-09-14 09:11	78.81	OK	5678	2026-09-14 09:12	79.62	OK
5679	2026-09-14 09:13	77.83	OK	5680	2026-09-14 09:14	80.01	OK
5681	2026-09-14 09:15	76.58	OK	5682	2026-09-14 09:16	77.99	OK
5683	2026-09-14 09:17	78.61	OK	5684	2026-09-14 09:18	81.31	OK
5685	2026-09-14 09:19	77.35	OK	5686	2026-09-14 09:20	78.09	OK
5687	2026-09-14 09:21	78.73	OK	5688	2026-09-14 09:22	81.12	OK
5689	2026-09-14 09:23	77.47	OK	5690	2026-09-14 09:24	79.95	OK
5691	2026-09-14 09:25	78.76	OK	5692	2026-09-14 09:26	78.19	OK
5693	2026-09-14 09:27	77.28	OK	5694	2026-09-14 09:28	79.33	OK
5695	2026-09-14 09:29	79.54	OK	5696	2026-09-14 09:30	78.72	OK
5697	2026-09-14 09:31	78.31	OK	5698	2026-09-14 09:32	75.91	OK
5699	2026-09-14 09:33	81.04	OK	5700	2026-09-14 09:34	77.58	OK
5701	2026-09-14 09:35	79.25	OK	5702	2026-09-14 09:36	81.68	OK
5703	2026-09-14 09:37	79.61	OK	5704	2026-09-14 09:38	78.17	OK
5705	2026-09-14 09:39	76.91	OK	5706	2026-09-14 09:40	79.22	OK
5707	2026-09-14 09:41	78.78	OK	5708	2026-09-14 09:42	77.50	OK
5709	2026-09-14 09:43	80.87	OK	5710	2026-09-14 09:44	78.90	OK
5711	2026-09-14 09:45	80.37	OK	5712	2026-09-14 09:46	77.47	OK
5713	2026-09-14 09:47	81.11	OK	5714	2026-09-14 09:48	81.07	OK
5715	2026-09-14 09:49	75.64	OK	5716	2026-09-14 09:50	77.83	OK
5717	2026-09-14 09:51	76.01	OK	5718	2026-09-14 09:52	79.81	OK
5719	2026-09-14 09:53	80.09	OK	5720	2026-09-14 09:54	78.10	OK
5721	2026-09-14 09:55	80.55	OK	5722	2026-09-14 09:56	77.95	OK
5723	2026-09-14 09:57	79.22	OK	5724	2026-09-14 09:58	77.27	OK
5725	2026-09-14 09:59	79.48	OK	5726	2026-09-14 10:00	78.84	OK
5727	2026-09-14 10:01	78.31	OK	5728	2026-09-14 10:02	80.21	OK
5729	2026-09-14 10:03	81.49	OK	5730	2026-09-14 10:04	81.62	OK
5731	2026-09-14 10:05	76.53	OK	5732	2026-09-14 10:06	80.89	OK
5733	2026-09-14 10:07	79.03	OK	5734	2026-09-14 10:08	80.51	OK
5735	2026-09-14 10:09	81.67	OK	5736	2026-09-14 10:10	80.82	OK
5737	2026-09-14 10:11	79.83	OK	5738	2026-09-14 10:12	79.21	OK
5739	2026-09-14 10:13	80.73	OK	5740	2026-09-14 10:14	76.89	OK
5741	2026-09-14 10:15	82.21	OK	5742	2026-09-14 10:16	77.24	OK
5743	2026-09-14 10:17	78.22	OK	5744	2026-09-14 10:18	78.40	OK
5745	2026-09-14 10:19	79.08	OK	5746	2026-09-14 10:20	81.32	OK
5747	2026-09-14 10:21	80.49	OK	5748	2026-09-14 10:22	78.86	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5749	2026-09-14 10:23	78.56	OK	5750	2026-09-14 10:24	82.96	OK
5751	2026-09-14 10:25	81.61	OK	5752	2026-09-14 10:26	78.49	OK
5753	2026-09-14 10:27	80.22	OK	5754	2026-09-14 10:28	77.95	OK
5755	2026-09-14 10:29	79.99	OK	5756	2026-09-14 10:30	80.06	OK
5757	2026-09-14 10:31	79.24	OK	5758	2026-09-14 10:32	80.25	OK
5759	2026-09-14 10:33	76.61	OK	5760	2026-09-14 10:34	79.29	OK
5761	2026-09-14 10:35	79.11	OK	5762	2026-09-14 10:36	79.84	OK
5763	2026-09-14 10:37	80.54	OK	5764	2026-09-14 10:38	80.20	OK
5765	2026-09-14 10:39	82.68	OK	5766	2026-09-14 10:40	81.01	OK
5767	2026-09-14 10:41	78.76	OK	5768	2026-09-14 10:42	79.01	OK
5769	2026-09-14 10:43	81.17	OK	5770	2026-09-14 10:44	78.46	OK
5771	2026-09-14 10:45	76.79	OK	5772	2026-09-14 10:46	80.00	OK
5773	2026-09-14 10:47	81.54	OK	5774	2026-09-14 10:48	79.61	OK
5775	2026-09-14 10:49	79.72	OK	5776	2026-09-14 10:50	78.01	OK
5777	2026-09-14 10:51	80.80	OK	5778	2026-09-14 10:52	79.80	OK
5779	2026-09-14 10:53	82.21	OK	5780	2026-09-14 10:54	81.32	OK
5781	2026-09-14 10:55	79.11	OK	5782	2026-09-14 10:56	78.99	OK
5783	2026-09-14 10:57	79.80	OK	5784	2026-09-14 10:58	80.19	OK
5785	2026-09-14 10:59	78.62	OK	5786	2026-09-14 11:00	79.77	OK
5787	2026-09-14 11:01	77.41	OK	5788	2026-09-14 11:02	81.24	OK
5789	2026-09-14 11:03	79.57	OK	5790	2026-09-14 11:04	81.21	OK
5791	2026-09-14 11:05	79.27	OK	5792	2026-09-14 11:06	79.71	OK
5793	2026-09-14 11:07	81.46	OK	5794	2026-09-14 11:08	80.72	OK
5795	2026-09-14 11:09	83.24	OK	5796	2026-09-14 11:10	79.34	OK
5797	2026-09-14 11:11	78.65	OK	5798	2026-09-14 11:12	84.20	OK
5799	2026-09-14 11:13	80.84	OK	5800	2026-09-14 11:14	80.03	OK
5801	2026-09-14 11:15	82.27	OK	5802	2026-09-14 11:16	80.19	OK
5803	2026-09-14 11:17	80.24	OK	5804	2026-09-14 11:18	78.61	OK
5805	2026-09-14 11:19	79.67	OK	5806	2026-09-14 11:20	78.21	OK
5807	2026-09-14 11:21	80.67	OK	5808	2026-09-14 11:22	78.84	OK
5809	2026-09-14 11:23	79.01	OK	5810	2026-09-14 11:24	78.47	OK
5811	2026-09-14 11:25	81.30	OK	5812	2026-09-14 11:26	77.86	OK
5813	2026-09-14 11:27	79.89	OK	5814	2026-09-14 11:28	84.09	OK
5815	2026-09-14 11:29	81.02	OK	5816	2026-09-14 11:30	82.02	OK
5817	2026-09-14 11:31	79.23	OK	5818	2026-09-14 11:32	80.75	OK
5819	2026-09-14 11:33	82.63	OK	5820	2026-09-14 11:34	78.53	OK
5821	2026-09-14 11:35	82.19	OK	5822	2026-09-14 11:36	81.00	OK
5823	2026-09-14 11:37	82.43	OK	5824	2026-09-14 11:38	77.35	OK
5825	2026-09-14 11:39	80.91	OK	5826	2026-09-14 11:40	83.31	OK
5827	2026-09-14 11:41	82.04	OK	5828	2026-09-14 11:42	82.64	OK
5829	2026-09-14 11:43	78.84	OK	5830	2026-09-14 11:44	77.81	OK
5831	2026-09-14 11:45	83.19	OK	5832	2026-09-14 11:46	80.43	OK
5833	2026-09-14 11:47	80.69	OK	5834	2026-09-14 11:48	80.90	OK
5835	2026-09-14 11:49	79.11	OK	5836	2026-09-14 11:50	78.56	OK
5837	2026-09-14 11:51	84.65	OK	5838	2026-09-14 11:52	80.99	OK
5839	2026-09-14 11:53	80.45	OK	5840	2026-09-14 11:54	80.45	OK
5841	2026-09-14 11:55	80.96	OK	5842	2026-09-14 11:56	83.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5843	2026-09-14 11:57	82.46	OK	5844	2026-09-14 11:58	80.05	OK
5845	2026-09-14 11:59	78.99	OK	5846	2026-09-14 12:00	80.73	OK
5847	2026-09-14 12:01	81.48	OK	5848	2026-09-14 12:02	83.17	OK
5849	2026-09-14 12:03	78.90	OK	5850	2026-09-14 12:04	79.19	OK
5851	2026-09-14 12:05	82.50	OK	5852	2026-09-14 12:06	80.93	OK
5853	2026-09-14 12:07	83.06	OK	5854	2026-09-14 12:08	79.70	OK
5855	2026-09-14 12:09	80.90	OK	5856	2026-09-14 12:10	79.98	OK
5857	2026-09-14 12:11	79.83	OK	5858	2026-09-14 12:12	81.27	OK
5859	2026-09-14 12:13	82.71	OK	5860	2026-09-14 12:14	80.91	OK
5861	2026-09-14 12:15	78.27	OK	5862	2026-09-14 12:16	80.37	OK
5863	2026-09-14 12:17	79.73	OK	5864	2026-09-14 12:18	80.50	OK
5865	2026-09-14 12:19	79.92	OK	5866	2026-09-14 12:20	78.43	OK
5867	2026-09-14 12:21	80.24	OK	5868	2026-09-14 12:22	80.45	OK
5869	2026-09-14 12:23	81.71	OK	5870	2026-09-14 12:24	79.85	OK
5871	2026-09-14 12:25	78.66	OK	5872	2026-09-14 12:26	81.22	OK
5873	2026-09-14 12:27	79.00	OK	5874	2026-09-14 12:28	79.19	OK
5875	2026-09-14 12:29	80.90	OK	5876	2026-09-14 12:30	82.38	OK
5877	2026-09-14 12:31	79.34	OK	5878	2026-09-14 12:32	82.05	OK
5879	2026-09-14 12:33	79.30	OK	5880	2026-09-14 12:34	84.03	OK
5881	2026-09-14 12:35	80.20	OK	5882	2026-09-14 12:36	80.74	OK
5883	2026-09-14 12:37	82.02	OK	5884	2026-09-14 12:38	79.41	OK
5885	2026-09-14 12:39	82.28	OK	5886	2026-09-14 12:40	80.99	OK
5887	2026-09-14 12:41	79.47	OK	5888	2026-09-14 12:42	80.85	OK
5889	2026-09-14 12:43	80.36	OK	5890	2026-09-14 12:44	81.55	OK
5891	2026-09-14 12:45	79.20	OK	5892	2026-09-14 12:46	82.82	OK
5893	2026-09-14 12:47	76.93	OK	5894	2026-09-14 12:48	79.51	OK
5895	2026-09-14 12:49	79.79	OK	5896	2026-09-14 12:50	79.61	OK
5897	2026-09-14 12:51	81.56	OK	5898	2026-09-14 12:52	79.05	OK
5899	2026-09-14 12:53	81.73	OK	5900	2026-09-14 12:54	83.08	OK
5901	2026-09-14 12:55	81.55	OK	5902	2026-09-14 12:56	80.66	OK
5903	2026-09-14 12:57	81.89	OK	5904	2026-09-14 12:58	79.43	OK
5905	2026-09-14 12:59	83.15	OK	5906	2026-09-14 13:00	80.85	OK
5907	2026-09-14 13:01	79.47	OK	5908	2026-09-14 13:02	79.27	OK
5909	2026-09-14 13:03	80.80	OK	5910	2026-09-14 13:04	80.32	OK
5911	2026-09-14 13:05	81.14	OK	5912	2026-09-14 13:06	80.97	OK
5913	2026-09-14 13:07	80.07	OK	5914	2026-09-14 13:08	81.33	OK
5915	2026-09-14 13:09	81.56	OK	5916	2026-09-14 13:10	82.33	OK
5917	2026-09-14 13:11	82.25	OK	5918	2026-09-14 13:12	81.37	OK
5919	2026-09-14 13:13	81.19	OK	5920	2026-09-14 13:14	78.40	OK
5921	2026-09-14 13:15	78.03	OK	5922	2026-09-14 13:16	81.73	OK
5923	2026-09-14 13:17	82.41	OK	5924	2026-09-14 13:18	78.95	OK
5925	2026-09-14 13:19	77.94	OK	5926	2026-09-14 13:20	78.81	OK
5927	2026-09-14 13:21	79.92	OK	5928	2026-09-14 13:22	79.19	OK
5929	2026-09-14 13:23	83.87	OK	5930	2026-09-14 13:24	83.71	OK
5931	2026-09-14 13:25	78.43	OK	5932	2026-09-14 13:26	80.62	OK
5933	2026-09-14 13:27	78.13	OK	5934	2026-09-14 13:28	81.85	OK
5935	2026-09-14 13:29	82.53	OK	5936	2026-09-14 13:30	78.90	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5937	2026-09-14 13:31	80.34	OK	5938	2026-09-14 13:32	81.20	OK
5939	2026-09-14 13:33	80.33	OK	5940	2026-09-14 13:34	78.97	OK
5941	2026-09-14 13:35	81.40	OK	5942	2026-09-14 13:36	79.94	OK
5943	2026-09-14 13:37	81.73	OK	5944	2026-09-14 13:38	78.72	OK
5945	2026-09-14 13:39	82.33	OK	5946	2026-09-14 13:40	81.63	OK
5947	2026-09-14 13:41	80.35	OK	5948	2026-09-14 13:42	79.89	OK
5949	2026-09-14 13:43	79.10	OK	5950	2026-09-14 13:44	79.13	OK
5951	2026-09-14 13:45	79.73	OK	5952	2026-09-14 13:46	80.16	OK
5953	2026-09-14 13:47	78.01	OK	5954	2026-09-14 13:48	82.02	OK
5955	2026-09-14 13:49	80.23	OK	5956	2026-09-14 13:50	81.09	OK
5957	2026-09-14 13:51	82.40	OK	5958	2026-09-14 13:52	80.55	OK
5959	2026-09-14 13:53	84.45	OK	5960	2026-09-14 13:54	79.17	OK
5961	2026-09-14 13:55	78.41	OK	5962	2026-09-14 13:56	78.13	OK
5963	2026-09-14 13:57	79.27	OK	5964	2026-09-14 13:58	81.61	OK
5965	2026-09-14 13:59	80.07	OK	5966	2026-09-14 14:00	80.55	OK
5967	2026-09-14 14:01	78.93	OK	5968	2026-09-14 14:02	80.68	OK
5969	2026-09-14 14:03	80.45	OK	5970	2026-09-14 14:04	81.85	OK
5971	2026-09-14 14:05	78.65	OK	5972	2026-09-14 14:06	79.64	OK
5973	2026-09-14 14:07	81.53	OK	5974	2026-09-14 14:08	81.55	OK
5975	2026-09-14 14:09	78.99	OK	5976	2026-09-14 14:10	82.75	OK
5977	2026-09-14 14:11	79.16	OK	5978	2026-09-14 14:12	79.63	OK
5979	2026-09-14 14:13	80.06	OK	5980	2026-09-14 14:14	81.90	OK
5981	2026-09-14 14:15	80.21	OK	5982	2026-09-14 14:16	78.08	OK
5983	2026-09-14 14:17	79.00	OK	5984	2026-09-14 14:18	84.29	OK
5985	2026-09-14 14:19	78.97	OK	5986	2026-09-14 14:20	82.99	OK
5987	2026-09-14 14:21	82.19	OK	5988	2026-09-14 14:22	80.01	OK
5989	2026-09-14 14:23	82.17	OK	5990	2026-09-14 14:24	80.74	OK
5991	2026-09-14 14:25	79.26	OK	5992	2026-09-14 14:26	77.05	OK
5993	2026-09-14 14:27	79.44	OK	5994	2026-09-14 14:28	78.87	OK
5995	2026-09-14 14:29	80.24	OK	5996	2026-09-14 14:30	78.86	OK
5997	2026-09-14 14:31	80.88	OK	5998	2026-09-14 14:32	81.16	OK
5999	2026-09-14 14:33	78.97	OK	6000	2026-09-14 14:34	79.29	OK
6001	2026-09-14 14:35	82.70	OK	6002	2026-09-14 14:36	80.29	OK
6003	2026-09-14 14:37	81.10	OK	6004	2026-09-14 14:38	82.39	OK
6005	2026-09-14 14:39	79.63	OK	6006	2026-09-14 14:40	79.71	OK
6007	2026-09-14 14:41	77.76	OK	6008	2026-09-14 14:42	80.72	OK
6009	2026-09-14 14:43	77.77	OK	6010	2026-09-14 14:44	82.19	OK
6011	2026-09-14 14:45	82.36	OK	6012	2026-09-14 14:46	79.92	OK
6013	2026-09-14 14:47	80.43	OK	6014	2026-09-14 14:48	80.74	OK
6015	2026-09-14 14:49	83.10	OK	6016	2026-09-14 14:50	79.12	OK
6017	2026-09-14 14:51	78.82	OK	6018	2026-09-14 14:52	82.63	OK
6019	2026-09-14 14:53	80.13	OK	6020	2026-09-14 14:54	80.14	OK
6021	2026-09-14 14:55	80.52	OK	6022	2026-09-14 14:56	80.47	OK
6023	2026-09-14 14:57	79.09	OK	6024	2026-09-14 14:58	76.52	OK
6025	2026-09-14 14:59	83.40	OK	6026	2026-09-14 15:00	81.46	OK
6027	2026-09-14 15:01	79.43	OK	6028	2026-09-14 15:02	79.18	OK
6029	2026-09-14 15:03	79.19	OK	6030	2026-09-14 15:04	79.18	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6031	2026-09-14 15:05	81.45	OK	6032	2026-09-14 15:06	79.53	OK
6033	2026-09-14 15:07	78.63	OK	6034	2026-09-14 15:08	79.97	OK
6035	2026-09-14 15:09	76.44	OK	6036	2026-09-14 15:10	82.65	OK
6037	2026-09-14 15:11	76.87	OK	6038	2026-09-14 15:12	80.93	OK
6039	2026-09-14 15:13	81.39	OK	6040	2026-09-14 15:14	79.31	OK
6041	2026-09-14 15:15	78.63	OK	6042	2026-09-14 15:16	82.86	OK
6043	2026-09-14 15:17	76.20	OK	6044	2026-09-14 15:18	81.92	OK
6045	2026-09-14 15:19	80.42	OK	6046	2026-09-14 15:20	81.61	OK
6047	2026-09-14 15:21	83.95	OK	6048	2026-09-14 15:22	79.88	OK
6049	2026-09-14 15:23	79.52	OK	6050	2026-09-14 15:24	79.66	OK
6051	2026-09-14 15:25	81.26	OK	6052	2026-09-14 15:26	78.05	OK
6053	2026-09-14 15:27	79.92	OK	6054	2026-09-14 15:28	80.23	OK
6055	2026-09-14 15:29	79.02	OK	6056	2026-09-14 15:30	77.21	OK
6057	2026-09-14 15:31	78.82	OK	6058	2026-09-14 15:32	79.95	OK
6059	2026-09-14 15:33	81.63	OK	6060	2026-09-14 15:34	81.21	OK
6061	2026-09-14 15:35	82.36	OK	6062	2026-09-14 15:36	80.59	OK
6063	2026-09-14 15:37	77.85	OK	6064	2026-09-14 15:38	82.21	OK
6065	2026-09-14 15:39	79.02	OK	6066	2026-09-14 15:40	77.72	OK
6067	2026-09-14 15:41	82.22	OK	6068	2026-09-14 15:42	79.49	OK
6069	2026-09-14 15:43	81.15	OK	6070	2026-09-14 15:44	81.40	OK
6071	2026-09-14 15:45	80.49	OK	6072	2026-09-14 15:46	76.20	OK
6073	2026-09-14 15:47	79.24	OK	6074	2026-09-14 15:48	78.18	OK
6075	2026-09-14 15:49	78.56	OK	6076	2026-09-14 15:50	77.27	OK
6077	2026-09-14 15:51	78.22	OK	6078	2026-09-14 15:52	82.32	OK
6079	2026-09-14 15:53	81.66	OK	6080	2026-09-14 15:54	76.92	OK
6081	2026-09-14 15:55	79.07	OK	6082	2026-09-14 15:56	80.91	OK
6083	2026-09-14 15:57	79.31	OK	6084	2026-09-14 15:58	78.80	OK
6085	2026-09-14 15:59	81.84	OK	6086	2026-09-14 16:00	77.84	OK
6087	2026-09-14 16:01	79.23	OK	6088	2026-09-14 16:02	79.41	OK
6089	2026-09-14 16:03	78.40	OK	6090	2026-09-14 16:04	78.21	OK
6091	2026-09-14 16:05	78.89	OK	6092	2026-09-14 16:06	77.78	OK
6093	2026-09-14 16:07	79.72	OK	6094	2026-09-14 16:08	79.73	OK
6095	2026-09-14 16:09	77.13	OK	6096	2026-09-14 16:10	75.11	OK
6097	2026-09-14 16:11	79.20	OK	6098	2026-09-14 16:12	76.19	OK
6099	2026-09-14 16:13	80.48	OK	6100	2026-09-14 16:14	79.29	OK
6101	2026-09-14 16:15	80.15	OK	6102	2026-09-14 16:16	79.32	OK
6103	2026-09-14 16:17	77.65	OK	6104	2026-09-14 16:18	76.67	OK
6105	2026-09-14 16:19	76.90	OK	6106	2026-09-14 16:20	77.94	OK
6107	2026-09-14 16:21	77.82	OK	6108	2026-09-14 16:22	79.59	OK
6109	2026-09-14 16:23	75.77	OK	6110	2026-09-14 16:24	78.83	OK
6111	2026-09-14 16:25	76.38	OK	6112	2026-09-14 16:26	77.71	OK
6113	2026-09-14 16:27	78.46	OK	6114	2026-09-14 16:28	76.47	OK
6115	2026-09-14 16:29	78.60	OK	6116	2026-09-14 16:30	76.44	OK
6117	2026-09-14 16:31	75.24	OK	6118	2026-09-14 16:32	77.66	OK
6119	2026-09-14 16:33	79.00	OK	6120	2026-09-14 16:34	76.15	OK
6121	2026-09-14 16:35	80.05	OK	6122	2026-09-14 16:36	81.90	OK
6123	2026-09-14 16:37	80.41	OK	6124	2026-09-14 16:38	75.63	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6125	2026-09-14 16:39	81.28	OK	6126	2026-09-14 16:40	78.41	OK
6127	2026-09-14 16:41	78.39	OK	6128	2026-09-14 16:42	79.75	OK
6129	2026-09-14 16:43	77.01	OK	6130	2026-09-14 16:44	76.26	OK
6131	2026-09-14 16:45	80.53	OK	6132	2026-09-14 16:46	78.26	OK
6133	2026-09-14 16:47	78.18	OK	6134	2026-09-14 16:48	76.07	OK
6135	2026-09-14 16:49	78.05	OK	6136	2026-09-14 16:50	77.44	OK
6137	2026-09-14 16:51	77.17	OK	6138	2026-09-14 16:52	77.11	OK
6139	2026-09-14 16:53	77.05	OK	6140	2026-09-14 16:54	77.71	OK
6141	2026-09-14 16:55	78.97	OK	6142	2026-09-14 16:56	77.32	OK
6143	2026-09-14 16:57	76.61	OK	6144	2026-09-14 16:58	80.30	OK
6145	2026-09-14 16:59	78.16	OK	6146	2026-09-14 17:00	79.80	OK
6147	2026-09-14 17:01	78.21	OK	6148	2026-09-14 17:02	77.95	OK
6149	2026-09-14 17:03	76.86	OK	6150	2026-09-14 17:04	78.20	OK
6151	2026-09-14 17:05	74.61	OK	6152	2026-09-14 17:06	74.69	OK
6153	2026-09-14 17:07	77.69	OK	6154	2026-09-14 17:08	74.05	OK
6155	2026-09-14 17:09	74.53	OK	6156	2026-09-14 17:10	79.60	OK
6157	2026-09-14 17:11	78.34	OK	6158	2026-09-14 17:12	76.76	OK
6159	2026-09-14 17:13	76.27	OK	6160	2026-09-14 17:14	75.07	OK
6161	2026-09-14 17:15	75.07	OK	6162	2026-09-14 17:16	78.46	OK
6163	2026-09-14 17:17	76.04	OK	6164	2026-09-14 17:18	79.23	OK
6165	2026-09-14 17:19	76.05	OK	6166	2026-09-14 17:20	77.64	OK
6167	2026-09-14 17:21	77.82	OK	6168	2026-09-14 17:22	78.27	OK
6169	2026-09-14 17:23	80.97	OK	6170	2026-09-14 17:24	77.39	OK
6171	2026-09-14 17:25	77.22	OK	6172	2026-09-14 17:26	77.71	OK
6173	2026-09-14 17:27	76.04	OK	6174	2026-09-14 17:28	75.31	OK
6175	2026-09-14 17:29	75.88	OK	6176	2026-09-14 17:30	75.01	OK
6177	2026-09-14 17:31	79.30	OK	6178	2026-09-14 17:32	76.65	OK
6179	2026-09-14 17:33	76.11	OK	6180	2026-09-14 17:34	78.48	OK
6181	2026-09-14 17:35	79.64	OK	6182	2026-09-14 17:36	78.39	OK
6183	2026-09-14 17:37	75.30	OK	6184	2026-09-14 17:38	79.81	OK
6185	2026-09-14 17:39	73.19	OK	6186	2026-09-14 17:40	76.44	OK
6187	2026-09-14 17:41	73.86	OK	6188	2026-09-14 17:42	76.69	OK
6189	2026-09-14 17:43	77.79	OK	6190	2026-09-14 17:44	80.92	OK
6191	2026-09-14 17:45	78.60	OK	6192	2026-09-14 17:46	75.08	OK
6193	2026-09-14 17:47	79.33	OK	6194	2026-09-14 17:48	77.43	OK
6195	2026-09-14 17:49	79.07	OK	6196	2026-09-14 17:50	78.04	OK
6197	2026-09-14 17:51	76.24	OK	6198	2026-09-14 17:52	77.90	OK
6199	2026-09-14 17:53	78.66	OK	6200	2026-09-14 17:54	75.37	OK
6201	2026-09-14 17:55	76.30	OK	6202	2026-09-14 17:56	75.09	OK
6203	2026-09-14 17:57	76.23	OK	6204	2026-09-14 17:58	79.89	OK
6205	2026-09-14 17:59	77.77	OK	6206	2026-09-14 18:00	77.83	OK
6207	2026-09-14 18:01	77.32	OK	6208	2026-09-14 18:02	75.67	OK
6209	2026-09-14 18:03	75.33	OK	6210	2026-09-14 18:04	75.46	OK
6211	2026-09-14 18:05	78.62	OK	6212	2026-09-14 18:06	76.57	OK
6213	2026-09-14 18:07	76.42	OK	6214	2026-09-14 18:08	77.50	OK
6215	2026-09-14 18:09	76.59	OK	6216	2026-09-14 18:10	76.76	OK
6217	2026-09-14 18:11	73.44	OK	6218	2026-09-14 18:12	73.81	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6219	2026-09-14 18:13	74.41	OK	6220	2026-09-14 18:14	76.08	OK
6221	2026-09-14 18:15	75.94	OK	6222	2026-09-14 18:16	71.76	OK
6223	2026-09-14 18:17	75.41	OK	6224	2026-09-14 18:18	78.51	OK
6225	2026-09-14 18:19	76.35	OK	6226	2026-09-14 18:20	75.36	OK
6227	2026-09-14 18:21	78.18	OK	6228	2026-09-14 18:22	73.88	OK
6229	2026-09-14 18:23	75.04	OK	6230	2026-09-14 18:24	76.51	OK
6231	2026-09-14 18:25	78.23	OK	6232	2026-09-14 18:26	76.12	OK
6233	2026-09-14 18:27	74.10	OK	6234	2026-09-14 18:28	79.19	OK
6235	2026-09-14 18:29	77.48	OK	6236	2026-09-14 18:30	75.80	OK
6237	2026-09-14 18:31	76.29	OK	6238	2026-09-14 18:32	78.88	OK
6239	2026-09-14 18:33	75.11	OK	6240	2026-09-14 18:34	73.71	OK
6241	2026-09-14 18:35	74.72	OK	6242	2026-09-14 18:36	77.36	OK
6243	2026-09-14 18:37	72.20	OK	6244	2026-09-14 18:38	73.98	OK
6245	2026-09-14 18:39	73.98	OK	6246	2026-09-14 18:40	72.62	OK
6247	2026-09-14 18:41	75.75	OK	6248	2026-09-14 18:42	77.09	OK
6249	2026-09-14 18:43	74.36	OK	6250	2026-09-14 18:44	76.79	OK
6251	2026-09-14 18:45	76.65	OK	6252	2026-09-14 18:46	77.16	OK
6253	2026-09-14 18:47	75.17	OK	6254	2026-09-14 18:48	75.12	OK
6255	2026-09-14 18:49	77.68	OK	6256	2026-09-14 18:50	73.51	OK
6257	2026-09-14 18:51	73.51	OK	6258	2026-09-14 18:52	76.35	OK
6259	2026-09-14 18:53	72.38	OK	6260	2026-09-14 18:54	75.56	OK
6261	2026-09-14 18:55	78.98	OK	6262	2026-09-14 18:56	78.70	OK
6263	2026-09-14 18:57	73.84	OK	6264	2026-09-14 18:58	73.87	OK
6265	2026-09-14 18:59	76.08	OK	6266	2026-09-14 19:00	75.98	OK
6267	2026-09-14 19:01	74.69	OK	6268	2026-09-14 19:02	77.57	OK
6269	2026-09-14 19:03	74.01	OK	6270	2026-09-14 19:04	72.76	OK
6271	2026-09-14 19:05	76.32	OK	6272	2026-09-14 19:06	72.39	OK
6273	2026-09-14 19:07	72.93	OK	6274	2026-09-14 19:08	75.45	OK
6275	2026-09-14 19:09	75.06	OK	6276	2026-09-14 19:10	74.62	OK
6277	2026-09-14 19:11	74.86	OK	6278	2026-09-14 19:12	72.66	OK
6279	2026-09-14 19:13	76.19	OK	6280	2026-09-14 19:14	74.21	OK
6281	2026-09-14 19:15	74.82	OK	6282	2026-09-14 19:16	74.15	OK
6283	2026-09-14 19:17	74.30	OK	6284	2026-09-14 19:18	72.92	OK
6285	2026-09-14 19:19	73.71	OK	6286	2026-09-14 19:20	72.38	OK
6287	2026-09-14 19:21	74.84	OK	6288	2026-09-14 19:22	75.95	OK
6289	2026-09-14 19:23	73.21	OK	6290	2026-09-14 19:24	76.49	OK
6291	2026-09-14 19:25	75.97	OK	6292	2026-09-14 19:26	75.73	OK
6293	2026-09-14 19:27	72.05	OK	6294	2026-09-14 19:28	75.30	OK
6295	2026-09-14 19:29	73.80	OK	6296	2026-09-14 19:30	72.71	OK
6297	2026-09-14 19:31	75.44	OK	6298	2026-09-14 19:32	75.77	OK
6299	2026-09-14 19:33	76.30	OK	6300	2026-09-14 19:34	75.90	OK
6301	2026-09-14 19:35	73.40	OK	6302	2026-09-14 19:36	71.96	OK
6303	2026-09-14 19:37	76.67	OK	6304	2026-09-14 19:38	73.66	OK
6305	2026-09-14 19:39	73.41	OK	6306	2026-09-14 19:40	72.56	OK
6307	2026-09-14 19:41	72.83	OK	6308	2026-09-14 19:42	73.40	OK
6309	2026-09-14 19:43	73.26	OK	6310	2026-09-14 19:44	74.16	OK
6311	2026-09-14 19:45	71.05	OK	6312	2026-09-14 19:46	72.22	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6313	2026-09-14 19:47	71.97	OK	6314	2026-09-14 19:48	73.72	OK
6315	2026-09-14 19:49	74.16	OK	6316	2026-09-14 19:50	72.39	OK
6317	2026-09-14 19:51	74.48	OK	6318	2026-09-14 19:52	75.65	OK
6319	2026-09-14 19:53	71.64	OK	6320	2026-09-14 19:54	71.60	OK
6321	2026-09-14 19:55	72.66	OK	6322	2026-09-14 19:56	75.08	OK
6323	2026-09-14 19:57	75.19	OK	6324	2026-09-14 19:58	72.59	OK
6325	2026-09-14 19:59	74.66	OK	6326	2026-09-14 20:00	73.09	OK
6327	2026-09-14 20:01	72.27	OK	6328	2026-09-14 20:02	74.92	OK
6329	2026-09-14 20:03	73.04	OK	6330	2026-09-14 20:04	74.80	OK
6331	2026-09-14 20:05	73.54	OK	6332	2026-09-14 20:06	73.03	OK
6333	2026-09-14 20:07	76.78	OK	6334	2026-09-14 20:08	70.95	OK
6335	2026-09-14 20:09	74.85	OK	6336	2026-09-14 20:10	72.65	OK
6337	2026-09-14 20:11	70.32	OK	6338	2026-09-14 20:12	74.32	OK
6339	2026-09-14 20:13	72.89	OK	6340	2026-09-14 20:14	70.72	OK
6341	2026-09-14 20:15	72.51	OK	6342	2026-09-14 20:16	73.45	OK
6343	2026-09-14 20:17	74.19	OK	6344	2026-09-14 20:18	71.11	OK
6345	2026-09-14 20:19	72.10	OK	6346	2026-09-14 20:20	74.53	OK
6347	2026-09-14 20:21	73.47	OK	6348	2026-09-14 20:22	71.11	OK
6349	2026-09-14 20:23	74.09	OK	6350	2026-09-14 20:24	70.66	OK
6351	2026-09-14 20:25	72.72	OK	6352	2026-09-14 20:26	73.91	OK
6353	2026-09-14 20:27	72.91	OK	6354	2026-09-14 20:28	71.77	OK
6355	2026-09-14 20:29	71.52	OK	6356	2026-09-14 20:30	73.14	OK
6357	2026-09-14 20:31	73.37	OK	6358	2026-09-14 20:32	74.30	OK
6359	2026-09-14 20:33	74.16	OK	6360	2026-09-14 20:34	72.93	OK
6361	2026-09-14 20:35	74.12	OK	6362	2026-09-14 20:36	74.02	OK
6363	2026-09-14 20:37	74.05	OK	6364	2026-09-14 20:38	72.61	OK
6365	2026-09-14 20:39	73.41	OK	6366	2026-09-14 20:40	71.01	OK
6367	2026-09-14 20:41	73.40	OK	6368	2026-09-14 20:42	74.04	OK
6369	2026-09-14 20:43	72.63	OK	6370	2026-09-14 20:44	73.03	OK
6371	2026-09-14 20:45	73.07	OK	6372	2026-09-14 20:46	72.35	OK
6373	2026-09-14 20:47	72.68	OK	6374	2026-09-14 20:48	70.72	OK
6375	2026-09-14 20:49	72.88	OK	6376	2026-09-14 20:50	70.35	OK
6377	2026-09-14 20:51	70.04	OK	6378	2026-09-14 20:52	73.00	OK
6379	2026-09-14 20:53	73.36	OK	6380	2026-09-14 20:54	70.88	OK
6381	2026-09-14 20:55	74.51	OK	6382	2026-09-14 20:56	73.55	OK
6383	2026-09-14 20:57	70.96	OK	6384	2026-09-14 20:58	70.10	OK
6385	2026-09-14 20:59	70.16	OK	6386	2026-09-14 21:00	74.10	OK
6387	2026-09-14 21:01	70.26	OK	6388	2026-09-14 21:02	70.65	OK
6389	2026-09-14 21:03	73.28	OK	6390	2026-09-14 21:04	72.41	OK
6391	2026-09-14 21:05	70.84	OK	6392	2026-09-14 21:06	71.93	OK
6393	2026-09-14 21:07	69.34	OK	6394	2026-09-14 21:08	73.07	OK
6395	2026-09-14 21:09	72.24	OK	6396	2026-09-14 21:10	71.70	OK
6397	2026-09-14 21:11	72.23	OK	6398	2026-09-14 21:12	71.24	OK
6399	2026-09-14 21:13	70.43	OK	6400	2026-09-14 21:14	72.86	OK
6401	2026-09-14 21:15	70.79	OK	6402	2026-09-14 21:16	74.06	OK
6403	2026-09-14 21:17	72.05	OK	6404	2026-09-14 21:18	72.60	OK
6405	2026-09-14 21:19	71.60	OK	6406	2026-09-14 21:20	70.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6407	2026-09-14 21:21	70.14	OK	6408	2026-09-14 21:22	72.47	OK
6409	2026-09-14 21:23	72.72	OK	6410	2026-09-14 21:24	71.46	OK
6411	2026-09-14 21:25	72.80	OK	6412	2026-09-14 21:26	70.18	OK
6413	2026-09-14 21:27	71.04	OK	6414	2026-09-14 21:28	68.27	OK
6415	2026-09-14 21:29	69.99	OK	6416	2026-09-14 21:30	73.35	OK
6417	2026-09-14 21:31	73.63	OK	6418	2026-09-14 21:32	72.35	OK
6419	2026-09-14 21:33	73.86	OK	6420	2026-09-14 21:34	70.77	OK
6421	2026-09-14 21:35	75.00	OK	6422	2026-09-14 21:36	74.81	OK
6423	2026-09-14 21:37	70.37	OK	6424	2026-09-14 21:38	70.44	OK
6425	2026-09-14 21:39	71.72	OK	6426	2026-09-14 21:40	71.79	OK
6427	2026-09-14 21:41	71.10	OK	6428	2026-09-14 21:42	73.14	OK
6429	2026-09-14 21:43	67.16	OK	6430	2026-09-14 21:44	72.08	OK
6431	2026-09-14 21:45	72.78	OK	6432	2026-09-14 21:46	72.50	OK
6433	2026-09-14 21:47	69.10	OK	6434	2026-09-14 21:48	71.36	OK
6435	2026-09-14 21:49	70.97	OK	6436	2026-09-14 21:50	73.18	OK
6437	2026-09-14 21:51	73.46	OK	6438	2026-09-14 21:52	71.17	OK
6439	2026-09-14 21:53	69.40	OK	6440	2026-09-14 21:54	70.79	OK
6441	2026-09-14 21:55	72.51	OK	6442	2026-09-14 21:56	71.36	OK
6443	2026-09-14 21:57	70.05	OK	6444	2026-09-14 21:58	70.86	OK
6445	2026-09-14 21:59	68.81	OK	6446	2026-09-14 22:00	69.81	OK
6447	2026-09-14 22:01	68.07	OK	6448	2026-09-14 22:02	71.13	OK
6449	2026-09-14 22:03	72.34	OK	6450	2026-09-14 22:04	74.10	OK
6451	2026-09-14 22:05	69.70	OK	6452	2026-09-14 22:06	71.52	OK
6453	2026-09-14 22:07	70.44	OK	6454	2026-09-14 22:08	71.99	OK
6455	2026-09-14 22:09	68.08	OK	6456	2026-09-14 22:10	70.41	OK
6457	2026-09-14 22:11	72.70	OK	6458	2026-09-14 22:12	72.26	OK
6459	2026-09-14 22:13	70.02	OK	6460	2026-09-14 22:14	71.50	OK
6461	2026-09-14 22:15	74.05	OK	6462	2026-09-14 22:16	69.94	OK
6463	2026-09-14 22:17	70.92	OK	6464	2026-09-14 22:18	69.75	OK
6465	2026-09-14 22:19	71.85	OK	6466	2026-09-14 22:20	69.09	OK
6467	2026-09-14 22:21	72.69	OK	6468	2026-09-14 22:22	68.24	OK
6469	2026-09-14 22:23	71.94	OK	6470	2026-09-14 22:24	71.39	OK
6471	2026-09-14 22:25	70.12	OK	6472	2026-09-14 22:26	69.66	OK
6473	2026-09-14 22:27	71.92	OK	6474	2026-09-14 22:28	72.75	OK
6475	2026-09-14 22:29	70.35	OK	6476	2026-09-14 22:30	68.09	OK
6477	2026-09-14 22:31	68.55	OK	6478	2026-09-14 22:32	72.82	OK
6479	2026-09-14 22:33	72.46	OK	6480	2026-09-14 22:34	70.48	OK
6481	2026-09-14 22:35	70.65	OK	6482	2026-09-14 22:36	68.42	OK
6483	2026-09-14 22:37	71.97	OK	6484	2026-09-14 22:38	72.04	OK
6485	2026-09-14 22:39	68.89	OK	6486	2026-09-14 22:40	72.59	OK
6487	2026-09-14 22:41	71.70	OK	6488	2026-09-14 22:42	67.88	OK
6489	2026-09-14 22:43	71.74	OK	6490	2026-09-14 22:44	70.97	OK
6491	2026-09-14 22:45	67.43	OK	6492	2026-09-14 22:46	71.65	OK
6493	2026-09-14 22:47	70.42	OK	6494	2026-09-14 22:48	69.55	OK
6495	2026-09-14 22:49	71.62	OK	6496	2026-09-14 22:50	71.96	OK
6497	2026-09-14 22:51	70.95	OK	6498	2026-09-14 22:52	70.65	OK
6499	2026-09-14 22:53	68.57	OK	6500	2026-09-14 22:54	70.38	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6501	2026-09-14 22:55	69.48	OK	6502	2026-09-14 22:56	70.22	OK
6503	2026-09-14 22:57	70.08	OK	6504	2026-09-14 22:58	70.09	OK
6505	2026-09-14 22:59	70.32	OK	6506	2026-09-14 23:00	71.68	OK
6507	2026-09-14 23:01	68.02	OK	6508	2026-09-14 23:02	69.96	OK
6509	2026-09-14 23:03	71.44	OK	6510	2026-09-14 23:04	67.79	OK
6511	2026-09-14 23:05	70.60	OK	6512	2026-09-14 23:06	72.33	OK
6513	2026-09-14 23:07	66.44	OK	6514	2026-09-14 23:08	69.90	OK
6515	2026-09-14 23:09	70.39	OK	6516	2026-09-14 23:10	68.94	OK
6517	2026-09-14 23:11	69.11	OK	6518	2026-09-14 23:12	70.69	OK
6519	2026-09-14 23:13	73.20	OK	6520	2026-09-14 23:14	70.81	OK
6521	2026-09-14 23:15	68.81	OK	6522	2026-09-14 23:16	70.43	OK
6523	2026-09-14 23:17	70.44	OK	6524	2026-09-14 23:18	72.57	OK
6525	2026-09-14 23:19	69.01	OK	6526	2026-09-14 23:20	69.15	OK
6527	2026-09-14 23:21	69.67	OK	6528	2026-09-14 23:22	67.91	OK
6529	2026-09-14 23:23	72.59	OK	6530	2026-09-14 23:24	68.31	OK
6531	2026-09-14 23:25	67.69	OK	6532	2026-09-14 23:26	68.50	OK
6533	2026-09-14 23:27	67.75	OK	6534	2026-09-14 23:28	70.09	OK
6535	2026-09-14 23:29	68.00	OK	6536	2026-09-14 23:30	69.68	OK
6537	2026-09-14 23:31	69.66	OK	6538	2026-09-14 23:32	70.00	OK
6539	2026-09-14 23:33	70.41	OK	6540	2026-09-14 23:34	68.95	OK
6541	2026-09-14 23:35	72.51	OK	6542	2026-09-14 23:36	71.13	OK
6543	2026-09-14 23:37	72.00	OK	6544	2026-09-14 23:38	71.05	OK
6545	2026-09-14 23:39	70.54	OK	6546	2026-09-14 23:40	69.57	OK
6547	2026-09-14 23:41	67.40	OK	6548	2026-09-14 23:42	66.01	OK
6549	2026-09-14 23:43	69.69	OK	6550	2026-09-14 23:44	71.28	OK
6551	2026-09-14 23:45	70.40	OK	6552	2026-09-14 23:46	68.72	OK
6553	2026-09-14 23:47	70.90	OK	6554	2026-09-14 23:48	73.07	OK
6555	2026-09-14 23:49	68.16	OK	6556	2026-09-14 23:50	70.82	OK
6557	2026-09-14 23:51	67.78	OK	6558	2026-09-14 23:52	66.28	OK
6559	2026-09-14 23:53	72.05	OK	6560	2026-09-14 23:54	67.74	OK
6561	2026-09-14 23:55	67.16	OK	6562	2026-09-14 23:56	70.96	OK
6563	2026-09-14 23:57	68.97	OK	6564	2026-09-14 23:58	69.52	OK
6565	2026-09-14 23:59	72.70	OK	6566	2026-09-15 00:00	70.73	OK
6567	2026-09-15 00:01	70.21	OK	6568	2026-09-15 00:02	67.46	OK
6569	2026-09-15 00:03	69.71	OK	6570	2026-09-15 00:04	70.13	OK
6571	2026-09-15 00:05	67.75	OK	6572	2026-09-15 00:06	71.41	OK
6573	2026-09-15 00:07	70.53	OK	6574	2026-09-15 00:08	68.77	OK
6575	2026-09-15 00:09	69.84	OK	6576	2026-09-15 00:10	68.17	OK
6577	2026-09-15 00:11	68.02	OK	6578	2026-09-15 00:12	70.76	OK
6579	2026-09-15 00:13	67.99	OK	6580	2026-09-15 00:14	69.29	OK
6581	2026-09-15 00:15	67.77	OK	6582	2026-09-15 00:16	67.11	OK
6583	2026-09-15 00:17	70.01	OK	6584	2026-09-15 00:18	68.36	OK
6585	2026-09-15 00:19	69.04	OK	6586	2026-09-15 00:20	72.13	OK
6587	2026-09-15 00:21	69.78	OK	6588	2026-09-15 00:22	71.89	OK
6589	2026-09-15 00:23	71.87	OK	6590	2026-09-15 00:24	71.26	OK
6591	2026-09-15 00:25	69.64	OK	6592	2026-09-15 00:26	67.35	OK
6593	2026-09-15 00:27	71.10	OK	6594	2026-09-15 00:28	71.29	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6595	2026-09-15 00:29	68.10	OK	6596	2026-09-15 00:30	72.40	OK
6597	2026-09-15 00:31	67.46	OK	6598	2026-09-15 00:32	69.40	OK
6599	2026-09-15 00:33	67.31	OK	6600	2026-09-15 00:34	70.84	OK
6601	2026-09-15 00:35	68.71	OK	6602	2026-09-15 00:36	70.54	OK
6603	2026-09-15 00:37	68.54	OK	6604	2026-09-15 00:38	67.00	OK
6605	2026-09-15 00:39	69.55	OK	6606	2026-09-15 00:40	66.38	OK
6607	2026-09-15 00:41	66.76	OK	6608	2026-09-15 00:42	68.32	OK
6609	2026-09-15 00:43	69.29	OK	6610	2026-09-15 00:44	65.31	OK
6611	2026-09-15 00:45	71.59	OK	6612	2026-09-15 00:46	68.55	OK
6613	2026-09-15 00:47	69.09	OK	6614	2026-09-15 00:48	72.54	OK
6615	2026-09-15 00:49	69.38	OK	6616	2026-09-15 00:50	68.10	OK
6617	2026-09-15 00:51	65.43	OK	6618	2026-09-15 00:52	68.72	OK
6619	2026-09-15 00:53	70.06	OK	6620	2026-09-15 00:54	70.84	OK
6621	2026-09-15 00:55	70.37	OK	6622	2026-09-15 00:56	67.78	OK
6623	2026-09-15 00:57	68.47	OK	6624	2026-09-15 00:58	69.74	OK
6625	2026-09-15 00:59	68.61	OK	6626	2026-09-15 01:00	73.18	OK
6627	2026-09-15 01:01	68.47	OK	6628	2026-09-15 01:02	67.15	OK
6629	2026-09-15 01:03	70.83	OK	6630	2026-09-15 01:04	71.54	OK
6631	2026-09-15 01:05	70.23	OK	6632	2026-09-15 01:06	67.35	OK
6633	2026-09-15 01:07	70.68	OK	6634	2026-09-15 01:08	70.34	OK
6635	2026-09-15 01:09	67.39	OK	6636	2026-09-15 01:10	68.12	OK
6637	2026-09-15 01:11	70.87	OK	6638	2026-09-15 01:12	67.25	OK
6639	2026-09-15 01:13	70.27	OK	6640	2026-09-15 01:14	69.60	OK
6641	2026-09-15 01:15	71.10	OK	6642	2026-09-15 01:16	69.16	OK
6643	2026-09-15 01:17	70.93	OK	6644	2026-09-15 01:18	70.37	OK
6645	2026-09-15 01:19	68.09	OK	6646	2026-09-15 01:20	69.29	OK
6647	2026-09-15 01:21	70.84	OK	6648	2026-09-15 01:22	68.77	OK
6649	2026-09-15 01:23	73.69	OK	6650	2026-09-15 01:24	71.02	OK
6651	2026-09-15 01:25	71.38	OK	6652	2026-09-15 01:26	69.78	OK
6653	2026-09-15 01:27	67.41	OK	6654	2026-09-15 01:28	71.02	OK
6655	2026-09-15 01:29	68.90	OK	6656	2026-09-15 01:30	71.74	OK
6657	2026-09-15 01:31	71.48	OK	6658	2026-09-15 01:32	69.59	OK
6659	2026-09-15 01:33	69.06	OK	6660	2026-09-15 01:34	69.16	OK
6661	2026-09-15 01:35	67.43	OK	6662	2026-09-15 01:36	66.66	OK
6663	2026-09-15 01:37	68.79	OK	6664	2026-09-15 01:38	72.34	OK
6665	2026-09-15 01:39	68.36	OK	6666	2026-09-15 01:40	70.05	OK
6667	2026-09-15 01:41	66.98	OK	6668	2026-09-15 01:42	71.46	OK
6669	2026-09-15 01:43	70.04	OK	6670	2026-09-15 01:44	66.88	OK
6671	2026-09-15 01:45	66.65	OK	6672	2026-09-15 01:46	66.57	OK
6673	2026-09-15 01:47	71.99	OK	6674	2026-09-15 01:48	70.54	OK
6675	2026-09-15 01:49	71.26	OK	6676	2026-09-15 01:50	71.47	OK
6677	2026-09-15 01:51	70.13	OK	6678	2026-09-15 01:52	67.77	OK
6679	2026-09-15 01:53	69.08	OK	6680	2026-09-15 01:54	71.39	OK
6681	2026-09-15 01:55	71.34	OK	6682	2026-09-15 01:56	71.39	OK
6683	2026-09-15 01:57	68.82	OK	6684	2026-09-15 01:58	67.92	OK
6685	2026-09-15 01:59	73.50	OK	6686	2026-09-15 02:00	69.30	OK
6687	2026-09-15 02:01	69.44	OK	6688	2026-09-15 02:02	67.04	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6689	2026-09-15 02:03	70.47	OK	6690	2026-09-15 02:04	69.12	OK
6691	2026-09-15 02:05	68.44	OK	6692	2026-09-15 02:06	69.63	OK
6693	2026-09-15 02:07	72.03	OK	6694	2026-09-15 02:08	69.33	OK
6695	2026-09-15 02:09	70.70	OK	6696	2026-09-15 02:10	71.18	OK
6697	2026-09-15 02:11	65.66	OK	6698	2026-09-15 02:12	71.72	OK
6699	2026-09-15 02:13	70.35	OK	6700	2026-09-15 02:14	70.41	OK
6701	2026-09-15 02:15	69.19	OK	6702	2026-09-15 02:16	70.20	OK
6703	2026-09-15 02:17	65.99	OK	6704	2026-09-15 02:18	71.10	OK
6705	2026-09-15 02:19	70.56	OK	6706	2026-09-15 02:20	69.58	OK
6707	2026-09-15 02:21	70.08	OK	6708	2026-09-15 02:22	71.52	OK
6709	2026-09-15 02:23	70.14	OK	6710	2026-09-15 02:24	73.13	OK
6711	2026-09-15 02:25	70.67	OK	6712	2026-09-15 02:26	69.19	OK
6713	2026-09-15 02:27	71.11	OK	6714	2026-09-15 02:28	73.47	OK
6715	2026-09-15 02:29	67.92	OK	6716	2026-09-15 02:30	67.95	OK
6717	2026-09-15 02:31	73.36	OK	6718	2026-09-15 02:32	70.76	OK
6719	2026-09-15 02:33	69.83	OK	6720	2026-09-15 02:34	72.15	OK
6721	2026-09-15 02:35	71.43	OK	6722	2026-09-15 02:36	70.85	OK
6723	2026-09-15 02:37	70.39	OK	6724	2026-09-15 02:38	69.24	OK
6725	2026-09-15 02:39	69.57	OK	6726	2026-09-15 02:40	71.88	OK
6727	2026-09-15 02:41	73.67	OK	6728	2026-09-15 02:42	69.89	OK
6729	2026-09-15 02:43	70.06	OK	6730	2026-09-15 02:44	69.08	OK
6731	2026-09-15 02:45	71.21	OK	6732	2026-09-15 02:46	68.75	OK
6733	2026-09-15 02:47	70.17	OK	6734	2026-09-15 02:48	69.45	OK
6735	2026-09-15 02:49	72.69	OK	6736	2026-09-15 02:50	69.50	OK
6737	2026-09-15 02:51	67.47	OK	6738	2026-09-15 02:52	70.81	OK
6739	2026-09-15 02:53	73.02	OK	6740	2026-09-15 02:54	69.99	OK
6741	2026-09-15 02:55	71.58	OK	6742	2026-09-15 02:56	67.65	OK
6743	2026-09-15 02:57	70.14	OK	6744	2026-09-15 02:58	72.36	OK
6745	2026-09-15 02:59	71.52	OK	6746	2026-09-15 03:00	70.62	OK
6747	2026-09-15 03:01	72.62	OK	6748	2026-09-15 03:02	71.94	OK
6749	2026-09-15 03:03	69.12	OK	6750	2026-09-15 03:04	69.36	OK
6751	2026-09-15 03:05	70.36	OK	6752	2026-09-15 03:06	72.89	OK
6753	2026-09-15 03:07	72.15	OK	6754	2026-09-15 03:08	67.92	OK
6755	2026-09-15 03:09	71.76	OK	6756	2026-09-15 03:10	69.43	OK
6757	2026-09-15 03:11	69.62	OK	6758	2026-09-15 03:12	69.14	OK
6759	2026-09-15 03:13	72.29	OK	6760	2026-09-15 03:14	73.28	OK
6761	2026-09-15 03:15	71.53	OK	6762	2026-09-15 03:16	71.21	OK
6763	2026-09-15 03:17	68.99	OK	6764	2026-09-15 03:18	69.94	OK
6765	2026-09-15 03:19	73.46	OK	6766	2026-09-15 03:20	72.12	OK
6767	2026-09-15 03:21	68.03	OK	6768	2026-09-15 03:22	72.01	OK
6769	2026-09-15 03:23	72.55	OK	6770	2026-09-15 03:24	69.66	OK
6771	2026-09-15 03:25	72.79	OK	6772	2026-09-15 03:26	70.02	OK
6773	2026-09-15 03:27	69.76	OK	6774	2026-09-15 03:28	70.48	OK
6775	2026-09-15 03:29	72.38	OK	6776	2026-09-15 03:30	72.19	OK
6777	2026-09-15 03:31	70.20	OK	6778	2026-09-15 03:32	69.72	OK
6779	2026-09-15 03:33	72.25	OK	6780	2026-09-15 03:34	70.66	OK
6781	2026-09-15 03:35	70.87	OK	6782	2026-09-15 03:36	72.53	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6783	2026-09-15 03:37	71.37	OK	6784	2026-09-15 03:38	70.04	OK
6785	2026-09-15 03:39	70.44	OK	6786	2026-09-15 03:40	71.07	OK
6787	2026-09-15 03:41	70.88	OK	6788	2026-09-15 03:42	69.34	OK
6789	2026-09-15 03:43	71.51	OK	6790	2026-09-15 03:44	68.21	OK
6791	2026-09-15 03:45	72.73	OK	6792	2026-09-15 03:46	68.48	OK
6793	2026-09-15 03:47	71.44	OK	6794	2026-09-15 03:48	72.33	OK
6795	2026-09-15 03:49	69.64	OK	6796	2026-09-15 03:50	70.35	OK
6797	2026-09-15 03:51	70.70	OK	6798	2026-09-15 03:52	70.35	OK
6799	2026-09-15 03:53	71.54	OK	6800	2026-09-15 03:54	69.55	OK
6801	2026-09-15 03:55	72.86	OK	6802	2026-09-15 03:56	73.98	OK
6803	2026-09-15 03:57	72.52	OK	6804	2026-09-15 03:58	71.94	OK
6805	2026-09-15 03:59	70.18	OK	6806	2026-09-15 04:00	73.16	OK
6807	2026-09-15 04:01	74.53	OK	6808	2026-09-15 04:02	70.62	OK
6809	2026-09-15 04:03	72.64	OK	6810	2026-09-15 04:04	69.42	OK
6811	2026-09-15 04:05	71.64	OK	6812	2026-09-15 04:06	73.11	OK
6813	2026-09-15 04:07	69.98	OK	6814	2026-09-15 04:08	72.35	OK
6815	2026-09-15 04:09	70.24	OK	6816	2026-09-15 04:10	73.65	OK
6817	2026-09-15 04:11	68.87	OK	6818	2026-09-15 04:12	74.21	OK
6819	2026-09-15 04:13	71.51	OK	6820	2026-09-15 04:14	70.77	OK
6821	2026-09-15 04:15	74.82	OK	6822	2026-09-15 04:16	71.77	OK
6823	2026-09-15 04:17	72.05	OK	6824	2026-09-15 04:18	72.35	OK
6825	2026-09-15 04:19	71.02	OK	6826	2026-09-15 04:20	70.46	OK
6827	2026-09-15 04:21	75.34	OK	6828	2026-09-15 04:22	72.37	OK
6829	2026-09-15 04:23	72.02	OK	6830	2026-09-15 04:24	74.14	OK
6831	2026-09-15 04:25	70.43	OK	6832	2026-09-15 04:26	71.08	OK
6833	2026-09-15 04:27	71.52	OK	6834	2026-09-15 04:28	73.68	OK
6835	2026-09-15 04:29	69.79	OK	6836	2026-09-15 04:30	69.33	OK
6837	2026-09-15 04:31	72.31	OK	6838	2026-09-15 04:32	72.96	OK
6839	2026-09-15 04:33	74.12	OK	6840	2026-09-15 04:34	74.36	OK
6841	2026-09-15 04:35	75.89	OK	6842	2026-09-15 04:36	71.02	OK
6843	2026-09-15 04:37	69.52	OK	6844	2026-09-15 04:38	71.97	OK
6845	2026-09-15 04:39	73.37	OK	6846	2026-09-15 04:40	70.19	OK
6847	2026-09-15 04:41	71.82	OK	6848	2026-09-15 04:42	72.19	OK
6849	2026-09-15 04:43	72.40	OK	6850	2026-09-15 04:44	75.70	OK
6851	2026-09-15 04:45	70.39	OK	6852	2026-09-15 04:46	70.87	OK
6853	2026-09-15 04:47	73.99	OK	6854	2026-09-15 04:48	69.57	OK
6855	2026-09-15 04:49	71.08	OK	6856	2026-09-15 04:50	73.19	OK
6857	2026-09-15 04:51	73.97	OK	6858	2026-09-15 04:52	72.72	OK
6859	2026-09-15 04:53	70.57	OK	6860	2026-09-15 04:54	73.10	OK
6861	2026-09-15 04:55	75.19	OK	6862	2026-09-15 04:56	73.30	OK
6863	2026-09-15 04:57	70.70	OK	6864	2026-09-15 04:58	73.11	OK
6865	2026-09-15 04:59	68.94	OK	6866	2026-09-15 05:00	74.18	OK
6867	2026-09-15 05:01	74.98	OK	6868	2026-09-15 05:02	70.43	OK
6869	2026-09-15 05:03	71.52	OK	6870	2026-09-15 05:04	73.91	OK
6871	2026-09-15 05:05	73.73	OK	6872	2026-09-15 05:06	73.74	OK
6873	2026-09-15 05:07	72.42	OK	6874	2026-09-15 05:08	71.66	OK
6875	2026-09-15 05:09	75.70	OK	6876	2026-09-15 05:10	72.51	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6877	2026-09-15 05:11	72.09	OK	6878	2026-09-15 05:12	74.40	OK
6879	2026-09-15 05:13	71.59	OK	6880	2026-09-15 05:14	73.07	OK
6881	2026-09-15 05:15	72.93	OK	6882	2026-09-15 05:16	70.39	OK
6883	2026-09-15 05:17	75.19	OK	6884	2026-09-15 05:18	73.59	OK
6885	2026-09-15 05:19	70.69	OK	6886	2026-09-15 05:20	70.96	OK
6887	2026-09-15 05:21	72.00	OK	6888	2026-09-15 05:22	72.64	OK
6889	2026-09-15 05:23	72.97	OK	6890	2026-09-15 05:24	74.04	OK
6891	2026-09-15 05:25	72.79	OK	6892	2026-09-15 05:26	72.09	OK
6893	2026-09-15 05:27	72.65	OK	6894	2026-09-15 05:28	73.14	OK
6895	2026-09-15 05:29	74.33	OK	6896	2026-09-15 05:30	75.66	OK
6897	2026-09-15 05:31	72.12	OK	6898	2026-09-15 05:32	75.82	OK
6899	2026-09-15 05:33	70.31	OK	6900	2026-09-15 05:34	73.87	OK
6901	2026-09-15 05:35	73.98	OK	6902	2026-09-15 05:36	73.55	OK
6903	2026-09-15 05:37	75.52	OK	6904	2026-09-15 05:38	74.76	OK
6905	2026-09-15 05:39	75.08	OK	6906	2026-09-15 05:40	73.85	OK
6907	2026-09-15 05:41	74.74	OK	6908	2026-09-15 05:42	70.60	OK
6909	2026-09-15 05:43	74.95	OK	6910	2026-09-15 05:44	76.00	OK
6911	2026-09-15 05:45	72.79	OK	6912	2026-09-15 05:46	72.94	OK
6913	2026-09-15 05:47	73.10	OK	6914	2026-09-15 05:48	72.50	OK
6915	2026-09-15 05:49	77.36	OK	6916	2026-09-15 05:50	74.63	OK
6917	2026-09-15 05:51	75.55	OK	6918	2026-09-15 05:52	75.36	OK
6919	2026-09-15 05:53	72.56	OK	6920	2026-09-15 05:54	73.07	OK
6921	2026-09-15 05:55	73.32	OK	6922	2026-09-15 05:56	74.53	OK
6923	2026-09-15 05:57	73.76	OK	6924	2026-09-15 05:58	76.05	OK
6925	2026-09-15 05:59	77.30	OK	6926	2026-09-15 06:00	75.16	OK
6927	2026-09-15 06:01	74.26	OK	6928	2026-09-15 06:02	74.56	OK
6929	2026-09-15 06:03	75.01	OK	6930	2026-09-15 06:04	73.73	OK
6931	2026-09-15 06:05	71.42	OK	6932	2026-09-15 06:06	75.37	OK
6933	2026-09-15 06:07	72.43	OK	6934	2026-09-15 06:08	73.09	OK
6935	2026-09-15 06:09	73.10	OK	6936	2026-09-15 06:10	72.21	OK
6937	2026-09-15 06:11	73.48	OK	6938	2026-09-15 06:12	74.19	OK
6939	2026-09-15 06:13	74.09	OK	6940	2026-09-15 06:14	74.16	OK
6941	2026-09-15 06:15	73.33	OK	6942	2026-09-15 06:16	74.32	OK
6943	2026-09-15 06:17	73.92	OK	6944	2026-09-15 06:18	76.46	OK
6945	2026-09-15 06:19	72.14	OK	6946	2026-09-15 06:20	72.68	OK
6947	2026-09-15 06:21	71.62	OK	6948	2026-09-15 06:22	72.94	OK
6949	2026-09-15 06:23	75.41	OK	6950	2026-09-15 06:24	73.63	OK
6951	2026-09-15 06:25	73.13	OK	6952	2026-09-15 06:26	71.95	OK
6953	2026-09-15 06:27	74.76	OK	6954	2026-09-15 06:28	76.12	OK
6955	2026-09-15 06:29	78.14	OK	6956	2026-09-15 06:30	74.21	OK
6957	2026-09-15 06:31	75.40	OK	6958	2026-09-15 06:32	75.59	OK
6959	2026-09-15 06:33	75.91	OK	6960	2026-09-15 06:34	77.34	OK
6961	2026-09-15 06:35	71.20	OK	6962	2026-09-15 06:36	75.18	OK
6963	2026-09-15 06:37	75.77	OK	6964	2026-09-15 06:38	73.68	OK
6965	2026-09-15 06:39	71.39	OK	6966	2026-09-15 06:40	74.25	OK
6967	2026-09-15 06:41	72.88	OK	6968	2026-09-15 06:42	73.52	OK
6969	2026-09-15 06:43	75.16	OK	6970	2026-09-15 06:44	71.02	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6971	2026-09-15 06:45	75.62	OK	6972	2026-09-15 06:46	75.34	OK
6973	2026-09-15 06:47	76.98	OK	6974	2026-09-15 06:48	74.65	OK
6975	2026-09-15 06:49	73.27	OK	6976	2026-09-15 06:50	76.28	OK
6977	2026-09-15 06:51	75.02	OK	6978	2026-09-15 06:52	73.15	OK
6979	2026-09-15 06:53	76.70	OK	6980	2026-09-15 06:54	76.76	OK
6981	2026-09-15 06:55	74.56	OK	6982	2026-09-15 06:56	72.86	OK
6983	2026-09-15 06:57	73.13	OK	6984	2026-09-15 06:58	72.97	OK
6985	2026-09-15 06:59	73.97	OK	6986	2026-09-15 07:00	77.22	OK
6987	2026-09-15 07:01	76.06	OK	6988	2026-09-15 07:02	76.40	OK
6989	2026-09-15 07:03	75.98	OK	6990	2026-09-15 07:04	74.17	OK
6991	2026-09-15 07:05	74.63	OK	6992	2026-09-15 07:06	77.63	OK
6993	2026-09-15 07:07	78.17	OK	6994	2026-09-15 07:08	74.74	OK
6995	2026-09-15 07:09	73.23	OK	6996	2026-09-15 07:10	76.22	OK
6997	2026-09-15 07:11	74.44	OK	6998	2026-09-15 07:12	73.86	OK
6999	2026-09-15 07:13	77.13	OK	7000	2026-09-15 07:14	75.18	OK
7001	2026-09-15 07:15	72.45	OK	7002	2026-09-15 07:16	76.28	OK
7003	2026-09-15 07:17	73.95	OK	7004	2026-09-15 07:18	77.32	OK
7005	2026-09-15 07:19	75.56	OK	7006	2026-09-15 07:20	76.89	OK
7007	2026-09-15 07:21	76.20	OK	7008	2026-09-15 07:22	75.70	OK
7009	2026-09-15 07:23	76.57	OK	7010	2026-09-15 07:24	76.39	OK
7011	2026-09-15 07:25	75.53	OK	7012	2026-09-15 07:26	77.35	OK
7013	2026-09-15 07:27	76.08	OK	7014	2026-09-15 07:28	77.08	OK
7015	2026-09-15 07:29	75.33	OK	7016	2026-09-15 07:30	73.24	OK
7017	2026-09-15 07:31	75.96	OK	7018	2026-09-15 07:32	75.02	OK
7019	2026-09-15 07:33	79.30	OK	7020	2026-09-15 07:34	74.31	OK
7021	2026-09-15 07:35	76.51	OK	7022	2026-09-15 07:36	76.42	OK
7023	2026-09-15 07:37	74.79	OK	7024	2026-09-15 07:38	75.75	OK
7025	2026-09-15 07:39	77.36	OK	7026	2026-09-15 07:40	76.96	OK
7027	2026-09-15 07:41	76.54	OK	7028	2026-09-15 07:42	72.43	OK
7029	2026-09-15 07:43	77.35	OK	7030	2026-09-15 07:44	77.57	OK
7031	2026-09-15 07:45	74.98	OK	7032	2026-09-15 07:46	79.22	OK
7033	2026-09-15 07:47	75.73	OK	7034	2026-09-15 07:48	74.14	OK
7035	2026-09-15 07:49	75.72	OK	7036	2026-09-15 07:50	77.74	OK
7037	2026-09-15 07:51	76.98	OK	7038	2026-09-15 07:52	78.25	OK
7039	2026-09-15 07:53	76.27	OK	7040	2026-09-15 07:54	76.42	OK
7041	2026-09-15 07:55	74.89	OK	7042	2026-09-15 07:56	74.32	OK
7043	2026-09-15 07:57	76.64	OK	7044	2026-09-15 07:58	78.38	OK
7045	2026-09-15 07:59	74.23	OK	7046	2026-09-15 08:00	77.71	OK
7047	2026-09-15 08:01	76.10	OK	7048	2026-09-15 08:02	79.52	OK
7049	2026-09-15 08:03	75.55	OK	7050	2026-09-15 08:04	80.61	OK
7051	2026-09-15 08:05	73.44	OK	7052	2026-09-15 08:06	78.21	OK
7053	2026-09-15 08:07	75.92	OK	7054	2026-09-15 08:08	76.83	OK
7055	2026-09-15 08:09	75.57	OK	7056	2026-09-15 08:10	76.13	OK
7057	2026-09-15 08:11	78.03	OK	7058	2026-09-15 08:12	74.48	OK
7059	2026-09-15 08:13	73.16	OK	7060	2026-09-15 08:14	77.86	OK
7061	2026-09-15 08:15	75.88	OK	7062	2026-09-15 08:16	74.61	OK
7063	2026-09-15 08:17	78.37	OK	7064	2026-09-15 08:18	75.71	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7065	2026-09-15 08:19	77.25	OK	7066	2026-09-15 08:20	78.77	OK
7067	2026-09-15 08:21	75.57	OK	7068	2026-09-15 08:22	80.26	OK
7069	2026-09-15 08:23	74.55	OK	7070	2026-09-15 08:24	75.43	OK
7071	2026-09-15 08:25	75.67	OK	7072	2026-09-15 08:26	76.14	OK
7073	2026-09-15 08:27	73.44	OK	7074	2026-09-15 08:28	77.43	OK
7075	2026-09-15 08:29	80.65	OK	7076	2026-09-15 08:30	80.04	OK
7077	2026-09-15 08:31	75.35	OK	7078	2026-09-15 08:32	77.02	OK
7079	2026-09-15 08:33	77.72	OK	7080	2026-09-15 08:34	78.05	OK
7081	2026-09-15 08:35	78.96	OK	7082	2026-09-15 08:36	76.04	OK
7083	2026-09-15 08:37	79.19	OK	7084	2026-09-15 08:38	77.98	OK
7085	2026-09-15 08:39	76.96	OK	7086	2026-09-15 08:40	76.91	OK
7087	2026-09-15 08:41	78.52	OK	7088	2026-09-15 08:42	75.84	OK
7089	2026-09-15 08:43	76.44	OK	7090	2026-09-15 08:44	77.38	OK
7091	2026-09-15 08:45	78.17	OK	7092	2026-09-15 08:46	77.16	OK
7093	2026-09-15 08:47	77.37	OK	7094	2026-09-15 08:48	76.61	OK
7095	2026-09-15 08:49	78.73	OK	7096	2026-09-15 08:50	78.37	OK
7097	2026-09-15 08:51	79.92	OK	7098	2026-09-15 08:52	79.69	OK
7099	2026-09-15 08:53	77.44	OK	7100	2026-09-15 08:54	79.91	OK
7101	2026-09-15 08:55	76.49	OK	7102	2026-09-15 08:56	78.48	OK
7103	2026-09-15 08:57	77.26	OK	7104	2026-09-15 08:58	78.45	OK
7105	2026-09-15 08:59	78.58	OK	7106	2026-09-15 09:00	77.61	OK
7107	2026-09-15 09:01	80.26	OK	7108	2026-09-15 09:02	78.06	OK
7109	2026-09-15 09:03	76.94	OK	7110	2026-09-15 09:04	80.50	OK
7111	2026-09-15 09:05	80.72	OK	7112	2026-09-15 09:06	77.04	OK
7113	2026-09-15 09:07	77.16	OK	7114	2026-09-15 09:08	75.34	OK
7115	2026-09-15 09:09	77.61	OK	7116	2026-09-15 09:10	80.43	OK
7117	2026-09-15 09:11	78.84	OK	7118	2026-09-15 09:12	80.34	OK
7119	2026-09-15 09:13	77.67	OK	7120	2026-09-15 09:14	78.65	OK
7121	2026-09-15 09:15	76.52	OK	7122	2026-09-15 09:16	76.05	OK
7123	2026-09-15 09:17	79.27	OK	7124	2026-09-15 09:18	79.27	OK
7125	2026-09-15 09:19	76.58	OK	7126	2026-09-15 09:20	76.73	OK
7127	2026-09-15 09:21	78.91	OK	7128	2026-09-15 09:22	79.95	OK
7129	2026-09-15 09:23	79.24	OK	7130	2026-09-15 09:24	79.39	OK
7131	2026-09-15 09:25	75.96	OK	7132	2026-09-15 09:26	80.97	OK
7133	2026-09-15 09:27	79.46	OK	7134	2026-09-15 09:28	75.87	OK
7135	2026-09-15 09:29	78.07	OK	7136	2026-09-15 09:30	83.23	OK
7137	2026-09-15 09:31	78.19	OK	7138	2026-09-15 09:32	78.51	OK
7139	2026-09-15 09:33	79.10	OK	7140	2026-09-15 09:34	77.50	OK
7141	2026-09-15 09:35	78.00	OK	7142	2026-09-15 09:36	76.10	OK
7143	2026-09-15 09:37	79.77	OK	7144	2026-09-15 09:38	79.43	OK
7145	2026-09-15 09:39	78.46	OK	7146	2026-09-15 09:40	78.81	OK
7147	2026-09-15 09:41	82.29	OK	7148	2026-09-15 09:42	76.40	OK
7149	2026-09-15 09:43	81.75	OK	7150	2026-09-15 09:44	80.43	OK
7151	2026-09-15 09:45	81.62	OK	7152	2026-09-15 09:46	78.24	OK
7153	2026-09-15 09:47	80.97	OK	7154	2026-09-15 09:48	78.82	OK
7155	2026-09-15 09:49	79.40	OK	7156	2026-09-15 09:50	77.13	OK
7157	2026-09-15 09:51	81.57	OK	7158	2026-09-15 09:52	81.18	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7159	2026-09-15 09:53	78.68	OK	7160	2026-09-15 09:54	77.68	OK
7161	2026-09-15 09:55	79.72	OK	7162	2026-09-15 09:56	77.18	OK
7163	2026-09-15 09:57	80.70	OK	7164	2026-09-15 09:58	78.83	OK
7165	2026-09-15 09:59	81.26	OK	7166	2026-09-15 10:00	80.49	OK
7167	2026-09-15 10:01	82.96	OK	7168	2026-09-15 10:02	79.25	OK
7169	2026-09-15 10:03	78.41	OK	7170	2026-09-15 10:04	78.21	OK
7171	2026-09-15 10:05	81.51	OK	7172	2026-09-15 10:06	79.56	OK
7173	2026-09-15 10:07	82.13	OK	7174	2026-09-15 10:08	80.19	OK
7175	2026-09-15 10:09	78.69	OK	7176	2026-09-15 10:10	79.37	OK
7177	2026-09-15 10:11	77.71	OK	7178	2026-09-15 10:12	79.63	OK
7179	2026-09-15 10:13	77.29	OK	7180	2026-09-15 10:14	79.50	OK
7181	2026-09-15 10:15	79.55	OK	7182	2026-09-15 10:16	81.24	OK
7183	2026-09-15 10:17	81.49	OK	7184	2026-09-15 10:18	77.43	OK
7185	2026-09-15 10:19	80.82	OK	7186	2026-09-15 10:20	80.86	OK
7187	2026-09-15 10:21	78.90	OK	7188	2026-09-15 10:22	80.47	OK
7189	2026-09-15 10:23	77.71	OK	7190	2026-09-15 10:24	78.73	OK
7191	2026-09-15 10:25	77.26	OK	7192	2026-09-15 10:26	78.61	OK
7193	2026-09-15 10:27	81.35	OK	7194	2026-09-15 10:28	81.52	OK
7195	2026-09-15 10:29	80.25	OK	7196	2026-09-15 10:30	81.80	OK
7197	2026-09-15 10:31	80.50	OK	7198	2026-09-15 10:32	80.51	OK
7199	2026-09-15 10:33	79.76	OK	7200	2026-09-15 10:34	78.13	OK
7201	2026-09-15 10:35	80.06	OK	7202	2026-09-15 10:36	82.62	OK
7203	2026-09-15 10:37	80.99	OK	7204	2026-09-15 10:38	80.86	OK
7205	2026-09-15 10:39	78.08	OK	7206	2026-09-15 10:40	79.40	OK
7207	2026-09-15 10:41	81.48	OK	7208	2026-09-15 10:42	78.68	OK
7209	2026-09-15 10:43	82.04	OK	7210	2026-09-15 10:44	81.75	OK
7211	2026-09-15 10:45	80.27	OK	7212	2026-09-15 10:46	79.09	OK
7213	2026-09-15 10:47	79.28	OK	7214	2026-09-15 10:48	82.72	OK
7215	2026-09-15 10:49	79.33	OK	7216	2026-09-15 10:50	78.56	OK
7217	2026-09-15 10:51	81.84	OK	7218	2026-09-15 10:52	80.86	OK
7219	2026-09-15 10:53	81.06	OK	7220	2026-09-15 10:54	78.55	OK
7221	2026-09-15 10:55	81.70	OK	7222	2026-09-15 10:56	79.48	OK
7223	2026-09-15 10:57	79.54	OK	7224	2026-09-15 10:58	79.74	OK
7225	2026-09-15 10:59	81.98	OK	7226	2026-09-15 11:00	83.66	OK
7227	2026-09-15 11:01	82.36	OK	7228	2026-09-15 11:02	80.89	OK
7229	2026-09-15 11:03	80.15	OK	7230	2026-09-15 11:04	80.09	OK
7231	2026-09-15 11:05	79.37	OK	7232	2026-09-15 11:06	82.90	OK
7233	2026-09-15 11:07	82.02	OK	7234	2026-09-15 11:08	83.01	OK
7235	2026-09-15 11:09	79.88	OK	7236	2026-09-15 11:10	79.54	OK
7237	2026-09-15 11:11	81.09	OK	7238	2026-09-15 11:12	80.74	OK
7239	2026-09-15 11:13	82.86	OK	7240	2026-09-15 11:14	80.10	OK
7241	2026-09-15 11:15	79.11	OK	7242	2026-09-15 11:16	77.00	OK
7243	2026-09-15 11:17	79.43	OK	7244	2026-09-15 11:18	77.78	OK
7245	2026-09-15 11:19	83.16	OK	7246	2026-09-15 11:20	81.40	OK
7247	2026-09-15 11:21	82.49	OK	7248	2026-09-15 11:22	82.36	OK
7249	2026-09-15 11:23	81.28	OK	7250	2026-09-15 11:24	79.01	OK
7251	2026-09-15 11:25	80.05	OK	7252	2026-09-15 11:26	80.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7253	2026-09-15 11:27	80.04	OK	7254	2026-09-15 11:28	80.48	OK
7255	2026-09-15 11:29	77.73	OK	7256	2026-09-15 11:30	78.74	OK
7257	2026-09-15 11:31	82.24	OK	7258	2026-09-15 11:32	80.22	OK
7259	2026-09-15 11:33	80.92	OK	7260	2026-09-15 11:34	80.92	OK
7261	2026-09-15 11:35	80.95	OK	7262	2026-09-15 11:36	80.09	OK
7263	2026-09-15 11:37	79.29	OK	7264	2026-09-15 11:38	81.62	OK
7265	2026-09-15 11:39	80.55	OK	7266	2026-09-15 11:40	82.63	OK
7267	2026-09-15 11:41	80.62	OK	7268	2026-09-15 11:42	78.82	OK
7269	2026-09-15 11:43	78.93	OK	7270	2026-09-15 11:44	81.66	OK
7271	2026-09-15 11:45	80.72	OK	7272	2026-09-15 11:46	80.15	OK
7273	2026-09-15 11:47	79.66	OK	7274	2026-09-15 11:48	82.62	OK
7275	2026-09-15 11:49	79.93	OK	7276	2026-09-15 11:50	81.01	OK
7277	2026-09-15 11:51	79.01	OK	7278	2026-09-15 11:52	82.50	OK
7279	2026-09-15 11:53	81.65	OK	7280	2026-09-15 11:54	81.60	OK
7281	2026-09-15 11:55	83.54	OK	7282	2026-09-15 11:56	81.09	OK
7283	2026-09-15 11:57	80.98	OK	7284	2026-09-15 11:58	78.84	OK
7285	2026-09-15 11:59	81.08	OK	7286	2026-09-15 12:00	81.09	OK
7287	2026-09-15 12:01	82.14	OK	7288	2026-09-15 12:02	82.29	OK
7289	2026-09-15 12:03	81.50	OK	7290	2026-09-15 12:04	80.93	OK
7291	2026-09-15 12:05	77.01	OK	7292	2026-09-15 12:06	80.35	OK
7293	2026-09-15 12:07	81.72	OK	7294	2026-09-15 12:08	81.20	OK
7295	2026-09-15 12:09	83.21	OK	7296	2026-09-15 12:10	81.20	OK
7297	2026-09-15 12:11	81.16	OK	7298	2026-09-15 12:12	79.87	OK
7299	2026-09-15 12:13	78.08	OK	7300	2026-09-15 12:14	77.00	OK
7301	2026-09-15 12:15	80.86	OK	7302	2026-09-15 12:16	81.67	OK
7303	2026-09-15 12:17	83.31	OK	7304	2026-09-15 12:18	82.28	OK
7305	2026-09-15 12:19	82.09	OK	7306	2026-09-15 12:20	80.56	OK
7307	2026-09-15 12:21	77.65	OK	7308	2026-09-15 12:22	81.03	OK
7309	2026-09-15 12:23	81.39	OK	7310	2026-09-15 12:24	76.97	OK
7311	2026-09-15 12:25	80.80	OK	7312	2026-09-15 12:26	78.40	OK
7313	2026-09-15 12:27	81.01	OK	7314	2026-09-15 12:28	81.61	OK
7315	2026-09-15 12:29	78.34	OK	7316	2026-09-15 12:30	82.60	OK
7317	2026-09-15 12:31	80.85	OK	7318	2026-09-15 12:32	82.83	OK
7319	2026-09-15 12:33	81.82	OK	7320	2026-09-15 12:34	78.86	OK
7321	2026-09-15 12:35	78.23	OK	7322	2026-09-15 12:36	79.41	OK
7323	2026-09-15 12:37	82.51	OK	7324	2026-09-15 12:38	79.90	OK
7325	2026-09-15 12:39	81.98	OK	7326	2026-09-15 12:40	82.06	OK
7327	2026-09-15 12:41	78.94	OK	7328	2026-09-15 12:42	79.29	OK
7329	2026-09-15 12:43	83.06	OK	7330	2026-09-15 12:44	80.29	OK
7331	2026-09-15 12:45	82.28	OK	7332	2026-09-15 12:46	81.56	OK
7333	2026-09-15 12:47	82.27	OK	7334	2026-09-15 12:48	82.20	OK
7335	2026-09-15 12:49	80.15	OK	7336	2026-09-15 12:50	79.91	OK
7337	2026-09-15 12:51	79.06	OK	7338	2026-09-15 12:52	77.92	OK
7339	2026-09-15 12:53	80.45	OK	7340	2026-09-15 12:54	80.51	OK
7341	2026-09-15 12:55	82.29	OK	7342	2026-09-15 12:56	82.15	OK
7343	2026-09-15 12:57	80.39	OK	7344	2026-09-15 12:58	82.10	OK
7345	2026-09-15 12:59	80.01	OK	7346	2026-09-15 13:00	81.57	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7347	2026-09-15 13:01	81.93	OK	7348	2026-09-15 13:02	81.09	OK
7349	2026-09-15 13:03	82.12	OK	7350	2026-09-15 13:04	81.74	OK
7351	2026-09-15 13:05	78.30	OK	7352	2026-09-15 13:06	77.63	OK
7353	2026-09-15 13:07	84.66	OK	7354	2026-09-15 13:08	77.30	OK
7355	2026-09-15 13:09	82.04	OK	7356	2026-09-15 13:10	80.32	OK
7357	2026-09-15 13:11	82.26	OK	7358	2026-09-15 13:12	80.44	OK
7359	2026-09-15 13:13	84.64	OK	7360	2026-09-15 13:14	81.94	OK
7361	2026-09-15 13:15	81.04	OK	7362	2026-09-15 13:16	78.50	OK
7363	2026-09-15 13:17	79.58	OK	7364	2026-09-15 13:18	84.04	OK
7365	2026-09-15 13:19	83.82	OK	7366	2026-09-15 13:20	82.17	OK
7367	2026-09-15 13:21	82.81	OK	7368	2026-09-15 13:22	81.06	OK
7369	2026-09-15 13:23	82.07	OK	7370	2026-09-15 13:24	79.18	OK
7371	2026-09-15 13:25	80.03	OK	7372	2026-09-15 13:26	81.31	OK
7373	2026-09-15 13:27	79.22	OK	7374	2026-09-15 13:28	78.81	OK
7375	2026-09-15 13:29	80.48	OK	7376	2026-09-15 13:30	81.23	OK
7377	2026-09-15 13:31	83.11	OK	7378	2026-09-15 13:32	80.12	OK
7379	2026-09-15 13:33	80.17	OK	7380	2026-09-15 13:34	81.04	OK
7381	2026-09-15 13:35	78.50	OK	7382	2026-09-15 13:36	77.95	OK
7383	2026-09-15 13:37	79.54	OK	7384	2026-09-15 13:38	80.76	OK
7385	2026-09-15 13:39	82.19	OK	7386	2026-09-15 13:40	82.39	OK
7387	2026-09-15 13:41	79.84	OK	7388	2026-09-15 13:42	82.45	OK
7389	2026-09-15 13:43	78.56	OK	7390	2026-09-15 13:44	79.56	OK
7391	2026-09-15 13:45	80.67	OK	7392	2026-09-15 13:46	80.26	OK
7393	2026-09-15 13:47	80.25	OK	7394	2026-09-15 13:48	83.12	OK
7395	2026-09-15 13:49	85.10	OK	7396	2026-09-15 13:50	81.38	OK
7397	2026-09-15 13:51	80.62	OK	7398	2026-09-15 13:52	78.24	OK
7399	2026-09-15 13:53	81.82	OK	7400	2026-09-15 13:54	80.76	OK
7401	2026-09-15 13:55	80.77	OK	7402	2026-09-15 13:56	81.19	OK
7403	2026-09-15 13:57	78.89	OK	7404	2026-09-15 13:58	78.88	OK
7405	2026-09-15 13:59	80.45	OK	7406	2026-09-15 14:00	77.88	OK
7407	2026-09-15 14:01	79.79	OK	7408	2026-09-15 14:02	81.07	OK
7409	2026-09-15 14:03	79.40	OK	7410	2026-09-15 14:04	81.70	OK
7411	2026-09-15 14:05	79.29	OK	7412	2026-09-15 14:06	79.90	OK
7413	2026-09-15 14:07	82.09	OK	7414	2026-09-15 14:08	79.50	OK
7415	2026-09-15 14:09	83.41	OK	7416	2026-09-15 14:10	78.72	OK
7417	2026-09-15 14:11	83.47	OK	7418	2026-09-15 14:12	79.61	OK
7419	2026-09-15 14:13	80.50	OK	7420	2026-09-15 14:14	81.51	OK
7421	2026-09-15 14:15	77.59	OK	7422	2026-09-15 14:16	79.11	OK
7423	2026-09-15 14:17	82.64	OK	7424	2026-09-15 14:18	80.50	OK
7425	2026-09-15 14:19	81.82	OK	7426	2026-09-15 14:20	79.47	OK
7427	2026-09-15 14:21	79.28	OK	7428	2026-09-15 14:22	78.44	OK
7429	2026-09-15 14:23	81.40	OK	7430	2026-09-15 14:24	79.01	OK
7431	2026-09-15 14:25	77.90	OK	7432	2026-09-15 14:26	81.69	OK
7433	2026-09-15 14:27	82.17	OK	7434	2026-09-15 14:28	80.93	OK
7435	2026-09-15 14:29	78.30	OK	7436	2026-09-15 14:30	80.30	OK
7437	2026-09-15 14:31	80.19	OK	7438	2026-09-15 14:32	81.37	OK
7439	2026-09-15 14:33	82.73	OK	7440	2026-09-15 14:34	79.88	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7441	2026-09-15 14:35	81.03	OK	7442	2026-09-15 14:36	82.47	OK
7443	2026-09-15 14:37	80.00	OK	7444	2026-09-15 14:38	82.49	OK
7445	2026-09-15 14:39	80.48	OK	7446	2026-09-15 14:40	80.49	OK
7447	2026-09-15 14:41	78.97	OK	7448	2026-09-15 14:42	80.69	OK
7449	2026-09-15 14:43	80.57	OK	7450	2026-09-15 14:44	78.59	OK
7451	2026-09-15 14:45	82.70	OK	7452	2026-09-15 14:46	81.53	OK
7453	2026-09-15 14:47	80.48	OK	7454	2026-09-15 14:48	81.36	OK
7455	2026-09-15 14:49	80.94	OK	7456	2026-09-15 14:50	79.89	OK
7457	2026-09-15 14:51	81.34	OK	7458	2026-09-15 14:52	82.19	OK
7459	2026-09-15 14:53	78.54	OK	7460	2026-09-15 14:54	83.09	OK
7461	2026-09-15 14:55	81.01	OK	7462	2026-09-15 14:56	79.08	OK
7463	2026-09-15 14:57	77.90	OK	7464	2026-09-15 14:58	77.76	OK
7465	2026-09-15 14:59	79.75	OK	7466	2026-09-15 15:00	82.36	OK
7467	2026-09-15 15:01	79.93	OK	7468	2026-09-15 15:02	78.49	OK
7469	2026-09-15 15:03	80.61	OK	7470	2026-09-15 15:04	80.81	OK
7471	2026-09-15 15:05	81.13	OK	7472	2026-09-15 15:06	80.51	OK
7473	2026-09-15 15:07	80.77	OK	7474	2026-09-15 15:08	78.81	OK
7475	2026-09-15 15:09	79.61	OK	7476	2026-09-15 15:10	81.22	OK
7477	2026-09-15 15:11	78.86	OK	7478	2026-09-15 15:12	79.53	OK
7479	2026-09-15 15:13	76.67	OK	7480	2026-09-15 15:14	78.86	OK
7481	2026-09-15 15:15	81.16	OK	7482	2026-09-15 15:16	79.43	OK
7483	2026-09-15 15:17	78.12	OK	7484	2026-09-15 15:18	79.05	OK
7485	2026-09-15 15:19	77.31	OK	7486	2026-09-15 15:20	79.63	OK
7487	2026-09-15 15:21	78.06	OK	7488	2026-09-15 15:22	78.80	OK
7489	2026-09-15 15:23	79.87	OK	7490	2026-09-15 15:24	80.93	OK
7491	2026-09-15 15:25	78.75	OK	7492	2026-09-15 15:26	79.87	OK
7493	2026-09-15 15:27	82.69	OK	7494	2026-09-15 15:28	80.05	OK
7495	2026-09-15 15:29	79.73	OK	7496	2026-09-15 15:30	81.99	OK
7497	2026-09-15 15:31	78.65	OK	7498	2026-09-15 15:32	79.16	OK
7499	2026-09-15 15:33	80.36	OK	7500	2026-09-15 15:34	78.32	OK
7501	2026-09-15 15:35	80.33	OK	7502	2026-09-15 15:36	80.44	OK
7503	2026-09-15 15:37	82.22	OK	7504	2026-09-15 15:38	80.36	OK
7505	2026-09-15 15:39	80.64	OK	7506	2026-09-15 15:40	79.87	OK
7507	2026-09-15 15:41	81.64	OK	7508	2026-09-15 15:42	80.65	OK
7509	2026-09-15 15:43	78.91	OK	7510	2026-09-15 15:44	78.74	OK
7511	2026-09-15 15:45	77.99	OK	7512	2026-09-15 15:46	81.35	OK
7513	2026-09-15 15:47	78.93	OK	7514	2026-09-15 15:48	81.98	OK
7515	2026-09-15 15:49	79.91	OK	7516	2026-09-15 15:50	79.46	OK
7517	2026-09-15 15:51	81.86	OK	7518	2026-09-15 15:52	77.21	OK
7519	2026-09-15 15:53	80.59	OK	7520	2026-09-15 15:54	79.26	OK
7521	2026-09-15 15:55	78.07	OK	7522	2026-09-15 15:56	78.55	OK
7523	2026-09-15 15:57	80.45	OK	7524	2026-09-15 15:58	80.19	OK
7525	2026-09-15 15:59	81.35	OK	7526	2026-09-15 16:00	80.46	OK
7527	2026-09-15 16:01	79.15	OK	7528	2026-09-15 16:02	79.33	OK
7529	2026-09-15 16:03	75.91	OK	7530	2026-09-15 16:04	80.25	OK
7531	2026-09-15 16:05	78.76	OK	7532	2026-09-15 16:06	78.06	OK
7533	2026-09-15 16:07	80.81	OK	7534	2026-09-15 16:08	80.14	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7535	2026-09-15 16:09	79.05	OK	7536	2026-09-15 16:10	79.49	OK
7537	2026-09-15 16:11	80.62	OK	7538	2026-09-15 16:12	77.78	OK
7539	2026-09-15 16:13	79.58	OK	7540	2026-09-15 16:14	75.82	OK
7541	2026-09-15 16:15	79.50	OK	7542	2026-09-15 16:16	78.64	OK
7543	2026-09-15 16:17	81.82	OK	7544	2026-09-15 16:18	80.88	OK
7545	2026-09-15 16:19	79.98	OK	7546	2026-09-15 16:20	79.40	OK
7547	2026-09-15 16:21	79.66	OK	7548	2026-09-15 16:22	79.72	OK
7549	2026-09-15 16:23	79.81	OK	7550	2026-09-15 16:24	78.02	OK
7551	2026-09-15 16:25	80.64	OK	7552	2026-09-15 16:26	78.53	OK
7553	2026-09-15 16:27	79.37	OK	7554	2026-09-15 16:28	78.47	OK
7555	2026-09-15 16:29	77.47	OK	7556	2026-09-15 16:30	81.09	OK
7557	2026-09-15 16:31	78.62	OK	7558	2026-09-15 16:32	78.48	OK
7559	2026-09-15 16:33	80.23	OK	7560	2026-09-15 16:34	79.65	OK
7561	2026-09-15 16:35	77.14	OK	7562	2026-09-15 16:36	76.82	OK
7563	2026-09-15 16:37	78.31	OK	7564	2026-09-15 16:38	77.43	OK
7565	2026-09-15 16:39	79.86	OK	7566	2026-09-15 16:40	78.07	OK
7567	2026-09-15 16:41	75.09	OK	7568	2026-09-15 16:42	75.97	OK
7569	2026-09-15 16:43	74.89	OK	7570	2026-09-15 16:44	79.91	OK
7571	2026-09-15 16:45	77.82	OK	7572	2026-09-15 16:46	78.03	OK
7573	2026-09-15 16:47	77.67	OK	7574	2026-09-15 16:48	76.60	OK
7575	2026-09-15 16:49	79.58	OK	7576	2026-09-15 16:50	76.86	OK
7577	2026-09-15 16:51	76.99	OK	7578	2026-09-15 16:52	78.92	OK
7579	2026-09-15 16:53	78.16	OK	7580	2026-09-15 16:54	78.78	OK
7581	2026-09-15 16:55	77.22	OK	7582	2026-09-15 16:56	78.39	OK
7583	2026-09-15 16:57	80.43	OK	7584	2026-09-15 16:58	79.10	OK
7585	2026-09-15 16:59	78.81	OK	7586	2026-09-15 17:00	79.10	OK
7587	2026-09-15 17:01	78.36	OK	7588	2026-09-15 17:02	79.22	OK
7589	2026-09-15 17:03	78.49	OK	7590	2026-09-15 17:04	78.25	OK
7591	2026-09-15 17:05	77.80	OK	7592	2026-09-15 17:06	79.18	OK
7593	2026-09-15 17:07	76.22	OK	7594	2026-09-15 17:08	80.02	OK
7595	2026-09-15 17:09	79.88	OK	7596	2026-09-15 17:10	76.78	OK
7597	2026-09-15 17:11	76.77	OK	7598	2026-09-15 17:12	75.83	OK
7599	2026-09-15 17:13	77.67	OK	7600	2026-09-15 17:14	79.29	OK
7601	2026-09-15 17:15	75.15	OK	7602	2026-09-15 17:16	75.97	OK
7603	2026-09-15 17:17	78.05	OK	7604	2026-09-15 17:18	80.10	OK
7605	2026-09-15 17:19	76.65	OK	7606	2026-09-15 17:20	74.40	OK
7607	2026-09-15 17:21	74.78	OK	7608	2026-09-15 17:22	78.08	OK
7609	2026-09-15 17:23	76.44	OK	7610	2026-09-15 17:24	76.75	OK
7611	2026-09-15 17:25	76.65	OK	7612	2026-09-15 17:26	76.62	OK
7613	2026-09-15 17:27	76.51	OK	7614	2026-09-15 17:28	79.42	OK
7615	2026-09-15 17:29	76.43	OK	7616	2026-09-15 17:30	78.39	OK
7617	2026-09-15 17:31	78.50	OK	7618	2026-09-15 17:32	76.41	OK
7619	2026-09-15 17:33	75.28	OK	7620	2026-09-15 17:34	77.79	OK
7621	2026-09-15 17:35	79.15	OK	7622	2026-09-15 17:36	77.06	OK
7623	2026-09-15 17:37	76.20	OK	7624	2026-09-15 17:38	79.39	OK
7625	2026-09-15 17:39	75.53	OK	7626	2026-09-15 17:40	74.88	OK
7627	2026-09-15 17:41	76.93	OK	7628	2026-09-15 17:42	78.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7629	2026-09-15 17:43	77.92	OK	7630	2026-09-15 17:44	75.81	OK
7631	2026-09-15 17:45	77.36	OK	7632	2026-09-15 17:46	76.71	OK
7633	2026-09-15 17:47	79.08	OK	7634	2026-09-15 17:48	77.10	OK
7635	2026-09-15 17:49	76.26	OK	7636	2026-09-15 17:50	77.52	OK
7637	2026-09-15 17:51	78.76	OK	7638	2026-09-15 17:52	78.77	OK
7639	2026-09-15 17:53	76.60	OK	7640	2026-09-15 17:54	74.47	OK
7641	2026-09-15 17:55	77.54	OK	7642	2026-09-15 17:56	76.49	OK
7643	2026-09-15 17:57	75.61	OK	7644	2026-09-15 17:58	77.01	OK
7645	2026-09-15 17:59	75.48	OK	7646	2026-09-15 18:00	76.80	OK
7647	2026-09-15 18:01	76.45	OK	7648	2026-09-15 18:02	76.71	OK
7649	2026-09-15 18:03	79.46	OK	7650	2026-09-15 18:04	76.97	OK
7651	2026-09-15 18:05	74.07	OK	7652	2026-09-15 18:06	75.02	OK
7653	2026-09-15 18:07	77.47	OK	7654	2026-09-15 18:08	74.20	OK
7655	2026-09-15 18:09	75.51	OK	7656	2026-09-15 18:10	74.02	OK
7657	2026-09-15 18:11	76.90	OK	7658	2026-09-15 18:12	76.08	OK
7659	2026-09-15 18:13	77.39	OK	7660	2026-09-15 18:14	76.51	OK
7661	2026-09-15 18:15	76.78	OK	7662	2026-09-15 18:16	74.67	OK
7663	2026-09-15 18:17	77.93	OK	7664	2026-09-15 18:18	79.82	OK
7665	2026-09-15 18:19	74.67	OK	7666	2026-09-15 18:20	74.25	OK
7667	2026-09-15 18:21	75.83	OK	7668	2026-09-15 18:22	75.43	OK
7669	2026-09-15 18:23	77.26	OK	7670	2026-09-15 18:24	74.99	OK
7671	2026-09-15 18:25	74.35	OK	7672	2026-09-15 18:26	76.36	OK
7673	2026-09-15 18:27	77.27	OK	7674	2026-09-15 18:28	74.73	OK
7675	2026-09-15 18:29	72.10	OK	7676	2026-09-15 18:30	77.69	OK
7677	2026-09-15 18:31	78.58	OK	7678	2026-09-15 18:32	77.53	OK
7679	2026-09-15 18:33	76.51	OK	7680	2026-09-15 18:34	74.99	OK
7681	2026-09-15 18:35	76.97	OK	7682	2026-09-15 18:36	77.47	OK
7683	2026-09-15 18:37	75.82	OK	7684	2026-09-15 18:38	74.33	OK
7685	2026-09-15 18:39	76.28	OK	7686	2026-09-15 18:40	73.87	OK
7687	2026-09-15 18:41	74.76	OK	7688	2026-09-15 18:42	76.98	OK
7689	2026-09-15 18:43	73.56	OK	7690	2026-09-15 18:44	76.02	OK
7691	2026-09-15 18:45	77.00	OK	7692	2026-09-15 18:46	75.00	OK
7693	2026-09-15 18:47	75.16	OK	7694	2026-09-15 18:48	74.64	OK
7695	2026-09-15 18:49	75.85	OK	7696	2026-09-15 18:50	75.49	OK
7697	2026-09-15 18:51	74.93	OK	7698	2026-09-15 18:52	74.43	OK
7699	2026-09-15 18:53	77.02	OK	7700	2026-09-15 18:54	77.66	OK
7701	2026-09-15 18:55	73.13	OK	7702	2026-09-15 18:56	75.81	OK
7703	2026-09-15 18:57	74.41	OK	7704	2026-09-15 18:58	73.12	OK
7705	2026-09-15 18:59	74.12	OK	7706	2026-09-15 19:00	74.80	OK
7707	2026-09-15 19:01	75.70	OK	7708	2026-09-15 19:02	73.12	OK
7709	2026-09-15 19:03	76.36	OK	7710	2026-09-15 19:04	76.42	OK
7711	2026-09-15 19:05	74.03	OK	7712	2026-09-15 19:06	71.42	OK
7713	2026-09-15 19:07	77.58	OK	7714	2026-09-15 19:08	73.81	OK
7715	2026-09-15 19:09	75.15	OK	7716	2026-09-15 19:10	72.76	OK
7717	2026-09-15 19:11	71.64	OK	7718	2026-09-15 19:12	74.18	OK
7719	2026-09-15 19:13	74.09	OK	7720	2026-09-15 19:14	74.63	OK
7721	2026-09-15 19:15	76.60	OK	7722	2026-09-15 19:16	76.55	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7723	2026-09-15 19:17	73.89	OK	7724	2026-09-15 19:18	74.61	OK
7725	2026-09-15 19:19	74.84	OK	7726	2026-09-15 19:20	72.40	OK
7727	2026-09-15 19:21	75.36	OK	7728	2026-09-15 19:22	74.32	OK
7729	2026-09-15 19:23	76.24	OK	7730	2026-09-15 19:24	72.09	OK
7731	2026-09-15 19:25	75.80	OK	7732	2026-09-15 19:26	71.28	OK
7733	2026-09-15 19:27	73.81	OK	7734	2026-09-15 19:28	73.54	OK
7735	2026-09-15 19:29	72.87	OK	7736	2026-09-15 19:30	76.62	OK
7737	2026-09-15 19:31	75.52	OK	7738	2026-09-15 19:32	75.96	OK
7739	2026-09-15 19:33	73.66	OK	7740	2026-09-15 19:34	75.28	OK
7741	2026-09-15 19:35	73.18	OK	7742	2026-09-15 19:36	74.70	OK
7743	2026-09-15 19:37	77.58	OK	7744	2026-09-15 19:38	74.39	OK
7745	2026-09-15 19:39	77.99	OK	7746	2026-09-15 19:40	72.63	OK
7747	2026-09-15 19:41	76.00	OK	7748	2026-09-15 19:42	75.92	OK
7749	2026-09-15 19:43	73.90	OK	7750	2026-09-15 19:44	69.93	OK
7751	2026-09-15 19:45	72.53	OK	7752	2026-09-15 19:46	74.13	OK
7753	2026-09-15 19:47	72.56	OK	7754	2026-09-15 19:48	74.43	OK
7755	2026-09-15 19:49	75.30	OK	7756	2026-09-15 19:50	74.88	OK
7757	2026-09-15 19:51	70.67	OK	7758	2026-09-15 19:52	75.85	OK
7759	2026-09-15 19:53	73.60	OK	7760	2026-09-15 19:54	74.78	OK
7761	2026-09-15 19:55	74.13	OK	7762	2026-09-15 19:56	73.82	OK
7763	2026-09-15 19:57	72.44	OK	7764	2026-09-15 19:58	72.80	OK
7765	2026-09-15 19:59	75.36	OK	7766	2026-09-15 20:00	74.47	OK
7767	2026-09-15 20:01	74.79	OK	7768	2026-09-15 20:02	71.76	OK
7769	2026-09-15 20:03	73.41	OK	7770	2026-09-15 20:04	72.16	OK
7771	2026-09-15 20:05	74.44	OK	7772	2026-09-15 20:06	75.04	OK
7773	2026-09-15 20:07	74.53	OK	7774	2026-09-15 20:08	73.78	OK
7775	2026-09-15 20:09	71.41	OK	7776	2026-09-15 20:10	72.43	OK
7777	2026-09-15 20:11	73.57	OK	7778	2026-09-15 20:12	73.17	OK
7779	2026-09-15 20:13	72.65	OK	7780	2026-09-15 20:14	75.97	OK
7781	2026-09-15 20:15	73.68	OK	7782	2026-09-15 20:16	75.16	OK
7783	2026-09-15 20:17	77.00	OK	7784	2026-09-15 20:18	71.56	OK
7785	2026-09-15 20:19	71.05	OK	7786	2026-09-15 20:20	76.52	OK
7787	2026-09-15 20:21	74.36	OK	7788	2026-09-15 20:22	73.53	OK
7789	2026-09-15 20:23	73.76	OK	7790	2026-09-15 20:24	76.66	OK
7791	2026-09-15 20:25	70.31	OK	7792	2026-09-15 20:26	72.13	OK
7793	2026-09-15 20:27	74.18	OK	7794	2026-09-15 20:28	75.08	OK
7795	2026-09-15 20:29	76.65	OK	7796	2026-09-15 20:30	70.94	OK
7797	2026-09-15 20:31	70.96	OK	7798	2026-09-15 20:32	71.33	OK
7799	2026-09-15 20:33	74.02	OK	7800	2026-09-15 20:34	72.87	OK
7801	2026-09-15 20:35	72.22	OK	7802	2026-09-15 20:36	70.54	OK
7803	2026-09-15 20:37	73.06	OK	7804	2026-09-15 20:38	75.63	OK
7805	2026-09-15 20:39	71.74	OK	7806	2026-09-15 20:40	70.74	OK
7807	2026-09-15 20:41	68.51	OK	7808	2026-09-15 20:42	72.69	OK
7809	2026-09-15 20:43	71.38	OK	7810	2026-09-15 20:44	74.83	OK
7811	2026-09-15 20:45	75.69	OK	7812	2026-09-15 20:46	69.34	OK
7813	2026-09-15 20:47	74.04	OK	7814	2026-09-15 20:48	71.02	OK
7815	2026-09-15 20:49	70.59	OK	7816	2026-09-15 20:50	69.68	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7817	2026-09-15 20:51	69.72	OK	7818	2026-09-15 20:52	74.09	OK
7819	2026-09-15 20:53	73.54	OK	7820	2026-09-15 20:54	70.31	OK
7821	2026-09-15 20:55	71.41	OK	7822	2026-09-15 20:56	73.66	OK
7823	2026-09-15 20:57	73.97	OK	7824	2026-09-15 20:58	71.57	OK
7825	2026-09-15 20:59	71.41	OK	7826	2026-09-15 21:00	73.66	OK
7827	2026-09-15 21:01	71.29	OK	7828	2026-09-15 21:02	72.95	OK
7829	2026-09-15 21:03	73.15	OK	7830	2026-09-15 21:04	71.02	OK
7831	2026-09-15 21:05	71.56	OK	7832	2026-09-15 21:06	73.84	OK
7833	2026-09-15 21:07	75.07	OK	7834	2026-09-15 21:08	70.36	OK
7835	2026-09-15 21:09	73.52	OK	7836	2026-09-15 21:10	68.21	OK
7837	2026-09-15 21:11	73.55	OK	7838	2026-09-15 21:12	71.32	OK
7839	2026-09-15 21:13	70.42	OK	7840	2026-09-15 21:14	70.64	OK
7841	2026-09-15 21:15	73.37	OK	7842	2026-09-15 21:16	70.98	OK
7843	2026-09-15 21:17	72.85	OK	7844	2026-09-15 21:18	69.83	OK
7845	2026-09-15 21:19	70.97	OK	7846	2026-09-15 21:20	70.13	OK
7847	2026-09-15 21:21	71.71	OK	7848	2026-09-15 21:22	71.18	OK
7849	2026-09-15 21:23	72.95	OK	7850	2026-09-15 21:24	71.51	OK
7851	2026-09-15 21:25	69.87	OK	7852	2026-09-15 21:26	72.89	OK
7853	2026-09-15 21:27	74.80	OK	7854	2026-09-15 21:28	70.93	OK
7855	2026-09-15 21:29	71.35	OK	7856	2026-09-15 21:30	69.24	OK
7857	2026-09-15 21:31	72.70	OK	7858	2026-09-15 21:32	71.24	OK
7859	2026-09-15 21:33	72.94	OK	7860	2026-09-15 21:34	72.70	OK
7861	2026-09-15 21:35	70.89	OK	7862	2026-09-15 21:36	72.65	OK
7863	2026-09-15 21:37	68.42	OK	7864	2026-09-15 21:38	69.96	OK
7865	2026-09-15 21:39	74.96	OK	7866	2026-09-15 21:40	71.89	OK
7867	2026-09-15 21:41	71.89	OK	7868	2026-09-15 21:42	72.91	OK
7869	2026-09-15 21:43	72.36	OK	7870	2026-09-15 21:44	72.85	OK
7871	2026-09-15 21:45	74.48	OK	7872	2026-09-15 21:46	69.51	OK
7873	2026-09-15 21:47	70.01	OK	7874	2026-09-15 21:48	72.54	OK
7875	2026-09-15 21:49	70.98	OK	7876	2026-09-15 21:50	74.06	OK
7877	2026-09-15 21:51	69.83	OK	7878	2026-09-15 21:52	72.98	OK
7879	2026-09-15 21:53	70.33	OK	7880	2026-09-15 21:54	69.76	OK
7881	2026-09-15 21:55	67.44	OK	7882	2026-09-15 21:56	68.24	OK
7883	2026-09-15 21:57	70.23	OK	7884	2026-09-15 21:58	71.18	OK
7885	2026-09-15 21:59	69.96	OK	7886	2026-09-15 22:00	71.64	OK
7887	2026-09-15 22:01	70.80	OK	7888	2026-09-15 22:02	74.95	OK
7889	2026-09-15 22:03	72.48	OK	7890	2026-09-15 22:04	70.49	OK
7891	2026-09-15 22:05	67.40	OK	7892	2026-09-15 22:06	73.69	OK
7893	2026-09-15 22:07	70.35	OK	7894	2026-09-15 22:08	70.71	OK
7895	2026-09-15 22:09	68.44	OK	7896	2026-09-15 22:10	73.64	OK
7897	2026-09-15 22:11	67.82	OK	7898	2026-09-15 22:12	71.09	OK
7899	2026-09-15 22:13	71.22	OK	7900	2026-09-15 22:14	71.89	OK
7901	2026-09-15 22:15	71.77	OK	7902	2026-09-15 22:16	72.61	OK
7903	2026-09-15 22:17	69.85	OK	7904	2026-09-15 22:18	72.90	OK
7905	2026-09-15 22:19	69.12	OK	7906	2026-09-15 22:20	71.30	OK
7907	2026-09-15 22:21	72.55	OK	7908	2026-09-15 22:22	68.32	OK
7909	2026-09-15 22:23	72.58	OK	7910	2026-09-15 22:24	69.93	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7911	2026-09-15 22:25	71.33	OK	7912	2026-09-15 22:26	69.49	OK
7913	2026-09-15 22:27	71.98	OK	7914	2026-09-15 22:28	69.43	OK
7915	2026-09-15 22:29	71.95	OK	7916	2026-09-15 22:30	70.77	OK
7917	2026-09-15 22:31	70.89	OK	7918	2026-09-15 22:32	70.15	OK
7919	2026-09-15 22:33	70.99	OK	7920	2026-09-15 22:34	70.53	OK
7921	2026-09-15 22:35	69.83	OK	7922	2026-09-15 22:36	71.48	OK
7923	2026-09-15 22:37	70.44	OK	7924	2026-09-15 22:38	69.27	OK
7925	2026-09-15 22:39	69.48	OK	7926	2026-09-15 22:40	69.58	OK
7927	2026-09-15 22:41	72.63	OK	7928	2026-09-15 22:42	72.78	OK
7929	2026-09-15 22:43	69.77	OK	7930	2026-09-15 22:44	69.95	OK
7931	2026-09-15 22:45	67.31	OK	7932	2026-09-15 22:46	69.58	OK
7933	2026-09-15 22:47	72.48	OK	7934	2026-09-15 22:48	68.11	OK
7935	2026-09-15 22:49	71.04	OK	7936	2026-09-15 22:50	72.07	OK
7937	2026-09-15 22:51	69.15	OK	7938	2026-09-15 22:52	69.19	OK
7939	2026-09-15 22:53	69.67	OK	7940	2026-09-15 22:54	68.45	OK
7941	2026-09-15 22:55	68.13	OK	7942	2026-09-15 22:56	72.11	OK
7943	2026-09-15 22:57	71.34	OK	7944	2026-09-15 22:58	72.20	OK
7945	2026-09-15 22:59	70.30	OK	7946	2026-09-15 23:00	71.92	OK
7947	2026-09-15 23:01	70.81	OK	7948	2026-09-15 23:02	67.80	OK
7949	2026-09-15 23:03	70.71	OK	7950	2026-09-15 23:04	69.82	OK
7951	2026-09-15 23:05	70.96	OK	7952	2026-09-15 23:06	70.82	OK
7953	2026-09-15 23:07	70.18	OK	7954	2026-09-15 23:08	70.78	OK
7955	2026-09-15 23:09	73.68	OK	7956	2026-09-15 23:10	73.14	OK
7957	2026-09-15 23:11	72.93	OK	7958	2026-09-15 23:12	65.81	OK
7959	2026-09-15 23:13	68.10	OK	7960	2026-09-15 23:14	69.59	OK
7961	2026-09-15 23:15	71.64	OK	7962	2026-09-15 23:16	70.86	OK
7963	2026-09-15 23:17	71.23	OK	7964	2026-09-15 23:18	68.74	OK
7965	2026-09-15 23:19	71.35	OK	7966	2026-09-15 23:20	68.36	OK
7967	2026-09-15 23:21	70.63	OK	7968	2026-09-15 23:22	70.46	OK
7969	2026-09-15 23:23	70.02	OK	7970	2026-09-15 23:24	67.96	OK
7971	2026-09-15 23:25	70.12	OK	7972	2026-09-15 23:26	67.06	OK
7973	2026-09-15 23:27	69.44	OK	7974	2026-09-15 23:28	70.69	OK
7975	2026-09-15 23:29	68.98	OK	7976	2026-09-15 23:30	70.40	OK
7977	2026-09-15 23:31	72.71	OK	7978	2026-09-15 23:32	68.55	OK
7979	2026-09-15 23:33	72.40	OK	7980	2026-09-15 23:34	68.08	OK
7981	2026-09-15 23:35	74.25	OK	7982	2026-09-15 23:36	69.32	OK
7983	2026-09-15 23:37	69.03	OK	7984	2026-09-15 23:38	67.62	OK
7985	2026-09-15 23:39	70.16	OK	7986	2026-09-15 23:40	67.02	OK
7987	2026-09-15 23:41	71.15	OK	7988	2026-09-15 23:42	72.02	OK
7989	2026-09-15 23:43	68.80	OK	7990	2026-09-15 23:44	70.64	OK
7991	2026-09-15 23:45	71.65	OK	7992	2026-09-15 23:46	70.03	OK
7993	2026-09-15 23:47	68.57	OK	7994	2026-09-15 23:48	69.29	OK
7995	2026-09-15 23:49	69.21	OK	7996	2026-09-15 23:50	71.03	OK
7997	2026-09-15 23:51	68.16	OK	7998	2026-09-15 23:52	71.76	OK
7999	2026-09-15 23:53	70.00	OK	8000	2026-09-15 23:54	71.19	OK
8001	2026-09-15 23:55	69.89	OK	8002	2026-09-15 23:56	70.37	OK
8003	2026-09-15 23:57	68.85	OK	8004	2026-09-15 23:58	71.75	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8005	2026-09-15 23:59	68.51	OK	8006	2026-09-16 00:00	69.37	OK
8007	2026-09-16 00:01	71.04	OK	8008	2026-09-16 00:02	72.42	OK
8009	2026-09-16 00:03	69.52	OK	8010	2026-09-16 00:04	68.61	OK
8011	2026-09-16 00:05	70.13	OK	8012	2026-09-16 00:06	71.51	OK
8013	2026-09-16 00:07	68.04	OK	8014	2026-09-16 00:08	66.46	OK
8015	2026-09-16 00:09	68.42	OK	8016	2026-09-16 00:10	69.65	OK
8017	2026-09-16 00:11	69.41	OK	8018	2026-09-16 00:12	72.16	OK
8019	2026-09-16 00:13	70.94	OK	8020	2026-09-16 00:14	69.17	OK
8021	2026-09-16 00:15	71.17	OK	8022	2026-09-16 00:16	68.76	OK
8023	2026-09-16 00:17	70.33	OK	8024	2026-09-16 00:18	69.69	OK
8025	2026-09-16 00:19	70.30	OK	8026	2026-09-16 00:20	69.55	OK
8027	2026-09-16 00:21	70.64	OK	8028	2026-09-16 00:22	70.03	OK
8029	2026-09-16 00:23	68.97	OK	8030	2026-09-16 00:24	69.60	OK
8031	2026-09-16 00:25	70.55	OK	8032	2026-09-16 00:26	70.32	OK
8033	2026-09-16 00:27	69.51	OK	8034	2026-09-16 00:28	67.98	OK
8035	2026-09-16 00:29	68.42	OK	8036	2026-09-16 00:30	69.05	OK
8037	2026-09-16 00:31	70.66	OK	8038	2026-09-16 00:32	69.22	OK
8039	2026-09-16 00:33	69.94	OK	8040	2026-09-16 00:34	71.13	OK
8041	2026-09-16 00:35	70.64	OK	8042	2026-09-16 00:36	71.13	OK
8043	2026-09-16 00:37	69.57	OK	8044	2026-09-16 00:38	71.54	OK
8045	2026-09-16 00:39	72.00	OK	8046	2026-09-16 00:40	70.86	OK
8047	2026-09-16 00:41	71.27	OK	8048	2026-09-16 00:42	67.33	OK
8049	2026-09-16 00:43	67.87	OK	8050	2026-09-16 00:44	68.24	OK
8051	2026-09-16 00:45	69.71	OK	8052	2026-09-16 00:46	69.07	OK
8053	2026-09-16 00:47	71.91	OK	8054	2026-09-16 00:48	68.74	OK
8055	2026-09-16 00:49	66.57	OK	8056	2026-09-16 00:50	69.26	OK
8057	2026-09-16 00:51	68.34	OK	8058	2026-09-16 00:52	68.86	OK
8059	2026-09-16 00:53	68.66	OK	8060	2026-09-16 00:54	71.62	OK
8061	2026-09-16 00:55	66.78	OK	8062	2026-09-16 00:56	68.82	OK
8063	2026-09-16 00:57	66.56	OK	8064	2026-09-16 00:58	72.80	OK
8065	2026-09-16 00:59	68.84	OK	8066	2026-09-16 01:00	68.31	OK
8067	2026-09-16 01:01	67.21	OK	8068	2026-09-16 01:02	68.14	OK
8069	2026-09-16 01:03	71.44	OK	8070	2026-09-16 01:04	67.70	OK
8071	2026-09-16 01:05	69.18	OK	8072	2026-09-16 01:06	67.62	OK
8073	2026-09-16 01:07	68.39	OK	8074	2026-09-16 01:08	67.25	OK
8075	2026-09-16 01:09	72.26	OK	8076	2026-09-16 01:10	68.48	OK
8077	2026-09-16 01:11	71.35	OK	8078	2026-09-16 01:12	69.29	OK
8079	2026-09-16 01:13	69.93	OK	8080	2026-09-16 01:14	66.66	OK
8081	2026-09-16 01:15	70.12	OK	8082	2026-09-16 01:16	69.98	OK
8083	2026-09-16 01:17	69.70	OK	8084	2026-09-16 01:18	68.33	OK
8085	2026-09-16 01:19	72.49	OK	8086	2026-09-16 01:20	70.99	OK
8087	2026-09-16 01:21	70.83	OK	8088	2026-09-16 01:22	71.22	OK
8089	2026-09-16 01:23	68.02	OK	8090	2026-09-16 01:24	70.60	OK
8091	2026-09-16 01:25	69.40	OK	8092	2026-09-16 01:26	70.85	OK
8093	2026-09-16 01:27	71.41	OK	8094	2026-09-16 01:28	70.21	OK
8095	2026-09-16 01:29	66.80	OK	8096	2026-09-16 01:30	69.72	OK
8097	2026-09-16 01:31	70.45	OK	8098	2026-09-16 01:32	72.13	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8099	2026-09-16 01:33	70.31	OK	8100	2026-09-16 01:34	71.82	OK
8101	2026-09-16 01:35	66.85	OK	8102	2026-09-16 01:36	65.36	OK
8103	2026-09-16 01:37	69.24	OK	8104	2026-09-16 01:38	68.59	OK
8105	2026-09-16 01:39	72.02	OK	8106	2026-09-16 01:40	67.70	OK
8107	2026-09-16 01:41	73.99	OK	8108	2026-09-16 01:42	64.87	OK
8109	2026-09-16 01:43	67.29	OK	8110	2026-09-16 01:44	73.67	OK
8111	2026-09-16 01:45	70.03	OK	8112	2026-09-16 01:46	68.80	OK
8113	2026-09-16 01:47	68.46	OK	8114	2026-09-16 01:48	70.97	OK
8115	2026-09-16 01:49	68.30	OK	8116	2026-09-16 01:50	70.49	OK
8117	2026-09-16 01:51	69.30	OK	8118	2026-09-16 01:52	70.87	OK
8119	2026-09-16 01:53	68.79	OK	8120	2026-09-16 01:54	70.90	OK
8121	2026-09-16 01:55	70.71	OK	8122	2026-09-16 01:56	68.94	OK
8123	2026-09-16 01:57	70.73	OK	8124	2026-09-16 01:58	69.93	OK
8125	2026-09-16 01:59	71.79	OK	8126	2026-09-16 02:00	71.08	OK
8127	2026-09-16 02:01	69.21	OK	8128	2026-09-16 02:02	68.63	OK
8129	2026-09-16 02:03	70.32	OK	8130	2026-09-16 02:04	73.46	OK
8131	2026-09-16 02:05	69.44	OK	8132	2026-09-16 02:06	69.63	OK
8133	2026-09-16 02:07	69.68	OK	8134	2026-09-16 02:08	71.49	OK
8135	2026-09-16 02:09	71.71	OK	8136	2026-09-16 02:10	73.11	OK
8137	2026-09-16 02:11	66.43	OK	8138	2026-09-16 02:12	69.66	OK
8139	2026-09-16 02:13	71.14	OK	8140	2026-09-16 02:14	68.64	OK
8141	2026-09-16 02:15	67.36	OK	8142	2026-09-16 02:16	71.04	OK
8143	2026-09-16 02:17	72.10	OK	8144	2026-09-16 02:18	71.17	OK
8145	2026-09-16 02:19	68.99	OK	8146	2026-09-16 02:20	70.57	OK
8147	2026-09-16 02:21	69.87	OK	8148	2026-09-16 02:22	72.09	OK
8149	2026-09-16 02:23	70.56	OK	8150	2026-09-16 02:24	68.18	OK
8151	2026-09-16 02:25	72.62	OK	8152	2026-09-16 02:26	69.13	OK
8153	2026-09-16 02:27	69.11	OK	8154	2026-09-16 02:28	71.71	OK
8155	2026-09-16 02:29	72.54	OK	8156	2026-09-16 02:30	68.64	OK
8157	2026-09-16 02:31	69.89	OK	8158	2026-09-16 02:32	68.76	OK
8159	2026-09-16 02:33	71.16	OK	8160	2026-09-16 02:34	68.10	OK
8161	2026-09-16 02:35	71.99	OK	8162	2026-09-16 02:36	68.77	OK
8163	2026-09-16 02:37	69.59	OK	8164	2026-09-16 02:38	68.67	OK
8165	2026-09-16 02:39	69.57	OK	8166	2026-09-16 02:40	69.58	OK
8167	2026-09-16 02:41	69.06	OK	8168	2026-09-16 02:42	68.36	OK
8169	2026-09-16 02:43	72.90	OK	8170	2026-09-16 02:44	72.85	OK
8171	2026-09-16 02:45	68.64	OK	8172	2026-09-16 02:46	71.05	OK
8173	2026-09-16 02:47	70.70	OK	8174	2026-09-16 02:48	66.34	OK
8175	2026-09-16 02:49	71.76	OK	8176	2026-09-16 02:50	70.38	OK
8177	2026-09-16 02:51	70.46	OK	8178	2026-09-16 02:52	70.95	OK
8179	2026-09-16 02:53	71.93	OK	8180	2026-09-16 02:54	71.24	OK
8181	2026-09-16 02:55	70.94	OK	8182	2026-09-16 02:56	67.98	OK
8183	2026-09-16 02:57	71.11	OK	8184	2026-09-16 02:58	69.32	OK
8185	2026-09-16 02:59	69.86	OK	8186	2026-09-16 03:00	72.17	OK
8187	2026-09-16 03:01	66.92	OK	8188	2026-09-16 03:02	71.85	OK
8189	2026-09-16 03:03	67.87	OK	8190	2026-09-16 03:04	73.46	OK
8191	2026-09-16 03:05	72.53	OK	8192	2026-09-16 03:06	69.13	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8193	2026-09-16 03:07	71.86	OK	8194	2026-09-16 03:08	71.54	OK
8195	2026-09-16 03:09	67.40	OK	8196	2026-09-16 03:10	71.25	OK
8197	2026-09-16 03:11	73.30	OK	8198	2026-09-16 03:12	68.87	OK
8199	2026-09-16 03:13	69.65	OK	8200	2026-09-16 03:14	66.20	OK
8201	2026-09-16 03:15	71.66	OK	8202	2026-09-16 03:16	70.58	OK
8203	2026-09-16 03:17	69.63	OK	8204	2026-09-16 03:18	69.31	OK
8205	2026-09-16 03:19	70.80	OK	8206	2026-09-16 03:20	68.40	OK
8207	2026-09-16 03:21	67.72	OK	8208	2026-09-16 03:22	69.07	OK
8209	2026-09-16 03:23	70.73	OK	8210	2026-09-16 03:24	68.04	OK
8211	2026-09-16 03:25	67.87	OK	8212	2026-09-16 03:26	71.18	OK
8213	2026-09-16 03:27	69.83	OK	8214	2026-09-16 03:28	72.54	OK
8215	2026-09-16 03:29	73.80	OK	8216	2026-09-16 03:30	69.17	OK
8217	2026-09-16 03:31	69.35	OK	8218	2026-09-16 03:32	69.17	OK
8219	2026-09-16 03:33	70.03	OK	8220	2026-09-16 03:34	70.88	OK
8221	2026-09-16 03:35	71.66	OK	8222	2026-09-16 03:36	68.88	OK
8223	2026-09-16 03:37	71.02	OK	8224	2026-09-16 03:38	71.58	OK
8225	2026-09-16 03:39	68.94	OK	8226	2026-09-16 03:40	72.78	OK
8227	2026-09-16 03:41	70.05	OK	8228	2026-09-16 03:42	71.96	OK
8229	2026-09-16 03:43	71.61	OK	8230	2026-09-16 03:44	69.16	OK
8231	2026-09-16 03:45	72.08	OK	8232	2026-09-16 03:46	68.71	OK
8233	2026-09-16 03:47	71.49	OK	8234	2026-09-16 03:48	74.22	OK
8235	2026-09-16 03:49	72.49	OK	8236	2026-09-16 03:50	69.74	OK
8237	2026-09-16 03:51	72.26	OK	8238	2026-09-16 03:52	71.12	OK
8239	2026-09-16 03:53	73.23	OK	8240	2026-09-16 03:54	73.08	OK
8241	2026-09-16 03:55	69.94	OK	8242	2026-09-16 03:56	69.83	OK
8243	2026-09-16 03:57	70.99	OK	8244	2026-09-16 03:58	71.89	OK
8245	2026-09-16 03:59	69.25	OK	8246	2026-09-16 04:00	71.48	OK
8247	2026-09-16 04:01	69.96	OK	8248	2026-09-16 04:02	70.11	OK
8249	2026-09-16 04:03	70.52	OK	8250	2026-09-16 04:04	71.84	OK
8251	2026-09-16 04:05	69.09	OK	8252	2026-09-16 04:06	69.09	OK
8253	2026-09-16 04:07	72.62	OK	8254	2026-09-16 04:08	72.54	OK
8255	2026-09-16 04:09	70.76	OK	8256	2026-09-16 04:10	73.52	OK
8257	2026-09-16 04:11	71.88	OK	8258	2026-09-16 04:12	71.93	OK
8259	2026-09-16 04:13	72.28	OK	8260	2026-09-16 04:14	74.01	OK
8261	2026-09-16 04:15	72.87	OK	8262	2026-09-16 04:16	73.08	OK
8263	2026-09-16 04:17	71.94	OK	8264	2026-09-16 04:18	72.33	OK
8265	2026-09-16 04:19	72.37	OK	8266	2026-09-16 04:20	69.03	OK
8267	2026-09-16 04:21	69.07	OK	8268	2026-09-16 04:22	71.93	OK
8269	2026-09-16 04:23	73.85	OK	8270	2026-09-16 04:24	68.72	OK
8271	2026-09-16 04:25	69.62	OK	8272	2026-09-16 04:26	70.23	OK
8273	2026-09-16 04:27	72.80	OK	8274	2026-09-16 04:28	71.93	OK
8275	2026-09-16 04:29	72.35	OK	8276	2026-09-16 04:30	73.02	OK
8277	2026-09-16 04:31	72.97	OK	8278	2026-09-16 04:32	71.39	OK
8279	2026-09-16 04:33	69.86	OK	8280	2026-09-16 04:34	73.16	OK
8281	2026-09-16 04:35	72.73	OK	8282	2026-09-16 04:36	70.73	OK
8283	2026-09-16 04:37	72.19	OK	8284	2026-09-16 04:38	69.82	OK
8285	2026-09-16 04:39	70.57	OK	8286	2026-09-16 04:40	71.87	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8287	2026-09-16 04:41	75.07	OK	8288	2026-09-16 04:42	70.54	OK
8289	2026-09-16 04:43	70.19	OK	8290	2026-09-16 04:44	71.97	OK
8291	2026-09-16 04:45	69.94	OK	8292	2026-09-16 04:46	73.45	OK
8293	2026-09-16 04:47	75.54	OK	8294	2026-09-16 04:48	70.72	OK
8295	2026-09-16 04:49	72.75	OK	8296	2026-09-16 04:50	75.11	OK
8297	2026-09-16 04:51	69.32	OK	8298	2026-09-16 04:52	72.77	OK
8299	2026-09-16 04:53	70.82	OK	8300	2026-09-16 04:54	72.38	OK
8301	2026-09-16 04:55	73.37	OK	8302	2026-09-16 04:56	74.08	OK
8303	2026-09-16 04:57	72.69	OK	8304	2026-09-16 04:58	71.79	OK
8305	2026-09-16 04:59	70.90	OK	8306	2026-09-16 05:00	73.76	OK
8307	2026-09-16 05:01	68.59	OK	8308	2026-09-16 05:02	73.26	OK
8309	2026-09-16 05:03	72.18	OK	8310	2026-09-16 05:04	73.11	OK
8311	2026-09-16 05:05	71.93	OK	8312	2026-09-16 05:06	71.49	OK
8313	2026-09-16 05:07	69.85	OK	8314	2026-09-16 05:08	73.80	OK
8315	2026-09-16 05:09	71.89	OK	8316	2026-09-16 05:10	72.12	OK
8317	2026-09-16 05:11	73.64	OK	8318	2026-09-16 05:12	74.19	OK
8319	2026-09-16 05:13	71.46	OK	8320	2026-09-16 05:14	71.48	OK
8321	2026-09-16 05:15	73.48	OK	8322	2026-09-16 05:16	70.69	OK
8323	2026-09-16 05:17	71.93	OK	8324	2026-09-16 05:18	75.52	OK
8325	2026-09-16 05:19	71.05	OK	8326	2026-09-16 05:20	69.59	OK
8327	2026-09-16 05:21	71.81	OK	8328	2026-09-16 05:22	73.03	OK
8329	2026-09-16 05:23	75.63	OK	8330	2026-09-16 05:24	72.50	OK
8331	2026-09-16 05:25	74.55	OK	8332	2026-09-16 05:26	70.83	OK
8333	2026-09-16 05:27	70.98	OK	8334	2026-09-16 05:28	71.64	OK
8335	2026-09-16 05:29	73.61	OK	8336	2026-09-16 05:30	71.01	OK
8337	2026-09-16 05:31	74.75	OK	8338	2026-09-16 05:32	72.91	OK
8339	2026-09-16 05:33	73.00	OK	8340	2026-09-16 05:34	75.32	OK
8341	2026-09-16 05:35	69.63	OK	8342	2026-09-16 05:36	74.91	OK
8343	2026-09-16 05:37	73.42	OK	8344	2026-09-16 05:38	76.06	OK
8345	2026-09-16 05:39	74.97	OK	8346	2026-09-16 05:40	70.64	OK
8347	2026-09-16 05:41	74.27	OK	8348	2026-09-16 05:42	70.82	OK
8349	2026-09-16 05:43	77.12	OK	8350	2026-09-16 05:44	71.90	OK
8351	2026-09-16 05:45	73.82	OK	8352	2026-09-16 05:46	75.92	OK
8353	2026-09-16 05:47	73.22	OK	8354	2026-09-16 05:48	70.42	OK
8355	2026-09-16 05:49	73.43	OK	8356	2026-09-16 05:50	74.07	OK
8357	2026-09-16 05:51	75.37	OK	8358	2026-09-16 05:52	75.59	OK
8359	2026-09-16 05:53	77.07	OK	8360	2026-09-16 05:54	75.88	OK
8361	2026-09-16 05:55	73.09	OK	8362	2026-09-16 05:56	72.44	OK
8363	2026-09-16 05:57	75.27	OK	8364	2026-09-16 05:58	75.66	OK
8365	2026-09-16 05:59	73.24	OK	8366	2026-09-16 06:00	74.13	OK
8367	2026-09-16 06:01	75.97	OK	8368	2026-09-16 06:02	74.58	OK
8369	2026-09-16 06:03	74.00	OK	8370	2026-09-16 06:04	74.43	OK
8371	2026-09-16 06:05	74.05	OK	8372	2026-09-16 06:06	73.17	OK
8373	2026-09-16 06:07	77.62	OK	8374	2026-09-16 06:08	77.19	OK
8375	2026-09-16 06:09	74.65	OK	8376	2026-09-16 06:10	73.50	OK
8377	2026-09-16 06:11	73.00	OK	8378	2026-09-16 06:12	73.21	OK
8379	2026-09-16 06:13	76.25	OK	8380	2026-09-16 06:14	73.71	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8381	2026-09-16 06:15	76.38	OK	8382	2026-09-16 06:16	72.37	OK
8383	2026-09-16 06:17	71.91	OK	8384	2026-09-16 06:18	70.28	OK
8385	2026-09-16 06:19	75.06	OK	8386	2026-09-16 06:20	75.89	OK
8387	2026-09-16 06:21	71.67	OK	8388	2026-09-16 06:22	74.84	OK
8389	2026-09-16 06:23	75.58	OK	8390	2026-09-16 06:24	76.61	OK
8391	2026-09-16 06:25	74.66	OK	8392	2026-09-16 06:26	72.08	OK
8393	2026-09-16 06:27	74.44	OK	8394	2026-09-16 06:28	75.11	OK
8395	2026-09-16 06:29	76.47	OK	8396	2026-09-16 06:30	77.64	OK
8397	2026-09-16 06:31	72.75	OK	8398	2026-09-16 06:32	76.06	OK
8399	2026-09-16 06:33	74.88	OK	8400	2026-09-16 06:34	75.57	OK
8401	2026-09-16 06:35	75.69	OK	8402	2026-09-16 06:36	75.72	OK
8403	2026-09-16 06:37	75.88	OK	8404	2026-09-16 06:38	78.80	OK
8405	2026-09-16 06:39	75.62	OK	8406	2026-09-16 06:40	74.17	OK
8407	2026-09-16 06:41	76.60	OK	8408	2026-09-16 06:42	75.11	OK
8409	2026-09-16 06:43	73.84	OK	8410	2026-09-16 06:44	75.76	OK
8411	2026-09-16 06:45	76.32	OK	8412	2026-09-16 06:46	71.89	OK
8413	2026-09-16 06:47	74.36	OK	8414	2026-09-16 06:48	74.59	OK
8415	2026-09-16 06:49	73.20	OK	8416	2026-09-16 06:50	74.84	OK
8417	2026-09-16 06:51	77.61	OK	8418	2026-09-16 06:52	77.04	OK
8419	2026-09-16 06:53	74.08	OK	8420	2026-09-16 06:54	77.01	OK
8421	2026-09-16 06:55	74.64	OK	8422	2026-09-16 06:56	71.39	OK
8423	2026-09-16 06:57	74.85	OK	8424	2026-09-16 06:58	75.05	OK
8425	2026-09-16 06:59	77.14	OK	8426	2026-09-16 07:00	72.94	OK
8427	2026-09-16 07:01	73.12	OK	8428	2026-09-16 07:02	74.85	OK
8429	2026-09-16 07:03	77.28	OK	8430	2026-09-16 07:04	74.34	OK
8431	2026-09-16 07:05	74.26	OK	8432	2026-09-16 07:06	76.22	OK
8433	2026-09-16 07:07	75.08	OK	8434	2026-09-16 07:08	77.55	OK
8435	2026-09-16 07:09	77.86	OK	8436	2026-09-16 07:10	75.21	OK
8437	2026-09-16 07:11	76.87	OK	8438	2026-09-16 07:12	75.06	OK
8439	2026-09-16 07:13	76.22	OK	8440	2026-09-16 07:14	77.22	OK
8441	2026-09-16 07:15	76.71	OK	8442	2026-09-16 07:16	76.49	OK
8443	2026-09-16 07:17	74.98	OK	8444	2026-09-16 07:18	73.97	OK
8445	2026-09-16 07:19	74.61	OK	8446	2026-09-16 07:20	76.50	OK
8447	2026-09-16 07:21	72.82	OK	8448	2026-09-16 07:22	73.65	OK
8449	2026-09-16 07:23	74.33	OK	8450	2026-09-16 07:24	75.55	OK
8451	2026-09-16 07:25	75.76	OK	8452	2026-09-16 07:26	76.19	OK
8453	2026-09-16 07:27	77.10	OK	8454	2026-09-16 07:28	75.81	OK
8455	2026-09-16 07:29	77.39	OK	8456	2026-09-16 07:30	75.40	OK
8457	2026-09-16 07:31	74.71	OK	8458	2026-09-16 07:32	75.42	OK
8459	2026-09-16 07:33	78.43	OK	8460	2026-09-16 07:34	77.00	OK
8461	2026-09-16 07:35	78.39	OK	8462	2026-09-16 07:36	74.86	OK
8463	2026-09-16 07:37	75.84	OK	8464	2026-09-16 07:38	75.03	OK
8465	2026-09-16 07:39	74.58	OK	8466	2026-09-16 07:40	76.21	OK
8467	2026-09-16 07:41	76.24	OK	8468	2026-09-16 07:42	74.19	OK
8469	2026-09-16 07:43	74.92	OK	8470	2026-09-16 07:44	72.69	OK
8471	2026-09-16 07:45	75.48	OK	8472	2026-09-16 07:46	76.42	OK
8473	2026-09-16 07:47	77.97	OK	8474	2026-09-16 07:48	75.64	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8475	2026-09-16 07:49	76.92	OK	8476	2026-09-16 07:50	77.01	OK
8477	2026-09-16 07:51	73.31	OK	8478	2026-09-16 07:52	78.27	OK
8479	2026-09-16 07:53	75.76	OK	8480	2026-09-16 07:54	75.73	OK
8481	2026-09-16 07:55	76.37	OK	8482	2026-09-16 07:56	78.29	OK
8483	2026-09-16 07:57	75.20	OK	8484	2026-09-16 07:58	77.88	OK
8485	2026-09-16 07:59	77.17	OK	8486	2026-09-16 08:00	77.76	OK
8487	2026-09-16 08:01	78.75	OK	8488	2026-09-16 08:02	76.71	OK
8489	2026-09-16 08:03	76.48	OK	8490	2026-09-16 08:04	76.43	OK
8491	2026-09-16 08:05	78.76	OK	8492	2026-09-16 08:06	77.76	OK
8493	2026-09-16 08:07	76.18	OK	8494	2026-09-16 08:08	75.69	OK
8495	2026-09-16 08:09	77.65	OK	8496	2026-09-16 08:10	76.62	OK
8497	2026-09-16 08:11	74.53	OK	8498	2026-09-16 08:12	76.26	OK
8499	2026-09-16 08:13	74.64	OK	8500	2026-09-16 08:14	76.31	OK
8501	2026-09-16 08:15	74.33	OK	8502	2026-09-16 08:16	74.07	OK
8503	2026-09-16 08:17	79.74	OK	8504	2026-09-16 08:18	78.90	OK
8505	2026-09-16 08:19	78.10	OK	8506	2026-09-16 08:20	78.64	OK
8507	2026-09-16 08:21	75.89	OK	8508	2026-09-16 08:22	78.88	OK
8509	2026-09-16 08:23	79.79	OK	8510	2026-09-16 08:24	76.39	OK
8511	2026-09-16 08:25	78.70	OK	8512	2026-09-16 08:26	78.47	OK
8513	2026-09-16 08:27	78.46	OK	8514	2026-09-16 08:28	80.49	OK
8515	2026-09-16 08:29	78.50	OK	8516	2026-09-16 08:30	77.16	OK
8517	2026-09-16 08:31	76.72	OK	8518	2026-09-16 08:32	76.72	OK
8519	2026-09-16 08:33	80.65	OK	8520	2026-09-16 08:34	78.18	OK
8521	2026-09-16 08:35	79.26	OK	8522	2026-09-16 08:36	77.01	OK
8523	2026-09-16 08:37	78.45	OK	8524	2026-09-16 08:38	78.69	OK
8525	2026-09-16 08:39	79.73	OK	8526	2026-09-16 08:40	77.77	OK
8527	2026-09-16 08:41	77.70	OK	8528	2026-09-16 08:42	76.21	OK
8529	2026-09-16 08:43	81.25	OK	8530	2026-09-16 08:44	78.31	OK
8531	2026-09-16 08:45	74.79	OK	8532	2026-09-16 08:46	79.03	OK
8533	2026-09-16 08:47	80.69	OK	8534	2026-09-16 08:48	76.67	OK
8535	2026-09-16 08:49	76.34	OK	8536	2026-09-16 08:50	77.72	OK
8537	2026-09-16 08:51	78.21	OK	8538	2026-09-16 08:52	78.51	OK
8539	2026-09-16 08:53	81.32	OK	8540	2026-09-16 08:54	79.98	OK
8541	2026-09-16 08:55	77.00	OK	8542	2026-09-16 08:56	75.15	OK
8543	2026-09-16 08:57	76.74	OK	8544	2026-09-16 08:58	76.27	OK
8545	2026-09-16 08:59	74.45	OK	8546	2026-09-16 09:00	78.54	OK
8547	2026-09-16 09:01	75.13	OK	8548	2026-09-16 09:02	78.39	OK
8549	2026-09-16 09:03	80.43	OK	8550	2026-09-16 09:04	79.59	OK
8551	2026-09-16 09:05	76.32	OK	8552	2026-09-16 09:06	80.01	OK
8553	2026-09-16 09:07	78.60	OK	8554	2026-09-16 09:08	77.18	OK
8555	2026-09-16 09:09	76.60	OK	8556	2026-09-16 09:10	76.53	OK
8557	2026-09-16 09:11	78.41	OK	8558	2026-09-16 09:12	79.12	OK
8559	2026-09-16 09:13	80.66	OK	8560	2026-09-16 09:14	77.71	OK
8561	2026-09-16 09:15	77.58	OK	8562	2026-09-16 09:16	78.77	OK
8563	2026-09-16 09:17	79.34	OK	8564	2026-09-16 09:18	80.14	OK
8565	2026-09-16 09:19	77.15	OK	8566	2026-09-16 09:20	79.01	OK
8567	2026-09-16 09:21	80.05	OK	8568	2026-09-16 09:22	76.42	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8569	2026-09-16 09:23	78.82	OK	8570	2026-09-16 09:24	80.15	OK
8571	2026-09-16 09:25	79.82	OK	8572	2026-09-16 09:26	78.84	OK
8573	2026-09-16 09:27	77.62	OK	8574	2026-09-16 09:28	79.97	OK
8575	2026-09-16 09:29	77.22	OK	8576	2026-09-16 09:30	78.62	OK
8577	2026-09-16 09:31	79.32	OK	8578	2026-09-16 09:32	79.64	OK
8579	2026-09-16 09:33	78.12	OK	8580	2026-09-16 09:34	80.38	OK
8581	2026-09-16 09:35	80.18	OK	8582	2026-09-16 09:36	79.97	OK
8583	2026-09-16 09:37	80.11	OK	8584	2026-09-16 09:38	77.75	OK
8585	2026-09-16 09:39	77.94	OK	8586	2026-09-16 09:40	75.82	OK
8587	2026-09-16 09:41	76.36	OK	8588	2026-09-16 09:42	82.71	OK
8589	2026-09-16 09:43	76.61	OK	8590	2026-09-16 09:44	79.34	OK
8591	2026-09-16 09:45	78.90	OK	8592	2026-09-16 09:46	78.64	OK
8593	2026-09-16 09:47	80.35	OK	8594	2026-09-16 09:48	78.65	OK
8595	2026-09-16 09:49	79.29	OK	8596	2026-09-16 09:50	77.50	OK
8597	2026-09-16 09:51	81.40	OK	8598	2026-09-16 09:52	80.42	OK
8599	2026-09-16 09:53	80.77	OK	8600	2026-09-16 09:54	80.35	OK
8601	2026-09-16 09:55	79.40	OK	8602	2026-09-16 09:56	76.86	OK
8603	2026-09-16 09:57	77.40	OK	8604	2026-09-16 09:58	79.03	OK
8605	2026-09-16 09:59	77.64	OK	8606	2026-09-16 10:00	77.29	OK
8607	2026-09-16 10:01	81.17	OK	8608	2026-09-16 10:02	82.66	OK
8609	2026-09-16 10:03	82.56	OK	8610	2026-09-16 10:04	79.83	OK
8611	2026-09-16 10:05	81.24	OK	8612	2026-09-16 10:06	81.06	OK
8613	2026-09-16 10:07	81.22	OK	8614	2026-09-16 10:08	82.11	OK
8615	2026-09-16 10:09	80.23	OK	8616	2026-09-16 10:10	78.81	OK
8617	2026-09-16 10:11	78.78	OK	8618	2026-09-16 10:12	79.37	OK
8619	2026-09-16 10:13	78.99	OK	8620	2026-09-16 10:14	79.22	OK
8621	2026-09-16 10:15	78.12	OK	8622	2026-09-16 10:16	80.87	OK
8623	2026-09-16 10:17	81.36	OK	8624	2026-09-16 10:18	79.42	OK
8625	2026-09-16 10:19	81.20	OK	8626	2026-09-16 10:20	79.59	OK
8627	2026-09-16 10:21	79.80	OK	8628	2026-09-16 10:22	76.78	OK
8629	2026-09-16 10:23	76.40	OK	8630	2026-09-16 10:24	79.78	OK
8631	2026-09-16 10:25	80.17	OK	8632	2026-09-16 10:26	76.31	OK
8633	2026-09-16 10:27	82.55	OK	8634	2026-09-16 10:28	77.57	OK
8635	2026-09-16 10:29	80.49	OK	8636	2026-09-16 10:30	81.65	OK
8637	2026-09-16 10:31	77.40	OK	8638	2026-09-16 10:32	82.05	OK
8639	2026-09-16 10:33	79.99	OK	8640	2026-09-16 10:34	81.13	OK
8641	2026-09-16 10:35	76.50	OK	8642	2026-09-16 10:36	81.11	OK
8643	2026-09-16 10:37	80.78	OK	8644	2026-09-16 10:38	77.58	OK
8645	2026-09-16 10:39	80.19	OK	8646	2026-09-16 10:40	80.99	OK
8647	2026-09-16 10:41	79.85	OK	8648	2026-09-16 10:42	80.07	OK
8649	2026-09-16 10:43	81.22	OK	8650	2026-09-16 10:44	81.35	OK
8651	2026-09-16 10:45	80.52	OK	8652	2026-09-16 10:46	82.42	OK
8653	2026-09-16 10:47	81.44	OK	8654	2026-09-16 10:48	81.33	OK
8655	2026-09-16 10:49	78.92	OK	8656	2026-09-16 10:50	77.23	OK
8657	2026-09-16 10:51	80.24	OK	8658	2026-09-16 10:52	80.36	OK
8659	2026-09-16 10:53	80.57	OK	8660	2026-09-16 10:54	82.79	OK
8661	2026-09-16 10:55	80.23	OK	8662	2026-09-16 10:56	79.01	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8663	2026-09-16 10:57	82.23	OK	8664	2026-09-16 10:58	77.99	OK
8665	2026-09-16 10:59	79.55	OK	8666	2026-09-16 11:00	79.87	OK
8667	2026-09-16 11:01	81.44	OK	8668	2026-09-16 11:02	83.03	OK
8669	2026-09-16 11:03	77.86	OK	8670	2026-09-16 11:04	78.48	OK
8671	2026-09-16 11:05	81.60	OK	8672	2026-09-16 11:06	81.83	OK
8673	2026-09-16 11:07	80.53	OK	8674	2026-09-16 11:08	82.33	OK
8675	2026-09-16 11:09	78.29	OK	8676	2026-09-16 11:10	79.61	OK
8677	2026-09-16 11:11	82.33	OK	8678	2026-09-16 11:12	78.49	OK
8679	2026-09-16 11:13	81.62	OK	8680	2026-09-16 11:14	81.42	OK
8681	2026-09-16 11:15	79.76	OK	8682	2026-09-16 11:16	79.42	OK
8683	2026-09-16 11:17	80.22	OK	8684	2026-09-16 11:18	79.37	OK
8685	2026-09-16 11:19	79.39	OK	8686	2026-09-16 11:20	80.62	OK
8687	2026-09-16 11:21	79.72	OK	8688	2026-09-16 11:22	78.77	OK
8689	2026-09-16 11:23	82.22	OK	8690	2026-09-16 11:24	81.51	OK
8691	2026-09-16 11:25	81.74	OK	8692	2026-09-16 11:26	81.67	OK
8693	2026-09-16 11:27	83.53	OK	8694	2026-09-16 11:28	80.37	OK
8695	2026-09-16 11:29	82.46	OK	8696	2026-09-16 11:30	81.11	OK
8697	2026-09-16 11:31	78.69	OK	8698	2026-09-16 11:32	79.20	OK
8699	2026-09-16 11:33	79.59	OK	8700	2026-09-16 11:34	78.18	OK
8701	2026-09-16 11:35	79.91	OK	8702	2026-09-16 11:36	79.73	OK
8703	2026-09-16 11:37	80.13	OK	8704	2026-09-16 11:38	80.17	OK
8705	2026-09-16 11:39	82.20	OK	8706	2026-09-16 11:40	78.77	OK
8707	2026-09-16 11:41	81.42	OK	8708	2026-09-16 11:42	80.40	OK
8709	2026-09-16 11:43	78.74	OK	8710	2026-09-16 11:44	82.88	OK
8711	2026-09-16 11:45	79.05	OK	8712	2026-09-16 11:46	80.94	OK
8713	2026-09-16 11:47	80.46	OK	8714	2026-09-16 11:48	79.82	OK
8715	2026-09-16 11:49	82.05	OK	8716	2026-09-16 11:50	79.38	OK
8717	2026-09-16 11:51	79.25	OK	8718	2026-09-16 11:52	80.05	OK
8719	2026-09-16 11:53	81.53	OK	8720	2026-09-16 11:54	84.47	OK
8721	2026-09-16 11:55	83.52	OK	8722	2026-09-16 11:56	80.06	OK
8723	2026-09-16 11:57	77.18	OK	8724	2026-09-16 11:58	81.89	OK
8725	2026-09-16 11:59	79.27	OK	8726	2026-09-16 12:00	78.17	OK
8727	2026-09-16 12:01	81.53	OK	8728	2026-09-16 12:02	80.38	OK
8729	2026-09-16 12:03	83.58	OK	8730	2026-09-16 12:04	79.97	OK
8731	2026-09-16 12:05	81.60	OK	8732	2026-09-16 12:06	80.52	OK
8733	2026-09-16 12:07	82.83	OK	8734	2026-09-16 12:08	83.03	OK
8735	2026-09-16 12:09	80.33	OK	8736	2026-09-16 12:10	80.79	OK
8737	2026-09-16 12:11	78.93	OK	8738	2026-09-16 12:12	81.14	OK
8739	2026-09-16 12:13	79.82	OK	8740	2026-09-16 12:14	78.73	OK
8741	2026-09-16 12:15	81.17	OK	8742	2026-09-16 12:16	78.17	OK
8743	2026-09-16 12:17	79.24	OK	8744	2026-09-16 12:18	80.87	OK
8745	2026-09-16 12:19	82.56	OK	8746	2026-09-16 12:20	83.06	OK
8747	2026-09-16 12:21	82.58	OK	8748	2026-09-16 12:22	80.76	OK
8749	2026-09-16 12:23	81.89	OK	8750	2026-09-16 12:24	81.95	OK
8751	2026-09-16 12:25	78.53	OK	8752	2026-09-16 12:26	79.76	OK
8753	2026-09-16 12:27	81.03	OK	8754	2026-09-16 12:28	82.61	OK
8755	2026-09-16 12:29	82.99	OK	8756	2026-09-16 12:30	82.06	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8757	2026-09-16 12:31	83.04	OK	8758	2026-09-16 12:32	82.29	OK
8759	2026-09-16 12:33	81.24	OK	8760	2026-09-16 12:34	77.98	OK
8761	2026-09-16 12:35	83.23	OK	8762	2026-09-16 12:36	79.03	OK
8763	2026-09-16 12:37	78.66	OK	8764	2026-09-16 12:38	80.55	OK
8765	2026-09-16 12:39	79.97	OK	8766	2026-09-16 12:40	80.27	OK
8767	2026-09-16 12:41	79.96	OK	8768	2026-09-16 12:42	83.87	OK
8769	2026-09-16 12:43	79.84	OK	8770	2026-09-16 12:44	82.79	OK
8771	2026-09-16 12:45	80.81	OK	8772	2026-09-16 12:46	80.64	OK
8773	2026-09-16 12:47	83.27	OK	8774	2026-09-16 12:48	80.28	OK
8775	2026-09-16 12:49	81.23	OK	8776	2026-09-16 12:50	80.48	OK
8777	2026-09-16 12:51	81.66	OK	8778	2026-09-16 12:52	78.13	OK
8779	2026-09-16 12:53	79.92	OK	8780	2026-09-16 12:54	81.07	OK
8781	2026-09-16 12:55	82.92	OK	8782	2026-09-16 12:56	81.44	OK
8783	2026-09-16 12:57	81.35	OK	8784	2026-09-16 12:58	78.99	OK
8785	2026-09-16 12:59	80.86	OK	8786	2026-09-16 13:00	81.06	OK
8787	2026-09-16 13:01	81.50	OK	8788	2026-09-16 13:02	80.93	OK
8789	2026-09-16 13:03	81.75	OK	8790	2026-09-16 13:04	81.30	OK
8791	2026-09-16 13:05	80.47	OK	8792	2026-09-16 13:06	78.69	OK
8793	2026-09-16 13:07	81.40	OK	8794	2026-09-16 13:08	83.60	OK
8795	2026-09-16 13:09	81.05	OK	8796	2026-09-16 13:10	80.84	OK
8797	2026-09-16 13:11	80.26	OK	8798	2026-09-16 13:12	83.22	OK
8799	2026-09-16 13:13	81.79	OK	8800	2026-09-16 13:14	79.83	OK
8801	2026-09-16 13:15	83.07	OK	8802	2026-09-16 13:16	80.88	OK
8803	2026-09-16 13:17	84.32	OK	8804	2026-09-16 13:18	81.07	OK
8805	2026-09-16 13:19	77.09	OK	8806	2026-09-16 13:20	79.15	OK
8807	2026-09-16 13:21	80.79	OK	8808	2026-09-16 13:22	81.26	OK
8809	2026-09-16 13:23	79.82	OK	8810	2026-09-16 13:24	79.71	OK
8811	2026-09-16 13:25	83.59	OK	8812	2026-09-16 13:26	79.98	OK
8813	2026-09-16 13:27	83.04	OK	8814	2026-09-16 13:28	81.70	OK
8815	2026-09-16 13:29	80.40	OK	8816	2026-09-16 13:30	79.37	OK
8817	2026-09-16 13:31	82.64	OK	8818	2026-09-16 13:32	80.43	OK
8819	2026-09-16 13:33	79.02	OK	8820	2026-09-16 13:34	81.83	OK
8821	2026-09-16 13:35	79.69	OK	8822	2026-09-16 13:36	78.81	OK
8823	2026-09-16 13:37	82.20	OK	8824	2026-09-16 13:38	83.86	OK
8825	2026-09-16 13:39	82.61	OK	8826	2026-09-16 13:40	79.71	OK
8827	2026-09-16 13:41	79.09	OK	8828	2026-09-16 13:42	79.74	OK
8829	2026-09-16 13:43	82.80	OK	8830	2026-09-16 13:44	80.77	OK
8831	2026-09-16 13:45	78.62	OK	8832	2026-09-16 13:46	81.67	OK
8833	2026-09-16 13:47	82.43	OK	8834	2026-09-16 13:48	79.62	OK
8835	2026-09-16 13:49	79.22	OK	8836	2026-09-16 13:50	84.96	OK
8837	2026-09-16 13:51	79.35	OK	8838	2026-09-16 13:52	80.78	OK
8839	2026-09-16 13:53	77.89	OK	8840	2026-09-16 13:54	81.97	OK
8841	2026-09-16 13:55	80.14	OK	8842	2026-09-16 13:56	81.53	OK
8843	2026-09-16 13:57	82.25	OK	8844	2026-09-16 13:58	77.61	OK
8845	2026-09-16 13:59	80.57	OK	8846	2026-09-16 14:00	80.57	OK
8847	2026-09-16 14:01	80.70	OK	8848	2026-09-16 14:02	79.05	OK
8849	2026-09-16 14:03	83.46	OK	8850	2026-09-16 14:04	81.96	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8851	2026-09-16 14:05	79.28	OK	8852	2026-09-16 14:06	81.84	OK
8853	2026-09-16 14:07	78.51	OK	8854	2026-09-16 14:08	79.59	OK
8855	2026-09-16 14:09	81.77	OK	8856	2026-09-16 14:10	77.91	OK
8857	2026-09-16 14:11	80.50	OK	8858	2026-09-16 14:12	80.01	OK
8859	2026-09-16 14:13	82.49	OK	8860	2026-09-16 14:14	79.36	OK
8861	2026-09-16 14:15	83.08	OK	8862	2026-09-16 14:16	80.10	OK
8863	2026-09-16 14:17	79.89	OK	8864	2026-09-16 14:18	76.95	OK
8865	2026-09-16 14:19	80.90	OK	8866	2026-09-16 14:20	80.08	OK
8867	2026-09-16 14:21	81.98	OK	8868	2026-09-16 14:22	78.01	OK
8869	2026-09-16 14:23	80.64	OK	8870	2026-09-16 14:24	80.85	OK
8871	2026-09-16 14:25	80.14	OK	8872	2026-09-16 14:26	82.86	OK
8873	2026-09-16 14:27	81.93	OK	8874	2026-09-16 14:28	80.83	OK
8875	2026-09-16 14:29	81.44	OK	8876	2026-09-16 14:30	79.53	OK
8877	2026-09-16 14:31	80.54	OK	8878	2026-09-16 14:32	81.37	OK
8879	2026-09-16 14:33	82.59	OK	8880	2026-09-16 14:34	80.08	OK
8881	2026-09-16 14:35	83.45	OK	8882	2026-09-16 14:36	80.18	OK
8883	2026-09-16 14:37	79.89	OK	8884	2026-09-16 14:38	81.22	OK
8885	2026-09-16 14:39	82.80	OK	8886	2026-09-16 14:40	80.27	OK
8887	2026-09-16 14:41	80.14	OK	8888	2026-09-16 14:42	81.76	OK
8889	2026-09-16 14:43	79.68	OK	8890	2026-09-16 14:44	84.11	OK
8891	2026-09-16 14:45	78.16	OK	8892	2026-09-16 14:46	76.76	OK
8893	2026-09-16 14:47	76.92	OK	8894	2026-09-16 14:48	80.36	OK
8895	2026-09-16 14:49	83.44	OK	8896	2026-09-16 14:50	82.26	OK
8897	2026-09-16 14:51	81.77	OK	8898	2026-09-16 14:52	81.91	OK
8899	2026-09-16 14:53	81.31	OK	8900	2026-09-16 14:54	79.07	OK
8901	2026-09-16 14:55	79.43	OK	8902	2026-09-16 14:56	79.07	OK
8903	2026-09-16 14:57	80.89	OK	8904	2026-09-16 14:58	79.45	OK
8905	2026-09-16 14:59	80.44	OK	8906	2026-09-16 15:00	78.23	OK
8907	2026-09-16 15:01	83.86	OK	8908	2026-09-16 15:02	80.19	OK
8909	2026-09-16 15:03	79.73	OK	8910	2026-09-16 15:04	80.40	OK
8911	2026-09-16 15:05	80.75	OK	8912	2026-09-16 15:06	80.77	OK
8913	2026-09-16 15:07	80.03	OK	8914	2026-09-16 15:08	79.87	OK
8915	2026-09-16 15:09	79.10	OK	8916	2026-09-16 15:10	81.40	OK
8917	2026-09-16 15:11	81.63	OK	8918	2026-09-16 15:12	80.49	OK
8919	2026-09-16 15:13	77.18	OK	8920	2026-09-16 15:14	80.35	OK
8921	2026-09-16 15:15	80.85	OK	8922	2026-09-16 15:16	81.18	OK
8923	2026-09-16 15:17	79.19	OK	8924	2026-09-16 15:18	79.51	OK
8925	2026-09-16 15:19	80.18	OK	8926	2026-09-16 15:20	82.64	OK
8927	2026-09-16 15:21	82.36	OK	8928	2026-09-16 15:22	78.06	OK
8929	2026-09-16 15:23	80.53	OK	8930	2026-09-16 15:24	76.66	OK
8931	2026-09-16 15:25	80.38	OK	8932	2026-09-16 15:26	77.33	OK
8933	2026-09-16 15:27	79.49	OK	8934	2026-09-16 15:28	80.10	OK
8935	2026-09-16 15:29	79.29	OK	8936	2026-09-16 15:30	83.15	OK
8937	2026-09-16 15:31	79.44	OK	8938	2026-09-16 15:32	80.96	OK
8939	2026-09-16 15:33	79.64	OK	8940	2026-09-16 15:34	81.35	OK
8941	2026-09-16 15:35	78.51	OK	8942	2026-09-16 15:36	78.95	OK
8943	2026-09-16 15:37	81.47	OK	8944	2026-09-16 15:38	79.58	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8945	2026-09-16 15:39	81.43	OK	8946	2026-09-16 15:40	78.91	OK
8947	2026-09-16 15:41	78.79	OK	8948	2026-09-16 15:42	77.34	OK
8949	2026-09-16 15:43	81.25	OK	8950	2026-09-16 15:44	82.16	OK
8951	2026-09-16 15:45	80.50	OK	8952	2026-09-16 15:46	78.14	OK
8953	2026-09-16 15:47	82.61	OK	8954	2026-09-16 15:48	79.40	OK
8955	2026-09-16 15:49	80.03	OK	8956	2026-09-16 15:50	78.52	OK
8957	2026-09-16 15:51	79.28	OK	8958	2026-09-16 15:52	77.95	OK
8959	2026-09-16 15:53	77.95	OK	8960	2026-09-16 15:54	78.15	OK
8961	2026-09-16 15:55	78.66	OK	8962	2026-09-16 15:56	79.17	OK
8963	2026-09-16 15:57	78.45	OK	8964	2026-09-16 15:58	77.10	OK
8965	2026-09-16 15:59	79.34	OK	8966	2026-09-16 16:00	80.73	OK
8967	2026-09-16 16:01	80.33	OK	8968	2026-09-16 16:02	80.51	OK
8969	2026-09-16 16:03	79.53	OK	8970	2026-09-16 16:04	79.49	OK
8971	2026-09-16 16:05	80.60	OK	8972	2026-09-16 16:06	78.45	OK
8973	2026-09-16 16:07	80.01	OK	8974	2026-09-16 16:08	82.35	OK
8975	2026-09-16 16:09	78.08	OK	8976	2026-09-16 16:10	75.79	OK
8977	2026-09-16 16:11	76.95	OK	8978	2026-09-16 16:12	77.78	OK
8979	2026-09-16 16:13	80.68	OK	8980	2026-09-16 16:14	77.16	OK
8981	2026-09-16 16:15	78.80	OK	8982	2026-09-16 16:16	76.46	OK
8983	2026-09-16 16:17	76.07	OK	8984	2026-09-16 16:18	77.10	OK
8985	2026-09-16 16:19	80.02	OK	8986	2026-09-16 16:20	78.53	OK
8987	2026-09-16 16:21	78.74	OK	8988	2026-09-16 16:22	76.60	OK
8989	2026-09-16 16:23	80.55	OK	8990	2026-09-16 16:24	79.82	OK
8991	2026-09-16 16:25	79.44	OK	8992	2026-09-16 16:26	78.32	OK
8993	2026-09-16 16:27	75.64	OK	8994	2026-09-16 16:28	82.87	OK
8995	2026-09-16 16:29	76.98	OK	8996	2026-09-16 16:30	78.66	OK
8997	2026-09-16 16:31	80.83	OK	8998	2026-09-16 16:32	75.53	OK
8999	2026-09-16 16:33	81.89	OK	9000	2026-09-16 16:34	78.81	OK
9001	2026-09-16 16:35	77.53	OK	9002	2026-09-16 16:36	78.60	OK
9003	2026-09-16 16:37	75.70	OK	9004	2026-09-16 16:38	77.06	OK
9005	2026-09-16 16:39	77.83	OK	9006	2026-09-16 16:40	76.12	OK
9007	2026-09-16 16:41	78.40	OK	9008	2026-09-16 16:42	77.09	OK
9009	2026-09-16 16:43	78.77	OK	9010	2026-09-16 16:44	76.17	OK
9011	2026-09-16 16:45	79.63	OK	9012	2026-09-16 16:46	79.23	OK
9013	2026-09-16 16:47	81.28	OK	9014	2026-09-16 16:48	78.55	OK
9015	2026-09-16 16:49	76.42	OK	9016	2026-09-16 16:50	79.52	OK
9017	2026-09-16 16:51	77.57	OK	9018	2026-09-16 16:52	80.15	OK
9019	2026-09-16 16:53	79.37	OK	9020	2026-09-16 16:54	78.36	OK
9021	2026-09-16 16:55	79.28	OK	9022	2026-09-16 16:56	76.18	OK
9023	2026-09-16 16:57	77.76	OK	9024	2026-09-16 16:58	77.54	OK
9025	2026-09-16 16:59	76.46	OK	9026	2026-09-16 17:00	77.58	OK
9027	2026-09-16 17:01	74.86	OK	9028	2026-09-16 17:02	76.53	OK
9029	2026-09-16 17:03	80.75	OK	9030	2026-09-16 17:04	77.65	OK
9031	2026-09-16 17:05	77.66	OK	9032	2026-09-16 17:06	79.50	OK
9033	2026-09-16 17:07	77.08	OK	9034	2026-09-16 17:08	78.00	OK
9035	2026-09-16 17:09	77.34	OK	9036	2026-09-16 17:10	78.76	OK
9037	2026-09-16 17:11	74.24	OK	9038	2026-09-16 17:12	76.31	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9039	2026-09-16 17:13	75.68	OK	9040	2026-09-16 17:14	76.05	OK
9041	2026-09-16 17:15	78.93	OK	9042	2026-09-16 17:16	76.18	OK
9043	2026-09-16 17:17	76.89	OK	9044	2026-09-16 17:18	79.12	OK
9045	2026-09-16 17:19	80.31	OK	9046	2026-09-16 17:20	78.87	OK
9047	2026-09-16 17:21	78.10	OK	9048	2026-09-16 17:22	78.81	OK
9049	2026-09-16 17:23	77.80	OK	9050	2026-09-16 17:24	80.24	OK
9051	2026-09-16 17:25	76.85	OK	9052	2026-09-16 17:26	78.39	OK
9053	2026-09-16 17:27	75.32	OK	9054	2026-09-16 17:28	76.78	OK
9055	2026-09-16 17:29	77.06	OK	9056	2026-09-16 17:30	77.60	OK
9057	2026-09-16 17:31	74.98	OK	9058	2026-09-16 17:32	77.58	OK
9059	2026-09-16 17:33	79.82	OK	9060	2026-09-16 17:34	78.66	OK
9061	2026-09-16 17:35	77.72	OK	9062	2026-09-16 17:36	78.84	OK
9063	2026-09-16 17:37	78.74	OK	9064	2026-09-16 17:38	74.38	OK
9065	2026-09-16 17:39	75.67	OK	9066	2026-09-16 17:40	76.36	OK
9067	2026-09-16 17:41	76.78	OK	9068	2026-09-16 17:42	75.21	OK
9069	2026-09-16 17:43	76.03	OK	9070	2026-09-16 17:44	80.93	OK
9071	2026-09-16 17:45	77.47	OK	9072	2026-09-16 17:46	76.82	OK
9073	2026-09-16 17:47	79.24	OK	9074	2026-09-16 17:48	75.13	OK
9075	2026-09-16 17:49	75.30	OK	9076	2026-09-16 17:50	79.74	OK
9077	2026-09-16 17:51	74.69	OK	9078	2026-09-16 17:52	75.81	OK
9079	2026-09-16 17:53	79.61	OK	9080	2026-09-16 17:54	76.53	OK
9081	2026-09-16 17:55	76.43	OK	9082	2026-09-16 17:56	75.80	OK
9083	2026-09-16 17:57	77.23	OK	9084	2026-09-16 17:58	77.89	OK
9085	2026-09-16 17:59	75.47	OK	9086	2026-09-16 18:00	76.17	OK
9087	2026-09-16 18:01	76.25	OK	9088	2026-09-16 18:02	78.67	OK
9089	2026-09-16 18:03	76.85	OK	9090	2026-09-16 18:04	76.80	OK
9091	2026-09-16 18:05	77.46	OK	9092	2026-09-16 18:06	76.14	OK
9093	2026-09-16 18:07	74.46	OK	9094	2026-09-16 18:08	78.96	OK
9095	2026-09-16 18:09	76.05	OK	9096	2026-09-16 18:10	74.91	OK
9097	2026-09-16 18:11	74.21	OK	9098	2026-09-16 18:12	76.04	OK
9099	2026-09-16 18:13	76.44	OK	9100	2026-09-16 18:14	74.76	OK
9101	2026-09-16 18:15	75.58	OK	9102	2026-09-16 18:16	74.38	OK
9103	2026-09-16 18:17	79.57	OK	9104	2026-09-16 18:18	74.79	OK
9105	2026-09-16 18:19	76.59	OK	9106	2026-09-16 18:20	78.70	OK
9107	2026-09-16 18:21	75.20	OK	9108	2026-09-16 18:22	79.34	OK
9109	2026-09-16 18:23	77.08	OK	9110	2026-09-16 18:24	75.96	OK
9111	2026-09-16 18:25	73.99	OK	9112	2026-09-16 18:26	76.41	OK
9113	2026-09-16 18:27	78.76	OK	9114	2026-09-16 18:28	77.68	OK
9115	2026-09-16 18:29	79.17	OK	9116	2026-09-16 18:30	73.73	OK
9117	2026-09-16 18:31	78.05	OK	9118	2026-09-16 18:32	75.09	OK
9119	2026-09-16 18:33	75.65	OK	9120	2026-09-16 18:34	75.17	OK
9121	2026-09-16 18:35	77.19	OK	9122	2026-09-16 18:36	79.31	OK
9123	2026-09-16 18:37	76.94	OK	9124	2026-09-16 18:38	75.92	OK
9125	2026-09-16 18:39	76.26	OK	9126	2026-09-16 18:40	75.25	OK
9127	2026-09-16 18:41	75.70	OK	9128	2026-09-16 18:42	74.48	OK
9129	2026-09-16 18:43	73.89	OK	9130	2026-09-16 18:44	74.39	OK
9131	2026-09-16 18:45	75.37	OK	9132	2026-09-16 18:46	74.80	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9133	2026-09-16 18:47	75.60	OK	9134	2026-09-16 18:48	73.35	OK
9135	2026-09-16 18:49	74.03	OK	9136	2026-09-16 18:50	73.54	OK
9137	2026-09-16 18:51	76.59	OK	9138	2026-09-16 18:52	76.91	OK
9139	2026-09-16 18:53	77.89	OK	9140	2026-09-16 18:54	75.62	OK
9141	2026-09-16 18:55	75.59	OK	9142	2026-09-16 18:56	74.22	OK
9143	2026-09-16 18:57	75.87	OK	9144	2026-09-16 18:58	75.07	OK
9145	2026-09-16 18:59	72.99	OK	9146	2026-09-16 19:00	79.49	OK
9147	2026-09-16 19:01	76.08	OK	9148	2026-09-16 19:02	72.45	OK
9149	2026-09-16 19:03	77.38	OK	9150	2026-09-16 19:04	74.75	OK
9151	2026-09-16 19:05	74.48	OK	9152	2026-09-16 19:06	74.50	OK
9153	2026-09-16 19:07	75.76	OK	9154	2026-09-16 19:08	71.92	OK
9155	2026-09-16 19:09	75.87	OK	9156	2026-09-16 19:10	74.47	OK
9157	2026-09-16 19:11	72.20	OK	9158	2026-09-16 19:12	76.07	OK
9159	2026-09-16 19:13	75.54	OK	9160	2026-09-16 19:14	75.81	OK
9161	2026-09-16 19:15	71.81	OK	9162	2026-09-16 19:16	72.80	OK
9163	2026-09-16 19:17	74.46	OK	9164	2026-09-16 19:18	77.26	OK
9165	2026-09-16 19:19	73.52	OK	9166	2026-09-16 19:20	73.77	OK
9167	2026-09-16 19:21	75.51	OK	9168	2026-09-16 19:22	73.28	OK
9169	2026-09-16 19:23	72.24	OK	9170	2026-09-16 19:24	73.10	OK
9171	2026-09-16 19:25	73.65	OK	9172	2026-09-16 19:26	70.89	OK
9173	2026-09-16 19:27	77.31	OK	9174	2026-09-16 19:28	73.30	OK
9175	2026-09-16 19:29	75.53	OK	9176	2026-09-16 19:30	74.47	OK
9177	2026-09-16 19:31	75.69	OK	9178	2026-09-16 19:32	72.88	OK
9179	2026-09-16 19:33	73.48	OK	9180	2026-09-16 19:34	72.27	OK
9181	2026-09-16 19:35	72.61	OK	9182	2026-09-16 19:36	72.51	OK
9183	2026-09-16 19:37	74.20	OK	9184	2026-09-16 19:38	72.44	OK
9185	2026-09-16 19:39	75.17	OK	9186	2026-09-16 19:40	73.90	OK
9187	2026-09-16 19:41	71.84	OK	9188	2026-09-16 19:42	77.79	OK
9189	2026-09-16 19:43	74.05	OK	9190	2026-09-16 19:44	74.75	OK
9191	2026-09-16 19:45	75.51	OK	9192	2026-09-16 19:46	72.81	OK
9193	2026-09-16 19:47	72.78	OK	9194	2026-09-16 19:48	75.46	OK
9195	2026-09-16 19:49	74.73	OK	9196	2026-09-16 19:50	74.50	OK
9197	2026-09-16 19:51	74.91	OK	9198	2026-09-16 19:52	73.89	OK
9199	2026-09-16 19:53	75.04	OK	9200	2026-09-16 19:54	72.90	OK
9201	2026-09-16 19:55	70.85	OK	9202	2026-09-16 19:56	69.83	OK
9203	2026-09-16 19:57	73.17	OK	9204	2026-09-16 19:58	75.53	OK
9205	2026-09-16 19:59	71.22	OK	9206	2026-09-16 20:00	74.36	OK
9207	2026-09-16 20:01	72.60	OK	9208	2026-09-16 20:02	74.18	OK
9209	2026-09-16 20:03	75.60	OK	9210	2026-09-16 20:04	71.00	OK
9211	2026-09-16 20:05	74.38	OK	9212	2026-09-16 20:06	74.32	OK
9213	2026-09-16 20:07	72.49	OK	9214	2026-09-16 20:08	76.63	OK
9215	2026-09-16 20:09	72.73	OK	9216	2026-09-16 20:10	74.90	OK
9217	2026-09-16 20:11	74.11	OK	9218	2026-09-16 20:12	73.32	OK
9219	2026-09-16 20:13	72.70	OK	9220	2026-09-16 20:14	74.68	OK
9221	2026-09-16 20:15	70.14	OK	9222	2026-09-16 20:16	75.27	OK
9223	2026-09-16 20:17	70.44	OK	9224	2026-09-16 20:18	69.67	OK
9225	2026-09-16 20:19	72.57	OK	9226	2026-09-16 20:20	70.43	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9227	2026-09-16 20:21	73.19	OK	9228	2026-09-16 20:22	72.87	OK
9229	2026-09-16 20:23	72.81	OK	9230	2026-09-16 20:24	72.41	OK
9231	2026-09-16 20:25	73.59	OK	9232	2026-09-16 20:26	75.13	OK
9233	2026-09-16 20:27	71.81	OK	9234	2026-09-16 20:28	74.26	OK
9235	2026-09-16 20:29	72.77	OK	9236	2026-09-16 20:30	70.69	OK
9237	2026-09-16 20:31	71.87	OK	9238	2026-09-16 20:32	73.00	OK
9239	2026-09-16 20:33	74.25	OK	9240	2026-09-16 20:34	75.27	OK
9241	2026-09-16 20:35	70.20	OK	9242	2026-09-16 20:36	69.35	OK
9243	2026-09-16 20:37	75.62	OK	9244	2026-09-16 20:38	74.67	OK
9245	2026-09-16 20:39	69.93	OK	9246	2026-09-16 20:40	72.18	OK
9247	2026-09-16 20:41	73.56	OK	9248	2026-09-16 20:42	73.67	OK
9249	2026-09-16 20:43	71.98	OK	9250	2026-09-16 20:44	74.28	OK
9251	2026-09-16 20:45	74.42	OK	9252	2026-09-16 20:46	73.11	OK
9253	2026-09-16 20:47	72.32	OK	9254	2026-09-16 20:48	73.37	OK
9255	2026-09-16 20:49	72.30	OK	9256	2026-09-16 20:50	71.94	OK
9257	2026-09-16 20:51	74.45	OK	9258	2026-09-16 20:52	72.60	OK
9259	2026-09-16 20:53	74.09	OK	9260	2026-09-16 20:54	70.63	OK
9261	2026-09-16 20:55	71.68	OK	9262	2026-09-16 20:56	74.51	OK
9263	2026-09-16 20:57	70.67	OK	9264	2026-09-16 20:58	72.14	OK
9265	2026-09-16 20:59	72.60	OK	9266	2026-09-16 21:00	71.15	OK
9267	2026-09-16 21:01	71.40	OK	9268	2026-09-16 21:02	70.45	OK
9269	2026-09-16 21:03	71.93	OK	9270	2026-09-16 21:04	75.01	OK
9271	2026-09-16 21:05	70.74	OK	9272	2026-09-16 21:06	71.55	OK
9273	2026-09-16 21:07	73.47	OK	9274	2026-09-16 21:08	71.03	OK
9275	2026-09-16 21:09	71.94	OK	9276	2026-09-16 21:10	73.28	OK
9277	2026-09-16 21:11	71.85	OK	9278	2026-09-16 21:12	71.31	OK
9279	2026-09-16 21:13	73.93	OK	9280	2026-09-16 21:14	72.60	OK
9281	2026-09-16 21:15	72.49	OK	9282	2026-09-16 21:16	71.92	OK
9283	2026-09-16 21:17	72.40	OK	9284	2026-09-16 21:18	68.65	OK
9285	2026-09-16 21:19	70.99	OK	9286	2026-09-16 21:20	71.84	OK
9287	2026-09-16 21:21	71.16	OK	9288	2026-09-16 21:22	71.51	OK
9289	2026-09-16 21:23	70.00	OK	9290	2026-09-16 21:24	71.36	OK
9291	2026-09-16 21:25	73.47	OK	9292	2026-09-16 21:26	73.59	OK
9293	2026-09-16 21:27	72.00	OK	9294	2026-09-16 21:28	75.75	OK
9295	2026-09-16 21:29	68.04	OK	9296	2026-09-16 21:30	75.28	OK
9297	2026-09-16 21:31	74.00	OK	9298	2026-09-16 21:32	69.20	OK
9299	2026-09-16 21:33	73.70	OK	9300	2026-09-16 21:34	69.47	OK
9301	2026-09-16 21:35	71.46	OK	9302	2026-09-16 21:36	71.29	OK
9303	2026-09-16 21:37	72.55	OK	9304	2026-09-16 21:38	70.17	OK
9305	2026-09-16 21:39	73.81	OK	9306	2026-09-16 21:40	73.54	OK
9307	2026-09-16 21:41	71.03	OK	9308	2026-09-16 21:42	70.25	OK
9309	2026-09-16 21:43	72.13	OK	9310	2026-09-16 21:44	72.45	OK
9311	2026-09-16 21:45	71.55	OK	9312	2026-09-16 21:46	70.45	OK
9313	2026-09-16 21:47	71.43	OK	9314	2026-09-16 21:48	71.71	OK
9315	2026-09-16 21:49	70.60	OK	9316	2026-09-16 21:50	68.55	OK
9317	2026-09-16 21:51	70.04	OK	9318	2026-09-16 21:52	72.76	OK
9319	2026-09-16 21:53	73.31	OK	9320	2026-09-16 21:54	70.36	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9321	2026-09-16 21:55	68.45	OK	9322	2026-09-16 21:56	72.98	OK
9323	2026-09-16 21:57	72.12	OK	9324	2026-09-16 21:58	69.60	OK
9325	2026-09-16 21:59	68.84	OK	9326	2026-09-16 22:00	71.41	OK
9327	2026-09-16 22:01	72.29	OK	9328	2026-09-16 22:02	73.72	OK
9329	2026-09-16 22:03	71.30	OK	9330	2026-09-16 22:04	70.27	OK
9331	2026-09-16 22:05	70.27	OK	9332	2026-09-16 22:06	70.90	OK
9333	2026-09-16 22:07	68.89	OK	9334	2026-09-16 22:08	69.94	OK
9335	2026-09-16 22:09	72.21	OK	9336	2026-09-16 22:10	67.77	OK
9337	2026-09-16 22:11	70.13	OK	9338	2026-09-16 22:12	70.22	OK
9339	2026-09-16 22:13	71.47	OK	9340	2026-09-16 22:14	69.28	OK
9341	2026-09-16 22:15	71.49	OK	9342	2026-09-16 22:16	69.05	OK
9343	2026-09-16 22:17	73.19	OK	9344	2026-09-16 22:18	72.35	OK
9345	2026-09-16 22:19	70.87	OK	9346	2026-09-16 22:20	71.63	OK
9347	2026-09-16 22:21	72.70	OK	9348	2026-09-16 22:22	66.75	OK
9349	2026-09-16 22:23	69.47	OK	9350	2026-09-16 22:24	69.08	OK
9351	2026-09-16 22:25	74.47	OK	9352	2026-09-16 22:26	71.18	OK
9353	2026-09-16 22:27	68.92	OK	9354	2026-09-16 22:28	70.74	OK
9355	2026-09-16 22:29	67.29	OK	9356	2026-09-16 22:30	71.54	OK
9357	2026-09-16 22:31	69.58	OK	9358	2026-09-16 22:32	70.59	OK
9359	2026-09-16 22:33	72.24	OK	9360	2026-09-16 22:34	73.07	OK
9361	2026-09-16 22:35	69.27	OK	9362	2026-09-16 22:36	72.39	OK
9363	2026-09-16 22:37	70.76	OK	9364	2026-09-16 22:38	71.83	OK
9365	2026-09-16 22:39	69.77	OK	9366	2026-09-16 22:40	67.38	OK
9367	2026-09-16 22:41	71.19	OK	9368	2026-09-16 22:42	69.46	OK
9369	2026-09-16 22:43	69.99	OK	9370	2026-09-16 22:44	71.59	OK
9371	2026-09-16 22:45	70.25	OK	9372	2026-09-16 22:46	70.08	OK
9373	2026-09-16 22:47	68.84	OK	9374	2026-09-16 22:48	70.84	OK
9375	2026-09-16 22:49	70.35	OK	9376	2026-09-16 22:50	69.37	OK
9377	2026-09-16 22:51	71.46	OK	9378	2026-09-16 22:52	72.93	OK
9379	2026-09-16 22:53	70.54	OK	9380	2026-09-16 22:54	71.67	OK
9381	2026-09-16 22:55	69.99	OK	9382	2026-09-16 22:56	69.87	OK
9383	2026-09-16 22:57	71.99	OK	9384	2026-09-16 22:58	72.16	OK
9385	2026-09-16 22:59	70.04	OK	9386	2026-09-16 23:00	68.07	OK
9387	2026-09-16 23:01	70.56	OK	9388	2026-09-16 23:02	70.75	OK
9389	2026-09-16 23:03	70.03	OK	9390	2026-09-16 23:04	69.35	OK
9391	2026-09-16 23:05	70.58	OK	9392	2026-09-16 23:06	70.51	OK
9393	2026-09-16 23:07	69.15	OK	9394	2026-09-16 23:08	70.42	OK
9395	2026-09-16 23:09	70.73	OK	9396	2026-09-16 23:10	67.96	OK
9397	2026-09-16 23:11	67.90	OK	9398	2026-09-16 23:12	71.46	OK
9399	2026-09-16 23:13	71.24	OK	9400	2026-09-16 23:14	68.06	OK
9401	2026-09-16 23:15	70.15	OK	9402	2026-09-16 23:16	71.57	OK
9403	2026-09-16 23:17	70.37	OK	9404	2026-09-16 23:18	69.82	OK
9405	2026-09-16 23:19	69.64	OK	9406	2026-09-16 23:20	70.33	OK
9407	2026-09-16 23:21	68.95	OK	9408	2026-09-16 23:22	71.87	OK
9409	2026-09-16 23:23	69.81	OK	9410	2026-09-16 23:24	69.90	OK
9411	2026-09-16 23:25	69.77	OK	9412	2026-09-16 23:26	70.21	OK
9413	2026-09-16 23:27	71.51	OK	9414	2026-09-16 23:28	71.00	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9415	2026-09-16 23:29	71.31	OK	9416	2026-09-16 23:30	72.14	OK
9417	2026-09-16 23:31	68.74	OK	9418	2026-09-16 23:32	69.77	OK
9419	2026-09-16 23:33	69.93	OK	9420	2026-09-16 23:34	68.92	OK
9421	2026-09-16 23:35	71.70	OK	9422	2026-09-16 23:36	66.44	OK
9423	2026-09-16 23:37	67.93	OK	9424	2026-09-16 23:38	70.28	OK
9425	2026-09-16 23:39	69.61	OK	9426	2026-09-16 23:40	71.42	OK
9427	2026-09-16 23:41	72.25	OK	9428	2026-09-16 23:42	71.41	OK
9429	2026-09-16 23:43	68.39	OK	9430	2026-09-16 23:44	68.92	OK
9431	2026-09-16 23:45	71.44	OK	9432	2026-09-16 23:46	70.59	OK
9433	2026-09-16 23:47	70.26	OK	9434	2026-09-16 23:48	68.16	OK
9435	2026-09-16 23:49	68.43	OK	9436	2026-09-16 23:50	69.81	OK
9437	2026-09-16 23:51	66.19	OK	9438	2026-09-16 23:52	66.94	OK
9439	2026-09-16 23:53	67.79	OK	9440	2026-09-16 23:54	68.80	OK
9441	2026-09-16 23:55	67.78	OK	9442	2026-09-16 23:56	69.36	OK
9443	2026-09-16 23:57	69.88	OK	9444	2026-09-16 23:58	70.51	OK
9445	2026-09-16 23:59	68.70	OK	9446	2026-09-17 00:00	72.61	OK
9447	2026-09-17 00:01	67.95	OK	9448	2026-09-17 00:02	70.92	OK
9449	2026-09-17 00:03	69.59	OK	9450	2026-09-17 00:04	70.55	OK
9451	2026-09-17 00:05	68.95	OK	9452	2026-09-17 00:06	70.79	OK
9453	2026-09-17 00:07	71.00	OK	9454	2026-09-17 00:08	70.90	OK
9455	2026-09-17 00:09	71.70	OK	9456	2026-09-17 00:10	67.24	OK
9457	2026-09-17 00:11	69.88	OK	9458	2026-09-17 00:12	68.79	OK
9459	2026-09-17 00:13	71.06	OK	9460	2026-09-17 00:14	69.62	OK
9461	2026-09-17 00:15	70.04	OK	9462	2026-09-17 00:16	70.09	OK
9463	2026-09-17 00:17	70.59	OK	9464	2026-09-17 00:18	70.22	OK
9465	2026-09-17 00:19	69.35	OK	9466	2026-09-17 00:20	69.70	OK
9467	2026-09-17 00:21	68.11	OK	9468	2026-09-17 00:22	69.77	OK
9469	2026-09-17 00:23	69.59	OK	9470	2026-09-17 00:24	66.72	OK
9471	2026-09-17 00:25	67.19	OK	9472	2026-09-17 00:26	66.88	OK
9473	2026-09-17 00:27	67.52	OK	9474	2026-09-17 00:28	69.16	OK
9475	2026-09-17 00:29	68.17	OK	9476	2026-09-17 00:30	69.17	OK
9477	2026-09-17 00:31	71.56	OK	9478	2026-09-17 00:32	71.94	OK
9479	2026-09-17 00:33	70.59	OK	9480	2026-09-17 00:34	71.27	OK
9481	2026-09-17 00:35	71.39	OK	9482	2026-09-17 00:36	70.16	OK
9483	2026-09-17 00:37	69.13	OK	9484	2026-09-17 00:38	70.86	OK
9485	2026-09-17 00:39	69.58	OK	9486	2026-09-17 00:40	70.44	OK
9487	2026-09-17 00:41	69.21	OK	9488	2026-09-17 00:42	66.85	OK
9489	2026-09-17 00:43	69.47	OK	9490	2026-09-17 00:44	66.75	OK
9491	2026-09-17 00:45	70.70	OK	9492	2026-09-17 00:46	71.89	OK
9493	2026-09-17 00:47	70.06	OK	9494	2026-09-17 00:48	68.59	OK
9495	2026-09-17 00:49	68.57	OK	9496	2026-09-17 00:50	67.12	OK
9497	2026-09-17 00:51	67.42	OK	9498	2026-09-17 00:52	70.94	OK
9499	2026-09-17 00:53	69.44	OK	9500	2026-09-17 00:54	66.81	OK
9501	2026-09-17 00:55	71.98	OK	9502	2026-09-17 00:56	67.33	OK
9503	2026-09-17 00:57	68.94	OK	9504	2026-09-17 00:58	69.02	OK
9505	2026-09-17 00:59	67.63	OK	9506	2026-09-17 01:00	67.27	OK
9507	2026-09-17 01:01	69.43	OK	9508	2026-09-17 01:02	67.09	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9509	2026-09-17 01:03	69.04	OK	9510	2026-09-17 01:04	71.01	OK
9511	2026-09-17 01:05	68.79	OK	9512	2026-09-17 01:06	67.63	OK
9513	2026-09-17 01:07	70.85	OK	9514	2026-09-17 01:08	70.66	OK
9515	2026-09-17 01:09	69.79	OK	9516	2026-09-17 01:10	68.88	OK
9517	2026-09-17 01:11	69.46	OK	9518	2026-09-17 01:12	67.85	OK
9519	2026-09-17 01:13	70.89	OK	9520	2026-09-17 01:14	69.12	OK
9521	2026-09-17 01:15	69.23	OK	9522	2026-09-17 01:16	71.85	OK
9523	2026-09-17 01:17	67.60	OK	9524	2026-09-17 01:18	68.93	OK
9525	2026-09-17 01:19	69.63	OK	9526	2026-09-17 01:20	69.67	OK
9527	2026-09-17 01:21	70.28	OK	9528	2026-09-17 01:22	67.67	OK
9529	2026-09-17 01:23	69.75	OK	9530	2026-09-17 01:24	70.01	OK
9531	2026-09-17 01:25	68.06	OK	9532	2026-09-17 01:26	70.56	OK
9533	2026-09-17 01:27	70.77	OK	9534	2026-09-17 01:28	69.11	OK
9535	2026-09-17 01:29	71.88	OK	9536	2026-09-17 01:30	69.95	OK
9537	2026-09-17 01:31	67.94	OK	9538	2026-09-17 01:32	69.59	OK
9539	2026-09-17 01:33	71.56	OK	9540	2026-09-17 01:34	71.30	OK
9541	2026-09-17 01:35	67.62	OK	9542	2026-09-17 01:36	70.60	OK
9543	2026-09-17 01:37	69.23	OK	9544	2026-09-17 01:38	71.87	OK
9545	2026-09-17 01:39	73.06	OK	9546	2026-09-17 01:40	68.13	OK
9547	2026-09-17 01:41	69.21	OK	9548	2026-09-17 01:42	67.14	OK
9549	2026-09-17 01:43	71.24	OK	9550	2026-09-17 01:44	71.72	OK
9551	2026-09-17 01:45	70.44	OK	9552	2026-09-17 01:46	71.06	OK
9553	2026-09-17 01:47	71.17	OK	9554	2026-09-17 01:48	69.43	OK
9555	2026-09-17 01:49	70.25	OK	9556	2026-09-17 01:50	67.63	OK
9557	2026-09-17 01:51	70.83	OK	9558	2026-09-17 01:52	67.07	OK
9559	2026-09-17 01:53	69.85	OK	9560	2026-09-17 01:54	71.13	OK
9561	2026-09-17 01:55	70.94	OK	9562	2026-09-17 01:56	68.26	OK
9563	2026-09-17 01:57	70.09	OK	9564	2026-09-17 01:58	72.07	OK
9565	2026-09-17 01:59	68.76	OK	9566	2026-09-17 02:00	66.72	OK
9567	2026-09-17 02:01	68.41	OK	9568	2026-09-17 02:02	69.96	OK
9569	2026-09-17 02:03	66.47	OK	9570	2026-09-17 02:04	67.12	OK
9571	2026-09-17 02:05	68.64	OK	9572	2026-09-17 02:06	68.98	OK
9573	2026-09-17 02:07	69.74	OK	9574	2026-09-17 02:08	67.22	OK
9575	2026-09-17 02:09	73.61	OK	9576	2026-09-17 02:10	70.09	OK
9577	2026-09-17 02:11	68.14	OK	9578	2026-09-17 02:12	71.12	OK
9579	2026-09-17 02:13	70.10	OK	9580	2026-09-17 02:14	71.15	OK
9581	2026-09-17 02:15	68.42	OK	9582	2026-09-17 02:16	69.00	OK
9583	2026-09-17 02:17	66.62	OK	9584	2026-09-17 02:18	67.01	OK
9585	2026-09-17 02:19	69.54	OK	9586	2026-09-17 02:20	69.86	OK
9587	2026-09-17 02:21	68.75	OK	9588	2026-09-17 02:22	70.18	OK
9589	2026-09-17 02:23	70.17	OK	9590	2026-09-17 02:24	69.56	OK
9591	2026-09-17 02:25	70.12	OK	9592	2026-09-17 02:26	68.32	OK
9593	2026-09-17 02:27	69.66	OK	9594	2026-09-17 02:28	69.31	OK
9595	2026-09-17 02:29	73.63	OK	9596	2026-09-17 02:30	69.28	OK
9597	2026-09-17 02:31	70.95	OK	9598	2026-09-17 02:32	69.61	OK
9599	2026-09-17 02:33	69.15	OK	9600	2026-09-17 02:34	68.31	OK
9601	2026-09-17 02:35	70.60	OK	9602	2026-09-17 02:36	70.14	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9603	2026-09-17 02:37	68.65	OK	9604	2026-09-17 02:38	70.49	OK
9605	2026-09-17 02:39	69.03	OK	9606	2026-09-17 02:40	69.05	OK
9607	2026-09-17 02:41	71.52	OK	9608	2026-09-17 02:42	69.25	OK
9609	2026-09-17 02:43	67.96	OK	9610	2026-09-17 02:44	68.07	OK
9611	2026-09-17 02:45	70.99	OK	9612	2026-09-17 02:46	69.57	OK
9613	2026-09-17 02:47	70.46	OK	9614	2026-09-17 02:48	68.93	OK
9615	2026-09-17 02:49	68.06	OK	9616	2026-09-17 02:50	71.20	OK
9617	2026-09-17 02:51	67.20	OK	9618	2026-09-17 02:52	71.67	OK
9619	2026-09-17 02:53	68.61	OK	9620	2026-09-17 02:54	71.14	OK
9621	2026-09-17 02:55	70.44	OK	9622	2026-09-17 02:56	71.64	OK
9623	2026-09-17 02:57	69.83	OK	9624	2026-09-17 02:58	68.91	OK
9625	2026-09-17 02:59	71.04	OK	9626	2026-09-17 03:00	68.56	OK
9627	2026-09-17 03:01	70.77	OK	9628	2026-09-17 03:02	72.24	OK
9629	2026-09-17 03:03	69.80	OK	9630	2026-09-17 03:04	72.48	OK
9631	2026-09-17 03:05	71.87	OK	9632	2026-09-17 03:06	67.25	OK
9633	2026-09-17 03:07	72.04	OK	9634	2026-09-17 03:08	68.80	OK
9635	2026-09-17 03:09	68.99	OK	9636	2026-09-17 03:10	69.78	OK
9637	2026-09-17 03:11	70.54	OK	9638	2026-09-17 03:12	69.96	OK
9639	2026-09-17 03:13	73.79	OK	9640	2026-09-17 03:14	71.82	OK
9641	2026-09-17 03:15	71.83	OK	9642	2026-09-17 03:16	71.15	OK
9643	2026-09-17 03:17	72.09	OK	9644	2026-09-17 03:18	70.45	OK
9645	2026-09-17 03:19	68.06	OK	9646	2026-09-17 03:20	70.46	OK
9647	2026-09-17 03:21	69.90	OK	9648	2026-09-17 03:22	74.44	OK
9649	2026-09-17 03:23	71.65	OK	9650	2026-09-17 03:24	73.86	OK
9651	2026-09-17 03:25	70.12	OK	9652	2026-09-17 03:26	72.04	OK
9653	2026-09-17 03:27	70.54	OK	9654	2026-09-17 03:28	72.74	OK
9655	2026-09-17 03:29	72.35	OK	9656	2026-09-17 03:30	74.41	OK
9657	2026-09-17 03:31	69.59	OK	9658	2026-09-17 03:32	72.29	OK
9659	2026-09-17 03:33	71.43	OK	9660	2026-09-17 03:34	68.88	OK
9661	2026-09-17 03:35	72.95	OK	9662	2026-09-17 03:36	73.47	OK
9663	2026-09-17 03:37	71.01	OK	9664	2026-09-17 03:38	72.17	OK
9665	2026-09-17 03:39	70.97	OK	9666	2026-09-17 03:40	72.80	OK
9667	2026-09-17 03:41	72.04	OK	9668	2026-09-17 03:42	72.03	OK
9669	2026-09-17 03:43	73.27	OK	9670	2026-09-17 03:44	73.82	OK
9671	2026-09-17 03:45	66.97	OK	9672	2026-09-17 03:46	71.55	OK
9673	2026-09-17 03:47	72.89	OK	9674	2026-09-17 03:48	69.78	OK
9675	2026-09-17 03:49	70.51	OK	9676	2026-09-17 03:50	72.57	OK
9677	2026-09-17 03:51	69.15	OK	9678	2026-09-17 03:52	70.10	OK
9679	2026-09-17 03:53	73.50	OK	9680	2026-09-17 03:54	69.62	OK
9681	2026-09-17 03:55	72.59	OK	9682	2026-09-17 03:56	72.53	OK
9683	2026-09-17 03:57	73.15	OK	9684	2026-09-17 03:58	70.84	OK
9685	2026-09-17 03:59	73.28	OK	9686	2026-09-17 04:00	73.91	OK
9687	2026-09-17 04:01	70.07	OK	9688	2026-09-17 04:02	70.22	OK
9689	2026-09-17 04:03	70.12	OK	9690	2026-09-17 04:04	70.82	OK
9691	2026-09-17 04:05	70.83	OK	9692	2026-09-17 04:06	68.66	OK
9693	2026-09-17 04:07	68.34	OK	9694	2026-09-17 04:08	71.48	OK
9695	2026-09-17 04:09	70.25	OK	9696	2026-09-17 04:10	70.10	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9697	2026-09-17 04:11	69.15	OK	9698	2026-09-17 04:12	71.22	OK
9699	2026-09-17 04:13	72.51	OK	9700	2026-09-17 04:14	70.25	OK
9701	2026-09-17 04:15	73.11	OK	9702	2026-09-17 04:16	73.26	OK
9703	2026-09-17 04:17	73.70	OK	9704	2026-09-17 04:18	69.53	OK
9705	2026-09-17 04:19	70.90	OK	9706	2026-09-17 04:20	70.70	OK
9707	2026-09-17 04:21	73.27	OK	9708	2026-09-17 04:22	72.90	OK
9709	2026-09-17 04:23	70.64	OK	9710	2026-09-17 04:24	72.31	OK
9711	2026-09-17 04:25	71.27	OK	9712	2026-09-17 04:26	68.13	OK
9713	2026-09-17 04:27	70.93	OK	9714	2026-09-17 04:28	73.82	OK
9715	2026-09-17 04:29	74.60	OK	9716	2026-09-17 04:30	69.08	OK
9717	2026-09-17 04:31	70.85	OK	9718	2026-09-17 04:32	76.02	OK
9719	2026-09-17 04:33	72.11	OK	9720	2026-09-17 04:34	73.49	OK
9721	2026-09-17 04:35	72.53	OK	9722	2026-09-17 04:36	73.78	OK
9723	2026-09-17 04:37	70.78	OK	9724	2026-09-17 04:38	75.24	OK
9725	2026-09-17 04:39	71.69	OK	9726	2026-09-17 04:40	74.09	OK
9727	2026-09-17 04:41	72.42	OK	9728	2026-09-17 04:42	71.85	OK
9729	2026-09-17 04:43	70.52	OK	9730	2026-09-17 04:44	70.69	OK
9731	2026-09-17 04:45	71.66	OK	9732	2026-09-17 04:46	70.81	OK
9733	2026-09-17 04:47	74.50	OK	9734	2026-09-17 04:48	70.38	OK
9735	2026-09-17 04:49	75.36	OK	9736	2026-09-17 04:50	72.59	OK
9737	2026-09-17 04:51	73.19	OK	9738	2026-09-17 04:52	69.58	OK
9739	2026-09-17 04:53	73.17	OK	9740	2026-09-17 04:54	69.41	OK
9741	2026-09-17 04:55	70.68	OK	9742	2026-09-17 04:56	73.86	OK
9743	2026-09-17 04:57	72.23	OK	9744	2026-09-17 04:58	70.16	OK
9745	2026-09-17 04:59	74.52	OK	9746	2026-09-17 05:00	71.55	OK
9747	2026-09-17 05:01	71.75	OK	9748	2026-09-17 05:02	70.78	OK
9749	2026-09-17 05:03	75.20	OK	9750	2026-09-17 05:04	72.98	OK
9751	2026-09-17 05:05	73.55	OK	9752	2026-09-17 05:06	74.48	OK
9753	2026-09-17 05:07	71.83	OK	9754	2026-09-17 05:08	70.75	OK
9755	2026-09-17 05:09	71.19	OK	9756	2026-09-17 05:10	70.67	OK
9757	2026-09-17 05:11	73.27	OK	9758	2026-09-17 05:12	73.70	OK
9759	2026-09-17 05:13	73.98	OK	9760	2026-09-17 05:14	69.65	OK
9761	2026-09-17 05:15	75.15	OK	9762	2026-09-17 05:16	71.38	OK
9763	2026-09-17 05:17	71.90	OK	9764	2026-09-17 05:18	71.76	OK
9765	2026-09-17 05:19	73.60	OK	9766	2026-09-17 05:20	73.63	OK
9767	2026-09-17 05:21	72.43	OK	9768	2026-09-17 05:22	73.91	OK
9769	2026-09-17 05:23	70.33	OK	9770	2026-09-17 05:24	70.17	OK
9771	2026-09-17 05:25	71.97	OK	9772	2026-09-17 05:26	71.36	OK
9773	2026-09-17 05:27	76.73	OK	9774	2026-09-17 05:28	71.78	OK
9775	2026-09-17 05:29	72.27	OK	9776	2026-09-17 05:30	71.32	OK
9777	2026-09-17 05:31	72.18	OK	9778	2026-09-17 05:32	72.47	OK
9779	2026-09-17 05:33	76.91	OK	9780	2026-09-17 05:34	73.25	OK
9781	2026-09-17 05:35	76.77	OK	9782	2026-09-17 05:36	73.15	OK
9783	2026-09-17 05:37	74.59	OK	9784	2026-09-17 05:38	74.76	OK
9785	2026-09-17 05:39	70.85	OK	9786	2026-09-17 05:40	71.73	OK
9787	2026-09-17 05:41	71.06	OK	9788	2026-09-17 05:42	73.06	OK
9789	2026-09-17 05:43	72.34	OK	9790	2026-09-17 05:44	72.33	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9791	2026-09-17 05:45	72.41	OK	9792	2026-09-17 05:46	73.49	OK
9793	2026-09-17 05:47	72.90	OK	9794	2026-09-17 05:48	71.09	OK
9795	2026-09-17 05:49	73.80	OK	9796	2026-09-17 05:50	74.02	OK
9797	2026-09-17 05:51	73.63	OK	9798	2026-09-17 05:52	72.17	OK
9799	2026-09-17 05:53	73.73	OK	9800	2026-09-17 05:54	74.41	OK
9801	2026-09-17 05:55	71.57	OK	9802	2026-09-17 05:56	75.09	OK
9803	2026-09-17 05:57	71.78	OK	9804	2026-09-17 05:58	71.66	OK
9805	2026-09-17 05:59	71.75	OK	9806	2026-09-17 06:00	71.23	OK
9807	2026-09-17 06:01	73.02	OK	9808	2026-09-17 06:02	69.91	OK
9809	2026-09-17 06:03	73.99	OK	9810	2026-09-17 06:04	75.27	OK
9811	2026-09-17 06:05	72.64	OK	9812	2026-09-17 06:06	73.83	OK
9813	2026-09-17 06:07	73.55	OK	9814	2026-09-17 06:08	75.97	OK
9815	2026-09-17 06:09	76.44	OK	9816	2026-09-17 06:10	73.18	OK
9817	2026-09-17 06:11	72.44	OK	9818	2026-09-17 06:12	75.63	OK
9819	2026-09-17 06:13	74.04	OK	9820	2026-09-17 06:14	75.10	OK
9821	2026-09-17 06:15	75.77	OK	9822	2026-09-17 06:16	72.58	OK
9823	2026-09-17 06:17	72.89	OK	9824	2026-09-17 06:18	73.54	OK
9825	2026-09-17 06:19	76.05	OK	9826	2026-09-17 06:20	74.92	OK
9827	2026-09-17 06:21	71.77	OK	9828	2026-09-17 06:22	74.68	OK
9829	2026-09-17 06:23	74.64	OK	9830	2026-09-17 06:24	73.77	OK
9831	2026-09-17 06:25	76.12	OK	9832	2026-09-17 06:26	73.55	OK
9833	2026-09-17 06:27	75.42	OK	9834	2026-09-17 06:28	72.87	OK
9835	2026-09-17 06:29	74.74	OK	9836	2026-09-17 06:30	73.99	OK
9837	2026-09-17 06:31	74.08	OK	9838	2026-09-17 06:32	73.06	OK
9839	2026-09-17 06:33	75.09	OK	9840	2026-09-17 06:34	75.34	OK
9841	2026-09-17 06:35	75.74	OK	9842	2026-09-17 06:36	73.60	OK
9843	2026-09-17 06:37	76.18	OK	9844	2026-09-17 06:38	76.28	OK
9845	2026-09-17 06:39	77.59	OK	9846	2026-09-17 06:40	74.81	OK
9847	2026-09-17 06:41	76.62	OK	9848	2026-09-17 06:42	74.39	OK
9849	2026-09-17 06:43	75.29	OK	9850	2026-09-17 06:44	73.11	OK
9851	2026-09-17 06:45	76.32	OK	9852	2026-09-17 06:46	75.53	OK
9853	2026-09-17 06:47	73.89	OK	9854	2026-09-17 06:48	77.16	OK
9855	2026-09-17 06:49	74.04	OK	9856	2026-09-17 06:50	77.00	OK
9857	2026-09-17 06:51	76.64	OK	9858	2026-09-17 06:52	75.50	OK
9859	2026-09-17 06:53	74.78	OK	9860	2026-09-17 06:54	74.02	OK
9861	2026-09-17 06:55	74.90	OK	9862	2026-09-17 06:56	74.71	OK
9863	2026-09-17 06:57	77.44	OK	9864	2026-09-17 06:58	74.10	OK
9865	2026-09-17 06:59	76.91	OK	9866	2026-09-17 07:00	72.73	OK
9867	2026-09-17 07:01	74.86	OK	9868	2026-09-17 07:02	76.05	OK
9869	2026-09-17 07:03	74.64	OK	9870	2026-09-17 07:04	75.19	OK
9871	2026-09-17 07:05	73.30	OK	9872	2026-09-17 07:06	76.47	OK
9873	2026-09-17 07:07	76.08	OK	9874	2026-09-17 07:08	76.30	OK
9875	2026-09-17 07:09	75.17	OK	9876	2026-09-17 07:10	78.09	OK
9877	2026-09-17 07:11	73.01	OK	9878	2026-09-17 07:12	76.85	OK
9879	2026-09-17 07:13	75.45	OK	9880	2026-09-17 07:14	78.50	OK
9881	2026-09-17 07:15	76.17	OK	9882	2026-09-17 07:16	74.58	OK
9883	2026-09-17 07:17	77.64	OK	9884	2026-09-17 07:18	74.43	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9885	2026-09-17 07:19	77.95	OK	9886	2026-09-17 07:20	77.85	OK
9887	2026-09-17 07:21	73.16	OK	9888	2026-09-17 07:22	75.56	OK
9889	2026-09-17 07:23	73.48	OK	9890	2026-09-17 07:24	75.90	OK
9891	2026-09-17 07:25	72.51	OK	9892	2026-09-17 07:26	77.95	OK
9893	2026-09-17 07:27	75.81	OK	9894	2026-09-17 07:28	77.08	OK
9895	2026-09-17 07:29	73.97	OK	9896	2026-09-17 07:30	77.54	OK
9897	2026-09-17 07:31	74.47	OK	9898	2026-09-17 07:32	79.22	OK
9899	2026-09-17 07:33	75.11	OK	9900	2026-09-17 07:34	74.27	OK
9901	2026-09-17 07:35	77.38	OK	9902	2026-09-17 07:36	76.76	OK
9903	2026-09-17 07:37	76.56	OK	9904	2026-09-17 07:38	74.20	OK
9905	2026-09-17 07:39	75.77	OK	9906	2026-09-17 07:40	75.95	OK
9907	2026-09-17 07:41	75.05	OK	9908	2026-09-17 07:42	74.83	OK
9909	2026-09-17 07:43	74.91	OK	9910	2026-09-17 07:44	76.36	OK
9911	2026-09-17 07:45	75.88	OK	9912	2026-09-17 07:46	77.93	OK
9913	2026-09-17 07:47	77.92	OK	9914	2026-09-17 07:48	77.61	OK
9915	2026-09-17 07:49	79.22	OK	9916	2026-09-17 07:50	78.02	OK
9917	2026-09-17 07:51	79.40	OK	9918	2026-09-17 07:52	78.49	OK
9919	2026-09-17 07:53	78.79	OK	9920	2026-09-17 07:54	76.63	OK
9921	2026-09-17 07:55	78.91	OK	9922	2026-09-17 07:56	74.52	OK
9923	2026-09-17 07:57	76.05	OK	9924	2026-09-17 07:58	76.68	OK
9925	2026-09-17 07:59	77.09	OK	9926	2026-09-17 08:00	77.59	OK
9927	2026-09-17 08:01	76.39	OK	9928	2026-09-17 08:02	75.13	OK
9929	2026-09-17 08:03	76.69	OK	9930	2026-09-17 08:04	75.77	OK
9931	2026-09-17 08:05	76.25	OK	9932	2026-09-17 08:06	76.48	OK
9933	2026-09-17 08:07	80.10	OK	9934	2026-09-17 08:08	78.81	OK
9935	2026-09-17 08:09	74.53	OK	9936	2026-09-17 08:10	78.66	OK
9937	2026-09-17 08:11	78.15	OK	9938	2026-09-17 08:12	75.92	OK
9939	2026-09-17 08:13	79.78	OK	9940	2026-09-17 08:14	74.06	OK
9941	2026-09-17 08:15	77.41	OK	9942	2026-09-17 08:16	76.60	OK
9943	2026-09-17 08:17	77.46	OK	9944	2026-09-17 08:18	79.14	OK
9945	2026-09-17 08:19	75.93	OK	9946	2026-09-17 08:20	79.52	OK
9947	2026-09-17 08:21	79.92	OK	9948	2026-09-17 08:22	76.65	OK
9949	2026-09-17 08:23	76.00	OK	9950	2026-09-17 08:24	76.11	OK
9951	2026-09-17 08:25	79.08	OK	9952	2026-09-17 08:26	74.95	OK
9953	2026-09-17 08:27	77.49	OK	9954	2026-09-17 08:28	78.11	OK
9955	2026-09-17 08:29	80.89	OK	9956	2026-09-17 08:30	81.15	OK
9957	2026-09-17 08:31	76.72	OK	9958	2026-09-17 08:32	77.31	OK
9959	2026-09-17 08:33	77.29	OK	9960	2026-09-17 08:34	78.31	OK
9961	2026-09-17 08:35	74.05	OK	9962	2026-09-17 08:36	78.18	OK
9963	2026-09-17 08:37	75.44	OK	9964	2026-09-17 08:38	76.40	OK
9965	2026-09-17 08:39	76.58	OK	9966	2026-09-17 08:40	78.00	OK
9967	2026-09-17 08:41	75.43	OK	9968	2026-09-17 08:42	79.21	OK
9969	2026-09-17 08:43	79.65	OK	9970	2026-09-17 08:44	79.56	OK
9971	2026-09-17 08:45	77.63	OK	9972	2026-09-17 08:46	78.74	OK
9973	2026-09-17 08:47	79.53	OK	9974	2026-09-17 08:48	78.26	OK
9975	2026-09-17 08:49	80.28	OK	9976	2026-09-17 08:50	78.45	OK
9977	2026-09-17 08:51	78.74	OK	9978	2026-09-17 08:52	76.97	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9979	2026-09-17 08:53	78.88	OK	9980	2026-09-17 08:54	75.47	OK
9981	2026-09-17 08:55	79.34	OK	9982	2026-09-17 08:56	78.30	OK
9983	2026-09-17 08:57	74.80	OK	9984	2026-09-17 08:58	78.12	OK
9985	2026-09-17 08:59	81.21	OK	9986	2026-09-17 09:00	79.53	OK
9987	2026-09-17 09:01	77.13	OK	9988	2026-09-17 09:02	80.15	OK
9989	2026-09-17 09:03	79.81	OK	9990	2026-09-17 09:04	77.98	OK
9991	2026-09-17 09:05	78.22	OK	9992	2026-09-17 09:06	78.81	OK
9993	2026-09-17 09:07	76.80	OK	9994	2026-09-17 09:08	79.79	OK
9995	2026-09-17 09:09	80.11	OK	9996	2026-09-17 09:10	76.46	OK
9997	2026-09-17 09:11	80.32	OK	9998	2026-09-17 09:12	78.20	OK
9999	2026-09-17 09:13	76.03	OK	10000	2026-09-17 09:14	77.02	OK
10001	2026-09-17 09:15	77.80	OK	10002	2026-09-17 09:16	77.28	OK
10003	2026-09-17 09:17	76.32	OK	10004	2026-09-17 09:18	75.14	OK
10005	2026-09-17 09:19	80.11	OK	10006	2026-09-17 09:20	80.58	OK
10007	2026-09-17 09:21	78.33	OK	10008	2026-09-17 09:22	78.78	OK
10009	2026-09-17 09:23	77.20	OK	10010	2026-09-17 09:24	77.93	OK
10011	2026-09-17 09:25	79.26	OK	10012	2026-09-17 09:26	80.13	OK
10013	2026-09-17 09:27	78.57	OK	10014	2026-09-17 09:28	80.26	OK
10015	2026-09-17 09:29	80.90	OK	10016	2026-09-17 09:30	79.45	OK
10017	2026-09-17 09:31	79.11	OK	10018	2026-09-17 09:32	78.25	OK
10019	2026-09-17 09:33	80.29	OK	10020	2026-09-17 09:34	79.30	OK
10021	2026-09-17 09:35	78.43	OK	10022	2026-09-17 09:36	79.33	OK
10023	2026-09-17 09:37	77.39	OK	10024	2026-09-17 09:38	78.72	OK
10025	2026-09-17 09:39	78.16	OK	10026	2026-09-17 09:40	82.01	OK
10027	2026-09-17 09:41	80.88	OK	10028	2026-09-17 09:42	77.21	OK
10029	2026-09-17 09:43	79.32	OK	10030	2026-09-17 09:44	80.01	OK
10031	2026-09-17 09:45	80.92	OK	10032	2026-09-17 09:46	76.71	OK
10033	2026-09-17 09:47	79.54	OK	10034	2026-09-17 09:48	80.96	OK
10035	2026-09-17 09:49	78.71	OK	10036	2026-09-17 09:50	76.63	OK
10037	2026-09-17 09:51	77.51	OK	10038	2026-09-17 09:52	80.22	OK
10039	2026-09-17 09:53	77.88	OK	10040	2026-09-17 09:54	81.22	OK
10041	2026-09-17 09:55	79.66	OK	10042	2026-09-17 09:56	80.63	OK
10043	2026-09-17 09:57	80.08	OK	10044	2026-09-17 09:58	81.53	OK
10045	2026-09-17 09:59	79.42	OK	10046	2026-09-17 10:00	79.11	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10047	2026-09-17 10:01	79.34	OK	10048	2026-09-17 10:02	80.98	OK
10049	2026-09-17 10:03	77.41	OK	10050	2026-09-17 10:04	82.33	OK
10051	2026-09-17 10:05	81.13	OK	10052	2026-09-17 10:06	78.85	OK
10053	2026-09-17 10:07	82.82	OK	10054	2026-09-17 10:08	79.71	OK
10055	2026-09-17 10:09	78.05	OK	10056	2026-09-17 10:10	78.87	OK
10057	2026-09-17 10:11	79.13	OK	10058	2026-09-17 10:12	79.12	OK
10059	2026-09-17 10:13	78.18	OK	10060	2026-09-17 10:14	80.69	OK
10061	2026-09-17 10:15	80.52	OK	10062	2026-09-17 10:16	80.65	OK
10063	2026-09-17 10:17	80.44	OK	10064	2026-09-17 10:18	79.21	OK
10065	2026-09-17 10:19	80.51	OK	10066	2026-09-17 10:20	79.64	OK
10067	2026-09-17 10:21	75.96	OK	10068	2026-09-17 10:22	80.64	OK
10069	2026-09-17 10:23	82.54	OK	10070	2026-09-17 10:24	78.61	OK
10071	2026-09-17 10:25	81.47	OK	10072	2026-09-17 10:26	78.80	OK
10073	2026-09-17 10:27	79.24	OK	10074	2026-09-17 10:28	78.67	OK
10075	2026-09-17 10:29	77.48	OK	10076	2026-09-17 10:30	81.82	OK
10077	2026-09-17 10:31	79.73	OK	10078	2026-09-17 10:32	80.58	OK
10079	2026-09-17 10:33	81.65	OK	10080	2026-09-17 10:34	81.48	OK
10081	2026-09-17 10:35	81.91	OK	10082	2026-09-17 10:36	81.74	OK
10083	2026-09-17 10:37	79.14	OK	10084	2026-09-17 10:38	76.20	OK
10085	2026-09-17 10:39	78.29	OK	10086	2026-09-17 10:40	83.24	OK
10087	2026-09-17 10:41	77.96	OK	10088	2026-09-17 10:42	77.61	OK
10089	2026-09-17 10:43	80.07	OK	10090	2026-09-17 10:44	78.74	OK
10091	2026-09-17 10:45	79.54	OK	10092	2026-09-17 10:46	78.80	OK
10093	2026-09-17 10:47	79.00	OK	10094	2026-09-17 10:48	81.13	OK
10095	2026-09-17 10:49	77.70	OK	10096	2026-09-17 10:50	82.31	OK
10097	2026-09-17 10:51	81.10	OK	10098	2026-09-17 10:52	80.26	OK
10099	2026-09-17 10:53	81.90	OK	10100	2026-09-17 10:54	80.17	OK
10101	2026-09-17 10:55	77.39	OK	10102	2026-09-17 10:56	80.41	OK
10103	2026-09-17 10:57	80.86	OK	10104	2026-09-17 10:58	78.41	OK
10105	2026-09-17 10:59	77.81	OK	10106	2026-09-17 11:00	78.43	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10107	2026-09-17 11:01	81.68	OK	10108	2026-09-17 11:02	77.83	OK
10109	2026-09-17 11:03	77.35	OK	10110	2026-09-17 11:04	80.20	OK
10111	2026-09-17 11:05	81.90	OK	10112	2026-09-17 11:06	81.02	OK
10113	2026-09-17 11:07	79.35	OK	10114	2026-09-17 11:08	76.79	OK
10115	2026-09-17 11:09	80.14	OK	10116	2026-09-17 11:10	81.45	OK
10117	2026-09-17 11:11	84.73	OK	10118	2026-09-17 11:12	80.69	OK
10119	2026-09-17 11:13	78.16	OK	10120	2026-09-17 11:14	81.49	OK
10121	2026-09-17 11:15	77.74	OK	10122	2026-09-17 11:16	79.37	OK
10123	2026-09-17 11:17	80.12	OK	10124	2026-09-17 11:18	79.84	OK
10125	2026-09-17 11:19	83.39	OK	10126	2026-09-17 11:20	79.55	OK
10127	2026-09-17 11:21	77.69	OK	10128	2026-09-17 11:22	81.40	OK
10129	2026-09-17 11:23	81.95	OK	10130	2026-09-17 11:24	77.07	OK
10131	2026-09-17 11:25	80.05	OK	10132	2026-09-17 11:26	80.72	OK
10133	2026-09-17 11:27	80.36	OK	10134	2026-09-17 11:28	81.56	OK
10135	2026-09-17 11:29	83.04	OK	10136	2026-09-17 11:30	83.12	OK
10137	2026-09-17 11:31	81.51	OK	10138	2026-09-17 11:32	80.48	OK
10139	2026-09-17 11:33	80.88	OK	10140	2026-09-17 11:34	82.75	OK
10141	2026-09-17 11:35	79.70	OK	10142	2026-09-17 11:36	80.59	OK
10143	2026-09-17 11:37	82.97	OK	10144	2026-09-17 11:38	80.54	OK
10145	2026-09-17 11:39	81.14	OK	10146	2026-09-17 11:40	80.72	OK
10147	2026-09-17 11:41	79.95	OK	10148	2026-09-17 11:42	80.03	OK
10149	2026-09-17 11:43	80.40	OK	10150	2026-09-17 11:44	80.12	OK
10151	2026-09-17 11:45	80.99	OK	10152	2026-09-17 11:46	80.03	OK
10153	2026-09-17 11:47	81.25	OK	10154	2026-09-17 11:48	79.01	OK
10155	2026-09-17 11:49	81.75	OK	10156	2026-09-17 11:50	77.63	OK
10157	2026-09-17 11:51	79.79	OK	10158	2026-09-17 11:52	80.30	OK
10159	2026-09-17 11:53	82.31	OK	10160	2026-09-17 11:54	76.90	OK
10161	2026-09-17 11:55	81.08	OK	10162	2026-09-17 11:56	80.21	OK
10163	2026-09-17 11:57	81.48	OK	10164	2026-09-17 11:58	81.34	OK
10165	2026-09-17 11:59	78.20	OK	10166	2026-09-17 12:00	81.99	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10167	2026-09-17 12:01	79.40	OK	10168	2026-09-17 12:02	82.05	OK
10169	2026-09-17 12:03	81.42	OK	10170	2026-09-17 12:04	77.30	OK
10171	2026-09-17 12:05	77.98	OK	10172	2026-09-17 12:06	82.86	OK
10173	2026-09-17 12:07	80.65	OK	10174	2026-09-17 12:08	80.63	OK
10175	2026-09-17 12:09	79.51	OK	10176	2026-09-17 12:10	82.85	OK
10177	2026-09-17 12:11	82.64	OK	10178	2026-09-17 12:12	79.28	OK
10179	2026-09-17 12:13	80.03	OK	10180	2026-09-17 12:14	82.09	OK
10181	2026-09-17 12:15	82.73	OK	10182	2026-09-17 12:16	80.03	OK
10183	2026-09-17 12:17	79.75	OK	10184	2026-09-17 12:18	81.65	OK
10185	2026-09-17 12:19	81.30	OK	10186	2026-09-17 12:20	79.05	OK
10187	2026-09-17 12:21	78.59	OK	10188	2026-09-17 12:22	81.24	OK
10189	2026-09-17 12:23	82.86	OK	10190	2026-09-17 12:24	77.21	OK
10191	2026-09-17 12:25	80.06	OK	10192	2026-09-17 12:26	78.70	OK
10193	2026-09-17 12:27	84.08	OK	10194	2026-09-17 12:28	82.03	OK
10195	2026-09-17 12:29	79.97	OK	10196	2026-09-17 12:30	81.57	OK
10197	2026-09-17 12:31	78.33	OK	10198	2026-09-17 12:32	81.45	OK
10199	2026-09-17 12:33	78.77	OK	10200	2026-09-17 12:34	82.11	OK
10201	2026-09-17 12:35	77.55	OK	10202	2026-09-17 12:36	81.91	OK
10203	2026-09-17 12:37	83.91	OK	10204	2026-09-17 12:38	80.76	OK
10205	2026-09-17 12:39	83.77	OK	10206	2026-09-17 12:40	79.11	OK
10207	2026-09-17 12:41	81.60	OK	10208	2026-09-17 12:42	79.07	OK
10209	2026-09-17 12:43	79.94	OK	10210	2026-09-17 12:44	80.80	OK
10211	2026-09-17 12:45	83.50	OK	10212	2026-09-17 12:46	79.95	OK
10213	2026-09-17 12:47	81.94	OK	10214	2026-09-17 12:48	81.79	OK
10215	2026-09-17 12:49	83.60	OK	10216	2026-09-17 12:50	80.74	OK
10217	2026-09-17 12:51	80.94	OK	10218	2026-09-17 12:52	80.53	OK
10219	2026-09-17 12:53	81.06	OK	10220	2026-09-17 12:54	82.25	OK
10221	2026-09-17 12:55	79.06	OK	10222	2026-09-17 12:56	80.56	OK
10223	2026-09-17 12:57	80.38	OK	10224	2026-09-17 12:58	82.22	OK
10225	2026-09-17 12:59	82.26	OK	10226	2026-09-17 13:00	80.06	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10227	2026-09-17 13:01	79.47	OK	10228	2026-09-17 13:02	78.06	OK
10229	2026-09-17 13:03	82.34	OK	10230	2026-09-17 13:04	80.57	OK
10231	2026-09-17 13:05	78.32	OK	10232	2026-09-17 13:06	80.23	OK
10233	2026-09-17 13:07	82.68	OK	10234	2026-09-17 13:08	82.72	OK
10235	2026-09-17 13:09	80.94	OK	10236	2026-09-17 13:10	78.11	OK
10237	2026-09-17 13:11	78.16	OK	10238	2026-09-17 13:12	78.01	OK
10239	2026-09-17 13:13	79.84	OK	10240	2026-09-17 13:14	82.46	OK
10241	2026-09-17 13:15	79.58	OK	10242	2026-09-17 13:16	82.66	OK
10243	2026-09-17 13:17	82.90	OK	10244	2026-09-17 13:18	84.03	OK
10245	2026-09-17 13:19	77.82	OK	10246	2026-09-17 13:20	81.58	OK
10247	2026-09-17 13:21	81.96	OK	10248	2026-09-17 13:22	82.44	OK
10249	2026-09-17 13:23	80.21	OK	10250	2026-09-17 13:24	80.06	OK
10251	2026-09-17 13:25	80.89	OK	10252	2026-09-17 13:26	82.12	OK
10253	2026-09-17 13:27	82.43	OK	10254	2026-09-17 13:28	82.63	OK
10255	2026-09-17 13:29	80.76	OK	10256	2026-09-17 13:30	82.59	OK
10257	2026-09-17 13:31	79.44	OK	10258	2026-09-17 13:32	79.71	OK
10259	2026-09-17 13:33	78.41	OK	10260	2026-09-17 13:34	80.49	OK
10261	2026-09-17 13:35	77.97	OK	10262	2026-09-17 13:36	81.07	OK
10263	2026-09-17 13:37	82.84	OK	10264	2026-09-17 13:38	78.36	OK
10265	2026-09-17 13:39	82.43	OK	10266	2026-09-17 13:40	83.03	OK
10267	2026-09-17 13:41	81.91	OK	10268	2026-09-17 13:42	81.80	OK
10269	2026-09-17 13:43	84.10	OK	10270	2026-09-17 13:44	79.99	OK
10271	2026-09-17 13:45	78.89	OK	10272	2026-09-17 13:46	78.63	OK
10273	2026-09-17 13:47	80.67	OK	10274	2026-09-17 13:48	79.97	OK
10275	2026-09-17 13:49	83.07	OK	10276	2026-09-17 13:50	84.20	OK
10277	2026-09-17 13:51	83.27	OK	10278	2026-09-17 13:52	84.36	OK
10279	2026-09-17 13:53	80.68	OK	10280	2026-09-17 13:54	80.19	OK
10281	2026-09-17 13:55	85.07	OK	10282	2026-09-17 13:56	83.67	OK
10283	2026-09-17 13:57	79.17	OK	10284	2026-09-17 13:58	81.46	OK
10285	2026-09-17 13:59	79.64	OK	10286	2026-09-17 14:00	79.99	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10287	2026-09-17 14:01	80.07	OK	10288	2026-09-17 14:02	81.04	OK
10289	2026-09-17 14:03	79.07	OK	10290	2026-09-17 14:04	80.25	OK
10291	2026-09-17 14:05	80.59	OK	10292	2026-09-17 14:06	79.76	OK
10293	2026-09-17 14:07	78.47	OK	10294	2026-09-17 14:08	78.28	OK
10295	2026-09-17 14:09	79.04	OK	10296	2026-09-17 14:10	83.04	OK
10297	2026-09-17 14:11	81.44	OK	10298	2026-09-17 14:12	84.21	OK
10299	2026-09-17 14:13	82.02	OK	10300	2026-09-17 14:14	80.08	OK
10301	2026-09-17 14:15	80.33	OK	10302	2026-09-17 14:16	82.12	OK
10303	2026-09-17 14:17	78.93	OK	10304	2026-09-17 14:18	78.71	OK
10305	2026-09-17 14:19	81.95	OK	10306	2026-09-17 14:20	81.05	OK
10307	2026-09-17 14:21	83.26	OK	10308	2026-09-17 14:22	80.52	OK
10309	2026-09-17 14:23	81.45	OK	10310	2026-09-17 14:24	82.31	OK
10311	2026-09-17 14:25	80.04	OK	10312	2026-09-17 14:26	84.81	OK
10313	2026-09-17 14:27	82.25	OK	10314	2026-09-17 14:28	79.67	OK
10315	2026-09-17 14:29	80.28	OK	10316	2026-09-17 14:30	78.90	OK
10317	2026-09-17 14:31	76.60	OK	10318	2026-09-17 14:32	83.04	OK
10319	2026-09-17 14:33	83.71	OK	10320	2026-09-17 14:34	80.44	OK
10321	2026-09-17 14:35	77.55	OK	10322	2026-09-17 14:36	81.18	OK
10323	2026-09-17 14:37	78.43	OK	10324	2026-09-17 14:38	80.73	OK
10325	2026-09-17 14:39	82.06	OK	10326	2026-09-17 14:40	78.09	OK
10327	2026-09-17 14:41	80.30	OK	10328	2026-09-17 14:42	82.96	OK
10329	2026-09-17 14:43	82.85	OK	10330	2026-09-17 14:44	80.56	OK
10331	2026-09-17 14:45	80.77	OK	10332	2026-09-17 14:46	80.93	OK
10333	2026-09-17 14:47	81.21	OK	10334	2026-09-17 14:48	84.45	OK
10335	2026-09-17 14:49	80.66	OK	10336	2026-09-17 14:50	80.09	OK
10337	2026-09-17 14:51	78.49	OK	10338	2026-09-17 14:52	81.70	OK
10339	2026-09-17 14:53	81.19	OK	10340	2026-09-17 14:54	82.75	OK
10341	2026-09-17 14:55	78.35	OK	10342	2026-09-17 14:56	81.94	OK
10343	2026-09-17 14:57	78.74	OK	10344	2026-09-17 14:58	78.00	OK
10345	2026-09-17 14:59	80.02	OK	10346	2026-09-17 15:00	80.96	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10347	2026-09-17 15:01	79.69	OK	10348	2026-09-17 15:02	80.40	OK
10349	2026-09-17 15:03	78.49	OK	10350	2026-09-17 15:04	81.50	OK
10351	2026-09-17 15:05	82.08	OK	10352	2026-09-17 15:06	77.22	OK
10353	2026-09-17 15:07	82.03	OK	10354	2026-09-17 15:08	79.12	OK
10355	2026-09-17 15:09	80.17	OK	10356	2026-09-17 15:10	78.92	OK
10357	2026-09-17 15:11	78.98	OK	10358	2026-09-17 15:12	81.54	OK
10359	2026-09-17 15:13	80.28	OK	10360	2026-09-17 15:14	78.72	OK
10361	2026-09-17 15:15	80.72	OK	10362	2026-09-17 15:16	75.87	OK
10363	2026-09-17 15:17	79.24	OK	10364	2026-09-17 15:18	79.54	OK
10365	2026-09-17 15:19	83.29	OK	10366	2026-09-17 15:20	82.94	OK
10367	2026-09-17 15:21	77.61	OK	10368	2026-09-17 15:22	83.27	OK
10369	2026-09-17 15:23	79.97	OK	10370	2026-09-17 15:24	76.36	OK
10371	2026-09-17 15:25	79.98	OK	10372	2026-09-17 15:26	80.52	OK
10373	2026-09-17 15:27	80.19	OK	10374	2026-09-17 15:28	79.46	OK
10375	2026-09-17 15:29	77.74	OK	10376	2026-09-17 15:30	78.52	OK
10377	2026-09-17 15:31	79.08	OK	10378	2026-09-17 15:32	83.21	OK
10379	2026-09-17 15:33	79.58	OK	10380	2026-09-17 15:34	78.11	OK
10381	2026-09-17 15:35	76.46	OK	10382	2026-09-17 15:36	77.95	OK
10383	2026-09-17 15:37	78.73	OK	10384	2026-09-17 15:38	80.69	OK
10385	2026-09-17 15:39	81.21	OK	10386	2026-09-17 15:40	80.69	OK
10387	2026-09-17 15:41	82.13	OK	10388	2026-09-17 15:42	80.15	OK
10389	2026-09-17 15:43	79.11	OK	10390	2026-09-17 15:44	83.67	OK
10391	2026-09-17 15:45	80.67	OK	10392	2026-09-17 15:46	82.10	OK
10393	2026-09-17 15:47	79.40	OK	10394	2026-09-17 15:48	78.44	OK
10395	2026-09-17 15:49	80.46	OK	10396	2026-09-17 15:50	79.41	OK
10397	2026-09-17 15:51	78.73	OK	10398	2026-09-17 15:52	79.28	OK
10399	2026-09-17 15:53	77.81	OK	10400	2026-09-17 15:54	78.94	OK
10401	2026-09-17 15:55	79.30	OK	10402	2026-09-17 15:56	79.84	OK
10403	2026-09-17 15:57	78.51	OK	10404	2026-09-17 15:58	81.17	OK
10405	2026-09-17 15:59	80.83	OK	10406	2026-09-17 16:00	80.85	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10407	2026-09-17 16:01	80.54	OK	10408	2026-09-17 16:02	79.17	OK
10409	2026-09-17 16:03	79.29	OK	10410	2026-09-17 16:04	76.70	OK
10411	2026-09-17 16:05	80.10	OK	10412	2026-09-17 16:06	79.40	OK
10413	2026-09-17 16:07	81.12	OK	10414	2026-09-17 16:08	79.44	OK
10415	2026-09-17 16:09	76.98	OK	10416	2026-09-17 16:10	78.76	OK
10417	2026-09-17 16:11	78.43	OK	10418	2026-09-17 16:12	78.65	OK
10419	2026-09-17 16:13	76.42	OK	10420	2026-09-17 16:14	80.27	OK
10421	2026-09-17 16:15	80.81	OK	10422	2026-09-17 16:16	81.42	OK
10423	2026-09-17 16:17	79.73	OK	10424	2026-09-17 16:18	77.00	OK
10425	2026-09-17 16:19	82.27	OK	10426	2026-09-17 16:20	81.01	OK
10427	2026-09-17 16:21	79.06	OK	10428	2026-09-17 16:22	77.76	OK
10429	2026-09-17 16:23	80.94	OK	10430	2026-09-17 16:24	74.86	OK
10431	2026-09-17 16:25	75.29	OK	10432	2026-09-17 16:26	78.56	OK
10433	2026-09-17 16:27	79.78	OK	10434	2026-09-17 16:28	76.40	OK
10435	2026-09-17 16:29	77.35	OK	10436	2026-09-17 16:30	78.36	OK
10437	2026-09-17 16:31	78.80	OK	10438	2026-09-17 16:32	79.60	OK
10439	2026-09-17 16:33	78.54	OK	10440	2026-09-17 16:34	78.60	OK
10441	2026-09-17 16:35	77.61	OK	10442	2026-09-17 16:36	77.79	OK
10443	2026-09-17 16:37	80.45	OK	10444	2026-09-17 16:38	79.05	OK
10445	2026-09-17 16:39	75.88	OK	10446	2026-09-17 16:40	78.56	OK
10447	2026-09-17 16:41	75.83	OK	10448	2026-09-17 16:42	77.30	OK
10449	2026-09-17 16:43	76.89	OK	10450	2026-09-17 16:44	75.98	OK
10451	2026-09-17 16:45	80.04	OK	10452	2026-09-17 16:46	79.30	OK
10453	2026-09-17 16:47	75.87	OK	10454	2026-09-17 16:48	76.94	OK
10455	2026-09-17 16:49	78.36	OK	10456	2026-09-17 16:50	80.30	OK
10457	2026-09-17 16:51	77.18	OK	10458	2026-09-17 16:52	79.41	OK
10459	2026-09-17 16:53	76.61	OK	10460	2026-09-17 16:54	80.99	OK
10461	2026-09-17 16:55	79.07	OK	10462	2026-09-17 16:56	77.03	OK
10463	2026-09-17 16:57	78.90	OK	10464	2026-09-17 16:58	75.56	OK
10465	2026-09-17 16:59	78.19	OK	10466	2026-09-17 17:00	78.70	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10467	2026-09-17 17:01	76.01	OK	10468	2026-09-17 17:02	75.54	OK
10469	2026-09-17 17:03	77.46	OK	10470	2026-09-17 17:04	76.73	OK
10471	2026-09-17 17:05	77.65	OK	10472	2026-09-17 17:06	76.84	OK
10473	2026-09-17 17:07	77.01	OK	10474	2026-09-17 17:08	78.85	OK
10475	2026-09-17 17:09	78.37	OK	10476	2026-09-17 17:10	79.37	OK
10477	2026-09-17 17:11	79.45	OK	10478	2026-09-17 17:12	78.91	OK
10479	2026-09-17 17:13	79.96	OK	10480	2026-09-17 17:14	74.27	OK
10481	2026-09-17 17:15	77.06	OK	10482	2026-09-17 17:16	78.88	OK
10483	2026-09-17 17:17	76.55	OK	10484	2026-09-17 17:18	76.45	OK
10485	2026-09-17 17:19	79.76	OK	10486	2026-09-17 17:20	81.27	OK
10487	2026-09-17 17:21	76.90	OK	10488	2026-09-17 17:22	78.32	OK
10489	2026-09-17 17:23	75.20	OK	10490	2026-09-17 17:24	74.09	OK
10491	2026-09-17 17:25	76.52	OK	10492	2026-09-17 17:26	76.32	OK
10493	2026-09-17 17:27	75.33	OK	10494	2026-09-17 17:28	76.55	OK
10495	2026-09-17 17:29	77.90	OK	10496	2026-09-17 17:30	78.02	OK
10497	2026-09-17 17:31	75.63	OK	10498	2026-09-17 17:32	79.74	OK
10499	2026-09-17 17:33	78.73	OK	10500	2026-09-17 17:34	76.90	OK
10501	2026-09-17 17:35	78.04	OK	10502	2026-09-17 17:36	74.41	OK
10503	2026-09-17 17:37	80.64	OK	10504	2026-09-17 17:38	76.32	OK
10505	2026-09-17 17:39	77.22	OK	10506	2026-09-17 17:40	76.18	OK
10507	2026-09-17 17:41	80.26	OK	10508	2026-09-17 17:42	76.71	OK
10509	2026-09-17 17:43	74.94	OK	10510	2026-09-17 17:44	77.56	OK
10511	2026-09-17 17:45	76.78	OK	10512	2026-09-17 17:46	78.05	OK
10513	2026-09-17 17:47	79.50	OK	10514	2026-09-17 17:48	76.23	OK
10515	2026-09-17 17:49	77.10	OK	10516	2026-09-17 17:50	76.01	OK
10517	2026-09-17 17:51	75.36	OK	10518	2026-09-17 17:52	78.91	OK
10519	2026-09-17 17:53	74.47	OK	10520	2026-09-17 17:54	73.98	OK
10521	2026-09-17 17:55	76.32	OK	10522	2026-09-17 17:56	78.56	OK
10523	2026-09-17 17:57	79.53	OK	10524	2026-09-17 17:58	75.35	OK
10525	2026-09-17 17:59	76.82	OK	10526	2026-09-17 18:00	75.79	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10527	2026-09-17 18:01	79.39	OK	10528	2026-09-17 18:02	75.27	OK
10529	2026-09-17 18:03	75.76	OK	10530	2026-09-17 18:04	75.89	OK
10531	2026-09-17 18:05	79.54	OK	10532	2026-09-17 18:06	77.52	OK
10533	2026-09-17 18:07	77.67	OK	10534	2026-09-17 18:08	74.02	OK
10535	2026-09-17 18:09	78.35	OK	10536	2026-09-17 18:10	77.09	OK
10537	2026-09-17 18:11	76.02	OK	10538	2026-09-17 18:12	75.58	OK
10539	2026-09-17 18:13	73.98	OK	10540	2026-09-17 18:14	76.49	OK
10541	2026-09-17 18:15	78.30	OK	10542	2026-09-17 18:16	78.82	OK
10543	2026-09-17 18:17	73.93	OK	10544	2026-09-17 18:18	73.38	OK
10545	2026-09-17 18:19	74.45	OK	10546	2026-09-17 18:20	77.77	OK
10547	2026-09-17 18:21	73.62	OK	10548	2026-09-17 18:22	79.04	OK
10549	2026-09-17 18:23	75.71	OK	10550	2026-09-17 18:24	74.25	OK
10551	2026-09-17 18:25	75.96	OK	10552	2026-09-17 18:26	73.01	OK
10553	2026-09-17 18:27	74.95	OK	10554	2026-09-17 18:28	74.72	OK
10555	2026-09-17 18:29	75.08	OK	10556	2026-09-17 18:30	74.24	OK
10557	2026-09-17 18:31	76.13	OK	10558	2026-09-17 18:32	76.70	OK
10559	2026-09-17 18:33	76.45	OK	10560	2026-09-17 18:34	76.57	OK
10561	2026-09-17 18:35	74.25	OK	10562	2026-09-17 18:36	76.10	OK
10563	2026-09-17 18:37	78.10	OK	10564	2026-09-17 18:38	76.16	OK
10565	2026-09-17 18:39	72.34	OK	10566	2026-09-17 18:40	74.39	OK
10567	2026-09-17 18:41	74.66	OK	10568	2026-09-17 18:42	72.83	OK
10569	2026-09-17 18:43	74.73	OK	10570	2026-09-17 18:44	76.35	OK
10571	2026-09-17 18:45	74.08	OK	10572	2026-09-17 18:46	78.60	OK
10573	2026-09-17 18:47	72.12	OK	10574	2026-09-17 18:48	78.44	OK
10575	2026-09-17 18:49	72.57	OK	10576	2026-09-17 18:50	74.66	OK
10577	2026-09-17 18:51	76.75	OK	10578	2026-09-17 18:52	76.16	OK
10579	2026-09-17 18:53	76.00	OK	10580	2026-09-17 18:54	73.89	OK
10581	2026-09-17 18:55	74.74	OK	10582	2026-09-17 18:56	75.03	OK
10583	2026-09-17 18:57	77.92	OK	10584	2026-09-17 18:58	77.98	OK
10585	2026-09-17 18:59	76.11	OK	10586	2026-09-17 19:00	76.61	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10587	2026-09-17 19:01	77.15	OK	10588	2026-09-17 19:02	74.87	OK
10589	2026-09-17 19:03	74.00	OK	10590	2026-09-17 19:04	74.28	OK
10591	2026-09-17 19:05	73.06	OK	10592	2026-09-17 19:06	75.78	OK
10593	2026-09-17 19:07	78.25	OK	10594	2026-09-17 19:08	73.23	OK
10595	2026-09-17 19:09	75.90	OK	10596	2026-09-17 19:10	75.56	OK
10597	2026-09-17 19:11	74.12	OK	10598	2026-09-17 19:12	74.39	OK
10599	2026-09-17 19:13	77.29	OK	10600	2026-09-17 19:14	76.22	OK
10601	2026-09-17 19:15	74.79	OK	10602	2026-09-17 19:16	73.77	OK
10603	2026-09-17 19:17	72.12	OK	10604	2026-09-17 19:18	78.03	OK
10605	2026-09-17 19:19	74.17	OK	10606	2026-09-17 19:20	74.88	OK
10607	2026-09-17 19:21	72.08	OK	10608	2026-09-17 19:22	74.94	OK
10609	2026-09-17 19:23	77.00	OK	10610	2026-09-17 19:24	78.30	OK
10611	2026-09-17 19:25	75.36	OK	10612	2026-09-17 19:26	74.34	OK
10613	2026-09-17 19:27	73.89	OK	10614	2026-09-17 19:28	75.24	OK
10615	2026-09-17 19:29	74.00	OK	10616	2026-09-17 19:30	76.80	OK
10617	2026-09-17 19:31	71.74	OK	10618	2026-09-17 19:32	75.25	OK
10619	2026-09-17 19:33	74.83	OK	10620	2026-09-17 19:34	75.70	OK
10621	2026-09-17 19:35	71.41	OK	10622	2026-09-17 19:36	75.21	OK
10623	2026-09-17 19:37	72.95	OK	10624	2026-09-17 19:38	73.20	OK
10625	2026-09-17 19:39	73.93	OK	10626	2026-09-17 19:40	76.54	OK
10627	2026-09-17 19:41	75.63	OK	10628	2026-09-17 19:42	72.19	OK
10629	2026-09-17 19:43	73.80	OK	10630	2026-09-17 19:44	73.70	OK
10631	2026-09-17 19:45	74.32	OK	10632	2026-09-17 19:46	73.33	OK
10633	2026-09-17 19:47	74.94	OK	10634	2026-09-17 19:48	76.05	OK
10635	2026-09-17 19:49	73.66	OK	10636	2026-09-17 19:50	76.11	OK
10637	2026-09-17 19:51	77.72	OK	10638	2026-09-17 19:52	74.01	OK
10639	2026-09-17 19:53	73.31	OK	10640	2026-09-17 19:54	71.64	OK
10641	2026-09-17 19:55	73.50	OK	10642	2026-09-17 19:56	72.84	OK
10643	2026-09-17 19:57	76.45	OK	10644	2026-09-17 19:58	74.50	OK
10645	2026-09-17 19:59	72.19	OK	10646	2026-09-17 20:00	73.76	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10647	2026-09-17 20:01	74.44	OK	10648	2026-09-17 20:02	72.74	OK
10649	2026-09-17 20:03	72.67	OK	10650	2026-09-17 20:04	75.53	OK
10651	2026-09-17 20:05	72.30	OK	10652	2026-09-17 20:06	72.92	OK
10653	2026-09-17 20:07	74.38	OK	10654	2026-09-17 20:08	70.82	OK
10655	2026-09-17 20:09	72.15	OK	10656	2026-09-17 20:10	74.37	OK
10657	2026-09-17 20:11	69.80	OK	10658	2026-09-17 20:12	72.58	OK
10659	2026-09-17 20:13	71.89	OK	10660	2026-09-17 20:14	71.45	OK
10661	2026-09-17 20:15	75.97	OK	10662	2026-09-17 20:16	72.53	OK
10663	2026-09-17 20:17	76.16	OK	10664	2026-09-17 20:18	74.90	OK
10665	2026-09-17 20:19	71.58	OK	10666	2026-09-17 20:20	73.83	OK
10667	2026-09-17 20:21	71.04	OK	10668	2026-09-17 20:22	68.61	OK
10669	2026-09-17 20:23	71.87	OK	10670	2026-09-17 20:24	72.03	OK
10671	2026-09-17 20:25	74.28	OK	10672	2026-09-17 20:26	72.31	OK
10673	2026-09-17 20:27	71.44	OK	10674	2026-09-17 20:28	73.12	OK
10675	2026-09-17 20:29	74.46	OK	10676	2026-09-17 20:30	72.90	OK
10677	2026-09-17 20:31	71.76	OK	10678	2026-09-17 20:32	71.50	OK
10679	2026-09-17 20:33	71.13	OK	10680	2026-09-17 20:34	74.73	OK
10681	2026-09-17 20:35	75.38	OK	10682	2026-09-17 20:36	69.64	OK
10683	2026-09-17 20:37	70.13	OK	10684	2026-09-17 20:38	73.03	OK
10685	2026-09-17 20:39	74.63	OK	10686	2026-09-17 20:40	74.44	OK
10687	2026-09-17 20:41	75.47	OK	10688	2026-09-17 20:42	74.21	OK
10689	2026-09-17 20:43	71.93	OK	10690	2026-09-17 20:44	70.20	OK
10691	2026-09-17 20:45	72.65	OK	10692	2026-09-17 20:46	70.12	OK
10693	2026-09-17 20:47	74.05	OK	10694	2026-09-17 20:48	72.19	OK
10695	2026-09-17 20:49	73.81	OK	10696	2026-09-17 20:50	73.31	OK
10697	2026-09-17 20:51	73.85	OK	10698	2026-09-17 20:52	74.13	OK
10699	2026-09-17 20:53	73.56	OK	10700	2026-09-17 20:54	74.19	OK
10701	2026-09-17 20:55	71.86	OK	10702	2026-09-17 20:56	72.71	OK
10703	2026-09-17 20:57	72.14	OK	10704	2026-09-17 20:58	70.32	OK
10705	2026-09-17 20:59	74.78	OK	10706	2026-09-17 21:00	70.85	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10707	2026-09-17 21:01	72.78	OK	10708	2026-09-17 21:02	73.18	OK
10709	2026-09-17 21:03	70.55	OK	10710	2026-09-17 21:04	74.47	OK
10711	2026-09-17 21:05	74.60	OK	10712	2026-09-17 21:06	71.28	OK
10713	2026-09-17 21:07	73.53	OK	10714	2026-09-17 21:08	74.41	OK
10715	2026-09-17 21:09	69.71	OK	10716	2026-09-17 21:10	71.93	OK
10717	2026-09-17 21:11	72.06	OK	10718	2026-09-17 21:12	74.43	OK
10719	2026-09-17 21:13	72.54	OK	10720	2026-09-17 21:14	75.43	OK
10721	2026-09-17 21:15	71.82	OK	10722	2026-09-17 21:16	70.62	OK
10723	2026-09-17 21:17	69.36	OK	10724	2026-09-17 21:18	67.96	OK
10725	2026-09-17 21:19	75.36	OK	10726	2026-09-17 21:20	71.60	OK
10727	2026-09-17 21:21	73.88	OK	10728	2026-09-17 21:22	74.30	OK
10729	2026-09-17 21:23	72.38	OK	10730	2026-09-17 21:24	71.26	OK
10731	2026-09-17 21:25	73.64	OK	10732	2026-09-17 21:26	72.80	OK
10733	2026-09-17 21:27	73.80	OK	10734	2026-09-17 21:28	69.58	OK
10735	2026-09-17 21:29	71.17	OK	10736	2026-09-17 21:30	71.94	OK
10737	2026-09-17 21:31	69.54	OK	10738	2026-09-17 21:32	73.80	OK
10739	2026-09-17 21:33	74.91	OK	10740	2026-09-17 21:34	69.51	OK
10741	2026-09-17 21:35	72.39	OK	10742	2026-09-17 21:36	70.07	OK
10743	2026-09-17 21:37	69.24	OK	10744	2026-09-17 21:38	69.27	OK
10745	2026-09-17 21:39	70.96	OK	10746	2026-09-17 21:40	70.30	OK
10747	2026-09-17 21:41	71.10	OK	10748	2026-09-17 21:42	68.26	OK
10749	2026-09-17 21:43	70.18	OK	10750	2026-09-17 21:44	70.19	OK
10751	2026-09-17 21:45	74.02	OK	10752	2026-09-17 21:46	71.64	OK
10753	2026-09-17 21:47	70.65	OK	10754	2026-09-17 21:48	73.65	OK
10755	2026-09-17 21:49	70.94	OK	10756	2026-09-17 21:50	73.87	OK
10757	2026-09-17 21:51	70.77	OK	10758	2026-09-17 21:52	68.85	OK
10759	2026-09-17 21:53	68.79	OK	10760	2026-09-17 21:54	69.78	OK
10761	2026-09-17 21:55	73.36	OK	10762	2026-09-17 21:56	69.27	OK
10763	2026-09-17 21:57	72.12	OK	10764	2026-09-17 21:58	67.45	OK
10765	2026-09-17 21:59	69.13	OK	10766	2026-09-17 22:00	71.20	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10767	2026-09-17 22:01	71.13	OK	10768	2026-09-17 22:02	69.04	OK
10769	2026-09-17 22:03	71.67	OK	10770	2026-09-17 22:04	70.26	OK
10771	2026-09-17 22:05	72.50	OK	10772	2026-09-17 22:06	70.70	OK
10773	2026-09-17 22:07	69.09	OK	10774	2026-09-17 22:08	73.80	OK
10775	2026-09-17 22:09	69.60	OK	10776	2026-09-17 22:10	68.70	OK
10777	2026-09-17 22:11	70.37	OK	10778	2026-09-17 22:12	70.61	OK
10779	2026-09-17 22:13	69.48	OK	10780	2026-09-17 22:14	68.51	OK
10781	2026-09-17 22:15	70.77	OK	10782	2026-09-17 22:16	72.79	OK
10783	2026-09-17 22:17	70.80	OK	10784	2026-09-17 22:18	72.39	OK
10785	2026-09-17 22:19	71.52	OK	10786	2026-09-17 22:20	71.67	OK
10787	2026-09-17 22:21	70.96	OK	10788	2026-09-17 22:22	72.94	OK
10789	2026-09-17 22:23	70.47	OK	10790	2026-09-17 22:24	70.00	OK
10791	2026-09-17 22:25	70.94	OK	10792	2026-09-17 22:26	72.50	OK
10793	2026-09-17 22:27	71.68	OK	10794	2026-09-17 22:28	70.58	OK
10795	2026-09-17 22:29	67.79	OK	10796	2026-09-17 22:30	70.74	OK
10797	2026-09-17 22:31	67.00	OK	10798	2026-09-17 22:32	68.06	OK
10799	2026-09-17 22:33	72.42	OK	10800	2026-09-17 22:34	73.28	OK
10801	2026-09-17 22:35	69.55	OK	10802	2026-09-17 22:36	70.85	OK
10803	2026-09-17 22:37	72.59	OK	10804	2026-09-17 22:38	71.28	OK
10805	2026-09-17 22:39	72.32	OK	10806	2026-09-17 22:40	72.68	OK
10807	2026-09-17 22:41	71.52	OK	10808	2026-09-17 22:42	69.71	OK
10809	2026-09-17 22:43	71.62	OK	10810	2026-09-17 22:44	68.54	OK
10811	2026-09-17 22:45	69.85	OK	10812	2026-09-17 22:46	67.91	OK
10813	2026-09-17 22:47	69.82	OK	10814	2026-09-17 22:48	67.78	OK
10815	2026-09-17 22:49	69.32	OK	10816	2026-09-17 22:50	70.67	OK
10817	2026-09-17 22:51	72.54	OK	10818	2026-09-17 22:52	67.94	OK
10819	2026-09-17 22:53	71.62	OK	10820	2026-09-17 22:54	69.32	OK
10821	2026-09-17 22:55	68.70	OK	10822	2026-09-17 22:56	71.20	OK
10823	2026-09-17 22:57	69.75	OK	10824	2026-09-17 22:58	71.35	OK
10825	2026-09-17 22:59	68.86	OK	10826	2026-09-17 23:00	70.73	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10827	2026-09-17 23:01	68.75	OK	10828	2026-09-17 23:02	69.81	OK
10829	2026-09-17 23:03	71.11	OK	10830	2026-09-17 23:04	71.14	OK
10831	2026-09-17 23:05	72.64	OK	10832	2026-09-17 23:06	70.43	OK
10833	2026-09-17 23:07	68.68	OK	10834	2026-09-17 23:08	70.71	OK
10835	2026-09-17 23:09	70.56	OK	10836	2026-09-17 23:10	68.90	OK
10837	2026-09-17 23:11	73.28	OK	10838	2026-09-17 23:12	70.37	OK
10839	2026-09-17 23:13	70.32	OK	10840	2026-09-17 23:14	65.37	OK
10841	2026-09-17 23:15	67.25	OK	10842	2026-09-17 23:16	69.92	OK
10843	2026-09-17 23:17	69.20	OK	10844	2026-09-17 23:18	73.01	OK
10845	2026-09-17 23:19	70.21	OK	10846	2026-09-17 23:20	72.12	OK
10847	2026-09-17 23:21	68.55	OK	10848	2026-09-17 23:22	70.56	OK
10849	2026-09-17 23:23	69.67	OK	10850	2026-09-17 23:24	70.53	OK
10851	2026-09-17 23:25	68.38	OK	10852	2026-09-17 23:26	71.51	OK
10853	2026-09-17 23:27	67.15	OK	10854	2026-09-17 23:28	69.82	OK
10855	2026-09-17 23:29	68.94	OK	10856	2026-09-17 23:30	68.57	OK
10857	2026-09-17 23:31	70.60	OK	10858	2026-09-17 23:32	67.80	OK
10859	2026-09-17 23:33	71.69	OK	10860	2026-09-17 23:34	71.42	OK
10861	2026-09-17 23:35	69.02	OK	10862	2026-09-17 23:36	72.44	OK
10863	2026-09-17 23:37	67.62	OK	10864	2026-09-17 23:38	68.58	OK
10865	2026-09-17 23:39	67.63	OK	10866	2026-09-17 23:40	69.53	OK
10867	2026-09-17 23:41	70.34	OK	10868	2026-09-17 23:42	66.44	OK
10869	2026-09-17 23:43	70.57	OK	10870	2026-09-17 23:44	69.37	OK
10871	2026-09-17 23:45	70.10	OK	10872	2026-09-17 23:46	68.78	OK
10873	2026-09-17 23:47	68.99	OK	10874	2026-09-17 23:48	69.42	OK
10875	2026-09-17 23:49	69.09	OK	10876	2026-09-17 23:50	69.66	OK
10877	2026-09-17 23:51	71.45	OK	10878	2026-09-17 23:52	71.27	OK
10879	2026-09-17 23:53	70.25	OK	10880	2026-09-17 23:54	66.60	OK
10881	2026-09-17 23:55	67.84	OK	10882	2026-09-17 23:56	71.64	OK
10883	2026-09-17 23:57	66.90	OK	10884	2026-09-17 23:58	70.85	OK
10885	2026-09-17 23:59	70.56	OK	10886	2026-09-18 00:00	68.28	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10887	2026-09-18 00:01	69.53	OK	10888	2026-09-18 00:02	71.19	OK
10889	2026-09-18 00:03	67.08	OK	10890	2026-09-18 00:04	70.56	OK
10891	2026-09-18 00:05	68.21	OK	10892	2026-09-18 00:06	69.83	OK
10893	2026-09-18 00:07	67.27	OK	10894	2026-09-18 00:08	70.40	OK
10895	2026-09-18 00:09	68.55	OK	10896	2026-09-18 00:10	66.73	OK
10897	2026-09-18 00:11	69.83	OK	10898	2026-09-18 00:12	68.58	OK
10899	2026-09-18 00:13	67.79	OK	10900	2026-09-18 00:14	68.87	OK
10901	2026-09-18 00:15	70.25	OK	10902	2026-09-18 00:16	72.82	OK
10903	2026-09-18 00:17	69.26	OK	10904	2026-09-18 00:18	70.53	OK
10905	2026-09-18 00:19	69.90	OK	10906	2026-09-18 00:20	68.08	OK
10907	2026-09-18 00:21	70.25	OK	10908	2026-09-18 00:22	68.06	OK
10909	2026-09-18 00:23	67.27	OK	10910	2026-09-18 00:24	69.58	OK
10911	2026-09-18 00:25	71.31	OK	10912	2026-09-18 00:26	68.32	OK
10913	2026-09-18 00:27	70.69	OK	10914	2026-09-18 00:28	70.86	OK
10915	2026-09-18 00:29	70.40	OK	10916	2026-09-18 00:30	69.72	OK
10917	2026-09-18 00:31	68.31	OK	10918	2026-09-18 00:32	70.22	OK
10919	2026-09-18 00:33	72.68	OK	10920	2026-09-18 00:34	68.75	OK
10921	2026-09-18 00:35	66.29	OK	10922	2026-09-18 00:36	66.81	OK
10923	2026-09-18 00:37	71.80	OK	10924	2026-09-18 00:38	73.16	OK
10925	2026-09-18 00:39	71.07	OK	10926	2026-09-18 00:40	65.41	OK
10927	2026-09-18 00:41	70.47	OK	10928	2026-09-18 00:42	67.23	OK
10929	2026-09-18 00:43	68.57	OK	10930	2026-09-18 00:44	70.36	OK
10931	2026-09-18 00:45	69.72	OK	10932	2026-09-18 00:46	69.62	OK
10933	2026-09-18 00:47	70.03	OK	10934	2026-09-18 00:48	72.45	OK
10935	2026-09-18 00:49	70.24	OK	10936	2026-09-18 00:50	70.09	OK
10937	2026-09-18 00:51	68.17	OK	10938	2026-09-18 00:52	70.42	OK
10939	2026-09-18 00:53	67.93	OK	10940	2026-09-18 00:54	72.09	OK
10941	2026-09-18 00:55	68.40	OK	10942	2026-09-18 00:56	67.25	OK
10943	2026-09-18 00:57	72.87	OK	10944	2026-09-18 00:58	69.82	OK
10945	2026-09-18 00:59	70.31	OK	10946	2026-09-18 01:00	67.44	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10947	2026-09-18 01:01	69.77	OK	10948	2026-09-18 01:02	69.78	OK
10949	2026-09-18 01:03	69.14	OK	10950	2026-09-18 01:04	67.38	OK
10951	2026-09-18 01:05	69.62	OK	10952	2026-09-18 01:06	70.89	OK
10953	2026-09-18 01:07	68.68	OK	10954	2026-09-18 01:08	70.46	OK
10955	2026-09-18 01:09	69.58	OK	10956	2026-09-18 01:10	67.57	OK
10957	2026-09-18 01:11	68.28	OK	10958	2026-09-18 01:12	69.51	OK
10959	2026-09-18 01:13	70.93	OK	10960	2026-09-18 01:14	69.41	OK
10961	2026-09-18 01:15	67.91	OK	10962	2026-09-18 01:16	66.80	OK
10963	2026-09-18 01:17	71.44	OK	10964	2026-09-18 01:18	67.62	OK
10965	2026-09-18 01:19	73.05	OK	10966	2026-09-18 01:20	71.89	OK
10967	2026-09-18 01:21	67.70	OK	10968	2026-09-18 01:22	69.58	OK
10969	2026-09-18 01:23	68.44	OK	10970	2026-09-18 01:24	69.08	OK
10971	2026-09-18 01:25	68.00	OK	10972	2026-09-18 01:26	69.90	OK
10973	2026-09-18 01:27	71.41	OK	10974	2026-09-18 01:28	69.75	OK
10975	2026-09-18 01:29	67.93	OK	10976	2026-09-18 01:30	71.08	OK
10977	2026-09-18 01:31	70.90	OK	10978	2026-09-18 01:32	69.25	OK
10979	2026-09-18 01:33	66.96	OK	10980	2026-09-18 01:34	70.70	OK
10981	2026-09-18 01:35	71.27	OK	10982	2026-09-18 01:36	70.44	OK
10983	2026-09-18 01:37	68.34	OK	10984	2026-09-18 01:38	70.16	OK
10985	2026-09-18 01:39	69.05	OK	10986	2026-09-18 01:40	73.58	OK
10987	2026-09-18 01:41	68.27	OK	10988	2026-09-18 01:42	66.91	OK
10989	2026-09-18 01:43	69.84	OK	10990	2026-09-18 01:44	70.57	OK
10991	2026-09-18 01:45	68.53	OK	10992	2026-09-18 01:46	66.51	OK
10993	2026-09-18 01:47	68.85	OK	10994	2026-09-18 01:48	69.46	OK
10995	2026-09-18 01:49	70.74	OK	10996	2026-09-18 01:50	67.30	OK
10997	2026-09-18 01:51	68.16	OK	10998	2026-09-18 01:52	67.50	OK
10999	2026-09-18 01:53	71.06	OK	11000	2026-09-18 01:54	69.07	OK
11001	2026-09-18 01:55	70.82	OK	11002	2026-09-18 01:56	70.60	OK
11003	2026-09-18 01:57	67.33	OK	11004	2026-09-18 01:58	71.09	OK
11005	2026-09-18 01:59	68.62	OK	11006	2026-09-18 02:00	70.18	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11007	2026-09-18 02:01	69.65	OK	11008	2026-09-18 02:02	72.20	OK
11009	2026-09-18 02:03	67.88	OK	11010	2026-09-18 02:04	71.27	OK
11011	2026-09-18 02:05	70.05	OK	11012	2026-09-18 02:06	69.91	OK
11013	2026-09-18 02:07	71.11	OK	11014	2026-09-18 02:08	68.77	OK
11015	2026-09-18 02:09	72.42	OK	11016	2026-09-18 02:10	69.49	OK
11017	2026-09-18 02:11	67.01	OK	11018	2026-09-18 02:12	71.04	OK
11019	2026-09-18 02:13	68.05	OK	11020	2026-09-18 02:14	67.06	OK
11021	2026-09-18 02:15	69.19	OK	11022	2026-09-18 02:16	68.87	OK
11023	2026-09-18 02:17	67.99	OK	11024	2026-09-18 02:18	69.28	OK
11025	2026-09-18 02:19	68.96	OK	11026	2026-09-18 02:20	70.35	OK
11027	2026-09-18 02:21	69.90	OK	11028	2026-09-18 02:22	68.87	OK
11029	2026-09-18 02:23	69.58	OK	11030	2026-09-18 02:24	71.13	OK
11031	2026-09-18 02:25	68.93	OK	11032	2026-09-18 02:26	65.78	OK
11033	2026-09-18 02:27	67.44	OK	11034	2026-09-18 02:28	68.17	OK
11035	2026-09-18 02:29	69.94	OK	11036	2026-09-18 02:30	69.17	OK
11037	2026-09-18 02:31	70.56	OK	11038	2026-09-18 02:32	72.15	OK
11039	2026-09-18 02:33	69.51	OK	11040	2026-09-18 02:34	71.43	OK
11041	2026-09-18 02:35	71.43	OK	11042	2026-09-18 02:36	69.17	OK
11043	2026-09-18 02:37	68.71	OK	11044	2026-09-18 02:38	70.32	OK
11045	2026-09-18 02:39	69.97	OK	11046	2026-09-18 02:40	69.64	OK
11047	2026-09-18 02:41	67.49	OK	11048	2026-09-18 02:42	69.08	OK
11049	2026-09-18 02:43	69.26	OK	11050	2026-09-18 02:44	70.74	OK
11051	2026-09-18 02:45	71.99	OK	11052	2026-09-18 02:46	72.37	OK
11053	2026-09-18 02:47	68.04	OK	11054	2026-09-18 02:48	70.51	OK
11055	2026-09-18 02:49	67.10	OK	11056	2026-09-18 02:50	68.09	OK
11057	2026-09-18 02:51	71.14	OK	11058	2026-09-18 02:52	73.96	OK
11059	2026-09-18 02:53	70.56	OK	11060	2026-09-18 02:54	70.66	OK
11061	2026-09-18 02:55	69.53	OK	11062	2026-09-18 02:56	69.02	OK
11063	2026-09-18 02:57	72.47	OK	11064	2026-09-18 02:58	70.92	OK
11065	2026-09-18 02:59	71.32	OK	11066	2026-09-18 03:00	70.47	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11067	2026-09-18 03:01	68.67	OK	11068	2026-09-18 03:02	69.14	OK
11069	2026-09-18 03:03	66.58	OK	11070	2026-09-18 03:04	69.94	OK
11071	2026-09-18 03:05	72.62	OK	11072	2026-09-18 03:06	73.00	OK
11073	2026-09-18 03:07	68.93	OK	11074	2026-09-18 03:08	69.02	OK
11075	2026-09-18 03:09	70.77	OK	11076	2026-09-18 03:10	69.34	OK
11077	2026-09-18 03:11	72.46	OK	11078	2026-09-18 03:12	70.18	OK
11079	2026-09-18 03:13	69.08	OK	11080	2026-09-18 03:14	68.16	OK
11081	2026-09-18 03:15	68.22	OK	11082	2026-09-18 03:16	71.87	OK
11083	2026-09-18 03:17	69.54	OK	11084	2026-09-18 03:18	68.20	OK
11085	2026-09-18 03:19	73.01	OK	11086	2026-09-18 03:20	71.18	OK
11087	2026-09-18 03:21	71.12	OK	11088	2026-09-18 03:22	70.60	OK
11089	2026-09-18 03:23	69.07	OK	11090	2026-09-18 03:24	68.78	OK
11091	2026-09-18 03:25	74.14	OK	11092	2026-09-18 03:26	72.49	OK
11093	2026-09-18 03:27	70.99	OK	11094	2026-09-18 03:28	70.67	OK
11095	2026-09-18 03:29	73.32	OK	11096	2026-09-18 03:30	70.90	OK
11097	2026-09-18 03:31	73.05	OK	11098	2026-09-18 03:32	68.64	OK
11099	2026-09-18 03:33	73.09	OK	11100	2026-09-18 03:34	68.06	OK
11101	2026-09-18 03:35	68.39	OK	11102	2026-09-18 03:36	69.54	OK
11103	2026-09-18 03:37	72.80	OK	11104	2026-09-18 03:38	72.36	OK
11105	2026-09-18 03:39	71.14	OK	11106	2026-09-18 03:40	69.62	OK
11107	2026-09-18 03:41	69.78	OK	11108	2026-09-18 03:42	72.20	OK
11109	2026-09-18 03:43	73.93	OK	11110	2026-09-18 03:44	73.88	OK
11111	2026-09-18 03:45	72.81	OK	11112	2026-09-18 03:46	70.23	OK
11113	2026-09-18 03:47	70.94	OK	11114	2026-09-18 03:48	70.33	OK
11115	2026-09-18 03:49	72.05	OK	11116	2026-09-18 03:50	72.13	OK
11117	2026-09-18 03:51	72.12	OK	11118	2026-09-18 03:52	67.26	OK
11119	2026-09-18 03:53	68.39	OK	11120	2026-09-18 03:54	71.42	OK
11121	2026-09-18 03:55	71.41	OK	11122	2026-09-18 03:56	69.43	OK
11123	2026-09-18 03:57	69.52	OK	11124	2026-09-18 03:58	74.25	OK
11125	2026-09-18 03:59	69.94	OK	11126	2026-09-18 04:00	71.38	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11127	2026-09-18 04:01	71.24	OK	11128	2026-09-18 04:02	71.22	OK
11129	2026-09-18 04:03	69.53	OK	11130	2026-09-18 04:04	74.78	OK
11131	2026-09-18 04:05	70.86	OK	11132	2026-09-18 04:06	71.63	OK
11133	2026-09-18 04:07	70.44	OK	11134	2026-09-18 04:08	72.97	OK
11135	2026-09-18 04:09	69.10	OK	11136	2026-09-18 04:10	70.83	OK
11137	2026-09-18 04:11	70.09	OK	11138	2026-09-18 04:12	72.77	OK
11139	2026-09-18 04:13	73.04	OK	11140	2026-09-18 04:14	69.54	OK
11141	2026-09-18 04:15	68.96	OK	11142	2026-09-18 04:16	72.19	OK
11143	2026-09-18 04:17	68.47	OK	11144	2026-09-18 04:18	71.83	OK
11145	2026-09-18 04:19	72.14	OK	11146	2026-09-18 04:20	72.93	OK
11147	2026-09-18 04:21	73.41	OK	11148	2026-09-18 04:22	70.86	OK
11149	2026-09-18 04:23	72.69	OK	11150	2026-09-18 04:24	71.11	OK
11151	2026-09-18 04:25	73.80	OK	11152	2026-09-18 04:26	70.44	OK
11153	2026-09-18 04:27	75.37	OK	11154	2026-09-18 04:28	69.72	OK
11155	2026-09-18 04:29	71.53	OK	11156	2026-09-18 04:30	72.32	OK
11157	2026-09-18 04:31	69.27	OK	11158	2026-09-18 04:32	71.58	OK
11159	2026-09-18 04:33	70.56	OK	11160	2026-09-18 04:34	70.45	OK
11161	2026-09-18 04:35	72.37	OK	11162	2026-09-18 04:36	70.32	OK
11163	2026-09-18 04:37	75.11	OK	11164	2026-09-18 04:38	70.46	OK
11165	2026-09-18 04:39	73.39	OK	11166	2026-09-18 04:40	71.77	OK
11167	2026-09-18 04:41	72.96	OK	11168	2026-09-18 04:42	72.40	OK
11169	2026-09-18 04:43	70.09	OK	11170	2026-09-18 04:44	74.39	OK
11171	2026-09-18 04:45	71.50	OK	11172	2026-09-18 04:46	72.87	OK
11173	2026-09-18 04:47	72.24	OK	11174	2026-09-18 04:48	72.64	OK
11175	2026-09-18 04:49	72.20	OK	11176	2026-09-18 04:50	70.39	OK
11177	2026-09-18 04:51	71.36	OK	11178	2026-09-18 04:52	72.03	OK
11179	2026-09-18 04:53	72.18	OK	11180	2026-09-18 04:54	73.76	OK
11181	2026-09-18 04:55	73.20	OK	11182	2026-09-18 04:56	69.30	OK
11183	2026-09-18 04:57	72.66	OK	11184	2026-09-18 04:58	74.38	OK
11185	2026-09-18 04:59	73.22	OK	11186	2026-09-18 05:00	70.91	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11187	2026-09-18 05:01	73.90	OK	11188	2026-09-18 05:02	73.14	OK
11189	2026-09-18 05:03	73.59	OK	11190	2026-09-18 05:04	72.05	OK
11191	2026-09-18 05:05	73.94	OK	11192	2026-09-18 05:06	75.81	OK
11193	2026-09-18 05:07	73.89	OK	11194	2026-09-18 05:08	73.31	OK
11195	2026-09-18 05:09	72.71	OK	11196	2026-09-18 05:10	72.96	OK
11197	2026-09-18 05:11	74.91	OK	11198	2026-09-18 05:12	71.64	OK
11199	2026-09-18 05:13	73.69	OK	11200	2026-09-18 05:14	71.92	OK
11201	2026-09-18 05:15	74.29	OK	11202	2026-09-18 05:16	73.06	OK
11203	2026-09-18 05:17	73.43	OK	11204	2026-09-18 05:18	72.13	OK
11205	2026-09-18 05:19	73.28	OK	11206	2026-09-18 05:20	71.92	OK
11207	2026-09-18 05:21	76.71	OK	11208	2026-09-18 05:22	76.64	OK
11209	2026-09-18 05:23	69.94	OK	11210	2026-09-18 05:24	71.71	OK
11211	2026-09-18 05:25	72.61	OK	11212	2026-09-18 05:26	70.69	OK
11213	2026-09-18 05:27	76.23	OK	11214	2026-09-18 05:28	73.89	OK
11215	2026-09-18 05:29	70.58	OK	11216	2026-09-18 05:30	73.43	OK
11217	2026-09-18 05:31	73.49	OK	11218	2026-09-18 05:32	75.83	OK
11219	2026-09-18 05:33	74.58	OK	11220	2026-09-18 05:34	72.38	OK
11221	2026-09-18 05:35	72.94	OK	11222	2026-09-18 05:36	75.88	OK
11223	2026-09-18 05:37	75.33	OK	11224	2026-09-18 05:38	71.33	OK
11225	2026-09-18 05:39	72.66	OK	11226	2026-09-18 05:40	70.22	OK
11227	2026-09-18 05:41	70.96	OK	11228	2026-09-18 05:42	73.24	OK
11229	2026-09-18 05:43	72.13	OK	11230	2026-09-18 05:44	72.62	OK
11231	2026-09-18 05:45	71.16	OK	11232	2026-09-18 05:46	73.05	OK
11233	2026-09-18 05:47	72.46	OK	11234	2026-09-18 05:48	73.69	OK
11235	2026-09-18 05:49	74.43	OK	11236	2026-09-18 05:50	77.29	OK
11237	2026-09-18 05:51	77.03	OK	11238	2026-09-18 05:52	77.29	OK
11239	2026-09-18 05:53	70.24	OK	11240	2026-09-18 05:54	74.61	OK
11241	2026-09-18 05:55	73.72	OK	11242	2026-09-18 05:56	72.09	OK
11243	2026-09-18 05:57	72.79	OK	11244	2026-09-18 05:58	74.49	OK
11245	2026-09-18 05:59	74.63	OK	11246	2026-09-18 06:00	75.57	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11247	2026-09-18 06:01	76.24	OK	11248	2026-09-18 06:02	73.18	OK
11249	2026-09-18 06:03	72.53	OK	11250	2026-09-18 06:04	71.81	OK
11251	2026-09-18 06:05	73.78	OK	11252	2026-09-18 06:06	71.49	OK
11253	2026-09-18 06:07	72.73	OK	11254	2026-09-18 06:08	73.14	OK
11255	2026-09-18 06:09	72.12	OK	11256	2026-09-18 06:10	74.78	OK
11257	2026-09-18 06:11	73.56	OK	11258	2026-09-18 06:12	76.70	OK
11259	2026-09-18 06:13	72.77	OK	11260	2026-09-18 06:14	71.56	OK
11261	2026-09-18 06:15	73.22	OK	11262	2026-09-18 06:16	75.23	OK
11263	2026-09-18 06:17	73.55	OK	11264	2026-09-18 06:18	72.46	OK
11265	2026-09-18 06:19	74.89	OK	11266	2026-09-18 06:20	76.40	OK
11267	2026-09-18 06:21	72.64	OK	11268	2026-09-18 06:22	74.16	OK
11269	2026-09-18 06:23	73.61	OK	11270	2026-09-18 06:24	76.76	OK
11271	2026-09-18 06:25	76.00	OK	11272	2026-09-18 06:26	74.99	OK
11273	2026-09-18 06:27	74.67	OK	11274	2026-09-18 06:28	76.97	OK
11275	2026-09-18 06:29	75.65	OK	11276	2026-09-18 06:30	73.22	OK
11277	2026-09-18 06:31	75.67	OK	11278	2026-09-18 06:32	77.12	OK
11279	2026-09-18 06:33	75.60	OK	11280	2026-09-18 06:34	76.16	OK
11281	2026-09-18 06:35	75.74	OK	11282	2026-09-18 06:36	73.18	OK
11283	2026-09-18 06:37	73.13	OK	11284	2026-09-18 06:38	73.32	OK
11285	2026-09-18 06:39	77.38	OK	11286	2026-09-18 06:40	76.96	OK
11287	2026-09-18 06:41	74.56	OK	11288	2026-09-18 06:42	77.53	OK
11289	2026-09-18 06:43	77.46	OK	11290	2026-09-18 06:44	75.42	OK
11291	2026-09-18 06:45	75.46	OK	11292	2026-09-18 06:46	76.85	OK
11293	2026-09-18 06:47	73.45	OK	11294	2026-09-18 06:48	73.81	OK
11295	2026-09-18 06:49	73.76	OK	11296	2026-09-18 06:50	75.11	OK
11297	2026-09-18 06:51	75.14	OK	11298	2026-09-18 06:52	74.75	OK
11299	2026-09-18 06:53	76.80	OK	11300	2026-09-18 06:54	77.79	OK
11301	2026-09-18 06:55	76.69	OK	11302	2026-09-18 06:56	75.17	OK
11303	2026-09-18 06:57	73.58	OK	11304	2026-09-18 06:58	77.37	OK
11305	2026-09-18 06:59	72.52	OK	11306	2026-09-18 07:00	73.83	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11307	2026-09-18 07:01	76.25	OK	11308	2026-09-18 07:02	75.81	OK
11309	2026-09-18 07:03	74.58	OK	11310	2026-09-18 07:04	75.00	OK
11311	2026-09-18 07:05	75.90	OK	11312	2026-09-18 07:06	75.74	OK
11313	2026-09-18 07:07	74.06	OK	11314	2026-09-18 07:08	74.65	OK
11315	2026-09-18 07:09	79.10	OK	11316	2026-09-18 07:10	77.28	OK
11317	2026-09-18 07:11	74.96	OK	11318	2026-09-18 07:12	76.88	OK
11319	2026-09-18 07:13	76.68	OK	11320	2026-09-18 07:14	76.78	OK
11321	2026-09-18 07:15	74.98	OK	11322	2026-09-18 07:16	77.03	OK
11323	2026-09-18 07:17	75.33	OK	11324	2026-09-18 07:18	78.59	OK
11325	2026-09-18 07:19	72.59	OK	11326	2026-09-18 07:20	74.42	OK
11327	2026-09-18 07:21	73.81	OK	11328	2026-09-18 07:22	77.71	OK
11329	2026-09-18 07:23	75.20	OK	11330	2026-09-18 07:24	76.93	OK
11331	2026-09-18 07:25	75.82	OK	11332	2026-09-18 07:26	74.39	OK
11333	2026-09-18 07:27	77.34	OK	11334	2026-09-18 07:28	73.53	OK
11335	2026-09-18 07:29	76.57	OK	11336	2026-09-18 07:30	77.16	OK
11337	2026-09-18 07:31	77.39	OK	11338	2026-09-18 07:32	77.65	OK
11339	2026-09-18 07:33	75.69	OK	11340	2026-09-18 07:34	76.33	OK
11341	2026-09-18 07:35	75.65	OK	11342	2026-09-18 07:36	76.45	OK
11343	2026-09-18 07:37	77.27	OK	11344	2026-09-18 07:38	77.52	OK
11345	2026-09-18 07:39	73.56	OK	11346	2026-09-18 07:40	77.47	OK
11347	2026-09-18 07:41	78.65	OK	11348	2026-09-18 07:42	75.47	OK
11349	2026-09-18 07:43	73.94	OK	11350	2026-09-18 07:44	76.58	OK
11351	2026-09-18 07:45	77.85	OK	11352	2026-09-18 07:46	76.49	OK
11353	2026-09-18 07:47	75.12	OK	11354	2026-09-18 07:48	76.23	OK
11355	2026-09-18 07:49	78.83	OK	11356	2026-09-18 07:50	75.08	OK
11357	2026-09-18 07:51	77.49	OK	11358	2026-09-18 07:52	74.04	OK
11359	2026-09-18 07:53	75.30	OK	11360	2026-09-18 07:54	78.16	OK
11361	2026-09-18 07:55	79.14	OK	11362	2026-09-18 07:56	75.43	OK
11363	2026-09-18 07:57	79.11	OK	11364	2026-09-18 07:58	79.72	OK
11365	2026-09-18 07:59	77.93	OK	11366	2026-09-18 08:00	75.53	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11367	2026-09-18 08:01	78.35	OK	11368	2026-09-18 08:02	76.92	OK
11369	2026-09-18 08:03	76.79	OK	11370	2026-09-18 08:04	81.06	OK
11371	2026-09-18 08:05	80.86	OK	11372	2026-09-18 08:06	76.75	OK
11373	2026-09-18 08:07	73.74	OK	11374	2026-09-18 08:08	75.68	OK
11375	2026-09-18 08:09	76.66	OK	11376	2026-09-18 08:10	76.67	OK
11377	2026-09-18 08:11	76.03	OK	11378	2026-09-18 08:12	76.64	OK
11379	2026-09-18 08:13	79.53	OK	11380	2026-09-18 08:14	78.02	OK
11381	2026-09-18 08:15	78.28	OK	11382	2026-09-18 08:16	78.28	OK
11383	2026-09-18 08:17	78.14	OK	11384	2026-09-18 08:18	79.31	OK
11385	2026-09-18 08:19	80.57	OK	11386	2026-09-18 08:20	74.99	OK
11387	2026-09-18 08:21	77.66	OK	11388	2026-09-18 08:22	78.41	OK
11389	2026-09-18 08:23	78.18	OK	11390	2026-09-18 08:24	75.21	OK
11391	2026-09-18 08:25	76.77	OK	11392	2026-09-18 08:26	79.10	OK
11393	2026-09-18 08:27	76.24	OK	11394	2026-09-18 08:28	73.35	OK
11395	2026-09-18 08:29	73.53	OK	11396	2026-09-18 08:30	79.04	OK
11397	2026-09-18 08:31	78.72	OK	11398	2026-09-18 08:32	74.69	OK
11399	2026-09-18 08:33	77.21	OK	11400	2026-09-18 08:34	77.11	OK
11401	2026-09-18 08:35	75.10	OK	11402	2026-09-18 08:36	75.00	OK
11403	2026-09-18 08:37	77.15	OK	11404	2026-09-18 08:38	78.65	OK
11405	2026-09-18 08:39	78.89	OK	11406	2026-09-18 08:40	75.85	OK
11407	2026-09-18 08:41	78.39	OK	11408	2026-09-18 08:42	77.61	OK
11409	2026-09-18 08:43	79.25	OK	11410	2026-09-18 08:44	77.25	OK
11411	2026-09-18 08:45	76.51	OK	11412	2026-09-18 08:46	80.14	OK
11413	2026-09-18 08:47	78.21	OK	11414	2026-09-18 08:48	76.47	OK
11415	2026-09-18 08:49	78.75	OK	11416	2026-09-18 08:50	77.24	OK
11417	2026-09-18 08:51	76.82	OK	11418	2026-09-18 08:52	81.62	OK
11419	2026-09-18 08:53	78.76	OK	11420	2026-09-18 08:54	77.99	OK
11421	2026-09-18 08:55	79.91	OK	11422	2026-09-18 08:56	78.79	OK
11423	2026-09-18 08:57	78.48	OK	11424	2026-09-18 08:58	76.51	OK
11425	2026-09-18 08:59	80.03	OK	11426	2026-09-18 09:00	77.47	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11427	2026-09-18 09:01	79.33	OK	11428	2026-09-18 09:02	78.34	OK
11429	2026-09-18 09:03	79.45	OK	11430	2026-09-18 09:04	76.28	OK
11431	2026-09-18 09:05	78.19	OK	11432	2026-09-18 09:06	77.33	OK
11433	2026-09-18 09:07	77.98	OK	11434	2026-09-18 09:08	79.77	OK
11435	2026-09-18 09:09	78.30	OK	11436	2026-09-18 09:10	80.17	OK
11437	2026-09-18 09:11	79.85	OK	11438	2026-09-18 09:12	80.47	OK
11439	2026-09-18 09:13	76.95	OK	11440	2026-09-18 09:14	79.65	OK
11441	2026-09-18 09:15	77.74	OK	11442	2026-09-18 09:16	81.63	OK
11443	2026-09-18 09:17	78.36	OK	11444	2026-09-18 09:18	77.55	OK
11445	2026-09-18 09:19	76.83	OK	11446	2026-09-18 09:20	79.17	OK
11447	2026-09-18 09:21	77.77	OK	11448	2026-09-18 09:22	80.41	OK
11449	2026-09-18 09:23	78.15	OK	11450	2026-09-18 09:24	77.55	OK
11451	2026-09-18 09:25	79.58	OK	11452	2026-09-18 09:26	79.34	OK
11453	2026-09-18 09:27	78.43	OK	11454	2026-09-18 09:28	79.29	OK
11455	2026-09-18 09:29	79.77	OK	11456	2026-09-18 09:30	77.86	OK
11457	2026-09-18 09:31	77.71	OK	11458	2026-09-18 09:32	78.14	OK
11459	2026-09-18 09:33	78.47	OK	11460	2026-09-18 09:34	79.64	OK
11461	2026-09-18 09:35	77.25	OK	11462	2026-09-18 09:36	76.87	OK
11463	2026-09-18 09:37	77.05	OK	11464	2026-09-18 09:38	80.32	OK
11465	2026-09-18 09:39	80.05	OK	11466	2026-09-18 09:40	77.09	OK
11467	2026-09-18 09:41	78.50	OK	11468	2026-09-18 09:42	80.09	OK
11469	2026-09-18 09:43	76.40	OK	11470	2026-09-18 09:44	80.90	OK
11471	2026-09-18 09:45	77.34	OK	11472	2026-09-18 09:46	82.08	OK
11473	2026-09-18 09:47	79.00	OK	11474	2026-09-18 09:48	78.73	OK
11475	2026-09-18 09:49	75.20	OK	11476	2026-09-18 09:50	78.18	OK
11477	2026-09-18 09:51	79.64	OK	11478	2026-09-18 09:52	80.20	OK
11479	2026-09-18 09:53	80.60	OK	11480	2026-09-18 09:54	79.49	OK
11481	2026-09-18 09:55	79.36	OK	11482	2026-09-18 09:56	78.28	OK
11483	2026-09-18 09:57	80.09	OK	11484	2026-09-18 09:58	77.99	OK
11485	2026-09-18 09:59	76.03	OK	11486	2026-09-18 10:00	79.43	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11487	2026-09-18 10:01	76.32	OK	11488	2026-09-18 10:02	80.21	OK
11489	2026-09-18 10:03	79.00	OK	11490	2026-09-18 10:04	80.48	OK
11491	2026-09-18 10:05	79.39	OK	11492	2026-09-18 10:06	78.42	OK
11493	2026-09-18 10:07	78.11	OK	11494	2026-09-18 10:08	81.00	OK
11495	2026-09-18 10:09	80.18	OK	11496	2026-09-18 10:10	78.38	OK
11497	2026-09-18 10:11	77.45	OK	11498	2026-09-18 10:12	77.74	OK
11499	2026-09-18 10:13	81.60	OK	11500	2026-09-18 10:14	78.69	OK
11501	2026-09-18 10:15	80.73	OK	11502	2026-09-18 10:16	80.40	OK
11503	2026-09-18 10:17	78.02	OK	11504	2026-09-18 10:18	79.55	OK
11505	2026-09-18 10:19	79.04	OK	11506	2026-09-18 10:20	79.89	OK
11507	2026-09-18 10:21	78.77	OK	11508	2026-09-18 10:22	79.55	OK
11509	2026-09-18 10:23	80.66	OK	11510	2026-09-18 10:24	77.09	OK
11511	2026-09-18 10:25	81.85	OK	11512	2026-09-18 10:26	82.51	OK
11513	2026-09-18 10:27	79.39	OK	11514	2026-09-18 10:28	79.24	OK
11515	2026-09-18 10:29	78.72	OK	11516	2026-09-18 10:30	77.83	OK
11517	2026-09-18 10:31	79.17	OK	11518	2026-09-18 10:32	80.40	OK
11519	2026-09-18 10:33	82.78	OK	11520	2026-09-18 10:34	77.85	OK
11521	2026-09-18 10:35	78.79	OK	11522	2026-09-18 10:36	78.18	OK
11523	2026-09-18 10:37	79.23	OK	11524	2026-09-18 10:38	79.93	OK
11525	2026-09-18 10:39	79.06	OK	11526	2026-09-18 10:40	79.35	OK
11527	2026-09-18 10:41	79.52	OK	11528	2026-09-18 10:42	79.04	OK
11529	2026-09-18 10:43	81.74	OK	11530	2026-09-18 10:44	79.07	OK
11531	2026-09-18 10:45	78.38	OK	11532	2026-09-18 10:46	81.57	OK
11533	2026-09-18 10:47	78.33	OK	11534	2026-09-18 10:48	78.52	OK
11535	2026-09-18 10:49	78.48	OK	11536	2026-09-18 10:50	80.06	OK
11537	2026-09-18 10:51	77.82	OK	11538	2026-09-18 10:52	81.37	OK
11539	2026-09-18 10:53	81.10	OK	11540	2026-09-18 10:54	80.91	OK
11541	2026-09-18 10:55	81.39	OK	11542	2026-09-18 10:56	79.75	OK
11543	2026-09-18 10:57	80.70	OK	11544	2026-09-18 10:58	82.24	OK
11545	2026-09-18 10:59	82.36	OK	11546	2026-09-18 11:00	79.34	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11547	2026-09-18 11:01	80.94	OK	11548	2026-09-18 11:02	77.99	OK
11549	2026-09-18 11:03	80.89	OK	11550	2026-09-18 11:04	79.33	OK
11551	2026-09-18 11:05	79.28	OK	11552	2026-09-18 11:06	78.69	OK
11553	2026-09-18 11:07	82.79	OK	11554	2026-09-18 11:08	81.24	OK
11555	2026-09-18 11:09	79.80	OK	11556	2026-09-18 11:10	81.97	OK
11557	2026-09-18 11:11	78.45	OK	11558	2026-09-18 11:12	81.14	OK
11559	2026-09-18 11:13	83.56	OK	11560	2026-09-18 11:14	78.34	OK
11561	2026-09-18 11:15	80.60	OK	11562	2026-09-18 11:16	82.79	OK
11563	2026-09-18 11:17	82.38	OK	11564	2026-09-18 11:18	79.30	OK
11565	2026-09-18 11:19	78.72	OK	11566	2026-09-18 11:20	78.01	OK
11567	2026-09-18 11:21	82.10	OK	11568	2026-09-18 11:22	80.92	OK
11569	2026-09-18 11:23	78.69	OK	11570	2026-09-18 11:24	80.72	OK
11571	2026-09-18 11:25	79.86	OK	11572	2026-09-18 11:26	81.49	OK
11573	2026-09-18 11:27	78.86	OK	11574	2026-09-18 11:28	79.17	OK
11575	2026-09-18 11:29	82.16	OK	11576	2026-09-18 11:30	81.88	OK
11577	2026-09-18 11:31	80.69	OK	11578	2026-09-18 11:32	81.98	OK
11579	2026-09-18 11:33	80.86	OK	11580	2026-09-18 11:34	82.12	OK
11581	2026-09-18 11:35	79.51	OK	11582	2026-09-18 11:36	79.83	OK
11583	2026-09-18 11:37	82.85	OK	11584	2026-09-18 11:38	81.32	OK
11585	2026-09-18 11:39	81.11	OK	11586	2026-09-18 11:40	81.68	OK
11587	2026-09-18 11:41	82.47	OK	11588	2026-09-18 11:42	77.88	OK
11589	2026-09-18 11:43	82.28	OK	11590	2026-09-18 11:44	79.78	OK
11591	2026-09-18 11:45	82.49	OK	11592	2026-09-18 11:46	81.98	OK
11593	2026-09-18 11:47	81.68	OK	11594	2026-09-18 11:48	81.02	OK
11595	2026-09-18 11:49	79.30	OK	11596	2026-09-18 11:50	81.05	OK
11597	2026-09-18 11:51	81.35	OK	11598	2026-09-18 11:52	79.95	OK
11599	2026-09-18 11:53	79.15	OK	11600	2026-09-18 11:54	79.73	OK
11601	2026-09-18 11:55	82.95	OK	11602	2026-09-18 11:56	81.31	OK
11603	2026-09-18 11:57	80.82	OK	11604	2026-09-18 11:58	82.82	OK
11605	2026-09-18 11:59	79.84	OK	11606	2026-09-18 12:00	82.44	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11607	2026-09-18 12:01	80.73	OK	11608	2026-09-18 12:02	83.39	OK
11609	2026-09-18 12:03	81.69	OK	11610	2026-09-18 12:04	78.68	OK
11611	2026-09-18 12:05	82.53	OK	11612	2026-09-18 12:06	81.14	OK
11613	2026-09-18 12:07	81.35	OK	11614	2026-09-18 12:08	80.78	OK
11615	2026-09-18 12:09	78.37	OK	11616	2026-09-18 12:10	80.62	OK
11617	2026-09-18 12:11	79.80	OK	11618	2026-09-18 12:12	82.62	OK
11619	2026-09-18 12:13	80.26	OK	11620	2026-09-18 12:14	81.08	OK
11621	2026-09-18 12:15	82.23	OK	11622	2026-09-18 12:16	76.92	OK
11623	2026-09-18 12:17	84.55	OK	11624	2026-09-18 12:18	81.68	OK
11625	2026-09-18 12:19	78.96	OK	11626	2026-09-18 12:20	78.59	OK
11627	2026-09-18 12:21	79.01	OK	11628	2026-09-18 12:22	77.99	OK
11629	2026-09-18 12:23	81.46	OK	11630	2026-09-18 12:24	78.96	OK
11631	2026-09-18 12:25	78.28	OK	11632	2026-09-18 12:26	78.33	OK
11633	2026-09-18 12:27	81.74	OK	11634	2026-09-18 12:28	80.43	OK
11635	2026-09-18 12:29	79.22	OK	11636	2026-09-18 12:30	84.52	OK
11637	2026-09-18 12:31	83.96	OK	11638	2026-09-18 12:32	81.52	OK
11639	2026-09-18 12:33	81.23	OK	11640	2026-09-18 12:34	80.54	OK
11641	2026-09-18 12:35	80.94	OK	11642	2026-09-18 12:36	77.40	OK
11643	2026-09-18 12:37	80.25	OK	11644	2026-09-18 12:38	80.07	OK
11645	2026-09-18 12:39	77.63	OK	11646	2026-09-18 12:40	83.73	OK
11647	2026-09-18 12:41	80.16	OK	11648	2026-09-18 12:42	82.12	OK
11649	2026-09-18 12:43	79.78	OK	11650	2026-09-18 12:44	77.48	OK
11651	2026-09-18 12:45	79.82	OK	11652	2026-09-18 12:46	79.16	OK
11653	2026-09-18 12:47	82.23	OK	11654	2026-09-18 12:48	79.89	OK
11655	2026-09-18 12:49	79.98	OK	11656	2026-09-18 12:50	84.34	OK
11657	2026-09-18 12:51	83.57	OK	11658	2026-09-18 12:52	83.27	OK
11659	2026-09-18 12:53	81.70	OK	11660	2026-09-18 12:54	81.25	OK
11661	2026-09-18 12:55	82.03	OK	11662	2026-09-18 12:56	80.34	OK
11663	2026-09-18 12:57	81.79	OK	11664	2026-09-18 12:58	82.74	OK
11665	2026-09-18 12:59	84.11	OK	11666	2026-09-18 13:00	78.39	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11667	2026-09-18 13:01	81.33	OK	11668	2026-09-18 13:02	80.63	OK
11669	2026-09-18 13:03	81.99	OK	11670	2026-09-18 13:04	81.37	OK
11671	2026-09-18 13:05	81.70	OK	11672	2026-09-18 13:06	80.12	OK
11673	2026-09-18 13:07	80.20	OK	11674	2026-09-18 13:08	79.86	OK
11675	2026-09-18 13:09	82.01	OK	11676	2026-09-18 13:10	79.76	OK
11677	2026-09-18 13:11	81.04	OK	11678	2026-09-18 13:12	79.78	OK
11679	2026-09-18 13:13	81.97	OK	11680	2026-09-18 13:14	82.64	OK
11681	2026-09-18 13:15	80.20	OK	11682	2026-09-18 13:16	82.39	OK
11683	2026-09-18 13:17	82.84	OK	11684	2026-09-18 13:18	81.41	OK
11685	2026-09-18 13:19	80.66	OK	11686	2026-09-18 13:20	82.11	OK
11687	2026-09-18 13:21	79.54	OK	11688	2026-09-18 13:22	81.02	OK
11689	2026-09-18 13:23	81.38	OK	11690	2026-09-18 13:24	81.78	OK
11691	2026-09-18 13:25	79.55	OK	11692	2026-09-18 13:26	80.87	OK
11693	2026-09-18 13:27	80.40	OK	11694	2026-09-18 13:28	81.34	OK
11695	2026-09-18 13:29	80.18	OK	11696	2026-09-18 13:30	79.59	OK
11697	2026-09-18 13:31	80.21	OK	11698	2026-09-18 13:32	80.23	OK
11699	2026-09-18 13:33	81.29	OK	11700	2026-09-18 13:34	81.24	OK
11701	2026-09-18 13:35	77.89	OK	11702	2026-09-18 13:36	81.29	OK
11703	2026-09-18 13:37	79.77	OK	11704	2026-09-18 13:38	78.79	OK
11705	2026-09-18 13:39	81.14	OK	11706	2026-09-18 13:40	80.24	OK
11707	2026-09-18 13:41	84.11	OK	11708	2026-09-18 13:42	80.97	OK
11709	2026-09-18 13:43	82.26	OK	11710	2026-09-18 13:44	80.81	OK
11711	2026-09-18 13:45	83.49	OK	11712	2026-09-18 13:46	80.94	OK
11713	2026-09-18 13:47	82.07	OK	11714	2026-09-18 13:48	83.44	OK
11715	2026-09-18 13:49	79.74	OK	11716	2026-09-18 13:50	79.26	OK
11717	2026-09-18 13:51	81.20	OK	11718	2026-09-18 13:52	80.39	OK
11719	2026-09-18 13:53	79.45	OK	11720	2026-09-18 13:54	79.04	OK
11721	2026-09-18 13:55	79.90	OK	11722	2026-09-18 13:56	83.66	OK
11723	2026-09-18 13:57	83.84	OK	11724	2026-09-18 13:58	77.63	OK
11725	2026-09-18 13:59	80.24	OK	11726	2026-09-18 14:00	83.26	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11727	2026-09-18 14:01	80.68	OK	11728	2026-09-18 14:02	83.78	OK
11729	2026-09-18 14:03	79.31	OK	11730	2026-09-18 14:04	81.59	OK
11731	2026-09-18 14:05	82.87	OK	11732	2026-09-18 14:06	81.12	OK
11733	2026-09-18 14:07	81.90	OK	11734	2026-09-18 14:08	78.69	OK
11735	2026-09-18 14:09	82.21	OK	11736	2026-09-18 14:10	79.57	OK
11737	2026-09-18 14:11	78.16	OK	11738	2026-09-18 14:12	76.97	OK
11739	2026-09-18 14:13	79.19	OK	11740	2026-09-18 14:14	79.54	OK
11741	2026-09-18 14:15	78.95	OK	11742	2026-09-18 14:16	81.24	OK
11743	2026-09-18 14:17	78.37	OK	11744	2026-09-18 14:18	82.77	OK
11745	2026-09-18 14:19	77.94	OK	11746	2026-09-18 14:20	78.75	OK
11747	2026-09-18 14:21	79.36	OK	11748	2026-09-18 14:22	79.26	OK
11749	2026-09-18 14:23	81.58	OK	11750	2026-09-18 14:24	77.67	OK
11751	2026-09-18 14:25	79.67	OK	11752	2026-09-18 14:26	79.77	OK
11753	2026-09-18 14:27	80.36	OK	11754	2026-09-18 14:28	81.16	OK
11755	2026-09-18 14:29	78.53	OK	11756	2026-09-18 14:30	82.31	OK
11757	2026-09-18 14:31	78.62	OK	11758	2026-09-18 14:32	76.37	OK
11759	2026-09-18 14:33	79.58	OK	11760	2026-09-18 14:34	78.22	OK
11761	2026-09-18 14:35	80.10	OK	11762	2026-09-18 14:36	80.98	OK
11763	2026-09-18 14:37	80.08	OK	11764	2026-09-18 14:38	83.19	OK
11765	2026-09-18 14:39	80.74	OK	11766	2026-09-18 14:40	80.38	OK
11767	2026-09-18 14:41	80.77	OK	11768	2026-09-18 14:42	79.01	OK
11769	2026-09-18 14:43	77.82	OK	11770	2026-09-18 14:44	83.78	OK
11771	2026-09-18 14:45	79.07	OK	11772	2026-09-18 14:46	82.70	OK
11773	2026-09-18 14:47	79.77	OK	11774	2026-09-18 14:48	77.91	OK
11775	2026-09-18 14:49	78.42	OK	11776	2026-09-18 14:50	81.80	OK
11777	2026-09-18 14:51	79.52	OK	11778	2026-09-18 14:52	80.28	OK
11779	2026-09-18 14:53	80.16	OK	11780	2026-09-18 14:54	80.73	OK
11781	2026-09-18 14:55	81.85	OK	11782	2026-09-18 14:56	79.26	OK
11783	2026-09-18 14:57	77.35	OK	11784	2026-09-18 14:58	79.37	OK
11785	2026-09-18 14:59	81.39	OK	11786	2026-09-18 15:00	80.55	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11787	2026-09-18 15:01	79.30	OK	11788	2026-09-18 15:02	81.13	OK
11789	2026-09-18 15:03	80.19	OK	11790	2026-09-18 15:04	80.39	OK
11791	2026-09-18 15:05	81.26	OK	11792	2026-09-18 15:06	80.39	OK
11793	2026-09-18 15:07	77.80	OK	11794	2026-09-18 15:08	79.84	OK
11795	2026-09-18 15:09	79.12	OK	11796	2026-09-18 15:10	79.30	OK
11797	2026-09-18 15:11	79.82	OK	11798	2026-09-18 15:12	80.36	OK
11799	2026-09-18 15:13	82.62	OK	11800	2026-09-18 15:14	81.40	OK
11801	2026-09-18 15:15	79.57	OK	11802	2026-09-18 15:16	78.15	OK
11803	2026-09-18 15:17	78.35	OK	11804	2026-09-18 15:18	82.61	OK
11805	2026-09-18 15:19	79.83	OK	11806	2026-09-18 15:20	79.05	OK
11807	2026-09-18 15:21	78.75	OK	11808	2026-09-18 15:22	79.46	OK
11809	2026-09-18 15:23	80.35	OK	11810	2026-09-18 15:24	79.58	OK
11811	2026-09-18 15:25	80.86	OK	11812	2026-09-18 15:26	79.96	OK
11813	2026-09-18 15:27	79.54	OK	11814	2026-09-18 15:28	80.09	OK
11815	2026-09-18 15:29	78.40	OK	11816	2026-09-18 15:30	82.74	OK
11817	2026-09-18 15:31	78.29	OK	11818	2026-09-18 15:32	79.53	OK
11819	2026-09-18 15:33	76.78	OK	11820	2026-09-18 15:34	81.18	OK
11821	2026-09-18 15:35	75.62	OK	11822	2026-09-18 15:36	79.40	OK
11823	2026-09-18 15:37	77.80	OK	11824	2026-09-18 15:38	78.59	OK
11825	2026-09-18 15:39	78.08	OK	11826	2026-09-18 15:40	79.33	OK
11827	2026-09-18 15:41	76.45	OK	11828	2026-09-18 15:42	80.82	OK
11829	2026-09-18 15:43	77.85	OK	11830	2026-09-18 15:44	79.30	OK
11831	2026-09-18 15:45	79.97	OK	11832	2026-09-18 15:46	79.54	OK
11833	2026-09-18 15:47	76.72	OK	11834	2026-09-18 15:48	80.52	OK
11835	2026-09-18 15:49	79.49	OK	11836	2026-09-18 15:50	82.74	OK
11837	2026-09-18 15:51	81.69	OK	11838	2026-09-18 15:52	77.59	OK
11839	2026-09-18 15:53	78.62	OK	11840	2026-09-18 15:54	78.57	OK
11841	2026-09-18 15:55	80.89	OK	11842	2026-09-18 15:56	80.75	OK
11843	2026-09-18 15:57	77.08	OK	11844	2026-09-18 15:58	79.56	OK
11845	2026-09-18 15:59	78.07	OK	11846	2026-09-18 16:00	81.36	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11847	2026-09-18 16:01	78.98	OK	11848	2026-09-18 16:02	77.73	OK
11849	2026-09-18 16:03	78.91	OK	11850	2026-09-18 16:04	78.46	OK
11851	2026-09-18 16:05	80.17	OK	11852	2026-09-18 16:06	78.95	OK
11853	2026-09-18 16:07	77.12	OK	11854	2026-09-18 16:08	78.55	OK
11855	2026-09-18 16:09	79.75	OK	11856	2026-09-18 16:10	80.63	OK
11857	2026-09-18 16:11	78.39	OK	11858	2026-09-18 16:12	80.83	OK
11859	2026-09-18 16:13	77.64	OK	11860	2026-09-18 16:14	81.59	OK
11861	2026-09-18 16:15	77.91	OK	11862	2026-09-18 16:16	78.03	OK
11863	2026-09-18 16:17	79.49	OK	11864	2026-09-18 16:18	81.85	OK
11865	2026-09-18 16:19	78.08	OK	11866	2026-09-18 16:20	81.33	OK
11867	2026-09-18 16:21	79.12	OK	11868	2026-09-18 16:22	76.79	OK
11869	2026-09-18 16:23	80.43	OK	11870	2026-09-18 16:24	78.86	OK
11871	2026-09-18 16:25	78.56	OK	11872	2026-09-18 16:26	77.27	OK
11873	2026-09-18 16:27	79.48	OK	11874	2026-09-18 16:28	75.45	OK
11875	2026-09-18 16:29	76.59	OK	11876	2026-09-18 16:30	78.45	OK
11877	2026-09-18 16:31	80.42	OK	11878	2026-09-18 16:32	79.25	OK
11879	2026-09-18 16:33	80.54	OK	11880	2026-09-18 16:34	80.01	OK
11881	2026-09-18 16:35	79.47	OK	11882	2026-09-18 16:36	76.87	OK
11883	2026-09-18 16:37	79.48	OK	11884	2026-09-18 16:38	78.28	OK
11885	2026-09-18 16:39	78.28	OK	11886	2026-09-18 16:40	79.89	OK
11887	2026-09-18 16:41	77.77	OK	11888	2026-09-18 16:42	76.97	OK
11889	2026-09-18 16:43	75.66	OK	11890	2026-09-18 16:44	77.22	OK
11891	2026-09-18 16:45	75.43	OK	11892	2026-09-18 16:46	75.01	OK
11893	2026-09-18 16:47	77.64	OK	11894	2026-09-18 16:48	77.91	OK
11895	2026-09-18 16:49	78.97	OK	11896	2026-09-18 16:50	79.48	OK
11897	2026-09-18 16:51	77.20	OK	11898	2026-09-18 16:52	78.53	OK
11899	2026-09-18 16:53	75.46	OK	11900	2026-09-18 16:54	78.32	OK
11901	2026-09-18 16:55	77.10	OK	11902	2026-09-18 16:56	79.21	OK
11903	2026-09-18 16:57	78.50	OK	11904	2026-09-18 16:58	79.62	OK
11905	2026-09-18 16:59	75.90	OK	11906	2026-09-18 17:00	77.85	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11907	2026-09-18 17:01	77.64	OK	11908	2026-09-18 17:02	79.49	OK
11909	2026-09-18 17:03	76.16	OK	11910	2026-09-18 17:04	77.51	OK
11911	2026-09-18 17:05	78.51	OK	11912	2026-09-18 17:06	77.66	OK
11913	2026-09-18 17:07	79.19	OK	11914	2026-09-18 17:08	77.67	OK
11915	2026-09-18 17:09	77.19	OK	11916	2026-09-18 17:10	74.88	OK
11917	2026-09-18 17:11	79.64	OK	11918	2026-09-18 17:12	78.26	OK
11919	2026-09-18 17:13	75.55	OK	11920	2026-09-18 17:14	77.93	OK
11921	2026-09-18 17:15	77.11	OK	11922	2026-09-18 17:16	75.65	OK
11923	2026-09-18 17:17	77.87	OK	11924	2026-09-18 17:18	76.87	OK
11925	2026-09-18 17:19	75.20	OK	11926	2026-09-18 17:20	78.88	OK
11927	2026-09-18 17:21	75.99	OK	11928	2026-09-18 17:22	74.79	OK
11929	2026-09-18 17:23	77.70	OK	11930	2026-09-18 17:24	74.93	OK
11931	2026-09-18 17:25	78.86	OK	11932	2026-09-18 17:26	77.02	OK
11933	2026-09-18 17:27	76.35	OK	11934	2026-09-18 17:28	78.09	OK
11935	2026-09-18 17:29	75.73	OK	11936	2026-09-18 17:30	75.52	OK
11937	2026-09-18 17:31	75.84	OK	11938	2026-09-18 17:32	79.62	OK
11939	2026-09-18 17:33	78.48	OK	11940	2026-09-18 17:34	76.49	OK
11941	2026-09-18 17:35	75.79	OK	11942	2026-09-18 17:36	75.94	OK
11943	2026-09-18 17:37	78.60	OK	11944	2026-09-18 17:38	78.28	OK
11945	2026-09-18 17:39	76.75	OK	11946	2026-09-18 17:40	75.71	OK
11947	2026-09-18 17:41	76.99	OK	11948	2026-09-18 17:42	77.93	OK
11949	2026-09-18 17:43	76.94	OK	11950	2026-09-18 17:44	76.10	OK
11951	2026-09-18 17:45	76.72	OK	11952	2026-09-18 17:46	78.71	OK
11953	2026-09-18 17:47	78.15	OK	11954	2026-09-18 17:48	77.31	OK
11955	2026-09-18 17:49	74.39	OK	11956	2026-09-18 17:50	76.93	OK
11957	2026-09-18 17:51	76.82	OK	11958	2026-09-18 17:52	76.54	OK
11959	2026-09-18 17:53	75.00	OK	11960	2026-09-18 17:54	77.79	OK
11961	2026-09-18 17:55	75.11	OK	11962	2026-09-18 17:56	77.52	OK
11963	2026-09-18 17:57	76.92	OK	11964	2026-09-18 17:58	74.85	OK
11965	2026-09-18 17:59	78.12	OK	11966	2026-09-18 18:00	77.34	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11967	2026-09-18 18:01	76.05	OK	11968	2026-09-18 18:02	76.24	OK
11969	2026-09-18 18:03	76.63	OK	11970	2026-09-18 18:04	76.69	OK
11971	2026-09-18 18:05	74.89	OK	11972	2026-09-18 18:06	76.60	OK
11973	2026-09-18 18:07	77.52	OK	11974	2026-09-18 18:08	75.19	OK
11975	2026-09-18 18:09	77.76	OK	11976	2026-09-18 18:10	79.87	OK
11977	2026-09-18 18:11	74.14	OK	11978	2026-09-18 18:12	74.52	OK
11979	2026-09-18 18:13	76.77	OK	11980	2026-09-18 18:14	78.41	OK
11981	2026-09-18 18:15	76.78	OK	11982	2026-09-18 18:16	74.86	OK
11983	2026-09-18 18:17	76.32	OK	11984	2026-09-18 18:18	74.23	OK
11985	2026-09-18 18:19	76.15	OK	11986	2026-09-18 18:20	74.68	OK
11987	2026-09-18 18:21	77.23	OK	11988	2026-09-18 18:22	73.69	OK
11989	2026-09-18 18:23	76.76	OK	11990	2026-09-18 18:24	77.07	OK
11991	2026-09-18 18:25	75.74	OK	11992	2026-09-18 18:26	73.40	OK
11993	2026-09-18 18:27	75.44	OK	11994	2026-09-18 18:28	77.47	OK
11995	2026-09-18 18:29	74.97	OK	11996	2026-09-18 18:30	75.96	OK
11997	2026-09-18 18:31	75.51	OK	11998	2026-09-18 18:32	76.46	OK
11999	2026-09-18 18:33	76.46	OK	12000	2026-09-18 18:34	75.57	OK
12001	2026-09-18 18:35	76.13	OK	12002	2026-09-18 18:36	75.19	OK
12003	2026-09-18 18:37	72.65	OK	12004	2026-09-18 18:38	76.10	OK
12005	2026-09-18 18:39	75.10	OK	12006	2026-09-18 18:40	74.57	OK
12007	2026-09-18 18:41	75.34	OK	12008	2026-09-18 18:42	75.84	OK
12009	2026-09-18 18:43	75.78	OK	12010	2026-09-18 18:44	75.93	OK
12011	2026-09-18 18:45	75.40	OK	12012	2026-09-18 18:46	76.00	OK
12013	2026-09-18 18:47	73.36	OK	12014	2026-09-18 18:48	75.60	OK
12015	2026-09-18 18:49	75.30	OK	12016	2026-09-18 18:50	75.08	OK
12017	2026-09-18 18:51	72.28	OK	12018	2026-09-18 18:52	75.60	OK
12019	2026-09-18 18:53	72.03	OK	12020	2026-09-18 18:54	73.50	OK
12021	2026-09-18 18:55	75.65	OK	12022	2026-09-18 18:56	75.52	OK
12023	2026-09-18 18:57	74.10	OK	12024	2026-09-18 18:58	73.40	OK
12025	2026-09-18 18:59	74.81	OK	12026	2026-09-18 19:00	75.36	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12027	2026-09-18 19:01	73.17	OK	12028	2026-09-18 19:02	73.60	OK
12029	2026-09-18 19:03	72.65	OK	12030	2026-09-18 19:04	76.28	OK
12031	2026-09-18 19:05	76.93	OK	12032	2026-09-18 19:06	76.57	OK
12033	2026-09-18 19:07	76.49	OK	12034	2026-09-18 19:08	72.48	OK
12035	2026-09-18 19:09	75.08	OK	12036	2026-09-18 19:10	73.31	OK
12037	2026-09-18 19:11	74.90	OK	12038	2026-09-18 19:12	74.11	OK
12039	2026-09-18 19:13	76.30	OK	12040	2026-09-18 19:14	76.47	OK
12041	2026-09-18 19:15	75.03	OK	12042	2026-09-18 19:16	74.94	OK
12043	2026-09-18 19:17	76.15	OK	12044	2026-09-18 19:18	75.30	OK
12045	2026-09-18 19:19	75.49	OK	12046	2026-09-18 19:20	72.46	OK
12047	2026-09-18 19:21	73.05	OK	12048	2026-09-18 19:22	76.31	OK
12049	2026-09-18 19:23	75.89	OK	12050	2026-09-18 19:24	78.65	OK
12051	2026-09-18 19:25	75.32	OK	12052	2026-09-18 19:26	74.26	OK
12053	2026-09-18 19:27	70.93	OK	12054	2026-09-18 19:28	73.93	OK
12055	2026-09-18 19:29	75.84	OK	12056	2026-09-18 19:30	74.73	OK
12057	2026-09-18 19:31	74.23	OK	12058	2026-09-18 19:32	74.79	OK
12059	2026-09-18 19:33	72.13	OK	12060	2026-09-18 19:34	76.18	OK
12061	2026-09-18 19:35	73.65	OK	12062	2026-09-18 19:36	73.93	OK
12063	2026-09-18 19:37	77.49	OK	12064	2026-09-18 19:38	75.87	OK
12065	2026-09-18 19:39	73.32	OK	12066	2026-09-18 19:40	70.33	OK
12067	2026-09-18 19:41	76.44	OK	12068	2026-09-18 19:42	71.89	OK
12069	2026-09-18 19:43	72.23	OK	12070	2026-09-18 19:44	72.68	OK
12071	2026-09-18 19:45	72.14	OK	12072	2026-09-18 19:46	72.21	OK
12073	2026-09-18 19:47	73.74	OK	12074	2026-09-18 19:48	71.71	OK
12075	2026-09-18 19:49	74.74	OK	12076	2026-09-18 19:50	72.02	OK
12077	2026-09-18 19:51	72.62	OK	12078	2026-09-18 19:52	75.51	OK
12079	2026-09-18 19:53	74.70	OK	12080	2026-09-18 19:54	72.69	OK
12081	2026-09-18 19:55	73.54	OK	12082	2026-09-18 19:56	72.31	OK
12083	2026-09-18 19:57	72.64	OK	12084	2026-09-18 19:58	75.99	OK
12085	2026-09-18 19:59	70.58	OK	12086	2026-09-18 20:00	74.35	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12087	2026-09-18 20:01	75.69	OK	12088	2026-09-18 20:02	75.53	OK
12089	2026-09-18 20:03	75.31	OK	12090	2026-09-18 20:04	71.51	OK
12091	2026-09-18 20:05	70.94	OK	12092	2026-09-18 20:06	72.03	OK
12093	2026-09-18 20:07	76.01	OK	12094	2026-09-18 20:08	75.82	OK
12095	2026-09-18 20:09	74.74	OK	12096	2026-09-18 20:10	70.84	OK
12097	2026-09-18 20:11	75.37	OK	12098	2026-09-18 20:12	74.04	OK
12099	2026-09-18 20:13	72.91	OK	12100	2026-09-18 20:14	72.00	OK
12101	2026-09-18 20:15	73.24	OK	12102	2026-09-18 20:16	75.74	OK
12103	2026-09-18 20:17	75.88	OK	12104	2026-09-18 20:18	73.28	OK
12105	2026-09-18 20:19	71.66	OK	12106	2026-09-18 20:20	74.57	OK
12107	2026-09-18 20:21	73.25	OK	12108	2026-09-18 20:22	72.98	OK
12109	2026-09-18 20:23	69.97	OK	12110	2026-09-18 20:24	73.66	OK
12111	2026-09-18 20:25	73.27	OK	12112	2026-09-18 20:26	73.70	OK
12113	2026-09-18 20:27	71.60	OK	12114	2026-09-18 20:28	75.01	OK
12115	2026-09-18 20:29	71.33	OK	12116	2026-09-18 20:30	71.57	OK
12117	2026-09-18 20:31	74.77	OK	12118	2026-09-18 20:32	72.91	OK
12119	2026-09-18 20:33	70.94	OK	12120	2026-09-18 20:34	71.92	OK
12121	2026-09-18 20:35	73.10	OK	12122	2026-09-18 20:36	71.81	OK
12123	2026-09-18 20:37	73.94	OK	12124	2026-09-18 20:38	72.38	OK
12125	2026-09-18 20:39	69.06	OK	12126	2026-09-18 20:40	74.08	OK
12127	2026-09-18 20:41	72.54	OK	12128	2026-09-18 20:42	72.37	OK
12129	2026-09-18 20:43	72.37	OK	12130	2026-09-18 20:44	70.79	OK
12131	2026-09-18 20:45	72.50	OK	12132	2026-09-18 20:46	73.48	OK
12133	2026-09-18 20:47	71.74	OK	12134	2026-09-18 20:48	71.05	OK
12135	2026-09-18 20:49	73.64	OK	12136	2026-09-18 20:50	69.67	OK
12137	2026-09-18 20:51	73.49	OK	12138	2026-09-18 20:52	72.94	OK
12139	2026-09-18 20:53	71.67	OK	12140	2026-09-18 20:54	71.81	OK
12141	2026-09-18 20:55	72.68	OK	12142	2026-09-18 20:56	72.91	OK
12143	2026-09-18 20:57	73.78	OK	12144	2026-09-18 20:58	72.79	OK
12145	2026-09-18 20:59	72.58	OK	12146	2026-09-18 21:00	72.13	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12147	2026-09-18 21:01	74.34	OK	12148	2026-09-18 21:02	74.87	OK
12149	2026-09-18 21:03	70.62	OK	12150	2026-09-18 21:04	73.97	OK
12151	2026-09-18 21:05	73.93	OK	12152	2026-09-18 21:06	68.41	OK
12153	2026-09-18 21:07	73.01	OK	12154	2026-09-18 21:08	70.61	OK
12155	2026-09-18 21:09	72.75	OK	12156	2026-09-18 21:10	73.04	OK
12157	2026-09-18 21:11	73.58	OK	12158	2026-09-18 21:12	73.34	OK
12159	2026-09-18 21:13	71.41	OK	12160	2026-09-18 21:14	73.03	OK
12161	2026-09-18 21:15	74.22	OK	12162	2026-09-18 21:16	72.89	OK
12163	2026-09-18 21:17	69.84	OK	12164	2026-09-18 21:18	69.58	OK
12165	2026-09-18 21:19	71.65	OK	12166	2026-09-18 21:20	71.28	OK
12167	2026-09-18 21:21	69.35	OK	12168	2026-09-18 21:22	70.57	OK
12169	2026-09-18 21:23	74.81	OK	12170	2026-09-18 21:24	74.77	OK
12171	2026-09-18 21:25	72.59	OK	12172	2026-09-18 21:26	70.52	OK
12173	2026-09-18 21:27	68.26	OK	12174	2026-09-18 21:28	73.81	OK
12175	2026-09-18 21:29	70.80	OK	12176	2026-09-18 21:30	71.57	OK
12177	2026-09-18 21:31	72.79	OK	12178	2026-09-18 21:32	70.43	OK
12179	2026-09-18 21:33	69.98	OK	12180	2026-09-18 21:34	70.68	OK
12181	2026-09-18 21:35	73.88	OK	12182	2026-09-18 21:36	71.67	OK
12183	2026-09-18 21:37	72.47	OK	12184	2026-09-18 21:38	71.75	OK
12185	2026-09-18 21:39	71.50	OK	12186	2026-09-18 21:40	74.49	OK
12187	2026-09-18 21:41	67.34	OK	12188	2026-09-18 21:42	71.65	OK
12189	2026-09-18 21:43	71.82	OK	12190	2026-09-18 21:44	72.28	OK
12191	2026-09-18 21:45	69.67	OK	12192	2026-09-18 21:46	70.79	OK
12193	2026-09-18 21:47	69.38	OK	12194	2026-09-18 21:48	68.34	OK
12195	2026-09-18 21:49	71.08	OK	12196	2026-09-18 21:50	68.31	OK
12197	2026-09-18 21:51	73.34	OK	12198	2026-09-18 21:52	74.02	OK
12199	2026-09-18 21:53	71.31	OK	12200	2026-09-18 21:54	72.21	OK
12201	2026-09-18 21:55	69.26	OK	12202	2026-09-18 21:56	71.92	OK
12203	2026-09-18 21:57	70.38	OK	12204	2026-09-18 21:58	72.31	OK
12205	2026-09-18 21:59	73.33	OK	12206	2026-09-18 22:00	70.99	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12207	2026-09-18 22:01	66.94	OK	12208	2026-09-18 22:02	70.84	OK
12209	2026-09-18 22:03	68.68	OK	12210	2026-09-18 22:04	72.35	OK
12211	2026-09-18 22:05	70.40	OK	12212	2026-09-18 22:06	71.02	OK
12213	2026-09-18 22:07	71.76	OK	12214	2026-09-18 22:08	74.03	OK
12215	2026-09-18 22:09	70.35	OK	12216	2026-09-18 22:10	68.34	OK
12217	2026-09-18 22:11	72.25	OK	12218	2026-09-18 22:12	69.78	OK
12219	2026-09-18 22:13	72.40	OK	12220	2026-09-18 22:14	72.69	OK
12221	2026-09-18 22:15	70.71	OK	12222	2026-09-18 22:16	66.94	OK
12223	2026-09-18 22:17	69.97	OK	12224	2026-09-18 22:18	71.64	OK
12225	2026-09-18 22:19	72.87	OK	12226	2026-09-18 22:20	71.13	OK
12227	2026-09-18 22:21	71.17	OK	12228	2026-09-18 22:22	68.12	OK
12229	2026-09-18 22:23	69.34	OK	12230	2026-09-18 22:24	68.69	OK
12231	2026-09-18 22:25	71.27	OK	12232	2026-09-18 22:26	71.34	OK
12233	2026-09-18 22:27	72.75	OK	12234	2026-09-18 22:28	69.74	OK
12235	2026-09-18 22:29	66.20	OK	12236	2026-09-18 22:30	70.45	OK
12237	2026-09-18 22:31	67.99	OK	12238	2026-09-18 22:32	70.85	OK
12239	2026-09-18 22:33	68.92	OK	12240	2026-09-18 22:34	72.47	OK
12241	2026-09-18 22:35	71.82	OK	12242	2026-09-18 22:36	69.66	OK
12243	2026-09-18 22:37	71.69	OK	12244	2026-09-18 22:38	71.91	OK
12245	2026-09-18 22:39	69.69	OK	12246	2026-09-18 22:40	71.99	OK
12247	2026-09-18 22:41	69.49	OK	12248	2026-09-18 22:42	71.03	OK
12249	2026-09-18 22:43	71.13	OK	12250	2026-09-18 22:44	71.79	OK
12251	2026-09-18 22:45	71.64	OK	12252	2026-09-18 22:46	73.43	OK
12253	2026-09-18 22:47	71.11	OK	12254	2026-09-18 22:48	69.35	OK
12255	2026-09-18 22:49	69.16	OK	12256	2026-09-18 22:50	73.30	OK
12257	2026-09-18 22:51	68.35	OK	12258	2026-09-18 22:52	70.66	OK
12259	2026-09-18 22:53	72.58	OK	12260	2026-09-18 22:54	72.90	OK
12261	2026-09-18 22:55	74.65	OK	12262	2026-09-18 22:56	70.05	OK
12263	2026-09-18 22:57	69.03	OK	12264	2026-09-18 22:58	73.18	OK
12265	2026-09-18 22:59	70.91	OK	12266	2026-09-18 23:00	66.27	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12267	2026-09-18 23:01	73.21	OK	12268	2026-09-18 23:02	69.56	OK
12269	2026-09-18 23:03	70.62	OK	12270	2026-09-18 23:04	71.88	OK
12271	2026-09-18 23:05	70.47	OK	12272	2026-09-18 23:06	70.33	OK
12273	2026-09-18 23:07	67.64	OK	12274	2026-09-18 23:08	68.75	OK
12275	2026-09-18 23:09	68.59	OK	12276	2026-09-18 23:10	68.14	OK
12277	2026-09-18 23:11	69.21	OK	12278	2026-09-18 23:12	71.40	OK
12279	2026-09-18 23:13	70.42	OK	12280	2026-09-18 23:14	71.07	OK
12281	2026-09-18 23:15	71.18	OK	12282	2026-09-18 23:16	68.09	OK
12283	2026-09-18 23:17	70.83	OK	12284	2026-09-18 23:18	67.64	OK
12285	2026-09-18 23:19	72.59	OK	12286	2026-09-18 23:20	67.63	OK
12287	2026-09-18 23:21	68.31	OK	12288	2026-09-18 23:22	66.97	OK
12289	2026-09-18 23:23	70.96	OK	12290	2026-09-18 23:24	71.35	OK
12291	2026-09-18 23:25	67.26	OK	12292	2026-09-18 23:26	70.44	OK
12293	2026-09-18 23:27	71.37	OK	12294	2026-09-18 23:28	70.35	OK
12295	2026-09-18 23:29	69.06	OK	12296	2026-09-18 23:30	71.03	OK
12297	2026-09-18 23:31	72.12	OK	12298	2026-09-18 23:32	67.84	OK
12299	2026-09-18 23:33	69.27	OK	12300	2026-09-18 23:34	69.22	OK
12301	2026-09-18 23:35	70.11	OK	12302	2026-09-18 23:36	66.80	OK
12303	2026-09-18 23:37	67.95	OK	12304	2026-09-18 23:38	70.64	OK
12305	2026-09-18 23:39	70.21	OK	12306	2026-09-18 23:40	71.45	OK
12307	2026-09-18 23:41	66.26	OK	12308	2026-09-18 23:42	69.26	OK
12309	2026-09-18 23:43	67.75	OK	12310	2026-09-18 23:44	66.54	OK
12311	2026-09-18 23:45	66.99	OK	12312	2026-09-18 23:46	70.53	OK
12313	2026-09-18 23:47	70.51	OK	12314	2026-09-18 23:48	66.58	OK
12315	2026-09-18 23:49	68.88	OK	12316	2026-09-18 23:50	68.98	OK
12317	2026-09-18 23:51	69.73	OK	12318	2026-09-18 23:52	69.94	OK
12319	2026-09-18 23:53	70.69	OK	12320	2026-09-18 23:54	66.59	OK
12321	2026-09-18 23:55	66.83	OK	12322	2026-09-18 23:56	67.57	OK
12323	2026-09-18 23:57	70.63	OK	12324	2026-09-18 23:58	68.37	OK
12325	2026-09-18 23:59	69.06	OK	12326	2026-09-19 00:00	71.34	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12327	2026-09-19 00:01	71.51	OK	12328	2026-09-19 00:02	68.99	OK
12329	2026-09-19 00:03	70.60	OK	12330	2026-09-19 00:04	70.10	OK
12331	2026-09-19 00:05	69.85	OK	12332	2026-09-19 00:06	71.82	OK
12333	2026-09-19 00:07	70.96	OK	12334	2026-09-19 00:08	70.88	OK
12335	2026-09-19 00:09	69.63	OK	12336	2026-09-19 00:10	73.10	OK
12337	2026-09-19 00:11	68.63	OK	12338	2026-09-19 00:12	70.51	OK
12339	2026-09-19 00:13	73.56	OK	12340	2026-09-19 00:14	69.48	OK
12341	2026-09-19 00:15	70.96	OK	12342	2026-09-19 00:16	69.72	OK
12343	2026-09-19 00:17	70.36	OK	12344	2026-09-19 00:18	67.59	OK
12345	2026-09-19 00:19	71.23	OK	12346	2026-09-19 00:20	70.98	OK
12347	2026-09-19 00:21	69.02	OK	12348	2026-09-19 00:22	69.70	OK
12349	2026-09-19 00:23	71.85	OK	12350	2026-09-19 00:24	70.33	OK
12351	2026-09-19 00:25	69.73	OK	12352	2026-09-19 00:26	69.51	OK
12353	2026-09-19 00:27	69.54	OK	12354	2026-09-19 00:28	68.43	OK
12355	2026-09-19 00:29	68.52	OK	12356	2026-09-19 00:30	71.74	OK
12357	2026-09-19 00:31	69.80	OK	12358	2026-09-19 00:32	70.85	OK
12359	2026-09-19 00:33	68.87	OK	12360	2026-09-19 00:34	70.73	OK
12361	2026-09-19 00:35	68.98	OK	12362	2026-09-19 00:36	66.69	OK
12363	2026-09-19 00:37	67.82	OK	12364	2026-09-19 00:38	71.70	OK
12365	2026-09-19 00:39	71.00	OK	12366	2026-09-19 00:40	70.40	OK
12367	2026-09-19 00:41	67.32	OK	12368	2026-09-19 00:42	71.29	OK
12369	2026-09-19 00:43	70.05	OK	12370	2026-09-19 00:44	70.38	OK
12371	2026-09-19 00:45	70.21	OK	12372	2026-09-19 00:46	69.68	OK
12373	2026-09-19 00:47	70.95	OK	12374	2026-09-19 00:48	71.11	OK
12375	2026-09-19 00:49	69.78	OK	12376	2026-09-19 00:50	69.39	OK
12377	2026-09-19 00:51	69.43	OK	12378	2026-09-19 00:52	67.90	OK
12379	2026-09-19 00:53	68.42	OK	12380	2026-09-19 00:54	67.35	OK
12381	2026-09-19 00:55	69.86	OK	12382	2026-09-19 00:56	70.77	OK
12383	2026-09-19 00:57	69.54	OK	12384	2026-09-19 00:58	68.07	OK
12385	2026-09-19 00:59	71.21	OK	12386	2026-09-19 01:00	67.18	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12387	2026-09-19 01:01	70.70	OK	12388	2026-09-19 01:02	68.88	OK
12389	2026-09-19 01:03	67.93	OK	12390	2026-09-19 01:04	69.69	OK
12391	2026-09-19 01:05	71.96	OK	12392	2026-09-19 01:06	68.42	OK
12393	2026-09-19 01:07	68.78	OK	12394	2026-09-19 01:08	68.83	OK
12395	2026-09-19 01:09	67.33	OK	12396	2026-09-19 01:10	71.75	OK
12397	2026-09-19 01:11	68.29	OK	12398	2026-09-19 01:12	70.43	OK
12399	2026-09-19 01:13	70.37	OK	12400	2026-09-19 01:14	68.06	OK
12401	2026-09-19 01:15	66.28	OK	12402	2026-09-19 01:16	68.87	OK
12403	2026-09-19 01:17	70.01	OK	12404	2026-09-19 01:18	69.01	OK
12405	2026-09-19 01:19	67.77	OK	12406	2026-09-19 01:20	66.70	OK
12407	2026-09-19 01:21	68.73	OK	12408	2026-09-19 01:22	69.09	OK
12409	2026-09-19 01:23	68.56	OK	12410	2026-09-19 01:24	67.89	OK
12411	2026-09-19 01:25	70.38	OK	12412	2026-09-19 01:26	71.66	OK
12413	2026-09-19 01:27	69.98	OK	12414	2026-09-19 01:28	69.66	OK
12415	2026-09-19 01:29	70.01	OK	12416	2026-09-19 01:30	66.54	OK
12417	2026-09-19 01:31	69.43	OK	12418	2026-09-19 01:32	71.78	OK
12419	2026-09-19 01:33	70.66	OK	12420	2026-09-19 01:34	68.92	OK
12421	2026-09-19 01:35	67.72	OK	12422	2026-09-19 01:36	70.33	OK
12423	2026-09-19 01:37	70.16	OK	12424	2026-09-19 01:38	70.41	OK
12425	2026-09-19 01:39	69.88	OK	12426	2026-09-19 01:40	69.66	OK
12427	2026-09-19 01:41	67.42	OK	12428	2026-09-19 01:42	67.56	OK
12429	2026-09-19 01:43	68.36	OK	12430	2026-09-19 01:44	70.41	OK
12431	2026-09-19 01:45	67.37	OK	12432	2026-09-19 01:46	71.21	OK
12433	2026-09-19 01:47	67.71	OK	12434	2026-09-19 01:48	71.88	OK
12435	2026-09-19 01:49	69.71	OK	12436	2026-09-19 01:50	67.40	OK
12437	2026-09-19 01:51	69.94	OK	12438	2026-09-19 01:52	66.14	OK
12439	2026-09-19 01:53	70.17	OK	12440	2026-09-19 01:54	71.58	OK
12441	2026-09-19 01:55	73.25	OK	12442	2026-09-19 01:56	69.46	OK
12443	2026-09-19 01:57	71.05	OK	12444	2026-09-19 01:58	67.51	OK
12445	2026-09-19 01:59	72.21	OK	12446	2026-09-19 02:00	68.99	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12447	2026-09-19 02:01	71.99	OK	12448	2026-09-19 02:02	67.47	OK
12449	2026-09-19 02:03	66.49	OK	12450	2026-09-19 02:04	69.48	OK
12451	2026-09-19 02:05	70.94	OK	12452	2026-09-19 02:06	67.16	OK
12453	2026-09-19 02:07	71.01	OK	12454	2026-09-19 02:08	70.60	OK
12455	2026-09-19 02:09	71.37	OK	12456	2026-09-19 02:10	69.37	OK
12457	2026-09-19 02:11	70.73	OK	12458	2026-09-19 02:12	71.51	OK
12459	2026-09-19 02:13	69.84	OK	12460	2026-09-19 02:14	71.12	OK
12461	2026-09-19 02:15	72.45	OK	12462	2026-09-19 02:16	69.93	OK
12463	2026-09-19 02:17	71.28	OK	12464	2026-09-19 02:18	70.46	OK
12465	2026-09-19 02:19	67.77	OK	12466	2026-09-19 02:20	69.45	OK
12467	2026-09-19 02:21	68.75	OK	12468	2026-09-19 02:22	71.20	OK
12469	2026-09-19 02:23	73.11	OK	12470	2026-09-19 02:24	69.77	OK
12471	2026-09-19 02:25	70.44	OK	12472	2026-09-19 02:26	69.86	OK
12473	2026-09-19 02:27	67.52	OK	12474	2026-09-19 02:28	71.05	OK
12475	2026-09-19 02:29	68.21	OK	12476	2026-09-19 02:30	67.71	OK
12477	2026-09-19 02:31	66.27	OK	12478	2026-09-19 02:32	71.46	OK
12479	2026-09-19 02:33	70.39	OK	12480	2026-09-19 02:34	70.21	OK
12481	2026-09-19 02:35	69.30	OK	12482	2026-09-19 02:36	67.89	OK
12483	2026-09-19 02:37	70.03	OK	12484	2026-09-19 02:38	70.71	OK
12485	2026-09-19 02:39	69.19	OK	12486	2026-09-19 02:40	69.17	OK
12487	2026-09-19 02:41	68.30	OK	12488	2026-09-19 02:42	71.71	OK
12489	2026-09-19 02:43	68.56	OK	12490	2026-09-19 02:44	71.98	OK
12491	2026-09-19 02:45	70.49	OK	12492	2026-09-19 02:46	69.79	OK
12493	2026-09-19 02:47	70.50	OK	12494	2026-09-19 02:48	68.71	OK
12495	2026-09-19 02:49	70.15	OK	12496	2026-09-19 02:50	67.01	OK
12497	2026-09-19 02:51	71.62	OK	12498	2026-09-19 02:52	70.47	OK
12499	2026-09-19 02:53	66.48	OK	12500	2026-09-19 02:54	69.72	OK
12501	2026-09-19 02:55	72.45	OK	12502	2026-09-19 02:56	72.99	OK
12503	2026-09-19 02:57	69.26	OK	12504	2026-09-19 02:58	68.20	OK
12505	2026-09-19 02:59	69.26	OK	12506	2026-09-19 03:00	70.92	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12507	2026-09-19 03:01	68.26	OK	12508	2026-09-19 03:02	70.67	OK
12509	2026-09-19 03:03	72.72	OK	12510	2026-09-19 03:04	70.55	OK
12511	2026-09-19 03:05	69.35	OK	12512	2026-09-19 03:06	70.75	OK
12513	2026-09-19 03:07	70.42	OK	12514	2026-09-19 03:08	71.03	OK
12515	2026-09-19 03:09	71.37	OK	12516	2026-09-19 03:10	68.35	OK
12517	2026-09-19 03:11	70.75	OK	12518	2026-09-19 03:12	67.62	OK
12519	2026-09-19 03:13	68.42	OK	12520	2026-09-19 03:14	71.66	OK
12521	2026-09-19 03:15	71.38	OK	12522	2026-09-19 03:16	71.49	OK
12523	2026-09-19 03:17	69.49	OK	12524	2026-09-19 03:18	68.69	OK
12525	2026-09-19 03:19	69.09	OK	12526	2026-09-19 03:20	68.65	OK
12527	2026-09-19 03:21	68.93	OK	12528	2026-09-19 03:22	70.00	OK
12529	2026-09-19 03:23	69.22	OK	12530	2026-09-19 03:24	70.32	OK
12531	2026-09-19 03:25	66.49	OK	12532	2026-09-19 03:26	68.25	OK
12533	2026-09-19 03:27	72.46	OK	12534	2026-09-19 03:28	70.41	OK
12535	2026-09-19 03:29	70.32	OK	12536	2026-09-19 03:30	73.28	OK
12537	2026-09-19 03:31	70.04	OK	12538	2026-09-19 03:32	70.01	OK
12539	2026-09-19 03:33	73.21	OK	12540	2026-09-19 03:34	72.33	OK
12541	2026-09-19 03:35	69.51	OK	12542	2026-09-19 03:36	72.98	OK
12543	2026-09-19 03:37	70.86	OK	12544	2026-09-19 03:38	72.50	OK
12545	2026-09-19 03:39	72.27	OK	12546	2026-09-19 03:40	71.32	OK
12547	2026-09-19 03:41	72.85	OK	12548	2026-09-19 03:42	72.65	OK
12549	2026-09-19 03:43	70.94	OK	12550	2026-09-19 03:44	72.21	OK
12551	2026-09-19 03:45	69.03	OK	12552	2026-09-19 03:46	70.83	OK
12553	2026-09-19 03:47	73.79	OK	12554	2026-09-19 03:48	67.55	OK
12555	2026-09-19 03:49	73.88	OK	12556	2026-09-19 03:50	73.49	OK
12557	2026-09-19 03:51	68.19	OK	12558	2026-09-19 03:52	71.69	OK
12559	2026-09-19 03:53	72.83	OK	12560	2026-09-19 03:54	70.36	OK
12561	2026-09-19 03:55	70.88	OK	12562	2026-09-19 03:56	73.52	OK
12563	2026-09-19 03:57	71.46	OK	12564	2026-09-19 03:58	70.23	OK
12565	2026-09-19 03:59	74.82	OK	12566	2026-09-19 04:00	72.90	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12567	2026-09-19 04:01	68.50	OK	12568	2026-09-19 04:02	68.63	OK
12569	2026-09-19 04:03	71.64	OK	12570	2026-09-19 04:04	69.79	OK
12571	2026-09-19 04:05	70.69	OK	12572	2026-09-19 04:06	68.94	OK
12573	2026-09-19 04:07	68.68	OK	12574	2026-09-19 04:08	72.52	OK
12575	2026-09-19 04:09	72.09	OK	12576	2026-09-19 04:10	72.40	OK
12577	2026-09-19 04:11	72.73	OK	12578	2026-09-19 04:12	75.47	OK
12579	2026-09-19 04:13	69.43	OK	12580	2026-09-19 04:14	69.31	OK
12581	2026-09-19 04:15	72.78	OK	12582	2026-09-19 04:16	71.16	OK
12583	2026-09-19 04:17	71.42	OK	12584	2026-09-19 04:18	74.12	OK
12585	2026-09-19 04:19	70.59	OK	12586	2026-09-19 04:20	73.48	OK
12587	2026-09-19 04:21	73.81	OK	12588	2026-09-19 04:22	72.41	OK
12589	2026-09-19 04:23	72.53	OK	12590	2026-09-19 04:24	69.01	OK
12591	2026-09-19 04:25	71.54	OK	12592	2026-09-19 04:26	73.39	OK
12593	2026-09-19 04:27	70.32	OK	12594	2026-09-19 04:28	73.11	OK
12595	2026-09-19 04:29	69.89	OK	12596	2026-09-19 04:30	71.39	OK
12597	2026-09-19 04:31	71.06	OK	12598	2026-09-19 04:32	69.06	OK
12599	2026-09-19 04:33	73.81	OK	12600	2026-09-19 04:34	74.72	OK
12601	2026-09-19 04:35	71.56	OK	12602	2026-09-19 04:36	69.61	OK
12603	2026-09-19 04:37	74.66	OK	12604	2026-09-19 04:38	70.38	OK
12605	2026-09-19 04:39	70.48	OK	12606	2026-09-19 04:40	72.13	OK
12607	2026-09-19 04:41	74.00	OK	12608	2026-09-19 04:42	71.34	OK
12609	2026-09-19 04:43	70.65	OK	12610	2026-09-19 04:44	71.83	OK
12611	2026-09-19 04:45	73.20	OK	12612	2026-09-19 04:46	71.04	OK
12613	2026-09-19 04:47	71.16	OK	12614	2026-09-19 04:48	73.42	OK
12615	2026-09-19 04:49	72.55	OK	12616	2026-09-19 04:50	73.95	OK
12617	2026-09-19 04:51	72.52	OK	12618	2026-09-19 04:52	68.17	OK
12619	2026-09-19 04:53	70.59	OK	12620	2026-09-19 04:54	69.48	OK
12621	2026-09-19 04:55	71.18	OK	12622	2026-09-19 04:56	75.35	OK
12623	2026-09-19 04:57	70.68	OK	12624	2026-09-19 04:58	71.70	OK
12625	2026-09-19 04:59	74.44	OK	12626	2026-09-19 05:00	75.24	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12627	2026-09-19 05:01	69.79	OK	12628	2026-09-19 05:02	73.49	OK
12629	2026-09-19 05:03	73.51	OK	12630	2026-09-19 05:04	71.32	OK
12631	2026-09-19 05:05	72.71	OK	12632	2026-09-19 05:06	71.19	OK
12633	2026-09-19 05:07	74.17	OK	12634	2026-09-19 05:08	73.16	OK
12635	2026-09-19 05:09	72.70	OK	12636	2026-09-19 05:10	75.63	OK
12637	2026-09-19 05:11	72.54	OK	12638	2026-09-19 05:12	71.45	OK
12639	2026-09-19 05:13	74.29	OK	12640	2026-09-19 05:14	71.10	OK
12641	2026-09-19 05:15	73.06	OK	12642	2026-09-19 05:16	73.56	OK
12643	2026-09-19 05:17	69.46	OK	12644	2026-09-19 05:18	75.90	OK
12645	2026-09-19 05:19	74.96	OK	12646	2026-09-19 05:20	70.80	OK
12647	2026-09-19 05:21	72.58	OK	12648	2026-09-19 05:22	71.83	OK
12649	2026-09-19 05:23	70.67	OK	12650	2026-09-19 05:24	72.48	OK
12651	2026-09-19 05:25	70.44	OK	12652	2026-09-19 05:26	68.45	OK
12653	2026-09-19 05:27	75.48	OK	12654	2026-09-19 05:28	72.02	OK
12655	2026-09-19 05:29	74.62	OK	12656	2026-09-19 05:30	70.76	OK
12657	2026-09-19 05:31	71.70	OK	12658	2026-09-19 05:32	74.87	OK
12659	2026-09-19 05:33	72.38	OK	12660	2026-09-19 05:34	73.16	OK
12661	2026-09-19 05:35	73.87	OK	12662	2026-09-19 05:36	72.27	OK
12663	2026-09-19 05:37	71.57	OK	12664	2026-09-19 05:38	72.67	OK
12665	2026-09-19 05:39	73.30	OK	12666	2026-09-19 05:40	73.60	OK
12667	2026-09-19 05:41	74.04	OK	12668	2026-09-19 05:42	72.47	OK
12669	2026-09-19 05:43	74.28	OK	12670	2026-09-19 05:44	73.36	OK
12671	2026-09-19 05:45	71.61	OK	12672	2026-09-19 05:46	71.63	OK
12673	2026-09-19 05:47	69.71	OK	12674	2026-09-19 05:48	73.98	OK
12675	2026-09-19 05:49	73.27	OK	12676	2026-09-19 05:50	75.32	OK
12677	2026-09-19 05:51	74.29	OK	12678	2026-09-19 05:52	72.80	OK
12679	2026-09-19 05:53	71.24	OK	12680	2026-09-19 05:54	73.72	OK
12681	2026-09-19 05:55	74.98	OK	12682	2026-09-19 05:56	71.28	OK
12683	2026-09-19 05:57	75.54	OK	12684	2026-09-19 05:58	74.07	OK
12685	2026-09-19 05:59	75.11	OK	12686	2026-09-19 06:00	74.49	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12687	2026-09-19 06:01	72.46	OK	12688	2026-09-19 06:02	72.69	OK
12689	2026-09-19 06:03	76.96	OK	12690	2026-09-19 06:04	75.63	OK
12691	2026-09-19 06:05	71.57	OK	12692	2026-09-19 06:06	75.19	OK
12693	2026-09-19 06:07	73.65	OK	12694	2026-09-19 06:08	75.94	OK
12695	2026-09-19 06:09	75.60	OK	12696	2026-09-19 06:10	73.83	OK
12697	2026-09-19 06:11	73.28	OK	12698	2026-09-19 06:12	74.37	OK
12699	2026-09-19 06:13	73.33	OK	12700	2026-09-19 06:14	73.64	OK
12701	2026-09-19 06:15	78.61	OK	12702	2026-09-19 06:16	72.20	OK
12703	2026-09-19 06:17	75.11	OK	12704	2026-09-19 06:18	74.01	OK
12705	2026-09-19 06:19	77.09	OK	12706	2026-09-19 06:20	71.82	OK
12707	2026-09-19 06:21	72.13	OK	12708	2026-09-19 06:22	73.01	OK
12709	2026-09-19 06:23	74.11	OK	12710	2026-09-19 06:24	75.38	OK
12711	2026-09-19 06:25	76.12	OK	12712	2026-09-19 06:26	76.00	OK
12713	2026-09-19 06:27	73.92	OK	12714	2026-09-19 06:28	73.41	OK
12715	2026-09-19 06:29	74.38	OK	12716	2026-09-19 06:30	75.80	OK
12717	2026-09-19 06:31	73.47	OK	12718	2026-09-19 06:32	75.66	OK
12719	2026-09-19 06:33	74.21	OK	12720	2026-09-19 06:34	74.98	OK
12721	2026-09-19 06:35	73.14	OK	12722	2026-09-19 06:36	74.05	OK
12723	2026-09-19 06:37	76.01	OK	12724	2026-09-19 06:38	75.27	OK
12725	2026-09-19 06:39	70.93	OK	12726	2026-09-19 06:40	73.49	OK
12727	2026-09-19 06:41	77.30	OK	12728	2026-09-19 06:42	73.81	OK
12729	2026-09-19 06:43	72.99	OK	12730	2026-09-19 06:44	74.95	OK
12731	2026-09-19 06:45	71.40	OK	12732	2026-09-19 06:46	74.50	OK
12733	2026-09-19 06:47	74.12	OK	12734	2026-09-19 06:48	73.20	OK
12735	2026-09-19 06:49	73.50	OK	12736	2026-09-19 06:50	76.47	OK
12737	2026-09-19 06:51	73.24	OK	12738	2026-09-19 06:52	74.10	OK
12739	2026-09-19 06:53	75.45	OK	12740	2026-09-19 06:54	74.41	OK
12741	2026-09-19 06:55	74.99	OK	12742	2026-09-19 06:56	78.26	OK
12743	2026-09-19 06:57	74.20	OK	12744	2026-09-19 06:58	74.63	OK
12745	2026-09-19 06:59	76.50	OK	12746	2026-09-19 07:00	74.89	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12747	2026-09-19 07:01	75.68	OK	12748	2026-09-19 07:02	75.02	OK
12749	2026-09-19 07:03	75.53	OK	12750	2026-09-19 07:04	75.28	OK
12751	2026-09-19 07:05	75.06	OK	12752	2026-09-19 07:06	75.20	OK
12753	2026-09-19 07:07	78.33	OK	12754	2026-09-19 07:08	76.21	OK
12755	2026-09-19 07:09	75.26	OK	12756	2026-09-19 07:10	77.36	OK
12757	2026-09-19 07:11	73.22	OK	12758	2026-09-19 07:12	78.44	OK
12759	2026-09-19 07:13	75.19	OK	12760	2026-09-19 07:14	76.21	OK
12761	2026-09-19 07:15	73.62	OK	12762	2026-09-19 07:16	76.95	OK
12763	2026-09-19 07:17	77.68	OK	12764	2026-09-19 07:18	77.53	OK
12765	2026-09-19 07:19	72.28	OK	12766	2026-09-19 07:20	77.05	OK
12767	2026-09-19 07:21	77.60	OK	12768	2026-09-19 07:22	77.76	OK
12769	2026-09-19 07:23	78.03	OK	12770	2026-09-19 07:24	75.44	OK
12771	2026-09-19 07:25	77.50	OK	12772	2026-09-19 07:26	73.12	OK
12773	2026-09-19 07:27	77.57	OK	12774	2026-09-19 07:28	73.19	OK
12775	2026-09-19 07:29	75.43	OK	12776	2026-09-19 07:30	74.32	OK
12777	2026-09-19 07:31	77.09	OK	12778	2026-09-19 07:32	75.74	OK
12779	2026-09-19 07:33	74.65	OK	12780	2026-09-19 07:34	76.68	OK
12781	2026-09-19 07:35	76.67	OK	12782	2026-09-19 07:36	75.16	OK
12783	2026-09-19 07:37	78.18	OK	12784	2026-09-19 07:38	76.55	OK
12785	2026-09-19 07:39	74.84	OK	12786	2026-09-19 07:40	79.57	OK
12787	2026-09-19 07:41	77.56	OK	12788	2026-09-19 07:42	75.49	OK
12789	2026-09-19 07:43	77.67	OK	12790	2026-09-19 07:44	75.04	OK
12791	2026-09-19 07:45	77.46	OK	12792	2026-09-19 07:46	74.21	OK
12793	2026-09-19 07:47	77.76	OK	12794	2026-09-19 07:48	75.14	OK
12795	2026-09-19 07:49	76.75	OK	12796	2026-09-19 07:50	77.67	OK
12797	2026-09-19 07:51	77.05	OK	12798	2026-09-19 07:52	77.73	OK
12799	2026-09-19 07:53	75.87	OK	12800	2026-09-19 07:54	77.44	OK
12801	2026-09-19 07:55	76.82	OK	12802	2026-09-19 07:56	76.68	OK
12803	2026-09-19 07:57	74.12	OK	12804	2026-09-19 07:58	79.74	OK
12805	2026-09-19 07:59	77.24	OK	12806	2026-09-19 08:00	78.02	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12807	2026-09-19 08:01	78.68	OK	12808	2026-09-19 08:02	74.86	OK
12809	2026-09-19 08:03	76.01	OK	12810	2026-09-19 08:04	79.45	OK
12811	2026-09-19 08:05	76.22	OK	12812	2026-09-19 08:06	78.63	OK
12813	2026-09-19 08:07	74.77	OK	12814	2026-09-19 08:08	75.17	OK
12815	2026-09-19 08:09	73.77	OK	12816	2026-09-19 08:10	77.88	OK
12817	2026-09-19 08:11	78.08	OK	12818	2026-09-19 08:12	74.19	OK
12819	2026-09-19 08:13	78.78	OK	12820	2026-09-19 08:14	75.27	OK
12821	2026-09-19 08:15	75.53	OK	12822	2026-09-19 08:16	77.64	OK
12823	2026-09-19 08:17	76.86	OK	12824	2026-09-19 08:18	77.96	OK
12825	2026-09-19 08:19	77.58	OK	12826	2026-09-19 08:20	76.77	OK
12827	2026-09-19 08:21	75.65	OK	12828	2026-09-19 08:22	79.40	OK
12829	2026-09-19 08:23	74.28	OK	12830	2026-09-19 08:24	78.75	OK
12831	2026-09-19 08:25	77.23	OK	12832	2026-09-19 08:26	77.81	OK
12833	2026-09-19 08:27	79.30	OK	12834	2026-09-19 08:28	75.46	OK
12835	2026-09-19 08:29	78.22	OK	12836	2026-09-19 08:30	77.55	OK
12837	2026-09-19 08:31	77.58	OK	12838	2026-09-19 08:32	77.41	OK
12839	2026-09-19 08:33	75.45	OK	12840	2026-09-19 08:34	76.41	OK
12841	2026-09-19 08:35	75.96	OK	12842	2026-09-19 08:36	76.75	OK
12843	2026-09-19 08:37	77.90	OK	12844	2026-09-19 08:38	75.00	OK
12845	2026-09-19 08:39	78.36	OK	12846	2026-09-19 08:40	79.35	OK
12847	2026-09-19 08:41	76.49	OK	12848	2026-09-19 08:42	78.23	OK
12849	2026-09-19 08:43	78.18	OK	12850	2026-09-19 08:44	80.70	OK
12851	2026-09-19 08:45	76.57	OK	12852	2026-09-19 08:46	74.43	OK
12853	2026-09-19 08:47	77.10	OK	12854	2026-09-19 08:48	78.34	OK
12855	2026-09-19 08:49	75.78	OK	12856	2026-09-19 08:50	77.69	OK
12857	2026-09-19 08:51	81.14	OK	12858	2026-09-19 08:52	75.73	OK
12859	2026-09-19 08:53	79.79	OK	12860	2026-09-19 08:54	80.22	OK
12861	2026-09-19 08:55	81.21	OK	12862	2026-09-19 08:56	80.04	OK
12863	2026-09-19 08:57	79.21	OK	12864	2026-09-19 08:58	80.08	OK
12865	2026-09-19 08:59	78.31	OK	12866	2026-09-19 09:00	75.94	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12867	2026-09-19 09:01	77.14	OK	12868	2026-09-19 09:02	76.60	OK
12869	2026-09-19 09:03	80.01	OK	12870	2026-09-19 09:04	79.59	OK
12871	2026-09-19 09:05	77.19	OK	12872	2026-09-19 09:06	79.48	OK
12873	2026-09-19 09:07	80.84	OK	12874	2026-09-19 09:08	79.70	OK
12875	2026-09-19 09:09	77.69	OK	12876	2026-09-19 09:10	82.33	OK
12877	2026-09-19 09:11	76.12	OK	12878	2026-09-19 09:12	78.05	OK
12879	2026-09-19 09:13	77.70	OK	12880	2026-09-19 09:14	79.10	OK
12881	2026-09-19 09:15	78.50	OK	12882	2026-09-19 09:16	79.86	OK
12883	2026-09-19 09:17	77.90	OK	12884	2026-09-19 09:18	81.32	OK
12885	2026-09-19 09:19	76.99	OK	12886	2026-09-19 09:20	82.16	OK
12887	2026-09-19 09:21	77.14	OK	12888	2026-09-19 09:22	74.79	OK
12889	2026-09-19 09:23	78.81	OK	12890	2026-09-19 09:24	79.09	OK
12891	2026-09-19 09:25	78.96	OK	12892	2026-09-19 09:26	80.76	OK
12893	2026-09-19 09:27	77.30	OK	12894	2026-09-19 09:28	81.20	OK
12895	2026-09-19 09:29	79.71	OK	12896	2026-09-19 09:30	78.09	OK
12897	2026-09-19 09:31	79.54	OK	12898	2026-09-19 09:32	77.66	OK
12899	2026-09-19 09:33	78.56	OK	12900	2026-09-19 09:34	78.66	OK
12901	2026-09-19 09:35	79.11	OK	12902	2026-09-19 09:36	80.51	OK
12903	2026-09-19 09:37	79.96	OK	12904	2026-09-19 09:38	79.47	OK
12905	2026-09-19 09:39	79.44	OK	12906	2026-09-19 09:40	80.95	OK
12907	2026-09-19 09:41	77.86	OK	12908	2026-09-19 09:42	81.22	OK
12909	2026-09-19 09:43	77.78	OK	12910	2026-09-19 09:44	78.55	OK
12911	2026-09-19 09:45	81.06	OK	12912	2026-09-19 09:46	80.39	OK
12913	2026-09-19 09:47	77.44	OK	12914	2026-09-19 09:48	80.70	OK
12915	2026-09-19 09:49	80.30	OK	12916	2026-09-19 09:50	78.59	OK
12917	2026-09-19 09:51	76.93	OK	12918	2026-09-19 09:52	80.58	OK
12919	2026-09-19 09:53	81.43	OK	12920	2026-09-19 09:54	81.30	OK
12921	2026-09-19 09:55	76.48	OK	12922	2026-09-19 09:56	79.31	OK
12923	2026-09-19 09:57	80.55	OK	12924	2026-09-19 09:58	80.47	OK
12925	2026-09-19 09:59	81.72	OK	12926	2026-09-19 10:00	78.73	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12927	2026-09-19 10:01	76.72	OK	12928	2026-09-19 10:02	78.81	OK
12929	2026-09-19 10:03	80.50	OK	12930	2026-09-19 10:04	79.68	OK
12931	2026-09-19 10:05	79.78	OK	12932	2026-09-19 10:06	79.80	OK
12933	2026-09-19 10:07	79.40	OK	12934	2026-09-19 10:08	82.56	OK
12935	2026-09-19 10:09	80.43	OK	12936	2026-09-19 10:10	79.67	OK
12937	2026-09-19 10:11	81.31	OK	12938	2026-09-19 10:12	78.10	OK
12939	2026-09-19 10:13	79.82	OK	12940	2026-09-19 10:14	81.44	OK
12941	2026-09-19 10:15	80.07	OK	12942	2026-09-19 10:16	78.94	OK
12943	2026-09-19 10:17	80.25	OK	12944	2026-09-19 10:18	76.29	OK
12945	2026-09-19 10:19	79.78	OK	12946	2026-09-19 10:20	81.57	OK
12947	2026-09-19 10:21	78.93	OK	12948	2026-09-19 10:22	79.94	OK
12949	2026-09-19 10:23	77.38	OK	12950	2026-09-19 10:24	79.73	OK
12951	2026-09-19 10:25	82.06	OK	12952	2026-09-19 10:26	81.31	OK
12953	2026-09-19 10:27	78.50	OK	12954	2026-09-19 10:28	76.52	OK
12955	2026-09-19 10:29	82.30	OK	12956	2026-09-19 10:30	78.77	OK
12957	2026-09-19 10:31	80.50	OK	12958	2026-09-19 10:32	80.47	OK
12959	2026-09-19 10:33	79.24	OK	12960	2026-09-19 10:34	80.63	OK
12961	2026-09-19 10:35	81.75	OK	12962	2026-09-19 10:36	79.86	OK
12963	2026-09-19 10:37	79.39	OK	12964	2026-09-19 10:38	78.40	OK
12965	2026-09-19 10:39	80.78	OK	12966	2026-09-19 10:40	79.23	OK
12967	2026-09-19 10:41	79.03	OK	12968	2026-09-19 10:42	81.66	OK
12969	2026-09-19 10:43	76.31	OK	12970	2026-09-19 10:44	80.75	OK
12971	2026-09-19 10:45	79.05	OK	12972	2026-09-19 10:46	80.96	OK
12973	2026-09-19 10:47	80.27	OK	12974	2026-09-19 10:48	81.75	OK
12975	2026-09-19 10:49	79.43	OK	12976	2026-09-19 10:50	76.06	OK
12977	2026-09-19 10:51	80.97	OK	12978	2026-09-19 10:52	81.53	OK
12979	2026-09-19 10:53	79.51	OK	12980	2026-09-19 10:54	83.02	OK
12981	2026-09-19 10:55	82.68	OK	12982	2026-09-19 10:56	80.63	OK
12983	2026-09-19 10:57	83.37	OK	12984	2026-09-19 10:58	80.62	OK
12985	2026-09-19 10:59	83.54	OK	12986	2026-09-19 11:00	77.46	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12987	2026-09-19 11:01	81.32	OK	12988	2026-09-19 11:02	82.33	OK
12989	2026-09-19 11:03	76.91	OK	12990	2026-09-19 11:04	80.52	OK
12991	2026-09-19 11:05	79.77	OK	12992	2026-09-19 11:06	81.65	OK
12993	2026-09-19 11:07	81.44	OK	12994	2026-09-19 11:08	81.84	OK
12995	2026-09-19 11:09	78.09	OK	12996	2026-09-19 11:10	82.46	OK
12997	2026-09-19 11:11	78.45	OK	12998	2026-09-19 11:12	82.11	OK
12999	2026-09-19 11:13	80.72	OK	13000	2026-09-19 11:14	80.06	OK
13001	2026-09-19 11:15	80.11	OK	13002	2026-09-19 11:16	79.80	OK
13003	2026-09-19 11:17	81.49	OK	13004	2026-09-19 11:18	81.75	OK
13005	2026-09-19 11:19	82.71	OK	13006	2026-09-19 11:20	79.22	OK
13007	2026-09-19 11:21	80.28	OK	13008	2026-09-19 11:22	76.87	OK
13009	2026-09-19 11:23	78.56	OK	13010	2026-09-19 11:24	80.11	OK
13011	2026-09-19 11:25	81.69	OK	13012	2026-09-19 11:26	83.29	OK
13013	2026-09-19 11:27	81.80	OK	13014	2026-09-19 11:28	78.46	OK
13015	2026-09-19 11:29	84.52	OK	13016	2026-09-19 11:30	78.77	OK
13017	2026-09-19 11:31	81.41	OK	13018	2026-09-19 11:32	79.96	OK
13019	2026-09-19 11:33	76.52	OK	13020	2026-09-19 11:34	80.68	OK
13021	2026-09-19 11:35	83.26	OK	13022	2026-09-19 11:36	79.50	OK
13023	2026-09-19 11:37	80.25	OK	13024	2026-09-19 11:38	82.64	OK
13025	2026-09-19 11:39	81.54	OK	13026	2026-09-19 11:40	83.44	OK
13027	2026-09-19 11:41	79.98	OK	13028	2026-09-19 11:42	82.42	OK
13029	2026-09-19 11:43	82.30	OK	13030	2026-09-19 11:44	83.12	OK
13031	2026-09-19 11:45	82.05	OK	13032	2026-09-19 11:46	81.16	OK
13033	2026-09-19 11:47	82.73	OK	13034	2026-09-19 11:48	78.79	OK
13035	2026-09-19 11:49	78.53	OK	13036	2026-09-19 11:50	82.04	OK
13037	2026-09-19 11:51	79.04	OK	13038	2026-09-19 11:52	83.31	OK
13039	2026-09-19 11:53	79.29	OK	13040	2026-09-19 11:54	80.70	OK
13041	2026-09-19 11:55	76.88	OK	13042	2026-09-19 11:56	81.27	OK
13043	2026-09-19 11:57	82.21	OK	13044	2026-09-19 11:58	79.74	OK
13045	2026-09-19 11:59	80.89	OK	13046	2026-09-19 12:00	82.42	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13047	2026-09-19 12:01	81.93	OK	13048	2026-09-19 12:02	83.76	OK
13049	2026-09-19 12:03	80.65	OK	13050	2026-09-19 12:04	77.38	OK
13051	2026-09-19 12:05	80.32	OK	13052	2026-09-19 12:06	82.56	OK
13053	2026-09-19 12:07	80.07	OK	13054	2026-09-19 12:08	82.30	OK
13055	2026-09-19 12:09	78.94	OK	13056	2026-09-19 12:10	80.56	OK
13057	2026-09-19 12:11	80.34	OK	13058	2026-09-19 12:12	82.64	OK
13059	2026-09-19 12:13	81.11	OK	13060	2026-09-19 12:14	79.52	OK
13061	2026-09-19 12:15	82.45	OK	13062	2026-09-19 12:16	80.88	OK
13063	2026-09-19 12:17	81.76	OK	13064	2026-09-19 12:18	78.95	OK
13065	2026-09-19 12:19	78.95	OK	13066	2026-09-19 12:20	80.12	OK
13067	2026-09-19 12:21	81.02	OK	13068	2026-09-19 12:22	78.34	OK
13069	2026-09-19 12:23	81.70	OK	13070	2026-09-19 12:24	80.36	OK
13071	2026-09-19 12:25	82.25	OK	13072	2026-09-19 12:26	80.93	OK
13073	2026-09-19 12:27	79.19	OK	13074	2026-09-19 12:28	79.64	OK
13075	2026-09-19 12:29	82.14	OK	13076	2026-09-19 12:30	82.20	OK
13077	2026-09-19 12:31	77.43	OK	13078	2026-09-19 12:32	78.24	OK
13079	2026-09-19 12:33	79.38	OK	13080	2026-09-19 12:34	80.37	OK
13081	2026-09-19 12:35	80.04	OK	13082	2026-09-19 12:36	82.04	OK
13083	2026-09-19 12:37	77.85	OK	13084	2026-09-19 12:38	80.31	OK
13085	2026-09-19 12:39	77.75	OK	13086	2026-09-19 12:40	79.69	OK
13087	2026-09-19 12:41	81.48	OK	13088	2026-09-19 12:42	80.00	OK
13089	2026-09-19 12:43	82.31	OK	13090	2026-09-19 12:44	80.16	OK
13091	2026-09-19 12:45	78.70	OK	13092	2026-09-19 12:46	80.59	OK
13093	2026-09-19 12:47	80.83	OK	13094	2026-09-19 12:48	77.81	OK
13095	2026-09-19 12:49	80.96	OK	13096	2026-09-19 12:50	80.15	OK
13097	2026-09-19 12:51	81.48	OK	13098	2026-09-19 12:52	80.51	OK
13099	2026-09-19 12:53	81.51	OK	13100	2026-09-19 12:54	81.77	OK
13101	2026-09-19 12:55	79.54	OK	13102	2026-09-19 12:56	84.12	OK
13103	2026-09-19 12:57	78.92	OK	13104	2026-09-19 12:58	77.84	OK
13105	2026-09-19 12:59	82.27	OK	13106	2026-09-19 13:00	80.27	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13107	2026-09-19 13:01	82.10	OK	13108	2026-09-19 13:02	78.99	OK
13109	2026-09-19 13:03	81.27	OK	13110	2026-09-19 13:04	79.13	OK
13111	2026-09-19 13:05	81.48	OK	13112	2026-09-19 13:06	79.24	OK
13113	2026-09-19 13:07	80.56	OK	13114	2026-09-19 13:08	80.76	OK
13115	2026-09-19 13:09	79.92	OK	13116	2026-09-19 13:10	79.45	OK
13117	2026-09-19 13:11	84.29	OK	13118	2026-09-19 13:12	80.62	OK
13119	2026-09-19 13:13	82.11	OK	13120	2026-09-19 13:14	80.89	OK
13121	2026-09-19 13:15	81.38	OK	13122	2026-09-19 13:16	80.78	OK
13123	2026-09-19 13:17	84.04	OK	13124	2026-09-19 13:18	80.06	OK
13125	2026-09-19 13:19	81.69	OK	13126	2026-09-19 13:20	80.68	OK
13127	2026-09-19 13:21	81.64	OK	13128	2026-09-19 13:22	82.02	OK
13129	2026-09-19 13:23	80.41	OK	13130	2026-09-19 13:24	81.92	OK
13131	2026-09-19 13:25	81.22	OK	13132	2026-09-19 13:26	83.19	OK
13133	2026-09-19 13:27	83.53	OK	13134	2026-09-19 13:28	83.38	OK
13135	2026-09-19 13:29	78.78	OK	13136	2026-09-19 13:30	81.07	OK
13137	2026-09-19 13:31	81.40	OK	13138	2026-09-19 13:32	83.30	OK
13139	2026-09-19 13:33	83.08	OK	13140	2026-09-19 13:34	78.10	OK
13141	2026-09-19 13:35	78.65	OK	13142	2026-09-19 13:36	77.41	OK
13143	2026-09-19 13:37	84.63	OK	13144	2026-09-19 13:38	81.40	OK
13145	2026-09-19 13:39	77.54	OK	13146	2026-09-19 13:40	82.73	OK
13147	2026-09-19 13:41	79.00	OK	13148	2026-09-19 13:42	84.63	OK
13149	2026-09-19 13:43	81.27	OK	13150	2026-09-19 13:44	82.65	OK
13151	2026-09-19 13:45	79.51	OK	13152	2026-09-19 13:46	80.73	OK
13153	2026-09-19 13:47	80.62	OK	13154	2026-09-19 13:48	81.11	OK
13155	2026-09-19 13:49	80.27	OK	13156	2026-09-19 13:50	81.25	OK
13157	2026-09-19 13:51	82.46	OK	13158	2026-09-19 13:52	82.25	OK
13159	2026-09-19 13:53	81.09	OK	13160	2026-09-19 13:54	83.15	OK
13161	2026-09-19 13:55	80.90	OK	13162	2026-09-19 13:56	78.92	OK
13163	2026-09-19 13:57	80.31	OK	13164	2026-09-19 13:58	79.85	OK
13165	2026-09-19 13:59	81.97	OK	13166	2026-09-19 14:00	81.96	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13167	2026-09-19 14:01	82.94	OK	13168	2026-09-19 14:02	80.79	OK
13169	2026-09-19 14:03	83.56	OK	13170	2026-09-19 14:04	82.93	OK
13171	2026-09-19 14:05	81.48	OK	13172	2026-09-19 14:06	82.76	OK
13173	2026-09-19 14:07	79.06	OK	13174	2026-09-19 14:08	80.17	OK
13175	2026-09-19 14:09	83.52	OK	13176	2026-09-19 14:10	79.90	OK
13177	2026-09-19 14:11	82.41	OK	13178	2026-09-19 14:12	80.28	OK
13179	2026-09-19 14:13	80.84	OK	13180	2026-09-19 14:14	81.29	OK
13181	2026-09-19 14:15	80.20	OK	13182	2026-09-19 14:16	82.14	OK
13183	2026-09-19 14:17	81.40	OK	13184	2026-09-19 14:18	80.86	OK
13185	2026-09-19 14:19	81.26	OK	13186	2026-09-19 14:20	81.12	OK
13187	2026-09-19 14:21	81.74	OK	13188	2026-09-19 14:22	78.22	OK
13189	2026-09-19 14:23	80.91	OK	13190	2026-09-19 14:24	79.54	OK
13191	2026-09-19 14:25	80.42	OK	13192	2026-09-19 14:26	81.31	OK
13193	2026-09-19 14:27	79.26	OK	13194	2026-09-19 14:28	78.74	OK
13195	2026-09-19 14:29	79.73	OK	13196	2026-09-19 14:30	81.25	OK
13197	2026-09-19 14:31	82.22	OK	13198	2026-09-19 14:32	81.91	OK
13199	2026-09-19 14:33	80.28	OK	13200	2026-09-19 14:34	82.67	OK
13201	2026-09-19 14:35	80.59	OK	13202	2026-09-19 14:36	80.68	OK
13203	2026-09-19 14:37	79.43	OK	13204	2026-09-19 14:38	78.05	OK
13205	2026-09-19 14:39	76.54	OK	13206	2026-09-19 14:40	79.86	OK
13207	2026-09-19 14:41	79.46	OK	13208	2026-09-19 14:42	83.41	OK
13209	2026-09-19 14:43	80.19	OK	13210	2026-09-19 14:44	80.97	OK
13211	2026-09-19 14:45	78.89	OK	13212	2026-09-19 14:46	76.11	OK
13213	2026-09-19 14:47	79.87	OK	13214	2026-09-19 14:48	79.71	OK
13215	2026-09-19 14:49	79.30	OK	13216	2026-09-19 14:50	82.40	OK
13217	2026-09-19 14:51	77.19	OK	13218	2026-09-19 14:52	82.20	OK
13219	2026-09-19 14:53	77.62	OK	13220	2026-09-19 14:54	78.30	OK
13221	2026-09-19 14:55	76.60	OK	13222	2026-09-19 14:56	81.65	OK
13223	2026-09-19 14:57	80.36	OK	13224	2026-09-19 14:58	80.67	OK
13225	2026-09-19 14:59	78.30	OK	13226	2026-09-19 15:00	82.13	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13227	2026-09-19 15:01	77.91	OK	13228	2026-09-19 15:02	79.26	OK
13229	2026-09-19 15:03	78.44	OK	13230	2026-09-19 15:04	80.22	OK
13231	2026-09-19 15:05	80.21	OK	13232	2026-09-19 15:06	80.86	OK
13233	2026-09-19 15:07	78.25	OK	13234	2026-09-19 15:08	80.82	OK
13235	2026-09-19 15:09	81.75	OK	13236	2026-09-19 15:10	80.15	OK
13237	2026-09-19 15:11	78.75	OK	13238	2026-09-19 15:12	81.59	OK
13239	2026-09-19 15:13	79.26	OK	13240	2026-09-19 15:14	79.61	OK
13241	2026-09-19 15:15	79.07	OK	13242	2026-09-19 15:16	80.06	OK
13243	2026-09-19 15:17	80.90	OK	13244	2026-09-19 15:18	78.45	OK
13245	2026-09-19 15:19	80.14	OK	13246	2026-09-19 15:20	83.67	OK
13247	2026-09-19 15:21	80.30	OK	13248	2026-09-19 15:22	78.48	OK
13249	2026-09-19 15:23	78.08	OK	13250	2026-09-19 15:24	80.43	OK
13251	2026-09-19 15:25	77.07	OK	13252	2026-09-19 15:26	81.36	OK
13253	2026-09-19 15:27	77.21	OK	13254	2026-09-19 15:28	78.38	OK
13255	2026-09-19 15:29	79.45	OK	13256	2026-09-19 15:30	81.97	OK
13257	2026-09-19 15:31	78.29	OK	13258	2026-09-19 15:32	79.75	OK
13259	2026-09-19 15:33	78.36	OK	13260	2026-09-19 15:34	80.49	OK
13261	2026-09-19 15:35	79.33	OK	13262	2026-09-19 15:36	81.09	OK
13263	2026-09-19 15:37	80.28	OK	13264	2026-09-19 15:38	81.15	OK
13265	2026-09-19 15:39	81.70	OK	13266	2026-09-19 15:40	77.90	OK
13267	2026-09-19 15:41	77.94	OK	13268	2026-09-19 15:42	78.54	OK
13269	2026-09-19 15:43	80.80	OK	13270	2026-09-19 15:44	79.10	OK
13271	2026-09-19 15:45	81.55	OK	13272	2026-09-19 15:46	80.28	OK
13273	2026-09-19 15:47	81.08	OK	13274	2026-09-19 15:48	77.46	OK
13275	2026-09-19 15:49	79.51	OK	13276	2026-09-19 15:50	78.39	OK
13277	2026-09-19 15:51	78.45	OK	13278	2026-09-19 15:52	78.04	OK
13279	2026-09-19 15:53	79.38	OK	13280	2026-09-19 15:54	79.77	OK
13281	2026-09-19 15:55	80.65	OK	13282	2026-09-19 15:56	79.48	OK
13283	2026-09-19 15:57	78.80	OK	13284	2026-09-19 15:58	79.37	OK
13285	2026-09-19 15:59	81.02	OK	13286	2026-09-19 16:00	79.30	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13287	2026-09-19 16:01	81.43	OK	13288	2026-09-19 16:02	77.07	OK
13289	2026-09-19 16:03	78.67	OK	13290	2026-09-19 16:04	79.34	OK
13291	2026-09-19 16:05	78.76	OK	13292	2026-09-19 16:06	78.99	OK
13293	2026-09-19 16:07	80.35	OK	13294	2026-09-19 16:08	80.76	OK
13295	2026-09-19 16:09	79.21	OK	13296	2026-09-19 16:10	81.26	OK
13297	2026-09-19 16:11	77.68	OK	13298	2026-09-19 16:12	78.38	OK
13299	2026-09-19 16:13	77.02	OK	13300	2026-09-19 16:14	76.53	OK
13301	2026-09-19 16:15	77.85	OK	13302	2026-09-19 16:16	78.55	OK
13303	2026-09-19 16:17	77.72	OK	13304	2026-09-19 16:18	79.83	OK
13305	2026-09-19 16:19	77.92	OK	13306	2026-09-19 16:20	82.97	OK
13307	2026-09-19 16:21	79.16	OK	13308	2026-09-19 16:22	78.30	OK
13309	2026-09-19 16:23	77.48	OK	13310	2026-09-19 16:24	78.83	OK
13311	2026-09-19 16:25	78.64	OK	13312	2026-09-19 16:26	77.21	OK
13313	2026-09-19 16:27	81.64	OK	13314	2026-09-19 16:28	78.15	OK
13315	2026-09-19 16:29	77.27	OK	13316	2026-09-19 16:30	79.25	OK
13317	2026-09-19 16:31	78.28	OK	13318	2026-09-19 16:32	77.62	OK
13319	2026-09-19 16:33	77.49	OK	13320	2026-09-19 16:34	78.19	OK
13321	2026-09-19 16:35	76.65	OK	13322	2026-09-19 16:36	76.46	OK
13323	2026-09-19 16:37	76.36	OK	13324	2026-09-19 16:38	79.20	OK
13325	2026-09-19 16:39	81.03	OK	13326	2026-09-19 16:40	80.06	OK
13327	2026-09-19 16:41	76.11	OK	13328	2026-09-19 16:42	80.26	OK
13329	2026-09-19 16:43	77.56	OK	13330	2026-09-19 16:44	77.42	OK
13331	2026-09-19 16:45	78.99	OK	13332	2026-09-19 16:46	79.23	OK
13333	2026-09-19 16:47	76.20	OK	13334	2026-09-19 16:48	77.45	OK
13335	2026-09-19 16:49	77.59	OK	13336	2026-09-19 16:50	78.23	OK
13337	2026-09-19 16:51	76.19	OK	13338	2026-09-19 16:52	78.98	OK
13339	2026-09-19 16:53	76.51	OK	13340	2026-09-19 16:54	78.69	OK
13341	2026-09-19 16:55	78.46	OK	13342	2026-09-19 16:56	78.76	OK
13343	2026-09-19 16:57	78.21	OK	13344	2026-09-19 16:58	75.90	OK
13345	2026-09-19 16:59	78.96	OK	13346	2026-09-19 17:00	79.12	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13347	2026-09-19 17:01	77.61	OK	13348	2026-09-19 17:02	80.62	OK
13349	2026-09-19 17:03	79.66	OK	13350	2026-09-19 17:04	76.76	OK
13351	2026-09-19 17:05	76.11	OK	13352	2026-09-19 17:06	78.93	OK
13353	2026-09-19 17:07	79.61	OK	13354	2026-09-19 17:08	76.50	OK
13355	2026-09-19 17:09	76.86	OK	13356	2026-09-19 17:10	76.28	OK
13357	2026-09-19 17:11	80.68	OK	13358	2026-09-19 17:12	80.74	OK
13359	2026-09-19 17:13	78.28	OK	13360	2026-09-19 17:14	79.40	OK
13361	2026-09-19 17:15	77.73	OK	13362	2026-09-19 17:16	76.39	OK
13363	2026-09-19 17:17	77.91	OK	13364	2026-09-19 17:18	76.99	OK
13365	2026-09-19 17:19	80.98	OK	13366	2026-09-19 17:20	74.19	OK
13367	2026-09-19 17:21	78.16	OK	13368	2026-09-19 17:22	76.59	OK
13369	2026-09-19 17:23	79.50	OK	13370	2026-09-19 17:24	75.13	OK
13371	2026-09-19 17:25	76.58	OK	13372	2026-09-19 17:26	76.64	OK
13373	2026-09-19 17:27	75.62	OK	13374	2026-09-19 17:28	79.04	OK
13375	2026-09-19 17:29	78.97	OK	13376	2026-09-19 17:30	78.38	OK
13377	2026-09-19 17:31	76.88	OK	13378	2026-09-19 17:32	76.93	OK
13379	2026-09-19 17:33	74.83	OK	13380	2026-09-19 17:34	77.81	OK
13381	2026-09-19 17:35	75.64	OK	13382	2026-09-19 17:36	77.93	OK
13383	2026-09-19 17:37	75.71	OK	13384	2026-09-19 17:38	76.12	OK
13385	2026-09-19 17:39	75.14	OK	13386	2026-09-19 17:40	77.05	OK
13387	2026-09-19 17:41	75.21	OK	13388	2026-09-19 17:42	78.04	OK
13389	2026-09-19 17:43	76.04	OK	13390	2026-09-19 17:44	77.53	OK
13391	2026-09-19 17:45	76.70	OK	13392	2026-09-19 17:46	78.46	OK
13393	2026-09-19 17:47	78.94	OK	13394	2026-09-19 17:48	77.58	OK
13395	2026-09-19 17:49	74.12	OK	13396	2026-09-19 17:50	77.40	OK
13397	2026-09-19 17:51	76.85	OK	13398	2026-09-19 17:52	77.07	OK
13399	2026-09-19 17:53	77.39	OK	13400	2026-09-19 17:54	74.61	OK
13401	2026-09-19 17:55	76.49	OK	13402	2026-09-19 17:56	74.23	OK
13403	2026-09-19 17:57	75.14	OK	13404	2026-09-19 17:58	76.44	OK
13405	2026-09-19 17:59	77.46	OK	13406	2026-09-19 18:00	78.13	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13407	2026-09-19 18:01	76.68	OK	13408	2026-09-19 18:02	75.37	OK
13409	2026-09-19 18:03	78.91	OK	13410	2026-09-19 18:04	77.49	OK
13411	2026-09-19 18:05	77.46	OK	13412	2026-09-19 18:06	75.18	OK
13413	2026-09-19 18:07	77.29	OK	13414	2026-09-19 18:08	73.45	OK
13415	2026-09-19 18:09	75.38	OK	13416	2026-09-19 18:10	74.50	OK
13417	2026-09-19 18:11	79.00	OK	13418	2026-09-19 18:12	75.98	OK
13419	2026-09-19 18:13	76.88	OK	13420	2026-09-19 18:14	75.71	OK
13421	2026-09-19 18:15	77.32	OK	13422	2026-09-19 18:16	77.31	OK
13423	2026-09-19 18:17	76.09	OK	13424	2026-09-19 18:18	78.81	OK
13425	2026-09-19 18:19	76.94	OK	13426	2026-09-19 18:20	75.51	OK
13427	2026-09-19 18:21	77.39	OK	13428	2026-09-19 18:22	74.25	OK
13429	2026-09-19 18:23	74.65	OK	13430	2026-09-19 18:24	76.01	OK
13431	2026-09-19 18:25	77.41	OK	13432	2026-09-19 18:26	76.78	OK
13433	2026-09-19 18:27	73.31	OK	13434	2026-09-19 18:28	77.98	OK
13435	2026-09-19 18:29	76.62	OK	13436	2026-09-19 18:30	75.25	OK
13437	2026-09-19 18:31	75.14	OK	13438	2026-09-19 18:32	75.08	OK
13439	2026-09-19 18:33	73.30	OK	13440	2026-09-19 18:34	77.03	OK
13441	2026-09-19 18:35	75.41	OK	13442	2026-09-19 18:36	73.63	OK
13443	2026-09-19 18:37	75.33	OK	13444	2026-09-19 18:38	77.68	OK
13445	2026-09-19 18:39	76.18	OK	13446	2026-09-19 18:40	74.42	OK
13447	2026-09-19 18:41	77.19	OK	13448	2026-09-19 18:42	74.67	OK
13449	2026-09-19 18:43	75.44	OK	13450	2026-09-19 18:44	71.91	OK
13451	2026-09-19 18:45	72.79	OK	13452	2026-09-19 18:46	75.42	OK
13453	2026-09-19 18:47	74.06	OK	13454	2026-09-19 18:48	72.16	OK
13455	2026-09-19 18:49	72.26	OK	13456	2026-09-19 18:50	74.20	OK
13457	2026-09-19 18:51	77.42	OK	13458	2026-09-19 18:52	74.82	OK
13459	2026-09-19 18:53	73.74	OK	13460	2026-09-19 18:54	73.28	OK
13461	2026-09-19 18:55	71.93	OK	13462	2026-09-19 18:56	76.96	OK
13463	2026-09-19 18:57	74.80	OK	13464	2026-09-19 18:58	74.94	OK
13465	2026-09-19 18:59	74.01	OK	13466	2026-09-19 19:00	76.14	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13467	2026-09-19 19:01	77.27	OK	13468	2026-09-19 19:02	76.28	OK
13469	2026-09-19 19:03	75.46	OK	13470	2026-09-19 19:04	76.05	OK
13471	2026-09-19 19:05	76.59	OK	13472	2026-09-19 19:06	77.85	OK
13473	2026-09-19 19:07	74.04	OK	13474	2026-09-19 19:08	74.44	OK
13475	2026-09-19 19:09	74.86	OK	13476	2026-09-19 19:10	74.00	OK
13477	2026-09-19 19:11	70.73	OK	13478	2026-09-19 19:12	76.04	OK
13479	2026-09-19 19:13	73.21	OK	13480	2026-09-19 19:14	74.60	OK
13481	2026-09-19 19:15	75.43	OK	13482	2026-09-19 19:16	70.98	OK
13483	2026-09-19 19:17	74.28	OK	13484	2026-09-19 19:18	73.30	OK
13485	2026-09-19 19:19	76.27	OK	13486	2026-09-19 19:20	75.13	OK
13487	2026-09-19 19:21	74.94	OK	13488	2026-09-19 19:22	73.26	OK
13489	2026-09-19 19:23	76.49	OK	13490	2026-09-19 19:24	70.13	OK
13491	2026-09-19 19:25	73.22	OK	13492	2026-09-19 19:26	76.69	OK
13493	2026-09-19 19:27	76.36	OK	13494	2026-09-19 19:28	74.41	OK
13495	2026-09-19 19:29	75.62	OK	13496	2026-09-19 19:30	74.69	OK
13497	2026-09-19 19:31	71.23	OK	13498	2026-09-19 19:32	73.07	OK
13499	2026-09-19 19:33	73.06	OK	13500	2026-09-19 19:34	75.75	OK
13501	2026-09-19 19:35	75.85	OK	13502	2026-09-19 19:36	74.37	OK
13503	2026-09-19 19:37	73.51	OK	13504	2026-09-19 19:38	76.11	OK
13505	2026-09-19 19:39	75.49	OK	13506	2026-09-19 19:40	71.66	OK
13507	2026-09-19 19:41	72.68	OK	13508	2026-09-19 19:42	72.61	OK
13509	2026-09-19 19:43	75.23	OK	13510	2026-09-19 19:44	71.74	OK
13511	2026-09-19 19:45	74.48	OK	13512	2026-09-19 19:46	72.47	OK
13513	2026-09-19 19:47	70.50	OK	13514	2026-09-19 19:48	76.13	OK
13515	2026-09-19 19:49	71.90	OK	13516	2026-09-19 19:50	69.19	OK
13517	2026-09-19 19:51	72.30	OK	13518	2026-09-19 19:52	75.37	OK
13519	2026-09-19 19:53	73.13	OK	13520	2026-09-19 19:54	73.40	OK
13521	2026-09-19 19:55	72.65	OK	13522	2026-09-19 19:56	76.23	OK
13523	2026-09-19 19:57	73.57	OK	13524	2026-09-19 19:58	74.77	OK
13525	2026-09-19 19:59	71.87	OK	13526	2026-09-19 20:00	74.30	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13527	2026-09-19 20:01	71.42	OK	13528	2026-09-19 20:02	74.71	OK
13529	2026-09-19 20:03	71.16	OK	13530	2026-09-19 20:04	73.99	OK
13531	2026-09-19 20:05	74.95	OK	13532	2026-09-19 20:06	74.28	OK
13533	2026-09-19 20:07	74.51	OK	13534	2026-09-19 20:08	73.41	OK
13535	2026-09-19 20:09	72.73	OK	13536	2026-09-19 20:10	75.70	OK
13537	2026-09-19 20:11	74.83	OK	13538	2026-09-19 20:12	72.05	OK
13539	2026-09-19 20:13	70.37	OK	13540	2026-09-19 20:14	72.05	OK
13541	2026-09-19 20:15	71.11	OK	13542	2026-09-19 20:16	73.26	OK
13543	2026-09-19 20:17	69.91	OK	13544	2026-09-19 20:18	74.50	OK
13545	2026-09-19 20:19	73.40	OK	13546	2026-09-19 20:20	72.27	OK
13547	2026-09-19 20:21	73.68	OK	13548	2026-09-19 20:22	72.97	OK
13549	2026-09-19 20:23	74.00	OK	13550	2026-09-19 20:24	77.05	OK
13551	2026-09-19 20:25	71.55	OK	13552	2026-09-19 20:26	72.11	OK
13553	2026-09-19 20:27	76.63	OK	13554	2026-09-19 20:28	71.81	OK
13555	2026-09-19 20:29	75.22	OK	13556	2026-09-19 20:30	72.00	OK
13557	2026-09-19 20:31	72.06	OK	13558	2026-09-19 20:32	74.29	OK
13559	2026-09-19 20:33	70.91	OK	13560	2026-09-19 20:34	72.13	OK
13561	2026-09-19 20:35	73.99	OK	13562	2026-09-19 20:36	73.13	OK
13563	2026-09-19 20:37	70.76	OK	13564	2026-09-19 20:38	72.93	OK
13565	2026-09-19 20:39	70.60	OK	13566	2026-09-19 20:40	74.85	OK
13567	2026-09-19 20:41	72.61	OK	13568	2026-09-19 20:42	72.70	OK
13569	2026-09-19 20:43	72.58	OK	13570	2026-09-19 20:44	74.33	OK
13571	2026-09-19 20:45	73.66	OK	13572	2026-09-19 20:46	72.46	OK
13573	2026-09-19 20:47	75.78	OK	13574	2026-09-19 20:48	71.83	OK
13575	2026-09-19 20:49	73.42	OK	13576	2026-09-19 20:50	73.28	OK
13577	2026-09-19 20:51	72.56	OK	13578	2026-09-19 20:52	70.51	OK
13579	2026-09-19 20:53	73.26	OK	13580	2026-09-19 20:54	74.64	OK
13581	2026-09-19 20:55	72.60	OK	13582	2026-09-19 20:56	71.70	OK
13583	2026-09-19 20:57	70.32	OK	13584	2026-09-19 20:58	71.69	OK
13585	2026-09-19 20:59	72.89	OK	13586	2026-09-19 21:00	71.18	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13587	2026-09-19 21:01	75.16	OK	13588	2026-09-19 21:02	73.17	OK
13589	2026-09-19 21:03	74.16	OK	13590	2026-09-19 21:04	71.13	OK
13591	2026-09-19 21:05	72.34	OK	13592	2026-09-19 21:06	72.82	OK
13593	2026-09-19 21:07	71.88	OK	13594	2026-09-19 21:08	73.38	OK
13595	2026-09-19 21:09	71.33	OK	13596	2026-09-19 21:10	70.17	OK
13597	2026-09-19 21:11	72.00	OK	13598	2026-09-19 21:12	73.90	OK
13599	2026-09-19 21:13	72.53	OK	13600	2026-09-19 21:14	72.62	OK
13601	2026-09-19 21:15	69.47	OK	13602	2026-09-19 21:16	71.06	OK
13603	2026-09-19 21:17	73.75	OK	13604	2026-09-19 21:18	70.70	OK
13605	2026-09-19 21:19	69.01	OK	13606	2026-09-19 21:20	73.66	OK
13607	2026-09-19 21:21	68.22	OK	13608	2026-09-19 21:22	73.86	OK
13609	2026-09-19 21:23	72.54	OK	13610	2026-09-19 21:24	72.41	OK
13611	2026-09-19 21:25	69.02	OK	13612	2026-09-19 21:26	72.16	OK
13613	2026-09-19 21:27	70.46	OK	13614	2026-09-19 21:28	69.60	OK
13615	2026-09-19 21:29	71.00	OK	13616	2026-09-19 21:30	70.59	OK
13617	2026-09-19 21:31	71.34	OK	13618	2026-09-19 21:32	71.04	OK
13619	2026-09-19 21:33	72.24	OK	13620	2026-09-19 21:34	72.19	OK
13621	2026-09-19 21:35	70.84	OK	13622	2026-09-19 21:36	70.41	OK
13623	2026-09-19 21:37	70.71	OK	13624	2026-09-19 21:38	71.60	OK
13625	2026-09-19 21:39	73.30	OK	13626	2026-09-19 21:40	71.02	OK
13627	2026-09-19 21:41	73.55	OK	13628	2026-09-19 21:42	72.40	OK
13629	2026-09-19 21:43	68.57	OK	13630	2026-09-19 21:44	71.09	OK
13631	2026-09-19 21:45	70.72	OK	13632	2026-09-19 21:46	72.84	OK
13633	2026-09-19 21:47	70.31	OK	13634	2026-09-19 21:48	70.38	OK
13635	2026-09-19 21:49	69.40	OK	13636	2026-09-19 21:50	72.87	OK
13637	2026-09-19 21:51	70.25	OK	13638	2026-09-19 21:52	73.48	OK
13639	2026-09-19 21:53	70.81	OK	13640	2026-09-19 21:54	73.36	OK
13641	2026-09-19 21:55	69.26	OK	13642	2026-09-19 21:56	73.21	OK
13643	2026-09-19 21:57	69.13	OK	13644	2026-09-19 21:58	69.89	OK
13645	2026-09-19 21:59	68.64	OK	13646	2026-09-19 22:00	73.01	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13647	2026-09-19 22:01	69.39	OK	13648	2026-09-19 22:02	72.60	OK
13649	2026-09-19 22:03	70.82	OK	13650	2026-09-19 22:04	69.36	OK
13651	2026-09-19 22:05	69.70	OK	13652	2026-09-19 22:06	70.98	OK
13653	2026-09-19 22:07	69.10	OK	13654	2026-09-19 22:08	70.30	OK
13655	2026-09-19 22:09	70.49	OK	13656	2026-09-19 22:10	71.46	OK
13657	2026-09-19 22:11	69.13	OK	13658	2026-09-19 22:12	75.40	OK
13659	2026-09-19 22:13	73.66	OK	13660	2026-09-19 22:14	70.81	OK
13661	2026-09-19 22:15	72.79	OK	13662	2026-09-19 22:16	69.96	OK
13663	2026-09-19 22:17	69.38	OK	13664	2026-09-19 22:18	70.45	OK
13665	2026-09-19 22:19	73.44	OK	13666	2026-09-19 22:20	68.74	OK
13667	2026-09-19 22:21	69.54	OK	13668	2026-09-19 22:22	69.50	OK
13669	2026-09-19 22:23	70.81	OK	13670	2026-09-19 22:24	71.67	OK
13671	2026-09-19 22:25	70.70	OK	13672	2026-09-19 22:26	66.00	OK
13673	2026-09-19 22:27	69.06	OK	13674	2026-09-19 22:28	72.32	OK
13675	2026-09-19 22:29	68.68	OK	13676	2026-09-19 22:30	67.57	OK
13677	2026-09-19 22:31	67.89	OK	13678	2026-09-19 22:32	69.50	OK
13679	2026-09-19 22:33	70.56	OK	13680	2026-09-19 22:34	71.33	OK
13681	2026-09-19 22:35	69.90	OK	13682	2026-09-19 22:36	69.29	OK
13683	2026-09-19 22:37	68.90	OK	13684	2026-09-19 22:38	70.54	OK
13685	2026-09-19 22:39	70.74	OK	13686	2026-09-19 22:40	73.48	OK
13687	2026-09-19 22:41	73.22	OK	13688	2026-09-19 22:42	71.02	OK
13689	2026-09-19 22:43	71.91	OK	13690	2026-09-19 22:44	69.94	OK
13691	2026-09-19 22:45	69.35	OK	13692	2026-09-19 22:46	68.74	OK
13693	2026-09-19 22:47	72.31	OK	13694	2026-09-19 22:48	72.98	OK
13695	2026-09-19 22:49	72.43	OK	13696	2026-09-19 22:50	73.12	OK
13697	2026-09-19 22:51	69.98	OK	13698	2026-09-19 22:52	68.88	OK
13699	2026-09-19 22:53	71.16	OK	13700	2026-09-19 22:54	69.24	OK
13701	2026-09-19 22:55	69.34	OK	13702	2026-09-19 22:56	71.74	OK
13703	2026-09-19 22:57	68.32	OK	13704	2026-09-19 22:58	69.71	OK
13705	2026-09-19 22:59	70.83	OK	13706	2026-09-19 23:00	71.11	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13707	2026-09-19 23:01	69.38	OK	13708	2026-09-19 23:02	70.12	OK
13709	2026-09-19 23:03	70.40	OK	13710	2026-09-19 23:04	72.22	OK
13711	2026-09-19 23:05	68.97	OK	13712	2026-09-19 23:06	72.32	OK
13713	2026-09-19 23:07	70.43	OK	13714	2026-09-19 23:08	70.41	OK
13715	2026-09-19 23:09	68.08	OK	13716	2026-09-19 23:10	70.47	OK
13717	2026-09-19 23:11	71.58	OK	13718	2026-09-19 23:12	71.20	OK
13719	2026-09-19 23:13	71.26	OK	13720	2026-09-19 23:14	69.24	OK
13721	2026-09-19 23:15	70.68	OK	13722	2026-09-19 23:16	66.54	OK
13723	2026-09-19 23:17	73.11	OK	13724	2026-09-19 23:18	69.19	OK
13725	2026-09-19 23:19	71.10	OK	13726	2026-09-19 23:20	72.25	OK
13727	2026-09-19 23:21	69.05	OK	13728	2026-09-19 23:22	70.48	OK
13729	2026-09-19 23:23	67.29	OK	13730	2026-09-19 23:24	68.98	OK
13731	2026-09-19 23:25	71.58	OK	13732	2026-09-19 23:26	68.69	OK
13733	2026-09-19 23:27	68.49	OK	13734	2026-09-19 23:28	68.89	OK
13735	2026-09-19 23:29	70.65	OK	13736	2026-09-19 23:30	70.98	OK
13737	2026-09-19 23:31	72.26	OK	13738	2026-09-19 23:32	70.41	OK
13739	2026-09-19 23:33	71.14	OK	13740	2026-09-19 23:34	71.41	OK
13741	2026-09-19 23:35	67.51	OK	13742	2026-09-19 23:36	70.74	OK
13743	2026-09-19 23:37	70.26	OK	13744	2026-09-19 23:38	70.43	OK
13745	2026-09-19 23:39	70.50	OK	13746	2026-09-19 23:40	69.14	OK
13747	2026-09-19 23:41	70.52	OK	13748	2026-09-19 23:42	70.23	OK
13749	2026-09-19 23:43	68.56	OK	13750	2026-09-19 23:44	69.26	OK
13751	2026-09-19 23:45	70.37	OK	13752	2026-09-19 23:46	71.24	OK
13753	2026-09-19 23:47	71.78	OK	13754	2026-09-19 23:48	69.78	OK
13755	2026-09-19 23:49	72.47	OK	13756	2026-09-19 23:50	70.22	OK
13757	2026-09-19 23:51	71.58	OK	13758	2026-09-19 23:52	72.58	OK
13759	2026-09-19 23:53	68.63	OK	13760	2026-09-19 23:54	70.83	OK
13761	2026-09-19 23:55	69.49	OK	13762	2026-09-19 23:56	68.44	OK
13763	2026-09-19 23:57	67.89	OK	13764	2026-09-19 23:58	70.65	OK
13765	2026-09-19 23:59	69.53	OK	13766	2026-09-20 00:00	71.73	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13767	2026-09-20 00:01	69.92	OK	13768	2026-09-20 00:02	72.54	OK
13769	2026-09-20 00:03	71.71	OK	13770	2026-09-20 00:04	71.85	OK
13771	2026-09-20 00:05	68.63	OK	13772	2026-09-20 00:06	70.76	OK
13773	2026-09-20 00:07	70.52	OK	13774	2026-09-20 00:08	69.17	OK
13775	2026-09-20 00:09	71.19	OK	13776	2026-09-20 00:10	70.13	OK
13777	2026-09-20 00:11	68.33	OK	13778	2026-09-20 00:12	70.97	OK
13779	2026-09-20 00:13	70.14	OK	13780	2026-09-20 00:14	69.94	OK
13781	2026-09-20 00:15	71.77	OK	13782	2026-09-20 00:16	68.25	OK
13783	2026-09-20 00:17	70.78	OK	13784	2026-09-20 00:18	69.11	OK
13785	2026-09-20 00:19	72.32	OK	13786	2026-09-20 00:20	66.96	OK
13787	2026-09-20 00:21	71.05	OK	13788	2026-09-20 00:22	70.59	OK
13789	2026-09-20 00:23	70.17	OK	13790	2026-09-20 00:24	72.89	OK
13791	2026-09-20 00:25	71.49	OK	13792	2026-09-20 00:26	70.19	OK
13793	2026-09-20 00:27	70.81	OK	13794	2026-09-20 00:28	67.16	OK
13795	2026-09-20 00:29	67.43	OK	13796	2026-09-20 00:30	69.79	OK
13797	2026-09-20 00:31	70.10	OK	13798	2026-09-20 00:32	67.63	OK
13799	2026-09-20 00:33	65.58	OK	13800	2026-09-20 00:34	70.91	OK
13801	2026-09-20 00:35	69.88	OK	13802	2026-09-20 00:36	67.16	OK
13803	2026-09-20 00:37	69.04	OK	13804	2026-09-20 00:38	68.72	OK
13805	2026-09-20 00:39	67.43	OK	13806	2026-09-20 00:40	67.70	OK
13807	2026-09-20 00:41	71.64	OK	13808	2026-09-20 00:42	69.72	OK
13809	2026-09-20 00:43	66.86	OK	13810	2026-09-20 00:44	70.80	OK
13811	2026-09-20 00:45	70.48	OK	13812	2026-09-20 00:46	69.72	OK
13813	2026-09-20 00:47	72.00	OK	13814	2026-09-20 00:48	70.74	OK
13815	2026-09-20 00:49	69.26	OK	13816	2026-09-20 00:50	72.81	OK
13817	2026-09-20 00:51	67.73	OK	13818	2026-09-20 00:52	68.10	OK
13819	2026-09-20 00:53	69.29	OK	13820	2026-09-20 00:54	68.96	OK
13821	2026-09-20 00:55	68.93	OK	13822	2026-09-20 00:56	66.77	OK
13823	2026-09-20 00:57	70.73	OK	13824	2026-09-20 00:58	69.23	OK
13825	2026-09-20 00:59	68.56	OK	13826	2026-09-20 01:00	70.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13827	2026-09-20 01:01	70.40	OK	13828	2026-09-20 01:02	69.67	OK
13829	2026-09-20 01:03	67.05	OK	13830	2026-09-20 01:04	70.01	OK
13831	2026-09-20 01:05	67.39	OK	13832	2026-09-20 01:06	71.38	OK
13833	2026-09-20 01:07	68.35	OK	13834	2026-09-20 01:08	68.00	OK
13835	2026-09-20 01:09	70.50	OK	13836	2026-09-20 01:10	69.36	OK
13837	2026-09-20 01:11	66.39	OK	13838	2026-09-20 01:12	66.77	OK
13839	2026-09-20 01:13	70.33	OK	13840	2026-09-20 01:14	69.38	OK
13841	2026-09-20 01:15	70.24	OK	13842	2026-09-20 01:16	70.16	OK
13843	2026-09-20 01:17	68.24	OK	13844	2026-09-20 01:18	70.01	OK
13845	2026-09-20 01:19	72.09	OK	13846	2026-09-20 01:20	65.53	OK
13847	2026-09-20 01:21	69.25	OK	13848	2026-09-20 01:22	69.59	OK
13849	2026-09-20 01:23	69.97	OK	13850	2026-09-20 01:24	65.40	OK
13851	2026-09-20 01:25	68.48	OK	13852	2026-09-20 01:26	68.32	OK
13853	2026-09-20 01:27	67.67	OK	13854	2026-09-20 01:28	69.85	OK
13855	2026-09-20 01:29	65.92	OK	13856	2026-09-20 01:30	69.62	OK
13857	2026-09-20 01:31	68.82	OK	13858	2026-09-20 01:32	68.19	OK
13859	2026-09-20 01:33	68.38	OK	13860	2026-09-20 01:34	71.32	OK
13861	2026-09-20 01:35	70.48	OK	13862	2026-09-20 01:36	68.23	OK
13863	2026-09-20 01:37	69.41	OK	13864	2026-09-20 01:38	71.23	OK
13865	2026-09-20 01:39	69.20	OK	13866	2026-09-20 01:40	68.28	OK
13867	2026-09-20 01:41	69.70	OK	13868	2026-09-20 01:42	68.77	OK
13869	2026-09-20 01:43	68.10	OK	13870	2026-09-20 01:44	68.93	OK
13871	2026-09-20 01:45	68.29	OK	13872	2026-09-20 01:46	66.04	OK
13873	2026-09-20 01:47	68.66	OK	13874	2026-09-20 01:48	67.97	OK
13875	2026-09-20 01:49	68.66	OK	13876	2026-09-20 01:50	67.14	OK
13877	2026-09-20 01:51	70.13	OK	13878	2026-09-20 01:52	71.52	OK
13879	2026-09-20 01:53	68.44	OK	13880	2026-09-20 01:54	68.21	OK
13881	2026-09-20 01:55	68.77	OK	13882	2026-09-20 01:56	71.07	OK
13883	2026-09-20 01:57	68.33	OK	13884	2026-09-20 01:58	72.12	OK
13885	2026-09-20 01:59	69.60	OK	13886	2026-09-20 02:00	69.59	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13887	2026-09-20 02:01	68.97	OK	13888	2026-09-20 02:02	67.48	OK
13889	2026-09-20 02:03	69.09	OK	13890	2026-09-20 02:04	69.19	OK
13891	2026-09-20 02:05	69.64	OK	13892	2026-09-20 02:06	68.74	OK
13893	2026-09-20 02:07	71.06	OK	13894	2026-09-20 02:08	71.02	OK
13895	2026-09-20 02:09	69.71	OK	13896	2026-09-20 02:10	66.58	OK
13897	2026-09-20 02:11	69.42	OK	13898	2026-09-20 02:12	67.53	OK
13899	2026-09-20 02:13	66.19	OK	13900	2026-09-20 02:14	71.72	OK
13901	2026-09-20 02:15	68.03	OK	13902	2026-09-20 02:16	70.26	OK
13903	2026-09-20 02:17	69.52	OK	13904	2026-09-20 02:18	69.18	OK
13905	2026-09-20 02:19	69.79	OK	13906	2026-09-20 02:20	70.33	OK
13907	2026-09-20 02:21	69.98	OK	13908	2026-09-20 02:22	73.51	OK
13909	2026-09-20 02:23	71.25	OK	13910	2026-09-20 02:24	67.83	OK
13911	2026-09-20 02:25	67.55	OK	13912	2026-09-20 02:26	69.27	OK
13913	2026-09-20 02:27	68.98	OK	13914	2026-09-20 02:28	69.89	OK
13915	2026-09-20 02:29	70.73	OK	13916	2026-09-20 02:30	67.11	OK
13917	2026-09-20 02:31	70.41	OK	13918	2026-09-20 02:32	69.71	OK
13919	2026-09-20 02:33	70.65	OK	13920	2026-09-20 02:34	70.19	OK
13921	2026-09-20 02:35	67.70	OK	13922	2026-09-20 02:36	71.28	OK
13923	2026-09-20 02:37	72.50	OK	13924	2026-09-20 02:38	69.32	OK
13925	2026-09-20 02:39	70.73	OK	13926	2026-09-20 02:40	69.74	OK
13927	2026-09-20 02:41	72.66	OK	13928	2026-09-20 02:42	69.50	OK
13929	2026-09-20 02:43	69.32	OK	13930	2026-09-20 02:44	69.64	OK
13931	2026-09-20 02:45	69.63	OK	13932	2026-09-20 02:46	66.97	OK
13933	2026-09-20 02:47	68.29	OK	13934	2026-09-20 02:48	71.17	OK
13935	2026-09-20 02:49	72.08	OK	13936	2026-09-20 02:50	68.80	OK
13937	2026-09-20 02:51	70.04	OK	13938	2026-09-20 02:52	72.14	OK
13939	2026-09-20 02:53	66.92	OK	13940	2026-09-20 02:54	71.05	OK
13941	2026-09-20 02:55	67.52	OK	13942	2026-09-20 02:56	73.18	OK
13943	2026-09-20 02:57	70.53	OK	13944	2026-09-20 02:58	68.23	OK
13945	2026-09-20 02:59	71.81	OK	13946	2026-09-20 03:00	67.65	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13947	2026-09-20 03:01	72.17	OK	13948	2026-09-20 03:02	67.88	OK
13949	2026-09-20 03:03	71.77	OK	13950	2026-09-20 03:04	66.47	OK
13951	2026-09-20 03:05	71.11	OK	13952	2026-09-20 03:06	70.90	OK
13953	2026-09-20 03:07	71.50	OK	13954	2026-09-20 03:08	69.22	OK
13955	2026-09-20 03:09	70.05	OK	13956	2026-09-20 03:10	72.53	OK
13957	2026-09-20 03:11	70.45	OK	13958	2026-09-20 03:12	67.42	OK
13959	2026-09-20 03:13	72.65	OK	13960	2026-09-20 03:14	68.70	OK
13961	2026-09-20 03:15	72.13	OK	13962	2026-09-20 03:16	71.12	OK
13963	2026-09-20 03:17	71.02	OK	13964	2026-09-20 03:18	69.32	OK
13965	2026-09-20 03:19	69.70	OK	13966	2026-09-20 03:20	71.89	OK
13967	2026-09-20 03:21	69.82	OK	13968	2026-09-20 03:22	70.02	OK
13969	2026-09-20 03:23	71.85	OK	13970	2026-09-20 03:24	67.45	OK
13971	2026-09-20 03:25	70.67	OK	13972	2026-09-20 03:26	70.65	OK
13973	2026-09-20 03:27	70.80	OK	13974	2026-09-20 03:28	69.82	OK
13975	2026-09-20 03:29	69.78	OK	13976	2026-09-20 03:30	73.53	OK
13977	2026-09-20 03:31	66.96	OK	13978	2026-09-20 03:32	70.97	OK
13979	2026-09-20 03:33	73.90	OK	13980	2026-09-20 03:34	67.57	OK
13981	2026-09-20 03:35	71.37	OK	13982	2026-09-20 03:36	72.92	OK
13983	2026-09-20 03:37	69.73	OK	13984	2026-09-20 03:38	67.56	OK
13985	2026-09-20 03:39	67.12	OK	13986	2026-09-20 03:40	69.38	OK
13987	2026-09-20 03:41	71.33	OK	13988	2026-09-20 03:42	72.93	OK
13989	2026-09-20 03:43	67.81	OK	13990	2026-09-20 03:44	73.42	OK
13991	2026-09-20 03:45	73.02	OK	13992	2026-09-20 03:46	70.10	OK
13993	2026-09-20 03:47	70.94	OK	13994	2026-09-20 03:48	68.91	OK
13995	2026-09-20 03:49	71.37	OK	13996	2026-09-20 03:50	69.61	OK
13997	2026-09-20 03:51	70.18	OK	13998	2026-09-20 03:52	68.61	OK
13999	2026-09-20 03:53	70.86	OK	14000	2026-09-20 03:54	70.70	OK
14001	2026-09-20 03:55	71.78	OK	14002	2026-09-20 03:56	72.78	OK
14003	2026-09-20 03:57	72.80	OK	14004	2026-09-20 03:58	71.23	OK
14005	2026-09-20 03:59	70.97	OK	14006	2026-09-20 04:00	67.68	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14007	2026-09-20 04:01	68.76	OK	14008	2026-09-20 04:02	69.47	OK
14009	2026-09-20 04:03	69.41	OK	14010	2026-09-20 04:04	70.96	OK
14011	2026-09-20 04:05	68.69	OK	14012	2026-09-20 04:06	73.29	OK
14013	2026-09-20 04:07	72.50	OK	14014	2026-09-20 04:08	70.17	OK
14015	2026-09-20 04:09	71.51	OK	14016	2026-09-20 04:10	70.15	OK
14017	2026-09-20 04:11	70.66	OK	14018	2026-09-20 04:12	71.23	OK
14019	2026-09-20 04:13	70.16	OK	14020	2026-09-20 04:14	71.12	OK
14021	2026-09-20 04:15	70.14	OK	14022	2026-09-20 04:16	73.47	OK
14023	2026-09-20 04:17	72.76	OK	14024	2026-09-20 04:18	68.67	OK
14025	2026-09-20 04:19	71.52	OK	14026	2026-09-20 04:20	69.41	OK
14027	2026-09-20 04:21	70.44	OK	14028	2026-09-20 04:22	74.56	OK
14029	2026-09-20 04:23	73.26	OK	14030	2026-09-20 04:24	71.84	OK
14031	2026-09-20 04:25	70.70	OK	14032	2026-09-20 04:26	72.96	OK
14033	2026-09-20 04:27	73.49	OK	14034	2026-09-20 04:28	70.85	OK
14035	2026-09-20 04:29	72.88	OK	14036	2026-09-20 04:30	70.85	OK
14037	2026-09-20 04:31	71.79	OK	14038	2026-09-20 04:32	70.99	OK
14039	2026-09-20 04:33	70.90	OK	14040	2026-09-20 04:34	72.17	OK
14041	2026-09-20 04:35	73.20	OK	14042	2026-09-20 04:36	73.19	OK
14043	2026-09-20 04:37	75.01	OK	14044	2026-09-20 04:38	69.45	OK
14045	2026-09-20 04:39	71.30	OK	14046	2026-09-20 04:40	72.27	OK
14047	2026-09-20 04:41	74.40	OK	14048	2026-09-20 04:42	71.58	OK
14049	2026-09-20 04:43	73.82	OK	14050	2026-09-20 04:44	73.99	OK
14051	2026-09-20 04:45	75.48	OK	14052	2026-09-20 04:46	70.14	OK
14053	2026-09-20 04:47	73.37	OK	14054	2026-09-20 04:48	70.93	OK
14055	2026-09-20 04:49	71.98	OK	14056	2026-09-20 04:50	73.76	OK
14057	2026-09-20 04:51	75.02	OK	14058	2026-09-20 04:52	70.71	OK
14059	2026-09-20 04:53	69.06	OK	14060	2026-09-20 04:54	71.40	OK
14061	2026-09-20 04:55	73.85	OK	14062	2026-09-20 04:56	73.09	OK
14063	2026-09-20 04:57	74.00	OK	14064	2026-09-20 04:58	72.32	OK
14065	2026-09-20 04:59	74.59	OK	14066	2026-09-20 05:00	75.79	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14067	2026-09-20 05:01	71.88	OK	14068	2026-09-20 05:02	74.82	OK
14069	2026-09-20 05:03	71.67	OK	14070	2026-09-20 05:04	73.34	OK
14071	2026-09-20 05:05	73.65	OK	14072	2026-09-20 05:06	70.55	OK
14073	2026-09-20 05:07	71.95	OK	14074	2026-09-20 05:08	71.92	OK
14075	2026-09-20 05:09	72.82	OK	14076	2026-09-20 05:10	71.60	OK
14077	2026-09-20 05:11	73.00	OK	14078	2026-09-20 05:12	71.24	OK
14079	2026-09-20 05:13	74.41	OK	14080	2026-09-20 05:14	74.45	OK
14081	2026-09-20 05:15	73.21	OK	14082	2026-09-20 05:16	72.25	OK
14083	2026-09-20 05:17	73.81	OK	14084	2026-09-20 05:18	74.30	OK
14085	2026-09-20 05:19	73.28	OK	14086	2026-09-20 05:20	73.64	OK
14087	2026-09-20 05:21	73.00	OK	14088	2026-09-20 05:22	74.20	OK
14089	2026-09-20 05:23	75.58	OK	14090	2026-09-20 05:24	72.39	OK
14091	2026-09-20 05:25	76.82	OK	14092	2026-09-20 05:26	73.74	OK
14093	2026-09-20 05:27	73.83	OK	14094	2026-09-20 05:28	74.11	OK
14095	2026-09-20 05:29	71.66	OK	14096	2026-09-20 05:30	74.55	OK
14097	2026-09-20 05:31	76.47	OK	14098	2026-09-20 05:32	76.36	OK
14099	2026-09-20 05:33	72.86	OK	14100	2026-09-20 05:34	73.93	OK
14101	2026-09-20 05:35	73.12	OK	14102	2026-09-20 05:36	76.39	OK
14103	2026-09-20 05:37	74.14	OK	14104	2026-09-20 05:38	71.53	OK
14105	2026-09-20 05:39	72.68	OK	14106	2026-09-20 05:40	71.82	OK
14107	2026-09-20 05:41	70.91	OK	14108	2026-09-20 05:42	74.49	OK
14109	2026-09-20 05:43	74.46	OK	14110	2026-09-20 05:44	71.84	OK
14111	2026-09-20 05:45	72.76	OK	14112	2026-09-20 05:46	73.42	OK
14113	2026-09-20 05:47	74.26	OK	14114	2026-09-20 05:48	72.85	OK
14115	2026-09-20 05:49	72.53	OK	14116	2026-09-20 05:50	75.22	OK
14117	2026-09-20 05:51	74.90	OK	14118	2026-09-20 05:52	72.85	OK
14119	2026-09-20 05:53	71.84	OK	14120	2026-09-20 05:54	74.36	OK
14121	2026-09-20 05:55	72.25	OK	14122	2026-09-20 05:56	73.93	OK
14123	2026-09-20 05:57	72.92	OK	14124	2026-09-20 05:58	75.70	OK
14125	2026-09-20 05:59	71.36	OK	14126	2026-09-20 06:00	72.43	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14127	2026-09-20 06:01	74.99	OK	14128	2026-09-20 06:02	71.19	OK
14129	2026-09-20 06:03	76.63	OK	14130	2026-09-20 06:04	77.30	OK
14131	2026-09-20 06:05	72.53	OK	14132	2026-09-20 06:06	74.79	OK
14133	2026-09-20 06:07	72.63	OK	14134	2026-09-20 06:08	74.86	OK
14135	2026-09-20 06:09	72.51	OK	14136	2026-09-20 06:10	72.65	OK
14137	2026-09-20 06:11	73.33	OK	14138	2026-09-20 06:12	75.05	OK
14139	2026-09-20 06:13	72.36	OK	14140	2026-09-20 06:14	74.44	OK
14141	2026-09-20 06:15	74.97	OK	14142	2026-09-20 06:16	74.39	OK
14143	2026-09-20 06:17	73.11	OK	14144	2026-09-20 06:18	75.11	OK
14145	2026-09-20 06:19	75.43	OK	14146	2026-09-20 06:20	72.32	OK
14147	2026-09-20 06:21	72.42	OK	14148	2026-09-20 06:22	71.53	OK
14149	2026-09-20 06:23	76.02	OK	14150	2026-09-20 06:24	73.28	OK
14151	2026-09-20 06:25	76.23	OK	14152	2026-09-20 06:26	75.13	OK
14153	2026-09-20 06:27	72.72	OK	14154	2026-09-20 06:28	75.48	OK
14155	2026-09-20 06:29	75.12	OK	14156	2026-09-20 06:30	72.96	OK
14157	2026-09-20 06:31	75.90	OK	14158	2026-09-20 06:32	72.93	OK
14159	2026-09-20 06:33	75.90	OK	14160	2026-09-20 06:34	71.98	OK
14161	2026-09-20 06:35	77.19	OK	14162	2026-09-20 06:36	76.21	OK
14163	2026-09-20 06:37	74.16	OK	14164	2026-09-20 06:38	75.65	OK
14165	2026-09-20 06:39	74.81	OK	14166	2026-09-20 06:40	74.57	OK
14167	2026-09-20 06:41	75.48	OK	14168	2026-09-20 06:42	76.14	OK
14169	2026-09-20 06:43	76.72	OK	14170	2026-09-20 06:44	75.74	OK
14171	2026-09-20 06:45	75.23	OK	14172	2026-09-20 06:46	77.07	OK
14173	2026-09-20 06:47	72.30	OK	14174	2026-09-20 06:48	75.22	OK
14175	2026-09-20 06:49	73.38	OK	14176	2026-09-20 06:50	74.15	OK
14177	2026-09-20 06:51	74.72	OK	14178	2026-09-20 06:52	72.08	OK
14179	2026-09-20 06:53	75.22	OK	14180	2026-09-20 06:54	76.67	OK
14181	2026-09-20 06:55	77.56	OK	14182	2026-09-20 06:56	73.25	OK
14183	2026-09-20 06:57	78.56	OK	14184	2026-09-20 06:58	75.95	OK
14185	2026-09-20 06:59	72.89	OK	14186	2026-09-20 07:00	72.49	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14187	2026-09-20 07:01	76.57	OK	14188	2026-09-20 07:02	76.75	OK
14189	2026-09-20 07:03	75.41	OK	14190	2026-09-20 07:04	76.42	OK
14191	2026-09-20 07:05	78.09	OK	14192	2026-09-20 07:06	77.52	OK
14193	2026-09-20 07:07	73.31	OK	14194	2026-09-20 07:08	75.37	OK
14195	2026-09-20 07:09	74.69	OK	14196	2026-09-20 07:10	75.19	OK
14197	2026-09-20 07:11	78.97	OK	14198	2026-09-20 07:12	73.35	OK
14199	2026-09-20 07:13	77.67	OK	14200	2026-09-20 07:14	77.60	OK
14201	2026-09-20 07:15	74.62	OK	14202	2026-09-20 07:16	72.74	OK
14203	2026-09-20 07:17	74.03	OK	14204	2026-09-20 07:18	78.41	OK
14205	2026-09-20 07:19	78.74	OK	14206	2026-09-20 07:20	77.04	OK
14207	2026-09-20 07:21	76.62	OK	14208	2026-09-20 07:22	77.75	OK
14209	2026-09-20 07:23	76.31	OK	14210	2026-09-20 07:24	75.20	OK
14211	2026-09-20 07:25	76.58	OK	14212	2026-09-20 07:26	77.43	OK
14213	2026-09-20 07:27	77.50	OK	14214	2026-09-20 07:28	75.67	OK
14215	2026-09-20 07:29	78.69	OK	14216	2026-09-20 07:30	76.68	OK
14217	2026-09-20 07:31	74.80	OK	14218	2026-09-20 07:32	76.71	OK
14219	2026-09-20 07:33	78.58	OK	14220	2026-09-20 07:34	75.94	OK
14221	2026-09-20 07:35	73.89	OK	14222	2026-09-20 07:36	78.05	OK
14223	2026-09-20 07:37	77.02	OK	14224	2026-09-20 07:38	78.08	OK
14225	2026-09-20 07:39	76.29	OK	14226	2026-09-20 07:40	77.80	OK
14227	2026-09-20 07:41	79.13	OK	14228	2026-09-20 07:42	76.49	OK
14229	2026-09-20 07:43	77.79	OK	14230	2026-09-20 07:44	76.76	OK
14231	2026-09-20 07:45	75.43	OK	14232	2026-09-20 07:46	77.40	OK
14233	2026-09-20 07:47	75.26	OK	14234	2026-09-20 07:48	78.73	OK
14235	2026-09-20 07:49	74.85	OK	14236	2026-09-20 07:50	75.98	OK
14237	2026-09-20 07:51	76.38	OK	14238	2026-09-20 07:52	74.28	OK
14239	2026-09-20 07:53	78.75	OK	14240	2026-09-20 07:54	73.41	OK
14241	2026-09-20 07:55	77.28	OK	14242	2026-09-20 07:56	79.98	OK
14243	2026-09-20 07:57	77.00	OK	14244	2026-09-20 07:58	74.00	OK
14245	2026-09-20 07:59	76.00	OK	14246	2026-09-20 08:00	79.89	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14247	2026-09-20 08:01	77.68	OK	14248	2026-09-20 08:02	77.10	OK
14249	2026-09-20 08:03	78.46	OK	14250	2026-09-20 08:04	76.92	OK
14251	2026-09-20 08:05	76.21	OK	14252	2026-09-20 08:06	78.30	OK
14253	2026-09-20 08:07	79.44	OK	14254	2026-09-20 08:08	77.16	OK
14255	2026-09-20 08:09	75.32	OK	14256	2026-09-20 08:10	76.45	OK
14257	2026-09-20 08:11	76.46	OK	14258	2026-09-20 08:12	79.77	OK
14259	2026-09-20 08:13	78.07	OK	14260	2026-09-20 08:14	76.05	OK
14261	2026-09-20 08:15	76.08	OK	14262	2026-09-20 08:16	74.96	OK
14263	2026-09-20 08:17	77.91	OK	14264	2026-09-20 08:18	79.58	OK
14265	2026-09-20 08:19	77.47	OK	14266	2026-09-20 08:20	77.81	OK
14267	2026-09-20 08:21	77.22	OK	14268	2026-09-20 08:22	78.01	OK
14269	2026-09-20 08:23	77.41	OK	14270	2026-09-20 08:24	77.64	OK
14271	2026-09-20 08:25	76.77	OK	14272	2026-09-20 08:26	76.27	OK
14273	2026-09-20 08:27	75.49	OK	14274	2026-09-20 08:28	78.05	OK
14275	2026-09-20 08:29	81.44	OK	14276	2026-09-20 08:30	76.33	OK
14277	2026-09-20 08:31	77.16	OK	14278	2026-09-20 08:32	78.54	OK
14279	2026-09-20 08:33	80.27	OK	14280	2026-09-20 08:34	77.72	OK
14281	2026-09-20 08:35	78.44	OK	14282	2026-09-20 08:36	78.51	OK
14283	2026-09-20 08:37	77.28	OK	14284	2026-09-20 08:38	76.01	OK
14285	2026-09-20 08:39	78.67	OK	14286	2026-09-20 08:40	77.71	OK
14287	2026-09-20 08:41	76.15	OK	14288	2026-09-20 08:42	80.43	OK
14289	2026-09-20 08:43	80.00	OK	14290	2026-09-20 08:44	77.65	OK
14291	2026-09-20 08:45	78.88	OK	14292	2026-09-20 08:46	78.40	OK
14293	2026-09-20 08:47	75.88	OK	14294	2026-09-20 08:48	79.27	OK
14295	2026-09-20 08:49	77.64	OK	14296	2026-09-20 08:50	77.52	OK
14297	2026-09-20 08:51	76.84	OK	14298	2026-09-20 08:52	77.60	OK
14299	2026-09-20 08:53	77.35	OK	14300	2026-09-20 08:54	80.88	OK
14301	2026-09-20 08:55	78.24	OK	14302	2026-09-20 08:56	78.62	OK
14303	2026-09-20 08:57	77.90	OK	14304	2026-09-20 08:58	77.72	OK
14305	2026-09-20 08:59	79.58	OK	14306	2026-09-20 09:00	78.38	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14307	2026-09-20 09:01	75.62	OK	14308	2026-09-20 09:02	76.84	OK
14309	2026-09-20 09:03	75.62	OK	14310	2026-09-20 09:04	77.60	OK
14311	2026-09-20 09:05	78.35	OK	14312	2026-09-20 09:06	78.17	OK
14313	2026-09-20 09:07	80.12	OK	14314	2026-09-20 09:08	78.42	OK
14315	2026-09-20 09:09	78.41	OK	14316	2026-09-20 09:10	80.38	OK
14317	2026-09-20 09:11	79.29	OK	14318	2026-09-20 09:12	77.14	OK
14319	2026-09-20 09:13	78.12	OK	14320	2026-09-20 09:14	80.63	OK
14321	2026-09-20 09:15	80.50	OK	14322	2026-09-20 09:16	78.29	OK
14323	2026-09-20 09:17	77.63	OK	14324	2026-09-20 09:18	78.54	OK
14325	2026-09-20 09:19	75.94	OK	14326	2026-09-20 09:20	79.24	OK
14327	2026-09-20 09:21	78.45	OK	14328	2026-09-20 09:22	79.10	OK
14329	2026-09-20 09:23	77.95	OK	14330	2026-09-20 09:24	78.21	OK
14331	2026-09-20 09:25	76.50	OK	14332	2026-09-20 09:26	76.87	OK
14333	2026-09-20 09:27	77.63	OK	14334	2026-09-20 09:28	78.36	OK
14335	2026-09-20 09:29	80.79	OK	14336	2026-09-20 09:30	76.75	OK
14337	2026-09-20 09:31	82.86	OK	14338	2026-09-20 09:32	79.37	OK
14339	2026-09-20 09:33	81.00	OK	14340	2026-09-20 09:34	78.13	OK
14341	2026-09-20 09:35	79.85	OK	14342	2026-09-20 09:36	80.47	OK
14343	2026-09-20 09:37	77.22	OK	14344	2026-09-20 09:38	79.00	OK
14345	2026-09-20 09:39	77.61	OK	14346	2026-09-20 09:40	79.27	OK
14347	2026-09-20 09:41	79.52	OK	14348	2026-09-20 09:42	79.71	OK
14349	2026-09-20 09:43	76.90	OK	14350	2026-09-20 09:44	80.27	OK
14351	2026-09-20 09:45	76.46	OK	14352	2026-09-20 09:46	79.09	OK
14353	2026-09-20 09:47	77.86	OK	14354	2026-09-20 09:48	79.89	OK
14355	2026-09-20 09:49	78.79	OK	14356	2026-09-20 09:50	80.56	OK
14357	2026-09-20 09:51	81.46	OK	14358	2026-09-20 09:52	80.29	OK
14359	2026-09-20 09:53	78.77	OK	14360	2026-09-20 09:54	80.00	OK
14361	2026-09-20 09:55	79.14	OK	14362	2026-09-20 09:56	80.79	OK
14363	2026-09-20 09:57	79.03	OK	14364	2026-09-20 09:58	76.78	OK
14365	2026-09-20 09:59	75.71	OK	14366	2026-09-20 10:00	75.55	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14367	2026-09-20 10:01	79.22	OK	14368	2026-09-20 10:02	79.56	OK
14369	2026-09-20 10:03	80.49	OK	14370	2026-09-20 10:04	81.67	OK
14371	2026-09-20 10:05	77.60	OK	14372	2026-09-20 10:06	79.81	OK
14373	2026-09-20 10:07	80.12	OK	14374	2026-09-20 10:08	80.15	OK
14375	2026-09-20 10:09	77.40	OK	14376	2026-09-20 10:10	78.56	OK
14377	2026-09-20 10:11	81.20	OK	14378	2026-09-20 10:12	79.97	OK
14379	2026-09-20 10:13	77.67	OK	14380	2026-09-20 10:14	77.19	OK
14381	2026-09-20 10:15	80.19	OK	14382	2026-09-20 10:16	80.16	OK
14383	2026-09-20 10:17	79.24	OK	14384	2026-09-20 10:18	80.20	OK
14385	2026-09-20 10:19	79.05	OK	14386	2026-09-20 10:20	79.74	OK
14387	2026-09-20 10:21	78.53	OK	14388	2026-09-20 10:22	78.99	OK
14389	2026-09-20 10:23	80.17	OK	14390	2026-09-20 10:24	80.96	OK
14391	2026-09-20 10:25	79.10	OK	14392	2026-09-20 10:26	79.71	OK
14393	2026-09-20 10:27	83.12	OK	14394	2026-09-20 10:28	79.99	OK
14395	2026-09-20 10:29	78.15	OK	14396	2026-09-20 10:30	82.84	OK
14397	2026-09-20 10:31	77.67	OK	14398	2026-09-20 10:32	79.81	OK
14399	2026-09-20 10:33	80.74	OK	14400	2026-09-20 10:34	80.90	OK
14401	2026-09-20 10:35	82.72	OK	14402	2026-09-20 10:36	83.17	OK
14403	2026-09-20 10:37	79.73	OK	14404	2026-09-20 10:38	78.57	OK
14405	2026-09-20 10:39	80.95	OK	14406	2026-09-20 10:40	76.78	OK
14407	2026-09-20 10:41	81.08	OK	14408	2026-09-20 10:42	81.00	OK
14409	2026-09-20 10:43	81.72	OK	14410	2026-09-20 10:44	78.65	OK
14411	2026-09-20 10:45	77.72	OK	14412	2026-09-20 10:46	81.39	OK
14413	2026-09-20 10:47	80.19	OK	14414	2026-09-20 10:48	81.45	OK
14415	2026-09-20 10:49	80.95	OK	14416	2026-09-20 10:50	80.29	OK
14417	2026-09-20 10:51	80.15	OK	14418	2026-09-20 10:52	78.61	OK
14419	2026-09-20 10:53	79.73	OK	14420	2026-09-20 10:54	79.15	OK
14421	2026-09-20 10:55	82.65	OK	14422	2026-09-20 10:56	79.02	OK
14423	2026-09-20 10:57	78.57	OK	14424	2026-09-20 10:58	78.06	OK
14425	2026-09-20 10:59	80.91	OK	14426	2026-09-20 11:00	83.20	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14427	2026-09-20 11:01	76.42	OK	14428	2026-09-20 11:02	80.32	OK
14429	2026-09-20 11:03	81.74	OK	14430	2026-09-20 11:04	79.97	OK
14431	2026-09-20 11:05	83.86	OK	14432	2026-09-20 11:06	78.02	OK
14433	2026-09-20 11:07	77.44	OK	14434	2026-09-20 11:08	78.31	OK
14435	2026-09-20 11:09	80.44	OK	14436	2026-09-20 11:10	78.80	OK
14437	2026-09-20 11:11	81.68	OK	14438	2026-09-20 11:12	81.24	OK
14439	2026-09-20 11:13	78.92	OK	14440	2026-09-20 11:14	77.55	OK
14441	2026-09-20 11:15	81.74	OK	14442	2026-09-20 11:16	79.11	OK
14443	2026-09-20 11:17	80.54	OK	14444	2026-09-20 11:18	81.12	OK
14445	2026-09-20 11:19	81.00	OK	14446	2026-09-20 11:20	80.70	OK
14447	2026-09-20 11:21	80.83	OK	14448	2026-09-20 11:22	83.36	OK
14449	2026-09-20 11:23	80.23	OK	14450	2026-09-20 11:24	83.31	OK
14451	2026-09-20 11:25	83.09	OK	14452	2026-09-20 11:26	78.93	OK
14453	2026-09-20 11:27	80.72	OK	14454	2026-09-20 11:28	81.06	OK
14455	2026-09-20 11:29	81.79	OK	14456	2026-09-20 11:30	82.96	OK
14457	2026-09-20 11:31	80.91	OK	14458	2026-09-20 11:32	81.83	OK
14459	2026-09-20 11:33	78.35	OK	14460	2026-09-20 11:34	81.93	OK
14461	2026-09-20 11:35	81.03	OK	14462	2026-09-20 11:36	81.25	OK
14463	2026-09-20 11:37	81.70	OK	14464	2026-09-20 11:38	77.01	OK
14465	2026-09-20 11:39	79.62	OK	14466	2026-09-20 11:40	78.48	OK
14467	2026-09-20 11:41	83.92	OK	14468	2026-09-20 11:42	78.74	OK
14469	2026-09-20 11:43	82.39	OK	14470	2026-09-20 11:44	82.10	OK
14471	2026-09-20 11:45	81.65	OK	14472	2026-09-20 11:46	82.23	OK
14473	2026-09-20 11:47	81.22	OK	14474	2026-09-20 11:48	79.77	OK
14475	2026-09-20 11:49	80.18	OK	14476	2026-09-20 11:50	80.72	OK
14477	2026-09-20 11:51	81.75	OK	14478	2026-09-20 11:52	81.79	OK
14479	2026-09-20 11:53	77.81	OK	14480	2026-09-20 11:54	82.91	OK
14481	2026-09-20 11:55	81.69	OK	14482	2026-09-20 11:56	80.01	OK
14483	2026-09-20 11:57	79.14	OK	14484	2026-09-20 11:58	80.48	OK
14485	2026-09-20 11:59	80.16	OK	14486	2026-09-20 12:00	80.64	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14487	2026-09-20 12:01	78.74	OK	14488	2026-09-20 12:02	81.52	OK
14489	2026-09-20 12:03	79.40	OK	14490	2026-09-20 12:04	81.08	OK
14491	2026-09-20 12:05	82.15	OK	14492	2026-09-20 12:06	82.00	OK
14493	2026-09-20 12:07	80.62	OK	14494	2026-09-20 12:08	76.94	OK
14495	2026-09-20 12:09	83.27	OK	14496	2026-09-20 12:10	80.99	OK
14497	2026-09-20 12:11	82.05	OK	14498	2026-09-20 12:12	82.54	OK
14499	2026-09-20 12:13	83.16	OK	14500	2026-09-20 12:14	84.07	OK
14501	2026-09-20 12:15	82.77	OK	14502	2026-09-20 12:16	80.02	OK
14503	2026-09-20 12:17	81.46	OK	14504	2026-09-20 12:18	83.19	OK
14505	2026-09-20 12:19	82.60	OK	14506	2026-09-20 12:20	79.58	OK
14507	2026-09-20 12:21	81.81	OK	14508	2026-09-20 12:22	81.81	OK
14509	2026-09-20 12:23	81.31	OK	14510	2026-09-20 12:24	82.53	OK
14511	2026-09-20 12:25	80.23	OK	14512	2026-09-20 12:26	79.40	OK
14513	2026-09-20 12:27	80.96	OK	14514	2026-09-20 12:28	80.25	OK
14515	2026-09-20 12:29	81.74	OK	14516	2026-09-20 12:30	81.80	OK
14517	2026-09-20 12:31	83.62	OK	14518	2026-09-20 12:32	82.43	OK
14519	2026-09-20 12:33	81.94	OK	14520	2026-09-20 12:34	83.97	OK
14521	2026-09-20 12:35	80.84	OK	14522	2026-09-20 12:36	80.83	OK
14523	2026-09-20 12:37	80.13	OK	14524	2026-09-20 12:38	83.40	OK
14525	2026-09-20 12:39	80.28	OK	14526	2026-09-20 12:40	80.88	OK
14527	2026-09-20 12:41	81.78	OK	14528	2026-09-20 12:42	83.95	OK
14529	2026-09-20 12:43	81.66	OK	14530	2026-09-20 12:44	82.48	OK
14531	2026-09-20 12:45	80.35	OK	14532	2026-09-20 12:46	79.96	OK
14533	2026-09-20 12:47	80.88	OK	14534	2026-09-20 12:48	81.77	OK
14535	2026-09-20 12:49	78.68	OK	14536	2026-09-20 12:50	81.53	OK
14537	2026-09-20 12:51	81.87	OK	14538	2026-09-20 12:52	81.24	OK
14539	2026-09-20 12:53	80.60	OK	14540	2026-09-20 12:54	82.19	OK
14541	2026-09-20 12:55	83.42	OK	14542	2026-09-20 12:56	78.19	OK
14543	2026-09-20 12:57	78.87	OK	14544	2026-09-20 12:58	81.44	OK
14545	2026-09-20 12:59	76.77	OK	14546	2026-09-20 13:00	78.28	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14547	2026-09-20 13:01	82.50	OK	14548	2026-09-20 13:02	84.85	OK
14549	2026-09-20 13:03	82.98	OK	14550	2026-09-20 13:04	78.41	OK
14551	2026-09-20 13:05	78.42	OK	14552	2026-09-20 13:06	81.27	OK
14553	2026-09-20 13:07	80.25	OK	14554	2026-09-20 13:08	80.65	OK
14555	2026-09-20 13:09	80.95	OK	14556	2026-09-20 13:10	82.14	OK
14557	2026-09-20 13:11	81.64	OK	14558	2026-09-20 13:12	80.87	OK
14559	2026-09-20 13:13	81.72	OK	14560	2026-09-20 13:14	80.54	OK
14561	2026-09-20 13:15	83.33	OK	14562	2026-09-20 13:16	82.37	OK
14563	2026-09-20 13:17	80.54	OK	14564	2026-09-20 13:18	81.57	OK
14565	2026-09-20 13:19	83.47	OK	14566	2026-09-20 13:20	79.87	OK
14567	2026-09-20 13:21	82.08	OK	14568	2026-09-20 13:22	79.65	OK
14569	2026-09-20 13:23	80.95	OK	14570	2026-09-20 13:24	80.66	OK
14571	2026-09-20 13:25	78.98	OK	14572	2026-09-20 13:26	80.80	OK
14573	2026-09-20 13:27	81.05	OK	14574	2026-09-20 13:28	81.46	OK
14575	2026-09-20 13:29	81.60	OK	14576	2026-09-20 13:30	78.46	OK
14577	2026-09-20 13:31	81.83	OK	14578	2026-09-20 13:32	81.44	OK
14579	2026-09-20 13:33	78.40	OK	14580	2026-09-20 13:34	79.41	OK
14581	2026-09-20 13:35	84.40	OK	14582	2026-09-20 13:36	83.11	OK
14583	2026-09-20 13:37	83.00	OK	14584	2026-09-20 13:38	79.90	OK
14585	2026-09-20 13:39	82.71	OK	14586	2026-09-20 13:40	79.43	OK
14587	2026-09-20 13:41	77.92	OK	14588	2026-09-20 13:42	81.51	OK
14589	2026-09-20 13:43	81.12	OK	14590	2026-09-20 13:44	81.96	OK
14591	2026-09-20 13:45	80.63	OK	14592	2026-09-20 13:46	81.08	OK
14593	2026-09-20 13:47	80.27	OK	14594	2026-09-20 13:48	78.91	OK
14595	2026-09-20 13:49	84.65	OK	14596	2026-09-20 13:50	79.36	OK
14597	2026-09-20 13:51	80.99	OK	14598	2026-09-20 13:52	84.06	OK
14599	2026-09-20 13:53	82.47	OK	14600	2026-09-20 13:54	80.73	OK
14601	2026-09-20 13:55	83.92	OK	14602	2026-09-20 13:56	80.41	OK
14603	2026-09-20 13:57	82.28	OK	14604	2026-09-20 13:58	81.88	OK
14605	2026-09-20 13:59	84.33	OK	14606	2026-09-20 14:00	80.77	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14607	2026-09-20 14:01	82.29	OK	14608	2026-09-20 14:02	79.49	OK
14609	2026-09-20 14:03	81.07	OK	14610	2026-09-20 14:04	79.82	OK
14611	2026-09-20 14:05	81.54	OK	14612	2026-09-20 14:06	77.64	OK
14613	2026-09-20 14:07	78.40	OK	14614	2026-09-20 14:08	78.97	OK
14615	2026-09-20 14:09	78.35	OK	14616	2026-09-20 14:10	80.33	OK
14617	2026-09-20 14:11	81.01	OK	14618	2026-09-20 14:12	79.06	OK
14619	2026-09-20 14:13	79.32	OK	14620	2026-09-20 14:14	81.41	OK
14621	2026-09-20 14:15	80.71	OK	14622	2026-09-20 14:16	81.66	OK
14623	2026-09-20 14:17	77.81	OK	14624	2026-09-20 14:18	83.01	OK
14625	2026-09-20 14:19	80.08	OK	14626	2026-09-20 14:20	78.51	OK
14627	2026-09-20 14:21	78.89	OK	14628	2026-09-20 14:22	81.69	OK
14629	2026-09-20 14:23	78.18	OK	14630	2026-09-20 14:24	79.60	OK
14631	2026-09-20 14:25	80.27	OK	14632	2026-09-20 14:26	81.05	OK
14633	2026-09-20 14:27	82.89	OK	14634	2026-09-20 14:28	80.15	OK
14635	2026-09-20 14:29	80.75	OK	14636	2026-09-20 14:30	82.59	OK
14637	2026-09-20 14:31	78.55	OK	14638	2026-09-20 14:32	82.14	OK
14639	2026-09-20 14:33	81.11	OK	14640	2026-09-20 14:34	80.91	OK
14641	2026-09-20 14:35	78.54	OK	14642	2026-09-20 14:36	80.27	OK
14643	2026-09-20 14:37	81.15	OK	14644	2026-09-20 14:38	80.41	OK
14645	2026-09-20 14:39	82.01	OK	14646	2026-09-20 14:40	80.65	OK
14647	2026-09-20 14:41	79.02	OK	14648	2026-09-20 14:42	81.93	OK
14649	2026-09-20 14:43	79.53	OK	14650	2026-09-20 14:44	82.93	OK
14651	2026-09-20 14:45	79.43	OK	14652	2026-09-20 14:46	78.74	OK
14653	2026-09-20 14:47	77.45	OK	14654	2026-09-20 14:48	77.35	OK
14655	2026-09-20 14:49	81.37	OK	14656	2026-09-20 14:50	81.14	OK
14657	2026-09-20 14:51	82.07	OK	14658	2026-09-20 14:52	79.58	OK
14659	2026-09-20 14:53	80.84	OK	14660	2026-09-20 14:54	79.21	OK
14661	2026-09-20 14:55	77.90	OK	14662	2026-09-20 14:56	80.20	OK
14663	2026-09-20 14:57	78.65	OK	14664	2026-09-20 14:58	78.69	OK
14665	2026-09-20 14:59	80.63	OK	14666	2026-09-20 15:00	77.25	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14667	2026-09-20 15:01	81.44	OK	14668	2026-09-20 15:02	80.92	OK
14669	2026-09-20 15:03	80.39	OK	14670	2026-09-20 15:04	83.72	OK
14671	2026-09-20 15:05	79.40	OK	14672	2026-09-20 15:06	77.23	OK
14673	2026-09-20 15:07	82.34	OK	14674	2026-09-20 15:08	81.15	OK
14675	2026-09-20 15:09	79.04	OK	14676	2026-09-20 15:10	81.33	OK
14677	2026-09-20 15:11	82.13	OK	14678	2026-09-20 15:12	78.33	OK
14679	2026-09-20 15:13	80.56	OK	14680	2026-09-20 15:14	77.19	OK
14681	2026-09-20 15:15	78.89	OK	14682	2026-09-20 15:16	78.28	OK
14683	2026-09-20 15:17	77.05	OK	14684	2026-09-20 15:18	80.99	OK
14685	2026-09-20 15:19	79.76	OK	14686	2026-09-20 15:20	80.93	OK
14687	2026-09-20 15:21	80.49	OK	14688	2026-09-20 15:22	78.15	OK
14689	2026-09-20 15:23	79.79	OK	14690	2026-09-20 15:24	79.96	OK
14691	2026-09-20 15:25	81.96	OK	14692	2026-09-20 15:26	79.35	OK
14693	2026-09-20 15:27	82.70	OK	14694	2026-09-20 15:28	78.89	OK
14695	2026-09-20 15:29	81.30	OK	14696	2026-09-20 15:30	80.94	OK
14697	2026-09-20 15:31	80.80	OK	14698	2026-09-20 15:32	78.79	OK
14699	2026-09-20 15:33	78.66	OK	14700	2026-09-20 15:34	78.54	OK
14701	2026-09-20 15:35	79.87	OK	14702	2026-09-20 15:36	76.13	OK
14703	2026-09-20 15:37	78.75	OK	14704	2026-09-20 15:38	79.39	OK
14705	2026-09-20 15:39	82.45	OK	14706	2026-09-20 15:40	80.26	OK
14707	2026-09-20 15:41	80.95	OK	14708	2026-09-20 15:42	79.28	OK
14709	2026-09-20 15:43	78.92	OK	14710	2026-09-20 15:44	80.95	OK
14711	2026-09-20 15:45	79.64	OK	14712	2026-09-20 15:46	82.12	OK
14713	2026-09-20 15:47	78.62	OK	14714	2026-09-20 15:48	77.08	OK
14715	2026-09-20 15:49	80.25	OK	14716	2026-09-20 15:50	81.21	OK
14717	2026-09-20 15:51	78.08	OK	14718	2026-09-20 15:52	82.15	OK
14719	2026-09-20 15:53	77.01	OK	14720	2026-09-20 15:54	79.54	OK
14721	2026-09-20 15:55	81.04	OK	14722	2026-09-20 15:56	78.49	OK
14723	2026-09-20 15:57	80.41	OK	14724	2026-09-20 15:58	81.18	OK
14725	2026-09-20 15:59	76.45	OK	14726	2026-09-20 16:00	78.64	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14727	2026-09-20 16:01	77.29	OK	14728	2026-09-20 16:02	79.74	OK
14729	2026-09-20 16:03	78.19	OK	14730	2026-09-20 16:04	82.25	OK
14731	2026-09-20 16:05	77.31	OK	14732	2026-09-20 16:06	80.09	OK
14733	2026-09-20 16:07	78.72	OK	14734	2026-09-20 16:08	75.53	OK
14735	2026-09-20 16:09	82.15	OK	14736	2026-09-20 16:10	81.03	OK
14737	2026-09-20 16:11	79.01	OK	14738	2026-09-20 16:12	76.86	OK
14739	2026-09-20 16:13	80.27	OK	14740	2026-09-20 16:14	81.63	OK
14741	2026-09-20 16:15	75.68	OK	14742	2026-09-20 16:16	77.50	OK
14743	2026-09-20 16:17	78.73	OK	14744	2026-09-20 16:18	77.14	OK
14745	2026-09-20 16:19	78.47	OK	14746	2026-09-20 16:20	77.44	OK
14747	2026-09-20 16:21	77.65	OK	14748	2026-09-20 16:22	80.06	OK
14749	2026-09-20 16:23	80.44	OK	14750	2026-09-20 16:24	79.92	OK
14751	2026-09-20 16:25	78.82	OK	14752	2026-09-20 16:26	77.17	OK
14753	2026-09-20 16:27	81.04	OK	14754	2026-09-20 16:28	75.87	OK
14755	2026-09-20 16:29	76.04	OK	14756	2026-09-20 16:30	79.16	OK
14757	2026-09-20 16:31	78.17	OK	14758	2026-09-20 16:32	79.60	OK
14759	2026-09-20 16:33	78.05	OK	14760	2026-09-20 16:34	76.00	OK
14761	2026-09-20 16:35	79.27	OK	14762	2026-09-20 16:36	79.49	OK
14763	2026-09-20 16:37	81.55	OK	14764	2026-09-20 16:38	76.41	OK
14765	2026-09-20 16:39	79.05	OK	14766	2026-09-20 16:40	81.61	OK
14767	2026-09-20 16:41	79.08	OK	14768	2026-09-20 16:42	77.09	OK
14769	2026-09-20 16:43	76.81	OK	14770	2026-09-20 16:44	78.62	OK
14771	2026-09-20 16:45	80.78	OK	14772	2026-09-20 16:46	79.42	OK
14773	2026-09-20 16:47	77.64	OK	14774	2026-09-20 16:48	75.26	OK
14775	2026-09-20 16:49	77.95	OK	14776	2026-09-20 16:50	79.54	OK
14777	2026-09-20 16:51	76.45	OK	14778	2026-09-20 16:52	75.50	OK
14779	2026-09-20 16:53	79.10	OK	14780	2026-09-20 16:54	77.42	OK
14781	2026-09-20 16:55	78.38	OK	14782	2026-09-20 16:56	81.03	OK
14783	2026-09-20 16:57	76.21	OK	14784	2026-09-20 16:58	77.03	OK
14785	2026-09-20 16:59	79.18	OK	14786	2026-09-20 17:00	78.21	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14787	2026-09-20 17:01	76.86	OK	14788	2026-09-20 17:02	80.59	OK
14789	2026-09-20 17:03	79.70	OK	14790	2026-09-20 17:04	77.05	OK
14791	2026-09-20 17:05	75.88	OK	14792	2026-09-20 17:06	80.04	OK
14793	2026-09-20 17:07	79.03	OK	14794	2026-09-20 17:08	77.46	OK
14795	2026-09-20 17:09	78.53	OK	14796	2026-09-20 17:10	77.76	OK
14797	2026-09-20 17:11	79.37	OK	14798	2026-09-20 17:12	77.16	OK
14799	2026-09-20 17:13	76.37	OK	14800	2026-09-20 17:14	76.69	OK
14801	2026-09-20 17:15	76.95	OK	14802	2026-09-20 17:16	79.45	OK
14803	2026-09-20 17:17	77.16	OK	14804	2026-09-20 17:18	75.96	OK
14805	2026-09-20 17:19	78.54	OK	14806	2026-09-20 17:20	76.79	OK
14807	2026-09-20 17:21	76.18	OK	14808	2026-09-20 17:22	77.54	OK
14809	2026-09-20 17:23	77.68	OK	14810	2026-09-20 17:24	77.94	OK
14811	2026-09-20 17:25	76.64	OK	14812	2026-09-20 17:26	79.08	OK
14813	2026-09-20 17:27	78.63	OK	14814	2026-09-20 17:28	78.80	OK
14815	2026-09-20 17:29	79.84	OK	14816	2026-09-20 17:30	74.55	OK
14817	2026-09-20 17:31	79.37	OK	14818	2026-09-20 17:32	79.47	OK
14819	2026-09-20 17:33	76.47	OK	14820	2026-09-20 17:34	79.49	OK
14821	2026-09-20 17:35	76.27	OK	14822	2026-09-20 17:36	78.49	OK
14823	2026-09-20 17:37	74.34	OK	14824	2026-09-20 17:38	77.97	OK
14825	2026-09-20 17:39	77.33	OK	14826	2026-09-20 17:40	78.94	OK
14827	2026-09-20 17:41	74.73	OK	14828	2026-09-20 17:42	76.99	OK
14829	2026-09-20 17:43	74.51	OK	14830	2026-09-20 17:44	77.49	OK
14831	2026-09-20 17:45	78.96	OK	14832	2026-09-20 17:46	77.28	OK
14833	2026-09-20 17:47	76.92	OK	14834	2026-09-20 17:48	76.88	OK
14835	2026-09-20 17:49	79.49	OK	14836	2026-09-20 17:50	76.44	OK
14837	2026-09-20 17:51	77.64	OK	14838	2026-09-20 17:52	76.79	OK
14839	2026-09-20 17:53	78.14	OK	14840	2026-09-20 17:54	74.17	OK
14841	2026-09-20 17:55	76.71	OK	14842	2026-09-20 17:56	76.02	OK
14843	2026-09-20 17:57	79.33	OK	14844	2026-09-20 17:58	77.09	OK
14845	2026-09-20 17:59	76.73	OK	14846	2026-09-20 18:00	75.14	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14847	2026-09-20 18:01	74.66	OK	14848	2026-09-20 18:02	76.03	OK
14849	2026-09-20 18:03	77.78	OK	14850	2026-09-20 18:04	78.86	OK
14851	2026-09-20 18:05	74.89	OK	14852	2026-09-20 18:06	78.84	OK
14853	2026-09-20 18:07	77.04	OK	14854	2026-09-20 18:08	75.70	OK
14855	2026-09-20 18:09	72.21	OK	14856	2026-09-20 18:10	75.45	OK
14857	2026-09-20 18:11	75.82	OK	14858	2026-09-20 18:12	77.35	OK
14859	2026-09-20 18:13	76.23	OK	14860	2026-09-20 18:14	75.96	OK
14861	2026-09-20 18:15	73.62	OK	14862	2026-09-20 18:16	75.51	OK
14863	2026-09-20 18:17	76.62	OK	14864	2026-09-20 18:18	76.20	OK
14865	2026-09-20 18:19	74.14	OK	14866	2026-09-20 18:20	75.96	OK
14867	2026-09-20 18:21	79.50	OK	14868	2026-09-20 18:22	75.00	OK
14869	2026-09-20 18:23	75.50	OK	14870	2026-09-20 18:24	75.52	OK
14871	2026-09-20 18:25	76.16	OK	14872	2026-09-20 18:26	78.45	OK
14873	2026-09-20 18:27	76.53	OK	14874	2026-09-20 18:28	76.38	OK
14875	2026-09-20 18:29	74.43	OK	14876	2026-09-20 18:30	74.01	OK
14877	2026-09-20 18:31	75.00	OK	14878	2026-09-20 18:32	74.72	OK
14879	2026-09-20 18:33	76.46	OK	14880	2026-09-20 18:34	75.57	OK
14881	2026-09-20 18:35	73.57	OK	14882	2026-09-20 18:36	73.26	OK
14883	2026-09-20 18:37	77.79	OK	14884	2026-09-20 18:38	74.34	OK
14885	2026-09-20 18:39	76.34	OK	14886	2026-09-20 18:40	73.59	OK
14887	2026-09-20 18:41	78.18	OK	14888	2026-09-20 18:42	77.78	OK
14889	2026-09-20 18:43	76.02	OK	14890	2026-09-20 18:44	76.25	OK
14891	2026-09-20 18:45	76.69	OK	14892	2026-09-20 18:46	74.57	OK
14893	2026-09-20 18:47	74.60	OK	14894	2026-09-20 18:48	73.63	OK
14895	2026-09-20 18:49	75.04	OK	14896	2026-09-20 18:50	74.76	OK
14897	2026-09-20 18:51	72.95	OK	14898	2026-09-20 18:52	75.86	OK
14899	2026-09-20 18:53	74.97	OK	14900	2026-09-20 18:54	75.24	OK
14901	2026-09-20 18:55	74.20	OK	14902	2026-09-20 18:56	73.07	OK
14903	2026-09-20 18:57	75.27	OK	14904	2026-09-20 18:58	74.32	OK
14905	2026-09-20 18:59	73.98	OK	14906	2026-09-20 19:00	74.44	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14907	2026-09-20 19:01	74.88	OK	14908	2026-09-20 19:02	76.19	OK
14909	2026-09-20 19:03	74.96	OK	14910	2026-09-20 19:04	76.64	OK
14911	2026-09-20 19:05	73.70	OK	14912	2026-09-20 19:06	73.60	OK
14913	2026-09-20 19:07	75.67	OK	14914	2026-09-20 19:08	75.49	OK
14915	2026-09-20 19:09	74.11	OK	14916	2026-09-20 19:10	75.79	OK
14917	2026-09-20 19:11	73.87	OK	14918	2026-09-20 19:12	72.75	OK
14919	2026-09-20 19:13	71.92	OK	14920	2026-09-20 19:14	75.61	OK
14921	2026-09-20 19:15	75.00	OK	14922	2026-09-20 19:16	77.71	OK
14923	2026-09-20 19:17	76.36	OK	14924	2026-09-20 19:18	74.58	OK
14925	2026-09-20 19:19	76.00	OK	14926	2026-09-20 19:20	74.92	OK
14927	2026-09-20 19:21	73.45	OK	14928	2026-09-20 19:22	73.42	OK
14929	2026-09-20 19:23	76.23	OK	14930	2026-09-20 19:24	76.02	OK
14931	2026-09-20 19:25	73.42	OK	14932	2026-09-20 19:26	75.32	OK
14933	2026-09-20 19:27	71.40	OK	14934	2026-09-20 19:28	74.12	OK
14935	2026-09-20 19:29	74.11	OK	14936	2026-09-20 19:30	72.26	OK
14937	2026-09-20 19:31	73.45	OK	14938	2026-09-20 19:32	73.67	OK
14939	2026-09-20 19:33	73.45	OK	14940	2026-09-20 19:34	74.40	OK
14941	2026-09-20 19:35	76.41	OK	14942	2026-09-20 19:36	75.88	OK
14943	2026-09-20 19:37	74.90	OK	14944	2026-09-20 19:38	72.40	OK
14945	2026-09-20 19:39	71.99	OK	14946	2026-09-20 19:40	74.07	OK
14947	2026-09-20 19:41	75.23	OK	14948	2026-09-20 19:42	72.91	OK
14949	2026-09-20 19:43	77.20	OK	14950	2026-09-20 19:44	72.24	OK
14951	2026-09-20 19:45	71.84	OK	14952	2026-09-20 19:46	73.53	OK
14953	2026-09-20 19:47	73.95	OK	14954	2026-09-20 19:48	75.03	OK
14955	2026-09-20 19:49	73.16	OK	14956	2026-09-20 19:50	74.59	OK
14957	2026-09-20 19:51	73.70	OK	14958	2026-09-20 19:52	74.42	OK
14959	2026-09-20 19:53	73.60	OK	14960	2026-09-20 19:54	71.14	OK
14961	2026-09-20 19:55	70.89	OK	14962	2026-09-20 19:56	73.47	OK
14963	2026-09-20 19:57	72.58	OK	14964	2026-09-20 19:58	73.69	OK
14965	2026-09-20 19:59	71.40	OK	14966	2026-09-20 20:00	74.38	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14967	2026-09-20 20:01	74.26	OK	14968	2026-09-20 20:02	74.35	OK
14969	2026-09-20 20:03	74.42	OK	14970	2026-09-20 20:04	75.43	OK
14971	2026-09-20 20:05	73.51	OK	14972	2026-09-20 20:06	75.32	OK
14973	2026-09-20 20:07	71.56	OK	14974	2026-09-20 20:08	73.62	OK
14975	2026-09-20 20:09	75.30	OK	14976	2026-09-20 20:10	72.85	OK
14977	2026-09-20 20:11	72.61	OK	14978	2026-09-20 20:12	73.51	OK
14979	2026-09-20 20:13	73.84	OK	14980	2026-09-20 20:14	74.51	OK
14981	2026-09-20 20:15	73.86	OK	14982	2026-09-20 20:16	74.23	OK
14983	2026-09-20 20:17	71.57	OK	14984	2026-09-20 20:18	73.88	OK
14985	2026-09-20 20:19	73.89	OK	14986	2026-09-20 20:20	72.79	OK
14987	2026-09-20 20:21	73.14	OK	14988	2026-09-20 20:22	73.89	OK
14989	2026-09-20 20:23	74.73	OK	14990	2026-09-20 20:24	74.94	OK
14991	2026-09-20 20:25	71.24	OK	14992	2026-09-20 20:26	75.47	OK
14993	2026-09-20 20:27	72.19	OK	14994	2026-09-20 20:28	73.07	OK
14995	2026-09-20 20:29	73.41	OK	14996	2026-09-20 20:30	69.19	OK
14997	2026-09-20 20:31	72.05	OK	14998	2026-09-20 20:32	74.07	OK
14999	2026-09-20 20:33	74.02	OK	15000	2026-09-20 20:34	75.20	OK
15001	2026-09-20 20:35	74.90	OK	15002	2026-09-20 20:36	70.97	OK
15003	2026-09-20 20:37	70.57	OK	15004	2026-09-20 20:38	70.33	OK
15005	2026-09-20 20:39	73.62	OK	15006	2026-09-20 20:40	73.05	OK
15007	2026-09-20 20:41	73.93	OK	15008	2026-09-20 20:42	70.11	OK
15009	2026-09-20 20:43	71.87	OK	15010	2026-09-20 20:44	72.08	OK
15011	2026-09-20 20:45	75.57	OK	15012	2026-09-20 20:46	72.10	OK
15013	2026-09-20 20:47	76.12	OK	15014	2026-09-20 20:48	72.80	OK
15015	2026-09-20 20:49	72.28	OK	15016	2026-09-20 20:50	73.56	OK
15017	2026-09-20 20:51	68.44	OK	15018	2026-09-20 20:52	71.56	OK
15019	2026-09-20 20:53	73.87	OK	15020	2026-09-20 20:54	73.49	OK
15021	2026-09-20 20:55	70.31	OK	15022	2026-09-20 20:56	72.06	OK
15023	2026-09-20 20:57	74.49	OK	15024	2026-09-20 20:58	71.08	OK
15025	2026-09-20 20:59	72.68	OK	15026	2026-09-20 21:00	69.67	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15027	2026-09-20 21:01	69.57	OK	15028	2026-09-20 21:02	73.80	OK
15029	2026-09-20 21:03	72.45	OK	15030	2026-09-20 21:04	75.56	OK
15031	2026-09-20 21:05	75.53	OK	15032	2026-09-20 21:06	69.66	OK
15033	2026-09-20 21:07	71.97	OK	15034	2026-09-20 21:08	76.30	OK
15035	2026-09-20 21:09	69.87	OK	15036	2026-09-20 21:10	69.31	OK
15037	2026-09-20 21:11	72.36	OK	15038	2026-09-20 21:12	73.25	OK
15039	2026-09-20 21:13	70.71	OK	15040	2026-09-20 21:14	71.86	OK
15041	2026-09-20 21:15	71.43	OK	15042	2026-09-20 21:16	69.21	OK
15043	2026-09-20 21:17	70.13	OK	15044	2026-09-20 21:18	73.07	OK
15045	2026-09-20 21:19	74.56	OK	15046	2026-09-20 21:20	74.59	OK
15047	2026-09-20 21:21	69.83	OK	15048	2026-09-20 21:22	72.41	OK
15049	2026-09-20 21:23	70.61	OK	15050	2026-09-20 21:24	69.93	OK
15051	2026-09-20 21:25	74.56	OK	15052	2026-09-20 21:26	69.95	OK
15053	2026-09-20 21:27	71.73	OK	15054	2026-09-20 21:28	70.05	OK
15055	2026-09-20 21:29	72.03	OK	15056	2026-09-20 21:30	69.13	OK
15057	2026-09-20 21:31	72.56	OK	15058	2026-09-20 21:32	70.84	OK
15059	2026-09-20 21:33	70.91	OK	15060	2026-09-20 21:34	74.25	OK
15061	2026-09-20 21:35	69.95	OK	15062	2026-09-20 21:36	71.45	OK
15063	2026-09-20 21:37	69.44	OK	15064	2026-09-20 21:38	72.56	OK
15065	2026-09-20 21:39	71.66	OK	15066	2026-09-20 21:40	70.40	OK
15067	2026-09-20 21:41	70.53	OK	15068	2026-09-20 21:42	70.63	OK
15069	2026-09-20 21:43	69.68	OK	15070	2026-09-20 21:44	71.41	OK
15071	2026-09-20 21:45	70.73	OK	15072	2026-09-20 21:46	67.75	OK
15073	2026-09-20 21:47	68.13	OK	15074	2026-09-20 21:48	70.22	OK
15075	2026-09-20 21:49	70.66	OK	15076	2026-09-20 21:50	72.08	OK
15077	2026-09-20 21:51	68.17	OK	15078	2026-09-20 21:52	69.59	OK
15079	2026-09-20 21:53	70.36	OK	15080	2026-09-20 21:54	71.34	OK
15081	2026-09-20 21:55	70.62	OK	15082	2026-09-20 21:56	72.64	OK
15083	2026-09-20 21:57	70.65	OK	15084	2026-09-20 21:58	73.10	OK
15085	2026-09-20 21:59	73.50	OK	15086	2026-09-20 22:00	71.11	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15087	2026-09-20 22:01	70.25	OK	15088	2026-09-20 22:02	72.75	OK
15089	2026-09-20 22:03	70.40	OK	15090	2026-09-20 22:04	72.59	OK
15091	2026-09-20 22:05	69.20	OK	15092	2026-09-20 22:06	71.70	OK
15093	2026-09-20 22:07	71.36	OK	15094	2026-09-20 22:08	69.73	OK
15095	2026-09-20 22:09	69.14	OK	15096	2026-09-20 22:10	68.53	OK
15097	2026-09-20 22:11	72.66	OK	15098	2026-09-20 22:12	69.87	OK
15099	2026-09-20 22:13	71.23	OK	15100	2026-09-20 22:14	73.62	OK
15101	2026-09-20 22:15	68.61	OK	15102	2026-09-20 22:16	69.87	OK
15103	2026-09-20 22:17	70.92	OK	15104	2026-09-20 22:18	71.99	OK
15105	2026-09-20 22:19	70.74	OK	15106	2026-09-20 22:20	70.45	OK
15107	2026-09-20 22:21	68.85	OK	15108	2026-09-20 22:22	71.52	OK
15109	2026-09-20 22:23	71.77	OK	15110	2026-09-20 22:24	73.70	OK
15111	2026-09-20 22:25	72.66	OK	15112	2026-09-20 22:26	68.63	OK
15113	2026-09-20 22:27	71.25	OK	15114	2026-09-20 22:28	72.60	OK
15115	2026-09-20 22:29	69.92	OK	15116	2026-09-20 22:30	70.68	OK
15117	2026-09-20 22:31	70.20	OK	15118	2026-09-20 22:32	68.07	OK
15119	2026-09-20 22:33	72.15	OK	15120	2026-09-20 22:34	67.38	OK
15121	2026-09-20 22:35	73.29	OK	15122	2026-09-20 22:36	66.43	OK
15123	2026-09-20 22:37	68.61	OK	15124	2026-09-20 22:38	70.70	OK
15125	2026-09-20 22:39	71.51	OK	15126	2026-09-20 22:40	68.42	OK
15127	2026-09-20 22:41	69.95	OK	15128	2026-09-20 22:42	72.42	OK
15129	2026-09-20 22:43	70.17	OK	15130	2026-09-20 22:44	72.38	OK
15131	2026-09-20 22:45	71.15	OK	15132	2026-09-20 22:46	70.76	OK
15133	2026-09-20 22:47	70.80	OK	15134	2026-09-20 22:48	71.50	OK
15135	2026-09-20 22:49	69.86	OK	15136	2026-09-20 22:50	69.57	OK
15137	2026-09-20 22:51	71.24	OK	15138	2026-09-20 22:52	70.88	OK
15139	2026-09-20 22:53	68.78	OK	15140	2026-09-20 22:54	70.14	OK
15141	2026-09-20 22:55	70.84	OK	15142	2026-09-20 22:56	71.54	OK
15143	2026-09-20 22:57	71.59	OK	15144	2026-09-20 22:58	69.74	OK
15145	2026-09-20 22:59	71.62	OK	15146	2026-09-20 23:00	70.30	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15147	2026-09-20 23:01	71.07	OK	15148	2026-09-20 23:02	69.65	OK
15149	2026-09-20 23:03	68.00	OK	15150	2026-09-20 23:04	73.62	OK
15151	2026-09-20 23:05	70.02	OK	15152	2026-09-20 23:06	68.88	OK
15153	2026-09-20 23:07	70.25	OK	15154	2026-09-20 23:08	72.17	OK
15155	2026-09-20 23:09	69.93	OK	15156	2026-09-20 23:10	67.42	OK
15157	2026-09-20 23:11	68.78	OK	15158	2026-09-20 23:12	69.40	OK
15159	2026-09-20 23:13	68.09	OK	15160	2026-09-20 23:14	73.14	OK
15161	2026-09-20 23:15	68.82	OK	15162	2026-09-20 23:16	69.85	OK
15163	2026-09-20 23:17	70.10	OK	15164	2026-09-20 23:18	70.39	OK
15165	2026-09-20 23:19	71.08	OK	15166	2026-09-20 23:20	70.18	OK
15167	2026-09-20 23:21	70.21	OK	15168	2026-09-20 23:22	70.39	OK
15169	2026-09-20 23:23	71.33	OK	15170	2026-09-20 23:24	68.53	OK
15171	2026-09-20 23:25	72.48	OK	15172	2026-09-20 23:26	68.94	OK
15173	2026-09-20 23:27	71.00	OK	15174	2026-09-20 23:28	68.44	OK
15175	2026-09-20 23:29	72.04	OK	15176	2026-09-20 23:30	69.60	OK
15177	2026-09-20 23:31	70.99	OK	15178	2026-09-20 23:32	67.45	OK
15179	2026-09-20 23:33	70.20	OK	15180	2026-09-20 23:34	68.84	OK
15181	2026-09-20 23:35	68.25	OK	15182	2026-09-20 23:36	70.07	OK
15183	2026-09-20 23:37	67.12	OK	15184	2026-09-20 23:38	72.76	OK
15185	2026-09-20 23:39	69.55	OK	15186	2026-09-20 23:40	70.18	OK
15187	2026-09-20 23:41	70.75	OK	15188	2026-09-20 23:42	73.19	OK
15189	2026-09-20 23:43	70.67	OK	15190	2026-09-20 23:44	69.07	OK
15191	2026-09-20 23:45	70.11	OK	15192	2026-09-20 23:46	69.68	OK
15193	2026-09-20 23:47	66.49	OK	15194	2026-09-20 23:48	69.58	OK
15195	2026-09-20 23:49	73.23	OK	15196	2026-09-20 23:50	68.28	OK
15197	2026-09-20 23:51	69.90	OK	15198	2026-09-20 23:52	70.21	OK
15199	2026-09-20 23:53	68.18	OK	15200	2026-09-20 23:54	71.90	OK
15201	2026-09-20 23:55	73.13	OK	15202	2026-09-20 23:56	66.04	OK
15203	2026-09-20 23:57	67.91	OK	15204	2026-09-20 23:58	70.00	OK
15205	2026-09-20 23:59	72.32	OK	15206	2026-09-21 00:00	70.11	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15207	2026-09-21 00:01	69.03	OK	15208	2026-09-21 00:02	72.81	OK
15209	2026-09-21 00:03	67.61	OK	15210	2026-09-21 00:04	67.40	OK
15211	2026-09-21 00:05	68.54	OK	15212	2026-09-21 00:06	68.30	OK
15213	2026-09-21 00:07	70.81	OK	15214	2026-09-21 00:08	66.36	OK
15215	2026-09-21 00:09	67.45	OK	15216	2026-09-21 00:10	68.00	OK
15217	2026-09-21 00:11	68.53	OK	15218	2026-09-21 00:12	70.49	OK
15219	2026-09-21 00:13	68.42	OK	15220	2026-09-21 00:14	70.53	OK
15221	2026-09-21 00:15	67.24	OK	15222	2026-09-21 00:16	67.02	OK
15223	2026-09-21 00:17	68.16	OK	15224	2026-09-21 00:18	67.12	OK
15225	2026-09-21 00:19	68.64	OK	15226	2026-09-21 00:20	69.57	OK
15227	2026-09-21 00:21	69.92	OK	15228	2026-09-21 00:22	68.89	OK
15229	2026-09-21 00:23	68.47	OK	15230	2026-09-21 00:24	68.41	OK
15231	2026-09-21 00:25	68.85	OK	15232	2026-09-21 00:26	70.50	OK
15233	2026-09-21 00:27	66.84	OK	15234	2026-09-21 00:28	71.16	OK
15235	2026-09-21 00:29	72.75	OK	15236	2026-09-21 00:30	71.85	OK
15237	2026-09-21 00:31	68.73	OK	15238	2026-09-21 00:32	72.09	OK
15239	2026-09-21 00:33	68.46	OK	15240	2026-09-21 00:34	69.42	OK
15241	2026-09-21 00:35	72.96	OK	15242	2026-09-21 00:36	68.68	OK
15243	2026-09-21 00:37	69.79	OK	15244	2026-09-21 00:38	66.41	OK
15245	2026-09-21 00:39	69.29	OK	15246	2026-09-21 00:40	70.51	OK
15247	2026-09-21 00:41	69.95	OK	15248	2026-09-21 00:42	70.13	OK
15249	2026-09-21 00:43	68.61	OK	15250	2026-09-21 00:44	70.22	OK
15251	2026-09-21 00:45	66.74	OK	15252	2026-09-21 00:46	66.46	OK
15253	2026-09-21 00:47	72.26	OK	15254	2026-09-21 00:48	70.82	OK
15255	2026-09-21 00:49	71.69	OK	15256	2026-09-21 00:50	67.62	OK
15257	2026-09-21 00:51	70.09	OK	15258	2026-09-21 00:52	71.92	OK
15259	2026-09-21 00:53	68.98	OK	15260	2026-09-21 00:54	67.92	OK
15261	2026-09-21 00:55	72.44	OK	15262	2026-09-21 00:56	67.37	OK
15263	2026-09-21 00:57	71.54	OK	15264	2026-09-21 00:58	69.56	OK
15265	2026-09-21 00:59	67.54	OK	15266	2026-09-21 01:00	72.48	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15267	2026-09-21 01:01	69.74	OK	15268	2026-09-21 01:02	68.08	OK
15269	2026-09-21 01:03	69.28	OK	15270	2026-09-21 01:04	69.88	OK
15271	2026-09-21 01:05	67.95	OK	15272	2026-09-21 01:06	71.94	OK
15273	2026-09-21 01:07	69.04	OK	15274	2026-09-21 01:08	70.75	OK
15275	2026-09-21 01:09	69.63	OK	15276	2026-09-21 01:10	69.26	OK
15277	2026-09-21 01:11	67.48	OK	15278	2026-09-21 01:12	69.17	OK
15279	2026-09-21 01:13	70.13	OK	15280	2026-09-21 01:14	72.32	OK
15281	2026-09-21 01:15	68.29	OK	15282	2026-09-21 01:16	68.29	OK
15283	2026-09-21 01:17	72.27	OK	15284	2026-09-21 01:18	70.56	OK
15285	2026-09-21 01:19	68.89	OK	15286	2026-09-21 01:20	68.19	OK
15287	2026-09-21 01:21	70.33	OK	15288	2026-09-21 01:22	71.16	OK
15289	2026-09-21 01:23	71.50	OK	15290	2026-09-21 01:24	69.89	OK
15291	2026-09-21 01:25	67.66	OK	15292	2026-09-21 01:26	69.40	OK
15293	2026-09-21 01:27	68.43	OK	15294	2026-09-21 01:28	71.31	OK
15295	2026-09-21 01:29	70.69	OK	15296	2026-09-21 01:30	71.47	OK
15297	2026-09-21 01:31	70.83	OK	15298	2026-09-21 01:32	68.03	OK
15299	2026-09-21 01:33	66.99	OK	15300	2026-09-21 01:34	69.31	OK
15301	2026-09-21 01:35	70.35	OK	15302	2026-09-21 01:36	71.56	OK
15303	2026-09-21 01:37	70.54	OK	15304	2026-09-21 01:38	66.57	OK
15305	2026-09-21 01:39	69.93	OK	15306	2026-09-21 01:40	71.58	OK
15307	2026-09-21 01:41	68.64	OK	15308	2026-09-21 01:42	71.72	OK
15309	2026-09-21 01:43	68.99	OK	15310	2026-09-21 01:44	72.17	OK
15311	2026-09-21 01:45	73.31	OK	15312	2026-09-21 01:46	71.00	OK
15313	2026-09-21 01:47	70.80	OK	15314	2026-09-21 01:48	71.47	OK
15315	2026-09-21 01:49	70.22	OK	15316	2026-09-21 01:50	66.99	OK
15317	2026-09-21 01:51	70.68	OK	15318	2026-09-21 01:52	69.06	OK
15319	2026-09-21 01:53	71.03	OK	15320	2026-09-21 01:54	67.61	OK
15321	2026-09-21 01:55	69.71	OK	15322	2026-09-21 01:56	72.04	OK
15323	2026-09-21 01:57	69.05	OK	15324	2026-09-21 01:58	67.95	OK
15325	2026-09-21 01:59	69.36	OK	15326	2026-09-21 02:00	70.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15327	2026-09-21 02:01	70.05	OK	15328	2026-09-21 02:02	69.17	OK
15329	2026-09-21 02:03	70.76	OK	15330	2026-09-21 02:04	70.52	OK
15331	2026-09-21 02:05	67.83	OK	15332	2026-09-21 02:06	66.92	OK
15333	2026-09-21 02:07	70.42	OK	15334	2026-09-21 02:08	72.10	OK
15335	2026-09-21 02:09	71.48	OK	15336	2026-09-21 02:10	69.98	OK
15337	2026-09-21 02:11	70.57	OK	15338	2026-09-21 02:12	70.19	OK
15339	2026-09-21 02:13	70.38	OK	15340	2026-09-21 02:14	66.34	OK
15341	2026-09-21 02:15	67.89	OK	15342	2026-09-21 02:16	71.91	OK
15343	2026-09-21 02:17	66.42	OK	15344	2026-09-21 02:18	68.09	OK
15345	2026-09-21 02:19	71.74	OK	15346	2026-09-21 02:20	66.62	OK
15347	2026-09-21 02:21	70.35	OK	15348	2026-09-21 02:22	70.72	OK
15349	2026-09-21 02:23	70.49	OK	15350	2026-09-21 02:24	68.85	OK
15351	2026-09-21 02:25	73.75	OK	15352	2026-09-21 02:26	72.26	OK
15353	2026-09-21 02:27	71.88	OK	15354	2026-09-21 02:28	68.18	OK
15355	2026-09-21 02:29	69.54	OK	15356	2026-09-21 02:30	71.52	OK
15357	2026-09-21 02:31	71.02	OK	15358	2026-09-21 02:32	68.26	OK
15359	2026-09-21 02:33	69.94	OK	15360	2026-09-21 02:34	70.06	OK
15361	2026-09-21 02:35	71.81	OK	15362	2026-09-21 02:36	71.18	OK
15363	2026-09-21 02:37	70.13	OK	15364	2026-09-21 02:38	69.46	OK
15365	2026-09-21 02:39	72.90	OK	15366	2026-09-21 02:40	67.21	OK
15367	2026-09-21 02:41	70.91	OK	15368	2026-09-21 02:42	68.19	OK
15369	2026-09-21 02:43	72.01	OK	15370	2026-09-21 02:44	69.23	OK
15371	2026-09-21 02:45	69.96	OK	15372	2026-09-21 02:46	68.69	OK
15373	2026-09-21 02:47	67.95	OK	15374	2026-09-21 02:48	67.84	OK
15375	2026-09-21 02:49	72.38	OK	15376	2026-09-21 02:50	70.77	OK
15377	2026-09-21 02:51	70.90	OK	15378	2026-09-21 02:52	70.36	OK
15379	2026-09-21 02:53	71.92	OK	15380	2026-09-21 02:54	67.83	OK
15381	2026-09-21 02:55	69.37	OK	15382	2026-09-21 02:56	71.86	OK
15383	2026-09-21 02:57	68.70	OK	15384	2026-09-21 02:58	70.69	OK
15385	2026-09-21 02:59	69.64	OK	15386	2026-09-21 03:00	67.84	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15387	2026-09-21 03:01	70.82	OK	15388	2026-09-21 03:02	67.60	OK
15389	2026-09-21 03:03	68.72	OK	15390	2026-09-21 03:04	69.36	OK
15391	2026-09-21 03:05	68.96	OK	15392	2026-09-21 03:06	68.65	OK
15393	2026-09-21 03:07	70.50	OK	15394	2026-09-21 03:08	68.19	OK
15395	2026-09-21 03:09	70.03	OK	15396	2026-09-21 03:10	69.06	OK
15397	2026-09-21 03:11	71.38	OK	15398	2026-09-21 03:12	69.45	OK
15399	2026-09-21 03:13	71.47	OK	15400	2026-09-21 03:14	70.52	OK
15401	2026-09-21 03:15	70.88	OK	15402	2026-09-21 03:16	69.28	OK
15403	2026-09-21 03:17	71.03	OK	15404	2026-09-21 03:18	71.69	OK
15405	2026-09-21 03:19	69.51	OK	15406	2026-09-21 03:20	70.87	OK
15407	2026-09-21 03:21	71.40	OK	15408	2026-09-21 03:22	71.21	OK
15409	2026-09-21 03:23	69.84	OK	15410	2026-09-21 03:24	68.04	OK
15411	2026-09-21 03:25	69.60	OK	15412	2026-09-21 03:26	70.78	OK
15413	2026-09-21 03:27	70.51	OK	15414	2026-09-21 03:28	70.64	OK
15415	2026-09-21 03:29	72.76	OK	15416	2026-09-21 03:30	69.31	OK
15417	2026-09-21 03:31	72.52	OK	15418	2026-09-21 03:32	68.36	OK
15419	2026-09-21 03:33	70.55	OK	15420	2026-09-21 03:34	72.64	OK
15421	2026-09-21 03:35	71.87	OK	15422	2026-09-21 03:36	73.61	OK
15423	2026-09-21 03:37	71.80	OK	15424	2026-09-21 03:38	68.86	OK
15425	2026-09-21 03:39	71.99	OK	15426	2026-09-21 03:40	72.92	OK
15427	2026-09-21 03:41	74.98	OK	15428	2026-09-21 03:42	71.92	OK
15429	2026-09-21 03:43	71.39	OK	15430	2026-09-21 03:44	71.31	OK
15431	2026-09-21 03:45	72.46	OK	15432	2026-09-21 03:46	69.48	OK
15433	2026-09-21 03:47	73.33	OK	15434	2026-09-21 03:48	71.84	OK
15435	2026-09-21 03:49	71.93	OK	15436	2026-09-21 03:50	69.75	OK
15437	2026-09-21 03:51	68.28	OK	15438	2026-09-21 03:52	71.98	OK
15439	2026-09-21 03:53	71.86	OK	15440	2026-09-21 03:54	70.32	OK
15441	2026-09-21 03:55	73.67	OK	15442	2026-09-21 03:56	72.84	OK
15443	2026-09-21 03:57	71.61	OK	15444	2026-09-21 03:58	69.53	OK
15445	2026-09-21 03:59	70.45	OK	15446	2026-09-21 04:00	71.75	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15447	2026-09-21 04:01	72.48	OK	15448	2026-09-21 04:02	68.49	OK
15449	2026-09-21 04:03	71.28	OK	15450	2026-09-21 04:04	71.88	OK
15451	2026-09-21 04:05	73.75	OK	15452	2026-09-21 04:06	70.81	OK
15453	2026-09-21 04:07	70.82	OK	15454	2026-09-21 04:08	72.36	OK
15455	2026-09-21 04:09	70.96	OK	15456	2026-09-21 04:10	71.65	OK
15457	2026-09-21 04:11	73.81	OK	15458	2026-09-21 04:12	75.07	OK
15459	2026-09-21 04:13	71.87	OK	15460	2026-09-21 04:14	75.05	OK
15461	2026-09-21 04:15	70.90	OK	15462	2026-09-21 04:16	73.63	OK
15463	2026-09-21 04:17	70.89	OK	15464	2026-09-21 04:18	72.61	OK
15465	2026-09-21 04:19	72.10	OK	15466	2026-09-21 04:20	71.56	OK
15467	2026-09-21 04:21	71.21	OK	15468	2026-09-21 04:22	70.48	OK
15469	2026-09-21 04:23	72.80	OK	15470	2026-09-21 04:24	70.09	OK
15471	2026-09-21 04:25	71.57	OK	15472	2026-09-21 04:26	69.96	OK
15473	2026-09-21 04:27	72.14	OK	15474	2026-09-21 04:28	70.16	OK
15475	2026-09-21 04:29	73.18	OK	15476	2026-09-21 04:30	73.12	OK
15477	2026-09-21 04:31	71.52	OK	15478	2026-09-21 04:32	71.28	OK
15479	2026-09-21 04:33	70.79	OK	15480	2026-09-21 04:34	71.24	OK
15481	2026-09-21 04:35	70.72	OK	15482	2026-09-21 04:36	71.70	OK
15483	2026-09-21 04:37	74.00	OK	15484	2026-09-21 04:38	73.49	OK
15485	2026-09-21 04:39	73.46	OK	15486	2026-09-21 04:40	71.12	OK
15487	2026-09-21 04:41	71.72	OK	15488	2026-09-21 04:42	72.94	OK
15489	2026-09-21 04:43	71.02	OK	15490	2026-09-21 04:44	72.60	OK
15491	2026-09-21 04:45	72.94	OK	15492	2026-09-21 04:46	70.65	OK
15493	2026-09-21 04:47	70.58	OK	15494	2026-09-21 04:48	71.47	OK
15495	2026-09-21 04:49	73.14	OK	15496	2026-09-21 04:50	74.16	OK
15497	2026-09-21 04:51	71.83	OK	15498	2026-09-21 04:52	75.08	OK
15499	2026-09-21 04:53	69.08	OK	15500	2026-09-21 04:54	74.45	OK
15501	2026-09-21 04:55	69.45	OK	15502	2026-09-21 04:56	68.95	OK
15503	2026-09-21 04:57	74.10	OK	15504	2026-09-21 04:58	70.83	OK
15505	2026-09-21 04:59	68.65	OK	15506	2026-09-21 05:00	72.10	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15507	2026-09-21 05:01	70.25	OK	15508	2026-09-21 05:02	70.12	OK
15509	2026-09-21 05:03	74.02	OK	15510	2026-09-21 05:04	71.78	OK
15511	2026-09-21 05:05	73.64	OK	15512	2026-09-21 05:06	72.46	OK
15513	2026-09-21 05:07	75.03	OK	15514	2026-09-21 05:08	71.07	OK
15515	2026-09-21 05:09	69.17	OK	15516	2026-09-21 05:10	71.78	OK
15517	2026-09-21 05:11	70.92	OK	15518	2026-09-21 05:12	70.72	OK
15519	2026-09-21 05:13	74.25	OK	15520	2026-09-21 05:14	74.05	OK
15521	2026-09-21 05:15	74.11	OK	15522	2026-09-21 05:16	73.89	OK
15523	2026-09-21 05:17	71.00	OK	15524	2026-09-21 05:18	73.25	OK
15525	2026-09-21 05:19	72.19	OK	15526	2026-09-21 05:20	73.26	OK
15527	2026-09-21 05:21	72.56	OK	15528	2026-09-21 05:22	70.54	OK
15529	2026-09-21 05:23	73.98	OK	15530	2026-09-21 05:24	72.01	OK
15531	2026-09-21 05:25	71.52	OK	15532	2026-09-21 05:26	72.97	OK
15533	2026-09-21 05:27	72.34	OK	15534	2026-09-21 05:28	75.36	OK
15535	2026-09-21 05:29	73.86	OK	15536	2026-09-21 05:30	73.54	OK
15537	2026-09-21 05:31	70.15	OK	15538	2026-09-21 05:32	72.05	OK
15539	2026-09-21 05:33	71.68	OK	15540	2026-09-21 05:34	73.73	OK
15541	2026-09-21 05:35	75.46	OK	15542	2026-09-21 05:36	73.73	OK
15543	2026-09-21 05:37	74.12	OK	15544	2026-09-21 05:38	74.97	OK
15545	2026-09-21 05:39	74.72	OK	15546	2026-09-21 05:40	71.53	OK
15547	2026-09-21 05:41	72.52	OK	15548	2026-09-21 05:42	75.04	OK
15549	2026-09-21 05:43	72.96	OK	15550	2026-09-21 05:44	69.88	OK
15551	2026-09-21 05:45	73.09	OK	15552	2026-09-21 05:46	74.81	OK
15553	2026-09-21 05:47	72.98	OK	15554	2026-09-21 05:48	70.39	OK
15555	2026-09-21 05:49	72.83	OK	15556	2026-09-21 05:50	71.09	OK
15557	2026-09-21 05:51	75.87	OK	15558	2026-09-21 05:52	72.08	OK
15559	2026-09-21 05:53	74.89	OK	15560	2026-09-21 05:54	72.64	OK
15561	2026-09-21 05:55	74.87	OK	15562	2026-09-21 05:56	76.20	OK
15563	2026-09-21 05:57	72.06	OK	15564	2026-09-21 05:58	73.84	OK
15565	2026-09-21 05:59	75.25	OK	15566	2026-09-21 06:00	76.22	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15567	2026-09-21 06:01	73.42	OK	15568	2026-09-21 06:02	74.80	OK
15569	2026-09-21 06:03	72.84	OK	15570	2026-09-21 06:04	72.75	OK
15571	2026-09-21 06:05	72.63	OK	15572	2026-09-21 06:06	76.83	OK
15573	2026-09-21 06:07	75.36	OK	15574	2026-09-21 06:08	73.02	OK
15575	2026-09-21 06:09	75.72	OK	15576	2026-09-21 06:10	72.95	OK
15577	2026-09-21 06:11	72.78	OK	15578	2026-09-21 06:12	76.39	OK
15579	2026-09-21 06:13	73.17	OK	15580	2026-09-21 06:14	73.02	OK
15581	2026-09-21 06:15	71.90	OK	15582	2026-09-21 06:16	73.38	OK
15583	2026-09-21 06:17	70.27	OK	15584	2026-09-21 06:18	74.70	OK
15585	2026-09-21 06:19	71.97	OK	15586	2026-09-21 06:20	75.97	OK
15587	2026-09-21 06:21	74.46	OK	15588	2026-09-21 06:22	71.73	OK
15589	2026-09-21 06:23	72.94	OK	15590	2026-09-21 06:24	72.80	OK
15591	2026-09-21 06:25	73.60	OK	15592	2026-09-21 06:26	76.22	OK
15593	2026-09-21 06:27	74.56	OK	15594	2026-09-21 06:28	74.46	OK
15595	2026-09-21 06:29	74.85	OK	15596	2026-09-21 06:30	73.77	OK
15597	2026-09-21 06:31	75.82	OK	15598	2026-09-21 06:32	76.32	OK
15599	2026-09-21 06:33	74.22	OK	15600	2026-09-21 06:34	75.22	OK
15601	2026-09-21 06:35	73.05	OK	15602	2026-09-21 06:36	75.03	OK
15603	2026-09-21 06:37	75.17	OK	15604	2026-09-21 06:38	72.78	OK
15605	2026-09-21 06:39	75.86	OK	15606	2026-09-21 06:40	75.28	OK
15607	2026-09-21 06:41	75.80	OK	15608	2026-09-21 06:42	71.51	OK
15609	2026-09-21 06:43	75.54	OK	15610	2026-09-21 06:44	75.87	OK
15611	2026-09-21 06:45	75.95	OK	15612	2026-09-21 06:46	75.78	OK
15613	2026-09-21 06:47	71.43	OK	15614	2026-09-21 06:48	76.07	OK
15615	2026-09-21 06:49	76.90	OK	15616	2026-09-21 06:50	73.65	OK
15617	2026-09-21 06:51	74.68	OK	15618	2026-09-21 06:52	77.03	OK
15619	2026-09-21 06:53	73.13	OK	15620	2026-09-21 06:54	74.14	OK
15621	2026-09-21 06:55	78.31	OK	15622	2026-09-21 06:56	73.44	OK
15623	2026-09-21 06:57	73.57	OK	15624	2026-09-21 06:58	77.10	OK
15625	2026-09-21 06:59	76.73	OK	15626	2026-09-21 07:00	74.29	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15627	2026-09-21 07:01	73.82	OK	15628	2026-09-21 07:02	75.11	OK
15629	2026-09-21 07:03	76.91	OK	15630	2026-09-21 07:04	72.24	OK
15631	2026-09-21 07:05	74.58	OK	15632	2026-09-21 07:06	74.39	OK
15633	2026-09-21 07:07	75.92	OK	15634	2026-09-21 07:08	77.54	OK
15635	2026-09-21 07:09	79.10	OK	15636	2026-09-21 07:10	75.02	OK
15637	2026-09-21 07:11	74.04	OK	15638	2026-09-21 07:12	72.29	OK
15639	2026-09-21 07:13	75.57	OK	15640	2026-09-21 07:14	76.23	OK
15641	2026-09-21 07:15	73.06	OK	15642	2026-09-21 07:16	76.22	OK
15643	2026-09-21 07:17	74.69	OK	15644	2026-09-21 07:18	77.10	OK
15645	2026-09-21 07:19	77.64	OK	15646	2026-09-21 07:20	73.03	OK
15647	2026-09-21 07:21	77.50	OK	15648	2026-09-21 07:22	75.21	OK
15649	2026-09-21 07:23	78.80	OK	15650	2026-09-21 07:24	73.72	OK
15651	2026-09-21 07:25	77.44	OK	15652	2026-09-21 07:26	73.72	OK
15653	2026-09-21 07:27	78.47	OK	15654	2026-09-21 07:28	75.51	OK
15655	2026-09-21 07:29	74.01	OK	15656	2026-09-21 07:30	76.36	OK
15657	2026-09-21 07:31	76.73	OK	15658	2026-09-21 07:32	74.79	OK
15659	2026-09-21 07:33	77.40	OK	15660	2026-09-21 07:34	74.72	OK
15661	2026-09-21 07:35	75.40	OK	15662	2026-09-21 07:36	75.82	OK
15663	2026-09-21 07:37	75.02	OK	15664	2026-09-21 07:38	77.84	OK
15665	2026-09-21 07:39	74.23	OK	15666	2026-09-21 07:40	79.06	OK
15667	2026-09-21 07:41	73.75	OK	15668	2026-09-21 07:42	77.15	OK
15669	2026-09-21 07:43	78.81	OK	15670	2026-09-21 07:44	76.46	OK
15671	2026-09-21 07:45	78.45	OK	15672	2026-09-21 07:46	76.65	OK
15673	2026-09-21 07:47	77.67	OK	15674	2026-09-21 07:48	76.54	OK
15675	2026-09-21 07:49	77.91	OK	15676	2026-09-21 07:50	75.53	OK
15677	2026-09-21 07:51	76.50	OK	15678	2026-09-21 07:52	77.32	OK
15679	2026-09-21 07:53	78.73	OK	15680	2026-09-21 07:54	77.91	OK
15681	2026-09-21 07:55	76.90	OK	15682	2026-09-21 07:56	77.44	OK
15683	2026-09-21 07:57	77.93	OK	15684	2026-09-21 07:58	75.13	OK
15685	2026-09-21 07:59	78.13	OK	15686	2026-09-21 08:00	78.64	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15687	2026-09-21 08:01	74.84	OK	15688	2026-09-21 08:02	76.02	OK
15689	2026-09-21 08:03	77.67	OK	15690	2026-09-21 08:04	74.99	OK
15691	2026-09-21 08:05	77.45	OK	15692	2026-09-21 08:06	77.19	OK
15693	2026-09-21 08:07	75.92	OK	15694	2026-09-21 08:08	76.81	OK
15695	2026-09-21 08:09	77.90	OK	15696	2026-09-21 08:10	75.56	OK
15697	2026-09-21 08:11	75.91	OK	15698	2026-09-21 08:12	75.07	OK
15699	2026-09-21 08:13	75.58	OK	15700	2026-09-21 08:14	76.51	OK
15701	2026-09-21 08:15	75.25	OK	15702	2026-09-21 08:16	78.23	OK
15703	2026-09-21 08:17	74.30	OK	15704	2026-09-21 08:18	76.17	OK
15705	2026-09-21 08:19	76.01	OK	15706	2026-09-21 08:20	76.15	OK
15707	2026-09-21 08:21	77.47	OK	15708	2026-09-21 08:22	78.89	OK
15709	2026-09-21 08:23	79.63	OK	15710	2026-09-21 08:24	75.91	OK
15711	2026-09-21 08:25	75.57	OK	15712	2026-09-21 08:26	79.56	OK
15713	2026-09-21 08:27	77.43	OK	15714	2026-09-21 08:28	78.89	OK
15715	2026-09-21 08:29	77.99	OK	15716	2026-09-21 08:30	79.52	OK
15717	2026-09-21 08:31	78.86	OK	15718	2026-09-21 08:32	79.02	OK
15719	2026-09-21 08:33	76.62	OK	15720	2026-09-21 08:34	75.06	OK
15721	2026-09-21 08:35	78.97	OK	15722	2026-09-21 08:36	78.06	OK
15723	2026-09-21 08:37	77.36	OK	15724	2026-09-21 08:38	77.05	OK
15725	2026-09-21 08:39	80.29	OK	15726	2026-09-21 08:40	78.22	OK
15727	2026-09-21 08:41	78.65	OK	15728	2026-09-21 08:42	78.81	OK
15729	2026-09-21 08:43	80.78	OK	15730	2026-09-21 08:44	76.77	OK
15731	2026-09-21 08:45	80.46	OK	15732	2026-09-21 08:46	76.88	OK
15733	2026-09-21 08:47	79.33	OK	15734	2026-09-21 08:48	81.33	OK
15735	2026-09-21 08:49	80.53	OK	15736	2026-09-21 08:50	77.12	OK
15737	2026-09-21 08:51	78.36	OK	15738	2026-09-21 08:52	76.32	OK
15739	2026-09-21 08:53	76.29	OK	15740	2026-09-21 08:54	74.42	OK
15741	2026-09-21 08:55	78.08	OK	15742	2026-09-21 08:56	78.05	OK
15743	2026-09-21 08:57	80.18	OK	15744	2026-09-21 08:58	75.69	OK
15745	2026-09-21 08:59	76.97	OK	15746	2026-09-21 09:00	79.24	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15747	2026-09-21 09:01	78.13	OK	15748	2026-09-21 09:02	78.05	OK
15749	2026-09-21 09:03	78.48	OK	15750	2026-09-21 09:04	78.79	OK
15751	2026-09-21 09:05	77.21	OK	15752	2026-09-21 09:06	79.52	OK
15753	2026-09-21 09:07	77.93	OK	15754	2026-09-21 09:08	82.30	OK
15755	2026-09-21 09:09	76.40	OK	15756	2026-09-21 09:10	77.07	OK
15757	2026-09-21 09:11	77.45	OK	15758	2026-09-21 09:12	79.50	OK
15759	2026-09-21 09:13	75.30	OK	15760	2026-09-21 09:14	78.78	OK
15761	2026-09-21 09:15	75.46	OK	15762	2026-09-21 09:16	78.62	OK
15763	2026-09-21 09:17	78.26	OK	15764	2026-09-21 09:18	75.55	OK
15765	2026-09-21 09:19	78.13	OK	15766	2026-09-21 09:20	78.43	OK
15767	2026-09-21 09:21	78.37	OK	15768	2026-09-21 09:22	78.45	OK
15769	2026-09-21 09:23	77.11	OK	15770	2026-09-21 09:24	78.14	OK
15771	2026-09-21 09:25	78.66	OK	15772	2026-09-21 09:26	80.66	OK
15773	2026-09-21 09:27	79.29	OK	15774	2026-09-21 09:28	77.93	OK
15775	2026-09-21 09:29	80.83	OK	15776	2026-09-21 09:30	78.77	OK
15777	2026-09-21 09:31	75.94	OK	15778	2026-09-21 09:32	78.52	OK
15779	2026-09-21 09:33	78.66	OK	15780	2026-09-21 09:34	78.63	OK
15781	2026-09-21 09:35	77.76	OK	15782	2026-09-21 09:36	80.22	OK
15783	2026-09-21 09:37	78.68	OK	15784	2026-09-21 09:38	77.73	OK
15785	2026-09-21 09:39	81.10	OK	15786	2026-09-21 09:40	80.59	OK
15787	2026-09-21 09:41	77.32	OK	15788	2026-09-21 09:42	76.07	OK
15789	2026-09-21 09:43	79.56	OK	15790	2026-09-21 09:44	79.14	OK
15791	2026-09-21 09:45	77.90	OK	15792	2026-09-21 09:46	78.41	OK
15793	2026-09-21 09:47	76.32	OK	15794	2026-09-21 09:48	80.79	OK
15795	2026-09-21 09:49	81.11	OK	15796	2026-09-21 09:50	80.22	OK
15797	2026-09-21 09:51	79.36	OK	15798	2026-09-21 09:52	76.99	OK
15799	2026-09-21 09:53	77.73	OK	15800	2026-09-21 09:54	77.16	OK
15801	2026-09-21 09:55	78.81	OK	15802	2026-09-21 09:56	78.75	OK
15803	2026-09-21 09:57	78.51	OK	15804	2026-09-21 09:58	81.28	OK
15805	2026-09-21 09:59	83.87	OK	15806	2026-09-21 10:00	79.02	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15807	2026-09-21 10:01	78.65	OK	15808	2026-09-21 10:02	77.61	OK
15809	2026-09-21 10:03	79.19	OK	15810	2026-09-21 10:04	78.47	OK
15811	2026-09-21 10:05	81.94	OK	15812	2026-09-21 10:06	80.04	OK
15813	2026-09-21 10:07	79.15	OK	15814	2026-09-21 10:08	81.33	OK
15815	2026-09-21 10:09	76.99	OK	15816	2026-09-21 10:10	80.02	OK
15817	2026-09-21 10:11	79.81	OK	15818	2026-09-21 10:12	79.83	OK
15819	2026-09-21 10:13	81.07	OK	15820	2026-09-21 10:14	79.22	OK
15821	2026-09-21 10:15	80.13	OK	15822	2026-09-21 10:16	80.59	OK
15823	2026-09-21 10:17	80.07	OK	15824	2026-09-21 10:18	79.39	OK
15825	2026-09-21 10:19	81.73	OK	15826	2026-09-21 10:20	78.50	OK
15827	2026-09-21 10:21	77.80	OK	15828	2026-09-21 10:22	78.86	OK
15829	2026-09-21 10:23	78.11	OK	15830	2026-09-21 10:24	81.84	OK
15831	2026-09-21 10:25	78.64	OK	15832	2026-09-21 10:26	82.14	OK
15833	2026-09-21 10:27	80.13	OK	15834	2026-09-21 10:28	80.94	OK
15835	2026-09-21 10:29	79.11	OK	15836	2026-09-21 10:30	79.14	OK
15837	2026-09-21 10:31	78.46	OK	15838	2026-09-21 10:32	79.16	OK
15839	2026-09-21 10:33	78.57	OK	15840	2026-09-21 10:34	80.52	OK
15841	2026-09-21 10:35	78.91	OK	15842	2026-09-21 10:36	80.33	OK
15843	2026-09-21 10:37	81.32	OK	15844	2026-09-21 10:38	78.19	OK
15845	2026-09-21 10:39	79.98	OK	15846	2026-09-21 10:40	78.07	OK
15847	2026-09-21 10:41	79.72	OK	15848	2026-09-21 10:42	81.37	OK
15849	2026-09-21 10:43	80.06	OK	15850	2026-09-21 10:44	78.20	OK
15851	2026-09-21 10:45	79.54	OK	15852	2026-09-21 10:46	79.17	OK
15853	2026-09-21 10:47	79.30	OK	15854	2026-09-21 10:48	80.47	OK
15855	2026-09-21 10:49	81.87	OK	15856	2026-09-21 10:50	79.60	OK
15857	2026-09-21 10:51	80.26	OK	15858	2026-09-21 10:52	80.23	OK
15859	2026-09-21 10:53	79.87	OK	15860	2026-09-21 10:54	81.15	OK
15861	2026-09-21 10:55	79.61	OK	15862	2026-09-21 10:56	80.75	OK
15863	2026-09-21 10:57	81.00	OK	15864	2026-09-21 10:58	80.74	OK
15865	2026-09-21 10:59	81.04	OK	15866	2026-09-21 11:00	82.06	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15867	2026-09-21 11:01	82.72	OK	15868	2026-09-21 11:02	83.17	OK
15869	2026-09-21 11:03	77.58	OK	15870	2026-09-21 11:04	80.87	OK
15871	2026-09-21 11:05	77.63	OK	15872	2026-09-21 11:06	80.93	OK
15873	2026-09-21 11:07	80.82	OK	15874	2026-09-21 11:08	78.81	OK
15875	2026-09-21 11:09	82.56	OK	15876	2026-09-21 11:10	77.39	OK
15877	2026-09-21 11:11	79.78	OK	15878	2026-09-21 11:12	82.24	OK
15879	2026-09-21 11:13	80.49	OK	15880	2026-09-21 11:14	83.13	OK
15881	2026-09-21 11:15	78.51	OK	15882	2026-09-21 11:16	80.29	OK
15883	2026-09-21 11:17	80.19	OK	15884	2026-09-21 11:18	79.76	OK
15885	2026-09-21 11:19	83.15	OK	15886	2026-09-21 11:20	79.78	OK
15887	2026-09-21 11:21	79.75	OK	15888	2026-09-21 11:22	79.51	OK
15889	2026-09-21 11:23	80.83	OK	15890	2026-09-21 11:24	82.01	OK
15891	2026-09-21 11:25	80.16	OK	15892	2026-09-21 11:26	79.55	OK
15893	2026-09-21 11:27	80.16	OK	15894	2026-09-21 11:28	78.39	OK
15895	2026-09-21 11:29	78.28	OK	15896	2026-09-21 11:30	82.08	OK
15897	2026-09-21 11:31	80.99	OK	15898	2026-09-21 11:32	79.82	OK
15899	2026-09-21 11:33	81.48	OK	15900	2026-09-21 11:34	77.91	OK
15901	2026-09-21 11:35	78.51	OK	15902	2026-09-21 11:36	79.42	OK
15903	2026-09-21 11:37	82.35	OK	15904	2026-09-21 11:38	81.83	OK
15905	2026-09-21 11:39	77.90	OK	15906	2026-09-21 11:40	81.04	OK
15907	2026-09-21 11:41	82.16	OK	15908	2026-09-21 11:42	80.97	OK
15909	2026-09-21 11:43	80.08	OK	15910	2026-09-21 11:44	83.51	OK
15911	2026-09-21 11:45	78.30	OK	15912	2026-09-21 11:46	81.02	OK
15913	2026-09-21 11:47	79.83	OK	15914	2026-09-21 11:48	79.09	OK
15915	2026-09-21 11:49	84.10	OK	15916	2026-09-21 11:50	82.55	OK
15917	2026-09-21 11:51	77.83	OK	15918	2026-09-21 11:52	79.18	OK
15919	2026-09-21 11:53	82.33	OK	15920	2026-09-21 11:54	83.11	OK
15921	2026-09-21 11:55	80.98	OK	15922	2026-09-21 11:56	80.97	OK
15923	2026-09-21 11:57	82.02	OK	15924	2026-09-21 11:58	79.20	OK
15925	2026-09-21 11:59	81.85	OK	15926	2026-09-21 12:00	82.89	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15927	2026-09-21 12:01	83.07	OK	15928	2026-09-21 12:02	80.31	OK
15929	2026-09-21 12:03	80.30	OK	15930	2026-09-21 12:04	78.76	OK
15931	2026-09-21 12:05	83.89	OK	15932	2026-09-21 12:06	81.58	OK
15933	2026-09-21 12:07	77.12	OK	15934	2026-09-21 12:08	78.85	OK
15935	2026-09-21 12:09	83.23	OK	15936	2026-09-21 12:10	81.27	OK
15937	2026-09-21 12:11	80.58	OK	15938	2026-09-21 12:12	84.23	OK
15939	2026-09-21 12:13	80.09	OK	15940	2026-09-21 12:14	80.60	OK
15941	2026-09-21 12:15	80.32	OK	15942	2026-09-21 12:16	79.95	OK
15943	2026-09-21 12:17	79.30	OK	15944	2026-09-21 12:18	82.99	OK
15945	2026-09-21 12:19	81.50	OK	15946	2026-09-21 12:20	78.41	OK
15947	2026-09-21 12:21	79.81	OK	15948	2026-09-21 12:22	80.74	OK
15949	2026-09-21 12:23	80.55	OK	15950	2026-09-21 12:24	80.24	OK
15951	2026-09-21 12:25	79.67	OK	15952	2026-09-21 12:26	80.33	OK
15953	2026-09-21 12:27	79.12	OK	15954	2026-09-21 12:28	78.15	OK
15955	2026-09-21 12:29	81.93	OK	15956	2026-09-21 12:30	80.04	OK
15957	2026-09-21 12:31	78.87	OK	15958	2026-09-21 12:32	81.89	OK
15959	2026-09-21 12:33	79.56	OK	15960	2026-09-21 12:34	80.00	OK
15961	2026-09-21 12:35	78.05	OK	15962	2026-09-21 12:36	81.93	OK
15963	2026-09-21 12:37	82.78	OK	15964	2026-09-21 12:38	81.45	OK
15965	2026-09-21 12:39	81.41	OK	15966	2026-09-21 12:40	81.62	OK
15967	2026-09-21 12:41	80.15	OK	15968	2026-09-21 12:42	81.81	OK
15969	2026-09-21 12:43	78.07	OK	15970	2026-09-21 12:44	82.90	OK
15971	2026-09-21 12:45	79.28	OK	15972	2026-09-21 12:46	81.54	OK
15973	2026-09-21 12:47	79.17	OK	15974	2026-09-21 12:48	82.46	OK
15975	2026-09-21 12:49	81.34	OK	15976	2026-09-21 12:50	78.84	OK
15977	2026-09-21 12:51	80.36	OK	15978	2026-09-21 12:52	81.90	OK
15979	2026-09-21 12:53	81.08	OK	15980	2026-09-21 12:54	79.03	OK
15981	2026-09-21 12:55	80.70	OK	15982	2026-09-21 12:56	80.23	OK
15983	2026-09-21 12:57	82.45	OK	15984	2026-09-21 12:58	79.79	OK
15985	2026-09-21 12:59	78.86	OK	15986	2026-09-21 13:00	81.05	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15987	2026-09-21 13:01	79.72	OK	15988	2026-09-21 13:02	80.69	OK
15989	2026-09-21 13:03	80.15	OK	15990	2026-09-21 13:04	78.10	OK
15991	2026-09-21 13:05	81.93	OK	15992	2026-09-21 13:06	81.87	OK
15993	2026-09-21 13:07	82.01	OK	15994	2026-09-21 13:08	80.45	OK
15995	2026-09-21 13:09	82.47	OK	15996	2026-09-21 13:10	80.70	OK
15997	2026-09-21 13:11	80.00	OK	15998	2026-09-21 13:12	80.91	OK
15999	2026-09-21 13:13	81.10	OK	16000	2026-09-21 13:14	78.97	OK
16001	2026-09-21 13:15	81.32	OK	16002	2026-09-21 13:16	82.72	OK
16003	2026-09-21 13:17	81.01	OK	16004	2026-09-21 13:18	78.09	OK
16005	2026-09-21 13:19	82.51	OK	16006	2026-09-21 13:20	78.90	OK
16007	2026-09-21 13:21	81.25	OK	16008	2026-09-21 13:22	79.75	OK
16009	2026-09-21 13:23	81.36	OK	16010	2026-09-21 13:24	79.96	OK
16011	2026-09-21 13:25	82.73	OK	16012	2026-09-21 13:26	81.85	OK
16013	2026-09-21 13:27	78.29	OK	16014	2026-09-21 13:28	81.63	OK
16015	2026-09-21 13:29	80.59	OK	16016	2026-09-21 13:30	79.85	OK
16017	2026-09-21 13:31	83.16	OK	16018	2026-09-21 13:32	78.95	OK
16019	2026-09-21 13:33	83.54	OK	16020	2026-09-21 13:34	77.53	OK
16021	2026-09-21 13:35	80.11	OK	16022	2026-09-21 13:36	83.07	OK
16023	2026-09-21 13:37	80.67	OK	16024	2026-09-21 13:38	78.74	OK
16025	2026-09-21 13:39	80.77	OK	16026	2026-09-21 13:40	81.64	OK
16027	2026-09-21 13:41	82.50	OK	16028	2026-09-21 13:42	81.61	OK
16029	2026-09-21 13:43	77.80	OK	16030	2026-09-21 13:44	79.94	OK
16031	2026-09-21 13:45	80.46	OK	16032	2026-09-21 13:46	82.18	OK
16033	2026-09-21 13:47	80.87	OK	16034	2026-09-21 13:48	76.73	OK
16035	2026-09-21 13:49	81.83	OK	16036	2026-09-21 13:50	82.22	OK
16037	2026-09-21 13:51	80.64	OK	16038	2026-09-21 13:52	81.10	OK
16039	2026-09-21 13:53	79.88	OK	16040	2026-09-21 13:54	78.71	OK
16041	2026-09-21 13:55	80.71	OK	16042	2026-09-21 13:56	80.09	OK
16043	2026-09-21 13:57	78.67	OK	16044	2026-09-21 13:58	77.22	OK
16045	2026-09-21 13:59	80.86	OK	16046	2026-09-21 14:00	80.28	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16047	2026-09-21 14:01	82.25	OK	16048	2026-09-21 14:02	80.04	OK
16049	2026-09-21 14:03	78.95	OK	16050	2026-09-21 14:04	80.38	OK
16051	2026-09-21 14:05	80.60	OK	16052	2026-09-21 14:06	79.89	OK
16053	2026-09-21 14:07	79.45	OK	16054	2026-09-21 14:08	81.29	OK
16055	2026-09-21 14:09	82.87	OK	16056	2026-09-21 14:10	81.36	OK
16057	2026-09-21 14:11	81.26	OK	16058	2026-09-21 14:12	79.44	OK
16059	2026-09-21 14:13	79.33	OK	16060	2026-09-21 14:14	79.64	OK
16061	2026-09-21 14:15	81.66	OK	16062	2026-09-21 14:16	79.49	OK
16063	2026-09-21 14:17	80.27	OK	16064	2026-09-21 14:18	78.97	OK
16065	2026-09-21 14:19	82.07	OK	16066	2026-09-21 14:20	81.97	OK
16067	2026-09-21 14:21	78.40	OK	16068	2026-09-21 14:22	75.96	OK
16069	2026-09-21 14:23	78.70	OK	16070	2026-09-21 14:24	81.26	OK
16071	2026-09-21 14:25	81.18	OK	16072	2026-09-21 14:26	77.57	OK
16073	2026-09-21 14:27	79.61	OK	16074	2026-09-21 14:28	80.84	OK
16075	2026-09-21 14:29	83.92	OK	16076	2026-09-21 14:30	80.99	OK
16077	2026-09-21 14:31	79.06	OK	16078	2026-09-21 14:32	82.15	OK
16079	2026-09-21 14:33	81.47	OK	16080	2026-09-21 14:34	79.95	OK
16081	2026-09-21 14:35	81.59	OK	16082	2026-09-21 14:36	83.38	OK
16083	2026-09-21 14:37	80.45	OK	16084	2026-09-21 14:38	79.39	OK
16085	2026-09-21 14:39	79.13	OK	16086	2026-09-21 14:40	82.86	OK
16087	2026-09-21 14:41	81.05	OK	16088	2026-09-21 14:42	80.76	OK
16089	2026-09-21 14:43	81.03	OK	16090	2026-09-21 14:44	80.86	OK
16091	2026-09-21 14:45	80.64	OK	16092	2026-09-21 14:46	77.40	OK
16093	2026-09-21 14:47	80.83	OK	16094	2026-09-21 14:48	81.11	OK
16095	2026-09-21 14:49	82.97	OK	16096	2026-09-21 14:50	80.11	OK
16097	2026-09-21 14:51	78.08	OK	16098	2026-09-21 14:52	79.10	OK
16099	2026-09-21 14:53	83.17	OK	16100	2026-09-21 14:54	80.90	OK
16101	2026-09-21 14:55	79.62	OK	16102	2026-09-21 14:56	80.25	OK
16103	2026-09-21 14:57	81.97	OK	16104	2026-09-21 14:58	78.62	OK
16105	2026-09-21 14:59	81.82	OK	16106	2026-09-21 15:00	79.46	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16107	2026-09-21 15:01	80.82	OK	16108	2026-09-21 15:02	80.37	OK
16109	2026-09-21 15:03	78.87	OK	16110	2026-09-21 15:04	81.18	OK
16111	2026-09-21 15:05	79.36	OK	16112	2026-09-21 15:06	80.50	OK
16113	2026-09-21 15:07	78.92	OK	16114	2026-09-21 15:08	78.87	OK
16115	2026-09-21 15:09	79.86	OK	16116	2026-09-21 15:10	82.30	OK
16117	2026-09-21 15:11	81.52	OK	16118	2026-09-21 15:12	79.85	OK
16119	2026-09-21 15:13	77.99	OK	16120	2026-09-21 15:14	80.96	OK
16121	2026-09-21 15:15	79.39	OK	16122	2026-09-21 15:16	81.07	OK
16123	2026-09-21 15:17	80.72	OK	16124	2026-09-21 15:18	79.44	OK
16125	2026-09-21 15:19	79.32	OK	16126	2026-09-21 15:20	84.25	OK
16127	2026-09-21 15:21	81.04	OK	16128	2026-09-21 15:22	82.81	OK
16129	2026-09-21 15:23	78.84	OK	16130	2026-09-21 15:24	81.38	OK
16131	2026-09-21 15:25	78.70	OK	16132	2026-09-21 15:26	76.97	OK
16133	2026-09-21 15:27	79.14	OK	16134	2026-09-21 15:28	77.15	OK
16135	2026-09-21 15:29	77.46	OK	16136	2026-09-21 15:30	80.46	OK
16137	2026-09-21 15:31	77.27	OK	16138	2026-09-21 15:32	80.17	OK
16139	2026-09-21 15:33	80.09	OK	16140	2026-09-21 15:34	78.87	OK
16141	2026-09-21 15:35	80.07	OK	16142	2026-09-21 15:36	78.25	OK
16143	2026-09-21 15:37	79.67	OK	16144	2026-09-21 15:38	77.75	OK
16145	2026-09-21 15:39	79.76	OK	16146	2026-09-21 15:40	77.45	OK
16147	2026-09-21 15:41	77.49	OK	16148	2026-09-21 15:42	79.24	OK
16149	2026-09-21 15:43	77.54	OK	16150	2026-09-21 15:44	79.38	OK
16151	2026-09-21 15:45	80.58	OK	16152	2026-09-21 15:46	79.58	OK
16153	2026-09-21 15:47	80.13	OK	16154	2026-09-21 15:48	78.76	OK
16155	2026-09-21 15:49	81.83	OK	16156	2026-09-21 15:50	79.83	OK
16157	2026-09-21 15:51	77.80	OK	16158	2026-09-21 15:52	78.79	OK
16159	2026-09-21 15:53	77.40	OK	16160	2026-09-21 15:54	79.36	OK
16161	2026-09-21 15:55	79.92	OK	16162	2026-09-21 15:56	78.57	OK
16163	2026-09-21 15:57	78.15	OK	16164	2026-09-21 15:58	77.62	OK
16165	2026-09-21 15:59	80.48	OK	16166	2026-09-21 16:00	81.89	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16167	2026-09-21 16:01	80.09	OK	16168	2026-09-21 16:02	80.72	OK
16169	2026-09-21 16:03	78.32	OK	16170	2026-09-21 16:04	79.51	OK
16171	2026-09-21 16:05	77.96	OK	16172	2026-09-21 16:06	76.83	OK
16173	2026-09-21 16:07	76.62	OK	16174	2026-09-21 16:08	77.64	OK
16175	2026-09-21 16:09	79.60	OK	16176	2026-09-21 16:10	80.45	OK
16177	2026-09-21 16:11	79.44	OK	16178	2026-09-21 16:12	79.02	OK
16179	2026-09-21 16:13	79.91	OK	16180	2026-09-21 16:14	77.98	OK
16181	2026-09-21 16:15	76.50	OK	16182	2026-09-21 16:16	80.54	OK
16183	2026-09-21 16:17	77.19	OK	16184	2026-09-21 16:18	77.96	OK
16185	2026-09-21 16:19	80.65	OK	16186	2026-09-21 16:20	81.56	OK
16187	2026-09-21 16:21	79.74	OK	16188	2026-09-21 16:22	78.49	OK
16189	2026-09-21 16:23	79.15	OK	16190	2026-09-21 16:24	77.35	OK
16191	2026-09-21 16:25	77.77	OK	16192	2026-09-21 16:26	80.40	OK
16193	2026-09-21 16:27	77.63	OK	16194	2026-09-21 16:28	77.96	OK
16195	2026-09-21 16:29	77.22	OK	16196	2026-09-21 16:30	77.69	OK
16197	2026-09-21 16:31	79.99	OK	16198	2026-09-21 16:32	77.94	OK
16199	2026-09-21 16:33	75.38	OK	16200	2026-09-21 16:34	80.05	OK
16201	2026-09-21 16:35	81.30	OK	16202	2026-09-21 16:36	76.49	OK
16203	2026-09-21 16:37	77.26	OK	16204	2026-09-21 16:38	78.59	OK
16205	2026-09-21 16:39	75.51	OK	16206	2026-09-21 16:40	77.22	OK
16207	2026-09-21 16:41	80.71	OK	16208	2026-09-21 16:42	76.91	OK
16209	2026-09-21 16:43	77.90	OK	16210	2026-09-21 16:44	80.91	OK
16211	2026-09-21 16:45	76.72	OK	16212	2026-09-21 16:46	77.44	OK
16213	2026-09-21 16:47	78.63	OK	16214	2026-09-21 16:48	80.58	OK
16215	2026-09-21 16:49	80.28	OK	16216	2026-09-21 16:50	77.69	OK
16217	2026-09-21 16:51	80.66	OK	16218	2026-09-21 16:52	80.38	OK
16219	2026-09-21 16:53	80.48	OK	16220	2026-09-21 16:54	75.97	OK
16221	2026-09-21 16:55	77.34	OK	16222	2026-09-21 16:56	78.32	OK
16223	2026-09-21 16:57	79.19	OK	16224	2026-09-21 16:58	79.38	OK
16225	2026-09-21 16:59	80.91	OK	16226	2026-09-21 17:00	76.84	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16227	2026-09-21 17:01	74.87	OK	16228	2026-09-21 17:02	77.20	OK
16229	2026-09-21 17:03	78.12	OK	16230	2026-09-21 17:04	79.13	OK
16231	2026-09-21 17:05	82.09	OK	16232	2026-09-21 17:06	78.46	OK
16233	2026-09-21 17:07	76.04	OK	16234	2026-09-21 17:08	76.93	OK
16235	2026-09-21 17:09	77.98	OK	16236	2026-09-21 17:10	76.23	OK
16237	2026-09-21 17:11	77.49	OK	16238	2026-09-21 17:12	77.51	OK
16239	2026-09-21 17:13	76.35	OK	16240	2026-09-21 17:14	75.70	OK
16241	2026-09-21 17:15	76.57	OK	16242	2026-09-21 17:16	78.95	OK
16243	2026-09-21 17:17	77.00	OK	16244	2026-09-21 17:18	75.38	OK
16245	2026-09-21 17:19	80.94	OK	16246	2026-09-21 17:20	77.76	OK
16247	2026-09-21 17:21	78.35	OK	16248	2026-09-21 17:22	78.28	OK
16249	2026-09-21 17:23	79.08	OK	16250	2026-09-21 17:24	78.98	OK
16251	2026-09-21 17:25	77.23	OK	16252	2026-09-21 17:26	76.51	OK
16253	2026-09-21 17:27	76.04	OK	16254	2026-09-21 17:28	78.80	OK
16255	2026-09-21 17:29	77.77	OK	16256	2026-09-21 17:30	75.57	OK
16257	2026-09-21 17:31	74.62	OK	16258	2026-09-21 17:32	78.12	OK
16259	2026-09-21 17:33	76.93	OK	16260	2026-09-21 17:34	75.26	OK
16261	2026-09-21 17:35	74.13	OK	16262	2026-09-21 17:36	75.33	OK
16263	2026-09-21 17:37	79.90	OK	16264	2026-09-21 17:38	78.47	OK
16265	2026-09-21 17:39	78.19	OK	16266	2026-09-21 17:40	78.20	OK
16267	2026-09-21 17:41	75.43	OK	16268	2026-09-21 17:42	78.92	OK
16269	2026-09-21 17:43	75.70	OK	16270	2026-09-21 17:44	78.68	OK
16271	2026-09-21 17:45	79.16	OK	16272	2026-09-21 17:46	75.53	OK
16273	2026-09-21 17:47	75.60	OK	16274	2026-09-21 17:48	78.75	OK
16275	2026-09-21 17:49	77.25	OK	16276	2026-09-21 17:50	73.04	OK
16277	2026-09-21 17:51	78.43	OK	16278	2026-09-21 17:52	74.92	OK
16279	2026-09-21 17:53	73.24	OK	16280	2026-09-21 17:54	73.36	OK
16281	2026-09-21 17:55	73.47	OK	16282	2026-09-21 17:56	79.35	OK
16283	2026-09-21 17:57	76.92	OK	16284	2026-09-21 17:58	75.70	OK
16285	2026-09-21 17:59	74.74	OK	16286	2026-09-21 18:00	74.71	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16287	2026-09-21 18:01	77.39	OK	16288	2026-09-21 18:02	76.93	OK
16289	2026-09-21 18:03	74.78	OK	16290	2026-09-21 18:04	76.94	OK
16291	2026-09-21 18:05	76.98	OK	16292	2026-09-21 18:06	74.89	OK
16293	2026-09-21 18:07	74.70	OK	16294	2026-09-21 18:08	77.33	OK
16295	2026-09-21 18:09	77.35	OK	16296	2026-09-21 18:10	77.63	OK
16297	2026-09-21 18:11	74.42	OK	16298	2026-09-21 18:12	78.12	OK
16299	2026-09-21 18:13	77.16	OK	16300	2026-09-21 18:14	78.08	OK
16301	2026-09-21 18:15	78.02	OK	16302	2026-09-21 18:16	74.38	OK
16303	2026-09-21 18:17	75.01	OK	16304	2026-09-21 18:18	73.30	OK
16305	2026-09-21 18:19	77.72	OK	16306	2026-09-21 18:20	75.20	OK
16307	2026-09-21 18:21	74.87	OK	16308	2026-09-21 18:22	75.73	OK
16309	2026-09-21 18:23	77.74	OK	16310	2026-09-21 18:24	76.91	OK
16311	2026-09-21 18:25	75.02	OK	16312	2026-09-21 18:26	78.27	OK
16313	2026-09-21 18:27	76.96	OK	16314	2026-09-21 18:28	74.79	OK
16315	2026-09-21 18:29	74.58	OK	16316	2026-09-21 18:30	76.15	OK
16317	2026-09-21 18:31	78.37	OK	16318	2026-09-21 18:32	74.94	OK
16319	2026-09-21 18:33	73.96	OK	16320	2026-09-21 18:34	75.75	OK
16321	2026-09-21 18:35	74.49	OK	16322	2026-09-21 18:36	76.69	OK
16323	2026-09-21 18:37	74.20	OK	16324	2026-09-21 18:38	74.13	OK
16325	2026-09-21 18:39	74.60	OK	16326	2026-09-21 18:40	76.37	OK
16327	2026-09-21 18:41	73.62	OK	16328	2026-09-21 18:42	76.95	OK
16329	2026-09-21 18:43	77.82	OK	16330	2026-09-21 18:44	75.53	OK
16331	2026-09-21 18:45	74.46	OK	16332	2026-09-21 18:46	76.50	OK
16333	2026-09-21 18:47	75.28	OK	16334	2026-09-21 18:48	75.78	OK
16335	2026-09-21 18:49	75.58	OK	16336	2026-09-21 18:50	75.86	OK
16337	2026-09-21 18:51	72.76	OK	16338	2026-09-21 18:52	76.56	OK
16339	2026-09-21 18:53	74.49	OK	16340	2026-09-21 18:54	77.69	OK
16341	2026-09-21 18:55	74.49	OK	16342	2026-09-21 18:56	76.24	OK
16343	2026-09-21 18:57	75.70	OK	16344	2026-09-21 18:58	76.80	OK
16345	2026-09-21 18:59	74.10	OK	16346	2026-09-21 19:00	73.54	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16347	2026-09-21 19:01	75.22	OK	16348	2026-09-21 19:02	74.28	OK
16349	2026-09-21 19:03	72.52	OK	16350	2026-09-21 19:04	75.46	OK
16351	2026-09-21 19:05	75.42	OK	16352	2026-09-21 19:06	77.22	OK
16353	2026-09-21 19:07	74.19	OK	16354	2026-09-21 19:08	72.31	OK
16355	2026-09-21 19:09	74.11	OK	16356	2026-09-21 19:10	73.73	OK
16357	2026-09-21 19:11	75.95	OK	16358	2026-09-21 19:12	76.79	OK
16359	2026-09-21 19:13	75.39	OK	16360	2026-09-21 19:14	75.72	OK
16361	2026-09-21 19:15	75.06	OK	16362	2026-09-21 19:16	75.45	OK
16363	2026-09-21 19:17	77.06	OK	16364	2026-09-21 19:18	75.10	OK
16365	2026-09-21 19:19	73.74	OK	16366	2026-09-21 19:20	77.19	OK
16367	2026-09-21 19:21	74.42	OK	16368	2026-09-21 19:22	74.51	OK
16369	2026-09-21 19:23	75.01	OK	16370	2026-09-21 19:24	75.10	OK
16371	2026-09-21 19:25	76.09	OK	16372	2026-09-21 19:26	77.54	OK
16373	2026-09-21 19:27	74.06	OK	16374	2026-09-21 19:28	74.55	OK
16375	2026-09-21 19:29	73.27	OK	16376	2026-09-21 19:30	72.75	OK
16377	2026-09-21 19:31	74.96	OK	16378	2026-09-21 19:32	74.99	OK
16379	2026-09-21 19:33	74.59	OK	16380	2026-09-21 19:34	77.26	OK
16381	2026-09-21 19:35	74.16	OK	16382	2026-09-21 19:36	75.27	OK
16383	2026-09-21 19:37	75.89	OK	16384	2026-09-21 19:38	72.62	OK
16385	2026-09-21 19:39	75.14	OK	16386	2026-09-21 19:40	72.02	OK
16387	2026-09-21 19:41	74.71	OK	16388	2026-09-21 19:42	75.76	OK
16389	2026-09-21 19:43	72.82	OK	16390	2026-09-21 19:44	74.48	OK
16391	2026-09-21 19:45	74.27	OK	16392	2026-09-21 19:46	74.55	OK
16393	2026-09-21 19:47	74.31	OK	16394	2026-09-21 19:48	71.98	OK
16395	2026-09-21 19:49	73.78	OK	16396	2026-09-21 19:50	72.87	OK
16397	2026-09-21 19:51	72.62	OK	16398	2026-09-21 19:52	70.84	OK
16399	2026-09-21 19:53	71.20	OK	16400	2026-09-21 19:54	71.80	OK
16401	2026-09-21 19:55	74.64	OK	16402	2026-09-21 19:56	73.44	OK
16403	2026-09-21 19:57	75.36	OK	16404	2026-09-21 19:58	73.40	OK
16405	2026-09-21 19:59	73.64	OK	16406	2026-09-21 20:00	72.54	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16407	2026-09-21 20:01	73.49	OK	16408	2026-09-21 20:02	75.02	OK
16409	2026-09-21 20:03	73.43	OK	16410	2026-09-21 20:04	76.55	OK
16411	2026-09-21 20:05	73.74	OK	16412	2026-09-21 20:06	72.77	OK
16413	2026-09-21 20:07	73.81	OK	16414	2026-09-21 20:08	73.83	OK
16415	2026-09-21 20:09	76.31	OK	16416	2026-09-21 20:10	73.61	OK
16417	2026-09-21 20:11	73.01	OK	16418	2026-09-21 20:12	73.69	OK
16419	2026-09-21 20:13	74.97	OK	16420	2026-09-21 20:14	74.83	OK
16421	2026-09-21 20:15	73.19	OK	16422	2026-09-21 20:16	75.58	OK
16423	2026-09-21 20:17	71.16	OK	16424	2026-09-21 20:18	73.44	OK
16425	2026-09-21 20:19	72.84	OK	16426	2026-09-21 20:20	74.36	OK
16427	2026-09-21 20:21	71.46	OK	16428	2026-09-21 20:22	69.95	OK
16429	2026-09-21 20:23	71.22	OK	16430	2026-09-21 20:24	72.14	OK
16431	2026-09-21 20:25	71.54	OK	16432	2026-09-21 20:26	72.48	OK
16433	2026-09-21 20:27	73.04	OK	16434	2026-09-21 20:28	73.45	OK
16435	2026-09-21 20:29	70.08	OK	16436	2026-09-21 20:30	73.51	OK
16437	2026-09-21 20:31	71.27	OK	16438	2026-09-21 20:32	71.09	OK
16439	2026-09-21 20:33	73.09	OK	16440	2026-09-21 20:34	73.57	OK
16441	2026-09-21 20:35	72.45	OK	16442	2026-09-21 20:36	73.62	OK
16443	2026-09-21 20:37	74.48	OK	16444	2026-09-21 20:38	73.51	OK
16445	2026-09-21 20:39	72.67	OK	16446	2026-09-21 20:40	72.16	OK
16447	2026-09-21 20:41	72.99	OK	16448	2026-09-21 20:42	72.87	OK
16449	2026-09-21 20:43	71.90	OK	16450	2026-09-21 20:44	71.34	OK
16451	2026-09-21 20:45	73.78	OK	16452	2026-09-21 20:46	72.45	OK
16453	2026-09-21 20:47	70.14	OK	16454	2026-09-21 20:48	73.78	OK
16455	2026-09-21 20:49	70.82	OK	16456	2026-09-21 20:50	74.59	OK
16457	2026-09-21 20:51	72.07	OK	16458	2026-09-21 20:52	73.63	OK
16459	2026-09-21 20:53	73.83	OK	16460	2026-09-21 20:54	74.75	OK
16461	2026-09-21 20:55	71.10	OK	16462	2026-09-21 20:56	72.57	OK
16463	2026-09-21 20:57	72.06	OK	16464	2026-09-21 20:58	74.10	OK
16465	2026-09-21 20:59	73.00	OK	16466	2026-09-21 21:00	72.39	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16467	2026-09-21 21:01	72.83	OK	16468	2026-09-21 21:02	71.91	OK
16469	2026-09-21 21:03	70.71	OK	16470	2026-09-21 21:04	74.03	OK
16471	2026-09-21 21:05	72.72	OK	16472	2026-09-21 21:06	72.35	OK
16473	2026-09-21 21:07	72.46	OK	16474	2026-09-21 21:08	71.64	OK
16475	2026-09-21 21:09	72.18	OK	16476	2026-09-21 21:10	73.22	OK
16477	2026-09-21 21:11	73.21	OK	16478	2026-09-21 21:12	71.33	OK
16479	2026-09-21 21:13	72.33	OK	16480	2026-09-21 21:14	73.98	OK
16481	2026-09-21 21:15	70.89	OK	16482	2026-09-21 21:16	70.58	OK
16483	2026-09-21 21:17	69.64	OK	16484	2026-09-21 21:18	71.89	OK
16485	2026-09-21 21:19	71.58	OK	16486	2026-09-21 21:20	71.41	OK
16487	2026-09-21 21:21	74.19	OK	16488	2026-09-21 21:22	73.14	OK
16489	2026-09-21 21:23	72.06	OK	16490	2026-09-21 21:24	71.33	OK
16491	2026-09-21 21:25	71.49	OK	16492	2026-09-21 21:26	70.78	OK
16493	2026-09-21 21:27	71.38	OK	16494	2026-09-21 21:28	70.92	OK
16495	2026-09-21 21:29	72.17	OK	16496	2026-09-21 21:30	72.76	OK
16497	2026-09-21 21:31	71.81	OK	16498	2026-09-21 21:32	71.70	OK
16499	2026-09-21 21:33	70.17	OK	16500	2026-09-21 21:34	74.11	OK
16501	2026-09-21 21:35	68.92	OK	16502	2026-09-21 21:36	70.51	OK
16503	2026-09-21 21:37	72.39	OK	16504	2026-09-21 21:38	70.85	OK
16505	2026-09-21 21:39	75.13	OK	16506	2026-09-21 21:40	71.60	OK
16507	2026-09-21 21:41	71.64	OK	16508	2026-09-21 21:42	70.92	OK
16509	2026-09-21 21:43	72.47	OK	16510	2026-09-21 21:44	73.48	OK
16511	2026-09-21 21:45	71.63	OK	16512	2026-09-21 21:46	71.57	OK
16513	2026-09-21 21:47	73.44	OK	16514	2026-09-21 21:48	69.59	OK
16515	2026-09-21 21:49	74.38	OK	16516	2026-09-21 21:50	69.99	OK
16517	2026-09-21 21:51	68.65	OK	16518	2026-09-21 21:52	70.79	OK
16519	2026-09-21 21:53	70.99	OK	16520	2026-09-21 21:54	70.95	OK
16521	2026-09-21 21:55	69.60	OK	16522	2026-09-21 21:56	71.33	OK
16523	2026-09-21 21:57	73.15	OK	16524	2026-09-21 21:58	70.75	OK
16525	2026-09-21 21:59	71.87	OK	16526	2026-09-21 22:00	69.76	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16527	2026-09-21 22:01	69.60	OK	16528	2026-09-21 22:02	70.44	OK
16529	2026-09-21 22:03	74.53	OK	16530	2026-09-21 22:04	68.93	OK
16531	2026-09-21 22:05	69.43	OK	16532	2026-09-21 22:06	66.84	OK
16533	2026-09-21 22:07	72.42	OK	16534	2026-09-21 22:08	70.20	OK
16535	2026-09-21 22:09	69.77	OK	16536	2026-09-21 22:10	73.08	OK
16537	2026-09-21 22:11	72.91	OK	16538	2026-09-21 22:12	70.54	OK
16539	2026-09-21 22:13	72.47	OK	16540	2026-09-21 22:14	71.80	OK
16541	2026-09-21 22:15	72.29	OK	16542	2026-09-21 22:16	73.69	OK
16543	2026-09-21 22:17	72.02	OK	16544	2026-09-21 22:18	69.13	OK
16545	2026-09-21 22:19	67.53	OK	16546	2026-09-21 22:20	69.95	OK
16547	2026-09-21 22:21	72.94	OK	16548	2026-09-21 22:22	68.68	OK
16549	2026-09-21 22:23	69.66	OK	16550	2026-09-21 22:24	68.32	OK
16551	2026-09-21 22:25	69.55	OK	16552	2026-09-21 22:26	67.37	OK
16553	2026-09-21 22:27	68.52	OK	16554	2026-09-21 22:28	70.73	OK
16555	2026-09-21 22:29	68.04	OK	16556	2026-09-21 22:30	72.32	OK
16557	2026-09-21 22:31	74.32	OK	16558	2026-09-21 22:32	71.10	OK
16559	2026-09-21 22:33	67.84	OK	16560	2026-09-21 22:34	69.14	OK
16561	2026-09-21 22:35	70.82	OK	16562	2026-09-21 22:36	70.19	OK
16563	2026-09-21 22:37	72.02	OK	16564	2026-09-21 22:38	69.82	OK
16565	2026-09-21 22:39	68.42	OK	16566	2026-09-21 22:40	71.61	OK
16567	2026-09-21 22:41	70.01	OK	16568	2026-09-21 22:42	67.03	OK
16569	2026-09-21 22:43	72.88	OK	16570	2026-09-21 22:44	69.45	OK
16571	2026-09-21 22:45	71.74	OK	16572	2026-09-21 22:46	71.42	OK
16573	2026-09-21 22:47	73.26	OK	16574	2026-09-21 22:48	72.78	OK
16575	2026-09-21 22:49	69.60	OK	16576	2026-09-21 22:50	69.36	OK
16577	2026-09-21 22:51	72.91	OK	16578	2026-09-21 22:52	71.52	OK
16579	2026-09-21 22:53	71.93	OK	16580	2026-09-21 22:54	70.19	OK
16581	2026-09-21 22:55	69.90	OK	16582	2026-09-21 22:56	69.67	OK
16583	2026-09-21 22:57	72.99	OK	16584	2026-09-21 22:58	67.18	OK
16585	2026-09-21 22:59	70.12	OK	16586	2026-09-21 23:00	68.89	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16587	2026-09-21 23:01	71.20	OK	16588	2026-09-21 23:02	65.76	OK
16589	2026-09-21 23:03	72.07	OK	16590	2026-09-21 23:04	70.23	OK
16591	2026-09-21 23:05	71.53	OK	16592	2026-09-21 23:06	71.39	OK
16593	2026-09-21 23:07	70.45	OK	16594	2026-09-21 23:08	71.95	OK
16595	2026-09-21 23:09	72.73	OK	16596	2026-09-21 23:10	72.10	OK
16597	2026-09-21 23:11	70.48	OK	16598	2026-09-21 23:12	67.45	OK
16599	2026-09-21 23:13	70.58	OK	16600	2026-09-21 23:14	69.32	OK
16601	2026-09-21 23:15	71.68	OK	16602	2026-09-21 23:16	68.77	OK
16603	2026-09-21 23:17	68.46	OK	16604	2026-09-21 23:18	70.57	OK
16605	2026-09-21 23:19	72.02	OK	16606	2026-09-21 23:20	70.33	OK
16607	2026-09-21 23:21	68.65	OK	16608	2026-09-21 23:22	68.70	OK
16609	2026-09-21 23:23	68.55	OK	16610	2026-09-21 23:24	69.46	OK
16611	2026-09-21 23:25	69.07	OK	16612	2026-09-21 23:26	69.09	OK
16613	2026-09-21 23:27	71.16	OK	16614	2026-09-21 23:28	68.61	OK
16615	2026-09-21 23:29	67.78	OK	16616	2026-09-21 23:30	69.89	OK
16617	2026-09-21 23:31	70.84	OK	16618	2026-09-21 23:32	70.86	OK
16619	2026-09-21 23:33	69.00	OK	16620	2026-09-21 23:34	70.77	OK
16621	2026-09-21 23:35	68.65	OK	16622	2026-09-21 23:36	68.37	OK
16623	2026-09-21 23:37	69.61	OK	16624	2026-09-21 23:38	70.71	OK
16625	2026-09-21 23:39	70.76	OK	16626	2026-09-21 23:40	69.17	OK
16627	2026-09-21 23:41	71.68	OK	16628	2026-09-21 23:42	70.92	OK
16629	2026-09-21 23:43	68.85	OK	16630	2026-09-21 23:44	68.14	OK
16631	2026-09-21 23:45	71.60	OK	16632	2026-09-21 23:46	69.09	OK
16633	2026-09-21 23:47	66.28	OK	16634	2026-09-21 23:48	73.28	OK
16635	2026-09-21 23:49	70.48	OK	16636	2026-09-21 23:50	72.10	OK
16637	2026-09-21 23:51	68.71	OK	16638	2026-09-21 23:52	71.95	OK
16639	2026-09-21 23:53	70.36	OK	16640	2026-09-21 23:54	70.47	OK
16641	2026-09-21 23:55	68.64	OK	16642	2026-09-21 23:56	70.10	OK
16643	2026-09-21 23:57	68.83	OK	16644	2026-09-21 23:58	69.12	OK
16645	2026-09-21 23:59	67.56	OK	16646	2026-09-22 00:00	69.23	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16647	2026-09-22 00:01	68.12	OK	16648	2026-09-22 00:02	67.39	OK
16649	2026-09-22 00:03	70.03	OK	16650	2026-09-22 00:04	67.87	OK
16651	2026-09-22 00:05	68.69	OK	16652	2026-09-22 00:06	70.67	OK
16653	2026-09-22 00:07	66.87	OK	16654	2026-09-22 00:08	70.24	OK
16655	2026-09-22 00:09	70.53	OK	16656	2026-09-22 00:10	71.43	OK
16657	2026-09-22 00:11	70.70	OK	16658	2026-09-22 00:12	69.27	OK
16659	2026-09-22 00:13	67.34	OK	16660	2026-09-22 00:14	70.81	OK
16661	2026-09-22 00:15	70.24	OK	16662	2026-09-22 00:16	66.19	OK
16663	2026-09-22 00:17	67.20	OK	16664	2026-09-22 00:18	67.90	OK
16665	2026-09-22 00:19	70.37	OK	16666	2026-09-22 00:20	69.95	OK
16667	2026-09-22 00:21	70.26	OK	16668	2026-09-22 00:22	70.88	OK
16669	2026-09-22 00:23	68.77	OK	16670	2026-09-22 00:24	69.28	OK
16671	2026-09-22 00:25	67.22	OK	16672	2026-09-22 00:26	67.11	OK
16673	2026-09-22 00:27	69.61	OK	16674	2026-09-22 00:28	69.31	OK
16675	2026-09-22 00:29	70.76	OK	16676	2026-09-22 00:30	68.06	OK
16677	2026-09-22 00:31	69.88	OK	16678	2026-09-22 00:32	70.25	OK
16679	2026-09-22 00:33	70.99	OK	16680	2026-09-22 00:34	70.25	OK
16681	2026-09-22 00:35	71.39	OK	16682	2026-09-22 00:36	69.02	OK
16683	2026-09-22 00:37	70.66	OK	16684	2026-09-22 00:38	71.09	OK
16685	2026-09-22 00:39	71.32	OK	16686	2026-09-22 00:40	68.65	OK
16687	2026-09-22 00:41	71.08	OK	16688	2026-09-22 00:42	69.37	OK
16689	2026-09-22 00:43	70.81	OK	16690	2026-09-22 00:44	69.32	OK
16691	2026-09-22 00:45	71.41	OK	16692	2026-09-22 00:46	68.19	OK
16693	2026-09-22 00:47	71.17	OK	16694	2026-09-22 00:48	68.58	OK
16695	2026-09-22 00:49	69.52	OK	16696	2026-09-22 00:50	68.30	OK
16697	2026-09-22 00:51	71.76	OK	16698	2026-09-22 00:52	66.76	OK
16699	2026-09-22 00:53	69.79	OK	16700	2026-09-22 00:54	67.50	OK
16701	2026-09-22 00:55	69.81	OK	16702	2026-09-22 00:56	68.63	OK
16703	2026-09-22 00:57	69.12	OK	16704	2026-09-22 00:58	69.15	OK
16705	2026-09-22 00:59	68.68	OK	16706	2026-09-22 01:00	67.09	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16707	2026-09-22 01:01	67.22	OK	16708	2026-09-22 01:02	70.50	OK
16709	2026-09-22 01:03	69.76	OK	16710	2026-09-22 01:04	70.78	OK
16711	2026-09-22 01:05	68.76	OK	16712	2026-09-22 01:06	67.94	OK
16713	2026-09-22 01:07	68.96	OK	16714	2026-09-22 01:08	69.60	OK
16715	2026-09-22 01:09	70.47	OK	16716	2026-09-22 01:10	70.10	OK
16717	2026-09-22 01:11	71.54	OK	16718	2026-09-22 01:12	66.70	OK
16719	2026-09-22 01:13	70.85	OK	16720	2026-09-22 01:14	67.57	OK
16721	2026-09-22 01:15	67.82	OK	16722	2026-09-22 01:16	69.82	OK
16723	2026-09-22 01:17	66.88	OK	16724	2026-09-22 01:18	68.58	OK
16725	2026-09-22 01:19	73.11	OK	16726	2026-09-22 01:20	66.29	OK
16727	2026-09-22 01:21	68.37	OK	16728	2026-09-22 01:22	71.76	OK
16729	2026-09-22 01:23	71.63	OK	16730	2026-09-22 01:24	69.16	OK
16731	2026-09-22 01:25	69.02	OK	16732	2026-09-22 01:26	72.50	OK
16733	2026-09-22 01:27	70.05	OK	16734	2026-09-22 01:28	73.60	OK
16735	2026-09-22 01:29	68.33	OK	16736	2026-09-22 01:30	68.70	OK
16737	2026-09-22 01:31	68.58	OK	16738	2026-09-22 01:32	71.99	OK
16739	2026-09-22 01:33	70.96	OK	16740	2026-09-22 01:34	73.38	OK
16741	2026-09-22 01:35	68.26	OK	16742	2026-09-22 01:36	65.75	OK
16743	2026-09-22 01:37	70.88	OK	16744	2026-09-22 01:38	71.49	OK
16745	2026-09-22 01:39	70.66	OK	16746	2026-09-22 01:40	67.68	OK
16747	2026-09-22 01:41	69.46	OK	16748	2026-09-22 01:42	68.02	OK
16749	2026-09-22 01:43	69.84	OK	16750	2026-09-22 01:44	70.90	OK
16751	2026-09-22 01:45	69.83	OK	16752	2026-09-22 01:46	72.03	OK
16753	2026-09-22 01:47	68.91	OK	16754	2026-09-22 01:48	69.68	OK
16755	2026-09-22 01:49	68.92	OK	16756	2026-09-22 01:50	71.26	OK
16757	2026-09-22 01:51	69.75	OK	16758	2026-09-22 01:52	72.82	OK
16759	2026-09-22 01:53	70.63	OK	16760	2026-09-22 01:54	69.15	OK
16761	2026-09-22 01:55	71.88	OK	16762	2026-09-22 01:56	69.90	OK
16763	2026-09-22 01:57	68.71	OK	16764	2026-09-22 01:58	70.06	OK
16765	2026-09-22 01:59	70.34	OK	16766	2026-09-22 02:00	69.36	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16767	2026-09-22 02:01	70.36	OK	16768	2026-09-22 02:02	72.67	OK
16769	2026-09-22 02:03	68.52	OK	16770	2026-09-22 02:04	68.11	OK
16771	2026-09-22 02:05	69.95	OK	16772	2026-09-22 02:06	68.66	OK
16773	2026-09-22 02:07	69.03	OK	16774	2026-09-22 02:08	69.42	OK
16775	2026-09-22 02:09	68.39	OK	16776	2026-09-22 02:10	70.41	OK
16777	2026-09-22 02:11	72.47	OK	16778	2026-09-22 02:12	69.62	OK
16779	2026-09-22 02:13	69.10	OK	16780	2026-09-22 02:14	70.18	OK
16781	2026-09-22 02:15	67.29	OK	16782	2026-09-22 02:16	69.88	OK
16783	2026-09-22 02:17	71.03	OK	16784	2026-09-22 02:18	68.93	OK
16785	2026-09-22 02:19	68.82	OK	16786	2026-09-22 02:20	68.04	OK
16787	2026-09-22 02:21	71.76	OK	16788	2026-09-22 02:22	68.84	OK
16789	2026-09-22 02:23	69.49	OK	16790	2026-09-22 02:24	67.17	OK
16791	2026-09-22 02:25	71.56	OK	16792	2026-09-22 02:26	68.68	OK
16793	2026-09-22 02:27	69.92	OK	16794	2026-09-22 02:28	69.28	OK
16795	2026-09-22 02:29	71.13	OK	16796	2026-09-22 02:30	72.60	OK
16797	2026-09-22 02:31	69.65	OK	16798	2026-09-22 02:32	69.84	OK
16799	2026-09-22 02:33	69.00	OK	16800	2026-09-22 02:34	73.53	OK
16801	2026-09-22 02:35	68.13	OK	16802	2026-09-22 02:36	68.66	OK
16803	2026-09-22 02:37	69.49	OK	16804	2026-09-22 02:38	68.11	OK
16805	2026-09-22 02:39	69.75	OK	16806	2026-09-22 02:40	70.01	OK
16807	2026-09-22 02:41	71.87	OK	16808	2026-09-22 02:42	67.79	OK
16809	2026-09-22 02:43	68.44	OK	16810	2026-09-22 02:44	66.58	OK
16811	2026-09-22 02:45	70.33	OK	16812	2026-09-22 02:46	71.16	OK
16813	2026-09-22 02:47	67.63	OK	16814	2026-09-22 02:48	71.52	OK
16815	2026-09-22 02:49	71.16	OK	16816	2026-09-22 02:50	68.53	OK
16817	2026-09-22 02:51	70.88	OK	16818	2026-09-22 02:52	70.82	OK
16819	2026-09-22 02:53	67.92	OK	16820	2026-09-22 02:54	68.97	OK
16821	2026-09-22 02:55	71.66	OK	16822	2026-09-22 02:56	70.09	OK
16823	2026-09-22 02:57	66.98	OK	16824	2026-09-22 02:58	69.62	OK
16825	2026-09-22 02:59	69.44	OK	16826	2026-09-22 03:00	67.85	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16827	2026-09-22 03:01	71.94	OK	16828	2026-09-22 03:02	69.12	OK
16829	2026-09-22 03:03	70.65	OK	16830	2026-09-22 03:04	68.43	OK
16831	2026-09-22 03:05	70.00	OK	16832	2026-09-22 03:06	70.33	OK
16833	2026-09-22 03:07	70.81	OK	16834	2026-09-22 03:08	69.64	OK
16835	2026-09-22 03:09	72.37	OK	16836	2026-09-22 03:10	69.35	OK
16837	2026-09-22 03:11	71.34	OK	16838	2026-09-22 03:12	72.10	OK
16839	2026-09-22 03:13	67.03	OK	16840	2026-09-22 03:14	72.49	OK
16841	2026-09-22 03:15	66.12	OK	16842	2026-09-22 03:16	69.70	OK
16843	2026-09-22 03:17	69.61	OK	16844	2026-09-22 03:18	70.98	OK
16845	2026-09-22 03:19	71.77	OK	16846	2026-09-22 03:20	68.43	OK
16847	2026-09-22 03:21	70.52	OK	16848	2026-09-22 03:22	68.58	OK
16849	2026-09-22 03:23	67.48	OK	16850	2026-09-22 03:24	70.35	OK
16851	2026-09-22 03:25	70.13	OK	16852	2026-09-22 03:26	69.87	OK
16853	2026-09-22 03:27	70.65	OK	16854	2026-09-22 03:28	71.63	OK
16855	2026-09-22 03:29	70.60	OK	16856	2026-09-22 03:30	72.97	OK
16857	2026-09-22 03:31	73.07	OK	16858	2026-09-22 03:32	71.25	OK
16859	2026-09-22 03:33	67.61	OK	16860	2026-09-22 03:34	69.90	OK
16861	2026-09-22 03:35	69.40	OK	16862	2026-09-22 03:36	72.86	OK
16863	2026-09-22 03:37	69.86	OK	16864	2026-09-22 03:38	69.45	OK
16865	2026-09-22 03:39	73.99	OK	16866	2026-09-22 03:40	71.88	OK
16867	2026-09-22 03:41	70.34	OK	16868	2026-09-22 03:42	71.52	OK
16869	2026-09-22 03:43	70.41	OK	16870	2026-09-22 03:44	73.44	OK
16871	2026-09-22 03:45	70.02	OK	16872	2026-09-22 03:46	71.62	OK
16873	2026-09-22 03:47	69.97	OK	16874	2026-09-22 03:48	69.65	OK
16875	2026-09-22 03:49	72.18	OK	16876	2026-09-22 03:50	67.82	OK
16877	2026-09-22 03:51	73.26	OK	16878	2026-09-22 03:52	69.16	OK
16879	2026-09-22 03:53	72.06	OK	16880	2026-09-22 03:54	71.62	OK
16881	2026-09-22 03:55	73.13	OK	16882	2026-09-22 03:56	71.52	OK
16883	2026-09-22 03:57	71.16	OK	16884	2026-09-22 03:58	72.44	OK
16885	2026-09-22 03:59	68.41	OK	16886	2026-09-22 04:00	69.02	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16887	2026-09-22 04:01	71.48	OK	16888	2026-09-22 04:02	70.61	OK
16889	2026-09-22 04:03	69.13	OK	16890	2026-09-22 04:04	69.92	OK
16891	2026-09-22 04:05	70.25	OK	16892	2026-09-22 04:06	69.34	OK
16893	2026-09-22 04:07	70.03	OK	16894	2026-09-22 04:08	72.61	OK
16895	2026-09-22 04:09	70.41	OK	16896	2026-09-22 04:10	69.52	OK
16897	2026-09-22 04:11	72.18	OK	16898	2026-09-22 04:12	72.96	OK
16899	2026-09-22 04:13	70.50	OK	16900	2026-09-22 04:14	69.64	OK
16901	2026-09-22 04:15	70.02	OK	16902	2026-09-22 04:16	73.97	OK
16903	2026-09-22 04:17	71.49	OK	16904	2026-09-22 04:18	74.14	OK
16905	2026-09-22 04:19	72.26	OK	16906	2026-09-22 04:20	71.71	OK
16907	2026-09-22 04:21	72.23	OK	16908	2026-09-22 04:22	71.24	OK
16909	2026-09-22 04:23	70.20	OK	16910	2026-09-22 04:24	71.53	OK
16911	2026-09-22 04:25	70.04	OK	16912	2026-09-22 04:26	70.29	OK
16913	2026-09-22 04:27	75.13	OK	16914	2026-09-22 04:28	69.53	OK
16915	2026-09-22 04:29	69.49	OK	16916	2026-09-22 04:30	72.64	OK
16917	2026-09-22 04:31	72.87	OK	16918	2026-09-22 04:32	69.97	OK
16919	2026-09-22 04:33	69.65	OK	16920	2026-09-22 04:34	70.23	OK
16921	2026-09-22 04:35	70.47	OK	16922	2026-09-22 04:36	72.65	OK
16923	2026-09-22 04:37	71.90	OK	16924	2026-09-22 04:38	70.15	OK
16925	2026-09-22 04:39	69.86	OK	16926	2026-09-22 04:40	71.07	OK
16927	2026-09-22 04:41	71.80	OK	16928	2026-09-22 04:42	73.59	OK
16929	2026-09-22 04:43	68.33	OK	16930	2026-09-22 04:44	70.33	OK
16931	2026-09-22 04:45	70.83	OK	16932	2026-09-22 04:46	70.52	OK
16933	2026-09-22 04:47	74.18	OK	16934	2026-09-22 04:48	72.51	OK
16935	2026-09-22 04:49	70.85	OK	16936	2026-09-22 04:50	72.71	OK
16937	2026-09-22 04:51	73.75	OK	16938	2026-09-22 04:52	69.51	OK
16939	2026-09-22 04:53	70.58	OK	16940	2026-09-22 04:54	71.40	OK
16941	2026-09-22 04:55	74.07	OK	16942	2026-09-22 04:56	70.40	OK
16943	2026-09-22 04:57	71.99	OK	16944	2026-09-22 04:58	70.48	OK
16945	2026-09-22 04:59	73.48	OK	16946	2026-09-22 05:00	72.16	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16947	2026-09-22 05:01	69.80	OK	16948	2026-09-22 05:02	75.84	OK
16949	2026-09-22 05:03	74.19	OK	16950	2026-09-22 05:04	72.81	OK
16951	2026-09-22 05:05	75.40	OK	16952	2026-09-22 05:06	71.49	OK
16953	2026-09-22 05:07	71.17	OK	16954	2026-09-22 05:08	72.03	OK
16955	2026-09-22 05:09	73.38	OK	16956	2026-09-22 05:10	70.76	OK
16957	2026-09-22 05:11	74.55	OK	16958	2026-09-22 05:12	75.59	OK
16959	2026-09-22 05:13	70.60	OK	16960	2026-09-22 05:14	69.77	OK
16961	2026-09-22 05:15	72.27	OK	16962	2026-09-22 05:16	74.91	OK
16963	2026-09-22 05:17	72.05	OK	16964	2026-09-22 05:18	71.84	OK
16965	2026-09-22 05:19	71.81	OK	16966	2026-09-22 05:20	74.77	OK
16967	2026-09-22 05:21	72.75	OK	16968	2026-09-22 05:22	74.86	OK
16969	2026-09-22 05:23	73.38	OK	16970	2026-09-22 05:24	73.24	OK
16971	2026-09-22 05:25	72.82	OK	16972	2026-09-22 05:26	73.33	OK
16973	2026-09-22 05:27	70.50	OK	16974	2026-09-22 05:28	74.53	OK
16975	2026-09-22 05:29	69.05	OK	16976	2026-09-22 05:30	74.49	OK
16977	2026-09-22 05:31	72.53	OK	16978	2026-09-22 05:32	72.88	OK
16979	2026-09-22 05:33	76.46	OK	16980	2026-09-22 05:34	72.82	OK
16981	2026-09-22 05:35	74.83	OK	16982	2026-09-22 05:36	75.76	OK
16983	2026-09-22 05:37	71.32	OK	16984	2026-09-22 05:38	71.75	OK
16985	2026-09-22 05:39	70.50	OK	16986	2026-09-22 05:40	72.93	OK
16987	2026-09-22 05:41	73.89	OK	16988	2026-09-22 05:42	72.71	OK
16989	2026-09-22 05:43	72.78	OK	16990	2026-09-22 05:44	74.49	OK
16991	2026-09-22 05:45	72.94	OK	16992	2026-09-22 05:46	73.97	OK
16993	2026-09-22 05:47	74.23	OK	16994	2026-09-22 05:48	71.51	OK
16995	2026-09-22 05:49	74.94	OK	16996	2026-09-22 05:50	71.58	OK
16997	2026-09-22 05:51	75.51	OK	16998	2026-09-22 05:52	73.35	OK
16999	2026-09-22 05:53	75.40	OK	17000	2026-09-22 05:54	74.17	OK
17001	2026-09-22 05:55	71.66	OK	17002	2026-09-22 05:56	72.29	OK
17003	2026-09-22 05:57	77.30	OK	17004	2026-09-22 05:58	75.85	OK
17005	2026-09-22 05:59	73.22	OK	17006	2026-09-22 06:00	74.69	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17007	2026-09-22 06:01	73.13	OK	17008	2026-09-22 06:02	75.65	OK
17009	2026-09-22 06:03	75.52	OK	17010	2026-09-22 06:04	76.08	OK
17011	2026-09-22 06:05	76.38	OK	17012	2026-09-22 06:06	73.92	OK
17013	2026-09-22 06:07	73.22	OK	17014	2026-09-22 06:08	73.61	OK
17015	2026-09-22 06:09	71.64	OK	17016	2026-09-22 06:10	73.95	OK
17017	2026-09-22 06:11	71.25	OK	17018	2026-09-22 06:12	75.36	OK
17019	2026-09-22 06:13	76.69	OK	17020	2026-09-22 06:14	71.43	OK
17021	2026-09-22 06:15	76.27	OK	17022	2026-09-22 06:16	76.92	OK
17023	2026-09-22 06:17	76.09	OK	17024	2026-09-22 06:18	75.76	OK
17025	2026-09-22 06:19	75.78	OK	17026	2026-09-22 06:20	73.11	OK
17027	2026-09-22 06:21	73.67	OK	17028	2026-09-22 06:22	76.12	OK
17029	2026-09-22 06:23	72.80	OK	17030	2026-09-22 06:24	72.70	OK
17031	2026-09-22 06:25	72.29	OK	17032	2026-09-22 06:26	71.83	OK
17033	2026-09-22 06:27	75.75	OK	17034	2026-09-22 06:28	74.72	OK
17035	2026-09-22 06:29	71.23	OK	17036	2026-09-22 06:30	76.25	OK
17037	2026-09-22 06:31	75.94	OK	17038	2026-09-22 06:32	74.08	OK
17039	2026-09-22 06:33	76.55	OK	17040	2026-09-22 06:34	75.42	OK
17041	2026-09-22 06:35	72.71	OK	17042	2026-09-22 06:36	73.31	OK
17043	2026-09-22 06:37	76.58	OK	17044	2026-09-22 06:38	73.26	OK
17045	2026-09-22 06:39	75.37	OK	17046	2026-09-22 06:40	73.24	OK
17047	2026-09-22 06:41	72.51	OK	17048	2026-09-22 06:42	74.01	OK
17049	2026-09-22 06:43	74.52	OK	17050	2026-09-22 06:44	73.39	OK
17051	2026-09-22 06:45	76.13	OK	17052	2026-09-22 06:46	72.15	OK
17053	2026-09-22 06:47	74.75	OK	17054	2026-09-22 06:48	75.05	OK
17055	2026-09-22 06:49	72.68	OK	17056	2026-09-22 06:50	71.78	OK
17057	2026-09-22 06:51	75.49	OK	17058	2026-09-22 06:52	74.56	OK
17059	2026-09-22 06:53	76.39	OK	17060	2026-09-22 06:54	76.96	OK
17061	2026-09-22 06:55	75.40	OK	17062	2026-09-22 06:56	74.88	OK
17063	2026-09-22 06:57	73.15	OK	17064	2026-09-22 06:58	73.34	OK
17065	2026-09-22 06:59	74.91	OK	17066	2026-09-22 07:00	75.10	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17067	2026-09-22 07:01	76.01	OK	17068	2026-09-22 07:02	77.03	OK
17069	2026-09-22 07:03	77.22	OK	17070	2026-09-22 07:04	72.63	OK
17071	2026-09-22 07:05	78.18	OK	17072	2026-09-22 07:06	76.04	OK
17073	2026-09-22 07:07	72.56	OK	17074	2026-09-22 07:08	77.07	OK
17075	2026-09-22 07:09	76.36	OK	17076	2026-09-22 07:10	71.89	OK
17077	2026-09-22 07:11	72.75	OK	17078	2026-09-22 07:12	74.48	OK
17079	2026-09-22 07:13	77.60	OK	17080	2026-09-22 07:14	78.16	OK
17081	2026-09-22 07:15	74.24	OK	17082	2026-09-22 07:16	78.26	OK
17083	2026-09-22 07:17	76.96	OK	17084	2026-09-22 07:18	74.98	OK
17085	2026-09-22 07:19	74.97	OK	17086	2026-09-22 07:20	74.66	OK
17087	2026-09-22 07:21	75.60	OK	17088	2026-09-22 07:22	74.08	OK
17089	2026-09-22 07:23	74.60	OK	17090	2026-09-22 07:24	74.64	OK
17091	2026-09-22 07:25	77.24	OK	17092	2026-09-22 07:26	75.00	OK
17093	2026-09-22 07:27	74.47	OK	17094	2026-09-22 07:28	75.13	OK
17095	2026-09-22 07:29	74.56	OK	17096	2026-09-22 07:30	74.82	OK
17097	2026-09-22 07:31	73.62	OK	17098	2026-09-22 07:32	79.90	OK
17099	2026-09-22 07:33	76.62	OK	17100	2026-09-22 07:34	75.20	OK
17101	2026-09-22 07:35	77.33	OK	17102	2026-09-22 07:36	71.89	OK
17103	2026-09-22 07:37	74.47	OK	17104	2026-09-22 07:38	73.55	OK
17105	2026-09-22 07:39	77.18	OK	17106	2026-09-22 07:40	75.07	OK
17107	2026-09-22 07:41	76.55	OK	17108	2026-09-22 07:42	76.24	OK
17109	2026-09-22 07:43	77.18	OK	17110	2026-09-22 07:44	74.91	OK
17111	2026-09-22 07:45	78.55	OK	17112	2026-09-22 07:46	76.31	OK
17113	2026-09-22 07:47	77.03	OK	17114	2026-09-22 07:48	77.11	OK
17115	2026-09-22 07:49	76.17	OK	17116	2026-09-22 07:50	77.98	OK
17117	2026-09-22 07:51	78.85	OK	17118	2026-09-22 07:52	76.58	OK
17119	2026-09-22 07:53	76.35	OK	17120	2026-09-22 07:54	77.30	OK
17121	2026-09-22 07:55	76.70	OK	17122	2026-09-22 07:56	74.90	OK
17123	2026-09-22 07:57	76.52	OK	17124	2026-09-22 07:58	76.71	OK
17125	2026-09-22 07:59	76.57	OK	17126	2026-09-22 08:00	77.59	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17127	2026-09-22 08:01	78.64	OK	17128	2026-09-22 08:02	77.16	OK
17129	2026-09-22 08:03	78.50	OK	17130	2026-09-22 08:04	75.73	OK
17131	2026-09-22 08:05	79.76	OK	17132	2026-09-22 08:06	78.81	OK
17133	2026-09-22 08:07	77.93	OK	17134	2026-09-22 08:08	78.51	OK
17135	2026-09-22 08:09	75.23	OK	17136	2026-09-22 08:10	77.25	OK
17137	2026-09-22 08:11	77.93	OK	17138	2026-09-22 08:12	74.54	OK
17139	2026-09-22 08:13	74.90	OK	17140	2026-09-22 08:14	76.31	OK
17141	2026-09-22 08:15	73.68	OK	17142	2026-09-22 08:16	76.12	OK
17143	2026-09-22 08:17	77.77	OK	17144	2026-09-22 08:18	79.81	OK
17145	2026-09-22 08:19	76.50	OK	17146	2026-09-22 08:20	75.49	OK
17147	2026-09-22 08:21	77.84	OK	17148	2026-09-22 08:22	76.89	OK
17149	2026-09-22 08:23	76.39	OK	17150	2026-09-22 08:24	76.70	OK
17151	2026-09-22 08:25	76.61	OK	17152	2026-09-22 08:26	79.59	OK
17153	2026-09-22 08:27	76.09	OK	17154	2026-09-22 08:28	74.48	OK
17155	2026-09-22 08:29	76.48	OK	17156	2026-09-22 08:30	75.20	OK
17157	2026-09-22 08:31	77.29	OK	17158	2026-09-22 08:32	78.47	OK
17159	2026-09-22 08:33	77.38	OK	17160	2026-09-22 08:34	74.62	OK
17161	2026-09-22 08:35	76.18	OK	17162	2026-09-22 08:36	80.42	OK
17163	2026-09-22 08:37	78.81	OK	17164	2026-09-22 08:38	79.52	OK
17165	2026-09-22 08:39	77.92	OK	17166	2026-09-22 08:40	80.01	OK
17167	2026-09-22 08:41	76.16	OK	17168	2026-09-22 08:42	78.71	OK
17169	2026-09-22 08:43	78.47	OK	17170	2026-09-22 08:44	75.50	OK
17171	2026-09-22 08:45	77.45	OK	17172	2026-09-22 08:46	77.95	OK
17173	2026-09-22 08:47	78.18	OK	17174	2026-09-22 08:48	79.52	OK
17175	2026-09-22 08:49	76.57	OK	17176	2026-09-22 08:50	79.55	OK
17177	2026-09-22 08:51	77.57	OK	17178	2026-09-22 08:52	73.95	OK
17179	2026-09-22 08:53	76.93	OK	17180	2026-09-22 08:54	78.64	OK
17181	2026-09-22 08:55	79.95	OK	17182	2026-09-22 08:56	76.18	OK
17183	2026-09-22 08:57	77.79	OK	17184	2026-09-22 08:58	78.10	OK
17185	2026-09-22 08:59	78.98	OK	17186	2026-09-22 09:00	76.83	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17187	2026-09-22 09:01	77.76	OK	17188	2026-09-22 09:02	76.69	OK
17189	2026-09-22 09:03	79.18	OK	17190	2026-09-22 09:04	75.15	OK
17191	2026-09-22 09:05	80.21	OK	17192	2026-09-22 09:06	78.92	OK
17193	2026-09-22 09:07	80.48	OK	17194	2026-09-22 09:08	78.29	OK
17195	2026-09-22 09:09	76.30	OK	17196	2026-09-22 09:10	79.33	OK
17197	2026-09-22 09:11	78.14	OK	17198	2026-09-22 09:12	77.63	OK
17199	2026-09-22 09:13	78.86	OK	17200	2026-09-22 09:14	78.46	OK
17201	2026-09-22 09:15	75.45	OK	17202	2026-09-22 09:16	79.76	OK
17203	2026-09-22 09:17	78.68	OK	17204	2026-09-22 09:18	80.03	OK
17205	2026-09-22 09:19	78.73	OK	17206	2026-09-22 09:20	80.66	OK
17207	2026-09-22 09:21	77.63	OK	17208	2026-09-22 09:22	79.28	OK
17209	2026-09-22 09:23	79.90	OK	17210	2026-09-22 09:24	76.98	OK
17211	2026-09-22 09:25	79.90	OK	17212	2026-09-22 09:26	79.05	OK
17213	2026-09-22 09:27	76.68	OK	17214	2026-09-22 09:28	77.86	OK
17215	2026-09-22 09:29	78.48	OK	17216	2026-09-22 09:30	77.59	OK
17217	2026-09-22 09:31	80.33	OK	17218	2026-09-22 09:32	79.26	OK
17219	2026-09-22 09:33	77.55	OK	17220	2026-09-22 09:34	79.57	OK
17221	2026-09-22 09:35	78.32	OK	17222	2026-09-22 09:36	77.65	OK
17223	2026-09-22 09:37	79.95	OK	17224	2026-09-22 09:38	78.62	OK
17225	2026-09-22 09:39	79.79	OK	17226	2026-09-22 09:40	79.80	OK
17227	2026-09-22 09:41	78.97	OK	17228	2026-09-22 09:42	78.92	OK
17229	2026-09-22 09:43	80.72	OK	17230	2026-09-22 09:44	76.25	OK
17231	2026-09-22 09:45	80.00	OK	17232	2026-09-22 09:46	79.46	OK
17233	2026-09-22 09:47	81.03	OK	17234	2026-09-22 09:48	78.04	OK
17235	2026-09-22 09:49	82.91	OK	17236	2026-09-22 09:50	77.51	OK
17237	2026-09-22 09:51	79.40	OK	17238	2026-09-22 09:52	80.34	OK
17239	2026-09-22 09:53	79.80	OK	17240	2026-09-22 09:54	78.25	OK
17241	2026-09-22 09:55	78.21	OK	17242	2026-09-22 09:56	77.42	OK
17243	2026-09-22 09:57	80.38	OK	17244	2026-09-22 09:58	77.22	OK
17245	2026-09-22 09:59	79.39	OK	17246	2026-09-22 10:00	80.20	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17247	2026-09-22 10:01	79.89	OK	17248	2026-09-22 10:02	82.23	OK
17249	2026-09-22 10:03	79.93	OK	17250	2026-09-22 10:04	81.23	OK
17251	2026-09-22 10:05	80.09	OK	17252	2026-09-22 10:06	80.52	OK
17253	2026-09-22 10:07	79.65	OK	17254	2026-09-22 10:08	82.56	OK
17255	2026-09-22 10:09	79.07	OK	17256	2026-09-22 10:10	78.98	OK
17257	2026-09-22 10:11	81.16	OK	17258	2026-09-22 10:12	82.28	OK
17259	2026-09-22 10:13	79.27	OK	17260	2026-09-22 10:14	81.87	OK
17261	2026-09-22 10:15	83.33	OK	17262	2026-09-22 10:16	80.01	OK
17263	2026-09-22 10:17	79.56	OK	17264	2026-09-22 10:18	81.51	OK
17265	2026-09-22 10:19	78.72	OK	17266	2026-09-22 10:20	81.12	OK
17267	2026-09-22 10:21	80.08	OK	17268	2026-09-22 10:22	80.29	OK
17269	2026-09-22 10:23	80.61	OK	17270	2026-09-22 10:24	79.64	OK
17271	2026-09-22 10:25	76.77	OK	17272	2026-09-22 10:26	82.03	OK
17273	2026-09-22 10:27	77.55	OK	17274	2026-09-22 10:28	79.76	OK
17275	2026-09-22 10:29	77.69	OK	17276	2026-09-22 10:30	80.50	OK
17277	2026-09-22 10:31	82.82	OK	17278	2026-09-22 10:32	78.48	OK
17279	2026-09-22 10:33	80.88	OK	17280	2026-09-22 10:34	81.42	OK
17281	2026-09-22 10:35	80.04	OK	17282	2026-09-22 10:36	80.39	OK
17283	2026-09-22 10:37	81.80	OK	17284	2026-09-22 10:38	81.07	OK
17285	2026-09-22 10:39	80.26	OK	17286	2026-09-22 10:40	81.83	OK
17287	2026-09-22 10:41	83.46	OK	17288	2026-09-22 10:42	76.91	OK
17289	2026-09-22 10:43	81.42	OK	17290	2026-09-22 10:44	81.72	OK
17291	2026-09-22 10:45	81.17	OK	17292	2026-09-22 10:46	79.08	OK
17293	2026-09-22 10:47	77.79	OK	17294	2026-09-22 10:48	80.80	OK
17295	2026-09-22 10:49	79.28	OK	17296	2026-09-22 10:50	80.95	OK
17297	2026-09-22 10:51	75.71	OK	17298	2026-09-22 10:52	80.39	OK
17299	2026-09-22 10:53	78.85	OK	17300	2026-09-22 10:54	83.03	OK
17301	2026-09-22 10:55	79.88	OK	17302	2026-09-22 10:56	77.55	OK
17303	2026-09-22 10:57	81.92	OK	17304	2026-09-22 10:58	79.09	OK
17305	2026-09-22 10:59	81.83	OK	17306	2026-09-22 11:00	78.91	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17307	2026-09-22 11:01	78.29	OK	17308	2026-09-22 11:02	79.08	OK
17309	2026-09-22 11:03	81.65	OK	17310	2026-09-22 11:04	80.80	OK
17311	2026-09-22 11:05	79.78	OK	17312	2026-09-22 11:06	79.62	OK
17313	2026-09-22 11:07	80.37	OK	17314	2026-09-22 11:08	83.48	OK
17315	2026-09-22 11:09	81.73	OK	17316	2026-09-22 11:10	80.31	OK
17317	2026-09-22 11:11	81.18	OK	17318	2026-09-22 11:12	81.63	OK
17319	2026-09-22 11:13	78.69	OK	17320	2026-09-22 11:14	82.44	OK
17321	2026-09-22 11:15	80.98	OK	17322	2026-09-22 11:16	80.16	OK
17323	2026-09-22 11:17	79.32	OK	17324	2026-09-22 11:18	82.85	OK
17325	2026-09-22 11:19	81.37	OK	17326	2026-09-22 11:20	83.33	OK
17327	2026-09-22 11:21	81.88	OK	17328	2026-09-22 11:22	80.66	OK
17329	2026-09-22 11:23	78.70	OK	17330	2026-09-22 11:24	81.11	OK
17331	2026-09-22 11:25	79.66	OK	17332	2026-09-22 11:26	81.19	OK
17333	2026-09-22 11:27	81.33	OK	17334	2026-09-22 11:28	81.69	OK
17335	2026-09-22 11:29	80.72	OK	17336	2026-09-22 11:30	78.20	OK
17337	2026-09-22 11:31	79.99	OK	17338	2026-09-22 11:32	82.69	OK
17339	2026-09-22 11:33	79.41	OK	17340	2026-09-22 11:34	79.18	OK
17341	2026-09-22 11:35	78.88	OK	17342	2026-09-22 11:36	77.77	OK
17343	2026-09-22 11:37	81.03	OK	17344	2026-09-22 11:38	77.73	OK
17345	2026-09-22 11:39	78.32	OK	17346	2026-09-22 11:40	80.65	OK
17347	2026-09-22 11:41	80.33	OK	17348	2026-09-22 11:42	82.72	OK
17349	2026-09-22 11:43	81.48	OK	17350	2026-09-22 11:44	77.31	OK
17351	2026-09-22 11:45	80.08	OK	17352	2026-09-22 11:46	83.31	OK
17353	2026-09-22 11:47	81.92	OK	17354	2026-09-22 11:48	84.05	OK
17355	2026-09-22 11:49	78.56	OK	17356	2026-09-22 11:50	82.43	OK
17357	2026-09-22 11:51	83.28	OK	17358	2026-09-22 11:52	78.05	OK
17359	2026-09-22 11:53	78.64	OK	17360	2026-09-22 11:54	79.68	OK
17361	2026-09-22 11:55	82.49	OK	17362	2026-09-22 11:56	79.94	OK
17363	2026-09-22 11:57	80.05	OK	17364	2026-09-22 11:58	80.35	OK
17365	2026-09-22 11:59	81.81	OK	17366	2026-09-22 12:00	79.16	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17367	2026-09-22 12:01	79.78	OK	17368	2026-09-22 12:02	80.38	OK
17369	2026-09-22 12:03	84.10	OK	17370	2026-09-22 12:04	80.03	OK
17371	2026-09-22 12:05	83.19	OK	17372	2026-09-22 12:06	82.04	OK
17373	2026-09-22 12:07	82.85	OK	17374	2026-09-22 12:08	82.69	OK
17375	2026-09-22 12:09	79.55	OK	17376	2026-09-22 12:10	79.72	OK
17377	2026-09-22 12:11	81.22	OK	17378	2026-09-22 12:12	83.77	OK
17379	2026-09-22 12:13	81.91	OK	17380	2026-09-22 12:14	81.45	OK
17381	2026-09-22 12:15	81.14	OK	17382	2026-09-22 12:16	79.76	OK
17383	2026-09-22 12:17	82.93	OK	17384	2026-09-22 12:18	80.56	OK
17385	2026-09-22 12:19	84.78	OK	17386	2026-09-22 12:20	79.56	OK
17387	2026-09-22 12:21	81.22	OK	17388	2026-09-22 12:22	83.05	OK
17389	2026-09-22 12:23	79.53	OK	17390	2026-09-22 12:24	81.76	OK
17391	2026-09-22 12:25	81.99	OK	17392	2026-09-22 12:26	80.43	OK
17393	2026-09-22 12:27	78.79	OK	17394	2026-09-22 12:28	82.45	OK
17395	2026-09-22 12:29	78.55	OK	17396	2026-09-22 12:30	80.77	OK
17397	2026-09-22 12:31	79.80	OK	17398	2026-09-22 12:32	79.08	OK
17399	2026-09-22 12:33	82.25	OK	17400	2026-09-22 12:34	79.72	OK
17401	2026-09-22 12:35	78.29	OK	17402	2026-09-22 12:36	81.81	OK
17403	2026-09-22 12:37	82.49	OK	17404	2026-09-22 12:38	79.59	OK
17405	2026-09-22 12:39	82.50	OK	17406	2026-09-22 12:40	81.84	OK
17407	2026-09-22 12:41	83.12	OK	17408	2026-09-22 12:42	81.63	OK
17409	2026-09-22 12:43	84.44	OK	17410	2026-09-22 12:44	78.55	OK
17411	2026-09-22 12:45	82.16	OK	17412	2026-09-22 12:46	77.51	OK
17413	2026-09-22 12:47	83.15	OK	17414	2026-09-22 12:48	81.89	OK
17415	2026-09-22 12:49	77.50	OK	17416	2026-09-22 12:50	80.62	OK
17417	2026-09-22 12:51	81.02	OK	17418	2026-09-22 12:52	82.90	OK
17419	2026-09-22 12:53	82.00	OK	17420	2026-09-22 12:54	84.69	OK
17421	2026-09-22 12:55	83.31	OK	17422	2026-09-22 12:56	81.56	OK
17423	2026-09-22 12:57	80.90	OK	17424	2026-09-22 12:58	82.89	OK
17425	2026-09-22 12:59	81.06	OK	17426	2026-09-22 13:00	80.90	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17427	2026-09-22 13:01	79.02	OK	17428	2026-09-22 13:02	81.16	OK
17429	2026-09-22 13:03	81.78	OK	17430	2026-09-22 13:04	77.97	OK
17431	2026-09-22 13:05	82.35	OK	17432	2026-09-22 13:06	80.86	OK
17433	2026-09-22 13:07	79.27	OK	17434	2026-09-22 13:08	79.76	OK
17435	2026-09-22 13:09	78.36	OK	17436	2026-09-22 13:10	80.41	OK
17437	2026-09-22 13:11	80.31	OK	17438	2026-09-22 13:12	80.53	OK
17439	2026-09-22 13:13	78.48	OK	17440	2026-09-22 13:14	82.01	OK
17441	2026-09-22 13:15	81.35	OK	17442	2026-09-22 13:16	80.93	OK
17443	2026-09-22 13:17	77.84	OK	17444	2026-09-22 13:18	82.75	OK
17445	2026-09-22 13:19	79.78	OK	17446	2026-09-22 13:20	80.47	OK
17447	2026-09-22 13:21	78.22	OK	17448	2026-09-22 13:22	80.12	OK
17449	2026-09-22 13:23	79.12	OK	17450	2026-09-22 13:24	79.38	OK
17451	2026-09-22 13:25	81.43	OK	17452	2026-09-22 13:26	80.79	OK
17453	2026-09-22 13:27	79.44	OK	17454	2026-09-22 13:28	81.80	OK
17455	2026-09-22 13:29	77.35	OK	17456	2026-09-22 13:30	80.95	OK
17457	2026-09-22 13:31	81.66	OK	17458	2026-09-22 13:32	81.92	OK
17459	2026-09-22 13:33	80.59	OK	17460	2026-09-22 13:34	77.61	OK
17461	2026-09-22 13:35	82.14	OK	17462	2026-09-22 13:36	79.71	OK
17463	2026-09-22 13:37	81.02	OK	17464	2026-09-22 13:38	80.60	OK
17465	2026-09-22 13:39	80.92	OK	17466	2026-09-22 13:40	82.26	OK
17467	2026-09-22 13:41	78.74	OK	17468	2026-09-22 13:42	81.00	OK
17469	2026-09-22 13:43	78.24	OK	17470	2026-09-22 13:44	84.14	OK
17471	2026-09-22 13:45	81.95	OK	17472	2026-09-22 13:46	80.76	OK
17473	2026-09-22 13:47	80.41	OK	17474	2026-09-22 13:48	79.22	OK
17475	2026-09-22 13:49	81.28	OK	17476	2026-09-22 13:50	79.63	OK
17477	2026-09-22 13:51	80.16	OK	17478	2026-09-22 13:52	81.23	OK
17479	2026-09-22 13:53	78.43	OK	17480	2026-09-22 13:54	83.97	OK
17481	2026-09-22 13:55	80.07	OK	17482	2026-09-22 13:56	81.21	OK
17483	2026-09-22 13:57	79.38	OK	17484	2026-09-22 13:58	80.12	OK
17485	2026-09-22 13:59	79.08	OK	17486	2026-09-22 14:00	81.66	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17487	2026-09-22 14:01	81.19	OK	17488	2026-09-22 14:02	80.23	OK
17489	2026-09-22 14:03	79.97	OK	17490	2026-09-22 14:04	76.63	OK
17491	2026-09-22 14:05	80.75	OK	17492	2026-09-22 14:06	78.07	OK
17493	2026-09-22 14:07	82.19	OK	17494	2026-09-22 14:08	82.27	OK
17495	2026-09-22 14:09	78.77	OK	17496	2026-09-22 14:10	78.83	OK
17497	2026-09-22 14:11	79.13	OK	17498	2026-09-22 14:12	78.05	OK
17499	2026-09-22 14:13	78.81	OK	17500	2026-09-22 14:14	79.52	OK
17501	2026-09-22 14:15	81.07	OK	17502	2026-09-22 14:16	80.22	OK
17503	2026-09-22 14:17	80.14	OK	17504	2026-09-22 14:18	83.84	OK
17505	2026-09-22 14:19	78.59	OK	17506	2026-09-22 14:20	78.48	OK
17507	2026-09-22 14:21	78.95	OK	17508	2026-09-22 14:22	80.28	OK
17509	2026-09-22 14:23	79.18	OK	17510	2026-09-22 14:24	80.88	OK
17511	2026-09-22 14:25	81.77	OK	17512	2026-09-22 14:26	78.03	OK
17513	2026-09-22 14:27	81.26	OK	17514	2026-09-22 14:28	80.20	OK
17515	2026-09-22 14:29	78.76	OK	17516	2026-09-22 14:30	80.88	OK
17517	2026-09-22 14:31	82.42	OK	17518	2026-09-22 14:32	81.70	OK
17519	2026-09-22 14:33	77.77	OK	17520	2026-09-22 14:34	82.05	OK
17521	2026-09-22 14:35	77.75	OK	17522	2026-09-22 14:36	79.97	OK
17523	2026-09-22 14:37	78.68	OK	17524	2026-09-22 14:38	78.59	OK
17525	2026-09-22 14:39	81.87	OK	17526	2026-09-22 14:40	81.92	OK
17527	2026-09-22 14:41	77.59	OK	17528	2026-09-22 14:42	80.60	OK
17529	2026-09-22 14:43	81.70	OK	17530	2026-09-22 14:44	81.50	OK
17531	2026-09-22 14:45	80.18	OK	17532	2026-09-22 14:46	80.42	OK
17533	2026-09-22 14:47	79.42	OK	17534	2026-09-22 14:48	79.34	OK
17535	2026-09-22 14:49	80.00	OK	17536	2026-09-22 14:50	80.45	OK
17537	2026-09-22 14:51	78.82	OK	17538	2026-09-22 14:52	79.56	OK
17539	2026-09-22 14:53	81.94	OK	17540	2026-09-22 14:54	80.89	OK
17541	2026-09-22 14:55	79.74	OK	17542	2026-09-22 14:56	78.07	OK
17543	2026-09-22 14:57	82.01	OK	17544	2026-09-22 14:58	81.61	OK
17545	2026-09-22 14:59	79.51	OK	17546	2026-09-22 15:00	80.57	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17547	2026-09-22 15:01	79.59	OK	17548	2026-09-22 15:02	81.22	OK
17549	2026-09-22 15:03	79.75	OK	17550	2026-09-22 15:04	79.04	OK
17551	2026-09-22 15:05	78.53	OK	17552	2026-09-22 15:06	77.77	OK
17553	2026-09-22 15:07	81.15	OK	17554	2026-09-22 15:08	80.97	OK
17555	2026-09-22 15:09	80.74	OK	17556	2026-09-22 15:10	81.24	OK
17557	2026-09-22 15:11	80.57	OK	17558	2026-09-22 15:12	82.18	OK
17559	2026-09-22 15:13	78.67	OK	17560	2026-09-22 15:14	80.09	OK
17561	2026-09-22 15:15	80.23	OK	17562	2026-09-22 15:16	82.70	OK
17563	2026-09-22 15:17	80.75	OK	17564	2026-09-22 15:18	82.51	OK
17565	2026-09-22 15:19	81.00	OK	17566	2026-09-22 15:20	77.77	OK
17567	2026-09-22 15:21	80.57	OK	17568	2026-09-22 15:22	82.00	OK
17569	2026-09-22 15:23	76.75	OK	17570	2026-09-22 15:24	81.36	OK
17571	2026-09-22 15:25	80.36	OK	17572	2026-09-22 15:26	79.80	OK
17573	2026-09-22 15:27	78.36	OK	17574	2026-09-22 15:28	82.78	OK
17575	2026-09-22 15:29	80.19	OK	17576	2026-09-22 15:30	81.62	OK
17577	2026-09-22 15:31	79.95	OK	17578	2026-09-22 15:32	80.79	OK
17579	2026-09-22 15:33	80.84	OK	17580	2026-09-22 15:34	78.70	OK
17581	2026-09-22 15:35	77.00	OK	17582	2026-09-22 15:36	78.67	OK
17583	2026-09-22 15:37	77.91	OK	17584	2026-09-22 15:38	77.96	OK
17585	2026-09-22 15:39	81.34	OK	17586	2026-09-22 15:40	79.56	OK
17587	2026-09-22 15:41	79.37	OK	17588	2026-09-22 15:42	80.91	OK
17589	2026-09-22 15:43	81.91	OK	17590	2026-09-22 15:44	80.00	OK
17591	2026-09-22 15:45	77.96	OK	17592	2026-09-22 15:46	79.68	OK
17593	2026-09-22 15:47	75.40	OK	17594	2026-09-22 15:48	79.88	OK
17595	2026-09-22 15:49	76.78	OK	17596	2026-09-22 15:50	80.09	OK
17597	2026-09-22 15:51	81.10	OK	17598	2026-09-22 15:52	82.10	OK
17599	2026-09-22 15:53	78.23	OK	17600	2026-09-22 15:54	79.31	OK
17601	2026-09-22 15:55	80.43	OK	17602	2026-09-22 15:56	82.12	OK
17603	2026-09-22 15:57	80.26	OK	17604	2026-09-22 15:58	80.29	OK
17605	2026-09-22 15:59	78.64	OK	17606	2026-09-22 16:00	80.86	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17607	2026-09-22 16:01	81.68	OK	17608	2026-09-22 16:02	81.35	OK
17609	2026-09-22 16:03	80.75	OK	17610	2026-09-22 16:04	77.01	OK
17611	2026-09-22 16:05	80.75	OK	17612	2026-09-22 16:06	79.91	OK
17613	2026-09-22 16:07	78.20	OK	17614	2026-09-22 16:08	78.03	OK
17615	2026-09-22 16:09	81.23	OK	17616	2026-09-22 16:10	77.19	OK
17617	2026-09-22 16:11	80.83	OK	17618	2026-09-22 16:12	77.53	OK
17619	2026-09-22 16:13	79.74	OK	17620	2026-09-22 16:14	77.81	OK
17621	2026-09-22 16:15	79.41	OK	17622	2026-09-22 16:16	80.62	OK
17623	2026-09-22 16:17	79.54	OK	17624	2026-09-22 16:18	76.94	OK
17625	2026-09-22 16:19	75.97	OK	17626	2026-09-22 16:20	79.27	OK
17627	2026-09-22 16:21	81.81	OK	17628	2026-09-22 16:22	80.27	OK
17629	2026-09-22 16:23	80.82	OK	17630	2026-09-22 16:24	78.69	OK
17631	2026-09-22 16:25	76.98	OK	17632	2026-09-22 16:26	79.13	OK
17633	2026-09-22 16:27	77.92	OK	17634	2026-09-22 16:28	78.50	OK
17635	2026-09-22 16:29	80.95	OK	17636	2026-09-22 16:30	80.48	OK
17637	2026-09-22 16:31	77.26	OK	17638	2026-09-22 16:32	79.61	OK
17639	2026-09-22 16:33	76.12	OK	17640	2026-09-22 16:34	78.32	OK
17641	2026-09-22 16:35	79.12	OK	17642	2026-09-22 16:36	77.30	OK
17643	2026-09-22 16:37	78.80	OK	17644	2026-09-22 16:38	78.46	OK
17645	2026-09-22 16:39	77.74	OK	17646	2026-09-22 16:40	80.43	OK
17647	2026-09-22 16:41	77.41	OK	17648	2026-09-22 16:42	78.54	OK
17649	2026-09-22 16:43	78.85	OK	17650	2026-09-22 16:44	77.14	OK
17651	2026-09-22 16:45	78.15	OK	17652	2026-09-22 16:46	79.97	OK
17653	2026-09-22 16:47	79.78	OK	17654	2026-09-22 16:48	77.65	OK
17655	2026-09-22 16:49	78.57	OK	17656	2026-09-22 16:50	77.00	OK
17657	2026-09-22 16:51	76.48	OK	17658	2026-09-22 16:52	76.81	OK
17659	2026-09-22 16:53	77.60	OK	17660	2026-09-22 16:54	78.42	OK
17661	2026-09-22 16:55	76.49	OK	17662	2026-09-22 16:56	78.23	OK
17663	2026-09-22 16:57	76.49	OK	17664	2026-09-22 16:58	79.15	OK
17665	2026-09-22 16:59	77.64	OK	17666	2026-09-22 17:00	74.02	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17667	2026-09-22 17:01	79.08	OK	17668	2026-09-22 17:02	77.46	OK
17669	2026-09-22 17:03	77.23	OK	17670	2026-09-22 17:04	74.08	OK
17671	2026-09-22 17:05	74.77	OK	17672	2026-09-22 17:06	79.30	OK
17673	2026-09-22 17:07	77.93	OK	17674	2026-09-22 17:08	78.25	OK
17675	2026-09-22 17:09	77.33	OK	17676	2026-09-22 17:10	76.89	OK
17677	2026-09-22 17:11	78.57	OK	17678	2026-09-22 17:12	78.50	OK
17679	2026-09-22 17:13	79.92	OK	17680	2026-09-22 17:14	77.80	OK
17681	2026-09-22 17:15	79.94	OK	17682	2026-09-22 17:16	75.32	OK
17683	2026-09-22 17:17	76.20	OK	17684	2026-09-22 17:18	75.84	OK
17685	2026-09-22 17:19	78.26	OK	17686	2026-09-22 17:20	78.62	OK
17687	2026-09-22 17:21	76.18	OK	17688	2026-09-22 17:22	78.91	OK
17689	2026-09-22 17:23	78.06	OK	17690	2026-09-22 17:24	77.48	OK
17691	2026-09-22 17:25	76.61	OK	17692	2026-09-22 17:26	78.89	OK
17693	2026-09-22 17:27	79.19	OK	17694	2026-09-22 17:28	74.23	OK
17695	2026-09-22 17:29	79.28	OK	17696	2026-09-22 17:30	74.79	OK
17697	2026-09-22 17:31	75.67	OK	17698	2026-09-22 17:32	81.48	OK
17699	2026-09-22 17:33	77.27	OK	17700	2026-09-22 17:34	76.04	OK
17701	2026-09-22 17:35	77.20	OK	17702	2026-09-22 17:36	75.59	OK
17703	2026-09-22 17:37	76.19	OK	17704	2026-09-22 17:38	77.76	OK
17705	2026-09-22 17:39	76.80	OK	17706	2026-09-22 17:40	77.18	OK
17707	2026-09-22 17:41	75.88	OK	17708	2026-09-22 17:42	79.06	OK
17709	2026-09-22 17:43	78.13	OK	17710	2026-09-22 17:44	79.22	OK
17711	2026-09-22 17:45	73.62	OK	17712	2026-09-22 17:46	77.36	OK
17713	2026-09-22 17:47	77.15	OK	17714	2026-09-22 17:48	76.49	OK
17715	2026-09-22 17:49	77.22	OK	17716	2026-09-22 17:50	77.21	OK
17717	2026-09-22 17:51	74.87	OK	17718	2026-09-22 17:52	77.35	OK
17719	2026-09-22 17:53	77.06	OK	17720	2026-09-22 17:54	76.17	OK
17721	2026-09-22 17:55	78.48	OK	17722	2026-09-22 17:56	75.56	OK
17723	2026-09-22 17:57	74.96	OK	17724	2026-09-22 17:58	77.10	OK
17725	2026-09-22 17:59	73.74	OK	17726	2026-09-22 18:00	77.43	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17727	2026-09-22 18:01	76.84	OK	17728	2026-09-22 18:02	80.57	OK
17729	2026-09-22 18:03	75.79	OK	17730	2026-09-22 18:04	74.18	OK
17731	2026-09-22 18:05	77.68	OK	17732	2026-09-22 18:06	77.61	OK
17733	2026-09-22 18:07	78.15	OK	17734	2026-09-22 18:08	75.95	OK
17735	2026-09-22 18:09	77.22	OK	17736	2026-09-22 18:10	79.25	OK
17737	2026-09-22 18:11	75.56	OK	17738	2026-09-22 18:12	76.39	OK
17739	2026-09-22 18:13	76.99	OK	17740	2026-09-22 18:14	76.30	OK
17741	2026-09-22 18:15	79.25	OK	17742	2026-09-22 18:16	79.03	OK
17743	2026-09-22 18:17	75.29	OK	17744	2026-09-22 18:18	74.08	OK
17745	2026-09-22 18:19	75.49	OK	17746	2026-09-22 18:20	72.24	OK
17747	2026-09-22 18:21	75.01	OK	17748	2026-09-22 18:22	76.43	OK
17749	2026-09-22 18:23	74.71	OK	17750	2026-09-22 18:24	75.56	OK
17751	2026-09-22 18:25	74.54	OK	17752	2026-09-22 18:26	75.43	OK
17753	2026-09-22 18:27	79.64	OK	17754	2026-09-22 18:28	73.95	OK
17755	2026-09-22 18:29	75.96	OK	17756	2026-09-22 18:30	76.64	OK
17757	2026-09-22 18:31	74.25	OK	17758	2026-09-22 18:32	76.32	OK
17759	2026-09-22 18:33	79.48	OK	17760	2026-09-22 18:34	73.46	OK
17761	2026-09-22 18:35	75.26	OK	17762	2026-09-22 18:36	74.49	OK
17763	2026-09-22 18:37	76.81	OK	17764	2026-09-22 18:38	72.54	OK
17765	2026-09-22 18:39	75.86	OK	17766	2026-09-22 18:40	73.65	OK
17767	2026-09-22 18:41	76.31	OK	17768	2026-09-22 18:42	77.01	OK
17769	2026-09-22 18:43	76.34	OK	17770	2026-09-22 18:44	77.81	OK
17771	2026-09-22 18:45	77.14	OK	17772	2026-09-22 18:46	77.00	OK
17773	2026-09-22 18:47	71.91	OK	17774	2026-09-22 18:48	72.94	OK
17775	2026-09-22 18:49	72.88	OK	17776	2026-09-22 18:50	71.61	OK
17777	2026-09-22 18:51	76.65	OK	17778	2026-09-22 18:52	78.59	OK
17779	2026-09-22 18:53	74.93	OK	17780	2026-09-22 18:54	75.35	OK
17781	2026-09-22 18:55	73.43	OK	17782	2026-09-22 18:56	76.90	OK
17783	2026-09-22 18:57	76.95	OK	17784	2026-09-22 18:58	76.26	OK
17785	2026-09-22 18:59	73.70	OK	17786	2026-09-22 19:00	75.45	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17787	2026-09-22 19:01	75.72	OK	17788	2026-09-22 19:02	77.51	OK
17789	2026-09-22 19:03	74.57	OK	17790	2026-09-22 19:04	75.25	OK
17791	2026-09-22 19:05	76.00	OK	17792	2026-09-22 19:06	75.84	OK
17793	2026-09-22 19:07	77.66	OK	17794	2026-09-22 19:08	74.64	OK
17795	2026-09-22 19:09	73.56	OK	17796	2026-09-22 19:10	73.32	OK
17797	2026-09-22 19:11	72.28	OK	17798	2026-09-22 19:12	70.33	OK
17799	2026-09-22 19:13	70.59	OK	17800	2026-09-22 19:14	72.95	OK
17801	2026-09-22 19:15	76.53	OK	17802	2026-09-22 19:16	74.72	OK
17803	2026-09-22 19:17	74.68	OK	17804	2026-09-22 19:18	76.37	OK
17805	2026-09-22 19:19	72.91	OK	17806	2026-09-22 19:20	74.79	OK
17807	2026-09-22 19:21	71.17	OK	17808	2026-09-22 19:22	76.13	OK
17809	2026-09-22 19:23	73.53	OK	17810	2026-09-22 19:24	74.23	OK
17811	2026-09-22 19:25	77.47	OK	17812	2026-09-22 19:26	76.01	OK
17813	2026-09-22 19:27	76.27	OK	17814	2026-09-22 19:28	74.16	OK
17815	2026-09-22 19:29	74.53	OK	17816	2026-09-22 19:30	75.12	OK
17817	2026-09-22 19:31	75.08	OK	17818	2026-09-22 19:32	74.11	OK
17819	2026-09-22 19:33	75.42	OK	17820	2026-09-22 19:34	74.11	OK
17821	2026-09-22 19:35	76.04	OK	17822	2026-09-22 19:36	75.40	OK
17823	2026-09-22 19:37	73.15	OK	17824	2026-09-22 19:38	74.25	OK
17825	2026-09-22 19:39	73.17	OK	17826	2026-09-22 19:40	73.26	OK
17827	2026-09-22 19:41	71.35	OK	17828	2026-09-22 19:42	73.80	OK
17829	2026-09-22 19:43	75.36	OK	17830	2026-09-22 19:44	72.01	OK
17831	2026-09-22 19:45	75.19	OK	17832	2026-09-22 19:46	74.24	OK
17833	2026-09-22 19:47	75.59	OK	17834	2026-09-22 19:48	71.77	OK
17835	2026-09-22 19:49	73.63	OK	17836	2026-09-22 19:50	74.86	OK
17837	2026-09-22 19:51	70.16	OK	17838	2026-09-22 19:52	74.28	OK
17839	2026-09-22 19:53	76.34	OK	17840	2026-09-22 19:54	73.99	OK
17841	2026-09-22 19:55	76.69	OK	17842	2026-09-22 19:56	75.72	OK
17843	2026-09-22 19:57	70.58	OK	17844	2026-09-22 19:58	75.21	OK
17845	2026-09-22 19:59	74.03	OK	17846	2026-09-22 20:00	73.45	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17847	2026-09-22 20:01	70.74	OK	17848	2026-09-22 20:02	74.67	OK
17849	2026-09-22 20:03	75.03	OK	17850	2026-09-22 20:04	76.78	OK
17851	2026-09-22 20:05	70.61	OK	17852	2026-09-22 20:06	73.89	OK
17853	2026-09-22 20:07	72.56	OK	17854	2026-09-22 20:08	75.74	OK
17855	2026-09-22 20:09	75.03	OK	17856	2026-09-22 20:10	76.89	OK
17857	2026-09-22 20:11	72.68	OK	17858	2026-09-22 20:12	75.09	OK
17859	2026-09-22 20:13	70.99	OK	17860	2026-09-22 20:14	72.68	OK
17861	2026-09-22 20:15	72.47	OK	17862	2026-09-22 20:16	74.53	OK
17863	2026-09-22 20:17	73.13	OK	17864	2026-09-22 20:18	73.95	OK
17865	2026-09-22 20:19	70.17	OK	17866	2026-09-22 20:20	71.68	OK
17867	2026-09-22 20:21	73.27	OK	17868	2026-09-22 20:22	76.81	OK
17869	2026-09-22 20:23	71.63	OK	17870	2026-09-22 20:24	72.35	OK
17871	2026-09-22 20:25	73.21	OK	17872	2026-09-22 20:26	77.17	OK
17873	2026-09-22 20:27	71.79	OK	17874	2026-09-22 20:28	74.68	OK
17875	2026-09-22 20:29	74.16	OK	17876	2026-09-22 20:30	73.30	OK
17877	2026-09-22 20:31	72.34	OK	17878	2026-09-22 20:32	71.24	OK
17879	2026-09-22 20:33	71.74	OK	17880	2026-09-22 20:34	70.96	OK
17881	2026-09-22 20:35	71.18	OK	17882	2026-09-22 20:36	71.13	OK
17883	2026-09-22 20:37	70.70	OK	17884	2026-09-22 20:38	73.96	OK
17885	2026-09-22 20:39	73.14	OK	17886	2026-09-22 20:40	73.41	OK
17887	2026-09-22 20:41	72.80	OK	17888	2026-09-22 20:42	72.28	OK
17889	2026-09-22 20:43	74.51	OK	17890	2026-09-22 20:44	74.04	OK
17891	2026-09-22 20:45	73.58	OK	17892	2026-09-22 20:46	73.14	OK
17893	2026-09-22 20:47	70.50	OK	17894	2026-09-22 20:48	72.41	OK
17895	2026-09-22 20:49	73.08	OK	17896	2026-09-22 20:50	75.11	OK
17897	2026-09-22 20:51	72.83	OK	17898	2026-09-22 20:52	74.21	OK
17899	2026-09-22 20:53	70.19	OK	17900	2026-09-22 20:54	72.40	OK
17901	2026-09-22 20:55	73.72	OK	17902	2026-09-22 20:56	73.55	OK
17903	2026-09-22 20:57	73.59	OK	17904	2026-09-22 20:58	70.77	OK
17905	2026-09-22 20:59	73.94	OK	17906	2026-09-22 21:00	71.44	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17907	2026-09-22 21:01	71.94	OK	17908	2026-09-22 21:02	70.19	OK
17909	2026-09-22 21:03	73.16	OK	17910	2026-09-22 21:04	73.01	OK
17911	2026-09-22 21:05	74.44	OK	17912	2026-09-22 21:06	72.34	OK
17913	2026-09-22 21:07	74.65	OK	17914	2026-09-22 21:08	68.94	OK
17915	2026-09-22 21:09	70.52	OK	17916	2026-09-22 21:10	71.67	OK
17917	2026-09-22 21:11	71.05	OK	17918	2026-09-22 21:12	70.82	OK
17919	2026-09-22 21:13	73.80	OK	17920	2026-09-22 21:14	71.07	OK
17921	2026-09-22 21:15	72.16	OK	17922	2026-09-22 21:16	72.79	OK
17923	2026-09-22 21:17	69.99	OK	17924	2026-09-22 21:18	74.22	OK
17925	2026-09-22 21:19	73.01	OK	17926	2026-09-22 21:20	74.16	OK
17927	2026-09-22 21:21	74.85	OK	17928	2026-09-22 21:22	71.62	OK
17929	2026-09-22 21:23	72.70	OK	17930	2026-09-22 21:24	72.18	OK
17931	2026-09-22 21:25	75.14	OK	17932	2026-09-22 21:26	70.10	OK
17933	2026-09-22 21:27	69.59	OK	17934	2026-09-22 21:28	73.03	OK
17935	2026-09-22 21:29	69.56	OK	17936	2026-09-22 21:30	70.87	OK
17937	2026-09-22 21:31	70.88	OK	17938	2026-09-22 21:32	72.23	OK
17939	2026-09-22 21:33	71.45	OK	17940	2026-09-22 21:34	73.96	OK
17941	2026-09-22 21:35	72.27	OK	17942	2026-09-22 21:36	71.84	OK
17943	2026-09-22 21:37	72.63	OK	17944	2026-09-22 21:38	71.38	OK
17945	2026-09-22 21:39	70.62	OK	17946	2026-09-22 21:40	70.62	OK
17947	2026-09-22 21:41	71.00	OK	17948	2026-09-22 21:42	72.86	OK
17949	2026-09-22 21:43	70.42	OK	17950	2026-09-22 21:44	68.78	OK
17951	2026-09-22 21:45	69.38	OK	17952	2026-09-22 21:46	72.92	OK
17953	2026-09-22 21:47	72.95	OK	17954	2026-09-22 21:48	70.76	OK
17955	2026-09-22 21:49	69.50	OK	17956	2026-09-22 21:50	70.23	OK
17957	2026-09-22 21:51	71.87	OK	17958	2026-09-22 21:52	69.29	OK
17959	2026-09-22 21:53	72.13	OK	17960	2026-09-22 21:54	68.50	OK
17961	2026-09-22 21:55	70.89	OK	17962	2026-09-22 21:56	71.69	OK
17963	2026-09-22 21:57	71.26	OK	17964	2026-09-22 21:58	74.20	OK
17965	2026-09-22 21:59	72.48	OK	17966	2026-09-22 22:00	67.85	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17967	2026-09-22 22:01	70.28	OK	17968	2026-09-22 22:02	68.48	OK
17969	2026-09-22 22:03	70.93	OK	17970	2026-09-22 22:04	72.71	OK
17971	2026-09-22 22:05	74.20	OK	17972	2026-09-22 22:06	69.42	OK
17973	2026-09-22 22:07	70.24	OK	17974	2026-09-22 22:08	70.00	OK
17975	2026-09-22 22:09	70.85	OK	17976	2026-09-22 22:10	69.43	OK
17977	2026-09-22 22:11	72.28	OK	17978	2026-09-22 22:12	71.03	OK
17979	2026-09-22 22:13	67.68	OK	17980	2026-09-22 22:14	71.72	OK
17981	2026-09-22 22:15	73.39	OK	17982	2026-09-22 22:16	73.22	OK
17983	2026-09-22 22:17	66.81	OK	17984	2026-09-22 22:18	70.24	OK
17985	2026-09-22 22:19	67.25	OK	17986	2026-09-22 22:20	70.45	OK
17987	2026-09-22 22:21	72.63	OK	17988	2026-09-22 22:22	70.42	OK
17989	2026-09-22 22:23	71.73	OK	17990	2026-09-22 22:24	68.18	OK
17991	2026-09-22 22:25	73.68	OK	17992	2026-09-22 22:26	71.01	OK
17993	2026-09-22 22:27	71.20	OK	17994	2026-09-22 22:28	71.01	OK
17995	2026-09-22 22:29	70.14	OK	17996	2026-09-22 22:30	70.00	OK
17997	2026-09-22 22:31	71.36	OK	17998	2026-09-22 22:32	72.61	OK
17999	2026-09-22 22:33	72.52	OK	18000	2026-09-22 22:34	69.63	OK
18001	2026-09-22 22:35	69.67	OK	18002	2026-09-22 22:36	71.11	OK
18003	2026-09-22 22:37	70.68	OK	18004	2026-09-22 22:38	71.91	OK
18005	2026-09-22 22:39	67.98	OK	18006	2026-09-22 22:40	71.21	OK
18007	2026-09-22 22:41	68.03	OK	18008	2026-09-22 22:42	68.45	OK
18009	2026-09-22 22:43	71.63	OK	18010	2026-09-22 22:44	68.28	OK
18011	2026-09-22 22:45	68.73	OK	18012	2026-09-22 22:46	68.08	OK
18013	2026-09-22 22:47	68.60	OK	18014	2026-09-22 22:48	66.70	OK
18015	2026-09-22 22:49	69.11	OK	18016	2026-09-22 22:50	69.00	OK
18017	2026-09-22 22:51	73.81	OK	18018	2026-09-22 22:52	72.74	OK
18019	2026-09-22 22:53	70.84	OK	18020	2026-09-22 22:54	70.29	OK
18021	2026-09-22 22:55	68.81	OK	18022	2026-09-22 22:56	68.73	OK
18023	2026-09-22 22:57	69.48	OK	18024	2026-09-22 22:58	68.98	OK
18025	2026-09-22 22:59	71.82	OK	18026	2026-09-22 23:00	72.25	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18027	2026-09-22 23:01	68.97	OK	18028	2026-09-22 23:02	72.04	OK
18029	2026-09-22 23:03	72.39	OK	18030	2026-09-22 23:04	69.18	OK
18031	2026-09-22 23:05	69.20	OK	18032	2026-09-22 23:06	70.06	OK
18033	2026-09-22 23:07	72.43	OK	18034	2026-09-22 23:08	67.92	OK
18035	2026-09-22 23:09	70.27	OK	18036	2026-09-22 23:10	71.25	OK
18037	2026-09-22 23:11	71.06	OK	18038	2026-09-22 23:12	67.65	OK
18039	2026-09-22 23:13	69.63	OK	18040	2026-09-22 23:14	71.62	OK
18041	2026-09-22 23:15	71.51	OK	18042	2026-09-22 23:16	68.09	OK
18043	2026-09-22 23:17	70.19	OK	18044	2026-09-22 23:18	67.37	OK
18045	2026-09-22 23:19	67.73	OK	18046	2026-09-22 23:20	68.20	OK
18047	2026-09-22 23:21	68.45	OK	18048	2026-09-22 23:22	66.51	OK
18049	2026-09-22 23:23	68.35	OK	18050	2026-09-22 23:24	69.03	OK
18051	2026-09-22 23:25	69.41	OK	18052	2026-09-22 23:26	67.07	OK
18053	2026-09-22 23:27	68.09	OK	18054	2026-09-22 23:28	68.76	OK
18055	2026-09-22 23:29	69.81	OK	18056	2026-09-22 23:30	68.98	OK
18057	2026-09-22 23:31	68.74	OK	18058	2026-09-22 23:32	69.74	OK
18059	2026-09-22 23:33	71.81	OK	18060	2026-09-22 23:34	67.27	OK
18061	2026-09-22 23:35	70.43	OK	18062	2026-09-22 23:36	70.51	OK
18063	2026-09-22 23:37	68.36	OK	18064	2026-09-22 23:38	70.74	OK
18065	2026-09-22 23:39	70.31	OK	18066	2026-09-22 23:40	70.04	OK
18067	2026-09-22 23:41	71.93	OK	18068	2026-09-22 23:42	73.27	OK
18069	2026-09-22 23:43	71.19	OK	18070	2026-09-22 23:44	68.88	OK
18071	2026-09-22 23:45	69.83	OK	18072	2026-09-22 23:46	68.52	OK
18073	2026-09-22 23:47	71.73	OK	18074	2026-09-22 23:48	69.82	OK
18075	2026-09-22 23:49	66.48	OK	18076	2026-09-22 23:50	68.25	OK
18077	2026-09-22 23:51	71.09	OK	18078	2026-09-22 23:52	68.76	OK
18079	2026-09-22 23:53	71.69	OK	18080	2026-09-22 23:54	68.28	OK
18081	2026-09-22 23:55	70.21	OK	18082	2026-09-22 23:56	69.47	OK
18083	2026-09-22 23:57	72.77	OK	18084	2026-09-22 23:58	70.42	OK
18085	2026-09-22 23:59	72.65	OK	18086	2026-09-23 00:00	69.82	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18087	2026-09-23 00:01	68.15	OK	18088	2026-09-23 00:02	71.56	OK
18089	2026-09-23 00:03	72.07	OK	18090	2026-09-23 00:04	71.09	OK
18091	2026-09-23 00:05	72.66	OK	18092	2026-09-23 00:06	70.40	OK
18093	2026-09-23 00:07	69.50	OK	18094	2026-09-23 00:08	67.16	OK
18095	2026-09-23 00:09	68.69	OK	18096	2026-09-23 00:10	69.35	OK
18097	2026-09-23 00:11	69.26	OK	18098	2026-09-23 00:12	70.58	OK
18099	2026-09-23 00:13	72.27	OK	18100	2026-09-23 00:14	68.55	OK
18101	2026-09-23 00:15	68.97	OK	18102	2026-09-23 00:16	68.65	OK
18103	2026-09-23 00:17	68.64	OK	18104	2026-09-23 00:18	72.53	OK
18105	2026-09-23 00:19	69.48	OK	18106	2026-09-23 00:20	70.58	OK
18107	2026-09-23 00:21	67.04	OK	18108	2026-09-23 00:22	73.12	OK
18109	2026-09-23 00:23	66.83	OK	18110	2026-09-23 00:24	70.93	OK
18111	2026-09-23 00:25	68.54	OK	18112	2026-09-23 00:26	66.64	OK
18113	2026-09-23 00:27	68.15	OK	18114	2026-09-23 00:28	72.65	OK
18115	2026-09-23 00:29	67.74	OK	18116	2026-09-23 00:30	67.78	OK
18117	2026-09-23 00:31	71.14	OK	18118	2026-09-23 00:32	68.51	OK
18119	2026-09-23 00:33	68.85	OK	18120	2026-09-23 00:34	68.52	OK
18121	2026-09-23 00:35	69.57	OK	18122	2026-09-23 00:36	67.81	OK
18123	2026-09-23 00:37	70.69	OK	18124	2026-09-23 00:38	68.92	OK
18125	2026-09-23 00:39	69.60	OK	18126	2026-09-23 00:40	66.32	OK
18127	2026-09-23 00:41	67.72	OK	18128	2026-09-23 00:42	70.64	OK
18129	2026-09-23 00:43	69.88	OK	18130	2026-09-23 00:44	69.78	OK
18131	2026-09-23 00:45	67.64	OK	18132	2026-09-23 00:46	67.04	OK
18133	2026-09-23 00:47	68.41	OK	18134	2026-09-23 00:48	67.87	OK
18135	2026-09-23 00:49	70.70	OK	18136	2026-09-23 00:50	69.20	OK
18137	2026-09-23 00:51	69.24	OK	18138	2026-09-23 00:52	69.75	OK
18139	2026-09-23 00:53	68.32	OK	18140	2026-09-23 00:54	67.98	OK
18141	2026-09-23 00:55	66.77	OK	18142	2026-09-23 00:56	71.05	OK
18143	2026-09-23 00:57	70.70	OK	18144	2026-09-23 00:58	69.08	OK
18145	2026-09-23 00:59	71.62	OK	18146	2026-09-23 01:00	69.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18147	2026-09-23 01:01	66.10	OK	18148	2026-09-23 01:02	70.48	OK
18149	2026-09-23 01:03	66.75	OK	18150	2026-09-23 01:04	69.16	OK
18151	2026-09-23 01:05	70.34	OK	18152	2026-09-23 01:06	66.02	OK
18153	2026-09-23 01:07	68.48	OK	18154	2026-09-23 01:08	70.68	OK
18155	2026-09-23 01:09	67.40	OK	18156	2026-09-23 01:10	69.85	OK
18157	2026-09-23 01:11	67.61	OK	18158	2026-09-23 01:12	71.92	OK
18159	2026-09-23 01:13	67.91	OK	18160	2026-09-23 01:14	68.79	OK
18161	2026-09-23 01:15	68.24	OK	18162	2026-09-23 01:16	68.12	OK
18163	2026-09-23 01:17	70.23	OK	18164	2026-09-23 01:18	68.96	OK
18165	2026-09-23 01:19	65.26	OK	18166	2026-09-23 01:20	69.13	OK
18167	2026-09-23 01:21	67.68	OK	18168	2026-09-23 01:22	67.92	OK
18169	2026-09-23 01:23	70.38	OK	18170	2026-09-23 01:24	68.00	OK
18171	2026-09-23 01:25	69.39	OK	18172	2026-09-23 01:26	67.83	OK
18173	2026-09-23 01:27	67.23	OK	18174	2026-09-23 01:28	68.56	OK
18175	2026-09-23 01:29	70.16	OK	18176	2026-09-23 01:30	70.77	OK
18177	2026-09-23 01:31	70.19	OK	18178	2026-09-23 01:32	68.62	OK
18179	2026-09-23 01:33	68.41	OK	18180	2026-09-23 01:34	68.04	OK
18181	2026-09-23 01:35	66.52	OK	18182	2026-09-23 01:36	71.40	OK
18183	2026-09-23 01:37	67.99	OK	18184	2026-09-23 01:38	66.89	OK
18185	2026-09-23 01:39	68.67	OK	18186	2026-09-23 01:40	68.34	OK
18187	2026-09-23 01:41	68.58	OK	18188	2026-09-23 01:42	69.58	OK
18189	2026-09-23 01:43	69.37	OK	18190	2026-09-23 01:44	70.94	OK
18191	2026-09-23 01:45	66.86	OK	18192	2026-09-23 01:46	69.11	OK
18193	2026-09-23 01:47	69.70	OK	18194	2026-09-23 01:48	69.61	OK
18195	2026-09-23 01:49	69.94	OK	18196	2026-09-23 01:50	69.26	OK
18197	2026-09-23 01:51	68.26	OK	18198	2026-09-23 01:52	69.72	OK
18199	2026-09-23 01:53	69.00	OK	18200	2026-09-23 01:54	72.18	OK
18201	2026-09-23 01:55	68.24	OK	18202	2026-09-23 01:56	70.91	OK
18203	2026-09-23 01:57	71.57	OK	18204	2026-09-23 01:58	65.53	OK
18205	2026-09-23 01:59	69.86	OK	18206	2026-09-23 02:00	69.52	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18207	2026-09-23 02:01	68.87	OK	18208	2026-09-23 02:02	68.36	OK
18209	2026-09-23 02:03	69.97	OK	18210	2026-09-23 02:04	70.86	OK
18211	2026-09-23 02:05	70.95	OK	18212	2026-09-23 02:06	70.73	OK
18213	2026-09-23 02:07	69.24	OK	18214	2026-09-23 02:08	68.92	OK
18215	2026-09-23 02:09	70.17	OK	18216	2026-09-23 02:10	69.26	OK
18217	2026-09-23 02:11	67.70	OK	18218	2026-09-23 02:12	72.10	OK
18219	2026-09-23 02:13	69.86	OK	18220	2026-09-23 02:14	69.94	OK
18221	2026-09-23 02:15	69.04	OK	18222	2026-09-23 02:16	71.14	OK
18223	2026-09-23 02:17	68.56	OK	18224	2026-09-23 02:18	67.49	OK
18225	2026-09-23 02:19	72.11	OK	18226	2026-09-23 02:20	72.15	OK
18227	2026-09-23 02:21	72.84	OK	18228	2026-09-23 02:22	72.14	OK
18229	2026-09-23 02:23	70.81	OK	18230	2026-09-23 02:24	69.03	OK
18231	2026-09-23 02:25	68.97	OK	18232	2026-09-23 02:26	68.49	OK
18233	2026-09-23 02:27	69.58	OK	18234	2026-09-23 02:28	70.07	OK
18235	2026-09-23 02:29	69.99	OK	18236	2026-09-23 02:30	70.55	OK
18237	2026-09-23 02:31	69.89	OK	18238	2026-09-23 02:32	67.63	OK
18239	2026-09-23 02:33	69.41	OK	18240	2026-09-23 02:34	70.08	OK
18241	2026-09-23 02:35	69.72	OK	18242	2026-09-23 02:36	71.62	OK
18243	2026-09-23 02:37	69.41	OK	18244	2026-09-23 02:38	69.76	OK
18245	2026-09-23 02:39	71.21	OK	18246	2026-09-23 02:40	74.47	OK
18247	2026-09-23 02:41	68.84	OK	18248	2026-09-23 02:42	68.87	OK
18249	2026-09-23 02:43	68.00	OK	18250	2026-09-23 02:44	67.06	OK
18251	2026-09-23 02:45	69.62	OK	18252	2026-09-23 02:46	71.65	OK
18253	2026-09-23 02:47	71.19	OK	18254	2026-09-23 02:48	72.75	OK
18255	2026-09-23 02:49	71.38	OK	18256	2026-09-23 02:50	74.17	OK
18257	2026-09-23 02:51	72.57	OK	18258	2026-09-23 02:52	70.05	OK
18259	2026-09-23 02:53	72.82	OK	18260	2026-09-23 02:54	71.25	OK
18261	2026-09-23 02:55	73.45	OK	18262	2026-09-23 02:56	68.66	OK
18263	2026-09-23 02:57	70.86	OK	18264	2026-09-23 02:58	69.54	OK
18265	2026-09-23 02:59	67.36	OK	18266	2026-09-23 03:00	72.23	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18267	2026-09-23 03:01	70.87	OK	18268	2026-09-23 03:02	72.05	OK
18269	2026-09-23 03:03	73.97	OK	18270	2026-09-23 03:04	69.55	OK
18271	2026-09-23 03:05	68.80	OK	18272	2026-09-23 03:06	72.01	OK
18273	2026-09-23 03:07	66.83	OK	18274	2026-09-23 03:08	71.39	OK
18275	2026-09-23 03:09	70.84	OK	18276	2026-09-23 03:10	71.44	OK
18277	2026-09-23 03:11	72.33	OK	18278	2026-09-23 03:12	67.81	OK
18279	2026-09-23 03:13	72.79	OK	18280	2026-09-23 03:14	68.98	OK
18281	2026-09-23 03:15	71.86	OK	18282	2026-09-23 03:16	73.14	OK
18283	2026-09-23 03:17	66.85	OK	18284	2026-09-23 03:18	72.54	OK
18285	2026-09-23 03:19	72.20	OK	18286	2026-09-23 03:20	71.53	OK
18287	2026-09-23 03:21	70.05	OK	18288	2026-09-23 03:22	68.43	OK
18289	2026-09-23 03:23	70.89	OK	18290	2026-09-23 03:24	71.64	OK
18291	2026-09-23 03:25	69.79	OK	18292	2026-09-23 03:26	69.72	OK
18293	2026-09-23 03:27	70.21	OK	18294	2026-09-23 03:28	69.36	OK
18295	2026-09-23 03:29	69.67	OK	18296	2026-09-23 03:30	72.71	OK
18297	2026-09-23 03:31	71.01	OK	18298	2026-09-23 03:32	72.66	OK
18299	2026-09-23 03:33	70.64	OK	18300	2026-09-23 03:34	71.27	OK
18301	2026-09-23 03:35	70.32	OK	18302	2026-09-23 03:36	68.42	OK
18303	2026-09-23 03:37	70.35	OK	18304	2026-09-23 03:38	68.59	OK
18305	2026-09-23 03:39	72.06	OK	18306	2026-09-23 03:40	72.21	OK
18307	2026-09-23 03:41	69.61	OK	18308	2026-09-23 03:42	72.23	OK
18309	2026-09-23 03:43	70.38	OK	18310	2026-09-23 03:44	72.53	OK
18311	2026-09-23 03:45	72.35	OK	18312	2026-09-23 03:46	68.69	OK
18313	2026-09-23 03:47	69.78	OK	18314	2026-09-23 03:48	70.44	OK
18315	2026-09-23 03:49	69.72	OK	18316	2026-09-23 03:50	67.33	OK
18317	2026-09-23 03:51	69.88	OK	18318	2026-09-23 03:52	72.27	OK
18319	2026-09-23 03:53	72.46	OK	18320	2026-09-23 03:54	70.40	OK
18321	2026-09-23 03:55	70.50	OK	18322	2026-09-23 03:56	72.09	OK
18323	2026-09-23 03:57	68.59	OK	18324	2026-09-23 03:58	71.91	OK
18325	2026-09-23 03:59	70.04	OK	18326	2026-09-23 04:00	73.27	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18327	2026-09-23 04:01	70.53	OK	18328	2026-09-23 04:02	74.74	OK
18329	2026-09-23 04:03	73.84	OK	18330	2026-09-23 04:04	74.60	OK
18331	2026-09-23 04:05	72.75	OK	18332	2026-09-23 04:06	71.07	OK
18333	2026-09-23 04:07	72.03	OK	18334	2026-09-23 04:08	69.61	OK
18335	2026-09-23 04:09	70.67	OK	18336	2026-09-23 04:10	70.88	OK
18337	2026-09-23 04:11	71.78	OK	18338	2026-09-23 04:12	70.48	OK
18339	2026-09-23 04:13	74.15	OK	18340	2026-09-23 04:14	72.28	OK
18341	2026-09-23 04:15	72.75	OK	18342	2026-09-23 04:16	71.50	OK
18343	2026-09-23 04:17	69.77	OK	18344	2026-09-23 04:18	71.32	OK
18345	2026-09-23 04:19	67.84	OK	18346	2026-09-23 04:20	70.43	OK
18347	2026-09-23 04:21	72.91	OK	18348	2026-09-23 04:22	71.37	OK
18349	2026-09-23 04:23	71.32	OK	18350	2026-09-23 04:24	71.42	OK
18351	2026-09-23 04:25	74.27	OK	18352	2026-09-23 04:26	68.52	OK
18353	2026-09-23 04:27	72.62	OK	18354	2026-09-23 04:28	73.66	OK
18355	2026-09-23 04:29	72.95	OK	18356	2026-09-23 04:30	70.57	OK
18357	2026-09-23 04:31	70.77	OK	18358	2026-09-23 04:32	73.85	OK
18359	2026-09-23 04:33	73.19	OK	18360	2026-09-23 04:34	70.65	OK
18361	2026-09-23 04:35	74.73	OK	18362	2026-09-23 04:36	70.26	OK
18363	2026-09-23 04:37	71.73	OK	18364	2026-09-23 04:38	73.06	OK
18365	2026-09-23 04:39	68.99	OK	18366	2026-09-23 04:40	75.27	OK
18367	2026-09-23 04:41	70.96	OK	18368	2026-09-23 04:42	74.99	OK
18369	2026-09-23 04:43	73.02	OK	18370	2026-09-23 04:44	69.94	OK
18371	2026-09-23 04:45	70.81	OK	18372	2026-09-23 04:46	70.68	OK
18373	2026-09-23 04:47	72.62	OK	18374	2026-09-23 04:48	75.05	OK
18375	2026-09-23 04:49	72.52	OK	18376	2026-09-23 04:50	70.60	OK
18377	2026-09-23 04:51	72.50	OK	18378	2026-09-23 04:52	70.36	OK
18379	2026-09-23 04:53	72.33	OK	18380	2026-09-23 04:54	74.28	OK
18381	2026-09-23 04:55	71.25	OK	18382	2026-09-23 04:56	72.09	OK
18383	2026-09-23 04:57	74.68	OK	18384	2026-09-23 04:58	73.94	OK
18385	2026-09-23 04:59	74.26	OK	18386	2026-09-23 05:00	72.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18387	2026-09-23 05:01	73.01	OK	18388	2026-09-23 05:02	73.61	OK
18389	2026-09-23 05:03	72.65	OK	18390	2026-09-23 05:04	71.38	OK
18391	2026-09-23 05:05	73.60	OK	18392	2026-09-23 05:06	74.81	OK
18393	2026-09-23 05:07	72.26	OK	18394	2026-09-23 05:08	73.03	OK
18395	2026-09-23 05:09	70.50	OK	18396	2026-09-23 05:10	72.00	OK
18397	2026-09-23 05:11	69.92	OK	18398	2026-09-23 05:12	70.22	OK
18399	2026-09-23 05:13	71.38	OK	18400	2026-09-23 05:14	70.44	OK
18401	2026-09-23 05:15	74.73	OK	18402	2026-09-23 05:16	73.38	OK
18403	2026-09-23 05:17	72.01	OK	18404	2026-09-23 05:18	72.84	OK
18405	2026-09-23 05:19	71.40	OK	18406	2026-09-23 05:20	74.90	OK
18407	2026-09-23 05:21	74.76	OK	18408	2026-09-23 05:22	72.84	OK
18409	2026-09-23 05:23	69.81	OK	18410	2026-09-23 05:24	72.50	OK
18411	2026-09-23 05:25	72.82	OK	18412	2026-09-23 05:26	72.76	OK
18413	2026-09-23 05:27	71.08	OK	18414	2026-09-23 05:28	74.33	OK
18415	2026-09-23 05:29	71.61	OK	18416	2026-09-23 05:30	75.28	OK
18417	2026-09-23 05:31	72.35	OK	18418	2026-09-23 05:32	73.99	OK
18419	2026-09-23 05:33	72.29	OK	18420	2026-09-23 05:34	70.98	OK
18421	2026-09-23 05:35	71.23	OK	18422	2026-09-23 05:36	70.99	OK
18423	2026-09-23 05:37	72.21	OK	18424	2026-09-23 05:38	75.11	OK
18425	2026-09-23 05:39	72.74	OK	18426	2026-09-23 05:40	74.53	OK
18427	2026-09-23 05:41	70.40	OK	18428	2026-09-23 05:42	73.95	OK
18429	2026-09-23 05:43	74.71	OK	18430	2026-09-23 05:44	75.98	OK
18431	2026-09-23 05:45	73.35	OK	18432	2026-09-23 05:46	73.08	OK
18433	2026-09-23 05:47	72.37	OK	18434	2026-09-23 05:48	71.87	OK
18435	2026-09-23 05:49	75.17	OK	18436	2026-09-23 05:50	70.37	OK
18437	2026-09-23 05:51	73.90	OK	18438	2026-09-23 05:52	72.17	OK
18439	2026-09-23 05:53	72.97	OK	18440	2026-09-23 05:54	75.62	OK
18441	2026-09-23 05:55	73.75	OK	18442	2026-09-23 05:56	73.82	OK
18443	2026-09-23 05:57	72.66	OK	18444	2026-09-23 05:58	73.45	OK
18445	2026-09-23 05:59	73.36	OK	18446	2026-09-23 06:00	75.06	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18447	2026-09-23 06:01	74.04	OK	18448	2026-09-23 06:02	74.17	OK
18449	2026-09-23 06:03	72.64	OK	18450	2026-09-23 06:04	74.52	OK
18451	2026-09-23 06:05	71.82	OK	18452	2026-09-23 06:06	75.80	OK
18453	2026-09-23 06:07	75.25	OK	18454	2026-09-23 06:08	75.80	OK
18455	2026-09-23 06:09	72.16	OK	18456	2026-09-23 06:10	76.86	OK
18457	2026-09-23 06:11	73.81	OK	18458	2026-09-23 06:12	73.14	OK
18459	2026-09-23 06:13	73.97	OK	18460	2026-09-23 06:14	71.49	OK
18461	2026-09-23 06:15	76.57	OK	18462	2026-09-23 06:16	73.54	OK
18463	2026-09-23 06:17	72.47	OK	18464	2026-09-23 06:18	76.29	OK
18465	2026-09-23 06:19	76.11	OK	18466	2026-09-23 06:20	75.40	OK
18467	2026-09-23 06:21	71.66	OK	18468	2026-09-23 06:22	76.57	OK
18469	2026-09-23 06:23	74.22	OK	18470	2026-09-23 06:24	72.73	OK
18471	2026-09-23 06:25	73.91	OK	18472	2026-09-23 06:26	72.89	OK
18473	2026-09-23 06:27	73.39	OK	18474	2026-09-23 06:28	73.90	OK
18475	2026-09-23 06:29	75.93	OK	18476	2026-09-23 06:30	76.99	OK
18477	2026-09-23 06:31	75.93	OK	18478	2026-09-23 06:32	75.67	OK
18479	2026-09-23 06:33	71.18	OK	18480	2026-09-23 06:34	75.21	OK
18481	2026-09-23 06:35	75.51	OK	18482	2026-09-23 06:36	74.89	OK
18483	2026-09-23 06:37	74.81	OK	18484	2026-09-23 06:38	71.87	OK
18485	2026-09-23 06:39	76.28	OK	18486	2026-09-23 06:40	77.46	OK
18487	2026-09-23 06:41	76.88	OK	18488	2026-09-23 06:42	74.14	OK
18489	2026-09-23 06:43	76.51	OK	18490	2026-09-23 06:44	75.79	OK
18491	2026-09-23 06:45	74.97	OK	18492	2026-09-23 06:46	77.29	OK
18493	2026-09-23 06:47	72.97	OK	18494	2026-09-23 06:48	73.83	OK
18495	2026-09-23 06:49	74.99	OK	18496	2026-09-23 06:50	72.12	OK
18497	2026-09-23 06:51	77.13	OK	18498	2026-09-23 06:52	76.31	OK
18499	2026-09-23 06:53	76.54	OK	18500	2026-09-23 06:54	75.74	OK
18501	2026-09-23 06:55	75.08	OK	18502	2026-09-23 06:56	74.56	OK
18503	2026-09-23 06:57	76.54	OK	18504	2026-09-23 06:58	76.63	OK
18505	2026-09-23 06:59	73.99	OK	18506	2026-09-23 07:00	77.01	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18507	2026-09-23 07:01	74.82	OK	18508	2026-09-23 07:02	77.18	OK
18509	2026-09-23 07:03	75.02	OK	18510	2026-09-23 07:04	71.41	OK
18511	2026-09-23 07:05	73.35	OK	18512	2026-09-23 07:06	76.21	OK
18513	2026-09-23 07:07	74.28	OK	18514	2026-09-23 07:08	75.90	OK
18515	2026-09-23 07:09	74.71	OK	18516	2026-09-23 07:10	73.96	OK
18517	2026-09-23 07:11	77.91	OK	18518	2026-09-23 07:12	76.21	OK
18519	2026-09-23 07:13	76.17	OK	18520	2026-09-23 07:14	73.93	OK
18521	2026-09-23 07:15	75.52	OK	18522	2026-09-23 07:16	78.95	OK
18523	2026-09-23 07:17	80.08	OK	18524	2026-09-23 07:18	74.76	OK
18525	2026-09-23 07:19	77.87	OK	18526	2026-09-23 07:20	74.58	OK
18527	2026-09-23 07:21	76.95	OK	18528	2026-09-23 07:22	75.26	OK
18529	2026-09-23 07:23	72.29	OK	18530	2026-09-23 07:24	75.84	OK
18531	2026-09-23 07:25	75.36	OK	18532	2026-09-23 07:26	79.31	OK
18533	2026-09-23 07:27	77.86	OK	18534	2026-09-23 07:28	74.84	OK
18535	2026-09-23 07:29	78.07	OK	18536	2026-09-23 07:30	77.46	OK
18537	2026-09-23 07:31	78.32	OK	18538	2026-09-23 07:32	75.89	OK
18539	2026-09-23 07:33	73.97	OK	18540	2026-09-23 07:34	73.84	OK
18541	2026-09-23 07:35	77.49	OK	18542	2026-09-23 07:36	76.36	OK
18543	2026-09-23 07:37	77.95	OK	18544	2026-09-23 07:38	73.58	OK
18545	2026-09-23 07:39	77.15	OK	18546	2026-09-23 07:40	74.80	OK
18547	2026-09-23 07:41	75.87	OK	18548	2026-09-23 07:42	76.03	OK
18549	2026-09-23 07:43	76.44	OK	18550	2026-09-23 07:44	78.04	OK
18551	2026-09-23 07:45	74.87	OK	18552	2026-09-23 07:46	75.62	OK
18553	2026-09-23 07:47	74.87	OK	18554	2026-09-23 07:48	74.86	OK
18555	2026-09-23 07:49	75.74	OK	18556	2026-09-23 07:50	76.13	OK
18557	2026-09-23 07:51	76.76	OK	18558	2026-09-23 07:52	79.39	OK
18559	2026-09-23 07:53	80.83	OK	18560	2026-09-23 07:54	77.32	OK
18561	2026-09-23 07:55	76.35	OK	18562	2026-09-23 07:56	78.12	OK
18563	2026-09-23 07:57	75.92	OK	18564	2026-09-23 07:58	75.92	OK
18565	2026-09-23 07:59	78.65	OK	18566	2026-09-23 08:00	75.21	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18567	2026-09-23 08:01	78.10	OK	18568	2026-09-23 08:02	76.30	OK
18569	2026-09-23 08:03	76.66	OK	18570	2026-09-23 08:04	77.91	OK
18571	2026-09-23 08:05	75.15	OK	18572	2026-09-23 08:06	77.11	OK
18573	2026-09-23 08:07	76.85	OK	18574	2026-09-23 08:08	76.11	OK
18575	2026-09-23 08:09	76.88	OK	18576	2026-09-23 08:10	76.39	OK
18577	2026-09-23 08:11	76.73	OK	18578	2026-09-23 08:12	74.14	OK
18579	2026-09-23 08:13	77.35	OK	18580	2026-09-23 08:14	77.62	OK
18581	2026-09-23 08:15	78.15	OK	18582	2026-09-23 08:16	79.54	OK
18583	2026-09-23 08:17	74.43	OK	18584	2026-09-23 08:18	77.43	OK
18585	2026-09-23 08:19	78.49	OK	18586	2026-09-23 08:20	77.86	OK
18587	2026-09-23 08:21	77.09	OK	18588	2026-09-23 08:22	74.45	OK
18589	2026-09-23 08:23	79.87	OK	18590	2026-09-23 08:24	79.09	OK
18591	2026-09-23 08:25	74.05	OK	18592	2026-09-23 08:26	77.48	OK
18593	2026-09-23 08:27	80.48	OK	18594	2026-09-23 08:28	75.98	OK
18595	2026-09-23 08:29	76.71	OK	18596	2026-09-23 08:30	79.92	OK
18597	2026-09-23 08:31	77.03	OK	18598	2026-09-23 08:32	76.84	OK
18599	2026-09-23 08:33	76.19	OK	18600	2026-09-23 08:34	80.52	OK
18601	2026-09-23 08:35	78.39	OK	18602	2026-09-23 08:36	81.68	OK
18603	2026-09-23 08:37	77.98	OK	18604	2026-09-23 08:38	77.27	OK
18605	2026-09-23 08:39	75.01	OK	18606	2026-09-23 08:40	79.24	OK
18607	2026-09-23 08:41	77.94	OK	18608	2026-09-23 08:42	77.73	OK
18609	2026-09-23 08:43	76.50	OK	18610	2026-09-23 08:44	74.89	OK
18611	2026-09-23 08:45	76.01	OK	18612	2026-09-23 08:46	77.81	OK
18613	2026-09-23 08:47	77.90	OK	18614	2026-09-23 08:48	78.25	OK
18615	2026-09-23 08:49	76.88	OK	18616	2026-09-23 08:50	76.25	OK
18617	2026-09-23 08:51	79.18	OK	18618	2026-09-23 08:52	79.54	OK
18619	2026-09-23 08:53	77.23	OK	18620	2026-09-23 08:54	78.43	OK
18621	2026-09-23 08:55	78.66	OK	18622	2026-09-23 08:56	74.95	OK
18623	2026-09-23 08:57	80.68	OK	18624	2026-09-23 08:58	77.64	OK
18625	2026-09-23 08:59	77.94	OK	18626	2026-09-23 09:00	75.62	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18627	2026-09-23 09:01	78.54	OK	18628	2026-09-23 09:02	77.73	OK
18629	2026-09-23 09:03	80.20	OK	18630	2026-09-23 09:04	81.45	OK
18631	2026-09-23 09:05	75.49	OK	18632	2026-09-23 09:06	76.97	OK
18633	2026-09-23 09:07	77.98	OK	18634	2026-09-23 09:08	80.15	OK
18635	2026-09-23 09:09	77.85	OK	18636	2026-09-23 09:10	76.34	OK
18637	2026-09-23 09:11	74.28	OK	18638	2026-09-23 09:12	79.80	OK
18639	2026-09-23 09:13	81.35	OK	18640	2026-09-23 09:14	77.00	OK
18641	2026-09-23 09:15	78.48	OK	18642	2026-09-23 09:16	77.24	OK
18643	2026-09-23 09:17	76.50	OK	18644	2026-09-23 09:18	80.79	OK
18645	2026-09-23 09:19	78.37	OK	18646	2026-09-23 09:20	81.16	OK
18647	2026-09-23 09:21	76.01	OK	18648	2026-09-23 09:22	77.91	OK
18649	2026-09-23 09:23	79.33	OK	18650	2026-09-23 09:24	77.52	OK
18651	2026-09-23 09:25	79.09	OK	18652	2026-09-23 09:26	80.11	OK
18653	2026-09-23 09:27	79.78	OK	18654	2026-09-23 09:28	79.01	OK
18655	2026-09-23 09:29	81.40	OK	18656	2026-09-23 09:30	79.47	OK
18657	2026-09-23 09:31	81.56	OK	18658	2026-09-23 09:32	82.03	OK
18659	2026-09-23 09:33	76.54	OK	18660	2026-09-23 09:34	77.42	OK
18661	2026-09-23 09:35	78.90	OK	18662	2026-09-23 09:36	76.34	OK
18663	2026-09-23 09:37	80.40	OK	18664	2026-09-23 09:38	79.68	OK
18665	2026-09-23 09:39	77.25	OK	18666	2026-09-23 09:40	78.49	OK
18667	2026-09-23 09:41	78.76	OK	18668	2026-09-23 09:42	76.68	OK
18669	2026-09-23 09:43	79.70	OK	18670	2026-09-23 09:44	80.86	OK
18671	2026-09-23 09:45	78.68	OK	18672	2026-09-23 09:46	80.83	OK
18673	2026-09-23 09:47	78.38	OK	18674	2026-09-23 09:48	79.69	OK
18675	2026-09-23 09:49	78.29	OK	18676	2026-09-23 09:50	80.23	OK
18677	2026-09-23 09:51	78.14	OK	18678	2026-09-23 09:52	76.60	OK
18679	2026-09-23 09:53	77.96	OK	18680	2026-09-23 09:54	80.02	OK
18681	2026-09-23 09:55	78.13	OK	18682	2026-09-23 09:56	77.35	OK
18683	2026-09-23 09:57	79.58	OK	18684	2026-09-23 09:58	79.99	OK
18685	2026-09-23 09:59	79.16	OK	18686	2026-09-23 10:00	81.33	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18687	2026-09-23 10:01	81.25	OK	18688	2026-09-23 10:02	80.03	OK
18689	2026-09-23 10:03	79.41	OK	18690	2026-09-23 10:04	81.81	OK
18691	2026-09-23 10:05	77.42	OK	18692	2026-09-23 10:06	79.01	OK
18693	2026-09-23 10:07	80.46	OK	18694	2026-09-23 10:08	76.85	OK
18695	2026-09-23 10:09	80.51	OK	18696	2026-09-23 10:10	75.90	OK
18697	2026-09-23 10:11	81.78	OK	18698	2026-09-23 10:12	81.96	OK
18699	2026-09-23 10:13	77.48	OK	18700	2026-09-23 10:14	80.04	OK
18701	2026-09-23 10:15	80.08	OK	18702	2026-09-23 10:16	81.79	OK
18703	2026-09-23 10:17	77.82	OK	18704	2026-09-23 10:18	79.62	OK
18705	2026-09-23 10:19	79.59	OK	18706	2026-09-23 10:20	78.48	OK
18707	2026-09-23 10:21	80.49	OK	18708	2026-09-23 10:22	80.14	OK
18709	2026-09-23 10:23	77.57	OK	18710	2026-09-23 10:24	78.36	OK
18711	2026-09-23 10:25	82.27	OK	18712	2026-09-23 10:26	76.78	OK
18713	2026-09-23 10:27	77.56	OK	18714	2026-09-23 10:28	81.05	OK
18715	2026-09-23 10:29	81.72	OK	18716	2026-09-23 10:30	81.44	OK
18717	2026-09-23 10:31	81.11	OK	18718	2026-09-23 10:32	76.44	OK
18719	2026-09-23 10:33	81.29	OK	18720	2026-09-23 10:34	81.96	OK
18721	2026-09-23 10:35	77.80	OK	18722	2026-09-23 10:36	79.10	OK
18723	2026-09-23 10:37	77.30	OK	18724	2026-09-23 10:38	79.08	OK
18725	2026-09-23 10:39	81.08	OK	18726	2026-09-23 10:40	77.15	OK
18727	2026-09-23 10:41	80.48	OK	18728	2026-09-23 10:42	82.44	OK
18729	2026-09-23 10:43	79.19	OK	18730	2026-09-23 10:44	78.23	OK
18731	2026-09-23 10:45	77.33	OK	18732	2026-09-23 10:46	80.30	OK
18733	2026-09-23 10:47	80.90	OK	18734	2026-09-23 10:48	81.94	OK
18735	2026-09-23 10:49	78.12	OK	18736	2026-09-23 10:50	79.00	OK
18737	2026-09-23 10:51	82.22	OK	18738	2026-09-23 10:52	78.44	OK
18739	2026-09-23 10:53	81.77	OK	18740	2026-09-23 10:54	83.22	OK
18741	2026-09-23 10:55	79.66	OK	18742	2026-09-23 10:56	79.34	OK
18743	2026-09-23 10:57	79.95	OK	18744	2026-09-23 10:58	80.45	OK
18745	2026-09-23 10:59	78.67	OK	18746	2026-09-23 11:00	81.15	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18747	2026-09-23 11:01	79.72	OK	18748	2026-09-23 11:02	81.74	OK
18749	2026-09-23 11:03	80.20	OK	18750	2026-09-23 11:04	78.97	OK
18751	2026-09-23 11:05	79.94	OK	18752	2026-09-23 11:06	78.72	OK
18753	2026-09-23 11:07	80.40	OK	18754	2026-09-23 11:08	80.12	OK
18755	2026-09-23 11:09	78.80	OK	18756	2026-09-23 11:10	81.99	OK
18757	2026-09-23 11:11	78.21	OK	18758	2026-09-23 11:12	78.45	OK
18759	2026-09-23 11:13	81.14	OK	18760	2026-09-23 11:14	82.92	OK
18761	2026-09-23 11:15	81.81	OK	18762	2026-09-23 11:16	79.29	OK
18763	2026-09-23 11:17	79.89	OK	18764	2026-09-23 11:18	78.58	OK
18765	2026-09-23 11:19	81.20	OK	18766	2026-09-23 11:20	83.32	OK
18767	2026-09-23 11:21	83.78	OK	18768	2026-09-23 11:22	78.93	OK
18769	2026-09-23 11:23	80.42	OK	18770	2026-09-23 11:24	77.65	OK
18771	2026-09-23 11:25	78.86	OK	18772	2026-09-23 11:26	81.18	OK
18773	2026-09-23 11:27	83.20	OK	18774	2026-09-23 11:28	81.73	OK
18775	2026-09-23 11:29	84.07	OK	18776	2026-09-23 11:30	79.39	OK
18777	2026-09-23 11:31	82.31	OK	18778	2026-09-23 11:32	82.84	OK
18779	2026-09-23 11:33	79.24	OK	18780	2026-09-23 11:34	80.62	OK
18781	2026-09-23 11:35	81.38	OK	18782	2026-09-23 11:36	79.95	OK
18783	2026-09-23 11:37	76.89	OK	18784	2026-09-23 11:38	80.31	OK
18785	2026-09-23 11:39	79.59	OK	18786	2026-09-23 11:40	82.72	OK
18787	2026-09-23 11:41	79.25	OK	18788	2026-09-23 11:42	80.17	OK
18789	2026-09-23 11:43	81.60	OK	18790	2026-09-23 11:44	82.53	OK
18791	2026-09-23 11:45	82.28	OK	18792	2026-09-23 11:46	77.15	OK
18793	2026-09-23 11:47	81.42	OK	18794	2026-09-23 11:48	81.06	OK
18795	2026-09-23 11:49	81.68	OK	18796	2026-09-23 11:50	81.40	OK
18797	2026-09-23 11:51	81.58	OK	18798	2026-09-23 11:52	82.39	OK
18799	2026-09-23 11:53	79.55	OK	18800	2026-09-23 11:54	80.85	OK
18801	2026-09-23 11:55	77.92	OK	18802	2026-09-23 11:56	79.71	OK
18803	2026-09-23 11:57	80.65	OK	18804	2026-09-23 11:58	78.12	OK
18805	2026-09-23 11:59	80.72	OK	18806	2026-09-23 12:00	81.57	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18807	2026-09-23 12:01	81.11	OK	18808	2026-09-23 12:02	80.85	OK
18809	2026-09-23 12:03	79.98	OK	18810	2026-09-23 12:04	81.77	OK
18811	2026-09-23 12:05	81.04	OK	18812	2026-09-23 12:06	79.64	OK
18813	2026-09-23 12:07	81.67	OK	18814	2026-09-23 12:08	80.58	OK
18815	2026-09-23 12:09	79.52	OK	18816	2026-09-23 12:10	81.25	OK
18817	2026-09-23 12:11	81.77	OK	18818	2026-09-23 12:12	83.15	OK
18819	2026-09-23 12:13	81.92	OK	18820	2026-09-23 12:14	79.09	OK
18821	2026-09-23 12:15	79.87	OK	18822	2026-09-23 12:16	80.68	OK
18823	2026-09-23 12:17	82.87	OK	18824	2026-09-23 12:18	82.32	OK
18825	2026-09-23 12:19	81.88	OK	18826	2026-09-23 12:20	79.24	OK
18827	2026-09-23 12:21	78.73	OK	18828	2026-09-23 12:22	79.46	OK
18829	2026-09-23 12:23	80.76	OK	18830	2026-09-23 12:24	80.42	OK
18831	2026-09-23 12:25	77.34	OK	18832	2026-09-23 12:26	82.06	OK
18833	2026-09-23 12:27	81.92	OK	18834	2026-09-23 12:28	80.25	OK
18835	2026-09-23 12:29	79.80	OK	18836	2026-09-23 12:30	80.46	OK
18837	2026-09-23 12:31	81.53	OK	18838	2026-09-23 12:32	83.81	OK
18839	2026-09-23 12:33	82.11	OK	18840	2026-09-23 12:34	79.84	OK
18841	2026-09-23 12:35	82.27	OK	18842	2026-09-23 12:36	82.58	OK
18843	2026-09-23 12:37	82.05	OK	18844	2026-09-23 12:38	82.29	OK
18845	2026-09-23 12:39	83.42	OK	18846	2026-09-23 12:40	80.40	OK
18847	2026-09-23 12:41	80.25	OK	18848	2026-09-23 12:42	78.20	OK
18849	2026-09-23 12:43	80.85	OK	18850	2026-09-23 12:44	80.79	OK
18851	2026-09-23 12:45	79.05	OK	18852	2026-09-23 12:46	80.63	OK
18853	2026-09-23 12:47	78.05	OK	18854	2026-09-23 12:48	82.01	OK
18855	2026-09-23 12:49	79.22	OK	18856	2026-09-23 12:50	81.20	OK
18857	2026-09-23 12:51	78.42	OK	18858	2026-09-23 12:52	80.45	OK
18859	2026-09-23 12:53	81.48	OK	18860	2026-09-23 12:54	80.38	OK
18861	2026-09-23 12:55	82.61	OK	18862	2026-09-23 12:56	80.45	OK
18863	2026-09-23 12:57	81.11	OK	18864	2026-09-23 12:58	82.86	OK
18865	2026-09-23 12:59	82.70	OK	18866	2026-09-23 13:00	81.81	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18867	2026-09-23 13:01	81.88	OK	18868	2026-09-23 13:02	80.52	OK
18869	2026-09-23 13:03	81.65	OK	18870	2026-09-23 13:04	80.30	OK
18871	2026-09-23 13:05	80.52	OK	18872	2026-09-23 13:06	81.38	OK
18873	2026-09-23 13:07	83.70	OK	18874	2026-09-23 13:08	80.79	OK
18875	2026-09-23 13:09	84.69	OK	18876	2026-09-23 13:10	79.20	OK
18877	2026-09-23 13:11	81.98	OK	18878	2026-09-23 13:12	81.19	OK
18879	2026-09-23 13:13	79.74	OK	18880	2026-09-23 13:14	81.18	OK
18881	2026-09-23 13:15	83.19	OK	18882	2026-09-23 13:16	79.19	OK
18883	2026-09-23 13:17	81.28	OK	18884	2026-09-23 13:18	80.98	OK
18885	2026-09-23 13:19	83.09	OK	18886	2026-09-23 13:20	82.45	OK
18887	2026-09-23 13:21	81.64	OK	18888	2026-09-23 13:22	80.66	OK
18889	2026-09-23 13:23	78.87	OK	18890	2026-09-23 13:24	83.64	OK
18891	2026-09-23 13:25	82.25	OK	18892	2026-09-23 13:26	81.27	OK
18893	2026-09-23 13:27	81.29	OK	18894	2026-09-23 13:28	81.95	OK
18895	2026-09-23 13:29	80.35	OK	18896	2026-09-23 13:30	81.65	OK
18897	2026-09-23 13:31	78.22	OK	18898	2026-09-23 13:32	83.26	OK
18899	2026-09-23 13:33	80.53	OK	18900	2026-09-23 13:34	81.10	OK
18901	2026-09-23 13:35	82.71	OK	18902	2026-09-23 13:36	81.46	OK
18903	2026-09-23 13:37	79.58	OK	18904	2026-09-23 13:38	80.99	OK
18905	2026-09-23 13:39	79.79	OK	18906	2026-09-23 13:40	83.16	OK
18907	2026-09-23 13:41	81.05	OK	18908	2026-09-23 13:42	80.55	OK
18909	2026-09-23 13:43	83.01	OK	18910	2026-09-23 13:44	79.67	OK
18911	2026-09-23 13:45	80.68	OK	18912	2026-09-23 13:46	81.49	OK
18913	2026-09-23 13:47	79.54	OK	18914	2026-09-23 13:48	79.73	OK
18915	2026-09-23 13:49	80.73	OK	18916	2026-09-23 13:50	81.59	OK
18917	2026-09-23 13:51	77.94	OK	18918	2026-09-23 13:52	81.03	OK
18919	2026-09-23 13:53	80.04	OK	18920	2026-09-23 13:54	83.71	OK
18921	2026-09-23 13:55	79.76	OK	18922	2026-09-23 13:56	79.88	OK
18923	2026-09-23 13:57	80.00	OK	18924	2026-09-23 13:58	81.30	OK
18925	2026-09-23 13:59	81.33	OK	18926	2026-09-23 14:00	82.58	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18927	2026-09-23 14:01	79.60	OK	18928	2026-09-23 14:02	79.70	OK
18929	2026-09-23 14:03	81.84	OK	18930	2026-09-23 14:04	80.52	OK
18931	2026-09-23 14:05	78.42	OK	18932	2026-09-23 14:06	79.68	OK
18933	2026-09-23 14:07	76.36	OK	18934	2026-09-23 14:08	80.37	OK
18935	2026-09-23 14:09	82.69	OK	18936	2026-09-23 14:10	80.56	OK
18937	2026-09-23 14:11	79.05	OK	18938	2026-09-23 14:12	80.03	OK
18939	2026-09-23 14:13	79.65	OK	18940	2026-09-23 14:14	79.77	OK
18941	2026-09-23 14:15	81.42	OK	18942	2026-09-23 14:16	79.54	OK
18943	2026-09-23 14:17	81.45	OK	18944	2026-09-23 14:18	78.37	OK
18945	2026-09-23 14:19	83.21	OK	18946	2026-09-23 14:20	81.14	OK
18947	2026-09-23 14:21	83.26	OK	18948	2026-09-23 14:22	78.30	OK
18949	2026-09-23 14:23	80.02	OK	18950	2026-09-23 14:24	79.74	OK
18951	2026-09-23 14:25	78.29	OK	18952	2026-09-23 14:26	78.03	OK
18953	2026-09-23 14:27	80.81	OK	18954	2026-09-23 14:28	82.39	OK
18955	2026-09-23 14:29	83.45	OK	18956	2026-09-23 14:30	80.04	OK
18957	2026-09-23 14:31	79.99	OK	18958	2026-09-23 14:32	83.64	OK
18959	2026-09-23 14:33	80.68	OK	18960	2026-09-23 14:34	79.01	OK
18961	2026-09-23 14:35	80.83	OK	18962	2026-09-23 14:36	78.57	OK
18963	2026-09-23 14:37	81.43	OK	18964	2026-09-23 14:38	80.55	OK
18965	2026-09-23 14:39	80.33	OK	18966	2026-09-23 14:40	79.60	OK
18967	2026-09-23 14:41	80.94	OK	18968	2026-09-23 14:42	81.52	OK
18969	2026-09-23 14:43	78.29	OK	18970	2026-09-23 14:44	81.91	OK
18971	2026-09-23 14:45	79.66	OK	18972	2026-09-23 14:46	81.72	OK
18973	2026-09-23 14:47	78.02	OK	18974	2026-09-23 14:48	80.46	OK
18975	2026-09-23 14:49	81.80	OK	18976	2026-09-23 14:50	77.79	OK
18977	2026-09-23 14:51	81.98	OK	18978	2026-09-23 14:52	80.59	OK
18979	2026-09-23 14:53	76.66	OK	18980	2026-09-23 14:54	81.59	OK
18981	2026-09-23 14:55	81.21	OK	18982	2026-09-23 14:56	80.35	OK
18983	2026-09-23 14:57	80.25	OK	18984	2026-09-23 14:58	80.10	OK
18985	2026-09-23 14:59	79.68	OK	18986	2026-09-23 15:00	80.41	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18987	2026-09-23 15:01	80.38	OK	18988	2026-09-23 15:02	77.53	OK
18989	2026-09-23 15:03	80.86	OK	18990	2026-09-23 15:04	82.38	OK
18991	2026-09-23 15:05	80.26	OK	18992	2026-09-23 15:06	77.41	OK
18993	2026-09-23 15:07	78.77	OK	18994	2026-09-23 15:08	77.83	OK
18995	2026-09-23 15:09	80.90	OK	18996	2026-09-23 15:10	78.90	OK
18997	2026-09-23 15:11	79.80	OK	18998	2026-09-23 15:12	78.73	OK
18999	2026-09-23 15:13	81.60	OK	19000	2026-09-23 15:14	79.09	OK
19001	2026-09-23 15:15	80.01	OK	19002	2026-09-23 15:16	80.40	OK
19003	2026-09-23 15:17	80.63	OK	19004	2026-09-23 15:18	79.33	OK
19005	2026-09-23 15:19	80.17	OK	19006	2026-09-23 15:20	79.95	OK
19007	2026-09-23 15:21	79.37	OK	19008	2026-09-23 15:22	80.17	OK
19009	2026-09-23 15:23	80.02	OK	19010	2026-09-23 15:24	78.62	OK
19011	2026-09-23 15:25	84.22	OK	19012	2026-09-23 15:26	79.49	OK
19013	2026-09-23 15:27	78.33	OK	19014	2026-09-23 15:28	77.84	OK
19015	2026-09-23 15:29	78.68	OK	19016	2026-09-23 15:30	80.15	OK
19017	2026-09-23 15:31	78.74	OK	19018	2026-09-23 15:32	80.13	OK
19019	2026-09-23 15:33	77.98	OK	19020	2026-09-23 15:34	79.20	OK
19021	2026-09-23 15:35	81.16	OK	19022	2026-09-23 15:36	79.76	OK
19023	2026-09-23 15:37	80.23	OK	19024	2026-09-23 15:38	80.60	OK
19025	2026-09-23 15:39	78.73	OK	19026	2026-09-23 15:40	80.25	OK
19027	2026-09-23 15:41	78.49	OK	19028	2026-09-23 15:42	77.91	OK
19029	2026-09-23 15:43	76.99	OK	19030	2026-09-23 15:44	78.18	OK
19031	2026-09-23 15:45	80.47	OK	19032	2026-09-23 15:46	77.87	OK
19033	2026-09-23 15:47	81.30	OK	19034	2026-09-23 15:48	79.92	OK
19035	2026-09-23 15:49	78.62	OK	19036	2026-09-23 15:50	78.76	OK
19037	2026-09-23 15:51	77.47	OK	19038	2026-09-23 15:52	80.17	OK
19039	2026-09-23 15:53	77.96	OK	19040	2026-09-23 15:54	79.61	OK
19041	2026-09-23 15:55	77.23	OK	19042	2026-09-23 15:56	77.52	OK
19043	2026-09-23 15:57	79.94	OK	19044	2026-09-23 15:58	79.39	OK
19045	2026-09-23 15:59	79.05	OK	19046	2026-09-23 16:00	81.91	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19047	2026-09-23 16:01	79.72	OK	19048	2026-09-23 16:02	76.98	OK
19049	2026-09-23 16:03	76.51	OK	19050	2026-09-23 16:04	74.80	OK
19051	2026-09-23 16:05	78.71	OK	19052	2026-09-23 16:06	79.64	OK
19053	2026-09-23 16:07	78.89	OK	19054	2026-09-23 16:08	77.15	OK
19055	2026-09-23 16:09	77.22	OK	19056	2026-09-23 16:10	78.99	OK
19057	2026-09-23 16:11	77.53	OK	19058	2026-09-23 16:12	77.61	OK
19059	2026-09-23 16:13	77.35	OK	19060	2026-09-23 16:14	79.17	OK
19061	2026-09-23 16:15	80.07	OK	19062	2026-09-23 16:16	80.84	OK
19063	2026-09-23 16:17	78.58	OK	19064	2026-09-23 16:18	77.22	OK
19065	2026-09-23 16:19	80.46	OK	19066	2026-09-23 16:20	79.46	OK
19067	2026-09-23 16:21	79.48	OK	19068	2026-09-23 16:22	78.87	OK
19069	2026-09-23 16:23	79.71	OK	19070	2026-09-23 16:24	76.15	OK
19071	2026-09-23 16:25	77.06	OK	19072	2026-09-23 16:26	80.19	OK
19073	2026-09-23 16:27	78.30	OK	19074	2026-09-23 16:28	81.59	OK
19075	2026-09-23 16:29	77.99	OK	19076	2026-09-23 16:30	76.47	OK
19077	2026-09-23 16:31	78.30	OK	19078	2026-09-23 16:32	77.97	OK
19079	2026-09-23 16:33	80.52	OK	19080	2026-09-23 16:34	79.61	OK
19081	2026-09-23 16:35	79.52	OK	19082	2026-09-23 16:36	77.63	OK
19083	2026-09-23 16:37	74.57	OK	19084	2026-09-23 16:38	78.34	OK
19085	2026-09-23 16:39	81.79	OK	19086	2026-09-23 16:40	77.84	OK
19087	2026-09-23 16:41	80.93	OK	19088	2026-09-23 16:42	77.66	OK
19089	2026-09-23 16:43	75.23	OK	19090	2026-09-23 16:44	78.19	OK
19091	2026-09-23 16:45	79.22	OK	19092	2026-09-23 16:46	79.10	OK
19093	2026-09-23 16:47	78.35	OK	19094	2026-09-23 16:48	77.22	OK
19095	2026-09-23 16:49	80.75	OK	19096	2026-09-23 16:50	76.17	OK
19097	2026-09-23 16:51	82.45	OK	19098	2026-09-23 16:52	79.13	OK
19099	2026-09-23 16:53	78.88	OK	19100	2026-09-23 16:54	77.26	OK
19101	2026-09-23 16:55	79.50	OK	19102	2026-09-23 16:56	76.34	OK
19103	2026-09-23 16:57	77.49	OK	19104	2026-09-23 16:58	78.57	OK
19105	2026-09-23 16:59	76.96	OK	19106	2026-09-23 17:00	77.20	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19107	2026-09-23 17:01	78.13	OK	19108	2026-09-23 17:02	80.87	OK
19109	2026-09-23 17:03	78.35	OK	19110	2026-09-23 17:04	79.20	OK
19111	2026-09-23 17:05	75.34	OK	19112	2026-09-23 17:06	80.93	OK
19113	2026-09-23 17:07	79.33	OK	19114	2026-09-23 17:08	77.54	OK
19115	2026-09-23 17:09	76.72	OK	19116	2026-09-23 17:10	78.08	OK
19117	2026-09-23 17:11	79.48	OK	19118	2026-09-23 17:12	78.77	OK
19119	2026-09-23 17:13	74.86	OK	19120	2026-09-23 17:14	79.25	OK
19121	2026-09-23 17:15	78.59	OK	19122	2026-09-23 17:16	76.58	OK
19123	2026-09-23 17:17	73.81	OK	19124	2026-09-23 17:18	77.71	OK
19125	2026-09-23 17:19	78.97	OK	19126	2026-09-23 17:20	78.78	OK
19127	2026-09-23 17:21	74.02	OK	19128	2026-09-23 17:22	74.33	OK
19129	2026-09-23 17:23	78.74	OK	19130	2026-09-23 17:24	75.21	OK
19131	2026-09-23 17:25	78.10	OK	19132	2026-09-23 17:26	77.69	OK
19133	2026-09-23 17:27	78.12	OK	19134	2026-09-23 17:28	77.83	OK
19135	2026-09-23 17:29	76.41	OK	19136	2026-09-23 17:30	78.69	OK
19137	2026-09-23 17:31	75.79	OK	19138	2026-09-23 17:32	74.32	OK
19139	2026-09-23 17:33	78.44	OK	19140	2026-09-23 17:34	78.21	OK
19141	2026-09-23 17:35	72.92	OK	19142	2026-09-23 17:36	77.99	OK
19143	2026-09-23 17:37	73.71	OK	19144	2026-09-23 17:38	75.89	OK
19145	2026-09-23 17:39	75.73	OK	19146	2026-09-23 17:40	75.63	OK
19147	2026-09-23 17:41	76.47	OK	19148	2026-09-23 17:42	78.62	OK
19149	2026-09-23 17:43	76.77	OK	19150	2026-09-23 17:44	78.45	OK
19151	2026-09-23 17:45	76.56	OK	19152	2026-09-23 17:46	77.12	OK
19153	2026-09-23 17:47	75.84	OK	19154	2026-09-23 17:48	75.76	OK
19155	2026-09-23 17:49	75.74	OK	19156	2026-09-23 17:50	74.56	OK
19157	2026-09-23 17:51	75.48	OK	19158	2026-09-23 17:52	76.83	OK
19159	2026-09-23 17:53	76.82	OK	19160	2026-09-23 17:54	77.44	OK
19161	2026-09-23 17:55	76.74	OK	19162	2026-09-23 17:56	73.67	OK
19163	2026-09-23 17:57	76.68	OK	19164	2026-09-23 17:58	75.88	OK
19165	2026-09-23 17:59	75.04	OK	19166	2026-09-23 18:00	77.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19167	2026-09-23 18:01	77.10	OK	19168	2026-09-23 18:02	74.84	OK
19169	2026-09-23 18:03	75.39	OK	19170	2026-09-23 18:04	74.80	OK
19171	2026-09-23 18:05	77.77	OK	19172	2026-09-23 18:06	77.58	OK
19173	2026-09-23 18:07	74.51	OK	19174	2026-09-23 18:08	76.65	OK
19175	2026-09-23 18:09	77.81	OK	19176	2026-09-23 18:10	76.76	OK
19177	2026-09-23 18:11	78.00	OK	19178	2026-09-23 18:12	78.84	OK
19179	2026-09-23 18:13	76.76	OK	19180	2026-09-23 18:14	77.71	OK
19181	2026-09-23 18:15	75.70	OK	19182	2026-09-23 18:16	72.55	OK
19183	2026-09-23 18:17	77.59	OK	19184	2026-09-23 18:18	73.56	OK
19185	2026-09-23 18:19	74.72	OK	19186	2026-09-23 18:20	74.58	OK
19187	2026-09-23 18:21	77.64	OK	19188	2026-09-23 18:22	77.16	OK
19189	2026-09-23 18:23	74.89	OK	19190	2026-09-23 18:24	74.40	OK
19191	2026-09-23 18:25	77.76	OK	19192	2026-09-23 18:26	76.42	OK
19193	2026-09-23 18:27	74.19	OK	19194	2026-09-23 18:28	75.69	OK
19195	2026-09-23 18:29	77.55	OK	19196	2026-09-23 18:30	76.80	OK
19197	2026-09-23 18:31	75.98	OK	19198	2026-09-23 18:32	77.07	OK
19199	2026-09-23 18:33	76.28	OK	19200	2026-09-23 18:34	78.53	OK
19201	2026-09-23 18:35	75.60	OK	19202	2026-09-23 18:36	74.39	OK
19203	2026-09-23 18:37	75.34	OK	19204	2026-09-23 18:38	76.50	OK
19205	2026-09-23 18:39	76.05	OK	19206	2026-09-23 18:40	76.85	OK
19207	2026-09-23 18:41	73.56	OK	19208	2026-09-23 18:42	75.25	OK
19209	2026-09-23 18:43	72.58	OK	19210	2026-09-23 18:44	75.35	OK
19211	2026-09-23 18:45	74.78	OK	19212	2026-09-23 18:46	75.04	OK
19213	2026-09-23 18:47	77.59	OK	19214	2026-09-23 18:48	76.65	OK
19215	2026-09-23 18:49	74.73	OK	19216	2026-09-23 18:50	73.92	OK
19217	2026-09-23 18:51	75.24	OK	19218	2026-09-23 18:52	73.81	OK
19219	2026-09-23 18:53	77.47	OK	19220	2026-09-23 18:54	78.10	OK
19221	2026-09-23 18:55	73.42	OK	19222	2026-09-23 18:56	73.10	OK
19223	2026-09-23 18:57	74.28	OK	19224	2026-09-23 18:58	73.39	OK
19225	2026-09-23 18:59	74.84	OK	19226	2026-09-23 19:00	71.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19227	2026-09-23 19:01	75.97	OK	19228	2026-09-23 19:02	75.57	OK
19229	2026-09-23 19:03	74.29	OK	19230	2026-09-23 19:04	73.65	OK
19231	2026-09-23 19:05	72.05	OK	19232	2026-09-23 19:06	74.85	OK
19233	2026-09-23 19:07	78.21	OK	19234	2026-09-23 19:08	77.84	OK
19235	2026-09-23 19:09	75.86	OK	19236	2026-09-23 19:10	75.34	OK
19237	2026-09-23 19:11	72.92	OK	19238	2026-09-23 19:12	75.32	OK
19239	2026-09-23 19:13	76.71	OK	19240	2026-09-23 19:14	76.04	OK
19241	2026-09-23 19:15	74.95	OK	19242	2026-09-23 19:16	71.01	OK
19243	2026-09-23 19:17	70.36	OK	19244	2026-09-23 19:18	73.52	OK
19245	2026-09-23 19:19	77.49	OK	19246	2026-09-23 19:20	77.40	OK
19247	2026-09-23 19:21	76.81	OK	19248	2026-09-23 19:22	76.33	OK
19249	2026-09-23 19:23	76.11	OK	19250	2026-09-23 19:24	74.66	OK
19251	2026-09-23 19:25	75.92	OK	19252	2026-09-23 19:26	74.47	OK
19253	2026-09-23 19:27	73.17	OK	19254	2026-09-23 19:28	72.94	OK
19255	2026-09-23 19:29	75.32	OK	19256	2026-09-23 19:30	75.72	OK
19257	2026-09-23 19:31	74.37	OK	19258	2026-09-23 19:32	70.81	OK
19259	2026-09-23 19:33	72.04	OK	19260	2026-09-23 19:34	75.42	OK
19261	2026-09-23 19:35	70.69	OK	19262	2026-09-23 19:36	74.80	OK
19263	2026-09-23 19:37	73.82	OK	19264	2026-09-23 19:38	73.68	OK
19265	2026-09-23 19:39	72.51	OK	19266	2026-09-23 19:40	73.94	OK
19267	2026-09-23 19:41	71.59	OK	19268	2026-09-23 19:42	74.30	OK
19269	2026-09-23 19:43	74.87	OK	19270	2026-09-23 19:44	77.25	OK
19271	2026-09-23 19:45	75.10	OK	19272	2026-09-23 19:46	71.03	OK
19273	2026-09-23 19:47	72.24	OK	19274	2026-09-23 19:48	75.85	OK
19275	2026-09-23 19:49	73.87	OK	19276	2026-09-23 19:50	71.84	OK
19277	2026-09-23 19:51	75.36	OK	19278	2026-09-23 19:52	72.21	OK
19279	2026-09-23 19:53	76.21	OK	19280	2026-09-23 19:54	76.57	OK
19281	2026-09-23 19:55	72.81	OK	19282	2026-09-23 19:56	74.75	OK
19283	2026-09-23 19:57	72.76	OK	19284	2026-09-23 19:58	74.56	OK
19285	2026-09-23 19:59	72.25	OK	19286	2026-09-23 20:00	72.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19287	2026-09-23 20:01	72.37	OK	19288	2026-09-23 20:02	76.30	OK
19289	2026-09-23 20:03	74.14	OK	19290	2026-09-23 20:04	75.89	OK
19291	2026-09-23 20:05	74.91	OK	19292	2026-09-23 20:06	76.07	OK
19293	2026-09-23 20:07	73.92	OK	19294	2026-09-23 20:08	74.10	OK
19295	2026-09-23 20:09	77.00	OK	19296	2026-09-23 20:10	76.59	OK
19297	2026-09-23 20:11	72.97	OK	19298	2026-09-23 20:12	70.08	OK
19299	2026-09-23 20:13	70.10	OK	19300	2026-09-23 20:14	73.27	OK
19301	2026-09-23 20:15	73.86	OK	19302	2026-09-23 20:16	73.90	OK
19303	2026-09-23 20:17	74.21	OK	19304	2026-09-23 20:18	74.07	OK
19305	2026-09-23 20:19	71.77	OK	19306	2026-09-23 20:20	72.93	OK
19307	2026-09-23 20:21	76.61	OK	19308	2026-09-23 20:22	72.14	OK
19309	2026-09-23 20:23	72.13	OK	19310	2026-09-23 20:24	74.19	OK
19311	2026-09-23 20:25	75.15	OK	19312	2026-09-23 20:26	73.53	OK
19313	2026-09-23 20:27	72.35	OK	19314	2026-09-23 20:28	71.00	OK
19315	2026-09-23 20:29	72.81	OK	19316	2026-09-23 20:30	72.99	OK
19317	2026-09-23 20:31	73.93	OK	19318	2026-09-23 20:32	71.76	OK
19319	2026-09-23 20:33	68.68	OK	19320	2026-09-23 20:34	68.54	OK
19321	2026-09-23 20:35	72.87	OK	19322	2026-09-23 20:36	72.96	OK
19323	2026-09-23 20:37	70.74	OK	19324	2026-09-23 20:38	71.61	OK
19325	2026-09-23 20:39	73.70	OK	19326	2026-09-23 20:40	74.91	OK
19327	2026-09-23 20:41	74.87	OK	19328	2026-09-23 20:42	73.60	OK
19329	2026-09-23 20:43	71.01	OK	19330	2026-09-23 20:44	74.16	OK
19331	2026-09-23 20:45	73.21	OK	19332	2026-09-23 20:46	71.98	OK
19333	2026-09-23 20:47	72.36	OK	19334	2026-09-23 20:48	73.49	OK
19335	2026-09-23 20:49	73.36	OK	19336	2026-09-23 20:50	70.63	OK
19337	2026-09-23 20:51	71.09	OK	19338	2026-09-23 20:52	73.09	OK
19339	2026-09-23 20:53	72.79	OK	19340	2026-09-23 20:54	73.58	OK
19341	2026-09-23 20:55	73.47	OK	19342	2026-09-23 20:56	73.61	OK
19343	2026-09-23 20:57	72.86	OK	19344	2026-09-23 20:58	68.60	OK
19345	2026-09-23 20:59	72.73	OK	19346	2026-09-23 21:00	72.48	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19347	2026-09-23 21:01	71.50	OK	19348	2026-09-23 21:02	71.98	OK
19349	2026-09-23 21:03	72.13	OK	19350	2026-09-23 21:04	71.66	OK
19351	2026-09-23 21:05	71.55	OK	19352	2026-09-23 21:06	70.19	OK
19353	2026-09-23 21:07	75.18	OK	19354	2026-09-23 21:08	69.94	OK
19355	2026-09-23 21:09	71.27	OK	19356	2026-09-23 21:10	73.73	OK
19357	2026-09-23 21:11	71.80	OK	19358	2026-09-23 21:12	71.15	OK
19359	2026-09-23 21:13	75.14	OK	19360	2026-09-23 21:14	70.29	OK
19361	2026-09-23 21:15	72.12	OK	19362	2026-09-23 21:16	72.82	OK
19363	2026-09-23 21:17	72.71	OK	19364	2026-09-23 21:18	69.83	OK
19365	2026-09-23 21:19	69.80	OK	19366	2026-09-23 21:20	75.28	OK
19367	2026-09-23 21:21	71.20	OK	19368	2026-09-23 21:22	68.34	OK
19369	2026-09-23 21:23	71.45	OK	19370	2026-09-23 21:24	70.47	OK
19371	2026-09-23 21:25	71.96	OK	19372	2026-09-23 21:26	70.66	OK
19373	2026-09-23 21:27	72.96	OK	19374	2026-09-23 21:28	69.15	OK
19375	2026-09-23 21:29	72.73	OK	19376	2026-09-23 21:30	69.66	OK
19377	2026-09-23 21:31	70.54	OK	19378	2026-09-23 21:32	73.65	OK
19379	2026-09-23 21:33	71.99	OK	19380	2026-09-23 21:34	73.20	OK
19381	2026-09-23 21:35	75.01	OK	19382	2026-09-23 21:36	70.15	OK
19383	2026-09-23 21:37	71.48	OK	19384	2026-09-23 21:38	72.27	OK
19385	2026-09-23 21:39	70.45	OK	19386	2026-09-23 21:40	71.27	OK
19387	2026-09-23 21:41	69.39	OK	19388	2026-09-23 21:42	71.55	OK
19389	2026-09-23 21:43	70.20	OK	19390	2026-09-23 21:44	69.68	OK
19391	2026-09-23 21:45	69.21	OK	19392	2026-09-23 21:46	70.12	OK
19393	2026-09-23 21:47	71.21	OK	19394	2026-09-23 21:48	69.01	OK
19395	2026-09-23 21:49	69.32	OK	19396	2026-09-23 21:50	69.67	OK
19397	2026-09-23 21:51	69.87	OK	19398	2026-09-23 21:52	70.36	OK
19399	2026-09-23 21:53	73.03	OK	19400	2026-09-23 21:54	72.06	OK
19401	2026-09-23 21:55	68.50	OK	19402	2026-09-23 21:56	70.25	OK
19403	2026-09-23 21:57	68.79	OK	19404	2026-09-23 21:58	69.75	OK
19405	2026-09-23 21:59	69.94	OK	19406	2026-09-23 22:00	74.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19407	2026-09-23 22:01	71.63	OK	19408	2026-09-23 22:02	68.97	OK
19409	2026-09-23 22:03	70.00	OK	19410	2026-09-23 22:04	71.43	OK
19411	2026-09-23 22:05	70.36	OK	19412	2026-09-23 22:06	72.97	OK
19413	2026-09-23 22:07	68.07	OK	19414	2026-09-23 22:08	71.22	OK
19415	2026-09-23 22:09	71.99	OK	19416	2026-09-23 22:10	71.67	OK
19417	2026-09-23 22:11	66.97	OK	19418	2026-09-23 22:12	68.20	OK
19419	2026-09-23 22:13	72.42	OK	19420	2026-09-23 22:14	70.72	OK
19421	2026-09-23 22:15	68.17	OK	19422	2026-09-23 22:16	73.62	OK
19423	2026-09-23 22:17	68.92	OK	19424	2026-09-23 22:18	71.25	OK
19425	2026-09-23 22:19	70.28	OK	19426	2026-09-23 22:20	71.91	OK
19427	2026-09-23 22:21	70.54	OK	19428	2026-09-23 22:22	71.51	OK
19429	2026-09-23 22:23	73.05	OK	19430	2026-09-23 22:24	72.93	OK
19431	2026-09-23 22:25	72.09	OK	19432	2026-09-23 22:26	69.70	OK
19433	2026-09-23 22:27	71.77	OK	19434	2026-09-23 22:28	69.23	OK
19435	2026-09-23 22:29	68.04	OK	19436	2026-09-23 22:30	70.33	OK
19437	2026-09-23 22:31	69.80	OK	19438	2026-09-23 22:32	68.50	OK
19439	2026-09-23 22:33	71.39	OK	19440	2026-09-23 22:34	69.03	OK
19441	2026-09-23 22:35	73.86	OK	19442	2026-09-23 22:36	71.29	OK
19443	2026-09-23 22:37	70.98	OK	19444	2026-09-23 22:38	72.79	OK
19445	2026-09-23 22:39	70.99	OK	19446	2026-09-23 22:40	69.37	OK
19447	2026-09-23 22:41	66.98	OK	19448	2026-09-23 22:42	70.78	OK
19449	2026-09-23 22:43	71.82	OK	19450	2026-09-23 22:44	71.36	OK
19451	2026-09-23 22:45	69.93	OK	19452	2026-09-23 22:46	73.60	OK
19453	2026-09-23 22:47	72.16	OK	19454	2026-09-23 22:48	69.59	OK
19455	2026-09-23 22:49	68.45	OK	19456	2026-09-23 22:50	70.28	OK
19457	2026-09-23 22:51	71.08	OK	19458	2026-09-23 22:52	72.11	OK
19459	2026-09-23 22:53	69.97	OK	19460	2026-09-23 22:54	69.39	OK
19461	2026-09-23 22:55	68.21	OK	19462	2026-09-23 22:56	69.98	OK
19463	2026-09-23 22:57	70.67	OK	19464	2026-09-23 22:58	71.80	OK
19465	2026-09-23 22:59	68.98	OK	19466	2026-09-23 23:00	68.54	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19467	2026-09-23 23:01	71.46	OK	19468	2026-09-23 23:02	68.61	OK
19469	2026-09-23 23:03	72.53	OK	19470	2026-09-23 23:04	70.98	OK
19471	2026-09-23 23:05	70.19	OK	19472	2026-09-23 23:06	70.60	OK
19473	2026-09-23 23:07	71.50	OK	19474	2026-09-23 23:08	67.61	OK
19475	2026-09-23 23:09	70.42	OK	19476	2026-09-23 23:10	70.72	OK
19477	2026-09-23 23:11	67.30	OK	19478	2026-09-23 23:12	67.66	OK
19479	2026-09-23 23:13	68.05	OK	19480	2026-09-23 23:14	67.81	OK
19481	2026-09-23 23:15	71.33	OK	19482	2026-09-23 23:16	72.80	OK
19483	2026-09-23 23:17	67.65	OK	19484	2026-09-23 23:18	69.34	OK
19485	2026-09-23 23:19	70.27	OK	19486	2026-09-23 23:20	68.92	OK
19487	2026-09-23 23:21	67.74	OK	19488	2026-09-23 23:22	71.55	OK
19489	2026-09-23 23:23	72.59	OK	19490	2026-09-23 23:24	70.35	OK
19491	2026-09-23 23:25	69.08	OK	19492	2026-09-23 23:26	70.28	OK
19493	2026-09-23 23:27	72.26	OK	19494	2026-09-23 23:28	72.02	OK
19495	2026-09-23 23:29	68.98	OK	19496	2026-09-23 23:30	68.25	OK
19497	2026-09-23 23:31	71.88	OK	19498	2026-09-23 23:32	68.89	OK
19499	2026-09-23 23:33	70.28	OK	19500	2026-09-23 23:34	67.16	OK
19501	2026-09-23 23:35	71.78	OK	19502	2026-09-23 23:36	70.78	OK
19503	2026-09-23 23:37	70.42	OK	19504	2026-09-23 23:38	70.03	OK
19505	2026-09-23 23:39	67.65	OK	19506	2026-09-23 23:40	74.14	OK
19507	2026-09-23 23:41	73.09	OK	19508	2026-09-23 23:42	70.14	OK
19509	2026-09-23 23:43	69.46	OK	19510	2026-09-23 23:44	68.66	OK
19511	2026-09-23 23:45	69.83	OK	19512	2026-09-23 23:46	70.95	OK
19513	2026-09-23 23:47	70.96	OK	19514	2026-09-23 23:48	70.86	OK
19515	2026-09-23 23:49	69.69	OK	19516	2026-09-23 23:50	71.46	OK
19517	2026-09-23 23:51	68.26	OK	19518	2026-09-23 23:52	71.90	OK
19519	2026-09-23 23:53	68.31	OK	19520	2026-09-23 23:54	65.49	OK
19521	2026-09-23 23:55	67.46	OK	19522	2026-09-23 23:56	69.79	OK
19523	2026-09-23 23:57	66.66	OK	19524	2026-09-23 23:58	68.34	OK
19525	2026-09-23 23:59	65.43	OK	19526	2026-09-24 00:00	68.39	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19527	2026-09-24 00:01	70.64	OK	19528	2026-09-24 00:02	68.91	OK
19529	2026-09-24 00:03	71.31	OK	19530	2026-09-24 00:04	71.02	OK
19531	2026-09-24 00:05	68.29	OK	19532	2026-09-24 00:06	69.69	OK
19533	2026-09-24 00:07	69.06	OK	19534	2026-09-24 00:08	68.70	OK
19535	2026-09-24 00:09	69.47	OK	19536	2026-09-24 00:10	71.54	OK
19537	2026-09-24 00:11	69.68	OK	19538	2026-09-24 00:12	70.84	OK
19539	2026-09-24 00:13	69.11	OK	19540	2026-09-24 00:14	71.41	OK
19541	2026-09-24 00:15	69.22	OK	19542	2026-09-24 00:16	73.11	OK
19543	2026-09-24 00:17	69.72	OK	19544	2026-09-24 00:18	70.79	OK
19545	2026-09-24 00:19	68.17	OK	19546	2026-09-24 00:20	70.52	OK
19547	2026-09-24 00:21	67.93	OK	19548	2026-09-24 00:22	67.76	OK
19549	2026-09-24 00:23	68.99	OK	19550	2026-09-24 00:24	69.32	OK
19551	2026-09-24 00:25	71.73	OK	19552	2026-09-24 00:26	71.05	OK
19553	2026-09-24 00:27	66.10	OK	19554	2026-09-24 00:28	70.83	OK
19555	2026-09-24 00:29	70.50	OK	19556	2026-09-24 00:30	70.11	OK
19557	2026-09-24 00:31	70.78	OK	19558	2026-09-24 00:32	68.16	OK
19559	2026-09-24 00:33	70.30	OK	19560	2026-09-24 00:34	72.02	OK
19561	2026-09-24 00:35	66.05	OK	19562	2026-09-24 00:36	70.08	OK
19563	2026-09-24 00:37	67.30	OK	19564	2026-09-24 00:38	70.74	OK
19565	2026-09-24 00:39	67.68	OK	19566	2026-09-24 00:40	70.59	OK
19567	2026-09-24 00:41	70.94	OK	19568	2026-09-24 00:42	70.28	OK
19569	2026-09-24 00:43	68.35	OK	19570	2026-09-24 00:44	71.39	OK
19571	2026-09-24 00:45	69.81	OK	19572	2026-09-24 00:46	66.38	OK
19573	2026-09-24 00:47	66.84	OK	19574	2026-09-24 00:48	71.14	OK
19575	2026-09-24 00:49	70.05	OK	19576	2026-09-24 00:50	68.86	OK
19577	2026-09-24 00:51	69.96	OK	19578	2026-09-24 00:52	72.39	OK
19579	2026-09-24 00:53	68.62	OK	19580	2026-09-24 00:54	68.32	OK
19581	2026-09-24 00:55	69.55	OK	19582	2026-09-24 00:56	67.53	OK
19583	2026-09-24 00:57	70.88	OK	19584	2026-09-24 00:58	67.36	OK
19585	2026-09-24 00:59	68.18	OK	19586	2026-09-24 01:00	69.83	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19587	2026-09-24 01:01	70.44	OK	19588	2026-09-24 01:02	68.94	OK
19589	2026-09-24 01:03	68.30	OK	19590	2026-09-24 01:04	68.58	OK
19591	2026-09-24 01:05	69.93	OK	19592	2026-09-24 01:06	66.42	OK
19593	2026-09-24 01:07	73.15	OK	19594	2026-09-24 01:08	70.62	OK
19595	2026-09-24 01:09	71.80	OK	19596	2026-09-24 01:10	70.56	OK
19597	2026-09-24 01:11	69.22	OK	19598	2026-09-24 01:12	68.30	OK
19599	2026-09-24 01:13	69.86	OK	19600	2026-09-24 01:14	69.97	OK
19601	2026-09-24 01:15	69.00	OK	19602	2026-09-24 01:16	68.15	OK
19603	2026-09-24 01:17	66.90	OK	19604	2026-09-24 01:18	66.32	OK
19605	2026-09-24 01:19	69.73	OK	19606	2026-09-24 01:20	69.34	OK
19607	2026-09-24 01:21	70.03	OK	19608	2026-09-24 01:22	70.85	OK
19609	2026-09-24 01:23	66.38	OK	19610	2026-09-24 01:24	70.68	OK
19611	2026-09-24 01:25	69.83	OK	19612	2026-09-24 01:26	71.93	OK
19613	2026-09-24 01:27	71.00	OK	19614	2026-09-24 01:28	68.97	OK
19615	2026-09-24 01:29	71.77	OK	19616	2026-09-24 01:30	73.15	OK
19617	2026-09-24 01:31	69.29	OK	19618	2026-09-24 01:32	67.15	OK
19619	2026-09-24 01:33	71.05	OK	19620	2026-09-24 01:34	68.22	OK
19621	2026-09-24 01:35	70.07	OK	19622	2026-09-24 01:36	71.81	OK
19623	2026-09-24 01:37	71.78	OK	19624	2026-09-24 01:38	70.97	OK
19625	2026-09-24 01:39	72.31	OK	19626	2026-09-24 01:40	71.09	OK
19627	2026-09-24 01:41	70.19	OK	19628	2026-09-24 01:42	67.69	OK
19629	2026-09-24 01:43	69.90	OK	19630	2026-09-24 01:44	69.30	OK
19631	2026-09-24 01:45	70.40	OK	19632	2026-09-24 01:46	71.80	OK
19633	2026-09-24 01:47	70.58	OK	19634	2026-09-24 01:48	70.81	OK
19635	2026-09-24 01:49	71.55	OK	19636	2026-09-24 01:50	69.50	OK
19637	2026-09-24 01:51	70.81	OK	19638	2026-09-24 01:52	69.34	OK
19639	2026-09-24 01:53	71.31	OK	19640	2026-09-24 01:54	66.43	OK
19641	2026-09-24 01:55	67.55	OK	19642	2026-09-24 01:56	69.73	OK
19643	2026-09-24 01:57	67.56	OK	19644	2026-09-24 01:58	72.73	OK
19645	2026-09-24 01:59	71.51	OK	19646	2026-09-24 02:00	72.24	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19647	2026-09-24 02:01	69.66	OK	19648	2026-09-24 02:02	72.38	OK
19649	2026-09-24 02:03	69.78	OK	19650	2026-09-24 02:04	68.50	OK
19651	2026-09-24 02:05	70.11	OK	19652	2026-09-24 02:06	68.83	OK
19653	2026-09-24 02:07	68.34	OK	19654	2026-09-24 02:08	69.65	OK
19655	2026-09-24 02:09	71.13	OK	19656	2026-09-24 02:10	70.39	OK
19657	2026-09-24 02:11	71.40	OK	19658	2026-09-24 02:12	68.99	OK
19659	2026-09-24 02:13	69.83	OK	19660	2026-09-24 02:14	69.45	OK
19661	2026-09-24 02:15	67.95	OK	19662	2026-09-24 02:16	71.18	OK
19663	2026-09-24 02:17	72.21	OK	19664	2026-09-24 02:18	70.05	OK
19665	2026-09-24 02:19	68.91	OK	19666	2026-09-24 02:20	71.29	OK
19667	2026-09-24 02:21	71.65	OK	19668	2026-09-24 02:22	69.80	OK
19669	2026-09-24 02:23	70.23	OK	19670	2026-09-24 02:24	68.41	OK
19671	2026-09-24 02:25	69.13	OK	19672	2026-09-24 02:26	70.93	OK
19673	2026-09-24 02:27	71.80	OK	19674	2026-09-24 02:28	69.29	OK
19675	2026-09-24 02:29	68.52	OK	19676	2026-09-24 02:30	69.24	OK
19677	2026-09-24 02:31	70.43	OK	19678	2026-09-24 02:32	70.21	OK
19679	2026-09-24 02:33	67.26	OK	19680	2026-09-24 02:34	71.48	OK
19681	2026-09-24 02:35	70.97	OK	19682	2026-09-24 02:36	70.87	OK
19683	2026-09-24 02:37	72.15	OK	19684	2026-09-24 02:38	72.21	OK
19685	2026-09-24 02:39	70.18	OK	19686	2026-09-24 02:40	70.32	OK
19687	2026-09-24 02:41	67.76	OK	19688	2026-09-24 02:42	70.98	OK
19689	2026-09-24 02:43	71.39	OK	19690	2026-09-24 02:44	67.12	OK
19691	2026-09-24 02:45	68.27	OK	19692	2026-09-24 02:46	69.43	OK
19693	2026-09-24 02:47	69.32	OK	19694	2026-09-24 02:48	71.13	OK
19695	2026-09-24 02:49	70.63	OK	19696	2026-09-24 02:50	68.92	OK
19697	2026-09-24 02:51	69.85	OK	19698	2026-09-24 02:52	73.99	OK
19699	2026-09-24 02:53	69.02	OK	19700	2026-09-24 02:54	69.78	OK
19701	2026-09-24 02:55	69.34	OK	19702	2026-09-24 02:56	71.12	OK
19703	2026-09-24 02:57	68.54	OK	19704	2026-09-24 02:58	67.24	OK
19705	2026-09-24 02:59	70.79	OK	19706	2026-09-24 03:00	70.08	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19707	2026-09-24 03:01	68.83	OK	19708	2026-09-24 03:02	67.29	OK
19709	2026-09-24 03:03	69.84	OK	19710	2026-09-24 03:04	72.95	OK
19711	2026-09-24 03:05	67.50	OK	19712	2026-09-24 03:06	71.22	OK
19713	2026-09-24 03:07	67.20	OK	19714	2026-09-24 03:08	73.49	OK
19715	2026-09-24 03:09	70.12	OK	19716	2026-09-24 03:10	69.20	OK
19717	2026-09-24 03:11	70.01	OK	19718	2026-09-24 03:12	70.95	OK
19719	2026-09-24 03:13	71.28	OK	19720	2026-09-24 03:14	71.49	OK
19721	2026-09-24 03:15	68.87	OK	19722	2026-09-24 03:16	67.99	OK
19723	2026-09-24 03:17	68.96	OK	19724	2026-09-24 03:18	72.00	OK
19725	2026-09-24 03:19	69.70	OK	19726	2026-09-24 03:20	70.53	OK
19727	2026-09-24 03:21	69.20	OK	19728	2026-09-24 03:22	70.12	OK
19729	2026-09-24 03:23	70.02	OK	19730	2026-09-24 03:24	69.57	OK
19731	2026-09-24 03:25	69.03	OK	19732	2026-09-24 03:26	68.79	OK
19733	2026-09-24 03:27	69.58	OK	19734	2026-09-24 03:28	70.69	OK
19735	2026-09-24 03:29	69.57	OK	19736	2026-09-24 03:30	73.02	OK
19737	2026-09-24 03:31	69.00	OK	19738	2026-09-24 03:32	68.80	OK
19739	2026-09-24 03:33	71.65	OK	19740	2026-09-24 03:34	69.17	OK
19741	2026-09-24 03:35	69.42	OK	19742	2026-09-24 03:36	67.35	OK
19743	2026-09-24 03:37	68.80	OK	19744	2026-09-24 03:38	72.61	OK
19745	2026-09-24 03:39	69.94	OK	19746	2026-09-24 03:40	68.47	OK
19747	2026-09-24 03:41	70.78	OK	19748	2026-09-24 03:42	69.12	OK
19749	2026-09-24 03:43	70.19	OK	19750	2026-09-24 03:44	72.93	OK
19751	2026-09-24 03:45	72.36	OK	19752	2026-09-24 03:46	70.75	OK
19753	2026-09-24 03:47	68.56	OK	19754	2026-09-24 03:48	69.48	OK
19755	2026-09-24 03:49	71.13	OK	19756	2026-09-24 03:50	68.49	OK
19757	2026-09-24 03:51	70.84	OK	19758	2026-09-24 03:52	71.48	OK
19759	2026-09-24 03:53	70.55	OK	19760	2026-09-24 03:54	69.37	OK
19761	2026-09-24 03:55	70.59	OK	19762	2026-09-24 03:56	67.97	OK
19763	2026-09-24 03:57	69.14	OK	19764	2026-09-24 03:58	71.95	OK
19765	2026-09-24 03:59	71.39	OK	19766	2026-09-24 04:00	73.13	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19767	2026-09-24 04:01	70.12	OK	19768	2026-09-24 04:02	71.99	OK
19769	2026-09-24 04:03	71.51	OK	19770	2026-09-24 04:04	70.96	OK
19771	2026-09-24 04:05	70.73	OK	19772	2026-09-24 04:06	70.25	OK
19773	2026-09-24 04:07	73.13	OK	19774	2026-09-24 04:08	72.00	OK
19775	2026-09-24 04:09	71.77	OK	19776	2026-09-24 04:10	71.25	OK
19777	2026-09-24 04:11	71.70	OK	19778	2026-09-24 04:12	69.36	OK
19779	2026-09-24 04:13	74.98	OK	19780	2026-09-24 04:14	72.49	OK
19781	2026-09-24 04:15	70.82	OK	19782	2026-09-24 04:16	73.90	OK
19783	2026-09-24 04:17	70.91	OK	19784	2026-09-24 04:18	69.88	OK
19785	2026-09-24 04:19	69.19	OK	19786	2026-09-24 04:20	71.32	OK
19787	2026-09-24 04:21	71.74	OK	19788	2026-09-24 04:22	70.32	OK
19789	2026-09-24 04:23	70.76	OK	19790	2026-09-24 04:24	71.70	OK
19791	2026-09-24 04:25	69.96	OK	19792	2026-09-24 04:26	71.06	OK
19793	2026-09-24 04:27	69.64	OK	19794	2026-09-24 04:28	70.90	OK
19795	2026-09-24 04:29	68.88	OK	19796	2026-09-24 04:30	68.18	OK
19797	2026-09-24 04:31	69.60	OK	19798	2026-09-24 04:32	71.71	OK
19799	2026-09-24 04:33	69.25	OK	19800	2026-09-24 04:34	72.21	OK
19801	2026-09-24 04:35	70.36	OK	19802	2026-09-24 04:36	69.30	OK
19803	2026-09-24 04:37	72.57	OK	19804	2026-09-24 04:38	70.77	OK
19805	2026-09-24 04:39	71.85	OK	19806	2026-09-24 04:40	72.41	OK
19807	2026-09-24 04:41	73.67	OK	19808	2026-09-24 04:42	74.61	OK
19809	2026-09-24 04:43	73.05	OK	19810	2026-09-24 04:44	72.13	OK
19811	2026-09-24 04:45	69.39	OK	19812	2026-09-24 04:46	69.38	OK
19813	2026-09-24 04:47	72.90	OK	19814	2026-09-24 04:48	71.18	OK
19815	2026-09-24 04:49	72.10	OK	19816	2026-09-24 04:50	72.03	OK
19817	2026-09-24 04:51	71.97	OK	19818	2026-09-24 04:52	70.74	OK
19819	2026-09-24 04:53	71.88	OK	19820	2026-09-24 04:54	71.67	OK
19821	2026-09-24 04:55	71.86	OK	19822	2026-09-24 04:56	73.06	OK
19823	2026-09-24 04:57	73.18	OK	19824	2026-09-24 04:58	71.66	OK
19825	2026-09-24 04:59	69.36	OK	19826	2026-09-24 05:00	74.08	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19827	2026-09-24 05:01	75.09	OK	19828	2026-09-24 05:02	70.11	OK
19829	2026-09-24 05:03	74.45	OK	19830	2026-09-24 05:04	73.07	OK
19831	2026-09-24 05:05	70.75	OK	19832	2026-09-24 05:06	72.42	OK
19833	2026-09-24 05:07	70.05	OK	19834	2026-09-24 05:08	69.74	OK
19835	2026-09-24 05:09	72.62	OK	19836	2026-09-24 05:10	74.74	OK
19837	2026-09-24 05:11	76.49	OK	19838	2026-09-24 05:12	72.01	OK
19839	2026-09-24 05:13	71.92	OK	19840	2026-09-24 05:14	73.13	OK
19841	2026-09-24 05:15	71.27	OK	19842	2026-09-24 05:16	69.85	OK
19843	2026-09-24 05:17	73.68	OK	19844	2026-09-24 05:18	76.37	OK
19845	2026-09-24 05:19	73.41	OK	19846	2026-09-24 05:20	71.74	OK
19847	2026-09-24 05:21	72.92	OK	19848	2026-09-24 05:22	72.95	OK
19849	2026-09-24 05:23	73.14	OK	19850	2026-09-24 05:24	72.88	OK
19851	2026-09-24 05:25	74.62	OK	19852	2026-09-24 05:26	71.86	OK
19853	2026-09-24 05:27	72.53	OK	19854	2026-09-24 05:28	72.14	OK
19855	2026-09-24 05:29	74.57	OK	19856	2026-09-24 05:30	72.06	OK
19857	2026-09-24 05:31	74.02	OK	19858	2026-09-24 05:32	72.93	OK
19859	2026-09-24 05:33	73.48	OK	19860	2026-09-24 05:34	75.25	OK
19861	2026-09-24 05:35	71.89	OK	19862	2026-09-24 05:36	74.46	OK
19863	2026-09-24 05:37	73.85	OK	19864	2026-09-24 05:38	73.58	OK
19865	2026-09-24 05:39	71.52	OK	19866	2026-09-24 05:40	75.87	OK
19867	2026-09-24 05:41	76.83	OK	19868	2026-09-24 05:42	70.38	OK
19869	2026-09-24 05:43	73.39	OK	19870	2026-09-24 05:44	72.04	OK
19871	2026-09-24 05:45	72.23	OK	19872	2026-09-24 05:46	75.49	OK
19873	2026-09-24 05:47	74.03	OK	19874	2026-09-24 05:48	74.31	OK
19875	2026-09-24 05:49	73.87	OK	19876	2026-09-24 05:50	74.42	OK
19877	2026-09-24 05:51	76.69	OK	19878	2026-09-24 05:52	74.50	OK
19879	2026-09-24 05:53	71.28	OK	19880	2026-09-24 05:54	75.22	OK
19881	2026-09-24 05:55	76.20	OK	19882	2026-09-24 05:56	75.16	OK
19883	2026-09-24 05:57	74.48	OK	19884	2026-09-24 05:58	73.32	OK
19885	2026-09-24 05:59	71.72	OK	19886	2026-09-24 06:00	71.80	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19887	2026-09-24 06:01	74.84	OK	19888	2026-09-24 06:02	75.61	OK
19889	2026-09-24 06:03	74.34	OK	19890	2026-09-24 06:04	74.05	OK
19891	2026-09-24 06:05	75.19	OK	19892	2026-09-24 06:06	73.86	OK
19893	2026-09-24 06:07	75.34	OK	19894	2026-09-24 06:08	71.35	OK
19895	2026-09-24 06:09	72.19	OK	19896	2026-09-24 06:10	73.79	OK
19897	2026-09-24 06:11	73.25	OK	19898	2026-09-24 06:12	75.38	OK
19899	2026-09-24 06:13	73.53	OK	19900	2026-09-24 06:14	72.46	OK
19901	2026-09-24 06:15	72.87	OK	19902	2026-09-24 06:16	75.33	OK
19903	2026-09-24 06:17	74.72	OK	19904	2026-09-24 06:18	77.64	OK
19905	2026-09-24 06:19	77.16	OK	19906	2026-09-24 06:20	74.57	OK
19907	2026-09-24 06:21	74.71	OK	19908	2026-09-24 06:22	76.69	OK
19909	2026-09-24 06:23	74.09	OK	19910	2026-09-24 06:24	72.00	OK
19911	2026-09-24 06:25	74.94	OK	19912	2026-09-24 06:26	75.33	OK
19913	2026-09-24 06:27	76.05	OK	19914	2026-09-24 06:28	73.54	OK
19915	2026-09-24 06:29	74.72	OK	19916	2026-09-24 06:30	72.74	OK
19917	2026-09-24 06:31	77.07	OK	19918	2026-09-24 06:32	75.04	OK
19919	2026-09-24 06:33	75.05	OK	19920	2026-09-24 06:34	74.41	OK
19921	2026-09-24 06:35	74.84	OK	19922	2026-09-24 06:36	78.01	OK
19923	2026-09-24 06:37	74.29	OK	19924	2026-09-24 06:38	74.32	OK
19925	2026-09-24 06:39	72.62	OK	19926	2026-09-24 06:40	72.70	OK
19927	2026-09-24 06:41	72.92	OK	19928	2026-09-24 06:42	72.61	OK
19929	2026-09-24 06:43	74.88	OK	19930	2026-09-24 06:44	75.44	OK
19931	2026-09-24 06:45	72.66	OK	19932	2026-09-24 06:46	73.68	OK
19933	2026-09-24 06:47	73.90	OK	19934	2026-09-24 06:48	76.83	OK
19935	2026-09-24 06:49	74.31	OK	19936	2026-09-24 06:50	73.44	OK
19937	2026-09-24 06:51	75.96	OK	19938	2026-09-24 06:52	74.60	OK
19939	2026-09-24 06:53	74.26	OK	19940	2026-09-24 06:54	76.01	OK
19941	2026-09-24 06:55	76.37	OK	19942	2026-09-24 06:56	75.99	OK
19943	2026-09-24 06:57	76.69	OK	19944	2026-09-24 06:58	74.00	OK
19945	2026-09-24 06:59	72.98	OK	19946	2026-09-24 07:00	74.81	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19947	2026-09-24 07:01	72.54	OK	19948	2026-09-24 07:02	74.89	OK
19949	2026-09-24 07:03	77.66	OK	19950	2026-09-24 07:04	76.75	OK
19951	2026-09-24 07:05	77.02	OK	19952	2026-09-24 07:06	76.09	OK
19953	2026-09-24 07:07	75.83	OK	19954	2026-09-24 07:08	74.08	OK
19955	2026-09-24 07:09	77.08	OK	19956	2026-09-24 07:10	73.28	OK
19957	2026-09-24 07:11	76.48	OK	19958	2026-09-24 07:12	73.53	OK
19959	2026-09-24 07:13	76.21	OK	19960	2026-09-24 07:14	76.69	OK
19961	2026-09-24 07:15	74.40	OK	19962	2026-09-24 07:16	77.74	OK
19963	2026-09-24 07:17	74.30	OK	19964	2026-09-24 07:18	75.53	OK
19965	2026-09-24 07:19	74.41	OK	19966	2026-09-24 07:20	77.80	OK
19967	2026-09-24 07:21	75.16	OK	19968	2026-09-24 07:22	75.07	OK
19969	2026-09-24 07:23	77.50	OK	19970	2026-09-24 07:24	73.52	OK
19971	2026-09-24 07:25	79.44	OK	19972	2026-09-24 07:26	78.20	OK
19973	2026-09-24 07:27	75.24	OK	19974	2026-09-24 07:28	75.72	OK
19975	2026-09-24 07:29	75.88	OK	19976	2026-09-24 07:30	78.86	OK
19977	2026-09-24 07:31	75.28	OK	19978	2026-09-24 07:32	76.15	OK
19979	2026-09-24 07:33	75.06	OK	19980	2026-09-24 07:34	77.19	OK
19981	2026-09-24 07:35	78.25	OK	19982	2026-09-24 07:36	77.00	OK
19983	2026-09-24 07:37	77.30	OK	19984	2026-09-24 07:38	74.24	OK
19985	2026-09-24 07:39	79.98	OK	19986	2026-09-24 07:40	75.15	OK
19987	2026-09-24 07:41	79.03	OK	19988	2026-09-24 07:42	79.15	OK
19989	2026-09-24 07:43	76.11	OK	19990	2026-09-24 07:44	74.77	OK
19991	2026-09-24 07:45	75.99	OK	19992	2026-09-24 07:46	76.92	OK
19993	2026-09-24 07:47	75.13	OK	19994	2026-09-24 07:48	74.26	OK
19995	2026-09-24 07:49	75.35	OK	19996	2026-09-24 07:50	76.32	OK
19997	2026-09-24 07:51	73.59	OK	19998	2026-09-24 07:52	77.04	OK
19999	2026-09-24 07:53	77.51	OK	20000	2026-09-24 07:54	77.44	OK
20001	2026-09-24 07:55	78.40	OK	20002	2026-09-24 07:56	76.24	OK
20003	2026-09-24 07:57	76.70	OK	20004	2026-09-24 07:58	75.51	OK
20005	2026-09-24 07:59	72.35	OK	20006	2026-09-24 08:00	78.53	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
20007	2026-09-24 08:01	73.82	OK	20008	2026-09-24 08:02	73.45	OK
20009	2026-09-24 08:03	76.79	OK	20010	2026-09-24 08:04	76.36	OK
20011	2026-09-24 08:05	74.60	OK	20012	2026-09-24 08:06	78.93	OK
20013	2026-09-24 08:07	77.50	OK	20014	2026-09-24 08:08	73.71	OK
20015	2026-09-24 08:09	76.50	OK	20016	2026-09-24 08:10	73.35	OK
20017	2026-09-24 08:11	75.89	OK	20018	2026-09-24 08:12	74.43	OK
20019	2026-09-24 08:13	75.77	OK	20020	2026-09-24 08:14	77.71	OK
20021	2026-09-24 08:15	76.67	OK	20022	2026-09-24 08:16	76.84	OK
20023	2026-09-24 08:17	80.53	OK	20024	2026-09-24 08:18	77.83	OK
20025	2026-09-24 08:19	75.35	OK	20026	2026-09-24 08:20	75.96	OK
20027	2026-09-24 08:21	78.86	OK	20028	2026-09-24 08:22	77.89	OK
20029	2026-09-24 08:23	77.69	OK	20030	2026-09-24 08:24	78.91	OK
20031	2026-09-24 08:25	77.53	OK	20032	2026-09-24 08:26	76.30	OK
20033	2026-09-24 08:27	76.25	OK	20034	2026-09-24 08:28	78.67	OK
20035	2026-09-24 08:29	76.26	OK	20036	2026-09-24 08:30	77.03	OK
20037	2026-09-24 08:31	78.93	OK	20038	2026-09-24 08:32	75.88	OK
20039	2026-09-24 08:33	75.48	OK	20040	2026-09-24 08:34	75.69	OK
20041	2026-09-24 08:35	77.88	OK	20042	2026-09-24 08:36	75.83	OK
20043	2026-09-24 08:37	78.53	OK	20044	2026-09-24 08:38	80.05	OK
20045	2026-09-24 08:39	77.97	OK	20046	2026-09-24 08:40	79.41	OK
20047	2026-09-24 08:41	78.20	OK	20048	2026-09-24 08:42	78.84	OK
20049	2026-09-24 08:43	78.70	OK	20050	2026-09-24 08:44	80.60	OK
20051	2026-09-24 08:45	75.82	OK	20052	2026-09-24 08:46	76.06	OK
20053	2026-09-24 08:47	79.04	OK	20054	2026-09-24 08:48	80.14	OK
20055	2026-09-24 08:49	81.22	OK	20056	2026-09-24 08:50	75.94	OK
20057	2026-09-24 08:51	76.31	OK	20058	2026-09-24 08:52	77.87	OK
20059	2026-09-24 08:53	80.22	OK	20060	2026-09-24 08:54	78.44	OK
20061	2026-09-24 08:55	80.37	OK	20062	2026-09-24 08:56	79.13	OK
20063	2026-09-24 08:57	75.88	OK	20064	2026-09-24 08:58	81.82	OK
20065	2026-09-24 08:59	78.44	OK	20066	2026-09-24 09:00	81.30	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
20067	2026-09-24 09:01	80.68	OK	20068	2026-09-24 09:02	79.95	OK
20069	2026-09-24 09:03	77.19	OK	20070	2026-09-24 09:04	75.24	OK
20071	2026-09-24 09:05	78.18	OK	20072	2026-09-24 09:06	79.50	OK
20073	2026-09-24 09:07	78.12	OK	20074	2026-09-24 09:08	77.60	OK
20075	2026-09-24 09:09	74.70	OK	20076	2026-09-24 09:10	78.55	OK
20077	2026-09-24 09:11	77.87	OK	20078	2026-09-24 09:12	77.93	OK
20079	2026-09-24 09:13	78.88	OK	20080	2026-09-24 09:14	76.73	OK
20081	2026-09-24 09:15	79.25	OK	20082	2026-09-24 09:16	78.56	OK
20083	2026-09-24 09:17	78.47	OK	20084	2026-09-24 09:18	78.44	OK
20085	2026-09-24 09:19	78.03	OK	20086	2026-09-24 09:20	78.11	OK
20087	2026-09-24 09:21	80.01	OK	20088	2026-09-24 09:22	81.31	OK
20089	2026-09-24 09:23	77.17	OK	20090	2026-09-24 09:24	78.18	OK
20091	2026-09-24 09:25	82.09	OK	20092	2026-09-24 09:26	80.22	OK
20093	2026-09-24 09:27	78.12	OK	20094	2026-09-24 09:28	78.50	OK
20095	2026-09-24 09:29	82.24	OK	20096	2026-09-24 09:30	79.84	OK
20097	2026-09-24 09:31	78.05	OK	20098	2026-09-24 09:32	78.51	OK
20099	2026-09-24 09:33	78.59	OK	20100	2026-09-24 09:34	80.23	OK
20101	2026-09-24 09:35	79.33	OK	20102	2026-09-24 09:36	80.66	OK
20103	2026-09-24 09:37	80.03	OK	20104	2026-09-24 09:38	81.15	OK
20105	2026-09-24 09:39	79.15	OK	20106	2026-09-24 09:40	76.72	OK
20107	2026-09-24 09:41	79.47	OK	20108	2026-09-24 09:42	78.53	OK
20109	2026-09-24 09:43	75.89	OK	20110	2026-09-24 09:44	81.15	OK
20111	2026-09-24 09:45	81.24	OK	20112	2026-09-24 09:46	75.95	OK
20113	2026-09-24 09:47	81.78	OK	20114	2026-09-24 09:48	81.55	OK
20115	2026-09-24 09:49	79.26	OK	20116	2026-09-24 09:50	77.33	OK
20117	2026-09-24 09:51	80.42	OK	20118	2026-09-24 09:52	80.00	OK
20119	2026-09-24 09:53	79.36	OK	20120	2026-09-24 09:54	81.45	OK
20121	2026-09-24 09:55	78.58	OK	20122	2026-09-24 09:56	76.21	OK
20123	2026-09-24 09:57	79.01	OK	20124	2026-09-24 09:58	79.73	OK
20125	2026-09-24 09:59	78.24	OK	20126	2026-09-24 10:00	80.90	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
20127	2026-09-24 10:01	78.75	OK	20128	2026-09-24 10:02	78.11	OK
20129	2026-09-24 10:03	80.11	OK	20130	2026-09-24 10:04	81.13	OK
20131	2026-09-24 10:05	80.34	OK	20132	2026-09-24 10:06	81.68	OK
20133	2026-09-24 10:07	78.53	OK	20134	2026-09-24 10:08	81.79	OK
20135	2026-09-24 10:09	78.40	OK	20136	2026-09-24 10:10	79.02	OK
20137	2026-09-24 10:11	82.64	OK	20138	2026-09-24 10:12	76.87	OK
20139	2026-09-24 10:13	79.82	OK	20140	2026-09-24 10:14	78.23	OK
20141	2026-09-24 10:15	79.13	OK	20142	2026-09-24 10:16	78.67	OK
20143	2026-09-24 10:17	81.21	OK	20144	2026-09-24 10:18	81.09	OK
20145	2026-09-24 10:19	80.27	OK	20146	2026-09-24 10:20	79.55	OK
20147	2026-09-24 10:21	83.28	OK	20148	2026-09-24 10:22	82.52	OK
20149	2026-09-24 10:23	80.42	OK	20150	2026-09-24 10:24	81.73	OK
20151	2026-09-24 10:25	79.85	OK	20152	2026-09-24 10:26	78.61	OK
20153	2026-09-24 10:27	82.09	OK	20154	2026-09-24 10:28	80.80	OK
20155	2026-09-24 10:29	78.87	OK	20156	2026-09-24 10:30	77.86	OK
20157	2026-09-24 10:31	81.91	OK	20158	2026-09-24 10:32	80.75	OK
20159	2026-09-24 10:33	81.35	OK	20160	2026-09-24 10:34	78.95	OK
20161	2026-09-24 10:35	79.39	OK				

Signal: Bearing_Temp_DE (°C)

Operating Limits: [10.0 to 95.0] • Observed: Min 42.44, Max 54.61, Mean 48.52

All 20,161 Raw Readings

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1	2026-09-10 10:35	50.87	OK	2	2026-09-10 10:36	52.72	OK
3	2026-09-10 10:37	51.22	OK	4	2026-09-10 10:38	51.98	OK
5	2026-09-10 10:39	49.45	OK	6	2026-09-10 10:40	49.82	OK
7	2026-09-10 10:41	50.91	OK	8	2026-09-10 10:42	51.77	OK
9	2026-09-10 10:43	48.34	OK	10	2026-09-10 10:44	51.12	OK
11	2026-09-10 10:45	52.28	OK	12	2026-09-10 10:46	50.73	OK
13	2026-09-10 10:47	50.42	OK	14	2026-09-10 10:48	51.58	OK
15	2026-09-10 10:49	49.76	OK	16	2026-09-10 10:50	51.99	OK
17	2026-09-10 10:51	51.77	OK	18	2026-09-10 10:52	50.34	OK
19	2026-09-10 10:53	51.52	OK	20	2026-09-10 10:54	49.88	OK
21	2026-09-10 10:55	48.51	OK	22	2026-09-10 10:56	52.19	OK
23	2026-09-10 10:57	50.26	OK	24	2026-09-10 10:58	50.88	OK
25	2026-09-10 10:59	50.71	OK	26	2026-09-10 11:00	51.92	OK
27	2026-09-10 11:01	52.05	OK	28	2026-09-10 11:02	50.80	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
29	2026-09-10 11:03	50.50	OK	30	2026-09-10 11:04	52.00	OK
31	2026-09-10 11:05	50.93	OK	32	2026-09-10 11:06	52.74	OK
33	2026-09-10 11:07	50.36	OK	34	2026-09-10 11:08	52.17	OK
35	2026-09-10 11:09	48.73	OK	36	2026-09-10 11:10	51.33	OK
37	2026-09-10 11:11	50.90	OK	38	2026-09-10 11:12	52.21	OK
39	2026-09-10 11:13	52.18	OK	40	2026-09-10 11:14	50.95	OK
41	2026-09-10 11:15	50.93	OK	42	2026-09-10 11:16	50.31	OK
43	2026-09-10 11:17	50.28	OK	44	2026-09-10 11:18	52.33	OK
45	2026-09-10 11:19	50.07	OK	46	2026-09-10 11:20	51.11	OK
47	2026-09-10 11:21	52.26	OK	48	2026-09-10 11:22	51.83	OK
49	2026-09-10 11:23	53.24	OK	50	2026-09-10 11:24	52.15	OK
51	2026-09-10 11:25	53.30	OK	52	2026-09-10 11:26	50.88	OK
53	2026-09-10 11:27	52.13	OK	54	2026-09-10 11:28	52.86	OK
55	2026-09-10 11:29	53.24	OK	56	2026-09-10 11:30	49.08	OK
57	2026-09-10 11:31	51.48	OK	58	2026-09-10 11:32	51.90	OK
59	2026-09-10 11:33	50.51	OK	60	2026-09-10 11:34	51.89	OK
61	2026-09-10 11:35	52.31	OK	62	2026-09-10 11:36	51.26	OK
63	2026-09-10 11:37	52.05	OK	64	2026-09-10 11:38	53.44	OK
65	2026-09-10 11:39	51.75	OK	66	2026-09-10 11:40	51.32	OK
67	2026-09-10 11:41	50.37	OK	68	2026-09-10 11:42	51.18	OK
69	2026-09-10 11:43	50.60	OK	70	2026-09-10 11:44	50.60	OK
71	2026-09-10 11:45	51.57	OK	72	2026-09-10 11:46	52.30	OK
73	2026-09-10 11:47	52.70	OK	74	2026-09-10 11:48	50.78	OK
75	2026-09-10 11:49	51.54	OK	76	2026-09-10 11:50	52.83	OK
77	2026-09-10 11:51	50.96	OK	78	2026-09-10 11:52	51.22	OK
79	2026-09-10 11:53	51.45	OK	80	2026-09-10 11:54	51.05	OK
81	2026-09-10 11:55	52.07	OK	82	2026-09-10 11:56	51.74	OK
83	2026-09-10 11:57	51.28	OK	84	2026-09-10 11:58	53.29	OK
85	2026-09-10 11:59	51.26	OK	86	2026-09-10 12:00	52.64	OK
87	2026-09-10 12:01	51.71	OK	88	2026-09-10 12:02	50.78	OK
89	2026-09-10 12:03	51.38	OK	90	2026-09-10 12:04	52.81	OK
91	2026-09-10 12:05	51.84	OK	92	2026-09-10 12:06	51.95	OK
93	2026-09-10 12:07	52.68	OK	94	2026-09-10 12:08	50.93	OK
95	2026-09-10 12:09	54.07	OK	96	2026-09-10 12:10	50.35	OK
97	2026-09-10 12:11	53.19	OK	98	2026-09-10 12:12	50.95	OK
99	2026-09-10 12:13	52.81	OK	100	2026-09-10 12:14	50.78	OK
101	2026-09-10 12:15	51.44	OK	102	2026-09-10 12:16	50.79	OK
103	2026-09-10 12:17	54.17	OK	104	2026-09-10 12:18	52.25	OK
105	2026-09-10 12:19	51.63	OK	106	2026-09-10 12:20	51.90	OK
107	2026-09-10 12:21	51.05	OK	108	2026-09-10 12:22	54.49	OK
109	2026-09-10 12:23	52.83	OK	110	2026-09-10 12:24	52.03	OK
111	2026-09-10 12:25	52.87	OK	112	2026-09-10 12:26	53.02	OK
113	2026-09-10 12:27	53.26	OK	114	2026-09-10 12:28	52.56	OK
115	2026-09-10 12:29	51.68	OK	116	2026-09-10 12:30	51.30	OK
117	2026-09-10 12:31	52.48	OK	118	2026-09-10 12:32	50.69	OK
119	2026-09-10 12:33	51.87	OK	120	2026-09-10 12:34	52.97	OK
121	2026-09-10 12:35	51.76	OK	122	2026-09-10 12:36	51.35	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
123	2026-09-10 12:37	51.20	OK	124	2026-09-10 12:38	51.23	OK
125	2026-09-10 12:39	52.20	OK	126	2026-09-10 12:40	52.40	OK
127	2026-09-10 12:41	50.49	OK	128	2026-09-10 12:42	49.88	OK
129	2026-09-10 12:43	51.88	OK	130	2026-09-10 12:44	52.53	OK
131	2026-09-10 12:45	51.06	OK	132	2026-09-10 12:46	52.35	OK
133	2026-09-10 12:47	52.88	OK	134	2026-09-10 12:48	52.13	OK
135	2026-09-10 12:49	53.21	OK	136	2026-09-10 12:50	52.73	OK
137	2026-09-10 12:51	49.35	OK	138	2026-09-10 12:52	52.10	OK
139	2026-09-10 12:53	52.65	OK	140	2026-09-10 12:54	51.17	OK
141	2026-09-10 12:55	52.68	OK	142	2026-09-10 12:56	51.85	OK
143	2026-09-10 12:57	51.02	OK	144	2026-09-10 12:58	52.91	OK
145	2026-09-10 12:59	51.38	OK	146	2026-09-10 13:00	51.65	OK
147	2026-09-10 13:01	50.25	OK	148	2026-09-10 13:02	50.91	OK
149	2026-09-10 13:03	50.12	OK	150	2026-09-10 13:04	52.37	OK
151	2026-09-10 13:05	50.94	OK	152	2026-09-10 13:06	52.46	OK
153	2026-09-10 13:07	51.16	OK	154	2026-09-10 13:08	52.86	OK
155	2026-09-10 13:09	52.33	OK	156	2026-09-10 13:10	53.36	OK
157	2026-09-10 13:11	52.70	OK	158	2026-09-10 13:12	52.30	OK
159	2026-09-10 13:13	51.99	OK	160	2026-09-10 13:14	51.38	OK
161	2026-09-10 13:15	52.15	OK	162	2026-09-10 13:16	51.79	OK
163	2026-09-10 13:17	51.24	OK	164	2026-09-10 13:18	53.35	OK
165	2026-09-10 13:19	52.03	OK	166	2026-09-10 13:20	52.65	OK
167	2026-09-10 13:21	51.47	OK	168	2026-09-10 13:22	53.14	OK
169	2026-09-10 13:23	51.56	OK	170	2026-09-10 13:24	51.97	OK
171	2026-09-10 13:25	53.40	OK	172	2026-09-10 13:26	52.25	OK
173	2026-09-10 13:27	50.89	OK	174	2026-09-10 13:28	53.44	OK
175	2026-09-10 13:29	50.11	OK	176	2026-09-10 13:30	51.48	OK
177	2026-09-10 13:31	52.85	OK	178	2026-09-10 13:32	51.03	OK
179	2026-09-10 13:33	52.79	OK	180	2026-09-10 13:34	50.78	OK
181	2026-09-10 13:35	52.86	OK	182	2026-09-10 13:36	50.92	OK
183	2026-09-10 13:37	52.52	OK	184	2026-09-10 13:38	52.24	OK
185	2026-09-10 13:39	51.53	OK	186	2026-09-10 13:40	51.61	OK
187	2026-09-10 13:41	52.23	OK	188	2026-09-10 13:42	50.77	OK
189	2026-09-10 13:43	50.41	OK	190	2026-09-10 13:44	50.17	OK
191	2026-09-10 13:45	50.60	OK	192	2026-09-10 13:46	52.75	OK
193	2026-09-10 13:47	51.54	OK	194	2026-09-10 13:48	51.29	OK
195	2026-09-10 13:49	52.95	OK	196	2026-09-10 13:50	49.95	OK
197	2026-09-10 13:51	51.90	OK	198	2026-09-10 13:52	52.48	OK
199	2026-09-10 13:53	51.69	OK	200	2026-09-10 13:54	51.05	OK
201	2026-09-10 13:55	51.03	OK	202	2026-09-10 13:56	52.54	OK
203	2026-09-10 13:57	51.42	OK	204	2026-09-10 13:58	51.40	OK
205	2026-09-10 13:59	53.11	OK	206	2026-09-10 14:00	51.67	OK
207	2026-09-10 14:01	50.91	OK	208	2026-09-10 14:02	50.03	OK
209	2026-09-10 14:03	51.73	OK	210	2026-09-10 14:04	51.92	OK
211	2026-09-10 14:05	53.06	OK	212	2026-09-10 14:06	51.66	OK
213	2026-09-10 14:07	52.12	OK	214	2026-09-10 14:08	50.97	OK
215	2026-09-10 14:09	50.81	OK	216	2026-09-10 14:10	53.65	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
217	2026-09-10 14:11	52.53	OK	218	2026-09-10 14:12	51.24	OK
219	2026-09-10 14:13	52.21	OK	220	2026-09-10 14:14	52.41	OK
221	2026-09-10 14:15	51.36	OK	222	2026-09-10 14:16	49.83	OK
223	2026-09-10 14:17	51.25	OK	224	2026-09-10 14:18	51.51	OK
225	2026-09-10 14:19	53.84	OK	226	2026-09-10 14:20	51.73	OK
227	2026-09-10 14:21	51.24	OK	228	2026-09-10 14:22	50.65	OK
229	2026-09-10 14:23	51.07	OK	230	2026-09-10 14:24	52.42	OK
231	2026-09-10 14:25	52.53	OK	232	2026-09-10 14:26	51.46	OK
233	2026-09-10 14:27	54.01	OK	234	2026-09-10 14:28	53.31	OK
235	2026-09-10 14:29	51.52	OK	236	2026-09-10 14:30	51.90	OK
237	2026-09-10 14:31	50.54	OK	238	2026-09-10 14:32	51.05	OK
239	2026-09-10 14:33	53.41	OK	240	2026-09-10 14:34	53.27	OK
241	2026-09-10 14:35	50.01	OK	242	2026-09-10 14:36	51.52	OK
243	2026-09-10 14:37	50.60	OK	244	2026-09-10 14:38	52.12	OK
245	2026-09-10 14:39	52.81	OK	246	2026-09-10 14:40	51.48	OK
247	2026-09-10 14:41	50.63	OK	248	2026-09-10 14:42	50.54	OK
249	2026-09-10 14:43	51.27	OK	250	2026-09-10 14:44	51.86	OK
251	2026-09-10 14:45	51.51	OK	252	2026-09-10 14:46	49.82	OK
253	2026-09-10 14:47	52.78	OK	254	2026-09-10 14:48	52.91	OK
255	2026-09-10 14:49	51.34	OK	256	2026-09-10 14:50	50.54	OK
257	2026-09-10 14:51	51.38	OK	258	2026-09-10 14:52	51.77	OK
259	2026-09-10 14:53	51.32	OK	260	2026-09-10 14:54	50.44	OK
261	2026-09-10 14:55	51.88	OK	262	2026-09-10 14:56	51.53	OK
263	2026-09-10 14:57	53.23	OK	264	2026-09-10 14:58	51.69	OK
265	2026-09-10 14:59	50.61	OK	266	2026-09-10 15:00	50.69	OK
267	2026-09-10 15:01	51.77	OK	268	2026-09-10 15:02	51.29	OK
269	2026-09-10 15:03	49.69	OK	270	2026-09-10 15:04	52.10	OK
271	2026-09-10 15:05	51.44	OK	272	2026-09-10 15:06	49.91	OK
273	2026-09-10 15:07	52.20	OK	274	2026-09-10 15:08	53.65	OK
275	2026-09-10 15:09	49.74	OK	276	2026-09-10 15:10	53.31	OK
277	2026-09-10 15:11	51.31	OK	278	2026-09-10 15:12	51.41	OK
279	2026-09-10 15:13	49.57	OK	280	2026-09-10 15:14	51.52	OK
281	2026-09-10 15:15	50.48	OK	282	2026-09-10 15:16	49.54	OK
283	2026-09-10 15:17	49.96	OK	284	2026-09-10 15:18	51.01	OK
285	2026-09-10 15:19	51.29	OK	286	2026-09-10 15:20	51.11	OK
287	2026-09-10 15:21	49.71	OK	288	2026-09-10 15:22	51.36	OK
289	2026-09-10 15:23	52.62	OK	290	2026-09-10 15:24	50.83	OK
291	2026-09-10 15:25	52.30	OK	292	2026-09-10 15:26	51.20	OK
293	2026-09-10 15:27	52.12	OK	294	2026-09-10 15:28	52.78	OK
295	2026-09-10 15:29	51.64	OK	296	2026-09-10 15:30	51.76	OK
297	2026-09-10 15:31	51.01	OK	298	2026-09-10 15:32	52.96	OK
299	2026-09-10 15:33	50.45	OK	300	2026-09-10 15:34	50.22	OK
301	2026-09-10 15:35	51.81	OK	302	2026-09-10 15:36	50.98	OK
303	2026-09-10 15:37	51.74	OK	304	2026-09-10 15:38	51.54	OK
305	2026-09-10 15:39	50.17	OK	306	2026-09-10 15:40	50.65	OK
307	2026-09-10 15:41	51.29	OK	308	2026-09-10 15:42	50.94	OK
309	2026-09-10 15:43	51.31	OK	310	2026-09-10 15:44	50.19	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
311	2026-09-10 15:45	51.94	OK	312	2026-09-10 15:46	51.29	OK
313	2026-09-10 15:47	51.27	OK	314	2026-09-10 15:48	49.59	OK
315	2026-09-10 15:49	49.57	OK	316	2026-09-10 15:50	49.49	OK
317	2026-09-10 15:51	50.17	OK	318	2026-09-10 15:52	51.82	OK
319	2026-09-10 15:53	50.79	OK	320	2026-09-10 15:54	52.41	OK
321	2026-09-10 15:55	50.03	OK	322	2026-09-10 15:56	50.20	OK
323	2026-09-10 15:57	50.95	OK	324	2026-09-10 15:58	51.82	OK
325	2026-09-10 15:59	51.93	OK	326	2026-09-10 16:00	51.38	OK
327	2026-09-10 16:01	50.96	OK	328	2026-09-10 16:02	52.76	OK
329	2026-09-10 16:03	51.98	OK	330	2026-09-10 16:04	49.37	OK
331	2026-09-10 16:05	52.92	OK	332	2026-09-10 16:06	51.62	OK
333	2026-09-10 16:07	51.48	OK	334	2026-09-10 16:08	52.31	OK
335	2026-09-10 16:09	51.28	OK	336	2026-09-10 16:10	49.78	OK
337	2026-09-10 16:11	51.47	OK	338	2026-09-10 16:12	50.27	OK
339	2026-09-10 16:13	50.52	OK	340	2026-09-10 16:14	50.56	OK
341	2026-09-10 16:15	52.66	OK	342	2026-09-10 16:16	52.81	OK
343	2026-09-10 16:17	51.11	OK	344	2026-09-10 16:18	52.32	OK
345	2026-09-10 16:19	50.90	OK	346	2026-09-10 16:20	49.70	OK
347	2026-09-10 16:21	50.62	OK	348	2026-09-10 16:22	50.01	OK
349	2026-09-10 16:23	50.05	OK	350	2026-09-10 16:24	52.01	OK
351	2026-09-10 16:25	50.73	OK	352	2026-09-10 16:26	49.28	OK
353	2026-09-10 16:27	51.69	OK	354	2026-09-10 16:28	52.06	OK
355	2026-09-10 16:29	50.54	OK	356	2026-09-10 16:30	49.42	OK
357	2026-09-10 16:31	49.64	OK	358	2026-09-10 16:32	49.87	OK
359	2026-09-10 16:33	51.63	OK	360	2026-09-10 16:34	49.03	OK
361	2026-09-10 16:35	49.24	OK	362	2026-09-10 16:36	52.73	OK
363	2026-09-10 16:37	51.82	OK	364	2026-09-10 16:38	49.87	OK
365	2026-09-10 16:39	48.95	OK	366	2026-09-10 16:40	50.12	OK
367	2026-09-10 16:41	51.46	OK	368	2026-09-10 16:42	50.91	OK
369	2026-09-10 16:43	51.54	OK	370	2026-09-10 16:44	50.22	OK
371	2026-09-10 16:45	51.55	OK	372	2026-09-10 16:46	51.65	OK
373	2026-09-10 16:47	49.48	OK	374	2026-09-10 16:48	51.15	OK
375	2026-09-10 16:49	48.10	OK	376	2026-09-10 16:50	51.95	OK
377	2026-09-10 16:51	52.27	OK	378	2026-09-10 16:52	51.20	OK
379	2026-09-10 16:53	49.63	OK	380	2026-09-10 16:54	49.78	OK
381	2026-09-10 16:55	50.52	OK	382	2026-09-10 16:56	49.30	OK
383	2026-09-10 16:57	50.13	OK	384	2026-09-10 16:58	50.81	OK
385	2026-09-10 16:59	49.84	OK	386	2026-09-10 17:00	49.26	OK
387	2026-09-10 17:01	51.41	OK	388	2026-09-10 17:02	49.91	OK
389	2026-09-10 17:03	51.08	OK	390	2026-09-10 17:04	49.75	OK
391	2026-09-10 17:05	50.39	OK	392	2026-09-10 17:06	48.91	OK
393	2026-09-10 17:07	49.57	OK	394	2026-09-10 17:08	50.88	OK
395	2026-09-10 17:09	49.25	OK	396	2026-09-10 17:10	50.00	OK
397	2026-09-10 17:11	50.74	OK	398	2026-09-10 17:12	51.08	OK
399	2026-09-10 17:13	51.29	OK	400	2026-09-10 17:14	51.61	OK
401	2026-09-10 17:15	48.57	OK	402	2026-09-10 17:16	51.54	OK
403	2026-09-10 17:17	49.81	OK	404	2026-09-10 17:18	49.68	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
405	2026-09-10 17:19	49.40	OK	406	2026-09-10 17:20	50.20	OK
407	2026-09-10 17:21	51.40	OK	408	2026-09-10 17:22	51.26	OK
409	2026-09-10 17:23	49.51	OK	410	2026-09-10 17:24	49.36	OK
411	2026-09-10 17:25	49.58	OK	412	2026-09-10 17:26	50.13	OK
413	2026-09-10 17:27	49.10	OK	414	2026-09-10 17:28	48.32	OK
415	2026-09-10 17:29	49.73	OK	416	2026-09-10 17:30	49.06	OK
417	2026-09-10 17:31	50.47	OK	418	2026-09-10 17:32	49.65	OK
419	2026-09-10 17:33	50.44	OK	420	2026-09-10 17:34	49.74	OK
421	2026-09-10 17:35	51.32	OK	422	2026-09-10 17:36	51.47	OK
423	2026-09-10 17:37	49.50	OK	424	2026-09-10 17:38	50.34	OK
425	2026-09-10 17:39	49.33	OK	426	2026-09-10 17:40	50.48	OK
427	2026-09-10 17:41	48.51	OK	428	2026-09-10 17:42	49.71	OK
429	2026-09-10 17:43	50.32	OK	430	2026-09-10 17:44	49.60	OK
431	2026-09-10 17:45	48.64	OK	432	2026-09-10 17:46	47.69	OK
433	2026-09-10 17:47	47.55	OK	434	2026-09-10 17:48	48.87	OK
435	2026-09-10 17:49	50.91	OK	436	2026-09-10 17:50	51.69	OK
437	2026-09-10 17:51	49.42	OK	438	2026-09-10 17:52	50.37	OK
439	2026-09-10 17:53	48.90	OK	440	2026-09-10 17:54	48.64	OK
441	2026-09-10 17:55	48.76	OK	442	2026-09-10 17:56	49.08	OK
443	2026-09-10 17:57	49.24	OK	444	2026-09-10 17:58	49.36	OK
445	2026-09-10 17:59	50.69	OK	446	2026-09-10 18:00	50.16	OK
447	2026-09-10 18:01	49.51	OK	448	2026-09-10 18:02	49.38	OK
449	2026-09-10 18:03	48.36	OK	450	2026-09-10 18:04	47.28	OK
451	2026-09-10 18:05	49.08	OK	452	2026-09-10 18:06	50.43	OK
453	2026-09-10 18:07	50.42	OK	454	2026-09-10 18:08	49.75	OK
455	2026-09-10 18:09	48.16	OK	456	2026-09-10 18:10	49.49	OK
457	2026-09-10 18:11	51.17	OK	458	2026-09-10 18:12	49.93	OK
459	2026-09-10 18:13	50.73	OK	460	2026-09-10 18:14	50.20	OK
461	2026-09-10 18:15	49.68	OK	462	2026-09-10 18:16	48.63	OK
463	2026-09-10 18:17	49.91	OK	464	2026-09-10 18:18	48.52	OK
465	2026-09-10 18:19	50.05	OK	466	2026-09-10 18:20	49.51	OK
467	2026-09-10 18:21	48.05	OK	468	2026-09-10 18:22	48.67	OK
469	2026-09-10 18:23	48.38	OK	470	2026-09-10 18:24	49.49	OK
471	2026-09-10 18:25	50.03	OK	472	2026-09-10 18:26	48.86	OK
473	2026-09-10 18:27	49.95	OK	474	2026-09-10 18:28	49.06	OK
475	2026-09-10 18:29	47.06	OK	476	2026-09-10 18:30	48.51	OK
477	2026-09-10 18:31	50.14	OK	478	2026-09-10 18:32	48.83	OK
479	2026-09-10 18:33	48.69	OK	480	2026-09-10 18:34	48.56	OK
481	2026-09-10 18:35	48.13	OK	482	2026-09-10 18:36	50.68	OK
483	2026-09-10 18:37	48.36	OK	484	2026-09-10 18:38	50.64	OK
485	2026-09-10 18:39	49.58	OK	486	2026-09-10 18:40	48.00	OK
487	2026-09-10 18:41	49.11	OK	488	2026-09-10 18:42	49.22	OK
489	2026-09-10 18:43	49.77	OK	490	2026-09-10 18:44	47.47	OK
491	2026-09-10 18:45	49.45	OK	492	2026-09-10 18:46	49.24	OK
493	2026-09-10 18:47	48.98	OK	494	2026-09-10 18:48	49.42	OK
495	2026-09-10 18:49	49.12	OK	496	2026-09-10 18:50	49.95	OK
497	2026-09-10 18:51	49.21	OK	498	2026-09-10 18:52	48.50	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
499	2026-09-10 18:53	50.09	OK	500	2026-09-10 18:54	48.65	OK
501	2026-09-10 18:55	48.84	OK	502	2026-09-10 18:56	49.97	OK
503	2026-09-10 18:57	48.91	OK	504	2026-09-10 18:58	48.36	OK
505	2026-09-10 18:59	50.08	OK	506	2026-09-10 19:00	51.00	OK
507	2026-09-10 19:01	49.35	OK	508	2026-09-10 19:02	48.09	OK
509	2026-09-10 19:03	49.97	OK	510	2026-09-10 19:04	49.43	OK
511	2026-09-10 19:05	49.24	OK	512	2026-09-10 19:06	48.40	OK
513	2026-09-10 19:07	48.88	OK	514	2026-09-10 19:08	50.39	OK
515	2026-09-10 19:09	47.65	OK	516	2026-09-10 19:10	47.71	OK
517	2026-09-10 19:11	47.91	OK	518	2026-09-10 19:12	47.47	OK
519	2026-09-10 19:13	49.42	OK	520	2026-09-10 19:14	49.65	OK
521	2026-09-10 19:15	49.54	OK	522	2026-09-10 19:16	49.49	OK
523	2026-09-10 19:17	49.94	OK	524	2026-09-10 19:18	50.03	OK
525	2026-09-10 19:19	48.66	OK	526	2026-09-10 19:20	47.85	OK
527	2026-09-10 19:21	49.22	OK	528	2026-09-10 19:22	46.81	OK
529	2026-09-10 19:23	47.36	OK	530	2026-09-10 19:24	49.55	OK
531	2026-09-10 19:25	47.88	OK	532	2026-09-10 19:26	48.14	OK
533	2026-09-10 19:27	49.23	OK	534	2026-09-10 19:28	48.55	OK
535	2026-09-10 19:29	48.39	OK	536	2026-09-10 19:30	47.59	OK
537	2026-09-10 19:31	49.52	OK	538	2026-09-10 19:32	48.72	OK
539	2026-09-10 19:33	48.52	OK	540	2026-09-10 19:34	49.15	OK
541	2026-09-10 19:35	49.07	OK	542	2026-09-10 19:36	45.89	OK
543	2026-09-10 19:37	48.88	OK	544	2026-09-10 19:38	47.28	OK
545	2026-09-10 19:39	48.14	OK	546	2026-09-10 19:40	46.28	OK
547	2026-09-10 19:41	49.04	OK	548	2026-09-10 19:42	47.47	OK
549	2026-09-10 19:43	47.86	OK	550	2026-09-10 19:44	49.47	OK
551	2026-09-10 19:45	48.44	OK	552	2026-09-10 19:46	47.34	OK
553	2026-09-10 19:47	47.74	OK	554	2026-09-10 19:48	49.22	OK
555	2026-09-10 19:49	47.04	OK	556	2026-09-10 19:50	48.11	OK
557	2026-09-10 19:51	47.81	OK	558	2026-09-10 19:52	46.98	OK
559	2026-09-10 19:53	47.59	OK	560	2026-09-10 19:54	49.22	OK
561	2026-09-10 19:55	46.94	OK	562	2026-09-10 19:56	48.31	OK
563	2026-09-10 19:57	47.92	OK	564	2026-09-10 19:58	47.92	OK
565	2026-09-10 19:59	46.83	OK	566	2026-09-10 20:00	49.48	OK
567	2026-09-10 20:01	49.47	OK	568	2026-09-10 20:02	47.95	OK
569	2026-09-10 20:03	47.38	OK	570	2026-09-10 20:04	46.98	OK
571	2026-09-10 20:05	47.69	OK	572	2026-09-10 20:06	48.31	OK
573	2026-09-10 20:07	47.96	OK	574	2026-09-10 20:08	46.44	OK
575	2026-09-10 20:09	48.78	OK	576	2026-09-10 20:10	49.65	OK
577	2026-09-10 20:11	46.70	OK	578	2026-09-10 20:12	46.95	OK
579	2026-09-10 20:13	49.27	OK	580	2026-09-10 20:14	46.73	OK
581	2026-09-10 20:15	47.90	OK	582	2026-09-10 20:16	46.90	OK
583	2026-09-10 20:17	47.47	OK	584	2026-09-10 20:18	48.19	OK
585	2026-09-10 20:19	46.12	OK	586	2026-09-10 20:20	48.51	OK
587	2026-09-10 20:21	47.63	OK	588	2026-09-10 20:22	49.26	OK
589	2026-09-10 20:23	46.10	OK	590	2026-09-10 20:24	45.93	OK
591	2026-09-10 20:25	48.89	OK	592	2026-09-10 20:26	45.72	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
593	2026-09-10 20:27	46.70	OK	594	2026-09-10 20:28	46.77	OK
595	2026-09-10 20:29	45.60	OK	596	2026-09-10 20:30	47.52	OK
597	2026-09-10 20:31	47.80	OK	598	2026-09-10 20:32	45.03	OK
599	2026-09-10 20:33	47.16	OK	600	2026-09-10 20:34	47.37	OK
601	2026-09-10 20:35	46.11	OK	602	2026-09-10 20:36	47.52	OK
603	2026-09-10 20:37	46.83	OK	604	2026-09-10 20:38	48.45	OK
605	2026-09-10 20:39	49.22	OK	606	2026-09-10 20:40	45.72	OK
607	2026-09-10 20:41	46.73	OK	608	2026-09-10 20:42	45.69	OK
609	2026-09-10 20:43	47.49	OK	610	2026-09-10 20:44	46.72	OK
611	2026-09-10 20:45	44.88	OK	612	2026-09-10 20:46	46.97	OK
613	2026-09-10 20:47	47.55	OK	614	2026-09-10 20:48	46.47	OK
615	2026-09-10 20:49	45.58	OK	616	2026-09-10 20:50	46.17	OK
617	2026-09-10 20:51	45.82	OK	618	2026-09-10 20:52	46.94	OK
619	2026-09-10 20:53	46.63	OK	620	2026-09-10 20:54	44.99	OK
621	2026-09-10 20:55	46.34	OK	622	2026-09-10 20:56	45.06	OK
623	2026-09-10 20:57	47.73	OK	624	2026-09-10 20:58	48.19	OK
625	2026-09-10 20:59	48.39	OK	626	2026-09-10 21:00	47.09	OK
627	2026-09-10 21:01	46.89	OK	628	2026-09-10 21:02	47.73	OK
629	2026-09-10 21:03	49.24	OK	630	2026-09-10 21:04	48.05	OK
631	2026-09-10 21:05	46.95	OK	632	2026-09-10 21:06	45.88	OK
633	2026-09-10 21:07	45.82	OK	634	2026-09-10 21:08	47.75	OK
635	2026-09-10 21:09	46.17	OK	636	2026-09-10 21:10	47.83	OK
637	2026-09-10 21:11	45.90	OK	638	2026-09-10 21:12	48.06	OK
639	2026-09-10 21:13	45.33	OK	640	2026-09-10 21:14	47.68	OK
641	2026-09-10 21:15	47.99	OK	642	2026-09-10 21:16	48.37	OK
643	2026-09-10 21:17	46.05	OK	644	2026-09-10 21:18	47.01	OK
645	2026-09-10 21:19	46.92	OK	646	2026-09-10 21:20	45.73	OK
647	2026-09-10 21:21	47.66	OK	648	2026-09-10 21:22	47.70	OK
649	2026-09-10 21:23	45.92	OK	650	2026-09-10 21:24	45.33	OK
651	2026-09-10 21:25	47.74	OK	652	2026-09-10 21:26	47.24	OK
653	2026-09-10 21:27	46.76	OK	654	2026-09-10 21:28	45.90	OK
655	2026-09-10 21:29	46.45	OK	656	2026-09-10 21:30	47.44	OK
657	2026-09-10 21:31	45.27	OK	658	2026-09-10 21:32	46.48	OK
659	2026-09-10 21:33	47.00	OK	660	2026-09-10 21:34	46.17	OK
661	2026-09-10 21:35	45.71	OK	662	2026-09-10 21:36	45.96	OK
663	2026-09-10 21:37	48.03	OK	664	2026-09-10 21:38	46.62	OK
665	2026-09-10 21:39	47.12	OK	666	2026-09-10 21:40	47.99	OK
667	2026-09-10 21:41	47.06	OK	668	2026-09-10 21:42	48.01	OK
669	2026-09-10 21:43	44.70	OK	670	2026-09-10 21:44	46.43	OK
671	2026-09-10 21:45	47.00	OK	672	2026-09-10 21:46	46.87	OK
673	2026-09-10 21:47	46.39	OK	674	2026-09-10 21:48	47.38	OK
675	2026-09-10 21:49	46.76	OK	676	2026-09-10 21:50	47.05	OK
677	2026-09-10 21:51	47.24	OK	678	2026-09-10 21:52	45.39	OK
679	2026-09-10 21:53	46.60	OK	680	2026-09-10 21:54	45.92	OK
681	2026-09-10 21:55	45.60	OK	682	2026-09-10 21:56	46.74	OK
683	2026-09-10 21:57	47.80	OK	684	2026-09-10 21:58	44.80	OK
685	2026-09-10 21:59	44.70	OK	686	2026-09-10 22:00	46.20	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
687	2026-09-10 22:01	44.65	OK	688	2026-09-10 22:02	46.56	OK
689	2026-09-10 22:03	46.65	OK	690	2026-09-10 22:04	46.35	OK
691	2026-09-10 22:05	44.97	OK	692	2026-09-10 22:06	46.60	OK
693	2026-09-10 22:07	46.00	OK	694	2026-09-10 22:08	46.90	OK
695	2026-09-10 22:09	45.77	OK	696	2026-09-10 22:10	46.43	OK
697	2026-09-10 22:11	46.00	OK	698	2026-09-10 22:12	45.82	OK
699	2026-09-10 22:13	44.73	OK	700	2026-09-10 22:14	44.21	OK
701	2026-09-10 22:15	47.22	OK	702	2026-09-10 22:16	45.31	OK
703	2026-09-10 22:17	45.69	OK	704	2026-09-10 22:18	46.11	OK
705	2026-09-10 22:19	48.03	OK	706	2026-09-10 22:20	45.40	OK
707	2026-09-10 22:21	45.48	OK	708	2026-09-10 22:22	47.57	OK
709	2026-09-10 22:23	47.45	OK	710	2026-09-10 22:24	46.37	OK
711	2026-09-10 22:25	48.42	OK	712	2026-09-10 22:26	45.75	OK
713	2026-09-10 22:27	46.76	OK	714	2026-09-10 22:28	46.89	OK
715	2026-09-10 22:29	47.09	OK	716	2026-09-10 22:30	46.64	OK
717	2026-09-10 22:31	46.63	OK	718	2026-09-10 22:32	46.58	OK
719	2026-09-10 22:33	45.81	OK	720	2026-09-10 22:34	45.41	OK
721	2026-09-10 22:35	45.41	OK	722	2026-09-10 22:36	44.93	OK
723	2026-09-10 22:37	46.57	OK	724	2026-09-10 22:38	48.44	OK
725	2026-09-10 22:39	47.29	OK	726	2026-09-10 22:40	46.78	OK
727	2026-09-10 22:41	46.38	OK	728	2026-09-10 22:42	44.04	OK
729	2026-09-10 22:43	44.60	OK	730	2026-09-10 22:44	46.59	OK
731	2026-09-10 22:45	46.97	OK	732	2026-09-10 22:46	46.29	OK
733	2026-09-10 22:47	47.21	OK	734	2026-09-10 22:48	46.10	OK
735	2026-09-10 22:49	47.34	OK	736	2026-09-10 22:50	45.90	OK
737	2026-09-10 22:51	44.71	OK	738	2026-09-10 22:52	47.26	OK
739	2026-09-10 22:53	46.32	OK	740	2026-09-10 22:54	45.11	OK
741	2026-09-10 22:55	46.36	OK	742	2026-09-10 22:56	45.36	OK
743	2026-09-10 22:57	45.46	OK	744	2026-09-10 22:58	45.14	OK
745	2026-09-10 22:59	46.23	OK	746	2026-09-10 23:00	44.53	OK
747	2026-09-10 23:01	46.67	OK	748	2026-09-10 23:02	45.66	OK
749	2026-09-10 23:03	45.71	OK	750	2026-09-10 23:04	44.65	OK
751	2026-09-10 23:05	46.21	OK	752	2026-09-10 23:06	44.82	OK
753	2026-09-10 23:07	44.28	OK	754	2026-09-10 23:08	46.09	OK
755	2026-09-10 23:09	46.39	OK	756	2026-09-10 23:10	43.26	OK
757	2026-09-10 23:11	46.87	OK	758	2026-09-10 23:12	45.35	OK
759	2026-09-10 23:13	46.23	OK	760	2026-09-10 23:14	44.78	OK
761	2026-09-10 23:15	45.24	OK	762	2026-09-10 23:16	46.13	OK
763	2026-09-10 23:17	46.74	OK	764	2026-09-10 23:18	45.82	OK
765	2026-09-10 23:19	44.27	OK	766	2026-09-10 23:20	43.64	OK
767	2026-09-10 23:21	45.52	OK	768	2026-09-10 23:22	47.98	OK
769	2026-09-10 23:23	44.06	OK	770	2026-09-10 23:24	44.39	OK
771	2026-09-10 23:25	44.06	OK	772	2026-09-10 23:26	46.25	OK
773	2026-09-10 23:27	46.49	OK	774	2026-09-10 23:28	44.63	OK
775	2026-09-10 23:29	44.58	OK	776	2026-09-10 23:30	44.81	OK
777	2026-09-10 23:31	44.83	OK	778	2026-09-10 23:32	46.16	OK
779	2026-09-10 23:33	45.53	OK	780	2026-09-10 23:34	45.85	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
781	2026-09-10 23:35	45.88	OK	782	2026-09-10 23:36	47.27	OK
783	2026-09-10 23:37	47.40	OK	784	2026-09-10 23:38	45.91	OK
785	2026-09-10 23:39	46.48	OK	786	2026-09-10 23:40	46.48	OK
787	2026-09-10 23:41	44.60	OK	788	2026-09-10 23:42	47.22	OK
789	2026-09-10 23:43	45.38	OK	790	2026-09-10 23:44	45.58	OK
791	2026-09-10 23:45	46.09	OK	792	2026-09-10 23:46	44.36	OK
793	2026-09-10 23:47	45.06	OK	794	2026-09-10 23:48	45.20	OK
795	2026-09-10 23:49	46.01	OK	796	2026-09-10 23:50	44.43	OK
797	2026-09-10 23:51	44.83	OK	798	2026-09-10 23:52	45.95	OK
799	2026-09-10 23:53	45.40	OK	800	2026-09-10 23:54	46.58	OK
801	2026-09-10 23:55	43.90	OK	802	2026-09-10 23:56	44.29	OK
803	2026-09-10 23:57	44.59	OK	804	2026-09-10 23:58	45.18	OK
805	2026-09-10 23:59	44.09	OK	806	2026-09-11 00:00	43.52	OK
807	2026-09-11 00:01	46.39	OK	808	2026-09-11 00:02	45.38	OK
809	2026-09-11 00:03	43.49	OK	810	2026-09-11 00:04	46.93	OK
811	2026-09-11 00:05	42.99	OK	812	2026-09-11 00:06	44.34	OK
813	2026-09-11 00:07	44.85	OK	814	2026-09-11 00:08	46.41	OK
815	2026-09-11 00:09	45.67	OK	816	2026-09-11 00:10	45.17	OK
817	2026-09-11 00:11	45.34	OK	818	2026-09-11 00:12	45.25	OK
819	2026-09-11 00:13	44.93	OK	820	2026-09-11 00:14	46.21	OK
821	2026-09-11 00:15	44.44	OK	822	2026-09-11 00:16	46.00	OK
823	2026-09-11 00:17	43.68	OK	824	2026-09-11 00:18	46.36	OK
825	2026-09-11 00:19	44.67	OK	826	2026-09-11 00:20	45.35	OK
827	2026-09-11 00:21	43.60	OK	828	2026-09-11 00:22	45.59	OK
829	2026-09-11 00:23	43.85	OK	830	2026-09-11 00:24	45.03	OK
831	2026-09-11 00:25	44.65	OK	832	2026-09-11 00:26	45.96	OK
833	2026-09-11 00:27	45.29	OK	834	2026-09-11 00:28	45.87	OK
835	2026-09-11 00:29	45.55	OK	836	2026-09-11 00:30	46.64	OK
837	2026-09-11 00:31	44.06	OK	838	2026-09-11 00:32	44.13	OK
839	2026-09-11 00:33	44.93	OK	840	2026-09-11 00:34	45.79	OK
841	2026-09-11 00:35	43.85	OK	842	2026-09-11 00:36	45.37	OK
843	2026-09-11 00:37	44.63	OK	844	2026-09-11 00:38	44.74	OK
845	2026-09-11 00:39	46.41	OK	846	2026-09-11 00:40	44.22	OK
847	2026-09-11 00:41	45.74	OK	848	2026-09-11 00:42	45.01	OK
849	2026-09-11 00:43	44.08	OK	850	2026-09-11 00:44	45.05	OK
851	2026-09-11 00:45	44.27	OK	852	2026-09-11 00:46	44.67	OK
853	2026-09-11 00:47	44.33	OK	854	2026-09-11 00:48	44.92	OK
855	2026-09-11 00:49	44.44	OK	856	2026-09-11 00:50	43.43	OK
857	2026-09-11 00:51	45.63	OK	858	2026-09-11 00:52	45.88	OK
859	2026-09-11 00:53	46.45	OK	860	2026-09-11 00:54	44.89	OK
861	2026-09-11 00:55	45.48	OK	862	2026-09-11 00:56	47.09	OK
863	2026-09-11 00:57	46.16	OK	864	2026-09-11 00:58	45.66	OK
865	2026-09-11 00:59	44.68	OK	866	2026-09-11 01:00	46.70	OK
867	2026-09-11 01:01	45.30	OK	868	2026-09-11 01:02	44.45	OK
869	2026-09-11 01:03	44.82	OK	870	2026-09-11 01:04	45.38	OK
871	2026-09-11 01:05	44.72	OK	872	2026-09-11 01:06	43.67	OK
873	2026-09-11 01:07	46.08	OK	874	2026-09-11 01:08	46.41	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
875	2026-09-11 01:09	45.14	OK	876	2026-09-11 01:10	45.59	OK
877	2026-09-11 01:11	44.48	OK	878	2026-09-11 01:12	44.30	OK
879	2026-09-11 01:13	45.37	OK	880	2026-09-11 01:14	45.97	OK
881	2026-09-11 01:15	47.25	OK	882	2026-09-11 01:16	45.82	OK
883	2026-09-11 01:17	43.35	OK	884	2026-09-11 01:18	43.17	OK
885	2026-09-11 01:19	43.83	OK	886	2026-09-11 01:20	46.70	OK
887	2026-09-11 01:21	46.37	OK	888	2026-09-11 01:22	46.02	OK
889	2026-09-11 01:23	46.07	OK	890	2026-09-11 01:24	45.20	OK
891	2026-09-11 01:25	45.84	OK	892	2026-09-11 01:26	43.73	OK
893	2026-09-11 01:27	45.19	OK	894	2026-09-11 01:28	46.82	OK
895	2026-09-11 01:29	45.12	OK	896	2026-09-11 01:30	44.36	OK
897	2026-09-11 01:31	44.78	OK	898	2026-09-11 01:32	43.37	OK
899	2026-09-11 01:33	45.70	OK	900	2026-09-11 01:34	43.64	OK
901	2026-09-11 01:35	46.18	OK	902	2026-09-11 01:36	43.58	OK
903	2026-09-11 01:37	45.58	OK	904	2026-09-11 01:38	45.10	OK
905	2026-09-11 01:39	43.45	OK	906	2026-09-11 01:40	46.53	OK
907	2026-09-11 01:41	47.35	OK	908	2026-09-11 01:42	44.90	OK
909	2026-09-11 01:43	45.11	OK	910	2026-09-11 01:44	45.21	OK
911	2026-09-11 01:45	45.10	OK	912	2026-09-11 01:46	47.70	OK
913	2026-09-11 01:47	44.33	OK	914	2026-09-11 01:48	44.49	OK
915	2026-09-11 01:49	45.41	OK	916	2026-09-11 01:50	44.85	OK
917	2026-09-11 01:51	44.90	OK	918	2026-09-11 01:52	45.23	OK
919	2026-09-11 01:53	45.30	OK	920	2026-09-11 01:54	45.32	OK
921	2026-09-11 01:55	46.46	OK	922	2026-09-11 01:56	44.48	OK
923	2026-09-11 01:57	44.53	OK	924	2026-09-11 01:58	47.16	OK
925	2026-09-11 01:59	43.24	OK	926	2026-09-11 02:00	45.00	OK
927	2026-09-11 02:01	46.29	OK	928	2026-09-11 02:02	46.77	OK
929	2026-09-11 02:03	45.93	OK	930	2026-09-11 02:04	46.18	OK
931	2026-09-11 02:05	45.01	OK	932	2026-09-11 02:06	45.41	OK
933	2026-09-11 02:07	45.20	OK	934	2026-09-11 02:08	46.30	OK
935	2026-09-11 02:09	44.58	OK	936	2026-09-11 02:10	45.32	OK
937	2026-09-11 02:11	46.06	OK	938	2026-09-11 02:12	45.12	OK
939	2026-09-11 02:13	45.38	OK	940	2026-09-11 02:14	44.47	OK
941	2026-09-11 02:15	45.40	OK	942	2026-09-11 02:16	45.70	OK
943	2026-09-11 02:17	44.25	OK	944	2026-09-11 02:18	46.52	OK
945	2026-09-11 02:19	46.22	OK	946	2026-09-11 02:20	44.48	OK
947	2026-09-11 02:21	42.94	OK	948	2026-09-11 02:22	45.35	OK
949	2026-09-11 02:23	46.59	OK	950	2026-09-11 02:24	44.76	OK
951	2026-09-11 02:25	46.19	OK	952	2026-09-11 02:26	45.25	OK
953	2026-09-11 02:27	44.82	OK	954	2026-09-11 02:28	44.64	OK
955	2026-09-11 02:29	44.88	OK	956	2026-09-11 02:30	44.81	OK
957	2026-09-11 02:31	47.80	OK	958	2026-09-11 02:32	44.49	OK
959	2026-09-11 02:33	46.63	OK	960	2026-09-11 02:34	45.93	OK
961	2026-09-11 02:35	46.24	OK	962	2026-09-11 02:36	46.28	OK
963	2026-09-11 02:37	45.69	OK	964	2026-09-11 02:38	43.74	OK
965	2026-09-11 02:39	44.68	OK	966	2026-09-11 02:40	45.85	OK
967	2026-09-11 02:41	44.50	OK	968	2026-09-11 02:42	45.51	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
969	2026-09-11 02:43	45.15	OK	970	2026-09-11 02:44	43.27	OK
971	2026-09-11 02:45	45.48	OK	972	2026-09-11 02:46	45.78	OK
973	2026-09-11 02:47	45.14	OK	974	2026-09-11 02:48	46.58	OK
975	2026-09-11 02:49	44.83	OK	976	2026-09-11 02:50	44.70	OK
977	2026-09-11 02:51	46.18	OK	978	2026-09-11 02:52	44.81	OK
979	2026-09-11 02:53	43.55	OK	980	2026-09-11 02:54	45.01	OK
981	2026-09-11 02:55	46.97	OK	982	2026-09-11 02:56	44.50	OK
983	2026-09-11 02:57	45.45	OK	984	2026-09-11 02:58	45.14	OK
985	2026-09-11 02:59	45.58	OK	986	2026-09-11 03:00	45.63	OK
987	2026-09-11 03:01	46.20	OK	988	2026-09-11 03:02	46.34	OK
989	2026-09-11 03:03	45.95	OK	990	2026-09-11 03:04	44.81	OK
991	2026-09-11 03:05	45.78	OK	992	2026-09-11 03:06	47.74	OK
993	2026-09-11 03:07	44.64	OK	994	2026-09-11 03:08	47.78	OK
995	2026-09-11 03:09	46.04	OK	996	2026-09-11 03:10	45.79	OK
997	2026-09-11 03:11	43.74	OK	998	2026-09-11 03:12	46.25	OK
999	2026-09-11 03:13	46.49	OK	1000	2026-09-11 03:14	43.60	OK
1001	2026-09-11 03:15	46.05	OK	1002	2026-09-11 03:16	45.09	OK
1003	2026-09-11 03:17	45.52	OK	1004	2026-09-11 03:18	45.41	OK
1005	2026-09-11 03:19	47.00	OK	1006	2026-09-11 03:20	45.50	OK
1007	2026-09-11 03:21	45.32	OK	1008	2026-09-11 03:22	44.40	OK
1009	2026-09-11 03:23	45.09	OK	1010	2026-09-11 03:24	43.98	OK
1011	2026-09-11 03:25	44.55	OK	1012	2026-09-11 03:26	46.04	OK
1013	2026-09-11 03:27	45.65	OK	1014	2026-09-11 03:28	44.46	OK
1015	2026-09-11 03:29	45.13	OK	1016	2026-09-11 03:30	45.88	OK
1017	2026-09-11 03:31	45.48	OK	1018	2026-09-11 03:32	46.49	OK
1019	2026-09-11 03:33	46.93	OK	1020	2026-09-11 03:34	45.72	OK
1021	2026-09-11 03:35	46.08	OK	1022	2026-09-11 03:36	46.14	OK
1023	2026-09-11 03:37	45.80	OK	1024	2026-09-11 03:38	47.96	OK
1025	2026-09-11 03:39	46.06	OK	1026	2026-09-11 03:40	45.53	OK
1027	2026-09-11 03:41	45.19	OK	1028	2026-09-11 03:42	45.54	OK
1029	2026-09-11 03:43	45.78	OK	1030	2026-09-11 03:44	44.57	OK
1031	2026-09-11 03:45	46.24	OK	1032	2026-09-11 03:46	46.84	OK
1033	2026-09-11 03:47	46.70	OK	1034	2026-09-11 03:48	45.22	OK
1035	2026-09-11 03:49	47.29	OK	1036	2026-09-11 03:50	45.83	OK
1037	2026-09-11 03:51	47.81	OK	1038	2026-09-11 03:52	46.89	OK
1039	2026-09-11 03:53	47.44	OK	1040	2026-09-11 03:54	46.42	OK
1041	2026-09-11 03:55	45.08	OK	1042	2026-09-11 03:56	43.41	OK
1043	2026-09-11 03:57	45.84	OK	1044	2026-09-11 03:58	45.12	OK
1045	2026-09-11 03:59	43.55	OK	1046	2026-09-11 04:00	45.53	OK
1047	2026-09-11 04:01	47.03	OK	1048	2026-09-11 04:02	45.03	OK
1049	2026-09-11 04:03	47.18	OK	1050	2026-09-11 04:04	46.22	OK
1051	2026-09-11 04:05	47.17	OK	1052	2026-09-11 04:06	45.79	OK
1053	2026-09-11 04:07	47.34	OK	1054	2026-09-11 04:08	44.93	OK
1055	2026-09-11 04:09	47.19	OK	1056	2026-09-11 04:10	45.63	OK
1057	2026-09-11 04:11	44.40	OK	1058	2026-09-11 04:12	46.25	OK
1059	2026-09-11 04:13	44.44	OK	1060	2026-09-11 04:14	45.95	OK
1061	2026-09-11 04:15	47.68	OK	1062	2026-09-11 04:16	45.96	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1063	2026-09-11 04:17	44.74	OK	1064	2026-09-11 04:18	45.29	OK
1065	2026-09-11 04:19	46.39	OK	1066	2026-09-11 04:20	46.76	OK
1067	2026-09-11 04:21	47.22	OK	1068	2026-09-11 04:22	46.43	OK
1069	2026-09-11 04:23	48.42	OK	1070	2026-09-11 04:24	46.61	OK
1071	2026-09-11 04:25	46.93	OK	1072	2026-09-11 04:26	45.94	OK
1073	2026-09-11 04:27	45.31	OK	1074	2026-09-11 04:28	46.90	OK
1075	2026-09-11 04:29	45.51	OK	1076	2026-09-11 04:30	46.50	OK
1077	2026-09-11 04:31	46.15	OK	1078	2026-09-11 04:32	46.25	OK
1079	2026-09-11 04:33	45.64	OK	1080	2026-09-11 04:34	47.12	OK
1081	2026-09-11 04:35	45.45	OK	1082	2026-09-11 04:36	46.74	OK
1083	2026-09-11 04:37	46.01	OK	1084	2026-09-11 04:38	46.30	OK
1085	2026-09-11 04:39	45.00	OK	1086	2026-09-11 04:40	46.05	OK
1087	2026-09-11 04:41	46.15	OK	1088	2026-09-11 04:42	45.91	OK
1089	2026-09-11 04:43	45.69	OK	1090	2026-09-11 04:44	45.47	OK
1091	2026-09-11 04:45	47.90	OK	1092	2026-09-11 04:46	45.37	OK
1093	2026-09-11 04:47	46.59	OK	1094	2026-09-11 04:48	46.82	OK
1095	2026-09-11 04:49	45.86	OK	1096	2026-09-11 04:50	45.56	OK
1097	2026-09-11 04:51	46.27	OK	1098	2026-09-11 04:52	44.97	OK
1099	2026-09-11 04:53	46.63	OK	1100	2026-09-11 04:54	46.51	OK
1101	2026-09-11 04:55	46.56	OK	1102	2026-09-11 04:56	43.98	OK
1103	2026-09-11 04:57	44.91	OK	1104	2026-09-11 04:58	47.91	OK
1105	2026-09-11 04:59	46.23	OK	1106	2026-09-11 05:00	47.22	OK
1107	2026-09-11 05:01	46.46	OK	1108	2026-09-11 05:02	45.31	OK
1109	2026-09-11 05:03	47.92	OK	1110	2026-09-11 05:04	46.23	OK
1111	2026-09-11 05:05	48.46	OK	1112	2026-09-11 05:06	45.92	OK
1113	2026-09-11 05:07	46.92	OK	1114	2026-09-11 05:08	46.21	OK
1115	2026-09-11 05:09	47.62	OK	1116	2026-09-11 05:10	45.63	OK
1117	2026-09-11 05:11	44.31	OK	1118	2026-09-11 05:12	47.45	OK
1119	2026-09-11 05:13	45.29	OK	1120	2026-09-11 05:14	47.66	OK
1121	2026-09-11 05:15	48.99	OK	1122	2026-09-11 05:16	45.56	OK
1123	2026-09-11 05:17	45.48	OK	1124	2026-09-11 05:18	46.39	OK
1125	2026-09-11 05:19	45.94	OK	1126	2026-09-11 05:20	47.95	OK
1127	2026-09-11 05:21	47.48	OK	1128	2026-09-11 05:22	46.99	OK
1129	2026-09-11 05:23	47.75	OK	1130	2026-09-11 05:24	47.62	OK
1131	2026-09-11 05:25	45.09	OK	1132	2026-09-11 05:26	48.51	OK
1133	2026-09-11 05:27	47.98	OK	1134	2026-09-11 05:28	46.82	OK
1135	2026-09-11 05:29	46.27	OK	1136	2026-09-11 05:30	47.52	OK
1137	2026-09-11 05:31	47.58	OK	1138	2026-09-11 05:32	47.49	OK
1139	2026-09-11 05:33	45.55	OK	1140	2026-09-11 05:34	46.35	OK
1141	2026-09-11 05:35	47.35	OK	1142	2026-09-11 05:36	48.53	OK
1143	2026-09-11 05:37	46.87	OK	1144	2026-09-11 05:38	45.84	OK
1145	2026-09-11 05:39	47.12	OK	1146	2026-09-11 05:40	45.95	OK
1147	2026-09-11 05:41	47.23	OK	1148	2026-09-11 05:42	47.27	OK
1149	2026-09-11 05:43	47.42	OK	1150	2026-09-11 05:44	46.74	OK
1151	2026-09-11 05:45	46.69	OK	1152	2026-09-11 05:46	48.90	OK
1153	2026-09-11 05:47	45.75	OK	1154	2026-09-11 05:48	46.62	OK
1155	2026-09-11 05:49	48.78	OK	1156	2026-09-11 05:50	46.72	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1157	2026-09-11 05:51	44.86	OK	1158	2026-09-11 05:52	47.38	OK
1159	2026-09-11 05:53	48.92	OK	1160	2026-09-11 05:54	45.95	OK
1161	2026-09-11 05:55	47.24	OK	1162	2026-09-11 05:56	46.54	OK
1163	2026-09-11 05:57	47.58	OK	1164	2026-09-11 05:58	48.45	OK
1165	2026-09-11 05:59	46.81	OK	1166	2026-09-11 06:00	48.14	OK
1167	2026-09-11 06:01	47.94	OK	1168	2026-09-11 06:02	47.75	OK
1169	2026-09-11 06:03	46.56	OK	1170	2026-09-11 06:04	48.28	OK
1171	2026-09-11 06:05	47.62	OK	1172	2026-09-11 06:06	47.71	OK
1173	2026-09-11 06:07	46.29	OK	1174	2026-09-11 06:08	48.42	OK
1175	2026-09-11 06:09	48.94	OK	1176	2026-09-11 06:10	46.55	OK
1177	2026-09-11 06:11	47.39	OK	1178	2026-09-11 06:12	47.95	OK
1179	2026-09-11 06:13	47.85	OK	1180	2026-09-11 06:14	47.43	OK
1181	2026-09-11 06:15	48.07	OK	1182	2026-09-11 06:16	47.93	OK
1183	2026-09-11 06:17	48.16	OK	1184	2026-09-11 06:18	48.93	OK
1185	2026-09-11 06:19	46.85	OK	1186	2026-09-11 06:20	48.43	OK
1187	2026-09-11 06:21	48.68	OK	1188	2026-09-11 06:22	48.74	OK
1189	2026-09-11 06:23	47.89	OK	1190	2026-09-11 06:24	47.40	OK
1191	2026-09-11 06:25	46.57	OK	1192	2026-09-11 06:26	48.61	OK
1193	2026-09-11 06:27	47.99	OK	1194	2026-09-11 06:28	48.12	OK
1195	2026-09-11 06:29	46.85	OK	1196	2026-09-11 06:30	48.37	OK
1197	2026-09-11 06:31	47.18	OK	1198	2026-09-11 06:32	48.89	OK
1199	2026-09-11 06:33	48.35	OK	1200	2026-09-11 06:34	47.88	OK
1201	2026-09-11 06:35	47.64	OK	1202	2026-09-11 06:36	46.42	OK
1203	2026-09-11 06:37	50.10	OK	1204	2026-09-11 06:38	48.21	OK
1205	2026-09-11 06:39	49.56	OK	1206	2026-09-11 06:40	49.01	OK
1207	2026-09-11 06:41	49.09	OK	1208	2026-09-11 06:42	46.92	OK
1209	2026-09-11 06:43	46.87	OK	1210	2026-09-11 06:44	46.92	OK
1211	2026-09-11 06:45	47.60	OK	1212	2026-09-11 06:46	48.99	OK
1213	2026-09-11 06:47	48.91	OK	1214	2026-09-11 06:48	48.40	OK
1215	2026-09-11 06:49	47.70	OK	1216	2026-09-11 06:50	47.80	OK
1217	2026-09-11 06:51	47.07	OK	1218	2026-09-11 06:52	47.37	OK
1219	2026-09-11 06:53	47.84	OK	1220	2026-09-11 06:54	48.93	OK
1221	2026-09-11 06:55	48.37	OK	1222	2026-09-11 06:56	48.49	OK
1223	2026-09-11 06:57	47.92	OK	1224	2026-09-11 06:58	48.54	OK
1225	2026-09-11 06:59	48.41	OK	1226	2026-09-11 07:00	47.58	OK
1227	2026-09-11 07:01	46.56	OK	1228	2026-09-11 07:02	47.25	OK
1229	2026-09-11 07:03	47.56	OK	1230	2026-09-11 07:04	48.10	OK
1231	2026-09-11 07:05	48.47	OK	1232	2026-09-11 07:06	48.31	OK
1233	2026-09-11 07:07	49.24	OK	1234	2026-09-11 07:08	47.84	OK
1235	2026-09-11 07:09	47.86	OK	1236	2026-09-11 07:10	48.94	OK
1237	2026-09-11 07:11	48.05	OK	1238	2026-09-11 07:12	47.94	OK
1239	2026-09-11 07:13	49.18	OK	1240	2026-09-11 07:14	48.19	OK
1241	2026-09-11 07:15	47.28	OK	1242	2026-09-11 07:16	47.02	OK
1243	2026-09-11 07:17	46.77	OK	1244	2026-09-11 07:18	48.41	OK
1245	2026-09-11 07:19	50.15	OK	1246	2026-09-11 07:20	49.29	OK
1247	2026-09-11 07:21	47.75	OK	1248	2026-09-11 07:22	49.30	OK
1249	2026-09-11 07:23	47.35	OK	1250	2026-09-11 07:24	49.20	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1251	2026-09-11 07:25	47.26	OK	1252	2026-09-11 07:26	49.12	OK
1253	2026-09-11 07:27	48.54	OK	1254	2026-09-11 07:28	45.87	OK
1255	2026-09-11 07:29	47.59	OK	1256	2026-09-11 07:30	47.54	OK
1257	2026-09-11 07:31	48.63	OK	1258	2026-09-11 07:32	49.99	OK
1259	2026-09-11 07:33	47.59	OK	1260	2026-09-11 07:34	47.32	OK
1261	2026-09-11 07:35	46.71	OK	1262	2026-09-11 07:36	49.53	OK
1263	2026-09-11 07:37	48.41	OK	1264	2026-09-11 07:38	49.15	OK
1265	2026-09-11 07:39	48.27	OK	1266	2026-09-11 07:40	50.02	OK
1267	2026-09-11 07:41	48.78	OK	1268	2026-09-11 07:42	47.38	OK
1269	2026-09-11 07:43	49.21	OK	1270	2026-09-11 07:44	48.63	OK
1271	2026-09-11 07:45	47.77	OK	1272	2026-09-11 07:46	47.95	OK
1273	2026-09-11 07:47	49.06	OK	1274	2026-09-11 07:48	50.33	OK
1275	2026-09-11 07:49	48.21	OK	1276	2026-09-11 07:50	49.72	OK
1277	2026-09-11 07:51	49.39	OK	1278	2026-09-11 07:52	51.13	OK
1279	2026-09-11 07:53	50.02	OK	1280	2026-09-11 07:54	50.64	OK
1281	2026-09-11 07:55	48.14	OK	1282	2026-09-11 07:56	48.94	OK
1283	2026-09-11 07:57	48.72	OK	1284	2026-09-11 07:58	47.11	OK
1285	2026-09-11 07:59	48.29	OK	1286	2026-09-11 08:00	48.23	OK
1287	2026-09-11 08:01	46.62	OK	1288	2026-09-11 08:02	49.42	OK
1289	2026-09-11 08:03	48.71	OK	1290	2026-09-11 08:04	49.96	OK
1291	2026-09-11 08:05	49.31	OK	1292	2026-09-11 08:06	49.67	OK
1293	2026-09-11 08:07	48.34	OK	1294	2026-09-11 08:08	48.95	OK
1295	2026-09-11 08:09	48.91	OK	1296	2026-09-11 08:10	48.31	OK
1297	2026-09-11 08:11	47.33	OK	1298	2026-09-11 08:12	49.45	OK
1299	2026-09-11 08:13	51.47	OK	1300	2026-09-11 08:14	50.16	OK
1301	2026-09-11 08:15	48.23	OK	1302	2026-09-11 08:16	48.37	OK
1303	2026-09-11 08:17	49.65	OK	1304	2026-09-11 08:18	47.52	OK
1305	2026-09-11 08:19	48.80	OK	1306	2026-09-11 08:20	49.09	OK
1307	2026-09-11 08:21	49.73	OK	1308	2026-09-11 08:22	48.53	OK
1309	2026-09-11 08:23	47.27	OK	1310	2026-09-11 08:24	49.83	OK
1311	2026-09-11 08:25	49.27	OK	1312	2026-09-11 08:26	48.31	OK
1313	2026-09-11 08:27	50.50	OK	1314	2026-09-11 08:28	48.93	OK
1315	2026-09-11 08:29	49.66	OK	1316	2026-09-11 08:30	50.59	OK
1317	2026-09-11 08:31	48.60	OK	1318	2026-09-11 08:32	48.97	OK
1319	2026-09-11 08:33	48.96	OK	1320	2026-09-11 08:34	49.48	OK
1321	2026-09-11 08:35	52.06	OK	1322	2026-09-11 08:36	50.24	OK
1323	2026-09-11 08:37	50.60	OK	1324	2026-09-11 08:38	50.57	OK
1325	2026-09-11 08:39	48.32	OK	1326	2026-09-11 08:40	49.73	OK
1327	2026-09-11 08:41	50.14	OK	1328	2026-09-11 08:42	51.18	OK
1329	2026-09-11 08:43	48.16	OK	1330	2026-09-11 08:44	49.48	OK
1331	2026-09-11 08:45	49.43	OK	1332	2026-09-11 08:46	48.86	OK
1333	2026-09-11 08:47	50.61	OK	1334	2026-09-11 08:48	51.68	OK
1335	2026-09-11 08:49	50.59	OK	1336	2026-09-11 08:50	50.98	OK
1337	2026-09-11 08:51	49.35	OK	1338	2026-09-11 08:52	48.10	OK
1339	2026-09-11 08:53	49.25	OK	1340	2026-09-11 08:54	51.25	OK
1341	2026-09-11 08:55	48.81	OK	1342	2026-09-11 08:56	50.89	OK
1343	2026-09-11 08:57	49.18	OK	1344	2026-09-11 08:58	49.50	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1345	2026-09-11 08:59	49.09	OK	1346	2026-09-11 09:00	49.91	OK
1347	2026-09-11 09:01	51.27	OK	1348	2026-09-11 09:02	50.15	OK
1349	2026-09-11 09:03	50.64	OK	1350	2026-09-11 09:04	48.73	OK
1351	2026-09-11 09:05	49.80	OK	1352	2026-09-11 09:06	49.86	OK
1353	2026-09-11 09:07	50.03	OK	1354	2026-09-11 09:08	51.66	OK
1355	2026-09-11 09:09	51.01	OK	1356	2026-09-11 09:10	50.79	OK
1357	2026-09-11 09:11	49.24	OK	1358	2026-09-11 09:12	52.26	OK
1359	2026-09-11 09:13	52.20	OK	1360	2026-09-11 09:14	48.92	OK
1361	2026-09-11 09:15	50.86	OK	1362	2026-09-11 09:16	49.44	OK
1363	2026-09-11 09:17	49.87	OK	1364	2026-09-11 09:18	50.91	OK
1365	2026-09-11 09:19	49.52	OK	1366	2026-09-11 09:20	50.08	OK
1367	2026-09-11 09:21	50.92	OK	1368	2026-09-11 09:22	49.76	OK
1369	2026-09-11 09:23	51.61	OK	1370	2026-09-11 09:24	50.93	OK
1371	2026-09-11 09:25	50.74	OK	1372	2026-09-11 09:26	49.72	OK
1373	2026-09-11 09:27	48.88	OK	1374	2026-09-11 09:28	51.39	OK
1375	2026-09-11 09:29	51.20	OK	1376	2026-09-11 09:30	49.75	OK
1377	2026-09-11 09:31	50.77	OK	1378	2026-09-11 09:32	50.31	OK
1379	2026-09-11 09:33	51.86	OK	1380	2026-09-11 09:34	51.49	OK
1381	2026-09-11 09:35	50.39	OK	1382	2026-09-11 09:36	52.08	OK
1383	2026-09-11 09:37	50.88	OK	1384	2026-09-11 09:38	50.65	OK
1385	2026-09-11 09:39	51.06	OK	1386	2026-09-11 09:40	51.15	OK
1387	2026-09-11 09:41	48.40	OK	1388	2026-09-11 09:42	49.96	OK
1389	2026-09-11 09:43	49.87	OK	1390	2026-09-11 09:44	50.24	OK
1391	2026-09-11 09:45	49.25	OK	1392	2026-09-11 09:46	49.44	OK
1393	2026-09-11 09:47	49.91	OK	1394	2026-09-11 09:48	51.27	OK
1395	2026-09-11 09:49	48.12	OK	1396	2026-09-11 09:50	52.54	OK
1397	2026-09-11 09:51	51.21	OK	1398	2026-09-11 09:52	51.08	OK
1399	2026-09-11 09:53	49.15	OK	1400	2026-09-11 09:54	52.75	OK
1401	2026-09-11 09:55	49.61	OK	1402	2026-09-11 09:56	51.56	OK
1403	2026-09-11 09:57	50.55	OK	1404	2026-09-11 09:58	50.94	OK
1405	2026-09-11 09:59	49.81	OK	1406	2026-09-11 10:00	52.20	OK
1407	2026-09-11 10:01	49.46	OK	1408	2026-09-11 10:02	49.59	OK
1409	2026-09-11 10:03	50.57	OK	1410	2026-09-11 10:04	50.38	OK
1411	2026-09-11 10:05	50.96	OK	1412	2026-09-11 10:06	51.04	OK
1413	2026-09-11 10:07	51.60	OK	1414	2026-09-11 10:08	50.08	OK
1415	2026-09-11 10:09	51.68	OK	1416	2026-09-11 10:10	49.35	OK
1417	2026-09-11 10:11	49.89	OK	1418	2026-09-11 10:12	52.06	OK
1419	2026-09-11 10:13	50.12	OK	1420	2026-09-11 10:14	50.30	OK
1421	2026-09-11 10:15	51.03	OK	1422	2026-09-11 10:16	51.96	OK
1423	2026-09-11 10:17	50.40	OK	1424	2026-09-11 10:18	51.23	OK
1425	2026-09-11 10:19	50.52	OK	1426	2026-09-11 10:20	51.53	OK
1427	2026-09-11 10:21	51.80	OK	1428	2026-09-11 10:22	51.47	OK
1429	2026-09-11 10:23	48.68	OK	1430	2026-09-11 10:24	52.58	OK
1431	2026-09-11 10:25	49.56	OK	1432	2026-09-11 10:26	49.05	OK
1433	2026-09-11 10:27	51.08	OK	1434	2026-09-11 10:28	51.16	OK
1435	2026-09-11 10:29	50.59	OK	1436	2026-09-11 10:30	52.11	OK
1437	2026-09-11 10:31	49.31	OK	1438	2026-09-11 10:32	49.12	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1439	2026-09-11 10:33	51.34	OK	1440	2026-09-11 10:34	50.64	OK
1441	2026-09-11 10:35	51.46	OK	1442	2026-09-11 10:36	51.91	OK
1443	2026-09-11 10:37	49.52	OK	1444	2026-09-11 10:38	50.50	OK
1445	2026-09-11 10:39	49.65	OK	1446	2026-09-11 10:40	51.82	OK
1447	2026-09-11 10:41	49.14	OK	1448	2026-09-11 10:42	52.15	OK
1449	2026-09-11 10:43	51.25	OK	1450	2026-09-11 10:44	51.68	OK
1451	2026-09-11 10:45	51.48	OK	1452	2026-09-11 10:46	49.53	OK
1453	2026-09-11 10:47	51.00	OK	1454	2026-09-11 10:48	50.86	OK
1455	2026-09-11 10:49	49.95	OK	1456	2026-09-11 10:50	50.12	OK
1457	2026-09-11 10:51	51.64	OK	1458	2026-09-11 10:52	52.24	OK
1459	2026-09-11 10:53	52.39	OK	1460	2026-09-11 10:54	52.56	OK
1461	2026-09-11 10:55	49.53	OK	1462	2026-09-11 10:56	49.87	OK
1463	2026-09-11 10:57	51.53	OK	1464	2026-09-11 10:58	50.96	OK
1465	2026-09-11 10:59	52.48	OK	1466	2026-09-11 11:00	50.58	OK
1467	2026-09-11 11:01	51.58	OK	1468	2026-09-11 11:02	51.56	OK
1469	2026-09-11 11:03	51.67	OK	1470	2026-09-11 11:04	50.82	OK
1471	2026-09-11 11:05	52.01	OK	1472	2026-09-11 11:06	51.74	OK
1473	2026-09-11 11:07	50.11	OK	1474	2026-09-11 11:08	51.79	OK
1475	2026-09-11 11:09	50.61	OK	1476	2026-09-11 11:10	51.15	OK
1477	2026-09-11 11:11	52.10	OK	1478	2026-09-11 11:12	52.06	OK
1479	2026-09-11 11:13	52.20	OK	1480	2026-09-11 11:14	51.33	OK
1481	2026-09-11 11:15	51.12	OK	1482	2026-09-11 11:16	53.05	OK
1483	2026-09-11 11:17	49.41	OK	1484	2026-09-11 11:18	50.56	OK
1485	2026-09-11 11:19	51.78	OK	1486	2026-09-11 11:20	49.50	OK
1487	2026-09-11 11:21	52.43	OK	1488	2026-09-11 11:22	51.90	OK
1489	2026-09-11 11:23	52.65	OK	1490	2026-09-11 11:24	50.19	OK
1491	2026-09-11 11:25	51.73	OK	1492	2026-09-11 11:26	51.21	OK
1493	2026-09-11 11:27	51.52	OK	1494	2026-09-11 11:28	53.06	OK
1495	2026-09-11 11:29	53.45	OK	1496	2026-09-11 11:30	51.80	OK
1497	2026-09-11 11:31	50.96	OK	1498	2026-09-11 11:32	52.11	OK
1499	2026-09-11 11:33	51.56	OK	1500	2026-09-11 11:34	49.49	OK
1501	2026-09-11 11:35	50.80	OK	1502	2026-09-11 11:36	53.07	OK
1503	2026-09-11 11:37	49.83	OK	1504	2026-09-11 11:38	50.99	OK
1505	2026-09-11 11:39	51.88	OK	1506	2026-09-11 11:40	50.37	OK
1507	2026-09-11 11:41	50.57	OK	1508	2026-09-11 11:42	51.79	OK
1509	2026-09-11 11:43	50.72	OK	1510	2026-09-11 11:44	52.47	OK
1511	2026-09-11 11:45	51.35	OK	1512	2026-09-11 11:46	50.51	OK
1513	2026-09-11 11:47	52.12	OK	1514	2026-09-11 11:48	52.06	OK
1515	2026-09-11 11:49	53.01	OK	1516	2026-09-11 11:50	50.35	OK
1517	2026-09-11 11:51	50.73	OK	1518	2026-09-11 11:52	52.25	OK
1519	2026-09-11 11:53	50.55	OK	1520	2026-09-11 11:54	51.98	OK
1521	2026-09-11 11:55	50.06	OK	1522	2026-09-11 11:56	52.80	OK
1523	2026-09-11 11:57	51.75	OK	1524	2026-09-11 11:58	52.70	OK
1525	2026-09-11 11:59	50.93	OK	1526	2026-09-11 12:00	51.46	OK
1527	2026-09-11 12:01	51.15	OK	1528	2026-09-11 12:02	52.86	OK
1529	2026-09-11 12:03	53.46	OK	1530	2026-09-11 12:04	51.76	OK
1531	2026-09-11 12:05	52.33	OK	1532	2026-09-11 12:06	50.12	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1533	2026-09-11 12:07	50.21	OK	1534	2026-09-11 12:08	52.71	OK
1535	2026-09-11 12:09	50.90	OK	1536	2026-09-11 12:10	53.23	OK
1537	2026-09-11 12:11	52.91	OK	1538	2026-09-11 12:12	51.71	OK
1539	2026-09-11 12:13	52.62	OK	1540	2026-09-11 12:14	51.00	OK
1541	2026-09-11 12:15	52.43	OK	1542	2026-09-11 12:16	51.06	OK
1543	2026-09-11 12:17	52.06	OK	1544	2026-09-11 12:18	50.39	OK
1545	2026-09-11 12:19	52.21	OK	1546	2026-09-11 12:20	52.58	OK
1547	2026-09-11 12:21	51.72	OK	1548	2026-09-11 12:22	53.82	OK
1549	2026-09-11 12:23	53.20	OK	1550	2026-09-11 12:24	53.17	OK
1551	2026-09-11 12:25	53.14	OK	1552	2026-09-11 12:26	52.38	OK
1553	2026-09-11 12:27	51.09	OK	1554	2026-09-11 12:28	50.30	OK
1555	2026-09-11 12:29	52.41	OK	1556	2026-09-11 12:30	52.17	OK
1557	2026-09-11 12:31	51.52	OK	1558	2026-09-11 12:32	52.51	OK
1559	2026-09-11 12:33	52.70	OK	1560	2026-09-11 12:34	50.42	OK
1561	2026-09-11 12:35	52.50	OK	1562	2026-09-11 12:36	52.82	OK
1563	2026-09-11 12:37	51.71	OK	1564	2026-09-11 12:38	53.46	OK
1565	2026-09-11 12:39	52.44	OK	1566	2026-09-11 12:40	49.39	OK
1567	2026-09-11 12:41	50.54	OK	1568	2026-09-11 12:42	52.90	OK
1569	2026-09-11 12:43	50.84	OK	1570	2026-09-11 12:44	53.52	OK
1571	2026-09-11 12:45	50.16	OK	1572	2026-09-11 12:46	50.30	OK
1573	2026-09-11 12:47	51.56	OK	1574	2026-09-11 12:48	51.99	OK
1575	2026-09-11 12:49	52.92	OK	1576	2026-09-11 12:50	51.40	OK
1577	2026-09-11 12:51	49.61	OK	1578	2026-09-11 12:52	50.32	OK
1579	2026-09-11 12:53	50.43	OK	1580	2026-09-11 12:54	51.78	OK
1581	2026-09-11 12:55	50.75	OK	1582	2026-09-11 12:56	52.53	OK
1583	2026-09-11 12:57	50.15	OK	1584	2026-09-11 12:58	52.36	OK
1585	2026-09-11 12:59	51.80	OK	1586	2026-09-11 13:00	52.90	OK
1587	2026-09-11 13:01	50.53	OK	1588	2026-09-11 13:02	51.27	OK
1589	2026-09-11 13:03	49.86	OK	1590	2026-09-11 13:04	54.61	OK
1591	2026-09-11 13:05	51.74	OK	1592	2026-09-11 13:06	52.32	OK
1593	2026-09-11 13:07	52.65	OK	1594	2026-09-11 13:08	53.75	OK
1595	2026-09-11 13:09	51.17	OK	1596	2026-09-11 13:10	52.41	OK
1597	2026-09-11 13:11	51.36	OK	1598	2026-09-11 13:12	51.24	OK
1599	2026-09-11 13:13	52.02	OK	1600	2026-09-11 13:14	52.42	OK
1601	2026-09-11 13:15	52.29	OK	1602	2026-09-11 13:16	51.85	OK
1603	2026-09-11 13:17	48.93	OK	1604	2026-09-11 13:18	51.17	OK
1605	2026-09-11 13:19	51.94	OK	1606	2026-09-11 13:20	51.82	OK
1607	2026-09-11 13:21	51.46	OK	1608	2026-09-11 13:22	52.95	OK
1609	2026-09-11 13:23	50.61	OK	1610	2026-09-11 13:24	50.73	OK
1611	2026-09-11 13:25	49.85	OK	1612	2026-09-11 13:26	52.36	OK
1613	2026-09-11 13:27	51.20	OK	1614	2026-09-11 13:28	51.80	OK
1615	2026-09-11 13:29	50.89	OK	1616	2026-09-11 13:30	51.81	OK
1617	2026-09-11 13:31	53.02	OK	1618	2026-09-11 13:32	51.82	OK
1619	2026-09-11 13:33	52.23	OK	1620	2026-09-11 13:34	52.93	OK
1621	2026-09-11 13:35	51.77	OK	1622	2026-09-11 13:36	53.76	OK
1623	2026-09-11 13:37	52.10	OK	1624	2026-09-11 13:38	53.31	OK
1625	2026-09-11 13:39	52.28	OK	1626	2026-09-11 13:40	52.31	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1627	2026-09-11 13:41	51.39	OK	1628	2026-09-11 13:42	53.49	OK
1629	2026-09-11 13:43	52.07	OK	1630	2026-09-11 13:44	49.62	OK
1631	2026-09-11 13:45	51.42	OK	1632	2026-09-11 13:46	50.60	OK
1633	2026-09-11 13:47	50.96	OK	1634	2026-09-11 13:48	52.33	OK
1635	2026-09-11 13:49	52.96	OK	1636	2026-09-11 13:50	52.01	OK
1637	2026-09-11 13:51	52.21	OK	1638	2026-09-11 13:52	52.60	OK
1639	2026-09-11 13:53	52.00	OK	1640	2026-09-11 13:54	53.29	OK
1641	2026-09-11 13:55	53.51	OK	1642	2026-09-11 13:56	52.50	OK
1643	2026-09-11 13:57	52.62	OK	1644	2026-09-11 13:58	51.84	OK
1645	2026-09-11 13:59	51.39	OK	1646	2026-09-11 14:00	52.66	OK
1647	2026-09-11 14:01	50.15	OK	1648	2026-09-11 14:02	51.34	OK
1649	2026-09-11 14:03	51.90	OK	1650	2026-09-11 14:04	52.75	OK
1651	2026-09-11 14:05	50.28	OK	1652	2026-09-11 14:06	52.37	OK
1653	2026-09-11 14:07	51.93	OK	1654	2026-09-11 14:08	51.31	OK
1655	2026-09-11 14:09	53.60	OK	1656	2026-09-11 14:10	52.25	OK
1657	2026-09-11 14:11	51.82	OK	1658	2026-09-11 14:12	50.79	OK
1659	2026-09-11 14:13	51.37	OK	1660	2026-09-11 14:14	50.35	OK
1661	2026-09-11 14:15	53.93	OK	1662	2026-09-11 14:16	49.49	OK
1663	2026-09-11 14:17	51.65	OK	1664	2026-09-11 14:18	52.65	OK
1665	2026-09-11 14:19	52.78	OK	1666	2026-09-11 14:20	50.61	OK
1667	2026-09-11 14:21	53.57	OK	1668	2026-09-11 14:22	51.01	OK
1669	2026-09-11 14:23	50.15	OK	1670	2026-09-11 14:24	50.03	OK
1671	2026-09-11 14:25	49.98	OK	1672	2026-09-11 14:26	52.08	OK
1673	2026-09-11 14:27	52.97	OK	1674	2026-09-11 14:28	52.80	OK
1675	2026-09-11 14:29	52.84	OK	1676	2026-09-11 14:30	52.03	OK
1677	2026-09-11 14:31	53.32	OK	1678	2026-09-11 14:32	52.64	OK
1679	2026-09-11 14:33	49.79	OK	1680	2026-09-11 14:34	52.49	OK
1681	2026-09-11 14:35	50.61	OK	1682	2026-09-11 14:36	50.44	OK
1683	2026-09-11 14:37	52.26	OK	1684	2026-09-11 14:38	50.93	OK
1685	2026-09-11 14:39	50.00	OK	1686	2026-09-11 14:40	51.68	OK
1687	2026-09-11 14:41	52.21	OK	1688	2026-09-11 14:42	52.73	OK
1689	2026-09-11 14:43	51.30	OK	1690	2026-09-11 14:44	51.79	OK
1691	2026-09-11 14:45	51.86	OK	1692	2026-09-11 14:46	52.87	OK
1693	2026-09-11 14:47	52.12	OK	1694	2026-09-11 14:48	49.85	OK
1695	2026-09-11 14:49	53.10	OK	1696	2026-09-11 14:50	52.88	OK
1697	2026-09-11 14:51	51.68	OK	1698	2026-09-11 14:52	52.54	OK
1699	2026-09-11 14:53	52.50	OK	1700	2026-09-11 14:54	54.37	OK
1701	2026-09-11 14:55	53.66	OK	1702	2026-09-11 14:56	51.53	OK
1703	2026-09-11 14:57	51.83	OK	1704	2026-09-11 14:58	50.55	OK
1705	2026-09-11 14:59	51.13	OK	1706	2026-09-11 15:00	51.79	OK
1707	2026-09-11 15:01	52.66	OK	1708	2026-09-11 15:02	50.09	OK
1709	2026-09-11 15:03	50.93	OK	1710	2026-09-11 15:04	51.88	OK
1711	2026-09-11 15:05	51.25	OK	1712	2026-09-11 15:06	51.64	OK
1713	2026-09-11 15:07	50.60	OK	1714	2026-09-11 15:08	50.10	OK
1715	2026-09-11 15:09	51.78	OK	1716	2026-09-11 15:10	52.04	OK
1717	2026-09-11 15:11	52.24	OK	1718	2026-09-11 15:12	50.17	OK
1719	2026-09-11 15:13	51.28	OK	1720	2026-09-11 15:14	51.20	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1721	2026-09-11 15:15	52.36	OK	1722	2026-09-11 15:16	50.94	OK
1723	2026-09-11 15:17	49.61	OK	1724	2026-09-11 15:18	51.37	OK
1725	2026-09-11 15:19	52.53	OK	1726	2026-09-11 15:20	53.23	OK
1727	2026-09-11 15:21	52.14	OK	1728	2026-09-11 15:22	50.37	OK
1729	2026-09-11 15:23	51.22	OK	1730	2026-09-11 15:24	51.21	OK
1731	2026-09-11 15:25	52.14	OK	1732	2026-09-11 15:26	51.23	OK
1733	2026-09-11 15:27	50.86	OK	1734	2026-09-11 15:28	51.65	OK
1735	2026-09-11 15:29	53.23	OK	1736	2026-09-11 15:30	52.20	OK
1737	2026-09-11 15:31	51.17	OK	1738	2026-09-11 15:32	50.12	OK
1739	2026-09-11 15:33	50.32	OK	1740	2026-09-11 15:34	51.17	OK
1741	2026-09-11 15:35	51.93	OK	1742	2026-09-11 15:36	51.84	OK
1743	2026-09-11 15:37	50.03	OK	1744	2026-09-11 15:38	50.50	OK
1745	2026-09-11 15:39	52.96	OK	1746	2026-09-11 15:40	51.91	OK
1747	2026-09-11 15:41	50.61	OK	1748	2026-09-11 15:42	50.86	OK
1749	2026-09-11 15:43	51.86	OK	1750	2026-09-11 15:44	50.42	OK
1751	2026-09-11 15:45	51.85	OK	1752	2026-09-11 15:46	52.03	OK
1753	2026-09-11 15:47	50.33	OK	1754	2026-09-11 15:48	51.66	OK
1755	2026-09-11 15:49	52.23	OK	1756	2026-09-11 15:50	52.63	OK
1757	2026-09-11 15:51	50.55	OK	1758	2026-09-11 15:52	50.00	OK
1759	2026-09-11 15:53	52.88	OK	1760	2026-09-11 15:54	50.82	OK
1761	2026-09-11 15:55	51.11	OK	1762	2026-09-11 15:56	53.43	OK
1763	2026-09-11 15:57	53.35	OK	1764	2026-09-11 15:58	50.53	OK
1765	2026-09-11 15:59	50.18	OK	1766	2026-09-11 16:00	50.52	OK
1767	2026-09-11 16:01	50.52	OK	1768	2026-09-11 16:02	52.04	OK
1769	2026-09-11 16:03	53.23	OK	1770	2026-09-11 16:04	49.64	OK
1771	2026-09-11 16:05	50.92	OK	1772	2026-09-11 16:06	50.89	OK
1773	2026-09-11 16:07	51.49	OK	1774	2026-09-11 16:08	50.90	OK
1775	2026-09-11 16:09	49.86	OK	1776	2026-09-11 16:10	51.86	OK
1777	2026-09-11 16:11	49.53	OK	1778	2026-09-11 16:12	51.00	OK
1779	2026-09-11 16:13	51.52	OK	1780	2026-09-11 16:14	51.72	OK
1781	2026-09-11 16:15	50.64	OK	1782	2026-09-11 16:16	50.31	OK
1783	2026-09-11 16:17	51.71	OK	1784	2026-09-11 16:18	51.66	OK
1785	2026-09-11 16:19	50.22	OK	1786	2026-09-11 16:20	50.36	OK
1787	2026-09-11 16:21	49.60	OK	1788	2026-09-11 16:22	49.34	OK
1789	2026-09-11 16:23	51.13	OK	1790	2026-09-11 16:24	49.37	OK
1791	2026-09-11 16:25	50.80	OK	1792	2026-09-11 16:26	50.28	OK
1793	2026-09-11 16:27	50.24	OK	1794	2026-09-11 16:28	52.55	OK
1795	2026-09-11 16:29	52.36	OK	1796	2026-09-11 16:30	50.34	OK
1797	2026-09-11 16:31	50.39	OK	1798	2026-09-11 16:32	48.49	OK
1799	2026-09-11 16:33	51.45	OK	1800	2026-09-11 16:34	51.22	OK
1801	2026-09-11 16:35	49.92	OK	1802	2026-09-11 16:36	49.84	OK
1803	2026-09-11 16:37	52.86	OK	1804	2026-09-11 16:38	50.59	OK
1805	2026-09-11 16:39	52.01	OK	1806	2026-09-11 16:40	50.45	OK
1807	2026-09-11 16:41	51.33	OK	1808	2026-09-11 16:42	51.72	OK
1809	2026-09-11 16:43	51.72	OK	1810	2026-09-11 16:44	48.84	OK
1811	2026-09-11 16:45	50.82	OK	1812	2026-09-11 16:46	50.98	OK
1813	2026-09-11 16:47	49.93	OK	1814	2026-09-11 16:48	51.58	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1815	2026-09-11 16:49	51.11	OK	1816	2026-09-11 16:50	49.95	OK
1817	2026-09-11 16:51	52.38	OK	1818	2026-09-11 16:52	51.33	OK
1819	2026-09-11 16:53	51.25	OK	1820	2026-09-11 16:54	49.77	OK
1821	2026-09-11 16:55	51.92	OK	1822	2026-09-11 16:56	50.23	OK
1823	2026-09-11 16:57	50.57	OK	1824	2026-09-11 16:58	51.43	OK
1825	2026-09-11 16:59	49.99	OK	1826	2026-09-11 17:00	49.90	OK
1827	2026-09-11 17:01	48.43	OK	1828	2026-09-11 17:02	49.96	OK
1829	2026-09-11 17:03	48.65	OK	1830	2026-09-11 17:04	51.73	OK
1831	2026-09-11 17:05	50.39	OK	1832	2026-09-11 17:06	52.26	OK
1833	2026-09-11 17:07	49.91	OK	1834	2026-09-11 17:08	50.61	OK
1835	2026-09-11 17:09	49.69	OK	1836	2026-09-11 17:10	50.92	OK
1837	2026-09-11 17:11	52.00	OK	1838	2026-09-11 17:12	50.58	OK
1839	2026-09-11 17:13	49.50	OK	1840	2026-09-11 17:14	49.67	OK
1841	2026-09-11 17:15	51.07	OK	1842	2026-09-11 17:16	50.56	OK
1843	2026-09-11 17:17	51.75	OK	1844	2026-09-11 17:18	50.63	OK
1845	2026-09-11 17:19	51.67	OK	1846	2026-09-11 17:20	49.79	OK
1847	2026-09-11 17:21	49.59	OK	1848	2026-09-11 17:22	52.39	OK
1849	2026-09-11 17:23	49.74	OK	1850	2026-09-11 17:24	49.59	OK
1851	2026-09-11 17:25	49.80	OK	1852	2026-09-11 17:26	49.00	OK
1853	2026-09-11 17:27	50.85	OK	1854	2026-09-11 17:28	48.23	OK
1855	2026-09-11 17:29	49.10	OK	1856	2026-09-11 17:30	49.97	OK
1857	2026-09-11 17:31	48.22	OK	1858	2026-09-11 17:32	49.94	OK
1859	2026-09-11 17:33	50.69	OK	1860	2026-09-11 17:34	48.43	OK
1861	2026-09-11 17:35	50.36	OK	1862	2026-09-11 17:36	50.10	OK
1863	2026-09-11 17:37	50.72	OK	1864	2026-09-11 17:38	49.33	OK
1865	2026-09-11 17:39	50.06	OK	1866	2026-09-11 17:40	47.78	OK
1867	2026-09-11 17:41	50.55	OK	1868	2026-09-11 17:42	50.78	OK
1869	2026-09-11 17:43	50.69	OK	1870	2026-09-11 17:44	49.28	OK
1871	2026-09-11 17:45	50.88	OK	1872	2026-09-11 17:46	49.55	OK
1873	2026-09-11 17:47	50.54	OK	1874	2026-09-11 17:48	49.12	OK
1875	2026-09-11 17:49	48.11	OK	1876	2026-09-11 17:50	51.28	OK
1877	2026-09-11 17:51	48.20	OK	1878	2026-09-11 17:52	49.04	OK
1879	2026-09-11 17:53	49.61	OK	1880	2026-09-11 17:54	49.32	OK
1881	2026-09-11 17:55	49.13	OK	1882	2026-09-11 17:56	50.46	OK
1883	2026-09-11 17:57	50.18	OK	1884	2026-09-11 17:58	50.12	OK
1885	2026-09-11 17:59	50.24	OK	1886	2026-09-11 18:00	49.62	OK
1887	2026-09-11 18:01	50.00	OK	1888	2026-09-11 18:02	48.56	OK
1889	2026-09-11 18:03	49.12	OK	1890	2026-09-11 18:04	48.67	OK
1891	2026-09-11 18:05	48.87	OK	1892	2026-09-11 18:06	49.33	OK
1893	2026-09-11 18:07	47.66	OK	1894	2026-09-11 18:08	48.44	OK
1895	2026-09-11 18:09	50.24	OK	1896	2026-09-11 18:10	49.85	OK
1897	2026-09-11 18:11	49.04	OK	1898	2026-09-11 18:12	50.54	OK
1899	2026-09-11 18:13	49.62	OK	1900	2026-09-11 18:14	49.17	OK
1901	2026-09-11 18:15	51.52	OK	1902	2026-09-11 18:16	48.79	OK
1903	2026-09-11 18:17	49.99	OK	1904	2026-09-11 18:18	49.00	OK
1905	2026-09-11 18:19	50.26	OK	1906	2026-09-11 18:20	49.42	OK
1907	2026-09-11 18:21	49.82	OK	1908	2026-09-11 18:22	48.83	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1909	2026-09-11 18:23	47.09	OK	1910	2026-09-11 18:24	50.89	OK
1911	2026-09-11 18:25	47.53	OK	1912	2026-09-11 18:26	51.07	OK
1913	2026-09-11 18:27	48.89	OK	1914	2026-09-11 18:28	50.40	OK
1915	2026-09-11 18:29	49.32	OK	1916	2026-09-11 18:30	49.77	OK
1917	2026-09-11 18:31	50.33	OK	1918	2026-09-11 18:32	48.61	OK
1919	2026-09-11 18:33	48.57	OK	1920	2026-09-11 18:34	49.71	OK
1921	2026-09-11 18:35	50.72	OK	1922	2026-09-11 18:36	50.50	OK
1923	2026-09-11 18:37	49.72	OK	1924	2026-09-11 18:38	49.31	OK
1925	2026-09-11 18:39	48.67	OK	1926	2026-09-11 18:40	50.00	OK
1927	2026-09-11 18:41	47.57	OK	1928	2026-09-11 18:42	51.05	OK
1929	2026-09-11 18:43	49.65	OK	1930	2026-09-11 18:44	49.51	OK
1931	2026-09-11 18:45	50.48	OK	1932	2026-09-11 18:46	51.49	OK
1933	2026-09-11 18:47	49.21	OK	1934	2026-09-11 18:48	49.19	OK
1935	2026-09-11 18:49	49.79	OK	1936	2026-09-11 18:50	48.35	OK
1937	2026-09-11 18:51	50.77	OK	1938	2026-09-11 18:52	48.90	OK
1939	2026-09-11 18:53	48.48	OK	1940	2026-09-11 18:54	46.57	OK
1941	2026-09-11 18:55	47.67	OK	1942	2026-09-11 18:56	48.69	OK
1943	2026-09-11 18:57	49.02	OK	1944	2026-09-11 18:58	48.37	OK
1945	2026-09-11 18:59	49.24	OK	1946	2026-09-11 19:00	48.13	OK
1947	2026-09-11 19:01	48.18	OK	1948	2026-09-11 19:02	49.65	OK
1949	2026-09-11 19:03	48.89	OK	1950	2026-09-11 19:04	49.93	OK
1951	2026-09-11 19:05	48.04	OK	1952	2026-09-11 19:06	48.32	OK
1953	2026-09-11 19:07	48.73	OK	1954	2026-09-11 19:08	49.67	OK
1955	2026-09-11 19:09	49.72	OK	1956	2026-09-11 19:10	48.58	OK
1957	2026-09-11 19:11	49.64	OK	1958	2026-09-11 19:12	48.93	OK
1959	2026-09-11 19:13	46.29	OK	1960	2026-09-11 19:14	49.05	OK
1961	2026-09-11 19:15	47.96	OK	1962	2026-09-11 19:16	48.59	OK
1963	2026-09-11 19:17	47.80	OK	1964	2026-09-11 19:18	49.75	OK
1965	2026-09-11 19:19	48.31	OK	1966	2026-09-11 19:20	47.93	OK
1967	2026-09-11 19:21	47.30	OK	1968	2026-09-11 19:22	49.19	OK
1969	2026-09-11 19:23	47.87	OK	1970	2026-09-11 19:24	49.18	OK
1971	2026-09-11 19:25	49.33	OK	1972	2026-09-11 19:26	48.38	OK
1973	2026-09-11 19:27	48.91	OK	1974	2026-09-11 19:28	46.38	OK
1975	2026-09-11 19:29	48.79	OK	1976	2026-09-11 19:30	48.80	OK
1977	2026-09-11 19:31	49.69	OK	1978	2026-09-11 19:32	47.67	OK
1979	2026-09-11 19:33	46.89	OK	1980	2026-09-11 19:34	49.45	OK
1981	2026-09-11 19:35	47.83	OK	1982	2026-09-11 19:36	46.50	OK
1983	2026-09-11 19:37	48.31	OK	1984	2026-09-11 19:38	48.24	OK
1985	2026-09-11 19:39	48.29	OK	1986	2026-09-11 19:40	48.34	OK
1987	2026-09-11 19:41	48.19	OK	1988	2026-09-11 19:42	48.93	OK
1989	2026-09-11 19:43	46.24	OK	1990	2026-09-11 19:44	48.01	OK
1991	2026-09-11 19:45	47.51	OK	1992	2026-09-11 19:46	48.23	OK
1993	2026-09-11 19:47	48.48	OK	1994	2026-09-11 19:48	48.12	OK
1995	2026-09-11 19:49	46.90	OK	1996	2026-09-11 19:50	49.13	OK
1997	2026-09-11 19:51	48.93	OK	1998	2026-09-11 19:52	48.62	OK
1999	2026-09-11 19:53	48.45	OK	2000	2026-09-11 19:54	47.80	OK
2001	2026-09-11 19:55	49.33	OK	2002	2026-09-11 19:56	50.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2003	2026-09-11 19:57	48.62	OK	2004	2026-09-11 19:58	46.83	OK
2005	2026-09-11 19:59	48.35	OK	2006	2026-09-11 20:00	48.89	OK
2007	2026-09-11 20:01	48.40	OK	2008	2026-09-11 20:02	46.66	OK
2009	2026-09-11 20:03	49.71	OK	2010	2026-09-11 20:04	47.01	OK
2011	2026-09-11 20:05	47.95	OK	2012	2026-09-11 20:06	45.76	OK
2013	2026-09-11 20:07	47.99	OK	2014	2026-09-11 20:08	46.55	OK
2015	2026-09-11 20:09	47.58	OK	2016	2026-09-11 20:10	47.92	OK
2017	2026-09-11 20:11	48.63	OK	2018	2026-09-11 20:12	47.69	OK
2019	2026-09-11 20:13	48.76	OK	2020	2026-09-11 20:14	48.66	OK
2021	2026-09-11 20:15	45.94	OK	2022	2026-09-11 20:16	48.26	OK
2023	2026-09-11 20:17	46.58	OK	2024	2026-09-11 20:18	47.72	OK
2025	2026-09-11 20:19	46.88	OK	2026	2026-09-11 20:20	49.21	OK
2027	2026-09-11 20:21	47.98	OK	2028	2026-09-11 20:22	49.83	OK
2029	2026-09-11 20:23	47.55	OK	2030	2026-09-11 20:24	47.28	OK
2031	2026-09-11 20:25	48.23	OK	2032	2026-09-11 20:26	48.49	OK
2033	2026-09-11 20:27	46.59	OK	2034	2026-09-11 20:28	49.75	OK
2035	2026-09-11 20:29	46.15	OK	2036	2026-09-11 20:30	48.32	OK
2037	2026-09-11 20:31	46.50	OK	2038	2026-09-11 20:32	48.50	OK
2039	2026-09-11 20:33	44.91	OK	2040	2026-09-11 20:34	49.70	OK
2041	2026-09-11 20:35	47.92	OK	2042	2026-09-11 20:36	48.81	OK
2043	2026-09-11 20:37	48.85	OK	2044	2026-09-11 20:38	46.24	OK
2045	2026-09-11 20:39	47.60	OK	2046	2026-09-11 20:40	46.38	OK
2047	2026-09-11 20:41	48.60	OK	2048	2026-09-11 20:42	46.59	OK
2049	2026-09-11 20:43	47.30	OK	2050	2026-09-11 20:44	47.31	OK
2051	2026-09-11 20:45	47.38	OK	2052	2026-09-11 20:46	46.16	OK
2053	2026-09-11 20:47	46.50	OK	2054	2026-09-11 20:48	48.28	OK
2055	2026-09-11 20:49	49.31	OK	2056	2026-09-11 20:50	47.47	OK
2057	2026-09-11 20:51	47.33	OK	2058	2026-09-11 20:52	47.99	OK
2059	2026-09-11 20:53	48.71	OK	2060	2026-09-11 20:54	45.12	OK
2061	2026-09-11 20:55	47.71	OK	2062	2026-09-11 20:56	48.14	OK
2063	2026-09-11 20:57	45.88	OK	2064	2026-09-11 20:58	45.09	OK
2065	2026-09-11 20:59	47.63	OK	2066	2026-09-11 21:00	46.93	OK
2067	2026-09-11 21:01	47.04	OK	2068	2026-09-11 21:02	48.25	OK
2069	2026-09-11 21:03	47.56	OK	2070	2026-09-11 21:04	48.41	OK
2071	2026-09-11 21:05	46.97	OK	2072	2026-09-11 21:06	47.04	OK
2073	2026-09-11 21:07	46.72	OK	2074	2026-09-11 21:08	46.50	OK
2075	2026-09-11 21:09	46.25	OK	2076	2026-09-11 21:10	47.55	OK
2077	2026-09-11 21:11	46.47	OK	2078	2026-09-11 21:12	46.85	OK
2079	2026-09-11 21:13	46.21	OK	2080	2026-09-11 21:14	47.66	OK
2081	2026-09-11 21:15	47.46	OK	2082	2026-09-11 21:16	48.14	OK
2083	2026-09-11 21:17	47.92	OK	2084	2026-09-11 21:18	46.67	OK
2085	2026-09-11 21:19	45.45	OK	2086	2026-09-11 21:20	47.84	OK
2087	2026-09-11 21:21	47.93	OK	2088	2026-09-11 21:22	47.32	OK
2089	2026-09-11 21:23	47.89	OK	2090	2026-09-11 21:24	45.66	OK
2091	2026-09-11 21:25	46.63	OK	2092	2026-09-11 21:26	46.90	OK
2093	2026-09-11 21:27	46.57	OK	2094	2026-09-11 21:28	47.40	OK
2095	2026-09-11 21:29	45.86	OK	2096	2026-09-11 21:30	45.82	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2097	2026-09-11 21:31	48.50	OK	2098	2026-09-11 21:32	47.20	OK
2099	2026-09-11 21:33	45.21	OK	2100	2026-09-11 21:34	47.01	OK
2101	2026-09-11 21:35	46.03	OK	2102	2026-09-11 21:36	45.78	OK
2103	2026-09-11 21:37	46.51	OK	2104	2026-09-11 21:38	45.04	OK
2105	2026-09-11 21:39	46.68	OK	2106	2026-09-11 21:40	44.49	OK
2107	2026-09-11 21:41	45.99	OK	2108	2026-09-11 21:42	44.44	OK
2109	2026-09-11 21:43	44.42	OK	2110	2026-09-11 21:44	46.15	OK
2111	2026-09-11 21:45	46.22	OK	2112	2026-09-11 21:46	47.85	OK
2113	2026-09-11 21:47	47.52	OK	2114	2026-09-11 21:48	45.51	OK
2115	2026-09-11 21:49	45.49	OK	2116	2026-09-11 21:50	47.85	OK
2117	2026-09-11 21:51	47.52	OK	2118	2026-09-11 21:52	45.98	OK
2119	2026-09-11 21:53	45.63	OK	2120	2026-09-11 21:54	47.13	OK
2121	2026-09-11 21:55	46.91	OK	2122	2026-09-11 21:56	47.55	OK
2123	2026-09-11 21:57	48.76	OK	2124	2026-09-11 21:58	48.61	OK
2125	2026-09-11 21:59	46.40	OK	2126	2026-09-11 22:00	46.73	OK
2127	2026-09-11 22:01	46.05	OK	2128	2026-09-11 22:02	47.15	OK
2129	2026-09-11 22:03	46.25	OK	2130	2026-09-11 22:04	48.18	OK
2131	2026-09-11 22:05	47.12	OK	2132	2026-09-11 22:06	45.50	OK
2133	2026-09-11 22:07	45.92	OK	2134	2026-09-11 22:08	46.87	OK
2135	2026-09-11 22:09	47.49	OK	2136	2026-09-11 22:10	46.73	OK
2137	2026-09-11 22:11	44.65	OK	2138	2026-09-11 22:12	45.12	OK
2139	2026-09-11 22:13	46.21	OK	2140	2026-09-11 22:14	44.55	OK
2141	2026-09-11 22:15	46.43	OK	2142	2026-09-11 22:16	47.31	OK
2143	2026-09-11 22:17	47.22	OK	2144	2026-09-11 22:18	45.41	OK
2145	2026-09-11 22:19	44.53	OK	2146	2026-09-11 22:20	46.05	OK
2147	2026-09-11 22:21	46.62	OK	2148	2026-09-11 22:22	46.16	OK
2149	2026-09-11 22:23	45.75	OK	2150	2026-09-11 22:24	46.74	OK
2151	2026-09-11 22:25	44.11	OK	2152	2026-09-11 22:26	46.81	OK
2153	2026-09-11 22:27	46.85	OK	2154	2026-09-11 22:28	44.50	OK
2155	2026-09-11 22:29	46.00	OK	2156	2026-09-11 22:30	46.20	OK
2157	2026-09-11 22:31	46.22	OK	2158	2026-09-11 22:32	46.60	OK
2159	2026-09-11 22:33	45.08	OK	2160	2026-09-11 22:34	45.33	OK
2161	2026-09-11 22:35	44.78	OK	2162	2026-09-11 22:36	45.87	OK
2163	2026-09-11 22:37	46.62	OK	2164	2026-09-11 22:38	45.96	OK
2165	2026-09-11 22:39	44.98	OK	2166	2026-09-11 22:40	46.34	OK
2167	2026-09-11 22:41	47.13	OK	2168	2026-09-11 22:42	44.91	OK
2169	2026-09-11 22:43	44.08	OK	2170	2026-09-11 22:44	46.64	OK
2171	2026-09-11 22:45	46.17	OK	2172	2026-09-11 22:46	45.30	OK
2173	2026-09-11 22:47	44.80	OK	2174	2026-09-11 22:48	47.46	OK
2175	2026-09-11 22:49	44.93	OK	2176	2026-09-11 22:50	46.02	OK
2177	2026-09-11 22:51	43.90	OK	2178	2026-09-11 22:52	44.10	OK
2179	2026-09-11 22:53	45.75	OK	2180	2026-09-11 22:54	46.21	OK
2181	2026-09-11 22:55	45.42	OK	2182	2026-09-11 22:56	47.78	OK
2183	2026-09-11 22:57	45.60	OK	2184	2026-09-11 22:58	44.62	OK
2185	2026-09-11 22:59	44.52	OK	2186	2026-09-11 23:00	44.80	OK
2187	2026-09-11 23:01	44.85	OK	2188	2026-09-11 23:02	45.28	OK
2189	2026-09-11 23:03	46.45	OK	2190	2026-09-11 23:04	45.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2191	2026-09-11 23:05	46.35	OK	2192	2026-09-11 23:06	47.81	OK
2193	2026-09-11 23:07	44.33	OK	2194	2026-09-11 23:08	47.00	OK
2195	2026-09-11 23:09	47.00	OK	2196	2026-09-11 23:10	44.84	OK
2197	2026-09-11 23:11	44.73	OK	2198	2026-09-11 23:12	47.19	OK
2199	2026-09-11 23:13	46.42	OK	2200	2026-09-11 23:14	45.93	OK
2201	2026-09-11 23:15	48.07	OK	2202	2026-09-11 23:16	45.48	OK
2203	2026-09-11 23:17	44.28	OK	2204	2026-09-11 23:18	46.94	OK
2205	2026-09-11 23:19	46.29	OK	2206	2026-09-11 23:20	46.72	OK
2207	2026-09-11 23:21	44.89	OK	2208	2026-09-11 23:22	47.15	OK
2209	2026-09-11 23:23	46.80	OK	2210	2026-09-11 23:24	45.43	OK
2211	2026-09-11 23:25	45.54	OK	2212	2026-09-11 23:26	43.78	OK
2213	2026-09-11 23:27	44.25	OK	2214	2026-09-11 23:28	44.51	OK
2215	2026-09-11 23:29	45.62	OK	2216	2026-09-11 23:30	45.23	OK
2217	2026-09-11 23:31	46.08	OK	2218	2026-09-11 23:32	46.71	OK
2219	2026-09-11 23:33	45.93	OK	2220	2026-09-11 23:34	45.88	OK
2221	2026-09-11 23:35	44.97	OK	2222	2026-09-11 23:36	45.38	OK
2223	2026-09-11 23:37	43.81	OK	2224	2026-09-11 23:38	44.58	OK
2225	2026-09-11 23:39	45.45	OK	2226	2026-09-11 23:40	45.00	OK
2227	2026-09-11 23:41	44.60	OK	2228	2026-09-11 23:42	45.46	OK
2229	2026-09-11 23:43	45.49	OK	2230	2026-09-11 23:44	47.45	OK
2231	2026-09-11 23:45	46.39	OK	2232	2026-09-11 23:46	43.56	OK
2233	2026-09-11 23:47	44.90	OK	2234	2026-09-11 23:48	44.64	OK
2235	2026-09-11 23:49	44.29	OK	2236	2026-09-11 23:50	47.11	OK
2237	2026-09-11 23:51	45.72	OK	2238	2026-09-11 23:52	45.35	OK
2239	2026-09-11 23:53	46.05	OK	2240	2026-09-11 23:54	45.84	OK
2241	2026-09-11 23:55	45.95	OK	2242	2026-09-11 23:56	47.26	OK
2243	2026-09-11 23:57	44.53	OK	2244	2026-09-11 23:58	43.62	OK
2245	2026-09-11 23:59	45.87	OK	2246	2026-09-12 00:00	45.58	OK
2247	2026-09-12 00:01	45.79	OK	2248	2026-09-12 00:02	45.94	OK
2249	2026-09-12 00:03	44.64	OK	2250	2026-09-12 00:04	45.02	OK
2251	2026-09-12 00:05	45.20	OK	2252	2026-09-12 00:06	47.81	OK
2253	2026-09-12 00:07	45.19	OK	2254	2026-09-12 00:08	44.47	OK
2255	2026-09-12 00:09	45.11	OK	2256	2026-09-12 00:10	46.92	OK
2257	2026-09-12 00:11	46.20	OK	2258	2026-09-12 00:12	46.42	OK
2259	2026-09-12 00:13	44.97	OK	2260	2026-09-12 00:14	46.32	OK
2261	2026-09-12 00:15	43.90	OK	2262	2026-09-12 00:16	46.12	OK
2263	2026-09-12 00:17	44.97	OK	2264	2026-09-12 00:18	45.47	OK
2265	2026-09-12 00:19	44.72	OK	2266	2026-09-12 00:20	47.14	OK
2267	2026-09-12 00:21	45.31	OK	2268	2026-09-12 00:22	45.45	OK
2269	2026-09-12 00:23	45.13	OK	2270	2026-09-12 00:24	44.23	OK
2271	2026-09-12 00:25	46.69	OK	2272	2026-09-12 00:26	43.59	OK
2273	2026-09-12 00:27	46.09	OK	2274	2026-09-12 00:28	45.25	OK
2275	2026-09-12 00:29	44.36	OK	2276	2026-09-12 00:30	44.52	OK
2277	2026-09-12 00:31	44.57	OK	2278	2026-09-12 00:32	47.64	OK
2279	2026-09-12 00:33	43.06	OK	2280	2026-09-12 00:34	45.54	OK
2281	2026-09-12 00:35	44.53	OK	2282	2026-09-12 00:36	45.46	OK
2283	2026-09-12 00:37	46.91	OK	2284	2026-09-12 00:38	45.44	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2285	2026-09-12 00:39	47.22	OK	2286	2026-09-12 00:40	44.58	OK
2287	2026-09-12 00:41	45.59	OK	2288	2026-09-12 00:42	43.91	OK
2289	2026-09-12 00:43	46.32	OK	2290	2026-09-12 00:44	44.43	OK
2291	2026-09-12 00:45	45.92	OK	2292	2026-09-12 00:46	43.84	OK
2293	2026-09-12 00:47	45.02	OK	2294	2026-09-12 00:48	44.14	OK
2295	2026-09-12 00:49	44.78	OK	2296	2026-09-12 00:50	44.50	OK
2297	2026-09-12 00:51	46.54	OK	2298	2026-09-12 00:52	44.07	OK
2299	2026-09-12 00:53	47.34	OK	2300	2026-09-12 00:54	45.23	OK
2301	2026-09-12 00:55	45.40	OK	2302	2026-09-12 00:56	46.55	OK
2303	2026-09-12 00:57	45.83	OK	2304	2026-09-12 00:58	45.58	OK
2305	2026-09-12 00:59	44.47	OK	2306	2026-09-12 01:00	45.33	OK
2307	2026-09-12 01:01	44.50	OK	2308	2026-09-12 01:02	45.48	OK
2309	2026-09-12 01:03	44.67	OK	2310	2026-09-12 01:04	46.83	OK
2311	2026-09-12 01:05	45.02	OK	2312	2026-09-12 01:06	44.83	OK
2313	2026-09-12 01:07	43.03	OK	2314	2026-09-12 01:08	45.24	OK
2315	2026-09-12 01:09	46.76	OK	2316	2026-09-12 01:10	43.80	OK
2317	2026-09-12 01:11	44.48	OK	2318	2026-09-12 01:12	46.69	OK
2319	2026-09-12 01:13	43.72	OK	2320	2026-09-12 01:14	46.19	OK
2321	2026-09-12 01:15	45.00	OK	2322	2026-09-12 01:16	45.85	OK
2323	2026-09-12 01:17	45.59	OK	2324	2026-09-12 01:18	44.16	OK
2325	2026-09-12 01:19	44.17	OK	2326	2026-09-12 01:20	45.26	OK
2327	2026-09-12 01:21	45.83	OK	2328	2026-09-12 01:22	45.06	OK
2329	2026-09-12 01:23	45.09	OK	2330	2026-09-12 01:24	46.96	OK
2331	2026-09-12 01:25	44.66	OK	2332	2026-09-12 01:26	47.40	OK
2333	2026-09-12 01:27	43.22	OK	2334	2026-09-12 01:28	46.63	OK
2335	2026-09-12 01:29	45.24	OK	2336	2026-09-12 01:30	45.04	OK
2337	2026-09-12 01:31	45.31	OK	2338	2026-09-12 01:32	45.02	OK
2339	2026-09-12 01:33	44.83	OK	2340	2026-09-12 01:34	45.76	OK
2341	2026-09-12 01:35	44.38	OK	2342	2026-09-12 01:36	45.39	OK
2343	2026-09-12 01:37	45.68	OK	2344	2026-09-12 01:38	45.34	OK
2345	2026-09-12 01:39	46.99	OK	2346	2026-09-12 01:40	45.31	OK
2347	2026-09-12 01:41	45.60	OK	2348	2026-09-12 01:42	45.88	OK
2349	2026-09-12 01:43	45.41	OK	2350	2026-09-12 01:44	44.81	OK
2351	2026-09-12 01:45	44.08	OK	2352	2026-09-12 01:46	45.67	OK
2353	2026-09-12 01:47	45.74	OK	2354	2026-09-12 01:48	45.55	OK
2355	2026-09-12 01:49	46.33	OK	2356	2026-09-12 01:50	44.64	OK
2357	2026-09-12 01:51	45.00	OK	2358	2026-09-12 01:52	46.99	OK
2359	2026-09-12 01:53	46.14	OK	2360	2026-09-12 01:54	45.79	OK
2361	2026-09-12 01:55	44.25	OK	2362	2026-09-12 01:56	44.38	OK
2363	2026-09-12 01:57	45.54	OK	2364	2026-09-12 01:58	45.77	OK
2365	2026-09-12 01:59	46.08	OK	2366	2026-09-12 02:00	45.84	OK
2367	2026-09-12 02:01	44.97	OK	2368	2026-09-12 02:02	45.33	OK
2369	2026-09-12 02:03	45.72	OK	2370	2026-09-12 02:04	45.35	OK
2371	2026-09-12 02:05	44.51	OK	2372	2026-09-12 02:06	45.80	OK
2373	2026-09-12 02:07	45.58	OK	2374	2026-09-12 02:08	44.91	OK
2375	2026-09-12 02:09	45.83	OK	2376	2026-09-12 02:10	46.99	OK
2377	2026-09-12 02:11	45.19	OK	2378	2026-09-12 02:12	42.56	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2379	2026-09-12 02:13	44.57	OK	2380	2026-09-12 02:14	46.03	OK
2381	2026-09-12 02:15	46.38	OK	2382	2026-09-12 02:16	44.88	OK
2383	2026-09-12 02:17	44.21	OK	2384	2026-09-12 02:18	44.84	OK
2385	2026-09-12 02:19	45.26	OK	2386	2026-09-12 02:20	44.69	OK
2387	2026-09-12 02:21	46.33	OK	2388	2026-09-12 02:22	44.37	OK
2389	2026-09-12 02:23	43.97	OK	2390	2026-09-12 02:24	47.21	OK
2391	2026-09-12 02:25	45.01	OK	2392	2026-09-12 02:26	43.49	OK
2393	2026-09-12 02:27	44.30	OK	2394	2026-09-12 02:28	47.56	OK
2395	2026-09-12 02:29	44.22	OK	2396	2026-09-12 02:30	44.72	OK
2397	2026-09-12 02:31	45.26	OK	2398	2026-09-12 02:32	45.42	OK
2399	2026-09-12 02:33	45.54	OK	2400	2026-09-12 02:34	44.07	OK
2401	2026-09-12 02:35	45.47	OK	2402	2026-09-12 02:36	45.23	OK
2403	2026-09-12 02:37	44.83	OK	2404	2026-09-12 02:38	43.50	OK
2405	2026-09-12 02:39	46.64	OK	2406	2026-09-12 02:40	44.48	OK
2407	2026-09-12 02:41	46.07	OK	2408	2026-09-12 02:42	45.20	OK
2409	2026-09-12 02:43	44.88	OK	2410	2026-09-12 02:44	46.44	OK
2411	2026-09-12 02:45	45.58	OK	2412	2026-09-12 02:46	45.25	OK
2413	2026-09-12 02:47	45.49	OK	2414	2026-09-12 02:48	44.48	OK
2415	2026-09-12 02:49	43.80	OK	2416	2026-09-12 02:50	46.41	OK
2417	2026-09-12 02:51	45.17	OK	2418	2026-09-12 02:52	43.49	OK
2419	2026-09-12 02:53	45.21	OK	2420	2026-09-12 02:54	46.38	OK
2421	2026-09-12 02:55	46.07	OK	2422	2026-09-12 02:56	44.94	OK
2423	2026-09-12 02:57	47.42	OK	2424	2026-09-12 02:58	45.25	OK
2425	2026-09-12 02:59	45.48	OK	2426	2026-09-12 03:00	46.04	OK
2427	2026-09-12 03:01	47.21	OK	2428	2026-09-12 03:02	44.70	OK
2429	2026-09-12 03:03	45.56	OK	2430	2026-09-12 03:04	46.48	OK
2431	2026-09-12 03:05	45.23	OK	2432	2026-09-12 03:06	44.71	OK
2433	2026-09-12 03:07	47.40	OK	2434	2026-09-12 03:08	45.17	OK
2435	2026-09-12 03:09	44.64	OK	2436	2026-09-12 03:10	44.65	OK
2437	2026-09-12 03:11	46.67	OK	2438	2026-09-12 03:12	44.57	OK
2439	2026-09-12 03:13	46.88	OK	2440	2026-09-12 03:14	46.30	OK
2441	2026-09-12 03:15	45.31	OK	2442	2026-09-12 03:16	44.69	OK
2443	2026-09-12 03:17	46.21	OK	2444	2026-09-12 03:18	45.96	OK
2445	2026-09-12 03:19	43.04	OK	2446	2026-09-12 03:20	45.29	OK
2447	2026-09-12 03:21	44.69	OK	2448	2026-09-12 03:22	45.91	OK
2449	2026-09-12 03:23	46.90	OK	2450	2026-09-12 03:24	46.19	OK
2451	2026-09-12 03:25	45.11	OK	2452	2026-09-12 03:26	44.85	OK
2453	2026-09-12 03:27	46.55	OK	2454	2026-09-12 03:28	45.37	OK
2455	2026-09-12 03:29	45.32	OK	2456	2026-09-12 03:30	44.48	OK
2457	2026-09-12 03:31	47.02	OK	2458	2026-09-12 03:32	45.82	OK
2459	2026-09-12 03:33	44.47	OK	2460	2026-09-12 03:34	48.30	OK
2461	2026-09-12 03:35	45.53	OK	2462	2026-09-12 03:36	44.96	OK
2463	2026-09-12 03:37	45.55	OK	2464	2026-09-12 03:38	44.17	OK
2465	2026-09-12 03:39	45.82	OK	2466	2026-09-12 03:40	46.82	OK
2467	2026-09-12 03:41	48.31	OK	2468	2026-09-12 03:42	45.33	OK
2469	2026-09-12 03:43	43.44	OK	2470	2026-09-12 03:44	44.50	OK
2471	2026-09-12 03:45	48.21	OK	2472	2026-09-12 03:46	44.65	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2473	2026-09-12 03:47	45.49	OK	2474	2026-09-12 03:48	44.72	OK
2475	2026-09-12 03:49	46.73	OK	2476	2026-09-12 03:50	45.72	OK
2477	2026-09-12 03:51	45.97	OK	2478	2026-09-12 03:52	45.84	OK
2479	2026-09-12 03:53	46.47	OK	2480	2026-09-12 03:54	45.74	OK
2481	2026-09-12 03:55	45.72	OK	2482	2026-09-12 03:56	45.99	OK
2483	2026-09-12 03:57	44.91	OK	2484	2026-09-12 03:58	46.86	OK
2485	2026-09-12 03:59	46.91	OK	2486	2026-09-12 04:00	45.60	OK
2487	2026-09-12 04:01	47.02	OK	2488	2026-09-12 04:02	44.81	OK
2489	2026-09-12 04:03	44.84	OK	2490	2026-09-12 04:04	45.63	OK
2491	2026-09-12 04:05	47.61	OK	2492	2026-09-12 04:06	46.82	OK
2493	2026-09-12 04:07	43.72	OK	2494	2026-09-12 04:08	45.80	OK
2495	2026-09-12 04:09	45.74	OK	2496	2026-09-12 04:10	45.14	OK
2497	2026-09-12 04:11	46.39	OK	2498	2026-09-12 04:12	45.57	OK
2499	2026-09-12 04:13	45.37	OK	2500	2026-09-12 04:14	46.44	OK
2501	2026-09-12 04:15	47.79	OK	2502	2026-09-12 04:16	46.43	OK
2503	2026-09-12 04:17	43.85	OK	2504	2026-09-12 04:18	45.52	OK
2505	2026-09-12 04:19	45.69	OK	2506	2026-09-12 04:20	47.02	OK
2507	2026-09-12 04:21	46.23	OK	2508	2026-09-12 04:22	47.52	OK
2509	2026-09-12 04:23	46.82	OK	2510	2026-09-12 04:24	47.23	OK
2511	2026-09-12 04:25	46.29	OK	2512	2026-09-12 04:26	45.66	OK
2513	2026-09-12 04:27	45.88	OK	2514	2026-09-12 04:28	48.25	OK
2515	2026-09-12 04:29	47.19	OK	2516	2026-09-12 04:30	45.98	OK
2517	2026-09-12 04:31	46.25	OK	2518	2026-09-12 04:32	46.62	OK
2519	2026-09-12 04:33	45.99	OK	2520	2026-09-12 04:34	46.81	OK
2521	2026-09-12 04:35	47.67	OK	2522	2026-09-12 04:36	44.98	OK
2523	2026-09-12 04:37	45.77	OK	2524	2026-09-12 04:38	45.00	OK
2525	2026-09-12 04:39	46.17	OK	2526	2026-09-12 04:40	44.90	OK
2527	2026-09-12 04:41	46.42	OK	2528	2026-09-12 04:42	46.21	OK
2529	2026-09-12 04:43	47.13	OK	2530	2026-09-12 04:44	46.77	OK
2531	2026-09-12 04:45	44.67	OK	2532	2026-09-12 04:46	45.78	OK
2533	2026-09-12 04:47	46.81	OK	2534	2026-09-12 04:48	46.86	OK
2535	2026-09-12 04:49	47.49	OK	2536	2026-09-12 04:50	45.88	OK
2537	2026-09-12 04:51	46.60	OK	2538	2026-09-12 04:52	46.96	OK
2539	2026-09-12 04:53	44.51	OK	2540	2026-09-12 04:54	45.76	OK
2541	2026-09-12 04:55	46.81	OK	2542	2026-09-12 04:56	46.67	OK
2543	2026-09-12 04:57	45.31	OK	2544	2026-09-12 04:58	46.89	OK
2545	2026-09-12 04:59	46.59	OK	2546	2026-09-12 05:00	47.08	OK
2547	2026-09-12 05:01	46.41	OK	2548	2026-09-12 05:02	46.95	OK
2549	2026-09-12 05:03	46.20	OK	2550	2026-09-12 05:04	47.19	OK
2551	2026-09-12 05:05	46.77	OK	2552	2026-09-12 05:06	45.76	OK
2553	2026-09-12 05:07	46.94	OK	2554	2026-09-12 05:08	46.46	OK
2555	2026-09-12 05:09	46.78	OK	2556	2026-09-12 05:10	46.86	OK
2557	2026-09-12 05:11	47.42	OK	2558	2026-09-12 05:12	46.60	OK
2559	2026-09-12 05:13	44.93	OK	2560	2026-09-12 05:14	47.18	OK
2561	2026-09-12 05:15	48.77	OK	2562	2026-09-12 05:16	47.84	OK
2563	2026-09-12 05:17	46.42	OK	2564	2026-09-12 05:18	46.21	OK
2565	2026-09-12 05:19	45.87	OK	2566	2026-09-12 05:20	46.02	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2567	2026-09-12 05:21	49.52	OK	2568	2026-09-12 05:22	46.52	OK
2569	2026-09-12 05:23	48.80	OK	2570	2026-09-12 05:24	47.72	OK
2571	2026-09-12 05:25	47.69	OK	2572	2026-09-12 05:26	47.40	OK
2573	2026-09-12 05:27	49.12	OK	2574	2026-09-12 05:28	46.35	OK
2575	2026-09-12 05:29	46.93	OK	2576	2026-09-12 05:30	46.96	OK
2577	2026-09-12 05:31	47.75	OK	2578	2026-09-12 05:32	46.04	OK
2579	2026-09-12 05:33	45.44	OK	2580	2026-09-12 05:34	45.28	OK
2581	2026-09-12 05:35	47.63	OK	2582	2026-09-12 05:36	46.34	OK
2583	2026-09-12 05:37	46.77	OK	2584	2026-09-12 05:38	48.52	OK
2585	2026-09-12 05:39	47.72	OK	2586	2026-09-12 05:40	47.95	OK
2587	2026-09-12 05:41	45.80	OK	2588	2026-09-12 05:42	47.13	OK
2589	2026-09-12 05:43	46.95	OK	2590	2026-09-12 05:44	49.49	OK
2591	2026-09-12 05:45	47.32	OK	2592	2026-09-12 05:46	46.51	OK
2593	2026-09-12 05:47	47.31	OK	2594	2026-09-12 05:48	46.85	OK
2595	2026-09-12 05:49	48.66	OK	2596	2026-09-12 05:50	47.33	OK
2597	2026-09-12 05:51	47.39	OK	2598	2026-09-12 05:52	46.24	OK
2599	2026-09-12 05:53	45.66	OK	2600	2026-09-12 05:54	47.28	OK
2601	2026-09-12 05:55	46.45	OK	2602	2026-09-12 05:56	46.77	OK
2603	2026-09-12 05:57	48.30	OK	2604	2026-09-12 05:58	47.10	OK
2605	2026-09-12 05:59	45.91	OK	2606	2026-09-12 06:00	47.49	OK
2607	2026-09-12 06:01	49.15	OK	2608	2026-09-12 06:02	47.45	OK
2609	2026-09-12 06:03	48.84	OK	2610	2026-09-12 06:04	47.44	OK
2611	2026-09-12 06:05	46.49	OK	2612	2026-09-12 06:06	46.56	OK
2613	2026-09-12 06:07	46.54	OK	2614	2026-09-12 06:08	46.06	OK
2615	2026-09-12 06:09	47.15	OK	2616	2026-09-12 06:10	48.26	OK
2617	2026-09-12 06:11	47.54	OK	2618	2026-09-12 06:12	45.51	OK
2619	2026-09-12 06:13	48.23	OK	2620	2026-09-12 06:14	48.50	OK
2621	2026-09-12 06:15	46.85	OK	2622	2026-09-12 06:16	47.45	OK
2623	2026-09-12 06:17	46.96	OK	2624	2026-09-12 06:18	47.37	OK
2625	2026-09-12 06:19	47.70	OK	2626	2026-09-12 06:20	48.23	OK
2627	2026-09-12 06:21	47.23	OK	2628	2026-09-12 06:22	48.37	OK
2629	2026-09-12 06:23	49.82	OK	2630	2026-09-12 06:24	46.97	OK
2631	2026-09-12 06:25	48.70	OK	2632	2026-09-12 06:26	49.76	OK
2633	2026-09-12 06:27	46.41	OK	2634	2026-09-12 06:28	48.76	OK
2635	2026-09-12 06:29	47.12	OK	2636	2026-09-12 06:30	48.54	OK
2637	2026-09-12 06:31	47.54	OK	2638	2026-09-12 06:32	45.28	OK
2639	2026-09-12 06:33	48.79	OK	2640	2026-09-12 06:34	48.92	OK
2641	2026-09-12 06:35	46.44	OK	2642	2026-09-12 06:36	47.83	OK
2643	2026-09-12 06:37	47.34	OK	2644	2026-09-12 06:38	47.89	OK
2645	2026-09-12 06:39	47.59	OK	2646	2026-09-12 06:40	46.36	OK
2647	2026-09-12 06:41	47.19	OK	2648	2026-09-12 06:42	46.93	OK
2649	2026-09-12 06:43	48.09	OK	2650	2026-09-12 06:44	47.17	OK
2651	2026-09-12 06:45	47.90	OK	2652	2026-09-12 06:46	49.36	OK
2653	2026-09-12 06:47	47.29	OK	2654	2026-09-12 06:48	45.91	OK
2655	2026-09-12 06:49	48.96	OK	2656	2026-09-12 06:50	47.68	OK
2657	2026-09-12 06:51	48.54	OK	2658	2026-09-12 06:52	48.86	OK
2659	2026-09-12 06:53	48.44	OK	2660	2026-09-12 06:54	47.00	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2661	2026-09-12 06:55	48.93	OK	2662	2026-09-12 06:56	48.33	OK
2663	2026-09-12 06:57	49.33	OK	2664	2026-09-12 06:58	48.33	OK
2665	2026-09-12 06:59	48.73	OK	2666	2026-09-12 07:00	46.91	OK
2667	2026-09-12 07:01	48.52	OK	2668	2026-09-12 07:02	48.67	OK
2669	2026-09-12 07:03	46.91	OK	2670	2026-09-12 07:04	47.40	OK
2671	2026-09-12 07:05	47.92	OK	2672	2026-09-12 07:06	47.74	OK
2673	2026-09-12 07:07	46.61	OK	2674	2026-09-12 07:08	48.58	OK
2675	2026-09-12 07:09	48.36	OK	2676	2026-09-12 07:10	46.86	OK
2677	2026-09-12 07:11	49.92	OK	2678	2026-09-12 07:12	49.51	OK
2679	2026-09-12 07:13	45.90	OK	2680	2026-09-12 07:14	48.97	OK
2681	2026-09-12 07:15	47.08	OK	2682	2026-09-12 07:16	48.92	OK
2683	2026-09-12 07:17	47.45	OK	2684	2026-09-12 07:18	47.83	OK
2685	2026-09-12 07:19	49.30	OK	2686	2026-09-12 07:20	47.47	OK
2687	2026-09-12 07:21	49.46	OK	2688	2026-09-12 07:22	48.97	OK
2689	2026-09-12 07:23	47.09	OK	2690	2026-09-12 07:24	48.39	OK
2691	2026-09-12 07:25	48.28	OK	2692	2026-09-12 07:26	47.59	OK
2693	2026-09-12 07:27	47.84	OK	2694	2026-09-12 07:28	46.87	OK
2695	2026-09-12 07:29	47.41	OK	2696	2026-09-12 07:30	50.13	OK
2697	2026-09-12 07:31	47.47	OK	2698	2026-09-12 07:32	47.18	OK
2699	2026-09-12 07:33	47.03	OK	2700	2026-09-12 07:34	48.75	OK
2701	2026-09-12 07:35	51.01	OK	2702	2026-09-12 07:36	49.14	OK
2703	2026-09-12 07:37	47.38	OK	2704	2026-09-12 07:38	48.30	OK
2705	2026-09-12 07:39	50.77	OK	2706	2026-09-12 07:40	48.91	OK
2707	2026-09-12 07:41	49.73	OK	2708	2026-09-12 07:42	49.11	OK
2709	2026-09-12 07:43	50.06	OK	2710	2026-09-12 07:44	47.81	OK
2711	2026-09-12 07:45	47.45	OK	2712	2026-09-12 07:46	49.68	OK
2713	2026-09-12 07:47	48.31	OK	2714	2026-09-12 07:48	49.30	OK
2715	2026-09-12 07:49	48.28	OK	2716	2026-09-12 07:50	49.85	OK
2717	2026-09-12 07:51	48.26	OK	2718	2026-09-12 07:52	48.64	OK
2719	2026-09-12 07:53	48.13	OK	2720	2026-09-12 07:54	48.79	OK
2721	2026-09-12 07:55	50.23	OK	2722	2026-09-12 07:56	49.61	OK
2723	2026-09-12 07:57	49.99	OK	2724	2026-09-12 07:58	50.09	OK
2725	2026-09-12 07:59	49.61	OK	2726	2026-09-12 08:00	50.20	OK
2727	2026-09-12 08:01	48.19	OK	2728	2026-09-12 08:02	49.70	OK
2729	2026-09-12 08:03	49.37	OK	2730	2026-09-12 08:04	48.62	OK
2731	2026-09-12 08:05	48.51	OK	2732	2026-09-12 08:06	48.21	OK
2733	2026-09-12 08:07	48.50	OK	2734	2026-09-12 08:08	48.00	OK
2735	2026-09-12 08:09	50.33	OK	2736	2026-09-12 08:10	49.54	OK
2737	2026-09-12 08:11	50.18	OK	2738	2026-09-12 08:12	48.47	OK
2739	2026-09-12 08:13	49.35	OK	2740	2026-09-12 08:14	50.09	OK
2741	2026-09-12 08:15	50.08	OK	2742	2026-09-12 08:16	50.03	OK
2743	2026-09-12 08:17	46.52	OK	2744	2026-09-12 08:18	49.45	OK
2745	2026-09-12 08:19	49.93	OK	2746	2026-09-12 08:20	51.37	OK
2747	2026-09-12 08:21	48.66	OK	2748	2026-09-12 08:22	49.17	OK
2749	2026-09-12 08:23	49.60	OK	2750	2026-09-12 08:24	49.12	OK
2751	2026-09-12 08:25	50.11	OK	2752	2026-09-12 08:26	50.79	OK
2753	2026-09-12 08:27	48.88	OK	2754	2026-09-12 08:28	49.56	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2755	2026-09-12 08:29	49.23	OK	2756	2026-09-12 08:30	49.60	OK
2757	2026-09-12 08:31	47.98	OK	2758	2026-09-12 08:32	48.34	OK
2759	2026-09-12 08:33	48.49	OK	2760	2026-09-12 08:34	49.64	OK
2761	2026-09-12 08:35	49.83	OK	2762	2026-09-12 08:36	49.95	OK
2763	2026-09-12 08:37	49.95	OK	2764	2026-09-12 08:38	48.53	OK
2765	2026-09-12 08:39	49.26	OK	2766	2026-09-12 08:40	49.51	OK
2767	2026-09-12 08:41	50.15	OK	2768	2026-09-12 08:42	49.55	OK
2769	2026-09-12 08:43	49.90	OK	2770	2026-09-12 08:44	49.60	OK
2771	2026-09-12 08:45	49.75	OK	2772	2026-09-12 08:46	49.83	OK
2773	2026-09-12 08:47	50.64	OK	2774	2026-09-12 08:48	48.63	OK
2775	2026-09-12 08:49	51.53	OK	2776	2026-09-12 08:50	50.61	OK
2777	2026-09-12 08:51	49.09	OK	2778	2026-09-12 08:52	48.62	OK
2779	2026-09-12 08:53	49.57	OK	2780	2026-09-12 08:54	50.04	OK
2781	2026-09-12 08:55	50.17	OK	2782	2026-09-12 08:56	49.21	OK
2783	2026-09-12 08:57	50.88	OK	2784	2026-09-12 08:58	49.41	OK
2785	2026-09-12 08:59	49.71	OK	2786	2026-09-12 09:00	49.59	OK
2787	2026-09-12 09:01	50.13	OK	2788	2026-09-12 09:02	50.94	OK
2789	2026-09-12 09:03	51.08	OK	2790	2026-09-12 09:04	49.08	OK
2791	2026-09-12 09:05	49.22	OK	2792	2026-09-12 09:06	50.92	OK
2793	2026-09-12 09:07	49.96	OK	2794	2026-09-12 09:08	48.79	OK
2795	2026-09-12 09:09	51.26	OK	2796	2026-09-12 09:10	50.57	OK
2797	2026-09-12 09:11	50.78	OK	2798	2026-09-12 09:12	50.42	OK
2799	2026-09-12 09:13	50.07	OK	2800	2026-09-12 09:14	51.43	OK
2801	2026-09-12 09:15	50.03	OK	2802	2026-09-12 09:16	49.10	OK
2803	2026-09-12 09:17	49.70	OK	2804	2026-09-12 09:18	48.99	OK
2805	2026-09-12 09:19	49.85	OK	2806	2026-09-12 09:20	49.56	OK
2807	2026-09-12 09:21	49.05	OK	2808	2026-09-12 09:22	48.43	OK
2809	2026-09-12 09:23	50.05	OK	2810	2026-09-12 09:24	49.20	OK
2811	2026-09-12 09:25	50.30	OK	2812	2026-09-12 09:26	49.54	OK
2813	2026-09-12 09:27	51.79	OK	2814	2026-09-12 09:28	50.69	OK
2815	2026-09-12 09:29	51.41	OK	2816	2026-09-12 09:30	51.72	OK
2817	2026-09-12 09:31	51.58	OK	2818	2026-09-12 09:32	50.89	OK
2819	2026-09-12 09:33	51.96	OK	2820	2026-09-12 09:34	51.08	OK
2821	2026-09-12 09:35	49.03	OK	2822	2026-09-12 09:36	49.83	OK
2823	2026-09-12 09:37	51.40	OK	2824	2026-09-12 09:38	49.72	OK
2825	2026-09-12 09:39	51.96	OK	2826	2026-09-12 09:40	50.75	OK
2827	2026-09-12 09:41	50.35	OK	2828	2026-09-12 09:42	51.57	OK
2829	2026-09-12 09:43	51.42	OK	2830	2026-09-12 09:44	50.46	OK
2831	2026-09-12 09:45	49.23	OK	2832	2026-09-12 09:46	48.13	OK
2833	2026-09-12 09:47	51.27	OK	2834	2026-09-12 09:48	53.07	OK
2835	2026-09-12 09:49	51.10	OK	2836	2026-09-12 09:50	51.18	OK
2837	2026-09-12 09:51	51.49	OK	2838	2026-09-12 09:52	48.77	OK
2839	2026-09-12 09:53	49.82	OK	2840	2026-09-12 09:54	52.19	OK
2841	2026-09-12 09:55	50.10	OK	2842	2026-09-12 09:56	52.36	OK
2843	2026-09-12 09:57	51.81	OK	2844	2026-09-12 09:58	51.22	OK
2845	2026-09-12 09:59	50.95	OK	2846	2026-09-12 10:00	51.85	OK
2847	2026-09-12 10:01	52.60	OK	2848	2026-09-12 10:02	50.31	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2849	2026-09-12 10:03	52.97	OK	2850	2026-09-12 10:04	51.76	OK
2851	2026-09-12 10:05	50.47	OK	2852	2026-09-12 10:06	50.21	OK
2853	2026-09-12 10:07	49.47	OK	2854	2026-09-12 10:08	50.58	OK
2855	2026-09-12 10:09	50.74	OK	2856	2026-09-12 10:10	50.91	OK
2857	2026-09-12 10:11	52.55	OK	2858	2026-09-12 10:12	52.45	OK
2859	2026-09-12 10:13	50.23	OK	2860	2026-09-12 10:14	49.34	OK
2861	2026-09-12 10:15	50.70	OK	2862	2026-09-12 10:16	49.28	OK
2863	2026-09-12 10:17	49.57	OK	2864	2026-09-12 10:18	49.92	OK
2865	2026-09-12 10:19	50.97	OK	2866	2026-09-12 10:20	49.20	OK
2867	2026-09-12 10:21	50.46	OK	2868	2026-09-12 10:22	50.47	OK
2869	2026-09-12 10:23	49.54	OK	2870	2026-09-12 10:24	50.43	OK
2871	2026-09-12 10:25	50.00	OK	2872	2026-09-12 10:26	50.75	OK
2873	2026-09-12 10:27	52.42	OK	2874	2026-09-12 10:28	50.35	OK
2875	2026-09-12 10:29	51.73	OK	2876	2026-09-12 10:30	49.30	OK
2877	2026-09-12 10:31	52.10	OK	2878	2026-09-12 10:32	52.04	OK
2879	2026-09-12 10:33	51.29	OK	2880	2026-09-12 10:34	49.35	OK
2881	2026-09-12 10:35	48.66	OK	2882	2026-09-12 10:36	53.67	OK
2883	2026-09-12 10:37	49.52	OK	2884	2026-09-12 10:38	51.03	OK
2885	2026-09-12 10:39	51.21	OK	2886	2026-09-12 10:40	49.63	OK
2887	2026-09-12 10:41	52.32	OK	2888	2026-09-12 10:42	50.69	OK
2889	2026-09-12 10:43	51.26	OK	2890	2026-09-12 10:44	49.47	OK
2891	2026-09-12 10:45	50.38	OK	2892	2026-09-12 10:46	51.79	OK
2893	2026-09-12 10:47	52.18	OK	2894	2026-09-12 10:48	51.22	OK
2895	2026-09-12 10:49	49.94	OK	2896	2026-09-12 10:50	51.74	OK
2897	2026-09-12 10:51	51.27	OK	2898	2026-09-12 10:52	52.85	OK
2899	2026-09-12 10:53	49.56	OK	2900	2026-09-12 10:54	51.01	OK
2901	2026-09-12 10:55	49.26	OK	2902	2026-09-12 10:56	52.21	OK
2903	2026-09-12 10:57	50.26	OK	2904	2026-09-12 10:58	51.50	OK
2905	2026-09-12 10:59	48.52	OK	2906	2026-09-12 11:00	50.78	OK
2907	2026-09-12 11:01	51.51	OK	2908	2026-09-12 11:02	50.23	OK
2909	2026-09-12 11:03	51.78	OK	2910	2026-09-12 11:04	50.98	OK
2911	2026-09-12 11:05	52.22	OK	2912	2026-09-12 11:06	50.38	OK
2913	2026-09-12 11:07	50.15	OK	2914	2026-09-12 11:08	52.23	OK
2915	2026-09-12 11:09	53.78	OK	2916	2026-09-12 11:10	50.54	OK
2917	2026-09-12 11:11	52.09	OK	2918	2026-09-12 11:12	50.84	OK
2919	2026-09-12 11:13	50.58	OK	2920	2026-09-12 11:14	50.62	OK
2921	2026-09-12 11:15	51.92	OK	2922	2026-09-12 11:16	51.71	OK
2923	2026-09-12 11:17	50.63	OK	2924	2026-09-12 11:18	53.61	OK
2925	2026-09-12 11:19	51.41	OK	2926	2026-09-12 11:20	53.62	OK
2927	2026-09-12 11:21	48.86	OK	2928	2026-09-12 11:22	52.33	OK
2929	2026-09-12 11:23	50.71	OK	2930	2026-09-12 11:24	51.88	OK
2931	2026-09-12 11:25	51.38	OK	2932	2026-09-12 11:26	51.09	OK
2933	2026-09-12 11:27	52.88	OK	2934	2026-09-12 11:28	49.57	OK
2935	2026-09-12 11:29	49.42	OK	2936	2026-09-12 11:30	52.81	OK
2937	2026-09-12 11:31	50.44	OK	2938	2026-09-12 11:32	52.23	OK
2939	2026-09-12 11:33	51.99	OK	2940	2026-09-12 11:34	49.73	OK
2941	2026-09-12 11:35	54.03	OK	2942	2026-09-12 11:36	53.10	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2943	2026-09-12 11:37	50.68	OK	2944	2026-09-12 11:38	50.86	OK
2945	2026-09-12 11:39	50.70	OK	2946	2026-09-12 11:40	52.04	OK
2947	2026-09-12 11:41	51.37	OK	2948	2026-09-12 11:42	52.17	OK
2949	2026-09-12 11:43	51.86	OK	2950	2026-09-12 11:44	53.29	OK
2951	2026-09-12 11:45	51.65	OK	2952	2026-09-12 11:46	52.26	OK
2953	2026-09-12 11:47	52.66	OK	2954	2026-09-12 11:48	50.43	OK
2955	2026-09-12 11:49	51.62	OK	2956	2026-09-12 11:50	52.82	OK
2957	2026-09-12 11:51	51.02	OK	2958	2026-09-12 11:52	52.30	OK
2959	2026-09-12 11:53	52.06	OK	2960	2026-09-12 11:54	52.25	OK
2961	2026-09-12 11:55	52.34	OK	2962	2026-09-12 11:56	51.70	OK
2963	2026-09-12 11:57	50.34	OK	2964	2026-09-12 11:58	49.69	OK
2965	2026-09-12 11:59	50.95	OK	2966	2026-09-12 12:00	51.89	OK
2967	2026-09-12 12:01	50.25	OK	2968	2026-09-12 12:02	50.51	OK
2969	2026-09-12 12:03	53.20	OK	2970	2026-09-12 12:04	52.18	OK
2971	2026-09-12 12:05	51.85	OK	2972	2026-09-12 12:06	50.39	OK
2973	2026-09-12 12:07	50.92	OK	2974	2026-09-12 12:08	51.39	OK
2975	2026-09-12 12:09	51.98	OK	2976	2026-09-12 12:10	52.66	OK
2977	2026-09-12 12:11	50.71	OK	2978	2026-09-12 12:12	52.89	OK
2979	2026-09-12 12:13	54.17	OK	2980	2026-09-12 12:14	51.32	OK
2981	2026-09-12 12:15	51.77	OK	2982	2026-09-12 12:16	52.10	OK
2983	2026-09-12 12:17	52.21	OK	2984	2026-09-12 12:18	51.35	OK
2985	2026-09-12 12:19	51.44	OK	2986	2026-09-12 12:20	49.91	OK
2987	2026-09-12 12:21	50.62	OK	2988	2026-09-12 12:22	51.77	OK
2989	2026-09-12 12:23	51.76	OK	2990	2026-09-12 12:24	50.70	OK
2991	2026-09-12 12:25	52.28	OK	2992	2026-09-12 12:26	51.08	OK
2993	2026-09-12 12:27	52.21	OK	2994	2026-09-12 12:28	50.76	OK
2995	2026-09-12 12:29	52.18	OK	2996	2026-09-12 12:30	52.12	OK
2997	2026-09-12 12:31	52.17	OK	2998	2026-09-12 12:32	52.03	OK
2999	2026-09-12 12:33	51.15	OK	3000	2026-09-12 12:34	51.38	OK
3001	2026-09-12 12:35	51.84	OK	3002	2026-09-12 12:36	50.67	OK
3003	2026-09-12 12:37	50.60	OK	3004	2026-09-12 12:38	52.47	OK
3005	2026-09-12 12:39	54.09	OK	3006	2026-09-12 12:40	51.28	OK
3007	2026-09-12 12:41	51.06	OK	3008	2026-09-12 12:42	52.14	OK
3009	2026-09-12 12:43	54.02	OK	3010	2026-09-12 12:44	50.43	OK
3011	2026-09-12 12:45	51.36	OK	3012	2026-09-12 12:46	50.89	OK
3013	2026-09-12 12:47	51.28	OK	3014	2026-09-12 12:48	52.84	OK
3015	2026-09-12 12:49	52.10	OK	3016	2026-09-12 12:50	49.86	OK
3017	2026-09-12 12:51	50.93	OK	3018	2026-09-12 12:52	51.30	OK
3019	2026-09-12 12:53	52.49	OK	3020	2026-09-12 12:54	52.00	OK
3021	2026-09-12 12:55	51.91	OK	3022	2026-09-12 12:56	53.73	OK
3023	2026-09-12 12:57	51.95	OK	3024	2026-09-12 12:58	51.96	OK
3025	2026-09-12 12:59	50.13	OK	3026	2026-09-12 13:00	52.37	OK
3027	2026-09-12 13:01	50.65	OK	3028	2026-09-12 13:02	50.03	OK
3029	2026-09-12 13:03	52.78	OK	3030	2026-09-12 13:04	51.03	OK
3031	2026-09-12 13:05	50.97	OK	3032	2026-09-12 13:06	52.96	OK
3033	2026-09-12 13:07	51.86	OK	3034	2026-09-12 13:08	50.81	OK
3035	2026-09-12 13:09	50.49	OK	3036	2026-09-12 13:10	52.98	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3037	2026-09-12 13:11	50.00	OK	3038	2026-09-12 13:12	51.68	OK
3039	2026-09-12 13:13	51.10	OK	3040	2026-09-12 13:14	50.58	OK
3041	2026-09-12 13:15	52.27	OK	3042	2026-09-12 13:16	54.55	OK
3043	2026-09-12 13:17	50.93	OK	3044	2026-09-12 13:18	51.23	OK
3045	2026-09-12 13:19	53.03	OK	3046	2026-09-12 13:20	54.26	OK
3047	2026-09-12 13:21	52.95	OK	3048	2026-09-12 13:22	53.33	OK
3049	2026-09-12 13:23	50.21	OK	3050	2026-09-12 13:24	53.62	OK
3051	2026-09-12 13:25	51.43	OK	3052	2026-09-12 13:26	52.30	OK
3053	2026-09-12 13:27	52.26	OK	3054	2026-09-12 13:28	52.57	OK
3055	2026-09-12 13:29	52.64	OK	3056	2026-09-12 13:30	52.40	OK
3057	2026-09-12 13:31	51.50	OK	3058	2026-09-12 13:32	52.01	OK
3059	2026-09-12 13:33	50.70	OK	3060	2026-09-12 13:34	51.09	OK
3061	2026-09-12 13:35	51.54	OK	3062	2026-09-12 13:36	52.12	OK
3063	2026-09-12 13:37	51.32	OK	3064	2026-09-12 13:38	52.59	OK
3065	2026-09-12 13:39	52.82	OK	3066	2026-09-12 13:40	51.49	OK
3067	2026-09-12 13:41	51.10	OK	3068	2026-09-12 13:42	53.23	OK
3069	2026-09-12 13:43	53.49	OK	3070	2026-09-12 13:44	51.75	OK
3071	2026-09-12 13:45	49.99	OK	3072	2026-09-12 13:46	53.57	OK
3073	2026-09-12 13:47	51.62	OK	3074	2026-09-12 13:48	50.92	OK
3075	2026-09-12 13:49	50.78	OK	3076	2026-09-12 13:50	52.68	OK
3077	2026-09-12 13:51	53.00	OK	3078	2026-09-12 13:52	52.19	OK
3079	2026-09-12 13:53	50.29	OK	3080	2026-09-12 13:54	50.68	OK
3081	2026-09-12 13:55	50.52	OK	3082	2026-09-12 13:56	51.45	OK
3083	2026-09-12 13:57	52.55	OK	3084	2026-09-12 13:58	50.24	OK
3085	2026-09-12 13:59	52.05	OK	3086	2026-09-12 14:00	51.22	OK
3087	2026-09-12 14:01	53.26	OK	3088	2026-09-12 14:02	52.48	OK
3089	2026-09-12 14:03	52.79	OK	3090	2026-09-12 14:04	53.41	OK
3091	2026-09-12 14:05	52.06	OK	3092	2026-09-12 14:06	51.62	OK
3093	2026-09-12 14:07	51.75	OK	3094	2026-09-12 14:08	52.67	OK
3095	2026-09-12 14:09	52.49	OK	3096	2026-09-12 14:10	51.65	OK
3097	2026-09-12 14:11	53.44	OK	3098	2026-09-12 14:12	52.65	OK
3099	2026-09-12 14:13	51.78	OK	3100	2026-09-12 14:14	50.70	OK
3101	2026-09-12 14:15	52.70	OK	3102	2026-09-12 14:16	53.15	OK
3103	2026-09-12 14:17	53.79	OK	3104	2026-09-12 14:18	52.79	OK
3105	2026-09-12 14:19	52.86	OK	3106	2026-09-12 14:20	52.03	OK
3107	2026-09-12 14:21	51.63	OK	3108	2026-09-12 14:22	51.04	OK
3109	2026-09-12 14:23	51.69	OK	3110	2026-09-12 14:24	52.06	OK
3111	2026-09-12 14:25	51.77	OK	3112	2026-09-12 14:26	50.42	OK
3113	2026-09-12 14:27	51.82	OK	3114	2026-09-12 14:28	51.48	OK
3115	2026-09-12 14:29	51.34	OK	3116	2026-09-12 14:30	50.48	OK
3117	2026-09-12 14:31	51.63	OK	3118	2026-09-12 14:32	50.33	OK
3119	2026-09-12 14:33	49.87	OK	3120	2026-09-12 14:34	52.20	OK
3121	2026-09-12 14:35	52.23	OK	3122	2026-09-12 14:36	51.11	OK
3123	2026-09-12 14:37	52.06	OK	3124	2026-09-12 14:38	51.79	OK
3125	2026-09-12 14:39	51.47	OK	3126	2026-09-12 14:40	51.31	OK
3127	2026-09-12 14:41	51.01	OK	3128	2026-09-12 14:42	53.35	OK
3129	2026-09-12 14:43	51.71	OK	3130	2026-09-12 14:44	51.08	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3131	2026-09-12 14:45	53.52	OK	3132	2026-09-12 14:46	51.65	OK
3133	2026-09-12 14:47	51.21	OK	3134	2026-09-12 14:48	52.09	OK
3135	2026-09-12 14:49	50.18	OK	3136	2026-09-12 14:50	53.18	OK
3137	2026-09-12 14:51	53.23	OK	3138	2026-09-12 14:52	51.61	OK
3139	2026-09-12 14:53	53.08	OK	3140	2026-09-12 14:54	53.47	OK
3141	2026-09-12 14:55	50.80	OK	3142	2026-09-12 14:56	50.26	OK
3143	2026-09-12 14:57	50.26	OK	3144	2026-09-12 14:58	52.88	OK
3145	2026-09-12 14:59	52.45	OK	3146	2026-09-12 15:00	51.87	OK
3147	2026-09-12 15:01	51.98	OK	3148	2026-09-12 15:02	52.17	OK
3149	2026-09-12 15:03	49.98	OK	3150	2026-09-12 15:04	50.84	OK
3151	2026-09-12 15:05	52.92	OK	3152	2026-09-12 15:06	52.01	OK
3153	2026-09-12 15:07	50.52	OK	3154	2026-09-12 15:08	51.87	OK
3155	2026-09-12 15:09	53.35	OK	3156	2026-09-12 15:10	51.02	OK
3157	2026-09-12 15:11	50.88	OK	3158	2026-09-12 15:12	51.27	OK
3159	2026-09-12 15:13	51.98	OK	3160	2026-09-12 15:14	50.92	OK
3161	2026-09-12 15:15	49.57	OK	3162	2026-09-12 15:16	52.64	OK
3163	2026-09-12 15:17	49.66	OK	3164	2026-09-12 15:18	52.63	OK
3165	2026-09-12 15:19	51.76	OK	3166	2026-09-12 15:20	50.99	OK
3167	2026-09-12 15:21	52.93	OK	3168	2026-09-12 15:22	53.14	OK
3169	2026-09-12 15:23	52.08	OK	3170	2026-09-12 15:24	51.13	OK
3171	2026-09-12 15:25	51.02	OK	3172	2026-09-12 15:26	51.71	OK
3173	2026-09-12 15:27	52.81	OK	3174	2026-09-12 15:28	51.86	OK
3175	2026-09-12 15:29	52.95	OK	3176	2026-09-12 15:30	49.90	OK
3177	2026-09-12 15:31	51.73	OK	3178	2026-09-12 15:32	52.70	OK
3179	2026-09-12 15:33	51.91	OK	3180	2026-09-12 15:34	51.34	OK
3181	2026-09-12 15:35	51.97	OK	3182	2026-09-12 15:36	50.62	OK
3183	2026-09-12 15:37	50.57	OK	3184	2026-09-12 15:38	51.03	OK
3185	2026-09-12 15:39	51.07	OK	3186	2026-09-12 15:40	51.59	OK
3187	2026-09-12 15:41	51.04	OK	3188	2026-09-12 15:42	51.37	OK
3189	2026-09-12 15:43	51.01	OK	3190	2026-09-12 15:44	51.88	OK
3191	2026-09-12 15:45	50.70	OK	3192	2026-09-12 15:46	51.46	OK
3193	2026-09-12 15:47	51.30	OK	3194	2026-09-12 15:48	52.88	OK
3195	2026-09-12 15:49	51.13	OK	3196	2026-09-12 15:50	52.56	OK
3197	2026-09-12 15:51	51.43	OK	3198	2026-09-12 15:52	52.29	OK
3199	2026-09-12 15:53	49.68	OK	3200	2026-09-12 15:54	52.51	OK
3201	2026-09-12 15:55	52.38	OK	3202	2026-09-12 15:56	51.60	OK
3203	2026-09-12 15:57	51.20	OK	3204	2026-09-12 15:58	52.83	OK
3205	2026-09-12 15:59	50.00	OK	3206	2026-09-12 16:00	53.49	OK
3207	2026-09-12 16:01	51.67	OK	3208	2026-09-12 16:02	52.72	OK
3209	2026-09-12 16:03	51.56	OK	3210	2026-09-12 16:04	51.53	OK
3211	2026-09-12 16:05	51.64	OK	3212	2026-09-12 16:06	51.29	OK
3213	2026-09-12 16:07	51.80	OK	3214	2026-09-12 16:08	50.70	OK
3215	2026-09-12 16:09	50.57	OK	3216	2026-09-12 16:10	51.89	OK
3217	2026-09-12 16:11	51.29	OK	3218	2026-09-12 16:12	50.07	OK
3219	2026-09-12 16:13	51.35	OK	3220	2026-09-12 16:14	50.04	OK
3221	2026-09-12 16:15	51.54	OK	3222	2026-09-12 16:16	51.31	OK
3223	2026-09-12 16:17	49.63	OK	3224	2026-09-12 16:18	52.38	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3225	2026-09-12 16:19	51.41	OK	3226	2026-09-12 16:20	52.09	OK
3227	2026-09-12 16:21	50.97	OK	3228	2026-09-12 16:22	49.71	OK
3229	2026-09-12 16:23	50.87	OK	3230	2026-09-12 16:24	51.33	OK
3231	2026-09-12 16:25	51.30	OK	3232	2026-09-12 16:26	50.65	OK
3233	2026-09-12 16:27	51.55	OK	3234	2026-09-12 16:28	51.36	OK
3235	2026-09-12 16:29	52.02	OK	3236	2026-09-12 16:30	50.70	OK
3237	2026-09-12 16:31	49.62	OK	3238	2026-09-12 16:32	51.88	OK
3239	2026-09-12 16:33	51.57	OK	3240	2026-09-12 16:34	50.25	OK
3241	2026-09-12 16:35	50.13	OK	3242	2026-09-12 16:36	52.99	OK
3243	2026-09-12 16:37	51.28	OK	3244	2026-09-12 16:38	50.42	OK
3245	2026-09-12 16:39	49.73	OK	3246	2026-09-12 16:40	50.67	OK
3247	2026-09-12 16:41	51.27	OK	3248	2026-09-12 16:42	52.25	OK
3249	2026-09-12 16:43	50.66	OK	3250	2026-09-12 16:44	51.10	OK
3251	2026-09-12 16:45	50.38	OK	3252	2026-09-12 16:46	51.58	OK
3253	2026-09-12 16:47	51.94	OK	3254	2026-09-12 16:48	51.40	OK
3255	2026-09-12 16:49	51.95	OK	3256	2026-09-12 16:50	50.45	OK
3257	2026-09-12 16:51	49.77	OK	3258	2026-09-12 16:52	51.13	OK
3259	2026-09-12 16:53	51.69	OK	3260	2026-09-12 16:54	49.74	OK
3261	2026-09-12 16:55	51.53	OK	3262	2026-09-12 16:56	49.51	OK
3263	2026-09-12 16:57	49.04	OK	3264	2026-09-12 16:58	49.95	OK
3265	2026-09-12 16:59	51.46	OK	3266	2026-09-12 17:00	50.88	OK
3267	2026-09-12 17:01	51.85	OK	3268	2026-09-12 17:02	49.40	OK
3269	2026-09-12 17:03	52.60	OK	3270	2026-09-12 17:04	49.99	OK
3271	2026-09-12 17:05	50.16	OK	3272	2026-09-12 17:06	50.92	OK
3273	2026-09-12 17:07	51.43	OK	3274	2026-09-12 17:08	51.34	OK
3275	2026-09-12 17:09	51.51	OK	3276	2026-09-12 17:10	49.54	OK
3277	2026-09-12 17:11	51.37	OK	3278	2026-09-12 17:12	51.13	OK
3279	2026-09-12 17:13	50.65	OK	3280	2026-09-12 17:14	50.30	OK
3281	2026-09-12 17:15	49.61	OK	3282	2026-09-12 17:16	50.57	OK
3283	2026-09-12 17:17	51.34	OK	3284	2026-09-12 17:18	48.93	OK
3285	2026-09-12 17:19	49.55	OK	3286	2026-09-12 17:20	49.62	OK
3287	2026-09-12 17:21	48.92	OK	3288	2026-09-12 17:22	49.46	OK
3289	2026-09-12 17:23	50.78	OK	3290	2026-09-12 17:24	51.30	OK
3291	2026-09-12 17:25	49.16	OK	3292	2026-09-12 17:26	49.49	OK
3293	2026-09-12 17:27	51.19	OK	3294	2026-09-12 17:28	51.65	OK
3295	2026-09-12 17:29	51.54	OK	3296	2026-09-12 17:30	50.29	OK
3297	2026-09-12 17:31	49.07	OK	3298	2026-09-12 17:32	51.18	OK
3299	2026-09-12 17:33	49.15	OK	3300	2026-09-12 17:34	50.14	OK
3301	2026-09-12 17:35	49.69	OK	3302	2026-09-12 17:36	49.33	OK
3303	2026-09-12 17:37	48.82	OK	3304	2026-09-12 17:38	51.24	OK
3305	2026-09-12 17:39	51.05	OK	3306	2026-09-12 17:40	50.50	OK
3307	2026-09-12 17:41	49.95	OK	3308	2026-09-12 17:42	49.22	OK
3309	2026-09-12 17:43	47.98	OK	3310	2026-09-12 17:44	51.28	OK
3311	2026-09-12 17:45	50.07	OK	3312	2026-09-12 17:46	51.15	OK
3313	2026-09-12 17:47	49.18	OK	3314	2026-09-12 17:48	49.42	OK
3315	2026-09-12 17:49	49.28	OK	3316	2026-09-12 17:50	50.76	OK
3317	2026-09-12 17:51	50.89	OK	3318	2026-09-12 17:52	49.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3319	2026-09-12 17:53	52.06	OK	3320	2026-09-12 17:54	50.60	OK
3321	2026-09-12 17:55	49.92	OK	3322	2026-09-12 17:56	49.17	OK
3323	2026-09-12 17:57	50.62	OK	3324	2026-09-12 17:58	50.82	OK
3325	2026-09-12 17:59	50.86	OK	3326	2026-09-12 18:00	49.72	OK
3327	2026-09-12 18:01	47.39	OK	3328	2026-09-12 18:02	48.91	OK
3329	2026-09-12 18:03	50.88	OK	3330	2026-09-12 18:04	49.83	OK
3331	2026-09-12 18:05	51.42	OK	3332	2026-09-12 18:06	49.79	OK
3333	2026-09-12 18:07	47.58	OK	3334	2026-09-12 18:08	50.16	OK
3335	2026-09-12 18:09	48.00	OK	3336	2026-09-12 18:10	48.47	OK
3337	2026-09-12 18:11	50.57	OK	3338	2026-09-12 18:12	47.70	OK
3339	2026-09-12 18:13	50.10	OK	3340	2026-09-12 18:14	49.67	OK
3341	2026-09-12 18:15	48.48	OK	3342	2026-09-12 18:16	48.66	OK
3343	2026-09-12 18:17	49.74	OK	3344	2026-09-12 18:18	49.37	OK
3345	2026-09-12 18:19	49.93	OK	3346	2026-09-12 18:20	50.84	OK
3347	2026-09-12 18:21	51.33	OK	3348	2026-09-12 18:22	47.99	OK
3349	2026-09-12 18:23	49.31	OK	3350	2026-09-12 18:24	49.47	OK
3351	2026-09-12 18:25	50.02	OK	3352	2026-09-12 18:26	50.69	OK
3353	2026-09-12 18:27	51.34	OK	3354	2026-09-12 18:28	49.93	OK
3355	2026-09-12 18:29	49.66	OK	3356	2026-09-12 18:30	50.35	OK
3357	2026-09-12 18:31	48.96	OK	3358	2026-09-12 18:32	49.76	OK
3359	2026-09-12 18:33	48.88	OK	3360	2026-09-12 18:34	48.65	OK
3361	2026-09-12 18:35	51.63	OK	3362	2026-09-12 18:36	50.43	OK
3363	2026-09-12 18:37	48.31	OK	3364	2026-09-12 18:38	49.53	OK
3365	2026-09-12 18:39	47.42	OK	3366	2026-09-12 18:40	48.60	OK
3367	2026-09-12 18:41	51.13	OK	3368	2026-09-12 18:42	48.15	OK
3369	2026-09-12 18:43	49.98	OK	3370	2026-09-12 18:44	49.93	OK
3371	2026-09-12 18:45	49.83	OK	3372	2026-09-12 18:46	47.41	OK
3373	2026-09-12 18:47	50.13	OK	3374	2026-09-12 18:48	47.94	OK
3375	2026-09-12 18:49	48.66	OK	3376	2026-09-12 18:50	50.76	OK
3377	2026-09-12 18:51	48.17	OK	3378	2026-09-12 18:52	46.88	OK
3379	2026-09-12 18:53	48.77	OK	3380	2026-09-12 18:54	50.31	OK
3381	2026-09-12 18:55	50.25	OK	3382	2026-09-12 18:56	47.59	OK
3383	2026-09-12 18:57	48.62	OK	3384	2026-09-12 18:58	48.28	OK
3385	2026-09-12 18:59	48.63	OK	3386	2026-09-12 19:00	50.31	OK
3387	2026-09-12 19:01	47.87	OK	3388	2026-09-12 19:02	48.26	OK
3389	2026-09-12 19:03	47.45	OK	3390	2026-09-12 19:04	48.37	OK
3391	2026-09-12 19:05	50.27	OK	3392	2026-09-12 19:06	48.38	OK
3393	2026-09-12 19:07	47.27	OK	3394	2026-09-12 19:08	48.43	OK
3395	2026-09-12 19:09	50.66	OK	3396	2026-09-12 19:10	47.40	OK
3397	2026-09-12 19:11	49.32	OK	3398	2026-09-12 19:12	49.23	OK
3399	2026-09-12 19:13	47.56	OK	3400	2026-09-12 19:14	50.11	OK
3401	2026-09-12 19:15	49.21	OK	3402	2026-09-12 19:16	49.79	OK
3403	2026-09-12 19:17	48.82	OK	3404	2026-09-12 19:18	49.20	OK
3405	2026-09-12 19:19	48.09	OK	3406	2026-09-12 19:20	47.48	OK
3407	2026-09-12 19:21	46.32	OK	3408	2026-09-12 19:22	46.73	OK
3409	2026-09-12 19:23	48.03	OK	3410	2026-09-12 19:24	47.04	OK
3411	2026-09-12 19:25	48.20	OK	3412	2026-09-12 19:26	48.57	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3413	2026-09-12 19:27	48.06	OK	3414	2026-09-12 19:28	48.68	OK
3415	2026-09-12 19:29	46.32	OK	3416	2026-09-12 19:30	48.86	OK
3417	2026-09-12 19:31	50.02	OK	3418	2026-09-12 19:32	48.24	OK
3419	2026-09-12 19:33	48.70	OK	3420	2026-09-12 19:34	49.86	OK
3421	2026-09-12 19:35	50.34	OK	3422	2026-09-12 19:36	48.31	OK
3423	2026-09-12 19:37	46.80	OK	3424	2026-09-12 19:38	46.83	OK
3425	2026-09-12 19:39	48.19	OK	3426	2026-09-12 19:40	46.00	OK
3427	2026-09-12 19:41	46.98	OK	3428	2026-09-12 19:42	48.85	OK
3429	2026-09-12 19:43	46.70	OK	3430	2026-09-12 19:44	49.10	OK
3431	2026-09-12 19:45	47.68	OK	3432	2026-09-12 19:46	46.77	OK
3433	2026-09-12 19:47	47.46	OK	3434	2026-09-12 19:48	49.22	OK
3435	2026-09-12 19:49	47.84	OK	3436	2026-09-12 19:50	48.09	OK
3437	2026-09-12 19:51	45.73	OK	3438	2026-09-12 19:52	48.87	OK
3439	2026-09-12 19:53	49.89	OK	3440	2026-09-12 19:54	47.27	OK
3441	2026-09-12 19:55	49.24	OK	3442	2026-09-12 19:56	47.18	OK
3443	2026-09-12 19:57	48.03	OK	3444	2026-09-12 19:58	48.09	OK
3445	2026-09-12 19:59	47.46	OK	3446	2026-09-12 20:00	48.59	OK
3447	2026-09-12 20:01	48.46	OK	3448	2026-09-12 20:02	47.29	OK
3449	2026-09-12 20:03	45.54	OK	3450	2026-09-12 20:04	48.83	OK
3451	2026-09-12 20:05	46.27	OK	3452	2026-09-12 20:06	47.83	OK
3453	2026-09-12 20:07	47.86	OK	3454	2026-09-12 20:08	47.85	OK
3455	2026-09-12 20:09	48.26	OK	3456	2026-09-12 20:10	47.03	OK
3457	2026-09-12 20:11	49.00	OK	3458	2026-09-12 20:12	48.32	OK
3459	2026-09-12 20:13	49.64	OK	3460	2026-09-12 20:14	46.64	OK
3461	2026-09-12 20:15	48.85	OK	3462	2026-09-12 20:16	47.03	OK
3463	2026-09-12 20:17	48.15	OK	3464	2026-09-12 20:18	47.28	OK
3465	2026-09-12 20:19	47.51	OK	3466	2026-09-12 20:20	49.20	OK
3467	2026-09-12 20:21	47.50	OK	3468	2026-09-12 20:22	48.29	OK
3469	2026-09-12 20:23	48.90	OK	3470	2026-09-12 20:24	44.99	OK
3471	2026-09-12 20:25	45.53	OK	3472	2026-09-12 20:26	48.73	OK
3473	2026-09-12 20:27	46.65	OK	3474	2026-09-12 20:28	47.95	OK
3475	2026-09-12 20:29	46.91	OK	3476	2026-09-12 20:30	48.03	OK
3477	2026-09-12 20:31	47.15	OK	3478	2026-09-12 20:32	45.74	OK
3479	2026-09-12 20:33	48.12	OK	3480	2026-09-12 20:34	48.02	OK
3481	2026-09-12 20:35	47.96	OK	3482	2026-09-12 20:36	45.35	OK
3483	2026-09-12 20:37	46.57	OK	3484	2026-09-12 20:38	48.95	OK
3485	2026-09-12 20:39	46.87	OK	3486	2026-09-12 20:40	47.53	OK
3487	2026-09-12 20:41	48.81	OK	3488	2026-09-12 20:42	47.71	OK
3489	2026-09-12 20:43	48.74	OK	3490	2026-09-12 20:44	48.62	OK
3491	2026-09-12 20:45	46.73	OK	3492	2026-09-12 20:46	46.41	OK
3493	2026-09-12 20:47	47.35	OK	3494	2026-09-12 20:48	49.44	OK
3495	2026-09-12 20:49	48.27	OK	3496	2026-09-12 20:50	46.92	OK
3497	2026-09-12 20:51	47.70	OK	3498	2026-09-12 20:52	47.21	OK
3499	2026-09-12 20:53	46.90	OK	3500	2026-09-12 20:54	46.59	OK
3501	2026-09-12 20:55	47.71	OK	3502	2026-09-12 20:56	48.00	OK
3503	2026-09-12 20:57	47.20	OK	3504	2026-09-12 20:58	46.82	OK
3505	2026-09-12 20:59	46.74	OK	3506	2026-09-12 21:00	46.96	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3507	2026-09-12 21:01	47.98	OK	3508	2026-09-12 21:02	47.13	OK
3509	2026-09-12 21:03	48.12	OK	3510	2026-09-12 21:04	47.89	OK
3511	2026-09-12 21:05	47.94	OK	3512	2026-09-12 21:06	48.64	OK
3513	2026-09-12 21:07	46.63	OK	3514	2026-09-12 21:08	46.46	OK
3515	2026-09-12 21:09	47.00	OK	3516	2026-09-12 21:10	48.30	OK
3517	2026-09-12 21:11	46.12	OK	3518	2026-09-12 21:12	46.55	OK
3519	2026-09-12 21:13	46.20	OK	3520	2026-09-12 21:14	45.25	OK
3521	2026-09-12 21:15	47.28	OK	3522	2026-09-12 21:16	45.50	OK
3523	2026-09-12 21:17	47.16	OK	3524	2026-09-12 21:18	48.37	OK
3525	2026-09-12 21:19	46.98	OK	3526	2026-09-12 21:20	46.51	OK
3527	2026-09-12 21:21	46.52	OK	3528	2026-09-12 21:22	47.90	OK
3529	2026-09-12 21:23	46.45	OK	3530	2026-09-12 21:24	48.57	OK
3531	2026-09-12 21:25	46.31	OK	3532	2026-09-12 21:26	45.60	OK
3533	2026-09-12 21:27	45.40	OK	3534	2026-09-12 21:28	47.02	OK
3535	2026-09-12 21:29	46.31	OK	3536	2026-09-12 21:30	47.54	OK
3537	2026-09-12 21:31	47.10	OK	3538	2026-09-12 21:32	44.64	OK
3539	2026-09-12 21:33	47.02	OK	3540	2026-09-12 21:34	46.12	OK
3541	2026-09-12 21:35	46.54	OK	3542	2026-09-12 21:36	45.68	OK
3543	2026-09-12 21:37	47.72	OK	3544	2026-09-12 21:38	48.22	OK
3545	2026-09-12 21:39	47.77	OK	3546	2026-09-12 21:40	48.35	OK
3547	2026-09-12 21:41	46.72	OK	3548	2026-09-12 21:42	46.95	OK
3549	2026-09-12 21:43	46.24	OK	3550	2026-09-12 21:44	45.79	OK
3551	2026-09-12 21:45	46.13	OK	3552	2026-09-12 21:46	46.79	OK
3553	2026-09-12 21:47	47.50	OK	3554	2026-09-12 21:48	46.49	OK
3555	2026-09-12 21:49	45.96	OK	3556	2026-09-12 21:50	45.18	OK
3557	2026-09-12 21:51	45.96	OK	3558	2026-09-12 21:52	46.69	OK
3559	2026-09-12 21:53	45.30	OK	3560	2026-09-12 21:54	49.22	OK
3561	2026-09-12 21:55	47.67	OK	3562	2026-09-12 21:56	45.51	OK
3563	2026-09-12 21:57	46.73	OK	3564	2026-09-12 21:58	45.87	OK
3565	2026-09-12 21:59	47.13	OK	3566	2026-09-12 22:00	45.08	OK
3567	2026-09-12 22:01	45.92	OK	3568	2026-09-12 22:02	46.83	OK
3569	2026-09-12 22:03	48.40	OK	3570	2026-09-12 22:04	47.86	OK
3571	2026-09-12 22:05	45.53	OK	3572	2026-09-12 22:06	47.20	OK
3573	2026-09-12 22:07	45.89	OK	3574	2026-09-12 22:08	45.52	OK
3575	2026-09-12 22:09	45.20	OK	3576	2026-09-12 22:10	47.34	OK
3577	2026-09-12 22:11	47.40	OK	3578	2026-09-12 22:12	47.44	OK
3579	2026-09-12 22:13	46.95	OK	3580	2026-09-12 22:14	47.43	OK
3581	2026-09-12 22:15	47.30	OK	3582	2026-09-12 22:16	45.06	OK
3583	2026-09-12 22:17	44.46	OK	3584	2026-09-12 22:18	45.34	OK
3585	2026-09-12 22:19	48.62	OK	3586	2026-09-12 22:20	46.90	OK
3587	2026-09-12 22:21	45.62	OK	3588	2026-09-12 22:22	46.41	OK
3589	2026-09-12 22:23	44.76	OK	3590	2026-09-12 22:24	45.01	OK
3591	2026-09-12 22:25	46.56	OK	3592	2026-09-12 22:26	45.54	OK
3593	2026-09-12 22:27	46.53	OK	3594	2026-09-12 22:28	45.15	OK
3595	2026-09-12 22:29	44.70	OK	3596	2026-09-12 22:30	45.79	OK
3597	2026-09-12 22:31	47.58	OK	3598	2026-09-12 22:32	47.75	OK
3599	2026-09-12 22:33	47.17	OK	3600	2026-09-12 22:34	48.08	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3601	2026-09-12 22:35	47.14	OK	3602	2026-09-12 22:36	46.95	OK
3603	2026-09-12 22:37	47.81	OK	3604	2026-09-12 22:38	45.87	OK
3605	2026-09-12 22:39	45.73	OK	3606	2026-09-12 22:40	46.18	OK
3607	2026-09-12 22:41	46.90	OK	3608	2026-09-12 22:42	44.51	OK
3609	2026-09-12 22:43	44.43	OK	3610	2026-09-12 22:44	44.26	OK
3611	2026-09-12 22:45	46.73	OK	3612	2026-09-12 22:46	47.09	OK
3613	2026-09-12 22:47	45.41	OK	3614	2026-09-12 22:48	46.22	OK
3615	2026-09-12 22:49	46.05	OK	3616	2026-09-12 22:50	47.49	OK
3617	2026-09-12 22:51	46.44	OK	3618	2026-09-12 22:52	44.69	OK
3619	2026-09-12 22:53	47.53	OK	3620	2026-09-12 22:54	46.39	OK
3621	2026-09-12 22:55	45.99	OK	3622	2026-09-12 22:56	45.26	OK
3623	2026-09-12 22:57	44.43	OK	3624	2026-09-12 22:58	43.94	OK
3625	2026-09-12 22:59	44.82	OK	3626	2026-09-12 23:00	45.96	OK
3627	2026-09-12 23:01	45.50	OK	3628	2026-09-12 23:02	45.69	OK
3629	2026-09-12 23:03	45.53	OK	3630	2026-09-12 23:04	43.65	OK
3631	2026-09-12 23:05	47.69	OK	3632	2026-09-12 23:06	47.20	OK
3633	2026-09-12 23:07	44.35	OK	3634	2026-09-12 23:08	44.84	OK
3635	2026-09-12 23:09	46.15	OK	3636	2026-09-12 23:10	45.26	OK
3637	2026-09-12 23:11	44.77	OK	3638	2026-09-12 23:12	46.44	OK
3639	2026-09-12 23:13	45.93	OK	3640	2026-09-12 23:14	46.89	OK
3641	2026-09-12 23:15	44.84	OK	3642	2026-09-12 23:16	46.43	OK
3643	2026-09-12 23:17	44.90	OK	3644	2026-09-12 23:18	44.61	OK
3645	2026-09-12 23:19	45.62	OK	3646	2026-09-12 23:20	46.21	OK
3647	2026-09-12 23:21	44.43	OK	3648	2026-09-12 23:22	45.98	OK
3649	2026-09-12 23:23	46.72	OK	3650	2026-09-12 23:24	43.22	OK
3651	2026-09-12 23:25	47.08	OK	3652	2026-09-12 23:26	44.40	OK
3653	2026-09-12 23:27	45.08	OK	3654	2026-09-12 23:28	44.17	OK
3655	2026-09-12 23:29	45.97	OK	3656	2026-09-12 23:30	46.72	OK
3657	2026-09-12 23:31	46.23	OK	3658	2026-09-12 23:32	47.69	OK
3659	2026-09-12 23:33	45.62	OK	3660	2026-09-12 23:34	44.78	OK
3661	2026-09-12 23:35	45.67	OK	3662	2026-09-12 23:36	45.55	OK
3663	2026-09-12 23:37	45.91	OK	3664	2026-09-12 23:38	45.47	OK
3665	2026-09-12 23:39	44.18	OK	3666	2026-09-12 23:40	45.94	OK
3667	2026-09-12 23:41	44.39	OK	3668	2026-09-12 23:42	44.50	OK
3669	2026-09-12 23:43	46.30	OK	3670	2026-09-12 23:44	44.53	OK
3671	2026-09-12 23:45	47.13	OK	3672	2026-09-12 23:46	44.63	OK
3673	2026-09-12 23:47	45.86	OK	3674	2026-09-12 23:48	45.20	OK
3675	2026-09-12 23:49	46.19	OK	3676	2026-09-12 23:50	44.26	OK
3677	2026-09-12 23:51	46.37	OK	3678	2026-09-12 23:52	45.16	OK
3679	2026-09-12 23:53	47.12	OK	3680	2026-09-12 23:54	45.67	OK
3681	2026-09-12 23:55	45.01	OK	3682	2026-09-12 23:56	44.56	OK
3683	2026-09-12 23:57	44.90	OK	3684	2026-09-12 23:58	45.07	OK
3685	2026-09-12 23:59	46.18	OK	3686	2026-09-13 00:00	44.43	OK
3687	2026-09-13 00:01	45.94	OK	3688	2026-09-13 00:02	45.79	OK
3689	2026-09-13 00:03	44.17	OK	3690	2026-09-13 00:04	44.45	OK
3691	2026-09-13 00:05	44.78	OK	3692	2026-09-13 00:06	43.31	OK
3693	2026-09-13 00:07	45.31	OK	3694	2026-09-13 00:08	45.58	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3695	2026-09-13 00:09	46.39	OK	3696	2026-09-13 00:10	44.13	OK
3697	2026-09-13 00:11	44.79	OK	3698	2026-09-13 00:12	44.35	OK
3699	2026-09-13 00:13	44.63	OK	3700	2026-09-13 00:14	45.28	OK
3701	2026-09-13 00:15	47.15	OK	3702	2026-09-13 00:16	44.01	OK
3703	2026-09-13 00:17	45.80	OK	3704	2026-09-13 00:18	45.37	OK
3705	2026-09-13 00:19	44.81	OK	3706	2026-09-13 00:20	44.82	OK
3707	2026-09-13 00:21	45.00	OK	3708	2026-09-13 00:22	45.72	OK
3709	2026-09-13 00:23	45.41	OK	3710	2026-09-13 00:24	46.89	OK
3711	2026-09-13 00:25	44.81	OK	3712	2026-09-13 00:26	44.11	OK
3713	2026-09-13 00:27	44.45	OK	3714	2026-09-13 00:28	44.87	OK
3715	2026-09-13 00:29	44.94	OK	3716	2026-09-13 00:30	45.09	OK
3717	2026-09-13 00:31	43.85	OK	3718	2026-09-13 00:32	45.50	OK
3719	2026-09-13 00:33	46.11	OK	3720	2026-09-13 00:34	45.14	OK
3721	2026-09-13 00:35	45.63	OK	3722	2026-09-13 00:36	44.52	OK
3723	2026-09-13 00:37	46.05	OK	3724	2026-09-13 00:38	44.69	OK
3725	2026-09-13 00:39	45.17	OK	3726	2026-09-13 00:40	45.16	OK
3727	2026-09-13 00:41	46.67	OK	3728	2026-09-13 00:42	45.09	OK
3729	2026-09-13 00:43	43.26	OK	3730	2026-09-13 00:44	45.63	OK
3731	2026-09-13 00:45	45.09	OK	3732	2026-09-13 00:46	44.77	OK
3733	2026-09-13 00:47	46.22	OK	3734	2026-09-13 00:48	46.79	OK
3735	2026-09-13 00:49	46.35	OK	3736	2026-09-13 00:50	45.63	OK
3737	2026-09-13 00:51	45.55	OK	3738	2026-09-13 00:52	46.15	OK
3739	2026-09-13 00:53	44.96	OK	3740	2026-09-13 00:54	45.48	OK
3741	2026-09-13 00:55	43.94	OK	3742	2026-09-13 00:56	45.49	OK
3743	2026-09-13 00:57	46.78	OK	3744	2026-09-13 00:58	46.38	OK
3745	2026-09-13 00:59	45.52	OK	3746	2026-09-13 01:00	43.54	OK
3747	2026-09-13 01:01	46.47	OK	3748	2026-09-13 01:02	45.32	OK
3749	2026-09-13 01:03	45.92	OK	3750	2026-09-13 01:04	45.64	OK
3751	2026-09-13 01:05	45.04	OK	3752	2026-09-13 01:06	46.67	OK
3753	2026-09-13 01:07	47.10	OK	3754	2026-09-13 01:08	45.89	OK
3755	2026-09-13 01:09	45.41	OK	3756	2026-09-13 01:10	45.55	OK
3757	2026-09-13 01:11	47.00	OK	3758	2026-09-13 01:12	44.67	OK
3759	2026-09-13 01:13	44.76	OK	3760	2026-09-13 01:14	45.33	OK
3761	2026-09-13 01:15	45.47	OK	3762	2026-09-13 01:16	44.30	OK
3763	2026-09-13 01:17	44.54	OK	3764	2026-09-13 01:18	46.52	OK
3765	2026-09-13 01:19	44.43	OK	3766	2026-09-13 01:20	44.92	OK
3767	2026-09-13 01:21	44.31	OK	3768	2026-09-13 01:22	46.27	OK
3769	2026-09-13 01:23	44.74	OK	3770	2026-09-13 01:24	45.64	OK
3771	2026-09-13 01:25	43.30	OK	3772	2026-09-13 01:26	46.74	OK
3773	2026-09-13 01:27	45.42	OK	3774	2026-09-13 01:28	44.37	OK
3775	2026-09-13 01:29	44.91	OK	3776	2026-09-13 01:30	43.45	OK
3777	2026-09-13 01:31	44.69	OK	3778	2026-09-13 01:32	44.11	OK
3779	2026-09-13 01:33	45.51	OK	3780	2026-09-13 01:34	46.47	OK
3781	2026-09-13 01:35	46.19	OK	3782	2026-09-13 01:36	43.54	OK
3783	2026-09-13 01:37	45.51	OK	3784	2026-09-13 01:38	43.78	OK
3785	2026-09-13 01:39	46.00	OK	3786	2026-09-13 01:40	44.77	OK
3787	2026-09-13 01:41	43.56	OK	3788	2026-09-13 01:42	44.39	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3789	2026-09-13 01:43	43.51	OK	3790	2026-09-13 01:44	46.05	OK
3791	2026-09-13 01:45	46.55	OK	3792	2026-09-13 01:46	44.56	OK
3793	2026-09-13 01:47	46.65	OK	3794	2026-09-13 01:48	45.80	OK
3795	2026-09-13 01:49	44.53	OK	3796	2026-09-13 01:50	44.59	OK
3797	2026-09-13 01:51	45.23	OK	3798	2026-09-13 01:52	46.27	OK
3799	2026-09-13 01:53	45.31	OK	3800	2026-09-13 01:54	44.92	OK
3801	2026-09-13 01:55	44.84	OK	3802	2026-09-13 01:56	45.46	OK
3803	2026-09-13 01:57	43.57	OK	3804	2026-09-13 01:58	46.98	OK
3805	2026-09-13 01:59	45.23	OK	3806	2026-09-13 02:00	43.92	OK
3807	2026-09-13 02:01	43.95	OK	3808	2026-09-13 02:02	45.45	OK
3809	2026-09-13 02:03	45.74	OK	3810	2026-09-13 02:04	44.20	OK
3811	2026-09-13 02:05	45.45	OK	3812	2026-09-13 02:06	45.90	OK
3813	2026-09-13 02:07	45.93	OK	3814	2026-09-13 02:08	45.49	OK
3815	2026-09-13 02:09	45.65	OK	3816	2026-09-13 02:10	45.09	OK
3817	2026-09-13 02:11	46.15	OK	3818	2026-09-13 02:12	46.34	OK
3819	2026-09-13 02:13	46.25	OK	3820	2026-09-13 02:14	47.19	OK
3821	2026-09-13 02:15	46.29	OK	3822	2026-09-13 02:16	44.08	OK
3823	2026-09-13 02:17	45.94	OK	3824	2026-09-13 02:18	44.63	OK
3825	2026-09-13 02:19	47.79	OK	3826	2026-09-13 02:20	46.90	OK
3827	2026-09-13 02:21	45.56	OK	3828	2026-09-13 02:22	46.55	OK
3829	2026-09-13 02:23	43.48	OK	3830	2026-09-13 02:24	44.74	OK
3831	2026-09-13 02:25	46.20	OK	3832	2026-09-13 02:26	45.33	OK
3833	2026-09-13 02:27	45.20	OK	3834	2026-09-13 02:28	44.96	OK
3835	2026-09-13 02:29	46.12	OK	3836	2026-09-13 02:30	44.46	OK
3837	2026-09-13 02:31	42.84	OK	3838	2026-09-13 02:32	45.38	OK
3839	2026-09-13 02:33	45.89	OK	3840	2026-09-13 02:34	47.23	OK
3841	2026-09-13 02:35	45.98	OK	3842	2026-09-13 02:36	44.54	OK
3843	2026-09-13 02:37	46.80	OK	3844	2026-09-13 02:38	46.44	OK
3845	2026-09-13 02:39	44.55	OK	3846	2026-09-13 02:40	46.21	OK
3847	2026-09-13 02:41	45.26	OK	3848	2026-09-13 02:42	44.67	OK
3849	2026-09-13 02:43	46.34	OK	3850	2026-09-13 02:44	46.31	OK
3851	2026-09-13 02:45	45.19	OK	3852	2026-09-13 02:46	44.91	OK
3853	2026-09-13 02:47	44.85	OK	3854	2026-09-13 02:48	44.54	OK
3855	2026-09-13 02:49	46.13	OK	3856	2026-09-13 02:50	46.08	OK
3857	2026-09-13 02:51	44.66	OK	3858	2026-09-13 02:52	45.69	OK
3859	2026-09-13 02:53	44.85	OK	3860	2026-09-13 02:54	47.25	OK
3861	2026-09-13 02:55	46.13	OK	3862	2026-09-13 02:56	45.37	OK
3863	2026-09-13 02:57	44.88	OK	3864	2026-09-13 02:58	47.03	OK
3865	2026-09-13 02:59	45.74	OK	3866	2026-09-13 03:00	44.84	OK
3867	2026-09-13 03:01	45.93	OK	3868	2026-09-13 03:02	44.65	OK
3869	2026-09-13 03:03	44.67	OK	3870	2026-09-13 03:04	43.97	OK
3871	2026-09-13 03:05	43.84	OK	3872	2026-09-13 03:06	45.25	OK
3873	2026-09-13 03:07	46.06	OK	3874	2026-09-13 03:08	46.43	OK
3875	2026-09-13 03:09	45.66	OK	3876	2026-09-13 03:10	45.30	OK
3877	2026-09-13 03:11	45.04	OK	3878	2026-09-13 03:12	46.30	OK
3879	2026-09-13 03:13	46.65	OK	3880	2026-09-13 03:14	44.52	OK
3881	2026-09-13 03:15	47.24	OK	3882	2026-09-13 03:16	45.83	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3883	2026-09-13 03:17	46.20	OK	3884	2026-09-13 03:18	46.81	OK
3885	2026-09-13 03:19	47.67	OK	3886	2026-09-13 03:20	44.33	OK
3887	2026-09-13 03:21	43.59	OK	3888	2026-09-13 03:22	45.18	OK
3889	2026-09-13 03:23	43.62	OK	3890	2026-09-13 03:24	46.93	OK
3891	2026-09-13 03:25	45.62	OK	3892	2026-09-13 03:26	46.07	OK
3893	2026-09-13 03:27	45.65	OK	3894	2026-09-13 03:28	46.17	OK
3895	2026-09-13 03:29	45.37	OK	3896	2026-09-13 03:30	45.04	OK
3897	2026-09-13 03:31	44.91	OK	3898	2026-09-13 03:32	44.41	OK
3899	2026-09-13 03:33	45.79	OK	3900	2026-09-13 03:34	44.03	OK
3901	2026-09-13 03:35	43.96	OK	3902	2026-09-13 03:36	45.88	OK
3903	2026-09-13 03:37	43.95	OK	3904	2026-09-13 03:38	45.26	OK
3905	2026-09-13 03:39	46.61	OK	3906	2026-09-13 03:40	46.81	OK
3907	2026-09-13 03:41	45.55	OK	3908	2026-09-13 03:42	44.12	OK
3909	2026-09-13 03:43	44.02	OK	3910	2026-09-13 03:44	44.92	OK
3911	2026-09-13 03:45	46.93	OK	3912	2026-09-13 03:46	45.18	OK
3913	2026-09-13 03:47	46.42	OK	3914	2026-09-13 03:48	46.65	OK
3915	2026-09-13 03:49	45.96	OK	3916	2026-09-13 03:50	44.31	OK
3917	2026-09-13 03:51	45.18	OK	3918	2026-09-13 03:52	45.57	OK
3919	2026-09-13 03:53	44.54	OK	3920	2026-09-13 03:54	46.02	OK
3921	2026-09-13 03:55	44.98	OK	3922	2026-09-13 03:56	45.32	OK
3923	2026-09-13 03:57	45.32	OK	3924	2026-09-13 03:58	45.54	OK
3925	2026-09-13 03:59	47.78	OK	3926	2026-09-13 04:00	46.18	OK
3927	2026-09-13 04:01	46.75	OK	3928	2026-09-13 04:02	43.71	OK
3929	2026-09-13 04:03	47.30	OK	3930	2026-09-13 04:04	44.64	OK
3931	2026-09-13 04:05	44.64	OK	3932	2026-09-13 04:06	46.01	OK
3933	2026-09-13 04:07	45.93	OK	3934	2026-09-13 04:08	46.67	OK
3935	2026-09-13 04:09	47.24	OK	3936	2026-09-13 04:10	44.97	OK
3937	2026-09-13 04:11	46.10	OK	3938	2026-09-13 04:12	47.00	OK
3939	2026-09-13 04:13	44.42	OK	3940	2026-09-13 04:14	48.23	OK
3941	2026-09-13 04:15	45.58	OK	3942	2026-09-13 04:16	47.08	OK
3943	2026-09-13 04:17	45.46	OK	3944	2026-09-13 04:18	46.69	OK
3945	2026-09-13 04:19	45.85	OK	3946	2026-09-13 04:20	45.31	OK
3947	2026-09-13 04:21	46.40	OK	3948	2026-09-13 04:22	46.00	OK
3949	2026-09-13 04:23	46.75	OK	3950	2026-09-13 04:24	47.16	OK
3951	2026-09-13 04:25	46.76	OK	3952	2026-09-13 04:26	43.98	OK
3953	2026-09-13 04:27	45.11	OK	3954	2026-09-13 04:28	46.54	OK
3955	2026-09-13 04:29	45.94	OK	3956	2026-09-13 04:30	46.31	OK
3957	2026-09-13 04:31	47.18	OK	3958	2026-09-13 04:32	46.44	OK
3959	2026-09-13 04:33	46.33	OK	3960	2026-09-13 04:34	45.01	OK
3961	2026-09-13 04:35	46.73	OK	3962	2026-09-13 04:36	45.70	OK
3963	2026-09-13 04:37	46.62	OK	3964	2026-09-13 04:38	46.56	OK
3965	2026-09-13 04:39	45.50	OK	3966	2026-09-13 04:40	46.56	OK
3967	2026-09-13 04:41	45.77	OK	3968	2026-09-13 04:42	46.79	OK
3969	2026-09-13 04:43	47.14	OK	3970	2026-09-13 04:44	44.18	OK
3971	2026-09-13 04:45	45.11	OK	3972	2026-09-13 04:46	46.47	OK
3973	2026-09-13 04:47	46.79	OK	3974	2026-09-13 04:48	47.53	OK
3975	2026-09-13 04:49	48.29	OK	3976	2026-09-13 04:50	45.83	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3977	2026-09-13 04:51	45.97	OK	3978	2026-09-13 04:52	47.92	OK
3979	2026-09-13 04:53	44.97	OK	3980	2026-09-13 04:54	47.14	OK
3981	2026-09-13 04:55	46.55	OK	3982	2026-09-13 04:56	46.16	OK
3983	2026-09-13 04:57	47.31	OK	3984	2026-09-13 04:58	45.84	OK
3985	2026-09-13 04:59	46.13	OK	3986	2026-09-13 05:00	48.85	OK
3987	2026-09-13 05:01	48.16	OK	3988	2026-09-13 05:02	45.48	OK
3989	2026-09-13 05:03	48.68	OK	3990	2026-09-13 05:04	46.64	OK
3991	2026-09-13 05:05	46.03	OK	3992	2026-09-13 05:06	45.95	OK
3993	2026-09-13 05:07	47.00	OK	3994	2026-09-13 05:08	46.86	OK
3995	2026-09-13 05:09	45.05	OK	3996	2026-09-13 05:10	46.49	OK
3997	2026-09-13 05:11	45.82	OK	3998	2026-09-13 05:12	47.07	OK
3999	2026-09-13 05:13	46.67	OK	4000	2026-09-13 05:14	45.24	OK
4001	2026-09-13 05:15	46.50	OK	4002	2026-09-13 05:16	46.11	OK
4003	2026-09-13 05:17	46.61	OK	4004	2026-09-13 05:18	46.22	OK
4005	2026-09-13 05:19	46.24	OK	4006	2026-09-13 05:20	48.28	OK
4007	2026-09-13 05:21	47.11	OK	4008	2026-09-13 05:22	46.88	OK
4009	2026-09-13 05:23	47.40	OK	4010	2026-09-13 05:24	45.38	OK
4011	2026-09-13 05:25	47.12	OK	4012	2026-09-13 05:26	46.74	OK
4013	2026-09-13 05:27	47.09	OK	4014	2026-09-13 05:28	47.48	OK
4015	2026-09-13 05:29	46.51	OK	4016	2026-09-13 05:30	45.26	OK
4017	2026-09-13 05:31	46.50	OK	4018	2026-09-13 05:32	48.86	OK
4019	2026-09-13 05:33	47.27	OK	4020	2026-09-13 05:34	48.06	OK
4021	2026-09-13 05:35	46.93	OK	4022	2026-09-13 05:36	46.22	OK
4023	2026-09-13 05:37	47.21	OK	4024	2026-09-13 05:38	44.72	OK
4025	2026-09-13 05:39	46.68	OK	4026	2026-09-13 05:40	46.28	OK
4027	2026-09-13 05:41	46.37	OK	4028	2026-09-13 05:42	45.95	OK
4029	2026-09-13 05:43	46.41	OK	4030	2026-09-13 05:44	47.59	OK
4031	2026-09-13 05:45	46.75	OK	4032	2026-09-13 05:46	48.26	OK
4033	2026-09-13 05:47	46.85	OK	4034	2026-09-13 05:48	48.88	OK
4035	2026-09-13 05:49	44.82	OK	4036	2026-09-13 05:50	47.22	OK
4037	2026-09-13 05:51	47.90	OK	4038	2026-09-13 05:52	47.67	OK
4039	2026-09-13 05:53	46.65	OK	4040	2026-09-13 05:54	46.16	OK
4041	2026-09-13 05:55	48.01	OK	4042	2026-09-13 05:56	48.07	OK
4043	2026-09-13 05:57	46.44	OK	4044	2026-09-13 05:58	45.14	OK
4045	2026-09-13 05:59	48.55	OK	4046	2026-09-13 06:00	48.35	OK
4047	2026-09-13 06:01	45.81	OK	4048	2026-09-13 06:02	48.17	OK
4049	2026-09-13 06:03	47.69	OK	4050	2026-09-13 06:04	47.80	OK
4051	2026-09-13 06:05	47.66	OK	4052	2026-09-13 06:06	46.80	OK
4053	2026-09-13 06:07	47.04	OK	4054	2026-09-13 06:08	45.12	OK
4055	2026-09-13 06:09	47.28	OK	4056	2026-09-13 06:10	48.79	OK
4057	2026-09-13 06:11	48.31	OK	4058	2026-09-13 06:12	46.78	OK
4059	2026-09-13 06:13	47.44	OK	4060	2026-09-13 06:14	47.16	OK
4061	2026-09-13 06:15	47.31	OK	4062	2026-09-13 06:16	45.04	OK
4063	2026-09-13 06:17	47.47	OK	4064	2026-09-13 06:18	48.00	OK
4065	2026-09-13 06:19	47.82	OK	4066	2026-09-13 06:20	47.82	OK
4067	2026-09-13 06:21	45.95	OK	4068	2026-09-13 06:22	48.23	OK
4069	2026-09-13 06:23	50.42	OK	4070	2026-09-13 06:24	47.57	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4071	2026-09-13 06:25	49.14	OK	4072	2026-09-13 06:26	48.35	OK
4073	2026-09-13 06:27	46.63	OK	4074	2026-09-13 06:28	46.55	OK
4075	2026-09-13 06:29	46.69	OK	4076	2026-09-13 06:30	45.35	OK
4077	2026-09-13 06:31	46.24	OK	4078	2026-09-13 06:32	48.69	OK
4079	2026-09-13 06:33	48.98	OK	4080	2026-09-13 06:34	47.96	OK
4081	2026-09-13 06:35	45.56	OK	4082	2026-09-13 06:36	47.11	OK
4083	2026-09-13 06:37	50.05	OK	4084	2026-09-13 06:38	48.03	OK
4085	2026-09-13 06:39	50.09	OK	4086	2026-09-13 06:40	47.81	OK
4087	2026-09-13 06:41	47.93	OK	4088	2026-09-13 06:42	47.00	OK
4089	2026-09-13 06:43	48.61	OK	4090	2026-09-13 06:44	47.69	OK
4091	2026-09-13 06:45	49.90	OK	4092	2026-09-13 06:46	47.64	OK
4093	2026-09-13 06:47	46.82	OK	4094	2026-09-13 06:48	47.11	OK
4095	2026-09-13 06:49	46.48	OK	4096	2026-09-13 06:50	47.99	OK
4097	2026-09-13 06:51	46.86	OK	4098	2026-09-13 06:52	49.81	OK
4099	2026-09-13 06:53	46.78	OK	4100	2026-09-13 06:54	47.17	OK
4101	2026-09-13 06:55	48.80	OK	4102	2026-09-13 06:56	48.10	OK
4103	2026-09-13 06:57	46.89	OK	4104	2026-09-13 06:58	47.46	OK
4105	2026-09-13 06:59	47.94	OK	4106	2026-09-13 07:00	49.22	OK
4107	2026-09-13 07:01	48.78	OK	4108	2026-09-13 07:02	48.52	OK
4109	2026-09-13 07:03	47.66	OK	4110	2026-09-13 07:04	49.44	OK
4111	2026-09-13 07:05	48.01	OK	4112	2026-09-13 07:06	48.44	OK
4113	2026-09-13 07:07	47.36	OK	4114	2026-09-13 07:08	50.09	OK
4115	2026-09-13 07:09	48.47	OK	4116	2026-09-13 07:10	47.51	OK
4117	2026-09-13 07:11	47.95	OK	4118	2026-09-13 07:12	47.72	OK
4119	2026-09-13 07:13	49.16	OK	4120	2026-09-13 07:14	48.56	OK
4121	2026-09-13 07:15	48.50	OK	4122	2026-09-13 07:16	47.20	OK
4123	2026-09-13 07:17	48.71	OK	4124	2026-09-13 07:18	48.93	OK
4125	2026-09-13 07:19	49.18	OK	4126	2026-09-13 07:20	49.77	OK
4127	2026-09-13 07:21	49.00	OK	4128	2026-09-13 07:22	48.90	OK
4129	2026-09-13 07:23	48.06	OK	4130	2026-09-13 07:24	46.27	OK
4131	2026-09-13 07:25	49.96	OK	4132	2026-09-13 07:26	48.25	OK
4133	2026-09-13 07:27	48.42	OK	4134	2026-09-13 07:28	48.50	OK
4135	2026-09-13 07:29	49.57	OK	4136	2026-09-13 07:30	48.60	OK
4137	2026-09-13 07:31	51.12	OK	4138	2026-09-13 07:32	49.58	OK
4139	2026-09-13 07:33	48.48	OK	4140	2026-09-13 07:34	47.12	OK
4141	2026-09-13 07:35	49.63	OK	4142	2026-09-13 07:36	48.38	OK
4143	2026-09-13 07:37	49.90	OK	4144	2026-09-13 07:38	48.75	OK
4145	2026-09-13 07:39	48.09	OK	4146	2026-09-13 07:40	49.41	OK
4147	2026-09-13 07:41	49.71	OK	4148	2026-09-13 07:42	49.92	OK
4149	2026-09-13 07:43	48.15	OK	4150	2026-09-13 07:44	49.88	OK
4151	2026-09-13 07:45	48.03	OK	4152	2026-09-13 07:46	49.72	OK
4153	2026-09-13 07:47	49.72	OK	4154	2026-09-13 07:48	48.73	OK
4155	2026-09-13 07:49	47.91	OK	4156	2026-09-13 07:50	48.53	OK
4157	2026-09-13 07:51	47.97	OK	4158	2026-09-13 07:52	50.32	OK
4159	2026-09-13 07:53	48.28	OK	4160	2026-09-13 07:54	49.04	OK
4161	2026-09-13 07:55	48.98	OK	4162	2026-09-13 07:56	48.33	OK
4163	2026-09-13 07:57	48.25	OK	4164	2026-09-13 07:58	49.90	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4165	2026-09-13 07:59	49.93	OK	4166	2026-09-13 08:00	50.36	OK
4167	2026-09-13 08:01	51.07	OK	4168	2026-09-13 08:02	49.67	OK
4169	2026-09-13 08:03	48.91	OK	4170	2026-09-13 08:04	51.00	OK
4171	2026-09-13 08:05	50.01	OK	4172	2026-09-13 08:06	48.00	OK
4173	2026-09-13 08:07	48.56	OK	4174	2026-09-13 08:08	48.47	OK
4175	2026-09-13 08:09	49.74	OK	4176	2026-09-13 08:10	49.29	OK
4177	2026-09-13 08:11	47.46	OK	4178	2026-09-13 08:12	48.27	OK
4179	2026-09-13 08:13	48.50	OK	4180	2026-09-13 08:14	47.93	OK
4181	2026-09-13 08:15	48.76	OK	4182	2026-09-13 08:16	48.64	OK
4183	2026-09-13 08:17	47.47	OK	4184	2026-09-13 08:18	49.69	OK
4185	2026-09-13 08:19	47.50	OK	4186	2026-09-13 08:20	47.89	OK
4187	2026-09-13 08:21	48.62	OK	4188	2026-09-13 08:22	49.01	OK
4189	2026-09-13 08:23	49.22	OK	4190	2026-09-13 08:24	49.63	OK
4191	2026-09-13 08:25	48.75	OK	4192	2026-09-13 08:26	50.66	OK
4193	2026-09-13 08:27	48.90	OK	4194	2026-09-13 08:28	49.53	OK
4195	2026-09-13 08:29	48.55	OK	4196	2026-09-13 08:30	50.29	OK
4197	2026-09-13 08:31	48.90	OK	4198	2026-09-13 08:32	50.54	OK
4199	2026-09-13 08:33	49.75	OK	4200	2026-09-13 08:34	49.51	OK
4201	2026-09-13 08:35	47.41	OK	4202	2026-09-13 08:36	49.47	OK
4203	2026-09-13 08:37	50.25	OK	4204	2026-09-13 08:38	49.08	OK
4205	2026-09-13 08:39	50.69	OK	4206	2026-09-13 08:40	51.70	OK
4207	2026-09-13 08:41	49.53	OK	4208	2026-09-13 08:42	48.34	OK
4209	2026-09-13 08:43	50.39	OK	4210	2026-09-13 08:44	50.20	OK
4211	2026-09-13 08:45	51.79	OK	4212	2026-09-13 08:46	50.44	OK
4213	2026-09-13 08:47	48.02	OK	4214	2026-09-13 08:48	49.97	OK
4215	2026-09-13 08:49	47.48	OK	4216	2026-09-13 08:50	51.13	OK
4217	2026-09-13 08:51	48.54	OK	4218	2026-09-13 08:52	50.34	OK
4219	2026-09-13 08:53	49.34	OK	4220	2026-09-13 08:54	48.35	OK
4221	2026-09-13 08:55	50.32	OK	4222	2026-09-13 08:56	50.85	OK
4223	2026-09-13 08:57	49.31	OK	4224	2026-09-13 08:58	49.86	OK
4225	2026-09-13 08:59	49.54	OK	4226	2026-09-13 09:00	49.23	OK
4227	2026-09-13 09:01	51.35	OK	4228	2026-09-13 09:02	48.60	OK
4229	2026-09-13 09:03	49.30	OK	4230	2026-09-13 09:04	49.69	OK
4231	2026-09-13 09:05	49.18	OK	4232	2026-09-13 09:06	49.26	OK
4233	2026-09-13 09:07	49.39	OK	4234	2026-09-13 09:08	50.78	OK
4235	2026-09-13 09:09	49.78	OK	4236	2026-09-13 09:10	48.50	OK
4237	2026-09-13 09:11	52.13	OK	4238	2026-09-13 09:12	49.53	OK
4239	2026-09-13 09:13	51.57	OK	4240	2026-09-13 09:14	49.80	OK
4241	2026-09-13 09:15	49.91	OK	4242	2026-09-13 09:16	49.25	OK
4243	2026-09-13 09:17	50.16	OK	4244	2026-09-13 09:18	51.33	OK
4245	2026-09-13 09:19	50.29	OK	4246	2026-09-13 09:20	49.71	OK
4247	2026-09-13 09:21	49.38	OK	4248	2026-09-13 09:22	51.15	OK
4249	2026-09-13 09:23	48.87	OK	4250	2026-09-13 09:24	50.79	OK
4251	2026-09-13 09:25	49.57	OK	4252	2026-09-13 09:26	50.07	OK
4253	2026-09-13 09:27	50.20	OK	4254	2026-09-13 09:28	52.18	OK
4255	2026-09-13 09:29	50.22	OK	4256	2026-09-13 09:30	51.30	OK
4257	2026-09-13 09:31	51.33	OK	4258	2026-09-13 09:32	50.54	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4259	2026-09-13 09:33	51.40	OK	4260	2026-09-13 09:34	52.20	OK
4261	2026-09-13 09:35	50.98	OK	4262	2026-09-13 09:36	49.39	OK
4263	2026-09-13 09:37	52.09	OK	4264	2026-09-13 09:38	51.08	OK
4265	2026-09-13 09:39	50.06	OK	4266	2026-09-13 09:40	48.99	OK
4267	2026-09-13 09:41	49.98	OK	4268	2026-09-13 09:42	52.66	OK
4269	2026-09-13 09:43	48.51	OK	4270	2026-09-13 09:44	52.11	OK
4271	2026-09-13 09:45	48.70	OK	4272	2026-09-13 09:46	50.12	OK
4273	2026-09-13 09:47	51.42	OK	4274	2026-09-13 09:48	50.33	OK
4275	2026-09-13 09:49	51.18	OK	4276	2026-09-13 09:50	52.10	OK
4277	2026-09-13 09:51	50.98	OK	4278	2026-09-13 09:52	50.11	OK
4279	2026-09-13 09:53	50.72	OK	4280	2026-09-13 09:54	51.44	OK
4281	2026-09-13 09:55	49.67	OK	4282	2026-09-13 09:56	51.99	OK
4283	2026-09-13 09:57	50.17	OK	4284	2026-09-13 09:58	49.65	OK
4285	2026-09-13 09:59	50.89	OK	4286	2026-09-13 10:00	50.34	OK
4287	2026-09-13 10:01	51.68	OK	4288	2026-09-13 10:02	52.14	OK
4289	2026-09-13 10:03	50.66	OK	4290	2026-09-13 10:04	49.83	OK
4291	2026-09-13 10:05	50.79	OK	4292	2026-09-13 10:06	50.98	OK
4293	2026-09-13 10:07	52.25	OK	4294	2026-09-13 10:08	53.16	OK
4295	2026-09-13 10:09	51.66	OK	4296	2026-09-13 10:10	51.04	OK
4297	2026-09-13 10:11	53.25	OK	4298	2026-09-13 10:12	51.53	OK
4299	2026-09-13 10:13	52.71	OK	4300	2026-09-13 10:14	50.23	OK
4301	2026-09-13 10:15	51.21	OK	4302	2026-09-13 10:16	50.31	OK
4303	2026-09-13 10:17	51.36	OK	4304	2026-09-13 10:18	51.83	OK
4305	2026-09-13 10:19	51.11	OK	4306	2026-09-13 10:20	50.33	OK
4307	2026-09-13 10:21	49.89	OK	4308	2026-09-13 10:22	51.47	OK
4309	2026-09-13 10:23	50.10	OK	4310	2026-09-13 10:24	49.64	OK
4311	2026-09-13 10:25	51.45	OK	4312	2026-09-13 10:26	50.64	OK
4313	2026-09-13 10:27	53.14	OK	4314	2026-09-13 10:28	50.70	OK
4315	2026-09-13 10:29	50.26	OK	4316	2026-09-13 10:30	50.87	OK
4317	2026-09-13 10:31	51.35	OK	4318	2026-09-13 10:32	51.63	OK
4319	2026-09-13 10:33	48.75	OK	4320	2026-09-13 10:34	50.30	OK
4321	2026-09-13 10:35	52.48	OK	4322	2026-09-13 10:36	51.31	OK
4323	2026-09-13 10:37	52.41	OK	4324	2026-09-13 10:38	50.71	OK
4325	2026-09-13 10:39	48.89	OK	4326	2026-09-13 10:40	51.48	OK
4327	2026-09-13 10:41	51.07	OK	4328	2026-09-13 10:42	50.55	OK
4329	2026-09-13 10:43	50.96	OK	4330	2026-09-13 10:44	49.70	OK
4331	2026-09-13 10:45	51.44	OK	4332	2026-09-13 10:46	51.60	OK
4333	2026-09-13 10:47	49.82	OK	4334	2026-09-13 10:48	51.03	OK
4335	2026-09-13 10:49	51.97	OK	4336	2026-09-13 10:50	50.79	OK
4337	2026-09-13 10:51	51.19	OK	4338	2026-09-13 10:52	52.85	OK
4339	2026-09-13 10:53	50.40	OK	4340	2026-09-13 10:54	51.79	OK
4341	2026-09-13 10:55	50.78	OK	4342	2026-09-13 10:56	53.41	OK
4343	2026-09-13 10:57	50.93	OK	4344	2026-09-13 10:58	51.18	OK
4345	2026-09-13 10:59	51.92	OK	4346	2026-09-13 11:00	51.46	OK
4347	2026-09-13 11:01	53.61	OK	4348	2026-09-13 11:02	51.26	OK
4349	2026-09-13 11:03	51.14	OK	4350	2026-09-13 11:04	51.38	OK
4351	2026-09-13 11:05	51.42	OK	4352	2026-09-13 11:06	50.16	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4353	2026-09-13 11:07	50.43	OK	4354	2026-09-13 11:08	51.39	OK
4355	2026-09-13 11:09	49.41	OK	4356	2026-09-13 11:10	51.72	OK
4357	2026-09-13 11:11	52.61	OK	4358	2026-09-13 11:12	51.86	OK
4359	2026-09-13 11:13	50.28	OK	4360	2026-09-13 11:14	52.55	OK
4361	2026-09-13 11:15	51.79	OK	4362	2026-09-13 11:16	50.24	OK
4363	2026-09-13 11:17	49.88	OK	4364	2026-09-13 11:18	53.12	OK
4365	2026-09-13 11:19	52.13	OK	4366	2026-09-13 11:20	49.44	OK
4367	2026-09-13 11:21	51.14	OK	4368	2026-09-13 11:22	50.75	OK
4369	2026-09-13 11:23	52.05	OK	4370	2026-09-13 11:24	51.74	OK
4371	2026-09-13 11:25	50.99	OK	4372	2026-09-13 11:26	50.80	OK
4373	2026-09-13 11:27	51.21	OK	4374	2026-09-13 11:28	52.54	OK
4375	2026-09-13 11:29	51.33	OK	4376	2026-09-13 11:30	51.54	OK
4377	2026-09-13 11:31	50.81	OK	4378	2026-09-13 11:32	53.01	OK
4379	2026-09-13 11:33	50.46	OK	4380	2026-09-13 11:34	50.37	OK
4381	2026-09-13 11:35	49.75	OK	4382	2026-09-13 11:36	52.55	OK
4383	2026-09-13 11:37	51.11	OK	4384	2026-09-13 11:38	51.93	OK
4385	2026-09-13 11:39	51.11	OK	4386	2026-09-13 11:40	52.10	OK
4387	2026-09-13 11:41	51.89	OK	4388	2026-09-13 11:42	53.57	OK
4389	2026-09-13 11:43	52.27	OK	4390	2026-09-13 11:44	52.80	OK
4391	2026-09-13 11:45	51.44	OK	4392	2026-09-13 11:46	51.31	OK
4393	2026-09-13 11:47	51.17	OK	4394	2026-09-13 11:48	51.37	OK
4395	2026-09-13 11:49	50.63	OK	4396	2026-09-13 11:50	52.37	OK
4397	2026-09-13 11:51	52.20	OK	4398	2026-09-13 11:52	52.75	OK
4399	2026-09-13 11:53	52.06	OK	4400	2026-09-13 11:54	51.88	OK
4401	2026-09-13 11:55	51.09	OK	4402	2026-09-13 11:56	52.10	OK
4403	2026-09-13 11:57	51.97	OK	4404	2026-09-13 11:58	51.26	OK
4405	2026-09-13 11:59	50.13	OK	4406	2026-09-13 12:00	51.64	OK
4407	2026-09-13 12:01	51.52	OK	4408	2026-09-13 12:02	52.19	OK
4409	2026-09-13 12:03	50.66	OK	4410	2026-09-13 12:04	51.08	OK
4411	2026-09-13 12:05	52.57	OK	4412	2026-09-13 12:06	52.27	OK
4413	2026-09-13 12:07	50.84	OK	4414	2026-09-13 12:08	49.98	OK
4415	2026-09-13 12:09	52.08	OK	4416	2026-09-13 12:10	51.84	OK
4417	2026-09-13 12:11	53.07	OK	4418	2026-09-13 12:12	50.83	OK
4419	2026-09-13 12:13	50.11	OK	4420	2026-09-13 12:14	52.57	OK
4421	2026-09-13 12:15	52.87	OK	4422	2026-09-13 12:16	52.80	OK
4423	2026-09-13 12:17	51.12	OK	4424	2026-09-13 12:18	51.79	OK
4425	2026-09-13 12:19	50.80	OK	4426	2026-09-13 12:20	51.97	OK
4427	2026-09-13 12:21	51.11	OK	4428	2026-09-13 12:22	51.40	OK
4429	2026-09-13 12:23	52.41	OK	4430	2026-09-13 12:24	51.09	OK
4431	2026-09-13 12:25	52.61	OK	4432	2026-09-13 12:26	51.07	OK
4433	2026-09-13 12:27	52.15	OK	4434	2026-09-13 12:28	51.99	OK
4435	2026-09-13 12:29	52.81	OK	4436	2026-09-13 12:30	51.57	OK
4437	2026-09-13 12:31	51.58	OK	4438	2026-09-13 12:32	52.60	OK
4439	2026-09-13 12:33	53.30	OK	4440	2026-09-13 12:34	53.18	OK
4441	2026-09-13 12:35	50.44	OK	4442	2026-09-13 12:36	51.28	OK
4443	2026-09-13 12:37	51.41	OK	4444	2026-09-13 12:38	52.73	OK
4445	2026-09-13 12:39	51.59	OK	4446	2026-09-13 12:40	51.13	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4447	2026-09-13 12:41	50.62	OK	4448	2026-09-13 12:42	51.16	OK
4449	2026-09-13 12:43	52.07	OK	4450	2026-09-13 12:44	51.90	OK
4451	2026-09-13 12:45	50.47	OK	4452	2026-09-13 12:46	52.21	OK
4453	2026-09-13 12:47	53.24	OK	4454	2026-09-13 12:48	52.41	OK
4455	2026-09-13 12:49	50.82	OK	4456	2026-09-13 12:50	50.60	OK
4457	2026-09-13 12:51	51.69	OK	4458	2026-09-13 12:52	52.37	OK
4459	2026-09-13 12:53	51.57	OK	4460	2026-09-13 12:54	50.93	OK
4461	2026-09-13 12:55	51.81	OK	4462	2026-09-13 12:56	52.34	OK
4463	2026-09-13 12:57	50.95	OK	4464	2026-09-13 12:58	51.26	OK
4465	2026-09-13 12:59	52.66	OK	4466	2026-09-13 13:00	51.23	OK
4467	2026-09-13 13:01	50.82	OK	4468	2026-09-13 13:02	52.70	OK
4469	2026-09-13 13:03	50.51	OK	4470	2026-09-13 13:04	51.10	OK
4471	2026-09-13 13:05	52.10	OK	4472	2026-09-13 13:06	52.14	OK
4473	2026-09-13 13:07	52.50	OK	4474	2026-09-13 13:08	51.43	OK
4475	2026-09-13 13:09	53.71	OK	4476	2026-09-13 13:10	51.65	OK
4477	2026-09-13 13:11	50.61	OK	4478	2026-09-13 13:12	50.89	OK
4479	2026-09-13 13:13	53.25	OK	4480	2026-09-13 13:14	52.50	OK
4481	2026-09-13 13:15	52.24	OK	4482	2026-09-13 13:16	52.26	OK
4483	2026-09-13 13:17	51.77	OK	4484	2026-09-13 13:18	52.21	OK
4485	2026-09-13 13:19	51.76	OK	4486	2026-09-13 13:20	51.94	OK
4487	2026-09-13 13:21	53.18	OK	4488	2026-09-13 13:22	52.43	OK
4489	2026-09-13 13:23	50.79	OK	4490	2026-09-13 13:24	51.15	OK
4491	2026-09-13 13:25	53.07	OK	4492	2026-09-13 13:26	52.05	OK
4493	2026-09-13 13:27	49.95	OK	4494	2026-09-13 13:28	51.16	OK
4495	2026-09-13 13:29	53.05	OK	4496	2026-09-13 13:30	52.12	OK
4497	2026-09-13 13:31	50.79	OK	4498	2026-09-13 13:32	50.44	OK
4499	2026-09-13 13:33	52.54	OK	4500	2026-09-13 13:34	52.05	OK
4501	2026-09-13 13:35	52.28	OK	4502	2026-09-13 13:36	52.55	OK
4503	2026-09-13 13:37	51.12	OK	4504	2026-09-13 13:38	52.81	OK
4505	2026-09-13 13:39	50.88	OK	4506	2026-09-13 13:40	51.55	OK
4507	2026-09-13 13:41	53.53	OK	4508	2026-09-13 13:42	51.44	OK
4509	2026-09-13 13:43	50.74	OK	4510	2026-09-13 13:44	51.87	OK
4511	2026-09-13 13:45	52.49	OK	4512	2026-09-13 13:46	51.22	OK
4513	2026-09-13 13:47	52.13	OK	4514	2026-09-13 13:48	49.32	OK
4515	2026-09-13 13:49	51.86	OK	4516	2026-09-13 13:50	52.72	OK
4517	2026-09-13 13:51	50.46	OK	4518	2026-09-13 13:52	52.53	OK
4519	2026-09-13 13:53	50.99	OK	4520	2026-09-13 13:54	53.04	OK
4521	2026-09-13 13:55	51.05	OK	4522	2026-09-13 13:56	51.17	OK
4523	2026-09-13 13:57	50.53	OK	4524	2026-09-13 13:58	50.48	OK
4525	2026-09-13 13:59	52.95	OK	4526	2026-09-13 14:00	51.35	OK
4527	2026-09-13 14:01	51.26	OK	4528	2026-09-13 14:02	51.84	OK
4529	2026-09-13 14:03	51.63	OK	4530	2026-09-13 14:04	52.07	OK
4531	2026-09-13 14:05	51.23	OK	4532	2026-09-13 14:06	51.41	OK
4533	2026-09-13 14:07	52.68	OK	4534	2026-09-13 14:08	52.86	OK
4535	2026-09-13 14:09	51.73	OK	4536	2026-09-13 14:10	50.75	OK
4537	2026-09-13 14:11	49.54	OK	4538	2026-09-13 14:12	50.97	OK
4539	2026-09-13 14:13	52.82	OK	4540	2026-09-13 14:14	52.19	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4541	2026-09-13 14:15	51.80	OK	4542	2026-09-13 14:16	52.56	OK
4543	2026-09-13 14:17	52.60	OK	4544	2026-09-13 14:18	51.24	OK
4545	2026-09-13 14:19	51.99	OK	4546	2026-09-13 14:20	50.98	OK
4547	2026-09-13 14:21	50.37	OK	4548	2026-09-13 14:22	52.31	OK
4549	2026-09-13 14:23	52.17	OK	4550	2026-09-13 14:24	52.50	OK
4551	2026-09-13 14:25	51.00	OK	4552	2026-09-13 14:26	50.09	OK
4553	2026-09-13 14:27	52.42	OK	4554	2026-09-13 14:28	52.79	OK
4555	2026-09-13 14:29	52.20	OK	4556	2026-09-13 14:30	51.30	OK
4557	2026-09-13 14:31	52.89	OK	4558	2026-09-13 14:32	52.32	OK
4559	2026-09-13 14:33	52.80	OK	4560	2026-09-13 14:34	52.92	OK
4561	2026-09-13 14:35	50.36	OK	4562	2026-09-13 14:36	50.74	OK
4563	2026-09-13 14:37	52.61	OK	4564	2026-09-13 14:38	52.58	OK
4565	2026-09-13 14:39	51.53	OK	4566	2026-09-13 14:40	50.60	OK
4567	2026-09-13 14:41	51.77	OK	4568	2026-09-13 14:42	52.56	OK
4569	2026-09-13 14:43	52.00	OK	4570	2026-09-13 14:44	52.07	OK
4571	2026-09-13 14:45	49.22	OK	4572	2026-09-13 14:46	52.65	OK
4573	2026-09-13 14:47	51.99	OK	4574	2026-09-13 14:48	51.99	OK
4575	2026-09-13 14:49	50.60	OK	4576	2026-09-13 14:50	52.06	OK
4577	2026-09-13 14:51	50.58	OK	4578	2026-09-13 14:52	52.83	OK
4579	2026-09-13 14:53	50.78	OK	4580	2026-09-13 14:54	51.53	OK
4581	2026-09-13 14:55	49.08	OK	4582	2026-09-13 14:56	50.83	OK
4583	2026-09-13 14:57	52.76	OK	4584	2026-09-13 14:58	53.03	OK
4585	2026-09-13 14:59	51.65	OK	4586	2026-09-13 15:00	51.40	OK
4587	2026-09-13 15:01	50.61	OK	4588	2026-09-13 15:02	50.69	OK
4589	2026-09-13 15:03	51.38	OK	4590	2026-09-13 15:04	52.91	OK
4591	2026-09-13 15:05	50.72	OK	4592	2026-09-13 15:06	50.94	OK
4593	2026-09-13 15:07	53.00	OK	4594	2026-09-13 15:08	51.86	OK
4595	2026-09-13 15:09	51.77	OK	4596	2026-09-13 15:10	50.28	OK
4597	2026-09-13 15:11	50.73	OK	4598	2026-09-13 15:12	50.60	OK
4599	2026-09-13 15:13	50.33	OK	4600	2026-09-13 15:14	50.11	OK
4601	2026-09-13 15:15	51.76	OK	4602	2026-09-13 15:16	50.95	OK
4603	2026-09-13 15:17	49.89	OK	4604	2026-09-13 15:18	52.82	OK
4605	2026-09-13 15:19	50.52	OK	4606	2026-09-13 15:20	52.89	OK
4607	2026-09-13 15:21	52.14	OK	4608	2026-09-13 15:22	49.60	OK
4609	2026-09-13 15:23	51.26	OK	4610	2026-09-13 15:24	50.62	OK
4611	2026-09-13 15:25	51.67	OK	4612	2026-09-13 15:26	50.38	OK
4613	2026-09-13 15:27	51.76	OK	4614	2026-09-13 15:28	51.83	OK
4615	2026-09-13 15:29	50.51	OK	4616	2026-09-13 15:30	52.66	OK
4617	2026-09-13 15:31	50.89	OK	4618	2026-09-13 15:32	52.18	OK
4619	2026-09-13 15:33	51.29	OK	4620	2026-09-13 15:34	52.20	OK
4621	2026-09-13 15:35	51.51	OK	4622	2026-09-13 15:36	51.30	OK
4623	2026-09-13 15:37	51.15	OK	4624	2026-09-13 15:38	48.95	OK
4625	2026-09-13 15:39	53.01	OK	4626	2026-09-13 15:40	51.79	OK
4627	2026-09-13 15:41	51.73	OK	4628	2026-09-13 15:42	49.71	OK
4629	2026-09-13 15:43	51.11	OK	4630	2026-09-13 15:44	52.11	OK
4631	2026-09-13 15:45	51.45	OK	4632	2026-09-13 15:46	52.20	OK
4633	2026-09-13 15:47	50.34	OK	4634	2026-09-13 15:48	51.33	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4635	2026-09-13 15:49	50.91	OK	4636	2026-09-13 15:50	50.20	OK
4637	2026-09-13 15:51	50.45	OK	4638	2026-09-13 15:52	52.18	OK
4639	2026-09-13 15:53	51.61	OK	4640	2026-09-13 15:54	50.60	OK
4641	2026-09-13 15:55	52.06	OK	4642	2026-09-13 15:56	51.11	OK
4643	2026-09-13 15:57	49.73	OK	4644	2026-09-13 15:58	51.96	OK
4645	2026-09-13 15:59	50.12	OK	4646	2026-09-13 16:00	50.70	OK
4647	2026-09-13 16:01	50.45	OK	4648	2026-09-13 16:02	52.28	OK
4649	2026-09-13 16:03	50.17	OK	4650	2026-09-13 16:04	51.74	OK
4651	2026-09-13 16:05	51.13	OK	4652	2026-09-13 16:06	50.63	OK
4653	2026-09-13 16:07	51.75	OK	4654	2026-09-13 16:08	51.35	OK
4655	2026-09-13 16:09	51.39	OK	4656	2026-09-13 16:10	50.17	OK
4657	2026-09-13 16:11	51.19	OK	4658	2026-09-13 16:12	51.00	OK
4659	2026-09-13 16:13	50.06	OK	4660	2026-09-13 16:14	49.89	OK
4661	2026-09-13 16:15	51.07	OK	4662	2026-09-13 16:16	49.82	OK
4663	2026-09-13 16:17	50.87	OK	4664	2026-09-13 16:18	51.43	OK
4665	2026-09-13 16:19	49.51	OK	4666	2026-09-13 16:20	51.24	OK
4667	2026-09-13 16:21	50.39	OK	4668	2026-09-13 16:22	49.88	OK
4669	2026-09-13 16:23	52.72	OK	4670	2026-09-13 16:24	50.34	OK
4671	2026-09-13 16:25	50.18	OK	4672	2026-09-13 16:26	52.04	OK
4673	2026-09-13 16:27	50.08	OK	4674	2026-09-13 16:28	49.61	OK
4675	2026-09-13 16:29	51.96	OK	4676	2026-09-13 16:30	50.56	OK
4677	2026-09-13 16:31	51.58	OK	4678	2026-09-13 16:32	51.32	OK
4679	2026-09-13 16:33	51.29	OK	4680	2026-09-13 16:34	50.37	OK
4681	2026-09-13 16:35	50.32	OK	4682	2026-09-13 16:36	51.00	OK
4683	2026-09-13 16:37	49.04	OK	4684	2026-09-13 16:38	51.69	OK
4685	2026-09-13 16:39	51.04	OK	4686	2026-09-13 16:40	50.72	OK
4687	2026-09-13 16:41	51.70	OK	4688	2026-09-13 16:42	50.63	OK
4689	2026-09-13 16:43	52.50	OK	4690	2026-09-13 16:44	50.88	OK
4691	2026-09-13 16:45	50.20	OK	4692	2026-09-13 16:46	49.66	OK
4693	2026-09-13 16:47	52.51	OK	4694	2026-09-13 16:48	50.16	OK
4695	2026-09-13 16:49	50.77	OK	4696	2026-09-13 16:50	50.97	OK
4697	2026-09-13 16:51	49.83	OK	4698	2026-09-13 16:52	51.76	OK
4699	2026-09-13 16:53	51.47	OK	4700	2026-09-13 16:54	51.05	OK
4701	2026-09-13 16:55	49.85	OK	4702	2026-09-13 16:56	48.23	OK
4703	2026-09-13 16:57	51.46	OK	4704	2026-09-13 16:58	50.17	OK
4705	2026-09-13 16:59	50.11	OK	4706	2026-09-13 17:00	49.74	OK
4707	2026-09-13 17:01	50.40	OK	4708	2026-09-13 17:02	49.01	OK
4709	2026-09-13 17:03	50.31	OK	4710	2026-09-13 17:04	49.25	OK
4711	2026-09-13 17:05	48.58	OK	4712	2026-09-13 17:06	50.87	OK
4713	2026-09-13 17:07	52.33	OK	4714	2026-09-13 17:08	49.77	OK
4715	2026-09-13 17:09	51.50	OK	4716	2026-09-13 17:10	50.20	OK
4717	2026-09-13 17:11	51.98	OK	4718	2026-09-13 17:12	49.75	OK
4719	2026-09-13 17:13	50.77	OK	4720	2026-09-13 17:14	48.93	OK
4721	2026-09-13 17:15	51.07	OK	4722	2026-09-13 17:16	49.44	OK
4723	2026-09-13 17:17	50.50	OK	4724	2026-09-13 17:18	50.82	OK
4725	2026-09-13 17:19	49.84	OK	4726	2026-09-13 17:20	49.78	OK
4727	2026-09-13 17:21	50.99	OK	4728	2026-09-13 17:22	50.42	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4729	2026-09-13 17:23	49.44	OK	4730	2026-09-13 17:24	50.94	OK
4731	2026-09-13 17:25	49.49	OK	4732	2026-09-13 17:26	52.15	OK
4733	2026-09-13 17:27	50.10	OK	4734	2026-09-13 17:28	49.38	OK
4735	2026-09-13 17:29	50.26	OK	4736	2026-09-13 17:30	50.20	OK
4737	2026-09-13 17:31	50.04	OK	4738	2026-09-13 17:32	49.14	OK
4739	2026-09-13 17:33	51.81	OK	4740	2026-09-13 17:34	50.76	OK
4741	2026-09-13 17:35	49.20	OK	4742	2026-09-13 17:36	49.29	OK
4743	2026-09-13 17:37	50.94	OK	4744	2026-09-13 17:38	49.75	OK
4745	2026-09-13 17:39	50.25	OK	4746	2026-09-13 17:40	49.78	OK
4747	2026-09-13 17:41	50.19	OK	4748	2026-09-13 17:42	50.32	OK
4749	2026-09-13 17:43	49.75	OK	4750	2026-09-13 17:44	50.36	OK
4751	2026-09-13 17:45	50.80	OK	4752	2026-09-13 17:46	47.76	OK
4753	2026-09-13 17:47	49.39	OK	4754	2026-09-13 17:48	48.73	OK
4755	2026-09-13 17:49	50.92	OK	4756	2026-09-13 17:50	49.99	OK
4757	2026-09-13 17:51	50.16	OK	4758	2026-09-13 17:52	50.43	OK
4759	2026-09-13 17:53	50.04	OK	4760	2026-09-13 17:54	50.58	OK
4761	2026-09-13 17:55	50.06	OK	4762	2026-09-13 17:56	48.51	OK
4763	2026-09-13 17:57	49.44	OK	4764	2026-09-13 17:58	49.72	OK
4765	2026-09-13 17:59	50.24	OK	4766	2026-09-13 18:00	50.10	OK
4767	2026-09-13 18:01	48.55	OK	4768	2026-09-13 18:02	49.18	OK
4769	2026-09-13 18:03	49.96	OK	4770	2026-09-13 18:04	49.21	OK
4771	2026-09-13 18:05	48.73	OK	4772	2026-09-13 18:06	50.78	OK
4773	2026-09-13 18:07	48.76	OK	4774	2026-09-13 18:08	50.06	OK
4775	2026-09-13 18:09	49.08	OK	4776	2026-09-13 18:10	50.41	OK
4777	2026-09-13 18:11	49.01	OK	4778	2026-09-13 18:12	47.89	OK
4779	2026-09-13 18:13	48.84	OK	4780	2026-09-13 18:14	50.04	OK
4781	2026-09-13 18:15	50.25	OK	4782	2026-09-13 18:16	49.64	OK
4783	2026-09-13 18:17	51.10	OK	4784	2026-09-13 18:18	50.90	OK
4785	2026-09-13 18:19	47.96	OK	4786	2026-09-13 18:20	48.75	OK
4787	2026-09-13 18:21	49.45	OK	4788	2026-09-13 18:22	49.83	OK
4789	2026-09-13 18:23	50.90	OK	4790	2026-09-13 18:24	49.11	OK
4791	2026-09-13 18:25	48.00	OK	4792	2026-09-13 18:26	50.70	OK
4793	2026-09-13 18:27	49.47	OK	4794	2026-09-13 18:28	48.60	OK
4795	2026-09-13 18:29	50.13	OK	4796	2026-09-13 18:30	48.57	OK
4797	2026-09-13 18:31	48.25	OK	4798	2026-09-13 18:32	48.99	OK
4799	2026-09-13 18:33	50.98	OK	4800	2026-09-13 18:34	49.90	OK
4801	2026-09-13 18:35	47.99	OK	4802	2026-09-13 18:36	47.62	OK
4803	2026-09-13 18:37	49.85	OK	4804	2026-09-13 18:38	48.00	OK
4805	2026-09-13 18:39	49.89	OK	4806	2026-09-13 18:40	48.41	OK
4807	2026-09-13 18:41	51.18	OK	4808	2026-09-13 18:42	47.62	OK
4809	2026-09-13 18:43	48.29	OK	4810	2026-09-13 18:44	49.95	OK
4811	2026-09-13 18:45	50.65	OK	4812	2026-09-13 18:46	48.63	OK
4813	2026-09-13 18:47	49.53	OK	4814	2026-09-13 18:48	48.72	OK
4815	2026-09-13 18:49	49.70	OK	4816	2026-09-13 18:50	49.05	OK
4817	2026-09-13 18:51	49.53	OK	4818	2026-09-13 18:52	50.19	OK
4819	2026-09-13 18:53	48.71	OK	4820	2026-09-13 18:54	49.04	OK
4821	2026-09-13 18:55	49.51	OK	4822	2026-09-13 18:56	49.51	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4823	2026-09-13 18:57	50.16	OK	4824	2026-09-13 18:58	47.90	OK
4825	2026-09-13 18:59	49.47	OK	4826	2026-09-13 19:00	50.06	OK
4827	2026-09-13 19:01	50.12	OK	4828	2026-09-13 19:02	49.79	OK
4829	2026-09-13 19:03	46.65	OK	4830	2026-09-13 19:04	47.22	OK
4831	2026-09-13 19:05	49.64	OK	4832	2026-09-13 19:06	47.87	OK
4833	2026-09-13 19:07	46.96	OK	4834	2026-09-13 19:08	48.73	OK
4835	2026-09-13 19:09	49.75	OK	4836	2026-09-13 19:10	49.44	OK
4837	2026-09-13 19:11	48.78	OK	4838	2026-09-13 19:12	49.92	OK
4839	2026-09-13 19:13	48.58	OK	4840	2026-09-13 19:14	47.64	OK
4841	2026-09-13 19:15	49.10	OK	4842	2026-09-13 19:16	49.90	OK
4843	2026-09-13 19:17	49.71	OK	4844	2026-09-13 19:18	47.47	OK
4845	2026-09-13 19:19	45.83	OK	4846	2026-09-13 19:20	50.97	OK
4847	2026-09-13 19:21	48.36	OK	4848	2026-09-13 19:22	47.39	OK
4849	2026-09-13 19:23	50.36	OK	4850	2026-09-13 19:24	49.88	OK
4851	2026-09-13 19:25	49.86	OK	4852	2026-09-13 19:26	49.13	OK
4853	2026-09-13 19:27	48.21	OK	4854	2026-09-13 19:28	49.05	OK
4855	2026-09-13 19:29	48.80	OK	4856	2026-09-13 19:30	48.00	OK
4857	2026-09-13 19:31	48.02	OK	4858	2026-09-13 19:32	49.12	OK
4859	2026-09-13 19:33	48.75	OK	4860	2026-09-13 19:34	49.39	OK
4861	2026-09-13 19:35	46.84	OK	4862	2026-09-13 19:36	47.68	OK
4863	2026-09-13 19:37	48.81	OK	4864	2026-09-13 19:38	48.65	OK
4865	2026-09-13 19:39	47.90	OK	4866	2026-09-13 19:40	47.90	OK
4867	2026-09-13 19:41	49.96	OK	4868	2026-09-13 19:42	49.01	OK
4869	2026-09-13 19:43	46.87	OK	4870	2026-09-13 19:44	49.73	OK
4871	2026-09-13 19:45	48.94	OK	4872	2026-09-13 19:46	48.47	OK
4873	2026-09-13 19:47	49.87	OK	4874	2026-09-13 19:48	48.93	OK
4875	2026-09-13 19:49	48.92	OK	4876	2026-09-13 19:50	48.23	OK
4877	2026-09-13 19:51	47.27	OK	4878	2026-09-13 19:52	47.91	OK
4879	2026-09-13 19:53	49.32	OK	4880	2026-09-13 19:54	46.87	OK
4881	2026-09-13 19:55	47.95	OK	4882	2026-09-13 19:56	47.62	OK
4883	2026-09-13 19:57	46.85	OK	4884	2026-09-13 19:58	49.99	OK
4885	2026-09-13 19:59	48.31	OK	4886	2026-09-13 20:00	47.18	OK
4887	2026-09-13 20:01	47.25	OK	4888	2026-09-13 20:02	47.28	OK
4889	2026-09-13 20:03	47.20	OK	4890	2026-09-13 20:04	45.34	OK
4891	2026-09-13 20:05	49.05	OK	4892	2026-09-13 20:06	48.70	OK
4893	2026-09-13 20:07	46.84	OK	4894	2026-09-13 20:08	47.76	OK
4895	2026-09-13 20:09	48.03	OK	4896	2026-09-13 20:10	47.39	OK
4897	2026-09-13 20:11	48.66	OK	4898	2026-09-13 20:12	49.01	OK
4899	2026-09-13 20:13	47.09	OK	4900	2026-09-13 20:14	48.07	OK
4901	2026-09-13 20:15	46.25	OK	4902	2026-09-13 20:16	47.03	OK
4903	2026-09-13 20:17	47.64	OK	4904	2026-09-13 20:18	48.86	OK
4905	2026-09-13 20:19	47.16	OK	4906	2026-09-13 20:20	48.98	OK
4907	2026-09-13 20:21	48.04	OK	4908	2026-09-13 20:22	48.06	OK
4909	2026-09-13 20:23	47.56	OK	4910	2026-09-13 20:24	46.24	OK
4911	2026-09-13 20:25	49.01	OK	4912	2026-09-13 20:26	47.15	OK
4913	2026-09-13 20:27	48.84	OK	4914	2026-09-13 20:28	48.36	OK
4915	2026-09-13 20:29	47.49	OK	4916	2026-09-13 20:30	48.72	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4917	2026-09-13 20:31	47.36	OK	4918	2026-09-13 20:32	48.99	OK
4919	2026-09-13 20:33	48.42	OK	4920	2026-09-13 20:34	47.43	OK
4921	2026-09-13 20:35	47.44	OK	4922	2026-09-13 20:36	46.17	OK
4923	2026-09-13 20:37	48.39	OK	4924	2026-09-13 20:38	48.89	OK
4925	2026-09-13 20:39	48.47	OK	4926	2026-09-13 20:40	46.71	OK
4927	2026-09-13 20:41	46.22	OK	4928	2026-09-13 20:42	47.14	OK
4929	2026-09-13 20:43	48.20	OK	4930	2026-09-13 20:44	46.57	OK
4931	2026-09-13 20:45	47.84	OK	4932	2026-09-13 20:46	47.60	OK
4933	2026-09-13 20:47	46.93	OK	4934	2026-09-13 20:48	47.36	OK
4935	2026-09-13 20:49	49.54	OK	4936	2026-09-13 20:50	49.15	OK
4937	2026-09-13 20:51	45.99	OK	4938	2026-09-13 20:52	47.52	OK
4939	2026-09-13 20:53	47.17	OK	4940	2026-09-13 20:54	46.33	OK
4941	2026-09-13 20:55	46.43	OK	4942	2026-09-13 20:56	46.15	OK
4943	2026-09-13 20:57	46.99	OK	4944	2026-09-13 20:58	48.40	OK
4945	2026-09-13 20:59	47.20	OK	4946	2026-09-13 21:00	47.74	OK
4947	2026-09-13 21:01	45.94	OK	4948	2026-09-13 21:02	46.84	OK
4949	2026-09-13 21:03	45.75	OK	4950	2026-09-13 21:04	47.64	OK
4951	2026-09-13 21:05	46.59	OK	4952	2026-09-13 21:06	48.70	OK
4953	2026-09-13 21:07	47.65	OK	4954	2026-09-13 21:08	46.15	OK
4955	2026-09-13 21:09	45.25	OK	4956	2026-09-13 21:10	48.65	OK
4957	2026-09-13 21:11	44.69	OK	4958	2026-09-13 21:12	46.58	OK
4959	2026-09-13 21:13	48.78	OK	4960	2026-09-13 21:14	45.60	OK
4961	2026-09-13 21:15	45.69	OK	4962	2026-09-13 21:16	46.82	OK
4963	2026-09-13 21:17	47.98	OK	4964	2026-09-13 21:18	46.37	OK
4965	2026-09-13 21:19	46.14	OK	4966	2026-09-13 21:20	46.98	OK
4967	2026-09-13 21:21	46.65	OK	4968	2026-09-13 21:22	47.81	OK
4969	2026-09-13 21:23	47.11	OK	4970	2026-09-13 21:24	48.09	OK
4971	2026-09-13 21:25	46.71	OK	4972	2026-09-13 21:26	45.01	OK
4973	2026-09-13 21:27	48.00	OK	4974	2026-09-13 21:28	47.00	OK
4975	2026-09-13 21:29	45.12	OK	4976	2026-09-13 21:30	48.52	OK
4977	2026-09-13 21:31	46.40	OK	4978	2026-09-13 21:32	44.56	OK
4979	2026-09-13 21:33	46.57	OK	4980	2026-09-13 21:34	47.86	OK
4981	2026-09-13 21:35	47.00	OK	4982	2026-09-13 21:36	46.11	OK
4983	2026-09-13 21:37	47.15	OK	4984	2026-09-13 21:38	46.77	OK
4985	2026-09-13 21:39	48.30	OK	4986	2026-09-13 21:40	47.78	OK
4987	2026-09-13 21:41	45.95	OK	4988	2026-09-13 21:42	46.10	OK
4989	2026-09-13 21:43	46.74	OK	4990	2026-09-13 21:44	49.28	OK
4991	2026-09-13 21:45	45.16	OK	4992	2026-09-13 21:46	48.47	OK
4993	2026-09-13 21:47	45.82	OK	4994	2026-09-13 21:48	47.33	OK
4995	2026-09-13 21:49	45.03	OK	4996	2026-09-13 21:50	47.98	OK
4997	2026-09-13 21:51	46.78	OK	4998	2026-09-13 21:52	46.88	OK
4999	2026-09-13 21:53	45.42	OK	5000	2026-09-13 21:54	46.97	OK
5001	2026-09-13 21:55	47.21	OK	5002	2026-09-13 21:56	47.06	OK
5003	2026-09-13 21:57	47.55	OK	5004	2026-09-13 21:58	45.22	OK
5005	2026-09-13 21:59	46.46	OK	5006	2026-09-13 22:00	47.74	OK
5007	2026-09-13 22:01	46.97	OK	5008	2026-09-13 22:02	44.98	OK
5009	2026-09-13 22:03	46.23	OK	5010	2026-09-13 22:04	47.82	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5011	2026-09-13 22:05	47.53	OK	5012	2026-09-13 22:06	47.21	OK
5013	2026-09-13 22:07	47.35	OK	5014	2026-09-13 22:08	47.05	OK
5015	2026-09-13 22:09	45.81	OK	5016	2026-09-13 22:10	46.02	OK
5017	2026-09-13 22:11	46.42	OK	5018	2026-09-13 22:12	45.04	OK
5019	2026-09-13 22:13	47.16	OK	5020	2026-09-13 22:14	46.38	OK
5021	2026-09-13 22:15	46.56	OK	5022	2026-09-13 22:16	46.82	OK
5023	2026-09-13 22:17	45.69	OK	5024	2026-09-13 22:18	46.03	OK
5025	2026-09-13 22:19	46.36	OK	5026	2026-09-13 22:20	45.12	OK
5027	2026-09-13 22:21	47.73	OK	5028	2026-09-13 22:22	45.48	OK
5029	2026-09-13 22:23	46.58	OK	5030	2026-09-13 22:24	45.98	OK
5031	2026-09-13 22:25	45.50	OK	5032	2026-09-13 22:26	45.11	OK
5033	2026-09-13 22:27	47.57	OK	5034	2026-09-13 22:28	45.38	OK
5035	2026-09-13 22:29	46.47	OK	5036	2026-09-13 22:30	46.92	OK
5037	2026-09-13 22:31	46.25	OK	5038	2026-09-13 22:32	45.61	OK
5039	2026-09-13 22:33	47.00	OK	5040	2026-09-13 22:34	46.46	OK
5041	2026-09-13 22:35	45.78	OK	5042	2026-09-13 22:36	45.99	OK
5043	2026-09-13 22:37	45.44	OK	5044	2026-09-13 22:38	47.33	OK
5045	2026-09-13 22:39	48.00	OK	5046	2026-09-13 22:40	46.50	OK
5047	2026-09-13 22:41	44.68	OK	5048	2026-09-13 22:42	45.21	OK
5049	2026-09-13 22:43	47.09	OK	5050	2026-09-13 22:44	46.24	OK
5051	2026-09-13 22:45	44.15	OK	5052	2026-09-13 22:46	46.24	OK
5053	2026-09-13 22:47	46.69	OK	5054	2026-09-13 22:48	46.59	OK
5055	2026-09-13 22:49	45.76	OK	5056	2026-09-13 22:50	46.81	OK
5057	2026-09-13 22:51	44.80	OK	5058	2026-09-13 22:52	47.01	OK
5059	2026-09-13 22:53	45.65	OK	5060	2026-09-13 22:54	46.30	OK
5061	2026-09-13 22:55	46.73	OK	5062	2026-09-13 22:56	47.34	OK
5063	2026-09-13 22:57	45.50	OK	5064	2026-09-13 22:58	48.37	OK
5065	2026-09-13 22:59	44.31	OK	5066	2026-09-13 23:00	48.37	OK
5067	2026-09-13 23:01	44.68	OK	5068	2026-09-13 23:02	45.48	OK
5069	2026-09-13 23:03	45.05	OK	5070	2026-09-13 23:04	43.96	OK
5071	2026-09-13 23:05	47.18	OK	5072	2026-09-13 23:06	44.59	OK
5073	2026-09-13 23:07	47.30	OK	5074	2026-09-13 23:08	45.73	OK
5075	2026-09-13 23:09	45.90	OK	5076	2026-09-13 23:10	45.15	OK
5077	2026-09-13 23:11	44.91	OK	5078	2026-09-13 23:12	45.00	OK
5079	2026-09-13 23:13	44.80	OK	5080	2026-09-13 23:14	46.82	OK
5081	2026-09-13 23:15	45.20	OK	5082	2026-09-13 23:16	44.81	OK
5083	2026-09-13 23:17	44.07	OK	5084	2026-09-13 23:18	46.16	OK
5085	2026-09-13 23:19	46.50	OK	5086	2026-09-13 23:20	44.73	OK
5087	2026-09-13 23:21	44.51	OK	5088	2026-09-13 23:22	46.99	OK
5089	2026-09-13 23:23	46.58	OK	5090	2026-09-13 23:24	46.30	OK
5091	2026-09-13 23:25	44.78	OK	5092	2026-09-13 23:26	45.61	OK
5093	2026-09-13 23:27	44.49	OK	5094	2026-09-13 23:28	44.38	OK
5095	2026-09-13 23:29	45.59	OK	5096	2026-09-13 23:30	43.21	OK
5097	2026-09-13 23:31	47.14	OK	5098	2026-09-13 23:32	46.76	OK
5099	2026-09-13 23:33	44.98	OK	5100	2026-09-13 23:34	46.26	OK
5101	2026-09-13 23:35	45.98	OK	5102	2026-09-13 23:36	47.17	OK
5103	2026-09-13 23:37	44.94	OK	5104	2026-09-13 23:38	45.68	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5105	2026-09-13 23:39	46.91	OK	5106	2026-09-13 23:40	45.10	OK
5107	2026-09-13 23:41	44.70	OK	5108	2026-09-13 23:42	45.74	OK
5109	2026-09-13 23:43	46.19	OK	5110	2026-09-13 23:44	47.11	OK
5111	2026-09-13 23:45	46.73	OK	5112	2026-09-13 23:46	44.60	OK
5113	2026-09-13 23:47	46.44	OK	5114	2026-09-13 23:48	43.71	OK
5115	2026-09-13 23:49	45.78	OK	5116	2026-09-13 23:50	45.91	OK
5117	2026-09-13 23:51	44.47	OK	5118	2026-09-13 23:52	47.11	OK
5119	2026-09-13 23:53	47.45	OK	5120	2026-09-13 23:54	47.13	OK
5121	2026-09-13 23:55	46.66	OK	5122	2026-09-13 23:56	45.03	OK
5123	2026-09-13 23:57	45.30	OK	5124	2026-09-13 23:58	45.24	OK
5125	2026-09-13 23:59	44.81	OK	5126	2026-09-14 00:00	45.42	OK
5127	2026-09-14 00:01	45.02	OK	5128	2026-09-14 00:02	46.00	OK
5129	2026-09-14 00:03	45.54	OK	5130	2026-09-14 00:04	44.51	OK
5131	2026-09-14 00:05	46.16	OK	5132	2026-09-14 00:06	44.57	OK
5133	2026-09-14 00:07	43.51	OK	5134	2026-09-14 00:08	45.30	OK
5135	2026-09-14 00:09	45.90	OK	5136	2026-09-14 00:10	45.60	OK
5137	2026-09-14 00:11	45.34	OK	5138	2026-09-14 00:12	44.42	OK
5139	2026-09-14 00:13	44.05	OK	5140	2026-09-14 00:14	46.00	OK
5141	2026-09-14 00:15	45.41	OK	5142	2026-09-14 00:16	47.42	OK
5143	2026-09-14 00:17	45.61	OK	5144	2026-09-14 00:18	44.56	OK
5145	2026-09-14 00:19	46.20	OK	5146	2026-09-14 00:20	44.43	OK
5147	2026-09-14 00:21	45.98	OK	5148	2026-09-14 00:22	45.16	OK
5149	2026-09-14 00:23	44.01	OK	5150	2026-09-14 00:24	44.36	OK
5151	2026-09-14 00:25	45.45	OK	5152	2026-09-14 00:26	44.77	OK
5153	2026-09-14 00:27	45.57	OK	5154	2026-09-14 00:28	45.49	OK
5155	2026-09-14 00:29	44.38	OK	5156	2026-09-14 00:30	47.30	OK
5157	2026-09-14 00:31	45.82	OK	5158	2026-09-14 00:32	45.31	OK
5159	2026-09-14 00:33	45.80	OK	5160	2026-09-14 00:34	46.18	OK
5161	2026-09-14 00:35	45.53	OK	5162	2026-09-14 00:36	43.93	OK
5163	2026-09-14 00:37	45.27	OK	5164	2026-09-14 00:38	43.33	OK
5165	2026-09-14 00:39	44.27	OK	5166	2026-09-14 00:40	45.15	OK
5167	2026-09-14 00:41	45.54	OK	5168	2026-09-14 00:42	42.59	OK
5169	2026-09-14 00:43	47.47	OK	5170	2026-09-14 00:44	45.45	OK
5171	2026-09-14 00:45	45.61	OK	5172	2026-09-14 00:46	44.74	OK
5173	2026-09-14 00:47	46.86	OK	5174	2026-09-14 00:48	45.36	OK
5175	2026-09-14 00:49	44.84	OK	5176	2026-09-14 00:50	45.92	OK
5177	2026-09-14 00:51	45.14	OK	5178	2026-09-14 00:52	46.10	OK
5179	2026-09-14 00:53	43.79	OK	5180	2026-09-14 00:54	46.70	OK
5181	2026-09-14 00:55	46.79	OK	5182	2026-09-14 00:56	45.86	OK
5183	2026-09-14 00:57	45.54	OK	5184	2026-09-14 00:58	47.58	OK
5185	2026-09-14 00:59	44.83	OK	5186	2026-09-14 01:00	44.56	OK
5187	2026-09-14 01:01	44.38	OK	5188	2026-09-14 01:02	43.94	OK
5189	2026-09-14 01:03	45.69	OK	5190	2026-09-14 01:04	45.61	OK
5191	2026-09-14 01:05	46.11	OK	5192	2026-09-14 01:06	44.21	OK
5193	2026-09-14 01:07	45.41	OK	5194	2026-09-14 01:08	45.38	OK
5195	2026-09-14 01:09	44.23	OK	5196	2026-09-14 01:10	44.92	OK
5197	2026-09-14 01:11	44.54	OK	5198	2026-09-14 01:12	47.08	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5199	2026-09-14 01:13	45.20	OK	5200	2026-09-14 01:14	46.05	OK
5201	2026-09-14 01:15	44.61	OK	5202	2026-09-14 01:16	44.78	OK
5203	2026-09-14 01:17	44.05	OK	5204	2026-09-14 01:18	46.93	OK
5205	2026-09-14 01:19	45.23	OK	5206	2026-09-14 01:20	46.76	OK
5207	2026-09-14 01:21	45.17	OK	5208	2026-09-14 01:22	44.13	OK
5209	2026-09-14 01:23	44.32	OK	5210	2026-09-14 01:24	44.40	OK
5211	2026-09-14 01:25	46.19	OK	5212	2026-09-14 01:26	43.96	OK
5213	2026-09-14 01:27	44.32	OK	5214	2026-09-14 01:28	46.78	OK
5215	2026-09-14 01:29	43.73	OK	5216	2026-09-14 01:30	44.72	OK
5217	2026-09-14 01:31	45.88	OK	5218	2026-09-14 01:32	46.51	OK
5219	2026-09-14 01:33	45.44	OK	5220	2026-09-14 01:34	46.03	OK
5221	2026-09-14 01:35	46.16	OK	5222	2026-09-14 01:36	44.59	OK
5223	2026-09-14 01:37	45.41	OK	5224	2026-09-14 01:38	45.06	OK
5225	2026-09-14 01:39	45.49	OK	5226	2026-09-14 01:40	46.51	OK
5227	2026-09-14 01:41	44.79	OK	5228	2026-09-14 01:42	46.12	OK
5229	2026-09-14 01:43	44.95	OK	5230	2026-09-14 01:44	44.28	OK
5231	2026-09-14 01:45	43.60	OK	5232	2026-09-14 01:46	44.26	OK
5233	2026-09-14 01:47	44.46	OK	5234	2026-09-14 01:48	47.06	OK
5235	2026-09-14 01:49	45.64	OK	5236	2026-09-14 01:50	45.33	OK
5237	2026-09-14 01:51	43.18	OK	5238	2026-09-14 01:52	43.82	OK
5239	2026-09-14 01:53	46.64	OK	5240	2026-09-14 01:54	44.94	OK
5241	2026-09-14 01:55	47.00	OK	5242	2026-09-14 01:56	45.21	OK
5243	2026-09-14 01:57	46.47	OK	5244	2026-09-14 01:58	43.94	OK
5245	2026-09-14 01:59	46.42	OK	5246	2026-09-14 02:00	45.52	OK
5247	2026-09-14 02:01	45.11	OK	5248	2026-09-14 02:02	43.33	OK
5249	2026-09-14 02:03	46.07	OK	5250	2026-09-14 02:04	47.18	OK
5251	2026-09-14 02:05	47.36	OK	5252	2026-09-14 02:06	44.49	OK
5253	2026-09-14 02:07	45.48	OK	5254	2026-09-14 02:08	44.33	OK
5255	2026-09-14 02:09	46.05	OK	5256	2026-09-14 02:10	46.07	OK
5257	2026-09-14 02:11	45.07	OK	5258	2026-09-14 02:12	45.78	OK
5259	2026-09-14 02:13	43.38	OK	5260	2026-09-14 02:14	46.10	OK
5261	2026-09-14 02:15	47.04	OK	5262	2026-09-14 02:16	44.79	OK
5263	2026-09-14 02:17	44.56	OK	5264	2026-09-14 02:18	47.05	OK
5265	2026-09-14 02:19	46.10	OK	5266	2026-09-14 02:20	43.42	OK
5267	2026-09-14 02:21	44.29	OK	5268	2026-09-14 02:22	44.41	OK
5269	2026-09-14 02:23	47.07	OK	5270	2026-09-14 02:24	45.28	OK
5271	2026-09-14 02:25	44.85	OK	5272	2026-09-14 02:26	44.17	OK
5273	2026-09-14 02:27	45.51	OK	5274	2026-09-14 02:28	43.90	OK
5275	2026-09-14 02:29	45.17	OK	5276	2026-09-14 02:30	45.31	OK
5277	2026-09-14 02:31	44.16	OK	5278	2026-09-14 02:32	45.26	OK
5279	2026-09-14 02:33	44.54	OK	5280	2026-09-14 02:34	45.83	OK
5281	2026-09-14 02:35	44.58	OK	5282	2026-09-14 02:36	45.73	OK
5283	2026-09-14 02:37	45.76	OK	5284	2026-09-14 02:38	43.31	OK
5285	2026-09-14 02:39	46.14	OK	5286	2026-09-14 02:40	45.87	OK
5287	2026-09-14 02:41	46.59	OK	5288	2026-09-14 02:42	44.80	OK
5289	2026-09-14 02:43	44.49	OK	5290	2026-09-14 02:44	45.37	OK
5291	2026-09-14 02:45	45.09	OK	5292	2026-09-14 02:46	45.18	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5293	2026-09-14 02:47	44.97	OK	5294	2026-09-14 02:48	44.30	OK
5295	2026-09-14 02:49	44.00	OK	5296	2026-09-14 02:50	44.43	OK
5297	2026-09-14 02:51	44.04	OK	5298	2026-09-14 02:52	44.95	OK
5299	2026-09-14 02:53	46.75	OK	5300	2026-09-14 02:54	44.68	OK
5301	2026-09-14 02:55	46.00	OK	5302	2026-09-14 02:56	45.67	OK
5303	2026-09-14 02:57	43.62	OK	5304	2026-09-14 02:58	45.61	OK
5305	2026-09-14 02:59	43.79	OK	5306	2026-09-14 03:00	46.22	OK
5307	2026-09-14 03:01	44.97	OK	5308	2026-09-14 03:02	46.03	OK
5309	2026-09-14 03:03	47.10	OK	5310	2026-09-14 03:04	44.37	OK
5311	2026-09-14 03:05	45.51	OK	5312	2026-09-14 03:06	47.40	OK
5313	2026-09-14 03:07	43.77	OK	5314	2026-09-14 03:08	45.39	OK
5315	2026-09-14 03:09	43.62	OK	5316	2026-09-14 03:10	46.69	OK
5317	2026-09-14 03:11	45.25	OK	5318	2026-09-14 03:12	45.03	OK
5319	2026-09-14 03:13	45.26	OK	5320	2026-09-14 03:14	44.96	OK
5321	2026-09-14 03:15	44.99	OK	5322	2026-09-14 03:16	44.73	OK
5323	2026-09-14 03:17	43.76	OK	5324	2026-09-14 03:18	45.04	OK
5325	2026-09-14 03:19	45.33	OK	5326	2026-09-14 03:20	46.48	OK
5327	2026-09-14 03:21	44.50	OK	5328	2026-09-14 03:22	46.28	OK
5329	2026-09-14 03:23	47.34	OK	5330	2026-09-14 03:24	44.08	OK
5331	2026-09-14 03:25	46.91	OK	5332	2026-09-14 03:26	48.24	OK
5333	2026-09-14 03:27	43.90	OK	5334	2026-09-14 03:28	47.62	OK
5335	2026-09-14 03:29	46.15	OK	5336	2026-09-14 03:30	46.45	OK
5337	2026-09-14 03:31	45.59	OK	5338	2026-09-14 03:32	43.77	OK
5339	2026-09-14 03:33	45.87	OK	5340	2026-09-14 03:34	45.24	OK
5341	2026-09-14 03:35	45.95	OK	5342	2026-09-14 03:36	45.75	OK
5343	2026-09-14 03:37	46.45	OK	5344	2026-09-14 03:38	45.91	OK
5345	2026-09-14 03:39	44.43	OK	5346	2026-09-14 03:40	45.26	OK
5347	2026-09-14 03:41	46.32	OK	5348	2026-09-14 03:42	46.05	OK
5349	2026-09-14 03:43	44.73	OK	5350	2026-09-14 03:44	46.26	OK
5351	2026-09-14 03:45	44.87	OK	5352	2026-09-14 03:46	46.50	OK
5353	2026-09-14 03:47	46.08	OK	5354	2026-09-14 03:48	46.32	OK
5355	2026-09-14 03:49	46.00	OK	5356	2026-09-14 03:50	45.03	OK
5357	2026-09-14 03:51	45.30	OK	5358	2026-09-14 03:52	46.67	OK
5359	2026-09-14 03:53	46.69	OK	5360	2026-09-14 03:54	46.69	OK
5361	2026-09-14 03:55	44.42	OK	5362	2026-09-14 03:56	43.91	OK
5363	2026-09-14 03:57	46.05	OK	5364	2026-09-14 03:58	46.42	OK
5365	2026-09-14 03:59	46.10	OK	5366	2026-09-14 04:00	46.82	OK
5367	2026-09-14 04:01	47.91	OK	5368	2026-09-14 04:02	45.18	OK
5369	2026-09-14 04:03	46.41	OK	5370	2026-09-14 04:04	45.52	OK
5371	2026-09-14 04:05	46.92	OK	5372	2026-09-14 04:06	46.91	OK
5373	2026-09-14 04:07	46.69	OK	5374	2026-09-14 04:08	47.26	OK
5375	2026-09-14 04:09	47.12	OK	5376	2026-09-14 04:10	47.08	OK
5377	2026-09-14 04:11	46.94	OK	5378	2026-09-14 04:12	45.43	OK
5379	2026-09-14 04:13	45.51	OK	5380	2026-09-14 04:14	45.01	OK
5381	2026-09-14 04:15	48.03	OK	5382	2026-09-14 04:16	45.76	OK
5383	2026-09-14 04:17	47.17	OK	5384	2026-09-14 04:18	46.20	OK
5385	2026-09-14 04:19	45.60	OK	5386	2026-09-14 04:20	44.18	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5387	2026-09-14 04:21	45.39	OK	5388	2026-09-14 04:22	47.10	OK
5389	2026-09-14 04:23	46.26	OK	5390	2026-09-14 04:24	45.38	OK
5391	2026-09-14 04:25	46.37	OK	5392	2026-09-14 04:26	46.19	OK
5393	2026-09-14 04:27	47.00	OK	5394	2026-09-14 04:28	47.13	OK
5395	2026-09-14 04:29	47.13	OK	5396	2026-09-14 04:30	46.95	OK
5397	2026-09-14 04:31	46.57	OK	5398	2026-09-14 04:32	45.94	OK
5399	2026-09-14 04:33	45.83	OK	5400	2026-09-14 04:34	47.56	OK
5401	2026-09-14 04:35	44.91	OK	5402	2026-09-14 04:36	46.32	OK
5403	2026-09-14 04:37	45.47	OK	5404	2026-09-14 04:38	47.06	OK
5405	2026-09-14 04:39	47.54	OK	5406	2026-09-14 04:40	47.97	OK
5407	2026-09-14 04:41	46.87	OK	5408	2026-09-14 04:42	45.90	OK
5409	2026-09-14 04:43	47.27	OK	5410	2026-09-14 04:44	44.92	OK
5411	2026-09-14 04:45	45.51	OK	5412	2026-09-14 04:46	44.97	OK
5413	2026-09-14 04:47	47.21	OK	5414	2026-09-14 04:48	46.91	OK
5415	2026-09-14 04:49	48.80	OK	5416	2026-09-14 04:50	44.50	OK
5417	2026-09-14 04:51	46.23	OK	5418	2026-09-14 04:52	46.89	OK
5419	2026-09-14 04:53	45.64	OK	5420	2026-09-14 04:54	46.30	OK
5421	2026-09-14 04:55	45.74	OK	5422	2026-09-14 04:56	45.67	OK
5423	2026-09-14 04:57	45.09	OK	5424	2026-09-14 04:58	45.94	OK
5425	2026-09-14 04:59	46.39	OK	5426	2026-09-14 05:00	45.34	OK
5427	2026-09-14 05:01	45.92	OK	5428	2026-09-14 05:02	46.04	OK
5429	2026-09-14 05:03	45.52	OK	5430	2026-09-14 05:04	46.72	OK
5431	2026-09-14 05:05	46.09	OK	5432	2026-09-14 05:06	46.51	OK
5433	2026-09-14 05:07	45.28	OK	5434	2026-09-14 05:08	47.00	OK
5435	2026-09-14 05:09	45.57	OK	5436	2026-09-14 05:10	47.83	OK
5437	2026-09-14 05:11	48.09	OK	5438	2026-09-14 05:12	48.58	OK
5439	2026-09-14 05:13	46.46	OK	5440	2026-09-14 05:14	47.95	OK
5441	2026-09-14 05:15	48.45	OK	5442	2026-09-14 05:16	48.03	OK
5443	2026-09-14 05:17	47.34	OK	5444	2026-09-14 05:18	48.11	OK
5445	2026-09-14 05:19	47.57	OK	5446	2026-09-14 05:20	45.53	OK
5447	2026-09-14 05:21	46.95	OK	5448	2026-09-14 05:22	46.34	OK
5449	2026-09-14 05:23	47.70	OK	5450	2026-09-14 05:24	47.59	OK
5451	2026-09-14 05:25	47.69	OK	5452	2026-09-14 05:26	45.46	OK
5453	2026-09-14 05:27	46.71	OK	5454	2026-09-14 05:28	46.07	OK
5455	2026-09-14 05:29	47.99	OK	5456	2026-09-14 05:30	47.53	OK
5457	2026-09-14 05:31	48.91	OK	5458	2026-09-14 05:32	47.44	OK
5459	2026-09-14 05:33	46.86	OK	5460	2026-09-14 05:34	47.74	OK
5461	2026-09-14 05:35	47.84	OK	5462	2026-09-14 05:36	47.30	OK
5463	2026-09-14 05:37	45.36	OK	5464	2026-09-14 05:38	44.79	OK
5465	2026-09-14 05:39	46.83	OK	5466	2026-09-14 05:40	47.53	OK
5467	2026-09-14 05:41	46.11	OK	5468	2026-09-14 05:42	46.22	OK
5469	2026-09-14 05:43	47.79	OK	5470	2026-09-14 05:44	46.45	OK
5471	2026-09-14 05:45	46.24	OK	5472	2026-09-14 05:46	47.02	OK
5473	2026-09-14 05:47	47.12	OK	5474	2026-09-14 05:48	46.49	OK
5475	2026-09-14 05:49	45.94	OK	5476	2026-09-14 05:50	45.70	OK
5477	2026-09-14 05:51	47.04	OK	5478	2026-09-14 05:52	47.43	OK
5479	2026-09-14 05:53	46.52	OK	5480	2026-09-14 05:54	47.40	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5481	2026-09-14 05:55	47.48	OK	5482	2026-09-14 05:56	47.41	OK
5483	2026-09-14 05:57	47.51	OK	5484	2026-09-14 05:58	47.72	OK
5485	2026-09-14 05:59	49.40	OK	5486	2026-09-14 06:00	45.90	OK
5487	2026-09-14 06:01	45.91	OK	5488	2026-09-14 06:02	46.36	OK
5489	2026-09-14 06:03	48.33	OK	5490	2026-09-14 06:04	49.36	OK
5491	2026-09-14 06:05	47.38	OK	5492	2026-09-14 06:06	46.70	OK
5493	2026-09-14 06:07	46.39	OK	5494	2026-09-14 06:08	47.60	OK
5495	2026-09-14 06:09	47.27	OK	5496	2026-09-14 06:10	46.08	OK
5497	2026-09-14 06:11	47.39	OK	5498	2026-09-14 06:12	48.03	OK
5499	2026-09-14 06:13	47.94	OK	5500	2026-09-14 06:14	47.41	OK
5501	2026-09-14 06:15	47.75	OK	5502	2026-09-14 06:16	48.34	OK
5503	2026-09-14 06:17	48.37	OK	5504	2026-09-14 06:18	47.22	OK
5505	2026-09-14 06:19	47.40	OK	5506	2026-09-14 06:20	48.26	OK
5507	2026-09-14 06:21	47.76	OK	5508	2026-09-14 06:22	47.74	OK
5509	2026-09-14 06:23	47.74	OK	5510	2026-09-14 06:24	46.87	OK
5511	2026-09-14 06:25	48.11	OK	5512	2026-09-14 06:26	48.27	OK
5513	2026-09-14 06:27	46.90	OK	5514	2026-09-14 06:28	47.95	OK
5515	2026-09-14 06:29	48.72	OK	5516	2026-09-14 06:30	47.53	OK
5517	2026-09-14 06:31	47.44	OK	5518	2026-09-14 06:32	47.27	OK
5519	2026-09-14 06:33	47.82	OK	5520	2026-09-14 06:34	47.98	OK
5521	2026-09-14 06:35	48.82	OK	5522	2026-09-14 06:36	47.29	OK
5523	2026-09-14 06:37	48.82	OK	5524	2026-09-14 06:38	49.78	OK
5525	2026-09-14 06:39	48.38	OK	5526	2026-09-14 06:40	48.50	OK
5527	2026-09-14 06:41	47.39	OK	5528	2026-09-14 06:42	46.97	OK
5529	2026-09-14 06:43	46.22	OK	5530	2026-09-14 06:44	47.28	OK
5531	2026-09-14 06:45	46.74	OK	5532	2026-09-14 06:46	48.04	OK
5533	2026-09-14 06:47	47.09	OK	5534	2026-09-14 06:48	49.47	OK
5535	2026-09-14 06:49	46.96	OK	5536	2026-09-14 06:50	47.40	OK
5537	2026-09-14 06:51	47.23	OK	5538	2026-09-14 06:52	48.56	OK
5539	2026-09-14 06:53	48.53	OK	5540	2026-09-14 06:54	46.57	OK
5541	2026-09-14 06:55	47.03	OK	5542	2026-09-14 06:56	50.58	OK
5543	2026-09-14 06:57	48.30	OK	5544	2026-09-14 06:58	49.03	OK
5545	2026-09-14 06:59	46.36	OK	5546	2026-09-14 07:00	49.00	OK
5547	2026-09-14 07:01	47.03	OK	5548	2026-09-14 07:02	46.38	OK
5549	2026-09-14 07:03	47.42	OK	5550	2026-09-14 07:04	49.49	OK
5551	2026-09-14 07:05	49.46	OK	5552	2026-09-14 07:06	49.33	OK
5553	2026-09-14 07:07	47.24	OK	5554	2026-09-14 07:08	47.61	OK
5555	2026-09-14 07:09	47.78	OK	5556	2026-09-14 07:10	49.16	OK
5557	2026-09-14 07:11	48.05	OK	5558	2026-09-14 07:12	49.93	OK
5559	2026-09-14 07:13	47.93	OK	5560	2026-09-14 07:14	49.45	OK
5561	2026-09-14 07:15	47.42	OK	5562	2026-09-14 07:16	49.17	OK
5563	2026-09-14 07:17	47.81	OK	5564	2026-09-14 07:18	48.72	OK
5565	2026-09-14 07:19	50.32	OK	5566	2026-09-14 07:20	49.15	OK
5567	2026-09-14 07:21	48.87	OK	5568	2026-09-14 07:22	46.64	OK
5569	2026-09-14 07:23	48.96	OK	5570	2026-09-14 07:24	46.96	OK
5571	2026-09-14 07:25	48.81	OK	5572	2026-09-14 07:26	48.28	OK
5573	2026-09-14 07:27	46.78	OK	5574	2026-09-14 07:28	50.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5575	2026-09-14 07:29	49.19	OK	5576	2026-09-14 07:30	46.85	OK
5577	2026-09-14 07:31	48.88	OK	5578	2026-09-14 07:32	48.42	OK
5579	2026-09-14 07:33	48.47	OK	5580	2026-09-14 07:34	46.87	OK
5581	2026-09-14 07:35	49.37	OK	5582	2026-09-14 07:36	48.65	OK
5583	2026-09-14 07:37	49.49	OK	5584	2026-09-14 07:38	49.26	OK
5585	2026-09-14 07:39	49.17	OK	5586	2026-09-14 07:40	48.24	OK
5587	2026-09-14 07:41	46.41	OK	5588	2026-09-14 07:42	48.17	OK
5589	2026-09-14 07:43	47.13	OK	5590	2026-09-14 07:44	49.68	OK
5591	2026-09-14 07:45	46.87	OK	5592	2026-09-14 07:46	49.58	OK
5593	2026-09-14 07:47	49.07	OK	5594	2026-09-14 07:48	49.18	OK
5595	2026-09-14 07:49	47.58	OK	5596	2026-09-14 07:50	49.03	OK
5597	2026-09-14 07:51	48.65	OK	5598	2026-09-14 07:52	47.26	OK
5599	2026-09-14 07:53	47.75	OK	5600	2026-09-14 07:54	48.75	OK
5601	2026-09-14 07:55	48.12	OK	5602	2026-09-14 07:56	50.30	OK
5603	2026-09-14 07:57	48.54	OK	5604	2026-09-14 07:58	49.15	OK
5605	2026-09-14 07:59	50.31	OK	5606	2026-09-14 08:00	49.54	OK
5607	2026-09-14 08:01	49.95	OK	5608	2026-09-14 08:02	48.76	OK
5609	2026-09-14 08:03	49.08	OK	5610	2026-09-14 08:04	48.02	OK
5611	2026-09-14 08:05	49.94	OK	5612	2026-09-14 08:06	49.44	OK
5613	2026-09-14 08:07	49.25	OK	5614	2026-09-14 08:08	48.00	OK
5615	2026-09-14 08:09	47.74	OK	5616	2026-09-14 08:10	49.53	OK
5617	2026-09-14 08:11	49.80	OK	5618	2026-09-14 08:12	47.74	OK
5619	2026-09-14 08:13	49.00	OK	5620	2026-09-14 08:14	48.68	OK
5621	2026-09-14 08:15	49.50	OK	5622	2026-09-14 08:16	50.37	OK
5623	2026-09-14 08:17	47.12	OK	5624	2026-09-14 08:18	49.13	OK
5625	2026-09-14 08:19	48.59	OK	5626	2026-09-14 08:20	49.06	OK
5627	2026-09-14 08:21	48.66	OK	5628	2026-09-14 08:22	49.29	OK
5629	2026-09-14 08:23	49.76	OK	5630	2026-09-14 08:24	48.55	OK
5631	2026-09-14 08:25	51.00	OK	5632	2026-09-14 08:26	51.59	OK
5633	2026-09-14 08:27	48.05	OK	5634	2026-09-14 08:28	49.40	OK
5635	2026-09-14 08:29	50.09	OK	5636	2026-09-14 08:30	50.54	OK
5637	2026-09-14 08:31	49.61	OK	5638	2026-09-14 08:32	49.30	OK
5639	2026-09-14 08:33	50.23	OK	5640	2026-09-14 08:34	48.75	OK
5641	2026-09-14 08:35	48.82	OK	5642	2026-09-14 08:36	48.78	OK
5643	2026-09-14 08:37	50.32	OK	5644	2026-09-14 08:38	47.70	OK
5645	2026-09-14 08:39	48.83	OK	5646	2026-09-14 08:40	49.30	OK
5647	2026-09-14 08:41	48.96	OK	5648	2026-09-14 08:42	49.61	OK
5649	2026-09-14 08:43	50.03	OK	5650	2026-09-14 08:44	49.29	OK
5651	2026-09-14 08:45	50.69	OK	5652	2026-09-14 08:46	49.80	OK
5653	2026-09-14 08:47	49.27	OK	5654	2026-09-14 08:48	51.33	OK
5655	2026-09-14 08:49	49.08	OK	5656	2026-09-14 08:50	48.96	OK
5657	2026-09-14 08:51	50.47	OK	5658	2026-09-14 08:52	48.53	OK
5659	2026-09-14 08:53	50.83	OK	5660	2026-09-14 08:54	51.54	OK
5661	2026-09-14 08:55	50.04	OK	5662	2026-09-14 08:56	49.08	OK
5663	2026-09-14 08:57	49.32	OK	5664	2026-09-14 08:58	50.11	OK
5665	2026-09-14 08:59	52.24	OK	5666	2026-09-14 09:00	50.69	OK
5667	2026-09-14 09:01	50.10	OK	5668	2026-09-14 09:02	50.41	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5669	2026-09-14 09:03	50.58	OK	5670	2026-09-14 09:04	51.18	OK
5671	2026-09-14 09:05	50.06	OK	5672	2026-09-14 09:06	50.85	OK
5673	2026-09-14 09:07	47.98	OK	5674	2026-09-14 09:08	49.95	OK
5675	2026-09-14 09:09	51.31	OK	5676	2026-09-14 09:10	51.22	OK
5677	2026-09-14 09:11	48.73	OK	5678	2026-09-14 09:12	50.72	OK
5679	2026-09-14 09:13	51.30	OK	5680	2026-09-14 09:14	49.30	OK
5681	2026-09-14 09:15	52.08	OK	5682	2026-09-14 09:16	51.43	OK
5683	2026-09-14 09:17	49.21	OK	5684	2026-09-14 09:18	51.03	OK
5685	2026-09-14 09:19	50.64	OK	5686	2026-09-14 09:20	50.27	OK
5687	2026-09-14 09:21	51.58	OK	5688	2026-09-14 09:22	51.28	OK
5689	2026-09-14 09:23	50.30	OK	5690	2026-09-14 09:24	49.52	OK
5691	2026-09-14 09:25	50.03	OK	5692	2026-09-14 09:26	49.35	OK
5693	2026-09-14 09:27	47.89	OK	5694	2026-09-14 09:28	49.52	OK
5695	2026-09-14 09:29	49.77	OK	5696	2026-09-14 09:30	51.81	OK
5697	2026-09-14 09:31	50.51	OK	5698	2026-09-14 09:32	48.98	OK
5699	2026-09-14 09:33	50.51	OK	5700	2026-09-14 09:34	49.38	OK
5701	2026-09-14 09:35	50.39	OK	5702	2026-09-14 09:36	50.37	OK
5703	2026-09-14 09:37	49.60	OK	5704	2026-09-14 09:38	51.36	OK
5705	2026-09-14 09:39	50.07	OK	5706	2026-09-14 09:40	51.16	OK
5707	2026-09-14 09:41	51.22	OK	5708	2026-09-14 09:42	48.68	OK
5709	2026-09-14 09:43	49.25	OK	5710	2026-09-14 09:44	49.32	OK
5711	2026-09-14 09:45	51.17	OK	5712	2026-09-14 09:46	50.27	OK
5713	2026-09-14 09:47	51.56	OK	5714	2026-09-14 09:48	50.06	OK
5715	2026-09-14 09:49	50.33	OK	5716	2026-09-14 09:50	50.27	OK
5717	2026-09-14 09:51	49.44	OK	5718	2026-09-14 09:52	50.88	OK
5719	2026-09-14 09:53	50.65	OK	5720	2026-09-14 09:54	49.91	OK
5721	2026-09-14 09:55	50.95	OK	5722	2026-09-14 09:56	49.23	OK
5723	2026-09-14 09:57	50.68	OK	5724	2026-09-14 09:58	52.27	OK
5725	2026-09-14 09:59	50.05	OK	5726	2026-09-14 10:00	49.61	OK
5727	2026-09-14 10:01	50.77	OK	5728	2026-09-14 10:02	49.08	OK
5729	2026-09-14 10:03	52.16	OK	5730	2026-09-14 10:04	50.36	OK
5731	2026-09-14 10:05	48.66	OK	5732	2026-09-14 10:06	50.46	OK
5733	2026-09-14 10:07	50.97	OK	5734	2026-09-14 10:08	50.46	OK
5735	2026-09-14 10:09	52.05	OK	5736	2026-09-14 10:10	49.06	OK
5737	2026-09-14 10:11	51.84	OK	5738	2026-09-14 10:12	50.38	OK
5739	2026-09-14 10:13	51.59	OK	5740	2026-09-14 10:14	49.69	OK
5741	2026-09-14 10:15	50.72	OK	5742	2026-09-14 10:16	49.25	OK
5743	2026-09-14 10:17	51.19	OK	5744	2026-09-14 10:18	51.60	OK
5745	2026-09-14 10:19	52.46	OK	5746	2026-09-14 10:20	51.67	OK
5747	2026-09-14 10:21	50.15	OK	5748	2026-09-14 10:22	48.89	OK
5749	2026-09-14 10:23	51.97	OK	5750	2026-09-14 10:24	50.52	OK
5751	2026-09-14 10:25	51.24	OK	5752	2026-09-14 10:26	50.74	OK
5753	2026-09-14 10:27	51.74	OK	5754	2026-09-14 10:28	50.67	OK
5755	2026-09-14 10:29	50.99	OK	5756	2026-09-14 10:30	51.55	OK
5757	2026-09-14 10:31	49.46	OK	5758	2026-09-14 10:32	50.60	OK
5759	2026-09-14 10:33	51.16	OK	5760	2026-09-14 10:34	51.48	OK
5761	2026-09-14 10:35	52.20	OK	5762	2026-09-14 10:36	50.65	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5763	2026-09-14 10:37	50.27	OK	5764	2026-09-14 10:38	49.05	OK
5765	2026-09-14 10:39	50.41	OK	5766	2026-09-14 10:40	48.99	OK
5767	2026-09-14 10:41	51.17	OK	5768	2026-09-14 10:42	50.20	OK
5769	2026-09-14 10:43	51.36	OK	5770	2026-09-14 10:44	50.46	OK
5771	2026-09-14 10:45	51.54	OK	5772	2026-09-14 10:46	50.19	OK
5773	2026-09-14 10:47	50.83	OK	5774	2026-09-14 10:48	52.17	OK
5775	2026-09-14 10:49	51.53	OK	5776	2026-09-14 10:50	50.53	OK
5777	2026-09-14 10:51	51.36	OK	5778	2026-09-14 10:52	52.16	OK
5779	2026-09-14 10:53	51.49	OK	5780	2026-09-14 10:54	52.79	OK
5781	2026-09-14 10:55	50.64	OK	5782	2026-09-14 10:56	51.99	OK
5783	2026-09-14 10:57	51.31	OK	5784	2026-09-14 10:58	52.30	OK
5785	2026-09-14 10:59	51.57	OK	5786	2026-09-14 11:00	53.38	OK
5787	2026-09-14 11:01	50.72	OK	5788	2026-09-14 11:02	52.22	OK
5789	2026-09-14 11:03	50.42	OK	5790	2026-09-14 11:04	52.43	OK
5791	2026-09-14 11:05	50.22	OK	5792	2026-09-14 11:06	52.59	OK
5793	2026-09-14 11:07	52.62	OK	5794	2026-09-14 11:08	53.75	OK
5795	2026-09-14 11:09	50.69	OK	5796	2026-09-14 11:10	53.39	OK
5797	2026-09-14 11:11	50.84	OK	5798	2026-09-14 11:12	51.46	OK
5799	2026-09-14 11:13	53.06	OK	5800	2026-09-14 11:14	51.65	OK
5801	2026-09-14 11:15	51.58	OK	5802	2026-09-14 11:16	51.27	OK
5803	2026-09-14 11:17	50.71	OK	5804	2026-09-14 11:18	52.12	OK
5805	2026-09-14 11:19	50.56	OK	5806	2026-09-14 11:20	52.55	OK
5807	2026-09-14 11:21	50.51	OK	5808	2026-09-14 11:22	52.43	OK
5809	2026-09-14 11:23	51.86	OK	5810	2026-09-14 11:24	49.66	OK
5811	2026-09-14 11:25	52.96	OK	5812	2026-09-14 11:26	50.48	OK
5813	2026-09-14 11:27	52.69	OK	5814	2026-09-14 11:28	50.93	OK
5815	2026-09-14 11:29	51.90	OK	5816	2026-09-14 11:30	50.04	OK
5817	2026-09-14 11:31	51.43	OK	5818	2026-09-14 11:32	51.55	OK
5819	2026-09-14 11:33	51.71	OK	5820	2026-09-14 11:34	51.10	OK
5821	2026-09-14 11:35	52.35	OK	5822	2026-09-14 11:36	53.14	OK
5823	2026-09-14 11:37	50.67	OK	5824	2026-09-14 11:38	50.48	OK
5825	2026-09-14 11:39	52.43	OK	5826	2026-09-14 11:40	51.44	OK
5827	2026-09-14 11:41	49.80	OK	5828	2026-09-14 11:42	50.85	OK
5829	2026-09-14 11:43	51.99	OK	5830	2026-09-14 11:44	52.28	OK
5831	2026-09-14 11:45	52.26	OK	5832	2026-09-14 11:46	51.28	OK
5833	2026-09-14 11:47	49.93	OK	5834	2026-09-14 11:48	50.23	OK
5835	2026-09-14 11:49	50.11	OK	5836	2026-09-14 11:50	52.04	OK
5837	2026-09-14 11:51	50.85	OK	5838	2026-09-14 11:52	51.28	OK
5839	2026-09-14 11:53	52.02	OK	5840	2026-09-14 11:54	50.93	OK
5841	2026-09-14 11:55	51.95	OK	5842	2026-09-14 11:56	52.30	OK
5843	2026-09-14 11:57	51.24	OK	5844	2026-09-14 11:58	50.21	OK
5845	2026-09-14 11:59	50.72	OK	5846	2026-09-14 12:00	52.29	OK
5847	2026-09-14 12:01	52.10	OK	5848	2026-09-14 12:02	51.95	OK
5849	2026-09-14 12:03	50.80	OK	5850	2026-09-14 12:04	51.58	OK
5851	2026-09-14 12:05	52.53	OK	5852	2026-09-14 12:06	52.37	OK
5853	2026-09-14 12:07	51.39	OK	5854	2026-09-14 12:08	52.40	OK
5855	2026-09-14 12:09	51.95	OK	5856	2026-09-14 12:10	50.11	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5857	2026-09-14 12:11	52.51	OK	5858	2026-09-14 12:12	52.57	OK
5859	2026-09-14 12:13	51.86	OK	5860	2026-09-14 12:14	51.10	OK
5861	2026-09-14 12:15	51.49	OK	5862	2026-09-14 12:16	51.78	OK
5863	2026-09-14 12:17	52.68	OK	5864	2026-09-14 12:18	52.56	OK
5865	2026-09-14 12:19	53.55	OK	5866	2026-09-14 12:20	52.53	OK
5867	2026-09-14 12:21	51.90	OK	5868	2026-09-14 12:22	51.68	OK
5869	2026-09-14 12:23	51.28	OK	5870	2026-09-14 12:24	51.88	OK
5871	2026-09-14 12:25	53.43	OK	5872	2026-09-14 12:26	52.75	OK
5873	2026-09-14 12:27	51.27	OK	5874	2026-09-14 12:28	50.82	OK
5875	2026-09-14 12:29	52.97	OK	5876	2026-09-14 12:30	52.49	OK
5877	2026-09-14 12:31	52.36	OK	5878	2026-09-14 12:32	51.13	OK
5879	2026-09-14 12:33	51.25	OK	5880	2026-09-14 12:34	49.69	OK
5881	2026-09-14 12:35	52.82	OK	5882	2026-09-14 12:36	51.71	OK
5883	2026-09-14 12:37	52.05	OK	5884	2026-09-14 12:38	53.24	OK
5885	2026-09-14 12:39	51.84	OK	5886	2026-09-14 12:40	51.23	OK
5887	2026-09-14 12:41	50.90	OK	5888	2026-09-14 12:42	51.00	OK
5889	2026-09-14 12:43	53.15	OK	5890	2026-09-14 12:44	52.47	OK
5891	2026-09-14 12:45	51.04	OK	5892	2026-09-14 12:46	50.26	OK
5893	2026-09-14 12:47	51.15	OK	5894	2026-09-14 12:48	52.01	OK
5895	2026-09-14 12:49	50.73	OK	5896	2026-09-14 12:50	51.03	OK
5897	2026-09-14 12:51	51.31	OK	5898	2026-09-14 12:52	52.77	OK
5899	2026-09-14 12:53	51.24	OK	5900	2026-09-14 12:54	50.66	OK
5901	2026-09-14 12:55	49.20	OK	5902	2026-09-14 12:56	52.95	OK
5903	2026-09-14 12:57	53.12	OK	5904	2026-09-14 12:58	51.00	OK
5905	2026-09-14 12:59	51.72	OK	5906	2026-09-14 13:00	51.60	OK
5907	2026-09-14 13:01	51.35	OK	5908	2026-09-14 13:02	51.00	OK
5909	2026-09-14 13:03	53.46	OK	5910	2026-09-14 13:04	52.18	OK
5911	2026-09-14 13:05	52.38	OK	5912	2026-09-14 13:06	50.13	OK
5913	2026-09-14 13:07	52.78	OK	5914	2026-09-14 13:08	52.45	OK
5915	2026-09-14 13:09	50.75	OK	5916	2026-09-14 13:10	49.24	OK
5917	2026-09-14 13:11	50.04	OK	5918	2026-09-14 13:12	52.60	OK
5919	2026-09-14 13:13	52.40	OK	5920	2026-09-14 13:14	51.55	OK
5921	2026-09-14 13:15	52.32	OK	5922	2026-09-14 13:16	52.12	OK
5923	2026-09-14 13:17	51.83	OK	5924	2026-09-14 13:18	50.49	OK
5925	2026-09-14 13:19	51.45	OK	5926	2026-09-14 13:20	52.61	OK
5927	2026-09-14 13:21	50.84	OK	5928	2026-09-14 13:22	52.48	OK
5929	2026-09-14 13:23	51.76	OK	5930	2026-09-14 13:24	50.65	OK
5931	2026-09-14 13:25	50.84	OK	5932	2026-09-14 13:26	51.56	OK
5933	2026-09-14 13:27	52.45	OK	5934	2026-09-14 13:28	51.88	OK
5935	2026-09-14 13:29	50.49	OK	5936	2026-09-14 13:30	51.61	OK
5937	2026-09-14 13:31	51.30	OK	5938	2026-09-14 13:32	51.73	OK
5939	2026-09-14 13:33	52.13	OK	5940	2026-09-14 13:34	52.00	OK
5941	2026-09-14 13:35	52.10	OK	5942	2026-09-14 13:36	50.69	OK
5943	2026-09-14 13:37	52.74	OK	5944	2026-09-14 13:38	52.76	OK
5945	2026-09-14 13:39	50.03	OK	5946	2026-09-14 13:40	52.38	OK
5947	2026-09-14 13:41	53.66	OK	5948	2026-09-14 13:42	50.23	OK
5949	2026-09-14 13:43	51.39	OK	5950	2026-09-14 13:44	50.92	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5951	2026-09-14 13:45	52.20	OK	5952	2026-09-14 13:46	51.69	OK
5953	2026-09-14 13:47	53.10	OK	5954	2026-09-14 13:48	51.60	OK
5955	2026-09-14 13:49	52.32	OK	5956	2026-09-14 13:50	50.51	OK
5957	2026-09-14 13:51	51.76	OK	5958	2026-09-14 13:52	52.13	OK
5959	2026-09-14 13:53	50.28	OK	5960	2026-09-14 13:54	54.14	OK
5961	2026-09-14 13:55	53.62	OK	5962	2026-09-14 13:56	50.35	OK
5963	2026-09-14 13:57	50.64	OK	5964	2026-09-14 13:58	52.73	OK
5965	2026-09-14 13:59	53.61	OK	5966	2026-09-14 14:00	52.26	OK
5967	2026-09-14 14:01	52.04	OK	5968	2026-09-14 14:02	51.03	OK
5969	2026-09-14 14:03	52.04	OK	5970	2026-09-14 14:04	53.96	OK
5971	2026-09-14 14:05	50.80	OK	5972	2026-09-14 14:06	52.64	OK
5973	2026-09-14 14:07	51.28	OK	5974	2026-09-14 14:08	53.11	OK
5975	2026-09-14 14:09	52.00	OK	5976	2026-09-14 14:10	51.08	OK
5977	2026-09-14 14:11	52.30	OK	5978	2026-09-14 14:12	52.38	OK
5979	2026-09-14 14:13	51.11	OK	5980	2026-09-14 14:14	50.21	OK
5981	2026-09-14 14:15	52.57	OK	5982	2026-09-14 14:16	53.91	OK
5983	2026-09-14 14:17	51.20	OK	5984	2026-09-14 14:18	51.24	OK
5985	2026-09-14 14:19	51.55	OK	5986	2026-09-14 14:20	52.82	OK
5987	2026-09-14 14:21	51.75	OK	5988	2026-09-14 14:22	52.19	OK
5989	2026-09-14 14:23	52.23	OK	5990	2026-09-14 14:24	52.31	OK
5991	2026-09-14 14:25	52.43	OK	5992	2026-09-14 14:26	51.68	OK
5993	2026-09-14 14:27	51.19	OK	5994	2026-09-14 14:28	51.74	OK
5995	2026-09-14 14:29	50.54	OK	5996	2026-09-14 14:30	51.14	OK
5997	2026-09-14 14:31	50.51	OK	5998	2026-09-14 14:32	52.23	OK
5999	2026-09-14 14:33	52.96	OK	6000	2026-09-14 14:34	49.55	OK
6001	2026-09-14 14:35	51.24	OK	6002	2026-09-14 14:36	51.09	OK
6003	2026-09-14 14:37	50.34	OK	6004	2026-09-14 14:38	51.74	OK
6005	2026-09-14 14:39	52.40	OK	6006	2026-09-14 14:40	51.82	OK
6007	2026-09-14 14:41	53.48	OK	6008	2026-09-14 14:42	50.79	OK
6009	2026-09-14 14:43	51.76	OK	6010	2026-09-14 14:44	52.02	OK
6011	2026-09-14 14:45	50.50	OK	6012	2026-09-14 14:46	52.71	OK
6013	2026-09-14 14:47	50.87	OK	6014	2026-09-14 14:48	52.75	OK
6015	2026-09-14 14:49	53.03	OK	6016	2026-09-14 14:50	52.53	OK
6017	2026-09-14 14:51	50.62	OK	6018	2026-09-14 14:52	50.44	OK
6019	2026-09-14 14:53	51.11	OK	6020	2026-09-14 14:54	51.08	OK
6021	2026-09-14 14:55	49.70	OK	6022	2026-09-14 14:56	50.51	OK
6023	2026-09-14 14:57	50.80	OK	6024	2026-09-14 14:58	51.07	OK
6025	2026-09-14 14:59	50.76	OK	6026	2026-09-14 15:00	51.25	OK
6027	2026-09-14 15:01	51.67	OK	6028	2026-09-14 15:02	52.12	OK
6029	2026-09-14 15:03	52.54	OK	6030	2026-09-14 15:04	52.85	OK
6031	2026-09-14 15:05	51.47	OK	6032	2026-09-14 15:06	51.76	OK
6033	2026-09-14 15:07	50.46	OK	6034	2026-09-14 15:08	49.70	OK
6035	2026-09-14 15:09	51.96	OK	6036	2026-09-14 15:10	52.75	OK
6037	2026-09-14 15:11	51.09	OK	6038	2026-09-14 15:12	49.48	OK
6039	2026-09-14 15:13	51.99	OK	6040	2026-09-14 15:14	51.02	OK
6041	2026-09-14 15:15	51.65	OK	6042	2026-09-14 15:16	50.65	OK
6043	2026-09-14 15:17	51.53	OK	6044	2026-09-14 15:18	51.68	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6045	2026-09-14 15:19	52.16	OK	6046	2026-09-14 15:20	52.15	OK
6047	2026-09-14 15:21	50.94	OK	6048	2026-09-14 15:22	50.50	OK
6049	2026-09-14 15:23	52.23	OK	6050	2026-09-14 15:24	50.77	OK
6051	2026-09-14 15:25	52.40	OK	6052	2026-09-14 15:26	51.36	OK
6053	2026-09-14 15:27	50.94	OK	6054	2026-09-14 15:28	50.47	OK
6055	2026-09-14 15:29	50.44	OK	6056	2026-09-14 15:30	52.02	OK
6057	2026-09-14 15:31	51.41	OK	6058	2026-09-14 15:32	50.87	OK
6059	2026-09-14 15:33	49.62	OK	6060	2026-09-14 15:34	49.88	OK
6061	2026-09-14 15:35	52.86	OK	6062	2026-09-14 15:36	52.10	OK
6063	2026-09-14 15:37	52.33	OK	6064	2026-09-14 15:38	51.05	OK
6065	2026-09-14 15:39	52.22	OK	6066	2026-09-14 15:40	51.55	OK
6067	2026-09-14 15:41	51.43	OK	6068	2026-09-14 15:42	49.85	OK
6069	2026-09-14 15:43	51.64	OK	6070	2026-09-14 15:44	51.50	OK
6071	2026-09-14 15:45	53.17	OK	6072	2026-09-14 15:46	52.13	OK
6073	2026-09-14 15:47	53.31	OK	6074	2026-09-14 15:48	52.39	OK
6075	2026-09-14 15:49	50.37	OK	6076	2026-09-14 15:50	49.41	OK
6077	2026-09-14 15:51	52.03	OK	6078	2026-09-14 15:52	50.74	OK
6079	2026-09-14 15:53	49.32	OK	6080	2026-09-14 15:54	51.65	OK
6081	2026-09-14 15:55	51.62	OK	6082	2026-09-14 15:56	51.53	OK
6083	2026-09-14 15:57	51.11	OK	6084	2026-09-14 15:58	52.27	OK
6085	2026-09-14 15:59	51.80	OK	6086	2026-09-14 16:00	52.57	OK
6087	2026-09-14 16:01	51.71	OK	6088	2026-09-14 16:02	52.39	OK
6089	2026-09-14 16:03	51.09	OK	6090	2026-09-14 16:04	51.16	OK
6091	2026-09-14 16:05	53.00	OK	6092	2026-09-14 16:06	51.11	OK
6093	2026-09-14 16:07	49.89	OK	6094	2026-09-14 16:08	51.93	OK
6095	2026-09-14 16:09	52.44	OK	6096	2026-09-14 16:10	52.67	OK
6097	2026-09-14 16:11	48.60	OK	6098	2026-09-14 16:12	51.90	OK
6099	2026-09-14 16:13	51.16	OK	6100	2026-09-14 16:14	51.53	OK
6101	2026-09-14 16:15	51.01	OK	6102	2026-09-14 16:16	51.34	OK
6103	2026-09-14 16:17	51.70	OK	6104	2026-09-14 16:18	52.33	OK
6105	2026-09-14 16:19	52.48	OK	6106	2026-09-14 16:20	49.21	OK
6107	2026-09-14 16:21	50.67	OK	6108	2026-09-14 16:22	51.53	OK
6109	2026-09-14 16:23	50.17	OK	6110	2026-09-14 16:24	50.88	OK
6111	2026-09-14 16:25	50.20	OK	6112	2026-09-14 16:26	49.53	OK
6113	2026-09-14 16:27	49.69	OK	6114	2026-09-14 16:28	49.47	OK
6115	2026-09-14 16:29	49.25	OK	6116	2026-09-14 16:30	49.41	OK
6117	2026-09-14 16:31	49.73	OK	6118	2026-09-14 16:32	50.38	OK
6119	2026-09-14 16:33	50.94	OK	6120	2026-09-14 16:34	50.94	OK
6121	2026-09-14 16:35	50.08	OK	6122	2026-09-14 16:36	49.71	OK
6123	2026-09-14 16:37	50.14	OK	6124	2026-09-14 16:38	49.81	OK
6125	2026-09-14 16:39	48.72	OK	6126	2026-09-14 16:40	48.67	OK
6127	2026-09-14 16:41	51.68	OK	6128	2026-09-14 16:42	52.15	OK
6129	2026-09-14 16:43	52.13	OK	6130	2026-09-14 16:44	49.04	OK
6131	2026-09-14 16:45	50.55	OK	6132	2026-09-14 16:46	52.09	OK
6133	2026-09-14 16:47	50.56	OK	6134	2026-09-14 16:48	52.45	OK
6135	2026-09-14 16:49	49.83	OK	6136	2026-09-14 16:50	51.54	OK
6137	2026-09-14 16:51	50.54	OK	6138	2026-09-14 16:52	51.27	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6139	2026-09-14 16:53	51.11	OK	6140	2026-09-14 16:54	50.40	OK
6141	2026-09-14 16:55	49.63	OK	6142	2026-09-14 16:56	50.63	OK
6143	2026-09-14 16:57	49.05	OK	6144	2026-09-14 16:58	50.14	OK
6145	2026-09-14 16:59	50.62	OK	6146	2026-09-14 17:00	51.19	OK
6147	2026-09-14 17:01	49.74	OK	6148	2026-09-14 17:02	51.72	OK
6149	2026-09-14 17:03	50.99	OK	6150	2026-09-14 17:04	49.49	OK
6151	2026-09-14 17:05	50.50	OK	6152	2026-09-14 17:06	49.13	OK
6153	2026-09-14 17:07	49.73	OK	6154	2026-09-14 17:08	51.03	OK
6155	2026-09-14 17:09	51.93	OK	6156	2026-09-14 17:10	50.41	OK
6157	2026-09-14 17:11	50.76	OK	6158	2026-09-14 17:12	51.44	OK
6159	2026-09-14 17:13	50.35	OK	6160	2026-09-14 17:14	49.87	OK
6161	2026-09-14 17:15	49.33	OK	6162	2026-09-14 17:16	50.30	OK
6163	2026-09-14 17:17	50.52	OK	6164	2026-09-14 17:18	50.68	OK
6165	2026-09-14 17:19	51.56	OK	6166	2026-09-14 17:20	50.20	OK
6167	2026-09-14 17:21	51.71	OK	6168	2026-09-14 17:22	49.67	OK
6169	2026-09-14 17:23	50.39	OK	6170	2026-09-14 17:24	50.25	OK
6171	2026-09-14 17:25	49.34	OK	6172	2026-09-14 17:26	49.71	OK
6173	2026-09-14 17:27	50.17	OK	6174	2026-09-14 17:28	50.90	OK
6175	2026-09-14 17:29	51.23	OK	6176	2026-09-14 17:30	50.17	OK
6177	2026-09-14 17:31	49.07	OK	6178	2026-09-14 17:32	51.33	OK
6179	2026-09-14 17:33	51.22	OK	6180	2026-09-14 17:34	50.31	OK
6181	2026-09-14 17:35	50.44	OK	6182	2026-09-14 17:36	48.81	OK
6183	2026-09-14 17:37	50.09	OK	6184	2026-09-14 17:38	50.57	OK
6185	2026-09-14 17:39	51.74	OK	6186	2026-09-14 17:40	50.38	OK
6187	2026-09-14 17:41	50.19	OK	6188	2026-09-14 17:42	50.52	OK
6189	2026-09-14 17:43	48.49	OK	6190	2026-09-14 17:44	49.66	OK
6191	2026-09-14 17:45	49.35	OK	6192	2026-09-14 17:46	50.02	OK
6193	2026-09-14 17:47	51.02	OK	6194	2026-09-14 17:48	50.08	OK
6195	2026-09-14 17:49	50.21	OK	6196	2026-09-14 17:50	50.47	OK
6197	2026-09-14 17:51	48.33	OK	6198	2026-09-14 17:52	49.11	OK
6199	2026-09-14 17:53	49.32	OK	6200	2026-09-14 17:54	49.64	OK
6201	2026-09-14 17:55	49.14	OK	6202	2026-09-14 17:56	51.24	OK
6203	2026-09-14 17:57	51.13	OK	6204	2026-09-14 17:58	49.66	OK
6205	2026-09-14 17:59	49.38	OK	6206	2026-09-14 18:00	49.69	OK
6207	2026-09-14 18:01	51.16	OK	6208	2026-09-14 18:02	49.86	OK
6209	2026-09-14 18:03	48.04	OK	6210	2026-09-14 18:04	48.07	OK
6211	2026-09-14 18:05	48.97	OK	6212	2026-09-14 18:06	50.05	OK
6213	2026-09-14 18:07	49.06	OK	6214	2026-09-14 18:08	49.17	OK
6215	2026-09-14 18:09	48.50	OK	6216	2026-09-14 18:10	49.97	OK
6217	2026-09-14 18:11	49.67	OK	6218	2026-09-14 18:12	50.17	OK
6219	2026-09-14 18:13	49.52	OK	6220	2026-09-14 18:14	49.28	OK
6221	2026-09-14 18:15	51.73	OK	6222	2026-09-14 18:16	49.40	OK
6223	2026-09-14 18:17	49.11	OK	6224	2026-09-14 18:18	50.36	OK
6225	2026-09-14 18:19	49.53	OK	6226	2026-09-14 18:20	48.82	OK
6227	2026-09-14 18:21	50.22	OK	6228	2026-09-14 18:22	49.34	OK
6229	2026-09-14 18:23	48.32	OK	6230	2026-09-14 18:24	48.76	OK
6231	2026-09-14 18:25	47.74	OK	6232	2026-09-14 18:26	48.49	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6233	2026-09-14 18:27	49.52	OK	6234	2026-09-14 18:28	48.57	OK
6235	2026-09-14 18:29	48.34	OK	6236	2026-09-14 18:30	49.13	OK
6237	2026-09-14 18:31	48.24	OK	6238	2026-09-14 18:32	47.93	OK
6239	2026-09-14 18:33	48.33	OK	6240	2026-09-14 18:34	49.69	OK
6241	2026-09-14 18:35	49.06	OK	6242	2026-09-14 18:36	49.44	OK
6243	2026-09-14 18:37	48.87	OK	6244	2026-09-14 18:38	47.18	OK
6245	2026-09-14 18:39	50.64	OK	6246	2026-09-14 18:40	49.13	OK
6247	2026-09-14 18:41	49.88	OK	6248	2026-09-14 18:42	48.21	OK
6249	2026-09-14 18:43	50.20	OK	6250	2026-09-14 18:44	49.77	OK
6251	2026-09-14 18:45	48.44	OK	6252	2026-09-14 18:46	49.32	OK
6253	2026-09-14 18:47	47.14	OK	6254	2026-09-14 18:48	48.75	OK
6255	2026-09-14 18:49	50.56	OK	6256	2026-09-14 18:50	49.32	OK
6257	2026-09-14 18:51	48.92	OK	6258	2026-09-14 18:52	49.56	OK
6259	2026-09-14 18:53	48.99	OK	6260	2026-09-14 18:54	49.81	OK
6261	2026-09-14 18:55	48.27	OK	6262	2026-09-14 18:56	48.83	OK
6263	2026-09-14 18:57	49.11	OK	6264	2026-09-14 18:58	49.61	OK
6265	2026-09-14 18:59	48.62	OK	6266	2026-09-14 19:00	50.81	OK
6267	2026-09-14 19:01	50.02	OK	6268	2026-09-14 19:02	48.65	OK
6269	2026-09-14 19:03	49.07	OK	6270	2026-09-14 19:04	49.63	OK
6271	2026-09-14 19:05	49.51	OK	6272	2026-09-14 19:06	48.36	OK
6273	2026-09-14 19:07	48.94	OK	6274	2026-09-14 19:08	48.38	OK
6275	2026-09-14 19:09	50.31	OK	6276	2026-09-14 19:10	47.63	OK
6277	2026-09-14 19:11	49.25	OK	6278	2026-09-14 19:12	48.63	OK
6279	2026-09-14 19:13	49.84	OK	6280	2026-09-14 19:14	48.48	OK
6281	2026-09-14 19:15	47.45	OK	6282	2026-09-14 19:16	46.25	OK
6283	2026-09-14 19:17	46.93	OK	6284	2026-09-14 19:18	47.88	OK
6285	2026-09-14 19:19	50.99	OK	6286	2026-09-14 19:20	47.60	OK
6287	2026-09-14 19:21	48.26	OK	6288	2026-09-14 19:22	49.31	OK
6289	2026-09-14 19:23	49.52	OK	6290	2026-09-14 19:24	48.36	OK
6291	2026-09-14 19:25	49.17	OK	6292	2026-09-14 19:26	47.22	OK
6293	2026-09-14 19:27	48.59	OK	6294	2026-09-14 19:28	46.94	OK
6295	2026-09-14 19:29	48.21	OK	6296	2026-09-14 19:30	46.62	OK
6297	2026-09-14 19:31	50.14	OK	6298	2026-09-14 19:32	48.06	OK
6299	2026-09-14 19:33	49.13	OK	6300	2026-09-14 19:34	48.81	OK
6301	2026-09-14 19:35	47.96	OK	6302	2026-09-14 19:36	49.42	OK
6303	2026-09-14 19:37	48.98	OK	6304	2026-09-14 19:38	49.82	OK
6305	2026-09-14 19:39	49.36	OK	6306	2026-09-14 19:40	51.03	OK
6307	2026-09-14 19:41	49.64	OK	6308	2026-09-14 19:42	47.52	OK
6309	2026-09-14 19:43	48.35	OK	6310	2026-09-14 19:44	48.75	OK
6311	2026-09-14 19:45	47.61	OK	6312	2026-09-14 19:46	49.61	OK
6313	2026-09-14 19:47	47.14	OK	6314	2026-09-14 19:48	47.65	OK
6315	2026-09-14 19:49	48.57	OK	6316	2026-09-14 19:50	47.52	OK
6317	2026-09-14 19:51	48.32	OK	6318	2026-09-14 19:52	48.22	OK
6319	2026-09-14 19:53	48.40	OK	6320	2026-09-14 19:54	46.63	OK
6321	2026-09-14 19:55	48.18	OK	6322	2026-09-14 19:56	45.41	OK
6323	2026-09-14 19:57	48.18	OK	6324	2026-09-14 19:58	47.61	OK
6325	2026-09-14 19:59	48.70	OK	6326	2026-09-14 20:00	48.84	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6327	2026-09-14 20:01	48.14	OK	6328	2026-09-14 20:02	47.96	OK
6329	2026-09-14 20:03	48.08	OK	6330	2026-09-14 20:04	49.17	OK
6331	2026-09-14 20:05	49.70	OK	6332	2026-09-14 20:06	49.17	OK
6333	2026-09-14 20:07	48.34	OK	6334	2026-09-14 20:08	46.32	OK
6335	2026-09-14 20:09	49.13	OK	6336	2026-09-14 20:10	48.67	OK
6337	2026-09-14 20:11	46.53	OK	6338	2026-09-14 20:12	49.05	OK
6339	2026-09-14 20:13	48.66	OK	6340	2026-09-14 20:14	48.12	OK
6341	2026-09-14 20:15	46.99	OK	6342	2026-09-14 20:16	47.77	OK
6343	2026-09-14 20:17	47.47	OK	6344	2026-09-14 20:18	48.24	OK
6345	2026-09-14 20:19	47.92	OK	6346	2026-09-14 20:20	48.63	OK
6347	2026-09-14 20:21	46.42	OK	6348	2026-09-14 20:22	46.55	OK
6349	2026-09-14 20:23	47.26	OK	6350	2026-09-14 20:24	47.53	OK
6351	2026-09-14 20:25	47.26	OK	6352	2026-09-14 20:26	47.19	OK
6353	2026-09-14 20:27	47.18	OK	6354	2026-09-14 20:28	45.65	OK
6355	2026-09-14 20:29	46.94	OK	6356	2026-09-14 20:30	49.29	OK
6357	2026-09-14 20:31	47.87	OK	6358	2026-09-14 20:32	46.28	OK
6359	2026-09-14 20:33	47.33	OK	6360	2026-09-14 20:34	48.85	OK
6361	2026-09-14 20:35	49.22	OK	6362	2026-09-14 20:36	46.65	OK
6363	2026-09-14 20:37	48.51	OK	6364	2026-09-14 20:38	47.89	OK
6365	2026-09-14 20:39	47.23	OK	6366	2026-09-14 20:40	48.12	OK
6367	2026-09-14 20:41	46.53	OK	6368	2026-09-14 20:42	47.39	OK
6369	2026-09-14 20:43	46.51	OK	6370	2026-09-14 20:44	46.54	OK
6371	2026-09-14 20:45	47.85	OK	6372	2026-09-14 20:46	48.61	OK
6373	2026-09-14 20:47	45.96	OK	6374	2026-09-14 20:48	46.34	OK
6375	2026-09-14 20:49	46.85	OK	6376	2026-09-14 20:50	48.44	OK
6377	2026-09-14 20:51	46.33	OK	6378	2026-09-14 20:52	47.09	OK
6379	2026-09-14 20:53	47.76	OK	6380	2026-09-14 20:54	46.73	OK
6381	2026-09-14 20:55	47.74	OK	6382	2026-09-14 20:56	47.00	OK
6383	2026-09-14 20:57	49.11	OK	6384	2026-09-14 20:58	46.74	OK
6385	2026-09-14 20:59	47.50	OK	6386	2026-09-14 21:00	45.39	OK
6387	2026-09-14 21:01	46.25	OK	6388	2026-09-14 21:02	49.50	OK
6389	2026-09-14 21:03	49.48	OK	6390	2026-09-14 21:04	47.42	OK
6391	2026-09-14 21:05	48.43	OK	6392	2026-09-14 21:06	48.10	OK
6393	2026-09-14 21:07	47.89	OK	6394	2026-09-14 21:08	48.07	OK
6395	2026-09-14 21:09	46.77	OK	6396	2026-09-14 21:10	46.39	OK
6397	2026-09-14 21:11	45.84	OK	6398	2026-09-14 21:12	46.62	OK
6399	2026-09-14 21:13	45.09	OK	6400	2026-09-14 21:14	46.81	OK
6401	2026-09-14 21:15	49.19	OK	6402	2026-09-14 21:16	47.04	OK
6403	2026-09-14 21:17	45.17	OK	6404	2026-09-14 21:18	45.79	OK
6405	2026-09-14 21:19	47.20	OK	6406	2026-09-14 21:20	47.81	OK
6407	2026-09-14 21:21	47.86	OK	6408	2026-09-14 21:22	45.42	OK
6409	2026-09-14 21:23	47.00	OK	6410	2026-09-14 21:24	47.96	OK
6411	2026-09-14 21:25	46.56	OK	6412	2026-09-14 21:26	47.33	OK
6413	2026-09-14 21:27	47.66	OK	6414	2026-09-14 21:28	46.14	OK
6415	2026-09-14 21:29	48.37	OK	6416	2026-09-14 21:30	46.21	OK
6417	2026-09-14 21:31	46.37	OK	6418	2026-09-14 21:32	45.44	OK
6419	2026-09-14 21:33	46.14	OK	6420	2026-09-14 21:34	46.28	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6421	2026-09-14 21:35	45.60	OK	6422	2026-09-14 21:36	46.03	OK
6423	2026-09-14 21:37	47.89	OK	6424	2026-09-14 21:38	45.69	OK
6425	2026-09-14 21:39	47.01	OK	6426	2026-09-14 21:40	46.08	OK
6427	2026-09-14 21:41	45.97	OK	6428	2026-09-14 21:42	45.59	OK
6429	2026-09-14 21:43	46.75	OK	6430	2026-09-14 21:44	47.52	OK
6431	2026-09-14 21:45	47.37	OK	6432	2026-09-14 21:46	47.40	OK
6433	2026-09-14 21:47	46.32	OK	6434	2026-09-14 21:48	45.59	OK
6435	2026-09-14 21:49	47.70	OK	6436	2026-09-14 21:50	46.19	OK
6437	2026-09-14 21:51	46.67	OK	6438	2026-09-14 21:52	46.19	OK
6439	2026-09-14 21:53	46.20	OK	6440	2026-09-14 21:54	46.45	OK
6441	2026-09-14 21:55	45.63	OK	6442	2026-09-14 21:56	45.17	OK
6443	2026-09-14 21:57	44.95	OK	6444	2026-09-14 21:58	45.46	OK
6445	2026-09-14 21:59	46.90	OK	6446	2026-09-14 22:00	47.50	OK
6447	2026-09-14 22:01	47.71	OK	6448	2026-09-14 22:02	44.49	OK
6449	2026-09-14 22:03	45.57	OK	6450	2026-09-14 22:04	46.46	OK
6451	2026-09-14 22:05	45.80	OK	6452	2026-09-14 22:06	45.67	OK
6453	2026-09-14 22:07	44.31	OK	6454	2026-09-14 22:08	46.20	OK
6455	2026-09-14 22:09	46.20	OK	6456	2026-09-14 22:10	47.62	OK
6457	2026-09-14 22:11	45.68	OK	6458	2026-09-14 22:12	46.80	OK
6459	2026-09-14 22:13	45.65	OK	6460	2026-09-14 22:14	45.38	OK
6461	2026-09-14 22:15	44.45	OK	6462	2026-09-14 22:16	45.81	OK
6463	2026-09-14 22:17	47.30	OK	6464	2026-09-14 22:18	48.69	OK
6465	2026-09-14 22:19	46.63	OK	6466	2026-09-14 22:20	46.51	OK
6467	2026-09-14 22:21	46.70	OK	6468	2026-09-14 22:22	46.56	OK
6469	2026-09-14 22:23	46.73	OK	6470	2026-09-14 22:24	46.10	OK
6471	2026-09-14 22:25	47.63	OK	6472	2026-09-14 22:26	47.75	OK
6473	2026-09-14 22:27	45.81	OK	6474	2026-09-14 22:28	46.37	OK
6475	2026-09-14 22:29	43.49	OK	6476	2026-09-14 22:30	45.49	OK
6477	2026-09-14 22:31	46.27	OK	6478	2026-09-14 22:32	45.69	OK
6479	2026-09-14 22:33	46.49	OK	6480	2026-09-14 22:34	46.30	OK
6481	2026-09-14 22:35	45.63	OK	6482	2026-09-14 22:36	45.59	OK
6483	2026-09-14 22:37	45.73	OK	6484	2026-09-14 22:38	48.02	OK
6485	2026-09-14 22:39	45.88	OK	6486	2026-09-14 22:40	44.88	OK
6487	2026-09-14 22:41	45.72	OK	6488	2026-09-14 22:42	45.68	OK
6489	2026-09-14 22:43	45.64	OK	6490	2026-09-14 22:44	45.30	OK
6491	2026-09-14 22:45	45.08	OK	6492	2026-09-14 22:46	45.21	OK
6493	2026-09-14 22:47	47.46	OK	6494	2026-09-14 22:48	45.63	OK
6495	2026-09-14 22:49	46.24	OK	6496	2026-09-14 22:50	46.23	OK
6497	2026-09-14 22:51	46.64	OK	6498	2026-09-14 22:52	45.73	OK
6499	2026-09-14 22:53	47.02	OK	6500	2026-09-14 22:54	46.49	OK
6501	2026-09-14 22:55	48.16	OK	6502	2026-09-14 22:56	45.69	OK
6503	2026-09-14 22:57	44.59	OK	6504	2026-09-14 22:58	44.73	OK
6505	2026-09-14 22:59	45.25	OK	6506	2026-09-14 23:00	46.90	OK
6507	2026-09-14 23:01	45.99	OK	6508	2026-09-14 23:02	44.16	OK
6509	2026-09-14 23:03	45.04	OK	6510	2026-09-14 23:04	46.59	OK
6511	2026-09-14 23:05	45.75	OK	6512	2026-09-14 23:06	45.48	OK
6513	2026-09-14 23:07	43.84	OK	6514	2026-09-14 23:08	43.92	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6515	2026-09-14 23:09	45.66	OK	6516	2026-09-14 23:10	45.42	OK
6517	2026-09-14 23:11	46.35	OK	6518	2026-09-14 23:12	45.98	OK
6519	2026-09-14 23:13	44.85	OK	6520	2026-09-14 23:14	45.52	OK
6521	2026-09-14 23:15	47.03	OK	6522	2026-09-14 23:16	47.31	OK
6523	2026-09-14 23:17	45.51	OK	6524	2026-09-14 23:18	44.53	OK
6525	2026-09-14 23:19	44.97	OK	6526	2026-09-14 23:20	44.70	OK
6527	2026-09-14 23:21	44.19	OK	6528	2026-09-14 23:22	43.94	OK
6529	2026-09-14 23:23	45.87	OK	6530	2026-09-14 23:24	45.00	OK
6531	2026-09-14 23:25	43.33	OK	6532	2026-09-14 23:26	44.35	OK
6533	2026-09-14 23:27	44.07	OK	6534	2026-09-14 23:28	44.96	OK
6535	2026-09-14 23:29	45.08	OK	6536	2026-09-14 23:30	45.00	OK
6537	2026-09-14 23:31	46.01	OK	6538	2026-09-14 23:32	45.98	OK
6539	2026-09-14 23:33	43.58	OK	6540	2026-09-14 23:34	45.63	OK
6541	2026-09-14 23:35	46.12	OK	6542	2026-09-14 23:36	45.81	OK
6543	2026-09-14 23:37	46.82	OK	6544	2026-09-14 23:38	43.54	OK
6545	2026-09-14 23:39	44.55	OK	6546	2026-09-14 23:40	44.64	OK
6547	2026-09-14 23:41	45.39	OK	6548	2026-09-14 23:42	47.86	OK
6549	2026-09-14 23:43	47.40	OK	6550	2026-09-14 23:44	46.51	OK
6551	2026-09-14 23:45	47.28	OK	6552	2026-09-14 23:46	45.68	OK
6553	2026-09-14 23:47	44.30	OK	6554	2026-09-14 23:48	47.79	OK
6555	2026-09-14 23:49	43.95	OK	6556	2026-09-14 23:50	45.66	OK
6557	2026-09-14 23:51	43.56	OK	6558	2026-09-14 23:52	43.01	OK
6559	2026-09-14 23:53	45.99	OK	6560	2026-09-14 23:54	44.82	OK
6561	2026-09-14 23:55	45.90	OK	6562	2026-09-14 23:56	44.83	OK
6563	2026-09-14 23:57	46.27	OK	6564	2026-09-14 23:58	43.67	OK
6565	2026-09-14 23:59	43.56	OK	6566	2026-09-15 00:00	45.53	OK
6567	2026-09-15 00:01	43.24	OK	6568	2026-09-15 00:02	45.63	OK
6569	2026-09-15 00:03	45.42	OK	6570	2026-09-15 00:04	46.18	OK
6571	2026-09-15 00:05	45.41	OK	6572	2026-09-15 00:06	46.14	OK
6573	2026-09-15 00:07	44.66	OK	6574	2026-09-15 00:08	44.39	OK
6575	2026-09-15 00:09	44.17	OK	6576	2026-09-15 00:10	45.47	OK
6577	2026-09-15 00:11	44.39	OK	6578	2026-09-15 00:12	43.45	OK
6579	2026-09-15 00:13	44.49	OK	6580	2026-09-15 00:14	45.13	OK
6581	2026-09-15 00:15	44.57	OK	6582	2026-09-15 00:16	44.04	OK
6583	2026-09-15 00:17	45.92	OK	6584	2026-09-15 00:18	45.53	OK
6585	2026-09-15 00:19	44.81	OK	6586	2026-09-15 00:20	44.88	OK
6587	2026-09-15 00:21	45.23	OK	6588	2026-09-15 00:22	47.50	OK
6589	2026-09-15 00:23	45.55	OK	6590	2026-09-15 00:24	44.01	OK
6591	2026-09-15 00:25	44.81	OK	6592	2026-09-15 00:26	45.21	OK
6593	2026-09-15 00:27	45.19	OK	6594	2026-09-15 00:28	44.11	OK
6595	2026-09-15 00:29	44.25	OK	6596	2026-09-15 00:30	44.70	OK
6597	2026-09-15 00:31	47.24	OK	6598	2026-09-15 00:32	43.69	OK
6599	2026-09-15 00:33	43.76	OK	6600	2026-09-15 00:34	45.62	OK
6601	2026-09-15 00:35	42.44	OK	6602	2026-09-15 00:36	45.81	OK
6603	2026-09-15 00:37	45.79	OK	6604	2026-09-15 00:38	43.83	OK
6605	2026-09-15 00:39	47.50	OK	6606	2026-09-15 00:40	46.59	OK
6607	2026-09-15 00:41	46.08	OK	6608	2026-09-15 00:42	45.51	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6609	2026-09-15 00:43	44.24	OK	6610	2026-09-15 00:44	44.91	OK
6611	2026-09-15 00:45	47.27	OK	6612	2026-09-15 00:46	46.08	OK
6613	2026-09-15 00:47	46.97	OK	6614	2026-09-15 00:48	44.71	OK
6615	2026-09-15 00:49	43.88	OK	6616	2026-09-15 00:50	43.72	OK
6617	2026-09-15 00:51	43.82	OK	6618	2026-09-15 00:52	46.29	OK
6619	2026-09-15 00:53	44.10	OK	6620	2026-09-15 00:54	44.86	OK
6621	2026-09-15 00:55	44.02	OK	6622	2026-09-15 00:56	46.30	OK
6623	2026-09-15 00:57	44.93	OK	6624	2026-09-15 00:58	44.70	OK
6625	2026-09-15 00:59	46.15	OK	6626	2026-09-15 01:00	45.69	OK
6627	2026-09-15 01:01	45.64	OK	6628	2026-09-15 01:02	44.76	OK
6629	2026-09-15 01:03	45.70	OK	6630	2026-09-15 01:04	45.76	OK
6631	2026-09-15 01:05	44.15	OK	6632	2026-09-15 01:06	46.54	OK
6633	2026-09-15 01:07	45.09	OK	6634	2026-09-15 01:08	44.90	OK
6635	2026-09-15 01:09	44.37	OK	6636	2026-09-15 01:10	45.40	OK
6637	2026-09-15 01:11	44.01	OK	6638	2026-09-15 01:12	45.45	OK
6639	2026-09-15 01:13	43.16	OK	6640	2026-09-15 01:14	44.59	OK
6641	2026-09-15 01:15	44.21	OK	6642	2026-09-15 01:16	47.09	OK
6643	2026-09-15 01:17	44.11	OK	6644	2026-09-15 01:18	45.82	OK
6645	2026-09-15 01:19	44.57	OK	6646	2026-09-15 01:20	46.07	OK
6647	2026-09-15 01:21	45.76	OK	6648	2026-09-15 01:22	46.91	OK
6649	2026-09-15 01:23	46.68	OK	6650	2026-09-15 01:24	46.38	OK
6651	2026-09-15 01:25	43.27	OK	6652	2026-09-15 01:26	43.78	OK
6653	2026-09-15 01:27	43.54	OK	6654	2026-09-15 01:28	44.79	OK
6655	2026-09-15 01:29	44.82	OK	6656	2026-09-15 01:30	47.43	OK
6657	2026-09-15 01:31	46.41	OK	6658	2026-09-15 01:32	44.20	OK
6659	2026-09-15 01:33	44.04	OK	6660	2026-09-15 01:34	45.78	OK
6661	2026-09-15 01:35	43.65	OK	6662	2026-09-15 01:36	45.37	OK
6663	2026-09-15 01:37	45.72	OK	6664	2026-09-15 01:38	44.49	OK
6665	2026-09-15 01:39	45.02	OK	6666	2026-09-15 01:40	44.25	OK
6667	2026-09-15 01:41	45.64	OK	6668	2026-09-15 01:42	45.65	OK
6669	2026-09-15 01:43	44.35	OK	6670	2026-09-15 01:44	45.12	OK
6671	2026-09-15 01:45	44.97	OK	6672	2026-09-15 01:46	43.88	OK
6673	2026-09-15 01:47	44.59	OK	6674	2026-09-15 01:48	44.98	OK
6675	2026-09-15 01:49	43.01	OK	6676	2026-09-15 01:50	44.84	OK
6677	2026-09-15 01:51	44.77	OK	6678	2026-09-15 01:52	45.70	OK
6679	2026-09-15 01:53	45.16	OK	6680	2026-09-15 01:54	45.05	OK
6681	2026-09-15 01:55	44.15	OK	6682	2026-09-15 01:56	45.35	OK
6683	2026-09-15 01:57	43.45	OK	6684	2026-09-15 01:58	46.21	OK
6685	2026-09-15 01:59	45.46	OK	6686	2026-09-15 02:00	46.72	OK
6687	2026-09-15 02:01	45.66	OK	6688	2026-09-15 02:02	44.48	OK
6689	2026-09-15 02:03	44.34	OK	6690	2026-09-15 02:04	44.53	OK
6691	2026-09-15 02:05	47.51	OK	6692	2026-09-15 02:06	45.72	OK
6693	2026-09-15 02:07	46.05	OK	6694	2026-09-15 02:08	46.82	OK
6695	2026-09-15 02:09	45.16	OK	6696	2026-09-15 02:10	44.21	OK
6697	2026-09-15 02:11	45.16	OK	6698	2026-09-15 02:12	44.79	OK
6699	2026-09-15 02:13	44.45	OK	6700	2026-09-15 02:14	44.93	OK
6701	2026-09-15 02:15	44.55	OK	6702	2026-09-15 02:16	43.59	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6703	2026-09-15 02:17	44.20	OK	6704	2026-09-15 02:18	46.78	OK
6705	2026-09-15 02:19	46.67	OK	6706	2026-09-15 02:20	44.66	OK
6707	2026-09-15 02:21	44.63	OK	6708	2026-09-15 02:22	45.86	OK
6709	2026-09-15 02:23	45.51	OK	6710	2026-09-15 02:24	46.56	OK
6711	2026-09-15 02:25	47.44	OK	6712	2026-09-15 02:26	46.34	OK
6713	2026-09-15 02:27	45.34	OK	6714	2026-09-15 02:28	45.37	OK
6715	2026-09-15 02:29	43.56	OK	6716	2026-09-15 02:30	44.42	OK
6717	2026-09-15 02:31	45.20	OK	6718	2026-09-15 02:32	45.34	OK
6719	2026-09-15 02:33	44.31	OK	6720	2026-09-15 02:34	45.67	OK
6721	2026-09-15 02:35	45.46	OK	6722	2026-09-15 02:36	46.13	OK
6723	2026-09-15 02:37	46.02	OK	6724	2026-09-15 02:38	46.39	OK
6725	2026-09-15 02:39	47.50	OK	6726	2026-09-15 02:40	43.81	OK
6727	2026-09-15 02:41	44.52	OK	6728	2026-09-15 02:42	44.48	OK
6729	2026-09-15 02:43	43.78	OK	6730	2026-09-15 02:44	45.19	OK
6731	2026-09-15 02:45	45.89	OK	6732	2026-09-15 02:46	46.58	OK
6733	2026-09-15 02:47	45.44	OK	6734	2026-09-15 02:48	45.71	OK
6735	2026-09-15 02:49	46.18	OK	6736	2026-09-15 02:50	46.45	OK
6737	2026-09-15 02:51	46.71	OK	6738	2026-09-15 02:52	47.06	OK
6739	2026-09-15 02:53	44.63	OK	6740	2026-09-15 02:54	46.85	OK
6741	2026-09-15 02:55	45.49	OK	6742	2026-09-15 02:56	45.03	OK
6743	2026-09-15 02:57	45.73	OK	6744	2026-09-15 02:58	46.02	OK
6745	2026-09-15 02:59	46.74	OK	6746	2026-09-15 03:00	45.46	OK
6747	2026-09-15 03:01	44.88	OK	6748	2026-09-15 03:02	47.61	OK
6749	2026-09-15 03:03	46.68	OK	6750	2026-09-15 03:04	44.33	OK
6751	2026-09-15 03:05	45.65	OK	6752	2026-09-15 03:06	44.79	OK
6753	2026-09-15 03:07	46.45	OK	6754	2026-09-15 03:08	45.90	OK
6755	2026-09-15 03:09	48.15	OK	6756	2026-09-15 03:10	45.93	OK
6757	2026-09-15 03:11	44.63	OK	6758	2026-09-15 03:12	44.12	OK
6759	2026-09-15 03:13	43.81	OK	6760	2026-09-15 03:14	47.25	OK
6761	2026-09-15 03:15	45.42	OK	6762	2026-09-15 03:16	45.22	OK
6763	2026-09-15 03:17	45.36	OK	6764	2026-09-15 03:18	44.56	OK
6765	2026-09-15 03:19	44.79	OK	6766	2026-09-15 03:20	45.46	OK
6767	2026-09-15 03:21	44.59	OK	6768	2026-09-15 03:22	45.19	OK
6769	2026-09-15 03:23	46.13	OK	6770	2026-09-15 03:24	45.20	OK
6771	2026-09-15 03:25	45.28	OK	6772	2026-09-15 03:26	44.44	OK
6773	2026-09-15 03:27	46.01	OK	6774	2026-09-15 03:28	44.55	OK
6775	2026-09-15 03:29	45.72	OK	6776	2026-09-15 03:30	45.75	OK
6777	2026-09-15 03:31	45.09	OK	6778	2026-09-15 03:32	44.29	OK
6779	2026-09-15 03:33	46.21	OK	6780	2026-09-15 03:34	46.54	OK
6781	2026-09-15 03:35	44.10	OK	6782	2026-09-15 03:36	44.59	OK
6783	2026-09-15 03:37	44.40	OK	6784	2026-09-15 03:38	46.87	OK
6785	2026-09-15 03:39	47.45	OK	6786	2026-09-15 03:40	44.88	OK
6787	2026-09-15 03:41	46.89	OK	6788	2026-09-15 03:42	44.87	OK
6789	2026-09-15 03:43	45.36	OK	6790	2026-09-15 03:44	45.74	OK
6791	2026-09-15 03:45	47.07	OK	6792	2026-09-15 03:46	46.16	OK
6793	2026-09-15 03:47	47.19	OK	6794	2026-09-15 03:48	47.27	OK
6795	2026-09-15 03:49	46.42	OK	6796	2026-09-15 03:50	45.90	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6797	2026-09-15 03:51	47.57	OK	6798	2026-09-15 03:52	45.37	OK
6799	2026-09-15 03:53	44.51	OK	6800	2026-09-15 03:54	44.41	OK
6801	2026-09-15 03:55	45.65	OK	6802	2026-09-15 03:56	45.85	OK
6803	2026-09-15 03:57	45.96	OK	6804	2026-09-15 03:58	46.07	OK
6805	2026-09-15 03:59	45.78	OK	6806	2026-09-15 04:00	47.14	OK
6807	2026-09-15 04:01	48.46	OK	6808	2026-09-15 04:02	46.88	OK
6809	2026-09-15 04:03	46.56	OK	6810	2026-09-15 04:04	44.08	OK
6811	2026-09-15 04:05	46.56	OK	6812	2026-09-15 04:06	46.17	OK
6813	2026-09-15 04:07	46.14	OK	6814	2026-09-15 04:08	44.89	OK
6815	2026-09-15 04:09	46.46	OK	6816	2026-09-15 04:10	47.40	OK
6817	2026-09-15 04:11	46.54	OK	6818	2026-09-15 04:12	46.67	OK
6819	2026-09-15 04:13	44.81	OK	6820	2026-09-15 04:14	45.84	OK
6821	2026-09-15 04:15	45.63	OK	6822	2026-09-15 04:16	47.03	OK
6823	2026-09-15 04:17	44.51	OK	6824	2026-09-15 04:18	46.00	OK
6825	2026-09-15 04:19	45.42	OK	6826	2026-09-15 04:20	46.15	OK
6827	2026-09-15 04:21	46.84	OK	6828	2026-09-15 04:22	44.65	OK
6829	2026-09-15 04:23	44.92	OK	6830	2026-09-15 04:24	45.33	OK
6831	2026-09-15 04:25	45.91	OK	6832	2026-09-15 04:26	46.87	OK
6833	2026-09-15 04:27	48.36	OK	6834	2026-09-15 04:28	47.62	OK
6835	2026-09-15 04:29	44.77	OK	6836	2026-09-15 04:30	44.05	OK
6837	2026-09-15 04:31	45.83	OK	6838	2026-09-15 04:32	44.81	OK
6839	2026-09-15 04:33	47.05	OK	6840	2026-09-15 04:34	45.55	OK
6841	2026-09-15 04:35	46.15	OK	6842	2026-09-15 04:36	47.07	OK
6843	2026-09-15 04:37	47.51	OK	6844	2026-09-15 04:38	45.29	OK
6845	2026-09-15 04:39	48.41	OK	6846	2026-09-15 04:40	45.54	OK
6847	2026-09-15 04:41	47.00	OK	6848	2026-09-15 04:42	46.38	OK
6849	2026-09-15 04:43	48.84	OK	6850	2026-09-15 04:44	45.32	OK
6851	2026-09-15 04:45	45.07	OK	6852	2026-09-15 04:46	46.12	OK
6853	2026-09-15 04:47	46.07	OK	6854	2026-09-15 04:48	46.57	OK
6855	2026-09-15 04:49	45.89	OK	6856	2026-09-15 04:50	47.31	OK
6857	2026-09-15 04:51	46.32	OK	6858	2026-09-15 04:52	47.48	OK
6859	2026-09-15 04:53	45.65	OK	6860	2026-09-15 04:54	46.58	OK
6861	2026-09-15 04:55	45.08	OK	6862	2026-09-15 04:56	45.85	OK
6863	2026-09-15 04:57	44.87	OK	6864	2026-09-15 04:58	45.72	OK
6865	2026-09-15 04:59	45.64	OK	6866	2026-09-15 05:00	48.04	OK
6867	2026-09-15 05:01	45.50	OK	6868	2026-09-15 05:02	48.04	OK
6869	2026-09-15 05:03	46.80	OK	6870	2026-09-15 05:04	44.32	OK
6871	2026-09-15 05:05	47.57	OK	6872	2026-09-15 05:06	46.31	OK
6873	2026-09-15 05:07	47.77	OK	6874	2026-09-15 05:08	45.57	OK
6875	2026-09-15 05:09	47.93	OK	6876	2026-09-15 05:10	46.09	OK
6877	2026-09-15 05:11	46.29	OK	6878	2026-09-15 05:12	45.71	OK
6879	2026-09-15 05:13	45.45	OK	6880	2026-09-15 05:14	48.26	OK
6881	2026-09-15 05:15	48.09	OK	6882	2026-09-15 05:16	47.05	OK
6883	2026-09-15 05:17	45.85	OK	6884	2026-09-15 05:18	47.30	OK
6885	2026-09-15 05:19	47.11	OK	6886	2026-09-15 05:20	46.67	OK
6887	2026-09-15 05:21	47.42	OK	6888	2026-09-15 05:22	47.55	OK
6889	2026-09-15 05:23	46.65	OK	6890	2026-09-15 05:24	45.37	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6891	2026-09-15 05:25	47.86	OK	6892	2026-09-15 05:26	47.08	OK
6893	2026-09-15 05:27	46.60	OK	6894	2026-09-15 05:28	47.26	OK
6895	2026-09-15 05:29	47.71	OK	6896	2026-09-15 05:30	45.57	OK
6897	2026-09-15 05:31	46.64	OK	6898	2026-09-15 05:32	45.76	OK
6899	2026-09-15 05:33	46.91	OK	6900	2026-09-15 05:34	47.68	OK
6901	2026-09-15 05:35	47.09	OK	6902	2026-09-15 05:36	44.84	OK
6903	2026-09-15 05:37	47.45	OK	6904	2026-09-15 05:38	47.62	OK
6905	2026-09-15 05:39	45.35	OK	6906	2026-09-15 05:40	48.98	OK
6907	2026-09-15 05:41	45.75	OK	6908	2026-09-15 05:42	47.35	OK
6909	2026-09-15 05:43	47.27	OK	6910	2026-09-15 05:44	48.29	OK
6911	2026-09-15 05:45	46.27	OK	6912	2026-09-15 05:46	45.18	OK
6913	2026-09-15 05:47	48.37	OK	6914	2026-09-15 05:48	48.20	OK
6915	2026-09-15 05:49	47.11	OK	6916	2026-09-15 05:50	45.38	OK
6917	2026-09-15 05:51	47.51	OK	6918	2026-09-15 05:52	46.92	OK
6919	2026-09-15 05:53	46.45	OK	6920	2026-09-15 05:54	47.24	OK
6921	2026-09-15 05:55	46.84	OK	6922	2026-09-15 05:56	48.99	OK
6923	2026-09-15 05:57	48.46	OK	6924	2026-09-15 05:58	48.53	OK
6925	2026-09-15 05:59	46.41	OK	6926	2026-09-15 06:00	47.75	OK
6927	2026-09-15 06:01	47.03	OK	6928	2026-09-15 06:02	47.04	OK
6929	2026-09-15 06:03	47.05	OK	6930	2026-09-15 06:04	47.77	OK
6931	2026-09-15 06:05	48.36	OK	6932	2026-09-15 06:06	48.94	OK
6933	2026-09-15 06:07	49.14	OK	6934	2026-09-15 06:08	46.12	OK
6935	2026-09-15 06:09	46.41	OK	6936	2026-09-15 06:10	49.86	OK
6937	2026-09-15 06:11	47.60	OK	6938	2026-09-15 06:12	45.95	OK
6939	2026-09-15 06:13	47.04	OK	6940	2026-09-15 06:14	45.59	OK
6941	2026-09-15 06:15	46.58	OK	6942	2026-09-15 06:16	46.49	OK
6943	2026-09-15 06:17	49.29	OK	6944	2026-09-15 06:18	48.08	OK
6945	2026-09-15 06:19	47.74	OK	6946	2026-09-15 06:20	46.95	OK
6947	2026-09-15 06:21	49.14	OK	6948	2026-09-15 06:22	47.70	OK
6949	2026-09-15 06:23	48.88	OK	6950	2026-09-15 06:24	47.57	OK
6951	2026-09-15 06:25	47.66	OK	6952	2026-09-15 06:26	46.61	OK
6953	2026-09-15 06:27	48.88	OK	6954	2026-09-15 06:28	46.00	OK
6955	2026-09-15 06:29	48.55	OK	6956	2026-09-15 06:30	47.16	OK
6957	2026-09-15 06:31	47.81	OK	6958	2026-09-15 06:32	47.34	OK
6959	2026-09-15 06:33	46.62	OK	6960	2026-09-15 06:34	46.92	OK
6961	2026-09-15 06:35	47.86	OK	6962	2026-09-15 06:36	47.20	OK
6963	2026-09-15 06:37	48.26	OK	6964	2026-09-15 06:38	46.53	OK
6965	2026-09-15 06:39	46.59	OK	6966	2026-09-15 06:40	47.26	OK
6967	2026-09-15 06:41	50.12	OK	6968	2026-09-15 06:42	46.98	OK
6969	2026-09-15 06:43	46.61	OK	6970	2026-09-15 06:44	47.02	OK
6971	2026-09-15 06:45	48.06	OK	6972	2026-09-15 06:46	49.71	OK
6973	2026-09-15 06:47	47.41	OK	6974	2026-09-15 06:48	48.48	OK
6975	2026-09-15 06:49	47.95	OK	6976	2026-09-15 06:50	48.06	OK
6977	2026-09-15 06:51	46.63	OK	6978	2026-09-15 06:52	49.16	OK
6979	2026-09-15 06:53	47.43	OK	6980	2026-09-15 06:54	47.25	OK
6981	2026-09-15 06:55	48.11	OK	6982	2026-09-15 06:56	48.42	OK
6983	2026-09-15 06:57	49.28	OK	6984	2026-09-15 06:58	47.34	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6985	2026-09-15 06:59	47.93	OK	6986	2026-09-15 07:00	48.31	OK
6987	2026-09-15 07:01	47.43	OK	6988	2026-09-15 07:02	49.49	OK
6989	2026-09-15 07:03	47.51	OK	6990	2026-09-15 07:04	49.09	OK
6991	2026-09-15 07:05	49.16	OK	6992	2026-09-15 07:06	49.08	OK
6993	2026-09-15 07:07	48.66	OK	6994	2026-09-15 07:08	47.03	OK
6995	2026-09-15 07:09	48.05	OK	6996	2026-09-15 07:10	48.16	OK
6997	2026-09-15 07:11	47.14	OK	6998	2026-09-15 07:12	47.41	OK
6999	2026-09-15 07:13	49.89	OK	7000	2026-09-15 07:14	48.57	OK
7001	2026-09-15 07:15	47.31	OK	7002	2026-09-15 07:16	48.91	OK
7003	2026-09-15 07:17	48.92	OK	7004	2026-09-15 07:18	47.52	OK
7005	2026-09-15 07:19	48.67	OK	7006	2026-09-15 07:20	48.69	OK
7007	2026-09-15 07:21	48.27	OK	7008	2026-09-15 07:22	49.47	OK
7009	2026-09-15 07:23	48.40	OK	7010	2026-09-15 07:24	47.74	OK
7011	2026-09-15 07:25	47.89	OK	7012	2026-09-15 07:26	48.89	OK
7013	2026-09-15 07:27	49.69	OK	7014	2026-09-15 07:28	48.59	OK
7015	2026-09-15 07:29	49.91	OK	7016	2026-09-15 07:30	48.99	OK
7017	2026-09-15 07:31	49.22	OK	7018	2026-09-15 07:32	48.60	OK
7019	2026-09-15 07:33	47.26	OK	7020	2026-09-15 07:34	48.61	OK
7021	2026-09-15 07:35	50.05	OK	7022	2026-09-15 07:36	49.86	OK
7023	2026-09-15 07:37	47.33	OK	7024	2026-09-15 07:38	50.09	OK
7025	2026-09-15 07:39	47.30	OK	7026	2026-09-15 07:40	48.89	OK
7027	2026-09-15 07:41	48.45	OK	7028	2026-09-15 07:42	50.00	OK
7029	2026-09-15 07:43	48.47	OK	7030	2026-09-15 07:44	49.13	OK
7031	2026-09-15 07:45	49.23	OK	7032	2026-09-15 07:46	48.53	OK
7033	2026-09-15 07:47	49.29	OK	7034	2026-09-15 07:48	48.97	OK
7035	2026-09-15 07:49	48.44	OK	7036	2026-09-15 07:50	48.88	OK
7037	2026-09-15 07:51	49.63	OK	7038	2026-09-15 07:52	49.26	OK
7039	2026-09-15 07:53	48.54	OK	7040	2026-09-15 07:54	48.44	OK
7041	2026-09-15 07:55	48.77	OK	7042	2026-09-15 07:56	51.05	OK
7043	2026-09-15 07:57	48.89	OK	7044	2026-09-15 07:58	46.55	OK
7045	2026-09-15 07:59	48.28	OK	7046	2026-09-15 08:00	47.77	OK
7047	2026-09-15 08:01	48.31	OK	7048	2026-09-15 08:02	50.12	OK
7049	2026-09-15 08:03	49.45	OK	7050	2026-09-15 08:04	48.57	OK
7051	2026-09-15 08:05	49.05	OK	7052	2026-09-15 08:06	49.05	OK
7053	2026-09-15 08:07	48.33	OK	7054	2026-09-15 08:08	50.44	OK
7055	2026-09-15 08:09	49.50	OK	7056	2026-09-15 08:10	50.72	OK
7057	2026-09-15 08:11	49.09	OK	7058	2026-09-15 08:12	48.98	OK
7059	2026-09-15 08:13	48.45	OK	7060	2026-09-15 08:14	49.80	OK
7061	2026-09-15 08:15	48.48	OK	7062	2026-09-15 08:16	50.17	OK
7063	2026-09-15 08:17	48.73	OK	7064	2026-09-15 08:18	49.55	OK
7065	2026-09-15 08:19	48.17	OK	7066	2026-09-15 08:20	47.52	OK
7067	2026-09-15 08:21	50.82	OK	7068	2026-09-15 08:22	48.56	OK
7069	2026-09-15 08:23	50.23	OK	7070	2026-09-15 08:24	51.61	OK
7071	2026-09-15 08:25	50.76	OK	7072	2026-09-15 08:26	49.01	OK
7073	2026-09-15 08:27	47.97	OK	7074	2026-09-15 08:28	48.02	OK
7075	2026-09-15 08:29	49.69	OK	7076	2026-09-15 08:30	51.81	OK
7077	2026-09-15 08:31	50.63	OK	7078	2026-09-15 08:32	50.64	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7079	2026-09-15 08:33	49.63	OK	7080	2026-09-15 08:34	49.43	OK
7081	2026-09-15 08:35	48.80	OK	7082	2026-09-15 08:36	48.28	OK
7083	2026-09-15 08:37	49.01	OK	7084	2026-09-15 08:38	48.90	OK
7085	2026-09-15 08:39	48.90	OK	7086	2026-09-15 08:40	50.49	OK
7087	2026-09-15 08:41	51.22	OK	7088	2026-09-15 08:42	50.83	OK
7089	2026-09-15 08:43	49.59	OK	7090	2026-09-15 08:44	49.26	OK
7091	2026-09-15 08:45	50.03	OK	7092	2026-09-15 08:46	51.16	OK
7093	2026-09-15 08:47	51.10	OK	7094	2026-09-15 08:48	50.11	OK
7095	2026-09-15 08:49	51.16	OK	7096	2026-09-15 08:50	49.64	OK
7097	2026-09-15 08:51	47.45	OK	7098	2026-09-15 08:52	47.77	OK
7099	2026-09-15 08:53	47.71	OK	7100	2026-09-15 08:54	49.69	OK
7101	2026-09-15 08:55	50.94	OK	7102	2026-09-15 08:56	48.92	OK
7103	2026-09-15 08:57	49.24	OK	7104	2026-09-15 08:58	49.33	OK
7105	2026-09-15 08:59	49.42	OK	7106	2026-09-15 09:00	50.62	OK
7107	2026-09-15 09:01	50.49	OK	7108	2026-09-15 09:02	51.12	OK
7109	2026-09-15 09:03	49.76	OK	7110	2026-09-15 09:04	51.44	OK
7111	2026-09-15 09:05	48.58	OK	7112	2026-09-15 09:06	50.55	OK
7113	2026-09-15 09:07	51.12	OK	7114	2026-09-15 09:08	50.74	OK
7115	2026-09-15 09:09	50.74	OK	7116	2026-09-15 09:10	50.41	OK
7117	2026-09-15 09:11	49.11	OK	7118	2026-09-15 09:12	49.09	OK
7119	2026-09-15 09:13	50.00	OK	7120	2026-09-15 09:14	49.74	OK
7121	2026-09-15 09:15	48.30	OK	7122	2026-09-15 09:16	49.96	OK
7123	2026-09-15 09:17	50.51	OK	7124	2026-09-15 09:18	50.07	OK
7125	2026-09-15 09:19	47.95	OK	7126	2026-09-15 09:20	48.55	OK
7127	2026-09-15 09:21	50.66	OK	7128	2026-09-15 09:22	50.25	OK
7129	2026-09-15 09:23	50.21	OK	7130	2026-09-15 09:24	51.59	OK
7131	2026-09-15 09:25	51.26	OK	7132	2026-09-15 09:26	52.76	OK
7133	2026-09-15 09:27	49.04	OK	7134	2026-09-15 09:28	48.61	OK
7135	2026-09-15 09:29	49.67	OK	7136	2026-09-15 09:30	50.69	OK
7137	2026-09-15 09:31	50.03	OK	7138	2026-09-15 09:32	49.87	OK
7139	2026-09-15 09:33	51.17	OK	7140	2026-09-15 09:34	51.77	OK
7141	2026-09-15 09:35	50.27	OK	7142	2026-09-15 09:36	51.49	OK
7143	2026-09-15 09:37	50.91	OK	7144	2026-09-15 09:38	50.65	OK
7145	2026-09-15 09:39	51.25	OK	7146	2026-09-15 09:40	50.98	OK
7147	2026-09-15 09:41	51.25	OK	7148	2026-09-15 09:42	50.24	OK
7149	2026-09-15 09:43	50.72	OK	7150	2026-09-15 09:44	49.70	OK
7151	2026-09-15 09:45	49.55	OK	7152	2026-09-15 09:46	50.50	OK
7153	2026-09-15 09:47	50.24	OK	7154	2026-09-15 09:48	50.66	OK
7155	2026-09-15 09:49	49.04	OK	7156	2026-09-15 09:50	50.62	OK
7157	2026-09-15 09:51	51.86	OK	7158	2026-09-15 09:52	51.40	OK
7159	2026-09-15 09:53	51.46	OK	7160	2026-09-15 09:54	49.06	OK
7161	2026-09-15 09:55	50.44	OK	7162	2026-09-15 09:56	50.01	OK
7163	2026-09-15 09:57	51.07	OK	7164	2026-09-15 09:58	50.35	OK
7165	2026-09-15 09:59	50.20	OK	7166	2026-09-15 10:00	49.90	OK
7167	2026-09-15 10:01	50.16	OK	7168	2026-09-15 10:02	50.49	OK
7169	2026-09-15 10:03	48.68	OK	7170	2026-09-15 10:04	49.28	OK
7171	2026-09-15 10:05	50.03	OK	7172	2026-09-15 10:06	49.57	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7173	2026-09-15 10:07	48.93	OK	7174	2026-09-15 10:08	49.96	OK
7175	2026-09-15 10:09	51.48	OK	7176	2026-09-15 10:10	49.97	OK
7177	2026-09-15 10:11	52.41	OK	7178	2026-09-15 10:12	50.14	OK
7179	2026-09-15 10:13	52.50	OK	7180	2026-09-15 10:14	51.18	OK
7181	2026-09-15 10:15	48.55	OK	7182	2026-09-15 10:16	51.71	OK
7183	2026-09-15 10:17	51.09	OK	7184	2026-09-15 10:18	49.95	OK
7185	2026-09-15 10:19	49.74	OK	7186	2026-09-15 10:20	49.17	OK
7187	2026-09-15 10:21	51.58	OK	7188	2026-09-15 10:22	50.58	OK
7189	2026-09-15 10:23	50.40	OK	7190	2026-09-15 10:24	51.84	OK
7191	2026-09-15 10:25	50.54	OK	7192	2026-09-15 10:26	52.34	OK
7193	2026-09-15 10:27	51.32	OK	7194	2026-09-15 10:28	51.17	OK
7195	2026-09-15 10:29	48.97	OK	7196	2026-09-15 10:30	51.00	OK
7197	2026-09-15 10:31	51.20	OK	7198	2026-09-15 10:32	51.67	OK
7199	2026-09-15 10:33	50.70	OK	7200	2026-09-15 10:34	50.93	OK
7201	2026-09-15 10:35	51.27	OK	7202	2026-09-15 10:36	49.44	OK
7203	2026-09-15 10:37	51.77	OK	7204	2026-09-15 10:38	50.10	OK
7205	2026-09-15 10:39	51.48	OK	7206	2026-09-15 10:40	51.05	OK
7207	2026-09-15 10:41	50.54	OK	7208	2026-09-15 10:42	51.23	OK
7209	2026-09-15 10:43	50.77	OK	7210	2026-09-15 10:44	52.57	OK
7211	2026-09-15 10:45	51.16	OK	7212	2026-09-15 10:46	52.43	OK
7213	2026-09-15 10:47	50.35	OK	7214	2026-09-15 10:48	51.49	OK
7215	2026-09-15 10:49	50.42	OK	7216	2026-09-15 10:50	51.91	OK
7217	2026-09-15 10:51	49.76	OK	7218	2026-09-15 10:52	51.43	OK
7219	2026-09-15 10:53	51.03	OK	7220	2026-09-15 10:54	49.80	OK
7221	2026-09-15 10:55	51.95	OK	7222	2026-09-15 10:56	49.28	OK
7223	2026-09-15 10:57	50.57	OK	7224	2026-09-15 10:58	53.02	OK
7225	2026-09-15 10:59	50.53	OK	7226	2026-09-15 11:00	50.49	OK
7227	2026-09-15 11:01	50.10	OK	7228	2026-09-15 11:02	50.95	OK
7229	2026-09-15 11:03	50.29	OK	7230	2026-09-15 11:04	50.84	OK
7231	2026-09-15 11:05	49.53	OK	7232	2026-09-15 11:06	50.41	OK
7233	2026-09-15 11:07	50.76	OK	7234	2026-09-15 11:08	51.32	OK
7235	2026-09-15 11:09	51.53	OK	7236	2026-09-15 11:10	49.93	OK
7237	2026-09-15 11:11	50.54	OK	7238	2026-09-15 11:12	51.87	OK
7239	2026-09-15 11:13	52.11	OK	7240	2026-09-15 11:14	51.48	OK
7241	2026-09-15 11:15	50.47	OK	7242	2026-09-15 11:16	53.36	OK
7243	2026-09-15 11:17	52.34	OK	7244	2026-09-15 11:18	52.42	OK
7245	2026-09-15 11:19	51.63	OK	7246	2026-09-15 11:20	51.52	OK
7247	2026-09-15 11:21	50.64	OK	7248	2026-09-15 11:22	52.44	OK
7249	2026-09-15 11:23	52.43	OK	7250	2026-09-15 11:24	49.86	OK
7251	2026-09-15 11:25	51.11	OK	7252	2026-09-15 11:26	53.82	OK
7253	2026-09-15 11:27	51.59	OK	7254	2026-09-15 11:28	52.11	OK
7255	2026-09-15 11:29	49.19	OK	7256	2026-09-15 11:30	51.62	OK
7257	2026-09-15 11:31	52.10	OK	7258	2026-09-15 11:32	50.28	OK
7259	2026-09-15 11:33	53.19	OK	7260	2026-09-15 11:34	51.02	OK
7261	2026-09-15 11:35	51.87	OK	7262	2026-09-15 11:36	50.48	OK
7263	2026-09-15 11:37	52.15	OK	7264	2026-09-15 11:38	49.98	OK
7265	2026-09-15 11:39	50.73	OK	7266	2026-09-15 11:40	51.63	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7267	2026-09-15 11:41	52.18	OK	7268	2026-09-15 11:42	52.58	OK
7269	2026-09-15 11:43	51.01	OK	7270	2026-09-15 11:44	51.32	OK
7271	2026-09-15 11:45	50.35	OK	7272	2026-09-15 11:46	52.53	OK
7273	2026-09-15 11:47	51.79	OK	7274	2026-09-15 11:48	53.23	OK
7275	2026-09-15 11:49	50.91	OK	7276	2026-09-15 11:50	52.49	OK
7277	2026-09-15 11:51	50.94	OK	7278	2026-09-15 11:52	51.04	OK
7279	2026-09-15 11:53	52.25	OK	7280	2026-09-15 11:54	51.51	OK
7281	2026-09-15 11:55	52.43	OK	7282	2026-09-15 11:56	52.35	OK
7283	2026-09-15 11:57	52.21	OK	7284	2026-09-15 11:58	51.71	OK
7285	2026-09-15 11:59	53.61	OK	7286	2026-09-15 12:00	51.05	OK
7287	2026-09-15 12:01	51.77	OK	7288	2026-09-15 12:02	49.96	OK
7289	2026-09-15 12:03	50.60	OK	7290	2026-09-15 12:04	50.26	OK
7291	2026-09-15 12:05	49.89	OK	7292	2026-09-15 12:06	52.60	OK
7293	2026-09-15 12:07	51.50	OK	7294	2026-09-15 12:08	53.08	OK
7295	2026-09-15 12:09	53.32	OK	7296	2026-09-15 12:10	51.92	OK
7297	2026-09-15 12:11	50.65	OK	7298	2026-09-15 12:12	50.56	OK
7299	2026-09-15 12:13	52.04	OK	7300	2026-09-15 12:14	52.32	OK
7301	2026-09-15 12:15	52.69	OK	7302	2026-09-15 12:16	52.39	OK
7303	2026-09-15 12:17	51.64	OK	7304	2026-09-15 12:18	52.84	OK
7305	2026-09-15 12:19	52.74	OK	7306	2026-09-15 12:20	50.54	OK
7307	2026-09-15 12:21	53.27	OK	7308	2026-09-15 12:22	52.38	OK
7309	2026-09-15 12:23	51.06	OK	7310	2026-09-15 12:24	51.65	OK
7311	2026-09-15 12:25	51.32	OK	7312	2026-09-15 12:26	50.36	OK
7313	2026-09-15 12:27	53.71	OK	7314	2026-09-15 12:28	52.00	OK
7315	2026-09-15 12:29	50.52	OK	7316	2026-09-15 12:30	53.71	OK
7317	2026-09-15 12:31	53.03	OK	7318	2026-09-15 12:32	52.06	OK
7319	2026-09-15 12:33	51.75	OK	7320	2026-09-15 12:34	49.88	OK
7321	2026-09-15 12:35	51.40	OK	7322	2026-09-15 12:36	52.16	OK
7323	2026-09-15 12:37	50.88	OK	7324	2026-09-15 12:38	51.33	OK
7325	2026-09-15 12:39	53.92	OK	7326	2026-09-15 12:40	50.54	OK
7327	2026-09-15 12:41	50.55	OK	7328	2026-09-15 12:42	51.71	OK
7329	2026-09-15 12:43	50.89	OK	7330	2026-09-15 12:44	51.92	OK
7331	2026-09-15 12:45	49.13	OK	7332	2026-09-15 12:46	50.70	OK
7333	2026-09-15 12:47	52.14	OK	7334	2026-09-15 12:48	51.31	OK
7335	2026-09-15 12:49	50.79	OK	7336	2026-09-15 12:50	52.14	OK
7337	2026-09-15 12:51	51.35	OK	7338	2026-09-15 12:52	51.57	OK
7339	2026-09-15 12:53	51.84	OK	7340	2026-09-15 12:54	52.22	OK
7341	2026-09-15 12:55	52.68	OK	7342	2026-09-15 12:56	53.57	OK
7343	2026-09-15 12:57	50.79	OK	7344	2026-09-15 12:58	52.41	OK
7345	2026-09-15 12:59	50.42	OK	7346	2026-09-15 13:00	52.38	OK
7347	2026-09-15 13:01	51.91	OK	7348	2026-09-15 13:02	50.88	OK
7349	2026-09-15 13:03	52.12	OK	7350	2026-09-15 13:04	52.69	OK
7351	2026-09-15 13:05	53.99	OK	7352	2026-09-15 13:06	51.23	OK
7353	2026-09-15 13:07	52.59	OK	7354	2026-09-15 13:08	49.49	OK
7355	2026-09-15 13:09	51.70	OK	7356	2026-09-15 13:10	52.11	OK
7357	2026-09-15 13:11	52.28	OK	7358	2026-09-15 13:12	51.82	OK
7359	2026-09-15 13:13	51.71	OK	7360	2026-09-15 13:14	52.18	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7361	2026-09-15 13:15	50.29	OK	7362	2026-09-15 13:16	51.08	OK
7363	2026-09-15 13:17	50.63	OK	7364	2026-09-15 13:18	51.63	OK
7365	2026-09-15 13:19	52.01	OK	7366	2026-09-15 13:20	51.12	OK
7367	2026-09-15 13:21	52.82	OK	7368	2026-09-15 13:22	52.35	OK
7369	2026-09-15 13:23	51.26	OK	7370	2026-09-15 13:24	52.27	OK
7371	2026-09-15 13:25	52.78	OK	7372	2026-09-15 13:26	52.57	OK
7373	2026-09-15 13:27	50.80	OK	7374	2026-09-15 13:28	50.73	OK
7375	2026-09-15 13:29	53.08	OK	7376	2026-09-15 13:30	51.90	OK
7377	2026-09-15 13:31	54.24	OK	7378	2026-09-15 13:32	52.58	OK
7379	2026-09-15 13:33	50.81	OK	7380	2026-09-15 13:34	51.97	OK
7381	2026-09-15 13:35	52.04	OK	7382	2026-09-15 13:36	50.20	OK
7383	2026-09-15 13:37	52.31	OK	7384	2026-09-15 13:38	50.91	OK
7385	2026-09-15 13:39	49.98	OK	7386	2026-09-15 13:40	51.46	OK
7387	2026-09-15 13:41	51.76	OK	7388	2026-09-15 13:42	51.36	OK
7389	2026-09-15 13:43	50.28	OK	7390	2026-09-15 13:44	52.27	OK
7391	2026-09-15 13:45	52.21	OK	7392	2026-09-15 13:46	52.66	OK
7393	2026-09-15 13:47	51.69	OK	7394	2026-09-15 13:48	53.20	OK
7395	2026-09-15 13:49	51.57	OK	7396	2026-09-15 13:50	51.41	OK
7397	2026-09-15 13:51	52.01	OK	7398	2026-09-15 13:52	53.64	OK
7399	2026-09-15 13:53	50.63	OK	7400	2026-09-15 13:54	51.30	OK
7401	2026-09-15 13:55	50.57	OK	7402	2026-09-15 13:56	50.28	OK
7403	2026-09-15 13:57	52.72	OK	7404	2026-09-15 13:58	51.94	OK
7405	2026-09-15 13:59	51.98	OK	7406	2026-09-15 14:00	51.26	OK
7407	2026-09-15 14:01	52.07	OK	7408	2026-09-15 14:02	51.29	OK
7409	2026-09-15 14:03	52.27	OK	7410	2026-09-15 14:04	53.18	OK
7411	2026-09-15 14:05	49.85	OK	7412	2026-09-15 14:06	50.36	OK
7413	2026-09-15 14:07	52.94	OK	7414	2026-09-15 14:08	52.38	OK
7415	2026-09-15 14:09	50.61	OK	7416	2026-09-15 14:10	53.43	OK
7417	2026-09-15 14:11	51.21	OK	7418	2026-09-15 14:12	50.52	OK
7419	2026-09-15 14:13	52.28	OK	7420	2026-09-15 14:14	52.36	OK
7421	2026-09-15 14:15	52.57	OK	7422	2026-09-15 14:16	51.24	OK
7423	2026-09-15 14:17	50.20	OK	7424	2026-09-15 14:18	51.79	OK
7425	2026-09-15 14:19	51.07	OK	7426	2026-09-15 14:20	52.95	OK
7427	2026-09-15 14:21	53.98	OK	7428	2026-09-15 14:22	51.67	OK
7429	2026-09-15 14:23	50.78	OK	7430	2026-09-15 14:24	53.33	OK
7431	2026-09-15 14:25	50.59	OK	7432	2026-09-15 14:26	53.48	OK
7433	2026-09-15 14:27	51.70	OK	7434	2026-09-15 14:28	50.77	OK
7435	2026-09-15 14:29	52.05	OK	7436	2026-09-15 14:30	51.44	OK
7437	2026-09-15 14:31	51.32	OK	7438	2026-09-15 14:32	52.96	OK
7439	2026-09-15 14:33	52.28	OK	7440	2026-09-15 14:34	53.47	OK
7441	2026-09-15 14:35	52.61	OK	7442	2026-09-15 14:36	50.19	OK
7443	2026-09-15 14:37	52.52	OK	7444	2026-09-15 14:38	50.45	OK
7445	2026-09-15 14:39	53.49	OK	7446	2026-09-15 14:40	52.73	OK
7447	2026-09-15 14:41	52.47	OK	7448	2026-09-15 14:42	51.99	OK
7449	2026-09-15 14:43	50.00	OK	7450	2026-09-15 14:44	52.11	OK
7451	2026-09-15 14:45	50.88	OK	7452	2026-09-15 14:46	52.66	OK
7453	2026-09-15 14:47	49.60	OK	7454	2026-09-15 14:48	53.31	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7455	2026-09-15 14:49	52.36	OK	7456	2026-09-15 14:50	51.68	OK
7457	2026-09-15 14:51	53.69	OK	7458	2026-09-15 14:52	52.11	OK
7459	2026-09-15 14:53	51.20	OK	7460	2026-09-15 14:54	50.39	OK
7461	2026-09-15 14:55	51.44	OK	7462	2026-09-15 14:56	51.91	OK
7463	2026-09-15 14:57	52.49	OK	7464	2026-09-15 14:58	52.46	OK
7465	2026-09-15 14:59	51.83	OK	7466	2026-09-15 15:00	52.29	OK
7467	2026-09-15 15:01	49.58	OK	7468	2026-09-15 15:02	51.34	OK
7469	2026-09-15 15:03	52.13	OK	7470	2026-09-15 15:04	51.48	OK
7471	2026-09-15 15:05	52.31	OK	7472	2026-09-15 15:06	50.99	OK
7473	2026-09-15 15:07	51.44	OK	7474	2026-09-15 15:08	51.11	OK
7475	2026-09-15 15:09	51.90	OK	7476	2026-09-15 15:10	52.13	OK
7477	2026-09-15 15:11	52.29	OK	7478	2026-09-15 15:12	52.28	OK
7479	2026-09-15 15:13	51.93	OK	7480	2026-09-15 15:14	51.05	OK
7481	2026-09-15 15:15	50.34	OK	7482	2026-09-15 15:16	52.29	OK
7483	2026-09-15 15:17	53.04	OK	7484	2026-09-15 15:18	53.42	OK
7485	2026-09-15 15:19	51.05	OK	7486	2026-09-15 15:20	51.70	OK
7487	2026-09-15 15:21	52.44	OK	7488	2026-09-15 15:22	50.43	OK
7489	2026-09-15 15:23	50.17	OK	7490	2026-09-15 15:24	50.49	OK
7491	2026-09-15 15:25	51.02	OK	7492	2026-09-15 15:26	51.15	OK
7493	2026-09-15 15:27	53.14	OK	7494	2026-09-15 15:28	51.20	OK
7495	2026-09-15 15:29	51.82	OK	7496	2026-09-15 15:30	52.07	OK
7497	2026-09-15 15:31	51.03	OK	7498	2026-09-15 15:32	50.63	OK
7499	2026-09-15 15:33	50.93	OK	7500	2026-09-15 15:34	51.10	OK
7501	2026-09-15 15:35	51.83	OK	7502	2026-09-15 15:36	50.27	OK
7503	2026-09-15 15:37	52.58	OK	7504	2026-09-15 15:38	49.67	OK
7505	2026-09-15 15:39	50.52	OK	7506	2026-09-15 15:40	51.93	OK
7507	2026-09-15 15:41	51.28	OK	7508	2026-09-15 15:42	50.69	OK
7509	2026-09-15 15:43	51.78	OK	7510	2026-09-15 15:44	49.74	OK
7511	2026-09-15 15:45	52.55	OK	7512	2026-09-15 15:46	50.11	OK
7513	2026-09-15 15:47	53.00	OK	7514	2026-09-15 15:48	51.98	OK
7515	2026-09-15 15:49	52.37	OK	7516	2026-09-15 15:50	50.02	OK
7517	2026-09-15 15:51	50.21	OK	7518	2026-09-15 15:52	50.27	OK
7519	2026-09-15 15:53	50.06	OK	7520	2026-09-15 15:54	49.85	OK
7521	2026-09-15 15:55	52.95	OK	7522	2026-09-15 15:56	50.20	OK
7523	2026-09-15 15:57	50.41	OK	7524	2026-09-15 15:58	51.35	OK
7525	2026-09-15 15:59	50.84	OK	7526	2026-09-15 16:00	50.34	OK
7527	2026-09-15 16:01	51.51	OK	7528	2026-09-15 16:02	50.98	OK
7529	2026-09-15 16:03	50.48	OK	7530	2026-09-15 16:04	51.60	OK
7531	2026-09-15 16:05	50.03	OK	7532	2026-09-15 16:06	51.19	OK
7533	2026-09-15 16:07	49.70	OK	7534	2026-09-15 16:08	51.29	OK
7535	2026-09-15 16:09	52.54	OK	7536	2026-09-15 16:10	50.89	OK
7537	2026-09-15 16:11	50.72	OK	7538	2026-09-15 16:12	50.74	OK
7539	2026-09-15 16:13	49.90	OK	7540	2026-09-15 16:14	50.85	OK
7541	2026-09-15 16:15	51.20	OK	7542	2026-09-15 16:16	50.96	OK
7543	2026-09-15 16:17	49.33	OK	7544	2026-09-15 16:18	51.61	OK
7545	2026-09-15 16:19	51.05	OK	7546	2026-09-15 16:20	49.47	OK
7547	2026-09-15 16:21	50.81	OK	7548	2026-09-15 16:22	50.96	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7549	2026-09-15 16:23	51.20	OK	7550	2026-09-15 16:24	52.25	OK
7551	2026-09-15 16:25	50.88	OK	7552	2026-09-15 16:26	50.56	OK
7553	2026-09-15 16:27	48.39	OK	7554	2026-09-15 16:28	50.88	OK
7555	2026-09-15 16:29	49.93	OK	7556	2026-09-15 16:30	48.91	OK
7557	2026-09-15 16:31	50.10	OK	7558	2026-09-15 16:32	50.69	OK
7559	2026-09-15 16:33	51.54	OK	7560	2026-09-15 16:34	51.45	OK
7561	2026-09-15 16:35	49.98	OK	7562	2026-09-15 16:36	50.54	OK
7563	2026-09-15 16:37	52.43	OK	7564	2026-09-15 16:38	50.53	OK
7565	2026-09-15 16:39	48.75	OK	7566	2026-09-15 16:40	50.25	OK
7567	2026-09-15 16:41	51.60	OK	7568	2026-09-15 16:42	49.57	OK
7569	2026-09-15 16:43	49.73	OK	7570	2026-09-15 16:44	50.97	OK
7571	2026-09-15 16:45	49.47	OK	7572	2026-09-15 16:46	52.46	OK
7573	2026-09-15 16:47	51.70	OK	7574	2026-09-15 16:48	50.06	OK
7575	2026-09-15 16:49	49.33	OK	7576	2026-09-15 16:50	50.17	OK
7577	2026-09-15 16:51	49.19	OK	7578	2026-09-15 16:52	49.79	OK
7579	2026-09-15 16:53	50.51	OK	7580	2026-09-15 16:54	52.55	OK
7581	2026-09-15 16:55	49.90	OK	7582	2026-09-15 16:56	50.83	OK
7583	2026-09-15 16:57	49.72	OK	7584	2026-09-15 16:58	51.39	OK
7585	2026-09-15 16:59	52.27	OK	7586	2026-09-15 17:00	50.99	OK
7587	2026-09-15 17:01	49.52	OK	7588	2026-09-15 17:02	50.04	OK
7589	2026-09-15 17:03	51.76	OK	7590	2026-09-15 17:04	50.53	OK
7591	2026-09-15 17:05	49.05	OK	7592	2026-09-15 17:06	50.05	OK
7593	2026-09-15 17:07	50.27	OK	7594	2026-09-15 17:08	50.97	OK
7595	2026-09-15 17:09	50.72	OK	7596	2026-09-15 17:10	51.45	OK
7597	2026-09-15 17:11	50.50	OK	7598	2026-09-15 17:12	50.60	OK
7599	2026-09-15 17:13	50.28	OK	7600	2026-09-15 17:14	50.50	OK
7601	2026-09-15 17:15	48.46	OK	7602	2026-09-15 17:16	50.70	OK
7603	2026-09-15 17:17	50.79	OK	7604	2026-09-15 17:18	47.96	OK
7605	2026-09-15 17:19	49.74	OK	7606	2026-09-15 17:20	51.11	OK
7607	2026-09-15 17:21	50.53	OK	7608	2026-09-15 17:22	50.79	OK
7609	2026-09-15 17:23	50.09	OK	7610	2026-09-15 17:24	50.33	OK
7611	2026-09-15 17:25	48.48	OK	7612	2026-09-15 17:26	48.53	OK
7613	2026-09-15 17:27	49.38	OK	7614	2026-09-15 17:28	52.18	OK
7615	2026-09-15 17:29	49.31	OK	7616	2026-09-15 17:30	50.68	OK
7617	2026-09-15 17:31	48.34	OK	7618	2026-09-15 17:32	49.71	OK
7619	2026-09-15 17:33	51.70	OK	7620	2026-09-15 17:34	48.27	OK
7621	2026-09-15 17:35	49.12	OK	7622	2026-09-15 17:36	50.64	OK
7623	2026-09-15 17:37	49.89	OK	7624	2026-09-15 17:38	48.12	OK
7625	2026-09-15 17:39	49.81	OK	7626	2026-09-15 17:40	49.13	OK
7627	2026-09-15 17:41	51.94	OK	7628	2026-09-15 17:42	50.77	OK
7629	2026-09-15 17:43	48.01	OK	7630	2026-09-15 17:44	49.55	OK
7631	2026-09-15 17:45	49.67	OK	7632	2026-09-15 17:46	48.47	OK
7633	2026-09-15 17:47	50.29	OK	7634	2026-09-15 17:48	50.93	OK
7635	2026-09-15 17:49	49.88	OK	7636	2026-09-15 17:50	50.28	OK
7637	2026-09-15 17:51	48.67	OK	7638	2026-09-15 17:52	49.02	OK
7639	2026-09-15 17:53	50.01	OK	7640	2026-09-15 17:54	51.04	OK
7641	2026-09-15 17:55	49.46	OK	7642	2026-09-15 17:56	49.83	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7643	2026-09-15 17:57	50.88	OK	7644	2026-09-15 17:58	48.43	OK
7645	2026-09-15 17:59	51.98	OK	7646	2026-09-15 18:00	48.14	OK
7647	2026-09-15 18:01	50.27	OK	7648	2026-09-15 18:02	48.76	OK
7649	2026-09-15 18:03	49.57	OK	7650	2026-09-15 18:04	51.51	OK
7651	2026-09-15 18:05	50.22	OK	7652	2026-09-15 18:06	49.35	OK
7653	2026-09-15 18:07	49.95	OK	7654	2026-09-15 18:08	49.18	OK
7655	2026-09-15 18:09	48.29	OK	7656	2026-09-15 18:10	49.36	OK
7657	2026-09-15 18:11	48.60	OK	7658	2026-09-15 18:12	51.03	OK
7659	2026-09-15 18:13	48.91	OK	7660	2026-09-15 18:14	48.72	OK
7661	2026-09-15 18:15	48.03	OK	7662	2026-09-15 18:16	50.11	OK
7663	2026-09-15 18:17	48.96	OK	7664	2026-09-15 18:18	50.71	OK
7665	2026-09-15 18:19	49.39	OK	7666	2026-09-15 18:20	49.91	OK
7667	2026-09-15 18:21	49.42	OK	7668	2026-09-15 18:22	49.77	OK
7669	2026-09-15 18:23	49.57	OK	7670	2026-09-15 18:24	49.98	OK
7671	2026-09-15 18:25	50.81	OK	7672	2026-09-15 18:26	48.79	OK
7673	2026-09-15 18:27	48.58	OK	7674	2026-09-15 18:28	49.12	OK
7675	2026-09-15 18:29	49.99	OK	7676	2026-09-15 18:30	50.03	OK
7677	2026-09-15 18:31	48.63	OK	7678	2026-09-15 18:32	48.90	OK
7679	2026-09-15 18:33	49.15	OK	7680	2026-09-15 18:34	48.24	OK
7681	2026-09-15 18:35	48.99	OK	7682	2026-09-15 18:36	50.85	OK
7683	2026-09-15 18:37	49.64	OK	7684	2026-09-15 18:38	47.17	OK
7685	2026-09-15 18:39	49.60	OK	7686	2026-09-15 18:40	47.57	OK
7687	2026-09-15 18:41	49.70	OK	7688	2026-09-15 18:42	50.85	OK
7689	2026-09-15 18:43	50.43	OK	7690	2026-09-15 18:44	47.82	OK
7691	2026-09-15 18:45	51.04	OK	7692	2026-09-15 18:46	48.95	OK
7693	2026-09-15 18:47	49.96	OK	7694	2026-09-15 18:48	47.94	OK
7695	2026-09-15 18:49	47.84	OK	7696	2026-09-15 18:50	49.29	OK
7697	2026-09-15 18:51	50.84	OK	7698	2026-09-15 18:52	49.31	OK
7699	2026-09-15 18:53	48.34	OK	7700	2026-09-15 18:54	48.74	OK
7701	2026-09-15 18:55	47.36	OK	7702	2026-09-15 18:56	49.57	OK
7703	2026-09-15 18:57	47.57	OK	7704	2026-09-15 18:58	47.82	OK
7705	2026-09-15 18:59	50.21	OK	7706	2026-09-15 19:00	49.58	OK
7707	2026-09-15 19:01	49.01	OK	7708	2026-09-15 19:02	50.16	OK
7709	2026-09-15 19:03	48.30	OK	7710	2026-09-15 19:04	47.25	OK
7711	2026-09-15 19:05	48.44	OK	7712	2026-09-15 19:06	49.32	OK
7713	2026-09-15 19:07	47.19	OK	7714	2026-09-15 19:08	48.45	OK
7715	2026-09-15 19:09	49.09	OK	7716	2026-09-15 19:10	49.32	OK
7717	2026-09-15 19:11	49.01	OK	7718	2026-09-15 19:12	48.41	OK
7719	2026-09-15 19:13	49.35	OK	7720	2026-09-15 19:14	48.30	OK
7721	2026-09-15 19:15	46.95	OK	7722	2026-09-15 19:16	49.29	OK
7723	2026-09-15 19:17	49.57	OK	7724	2026-09-15 19:18	48.28	OK
7725	2026-09-15 19:19	49.35	OK	7726	2026-09-15 19:20	50.40	OK
7727	2026-09-15 19:21	47.19	OK	7728	2026-09-15 19:22	48.61	OK
7729	2026-09-15 19:23	49.08	OK	7730	2026-09-15 19:24	48.43	OK
7731	2026-09-15 19:25	49.05	OK	7732	2026-09-15 19:26	47.78	OK
7733	2026-09-15 19:27	48.83	OK	7734	2026-09-15 19:28	47.91	OK
7735	2026-09-15 19:29	48.60	OK	7736	2026-09-15 19:30	48.04	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7737	2026-09-15 19:31	51.05	OK	7738	2026-09-15 19:32	47.96	OK
7739	2026-09-15 19:33	48.58	OK	7740	2026-09-15 19:34	48.99	OK
7741	2026-09-15 19:35	47.84	OK	7742	2026-09-15 19:36	48.75	OK
7743	2026-09-15 19:37	47.04	OK	7744	2026-09-15 19:38	48.84	OK
7745	2026-09-15 19:39	47.73	OK	7746	2026-09-15 19:40	47.22	OK
7747	2026-09-15 19:41	48.63	OK	7748	2026-09-15 19:42	48.38	OK
7749	2026-09-15 19:43	48.83	OK	7750	2026-09-15 19:44	47.49	OK
7751	2026-09-15 19:45	47.99	OK	7752	2026-09-15 19:46	49.40	OK
7753	2026-09-15 19:47	49.01	OK	7754	2026-09-15 19:48	49.08	OK
7755	2026-09-15 19:49	47.70	OK	7756	2026-09-15 19:50	48.68	OK
7757	2026-09-15 19:51	46.90	OK	7758	2026-09-15 19:52	48.12	OK
7759	2026-09-15 19:53	49.52	OK	7760	2026-09-15 19:54	47.68	OK
7761	2026-09-15 19:55	46.67	OK	7762	2026-09-15 19:56	46.37	OK
7763	2026-09-15 19:57	49.64	OK	7764	2026-09-15 19:58	46.85	OK
7765	2026-09-15 19:59	47.23	OK	7766	2026-09-15 20:00	47.35	OK
7767	2026-09-15 20:01	48.52	OK	7768	2026-09-15 20:02	48.69	OK
7769	2026-09-15 20:03	47.60	OK	7770	2026-09-15 20:04	48.56	OK
7771	2026-09-15 20:05	47.63	OK	7772	2026-09-15 20:06	48.39	OK
7773	2026-09-15 20:07	47.22	OK	7774	2026-09-15 20:08	48.15	OK
7775	2026-09-15 20:09	45.59	OK	7776	2026-09-15 20:10	47.63	OK
7777	2026-09-15 20:11	46.05	OK	7778	2026-09-15 20:12	47.97	OK
7779	2026-09-15 20:13	48.47	OK	7780	2026-09-15 20:14	46.52	OK
7781	2026-09-15 20:15	48.12	OK	7782	2026-09-15 20:16	47.88	OK
7783	2026-09-15 20:17	47.12	OK	7784	2026-09-15 20:18	48.47	OK
7785	2026-09-15 20:19	48.97	OK	7786	2026-09-15 20:20	48.94	OK
7787	2026-09-15 20:21	47.18	OK	7788	2026-09-15 20:22	48.61	OK
7789	2026-09-15 20:23	48.25	OK	7790	2026-09-15 20:24	49.90	OK
7791	2026-09-15 20:25	47.13	OK	7792	2026-09-15 20:26	47.31	OK
7793	2026-09-15 20:27	46.20	OK	7794	2026-09-15 20:28	47.43	OK
7795	2026-09-15 20:29	48.57	OK	7796	2026-09-15 20:30	48.32	OK
7797	2026-09-15 20:31	49.17	OK	7798	2026-09-15 20:32	47.02	OK
7799	2026-09-15 20:33	47.50	OK	7800	2026-09-15 20:34	47.51	OK
7801	2026-09-15 20:35	46.91	OK	7802	2026-09-15 20:36	46.65	OK
7803	2026-09-15 20:37	46.99	OK	7804	2026-09-15 20:38	47.04	OK
7805	2026-09-15 20:39	48.17	OK	7806	2026-09-15 20:40	47.07	OK
7807	2026-09-15 20:41	47.75	OK	7808	2026-09-15 20:42	46.74	OK
7809	2026-09-15 20:43	47.32	OK	7810	2026-09-15 20:44	49.02	OK
7811	2026-09-15 20:45	48.02	OK	7812	2026-09-15 20:46	49.96	OK
7813	2026-09-15 20:47	47.52	OK	7814	2026-09-15 20:48	47.01	OK
7815	2026-09-15 20:49	47.21	OK	7816	2026-09-15 20:50	46.39	OK
7817	2026-09-15 20:51	48.15	OK	7818	2026-09-15 20:52	46.58	OK
7819	2026-09-15 20:53	48.50	OK	7820	2026-09-15 20:54	46.53	OK
7821	2026-09-15 20:55	45.67	OK	7822	2026-09-15 20:56	46.72	OK
7823	2026-09-15 20:57	47.46	OK	7824	2026-09-15 20:58	46.64	OK
7825	2026-09-15 20:59	47.18	OK	7826	2026-09-15 21:00	46.26	OK
7827	2026-09-15 21:01	47.83	OK	7828	2026-09-15 21:02	47.40	OK
7829	2026-09-15 21:03	44.77	OK	7830	2026-09-15 21:04	47.27	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7831	2026-09-15 21:05	48.22	OK	7832	2026-09-15 21:06	46.88	OK
7833	2026-09-15 21:07	45.61	OK	7834	2026-09-15 21:08	46.99	OK
7835	2026-09-15 21:09	49.17	OK	7836	2026-09-15 21:10	46.12	OK
7837	2026-09-15 21:11	46.83	OK	7838	2026-09-15 21:12	48.10	OK
7839	2026-09-15 21:13	46.47	OK	7840	2026-09-15 21:14	45.20	OK
7841	2026-09-15 21:15	46.32	OK	7842	2026-09-15 21:16	47.87	OK
7843	2026-09-15 21:17	49.12	OK	7844	2026-09-15 21:18	47.36	OK
7845	2026-09-15 21:19	47.90	OK	7846	2026-09-15 21:20	48.78	OK
7847	2026-09-15 21:21	47.83	OK	7848	2026-09-15 21:22	46.41	OK
7849	2026-09-15 21:23	48.44	OK	7850	2026-09-15 21:24	47.90	OK
7851	2026-09-15 21:25	48.48	OK	7852	2026-09-15 21:26	46.44	OK
7853	2026-09-15 21:27	48.07	OK	7854	2026-09-15 21:28	45.86	OK
7855	2026-09-15 21:29	46.49	OK	7856	2026-09-15 21:30	47.43	OK
7857	2026-09-15 21:31	46.32	OK	7858	2026-09-15 21:32	48.23	OK
7859	2026-09-15 21:33	44.83	OK	7860	2026-09-15 21:34	47.52	OK
7861	2026-09-15 21:35	47.45	OK	7862	2026-09-15 21:36	46.39	OK
7863	2026-09-15 21:37	47.85	OK	7864	2026-09-15 21:38	48.51	OK
7865	2026-09-15 21:39	47.54	OK	7866	2026-09-15 21:40	46.64	OK
7867	2026-09-15 21:41	46.48	OK	7868	2026-09-15 21:42	47.81	OK
7869	2026-09-15 21:43	47.73	OK	7870	2026-09-15 21:44	45.36	OK
7871	2026-09-15 21:45	47.24	OK	7872	2026-09-15 21:46	45.71	OK
7873	2026-09-15 21:47	45.15	OK	7874	2026-09-15 21:48	45.85	OK
7875	2026-09-15 21:49	45.55	OK	7876	2026-09-15 21:50	46.77	OK
7877	2026-09-15 21:51	47.25	OK	7878	2026-09-15 21:52	47.33	OK
7879	2026-09-15 21:53	47.65	OK	7880	2026-09-15 21:54	48.18	OK
7881	2026-09-15 21:55	46.75	OK	7882	2026-09-15 21:56	46.45	OK
7883	2026-09-15 21:57	47.86	OK	7884	2026-09-15 21:58	46.80	OK
7885	2026-09-15 21:59	45.10	OK	7886	2026-09-15 22:00	46.00	OK
7887	2026-09-15 22:01	46.00	OK	7888	2026-09-15 22:02	47.17	OK
7889	2026-09-15 22:03	47.39	OK	7890	2026-09-15 22:04	46.03	OK
7891	2026-09-15 22:05	47.71	OK	7892	2026-09-15 22:06	45.35	OK
7893	2026-09-15 22:07	46.81	OK	7894	2026-09-15 22:08	46.05	OK
7895	2026-09-15 22:09	45.32	OK	7896	2026-09-15 22:10	47.56	OK
7897	2026-09-15 22:11	45.85	OK	7898	2026-09-15 22:12	46.39	OK
7899	2026-09-15 22:13	46.06	OK	7900	2026-09-15 22:14	45.76	OK
7901	2026-09-15 22:15	46.36	OK	7902	2026-09-15 22:16	46.43	OK
7903	2026-09-15 22:17	44.91	OK	7904	2026-09-15 22:18	47.03	OK
7905	2026-09-15 22:19	46.62	OK	7906	2026-09-15 22:20	46.72	OK
7907	2026-09-15 22:21	46.90	OK	7908	2026-09-15 22:22	46.04	OK
7909	2026-09-15 22:23	47.56	OK	7910	2026-09-15 22:24	46.80	OK
7911	2026-09-15 22:25	46.24	OK	7912	2026-09-15 22:26	45.61	OK
7913	2026-09-15 22:27	47.39	OK	7914	2026-09-15 22:28	45.93	OK
7915	2026-09-15 22:29	45.44	OK	7916	2026-09-15 22:30	45.96	OK
7917	2026-09-15 22:31	46.23	OK	7918	2026-09-15 22:32	44.16	OK
7919	2026-09-15 22:33	45.21	OK	7920	2026-09-15 22:34	43.65	OK
7921	2026-09-15 22:35	46.00	OK	7922	2026-09-15 22:36	44.82	OK
7923	2026-09-15 22:37	47.34	OK	7924	2026-09-15 22:38	45.21	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7925	2026-09-15 22:39	46.11	OK	7926	2026-09-15 22:40	43.50	OK
7927	2026-09-15 22:41	45.63	OK	7928	2026-09-15 22:42	46.68	OK
7929	2026-09-15 22:43	45.16	OK	7930	2026-09-15 22:44	45.13	OK
7931	2026-09-15 22:45	46.22	OK	7932	2026-09-15 22:46	44.62	OK
7933	2026-09-15 22:47	45.32	OK	7934	2026-09-15 22:48	43.53	OK
7935	2026-09-15 22:49	46.05	OK	7936	2026-09-15 22:50	43.82	OK
7937	2026-09-15 22:51	46.70	OK	7938	2026-09-15 22:52	47.06	OK
7939	2026-09-15 22:53	45.26	OK	7940	2026-09-15 22:54	46.25	OK
7941	2026-09-15 22:55	46.33	OK	7942	2026-09-15 22:56	46.25	OK
7943	2026-09-15 22:57	44.46	OK	7944	2026-09-15 22:58	46.14	OK
7945	2026-09-15 22:59	47.29	OK	7946	2026-09-15 23:00	46.88	OK
7947	2026-09-15 23:01	48.28	OK	7948	2026-09-15 23:02	45.93	OK
7949	2026-09-15 23:03	45.15	OK	7950	2026-09-15 23:04	46.26	OK
7951	2026-09-15 23:05	44.23	OK	7952	2026-09-15 23:06	45.75	OK
7953	2026-09-15 23:07	45.71	OK	7954	2026-09-15 23:08	44.47	OK
7955	2026-09-15 23:09	45.74	OK	7956	2026-09-15 23:10	45.46	OK
7957	2026-09-15 23:11	45.49	OK	7958	2026-09-15 23:12	48.16	OK
7959	2026-09-15 23:13	46.26	OK	7960	2026-09-15 23:14	45.15	OK
7961	2026-09-15 23:15	45.08	OK	7962	2026-09-15 23:16	45.00	OK
7963	2026-09-15 23:17	47.19	OK	7964	2026-09-15 23:18	47.35	OK
7965	2026-09-15 23:19	47.01	OK	7966	2026-09-15 23:20	43.28	OK
7967	2026-09-15 23:21	45.79	OK	7968	2026-09-15 23:22	46.59	OK
7969	2026-09-15 23:23	45.82	OK	7970	2026-09-15 23:24	46.23	OK
7971	2026-09-15 23:25	45.17	OK	7972	2026-09-15 23:26	46.03	OK
7973	2026-09-15 23:27	44.86	OK	7974	2026-09-15 23:28	43.97	OK
7975	2026-09-15 23:29	44.15	OK	7976	2026-09-15 23:30	46.25	OK
7977	2026-09-15 23:31	44.20	OK	7978	2026-09-15 23:32	46.74	OK
7979	2026-09-15 23:33	44.72	OK	7980	2026-09-15 23:34	46.05	OK
7981	2026-09-15 23:35	45.24	OK	7982	2026-09-15 23:36	46.57	OK
7983	2026-09-15 23:37	43.85	OK	7984	2026-09-15 23:38	46.15	OK
7985	2026-09-15 23:39	42.96	OK	7986	2026-09-15 23:40	45.78	OK
7987	2026-09-15 23:41	46.53	OK	7988	2026-09-15 23:42	47.00	OK
7989	2026-09-15 23:43	44.62	OK	7990	2026-09-15 23:44	45.24	OK
7991	2026-09-15 23:45	45.58	OK	7992	2026-09-15 23:46	46.76	OK
7993	2026-09-15 23:47	45.65	OK	7994	2026-09-15 23:48	45.53	OK
7995	2026-09-15 23:49	44.56	OK	7996	2026-09-15 23:50	44.60	OK
7997	2026-09-15 23:51	46.90	OK	7998	2026-09-15 23:52	45.67	OK
7999	2026-09-15 23:53	45.42	OK	8000	2026-09-15 23:54	44.64	OK
8001	2026-09-15 23:55	45.14	OK	8002	2026-09-15 23:56	45.34	OK
8003	2026-09-15 23:57	44.95	OK	8004	2026-09-15 23:58	45.01	OK
8005	2026-09-15 23:59	45.77	OK	8006	2026-09-16 00:00	44.63	OK
8007	2026-09-16 00:01	46.12	OK	8008	2026-09-16 00:02	44.67	OK
8009	2026-09-16 00:03	43.33	OK	8010	2026-09-16 00:04	45.64	OK
8011	2026-09-16 00:05	44.90	OK	8012	2026-09-16 00:06	44.19	OK
8013	2026-09-16 00:07	46.07	OK	8014	2026-09-16 00:08	47.17	OK
8015	2026-09-16 00:09	44.54	OK	8016	2026-09-16 00:10	46.01	OK
8017	2026-09-16 00:11	46.32	OK	8018	2026-09-16 00:12	46.49	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8019	2026-09-16 00:13	46.52	OK	8020	2026-09-16 00:14	44.56	OK
8021	2026-09-16 00:15	44.51	OK	8022	2026-09-16 00:16	44.63	OK
8023	2026-09-16 00:17	45.21	OK	8024	2026-09-16 00:18	46.12	OK
8025	2026-09-16 00:19	45.92	OK	8026	2026-09-16 00:20	44.87	OK
8027	2026-09-16 00:21	46.01	OK	8028	2026-09-16 00:22	46.23	OK
8029	2026-09-16 00:23	45.10	OK	8030	2026-09-16 00:24	46.44	OK
8031	2026-09-16 00:25	43.19	OK	8032	2026-09-16 00:26	46.44	OK
8033	2026-09-16 00:27	44.81	OK	8034	2026-09-16 00:28	44.99	OK
8035	2026-09-16 00:29	45.91	OK	8036	2026-09-16 00:30	46.21	OK
8037	2026-09-16 00:31	45.64	OK	8038	2026-09-16 00:32	44.93	OK
8039	2026-09-16 00:33	45.23	OK	8040	2026-09-16 00:34	45.86	OK
8041	2026-09-16 00:35	45.72	OK	8042	2026-09-16 00:36	45.40	OK
8043	2026-09-16 00:37	43.94	OK	8044	2026-09-16 00:38	45.45	OK
8045	2026-09-16 00:39	45.40	OK	8046	2026-09-16 00:40	45.12	OK
8047	2026-09-16 00:41	44.03	OK	8048	2026-09-16 00:42	46.37	OK
8049	2026-09-16 00:43	45.34	OK	8050	2026-09-16 00:44	44.59	OK
8051	2026-09-16 00:45	45.77	OK	8052	2026-09-16 00:46	45.78	OK
8053	2026-09-16 00:47	45.43	OK	8054	2026-09-16 00:48	45.11	OK
8055	2026-09-16 00:49	43.20	OK	8056	2026-09-16 00:50	45.51	OK
8057	2026-09-16 00:51	44.63	OK	8058	2026-09-16 00:52	44.32	OK
8059	2026-09-16 00:53	45.21	OK	8060	2026-09-16 00:54	44.57	OK
8061	2026-09-16 00:55	44.68	OK	8062	2026-09-16 00:56	44.80	OK
8063	2026-09-16 00:57	45.15	OK	8064	2026-09-16 00:58	45.74	OK
8065	2026-09-16 00:59	44.79	OK	8066	2026-09-16 01:00	45.30	OK
8067	2026-09-16 01:01	46.07	OK	8068	2026-09-16 01:02	44.50	OK
8069	2026-09-16 01:03	44.07	OK	8070	2026-09-16 01:04	43.43	OK
8071	2026-09-16 01:05	43.82	OK	8072	2026-09-16 01:06	46.83	OK
8073	2026-09-16 01:07	45.18	OK	8074	2026-09-16 01:08	43.92	OK
8075	2026-09-16 01:09	44.13	OK	8076	2026-09-16 01:10	44.94	OK
8077	2026-09-16 01:11	46.84	OK	8078	2026-09-16 01:12	44.70	OK
8079	2026-09-16 01:13	45.10	OK	8080	2026-09-16 01:14	45.23	OK
8081	2026-09-16 01:15	43.75	OK	8082	2026-09-16 01:16	45.64	OK
8083	2026-09-16 01:17	44.30	OK	8084	2026-09-16 01:18	45.51	OK
8085	2026-09-16 01:19	44.97	OK	8086	2026-09-16 01:20	43.89	OK
8087	2026-09-16 01:21	45.37	OK	8088	2026-09-16 01:22	44.04	OK
8089	2026-09-16 01:23	44.14	OK	8090	2026-09-16 01:24	46.18	OK
8091	2026-09-16 01:25	44.58	OK	8092	2026-09-16 01:26	46.58	OK
8093	2026-09-16 01:27	44.52	OK	8094	2026-09-16 01:28	43.94	OK
8095	2026-09-16 01:29	45.80	OK	8096	2026-09-16 01:30	44.91	OK
8097	2026-09-16 01:31	47.40	OK	8098	2026-09-16 01:32	45.64	OK
8099	2026-09-16 01:33	44.58	OK	8100	2026-09-16 01:34	45.99	OK
8101	2026-09-16 01:35	45.24	OK	8102	2026-09-16 01:36	45.62	OK
8103	2026-09-16 01:37	45.84	OK	8104	2026-09-16 01:38	46.73	OK
8105	2026-09-16 01:39	47.49	OK	8106	2026-09-16 01:40	46.29	OK
8107	2026-09-16 01:41	47.04	OK	8108	2026-09-16 01:42	44.01	OK
8109	2026-09-16 01:43	44.26	OK	8110	2026-09-16 01:44	45.56	OK
8111	2026-09-16 01:45	45.48	OK	8112	2026-09-16 01:46	43.77	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8113	2026-09-16 01:47	46.68	OK	8114	2026-09-16 01:48	46.04	OK
8115	2026-09-16 01:49	44.95	OK	8116	2026-09-16 01:50	45.45	OK
8117	2026-09-16 01:51	43.49	OK	8118	2026-09-16 01:52	45.44	OK
8119	2026-09-16 01:53	45.82	OK	8120	2026-09-16 01:54	44.44	OK
8121	2026-09-16 01:55	44.33	OK	8122	2026-09-16 01:56	44.46	OK
8123	2026-09-16 01:57	46.12	OK	8124	2026-09-16 01:58	45.50	OK
8125	2026-09-16 01:59	43.27	OK	8126	2026-09-16 02:00	44.84	OK
8127	2026-09-16 02:01	45.37	OK	8128	2026-09-16 02:02	45.60	OK
8129	2026-09-16 02:03	46.56	OK	8130	2026-09-16 02:04	44.19	OK
8131	2026-09-16 02:05	46.96	OK	8132	2026-09-16 02:06	44.45	OK
8133	2026-09-16 02:07	46.02	OK	8134	2026-09-16 02:08	43.60	OK
8135	2026-09-16 02:09	46.75	OK	8136	2026-09-16 02:10	45.22	OK
8137	2026-09-16 02:11	43.25	OK	8138	2026-09-16 02:12	44.58	OK
8139	2026-09-16 02:13	45.13	OK	8140	2026-09-16 02:14	45.87	OK
8141	2026-09-16 02:15	45.02	OK	8142	2026-09-16 02:16	44.09	OK
8143	2026-09-16 02:17	46.12	OK	8144	2026-09-16 02:18	45.35	OK
8145	2026-09-16 02:19	46.77	OK	8146	2026-09-16 02:20	44.72	OK
8147	2026-09-16 02:21	45.96	OK	8148	2026-09-16 02:22	45.25	OK
8149	2026-09-16 02:23	46.44	OK	8150	2026-09-16 02:24	45.10	OK
8151	2026-09-16 02:25	46.28	OK	8152	2026-09-16 02:26	46.31	OK
8153	2026-09-16 02:27	43.77	OK	8154	2026-09-16 02:28	43.06	OK
8155	2026-09-16 02:29	45.74	OK	8156	2026-09-16 02:30	44.70	OK
8157	2026-09-16 02:31	45.30	OK	8158	2026-09-16 02:32	44.64	OK
8159	2026-09-16 02:33	44.40	OK	8160	2026-09-16 02:34	46.28	OK
8161	2026-09-16 02:35	44.64	OK	8162	2026-09-16 02:36	46.35	OK
8163	2026-09-16 02:37	44.60	OK	8164	2026-09-16 02:38	45.27	OK
8165	2026-09-16 02:39	43.52	OK	8166	2026-09-16 02:40	44.79	OK
8167	2026-09-16 02:41	45.82	OK	8168	2026-09-16 02:42	46.49	OK
8169	2026-09-16 02:43	47.02	OK	8170	2026-09-16 02:44	45.89	OK
8171	2026-09-16 02:45	45.27	OK	8172	2026-09-16 02:46	47.08	OK
8173	2026-09-16 02:47	43.56	OK	8174	2026-09-16 02:48	45.50	OK
8175	2026-09-16 02:49	45.74	OK	8176	2026-09-16 02:50	45.15	OK
8177	2026-09-16 02:51	42.84	OK	8178	2026-09-16 02:52	44.37	OK
8179	2026-09-16 02:53	46.69	OK	8180	2026-09-16 02:54	45.69	OK
8181	2026-09-16 02:55	45.35	OK	8182	2026-09-16 02:56	46.09	OK
8183	2026-09-16 02:57	44.41	OK	8184	2026-09-16 02:58	44.11	OK
8185	2026-09-16 02:59	46.30	OK	8186	2026-09-16 03:00	46.82	OK
8187	2026-09-16 03:01	45.95	OK	8188	2026-09-16 03:02	46.30	OK
8189	2026-09-16 03:03	44.61	OK	8190	2026-09-16 03:04	44.76	OK
8191	2026-09-16 03:05	44.58	OK	8192	2026-09-16 03:06	45.72	OK
8193	2026-09-16 03:07	45.18	OK	8194	2026-09-16 03:08	45.69	OK
8195	2026-09-16 03:09	46.35	OK	8196	2026-09-16 03:10	46.52	OK
8197	2026-09-16 03:11	43.77	OK	8198	2026-09-16 03:12	46.32	OK
8199	2026-09-16 03:13	46.60	OK	8200	2026-09-16 03:14	45.64	OK
8201	2026-09-16 03:15	45.38	OK	8202	2026-09-16 03:16	46.61	OK
8203	2026-09-16 03:17	44.53	OK	8204	2026-09-16 03:18	45.16	OK
8205	2026-09-16 03:19	44.49	OK	8206	2026-09-16 03:20	44.81	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8207	2026-09-16 03:21	45.17	OK	8208	2026-09-16 03:22	47.16	OK
8209	2026-09-16 03:23	45.77	OK	8210	2026-09-16 03:24	46.67	OK
8211	2026-09-16 03:25	46.29	OK	8212	2026-09-16 03:26	45.35	OK
8213	2026-09-16 03:27	46.12	OK	8214	2026-09-16 03:28	47.62	OK
8215	2026-09-16 03:29	45.06	OK	8216	2026-09-16 03:30	46.59	OK
8217	2026-09-16 03:31	45.44	OK	8218	2026-09-16 03:32	46.26	OK
8219	2026-09-16 03:33	45.71	OK	8220	2026-09-16 03:34	45.70	OK
8221	2026-09-16 03:35	44.49	OK	8222	2026-09-16 03:36	45.38	OK
8223	2026-09-16 03:37	43.68	OK	8224	2026-09-16 03:38	43.90	OK
8225	2026-09-16 03:39	45.77	OK	8226	2026-09-16 03:40	45.93	OK
8227	2026-09-16 03:41	46.95	OK	8228	2026-09-16 03:42	43.65	OK
8229	2026-09-16 03:43	44.82	OK	8230	2026-09-16 03:44	47.26	OK
8231	2026-09-16 03:45	44.97	OK	8232	2026-09-16 03:46	45.45	OK
8233	2026-09-16 03:47	47.62	OK	8234	2026-09-16 03:48	46.22	OK
8235	2026-09-16 03:49	47.43	OK	8236	2026-09-16 03:50	45.48	OK
8237	2026-09-16 03:51	46.36	OK	8238	2026-09-16 03:52	46.37	OK
8239	2026-09-16 03:53	46.90	OK	8240	2026-09-16 03:54	44.61	OK
8241	2026-09-16 03:55	45.05	OK	8242	2026-09-16 03:56	46.03	OK
8243	2026-09-16 03:57	45.71	OK	8244	2026-09-16 03:58	46.47	OK
8245	2026-09-16 03:59	47.16	OK	8246	2026-09-16 04:00	45.74	OK
8247	2026-09-16 04:01	44.57	OK	8248	2026-09-16 04:02	45.71	OK
8249	2026-09-16 04:03	46.81	OK	8250	2026-09-16 04:04	46.82	OK
8251	2026-09-16 04:05	45.72	OK	8252	2026-09-16 04:06	47.92	OK
8253	2026-09-16 04:07	46.91	OK	8254	2026-09-16 04:08	44.46	OK
8255	2026-09-16 04:09	45.12	OK	8256	2026-09-16 04:10	45.80	OK
8257	2026-09-16 04:11	45.98	OK	8258	2026-09-16 04:12	48.33	OK
8259	2026-09-16 04:13	45.83	OK	8260	2026-09-16 04:14	45.53	OK
8261	2026-09-16 04:15	44.99	OK	8262	2026-09-16 04:16	48.10	OK
8263	2026-09-16 04:17	45.85	OK	8264	2026-09-16 04:18	46.31	OK
8265	2026-09-16 04:19	46.26	OK	8266	2026-09-16 04:20	45.71	OK
8267	2026-09-16 04:21	44.61	OK	8268	2026-09-16 04:22	45.98	OK
8269	2026-09-16 04:23	47.58	OK	8270	2026-09-16 04:24	46.37	OK
8271	2026-09-16 04:25	46.99	OK	8272	2026-09-16 04:26	46.53	OK
8273	2026-09-16 04:27	46.63	OK	8274	2026-09-16 04:28	44.74	OK
8275	2026-09-16 04:29	46.96	OK	8276	2026-09-16 04:30	46.42	OK
8277	2026-09-16 04:31	46.38	OK	8278	2026-09-16 04:32	46.31	OK
8279	2026-09-16 04:33	45.01	OK	8280	2026-09-16 04:34	45.93	OK
8281	2026-09-16 04:35	46.69	OK	8282	2026-09-16 04:36	44.58	OK
8283	2026-09-16 04:37	47.87	OK	8284	2026-09-16 04:38	45.24	OK
8285	2026-09-16 04:39	46.68	OK	8286	2026-09-16 04:40	47.35	OK
8287	2026-09-16 04:41	47.20	OK	8288	2026-09-16 04:42	47.56	OK
8289	2026-09-16 04:43	46.53	OK	8290	2026-09-16 04:44	46.83	OK
8291	2026-09-16 04:45	45.47	OK	8292	2026-09-16 04:46	47.21	OK
8293	2026-09-16 04:47	47.74	OK	8294	2026-09-16 04:48	46.00	OK
8295	2026-09-16 04:49	46.71	OK	8296	2026-09-16 04:50	46.27	OK
8297	2026-09-16 04:51	46.70	OK	8298	2026-09-16 04:52	45.70	OK
8299	2026-09-16 04:53	46.47	OK	8300	2026-09-16 04:54	45.39	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8301	2026-09-16 04:55	46.53	OK	8302	2026-09-16 04:56	45.50	OK
8303	2026-09-16 04:57	46.43	OK	8304	2026-09-16 04:58	46.62	OK
8305	2026-09-16 04:59	45.34	OK	8306	2026-09-16 05:00	46.89	OK
8307	2026-09-16 05:01	45.71	OK	8308	2026-09-16 05:02	45.93	OK
8309	2026-09-16 05:03	46.89	OK	8310	2026-09-16 05:04	44.40	OK
8311	2026-09-16 05:05	46.89	OK	8312	2026-09-16 05:06	47.94	OK
8313	2026-09-16 05:07	45.83	OK	8314	2026-09-16 05:08	46.94	OK
8315	2026-09-16 05:09	45.37	OK	8316	2026-09-16 05:10	46.14	OK
8317	2026-09-16 05:11	45.07	OK	8318	2026-09-16 05:12	47.60	OK
8319	2026-09-16 05:13	46.31	OK	8320	2026-09-16 05:14	45.94	OK
8321	2026-09-16 05:15	47.92	OK	8322	2026-09-16 05:16	46.88	OK
8323	2026-09-16 05:17	46.81	OK	8324	2026-09-16 05:18	46.73	OK
8325	2026-09-16 05:19	45.25	OK	8326	2026-09-16 05:20	45.68	OK
8327	2026-09-16 05:21	48.12	OK	8328	2026-09-16 05:22	45.13	OK
8329	2026-09-16 05:23	46.77	OK	8330	2026-09-16 05:24	47.15	OK
8331	2026-09-16 05:25	47.05	OK	8332	2026-09-16 05:26	46.10	OK
8333	2026-09-16 05:27	46.73	OK	8334	2026-09-16 05:28	46.73	OK
8335	2026-09-16 05:29	47.79	OK	8336	2026-09-16 05:30	46.76	OK
8337	2026-09-16 05:31	47.34	OK	8338	2026-09-16 05:32	47.12	OK
8339	2026-09-16 05:33	46.79	OK	8340	2026-09-16 05:34	48.99	OK
8341	2026-09-16 05:35	45.93	OK	8342	2026-09-16 05:36	45.39	OK
8343	2026-09-16 05:37	47.98	OK	8344	2026-09-16 05:38	46.83	OK
8345	2026-09-16 05:39	46.12	OK	8346	2026-09-16 05:40	46.33	OK
8347	2026-09-16 05:41	45.88	OK	8348	2026-09-16 05:42	46.17	OK
8349	2026-09-16 05:43	46.63	OK	8350	2026-09-16 05:44	48.45	OK
8351	2026-09-16 05:45	47.29	OK	8352	2026-09-16 05:46	46.31	OK
8353	2026-09-16 05:47	46.19	OK	8354	2026-09-16 05:48	47.72	OK
8355	2026-09-16 05:49	46.85	OK	8356	2026-09-16 05:50	48.22	OK
8357	2026-09-16 05:51	48.10	OK	8358	2026-09-16 05:52	48.33	OK
8359	2026-09-16 05:53	47.79	OK	8360	2026-09-16 05:54	46.61	OK
8361	2026-09-16 05:55	47.71	OK	8362	2026-09-16 05:56	46.82	OK
8363	2026-09-16 05:57	46.25	OK	8364	2026-09-16 05:58	45.48	OK
8365	2026-09-16 05:59	47.84	OK	8366	2026-09-16 06:00	48.23	OK
8367	2026-09-16 06:01	47.90	OK	8368	2026-09-16 06:02	48.15	OK
8369	2026-09-16 06:03	47.05	OK	8370	2026-09-16 06:04	49.72	OK
8371	2026-09-16 06:05	48.76	OK	8372	2026-09-16 06:06	48.63	OK
8373	2026-09-16 06:07	48.59	OK	8374	2026-09-16 06:08	47.54	OK
8375	2026-09-16 06:09	46.67	OK	8376	2026-09-16 06:10	45.58	OK
8377	2026-09-16 06:11	46.44	OK	8378	2026-09-16 06:12	48.02	OK
8379	2026-09-16 06:13	46.54	OK	8380	2026-09-16 06:14	46.56	OK
8381	2026-09-16 06:15	49.33	OK	8382	2026-09-16 06:16	48.30	OK
8383	2026-09-16 06:17	48.74	OK	8384	2026-09-16 06:18	47.85	OK
8385	2026-09-16 06:19	47.36	OK	8386	2026-09-16 06:20	46.84	OK
8387	2026-09-16 06:21	47.31	OK	8388	2026-09-16 06:22	48.28	OK
8389	2026-09-16 06:23	48.80	OK	8390	2026-09-16 06:24	46.55	OK
8391	2026-09-16 06:25	48.78	OK	8392	2026-09-16 06:26	48.10	OK
8393	2026-09-16 06:27	48.66	OK	8394	2026-09-16 06:28	47.80	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8395	2026-09-16 06:29	47.07	OK	8396	2026-09-16 06:30	47.69	OK
8397	2026-09-16 06:31	48.27	OK	8398	2026-09-16 06:32	49.47	OK
8399	2026-09-16 06:33	49.30	OK	8400	2026-09-16 06:34	47.86	OK
8401	2026-09-16 06:35	49.10	OK	8402	2026-09-16 06:36	46.02	OK
8403	2026-09-16 06:37	48.20	OK	8404	2026-09-16 06:38	48.05	OK
8405	2026-09-16 06:39	47.62	OK	8406	2026-09-16 06:40	48.52	OK
8407	2026-09-16 06:41	47.81	OK	8408	2026-09-16 06:42	46.92	OK
8409	2026-09-16 06:43	46.72	OK	8410	2026-09-16 06:44	47.60	OK
8411	2026-09-16 06:45	49.02	OK	8412	2026-09-16 06:46	47.93	OK
8413	2026-09-16 06:47	47.81	OK	8414	2026-09-16 06:48	46.63	OK
8415	2026-09-16 06:49	47.02	OK	8416	2026-09-16 06:50	49.62	OK
8417	2026-09-16 06:51	47.77	OK	8418	2026-09-16 06:52	48.37	OK
8419	2026-09-16 06:53	48.56	OK	8420	2026-09-16 06:54	48.47	OK
8421	2026-09-16 06:55	47.14	OK	8422	2026-09-16 06:56	48.68	OK
8423	2026-09-16 06:57	48.61	OK	8424	2026-09-16 06:58	49.87	OK
8425	2026-09-16 06:59	47.37	OK	8426	2026-09-16 07:00	49.01	OK
8427	2026-09-16 07:01	49.48	OK	8428	2026-09-16 07:02	49.24	OK
8429	2026-09-16 07:03	47.67	OK	8430	2026-09-16 07:04	47.47	OK
8431	2026-09-16 07:05	48.48	OK	8432	2026-09-16 07:06	49.48	OK
8433	2026-09-16 07:07	49.11	OK	8434	2026-09-16 07:08	49.39	OK
8435	2026-09-16 07:09	48.39	OK	8436	2026-09-16 07:10	47.12	OK
8437	2026-09-16 07:11	47.98	OK	8438	2026-09-16 07:12	48.71	OK
8439	2026-09-16 07:13	48.24	OK	8440	2026-09-16 07:14	49.31	OK
8441	2026-09-16 07:15	49.37	OK	8442	2026-09-16 07:16	48.43	OK
8443	2026-09-16 07:17	49.78	OK	8444	2026-09-16 07:18	48.05	OK
8445	2026-09-16 07:19	48.75	OK	8446	2026-09-16 07:20	48.59	OK
8447	2026-09-16 07:21	49.84	OK	8448	2026-09-16 07:22	48.72	OK
8449	2026-09-16 07:23	50.02	OK	8450	2026-09-16 07:24	48.77	OK
8451	2026-09-16 07:25	48.20	OK	8452	2026-09-16 07:26	46.70	OK
8453	2026-09-16 07:27	50.30	OK	8454	2026-09-16 07:28	49.72	OK
8455	2026-09-16 07:29	48.99	OK	8456	2026-09-16 07:30	48.61	OK
8457	2026-09-16 07:31	48.84	OK	8458	2026-09-16 07:32	47.83	OK
8459	2026-09-16 07:33	50.04	OK	8460	2026-09-16 07:34	49.02	OK
8461	2026-09-16 07:35	49.26	OK	8462	2026-09-16 07:36	48.29	OK
8463	2026-09-16 07:37	49.77	OK	8464	2026-09-16 07:38	49.05	OK
8465	2026-09-16 07:39	48.31	OK	8466	2026-09-16 07:40	49.67	OK
8467	2026-09-16 07:41	49.51	OK	8468	2026-09-16 07:42	49.29	OK
8469	2026-09-16 07:43	50.39	OK	8470	2026-09-16 07:44	45.91	OK
8471	2026-09-16 07:45	49.68	OK	8472	2026-09-16 07:46	48.92	OK
8473	2026-09-16 07:47	48.26	OK	8474	2026-09-16 07:48	48.83	OK
8475	2026-09-16 07:49	47.11	OK	8476	2026-09-16 07:50	48.88	OK
8477	2026-09-16 07:51	49.23	OK	8478	2026-09-16 07:52	47.74	OK
8479	2026-09-16 07:53	49.61	OK	8480	2026-09-16 07:54	49.08	OK
8481	2026-09-16 07:55	48.33	OK	8482	2026-09-16 07:56	47.51	OK
8483	2026-09-16 07:57	49.54	OK	8484	2026-09-16 07:58	48.74	OK
8485	2026-09-16 07:59	48.97	OK	8486	2026-09-16 08:00	47.95	OK
8487	2026-09-16 08:01	51.28	OK	8488	2026-09-16 08:02	47.66	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8489	2026-09-16 08:03	49.73	OK	8490	2026-09-16 08:04	49.18	OK
8491	2026-09-16 08:05	50.63	OK	8492	2026-09-16 08:06	48.16	OK
8493	2026-09-16 08:07	49.54	OK	8494	2026-09-16 08:08	48.06	OK
8495	2026-09-16 08:09	48.74	OK	8496	2026-09-16 08:10	49.14	OK
8497	2026-09-16 08:11	50.74	OK	8498	2026-09-16 08:12	49.40	OK
8499	2026-09-16 08:13	49.72	OK	8500	2026-09-16 08:14	49.78	OK
8501	2026-09-16 08:15	49.47	OK	8502	2026-09-16 08:16	50.89	OK
8503	2026-09-16 08:17	49.17	OK	8504	2026-09-16 08:18	51.01	OK
8505	2026-09-16 08:19	49.72	OK	8506	2026-09-16 08:20	49.53	OK
8507	2026-09-16 08:21	48.59	OK	8508	2026-09-16 08:22	48.26	OK
8509	2026-09-16 08:23	49.33	OK	8510	2026-09-16 08:24	50.14	OK
8511	2026-09-16 08:25	48.51	OK	8512	2026-09-16 08:26	50.24	OK
8513	2026-09-16 08:27	50.22	OK	8514	2026-09-16 08:28	48.06	OK
8515	2026-09-16 08:29	48.45	OK	8516	2026-09-16 08:30	50.19	OK
8517	2026-09-16 08:31	50.42	OK	8518	2026-09-16 08:32	48.44	OK
8519	2026-09-16 08:33	49.26	OK	8520	2026-09-16 08:34	47.64	OK
8521	2026-09-16 08:35	49.65	OK	8522	2026-09-16 08:36	49.06	OK
8523	2026-09-16 08:37	48.82	OK	8524	2026-09-16 08:38	49.18	OK
8525	2026-09-16 08:39	49.71	OK	8526	2026-09-16 08:40	50.09	OK
8527	2026-09-16 08:41	49.62	OK	8528	2026-09-16 08:42	50.90	OK
8529	2026-09-16 08:43	48.76	OK	8530	2026-09-16 08:44	48.81	OK
8531	2026-09-16 08:45	49.63	OK	8532	2026-09-16 08:46	49.69	OK
8533	2026-09-16 08:47	48.80	OK	8534	2026-09-16 08:48	50.63	OK
8535	2026-09-16 08:49	50.46	OK	8536	2026-09-16 08:50	50.43	OK
8537	2026-09-16 08:51	48.17	OK	8538	2026-09-16 08:52	50.68	OK
8539	2026-09-16 08:53	50.19	OK	8540	2026-09-16 08:54	49.07	OK
8541	2026-09-16 08:55	51.54	OK	8542	2026-09-16 08:56	48.91	OK
8543	2026-09-16 08:57	50.76	OK	8544	2026-09-16 08:58	50.66	OK
8545	2026-09-16 08:59	49.45	OK	8546	2026-09-16 09:00	50.24	OK
8547	2026-09-16 09:01	48.95	OK	8548	2026-09-16 09:02	50.67	OK
8549	2026-09-16 09:03	50.13	OK	8550	2026-09-16 09:04	51.04	OK
8551	2026-09-16 09:05	50.64	OK	8552	2026-09-16 09:06	50.93	OK
8553	2026-09-16 09:07	49.91	OK	8554	2026-09-16 09:08	50.45	OK
8555	2026-09-16 09:09	48.79	OK	8556	2026-09-16 09:10	50.76	OK
8557	2026-09-16 09:11	50.30	OK	8558	2026-09-16 09:12	48.54	OK
8559	2026-09-16 09:13	50.86	OK	8560	2026-09-16 09:14	51.77	OK
8561	2026-09-16 09:15	50.03	OK	8562	2026-09-16 09:16	49.99	OK
8563	2026-09-16 09:17	50.43	OK	8564	2026-09-16 09:18	50.63	OK
8565	2026-09-16 09:19	50.01	OK	8566	2026-09-16 09:20	51.02	OK
8567	2026-09-16 09:21	50.44	OK	8568	2026-09-16 09:22	50.56	OK
8569	2026-09-16 09:23	49.96	OK	8570	2026-09-16 09:24	50.31	OK
8571	2026-09-16 09:25	50.20	OK	8572	2026-09-16 09:26	50.67	OK
8573	2026-09-16 09:27	51.60	OK	8574	2026-09-16 09:28	49.61	OK
8575	2026-09-16 09:29	50.31	OK	8576	2026-09-16 09:30	49.17	OK
8577	2026-09-16 09:31	50.45	OK	8578	2026-09-16 09:32	50.47	OK
8579	2026-09-16 09:33	51.25	OK	8580	2026-09-16 09:34	52.09	OK
8581	2026-09-16 09:35	50.92	OK	8582	2026-09-16 09:36	48.88	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8583	2026-09-16 09:37	50.78	OK	8584	2026-09-16 09:38	49.96	OK
8585	2026-09-16 09:39	51.01	OK	8586	2026-09-16 09:40	52.97	OK
8587	2026-09-16 09:41	49.14	OK	8588	2026-09-16 09:42	48.23	OK
8589	2026-09-16 09:43	51.21	OK	8590	2026-09-16 09:44	50.20	OK
8591	2026-09-16 09:45	50.28	OK	8592	2026-09-16 09:46	49.42	OK
8593	2026-09-16 09:47	51.27	OK	8594	2026-09-16 09:48	49.76	OK
8595	2026-09-16 09:49	50.68	OK	8596	2026-09-16 09:50	49.32	OK
8597	2026-09-16 09:51	50.31	OK	8598	2026-09-16 09:52	51.45	OK
8599	2026-09-16 09:53	50.01	OK	8600	2026-09-16 09:54	50.51	OK
8601	2026-09-16 09:55	51.38	OK	8602	2026-09-16 09:56	50.97	OK
8603	2026-09-16 09:57	50.83	OK	8604	2026-09-16 09:58	51.60	OK
8605	2026-09-16 09:59	50.41	OK	8606	2026-09-16 10:00	50.14	OK
8607	2026-09-16 10:01	50.11	OK	8608	2026-09-16 10:02	48.73	OK
8609	2026-09-16 10:03	49.46	OK	8610	2026-09-16 10:04	48.90	OK
8611	2026-09-16 10:05	51.17	OK	8612	2026-09-16 10:06	49.66	OK
8613	2026-09-16 10:07	50.92	OK	8614	2026-09-16 10:08	51.49	OK
8615	2026-09-16 10:09	50.35	OK	8616	2026-09-16 10:10	50.66	OK
8617	2026-09-16 10:11	50.54	OK	8618	2026-09-16 10:12	50.46	OK
8619	2026-09-16 10:13	51.19	OK	8620	2026-09-16 10:14	49.93	OK
8621	2026-09-16 10:15	50.35	OK	8622	2026-09-16 10:16	51.83	OK
8623	2026-09-16 10:17	52.87	OK	8624	2026-09-16 10:18	53.13	OK
8625	2026-09-16 10:19	51.43	OK	8626	2026-09-16 10:20	51.26	OK
8627	2026-09-16 10:21	50.51	OK	8628	2026-09-16 10:22	50.44	OK
8629	2026-09-16 10:23	50.87	OK	8630	2026-09-16 10:24	48.82	OK
8631	2026-09-16 10:25	51.55	OK	8632	2026-09-16 10:26	49.49	OK
8633	2026-09-16 10:27	50.64	OK	8634	2026-09-16 10:28	49.72	OK
8635	2026-09-16 10:29	50.49	OK	8636	2026-09-16 10:30	49.51	OK
8637	2026-09-16 10:31	51.57	OK	8638	2026-09-16 10:32	50.44	OK
8639	2026-09-16 10:33	51.27	OK	8640	2026-09-16 10:34	50.64	OK
8641	2026-09-16 10:35	51.06	OK	8642	2026-09-16 10:36	49.16	OK
8643	2026-09-16 10:37	52.23	OK	8644	2026-09-16 10:38	51.34	OK
8645	2026-09-16 10:39	52.23	OK	8646	2026-09-16 10:40	50.53	OK
8647	2026-09-16 10:41	49.90	OK	8648	2026-09-16 10:42	49.90	OK
8649	2026-09-16 10:43	52.13	OK	8650	2026-09-16 10:44	50.02	OK
8651	2026-09-16 10:45	50.69	OK	8652	2026-09-16 10:46	49.97	OK
8653	2026-09-16 10:47	50.04	OK	8654	2026-09-16 10:48	48.75	OK
8655	2026-09-16 10:49	52.91	OK	8656	2026-09-16 10:50	50.68	OK
8657	2026-09-16 10:51	51.59	OK	8658	2026-09-16 10:52	51.85	OK
8659	2026-09-16 10:53	51.78	OK	8660	2026-09-16 10:54	52.00	OK
8661	2026-09-16 10:55	51.34	OK	8662	2026-09-16 10:56	52.13	OK
8663	2026-09-16 10:57	50.90	OK	8664	2026-09-16 10:58	52.42	OK
8665	2026-09-16 10:59	51.62	OK	8666	2026-09-16 11:00	51.30	OK
8667	2026-09-16 11:01	51.55	OK	8668	2026-09-16 11:02	52.23	OK
8669	2026-09-16 11:03	52.92	OK	8670	2026-09-16 11:04	51.51	OK
8671	2026-09-16 11:05	49.72	OK	8672	2026-09-16 11:06	50.87	OK
8673	2026-09-16 11:07	51.22	OK	8674	2026-09-16 11:08	50.36	OK
8675	2026-09-16 11:09	51.10	OK	8676	2026-09-16 11:10	51.71	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8677	2026-09-16 11:11	49.70	OK	8678	2026-09-16 11:12	51.61	OK
8679	2026-09-16 11:13	50.47	OK	8680	2026-09-16 11:14	52.91	OK
8681	2026-09-16 11:15	50.21	OK	8682	2026-09-16 11:16	51.11	OK
8683	2026-09-16 11:17	51.35	OK	8684	2026-09-16 11:18	50.64	OK
8685	2026-09-16 11:19	50.76	OK	8686	2026-09-16 11:20	51.44	OK
8687	2026-09-16 11:21	51.02	OK	8688	2026-09-16 11:22	50.70	OK
8689	2026-09-16 11:23	52.34	OK	8690	2026-09-16 11:24	50.61	OK
8691	2026-09-16 11:25	52.93	OK	8692	2026-09-16 11:26	53.01	OK
8693	2026-09-16 11:27	49.20	OK	8694	2026-09-16 11:28	51.88	OK
8695	2026-09-16 11:29	52.73	OK	8696	2026-09-16 11:30	52.67	OK
8697	2026-09-16 11:31	49.87	OK	8698	2026-09-16 11:32	52.07	OK
8699	2026-09-16 11:33	50.80	OK	8700	2026-09-16 11:34	52.19	OK
8701	2026-09-16 11:35	51.34	OK	8702	2026-09-16 11:36	53.88	OK
8703	2026-09-16 11:37	49.50	OK	8704	2026-09-16 11:38	51.03	OK
8705	2026-09-16 11:39	51.71	OK	8706	2026-09-16 11:40	51.83	OK
8707	2026-09-16 11:41	52.65	OK	8708	2026-09-16 11:42	52.32	OK
8709	2026-09-16 11:43	51.30	OK	8710	2026-09-16 11:44	51.59	OK
8711	2026-09-16 11:45	50.77	OK	8712	2026-09-16 11:46	52.92	OK
8713	2026-09-16 11:47	50.96	OK	8714	2026-09-16 11:48	53.39	OK
8715	2026-09-16 11:49	52.19	OK	8716	2026-09-16 11:50	50.15	OK
8717	2026-09-16 11:51	51.15	OK	8718	2026-09-16 11:52	50.44	OK
8719	2026-09-16 11:53	51.49	OK	8720	2026-09-16 11:54	50.44	OK
8721	2026-09-16 11:55	50.56	OK	8722	2026-09-16 11:56	50.95	OK
8723	2026-09-16 11:57	52.05	OK	8724	2026-09-16 11:58	51.82	OK
8725	2026-09-16 11:59	52.13	OK	8726	2026-09-16 12:00	50.90	OK
8727	2026-09-16 12:01	50.99	OK	8728	2026-09-16 12:02	53.60	OK
8729	2026-09-16 12:03	52.11	OK	8730	2026-09-16 12:04	51.38	OK
8731	2026-09-16 12:05	51.46	OK	8732	2026-09-16 12:06	51.26	OK
8733	2026-09-16 12:07	50.87	OK	8734	2026-09-16 12:08	54.16	OK
8735	2026-09-16 12:09	50.91	OK	8736	2026-09-16 12:10	50.74	OK
8737	2026-09-16 12:11	53.58	OK	8738	2026-09-16 12:12	50.72	OK
8739	2026-09-16 12:13	52.68	OK	8740	2026-09-16 12:14	52.34	OK
8741	2026-09-16 12:15	51.14	OK	8742	2026-09-16 12:16	54.10	OK
8743	2026-09-16 12:17	51.73	OK	8744	2026-09-16 12:18	51.35	OK
8745	2026-09-16 12:19	52.34	OK	8746	2026-09-16 12:20	51.99	OK
8747	2026-09-16 12:21	51.79	OK	8748	2026-09-16 12:22	52.80	OK
8749	2026-09-16 12:23	51.32	OK	8750	2026-09-16 12:24	54.15	OK
8751	2026-09-16 12:25	50.18	OK	8752	2026-09-16 12:26	51.58	OK
8753	2026-09-16 12:27	52.11	OK	8754	2026-09-16 12:28	52.71	OK
8755	2026-09-16 12:29	52.08	OK	8756	2026-09-16 12:30	52.05	OK
8757	2026-09-16 12:31	52.80	OK	8758	2026-09-16 12:32	51.31	OK
8759	2026-09-16 12:33	53.24	OK	8760	2026-09-16 12:34	52.64	OK
8761	2026-09-16 12:35	52.14	OK	8762	2026-09-16 12:36	52.82	OK
8763	2026-09-16 12:37	51.27	OK	8764	2026-09-16 12:38	52.45	OK
8765	2026-09-16 12:39	51.98	OK	8766	2026-09-16 12:40	52.73	OK
8767	2026-09-16 12:41	52.38	OK	8768	2026-09-16 12:42	52.71	OK
8769	2026-09-16 12:43	51.05	OK	8770	2026-09-16 12:44	52.94	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8771	2026-09-16 12:45	52.77	OK	8772	2026-09-16 12:46	50.34	OK
8773	2026-09-16 12:47	51.15	OK	8774	2026-09-16 12:48	52.33	OK
8775	2026-09-16 12:49	51.78	OK	8776	2026-09-16 12:50	51.76	OK
8777	2026-09-16 12:51	50.45	OK	8778	2026-09-16 12:52	51.35	OK
8779	2026-09-16 12:53	51.81	OK	8780	2026-09-16 12:54	52.68	OK
8781	2026-09-16 12:55	53.79	OK	8782	2026-09-16 12:56	52.16	OK
8783	2026-09-16 12:57	52.43	OK	8784	2026-09-16 12:58	52.28	OK
8785	2026-09-16 12:59	51.52	OK	8786	2026-09-16 13:00	51.96	OK
8787	2026-09-16 13:01	52.58	OK	8788	2026-09-16 13:02	52.97	OK
8789	2026-09-16 13:03	50.55	OK	8790	2026-09-16 13:04	50.99	OK
8791	2026-09-16 13:05	51.71	OK	8792	2026-09-16 13:06	51.55	OK
8793	2026-09-16 13:07	53.18	OK	8794	2026-09-16 13:08	51.52	OK
8795	2026-09-16 13:09	51.54	OK	8796	2026-09-16 13:10	51.34	OK
8797	2026-09-16 13:11	52.03	OK	8798	2026-09-16 13:12	53.36	OK
8799	2026-09-16 13:13	51.87	OK	8800	2026-09-16 13:14	51.18	OK
8801	2026-09-16 13:15	52.02	OK	8802	2026-09-16 13:16	50.97	OK
8803	2026-09-16 13:17	52.90	OK	8804	2026-09-16 13:18	51.33	OK
8805	2026-09-16 13:19	50.84	OK	8806	2026-09-16 13:20	52.28	OK
8807	2026-09-16 13:21	51.00	OK	8808	2026-09-16 13:22	52.17	OK
8809	2026-09-16 13:23	52.47	OK	8810	2026-09-16 13:24	49.80	OK
8811	2026-09-16 13:25	50.33	OK	8812	2026-09-16 13:26	51.90	OK
8813	2026-09-16 13:27	51.71	OK	8814	2026-09-16 13:28	50.93	OK
8815	2026-09-16 13:29	53.14	OK	8816	2026-09-16 13:30	53.66	OK
8817	2026-09-16 13:31	52.97	OK	8818	2026-09-16 13:32	50.13	OK
8819	2026-09-16 13:33	51.85	OK	8820	2026-09-16 13:34	51.94	OK
8821	2026-09-16 13:35	51.69	OK	8822	2026-09-16 13:36	53.08	OK
8823	2026-09-16 13:37	51.80	OK	8824	2026-09-16 13:38	52.47	OK
8825	2026-09-16 13:39	53.20	OK	8826	2026-09-16 13:40	51.21	OK
8827	2026-09-16 13:41	53.45	OK	8828	2026-09-16 13:42	51.51	OK
8829	2026-09-16 13:43	52.62	OK	8830	2026-09-16 13:44	53.43	OK
8831	2026-09-16 13:45	49.30	OK	8832	2026-09-16 13:46	50.33	OK
8833	2026-09-16 13:47	51.45	OK	8834	2026-09-16 13:48	52.10	OK
8835	2026-09-16 13:49	51.95	OK	8836	2026-09-16 13:50	51.45	OK
8837	2026-09-16 13:51	50.72	OK	8838	2026-09-16 13:52	52.01	OK
8839	2026-09-16 13:53	50.96	OK	8840	2026-09-16 13:54	51.18	OK
8841	2026-09-16 13:55	50.95	OK	8842	2026-09-16 13:56	50.09	OK
8843	2026-09-16 13:57	51.87	OK	8844	2026-09-16 13:58	51.03	OK
8845	2026-09-16 13:59	52.48	OK	8846	2026-09-16 14:00	51.66	OK
8847	2026-09-16 14:01	51.60	OK	8848	2026-09-16 14:02	53.70	OK
8849	2026-09-16 14:03	52.52	OK	8850	2026-09-16 14:04	52.64	OK
8851	2026-09-16 14:05	50.41	OK	8852	2026-09-16 14:06	52.78	OK
8853	2026-09-16 14:07	50.92	OK	8854	2026-09-16 14:08	52.16	OK
8855	2026-09-16 14:09	51.71	OK	8856	2026-09-16 14:10	51.58	OK
8857	2026-09-16 14:11	52.23	OK	8858	2026-09-16 14:12	51.59	OK
8859	2026-09-16 14:13	53.76	OK	8860	2026-09-16 14:14	52.79	OK
8861	2026-09-16 14:15	51.49	OK	8862	2026-09-16 14:16	51.73	OK
8863	2026-09-16 14:17	51.41	OK	8864	2026-09-16 14:18	52.52	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8865	2026-09-16 14:19	50.12	OK	8866	2026-09-16 14:20	52.38	OK
8867	2026-09-16 14:21	51.04	OK	8868	2026-09-16 14:22	51.16	OK
8869	2026-09-16 14:23	52.18	OK	8870	2026-09-16 14:24	53.82	OK
8871	2026-09-16 14:25	53.00	OK	8872	2026-09-16 14:26	52.46	OK
8873	2026-09-16 14:27	51.47	OK	8874	2026-09-16 14:28	53.06	OK
8875	2026-09-16 14:29	51.56	OK	8876	2026-09-16 14:30	51.47	OK
8877	2026-09-16 14:31	52.09	OK	8878	2026-09-16 14:32	53.05	OK
8879	2026-09-16 14:33	52.20	OK	8880	2026-09-16 14:34	52.08	OK
8881	2026-09-16 14:35	51.02	OK	8882	2026-09-16 14:36	51.89	OK
8883	2026-09-16 14:37	51.98	OK	8884	2026-09-16 14:38	50.27	OK
8885	2026-09-16 14:39	51.75	OK	8886	2026-09-16 14:40	51.08	OK
8887	2026-09-16 14:41	51.66	OK	8888	2026-09-16 14:42	50.87	OK
8889	2026-09-16 14:43	52.69	OK	8890	2026-09-16 14:44	50.73	OK
8891	2026-09-16 14:45	52.13	OK	8892	2026-09-16 14:46	51.79	OK
8893	2026-09-16 14:47	50.58	OK	8894	2026-09-16 14:48	52.09	OK
8895	2026-09-16 14:49	50.03	OK	8896	2026-09-16 14:50	52.17	OK
8897	2026-09-16 14:51	52.73	OK	8898	2026-09-16 14:52	50.37	OK
8899	2026-09-16 14:53	50.82	OK	8900	2026-09-16 14:54	52.12	OK
8901	2026-09-16 14:55	52.61	OK	8902	2026-09-16 14:56	53.06	OK
8903	2026-09-16 14:57	51.90	OK	8904	2026-09-16 14:58	52.39	OK
8905	2026-09-16 14:59	52.89	OK	8906	2026-09-16 15:00	50.53	OK
8907	2026-09-16 15:01	51.92	OK	8908	2026-09-16 15:02	51.69	OK
8909	2026-09-16 15:03	49.25	OK	8910	2026-09-16 15:04	51.24	OK
8911	2026-09-16 15:05	51.61	OK	8912	2026-09-16 15:06	52.45	OK
8913	2026-09-16 15:07	51.82	OK	8914	2026-09-16 15:08	50.59	OK
8915	2026-09-16 15:09	51.03	OK	8916	2026-09-16 15:10	51.13	OK
8917	2026-09-16 15:11	51.29	OK	8918	2026-09-16 15:12	51.46	OK
8919	2026-09-16 15:13	53.20	OK	8920	2026-09-16 15:14	51.27	OK
8921	2026-09-16 15:15	51.84	OK	8922	2026-09-16 15:16	52.43	OK
8923	2026-09-16 15:17	50.40	OK	8924	2026-09-16 15:18	52.12	OK
8925	2026-09-16 15:19	51.38	OK	8926	2026-09-16 15:20	53.06	OK
8927	2026-09-16 15:21	52.36	OK	8928	2026-09-16 15:22	49.41	OK
8929	2026-09-16 15:23	52.20	OK	8930	2026-09-16 15:24	50.50	OK
8931	2026-09-16 15:25	52.68	OK	8932	2026-09-16 15:26	50.42	OK
8933	2026-09-16 15:27	52.34	OK	8934	2026-09-16 15:28	51.69	OK
8935	2026-09-16 15:29	51.49	OK	8936	2026-09-16 15:30	53.61	OK
8937	2026-09-16 15:31	50.42	OK	8938	2026-09-16 15:32	49.92	OK
8939	2026-09-16 15:33	50.24	OK	8940	2026-09-16 15:34	53.28	OK
8941	2026-09-16 15:35	51.36	OK	8942	2026-09-16 15:36	50.84	OK
8943	2026-09-16 15:37	51.56	OK	8944	2026-09-16 15:38	51.42	OK
8945	2026-09-16 15:39	50.35	OK	8946	2026-09-16 15:40	50.85	OK
8947	2026-09-16 15:41	50.98	OK	8948	2026-09-16 15:42	52.70	OK
8949	2026-09-16 15:43	50.16	OK	8950	2026-09-16 15:44	53.02	OK
8951	2026-09-16 15:45	50.31	OK	8952	2026-09-16 15:46	50.60	OK
8953	2026-09-16 15:47	50.22	OK	8954	2026-09-16 15:48	49.82	OK
8955	2026-09-16 15:49	50.04	OK	8956	2026-09-16 15:50	49.95	OK
8957	2026-09-16 15:51	50.75	OK	8958	2026-09-16 15:52	51.89	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8959	2026-09-16 15:53	49.83	OK	8960	2026-09-16 15:54	52.44	OK
8961	2026-09-16 15:55	52.26	OK	8962	2026-09-16 15:56	49.64	OK
8963	2026-09-16 15:57	51.01	OK	8964	2026-09-16 15:58	50.99	OK
8965	2026-09-16 15:59	52.52	OK	8966	2026-09-16 16:00	51.57	OK
8967	2026-09-16 16:01	53.50	OK	8968	2026-09-16 16:02	50.76	OK
8969	2026-09-16 16:03	50.74	OK	8970	2026-09-16 16:04	52.64	OK
8971	2026-09-16 16:05	51.32	OK	8972	2026-09-16 16:06	51.02	OK
8973	2026-09-16 16:07	50.67	OK	8974	2026-09-16 16:08	52.21	OK
8975	2026-09-16 16:09	52.05	OK	8976	2026-09-16 16:10	51.01	OK
8977	2026-09-16 16:11	50.86	OK	8978	2026-09-16 16:12	49.87	OK
8979	2026-09-16 16:13	51.21	OK	8980	2026-09-16 16:14	50.21	OK
8981	2026-09-16 16:15	50.68	OK	8982	2026-09-16 16:16	49.43	OK
8983	2026-09-16 16:17	53.06	OK	8984	2026-09-16 16:18	51.13	OK
8985	2026-09-16 16:19	52.43	OK	8986	2026-09-16 16:20	52.74	OK
8987	2026-09-16 16:21	49.22	OK	8988	2026-09-16 16:22	51.68	OK
8989	2026-09-16 16:23	51.04	OK	8990	2026-09-16 16:24	50.47	OK
8991	2026-09-16 16:25	52.17	OK	8992	2026-09-16 16:26	52.11	OK
8993	2026-09-16 16:27	51.43	OK	8994	2026-09-16 16:28	50.70	OK
8995	2026-09-16 16:29	53.12	OK	8996	2026-09-16 16:30	51.48	OK
8997	2026-09-16 16:31	48.96	OK	8998	2026-09-16 16:32	49.37	OK
8999	2026-09-16 16:33	52.10	OK	9000	2026-09-16 16:34	48.99	OK
9001	2026-09-16 16:35	50.49	OK	9002	2026-09-16 16:36	51.31	OK
9003	2026-09-16 16:37	49.14	OK	9004	2026-09-16 16:38	50.42	OK
9005	2026-09-16 16:39	48.51	OK	9006	2026-09-16 16:40	49.95	OK
9007	2026-09-16 16:41	52.41	OK	9008	2026-09-16 16:42	52.42	OK
9009	2026-09-16 16:43	49.08	OK	9010	2026-09-16 16:44	52.45	OK
9011	2026-09-16 16:45	52.05	OK	9012	2026-09-16 16:46	50.78	OK
9013	2026-09-16 16:47	51.96	OK	9014	2026-09-16 16:48	50.74	OK
9015	2026-09-16 16:49	49.55	OK	9016	2026-09-16 16:50	50.36	OK
9017	2026-09-16 16:51	51.90	OK	9018	2026-09-16 16:52	51.23	OK
9019	2026-09-16 16:53	50.84	OK	9020	2026-09-16 16:54	51.44	OK
9021	2026-09-16 16:55	48.09	OK	9022	2026-09-16 16:56	50.33	OK
9023	2026-09-16 16:57	50.70	OK	9024	2026-09-16 16:58	51.39	OK
9025	2026-09-16 16:59	50.77	OK	9026	2026-09-16 17:00	50.76	OK
9027	2026-09-16 17:01	51.35	OK	9028	2026-09-16 17:02	50.01	OK
9029	2026-09-16 17:03	50.16	OK	9030	2026-09-16 17:04	49.57	OK
9031	2026-09-16 17:05	51.81	OK	9032	2026-09-16 17:06	51.70	OK
9033	2026-09-16 17:07	51.81	OK	9034	2026-09-16 17:08	51.75	OK
9035	2026-09-16 17:09	50.76	OK	9036	2026-09-16 17:10	49.53	OK
9037	2026-09-16 17:11	50.12	OK	9038	2026-09-16 17:12	49.58	OK
9039	2026-09-16 17:13	50.53	OK	9040	2026-09-16 17:14	49.65	OK
9041	2026-09-16 17:15	50.04	OK	9042	2026-09-16 17:16	48.47	OK
9043	2026-09-16 17:17	49.96	OK	9044	2026-09-16 17:18	49.84	OK
9045	2026-09-16 17:19	50.64	OK	9046	2026-09-16 17:20	49.19	OK
9047	2026-09-16 17:21	48.35	OK	9048	2026-09-16 17:22	49.23	OK
9049	2026-09-16 17:23	50.14	OK	9050	2026-09-16 17:24	49.75	OK
9051	2026-09-16 17:25	49.76	OK	9052	2026-09-16 17:26	48.70	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9053	2026-09-16 17:27	49.94	OK	9054	2026-09-16 17:28	49.19	OK
9055	2026-09-16 17:29	47.58	OK	9056	2026-09-16 17:30	49.96	OK
9057	2026-09-16 17:31	50.85	OK	9058	2026-09-16 17:32	48.98	OK
9059	2026-09-16 17:33	49.99	OK	9060	2026-09-16 17:34	51.05	OK
9061	2026-09-16 17:35	48.91	OK	9062	2026-09-16 17:36	49.19	OK
9063	2026-09-16 17:37	47.81	OK	9064	2026-09-16 17:38	49.33	OK
9065	2026-09-16 17:39	51.27	OK	9066	2026-09-16 17:40	49.48	OK
9067	2026-09-16 17:41	48.52	OK	9068	2026-09-16 17:42	50.43	OK
9069	2026-09-16 17:43	50.70	OK	9070	2026-09-16 17:44	50.37	OK
9071	2026-09-16 17:45	48.48	OK	9072	2026-09-16 17:46	50.17	OK
9073	2026-09-16 17:47	50.67	OK	9074	2026-09-16 17:48	49.78	OK
9075	2026-09-16 17:49	50.53	OK	9076	2026-09-16 17:50	49.82	OK
9077	2026-09-16 17:51	49.92	OK	9078	2026-09-16 17:52	49.72	OK
9079	2026-09-16 17:53	50.75	OK	9080	2026-09-16 17:54	51.32	OK
9081	2026-09-16 17:55	48.47	OK	9082	2026-09-16 17:56	50.56	OK
9083	2026-09-16 17:57	48.69	OK	9084	2026-09-16 17:58	48.74	OK
9085	2026-09-16 17:59	50.28	OK	9086	2026-09-16 18:00	50.96	OK
9087	2026-09-16 18:01	51.05	OK	9088	2026-09-16 18:02	49.39	OK
9089	2026-09-16 18:03	48.99	OK	9090	2026-09-16 18:04	48.26	OK
9091	2026-09-16 18:05	48.94	OK	9092	2026-09-16 18:06	51.04	OK
9093	2026-09-16 18:07	48.21	OK	9094	2026-09-16 18:08	51.57	OK
9095	2026-09-16 18:09	50.45	OK	9096	2026-09-16 18:10	50.71	OK
9097	2026-09-16 18:11	48.89	OK	9098	2026-09-16 18:12	51.26	OK
9099	2026-09-16 18:13	48.47	OK	9100	2026-09-16 18:14	49.42	OK
9101	2026-09-16 18:15	47.09	OK	9102	2026-09-16 18:16	47.94	OK
9103	2026-09-16 18:17	50.79	OK	9104	2026-09-16 18:18	48.55	OK
9105	2026-09-16 18:19	47.73	OK	9106	2026-09-16 18:20	49.00	OK
9107	2026-09-16 18:21	49.78	OK	9108	2026-09-16 18:22	48.77	OK
9109	2026-09-16 18:23	48.61	OK	9110	2026-09-16 18:24	49.81	OK
9111	2026-09-16 18:25	50.14	OK	9112	2026-09-16 18:26	50.14	OK
9113	2026-09-16 18:27	50.69	OK	9114	2026-09-16 18:28	47.78	OK
9115	2026-09-16 18:29	48.53	OK	9116	2026-09-16 18:30	51.22	OK
9117	2026-09-16 18:31	49.75	OK	9118	2026-09-16 18:32	51.59	OK
9119	2026-09-16 18:33	48.79	OK	9120	2026-09-16 18:34	49.01	OK
9121	2026-09-16 18:35	50.95	OK	9122	2026-09-16 18:36	46.77	OK
9123	2026-09-16 18:37	49.10	OK	9124	2026-09-16 18:38	48.46	OK
9125	2026-09-16 18:39	49.84	OK	9126	2026-09-16 18:40	48.54	OK
9127	2026-09-16 18:41	49.02	OK	9128	2026-09-16 18:42	49.03	OK
9129	2026-09-16 18:43	50.04	OK	9130	2026-09-16 18:44	50.33	OK
9131	2026-09-16 18:45	48.14	OK	9132	2026-09-16 18:46	48.95	OK
9133	2026-09-16 18:47	48.96	OK	9134	2026-09-16 18:48	47.28	OK
9135	2026-09-16 18:49	48.11	OK	9136	2026-09-16 18:50	48.04	OK
9137	2026-09-16 18:51	49.52	OK	9138	2026-09-16 18:52	48.60	OK
9139	2026-09-16 18:53	48.77	OK	9140	2026-09-16 18:54	50.01	OK
9141	2026-09-16 18:55	48.53	OK	9142	2026-09-16 18:56	50.53	OK
9143	2026-09-16 18:57	48.71	OK	9144	2026-09-16 18:58	49.76	OK
9145	2026-09-16 18:59	48.65	OK	9146	2026-09-16 19:00	47.98	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9147	2026-09-16 19:01	48.06	OK	9148	2026-09-16 19:02	48.16	OK
9149	2026-09-16 19:03	49.88	OK	9150	2026-09-16 19:04	49.71	OK
9151	2026-09-16 19:05	47.69	OK	9152	2026-09-16 19:06	49.93	OK
9153	2026-09-16 19:07	48.22	OK	9154	2026-09-16 19:08	47.93	OK
9155	2026-09-16 19:09	49.76	OK	9156	2026-09-16 19:10	46.79	OK
9157	2026-09-16 19:11	48.44	OK	9158	2026-09-16 19:12	50.30	OK
9159	2026-09-16 19:13	49.17	OK	9160	2026-09-16 19:14	47.75	OK
9161	2026-09-16 19:15	47.76	OK	9162	2026-09-16 19:16	48.49	OK
9163	2026-09-16 19:17	50.58	OK	9164	2026-09-16 19:18	48.92	OK
9165	2026-09-16 19:19	49.88	OK	9166	2026-09-16 19:20	48.68	OK
9167	2026-09-16 19:21	47.63	OK	9168	2026-09-16 19:22	47.78	OK
9169	2026-09-16 19:23	49.45	OK	9170	2026-09-16 19:24	49.85	OK
9171	2026-09-16 19:25	50.46	OK	9172	2026-09-16 19:26	46.57	OK
9173	2026-09-16 19:27	48.34	OK	9174	2026-09-16 19:28	47.80	OK
9175	2026-09-16 19:29	48.91	OK	9176	2026-09-16 19:30	49.88	OK
9177	2026-09-16 19:31	48.77	OK	9178	2026-09-16 19:32	47.21	OK
9179	2026-09-16 19:33	50.03	OK	9180	2026-09-16 19:34	47.35	OK
9181	2026-09-16 19:35	49.30	OK	9182	2026-09-16 19:36	47.73	OK
9183	2026-09-16 19:37	47.83	OK	9184	2026-09-16 19:38	47.26	OK
9185	2026-09-16 19:39	48.30	OK	9186	2026-09-16 19:40	48.16	OK
9187	2026-09-16 19:41	49.78	OK	9188	2026-09-16 19:42	47.59	OK
9189	2026-09-16 19:43	49.84	OK	9190	2026-09-16 19:44	49.15	OK
9191	2026-09-16 19:45	47.43	OK	9192	2026-09-16 19:46	48.18	OK
9193	2026-09-16 19:47	46.89	OK	9194	2026-09-16 19:48	47.93	OK
9195	2026-09-16 19:49	47.45	OK	9196	2026-09-16 19:50	47.61	OK
9197	2026-09-16 19:51	46.51	OK	9198	2026-09-16 19:52	47.76	OK
9199	2026-09-16 19:53	47.14	OK	9200	2026-09-16 19:54	48.73	OK
9201	2026-09-16 19:55	47.41	OK	9202	2026-09-16 19:56	48.01	OK
9203	2026-09-16 19:57	48.55	OK	9204	2026-09-16 19:58	48.71	OK
9205	2026-09-16 19:59	48.89	OK	9206	2026-09-16 20:00	48.32	OK
9207	2026-09-16 20:01	48.99	OK	9208	2026-09-16 20:02	49.10	OK
9209	2026-09-16 20:03	46.39	OK	9210	2026-09-16 20:04	47.72	OK
9211	2026-09-16 20:05	48.31	OK	9212	2026-09-16 20:06	49.50	OK
9213	2026-09-16 20:07	48.03	OK	9214	2026-09-16 20:08	49.52	OK
9215	2026-09-16 20:09	48.80	OK	9216	2026-09-16 20:10	47.19	OK
9217	2026-09-16 20:11	46.22	OK	9218	2026-09-16 20:12	48.48	OK
9219	2026-09-16 20:13	47.01	OK	9220	2026-09-16 20:14	47.79	OK
9221	2026-09-16 20:15	47.79	OK	9222	2026-09-16 20:16	49.06	OK
9223	2026-09-16 20:17	47.00	OK	9224	2026-09-16 20:18	48.29	OK
9225	2026-09-16 20:19	47.77	OK	9226	2026-09-16 20:20	45.86	OK
9227	2026-09-16 20:21	47.56	OK	9228	2026-09-16 20:22	48.39	OK
9229	2026-09-16 20:23	46.42	OK	9230	2026-09-16 20:24	45.91	OK
9231	2026-09-16 20:25	46.67	OK	9232	2026-09-16 20:26	47.57	OK
9233	2026-09-16 20:27	47.64	OK	9234	2026-09-16 20:28	47.50	OK
9235	2026-09-16 20:29	46.89	OK	9236	2026-09-16 20:30	47.18	OK
9237	2026-09-16 20:31	46.98	OK	9238	2026-09-16 20:32	48.22	OK
9239	2026-09-16 20:33	46.66	OK	9240	2026-09-16 20:34	47.10	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9241	2026-09-16 20:35	47.26	OK	9242	2026-09-16 20:36	47.09	OK
9243	2026-09-16 20:37	47.81	OK	9244	2026-09-16 20:38	47.63	OK
9245	2026-09-16 20:39	46.95	OK	9246	2026-09-16 20:40	47.84	OK
9247	2026-09-16 20:41	47.24	OK	9248	2026-09-16 20:42	46.58	OK
9249	2026-09-16 20:43	47.04	OK	9250	2026-09-16 20:44	46.10	OK
9251	2026-09-16 20:45	46.39	OK	9252	2026-09-16 20:46	45.63	OK
9253	2026-09-16 20:47	48.16	OK	9254	2026-09-16 20:48	48.35	OK
9255	2026-09-16 20:49	48.70	OK	9256	2026-09-16 20:50	46.28	OK
9257	2026-09-16 20:51	46.78	OK	9258	2026-09-16 20:52	46.33	OK
9259	2026-09-16 20:53	45.63	OK	9260	2026-09-16 20:54	47.41	OK
9261	2026-09-16 20:55	48.10	OK	9262	2026-09-16 20:56	46.12	OK
9263	2026-09-16 20:57	46.47	OK	9264	2026-09-16 20:58	45.76	OK
9265	2026-09-16 20:59	47.12	OK	9266	2026-09-16 21:00	47.70	OK
9267	2026-09-16 21:01	48.50	OK	9268	2026-09-16 21:02	47.15	OK
9269	2026-09-16 21:03	46.27	OK	9270	2026-09-16 21:04	47.93	OK
9271	2026-09-16 21:05	47.53	OK	9272	2026-09-16 21:06	46.07	OK
9273	2026-09-16 21:07	47.99	OK	9274	2026-09-16 21:08	46.98	OK
9275	2026-09-16 21:09	47.70	OK	9276	2026-09-16 21:10	47.76	OK
9277	2026-09-16 21:11	46.61	OK	9278	2026-09-16 21:12	47.02	OK
9279	2026-09-16 21:13	46.14	OK	9280	2026-09-16 21:14	46.53	OK
9281	2026-09-16 21:15	47.52	OK	9282	2026-09-16 21:16	46.65	OK
9283	2026-09-16 21:17	45.02	OK	9284	2026-09-16 21:18	48.46	OK
9285	2026-09-16 21:19	44.91	OK	9286	2026-09-16 21:20	48.92	OK
9287	2026-09-16 21:21	47.35	OK	9288	2026-09-16 21:22	46.57	OK
9289	2026-09-16 21:23	46.49	OK	9290	2026-09-16 21:24	46.43	OK
9291	2026-09-16 21:25	47.74	OK	9292	2026-09-16 21:26	46.60	OK
9293	2026-09-16 21:27	48.48	OK	9294	2026-09-16 21:28	45.13	OK
9295	2026-09-16 21:29	46.14	OK	9296	2026-09-16 21:30	45.90	OK
9297	2026-09-16 21:31	48.12	OK	9298	2026-09-16 21:32	46.68	OK
9299	2026-09-16 21:33	45.25	OK	9300	2026-09-16 21:34	46.11	OK
9301	2026-09-16 21:35	48.91	OK	9302	2026-09-16 21:36	48.30	OK
9303	2026-09-16 21:37	45.03	OK	9304	2026-09-16 21:38	45.97	OK
9305	2026-09-16 21:39	48.46	OK	9306	2026-09-16 21:40	47.09	OK
9307	2026-09-16 21:41	46.34	OK	9308	2026-09-16 21:42	45.77	OK
9309	2026-09-16 21:43	47.77	OK	9310	2026-09-16 21:44	47.06	OK
9311	2026-09-16 21:45	48.45	OK	9312	2026-09-16 21:46	46.56	OK
9313	2026-09-16 21:47	45.02	OK	9314	2026-09-16 21:48	46.31	OK
9315	2026-09-16 21:49	47.19	OK	9316	2026-09-16 21:50	46.07	OK
9317	2026-09-16 21:51	46.87	OK	9318	2026-09-16 21:52	45.81	OK
9319	2026-09-16 21:53	47.07	OK	9320	2026-09-16 21:54	45.37	OK
9321	2026-09-16 21:55	46.35	OK	9322	2026-09-16 21:56	47.27	OK
9323	2026-09-16 21:57	46.05	OK	9324	2026-09-16 21:58	46.13	OK
9325	2026-09-16 21:59	45.70	OK	9326	2026-09-16 22:00	46.55	OK
9327	2026-09-16 22:01	47.28	OK	9328	2026-09-16 22:02	46.85	OK
9329	2026-09-16 22:03	45.99	OK	9330	2026-09-16 22:04	47.69	OK
9331	2026-09-16 22:05	44.61	OK	9332	2026-09-16 22:06	46.00	OK
9333	2026-09-16 22:07	45.85	OK	9334	2026-09-16 22:08	47.52	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9335	2026-09-16 22:09	46.58	OK	9336	2026-09-16 22:10	47.33	OK
9337	2026-09-16 22:11	48.02	OK	9338	2026-09-16 22:12	47.10	OK
9339	2026-09-16 22:13	44.70	OK	9340	2026-09-16 22:14	44.66	OK
9341	2026-09-16 22:15	45.32	OK	9342	2026-09-16 22:16	48.39	OK
9343	2026-09-16 22:17	46.23	OK	9344	2026-09-16 22:18	46.54	OK
9345	2026-09-16 22:19	48.17	OK	9346	2026-09-16 22:20	45.57	OK
9347	2026-09-16 22:21	44.45	OK	9348	2026-09-16 22:22	45.68	OK
9349	2026-09-16 22:23	47.45	OK	9350	2026-09-16 22:24	45.44	OK
9351	2026-09-16 22:25	45.53	OK	9352	2026-09-16 22:26	47.75	OK
9353	2026-09-16 22:27	47.05	OK	9354	2026-09-16 22:28	45.24	OK
9355	2026-09-16 22:29	47.21	OK	9356	2026-09-16 22:30	46.79	OK
9357	2026-09-16 22:31	45.93	OK	9358	2026-09-16 22:32	46.32	OK
9359	2026-09-16 22:33	47.46	OK	9360	2026-09-16 22:34	47.05	OK
9361	2026-09-16 22:35	45.01	OK	9362	2026-09-16 22:36	46.88	OK
9363	2026-09-16 22:37	43.73	OK	9364	2026-09-16 22:38	46.85	OK
9365	2026-09-16 22:39	46.58	OK	9366	2026-09-16 22:40	45.71	OK
9367	2026-09-16 22:41	45.26	OK	9368	2026-09-16 22:42	46.69	OK
9369	2026-09-16 22:43	45.82	OK	9370	2026-09-16 22:44	46.75	OK
9371	2026-09-16 22:45	47.26	OK	9372	2026-09-16 22:46	47.66	OK
9373	2026-09-16 22:47	47.98	OK	9374	2026-09-16 22:48	44.15	OK
9375	2026-09-16 22:49	46.51	OK	9376	2026-09-16 22:50	43.59	OK
9377	2026-09-16 22:51	45.54	OK	9378	2026-09-16 22:52	45.54	OK
9379	2026-09-16 22:53	46.58	OK	9380	2026-09-16 22:54	45.65	OK
9381	2026-09-16 22:55	45.82	OK	9382	2026-09-16 22:56	45.28	OK
9383	2026-09-16 22:57	45.30	OK	9384	2026-09-16 22:58	46.33	OK
9385	2026-09-16 22:59	48.00	OK	9386	2026-09-16 23:00	44.89	OK
9387	2026-09-16 23:01	44.73	OK	9388	2026-09-16 23:02	44.21	OK
9389	2026-09-16 23:03	46.32	OK	9390	2026-09-16 23:04	45.99	OK
9391	2026-09-16 23:05	46.20	OK	9392	2026-09-16 23:06	46.80	OK
9393	2026-09-16 23:07	44.54	OK	9394	2026-09-16 23:08	47.42	OK
9395	2026-09-16 23:09	44.28	OK	9396	2026-09-16 23:10	45.07	OK
9397	2026-09-16 23:11	46.29	OK	9398	2026-09-16 23:12	44.25	OK
9399	2026-09-16 23:13	45.07	OK	9400	2026-09-16 23:14	43.59	OK
9401	2026-09-16 23:15	46.83	OK	9402	2026-09-16 23:16	45.62	OK
9403	2026-09-16 23:17	44.67	OK	9404	2026-09-16 23:18	46.17	OK
9405	2026-09-16 23:19	46.80	OK	9406	2026-09-16 23:20	46.90	OK
9407	2026-09-16 23:21	47.22	OK	9408	2026-09-16 23:22	45.28	OK
9409	2026-09-16 23:23	46.52	OK	9410	2026-09-16 23:24	46.22	OK
9411	2026-09-16 23:25	44.03	OK	9412	2026-09-16 23:26	44.86	OK
9413	2026-09-16 23:27	43.24	OK	9414	2026-09-16 23:28	43.72	OK
9415	2026-09-16 23:29	46.04	OK	9416	2026-09-16 23:30	46.13	OK
9417	2026-09-16 23:31	46.79	OK	9418	2026-09-16 23:32	47.41	OK
9419	2026-09-16 23:33	47.03	OK	9420	2026-09-16 23:34	45.98	OK
9421	2026-09-16 23:35	44.98	OK	9422	2026-09-16 23:36	44.64	OK
9423	2026-09-16 23:37	46.61	OK	9424	2026-09-16 23:38	44.65	OK
9425	2026-09-16 23:39	44.73	OK	9426	2026-09-16 23:40	46.52	OK
9427	2026-09-16 23:41	46.20	OK	9428	2026-09-16 23:42	45.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9429	2026-09-16 23:43	45.18	OK	9430	2026-09-16 23:44	45.96	OK
9431	2026-09-16 23:45	44.70	OK	9432	2026-09-16 23:46	45.15	OK
9433	2026-09-16 23:47	46.24	OK	9434	2026-09-16 23:48	45.90	OK
9435	2026-09-16 23:49	45.17	OK	9436	2026-09-16 23:50	45.94	OK
9437	2026-09-16 23:51	45.13	OK	9438	2026-09-16 23:52	45.69	OK
9439	2026-09-16 23:53	45.30	OK	9440	2026-09-16 23:54	45.97	OK
9441	2026-09-16 23:55	45.86	OK	9442	2026-09-16 23:56	44.40	OK
9443	2026-09-16 23:57	46.50	OK	9444	2026-09-16 23:58	45.71	OK
9445	2026-09-16 23:59	48.10	OK	9446	2026-09-17 00:00	45.63	OK
9447	2026-09-17 00:01	43.82	OK	9448	2026-09-17 00:02	46.25	OK
9449	2026-09-17 00:03	44.59	OK	9450	2026-09-17 00:04	45.93	OK
9451	2026-09-17 00:05	44.43	OK	9452	2026-09-17 00:06	46.17	OK
9453	2026-09-17 00:07	45.76	OK	9454	2026-09-17 00:08	45.64	OK
9455	2026-09-17 00:09	45.91	OK	9456	2026-09-17 00:10	44.66	OK
9457	2026-09-17 00:11	44.58	OK	9458	2026-09-17 00:12	45.19	OK
9459	2026-09-17 00:13	45.21	OK	9460	2026-09-17 00:14	45.86	OK
9461	2026-09-17 00:15	44.46	OK	9462	2026-09-17 00:16	45.18	OK
9463	2026-09-17 00:17	44.75	OK	9464	2026-09-17 00:18	44.78	OK
9465	2026-09-17 00:19	47.10	OK	9466	2026-09-17 00:20	43.85	OK
9467	2026-09-17 00:21	47.19	OK	9468	2026-09-17 00:22	46.02	OK
9469	2026-09-17 00:23	46.05	OK	9470	2026-09-17 00:24	45.41	OK
9471	2026-09-17 00:25	46.27	OK	9472	2026-09-17 00:26	46.02	OK
9473	2026-09-17 00:27	44.04	OK	9474	2026-09-17 00:28	44.83	OK
9475	2026-09-17 00:29	45.00	OK	9476	2026-09-17 00:30	45.32	OK
9477	2026-09-17 00:31	45.67	OK	9478	2026-09-17 00:32	44.84	OK
9479	2026-09-17 00:33	44.67	OK	9480	2026-09-17 00:34	44.65	OK
9481	2026-09-17 00:35	45.72	OK	9482	2026-09-17 00:36	44.99	OK
9483	2026-09-17 00:37	45.53	OK	9484	2026-09-17 00:38	45.44	OK
9485	2026-09-17 00:39	45.96	OK	9486	2026-09-17 00:40	43.91	OK
9487	2026-09-17 00:41	44.32	OK	9488	2026-09-17 00:42	43.50	OK
9489	2026-09-17 00:43	45.65	OK	9490	2026-09-17 00:44	44.66	OK
9491	2026-09-17 00:45	44.95	OK	9492	2026-09-17 00:46	44.41	OK
9493	2026-09-17 00:47	47.10	OK	9494	2026-09-17 00:48	45.68	OK
9495	2026-09-17 00:49	44.81	OK	9496	2026-09-17 00:50	46.60	OK
9497	2026-09-17 00:51	45.38	OK	9498	2026-09-17 00:52	47.45	OK
9499	2026-09-17 00:53	46.33	OK	9500	2026-09-17 00:54	46.25	OK
9501	2026-09-17 00:55	44.15	OK	9502	2026-09-17 00:56	46.12	OK
9503	2026-09-17 00:57	45.14	OK	9504	2026-09-17 00:58	45.81	OK
9505	2026-09-17 00:59	44.51	OK	9506	2026-09-17 01:00	45.60	OK
9507	2026-09-17 01:01	43.90	OK	9508	2026-09-17 01:02	45.37	OK
9509	2026-09-17 01:03	45.00	OK	9510	2026-09-17 01:04	44.95	OK
9511	2026-09-17 01:05	45.28	OK	9512	2026-09-17 01:06	45.64	OK
9513	2026-09-17 01:07	46.19	OK	9514	2026-09-17 01:08	44.16	OK
9515	2026-09-17 01:09	44.93	OK	9516	2026-09-17 01:10	44.46	OK
9517	2026-09-17 01:11	46.31	OK	9518	2026-09-17 01:12	45.58	OK
9519	2026-09-17 01:13	45.33	OK	9520	2026-09-17 01:14	43.19	OK
9521	2026-09-17 01:15	44.89	OK	9522	2026-09-17 01:16	47.45	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9523	2026-09-17 01:17	44.59	OK	9524	2026-09-17 01:18	45.18	OK
9525	2026-09-17 01:19	45.32	OK	9526	2026-09-17 01:20	45.91	OK
9527	2026-09-17 01:21	45.81	OK	9528	2026-09-17 01:22	43.45	OK
9529	2026-09-17 01:23	44.20	OK	9530	2026-09-17 01:24	45.50	OK
9531	2026-09-17 01:25	45.00	OK	9532	2026-09-17 01:26	45.91	OK
9533	2026-09-17 01:27	45.28	OK	9534	2026-09-17 01:28	44.98	OK
9535	2026-09-17 01:29	45.96	OK	9536	2026-09-17 01:30	45.77	OK
9537	2026-09-17 01:31	45.09	OK	9538	2026-09-17 01:32	43.93	OK
9539	2026-09-17 01:33	44.76	OK	9540	2026-09-17 01:34	44.24	OK
9541	2026-09-17 01:35	45.76	OK	9542	2026-09-17 01:36	42.73	OK
9543	2026-09-17 01:37	44.61	OK	9544	2026-09-17 01:38	46.34	OK
9545	2026-09-17 01:39	47.15	OK	9546	2026-09-17 01:40	44.05	OK
9547	2026-09-17 01:41	46.85	OK	9548	2026-09-17 01:42	47.11	OK
9549	2026-09-17 01:43	44.45	OK	9550	2026-09-17 01:44	43.93	OK
9551	2026-09-17 01:45	44.67	OK	9552	2026-09-17 01:46	45.36	OK
9553	2026-09-17 01:47	44.60	OK	9554	2026-09-17 01:48	44.37	OK
9555	2026-09-17 01:49	43.99	OK	9556	2026-09-17 01:50	45.03	OK
9557	2026-09-17 01:51	46.07	OK	9558	2026-09-17 01:52	46.83	OK
9559	2026-09-17 01:53	43.79	OK	9560	2026-09-17 01:54	46.19	OK
9561	2026-09-17 01:55	43.78	OK	9562	2026-09-17 01:56	45.67	OK
9563	2026-09-17 01:57	44.34	OK	9564	2026-09-17 01:58	44.79	OK
9565	2026-09-17 01:59	44.35	OK	9566	2026-09-17 02:00	47.10	OK
9567	2026-09-17 02:01	44.51	OK	9568	2026-09-17 02:02	45.56	OK
9569	2026-09-17 02:03	44.80	OK	9570	2026-09-17 02:04	44.87	OK
9571	2026-09-17 02:05	45.37	OK	9572	2026-09-17 02:06	45.44	OK
9573	2026-09-17 02:07	45.19	OK	9574	2026-09-17 02:08	45.18	OK
9575	2026-09-17 02:09	44.04	OK	9576	2026-09-17 02:10	44.34	OK
9577	2026-09-17 02:11	45.98	OK	9578	2026-09-17 02:12	45.56	OK
9579	2026-09-17 02:13	46.08	OK	9580	2026-09-17 02:14	45.43	OK
9581	2026-09-17 02:15	45.15	OK	9582	2026-09-17 02:16	46.51	OK
9583	2026-09-17 02:17	44.67	OK	9584	2026-09-17 02:18	42.88	OK
9585	2026-09-17 02:19	45.39	OK	9586	2026-09-17 02:20	45.11	OK
9587	2026-09-17 02:21	44.82	OK	9588	2026-09-17 02:22	44.31	OK
9589	2026-09-17 02:23	44.98	OK	9590	2026-09-17 02:24	43.76	OK
9591	2026-09-17 02:25	46.01	OK	9592	2026-09-17 02:26	44.22	OK
9593	2026-09-17 02:27	44.93	OK	9594	2026-09-17 02:28	44.99	OK
9595	2026-09-17 02:29	44.66	OK	9596	2026-09-17 02:30	45.75	OK
9597	2026-09-17 02:31	45.92	OK	9598	2026-09-17 02:32	46.02	OK
9599	2026-09-17 02:33	45.60	OK	9600	2026-09-17 02:34	44.91	OK
9601	2026-09-17 02:35	43.45	OK	9602	2026-09-17 02:36	44.54	OK
9603	2026-09-17 02:37	45.67	OK	9604	2026-09-17 02:38	45.12	OK
9605	2026-09-17 02:39	44.45	OK	9606	2026-09-17 02:40	46.36	OK
9607	2026-09-17 02:41	44.39	OK	9608	2026-09-17 02:42	44.65	OK
9609	2026-09-17 02:43	45.93	OK	9610	2026-09-17 02:44	46.73	OK
9611	2026-09-17 02:45	47.40	OK	9612	2026-09-17 02:46	46.29	OK
9613	2026-09-17 02:47	44.96	OK	9614	2026-09-17 02:48	45.98	OK
9615	2026-09-17 02:49	45.86	OK	9616	2026-09-17 02:50	45.96	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9617	2026-09-17 02:51	44.08	OK	9618	2026-09-17 02:52	47.75	OK
9619	2026-09-17 02:53	46.98	OK	9620	2026-09-17 02:54	45.57	OK
9621	2026-09-17 02:55	45.52	OK	9622	2026-09-17 02:56	45.34	OK
9623	2026-09-17 02:57	44.34	OK	9624	2026-09-17 02:58	47.15	OK
9625	2026-09-17 02:59	46.39	OK	9626	2026-09-17 03:00	44.46	OK
9627	2026-09-17 03:01	45.07	OK	9628	2026-09-17 03:02	45.91	OK
9629	2026-09-17 03:03	46.01	OK	9630	2026-09-17 03:04	47.87	OK
9631	2026-09-17 03:05	45.33	OK	9632	2026-09-17 03:06	45.88	OK
9633	2026-09-17 03:07	45.32	OK	9634	2026-09-17 03:08	46.60	OK
9635	2026-09-17 03:09	44.29	OK	9636	2026-09-17 03:10	45.17	OK
9637	2026-09-17 03:11	44.16	OK	9638	2026-09-17 03:12	45.88	OK
9639	2026-09-17 03:13	45.95	OK	9640	2026-09-17 03:14	45.64	OK
9641	2026-09-17 03:15	44.49	OK	9642	2026-09-17 03:16	44.19	OK
9643	2026-09-17 03:17	43.85	OK	9644	2026-09-17 03:18	43.91	OK
9645	2026-09-17 03:19	43.20	OK	9646	2026-09-17 03:20	45.21	OK
9647	2026-09-17 03:21	46.20	OK	9648	2026-09-17 03:22	44.72	OK
9649	2026-09-17 03:23	45.72	OK	9650	2026-09-17 03:24	46.98	OK
9651	2026-09-17 03:25	43.94	OK	9652	2026-09-17 03:26	48.14	OK
9653	2026-09-17 03:27	45.76	OK	9654	2026-09-17 03:28	47.01	OK
9655	2026-09-17 03:29	44.78	OK	9656	2026-09-17 03:30	46.95	OK
9657	2026-09-17 03:31	46.74	OK	9658	2026-09-17 03:32	44.81	OK
9659	2026-09-17 03:33	44.99	OK	9660	2026-09-17 03:34	45.24	OK
9661	2026-09-17 03:35	46.12	OK	9662	2026-09-17 03:36	44.97	OK
9663	2026-09-17 03:37	45.03	OK	9664	2026-09-17 03:38	47.08	OK
9665	2026-09-17 03:39	43.65	OK	9666	2026-09-17 03:40	45.02	OK
9667	2026-09-17 03:41	47.40	OK	9668	2026-09-17 03:42	44.26	OK
9669	2026-09-17 03:43	47.60	OK	9670	2026-09-17 03:44	45.79	OK
9671	2026-09-17 03:45	46.12	OK	9672	2026-09-17 03:46	46.02	OK
9673	2026-09-17 03:47	45.01	OK	9674	2026-09-17 03:48	46.30	OK
9675	2026-09-17 03:49	46.24	OK	9676	2026-09-17 03:50	46.14	OK
9677	2026-09-17 03:51	47.26	OK	9678	2026-09-17 03:52	45.75	OK
9679	2026-09-17 03:53	45.47	OK	9680	2026-09-17 03:54	47.30	OK
9681	2026-09-17 03:55	46.14	OK	9682	2026-09-17 03:56	45.66	OK
9683	2026-09-17 03:57	46.90	OK	9684	2026-09-17 03:58	44.85	OK
9685	2026-09-17 03:59	43.85	OK	9686	2026-09-17 04:00	45.41	OK
9687	2026-09-17 04:01	46.23	OK	9688	2026-09-17 04:02	45.78	OK
9689	2026-09-17 04:03	46.06	OK	9690	2026-09-17 04:04	46.75	OK
9691	2026-09-17 04:05	44.99	OK	9692	2026-09-17 04:06	44.93	OK
9693	2026-09-17 04:07	45.23	OK	9694	2026-09-17 04:08	45.24	OK
9695	2026-09-17 04:09	46.41	OK	9696	2026-09-17 04:10	46.85	OK
9697	2026-09-17 04:11	47.90	OK	9698	2026-09-17 04:12	45.97	OK
9699	2026-09-17 04:13	48.83	OK	9700	2026-09-17 04:14	46.22	OK
9701	2026-09-17 04:15	46.43	OK	9702	2026-09-17 04:16	46.90	OK
9703	2026-09-17 04:17	46.64	OK	9704	2026-09-17 04:18	46.55	OK
9705	2026-09-17 04:19	47.78	OK	9706	2026-09-17 04:20	46.09	OK
9707	2026-09-17 04:21	46.61	OK	9708	2026-09-17 04:22	45.31	OK
9709	2026-09-17 04:23	46.05	OK	9710	2026-09-17 04:24	46.78	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9711	2026-09-17 04:25	45.15	OK	9712	2026-09-17 04:26	46.77	OK
9713	2026-09-17 04:27	47.03	OK	9714	2026-09-17 04:28	45.56	OK
9715	2026-09-17 04:29	45.71	OK	9716	2026-09-17 04:30	45.80	OK
9717	2026-09-17 04:31	48.55	OK	9718	2026-09-17 04:32	46.07	OK
9719	2026-09-17 04:33	46.91	OK	9720	2026-09-17 04:34	46.30	OK
9721	2026-09-17 04:35	46.50	OK	9722	2026-09-17 04:36	46.73	OK
9723	2026-09-17 04:37	46.66	OK	9724	2026-09-17 04:38	47.19	OK
9725	2026-09-17 04:39	46.82	OK	9726	2026-09-17 04:40	45.11	OK
9727	2026-09-17 04:41	46.23	OK	9728	2026-09-17 04:42	47.07	OK
9729	2026-09-17 04:43	45.31	OK	9730	2026-09-17 04:44	47.56	OK
9731	2026-09-17 04:45	46.89	OK	9732	2026-09-17 04:46	47.19	OK
9733	2026-09-17 04:47	46.09	OK	9734	2026-09-17 04:48	48.17	OK
9735	2026-09-17 04:49	46.35	OK	9736	2026-09-17 04:50	45.66	OK
9737	2026-09-17 04:51	46.82	OK	9738	2026-09-17 04:52	46.03	OK
9739	2026-09-17 04:53	46.18	OK	9740	2026-09-17 04:54	46.81	OK
9741	2026-09-17 04:55	45.60	OK	9742	2026-09-17 04:56	47.33	OK
9743	2026-09-17 04:57	47.87	OK	9744	2026-09-17 04:58	45.75	OK
9745	2026-09-17 04:59	46.86	OK	9746	2026-09-17 05:00	46.10	OK
9747	2026-09-17 05:01	45.19	OK	9748	2026-09-17 05:02	47.08	OK
9749	2026-09-17 05:03	45.81	OK	9750	2026-09-17 05:04	45.25	OK
9751	2026-09-17 05:05	45.39	OK	9752	2026-09-17 05:06	46.84	OK
9753	2026-09-17 05:07	47.59	OK	9754	2026-09-17 05:08	45.84	OK
9755	2026-09-17 05:09	48.39	OK	9756	2026-09-17 05:10	44.79	OK
9757	2026-09-17 05:11	46.81	OK	9758	2026-09-17 05:12	46.02	OK
9759	2026-09-17 05:13	46.67	OK	9760	2026-09-17 05:14	48.10	OK
9761	2026-09-17 05:15	46.07	OK	9762	2026-09-17 05:16	46.60	OK
9763	2026-09-17 05:17	45.96	OK	9764	2026-09-17 05:18	47.25	OK
9765	2026-09-17 05:19	48.31	OK	9766	2026-09-17 05:20	45.72	OK
9767	2026-09-17 05:21	47.34	OK	9768	2026-09-17 05:22	47.54	OK
9769	2026-09-17 05:23	46.45	OK	9770	2026-09-17 05:24	46.44	OK
9771	2026-09-17 05:25	47.35	OK	9772	2026-09-17 05:26	47.55	OK
9773	2026-09-17 05:27	47.98	OK	9774	2026-09-17 05:28	47.19	OK
9775	2026-09-17 05:29	48.90	OK	9776	2026-09-17 05:30	48.77	OK
9777	2026-09-17 05:31	46.27	OK	9778	2026-09-17 05:32	47.67	OK
9779	2026-09-17 05:33	45.82	OK	9780	2026-09-17 05:34	47.91	OK
9781	2026-09-17 05:35	46.22	OK	9782	2026-09-17 05:36	46.17	OK
9783	2026-09-17 05:37	47.83	OK	9784	2026-09-17 05:38	47.57	OK
9785	2026-09-17 05:39	44.66	OK	9786	2026-09-17 05:40	46.22	OK
9787	2026-09-17 05:41	44.89	OK	9788	2026-09-17 05:42	46.17	OK
9789	2026-09-17 05:43	47.60	OK	9790	2026-09-17 05:44	46.17	OK
9791	2026-09-17 05:45	47.97	OK	9792	2026-09-17 05:46	48.29	OK
9793	2026-09-17 05:47	47.40	OK	9794	2026-09-17 05:48	46.25	OK
9795	2026-09-17 05:49	47.23	OK	9796	2026-09-17 05:50	48.16	OK
9797	2026-09-17 05:51	46.22	OK	9798	2026-09-17 05:52	47.47	OK
9799	2026-09-17 05:53	47.80	OK	9800	2026-09-17 05:54	45.55	OK
9801	2026-09-17 05:55	47.32	OK	9802	2026-09-17 05:56	46.49	OK
9803	2026-09-17 05:57	48.32	OK	9804	2026-09-17 05:58	48.08	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9805	2026-09-17 05:59	46.94	OK	9806	2026-09-17 06:00	45.54	OK
9807	2026-09-17 06:01	46.72	OK	9808	2026-09-17 06:02	47.24	OK
9809	2026-09-17 06:03	48.07	OK	9810	2026-09-17 06:04	48.70	OK
9811	2026-09-17 06:05	46.79	OK	9812	2026-09-17 06:06	46.43	OK
9813	2026-09-17 06:07	45.76	OK	9814	2026-09-17 06:08	47.01	OK
9815	2026-09-17 06:09	45.39	OK	9816	2026-09-17 06:10	48.88	OK
9817	2026-09-17 06:11	45.12	OK	9818	2026-09-17 06:12	47.45	OK
9819	2026-09-17 06:13	47.23	OK	9820	2026-09-17 06:14	48.80	OK
9821	2026-09-17 06:15	47.56	OK	9822	2026-09-17 06:16	49.92	OK
9823	2026-09-17 06:17	46.70	OK	9824	2026-09-17 06:18	46.75	OK
9825	2026-09-17 06:19	47.34	OK	9826	2026-09-17 06:20	46.99	OK
9827	2026-09-17 06:21	45.39	OK	9828	2026-09-17 06:22	47.55	OK
9829	2026-09-17 06:23	48.29	OK	9830	2026-09-17 06:24	47.64	OK
9831	2026-09-17 06:25	45.99	OK	9832	2026-09-17 06:26	46.73	OK
9833	2026-09-17 06:27	47.91	OK	9834	2026-09-17 06:28	48.07	OK
9835	2026-09-17 06:29	47.50	OK	9836	2026-09-17 06:30	48.99	OK
9837	2026-09-17 06:31	48.51	OK	9838	2026-09-17 06:32	49.04	OK
9839	2026-09-17 06:33	48.03	OK	9840	2026-09-17 06:34	47.50	OK
9841	2026-09-17 06:35	47.23	OK	9842	2026-09-17 06:36	48.82	OK
9843	2026-09-17 06:37	49.02	OK	9844	2026-09-17 06:38	46.86	OK
9845	2026-09-17 06:39	47.26	OK	9846	2026-09-17 06:40	46.10	OK
9847	2026-09-17 06:41	48.50	OK	9848	2026-09-17 06:42	47.49	OK
9849	2026-09-17 06:43	46.36	OK	9850	2026-09-17 06:44	48.71	OK
9851	2026-09-17 06:45	48.02	OK	9852	2026-09-17 06:46	49.40	OK
9853	2026-09-17 06:47	47.85	OK	9854	2026-09-17 06:48	47.84	OK
9855	2026-09-17 06:49	48.89	OK	9856	2026-09-17 06:50	46.59	OK
9857	2026-09-17 06:51	49.30	OK	9858	2026-09-17 06:52	48.46	OK
9859	2026-09-17 06:53	48.89	OK	9860	2026-09-17 06:54	46.56	OK
9861	2026-09-17 06:55	47.60	OK	9862	2026-09-17 06:56	48.28	OK
9863	2026-09-17 06:57	47.28	OK	9864	2026-09-17 06:58	46.34	OK
9865	2026-09-17 06:59	48.89	OK	9866	2026-09-17 07:00	49.45	OK
9867	2026-09-17 07:01	49.01	OK	9868	2026-09-17 07:02	46.77	OK
9869	2026-09-17 07:03	48.16	OK	9870	2026-09-17 07:04	49.67	OK
9871	2026-09-17 07:05	50.47	OK	9872	2026-09-17 07:06	48.28	OK
9873	2026-09-17 07:07	45.82	OK	9874	2026-09-17 07:08	49.87	OK
9875	2026-09-17 07:09	49.37	OK	9876	2026-09-17 07:10	49.19	OK
9877	2026-09-17 07:11	48.38	OK	9878	2026-09-17 07:12	49.05	OK
9879	2026-09-17 07:13	47.64	OK	9880	2026-09-17 07:14	46.59	OK
9881	2026-09-17 07:15	47.79	OK	9882	2026-09-17 07:16	49.32	OK
9883	2026-09-17 07:17	49.36	OK	9884	2026-09-17 07:18	47.75	OK
9885	2026-09-17 07:19	49.01	OK	9886	2026-09-17 07:20	50.56	OK
9887	2026-09-17 07:21	48.38	OK	9888	2026-09-17 07:22	47.56	OK
9889	2026-09-17 07:23	48.61	OK	9890	2026-09-17 07:24	49.44	OK
9891	2026-09-17 07:25	47.75	OK	9892	2026-09-17 07:26	48.48	OK
9893	2026-09-17 07:27	48.56	OK	9894	2026-09-17 07:28	49.02	OK
9895	2026-09-17 07:29	49.50	OK	9896	2026-09-17 07:30	49.51	OK
9897	2026-09-17 07:31	48.85	OK	9898	2026-09-17 07:32	47.28	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9899	2026-09-17 07:33	47.88	OK	9900	2026-09-17 07:34	49.09	OK
9901	2026-09-17 07:35	50.24	OK	9902	2026-09-17 07:36	47.98	OK
9903	2026-09-17 07:37	49.79	OK	9904	2026-09-17 07:38	49.26	OK
9905	2026-09-17 07:39	50.44	OK	9906	2026-09-17 07:40	47.84	OK
9907	2026-09-17 07:41	50.47	OK	9908	2026-09-17 07:42	50.60	OK
9909	2026-09-17 07:43	48.19	OK	9910	2026-09-17 07:44	49.88	OK
9911	2026-09-17 07:45	48.95	OK	9912	2026-09-17 07:46	48.71	OK
9913	2026-09-17 07:47	49.53	OK	9914	2026-09-17 07:48	48.35	OK
9915	2026-09-17 07:49	49.25	OK	9916	2026-09-17 07:50	48.45	OK
9917	2026-09-17 07:51	48.03	OK	9918	2026-09-17 07:52	47.22	OK
9919	2026-09-17 07:53	49.19	OK	9920	2026-09-17 07:54	48.79	OK
9921	2026-09-17 07:55	49.62	OK	9922	2026-09-17 07:56	47.86	OK
9923	2026-09-17 07:57	48.06	OK	9924	2026-09-17 07:58	48.83	OK
9925	2026-09-17 07:59	48.87	OK	9926	2026-09-17 08:00	50.61	OK
9927	2026-09-17 08:01	49.88	OK	9928	2026-09-17 08:02	48.87	OK
9929	2026-09-17 08:03	50.02	OK	9930	2026-09-17 08:04	48.71	OK
9931	2026-09-17 08:05	48.24	OK	9932	2026-09-17 08:06	50.85	OK
9933	2026-09-17 08:07	49.24	OK	9934	2026-09-17 08:08	50.28	OK
9935	2026-09-17 08:09	49.36	OK	9936	2026-09-17 08:10	48.48	OK
9937	2026-09-17 08:11	50.29	OK	9938	2026-09-17 08:12	48.71	OK
9939	2026-09-17 08:13	49.40	OK	9940	2026-09-17 08:14	50.00	OK
9941	2026-09-17 08:15	50.03	OK	9942	2026-09-17 08:16	50.86	OK
9943	2026-09-17 08:17	50.41	OK	9944	2026-09-17 08:18	48.45	OK
9945	2026-09-17 08:19	48.81	OK	9946	2026-09-17 08:20	49.03	OK
9947	2026-09-17 08:21	49.30	OK	9948	2026-09-17 08:22	48.37	OK
9949	2026-09-17 08:23	51.44	OK	9950	2026-09-17 08:24	47.52	OK
9951	2026-09-17 08:25	49.14	OK	9952	2026-09-17 08:26	50.42	OK
9953	2026-09-17 08:27	49.24	OK	9954	2026-09-17 08:28	51.24	OK
9955	2026-09-17 08:29	49.06	OK	9956	2026-09-17 08:30	50.44	OK
9957	2026-09-17 08:31	51.08	OK	9958	2026-09-17 08:32	49.83	OK
9959	2026-09-17 08:33	48.70	OK	9960	2026-09-17 08:34	49.65	OK
9961	2026-09-17 08:35	49.09	OK	9962	2026-09-17 08:36	49.96	OK
9963	2026-09-17 08:37	50.28	OK	9964	2026-09-17 08:38	50.24	OK
9965	2026-09-17 08:39	50.58	OK	9966	2026-09-17 08:40	51.29	OK
9967	2026-09-17 08:41	49.75	OK	9968	2026-09-17 08:42	49.34	OK
9969	2026-09-17 08:43	49.02	OK	9970	2026-09-17 08:44	49.31	OK
9971	2026-09-17 08:45	49.87	OK	9972	2026-09-17 08:46	49.20	OK
9973	2026-09-17 08:47	49.24	OK	9974	2026-09-17 08:48	51.00	OK
9975	2026-09-17 08:49	50.71	OK	9976	2026-09-17 08:50	49.32	OK
9977	2026-09-17 08:51	48.03	OK	9978	2026-09-17 08:52	49.26	OK
9979	2026-09-17 08:53	48.00	OK	9980	2026-09-17 08:54	49.66	OK
9981	2026-09-17 08:55	50.28	OK	9982	2026-09-17 08:56	51.22	OK
9983	2026-09-17 08:57	49.04	OK	9984	2026-09-17 08:58	50.02	OK
9985	2026-09-17 08:59	50.38	OK	9986	2026-09-17 09:00	49.75	OK
9987	2026-09-17 09:01	48.02	OK	9988	2026-09-17 09:02	49.38	OK
9989	2026-09-17 09:03	50.13	OK	9990	2026-09-17 09:04	51.45	OK
9991	2026-09-17 09:05	47.91	OK	9992	2026-09-17 09:06	48.76	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9993	2026-09-17 09:07	50.85	OK	9994	2026-09-17 09:08	48.91	OK
9995	2026-09-17 09:09	49.59	OK	9996	2026-09-17 09:10	50.88	OK
9997	2026-09-17 09:11	49.06	OK	9998	2026-09-17 09:12	50.44	OK
9999	2026-09-17 09:13	50.43	OK	10000	2026-09-17 09:14	49.19	OK
10001	2026-09-17 09:15	49.19	OK	10002	2026-09-17 09:16	50.31	OK
10003	2026-09-17 09:17	50.50	OK	10004	2026-09-17 09:18	49.98	OK
10005	2026-09-17 09:19	50.05	OK	10006	2026-09-17 09:20	48.42	OK
10007	2026-09-17 09:21	48.83	OK	10008	2026-09-17 09:22	49.99	OK
10009	2026-09-17 09:23	49.99	OK	10010	2026-09-17 09:24	51.93	OK
10011	2026-09-17 09:25	48.40	OK	10012	2026-09-17 09:26	49.53	OK
10013	2026-09-17 09:27	49.47	OK	10014	2026-09-17 09:28	50.46	OK
10015	2026-09-17 09:29	49.55	OK	10016	2026-09-17 09:30	51.40	OK
10017	2026-09-17 09:31	48.10	OK	10018	2026-09-17 09:32	51.20	OK
10019	2026-09-17 09:33	49.42	OK	10020	2026-09-17 09:34	48.90	OK
10021	2026-09-17 09:35	52.15	OK	10022	2026-09-17 09:36	49.35	OK
10023	2026-09-17 09:37	50.41	OK	10024	2026-09-17 09:38	49.31	OK
10025	2026-09-17 09:39	52.66	OK	10026	2026-09-17 09:40	50.10	OK
10027	2026-09-17 09:41	50.11	OK	10028	2026-09-17 09:42	49.84	OK
10029	2026-09-17 09:43	51.67	OK	10030	2026-09-17 09:44	49.49	OK
10031	2026-09-17 09:45	48.68	OK	10032	2026-09-17 09:46	50.81	OK
10033	2026-09-17 09:47	50.18	OK	10034	2026-09-17 09:48	50.71	OK
10035	2026-09-17 09:49	50.10	OK	10036	2026-09-17 09:50	51.68	OK
10037	2026-09-17 09:51	49.26	OK	10038	2026-09-17 09:52	51.43	OK
10039	2026-09-17 09:53	49.65	OK	10040	2026-09-17 09:54	51.76	OK
10041	2026-09-17 09:55	52.71	OK	10042	2026-09-17 09:56	50.06	OK
10043	2026-09-17 09:57	50.48	OK	10044	2026-09-17 09:58	50.99	OK
10045	2026-09-17 09:59	50.28	OK	10046	2026-09-17 10:00	49.27	OK
10047	2026-09-17 10:01	49.35	OK	10048	2026-09-17 10:02	49.94	OK
10049	2026-09-17 10:03	51.79	OK	10050	2026-09-17 10:04	50.80	OK
10051	2026-09-17 10:05	49.72	OK	10052	2026-09-17 10:06	51.65	OK
10053	2026-09-17 10:07	49.44	OK	10054	2026-09-17 10:08	51.63	OK
10055	2026-09-17 10:09	52.67	OK	10055	2026-09-17 10:10	51.26	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
10057	2026-09-17 10:11	49.60	OK	10058	2026-09-17 10:12	50.86	OK
10059	2026-09-17 10:13	48.76	OK	10060	2026-09-17 10:14	51.75	OK
10061	2026-09-17 10:15	50.22	OK	10062	2026-09-17 10:16	50.09	OK
10063	2026-09-17 10:17	50.16	OK	10064	2026-09-17 10:18	51.17	OK
10065	2026-09-17 10:19	51.89	OK	10066	2026-09-17 10:20	51.27	OK
10067	2026-09-17 10:21	51.13	OK	10068	2026-09-17 10:22	49.89	OK
10069	2026-09-17 10:23	50.40	OK	10070	2026-09-17 10:24	50.13	OK
10071	2026-09-17 10:25	52.58	OK	10072	2026-09-17 10:26	51.66	OK
10073	2026-09-17 10:27	51.13	OK	10074	2026-09-17 10:28	49.05	OK
10075	2026-09-17 10:29	51.65	OK	10076	2026-09-17 10:30	50.31	OK
10077	2026-09-17 10:31	51.08	OK	10078	2026-09-17 10:32	49.25	OK
10079	2026-09-17 10:33	49.58	OK	10080	2026-09-17 10:34	49.29	OK
10081	2026-09-17 10:35	50.83	OK	10082	2026-09-17 10:36	50.27	OK
10083	2026-09-17 10:37	50.01	OK	10084	2026-09-17 10:38	51.41	OK
10085	2026-09-17 10:39	51.43	OK	10086	2026-09-17 10:40	50.29	OK
10087	2026-09-17 10:41	51.02	OK	10088	2026-09-17 10:42	52.05	OK
10089	2026-09-17 10:43	51.09	OK	10090	2026-09-17 10:44	52.01	OK
10091	2026-09-17 10:45	51.16	OK	10092	2026-09-17 10:46	53.24	OK
10093	2026-09-17 10:47	49.89	OK	10094	2026-09-17 10:48	51.81	OK
10095	2026-09-17 10:49	50.45	OK	10096	2026-09-17 10:50	50.02	OK
10097	2026-09-17 10:51	51.76	OK	10098	2026-09-17 10:52	50.65	OK
10099	2026-09-17 10:53	51.14	OK	10100	2026-09-17 10:54	52.67	OK
10101	2026-09-17 10:55	50.51	OK	10102	2026-09-17 10:56	52.85	OK
10103	2026-09-17 10:57	50.28	OK	10104	2026-09-17 10:58	51.82	OK
10105	2026-09-17 10:59	51.27	OK	10106	2026-09-17 11:00	53.80	OK
10107	2026-09-17 11:01	50.32	OK	10108	2026-09-17 11:02	49.59	OK
10109	2026-09-17 11:03	49.94	OK	10110	2026-09-17 11:04	52.60	OK
10111	2026-09-17 11:05	52.33	OK	10112	2026-09-17 11:06	52.44	OK
10113	2026-09-17 11:07	50.28	OK	10114	2026-09-17 11:08	50.44	OK
10115	2026-09-17 11:09	50.97	OK	10116	2026-09-17 11:10	51.69	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
10117	2026-09-17 11:11	53.21	OK	10118	2026-09-17 11:12	52.74	OK
10119	2026-09-17 11:13	50.98	OK	10120	2026-09-17 11:14	49.64	OK
10121	2026-09-17 11:15	49.36	OK	10122	2026-09-17 11:16	50.06	OK
10123	2026-09-17 11:17	51.48	OK	10124	2026-09-17 11:18	50.36	OK
10125	2026-09-17 11:19	51.43	OK	10126	2026-09-17 11:20	52.55	OK
10127	2026-09-17 11:21	49.58	OK	10128	2026-09-17 11:22	50.44	OK
10129	2026-09-17 11:23	48.95	OK	10130	2026-09-17 11:24	50.53	OK
10131	2026-09-17 11:25	50.97	OK	10132	2026-09-17 11:26	50.17	OK
10133	2026-09-17 11:27	52.21	OK	10134	2026-09-17 11:28	50.14	OK
10135	2026-09-17 11:29	51.87	OK	10136	2026-09-17 11:30	50.46	OK
10137	2026-09-17 11:31	54.28	OK	10138	2026-09-17 11:32	49.41	OK
10139	2026-09-17 11:33	52.18	OK	10140	2026-09-17 11:34	51.16	OK
10141	2026-09-17 11:35	53.58	OK	10142	2026-09-17 11:36	50.05	OK
10143	2026-09-17 11:37	50.64	OK	10144	2026-09-17 11:38	52.01	OK
10145	2026-09-17 11:39	52.84	OK	10146	2026-09-17 11:40	51.21	OK
10147	2026-09-17 11:41	50.39	OK	10148	2026-09-17 11:42	51.44	OK
10149	2026-09-17 11:43	50.88	OK	10150	2026-09-17 11:44	52.01	OK
10151	2026-09-17 11:45	50.92	OK	10152	2026-09-17 11:46	51.15	OK
10153	2026-09-17 11:47	51.15	OK	10154	2026-09-17 11:48	51.75	OK
10155	2026-09-17 11:49	51.32	OK	10156	2026-09-17 11:50	52.86	OK
10157	2026-09-17 11:51	51.39	OK	10158	2026-09-17 11:52	52.27	OK
10159	2026-09-17 11:53	52.00	OK	10160	2026-09-17 11:54	51.25	OK
10161	2026-09-17 11:55	53.14	OK	10162	2026-09-17 11:56	49.97	OK
10163	2026-09-17 11:57	52.98	OK	10164	2026-09-17 11:58	52.71	OK
10165	2026-09-17 11:59	52.31	OK	10166	2026-09-17 12:00	51.02	OK
10167	2026-09-17 12:01	51.31	OK	10168	2026-09-17 12:02	51.76	OK
10169	2026-09-17 12:03	53.07	OK	10170	2026-09-17 12:04	53.38	OK
10171	2026-09-17 12:05	52.23	OK	10172	2026-09-17 12:06	50.84	OK
10173	2026-09-17 12:07	51.91	OK	10174	2026-09-17 12:08	50.92	OK
1017	2026-09-17 12:09	52.42	OK	1017	2026-09-17 12:10	52.94	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
10177	2026-09-17 12:11	50.71	OK	10178	2026-09-17 12:12	52.53	OK
10179	2026-09-17 12:13	52.57	OK	10180	2026-09-17 12:14	50.68	OK
10181	2026-09-17 12:15	52.55	OK	10182	2026-09-17 12:16	51.26	OK
10183	2026-09-17 12:17	52.33	OK	10184	2026-09-17 12:18	52.53	OK
10185	2026-09-17 12:19	52.03	OK	10186	2026-09-17 12:20	50.68	OK
10187	2026-09-17 12:21	53.94	OK	10188	2026-09-17 12:22	52.26	OK
10189	2026-09-17 12:23	51.53	OK	10190	2026-09-17 12:24	51.26	OK
10191	2026-09-17 12:25	52.43	OK	10192	2026-09-17 12:26	54.37	OK
10193	2026-09-17 12:27	52.96	OK	10194	2026-09-17 12:28	52.01	OK
10195	2026-09-17 12:29	52.09	OK	10196	2026-09-17 12:30	52.94	OK
10197	2026-09-17 12:31	53.03	OK	10198	2026-09-17 12:32	51.94	OK
10199	2026-09-17 12:33	54.24	OK	10200	2026-09-17 12:34	52.62	OK
10201	2026-09-17 12:35	51.18	OK	10202	2026-09-17 12:36	51.16	OK
10203	2026-09-17 12:37	51.78	OK	10204	2026-09-17 12:38	51.55	OK
10205	2026-09-17 12:39	51.55	OK	10206	2026-09-17 12:40	50.25	OK
10207	2026-09-17 12:41	53.26	OK	10208	2026-09-17 12:42	52.48	OK
10209	2026-09-17 12:43	50.00	OK	10210	2026-09-17 12:44	51.70	OK
10211	2026-09-17 12:45	50.94	OK	10212	2026-09-17 12:46	52.29	OK
10213	2026-09-17 12:47	51.76	OK	10214	2026-09-17 12:48	51.84	OK
10215	2026-09-17 12:49	51.37	OK	10216	2026-09-17 12:50	52.12	OK
10217	2026-09-17 12:51	52.89	OK	10218	2026-09-17 12:52	50.62	OK
10219	2026-09-17 12:53	51.34	OK	10220	2026-09-17 12:54	53.59	OK
10221	2026-09-17 12:55	51.91	OK	10222	2026-09-17 12:56	51.78	OK
10223	2026-09-17 12:57	52.96	OK	10224	2026-09-17 12:58	51.11	OK
10225	2026-09-17 12:59	53.10	OK	10226	2026-09-17 13:00	54.02	OK
10227	2026-09-17 13:01	52.61	OK	10228	2026-09-17 13:02	51.29	OK
10229	2026-09-17 13:03	49.88	OK	10230	2026-09-17 13:04	51.48	OK
10231	2026-09-17 13:05	51.13	OK	10232	2026-09-17 13:06	52.57	OK
10233	2026-09-17 13:07	51.00	OK	10234	2026-09-17 13:08	52.68	OK
1023	2026-09-17 13:09	53.50	OK	1023	2026-09-17 13:10	51.51	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
10237	2026-09-17 13:11	53.15	OK	10238	2026-09-17 13:12	49.49	OK
10239	2026-09-17 13:13	51.37	OK	10240	2026-09-17 13:14	50.80	OK
10241	2026-09-17 13:15	52.16	OK	10242	2026-09-17 13:16	51.92	OK
10243	2026-09-17 13:17	51.29	OK	10244	2026-09-17 13:18	52.36	OK
10245	2026-09-17 13:19	51.90	OK	10246	2026-09-17 13:20	52.57	OK
10247	2026-09-17 13:21	53.34	OK	10248	2026-09-17 13:22	51.08	OK
10249	2026-09-17 13:23	52.77	OK	10250	2026-09-17 13:24	51.22	OK
10251	2026-09-17 13:25	54.08	OK	10252	2026-09-17 13:26	53.39	OK
10253	2026-09-17 13:27	49.65	OK	10254	2026-09-17 13:28	52.37	OK
10255	2026-09-17 13:29	50.68	OK	10256	2026-09-17 13:30	52.71	OK
10257	2026-09-17 13:31	52.02	OK	10258	2026-09-17 13:32	53.19	OK
10259	2026-09-17 13:33	50.82	OK	10260	2026-09-17 13:34	52.27	OK
10261	2026-09-17 13:35	52.53	OK	10262	2026-09-17 13:36	53.28	OK
10263	2026-09-17 13:37	51.84	OK	10264	2026-09-17 13:38	50.87	OK
10265	2026-09-17 13:39	52.45	OK	10266	2026-09-17 13:40	51.41	OK
10267	2026-09-17 13:41	50.34	OK	10268	2026-09-17 13:42	52.33	OK
10269	2026-09-17 13:43	51.32	OK	10270	2026-09-17 13:44	51.87	OK
10271	2026-09-17 13:45	51.25	OK	10272	2026-09-17 13:46	53.27	OK
10273	2026-09-17 13:47	52.93	OK	10274	2026-09-17 13:48	52.34	OK
10275	2026-09-17 13:49	51.27	OK	10276	2026-09-17 13:50	51.17	OK
10277	2026-09-17 13:51	52.22	OK	10278	2026-09-17 13:52	52.16	OK
10279	2026-09-17 13:53	51.96	OK	10280	2026-09-17 13:54	51.33	OK
10281	2026-09-17 13:55	51.01	OK	10282	2026-09-17 13:56	50.72	OK
10283	2026-09-17 13:57	53.02	OK	10284	2026-09-17 13:58	53.36	OK
10285	2026-09-17 13:59	50.51	OK	10286	2026-09-17 14:00	51.92	OK
10287	2026-09-17 14:01	51.75	OK	10288	2026-09-17 14:02	53.04	OK
10289	2026-09-17 14:03	52.60	OK	10290	2026-09-17 14:04	52.44	OK
10291	2026-09-17 14:05	51.87	OK	10292	2026-09-17 14:06	50.74	OK
10293	2026-09-17 14:07	49.85	OK	10294	2026-09-17 14:08	52.03	OK
1029	2026-09-17 14:09	52.40	OK	1029	2026-09-17 14:10	53.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
10297	2026-09-17 14:11	51.64	OK	10298	2026-09-17 14:12	51.80	OK
10299	2026-09-17 14:13	52.08	OK	10300	2026-09-17 14:14	50.70	OK
10301	2026-09-17 14:15	53.07	OK	10302	2026-09-17 14:16	49.92	OK
10303	2026-09-17 14:17	51.96	OK	10304	2026-09-17 14:18	51.01	OK
10305	2026-09-17 14:19	52.35	OK	10306	2026-09-17 14:20	50.79	OK
10307	2026-09-17 14:21	51.95	OK	10308	2026-09-17 14:22	52.33	OK
10309	2026-09-17 14:23	52.09	OK	10310	2026-09-17 14:24	52.15	OK
10311	2026-09-17 14:25	51.30	OK	10312	2026-09-17 14:26	53.16	OK
10313	2026-09-17 14:27	51.47	OK	10314	2026-09-17 14:28	50.67	OK
10315	2026-09-17 14:29	52.39	OK	10316	2026-09-17 14:30	52.73	OK
10317	2026-09-17 14:31	51.79	OK	10318	2026-09-17 14:32	52.70	OK
10319	2026-09-17 14:33	52.31	OK	10320	2026-09-17 14:34	51.39	OK
10321	2026-09-17 14:35	51.17	OK	10322	2026-09-17 14:36	53.07	OK
10323	2026-09-17 14:37	54.21	OK	10324	2026-09-17 14:38	50.14	OK
10325	2026-09-17 14:39	50.61	OK	10326	2026-09-17 14:40	50.59	OK
10327	2026-09-17 14:41	50.56	OK	10328	2026-09-17 14:42	51.95	OK
10329	2026-09-17 14:43	50.81	OK	10330	2026-09-17 14:44	51.33	OK
10331	2026-09-17 14:45	51.19	OK	10332	2026-09-17 14:46	49.34	OK
10333	2026-09-17 14:47	50.93	OK	10334	2026-09-17 14:48	51.84	OK
10335	2026-09-17 14:49	52.98	OK	10336	2026-09-17 14:50	52.37	OK
10337	2026-09-17 14:51	51.41	OK	10338	2026-09-17 14:52	51.07	OK
10339	2026-09-17 14:53	53.89	OK	10340	2026-09-17 14:54	52.14	OK
10341	2026-09-17 14:55	50.07	OK	10342	2026-09-17 14:56	52.45	OK
10343	2026-09-17 14:57	51.13	OK	10344	2026-09-17 14:58	50.29	OK
10345	2026-09-17 14:59	54.23	OK	10346	2026-09-17 15:00	49.16	OK
10347	2026-09-17 15:01	50.56	OK	10348	2026-09-17 15:02	52.85	OK
10349	2026-09-17 15:03	53.54	OK	10350	2026-09-17 15:04	52.49	OK
10351	2026-09-17 15:05	51.14	OK	10352	2026-09-17 15:06	52.06	OK
10353	2026-09-17 15:07	52.68	OK	10354	2026-09-17 15:08	52.65	OK
1035	2026-09-17 15:09	51.86	OK	1035	2026-09-17 15:10	51.02	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
10357	2026-09-17 15:11	51.72	OK	10358	2026-09-17 15:12	52.03	OK
10359	2026-09-17 15:13	51.60	OK	10360	2026-09-17 15:14	53.53	OK
10361	2026-09-17 15:15	52.24	OK	10362	2026-09-17 15:16	52.99	OK
10363	2026-09-17 15:17	50.92	OK	10364	2026-09-17 15:18	53.58	OK
10365	2026-09-17 15:19	51.11	OK	10366	2026-09-17 15:20	51.59	OK
10367	2026-09-17 15:21	52.28	OK	10368	2026-09-17 15:22	50.04	OK
10369	2026-09-17 15:23	50.32	OK	10370	2026-09-17 15:24	50.40	OK
10371	2026-09-17 15:25	51.45	OK	10372	2026-09-17 15:26	52.71	OK
10373	2026-09-17 15:27	52.07	OK	10374	2026-09-17 15:28	51.22	OK
10375	2026-09-17 15:29	51.86	OK	10376	2026-09-17 15:30	50.37	OK
10377	2026-09-17 15:31	51.61	OK	10378	2026-09-17 15:32	51.05	OK
10379	2026-09-17 15:33	51.68	OK	10380	2026-09-17 15:34	52.09	OK
10381	2026-09-17 15:35	51.65	OK	10382	2026-09-17 15:36	51.56	OK
10383	2026-09-17 15:37	50.28	OK	10384	2026-09-17 15:38	50.94	OK
10385	2026-09-17 15:39	51.43	OK	10386	2026-09-17 15:40	51.40	OK
10387	2026-09-17 15:41	52.14	OK	10388	2026-09-17 15:42	50.95	OK
10389	2026-09-17 15:43	50.90	OK	10390	2026-09-17 15:44	51.80	OK
10391	2026-09-17 15:45	50.31	OK	10392	2026-09-17 15:46	52.11	OK
10393	2026-09-17 15:47	52.13	OK	10394	2026-09-17 15:48	51.33	OK
10395	2026-09-17 15:49	51.40	OK	10396	2026-09-17 15:50	52.19	OK
10397	2026-09-17 15:51	51.20	OK	10398	2026-09-17 15:52	52.41	OK
10399	2026-09-17 15:53	51.19	OK	10400	2026-09-17 15:54	51.62	OK
10401	2026-09-17 15:55	48.84	OK	10402	2026-09-17 15:56	51.47	OK
10403	2026-09-17 15:57	51.01	OK	10404	2026-09-17 15:58	49.90	OK
10405	2026-09-17 15:59	53.08	OK	10406	2026-09-17 16:00	50.60	OK
10407	2026-09-17 16:01	52.69	OK	10408	2026-09-17 16:02	50.10	OK
10409	2026-09-17 16:03	51.13	OK	10410	2026-09-17 16:04	50.27	OK
10411	2026-09-17 16:05	52.18	OK	10412	2026-09-17 16:06	50.61	OK
10413	2026-09-17 16:07	52.85	OK	10414	2026-09-17 16:08	51.93	OK
1041	2026-09-17 16:09	52.05	OK	1041	2026-09-17 16:10	50.75	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
10417	2026-09-17 16:11	50.13	OK	10418	2026-09-17 16:12	50.90	OK
10419	2026-09-17 16:13	49.81	OK	10420	2026-09-17 16:14	49.74	OK
10421	2026-09-17 16:15	51.38	OK	10422	2026-09-17 16:16	50.43	OK
10423	2026-09-17 16:17	50.93	OK	10424	2026-09-17 16:18	51.27	OK
10425	2026-09-17 16:19	50.63	OK	10426	2026-09-17 16:20	50.69	OK
10427	2026-09-17 16:21	52.16	OK	10428	2026-09-17 16:22	51.50	OK
10429	2026-09-17 16:23	52.32	OK	10430	2026-09-17 16:24	50.81	OK
10431	2026-09-17 16:25	51.49	OK	10432	2026-09-17 16:26	52.12	OK
10433	2026-09-17 16:27	51.54	OK	10434	2026-09-17 16:28	51.38	OK
10435	2026-09-17 16:29	48.25	OK	10436	2026-09-17 16:30	49.44	OK
10437	2026-09-17 16:31	51.57	OK	10438	2026-09-17 16:32	52.68	OK
10439	2026-09-17 16:33	51.41	OK	10440	2026-09-17 16:34	51.49	OK
10441	2026-09-17 16:35	50.36	OK	10442	2026-09-17 16:36	51.88	OK
10443	2026-09-17 16:37	49.37	OK	10444	2026-09-17 16:38	50.36	OK
10445	2026-09-17 16:39	50.16	OK	10446	2026-09-17 16:40	49.78	OK
10447	2026-09-17 16:41	50.40	OK	10448	2026-09-17 16:42	50.43	OK
10449	2026-09-17 16:43	50.19	OK	10450	2026-09-17 16:44	49.06	OK
10451	2026-09-17 16:45	51.24	OK	10452	2026-09-17 16:46	52.10	OK
10453	2026-09-17 16:47	50.69	OK	10454	2026-09-17 16:48	50.34	OK
10455	2026-09-17 16:49	51.63	OK	10456	2026-09-17 16:50	51.28	OK
10457	2026-09-17 16:51	49.38	OK	10458	2026-09-17 16:52	49.60	OK
10459	2026-09-17 16:53	51.84	OK	10460	2026-09-17 16:54	49.64	OK
10461	2026-09-17 16:55	50.88	OK	10462	2026-09-17 16:56	50.59	OK
10463	2026-09-17 16:57	49.67	OK	10464	2026-09-17 16:58	50.88	OK
10465	2026-09-17 16:59	50.26	OK	10466	2026-09-17 17:00	51.62	OK
10467	2026-09-17 17:01	49.34	OK	10468	2026-09-17 17:02	50.26	OK
10469	2026-09-17 17:03	50.94	OK	10470	2026-09-17 17:04	51.04	OK
10471	2026-09-17 17:05	49.07	OK	10472	2026-09-17 17:06	49.98	OK
10473	2026-09-17 17:07	52.14	OK	10474	2026-09-17 17:08	50.63	OK
1047	2026-09-17 17:09	49.57	OK	1047	2026-09-17 17:10	51.92	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
10477	2026-09-17 17:11	50.19	OK	10478	2026-09-17 17:12	51.21	OK
10479	2026-09-17 17:13	51.43	OK	10480	2026-09-17 17:14	49.08	OK
10481	2026-09-17 17:15	51.61	OK	10482	2026-09-17 17:16	50.36	OK
10483	2026-09-17 17:17	49.85	OK	10484	2026-09-17 17:18	50.64	OK
10485	2026-09-17 17:19	51.59	OK	10486	2026-09-17 17:20	51.84	OK
10487	2026-09-17 17:21	49.31	OK	10488	2026-09-17 17:22	50.39	OK
10489	2026-09-17 17:23	50.67	OK	10490	2026-09-17 17:24	51.19	OK
10491	2026-09-17 17:25	50.23	OK	10492	2026-09-17 17:26	49.74	OK
10493	2026-09-17 17:27	50.64	OK	10494	2026-09-17 17:28	48.84	OK
10495	2026-09-17 17:29	50.23	OK	10496	2026-09-17 17:30	50.67	OK
10497	2026-09-17 17:31	48.41	OK	10498	2026-09-17 17:32	50.72	OK
10499	2026-09-17 17:33	50.63	OK	10500	2026-09-17 17:34	50.02	OK
10501	2026-09-17 17:35	49.57	OK	10502	2026-09-17 17:36	49.99	OK
10503	2026-09-17 17:37	48.14	OK	10504	2026-09-17 17:38	50.77	OK
10505	2026-09-17 17:39	50.03	OK	10506	2026-09-17 17:40	49.46	OK
10507	2026-09-17 17:41	49.74	OK	10508	2026-09-17 17:42	49.12	OK
10509	2026-09-17 17:43	49.57	OK	10510	2026-09-17 17:44	49.93	OK
10511	2026-09-17 17:45	49.56	OK	10512	2026-09-17 17:46	48.60	OK
10513	2026-09-17 17:47	50.93	OK	10514	2026-09-17 17:48	49.65	OK
10515	2026-09-17 17:49	48.63	OK	10516	2026-09-17 17:50	50.84	OK
10517	2026-09-17 17:51	48.36	OK	10518	2026-09-17 17:52	48.46	OK
10519	2026-09-17 17:53	51.23	OK	10520	2026-09-17 17:54	47.72	OK
10521	2026-09-17 17:55	49.01	OK	10522	2026-09-17 17:56	49.95	OK
10523	2026-09-17 17:57	49.67	OK	10524	2026-09-17 17:58	50.20	OK
10525	2026-09-17 17:59	50.26	OK	10526	2026-09-17 18:00	50.29	OK
10527	2026-09-17 18:01	49.14	OK	10528	2026-09-17 18:02	49.09	OK
10529	2026-09-17 18:03	49.92	OK	10530	2026-09-17 18:04	50.47	OK
10531	2026-09-17 18:05	48.66	OK	10532	2026-09-17 18:06	49.75	OK
10533	2026-09-17 18:07	50.81	OK	10534	2026-09-17 18:08	47.60	OK
1053	2026-09-17 18:09	48.69	OK	1053	2026-09-17 18:10	50.31	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
10537	2026-09-17 18:11	48.93	OK	10538	2026-09-17 18:12	48.86	OK
10539	2026-09-17 18:13	49.51	OK	10540	2026-09-17 18:14	49.53	OK
10541	2026-09-17 18:15	49.61	OK	10542	2026-09-17 18:16	49.50	OK
10543	2026-09-17 18:17	50.14	OK	10544	2026-09-17 18:18	49.95	OK
10545	2026-09-17 18:19	50.97	OK	10546	2026-09-17 18:20	48.27	OK
10547	2026-09-17 18:21	50.58	OK	10548	2026-09-17 18:22	49.06	OK
10549	2026-09-17 18:23	49.07	OK	10550	2026-09-17 18:24	48.90	OK
10551	2026-09-17 18:25	48.02	OK	10552	2026-09-17 18:26	48.69	OK
10553	2026-09-17 18:27	50.40	OK	10554	2026-09-17 18:28	51.52	OK
10555	2026-09-17 18:29	50.44	OK	10556	2026-09-17 18:30	49.11	OK
10557	2026-09-17 18:31	49.56	OK	10558	2026-09-17 18:32	50.27	OK
10559	2026-09-17 18:33	48.95	OK	10560	2026-09-17 18:34	48.60	OK
10561	2026-09-17 18:35	49.43	OK	10562	2026-09-17 18:36	46.95	OK
10563	2026-09-17 18:37	49.65	OK	10564	2026-09-17 18:38	47.82	OK
10565	2026-09-17 18:39	50.46	OK	10566	2026-09-17 18:40	49.60	OK
10567	2026-09-17 18:41	48.24	OK	10568	2026-09-17 18:42	50.33	OK
10569	2026-09-17 18:43	50.33	OK	10570	2026-09-17 18:44	50.69	OK
10571	2026-09-17 18:45	48.14	OK	10572	2026-09-17 18:46	48.65	OK
10573	2026-09-17 18:47	50.01	OK	10574	2026-09-17 18:48	48.31	OK
10575	2026-09-17 18:49	49.92	OK	10576	2026-09-17 18:50	49.53	OK
10577	2026-09-17 18:51	50.89	OK	10578	2026-09-17 18:52	49.75	OK
10579	2026-09-17 18:53	48.03	OK	10580	2026-09-17 18:54	48.21	OK
10581	2026-09-17 18:55	48.76	OK	10582	2026-09-17 18:56	47.24	OK
10583	2026-09-17 18:57	48.93	OK	10584	2026-09-17 18:58	50.00	OK
10585	2026-09-17 18:59	49.56	OK	10586	2026-09-17 19:00	48.86	OK
10587	2026-09-17 19:01	50.07	OK	10588	2026-09-17 19:02	49.61	OK
10589	2026-09-17 19:03	48.73	OK	10590	2026-09-17 19:04	49.27	OK
10591	2026-09-17 19:05	50.11	OK	10592	2026-09-17 19:06	49.77	OK
10593	2026-09-17 19:07	49.04	OK	10594	2026-09-17 19:08	49.60	OK
1059	2026-09-17 19:09	50.63	OK	1059	2026-09-17 19:10	48.61	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
10597	2026-09-17 19:11	49.25	OK	10598	2026-09-17 19:12	47.42	OK
10599	2026-09-17 19:13	49.72	OK	10600	2026-09-17 19:14	48.74	OK
10601	2026-09-17 19:15	46.93	OK	10602	2026-09-17 19:16	46.84	OK
10603	2026-09-17 19:17	48.34	OK	10604	2026-09-17 19:18	49.36	OK
10605	2026-09-17 19:19	48.79	OK	10606	2026-09-17 19:20	49.40	OK
10607	2026-09-17 19:21	50.31	OK	10608	2026-09-17 19:22	47.93	OK
10609	2026-09-17 19:23	47.46	OK	10610	2026-09-17 19:24	48.95	OK
10611	2026-09-17 19:25	48.27	OK	10612	2026-09-17 19:26	49.25	OK
10613	2026-09-17 19:27	48.35	OK	10614	2026-09-17 19:28	49.31	OK
10615	2026-09-17 19:29	49.34	OK	10616	2026-09-17 19:30	49.57	OK
10617	2026-09-17 19:31	47.64	OK	10618	2026-09-17 19:32	49.29	OK
10619	2026-09-17 19:33	47.47	OK	10620	2026-09-17 19:34	46.26	OK
10621	2026-09-17 19:35	46.78	OK	10622	2026-09-17 19:36	48.48	OK
10623	2026-09-17 19:37	49.06	OK	10624	2026-09-17 19:38	49.66	OK
10625	2026-09-17 19:39	47.99	OK	10626	2026-09-17 19:40	48.63	OK
10627	2026-09-17 19:41	49.18	OK	10628	2026-09-17 19:42	48.75	OK
10629	2026-09-17 19:43	47.37	OK	10630	2026-09-17 19:44	46.57	OK
10631	2026-09-17 19:45	47.66	OK	10632	2026-09-17 19:46	48.37	OK
10633	2026-09-17 19:47	48.72	OK	10634	2026-09-17 19:48	48.37	OK
10635	2026-09-17 19:49	47.91	OK	10636	2026-09-17 19:50	48.64	OK
10637	2026-09-17 19:51	47.72	OK	10638	2026-09-17 19:52	49.71	OK
10639	2026-09-17 19:53	46.88	OK	10640	2026-09-17 19:54	48.84	OK
10641	2026-09-17 19:55	46.89	OK	10642	2026-09-17 19:56	48.85	OK
10643	2026-09-17 19:57	47.85	OK	10644	2026-09-17 19:58	49.43	OK
10645	2026-09-17 19:59	50.89	OK	10646	2026-09-17 20:00	47.61	OK
10647	2026-09-17 20:01	47.08	OK	10648	2026-09-17 20:02	48.25	OK
10649	2026-09-17 20:03	47.53	OK	10650	2026-09-17 20:04	47.25	OK
10651	2026-09-17 20:05	46.73	OK	10652	2026-09-17 20:06	48.28	OK
10653	2026-09-17 20:07	48.28	OK	10654	2026-09-17 20:08	47.16	OK
1065	2026-09-17 20:09	47.69	OK	1065	2026-09-17 20:10	46.59	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
10657	2026-09-17 20:11	48.52	OK	10658	2026-09-17 20:12	47.42	OK
10659	2026-09-17 20:13	48.73	OK	10660	2026-09-17 20:14	47.87	OK
10661	2026-09-17 20:15	49.06	OK	10662	2026-09-17 20:16	48.30	OK
10663	2026-09-17 20:17	48.45	OK	10664	2026-09-17 20:18	47.08	OK
10665	2026-09-17 20:19	46.67	OK	10666	2026-09-17 20:20	46.41	OK
10667	2026-09-17 20:21	48.01	OK	10668	2026-09-17 20:22	46.13	OK
10669	2026-09-17 20:23	46.98	OK	10670	2026-09-17 20:24	46.73	OK
10671	2026-09-17 20:25	47.65	OK	10672	2026-09-17 20:26	49.22	OK
10673	2026-09-17 20:27	48.24	OK	10674	2026-09-17 20:28	47.55	OK
10675	2026-09-17 20:29	47.15	OK	10676	2026-09-17 20:30	47.63	OK
10677	2026-09-17 20:31	47.21	OK	10678	2026-09-17 20:32	47.78	OK
10679	2026-09-17 20:33	46.50	OK	10680	2026-09-17 20:34	47.87	OK
10681	2026-09-17 20:35	45.90	OK	10682	2026-09-17 20:36	46.77	OK
10683	2026-09-17 20:37	48.28	OK	10684	2026-09-17 20:38	48.53	OK
10685	2026-09-17 20:39	47.15	OK	10686	2026-09-17 20:40	46.28	OK
10687	2026-09-17 20:41	48.74	OK	10688	2026-09-17 20:42	47.62	OK
10689	2026-09-17 20:43	48.94	OK	10690	2026-09-17 20:44	48.53	OK
10691	2026-09-17 20:45	48.71	OK	10692	2026-09-17 20:46	48.08	OK
10693	2026-09-17 20:47	47.27	OK	10694	2026-09-17 20:48	46.99	OK
10695	2026-09-17 20:49	46.60	OK	10696	2026-09-17 20:50	46.51	OK
10697	2026-09-17 20:51	48.67	OK	10698	2026-09-17 20:52	45.49	OK
10699	2026-09-17 20:53	47.08	OK	10700	2026-09-17 20:54	48.72	OK
10701	2026-09-17 20:55	47.51	OK	10702	2026-09-17 20:56	46.27	OK
10703	2026-09-17 20:57	46.10	OK	10704	2026-09-17 20:58	47.21	OK
10705	2026-09-17 20:59	45.57	OK	10706	2026-09-17 21:00	48.22	OK
10707	2026-09-17 21:01	47.63	OK	10708	2026-09-17 21:02	46.14	OK
10709	2026-09-17 21:03	47.63	OK	10710	2026-09-17 21:04	45.93	OK
10711	2026-09-17 21:05	47.80	OK	10712	2026-09-17 21:06	46.28	OK
10713	2026-09-17 21:07	47.30	OK	10714	2026-09-17 21:08	48.06	OK
1071	2026-09-17 21:09	46.90	OK	1071	2026-09-17 21:10	46.44	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
10717	2026-09-17 21:11	47.08	OK	10718	2026-09-17 21:12	46.13	OK
10719	2026-09-17 21:13	46.28	OK	10720	2026-09-17 21:14	45.80	OK
10721	2026-09-17 21:15	46.71	OK	10722	2026-09-17 21:16	45.26	OK
10723	2026-09-17 21:17	47.24	OK	10724	2026-09-17 21:18	45.60	OK
10725	2026-09-17 21:19	45.59	OK	10726	2026-09-17 21:20	45.21	OK
10727	2026-09-17 21:21	45.90	OK	10728	2026-09-17 21:22	47.56	OK
10729	2026-09-17 21:23	47.50	OK	10730	2026-09-17 21:24	47.39	OK
10731	2026-09-17 21:25	47.21	OK	10732	2026-09-17 21:26	47.51	OK
10733	2026-09-17 21:27	46.97	OK	10734	2026-09-17 21:28	46.11	OK
10735	2026-09-17 21:29	46.17	OK	10736	2026-09-17 21:30	46.74	OK
10737	2026-09-17 21:31	46.62	OK	10738	2026-09-17 21:32	46.58	OK
10739	2026-09-17 21:33	46.77	OK	10740	2026-09-17 21:34	47.79	OK
10741	2026-09-17 21:35	47.57	OK	10742	2026-09-17 21:36	45.16	OK
10743	2026-09-17 21:37	48.00	OK	10744	2026-09-17 21:38	47.75	OK
10745	2026-09-17 21:39	47.20	OK	10746	2026-09-17 21:40	46.79	OK
10747	2026-09-17 21:41	47.43	OK	10748	2026-09-17 21:42	46.42	OK
10749	2026-09-17 21:43	47.62	OK	10750	2026-09-17 21:44	47.76	OK
10751	2026-09-17 21:45	47.94	OK	10752	2026-09-17 21:46	46.08	OK
10753	2026-09-17 21:47	46.32	OK	10754	2026-09-17 21:48	45.84	OK
10755	2026-09-17 21:49	45.47	OK	10756	2026-09-17 21:50	46.07	OK
10757	2026-09-17 21:51	47.11	OK	10758	2026-09-17 21:52	46.75	OK
10759	2026-09-17 21:53	47.15	OK	10760	2026-09-17 21:54	45.53	OK
10761	2026-09-17 21:55	46.74	OK	10762	2026-09-17 21:56	46.18	OK
10763	2026-09-17 21:57	45.77	OK	10764	2026-09-17 21:58	46.66	OK
10765	2026-09-17 21:59	46.35	OK	10766	2026-09-17 22:00	45.94	OK
10767	2026-09-17 22:01	46.06	OK	10768	2026-09-17 22:02	47.14	OK
10769	2026-09-17 22:03	45.69	OK	10770	2026-09-17 22:04	46.82	OK
10771	2026-09-17 22:05	47.13	OK	10772	2026-09-17 22:06	46.11	OK
10773	2026-09-17 22:07	47.37	OK	10774	2026-09-17 22:08	47.59	OK
1077	2026-09-17 22:09	46.94	OK	1077	2026-09-17 22:10	44.24	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
10777	2026-09-17 22:11	47.42	OK	10778	2026-09-17 22:12	46.05	OK
10779	2026-09-17 22:13	47.36	OK	10780	2026-09-17 22:14	45.96	OK
10781	2026-09-17 22:15	46.69	OK	10782	2026-09-17 22:16	44.94	OK
10783	2026-09-17 22:17	46.47	OK	10784	2026-09-17 22:18	47.51	OK
10785	2026-09-17 22:19	46.67	OK	10786	2026-09-17 22:20	46.95	OK
10787	2026-09-17 22:21	45.31	OK	10788	2026-09-17 22:22	45.67	OK
10789	2026-09-17 22:23	44.98	OK	10790	2026-09-17 22:24	47.17	OK
10791	2026-09-17 22:25	47.69	OK	10792	2026-09-17 22:26	47.40	OK
10793	2026-09-17 22:27	47.22	OK	10794	2026-09-17 22:28	45.12	OK
10795	2026-09-17 22:29	46.52	OK	10796	2026-09-17 22:30	46.84	OK
10797	2026-09-17 22:31	47.04	OK	10798	2026-09-17 22:32	45.49	OK
10799	2026-09-17 22:33	47.16	OK	10800	2026-09-17 22:34	46.18	OK
10801	2026-09-17 22:35	46.11	OK	10802	2026-09-17 22:36	44.94	OK
10803	2026-09-17 22:37	45.59	OK	10804	2026-09-17 22:38	44.84	OK
10805	2026-09-17 22:39	46.19	OK	10806	2026-09-17 22:40	45.15	OK
10807	2026-09-17 22:41	44.20	OK	10808	2026-09-17 22:42	45.45	OK
10809	2026-09-17 22:43	45.99	OK	10810	2026-09-17 22:44	47.31	OK
10811	2026-09-17 22:45	45.79	OK	10812	2026-09-17 22:46	46.78	OK
10813	2026-09-17 22:47	46.03	OK	10814	2026-09-17 22:48	46.66	OK
10815	2026-09-17 22:49	46.56	OK	10816	2026-09-17 22:50	47.46	OK
10817	2026-09-17 22:51	47.55	OK	10818	2026-09-17 22:52	44.34	OK
10819	2026-09-17 22:53	44.80	OK	10820	2026-09-17 22:54	44.95	OK
10821	2026-09-17 22:55	47.68	OK	10822	2026-09-17 22:56	45.22	OK
10823	2026-09-17 22:57	44.58	OK	10824	2026-09-17 22:58	45.88	OK
10825	2026-09-17 22:59	44.99	OK	10826	2026-09-17 23:00	45.23	OK
10827	2026-09-17 23:01	46.30	OK	10828	2026-09-17 23:02	44.85	OK
10829	2026-09-17 23:03	46.57	OK	10830	2026-09-17 23:04	44.99	OK
10831	2026-09-17 23:05	44.70	OK	10832	2026-09-17 23:06	46.94	OK
10833	2026-09-17 23:07	44.22	OK	10834	2026-09-17 23:08	45.76	OK
1083	2026-09-17 23:09	44.62	OK	1083	2026-09-17 23:10	45.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
10837	2026-09-17 23:11	48.16	OK	10838	2026-09-17 23:12	44.98	OK
10839	2026-09-17 23:13	45.25	OK	10840	2026-09-17 23:14	44.14	OK
10841	2026-09-17 23:15	43.92	OK	10842	2026-09-17 23:16	45.53	OK
10843	2026-09-17 23:17	45.96	OK	10844	2026-09-17 23:18	46.44	OK
10845	2026-09-17 23:19	46.14	OK	10846	2026-09-17 23:20	44.35	OK
10847	2026-09-17 23:21	45.27	OK	10848	2026-09-17 23:22	45.97	OK
10849	2026-09-17 23:23	44.94	OK	10850	2026-09-17 23:24	45.08	OK
10851	2026-09-17 23:25	46.62	OK	10852	2026-09-17 23:26	43.95	OK
10853	2026-09-17 23:27	44.64	OK	10854	2026-09-17 23:28	47.75	OK
10855	2026-09-17 23:29	45.86	OK	10856	2026-09-17 23:30	44.13	OK
10857	2026-09-17 23:31	45.67	OK	10858	2026-09-17 23:32	45.24	OK
10859	2026-09-17 23:33	44.08	OK	10860	2026-09-17 23:34	46.33	OK
10861	2026-09-17 23:35	44.85	OK	10862	2026-09-17 23:36	44.99	OK
10863	2026-09-17 23:37	44.94	OK	10864	2026-09-17 23:38	45.95	OK
10865	2026-09-17 23:39	45.52	OK	10866	2026-09-17 23:40	44.93	OK
10867	2026-09-17 23:41	44.14	OK	10868	2026-09-17 23:42	44.42	OK
10869	2026-09-17 23:43	46.12	OK	10870	2026-09-17 23:44	44.92	OK
10871	2026-09-17 23:45	47.06	OK	10872	2026-09-17 23:46	45.03	OK
10873	2026-09-17 23:47	46.59	OK	10874	2026-09-17 23:48	45.97	OK
10875	2026-09-17 23:49	47.19	OK	10876	2026-09-17 23:50	46.00	OK
10877	2026-09-17 23:51	46.61	OK	10878	2026-09-17 23:52	43.83	OK
10879	2026-09-17 23:53	46.19	OK	10880	2026-09-17 23:54	46.13	OK
10881	2026-09-17 23:55	45.98	OK	10882	2026-09-17 23:56	43.29	OK
10883	2026-09-17 23:57	45.08	OK	10884	2026-09-17 23:58	46.11	OK
10885	2026-09-17 23:59	45.38	OK	10886	2026-09-18 00:00	45.80	OK
10887	2026-09-18 00:01	45.42	OK	10888	2026-09-18 00:02	47.03	OK
10889	2026-09-18 00:03	43.79	OK	10890	2026-09-18 00:04	45.20	OK
10891	2026-09-18 00:05	45.52	OK	10892	2026-09-18 00:06	46.11	OK
10893	2026-09-18 00:07	44.18	OK	10894	2026-09-18 00:08	45.91	OK
1089	2026-09-18 00:09	43.98	OK	1089	2026-09-18 00:10	46.39	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
10897	2026-09-18 00:11	45.49	OK	10898	2026-09-18 00:12	45.92	OK
10899	2026-09-18 00:13	45.43	OK	10900	2026-09-18 00:14	42.66	OK
10901	2026-09-18 00:15	45.56	OK	10902	2026-09-18 00:16	44.07	OK
10903	2026-09-18 00:17	45.64	OK	10904	2026-09-18 00:18	43.75	OK
10905	2026-09-18 00:19	47.41	OK	10906	2026-09-18 00:20	46.10	OK
10907	2026-09-18 00:21	44.86	OK	10908	2026-09-18 00:22	44.24	OK
10909	2026-09-18 00:23	43.24	OK	10910	2026-09-18 00:24	44.65	OK
10911	2026-09-18 00:25	43.34	OK	10912	2026-09-18 00:26	43.50	OK
10913	2026-09-18 00:27	44.32	OK	10914	2026-09-18 00:28	43.43	OK
10915	2026-09-18 00:29	44.76	OK	10916	2026-09-18 00:30	45.21	OK
10917	2026-09-18 00:31	44.49	OK	10918	2026-09-18 00:32	44.64	OK
10919	2026-09-18 00:33	45.04	OK	10920	2026-09-18 00:34	44.62	OK
10921	2026-09-18 00:35	45.58	OK	10922	2026-09-18 00:36	43.92	OK
10923	2026-09-18 00:37	44.28	OK	10924	2026-09-18 00:38	46.30	OK
10925	2026-09-18 00:39	45.50	OK	10926	2026-09-18 00:40	45.91	OK
10927	2026-09-18 00:41	46.24	OK	10928	2026-09-18 00:42	44.44	OK
10929	2026-09-18 00:43	44.58	OK	10930	2026-09-18 00:44	43.67	OK
10931	2026-09-18 00:45	45.96	OK	10932	2026-09-18 00:46	44.19	OK
10933	2026-09-18 00:47	45.10	OK	10934	2026-09-18 00:48	46.81	OK
10935	2026-09-18 00:49	44.55	OK	10936	2026-09-18 00:50	45.24	OK
10937	2026-09-18 00:51	45.55	OK	10938	2026-09-18 00:52	44.60	OK
10939	2026-09-18 00:53	44.53	OK	10940	2026-09-18 00:54	47.26	OK
10941	2026-09-18 00:55	45.66	OK	10942	2026-09-18 00:56	45.00	OK
10943	2026-09-18 00:57	44.06	OK	10944	2026-09-18 00:58	45.30	OK
10945	2026-09-18 00:59	43.95	OK	10946	2026-09-18 01:00	44.75	OK
10947	2026-09-18 01:01	46.01	OK	10948	2026-09-18 01:02	43.63	OK
10949	2026-09-18 01:03	44.98	OK	10950	2026-09-18 01:04	44.48	OK
10951	2026-09-18 01:05	43.42	OK	10952	2026-09-18 01:06	43.41	OK
10953	2026-09-18 01:07	45.71	OK	10954	2026-09-18 01:08	46.07	OK
1095	2026-09-18 01:09	44.44	OK	1095	2026-09-18 01:10	45.66	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
10957	2026-09-18 01:11	43.60	OK	10958	2026-09-18 01:12	46.03	OK
10959	2026-09-18 01:13	43.86	OK	10960	2026-09-18 01:14	46.56	OK
10961	2026-09-18 01:15	43.16	OK	10962	2026-09-18 01:16	44.87	OK
10963	2026-09-18 01:17	44.53	OK	10964	2026-09-18 01:18	45.20	OK
10965	2026-09-18 01:19	44.56	OK	10966	2026-09-18 01:20	45.72	OK
10967	2026-09-18 01:21	44.93	OK	10968	2026-09-18 01:22	46.55	OK
10969	2026-09-18 01:23	46.53	OK	10970	2026-09-18 01:24	45.15	OK
10971	2026-09-18 01:25	45.95	OK	10972	2026-09-18 01:26	43.75	OK
10973	2026-09-18 01:27	45.16	OK	10974	2026-09-18 01:28	43.97	OK
10975	2026-09-18 01:29	45.82	OK	10976	2026-09-18 01:30	46.56	OK
10977	2026-09-18 01:31	43.54	OK	10978	2026-09-18 01:32	44.34	OK
10979	2026-09-18 01:33	44.57	OK	10980	2026-09-18 01:34	44.80	OK
10981	2026-09-18 01:35	45.79	OK	10982	2026-09-18 01:36	44.74	OK
10983	2026-09-18 01:37	46.68	OK	10984	2026-09-18 01:38	44.47	OK
10985	2026-09-18 01:39	46.24	OK	10986	2026-09-18 01:40	46.44	OK
10987	2026-09-18 01:41	46.13	OK	10988	2026-09-18 01:42	46.70	OK
10989	2026-09-18 01:43	44.43	OK	10990	2026-09-18 01:44	43.33	OK
10991	2026-09-18 01:45	45.27	OK	10992	2026-09-18 01:46	45.27	OK
10993	2026-09-18 01:47	44.45	OK	10994	2026-09-18 01:48	45.03	OK
10995	2026-09-18 01:49	45.43	OK	10996	2026-09-18 01:50	45.48	OK
10997	2026-09-18 01:51	46.67	OK	10998	2026-09-18 01:52	43.80	OK
10999	2026-09-18 01:53	43.51	OK	11000	2026-09-18 01:54	46.15	OK
11001	2026-09-18 01:55	45.38	OK	11002	2026-09-18 01:56	45.02	OK
11003	2026-09-18 01:57	45.44	OK	11004	2026-09-18 01:58	44.61	OK
11005	2026-09-18 01:59	43.73	OK	11006	2026-09-18 02:00	44.96	OK
11007	2026-09-18 02:01	47.32	OK	11008	2026-09-18 02:02	45.85	OK
11009	2026-09-18 02:03	46.76	OK	11010	2026-09-18 02:04	45.68	OK
11011	2026-09-18 02:05	45.51	OK	11012	2026-09-18 02:06	45.50	OK
11013	2026-09-18 02:07	45.44	OK	11014	2026-09-18 02:08	44.79	OK
1101	2026-09-18 02:09	44.62	OK	1101	2026-09-18 02:10	45.15	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
11017	2026-09-18 02:11	45.83	OK	11018	2026-09-18 02:12	46.01	OK
11019	2026-09-18 02:13	44.19	OK	11020	2026-09-18 02:14	46.39	OK
11021	2026-09-18 02:15	44.23	OK	11022	2026-09-18 02:16	45.75	OK
11023	2026-09-18 02:17	45.46	OK	11024	2026-09-18 02:18	47.33	OK
11025	2026-09-18 02:19	45.80	OK	11026	2026-09-18 02:20	45.86	OK
11027	2026-09-18 02:21	45.68	OK	11028	2026-09-18 02:22	43.06	OK
11029	2026-09-18 02:23	47.52	OK	11030	2026-09-18 02:24	45.29	OK
11031	2026-09-18 02:25	44.04	OK	11032	2026-09-18 02:26	44.04	OK
11033	2026-09-18 02:27	45.09	OK	11034	2026-09-18 02:28	44.73	OK
11035	2026-09-18 02:29	45.66	OK	11036	2026-09-18 02:30	42.54	OK
11037	2026-09-18 02:31	45.60	OK	11038	2026-09-18 02:32	45.90	OK
11039	2026-09-18 02:33	45.14	OK	11040	2026-09-18 02:34	47.13	OK
11041	2026-09-18 02:35	45.35	OK	11042	2026-09-18 02:36	45.61	OK
11043	2026-09-18 02:37	45.15	OK	11044	2026-09-18 02:38	45.13	OK
11045	2026-09-18 02:39	43.91	OK	11046	2026-09-18 02:40	44.43	OK
11047	2026-09-18 02:41	44.78	OK	11048	2026-09-18 02:42	44.04	OK
11049	2026-09-18 02:43	46.12	OK	11050	2026-09-18 02:44	46.90	OK
11051	2026-09-18 02:45	47.80	OK	11052	2026-09-18 02:46	45.11	OK
11053	2026-09-18 02:47	46.61	OK	11054	2026-09-18 02:48	47.03	OK
11055	2026-09-18 02:49	43.81	OK	11056	2026-09-18 02:50	45.38	OK
11057	2026-09-18 02:51	44.11	OK	11058	2026-09-18 02:52	44.42	OK
11059	2026-09-18 02:53	46.09	OK	11060	2026-09-18 02:54	46.55	OK
11061	2026-09-18 02:55	45.41	OK	11062	2026-09-18 02:56	46.29	OK
11063	2026-09-18 02:57	44.21	OK	11064	2026-09-18 02:58	45.42	OK
11065	2026-09-18 02:59	46.63	OK	11066	2026-09-18 03:00	46.51	OK
11067	2026-09-18 03:01	43.56	OK	11068	2026-09-18 03:02	44.75	OK
11069	2026-09-18 03:03	44.98	OK	11070	2026-09-18 03:04	45.67	OK
11071	2026-09-18 03:05	45.13	OK	11072	2026-09-18 03:06	45.88	OK
11073	2026-09-18 03:07	44.46	OK	11074	2026-09-18 03:08	46.63	OK
1107	2026-09-18 03:09	47.45	OK	1107	2026-09-18 03:10	44.62	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
11077	2026-09-18 03:11	44.75	OK	11078	2026-09-18 03:12	44.30	OK
11079	2026-09-18 03:13	47.09	OK	11080	2026-09-18 03:14	46.56	OK
11081	2026-09-18 03:15	45.35	OK	11082	2026-09-18 03:16	45.00	OK
11083	2026-09-18 03:17	45.15	OK	11084	2026-09-18 03:18	46.16	OK
11085	2026-09-18 03:19	44.76	OK	11086	2026-09-18 03:20	46.13	OK
11087	2026-09-18 03:21	45.47	OK	11088	2026-09-18 03:22	47.50	OK
11089	2026-09-18 03:23	47.93	OK	11090	2026-09-18 03:24	46.18	OK
11091	2026-09-18 03:25	46.85	OK	11092	2026-09-18 03:26	44.98	OK
11093	2026-09-18 03:27	46.76	OK	11094	2026-09-18 03:28	44.17	OK
11095	2026-09-18 03:29	44.77	OK	11096	2026-09-18 03:30	45.94	OK
11097	2026-09-18 03:31	44.41	OK	11098	2026-09-18 03:32	46.28	OK
11099	2026-09-18 03:33	44.87	OK	11100	2026-09-18 03:34	45.58	OK
11101	2026-09-18 03:35	46.35	OK	11102	2026-09-18 03:36	45.61	OK
11103	2026-09-18 03:37	45.93	OK	11104	2026-09-18 03:38	44.73	OK
11105	2026-09-18 03:39	45.77	OK	11106	2026-09-18 03:40	46.06	OK
11107	2026-09-18 03:41	44.38	OK	11108	2026-09-18 03:42	45.89	OK
11109	2026-09-18 03:43	47.07	OK	11110	2026-09-18 03:44	47.48	OK
11111	2026-09-18 03:45	45.34	OK	11112	2026-09-18 03:46	46.32	OK
11113	2026-09-18 03:47	45.44	OK	11114	2026-09-18 03:48	45.00	OK
11115	2026-09-18 03:49	46.02	OK	11116	2026-09-18 03:50	45.71	OK
11117	2026-09-18 03:51	45.15	OK	11118	2026-09-18 03:52	46.23	OK
11119	2026-09-18 03:53	45.84	OK	11120	2026-09-18 03:54	45.86	OK
11121	2026-09-18 03:55	46.10	OK	11122	2026-09-18 03:56	46.00	OK
11123	2026-09-18 03:57	46.67	OK	11124	2026-09-18 03:58	44.87	OK
11125	2026-09-18 03:59	45.46	OK	11126	2026-09-18 04:00	45.63	OK
11127	2026-09-18 04:01	44.47	OK	11128	2026-09-18 04:02	46.76	OK
11129	2026-09-18 04:03	47.43	OK	11130	2026-09-18 04:04	47.18	OK
11131	2026-09-18 04:05	44.86	OK	11132	2026-09-18 04:06	47.63	OK
11133	2026-09-18 04:07	47.30	OK	11134	2026-09-18 04:08	46.54	OK
1113	2026-09-18 04:09	47.77	OK	1113	2026-09-18 04:10	46.61	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
11137	2026-09-18 04:11	48.17	OK	11138	2026-09-18 04:12	46.58	OK
11139	2026-09-18 04:13	47.79	OK	11140	2026-09-18 04:14	45.49	OK
11141	2026-09-18 04:15	46.95	OK	11142	2026-09-18 04:16	45.00	OK
11143	2026-09-18 04:17	44.77	OK	11144	2026-09-18 04:18	44.92	OK
11145	2026-09-18 04:19	46.66	OK	11146	2026-09-18 04:20	45.29	OK
11147	2026-09-18 04:21	46.17	OK	11148	2026-09-18 04:22	46.57	OK
11149	2026-09-18 04:23	46.97	OK	11150	2026-09-18 04:24	45.51	OK
11151	2026-09-18 04:25	47.15	OK	11152	2026-09-18 04:26	45.96	OK
11153	2026-09-18 04:27	46.51	OK	11154	2026-09-18 04:28	46.60	OK
11155	2026-09-18 04:29	44.99	OK	11156	2026-09-18 04:30	46.93	OK
11157	2026-09-18 04:31	45.77	OK	11158	2026-09-18 04:32	45.73	OK
11159	2026-09-18 04:33	45.45	OK	11160	2026-09-18 04:34	45.01	OK
11161	2026-09-18 04:35	47.28	OK	11162	2026-09-18 04:36	44.87	OK
11163	2026-09-18 04:37	45.87	OK	11164	2026-09-18 04:38	45.91	OK
11165	2026-09-18 04:39	46.38	OK	11166	2026-09-18 04:40	44.37	OK
11167	2026-09-18 04:41	46.72	OK	11168	2026-09-18 04:42	44.86	OK
11169	2026-09-18 04:43	46.89	OK	11170	2026-09-18 04:44	47.07	OK
11171	2026-09-18 04:45	46.85	OK	11172	2026-09-18 04:46	47.87	OK
11173	2026-09-18 04:47	45.44	OK	11174	2026-09-18 04:48	46.55	OK
11175	2026-09-18 04:49	46.05	OK	11176	2026-09-18 04:50	46.34	OK
11177	2026-09-18 04:51	46.91	OK	11178	2026-09-18 04:52	47.39	OK
11179	2026-09-18 04:53	45.51	OK	11180	2026-09-18 04:54	46.75	OK
11181	2026-09-18 04:55	46.28	OK	11182	2026-09-18 04:56	48.16	OK
11183	2026-09-18 04:57	47.80	OK	11184	2026-09-18 04:58	45.72	OK
11185	2026-09-18 04:59	48.14	OK	11186	2026-09-18 05:00	45.98	OK
11187	2026-09-18 05:01	47.43	OK	11188	2026-09-18 05:02	47.43	OK
11189	2026-09-18 05:03	46.00	OK	11190	2026-09-18 05:04	48.59	OK
11191	2026-09-18 05:05	47.13	OK	11192	2026-09-18 05:06	46.68	OK
11193	2026-09-18 05:07	46.40	OK	11194	2026-09-18 05:08	47.44	OK
1119	2026-09-18 05:09	47.99	OK	1119	2026-09-18 05:10	47.97	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
11197	2026-09-18 05:11	47.78	OK	11198	2026-09-18 05:12	48.84	OK
11199	2026-09-18 05:13	46.35	OK	11200	2026-09-18 05:14	47.12	OK
11201	2026-09-18 05:15	46.93	OK	11202	2026-09-18 05:16	47.19	OK
11203	2026-09-18 05:17	45.30	OK	11204	2026-09-18 05:18	48.11	OK
11205	2026-09-18 05:19	47.36	OK	11206	2026-09-18 05:20	48.39	OK
11207	2026-09-18 05:21	47.80	OK	11208	2026-09-18 05:22	46.47	OK
11209	2026-09-18 05:23	47.39	OK	11210	2026-09-18 05:24	46.54	OK
11211	2026-09-18 05:25	46.63	OK	11212	2026-09-18 05:26	47.43	OK
11213	2026-09-18 05:27	49.19	OK	11214	2026-09-18 05:28	46.40	OK
11215	2026-09-18 05:29	45.90	OK	11216	2026-09-18 05:30	44.70	OK
11217	2026-09-18 05:31	47.29	OK	11218	2026-09-18 05:32	47.16	OK
11219	2026-09-18 05:33	46.97	OK	11220	2026-09-18 05:34	47.43	OK
11221	2026-09-18 05:35	47.29	OK	11222	2026-09-18 05:36	47.72	OK
11223	2026-09-18 05:37	45.88	OK	11224	2026-09-18 05:38	46.32	OK
11225	2026-09-18 05:39	45.57	OK	11226	2026-09-18 05:40	46.59	OK
11227	2026-09-18 05:41	47.51	OK	11228	2026-09-18 05:42	45.78	OK
11229	2026-09-18 05:43	46.06	OK	11230	2026-09-18 05:44	46.55	OK
11231	2026-09-18 05:45	48.62	OK	11232	2026-09-18 05:46	47.28	OK
11233	2026-09-18 05:47	47.57	OK	11234	2026-09-18 05:48	47.11	OK
11235	2026-09-18 05:49	48.49	OK	11236	2026-09-18 05:50	47.95	OK
11237	2026-09-18 05:51	45.26	OK	11238	2026-09-18 05:52	46.85	OK
11239	2026-09-18 05:53	48.13	OK	11240	2026-09-18 05:54	47.19	OK
11241	2026-09-18 05:55	48.90	OK	11242	2026-09-18 05:56	49.24	OK
11243	2026-09-18 05:57	48.75	OK	11244	2026-09-18 05:58	47.21	OK
11245	2026-09-18 05:59	45.68	OK	11246	2026-09-18 06:00	46.64	OK
11247	2026-09-18 06:01	46.94	OK	11248	2026-09-18 06:02	46.63	OK
11249	2026-09-18 06:03	46.44	OK	11250	2026-09-18 06:04	47.54	OK
11251	2026-09-18 06:05	47.72	OK	11252	2026-09-18 06:06	45.90	OK
11253	2026-09-18 06:07	47.54	OK	11254	2026-09-18 06:08	48.01	OK
1125	2026-09-18 06:09	46.86	OK	1125	2026-09-18 06:10	47.70	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
11257	2026-09-18 06:11	46.50	OK	11258	2026-09-18 06:12	47.72	OK
11259	2026-09-18 06:13	49.46	OK	11260	2026-09-18 06:14	46.94	OK
11261	2026-09-18 06:15	47.22	OK	11262	2026-09-18 06:16	45.76	OK
11263	2026-09-18 06:17	49.17	OK	11264	2026-09-18 06:18	47.52	OK
11265	2026-09-18 06:19	48.02	OK	11266	2026-09-18 06:20	46.80	OK
11267	2026-09-18 06:21	47.32	OK	11268	2026-09-18 06:22	46.79	OK
11269	2026-09-18 06:23	47.16	OK	11270	2026-09-18 06:24	48.12	OK
11271	2026-09-18 06:25	48.69	OK	11272	2026-09-18 06:26	47.21	OK
11273	2026-09-18 06:27	45.79	OK	11274	2026-09-18 06:28	46.43	OK
11275	2026-09-18 06:29	47.93	OK	11276	2026-09-18 06:30	48.28	OK
11277	2026-09-18 06:31	46.01	OK	11278	2026-09-18 06:32	47.85	OK
11279	2026-09-18 06:33	49.00	OK	11280	2026-09-18 06:34	46.13	OK
11281	2026-09-18 06:35	48.14	OK	11282	2026-09-18 06:36	47.87	OK
11283	2026-09-18 06:37	47.79	OK	11284	2026-09-18 06:38	46.09	OK
11285	2026-09-18 06:39	47.65	OK	11286	2026-09-18 06:40	47.97	OK
11287	2026-09-18 06:41	48.43	OK	11288	2026-09-18 06:42	47.73	OK
11289	2026-09-18 06:43	49.70	OK	11290	2026-09-18 06:44	48.23	OK
11291	2026-09-18 06:45	49.13	OK	11292	2026-09-18 06:46	49.98	OK
11293	2026-09-18 06:47	48.34	OK	11294	2026-09-18 06:48	46.84	OK
11295	2026-09-18 06:49	47.70	OK	11296	2026-09-18 06:50	48.92	OK
11297	2026-09-18 06:51	48.61	OK	11298	2026-09-18 06:52	48.29	OK
11299	2026-09-18 06:53	47.78	OK	11300	2026-09-18 06:54	48.39	OK
11301	2026-09-18 06:55	47.27	OK	11302	2026-09-18 06:56	49.15	OK
11303	2026-09-18 06:57	48.66	OK	11304	2026-09-18 06:58	47.52	OK
11305	2026-09-18 06:59	47.41	OK	11306	2026-09-18 07:00	48.31	OK
11307	2026-09-18 07:01	48.88	OK	11308	2026-09-18 07:02	48.06	OK
11309	2026-09-18 07:03	46.93	OK	11310	2026-09-18 07:04	49.70	OK
11311	2026-09-18 07:05	49.52	OK	11312	2026-09-18 07:06	47.59	OK
11313	2026-09-18 07:07	50.36	OK	11314	2026-09-18 07:08	49.99	OK
1131	2026-09-18 07:09	48.12	OK	1131	2026-09-18 07:10	46.83	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
11317	2026-09-18 07:11	46.32	OK	11318	2026-09-18 07:12	50.10	OK
11319	2026-09-18 07:13	49.94	OK	11320	2026-09-18 07:14	50.54	OK
11321	2026-09-18 07:15	47.10	OK	11322	2026-09-18 07:16	47.94	OK
11323	2026-09-18 07:17	48.81	OK	11324	2026-09-18 07:18	48.49	OK
11325	2026-09-18 07:19	47.71	OK	11326	2026-09-18 07:20	49.34	OK
11327	2026-09-18 07:21	48.10	OK	11328	2026-09-18 07:22	48.10	OK
11329	2026-09-18 07:23	46.65	OK	11330	2026-09-18 07:24	47.06	OK
11331	2026-09-18 07:25	49.45	OK	11332	2026-09-18 07:26	48.99	OK
11333	2026-09-18 07:27	48.89	OK	11334	2026-09-18 07:28	49.68	OK
11335	2026-09-18 07:29	49.01	OK	11336	2026-09-18 07:30	48.01	OK
11337	2026-09-18 07:31	49.58	OK	11338	2026-09-18 07:32	49.75	OK
11339	2026-09-18 07:33	49.43	OK	11340	2026-09-18 07:34	48.21	OK
11341	2026-09-18 07:35	47.15	OK	11342	2026-09-18 07:36	49.20	OK
11343	2026-09-18 07:37	49.40	OK	11344	2026-09-18 07:38	47.13	OK
11345	2026-09-18 07:39	48.31	OK	11346	2026-09-18 07:40	48.39	OK
11347	2026-09-18 07:41	48.70	OK	11348	2026-09-18 07:42	48.73	OK
11349	2026-09-18 07:43	50.14	OK	11350	2026-09-18 07:44	49.17	OK
11351	2026-09-18 07:45	48.87	OK	11352	2026-09-18 07:46	49.63	OK
11353	2026-09-18 07:47	48.66	OK	11354	2026-09-18 07:48	48.91	OK
11355	2026-09-18 07:49	48.52	OK	11356	2026-09-18 07:50	48.64	OK
11357	2026-09-18 07:51	49.81	OK	11358	2026-09-18 07:52	47.60	OK
11359	2026-09-18 07:53	49.56	OK	11360	2026-09-18 07:54	48.60	OK
11361	2026-09-18 07:55	48.41	OK	11362	2026-09-18 07:56	49.81	OK
11363	2026-09-18 07:57	50.52	OK	11364	2026-09-18 07:58	49.17	OK
11365	2026-09-18 07:59	47.85	OK	11366	2026-09-18 08:00	49.00	OK
11367	2026-09-18 08:01	49.52	OK	11368	2026-09-18 08:02	48.84	OK
11369	2026-09-18 08:03	48.94	OK	11370	2026-09-18 08:04	49.84	OK
11371	2026-09-18 08:05	49.39	OK	11372	2026-09-18 08:06	48.30	OK
11373	2026-09-18 08:07	48.66	OK	11374	2026-09-18 08:08	49.44	OK
1137	2026-09-18 08:09	48.40	OK	1137	2026-09-18 08:10	49.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
11377	2026-09-18 08:11	49.94	OK	11378	2026-09-18 08:12	51.07	OK
11379	2026-09-18 08:13	49.86	OK	11380	2026-09-18 08:14	47.88	OK
11381	2026-09-18 08:15	48.35	OK	11382	2026-09-18 08:16	46.65	OK
11383	2026-09-18 08:17	49.76	OK	11384	2026-09-18 08:18	49.14	OK
11385	2026-09-18 08:19	49.12	OK	11386	2026-09-18 08:20	48.36	OK
11387	2026-09-18 08:21	50.73	OK	11388	2026-09-18 08:22	49.14	OK
11389	2026-09-18 08:23	49.24	OK	11390	2026-09-18 08:24	47.48	OK
11391	2026-09-18 08:25	51.08	OK	11392	2026-09-18 08:26	50.59	OK
11393	2026-09-18 08:27	50.13	OK	11394	2026-09-18 08:28	49.75	OK
11395	2026-09-18 08:29	48.34	OK	11396	2026-09-18 08:30	50.66	OK
11397	2026-09-18 08:31	47.24	OK	11398	2026-09-18 08:32	51.88	OK
11399	2026-09-18 08:33	50.05	OK	11400	2026-09-18 08:34	50.85	OK
11401	2026-09-18 08:35	49.98	OK	11402	2026-09-18 08:36	48.74	OK
11403	2026-09-18 08:37	47.64	OK	11404	2026-09-18 08:38	49.84	OK
11405	2026-09-18 08:39	51.53	OK	11406	2026-09-18 08:40	48.84	OK
11407	2026-09-18 08:41	49.94	OK	11408	2026-09-18 08:42	48.30	OK
11409	2026-09-18 08:43	50.89	OK	11410	2026-09-18 08:44	47.66	OK
11411	2026-09-18 08:45	49.39	OK	11412	2026-09-18 08:46	52.24	OK
11413	2026-09-18 08:47	50.14	OK	11414	2026-09-18 08:48	48.50	OK
11415	2026-09-18 08:49	48.52	OK	11416	2026-09-18 08:50	50.02	OK
11417	2026-09-18 08:51	49.83	OK	11418	2026-09-18 08:52	48.74	OK
11419	2026-09-18 08:53	48.96	OK	11420	2026-09-18 08:54	50.65	OK
11421	2026-09-18 08:55	48.12	OK	11422	2026-09-18 08:56	50.40	OK
11423	2026-09-18 08:57	48.71	OK	11424	2026-09-18 08:58	47.89	OK
11425	2026-09-18 08:59	48.95	OK	11426	2026-09-18 09:00	49.53	OK
11427	2026-09-18 09:01	51.35	OK	11428	2026-09-18 09:02	50.20	OK
11429	2026-09-18 09:03	49.70	OK	11430	2026-09-18 09:04	50.96	OK
11431	2026-09-18 09:05	49.92	OK	11432	2026-09-18 09:06	51.53	OK
11433	2026-09-18 09:07	49.06	OK	11434	2026-09-18 09:08	49.66	OK
1143	2026-09-18 09:09	51.02	OK	1143	2026-09-18 09:10	51.46	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
11437	2026-09-18 09:11	49.43	OK	11438	2026-09-18 09:12	48.87	OK
11439	2026-09-18 09:13	50.62	OK	11440	2026-09-18 09:14	48.71	OK
11441	2026-09-18 09:15	50.69	OK	11442	2026-09-18 09:16	51.10	OK
11443	2026-09-18 09:17	48.68	OK	11444	2026-09-18 09:18	49.65	OK
11445	2026-09-18 09:19	52.17	OK	11446	2026-09-18 09:20	48.77	OK
11447	2026-09-18 09:21	51.46	OK	11448	2026-09-18 09:22	50.81	OK
11449	2026-09-18 09:23	51.65	OK	11450	2026-09-18 09:24	50.75	OK
11451	2026-09-18 09:25	51.45	OK	11452	2026-09-18 09:26	51.33	OK
11453	2026-09-18 09:27	49.19	OK	11454	2026-09-18 09:28	50.53	OK
11455	2026-09-18 09:29	49.74	OK	11456	2026-09-18 09:30	48.79	OK
11457	2026-09-18 09:31	50.18	OK	11458	2026-09-18 09:32	49.60	OK
11459	2026-09-18 09:33	50.71	OK	11460	2026-09-18 09:34	49.46	OK
11461	2026-09-18 09:35	49.60	OK	11462	2026-09-18 09:36	49.47	OK
11463	2026-09-18 09:37	50.43	OK	11464	2026-09-18 09:38	50.58	OK
11465	2026-09-18 09:39	49.74	OK	11466	2026-09-18 09:40	50.69	OK
11467	2026-09-18 09:41	48.27	OK	11468	2026-09-18 09:42	49.22	OK
11469	2026-09-18 09:43	51.08	OK	11470	2026-09-18 09:44	50.79	OK
11471	2026-09-18 09:45	51.81	OK	11472	2026-09-18 09:46	50.14	OK
11473	2026-09-18 09:47	50.51	OK	11474	2026-09-18 09:48	51.02	OK
11475	2026-09-18 09:49	48.38	OK	11476	2026-09-18 09:50	51.21	OK
11477	2026-09-18 09:51	49.74	OK	11478	2026-09-18 09:52	50.06	OK
11479	2026-09-18 09:53	51.15	OK	11480	2026-09-18 09:54	48.50	OK
11481	2026-09-18 09:55	51.53	OK	11482	2026-09-18 09:56	49.73	OK
11483	2026-09-18 09:57	51.10	OK	11484	2026-09-18 09:58	50.02	OK
11485	2026-09-18 09:59	50.44	OK	11486	2026-09-18 10:00	49.69	OK
11487	2026-09-18 10:01	52.35	OK	11488	2026-09-18 10:02	49.34	OK
11489	2026-09-18 10:03	51.63	OK	11490	2026-09-18 10:04	50.88	OK
11491	2026-09-18 10:05	50.22	OK	11492	2026-09-18 10:06	49.65	OK
11493	2026-09-18 10:07	51.11	OK	11494	2026-09-18 10:08	50.61	OK
1149	2026-09-18 10:09	49.64	OK	1149	2026-09-18 10:10	51.16	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
11497	2026-09-18 10:11	52.02	OK	11498	2026-09-18 10:12	49.79	OK
11499	2026-09-18 10:13	50.55	OK	11500	2026-09-18 10:14	52.63	OK
11501	2026-09-18 10:15	50.61	OK	11502	2026-09-18 10:16	50.82	OK
11503	2026-09-18 10:17	50.85	OK	11504	2026-09-18 10:18	49.48	OK
11505	2026-09-18 10:19	51.67	OK	11506	2026-09-18 10:20	51.26	OK
11507	2026-09-18 10:21	51.02	OK	11508	2026-09-18 10:22	50.76	OK
11509	2026-09-18 10:23	50.89	OK	11510	2026-09-18 10:24	52.01	OK
11511	2026-09-18 10:25	49.57	OK	11512	2026-09-18 10:26	52.04	OK
11513	2026-09-18 10:27	49.15	OK	11514	2026-09-18 10:28	50.60	OK
11515	2026-09-18 10:29	49.11	OK	11516	2026-09-18 10:30	51.23	OK
11517	2026-09-18 10:31	50.94	OK	11518	2026-09-18 10:32	50.34	OK
11519	2026-09-18 10:33	51.27	OK	11520	2026-09-18 10:34	49.22	OK
11521	2026-09-18 10:35	50.21	OK	11522	2026-09-18 10:36	50.45	OK
11523	2026-09-18 10:37	50.06	OK	11524	2026-09-18 10:38	50.55	OK
11525	2026-09-18 10:39	50.49	OK	11526	2026-09-18 10:40	51.72	OK
11527	2026-09-18 10:41	50.09	OK	11528	2026-09-18 10:42	50.01	OK
11529	2026-09-18 10:43	50.86	OK	11530	2026-09-18 10:44	52.18	OK
11531	2026-09-18 10:45	52.13	OK	11532	2026-09-18 10:46	52.52	OK
11533	2026-09-18 10:47	51.40	OK	11534	2026-09-18 10:48	49.35	OK
11535	2026-09-18 10:49	52.64	OK	11536	2026-09-18 10:50	50.58	OK
11537	2026-09-18 10:51	49.90	OK	11538	2026-09-18 10:52	50.10	OK
11539	2026-09-18 10:53	50.99	OK	11540	2026-09-18 10:54	50.12	OK
11541	2026-09-18 10:55	49.86	OK	11542	2026-09-18 10:56	49.57	OK
11543	2026-09-18 10:57	51.30	OK	11544	2026-09-18 10:58	50.87	OK
11545	2026-09-18 10:59	53.47	OK	11546	2026-09-18 11:00	51.94	OK
11547	2026-09-18 11:01	51.71	OK	11548	2026-09-18 11:02	51.88	OK
11549	2026-09-18 11:03	50.71	OK	11550	2026-09-18 11:04	52.03	OK
11551	2026-09-18 11:05	50.63	OK	11552	2026-09-18 11:06	50.65	OK
11553	2026-09-18 11:07	50.79	OK	11554	2026-09-18 11:08	52.85	OK
1155	2026-09-18 11:09	51.54	OK	1155	2026-09-18 11:10	50.55	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
11557	2026-09-18 11:11	51.56	OK	11558	2026-09-18 11:12	51.07	OK
11559	2026-09-18 11:13	52.67	OK	11560	2026-09-18 11:14	50.07	OK
11561	2026-09-18 11:15	51.43	OK	11562	2026-09-18 11:16	52.06	OK
11563	2026-09-18 11:17	51.93	OK	11564	2026-09-18 11:18	52.17	OK
11565	2026-09-18 11:19	51.83	OK	11566	2026-09-18 11:20	52.85	OK
11567	2026-09-18 11:21	51.56	OK	11568	2026-09-18 11:22	52.79	OK
11569	2026-09-18 11:23	52.21	OK	11570	2026-09-18 11:24	50.71	OK
11571	2026-09-18 11:25	51.23	OK	11572	2026-09-18 11:26	53.21	OK
11573	2026-09-18 11:27	53.84	OK	11574	2026-09-18 11:28	52.63	OK
11575	2026-09-18 11:29	50.59	OK	11576	2026-09-18 11:30	53.02	OK
11577	2026-09-18 11:31	51.06	OK	11578	2026-09-18 11:32	51.15	OK
11579	2026-09-18 11:33	51.05	OK	11580	2026-09-18 11:34	53.26	OK
11581	2026-09-18 11:35	50.93	OK	11582	2026-09-18 11:36	49.67	OK
11583	2026-09-18 11:37	51.38	OK	11584	2026-09-18 11:38	50.86	OK
11585	2026-09-18 11:39	50.62	OK	11586	2026-09-18 11:40	52.90	OK
11587	2026-09-18 11:41	51.87	OK	11588	2026-09-18 11:42	50.25	OK
11589	2026-09-18 11:43	50.76	OK	11590	2026-09-18 11:44	51.62	OK
11591	2026-09-18 11:45	53.26	OK	11592	2026-09-18 11:46	53.73	OK
11593	2026-09-18 11:47	52.34	OK	11594	2026-09-18 11:48	50.73	OK
11595	2026-09-18 11:49	51.65	OK	11596	2026-09-18 11:50	52.08	OK
11597	2026-09-18 11:51	52.23	OK	11598	2026-09-18 11:52	51.92	OK
11599	2026-09-18 11:53	53.02	OK	11600	2026-09-18 11:54	52.18	OK
11601	2026-09-18 11:55	51.51	OK	11602	2026-09-18 11:56	52.90	OK
11603	2026-09-18 11:57	53.89	OK	11604	2026-09-18 11:58	50.51	OK
11605	2026-09-18 11:59	50.92	OK	11606	2026-09-18 12:00	49.19	OK
11607	2026-09-18 12:01	52.86	OK	11608	2026-09-18 12:02	52.91	OK
11609	2026-09-18 12:03	53.00	OK	11610	2026-09-18 12:04	52.76	OK
11611	2026-09-18 12:05	51.17	OK	11612	2026-09-18 12:06	49.64	OK
11613	2026-09-18 12:07	52.48	OK	11614	2026-09-18 12:08	49.67	OK
1161	2026-09-18 12:09	52.83	OK	1161	2026-09-18 12:10	50.60	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
11617	2026-09-18 12:11	52.89	OK	11618	2026-09-18 12:12	51.57	OK
11619	2026-09-18 12:13	52.40	OK	11620	2026-09-18 12:14	51.76	OK
11621	2026-09-18 12:15	51.05	OK	11622	2026-09-18 12:16	50.72	OK
11623	2026-09-18 12:17	50.71	OK	11624	2026-09-18 12:18	52.46	OK
11625	2026-09-18 12:19	51.11	OK	11626	2026-09-18 12:20	52.56	OK
11627	2026-09-18 12:21	51.89	OK	11628	2026-09-18 12:22	54.21	OK
11629	2026-09-18 12:23	50.91	OK	11630	2026-09-18 12:24	50.02	OK
11631	2026-09-18 12:25	50.20	OK	11632	2026-09-18 12:26	51.55	OK
11633	2026-09-18 12:27	52.09	OK	11634	2026-09-18 12:28	51.04	OK
11635	2026-09-18 12:29	52.11	OK	11636	2026-09-18 12:30	51.38	OK
11637	2026-09-18 12:31	49.96	OK	11638	2026-09-18 12:32	50.74	OK
11639	2026-09-18 12:33	50.12	OK	11640	2026-09-18 12:34	50.47	OK
11641	2026-09-18 12:35	50.57	OK	11642	2026-09-18 12:36	51.27	OK
11643	2026-09-18 12:37	50.47	OK	11644	2026-09-18 12:38	53.20	OK
11645	2026-09-18 12:39	51.47	OK	11646	2026-09-18 12:40	53.03	OK
11647	2026-09-18 12:41	52.71	OK	11648	2026-09-18 12:42	52.57	OK
11649	2026-09-18 12:43	52.11	OK	11650	2026-09-18 12:44	51.67	OK
11651	2026-09-18 12:45	51.11	OK	11652	2026-09-18 12:46	52.64	OK
11653	2026-09-18 12:47	53.12	OK	11654	2026-09-18 12:48	52.07	OK
11655	2026-09-18 12:49	51.45	OK	11656	2026-09-18 12:50	52.35	OK
11657	2026-09-18 12:51	49.95	OK	11658	2026-09-18 12:52	52.54	OK
11659	2026-09-18 12:53	52.89	OK	11660	2026-09-18 12:54	51.28	OK
11661	2026-09-18 12:55	51.30	OK	11662	2026-09-18 12:56	52.88	OK
11663	2026-09-18 12:57	52.15	OK	11664	2026-09-18 12:58	51.22	OK
11665	2026-09-18 12:59	52.66	OK	11666	2026-09-18 13:00	50.28	OK
11667	2026-09-18 13:01	53.11	OK	11668	2026-09-18 13:02	52.21	OK
11669	2026-09-18 13:03	50.87	OK	11670	2026-09-18 13:04	52.86	OK
11671	2026-09-18 13:05	54.00	OK	11672	2026-09-18 13:06	53.20	OK
11673	2026-09-18 13:07	53.22	OK	11674	2026-09-18 13:08	50.78	OK
1167	2026-09-18 13:09	51.59	OK	1167	2026-09-18 13:10	52.50	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
11677	2026-09-18 13:11	50.05	OK	11678	2026-09-18 13:12	51.09	OK
11679	2026-09-18 13:13	54.03	OK	11680	2026-09-18 13:14	50.15	OK
11681	2026-09-18 13:15	53.39	OK	11682	2026-09-18 13:16	51.52	OK
11683	2026-09-18 13:17	52.37	OK	11684	2026-09-18 13:18	49.36	OK
11685	2026-09-18 13:19	50.12	OK	11686	2026-09-18 13:20	52.24	OK
11687	2026-09-18 13:21	53.57	OK	11688	2026-09-18 13:22	51.82	OK
11689	2026-09-18 13:23	52.35	OK	11690	2026-09-18 13:24	52.16	OK
11691	2026-09-18 13:25	50.83	OK	11692	2026-09-18 13:26	50.87	OK
11693	2026-09-18 13:27	52.37	OK	11694	2026-09-18 13:28	50.72	OK
11695	2026-09-18 13:29	51.35	OK	11696	2026-09-18 13:30	49.60	OK
11697	2026-09-18 13:31	51.71	OK	11698	2026-09-18 13:32	52.21	OK
11699	2026-09-18 13:33	50.75	OK	11700	2026-09-18 13:34	50.63	OK
11701	2026-09-18 13:35	52.23	OK	11702	2026-09-18 13:36	52.19	OK
11703	2026-09-18 13:37	50.94	OK	11704	2026-09-18 13:38	53.24	OK
11705	2026-09-18 13:39	51.50	OK	11706	2026-09-18 13:40	50.02	OK
11707	2026-09-18 13:41	52.37	OK	11708	2026-09-18 13:42	51.28	OK
11709	2026-09-18 13:43	51.48	OK	11710	2026-09-18 13:44	51.00	OK
11711	2026-09-18 13:45	53.80	OK	11712	2026-09-18 13:46	50.96	OK
11713	2026-09-18 13:47	51.45	OK	11714	2026-09-18 13:48	51.15	OK
11715	2026-09-18 13:49	52.21	OK	11716	2026-09-18 13:50	49.30	OK
11717	2026-09-18 13:51	51.32	OK	11718	2026-09-18 13:52	51.89	OK
11719	2026-09-18 13:53	50.78	OK	11720	2026-09-18 13:54	50.60	OK
11721	2026-09-18 13:55	50.25	OK	11722	2026-09-18 13:56	52.71	OK
11723	2026-09-18 13:57	52.37	OK	11724	2026-09-18 13:58	51.37	OK
11725	2026-09-18 13:59	51.27	OK	11726	2026-09-18 14:00	52.99	OK
11727	2026-09-18 14:01	51.30	OK	11728	2026-09-18 14:02	51.30	OK
11729	2026-09-18 14:03	52.06	OK	11730	2026-09-18 14:04	50.94	OK
11731	2026-09-18 14:05	52.44	OK	11732	2026-09-18 14:06	52.63	OK
11733	2026-09-18 14:07	50.86	OK	11734	2026-09-18 14:08	51.19	OK
1173	2026-09-18 14:09	51.42	OK	1173	2026-09-18 14:10	52.61	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
11737	2026-09-18 14:11	51.02	OK	11738	2026-09-18 14:12	51.20	OK
11739	2026-09-18 14:13	53.25	OK	11740	2026-09-18 14:14	52.04	OK
11741	2026-09-18 14:15	51.91	OK	11742	2026-09-18 14:16	51.50	OK
11743	2026-09-18 14:17	51.47	OK	11744	2026-09-18 14:18	53.33	OK
11745	2026-09-18 14:19	51.86	OK	11746	2026-09-18 14:20	52.26	OK
11747	2026-09-18 14:21	52.61	OK	11748	2026-09-18 14:22	50.84	OK
11749	2026-09-18 14:23	50.51	OK	11750	2026-09-18 14:24	53.28	OK
11751	2026-09-18 14:25	51.54	OK	11752	2026-09-18 14:26	52.84	OK
11753	2026-09-18 14:27	53.47	OK	11754	2026-09-18 14:28	52.44	OK
11755	2026-09-18 14:29	51.23	OK	11756	2026-09-18 14:30	50.09	OK
11757	2026-09-18 14:31	51.23	OK	11758	2026-09-18 14:32	51.65	OK
11759	2026-09-18 14:33	51.47	OK	11760	2026-09-18 14:34	51.35	OK
11761	2026-09-18 14:35	51.08	OK	11762	2026-09-18 14:36	51.07	OK
11763	2026-09-18 14:37	52.00	OK	11764	2026-09-18 14:38	51.49	OK
11765	2026-09-18 14:39	53.69	OK	11766	2026-09-18 14:40	50.79	OK
11767	2026-09-18 14:41	51.88	OK	11768	2026-09-18 14:42	51.83	OK
11769	2026-09-18 14:43	51.67	OK	11770	2026-09-18 14:44	51.08	OK
11771	2026-09-18 14:45	51.51	OK	11772	2026-09-18 14:46	52.16	OK
11773	2026-09-18 14:47	50.39	OK	11774	2026-09-18 14:48	50.77	OK
11775	2026-09-18 14:49	51.22	OK	11776	2026-09-18 14:50	49.46	OK
11777	2026-09-18 14:51	51.44	OK	11778	2026-09-18 14:52	50.94	OK
11779	2026-09-18 14:53	50.70	OK	11780	2026-09-18 14:54	52.27	OK
11781	2026-09-18 14:55	52.68	OK	11782	2026-09-18 14:56	50.04	OK
11783	2026-09-18 14:57	52.16	OK	11784	2026-09-18 14:58	51.85	OK
11785	2026-09-18 14:59	52.86	OK	11786	2026-09-18 15:00	51.59	OK
11787	2026-09-18 15:01	52.65	OK	11788	2026-09-18 15:02	52.18	OK
11789	2026-09-18 15:03	50.74	OK	11790	2026-09-18 15:04	52.00	OK
11791	2026-09-18 15:05	50.46	OK	11792	2026-09-18 15:06	49.87	OK
11793	2026-09-18 15:07	53.82	OK	11794	2026-09-18 15:08	51.83	OK
1179	2026-09-18 15:09	52.12	OK	1179	2026-09-18 15:10	50.79	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
11797	2026-09-18 15:11	52.08	OK	11798	2026-09-18 15:12	51.99	OK
11799	2026-09-18 15:13	51.38	OK	11800	2026-09-18 15:14	51.45	OK
11801	2026-09-18 15:15	52.95	OK	11802	2026-09-18 15:16	52.13	OK
11803	2026-09-18 15:17	52.10	OK	11804	2026-09-18 15:18	51.28	OK
11805	2026-09-18 15:19	51.10	OK	11806	2026-09-18 15:20	50.70	OK
11807	2026-09-18 15:21	51.82	OK	11808	2026-09-18 15:22	53.89	OK
11809	2026-09-18 15:23	51.90	OK	11810	2026-09-18 15:24	53.45	OK
11811	2026-09-18 15:25	51.54	OK	11812	2026-09-18 15:26	50.50	OK
11813	2026-09-18 15:27	53.17	OK	11814	2026-09-18 15:28	51.41	OK
11815	2026-09-18 15:29	49.12	OK	11816	2026-09-18 15:30	49.24	OK
11817	2026-09-18 15:31	51.95	OK	11818	2026-09-18 15:32	50.81	OK
11819	2026-09-18 15:33	49.85	OK	11820	2026-09-18 15:34	52.62	OK
11821	2026-09-18 15:35	51.69	OK	11822	2026-09-18 15:36	49.62	OK
11823	2026-09-18 15:37	49.27	OK	11824	2026-09-18 15:38	49.41	OK
11825	2026-09-18 15:39	51.41	OK	11826	2026-09-18 15:40	50.69	OK
11827	2026-09-18 15:41	52.01	OK	11828	2026-09-18 15:42	52.47	OK
11829	2026-09-18 15:43	50.80	OK	11830	2026-09-18 15:44	52.38	OK
11831	2026-09-18 15:45	49.79	OK	11832	2026-09-18 15:46	51.34	OK
11833	2026-09-18 15:47	50.86	OK	11834	2026-09-18 15:48	51.86	OK
11835	2026-09-18 15:49	52.11	OK	11836	2026-09-18 15:50	49.49	OK
11837	2026-09-18 15:51	49.64	OK	11838	2026-09-18 15:52	51.22	OK
11839	2026-09-18 15:53	51.76	OK	11840	2026-09-18 15:54	49.84	OK
11841	2026-09-18 15:55	51.83	OK	11842	2026-09-18 15:56	50.54	OK
11843	2026-09-18 15:57	50.12	OK	11844	2026-09-18 15:58	50.72	OK
11845	2026-09-18 15:59	52.37	OK	11846	2026-09-18 16:00	50.73	OK
11847	2026-09-18 16:01	50.36	OK	11848	2026-09-18 16:02	49.58	OK
11849	2026-09-18 16:03	49.52	OK	11850	2026-09-18 16:04	50.28	OK
11851	2026-09-18 16:05	49.76	OK	11852	2026-09-18 16:06	52.17	OK
11853	2026-09-18 16:07	51.42	OK	11854	2026-09-18 16:08	50.18	OK
1185	2026-09-18 16:09	49.18	OK	1185	2026-09-18 16:10	51.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
11857	2026-09-18 16:11	50.36	OK	11858	2026-09-18 16:12	50.70	OK
11859	2026-09-18 16:13	51.37	OK	11860	2026-09-18 16:14	53.14	OK
11861	2026-09-18 16:15	51.06	OK	11862	2026-09-18 16:16	51.64	OK
11863	2026-09-18 16:17	50.81	OK	11864	2026-09-18 16:18	51.39	OK
11865	2026-09-18 16:19	53.11	OK	11866	2026-09-18 16:20	51.88	OK
11867	2026-09-18 16:21	49.16	OK	11868	2026-09-18 16:22	51.36	OK
11869	2026-09-18 16:23	50.94	OK	11870	2026-09-18 16:24	51.71	OK
11871	2026-09-18 16:25	49.97	OK	11872	2026-09-18 16:26	49.14	OK
11873	2026-09-18 16:27	50.77	OK	11874	2026-09-18 16:28	50.93	OK
11875	2026-09-18 16:29	49.62	OK	11876	2026-09-18 16:30	50.09	OK
11877	2026-09-18 16:31	52.37	OK	11878	2026-09-18 16:32	53.15	OK
11879	2026-09-18 16:33	50.38	OK	11880	2026-09-18 16:34	49.80	OK
11881	2026-09-18 16:35	50.90	OK	11882	2026-09-18 16:36	51.81	OK
11883	2026-09-18 16:37	50.44	OK	11884	2026-09-18 16:38	50.41	OK
11885	2026-09-18 16:39	52.03	OK	11886	2026-09-18 16:40	50.55	OK
11887	2026-09-18 16:41	50.58	OK	11888	2026-09-18 16:42	51.28	OK
11889	2026-09-18 16:43	51.41	OK	11890	2026-09-18 16:44	49.42	OK
11891	2026-09-18 16:45	51.63	OK	11892	2026-09-18 16:46	51.53	OK
11893	2026-09-18 16:47	48.85	OK	11894	2026-09-18 16:48	51.81	OK
11895	2026-09-18 16:49	50.09	OK	11896	2026-09-18 16:50	49.86	OK
11897	2026-09-18 16:51	49.60	OK	11898	2026-09-18 16:52	49.88	OK
11899	2026-09-18 16:53	51.23	OK	11900	2026-09-18 16:54	50.16	OK
11901	2026-09-18 16:55	51.36	OK	11902	2026-09-18 16:56	51.97	OK
11903	2026-09-18 16:57	49.16	OK	11904	2026-09-18 16:58	50.32	OK
11905	2026-09-18 16:59	49.50	OK	11906	2026-09-18 17:00	50.53	OK
11907	2026-09-18 17:01	50.03	OK	11908	2026-09-18 17:02	49.68	OK
11909	2026-09-18 17:03	50.99	OK	11910	2026-09-18 17:04	50.79	OK
11911	2026-09-18 17:05	51.40	OK	11912	2026-09-18 17:06	50.43	OK
11913	2026-09-18 17:07	49.85	OK	11914	2026-09-18 17:08	50.29	OK
1191	2026-09-18 17:09	50.76	OK	1191	2026-09-18 17:10	51.52	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
11917	2026-09-18 17:11	49.09	OK	11918	2026-09-18 17:12	50.54	OK
11919	2026-09-18 17:13	49.87	OK	11920	2026-09-18 17:14	50.31	OK
11921	2026-09-18 17:15	51.29	OK	11922	2026-09-18 17:16	50.54	OK
11923	2026-09-18 17:17	48.32	OK	11924	2026-09-18 17:18	50.77	OK
11925	2026-09-18 17:19	51.72	OK	11926	2026-09-18 17:20	49.44	OK
11927	2026-09-18 17:21	49.09	OK	11928	2026-09-18 17:22	49.65	OK
11929	2026-09-18 17:23	48.87	OK	11930	2026-09-18 17:24	49.27	OK
11931	2026-09-18 17:25	49.58	OK	11932	2026-09-18 17:26	48.63	OK
11933	2026-09-18 17:27	50.92	OK	11934	2026-09-18 17:28	50.15	OK
11935	2026-09-18 17:29	51.28	OK	11936	2026-09-18 17:30	50.64	OK
11937	2026-09-18 17:31	50.79	OK	11938	2026-09-18 17:32	48.82	OK
11939	2026-09-18 17:33	51.04	OK	11940	2026-09-18 17:34	48.48	OK
11941	2026-09-18 17:35	50.29	OK	11942	2026-09-18 17:36	50.51	OK
11943	2026-09-18 17:37	49.59	OK	11944	2026-09-18 17:38	49.80	OK
11945	2026-09-18 17:39	49.86	OK	11946	2026-09-18 17:40	50.77	OK
11947	2026-09-18 17:41	52.31	OK	11948	2026-09-18 17:42	48.74	OK
11949	2026-09-18 17:43	51.32	OK	11950	2026-09-18 17:44	50.82	OK
11951	2026-09-18 17:45	52.01	OK	11952	2026-09-18 17:46	47.95	OK
11953	2026-09-18 17:47	49.30	OK	11954	2026-09-18 17:48	50.59	OK
11955	2026-09-18 17:49	49.28	OK	11956	2026-09-18 17:50	48.77	OK
11957	2026-09-18 17:51	48.27	OK	11958	2026-09-18 17:52	48.10	OK
11959	2026-09-18 17:53	49.69	OK	11960	2026-09-18 17:54	50.20	OK
11961	2026-09-18 17:55	51.22	OK	11962	2026-09-18 17:56	48.31	OK
11963	2026-09-18 17:57	49.27	OK	11964	2026-09-18 17:58	50.62	OK
11965	2026-09-18 17:59	52.14	OK	11966	2026-09-18 18:00	49.20	OK
11967	2026-09-18 18:01	49.47	OK	11968	2026-09-18 18:02	50.65	OK
11969	2026-09-18 18:03	51.63	OK	11970	2026-09-18 18:04	48.91	OK
11971	2026-09-18 18:05	47.78	OK	11972	2026-09-18 18:06	50.22	OK
11973	2026-09-18 18:07	51.64	OK	11974	2026-09-18 18:08	50.41	OK
1197	2026-09-18 18:09	48.52	OK	1197	2026-09-18 18:10	50.49	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
11977	2026-09-18 18:11	51.36	OK	11978	2026-09-18 18:12	47.12	OK
11979	2026-09-18 18:13	50.06	OK	11980	2026-09-18 18:14	50.12	OK
11981	2026-09-18 18:15	50.84	OK	11982	2026-09-18 18:16	49.62	OK
11983	2026-09-18 18:17	50.34	OK	11984	2026-09-18 18:18	50.53	OK
11985	2026-09-18 18:19	50.25	OK	11986	2026-09-18 18:20	47.11	OK
11987	2026-09-18 18:21	49.80	OK	11988	2026-09-18 18:22	50.41	OK
11989	2026-09-18 18:23	50.19	OK	11990	2026-09-18 18:24	48.21	OK
11991	2026-09-18 18:25	48.83	OK	11992	2026-09-18 18:26	47.72	OK
11993	2026-09-18 18:27	47.62	OK	11994	2026-09-18 18:28	49.95	OK
11995	2026-09-18 18:29	51.39	OK	11996	2026-09-18 18:30	50.05	OK
11997	2026-09-18 18:31	51.64	OK	11998	2026-09-18 18:32	50.05	OK
11999	2026-09-18 18:33	47.47	OK	12000	2026-09-18 18:34	48.96	OK
12001	2026-09-18 18:35	48.92	OK	12002	2026-09-18 18:36	48.38	OK
12003	2026-09-18 18:37	50.90	OK	12004	2026-09-18 18:38	48.98	OK
12005	2026-09-18 18:39	50.09	OK	12006	2026-09-18 18:40	49.17	OK
12007	2026-09-18 18:41	49.61	OK	12008	2026-09-18 18:42	50.59	OK
12009	2026-09-18 18:43	51.23	OK	12010	2026-09-18 18:44	50.08	OK
12011	2026-09-18 18:45	50.39	OK	12012	2026-09-18 18:46	47.92	OK
12013	2026-09-18 18:47	49.44	OK	12014	2026-09-18 18:48	49.42	OK
12015	2026-09-18 18:49	49.96	OK	12016	2026-09-18 18:50	48.39	OK
12017	2026-09-18 18:51	50.33	OK	12018	2026-09-18 18:52	48.15	OK
12019	2026-09-18 18:53	49.61	OK	12020	2026-09-18 18:54	49.91	OK
12021	2026-09-18 18:55	48.23	OK	12022	2026-09-18 18:56	48.66	OK
12023	2026-09-18 18:57	49.32	OK	12024	2026-09-18 18:58	48.28	OK
12025	2026-09-18 18:59	47.49	OK	12026	2026-09-18 19:00	46.44	OK
12027	2026-09-18 19:01	48.68	OK	12028	2026-09-18 19:02	48.48	OK
12029	2026-09-18 19:03	48.46	OK	12030	2026-09-18 19:04	50.11	OK
12031	2026-09-18 19:05	48.26	OK	12032	2026-09-18 19:06	47.68	OK
12033	2026-09-18 19:07	47.87	OK	12034	2026-09-18 19:08	49.31	OK
1203	2026-09-18 19:09	48.02	OK	1203	2026-09-18 19:10	49.38	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
12037	2026-09-18 19:11	47.61	OK	12038	2026-09-18 19:12	49.92	OK
12039	2026-09-18 19:13	50.09	OK	12040	2026-09-18 19:14	48.87	OK
12041	2026-09-18 19:15	50.31	OK	12042	2026-09-18 19:16	49.47	OK
12043	2026-09-18 19:17	47.29	OK	12044	2026-09-18 19:18	49.91	OK
12045	2026-09-18 19:19	49.64	OK	12046	2026-09-18 19:20	47.56	OK
12047	2026-09-18 19:21	48.71	OK	12048	2026-09-18 19:22	49.56	OK
12049	2026-09-18 19:23	48.13	OK	12050	2026-09-18 19:24	49.52	OK
12051	2026-09-18 19:25	48.39	OK	12052	2026-09-18 19:26	47.96	OK
12053	2026-09-18 19:27	47.12	OK	12054	2026-09-18 19:28	48.87	OK
12055	2026-09-18 19:29	48.40	OK	12056	2026-09-18 19:30	47.77	OK
12057	2026-09-18 19:31	48.33	OK	12058	2026-09-18 19:32	48.92	OK
12059	2026-09-18 19:33	49.20	OK	12060	2026-09-18 19:34	46.36	OK
12061	2026-09-18 19:35	47.71	OK	12062	2026-09-18 19:36	47.87	OK
12063	2026-09-18 19:37	48.63	OK	12064	2026-09-18 19:38	49.66	OK
12065	2026-09-18 19:39	48.53	OK	12066	2026-09-18 19:40	49.80	OK
12067	2026-09-18 19:41	49.04	OK	12068	2026-09-18 19:42	48.48	OK
12069	2026-09-18 19:43	48.95	OK	12070	2026-09-18 19:44	48.27	OK
12071	2026-09-18 19:45	47.71	OK	12072	2026-09-18 19:46	48.47	OK
12073	2026-09-18 19:47	47.66	OK	12074	2026-09-18 19:48	47.87	OK
12075	2026-09-18 19:49	48.59	OK	12076	2026-09-18 19:50	48.79	OK
12077	2026-09-18 19:51	47.60	OK	12078	2026-09-18 19:52	47.98	OK
12079	2026-09-18 19:53	47.33	OK	12080	2026-09-18 19:54	47.50	OK
12081	2026-09-18 19:55	48.49	OK	12082	2026-09-18 19:56	48.29	OK
12083	2026-09-18 19:57	46.57	OK	12084	2026-09-18 19:58	49.07	OK
12085	2026-09-18 19:59	48.43	OK	12086	2026-09-18 20:00	45.89	OK
12087	2026-09-18 20:01	49.73	OK	12088	2026-09-18 20:02	47.85	OK
12089	2026-09-18 20:03	47.47	OK	12090	2026-09-18 20:04	47.90	OK
12091	2026-09-18 20:05	48.38	OK	12092	2026-09-18 20:06	47.69	OK
12093	2026-09-18 20:07	47.59	OK	12094	2026-09-18 20:08	47.81	OK
1209	2026-09-18 20:09	47.50	OK	1209	2026-09-18 20:10	48.39	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
12097	2026-09-18 20:11	48.32	OK	12098	2026-09-18 20:12	46.92	OK
12099	2026-09-18 20:13	47.78	OK	12100	2026-09-18 20:14	47.46	OK
12101	2026-09-18 20:15	46.99	OK	12102	2026-09-18 20:16	47.57	OK
12103	2026-09-18 20:17	46.60	OK	12104	2026-09-18 20:18	48.93	OK
12105	2026-09-18 20:19	47.62	OK	12106	2026-09-18 20:20	48.03	OK
12107	2026-09-18 20:21	46.27	OK	12108	2026-09-18 20:22	47.36	OK
12109	2026-09-18 20:23	48.20	OK	12110	2026-09-18 20:24	46.89	OK
12111	2026-09-18 20:25	48.76	OK	12112	2026-09-18 20:26	47.44	OK
12113	2026-09-18 20:27	47.45	OK	12114	2026-09-18 20:28	48.60	OK
12115	2026-09-18 20:29	48.78	OK	12116	2026-09-18 20:30	47.83	OK
12117	2026-09-18 20:31	47.29	OK	12118	2026-09-18 20:32	46.81	OK
12119	2026-09-18 20:33	47.85	OK	12120	2026-09-18 20:34	46.26	OK
12121	2026-09-18 20:35	47.25	OK	12122	2026-09-18 20:36	45.82	OK
12123	2026-09-18 20:37	47.81	OK	12124	2026-09-18 20:38	46.76	OK
12125	2026-09-18 20:39	47.44	OK	12126	2026-09-18 20:40	48.82	OK
12127	2026-09-18 20:41	46.90	OK	12128	2026-09-18 20:42	47.11	OK
12129	2026-09-18 20:43	46.20	OK	12130	2026-09-18 20:44	47.50	OK
12131	2026-09-18 20:45	45.85	OK	12132	2026-09-18 20:46	47.47	OK
12133	2026-09-18 20:47	45.13	OK	12134	2026-09-18 20:48	45.53	OK
12135	2026-09-18 20:49	47.32	OK	12136	2026-09-18 20:50	49.61	OK
12137	2026-09-18 20:51	47.70	OK	12138	2026-09-18 20:52	46.76	OK
12139	2026-09-18 20:53	46.82	OK	12140	2026-09-18 20:54	47.24	OK
12141	2026-09-18 20:55	45.74	OK	12142	2026-09-18 20:56	47.36	OK
12143	2026-09-18 20:57	49.35	OK	12144	2026-09-18 20:58	47.38	OK
12145	2026-09-18 20:59	46.89	OK	12146	2026-09-18 21:00	45.91	OK
12147	2026-09-18 21:01	46.99	OK	12148	2026-09-18 21:02	48.16	OK
12149	2026-09-18 21:03	47.90	OK	12150	2026-09-18 21:04	47.74	OK
12151	2026-09-18 21:05	48.13	OK	12152	2026-09-18 21:06	49.42	OK
12153	2026-09-18 21:07	48.71	OK	12154	2026-09-18 21:08	44.96	OK
1215	2026-09-18 21:09	49.20	OK	1215	2026-09-18 21:10	46.77	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
12157	2026-09-18 21:11	47.37	OK	12158	2026-09-18 21:12	47.12	OK
12159	2026-09-18 21:13	44.94	OK	12160	2026-09-18 21:14	48.47	OK
12161	2026-09-18 21:15	47.66	OK	12162	2026-09-18 21:16	45.31	OK
12163	2026-09-18 21:17	46.76	OK	12164	2026-09-18 21:18	47.26	OK
12165	2026-09-18 21:19	46.46	OK	12166	2026-09-18 21:20	47.84	OK
12167	2026-09-18 21:21	46.69	OK	12168	2026-09-18 21:22	46.86	OK
12169	2026-09-18 21:23	44.95	OK	12170	2026-09-18 21:24	46.28	OK
12171	2026-09-18 21:25	47.74	OK	12172	2026-09-18 21:26	45.50	OK
12173	2026-09-18 21:27	48.58	OK	12174	2026-09-18 21:28	46.98	OK
12175	2026-09-18 21:29	46.50	OK	12176	2026-09-18 21:30	46.39	OK
12177	2026-09-18 21:31	46.43	OK	12178	2026-09-18 21:32	45.76	OK
12179	2026-09-18 21:33	48.75	OK	12180	2026-09-18 21:34	47.49	OK
12181	2026-09-18 21:35	45.66	OK	12182	2026-09-18 21:36	46.43	OK
12183	2026-09-18 21:37	46.59	OK	12184	2026-09-18 21:38	44.86	OK
12185	2026-09-18 21:39	46.64	OK	12186	2026-09-18 21:40	47.41	OK
12187	2026-09-18 21:41	47.04	OK	12188	2026-09-18 21:42	46.29	OK
12189	2026-09-18 21:43	46.50	OK	12190	2026-09-18 21:44	46.95	OK
12191	2026-09-18 21:45	46.41	OK	12192	2026-09-18 21:46	48.06	OK
12193	2026-09-18 21:47	47.20	OK	12194	2026-09-18 21:48	47.42	OK
12195	2026-09-18 21:49	44.53	OK	12196	2026-09-18 21:50	47.23	OK
12197	2026-09-18 21:51	47.07	OK	12198	2026-09-18 21:52	45.73	OK
12199	2026-09-18 21:53	47.25	OK	12200	2026-09-18 21:54	47.03	OK
12201	2026-09-18 21:55	46.29	OK	12202	2026-09-18 21:56	45.41	OK
12203	2026-09-18 21:57	44.40	OK	12204	2026-09-18 21:58	47.87	OK
12205	2026-09-18 21:59	45.80	OK	12206	2026-09-18 22:00	46.01	OK
12207	2026-09-18 22:01	47.97	OK	12208	2026-09-18 22:02	47.00	OK
12209	2026-09-18 22:03	45.60	OK	12210	2026-09-18 22:04	44.84	OK
12211	2026-09-18 22:05	46.17	OK	12212	2026-09-18 22:06	48.10	OK
12213	2026-09-18 22:07	46.07	OK	12214	2026-09-18 22:08	46.36	OK
1221	2026-09-18 22:09	46.54	OK	1221	2026-09-18 22:10	45.69	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
12217	2026-09-18 22:11	47.20	OK	12218	2026-09-18 22:12	47.60	OK
12219	2026-09-18 22:13	46.79	OK	12220	2026-09-18 22:14	46.45	OK
12221	2026-09-18 22:15	46.92	OK	12222	2026-09-18 22:16	45.80	OK
12223	2026-09-18 22:17	44.28	OK	12224	2026-09-18 22:18	47.37	OK
12225	2026-09-18 22:19	46.93	OK	12226	2026-09-18 22:20	45.28	OK
12227	2026-09-18 22:21	45.67	OK	12228	2026-09-18 22:22	45.88	OK
12229	2026-09-18 22:23	46.11	OK	12230	2026-09-18 22:24	46.83	OK
12231	2026-09-18 22:25	47.36	OK	12232	2026-09-18 22:26	45.87	OK
12233	2026-09-18 22:27	45.96	OK	12234	2026-09-18 22:28	43.81	OK
12235	2026-09-18 22:29	45.89	OK	12236	2026-09-18 22:30	46.95	OK
12237	2026-09-18 22:31	47.28	OK	12238	2026-09-18 22:32	45.38	OK
12239	2026-09-18 22:33	46.69	OK	12240	2026-09-18 22:34	45.56	OK
12241	2026-09-18 22:35	44.98	OK	12242	2026-09-18 22:36	45.06	OK
12243	2026-09-18 22:37	47.12	OK	12244	2026-09-18 22:38	45.03	OK
12245	2026-09-18 22:39	44.96	OK	12246	2026-09-18 22:40	46.43	OK
12247	2026-09-18 22:41	45.43	OK	12248	2026-09-18 22:42	45.55	OK
12249	2026-09-18 22:43	44.08	OK	12250	2026-09-18 22:44	44.84	OK
12251	2026-09-18 22:45	45.54	OK	12252	2026-09-18 22:46	45.77	OK
12253	2026-09-18 22:47	45.92	OK	12254	2026-09-18 22:48	46.13	OK
12255	2026-09-18 22:49	44.16	OK	12256	2026-09-18 22:50	44.97	OK
12257	2026-09-18 22:51	45.05	OK	12258	2026-09-18 22:52	45.58	OK
12259	2026-09-18 22:53	46.05	OK	12260	2026-09-18 22:54	43.65	OK
12261	2026-09-18 22:55	44.85	OK	12262	2026-09-18 22:56	45.66	OK
12263	2026-09-18 22:57	45.22	OK	12264	2026-09-18 22:58	45.95	OK
12265	2026-09-18 22:59	45.65	OK	12266	2026-09-18 23:00	45.03	OK
12267	2026-09-18 23:01	45.85	OK	12268	2026-09-18 23:02	45.77	OK
12269	2026-09-18 23:03	44.72	OK	12270	2026-09-18 23:04	45.94	OK
12271	2026-09-18 23:05	45.45	OK	12272	2026-09-18 23:06	46.00	OK
12273	2026-09-18 23:07	46.49	OK	12274	2026-09-18 23:08	45.73	OK
1227	2026-09-18 23:09	44.74	OK	1227	2026-09-18 23:10	46.56	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
12277	2026-09-18 23:11	47.31	OK	12278	2026-09-18 23:12	45.03	OK
12279	2026-09-18 23:13	45.72	OK	12280	2026-09-18 23:14	46.08	OK
12281	2026-09-18 23:15	45.10	OK	12282	2026-09-18 23:16	47.19	OK
12283	2026-09-18 23:17	46.36	OK	12284	2026-09-18 23:18	46.42	OK
12285	2026-09-18 23:19	44.87	OK	12286	2026-09-18 23:20	46.61	OK
12287	2026-09-18 23:21	46.17	OK	12288	2026-09-18 23:22	47.15	OK
12289	2026-09-18 23:23	45.34	OK	12290	2026-09-18 23:24	44.37	OK
12291	2026-09-18 23:25	45.76	OK	12292	2026-09-18 23:26	44.94	OK
12293	2026-09-18 23:27	46.05	OK	12294	2026-09-18 23:28	44.34	OK
12295	2026-09-18 23:29	47.02	OK	12296	2026-09-18 23:30	44.95	OK
12297	2026-09-18 23:31	47.38	OK	12298	2026-09-18 23:32	44.44	OK
12299	2026-09-18 23:33	45.03	OK	12300	2026-09-18 23:34	45.28	OK
12301	2026-09-18 23:35	46.68	OK	12302	2026-09-18 23:36	45.93	OK
12303	2026-09-18 23:37	44.96	OK	12304	2026-09-18 23:38	47.28	OK
12305	2026-09-18 23:39	43.54	OK	12306	2026-09-18 23:40	45.92	OK
12307	2026-09-18 23:41	47.24	OK	12308	2026-09-18 23:42	44.12	OK
12309	2026-09-18 23:43	46.09	OK	12310	2026-09-18 23:44	47.08	OK
12311	2026-09-18 23:45	44.98	OK	12312	2026-09-18 23:46	46.81	OK
12313	2026-09-18 23:47	45.26	OK	12314	2026-09-18 23:48	43.72	OK
12315	2026-09-18 23:49	46.97	OK	12316	2026-09-18 23:50	45.35	OK
12317	2026-09-18 23:51	46.55	OK	12318	2026-09-18 23:52	44.76	OK
12319	2026-09-18 23:53	45.48	OK	12320	2026-09-18 23:54	45.35	OK
12321	2026-09-18 23:55	46.76	OK	12322	2026-09-18 23:56	45.07	OK
12323	2026-09-18 23:57	45.04	OK	12324	2026-09-18 23:58	44.34	OK
12325	2026-09-18 23:59	45.43	OK	12326	2026-09-19 00:00	45.38	OK
12327	2026-09-19 00:01	44.66	OK	12328	2026-09-19 00:02	45.21	OK
12329	2026-09-19 00:03	44.83	OK	12330	2026-09-19 00:04	44.58	OK
12331	2026-09-19 00:05	44.20	OK	12332	2026-09-19 00:06	46.53	OK
12333	2026-09-19 00:07	45.94	OK	12334	2026-09-19 00:08	44.18	OK
1233	2026-09-19 00:09	46.09	OK	1233	2026-09-19 00:10	44.61	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
12337	2026-09-19 00:11	45.26	OK	12338	2026-09-19 00:12	44.21	OK
12339	2026-09-19 00:13	45.60	OK	12340	2026-09-19 00:14	44.83	OK
12341	2026-09-19 00:15	45.02	OK	12342	2026-09-19 00:16	45.94	OK
12343	2026-09-19 00:17	44.86	OK	12344	2026-09-19 00:18	46.73	OK
12345	2026-09-19 00:19	46.77	OK	12346	2026-09-19 00:20	43.83	OK
12347	2026-09-19 00:21	46.40	OK	12348	2026-09-19 00:22	46.98	OK
12349	2026-09-19 00:23	45.43	OK	12350	2026-09-19 00:24	46.36	OK
12351	2026-09-19 00:25	46.47	OK	12352	2026-09-19 00:26	44.33	OK
12353	2026-09-19 00:27	44.65	OK	12354	2026-09-19 00:28	44.83	OK
12355	2026-09-19 00:29	45.61	OK	12356	2026-09-19 00:30	45.53	OK
12357	2026-09-19 00:31	45.20	OK	12358	2026-09-19 00:32	44.48	OK
12359	2026-09-19 00:33	43.64	OK	12360	2026-09-19 00:34	46.94	OK
12361	2026-09-19 00:35	45.62	OK	12362	2026-09-19 00:36	44.95	OK
12363	2026-09-19 00:37	46.20	OK	12364	2026-09-19 00:38	44.78	OK
12365	2026-09-19 00:39	44.00	OK	12366	2026-09-19 00:40	45.81	OK
12367	2026-09-19 00:41	45.31	OK	12368	2026-09-19 00:42	44.46	OK
12369	2026-09-19 00:43	45.37	OK	12370	2026-09-19 00:44	45.02	OK
12371	2026-09-19 00:45	45.30	OK	12372	2026-09-19 00:46	44.10	OK
12373	2026-09-19 00:47	45.82	OK	12374	2026-09-19 00:48	44.24	OK
12375	2026-09-19 00:49	45.84	OK	12376	2026-09-19 00:50	46.80	OK
12377	2026-09-19 00:51	44.37	OK	12378	2026-09-19 00:52	44.59	OK
12379	2026-09-19 00:53	44.90	OK	12380	2026-09-19 00:54	47.08	OK
12381	2026-09-19 00:55	44.40	OK	12382	2026-09-19 00:56	45.89	OK
12383	2026-09-19 00:57	45.84	OK	12384	2026-09-19 00:58	44.31	OK
12385	2026-09-19 00:59	45.60	OK	12386	2026-09-19 01:00	45.52	OK
12387	2026-09-19 01:01	46.33	OK	12388	2026-09-19 01:02	46.19	OK
12389	2026-09-19 01:03	46.28	OK	12390	2026-09-19 01:04	43.79	OK
12391	2026-09-19 01:05	45.66	OK	12392	2026-09-19 01:06	46.33	OK
12393	2026-09-19 01:07	45.81	OK	12394	2026-09-19 01:08	45.84	OK
1239	2026-09-19 01:09	46.00	OK	1239	2026-09-19 01:10	44.33	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
12397	2026-09-19 01:11	45.15	OK	12398	2026-09-19 01:12	45.67	OK
12399	2026-09-19 01:13	44.73	OK	12400	2026-09-19 01:14	46.96	OK
12401	2026-09-19 01:15	46.59	OK	12402	2026-09-19 01:16	45.73	OK
12403	2026-09-19 01:17	46.55	OK	12404	2026-09-19 01:18	43.34	OK
12405	2026-09-19 01:19	46.01	OK	12406	2026-09-19 01:20	45.08	OK
12407	2026-09-19 01:21	45.86	OK	12408	2026-09-19 01:22	46.66	OK
12409	2026-09-19 01:23	45.01	OK	12410	2026-09-19 01:24	44.05	OK
12411	2026-09-19 01:25	44.19	OK	12412	2026-09-19 01:26	45.14	OK
12413	2026-09-19 01:27	44.99	OK	12414	2026-09-19 01:28	44.64	OK
12415	2026-09-19 01:29	43.55	OK	12416	2026-09-19 01:30	44.32	OK
12417	2026-09-19 01:31	44.80	OK	12418	2026-09-19 01:32	45.32	OK
12419	2026-09-19 01:33	45.34	OK	12420	2026-09-19 01:34	47.17	OK
12421	2026-09-19 01:35	44.44	OK	12422	2026-09-19 01:36	44.78	OK
12423	2026-09-19 01:37	45.15	OK	12424	2026-09-19 01:38	46.33	OK
12425	2026-09-19 01:39	45.06	OK	12426	2026-09-19 01:40	45.91	OK
12427	2026-09-19 01:41	44.94	OK	12428	2026-09-19 01:42	47.09	OK
12429	2026-09-19 01:43	46.25	OK	12430	2026-09-19 01:44	44.23	OK
12431	2026-09-19 01:45	43.12	OK	12432	2026-09-19 01:46	45.96	OK
12433	2026-09-19 01:47	46.18	OK	12434	2026-09-19 01:48	46.14	OK
12435	2026-09-19 01:49	45.91	OK	12436	2026-09-19 01:50	47.01	OK
12437	2026-09-19 01:51	45.62	OK	12438	2026-09-19 01:52	45.18	OK
12439	2026-09-19 01:53	44.40	OK	12440	2026-09-19 01:54	46.70	OK
12441	2026-09-19 01:55	45.30	OK	12442	2026-09-19 01:56	43.90	OK
12443	2026-09-19 01:57	45.69	OK	12444	2026-09-19 01:58	47.56	OK
12445	2026-09-19 01:59	44.84	OK	12446	2026-09-19 02:00	45.80	OK
12447	2026-09-19 02:01	44.70	OK	12448	2026-09-19 02:02	45.14	OK
12449	2026-09-19 02:03	44.36	OK	12450	2026-09-19 02:04	44.50	OK
12451	2026-09-19 02:05	44.25	OK	12452	2026-09-19 02:06	44.76	OK
12453	2026-09-19 02:07	45.67	OK	12454	2026-09-19 02:08	44.37	OK
1245	2026-09-19 02:09	45.05	OK	1245	2026-09-19 02:10	45.41	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
12457	2026-09-19 02:11	45.97	OK	12458	2026-09-19 02:12	46.01	OK
12459	2026-09-19 02:13	45.37	OK	12460	2026-09-19 02:14	46.43	OK
12461	2026-09-19 02:15	43.75	OK	12462	2026-09-19 02:16	45.04	OK
12463	2026-09-19 02:17	45.33	OK	12464	2026-09-19 02:18	44.43	OK
12465	2026-09-19 02:19	44.23	OK	12466	2026-09-19 02:20	45.19	OK
12467	2026-09-19 02:21	47.76	OK	12468	2026-09-19 02:22	44.12	OK
12469	2026-09-19 02:23	43.82	OK	12470	2026-09-19 02:24	47.32	OK
12471	2026-09-19 02:25	44.85	OK	12472	2026-09-19 02:26	44.06	OK
12473	2026-09-19 02:27	45.06	OK	12474	2026-09-19 02:28	46.46	OK
12475	2026-09-19 02:29	44.02	OK	12476	2026-09-19 02:30	45.91	OK
12477	2026-09-19 02:31	45.99	OK	12478	2026-09-19 02:32	43.57	OK
12479	2026-09-19 02:33	44.79	OK	12480	2026-09-19 02:34	44.72	OK
12481	2026-09-19 02:35	45.31	OK	12482	2026-09-19 02:36	44.73	OK
12483	2026-09-19 02:37	46.87	OK	12484	2026-09-19 02:38	45.19	OK
12485	2026-09-19 02:39	45.01	OK	12486	2026-09-19 02:40	44.13	OK
12487	2026-09-19 02:41	46.08	OK	12488	2026-09-19 02:42	44.27	OK
12489	2026-09-19 02:43	45.16	OK	12490	2026-09-19 02:44	45.14	OK
12491	2026-09-19 02:45	44.50	OK	12492	2026-09-19 02:46	44.91	OK
12493	2026-09-19 02:47	45.02	OK	12494	2026-09-19 02:48	47.05	OK
12495	2026-09-19 02:49	47.61	OK	12496	2026-09-19 02:50	45.56	OK
12497	2026-09-19 02:51	44.72	OK	12498	2026-09-19 02:52	44.44	OK
12499	2026-09-19 02:53	44.94	OK	12500	2026-09-19 02:54	45.42	OK
12501	2026-09-19 02:55	45.79	OK	12502	2026-09-19 02:56	46.29	OK
12503	2026-09-19 02:57	46.62	OK	12504	2026-09-19 02:58	45.39	OK
12505	2026-09-19 02:59	45.43	OK	12506	2026-09-19 03:00	44.13	OK
12507	2026-09-19 03:01	46.01	OK	12508	2026-09-19 03:02	44.23	OK
12509	2026-09-19 03:03	46.52	OK	12510	2026-09-19 03:04	45.41	OK
12511	2026-09-19 03:05	43.64	OK	12512	2026-09-19 03:06	44.05	OK
12513	2026-09-19 03:07	45.22	OK	12514	2026-09-19 03:08	47.35	OK
1251	2026-09-19 03:09	45.44	OK	1251	2026-09-19 03:10	44.76	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
12517	2026-09-19 03:11	47.34	OK	12518	2026-09-19 03:12	44.75	OK
12519	2026-09-19 03:13	45.98	OK	12520	2026-09-19 03:14	45.48	OK
12521	2026-09-19 03:15	46.64	OK	12522	2026-09-19 03:16	46.39	OK
12523	2026-09-19 03:17	45.95	OK	12524	2026-09-19 03:18	45.74	OK
12525	2026-09-19 03:19	45.90	OK	12526	2026-09-19 03:20	46.15	OK
12527	2026-09-19 03:21	45.36	OK	12528	2026-09-19 03:22	46.73	OK
12529	2026-09-19 03:23	44.84	OK	12530	2026-09-19 03:24	44.93	OK
12531	2026-09-19 03:25	46.01	OK	12532	2026-09-19 03:26	45.92	OK
12533	2026-09-19 03:27	45.50	OK	12534	2026-09-19 03:28	47.37	OK
12535	2026-09-19 03:29	48.05	OK	12536	2026-09-19 03:30	44.43	OK
12537	2026-09-19 03:31	44.23	OK	12538	2026-09-19 03:32	45.65	OK
12539	2026-09-19 03:33	46.13	OK	12540	2026-09-19 03:34	46.04	OK
12541	2026-09-19 03:35	44.48	OK	12542	2026-09-19 03:36	46.21	OK
12543	2026-09-19 03:37	46.85	OK	12544	2026-09-19 03:38	44.42	OK
12545	2026-09-19 03:39	45.51	OK	12546	2026-09-19 03:40	46.03	OK
12547	2026-09-19 03:41	47.26	OK	12548	2026-09-19 03:42	45.14	OK
12549	2026-09-19 03:43	46.94	OK	12550	2026-09-19 03:44	45.26	OK
12551	2026-09-19 03:45	47.55	OK	12552	2026-09-19 03:46	45.90	OK
12553	2026-09-19 03:47	45.86	OK	12554	2026-09-19 03:48	46.24	OK
12555	2026-09-19 03:49	45.56	OK	12556	2026-09-19 03:50	45.87	OK
12557	2026-09-19 03:51	44.47	OK	12558	2026-09-19 03:52	45.95	OK
12559	2026-09-19 03:53	45.23	OK	12560	2026-09-19 03:54	46.08	OK
12561	2026-09-19 03:55	45.37	OK	12562	2026-09-19 03:56	46.35	OK
12563	2026-09-19 03:57	46.32	OK	12564	2026-09-19 03:58	43.95	OK
12565	2026-09-19 03:59	45.49	OK	12566	2026-09-19 04:00	45.24	OK
12567	2026-09-19 04:01	44.61	OK	12568	2026-09-19 04:02	45.64	OK
12569	2026-09-19 04:03	44.91	OK	12570	2026-09-19 04:04	46.26	OK
12571	2026-09-19 04:05	45.87	OK	12572	2026-09-19 04:06	46.81	OK
12573	2026-09-19 04:07	47.57	OK	12574	2026-09-19 04:08	45.82	OK
1257	2026-09-19 04:09	44.35	OK	1257	2026-09-19 04:10	45.38	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
12577	2026-09-19 04:11	47.04	OK	12578	2026-09-19 04:12	44.70	OK
12579	2026-09-19 04:13	46.00	OK	12580	2026-09-19 04:14	47.24	OK
12581	2026-09-19 04:15	44.69	OK	12582	2026-09-19 04:16	46.18	OK
12583	2026-09-19 04:17	46.88	OK	12584	2026-09-19 04:18	45.59	OK
12585	2026-09-19 04:19	47.36	OK	12586	2026-09-19 04:20	45.48	OK
12587	2026-09-19 04:21	45.91	OK	12588	2026-09-19 04:22	45.50	OK
12589	2026-09-19 04:23	48.20	OK	12590	2026-09-19 04:24	47.71	OK
12591	2026-09-19 04:25	45.01	OK	12592	2026-09-19 04:26	46.22	OK
12593	2026-09-19 04:27	46.54	OK	12594	2026-09-19 04:28	45.30	OK
12595	2026-09-19 04:29	44.32	OK	12596	2026-09-19 04:30	46.38	OK
12597	2026-09-19 04:31	45.54	OK	12598	2026-09-19 04:32	46.90	OK
12599	2026-09-19 04:33	46.66	OK	12600	2026-09-19 04:34	45.52	OK
12601	2026-09-19 04:35	46.21	OK	12602	2026-09-19 04:36	46.84	OK
12603	2026-09-19 04:37	45.90	OK	12604	2026-09-19 04:38	44.70	OK
12605	2026-09-19 04:39	45.98	OK	12606	2026-09-19 04:40	44.95	OK
12607	2026-09-19 04:41	46.60	OK	12608	2026-09-19 04:42	46.58	OK
12609	2026-09-19 04:43	45.57	OK	12610	2026-09-19 04:44	44.45	OK
12611	2026-09-19 04:45	46.81	OK	12612	2026-09-19 04:46	45.60	OK
12613	2026-09-19 04:47	47.97	OK	12614	2026-09-19 04:48	45.75	OK
12615	2026-09-19 04:49	46.01	OK	12616	2026-09-19 04:50	45.38	OK
12617	2026-09-19 04:51	46.42	OK	12618	2026-09-19 04:52	44.79	OK
12619	2026-09-19 04:53	46.22	OK	12620	2026-09-19 04:54	46.82	OK
12621	2026-09-19 04:55	46.55	OK	12622	2026-09-19 04:56	47.45	OK
12623	2026-09-19 04:57	46.40	OK	12624	2026-09-19 04:58	47.40	OK
12625	2026-09-19 04:59	44.99	OK	12626	2026-09-19 05:00	47.31	OK
12627	2026-09-19 05:01	45.51	OK	12628	2026-09-19 05:02	46.48	OK
12629	2026-09-19 05:03	46.43	OK	12630	2026-09-19 05:04	48.05	OK
12631	2026-09-19 05:05	45.89	OK	12632	2026-09-19 05:06	46.55	OK
12633	2026-09-19 05:07	47.40	OK	12634	2026-09-19 05:08	45.46	OK
1263	2026-09-19 05:09	46.31	OK	1263	2026-09-19 05:10	47.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
12637	2026-09-19 05:11	47.30	OK	12638	2026-09-19 05:12	47.66	OK
12639	2026-09-19 05:13	47.24	OK	12640	2026-09-19 05:14	46.66	OK
12641	2026-09-19 05:15	48.17	OK	12642	2026-09-19 05:16	45.68	OK
12643	2026-09-19 05:17	44.62	OK	12644	2026-09-19 05:18	48.02	OK
12645	2026-09-19 05:19	45.75	OK	12646	2026-09-19 05:20	47.06	OK
12647	2026-09-19 05:21	48.14	OK	12648	2026-09-19 05:22	45.10	OK
12649	2026-09-19 05:23	47.40	OK	12650	2026-09-19 05:24	47.05	OK
12651	2026-09-19 05:25	46.85	OK	12652	2026-09-19 05:26	46.34	OK
12653	2026-09-19 05:27	47.02	OK	12654	2026-09-19 05:28	47.03	OK
12655	2026-09-19 05:29	45.99	OK	12656	2026-09-19 05:30	46.64	OK
12657	2026-09-19 05:31	45.13	OK	12658	2026-09-19 05:32	47.24	OK
12659	2026-09-19 05:33	45.79	OK	12660	2026-09-19 05:34	49.29	OK
12661	2026-09-19 05:35	48.75	OK	12662	2026-09-19 05:36	48.08	OK
12663	2026-09-19 05:37	46.60	OK	12664	2026-09-19 05:38	48.41	OK
12665	2026-09-19 05:39	48.07	OK	12666	2026-09-19 05:40	46.21	OK
12667	2026-09-19 05:41	46.09	OK	12668	2026-09-19 05:42	46.38	OK
12669	2026-09-19 05:43	47.48	OK	12670	2026-09-19 05:44	48.37	OK
12671	2026-09-19 05:45	47.35	OK	12672	2026-09-19 05:46	47.39	OK
12673	2026-09-19 05:47	48.83	OK	12674	2026-09-19 05:48	47.70	OK
12675	2026-09-19 05:49	48.07	OK	12676	2026-09-19 05:50	46.96	OK
12677	2026-09-19 05:51	48.59	OK	12678	2026-09-19 05:52	48.71	OK
12679	2026-09-19 05:53	46.09	OK	12680	2026-09-19 05:54	47.31	OK
12681	2026-09-19 05:55	47.21	OK	12682	2026-09-19 05:56	45.72	OK
12683	2026-09-19 05:57	47.51	OK	12684	2026-09-19 05:58	46.08	OK
12685	2026-09-19 05:59	47.88	OK	12686	2026-09-19 06:00	48.17	OK
12687	2026-09-19 06:01	46.79	OK	12688	2026-09-19 06:02	46.66	OK
12689	2026-09-19 06:03	48.32	OK	12690	2026-09-19 06:04	48.26	OK
12691	2026-09-19 06:05	46.00	OK	12692	2026-09-19 06:06	48.35	OK
12693	2026-09-19 06:07	48.16	OK	12694	2026-09-19 06:08	47.52	OK
1269	2026-09-19 06:09	47.27	OK	1269	2026-09-19 06:10	46.14	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
12697	2026-09-19 06:11	46.44	OK	12698	2026-09-19 06:12	46.73	OK
12699	2026-09-19 06:13	49.12	OK	12700	2026-09-19 06:14	48.48	OK
12701	2026-09-19 06:15	46.51	OK	12702	2026-09-19 06:16	44.92	OK
12703	2026-09-19 06:17	48.77	OK	12704	2026-09-19 06:18	47.60	OK
12705	2026-09-19 06:19	47.57	OK	12706	2026-09-19 06:20	47.89	OK
12707	2026-09-19 06:21	49.78	OK	12708	2026-09-19 06:22	48.63	OK
12709	2026-09-19 06:23	47.39	OK	12710	2026-09-19 06:24	47.10	OK
12711	2026-09-19 06:25	45.89	OK	12712	2026-09-19 06:26	49.31	OK
12713	2026-09-19 06:27	46.37	OK	12714	2026-09-19 06:28	47.41	OK
12715	2026-09-19 06:29	46.20	OK	12716	2026-09-19 06:30	48.11	OK
12717	2026-09-19 06:31	47.12	OK	12718	2026-09-19 06:32	47.94	OK
12719	2026-09-19 06:33	47.29	OK	12720	2026-09-19 06:34	47.11	OK
12721	2026-09-19 06:35	47.62	OK	12722	2026-09-19 06:36	46.22	OK
12723	2026-09-19 06:37	46.88	OK	12724	2026-09-19 06:38	48.49	OK
12725	2026-09-19 06:39	48.04	OK	12726	2026-09-19 06:40	47.70	OK
12727	2026-09-19 06:41	47.50	OK	12728	2026-09-19 06:42	48.10	OK
12729	2026-09-19 06:43	49.80	OK	12730	2026-09-19 06:44	46.48	OK
12731	2026-09-19 06:45	48.30	OK	12732	2026-09-19 06:46	48.60	OK
12733	2026-09-19 06:47	47.48	OK	12734	2026-09-19 06:48	46.99	OK
12735	2026-09-19 06:49	46.57	OK	12736	2026-09-19 06:50	46.35	OK
12737	2026-09-19 06:51	48.33	OK	12738	2026-09-19 06:52	49.30	OK
12739	2026-09-19 06:53	47.96	OK	12740	2026-09-19 06:54	48.70	OK
12741	2026-09-19 06:55	48.10	OK	12742	2026-09-19 06:56	46.66	OK
12743	2026-09-19 06:57	45.64	OK	12744	2026-09-19 06:58	47.98	OK
12745	2026-09-19 06:59	47.19	OK	12746	2026-09-19 07:00	47.03	OK
12747	2026-09-19 07:01	47.29	OK	12748	2026-09-19 07:02	50.52	OK
12749	2026-09-19 07:03	47.94	OK	12750	2026-09-19 07:04	48.75	OK
12751	2026-09-19 07:05	46.06	OK	12752	2026-09-19 07:06	47.37	OK
12753	2026-09-19 07:07	47.84	OK	12754	2026-09-19 07:08	47.93	OK
1275	2026-09-19 07:09	50.24	OK	1275	2026-09-19 07:10	47.28	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
12757	2026-09-19 07:11	49.29	OK	12758	2026-09-19 07:12	48.85	OK
12759	2026-09-19 07:13	46.33	OK	12760	2026-09-19 07:14	48.20	OK
12761	2026-09-19 07:15	47.81	OK	12762	2026-09-19 07:16	48.77	OK
12763	2026-09-19 07:17	48.95	OK	12764	2026-09-19 07:18	48.33	OK
12765	2026-09-19 07:19	47.74	OK	12766	2026-09-19 07:20	48.60	OK
12767	2026-09-19 07:21	48.23	OK	12768	2026-09-19 07:22	48.77	OK
12769	2026-09-19 07:23	47.98	OK	12770	2026-09-19 07:24	48.19	OK
12771	2026-09-19 07:25	49.46	OK	12772	2026-09-19 07:26	49.12	OK
12773	2026-09-19 07:27	49.01	OK	12774	2026-09-19 07:28	48.47	OK
12775	2026-09-19 07:29	49.33	OK	12776	2026-09-19 07:30	49.09	OK
12777	2026-09-19 07:31	51.00	OK	12778	2026-09-19 07:32	49.33	OK
12779	2026-09-19 07:33	48.35	OK	12780	2026-09-19 07:34	49.26	OK
12781	2026-09-19 07:35	48.13	OK	12782	2026-09-19 07:36	47.78	OK
12783	2026-09-19 07:37	48.42	OK	12784	2026-09-19 07:38	48.75	OK
12785	2026-09-19 07:39	48.74	OK	12786	2026-09-19 07:40	48.42	OK
12787	2026-09-19 07:41	48.88	OK	12788	2026-09-19 07:42	49.41	OK
12789	2026-09-19 07:43	49.64	OK	12790	2026-09-19 07:44	48.29	OK
12791	2026-09-19 07:45	47.50	OK	12792	2026-09-19 07:46	48.02	OK
12793	2026-09-19 07:47	49.67	OK	12794	2026-09-19 07:48	49.75	OK
12795	2026-09-19 07:49	49.59	OK	12796	2026-09-19 07:50	47.19	OK
12797	2026-09-19 07:51	49.01	OK	12798	2026-09-19 07:52	48.73	OK
12799	2026-09-19 07:53	48.46	OK	12800	2026-09-19 07:54	47.84	OK
12801	2026-09-19 07:55	47.92	OK	12802	2026-09-19 07:56	47.73	OK
12803	2026-09-19 07:57	48.83	OK	12804	2026-09-19 07:58	49.65	OK
12805	2026-09-19 07:59	49.45	OK	12806	2026-09-19 08:00	50.58	OK
12807	2026-09-19 08:01	50.03	OK	12808	2026-09-19 08:02	48.78	OK
12809	2026-09-19 08:03	48.29	OK	12810	2026-09-19 08:04	49.01	OK
12811	2026-09-19 08:05	50.68	OK	12812	2026-09-19 08:06	50.48	OK
12813	2026-09-19 08:07	47.98	OK	12814	2026-09-19 08:08	49.45	OK
1281	2026-09-19 08:09	48.15	OK	1281	2026-09-19 08:10	47.06	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
12817	2026-09-19 08:11	49.07	OK	12818	2026-09-19 08:12	49.35	OK
12819	2026-09-19 08:13	49.34	OK	12820	2026-09-19 08:14	47.62	OK
12821	2026-09-19 08:15	50.08	OK	12822	2026-09-19 08:16	48.32	OK
12823	2026-09-19 08:17	50.14	OK	12824	2026-09-19 08:18	50.75	OK
12825	2026-09-19 08:19	49.78	OK	12826	2026-09-19 08:20	50.73	OK
12827	2026-09-19 08:21	49.22	OK	12828	2026-09-19 08:22	50.33	OK
12829	2026-09-19 08:23	48.56	OK	12830	2026-09-19 08:24	50.68	OK
12831	2026-09-19 08:25	49.10	OK	12832	2026-09-19 08:26	48.72	OK
12833	2026-09-19 08:27	49.56	OK	12834	2026-09-19 08:28	50.86	OK
12835	2026-09-19 08:29	50.07	OK	12836	2026-09-19 08:30	49.03	OK
12837	2026-09-19 08:31	51.43	OK	12838	2026-09-19 08:32	49.34	OK
12839	2026-09-19 08:33	49.90	OK	12840	2026-09-19 08:34	50.23	OK
12841	2026-09-19 08:35	49.94	OK	12842	2026-09-19 08:36	50.23	OK
12843	2026-09-19 08:37	48.92	OK	12844	2026-09-19 08:38	51.01	OK
12845	2026-09-19 08:39	51.05	OK	12846	2026-09-19 08:40	49.92	OK
12847	2026-09-19 08:41	49.73	OK	12848	2026-09-19 08:42	48.97	OK
12849	2026-09-19 08:43	50.18	OK	12850	2026-09-19 08:44	49.84	OK
12851	2026-09-19 08:45	50.09	OK	12852	2026-09-19 08:46	50.89	OK
12853	2026-09-19 08:47	50.70	OK	12854	2026-09-19 08:48	48.72	OK
12855	2026-09-19 08:49	51.08	OK	12856	2026-09-19 08:50	48.97	OK
12857	2026-09-19 08:51	49.43	OK	12858	2026-09-19 08:52	49.96	OK
12859	2026-09-19 08:53	50.49	OK	12860	2026-09-19 08:54	49.94	OK
12861	2026-09-19 08:55	49.64	OK	12862	2026-09-19 08:56	50.47	OK
12863	2026-09-19 08:57	49.43	OK	12864	2026-09-19 08:58	50.16	OK
12865	2026-09-19 08:59	48.61	OK	12866	2026-09-19 09:00	49.79	OK
12867	2026-09-19 09:01	50.47	OK	12868	2026-09-19 09:02	50.49	OK
12869	2026-09-19 09:03	49.52	OK	12870	2026-09-19 09:04	49.69	OK
12871	2026-09-19 09:05	50.53	OK	12872	2026-09-19 09:06	51.27	OK
12873	2026-09-19 09:07	50.30	OK	12874	2026-09-19 09:08	50.80	OK
1287	2026-09-19 09:09	49.38	OK	1287	2026-09-19 09:10	49.36	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
12877	2026-09-19 09:11	49.28	OK	12878	2026-09-19 09:12	51.77	OK
12879	2026-09-19 09:13	50.12	OK	12880	2026-09-19 09:14	50.58	OK
12881	2026-09-19 09:15	49.95	OK	12882	2026-09-19 09:16	49.78	OK
12883	2026-09-19 09:17	51.95	OK	12884	2026-09-19 09:18	51.33	OK
12885	2026-09-19 09:19	51.57	OK	12886	2026-09-19 09:20	50.82	OK
12887	2026-09-19 09:21	52.65	OK	12888	2026-09-19 09:22	48.99	OK
12889	2026-09-19 09:23	50.85	OK	12890	2026-09-19 09:24	51.07	OK
12891	2026-09-19 09:25	52.49	OK	12892	2026-09-19 09:26	50.20	OK
12893	2026-09-19 09:27	50.97	OK	12894	2026-09-19 09:28	48.36	OK
12895	2026-09-19 09:29	49.69	OK	12896	2026-09-19 09:30	51.21	OK
12897	2026-09-19 09:31	49.28	OK	12898	2026-09-19 09:32	49.78	OK
12899	2026-09-19 09:33	49.41	OK	12900	2026-09-19 09:34	50.20	OK
12901	2026-09-19 09:35	49.06	OK	12902	2026-09-19 09:36	49.77	OK
12903	2026-09-19 09:37	48.67	OK	12904	2026-09-19 09:38	50.51	OK
12905	2026-09-19 09:39	51.22	OK	12906	2026-09-19 09:40	51.77	OK
12907	2026-09-19 09:41	50.70	OK	12908	2026-09-19 09:42	49.74	OK
12909	2026-09-19 09:43	50.05	OK	12910	2026-09-19 09:44	50.66	OK
12911	2026-09-19 09:45	49.00	OK	12912	2026-09-19 09:46	50.19	OK
12913	2026-09-19 09:47	48.20	OK	12914	2026-09-19 09:48	52.88	OK
12915	2026-09-19 09:49	48.92	OK	12916	2026-09-19 09:50	50.75	OK
12917	2026-09-19 09:51	50.43	OK	12918	2026-09-19 09:52	50.54	OK
12919	2026-09-19 09:53	50.80	OK	12920	2026-09-19 09:54	49.45	OK
12921	2026-09-19 09:55	49.83	OK	12922	2026-09-19 09:56	51.83	OK
12923	2026-09-19 09:57	51.06	OK	12924	2026-09-19 09:58	50.56	OK
12925	2026-09-19 09:59	48.49	OK	12926	2026-09-19 10:00	50.83	OK
12927	2026-09-19 10:01	51.98	OK	12928	2026-09-19 10:02	51.33	OK
12929	2026-09-19 10:03	52.42	OK	12930	2026-09-19 10:04	51.07	OK
12931	2026-09-19 10:05	50.60	OK	12932	2026-09-19 10:06	50.72	OK
12933	2026-09-19 10:07	50.85	OK	12934	2026-09-19 10:08	51.85	OK
1293	2026-09-19 10:09	50.18	OK	1293	2026-09-19 10:10	52.58	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
12937	2026-09-19 10:11	51.24	OK	12938	2026-09-19 10:12	51.14	OK
12939	2026-09-19 10:13	49.95	OK	12940	2026-09-19 10:14	50.79	OK
12941	2026-09-19 10:15	50.75	OK	12942	2026-09-19 10:16	49.84	OK
12943	2026-09-19 10:17	48.93	OK	12944	2026-09-19 10:18	51.70	OK
12945	2026-09-19 10:19	50.19	OK	12946	2026-09-19 10:20	50.54	OK
12947	2026-09-19 10:21	51.10	OK	12948	2026-09-19 10:22	49.63	OK
12949	2026-09-19 10:23	51.52	OK	12950	2026-09-19 10:24	49.60	OK
12951	2026-09-19 10:25	51.38	OK	12952	2026-09-19 10:26	51.35	OK
12953	2026-09-19 10:27	51.12	OK	12954	2026-09-19 10:28	53.06	OK
12955	2026-09-19 10:29	52.12	OK	12956	2026-09-19 10:30	51.46	OK
12957	2026-09-19 10:31	49.78	OK	12958	2026-09-19 10:32	50.08	OK
12959	2026-09-19 10:33	51.45	OK	12960	2026-09-19 10:34	50.27	OK
12961	2026-09-19 10:35	50.00	OK	12962	2026-09-19 10:36	51.44	OK
12963	2026-09-19 10:37	48.86	OK	12964	2026-09-19 10:38	51.71	OK
12965	2026-09-19 10:39	52.01	OK	12966	2026-09-19 10:40	52.47	OK
12967	2026-09-19 10:41	51.74	OK	12968	2026-09-19 10:42	49.55	OK
12969	2026-09-19 10:43	52.26	OK	12970	2026-09-19 10:44	50.47	OK
12971	2026-09-19 10:45	52.91	OK	12972	2026-09-19 10:46	52.98	OK
12973	2026-09-19 10:47	50.94	OK	12974	2026-09-19 10:48	51.08	OK
12975	2026-09-19 10:49	52.50	OK	12976	2026-09-19 10:50	52.55	OK
12977	2026-09-19 10:51	51.62	OK	12978	2026-09-19 10:52	52.37	OK
12979	2026-09-19 10:53	51.17	OK	12980	2026-09-19 10:54	53.33	OK
12981	2026-09-19 10:55	51.48	OK	12982	2026-09-19 10:56	51.76	OK
12983	2026-09-19 10:57	52.71	OK	12984	2026-09-19 10:58	50.09	OK
12985	2026-09-19 10:59	52.62	OK	12986	2026-09-19 11:00	51.03	OK
12987	2026-09-19 11:01	52.14	OK	12988	2026-09-19 11:02	52.35	OK
12989	2026-09-19 11:03	49.11	OK	12990	2026-09-19 11:04	52.41	OK
12991	2026-09-19 11:05	49.55	OK	12992	2026-09-19 11:06	53.72	OK
12993	2026-09-19 11:07	51.24	OK	12994	2026-09-19 11:08	52.01	OK
1299	2026-09-19 11:09	50.78	OK	1299	2026-09-19 11:10	51.23	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
12997	2026-09-19 11:11	51.38	OK	12998	2026-09-19 11:12	50.68	OK
12999	2026-09-19 11:13	50.02	OK	13000	2026-09-19 11:14	52.54	OK
13001	2026-09-19 11:15	50.32	OK	13002	2026-09-19 11:16	52.20	OK
13003	2026-09-19 11:17	52.14	OK	13004	2026-09-19 11:18	50.88	OK
13005	2026-09-19 11:19	52.01	OK	13006	2026-09-19 11:20	52.82	OK
13007	2026-09-19 11:21	51.49	OK	13008	2026-09-19 11:22	52.85	OK
13009	2026-09-19 11:23	50.49	OK	13010	2026-09-19 11:24	52.40	OK
13011	2026-09-19 11:25	49.69	OK	13012	2026-09-19 11:26	52.49	OK
13013	2026-09-19 11:27	51.72	OK	13014	2026-09-19 11:28	51.28	OK
13015	2026-09-19 11:29	52.13	OK	13016	2026-09-19 11:30	52.77	OK
13017	2026-09-19 11:31	51.91	OK	13018	2026-09-19 11:32	49.97	OK
13019	2026-09-19 11:33	51.02	OK	13020	2026-09-19 11:34	50.89	OK
13021	2026-09-19 11:35	50.46	OK	13022	2026-09-19 11:36	50.27	OK
13023	2026-09-19 11:37	52.80	OK	13024	2026-09-19 11:38	50.60	OK
13025	2026-09-19 11:39	50.52	OK	13026	2026-09-19 11:40	52.01	OK
13027	2026-09-19 11:41	51.66	OK	13028	2026-09-19 11:42	52.96	OK
13029	2026-09-19 11:43	53.08	OK	13030	2026-09-19 11:44	51.27	OK
13031	2026-09-19 11:45	50.52	OK	13032	2026-09-19 11:46	50.75	OK
13033	2026-09-19 11:47	52.85	OK	13034	2026-09-19 11:48	51.29	OK
13035	2026-09-19 11:49	51.35	OK	13036	2026-09-19 11:50	53.09	OK
13037	2026-09-19 11:51	51.98	OK	13038	2026-09-19 11:52	51.46	OK
13039	2026-09-19 11:53	50.28	OK	13040	2026-09-19 11:54	50.48	OK
13041	2026-09-19 11:55	52.21	OK	13042	2026-09-19 11:56	53.36	OK
13043	2026-09-19 11:57	50.24	OK	13044	2026-09-19 11:58	51.17	OK
13045	2026-09-19 11:59	49.70	OK	13046	2026-09-19 12:00	51.34	OK
13047	2026-09-19 12:01	52.46	OK	13048	2026-09-19 12:02	51.63	OK
13049	2026-09-19 12:03	51.40	OK	13050	2026-09-19 12:04	51.67	OK
13051	2026-09-19 12:05	52.02	OK	13052	2026-09-19 12:06	50.97	OK
13053	2026-09-19 12:07	52.69	OK	13054	2026-09-19 12:08	52.48	OK
1305	2026-09-19 12:09	50.76	OK	1305	2026-09-19 12:10	51.67	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
13057	2026-09-19 12:11	51.98	OK	13058	2026-09-19 12:12	50.37	OK
13059	2026-09-19 12:13	50.12	OK	13060	2026-09-19 12:14	52.59	OK
13061	2026-09-19 12:15	53.45	OK	13062	2026-09-19 12:16	52.28	OK
13063	2026-09-19 12:17	53.56	OK	13064	2026-09-19 12:18	51.94	OK
13065	2026-09-19 12:19	52.13	OK	13066	2026-09-19 12:20	52.04	OK
13067	2026-09-19 12:21	51.85	OK	13068	2026-09-19 12:22	52.05	OK
13069	2026-09-19 12:23	51.53	OK	13070	2026-09-19 12:24	51.37	OK
13071	2026-09-19 12:25	51.03	OK	13072	2026-09-19 12:26	51.41	OK
13073	2026-09-19 12:27	53.55	OK	13074	2026-09-19 12:28	50.31	OK
13075	2026-09-19 12:29	51.55	OK	13076	2026-09-19 12:30	53.46	OK
13077	2026-09-19 12:31	52.41	OK	13078	2026-09-19 12:32	51.16	OK
13079	2026-09-19 12:33	51.24	OK	13080	2026-09-19 12:34	51.54	OK
13081	2026-09-19 12:35	51.83	OK	13082	2026-09-19 12:36	50.56	OK
13083	2026-09-19 12:37	50.32	OK	13084	2026-09-19 12:38	50.33	OK
13085	2026-09-19 12:39	51.32	OK	13086	2026-09-19 12:40	50.93	OK
13087	2026-09-19 12:41	51.41	OK	13088	2026-09-19 12:42	51.45	OK
13089	2026-09-19 12:43	51.52	OK	13090	2026-09-19 12:44	50.12	OK
13091	2026-09-19 12:45	51.87	OK	13092	2026-09-19 12:46	51.06	OK
13093	2026-09-19 12:47	51.06	OK	13094	2026-09-19 12:48	52.57	OK
13095	2026-09-19 12:49	52.26	OK	13096	2026-09-19 12:50	51.17	OK
13097	2026-09-19 12:51	51.64	OK	13098	2026-09-19 12:52	53.23	OK
13099	2026-09-19 12:53	51.45	OK	13100	2026-09-19 12:54	50.21	OK
13101	2026-09-19 12:55	51.36	OK	13102	2026-09-19 12:56	51.23	OK
13103	2026-09-19 12:57	51.34	OK	13104	2026-09-19 12:58	52.95	OK
13105	2026-09-19 12:59	52.22	OK	13106	2026-09-19 13:00	51.52	OK
13107	2026-09-19 13:01	52.13	OK	13108	2026-09-19 13:02	51.25	OK
13109	2026-09-19 13:03	51.24	OK	13110	2026-09-19 13:04	50.75	OK
13111	2026-09-19 13:05	52.42	OK	13112	2026-09-19 13:06	51.38	OK
13113	2026-09-19 13:07	52.29	OK	13114	2026-09-19 13:08	51.77	OK
1311	2026-09-19 13:09	52.77	OK	1311	2026-09-19 13:10	52.71	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
13117	2026-09-19 13:11	52.56	OK	13118	2026-09-19 13:12	51.86	OK
13119	2026-09-19 13:13	50.85	OK	13120	2026-09-19 13:14	50.93	OK
13121	2026-09-19 13:15	50.93	OK	13122	2026-09-19 13:16	51.71	OK
13123	2026-09-19 13:17	50.39	OK	13124	2026-09-19 13:18	50.85	OK
13125	2026-09-19 13:19	50.56	OK	13126	2026-09-19 13:20	52.58	OK
13127	2026-09-19 13:21	52.39	OK	13128	2026-09-19 13:22	52.09	OK
13129	2026-09-19 13:23	50.69	OK	13130	2026-09-19 13:24	52.05	OK
13131	2026-09-19 13:25	52.09	OK	13132	2026-09-19 13:26	50.27	OK
13133	2026-09-19 13:27	51.48	OK	13134	2026-09-19 13:28	52.06	OK
13135	2026-09-19 13:29	50.29	OK	13136	2026-09-19 13:30	52.83	OK
13137	2026-09-19 13:31	51.82	OK	13138	2026-09-19 13:32	51.83	OK
13139	2026-09-19 13:33	52.36	OK	13140	2026-09-19 13:34	52.82	OK
13141	2026-09-19 13:35	51.81	OK	13142	2026-09-19 13:36	52.69	OK
13143	2026-09-19 13:37	50.45	OK	13144	2026-09-19 13:38	53.28	OK
13145	2026-09-19 13:39	51.04	OK	13146	2026-09-19 13:40	53.56	OK
13147	2026-09-19 13:41	51.69	OK	13148	2026-09-19 13:42	51.32	OK
13149	2026-09-19 13:43	53.01	OK	13150	2026-09-19 13:44	52.06	OK
13151	2026-09-19 13:45	50.44	OK	13152	2026-09-19 13:46	53.93	OK
13153	2026-09-19 13:47	50.45	OK	13154	2026-09-19 13:48	51.57	OK
13155	2026-09-19 13:49	52.20	OK	13156	2026-09-19 13:50	52.06	OK
13157	2026-09-19 13:51	54.47	OK	13158	2026-09-19 13:52	52.16	OK
13159	2026-09-19 13:53	52.40	OK	13160	2026-09-19 13:54	52.10	OK
13161	2026-09-19 13:55	52.45	OK	13162	2026-09-19 13:56	50.99	OK
13163	2026-09-19 13:57	50.92	OK	13164	2026-09-19 13:58	52.01	OK
13165	2026-09-19 13:59	51.08	OK	13166	2026-09-19 14:00	52.75	OK
13167	2026-09-19 14:01	50.39	OK	13168	2026-09-19 14:02	49.77	OK
13169	2026-09-19 14:03	52.06	OK	13170	2026-09-19 14:04	51.06	OK
13171	2026-09-19 14:05	49.99	OK	13172	2026-09-19 14:06	51.13	OK
13173	2026-09-19 14:07	53.31	OK	13174	2026-09-19 14:08	50.34	OK
1317	2026-09-19 14:09	53.72	OK	1317	2026-09-19 14:10	52.61	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
13177	2026-09-19 14:11	51.13	OK	13178	2026-09-19 14:12	52.63	OK
13179	2026-09-19 14:13	53.50	OK	13180	2026-09-19 14:14	52.04	OK
13181	2026-09-19 14:15	52.20	OK	13182	2026-09-19 14:16	51.45	OK
13183	2026-09-19 14:17	53.21	OK	13184	2026-09-19 14:18	50.37	OK
13185	2026-09-19 14:19	53.39	OK	13186	2026-09-19 14:20	51.39	OK
13187	2026-09-19 14:21	51.83	OK	13188	2026-09-19 14:22	52.46	OK
13189	2026-09-19 14:23	51.83	OK	13190	2026-09-19 14:24	51.13	OK
13191	2026-09-19 14:25	50.66	OK	13192	2026-09-19 14:26	50.10	OK
13193	2026-09-19 14:27	53.22	OK	13194	2026-09-19 14:28	49.65	OK
13195	2026-09-19 14:29	51.10	OK	13196	2026-09-19 14:30	52.42	OK
13197	2026-09-19 14:31	51.17	OK	13198	2026-09-19 14:32	52.04	OK
13199	2026-09-19 14:33	51.93	OK	13200	2026-09-19 14:34	51.80	OK
13201	2026-09-19 14:35	53.02	OK	13202	2026-09-19 14:36	51.65	OK
13203	2026-09-19 14:37	50.32	OK	13204	2026-09-19 14:38	52.74	OK
13205	2026-09-19 14:39	51.08	OK	13206	2026-09-19 14:40	52.08	OK
13207	2026-09-19 14:41	51.87	OK	13208	2026-09-19 14:42	51.85	OK
13209	2026-09-19 14:43	50.06	OK	13210	2026-09-19 14:44	52.18	OK
13211	2026-09-19 14:45	50.98	OK	13212	2026-09-19 14:46	51.18	OK
13213	2026-09-19 14:47	50.94	OK	13214	2026-09-19 14:48	52.53	OK
13215	2026-09-19 14:49	51.94	OK	13216	2026-09-19 14:50	51.61	OK
13217	2026-09-19 14:51	52.45	OK	13218	2026-09-19 14:52	50.47	OK
13219	2026-09-19 14:53	51.28	OK	13220	2026-09-19 14:54	50.71	OK
13221	2026-09-19 14:55	50.92	OK	13222	2026-09-19 14:56	51.67	OK
13223	2026-09-19 14:57	50.29	OK	13224	2026-09-19 14:58	52.23	OK
13225	2026-09-19 14:59	52.40	OK	13226	2026-09-19 15:00	52.41	OK
13227	2026-09-19 15:01	50.47	OK	13228	2026-09-19 15:02	50.60	OK
13229	2026-09-19 15:03	50.84	OK	13230	2026-09-19 15:04	50.50	OK
13231	2026-09-19 15:05	51.28	OK	13232	2026-09-19 15:06	49.60	OK
13233	2026-09-19 15:07	52.72	OK	13234	2026-09-19 15:08	51.15	OK
1323	2026-09-19 15:09	52.33	OK	1323	2026-09-19 15:10	53.10	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
13237	2026-09-19 15:11	52.69	OK	13238	2026-09-19 15:12	53.08	OK
13239	2026-09-19 15:13	51.80	OK	13240	2026-09-19 15:14	52.46	OK
13241	2026-09-19 15:15	51.46	OK	13242	2026-09-19 15:16	53.28	OK
13243	2026-09-19 15:17	53.35	OK	13244	2026-09-19 15:18	49.99	OK
13245	2026-09-19 15:19	49.59	OK	13246	2026-09-19 15:20	51.42	OK
13247	2026-09-19 15:21	51.86	OK	13248	2026-09-19 15:22	49.45	OK
13249	2026-09-19 15:23	51.27	OK	13250	2026-09-19 15:24	51.24	OK
13251	2026-09-19 15:25	51.92	OK	13252	2026-09-19 15:26	51.79	OK
13253	2026-09-19 15:27	51.65	OK	13254	2026-09-19 15:28	51.73	OK
13255	2026-09-19 15:29	50.16	OK	13256	2026-09-19 15:30	52.30	OK
13257	2026-09-19 15:31	52.12	OK	13258	2026-09-19 15:32	51.27	OK
13259	2026-09-19 15:33	53.25	OK	13260	2026-09-19 15:34	51.32	OK
13261	2026-09-19 15:35	53.23	OK	13262	2026-09-19 15:36	52.63	OK
13263	2026-09-19 15:37	51.68	OK	13264	2026-09-19 15:38	52.41	OK
13265	2026-09-19 15:39	52.63	OK	13266	2026-09-19 15:40	50.56	OK
13267	2026-09-19 15:41	51.03	OK	13268	2026-09-19 15:42	49.57	OK
13269	2026-09-19 15:43	51.18	OK	13270	2026-09-19 15:44	51.36	OK
13271	2026-09-19 15:45	48.83	OK	13272	2026-09-19 15:46	50.53	OK
13273	2026-09-19 15:47	51.53	OK	13274	2026-09-19 15:48	49.99	OK
13275	2026-09-19 15:49	51.74	OK	13276	2026-09-19 15:50	51.71	OK
13277	2026-09-19 15:51	50.77	OK	13278	2026-09-19 15:52	50.58	OK
13279	2026-09-19 15:53	52.02	OK	13280	2026-09-19 15:54	53.23	OK
13281	2026-09-19 15:55	52.24	OK	13282	2026-09-19 15:56	50.41	OK
13283	2026-09-19 15:57	52.12	OK	13284	2026-09-19 15:58	52.49	OK
13285	2026-09-19 15:59	52.02	OK	13286	2026-09-19 16:00	49.18	OK
13287	2026-09-19 16:01	51.51	OK	13288	2026-09-19 16:02	50.06	OK
13289	2026-09-19 16:03	52.05	OK	13290	2026-09-19 16:04	52.64	OK
13291	2026-09-19 16:05	50.39	OK	13292	2026-09-19 16:06	51.14	OK
13293	2026-09-19 16:07	50.34	OK	13294	2026-09-19 16:08	52.61	OK
1329	2026-09-19 16:09	51.31	OK	1329	2026-09-19 16:10	52.24	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
13297	2026-09-19 16:11	50.92	OK	13298	2026-09-19 16:12	50.66	OK
13299	2026-09-19 16:13	51.84	OK	13300	2026-09-19 16:14	51.28	OK
13301	2026-09-19 16:15	48.39	OK	13302	2026-09-19 16:16	50.07	OK
13303	2026-09-19 16:17	50.15	OK	13304	2026-09-19 16:18	53.06	OK
13305	2026-09-19 16:19	49.78	OK	13306	2026-09-19 16:20	50.39	OK
13307	2026-09-19 16:21	49.58	OK	13308	2026-09-19 16:22	52.37	OK
13309	2026-09-19 16:23	49.94	OK	13310	2026-09-19 16:24	50.72	OK
13311	2026-09-19 16:25	50.62	OK	13312	2026-09-19 16:26	48.78	OK
13313	2026-09-19 16:27	51.36	OK	13314	2026-09-19 16:28	50.54	OK
13315	2026-09-19 16:29	53.13	OK	13316	2026-09-19 16:30	51.62	OK
13317	2026-09-19 16:31	50.10	OK	13318	2026-09-19 16:32	51.41	OK
13319	2026-09-19 16:33	51.88	OK	13320	2026-09-19 16:34	50.78	OK
13321	2026-09-19 16:35	50.67	OK	13322	2026-09-19 16:36	50.16	OK
13323	2026-09-19 16:37	51.45	OK	13324	2026-09-19 16:38	50.89	OK
13325	2026-09-19 16:39	50.78	OK	13326	2026-09-19 16:40	51.83	OK
13327	2026-09-19 16:41	51.17	OK	13328	2026-09-19 16:42	51.94	OK
13329	2026-09-19 16:43	49.87	OK	13330	2026-09-19 16:44	51.09	OK
13331	2026-09-19 16:45	49.33	OK	13332	2026-09-19 16:46	49.42	OK
13333	2026-09-19 16:47	51.46	OK	13334	2026-09-19 16:48	50.19	OK
13335	2026-09-19 16:49	48.63	OK	13336	2026-09-19 16:50	52.57	OK
13337	2026-09-19 16:51	50.14	OK	13338	2026-09-19 16:52	49.90	OK
13339	2026-09-19 16:53	49.68	OK	13340	2026-09-19 16:54	51.47	OK
13341	2026-09-19 16:55	49.92	OK	13342	2026-09-19 16:56	49.89	OK
13343	2026-09-19 16:57	51.81	OK	13344	2026-09-19 16:58	52.08	OK
13345	2026-09-19 16:59	51.35	OK	13346	2026-09-19 17:00	50.13	OK
13347	2026-09-19 17:01	52.46	OK	13348	2026-09-19 17:02	49.65	OK
13349	2026-09-19 17:03	49.81	OK	13350	2026-09-19 17:04	49.27	OK
13351	2026-09-19 17:05	49.45	OK	13352	2026-09-19 17:06	49.85	OK
13353	2026-09-19 17:07	50.17	OK	13354	2026-09-19 17:08	51.02	OK
1335	2026-09-19 17:09	49.28	OK	1335	2026-09-19 17:10	49.91	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
13357	2026-09-19 17:11	51.47	OK	13358	2026-09-19 17:12	50.86	OK
13359	2026-09-19 17:13	52.30	OK	13360	2026-09-19 17:14	51.08	OK
13361	2026-09-19 17:15	49.58	OK	13362	2026-09-19 17:16	50.45	OK
13363	2026-09-19 17:17	50.98	OK	13364	2026-09-19 17:18	50.14	OK
13365	2026-09-19 17:19	50.13	OK	13366	2026-09-19 17:20	52.24	OK
13367	2026-09-19 17:21	51.36	OK	13368	2026-09-19 17:22	49.44	OK
13369	2026-09-19 17:23	50.99	OK	13370	2026-09-19 17:24	51.04	OK
13371	2026-09-19 17:25	49.02	OK	13372	2026-09-19 17:26	51.29	OK
13373	2026-09-19 17:27	49.07	OK	13374	2026-09-19 17:28	50.01	OK
13375	2026-09-19 17:29	50.63	OK	13376	2026-09-19 17:30	50.40	OK
13377	2026-09-19 17:31	49.76	OK	13378	2026-09-19 17:32	49.06	OK
13379	2026-09-19 17:33	49.48	OK	13380	2026-09-19 17:34	50.95	OK
13381	2026-09-19 17:35	49.76	OK	13382	2026-09-19 17:36	49.52	OK
13383	2026-09-19 17:37	50.82	OK	13384	2026-09-19 17:38	51.96	OK
13385	2026-09-19 17:39	50.86	OK	13386	2026-09-19 17:40	48.86	OK
13387	2026-09-19 17:41	49.93	OK	13388	2026-09-19 17:42	47.71	OK
13389	2026-09-19 17:43	50.77	OK	13390	2026-09-19 17:44	48.86	OK
13391	2026-09-19 17:45	50.37	OK	13392	2026-09-19 17:46	50.10	OK
13393	2026-09-19 17:47	49.97	OK	13394	2026-09-19 17:48	50.63	OK
13395	2026-09-19 17:49	50.80	OK	13396	2026-09-19 17:50	48.82	OK
13397	2026-09-19 17:51	49.90	OK	13398	2026-09-19 17:52	50.16	OK
13399	2026-09-19 17:53	49.59	OK	13400	2026-09-19 17:54	47.85	OK
13401	2026-09-19 17:55	49.84	OK	13402	2026-09-19 17:56	49.20	OK
13403	2026-09-19 17:57	48.99	OK	13404	2026-09-19 17:58	50.63	OK
13405	2026-09-19 17:59	48.22	OK	13406	2026-09-19 18:00	48.47	OK
13407	2026-09-19 18:01	49.55	OK	13408	2026-09-19 18:02	50.34	OK
13409	2026-09-19 18:03	49.57	OK	13410	2026-09-19 18:04	50.91	OK
13411	2026-09-19 18:05	49.17	OK	13412	2026-09-19 18:06	50.43	OK
13413	2026-09-19 18:07	49.59	OK	13414	2026-09-19 18:08	49.22	OK
1341	2026-09-19 18:09	49.45	OK	1341	2026-09-19 18:10	50.67	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
13417	2026-09-19 18:11	49.87	OK	13418	2026-09-19 18:12	49.10	OK
13419	2026-09-19 18:13	50.85	OK	13420	2026-09-19 18:14	49.67	OK
13421	2026-09-19 18:15	48.43	OK	13422	2026-09-19 18:16	49.94	OK
13423	2026-09-19 18:17	47.28	OK	13424	2026-09-19 18:18	48.92	OK
13425	2026-09-19 18:19	49.22	OK	13426	2026-09-19 18:20	47.98	OK
13427	2026-09-19 18:21	50.45	OK	13428	2026-09-19 18:22	49.24	OK
13429	2026-09-19 18:23	50.60	OK	13430	2026-09-19 18:24	48.33	OK
13431	2026-09-19 18:25	48.88	OK	13432	2026-09-19 18:26	50.22	OK
13433	2026-09-19 18:27	48.20	OK	13434	2026-09-19 18:28	49.58	OK
13435	2026-09-19 18:29	50.27	OK	13436	2026-09-19 18:30	49.30	OK
13437	2026-09-19 18:31	49.33	OK	13438	2026-09-19 18:32	50.66	OK
13439	2026-09-19 18:33	51.51	OK	13440	2026-09-19 18:34	49.99	OK
13441	2026-09-19 18:35	49.43	OK	13442	2026-09-19 18:36	48.67	OK
13443	2026-09-19 18:37	50.06	OK	13444	2026-09-19 18:38	48.90	OK
13445	2026-09-19 18:39	49.42	OK	13446	2026-09-19 18:40	48.21	OK
13447	2026-09-19 18:41	49.35	OK	13448	2026-09-19 18:42	47.79	OK
13449	2026-09-19 18:43	48.24	OK	13450	2026-09-19 18:44	49.49	OK
13451	2026-09-19 18:45	48.14	OK	13452	2026-09-19 18:46	51.21	OK
13453	2026-09-19 18:47	48.02	OK	13454	2026-09-19 18:48	48.36	OK
13455	2026-09-19 18:49	50.45	OK	13456	2026-09-19 18:50	50.27	OK
13457	2026-09-19 18:51	48.18	OK	13458	2026-09-19 18:52	49.36	OK
13459	2026-09-19 18:53	50.69	OK	13460	2026-09-19 18:54	50.01	OK
13461	2026-09-19 18:55	47.96	OK	13462	2026-09-19 18:56	50.10	OK
13463	2026-09-19 18:57	48.37	OK	13464	2026-09-19 18:58	50.04	OK
13465	2026-09-19 18:59	48.37	OK	13466	2026-09-19 19:00	50.76	OK
13467	2026-09-19 19:01	49.90	OK	13468	2026-09-19 19:02	49.24	OK
13469	2026-09-19 19:03	47.28	OK	13470	2026-09-19 19:04	48.63	OK
13471	2026-09-19 19:05	48.94	OK	13472	2026-09-19 19:06	49.24	OK
13473	2026-09-19 19:07	50.34	OK	13474	2026-09-19 19:08	49.90	OK
1347	2026-09-19 19:09	49.68	OK	1347	2026-09-19 19:10	49.27	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
13477	2026-09-19 19:11	48.44	OK	13478	2026-09-19 19:12	49.37	OK
13479	2026-09-19 19:13	47.68	OK	13480	2026-09-19 19:14	48.67	OK
13481	2026-09-19 19:15	47.79	OK	13482	2026-09-19 19:16	49.89	OK
13483	2026-09-19 19:17	49.88	OK	13484	2026-09-19 19:18	48.71	OK
13485	2026-09-19 19:19	48.11	OK	13486	2026-09-19 19:20	49.59	OK
13487	2026-09-19 19:21	48.14	OK	13488	2026-09-19 19:22	47.31	OK
13489	2026-09-19 19:23	49.27	OK	13490	2026-09-19 19:24	47.72	OK
13491	2026-09-19 19:25	47.87	OK	13492	2026-09-19 19:26	48.79	OK
13493	2026-09-19 19:27	48.87	OK	13494	2026-09-19 19:28	48.95	OK
13495	2026-09-19 19:29	47.94	OK	13496	2026-09-19 19:30	47.66	OK
13497	2026-09-19 19:31	47.76	OK	13498	2026-09-19 19:32	47.30	OK
13499	2026-09-19 19:33	47.68	OK	13500	2026-09-19 19:34	46.55	OK
13501	2026-09-19 19:35	47.50	OK	13502	2026-09-19 19:36	47.08	OK
13503	2026-09-19 19:37	49.40	OK	13504	2026-09-19 19:38	49.46	OK
13505	2026-09-19 19:39	47.25	OK	13506	2026-09-19 19:40	46.38	OK
13507	2026-09-19 19:41	48.68	OK	13508	2026-09-19 19:42	48.19	OK
13509	2026-09-19 19:43	48.59	OK	13510	2026-09-19 19:44	49.43	OK
13511	2026-09-19 19:45	47.23	OK	13512	2026-09-19 19:46	47.33	OK
13513	2026-09-19 19:47	48.25	OK	13514	2026-09-19 19:48	48.75	OK
13515	2026-09-19 19:49	46.97	OK	13516	2026-09-19 19:50	47.67	OK
13517	2026-09-19 19:51	49.15	OK	13518	2026-09-19 19:52	48.40	OK
13519	2026-09-19 19:53	48.62	OK	13520	2026-09-19 19:54	49.50	OK
13521	2026-09-19 19:55	48.59	OK	13522	2026-09-19 19:56	47.63	OK
13523	2026-09-19 19:57	48.44	OK	13524	2026-09-19 19:58	49.90	OK
13525	2026-09-19 19:59	48.80	OK	13526	2026-09-19 20:00	48.37	OK
13527	2026-09-19 20:01	49.56	OK	13528	2026-09-19 20:02	48.32	OK
13529	2026-09-19 20:03	50.87	OK	13530	2026-09-19 20:04	46.84	OK
13531	2026-09-19 20:05	47.84	OK	13532	2026-09-19 20:06	48.97	OK
13533	2026-09-19 20:07	47.75	OK	13534	2026-09-19 20:08	47.68	OK
1353	2026-09-19 20:09	47.95	OK	1353	2026-09-19 20:10	48.10	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
13537	2026-09-19 20:11	49.44	OK	13538	2026-09-19 20:12	47.76	OK
13539	2026-09-19 20:13	48.32	OK	13540	2026-09-19 20:14	49.17	OK
13541	2026-09-19 20:15	48.22	OK	13542	2026-09-19 20:16	48.46	OK
13543	2026-09-19 20:17	46.16	OK	13544	2026-09-19 20:18	48.75	OK
13545	2026-09-19 20:19	46.28	OK	13546	2026-09-19 20:20	48.41	OK
13547	2026-09-19 20:21	48.74	OK	13548	2026-09-19 20:22	48.27	OK
13549	2026-09-19 20:23	46.29	OK	13550	2026-09-19 20:24	47.27	OK
13551	2026-09-19 20:25	48.13	OK	13552	2026-09-19 20:26	47.23	OK
13553	2026-09-19 20:27	46.51	OK	13554	2026-09-19 20:28	46.87	OK
13555	2026-09-19 20:29	46.84	OK	13556	2026-09-19 20:30	46.93	OK
13557	2026-09-19 20:31	46.70	OK	13558	2026-09-19 20:32	47.47	OK
13559	2026-09-19 20:33	48.01	OK	13560	2026-09-19 20:34	46.69	OK
13561	2026-09-19 20:35	48.19	OK	13562	2026-09-19 20:36	48.18	OK
13563	2026-09-19 20:37	46.36	OK	13564	2026-09-19 20:38	47.35	OK
13565	2026-09-19 20:39	49.28	OK	13566	2026-09-19 20:40	48.14	OK
13567	2026-09-19 20:41	48.03	OK	13568	2026-09-19 20:42	48.87	OK
13569	2026-09-19 20:43	49.31	OK	13570	2026-09-19 20:44	45.89	OK
13571	2026-09-19 20:45	50.07	OK	13572	2026-09-19 20:46	45.51	OK
13573	2026-09-19 20:47	46.39	OK	13574	2026-09-19 20:48	47.33	OK
13575	2026-09-19 20:49	49.56	OK	13576	2026-09-19 20:50	47.34	OK
13577	2026-09-19 20:51	48.50	OK	13578	2026-09-19 20:52	47.13	OK
13579	2026-09-19 20:53	46.22	OK	13580	2026-09-19 20:54	46.89	OK
13581	2026-09-19 20:55	48.69	OK	13582	2026-09-19 20:56	48.29	OK
13583	2026-09-19 20:57	47.32	OK	13584	2026-09-19 20:58	48.19	OK
13585	2026-09-19 20:59	47.14	OK	13586	2026-09-19 21:00	47.11	OK
13587	2026-09-19 21:01	47.52	OK	13588	2026-09-19 21:02	48.07	OK
13589	2026-09-19 21:03	47.90	OK	13590	2026-09-19 21:04	47.43	OK
13591	2026-09-19 21:05	47.12	OK	13592	2026-09-19 21:06	46.90	OK
13593	2026-09-19 21:07	47.79	OK	13594	2026-09-19 21:08	46.20	OK
1359	2026-09-19 21:09	47.18	OK	1359	2026-09-19 21:10	48.41	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
13597	2026-09-19 21:11	47.87	OK	13598	2026-09-19 21:12	46.14	OK
13599	2026-09-19 21:13	44.86	OK	13600	2026-09-19 21:14	46.03	OK
13601	2026-09-19 21:15	47.15	OK	13602	2026-09-19 21:16	46.58	OK
13603	2026-09-19 21:17	48.27	OK	13604	2026-09-19 21:18	48.08	OK
13605	2026-09-19 21:19	46.67	OK	13606	2026-09-19 21:20	46.53	OK
13607	2026-09-19 21:21	45.94	OK	13608	2026-09-19 21:22	47.45	OK
13609	2026-09-19 21:23	47.54	OK	13610	2026-09-19 21:24	46.09	OK
13611	2026-09-19 21:25	46.05	OK	13612	2026-09-19 21:26	47.94	OK
13613	2026-09-19 21:27	46.44	OK	13614	2026-09-19 21:28	45.36	OK
13615	2026-09-19 21:29	47.03	OK	13616	2026-09-19 21:30	47.95	OK
13617	2026-09-19 21:31	48.33	OK	13618	2026-09-19 21:32	46.36	OK
13619	2026-09-19 21:33	45.12	OK	13620	2026-09-19 21:34	48.66	OK
13621	2026-09-19 21:35	45.88	OK	13622	2026-09-19 21:36	45.18	OK
13623	2026-09-19 21:37	47.11	OK	13624	2026-09-19 21:38	47.16	OK
13625	2026-09-19 21:39	45.15	OK	13626	2026-09-19 21:40	47.88	OK
13627	2026-09-19 21:41	47.36	OK	13628	2026-09-19 21:42	48.51	OK
13629	2026-09-19 21:43	47.43	OK	13630	2026-09-19 21:44	47.62	OK
13631	2026-09-19 21:45	45.67	OK	13632	2026-09-19 21:46	48.98	OK
13633	2026-09-19 21:47	45.48	OK	13634	2026-09-19 21:48	46.54	OK
13635	2026-09-19 21:49	47.13	OK	13636	2026-09-19 21:50	46.46	OK
13637	2026-09-19 21:51	44.53	OK	13638	2026-09-19 21:52	47.62	OK
13639	2026-09-19 21:53	48.63	OK	13640	2026-09-19 21:54	47.61	OK
13641	2026-09-19 21:55	48.76	OK	13642	2026-09-19 21:56	48.06	OK
13643	2026-09-19 21:57	44.03	OK	13644	2026-09-19 21:58	46.44	OK
13645	2026-09-19 21:59	46.63	OK	13646	2026-09-19 22:00	48.75	OK
13647	2026-09-19 22:01	45.44	OK	13648	2026-09-19 22:02	45.72	OK
13649	2026-09-19 22:03	46.76	OK	13650	2026-09-19 22:04	46.70	OK
13651	2026-09-19 22:05	46.09	OK	13652	2026-09-19 22:06	48.41	OK
13653	2026-09-19 22:07	44.66	OK	13654	2026-09-19 22:08	46.54	OK
1365	2026-09-19 22:09	48.01	OK	1365	2026-09-19 22:10	46.72	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
13657	2026-09-19 22:11	47.28	OK	13658	2026-09-19 22:12	47.15	OK
13659	2026-09-19 22:13	46.03	OK	13660	2026-09-19 22:14	45.34	OK
13661	2026-09-19 22:15	44.82	OK	13662	2026-09-19 22:16	46.02	OK
13663	2026-09-19 22:17	47.80	OK	13664	2026-09-19 22:18	46.59	OK
13665	2026-09-19 22:19	46.08	OK	13666	2026-09-19 22:20	46.67	OK
13667	2026-09-19 22:21	46.02	OK	13668	2026-09-19 22:22	47.25	OK
13669	2026-09-19 22:23	47.14	OK	13670	2026-09-19 22:24	46.34	OK
13671	2026-09-19 22:25	46.22	OK	13672	2026-09-19 22:26	45.54	OK
13673	2026-09-19 22:27	46.42	OK	13674	2026-09-19 22:28	47.70	OK
13675	2026-09-19 22:29	44.70	OK	13676	2026-09-19 22:30	45.64	OK
13677	2026-09-19 22:31	44.75	OK	13678	2026-09-19 22:32	47.21	OK
13679	2026-09-19 22:33	44.77	OK	13680	2026-09-19 22:34	45.79	OK
13681	2026-09-19 22:35	47.91	OK	13682	2026-09-19 22:36	44.82	OK
13683	2026-09-19 22:37	45.72	OK	13684	2026-09-19 22:38	45.39	OK
13685	2026-09-19 22:39	46.84	OK	13686	2026-09-19 22:40	47.01	OK
13687	2026-09-19 22:41	46.27	OK	13688	2026-09-19 22:42	46.93	OK
13689	2026-09-19 22:43	46.91	OK	13690	2026-09-19 22:44	46.37	OK
13691	2026-09-19 22:45	47.11	OK	13692	2026-09-19 22:46	46.13	OK
13693	2026-09-19 22:47	46.13	OK	13694	2026-09-19 22:48	46.26	OK
13695	2026-09-19 22:49	45.14	OK	13696	2026-09-19 22:50	44.65	OK
13697	2026-09-19 22:51	46.39	OK	13698	2026-09-19 22:52	45.11	OK
13699	2026-09-19 22:53	47.07	OK	13700	2026-09-19 22:54	46.74	OK
13701	2026-09-19 22:55	46.23	OK	13702	2026-09-19 22:56	46.93	OK
13703	2026-09-19 22:57	46.30	OK	13704	2026-09-19 22:58	45.37	OK
13705	2026-09-19 22:59	45.24	OK	13706	2026-09-19 23:00	44.94	OK
13707	2026-09-19 23:01	46.51	OK	13708	2026-09-19 23:02	47.14	OK
13709	2026-09-19 23:03	45.01	OK	13710	2026-09-19 23:04	44.71	OK
13711	2026-09-19 23:05	45.54	OK	13712	2026-09-19 23:06	45.33	OK
13713	2026-09-19 23:07	44.44	OK	13714	2026-09-19 23:08	45.88	OK
1371	2026-09-19 23:09	43.96	OK	1371	2026-09-19 23:10	44.38	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
13717	2026-09-19 23:11	46.19	OK	13718	2026-09-19 23:12	44.80	OK
13719	2026-09-19 23:13	46.65	OK	13720	2026-09-19 23:14	46.46	OK
13721	2026-09-19 23:15	45.60	OK	13722	2026-09-19 23:16	46.09	OK
13723	2026-09-19 23:17	47.00	OK	13724	2026-09-19 23:18	44.94	OK
13725	2026-09-19 23:19	45.39	OK	13726	2026-09-19 23:20	47.56	OK
13727	2026-09-19 23:21	45.44	OK	13728	2026-09-19 23:22	46.19	OK
13729	2026-09-19 23:23	45.56	OK	13730	2026-09-19 23:24	47.05	OK
13731	2026-09-19 23:25	44.82	OK	13732	2026-09-19 23:26	45.46	OK
13733	2026-09-19 23:27	44.94	OK	13734	2026-09-19 23:28	46.07	OK
13735	2026-09-19 23:29	45.40	OK	13736	2026-09-19 23:30	45.84	OK
13737	2026-09-19 23:31	43.46	OK	13738	2026-09-19 23:32	43.61	OK
13739	2026-09-19 23:33	46.06	OK	13740	2026-09-19 23:34	45.60	OK
13741	2026-09-19 23:35	45.64	OK	13742	2026-09-19 23:36	47.26	OK
13743	2026-09-19 23:37	44.71	OK	13744	2026-09-19 23:38	45.00	OK
13745	2026-09-19 23:39	46.16	OK	13746	2026-09-19 23:40	46.41	OK
13747	2026-09-19 23:41	46.09	OK	13748	2026-09-19 23:42	45.65	OK
13749	2026-09-19 23:43	43.35	OK	13750	2026-09-19 23:44	44.54	OK
13751	2026-09-19 23:45	46.21	OK	13752	2026-09-19 23:46	44.93	OK
13753	2026-09-19 23:47	44.77	OK	13754	2026-09-19 23:48	46.67	OK
13755	2026-09-19 23:49	45.37	OK	13756	2026-09-19 23:50	46.97	OK
13757	2026-09-19 23:51	46.64	OK	13758	2026-09-19 23:52	46.41	OK
13759	2026-09-19 23:53	46.81	OK	13760	2026-09-19 23:54	45.37	OK
13761	2026-09-19 23:55	44.64	OK	13762	2026-09-19 23:56	44.69	OK
13763	2026-09-19 23:57	46.03	OK	13764	2026-09-19 23:58	45.51	OK
13765	2026-09-19 23:59	46.46	OK	13766	2026-09-20 00:00	43.78	OK
13767	2026-09-20 00:01	44.51	OK	13768	2026-09-20 00:02	45.79	OK
13769	2026-09-20 00:03	45.69	OK	13770	2026-09-20 00:04	45.65	OK
13771	2026-09-20 00:05	45.60	OK	13772	2026-09-20 00:06	47.12	OK
13773	2026-09-20 00:07	44.50	OK	13774	2026-09-20 00:08	43.86	OK
1377	2026-09-20 00:09	46.05	OK	1377	2026-09-20 00:10	46.51	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
13777	2026-09-20 00:11	45.68	OK	13778	2026-09-20 00:12	45.11	OK
13779	2026-09-20 00:13	44.88	OK	13780	2026-09-20 00:14	44.22	OK
13781	2026-09-20 00:15	44.36	OK	13782	2026-09-20 00:16	47.33	OK
13783	2026-09-20 00:17	46.08	OK	13784	2026-09-20 00:18	46.09	OK
13785	2026-09-20 00:19	44.25	OK	13786	2026-09-20 00:20	46.36	OK
13787	2026-09-20 00:21	45.66	OK	13788	2026-09-20 00:22	46.07	OK
13789	2026-09-20 00:23	44.58	OK	13790	2026-09-20 00:24	46.05	OK
13791	2026-09-20 00:25	46.38	OK	13792	2026-09-20 00:26	43.95	OK
13793	2026-09-20 00:27	43.92	OK	13794	2026-09-20 00:28	45.00	OK
13795	2026-09-20 00:29	45.50	OK	13796	2026-09-20 00:30	45.50	OK
13797	2026-09-20 00:31	46.35	OK	13798	2026-09-20 00:32	47.14	OK
13799	2026-09-20 00:33	45.24	OK	13800	2026-09-20 00:34	46.16	OK
13801	2026-09-20 00:35	45.77	OK	13802	2026-09-20 00:36	44.66	OK
13803	2026-09-20 00:37	47.44	OK	13804	2026-09-20 00:38	46.15	OK
13805	2026-09-20 00:39	45.51	OK	13806	2026-09-20 00:40	44.03	OK
13807	2026-09-20 00:41	45.05	OK	13808	2026-09-20 00:42	43.21	OK
13809	2026-09-20 00:43	45.51	OK	13810	2026-09-20 00:44	45.78	OK
13811	2026-09-20 00:45	43.10	OK	13812	2026-09-20 00:46	45.44	OK
13813	2026-09-20 00:47	45.95	OK	13814	2026-09-20 00:48	45.12	OK
13815	2026-09-20 00:49	45.92	OK	13816	2026-09-20 00:50	44.37	OK
13817	2026-09-20 00:51	45.11	OK	13818	2026-09-20 00:52	46.11	OK
13819	2026-09-20 00:53	44.65	OK	13820	2026-09-20 00:54	44.59	OK
13821	2026-09-20 00:55	46.72	OK	13822	2026-09-20 00:56	45.17	OK
13823	2026-09-20 00:57	46.20	OK	13824	2026-09-20 00:58	47.16	OK
13825	2026-09-20 00:59	44.59	OK	13826	2026-09-20 01:00	45.12	OK
13827	2026-09-20 01:01	46.35	OK	13828	2026-09-20 01:02	46.84	OK
13829	2026-09-20 01:03	45.72	OK	13830	2026-09-20 01:04	45.34	OK
13831	2026-09-20 01:05	45.40	OK	13832	2026-09-20 01:06	46.74	OK
13833	2026-09-20 01:07	44.21	OK	13834	2026-09-20 01:08	45.35	OK
1383	2026-09-20 01:09	44.71	OK	1383	2026-09-20 01:10	43.92	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
13837	2026-09-20 01:11	44.54	OK	13838	2026-09-20 01:12	47.54	OK
13839	2026-09-20 01:13	44.69	OK	13840	2026-09-20 01:14	44.73	OK
13841	2026-09-20 01:15	43.76	OK	13842	2026-09-20 01:16	46.83	OK
13843	2026-09-20 01:17	44.70	OK	13844	2026-09-20 01:18	45.72	OK
13845	2026-09-20 01:19	45.51	OK	13846	2026-09-20 01:20	44.27	OK
13847	2026-09-20 01:21	45.79	OK	13848	2026-09-20 01:22	45.47	OK
13849	2026-09-20 01:23	46.14	OK	13850	2026-09-20 01:24	43.11	OK
13851	2026-09-20 01:25	45.29	OK	13852	2026-09-20 01:26	43.82	OK
13853	2026-09-20 01:27	44.29	OK	13854	2026-09-20 01:28	45.72	OK
13855	2026-09-20 01:29	45.73	OK	13856	2026-09-20 01:30	44.34	OK
13857	2026-09-20 01:31	44.00	OK	13858	2026-09-20 01:32	43.96	OK
13859	2026-09-20 01:33	45.00	OK	13860	2026-09-20 01:34	44.16	OK
13861	2026-09-20 01:35	45.40	OK	13862	2026-09-20 01:36	44.60	OK
13863	2026-09-20 01:37	44.85	OK	13864	2026-09-20 01:38	44.68	OK
13865	2026-09-20 01:39	46.81	OK	13866	2026-09-20 01:40	44.56	OK
13867	2026-09-20 01:41	45.30	OK	13868	2026-09-20 01:42	43.35	OK
13869	2026-09-20 01:43	44.67	OK	13870	2026-09-20 01:44	45.10	OK
13871	2026-09-20 01:45	47.01	OK	13872	2026-09-20 01:46	46.28	OK
13873	2026-09-20 01:47	43.43	OK	13874	2026-09-20 01:48	46.77	OK
13875	2026-09-20 01:49	45.17	OK	13876	2026-09-20 01:50	43.89	OK
13877	2026-09-20 01:51	44.56	OK	13878	2026-09-20 01:52	43.95	OK
13879	2026-09-20 01:53	44.93	OK	13880	2026-09-20 01:54	43.82	OK
13881	2026-09-20 01:55	45.87	OK	13882	2026-09-20 01:56	44.73	OK
13883	2026-09-20 01:57	44.99	OK	13884	2026-09-20 01:58	44.97	OK
13885	2026-09-20 01:59	44.35	OK	13886	2026-09-20 02:00	45.35	OK
13887	2026-09-20 02:01	43.52	OK	13888	2026-09-20 02:02	43.35	OK
13889	2026-09-20 02:03	45.27	OK	13890	2026-09-20 02:04	44.35	OK
13891	2026-09-20 02:05	43.73	OK	13892	2026-09-20 02:06	46.43	OK
13893	2026-09-20 02:07	44.18	OK	13894	2026-09-20 02:08	45.25	OK
1389	2026-09-20 02:09	46.55	OK	1389	2026-09-20 02:10	44.25	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
13897	2026-09-20 02:11	45.68	OK	13898	2026-09-20 02:12	46.72	OK
13899	2026-09-20 02:13	46.27	OK	13900	2026-09-20 02:14	45.20	OK
13901	2026-09-20 02:15	45.86	OK	13902	2026-09-20 02:16	44.98	OK
13903	2026-09-20 02:17	44.44	OK	13904	2026-09-20 02:18	45.03	OK
13905	2026-09-20 02:19	45.84	OK	13906	2026-09-20 02:20	45.80	OK
13907	2026-09-20 02:21	47.56	OK	13908	2026-09-20 02:22	44.98	OK
13909	2026-09-20 02:23	45.15	OK	13910	2026-09-20 02:24	44.83	OK
13911	2026-09-20 02:25	43.87	OK	13912	2026-09-20 02:26	44.12	OK
13913	2026-09-20 02:27	44.70	OK	13914	2026-09-20 02:28	45.52	OK
13915	2026-09-20 02:29	44.38	OK	13916	2026-09-20 02:30	44.52	OK
13917	2026-09-20 02:31	47.42	OK	13918	2026-09-20 02:32	44.96	OK
13919	2026-09-20 02:33	44.89	OK	13920	2026-09-20 02:34	44.62	OK
13921	2026-09-20 02:35	44.74	OK	13922	2026-09-20 02:36	44.63	OK
13923	2026-09-20 02:37	46.60	OK	13924	2026-09-20 02:38	46.68	OK
13925	2026-09-20 02:39	44.33	OK	13926	2026-09-20 02:40	45.16	OK
13927	2026-09-20 02:41	45.27	OK	13928	2026-09-20 02:42	45.83	OK
13929	2026-09-20 02:43	44.24	OK	13930	2026-09-20 02:44	43.85	OK
13931	2026-09-20 02:45	44.72	OK	13932	2026-09-20 02:46	46.72	OK
13933	2026-09-20 02:47	46.34	OK	13934	2026-09-20 02:48	46.81	OK
13935	2026-09-20 02:49	45.02	OK	13936	2026-09-20 02:50	45.46	OK
13937	2026-09-20 02:51	46.38	OK	13938	2026-09-20 02:52	44.84	OK
13939	2026-09-20 02:53	44.46	OK	13940	2026-09-20 02:54	47.34	OK
13941	2026-09-20 02:55	45.55	OK	13942	2026-09-20 02:56	45.41	OK
13943	2026-09-20 02:57	44.36	OK	13944	2026-09-20 02:58	44.92	OK
13945	2026-09-20 02:59	46.85	OK	13946	2026-09-20 03:00	45.46	OK
13947	2026-09-20 03:01	47.06	OK	13948	2026-09-20 03:02	43.36	OK
13949	2026-09-20 03:03	47.00	OK	13950	2026-09-20 03:04	46.29	OK
13951	2026-09-20 03:05	45.30	OK	13952	2026-09-20 03:06	45.76	OK
13953	2026-09-20 03:07	43.86	OK	13954	2026-09-20 03:08	45.27	OK
1395	2026-09-20 03:09	45.79	OK	1395	2026-09-20 03:10	46.33	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
13957	2026-09-20 03:11	46.80	OK	13958	2026-09-20 03:12	44.34	OK
13959	2026-09-20 03:13	46.01	OK	13960	2026-09-20 03:14	46.16	OK
13961	2026-09-20 03:15	45.03	OK	13962	2026-09-20 03:16	45.42	OK
13963	2026-09-20 03:17	44.78	OK	13964	2026-09-20 03:18	44.67	OK
13965	2026-09-20 03:19	43.85	OK	13966	2026-09-20 03:20	45.74	OK
13967	2026-09-20 03:21	46.26	OK	13968	2026-09-20 03:22	44.97	OK
13969	2026-09-20 03:23	43.86	OK	13970	2026-09-20 03:24	44.22	OK
13971	2026-09-20 03:25	46.32	OK	13972	2026-09-20 03:26	46.91	OK
13973	2026-09-20 03:27	45.99	OK	13974	2026-09-20 03:28	48.17	OK
13975	2026-09-20 03:29	45.34	OK	13976	2026-09-20 03:30	44.86	OK
13977	2026-09-20 03:31	44.40	OK	13978	2026-09-20 03:32	46.97	OK
13979	2026-09-20 03:33	46.69	OK	13980	2026-09-20 03:34	46.27	OK
13981	2026-09-20 03:35	46.03	OK	13982	2026-09-20 03:36	44.50	OK
13983	2026-09-20 03:37	46.84	OK	13984	2026-09-20 03:38	44.52	OK
13985	2026-09-20 03:39	45.48	OK	13986	2026-09-20 03:40	45.50	OK
13987	2026-09-20 03:41	45.39	OK	13988	2026-09-20 03:42	45.87	OK
13989	2026-09-20 03:43	44.64	OK	13990	2026-09-20 03:44	46.48	OK
13991	2026-09-20 03:45	46.24	OK	13992	2026-09-20 03:46	45.97	OK
13993	2026-09-20 03:47	45.87	OK	13994	2026-09-20 03:48	46.55	OK
13995	2026-09-20 03:49	47.22	OK	13996	2026-09-20 03:50	45.15	OK
13997	2026-09-20 03:51	46.79	OK	13998	2026-09-20 03:52	45.38	OK
13999	2026-09-20 03:53	46.05	OK	14000	2026-09-20 03:54	47.49	OK
14001	2026-09-20 03:55	47.30	OK	14002	2026-09-20 03:56	46.41	OK
14003	2026-09-20 03:57	46.25	OK	14004	2026-09-20 03:58	45.02	OK
14005	2026-09-20 03:59	46.70	OK	14006	2026-09-20 04:00	46.30	OK
14007	2026-09-20 04:01	47.10	OK	14008	2026-09-20 04:02	45.97	OK
14009	2026-09-20 04:03	47.04	OK	14010	2026-09-20 04:04	44.58	OK
14011	2026-09-20 04:05	45.84	OK	14012	2026-09-20 04:06	46.14	OK
14013	2026-09-20 04:07	44.50	OK	14014	2026-09-20 04:08	43.89	OK
1401	2026-09-20 04:09	46.59	OK	1401	2026-09-20 04:10	45.21	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
14017	2026-09-20 04:11	45.75	OK	14018	2026-09-20 04:12	47.23	OK
14019	2026-09-20 04:13	46.13	OK	14020	2026-09-20 04:14	45.28	OK
14021	2026-09-20 04:15	47.43	OK	14022	2026-09-20 04:16	45.19	OK
14023	2026-09-20 04:17	45.29	OK	14024	2026-09-20 04:18	43.66	OK
14025	2026-09-20 04:19	45.65	OK	14026	2026-09-20 04:20	45.45	OK
14027	2026-09-20 04:21	46.78	OK	14028	2026-09-20 04:22	44.74	OK
14029	2026-09-20 04:23	46.58	OK	14030	2026-09-20 04:24	45.98	OK
14031	2026-09-20 04:25	47.59	OK	14032	2026-09-20 04:26	46.85	OK
14033	2026-09-20 04:27	43.66	OK	14034	2026-09-20 04:28	45.51	OK
14035	2026-09-20 04:29	44.98	OK	14036	2026-09-20 04:30	46.81	OK
14037	2026-09-20 04:31	44.98	OK	14038	2026-09-20 04:32	45.97	OK
14039	2026-09-20 04:33	47.15	OK	14040	2026-09-20 04:34	47.49	OK
14041	2026-09-20 04:35	44.49	OK	14042	2026-09-20 04:36	45.56	OK
14043	2026-09-20 04:37	46.70	OK	14044	2026-09-20 04:38	45.95	OK
14045	2026-09-20 04:39	44.98	OK	14046	2026-09-20 04:40	45.59	OK
14047	2026-09-20 04:41	46.40	OK	14048	2026-09-20 04:42	46.73	OK
14049	2026-09-20 04:43	45.26	OK	14050	2026-09-20 04:44	46.56	OK
14051	2026-09-20 04:45	47.43	OK	14052	2026-09-20 04:46	44.64	OK
14053	2026-09-20 04:47	45.96	OK	14054	2026-09-20 04:48	46.82	OK
14055	2026-09-20 04:49	46.46	OK	14056	2026-09-20 04:50	47.32	OK
14057	2026-09-20 04:51	45.88	OK	14058	2026-09-20 04:52	46.92	OK
14059	2026-09-20 04:53	45.93	OK	14060	2026-09-20 04:54	46.22	OK
14061	2026-09-20 04:55	46.67	OK	14062	2026-09-20 04:56	45.47	OK
14063	2026-09-20 04:57	45.52	OK	14064	2026-09-20 04:58	48.77	OK
14065	2026-09-20 04:59	47.57	OK	14066	2026-09-20 05:00	48.29	OK
14067	2026-09-20 05:01	46.60	OK	14068	2026-09-20 05:02	46.16	OK
14069	2026-09-20 05:03	47.08	OK	14070	2026-09-20 05:04	45.79	OK
14071	2026-09-20 05:05	45.88	OK	14072	2026-09-20 05:06	46.23	OK
14073	2026-09-20 05:07	47.07	OK	14074	2026-09-20 05:08	46.70	OK
1407	2026-09-20 05:09	47.63	OK	1407	2026-09-20 05:10	47.80	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
14077	2026-09-20 05:11	46.51	OK	14078	2026-09-20 05:12	47.56	OK
14079	2026-09-20 05:13	46.38	OK	14080	2026-09-20 05:14	47.17	OK
14081	2026-09-20 05:15	48.16	OK	14082	2026-09-20 05:16	47.43	OK
14083	2026-09-20 05:17	48.19	OK	14084	2026-09-20 05:18	44.89	OK
14085	2026-09-20 05:19	45.98	OK	14086	2026-09-20 05:20	48.17	OK
14087	2026-09-20 05:21	46.55	OK	14088	2026-09-20 05:22	45.27	OK
14089	2026-09-20 05:23	47.28	OK	14090	2026-09-20 05:24	47.32	OK
14091	2026-09-20 05:25	48.77	OK	14092	2026-09-20 05:26	48.26	OK
14093	2026-09-20 05:27	44.34	OK	14094	2026-09-20 05:28	45.90	OK
14095	2026-09-20 05:29	46.28	OK	14096	2026-09-20 05:30	48.17	OK
14097	2026-09-20 05:31	46.61	OK	14098	2026-09-20 05:32	47.13	OK
14099	2026-09-20 05:33	46.51	OK	14100	2026-09-20 05:34	46.77	OK
14101	2026-09-20 05:35	48.04	OK	14102	2026-09-20 05:36	45.45	OK
14103	2026-09-20 05:37	44.69	OK	14104	2026-09-20 05:38	47.12	OK
14105	2026-09-20 05:39	48.47	OK	14106	2026-09-20 05:40	48.34	OK
14107	2026-09-20 05:41	44.76	OK	14108	2026-09-20 05:42	48.28	OK
14109	2026-09-20 05:43	46.59	OK	14110	2026-09-20 05:44	47.15	OK
14111	2026-09-20 05:45	46.52	OK	14112	2026-09-20 05:46	46.16	OK
14113	2026-09-20 05:47	48.19	OK	14114	2026-09-20 05:48	47.00	OK
14115	2026-09-20 05:49	47.89	OK	14116	2026-09-20 05:50	47.01	OK
14117	2026-09-20 05:51	46.81	OK	14118	2026-09-20 05:52	47.05	OK
14119	2026-09-20 05:53	49.05	OK	14120	2026-09-20 05:54	45.74	OK
14121	2026-09-20 05:55	46.33	OK	14122	2026-09-20 05:56	47.58	OK
14123	2026-09-20 05:57	47.37	OK	14124	2026-09-20 05:58	46.52	OK
14125	2026-09-20 05:59	48.03	OK	14126	2026-09-20 06:00	47.52	OK
14127	2026-09-20 06:01	47.09	OK	14128	2026-09-20 06:02	47.18	OK
14129	2026-09-20 06:03	46.99	OK	14130	2026-09-20 06:04	48.11	OK
14131	2026-09-20 06:05	47.24	OK	14132	2026-09-20 06:06	48.40	OK
14133	2026-09-20 06:07	47.08	OK	14134	2026-09-20 06:08	48.35	OK
1413	2026-09-20 06:09	48.74	OK	1413	2026-09-20 06:10	48.26	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
14137	2026-09-20 06:11	47.39	OK	14138	2026-09-20 06:12	47.18	OK
14139	2026-09-20 06:13	46.25	OK	14140	2026-09-20 06:14	46.75	OK
14141	2026-09-20 06:15	47.56	OK	14142	2026-09-20 06:16	45.97	OK
14143	2026-09-20 06:17	47.15	OK	14144	2026-09-20 06:18	49.28	OK
14145	2026-09-20 06:19	47.69	OK	14146	2026-09-20 06:20	49.94	OK
14147	2026-09-20 06:21	47.60	OK	14148	2026-09-20 06:22	47.86	OK
14149	2026-09-20 06:23	45.73	OK	14150	2026-09-20 06:24	48.04	OK
14151	2026-09-20 06:25	46.15	OK	14152	2026-09-20 06:26	47.12	OK
14153	2026-09-20 06:27	47.87	OK	14154	2026-09-20 06:28	47.75	OK
14155	2026-09-20 06:29	50.38	OK	14156	2026-09-20 06:30	47.36	OK
14157	2026-09-20 06:31	47.69	OK	14158	2026-09-20 06:32	46.59	OK
14159	2026-09-20 06:33	48.35	OK	14160	2026-09-20 06:34	45.97	OK
14161	2026-09-20 06:35	49.42	OK	14162	2026-09-20 06:36	48.65	OK
14163	2026-09-20 06:37	46.33	OK	14164	2026-09-20 06:38	47.75	OK
14165	2026-09-20 06:39	47.57	OK	14166	2026-09-20 06:40	49.04	OK
14167	2026-09-20 06:41	48.71	OK	14168	2026-09-20 06:42	49.59	OK
14169	2026-09-20 06:43	48.00	OK	14170	2026-09-20 06:44	48.15	OK
14171	2026-09-20 06:45	46.61	OK	14172	2026-09-20 06:46	48.71	OK
14173	2026-09-20 06:47	50.19	OK	14174	2026-09-20 06:48	48.33	OK
14175	2026-09-20 06:49	47.29	OK	14176	2026-09-20 06:50	48.74	OK
14177	2026-09-20 06:51	48.03	OK	14178	2026-09-20 06:52	47.19	OK
14179	2026-09-20 06:53	46.08	OK	14180	2026-09-20 06:54	47.87	OK
14181	2026-09-20 06:55	48.25	OK	14182	2026-09-20 06:56	48.53	OK
14183	2026-09-20 06:57	47.89	OK	14184	2026-09-20 06:58	47.49	OK
14185	2026-09-20 06:59	50.86	OK	14186	2026-09-20 07:00	48.00	OK
14187	2026-09-20 07:01	47.68	OK	14188	2026-09-20 07:02	48.16	OK
14189	2026-09-20 07:03	48.87	OK	14190	2026-09-20 07:04	47.80	OK
14191	2026-09-20 07:05	47.60	OK	14192	2026-09-20 07:06	49.65	OK
14193	2026-09-20 07:07	49.03	OK	14194	2026-09-20 07:08	48.43	OK
1419	2026-09-20 07:09	48.15	OK	1419	2026-09-20 07:10	48.46	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
14197	2026-09-20 07:11	47.51	OK	14198	2026-09-20 07:12	47.52	OK
14199	2026-09-20 07:13	48.57	OK	14200	2026-09-20 07:14	48.61	OK
14201	2026-09-20 07:15	49.09	OK	14202	2026-09-20 07:16	48.70	OK
14203	2026-09-20 07:17	48.19	OK	14204	2026-09-20 07:18	48.61	OK
14205	2026-09-20 07:19	49.68	OK	14206	2026-09-20 07:20	47.39	OK
14207	2026-09-20 07:21	46.83	OK	14208	2026-09-20 07:22	47.90	OK
14209	2026-09-20 07:23	46.94	OK	14210	2026-09-20 07:24	49.07	OK
14211	2026-09-20 07:25	48.52	OK	14212	2026-09-20 07:26	49.60	OK
14213	2026-09-20 07:27	47.70	OK	14214	2026-09-20 07:28	49.32	OK
14215	2026-09-20 07:29	49.24	OK	14216	2026-09-20 07:30	49.83	OK
14217	2026-09-20 07:31	49.47	OK	14218	2026-09-20 07:32	48.48	OK
14219	2026-09-20 07:33	46.80	OK	14220	2026-09-20 07:34	47.18	OK
14221	2026-09-20 07:35	47.69	OK	14222	2026-09-20 07:36	48.83	OK
14223	2026-09-20 07:37	50.43	OK	14224	2026-09-20 07:38	49.86	OK
14225	2026-09-20 07:39	48.55	OK	14226	2026-09-20 07:40	50.62	OK
14227	2026-09-20 07:41	48.45	OK	14228	2026-09-20 07:42	50.63	OK
14229	2026-09-20 07:43	47.68	OK	14230	2026-09-20 07:44	48.26	OK
14231	2026-09-20 07:45	49.56	OK	14232	2026-09-20 07:46	49.70	OK
14233	2026-09-20 07:47	47.30	OK	14234	2026-09-20 07:48	49.29	OK
14235	2026-09-20 07:49	49.80	OK	14236	2026-09-20 07:50	49.69	OK
14237	2026-09-20 07:51	49.94	OK	14238	2026-09-20 07:52	49.60	OK
14239	2026-09-20 07:53	47.88	OK	14240	2026-09-20 07:54	47.99	OK
14241	2026-09-20 07:55	48.16	OK	14242	2026-09-20 07:56	50.06	OK
14243	2026-09-20 07:57	49.41	OK	14244	2026-09-20 07:58	48.86	OK
14245	2026-09-20 07:59	48.91	OK	14246	2026-09-20 08:00	50.53	OK
14247	2026-09-20 08:01	48.68	OK	14248	2026-09-20 08:02	49.95	OK
14249	2026-09-20 08:03	51.18	OK	14250	2026-09-20 08:04	48.55	OK
14251	2026-09-20 08:05	48.16	OK	14252	2026-09-20 08:06	50.30	OK
14253	2026-09-20 08:07	49.03	OK	14254	2026-09-20 08:08	48.28	OK
1425	2026-09-20 08:09	50.72	OK	1425	2026-09-20 08:10	49.82	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
14257	2026-09-20 08:11	49.34	OK	14258	2026-09-20 08:12	49.83	OK
14259	2026-09-20 08:13	49.73	OK	14260	2026-09-20 08:14	51.35	OK
14261	2026-09-20 08:15	49.94	OK	14262	2026-09-20 08:16	50.09	OK
14263	2026-09-20 08:17	49.59	OK	14264	2026-09-20 08:18	50.43	OK
14265	2026-09-20 08:19	48.46	OK	14266	2026-09-20 08:20	49.04	OK
14267	2026-09-20 08:21	49.05	OK	14268	2026-09-20 08:22	47.59	OK
14269	2026-09-20 08:23	48.80	OK	14270	2026-09-20 08:24	49.41	OK
14271	2026-09-20 08:25	49.18	OK	14272	2026-09-20 08:26	51.08	OK
14273	2026-09-20 08:27	50.00	OK	14274	2026-09-20 08:28	51.88	OK
14275	2026-09-20 08:29	51.19	OK	14276	2026-09-20 08:30	51.27	OK
14277	2026-09-20 08:31	49.00	OK	14278	2026-09-20 08:32	48.02	OK
14279	2026-09-20 08:33	49.50	OK	14280	2026-09-20 08:34	50.82	OK
14281	2026-09-20 08:35	49.48	OK	14282	2026-09-20 08:36	49.63	OK
14283	2026-09-20 08:37	49.86	OK	14284	2026-09-20 08:38	50.56	OK
14285	2026-09-20 08:39	51.27	OK	14286	2026-09-20 08:40	48.44	OK
14287	2026-09-20 08:41	49.08	OK	14288	2026-09-20 08:42	49.31	OK
14289	2026-09-20 08:43	50.92	OK	14290	2026-09-20 08:44	48.68	OK
14291	2026-09-20 08:45	50.04	OK	14292	2026-09-20 08:46	48.57	OK
14293	2026-09-20 08:47	49.16	OK	14294	2026-09-20 08:48	50.52	OK
14295	2026-09-20 08:49	50.09	OK	14296	2026-09-20 08:50	48.96	OK
14297	2026-09-20 08:51	49.01	OK	14298	2026-09-20 08:52	48.77	OK
14299	2026-09-20 08:53	48.37	OK	14300	2026-09-20 08:54	51.42	OK
14301	2026-09-20 08:55	49.53	OK	14302	2026-09-20 08:56	47.79	OK
14303	2026-09-20 08:57	49.81	OK	14304	2026-09-20 08:58	52.14	OK
14305	2026-09-20 08:59	49.52	OK	14306	2026-09-20 09:00	51.46	OK
14307	2026-09-20 09:01	48.63	OK	14308	2026-09-20 09:02	52.14	OK
14309	2026-09-20 09:03	49.22	OK	14310	2026-09-20 09:04	51.42	OK
14311	2026-09-20 09:05	48.42	OK	14312	2026-09-20 09:06	48.53	OK
14313	2026-09-20 09:07	49.96	OK	14314	2026-09-20 09:08	50.38	OK
1431	2026-09-20 09:09	51.83	OK	1431	2026-09-20 09:10	49.14	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
14317	2026-09-20 09:11	52.24	OK	14318	2026-09-20 09:12	51.89	OK
14319	2026-09-20 09:13	51.28	OK	14320	2026-09-20 09:14	50.81	OK
14321	2026-09-20 09:15	49.61	OK	14322	2026-09-20 09:16	50.08	OK
14323	2026-09-20 09:17	50.21	OK	14324	2026-09-20 09:18	51.09	OK
14325	2026-09-20 09:19	48.93	OK	14326	2026-09-20 09:20	51.00	OK
14327	2026-09-20 09:21	47.58	OK	14328	2026-09-20 09:22	50.22	OK
14329	2026-09-20 09:23	51.10	OK	14330	2026-09-20 09:24	48.63	OK
14331	2026-09-20 09:25	48.60	OK	14332	2026-09-20 09:26	50.73	OK
14333	2026-09-20 09:27	49.94	OK	14334	2026-09-20 09:28	49.55	OK
14335	2026-09-20 09:29	51.76	OK	14336	2026-09-20 09:30	50.38	OK
14337	2026-09-20 09:31	52.24	OK	14338	2026-09-20 09:32	49.97	OK
14339	2026-09-20 09:33	49.83	OK	14340	2026-09-20 09:34	49.89	OK
14341	2026-09-20 09:35	51.47	OK	14342	2026-09-20 09:36	49.50	OK
14343	2026-09-20 09:37	52.14	OK	14344	2026-09-20 09:38	50.46	OK
14345	2026-09-20 09:39	49.03	OK	14346	2026-09-20 09:40	49.40	OK
14347	2026-09-20 09:41	52.12	OK	14348	2026-09-20 09:42	49.05	OK
14349	2026-09-20 09:43	50.63	OK	14350	2026-09-20 09:44	49.31	OK
14351	2026-09-20 09:45	52.86	OK	14352	2026-09-20 09:46	48.54	OK
14353	2026-09-20 09:47	51.17	OK	14354	2026-09-20 09:48	50.80	OK
14355	2026-09-20 09:49	51.00	OK	14356	2026-09-20 09:50	49.87	OK
14357	2026-09-20 09:51	48.99	OK	14358	2026-09-20 09:52	51.78	OK
14359	2026-09-20 09:53	50.04	OK	14360	2026-09-20 09:54	49.99	OK
14361	2026-09-20 09:55	51.90	OK	14362	2026-09-20 09:56	51.26	OK
14363	2026-09-20 09:57	49.03	OK	14364	2026-09-20 09:58	50.34	OK
14365	2026-09-20 09:59	49.59	OK	14366	2026-09-20 10:00	51.39	OK
14367	2026-09-20 10:01	50.56	OK	14368	2026-09-20 10:02	51.64	OK
14369	2026-09-20 10:03	52.73	OK	14370	2026-09-20 10:04	52.84	OK
14371	2026-09-20 10:05	51.37	OK	14372	2026-09-20 10:06	51.07	OK
14373	2026-09-20 10:07	51.73	OK	14374	2026-09-20 10:08	50.57	OK
1437	2026-09-20 10:09	49.61	OK	1437	2026-09-20 10:10	48.62	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
14377	2026-09-20 10:11	51.18	OK	14378	2026-09-20 10:12	52.45	OK
14379	2026-09-20 10:13	51.79	OK	14380	2026-09-20 10:14	49.37	OK
14381	2026-09-20 10:15	51.19	OK	14382	2026-09-20 10:16	50.97	OK
14383	2026-09-20 10:17	50.63	OK	14384	2026-09-20 10:18	51.17	OK
14385	2026-09-20 10:19	51.74	OK	14386	2026-09-20 10:20	49.01	OK
14387	2026-09-20 10:21	49.66	OK	14388	2026-09-20 10:22	52.17	OK
14389	2026-09-20 10:23	50.77	OK	14390	2026-09-20 10:24	51.53	OK
14391	2026-09-20 10:25	52.07	OK	14392	2026-09-20 10:26	52.60	OK
14393	2026-09-20 10:27	49.90	OK	14394	2026-09-20 10:28	50.74	OK
14395	2026-09-20 10:29	52.62	OK	14396	2026-09-20 10:30	51.05	OK
14397	2026-09-20 10:31	51.38	OK	14398	2026-09-20 10:32	50.00	OK
14399	2026-09-20 10:33	52.24	OK	14400	2026-09-20 10:34	51.27	OK
14401	2026-09-20 10:35	51.41	OK	14402	2026-09-20 10:36	51.98	OK
14403	2026-09-20 10:37	49.01	OK	14404	2026-09-20 10:38	51.19	OK
14405	2026-09-20 10:39	51.35	OK	14406	2026-09-20 10:40	50.63	OK
14407	2026-09-20 10:41	50.45	OK	14408	2026-09-20 10:42	50.20	OK
14409	2026-09-20 10:43	50.66	OK	14410	2026-09-20 10:44	49.47	OK
14411	2026-09-20 10:45	49.82	OK	14412	2026-09-20 10:46	52.11	OK
14413	2026-09-20 10:47	50.24	OK	14414	2026-09-20 10:48	52.87	OK
14415	2026-09-20 10:49	52.55	OK	14416	2026-09-20 10:50	51.43	OK
14417	2026-09-20 10:51	51.11	OK	14418	2026-09-20 10:52	49.90	OK
14419	2026-09-20 10:53	50.74	OK	14420	2026-09-20 10:54	51.56	OK
14421	2026-09-20 10:55	50.81	OK	14422	2026-09-20 10:56	51.02	OK
14423	2026-09-20 10:57	51.62	OK	14424	2026-09-20 10:58	53.62	OK
14425	2026-09-20 10:59	53.48	OK	14426	2026-09-20 11:00	49.82	OK
14427	2026-09-20 11:01	48.77	OK	14428	2026-09-20 11:02	52.08	OK
14429	2026-09-20 11:03	50.45	OK	14430	2026-09-20 11:04	52.85	OK
14431	2026-09-20 11:05	50.44	OK	14432	2026-09-20 11:06	51.59	OK
14433	2026-09-20 11:07	52.65	OK	14434	2026-09-20 11:08	51.21	OK
1443	2026-09-20 11:09	51.58	OK	1443	2026-09-20 11:10	51.64	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
14437	2026-09-20 11:11	52.14	OK	14438	2026-09-20 11:12	52.75	OK
14439	2026-09-20 11:13	51.37	OK	14440	2026-09-20 11:14	52.26	OK
14441	2026-09-20 11:15	51.15	OK	14442	2026-09-20 11:16	51.02	OK
14443	2026-09-20 11:17	50.82	OK	14444	2026-09-20 11:18	51.57	OK
14445	2026-09-20 11:19	50.84	OK	14446	2026-09-20 11:20	50.18	OK
14447	2026-09-20 11:21	51.22	OK	14448	2026-09-20 11:22	49.50	OK
14449	2026-09-20 11:23	51.13	OK	14450	2026-09-20 11:24	50.56	OK
14451	2026-09-20 11:25	52.68	OK	14452	2026-09-20 11:26	51.75	OK
14453	2026-09-20 11:27	51.82	OK	14454	2026-09-20 11:28	51.62	OK
14455	2026-09-20 11:29	52.33	OK	14456	2026-09-20 11:30	51.82	OK
14457	2026-09-20 11:31	50.38	OK	14458	2026-09-20 11:32	52.87	OK
14459	2026-09-20 11:33	50.92	OK	14460	2026-09-20 11:34	52.22	OK
14461	2026-09-20 11:35	50.47	OK	14462	2026-09-20 11:36	49.80	OK
14463	2026-09-20 11:37	51.14	OK	14464	2026-09-20 11:38	49.39	OK
14465	2026-09-20 11:39	50.57	OK	14466	2026-09-20 11:40	51.77	OK
14467	2026-09-20 11:41	51.26	OK	14468	2026-09-20 11:42	52.09	OK
14469	2026-09-20 11:43	51.30	OK	14470	2026-09-20 11:44	51.22	OK
14471	2026-09-20 11:45	51.75	OK	14472	2026-09-20 11:46	53.60	OK
14473	2026-09-20 11:47	50.32	OK	14474	2026-09-20 11:48	49.80	OK
14475	2026-09-20 11:49	51.43	OK	14476	2026-09-20 11:50	51.29	OK
14477	2026-09-20 11:51	51.92	OK	14478	2026-09-20 11:52	52.87	OK
14479	2026-09-20 11:53	50.59	OK	14480	2026-09-20 11:54	51.50	OK
14481	2026-09-20 11:55	52.91	OK	14482	2026-09-20 11:56	50.78	OK
14483	2026-09-20 11:57	52.81	OK	14484	2026-09-20 11:58	51.08	OK
14485	2026-09-20 11:59	53.82	OK	14486	2026-09-20 12:00	51.86	OK
14487	2026-09-20 12:01	51.55	OK	14488	2026-09-20 12:02	52.11	OK
14489	2026-09-20 12:03	52.21	OK	14490	2026-09-20 12:04	52.08	OK
14491	2026-09-20 12:05	51.29	OK	14492	2026-09-20 12:06	52.95	OK
14493	2026-09-20 12:07	53.01	OK	14494	2026-09-20 12:08	50.28	OK
1449	2026-09-20 12:09	52.82	OK	1449	2026-09-20 12:10	51.96	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
14497	2026-09-20 12:11	51.74	OK	14498	2026-09-20 12:12	52.51	OK
14499	2026-09-20 12:13	51.85	OK	14500	2026-09-20 12:14	50.11	OK
14501	2026-09-20 12:15	51.39	OK	14502	2026-09-20 12:16	51.11	OK
14503	2026-09-20 12:17	52.92	OK	14504	2026-09-20 12:18	51.90	OK
14505	2026-09-20 12:19	53.95	OK	14506	2026-09-20 12:20	51.57	OK
14507	2026-09-20 12:21	52.89	OK	14508	2026-09-20 12:22	52.01	OK
14509	2026-09-20 12:23	52.39	OK	14510	2026-09-20 12:24	51.49	OK
14511	2026-09-20 12:25	50.71	OK	14512	2026-09-20 12:26	53.08	OK
14513	2026-09-20 12:27	51.51	OK	14514	2026-09-20 12:28	52.62	OK
14515	2026-09-20 12:29	51.53	OK	14516	2026-09-20 12:30	50.56	OK
14517	2026-09-20 12:31	53.58	OK	14518	2026-09-20 12:32	52.14	OK
14519	2026-09-20 12:33	51.56	OK	14520	2026-09-20 12:34	51.58	OK
14521	2026-09-20 12:35	52.34	OK	14522	2026-09-20 12:36	52.91	OK
14523	2026-09-20 12:37	51.85	OK	14524	2026-09-20 12:38	52.11	OK
14525	2026-09-20 12:39	51.70	OK	14526	2026-09-20 12:40	50.77	OK
14527	2026-09-20 12:41	51.42	OK	14528	2026-09-20 12:42	52.14	OK
14529	2026-09-20 12:43	51.86	OK	14530	2026-09-20 12:44	51.30	OK
14531	2026-09-20 12:45	51.82	OK	14532	2026-09-20 12:46	51.53	OK
14533	2026-09-20 12:47	52.38	OK	14534	2026-09-20 12:48	51.64	OK
14535	2026-09-20 12:49	50.00	OK	14536	2026-09-20 12:50	50.69	OK
14537	2026-09-20 12:51	53.09	OK	14538	2026-09-20 12:52	50.89	OK
14539	2026-09-20 12:53	52.75	OK	14540	2026-09-20 12:54	51.19	OK
14541	2026-09-20 12:55	52.04	OK	14542	2026-09-20 12:56	53.18	OK
14543	2026-09-20 12:57	52.61	OK	14544	2026-09-20 12:58	53.49	OK
14545	2026-09-20 12:59	51.59	OK	14546	2026-09-20 13:00	52.68	OK
14547	2026-09-20 13:01	51.99	OK	14548	2026-09-20 13:02	52.17	OK
14549	2026-09-20 13:03	51.11	OK	14550	2026-09-20 13:04	52.32	OK
14551	2026-09-20 13:05	52.55	OK	14552	2026-09-20 13:06	53.51	OK
14553	2026-09-20 13:07	50.73	OK	14554	2026-09-20 13:08	51.87	OK
14555	2026-09-20 13:09	52.87	OK	14555	2026-09-20 13:10	53.20	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
14557	2026-09-20 13:11	52.95	OK	14558	2026-09-20 13:12	52.28	OK
14559	2026-09-20 13:13	52.26	OK	14560	2026-09-20 13:14	50.96	OK
14561	2026-09-20 13:15	52.33	OK	14562	2026-09-20 13:16	53.99	OK
14563	2026-09-20 13:17	50.35	OK	14564	2026-09-20 13:18	52.70	OK
14565	2026-09-20 13:19	52.40	OK	14566	2026-09-20 13:20	52.55	OK
14567	2026-09-20 13:21	51.80	OK	14568	2026-09-20 13:22	52.81	OK
14569	2026-09-20 13:23	52.62	OK	14570	2026-09-20 13:24	50.46	OK
14571	2026-09-20 13:25	52.86	OK	14572	2026-09-20 13:26	52.58	OK
14573	2026-09-20 13:27	51.39	OK	14574	2026-09-20 13:28	51.98	OK
14575	2026-09-20 13:29	50.99	OK	14576	2026-09-20 13:30	51.84	OK
14577	2026-09-20 13:31	51.82	OK	14578	2026-09-20 13:32	51.41	OK
14579	2026-09-20 13:33	50.87	OK	14580	2026-09-20 13:34	51.46	OK
14581	2026-09-20 13:35	51.53	OK	14582	2026-09-20 13:36	51.87	OK
14583	2026-09-20 13:37	51.20	OK	14584	2026-09-20 13:38	51.62	OK
14585	2026-09-20 13:39	52.50	OK	14586	2026-09-20 13:40	52.15	OK
14587	2026-09-20 13:41	52.21	OK	14588	2026-09-20 13:42	52.95	OK
14589	2026-09-20 13:43	51.53	OK	14590	2026-09-20 13:44	52.73	OK
14591	2026-09-20 13:45	51.54	OK	14592	2026-09-20 13:46	51.98	OK
14593	2026-09-20 13:47	52.01	OK	14594	2026-09-20 13:48	51.35	OK
14595	2026-09-20 13:49	50.81	OK	14596	2026-09-20 13:50	52.47	OK
14597	2026-09-20 13:51	52.67	OK	14598	2026-09-20 13:52	52.73	OK
14599	2026-09-20 13:53	53.09	OK	14600	2026-09-20 13:54	52.09	OK
14601	2026-09-20 13:55	49.90	OK	14602	2026-09-20 13:56	50.25	OK
14603	2026-09-20 13:57	50.37	OK	14604	2026-09-20 13:58	49.36	OK
14605	2026-09-20 13:59	51.36	OK	14606	2026-09-20 14:00	52.16	OK
14607	2026-09-20 14:01	51.69	OK	14608	2026-09-20 14:02	52.57	OK
14609	2026-09-20 14:03	51.57	OK	14610	2026-09-20 14:04	51.71	OK
14611	2026-09-20 14:05	50.71	OK	14612	2026-09-20 14:06	53.50	OK
14613	2026-09-20 14:07	53.35	OK	14614	2026-09-20 14:08	52.43	OK
1461	2026-09-20 14:09	52.50	OK	1461	2026-09-20 14:10	51.97	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
14617	2026-09-20 14:11	50.94	OK	14618	2026-09-20 14:12	49.82	OK
14619	2026-09-20 14:13	52.03	OK	14620	2026-09-20 14:14	52.93	OK
14621	2026-09-20 14:15	51.58	OK	14622	2026-09-20 14:16	52.03	OK
14623	2026-09-20 14:17	51.19	OK	14624	2026-09-20 14:18	50.58	OK
14625	2026-09-20 14:19	52.12	OK	14626	2026-09-20 14:20	52.58	OK
14627	2026-09-20 14:21	51.07	OK	14628	2026-09-20 14:22	51.82	OK
14629	2026-09-20 14:23	52.63	OK	14630	2026-09-20 14:24	51.55	OK
14631	2026-09-20 14:25	51.23	OK	14632	2026-09-20 14:26	51.04	OK
14633	2026-09-20 14:27	52.45	OK	14634	2026-09-20 14:28	52.15	OK
14635	2026-09-20 14:29	50.53	OK	14636	2026-09-20 14:30	49.76	OK
14637	2026-09-20 14:31	52.50	OK	14638	2026-09-20 14:32	52.72	OK
14639	2026-09-20 14:33	52.90	OK	14640	2026-09-20 14:34	52.31	OK
14641	2026-09-20 14:35	51.04	OK	14642	2026-09-20 14:36	52.24	OK
14643	2026-09-20 14:37	51.54	OK	14644	2026-09-20 14:38	52.91	OK
14645	2026-09-20 14:39	53.08	OK	14646	2026-09-20 14:40	53.36	OK
14647	2026-09-20 14:41	52.23	OK	14648	2026-09-20 14:42	53.23	OK
14649	2026-09-20 14:43	51.28	OK	14650	2026-09-20 14:44	51.35	OK
14651	2026-09-20 14:45	50.99	OK	14652	2026-09-20 14:46	51.70	OK
14653	2026-09-20 14:47	51.30	OK	14654	2026-09-20 14:48	52.46	OK
14655	2026-09-20 14:49	51.57	OK	14656	2026-09-20 14:50	51.98	OK
14657	2026-09-20 14:51	53.37	OK	14658	2026-09-20 14:52	52.46	OK
14659	2026-09-20 14:53	50.20	OK	14660	2026-09-20 14:54	51.27	OK
14661	2026-09-20 14:55	51.58	OK	14662	2026-09-20 14:56	51.02	OK
14663	2026-09-20 14:57	51.83	OK	14664	2026-09-20 14:58	50.65	OK
14665	2026-09-20 14:59	52.09	OK	14666	2026-09-20 15:00	51.48	OK
14667	2026-09-20 15:01	50.83	OK	14668	2026-09-20 15:02	52.14	OK
14669	2026-09-20 15:03	51.93	OK	14670	2026-09-20 15:04	50.47	OK
14671	2026-09-20 15:05	50.56	OK	14672	2026-09-20 15:06	52.21	OK
14673	2026-09-20 15:07	52.12	OK	14674	2026-09-20 15:08	51.78	OK
1467	2026-09-20 15:09	50.82	OK	1467	2026-09-20 15:10	53.05	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
14677	2026-09-20 15:11	52.39	OK	14678	2026-09-20 15:12	51.18	OK
14679	2026-09-20 15:13	50.41	OK	14680	2026-09-20 15:14	51.11	OK
14681	2026-09-20 15:15	52.44	OK	14682	2026-09-20 15:16	49.47	OK
14683	2026-09-20 15:17	50.81	OK	14684	2026-09-20 15:18	51.54	OK
14685	2026-09-20 15:19	51.90	OK	14686	2026-09-20 15:20	50.00	OK
14687	2026-09-20 15:21	50.08	OK	14688	2026-09-20 15:22	51.50	OK
14689	2026-09-20 15:23	51.27	OK	14690	2026-09-20 15:24	51.07	OK
14691	2026-09-20 15:25	52.74	OK	14692	2026-09-20 15:26	51.54	OK
14693	2026-09-20 15:27	51.64	OK	14694	2026-09-20 15:28	51.93	OK
14695	2026-09-20 15:29	49.53	OK	14696	2026-09-20 15:30	50.31	OK
14697	2026-09-20 15:31	49.67	OK	14698	2026-09-20 15:32	51.72	OK
14699	2026-09-20 15:33	50.52	OK	14700	2026-09-20 15:34	51.52	OK
14701	2026-09-20 15:35	51.20	OK	14702	2026-09-20 15:36	50.76	OK
14703	2026-09-20 15:37	50.60	OK	14704	2026-09-20 15:38	51.38	OK
14705	2026-09-20 15:39	52.90	OK	14706	2026-09-20 15:40	52.44	OK
14707	2026-09-20 15:41	50.52	OK	14708	2026-09-20 15:42	51.34	OK
14709	2026-09-20 15:43	49.48	OK	14710	2026-09-20 15:44	49.72	OK
14711	2026-09-20 15:45	50.17	OK	14712	2026-09-20 15:46	51.62	OK
14713	2026-09-20 15:47	51.75	OK	14714	2026-09-20 15:48	51.27	OK
14715	2026-09-20 15:49	52.33	OK	14716	2026-09-20 15:50	52.39	OK
14717	2026-09-20 15:51	50.22	OK	14718	2026-09-20 15:52	50.09	OK
14719	2026-09-20 15:53	49.64	OK	14720	2026-09-20 15:54	52.59	OK
14721	2026-09-20 15:55	50.12	OK	14722	2026-09-20 15:56	51.47	OK
14723	2026-09-20 15:57	51.42	OK	14724	2026-09-20 15:58	50.05	OK
14725	2026-09-20 15:59	49.93	OK	14726	2026-09-20 16:00	50.02	OK
14727	2026-09-20 16:01	52.15	OK	14728	2026-09-20 16:02	51.81	OK
14729	2026-09-20 16:03	50.64	OK	14730	2026-09-20 16:04	52.76	OK
14731	2026-09-20 16:05	52.42	OK	14732	2026-09-20 16:06	50.87	OK
14733	2026-09-20 16:07	50.14	OK	14734	2026-09-20 16:08	49.30	OK
1473	2026-09-20 16:09	51.04	OK	1473	2026-09-20 16:10	50.58	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
14737	2026-09-20 16:11	50.42	OK	14738	2026-09-20 16:12	51.93	OK
14739	2026-09-20 16:13	52.50	OK	14740	2026-09-20 16:14	50.25	OK
14741	2026-09-20 16:15	50.10	OK	14742	2026-09-20 16:16	52.16	OK
14743	2026-09-20 16:17	50.55	OK	14744	2026-09-20 16:18	52.08	OK
14745	2026-09-20 16:19	51.06	OK	14746	2026-09-20 16:20	48.55	OK
14747	2026-09-20 16:21	49.31	OK	14748	2026-09-20 16:22	50.96	OK
14749	2026-09-20 16:23	50.98	OK	14750	2026-09-20 16:24	51.77	OK
14751	2026-09-20 16:25	51.40	OK	14752	2026-09-20 16:26	50.70	OK
14753	2026-09-20 16:27	49.89	OK	14754	2026-09-20 16:28	52.19	OK
14755	2026-09-20 16:29	50.51	OK	14756	2026-09-20 16:30	49.86	OK
14757	2026-09-20 16:31	50.35	OK	14758	2026-09-20 16:32	50.05	OK
14759	2026-09-20 16:33	50.55	OK	14760	2026-09-20 16:34	51.59	OK
14761	2026-09-20 16:35	50.23	OK	14762	2026-09-20 16:36	48.68	OK
14763	2026-09-20 16:37	50.79	OK	14764	2026-09-20 16:38	50.30	OK
14765	2026-09-20 16:39	51.97	OK	14766	2026-09-20 16:40	50.52	OK
14767	2026-09-20 16:41	51.38	OK	14768	2026-09-20 16:42	50.76	OK
14769	2026-09-20 16:43	51.16	OK	14770	2026-09-20 16:44	48.60	OK
14771	2026-09-20 16:45	50.10	OK	14772	2026-09-20 16:46	51.14	OK
14773	2026-09-20 16:47	52.27	OK	14774	2026-09-20 16:48	52.66	OK
14775	2026-09-20 16:49	52.09	OK	14776	2026-09-20 16:50	51.63	OK
14777	2026-09-20 16:51	50.41	OK	14778	2026-09-20 16:52	49.51	OK
14779	2026-09-20 16:53	51.13	OK	14780	2026-09-20 16:54	50.01	OK
14781	2026-09-20 16:55	49.98	OK	14782	2026-09-20 16:56	51.81	OK
14783	2026-09-20 16:57	50.68	OK	14784	2026-09-20 16:58	50.72	OK
14785	2026-09-20 16:59	49.31	OK	14786	2026-09-20 17:00	50.01	OK
14787	2026-09-20 17:01	51.07	OK	14788	2026-09-20 17:02	49.80	OK
14789	2026-09-20 17:03	51.05	OK	14790	2026-09-20 17:04	48.76	OK
14791	2026-09-20 17:05	49.02	OK	14792	2026-09-20 17:06	50.26	OK
14793	2026-09-20 17:07	50.40	OK	14794	2026-09-20 17:08	50.11	OK
1479	2026-09-20 17:09	49.29	OK	1479	2026-09-20 17:10	50.66	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
14797	2026-09-20 17:11	51.20	OK	14798	2026-09-20 17:12	49.70	OK
14799	2026-09-20 17:13	51.43	OK	14800	2026-09-20 17:14	51.09	OK
14801	2026-09-20 17:15	50.98	OK	14802	2026-09-20 17:16	51.20	OK
14803	2026-09-20 17:17	50.97	OK	14804	2026-09-20 17:18	51.71	OK
14805	2026-09-20 17:19	48.99	OK	14806	2026-09-20 17:20	49.40	OK
14807	2026-09-20 17:21	50.93	OK	14808	2026-09-20 17:22	50.38	OK
14809	2026-09-20 17:23	51.27	OK	14810	2026-09-20 17:24	51.45	OK
14811	2026-09-20 17:25	48.72	OK	14812	2026-09-20 17:26	50.31	OK
14813	2026-09-20 17:27	50.79	OK	14814	2026-09-20 17:28	48.80	OK
14815	2026-09-20 17:29	50.64	OK	14816	2026-09-20 17:30	49.44	OK
14817	2026-09-20 17:31	52.09	OK	14818	2026-09-20 17:32	50.50	OK
14819	2026-09-20 17:33	49.06	OK	14820	2026-09-20 17:34	50.86	OK
14821	2026-09-20 17:35	49.91	OK	14822	2026-09-20 17:36	49.64	OK
14823	2026-09-20 17:37	50.22	OK	14824	2026-09-20 17:38	51.21	OK
14825	2026-09-20 17:39	50.53	OK	14826	2026-09-20 17:40	48.68	OK
14827	2026-09-20 17:41	48.94	OK	14828	2026-09-20 17:42	49.51	OK
14829	2026-09-20 17:43	47.72	OK	14830	2026-09-20 17:44	48.84	OK
14831	2026-09-20 17:45	50.66	OK	14832	2026-09-20 17:46	50.42	OK
14833	2026-09-20 17:47	49.71	OK	14834	2026-09-20 17:48	50.53	OK
14835	2026-09-20 17:49	50.72	OK	14836	2026-09-20 17:50	48.20	OK
14837	2026-09-20 17:51	47.85	OK	14838	2026-09-20 17:52	48.43	OK
14839	2026-09-20 17:53	48.11	OK	14840	2026-09-20 17:54	50.42	OK
14841	2026-09-20 17:55	50.35	OK	14842	2026-09-20 17:56	48.55	OK
14843	2026-09-20 17:57	51.00	OK	14844	2026-09-20 17:58	51.98	OK
14845	2026-09-20 17:59	50.65	OK	14846	2026-09-20 18:00	48.96	OK
14847	2026-09-20 18:01	48.91	OK	14848	2026-09-20 18:02	51.01	OK
14849	2026-09-20 18:03	51.09	OK	14850	2026-09-20 18:04	49.56	OK
14851	2026-09-20 18:05	50.98	OK	14852	2026-09-20 18:06	49.94	OK
14853	2026-09-20 18:07	48.74	OK	14854	2026-09-20 18:08	49.96	OK
1485	2026-09-20 18:09	48.59	OK	1485	2026-09-20 18:10	49.67	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
14857	2026-09-20 18:11	50.43	OK	14858	2026-09-20 18:12	49.39	OK
14859	2026-09-20 18:13	47.86	OK	14860	2026-09-20 18:14	49.45	OK
14861	2026-09-20 18:15	50.61	OK	14862	2026-09-20 18:16	48.91	OK
14863	2026-09-20 18:17	49.21	OK	14864	2026-09-20 18:18	49.65	OK
14865	2026-09-20 18:19	48.17	OK	14866	2026-09-20 18:20	47.76	OK
14867	2026-09-20 18:21	48.42	OK	14868	2026-09-20 18:22	50.98	OK
14869	2026-09-20 18:23	49.06	OK	14870	2026-09-20 18:24	48.84	OK
14871	2026-09-20 18:25	49.30	OK	14872	2026-09-20 18:26	48.59	OK
14873	2026-09-20 18:27	48.82	OK	14874	2026-09-20 18:28	47.93	OK
14875	2026-09-20 18:29	48.89	OK	14876	2026-09-20 18:30	49.72	OK
14877	2026-09-20 18:31	50.76	OK	14878	2026-09-20 18:32	49.64	OK
14879	2026-09-20 18:33	48.49	OK	14880	2026-09-20 18:34	49.12	OK
14881	2026-09-20 18:35	47.20	OK	14882	2026-09-20 18:36	48.36	OK
14883	2026-09-20 18:37	48.83	OK	14884	2026-09-20 18:38	47.99	OK
14885	2026-09-20 18:39	50.66	OK	14886	2026-09-20 18:40	48.55	OK
14887	2026-09-20 18:41	49.40	OK	14888	2026-09-20 18:42	49.09	OK
14889	2026-09-20 18:43	49.84	OK	14890	2026-09-20 18:44	47.47	OK
14891	2026-09-20 18:45	48.48	OK	14892	2026-09-20 18:46	47.92	OK
14893	2026-09-20 18:47	48.98	OK	14894	2026-09-20 18:48	50.00	OK
14895	2026-09-20 18:49	48.35	OK	14896	2026-09-20 18:50	48.38	OK
14897	2026-09-20 18:51	49.19	OK	14898	2026-09-20 18:52	49.62	OK
14899	2026-09-20 18:53	48.77	OK	14900	2026-09-20 18:54	47.83	OK
14901	2026-09-20 18:55	49.89	OK	14902	2026-09-20 18:56	47.23	OK
14903	2026-09-20 18:57	49.07	OK	14904	2026-09-20 18:58	49.11	OK
14905	2026-09-20 18:59	49.42	OK	14906	2026-09-20 19:00	51.09	OK
14907	2026-09-20 19:01	50.75	OK	14908	2026-09-20 19:02	48.04	OK
14909	2026-09-20 19:03	50.89	OK	14910	2026-09-20 19:04	47.77	OK
14911	2026-09-20 19:05	49.08	OK	14912	2026-09-20 19:06	49.25	OK
14913	2026-09-20 19:07	48.81	OK	14914	2026-09-20 19:08	50.24	OK
1491	2026-09-20 19:09	50.76	OK	1491	2026-09-20 19:10	47.19	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
14917	2026-09-20 19:11	49.44	OK	14918	2026-09-20 19:12	49.89	OK
14919	2026-09-20 19:13	50.81	OK	14920	2026-09-20 19:14	46.35	OK
14921	2026-09-20 19:15	48.72	OK	14922	2026-09-20 19:16	47.77	OK
14923	2026-09-20 19:17	49.53	OK	14924	2026-09-20 19:18	48.58	OK
14925	2026-09-20 19:19	49.32	OK	14926	2026-09-20 19:20	49.11	OK
14927	2026-09-20 19:21	48.92	OK	14928	2026-09-20 19:22	48.82	OK
14929	2026-09-20 19:23	48.05	OK	14930	2026-09-20 19:24	47.50	OK
14931	2026-09-20 19:25	48.54	OK	14932	2026-09-20 19:26	48.78	OK
14933	2026-09-20 19:27	48.92	OK	14934	2026-09-20 19:28	47.95	OK
14935	2026-09-20 19:29	48.08	OK	14936	2026-09-20 19:30	50.10	OK
14937	2026-09-20 19:31	48.21	OK	14938	2026-09-20 19:32	49.26	OK
14939	2026-09-20 19:33	46.79	OK	14940	2026-09-20 19:34	50.05	OK
14941	2026-09-20 19:35	48.70	OK	14942	2026-09-20 19:36	47.93	OK
14943	2026-09-20 19:37	50.47	OK	14944	2026-09-20 19:38	48.81	OK
14945	2026-09-20 19:39	46.47	OK	14946	2026-09-20 19:40	47.14	OK
14947	2026-09-20 19:41	49.83	OK	14948	2026-09-20 19:42	48.94	OK
14949	2026-09-20 19:43	48.25	OK	14950	2026-09-20 19:44	48.21	OK
14951	2026-09-20 19:45	47.30	OK	14952	2026-09-20 19:46	47.98	OK
14953	2026-09-20 19:47	47.46	OK	14954	2026-09-20 19:48	46.08	OK
14955	2026-09-20 19:49	47.56	OK	14956	2026-09-20 19:50	48.75	OK
14957	2026-09-20 19:51	48.09	OK	14958	2026-09-20 19:52	47.27	OK
14959	2026-09-20 19:53	45.92	OK	14960	2026-09-20 19:54	47.75	OK
14961	2026-09-20 19:55	47.45	OK	14962	2026-09-20 19:56	46.51	OK
14963	2026-09-20 19:57	49.21	OK	14964	2026-09-20 19:58	47.49	OK
14965	2026-09-20 19:59	47.88	OK	14966	2026-09-20 20:00	45.72	OK
14967	2026-09-20 20:01	47.55	OK	14968	2026-09-20 20:02	46.80	OK
14969	2026-09-20 20:03	48.39	OK	14970	2026-09-20 20:04	47.36	OK
14971	2026-09-20 20:05	48.06	OK	14972	2026-09-20 20:06	48.66	OK
14973	2026-09-20 20:07	46.61	OK	14974	2026-09-20 20:08	47.83	OK
1497	2026-09-20 20:09	48.93	OK	1497	2026-09-20 20:10	46.52	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
14977	2026-09-20 20:11	48.34	OK	14978	2026-09-20 20:12	47.30	OK
14979	2026-09-20 20:13	47.81	OK	14980	2026-09-20 20:14	49.54	OK
14981	2026-09-20 20:15	47.91	OK	14982	2026-09-20 20:16	47.57	OK
14983	2026-09-20 20:17	46.98	OK	14984	2026-09-20 20:18	46.51	OK
14985	2026-09-20 20:19	48.60	OK	14986	2026-09-20 20:20	47.68	OK
14987	2026-09-20 20:21	47.03	OK	14988	2026-09-20 20:22	48.36	OK
14989	2026-09-20 20:23	47.89	OK	14990	2026-09-20 20:24	48.52	OK
14991	2026-09-20 20:25	48.40	OK	14992	2026-09-20 20:26	48.98	OK
14993	2026-09-20 20:27	47.57	OK	14994	2026-09-20 20:28	47.28	OK
14995	2026-09-20 20:29	48.03	OK	14996	2026-09-20 20:30	49.27	OK
14997	2026-09-20 20:31	49.52	OK	14998	2026-09-20 20:32	45.63	OK
14999	2026-09-20 20:33	46.31	OK	15000	2026-09-20 20:34	49.86	OK
15001	2026-09-20 20:35	48.04	OK	15002	2026-09-20 20:36	47.12	OK
15003	2026-09-20 20:37	48.12	OK	15004	2026-09-20 20:38	48.70	OK
15005	2026-09-20 20:39	48.94	OK	15006	2026-09-20 20:40	47.40	OK
15007	2026-09-20 20:41	45.38	OK	15008	2026-09-20 20:42	47.63	OK
15009	2026-09-20 20:43	49.62	OK	15010	2026-09-20 20:44	48.09	OK
15011	2026-09-20 20:45	47.20	OK	15012	2026-09-20 20:46	47.12	OK
15013	2026-09-20 20:47	47.78	OK	15014	2026-09-20 20:48	48.57	OK
15015	2026-09-20 20:49	46.40	OK	15016	2026-09-20 20:50	46.78	OK
15017	2026-09-20 20:51	47.27	OK	15018	2026-09-20 20:52	47.64	OK
15019	2026-09-20 20:53	48.42	OK	15020	2026-09-20 20:54	45.79	OK
15021	2026-09-20 20:55	48.13	OK	15022	2026-09-20 20:56	46.12	OK
15023	2026-09-20 20:57	46.47	OK	15024	2026-09-20 20:58	47.64	OK
15025	2026-09-20 20:59	46.05	OK	15026	2026-09-20 21:00	46.56	OK
15027	2026-09-20 21:01	47.20	OK	15028	2026-09-20 21:02	47.52	OK
15029	2026-09-20 21:03	46.71	OK	15030	2026-09-20 21:04	47.31	OK
15031	2026-09-20 21:05	48.38	OK	15032	2026-09-20 21:06	45.90	OK
15033	2026-09-20 21:07	47.35	OK	15034	2026-09-20 21:08	48.21	OK
1503	2026-09-20 21:09	47.57	OK	1503	2026-09-20 21:10	46.84	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
15037	2026-09-20 21:11	46.20	OK	15038	2026-09-20 21:12	45.36	OK
15039	2026-09-20 21:13	47.30	OK	15040	2026-09-20 21:14	48.95	OK
15041	2026-09-20 21:15	46.09	OK	15042	2026-09-20 21:16	46.75	OK
15043	2026-09-20 21:17	46.89	OK	15044	2026-09-20 21:18	45.55	OK
15045	2026-09-20 21:19	48.05	OK	15046	2026-09-20 21:20	49.06	OK
15047	2026-09-20 21:21	46.56	OK	15048	2026-09-20 21:22	45.86	OK
15049	2026-09-20 21:23	48.29	OK	15050	2026-09-20 21:24	44.91	OK
15051	2026-09-20 21:25	48.29	OK	15052	2026-09-20 21:26	48.10	OK
15053	2026-09-20 21:27	44.97	OK	15054	2026-09-20 21:28	47.52	OK
15055	2026-09-20 21:29	46.09	OK	15056	2026-09-20 21:30	47.55	OK
15057	2026-09-20 21:31	47.53	OK	15058	2026-09-20 21:32	47.35	OK
15059	2026-09-20 21:33	46.18	OK	15060	2026-09-20 21:34	46.37	OK
15061	2026-09-20 21:35	45.09	OK	15062	2026-09-20 21:36	46.32	OK
15063	2026-09-20 21:37	48.01	OK	15064	2026-09-20 21:38	46.43	OK
15065	2026-09-20 21:39	46.93	OK	15066	2026-09-20 21:40	46.79	OK
15067	2026-09-20 21:41	45.87	OK	15068	2026-09-20 21:42	46.51	OK
15069	2026-09-20 21:43	46.04	OK	15070	2026-09-20 21:44	46.08	OK
15071	2026-09-20 21:45	47.56	OK	15072	2026-09-20 21:46	47.22	OK
15073	2026-09-20 21:47	44.55	OK	15074	2026-09-20 21:48	46.08	OK
15075	2026-09-20 21:49	45.47	OK	15076	2026-09-20 21:50	47.63	OK
15077	2026-09-20 21:51	45.78	OK	15078	2026-09-20 21:52	47.46	OK
15079	2026-09-20 21:53	48.23	OK	15080	2026-09-20 21:54	45.10	OK
15081	2026-09-20 21:55	47.34	OK	15082	2026-09-20 21:56	47.03	OK
15083	2026-09-20 21:57	47.25	OK	15084	2026-09-20 21:58	46.04	OK
15085	2026-09-20 21:59	44.66	OK	15086	2026-09-20 22:00	46.64	OK
15087	2026-09-20 22:01	44.79	OK	15088	2026-09-20 22:02	45.56	OK
15089	2026-09-20 22:03	45.74	OK	15090	2026-09-20 22:04	46.68	OK
15091	2026-09-20 22:05	46.28	OK	15092	2026-09-20 22:06	45.92	OK
15093	2026-09-20 22:07	47.87	OK	15094	2026-09-20 22:08	45.07	OK
1509	2026-09-20 22:09	45.55	OK	1509	2026-09-20 22:10	46.54	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
15097	2026-09-20 22:11	46.19	OK	15098	2026-09-20 22:12	44.83	OK
15099	2026-09-20 22:13	46.84	OK	15100	2026-09-20 22:14	45.96	OK
15101	2026-09-20 22:15	45.95	OK	15102	2026-09-20 22:16	47.57	OK
15103	2026-09-20 22:17	44.27	OK	15104	2026-09-20 22:18	46.29	OK
15105	2026-09-20 22:19	46.59	OK	15106	2026-09-20 22:20	46.10	OK
15107	2026-09-20 22:21	46.50	OK	15108	2026-09-20 22:22	45.69	OK
15109	2026-09-20 22:23	47.28	OK	15110	2026-09-20 22:24	45.17	OK
15111	2026-09-20 22:25	45.51	OK	15112	2026-09-20 22:26	45.82	OK
15113	2026-09-20 22:27	45.46	OK	15114	2026-09-20 22:28	45.41	OK
15115	2026-09-20 22:29	44.75	OK	15116	2026-09-20 22:30	45.87	OK
15117	2026-09-20 22:31	45.65	OK	15118	2026-09-20 22:32	44.74	OK
15119	2026-09-20 22:33	47.14	OK	15120	2026-09-20 22:34	46.42	OK
15121	2026-09-20 22:35	45.99	OK	15122	2026-09-20 22:36	48.21	OK
15123	2026-09-20 22:37	44.69	OK	15124	2026-09-20 22:38	46.83	OK
15125	2026-09-20 22:39	45.97	OK	15126	2026-09-20 22:40	48.09	OK
15127	2026-09-20 22:41	45.34	OK	15128	2026-09-20 22:42	46.31	OK
15129	2026-09-20 22:43	48.73	OK	15130	2026-09-20 22:44	45.26	OK
15131	2026-09-20 22:45	46.99	OK	15132	2026-09-20 22:46	45.26	OK
15133	2026-09-20 22:47	46.35	OK	15134	2026-09-20 22:48	47.57	OK
15135	2026-09-20 22:49	46.74	OK	15136	2026-09-20 22:50	45.47	OK
15137	2026-09-20 22:51	45.90	OK	15138	2026-09-20 22:52	44.54	OK
15139	2026-09-20 22:53	45.40	OK	15140	2026-09-20 22:54	45.96	OK
15141	2026-09-20 22:55	44.40	OK	15142	2026-09-20 22:56	46.16	OK
15143	2026-09-20 22:57	44.18	OK	15144	2026-09-20 22:58	46.01	OK
15145	2026-09-20 22:59	48.13	OK	15146	2026-09-20 23:00	45.71	OK
15147	2026-09-20 23:01	45.56	OK	15148	2026-09-20 23:02	45.45	OK
15149	2026-09-20 23:03	45.39	OK	15150	2026-09-20 23:04	45.65	OK
15151	2026-09-20 23:05	46.47	OK	15152	2026-09-20 23:06	44.97	OK
15153	2026-09-20 23:07	47.22	OK	15154	2026-09-20 23:08	46.69	OK
1515	2026-09-20 23:09	44.68	OK	1515	2026-09-20 23:10	43.86	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
15157	2026-09-20 23:11	46.47	OK	15158	2026-09-20 23:12	48.00	OK
15159	2026-09-20 23:13	46.50	OK	15160	2026-09-20 23:14	45.38	OK
15161	2026-09-20 23:15	46.24	OK	15162	2026-09-20 23:16	45.16	OK
15163	2026-09-20 23:17	45.15	OK	15164	2026-09-20 23:18	46.12	OK
15165	2026-09-20 23:19	44.95	OK	15166	2026-09-20 23:20	45.31	OK
15167	2026-09-20 23:21	46.76	OK	15168	2026-09-20 23:22	44.82	OK
15169	2026-09-20 23:23	46.45	OK	15170	2026-09-20 23:24	45.84	OK
15171	2026-09-20 23:25	45.97	OK	15172	2026-09-20 23:26	43.99	OK
15173	2026-09-20 23:27	44.46	OK	15174	2026-09-20 23:28	47.08	OK
15175	2026-09-20 23:29	44.90	OK	15176	2026-09-20 23:30	45.82	OK
15177	2026-09-20 23:31	44.56	OK	15178	2026-09-20 23:32	46.38	OK
15179	2026-09-20 23:33	46.03	OK	15180	2026-09-20 23:34	45.22	OK
15181	2026-09-20 23:35	46.13	OK	15182	2026-09-20 23:36	45.77	OK
15183	2026-09-20 23:37	43.89	OK	15184	2026-09-20 23:38	45.14	OK
15185	2026-09-20 23:39	46.20	OK	15186	2026-09-20 23:40	47.69	OK
15187	2026-09-20 23:41	45.23	OK	15188	2026-09-20 23:42	44.98	OK
15189	2026-09-20 23:43	45.14	OK	15190	2026-09-20 23:44	44.79	OK
15191	2026-09-20 23:45	45.31	OK	15192	2026-09-20 23:46	45.27	OK
15193	2026-09-20 23:47	46.41	OK	15194	2026-09-20 23:48	45.49	OK
15195	2026-09-20 23:49	46.33	OK	15196	2026-09-20 23:50	44.50	OK
15197	2026-09-20 23:51	46.49	OK	15198	2026-09-20 23:52	44.16	OK
15199	2026-09-20 23:53	45.31	OK	15200	2026-09-20 23:54	45.09	OK
15201	2026-09-20 23:55	44.04	OK	15202	2026-09-20 23:56	44.96	OK
15203	2026-09-20 23:57	47.35	OK	15204	2026-09-20 23:58	47.36	OK
15205	2026-09-20 23:59	45.69	OK	15206	2026-09-21 00:00	46.05	OK
15207	2026-09-21 00:01	45.74	OK	15208	2026-09-21 00:02	46.24	OK
15209	2026-09-21 00:03	44.58	OK	15210	2026-09-21 00:04	44.00	OK
15211	2026-09-21 00:05	45.32	OK	15212	2026-09-21 00:06	45.93	OK
15213	2026-09-21 00:07	46.47	OK	15214	2026-09-21 00:08	45.54	OK
1521	2026-09-21 00:09	44.45	OK	1521	2026-09-21 00:10	43.82	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
15217	2026-09-21 00:11	43.56	OK	15218	2026-09-21 00:12	44.67	OK
15219	2026-09-21 00:13	45.32	OK	15220	2026-09-21 00:14	44.02	OK
15221	2026-09-21 00:15	44.61	OK	15222	2026-09-21 00:16	45.18	OK
15223	2026-09-21 00:17	45.19	OK	15224	2026-09-21 00:18	45.34	OK
15225	2026-09-21 00:19	44.03	OK	15226	2026-09-21 00:20	45.44	OK
15227	2026-09-21 00:21	47.13	OK	15228	2026-09-21 00:22	44.18	OK
15229	2026-09-21 00:23	44.52	OK	15230	2026-09-21 00:24	45.87	OK
15231	2026-09-21 00:25	47.16	OK	15232	2026-09-21 00:26	46.62	OK
15233	2026-09-21 00:27	44.20	OK	15234	2026-09-21 00:28	45.09	OK
15235	2026-09-21 00:29	44.07	OK	15236	2026-09-21 00:30	45.96	OK
15237	2026-09-21 00:31	43.59	OK	15238	2026-09-21 00:32	45.20	OK
15239	2026-09-21 00:33	46.30	OK	15240	2026-09-21 00:34	44.99	OK
15241	2026-09-21 00:35	44.24	OK	15242	2026-09-21 00:36	46.25	OK
15243	2026-09-21 00:37	45.29	OK	15244	2026-09-21 00:38	46.26	OK
15245	2026-09-21 00:39	44.35	OK	15246	2026-09-21 00:40	46.10	OK
15247	2026-09-21 00:41	42.96	OK	15248	2026-09-21 00:42	43.74	OK
15249	2026-09-21 00:43	46.96	OK	15250	2026-09-21 00:44	44.13	OK
15251	2026-09-21 00:45	46.27	OK	15252	2026-09-21 00:46	44.08	OK
15253	2026-09-21 00:47	44.77	OK	15254	2026-09-21 00:48	44.95	OK
15255	2026-09-21 00:49	46.45	OK	15256	2026-09-21 00:50	45.12	OK
15257	2026-09-21 00:51	46.65	OK	15258	2026-09-21 00:52	45.98	OK
15259	2026-09-21 00:53	45.15	OK	15260	2026-09-21 00:54	47.00	OK
15261	2026-09-21 00:55	44.65	OK	15262	2026-09-21 00:56	45.79	OK
15263	2026-09-21 00:57	45.47	OK	15264	2026-09-21 00:58	46.00	OK
15265	2026-09-21 00:59	46.73	OK	15266	2026-09-21 01:00	44.79	OK
15267	2026-09-21 01:01	44.32	OK	15268	2026-09-21 01:02	43.64	OK
15269	2026-09-21 01:03	46.98	OK	15270	2026-09-21 01:04	44.73	OK
15271	2026-09-21 01:05	46.63	OK	15272	2026-09-21 01:06	45.35	OK
15273	2026-09-21 01:07	43.42	OK	15274	2026-09-21 01:08	43.34	OK
1527	2026-09-21 01:09	46.75	OK	1527	2026-09-21 01:10	46.18	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
15277	2026-09-21 01:11	44.59	OK	15278	2026-09-21 01:12	44.00	OK
15279	2026-09-21 01:13	45.04	OK	15280	2026-09-21 01:14	45.96	OK
15281	2026-09-21 01:15	45.15	OK	15282	2026-09-21 01:16	45.20	OK
15283	2026-09-21 01:17	44.81	OK	15284	2026-09-21 01:18	44.93	OK
15285	2026-09-21 01:19	45.71	OK	15286	2026-09-21 01:20	45.81	OK
15287	2026-09-21 01:21	45.42	OK	15288	2026-09-21 01:22	43.42	OK
15289	2026-09-21 01:23	43.91	OK	15290	2026-09-21 01:24	44.48	OK
15291	2026-09-21 01:25	44.48	OK	15292	2026-09-21 01:26	45.65	OK
15293	2026-09-21 01:27	44.68	OK	15294	2026-09-21 01:28	46.63	OK
15295	2026-09-21 01:29	45.94	OK	15296	2026-09-21 01:30	44.49	OK
15297	2026-09-21 01:31	45.68	OK	15298	2026-09-21 01:32	45.06	OK
15299	2026-09-21 01:33	44.42	OK	15300	2026-09-21 01:34	46.22	OK
15301	2026-09-21 01:35	44.56	OK	15302	2026-09-21 01:36	44.88	OK
15303	2026-09-21 01:37	46.49	OK	15304	2026-09-21 01:38	44.65	OK
15305	2026-09-21 01:39	43.86	OK	15306	2026-09-21 01:40	46.41	OK
15307	2026-09-21 01:41	45.19	OK	15308	2026-09-21 01:42	46.91	OK
15309	2026-09-21 01:43	44.86	OK	15310	2026-09-21 01:44	45.25	OK
15311	2026-09-21 01:45	46.06	OK	15312	2026-09-21 01:46	46.13	OK
15313	2026-09-21 01:47	43.61	OK	15314	2026-09-21 01:48	45.79	OK
15315	2026-09-21 01:49	45.75	OK	15316	2026-09-21 01:50	44.20	OK
15317	2026-09-21 01:51	46.74	OK	15318	2026-09-21 01:52	43.85	OK
15319	2026-09-21 01:53	44.52	OK	15320	2026-09-21 01:54	45.27	OK
15321	2026-09-21 01:55	45.68	OK	15322	2026-09-21 01:56	46.43	OK
15323	2026-09-21 01:57	45.09	OK	15324	2026-09-21 01:58	44.32	OK
15325	2026-09-21 01:59	44.67	OK	15326	2026-09-21 02:00	46.25	OK
15327	2026-09-21 02:01	44.67	OK	15328	2026-09-21 02:02	44.82	OK
15329	2026-09-21 02:03	45.22	OK	15330	2026-09-21 02:04	46.32	OK
15331	2026-09-21 02:05	44.90	OK	15332	2026-09-21 02:06	45.04	OK
15333	2026-09-21 02:07	45.27	OK	15334	2026-09-21 02:08	46.78	OK
1533	2026-09-21 02:09	45.91	OK	1533	2026-09-21 02:10	46.61	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
15337	2026-09-21 02:11	44.94	OK	15338	2026-09-21 02:12	46.68	OK
15339	2026-09-21 02:13	45.05	OK	15340	2026-09-21 02:14	44.17	OK
15341	2026-09-21 02:15	45.01	OK	15342	2026-09-21 02:16	47.12	OK
15343	2026-09-21 02:17	46.66	OK	15344	2026-09-21 02:18	43.98	OK
15345	2026-09-21 02:19	44.71	OK	15346	2026-09-21 02:20	45.05	OK
15347	2026-09-21 02:21	43.65	OK	15348	2026-09-21 02:22	44.35	OK
15349	2026-09-21 02:23	43.57	OK	15350	2026-09-21 02:24	46.42	OK
15351	2026-09-21 02:25	47.08	OK	15352	2026-09-21 02:26	44.89	OK
15353	2026-09-21 02:27	46.51	OK	15354	2026-09-21 02:28	43.93	OK
15355	2026-09-21 02:29	45.16	OK	15356	2026-09-21 02:30	46.49	OK
15357	2026-09-21 02:31	44.84	OK	15358	2026-09-21 02:32	43.76	OK
15359	2026-09-21 02:33	43.79	OK	15360	2026-09-21 02:34	46.04	OK
15361	2026-09-21 02:35	44.82	OK	15362	2026-09-21 02:36	46.32	OK
15363	2026-09-21 02:37	45.45	OK	15364	2026-09-21 02:38	44.84	OK
15365	2026-09-21 02:39	47.24	OK	15366	2026-09-21 02:40	47.05	OK
15367	2026-09-21 02:41	44.99	OK	15368	2026-09-21 02:42	45.36	OK
15369	2026-09-21 02:43	45.87	OK	15370	2026-09-21 02:44	45.40	OK
15371	2026-09-21 02:45	46.15	OK	15372	2026-09-21 02:46	44.85	OK
15373	2026-09-21 02:47	45.98	OK	15374	2026-09-21 02:48	47.04	OK
15375	2026-09-21 02:49	45.83	OK	15376	2026-09-21 02:50	46.49	OK
15377	2026-09-21 02:51	43.09	OK	15378	2026-09-21 02:52	44.56	OK
15379	2026-09-21 02:53	45.90	OK	15380	2026-09-21 02:54	45.72	OK
15381	2026-09-21 02:55	45.22	OK	15382	2026-09-21 02:56	44.10	OK
15383	2026-09-21 02:57	44.47	OK	15384	2026-09-21 02:58	45.96	OK
15385	2026-09-21 02:59	45.08	OK	15386	2026-09-21 03:00	44.64	OK
15387	2026-09-21 03:01	45.92	OK	15388	2026-09-21 03:02	44.98	OK
15389	2026-09-21 03:03	45.63	OK	15390	2026-09-21 03:04	45.88	OK
15391	2026-09-21 03:05	44.51	OK	15392	2026-09-21 03:06	45.60	OK
15393	2026-09-21 03:07	45.06	OK	15394	2026-09-21 03:08	45.85	OK
1539	2026-09-21 03:09	43.99	OK	1539	2026-09-21 03:10	44.57	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
15397	2026-09-21 03:11	44.63	OK	15398	2026-09-21 03:12	46.52	OK
15399	2026-09-21 03:13	46.02	OK	15400	2026-09-21 03:14	46.09	OK
15401	2026-09-21 03:15	44.26	OK	15402	2026-09-21 03:16	46.89	OK
15403	2026-09-21 03:17	45.17	OK	15404	2026-09-21 03:18	43.00	OK
15405	2026-09-21 03:19	44.33	OK	15406	2026-09-21 03:20	45.51	OK
15407	2026-09-21 03:21	43.97	OK	15408	2026-09-21 03:22	44.69	OK
15409	2026-09-21 03:23	47.08	OK	15410	2026-09-21 03:24	45.27	OK
15411	2026-09-21 03:25	45.92	OK	15412	2026-09-21 03:26	44.85	OK
15413	2026-09-21 03:27	45.04	OK	15414	2026-09-21 03:28	45.24	OK
15415	2026-09-21 03:29	44.27	OK	15416	2026-09-21 03:30	44.62	OK
15417	2026-09-21 03:31	44.38	OK	15418	2026-09-21 03:32	44.65	OK
15419	2026-09-21 03:33	45.74	OK	15420	2026-09-21 03:34	45.65	OK
15421	2026-09-21 03:35	45.78	OK	15422	2026-09-21 03:36	45.13	OK
15423	2026-09-21 03:37	45.75	OK	15424	2026-09-21 03:38	46.33	OK
15425	2026-09-21 03:39	44.82	OK	15426	2026-09-21 03:40	45.45	OK
15427	2026-09-21 03:41	46.28	OK	15428	2026-09-21 03:42	46.44	OK
15429	2026-09-21 03:43	45.43	OK	15430	2026-09-21 03:44	45.72	OK
15431	2026-09-21 03:45	44.94	OK	15432	2026-09-21 03:46	46.72	OK
15433	2026-09-21 03:47	46.38	OK	15434	2026-09-21 03:48	46.11	OK
15435	2026-09-21 03:49	46.54	OK	15436	2026-09-21 03:50	45.02	OK
15437	2026-09-21 03:51	46.21	OK	15438	2026-09-21 03:52	45.53	OK
15439	2026-09-21 03:53	45.37	OK	15440	2026-09-21 03:54	46.85	OK
15441	2026-09-21 03:55	45.91	OK	15442	2026-09-21 03:56	47.59	OK
15443	2026-09-21 03:57	46.79	OK	15444	2026-09-21 03:58	44.84	OK
15445	2026-09-21 03:59	44.05	OK	15446	2026-09-21 04:00	46.89	OK
15447	2026-09-21 04:01	47.32	OK	15448	2026-09-21 04:02	46.85	OK
15449	2026-09-21 04:03	46.89	OK	15450	2026-09-21 04:04	45.54	OK
15451	2026-09-21 04:05	46.21	OK	15452	2026-09-21 04:06	45.25	OK
15453	2026-09-21 04:07	45.47	OK	15454	2026-09-21 04:08	45.40	OK
1545	2026-09-21 04:09	47.21	OK	1545	2026-09-21 04:10	46.11	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
15457	2026-09-21 04:11	48.40	OK	15458	2026-09-21 04:12	47.58	OK
15459	2026-09-21 04:13	45.62	OK	15460	2026-09-21 04:14	47.73	OK
15461	2026-09-21 04:15	44.25	OK	15462	2026-09-21 04:16	47.13	OK
15463	2026-09-21 04:17	47.25	OK	15464	2026-09-21 04:18	44.01	OK
15465	2026-09-21 04:19	45.17	OK	15466	2026-09-21 04:20	46.38	OK
15467	2026-09-21 04:21	47.84	OK	15468	2026-09-21 04:22	45.65	OK
15469	2026-09-21 04:23	46.55	OK	15470	2026-09-21 04:24	44.05	OK
15471	2026-09-21 04:25	45.11	OK	15472	2026-09-21 04:26	48.27	OK
15473	2026-09-21 04:27	46.62	OK	15474	2026-09-21 04:28	45.09	OK
15475	2026-09-21 04:29	47.18	OK	15476	2026-09-21 04:30	48.26	OK
15477	2026-09-21 04:31	45.48	OK	15478	2026-09-21 04:32	47.64	OK
15479	2026-09-21 04:33	45.66	OK	15480	2026-09-21 04:34	46.70	OK
15481	2026-09-21 04:35	44.50	OK	15482	2026-09-21 04:36	47.12	OK
15483	2026-09-21 04:37	45.59	OK	15484	2026-09-21 04:38	45.48	OK
15485	2026-09-21 04:39	45.74	OK	15486	2026-09-21 04:40	47.36	OK
15487	2026-09-21 04:41	46.41	OK	15488	2026-09-21 04:42	46.02	OK
15489	2026-09-21 04:43	46.63	OK	15490	2026-09-21 04:44	47.24	OK
15491	2026-09-21 04:45	46.37	OK	15492	2026-09-21 04:46	47.94	OK
15493	2026-09-21 04:47	45.98	OK	15494	2026-09-21 04:48	45.20	OK
15495	2026-09-21 04:49	45.38	OK	15496	2026-09-21 04:50	44.27	OK
15497	2026-09-21 04:51	46.77	OK	15498	2026-09-21 04:52	46.66	OK
15499	2026-09-21 04:53	48.07	OK	15500	2026-09-21 04:54	45.42	OK
15501	2026-09-21 04:55	45.80	OK	15502	2026-09-21 04:56	46.10	OK
15503	2026-09-21 04:57	47.12	OK	15504	2026-09-21 04:58	44.47	OK
15505	2026-09-21 04:59	46.40	OK	15506	2026-09-21 05:00	46.94	OK
15507	2026-09-21 05:01	47.34	OK	15508	2026-09-21 05:02	44.60	OK
15509	2026-09-21 05:03	47.62	OK	15510	2026-09-21 05:04	48.43	OK
15511	2026-09-21 05:05	46.75	OK	15512	2026-09-21 05:06	47.82	OK
15513	2026-09-21 05:07	46.00	OK	15514	2026-09-21 05:08	47.77	OK
15515	2026-09-21 05:09	46.03	OK	15515	2026-09-21 05:10	46.49	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
15517	2026-09-21 05:11	46.87	OK	15518	2026-09-21 05:12	46.93	OK
15519	2026-09-21 05:13	44.82	OK	15520	2026-09-21 05:14	46.55	OK
15521	2026-09-21 05:15	47.68	OK	15522	2026-09-21 05:16	47.74	OK
15523	2026-09-21 05:17	48.49	OK	15524	2026-09-21 05:18	47.15	OK
15525	2026-09-21 05:19	47.61	OK	15526	2026-09-21 05:20	45.70	OK
15527	2026-09-21 05:21	45.87	OK	15528	2026-09-21 05:22	47.58	OK
15529	2026-09-21 05:23	46.92	OK	15530	2026-09-21 05:24	46.55	OK
15531	2026-09-21 05:25	48.02	OK	15532	2026-09-21 05:26	46.90	OK
15533	2026-09-21 05:27	44.98	OK	15534	2026-09-21 05:28	47.28	OK
15535	2026-09-21 05:29	46.05	OK	15536	2026-09-21 05:30	47.23	OK
15537	2026-09-21 05:31	48.37	OK	15538	2026-09-21 05:32	47.08	OK
15539	2026-09-21 05:33	45.47	OK	15540	2026-09-21 05:34	47.36	OK
15541	2026-09-21 05:35	47.10	OK	15542	2026-09-21 05:36	48.00	OK
15543	2026-09-21 05:37	45.83	OK	15544	2026-09-21 05:38	47.42	OK
15545	2026-09-21 05:39	45.50	OK	15546	2026-09-21 05:40	48.00	OK
15547	2026-09-21 05:41	48.03	OK	15548	2026-09-21 05:42	47.24	OK
15549	2026-09-21 05:43	47.36	OK	15550	2026-09-21 05:44	47.49	OK
15551	2026-09-21 05:45	47.31	OK	15552	2026-09-21 05:46	46.46	OK
15553	2026-09-21 05:47	47.83	OK	15554	2026-09-21 05:48	47.25	OK
15555	2026-09-21 05:49	46.96	OK	15556	2026-09-21 05:50	46.56	OK
15557	2026-09-21 05:51	46.96	OK	15558	2026-09-21 05:52	48.16	OK
15559	2026-09-21 05:53	46.70	OK	15560	2026-09-21 05:54	48.48	OK
15561	2026-09-21 05:55	48.90	OK	15562	2026-09-21 05:56	47.76	OK
15563	2026-09-21 05:57	46.94	OK	15564	2026-09-21 05:58	48.99	OK
15565	2026-09-21 05:59	46.15	OK	15566	2026-09-21 06:00	47.22	OK
15567	2026-09-21 06:01	47.36	OK	15568	2026-09-21 06:02	48.32	OK
15569	2026-09-21 06:03	47.50	OK	15570	2026-09-21 06:04	47.57	OK
15571	2026-09-21 06:05	49.66	OK	15572	2026-09-21 06:06	47.03	OK
15573	2026-09-21 06:07	46.63	OK	15574	2026-09-21 06:08	46.56	OK
1557	2026-09-21 06:09	46.89	OK	1557	2026-09-21 06:10	48.81	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
15577	2026-09-21 06:11	48.96	OK	15578	2026-09-21 06:12	47.39	OK
15579	2026-09-21 06:13	47.32	OK	15580	2026-09-21 06:14	49.20	OK
15581	2026-09-21 06:15	48.11	OK	15582	2026-09-21 06:16	49.55	OK
15583	2026-09-21 06:17	47.15	OK	15584	2026-09-21 06:18	46.73	OK
15585	2026-09-21 06:19	46.77	OK	15586	2026-09-21 06:20	49.94	OK
15587	2026-09-21 06:21	48.00	OK	15588	2026-09-21 06:22	48.03	OK
15589	2026-09-21 06:23	48.45	OK	15590	2026-09-21 06:24	46.61	OK
15591	2026-09-21 06:25	48.82	OK	15592	2026-09-21 06:26	47.91	OK
15593	2026-09-21 06:27	49.31	OK	15594	2026-09-21 06:28	46.81	OK
15595	2026-09-21 06:29	47.11	OK	15596	2026-09-21 06:30	48.36	OK
15597	2026-09-21 06:31	46.82	OK	15598	2026-09-21 06:32	47.43	OK
15599	2026-09-21 06:33	47.21	OK	15600	2026-09-21 06:34	47.09	OK
15601	2026-09-21 06:35	45.65	OK	15602	2026-09-21 06:36	48.23	OK
15603	2026-09-21 06:37	46.24	OK	15604	2026-09-21 06:38	47.55	OK
15605	2026-09-21 06:39	49.55	OK	15606	2026-09-21 06:40	48.90	OK
15607	2026-09-21 06:41	48.11	OK	15608	2026-09-21 06:42	49.01	OK
15609	2026-09-21 06:43	49.19	OK	15610	2026-09-21 06:44	47.93	OK
15611	2026-09-21 06:45	46.61	OK	15612	2026-09-21 06:46	47.84	OK
15613	2026-09-21 06:47	49.22	OK	15614	2026-09-21 06:48	46.63	OK
15615	2026-09-21 06:49	48.64	OK	15616	2026-09-21 06:50	49.26	OK
15617	2026-09-21 06:51	45.92	OK	15618	2026-09-21 06:52	49.64	OK
15619	2026-09-21 06:53	47.62	OK	15620	2026-09-21 06:54	49.09	OK
15621	2026-09-21 06:55	47.18	OK	15622	2026-09-21 06:56	48.56	OK
15623	2026-09-21 06:57	49.17	OK	15624	2026-09-21 06:58	47.90	OK
15625	2026-09-21 06:59	47.06	OK	15626	2026-09-21 07:00	45.93	OK
15627	2026-09-21 07:01	49.28	OK	15628	2026-09-21 07:02	48.87	OK
15629	2026-09-21 07:03	47.60	OK	15630	2026-09-21 07:04	50.29	OK
15631	2026-09-21 07:05	48.11	OK	15632	2026-09-21 07:06	47.26	OK
15633	2026-09-21 07:07	48.59	OK	15634	2026-09-21 07:08	49.49	OK
1563	2026-09-21 07:09	49.33	OK	1563	2026-09-21 07:10	47.05	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
15637	2026-09-21 07:11	48.41	OK	15638	2026-09-21 07:12	49.42	OK
15639	2026-09-21 07:13	47.79	OK	15640	2026-09-21 07:14	48.80	OK
15641	2026-09-21 07:15	47.84	OK	15642	2026-09-21 07:16	48.67	OK
15643	2026-09-21 07:17	48.68	OK	15644	2026-09-21 07:18	47.37	OK
15645	2026-09-21 07:19	48.10	OK	15646	2026-09-21 07:20	48.31	OK
15647	2026-09-21 07:21	49.17	OK	15648	2026-09-21 07:22	48.76	OK
15649	2026-09-21 07:23	48.12	OK	15650	2026-09-21 07:24	48.52	OK
15651	2026-09-21 07:25	49.17	OK	15652	2026-09-21 07:26	50.29	OK
15653	2026-09-21 07:27	48.40	OK	15654	2026-09-21 07:28	46.63	OK
15655	2026-09-21 07:29	48.96	OK	15656	2026-09-21 07:30	49.53	OK
15657	2026-09-21 07:31	48.63	OK	15658	2026-09-21 07:32	48.32	OK
15659	2026-09-21 07:33	48.70	OK	15660	2026-09-21 07:34	49.03	OK
15661	2026-09-21 07:35	48.52	OK	15662	2026-09-21 07:36	48.05	OK
15663	2026-09-21 07:37	49.00	OK	15664	2026-09-21 07:38	49.12	OK
15665	2026-09-21 07:39	49.29	OK	15666	2026-09-21 07:40	48.81	OK
15667	2026-09-21 07:41	48.25	OK	15668	2026-09-21 07:42	48.61	OK
15669	2026-09-21 07:43	48.89	OK	15670	2026-09-21 07:44	47.68	OK
15671	2026-09-21 07:45	49.96	OK	15672	2026-09-21 07:46	48.76	OK
15673	2026-09-21 07:47	47.87	OK	15674	2026-09-21 07:48	48.38	OK
15675	2026-09-21 07:49	47.63	OK	15676	2026-09-21 07:50	50.71	OK
15677	2026-09-21 07:51	48.94	OK	15678	2026-09-21 07:52	48.59	OK
15679	2026-09-21 07:53	46.44	OK	15680	2026-09-21 07:54	48.43	OK
15681	2026-09-21 07:55	48.85	OK	15682	2026-09-21 07:56	49.97	OK
15683	2026-09-21 07:57	50.23	OK	15684	2026-09-21 07:58	47.47	OK
15685	2026-09-21 07:59	50.96	OK	15686	2026-09-21 08:00	49.76	OK
15687	2026-09-21 08:01	48.24	OK	15688	2026-09-21 08:02	49.96	OK
15689	2026-09-21 08:03	48.51	OK	15690	2026-09-21 08:04	48.37	OK
15691	2026-09-21 08:05	50.82	OK	15692	2026-09-21 08:06	49.58	OK
15693	2026-09-21 08:07	49.49	OK	15694	2026-09-21 08:08	48.62	OK
1569	2026-09-21 08:09	51.29	OK	1569	2026-09-21 08:10	49.72	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
15697	2026-09-21 08:11	49.67	OK	15698	2026-09-21 08:12	50.81	OK
15699	2026-09-21 08:13	48.35	OK	15700	2026-09-21 08:14	51.63	OK
15701	2026-09-21 08:15	49.69	OK	15702	2026-09-21 08:16	49.04	OK
15703	2026-09-21 08:17	47.73	OK	15704	2026-09-21 08:18	50.62	OK
15705	2026-09-21 08:19	47.96	OK	15706	2026-09-21 08:20	47.94	OK
15707	2026-09-21 08:21	50.66	OK	15708	2026-09-21 08:22	48.98	OK
15709	2026-09-21 08:23	48.25	OK	15710	2026-09-21 08:24	49.71	OK
15711	2026-09-21 08:25	48.08	OK	15712	2026-09-21 08:26	50.50	OK
15713	2026-09-21 08:27	48.86	OK	15714	2026-09-21 08:28	49.06	OK
15715	2026-09-21 08:29	50.07	OK	15716	2026-09-21 08:30	49.95	OK
15717	2026-09-21 08:31	48.72	OK	15718	2026-09-21 08:32	49.66	OK
15719	2026-09-21 08:33	50.17	OK	15720	2026-09-21 08:34	47.26	OK
15721	2026-09-21 08:35	50.60	OK	15722	2026-09-21 08:36	48.11	OK
15723	2026-09-21 08:37	49.65	OK	15724	2026-09-21 08:38	48.59	OK
15725	2026-09-21 08:39	49.34	OK	15726	2026-09-21 08:40	47.67	OK
15727	2026-09-21 08:41	49.24	OK	15728	2026-09-21 08:42	49.03	OK
15729	2026-09-21 08:43	51.01	OK	15730	2026-09-21 08:44	48.69	OK
15731	2026-09-21 08:45	50.79	OK	15732	2026-09-21 08:46	50.14	OK
15733	2026-09-21 08:47	50.10	OK	15734	2026-09-21 08:48	48.99	OK
15735	2026-09-21 08:49	50.08	OK	15736	2026-09-21 08:50	51.49	OK
15737	2026-09-21 08:51	50.92	OK	15738	2026-09-21 08:52	51.49	OK
15739	2026-09-21 08:53	50.92	OK	15740	2026-09-21 08:54	50.94	OK
15741	2026-09-21 08:55	49.69	OK	15742	2026-09-21 08:56	51.37	OK
15743	2026-09-21 08:57	48.53	OK	15744	2026-09-21 08:58	51.06	OK
15745	2026-09-21 08:59	51.31	OK	15746	2026-09-21 09:00	50.97	OK
15747	2026-09-21 09:01	50.44	OK	15748	2026-09-21 09:02	50.25	OK
15749	2026-09-21 09:03	50.07	OK	15750	2026-09-21 09:04	50.86	OK
15751	2026-09-21 09:05	49.91	OK	15752	2026-09-21 09:06	50.24	OK
15753	2026-09-21 09:07	49.80	OK	15754	2026-09-21 09:08	50.09	OK
15755	2026-09-21 09:09	50.94	OK	15755	2026-09-21 09:10	49.77	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
15757	2026-09-21 09:11	51.54	OK	15758	2026-09-21 09:12	50.10	OK
15759	2026-09-21 09:13	48.76	OK	15760	2026-09-21 09:14	47.93	OK
15761	2026-09-21 09:15	50.41	OK	15762	2026-09-21 09:16	50.68	OK
15763	2026-09-21 09:17	50.64	OK	15764	2026-09-21 09:18	48.81	OK
15765	2026-09-21 09:19	50.26	OK	15766	2026-09-21 09:20	50.69	OK
15767	2026-09-21 09:21	50.30	OK	15768	2026-09-21 09:22	49.06	OK
15769	2026-09-21 09:23	51.72	OK	15770	2026-09-21 09:24	49.22	OK
15771	2026-09-21 09:25	50.80	OK	15772	2026-09-21 09:26	48.76	OK
15773	2026-09-21 09:27	49.03	OK	15774	2026-09-21 09:28	50.34	OK
15775	2026-09-21 09:29	48.41	OK	15776	2026-09-21 09:30	51.46	OK
15777	2026-09-21 09:31	51.86	OK	15778	2026-09-21 09:32	49.40	OK
15779	2026-09-21 09:33	50.89	OK	15780	2026-09-21 09:34	50.75	OK
15781	2026-09-21 09:35	49.09	OK	15782	2026-09-21 09:36	48.50	OK
15783	2026-09-21 09:37	50.13	OK	15784	2026-09-21 09:38	50.77	OK
15785	2026-09-21 09:39	50.41	OK	15786	2026-09-21 09:40	49.93	OK
15787	2026-09-21 09:41	50.37	OK	15788	2026-09-21 09:42	50.69	OK
15789	2026-09-21 09:43	50.29	OK	15790	2026-09-21 09:44	51.27	OK
15791	2026-09-21 09:45	51.43	OK	15792	2026-09-21 09:46	50.83	OK
15793	2026-09-21 09:47	49.66	OK	15794	2026-09-21 09:48	50.90	OK
15795	2026-09-21 09:49	49.43	OK	15796	2026-09-21 09:50	50.78	OK
15797	2026-09-21 09:51	49.79	OK	15798	2026-09-21 09:52	50.30	OK
15799	2026-09-21 09:53	51.79	OK	15800	2026-09-21 09:54	49.97	OK
15801	2026-09-21 09:55	50.29	OK	15802	2026-09-21 09:56	52.71	OK
15803	2026-09-21 09:57	51.16	OK	15804	2026-09-21 09:58	50.81	OK
15805	2026-09-21 09:59	49.31	OK	15806	2026-09-21 10:00	49.35	OK
15807	2026-09-21 10:01	48.77	OK	15808	2026-09-21 10:02	49.07	OK
15809	2026-09-21 10:03	49.50	OK	15810	2026-09-21 10:04	49.43	OK
15811	2026-09-21 10:05	49.98	OK	15812	2026-09-21 10:06	50.31	OK
15813	2026-09-21 10:07	50.26	OK	15814	2026-09-21 10:08	51.17	OK
1581	2026-09-21 10:09	48.96	OK	1581	2026-09-21 10:10	52.03	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
15817	2026-09-21 10:11	49.24	OK	15818	2026-09-21 10:12	50.26	OK
15819	2026-09-21 10:13	49.41	OK	15820	2026-09-21 10:14	50.24	OK
15821	2026-09-21 10:15	51.70	OK	15822	2026-09-21 10:16	51.26	OK
15823	2026-09-21 10:17	50.89	OK	15824	2026-09-21 10:18	51.72	OK
15825	2026-09-21 10:19	49.67	OK	15826	2026-09-21 10:20	49.55	OK
15827	2026-09-21 10:21	51.23	OK	15828	2026-09-21 10:22	50.19	OK
15829	2026-09-21 10:23	52.07	OK	15830	2026-09-21 10:24	50.68	OK
15831	2026-09-21 10:25	52.68	OK	15832	2026-09-21 10:26	50.30	OK
15833	2026-09-21 10:27	51.61	OK	15834	2026-09-21 10:28	50.71	OK
15835	2026-09-21 10:29	52.91	OK	15836	2026-09-21 10:30	50.27	OK
15837	2026-09-21 10:31	50.30	OK	15838	2026-09-21 10:32	49.92	OK
15839	2026-09-21 10:33	51.45	OK	15840	2026-09-21 10:34	50.18	OK
15841	2026-09-21 10:35	51.38	OK	15842	2026-09-21 10:36	51.71	OK
15843	2026-09-21 10:37	50.82	OK	15844	2026-09-21 10:38	50.85	OK
15845	2026-09-21 10:39	50.31	OK	15846	2026-09-21 10:40	53.62	OK
15847	2026-09-21 10:41	50.12	OK	15848	2026-09-21 10:42	51.50	OK
15849	2026-09-21 10:43	52.35	OK	15850	2026-09-21 10:44	50.14	OK
15851	2026-09-21 10:45	49.22	OK	15852	2026-09-21 10:46	51.26	OK
15853	2026-09-21 10:47	50.33	OK	15854	2026-09-21 10:48	51.33	OK
15855	2026-09-21 10:49	51.29	OK	15856	2026-09-21 10:50	51.16	OK
15857	2026-09-21 10:51	52.36	OK	15858	2026-09-21 10:52	50.47	OK
15859	2026-09-21 10:53	51.53	OK	15860	2026-09-21 10:54	51.67	OK
15861	2026-09-21 10:55	49.50	OK	15862	2026-09-21 10:56	51.88	OK
15863	2026-09-21 10:57	50.03	OK	15864	2026-09-21 10:58	51.35	OK
15865	2026-09-21 10:59	51.03	OK	15866	2026-09-21 11:00	51.61	OK
15867	2026-09-21 11:01	51.67	OK	15868	2026-09-21 11:02	50.99	OK
15869	2026-09-21 11:03	51.02	OK	15870	2026-09-21 11:04	51.38	OK
15871	2026-09-21 11:05	50.70	OK	15872	2026-09-21 11:06	52.83	OK
15873	2026-09-21 11:07	50.41	OK	15874	2026-09-21 11:08	50.59	OK
1587	2026-09-21 11:09	51.98	OK	1587	2026-09-21 11:10	51.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
15877	2026-09-21 11:11	50.76	OK	15878	2026-09-21 11:12	49.92	OK
15879	2026-09-21 11:13	51.21	OK	15880	2026-09-21 11:14	52.03	OK
15881	2026-09-21 11:15	52.31	OK	15882	2026-09-21 11:16	50.90	OK
15883	2026-09-21 11:17	53.66	OK	15884	2026-09-21 11:18	51.31	OK
15885	2026-09-21 11:19	49.78	OK	15886	2026-09-21 11:20	50.62	OK
15887	2026-09-21 11:21	50.77	OK	15888	2026-09-21 11:22	52.36	OK
15889	2026-09-21 11:23	51.59	OK	15890	2026-09-21 11:24	51.22	OK
15891	2026-09-21 11:25	50.98	OK	15892	2026-09-21 11:26	50.93	OK
15893	2026-09-21 11:27	50.79	OK	15894	2026-09-21 11:28	50.71	OK
15895	2026-09-21 11:29	50.05	OK	15896	2026-09-21 11:30	52.03	OK
15897	2026-09-21 11:31	50.17	OK	15898	2026-09-21 11:32	50.28	OK
15899	2026-09-21 11:33	51.76	OK	15900	2026-09-21 11:34	52.68	OK
15901	2026-09-21 11:35	51.66	OK	15902	2026-09-21 11:36	51.87	OK
15903	2026-09-21 11:37	51.85	OK	15904	2026-09-21 11:38	53.14	OK
15905	2026-09-21 11:39	54.02	OK	15906	2026-09-21 11:40	53.59	OK
15907	2026-09-21 11:41	51.50	OK	15908	2026-09-21 11:42	51.98	OK
15909	2026-09-21 11:43	52.47	OK	15910	2026-09-21 11:44	51.91	OK
15911	2026-09-21 11:45	52.81	OK	15912	2026-09-21 11:46	50.70	OK
15913	2026-09-21 11:47	52.65	OK	15914	2026-09-21 11:48	52.64	OK
15915	2026-09-21 11:49	50.34	OK	15916	2026-09-21 11:50	49.40	OK
15917	2026-09-21 11:51	51.15	OK	15918	2026-09-21 11:52	52.13	OK
15919	2026-09-21 11:53	51.02	OK	15920	2026-09-21 11:54	52.04	OK
15921	2026-09-21 11:55	50.86	OK	15922	2026-09-21 11:56	52.84	OK
15923	2026-09-21 11:57	51.81	OK	15924	2026-09-21 11:58	50.78	OK
15925	2026-09-21 11:59	49.57	OK	15926	2026-09-21 12:00	49.95	OK
15927	2026-09-21 12:01	52.19	OK	15928	2026-09-21 12:02	52.50	OK
15929	2026-09-21 12:03	51.61	OK	15930	2026-09-21 12:04	50.80	OK
15931	2026-09-21 12:05	52.33	OK	15932	2026-09-21 12:06	52.99	OK
15933	2026-09-21 12:07	52.33	OK	15934	2026-09-21 12:08	53.78	OK
15935	2026-09-21 12:09	51.78	OK	15935	2026-09-21 12:10	52.98	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
15937	2026-09-21 12:11	53.07	OK	15938	2026-09-21 12:12	52.24	OK
15939	2026-09-21 12:13	51.42	OK	15940	2026-09-21 12:14	53.05	OK
15941	2026-09-21 12:15	50.23	OK	15942	2026-09-21 12:16	52.30	OK
15943	2026-09-21 12:17	50.84	OK	15944	2026-09-21 12:18	50.38	OK
15945	2026-09-21 12:19	51.81	OK	15946	2026-09-21 12:20	52.41	OK
15947	2026-09-21 12:21	51.44	OK	15948	2026-09-21 12:22	51.07	OK
15949	2026-09-21 12:23	52.71	OK	15950	2026-09-21 12:24	51.96	OK
15951	2026-09-21 12:25	51.29	OK	15952	2026-09-21 12:26	51.19	OK
15953	2026-09-21 12:27	53.06	OK	15954	2026-09-21 12:28	51.55	OK
15955	2026-09-21 12:29	49.92	OK	15956	2026-09-21 12:30	50.83	OK
15957	2026-09-21 12:31	52.25	OK	15958	2026-09-21 12:32	51.41	OK
15959	2026-09-21 12:33	51.89	OK	15960	2026-09-21 12:34	53.47	OK
15961	2026-09-21 12:35	50.25	OK	15962	2026-09-21 12:36	52.30	OK
15963	2026-09-21 12:37	51.42	OK	15964	2026-09-21 12:38	52.70	OK
15965	2026-09-21 12:39	52.17	OK	15966	2026-09-21 12:40	50.01	OK
15967	2026-09-21 12:41	49.63	OK	15968	2026-09-21 12:42	52.75	OK
15969	2026-09-21 12:43	52.96	OK	15970	2026-09-21 12:44	49.91	OK
15971	2026-09-21 12:45	52.51	OK	15972	2026-09-21 12:46	51.37	OK
15973	2026-09-21 12:47	51.92	OK	15974	2026-09-21 12:48	51.14	OK
15975	2026-09-21 12:49	52.56	OK	15976	2026-09-21 12:50	52.48	OK
15977	2026-09-21 12:51	51.40	OK	15978	2026-09-21 12:52	52.83	OK
15979	2026-09-21 12:53	52.67	OK	15980	2026-09-21 12:54	50.42	OK
15981	2026-09-21 12:55	49.52	OK	15982	2026-09-21 12:56	50.35	OK
15983	2026-09-21 12:57	51.70	OK	15984	2026-09-21 12:58	51.48	OK
15985	2026-09-21 12:59	50.16	OK	15986	2026-09-21 13:00	53.85	OK
15987	2026-09-21 13:01	51.27	OK	15988	2026-09-21 13:02	52.60	OK
15989	2026-09-21 13:03	51.16	OK	15990	2026-09-21 13:04	52.66	OK
15991	2026-09-21 13:05	50.85	OK	15992	2026-09-21 13:06	50.90	OK
15993	2026-09-21 13:07	50.16	OK	15994	2026-09-21 13:08	51.28	OK
1599	2026-09-21 13:09	50.69	OK	1599	2026-09-21 13:10	53.10	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
15997	2026-09-21 13:11	50.85	OK	15998	2026-09-21 13:12	54.29	OK
15999	2026-09-21 13:13	52.18	OK	16000	2026-09-21 13:14	51.26	OK
16001	2026-09-21 13:15	52.35	OK	16002	2026-09-21 13:16	52.24	OK
16003	2026-09-21 13:17	52.50	OK	16004	2026-09-21 13:18	52.27	OK
16005	2026-09-21 13:19	51.42	OK	16006	2026-09-21 13:20	53.14	OK
16007	2026-09-21 13:21	51.34	OK	16008	2026-09-21 13:22	51.57	OK
16009	2026-09-21 13:23	50.16	OK	16010	2026-09-21 13:24	52.77	OK
16011	2026-09-21 13:25	51.14	OK	16012	2026-09-21 13:26	51.48	OK
16013	2026-09-21 13:27	50.52	OK	16014	2026-09-21 13:28	51.45	OK
16015	2026-09-21 13:29	51.63	OK	16016	2026-09-21 13:30	51.46	OK
16017	2026-09-21 13:31	51.74	OK	16018	2026-09-21 13:32	51.58	OK
16019	2026-09-21 13:33	51.25	OK	16020	2026-09-21 13:34	50.85	OK
16021	2026-09-21 13:35	52.58	OK	16022	2026-09-21 13:36	53.88	OK
16023	2026-09-21 13:37	53.13	OK	16024	2026-09-21 13:38	52.38	OK
16025	2026-09-21 13:39	52.92	OK	16026	2026-09-21 13:40	52.50	OK
16027	2026-09-21 13:41	52.71	OK	16028	2026-09-21 13:42	52.82	OK
16029	2026-09-21 13:43	51.63	OK	16030	2026-09-21 13:44	53.55	OK
16031	2026-09-21 13:45	50.86	OK	16032	2026-09-21 13:46	52.72	OK
16033	2026-09-21 13:47	52.40	OK	16034	2026-09-21 13:48	52.05	OK
16035	2026-09-21 13:49	52.77	OK	16036	2026-09-21 13:50	52.48	OK
16037	2026-09-21 13:51	51.84	OK	16038	2026-09-21 13:52	52.10	OK
16039	2026-09-21 13:53	52.12	OK	16040	2026-09-21 13:54	52.20	OK
16041	2026-09-21 13:55	50.59	OK	16042	2026-09-21 13:56	53.54	OK
16043	2026-09-21 13:57	52.60	OK	16044	2026-09-21 13:58	51.33	OK
16045	2026-09-21 13:59	52.35	OK	16046	2026-09-21 14:00	50.63	OK
16047	2026-09-21 14:01	51.35	OK	16048	2026-09-21 14:02	50.92	OK
16049	2026-09-21 14:03	51.32	OK	16050	2026-09-21 14:04	50.75	OK
16051	2026-09-21 14:05	52.29	OK	16052	2026-09-21 14:06	51.80	OK
16053	2026-09-21 14:07	53.95	OK	16054	2026-09-21 14:08	52.91	OK
1605	2026-09-21 14:09	52.15	OK	1605	2026-09-21 14:10	52.54	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
16057	2026-09-21 14:11	53.08	OK	16058	2026-09-21 14:12	52.18	OK
16059	2026-09-21 14:13	51.45	OK	16060	2026-09-21 14:14	49.57	OK
16061	2026-09-21 14:15	51.04	OK	16062	2026-09-21 14:16	52.67	OK
16063	2026-09-21 14:17	51.79	OK	16064	2026-09-21 14:18	52.15	OK
16065	2026-09-21 14:19	51.92	OK	16066	2026-09-21 14:20	52.63	OK
16067	2026-09-21 14:21	51.14	OK	16068	2026-09-21 14:22	50.34	OK
16069	2026-09-21 14:23	51.67	OK	16070	2026-09-21 14:24	50.70	OK
16071	2026-09-21 14:25	51.21	OK	16072	2026-09-21 14:26	50.43	OK
16073	2026-09-21 14:27	50.98	OK	16074	2026-09-21 14:28	52.82	OK
16075	2026-09-21 14:29	50.35	OK	16076	2026-09-21 14:30	50.12	OK
16077	2026-09-21 14:31	52.47	OK	16078	2026-09-21 14:32	50.82	OK
16079	2026-09-21 14:33	53.62	OK	16080	2026-09-21 14:34	51.85	OK
16081	2026-09-21 14:35	51.19	OK	16082	2026-09-21 14:36	51.79	OK
16083	2026-09-21 14:37	52.42	OK	16084	2026-09-21 14:38	52.46	OK
16085	2026-09-21 14:39	49.47	OK	16086	2026-09-21 14:40	51.16	OK
16087	2026-09-21 14:41	51.33	OK	16088	2026-09-21 14:42	51.75	OK
16089	2026-09-21 14:43	51.94	OK	16090	2026-09-21 14:44	50.82	OK
16091	2026-09-21 14:45	52.44	OK	16092	2026-09-21 14:46	50.67	OK
16093	2026-09-21 14:47	50.73	OK	16094	2026-09-21 14:48	52.44	OK
16095	2026-09-21 14:49	51.61	OK	16096	2026-09-21 14:50	52.56	OK
16097	2026-09-21 14:51	51.63	OK	16098	2026-09-21 14:52	50.08	OK
16099	2026-09-21 14:53	52.12	OK	16100	2026-09-21 14:54	51.84	OK
16101	2026-09-21 14:55	51.40	OK	16102	2026-09-21 14:56	50.63	OK
16103	2026-09-21 14:57	51.29	OK	16104	2026-09-21 14:58	52.05	OK
16105	2026-09-21 14:59	51.88	OK	16106	2026-09-21 15:00	52.66	OK
16107	2026-09-21 15:01	52.02	OK	16108	2026-09-21 15:02	51.83	OK
16109	2026-09-21 15:03	52.76	OK	16110	2026-09-21 15:04	51.70	OK
16111	2026-09-21 15:05	50.83	OK	16112	2026-09-21 15:06	52.02	OK
16113	2026-09-21 15:07	51.26	OK	16114	2026-09-21 15:08	49.68	OK
1611	2026-09-21 15:09	50.96	OK	1611	2026-09-21 15:10	50.83	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
16117	2026-09-21 15:11	51.65	OK	16118	2026-09-21 15:12	50.85	OK
16119	2026-09-21 15:13	52.58	OK	16120	2026-09-21 15:14	51.23	OK
16121	2026-09-21 15:15	49.07	OK	16122	2026-09-21 15:16	51.43	OK
16123	2026-09-21 15:17	51.15	OK	16124	2026-09-21 15:18	53.08	OK
16125	2026-09-21 15:19	52.37	OK	16126	2026-09-21 15:20	52.68	OK
16127	2026-09-21 15:21	53.32	OK	16128	2026-09-21 15:22	51.19	OK
16129	2026-09-21 15:23	51.96	OK	16130	2026-09-21 15:24	54.01	OK
16131	2026-09-21 15:25	50.01	OK	16132	2026-09-21 15:26	51.48	OK
16133	2026-09-21 15:27	52.99	OK	16134	2026-09-21 15:28	50.33	OK
16135	2026-09-21 15:29	49.93	OK	16136	2026-09-21 15:30	51.69	OK
16137	2026-09-21 15:31	51.61	OK	16138	2026-09-21 15:32	52.65	OK
16139	2026-09-21 15:33	51.33	OK	16140	2026-09-21 15:34	51.12	OK
16141	2026-09-21 15:35	50.69	OK	16142	2026-09-21 15:36	51.43	OK
16143	2026-09-21 15:37	51.85	OK	16144	2026-09-21 15:38	50.25	OK
16145	2026-09-21 15:39	49.83	OK	16146	2026-09-21 15:40	51.08	OK
16147	2026-09-21 15:41	50.95	OK	16148	2026-09-21 15:42	49.73	OK
16149	2026-09-21 15:43	51.89	OK	16150	2026-09-21 15:44	51.67	OK
16151	2026-09-21 15:45	49.60	OK	16152	2026-09-21 15:46	52.97	OK
16153	2026-09-21 15:47	50.15	OK	16154	2026-09-21 15:48	51.35	OK
16155	2026-09-21 15:49	50.58	OK	16156	2026-09-21 15:50	49.88	OK
16157	2026-09-21 15:51	52.02	OK	16158	2026-09-21 15:52	51.06	OK
16159	2026-09-21 15:53	51.19	OK	16160	2026-09-21 15:54	51.13	OK
16161	2026-09-21 15:55	52.08	OK	16162	2026-09-21 15:56	52.41	OK
16163	2026-09-21 15:57	51.17	OK	16164	2026-09-21 15:58	51.88	OK
16165	2026-09-21 15:59	52.21	OK	16166	2026-09-21 16:00	52.32	OK
16167	2026-09-21 16:01	52.04	OK	16168	2026-09-21 16:02	50.21	OK
16169	2026-09-21 16:03	51.22	OK	16170	2026-09-21 16:04	51.23	OK
16171	2026-09-21 16:05	50.95	OK	16172	2026-09-21 16:06	52.04	OK
16173	2026-09-21 16:07	51.22	OK	16174	2026-09-21 16:08	51.64	OK
1617	2026-09-21 16:09	51.44	OK	1617	2026-09-21 16:10	49.85	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
16177	2026-09-21 16:11	49.97	OK	16178	2026-09-21 16:12	49.25	OK
16179	2026-09-21 16:13	49.22	OK	16180	2026-09-21 16:14	51.86	OK
16181	2026-09-21 16:15	52.97	OK	16182	2026-09-21 16:16	51.43	OK
16183	2026-09-21 16:17	48.94	OK	16184	2026-09-21 16:18	50.54	OK
16185	2026-09-21 16:19	48.65	OK	16186	2026-09-21 16:20	50.35	OK
16187	2026-09-21 16:21	52.58	OK	16188	2026-09-21 16:22	50.81	OK
16189	2026-09-21 16:23	50.91	OK	16190	2026-09-21 16:24	51.00	OK
16191	2026-09-21 16:25	49.70	OK	16192	2026-09-21 16:26	49.03	OK
16193	2026-09-21 16:27	51.70	OK	16194	2026-09-21 16:28	52.32	OK
16195	2026-09-21 16:29	52.09	OK	16196	2026-09-21 16:30	51.05	OK
16197	2026-09-21 16:31	51.42	OK	16198	2026-09-21 16:32	51.84	OK
16199	2026-09-21 16:33	49.37	OK	16200	2026-09-21 16:34	50.62	OK
16201	2026-09-21 16:35	51.41	OK	16202	2026-09-21 16:36	51.09	OK
16203	2026-09-21 16:37	49.48	OK	16204	2026-09-21 16:38	51.06	OK
16205	2026-09-21 16:39	50.98	OK	16206	2026-09-21 16:40	50.59	OK
16207	2026-09-21 16:41	50.87	OK	16208	2026-09-21 16:42	51.43	OK
16209	2026-09-21 16:43	49.75	OK	16210	2026-09-21 16:44	50.09	OK
16211	2026-09-21 16:45	51.07	OK	16212	2026-09-21 16:46	50.38	OK
16213	2026-09-21 16:47	49.07	OK	16214	2026-09-21 16:48	49.66	OK
16215	2026-09-21 16:49	52.09	OK	16216	2026-09-21 16:50	49.43	OK
16217	2026-09-21 16:51	48.20	OK	16218	2026-09-21 16:52	50.46	OK
16219	2026-09-21 16:53	49.85	OK	16220	2026-09-21 16:54	48.53	OK
16221	2026-09-21 16:55	48.88	OK	16222	2026-09-21 16:56	50.20	OK
16223	2026-09-21 16:57	49.07	OK	16224	2026-09-21 16:58	51.51	OK
16225	2026-09-21 16:59	50.60	OK	16226	2026-09-21 17:00	51.37	OK
16227	2026-09-21 17:01	48.99	OK	16228	2026-09-21 17:02	51.28	OK
16229	2026-09-21 17:03	50.71	OK	16230	2026-09-21 17:04	48.96	OK
16231	2026-09-21 17:05	49.75	OK	16232	2026-09-21 17:06	51.31	OK
16233	2026-09-21 17:07	51.50	OK	16234	2026-09-21 17:08	51.35	OK
1623	2026-09-21 17:09	49.62	OK	1623	2026-09-21 17:10	49.91	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
16237	2026-09-21 17:11	51.35	OK	16238	2026-09-21 17:12	47.96	OK
16239	2026-09-21 17:13	52.58	OK	16240	2026-09-21 17:14	49.14	OK
16241	2026-09-21 17:15	50.34	OK	16242	2026-09-21 17:16	49.44	OK
16243	2026-09-21 17:17	49.08	OK	16244	2026-09-21 17:18	48.39	OK
16245	2026-09-21 17:19	51.23	OK	16246	2026-09-21 17:20	49.27	OK
16247	2026-09-21 17:21	51.54	OK	16248	2026-09-21 17:22	51.27	OK
16249	2026-09-21 17:23	49.43	OK	16250	2026-09-21 17:24	48.99	OK
16251	2026-09-21 17:25	49.06	OK	16252	2026-09-21 17:26	49.68	OK
16253	2026-09-21 17:27	50.04	OK	16254	2026-09-21 17:28	49.59	OK
16255	2026-09-21 17:29	51.11	OK	16256	2026-09-21 17:30	50.07	OK
16257	2026-09-21 17:31	51.18	OK	16258	2026-09-21 17:32	50.18	OK
16259	2026-09-21 17:33	49.37	OK	16260	2026-09-21 17:34	50.48	OK
16261	2026-09-21 17:35	49.75	OK	16262	2026-09-21 17:36	50.99	OK
16263	2026-09-21 17:37	50.24	OK	16264	2026-09-21 17:38	48.94	OK
16265	2026-09-21 17:39	47.69	OK	16266	2026-09-21 17:40	48.95	OK
16267	2026-09-21 17:41	49.59	OK	16268	2026-09-21 17:42	49.95	OK
16269	2026-09-21 17:43	50.84	OK	16270	2026-09-21 17:44	48.95	OK
16271	2026-09-21 17:45	50.25	OK	16272	2026-09-21 17:46	51.23	OK
16273	2026-09-21 17:47	49.43	OK	16274	2026-09-21 17:48	50.21	OK
16275	2026-09-21 17:49	51.89	OK	16276	2026-09-21 17:50	47.98	OK
16277	2026-09-21 17:51	51.53	OK	16278	2026-09-21 17:52	51.06	OK
16279	2026-09-21 17:53	48.33	OK	16280	2026-09-21 17:54	50.51	OK
16281	2026-09-21 17:55	50.18	OK	16282	2026-09-21 17:56	48.72	OK
16283	2026-09-21 17:57	48.46	OK	16284	2026-09-21 17:58	48.70	OK
16285	2026-09-21 17:59	50.05	OK	16286	2026-09-21 18:00	48.97	OK
16287	2026-09-21 18:01	48.55	OK	16288	2026-09-21 18:02	50.27	OK
16289	2026-09-21 18:03	49.59	OK	16290	2026-09-21 18:04	50.58	OK
16291	2026-09-21 18:05	48.94	OK	16292	2026-09-21 18:06	49.68	OK
16293	2026-09-21 18:07	46.93	OK	16294	2026-09-21 18:08	48.79	OK
1629	2026-09-21 18:09	50.36	OK	1629	2026-09-21 18:10	50.48	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
16297	2026-09-21 18:11	50.51	OK	16298	2026-09-21 18:12	49.76	OK
16299	2026-09-21 18:13	51.35	OK	16300	2026-09-21 18:14	48.63	OK
16301	2026-09-21 18:15	48.73	OK	16302	2026-09-21 18:16	48.99	OK
16303	2026-09-21 18:17	48.44	OK	16304	2026-09-21 18:18	49.29	OK
16305	2026-09-21 18:19	48.98	OK	16306	2026-09-21 18:20	51.60	OK
16307	2026-09-21 18:21	49.46	OK	16308	2026-09-21 18:22	47.53	OK
16309	2026-09-21 18:23	49.38	OK	16310	2026-09-21 18:24	50.86	OK
16311	2026-09-21 18:25	49.34	OK	16312	2026-09-21 18:26	49.69	OK
16313	2026-09-21 18:27	48.02	OK	16314	2026-09-21 18:28	47.82	OK
16315	2026-09-21 18:29	49.13	OK	16316	2026-09-21 18:30	49.67	OK
16317	2026-09-21 18:31	49.37	OK	16318	2026-09-21 18:32	49.81	OK
16319	2026-09-21 18:33	48.82	OK	16320	2026-09-21 18:34	50.36	OK
16321	2026-09-21 18:35	49.26	OK	16322	2026-09-21 18:36	49.51	OK
16323	2026-09-21 18:37	48.73	OK	16324	2026-09-21 18:38	48.56	OK
16325	2026-09-21 18:39	50.26	OK	16326	2026-09-21 18:40	48.42	OK
16327	2026-09-21 18:41	49.48	OK	16328	2026-09-21 18:42	48.46	OK
16329	2026-09-21 18:43	50.10	OK	16330	2026-09-21 18:44	48.74	OK
16331	2026-09-21 18:45	48.05	OK	16332	2026-09-21 18:46	50.09	OK
16333	2026-09-21 18:47	47.25	OK	16334	2026-09-21 18:48	48.89	OK
16335	2026-09-21 18:49	48.65	OK	16336	2026-09-21 18:50	50.54	OK
16337	2026-09-21 18:51	49.30	OK	16338	2026-09-21 18:52	48.20	OK
16339	2026-09-21 18:53	50.69	OK	16340	2026-09-21 18:54	48.42	OK
16341	2026-09-21 18:55	50.04	OK	16342	2026-09-21 18:56	47.69	OK
16343	2026-09-21 18:57	49.49	OK	16344	2026-09-21 18:58	50.70	OK
16345	2026-09-21 18:59	48.28	OK	16346	2026-09-21 19:00	49.07	OK
16347	2026-09-21 19:01	49.31	OK	16348	2026-09-21 19:02	49.88	OK
16349	2026-09-21 19:03	49.95	OK	16350	2026-09-21 19:04	48.01	OK
16351	2026-09-21 19:05	48.01	OK	16352	2026-09-21 19:06	48.02	OK
16353	2026-09-21 19:07	48.28	OK	16354	2026-09-21 19:08	49.56	OK
1635	2026-09-21 19:09	48.31	OK	1635	2026-09-21 19:10	49.72	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
16357	2026-09-21 19:11	47.31	OK	16358	2026-09-21 19:12	47.37	OK
16359	2026-09-21 19:13	49.54	OK	16360	2026-09-21 19:14	47.94	OK
16361	2026-09-21 19:15	48.05	OK	16362	2026-09-21 19:16	49.10	OK
16363	2026-09-21 19:17	49.72	OK	16364	2026-09-21 19:18	47.94	OK
16365	2026-09-21 19:19	49.46	OK	16366	2026-09-21 19:20	47.07	OK
16367	2026-09-21 19:21	50.50	OK	16368	2026-09-21 19:22	48.45	OK
16369	2026-09-21 19:23	47.20	OK	16370	2026-09-21 19:24	47.32	OK
16371	2026-09-21 19:25	46.12	OK	16372	2026-09-21 19:26	47.85	OK
16373	2026-09-21 19:27	47.95	OK	16374	2026-09-21 19:28	50.90	OK
16375	2026-09-21 19:29	48.63	OK	16376	2026-09-21 19:30	50.51	OK
16377	2026-09-21 19:31	48.01	OK	16378	2026-09-21 19:32	49.50	OK
16379	2026-09-21 19:33	49.00	OK	16380	2026-09-21 19:34	49.21	OK
16381	2026-09-21 19:35	49.10	OK	16382	2026-09-21 19:36	49.17	OK
16383	2026-09-21 19:37	46.22	OK	16384	2026-09-21 19:38	46.72	OK
16385	2026-09-21 19:39	47.62	OK	16386	2026-09-21 19:40	48.15	OK
16387	2026-09-21 19:41	47.17	OK	16388	2026-09-21 19:42	47.78	OK
16389	2026-09-21 19:43	48.92	OK	16390	2026-09-21 19:44	47.88	OK
16391	2026-09-21 19:45	47.74	OK	16392	2026-09-21 19:46	47.60	OK
16393	2026-09-21 19:47	49.46	OK	16394	2026-09-21 19:48	48.71	OK
16395	2026-09-21 19:49	48.02	OK	16396	2026-09-21 19:50	49.62	OK
16397	2026-09-21 19:51	48.47	OK	16398	2026-09-21 19:52	48.78	OK
16399	2026-09-21 19:53	46.94	OK	16400	2026-09-21 19:54	47.37	OK
16401	2026-09-21 19:55	49.01	OK	16402	2026-09-21 19:56	48.19	OK
16403	2026-09-21 19:57	46.35	OK	16404	2026-09-21 19:58	47.18	OK
16405	2026-09-21 19:59	46.32	OK	16406	2026-09-21 20:00	47.79	OK
16407	2026-09-21 20:01	48.88	OK	16408	2026-09-21 20:02	48.58	OK
16409	2026-09-21 20:03	49.09	OK	16410	2026-09-21 20:04	47.32	OK
16411	2026-09-21 20:05	48.48	OK	16412	2026-09-21 20:06	46.17	OK
16413	2026-09-21 20:07	49.13	OK	16414	2026-09-21 20:08	48.94	OK
1641	2026-09-21 20:09	47.28	OK	1641	2026-09-21 20:10	48.03	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
16417	2026-09-21 20:11	48.40	OK	16418	2026-09-21 20:12	49.26	OK
16419	2026-09-21 20:13	48.16	OK	16420	2026-09-21 20:14	47.47	OK
16421	2026-09-21 20:15	47.32	OK	16422	2026-09-21 20:16	47.57	OK
16423	2026-09-21 20:17	48.67	OK	16424	2026-09-21 20:18	47.66	OK
16425	2026-09-21 20:19	50.11	OK	16426	2026-09-21 20:20	48.16	OK
16427	2026-09-21 20:21	48.51	OK	16428	2026-09-21 20:22	46.36	OK
16429	2026-09-21 20:23	49.05	OK	16430	2026-09-21 20:24	48.62	OK
16431	2026-09-21 20:25	48.24	OK	16432	2026-09-21 20:26	46.59	OK
16433	2026-09-21 20:27	48.13	OK	16434	2026-09-21 20:28	47.87	OK
16435	2026-09-21 20:29	47.58	OK	16436	2026-09-21 20:30	49.77	OK
16437	2026-09-21 20:31	48.86	OK	16438	2026-09-21 20:32	48.31	OK
16439	2026-09-21 20:33	48.14	OK	16440	2026-09-21 20:34	48.06	OK
16441	2026-09-21 20:35	48.77	OK	16442	2026-09-21 20:36	48.02	OK
16443	2026-09-21 20:37	47.35	OK	16444	2026-09-21 20:38	48.28	OK
16445	2026-09-21 20:39	47.71	OK	16446	2026-09-21 20:40	47.85	OK
16447	2026-09-21 20:41	47.85	OK	16448	2026-09-21 20:42	45.92	OK
16449	2026-09-21 20:43	46.52	OK	16450	2026-09-21 20:44	47.61	OK
16451	2026-09-21 20:45	47.18	OK	16452	2026-09-21 20:46	48.95	OK
16453	2026-09-21 20:47	48.19	OK	16454	2026-09-21 20:48	46.46	OK
16455	2026-09-21 20:49	48.43	OK	16456	2026-09-21 20:50	45.39	OK
16457	2026-09-21 20:51	47.91	OK	16458	2026-09-21 20:52	45.37	OK
16459	2026-09-21 20:53	49.73	OK	16460	2026-09-21 20:54	47.11	OK
16461	2026-09-21 20:55	47.29	OK	16462	2026-09-21 20:56	46.56	OK
16463	2026-09-21 20:57	47.17	OK	16464	2026-09-21 20:58	48.60	OK
16465	2026-09-21 20:59	47.53	OK	16466	2026-09-21 21:00	48.44	OK
16467	2026-09-21 21:01	45.81	OK	16468	2026-09-21 21:02	46.92	OK
16469	2026-09-21 21:03	47.26	OK	16470	2026-09-21 21:04	46.96	OK
16471	2026-09-21 21:05	47.94	OK	16472	2026-09-21 21:06	45.15	OK
16473	2026-09-21 21:07	47.53	OK	16474	2026-09-21 21:08	46.16	OK
1647	2026-09-21 21:09	46.74	OK	1647	2026-09-21 21:10	47.61	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
16477	2026-09-21 21:11	45.43	OK	16478	2026-09-21 21:12	47.41	OK
16479	2026-09-21 21:13	46.65	OK	16480	2026-09-21 21:14	47.16	OK
16481	2026-09-21 21:15	47.55	OK	16482	2026-09-21 21:16	47.49	OK
16483	2026-09-21 21:17	48.29	OK	16484	2026-09-21 21:18	47.15	OK
16485	2026-09-21 21:19	47.84	OK	16486	2026-09-21 21:20	47.47	OK
16487	2026-09-21 21:21	46.69	OK	16488	2026-09-21 21:22	45.40	OK
16489	2026-09-21 21:23	46.18	OK	16490	2026-09-21 21:24	46.53	OK
16491	2026-09-21 21:25	47.55	OK	16492	2026-09-21 21:26	46.99	OK
16493	2026-09-21 21:27	46.85	OK	16494	2026-09-21 21:28	48.25	OK
16495	2026-09-21 21:29	47.01	OK	16496	2026-09-21 21:30	46.69	OK
16497	2026-09-21 21:31	46.01	OK	16498	2026-09-21 21:32	44.70	OK
16499	2026-09-21 21:33	47.90	OK	16500	2026-09-21 21:34	46.44	OK
16501	2026-09-21 21:35	48.06	OK	16502	2026-09-21 21:36	46.98	OK
16503	2026-09-21 21:37	45.07	OK	16504	2026-09-21 21:38	46.45	OK
16505	2026-09-21 21:39	45.14	OK	16506	2026-09-21 21:40	47.89	OK
16507	2026-09-21 21:41	46.35	OK	16508	2026-09-21 21:42	46.70	OK
16509	2026-09-21 21:43	46.14	OK	16510	2026-09-21 21:44	45.96	OK
16511	2026-09-21 21:45	45.40	OK	16512	2026-09-21 21:46	46.63	OK
16513	2026-09-21 21:47	45.61	OK	16514	2026-09-21 21:48	45.44	OK
16515	2026-09-21 21:49	44.20	OK	16516	2026-09-21 21:50	44.93	OK
16517	2026-09-21 21:51	48.47	OK	16518	2026-09-21 21:52	45.14	OK
16519	2026-09-21 21:53	46.50	OK	16520	2026-09-21 21:54	46.23	OK
16521	2026-09-21 21:55	46.09	OK	16522	2026-09-21 21:56	47.95	OK
16523	2026-09-21 21:57	46.97	OK	16524	2026-09-21 21:58	46.13	OK
16525	2026-09-21 21:59	47.94	OK	16526	2026-09-21 22:00	46.62	OK
16527	2026-09-21 22:01	46.00	OK	16528	2026-09-21 22:02	46.76	OK
16529	2026-09-21 22:03	45.98	OK	16530	2026-09-21 22:04	46.54	OK
16531	2026-09-21 22:05	46.34	OK	16532	2026-09-21 22:06	45.15	OK
16533	2026-09-21 22:07	45.79	OK	16534	2026-09-21 22:08	46.02	OK
1653	2026-09-21 22:09	45.38	OK	1653	2026-09-21 22:10	45.60	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
16537	2026-09-21 22:11	44.50	OK	16538	2026-09-21 22:12	46.88	OK
16539	2026-09-21 22:13	45.91	OK	16540	2026-09-21 22:14	44.39	OK
16541	2026-09-21 22:15	46.07	OK	16542	2026-09-21 22:16	47.70	OK
16543	2026-09-21 22:17	45.26	OK	16544	2026-09-21 22:18	45.03	OK
16545	2026-09-21 22:19	45.64	OK	16546	2026-09-21 22:20	45.55	OK
16547	2026-09-21 22:21	45.05	OK	16548	2026-09-21 22:22	46.49	OK
16549	2026-09-21 22:23	47.91	OK	16550	2026-09-21 22:24	46.34	OK
16551	2026-09-21 22:25	45.77	OK	16552	2026-09-21 22:26	45.83	OK
16553	2026-09-21 22:27	45.33	OK	16554	2026-09-21 22:28	46.25	OK
16555	2026-09-21 22:29	44.07	OK	16556	2026-09-21 22:30	47.15	OK
16557	2026-09-21 22:31	45.15	OK	16558	2026-09-21 22:32	46.68	OK
16559	2026-09-21 22:33	45.22	OK	16560	2026-09-21 22:34	47.49	OK
16561	2026-09-21 22:35	47.22	OK	16562	2026-09-21 22:36	47.45	OK
16563	2026-09-21 22:37	45.39	OK	16564	2026-09-21 22:38	45.92	OK
16565	2026-09-21 22:39	47.00	OK	16566	2026-09-21 22:40	47.13	OK
16567	2026-09-21 22:41	45.83	OK	16568	2026-09-21 22:42	47.01	OK
16569	2026-09-21 22:43	45.77	OK	16570	2026-09-21 22:44	46.70	OK
16571	2026-09-21 22:45	47.99	OK	16572	2026-09-21 22:46	45.76	OK
16573	2026-09-21 22:47	44.68	OK	16574	2026-09-21 22:48	46.86	OK
16575	2026-09-21 22:49	46.77	OK	16576	2026-09-21 22:50	44.57	OK
16577	2026-09-21 22:51	45.22	OK	16578	2026-09-21 22:52	45.04	OK
16579	2026-09-21 22:53	46.44	OK	16580	2026-09-21 22:54	45.28	OK
16581	2026-09-21 22:55	44.30	OK	16582	2026-09-21 22:56	46.64	OK
16583	2026-09-21 22:57	47.07	OK	16584	2026-09-21 22:58	47.02	OK
16585	2026-09-21 22:59	45.64	OK	16586	2026-09-21 23:00	44.65	OK
16587	2026-09-21 23:01	45.88	OK	16588	2026-09-21 23:02	45.97	OK
16589	2026-09-21 23:03	44.50	OK	16590	2026-09-21 23:04	45.39	OK
16591	2026-09-21 23:05	44.87	OK	16592	2026-09-21 23:06	46.53	OK
16593	2026-09-21 23:07	45.45	OK	16594	2026-09-21 23:08	43.54	OK
1659	2026-09-21 23:09	46.64	OK	1659	2026-09-21 23:10	46.14	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
16597	2026-09-21 23:11	44.17	OK	16598	2026-09-21 23:12	44.83	OK
16599	2026-09-21 23:13	47.45	OK	16600	2026-09-21 23:14	46.81	OK
16601	2026-09-21 23:15	46.37	OK	16602	2026-09-21 23:16	44.87	OK
16603	2026-09-21 23:17	45.63	OK	16604	2026-09-21 23:18	45.74	OK
16605	2026-09-21 23:19	46.18	OK	16606	2026-09-21 23:20	46.32	OK
16607	2026-09-21 23:21	46.10	OK	16608	2026-09-21 23:22	45.69	OK
16609	2026-09-21 23:23	45.34	OK	16610	2026-09-21 23:24	46.04	OK
16611	2026-09-21 23:25	47.18	OK	16612	2026-09-21 23:26	45.99	OK
16613	2026-09-21 23:27	45.79	OK	16614	2026-09-21 23:28	44.67	OK
16615	2026-09-21 23:29	44.39	OK	16616	2026-09-21 23:30	46.32	OK
16617	2026-09-21 23:31	45.81	OK	16618	2026-09-21 23:32	46.35	OK
16619	2026-09-21 23:33	45.59	OK	16620	2026-09-21 23:34	44.19	OK
16621	2026-09-21 23:35	45.66	OK	16622	2026-09-21 23:36	44.57	OK
16623	2026-09-21 23:37	46.90	OK	16624	2026-09-21 23:38	45.32	OK
16625	2026-09-21 23:39	44.83	OK	16626	2026-09-21 23:40	45.38	OK
16627	2026-09-21 23:41	45.11	OK	16628	2026-09-21 23:42	45.78	OK
16629	2026-09-21 23:43	44.18	OK	16630	2026-09-21 23:44	47.03	OK
16631	2026-09-21 23:45	44.85	OK	16632	2026-09-21 23:46	47.11	OK
16633	2026-09-21 23:47	45.08	OK	16634	2026-09-21 23:48	47.11	OK
16635	2026-09-21 23:49	45.47	OK	16636	2026-09-21 23:50	45.63	OK
16637	2026-09-21 23:51	46.93	OK	16638	2026-09-21 23:52	46.21	OK
16639	2026-09-21 23:53	46.77	OK	16640	2026-09-21 23:54	44.85	OK
16641	2026-09-21 23:55	44.04	OK	16642	2026-09-21 23:56	44.79	OK
16643	2026-09-21 23:57	45.69	OK	16644	2026-09-21 23:58	43.41	OK
16645	2026-09-21 23:59	46.73	OK	16646	2026-09-22 00:00	45.83	OK
16647	2026-09-22 00:01	45.06	OK	16648	2026-09-22 00:02	45.09	OK
16649	2026-09-22 00:03	45.50	OK	16650	2026-09-22 00:04	46.23	OK
16651	2026-09-22 00:05	45.60	OK	16652	2026-09-22 00:06	44.62	OK
16653	2026-09-22 00:07	43.87	OK	16654	2026-09-22 00:08	45.63	OK
1665	2026-09-22 00:09	45.77	OK	1665	2026-09-22 00:10	46.05	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
16657	2026-09-22 00:11	47.41	OK	16658	2026-09-22 00:12	44.03	OK
16659	2026-09-22 00:13	44.29	OK	16660	2026-09-22 00:14	45.05	OK
16661	2026-09-22 00:15	45.22	OK	16662	2026-09-22 00:16	44.00	OK
16663	2026-09-22 00:17	44.91	OK	16664	2026-09-22 00:18	46.16	OK
16665	2026-09-22 00:19	45.92	OK	16666	2026-09-22 00:20	46.21	OK
16667	2026-09-22 00:21	44.24	OK	16668	2026-09-22 00:22	43.89	OK
16669	2026-09-22 00:23	46.88	OK	16670	2026-09-22 00:24	44.24	OK
16671	2026-09-22 00:25	45.87	OK	16672	2026-09-22 00:26	44.36	OK
16673	2026-09-22 00:27	45.17	OK	16674	2026-09-22 00:28	44.02	OK
16675	2026-09-22 00:29	43.14	OK	16676	2026-09-22 00:30	45.28	OK
16677	2026-09-22 00:31	46.19	OK	16678	2026-09-22 00:32	44.86	OK
16679	2026-09-22 00:33	45.25	OK	16680	2026-09-22 00:34	44.54	OK
16681	2026-09-22 00:35	45.34	OK	16682	2026-09-22 00:36	45.29	OK
16683	2026-09-22 00:37	46.13	OK	16684	2026-09-22 00:38	45.32	OK
16685	2026-09-22 00:39	44.01	OK	16686	2026-09-22 00:40	44.72	OK
16687	2026-09-22 00:41	44.18	OK	16688	2026-09-22 00:42	45.51	OK
16689	2026-09-22 00:43	43.77	OK	16690	2026-09-22 00:44	44.75	OK
16691	2026-09-22 00:45	44.00	OK	16692	2026-09-22 00:46	44.85	OK
16693	2026-09-22 00:47	44.19	OK	16694	2026-09-22 00:48	44.86	OK
16695	2026-09-22 00:49	45.86	OK	16696	2026-09-22 00:50	43.98	OK
16697	2026-09-22 00:51	46.50	OK	16698	2026-09-22 00:52	44.88	OK
16699	2026-09-22 00:53	44.41	OK	16700	2026-09-22 00:54	44.48	OK
16701	2026-09-22 00:55	45.16	OK	16702	2026-09-22 00:56	46.75	OK
16703	2026-09-22 00:57	43.89	OK	16704	2026-09-22 00:58	46.45	OK
16705	2026-09-22 00:59	44.97	OK	16706	2026-09-22 01:00	44.41	OK
16707	2026-09-22 01:01	45.67	OK	16708	2026-09-22 01:02	45.62	OK
16709	2026-09-22 01:03	43.84	OK	16710	2026-09-22 01:04	45.36	OK
16711	2026-09-22 01:05	45.39	OK	16712	2026-09-22 01:06	44.14	OK
16713	2026-09-22 01:07	46.82	OK	16714	2026-09-22 01:08	44.27	OK
1671	2026-09-22 01:09	47.08	OK	1671	2026-09-22 01:10	45.16	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
16717	2026-09-22 01:11	44.00	OK	16718	2026-09-22 01:12	44.77	OK
16719	2026-09-22 01:13	46.56	OK	16720	2026-09-22 01:14	44.06	OK
16721	2026-09-22 01:15	44.76	OK	16722	2026-09-22 01:16	46.18	OK
16723	2026-09-22 01:17	45.60	OK	16724	2026-09-22 01:18	45.11	OK
16725	2026-09-22 01:19	43.04	OK	16726	2026-09-22 01:20	46.82	OK
16727	2026-09-22 01:21	45.02	OK	16728	2026-09-22 01:22	44.35	OK
16729	2026-09-22 01:23	45.75	OK	16730	2026-09-22 01:24	43.43	OK
16731	2026-09-22 01:25	46.37	OK	16732	2026-09-22 01:26	44.38	OK
16733	2026-09-22 01:27	45.99	OK	16734	2026-09-22 01:28	43.49	OK
16735	2026-09-22 01:29	45.86	OK	16736	2026-09-22 01:30	44.21	OK
16737	2026-09-22 01:31	45.50	OK	16738	2026-09-22 01:32	42.59	OK
16739	2026-09-22 01:33	44.76	OK	16740	2026-09-22 01:34	44.27	OK
16741	2026-09-22 01:35	46.68	OK	16742	2026-09-22 01:36	46.47	OK
16743	2026-09-22 01:37	43.75	OK	16744	2026-09-22 01:38	45.09	OK
16745	2026-09-22 01:39	45.47	OK	16746	2026-09-22 01:40	45.15	OK
16747	2026-09-22 01:41	44.29	OK	16748	2026-09-22 01:42	46.36	OK
16749	2026-09-22 01:43	44.84	OK	16750	2026-09-22 01:44	44.23	OK
16751	2026-09-22 01:45	44.62	OK	16752	2026-09-22 01:46	46.81	OK
16753	2026-09-22 01:47	44.01	OK	16754	2026-09-22 01:48	43.27	OK
16755	2026-09-22 01:49	46.83	OK	16756	2026-09-22 01:50	46.97	OK
16757	2026-09-22 01:51	46.32	OK	16758	2026-09-22 01:52	44.62	OK
16759	2026-09-22 01:53	46.31	OK	16760	2026-09-22 01:54	46.46	OK
16761	2026-09-22 01:55	43.54	OK	16762	2026-09-22 01:56	44.99	OK
16763	2026-09-22 01:57	43.91	OK	16764	2026-09-22 01:58	45.90	OK
16765	2026-09-22 01:59	46.19	OK	16766	2026-09-22 02:00	46.65	OK
16767	2026-09-22 02:01	44.83	OK	16768	2026-09-22 02:02	45.31	OK
16769	2026-09-22 02:03	44.77	OK	16770	2026-09-22 02:04	44.22	OK
16771	2026-09-22 02:05	45.42	OK	16772	2026-09-22 02:06	44.49	OK
16773	2026-09-22 02:07	45.52	OK	16774	2026-09-22 02:08	45.57	OK
1677	2026-09-22 02:09	44.26	OK	1677	2026-09-22 02:10	46.63	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
16777	2026-09-22 02:11	45.27	OK	16778	2026-09-22 02:12	46.21	OK
16779	2026-09-22 02:13	46.95	OK	16780	2026-09-22 02:14	45.75	OK
16781	2026-09-22 02:15	45.02	OK	16782	2026-09-22 02:16	44.08	OK
16783	2026-09-22 02:17	43.73	OK	16784	2026-09-22 02:18	46.58	OK
16785	2026-09-22 02:19	44.49	OK	16786	2026-09-22 02:20	46.45	OK
16787	2026-09-22 02:21	44.31	OK	16788	2026-09-22 02:22	46.14	OK
16789	2026-09-22 02:23	44.66	OK	16790	2026-09-22 02:24	44.43	OK
16791	2026-09-22 02:25	45.77	OK	16792	2026-09-22 02:26	44.79	OK
16793	2026-09-22 02:27	43.94	OK	16794	2026-09-22 02:28	46.15	OK
16795	2026-09-22 02:29	44.48	OK	16796	2026-09-22 02:30	44.74	OK
16797	2026-09-22 02:31	45.53	OK	16798	2026-09-22 02:32	43.87	OK
16799	2026-09-22 02:33	46.42	OK	16800	2026-09-22 02:34	43.81	OK
16801	2026-09-22 02:35	45.46	OK	16802	2026-09-22 02:36	45.38	OK
16803	2026-09-22 02:37	44.44	OK	16804	2026-09-22 02:38	46.81	OK
16805	2026-09-22 02:39	44.53	OK	16806	2026-09-22 02:40	45.30	OK
16807	2026-09-22 02:41	45.99	OK	16808	2026-09-22 02:42	45.92	OK
16809	2026-09-22 02:43	44.58	OK	16810	2026-09-22 02:44	43.20	OK
16811	2026-09-22 02:45	45.48	OK	16812	2026-09-22 02:46	46.08	OK
16813	2026-09-22 02:47	46.03	OK	16814	2026-09-22 02:48	46.83	OK
16815	2026-09-22 02:49	46.44	OK	16816	2026-09-22 02:50	46.41	OK
16817	2026-09-22 02:51	43.34	OK	16818	2026-09-22 02:52	44.81	OK
16819	2026-09-22 02:53	46.27	OK	16820	2026-09-22 02:54	43.97	OK
16821	2026-09-22 02:55	44.81	OK	16822	2026-09-22 02:56	45.16	OK
16823	2026-09-22 02:57	43.65	OK	16824	2026-09-22 02:58	46.31	OK
16825	2026-09-22 02:59	44.41	OK	16826	2026-09-22 03:00	45.32	OK
16827	2026-09-22 03:01	46.42	OK	16828	2026-09-22 03:02	47.37	OK
16829	2026-09-22 03:03	45.60	OK	16830	2026-09-22 03:04	44.45	OK
16831	2026-09-22 03:05	45.13	OK	16832	2026-09-22 03:06	44.46	OK
16833	2026-09-22 03:07	46.76	OK	16834	2026-09-22 03:08	43.18	OK
1683	2026-09-22 03:09	42.74	OK	1683	2026-09-22 03:10	44.77	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
16837	2026-09-22 03:11	45.28	OK	16838	2026-09-22 03:12	45.90	OK
16839	2026-09-22 03:13	44.61	OK	16840	2026-09-22 03:14	43.92	OK
16841	2026-09-22 03:15	44.77	OK	16842	2026-09-22 03:16	44.70	OK
16843	2026-09-22 03:17	44.97	OK	16844	2026-09-22 03:18	45.19	OK
16845	2026-09-22 03:19	45.96	OK	16846	2026-09-22 03:20	45.08	OK
16847	2026-09-22 03:21	46.38	OK	16848	2026-09-22 03:22	46.67	OK
16849	2026-09-22 03:23	44.85	OK	16850	2026-09-22 03:24	44.98	OK
16851	2026-09-22 03:25	47.15	OK	16852	2026-09-22 03:26	46.81	OK
16853	2026-09-22 03:27	44.99	OK	16854	2026-09-22 03:28	44.44	OK
16855	2026-09-22 03:29	46.54	OK	16856	2026-09-22 03:30	46.94	OK
16857	2026-09-22 03:31	43.88	OK	16858	2026-09-22 03:32	45.05	OK
16859	2026-09-22 03:33	44.66	OK	16860	2026-09-22 03:34	45.33	OK
16861	2026-09-22 03:35	44.43	OK	16862	2026-09-22 03:36	44.91	OK
16863	2026-09-22 03:37	46.72	OK	16864	2026-09-22 03:38	45.43	OK
16865	2026-09-22 03:39	43.89	OK	16866	2026-09-22 03:40	47.36	OK
16867	2026-09-22 03:41	45.71	OK	16868	2026-09-22 03:42	46.51	OK
16869	2026-09-22 03:43	45.59	OK	16870	2026-09-22 03:44	46.57	OK
16871	2026-09-22 03:45	46.75	OK	16872	2026-09-22 03:46	45.67	OK
16873	2026-09-22 03:47	45.00	OK	16874	2026-09-22 03:48	45.57	OK
16875	2026-09-22 03:49	46.35	OK	16876	2026-09-22 03:50	44.30	OK
16877	2026-09-22 03:51	45.65	OK	16878	2026-09-22 03:52	45.92	OK
16879	2026-09-22 03:53	44.87	OK	16880	2026-09-22 03:54	46.49	OK
16881	2026-09-22 03:55	46.18	OK	16882	2026-09-22 03:56	45.75	OK
16883	2026-09-22 03:57	45.94	OK	16884	2026-09-22 03:58	47.31	OK
16885	2026-09-22 03:59	45.11	OK	16886	2026-09-22 04:00	44.07	OK
16887	2026-09-22 04:01	46.57	OK	16888	2026-09-22 04:02	45.89	OK
16889	2026-09-22 04:03	46.29	OK	16890	2026-09-22 04:04	47.25	OK
16891	2026-09-22 04:05	47.03	OK	16892	2026-09-22 04:06	46.46	OK
16893	2026-09-22 04:07	45.86	OK	16894	2026-09-22 04:08	45.55	OK
1689	2026-09-22 04:09	44.95	OK	1689	2026-09-22 04:10	47.22	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
16897	2026-09-22 04:11	46.36	OK	16898	2026-09-22 04:12	47.67	OK
16899	2026-09-22 04:13	47.18	OK	16900	2026-09-22 04:14	47.39	OK
16901	2026-09-22 04:15	45.81	OK	16902	2026-09-22 04:16	44.68	OK
16903	2026-09-22 04:17	43.95	OK	16904	2026-09-22 04:18	45.68	OK
16905	2026-09-22 04:19	46.18	OK	16906	2026-09-22 04:20	45.64	OK
16907	2026-09-22 04:21	45.77	OK	16908	2026-09-22 04:22	48.45	OK
16909	2026-09-22 04:23	46.41	OK	16910	2026-09-22 04:24	46.39	OK
16911	2026-09-22 04:25	45.81	OK	16912	2026-09-22 04:26	46.15	OK
16913	2026-09-22 04:27	45.80	OK	16914	2026-09-22 04:28	46.05	OK
16915	2026-09-22 04:29	46.04	OK	16916	2026-09-22 04:30	45.59	OK
16917	2026-09-22 04:31	47.12	OK	16918	2026-09-22 04:32	45.70	OK
16919	2026-09-22 04:33	46.08	OK	16920	2026-09-22 04:34	46.68	OK
16921	2026-09-22 04:35	48.17	OK	16922	2026-09-22 04:36	46.02	OK
16923	2026-09-22 04:37	47.10	OK	16924	2026-09-22 04:38	47.61	OK
16925	2026-09-22 04:39	46.45	OK	16926	2026-09-22 04:40	46.31	OK
16927	2026-09-22 04:41	45.54	OK	16928	2026-09-22 04:42	45.65	OK
16929	2026-09-22 04:43	47.17	OK	16930	2026-09-22 04:44	46.44	OK
16931	2026-09-22 04:45	45.44	OK	16932	2026-09-22 04:46	47.61	OK
16933	2026-09-22 04:47	46.02	OK	16934	2026-09-22 04:48	45.80	OK
16935	2026-09-22 04:49	46.01	OK	16936	2026-09-22 04:50	44.88	OK
16937	2026-09-22 04:51	47.14	OK	16938	2026-09-22 04:52	45.29	OK
16939	2026-09-22 04:53	46.22	OK	16940	2026-09-22 04:54	44.05	OK
16941	2026-09-22 04:55	46.63	OK	16942	2026-09-22 04:56	47.22	OK
16943	2026-09-22 04:57	46.75	OK	16944	2026-09-22 04:58	46.74	OK
16945	2026-09-22 04:59	46.82	OK	16946	2026-09-22 05:00	45.95	OK
16947	2026-09-22 05:01	47.43	OK	16948	2026-09-22 05:02	46.37	OK
16949	2026-09-22 05:03	45.98	OK	16950	2026-09-22 05:04	46.20	OK
16951	2026-09-22 05:05	47.23	OK	16952	2026-09-22 05:06	46.83	OK
16953	2026-09-22 05:07	46.31	OK	16954	2026-09-22 05:08	46.60	OK
1695	2026-09-22 05:09	46.37	OK	1695	2026-09-22 05:10	44.60	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
16957	2026-09-22 05:11	46.10	OK	16958	2026-09-22 05:12	48.33	OK
16959	2026-09-22 05:13	45.79	OK	16960	2026-09-22 05:14	48.93	OK
16961	2026-09-22 05:15	46.18	OK	16962	2026-09-22 05:16	46.59	OK
16963	2026-09-22 05:17	47.83	OK	16964	2026-09-22 05:18	47.56	OK
16965	2026-09-22 05:19	48.81	OK	16966	2026-09-22 05:20	46.59	OK
16967	2026-09-22 05:21	44.92	OK	16968	2026-09-22 05:22	46.48	OK
16969	2026-09-22 05:23	45.87	OK	16970	2026-09-22 05:24	46.34	OK
16971	2026-09-22 05:25	46.13	OK	16972	2026-09-22 05:26	47.21	OK
16973	2026-09-22 05:27	45.40	OK	16974	2026-09-22 05:28	47.96	OK
16975	2026-09-22 05:29	46.83	OK	16976	2026-09-22 05:30	47.00	OK
16977	2026-09-22 05:31	46.26	OK	16978	2026-09-22 05:32	48.72	OK
16979	2026-09-22 05:33	45.69	OK	16980	2026-09-22 05:34	46.77	OK
16981	2026-09-22 05:35	47.19	OK	16982	2026-09-22 05:36	46.42	OK
16983	2026-09-22 05:37	46.44	OK	16984	2026-09-22 05:38	48.29	OK
16985	2026-09-22 05:39	46.04	OK	16986	2026-09-22 05:40	46.70	OK
16987	2026-09-22 05:41	45.67	OK	16988	2026-09-22 05:42	46.09	OK
16989	2026-09-22 05:43	48.26	OK	16990	2026-09-22 05:44	45.57	OK
16991	2026-09-22 05:45	45.76	OK	16992	2026-09-22 05:46	46.17	OK
16993	2026-09-22 05:47	48.30	OK	16994	2026-09-22 05:48	47.00	OK
16995	2026-09-22 05:49	47.14	OK	16996	2026-09-22 05:50	47.52	OK
16997	2026-09-22 05:51	47.17	OK	16998	2026-09-22 05:52	45.98	OK
16999	2026-09-22 05:53	45.78	OK	17000	2026-09-22 05:54	47.83	OK
17001	2026-09-22 05:55	46.61	OK	17002	2026-09-22 05:56	47.10	OK
17003	2026-09-22 05:57	47.43	OK	17004	2026-09-22 05:58	47.21	OK
17005	2026-09-22 05:59	45.82	OK	17006	2026-09-22 06:00	47.13	OK
17007	2026-09-22 06:01	47.91	OK	17008	2026-09-22 06:02	48.94	OK
17009	2026-09-22 06:03	48.64	OK	17010	2026-09-22 06:04	48.61	OK
17011	2026-09-22 06:05	45.47	OK	17012	2026-09-22 06:06	46.54	OK
17013	2026-09-22 06:07	47.65	OK	17014	2026-09-22 06:08	48.40	OK
1701	2026-09-22 06:09	47.15	OK	1701	2026-09-22 06:10	46.62	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
17017	2026-09-22 06:11	45.89	OK	17018	2026-09-22 06:12	48.45	OK
17019	2026-09-22 06:13	47.43	OK	17020	2026-09-22 06:14	47.64	OK
17021	2026-09-22 06:15	47.24	OK	17022	2026-09-22 06:16	47.15	OK
17023	2026-09-22 06:17	47.86	OK	17024	2026-09-22 06:18	47.35	OK
17025	2026-09-22 06:19	47.82	OK	17026	2026-09-22 06:20	48.26	OK
17027	2026-09-22 06:21	48.35	OK	17028	2026-09-22 06:22	47.72	OK
17029	2026-09-22 06:23	48.30	OK	17030	2026-09-22 06:24	47.38	OK
17031	2026-09-22 06:25	46.08	OK	17032	2026-09-22 06:26	46.04	OK
17033	2026-09-22 06:27	46.80	OK	17034	2026-09-22 06:28	47.51	OK
17035	2026-09-22 06:29	47.36	OK	17036	2026-09-22 06:30	48.31	OK
17037	2026-09-22 06:31	49.14	OK	17038	2026-09-22 06:32	47.07	OK
17039	2026-09-22 06:33	49.86	OK	17040	2026-09-22 06:34	48.08	OK
17041	2026-09-22 06:35	46.66	OK	17042	2026-09-22 06:36	47.29	OK
17043	2026-09-22 06:37	48.01	OK	17044	2026-09-22 06:38	46.71	OK
17045	2026-09-22 06:39	49.78	OK	17046	2026-09-22 06:40	47.19	OK
17047	2026-09-22 06:41	47.17	OK	17048	2026-09-22 06:42	45.67	OK
17049	2026-09-22 06:43	49.09	OK	17050	2026-09-22 06:44	47.34	OK
17051	2026-09-22 06:45	46.87	OK	17052	2026-09-22 06:46	48.43	OK
17053	2026-09-22 06:47	48.30	OK	17054	2026-09-22 06:48	47.97	OK
17055	2026-09-22 06:49	47.83	OK	17056	2026-09-22 06:50	47.58	OK
17057	2026-09-22 06:51	47.90	OK	17058	2026-09-22 06:52	50.22	OK
17059	2026-09-22 06:53	47.19	OK	17060	2026-09-22 06:54	47.10	OK
17061	2026-09-22 06:55	45.88	OK	17062	2026-09-22 06:56	47.67	OK
17063	2026-09-22 06:57	47.90	OK	17064	2026-09-22 06:58	46.91	OK
17065	2026-09-22 06:59	48.19	OK	17066	2026-09-22 07:00	47.76	OK
17067	2026-09-22 07:01	46.59	OK	17068	2026-09-22 07:02	48.97	OK
17069	2026-09-22 07:03	49.66	OK	17070	2026-09-22 07:04	49.82	OK
17071	2026-09-22 07:05	48.50	OK	17072	2026-09-22 07:06	48.08	OK
17073	2026-09-22 07:07	48.66	OK	17074	2026-09-22 07:08	47.34	OK
1707	2026-09-22 07:09	49.03	OK	1707	2026-09-22 07:10	47.55	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
17077	2026-09-22 07:11	48.51	OK	17078	2026-09-22 07:12	47.79	OK
17079	2026-09-22 07:13	48.38	OK	17080	2026-09-22 07:14	47.99	OK
17081	2026-09-22 07:15	49.02	OK	17082	2026-09-22 07:16	49.64	OK
17083	2026-09-22 07:17	47.45	OK	17084	2026-09-22 07:18	49.13	OK
17085	2026-09-22 07:19	48.31	OK	17086	2026-09-22 07:20	48.37	OK
17087	2026-09-22 07:21	50.05	OK	17088	2026-09-22 07:22	48.74	OK
17089	2026-09-22 07:23	49.58	OK	17090	2026-09-22 07:24	48.13	OK
17091	2026-09-22 07:25	49.60	OK	17092	2026-09-22 07:26	48.26	OK
17093	2026-09-22 07:27	47.87	OK	17094	2026-09-22 07:28	48.87	OK
17095	2026-09-22 07:29	48.58	OK	17096	2026-09-22 07:30	47.92	OK
17097	2026-09-22 07:31	47.74	OK	17098	2026-09-22 07:32	47.27	OK
17099	2026-09-22 07:33	49.99	OK	17100	2026-09-22 07:34	47.96	OK
17101	2026-09-22 07:35	50.58	OK	17102	2026-09-22 07:36	49.41	OK
17103	2026-09-22 07:37	49.96	OK	17104	2026-09-22 07:38	50.22	OK
17105	2026-09-22 07:39	48.72	OK	17106	2026-09-22 07:40	49.32	OK
17107	2026-09-22 07:41	48.93	OK	17108	2026-09-22 07:42	49.14	OK
17109	2026-09-22 07:43	47.83	OK	17110	2026-09-22 07:44	48.64	OK
17111	2026-09-22 07:45	48.34	OK	17112	2026-09-22 07:46	49.95	OK
17113	2026-09-22 07:47	48.68	OK	17114	2026-09-22 07:48	46.84	OK
17115	2026-09-22 07:49	49.28	OK	17116	2026-09-22 07:50	48.89	OK
17117	2026-09-22 07:51	49.68	OK	17118	2026-09-22 07:52	48.08	OK
17119	2026-09-22 07:53	48.69	OK	17120	2026-09-22 07:54	48.97	OK
17121	2026-09-22 07:55	47.97	OK	17122	2026-09-22 07:56	49.36	OK
17123	2026-09-22 07:57	50.53	OK	17124	2026-09-22 07:58	48.55	OK
17125	2026-09-22 07:59	49.55	OK	17126	2026-09-22 08:00	47.78	OK
17127	2026-09-22 08:01	47.21	OK	17128	2026-09-22 08:02	50.05	OK
17129	2026-09-22 08:03	49.13	OK	17130	2026-09-22 08:04	48.65	OK
17131	2026-09-22 08:05	49.20	OK	17132	2026-09-22 08:06	49.12	OK
17133	2026-09-22 08:07	48.20	OK	17134	2026-09-22 08:08	49.02	OK
1713	2026-09-22 08:09	48.19	OK	1713	2026-09-22 08:10	49.73	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
17137	2026-09-22 08:11	47.34	OK	17138	2026-09-22 08:12	48.39	OK
17139	2026-09-22 08:13	49.40	OK	17140	2026-09-22 08:14	49.85	OK
17141	2026-09-22 08:15	50.75	OK	17142	2026-09-22 08:16	48.44	OK
17143	2026-09-22 08:17	49.20	OK	17144	2026-09-22 08:18	50.02	OK
17145	2026-09-22 08:19	50.63	OK	17146	2026-09-22 08:20	48.37	OK
17147	2026-09-22 08:21	51.16	OK	17148	2026-09-22 08:22	48.12	OK
17149	2026-09-22 08:23	50.04	OK	17150	2026-09-22 08:24	50.80	OK
17151	2026-09-22 08:25	51.66	OK	17152	2026-09-22 08:26	50.01	OK
17153	2026-09-22 08:27	48.61	OK	17154	2026-09-22 08:28	47.64	OK
17155	2026-09-22 08:29	48.73	OK	17156	2026-09-22 08:30	50.89	OK
17157	2026-09-22 08:31	48.41	OK	17158	2026-09-22 08:32	50.17	OK
17159	2026-09-22 08:33	48.59	OK	17160	2026-09-22 08:34	51.03	OK
17161	2026-09-22 08:35	50.36	OK	17162	2026-09-22 08:36	49.43	OK
17163	2026-09-22 08:37	47.74	OK	17164	2026-09-22 08:38	50.70	OK
17165	2026-09-22 08:39	50.56	OK	17166	2026-09-22 08:40	49.80	OK
17167	2026-09-22 08:41	49.64	OK	17168	2026-09-22 08:42	48.90	OK
17169	2026-09-22 08:43	47.72	OK	17170	2026-09-22 08:44	50.12	OK
17171	2026-09-22 08:45	50.24	OK	17172	2026-09-22 08:46	50.68	OK
17173	2026-09-22 08:47	48.71	OK	17174	2026-09-22 08:48	48.10	OK
17175	2026-09-22 08:49	51.69	OK	17176	2026-09-22 08:50	50.14	OK
17177	2026-09-22 08:51	49.18	OK	17178	2026-09-22 08:52	49.42	OK
17179	2026-09-22 08:53	48.73	OK	17180	2026-09-22 08:54	50.26	OK
17181	2026-09-22 08:55	47.78	OK	17182	2026-09-22 08:56	50.41	OK
17183	2026-09-22 08:57	50.87	OK	17184	2026-09-22 08:58	51.07	OK
17185	2026-09-22 08:59	50.76	OK	17186	2026-09-22 09:00	50.48	OK
17187	2026-09-22 09:01	50.36	OK	17188	2026-09-22 09:02	49.53	OK
17189	2026-09-22 09:03	50.08	OK	17190	2026-09-22 09:04	50.10	OK
17191	2026-09-22 09:05	48.60	OK	17192	2026-09-22 09:06	48.97	OK
17193	2026-09-22 09:07	49.38	OK	17194	2026-09-22 09:08	47.70	OK
1719	2026-09-22 09:09	48.20	OK	1719	2026-09-22 09:10	49.54	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
17197	2026-09-22 09:11	50.25	OK	17198	2026-09-22 09:12	50.31	OK
17199	2026-09-22 09:13	50.24	OK	17200	2026-09-22 09:14	50.95	OK
17201	2026-09-22 09:15	50.62	OK	17202	2026-09-22 09:16	50.02	OK
17203	2026-09-22 09:17	50.68	OK	17204	2026-09-22 09:18	51.14	OK
17205	2026-09-22 09:19	51.96	OK	17206	2026-09-22 09:20	49.30	OK
17207	2026-09-22 09:21	49.71	OK	17208	2026-09-22 09:22	48.87	OK
17209	2026-09-22 09:23	49.57	OK	17210	2026-09-22 09:24	49.71	OK
17211	2026-09-22 09:25	48.05	OK	17212	2026-09-22 09:26	50.93	OK
17213	2026-09-22 09:27	50.37	OK	17214	2026-09-22 09:28	50.81	OK
17215	2026-09-22 09:29	49.35	OK	17216	2026-09-22 09:30	49.60	OK
17217	2026-09-22 09:31	49.70	OK	17218	2026-09-22 09:32	50.98	OK
17219	2026-09-22 09:33	49.25	OK	17220	2026-09-22 09:34	50.16	OK
17221	2026-09-22 09:35	49.21	OK	17222	2026-09-22 09:36	48.66	OK
17223	2026-09-22 09:37	50.07	OK	17224	2026-09-22 09:38	49.74	OK
17225	2026-09-22 09:39	50.78	OK	17226	2026-09-22 09:40	51.80	OK
17227	2026-09-22 09:41	50.46	OK	17228	2026-09-22 09:42	49.15	OK
17229	2026-09-22 09:43	51.78	OK	17230	2026-09-22 09:44	50.40	OK
17231	2026-09-22 09:45	50.10	OK	17232	2026-09-22 09:46	50.81	OK
17233	2026-09-22 09:47	49.80	OK	17234	2026-09-22 09:48	50.46	OK
17235	2026-09-22 09:49	49.32	OK	17236	2026-09-22 09:50	49.83	OK
17237	2026-09-22 09:51	50.18	OK	17238	2026-09-22 09:52	52.00	OK
17239	2026-09-22 09:53	51.32	OK	17240	2026-09-22 09:54	51.16	OK
17241	2026-09-22 09:55	48.39	OK	17242	2026-09-22 09:56	51.15	OK
17243	2026-09-22 09:57	50.56	OK	17244	2026-09-22 09:58	49.49	OK
17245	2026-09-22 09:59	51.47	OK	17246	2026-09-22 10:00	49.93	OK
17247	2026-09-22 10:01	48.56	OK	17248	2026-09-22 10:02	52.09	OK
17249	2026-09-22 10:03	52.15	OK	17250	2026-09-22 10:04	49.75	OK
17251	2026-09-22 10:05	50.30	OK	17252	2026-09-22 10:06	49.84	OK
17253	2026-09-22 10:07	50.04	OK	17254	2026-09-22 10:08	52.35	OK
1725	2026-09-22 10:09	50.16	OK	1725	2026-09-22 10:10	48.80	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
17257	2026-09-22 10:11	50.11	OK	17258	2026-09-22 10:12	51.16	OK
17259	2026-09-22 10:13	53.01	OK	17260	2026-09-22 10:14	53.09	OK
17261	2026-09-22 10:15	52.11	OK	17262	2026-09-22 10:16	50.44	OK
17263	2026-09-22 10:17	49.94	OK	17264	2026-09-22 10:18	51.15	OK
17265	2026-09-22 10:19	51.40	OK	17266	2026-09-22 10:20	51.75	OK
17267	2026-09-22 10:21	51.07	OK	17268	2026-09-22 10:22	51.72	OK
17269	2026-09-22 10:23	49.81	OK	17270	2026-09-22 10:24	51.24	OK
17271	2026-09-22 10:25	50.89	OK	17272	2026-09-22 10:26	51.02	OK
17273	2026-09-22 10:27	52.34	OK	17274	2026-09-22 10:28	50.18	OK
17275	2026-09-22 10:29	51.43	OK	17276	2026-09-22 10:30	49.13	OK
17277	2026-09-22 10:31	50.23	OK	17278	2026-09-22 10:32	52.08	OK
17279	2026-09-22 10:33	51.34	OK	17280	2026-09-22 10:34	51.40	OK
17281	2026-09-22 10:35	49.84	OK	17282	2026-09-22 10:36	51.18	OK
17283	2026-09-22 10:37	51.50	OK	17284	2026-09-22 10:38	51.05	OK
17285	2026-09-22 10:39	49.61	OK	17286	2026-09-22 10:40	52.16	OK
17287	2026-09-22 10:41	50.54	OK	17288	2026-09-22 10:42	50.05	OK
17289	2026-09-22 10:43	48.72	OK	17290	2026-09-22 10:44	52.23	OK
17291	2026-09-22 10:45	52.21	OK	17292	2026-09-22 10:46	49.71	OK
17293	2026-09-22 10:47	50.47	OK	17294	2026-09-22 10:48	50.43	OK
17295	2026-09-22 10:49	51.74	OK	17296	2026-09-22 10:50	51.93	OK
17297	2026-09-22 10:51	49.69	OK	17298	2026-09-22 10:52	52.38	OK
17299	2026-09-22 10:53	50.21	OK	17300	2026-09-22 10:54	50.44	OK
17301	2026-09-22 10:55	50.30	OK	17302	2026-09-22 10:56	50.67	OK
17303	2026-09-22 10:57	51.42	OK	17304	2026-09-22 10:58	50.77	OK
17305	2026-09-22 10:59	53.59	OK	17306	2026-09-22 11:00	50.18	OK
17307	2026-09-22 11:01	50.80	OK	17308	2026-09-22 11:02	53.35	OK
17309	2026-09-22 11:03	50.77	OK	17310	2026-09-22 11:04	52.01	OK
17311	2026-09-22 11:05	51.51	OK	17312	2026-09-22 11:06	51.97	OK
17313	2026-09-22 11:07	50.74	OK	17314	2026-09-22 11:08	50.80	OK
1731	2026-09-22 11:09	51.53	OK	1731	2026-09-22 11:10	50.69	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
17317	2026-09-22 11:11	51.32	OK	17318	2026-09-22 11:12	51.05	OK
17319	2026-09-22 11:13	49.77	OK	17320	2026-09-22 11:14	51.61	OK
17321	2026-09-22 11:15	51.75	OK	17322	2026-09-22 11:16	48.78	OK
17323	2026-09-22 11:17	50.78	OK	17324	2026-09-22 11:18	51.71	OK
17325	2026-09-22 11:19	51.02	OK	17326	2026-09-22 11:20	50.69	OK
17327	2026-09-22 11:21	52.01	OK	17328	2026-09-22 11:22	51.27	OK
17329	2026-09-22 11:23	52.44	OK	17330	2026-09-22 11:24	53.57	OK
17331	2026-09-22 11:25	50.60	OK	17332	2026-09-22 11:26	51.22	OK
17333	2026-09-22 11:27	50.63	OK	17334	2026-09-22 11:28	50.65	OK
17335	2026-09-22 11:29	50.21	OK	17336	2026-09-22 11:30	50.58	OK
17337	2026-09-22 11:31	51.65	OK	17338	2026-09-22 11:32	52.83	OK
17339	2026-09-22 11:33	51.34	OK	17340	2026-09-22 11:34	51.86	OK
17341	2026-09-22 11:35	51.29	OK	17342	2026-09-22 11:36	52.87	OK
17343	2026-09-22 11:37	52.32	OK	17344	2026-09-22 11:38	51.36	OK
17345	2026-09-22 11:39	50.91	OK	17346	2026-09-22 11:40	49.96	OK
17347	2026-09-22 11:41	49.15	OK	17348	2026-09-22 11:42	52.13	OK
17349	2026-09-22 11:43	51.88	OK	17350	2026-09-22 11:44	50.83	OK
17351	2026-09-22 11:45	53.76	OK	17352	2026-09-22 11:46	50.67	OK
17353	2026-09-22 11:47	51.51	OK	17354	2026-09-22 11:48	51.40	OK
17355	2026-09-22 11:49	51.90	OK	17356	2026-09-22 11:50	52.09	OK
17357	2026-09-22 11:51	51.20	OK	17358	2026-09-22 11:52	51.60	OK
17359	2026-09-22 11:53	50.03	OK	17360	2026-09-22 11:54	51.49	OK
17361	2026-09-22 11:55	51.91	OK	17362	2026-09-22 11:56	51.67	OK
17363	2026-09-22 11:57	51.25	OK	17364	2026-09-22 11:58	50.66	OK
17365	2026-09-22 11:59	51.30	OK	17366	2026-09-22 12:00	50.16	OK
17367	2026-09-22 12:01	52.43	OK	17368	2026-09-22 12:02	53.16	OK
17369	2026-09-22 12:03	49.97	OK	17370	2026-09-22 12:04	52.18	OK
17371	2026-09-22 12:05	52.21	OK	17372	2026-09-22 12:06	52.72	OK
17373	2026-09-22 12:07	50.96	OK	17374	2026-09-22 12:08	50.25	OK
1737	2026-09-22 12:09	52.02	OK	1737	2026-09-22 12:10	51.20	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
17377	2026-09-22 12:11	51.49	OK	17378	2026-09-22 12:12	52.23	OK
17379	2026-09-22 12:13	53.20	OK	17380	2026-09-22 12:14	50.23	OK
17381	2026-09-22 12:15	53.19	OK	17382	2026-09-22 12:16	50.30	OK
17383	2026-09-22 12:17	51.38	OK	17384	2026-09-22 12:18	52.49	OK
17385	2026-09-22 12:19	51.67	OK	17386	2026-09-22 12:20	53.28	OK
17387	2026-09-22 12:21	50.92	OK	17388	2026-09-22 12:22	51.46	OK
17389	2026-09-22 12:23	53.14	OK	17390	2026-09-22 12:24	51.21	OK
17391	2026-09-22 12:25	53.59	OK	17392	2026-09-22 12:26	51.08	OK
17393	2026-09-22 12:27	53.53	OK	17394	2026-09-22 12:28	52.01	OK
17395	2026-09-22 12:29	53.16	OK	17396	2026-09-22 12:30	52.69	OK
17397	2026-09-22 12:31	52.16	OK	17398	2026-09-22 12:32	53.79	OK
17399	2026-09-22 12:33	52.49	OK	17400	2026-09-22 12:34	50.39	OK
17401	2026-09-22 12:35	51.39	OK	17402	2026-09-22 12:36	52.66	OK
17403	2026-09-22 12:37	50.62	OK	17404	2026-09-22 12:38	51.21	OK
17405	2026-09-22 12:39	52.85	OK	17406	2026-09-22 12:40	52.33	OK
17407	2026-09-22 12:41	50.82	OK	17408	2026-09-22 12:42	49.74	OK
17409	2026-09-22 12:43	52.53	OK	17410	2026-09-22 12:44	51.89	OK
17411	2026-09-22 12:45	52.95	OK	17412	2026-09-22 12:46	52.91	OK
17413	2026-09-22 12:47	51.53	OK	17414	2026-09-22 12:48	51.93	OK
17415	2026-09-22 12:49	52.61	OK	17416	2026-09-22 12:50	50.55	OK
17417	2026-09-22 12:51	52.32	OK	17418	2026-09-22 12:52	50.68	OK
17419	2026-09-22 12:53	51.26	OK	17420	2026-09-22 12:54	52.16	OK
17421	2026-09-22 12:55	51.83	OK	17422	2026-09-22 12:56	52.43	OK
17423	2026-09-22 12:57	53.49	OK	17424	2026-09-22 12:58	52.37	OK
17425	2026-09-22 12:59	51.47	OK	17426	2026-09-22 13:00	51.95	OK
17427	2026-09-22 13:01	51.62	OK	17428	2026-09-22 13:02	50.21	OK
17429	2026-09-22 13:03	52.70	OK	17430	2026-09-22 13:04	50.52	OK
17431	2026-09-22 13:05	52.60	OK	17432	2026-09-22 13:06	53.96	OK
17433	2026-09-22 13:07	51.42	OK	17434	2026-09-22 13:08	52.89	OK
1743	2026-09-22 13:09	53.17	OK	1743	2026-09-22 13:10	51.92	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
17437	2026-09-22 13:11	51.38	OK	17438	2026-09-22 13:12	50.85	OK
17439	2026-09-22 13:13	52.25	OK	17440	2026-09-22 13:14	50.20	OK
17441	2026-09-22 13:15	53.20	OK	17442	2026-09-22 13:16	50.97	OK
17443	2026-09-22 13:17	52.57	OK	17444	2026-09-22 13:18	50.71	OK
17445	2026-09-22 13:19	52.14	OK	17446	2026-09-22 13:20	52.48	OK
17447	2026-09-22 13:21	51.95	OK	17448	2026-09-22 13:22	53.25	OK
17449	2026-09-22 13:23	50.74	OK	17450	2026-09-22 13:24	51.82	OK
17451	2026-09-22 13:25	50.78	OK	17452	2026-09-22 13:26	51.75	OK
17453	2026-09-22 13:27	51.42	OK	17454	2026-09-22 13:28	53.32	OK
17455	2026-09-22 13:29	52.51	OK	17456	2026-09-22 13:30	52.38	OK
17457	2026-09-22 13:31	52.37	OK	17458	2026-09-22 13:32	51.74	OK
17459	2026-09-22 13:33	50.91	OK	17460	2026-09-22 13:34	52.27	OK
17461	2026-09-22 13:35	53.73	OK	17462	2026-09-22 13:36	53.23	OK
17463	2026-09-22 13:37	51.55	OK	17464	2026-09-22 13:38	52.35	OK
17465	2026-09-22 13:39	50.26	OK	17466	2026-09-22 13:40	50.51	OK
17467	2026-09-22 13:41	52.17	OK	17468	2026-09-22 13:42	53.13	OK
17469	2026-09-22 13:43	53.83	OK	17470	2026-09-22 13:44	51.08	OK
17471	2026-09-22 13:45	52.16	OK	17472	2026-09-22 13:46	51.55	OK
17473	2026-09-22 13:47	52.17	OK	17474	2026-09-22 13:48	54.39	OK
17475	2026-09-22 13:49	51.78	OK	17476	2026-09-22 13:50	51.30	OK
17477	2026-09-22 13:51	51.88	OK	17478	2026-09-22 13:52	52.71	OK
17479	2026-09-22 13:53	52.08	OK	17480	2026-09-22 13:54	52.33	OK
17481	2026-09-22 13:55	51.43	OK	17482	2026-09-22 13:56	49.96	OK
17483	2026-09-22 13:57	53.30	OK	17484	2026-09-22 13:58	51.76	OK
17485	2026-09-22 13:59	51.74	OK	17486	2026-09-22 14:00	51.10	OK
17487	2026-09-22 14:01	53.57	OK	17488	2026-09-22 14:02	49.82	OK
17489	2026-09-22 14:03	53.28	OK	17490	2026-09-22 14:04	50.78	OK
17491	2026-09-22 14:05	53.08	OK	17492	2026-09-22 14:06	52.37	OK
17493	2026-09-22 14:07	52.09	OK	17494	2026-09-22 14:08	53.73	OK
1749	2026-09-22 14:09	51.53	OK	1749	2026-09-22 14:10	52.01	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
17497	2026-09-22 14:11	49.94	OK	17498	2026-09-22 14:12	50.78	OK
17499	2026-09-22 14:13	52.96	OK	17500	2026-09-22 14:14	53.35	OK
17501	2026-09-22 14:15	51.66	OK	17502	2026-09-22 14:16	53.32	OK
17503	2026-09-22 14:17	51.22	OK	17504	2026-09-22 14:18	52.19	OK
17505	2026-09-22 14:19	51.13	OK	17506	2026-09-22 14:20	50.92	OK
17507	2026-09-22 14:21	51.90	OK	17508	2026-09-22 14:22	53.94	OK
17509	2026-09-22 14:23	53.29	OK	17510	2026-09-22 14:24	52.02	OK
17511	2026-09-22 14:25	52.85	OK	17512	2026-09-22 14:26	52.52	OK
17513	2026-09-22 14:27	50.97	OK	17514	2026-09-22 14:28	52.72	OK
17515	2026-09-22 14:29	52.85	OK	17516	2026-09-22 14:30	51.54	OK
17517	2026-09-22 14:31	50.27	OK	17518	2026-09-22 14:32	50.94	OK
17519	2026-09-22 14:33	51.26	OK	17520	2026-09-22 14:34	52.48	OK
17521	2026-09-22 14:35	52.62	OK	17522	2026-09-22 14:36	50.14	OK
17523	2026-09-22 14:37	51.06	OK	17524	2026-09-22 14:38	53.35	OK
17525	2026-09-22 14:39	53.30	OK	17526	2026-09-22 14:40	51.53	OK
17527	2026-09-22 14:41	52.29	OK	17528	2026-09-22 14:42	51.39	OK
17529	2026-09-22 14:43	51.53	OK	17530	2026-09-22 14:44	50.63	OK
17531	2026-09-22 14:45	52.09	OK	17532	2026-09-22 14:46	50.74	OK
17533	2026-09-22 14:47	49.91	OK	17534	2026-09-22 14:48	52.96	OK
17535	2026-09-22 14:49	52.94	OK	17536	2026-09-22 14:50	51.93	OK
17537	2026-09-22 14:51	50.36	OK	17538	2026-09-22 14:52	50.74	OK
17539	2026-09-22 14:53	51.59	OK	17540	2026-09-22 14:54	51.95	OK
17541	2026-09-22 14:55	52.90	OK	17542	2026-09-22 14:56	51.87	OK
17543	2026-09-22 14:57	50.33	OK	17544	2026-09-22 14:58	51.42	OK
17545	2026-09-22 14:59	51.83	OK	17546	2026-09-22 15:00	51.80	OK
17547	2026-09-22 15:01	50.84	OK	17548	2026-09-22 15:02	52.21	OK
17549	2026-09-22 15:03	51.24	OK	17550	2026-09-22 15:04	50.83	OK
17551	2026-09-22 15:05	53.05	OK	17552	2026-09-22 15:06	50.98	OK
17553	2026-09-22 15:07	50.19	OK	17554	2026-09-22 15:08	49.96	OK
17555	2026-09-22 15:09	53.04	OK	17556	2026-09-22 15:10	52.34	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
17557	2026-09-22 15:11	52.50	OK	17558	2026-09-22 15:12	50.77	OK
17559	2026-09-22 15:13	52.02	OK	17560	2026-09-22 15:14	50.09	OK
17561	2026-09-22 15:15	51.35	OK	17562	2026-09-22 15:16	50.76	OK
17563	2026-09-22 15:17	51.79	OK	17564	2026-09-22 15:18	50.61	OK
17565	2026-09-22 15:19	49.30	OK	17566	2026-09-22 15:20	50.10	OK
17567	2026-09-22 15:21	52.19	OK	17568	2026-09-22 15:22	52.05	OK
17569	2026-09-22 15:23	51.70	OK	17570	2026-09-22 15:24	50.66	OK
17571	2026-09-22 15:25	53.16	OK	17572	2026-09-22 15:26	53.51	OK
17573	2026-09-22 15:27	52.05	OK	17574	2026-09-22 15:28	52.33	OK
17575	2026-09-22 15:29	51.28	OK	17576	2026-09-22 15:30	51.39	OK
17577	2026-09-22 15:31	48.93	OK	17578	2026-09-22 15:32	50.31	OK
17579	2026-09-22 15:33	51.80	OK	17580	2026-09-22 15:34	51.55	OK
17581	2026-09-22 15:35	53.02	OK	17582	2026-09-22 15:36	51.31	OK
17583	2026-09-22 15:37	51.59	OK	17584	2026-09-22 15:38	51.49	OK
17585	2026-09-22 15:39	50.95	OK	17586	2026-09-22 15:40	50.99	OK
17587	2026-09-22 15:41	50.78	OK	17588	2026-09-22 15:42	50.76	OK
17589	2026-09-22 15:43	51.31	OK	17590	2026-09-22 15:44	50.24	OK
17591	2026-09-22 15:45	50.71	OK	17592	2026-09-22 15:46	50.10	OK
17593	2026-09-22 15:47	49.87	OK	17594	2026-09-22 15:48	50.82	OK
17595	2026-09-22 15:49	50.30	OK	17596	2026-09-22 15:50	51.44	OK
17597	2026-09-22 15:51	51.44	OK	17598	2026-09-22 15:52	49.29	OK
17599	2026-09-22 15:53	51.63	OK	17600	2026-09-22 15:54	49.71	OK
17601	2026-09-22 15:55	50.07	OK	17602	2026-09-22 15:56	51.70	OK
17603	2026-09-22 15:57	49.03	OK	17604	2026-09-22 15:58	53.00	OK
17605	2026-09-22 15:59	50.17	OK	17606	2026-09-22 16:00	50.41	OK
17607	2026-09-22 16:01	51.42	OK	17608	2026-09-22 16:02	49.82	OK
17609	2026-09-22 16:03	48.71	OK	17610	2026-09-22 16:04	51.50	OK
17611	2026-09-22 16:05	50.73	OK	17612	2026-09-22 16:06	50.57	OK
17613	2026-09-22 16:07	51.75	OK	17614	2026-09-22 16:08	49.23	OK
1761	2026-09-22 16:09	50.57	OK	1761	2026-09-22 16:10	50.18	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
17617	2026-09-22 16:11	51.53	OK	17618	2026-09-22 16:12	50.26	OK
17619	2026-09-22 16:13	51.56	OK	17620	2026-09-22 16:14	51.76	OK
17621	2026-09-22 16:15	51.85	OK	17622	2026-09-22 16:16	50.56	OK
17623	2026-09-22 16:17	50.88	OK	17624	2026-09-22 16:18	51.27	OK
17625	2026-09-22 16:19	49.56	OK	17626	2026-09-22 16:20	52.76	OK
17627	2026-09-22 16:21	50.56	OK	17628	2026-09-22 16:22	51.40	OK
17629	2026-09-22 16:23	51.49	OK	17630	2026-09-22 16:24	51.51	OK
17631	2026-09-22 16:25	51.23	OK	17632	2026-09-22 16:26	51.46	OK
17633	2026-09-22 16:27	49.05	OK	17634	2026-09-22 16:28	51.48	OK
17635	2026-09-22 16:29	51.03	OK	17636	2026-09-22 16:30	51.64	OK
17637	2026-09-22 16:31	48.48	OK	17638	2026-09-22 16:32	49.70	OK
17639	2026-09-22 16:33	50.92	OK	17640	2026-09-22 16:34	50.36	OK
17641	2026-09-22 16:35	51.44	OK	17642	2026-09-22 16:36	49.52	OK
17643	2026-09-22 16:37	51.33	OK	17644	2026-09-22 16:38	49.64	OK
17645	2026-09-22 16:39	51.35	OK	17646	2026-09-22 16:40	51.03	OK
17647	2026-09-22 16:41	50.01	OK	17648	2026-09-22 16:42	51.41	OK
17649	2026-09-22 16:43	51.09	OK	17650	2026-09-22 16:44	49.59	OK
17651	2026-09-22 16:45	49.11	OK	17652	2026-09-22 16:46	51.22	OK
17653	2026-09-22 16:47	49.78	OK	17654	2026-09-22 16:48	51.18	OK
17655	2026-09-22 16:49	50.30	OK	17656	2026-09-22 16:50	48.80	OK
17657	2026-09-22 16:51	51.61	OK	17658	2026-09-22 16:52	50.05	OK
17659	2026-09-22 16:53	51.54	OK	17660	2026-09-22 16:54	50.15	OK
17661	2026-09-22 16:55	50.96	OK	17662	2026-09-22 16:56	51.71	OK
17663	2026-09-22 16:57	51.58	OK	17664	2026-09-22 16:58	52.31	OK
17665	2026-09-22 16:59	50.39	OK	17666	2026-09-22 17:00	51.09	OK
17667	2026-09-22 17:01	50.92	OK	17668	2026-09-22 17:02	50.80	OK
17669	2026-09-22 17:03	50.17	OK	17670	2026-09-22 17:04	52.01	OK
17671	2026-09-22 17:05	51.06	OK	17672	2026-09-22 17:06	50.40	OK
17673	2026-09-22 17:07	48.72	OK	17674	2026-09-22 17:08	51.61	OK
1767	2026-09-22 17:09	49.50	OK	1767	2026-09-22 17:10	51.91	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
17677	2026-09-22 17:11	51.18	OK	17678	2026-09-22 17:12	51.83	OK
17679	2026-09-22 17:13	50.27	OK	17680	2026-09-22 17:14	50.55	OK
17681	2026-09-22 17:15	49.23	OK	17682	2026-09-22 17:16	50.08	OK
17683	2026-09-22 17:17	51.18	OK	17684	2026-09-22 17:18	49.66	OK
17685	2026-09-22 17:19	50.42	OK	17686	2026-09-22 17:20	51.00	OK
17687	2026-09-22 17:21	50.56	OK	17688	2026-09-22 17:22	48.33	OK
17689	2026-09-22 17:23	51.09	OK	17690	2026-09-22 17:24	50.40	OK
17691	2026-09-22 17:25	51.44	OK	17692	2026-09-22 17:26	50.95	OK
17693	2026-09-22 17:27	50.69	OK	17694	2026-09-22 17:28	49.29	OK
17695	2026-09-22 17:29	49.59	OK	17696	2026-09-22 17:30	50.49	OK
17697	2026-09-22 17:31	50.18	OK	17698	2026-09-22 17:32	50.93	OK
17699	2026-09-22 17:33	50.06	OK	17700	2026-09-22 17:34	52.02	OK
17701	2026-09-22 17:35	51.40	OK	17702	2026-09-22 17:36	52.16	OK
17703	2026-09-22 17:37	51.19	OK	17704	2026-09-22 17:38	51.17	OK
17705	2026-09-22 17:39	50.78	OK	17706	2026-09-22 17:40	47.78	OK
17707	2026-09-22 17:41	51.20	OK	17708	2026-09-22 17:42	49.93	OK
17709	2026-09-22 17:43	51.21	OK	17710	2026-09-22 17:44	49.76	OK
17711	2026-09-22 17:45	50.87	OK	17712	2026-09-22 17:46	47.98	OK
17713	2026-09-22 17:47	49.62	OK	17714	2026-09-22 17:48	51.91	OK
17715	2026-09-22 17:49	49.68	OK	17716	2026-09-22 17:50	50.31	OK
17717	2026-09-22 17:51	49.83	OK	17718	2026-09-22 17:52	50.08	OK
17719	2026-09-22 17:53	50.52	OK	17720	2026-09-22 17:54	50.54	OK
17721	2026-09-22 17:55	49.87	OK	17722	2026-09-22 17:56	49.83	OK
17723	2026-09-22 17:57	48.42	OK	17724	2026-09-22 17:58	49.89	OK
17725	2026-09-22 17:59	49.66	OK	17726	2026-09-22 18:00	48.85	OK
17727	2026-09-22 18:01	49.78	OK	17728	2026-09-22 18:02	49.04	OK
17729	2026-09-22 18:03	50.12	OK	17730	2026-09-22 18:04	50.05	OK
17731	2026-09-22 18:05	49.85	OK	17732	2026-09-22 18:06	47.89	OK
17733	2026-09-22 18:07	48.75	OK	17734	2026-09-22 18:08	50.35	OK
1773	2026-09-22 18:09	47.80	OK	1773	2026-09-22 18:10	49.34	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
17737	2026-09-22 18:11	50.21	OK	17738	2026-09-22 18:12	51.25	OK
17739	2026-09-22 18:13	50.59	OK	17740	2026-09-22 18:14	49.72	OK
17741	2026-09-22 18:15	50.61	OK	17742	2026-09-22 18:16	50.77	OK
17743	2026-09-22 18:17	50.16	OK	17744	2026-09-22 18:18	49.94	OK
17745	2026-09-22 18:19	49.73	OK	17746	2026-09-22 18:20	49.91	OK
17747	2026-09-22 18:21	48.88	OK	17748	2026-09-22 18:22	47.94	OK
17749	2026-09-22 18:23	48.89	OK	17750	2026-09-22 18:24	49.39	OK
17751	2026-09-22 18:25	50.33	OK	17752	2026-09-22 18:26	48.71	OK
17753	2026-09-22 18:27	49.14	OK	17754	2026-09-22 18:28	49.24	OK
17755	2026-09-22 18:29	49.16	OK	17756	2026-09-22 18:30	48.56	OK
17757	2026-09-22 18:31	48.50	OK	17758	2026-09-22 18:32	47.93	OK
17759	2026-09-22 18:33	49.33	OK	17760	2026-09-22 18:34	48.23	OK
17761	2026-09-22 18:35	48.46	OK	17762	2026-09-22 18:36	48.98	OK
17763	2026-09-22 18:37	50.16	OK	17764	2026-09-22 18:38	49.69	OK
17765	2026-09-22 18:39	50.29	OK	17766	2026-09-22 18:40	49.21	OK
17767	2026-09-22 18:41	50.76	OK	17768	2026-09-22 18:42	51.31	OK
17769	2026-09-22 18:43	49.84	OK	17770	2026-09-22 18:44	48.82	OK
17771	2026-09-22 18:45	49.73	OK	17772	2026-09-22 18:46	50.71	OK
17773	2026-09-22 18:47	47.92	OK	17774	2026-09-22 18:48	50.57	OK
17775	2026-09-22 18:49	49.36	OK	17776	2026-09-22 18:50	48.79	OK
17777	2026-09-22 18:51	47.40	OK	17778	2026-09-22 18:52	47.78	OK
17779	2026-09-22 18:53	49.30	OK	17780	2026-09-22 18:54	49.30	OK
17781	2026-09-22 18:55	48.92	OK	17782	2026-09-22 18:56	48.38	OK
17783	2026-09-22 18:57	49.85	OK	17784	2026-09-22 18:58	49.78	OK
17785	2026-09-22 18:59	50.96	OK	17786	2026-09-22 19:00	50.46	OK
17787	2026-09-22 19:01	47.64	OK	17788	2026-09-22 19:02	49.16	OK
17789	2026-09-22 19:03	47.98	OK	17790	2026-09-22 19:04	49.70	OK
17791	2026-09-22 19:05	48.56	OK	17792	2026-09-22 19:06	50.54	OK
17793	2026-09-22 19:07	48.02	OK	17794	2026-09-22 19:08	48.57	OK
1779	2026-09-22 19:09	50.29	OK	1779	2026-09-22 19:10	47.86	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
17797	2026-09-22 19:11	47.99	OK	17798	2026-09-22 19:12	48.99	OK
17799	2026-09-22 19:13	48.20	OK	17800	2026-09-22 19:14	47.96	OK
17801	2026-09-22 19:15	48.33	OK	17802	2026-09-22 19:16	47.82	OK
17803	2026-09-22 19:17	48.40	OK	17804	2026-09-22 19:18	48.04	OK
17805	2026-09-22 19:19	46.50	OK	17806	2026-09-22 19:20	50.22	OK
17807	2026-09-22 19:21	48.66	OK	17808	2026-09-22 19:22	49.71	OK
17809	2026-09-22 19:23	49.62	OK	17810	2026-09-22 19:24	48.14	OK
17811	2026-09-22 19:25	48.65	OK	17812	2026-09-22 19:26	47.38	OK
17813	2026-09-22 19:27	47.97	OK	17814	2026-09-22 19:28	47.94	OK
17815	2026-09-22 19:29	47.41	OK	17816	2026-09-22 19:30	49.08	OK
17817	2026-09-22 19:31	50.62	OK	17818	2026-09-22 19:32	48.18	OK
17819	2026-09-22 19:33	48.75	OK	17820	2026-09-22 19:34	48.40	OK
17821	2026-09-22 19:35	47.22	OK	17822	2026-09-22 19:36	49.47	OK
17823	2026-09-22 19:37	48.43	OK	17824	2026-09-22 19:38	48.25	OK
17825	2026-09-22 19:39	46.39	OK	17826	2026-09-22 19:40	48.35	OK
17827	2026-09-22 19:41	47.76	OK	17828	2026-09-22 19:42	49.10	OK
17829	2026-09-22 19:43	49.02	OK	17830	2026-09-22 19:44	48.78	OK
17831	2026-09-22 19:45	48.42	OK	17832	2026-09-22 19:46	48.46	OK
17833	2026-09-22 19:47	48.33	OK	17834	2026-09-22 19:48	48.87	OK
17835	2026-09-22 19:49	48.39	OK	17836	2026-09-22 19:50	49.60	OK
17837	2026-09-22 19:51	47.94	OK	17838	2026-09-22 19:52	48.33	OK
17839	2026-09-22 19:53	48.33	OK	17840	2026-09-22 19:54	48.87	OK
17841	2026-09-22 19:55	46.95	OK	17842	2026-09-22 19:56	48.43	OK
17843	2026-09-22 19:57	48.10	OK	17844	2026-09-22 19:58	48.93	OK
17845	2026-09-22 19:59	47.63	OK	17846	2026-09-22 20:00	47.00	OK
17847	2026-09-22 20:01	48.59	OK	17848	2026-09-22 20:02	46.31	OK
17849	2026-09-22 20:03	49.27	OK	17850	2026-09-22 20:04	47.67	OK
17851	2026-09-22 20:05	48.35	OK	17852	2026-09-22 20:06	47.86	OK
17853	2026-09-22 20:07	48.01	OK	17854	2026-09-22 20:08	49.15	OK
1785	2026-09-22 20:09	49.37	OK	1785	2026-09-22 20:10	47.53	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
17857	2026-09-22 20:11	47.36	OK	17858	2026-09-22 20:12	48.57	OK
17859	2026-09-22 20:13	46.90	OK	17860	2026-09-22 20:14	47.79	OK
17861	2026-09-22 20:15	48.30	OK	17862	2026-09-22 20:16	48.13	OK
17863	2026-09-22 20:17	47.59	OK	17864	2026-09-22 20:18	48.89	OK
17865	2026-09-22 20:19	47.60	OK	17866	2026-09-22 20:20	47.43	OK
17867	2026-09-22 20:21	48.32	OK	17868	2026-09-22 20:22	45.41	OK
17869	2026-09-22 20:23	45.57	OK	17870	2026-09-22 20:24	46.32	OK
17871	2026-09-22 20:25	46.96	OK	17872	2026-09-22 20:26	47.11	OK
17873	2026-09-22 20:27	48.65	OK	17874	2026-09-22 20:28	47.30	OK
17875	2026-09-22 20:29	49.41	OK	17876	2026-09-22 20:30	48.50	OK
17877	2026-09-22 20:31	48.70	OK	17878	2026-09-22 20:32	47.83	OK
17879	2026-09-22 20:33	46.54	OK	17880	2026-09-22 20:34	49.53	OK
17881	2026-09-22 20:35	47.58	OK	17882	2026-09-22 20:36	47.71	OK
17883	2026-09-22 20:37	46.73	OK	17884	2026-09-22 20:38	46.51	OK
17885	2026-09-22 20:39	46.83	OK	17886	2026-09-22 20:40	47.82	OK
17887	2026-09-22 20:41	47.55	OK	17888	2026-09-22 20:42	46.64	OK
17889	2026-09-22 20:43	47.49	OK	17890	2026-09-22 20:44	48.21	OK
17891	2026-09-22 20:45	46.64	OK	17892	2026-09-22 20:46	47.67	OK
17893	2026-09-22 20:47	48.97	OK	17894	2026-09-22 20:48	47.04	OK
17895	2026-09-22 20:49	46.00	OK	17896	2026-09-22 20:50	47.20	OK
17897	2026-09-22 20:51	46.83	OK	17898	2026-09-22 20:52	47.49	OK
17899	2026-09-22 20:53	46.13	OK	17900	2026-09-22 20:54	46.19	OK
17901	2026-09-22 20:55	48.66	OK	17902	2026-09-22 20:56	47.70	OK
17903	2026-09-22 20:57	47.03	OK	17904	2026-09-22 20:58	47.77	OK
17905	2026-09-22 20:59	48.85	OK	17906	2026-09-22 21:00	46.88	OK
17907	2026-09-22 21:01	45.84	OK	17908	2026-09-22 21:02	47.75	OK
17909	2026-09-22 21:03	48.13	OK	17910	2026-09-22 21:04	47.90	OK
17911	2026-09-22 21:05	47.14	OK	17912	2026-09-22 21:06	48.17	OK
17913	2026-09-22 21:07	46.51	OK	17914	2026-09-22 21:08	47.98	OK
1791	2026-09-22 21:09	46.22	OK	1791	2026-09-22 21:10	46.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
17917	2026-09-22 21:11	45.96	OK	17918	2026-09-22 21:12	45.97	OK
17919	2026-09-22 21:13	46.79	OK	17920	2026-09-22 21:14	45.26	OK
17921	2026-09-22 21:15	45.46	OK	17922	2026-09-22 21:16	47.27	OK
17923	2026-09-22 21:17	48.30	OK	17924	2026-09-22 21:18	46.05	OK
17925	2026-09-22 21:19	47.08	OK	17926	2026-09-22 21:20	47.59	OK
17927	2026-09-22 21:21	44.55	OK	17928	2026-09-22 21:22	48.49	OK
17929	2026-09-22 21:23	47.18	OK	17930	2026-09-22 21:24	46.72	OK
17931	2026-09-22 21:25	48.63	OK	17932	2026-09-22 21:26	47.02	OK
17933	2026-09-22 21:27	47.14	OK	17934	2026-09-22 21:28	47.73	OK
17935	2026-09-22 21:29	46.02	OK	17936	2026-09-22 21:30	46.83	OK
17937	2026-09-22 21:31	45.60	OK	17938	2026-09-22 21:32	46.63	OK
17939	2026-09-22 21:33	48.15	OK	17940	2026-09-22 21:34	45.53	OK
17941	2026-09-22 21:35	48.03	OK	17942	2026-09-22 21:36	45.77	OK
17943	2026-09-22 21:37	46.34	OK	17944	2026-09-22 21:38	48.08	OK
17945	2026-09-22 21:39	46.73	OK	17946	2026-09-22 21:40	44.76	OK
17947	2026-09-22 21:41	47.17	OK	17948	2026-09-22 21:42	46.12	OK
17949	2026-09-22 21:43	46.06	OK	17950	2026-09-22 21:44	46.45	OK
17951	2026-09-22 21:45	48.31	OK	17952	2026-09-22 21:46	47.13	OK
17953	2026-09-22 21:47	47.90	OK	17954	2026-09-22 21:48	45.66	OK
17955	2026-09-22 21:49	46.37	OK	17956	2026-09-22 21:50	46.84	OK
17957	2026-09-22 21:51	46.53	OK	17958	2026-09-22 21:52	47.70	OK
17959	2026-09-22 21:53	45.37	OK	17960	2026-09-22 21:54	47.34	OK
17961	2026-09-22 21:55	45.04	OK	17962	2026-09-22 21:56	45.70	OK
17963	2026-09-22 21:57	47.35	OK	17964	2026-09-22 21:58	46.57	OK
17965	2026-09-22 21:59	45.60	OK	17966	2026-09-22 22:00	46.23	OK
17967	2026-09-22 22:01	46.89	OK	17968	2026-09-22 22:02	46.13	OK
17969	2026-09-22 22:03	46.61	OK	17970	2026-09-22 22:04	47.29	OK
17971	2026-09-22 22:05	48.76	OK	17972	2026-09-22 22:06	45.80	OK
17973	2026-09-22 22:07	44.27	OK	17974	2026-09-22 22:08	47.52	OK
1797	2026-09-22 22:09	46.94	OK	1797	2026-09-22 22:10	46.44	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
17977	2026-09-22 22:11	48.00	OK	17978	2026-09-22 22:12	47.99	OK
17979	2026-09-22 22:13	45.69	OK	17980	2026-09-22 22:14	46.33	OK
17981	2026-09-22 22:15	45.00	OK	17982	2026-09-22 22:16	48.47	OK
17983	2026-09-22 22:17	45.13	OK	17984	2026-09-22 22:18	44.87	OK
17985	2026-09-22 22:19	45.94	OK	17986	2026-09-22 22:20	47.24	OK
17987	2026-09-22 22:21	47.70	OK	17988	2026-09-22 22:22	44.91	OK
17989	2026-09-22 22:23	45.76	OK	17990	2026-09-22 22:24	46.25	OK
17991	2026-09-22 22:25	46.44	OK	17992	2026-09-22 22:26	44.70	OK
17993	2026-09-22 22:27	43.35	OK	17994	2026-09-22 22:28	45.32	OK
17995	2026-09-22 22:29	45.32	OK	17996	2026-09-22 22:30	44.30	OK
17997	2026-09-22 22:31	44.79	OK	17998	2026-09-22 22:32	45.75	OK
17999	2026-09-22 22:33	44.67	OK	18000	2026-09-22 22:34	45.75	OK
18001	2026-09-22 22:35	45.78	OK	18002	2026-09-22 22:36	46.06	OK
18003	2026-09-22 22:37	45.31	OK	18004	2026-09-22 22:38	45.36	OK
18005	2026-09-22 22:39	47.30	OK	18006	2026-09-22 22:40	46.35	OK
18007	2026-09-22 22:41	44.47	OK	18008	2026-09-22 22:42	45.34	OK
18009	2026-09-22 22:43	47.16	OK	18010	2026-09-22 22:44	45.24	OK
18011	2026-09-22 22:45	43.82	OK	18012	2026-09-22 22:46	46.77	OK
18013	2026-09-22 22:47	44.69	OK	18014	2026-09-22 22:48	45.45	OK
18015	2026-09-22 22:49	45.61	OK	18016	2026-09-22 22:50	46.75	OK
18017	2026-09-22 22:51	46.02	OK	18018	2026-09-22 22:52	45.37	OK
18019	2026-09-22 22:53	47.40	OK	18020	2026-09-22 22:54	47.66	OK
18021	2026-09-22 22:55	44.74	OK	18022	2026-09-22 22:56	45.15	OK
18023	2026-09-22 22:57	45.70	OK	18024	2026-09-22 22:58	45.69	OK
18025	2026-09-22 22:59	46.28	OK	18026	2026-09-22 23:00	45.05	OK
18027	2026-09-22 23:01	44.20	OK	18028	2026-09-22 23:02	46.32	OK
18029	2026-09-22 23:03	46.88	OK	18030	2026-09-22 23:04	45.09	OK
18031	2026-09-22 23:05	45.22	OK	18032	2026-09-22 23:06	48.16	OK
18033	2026-09-22 23:07	45.39	OK	18034	2026-09-22 23:08	45.88	OK
1803	2026-09-22 23:09	45.06	OK	1803	2026-09-22 23:10	47.03	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
18037	2026-09-22 23:11	45.28	OK	18038	2026-09-22 23:12	46.55	OK
18039	2026-09-22 23:13	47.61	OK	18040	2026-09-22 23:14	47.06	OK
18041	2026-09-22 23:15	45.52	OK	18042	2026-09-22 23:16	45.35	OK
18043	2026-09-22 23:17	44.92	OK	18044	2026-09-22 23:18	47.34	OK
18045	2026-09-22 23:19	44.45	OK	18046	2026-09-22 23:20	46.94	OK
18047	2026-09-22 23:21	45.17	OK	18048	2026-09-22 23:22	46.51	OK
18049	2026-09-22 23:23	46.03	OK	18050	2026-09-22 23:24	45.00	OK
18051	2026-09-22 23:25	45.25	OK	18052	2026-09-22 23:26	46.49	OK
18053	2026-09-22 23:27	45.62	OK	18054	2026-09-22 23:28	43.68	OK
18055	2026-09-22 23:29	44.25	OK	18056	2026-09-22 23:30	46.17	OK
18057	2026-09-22 23:31	44.03	OK	18058	2026-09-22 23:32	45.54	OK
18059	2026-09-22 23:33	43.92	OK	18060	2026-09-22 23:34	45.13	OK
18061	2026-09-22 23:35	43.95	OK	18062	2026-09-22 23:36	46.15	OK
18063	2026-09-22 23:37	44.94	OK	18064	2026-09-22 23:38	45.30	OK
18065	2026-09-22 23:39	44.93	OK	18066	2026-09-22 23:40	46.38	OK
18067	2026-09-22 23:41	46.55	OK	18068	2026-09-22 23:42	45.22	OK
18069	2026-09-22 23:43	44.12	OK	18070	2026-09-22 23:44	45.36	OK
18071	2026-09-22 23:45	44.41	OK	18072	2026-09-22 23:46	43.79	OK
18073	2026-09-22 23:47	45.18	OK	18074	2026-09-22 23:48	44.26	OK
18075	2026-09-22 23:49	45.42	OK	18076	2026-09-22 23:50	44.41	OK
18077	2026-09-22 23:51	45.97	OK	18078	2026-09-22 23:52	45.68	OK
18079	2026-09-22 23:53	45.96	OK	18080	2026-09-22 23:54	44.96	OK
18081	2026-09-22 23:55	45.82	OK	18082	2026-09-22 23:56	45.01	OK
18083	2026-09-22 23:57	44.12	OK	18084	2026-09-22 23:58	45.96	OK
18085	2026-09-22 23:59	45.38	OK	18086	2026-09-23 00:00	43.78	OK
18087	2026-09-23 00:01	45.83	OK	18088	2026-09-23 00:02	46.06	OK
18089	2026-09-23 00:03	46.04	OK	18090	2026-09-23 00:04	44.68	OK
18091	2026-09-23 00:05	45.33	OK	18092	2026-09-23 00:06	46.22	OK
18093	2026-09-23 00:07	44.22	OK	18094	2026-09-23 00:08	45.44	OK
1809	2026-09-23 00:09	45.71	OK	1809	2026-09-23 00:10	43.92	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
18097	2026-09-23 00:11	45.67	OK	18098	2026-09-23 00:12	46.40	OK
18099	2026-09-23 00:13	45.23	OK	18100	2026-09-23 00:14	44.91	OK
18101	2026-09-23 00:15	45.30	OK	18102	2026-09-23 00:16	43.92	OK
18103	2026-09-23 00:17	46.12	OK	18104	2026-09-23 00:18	44.10	OK
18105	2026-09-23 00:19	45.68	OK	18106	2026-09-23 00:20	46.07	OK
18107	2026-09-23 00:21	44.94	OK	18108	2026-09-23 00:22	43.80	OK
18109	2026-09-23 00:23	45.00	OK	18110	2026-09-23 00:24	45.92	OK
18111	2026-09-23 00:25	46.48	OK	18112	2026-09-23 00:26	45.53	OK
18113	2026-09-23 00:27	46.79	OK	18114	2026-09-23 00:28	47.60	OK
18115	2026-09-23 00:29	44.80	OK	18116	2026-09-23 00:30	43.48	OK
18117	2026-09-23 00:31	42.91	OK	18118	2026-09-23 00:32	47.39	OK
18119	2026-09-23 00:33	45.11	OK	18120	2026-09-23 00:34	45.39	OK
18121	2026-09-23 00:35	45.56	OK	18122	2026-09-23 00:36	42.95	OK
18123	2026-09-23 00:37	45.18	OK	18124	2026-09-23 00:38	45.82	OK
18125	2026-09-23 00:39	45.29	OK	18126	2026-09-23 00:40	45.06	OK
18127	2026-09-23 00:41	44.29	OK	18128	2026-09-23 00:42	44.97	OK
18129	2026-09-23 00:43	45.95	OK	18130	2026-09-23 00:44	44.62	OK
18131	2026-09-23 00:45	46.19	OK	18132	2026-09-23 00:46	43.96	OK
18133	2026-09-23 00:47	44.26	OK	18134	2026-09-23 00:48	44.33	OK
18135	2026-09-23 00:49	44.33	OK	18136	2026-09-23 00:50	46.32	OK
18137	2026-09-23 00:51	43.81	OK	18138	2026-09-23 00:52	46.15	OK
18139	2026-09-23 00:53	43.38	OK	18140	2026-09-23 00:54	46.10	OK
18141	2026-09-23 00:55	45.91	OK	18142	2026-09-23 00:56	45.22	OK
18143	2026-09-23 00:57	46.73	OK	18144	2026-09-23 00:58	44.83	OK
18145	2026-09-23 00:59	45.70	OK	18146	2026-09-23 01:00	45.93	OK
18147	2026-09-23 01:01	44.38	OK	18148	2026-09-23 01:02	44.78	OK
18149	2026-09-23 01:03	43.95	OK	18150	2026-09-23 01:04	44.47	OK
18151	2026-09-23 01:05	44.58	OK	18152	2026-09-23 01:06	44.17	OK
18153	2026-09-23 01:07	44.82	OK	18154	2026-09-23 01:08	45.14	OK
1815	2026-09-23 01:09	44.68	OK	1815	2026-09-23 01:10	45.54	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
18157	2026-09-23 01:11	46.74	OK	18158	2026-09-23 01:12	46.28	OK
18159	2026-09-23 01:13	45.46	OK	18160	2026-09-23 01:14	44.55	OK
18161	2026-09-23 01:15	44.61	OK	18162	2026-09-23 01:16	45.59	OK
18163	2026-09-23 01:17	44.22	OK	18164	2026-09-23 01:18	45.74	OK
18165	2026-09-23 01:19	45.01	OK	18166	2026-09-23 01:20	45.91	OK
18167	2026-09-23 01:21	45.94	OK	18168	2026-09-23 01:22	44.30	OK
18169	2026-09-23 01:23	45.06	OK	18170	2026-09-23 01:24	44.81	OK
18171	2026-09-23 01:25	45.92	OK	18172	2026-09-23 01:26	47.13	OK
18173	2026-09-23 01:27	45.78	OK	18174	2026-09-23 01:28	45.29	OK
18175	2026-09-23 01:29	45.56	OK	18176	2026-09-23 01:30	45.53	OK
18177	2026-09-23 01:31	44.22	OK	18178	2026-09-23 01:32	46.02	OK
18179	2026-09-23 01:33	45.89	OK	18180	2026-09-23 01:34	44.10	OK
18181	2026-09-23 01:35	44.90	OK	18182	2026-09-23 01:36	43.41	OK
18183	2026-09-23 01:37	46.29	OK	18184	2026-09-23 01:38	45.97	OK
18185	2026-09-23 01:39	44.51	OK	18186	2026-09-23 01:40	45.99	OK
18187	2026-09-23 01:41	45.43	OK	18188	2026-09-23 01:42	46.13	OK
18189	2026-09-23 01:43	46.17	OK	18190	2026-09-23 01:44	43.67	OK
18191	2026-09-23 01:45	43.47	OK	18192	2026-09-23 01:46	44.77	OK
18193	2026-09-23 01:47	46.35	OK	18194	2026-09-23 01:48	46.69	OK
18195	2026-09-23 01:49	45.57	OK	18196	2026-09-23 01:50	44.41	OK
18197	2026-09-23 01:51	45.41	OK	18198	2026-09-23 01:52	46.05	OK
18199	2026-09-23 01:53	46.37	OK	18200	2026-09-23 01:54	43.24	OK
18201	2026-09-23 01:55	46.40	OK	18202	2026-09-23 01:56	44.96	OK
18203	2026-09-23 01:57	46.69	OK	18204	2026-09-23 01:58	45.24	OK
18205	2026-09-23 01:59	46.72	OK	18206	2026-09-23 02:00	44.24	OK
18207	2026-09-23 02:01	44.67	OK	18208	2026-09-23 02:02	43.82	OK
18209	2026-09-23 02:03	45.54	OK	18210	2026-09-23 02:04	44.16	OK
18211	2026-09-23 02:05	44.51	OK	18212	2026-09-23 02:06	45.25	OK
18213	2026-09-23 02:07	46.00	OK	18214	2026-09-23 02:08	44.11	OK
1821	2026-09-23 02:09	46.43	OK	1821	2026-09-23 02:10	44.13	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
18217	2026-09-23 02:11	43.97	OK	18218	2026-09-23 02:12	42.99	OK
18219	2026-09-23 02:13	44.72	OK	18220	2026-09-23 02:14	43.62	OK
18221	2026-09-23 02:15	46.00	OK	18222	2026-09-23 02:16	43.51	OK
18223	2026-09-23 02:17	46.47	OK	18224	2026-09-23 02:18	43.84	OK
18225	2026-09-23 02:19	45.11	OK	18226	2026-09-23 02:20	44.17	OK
18227	2026-09-23 02:21	46.04	OK	18228	2026-09-23 02:22	44.24	OK
18229	2026-09-23 02:23	43.76	OK	18230	2026-09-23 02:24	45.35	OK
18231	2026-09-23 02:25	44.88	OK	18232	2026-09-23 02:26	43.92	OK
18233	2026-09-23 02:27	43.17	OK	18234	2026-09-23 02:28	44.91	OK
18235	2026-09-23 02:29	45.09	OK	18236	2026-09-23 02:30	46.47	OK
18237	2026-09-23 02:31	46.59	OK	18238	2026-09-23 02:32	44.66	OK
18239	2026-09-23 02:33	43.62	OK	18240	2026-09-23 02:34	45.33	OK
18241	2026-09-23 02:35	45.82	OK	18242	2026-09-23 02:36	45.92	OK
18243	2026-09-23 02:37	45.63	OK	18244	2026-09-23 02:38	43.63	OK
18245	2026-09-23 02:39	44.41	OK	18246	2026-09-23 02:40	45.33	OK
18247	2026-09-23 02:41	46.47	OK	18248	2026-09-23 02:42	46.69	OK
18249	2026-09-23 02:43	44.49	OK	18250	2026-09-23 02:44	45.17	OK
18251	2026-09-23 02:45	44.44	OK	18252	2026-09-23 02:46	45.89	OK
18253	2026-09-23 02:47	46.01	OK	18254	2026-09-23 02:48	46.31	OK
18255	2026-09-23 02:49	44.40	OK	18256	2026-09-23 02:50	46.71	OK
18257	2026-09-23 02:51	47.05	OK	18258	2026-09-23 02:52	44.73	OK
18259	2026-09-23 02:53	46.27	OK	18260	2026-09-23 02:54	44.93	OK
18261	2026-09-23 02:55	44.75	OK	18262	2026-09-23 02:56	45.22	OK
18263	2026-09-23 02:57	44.12	OK	18264	2026-09-23 02:58	44.85	OK
18265	2026-09-23 02:59	45.61	OK	18266	2026-09-23 03:00	45.80	OK
18267	2026-09-23 03:01	44.32	OK	18268	2026-09-23 03:02	44.44	OK
18269	2026-09-23 03:03	46.60	OK	18270	2026-09-23 03:04	45.13	OK
18271	2026-09-23 03:05	44.01	OK	18272	2026-09-23 03:06	45.28	OK
18273	2026-09-23 03:07	44.44	OK	18274	2026-09-23 03:08	45.52	OK
1827	2026-09-23 03:09	45.82	OK	1827	2026-09-23 03:10	46.35	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
18277	2026-09-23 03:11	45.06	OK	18278	2026-09-23 03:12	44.10	OK
18279	2026-09-23 03:13	47.59	OK	18280	2026-09-23 03:14	44.15	OK
18281	2026-09-23 03:15	45.79	OK	18282	2026-09-23 03:16	45.50	OK
18283	2026-09-23 03:17	47.06	OK	18284	2026-09-23 03:18	44.82	OK
18285	2026-09-23 03:19	47.08	OK	18286	2026-09-23 03:20	46.32	OK
18287	2026-09-23 03:21	46.38	OK	18288	2026-09-23 03:22	46.98	OK
18289	2026-09-23 03:23	43.60	OK	18290	2026-09-23 03:24	46.09	OK
18291	2026-09-23 03:25	46.27	OK	18292	2026-09-23 03:26	45.63	OK
18293	2026-09-23 03:27	45.47	OK	18294	2026-09-23 03:28	45.44	OK
18295	2026-09-23 03:29	46.15	OK	18296	2026-09-23 03:30	45.72	OK
18297	2026-09-23 03:31	43.26	OK	18298	2026-09-23 03:32	45.66	OK
18299	2026-09-23 03:33	45.42	OK	18300	2026-09-23 03:34	46.86	OK
18301	2026-09-23 03:35	46.78	OK	18302	2026-09-23 03:36	45.42	OK
18303	2026-09-23 03:37	45.53	OK	18304	2026-09-23 03:38	46.55	OK
18305	2026-09-23 03:39	45.22	OK	18306	2026-09-23 03:40	45.23	OK
18307	2026-09-23 03:41	44.95	OK	18308	2026-09-23 03:42	47.08	OK
18309	2026-09-23 03:43	45.50	OK	18310	2026-09-23 03:44	45.85	OK
18311	2026-09-23 03:45	44.81	OK	18312	2026-09-23 03:46	46.61	OK
18313	2026-09-23 03:47	45.29	OK	18314	2026-09-23 03:48	46.75	OK
18315	2026-09-23 03:49	45.07	OK	18316	2026-09-23 03:50	45.33	OK
18317	2026-09-23 03:51	45.32	OK	18318	2026-09-23 03:52	46.68	OK
18319	2026-09-23 03:53	47.99	OK	18320	2026-09-23 03:54	46.86	OK
18321	2026-09-23 03:55	45.54	OK	18322	2026-09-23 03:56	44.52	OK
18323	2026-09-23 03:57	45.09	OK	18324	2026-09-23 03:58	44.94	OK
18325	2026-09-23 03:59	46.45	OK	18326	2026-09-23 04:00	45.13	OK
18327	2026-09-23 04:01	46.72	OK	18328	2026-09-23 04:02	43.88	OK
18329	2026-09-23 04:03	45.76	OK	18330	2026-09-23 04:04	47.41	OK
18331	2026-09-23 04:05	47.39	OK	18332	2026-09-23 04:06	45.59	OK
18333	2026-09-23 04:07	44.58	OK	18334	2026-09-23 04:08	45.65	OK
1833	2026-09-23 04:09	47.94	OK	1833	2026-09-23 04:10	46.80	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
18337	2026-09-23 04:11	47.51	OK	18338	2026-09-23 04:12	46.43	OK
18339	2026-09-23 04:13	46.64	OK	18340	2026-09-23 04:14	46.11	OK
18341	2026-09-23 04:15	45.50	OK	18342	2026-09-23 04:16	47.43	OK
18343	2026-09-23 04:17	46.53	OK	18344	2026-09-23 04:18	47.43	OK
18345	2026-09-23 04:19	47.44	OK	18346	2026-09-23 04:20	45.44	OK
18347	2026-09-23 04:21	45.23	OK	18348	2026-09-23 04:22	45.15	OK
18349	2026-09-23 04:23	46.39	OK	18350	2026-09-23 04:24	44.90	OK
18351	2026-09-23 04:25	46.97	OK	18352	2026-09-23 04:26	45.41	OK
18353	2026-09-23 04:27	45.63	OK	18354	2026-09-23 04:28	46.54	OK
18355	2026-09-23 04:29	46.70	OK	18356	2026-09-23 04:30	47.40	OK
18357	2026-09-23 04:31	46.45	OK	18358	2026-09-23 04:32	46.13	OK
18359	2026-09-23 04:33	46.75	OK	18360	2026-09-23 04:34	47.08	OK
18361	2026-09-23 04:35	44.93	OK	18362	2026-09-23 04:36	45.94	OK
18363	2026-09-23 04:37	45.36	OK	18364	2026-09-23 04:38	46.59	OK
18365	2026-09-23 04:39	47.56	OK	18366	2026-09-23 04:40	47.99	OK
18367	2026-09-23 04:41	46.75	OK	18368	2026-09-23 04:42	46.77	OK
18369	2026-09-23 04:43	44.51	OK	18370	2026-09-23 04:44	48.16	OK
18371	2026-09-23 04:45	46.89	OK	18372	2026-09-23 04:46	48.74	OK
18373	2026-09-23 04:47	45.18	OK	18374	2026-09-23 04:48	46.80	OK
18375	2026-09-23 04:49	47.52	OK	18376	2026-09-23 04:50	45.57	OK
18377	2026-09-23 04:51	47.13	OK	18378	2026-09-23 04:52	46.37	OK
18379	2026-09-23 04:53	46.97	OK	18380	2026-09-23 04:54	45.50	OK
18381	2026-09-23 04:55	48.18	OK	18382	2026-09-23 04:56	45.98	OK
18383	2026-09-23 04:57	47.46	OK	18384	2026-09-23 04:58	45.59	OK
18385	2026-09-23 04:59	46.10	OK	18386	2026-09-23 05:00	47.34	OK
18387	2026-09-23 05:01	46.10	OK	18388	2026-09-23 05:02	48.70	OK
18389	2026-09-23 05:03	47.00	OK	18390	2026-09-23 05:04	45.56	OK
18391	2026-09-23 05:05	45.37	OK	18392	2026-09-23 05:06	46.94	OK
18393	2026-09-23 05:07	45.48	OK	18394	2026-09-23 05:08	46.45	OK
1839	2026-09-23 05:09	46.74	OK	1839	2026-09-23 05:10	45.97	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
18397	2026-09-23 05:11	45.66	OK	18398	2026-09-23 05:12	46.80	OK
18399	2026-09-23 05:13	47.79	OK	18400	2026-09-23 05:14	47.23	OK
18401	2026-09-23 05:15	46.98	OK	18402	2026-09-23 05:16	45.44	OK
18403	2026-09-23 05:17	45.84	OK	18404	2026-09-23 05:18	45.95	OK
18405	2026-09-23 05:19	47.64	OK	18406	2026-09-23 05:20	45.68	OK
18407	2026-09-23 05:21	48.40	OK	18408	2026-09-23 05:22	45.75	OK
18409	2026-09-23 05:23	47.57	OK	18410	2026-09-23 05:24	45.59	OK
18411	2026-09-23 05:25	46.55	OK	18412	2026-09-23 05:26	46.62	OK
18413	2026-09-23 05:27	46.55	OK	18414	2026-09-23 05:28	48.27	OK
18415	2026-09-23 05:29	48.07	OK	18416	2026-09-23 05:30	46.27	OK
18417	2026-09-23 05:31	46.00	OK	18418	2026-09-23 05:32	48.89	OK
18419	2026-09-23 05:33	48.50	OK	18420	2026-09-23 05:34	46.48	OK
18421	2026-09-23 05:35	47.01	OK	18422	2026-09-23 05:36	45.71	OK
18423	2026-09-23 05:37	45.16	OK	18424	2026-09-23 05:38	47.28	OK
18425	2026-09-23 05:39	46.50	OK	18426	2026-09-23 05:40	46.25	OK
18427	2026-09-23 05:41	45.34	OK	18428	2026-09-23 05:42	46.80	OK
18429	2026-09-23 05:43	47.77	OK	18430	2026-09-23 05:44	46.24	OK
18431	2026-09-23 05:45	47.90	OK	18432	2026-09-23 05:46	47.30	OK
18433	2026-09-23 05:47	47.58	OK	18434	2026-09-23 05:48	48.04	OK
18435	2026-09-23 05:49	48.16	OK	18436	2026-09-23 05:50	45.76	OK
18437	2026-09-23 05:51	46.35	OK	18438	2026-09-23 05:52	48.74	OK
18439	2026-09-23 05:53	47.19	OK	18440	2026-09-23 05:54	46.04	OK
18441	2026-09-23 05:55	46.69	OK	18442	2026-09-23 05:56	46.85	OK
18443	2026-09-23 05:57	47.57	OK	18444	2026-09-23 05:58	49.06	OK
18445	2026-09-23 05:59	46.97	OK	18446	2026-09-23 06:00	46.85	OK
18447	2026-09-23 06:01	47.71	OK	18448	2026-09-23 06:02	47.98	OK
18449	2026-09-23 06:03	50.09	OK	18450	2026-09-23 06:04	47.79	OK
18451	2026-09-23 06:05	46.74	OK	18452	2026-09-23 06:06	46.98	OK
18453	2026-09-23 06:07	46.44	OK	18454	2026-09-23 06:08	45.76	OK
1845	2026-09-23 06:09	47.90	OK	1845	2026-09-23 06:10	46.83	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
18457	2026-09-23 06:11	47.14	OK	18458	2026-09-23 06:12	46.25	OK
18459	2026-09-23 06:13	46.46	OK	18460	2026-09-23 06:14	47.57	OK
18461	2026-09-23 06:15	47.07	OK	18462	2026-09-23 06:16	46.73	OK
18463	2026-09-23 06:17	47.25	OK	18464	2026-09-23 06:18	48.50	OK
18465	2026-09-23 06:19	46.34	OK	18466	2026-09-23 06:20	47.92	OK
18467	2026-09-23 06:21	47.47	OK	18468	2026-09-23 06:22	47.95	OK
18469	2026-09-23 06:23	47.42	OK	18470	2026-09-23 06:24	47.66	OK
18471	2026-09-23 06:25	48.56	OK	18472	2026-09-23 06:26	46.91	OK
18473	2026-09-23 06:27	48.26	OK	18474	2026-09-23 06:28	46.72	OK
18475	2026-09-23 06:29	48.78	OK	18476	2026-09-23 06:30	48.36	OK
18477	2026-09-23 06:31	47.50	OK	18478	2026-09-23 06:32	48.63	OK
18479	2026-09-23 06:33	48.15	OK	18480	2026-09-23 06:34	47.01	OK
18481	2026-09-23 06:35	47.28	OK	18482	2026-09-23 06:36	45.74	OK
18483	2026-09-23 06:37	46.56	OK	18484	2026-09-23 06:38	48.80	OK
18485	2026-09-23 06:39	47.20	OK	18486	2026-09-23 06:40	49.59	OK
18487	2026-09-23 06:41	48.45	OK	18488	2026-09-23 06:42	48.06	OK
18489	2026-09-23 06:43	47.50	OK	18490	2026-09-23 06:44	46.68	OK
18491	2026-09-23 06:45	46.09	OK	18492	2026-09-23 06:46	47.51	OK
18493	2026-09-23 06:47	47.13	OK	18494	2026-09-23 06:48	47.46	OK
18495	2026-09-23 06:49	47.60	OK	18496	2026-09-23 06:50	47.88	OK
18497	2026-09-23 06:51	47.81	OK	18498	2026-09-23 06:52	47.79	OK
18499	2026-09-23 06:53	47.80	OK	18500	2026-09-23 06:54	47.60	OK
18501	2026-09-23 06:55	47.49	OK	18502	2026-09-23 06:56	47.88	OK
18503	2026-09-23 06:57	50.26	OK	18504	2026-09-23 06:58	46.72	OK
18505	2026-09-23 06:59	49.48	OK	18506	2026-09-23 07:00	49.99	OK
18507	2026-09-23 07:01	48.41	OK	18508	2026-09-23 07:02	47.01	OK
18509	2026-09-23 07:03	48.31	OK	18510	2026-09-23 07:04	47.22	OK
18511	2026-09-23 07:05	47.72	OK	18512	2026-09-23 07:06	47.98	OK
18513	2026-09-23 07:07	47.35	OK	18514	2026-09-23 07:08	49.01	OK
1851	2026-09-23 07:09	46.19	OK	1851	2026-09-23 07:10	50.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
18517	2026-09-23 07:11	49.14	OK	18518	2026-09-23 07:12	46.82	OK
18519	2026-09-23 07:13	47.54	OK	18520	2026-09-23 07:14	49.08	OK
18521	2026-09-23 07:15	49.65	OK	18522	2026-09-23 07:16	48.98	OK
18523	2026-09-23 07:17	47.67	OK	18524	2026-09-23 07:18	48.91	OK
18525	2026-09-23 07:19	50.35	OK	18526	2026-09-23 07:20	50.15	OK
18527	2026-09-23 07:21	48.88	OK	18528	2026-09-23 07:22	47.32	OK
18529	2026-09-23 07:23	49.04	OK	18530	2026-09-23 07:24	48.30	OK
18531	2026-09-23 07:25	48.45	OK	18532	2026-09-23 07:26	49.36	OK
18533	2026-09-23 07:27	48.37	OK	18534	2026-09-23 07:28	47.94	OK
18535	2026-09-23 07:29	48.11	OK	18536	2026-09-23 07:30	48.42	OK
18537	2026-09-23 07:31	50.21	OK	18538	2026-09-23 07:32	46.85	OK
18539	2026-09-23 07:33	48.63	OK	18540	2026-09-23 07:34	47.42	OK
18541	2026-09-23 07:35	46.87	OK	18542	2026-09-23 07:36	47.30	OK
18543	2026-09-23 07:37	50.83	OK	18544	2026-09-23 07:38	50.70	OK
18545	2026-09-23 07:39	47.44	OK	18546	2026-09-23 07:40	48.80	OK
18547	2026-09-23 07:41	46.28	OK	18548	2026-09-23 07:42	48.77	OK
18549	2026-09-23 07:43	49.99	OK	18550	2026-09-23 07:44	49.97	OK
18551	2026-09-23 07:45	46.93	OK	18552	2026-09-23 07:46	47.66	OK
18553	2026-09-23 07:47	49.27	OK	18554	2026-09-23 07:48	50.46	OK
18555	2026-09-23 07:49	47.35	OK	18556	2026-09-23 07:50	49.47	OK
18557	2026-09-23 07:51	51.33	OK	18558	2026-09-23 07:52	48.53	OK
18559	2026-09-23 07:53	48.46	OK	18560	2026-09-23 07:54	49.55	OK
18561	2026-09-23 07:55	50.85	OK	18562	2026-09-23 07:56	49.21	OK
18563	2026-09-23 07:57	49.35	OK	18564	2026-09-23 07:58	48.33	OK
18565	2026-09-23 07:59	48.99	OK	18566	2026-09-23 08:00	48.64	OK
18567	2026-09-23 08:01	47.94	OK	18568	2026-09-23 08:02	47.08	OK
18569	2026-09-23 08:03	49.83	OK	18570	2026-09-23 08:04	49.36	OK
18571	2026-09-23 08:05	47.43	OK	18572	2026-09-23 08:06	50.67	OK
18573	2026-09-23 08:07	49.84	OK	18574	2026-09-23 08:08	50.28	OK
1857	2026-09-23 08:09	48.49	OK	1857	2026-09-23 08:10	48.88	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
18577	2026-09-23 08:11	50.88	OK	18578	2026-09-23 08:12	48.25	OK
18579	2026-09-23 08:13	50.50	OK	18580	2026-09-23 08:14	51.06	OK
18581	2026-09-23 08:15	49.86	OK	18582	2026-09-23 08:16	49.14	OK
18583	2026-09-23 08:17	50.75	OK	18584	2026-09-23 08:18	48.44	OK
18585	2026-09-23 08:19	48.25	OK	18586	2026-09-23 08:20	51.22	OK
18587	2026-09-23 08:21	50.42	OK	18588	2026-09-23 08:22	50.16	OK
18589	2026-09-23 08:23	50.59	OK	18590	2026-09-23 08:24	48.26	OK
18591	2026-09-23 08:25	51.70	OK	18592	2026-09-23 08:26	48.21	OK
18593	2026-09-23 08:27	50.99	OK	18594	2026-09-23 08:28	50.34	OK
18595	2026-09-23 08:29	51.12	OK	18596	2026-09-23 08:30	50.02	OK
18597	2026-09-23 08:31	48.33	OK	18598	2026-09-23 08:32	49.15	OK
18599	2026-09-23 08:33	50.04	OK	18600	2026-09-23 08:34	49.35	OK
18601	2026-09-23 08:35	48.12	OK	18602	2026-09-23 08:36	50.60	OK
18603	2026-09-23 08:37	48.91	OK	18604	2026-09-23 08:38	48.03	OK
18605	2026-09-23 08:39	51.25	OK	18606	2026-09-23 08:40	48.79	OK
18607	2026-09-23 08:41	49.72	OK	18608	2026-09-23 08:42	50.25	OK
18609	2026-09-23 08:43	49.35	OK	18610	2026-09-23 08:44	51.30	OK
18611	2026-09-23 08:45	49.82	OK	18612	2026-09-23 08:46	50.30	OK
18613	2026-09-23 08:47	51.87	OK	18614	2026-09-23 08:48	50.04	OK
18615	2026-09-23 08:49	50.24	OK	18616	2026-09-23 08:50	50.72	OK
18617	2026-09-23 08:51	49.26	OK	18618	2026-09-23 08:52	50.40	OK
18619	2026-09-23 08:53	48.90	OK	18620	2026-09-23 08:54	50.73	OK
18621	2026-09-23 08:55	49.72	OK	18622	2026-09-23 08:56	50.60	OK
18623	2026-09-23 08:57	50.63	OK	18624	2026-09-23 08:58	50.18	OK
18625	2026-09-23 08:59	51.06	OK	18626	2026-09-23 09:00	49.65	OK
18627	2026-09-23 09:01	50.65	OK	18628	2026-09-23 09:02	49.27	OK
18629	2026-09-23 09:03	50.72	OK	18630	2026-09-23 09:04	50.88	OK
18631	2026-09-23 09:05	51.79	OK	18632	2026-09-23 09:06	50.56	OK
18633	2026-09-23 09:07	50.03	OK	18634	2026-09-23 09:08	49.42	OK
1863	2026-09-23 09:09	52.63	OK	1863	2026-09-23 09:10	52.24	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
18637	2026-09-23 09:11	48.50	OK	18638	2026-09-23 09:12	50.90	OK
18639	2026-09-23 09:13	50.57	OK	18640	2026-09-23 09:14	48.16	OK
18641	2026-09-23 09:15	51.27	OK	18642	2026-09-23 09:16	52.57	OK
18643	2026-09-23 09:17	51.79	OK	18644	2026-09-23 09:18	49.72	OK
18645	2026-09-23 09:19	50.34	OK	18646	2026-09-23 09:20	49.57	OK
18647	2026-09-23 09:21	48.90	OK	18648	2026-09-23 09:22	50.54	OK
18649	2026-09-23 09:23	50.30	OK	18650	2026-09-23 09:24	50.91	OK
18651	2026-09-23 09:25	49.79	OK	18652	2026-09-23 09:26	49.78	OK
18653	2026-09-23 09:27	50.98	OK	18654	2026-09-23 09:28	48.51	OK
18655	2026-09-23 09:29	49.33	OK	18656	2026-09-23 09:30	49.12	OK
18657	2026-09-23 09:31	50.12	OK	18658	2026-09-23 09:32	48.82	OK
18659	2026-09-23 09:33	49.84	OK	18660	2026-09-23 09:34	51.45	OK
18661	2026-09-23 09:35	51.33	OK	18662	2026-09-23 09:36	49.86	OK
18663	2026-09-23 09:37	50.88	OK	18664	2026-09-23 09:38	51.93	OK
18665	2026-09-23 09:39	50.98	OK	18666	2026-09-23 09:40	49.86	OK
18667	2026-09-23 09:41	50.22	OK	18668	2026-09-23 09:42	49.10	OK
18669	2026-09-23 09:43	51.25	OK	18670	2026-09-23 09:44	49.08	OK
18671	2026-09-23 09:45	48.95	OK	18672	2026-09-23 09:46	49.47	OK
18673	2026-09-23 09:47	49.72	OK	18674	2026-09-23 09:48	51.86	OK
18675	2026-09-23 09:49	51.76	OK	18676	2026-09-23 09:50	51.44	OK
18677	2026-09-23 09:51	51.87	OK	18678	2026-09-23 09:52	50.04	OK
18679	2026-09-23 09:53	50.69	OK	18680	2026-09-23 09:54	50.82	OK
18681	2026-09-23 09:55	51.43	OK	18682	2026-09-23 09:56	50.41	OK
18683	2026-09-23 09:57	51.19	OK	18684	2026-09-23 09:58	50.05	OK
18685	2026-09-23 09:59	48.87	OK	18686	2026-09-23 10:00	52.00	OK
18687	2026-09-23 10:01	48.63	OK	18688	2026-09-23 10:02	50.51	OK
18689	2026-09-23 10:03	50.59	OK	18690	2026-09-23 10:04	51.90	OK
18691	2026-09-23 10:05	51.09	OK	18692	2026-09-23 10:06	50.68	OK
18693	2026-09-23 10:07	50.95	OK	18694	2026-09-23 10:08	49.57	OK
1869	2026-09-23 10:09	50.40	OK	1869	2026-09-23 10:10	51.23	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
18697	2026-09-23 10:11	51.98	OK	18698	2026-09-23 10:12	51.62	OK
18699	2026-09-23 10:13	50.80	OK	18700	2026-09-23 10:14	51.68	OK
18701	2026-09-23 10:15	50.57	OK	18702	2026-09-23 10:16	51.55	OK
18703	2026-09-23 10:17	52.31	OK	18704	2026-09-23 10:18	51.29	OK
18705	2026-09-23 10:19	50.95	OK	18706	2026-09-23 10:20	48.86	OK
18707	2026-09-23 10:21	48.08	OK	18708	2026-09-23 10:22	52.16	OK
18709	2026-09-23 10:23	49.09	OK	18710	2026-09-23 10:24	50.82	OK
18711	2026-09-23 10:25	50.49	OK	18712	2026-09-23 10:26	51.20	OK
18713	2026-09-23 10:27	51.82	OK	18714	2026-09-23 10:28	50.56	OK
18715	2026-09-23 10:29	50.16	OK	18716	2026-09-23 10:30	51.63	OK
18717	2026-09-23 10:31	49.87	OK	18718	2026-09-23 10:32	52.24	OK
18719	2026-09-23 10:33	51.46	OK	18720	2026-09-23 10:34	51.20	OK
18721	2026-09-23 10:35	49.77	OK	18722	2026-09-23 10:36	51.57	OK
18723	2026-09-23 10:37	52.16	OK	18724	2026-09-23 10:38	50.60	OK
18725	2026-09-23 10:39	51.42	OK	18726	2026-09-23 10:40	51.22	OK
18727	2026-09-23 10:41	52.17	OK	18728	2026-09-23 10:42	51.92	OK
18729	2026-09-23 10:43	51.08	OK	18730	2026-09-23 10:44	52.76	OK
18731	2026-09-23 10:45	51.05	OK	18732	2026-09-23 10:46	51.14	OK
18733	2026-09-23 10:47	50.31	OK	18734	2026-09-23 10:48	51.89	OK
18735	2026-09-23 10:49	51.14	OK	18736	2026-09-23 10:50	51.37	OK
18737	2026-09-23 10:51	51.16	OK	18738	2026-09-23 10:52	50.98	OK
18739	2026-09-23 10:53	51.09	OK	18740	2026-09-23 10:54	51.74	OK
18741	2026-09-23 10:55	51.94	OK	18742	2026-09-23 10:56	52.80	OK
18743	2026-09-23 10:57	50.57	OK	18744	2026-09-23 10:58	50.98	OK
18745	2026-09-23 10:59	52.17	OK	18746	2026-09-23 11:00	50.82	OK
18747	2026-09-23 11:01	51.53	OK	18748	2026-09-23 11:02	52.10	OK
18749	2026-09-23 11:03	51.81	OK	18750	2026-09-23 11:04	51.02	OK
18751	2026-09-23 11:05	50.93	OK	18752	2026-09-23 11:06	52.25	OK
18753	2026-09-23 11:07	51.56	OK	18754	2026-09-23 11:08	50.39	OK
1875	2026-09-23 11:09	52.81	OK	1875	2026-09-23 11:10	51.36	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
18757	2026-09-23 11:11	49.85	OK	18758	2026-09-23 11:12	52.09	OK
18759	2026-09-23 11:13	49.44	OK	18760	2026-09-23 11:14	51.80	OK
18761	2026-09-23 11:15	50.55	OK	18762	2026-09-23 11:16	53.15	OK
18763	2026-09-23 11:17	51.84	OK	18764	2026-09-23 11:18	52.37	OK
18765	2026-09-23 11:19	51.66	OK	18766	2026-09-23 11:20	50.32	OK
18767	2026-09-23 11:21	49.41	OK	18768	2026-09-23 11:22	50.75	OK
18769	2026-09-23 11:23	52.06	OK	18770	2026-09-23 11:24	50.43	OK
18771	2026-09-23 11:25	53.00	OK	18772	2026-09-23 11:26	50.92	OK
18773	2026-09-23 11:27	51.31	OK	18774	2026-09-23 11:28	51.85	OK
18775	2026-09-23 11:29	51.91	OK	18776	2026-09-23 11:30	52.52	OK
18777	2026-09-23 11:31	53.96	OK	18778	2026-09-23 11:32	49.85	OK
18779	2026-09-23 11:33	50.86	OK	18780	2026-09-23 11:34	50.51	OK
18781	2026-09-23 11:35	50.24	OK	18782	2026-09-23 11:36	53.03	OK
18783	2026-09-23 11:37	51.90	OK	18784	2026-09-23 11:38	51.02	OK
18785	2026-09-23 11:39	51.68	OK	18786	2026-09-23 11:40	50.88	OK
18787	2026-09-23 11:41	50.23	OK	18788	2026-09-23 11:42	51.57	OK
18789	2026-09-23 11:43	52.46	OK	18790	2026-09-23 11:44	49.27	OK
18791	2026-09-23 11:45	52.15	OK	18792	2026-09-23 11:46	50.66	OK
18793	2026-09-23 11:47	52.67	OK	18794	2026-09-23 11:48	51.31	OK
18795	2026-09-23 11:49	50.97	OK	18796	2026-09-23 11:50	52.07	OK
18797	2026-09-23 11:51	50.90	OK	18798	2026-09-23 11:52	49.28	OK
18799	2026-09-23 11:53	53.48	OK	18800	2026-09-23 11:54	50.41	OK
18801	2026-09-23 11:55	51.14	OK	18802	2026-09-23 11:56	51.36	OK
18803	2026-09-23 11:57	51.70	OK	18804	2026-09-23 11:58	51.47	OK
18805	2026-09-23 11:59	50.65	OK	18806	2026-09-23 12:00	51.03	OK
18807	2026-09-23 12:01	51.30	OK	18808	2026-09-23 12:02	52.92	OK
18809	2026-09-23 12:03	52.74	OK	18810	2026-09-23 12:04	51.41	OK
18811	2026-09-23 12:05	52.63	OK	18812	2026-09-23 12:06	53.10	OK
18813	2026-09-23 12:07	53.42	OK	18814	2026-09-23 12:08	52.38	OK
1881	2026-09-23 12:09	51.03	OK	1881	2026-09-23 12:10	52.92	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
18817	2026-09-23 12:11	52.01	OK	18818	2026-09-23 12:12	51.72	OK
18819	2026-09-23 12:13	52.19	OK	18820	2026-09-23 12:14	52.65	OK
18821	2026-09-23 12:15	53.66	OK	18822	2026-09-23 12:16	52.34	OK
18823	2026-09-23 12:17	52.11	OK	18824	2026-09-23 12:18	52.03	OK
18825	2026-09-23 12:19	52.41	OK	18826	2026-09-23 12:20	53.02	OK
18827	2026-09-23 12:21	50.29	OK	18828	2026-09-23 12:22	53.22	OK
18829	2026-09-23 12:23	54.49	OK	18830	2026-09-23 12:24	51.25	OK
18831	2026-09-23 12:25	49.83	OK	18832	2026-09-23 12:26	50.94	OK
18833	2026-09-23 12:27	51.94	OK	18834	2026-09-23 12:28	50.66	OK
18835	2026-09-23 12:29	49.59	OK	18836	2026-09-23 12:30	52.92	OK
18837	2026-09-23 12:31	51.11	OK	18838	2026-09-23 12:32	51.23	OK
18839	2026-09-23 12:33	53.79	OK	18840	2026-09-23 12:34	51.95	OK
18841	2026-09-23 12:35	51.24	OK	18842	2026-09-23 12:36	52.26	OK
18843	2026-09-23 12:37	52.71	OK	18844	2026-09-23 12:38	51.75	OK
18845	2026-09-23 12:39	50.56	OK	18846	2026-09-23 12:40	51.49	OK
18847	2026-09-23 12:41	54.29	OK	18848	2026-09-23 12:42	52.53	OK
18849	2026-09-23 12:43	51.71	OK	18850	2026-09-23 12:44	51.28	OK
18851	2026-09-23 12:45	50.74	OK	18852	2026-09-23 12:46	50.29	OK
18853	2026-09-23 12:47	52.42	OK	18854	2026-09-23 12:48	53.42	OK
18855	2026-09-23 12:49	53.64	OK	18856	2026-09-23 12:50	50.72	OK
18857	2026-09-23 12:51	52.78	OK	18858	2026-09-23 12:52	50.16	OK
18859	2026-09-23 12:53	51.70	OK	18860	2026-09-23 12:54	51.76	OK
18861	2026-09-23 12:55	51.89	OK	18862	2026-09-23 12:56	51.68	OK
18863	2026-09-23 12:57	52.61	OK	18864	2026-09-23 12:58	50.30	OK
18865	2026-09-23 12:59	53.84	OK	18866	2026-09-23 13:00	51.59	OK
18867	2026-09-23 13:01	51.94	OK	18868	2026-09-23 13:02	53.45	OK
18869	2026-09-23 13:03	51.77	OK	18870	2026-09-23 13:04	52.45	OK
18871	2026-09-23 13:05	50.65	OK	18872	2026-09-23 13:06	54.13	OK
18873	2026-09-23 13:07	51.98	OK	18874	2026-09-23 13:08	52.75	OK
1887	2026-09-23 13:09	51.51	OK	1887	2026-09-23 13:10	51.78	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
18877	2026-09-23 13:11	50.65	OK	18878	2026-09-23 13:12	51.20	OK
18879	2026-09-23 13:13	51.12	OK	18880	2026-09-23 13:14	52.85	OK
18881	2026-09-23 13:15	51.42	OK	18882	2026-09-23 13:16	51.88	OK
18883	2026-09-23 13:17	51.10	OK	18884	2026-09-23 13:18	52.17	OK
18885	2026-09-23 13:19	53.22	OK	18886	2026-09-23 13:20	52.87	OK
18887	2026-09-23 13:21	51.78	OK	18888	2026-09-23 13:22	51.00	OK
18889	2026-09-23 13:23	52.67	OK	18890	2026-09-23 13:24	50.04	OK
18891	2026-09-23 13:25	52.11	OK	18892	2026-09-23 13:26	52.67	OK
18893	2026-09-23 13:27	53.85	OK	18894	2026-09-23 13:28	50.51	OK
18895	2026-09-23 13:29	50.77	OK	18896	2026-09-23 13:30	53.94	OK
18897	2026-09-23 13:31	51.93	OK	18898	2026-09-23 13:32	52.58	OK
18899	2026-09-23 13:33	52.77	OK	18900	2026-09-23 13:34	50.28	OK
18901	2026-09-23 13:35	50.86	OK	18902	2026-09-23 13:36	52.26	OK
18903	2026-09-23 13:37	52.18	OK	18904	2026-09-23 13:38	51.30	OK
18905	2026-09-23 13:39	53.97	OK	18906	2026-09-23 13:40	53.21	OK
18907	2026-09-23 13:41	52.07	OK	18908	2026-09-23 13:42	49.86	OK
18909	2026-09-23 13:43	51.96	OK	18910	2026-09-23 13:44	53.74	OK
18911	2026-09-23 13:45	51.69	OK	18912	2026-09-23 13:46	51.72	OK
18913	2026-09-23 13:47	51.03	OK	18914	2026-09-23 13:48	53.55	OK
18915	2026-09-23 13:49	49.89	OK	18916	2026-09-23 13:50	51.08	OK
18917	2026-09-23 13:51	51.51	OK	18918	2026-09-23 13:52	50.58	OK
18919	2026-09-23 13:53	52.11	OK	18920	2026-09-23 13:54	50.05	OK
18921	2026-09-23 13:55	52.56	OK	18922	2026-09-23 13:56	52.37	OK
18923	2026-09-23 13:57	52.52	OK	18924	2026-09-23 13:58	51.39	OK
18925	2026-09-23 13:59	51.21	OK	18926	2026-09-23 14:00	52.02	OK
18927	2026-09-23 14:01	52.52	OK	18928	2026-09-23 14:02	50.93	OK
18929	2026-09-23 14:03	51.26	OK	18930	2026-09-23 14:04	50.64	OK
18931	2026-09-23 14:05	52.12	OK	18932	2026-09-23 14:06	53.47	OK
18933	2026-09-23 14:07	52.36	OK	18934	2026-09-23 14:08	49.92	OK
1893	2026-09-23 14:09	52.63	OK	1893	2026-09-23 14:10	51.45	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
18937	2026-09-23 14:11	51.01	OK	18938	2026-09-23 14:12	51.08	OK
18939	2026-09-23 14:13	52.32	OK	18940	2026-09-23 14:14	51.23	OK
18941	2026-09-23 14:15	50.65	OK	18942	2026-09-23 14:16	52.34	OK
18943	2026-09-23 14:17	51.15	OK	18944	2026-09-23 14:18	52.92	OK
18945	2026-09-23 14:19	50.35	OK	18946	2026-09-23 14:20	52.05	OK
18947	2026-09-23 14:21	53.69	OK	18948	2026-09-23 14:22	51.46	OK
18949	2026-09-23 14:23	51.98	OK	18950	2026-09-23 14:24	52.12	OK
18951	2026-09-23 14:25	52.84	OK	18952	2026-09-23 14:26	50.86	OK
18953	2026-09-23 14:27	51.62	OK	18954	2026-09-23 14:28	50.77	OK
18955	2026-09-23 14:29	50.54	OK	18956	2026-09-23 14:30	51.76	OK
18957	2026-09-23 14:31	50.61	OK	18958	2026-09-23 14:32	51.98	OK
18959	2026-09-23 14:33	53.20	OK	18960	2026-09-23 14:34	52.52	OK
18961	2026-09-23 14:35	50.34	OK	18962	2026-09-23 14:36	50.53	OK
18963	2026-09-23 14:37	53.40	OK	18964	2026-09-23 14:38	52.03	OK
18965	2026-09-23 14:39	51.70	OK	18966	2026-09-23 14:40	49.93	OK
18967	2026-09-23 14:41	51.08	OK	18968	2026-09-23 14:42	52.30	OK
18969	2026-09-23 14:43	51.88	OK	18970	2026-09-23 14:44	52.99	OK
18971	2026-09-23 14:45	53.60	OK	18972	2026-09-23 14:46	53.44	OK
18973	2026-09-23 14:47	50.67	OK	18974	2026-09-23 14:48	51.60	OK
18975	2026-09-23 14:49	52.01	OK	18976	2026-09-23 14:50	51.54	OK
18977	2026-09-23 14:51	50.68	OK	18978	2026-09-23 14:52	49.57	OK
18979	2026-09-23 14:53	51.60	OK	18980	2026-09-23 14:54	51.62	OK
18981	2026-09-23 14:55	53.73	OK	18982	2026-09-23 14:56	50.48	OK
18983	2026-09-23 14:57	49.55	OK	18984	2026-09-23 14:58	51.73	OK
18985	2026-09-23 14:59	51.57	OK	18986	2026-09-23 15:00	52.16	OK
18987	2026-09-23 15:01	49.98	OK	18988	2026-09-23 15:02	52.34	OK
18989	2026-09-23 15:03	51.25	OK	18990	2026-09-23 15:04	52.65	OK
18991	2026-09-23 15:05	51.58	OK	18992	2026-09-23 15:06	52.20	OK
18993	2026-09-23 15:07	49.94	OK	18994	2026-09-23 15:08	51.71	OK
1899	2026-09-23 15:09	50.70	OK	1899	2026-09-23 15:10	50.10	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
18997	2026-09-23 15:11	52.69	OK	18998	2026-09-23 15:12	51.84	OK
18999	2026-09-23 15:13	52.16	OK	19000	2026-09-23 15:14	51.89	OK
19001	2026-09-23 15:15	49.46	OK	19002	2026-09-23 15:16	52.51	OK
19003	2026-09-23 15:17	50.12	OK	19004	2026-09-23 15:18	51.83	OK
19005	2026-09-23 15:19	50.59	OK	19006	2026-09-23 15:20	51.42	OK
19007	2026-09-23 15:21	50.07	OK	19008	2026-09-23 15:22	51.07	OK
19009	2026-09-23 15:23	49.57	OK	19010	2026-09-23 15:24	50.44	OK
19011	2026-09-23 15:25	50.31	OK	19012	2026-09-23 15:26	51.22	OK
19013	2026-09-23 15:27	50.36	OK	19014	2026-09-23 15:28	51.30	OK
19015	2026-09-23 15:29	52.41	OK	19016	2026-09-23 15:30	51.61	OK
19017	2026-09-23 15:31	48.94	OK	19018	2026-09-23 15:32	52.69	OK
19019	2026-09-23 15:33	51.87	OK	19020	2026-09-23 15:34	50.39	OK
19021	2026-09-23 15:35	51.55	OK	19022	2026-09-23 15:36	49.54	OK
19023	2026-09-23 15:37	50.48	OK	19024	2026-09-23 15:38	50.56	OK
19025	2026-09-23 15:39	51.40	OK	19026	2026-09-23 15:40	51.44	OK
19027	2026-09-23 15:41	49.78	OK	19028	2026-09-23 15:42	53.45	OK
19029	2026-09-23 15:43	52.62	OK	19030	2026-09-23 15:44	51.53	OK
19031	2026-09-23 15:45	49.25	OK	19032	2026-09-23 15:46	51.72	OK
19033	2026-09-23 15:47	52.22	OK	19034	2026-09-23 15:48	50.60	OK
19035	2026-09-23 15:49	52.54	OK	19036	2026-09-23 15:50	52.49	OK
19037	2026-09-23 15:51	52.48	OK	19038	2026-09-23 15:52	53.50	OK
19039	2026-09-23 15:53	51.69	OK	19040	2026-09-23 15:54	51.90	OK
19041	2026-09-23 15:55	50.28	OK	19042	2026-09-23 15:56	49.76	OK
19043	2026-09-23 15:57	50.71	OK	19044	2026-09-23 15:58	52.97	OK
19045	2026-09-23 15:59	50.32	OK	19046	2026-09-23 16:00	51.16	OK
19047	2026-09-23 16:01	50.16	OK	19048	2026-09-23 16:02	50.64	OK
19049	2026-09-23 16:03	50.04	OK	19050	2026-09-23 16:04	51.42	OK
19051	2026-09-23 16:05	49.62	OK	19052	2026-09-23 16:06	51.35	OK
19053	2026-09-23 16:07	49.04	OK	19054	2026-09-23 16:08	49.76	OK
1905	2026-09-23 16:09	49.91	OK	1905	2026-09-23 16:10	51.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
19057	2026-09-23 16:11	51.39	OK	19058	2026-09-23 16:12	51.17	OK
19059	2026-09-23 16:13	50.71	OK	19060	2026-09-23 16:14	49.50	OK
19061	2026-09-23 16:15	50.91	OK	19062	2026-09-23 16:16	50.19	OK
19063	2026-09-23 16:17	49.62	OK	19064	2026-09-23 16:18	51.76	OK
19065	2026-09-23 16:19	50.27	OK	19066	2026-09-23 16:20	50.58	OK
19067	2026-09-23 16:21	50.54	OK	19068	2026-09-23 16:22	50.50	OK
19069	2026-09-23 16:23	52.26	OK	19070	2026-09-23 16:24	51.28	OK
19071	2026-09-23 16:25	50.30	OK	19072	2026-09-23 16:26	49.28	OK
19073	2026-09-23 16:27	52.04	OK	19074	2026-09-23 16:28	50.20	OK
19075	2026-09-23 16:29	50.21	OK	19076	2026-09-23 16:30	51.64	OK
19077	2026-09-23 16:31	49.93	OK	19078	2026-09-23 16:32	50.01	OK
19079	2026-09-23 16:33	50.21	OK	19080	2026-09-23 16:34	49.48	OK
19081	2026-09-23 16:35	50.54	OK	19082	2026-09-23 16:36	50.58	OK
19083	2026-09-23 16:37	50.66	OK	19084	2026-09-23 16:38	50.21	OK
19085	2026-09-23 16:39	49.78	OK	19086	2026-09-23 16:40	49.46	OK
19087	2026-09-23 16:41	51.39	OK	19088	2026-09-23 16:42	51.16	OK
19089	2026-09-23 16:43	50.33	OK	19090	2026-09-23 16:44	49.74	OK
19091	2026-09-23 16:45	51.55	OK	19092	2026-09-23 16:46	49.37	OK
19093	2026-09-23 16:47	51.16	OK	19094	2026-09-23 16:48	51.31	OK
19095	2026-09-23 16:49	52.19	OK	19096	2026-09-23 16:50	51.67	OK
19097	2026-09-23 16:51	50.47	OK	19098	2026-09-23 16:52	52.11	OK
19099	2026-09-23 16:53	48.42	OK	19100	2026-09-23 16:54	50.08	OK
19101	2026-09-23 16:55	51.47	OK	19102	2026-09-23 16:56	48.27	OK
19103	2026-09-23 16:57	51.26	OK	19104	2026-09-23 16:58	49.69	OK
19105	2026-09-23 16:59	50.93	OK	19106	2026-09-23 17:00	51.92	OK
19107	2026-09-23 17:01	52.91	OK	19108	2026-09-23 17:02	51.83	OK
19109	2026-09-23 17:03	49.81	OK	19110	2026-09-23 17:04	50.47	OK
19111	2026-09-23 17:05	50.34	OK	19112	2026-09-23 17:06	49.20	OK
19113	2026-09-23 17:07	49.79	OK	19114	2026-09-23 17:08	51.74	OK
19115	2026-09-23 17:09	51.61	OK	19115	2026-09-23 17:10	50.75	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
19117	2026-09-23 17:11	50.51	OK	19118	2026-09-23 17:12	51.22	OK
19119	2026-09-23 17:13	49.95	OK	19120	2026-09-23 17:14	51.79	OK
19121	2026-09-23 17:15	50.22	OK	19122	2026-09-23 17:16	50.59	OK
19123	2026-09-23 17:17	51.90	OK	19124	2026-09-23 17:18	49.75	OK
19125	2026-09-23 17:19	49.51	OK	19126	2026-09-23 17:20	50.25	OK
19127	2026-09-23 17:21	47.62	OK	19128	2026-09-23 17:22	49.58	OK
19129	2026-09-23 17:23	50.72	OK	19130	2026-09-23 17:24	50.41	OK
19131	2026-09-23 17:25	49.19	OK	19132	2026-09-23 17:26	50.70	OK
19133	2026-09-23 17:27	49.89	OK	19134	2026-09-23 17:28	49.41	OK
19135	2026-09-23 17:29	51.71	OK	19136	2026-09-23 17:30	48.74	OK
19137	2026-09-23 17:31	50.43	OK	19138	2026-09-23 17:32	49.58	OK
19139	2026-09-23 17:33	49.74	OK	19140	2026-09-23 17:34	51.41	OK
19141	2026-09-23 17:35	51.47	OK	19142	2026-09-23 17:36	50.18	OK
19143	2026-09-23 17:37	49.09	OK	19144	2026-09-23 17:38	48.33	OK
19145	2026-09-23 17:39	48.37	OK	19146	2026-09-23 17:40	49.80	OK
19147	2026-09-23 17:41	51.08	OK	19148	2026-09-23 17:42	49.80	OK
19149	2026-09-23 17:43	48.54	OK	19150	2026-09-23 17:44	49.88	OK
19151	2026-09-23 17:45	48.56	OK	19152	2026-09-23 17:46	51.18	OK
19153	2026-09-23 17:47	49.95	OK	19154	2026-09-23 17:48	49.93	OK
19155	2026-09-23 17:49	50.29	OK	19156	2026-09-23 17:50	49.64	OK
19157	2026-09-23 17:51	49.25	OK	19158	2026-09-23 17:52	48.28	OK
19159	2026-09-23 17:53	52.01	OK	19160	2026-09-23 17:54	51.02	OK
19161	2026-09-23 17:55	48.84	OK	19162	2026-09-23 17:56	48.97	OK
19163	2026-09-23 17:57	50.25	OK	19164	2026-09-23 17:58	48.95	OK
19165	2026-09-23 17:59	51.09	OK	19166	2026-09-23 18:00	50.54	OK
19167	2026-09-23 18:01	48.78	OK	19168	2026-09-23 18:02	49.00	OK
19169	2026-09-23 18:03	49.99	OK	19170	2026-09-23 18:04	52.39	OK
19171	2026-09-23 18:05	48.94	OK	19172	2026-09-23 18:06	49.83	OK
19173	2026-09-23 18:07	49.11	OK	19174	2026-09-23 18:08	49.49	OK
1917	2026-09-23 18:09	48.58	OK	1917	2026-09-23 18:10	50.98	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
19177	2026-09-23 18:11	49.90	OK	19178	2026-09-23 18:12	50.28	OK
19179	2026-09-23 18:13	48.03	OK	19180	2026-09-23 18:14	50.35	OK
19181	2026-09-23 18:15	51.32	OK	19182	2026-09-23 18:16	49.85	OK
19183	2026-09-23 18:17	51.14	OK	19184	2026-09-23 18:18	48.12	OK
19185	2026-09-23 18:19	48.85	OK	19186	2026-09-23 18:20	51.20	OK
19187	2026-09-23 18:21	51.99	OK	19188	2026-09-23 18:22	50.35	OK
19189	2026-09-23 18:23	49.16	OK	19190	2026-09-23 18:24	50.64	OK
19191	2026-09-23 18:25	48.19	OK	19192	2026-09-23 18:26	49.78	OK
19193	2026-09-23 18:27	49.97	OK	19194	2026-09-23 18:28	48.14	OK
19195	2026-09-23 18:29	48.95	OK	19196	2026-09-23 18:30	49.04	OK
19197	2026-09-23 18:31	48.90	OK	19198	2026-09-23 18:32	50.09	OK
19199	2026-09-23 18:33	49.21	OK	19200	2026-09-23 18:34	49.94	OK
19201	2026-09-23 18:35	49.71	OK	19202	2026-09-23 18:36	49.58	OK
19203	2026-09-23 18:37	50.22	OK	19204	2026-09-23 18:38	50.24	OK
19205	2026-09-23 18:39	50.23	OK	19206	2026-09-23 18:40	50.00	OK
19207	2026-09-23 18:41	49.50	OK	19208	2026-09-23 18:42	48.94	OK
19209	2026-09-23 18:43	49.16	OK	19210	2026-09-23 18:44	47.65	OK
19211	2026-09-23 18:45	50.58	OK	19212	2026-09-23 18:46	50.47	OK
19213	2026-09-23 18:47	48.32	OK	19214	2026-09-23 18:48	49.19	OK
19215	2026-09-23 18:49	50.25	OK	19216	2026-09-23 18:50	47.30	OK
19217	2026-09-23 18:51	48.69	OK	19218	2026-09-23 18:52	48.81	OK
19219	2026-09-23 18:53	48.78	OK	19220	2026-09-23 18:54	49.17	OK
19221	2026-09-23 18:55	48.94	OK	19222	2026-09-23 18:56	49.37	OK
19223	2026-09-23 18:57	48.38	OK	19224	2026-09-23 18:58	49.48	OK
19225	2026-09-23 18:59	47.19	OK	19226	2026-09-23 19:00	48.05	OK
19227	2026-09-23 19:01	48.62	OK	19228	2026-09-23 19:02	48.38	OK
19229	2026-09-23 19:03	49.13	OK	19230	2026-09-23 19:04	48.94	OK
19231	2026-09-23 19:05	48.04	OK	19232	2026-09-23 19:06	47.69	OK
19233	2026-09-23 19:07	50.14	OK	19234	2026-09-23 19:08	49.35	OK
1923	2026-09-23 19:09	46.80	OK	1923	2026-09-23 19:10	49.73	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
19237	2026-09-23 19:11	49.26	OK	19238	2026-09-23 19:12	47.96	OK
19239	2026-09-23 19:13	48.76	OK	19240	2026-09-23 19:14	48.66	OK
19241	2026-09-23 19:15	46.18	OK	19242	2026-09-23 19:16	49.84	OK
19243	2026-09-23 19:17	47.56	OK	19244	2026-09-23 19:18	49.16	OK
19245	2026-09-23 19:19	49.94	OK	19246	2026-09-23 19:20	47.16	OK
19247	2026-09-23 19:21	49.14	OK	19248	2026-09-23 19:22	48.52	OK
19249	2026-09-23 19:23	50.03	OK	19250	2026-09-23 19:24	46.98	OK
19251	2026-09-23 19:25	49.11	OK	19252	2026-09-23 19:26	49.00	OK
19253	2026-09-23 19:27	49.44	OK	19254	2026-09-23 19:28	47.50	OK
19255	2026-09-23 19:29	49.16	OK	19256	2026-09-23 19:30	47.33	OK
19257	2026-09-23 19:31	47.97	OK	19258	2026-09-23 19:32	47.09	OK
19259	2026-09-23 19:33	49.75	OK	19260	2026-09-23 19:34	49.07	OK
19261	2026-09-23 19:35	48.95	OK	19262	2026-09-23 19:36	47.39	OK
19263	2026-09-23 19:37	47.55	OK	19264	2026-09-23 19:38	47.24	OK
19265	2026-09-23 19:39	46.19	OK	19266	2026-09-23 19:40	49.93	OK
19267	2026-09-23 19:41	49.33	OK	19268	2026-09-23 19:42	47.30	OK
19269	2026-09-23 19:43	49.90	OK	19270	2026-09-23 19:44	47.74	OK
19271	2026-09-23 19:45	47.68	OK	19272	2026-09-23 19:46	46.84	OK
19273	2026-09-23 19:47	48.58	OK	19274	2026-09-23 19:48	50.04	OK
19275	2026-09-23 19:49	47.22	OK	19276	2026-09-23 19:50	48.23	OK
19277	2026-09-23 19:51	45.55	OK	19278	2026-09-23 19:52	46.91	OK
19279	2026-09-23 19:53	48.40	OK	19280	2026-09-23 19:54	48.67	OK
19281	2026-09-23 19:55	46.61	OK	19282	2026-09-23 19:56	48.62	OK
19283	2026-09-23 19:57	48.33	OK	19284	2026-09-23 19:58	48.72	OK
19285	2026-09-23 19:59	49.21	OK	19286	2026-09-23 20:00	47.97	OK
19287	2026-09-23 20:01	49.26	OK	19288	2026-09-23 20:02	47.87	OK
19289	2026-09-23 20:03	46.55	OK	19290	2026-09-23 20:04	45.35	OK
19291	2026-09-23 20:05	47.06	OK	19292	2026-09-23 20:06	46.89	OK
19293	2026-09-23 20:07	46.91	OK	19294	2026-09-23 20:08	49.14	OK
1929	2026-09-23 20:09	47.57	OK	1929	2026-09-23 20:10	47.66	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
19297	2026-09-23 20:11	48.26	OK	19298	2026-09-23 20:12	47.15	OK
19299	2026-09-23 20:13	46.10	OK	19300	2026-09-23 20:14	47.48	OK
19301	2026-09-23 20:15	47.59	OK	19302	2026-09-23 20:16	48.34	OK
19303	2026-09-23 20:17	46.21	OK	19304	2026-09-23 20:18	48.21	OK
19305	2026-09-23 20:19	47.82	OK	19306	2026-09-23 20:20	46.79	OK
19307	2026-09-23 20:21	49.12	OK	19308	2026-09-23 20:22	47.26	OK
19309	2026-09-23 20:23	48.85	OK	19310	2026-09-23 20:24	49.69	OK
19311	2026-09-23 20:25	49.14	OK	19312	2026-09-23 20:26	47.94	OK
19313	2026-09-23 20:27	48.14	OK	19314	2026-09-23 20:28	47.64	OK
19315	2026-09-23 20:29	48.92	OK	19316	2026-09-23 20:30	48.57	OK
19317	2026-09-23 20:31	50.23	OK	19318	2026-09-23 20:32	47.40	OK
19319	2026-09-23 20:33	47.15	OK	19320	2026-09-23 20:34	49.18	OK
19321	2026-09-23 20:35	47.68	OK	19322	2026-09-23 20:36	46.39	OK
19323	2026-09-23 20:37	47.81	OK	19324	2026-09-23 20:38	46.63	OK
19325	2026-09-23 20:39	47.39	OK	19326	2026-09-23 20:40	46.97	OK
19327	2026-09-23 20:41	45.73	OK	19328	2026-09-23 20:42	47.69	OK
19329	2026-09-23 20:43	46.70	OK	19330	2026-09-23 20:44	47.80	OK
19331	2026-09-23 20:45	46.38	OK	19332	2026-09-23 20:46	48.93	OK
19333	2026-09-23 20:47	46.56	OK	19334	2026-09-23 20:48	46.55	OK
19335	2026-09-23 20:49	47.34	OK	19336	2026-09-23 20:50	46.90	OK
19337	2026-09-23 20:51	48.85	OK	19338	2026-09-23 20:52	47.78	OK
19339	2026-09-23 20:53	48.02	OK	19340	2026-09-23 20:54	45.94	OK
19341	2026-09-23 20:55	48.54	OK	19342	2026-09-23 20:56	46.51	OK
19343	2026-09-23 20:57	48.35	OK	19344	2026-09-23 20:58	47.33	OK
19345	2026-09-23 20:59	48.51	OK	19346	2026-09-23 21:00	46.94	OK
19347	2026-09-23 21:01	46.91	OK	19348	2026-09-23 21:02	48.31	OK
19349	2026-09-23 21:03	46.53	OK	19350	2026-09-23 21:04	46.94	OK
19351	2026-09-23 21:05	47.82	OK	19352	2026-09-23 21:06	47.15	OK
19353	2026-09-23 21:07	47.14	OK	19354	2026-09-23 21:08	46.18	OK
1935	2026-09-23 21:09	47.67	OK	1935	2026-09-23 21:10	45.39	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
19357	2026-09-23 21:11	48.02	OK	19358	2026-09-23 21:12	46.28	OK
19359	2026-09-23 21:13	45.93	OK	19360	2026-09-23 21:14	46.86	OK
19361	2026-09-23 21:15	47.66	OK	19362	2026-09-23 21:16	45.69	OK
19363	2026-09-23 21:17	45.64	OK	19364	2026-09-23 21:18	46.83	OK
19365	2026-09-23 21:19	48.77	OK	19366	2026-09-23 21:20	47.07	OK
19367	2026-09-23 21:21	47.52	OK	19368	2026-09-23 21:22	46.27	OK
19369	2026-09-23 21:23	47.94	OK	19370	2026-09-23 21:24	48.71	OK
19371	2026-09-23 21:25	47.17	OK	19372	2026-09-23 21:26	47.81	OK
19373	2026-09-23 21:27	46.54	OK	19374	2026-09-23 21:28	45.64	OK
19375	2026-09-23 21:29	45.99	OK	19376	2026-09-23 21:30	46.83	OK
19377	2026-09-23 21:31	46.59	OK	19378	2026-09-23 21:32	45.42	OK
19379	2026-09-23 21:33	45.10	OK	19380	2026-09-23 21:34	46.70	OK
19381	2026-09-23 21:35	45.51	OK	19382	2026-09-23 21:36	45.73	OK
19383	2026-09-23 21:37	47.79	OK	19384	2026-09-23 21:38	46.18	OK
19385	2026-09-23 21:39	45.72	OK	19386	2026-09-23 21:40	44.16	OK
19387	2026-09-23 21:41	45.49	OK	19388	2026-09-23 21:42	47.24	OK
19389	2026-09-23 21:43	46.26	OK	19390	2026-09-23 21:44	47.21	OK
19391	2026-09-23 21:45	47.72	OK	19392	2026-09-23 21:46	48.05	OK
19393	2026-09-23 21:47	46.38	OK	19394	2026-09-23 21:48	46.53	OK
19395	2026-09-23 21:49	47.10	OK	19396	2026-09-23 21:50	46.85	OK
19397	2026-09-23 21:51	46.82	OK	19398	2026-09-23 21:52	45.83	OK
19399	2026-09-23 21:53	45.70	OK	19400	2026-09-23 21:54	46.66	OK
19401	2026-09-23 21:55	48.06	OK	19402	2026-09-23 21:56	44.95	OK
19403	2026-09-23 21:57	45.95	OK	19404	2026-09-23 21:58	46.15	OK
19405	2026-09-23 21:59	45.02	OK	19406	2026-09-23 22:00	47.36	OK
19407	2026-09-23 22:01	46.18	OK	19408	2026-09-23 22:02	45.02	OK
19409	2026-09-23 22:03	46.22	OK	19410	2026-09-23 22:04	46.35	OK
19411	2026-09-23 22:05	46.25	OK	19412	2026-09-23 22:06	45.78	OK
19413	2026-09-23 22:07	46.41	OK	19414	2026-09-23 22:08	45.51	OK
1941	2026-09-23 22:09	46.34	OK	1941	2026-09-23 22:10	46.01	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
19417	2026-09-23 22:11	46.17	OK	19418	2026-09-23 22:12	46.15	OK
19419	2026-09-23 22:13	46.85	OK	19420	2026-09-23 22:14	45.65	OK
19421	2026-09-23 22:15	47.68	OK	19422	2026-09-23 22:16	45.58	OK
19423	2026-09-23 22:17	47.35	OK	19424	2026-09-23 22:18	46.33	OK
19425	2026-09-23 22:19	47.35	OK	19426	2026-09-23 22:20	47.07	OK
19427	2026-09-23 22:21	46.11	OK	19428	2026-09-23 22:22	46.93	OK
19429	2026-09-23 22:23	46.00	OK	19430	2026-09-23 22:24	45.26	OK
19431	2026-09-23 22:25	46.06	OK	19432	2026-09-23 22:26	45.03	OK
19433	2026-09-23 22:27	44.36	OK	19434	2026-09-23 22:28	47.26	OK
19435	2026-09-23 22:29	45.71	OK	19436	2026-09-23 22:30	46.07	OK
19437	2026-09-23 22:31	46.97	OK	19438	2026-09-23 22:32	44.85	OK
19439	2026-09-23 22:33	46.55	OK	19440	2026-09-23 22:34	46.09	OK
19441	2026-09-23 22:35	44.74	OK	19442	2026-09-23 22:36	47.47	OK
19443	2026-09-23 22:37	47.12	OK	19444	2026-09-23 22:38	46.25	OK
19445	2026-09-23 22:39	45.35	OK	19446	2026-09-23 22:40	46.07	OK
19447	2026-09-23 22:41	43.82	OK	19448	2026-09-23 22:42	44.57	OK
19449	2026-09-23 22:43	44.67	OK	19450	2026-09-23 22:44	46.43	OK
19451	2026-09-23 22:45	46.79	OK	19452	2026-09-23 22:46	45.33	OK
19453	2026-09-23 22:47	46.49	OK	19454	2026-09-23 22:48	46.04	OK
19455	2026-09-23 22:49	46.87	OK	19456	2026-09-23 22:50	45.78	OK
19457	2026-09-23 22:51	46.31	OK	19458	2026-09-23 22:52	46.33	OK
19459	2026-09-23 22:53	44.96	OK	19460	2026-09-23 22:54	44.57	OK
19461	2026-09-23 22:55	46.22	OK	19462	2026-09-23 22:56	44.98	OK
19463	2026-09-23 22:57	46.68	OK	19464	2026-09-23 22:58	45.03	OK
19465	2026-09-23 22:59	45.74	OK	19466	2026-09-23 23:00	45.00	OK
19467	2026-09-23 23:01	44.30	OK	19468	2026-09-23 23:02	45.75	OK
19469	2026-09-23 23:03	45.28	OK	19470	2026-09-23 23:04	46.87	OK
19471	2026-09-23 23:05	45.28	OK	19472	2026-09-23 23:06	46.41	OK
19473	2026-09-23 23:07	46.70	OK	19474	2026-09-23 23:08	45.80	OK
1947	2026-09-23 23:09	44.09	OK	1947	2026-09-23 23:10	46.56	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
19477	2026-09-23 23:11	46.59	OK	19478	2026-09-23 23:12	45.54	OK
19479	2026-09-23 23:13	46.99	OK	19480	2026-09-23 23:14	46.19	OK
19481	2026-09-23 23:15	44.68	OK	19482	2026-09-23 23:16	46.80	OK
19483	2026-09-23 23:17	46.89	OK	19484	2026-09-23 23:18	46.85	OK
19485	2026-09-23 23:19	46.27	OK	19486	2026-09-23 23:20	45.02	OK
19487	2026-09-23 23:21	44.68	OK	19488	2026-09-23 23:22	44.91	OK
19489	2026-09-23 23:23	44.95	OK	19490	2026-09-23 23:24	46.97	OK
19491	2026-09-23 23:25	44.36	OK	19492	2026-09-23 23:26	46.90	OK
19493	2026-09-23 23:27	45.64	OK	19494	2026-09-23 23:28	45.99	OK
19495	2026-09-23 23:29	45.53	OK	19496	2026-09-23 23:30	46.47	OK
19497	2026-09-23 23:31	46.46	OK	19498	2026-09-23 23:32	46.23	OK
19499	2026-09-23 23:33	44.65	OK	19500	2026-09-23 23:34	44.34	OK
19501	2026-09-23 23:35	46.38	OK	19502	2026-09-23 23:36	45.17	OK
19503	2026-09-23 23:37	45.39	OK	19504	2026-09-23 23:38	45.26	OK
19505	2026-09-23 23:39	45.38	OK	19506	2026-09-23 23:40	45.48	OK
19507	2026-09-23 23:41	46.15	OK	19508	2026-09-23 23:42	46.03	OK
19509	2026-09-23 23:43	44.75	OK	19510	2026-09-23 23:44	45.02	OK
19511	2026-09-23 23:45	44.65	OK	19512	2026-09-23 23:46	45.29	OK
19513	2026-09-23 23:47	45.80	OK	19514	2026-09-23 23:48	45.12	OK
19515	2026-09-23 23:49	43.99	OK	19516	2026-09-23 23:50	45.94	OK
19517	2026-09-23 23:51	45.02	OK	19518	2026-09-23 23:52	44.91	OK
19519	2026-09-23 23:53	46.70	OK	19520	2026-09-23 23:54	45.59	OK
19521	2026-09-23 23:55	44.74	OK	19522	2026-09-23 23:56	45.25	OK
19523	2026-09-23 23:57	45.61	OK	19524	2026-09-23 23:58	43.65	OK
19525	2026-09-23 23:59	45.63	OK	19526	2026-09-24 00:00	46.50	OK
19527	2026-09-24 00:01	46.43	OK	19528	2026-09-24 00:02	46.92	OK
19529	2026-09-24 00:03	47.00	OK	19530	2026-09-24 00:04	46.51	OK
19531	2026-09-24 00:05	43.33	OK	19532	2026-09-24 00:06	46.01	OK
19533	2026-09-24 00:07	44.65	OK	19534	2026-09-24 00:08	43.62	OK
1953	2026-09-24 00:09	47.19	OK	1953	2026-09-24 00:10	44.02	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
19537	2026-09-24 00:11	45.19	OK	19538	2026-09-24 00:12	43.96	OK
19539	2026-09-24 00:13	45.60	OK	19540	2026-09-24 00:14	44.16	OK
19541	2026-09-24 00:15	44.60	OK	19542	2026-09-24 00:16	44.85	OK
19543	2026-09-24 00:17	45.91	OK	19544	2026-09-24 00:18	45.52	OK
19545	2026-09-24 00:19	45.10	OK	19546	2026-09-24 00:20	44.64	OK
19547	2026-09-24 00:21	45.38	OK	19548	2026-09-24 00:22	44.77	OK
19549	2026-09-24 00:23	44.50	OK	19550	2026-09-24 00:24	45.00	OK
19551	2026-09-24 00:25	43.88	OK	19552	2026-09-24 00:26	43.79	OK
19553	2026-09-24 00:27	46.54	OK	19554	2026-09-24 00:28	45.48	OK
19555	2026-09-24 00:29	46.72	OK	19556	2026-09-24 00:30	44.19	OK
19557	2026-09-24 00:31	45.10	OK	19558	2026-09-24 00:32	46.23	OK
19559	2026-09-24 00:33	45.67	OK	19560	2026-09-24 00:34	45.08	OK
19561	2026-09-24 00:35	44.63	OK	19562	2026-09-24 00:36	44.69	OK
19563	2026-09-24 00:37	44.93	OK	19564	2026-09-24 00:38	44.83	OK
19565	2026-09-24 00:39	46.24	OK	19566	2026-09-24 00:40	45.59	OK
19567	2026-09-24 00:41	45.48	OK	19568	2026-09-24 00:42	45.03	OK
19569	2026-09-24 00:43	45.13	OK	19570	2026-09-24 00:44	45.70	OK
19571	2026-09-24 00:45	45.96	OK	19572	2026-09-24 00:46	45.91	OK
19573	2026-09-24 00:47	45.39	OK	19574	2026-09-24 00:48	44.83	OK
19575	2026-09-24 00:49	45.63	OK	19576	2026-09-24 00:50	45.52	OK
19577	2026-09-24 00:51	45.48	OK	19578	2026-09-24 00:52	44.98	OK
19579	2026-09-24 00:53	45.99	OK	19580	2026-09-24 00:54	42.88	OK
19581	2026-09-24 00:55	46.05	OK	19582	2026-09-24 00:56	45.03	OK
19583	2026-09-24 00:57	45.18	OK	19584	2026-09-24 00:58	45.63	OK
19585	2026-09-24 00:59	45.65	OK	19586	2026-09-24 01:00	46.11	OK
19587	2026-09-24 01:01	43.78	OK	19588	2026-09-24 01:02	46.54	OK
19589	2026-09-24 01:03	44.55	OK	19590	2026-09-24 01:04	44.55	OK
19591	2026-09-24 01:05	47.01	OK	19592	2026-09-24 01:06	46.58	OK
19593	2026-09-24 01:07	44.74	OK	19594	2026-09-24 01:08	44.91	OK
1959	2026-09-24 01:09	45.96	OK	1959	2026-09-24 01:10	43.62	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
19597	2026-09-24 01:11	45.89	OK	19598	2026-09-24 01:12	43.82	OK
19599	2026-09-24 01:13	46.10	OK	19600	2026-09-24 01:14	45.79	OK
19601	2026-09-24 01:15	44.92	OK	19602	2026-09-24 01:16	44.76	OK
19603	2026-09-24 01:17	43.98	OK	19604	2026-09-24 01:18	44.34	OK
19605	2026-09-24 01:19	45.45	OK	19606	2026-09-24 01:20	44.16	OK
19607	2026-09-24 01:21	45.88	OK	19608	2026-09-24 01:22	44.42	OK
19609	2026-09-24 01:23	44.23	OK	19610	2026-09-24 01:24	44.48	OK
19611	2026-09-24 01:25	46.39	OK	19612	2026-09-24 01:26	44.55	OK
19613	2026-09-24 01:27	44.70	OK	19614	2026-09-24 01:28	43.55	OK
19615	2026-09-24 01:29	45.73	OK	19616	2026-09-24 01:30	46.37	OK
19617	2026-09-24 01:31	46.09	OK	19618	2026-09-24 01:32	44.68	OK
19619	2026-09-24 01:33	45.64	OK	19620	2026-09-24 01:34	45.77	OK
19621	2026-09-24 01:35	47.04	OK	19622	2026-09-24 01:36	44.27	OK
19623	2026-09-24 01:37	44.20	OK	19624	2026-09-24 01:38	46.65	OK
19625	2026-09-24 01:39	44.49	OK	19626	2026-09-24 01:40	45.34	OK
19627	2026-09-24 01:41	44.76	OK	19628	2026-09-24 01:42	46.90	OK
19629	2026-09-24 01:43	46.64	OK	19630	2026-09-24 01:44	44.86	OK
19631	2026-09-24 01:45	45.85	OK	19632	2026-09-24 01:46	43.25	OK
19633	2026-09-24 01:47	45.74	OK	19634	2026-09-24 01:48	45.11	OK
19635	2026-09-24 01:49	46.89	OK	19636	2026-09-24 01:50	43.48	OK
19637	2026-09-24 01:51	44.31	OK	19638	2026-09-24 01:52	46.07	OK
19639	2026-09-24 01:53	45.07	OK	19640	2026-09-24 01:54	45.23	OK
19641	2026-09-24 01:55	44.71	OK	19642	2026-09-24 01:56	44.42	OK
19643	2026-09-24 01:57	44.38	OK	19644	2026-09-24 01:58	44.81	OK
19645	2026-09-24 01:59	46.26	OK	19646	2026-09-24 02:00	44.81	OK
19647	2026-09-24 02:01	45.59	OK	19648	2026-09-24 02:02	45.92	OK
19649	2026-09-24 02:03	47.92	OK	19650	2026-09-24 02:04	43.21	OK
19651	2026-09-24 02:05	43.54	OK	19652	2026-09-24 02:06	44.96	OK
19653	2026-09-24 02:07	44.50	OK	19654	2026-09-24 02:08	45.39	OK
1965	2026-09-24 02:09	45.66	OK	1965	2026-09-24 02:10	44.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
19657	2026-09-24 02:11	45.05	OK	19658	2026-09-24 02:12	44.88	OK
19659	2026-09-24 02:13	45.77	OK	19660	2026-09-24 02:14	45.98	OK
19661	2026-09-24 02:15	44.05	OK	19662	2026-09-24 02:16	42.78	OK
19663	2026-09-24 02:17	46.82	OK	19664	2026-09-24 02:18	45.94	OK
19665	2026-09-24 02:19	44.80	OK	19666	2026-09-24 02:20	45.03	OK
19667	2026-09-24 02:21	45.00	OK	19668	2026-09-24 02:22	44.36	OK
19669	2026-09-24 02:23	46.40	OK	19670	2026-09-24 02:24	44.63	OK
19671	2026-09-24 02:25	45.14	OK	19672	2026-09-24 02:26	44.53	OK
19673	2026-09-24 02:27	44.79	OK	19674	2026-09-24 02:28	46.81	OK
19675	2026-09-24 02:29	45.63	OK	19676	2026-09-24 02:30	44.35	OK
19677	2026-09-24 02:31	46.67	OK	19678	2026-09-24 02:32	45.97	OK
19679	2026-09-24 02:33	47.15	OK	19680	2026-09-24 02:34	45.30	OK
19681	2026-09-24 02:35	44.48	OK	19682	2026-09-24 02:36	46.20	OK
19683	2026-09-24 02:37	44.66	OK	19684	2026-09-24 02:38	43.89	OK
19685	2026-09-24 02:39	45.15	OK	19686	2026-09-24 02:40	46.40	OK
19687	2026-09-24 02:41	45.67	OK	19688	2026-09-24 02:42	45.69	OK
19689	2026-09-24 02:43	45.10	OK	19690	2026-09-24 02:44	45.21	OK
19691	2026-09-24 02:45	46.91	OK	19692	2026-09-24 02:46	44.94	OK
19693	2026-09-24 02:47	45.86	OK	19694	2026-09-24 02:48	43.62	OK
19695	2026-09-24 02:49	45.48	OK	19696	2026-09-24 02:50	45.70	OK
19697	2026-09-24 02:51	47.59	OK	19698	2026-09-24 02:52	45.49	OK
19699	2026-09-24 02:53	45.38	OK	19700	2026-09-24 02:54	46.13	OK
19701	2026-09-24 02:55	46.03	OK	19702	2026-09-24 02:56	45.91	OK
19703	2026-09-24 02:57	44.99	OK	19704	2026-09-24 02:58	46.89	OK
19705	2026-09-24 02:59	46.34	OK	19706	2026-09-24 03:00	44.34	OK
19707	2026-09-24 03:01	45.94	OK	19708	2026-09-24 03:02	46.17	OK
19709	2026-09-24 03:03	45.72	OK	19710	2026-09-24 03:04	46.01	OK
19711	2026-09-24 03:05	46.75	OK	19712	2026-09-24 03:06	46.67	OK
19713	2026-09-24 03:07	46.27	OK	19714	2026-09-24 03:08	46.95	OK
1971	2026-09-24 03:09	45.68	OK	1971	2026-09-24 03:10	46.97	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
19717	2026-09-24 03:11	46.98	OK	19718	2026-09-24 03:12	45.99	OK
19719	2026-09-24 03:13	46.11	OK	19720	2026-09-24 03:14	45.76	OK
19721	2026-09-24 03:15	45.23	OK	19722	2026-09-24 03:16	45.72	OK
19723	2026-09-24 03:17	45.20	OK	19724	2026-09-24 03:18	46.49	OK
19725	2026-09-24 03:19	45.49	OK	19726	2026-09-24 03:20	46.26	OK
19727	2026-09-24 03:21	46.88	OK	19728	2026-09-24 03:22	46.24	OK
19729	2026-09-24 03:23	45.11	OK	19730	2026-09-24 03:24	46.71	OK
19731	2026-09-24 03:25	45.22	OK	19732	2026-09-24 03:26	47.15	OK
19733	2026-09-24 03:27	46.09	OK	19734	2026-09-24 03:28	44.06	OK
19735	2026-09-24 03:29	46.01	OK	19736	2026-09-24 03:30	45.28	OK
19737	2026-09-24 03:31	45.09	OK	19738	2026-09-24 03:32	47.28	OK
19739	2026-09-24 03:33	45.13	OK	19740	2026-09-24 03:34	45.07	OK
19741	2026-09-24 03:35	47.24	OK	19742	2026-09-24 03:36	45.00	OK
19743	2026-09-24 03:37	46.89	OK	19744	2026-09-24 03:38	46.56	OK
19745	2026-09-24 03:39	46.70	OK	19746	2026-09-24 03:40	45.87	OK
19747	2026-09-24 03:41	47.41	OK	19748	2026-09-24 03:42	46.57	OK
19749	2026-09-24 03:43	46.73	OK	19750	2026-09-24 03:44	45.17	OK
19751	2026-09-24 03:45	45.95	OK	19752	2026-09-24 03:46	48.33	OK
19753	2026-09-24 03:47	45.49	OK	19754	2026-09-24 03:48	46.73	OK
19755	2026-09-24 03:49	46.15	OK	19756	2026-09-24 03:50	46.67	OK
19757	2026-09-24 03:51	46.25	OK	19758	2026-09-24 03:52	46.41	OK
19759	2026-09-24 03:53	45.29	OK	19760	2026-09-24 03:54	46.21	OK
19761	2026-09-24 03:55	46.17	OK	19762	2026-09-24 03:56	45.91	OK
19763	2026-09-24 03:57	45.81	OK	19764	2026-09-24 03:58	46.39	OK
19765	2026-09-24 03:59	45.65	OK	19766	2026-09-24 04:00	44.97	OK
19767	2026-09-24 04:01	46.48	OK	19768	2026-09-24 04:02	46.65	OK
19769	2026-09-24 04:03	45.77	OK	19770	2026-09-24 04:04	45.85	OK
19771	2026-09-24 04:05	45.37	OK	19772	2026-09-24 04:06	43.83	OK
19773	2026-09-24 04:07	46.41	OK	19774	2026-09-24 04:08	45.31	OK
1977	2026-09-24 04:09	45.60	OK	1977	2026-09-24 04:10	45.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
19777	2026-09-24 04:11	45.77	OK	19778	2026-09-24 04:12	44.80	OK
19779	2026-09-24 04:13	47.27	OK	19780	2026-09-24 04:14	46.89	OK
19781	2026-09-24 04:15	47.83	OK	19782	2026-09-24 04:16	46.80	OK
19783	2026-09-24 04:17	45.63	OK	19784	2026-09-24 04:18	46.77	OK
19785	2026-09-24 04:19	46.11	OK	19786	2026-09-24 04:20	45.15	OK
19787	2026-09-24 04:21	47.03	OK	19788	2026-09-24 04:22	47.61	OK
19789	2026-09-24 04:23	47.15	OK	19790	2026-09-24 04:24	47.00	OK
19791	2026-09-24 04:25	45.70	OK	19792	2026-09-24 04:26	44.48	OK
19793	2026-09-24 04:27	46.78	OK	19794	2026-09-24 04:28	46.11	OK
19795	2026-09-24 04:29	45.63	OK	19796	2026-09-24 04:30	48.18	OK
19797	2026-09-24 04:31	46.07	OK	19798	2026-09-24 04:32	46.78	OK
19799	2026-09-24 04:33	46.40	OK	19800	2026-09-24 04:34	46.22	OK
19801	2026-09-24 04:35	46.69	OK	19802	2026-09-24 04:36	45.06	OK
19803	2026-09-24 04:37	45.61	OK	19804	2026-09-24 04:38	46.67	OK
19805	2026-09-24 04:39	44.79	OK	19806	2026-09-24 04:40	45.25	OK
19807	2026-09-24 04:41	46.05	OK	19808	2026-09-24 04:42	45.44	OK
19809	2026-09-24 04:43	45.74	OK	19810	2026-09-24 04:44	46.45	OK
19811	2026-09-24 04:45	47.01	OK	19812	2026-09-24 04:46	46.71	OK
19813	2026-09-24 04:47	46.18	OK	19814	2026-09-24 04:48	45.85	OK
19815	2026-09-24 04:49	47.83	OK	19816	2026-09-24 04:50	48.28	OK
19817	2026-09-24 04:51	46.19	OK	19818	2026-09-24 04:52	45.99	OK
19819	2026-09-24 04:53	44.63	OK	19820	2026-09-24 04:54	46.63	OK
19821	2026-09-24 04:55	46.13	OK	19822	2026-09-24 04:56	46.61	OK
19823	2026-09-24 04:57	46.46	OK	19824	2026-09-24 04:58	48.21	OK
19825	2026-09-24 04:59	46.62	OK	19826	2026-09-24 05:00	45.19	OK
19827	2026-09-24 05:01	48.15	OK	19828	2026-09-24 05:02	46.09	OK
19829	2026-09-24 05:03	45.76	OK	19830	2026-09-24 05:04	46.71	OK
19831	2026-09-24 05:05	45.56	OK	19832	2026-09-24 05:06	46.63	OK
19833	2026-09-24 05:07	47.67	OK	19834	2026-09-24 05:08	46.41	OK
1983	2026-09-24 05:09	47.99	OK	1983	2026-09-24 05:10	48.27	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
19837	2026-09-24 05:11	45.70	OK	19838	2026-09-24 05:12	46.15	OK
19839	2026-09-24 05:13	45.12	OK	19840	2026-09-24 05:14	45.36	OK
19841	2026-09-24 05:15	46.80	OK	19842	2026-09-24 05:16	46.86	OK
19843	2026-09-24 05:17	46.90	OK	19844	2026-09-24 05:18	48.20	OK
19845	2026-09-24 05:19	47.23	OK	19846	2026-09-24 05:20	47.26	OK
19847	2026-09-24 05:21	46.41	OK	19848	2026-09-24 05:22	47.85	OK
19849	2026-09-24 05:23	47.05	OK	19850	2026-09-24 05:24	46.49	OK
19851	2026-09-24 05:25	45.33	OK	19852	2026-09-24 05:26	45.82	OK
19853	2026-09-24 05:27	45.48	OK	19854	2026-09-24 05:28	46.46	OK
19855	2026-09-24 05:29	46.65	OK	19856	2026-09-24 05:30	49.02	OK
19857	2026-09-24 05:31	46.75	OK	19858	2026-09-24 05:32	47.26	OK
19859	2026-09-24 05:33	46.31	OK	19860	2026-09-24 05:34	48.64	OK
19861	2026-09-24 05:35	46.69	OK	19862	2026-09-24 05:36	47.28	OK
19863	2026-09-24 05:37	47.96	OK	19864	2026-09-24 05:38	48.28	OK
19865	2026-09-24 05:39	47.57	OK	19866	2026-09-24 05:40	48.82	OK
19867	2026-09-24 05:41	47.77	OK	19868	2026-09-24 05:42	46.92	OK
19869	2026-09-24 05:43	46.87	OK	19870	2026-09-24 05:44	48.24	OK
19871	2026-09-24 05:45	47.41	OK	19872	2026-09-24 05:46	46.61	OK
19873	2026-09-24 05:47	47.59	OK	19874	2026-09-24 05:48	48.60	OK
19875	2026-09-24 05:49	47.29	OK	19876	2026-09-24 05:50	48.96	OK
19877	2026-09-24 05:51	46.36	OK	19878	2026-09-24 05:52	45.79	OK
19879	2026-09-24 05:53	46.31	OK	19880	2026-09-24 05:54	48.08	OK
19881	2026-09-24 05:55	45.98	OK	19882	2026-09-24 05:56	46.20	OK
19883	2026-09-24 05:57	46.99	OK	19884	2026-09-24 05:58	46.59	OK
19885	2026-09-24 05:59	48.70	OK	19886	2026-09-24 06:00	48.35	OK
19887	2026-09-24 06:01	48.08	OK	19888	2026-09-24 06:02	45.82	OK
19889	2026-09-24 06:03	47.88	OK	19890	2026-09-24 06:04	46.57	OK
19891	2026-09-24 06:05	48.13	OK	19892	2026-09-24 06:06	47.74	OK
19893	2026-09-24 06:07	46.61	OK	19894	2026-09-24 06:08	47.59	OK
1989	2026-09-24 06:09	49.73	OK	1989	2026-09-24 06:10	46.44	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
19897	2026-09-24 06:11	46.64	OK	19898	2026-09-24 06:12	47.57	OK
19899	2026-09-24 06:13	47.22	OK	19900	2026-09-24 06:14	46.12	OK
19901	2026-09-24 06:15	47.84	OK	19902	2026-09-24 06:16	46.94	OK
19903	2026-09-24 06:17	46.55	OK	19904	2026-09-24 06:18	46.82	OK
19905	2026-09-24 06:19	47.68	OK	19906	2026-09-24 06:20	47.17	OK
19907	2026-09-24 06:21	46.64	OK	19908	2026-09-24 06:22	46.16	OK
19909	2026-09-24 06:23	46.56	OK	19910	2026-09-24 06:24	48.29	OK
19911	2026-09-24 06:25	47.05	OK	19912	2026-09-24 06:26	47.94	OK
19913	2026-09-24 06:27	47.35	OK	19914	2026-09-24 06:28	47.64	OK
19915	2026-09-24 06:29	47.48	OK	19916	2026-09-24 06:30	49.65	OK
19917	2026-09-24 06:31	47.07	OK	19918	2026-09-24 06:32	45.84	OK
19919	2026-09-24 06:33	47.00	OK	19920	2026-09-24 06:34	48.76	OK
19921	2026-09-24 06:35	46.14	OK	19922	2026-09-24 06:36	46.41	OK
19923	2026-09-24 06:37	46.11	OK	19924	2026-09-24 06:38	48.23	OK
19925	2026-09-24 06:39	47.13	OK	19926	2026-09-24 06:40	47.17	OK
19927	2026-09-24 06:41	49.56	OK	19928	2026-09-24 06:42	47.97	OK
19929	2026-09-24 06:43	46.15	OK	19930	2026-09-24 06:44	50.25	OK
19931	2026-09-24 06:45	46.72	OK	19932	2026-09-24 06:46	48.20	OK
19933	2026-09-24 06:47	49.85	OK	19934	2026-09-24 06:48	48.79	OK
19935	2026-09-24 06:49	48.83	OK	19936	2026-09-24 06:50	47.68	OK
19937	2026-09-24 06:51	46.66	OK	19938	2026-09-24 06:52	48.45	OK
19939	2026-09-24 06:53	48.59	OK	19940	2026-09-24 06:54	48.81	OK
19941	2026-09-24 06:55	48.96	OK	19942	2026-09-24 06:56	49.70	OK
19943	2026-09-24 06:57	48.91	OK	19944	2026-09-24 06:58	47.39	OK
19945	2026-09-24 06:59	48.35	OK	19946	2026-09-24 07:00	47.44	OK
19947	2026-09-24 07:01	48.77	OK	19948	2026-09-24 07:02	48.34	OK
19949	2026-09-24 07:03	49.74	OK	19950	2026-09-24 07:04	47.14	OK
19951	2026-09-24 07:05	48.67	OK	19952	2026-09-24 07:06	49.78	OK
19953	2026-09-24 07:07	48.07	OK	19954	2026-09-24 07:08	47.49	OK
19955	2026-09-24 07:09	49.51	OK	19955	2026-09-24 07:10	48.36	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
19957	2026-09-24 07:11	48.62	OK	19958	2026-09-24 07:12	49.20	OK
19959	2026-09-24 07:13	48.58	OK	19960	2026-09-24 07:14	47.97	OK
19961	2026-09-24 07:15	49.27	OK	19962	2026-09-24 07:16	47.18	OK
19963	2026-09-24 07:17	48.26	OK	19964	2026-09-24 07:18	48.86	OK
19965	2026-09-24 07:19	47.73	OK	19966	2026-09-24 07:20	49.67	OK
19967	2026-09-24 07:21	48.49	OK	19968	2026-09-24 07:22	48.26	OK
19969	2026-09-24 07:23	47.34	OK	19970	2026-09-24 07:24	47.23	OK
19971	2026-09-24 07:25	47.25	OK	19972	2026-09-24 07:26	47.65	OK
19973	2026-09-24 07:27	46.97	OK	19974	2026-09-24 07:28	49.36	OK
19975	2026-09-24 07:29	48.46	OK	19976	2026-09-24 07:30	48.24	OK
19977	2026-09-24 07:31	48.45	OK	19978	2026-09-24 07:32	49.30	OK
19979	2026-09-24 07:33	49.79	OK	19980	2026-09-24 07:34	46.99	OK
19981	2026-09-24 07:35	49.42	OK	19982	2026-09-24 07:36	47.31	OK
19983	2026-09-24 07:37	48.01	OK	19984	2026-09-24 07:38	49.12	OK
19985	2026-09-24 07:39	47.95	OK	19986	2026-09-24 07:40	48.52	OK
19987	2026-09-24 07:41	48.51	OK	19988	2026-09-24 07:42	47.99	OK
19989	2026-09-24 07:43	50.97	OK	19990	2026-09-24 07:44	49.18	OK
19991	2026-09-24 07:45	50.18	OK	19992	2026-09-24 07:46	49.83	OK
19993	2026-09-24 07:47	50.25	OK	19994	2026-09-24 07:48	48.19	OK
19995	2026-09-24 07:49	48.01	OK	19996	2026-09-24 07:50	47.13	OK
19997	2026-09-24 07:51	48.97	OK	19998	2026-09-24 07:52	48.88	OK
19999	2026-09-24 07:53	49.29	OK	20000	2026-09-24 07:54	49.81	OK
20001	2026-09-24 07:55	49.06	OK	20002	2026-09-24 07:56	49.65	OK
20003	2026-09-24 07:57	48.61	OK	20004	2026-09-24 07:58	50.47	OK
20005	2026-09-24 07:59	48.75	OK	20006	2026-09-24 08:00	50.80	OK
20007	2026-09-24 08:01	49.12	OK	20008	2026-09-24 08:02	49.30	OK
20009	2026-09-24 08:03	49.28	OK	20010	2026-09-24 08:04	49.62	OK
20011	2026-09-24 08:05	49.01	OK	20012	2026-09-24 08:06	49.62	OK
20013	2026-09-24 08:07	48.39	OK	20014	2026-09-24 08:08	50.29	OK
2001	2026-09-24 08:09	47.17	OK	2001	2026-09-24 08:10	48.84	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status
5			
20017	2026-09-24 08:11	50.76	OK
20019	2026-09-24 08:13	48.56	OK
20021	2026-09-24 08:15	48.40	OK
20023	2026-09-24 08:17	50.71	OK
20025	2026-09-24 08:19	50.10	OK
20027	2026-09-24 08:21	49.66	OK
20029	2026-09-24 08:23	49.01	OK
20031	2026-09-24 08:25	49.65	OK
20033	2026-09-24 08:27	50.37	OK
20035	2026-09-24 08:29	49.88	OK
20037	2026-09-24 08:31	49.51	OK
20039	2026-09-24 08:33	48.55	OK
20041	2026-09-24 08:35	49.36	OK
20043	2026-09-24 08:37	51.33	OK
20045	2026-09-24 08:39	51.06	OK
20047	2026-09-24 08:41	48.33	OK
20049	2026-09-24 08:43	49.15	OK
20051	2026-09-24 08:45	50.83	OK
20053	2026-09-24 08:47	49.73	OK
20055	2026-09-24 08:49	49.09	OK
20057	2026-09-24 08:51	50.10	OK
20059	2026-09-24 08:53	50.82	OK
20061	2026-09-24 08:55	50.29	OK
20063	2026-09-24 08:57	51.55	OK
20065	2026-09-24 08:59	50.51	OK
20067	2026-09-24 09:01	51.32	OK
20069	2026-09-24 09:03	50.03	OK
20071	2026-09-24 09:05	49.55	OK
20073	2026-09-24 09:07	49.82	OK
2007	2026-09-24 09:09	50.65	OK

#	Time (UTC)	Value (°C)	Status
6			
20018	2026-09-24 08:12	48.43	OK
20020	2026-09-24 08:14	50.45	OK
20022	2026-09-24 08:16	49.50	OK
20024	2026-09-24 08:18	50.10	OK
20026	2026-09-24 08:20	49.73	OK
20028	2026-09-24 08:22	50.45	OK
20030	2026-09-24 08:24	50.83	OK
20032	2026-09-24 08:26	48.00	OK
20034	2026-09-24 08:28	48.74	OK
20036	2026-09-24 08:30	50.60	OK
20038	2026-09-24 08:32	49.59	OK
20040	2026-09-24 08:34	50.73	OK
20042	2026-09-24 08:36	51.86	OK
20044	2026-09-24 08:38	50.27	OK
20046	2026-09-24 08:40	48.70	OK
20048	2026-09-24 08:42	48.48	OK
20050	2026-09-24 08:44	48.20	OK
20052	2026-09-24 08:46	50.57	OK
20054	2026-09-24 08:48	50.80	OK
20056	2026-09-24 08:50	49.24	OK
20058	2026-09-24 08:52	50.35	OK
20060	2026-09-24 08:54	50.77	OK
20062	2026-09-24 08:56	51.11	OK
20064	2026-09-24 08:58	50.96	OK
20066	2026-09-24 09:00	48.69	OK
20068	2026-09-24 09:02	50.94	OK
20070	2026-09-24 09:04	50.83	OK
20072	2026-09-24 09:06	51.19	OK
20074	2026-09-24 09:08	50.78	OK
2007	2026-09-24 09:10	48.66	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
20077	2026-09-24 09:11	50.23	OK	20078	2026-09-24 09:12	49.07	OK
20079	2026-09-24 09:13	50.95	OK	20080	2026-09-24 09:14	50.46	OK
20081	2026-09-24 09:15	51.82	OK	20082	2026-09-24 09:16	48.40	OK
20083	2026-09-24 09:17	49.23	OK	20084	2026-09-24 09:18	49.09	OK
20085	2026-09-24 09:19	50.15	OK	20086	2026-09-24 09:20	48.84	OK
20087	2026-09-24 09:21	50.87	OK	20088	2026-09-24 09:22	50.66	OK
20089	2026-09-24 09:23	50.77	OK	20090	2026-09-24 09:24	49.83	OK
20091	2026-09-24 09:25	48.58	OK	20092	2026-09-24 09:26	48.33	OK
20093	2026-09-24 09:27	50.07	OK	20094	2026-09-24 09:28	48.99	OK
20095	2026-09-24 09:29	50.79	OK	20096	2026-09-24 09:30	49.65	OK
20097	2026-09-24 09:31	49.88	OK	20098	2026-09-24 09:32	49.61	OK
20099	2026-09-24 09:33	51.32	OK	20100	2026-09-24 09:34	49.73	OK
20101	2026-09-24 09:35	50.67	OK	20102	2026-09-24 09:36	48.89	OK
20103	2026-09-24 09:37	51.50	OK	20104	2026-09-24 09:38	49.71	OK
20105	2026-09-24 09:39	50.76	OK	20106	2026-09-24 09:40	48.61	OK
20107	2026-09-24 09:41	50.79	OK	20108	2026-09-24 09:42	51.50	OK
20109	2026-09-24 09:43	50.45	OK	20110	2026-09-24 09:44	49.22	OK
20111	2026-09-24 09:45	49.12	OK	20112	2026-09-24 09:46	49.60	OK
20113	2026-09-24 09:47	50.44	OK	20114	2026-09-24 09:48	48.23	OK
20115	2026-09-24 09:49	49.40	OK	20116	2026-09-24 09:50	51.20	OK
20117	2026-09-24 09:51	51.80	OK	20118	2026-09-24 09:52	49.35	OK
20119	2026-09-24 09:53	52.36	OK	20120	2026-09-24 09:54	52.97	OK
20121	2026-09-24 09:55	50.35	OK	20122	2026-09-24 09:56	48.76	OK
20123	2026-09-24 09:57	51.31	OK	20124	2026-09-24 09:58	52.49	OK
20125	2026-09-24 09:59	49.94	OK	20126	2026-09-24 10:00	52.41	OK
20127	2026-09-24 10:01	50.67	OK	20128	2026-09-24 10:02	51.01	OK
20129	2026-09-24 10:03	50.43	OK	20130	2026-09-24 10:04	50.05	OK
20131	2026-09-24 10:05	51.90	OK	20132	2026-09-24 10:06	49.51	OK
20133	2026-09-24 10:07	52.16	OK	20134	2026-09-24 10:08	51.00	OK
2013	2026-09-24 10:09	50.80	OK	2013	2026-09-24 10:10	51.96	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5				6			
20137	2026-09-24 10:11	53.28	OK	20138	2026-09-24 10:12	49.76	OK
20139	2026-09-24 10:13	51.47	OK	20140	2026-09-24 10:14	52.32	OK
20141	2026-09-24 10:15	51.02	OK	20142	2026-09-24 10:16	48.47	OK
20143	2026-09-24 10:17	49.97	OK	20144	2026-09-24 10:18	50.84	OK
20145	2026-09-24 10:19	48.68	OK	20146	2026-09-24 10:20	50.59	OK
20147	2026-09-24 10:21	50.59	OK	20148	2026-09-24 10:22	50.61	OK
20149	2026-09-24 10:23	50.39	OK	20150	2026-09-24 10:24	50.98	OK
20151	2026-09-24 10:25	48.81	OK	20152	2026-09-24 10:26	51.79	OK
20153	2026-09-24 10:27	51.71	OK	20154	2026-09-24 10:28	50.81	OK
20155	2026-09-24 10:29	51.33	OK	20156	2026-09-24 10:30	50.88	OK
20157	2026-09-24 10:31	51.12	OK	20158	2026-09-24 10:32	51.30	OK
20159	2026-09-24 10:33	50.93	OK	20160	2026-09-24 10:34	51.79	OK
20161	2026-09-24 10:35	50.34	OK				

Signal: Bearing_Temp_NDE (°C)

All 20,161 Raw Readings

Operating Limits: [10.0 to 95.0] • Observed: Min 41.69, Max 57.04, Mean 49.42

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1	2026-09-10 10:35	53.71	OK	2	2026-09-10 10:36	52.40	OK
3	2026-09-10 10:37	53.82	OK	4	2026-09-10 10:38	54.28	OK
5	2026-09-10 10:39	55.13	OK	6	2026-09-10 10:40	51.75	OK
7	2026-09-10 10:41	53.37	OK	8	2026-09-10 10:42	55.13	OK
9	2026-09-10 10:43	55.14	OK	10	2026-09-10 10:44	54.07	OK
11	2026-09-10 10:45	53.92	OK	12	2026-09-10 10:46	54.47	OK
13	2026-09-10 10:47	53.76	OK	14	2026-09-10 10:48	53.06	OK
15	2026-09-10 10:49	54.67	OK	16	2026-09-10 10:50	54.28	OK
17	2026-09-10 10:51	53.84	OK	18	2026-09-10 10:52	54.81	OK
19	2026-09-10 10:53	55.47	OK	20	2026-09-10 10:54	53.07	OK
21	2026-09-10 10:55	55.97	OK	22	2026-09-10 10:56	54.26	OK
23	2026-09-10 10:57	56.41	OK	24	2026-09-10 10:58	53.96	OK
25	2026-09-10 10:59	52.25	OK	26	2026-09-10 11:00	53.82	OK
27	2026-09-10 11:01	55.10	OK	28	2026-09-10 11:02	53.62	OK
29	2026-09-10 11:03	55.89	OK	30	2026-09-10 11:04	54.64	OK
31	2026-09-10 11:05	53.23	OK	32	2026-09-10 11:06	55.68	OK
33	2026-09-10 11:07	52.42	OK	34	2026-09-10 11:08	54.72	OK
35	2026-09-10 11:09	53.52	OK	36	2026-09-10 11:10	54.17	OK
37	2026-09-10 11:11	52.84	OK	38	2026-09-10 11:12	53.77	OK
39	2026-09-10 11:13	55.10	OK	40	2026-09-10 11:14	54.28	OK
41	2026-09-10 11:15	54.79	OK	42	2026-09-10 11:16	53.51	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
43	2026-09-10 11:17	52.22	OK	44	2026-09-10 11:18	54.17	OK
45	2026-09-10 11:19	55.57	OK	46	2026-09-10 11:20	55.32	OK
47	2026-09-10 11:21	55.90	OK	48	2026-09-10 11:22	53.73	OK
49	2026-09-10 11:23	55.87	OK	50	2026-09-10 11:24	54.06	OK
51	2026-09-10 11:25	56.06	OK	52	2026-09-10 11:26	54.05	OK
53	2026-09-10 11:27	54.05	OK	54	2026-09-10 11:28	53.68	OK
55	2026-09-10 11:29	55.39	OK	56	2026-09-10 11:30	54.75	OK
57	2026-09-10 11:31	55.31	OK	58	2026-09-10 11:32	53.10	OK
59	2026-09-10 11:33	54.39	OK	60	2026-09-10 11:34	54.07	OK
61	2026-09-10 11:35	53.66	OK	62	2026-09-10 11:36	52.59	OK
63	2026-09-10 11:37	53.04	OK	64	2026-09-10 11:38	53.97	OK
65	2026-09-10 11:39	53.81	OK	66	2026-09-10 11:40	54.45	OK
67	2026-09-10 11:41	54.19	OK	68	2026-09-10 11:42	53.08	OK
69	2026-09-10 11:43	54.62	OK	70	2026-09-10 11:44	53.82	OK
71	2026-09-10 11:45	54.13	OK	72	2026-09-10 11:46	51.60	OK
73	2026-09-10 11:47	54.32	OK	74	2026-09-10 11:48	54.90	OK
75	2026-09-10 11:49	53.70	OK	76	2026-09-10 11:50	53.07	OK
77	2026-09-10 11:51	53.28	OK	78	2026-09-10 11:52	53.65	OK
79	2026-09-10 11:53	53.75	OK	80	2026-09-10 11:54	52.98	OK
81	2026-09-10 11:55	53.23	OK	82	2026-09-10 11:56	54.44	OK
83	2026-09-10 11:57	53.64	OK	84	2026-09-10 11:58	54.28	OK
85	2026-09-10 11:59	54.72	OK	86	2026-09-10 12:00	53.76	OK
87	2026-09-10 12:01	52.88	OK	88	2026-09-10 12:02	56.34	OK
89	2026-09-10 12:03	52.08	OK	90	2026-09-10 12:04	54.37	OK
91	2026-09-10 12:05	53.49	OK	92	2026-09-10 12:06	56.30	OK
93	2026-09-10 12:07	51.72	OK	94	2026-09-10 12:08	52.04	OK
95	2026-09-10 12:09	53.76	OK	96	2026-09-10 12:10	54.80	OK
97	2026-09-10 12:11	54.00	OK	98	2026-09-10 12:12	55.19	OK
99	2026-09-10 12:13	53.01	OK	100	2026-09-10 12:14	56.13	OK
101	2026-09-10 12:15	55.18	OK	102	2026-09-10 12:16	53.84	OK
103	2026-09-10 12:17	53.59	OK	104	2026-09-10 12:18	53.18	OK
105	2026-09-10 12:19	52.25	OK	106	2026-09-10 12:20	54.31	OK
107	2026-09-10 12:21	55.52	OK	108	2026-09-10 12:22	54.80	OK
109	2026-09-10 12:23	54.25	OK	110	2026-09-10 12:24	54.73	OK
111	2026-09-10 12:25	55.18	OK	112	2026-09-10 12:26	54.68	OK
113	2026-09-10 12:27	53.30	OK	114	2026-09-10 12:28	54.53	OK
115	2026-09-10 12:29	54.93	OK	116	2026-09-10 12:30	52.91	OK
117	2026-09-10 12:31	54.91	OK	118	2026-09-10 12:32	54.19	OK
119	2026-09-10 12:33	54.88	OK	120	2026-09-10 12:34	52.49	OK
121	2026-09-10 12:35	54.77	OK	122	2026-09-10 12:36	54.91	OK
123	2026-09-10 12:37	52.51	OK	124	2026-09-10 12:38	53.21	OK
125	2026-09-10 12:39	55.95	OK	126	2026-09-10 12:40	54.36	OK
127	2026-09-10 12:41	52.68	OK	128	2026-09-10 12:42	56.68	OK
129	2026-09-10 12:43	53.67	OK	130	2026-09-10 12:44	53.66	OK
131	2026-09-10 12:45	55.71	OK	132	2026-09-10 12:46	54.53	OK
133	2026-09-10 12:47	53.05	OK	134	2026-09-10 12:48	54.07	OK
135	2026-09-10 12:49	55.22	OK	136	2026-09-10 12:50	53.19	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
137	2026-09-10 12:51	51.95	OK	138	2026-09-10 12:52	53.64	OK
139	2026-09-10 12:53	52.51	OK	140	2026-09-10 12:54	52.52	OK
141	2026-09-10 12:55	54.23	OK	142	2026-09-10 12:56	53.15	OK
143	2026-09-10 12:57	55.61	OK	144	2026-09-10 12:58	54.05	OK
145	2026-09-10 12:59	54.20	OK	146	2026-09-10 13:00	52.94	OK
147	2026-09-10 13:01	53.87	OK	148	2026-09-10 13:02	54.36	OK
149	2026-09-10 13:03	53.94	OK	150	2026-09-10 13:04	52.64	OK
151	2026-09-10 13:05	54.63	OK	152	2026-09-10 13:06	55.37	OK
153	2026-09-10 13:07	52.81	OK	154	2026-09-10 13:08	52.27	OK
155	2026-09-10 13:09	53.44	OK	156	2026-09-10 13:10	55.48	OK
157	2026-09-10 13:11	52.04	OK	158	2026-09-10 13:12	55.14	OK
159	2026-09-10 13:13	54.28	OK	160	2026-09-10 13:14	54.12	OK
161	2026-09-10 13:15	53.46	OK	162	2026-09-10 13:16	54.15	OK
163	2026-09-10 13:17	52.91	OK	164	2026-09-10 13:18	55.29	OK
165	2026-09-10 13:19	51.51	OK	166	2026-09-10 13:20	51.71	OK
167	2026-09-10 13:21	55.00	OK	168	2026-09-10 13:22	52.85	OK
169	2026-09-10 13:23	55.52	OK	170	2026-09-10 13:24	52.39	OK
171	2026-09-10 13:25	55.45	OK	172	2026-09-10 13:26	54.58	OK
173	2026-09-10 13:27	52.67	OK	174	2026-09-10 13:28	52.59	OK
175	2026-09-10 13:29	50.71	OK	176	2026-09-10 13:30	54.28	OK
177	2026-09-10 13:31	54.28	OK	178	2026-09-10 13:32	53.33	OK
179	2026-09-10 13:33	53.73	OK	180	2026-09-10 13:34	52.63	OK
181	2026-09-10 13:35	54.10	OK	182	2026-09-10 13:36	55.43	OK
183	2026-09-10 13:37	53.46	OK	184	2026-09-10 13:38	53.57	OK
185	2026-09-10 13:39	52.53	OK	186	2026-09-10 13:40	53.61	OK
187	2026-09-10 13:41	54.60	OK	188	2026-09-10 13:42	52.39	OK
189	2026-09-10 13:43	52.36	OK	190	2026-09-10 13:44	53.66	OK
191	2026-09-10 13:45	52.39	OK	192	2026-09-10 13:46	51.01	OK
193	2026-09-10 13:47	54.50	OK	194	2026-09-10 13:48	53.70	OK
195	2026-09-10 13:49	53.98	OK	196	2026-09-10 13:50	52.91	OK
197	2026-09-10 13:51	52.67	OK	198	2026-09-10 13:52	52.76	OK
199	2026-09-10 13:53	54.24	OK	200	2026-09-10 13:54	51.23	OK
201	2026-09-10 13:55	51.37	OK	202	2026-09-10 13:56	54.27	OK
203	2026-09-10 13:57	52.57	OK	204	2026-09-10 13:58	55.20	OK
205	2026-09-10 13:59	53.39	OK	206	2026-09-10 14:00	53.38	OK
207	2026-09-10 14:01	55.35	OK	208	2026-09-10 14:02	54.45	OK
209	2026-09-10 14:03	54.53	OK	210	2026-09-10 14:04	52.50	OK
211	2026-09-10 14:05	54.35	OK	212	2026-09-10 14:06	53.01	OK
213	2026-09-10 14:07	52.06	OK	214	2026-09-10 14:08	53.19	OK
215	2026-09-10 14:09	51.90	OK	216	2026-09-10 14:10	52.74	OK
217	2026-09-10 14:11	52.34	OK	218	2026-09-10 14:12	52.20	OK
219	2026-09-10 14:13	52.02	OK	220	2026-09-10 14:14	52.61	OK
221	2026-09-10 14:15	51.91	OK	222	2026-09-10 14:16	51.52	OK
223	2026-09-10 14:17	50.59	OK	224	2026-09-10 14:18	50.65	OK
225	2026-09-10 14:19	53.74	OK	226	2026-09-10 14:20	54.71	OK
227	2026-09-10 14:21	52.04	OK	228	2026-09-10 14:22	52.35	OK
229	2026-09-10 14:23	53.82	OK	230	2026-09-10 14:24	51.68	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
231	2026-09-10 14:25	52.26	OK	232	2026-09-10 14:26	53.40	OK
233	2026-09-10 14:27	53.78	OK	234	2026-09-10 14:28	52.03	OK
235	2026-09-10 14:29	50.59	OK	236	2026-09-10 14:30	52.93	OK
237	2026-09-10 14:31	54.96	OK	238	2026-09-10 14:32	51.69	OK
239	2026-09-10 14:33	51.19	OK	240	2026-09-10 14:34	53.40	OK
241	2026-09-10 14:35	52.53	OK	242	2026-09-10 14:36	53.36	OK
243	2026-09-10 14:37	52.23	OK	244	2026-09-10 14:38	50.68	OK
245	2026-09-10 14:39	52.60	OK	246	2026-09-10 14:40	52.76	OK
247	2026-09-10 14:41	53.21	OK	248	2026-09-10 14:42	53.54	OK
249	2026-09-10 14:43	51.33	OK	250	2026-09-10 14:44	51.84	OK
251	2026-09-10 14:45	50.89	OK	252	2026-09-10 14:46	51.43	OK
253	2026-09-10 14:47	50.10	OK	254	2026-09-10 14:48	54.59	OK
255	2026-09-10 14:49	53.02	OK	256	2026-09-10 14:50	54.81	OK
257	2026-09-10 14:51	53.07	OK	258	2026-09-10 14:52	53.08	OK
259	2026-09-10 14:53	51.93	OK	260	2026-09-10 14:54	52.73	OK
261	2026-09-10 14:55	53.66	OK	262	2026-09-10 14:56	51.13	OK
263	2026-09-10 14:57	51.02	OK	264	2026-09-10 14:58	53.53	OK
265	2026-09-10 14:59	54.79	OK	266	2026-09-10 15:00	53.29	OK
267	2026-09-10 15:01	51.74	OK	268	2026-09-10 15:02	52.38	OK
269	2026-09-10 15:03	52.71	OK	270	2026-09-10 15:04	52.73	OK
271	2026-09-10 15:05	53.06	OK	272	2026-09-10 15:06	49.89	OK
273	2026-09-10 15:07	53.29	OK	274	2026-09-10 15:08	52.49	OK
275	2026-09-10 15:09	52.29	OK	276	2026-09-10 15:10	50.63	OK
277	2026-09-10 15:11	53.33	OK	278	2026-09-10 15:12	52.83	OK
279	2026-09-10 15:13	54.61	OK	280	2026-09-10 15:14	50.42	OK
281	2026-09-10 15:15	52.55	OK	282	2026-09-10 15:16	50.52	OK
283	2026-09-10 15:17	51.03	OK	284	2026-09-10 15:18	51.18	OK
285	2026-09-10 15:19	50.93	OK	286	2026-09-10 15:20	52.05	OK
287	2026-09-10 15:21	51.41	OK	288	2026-09-10 15:22	49.35	OK
289	2026-09-10 15:23	50.23	OK	290	2026-09-10 15:24	51.88	OK
291	2026-09-10 15:25	51.29	OK	292	2026-09-10 15:26	50.61	OK
293	2026-09-10 15:27	53.02	OK	294	2026-09-10 15:28	51.62	OK
295	2026-09-10 15:29	50.23	OK	296	2026-09-10 15:30	50.17	OK
297	2026-09-10 15:31	51.51	OK	298	2026-09-10 15:32	52.36	OK
299	2026-09-10 15:33	51.03	OK	300	2026-09-10 15:34	52.25	OK
301	2026-09-10 15:35	52.93	OK	302	2026-09-10 15:36	50.81	OK
303	2026-09-10 15:37	52.18	OK	304	2026-09-10 15:38	51.86	OK
305	2026-09-10 15:39	51.37	OK	306	2026-09-10 15:40	51.35	OK
307	2026-09-10 15:41	51.18	OK	308	2026-09-10 15:42	51.38	OK
309	2026-09-10 15:43	51.74	OK	310	2026-09-10 15:44	50.85	OK
311	2026-09-10 15:45	51.22	OK	312	2026-09-10 15:46	52.00	OK
313	2026-09-10 15:47	50.20	OK	314	2026-09-10 15:48	52.71	OK
315	2026-09-10 15:49	50.71	OK	316	2026-09-10 15:50	51.50	OK
317	2026-09-10 15:51	49.44	OK	318	2026-09-10 15:52	50.98	OK
319	2026-09-10 15:53	51.08	OK	320	2026-09-10 15:54	50.92	OK
321	2026-09-10 15:55	53.15	OK	322	2026-09-10 15:56	51.29	OK
323	2026-09-10 15:57	52.54	OK	324	2026-09-10 15:58	52.28	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
325	2026-09-10 15:59	49.26	OK	326	2026-09-10 16:00	49.35	OK
327	2026-09-10 16:01	51.79	OK	328	2026-09-10 16:02	50.47	OK
329	2026-09-10 16:03	51.36	OK	330	2026-09-10 16:04	51.51	OK
331	2026-09-10 16:05	51.48	OK	332	2026-09-10 16:06	51.44	OK
333	2026-09-10 16:07	51.05	OK	334	2026-09-10 16:08	51.06	OK
335	2026-09-10 16:09	50.63	OK	336	2026-09-10 16:10	49.88	OK
337	2026-09-10 16:11	50.85	OK	338	2026-09-10 16:12	50.80	OK
339	2026-09-10 16:13	50.64	OK	340	2026-09-10 16:14	51.27	OK
341	2026-09-10 16:15	53.98	OK	342	2026-09-10 16:16	49.45	OK
343	2026-09-10 16:17	50.24	OK	344	2026-09-10 16:18	48.80	OK
345	2026-09-10 16:19	52.13	OK	346	2026-09-10 16:20	49.34	OK
347	2026-09-10 16:21	51.55	OK	348	2026-09-10 16:22	50.19	OK
349	2026-09-10 16:23	52.31	OK	350	2026-09-10 16:24	48.59	OK
351	2026-09-10 16:25	49.91	OK	352	2026-09-10 16:26	51.32	OK
353	2026-09-10 16:27	51.05	OK	354	2026-09-10 16:28	48.69	OK
355	2026-09-10 16:29	49.88	OK	356	2026-09-10 16:30	50.85	OK
357	2026-09-10 16:31	49.67	OK	358	2026-09-10 16:32	50.06	OK
359	2026-09-10 16:33	50.46	OK	360	2026-09-10 16:34	51.41	OK
361	2026-09-10 16:35	49.84	OK	362	2026-09-10 16:36	50.13	OK
363	2026-09-10 16:37	49.00	OK	364	2026-09-10 16:38	50.61	OK
365	2026-09-10 16:39	49.96	OK	366	2026-09-10 16:40	50.76	OK
367	2026-09-10 16:41	51.88	OK	368	2026-09-10 16:42	50.02	OK
369	2026-09-10 16:43	51.21	OK	370	2026-09-10 16:44	51.05	OK
371	2026-09-10 16:45	50.37	OK	372	2026-09-10 16:46	50.66	OK
373	2026-09-10 16:47	50.04	OK	374	2026-09-10 16:48	50.14	OK
375	2026-09-10 16:49	48.87	OK	376	2026-09-10 16:50	51.16	OK
377	2026-09-10 16:51	48.87	OK	378	2026-09-10 16:52	50.87	OK
379	2026-09-10 16:53	51.73	OK	380	2026-09-10 16:54	50.34	OK
381	2026-09-10 16:55	50.97	OK	382	2026-09-10 16:56	49.93	OK
383	2026-09-10 16:57	50.17	OK	384	2026-09-10 16:58	52.20	OK
385	2026-09-10 16:59	50.67	OK	386	2026-09-10 17:00	50.01	OK
387	2026-09-10 17:01	49.57	OK	388	2026-09-10 17:02	50.42	OK
389	2026-09-10 17:03	48.62	OK	390	2026-09-10 17:04	47.16	OK
391	2026-09-10 17:05	47.71	OK	392	2026-09-10 17:06	51.01	OK
393	2026-09-10 17:07	47.83	OK	394	2026-09-10 17:08	50.32	OK
395	2026-09-10 17:09	48.65	OK	396	2026-09-10 17:10	47.45	OK
397	2026-09-10 17:11	50.41	OK	398	2026-09-10 17:12	50.48	OK
399	2026-09-10 17:13	47.64	OK	400	2026-09-10 17:14	49.03	OK
401	2026-09-10 17:15	49.35	OK	402	2026-09-10 17:16	49.97	OK
403	2026-09-10 17:17	50.30	OK	404	2026-09-10 17:18	51.08	OK
405	2026-09-10 17:19	47.94	OK	406	2026-09-10 17:20	49.42	OK
407	2026-09-10 17:21	49.27	OK	408	2026-09-10 17:22	49.05	OK
409	2026-09-10 17:23	48.66	OK	410	2026-09-10 17:24	50.74	OK
411	2026-09-10 17:25	49.74	OK	412	2026-09-10 17:26	49.80	OK
413	2026-09-10 17:27	49.03	OK	414	2026-09-10 17:28	49.62	OK
415	2026-09-10 17:29	49.58	OK	416	2026-09-10 17:30	50.61	OK
417	2026-09-10 17:31	48.94	OK	418	2026-09-10 17:32	51.68	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
419	2026-09-10 17:33	49.07	OK	420	2026-09-10 17:34	49.14	OK
421	2026-09-10 17:35	49.39	OK	422	2026-09-10 17:36	48.64	OK
423	2026-09-10 17:37	50.41	OK	424	2026-09-10 17:38	48.50	OK
425	2026-09-10 17:39	48.40	OK	426	2026-09-10 17:40	48.50	OK
427	2026-09-10 17:41	48.78	OK	428	2026-09-10 17:42	50.07	OK
429	2026-09-10 17:43	49.49	OK	430	2026-09-10 17:44	49.22	OK
431	2026-09-10 17:45	47.29	OK	432	2026-09-10 17:46	48.11	OK
433	2026-09-10 17:47	48.63	OK	434	2026-09-10 17:48	48.91	OK
435	2026-09-10 17:49	48.56	OK	436	2026-09-10 17:50	49.26	OK
437	2026-09-10 17:51	48.24	OK	438	2026-09-10 17:52	49.01	OK
439	2026-09-10 17:53	47.53	OK	440	2026-09-10 17:54	48.13	OK
441	2026-09-10 17:55	50.40	OK	442	2026-09-10 17:56	49.27	OK
443	2026-09-10 17:57	49.02	OK	444	2026-09-10 17:58	50.09	OK
445	2026-09-10 17:59	47.87	OK	446	2026-09-10 18:00	49.74	OK
447	2026-09-10 18:01	49.26	OK	448	2026-09-10 18:02	47.07	OK
449	2026-09-10 18:03	50.07	OK	450	2026-09-10 18:04	48.19	OK
451	2026-09-10 18:05	47.93	OK	452	2026-09-10 18:06	48.32	OK
453	2026-09-10 18:07	49.90	OK	454	2026-09-10 18:08	48.24	OK
455	2026-09-10 18:09	47.55	OK	456	2026-09-10 18:10	47.87	OK
457	2026-09-10 18:11	49.78	OK	458	2026-09-10 18:12	48.83	OK
459	2026-09-10 18:13	47.63	OK	460	2026-09-10 18:14	49.88	OK
461	2026-09-10 18:15	48.81	OK	462	2026-09-10 18:16	46.27	OK
463	2026-09-10 18:17	47.76	OK	464	2026-09-10 18:18	46.93	OK
465	2026-09-10 18:19	48.86	OK	466	2026-09-10 18:20	46.49	OK
467	2026-09-10 18:21	47.13	OK	468	2026-09-10 18:22	47.43	OK
469	2026-09-10 18:23	48.11	OK	470	2026-09-10 18:24	47.28	OK
471	2026-09-10 18:25	49.71	OK	472	2026-09-10 18:26	48.74	OK
473	2026-09-10 18:27	47.77	OK	474	2026-09-10 18:28	47.53	OK
475	2026-09-10 18:29	48.94	OK	476	2026-09-10 18:30	47.16	OK
477	2026-09-10 18:31	48.49	OK	478	2026-09-10 18:32	49.26	OK
479	2026-09-10 18:33	45.97	OK	480	2026-09-10 18:34	47.93	OK
481	2026-09-10 18:35	47.70	OK	482	2026-09-10 18:36	47.74	OK
483	2026-09-10 18:37	48.39	OK	484	2026-09-10 18:38	48.75	OK
485	2026-09-10 18:39	47.85	OK	486	2026-09-10 18:40	48.59	OK
487	2026-09-10 18:41	48.68	OK	488	2026-09-10 18:42	49.07	OK
489	2026-09-10 18:43	50.03	OK	490	2026-09-10 18:44	49.23	OK
491	2026-09-10 18:45	47.74	OK	492	2026-09-10 18:46	47.86	OK
493	2026-09-10 18:47	47.68	OK	494	2026-09-10 18:48	48.04	OK
495	2026-09-10 18:49	48.24	OK	496	2026-09-10 18:50	49.32	OK
497	2026-09-10 18:51	48.28	OK	498	2026-09-10 18:52	47.48	OK
499	2026-09-10 18:53	46.52	OK	500	2026-09-10 18:54	46.96	OK
501	2026-09-10 18:55	48.19	OK	502	2026-09-10 18:56	47.47	OK
503	2026-09-10 18:57	48.01	OK	504	2026-09-10 18:58	48.07	OK
505	2026-09-10 18:59	48.36	OK	506	2026-09-10 19:00	48.81	OK
507	2026-09-10 19:01	46.43	OK	508	2026-09-10 19:02	46.68	OK
509	2026-09-10 19:03	48.87	OK	510	2026-09-10 19:04	47.48	OK
511	2026-09-10 19:05	48.99	OK	512	2026-09-10 19:06	49.55	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
513	2026-09-10 19:07	47.19	OK	514	2026-09-10 19:08	48.74	OK
515	2026-09-10 19:09	48.82	OK	516	2026-09-10 19:10	46.29	OK
517	2026-09-10 19:11	46.33	OK	518	2026-09-10 19:12	47.86	OK
519	2026-09-10 19:13	45.87	OK	520	2026-09-10 19:14	46.89	OK
521	2026-09-10 19:15	46.34	OK	522	2026-09-10 19:16	45.49	OK
523	2026-09-10 19:17	47.81	OK	524	2026-09-10 19:18	46.25	OK
525	2026-09-10 19:19	45.90	OK	526	2026-09-10 19:20	45.28	OK
527	2026-09-10 19:21	48.69	OK	528	2026-09-10 19:22	46.38	OK
529	2026-09-10 19:23	45.81	OK	530	2026-09-10 19:24	46.27	OK
531	2026-09-10 19:25	48.27	OK	532	2026-09-10 19:26	47.24	OK
533	2026-09-10 19:27	46.68	OK	534	2026-09-10 19:28	45.35	OK
535	2026-09-10 19:29	47.54	OK	536	2026-09-10 19:30	45.92	OK
537	2026-09-10 19:31	45.63	OK	538	2026-09-10 19:32	45.31	OK
539	2026-09-10 19:33	46.44	OK	540	2026-09-10 19:34	46.36	OK
541	2026-09-10 19:35	47.51	OK	542	2026-09-10 19:36	47.26	OK
543	2026-09-10 19:37	46.03	OK	544	2026-09-10 19:38	46.88	OK
545	2026-09-10 19:39	46.21	OK	546	2026-09-10 19:40	44.93	OK
547	2026-09-10 19:41	45.93	OK	548	2026-09-10 19:42	45.74	OK
549	2026-09-10 19:43	47.45	OK	550	2026-09-10 19:44	45.85	OK
551	2026-09-10 19:45	47.68	OK	552	2026-09-10 19:46	45.90	OK
553	2026-09-10 19:47	47.08	OK	554	2026-09-10 19:48	45.65	OK
555	2026-09-10 19:49	48.15	OK	556	2026-09-10 19:50	47.65	OK
557	2026-09-10 19:51	45.08	OK	558	2026-09-10 19:52	46.62	OK
559	2026-09-10 19:53	48.94	OK	560	2026-09-10 19:54	46.61	OK
561	2026-09-10 19:55	44.63	OK	562	2026-09-10 19:56	46.90	OK
563	2026-09-10 19:57	48.65	OK	564	2026-09-10 19:58	44.43	OK
565	2026-09-10 19:59	47.26	OK	566	2026-09-10 20:00	45.98	OK
567	2026-09-10 20:01	44.42	OK	568	2026-09-10 20:02	48.62	OK
569	2026-09-10 20:03	45.86	OK	570	2026-09-10 20:04	46.60	OK
571	2026-09-10 20:05	47.19	OK	572	2026-09-10 20:06	47.28	OK
573	2026-09-10 20:07	47.21	OK	574	2026-09-10 20:08	45.44	OK
575	2026-09-10 20:09	44.20	OK	576	2026-09-10 20:10	46.55	OK
577	2026-09-10 20:11	46.54	OK	578	2026-09-10 20:12	46.04	OK
579	2026-09-10 20:13	47.49	OK	580	2026-09-10 20:14	44.65	OK
581	2026-09-10 20:15	45.02	OK	582	2026-09-10 20:16	47.30	OK
583	2026-09-10 20:17	45.78	OK	584	2026-09-10 20:18	45.77	OK
585	2026-09-10 20:19	47.85	OK	586	2026-09-10 20:20	48.32	OK
587	2026-09-10 20:21	45.97	OK	588	2026-09-10 20:22	45.73	OK
589	2026-09-10 20:23	48.59	OK	590	2026-09-10 20:24	47.23	OK
591	2026-09-10 20:25	45.35	OK	592	2026-09-10 20:26	44.98	OK
593	2026-09-10 20:27	47.58	OK	594	2026-09-10 20:28	46.40	OK
595	2026-09-10 20:29	47.25	OK	596	2026-09-10 20:30	45.87	OK
597	2026-09-10 20:31	45.42	OK	598	2026-09-10 20:32	46.74	OK
599	2026-09-10 20:33	46.42	OK	600	2026-09-10 20:34	47.16	OK
601	2026-09-10 20:35	45.25	OK	602	2026-09-10 20:36	44.64	OK
603	2026-09-10 20:37	43.60	OK	604	2026-09-10 20:38	46.43	OK
605	2026-09-10 20:39	45.13	OK	606	2026-09-10 20:40	44.59	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
607	2026-09-10 20:41	45.93	OK	608	2026-09-10 20:42	44.87	OK
609	2026-09-10 20:43	44.85	OK	610	2026-09-10 20:44	45.48	OK
611	2026-09-10 20:45	47.97	OK	612	2026-09-10 20:46	46.80	OK
613	2026-09-10 20:47	46.84	OK	614	2026-09-10 20:48	44.66	OK
615	2026-09-10 20:49	43.88	OK	616	2026-09-10 20:50	47.75	OK
617	2026-09-10 20:51	43.95	OK	618	2026-09-10 20:52	45.70	OK
619	2026-09-10 20:53	46.18	OK	620	2026-09-10 20:54	45.20	OK
621	2026-09-10 20:55	47.59	OK	622	2026-09-10 20:56	43.92	OK
623	2026-09-10 20:57	47.95	OK	624	2026-09-10 20:58	43.71	OK
625	2026-09-10 20:59	46.08	OK	626	2026-09-10 21:00	47.10	OK
627	2026-09-10 21:01	44.72	OK	628	2026-09-10 21:02	44.78	OK
629	2026-09-10 21:03	45.66	OK	630	2026-09-10 21:04	46.43	OK
631	2026-09-10 21:05	47.32	OK	632	2026-09-10 21:06	47.22	OK
633	2026-09-10 21:07	44.98	OK	634	2026-09-10 21:08	45.23	OK
635	2026-09-10 21:09	45.69	OK	636	2026-09-10 21:10	45.14	OK
637	2026-09-10 21:11	45.56	OK	638	2026-09-10 21:12	43.66	OK
639	2026-09-10 21:13	44.67	OK	640	2026-09-10 21:14	47.67	OK
641	2026-09-10 21:15	45.31	OK	642	2026-09-10 21:16	45.42	OK
643	2026-09-10 21:17	44.70	OK	644	2026-09-10 21:18	45.73	OK
645	2026-09-10 21:19	45.97	OK	646	2026-09-10 21:20	45.30	OK
647	2026-09-10 21:21	46.00	OK	648	2026-09-10 21:22	46.85	OK
649	2026-09-10 21:23	44.53	OK	650	2026-09-10 21:24	44.64	OK
651	2026-09-10 21:25	46.18	OK	652	2026-09-10 21:26	45.43	OK
653	2026-09-10 21:27	45.58	OK	654	2026-09-10 21:28	45.39	OK
655	2026-09-10 21:29	44.58	OK	656	2026-09-10 21:30	46.93	OK
657	2026-09-10 21:31	44.99	OK	658	2026-09-10 21:32	48.22	OK
659	2026-09-10 21:33	46.42	OK	660	2026-09-10 21:34	45.79	OK
661	2026-09-10 21:35	45.13	OK	662	2026-09-10 21:36	46.72	OK
663	2026-09-10 21:37	47.00	OK	664	2026-09-10 21:38	44.44	OK
665	2026-09-10 21:39	45.96	OK	666	2026-09-10 21:40	44.87	OK
667	2026-09-10 21:41	42.95	OK	668	2026-09-10 21:42	42.48	OK
669	2026-09-10 21:43	45.11	OK	670	2026-09-10 21:44	44.91	OK
671	2026-09-10 21:45	45.76	OK	672	2026-09-10 21:46	44.13	OK
673	2026-09-10 21:47	45.30	OK	674	2026-09-10 21:48	45.31	OK
675	2026-09-10 21:49	44.89	OK	676	2026-09-10 21:50	45.06	OK
677	2026-09-10 21:51	47.50	OK	678	2026-09-10 21:52	45.78	OK
679	2026-09-10 21:53	45.09	OK	680	2026-09-10 21:54	46.53	OK
681	2026-09-10 21:55	45.64	OK	682	2026-09-10 21:56	45.13	OK
683	2026-09-10 21:57	46.36	OK	684	2026-09-10 21:58	42.78	OK
685	2026-09-10 21:59	45.47	OK	686	2026-09-10 22:00	45.29	OK
687	2026-09-10 22:01	44.66	OK	688	2026-09-10 22:02	46.14	OK
689	2026-09-10 22:03	47.24	OK	690	2026-09-10 22:04	43.99	OK
691	2026-09-10 22:05	44.43	OK	692	2026-09-10 22:06	44.88	OK
693	2026-09-10 22:07	43.71	OK	694	2026-09-10 22:08	45.04	OK
695	2026-09-10 22:09	46.22	OK	696	2026-09-10 22:10	43.54	OK
697	2026-09-10 22:11	43.50	OK	698	2026-09-10 22:12	44.62	OK
699	2026-09-10 22:13	44.41	OK	700	2026-09-10 22:14	45.14	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
701	2026-09-10 22:15	46.62	OK	702	2026-09-10 22:16	46.52	OK
703	2026-09-10 22:17	45.47	OK	704	2026-09-10 22:18	45.72	OK
705	2026-09-10 22:19	43.84	OK	706	2026-09-10 22:20	45.16	OK
707	2026-09-10 22:21	44.18	OK	708	2026-09-10 22:22	42.68	OK
709	2026-09-10 22:23	47.30	OK	710	2026-09-10 22:24	43.90	OK
711	2026-09-10 22:25	44.69	OK	712	2026-09-10 22:26	43.84	OK
713	2026-09-10 22:27	44.83	OK	714	2026-09-10 22:28	45.43	OK
715	2026-09-10 22:29	43.95	OK	716	2026-09-10 22:30	42.58	OK
717	2026-09-10 22:31	44.98	OK	718	2026-09-10 22:32	45.30	OK
719	2026-09-10 22:33	43.79	OK	720	2026-09-10 22:34	42.78	OK
721	2026-09-10 22:35	46.18	OK	722	2026-09-10 22:36	43.62	OK
723	2026-09-10 22:37	43.58	OK	724	2026-09-10 22:38	45.07	OK
725	2026-09-10 22:39	45.60	OK	726	2026-09-10 22:40	45.44	OK
727	2026-09-10 22:41	44.76	OK	728	2026-09-10 22:42	46.48	OK
729	2026-09-10 22:43	44.72	OK	730	2026-09-10 22:44	46.68	OK
731	2026-09-10 22:45	45.37	OK	732	2026-09-10 22:46	44.14	OK
733	2026-09-10 22:47	45.61	OK	734	2026-09-10 22:48	44.10	OK
735	2026-09-10 22:49	46.07	OK	736	2026-09-10 22:50	42.94	OK
737	2026-09-10 22:51	46.61	OK	738	2026-09-10 22:52	42.76	OK
739	2026-09-10 22:53	44.80	OK	740	2026-09-10 22:54	45.83	OK
741	2026-09-10 22:55	44.29	OK	742	2026-09-10 22:56	45.40	OK
743	2026-09-10 22:57	42.90	OK	744	2026-09-10 22:58	45.46	OK
745	2026-09-10 22:59	45.22	OK	746	2026-09-10 23:00	47.20	OK
747	2026-09-10 23:01	46.25	OK	748	2026-09-10 23:02	44.62	OK
749	2026-09-10 23:03	44.12	OK	750	2026-09-10 23:04	45.83	OK
751	2026-09-10 23:05	44.76	OK	752	2026-09-10 23:06	44.73	OK
753	2026-09-10 23:07	45.33	OK	754	2026-09-10 23:08	46.34	OK
755	2026-09-10 23:09	43.09	OK	756	2026-09-10 23:10	45.60	OK
757	2026-09-10 23:11	43.25	OK	758	2026-09-10 23:12	44.97	OK
759	2026-09-10 23:13	45.17	OK	760	2026-09-10 23:14	46.41	OK
761	2026-09-10 23:15	44.54	OK	762	2026-09-10 23:16	45.05	OK
763	2026-09-10 23:17	43.21	OK	764	2026-09-10 23:18	44.01	OK
765	2026-09-10 23:19	44.38	OK	766	2026-09-10 23:20	42.26	OK
767	2026-09-10 23:21	44.69	OK	768	2026-09-10 23:22	45.58	OK
769	2026-09-10 23:23	45.26	OK	770	2026-09-10 23:24	42.69	OK
771	2026-09-10 23:25	45.80	OK	772	2026-09-10 23:26	46.51	OK
773	2026-09-10 23:27	44.46	OK	774	2026-09-10 23:28	45.81	OK
775	2026-09-10 23:29	43.47	OK	776	2026-09-10 23:30	44.80	OK
777	2026-09-10 23:31	46.01	OK	778	2026-09-10 23:32	46.74	OK
779	2026-09-10 23:33	42.97	OK	780	2026-09-10 23:34	46.26	OK
781	2026-09-10 23:35	42.77	OK	782	2026-09-10 23:36	44.01	OK
783	2026-09-10 23:37	44.54	OK	784	2026-09-10 23:38	43.72	OK
785	2026-09-10 23:39	46.56	OK	786	2026-09-10 23:40	44.52	OK
787	2026-09-10 23:41	43.81	OK	788	2026-09-10 23:42	45.04	OK
789	2026-09-10 23:43	43.87	OK	790	2026-09-10 23:44	44.13	OK
791	2026-09-10 23:45	42.52	OK	792	2026-09-10 23:46	43.19	OK
793	2026-09-10 23:47	45.91	OK	794	2026-09-10 23:48	44.05	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
795	2026-09-10 23:49	45.75	OK	796	2026-09-10 23:50	45.84	OK
797	2026-09-10 23:51	43.75	OK	798	2026-09-10 23:52	43.62	OK
799	2026-09-10 23:53	45.57	OK	800	2026-09-10 23:54	43.74	OK
801	2026-09-10 23:55	45.34	OK	802	2026-09-10 23:56	45.26	OK
803	2026-09-10 23:57	42.31	OK	804	2026-09-10 23:58	45.56	OK
805	2026-09-10 23:59	42.82	OK	806	2026-09-11 00:00	45.38	OK
807	2026-09-11 00:01	46.73	OK	808	2026-09-11 00:02	45.25	OK
809	2026-09-11 00:03	46.33	OK	810	2026-09-11 00:04	45.41	OK
811	2026-09-11 00:05	46.21	OK	812	2026-09-11 00:06	44.26	OK
813	2026-09-11 00:07	45.02	OK	814	2026-09-11 00:08	45.48	OK
815	2026-09-11 00:09	43.85	OK	816	2026-09-11 00:10	44.38	OK
817	2026-09-11 00:11	44.98	OK	818	2026-09-11 00:12	44.99	OK
819	2026-09-11 00:13	43.26	OK	820	2026-09-11 00:14	45.86	OK
821	2026-09-11 00:15	45.26	OK	822	2026-09-11 00:16	45.75	OK
823	2026-09-11 00:17	42.87	OK	824	2026-09-11 00:18	43.62	OK
825	2026-09-11 00:19	43.62	OK	826	2026-09-11 00:20	43.72	OK
827	2026-09-11 00:21	45.20	OK	828	2026-09-11 00:22	45.99	OK
829	2026-09-11 00:23	44.26	OK	830	2026-09-11 00:24	46.17	OK
831	2026-09-11 00:25	43.94	OK	832	2026-09-11 00:26	43.96	OK
833	2026-09-11 00:27	46.80	OK	834	2026-09-11 00:28	44.82	OK
835	2026-09-11 00:29	43.76	OK	836	2026-09-11 00:30	45.19	OK
837	2026-09-11 00:31	45.03	OK	838	2026-09-11 00:32	42.94	OK
839	2026-09-11 00:33	44.66	OK	840	2026-09-11 00:34	46.71	OK
841	2026-09-11 00:35	43.14	OK	842	2026-09-11 00:36	44.83	OK
843	2026-09-11 00:37	46.29	OK	844	2026-09-11 00:38	43.02	OK
845	2026-09-11 00:39	43.71	OK	846	2026-09-11 00:40	45.57	OK
847	2026-09-11 00:41	46.88	OK	848	2026-09-11 00:42	46.34	OK
849	2026-09-11 00:43	45.04	OK	850	2026-09-11 00:44	46.01	OK
851	2026-09-11 00:45	45.05	OK	852	2026-09-11 00:46	46.20	OK
853	2026-09-11 00:47	46.26	OK	854	2026-09-11 00:48	45.05	OK
855	2026-09-11 00:49	44.85	OK	856	2026-09-11 00:50	45.71	OK
857	2026-09-11 00:51	44.68	OK	858	2026-09-11 00:52	45.01	OK
859	2026-09-11 00:53	47.68	OK	860	2026-09-11 00:54	44.35	OK
861	2026-09-11 00:55	44.47	OK	862	2026-09-11 00:56	44.72	OK
863	2026-09-11 00:57	45.61	OK	864	2026-09-11 00:58	44.28	OK
865	2026-09-11 00:59	45.66	OK	866	2026-09-11 01:00	44.24	OK
867	2026-09-11 01:01	42.98	OK	868	2026-09-11 01:02	44.31	OK
869	2026-09-11 01:03	45.98	OK	870	2026-09-11 01:04	43.41	OK
871	2026-09-11 01:05	43.22	OK	872	2026-09-11 01:06	46.49	OK
873	2026-09-11 01:07	46.42	OK	874	2026-09-11 01:08	43.65	OK
875	2026-09-11 01:09	46.08	OK	876	2026-09-11 01:10	46.69	OK
877	2026-09-11 01:11	46.56	OK	878	2026-09-11 01:12	45.37	OK
879	2026-09-11 01:13	46.16	OK	880	2026-09-11 01:14	45.99	OK
881	2026-09-11 01:15	46.61	OK	882	2026-09-11 01:16	44.45	OK
883	2026-09-11 01:17	45.78	OK	884	2026-09-11 01:18	46.35	OK
885	2026-09-11 01:19	43.69	OK	886	2026-09-11 01:20	44.78	OK
887	2026-09-11 01:21	47.07	OK	888	2026-09-11 01:22	44.27	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
889	2026-09-11 01:23	46.47	OK	890	2026-09-11 01:24	43.47	OK
891	2026-09-11 01:25	43.59	OK	892	2026-09-11 01:26	46.22	OK
893	2026-09-11 01:27	44.03	OK	894	2026-09-11 01:28	46.41	OK
895	2026-09-11 01:29	45.12	OK	896	2026-09-11 01:30	45.62	OK
897	2026-09-11 01:31	46.53	OK	898	2026-09-11 01:32	44.72	OK
899	2026-09-11 01:33	44.83	OK	900	2026-09-11 01:34	44.32	OK
901	2026-09-11 01:35	45.01	OK	902	2026-09-11 01:36	45.85	OK
903	2026-09-11 01:37	44.78	OK	904	2026-09-11 01:38	45.61	OK
905	2026-09-11 01:39	44.39	OK	906	2026-09-11 01:40	47.83	OK
907	2026-09-11 01:41	43.94	OK	908	2026-09-11 01:42	44.88	OK
909	2026-09-11 01:43	45.87	OK	910	2026-09-11 01:44	47.61	OK
911	2026-09-11 01:45	46.58	OK	912	2026-09-11 01:46	46.83	OK
913	2026-09-11 01:47	47.09	OK	914	2026-09-11 01:48	44.29	OK
915	2026-09-11 01:49	44.26	OK	916	2026-09-11 01:50	46.01	OK
917	2026-09-11 01:51	43.60	OK	918	2026-09-11 01:52	46.75	OK
919	2026-09-11 01:53	45.90	OK	920	2026-09-11 01:54	44.68	OK
921	2026-09-11 01:55	44.81	OK	922	2026-09-11 01:56	46.17	OK
923	2026-09-11 01:57	45.22	OK	924	2026-09-11 01:58	45.66	OK
925	2026-09-11 01:59	43.54	OK	926	2026-09-11 02:00	45.05	OK
927	2026-09-11 02:01	45.02	OK	928	2026-09-11 02:02	45.53	OK
929	2026-09-11 02:03	44.19	OK	930	2026-09-11 02:04	44.99	OK
931	2026-09-11 02:05	45.11	OK	932	2026-09-11 02:06	47.41	OK
933	2026-09-11 02:07	45.13	OK	934	2026-09-11 02:08	45.91	OK
935	2026-09-11 02:09	45.29	OK	936	2026-09-11 02:10	43.55	OK
937	2026-09-11 02:11	45.72	OK	938	2026-09-11 02:12	46.79	OK
939	2026-09-11 02:13	45.47	OK	940	2026-09-11 02:14	46.68	OK
941	2026-09-11 02:15	46.81	OK	942	2026-09-11 02:16	45.82	OK
943	2026-09-11 02:17	46.30	OK	944	2026-09-11 02:18	45.49	OK
945	2026-09-11 02:19	46.24	OK	946	2026-09-11 02:20	47.08	OK
947	2026-09-11 02:21	45.68	OK	948	2026-09-11 02:22	45.88	OK
949	2026-09-11 02:23	44.71	OK	950	2026-09-11 02:24	43.40	OK
951	2026-09-11 02:25	46.06	OK	952	2026-09-11 02:26	44.81	OK
953	2026-09-11 02:27	45.63	OK	954	2026-09-11 02:28	46.69	OK
955	2026-09-11 02:29	45.50	OK	956	2026-09-11 02:30	45.74	OK
957	2026-09-11 02:31	45.02	OK	958	2026-09-11 02:32	47.29	OK
959	2026-09-11 02:33	46.55	OK	960	2026-09-11 02:34	44.54	OK
961	2026-09-11 02:35	46.22	OK	962	2026-09-11 02:36	47.05	OK
963	2026-09-11 02:37	46.74	OK	964	2026-09-11 02:38	46.67	OK
965	2026-09-11 02:39	45.57	OK	966	2026-09-11 02:40	46.19	OK
967	2026-09-11 02:41	44.84	OK	968	2026-09-11 02:42	48.57	OK
969	2026-09-11 02:43	47.93	OK	970	2026-09-11 02:44	47.61	OK
971	2026-09-11 02:45	46.76	OK	972	2026-09-11 02:46	44.67	OK
973	2026-09-11 02:47	46.75	OK	974	2026-09-11 02:48	48.39	OK
975	2026-09-11 02:49	47.42	OK	976	2026-09-11 02:50	46.67	OK
977	2026-09-11 02:51	44.01	OK	978	2026-09-11 02:52	46.59	OK
979	2026-09-11 02:53	47.45	OK	980	2026-09-11 02:54	47.27	OK
981	2026-09-11 02:55	46.06	OK	982	2026-09-11 02:56	45.61	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
983	2026-09-11 02:57	45.30	OK	984	2026-09-11 02:58	47.07	OK
985	2026-09-11 02:59	46.75	OK	986	2026-09-11 03:00	45.54	OK
987	2026-09-11 03:01	47.22	OK	988	2026-09-11 03:02	46.34	OK
989	2026-09-11 03:03	45.44	OK	990	2026-09-11 03:04	44.75	OK
991	2026-09-11 03:05	45.45	OK	992	2026-09-11 03:06	46.21	OK
993	2026-09-11 03:07	45.50	OK	994	2026-09-11 03:08	49.63	OK
995	2026-09-11 03:09	47.57	OK	996	2026-09-11 03:10	47.45	OK
997	2026-09-11 03:11	46.06	OK	998	2026-09-11 03:12	48.05	OK
999	2026-09-11 03:13	47.76	OK	1000	2026-09-11 03:14	45.95	OK
1001	2026-09-11 03:15	48.48	OK	1002	2026-09-11 03:16	47.97	OK
1003	2026-09-11 03:17	47.31	OK	1004	2026-09-11 03:18	45.79	OK
1005	2026-09-11 03:19	48.29	OK	1006	2026-09-11 03:20	47.45	OK
1007	2026-09-11 03:21	47.33	OK	1008	2026-09-11 03:22	46.03	OK
1009	2026-09-11 03:23	47.71	OK	1010	2026-09-11 03:24	48.23	OK
1011	2026-09-11 03:25	46.86	OK	1012	2026-09-11 03:26	46.19	OK
1013	2026-09-11 03:27	45.33	OK	1014	2026-09-11 03:28	46.12	OK
1015	2026-09-11 03:29	46.85	OK	1016	2026-09-11 03:30	49.48	OK
1017	2026-09-11 03:31	47.44	OK	1018	2026-09-11 03:32	46.51	OK
1019	2026-09-11 03:33	46.98	OK	1020	2026-09-11 03:34	45.08	OK
1021	2026-09-11 03:35	48.30	OK	1022	2026-09-11 03:36	47.47	OK
1023	2026-09-11 03:37	47.41	OK	1024	2026-09-11 03:38	47.41	OK
1025	2026-09-11 03:39	48.89	OK	1026	2026-09-11 03:40	46.97	OK
1027	2026-09-11 03:41	47.61	OK	1028	2026-09-11 03:42	45.98	OK
1029	2026-09-11 03:43	47.51	OK	1030	2026-09-11 03:44	48.39	OK
1031	2026-09-11 03:45	47.46	OK	1032	2026-09-11 03:46	44.95	OK
1033	2026-09-11 03:47	48.48	OK	1034	2026-09-11 03:48	50.25	OK
1035	2026-09-11 03:49	47.61	OK	1036	2026-09-11 03:50	47.12	OK
1037	2026-09-11 03:51	47.13	OK	1038	2026-09-11 03:52	46.67	OK
1039	2026-09-11 03:53	49.08	OK	1040	2026-09-11 03:54	47.18	OK
1041	2026-09-11 03:55	47.52	OK	1042	2026-09-11 03:56	47.19	OK
1043	2026-09-11 03:57	46.81	OK	1044	2026-09-11 03:58	47.50	OK
1045	2026-09-11 03:59	47.62	OK	1046	2026-09-11 04:00	48.88	OK
1047	2026-09-11 04:01	48.93	OK	1048	2026-09-11 04:02	49.14	OK
1049	2026-09-11 04:03	47.84	OK	1050	2026-09-11 04:04	47.91	OK
1051	2026-09-11 04:05	47.18	OK	1052	2026-09-11 04:06	47.39	OK
1053	2026-09-11 04:07	46.69	OK	1054	2026-09-11 04:08	48.70	OK
1055	2026-09-11 04:09	48.46	OK	1056	2026-09-11 04:10	47.71	OK
1057	2026-09-11 04:11	46.06	OK	1058	2026-09-11 04:12	49.32	OK
1059	2026-09-11 04:13	48.02	OK	1060	2026-09-11 04:14	47.96	OK
1061	2026-09-11 04:15	50.02	OK	1062	2026-09-11 04:16	48.79	OK
1063	2026-09-11 04:17	48.80	OK	1064	2026-09-11 04:18	46.99	OK
1065	2026-09-11 04:19	49.66	OK	1066	2026-09-11 04:20	49.93	OK
1067	2026-09-11 04:21	50.18	OK	1068	2026-09-11 04:22	49.70	OK
1069	2026-09-11 04:23	47.17	OK	1070	2026-09-11 04:24	47.80	OK
1071	2026-09-11 04:25	49.02	OK	1072	2026-09-11 04:26	47.20	OK
1073	2026-09-11 04:27	50.64	OK	1074	2026-09-11 04:28	48.56	OK
1075	2026-09-11 04:29	47.59	OK	1076	2026-09-11 04:30	49.34	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1077	2026-09-11 04:31	49.17	OK	1078	2026-09-11 04:32	48.29	OK
1079	2026-09-11 04:33	46.48	OK	1080	2026-09-11 04:34	48.64	OK
1081	2026-09-11 04:35	48.86	OK	1082	2026-09-11 04:36	49.17	OK
1083	2026-09-11 04:37	48.70	OK	1084	2026-09-11 04:38	48.24	OK
1085	2026-09-11 04:39	48.96	OK	1086	2026-09-11 04:40	49.23	OK
1087	2026-09-11 04:41	49.75	OK	1088	2026-09-11 04:42	46.27	OK
1089	2026-09-11 04:43	49.51	OK	1090	2026-09-11 04:44	46.20	OK
1091	2026-09-11 04:45	49.74	OK	1092	2026-09-11 04:46	46.53	OK
1093	2026-09-11 04:47	49.40	OK	1094	2026-09-11 04:48	47.71	OK
1095	2026-09-11 04:49	47.97	OK	1096	2026-09-11 04:50	48.52	OK
1097	2026-09-11 04:51	47.20	OK	1098	2026-09-11 04:52	48.90	OK
1099	2026-09-11 04:53	46.47	OK	1100	2026-09-11 04:54	48.64	OK
1101	2026-09-11 04:55	49.28	OK	1102	2026-09-11 04:56	49.11	OK
1103	2026-09-11 04:57	48.29	OK	1104	2026-09-11 04:58	49.02	OK
1105	2026-09-11 04:59	49.54	OK	1106	2026-09-11 05:00	49.37	OK
1107	2026-09-11 05:01	47.67	OK	1108	2026-09-11 05:02	51.59	OK
1109	2026-09-11 05:03	49.05	OK	1110	2026-09-11 05:04	47.66	OK
1111	2026-09-11 05:05	49.05	OK	1112	2026-09-11 05:06	46.60	OK
1113	2026-09-11 05:07	50.49	OK	1114	2026-09-11 05:08	49.75	OK
1115	2026-09-11 05:09	49.57	OK	1116	2026-09-11 05:10	49.28	OK
1117	2026-09-11 05:11	48.72	OK	1118	2026-09-11 05:12	49.90	OK
1119	2026-09-11 05:13	50.12	OK	1120	2026-09-11 05:14	48.05	OK
1121	2026-09-11 05:15	48.65	OK	1122	2026-09-11 05:16	50.82	OK
1123	2026-09-11 05:17	47.01	OK	1124	2026-09-11 05:18	48.73	OK
1125	2026-09-11 05:19	48.95	OK	1126	2026-09-11 05:20	49.50	OK
1127	2026-09-11 05:21	49.06	OK	1128	2026-09-11 05:22	48.78	OK
1129	2026-09-11 05:23	49.59	OK	1130	2026-09-11 05:24	50.19	OK
1131	2026-09-11 05:25	48.03	OK	1132	2026-09-11 05:26	49.89	OK
1133	2026-09-11 05:27	48.78	OK	1134	2026-09-11 05:28	48.14	OK
1135	2026-09-11 05:29	48.88	OK	1136	2026-09-11 05:30	49.10	OK
1137	2026-09-11 05:31	49.92	OK	1138	2026-09-11 05:32	50.83	OK
1139	2026-09-11 05:33	49.51	OK	1140	2026-09-11 05:34	50.58	OK
1141	2026-09-11 05:35	50.30	OK	1142	2026-09-11 05:36	47.81	OK
1143	2026-09-11 05:37	49.22	OK	1144	2026-09-11 05:38	50.47	OK
1145	2026-09-11 05:39	48.38	OK	1146	2026-09-11 05:40	47.70	OK
1147	2026-09-11 05:41	48.24	OK	1148	2026-09-11 05:42	50.06	OK
1149	2026-09-11 05:43	49.72	OK	1150	2026-09-11 05:44	50.56	OK
1151	2026-09-11 05:45	50.19	OK	1152	2026-09-11 05:46	48.84	OK
1153	2026-09-11 05:47	49.25	OK	1154	2026-09-11 05:48	49.55	OK
1155	2026-09-11 05:49	48.68	OK	1156	2026-09-11 05:50	48.92	OK
1157	2026-09-11 05:51	47.48	OK	1158	2026-09-11 05:52	50.41	OK
1159	2026-09-11 05:53	47.83	OK	1160	2026-09-11 05:54	47.62	OK
1161	2026-09-11 05:55	50.47	OK	1162	2026-09-11 05:56	49.32	OK
1163	2026-09-11 05:57	51.06	OK	1164	2026-09-11 05:58	50.54	OK
1165	2026-09-11 05:59	49.20	OK	1166	2026-09-11 06:00	50.13	OK
1167	2026-09-11 06:01	52.51	OK	1168	2026-09-11 06:02	50.84	OK
1169	2026-09-11 06:03	49.59	OK	1170	2026-09-11 06:04	49.27	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1171	2026-09-11 06:05	50.78	OK	1172	2026-09-11 06:06	51.80	OK
1173	2026-09-11 06:07	51.31	OK	1174	2026-09-11 06:08	49.64	OK
1175	2026-09-11 06:09	52.05	OK	1176	2026-09-11 06:10	51.05	OK
1177	2026-09-11 06:11	52.14	OK	1178	2026-09-11 06:12	50.20	OK
1179	2026-09-11 06:13	51.63	OK	1180	2026-09-11 06:14	50.19	OK
1181	2026-09-11 06:15	50.35	OK	1182	2026-09-11 06:16	50.75	OK
1183	2026-09-11 06:17	52.84	OK	1184	2026-09-11 06:18	52.73	OK
1185	2026-09-11 06:19	50.46	OK	1186	2026-09-11 06:20	52.70	OK
1187	2026-09-11 06:21	51.38	OK	1188	2026-09-11 06:22	51.21	OK
1189	2026-09-11 06:23	51.87	OK	1190	2026-09-11 06:24	50.94	OK
1191	2026-09-11 06:25	47.82	OK	1192	2026-09-11 06:26	51.18	OK
1193	2026-09-11 06:27	51.38	OK	1194	2026-09-11 06:28	50.47	OK
1195	2026-09-11 06:29	51.46	OK	1196	2026-09-11 06:30	51.66	OK
1197	2026-09-11 06:31	53.04	OK	1198	2026-09-11 06:32	51.94	OK
1199	2026-09-11 06:33	50.47	OK	1200	2026-09-11 06:34	50.31	OK
1201	2026-09-11 06:35	50.98	OK	1202	2026-09-11 06:36	50.91	OK
1203	2026-09-11 06:37	51.49	OK	1204	2026-09-11 06:38	52.18	OK
1205	2026-09-11 06:39	52.11	OK	1206	2026-09-11 06:40	52.00	OK
1207	2026-09-11 06:41	49.18	OK	1208	2026-09-11 06:42	52.25	OK
1209	2026-09-11 06:43	50.66	OK	1210	2026-09-11 06:44	49.97	OK
1211	2026-09-11 06:45	52.91	OK	1212	2026-09-11 06:46	52.12	OK
1213	2026-09-11 06:47	52.17	OK	1214	2026-09-11 06:48	50.42	OK
1215	2026-09-11 06:49	50.53	OK	1216	2026-09-11 06:50	52.38	OK
1217	2026-09-11 06:51	50.16	OK	1218	2026-09-11 06:52	49.57	OK
1219	2026-09-11 06:53	50.44	OK	1220	2026-09-11 06:54	51.80	OK
1221	2026-09-11 06:55	50.64	OK	1222	2026-09-11 06:56	49.97	OK
1223	2026-09-11 06:57	52.80	OK	1224	2026-09-11 06:58	50.65	OK
1225	2026-09-11 06:59	51.76	OK	1226	2026-09-11 07:00	53.39	OK
1227	2026-09-11 07:01	52.25	OK	1228	2026-09-11 07:02	50.69	OK
1229	2026-09-11 07:03	52.83	OK	1230	2026-09-11 07:04	50.16	OK
1231	2026-09-11 07:05	53.38	OK	1232	2026-09-11 07:06	54.20	OK
1233	2026-09-11 07:07	53.07	OK	1234	2026-09-11 07:08	53.96	OK
1235	2026-09-11 07:09	48.89	OK	1236	2026-09-11 07:10	50.77	OK
1237	2026-09-11 07:11	51.38	OK	1238	2026-09-11 07:12	53.22	OK
1239	2026-09-11 07:13	51.58	OK	1240	2026-09-11 07:14	51.72	OK
1241	2026-09-11 07:15	51.38	OK	1242	2026-09-11 07:16	51.79	OK
1243	2026-09-11 07:17	51.53	OK	1244	2026-09-11 07:18	51.35	OK
1245	2026-09-11 07:19	51.57	OK	1246	2026-09-11 07:20	52.35	OK
1247	2026-09-11 07:21	51.14	OK	1248	2026-09-11 07:22	52.41	OK
1249	2026-09-11 07:23	52.34	OK	1250	2026-09-11 07:24	50.71	OK
1251	2026-09-11 07:25	52.21	OK	1252	2026-09-11 07:26	52.30	OK
1253	2026-09-11 07:27	51.00	OK	1254	2026-09-11 07:28	50.37	OK
1255	2026-09-11 07:29	53.59	OK	1256	2026-09-11 07:30	53.66	OK
1257	2026-09-11 07:31	53.65	OK	1258	2026-09-11 07:32	51.10	OK
1259	2026-09-11 07:33	53.78	OK	1260	2026-09-11 07:34	52.50	OK
1261	2026-09-11 07:35	52.59	OK	1262	2026-09-11 07:36	50.70	OK
1263	2026-09-11 07:37	53.56	OK	1264	2026-09-11 07:38	51.70	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1265	2026-09-11 07:39	54.35	OK	1266	2026-09-11 07:40	50.84	OK
1267	2026-09-11 07:41	50.46	OK	1268	2026-09-11 07:42	52.02	OK
1269	2026-09-11 07:43	49.85	OK	1270	2026-09-11 07:44	51.87	OK
1271	2026-09-11 07:45	51.29	OK	1272	2026-09-11 07:46	52.06	OK
1273	2026-09-11 07:47	52.34	OK	1274	2026-09-11 07:48	52.13	OK
1275	2026-09-11 07:49	51.30	OK	1276	2026-09-11 07:50	50.37	OK
1277	2026-09-11 07:51	53.28	OK	1278	2026-09-11 07:52	51.35	OK
1279	2026-09-11 07:53	52.88	OK	1280	2026-09-11 07:54	54.46	OK
1281	2026-09-11 07:55	52.67	OK	1282	2026-09-11 07:56	51.40	OK
1283	2026-09-11 07:57	51.15	OK	1284	2026-09-11 07:58	52.85	OK
1285	2026-09-11 07:59	53.04	OK	1286	2026-09-11 08:00	50.70	OK
1287	2026-09-11 08:01	52.72	OK	1288	2026-09-11 08:02	50.79	OK
1289	2026-09-11 08:03	52.61	OK	1290	2026-09-11 08:04	51.98	OK
1291	2026-09-11 08:05	54.06	OK	1292	2026-09-11 08:06	52.30	OK
1293	2026-09-11 08:07	51.70	OK	1294	2026-09-11 08:08	53.02	OK
1295	2026-09-11 08:09	51.63	OK	1296	2026-09-11 08:10	51.69	OK
1297	2026-09-11 08:11	52.32	OK	1298	2026-09-11 08:12	53.87	OK
1299	2026-09-11 08:13	51.62	OK	1300	2026-09-11 08:14	51.40	OK
1301	2026-09-11 08:15	53.57	OK	1302	2026-09-11 08:16	52.40	OK
1303	2026-09-11 08:17	51.46	OK	1304	2026-09-11 08:18	54.32	OK
1305	2026-09-11 08:19	51.81	OK	1306	2026-09-11 08:20	52.69	OK
1307	2026-09-11 08:21	52.87	OK	1308	2026-09-11 08:22	55.29	OK
1309	2026-09-11 08:23	51.27	OK	1310	2026-09-11 08:24	51.82	OK
1311	2026-09-11 08:25	52.66	OK	1312	2026-09-11 08:26	52.85	OK
1313	2026-09-11 08:27	53.50	OK	1314	2026-09-11 08:28	54.76	OK
1315	2026-09-11 08:29	53.51	OK	1316	2026-09-11 08:30	53.49	OK
1317	2026-09-11 08:31	52.75	OK	1318	2026-09-11 08:32	54.16	OK
1319	2026-09-11 08:33	51.94	OK	1320	2026-09-11 08:34	51.25	OK
1321	2026-09-11 08:35	52.82	OK	1322	2026-09-11 08:36	53.62	OK
1323	2026-09-11 08:37	52.12	OK	1324	2026-09-11 08:38	52.12	OK
1325	2026-09-11 08:39	51.87	OK	1326	2026-09-11 08:40	53.73	OK
1327	2026-09-11 08:41	53.92	OK	1328	2026-09-11 08:42	52.86	OK
1329	2026-09-11 08:43	51.89	OK	1330	2026-09-11 08:44	54.42	OK
1331	2026-09-11 08:45	52.56	OK	1332	2026-09-11 08:46	52.67	OK
1333	2026-09-11 08:47	51.83	OK	1334	2026-09-11 08:48	52.17	OK
1335	2026-09-11 08:49	52.71	OK	1336	2026-09-11 08:50	51.52	OK
1337	2026-09-11 08:51	52.21	OK	1338	2026-09-11 08:52	52.58	OK
1339	2026-09-11 08:53	52.94	OK	1340	2026-09-11 08:54	52.71	OK
1341	2026-09-11 08:55	52.52	OK	1342	2026-09-11 08:56	55.40	OK
1343	2026-09-11 08:57	53.98	OK	1344	2026-09-11 08:58	53.35	OK
1345	2026-09-11 08:59	51.61	OK	1346	2026-09-11 09:00	52.90	OK
1347	2026-09-11 09:01	52.88	OK	1348	2026-09-11 09:02	52.19	OK
1349	2026-09-11 09:03	53.04	OK	1350	2026-09-11 09:04	55.16	OK
1351	2026-09-11 09:05	53.03	OK	1352	2026-09-11 09:06	54.52	OK
1353	2026-09-11 09:07	52.63	OK	1354	2026-09-11 09:08	51.92	OK
1355	2026-09-11 09:09	51.56	OK	1356	2026-09-11 09:10	52.00	OK
1357	2026-09-11 09:11	52.37	OK	1358	2026-09-11 09:12	53.78	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1359	2026-09-11 09:13	54.00	OK	1360	2026-09-11 09:14	51.82	OK
1361	2026-09-11 09:15	54.66	OK	1362	2026-09-11 09:16	54.19	OK
1363	2026-09-11 09:17	54.79	OK	1364	2026-09-11 09:18	53.38	OK
1365	2026-09-11 09:19	53.58	OK	1366	2026-09-11 09:20	54.54	OK
1367	2026-09-11 09:21	52.85	OK	1368	2026-09-11 09:22	52.93	OK
1369	2026-09-11 09:23	54.17	OK	1370	2026-09-11 09:24	53.99	OK
1371	2026-09-11 09:25	55.09	OK	1372	2026-09-11 09:26	55.30	OK
1373	2026-09-11 09:27	50.80	OK	1374	2026-09-11 09:28	52.79	OK
1375	2026-09-11 09:29	52.59	OK	1376	2026-09-11 09:30	55.25	OK
1377	2026-09-11 09:31	55.60	OK	1378	2026-09-11 09:32	53.35	OK
1379	2026-09-11 09:33	54.65	OK	1380	2026-09-11 09:34	54.47	OK
1381	2026-09-11 09:35	52.95	OK	1382	2026-09-11 09:36	54.46	OK
1383	2026-09-11 09:37	54.07	OK	1384	2026-09-11 09:38	53.26	OK
1385	2026-09-11 09:39	51.93	OK	1386	2026-09-11 09:40	53.38	OK
1387	2026-09-11 09:41	53.51	OK	1388	2026-09-11 09:42	53.87	OK
1389	2026-09-11 09:43	53.82	OK	1390	2026-09-11 09:44	53.98	OK
1391	2026-09-11 09:45	54.23	OK	1392	2026-09-11 09:46	55.89	OK
1393	2026-09-11 09:47	54.02	OK	1394	2026-09-11 09:48	56.21	OK
1395	2026-09-11 09:49	52.90	OK	1396	2026-09-11 09:50	54.38	OK
1397	2026-09-11 09:51	53.58	OK	1398	2026-09-11 09:52	54.38	OK
1399	2026-09-11 09:53	55.65	OK	1400	2026-09-11 09:54	54.68	OK
1401	2026-09-11 09:55	53.89	OK	1402	2026-09-11 09:56	53.13	OK
1403	2026-09-11 09:57	53.72	OK	1404	2026-09-11 09:58	52.93	OK
1405	2026-09-11 09:59	52.20	OK	1406	2026-09-11 10:00	52.88	OK
1407	2026-09-11 10:01	55.54	OK	1408	2026-09-11 10:02	52.99	OK
1409	2026-09-11 10:03	52.22	OK	1410	2026-09-11 10:04	52.44	OK
1411	2026-09-11 10:05	52.07	OK	1412	2026-09-11 10:06	53.19	OK
1413	2026-09-11 10:07	54.46	OK	1414	2026-09-11 10:08	54.26	OK
1415	2026-09-11 10:09	53.94	OK	1416	2026-09-11 10:10	54.44	OK
1417	2026-09-11 10:11	54.79	OK	1418	2026-09-11 10:12	54.50	OK
1419	2026-09-11 10:13	53.54	OK	1420	2026-09-11 10:14	54.31	OK
1421	2026-09-11 10:15	52.95	OK	1422	2026-09-11 10:16	53.45	OK
1423	2026-09-11 10:17	56.33	OK	1424	2026-09-11 10:18	54.75	OK
1425	2026-09-11 10:19	52.73	OK	1426	2026-09-11 10:20	53.30	OK
1427	2026-09-11 10:21	54.44	OK	1428	2026-09-11 10:22	53.87	OK
1429	2026-09-11 10:23	53.42	OK	1430	2026-09-11 10:24	53.79	OK
1431	2026-09-11 10:25	54.14	OK	1432	2026-09-11 10:26	55.37	OK
1433	2026-09-11 10:27	54.25	OK	1434	2026-09-11 10:28	53.27	OK
1435	2026-09-11 10:29	55.11	OK	1436	2026-09-11 10:30	53.42	OK
1437	2026-09-11 10:31	53.24	OK	1438	2026-09-11 10:32	53.18	OK
1439	2026-09-11 10:33	53.99	OK	1440	2026-09-11 10:34	55.47	OK
1441	2026-09-11 10:35	53.82	OK	1442	2026-09-11 10:36	54.79	OK
1443	2026-09-11 10:37	55.87	OK	1444	2026-09-11 10:38	55.53	OK
1445	2026-09-11 10:39	55.16	OK	1446	2026-09-11 10:40	53.33	OK
1447	2026-09-11 10:41	55.06	OK	1448	2026-09-11 10:42	53.67	OK
1449	2026-09-11 10:43	54.44	OK	1450	2026-09-11 10:44	54.71	OK
1451	2026-09-11 10:45	54.46	OK	1452	2026-09-11 10:46	54.11	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1453	2026-09-11 10:47	54.13	OK	1454	2026-09-11 10:48	53.93	OK
1455	2026-09-11 10:49	53.24	OK	1456	2026-09-11 10:50	54.36	OK
1457	2026-09-11 10:51	54.29	OK	1458	2026-09-11 10:52	54.29	OK
1459	2026-09-11 10:53	56.06	OK	1460	2026-09-11 10:54	54.37	OK
1461	2026-09-11 10:55	53.61	OK	1462	2026-09-11 10:56	53.87	OK
1463	2026-09-11 10:57	54.49	OK	1464	2026-09-11 10:58	53.72	OK
1465	2026-09-11 10:59	55.65	OK	1466	2026-09-11 11:00	51.69	OK
1467	2026-09-11 11:01	55.69	OK	1468	2026-09-11 11:02	54.70	OK
1469	2026-09-11 11:03	53.61	OK	1470	2026-09-11 11:04	53.15	OK
1471	2026-09-11 11:05	52.61	OK	1472	2026-09-11 11:06	53.92	OK
1473	2026-09-11 11:07	54.59	OK	1474	2026-09-11 11:08	52.66	OK
1475	2026-09-11 11:09	52.98	OK	1476	2026-09-11 11:10	56.02	OK
1477	2026-09-11 11:11	54.47	OK	1478	2026-09-11 11:12	52.63	OK
1479	2026-09-11 11:13	55.13	OK	1480	2026-09-11 11:14	53.51	OK
1481	2026-09-11 11:15	53.26	OK	1482	2026-09-11 11:16	55.99	OK
1483	2026-09-11 11:17	52.95	OK	1484	2026-09-11 11:18	54.04	OK
1485	2026-09-11 11:19	55.16	OK	1486	2026-09-11 11:20	55.36	OK
1487	2026-09-11 11:21	56.11	OK	1488	2026-09-11 11:22	54.15	OK
1489	2026-09-11 11:23	53.47	OK	1490	2026-09-11 11:24	52.09	OK
1491	2026-09-11 11:25	54.05	OK	1492	2026-09-11 11:26	54.18	OK
1493	2026-09-11 11:27	54.79	OK	1494	2026-09-11 11:28	53.47	OK
1495	2026-09-11 11:29	54.70	OK	1496	2026-09-11 11:30	52.61	OK
1497	2026-09-11 11:31	53.40	OK	1498	2026-09-11 11:32	54.67	OK
1499	2026-09-11 11:33	55.99	OK	1500	2026-09-11 11:34	52.52	OK
1501	2026-09-11 11:35	54.96	OK	1502	2026-09-11 11:36	52.61	OK
1503	2026-09-11 11:37	53.54	OK	1504	2026-09-11 11:38	55.84	OK
1505	2026-09-11 11:39	55.20	OK	1506	2026-09-11 11:40	53.71	OK
1507	2026-09-11 11:41	54.41	OK	1508	2026-09-11 11:42	53.28	OK
1509	2026-09-11 11:43	54.87	OK	1510	2026-09-11 11:44	54.79	OK
1511	2026-09-11 11:45	54.63	OK	1512	2026-09-11 11:46	54.42	OK
1513	2026-09-11 11:47	53.56	OK	1514	2026-09-11 11:48	54.05	OK
1515	2026-09-11 11:49	53.83	OK	1516	2026-09-11 11:50	53.11	OK
1517	2026-09-11 11:51	53.09	OK	1518	2026-09-11 11:52	52.48	OK
1519	2026-09-11 11:53	54.58	OK	1520	2026-09-11 11:54	53.70	OK
1521	2026-09-11 11:55	54.69	OK	1522	2026-09-11 11:56	54.18	OK
1523	2026-09-11 11:57	55.39	OK	1524	2026-09-11 11:58	56.22	OK
1525	2026-09-11 11:59	54.43	OK	1526	2026-09-11 12:00	52.57	OK
1527	2026-09-11 12:01	55.55	OK	1528	2026-09-11 12:02	55.46	OK
1529	2026-09-11 12:03	52.91	OK	1530	2026-09-11 12:04	54.75	OK
1531	2026-09-11 12:05	55.79	OK	1532	2026-09-11 12:06	55.74	OK
1533	2026-09-11 12:07	53.86	OK	1534	2026-09-11 12:08	54.24	OK
1535	2026-09-11 12:09	54.56	OK	1536	2026-09-11 12:10	52.82	OK
1537	2026-09-11 12:11	54.78	OK	1538	2026-09-11 12:12	54.82	OK
1539	2026-09-11 12:13	53.26	OK	1540	2026-09-11 12:14	54.15	OK
1541	2026-09-11 12:15	53.60	OK	1542	2026-09-11 12:16	52.92	OK
1543	2026-09-11 12:17	53.47	OK	1544	2026-09-11 12:18	53.55	OK
1545	2026-09-11 12:19	54.37	OK	1546	2026-09-11 12:20	54.26	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1547	2026-09-11 12:21	53.53	OK	1548	2026-09-11 12:22	52.90	OK
1549	2026-09-11 12:23	55.60	OK	1550	2026-09-11 12:24	54.35	OK
1551	2026-09-11 12:25	53.84	OK	1552	2026-09-11 12:26	53.21	OK
1553	2026-09-11 12:27	55.68	OK	1554	2026-09-11 12:28	54.53	OK
1555	2026-09-11 12:29	54.96	OK	1556	2026-09-11 12:30	52.20	OK
1557	2026-09-11 12:31	54.18	OK	1558	2026-09-11 12:32	53.83	OK
1559	2026-09-11 12:33	53.62	OK	1560	2026-09-11 12:34	52.95	OK
1561	2026-09-11 12:35	53.16	OK	1562	2026-09-11 12:36	53.19	OK
1563	2026-09-11 12:37	56.18	OK	1564	2026-09-11 12:38	55.25	OK
1565	2026-09-11 12:39	55.44	OK	1566	2026-09-11 12:40	56.06	OK
1567	2026-09-11 12:41	52.68	OK	1568	2026-09-11 12:42	55.73	OK
1569	2026-09-11 12:43	54.68	OK	1570	2026-09-11 12:44	53.88	OK
1571	2026-09-11 12:45	54.21	OK	1572	2026-09-11 12:46	52.81	OK
1573	2026-09-11 12:47	54.05	OK	1574	2026-09-11 12:48	54.99	OK
1575	2026-09-11 12:49	55.58	OK	1576	2026-09-11 12:50	55.70	OK
1577	2026-09-11 12:51	54.04	OK	1578	2026-09-11 12:52	54.83	OK
1579	2026-09-11 12:53	52.85	OK	1580	2026-09-11 12:54	53.80	OK
1581	2026-09-11 12:55	54.64	OK	1582	2026-09-11 12:56	53.51	OK
1583	2026-09-11 12:57	53.85	OK	1584	2026-09-11 12:58	54.59	OK
1585	2026-09-11 12:59	54.54	OK	1586	2026-09-11 13:00	53.54	OK
1587	2026-09-11 13:01	51.67	OK	1588	2026-09-11 13:02	53.42	OK
1589	2026-09-11 13:03	56.21	OK	1590	2026-09-11 13:04	53.97	OK
1591	2026-09-11 13:05	52.73	OK	1592	2026-09-11 13:06	54.93	OK
1593	2026-09-11 13:07	54.16	OK	1594	2026-09-11 13:08	51.58	OK
1595	2026-09-11 13:09	53.90	OK	1596	2026-09-11 13:10	55.72	OK
1597	2026-09-11 13:11	54.10	OK	1598	2026-09-11 13:12	55.01	OK
1599	2026-09-11 13:13	52.02	OK	1600	2026-09-11 13:14	54.25	OK
1601	2026-09-11 13:15	54.71	OK	1602	2026-09-11 13:16	54.15	OK
1603	2026-09-11 13:17	54.47	OK	1604	2026-09-11 13:18	54.45	OK
1605	2026-09-11 13:19	53.49	OK	1606	2026-09-11 13:20	52.26	OK
1607	2026-09-11 13:21	54.52	OK	1608	2026-09-11 13:22	54.91	OK
1609	2026-09-11 13:23	53.90	OK	1610	2026-09-11 13:24	53.97	OK
1611	2026-09-11 13:25	53.89	OK	1612	2026-09-11 13:26	53.58	OK
1613	2026-09-11 13:27	53.06	OK	1614	2026-09-11 13:28	53.52	OK
1615	2026-09-11 13:29	54.21	OK	1616	2026-09-11 13:30	56.44	OK
1617	2026-09-11 13:31	53.87	OK	1618	2026-09-11 13:32	53.81	OK
1619	2026-09-11 13:33	55.86	OK	1620	2026-09-11 13:34	52.17	OK
1621	2026-09-11 13:35	54.64	OK	1622	2026-09-11 13:36	53.46	OK
1623	2026-09-11 13:37	52.53	OK	1624	2026-09-11 13:38	53.12	OK
1625	2026-09-11 13:39	52.70	OK	1626	2026-09-11 13:40	53.42	OK
1627	2026-09-11 13:41	53.27	OK	1628	2026-09-11 13:42	54.07	OK
1629	2026-09-11 13:43	55.12	OK	1630	2026-09-11 13:44	54.57	OK
1631	2026-09-11 13:45	53.72	OK	1632	2026-09-11 13:46	51.48	OK
1633	2026-09-11 13:47	52.50	OK	1634	2026-09-11 13:48	54.19	OK
1635	2026-09-11 13:49	53.10	OK	1636	2026-09-11 13:50	53.43	OK
1637	2026-09-11 13:51	54.59	OK	1638	2026-09-11 13:52	54.56	OK
1639	2026-09-11 13:53	53.72	OK	1640	2026-09-11 13:54	52.41	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1641	2026-09-11 13:55	54.72	OK	1642	2026-09-11 13:56	53.15	OK
1643	2026-09-11 13:57	53.35	OK	1644	2026-09-11 13:58	53.87	OK
1645	2026-09-11 13:59	53.59	OK	1646	2026-09-11 14:00	53.19	OK
1647	2026-09-11 14:01	52.73	OK	1648	2026-09-11 14:02	54.22	OK
1649	2026-09-11 14:03	52.87	OK	1650	2026-09-11 14:04	53.31	OK
1651	2026-09-11 14:05	51.34	OK	1652	2026-09-11 14:06	53.58	OK
1653	2026-09-11 14:07	51.53	OK	1654	2026-09-11 14:08	51.43	OK
1655	2026-09-11 14:09	52.58	OK	1656	2026-09-11 14:10	54.28	OK
1657	2026-09-11 14:11	51.73	OK	1658	2026-09-11 14:12	52.76	OK
1659	2026-09-11 14:13	52.46	OK	1660	2026-09-11 14:14	52.93	OK
1661	2026-09-11 14:15	52.66	OK	1662	2026-09-11 14:16	52.89	OK
1663	2026-09-11 14:17	53.45	OK	1664	2026-09-11 14:18	52.96	OK
1665	2026-09-11 14:19	54.76	OK	1666	2026-09-11 14:20	50.96	OK
1667	2026-09-11 14:21	51.25	OK	1668	2026-09-11 14:22	52.70	OK
1669	2026-09-11 14:23	52.40	OK	1670	2026-09-11 14:24	51.95	OK
1671	2026-09-11 14:25	50.99	OK	1672	2026-09-11 14:26	53.20	OK
1673	2026-09-11 14:27	53.86	OK	1674	2026-09-11 14:28	52.89	OK
1675	2026-09-11 14:29	51.96	OK	1676	2026-09-11 14:30	53.19	OK
1677	2026-09-11 14:31	52.23	OK	1678	2026-09-11 14:32	53.09	OK
1679	2026-09-11 14:33	53.84	OK	1680	2026-09-11 14:34	51.22	OK
1681	2026-09-11 14:35	51.82	OK	1682	2026-09-11 14:36	53.54	OK
1683	2026-09-11 14:37	52.99	OK	1684	2026-09-11 14:38	51.81	OK
1685	2026-09-11 14:39	53.47	OK	1686	2026-09-11 14:40	53.93	OK
1687	2026-09-11 14:41	51.57	OK	1688	2026-09-11 14:42	52.68	OK
1689	2026-09-11 14:43	52.73	OK	1690	2026-09-11 14:44	52.88	OK
1691	2026-09-11 14:45	53.92	OK	1692	2026-09-11 14:46	52.82	OK
1693	2026-09-11 14:47	52.46	OK	1694	2026-09-11 14:48	50.96	OK
1695	2026-09-11 14:49	52.31	OK	1696	2026-09-11 14:50	51.32	OK
1697	2026-09-11 14:51	52.22	OK	1698	2026-09-11 14:52	52.78	OK
1699	2026-09-11 14:53	53.12	OK	1700	2026-09-11 14:54	51.61	OK
1701	2026-09-11 14:55	51.11	OK	1702	2026-09-11 14:56	51.08	OK
1703	2026-09-11 14:57	51.87	OK	1704	2026-09-11 14:58	52.46	OK
1705	2026-09-11 14:59	51.53	OK	1706	2026-09-11 15:00	53.77	OK
1707	2026-09-11 15:01	51.67	OK	1708	2026-09-11 15:02	50.50	OK
1709	2026-09-11 15:03	52.73	OK	1710	2026-09-11 15:04	51.61	OK
1711	2026-09-11 15:05	50.75	OK	1712	2026-09-11 15:06	51.76	OK
1713	2026-09-11 15:07	53.00	OK	1714	2026-09-11 15:08	53.45	OK
1715	2026-09-11 15:09	52.87	OK	1716	2026-09-11 15:10	54.10	OK
1717	2026-09-11 15:11	51.84	OK	1718	2026-09-11 15:12	49.91	OK
1719	2026-09-11 15:13	52.53	OK	1720	2026-09-11 15:14	51.42	OK
1721	2026-09-11 15:15	50.69	OK	1722	2026-09-11 15:16	53.44	OK
1723	2026-09-11 15:17	51.50	OK	1724	2026-09-11 15:18	52.43	OK
1725	2026-09-11 15:19	50.92	OK	1726	2026-09-11 15:20	52.72	OK
1727	2026-09-11 15:21	52.20	OK	1728	2026-09-11 15:22	53.14	OK
1729	2026-09-11 15:23	51.67	OK	1730	2026-09-11 15:24	51.39	OK
1731	2026-09-11 15:25	54.05	OK	1732	2026-09-11 15:26	51.35	OK
1733	2026-09-11 15:27	52.85	OK	1734	2026-09-11 15:28	52.21	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1735	2026-09-11 15:29	51.65	OK	1736	2026-09-11 15:30	52.12	OK
1737	2026-09-11 15:31	50.66	OK	1738	2026-09-11 15:32	51.32	OK
1739	2026-09-11 15:33	51.21	OK	1740	2026-09-11 15:34	52.49	OK
1741	2026-09-11 15:35	52.61	OK	1742	2026-09-11 15:36	52.37	OK
1743	2026-09-11 15:37	51.19	OK	1744	2026-09-11 15:38	52.99	OK
1745	2026-09-11 15:39	54.55	OK	1746	2026-09-11 15:40	51.55	OK
1747	2026-09-11 15:41	52.63	OK	1748	2026-09-11 15:42	51.94	OK
1749	2026-09-11 15:43	53.13	OK	1750	2026-09-11 15:44	50.51	OK
1751	2026-09-11 15:45	51.23	OK	1752	2026-09-11 15:46	52.26	OK
1753	2026-09-11 15:47	50.86	OK	1754	2026-09-11 15:48	50.92	OK
1755	2026-09-11 15:49	51.43	OK	1756	2026-09-11 15:50	53.94	OK
1757	2026-09-11 15:51	52.33	OK	1758	2026-09-11 15:52	51.33	OK
1759	2026-09-11 15:53	52.98	OK	1760	2026-09-11 15:54	51.19	OK
1761	2026-09-11 15:55	49.28	OK	1762	2026-09-11 15:56	49.72	OK
1763	2026-09-11 15:57	49.21	OK	1764	2026-09-11 15:58	50.76	OK
1765	2026-09-11 15:59	51.66	OK	1766	2026-09-11 16:00	50.94	OK
1767	2026-09-11 16:01	51.18	OK	1768	2026-09-11 16:02	50.09	OK
1769	2026-09-11 16:03	49.08	OK	1770	2026-09-11 16:04	50.08	OK
1771	2026-09-11 16:05	50.52	OK	1772	2026-09-11 16:06	50.48	OK
1773	2026-09-11 16:07	50.46	OK	1774	2026-09-11 16:08	50.68	OK
1775	2026-09-11 16:09	51.59	OK	1776	2026-09-11 16:10	51.72	OK
1777	2026-09-11 16:11	50.71	OK	1778	2026-09-11 16:12	50.40	OK
1779	2026-09-11 16:13	52.12	OK	1780	2026-09-11 16:14	51.22	OK
1781	2026-09-11 16:15	51.02	OK	1782	2026-09-11 16:16	50.61	OK
1783	2026-09-11 16:17	52.17	OK	1784	2026-09-11 16:18	49.09	OK
1785	2026-09-11 16:19	51.42	OK	1786	2026-09-11 16:20	51.72	OK
1787	2026-09-11 16:21	50.32	OK	1788	2026-09-11 16:22	49.55	OK
1789	2026-09-11 16:23	51.08	OK	1790	2026-09-11 16:24	51.78	OK
1791	2026-09-11 16:25	51.68	OK	1792	2026-09-11 16:26	51.58	OK
1793	2026-09-11 16:27	50.69	OK	1794	2026-09-11 16:28	51.58	OK
1795	2026-09-11 16:29	50.01	OK	1796	2026-09-11 16:30	49.60	OK
1797	2026-09-11 16:31	52.41	OK	1798	2026-09-11 16:32	50.64	OK
1799	2026-09-11 16:33	50.76	OK	1800	2026-09-11 16:34	50.29	OK
1801	2026-09-11 16:35	49.36	OK	1802	2026-09-11 16:36	49.96	OK
1803	2026-09-11 16:37	49.13	OK	1804	2026-09-11 16:38	52.15	OK
1805	2026-09-11 16:39	49.97	OK	1806	2026-09-11 16:40	51.88	OK
1807	2026-09-11 16:41	50.98	OK	1808	2026-09-11 16:42	49.03	OK
1809	2026-09-11 16:43	48.73	OK	1810	2026-09-11 16:44	48.86	OK
1811	2026-09-11 16:45	50.30	OK	1812	2026-09-11 16:46	50.36	OK
1813	2026-09-11 16:47	48.43	OK	1814	2026-09-11 16:48	51.26	OK
1815	2026-09-11 16:49	49.98	OK	1816	2026-09-11 16:50	52.01	OK
1817	2026-09-11 16:51	51.00	OK	1818	2026-09-11 16:52	50.75	OK
1819	2026-09-11 16:53	51.76	OK	1820	2026-09-11 16:54	51.46	OK
1821	2026-09-11 16:55	49.66	OK	1822	2026-09-11 16:56	51.19	OK
1823	2026-09-11 16:57	49.79	OK	1824	2026-09-11 16:58	50.10	OK
1825	2026-09-11 16:59	50.03	OK	1826	2026-09-11 17:00	49.20	OK
1827	2026-09-11 17:01	51.56	OK	1828	2026-09-11 17:02	49.23	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1829	2026-09-11 17:03	50.84	OK	1830	2026-09-11 17:04	49.22	OK
1831	2026-09-11 17:05	52.04	OK	1832	2026-09-11 17:06	48.27	OK
1833	2026-09-11 17:07	48.42	OK	1834	2026-09-11 17:08	49.98	OK
1835	2026-09-11 17:09	49.97	OK	1836	2026-09-11 17:10	49.05	OK
1837	2026-09-11 17:11	49.42	OK	1838	2026-09-11 17:12	47.61	OK
1839	2026-09-11 17:13	49.19	OK	1840	2026-09-11 17:14	50.08	OK
1841	2026-09-11 17:15	51.00	OK	1842	2026-09-11 17:16	50.80	OK
1843	2026-09-11 17:17	50.58	OK	1844	2026-09-11 17:18	47.56	OK
1845	2026-09-11 17:19	49.03	OK	1846	2026-09-11 17:20	50.70	OK
1847	2026-09-11 17:21	51.91	OK	1848	2026-09-11 17:22	49.89	OK
1849	2026-09-11 17:23	49.88	OK	1850	2026-09-11 17:24	48.63	OK
1851	2026-09-11 17:25	48.25	OK	1852	2026-09-11 17:26	49.52	OK
1853	2026-09-11 17:27	52.11	OK	1854	2026-09-11 17:28	50.18	OK
1855	2026-09-11 17:29	49.71	OK	1856	2026-09-11 17:30	49.77	OK
1857	2026-09-11 17:31	49.99	OK	1858	2026-09-11 17:32	51.64	OK
1859	2026-09-11 17:33	48.81	OK	1860	2026-09-11 17:34	48.10	OK
1861	2026-09-11 17:35	49.11	OK	1862	2026-09-11 17:36	49.27	OK
1863	2026-09-11 17:37	49.43	OK	1864	2026-09-11 17:38	49.87	OK
1865	2026-09-11 17:39	49.19	OK	1866	2026-09-11 17:40	49.33	OK
1867	2026-09-11 17:41	48.22	OK	1868	2026-09-11 17:42	49.64	OK
1869	2026-09-11 17:43	50.58	OK	1870	2026-09-11 17:44	48.38	OK
1871	2026-09-11 17:45	49.57	OK	1872	2026-09-11 17:46	48.85	OK
1873	2026-09-11 17:47	49.20	OK	1874	2026-09-11 17:48	50.03	OK
1875	2026-09-11 17:49	50.45	OK	1876	2026-09-11 17:50	48.40	OK
1877	2026-09-11 17:51	48.66	OK	1878	2026-09-11 17:52	51.68	OK
1879	2026-09-11 17:53	49.07	OK	1880	2026-09-11 17:54	49.10	OK
1881	2026-09-11 17:55	49.63	OK	1882	2026-09-11 17:56	48.32	OK
1883	2026-09-11 17:57	48.61	OK	1884	2026-09-11 17:58	48.41	OK
1885	2026-09-11 17:59	49.86	OK	1886	2026-09-11 18:00	47.03	OK
1887	2026-09-11 18:01	49.90	OK	1888	2026-09-11 18:02	49.85	OK
1889	2026-09-11 18:03	50.28	OK	1890	2026-09-11 18:04	51.49	OK
1891	2026-09-11 18:05	48.25	OK	1892	2026-09-11 18:06	49.24	OK
1893	2026-09-11 18:07	46.28	OK	1894	2026-09-11 18:08	49.40	OK
1895	2026-09-11 18:09	48.22	OK	1896	2026-09-11 18:10	49.78	OK
1897	2026-09-11 18:11	50.36	OK	1898	2026-09-11 18:12	47.55	OK
1899	2026-09-11 18:13	47.43	OK	1900	2026-09-11 18:14	48.23	OK
1901	2026-09-11 18:15	48.39	OK	1902	2026-09-11 18:16	48.49	OK
1903	2026-09-11 18:17	47.89	OK	1904	2026-09-11 18:18	49.49	OK
1905	2026-09-11 18:19	46.12	OK	1906	2026-09-11 18:20	47.80	OK
1907	2026-09-11 18:21	47.89	OK	1908	2026-09-11 18:22	49.40	OK
1909	2026-09-11 18:23	47.33	OK	1910	2026-09-11 18:24	49.02	OK
1911	2026-09-11 18:25	48.33	OK	1912	2026-09-11 18:26	48.78	OK
1913	2026-09-11 18:27	46.83	OK	1914	2026-09-11 18:28	47.59	OK
1915	2026-09-11 18:29	46.94	OK	1916	2026-09-11 18:30	49.58	OK
1917	2026-09-11 18:31	50.12	OK	1918	2026-09-11 18:32	48.89	OK
1919	2026-09-11 18:33	46.10	OK	1920	2026-09-11 18:34	48.69	OK
1921	2026-09-11 18:35	47.52	OK	1922	2026-09-11 18:36	49.64	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1923	2026-09-11 18:37	46.99	OK	1924	2026-09-11 18:38	46.94	OK
1925	2026-09-11 18:39	46.89	OK	1926	2026-09-11 18:40	48.56	OK
1927	2026-09-11 18:41	48.72	OK	1928	2026-09-11 18:42	47.70	OK
1929	2026-09-11 18:43	47.65	OK	1930	2026-09-11 18:44	46.15	OK
1931	2026-09-11 18:45	48.33	OK	1932	2026-09-11 18:46	47.77	OK
1933	2026-09-11 18:47	47.44	OK	1934	2026-09-11 18:48	47.51	OK
1935	2026-09-11 18:49	46.55	OK	1936	2026-09-11 18:50	47.96	OK
1937	2026-09-11 18:51	48.85	OK	1938	2026-09-11 18:52	48.28	OK
1939	2026-09-11 18:53	48.21	OK	1940	2026-09-11 18:54	48.27	OK
1941	2026-09-11 18:55	48.31	OK	1942	2026-09-11 18:56	48.50	OK
1943	2026-09-11 18:57	48.36	OK	1944	2026-09-11 18:58	48.40	OK
1945	2026-09-11 18:59	45.88	OK	1946	2026-09-11 19:00	49.47	OK
1947	2026-09-11 19:01	47.59	OK	1948	2026-09-11 19:02	47.35	OK
1949	2026-09-11 19:03	48.65	OK	1950	2026-09-11 19:04	47.85	OK
1951	2026-09-11 19:05	46.25	OK	1952	2026-09-11 19:06	48.08	OK
1953	2026-09-11 19:07	47.78	OK	1954	2026-09-11 19:08	48.54	OK
1955	2026-09-11 19:09	47.15	OK	1956	2026-09-11 19:10	47.67	OK
1957	2026-09-11 19:11	45.72	OK	1958	2026-09-11 19:12	46.92	OK
1959	2026-09-11 19:13	46.91	OK	1960	2026-09-11 19:14	47.86	OK
1961	2026-09-11 19:15	47.55	OK	1962	2026-09-11 19:16	47.40	OK
1963	2026-09-11 19:17	49.12	OK	1964	2026-09-11 19:18	48.25	OK
1965	2026-09-11 19:19	48.54	OK	1966	2026-09-11 19:20	47.08	OK
1967	2026-09-11 19:21	47.10	OK	1968	2026-09-11 19:22	46.84	OK
1969	2026-09-11 19:23	48.42	OK	1970	2026-09-11 19:24	45.36	OK
1971	2026-09-11 19:25	47.03	OK	1972	2026-09-11 19:26	46.27	OK
1973	2026-09-11 19:27	46.58	OK	1974	2026-09-11 19:28	48.09	OK
1975	2026-09-11 19:29	46.45	OK	1976	2026-09-11 19:30	48.89	OK
1977	2026-09-11 19:31	47.96	OK	1978	2026-09-11 19:32	47.96	OK
1979	2026-09-11 19:33	47.47	OK	1980	2026-09-11 19:34	45.72	OK
1981	2026-09-11 19:35	46.66	OK	1982	2026-09-11 19:36	46.03	OK
1983	2026-09-11 19:37	47.50	OK	1984	2026-09-11 19:38	47.53	OK
1985	2026-09-11 19:39	47.20	OK	1986	2026-09-11 19:40	46.31	OK
1987	2026-09-11 19:41	47.66	OK	1988	2026-09-11 19:42	47.59	OK
1989	2026-09-11 19:43	46.24	OK	1990	2026-09-11 19:44	49.46	OK
1991	2026-09-11 19:45	48.35	OK	1992	2026-09-11 19:46	45.38	OK
1993	2026-09-11 19:47	46.65	OK	1994	2026-09-11 19:48	47.32	OK
1995	2026-09-11 19:49	45.68	OK	1996	2026-09-11 19:50	48.07	OK
1997	2026-09-11 19:51	48.77	OK	1998	2026-09-11 19:52	47.54	OK
1999	2026-09-11 19:53	46.09	OK	2000	2026-09-11 19:54	45.47	OK
2001	2026-09-11 19:55	45.58	OK	2002	2026-09-11 19:56	47.46	OK
2003	2026-09-11 19:57	49.13	OK	2004	2026-09-11 19:58	48.52	OK
2005	2026-09-11 19:59	47.02	OK	2006	2026-09-11 20:00	46.66	OK
2007	2026-09-11 20:01	47.03	OK	2008	2026-09-11 20:02	45.91	OK
2009	2026-09-11 20:03	44.79	OK	2010	2026-09-11 20:04	46.75	OK
2011	2026-09-11 20:05	45.21	OK	2012	2026-09-11 20:06	44.57	OK
2013	2026-09-11 20:07	46.27	OK	2014	2026-09-11 20:08	45.86	OK
2015	2026-09-11 20:09	48.14	OK	2016	2026-09-11 20:10	44.31	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2017	2026-09-11 20:11	45.91	OK	2018	2026-09-11 20:12	43.87	OK
2019	2026-09-11 20:13	46.42	OK	2020	2026-09-11 20:14	47.31	OK
2021	2026-09-11 20:15	45.86	OK	2022	2026-09-11 20:16	45.87	OK
2023	2026-09-11 20:17	45.70	OK	2024	2026-09-11 20:18	47.00	OK
2025	2026-09-11 20:19	47.84	OK	2026	2026-09-11 20:20	46.91	OK
2027	2026-09-11 20:21	46.11	OK	2028	2026-09-11 20:22	47.03	OK
2029	2026-09-11 20:23	46.24	OK	2030	2026-09-11 20:24	45.66	OK
2031	2026-09-11 20:25	46.12	OK	2032	2026-09-11 20:26	46.88	OK
2033	2026-09-11 20:27	45.74	OK	2034	2026-09-11 20:28	45.94	OK
2035	2026-09-11 20:29	46.29	OK	2036	2026-09-11 20:30	46.24	OK
2037	2026-09-11 20:31	45.05	OK	2038	2026-09-11 20:32	44.26	OK
2039	2026-09-11 20:33	45.23	OK	2040	2026-09-11 20:34	46.37	OK
2041	2026-09-11 20:35	44.85	OK	2042	2026-09-11 20:36	45.99	OK
2043	2026-09-11 20:37	45.95	OK	2044	2026-09-11 20:38	47.07	OK
2045	2026-09-11 20:39	48.20	OK	2046	2026-09-11 20:40	47.87	OK
2047	2026-09-11 20:41	45.74	OK	2048	2026-09-11 20:42	44.19	OK
2049	2026-09-11 20:43	46.67	OK	2050	2026-09-11 20:44	44.77	OK
2051	2026-09-11 20:45	46.00	OK	2052	2026-09-11 20:46	44.16	OK
2053	2026-09-11 20:47	44.52	OK	2054	2026-09-11 20:48	46.69	OK
2055	2026-09-11 20:49	45.63	OK	2056	2026-09-11 20:50	46.72	OK
2057	2026-09-11 20:51	46.37	OK	2058	2026-09-11 20:52	46.05	OK
2059	2026-09-11 20:53	45.60	OK	2060	2026-09-11 20:54	46.34	OK
2061	2026-09-11 20:55	46.12	OK	2062	2026-09-11 20:56	44.59	OK
2063	2026-09-11 20:57	45.81	OK	2064	2026-09-11 20:58	45.62	OK
2065	2026-09-11 20:59	44.44	OK	2066	2026-09-11 21:00	46.99	OK
2067	2026-09-11 21:01	44.27	OK	2068	2026-09-11 21:02	47.20	OK
2069	2026-09-11 21:03	47.78	OK	2070	2026-09-11 21:04	45.88	OK
2071	2026-09-11 21:05	46.83	OK	2072	2026-09-11 21:06	45.90	OK
2073	2026-09-11 21:07	47.16	OK	2074	2026-09-11 21:08	46.05	OK
2075	2026-09-11 21:09	46.72	OK	2076	2026-09-11 21:10	43.25	OK
2077	2026-09-11 21:11	46.02	OK	2078	2026-09-11 21:12	45.92	OK
2079	2026-09-11 21:13	44.52	OK	2080	2026-09-11 21:14	45.81	OK
2081	2026-09-11 21:15	45.06	OK	2082	2026-09-11 21:16	43.51	OK
2083	2026-09-11 21:17	45.69	OK	2084	2026-09-11 21:18	43.52	OK
2085	2026-09-11 21:19	45.51	OK	2086	2026-09-11 21:20	46.60	OK
2087	2026-09-11 21:21	44.98	OK	2088	2026-09-11 21:22	44.42	OK
2089	2026-09-11 21:23	45.76	OK	2090	2026-09-11 21:24	44.79	OK
2091	2026-09-11 21:25	45.57	OK	2092	2026-09-11 21:26	45.16	OK
2093	2026-09-11 21:27	43.06	OK	2094	2026-09-11 21:28	45.55	OK
2095	2026-09-11 21:29	45.52	OK	2096	2026-09-11 21:30	45.59	OK
2097	2026-09-11 21:31	46.67	OK	2098	2026-09-11 21:32	46.05	OK
2099	2026-09-11 21:33	46.42	OK	2100	2026-09-11 21:34	44.88	OK
2101	2026-09-11 21:35	44.37	OK	2102	2026-09-11 21:36	45.23	OK
2103	2026-09-11 21:37	46.64	OK	2104	2026-09-11 21:38	44.71	OK
2105	2026-09-11 21:39	44.97	OK	2106	2026-09-11 21:40	46.85	OK
2107	2026-09-11 21:41	46.58	OK	2108	2026-09-11 21:42	44.90	OK
2109	2026-09-11 21:43	44.64	OK	2110	2026-09-11 21:44	43.52	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2111	2026-09-11 21:45	45.42	OK	2112	2026-09-11 21:46	46.13	OK
2113	2026-09-11 21:47	44.61	OK	2114	2026-09-11 21:48	42.81	OK
2115	2026-09-11 21:49	45.22	OK	2116	2026-09-11 21:50	45.49	OK
2117	2026-09-11 21:51	44.37	OK	2118	2026-09-11 21:52	45.78	OK
2119	2026-09-11 21:53	44.66	OK	2120	2026-09-11 21:54	46.44	OK
2121	2026-09-11 21:55	45.47	OK	2122	2026-09-11 21:56	46.30	OK
2123	2026-09-11 21:57	46.07	OK	2124	2026-09-11 21:58	44.69	OK
2125	2026-09-11 21:59	44.90	OK	2126	2026-09-11 22:00	45.11	OK
2127	2026-09-11 22:01	44.53	OK	2128	2026-09-11 22:02	46.13	OK
2129	2026-09-11 22:03	44.07	OK	2130	2026-09-11 22:04	45.63	OK
2131	2026-09-11 22:05	44.20	OK	2132	2026-09-11 22:06	43.18	OK
2133	2026-09-11 22:07	44.36	OK	2134	2026-09-11 22:08	45.66	OK
2135	2026-09-11 22:09	44.02	OK	2136	2026-09-11 22:10	46.53	OK
2137	2026-09-11 22:11	44.93	OK	2138	2026-09-11 22:12	45.01	OK
2139	2026-09-11 22:13	45.14	OK	2140	2026-09-11 22:14	42.88	OK
2141	2026-09-11 22:15	44.79	OK	2142	2026-09-11 22:16	44.94	OK
2143	2026-09-11 22:17	43.67	OK	2144	2026-09-11 22:18	43.64	OK
2145	2026-09-11 22:19	43.77	OK	2146	2026-09-11 22:20	44.95	OK
2147	2026-09-11 22:21	45.37	OK	2148	2026-09-11 22:22	43.84	OK
2149	2026-09-11 22:23	44.28	OK	2150	2026-09-11 22:24	45.40	OK
2151	2026-09-11 22:25	44.86	OK	2152	2026-09-11 22:26	46.31	OK
2153	2026-09-11 22:27	43.64	OK	2154	2026-09-11 22:28	46.69	OK
2155	2026-09-11 22:29	43.24	OK	2156	2026-09-11 22:30	44.31	OK
2157	2026-09-11 22:31	46.85	OK	2158	2026-09-11 22:32	45.81	OK
2159	2026-09-11 22:33	46.98	OK	2160	2026-09-11 22:34	43.41	OK
2161	2026-09-11 22:35	44.40	OK	2162	2026-09-11 22:36	44.40	OK
2163	2026-09-11 22:37	43.18	OK	2164	2026-09-11 22:38	45.29	OK
2165	2026-09-11 22:39	44.96	OK	2166	2026-09-11 22:40	46.04	OK
2167	2026-09-11 22:41	45.78	OK	2168	2026-09-11 22:42	44.36	OK
2169	2026-09-11 22:43	45.34	OK	2170	2026-09-11 22:44	44.08	OK
2171	2026-09-11 22:45	46.20	OK	2172	2026-09-11 22:46	44.84	OK
2173	2026-09-11 22:47	44.57	OK	2174	2026-09-11 22:48	44.11	OK
2175	2026-09-11 22:49	42.74	OK	2176	2026-09-11 22:50	44.64	OK
2177	2026-09-11 22:51	45.18	OK	2178	2026-09-11 22:52	44.45	OK
2179	2026-09-11 22:53	44.17	OK	2180	2026-09-11 22:54	43.98	OK
2181	2026-09-11 22:55	45.14	OK	2182	2026-09-11 22:56	43.05	OK
2183	2026-09-11 22:57	43.35	OK	2184	2026-09-11 22:58	43.92	OK
2185	2026-09-11 22:59	44.04	OK	2186	2026-09-11 23:00	42.63	OK
2187	2026-09-11 23:01	44.16	OK	2188	2026-09-11 23:02	44.40	OK
2189	2026-09-11 23:03	44.76	OK	2190	2026-09-11 23:04	43.71	OK
2191	2026-09-11 23:05	44.37	OK	2192	2026-09-11 23:06	46.14	OK
2193	2026-09-11 23:07	43.21	OK	2194	2026-09-11 23:08	44.87	OK
2195	2026-09-11 23:09	45.51	OK	2196	2026-09-11 23:10	44.65	OK
2197	2026-09-11 23:11	45.79	OK	2198	2026-09-11 23:12	45.11	OK
2199	2026-09-11 23:13	43.83	OK	2200	2026-09-11 23:14	44.28	OK
2201	2026-09-11 23:15	43.61	OK	2202	2026-09-11 23:16	45.05	OK
2203	2026-09-11 23:17	46.30	OK	2204	2026-09-11 23:18	43.10	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2205	2026-09-11 23:19	45.49	OK	2206	2026-09-11 23:20	46.46	OK
2207	2026-09-11 23:21	45.39	OK	2208	2026-09-11 23:22	44.46	OK
2209	2026-09-11 23:23	43.86	OK	2210	2026-09-11 23:24	45.14	OK
2211	2026-09-11 23:25	45.57	OK	2212	2026-09-11 23:26	45.46	OK
2213	2026-09-11 23:27	45.60	OK	2214	2026-09-11 23:28	44.66	OK
2215	2026-09-11 23:29	44.36	OK	2216	2026-09-11 23:30	45.66	OK
2217	2026-09-11 23:31	42.88	OK	2218	2026-09-11 23:32	44.63	OK
2219	2026-09-11 23:33	47.46	OK	2220	2026-09-11 23:34	45.13	OK
2221	2026-09-11 23:35	43.36	OK	2222	2026-09-11 23:36	45.92	OK
2223	2026-09-11 23:37	46.10	OK	2224	2026-09-11 23:38	46.61	OK
2225	2026-09-11 23:39	45.37	OK	2226	2026-09-11 23:40	44.22	OK
2227	2026-09-11 23:41	44.82	OK	2228	2026-09-11 23:42	42.28	OK
2229	2026-09-11 23:43	44.83	OK	2230	2026-09-11 23:44	44.10	OK
2231	2026-09-11 23:45	44.59	OK	2232	2026-09-11 23:46	45.43	OK
2233	2026-09-11 23:47	44.37	OK	2234	2026-09-11 23:48	43.65	OK
2235	2026-09-11 23:49	45.46	OK	2236	2026-09-11 23:50	43.26	OK
2237	2026-09-11 23:51	43.63	OK	2238	2026-09-11 23:52	45.24	OK
2239	2026-09-11 23:53	44.63	OK	2240	2026-09-11 23:54	42.52	OK
2241	2026-09-11 23:55	44.23	OK	2242	2026-09-11 23:56	44.28	OK
2243	2026-09-11 23:57	45.98	OK	2244	2026-09-11 23:58	45.21	OK
2245	2026-09-11 23:59	42.53	OK	2246	2026-09-12 00:00	44.66	OK
2247	2026-09-12 00:01	45.58	OK	2248	2026-09-12 00:02	42.77	OK
2249	2026-09-12 00:03	44.51	OK	2250	2026-09-12 00:04	44.09	OK
2251	2026-09-12 00:05	45.51	OK	2252	2026-09-12 00:06	43.68	OK
2253	2026-09-12 00:07	43.09	OK	2254	2026-09-12 00:08	44.06	OK
2255	2026-09-12 00:09	44.96	OK	2256	2026-09-12 00:10	43.20	OK
2257	2026-09-12 00:11	44.84	OK	2258	2026-09-12 00:12	46.41	OK
2259	2026-09-12 00:13	44.26	OK	2260	2026-09-12 00:14	43.91	OK
2261	2026-09-12 00:15	44.95	OK	2262	2026-09-12 00:16	42.37	OK
2263	2026-09-12 00:17	44.56	OK	2264	2026-09-12 00:18	44.54	OK
2265	2026-09-12 00:19	46.04	OK	2266	2026-09-12 00:20	44.58	OK
2267	2026-09-12 00:21	44.73	OK	2268	2026-09-12 00:22	44.65	OK
2269	2026-09-12 00:23	45.60	OK	2270	2026-09-12 00:24	43.80	OK
2271	2026-09-12 00:25	44.81	OK	2272	2026-09-12 00:26	44.65	OK
2273	2026-09-12 00:27	47.06	OK	2274	2026-09-12 00:28	44.85	OK
2275	2026-09-12 00:29	44.51	OK	2276	2026-09-12 00:30	45.24	OK
2277	2026-09-12 00:31	44.98	OK	2278	2026-09-12 00:32	45.38	OK
2279	2026-09-12 00:33	44.56	OK	2280	2026-09-12 00:34	46.97	OK
2281	2026-09-12 00:35	45.02	OK	2282	2026-09-12 00:36	45.62	OK
2283	2026-09-12 00:37	45.04	OK	2284	2026-09-12 00:38	46.63	OK
2285	2026-09-12 00:39	44.21	OK	2286	2026-09-12 00:40	46.35	OK
2287	2026-09-12 00:41	43.44	OK	2288	2026-09-12 00:42	43.79	OK
2289	2026-09-12 00:43	46.17	OK	2290	2026-09-12 00:44	46.36	OK
2291	2026-09-12 00:45	44.38	OK	2292	2026-09-12 00:46	46.04	OK
2293	2026-09-12 00:47	42.61	OK	2294	2026-09-12 00:48	45.41	OK
2295	2026-09-12 00:49	44.63	OK	2296	2026-09-12 00:50	43.69	OK
2297	2026-09-12 00:51	46.73	OK	2298	2026-09-12 00:52	44.70	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2299	2026-09-12 00:53	42.96	OK	2300	2026-09-12 00:54	44.46	OK
2301	2026-09-12 00:55	42.94	OK	2302	2026-09-12 00:56	45.43	OK
2303	2026-09-12 00:57	44.52	OK	2304	2026-09-12 00:58	43.91	OK
2305	2026-09-12 00:59	45.24	OK	2306	2026-09-12 01:00	45.91	OK
2307	2026-09-12 01:01	47.61	OK	2308	2026-09-12 01:02	43.31	OK
2309	2026-09-12 01:03	46.89	OK	2310	2026-09-12 01:04	45.37	OK
2311	2026-09-12 01:05	44.90	OK	2312	2026-09-12 01:06	44.80	OK
2313	2026-09-12 01:07	44.14	OK	2314	2026-09-12 01:08	43.78	OK
2315	2026-09-12 01:09	46.49	OK	2316	2026-09-12 01:10	44.79	OK
2317	2026-09-12 01:11	43.97	OK	2318	2026-09-12 01:12	44.68	OK
2319	2026-09-12 01:13	42.88	OK	2320	2026-09-12 01:14	44.45	OK
2321	2026-09-12 01:15	45.66	OK	2322	2026-09-12 01:16	45.50	OK
2323	2026-09-12 01:17	47.44	OK	2324	2026-09-12 01:18	47.83	OK
2325	2026-09-12 01:19	45.17	OK	2326	2026-09-12 01:20	45.56	OK
2327	2026-09-12 01:21	45.56	OK	2328	2026-09-12 01:22	44.71	OK
2329	2026-09-12 01:23	44.29	OK	2330	2026-09-12 01:24	44.44	OK
2331	2026-09-12 01:25	45.02	OK	2332	2026-09-12 01:26	43.80	OK
2333	2026-09-12 01:27	44.18	OK	2334	2026-09-12 01:28	45.12	OK
2335	2026-09-12 01:29	44.75	OK	2336	2026-09-12 01:30	46.32	OK
2337	2026-09-12 01:31	44.74	OK	2338	2026-09-12 01:32	46.01	OK
2339	2026-09-12 01:33	44.86	OK	2340	2026-09-12 01:34	43.91	OK
2341	2026-09-12 01:35	45.86	OK	2342	2026-09-12 01:36	47.43	OK
2343	2026-09-12 01:37	45.45	OK	2344	2026-09-12 01:38	45.86	OK
2345	2026-09-12 01:39	43.51	OK	2346	2026-09-12 01:40	47.52	OK
2347	2026-09-12 01:41	46.55	OK	2348	2026-09-12 01:42	44.12	OK
2349	2026-09-12 01:43	46.37	OK	2350	2026-09-12 01:44	44.93	OK
2351	2026-09-12 01:45	45.96	OK	2352	2026-09-12 01:46	45.52	OK
2353	2026-09-12 01:47	46.56	OK	2354	2026-09-12 01:48	46.37	OK
2355	2026-09-12 01:49	47.95	OK	2356	2026-09-12 01:50	44.49	OK
2357	2026-09-12 01:51	47.28	OK	2358	2026-09-12 01:52	44.43	OK
2359	2026-09-12 01:53	44.45	OK	2360	2026-09-12 01:54	45.23	OK
2361	2026-09-12 01:55	46.59	OK	2362	2026-09-12 01:56	45.93	OK
2363	2026-09-12 01:57	43.52	OK	2364	2026-09-12 01:58	47.41	OK
2365	2026-09-12 01:59	46.22	OK	2366	2026-09-12 02:00	45.90	OK
2367	2026-09-12 02:01	46.98	OK	2368	2026-09-12 02:02	46.40	OK
2369	2026-09-12 02:03	46.56	OK	2370	2026-09-12 02:04	45.87	OK
2371	2026-09-12 02:05	45.73	OK	2372	2026-09-12 02:06	46.28	OK
2373	2026-09-12 02:07	47.17	OK	2374	2026-09-12 02:08	45.73	OK
2375	2026-09-12 02:09	43.93	OK	2376	2026-09-12 02:10	45.63	OK
2377	2026-09-12 02:11	44.58	OK	2378	2026-09-12 02:12	45.82	OK
2379	2026-09-12 02:13	44.51	OK	2380	2026-09-12 02:14	44.48	OK
2381	2026-09-12 02:15	45.62	OK	2382	2026-09-12 02:16	45.27	OK
2383	2026-09-12 02:17	45.88	OK	2384	2026-09-12 02:18	45.81	OK
2385	2026-09-12 02:19	45.66	OK	2386	2026-09-12 02:20	44.32	OK
2387	2026-09-12 02:21	46.67	OK	2388	2026-09-12 02:22	45.28	OK
2389	2026-09-12 02:23	46.07	OK	2390	2026-09-12 02:24	44.41	OK
2391	2026-09-12 02:25	47.07	OK	2392	2026-09-12 02:26	47.80	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2393	2026-09-12 02:27	46.29	OK	2394	2026-09-12 02:28	46.97	OK
2395	2026-09-12 02:29	45.18	OK	2396	2026-09-12 02:30	47.00	OK
2397	2026-09-12 02:31	44.74	OK	2398	2026-09-12 02:32	45.88	OK
2399	2026-09-12 02:33	46.71	OK	2400	2026-09-12 02:34	47.07	OK
2401	2026-09-12 02:35	45.45	OK	2402	2026-09-12 02:36	45.32	OK
2403	2026-09-12 02:37	46.79	OK	2404	2026-09-12 02:38	48.14	OK
2405	2026-09-12 02:39	45.55	OK	2406	2026-09-12 02:40	47.89	OK
2407	2026-09-12 02:41	44.82	OK	2408	2026-09-12 02:42	47.52	OK
2409	2026-09-12 02:43	45.99	OK	2410	2026-09-12 02:44	46.65	OK
2411	2026-09-12 02:45	48.14	OK	2412	2026-09-12 02:46	48.41	OK
2413	2026-09-12 02:47	47.08	OK	2414	2026-09-12 02:48	46.71	OK
2415	2026-09-12 02:49	45.00	OK	2416	2026-09-12 02:50	48.53	OK
2417	2026-09-12 02:51	45.17	OK	2418	2026-09-12 02:52	48.13	OK
2419	2026-09-12 02:53	45.14	OK	2420	2026-09-12 02:54	46.57	OK
2421	2026-09-12 02:55	46.13	OK	2422	2026-09-12 02:56	47.70	OK
2423	2026-09-12 02:57	45.85	OK	2424	2026-09-12 02:58	46.80	OK
2425	2026-09-12 02:59	43.86	OK	2426	2026-09-12 03:00	46.13	OK
2427	2026-09-12 03:01	47.16	OK	2428	2026-09-12 03:02	48.40	OK
2429	2026-09-12 03:03	46.59	OK	2430	2026-09-12 03:04	46.32	OK
2431	2026-09-12 03:05	45.30	OK	2432	2026-09-12 03:06	47.09	OK
2433	2026-09-12 03:07	46.66	OK	2434	2026-09-12 03:08	46.84	OK
2435	2026-09-12 03:09	45.50	OK	2436	2026-09-12 03:10	46.85	OK
2437	2026-09-12 03:11	47.93	OK	2438	2026-09-12 03:12	44.73	OK
2439	2026-09-12 03:13	47.16	OK	2440	2026-09-12 03:14	44.89	OK
2441	2026-09-12 03:15	45.84	OK	2442	2026-09-12 03:16	47.43	OK
2443	2026-09-12 03:17	45.75	OK	2444	2026-09-12 03:18	46.65	OK
2445	2026-09-12 03:19	46.39	OK	2446	2026-09-12 03:20	48.14	OK
2447	2026-09-12 03:21	47.82	OK	2448	2026-09-12 03:22	47.02	OK
2449	2026-09-12 03:23	46.12	OK	2450	2026-09-12 03:24	47.60	OK
2451	2026-09-12 03:25	47.74	OK	2452	2026-09-12 03:26	47.30	OK
2453	2026-09-12 03:27	47.02	OK	2454	2026-09-12 03:28	46.49	OK
2455	2026-09-12 03:29	47.27	OK	2456	2026-09-12 03:30	46.42	OK
2457	2026-09-12 03:31	49.60	OK	2458	2026-09-12 03:32	46.67	OK
2459	2026-09-12 03:33	48.92	OK	2460	2026-09-12 03:34	46.59	OK
2461	2026-09-12 03:35	49.59	OK	2462	2026-09-12 03:36	45.97	OK
2463	2026-09-12 03:37	47.77	OK	2464	2026-09-12 03:38	46.97	OK
2465	2026-09-12 03:39	47.16	OK	2466	2026-09-12 03:40	45.53	OK
2467	2026-09-12 03:41	47.73	OK	2468	2026-09-12 03:42	47.97	OK
2469	2026-09-12 03:43	47.51	OK	2470	2026-09-12 03:44	47.83	OK
2471	2026-09-12 03:45	47.45	OK	2472	2026-09-12 03:46	47.13	OK
2473	2026-09-12 03:47	45.98	OK	2474	2026-09-12 03:48	47.74	OK
2475	2026-09-12 03:49	47.34	OK	2476	2026-09-12 03:50	47.14	OK
2477	2026-09-12 03:51	46.66	OK	2478	2026-09-12 03:52	48.23	OK
2479	2026-09-12 03:53	45.32	OK	2480	2026-09-12 03:54	47.48	OK
2481	2026-09-12 03:55	47.66	OK	2482	2026-09-12 03:56	48.58	OK
2483	2026-09-12 03:57	45.81	OK	2484	2026-09-12 03:58	47.20	OK
2485	2026-09-12 03:59	46.36	OK	2486	2026-09-12 04:00	47.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2487	2026-09-12 04:01	48.73	OK	2488	2026-09-12 04:02	47.26	OK
2489	2026-09-12 04:03	47.09	OK	2490	2026-09-12 04:04	47.45	OK
2491	2026-09-12 04:05	45.99	OK	2492	2026-09-12 04:06	48.23	OK
2493	2026-09-12 04:07	48.43	OK	2494	2026-09-12 04:08	47.44	OK
2495	2026-09-12 04:09	47.13	OK	2496	2026-09-12 04:10	45.83	OK
2497	2026-09-12 04:11	47.16	OK	2498	2026-09-12 04:12	48.57	OK
2499	2026-09-12 04:13	47.06	OK	2500	2026-09-12 04:14	49.23	OK
2501	2026-09-12 04:15	46.40	OK	2502	2026-09-12 04:16	48.08	OK
2503	2026-09-12 04:17	47.97	OK	2504	2026-09-12 04:18	48.57	OK
2505	2026-09-12 04:19	47.62	OK	2506	2026-09-12 04:20	46.89	OK
2507	2026-09-12 04:21	46.43	OK	2508	2026-09-12 04:22	50.45	OK
2509	2026-09-12 04:23	47.73	OK	2510	2026-09-12 04:24	48.98	OK
2511	2026-09-12 04:25	49.54	OK	2512	2026-09-12 04:26	48.94	OK
2513	2026-09-12 04:27	48.94	OK	2514	2026-09-12 04:28	48.02	OK
2515	2026-09-12 04:29	47.61	OK	2516	2026-09-12 04:30	46.82	OK
2517	2026-09-12 04:31	48.52	OK	2518	2026-09-12 04:32	48.10	OK
2519	2026-09-12 04:33	48.59	OK	2520	2026-09-12 04:34	46.26	OK
2521	2026-09-12 04:35	46.73	OK	2522	2026-09-12 04:36	48.26	OK
2523	2026-09-12 04:37	47.54	OK	2524	2026-09-12 04:38	47.50	OK
2525	2026-09-12 04:39	47.83	OK	2526	2026-09-12 04:40	47.82	OK
2527	2026-09-12 04:41	46.12	OK	2528	2026-09-12 04:42	47.92	OK
2529	2026-09-12 04:43	49.25	OK	2530	2026-09-12 04:44	48.01	OK
2531	2026-09-12 04:45	47.86	OK	2532	2026-09-12 04:46	49.77	OK
2533	2026-09-12 04:47	48.01	OK	2534	2026-09-12 04:48	48.61	OK
2535	2026-09-12 04:49	48.47	OK	2536	2026-09-12 04:50	48.80	OK
2537	2026-09-12 04:51	47.96	OK	2538	2026-09-12 04:52	49.35	OK
2539	2026-09-12 04:53	48.37	OK	2540	2026-09-12 04:54	47.37	OK
2541	2026-09-12 04:55	48.50	OK	2542	2026-09-12 04:56	48.66	OK
2543	2026-09-12 04:57	49.50	OK	2544	2026-09-12 04:58	48.58	OK
2545	2026-09-12 04:59	50.67	OK	2546	2026-09-12 05:00	49.56	OK
2547	2026-09-12 05:01	48.13	OK	2548	2026-09-12 05:02	49.29	OK
2549	2026-09-12 05:03	49.75	OK	2550	2026-09-12 05:04	48.14	OK
2551	2026-09-12 05:05	47.45	OK	2552	2026-09-12 05:06	50.23	OK
2553	2026-09-12 05:07	50.52	OK	2554	2026-09-12 05:08	47.54	OK
2555	2026-09-12 05:09	48.80	OK	2556	2026-09-12 05:10	48.76	OK
2557	2026-09-12 05:11	47.08	OK	2558	2026-09-12 05:12	47.56	OK
2559	2026-09-12 05:13	48.76	OK	2560	2026-09-12 05:14	50.37	OK
2561	2026-09-12 05:15	49.18	OK	2562	2026-09-12 05:16	47.86	OK
2563	2026-09-12 05:17	48.38	OK	2564	2026-09-12 05:18	48.89	OK
2565	2026-09-12 05:19	50.95	OK	2566	2026-09-12 05:20	47.94	OK
2567	2026-09-12 05:21	48.64	OK	2568	2026-09-12 05:22	48.46	OK
2569	2026-09-12 05:23	48.51	OK	2570	2026-09-12 05:24	49.05	OK
2571	2026-09-12 05:25	47.94	OK	2572	2026-09-12 05:26	50.06	OK
2573	2026-09-12 05:27	48.69	OK	2574	2026-09-12 05:28	49.65	OK
2575	2026-09-12 05:29	49.40	OK	2576	2026-09-12 05:30	49.29	OK
2577	2026-09-12 05:31	48.19	OK	2578	2026-09-12 05:32	49.95	OK
2579	2026-09-12 05:33	47.66	OK	2580	2026-09-12 05:34	49.57	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2581	2026-09-12 05:35	48.76	OK	2582	2026-09-12 05:36	48.41	OK
2583	2026-09-12 05:37	46.64	OK	2584	2026-09-12 05:38	49.62	OK
2585	2026-09-12 05:39	51.11	OK	2586	2026-09-12 05:40	48.94	OK
2587	2026-09-12 05:41	48.86	OK	2588	2026-09-12 05:42	48.77	OK
2589	2026-09-12 05:43	49.56	OK	2590	2026-09-12 05:44	49.49	OK
2591	2026-09-12 05:45	50.88	OK	2592	2026-09-12 05:46	49.85	OK
2593	2026-09-12 05:47	47.92	OK	2594	2026-09-12 05:48	49.45	OK
2595	2026-09-12 05:49	51.33	OK	2596	2026-09-12 05:50	50.72	OK
2597	2026-09-12 05:51	49.88	OK	2598	2026-09-12 05:52	47.90	OK
2599	2026-09-12 05:53	50.32	OK	2600	2026-09-12 05:54	51.58	OK
2601	2026-09-12 05:55	51.10	OK	2602	2026-09-12 05:56	48.70	OK
2603	2026-09-12 05:57	49.85	OK	2604	2026-09-12 05:58	48.56	OK
2605	2026-09-12 05:59	48.26	OK	2606	2026-09-12 06:00	49.78	OK
2607	2026-09-12 06:01	50.20	OK	2608	2026-09-12 06:02	50.14	OK
2609	2026-09-12 06:03	51.43	OK	2610	2026-09-12 06:04	49.15	OK
2611	2026-09-12 06:05	52.04	OK	2612	2026-09-12 06:06	48.63	OK
2613	2026-09-12 06:07	49.13	OK	2614	2026-09-12 06:08	50.73	OK
2615	2026-09-12 06:09	48.38	OK	2616	2026-09-12 06:10	47.83	OK
2617	2026-09-12 06:11	48.22	OK	2618	2026-09-12 06:12	51.22	OK
2619	2026-09-12 06:13	48.24	OK	2620	2026-09-12 06:14	49.04	OK
2621	2026-09-12 06:15	51.10	OK	2622	2026-09-12 06:16	52.55	OK
2623	2026-09-12 06:17	51.54	OK	2624	2026-09-12 06:18	48.93	OK
2625	2026-09-12 06:19	53.06	OK	2626	2026-09-12 06:20	48.32	OK
2627	2026-09-12 06:21	51.51	OK	2628	2026-09-12 06:22	50.12	OK
2629	2026-09-12 06:23	52.62	OK	2630	2026-09-12 06:24	51.36	OK
2631	2026-09-12 06:25	48.85	OK	2632	2026-09-12 06:26	52.11	OK
2633	2026-09-12 06:27	48.46	OK	2634	2026-09-12 06:28	49.99	OK
2635	2026-09-12 06:29	50.13	OK	2636	2026-09-12 06:30	49.37	OK
2637	2026-09-12 06:31	51.94	OK	2638	2026-09-12 06:32	51.87	OK
2639	2026-09-12 06:33	53.18	OK	2640	2026-09-12 06:34	52.06	OK
2641	2026-09-12 06:35	51.69	OK	2642	2026-09-12 06:36	51.99	OK
2643	2026-09-12 06:37	50.99	OK	2644	2026-09-12 06:38	50.69	OK
2645	2026-09-12 06:39	48.84	OK	2646	2026-09-12 06:40	51.33	OK
2647	2026-09-12 06:41	51.04	OK	2648	2026-09-12 06:42	50.21	OK
2649	2026-09-12 06:43	51.33	OK	2650	2026-09-12 06:44	51.64	OK
2651	2026-09-12 06:45	50.76	OK	2652	2026-09-12 06:46	50.92	OK
2653	2026-09-12 06:47	50.77	OK	2654	2026-09-12 06:48	50.45	OK
2655	2026-09-12 06:49	52.21	OK	2656	2026-09-12 06:50	48.75	OK
2657	2026-09-12 06:51	51.49	OK	2658	2026-09-12 06:52	49.23	OK
2659	2026-09-12 06:53	48.46	OK	2660	2026-09-12 06:54	50.72	OK
2661	2026-09-12 06:55	49.87	OK	2662	2026-09-12 06:56	51.00	OK
2663	2026-09-12 06:57	53.49	OK	2664	2026-09-12 06:58	50.53	OK
2665	2026-09-12 06:59	52.49	OK	2666	2026-09-12 07:00	52.53	OK
2667	2026-09-12 07:01	52.08	OK	2668	2026-09-12 07:02	52.68	OK
2669	2026-09-12 07:03	50.60	OK	2670	2026-09-12 07:04	52.74	OK
2671	2026-09-12 07:05	51.42	OK	2672	2026-09-12 07:06	51.03	OK
2673	2026-09-12 07:07	51.91	OK	2674	2026-09-12 07:08	49.96	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2675	2026-09-12 07:09	52.92	OK	2676	2026-09-12 07:10	52.19	OK
2677	2026-09-12 07:11	49.80	OK	2678	2026-09-12 07:12	50.99	OK
2679	2026-09-12 07:13	50.82	OK	2680	2026-09-12 07:14	53.19	OK
2681	2026-09-12 07:15	52.60	OK	2682	2026-09-12 07:16	52.78	OK
2683	2026-09-12 07:17	51.91	OK	2684	2026-09-12 07:18	52.79	OK
2685	2026-09-12 07:19	52.60	OK	2686	2026-09-12 07:20	52.27	OK
2687	2026-09-12 07:21	52.26	OK	2688	2026-09-12 07:22	51.72	OK
2689	2026-09-12 07:23	51.04	OK	2690	2026-09-12 07:24	49.84	OK
2691	2026-09-12 07:25	51.05	OK	2692	2026-09-12 07:26	51.84	OK
2693	2026-09-12 07:27	49.78	OK	2694	2026-09-12 07:28	53.17	OK
2695	2026-09-12 07:29	50.10	OK	2696	2026-09-12 07:30	53.13	OK
2697	2026-09-12 07:31	53.38	OK	2698	2026-09-12 07:32	53.77	OK
2699	2026-09-12 07:33	51.33	OK	2700	2026-09-12 07:34	51.33	OK
2701	2026-09-12 07:35	52.38	OK	2702	2026-09-12 07:36	54.18	OK
2703	2026-09-12 07:37	51.75	OK	2704	2026-09-12 07:38	52.93	OK
2705	2026-09-12 07:39	50.41	OK	2706	2026-09-12 07:40	53.29	OK
2707	2026-09-12 07:41	50.69	OK	2708	2026-09-12 07:42	51.23	OK
2709	2026-09-12 07:43	51.28	OK	2710	2026-09-12 07:44	51.80	OK
2711	2026-09-12 07:45	52.28	OK	2712	2026-09-12 07:46	51.46	OK
2713	2026-09-12 07:47	52.10	OK	2714	2026-09-12 07:48	51.62	OK
2715	2026-09-12 07:49	51.27	OK	2716	2026-09-12 07:50	51.89	OK
2717	2026-09-12 07:51	53.38	OK	2718	2026-09-12 07:52	53.73	OK
2719	2026-09-12 07:53	51.62	OK	2720	2026-09-12 07:54	52.58	OK
2721	2026-09-12 07:55	50.55	OK	2722	2026-09-12 07:56	51.79	OK
2723	2026-09-12 07:57	52.14	OK	2724	2026-09-12 07:58	52.78	OK
2725	2026-09-12 07:59	50.82	OK	2726	2026-09-12 08:00	52.67	OK
2727	2026-09-12 08:01	51.64	OK	2728	2026-09-12 08:02	52.09	OK
2729	2026-09-12 08:03	51.98	OK	2730	2026-09-12 08:04	53.16	OK
2731	2026-09-12 08:05	52.49	OK	2732	2026-09-12 08:06	51.76	OK
2733	2026-09-12 08:07	54.07	OK	2734	2026-09-12 08:08	50.72	OK
2735	2026-09-12 08:09	53.18	OK	2736	2026-09-12 08:10	52.93	OK
2737	2026-09-12 08:11	52.13	OK	2738	2026-09-12 08:12	50.77	OK
2739	2026-09-12 08:13	51.98	OK	2740	2026-09-12 08:14	53.29	OK
2741	2026-09-12 08:15	54.51	OK	2742	2026-09-12 08:16	53.63	OK
2743	2026-09-12 08:17	50.70	OK	2744	2026-09-12 08:18	53.03	OK
2745	2026-09-12 08:19	52.40	OK	2746	2026-09-12 08:20	53.35	OK
2747	2026-09-12 08:21	54.67	OK	2748	2026-09-12 08:22	50.84	OK
2749	2026-09-12 08:23	51.79	OK	2750	2026-09-12 08:24	52.77	OK
2751	2026-09-12 08:25	51.75	OK	2752	2026-09-12 08:26	52.01	OK
2753	2026-09-12 08:27	52.55	OK	2754	2026-09-12 08:28	54.23	OK
2755	2026-09-12 08:29	53.99	OK	2756	2026-09-12 08:30	53.16	OK
2757	2026-09-12 08:31	51.00	OK	2758	2026-09-12 08:32	53.42	OK
2759	2026-09-12 08:33	52.32	OK	2760	2026-09-12 08:34	53.13	OK
2761	2026-09-12 08:35	54.44	OK	2762	2026-09-12 08:36	52.36	OK
2763	2026-09-12 08:37	52.76	OK	2764	2026-09-12 08:38	52.39	OK
2765	2026-09-12 08:39	53.96	OK	2766	2026-09-12 08:40	52.54	OK
2767	2026-09-12 08:41	52.59	OK	2768	2026-09-12 08:42	55.40	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2769	2026-09-12 08:43	53.93	OK	2770	2026-09-12 08:44	52.73	OK
2771	2026-09-12 08:45	53.89	OK	2772	2026-09-12 08:46	53.26	OK
2773	2026-09-12 08:47	52.43	OK	2774	2026-09-12 08:48	51.62	OK
2775	2026-09-12 08:49	52.20	OK	2776	2026-09-12 08:50	54.70	OK
2777	2026-09-12 08:51	54.96	OK	2778	2026-09-12 08:52	53.16	OK
2779	2026-09-12 08:53	51.71	OK	2780	2026-09-12 08:54	53.58	OK
2781	2026-09-12 08:55	52.15	OK	2782	2026-09-12 08:56	52.61	OK
2783	2026-09-12 08:57	53.48	OK	2784	2026-09-12 08:58	52.18	OK
2785	2026-09-12 08:59	51.98	OK	2786	2026-09-12 09:00	52.43	OK
2787	2026-09-12 09:01	51.97	OK	2788	2026-09-12 09:02	52.49	OK
2789	2026-09-12 09:03	52.50	OK	2790	2026-09-12 09:04	53.52	OK
2791	2026-09-12 09:05	54.88	OK	2792	2026-09-12 09:06	53.34	OK
2793	2026-09-12 09:07	54.87	OK	2794	2026-09-12 09:08	52.69	OK
2795	2026-09-12 09:09	52.97	OK	2796	2026-09-12 09:10	53.68	OK
2797	2026-09-12 09:11	52.77	OK	2798	2026-09-12 09:12	53.19	OK
2799	2026-09-12 09:13	52.29	OK	2800	2026-09-12 09:14	52.85	OK
2801	2026-09-12 09:15	51.38	OK	2802	2026-09-12 09:16	53.90	OK
2803	2026-09-12 09:17	52.62	OK	2804	2026-09-12 09:18	53.29	OK
2805	2026-09-12 09:19	52.11	OK	2806	2026-09-12 09:20	54.22	OK
2807	2026-09-12 09:21	53.53	OK	2808	2026-09-12 09:22	53.11	OK
2809	2026-09-12 09:23	53.72	OK	2810	2026-09-12 09:24	54.09	OK
2811	2026-09-12 09:25	52.70	OK	2812	2026-09-12 09:26	53.11	OK
2813	2026-09-12 09:27	53.13	OK	2814	2026-09-12 09:28	52.23	OK
2815	2026-09-12 09:29	54.67	OK	2816	2026-09-12 09:30	52.89	OK
2817	2026-09-12 09:31	55.30	OK	2818	2026-09-12 09:32	54.35	OK
2819	2026-09-12 09:33	53.26	OK	2820	2026-09-12 09:34	52.23	OK
2821	2026-09-12 09:35	54.69	OK	2822	2026-09-12 09:36	52.65	OK
2823	2026-09-12 09:37	51.55	OK	2824	2026-09-12 09:38	55.59	OK
2825	2026-09-12 09:39	55.69	OK	2826	2026-09-12 09:40	52.84	OK
2827	2026-09-12 09:41	53.97	OK	2828	2026-09-12 09:42	54.19	OK
2829	2026-09-12 09:43	53.82	OK	2830	2026-09-12 09:44	53.93	OK
2831	2026-09-12 09:45	53.11	OK	2832	2026-09-12 09:46	53.71	OK
2833	2026-09-12 09:47	54.46	OK	2834	2026-09-12 09:48	55.00	OK
2835	2026-09-12 09:49	52.59	OK	2836	2026-09-12 09:50	54.24	OK
2837	2026-09-12 09:51	53.73	OK	2838	2026-09-12 09:52	53.62	OK
2839	2026-09-12 09:53	53.34	OK	2840	2026-09-12 09:54	54.48	OK
2841	2026-09-12 09:55	52.96	OK	2842	2026-09-12 09:56	54.02	OK
2843	2026-09-12 09:57	52.87	OK	2844	2026-09-12 09:58	54.25	OK
2845	2026-09-12 09:59	55.85	OK	2846	2026-09-12 10:00	53.44	OK
2847	2026-09-12 10:01	53.47	OK	2848	2026-09-12 10:02	54.48	OK
2849	2026-09-12 10:03	55.55	OK	2850	2026-09-12 10:04	53.79	OK
2851	2026-09-12 10:05	53.17	OK	2852	2026-09-12 10:06	54.14	OK
2853	2026-09-12 10:07	52.63	OK	2854	2026-09-12 10:08	52.23	OK
2855	2026-09-12 10:09	53.21	OK	2856	2026-09-12 10:10	54.31	OK
2857	2026-09-12 10:11	54.74	OK	2858	2026-09-12 10:12	53.01	OK
2859	2026-09-12 10:13	53.32	OK	2860	2026-09-12 10:14	54.03	OK
2861	2026-09-12 10:15	53.31	OK	2862	2026-09-12 10:16	53.38	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2863	2026-09-12 10:17	52.48	OK	2864	2026-09-12 10:18	54.32	OK
2865	2026-09-12 10:19	52.83	OK	2866	2026-09-12 10:20	51.86	OK
2867	2026-09-12 10:21	54.19	OK	2868	2026-09-12 10:22	56.04	OK
2869	2026-09-12 10:23	54.27	OK	2870	2026-09-12 10:24	53.33	OK
2871	2026-09-12 10:25	54.08	OK	2872	2026-09-12 10:26	55.34	OK
2873	2026-09-12 10:27	54.36	OK	2874	2026-09-12 10:28	54.88	OK
2875	2026-09-12 10:29	53.09	OK	2876	2026-09-12 10:30	54.61	OK
2877	2026-09-12 10:31	53.63	OK	2878	2026-09-12 10:32	54.74	OK
2879	2026-09-12 10:33	54.45	OK	2880	2026-09-12 10:34	54.61	OK
2881	2026-09-12 10:35	53.76	OK	2882	2026-09-12 10:36	54.26	OK
2883	2026-09-12 10:37	52.39	OK	2884	2026-09-12 10:38	54.00	OK
2885	2026-09-12 10:39	54.18	OK	2886	2026-09-12 10:40	54.18	OK
2887	2026-09-12 10:41	54.79	OK	2888	2026-09-12 10:42	55.01	OK
2889	2026-09-12 10:43	54.43	OK	2890	2026-09-12 10:44	54.88	OK
2891	2026-09-12 10:45	56.44	OK	2892	2026-09-12 10:46	54.32	OK
2893	2026-09-12 10:47	53.07	OK	2894	2026-09-12 10:48	53.02	OK
2895	2026-09-12 10:49	52.87	OK	2896	2026-09-12 10:50	55.03	OK
2897	2026-09-12 10:51	53.73	OK	2898	2026-09-12 10:52	55.33	OK
2899	2026-09-12 10:53	54.28	OK	2900	2026-09-12 10:54	55.56	OK
2901	2026-09-12 10:55	55.73	OK	2902	2026-09-12 10:56	54.66	OK
2903	2026-09-12 10:57	56.66	OK	2904	2026-09-12 10:58	55.41	OK
2905	2026-09-12 10:59	52.86	OK	2906	2026-09-12 11:00	55.34	OK
2907	2026-09-12 11:01	53.94	OK	2908	2026-09-12 11:02	54.66	OK
2909	2026-09-12 11:03	57.02	OK	2910	2026-09-12 11:04	53.30	OK
2911	2026-09-12 11:05	56.19	OK	2912	2026-09-12 11:06	54.00	OK
2913	2026-09-12 11:07	54.33	OK	2914	2026-09-12 11:08	54.82	OK
2915	2026-09-12 11:09	53.11	OK	2916	2026-09-12 11:10	55.41	OK
2917	2026-09-12 11:11	54.19	OK	2918	2026-09-12 11:12	55.11	OK
2919	2026-09-12 11:13	52.67	OK	2920	2026-09-12 11:14	55.84	OK
2921	2026-09-12 11:15	55.73	OK	2922	2026-09-12 11:16	53.47	OK
2923	2026-09-12 11:17	55.85	OK	2924	2026-09-12 11:18	54.12	OK
2925	2026-09-12 11:19	52.81	OK	2926	2026-09-12 11:20	54.62	OK
2927	2026-09-12 11:21	53.81	OK	2928	2026-09-12 11:22	55.96	OK
2929	2026-09-12 11:23	55.14	OK	2930	2026-09-12 11:24	54.96	OK
2931	2026-09-12 11:25	56.29	OK	2932	2026-09-12 11:26	54.28	OK
2933	2026-09-12 11:27	52.46	OK	2934	2026-09-12 11:28	54.67	OK
2935	2026-09-12 11:29	53.86	OK	2936	2026-09-12 11:30	54.44	OK
2937	2026-09-12 11:31	54.72	OK	2938	2026-09-12 11:32	55.69	OK
2939	2026-09-12 11:33	53.37	OK	2940	2026-09-12 11:34	53.24	OK
2941	2026-09-12 11:35	54.64	OK	2942	2026-09-12 11:36	52.68	OK
2943	2026-09-12 11:37	52.96	OK	2944	2026-09-12 11:38	54.72	OK
2945	2026-09-12 11:39	53.16	OK	2946	2026-09-12 11:40	54.99	OK
2947	2026-09-12 11:41	53.42	OK	2948	2026-09-12 11:42	55.53	OK
2949	2026-09-12 11:43	55.93	OK	2950	2026-09-12 11:44	53.77	OK
2951	2026-09-12 11:45	54.25	OK	2952	2026-09-12 11:46	54.11	OK
2953	2026-09-12 11:47	53.22	OK	2954	2026-09-12 11:48	53.61	OK
2955	2026-09-12 11:49	53.34	OK	2956	2026-09-12 11:50	54.03	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2957	2026-09-12 11:51	55.25	OK	2958	2026-09-12 11:52	52.44	OK
2959	2026-09-12 11:53	54.10	OK	2960	2026-09-12 11:54	54.59	OK
2961	2026-09-12 11:55	52.68	OK	2962	2026-09-12 11:56	53.43	OK
2963	2026-09-12 11:57	53.13	OK	2964	2026-09-12 11:58	52.91	OK
2965	2026-09-12 11:59	54.60	OK	2966	2026-09-12 12:00	54.36	OK
2967	2026-09-12 12:01	55.45	OK	2968	2026-09-12 12:02	53.91	OK
2969	2026-09-12 12:03	54.61	OK	2970	2026-09-12 12:04	56.01	OK
2971	2026-09-12 12:05	53.63	OK	2972	2026-09-12 12:06	53.89	OK
2973	2026-09-12 12:07	52.18	OK	2974	2026-09-12 12:08	54.84	OK
2975	2026-09-12 12:09	53.14	OK	2976	2026-09-12 12:10	54.17	OK
2977	2026-09-12 12:11	53.37	OK	2978	2026-09-12 12:12	56.16	OK
2979	2026-09-12 12:13	53.87	OK	2980	2026-09-12 12:14	52.12	OK
2981	2026-09-12 12:15	53.32	OK	2982	2026-09-12 12:16	56.48	OK
2983	2026-09-12 12:17	53.72	OK	2984	2026-09-12 12:18	53.04	OK
2985	2026-09-12 12:19	56.88	OK	2986	2026-09-12 12:20	53.75	OK
2987	2026-09-12 12:21	53.22	OK	2988	2026-09-12 12:22	55.71	OK
2989	2026-09-12 12:23	56.05	OK	2990	2026-09-12 12:24	53.42	OK
2991	2026-09-12 12:25	51.38	OK	2992	2026-09-12 12:26	53.05	OK
2993	2026-09-12 12:27	52.01	OK	2994	2026-09-12 12:28	55.02	OK
2995	2026-09-12 12:29	53.24	OK	2996	2026-09-12 12:30	54.87	OK
2997	2026-09-12 12:31	53.55	OK	2998	2026-09-12 12:32	52.88	OK
2999	2026-09-12 12:33	54.67	OK	3000	2026-09-12 12:34	54.94	OK
3001	2026-09-12 12:35	52.11	OK	3002	2026-09-12 12:36	54.66	OK
3003	2026-09-12 12:37	54.30	OK	3004	2026-09-12 12:38	52.40	OK
3005	2026-09-12 12:39	55.24	OK	3006	2026-09-12 12:40	51.84	OK
3007	2026-09-12 12:41	54.24	OK	3008	2026-09-12 12:42	52.53	OK
3009	2026-09-12 12:43	54.86	OK	3010	2026-09-12 12:44	55.46	OK
3011	2026-09-12 12:45	54.11	OK	3012	2026-09-12 12:46	53.80	OK
3013	2026-09-12 12:47	53.44	OK	3014	2026-09-12 12:48	51.67	OK
3015	2026-09-12 12:49	54.67	OK	3016	2026-09-12 12:50	53.23	OK
3017	2026-09-12 12:51	55.30	OK	3018	2026-09-12 12:52	53.53	OK
3019	2026-09-12 12:53	55.34	OK	3020	2026-09-12 12:54	54.34	OK
3021	2026-09-12 12:55	55.10	OK	3022	2026-09-12 12:56	53.76	OK
3023	2026-09-12 12:57	53.55	OK	3024	2026-09-12 12:58	54.36	OK
3025	2026-09-12 12:59	53.75	OK	3026	2026-09-12 13:00	53.38	OK
3027	2026-09-12 13:01	53.27	OK	3028	2026-09-12 13:02	52.81	OK
3029	2026-09-12 13:03	54.35	OK	3030	2026-09-12 13:04	54.71	OK
3031	2026-09-12 13:05	54.07	OK	3032	2026-09-12 13:06	52.43	OK
3033	2026-09-12 13:07	54.23	OK	3034	2026-09-12 13:08	55.36	OK
3035	2026-09-12 13:09	53.81	OK	3036	2026-09-12 13:10	53.06	OK
3037	2026-09-12 13:11	52.81	OK	3038	2026-09-12 13:12	54.53	OK
3039	2026-09-12 13:13	53.20	OK	3040	2026-09-12 13:14	53.33	OK
3041	2026-09-12 13:15	54.84	OK	3042	2026-09-12 13:16	54.73	OK
3043	2026-09-12 13:17	52.21	OK	3044	2026-09-12 13:18	53.83	OK
3045	2026-09-12 13:19	55.70	OK	3046	2026-09-12 13:20	56.38	OK
3047	2026-09-12 13:21	54.48	OK	3048	2026-09-12 13:22	54.61	OK
3049	2026-09-12 13:23	54.70	OK	3050	2026-09-12 13:24	55.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3051	2026-09-12 13:25	52.92	OK	3052	2026-09-12 13:26	51.70	OK
3053	2026-09-12 13:27	54.07	OK	3054	2026-09-12 13:28	52.18	OK
3055	2026-09-12 13:29	54.14	OK	3056	2026-09-12 13:30	53.73	OK
3057	2026-09-12 13:31	52.61	OK	3058	2026-09-12 13:32	52.59	OK
3059	2026-09-12 13:33	53.02	OK	3060	2026-09-12 13:34	55.08	OK
3061	2026-09-12 13:35	55.15	OK	3062	2026-09-12 13:36	53.93	OK
3063	2026-09-12 13:37	52.64	OK	3064	2026-09-12 13:38	54.23	OK
3065	2026-09-12 13:39	55.16	OK	3066	2026-09-12 13:40	54.17	OK
3067	2026-09-12 13:41	53.72	OK	3068	2026-09-12 13:42	54.68	OK
3069	2026-09-12 13:43	52.67	OK	3070	2026-09-12 13:44	53.75	OK
3071	2026-09-12 13:45	52.36	OK	3072	2026-09-12 13:46	52.73	OK
3073	2026-09-12 13:47	53.77	OK	3074	2026-09-12 13:48	54.18	OK
3075	2026-09-12 13:49	52.38	OK	3076	2026-09-12 13:50	53.36	OK
3077	2026-09-12 13:51	52.67	OK	3078	2026-09-12 13:52	53.94	OK
3079	2026-09-12 13:53	53.61	OK	3080	2026-09-12 13:54	53.38	OK
3081	2026-09-12 13:55	51.48	OK	3082	2026-09-12 13:56	53.85	OK
3083	2026-09-12 13:57	53.89	OK	3084	2026-09-12 13:58	53.06	OK
3085	2026-09-12 13:59	54.04	OK	3086	2026-09-12 14:00	51.79	OK
3087	2026-09-12 14:01	52.79	OK	3088	2026-09-12 14:02	52.76	OK
3089	2026-09-12 14:03	54.56	OK	3090	2026-09-12 14:04	54.01	OK
3091	2026-09-12 14:05	51.89	OK	3092	2026-09-12 14:06	52.23	OK
3093	2026-09-12 14:07	52.69	OK	3094	2026-09-12 14:08	51.43	OK
3095	2026-09-12 14:09	53.97	OK	3096	2026-09-12 14:10	52.34	OK
3097	2026-09-12 14:11	51.78	OK	3098	2026-09-12 14:12	52.91	OK
3099	2026-09-12 14:13	50.57	OK	3100	2026-09-12 14:14	54.08	OK
3101	2026-09-12 14:15	53.65	OK	3102	2026-09-12 14:16	53.19	OK
3103	2026-09-12 14:17	51.52	OK	3104	2026-09-12 14:18	55.35	OK
3105	2026-09-12 14:19	55.21	OK	3106	2026-09-12 14:20	52.31	OK
3107	2026-09-12 14:21	52.29	OK	3108	2026-09-12 14:22	53.24	OK
3109	2026-09-12 14:23	51.74	OK	3110	2026-09-12 14:24	53.95	OK
3111	2026-09-12 14:25	52.84	OK	3112	2026-09-12 14:26	51.66	OK
3113	2026-09-12 14:27	51.74	OK	3114	2026-09-12 14:28	52.18	OK
3115	2026-09-12 14:29	50.85	OK	3116	2026-09-12 14:30	50.76	OK
3117	2026-09-12 14:31	50.65	OK	3118	2026-09-12 14:32	53.73	OK
3119	2026-09-12 14:33	51.60	OK	3120	2026-09-12 14:34	50.85	OK
3121	2026-09-12 14:35	51.99	OK	3122	2026-09-12 14:36	53.68	OK
3123	2026-09-12 14:37	53.17	OK	3124	2026-09-12 14:38	52.23	OK
3125	2026-09-12 14:39	53.94	OK	3126	2026-09-12 14:40	53.27	OK
3127	2026-09-12 14:41	53.47	OK	3128	2026-09-12 14:42	53.90	OK
3129	2026-09-12 14:43	51.46	OK	3130	2026-09-12 14:44	52.91	OK
3131	2026-09-12 14:45	51.63	OK	3132	2026-09-12 14:46	52.53	OK
3133	2026-09-12 14:47	52.96	OK	3134	2026-09-12 14:48	52.26	OK
3135	2026-09-12 14:49	54.22	OK	3136	2026-09-12 14:50	53.25	OK
3137	2026-09-12 14:51	51.16	OK	3138	2026-09-12 14:52	50.80	OK
3139	2026-09-12 14:53	53.44	OK	3140	2026-09-12 14:54	53.66	OK
3141	2026-09-12 14:55	52.07	OK	3142	2026-09-12 14:56	52.94	OK
3143	2026-09-12 14:57	52.43	OK	3144	2026-09-12 14:58	53.28	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3145	2026-09-12 14:59	52.61	OK	3146	2026-09-12 15:00	53.77	OK
3147	2026-09-12 15:01	51.51	OK	3148	2026-09-12 15:02	53.53	OK
3149	2026-09-12 15:03	52.53	OK	3150	2026-09-12 15:04	52.98	OK
3151	2026-09-12 15:05	50.92	OK	3152	2026-09-12 15:06	52.26	OK
3153	2026-09-12 15:07	52.79	OK	3154	2026-09-12 15:08	53.10	OK
3155	2026-09-12 15:09	50.65	OK	3156	2026-09-12 15:10	54.69	OK
3157	2026-09-12 15:11	51.13	OK	3158	2026-09-12 15:12	51.23	OK
3159	2026-09-12 15:13	53.58	OK	3160	2026-09-12 15:14	52.68	OK
3161	2026-09-12 15:15	52.45	OK	3162	2026-09-12 15:16	54.59	OK
3163	2026-09-12 15:17	52.88	OK	3164	2026-09-12 15:18	52.18	OK
3165	2026-09-12 15:19	54.15	OK	3166	2026-09-12 15:20	52.17	OK
3167	2026-09-12 15:21	51.05	OK	3168	2026-09-12 15:22	53.40	OK
3169	2026-09-12 15:23	53.93	OK	3170	2026-09-12 15:24	50.19	OK
3171	2026-09-12 15:25	52.20	OK	3172	2026-09-12 15:26	50.48	OK
3173	2026-09-12 15:27	51.94	OK	3174	2026-09-12 15:28	51.85	OK
3175	2026-09-12 15:29	52.95	OK	3176	2026-09-12 15:30	52.40	OK
3177	2026-09-12 15:31	51.57	OK	3178	2026-09-12 15:32	50.86	OK
3179	2026-09-12 15:33	51.14	OK	3180	2026-09-12 15:34	52.42	OK
3181	2026-09-12 15:35	52.55	OK	3182	2026-09-12 15:36	52.69	OK
3183	2026-09-12 15:37	51.06	OK	3184	2026-09-12 15:38	53.89	OK
3185	2026-09-12 15:39	50.48	OK	3186	2026-09-12 15:40	51.48	OK
3187	2026-09-12 15:41	54.08	OK	3188	2026-09-12 15:42	52.61	OK
3189	2026-09-12 15:43	51.12	OK	3190	2026-09-12 15:44	49.76	OK
3191	2026-09-12 15:45	49.92	OK	3192	2026-09-12 15:46	52.14	OK
3193	2026-09-12 15:47	53.81	OK	3194	2026-09-12 15:48	53.20	OK
3195	2026-09-12 15:49	51.09	OK	3196	2026-09-12 15:50	51.27	OK
3197	2026-09-12 15:51	51.15	OK	3198	2026-09-12 15:52	49.81	OK
3199	2026-09-12 15:53	51.86	OK	3200	2026-09-12 15:54	51.16	OK
3201	2026-09-12 15:55	51.25	OK	3202	2026-09-12 15:56	51.43	OK
3203	2026-09-12 15:57	50.55	OK	3204	2026-09-12 15:58	51.55	OK
3205	2026-09-12 15:59	52.15	OK	3206	2026-09-12 16:00	50.69	OK
3207	2026-09-12 16:01	52.12	OK	3208	2026-09-12 16:02	52.35	OK
3209	2026-09-12 16:03	49.10	OK	3210	2026-09-12 16:04	50.13	OK
3211	2026-09-12 16:05	51.93	OK	3212	2026-09-12 16:06	53.23	OK
3213	2026-09-12 16:07	52.40	OK	3214	2026-09-12 16:08	51.12	OK
3215	2026-09-12 16:09	49.61	OK	3216	2026-09-12 16:10	51.08	OK
3217	2026-09-12 16:11	50.14	OK	3218	2026-09-12 16:12	49.30	OK
3219	2026-09-12 16:13	50.85	OK	3220	2026-09-12 16:14	52.19	OK
3221	2026-09-12 16:15	51.47	OK	3222	2026-09-12 16:16	48.49	OK
3223	2026-09-12 16:17	51.22	OK	3224	2026-09-12 16:18	49.40	OK
3225	2026-09-12 16:19	52.46	OK	3226	2026-09-12 16:20	51.00	OK
3227	2026-09-12 16:21	51.09	OK	3228	2026-09-12 16:22	50.66	OK
3229	2026-09-12 16:23	50.24	OK	3230	2026-09-12 16:24	50.57	OK
3231	2026-09-12 16:25	50.61	OK	3232	2026-09-12 16:26	53.78	OK
3233	2026-09-12 16:27	51.78	OK	3234	2026-09-12 16:28	50.39	OK
3235	2026-09-12 16:29	50.97	OK	3236	2026-09-12 16:30	50.35	OK
3237	2026-09-12 16:31	50.26	OK	3238	2026-09-12 16:32	52.20	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3239	2026-09-12 16:33	49.04	OK	3240	2026-09-12 16:34	51.59	OK
3241	2026-09-12 16:35	51.28	OK	3242	2026-09-12 16:36	50.22	OK
3243	2026-09-12 16:37	51.39	OK	3244	2026-09-12 16:38	50.96	OK
3245	2026-09-12 16:39	52.00	OK	3246	2026-09-12 16:40	50.44	OK
3247	2026-09-12 16:41	49.06	OK	3248	2026-09-12 16:42	50.70	OK
3249	2026-09-12 16:43	51.70	OK	3250	2026-09-12 16:44	50.01	OK
3251	2026-09-12 16:45	51.83	OK	3252	2026-09-12 16:46	51.34	OK
3253	2026-09-12 16:47	49.75	OK	3254	2026-09-12 16:48	50.53	OK
3255	2026-09-12 16:49	48.39	OK	3256	2026-09-12 16:50	49.46	OK
3257	2026-09-12 16:51	49.69	OK	3258	2026-09-12 16:52	51.00	OK
3259	2026-09-12 16:53	52.00	OK	3260	2026-09-12 16:54	51.35	OK
3261	2026-09-12 16:55	48.57	OK	3262	2026-09-12 16:56	50.94	OK
3263	2026-09-12 16:57	51.28	OK	3264	2026-09-12 16:58	48.70	OK
3265	2026-09-12 16:59	49.68	OK	3266	2026-09-12 17:00	50.61	OK
3267	2026-09-12 17:01	48.28	OK	3268	2026-09-12 17:02	51.00	OK
3269	2026-09-12 17:03	50.61	OK	3270	2026-09-12 17:04	51.23	OK
3271	2026-09-12 17:05	51.20	OK	3272	2026-09-12 17:06	51.98	OK
3273	2026-09-12 17:07	48.23	OK	3274	2026-09-12 17:08	52.21	OK
3275	2026-09-12 17:09	48.51	OK	3276	2026-09-12 17:10	50.93	OK
3277	2026-09-12 17:11	51.55	OK	3278	2026-09-12 17:12	47.93	OK
3279	2026-09-12 17:13	48.73	OK	3280	2026-09-12 17:14	49.47	OK
3281	2026-09-12 17:15	48.64	OK	3282	2026-09-12 17:16	49.36	OK
3283	2026-09-12 17:17	50.71	OK	3284	2026-09-12 17:18	49.66	OK
3285	2026-09-12 17:19	49.90	OK	3286	2026-09-12 17:20	50.35	OK
3287	2026-09-12 17:21	49.08	OK	3288	2026-09-12 17:22	50.66	OK
3289	2026-09-12 17:23	49.98	OK	3290	2026-09-12 17:24	49.49	OK
3291	2026-09-12 17:25	49.81	OK	3292	2026-09-12 17:26	49.61	OK
3293	2026-09-12 17:27	49.55	OK	3294	2026-09-12 17:28	49.24	OK
3295	2026-09-12 17:29	49.83	OK	3296	2026-09-12 17:30	50.57	OK
3297	2026-09-12 17:31	49.73	OK	3298	2026-09-12 17:32	49.04	OK
3299	2026-09-12 17:33	48.49	OK	3300	2026-09-12 17:34	50.21	OK
3301	2026-09-12 17:35	50.40	OK	3302	2026-09-12 17:36	51.96	OK
3303	2026-09-12 17:37	48.74	OK	3304	2026-09-12 17:38	50.55	OK
3305	2026-09-12 17:39	48.27	OK	3306	2026-09-12 17:40	50.64	OK
3307	2026-09-12 17:41	50.73	OK	3308	2026-09-12 17:42	47.99	OK
3309	2026-09-12 17:43	47.69	OK	3310	2026-09-12 17:44	49.05	OK
3311	2026-09-12 17:45	49.56	OK	3312	2026-09-12 17:46	49.49	OK
3313	2026-09-12 17:47	49.93	OK	3314	2026-09-12 17:48	49.20	OK
3315	2026-09-12 17:49	47.39	OK	3316	2026-09-12 17:50	49.08	OK
3317	2026-09-12 17:51	48.24	OK	3318	2026-09-12 17:52	49.85	OK
3319	2026-09-12 17:53	48.83	OK	3320	2026-09-12 17:54	48.72	OK
3321	2026-09-12 17:55	50.02	OK	3322	2026-09-12 17:56	49.60	OK
3323	2026-09-12 17:57	50.36	OK	3324	2026-09-12 17:58	48.34	OK
3325	2026-09-12 17:59	50.60	OK	3326	2026-09-12 18:00	51.16	OK
3327	2026-09-12 18:01	47.77	OK	3328	2026-09-12 18:02	48.48	OK
3329	2026-09-12 18:03	48.52	OK	3330	2026-09-12 18:04	47.96	OK
3331	2026-09-12 18:05	50.07	OK	3332	2026-09-12 18:06	49.19	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3333	2026-09-12 18:07	47.40	OK	3334	2026-09-12 18:08	49.20	OK
3335	2026-09-12 18:09	49.49	OK	3336	2026-09-12 18:10	48.77	OK
3337	2026-09-12 18:11	46.24	OK	3338	2026-09-12 18:12	48.33	OK
3339	2026-09-12 18:13	46.08	OK	3340	2026-09-12 18:14	50.04	OK
3341	2026-09-12 18:15	48.41	OK	3342	2026-09-12 18:16	49.33	OK
3343	2026-09-12 18:17	48.10	OK	3344	2026-09-12 18:18	47.08	OK
3345	2026-09-12 18:19	48.42	OK	3346	2026-09-12 18:20	49.05	OK
3347	2026-09-12 18:21	48.69	OK	3348	2026-09-12 18:22	47.84	OK
3349	2026-09-12 18:23	46.85	OK	3350	2026-09-12 18:24	49.83	OK
3351	2026-09-12 18:25	47.73	OK	3352	2026-09-12 18:26	48.48	OK
3353	2026-09-12 18:27	47.80	OK	3354	2026-09-12 18:28	49.27	OK
3355	2026-09-12 18:29	46.84	OK	3356	2026-09-12 18:30	45.61	OK
3357	2026-09-12 18:31	46.45	OK	3358	2026-09-12 18:32	47.54	OK
3359	2026-09-12 18:33	47.62	OK	3360	2026-09-12 18:34	46.85	OK
3361	2026-09-12 18:35	47.52	OK	3362	2026-09-12 18:36	47.89	OK
3363	2026-09-12 18:37	48.04	OK	3364	2026-09-12 18:38	47.17	OK
3365	2026-09-12 18:39	47.93	OK	3366	2026-09-12 18:40	49.37	OK
3367	2026-09-12 18:41	50.08	OK	3368	2026-09-12 18:42	48.22	OK
3369	2026-09-12 18:43	46.55	OK	3370	2026-09-12 18:44	47.86	OK
3371	2026-09-12 18:45	47.56	OK	3372	2026-09-12 18:46	47.35	OK
3373	2026-09-12 18:47	46.45	OK	3374	2026-09-12 18:48	47.89	OK
3375	2026-09-12 18:49	48.31	OK	3376	2026-09-12 18:50	47.19	OK
3377	2026-09-12 18:51	47.52	OK	3378	2026-09-12 18:52	45.86	OK
3379	2026-09-12 18:53	46.77	OK	3380	2026-09-12 18:54	45.79	OK
3381	2026-09-12 18:55	49.27	OK	3382	2026-09-12 18:56	44.71	OK
3383	2026-09-12 18:57	47.26	OK	3384	2026-09-12 18:58	48.00	OK
3385	2026-09-12 18:59	46.46	OK	3386	2026-09-12 19:00	48.28	OK
3387	2026-09-12 19:01	47.20	OK	3388	2026-09-12 19:02	47.11	OK
3389	2026-09-12 19:03	46.68	OK	3390	2026-09-12 19:04	48.93	OK
3391	2026-09-12 19:05	47.29	OK	3392	2026-09-12 19:06	46.46	OK
3393	2026-09-12 19:07	46.94	OK	3394	2026-09-12 19:08	46.73	OK
3395	2026-09-12 19:09	46.64	OK	3396	2026-09-12 19:10	48.53	OK
3397	2026-09-12 19:11	47.40	OK	3398	2026-09-12 19:12	49.14	OK
3399	2026-09-12 19:13	47.34	OK	3400	2026-09-12 19:14	49.40	OK
3401	2026-09-12 19:15	47.52	OK	3402	2026-09-12 19:16	46.98	OK
3403	2026-09-12 19:17	47.18	OK	3404	2026-09-12 19:18	47.86	OK
3405	2026-09-12 19:19	47.79	OK	3406	2026-09-12 19:20	45.31	OK
3407	2026-09-12 19:21	47.18	OK	3408	2026-09-12 19:22	48.24	OK
3409	2026-09-12 19:23	49.58	OK	3410	2026-09-12 19:24	47.02	OK
3411	2026-09-12 19:25	47.27	OK	3412	2026-09-12 19:26	46.65	OK
3413	2026-09-12 19:27	44.55	OK	3414	2026-09-12 19:28	47.01	OK
3415	2026-09-12 19:29	47.92	OK	3416	2026-09-12 19:30	48.57	OK
3417	2026-09-12 19:31	44.57	OK	3418	2026-09-12 19:32	48.07	OK
3419	2026-09-12 19:33	47.49	OK	3420	2026-09-12 19:34	46.57	OK
3421	2026-09-12 19:35	45.26	OK	3422	2026-09-12 19:36	46.60	OK
3423	2026-09-12 19:37	48.34	OK	3424	2026-09-12 19:38	46.52	OK
3425	2026-09-12 19:39	46.49	OK	3426	2026-09-12 19:40	45.63	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3427	2026-09-12 19:41	47.79	OK	3428	2026-09-12 19:42	46.81	OK
3429	2026-09-12 19:43	47.68	OK	3430	2026-09-12 19:44	46.79	OK
3431	2026-09-12 19:45	47.10	OK	3432	2026-09-12 19:46	46.39	OK
3433	2026-09-12 19:47	46.27	OK	3434	2026-09-12 19:48	46.19	OK
3435	2026-09-12 19:49	45.07	OK	3436	2026-09-12 19:50	47.40	OK
3437	2026-09-12 19:51	46.10	OK	3438	2026-09-12 19:52	47.95	OK
3439	2026-09-12 19:53	47.74	OK	3440	2026-09-12 19:54	45.67	OK
3441	2026-09-12 19:55	45.22	OK	3442	2026-09-12 19:56	45.01	OK
3443	2026-09-12 19:57	45.54	OK	3444	2026-09-12 19:58	47.18	OK
3445	2026-09-12 19:59	45.21	OK	3446	2026-09-12 20:00	47.44	OK
3447	2026-09-12 20:01	47.11	OK	3448	2026-09-12 20:02	44.68	OK
3449	2026-09-12 20:03	44.24	OK	3450	2026-09-12 20:04	45.61	OK
3451	2026-09-12 20:05	46.34	OK	3452	2026-09-12 20:06	46.66	OK
3453	2026-09-12 20:07	47.88	OK	3454	2026-09-12 20:08	44.00	OK
3455	2026-09-12 20:09	46.49	OK	3456	2026-09-12 20:10	46.43	OK
3457	2026-09-12 20:11	46.04	OK	3458	2026-09-12 20:12	46.38	OK
3459	2026-09-12 20:13	45.18	OK	3460	2026-09-12 20:14	46.87	OK
3461	2026-09-12 20:15	49.04	OK	3462	2026-09-12 20:16	47.51	OK
3463	2026-09-12 20:17	46.52	OK	3464	2026-09-12 20:18	46.84	OK
3465	2026-09-12 20:19	45.06	OK	3466	2026-09-12 20:20	46.50	OK
3467	2026-09-12 20:21	45.48	OK	3468	2026-09-12 20:22	47.77	OK
3469	2026-09-12 20:23	46.64	OK	3470	2026-09-12 20:24	44.85	OK
3471	2026-09-12 20:25	46.21	OK	3472	2026-09-12 20:26	46.58	OK
3473	2026-09-12 20:27	46.55	OK	3474	2026-09-12 20:28	45.25	OK
3475	2026-09-12 20:29	46.91	OK	3476	2026-09-12 20:30	47.41	OK
3477	2026-09-12 20:31	44.49	OK	3478	2026-09-12 20:32	44.72	OK
3479	2026-09-12 20:33	46.34	OK	3480	2026-09-12 20:34	46.13	OK
3481	2026-09-12 20:35	46.27	OK	3482	2026-09-12 20:36	47.67	OK
3483	2026-09-12 20:37	46.85	OK	3484	2026-09-12 20:38	46.78	OK
3485	2026-09-12 20:39	48.14	OK	3486	2026-09-12 20:40	47.09	OK
3487	2026-09-12 20:41	46.23	OK	3488	2026-09-12 20:42	46.40	OK
3489	2026-09-12 20:43	46.50	OK	3490	2026-09-12 20:44	45.58	OK
3491	2026-09-12 20:45	47.72	OK	3492	2026-09-12 20:46	44.46	OK
3493	2026-09-12 20:47	44.09	OK	3494	2026-09-12 20:48	46.32	OK
3495	2026-09-12 20:49	46.53	OK	3496	2026-09-12 20:50	46.77	OK
3497	2026-09-12 20:51	45.58	OK	3498	2026-09-12 20:52	46.37	OK
3499	2026-09-12 20:53	46.62	OK	3500	2026-09-12 20:54	45.18	OK
3501	2026-09-12 20:55	44.42	OK	3502	2026-09-12 20:56	45.19	OK
3503	2026-09-12 20:57	47.09	OK	3504	2026-09-12 20:58	45.62	OK
3505	2026-09-12 20:59	44.90	OK	3506	2026-09-12 21:00	46.09	OK
3507	2026-09-12 21:01	44.53	OK	3508	2026-09-12 21:02	44.67	OK
3509	2026-09-12 21:03	43.18	OK	3510	2026-09-12 21:04	45.73	OK
3511	2026-09-12 21:05	44.04	OK	3512	2026-09-12 21:06	44.36	OK
3513	2026-09-12 21:07	44.73	OK	3514	2026-09-12 21:08	44.69	OK
3515	2026-09-12 21:09	43.22	OK	3516	2026-09-12 21:10	44.85	OK
3517	2026-09-12 21:11	44.01	OK	3518	2026-09-12 21:12	46.56	OK
3519	2026-09-12 21:13	44.86	OK	3520	2026-09-12 21:14	45.00	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3521	2026-09-12 21:15	45.46	OK	3522	2026-09-12 21:16	44.59	OK
3523	2026-09-12 21:17	46.21	OK	3524	2026-09-12 21:18	46.13	OK
3525	2026-09-12 21:19	46.00	OK	3526	2026-09-12 21:20	44.34	OK
3527	2026-09-12 21:21	44.19	OK	3528	2026-09-12 21:22	45.62	OK
3529	2026-09-12 21:23	45.77	OK	3530	2026-09-12 21:24	44.11	OK
3531	2026-09-12 21:25	45.17	OK	3532	2026-09-12 21:26	43.95	OK
3533	2026-09-12 21:27	45.39	OK	3534	2026-09-12 21:28	45.87	OK
3535	2026-09-12 21:29	44.00	OK	3536	2026-09-12 21:30	46.30	OK
3537	2026-09-12 21:31	45.39	OK	3538	2026-09-12 21:32	44.69	OK
3539	2026-09-12 21:33	44.89	OK	3540	2026-09-12 21:34	46.98	OK
3541	2026-09-12 21:35	47.84	OK	3542	2026-09-12 21:36	44.73	OK
3543	2026-09-12 21:37	44.86	OK	3544	2026-09-12 21:38	45.90	OK
3545	2026-09-12 21:39	44.76	OK	3546	2026-09-12 21:40	45.02	OK
3547	2026-09-12 21:41	45.15	OK	3548	2026-09-12 21:42	45.58	OK
3549	2026-09-12 21:43	43.94	OK	3550	2026-09-12 21:44	45.60	OK
3551	2026-09-12 21:45	44.70	OK	3552	2026-09-12 21:46	44.81	OK
3553	2026-09-12 21:47	46.49	OK	3554	2026-09-12 21:48	43.92	OK
3555	2026-09-12 21:49	45.81	OK	3556	2026-09-12 21:50	46.55	OK
3557	2026-09-12 21:51	45.61	OK	3558	2026-09-12 21:52	44.90	OK
3559	2026-09-12 21:53	45.32	OK	3560	2026-09-12 21:54	43.83	OK
3561	2026-09-12 21:55	46.31	OK	3562	2026-09-12 21:56	45.98	OK
3563	2026-09-12 21:57	44.68	OK	3564	2026-09-12 21:58	45.86	OK
3565	2026-09-12 21:59	44.98	OK	3566	2026-09-12 22:00	42.21	OK
3567	2026-09-12 22:01	46.52	OK	3568	2026-09-12 22:02	43.18	OK
3569	2026-09-12 22:03	45.33	OK	3570	2026-09-12 22:04	44.32	OK
3571	2026-09-12 22:05	44.60	OK	3572	2026-09-12 22:06	45.96	OK
3573	2026-09-12 22:07	45.62	OK	3574	2026-09-12 22:08	45.53	OK
3575	2026-09-12 22:09	43.83	OK	3576	2026-09-12 22:10	44.30	OK
3577	2026-09-12 22:11	43.39	OK	3578	2026-09-12 22:12	44.23	OK
3579	2026-09-12 22:13	46.53	OK	3580	2026-09-12 22:14	43.63	OK
3581	2026-09-12 22:15	44.49	OK	3582	2026-09-12 22:16	45.45	OK
3583	2026-09-12 22:17	43.92	OK	3584	2026-09-12 22:18	46.15	OK
3585	2026-09-12 22:19	45.13	OK	3586	2026-09-12 22:20	46.04	OK
3587	2026-09-12 22:21	44.68	OK	3588	2026-09-12 22:22	45.43	OK
3589	2026-09-12 22:23	46.00	OK	3590	2026-09-12 22:24	45.79	OK
3591	2026-09-12 22:25	43.56	OK	3592	2026-09-12 22:26	42.90	OK
3593	2026-09-12 22:27	42.77	OK	3594	2026-09-12 22:28	44.58	OK
3595	2026-09-12 22:29	44.18	OK	3596	2026-09-12 22:30	45.08	OK
3597	2026-09-12 22:31	44.51	OK	3598	2026-09-12 22:32	44.78	OK
3599	2026-09-12 22:33	43.26	OK	3600	2026-09-12 22:34	45.89	OK
3601	2026-09-12 22:35	44.02	OK	3602	2026-09-12 22:36	44.38	OK
3603	2026-09-12 22:37	45.65	OK	3604	2026-09-12 22:38	46.26	OK
3605	2026-09-12 22:39	43.67	OK	3606	2026-09-12 22:40	43.94	OK
3607	2026-09-12 22:41	44.86	OK	3608	2026-09-12 22:42	43.39	OK
3609	2026-09-12 22:43	44.06	OK	3610	2026-09-12 22:44	45.77	OK
3611	2026-09-12 22:45	45.28	OK	3612	2026-09-12 22:46	43.86	OK
3613	2026-09-12 22:47	44.15	OK	3614	2026-09-12 22:48	42.51	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3615	2026-09-12 22:49	43.86	OK	3616	2026-09-12 22:50	46.15	OK
3617	2026-09-12 22:51	43.53	OK	3618	2026-09-12 22:52	46.02	OK
3619	2026-09-12 22:53	45.19	OK	3620	2026-09-12 22:54	43.93	OK
3621	2026-09-12 22:55	44.77	OK	3622	2026-09-12 22:56	42.77	OK
3623	2026-09-12 22:57	45.11	OK	3624	2026-09-12 22:58	44.96	OK
3625	2026-09-12 22:59	42.97	OK	3626	2026-09-12 23:00	44.71	OK
3627	2026-09-12 23:01	44.73	OK	3628	2026-09-12 23:02	44.31	OK
3629	2026-09-12 23:03	45.27	OK	3630	2026-09-12 23:04	42.04	OK
3631	2026-09-12 23:05	45.83	OK	3632	2026-09-12 23:06	43.78	OK
3633	2026-09-12 23:07	43.94	OK	3634	2026-09-12 23:08	45.50	OK
3635	2026-09-12 23:09	45.89	OK	3636	2026-09-12 23:10	44.01	OK
3637	2026-09-12 23:11	45.87	OK	3638	2026-09-12 23:12	44.94	OK
3639	2026-09-12 23:13	44.68	OK	3640	2026-09-12 23:14	46.35	OK
3641	2026-09-12 23:15	44.64	OK	3642	2026-09-12 23:16	43.54	OK
3643	2026-09-12 23:17	45.41	OK	3644	2026-09-12 23:18	43.80	OK
3645	2026-09-12 23:19	46.63	OK	3646	2026-09-12 23:20	45.83	OK
3647	2026-09-12 23:21	44.57	OK	3648	2026-09-12 23:22	44.05	OK
3649	2026-09-12 23:23	44.50	OK	3650	2026-09-12 23:24	45.84	OK
3651	2026-09-12 23:25	45.60	OK	3652	2026-09-12 23:26	45.14	OK
3653	2026-09-12 23:27	43.39	OK	3654	2026-09-12 23:28	45.16	OK
3655	2026-09-12 23:29	45.62	OK	3656	2026-09-12 23:30	45.84	OK
3657	2026-09-12 23:31	43.77	OK	3658	2026-09-12 23:32	44.21	OK
3659	2026-09-12 23:33	44.75	OK	3660	2026-09-12 23:34	45.57	OK
3661	2026-09-12 23:35	46.06	OK	3662	2026-09-12 23:36	43.41	OK
3663	2026-09-12 23:37	43.54	OK	3664	2026-09-12 23:38	44.59	OK
3665	2026-09-12 23:39	45.10	OK	3666	2026-09-12 23:40	42.64	OK
3667	2026-09-12 23:41	42.73	OK	3668	2026-09-12 23:42	45.03	OK
3669	2026-09-12 23:43	43.57	OK	3670	2026-09-12 23:44	44.18	OK
3671	2026-09-12 23:45	44.15	OK	3672	2026-09-12 23:46	45.17	OK
3673	2026-09-12 23:47	46.35	OK	3674	2026-09-12 23:48	45.53	OK
3675	2026-09-12 23:49	44.01	OK	3676	2026-09-12 23:50	44.24	OK
3677	2026-09-12 23:51	44.70	OK	3678	2026-09-12 23:52	43.66	OK
3679	2026-09-12 23:53	44.80	OK	3680	2026-09-12 23:54	44.41	OK
3681	2026-09-12 23:55	43.90	OK	3682	2026-09-12 23:56	43.31	OK
3683	2026-09-12 23:57	44.53	OK	3684	2026-09-12 23:58	43.45	OK
3685	2026-09-12 23:59	44.74	OK	3686	2026-09-13 00:00	45.96	OK
3687	2026-09-13 00:01	43.70	OK	3688	2026-09-13 00:02	44.42	OK
3689	2026-09-13 00:03	45.10	OK	3690	2026-09-13 00:04	43.60	OK
3691	2026-09-13 00:05	41.69	OK	3692	2026-09-13 00:06	44.39	OK
3693	2026-09-13 00:07	45.31	OK	3694	2026-09-13 00:08	42.92	OK
3695	2026-09-13 00:09	46.18	OK	3696	2026-09-13 00:10	42.48	OK
3697	2026-09-13 00:11	43.89	OK	3698	2026-09-13 00:12	46.31	OK
3699	2026-09-13 00:13	43.80	OK	3700	2026-09-13 00:14	47.34	OK
3701	2026-09-13 00:15	44.58	OK	3702	2026-09-13 00:16	44.26	OK
3703	2026-09-13 00:17	42.36	OK	3704	2026-09-13 00:18	43.87	OK
3705	2026-09-13 00:19	45.06	OK	3706	2026-09-13 00:20	43.06	OK
3707	2026-09-13 00:21	45.36	OK	3708	2026-09-13 00:22	43.90	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3709	2026-09-13 00:23	44.83	OK	3710	2026-09-13 00:24	45.71	OK
3711	2026-09-13 00:25	45.05	OK	3712	2026-09-13 00:26	46.46	OK
3713	2026-09-13 00:27	46.33	OK	3714	2026-09-13 00:28	43.48	OK
3715	2026-09-13 00:29	45.20	OK	3716	2026-09-13 00:30	46.33	OK
3717	2026-09-13 00:31	44.11	OK	3718	2026-09-13 00:32	44.55	OK
3719	2026-09-13 00:33	46.86	OK	3720	2026-09-13 00:34	43.86	OK
3721	2026-09-13 00:35	46.71	OK	3722	2026-09-13 00:36	42.70	OK
3723	2026-09-13 00:37	44.07	OK	3724	2026-09-13 00:38	47.34	OK
3725	2026-09-13 00:39	43.70	OK	3726	2026-09-13 00:40	45.89	OK
3727	2026-09-13 00:41	44.98	OK	3728	2026-09-13 00:42	46.34	OK
3729	2026-09-13 00:43	45.15	OK	3730	2026-09-13 00:44	44.61	OK
3731	2026-09-13 00:45	42.39	OK	3732	2026-09-13 00:46	45.82	OK
3733	2026-09-13 00:47	45.10	OK	3734	2026-09-13 00:48	44.44	OK
3735	2026-09-13 00:49	44.28	OK	3736	2026-09-13 00:50	44.02	OK
3737	2026-09-13 00:51	45.49	OK	3738	2026-09-13 00:52	44.38	OK
3739	2026-09-13 00:53	45.40	OK	3740	2026-09-13 00:54	43.07	OK
3741	2026-09-13 00:55	46.37	OK	3742	2026-09-13 00:56	46.01	OK
3743	2026-09-13 00:57	45.86	OK	3744	2026-09-13 00:58	44.24	OK
3745	2026-09-13 00:59	46.63	OK	3746	2026-09-13 01:00	44.70	OK
3747	2026-09-13 01:01	44.32	OK	3748	2026-09-13 01:02	45.71	OK
3749	2026-09-13 01:03	44.17	OK	3750	2026-09-13 01:04	44.14	OK
3751	2026-09-13 01:05	45.86	OK	3752	2026-09-13 01:06	45.02	OK
3753	2026-09-13 01:07	43.36	OK	3754	2026-09-13 01:08	44.34	OK
3755	2026-09-13 01:09	45.97	OK	3756	2026-09-13 01:10	44.52	OK
3757	2026-09-13 01:11	44.49	OK	3758	2026-09-13 01:12	45.27	OK
3759	2026-09-13 01:13	46.01	OK	3760	2026-09-13 01:14	47.76	OK
3761	2026-09-13 01:15	45.42	OK	3762	2026-09-13 01:16	46.08	OK
3763	2026-09-13 01:17	46.66	OK	3764	2026-09-13 01:18	42.92	OK
3765	2026-09-13 01:19	45.83	OK	3766	2026-09-13 01:20	44.40	OK
3767	2026-09-13 01:21	45.35	OK	3768	2026-09-13 01:22	46.17	OK
3769	2026-09-13 01:23	44.21	OK	3770	2026-09-13 01:24	45.25	OK
3771	2026-09-13 01:25	46.04	OK	3772	2026-09-13 01:26	47.30	OK
3773	2026-09-13 01:27	46.44	OK	3774	2026-09-13 01:28	45.39	OK
3775	2026-09-13 01:29	45.13	OK	3776	2026-09-13 01:30	44.53	OK
3777	2026-09-13 01:31	44.78	OK	3778	2026-09-13 01:32	46.04	OK
3779	2026-09-13 01:33	44.66	OK	3780	2026-09-13 01:34	45.31	OK
3781	2026-09-13 01:35	46.92	OK	3782	2026-09-13 01:36	44.69	OK
3783	2026-09-13 01:37	46.48	OK	3784	2026-09-13 01:38	46.36	OK
3785	2026-09-13 01:39	44.39	OK	3786	2026-09-13 01:40	45.90	OK
3787	2026-09-13 01:41	44.34	OK	3788	2026-09-13 01:42	44.99	OK
3789	2026-09-13 01:43	45.53	OK	3790	2026-09-13 01:44	45.74	OK
3791	2026-09-13 01:45	45.97	OK	3792	2026-09-13 01:46	46.46	OK
3793	2026-09-13 01:47	43.65	OK	3794	2026-09-13 01:48	46.57	OK
3795	2026-09-13 01:49	47.63	OK	3796	2026-09-13 01:50	45.99	OK
3797	2026-09-13 01:51	44.79	OK	3798	2026-09-13 01:52	46.32	OK
3799	2026-09-13 01:53	46.19	OK	3800	2026-09-13 01:54	45.13	OK
3801	2026-09-13 01:55	45.19	OK	3802	2026-09-13 01:56	44.83	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3803	2026-09-13 01:57	45.50	OK	3804	2026-09-13 01:58	46.93	OK
3805	2026-09-13 01:59	45.78	OK	3806	2026-09-13 02:00	47.61	OK
3807	2026-09-13 02:01	45.50	OK	3808	2026-09-13 02:02	44.39	OK
3809	2026-09-13 02:03	47.59	OK	3810	2026-09-13 02:04	45.34	OK
3811	2026-09-13 02:05	46.95	OK	3812	2026-09-13 02:06	46.11	OK
3813	2026-09-13 02:07	46.41	OK	3814	2026-09-13 02:08	45.07	OK
3815	2026-09-13 02:09	47.26	OK	3816	2026-09-13 02:10	45.99	OK
3817	2026-09-13 02:11	46.39	OK	3818	2026-09-13 02:12	45.90	OK
3819	2026-09-13 02:13	43.63	OK	3820	2026-09-13 02:14	45.19	OK
3821	2026-09-13 02:15	45.41	OK	3822	2026-09-13 02:16	44.74	OK
3823	2026-09-13 02:17	47.55	OK	3824	2026-09-13 02:18	43.91	OK
3825	2026-09-13 02:19	46.72	OK	3826	2026-09-13 02:20	44.47	OK
3827	2026-09-13 02:21	43.94	OK	3828	2026-09-13 02:22	43.78	OK
3829	2026-09-13 02:23	46.25	OK	3830	2026-09-13 02:24	46.91	OK
3831	2026-09-13 02:25	45.27	OK	3832	2026-09-13 02:26	47.22	OK
3833	2026-09-13 02:27	45.41	OK	3834	2026-09-13 02:28	46.08	OK
3835	2026-09-13 02:29	47.51	OK	3836	2026-09-13 02:30	46.71	OK
3837	2026-09-13 02:31	45.74	OK	3838	2026-09-13 02:32	43.32	OK
3839	2026-09-13 02:33	46.18	OK	3840	2026-09-13 02:34	47.58	OK
3841	2026-09-13 02:35	46.87	OK	3842	2026-09-13 02:36	47.80	OK
3843	2026-09-13 02:37	46.44	OK	3844	2026-09-13 02:38	46.22	OK
3845	2026-09-13 02:39	46.67	OK	3846	2026-09-13 02:40	44.98	OK
3847	2026-09-13 02:41	45.17	OK	3848	2026-09-13 02:42	47.11	OK
3849	2026-09-13 02:43	46.72	OK	3850	2026-09-13 02:44	46.60	OK
3851	2026-09-13 02:45	47.08	OK	3852	2026-09-13 02:46	48.65	OK
3853	2026-09-13 02:47	47.08	OK	3854	2026-09-13 02:48	45.93	OK
3855	2026-09-13 02:49	45.03	OK	3856	2026-09-13 02:50	46.86	OK
3857	2026-09-13 02:51	46.20	OK	3858	2026-09-13 02:52	45.41	OK
3859	2026-09-13 02:53	48.83	OK	3860	2026-09-13 02:54	46.91	OK
3861	2026-09-13 02:55	46.73	OK	3862	2026-09-13 02:56	47.15	OK
3863	2026-09-13 02:57	46.30	OK	3864	2026-09-13 02:58	46.47	OK
3865	2026-09-13 02:59	48.49	OK	3866	2026-09-13 03:00	46.47	OK
3867	2026-09-13 03:01	45.12	OK	3868	2026-09-13 03:02	47.25	OK
3869	2026-09-13 03:03	47.88	OK	3870	2026-09-13 03:04	45.29	OK
3871	2026-09-13 03:05	47.44	OK	3872	2026-09-13 03:06	46.05	OK
3873	2026-09-13 03:07	47.09	OK	3874	2026-09-13 03:08	45.17	OK
3875	2026-09-13 03:09	46.37	OK	3876	2026-09-13 03:10	46.69	OK
3877	2026-09-13 03:11	47.18	OK	3878	2026-09-13 03:12	48.40	OK
3879	2026-09-13 03:13	46.63	OK	3880	2026-09-13 03:14	46.74	OK
3881	2026-09-13 03:15	47.09	OK	3882	2026-09-13 03:16	47.42	OK
3883	2026-09-13 03:17	46.04	OK	3884	2026-09-13 03:18	47.15	OK
3885	2026-09-13 03:19	45.11	OK	3886	2026-09-13 03:20	47.44	OK
3887	2026-09-13 03:21	45.42	OK	3888	2026-09-13 03:22	47.61	OK
3889	2026-09-13 03:23	47.41	OK	3890	2026-09-13 03:24	46.90	OK
3891	2026-09-13 03:25	45.51	OK	3892	2026-09-13 03:26	47.62	OK
3893	2026-09-13 03:27	47.75	OK	3894	2026-09-13 03:28	47.21	OK
3895	2026-09-13 03:29	45.41	OK	3896	2026-09-13 03:30	44.49	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3897	2026-09-13 03:31	48.55	OK	3898	2026-09-13 03:32	46.64	OK
3899	2026-09-13 03:33	48.15	OK	3900	2026-09-13 03:34	48.54	OK
3901	2026-09-13 03:35	47.34	OK	3902	2026-09-13 03:36	46.00	OK
3903	2026-09-13 03:37	46.83	OK	3904	2026-09-13 03:38	48.84	OK
3905	2026-09-13 03:39	47.75	OK	3906	2026-09-13 03:40	46.28	OK
3907	2026-09-13 03:41	45.30	OK	3908	2026-09-13 03:42	48.32	OK
3909	2026-09-13 03:43	45.64	OK	3910	2026-09-13 03:44	47.57	OK
3911	2026-09-13 03:45	47.07	OK	3912	2026-09-13 03:46	47.21	OK
3913	2026-09-13 03:47	47.01	OK	3914	2026-09-13 03:48	47.21	OK
3915	2026-09-13 03:49	46.71	OK	3916	2026-09-13 03:50	48.14	OK
3917	2026-09-13 03:51	46.25	OK	3918	2026-09-13 03:52	45.08	OK
3919	2026-09-13 03:53	49.60	OK	3920	2026-09-13 03:54	47.44	OK
3921	2026-09-13 03:55	45.53	OK	3922	2026-09-13 03:56	46.97	OK
3923	2026-09-13 03:57	47.04	OK	3924	2026-09-13 03:58	46.70	OK
3925	2026-09-13 03:59	49.15	OK	3926	2026-09-13 04:00	48.26	OK
3927	2026-09-13 04:01	45.10	OK	3928	2026-09-13 04:02	45.38	OK
3929	2026-09-13 04:03	49.16	OK	3930	2026-09-13 04:04	49.59	OK
3931	2026-09-13 04:05	47.92	OK	3932	2026-09-13 04:06	46.95	OK
3933	2026-09-13 04:07	47.78	OK	3934	2026-09-13 04:08	46.23	OK
3935	2026-09-13 04:09	45.94	OK	3936	2026-09-13 04:10	46.37	OK
3937	2026-09-13 04:11	47.07	OK	3938	2026-09-13 04:12	49.60	OK
3939	2026-09-13 04:13	50.27	OK	3940	2026-09-13 04:14	48.74	OK
3941	2026-09-13 04:15	49.46	OK	3942	2026-09-13 04:16	47.11	OK
3943	2026-09-13 04:17	47.26	OK	3944	2026-09-13 04:18	47.09	OK
3945	2026-09-13 04:19	48.37	OK	3946	2026-09-13 04:20	46.48	OK
3947	2026-09-13 04:21	48.09	OK	3948	2026-09-13 04:22	46.88	OK
3949	2026-09-13 04:23	46.52	OK	3950	2026-09-13 04:24	47.14	OK
3951	2026-09-13 04:25	46.50	OK	3952	2026-09-13 04:26	46.68	OK
3953	2026-09-13 04:27	48.76	OK	3954	2026-09-13 04:28	48.22	OK
3955	2026-09-13 04:29	48.43	OK	3956	2026-09-13 04:30	46.85	OK
3957	2026-09-13 04:31	47.94	OK	3958	2026-09-13 04:32	48.75	OK
3959	2026-09-13 04:33	49.37	OK	3960	2026-09-13 04:34	48.44	OK
3961	2026-09-13 04:35	48.10	OK	3962	2026-09-13 04:36	48.17	OK
3963	2026-09-13 04:37	47.13	OK	3964	2026-09-13 04:38	46.46	OK
3965	2026-09-13 04:39	48.35	OK	3966	2026-09-13 04:40	48.64	OK
3967	2026-09-13 04:41	48.03	OK	3968	2026-09-13 04:42	48.42	OK
3969	2026-09-13 04:43	49.25	OK	3970	2026-09-13 04:44	48.51	OK
3971	2026-09-13 04:45	49.38	OK	3972	2026-09-13 04:46	48.54	OK
3973	2026-09-13 04:47	50.91	OK	3974	2026-09-13 04:48	49.51	OK
3975	2026-09-13 04:49	48.69	OK	3976	2026-09-13 04:50	50.59	OK
3977	2026-09-13 04:51	49.43	OK	3978	2026-09-13 04:52	48.73	OK
3979	2026-09-13 04:53	50.50	OK	3980	2026-09-13 04:54	46.83	OK
3981	2026-09-13 04:55	47.73	OK	3982	2026-09-13 04:56	47.64	OK
3983	2026-09-13 04:57	49.98	OK	3984	2026-09-13 04:58	48.16	OK
3985	2026-09-13 04:59	48.24	OK	3986	2026-09-13 05:00	49.12	OK
3987	2026-09-13 05:01	49.55	OK	3988	2026-09-13 05:02	48.04	OK
3989	2026-09-13 05:03	47.60	OK	3990	2026-09-13 05:04	47.02	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3991	2026-09-13 05:05	49.63	OK	3992	2026-09-13 05:06	51.49	OK
3993	2026-09-13 05:07	49.34	OK	3994	2026-09-13 05:08	50.39	OK
3995	2026-09-13 05:09	48.76	OK	3996	2026-09-13 05:10	49.44	OK
3997	2026-09-13 05:11	50.35	OK	3998	2026-09-13 05:12	47.96	OK
3999	2026-09-13 05:13	50.49	OK	4000	2026-09-13 05:14	48.78	OK
4001	2026-09-13 05:15	49.42	OK	4002	2026-09-13 05:16	49.44	OK
4003	2026-09-13 05:17	49.86	OK	4004	2026-09-13 05:18	48.80	OK
4005	2026-09-13 05:19	50.54	OK	4006	2026-09-13 05:20	50.73	OK
4007	2026-09-13 05:21	49.96	OK	4008	2026-09-13 05:22	50.73	OK
4009	2026-09-13 05:23	50.65	OK	4010	2026-09-13 05:24	49.42	OK
4011	2026-09-13 05:25	50.78	OK	4012	2026-09-13 05:26	50.16	OK
4013	2026-09-13 05:27	48.17	OK	4014	2026-09-13 05:28	51.06	OK
4015	2026-09-13 05:29	49.24	OK	4016	2026-09-13 05:30	49.31	OK
4017	2026-09-13 05:31	48.32	OK	4018	2026-09-13 05:32	51.01	OK
4019	2026-09-13 05:33	48.89	OK	4020	2026-09-13 05:34	48.77	OK
4021	2026-09-13 05:35	47.91	OK	4022	2026-09-13 05:36	50.42	OK
4023	2026-09-13 05:37	49.03	OK	4024	2026-09-13 05:38	50.82	OK
4025	2026-09-13 05:39	49.18	OK	4026	2026-09-13 05:40	48.44	OK
4027	2026-09-13 05:41	50.22	OK	4028	2026-09-13 05:42	50.28	OK
4029	2026-09-13 05:43	48.16	OK	4030	2026-09-13 05:44	50.22	OK
4031	2026-09-13 05:45	51.69	OK	4032	2026-09-13 05:46	49.28	OK
4033	2026-09-13 05:47	49.39	OK	4034	2026-09-13 05:48	49.43	OK
4035	2026-09-13 05:49	51.70	OK	4036	2026-09-13 05:50	51.99	OK
4037	2026-09-13 05:51	51.90	OK	4038	2026-09-13 05:52	50.21	OK
4039	2026-09-13 05:53	51.09	OK	4040	2026-09-13 05:54	51.74	OK
4041	2026-09-13 05:55	49.75	OK	4042	2026-09-13 05:56	49.64	OK
4043	2026-09-13 05:57	48.83	OK	4044	2026-09-13 05:58	51.86	OK
4045	2026-09-13 05:59	50.75	OK	4046	2026-09-13 06:00	48.76	OK
4047	2026-09-13 06:01	49.10	OK	4048	2026-09-13 06:02	49.29	OK
4049	2026-09-13 06:03	47.46	OK	4050	2026-09-13 06:04	49.94	OK
4051	2026-09-13 06:05	50.09	OK	4052	2026-09-13 06:06	50.05	OK
4053	2026-09-13 06:07	50.64	OK	4054	2026-09-13 06:08	49.81	OK
4055	2026-09-13 06:09	49.37	OK	4056	2026-09-13 06:10	50.07	OK
4057	2026-09-13 06:11	50.28	OK	4058	2026-09-13 06:12	50.31	OK
4059	2026-09-13 06:13	49.17	OK	4060	2026-09-13 06:14	51.58	OK
4061	2026-09-13 06:15	51.31	OK	4062	2026-09-13 06:16	50.56	OK
4063	2026-09-13 06:17	50.89	OK	4064	2026-09-13 06:18	49.10	OK
4065	2026-09-13 06:19	53.18	OK	4066	2026-09-13 06:20	50.93	OK
4067	2026-09-13 06:21	50.53	OK	4068	2026-09-13 06:22	50.13	OK
4069	2026-09-13 06:23	52.47	OK	4070	2026-09-13 06:24	48.84	OK
4071	2026-09-13 06:25	51.09	OK	4072	2026-09-13 06:26	48.61	OK
4073	2026-09-13 06:27	50.42	OK	4074	2026-09-13 06:28	52.03	OK
4075	2026-09-13 06:29	53.07	OK	4076	2026-09-13 06:30	49.95	OK
4077	2026-09-13 06:31	51.15	OK	4078	2026-09-13 06:32	50.14	OK
4079	2026-09-13 06:33	51.70	OK	4080	2026-09-13 06:34	50.32	OK
4081	2026-09-13 06:35	53.10	OK	4082	2026-09-13 06:36	51.83	OK
4083	2026-09-13 06:37	51.29	OK	4084	2026-09-13 06:38	51.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4085	2026-09-13 06:39	49.85	OK	4086	2026-09-13 06:40	50.72	OK
4087	2026-09-13 06:41	50.98	OK	4088	2026-09-13 06:42	51.21	OK
4089	2026-09-13 06:43	51.45	OK	4090	2026-09-13 06:44	50.73	OK
4091	2026-09-13 06:45	50.68	OK	4092	2026-09-13 06:46	50.49	OK
4093	2026-09-13 06:47	48.74	OK	4094	2026-09-13 06:48	48.79	OK
4095	2026-09-13 06:49	51.19	OK	4096	2026-09-13 06:50	51.80	OK
4097	2026-09-13 06:51	53.28	OK	4098	2026-09-13 06:52	51.12	OK
4099	2026-09-13 06:53	50.69	OK	4100	2026-09-13 06:54	52.51	OK
4101	2026-09-13 06:55	50.91	OK	4102	2026-09-13 06:56	50.01	OK
4103	2026-09-13 06:57	52.18	OK	4104	2026-09-13 06:58	49.64	OK
4105	2026-09-13 06:59	48.96	OK	4106	2026-09-13 07:00	51.47	OK
4107	2026-09-13 07:01	49.37	OK	4108	2026-09-13 07:02	52.56	OK
4109	2026-09-13 07:03	52.33	OK	4110	2026-09-13 07:04	49.58	OK
4111	2026-09-13 07:05	50.93	OK	4112	2026-09-13 07:06	50.43	OK
4113	2026-09-13 07:07	49.41	OK	4114	2026-09-13 07:08	49.94	OK
4115	2026-09-13 07:09	50.63	OK	4116	2026-09-13 07:10	51.56	OK
4117	2026-09-13 07:11	50.84	OK	4118	2026-09-13 07:12	50.53	OK
4119	2026-09-13 07:13	54.00	OK	4120	2026-09-13 07:14	51.53	OK
4121	2026-09-13 07:15	51.24	OK	4122	2026-09-13 07:16	53.04	OK
4123	2026-09-13 07:17	51.35	OK	4124	2026-09-13 07:18	52.08	OK
4125	2026-09-13 07:19	52.74	OK	4126	2026-09-13 07:20	50.21	OK
4127	2026-09-13 07:21	51.46	OK	4128	2026-09-13 07:22	51.83	OK
4129	2026-09-13 07:23	52.24	OK	4130	2026-09-13 07:24	50.54	OK
4131	2026-09-13 07:25	52.22	OK	4132	2026-09-13 07:26	51.82	OK
4133	2026-09-13 07:27	51.62	OK	4134	2026-09-13 07:28	52.41	OK
4135	2026-09-13 07:29	52.94	OK	4136	2026-09-13 07:30	51.24	OK
4137	2026-09-13 07:31	51.50	OK	4138	2026-09-13 07:32	50.45	OK
4139	2026-09-13 07:33	53.18	OK	4140	2026-09-13 07:34	52.16	OK
4141	2026-09-13 07:35	50.71	OK	4142	2026-09-13 07:36	50.89	OK
4143	2026-09-13 07:37	52.17	OK	4144	2026-09-13 07:38	50.37	OK
4145	2026-09-13 07:39	53.88	OK	4146	2026-09-13 07:40	51.49	OK
4147	2026-09-13 07:41	52.52	OK	4148	2026-09-13 07:42	51.04	OK
4149	2026-09-13 07:43	53.25	OK	4150	2026-09-13 07:44	53.38	OK
4151	2026-09-13 07:45	53.59	OK	4152	2026-09-13 07:46	50.87	OK
4153	2026-09-13 07:47	51.94	OK	4154	2026-09-13 07:48	50.96	OK
4155	2026-09-13 07:49	51.68	OK	4156	2026-09-13 07:50	51.96	OK
4157	2026-09-13 07:51	51.56	OK	4158	2026-09-13 07:52	54.42	OK
4159	2026-09-13 07:53	52.17	OK	4160	2026-09-13 07:54	52.52	OK
4161	2026-09-13 07:55	52.22	OK	4162	2026-09-13 07:56	52.36	OK
4163	2026-09-13 07:57	53.48	OK	4164	2026-09-13 07:58	51.18	OK
4165	2026-09-13 07:59	53.23	OK	4166	2026-09-13 08:00	53.22	OK
4167	2026-09-13 08:01	51.18	OK	4168	2026-09-13 08:02	54.71	OK
4169	2026-09-13 08:03	53.70	OK	4170	2026-09-13 08:04	52.63	OK
4171	2026-09-13 08:05	51.74	OK	4172	2026-09-13 08:06	52.87	OK
4173	2026-09-13 08:07	53.34	OK	4174	2026-09-13 08:08	51.64	OK
4175	2026-09-13 08:09	53.58	OK	4176	2026-09-13 08:10	54.17	OK
4177	2026-09-13 08:11	53.16	OK	4178	2026-09-13 08:12	53.53	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4179	2026-09-13 08:13	54.52	OK	4180	2026-09-13 08:14	51.12	OK
4181	2026-09-13 08:15	52.17	OK	4182	2026-09-13 08:16	53.10	OK
4183	2026-09-13 08:17	52.83	OK	4184	2026-09-13 08:18	52.21	OK
4185	2026-09-13 08:19	52.23	OK	4186	2026-09-13 08:20	51.86	OK
4187	2026-09-13 08:21	52.91	OK	4188	2026-09-13 08:22	52.37	OK
4189	2026-09-13 08:23	52.31	OK	4190	2026-09-13 08:24	51.40	OK
4191	2026-09-13 08:25	51.94	OK	4192	2026-09-13 08:26	52.44	OK
4193	2026-09-13 08:27	52.07	OK	4194	2026-09-13 08:28	53.60	OK
4195	2026-09-13 08:29	53.14	OK	4196	2026-09-13 08:30	54.14	OK
4197	2026-09-13 08:31	52.93	OK	4198	2026-09-13 08:32	52.65	OK
4199	2026-09-13 08:33	50.43	OK	4200	2026-09-13 08:34	54.00	OK
4201	2026-09-13 08:35	54.06	OK	4202	2026-09-13 08:36	52.12	OK
4203	2026-09-13 08:37	54.24	OK	4204	2026-09-13 08:38	54.61	OK
4205	2026-09-13 08:39	53.64	OK	4206	2026-09-13 08:40	51.43	OK
4207	2026-09-13 08:41	53.36	OK	4208	2026-09-13 08:42	53.08	OK
4209	2026-09-13 08:43	52.69	OK	4210	2026-09-13 08:44	54.59	OK
4211	2026-09-13 08:45	53.23	OK	4212	2026-09-13 08:46	50.37	OK
4213	2026-09-13 08:47	51.46	OK	4214	2026-09-13 08:48	52.37	OK
4215	2026-09-13 08:49	52.92	OK	4216	2026-09-13 08:50	53.31	OK
4217	2026-09-13 08:51	54.22	OK	4218	2026-09-13 08:52	52.66	OK
4219	2026-09-13 08:53	52.34	OK	4220	2026-09-13 08:54	53.29	OK
4221	2026-09-13 08:55	54.33	OK	4222	2026-09-13 08:56	52.88	OK
4223	2026-09-13 08:57	52.81	OK	4224	2026-09-13 08:58	53.88	OK
4225	2026-09-13 08:59	52.02	OK	4226	2026-09-13 09:00	53.54	OK
4227	2026-09-13 09:01	53.47	OK	4228	2026-09-13 09:02	54.24	OK
4229	2026-09-13 09:03	54.03	OK	4230	2026-09-13 09:04	52.65	OK
4231	2026-09-13 09:05	52.94	OK	4232	2026-09-13 09:06	53.02	OK
4233	2026-09-13 09:07	53.14	OK	4234	2026-09-13 09:08	51.26	OK
4235	2026-09-13 09:09	52.70	OK	4236	2026-09-13 09:10	51.53	OK
4237	2026-09-13 09:11	54.30	OK	4238	2026-09-13 09:12	53.06	OK
4239	2026-09-13 09:13	53.09	OK	4240	2026-09-13 09:14	53.03	OK
4241	2026-09-13 09:15	52.89	OK	4242	2026-09-13 09:16	53.14	OK
4243	2026-09-13 09:17	53.58	OK	4244	2026-09-13 09:18	52.71	OK
4245	2026-09-13 09:19	53.38	OK	4246	2026-09-13 09:20	53.39	OK
4247	2026-09-13 09:21	53.05	OK	4248	2026-09-13 09:22	53.85	OK
4249	2026-09-13 09:23	54.53	OK	4250	2026-09-13 09:24	52.25	OK
4251	2026-09-13 09:25	54.15	OK	4252	2026-09-13 09:26	52.87	OK
4253	2026-09-13 09:27	53.73	OK	4254	2026-09-13 09:28	54.43	OK
4255	2026-09-13 09:29	52.14	OK	4256	2026-09-13 09:30	53.39	OK
4257	2026-09-13 09:31	56.26	OK	4258	2026-09-13 09:32	54.05	OK
4259	2026-09-13 09:33	56.20	OK	4260	2026-09-13 09:34	53.01	OK
4261	2026-09-13 09:35	52.26	OK	4262	2026-09-13 09:36	52.04	OK
4263	2026-09-13 09:37	52.60	OK	4264	2026-09-13 09:38	55.02	OK
4265	2026-09-13 09:39	50.99	OK	4266	2026-09-13 09:40	53.70	OK
4267	2026-09-13 09:41	52.80	OK	4268	2026-09-13 09:42	51.71	OK
4269	2026-09-13 09:43	53.67	OK	4270	2026-09-13 09:44	54.93	OK
4271	2026-09-13 09:45	53.88	OK	4272	2026-09-13 09:46	53.99	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4273	2026-09-13 09:47	53.58	OK	4274	2026-09-13 09:48	53.34	OK
4275	2026-09-13 09:49	54.54	OK	4276	2026-09-13 09:50	52.05	OK
4277	2026-09-13 09:51	53.39	OK	4278	2026-09-13 09:52	54.52	OK
4279	2026-09-13 09:53	51.82	OK	4280	2026-09-13 09:54	54.15	OK
4281	2026-09-13 09:55	55.31	OK	4282	2026-09-13 09:56	53.70	OK
4283	2026-09-13 09:57	53.66	OK	4284	2026-09-13 09:58	55.36	OK
4285	2026-09-13 09:59	54.73	OK	4286	2026-09-13 10:00	54.46	OK
4287	2026-09-13 10:01	54.99	OK	4288	2026-09-13 10:02	56.48	OK
4289	2026-09-13 10:03	52.53	OK	4290	2026-09-13 10:04	53.54	OK
4291	2026-09-13 10:05	54.10	OK	4292	2026-09-13 10:06	54.12	OK
4293	2026-09-13 10:07	55.43	OK	4294	2026-09-13 10:08	56.52	OK
4295	2026-09-13 10:09	53.46	OK	4296	2026-09-13 10:10	53.19	OK
4297	2026-09-13 10:11	53.53	OK	4298	2026-09-13 10:12	52.86	OK
4299	2026-09-13 10:13	54.26	OK	4300	2026-09-13 10:14	51.68	OK
4301	2026-09-13 10:15	52.31	OK	4302	2026-09-13 10:16	54.06	OK
4303	2026-09-13 10:17	53.59	OK	4304	2026-09-13 10:18	53.36	OK
4305	2026-09-13 10:19	52.90	OK	4306	2026-09-13 10:20	54.73	OK
4307	2026-09-13 10:21	54.55	OK	4308	2026-09-13 10:22	54.84	OK
4309	2026-09-13 10:23	53.48	OK	4310	2026-09-13 10:24	54.54	OK
4311	2026-09-13 10:25	52.64	OK	4312	2026-09-13 10:26	54.08	OK
4313	2026-09-13 10:27	54.59	OK	4314	2026-09-13 10:28	54.08	OK
4315	2026-09-13 10:29	55.21	OK	4316	2026-09-13 10:30	55.68	OK
4317	2026-09-13 10:31	52.66	OK	4318	2026-09-13 10:32	53.62	OK
4319	2026-09-13 10:33	51.99	OK	4320	2026-09-13 10:34	54.46	OK
4321	2026-09-13 10:35	54.82	OK	4322	2026-09-13 10:36	52.44	OK
4323	2026-09-13 10:37	53.97	OK	4324	2026-09-13 10:38	54.31	OK
4325	2026-09-13 10:39	55.01	OK	4326	2026-09-13 10:40	54.86	OK
4327	2026-09-13 10:41	53.82	OK	4328	2026-09-13 10:42	54.27	OK
4329	2026-09-13 10:43	54.58	OK	4330	2026-09-13 10:44	54.27	OK
4331	2026-09-13 10:45	54.68	OK	4332	2026-09-13 10:46	55.38	OK
4333	2026-09-13 10:47	55.01	OK	4334	2026-09-13 10:48	54.28	OK
4335	2026-09-13 10:49	53.38	OK	4336	2026-09-13 10:50	53.44	OK
4337	2026-09-13 10:51	52.92	OK	4338	2026-09-13 10:52	53.65	OK
4339	2026-09-13 10:53	55.68	OK	4340	2026-09-13 10:54	53.93	OK
4341	2026-09-13 10:55	54.80	OK	4342	2026-09-13 10:56	54.41	OK
4343	2026-09-13 10:57	55.13	OK	4344	2026-09-13 10:58	52.16	OK
4345	2026-09-13 10:59	53.77	OK	4346	2026-09-13 11:00	56.60	OK
4347	2026-09-13 11:01	54.54	OK	4348	2026-09-13 11:02	53.67	OK
4349	2026-09-13 11:03	55.15	OK	4350	2026-09-13 11:04	54.84	OK
4351	2026-09-13 11:05	53.50	OK	4352	2026-09-13 11:06	56.34	OK
4353	2026-09-13 11:07	54.74	OK	4354	2026-09-13 11:08	53.11	OK
4355	2026-09-13 11:09	54.12	OK	4356	2026-09-13 11:10	53.44	OK
4357	2026-09-13 11:11	55.03	OK	4358	2026-09-13 11:12	52.96	OK
4359	2026-09-13 11:13	53.69	OK	4360	2026-09-13 11:14	54.02	OK
4361	2026-09-13 11:15	53.18	OK	4362	2026-09-13 11:16	53.04	OK
4363	2026-09-13 11:17	54.70	OK	4364	2026-09-13 11:18	54.77	OK
4365	2026-09-13 11:19	53.91	OK	4366	2026-09-13 11:20	54.66	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4367	2026-09-13 11:21	52.21	OK	4368	2026-09-13 11:22	54.73	OK
4369	2026-09-13 11:23	54.98	OK	4370	2026-09-13 11:24	53.67	OK
4371	2026-09-13 11:25	53.22	OK	4372	2026-09-13 11:26	54.84	OK
4373	2026-09-13 11:27	53.48	OK	4374	2026-09-13 11:28	54.53	OK
4375	2026-09-13 11:29	54.80	OK	4376	2026-09-13 11:30	52.28	OK
4377	2026-09-13 11:31	52.11	OK	4378	2026-09-13 11:32	55.50	OK
4379	2026-09-13 11:33	52.59	OK	4380	2026-09-13 11:34	55.72	OK
4381	2026-09-13 11:35	53.74	OK	4382	2026-09-13 11:36	51.96	OK
4383	2026-09-13 11:37	56.30	OK	4384	2026-09-13 11:38	53.20	OK
4385	2026-09-13 11:39	52.81	OK	4386	2026-09-13 11:40	55.91	OK
4387	2026-09-13 11:41	54.03	OK	4388	2026-09-13 11:42	52.72	OK
4389	2026-09-13 11:43	54.03	OK	4390	2026-09-13 11:44	53.14	OK
4391	2026-09-13 11:45	54.43	OK	4392	2026-09-13 11:46	54.03	OK
4393	2026-09-13 11:47	54.56	OK	4394	2026-09-13 11:48	55.58	OK
4395	2026-09-13 11:49	53.27	OK	4396	2026-09-13 11:50	53.50	OK
4397	2026-09-13 11:51	54.83	OK	4398	2026-09-13 11:52	53.46	OK
4399	2026-09-13 11:53	54.71	OK	4400	2026-09-13 11:54	54.40	OK
4401	2026-09-13 11:55	56.30	OK	4402	2026-09-13 11:56	54.65	OK
4403	2026-09-13 11:57	53.13	OK	4404	2026-09-13 11:58	51.74	OK
4405	2026-09-13 11:59	55.20	OK	4406	2026-09-13 12:00	52.51	OK
4407	2026-09-13 12:01	55.80	OK	4408	2026-09-13 12:02	54.13	OK
4409	2026-09-13 12:03	51.75	OK	4410	2026-09-13 12:04	54.51	OK
4411	2026-09-13 12:05	53.63	OK	4412	2026-09-13 12:06	56.51	OK
4413	2026-09-13 12:07	54.60	OK	4414	2026-09-13 12:08	53.43	OK
4415	2026-09-13 12:09	52.87	OK	4416	2026-09-13 12:10	54.78	OK
4417	2026-09-13 12:11	55.56	OK	4418	2026-09-13 12:12	54.73	OK
4419	2026-09-13 12:13	52.82	OK	4420	2026-09-13 12:14	53.67	OK
4421	2026-09-13 12:15	54.07	OK	4422	2026-09-13 12:16	51.54	OK
4423	2026-09-13 12:17	52.42	OK	4424	2026-09-13 12:18	53.57	OK
4425	2026-09-13 12:19	54.42	OK	4426	2026-09-13 12:20	53.74	OK
4427	2026-09-13 12:21	53.03	OK	4428	2026-09-13 12:22	55.23	OK
4429	2026-09-13 12:23	54.96	OK	4430	2026-09-13 12:24	52.83	OK
4431	2026-09-13 12:25	53.63	OK	4432	2026-09-13 12:26	55.07	OK
4433	2026-09-13 12:27	52.77	OK	4434	2026-09-13 12:28	54.32	OK
4435	2026-09-13 12:29	51.30	OK	4436	2026-09-13 12:30	52.34	OK
4437	2026-09-13 12:31	53.58	OK	4438	2026-09-13 12:32	53.83	OK
4439	2026-09-13 12:33	54.09	OK	4440	2026-09-13 12:34	54.25	OK
4441	2026-09-13 12:35	54.18	OK	4442	2026-09-13 12:36	53.89	OK
4443	2026-09-13 12:37	56.07	OK	4444	2026-09-13 12:38	53.82	OK
4445	2026-09-13 12:39	51.44	OK	4446	2026-09-13 12:40	53.37	OK
4447	2026-09-13 12:41	54.74	OK	4448	2026-09-13 12:42	53.28	OK
4449	2026-09-13 12:43	54.41	OK	4450	2026-09-13 12:44	53.40	OK
4451	2026-09-13 12:45	54.48	OK	4452	2026-09-13 12:46	54.01	OK
4453	2026-09-13 12:47	52.31	OK	4454	2026-09-13 12:48	53.81	OK
4455	2026-09-13 12:49	53.80	OK	4456	2026-09-13 12:50	54.93	OK
4457	2026-09-13 12:51	54.37	OK	4458	2026-09-13 12:52	51.77	OK
4459	2026-09-13 12:53	52.30	OK	4460	2026-09-13 12:54	54.48	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4461	2026-09-13 12:55	51.95	OK	4462	2026-09-13 12:56	55.11	OK
4463	2026-09-13 12:57	53.31	OK	4464	2026-09-13 12:58	51.95	OK
4465	2026-09-13 12:59	55.11	OK	4466	2026-09-13 13:00	52.78	OK
4467	2026-09-13 13:01	52.76	OK	4468	2026-09-13 13:02	54.61	OK
4469	2026-09-13 13:03	52.61	OK	4470	2026-09-13 13:04	53.92	OK
4471	2026-09-13 13:05	52.60	OK	4472	2026-09-13 13:06	54.80	OK
4473	2026-09-13 13:07	53.67	OK	4474	2026-09-13 13:08	55.95	OK
4475	2026-09-13 13:09	54.85	OK	4476	2026-09-13 13:10	54.03	OK
4477	2026-09-13 13:11	52.19	OK	4478	2026-09-13 13:12	53.49	OK
4479	2026-09-13 13:13	54.48	OK	4480	2026-09-13 13:14	51.93	OK
4481	2026-09-13 13:15	53.89	OK	4482	2026-09-13 13:16	53.29	OK
4483	2026-09-13 13:17	53.26	OK	4484	2026-09-13 13:18	54.33	OK
4485	2026-09-13 13:19	53.91	OK	4486	2026-09-13 13:20	55.79	OK
4487	2026-09-13 13:21	53.82	OK	4488	2026-09-13 13:22	54.24	OK
4489	2026-09-13 13:23	52.67	OK	4490	2026-09-13 13:24	52.87	OK
4491	2026-09-13 13:25	55.26	OK	4492	2026-09-13 13:26	51.80	OK
4493	2026-09-13 13:27	53.99	OK	4494	2026-09-13 13:28	52.31	OK
4495	2026-09-13 13:29	55.86	OK	4496	2026-09-13 13:30	52.32	OK
4497	2026-09-13 13:31	54.25	OK	4498	2026-09-13 13:32	54.41	OK
4499	2026-09-13 13:33	54.30	OK	4500	2026-09-13 13:34	54.62	OK
4501	2026-09-13 13:35	54.60	OK	4502	2026-09-13 13:36	53.27	OK
4503	2026-09-13 13:37	55.93	OK	4504	2026-09-13 13:38	54.03	OK
4505	2026-09-13 13:39	53.02	OK	4506	2026-09-13 13:40	52.64	OK
4507	2026-09-13 13:41	54.48	OK	4508	2026-09-13 13:42	53.46	OK
4509	2026-09-13 13:43	52.21	OK	4510	2026-09-13 13:44	54.34	OK
4511	2026-09-13 13:45	52.33	OK	4512	2026-09-13 13:46	54.17	OK
4513	2026-09-13 13:47	52.55	OK	4514	2026-09-13 13:48	53.75	OK
4515	2026-09-13 13:49	54.53	OK	4516	2026-09-13 13:50	53.13	OK
4517	2026-09-13 13:51	52.20	OK	4518	2026-09-13 13:52	53.26	OK
4519	2026-09-13 13:53	55.21	OK	4520	2026-09-13 13:54	53.46	OK
4521	2026-09-13 13:55	54.94	OK	4522	2026-09-13 13:56	52.64	OK
4523	2026-09-13 13:57	52.43	OK	4524	2026-09-13 13:58	53.65	OK
4525	2026-09-13 13:59	53.03	OK	4526	2026-09-13 14:00	53.32	OK
4527	2026-09-13 14:01	53.57	OK	4528	2026-09-13 14:02	52.38	OK
4529	2026-09-13 14:03	52.16	OK	4530	2026-09-13 14:04	53.85	OK
4531	2026-09-13 14:05	53.85	OK	4532	2026-09-13 14:06	52.58	OK
4533	2026-09-13 14:07	53.73	OK	4534	2026-09-13 14:08	51.90	OK
4535	2026-09-13 14:09	53.20	OK	4536	2026-09-13 14:10	53.18	OK
4537	2026-09-13 14:11	53.74	OK	4538	2026-09-13 14:12	52.66	OK
4539	2026-09-13 14:13	51.76	OK	4540	2026-09-13 14:14	53.24	OK
4541	2026-09-13 14:15	55.15	OK	4542	2026-09-13 14:16	53.88	OK
4543	2026-09-13 14:17	52.74	OK	4544	2026-09-13 14:18	52.14	OK
4545	2026-09-13 14:19	51.70	OK	4546	2026-09-13 14:20	54.08	OK
4547	2026-09-13 14:21	52.46	OK	4548	2026-09-13 14:22	52.68	OK
4549	2026-09-13 14:23	52.78	OK	4550	2026-09-13 14:24	51.62	OK
4551	2026-09-13 14:25	53.04	OK	4552	2026-09-13 14:26	52.70	OK
4553	2026-09-13 14:27	51.85	OK	4554	2026-09-13 14:28	53.25	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4555	2026-09-13 14:29	51.06	OK	4556	2026-09-13 14:30	53.00	OK
4557	2026-09-13 14:31	54.89	OK	4558	2026-09-13 14:32	53.11	OK
4559	2026-09-13 14:33	52.45	OK	4560	2026-09-13 14:34	50.92	OK
4561	2026-09-13 14:35	53.34	OK	4562	2026-09-13 14:36	52.66	OK
4563	2026-09-13 14:37	52.55	OK	4564	2026-09-13 14:38	53.22	OK
4565	2026-09-13 14:39	52.67	OK	4566	2026-09-13 14:40	52.13	OK
4567	2026-09-13 14:41	51.16	OK	4568	2026-09-13 14:42	50.75	OK
4569	2026-09-13 14:43	54.71	OK	4570	2026-09-13 14:44	52.13	OK
4571	2026-09-13 14:45	52.49	OK	4572	2026-09-13 14:46	52.86	OK
4573	2026-09-13 14:47	53.01	OK	4574	2026-09-13 14:48	52.61	OK
4575	2026-09-13 14:49	52.90	OK	4576	2026-09-13 14:50	51.26	OK
4577	2026-09-13 14:51	51.44	OK	4578	2026-09-13 14:52	50.88	OK
4579	2026-09-13 14:53	53.57	OK	4580	2026-09-13 14:54	51.05	OK
4581	2026-09-13 14:55	52.45	OK	4582	2026-09-13 14:56	52.57	OK
4583	2026-09-13 14:57	53.86	OK	4584	2026-09-13 14:58	51.66	OK
4585	2026-09-13 14:59	52.35	OK	4586	2026-09-13 15:00	52.76	OK
4587	2026-09-13 15:01	51.11	OK	4588	2026-09-13 15:02	53.09	OK
4589	2026-09-13 15:03	52.81	OK	4590	2026-09-13 15:04	53.67	OK
4591	2026-09-13 15:05	52.78	OK	4592	2026-09-13 15:06	51.92	OK
4593	2026-09-13 15:07	51.12	OK	4594	2026-09-13 15:08	50.64	OK
4595	2026-09-13 15:09	52.02	OK	4596	2026-09-13 15:10	51.00	OK
4597	2026-09-13 15:11	52.45	OK	4598	2026-09-13 15:12	51.46	OK
4599	2026-09-13 15:13	53.85	OK	4600	2026-09-13 15:14	51.67	OK
4601	2026-09-13 15:15	52.52	OK	4602	2026-09-13 15:16	52.92	OK
4603	2026-09-13 15:17	53.02	OK	4604	2026-09-13 15:18	52.69	OK
4605	2026-09-13 15:19	51.13	OK	4606	2026-09-13 15:20	50.95	OK
4607	2026-09-13 15:21	50.08	OK	4608	2026-09-13 15:22	51.20	OK
4609	2026-09-13 15:23	50.31	OK	4610	2026-09-13 15:24	52.19	OK
4611	2026-09-13 15:25	54.01	OK	4612	2026-09-13 15:26	53.08	OK
4613	2026-09-13 15:27	52.14	OK	4614	2026-09-13 15:28	51.73	OK
4615	2026-09-13 15:29	52.07	OK	4616	2026-09-13 15:30	49.27	OK
4617	2026-09-13 15:31	53.69	OK	4618	2026-09-13 15:32	52.10	OK
4619	2026-09-13 15:33	50.66	OK	4620	2026-09-13 15:34	49.80	OK
4621	2026-09-13 15:35	51.59	OK	4622	2026-09-13 15:36	50.68	OK
4623	2026-09-13 15:37	51.76	OK	4624	2026-09-13 15:38	52.16	OK
4625	2026-09-13 15:39	52.91	OK	4626	2026-09-13 15:40	50.79	OK
4627	2026-09-13 15:41	52.91	OK	4628	2026-09-13 15:42	53.50	OK
4629	2026-09-13 15:43	50.90	OK	4630	2026-09-13 15:44	51.42	OK
4631	2026-09-13 15:45	52.67	OK	4632	2026-09-13 15:46	53.28	OK
4633	2026-09-13 15:47	50.42	OK	4634	2026-09-13 15:48	51.74	OK
4635	2026-09-13 15:49	51.87	OK	4636	2026-09-13 15:50	51.81	OK
4637	2026-09-13 15:51	52.46	OK	4638	2026-09-13 15:52	51.66	OK
4639	2026-09-13 15:53	50.58	OK	4640	2026-09-13 15:54	51.66	OK
4641	2026-09-13 15:55	52.35	OK	4642	2026-09-13 15:56	50.97	OK
4643	2026-09-13 15:57	50.52	OK	4644	2026-09-13 15:58	52.18	OK
4645	2026-09-13 15:59	52.51	OK	4646	2026-09-13 16:00	50.69	OK
4647	2026-09-13 16:01	49.01	OK	4648	2026-09-13 16:02	49.67	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4649	2026-09-13 16:03	52.72	OK	4650	2026-09-13 16:04	50.15	OK
4651	2026-09-13 16:05	50.79	OK	4652	2026-09-13 16:06	51.06	OK
4653	2026-09-13 16:07	51.27	OK	4654	2026-09-13 16:08	51.41	OK
4655	2026-09-13 16:09	53.01	OK	4656	2026-09-13 16:10	51.23	OK
4657	2026-09-13 16:11	51.68	OK	4658	2026-09-13 16:12	52.41	OK
4659	2026-09-13 16:13	50.46	OK	4660	2026-09-13 16:14	50.52	OK
4661	2026-09-13 16:15	51.71	OK	4662	2026-09-13 16:16	51.78	OK
4663	2026-09-13 16:17	51.30	OK	4664	2026-09-13 16:18	51.03	OK
4665	2026-09-13 16:19	50.61	OK	4666	2026-09-13 16:20	48.08	OK
4667	2026-09-13 16:21	51.31	OK	4668	2026-09-13 16:22	51.88	OK
4669	2026-09-13 16:23	49.74	OK	4670	2026-09-13 16:24	49.96	OK
4671	2026-09-13 16:25	51.46	OK	4672	2026-09-13 16:26	51.78	OK
4673	2026-09-13 16:27	50.02	OK	4674	2026-09-13 16:28	52.97	OK
4675	2026-09-13 16:29	51.32	OK	4676	2026-09-13 16:30	49.54	OK
4677	2026-09-13 16:31	51.86	OK	4678	2026-09-13 16:32	50.51	OK
4679	2026-09-13 16:33	49.11	OK	4680	2026-09-13 16:34	49.39	OK
4681	2026-09-13 16:35	51.11	OK	4682	2026-09-13 16:36	49.10	OK
4683	2026-09-13 16:37	49.29	OK	4684	2026-09-13 16:38	52.78	OK
4685	2026-09-13 16:39	51.14	OK	4686	2026-09-13 16:40	50.49	OK
4687	2026-09-13 16:41	49.74	OK	4688	2026-09-13 16:42	50.56	OK
4689	2026-09-13 16:43	48.91	OK	4690	2026-09-13 16:44	49.58	OK
4691	2026-09-13 16:45	49.85	OK	4692	2026-09-13 16:46	47.89	OK
4693	2026-09-13 16:47	51.15	OK	4694	2026-09-13 16:48	50.68	OK
4695	2026-09-13 16:49	49.20	OK	4696	2026-09-13 16:50	48.81	OK
4697	2026-09-13 16:51	49.98	OK	4698	2026-09-13 16:52	50.72	OK
4699	2026-09-13 16:53	50.82	OK	4700	2026-09-13 16:54	50.09	OK
4701	2026-09-13 16:55	51.71	OK	4702	2026-09-13 16:56	49.96	OK
4703	2026-09-13 16:57	49.85	OK	4704	2026-09-13 16:58	50.93	OK
4705	2026-09-13 16:59	49.37	OK	4706	2026-09-13 17:00	48.99	OK
4707	2026-09-13 17:01	49.95	OK	4708	2026-09-13 17:02	47.30	OK
4709	2026-09-13 17:03	50.80	OK	4710	2026-09-13 17:04	49.28	OK
4711	2026-09-13 17:05	50.75	OK	4712	2026-09-13 17:06	49.81	OK
4713	2026-09-13 17:07	49.81	OK	4714	2026-09-13 17:08	48.57	OK
4715	2026-09-13 17:09	51.77	OK	4716	2026-09-13 17:10	48.18	OK
4717	2026-09-13 17:11	47.16	OK	4718	2026-09-13 17:12	48.97	OK
4719	2026-09-13 17:13	48.26	OK	4720	2026-09-13 17:14	51.10	OK
4721	2026-09-13 17:15	49.71	OK	4722	2026-09-13 17:16	48.88	OK
4723	2026-09-13 17:17	48.40	OK	4724	2026-09-13 17:18	50.01	OK
4725	2026-09-13 17:19	52.21	OK	4726	2026-09-13 17:20	51.49	OK
4727	2026-09-13 17:21	47.89	OK	4728	2026-09-13 17:22	48.35	OK
4729	2026-09-13 17:23	50.46	OK	4730	2026-09-13 17:24	48.57	OK
4731	2026-09-13 17:25	49.00	OK	4732	2026-09-13 17:26	51.08	OK
4733	2026-09-13 17:27	50.55	OK	4734	2026-09-13 17:28	49.26	OK
4735	2026-09-13 17:29	49.26	OK	4736	2026-09-13 17:30	49.79	OK
4737	2026-09-13 17:31	48.31	OK	4738	2026-09-13 17:32	50.92	OK
4739	2026-09-13 17:33	50.31	OK	4740	2026-09-13 17:34	48.99	OK
4741	2026-09-13 17:35	49.75	OK	4742	2026-09-13 17:36	48.94	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4743	2026-09-13 17:37	49.37	OK	4744	2026-09-13 17:38	47.45	OK
4745	2026-09-13 17:39	50.03	OK	4746	2026-09-13 17:40	47.49	OK
4747	2026-09-13 17:41	47.58	OK	4748	2026-09-13 17:42	48.34	OK
4749	2026-09-13 17:43	50.18	OK	4750	2026-09-13 17:44	48.69	OK
4751	2026-09-13 17:45	49.54	OK	4752	2026-09-13 17:46	48.84	OK
4753	2026-09-13 17:47	49.72	OK	4754	2026-09-13 17:48	48.44	OK
4755	2026-09-13 17:49	49.14	OK	4756	2026-09-13 17:50	50.17	OK
4757	2026-09-13 17:51	50.62	OK	4758	2026-09-13 17:52	49.32	OK
4759	2026-09-13 17:53	49.06	OK	4760	2026-09-13 17:54	47.75	OK
4761	2026-09-13 17:55	48.84	OK	4762	2026-09-13 17:56	46.98	OK
4763	2026-09-13 17:57	48.07	OK	4764	2026-09-13 17:58	48.16	OK
4765	2026-09-13 17:59	47.40	OK	4766	2026-09-13 18:00	48.94	OK
4767	2026-09-13 18:01	49.26	OK	4768	2026-09-13 18:02	47.47	OK
4769	2026-09-13 18:03	50.27	OK	4770	2026-09-13 18:04	47.65	OK
4771	2026-09-13 18:05	48.44	OK	4772	2026-09-13 18:06	49.75	OK
4773	2026-09-13 18:07	48.68	OK	4774	2026-09-13 18:08	49.31	OK
4775	2026-09-13 18:09	48.36	OK	4776	2026-09-13 18:10	48.80	OK
4777	2026-09-13 18:11	48.51	OK	4778	2026-09-13 18:12	47.97	OK
4779	2026-09-13 18:13	49.29	OK	4780	2026-09-13 18:14	48.53	OK
4781	2026-09-13 18:15	47.82	OK	4782	2026-09-13 18:16	47.82	OK
4783	2026-09-13 18:17	48.86	OK	4784	2026-09-13 18:18	47.82	OK
4785	2026-09-13 18:19	48.32	OK	4786	2026-09-13 18:20	50.07	OK
4787	2026-09-13 18:21	48.54	OK	4788	2026-09-13 18:22	47.94	OK
4789	2026-09-13 18:23	49.31	OK	4790	2026-09-13 18:24	47.73	OK
4791	2026-09-13 18:25	47.97	OK	4792	2026-09-13 18:26	50.18	OK
4793	2026-09-13 18:27	48.71	OK	4794	2026-09-13 18:28	47.21	OK
4795	2026-09-13 18:29	47.08	OK	4796	2026-09-13 18:30	46.09	OK
4797	2026-09-13 18:31	47.95	OK	4798	2026-09-13 18:32	46.72	OK
4799	2026-09-13 18:33	49.98	OK	4800	2026-09-13 18:34	48.79	OK
4801	2026-09-13 18:35	47.16	OK	4802	2026-09-13 18:36	47.87	OK
4803	2026-09-13 18:37	48.74	OK	4804	2026-09-13 18:38	47.71	OK
4805	2026-09-13 18:39	46.90	OK	4806	2026-09-13 18:40	48.94	OK
4807	2026-09-13 18:41	48.38	OK	4808	2026-09-13 18:42	47.89	OK
4809	2026-09-13 18:43	48.03	OK	4810	2026-09-13 18:44	49.43	OK
4811	2026-09-13 18:45	45.98	OK	4812	2026-09-13 18:46	47.79	OK
4813	2026-09-13 18:47	49.25	OK	4814	2026-09-13 18:48	47.55	OK
4815	2026-09-13 18:49	48.86	OK	4816	2026-09-13 18:50	47.63	OK
4817	2026-09-13 18:51	47.81	OK	4818	2026-09-13 18:52	45.46	OK
4819	2026-09-13 18:53	46.48	OK	4820	2026-09-13 18:54	48.20	OK
4821	2026-09-13 18:55	45.39	OK	4822	2026-09-13 18:56	46.87	OK
4823	2026-09-13 18:57	46.75	OK	4824	2026-09-13 18:58	47.51	OK
4825	2026-09-13 18:59	49.70	OK	4826	2026-09-13 19:00	49.30	OK
4827	2026-09-13 19:01	47.13	OK	4828	2026-09-13 19:02	46.63	OK
4829	2026-09-13 19:03	47.97	OK	4830	2026-09-13 19:04	50.45	OK
4831	2026-09-13 19:05	46.95	OK	4832	2026-09-13 19:06	46.40	OK
4833	2026-09-13 19:07	47.39	OK	4834	2026-09-13 19:08	47.01	OK
4835	2026-09-13 19:09	48.76	OK	4836	2026-09-13 19:10	46.59	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4837	2026-09-13 19:11	46.90	OK	4838	2026-09-13 19:12	49.14	OK
4839	2026-09-13 19:13	50.10	OK	4840	2026-09-13 19:14	47.94	OK
4841	2026-09-13 19:15	48.13	OK	4842	2026-09-13 19:16	45.74	OK
4843	2026-09-13 19:17	48.22	OK	4844	2026-09-13 19:18	48.79	OK
4845	2026-09-13 19:19	45.55	OK	4846	2026-09-13 19:20	45.90	OK
4847	2026-09-13 19:21	47.12	OK	4848	2026-09-13 19:22	46.12	OK
4849	2026-09-13 19:23	45.36	OK	4850	2026-09-13 19:24	48.94	OK
4851	2026-09-13 19:25	47.83	OK	4852	2026-09-13 19:26	44.03	OK
4853	2026-09-13 19:27	46.26	OK	4854	2026-09-13 19:28	47.47	OK
4855	2026-09-13 19:29	47.32	OK	4856	2026-09-13 19:30	48.19	OK
4857	2026-09-13 19:31	45.67	OK	4858	2026-09-13 19:32	46.70	OK
4859	2026-09-13 19:33	47.22	OK	4860	2026-09-13 19:34	47.81	OK
4861	2026-09-13 19:35	47.74	OK	4862	2026-09-13 19:36	47.75	OK
4863	2026-09-13 19:37	45.54	OK	4864	2026-09-13 19:38	46.23	OK
4865	2026-09-13 19:39	48.56	OK	4866	2026-09-13 19:40	44.90	OK
4867	2026-09-13 19:41	46.94	OK	4868	2026-09-13 19:42	48.13	OK
4869	2026-09-13 19:43	47.14	OK	4870	2026-09-13 19:44	47.22	OK
4871	2026-09-13 19:45	46.73	OK	4872	2026-09-13 19:46	47.58	OK
4873	2026-09-13 19:47	46.44	OK	4874	2026-09-13 19:48	45.84	OK
4875	2026-09-13 19:49	48.59	OK	4876	2026-09-13 19:50	43.93	OK
4877	2026-09-13 19:51	47.94	OK	4878	2026-09-13 19:52	46.60	OK
4879	2026-09-13 19:53	48.29	OK	4880	2026-09-13 19:54	45.62	OK
4881	2026-09-13 19:55	49.08	OK	4882	2026-09-13 19:56	45.76	OK
4883	2026-09-13 19:57	47.45	OK	4884	2026-09-13 19:58	46.44	OK
4885	2026-09-13 19:59	45.23	OK	4886	2026-09-13 20:00	45.85	OK
4887	2026-09-13 20:01	47.30	OK	4888	2026-09-13 20:02	47.10	OK
4889	2026-09-13 20:03	45.96	OK	4890	2026-09-13 20:04	47.32	OK
4891	2026-09-13 20:05	44.72	OK	4892	2026-09-13 20:06	45.50	OK
4893	2026-09-13 20:07	46.76	OK	4894	2026-09-13 20:08	45.08	OK
4895	2026-09-13 20:09	45.90	OK	4896	2026-09-13 20:10	44.83	OK
4897	2026-09-13 20:11	45.04	OK	4898	2026-09-13 20:12	46.40	OK
4899	2026-09-13 20:13	47.41	OK	4900	2026-09-13 20:14	45.52	OK
4901	2026-09-13 20:15	46.37	OK	4902	2026-09-13 20:16	46.75	OK
4903	2026-09-13 20:17	46.55	OK	4904	2026-09-13 20:18	47.28	OK
4905	2026-09-13 20:19	46.78	OK	4906	2026-09-13 20:20	46.27	OK
4907	2026-09-13 20:21	45.39	OK	4908	2026-09-13 20:22	46.51	OK
4909	2026-09-13 20:23	47.68	OK	4910	2026-09-13 20:24	45.15	OK
4911	2026-09-13 20:25	45.05	OK	4912	2026-09-13 20:26	44.54	OK
4913	2026-09-13 20:27	44.70	OK	4914	2026-09-13 20:28	45.26	OK
4915	2026-09-13 20:29	46.33	OK	4916	2026-09-13 20:30	47.00	OK
4917	2026-09-13 20:31	45.68	OK	4918	2026-09-13 20:32	47.08	OK
4919	2026-09-13 20:33	46.52	OK	4920	2026-09-13 20:34	46.27	OK
4921	2026-09-13 20:35	45.82	OK	4922	2026-09-13 20:36	44.43	OK
4923	2026-09-13 20:37	45.67	OK	4924	2026-09-13 20:38	45.25	OK
4925	2026-09-13 20:39	45.44	OK	4926	2026-09-13 20:40	45.63	OK
4927	2026-09-13 20:41	45.83	OK	4928	2026-09-13 20:42	46.04	OK
4929	2026-09-13 20:43	45.61	OK	4930	2026-09-13 20:44	47.04	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4931	2026-09-13 20:45	46.86	OK	4932	2026-09-13 20:46	43.96	OK
4933	2026-09-13 20:47	44.99	OK	4934	2026-09-13 20:48	45.23	OK
4935	2026-09-13 20:49	45.48	OK	4936	2026-09-13 20:50	47.36	OK
4937	2026-09-13 20:51	44.35	OK	4938	2026-09-13 20:52	45.00	OK
4939	2026-09-13 20:53	44.60	OK	4940	2026-09-13 20:54	45.64	OK
4941	2026-09-13 20:55	47.77	OK	4942	2026-09-13 20:56	46.21	OK
4943	2026-09-13 20:57	48.51	OK	4944	2026-09-13 20:58	45.11	OK
4945	2026-09-13 20:59	46.10	OK	4946	2026-09-13 21:00	43.90	OK
4947	2026-09-13 21:01	45.46	OK	4948	2026-09-13 21:02	45.90	OK
4949	2026-09-13 21:03	43.85	OK	4950	2026-09-13 21:04	44.40	OK
4951	2026-09-13 21:05	46.96	OK	4952	2026-09-13 21:06	45.85	OK
4953	2026-09-13 21:07	43.28	OK	4954	2026-09-13 21:08	43.92	OK
4955	2026-09-13 21:09	45.60	OK	4956	2026-09-13 21:10	46.35	OK
4957	2026-09-13 21:11	47.53	OK	4958	2026-09-13 21:12	47.52	OK
4959	2026-09-13 21:13	45.28	OK	4960	2026-09-13 21:14	44.46	OK
4961	2026-09-13 21:15	46.27	OK	4962	2026-09-13 21:16	46.96	OK
4963	2026-09-13 21:17	44.97	OK	4964	2026-09-13 21:18	45.92	OK
4965	2026-09-13 21:19	44.53	OK	4966	2026-09-13 21:20	45.16	OK
4967	2026-09-13 21:21	46.33	OK	4968	2026-09-13 21:22	45.77	OK
4969	2026-09-13 21:23	43.30	OK	4970	2026-09-13 21:24	45.28	OK
4971	2026-09-13 21:25	46.13	OK	4972	2026-09-13 21:26	43.75	OK
4973	2026-09-13 21:27	45.12	OK	4974	2026-09-13 21:28	44.77	OK
4975	2026-09-13 21:29	44.13	OK	4976	2026-09-13 21:30	44.44	OK
4977	2026-09-13 21:31	47.39	OK	4978	2026-09-13 21:32	43.34	OK
4979	2026-09-13 21:33	43.59	OK	4980	2026-09-13 21:34	43.81	OK
4981	2026-09-13 21:35	47.06	OK	4982	2026-09-13 21:36	45.93	OK
4983	2026-09-13 21:37	44.52	OK	4984	2026-09-13 21:38	45.17	OK
4985	2026-09-13 21:39	44.13	OK	4986	2026-09-13 21:40	44.98	OK
4987	2026-09-13 21:41	44.25	OK	4988	2026-09-13 21:42	45.17	OK
4989	2026-09-13 21:43	43.73	OK	4990	2026-09-13 21:44	46.76	OK
4991	2026-09-13 21:45	45.11	OK	4992	2026-09-13 21:46	46.68	OK
4993	2026-09-13 21:47	44.84	OK	4994	2026-09-13 21:48	46.51	OK
4995	2026-09-13 21:49	44.94	OK	4996	2026-09-13 21:50	45.17	OK
4997	2026-09-13 21:51	45.21	OK	4998	2026-09-13 21:52	43.90	OK
4999	2026-09-13 21:53	45.09	OK	5000	2026-09-13 21:54	45.68	OK
5001	2026-09-13 21:55	43.34	OK	5002	2026-09-13 21:56	46.44	OK
5003	2026-09-13 21:57	45.64	OK	5004	2026-09-13 21:58	47.34	OK
5005	2026-09-13 21:59	45.05	OK	5006	2026-09-13 22:00	44.93	OK
5007	2026-09-13 22:01	47.08	OK	5008	2026-09-13 22:02	45.62	OK
5009	2026-09-13 22:03	46.12	OK	5010	2026-09-13 22:04	43.69	OK
5011	2026-09-13 22:05	45.73	OK	5012	2026-09-13 22:06	43.34	OK
5013	2026-09-13 22:07	43.51	OK	5014	2026-09-13 22:08	46.87	OK
5015	2026-09-13 22:09	46.31	OK	5016	2026-09-13 22:10	44.16	OK
5017	2026-09-13 22:11	46.57	OK	5018	2026-09-13 22:12	45.12	OK
5019	2026-09-13 22:13	46.63	OK	5020	2026-09-13 22:14	46.13	OK
5021	2026-09-13 22:15	44.28	OK	5022	2026-09-13 22:16	44.44	OK
5023	2026-09-13 22:17	44.59	OK	5024	2026-09-13 22:18	46.27	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5025	2026-09-13 22:19	44.24	OK	5026	2026-09-13 22:20	44.84	OK
5027	2026-09-13 22:21	42.71	OK	5028	2026-09-13 22:22	44.74	OK
5029	2026-09-13 22:23	45.09	OK	5030	2026-09-13 22:24	44.34	OK
5031	2026-09-13 22:25	45.48	OK	5032	2026-09-13 22:26	44.31	OK
5033	2026-09-13 22:27	43.72	OK	5034	2026-09-13 22:28	44.96	OK
5035	2026-09-13 22:29	44.75	OK	5036	2026-09-13 22:30	45.07	OK
5037	2026-09-13 22:31	45.73	OK	5038	2026-09-13 22:32	43.62	OK
5039	2026-09-13 22:33	43.47	OK	5040	2026-09-13 22:34	43.54	OK
5041	2026-09-13 22:35	43.75	OK	5042	2026-09-13 22:36	45.00	OK
5043	2026-09-13 22:37	44.64	OK	5044	2026-09-13 22:38	46.32	OK
5045	2026-09-13 22:39	44.94	OK	5046	2026-09-13 22:40	44.70	OK
5047	2026-09-13 22:41	45.09	OK	5048	2026-09-13 22:42	45.03	OK
5049	2026-09-13 22:43	45.19	OK	5050	2026-09-13 22:44	44.79	OK
5051	2026-09-13 22:45	45.02	OK	5052	2026-09-13 22:46	44.26	OK
5053	2026-09-13 22:47	45.43	OK	5054	2026-09-13 22:48	45.40	OK
5055	2026-09-13 22:49	43.73	OK	5056	2026-09-13 22:50	45.71	OK
5057	2026-09-13 22:51	43.97	OK	5058	2026-09-13 22:52	44.38	OK
5059	2026-09-13 22:53	45.53	OK	5060	2026-09-13 22:54	42.73	OK
5061	2026-09-13 22:55	44.73	OK	5062	2026-09-13 22:56	44.93	OK
5063	2026-09-13 22:57	43.62	OK	5064	2026-09-13 22:58	46.56	OK
5065	2026-09-13 22:59	45.08	OK	5066	2026-09-13 23:00	46.16	OK
5067	2026-09-13 23:01	45.74	OK	5068	2026-09-13 23:02	45.53	OK
5069	2026-09-13 23:03	44.86	OK	5070	2026-09-13 23:04	47.70	OK
5071	2026-09-13 23:05	44.22	OK	5072	2026-09-13 23:06	44.93	OK
5073	2026-09-13 23:07	45.24	OK	5074	2026-09-13 23:08	42.76	OK
5075	2026-09-13 23:09	44.44	OK	5076	2026-09-13 23:10	45.29	OK
5077	2026-09-13 23:11	43.77	OK	5078	2026-09-13 23:12	42.88	OK
5079	2026-09-13 23:13	44.48	OK	5080	2026-09-13 23:14	45.37	OK
5081	2026-09-13 23:15	44.98	OK	5082	2026-09-13 23:16	46.58	OK
5083	2026-09-13 23:17	46.07	OK	5084	2026-09-13 23:18	45.83	OK
5085	2026-09-13 23:19	46.74	OK	5086	2026-09-13 23:20	44.76	OK
5087	2026-09-13 23:21	45.86	OK	5088	2026-09-13 23:22	43.29	OK
5089	2026-09-13 23:23	44.31	OK	5090	2026-09-13 23:24	44.09	OK
5091	2026-09-13 23:25	46.41	OK	5092	2026-09-13 23:26	45.21	OK
5093	2026-09-13 23:27	44.08	OK	5094	2026-09-13 23:28	43.33	OK
5095	2026-09-13 23:29	43.36	OK	5096	2026-09-13 23:30	45.84	OK
5097	2026-09-13 23:31	45.01	OK	5098	2026-09-13 23:32	44.80	OK
5099	2026-09-13 23:33	46.33	OK	5100	2026-09-13 23:34	45.23	OK
5101	2026-09-13 23:35	44.09	OK	5102	2026-09-13 23:36	44.39	OK
5103	2026-09-13 23:37	44.92	OK	5104	2026-09-13 23:38	44.98	OK
5105	2026-09-13 23:39	47.09	OK	5106	2026-09-13 23:40	46.08	OK
5107	2026-09-13 23:41	44.90	OK	5108	2026-09-13 23:42	45.46	OK
5109	2026-09-13 23:43	43.83	OK	5110	2026-09-13 23:44	44.65	OK
5111	2026-09-13 23:45	44.00	OK	5112	2026-09-13 23:46	46.81	OK
5113	2026-09-13 23:47	45.12	OK	5114	2026-09-13 23:48	44.60	OK
5115	2026-09-13 23:49	42.22	OK	5116	2026-09-13 23:50	43.89	OK
5117	2026-09-13 23:51	45.09	OK	5118	2026-09-13 23:52	44.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5119	2026-09-13 23:53	42.64	OK	5120	2026-09-13 23:54	43.97	OK
5121	2026-09-13 23:55	47.00	OK	5122	2026-09-13 23:56	44.94	OK
5123	2026-09-13 23:57	43.92	OK	5124	2026-09-13 23:58	45.33	OK
5125	2026-09-13 23:59	44.25	OK	5126	2026-09-14 00:00	43.72	OK
5127	2026-09-14 00:01	44.83	OK	5128	2026-09-14 00:02	46.49	OK
5129	2026-09-14 00:03	44.25	OK	5130	2026-09-14 00:04	44.46	OK
5131	2026-09-14 00:05	46.87	OK	5132	2026-09-14 00:06	45.43	OK
5133	2026-09-14 00:07	43.91	OK	5134	2026-09-14 00:08	45.46	OK
5135	2026-09-14 00:09	44.77	OK	5136	2026-09-14 00:10	46.67	OK
5137	2026-09-14 00:11	44.51	OK	5138	2026-09-14 00:12	47.21	OK
5139	2026-09-14 00:13	44.78	OK	5140	2026-09-14 00:14	44.41	OK
5141	2026-09-14 00:15	46.62	OK	5142	2026-09-14 00:16	45.25	OK
5143	2026-09-14 00:17	45.07	OK	5144	2026-09-14 00:18	42.87	OK
5145	2026-09-14 00:19	44.57	OK	5146	2026-09-14 00:20	44.78	OK
5147	2026-09-14 00:21	44.70	OK	5148	2026-09-14 00:22	44.48	OK
5149	2026-09-14 00:23	42.70	OK	5150	2026-09-14 00:24	46.49	OK
5151	2026-09-14 00:25	45.57	OK	5152	2026-09-14 00:26	42.79	OK
5153	2026-09-14 00:27	43.99	OK	5154	2026-09-14 00:28	43.93	OK
5155	2026-09-14 00:29	45.66	OK	5156	2026-09-14 00:30	46.11	OK
5157	2026-09-14 00:31	45.28	OK	5158	2026-09-14 00:32	44.92	OK
5159	2026-09-14 00:33	45.46	OK	5160	2026-09-14 00:34	43.84	OK
5161	2026-09-14 00:35	44.33	OK	5162	2026-09-14 00:36	43.17	OK
5163	2026-09-14 00:37	44.94	OK	5164	2026-09-14 00:38	43.88	OK
5165	2026-09-14 00:39	46.25	OK	5166	2026-09-14 00:40	46.76	OK
5167	2026-09-14 00:41	46.47	OK	5168	2026-09-14 00:42	42.84	OK
5169	2026-09-14 00:43	46.29	OK	5170	2026-09-14 00:44	45.49	OK
5171	2026-09-14 00:45	45.14	OK	5172	2026-09-14 00:46	44.89	OK
5173	2026-09-14 00:47	43.75	OK	5174	2026-09-14 00:48	44.77	OK
5175	2026-09-14 00:49	45.83	OK	5176	2026-09-14 00:50	42.58	OK
5177	2026-09-14 00:51	45.18	OK	5178	2026-09-14 00:52	47.41	OK
5179	2026-09-14 00:53	44.54	OK	5180	2026-09-14 00:54	47.06	OK
5181	2026-09-14 00:55	44.33	OK	5182	2026-09-14 00:56	45.02	OK
5183	2026-09-14 00:57	46.06	OK	5184	2026-09-14 00:58	44.65	OK
5185	2026-09-14 00:59	44.26	OK	5186	2026-09-14 01:00	46.22	OK
5187	2026-09-14 01:01	45.65	OK	5188	2026-09-14 01:02	47.20	OK
5189	2026-09-14 01:03	45.22	OK	5190	2026-09-14 01:04	45.37	OK
5191	2026-09-14 01:05	45.03	OK	5192	2026-09-14 01:06	45.39	OK
5193	2026-09-14 01:07	44.97	OK	5194	2026-09-14 01:08	46.10	OK
5195	2026-09-14 01:09	43.16	OK	5196	2026-09-14 01:10	45.17	OK
5197	2026-09-14 01:11	42.78	OK	5198	2026-09-14 01:12	45.10	OK
5199	2026-09-14 01:13	45.75	OK	5200	2026-09-14 01:14	44.26	OK
5201	2026-09-14 01:15	47.49	OK	5202	2026-09-14 01:16	45.25	OK
5203	2026-09-14 01:17	43.38	OK	5204	2026-09-14 01:18	44.39	OK
5205	2026-09-14 01:19	43.72	OK	5206	2026-09-14 01:20	45.04	OK
5207	2026-09-14 01:21	44.81	OK	5208	2026-09-14 01:22	47.88	OK
5209	2026-09-14 01:23	47.07	OK	5210	2026-09-14 01:24	44.42	OK
5211	2026-09-14 01:25	46.58	OK	5212	2026-09-14 01:26	43.82	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5213	2026-09-14 01:27	43.41	OK	5214	2026-09-14 01:28	44.38	OK
5215	2026-09-14 01:29	44.28	OK	5216	2026-09-14 01:30	47.79	OK
5217	2026-09-14 01:31	45.55	OK	5218	2026-09-14 01:32	44.72	OK
5219	2026-09-14 01:33	46.27	OK	5220	2026-09-14 01:34	44.05	OK
5221	2026-09-14 01:35	46.91	OK	5222	2026-09-14 01:36	44.14	OK
5223	2026-09-14 01:37	44.94	OK	5224	2026-09-14 01:38	45.36	OK
5225	2026-09-14 01:39	46.03	OK	5226	2026-09-14 01:40	43.68	OK
5227	2026-09-14 01:41	46.07	OK	5228	2026-09-14 01:42	43.98	OK
5229	2026-09-14 01:43	47.16	OK	5230	2026-09-14 01:44	43.79	OK
5231	2026-09-14 01:45	46.59	OK	5232	2026-09-14 01:46	46.31	OK
5233	2026-09-14 01:47	46.99	OK	5234	2026-09-14 01:48	44.84	OK
5235	2026-09-14 01:49	45.01	OK	5236	2026-09-14 01:50	43.21	OK
5237	2026-09-14 01:51	46.55	OK	5238	2026-09-14 01:52	44.62	OK
5239	2026-09-14 01:53	46.05	OK	5240	2026-09-14 01:54	47.52	OK
5241	2026-09-14 01:55	45.64	OK	5242	2026-09-14 01:56	43.75	OK
5243	2026-09-14 01:57	44.93	OK	5244	2026-09-14 01:58	45.91	OK
5245	2026-09-14 01:59	46.56	OK	5246	2026-09-14 02:00	45.78	OK
5247	2026-09-14 02:01	45.28	OK	5248	2026-09-14 02:02	43.75	OK
5249	2026-09-14 02:03	47.04	OK	5250	2026-09-14 02:04	46.87	OK
5251	2026-09-14 02:05	45.60	OK	5252	2026-09-14 02:06	45.83	OK
5253	2026-09-14 02:07	45.65	OK	5254	2026-09-14 02:08	43.58	OK
5255	2026-09-14 02:09	45.27	OK	5256	2026-09-14 02:10	45.48	OK
5257	2026-09-14 02:11	45.90	OK	5258	2026-09-14 02:12	45.42	OK
5259	2026-09-14 02:13	45.33	OK	5260	2026-09-14 02:14	46.31	OK
5261	2026-09-14 02:15	47.45	OK	5262	2026-09-14 02:16	46.01	OK
5263	2026-09-14 02:17	44.83	OK	5264	2026-09-14 02:18	43.40	OK
5265	2026-09-14 02:19	43.69	OK	5266	2026-09-14 02:20	45.30	OK
5267	2026-09-14 02:21	44.24	OK	5268	2026-09-14 02:22	45.24	OK
5269	2026-09-14 02:23	46.31	OK	5270	2026-09-14 02:24	45.18	OK
5271	2026-09-14 02:25	46.30	OK	5272	2026-09-14 02:26	45.22	OK
5273	2026-09-14 02:27	47.47	OK	5274	2026-09-14 02:28	46.80	OK
5275	2026-09-14 02:29	46.02	OK	5276	2026-09-14 02:30	46.32	OK
5277	2026-09-14 02:31	47.19	OK	5278	2026-09-14 02:32	47.66	OK
5279	2026-09-14 02:33	47.77	OK	5280	2026-09-14 02:34	44.87	OK
5281	2026-09-14 02:35	43.54	OK	5282	2026-09-14 02:36	44.21	OK
5283	2026-09-14 02:37	46.22	OK	5284	2026-09-14 02:38	45.82	OK
5285	2026-09-14 02:39	46.78	OK	5286	2026-09-14 02:40	46.10	OK
5287	2026-09-14 02:41	44.79	OK	5288	2026-09-14 02:42	45.95	OK
5289	2026-09-14 02:43	44.83	OK	5290	2026-09-14 02:44	44.98	OK
5291	2026-09-14 02:45	46.40	OK	5292	2026-09-14 02:46	48.85	OK
5293	2026-09-14 02:47	47.58	OK	5294	2026-09-14 02:48	46.60	OK
5295	2026-09-14 02:49	47.66	OK	5296	2026-09-14 02:50	46.52	OK
5297	2026-09-14 02:51	46.67	OK	5298	2026-09-14 02:52	46.28	OK
5299	2026-09-14 02:53	45.12	OK	5300	2026-09-14 02:54	45.48	OK
5301	2026-09-14 02:55	48.73	OK	5302	2026-09-14 02:56	45.73	OK
5303	2026-09-14 02:57	47.29	OK	5304	2026-09-14 02:58	48.56	OK
5305	2026-09-14 02:59	47.33	OK	5306	2026-09-14 03:00	44.09	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5307	2026-09-14 03:01	44.66	OK	5308	2026-09-14 03:02	46.50	OK
5309	2026-09-14 03:03	44.69	OK	5310	2026-09-14 03:04	46.03	OK
5311	2026-09-14 03:05	44.50	OK	5312	2026-09-14 03:06	45.03	OK
5313	2026-09-14 03:07	46.95	OK	5314	2026-09-14 03:08	47.53	OK
5315	2026-09-14 03:09	45.91	OK	5316	2026-09-14 03:10	47.86	OK
5317	2026-09-14 03:11	45.18	OK	5318	2026-09-14 03:12	47.93	OK
5319	2026-09-14 03:13	45.75	OK	5320	2026-09-14 03:14	46.56	OK
5321	2026-09-14 03:15	47.96	OK	5322	2026-09-14 03:16	48.64	OK
5323	2026-09-14 03:17	48.38	OK	5324	2026-09-14 03:18	47.81	OK
5325	2026-09-14 03:19	47.64	OK	5326	2026-09-14 03:20	46.33	OK
5327	2026-09-14 03:21	47.25	OK	5328	2026-09-14 03:22	47.04	OK
5329	2026-09-14 03:23	47.34	OK	5330	2026-09-14 03:24	49.40	OK
5331	2026-09-14 03:25	49.21	OK	5332	2026-09-14 03:26	45.76	OK
5333	2026-09-14 03:27	46.18	OK	5334	2026-09-14 03:28	48.32	OK
5335	2026-09-14 03:29	46.38	OK	5336	2026-09-14 03:30	46.64	OK
5337	2026-09-14 03:31	46.21	OK	5338	2026-09-14 03:32	49.07	OK
5339	2026-09-14 03:33	46.57	OK	5340	2026-09-14 03:34	47.22	OK
5341	2026-09-14 03:35	48.04	OK	5342	2026-09-14 03:36	47.44	OK
5343	2026-09-14 03:37	48.21	OK	5344	2026-09-14 03:38	48.04	OK
5345	2026-09-14 03:39	47.00	OK	5346	2026-09-14 03:40	48.29	OK
5347	2026-09-14 03:41	47.52	OK	5348	2026-09-14 03:42	45.42	OK
5349	2026-09-14 03:43	47.99	OK	5350	2026-09-14 03:44	47.04	OK
5351	2026-09-14 03:45	46.90	OK	5352	2026-09-14 03:46	48.24	OK
5353	2026-09-14 03:47	46.19	OK	5354	2026-09-14 03:48	47.59	OK
5355	2026-09-14 03:49	46.28	OK	5356	2026-09-14 03:50	47.25	OK
5357	2026-09-14 03:51	47.17	OK	5358	2026-09-14 03:52	47.82	OK
5359	2026-09-14 03:53	48.23	OK	5360	2026-09-14 03:54	47.89	OK
5361	2026-09-14 03:55	46.85	OK	5362	2026-09-14 03:56	46.62	OK
5363	2026-09-14 03:57	49.35	OK	5364	2026-09-14 03:58	47.38	OK
5365	2026-09-14 03:59	49.20	OK	5366	2026-09-14 04:00	47.45	OK
5367	2026-09-14 04:01	48.77	OK	5368	2026-09-14 04:02	47.91	OK
5369	2026-09-14 04:03	48.35	OK	5370	2026-09-14 04:04	47.55	OK
5371	2026-09-14 04:05	49.09	OK	5372	2026-09-14 04:06	48.17	OK
5373	2026-09-14 04:07	49.09	OK	5374	2026-09-14 04:08	47.82	OK
5375	2026-09-14 04:09	47.33	OK	5376	2026-09-14 04:10	46.80	OK
5377	2026-09-14 04:11	45.91	OK	5378	2026-09-14 04:12	49.04	OK
5379	2026-09-14 04:13	45.28	OK	5380	2026-09-14 04:14	48.20	OK
5381	2026-09-14 04:15	46.75	OK	5382	2026-09-14 04:16	48.13	OK
5383	2026-09-14 04:17	48.12	OK	5384	2026-09-14 04:18	46.04	OK
5385	2026-09-14 04:19	46.03	OK	5386	2026-09-14 04:20	48.26	OK
5387	2026-09-14 04:21	47.77	OK	5388	2026-09-14 04:22	48.19	OK
5389	2026-09-14 04:23	49.11	OK	5390	2026-09-14 04:24	48.46	OK
5391	2026-09-14 04:25	48.81	OK	5392	2026-09-14 04:26	46.83	OK
5393	2026-09-14 04:27	49.55	OK	5394	2026-09-14 04:28	48.57	OK
5395	2026-09-14 04:29	48.68	OK	5396	2026-09-14 04:30	48.26	OK
5397	2026-09-14 04:31	46.97	OK	5398	2026-09-14 04:32	47.36	OK
5399	2026-09-14 04:33	47.17	OK	5400	2026-09-14 04:34	46.94	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5401	2026-09-14 04:35	48.05	OK	5402	2026-09-14 04:36	48.60	OK
5403	2026-09-14 04:37	48.29	OK	5404	2026-09-14 04:38	46.76	OK
5405	2026-09-14 04:39	50.39	OK	5406	2026-09-14 04:40	48.24	OK
5407	2026-09-14 04:41	47.31	OK	5408	2026-09-14 04:42	47.83	OK
5409	2026-09-14 04:43	47.03	OK	5410	2026-09-14 04:44	49.35	OK
5411	2026-09-14 04:45	49.64	OK	5412	2026-09-14 04:46	46.03	OK
5413	2026-09-14 04:47	48.02	OK	5414	2026-09-14 04:48	48.94	OK
5415	2026-09-14 04:49	48.77	OK	5416	2026-09-14 04:50	48.75	OK
5417	2026-09-14 04:51	50.24	OK	5418	2026-09-14 04:52	48.69	OK
5419	2026-09-14 04:53	47.21	OK	5420	2026-09-14 04:54	49.47	OK
5421	2026-09-14 04:55	50.79	OK	5422	2026-09-14 04:56	46.61	OK
5423	2026-09-14 04:57	48.48	OK	5424	2026-09-14 04:58	49.96	OK
5425	2026-09-14 04:59	47.63	OK	5426	2026-09-14 05:00	48.64	OK
5427	2026-09-14 05:01	48.48	OK	5428	2026-09-14 05:02	48.21	OK
5429	2026-09-14 05:03	50.67	OK	5430	2026-09-14 05:04	49.84	OK
5431	2026-09-14 05:05	47.07	OK	5432	2026-09-14 05:06	49.49	OK
5433	2026-09-14 05:07	46.78	OK	5434	2026-09-14 05:08	49.46	OK
5435	2026-09-14 05:09	48.48	OK	5436	2026-09-14 05:10	48.35	OK
5437	2026-09-14 05:11	50.71	OK	5438	2026-09-14 05:12	48.74	OK
5439	2026-09-14 05:13	50.43	OK	5440	2026-09-14 05:14	47.11	OK
5441	2026-09-14 05:15	48.81	OK	5442	2026-09-14 05:16	50.39	OK
5443	2026-09-14 05:17	48.43	OK	5444	2026-09-14 05:18	51.32	OK
5445	2026-09-14 05:19	51.43	OK	5446	2026-09-14 05:20	49.11	OK
5447	2026-09-14 05:21	48.35	OK	5448	2026-09-14 05:22	49.45	OK
5449	2026-09-14 05:23	49.02	OK	5450	2026-09-14 05:24	49.32	OK
5451	2026-09-14 05:25	47.53	OK	5452	2026-09-14 05:26	48.70	OK
5453	2026-09-14 05:27	49.93	OK	5454	2026-09-14 05:28	50.50	OK
5455	2026-09-14 05:29	50.13	OK	5456	2026-09-14 05:30	49.35	OK
5457	2026-09-14 05:31	49.50	OK	5458	2026-09-14 05:32	48.77	OK
5459	2026-09-14 05:33	49.49	OK	5460	2026-09-14 05:34	50.41	OK
5461	2026-09-14 05:35	47.65	OK	5462	2026-09-14 05:36	48.32	OK
5463	2026-09-14 05:37	49.38	OK	5464	2026-09-14 05:38	49.71	OK
5465	2026-09-14 05:39	48.54	OK	5466	2026-09-14 05:40	49.80	OK
5467	2026-09-14 05:41	47.26	OK	5468	2026-09-14 05:42	49.05	OK
5469	2026-09-14 05:43	48.96	OK	5470	2026-09-14 05:44	48.39	OK
5471	2026-09-14 05:45	49.70	OK	5472	2026-09-14 05:46	49.94	OK
5473	2026-09-14 05:47	50.92	OK	5474	2026-09-14 05:48	50.89	OK
5475	2026-09-14 05:49	49.63	OK	5476	2026-09-14 05:50	51.22	OK
5477	2026-09-14 05:51	49.26	OK	5478	2026-09-14 05:52	49.76	OK
5479	2026-09-14 05:53	49.60	OK	5480	2026-09-14 05:54	50.67	OK
5481	2026-09-14 05:55	51.55	OK	5482	2026-09-14 05:56	52.13	OK
5483	2026-09-14 05:57	49.62	OK	5484	2026-09-14 05:58	47.66	OK
5485	2026-09-14 05:59	50.86	OK	5486	2026-09-14 06:00	49.61	OK
5487	2026-09-14 06:01	52.47	OK	5488	2026-09-14 06:02	49.27	OK
5489	2026-09-14 06:03	51.71	OK	5490	2026-09-14 06:04	50.95	OK
5491	2026-09-14 06:05	51.80	OK	5492	2026-09-14 06:06	48.29	OK
5493	2026-09-14 06:07	49.73	OK	5494	2026-09-14 06:08	51.48	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5495	2026-09-14 06:09	51.81	OK	5496	2026-09-14 06:10	52.28	OK
5497	2026-09-14 06:11	50.57	OK	5498	2026-09-14 06:12	52.36	OK
5499	2026-09-14 06:13	49.13	OK	5500	2026-09-14 06:14	50.60	OK
5501	2026-09-14 06:15	51.81	OK	5502	2026-09-14 06:16	51.10	OK
5503	2026-09-14 06:17	50.05	OK	5504	2026-09-14 06:18	49.44	OK
5505	2026-09-14 06:19	50.87	OK	5506	2026-09-14 06:20	52.69	OK
5507	2026-09-14 06:21	50.64	OK	5508	2026-09-14 06:22	50.66	OK
5509	2026-09-14 06:23	51.04	OK	5510	2026-09-14 06:24	50.06	OK
5511	2026-09-14 06:25	49.73	OK	5512	2026-09-14 06:26	50.08	OK
5513	2026-09-14 06:27	51.57	OK	5514	2026-09-14 06:28	50.68	OK
5515	2026-09-14 06:29	50.46	OK	5516	2026-09-14 06:30	49.41	OK
5517	2026-09-14 06:31	49.67	OK	5518	2026-09-14 06:32	51.27	OK
5519	2026-09-14 06:33	49.60	OK	5520	2026-09-14 06:34	52.70	OK
5521	2026-09-14 06:35	49.79	OK	5522	2026-09-14 06:36	51.84	OK
5523	2026-09-14 06:37	51.94	OK	5524	2026-09-14 06:38	52.54	OK
5525	2026-09-14 06:39	51.03	OK	5526	2026-09-14 06:40	52.56	OK
5527	2026-09-14 06:41	48.92	OK	5528	2026-09-14 06:42	50.12	OK
5529	2026-09-14 06:43	49.79	OK	5530	2026-09-14 06:44	51.75	OK
5531	2026-09-14 06:45	50.89	OK	5532	2026-09-14 06:46	51.62	OK
5533	2026-09-14 06:47	50.04	OK	5534	2026-09-14 06:48	50.51	OK
5535	2026-09-14 06:49	49.36	OK	5536	2026-09-14 06:50	51.31	OK
5537	2026-09-14 06:51	51.18	OK	5538	2026-09-14 06:52	50.90	OK
5539	2026-09-14 06:53	52.20	OK	5540	2026-09-14 06:54	51.31	OK
5541	2026-09-14 06:55	50.71	OK	5542	2026-09-14 06:56	51.48	OK
5543	2026-09-14 06:57	50.85	OK	5544	2026-09-14 06:58	53.06	OK
5545	2026-09-14 06:59	51.28	OK	5546	2026-09-14 07:00	50.70	OK
5547	2026-09-14 07:01	51.88	OK	5548	2026-09-14 07:02	51.80	OK
5549	2026-09-14 07:03	50.34	OK	5550	2026-09-14 07:04	52.81	OK
5551	2026-09-14 07:05	51.57	OK	5552	2026-09-14 07:06	53.24	OK
5553	2026-09-14 07:07	51.08	OK	5554	2026-09-14 07:08	51.62	OK
5555	2026-09-14 07:09	51.28	OK	5556	2026-09-14 07:10	51.51	OK
5557	2026-09-14 07:11	51.97	OK	5558	2026-09-14 07:12	50.95	OK
5559	2026-09-14 07:13	51.55	OK	5560	2026-09-14 07:14	51.01	OK
5561	2026-09-14 07:15	50.43	OK	5562	2026-09-14 07:16	51.47	OK
5563	2026-09-14 07:17	51.78	OK	5564	2026-09-14 07:18	52.02	OK
5565	2026-09-14 07:19	53.79	OK	5566	2026-09-14 07:20	53.21	OK
5567	2026-09-14 07:21	54.01	OK	5568	2026-09-14 07:22	54.54	OK
5569	2026-09-14 07:23	53.74	OK	5570	2026-09-14 07:24	50.20	OK
5571	2026-09-14 07:25	49.71	OK	5572	2026-09-14 07:26	49.20	OK
5573	2026-09-14 07:27	52.22	OK	5574	2026-09-14 07:28	51.96	OK
5575	2026-09-14 07:29	52.51	OK	5576	2026-09-14 07:30	52.08	OK
5577	2026-09-14 07:31	51.19	OK	5578	2026-09-14 07:32	53.80	OK
5579	2026-09-14 07:33	53.36	OK	5580	2026-09-14 07:34	53.19	OK
5581	2026-09-14 07:35	52.73	OK	5582	2026-09-14 07:36	52.27	OK
5583	2026-09-14 07:37	51.35	OK	5584	2026-09-14 07:38	50.64	OK
5585	2026-09-14 07:39	51.12	OK	5586	2026-09-14 07:40	51.22	OK
5587	2026-09-14 07:41	52.59	OK	5588	2026-09-14 07:42	52.45	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5589	2026-09-14 07:43	53.11	OK	5590	2026-09-14 07:44	52.74	OK
5591	2026-09-14 07:45	51.66	OK	5592	2026-09-14 07:46	51.40	OK
5593	2026-09-14 07:47	52.59	OK	5594	2026-09-14 07:48	51.10	OK
5595	2026-09-14 07:49	53.22	OK	5596	2026-09-14 07:50	52.66	OK
5597	2026-09-14 07:51	51.08	OK	5598	2026-09-14 07:52	53.72	OK
5599	2026-09-14 07:53	52.15	OK	5600	2026-09-14 07:54	52.65	OK
5601	2026-09-14 07:55	53.24	OK	5602	2026-09-14 07:56	54.76	OK
5603	2026-09-14 07:57	51.92	OK	5604	2026-09-14 07:58	53.80	OK
5605	2026-09-14 07:59	52.62	OK	5606	2026-09-14 08:00	51.77	OK
5607	2026-09-14 08:01	54.22	OK	5608	2026-09-14 08:02	51.49	OK
5609	2026-09-14 08:03	50.97	OK	5610	2026-09-14 08:04	53.68	OK
5611	2026-09-14 08:05	52.13	OK	5612	2026-09-14 08:06	55.41	OK
5613	2026-09-14 08:07	54.49	OK	5614	2026-09-14 08:08	52.92	OK
5615	2026-09-14 08:09	51.60	OK	5616	2026-09-14 08:10	53.51	OK
5617	2026-09-14 08:11	51.12	OK	5618	2026-09-14 08:12	53.79	OK
5619	2026-09-14 08:13	52.99	OK	5620	2026-09-14 08:14	54.27	OK
5621	2026-09-14 08:15	53.63	OK	5622	2026-09-14 08:16	54.18	OK
5623	2026-09-14 08:17	52.31	OK	5624	2026-09-14 08:18	53.66	OK
5625	2026-09-14 08:19	52.58	OK	5626	2026-09-14 08:20	52.34	OK
5627	2026-09-14 08:21	52.44	OK	5628	2026-09-14 08:22	54.67	OK
5629	2026-09-14 08:23	51.59	OK	5630	2026-09-14 08:24	51.87	OK
5631	2026-09-14 08:25	53.28	OK	5632	2026-09-14 08:26	53.31	OK
5633	2026-09-14 08:27	52.30	OK	5634	2026-09-14 08:28	51.60	OK
5635	2026-09-14 08:29	50.46	OK	5636	2026-09-14 08:30	52.44	OK
5637	2026-09-14 08:31	52.27	OK	5638	2026-09-14 08:32	50.62	OK
5639	2026-09-14 08:33	52.98	OK	5640	2026-09-14 08:34	51.40	OK
5641	2026-09-14 08:35	53.36	OK	5642	2026-09-14 08:36	54.41	OK
5643	2026-09-14 08:37	54.59	OK	5644	2026-09-14 08:38	53.41	OK
5645	2026-09-14 08:39	52.48	OK	5646	2026-09-14 08:40	52.63	OK
5647	2026-09-14 08:41	53.71	OK	5648	2026-09-14 08:42	54.31	OK
5649	2026-09-14 08:43	53.29	OK	5650	2026-09-14 08:44	53.14	OK
5651	2026-09-14 08:45	53.92	OK	5652	2026-09-14 08:46	51.57	OK
5653	2026-09-14 08:47	52.40	OK	5654	2026-09-14 08:48	54.38	OK
5655	2026-09-14 08:49	51.93	OK	5656	2026-09-14 08:50	53.69	OK
5657	2026-09-14 08:51	52.14	OK	5658	2026-09-14 08:52	54.04	OK
5659	2026-09-14 08:53	52.32	OK	5660	2026-09-14 08:54	53.49	OK
5661	2026-09-14 08:55	52.77	OK	5662	2026-09-14 08:56	53.01	OK
5663	2026-09-14 08:57	53.34	OK	5664	2026-09-14 08:58	51.55	OK
5665	2026-09-14 08:59	52.73	OK	5666	2026-09-14 09:00	53.41	OK
5667	2026-09-14 09:01	54.14	OK	5668	2026-09-14 09:02	54.57	OK
5669	2026-09-14 09:03	54.29	OK	5670	2026-09-14 09:04	51.68	OK
5671	2026-09-14 09:05	52.27	OK	5672	2026-09-14 09:06	51.78	OK
5673	2026-09-14 09:07	51.86	OK	5674	2026-09-14 09:08	55.11	OK
5675	2026-09-14 09:09	53.43	OK	5676	2026-09-14 09:10	54.61	OK
5677	2026-09-14 09:11	53.22	OK	5678	2026-09-14 09:12	54.40	OK
5679	2026-09-14 09:13	52.60	OK	5680	2026-09-14 09:14	53.55	OK
5681	2026-09-14 09:15	54.23	OK	5682	2026-09-14 09:16	53.87	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5683	2026-09-14 09:17	51.79	OK	5684	2026-09-14 09:18	54.81	OK
5685	2026-09-14 09:19	53.98	OK	5686	2026-09-14 09:20	52.45	OK
5687	2026-09-14 09:21	56.41	OK	5688	2026-09-14 09:22	52.44	OK
5689	2026-09-14 09:23	54.53	OK	5690	2026-09-14 09:24	54.54	OK
5691	2026-09-14 09:25	51.39	OK	5692	2026-09-14 09:26	52.66	OK
5693	2026-09-14 09:27	53.84	OK	5694	2026-09-14 09:28	52.96	OK
5695	2026-09-14 09:29	52.94	OK	5696	2026-09-14 09:30	53.11	OK
5697	2026-09-14 09:31	53.05	OK	5698	2026-09-14 09:32	53.15	OK
5699	2026-09-14 09:33	53.35	OK	5700	2026-09-14 09:34	54.34	OK
5701	2026-09-14 09:35	54.07	OK	5702	2026-09-14 09:36	53.33	OK
5703	2026-09-14 09:37	52.89	OK	5704	2026-09-14 09:38	54.22	OK
5705	2026-09-14 09:39	53.76	OK	5706	2026-09-14 09:40	52.61	OK
5707	2026-09-14 09:41	55.80	OK	5708	2026-09-14 09:42	54.80	OK
5709	2026-09-14 09:43	53.25	OK	5710	2026-09-14 09:44	53.09	OK
5711	2026-09-14 09:45	55.58	OK	5712	2026-09-14 09:46	55.08	OK
5713	2026-09-14 09:47	52.59	OK	5714	2026-09-14 09:48	54.43	OK
5715	2026-09-14 09:49	54.21	OK	5716	2026-09-14 09:50	52.88	OK
5717	2026-09-14 09:51	52.47	OK	5718	2026-09-14 09:52	52.28	OK
5719	2026-09-14 09:53	56.77	OK	5720	2026-09-14 09:54	54.57	OK
5721	2026-09-14 09:55	54.31	OK	5722	2026-09-14 09:56	52.99	OK
5723	2026-09-14 09:57	53.64	OK	5724	2026-09-14 09:58	54.82	OK
5725	2026-09-14 09:59	53.45	OK	5726	2026-09-14 10:00	53.03	OK
5727	2026-09-14 10:01	54.77	OK	5728	2026-09-14 10:02	53.27	OK
5729	2026-09-14 10:03	51.59	OK	5730	2026-09-14 10:04	54.70	OK
5731	2026-09-14 10:05	51.76	OK	5732	2026-09-14 10:06	52.95	OK
5733	2026-09-14 10:07	53.12	OK	5734	2026-09-14 10:08	54.16	OK
5735	2026-09-14 10:09	52.04	OK	5736	2026-09-14 10:10	53.68	OK
5737	2026-09-14 10:11	53.07	OK	5738	2026-09-14 10:12	54.64	OK
5739	2026-09-14 10:13	54.25	OK	5740	2026-09-14 10:14	52.25	OK
5741	2026-09-14 10:15	55.90	OK	5742	2026-09-14 10:16	55.57	OK
5743	2026-09-14 10:17	55.32	OK	5744	2026-09-14 10:18	52.36	OK
5745	2026-09-14 10:19	56.03	OK	5746	2026-09-14 10:20	52.88	OK
5747	2026-09-14 10:21	53.41	OK	5748	2026-09-14 10:22	52.57	OK
5749	2026-09-14 10:23	53.53	OK	5750	2026-09-14 10:24	53.29	OK
5751	2026-09-14 10:25	52.38	OK	5752	2026-09-14 10:26	54.87	OK
5753	2026-09-14 10:27	54.42	OK	5754	2026-09-14 10:28	54.03	OK
5755	2026-09-14 10:29	54.80	OK	5756	2026-09-14 10:30	53.80	OK
5757	2026-09-14 10:31	54.62	OK	5758	2026-09-14 10:32	55.65	OK
5759	2026-09-14 10:33	52.68	OK	5760	2026-09-14 10:34	53.18	OK
5761	2026-09-14 10:35	53.51	OK	5762	2026-09-14 10:36	54.04	OK
5763	2026-09-14 10:37	54.30	OK	5764	2026-09-14 10:38	53.16	OK
5765	2026-09-14 10:39	54.94	OK	5766	2026-09-14 10:40	54.39	OK
5767	2026-09-14 10:41	53.54	OK	5768	2026-09-14 10:42	54.19	OK
5769	2026-09-14 10:43	53.63	OK	5770	2026-09-14 10:44	56.50	OK
5771	2026-09-14 10:45	52.69	OK	5772	2026-09-14 10:46	53.69	OK
5773	2026-09-14 10:47	55.16	OK	5774	2026-09-14 10:48	53.69	OK
5775	2026-09-14 10:49	54.85	OK	5776	2026-09-14 10:50	54.42	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5777	2026-09-14 10:51	53.62	OK	5778	2026-09-14 10:52	52.05	OK
5779	2026-09-14 10:53	53.72	OK	5780	2026-09-14 10:54	53.79	OK
5781	2026-09-14 10:55	55.97	OK	5782	2026-09-14 10:56	51.79	OK
5783	2026-09-14 10:57	55.09	OK	5784	2026-09-14 10:58	54.48	OK
5785	2026-09-14 10:59	53.99	OK	5786	2026-09-14 11:00	54.69	OK
5787	2026-09-14 11:01	55.21	OK	5788	2026-09-14 11:02	54.58	OK
5789	2026-09-14 11:03	52.27	OK	5790	2026-09-14 11:04	54.36	OK
5791	2026-09-14 11:05	53.28	OK	5792	2026-09-14 11:06	55.46	OK
5793	2026-09-14 11:07	54.46	OK	5794	2026-09-14 11:08	56.13	OK
5795	2026-09-14 11:09	53.34	OK	5796	2026-09-14 11:10	54.39	OK
5797	2026-09-14 11:11	52.54	OK	5798	2026-09-14 11:12	51.79	OK
5799	2026-09-14 11:13	53.55	OK	5800	2026-09-14 11:14	54.29	OK
5801	2026-09-14 11:15	52.26	OK	5802	2026-09-14 11:16	56.53	OK
5803	2026-09-14 11:17	55.16	OK	5804	2026-09-14 11:18	54.59	OK
5805	2026-09-14 11:19	52.29	OK	5806	2026-09-14 11:20	54.91	OK
5807	2026-09-14 11:21	54.29	OK	5808	2026-09-14 11:22	55.42	OK
5809	2026-09-14 11:23	53.72	OK	5810	2026-09-14 11:24	53.87	OK
5811	2026-09-14 11:25	53.96	OK	5812	2026-09-14 11:26	55.13	OK
5813	2026-09-14 11:27	53.99	OK	5814	2026-09-14 11:28	51.84	OK
5815	2026-09-14 11:29	53.29	OK	5816	2026-09-14 11:30	53.24	OK
5817	2026-09-14 11:31	52.87	OK	5818	2026-09-14 11:32	55.45	OK
5819	2026-09-14 11:33	54.24	OK	5820	2026-09-14 11:34	55.04	OK
5821	2026-09-14 11:35	54.05	OK	5822	2026-09-14 11:36	56.03	OK
5823	2026-09-14 11:37	56.58	OK	5824	2026-09-14 11:38	53.37	OK
5825	2026-09-14 11:39	53.70	OK	5826	2026-09-14 11:40	53.94	OK
5827	2026-09-14 11:41	52.51	OK	5828	2026-09-14 11:42	54.21	OK
5829	2026-09-14 11:43	52.30	OK	5830	2026-09-14 11:44	52.12	OK
5831	2026-09-14 11:45	53.31	OK	5832	2026-09-14 11:46	55.74	OK
5833	2026-09-14 11:47	54.86	OK	5834	2026-09-14 11:48	53.34	OK
5835	2026-09-14 11:49	54.62	OK	5836	2026-09-14 11:50	54.65	OK
5837	2026-09-14 11:51	53.89	OK	5838	2026-09-14 11:52	54.06	OK
5839	2026-09-14 11:53	53.71	OK	5840	2026-09-14 11:54	54.89	OK
5841	2026-09-14 11:55	53.58	OK	5842	2026-09-14 11:56	55.20	OK
5843	2026-09-14 11:57	54.06	OK	5844	2026-09-14 11:58	55.27	OK
5845	2026-09-14 11:59	52.45	OK	5846	2026-09-14 12:00	54.23	OK
5847	2026-09-14 12:01	54.73	OK	5848	2026-09-14 12:02	54.36	OK
5849	2026-09-14 12:03	52.79	OK	5850	2026-09-14 12:04	51.41	OK
5851	2026-09-14 12:05	53.08	OK	5852	2026-09-14 12:06	53.03	OK
5853	2026-09-14 12:07	54.03	OK	5854	2026-09-14 12:08	55.83	OK
5855	2026-09-14 12:09	55.10	OK	5856	2026-09-14 12:10	53.29	OK
5857	2026-09-14 12:11	53.54	OK	5858	2026-09-14 12:12	53.20	OK
5859	2026-09-14 12:13	55.36	OK	5860	2026-09-14 12:14	55.36	OK
5861	2026-09-14 12:15	53.05	OK	5862	2026-09-14 12:16	56.19	OK
5863	2026-09-14 12:17	55.58	OK	5864	2026-09-14 12:18	56.16	OK
5865	2026-09-14 12:19	54.92	OK	5866	2026-09-14 12:20	53.58	OK
5867	2026-09-14 12:21	53.59	OK	5868	2026-09-14 12:22	55.68	OK
5869	2026-09-14 12:23	53.25	OK	5870	2026-09-14 12:24	53.97	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5871	2026-09-14 12:25	53.34	OK	5872	2026-09-14 12:26	55.21	OK
5873	2026-09-14 12:27	54.09	OK	5874	2026-09-14 12:28	55.03	OK
5875	2026-09-14 12:29	53.75	OK	5876	2026-09-14 12:30	54.26	OK
5877	2026-09-14 12:31	55.10	OK	5878	2026-09-14 12:32	53.66	OK
5879	2026-09-14 12:33	52.32	OK	5880	2026-09-14 12:34	55.53	OK
5881	2026-09-14 12:35	53.32	OK	5882	2026-09-14 12:36	54.34	OK
5883	2026-09-14 12:37	54.36	OK	5884	2026-09-14 12:38	53.02	OK
5885	2026-09-14 12:39	54.61	OK	5886	2026-09-14 12:40	52.27	OK
5887	2026-09-14 12:41	55.01	OK	5888	2026-09-14 12:42	55.21	OK
5889	2026-09-14 12:43	51.92	OK	5890	2026-09-14 12:44	54.96	OK
5891	2026-09-14 12:45	53.26	OK	5892	2026-09-14 12:46	54.49	OK
5893	2026-09-14 12:47	55.09	OK	5894	2026-09-14 12:48	55.36	OK
5895	2026-09-14 12:49	53.83	OK	5896	2026-09-14 12:50	53.84	OK
5897	2026-09-14 12:51	53.00	OK	5898	2026-09-14 12:52	53.16	OK
5899	2026-09-14 12:53	54.28	OK	5900	2026-09-14 12:54	53.56	OK
5901	2026-09-14 12:55	53.66	OK	5902	2026-09-14 12:56	51.58	OK
5903	2026-09-14 12:57	54.14	OK	5904	2026-09-14 12:58	51.94	OK
5905	2026-09-14 12:59	54.43	OK	5906	2026-09-14 13:00	53.89	OK
5907	2026-09-14 13:01	55.79	OK	5908	2026-09-14 13:02	54.36	OK
5909	2026-09-14 13:03	53.26	OK	5910	2026-09-14 13:04	52.89	OK
5911	2026-09-14 13:05	53.66	OK	5912	2026-09-14 13:06	53.88	OK
5913	2026-09-14 13:07	52.12	OK	5914	2026-09-14 13:08	52.85	OK
5915	2026-09-14 13:09	53.81	OK	5916	2026-09-14 13:10	53.02	OK
5917	2026-09-14 13:11	53.31	OK	5918	2026-09-14 13:12	53.79	OK
5919	2026-09-14 13:13	53.46	OK	5920	2026-09-14 13:14	51.95	OK
5921	2026-09-14 13:15	52.33	OK	5922	2026-09-14 13:16	52.94	OK
5923	2026-09-14 13:17	54.76	OK	5924	2026-09-14 13:18	53.88	OK
5925	2026-09-14 13:19	53.56	OK	5926	2026-09-14 13:20	53.76	OK
5927	2026-09-14 13:21	54.23	OK	5928	2026-09-14 13:22	53.43	OK
5929	2026-09-14 13:23	54.75	OK	5930	2026-09-14 13:24	53.90	OK
5931	2026-09-14 13:25	54.86	OK	5932	2026-09-14 13:26	52.41	OK
5933	2026-09-14 13:27	54.00	OK	5934	2026-09-14 13:28	55.15	OK
5935	2026-09-14 13:29	53.42	OK	5936	2026-09-14 13:30	54.08	OK
5937	2026-09-14 13:31	54.26	OK	5938	2026-09-14 13:32	54.23	OK
5939	2026-09-14 13:33	52.48	OK	5940	2026-09-14 13:34	55.38	OK
5941	2026-09-14 13:35	55.43	OK	5942	2026-09-14 13:36	53.26	OK
5943	2026-09-14 13:37	53.22	OK	5944	2026-09-14 13:38	54.98	OK
5945	2026-09-14 13:39	53.23	OK	5946	2026-09-14 13:40	52.96	OK
5947	2026-09-14 13:41	53.67	OK	5948	2026-09-14 13:42	53.65	OK
5949	2026-09-14 13:43	52.49	OK	5950	2026-09-14 13:44	51.99	OK
5951	2026-09-14 13:45	54.27	OK	5952	2026-09-14 13:46	53.10	OK
5953	2026-09-14 13:47	54.87	OK	5954	2026-09-14 13:48	53.90	OK
5955	2026-09-14 13:49	55.12	OK	5956	2026-09-14 13:50	53.13	OK
5957	2026-09-14 13:51	52.45	OK	5958	2026-09-14 13:52	53.08	OK
5959	2026-09-14 13:53	52.95	OK	5960	2026-09-14 13:54	54.36	OK
5961	2026-09-14 13:55	55.47	OK	5962	2026-09-14 13:56	53.12	OK
5963	2026-09-14 13:57	51.28	OK	5964	2026-09-14 13:58	54.41	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5965	2026-09-14 13:59	52.90	OK	5966	2026-09-14 14:00	54.68	OK
5967	2026-09-14 14:01	51.99	OK	5968	2026-09-14 14:02	55.16	OK
5969	2026-09-14 14:03	52.28	OK	5970	2026-09-14 14:04	52.27	OK
5971	2026-09-14 14:05	53.75	OK	5972	2026-09-14 14:06	53.14	OK
5973	2026-09-14 14:07	52.50	OK	5974	2026-09-14 14:08	51.43	OK
5975	2026-09-14 14:09	52.55	OK	5976	2026-09-14 14:10	53.46	OK
5977	2026-09-14 14:11	53.14	OK	5978	2026-09-14 14:12	54.71	OK
5979	2026-09-14 14:13	52.61	OK	5980	2026-09-14 14:14	53.63	OK
5981	2026-09-14 14:15	53.53	OK	5982	2026-09-14 14:16	52.72	OK
5983	2026-09-14 14:17	53.79	OK	5984	2026-09-14 14:18	52.63	OK
5985	2026-09-14 14:19	51.11	OK	5986	2026-09-14 14:20	52.88	OK
5987	2026-09-14 14:21	52.38	OK	5988	2026-09-14 14:22	52.83	OK
5989	2026-09-14 14:23	52.75	OK	5990	2026-09-14 14:24	51.11	OK
5991	2026-09-14 14:25	53.99	OK	5992	2026-09-14 14:26	51.72	OK
5993	2026-09-14 14:27	52.39	OK	5994	2026-09-14 14:28	53.11	OK
5995	2026-09-14 14:29	52.66	OK	5996	2026-09-14 14:30	52.59	OK
5997	2026-09-14 14:31	54.37	OK	5998	2026-09-14 14:32	53.39	OK
5999	2026-09-14 14:33	54.18	OK	6000	2026-09-14 14:34	53.61	OK
6001	2026-09-14 14:35	54.60	OK	6002	2026-09-14 14:36	50.68	OK
6003	2026-09-14 14:37	51.83	OK	6004	2026-09-14 14:38	53.69	OK
6005	2026-09-14 14:39	51.62	OK	6006	2026-09-14 14:40	53.89	OK
6007	2026-09-14 14:41	51.69	OK	6008	2026-09-14 14:42	51.52	OK
6009	2026-09-14 14:43	51.23	OK	6010	2026-09-14 14:44	53.57	OK
6011	2026-09-14 14:45	53.99	OK	6012	2026-09-14 14:46	52.95	OK
6013	2026-09-14 14:47	52.72	OK	6014	2026-09-14 14:48	53.73	OK
6015	2026-09-14 14:49	53.70	OK	6016	2026-09-14 14:50	52.45	OK
6017	2026-09-14 14:51	51.09	OK	6018	2026-09-14 14:52	52.49	OK
6019	2026-09-14 14:53	52.18	OK	6020	2026-09-14 14:54	54.09	OK
6021	2026-09-14 14:55	54.16	OK	6022	2026-09-14 14:56	51.91	OK
6023	2026-09-14 14:57	54.17	OK	6024	2026-09-14 14:58	51.87	OK
6025	2026-09-14 14:59	50.72	OK	6026	2026-09-14 15:00	53.49	OK
6027	2026-09-14 15:01	50.46	OK	6028	2026-09-14 15:02	52.32	OK
6029	2026-09-14 15:03	53.21	OK	6030	2026-09-14 15:04	52.60	OK
6031	2026-09-14 15:05	53.22	OK	6032	2026-09-14 15:06	52.06	OK
6033	2026-09-14 15:07	51.66	OK	6034	2026-09-14 15:08	51.22	OK
6035	2026-09-14 15:09	53.18	OK	6036	2026-09-14 15:10	53.38	OK
6037	2026-09-14 15:11	51.11	OK	6038	2026-09-14 15:12	52.56	OK
6039	2026-09-14 15:13	52.91	OK	6040	2026-09-14 15:14	52.65	OK
6041	2026-09-14 15:15	51.74	OK	6042	2026-09-14 15:16	52.81	OK
6043	2026-09-14 15:17	51.94	OK	6044	2026-09-14 15:18	50.16	OK
6045	2026-09-14 15:19	50.43	OK	6046	2026-09-14 15:20	52.21	OK
6047	2026-09-14 15:21	52.22	OK	6048	2026-09-14 15:22	52.40	OK
6049	2026-09-14 15:23	50.95	OK	6050	2026-09-14 15:24	54.27	OK
6051	2026-09-14 15:25	50.74	OK	6052	2026-09-14 15:26	52.69	OK
6053	2026-09-14 15:27	52.73	OK	6054	2026-09-14 15:28	51.46	OK
6055	2026-09-14 15:29	50.76	OK	6056	2026-09-14 15:30	51.50	OK
6057	2026-09-14 15:31	50.64	OK	6058	2026-09-14 15:32	53.55	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6059	2026-09-14 15:33	52.00	OK	6060	2026-09-14 15:34	50.54	OK
6061	2026-09-14 15:35	51.34	OK	6062	2026-09-14 15:36	50.56	OK
6063	2026-09-14 15:37	52.98	OK	6064	2026-09-14 15:38	53.56	OK
6065	2026-09-14 15:39	50.67	OK	6066	2026-09-14 15:40	51.83	OK
6067	2026-09-14 15:41	52.55	OK	6068	2026-09-14 15:42	53.22	OK
6069	2026-09-14 15:43	52.08	OK	6070	2026-09-14 15:44	49.84	OK
6071	2026-09-14 15:45	52.60	OK	6072	2026-09-14 15:46	50.97	OK
6073	2026-09-14 15:47	50.22	OK	6074	2026-09-14 15:48	50.04	OK
6075	2026-09-14 15:49	51.18	OK	6076	2026-09-14 15:50	52.81	OK
6077	2026-09-14 15:51	50.23	OK	6078	2026-09-14 15:52	49.75	OK
6079	2026-09-14 15:53	50.36	OK	6080	2026-09-14 15:54	51.02	OK
6081	2026-09-14 15:55	52.77	OK	6082	2026-09-14 15:56	52.68	OK
6083	2026-09-14 15:57	51.24	OK	6084	2026-09-14 15:58	50.74	OK
6085	2026-09-14 15:59	51.45	OK	6086	2026-09-14 16:00	52.85	OK
6087	2026-09-14 16:01	51.93	OK	6088	2026-09-14 16:02	50.21	OK
6089	2026-09-14 16:03	50.77	OK	6090	2026-09-14 16:04	50.17	OK
6091	2026-09-14 16:05	51.39	OK	6092	2026-09-14 16:06	51.60	OK
6093	2026-09-14 16:07	52.79	OK	6094	2026-09-14 16:08	50.68	OK
6095	2026-09-14 16:09	51.42	OK	6096	2026-09-14 16:10	52.25	OK
6097	2026-09-14 16:11	53.61	OK	6098	2026-09-14 16:12	49.12	OK
6099	2026-09-14 16:13	50.43	OK	6100	2026-09-14 16:14	51.35	OK
6101	2026-09-14 16:15	49.15	OK	6102	2026-09-14 16:16	50.50	OK
6103	2026-09-14 16:17	49.75	OK	6104	2026-09-14 16:18	51.11	OK
6105	2026-09-14 16:19	49.47	OK	6106	2026-09-14 16:20	50.89	OK
6107	2026-09-14 16:21	50.27	OK	6108	2026-09-14 16:22	51.75	OK
6109	2026-09-14 16:23	51.75	OK	6110	2026-09-14 16:24	52.28	OK
6111	2026-09-14 16:25	49.51	OK	6112	2026-09-14 16:26	49.19	OK
6113	2026-09-14 16:27	48.63	OK	6114	2026-09-14 16:28	48.98	OK
6115	2026-09-14 16:29	50.67	OK	6116	2026-09-14 16:30	51.30	OK
6117	2026-09-14 16:31	50.54	OK	6118	2026-09-14 16:32	51.38	OK
6119	2026-09-14 16:33	52.98	OK	6120	2026-09-14 16:34	50.49	OK
6121	2026-09-14 16:35	49.43	OK	6122	2026-09-14 16:36	51.55	OK
6123	2026-09-14 16:37	51.41	OK	6124	2026-09-14 16:38	49.16	OK
6125	2026-09-14 16:39	51.26	OK	6126	2026-09-14 16:40	50.85	OK
6127	2026-09-14 16:41	52.23	OK	6128	2026-09-14 16:42	50.29	OK
6129	2026-09-14 16:43	51.11	OK	6130	2026-09-14 16:44	49.10	OK
6131	2026-09-14 16:45	51.84	OK	6132	2026-09-14 16:46	49.57	OK
6133	2026-09-14 16:47	50.29	OK	6134	2026-09-14 16:48	51.07	OK
6135	2026-09-14 16:49	49.23	OK	6136	2026-09-14 16:50	47.82	OK
6137	2026-09-14 16:51	49.88	OK	6138	2026-09-14 16:52	50.63	OK
6139	2026-09-14 16:53	50.95	OK	6140	2026-09-14 16:54	50.34	OK
6141	2026-09-14 16:55	51.60	OK	6142	2026-09-14 16:56	50.95	OK
6143	2026-09-14 16:57	52.51	OK	6144	2026-09-14 16:58	49.55	OK
6145	2026-09-14 16:59	49.64	OK	6146	2026-09-14 17:00	49.04	OK
6147	2026-09-14 17:01	52.13	OK	6148	2026-09-14 17:02	49.89	OK
6149	2026-09-14 17:03	51.24	OK	6150	2026-09-14 17:04	50.75	OK
6151	2026-09-14 17:05	51.40	OK	6152	2026-09-14 17:06	49.40	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6153	2026-09-14 17:07	48.45	OK	6154	2026-09-14 17:08	50.98	OK
6155	2026-09-14 17:09	49.35	OK	6156	2026-09-14 17:10	47.44	OK
6157	2026-09-14 17:11	48.99	OK	6158	2026-09-14 17:12	50.11	OK
6159	2026-09-14 17:13	52.04	OK	6160	2026-09-14 17:14	49.65	OK
6161	2026-09-14 17:15	49.55	OK	6162	2026-09-14 17:16	49.98	OK
6163	2026-09-14 17:17	50.43	OK	6164	2026-09-14 17:18	50.54	OK
6165	2026-09-14 17:19	49.72	OK	6166	2026-09-14 17:20	49.58	OK
6167	2026-09-14 17:21	50.01	OK	6168	2026-09-14 17:22	50.37	OK
6169	2026-09-14 17:23	48.25	OK	6170	2026-09-14 17:24	49.68	OK
6171	2026-09-14 17:25	49.66	OK	6172	2026-09-14 17:26	49.84	OK
6173	2026-09-14 17:27	51.37	OK	6174	2026-09-14 17:28	48.14	OK
6175	2026-09-14 17:29	49.73	OK	6176	2026-09-14 17:30	47.97	OK
6177	2026-09-14 17:31	49.33	OK	6178	2026-09-14 17:32	48.84	OK
6179	2026-09-14 17:33	49.32	OK	6180	2026-09-14 17:34	48.88	OK
6181	2026-09-14 17:35	50.93	OK	6182	2026-09-14 17:36	48.80	OK
6183	2026-09-14 17:37	48.95	OK	6184	2026-09-14 17:38	47.14	OK
6185	2026-09-14 17:39	47.33	OK	6186	2026-09-14 17:40	50.71	OK
6187	2026-09-14 17:41	48.28	OK	6188	2026-09-14 17:42	49.08	OK
6189	2026-09-14 17:43	49.16	OK	6190	2026-09-14 17:44	49.15	OK
6191	2026-09-14 17:45	48.12	OK	6192	2026-09-14 17:46	49.51	OK
6193	2026-09-14 17:47	49.40	OK	6194	2026-09-14 17:48	47.55	OK
6195	2026-09-14 17:49	48.42	OK	6196	2026-09-14 17:50	49.10	OK
6197	2026-09-14 17:51	47.82	OK	6198	2026-09-14 17:52	50.19	OK
6199	2026-09-14 17:53	50.51	OK	6200	2026-09-14 17:54	48.20	OK
6201	2026-09-14 17:55	47.79	OK	6202	2026-09-14 17:56	49.22	OK
6203	2026-09-14 17:57	48.52	OK	6204	2026-09-14 17:58	48.36	OK
6205	2026-09-14 17:59	47.91	OK	6206	2026-09-14 18:00	49.05	OK
6207	2026-09-14 18:01	47.47	OK	6208	2026-09-14 18:02	47.14	OK
6209	2026-09-14 18:03	50.17	OK	6210	2026-09-14 18:04	49.30	OK
6211	2026-09-14 18:05	49.83	OK	6212	2026-09-14 18:06	48.77	OK
6213	2026-09-14 18:07	49.79	OK	6214	2026-09-14 18:08	48.36	OK
6215	2026-09-14 18:09	49.20	OK	6216	2026-09-14 18:10	47.02	OK
6217	2026-09-14 18:11	48.61	OK	6218	2026-09-14 18:12	49.86	OK
6219	2026-09-14 18:13	49.34	OK	6220	2026-09-14 18:14	49.09	OK
6221	2026-09-14 18:15	47.09	OK	6222	2026-09-14 18:16	47.21	OK
6223	2026-09-14 18:17	48.86	OK	6224	2026-09-14 18:18	46.48	OK
6225	2026-09-14 18:19	47.62	OK	6226	2026-09-14 18:20	46.22	OK
6227	2026-09-14 18:21	47.76	OK	6228	2026-09-14 18:22	48.28	OK
6229	2026-09-14 18:23	47.66	OK	6230	2026-09-14 18:24	49.83	OK
6231	2026-09-14 18:25	47.49	OK	6232	2026-09-14 18:26	47.44	OK
6233	2026-09-14 18:27	47.25	OK	6234	2026-09-14 18:28	51.28	OK
6235	2026-09-14 18:29	46.99	OK	6236	2026-09-14 18:30	47.56	OK
6237	2026-09-14 18:31	49.19	OK	6238	2026-09-14 18:32	47.54	OK
6239	2026-09-14 18:33	46.67	OK	6240	2026-09-14 18:34	48.14	OK
6241	2026-09-14 18:35	48.76	OK	6242	2026-09-14 18:36	49.06	OK
6243	2026-09-14 18:37	47.24	OK	6244	2026-09-14 18:38	49.64	OK
6245	2026-09-14 18:39	47.36	OK	6246	2026-09-14 18:40	49.04	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6247	2026-09-14 18:41	47.28	OK	6248	2026-09-14 18:42	48.73	OK
6249	2026-09-14 18:43	47.57	OK	6250	2026-09-14 18:44	47.47	OK
6251	2026-09-14 18:45	47.86	OK	6252	2026-09-14 18:46	48.25	OK
6253	2026-09-14 18:47	46.22	OK	6254	2026-09-14 18:48	45.21	OK
6255	2026-09-14 18:49	47.31	OK	6256	2026-09-14 18:50	47.98	OK
6257	2026-09-14 18:51	45.18	OK	6258	2026-09-14 18:52	45.99	OK
6259	2026-09-14 18:53	47.42	OK	6260	2026-09-14 18:54	48.35	OK
6261	2026-09-14 18:55	46.29	OK	6262	2026-09-14 18:56	48.08	OK
6263	2026-09-14 18:57	47.31	OK	6264	2026-09-14 18:58	46.55	OK
6265	2026-09-14 18:59	47.96	OK	6266	2026-09-14 19:00	46.48	OK
6267	2026-09-14 19:01	48.19	OK	6268	2026-09-14 19:02	46.83	OK
6269	2026-09-14 19:03	48.51	OK	6270	2026-09-14 19:04	47.07	OK
6271	2026-09-14 19:05	47.41	OK	6272	2026-09-14 19:06	46.93	OK
6273	2026-09-14 19:07	49.03	OK	6274	2026-09-14 19:08	45.58	OK
6275	2026-09-14 19:09	46.14	OK	6276	2026-09-14 19:10	48.06	OK
6277	2026-09-14 19:11	47.32	OK	6278	2026-09-14 19:12	48.17	OK
6279	2026-09-14 19:13	46.31	OK	6280	2026-09-14 19:14	45.92	OK
6281	2026-09-14 19:15	46.90	OK	6282	2026-09-14 19:16	48.50	OK
6283	2026-09-14 19:17	47.96	OK	6284	2026-09-14 19:18	47.34	OK
6285	2026-09-14 19:19	46.73	OK	6286	2026-09-14 19:20	49.15	OK
6287	2026-09-14 19:21	46.10	OK	6288	2026-09-14 19:22	45.19	OK
6289	2026-09-14 19:23	45.36	OK	6290	2026-09-14 19:24	49.09	OK
6291	2026-09-14 19:25	47.49	OK	6292	2026-09-14 19:26	48.95	OK
6293	2026-09-14 19:27	47.52	OK	6294	2026-09-14 19:28	46.81	OK
6295	2026-09-14 19:29	46.68	OK	6296	2026-09-14 19:30	45.69	OK
6297	2026-09-14 19:31	48.39	OK	6298	2026-09-14 19:32	48.15	OK
6299	2026-09-14 19:33	47.12	OK	6300	2026-09-14 19:34	46.22	OK
6301	2026-09-14 19:35	45.63	OK	6302	2026-09-14 19:36	47.25	OK
6303	2026-09-14 19:37	47.13	OK	6304	2026-09-14 19:38	46.61	OK
6305	2026-09-14 19:39	47.70	OK	6306	2026-09-14 19:40	46.06	OK
6307	2026-09-14 19:41	48.77	OK	6308	2026-09-14 19:42	46.45	OK
6309	2026-09-14 19:43	46.03	OK	6310	2026-09-14 19:44	45.94	OK
6311	2026-09-14 19:45	48.01	OK	6312	2026-09-14 19:46	46.59	OK
6313	2026-09-14 19:47	45.25	OK	6314	2026-09-14 19:48	46.43	OK
6315	2026-09-14 19:49	47.35	OK	6316	2026-09-14 19:50	47.29	OK
6317	2026-09-14 19:51	44.99	OK	6318	2026-09-14 19:52	45.68	OK
6319	2026-09-14 19:53	45.50	OK	6320	2026-09-14 19:54	44.41	OK
6321	2026-09-14 19:55	48.19	OK	6322	2026-09-14 19:56	47.37	OK
6323	2026-09-14 19:57	48.32	OK	6324	2026-09-14 19:58	48.16	OK
6325	2026-09-14 19:59	46.53	OK	6326	2026-09-14 20:00	46.25	OK
6327	2026-09-14 20:01	45.61	OK	6328	2026-09-14 20:02	47.86	OK
6329	2026-09-14 20:03	47.99	OK	6330	2026-09-14 20:04	46.77	OK
6331	2026-09-14 20:05	48.89	OK	6332	2026-09-14 20:06	47.41	OK
6333	2026-09-14 20:07	44.14	OK	6334	2026-09-14 20:08	46.46	OK
6335	2026-09-14 20:09	45.44	OK	6336	2026-09-14 20:10	46.13	OK
6337	2026-09-14 20:11	45.96	OK	6338	2026-09-14 20:12	44.98	OK
6339	2026-09-14 20:13	48.00	OK	6340	2026-09-14 20:14	45.31	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6341	2026-09-14 20:15	47.34	OK	6342	2026-09-14 20:16	47.14	OK
6343	2026-09-14 20:17	46.09	OK	6344	2026-09-14 20:18	45.35	OK
6345	2026-09-14 20:19	47.01	OK	6346	2026-09-14 20:20	45.38	OK
6347	2026-09-14 20:21	47.20	OK	6348	2026-09-14 20:22	47.31	OK
6349	2026-09-14 20:23	46.45	OK	6350	2026-09-14 20:24	45.57	OK
6351	2026-09-14 20:25	44.39	OK	6352	2026-09-14 20:26	45.71	OK
6353	2026-09-14 20:27	44.40	OK	6354	2026-09-14 20:28	46.07	OK
6355	2026-09-14 20:29	46.49	OK	6356	2026-09-14 20:30	47.47	OK
6357	2026-09-14 20:31	46.62	OK	6358	2026-09-14 20:32	46.04	OK
6359	2026-09-14 20:33	44.68	OK	6360	2026-09-14 20:34	45.10	OK
6361	2026-09-14 20:35	46.07	OK	6362	2026-09-14 20:36	44.63	OK
6363	2026-09-14 20:37	45.16	OK	6364	2026-09-14 20:38	46.38	OK
6365	2026-09-14 20:39	44.79	OK	6366	2026-09-14 20:40	44.38	OK
6367	2026-09-14 20:41	45.49	OK	6368	2026-09-14 20:42	47.76	OK
6369	2026-09-14 20:43	45.70	OK	6370	2026-09-14 20:44	46.52	OK
6371	2026-09-14 20:45	47.67	OK	6372	2026-09-14 20:46	44.71	OK
6373	2026-09-14 20:47	46.78	OK	6374	2026-09-14 20:48	46.79	OK
6375	2026-09-14 20:49	43.80	OK	6376	2026-09-14 20:50	45.53	OK
6377	2026-09-14 20:51	47.03	OK	6378	2026-09-14 20:52	46.10	OK
6379	2026-09-14 20:53	46.96	OK	6380	2026-09-14 20:54	46.82	OK
6381	2026-09-14 20:55	44.60	OK	6382	2026-09-14 20:56	44.99	OK
6383	2026-09-14 20:57	44.56	OK	6384	2026-09-14 20:58	46.09	OK
6385	2026-09-14 20:59	46.65	OK	6386	2026-09-14 21:00	44.90	OK
6387	2026-09-14 21:01	46.63	OK	6388	2026-09-14 21:02	44.23	OK
6389	2026-09-14 21:03	44.01	OK	6390	2026-09-14 21:04	46.69	OK
6391	2026-09-14 21:05	46.46	OK	6392	2026-09-14 21:06	44.69	OK
6393	2026-09-14 21:07	44.40	OK	6394	2026-09-14 21:08	47.22	OK
6395	2026-09-14 21:09	45.30	OK	6396	2026-09-14 21:10	44.60	OK
6397	2026-09-14 21:11	44.73	OK	6398	2026-09-14 21:12	44.91	OK
6399	2026-09-14 21:13	45.25	OK	6400	2026-09-14 21:14	45.97	OK
6401	2026-09-14 21:15	43.97	OK	6402	2026-09-14 21:16	44.48	OK
6403	2026-09-14 21:17	45.29	OK	6404	2026-09-14 21:18	46.09	OK
6405	2026-09-14 21:19	45.90	OK	6406	2026-09-14 21:20	46.39	OK
6407	2026-09-14 21:21	44.52	OK	6408	2026-09-14 21:22	45.57	OK
6409	2026-09-14 21:23	44.47	OK	6410	2026-09-14 21:24	44.12	OK
6411	2026-09-14 21:25	45.57	OK	6412	2026-09-14 21:26	45.79	OK
6413	2026-09-14 21:27	46.63	OK	6414	2026-09-14 21:28	46.54	OK
6415	2026-09-14 21:29	45.33	OK	6416	2026-09-14 21:30	45.83	OK
6417	2026-09-14 21:31	45.72	OK	6418	2026-09-14 21:32	43.47	OK
6419	2026-09-14 21:33	45.23	OK	6420	2026-09-14 21:34	47.01	OK
6421	2026-09-14 21:35	44.50	OK	6422	2026-09-14 21:36	44.40	OK
6423	2026-09-14 21:37	43.67	OK	6424	2026-09-14 21:38	45.07	OK
6425	2026-09-14 21:39	44.89	OK	6426	2026-09-14 21:40	44.61	OK
6427	2026-09-14 21:41	45.18	OK	6428	2026-09-14 21:42	46.05	OK
6429	2026-09-14 21:43	43.52	OK	6430	2026-09-14 21:44	44.15	OK
6431	2026-09-14 21:45	43.43	OK	6432	2026-09-14 21:46	45.75	OK
6433	2026-09-14 21:47	46.01	OK	6434	2026-09-14 21:48	46.47	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6435	2026-09-14 21:49	45.82	OK	6436	2026-09-14 21:50	45.53	OK
6437	2026-09-14 21:51	44.28	OK	6438	2026-09-14 21:52	46.45	OK
6439	2026-09-14 21:53	45.82	OK	6440	2026-09-14 21:54	45.32	OK
6441	2026-09-14 21:55	46.40	OK	6442	2026-09-14 21:56	44.93	OK
6443	2026-09-14 21:57	45.32	OK	6444	2026-09-14 21:58	44.95	OK
6445	2026-09-14 21:59	44.96	OK	6446	2026-09-14 22:00	45.65	OK
6447	2026-09-14 22:01	46.94	OK	6448	2026-09-14 22:02	43.64	OK
6449	2026-09-14 22:03	43.55	OK	6450	2026-09-14 22:04	44.48	OK
6451	2026-09-14 22:05	44.15	OK	6452	2026-09-14 22:06	44.60	OK
6453	2026-09-14 22:07	46.29	OK	6454	2026-09-14 22:08	45.96	OK
6455	2026-09-14 22:09	45.73	OK	6456	2026-09-14 22:10	45.09	OK
6457	2026-09-14 22:11	43.88	OK	6458	2026-09-14 22:12	43.09	OK
6459	2026-09-14 22:13	45.62	OK	6460	2026-09-14 22:14	45.75	OK
6461	2026-09-14 22:15	44.82	OK	6462	2026-09-14 22:16	45.34	OK
6463	2026-09-14 22:17	45.63	OK	6464	2026-09-14 22:18	45.57	OK
6465	2026-09-14 22:19	46.36	OK	6466	2026-09-14 22:20	45.65	OK
6467	2026-09-14 22:21	47.80	OK	6468	2026-09-14 22:22	44.30	OK
6469	2026-09-14 22:23	43.70	OK	6470	2026-09-14 22:24	43.72	OK
6471	2026-09-14 22:25	43.09	OK	6472	2026-09-14 22:26	45.33	OK
6473	2026-09-14 22:27	44.24	OK	6474	2026-09-14 22:28	43.18	OK
6475	2026-09-14 22:29	44.24	OK	6476	2026-09-14 22:30	45.53	OK
6477	2026-09-14 22:31	44.91	OK	6478	2026-09-14 22:32	46.37	OK
6479	2026-09-14 22:33	43.46	OK	6480	2026-09-14 22:34	47.22	OK
6481	2026-09-14 22:35	45.03	OK	6482	2026-09-14 22:36	43.34	OK
6483	2026-09-14 22:37	46.90	OK	6484	2026-09-14 22:38	47.12	OK
6485	2026-09-14 22:39	42.83	OK	6486	2026-09-14 22:40	43.33	OK
6487	2026-09-14 22:41	43.33	OK	6488	2026-09-14 22:42	44.77	OK
6489	2026-09-14 22:43	45.33	OK	6490	2026-09-14 22:44	42.33	OK
6491	2026-09-14 22:45	43.72	OK	6492	2026-09-14 22:46	45.63	OK
6493	2026-09-14 22:47	45.18	OK	6494	2026-09-14 22:48	46.07	OK
6495	2026-09-14 22:49	44.76	OK	6496	2026-09-14 22:50	44.68	OK
6497	2026-09-14 22:51	44.86	OK	6498	2026-09-14 22:52	43.72	OK
6499	2026-09-14 22:53	44.27	OK	6500	2026-09-14 22:54	45.07	OK
6501	2026-09-14 22:55	43.01	OK	6502	2026-09-14 22:56	44.33	OK
6503	2026-09-14 22:57	43.66	OK	6504	2026-09-14 22:58	45.20	OK
6505	2026-09-14 22:59	43.77	OK	6506	2026-09-14 23:00	44.94	OK
6507	2026-09-14 23:01	44.41	OK	6508	2026-09-14 23:02	45.64	OK
6509	2026-09-14 23:03	44.32	OK	6510	2026-09-14 23:04	43.14	OK
6511	2026-09-14 23:05	44.95	OK	6512	2026-09-14 23:06	44.69	OK
6513	2026-09-14 23:07	43.84	OK	6514	2026-09-14 23:08	45.13	OK
6515	2026-09-14 23:09	44.16	OK	6516	2026-09-14 23:10	42.87	OK
6517	2026-09-14 23:11	44.53	OK	6518	2026-09-14 23:12	45.74	OK
6519	2026-09-14 23:13	46.68	OK	6520	2026-09-14 23:14	43.84	OK
6521	2026-09-14 23:15	44.57	OK	6522	2026-09-14 23:16	45.27	OK
6523	2026-09-14 23:17	44.48	OK	6524	2026-09-14 23:18	45.25	OK
6525	2026-09-14 23:19	43.52	OK	6526	2026-09-14 23:20	45.53	OK
6527	2026-09-14 23:21	42.74	OK	6528	2026-09-14 23:22	44.43	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6529	2026-09-14 23:23	44.25	OK	6530	2026-09-14 23:24	44.02	OK
6531	2026-09-14 23:25	44.54	OK	6532	2026-09-14 23:26	45.32	OK
6533	2026-09-14 23:27	43.90	OK	6534	2026-09-14 23:28	45.24	OK
6535	2026-09-14 23:29	42.24	OK	6536	2026-09-14 23:30	44.35	OK
6537	2026-09-14 23:31	44.39	OK	6538	2026-09-14 23:32	42.25	OK
6539	2026-09-14 23:33	44.76	OK	6540	2026-09-14 23:34	44.04	OK
6541	2026-09-14 23:35	42.15	OK	6542	2026-09-14 23:36	42.65	OK
6543	2026-09-14 23:37	45.16	OK	6544	2026-09-14 23:38	44.81	OK
6545	2026-09-14 23:39	44.16	OK	6546	2026-09-14 23:40	43.95	OK
6547	2026-09-14 23:41	45.95	OK	6548	2026-09-14 23:42	45.53	OK
6549	2026-09-14 23:43	45.46	OK	6550	2026-09-14 23:44	45.45	OK
6551	2026-09-14 23:45	43.71	OK	6552	2026-09-14 23:46	43.23	OK
6553	2026-09-14 23:47	43.68	OK	6554	2026-09-14 23:48	46.06	OK
6555	2026-09-14 23:49	45.00	OK	6556	2026-09-14 23:50	45.37	OK
6557	2026-09-14 23:51	44.77	OK	6558	2026-09-14 23:52	47.00	OK
6559	2026-09-14 23:53	44.42	OK	6560	2026-09-14 23:54	45.93	OK
6561	2026-09-14 23:55	44.92	OK	6562	2026-09-14 23:56	45.06	OK
6563	2026-09-14 23:57	46.27	OK	6564	2026-09-14 23:58	45.14	OK
6565	2026-09-14 23:59	46.11	OK	6566	2026-09-15 00:00	44.32	OK
6567	2026-09-15 00:01	44.30	OK	6568	2026-09-15 00:02	43.80	OK
6569	2026-09-15 00:03	44.03	OK	6570	2026-09-15 00:04	46.08	OK
6571	2026-09-15 00:05	44.46	OK	6572	2026-09-15 00:06	44.43	OK
6573	2026-09-15 00:07	44.68	OK	6574	2026-09-15 00:08	43.11	OK
6575	2026-09-15 00:09	42.54	OK	6576	2026-09-15 00:10	43.56	OK
6577	2026-09-15 00:11	45.21	OK	6578	2026-09-15 00:12	44.97	OK
6579	2026-09-15 00:13	44.94	OK	6580	2026-09-15 00:14	44.84	OK
6581	2026-09-15 00:15	45.27	OK	6582	2026-09-15 00:16	46.95	OK
6583	2026-09-15 00:17	44.78	OK	6584	2026-09-15 00:18	43.91	OK
6585	2026-09-15 00:19	44.96	OK	6586	2026-09-15 00:20	44.25	OK
6587	2026-09-15 00:21	44.59	OK	6588	2026-09-15 00:22	44.13	OK
6589	2026-09-15 00:23	42.44	OK	6590	2026-09-15 00:24	44.14	OK
6591	2026-09-15 00:25	45.56	OK	6592	2026-09-15 00:26	46.09	OK
6593	2026-09-15 00:27	43.55	OK	6594	2026-09-15 00:28	44.84	OK
6595	2026-09-15 00:29	45.80	OK	6596	2026-09-15 00:30	46.09	OK
6597	2026-09-15 00:31	43.67	OK	6598	2026-09-15 00:32	44.20	OK
6599	2026-09-15 00:33	45.38	OK	6600	2026-09-15 00:34	44.86	OK
6601	2026-09-15 00:35	45.56	OK	6602	2026-09-15 00:36	44.90	OK
6603	2026-09-15 00:37	46.33	OK	6604	2026-09-15 00:38	44.12	OK
6605	2026-09-15 00:39	45.35	OK	6606	2026-09-15 00:40	43.79	OK
6607	2026-09-15 00:41	45.62	OK	6608	2026-09-15 00:42	45.06	OK
6609	2026-09-15 00:43	43.30	OK	6610	2026-09-15 00:44	45.31	OK
6611	2026-09-15 00:45	42.85	OK	6612	2026-09-15 00:46	45.13	OK
6613	2026-09-15 00:47	43.73	OK	6614	2026-09-15 00:48	47.16	OK
6615	2026-09-15 00:49	43.89	OK	6616	2026-09-15 00:50	46.19	OK
6617	2026-09-15 00:51	46.35	OK	6618	2026-09-15 00:52	44.10	OK
6619	2026-09-15 00:53	43.28	OK	6620	2026-09-15 00:54	47.07	OK
6621	2026-09-15 00:55	44.72	OK	6622	2026-09-15 00:56	45.63	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6623	2026-09-15 00:57	46.23	OK	6624	2026-09-15 00:58	43.43	OK
6625	2026-09-15 00:59	45.59	OK	6626	2026-09-15 01:00	42.57	OK
6627	2026-09-15 01:01	44.84	OK	6628	2026-09-15 01:02	43.85	OK
6629	2026-09-15 01:03	44.82	OK	6630	2026-09-15 01:04	42.75	OK
6631	2026-09-15 01:05	44.88	OK	6632	2026-09-15 01:06	44.27	OK
6633	2026-09-15 01:07	44.84	OK	6634	2026-09-15 01:08	43.47	OK
6635	2026-09-15 01:09	46.31	OK	6636	2026-09-15 01:10	46.53	OK
6637	2026-09-15 01:11	47.23	OK	6638	2026-09-15 01:12	46.55	OK
6639	2026-09-15 01:13	45.18	OK	6640	2026-09-15 01:14	45.77	OK
6641	2026-09-15 01:15	47.31	OK	6642	2026-09-15 01:16	44.78	OK
6643	2026-09-15 01:17	47.19	OK	6644	2026-09-15 01:18	43.95	OK
6645	2026-09-15 01:19	45.11	OK	6646	2026-09-15 01:20	46.13	OK
6647	2026-09-15 01:21	45.44	OK	6648	2026-09-15 01:22	46.42	OK
6649	2026-09-15 01:23	45.87	OK	6650	2026-09-15 01:24	43.54	OK
6651	2026-09-15 01:25	46.10	OK	6652	2026-09-15 01:26	46.16	OK
6653	2026-09-15 01:27	44.89	OK	6654	2026-09-15 01:28	45.86	OK
6655	2026-09-15 01:29	45.66	OK	6656	2026-09-15 01:30	43.72	OK
6657	2026-09-15 01:31	45.79	OK	6658	2026-09-15 01:32	46.95	OK
6659	2026-09-15 01:33	45.92	OK	6660	2026-09-15 01:34	48.12	OK
6661	2026-09-15 01:35	44.93	OK	6662	2026-09-15 01:36	44.96	OK
6663	2026-09-15 01:37	45.32	OK	6664	2026-09-15 01:38	46.44	OK
6665	2026-09-15 01:39	45.40	OK	6666	2026-09-15 01:40	47.01	OK
6667	2026-09-15 01:41	47.05	OK	6668	2026-09-15 01:42	44.03	OK
6669	2026-09-15 01:43	45.03	OK	6670	2026-09-15 01:44	43.70	OK
6671	2026-09-15 01:45	45.83	OK	6672	2026-09-15 01:46	44.53	OK
6673	2026-09-15 01:47	46.57	OK	6674	2026-09-15 01:48	44.33	OK
6675	2026-09-15 01:49	46.29	OK	6676	2026-09-15 01:50	45.30	OK
6677	2026-09-15 01:51	44.89	OK	6678	2026-09-15 01:52	45.00	OK
6679	2026-09-15 01:53	45.60	OK	6680	2026-09-15 01:54	47.08	OK
6681	2026-09-15 01:55	43.98	OK	6682	2026-09-15 01:56	45.57	OK
6683	2026-09-15 01:57	43.53	OK	6684	2026-09-15 01:58	45.16	OK
6685	2026-09-15 01:59	44.72	OK	6686	2026-09-15 02:00	42.91	OK
6687	2026-09-15 02:01	46.61	OK	6688	2026-09-15 02:02	45.86	OK
6689	2026-09-15 02:03	46.12	OK	6690	2026-09-15 02:04	45.79	OK
6691	2026-09-15 02:05	46.05	OK	6692	2026-09-15 02:06	46.69	OK
6693	2026-09-15 02:07	45.44	OK	6694	2026-09-15 02:08	45.70	OK
6695	2026-09-15 02:09	46.55	OK	6696	2026-09-15 02:10	44.39	OK
6697	2026-09-15 02:11	46.34	OK	6698	2026-09-15 02:12	46.50	OK
6699	2026-09-15 02:13	43.71	OK	6700	2026-09-15 02:14	45.89	OK
6701	2026-09-15 02:15	45.81	OK	6702	2026-09-15 02:16	46.62	OK
6703	2026-09-15 02:17	44.77	OK	6704	2026-09-15 02:18	45.33	OK
6705	2026-09-15 02:19	46.27	OK	6706	2026-09-15 02:20	48.27	OK
6707	2026-09-15 02:21	46.71	OK	6708	2026-09-15 02:22	45.52	OK
6709	2026-09-15 02:23	43.74	OK	6710	2026-09-15 02:24	47.59	OK
6711	2026-09-15 02:25	46.81	OK	6712	2026-09-15 02:26	45.96	OK
6713	2026-09-15 02:27	45.34	OK	6714	2026-09-15 02:28	44.89	OK
6715	2026-09-15 02:29	46.99	OK	6716	2026-09-15 02:30	47.55	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6717	2026-09-15 02:31	46.16	OK	6718	2026-09-15 02:32	45.65	OK
6719	2026-09-15 02:33	45.81	OK	6720	2026-09-15 02:34	46.66	OK
6721	2026-09-15 02:35	46.58	OK	6722	2026-09-15 02:36	47.43	OK
6723	2026-09-15 02:37	45.00	OK	6724	2026-09-15 02:38	46.53	OK
6725	2026-09-15 02:39	47.61	OK	6726	2026-09-15 02:40	46.10	OK
6727	2026-09-15 02:41	46.84	OK	6728	2026-09-15 02:42	46.22	OK
6729	2026-09-15 02:43	47.87	OK	6730	2026-09-15 02:44	45.40	OK
6731	2026-09-15 02:45	45.01	OK	6732	2026-09-15 02:46	45.03	OK
6733	2026-09-15 02:47	47.62	OK	6734	2026-09-15 02:48	45.80	OK
6735	2026-09-15 02:49	47.30	OK	6736	2026-09-15 02:50	44.95	OK
6737	2026-09-15 02:51	46.18	OK	6738	2026-09-15 02:52	46.80	OK
6739	2026-09-15 02:53	46.10	OK	6740	2026-09-15 02:54	46.53	OK
6741	2026-09-15 02:55	46.16	OK	6742	2026-09-15 02:56	45.60	OK
6743	2026-09-15 02:57	45.36	OK	6744	2026-09-15 02:58	47.37	OK
6745	2026-09-15 02:59	46.60	OK	6746	2026-09-15 03:00	47.18	OK
6747	2026-09-15 03:01	47.63	OK	6748	2026-09-15 03:02	45.91	OK
6749	2026-09-15 03:03	47.11	OK	6750	2026-09-15 03:04	45.56	OK
6751	2026-09-15 03:05	46.05	OK	6752	2026-09-15 03:06	45.22	OK
6753	2026-09-15 03:07	47.70	OK	6754	2026-09-15 03:08	47.00	OK
6755	2026-09-15 03:09	46.38	OK	6756	2026-09-15 03:10	47.33	OK
6757	2026-09-15 03:11	47.48	OK	6758	2026-09-15 03:12	47.39	OK
6759	2026-09-15 03:13	47.41	OK	6760	2026-09-15 03:14	47.96	OK
6761	2026-09-15 03:15	47.49	OK	6762	2026-09-15 03:16	47.25	OK
6763	2026-09-15 03:17	48.65	OK	6764	2026-09-15 03:18	46.15	OK
6765	2026-09-15 03:19	48.47	OK	6766	2026-09-15 03:20	46.97	OK
6767	2026-09-15 03:21	46.85	OK	6768	2026-09-15 03:22	47.25	OK
6769	2026-09-15 03:23	46.49	OK	6770	2026-09-15 03:24	48.51	OK
6771	2026-09-15 03:25	45.88	OK	6772	2026-09-15 03:26	47.47	OK
6773	2026-09-15 03:27	47.85	OK	6774	2026-09-15 03:28	46.13	OK
6775	2026-09-15 03:29	48.36	OK	6776	2026-09-15 03:30	47.69	OK
6777	2026-09-15 03:31	46.41	OK	6778	2026-09-15 03:32	46.63	OK
6779	2026-09-15 03:33	47.45	OK	6780	2026-09-15 03:34	47.47	OK
6781	2026-09-15 03:35	47.04	OK	6782	2026-09-15 03:36	46.05	OK
6783	2026-09-15 03:37	45.65	OK	6784	2026-09-15 03:38	46.02	OK
6785	2026-09-15 03:39	46.03	OK	6786	2026-09-15 03:40	48.03	OK
6787	2026-09-15 03:41	45.05	OK	6788	2026-09-15 03:42	48.73	OK
6789	2026-09-15 03:43	49.26	OK	6790	2026-09-15 03:44	49.65	OK
6791	2026-09-15 03:45	47.13	OK	6792	2026-09-15 03:46	49.59	OK
6793	2026-09-15 03:47	48.37	OK	6794	2026-09-15 03:48	46.73	OK
6795	2026-09-15 03:49	47.06	OK	6796	2026-09-15 03:50	47.78	OK
6797	2026-09-15 03:51	47.87	OK	6798	2026-09-15 03:52	47.01	OK
6799	2026-09-15 03:53	46.44	OK	6800	2026-09-15 03:54	48.48	OK
6801	2026-09-15 03:55	47.68	OK	6802	2026-09-15 03:56	47.11	OK
6803	2026-09-15 03:57	47.21	OK	6804	2026-09-15 03:58	48.47	OK
6805	2026-09-15 03:59	47.93	OK	6806	2026-09-15 04:00	46.90	OK
6807	2026-09-15 04:01	49.84	OK	6808	2026-09-15 04:02	46.22	OK
6809	2026-09-15 04:03	47.85	OK	6810	2026-09-15 04:04	47.89	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6811	2026-09-15 04:05	50.05	OK	6812	2026-09-15 04:06	47.16	OK
6813	2026-09-15 04:07	46.52	OK	6814	2026-09-15 04:08	47.20	OK
6815	2026-09-15 04:09	47.67	OK	6816	2026-09-15 04:10	47.33	OK
6817	2026-09-15 04:11	48.51	OK	6818	2026-09-15 04:12	46.36	OK
6819	2026-09-15 04:13	47.15	OK	6820	2026-09-15 04:14	47.54	OK
6821	2026-09-15 04:15	48.54	OK	6822	2026-09-15 04:16	46.33	OK
6823	2026-09-15 04:17	49.46	OK	6824	2026-09-15 04:18	47.69	OK
6825	2026-09-15 04:19	48.97	OK	6826	2026-09-15 04:20	47.25	OK
6827	2026-09-15 04:21	47.19	OK	6828	2026-09-15 04:22	47.60	OK
6829	2026-09-15 04:23	46.75	OK	6830	2026-09-15 04:24	45.18	OK
6831	2026-09-15 04:25	47.10	OK	6832	2026-09-15 04:26	47.32	OK
6833	2026-09-15 04:27	48.18	OK	6834	2026-09-15 04:28	49.40	OK
6835	2026-09-15 04:29	48.27	OK	6836	2026-09-15 04:30	47.54	OK
6837	2026-09-15 04:31	48.66	OK	6838	2026-09-15 04:32	47.76	OK
6839	2026-09-15 04:33	47.60	OK	6840	2026-09-15 04:34	47.28	OK
6841	2026-09-15 04:35	48.08	OK	6842	2026-09-15 04:36	47.90	OK
6843	2026-09-15 04:37	47.86	OK	6844	2026-09-15 04:38	47.42	OK
6845	2026-09-15 04:39	48.82	OK	6846	2026-09-15 04:40	47.64	OK
6847	2026-09-15 04:41	47.12	OK	6848	2026-09-15 04:42	48.18	OK
6849	2026-09-15 04:43	48.66	OK	6850	2026-09-15 04:44	47.81	OK
6851	2026-09-15 04:45	49.31	OK	6852	2026-09-15 04:46	48.92	OK
6853	2026-09-15 04:47	47.67	OK	6854	2026-09-15 04:48	49.38	OK
6855	2026-09-15 04:49	50.78	OK	6856	2026-09-15 04:50	49.40	OK
6857	2026-09-15 04:51	48.58	OK	6858	2026-09-15 04:52	49.34	OK
6859	2026-09-15 04:53	48.19	OK	6860	2026-09-15 04:54	48.82	OK
6861	2026-09-15 04:55	47.31	OK	6862	2026-09-15 04:56	47.88	OK
6863	2026-09-15 04:57	48.65	OK	6864	2026-09-15 04:58	49.62	OK
6865	2026-09-15 04:59	47.64	OK	6866	2026-09-15 05:00	49.49	OK
6867	2026-09-15 05:01	49.98	OK	6868	2026-09-15 05:02	49.50	OK
6869	2026-09-15 05:03	49.21	OK	6870	2026-09-15 05:04	47.37	OK
6871	2026-09-15 05:05	47.73	OK	6872	2026-09-15 05:06	48.54	OK
6873	2026-09-15 05:07	48.32	OK	6874	2026-09-15 05:08	48.83	OK
6875	2026-09-15 05:09	48.48	OK	6876	2026-09-15 05:10	50.21	OK
6877	2026-09-15 05:11	51.13	OK	6878	2026-09-15 05:12	51.31	OK
6879	2026-09-15 05:13	49.55	OK	6880	2026-09-15 05:14	50.56	OK
6881	2026-09-15 05:15	51.10	OK	6882	2026-09-15 05:16	49.20	OK
6883	2026-09-15 05:17	48.80	OK	6884	2026-09-15 05:18	47.44	OK
6885	2026-09-15 05:19	51.73	OK	6886	2026-09-15 05:20	50.17	OK
6887	2026-09-15 05:21	49.64	OK	6888	2026-09-15 05:22	49.29	OK
6889	2026-09-15 05:23	50.58	OK	6890	2026-09-15 05:24	50.00	OK
6891	2026-09-15 05:25	47.82	OK	6892	2026-09-15 05:26	48.73	OK
6893	2026-09-15 05:27	47.89	OK	6894	2026-09-15 05:28	49.39	OK
6895	2026-09-15 05:29	49.07	OK	6896	2026-09-15 05:30	48.62	OK
6897	2026-09-15 05:31	50.72	OK	6898	2026-09-15 05:32	47.95	OK
6899	2026-09-15 05:33	50.68	OK	6900	2026-09-15 05:34	49.42	OK
6901	2026-09-15 05:35	48.46	OK	6902	2026-09-15 05:36	48.75	OK
6903	2026-09-15 05:37	49.20	OK	6904	2026-09-15 05:38	50.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6905	2026-09-15 05:39	49.83	OK	6906	2026-09-15 05:40	49.59	OK
6907	2026-09-15 05:41	48.26	OK	6908	2026-09-15 05:42	49.83	OK
6909	2026-09-15 05:43	49.64	OK	6910	2026-09-15 05:44	52.00	OK
6911	2026-09-15 05:45	50.56	OK	6912	2026-09-15 05:46	49.40	OK
6913	2026-09-15 05:47	50.39	OK	6914	2026-09-15 05:48	50.71	OK
6915	2026-09-15 05:49	50.16	OK	6916	2026-09-15 05:50	50.18	OK
6917	2026-09-15 05:51	48.82	OK	6918	2026-09-15 05:52	50.07	OK
6919	2026-09-15 05:53	51.44	OK	6920	2026-09-15 05:54	49.35	OK
6921	2026-09-15 05:55	50.44	OK	6922	2026-09-15 05:56	50.13	OK
6923	2026-09-15 05:57	49.40	OK	6924	2026-09-15 05:58	49.97	OK
6925	2026-09-15 05:59	49.79	OK	6926	2026-09-15 06:00	48.97	OK
6927	2026-09-15 06:01	51.67	OK	6928	2026-09-15 06:02	50.88	OK
6929	2026-09-15 06:03	50.21	OK	6930	2026-09-15 06:04	50.72	OK
6931	2026-09-15 06:05	52.02	OK	6932	2026-09-15 06:06	48.96	OK
6933	2026-09-15 06:07	49.44	OK	6934	2026-09-15 06:08	51.46	OK
6935	2026-09-15 06:09	49.74	OK	6936	2026-09-15 06:10	50.65	OK
6937	2026-09-15 06:11	51.32	OK	6938	2026-09-15 06:12	51.03	OK
6939	2026-09-15 06:13	49.34	OK	6940	2026-09-15 06:14	49.67	OK
6941	2026-09-15 06:15	50.57	OK	6942	2026-09-15 06:16	49.77	OK
6943	2026-09-15 06:17	50.77	OK	6944	2026-09-15 06:18	51.20	OK
6945	2026-09-15 06:19	49.66	OK	6946	2026-09-15 06:20	50.20	OK
6947	2026-09-15 06:21	51.73	OK	6948	2026-09-15 06:22	49.72	OK
6949	2026-09-15 06:23	50.22	OK	6950	2026-09-15 06:24	50.95	OK
6951	2026-09-15 06:25	51.55	OK	6952	2026-09-15 06:26	51.60	OK
6953	2026-09-15 06:27	50.28	OK	6954	2026-09-15 06:28	50.49	OK
6955	2026-09-15 06:29	51.89	OK	6956	2026-09-15 06:30	51.16	OK
6957	2026-09-15 06:31	50.92	OK	6958	2026-09-15 06:32	51.57	OK
6959	2026-09-15 06:33	50.10	OK	6960	2026-09-15 06:34	49.21	OK
6961	2026-09-15 06:35	50.58	OK	6962	2026-09-15 06:36	49.73	OK
6963	2026-09-15 06:37	51.74	OK	6964	2026-09-15 06:38	49.98	OK
6965	2026-09-15 06:39	49.61	OK	6966	2026-09-15 06:40	50.42	OK
6967	2026-09-15 06:41	51.22	OK	6968	2026-09-15 06:42	50.04	OK
6969	2026-09-15 06:43	48.66	OK	6970	2026-09-15 06:44	51.13	OK
6971	2026-09-15 06:45	50.09	OK	6972	2026-09-15 06:46	50.57	OK
6973	2026-09-15 06:47	52.22	OK	6974	2026-09-15 06:48	50.53	OK
6975	2026-09-15 06:49	51.45	OK	6976	2026-09-15 06:50	50.78	OK
6977	2026-09-15 06:51	51.14	OK	6978	2026-09-15 06:52	51.48	OK
6979	2026-09-15 06:53	49.87	OK	6980	2026-09-15 06:54	50.51	OK
6981	2026-09-15 06:55	50.84	OK	6982	2026-09-15 06:56	52.01	OK
6983	2026-09-15 06:57	48.93	OK	6984	2026-09-15 06:58	53.82	OK
6985	2026-09-15 06:59	50.06	OK	6986	2026-09-15 07:00	50.00	OK
6987	2026-09-15 07:01	51.03	OK	6988	2026-09-15 07:02	52.24	OK
6989	2026-09-15 07:03	51.87	OK	6990	2026-09-15 07:04	51.66	OK
6991	2026-09-15 07:05	49.64	OK	6992	2026-09-15 07:06	52.04	OK
6993	2026-09-15 07:07	52.08	OK	6994	2026-09-15 07:08	50.89	OK
6995	2026-09-15 07:09	52.70	OK	6996	2026-09-15 07:10	51.32	OK
6997	2026-09-15 07:11	50.21	OK	6998	2026-09-15 07:12	50.80	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6999	2026-09-15 07:13	51.22	OK	7000	2026-09-15 07:14	51.92	OK
7001	2026-09-15 07:15	51.13	OK	7002	2026-09-15 07:16	51.38	OK
7003	2026-09-15 07:17	53.22	OK	7004	2026-09-15 07:18	52.82	OK
7005	2026-09-15 07:19	51.91	OK	7006	2026-09-15 07:20	52.94	OK
7007	2026-09-15 07:21	49.57	OK	7008	2026-09-15 07:22	50.81	OK
7009	2026-09-15 07:23	51.99	OK	7010	2026-09-15 07:24	49.66	OK
7011	2026-09-15 07:25	50.18	OK	7012	2026-09-15 07:26	51.63	OK
7013	2026-09-15 07:27	53.73	OK	7014	2026-09-15 07:28	52.55	OK
7015	2026-09-15 07:29	50.77	OK	7016	2026-09-15 07:30	50.97	OK
7017	2026-09-15 07:31	52.52	OK	7018	2026-09-15 07:32	53.81	OK
7019	2026-09-15 07:33	53.75	OK	7020	2026-09-15 07:34	51.80	OK
7021	2026-09-15 07:35	50.59	OK	7022	2026-09-15 07:36	52.39	OK
7023	2026-09-15 07:37	51.13	OK	7024	2026-09-15 07:38	51.79	OK
7025	2026-09-15 07:39	53.24	OK	7026	2026-09-15 07:40	52.94	OK
7027	2026-09-15 07:41	51.74	OK	7028	2026-09-15 07:42	52.38	OK
7029	2026-09-15 07:43	53.58	OK	7030	2026-09-15 07:44	52.13	OK
7031	2026-09-15 07:45	51.76	OK	7032	2026-09-15 07:46	51.60	OK
7033	2026-09-15 07:47	51.86	OK	7034	2026-09-15 07:48	51.83	OK
7035	2026-09-15 07:49	51.18	OK	7036	2026-09-15 07:50	51.45	OK
7037	2026-09-15 07:51	50.96	OK	7038	2026-09-15 07:52	51.51	OK
7039	2026-09-15 07:53	49.65	OK	7040	2026-09-15 07:54	51.65	OK
7041	2026-09-15 07:55	52.94	OK	7042	2026-09-15 07:56	53.35	OK
7043	2026-09-15 07:57	53.29	OK	7044	2026-09-15 07:58	51.28	OK
7045	2026-09-15 07:59	53.81	OK	7046	2026-09-15 08:00	52.98	OK
7047	2026-09-15 08:01	52.38	OK	7048	2026-09-15 08:02	51.87	OK
7049	2026-09-15 08:03	52.88	OK	7050	2026-09-15 08:04	51.25	OK
7051	2026-09-15 08:05	52.63	OK	7052	2026-09-15 08:06	52.93	OK
7053	2026-09-15 08:07	52.80	OK	7054	2026-09-15 08:08	52.22	OK
7055	2026-09-15 08:09	50.58	OK	7056	2026-09-15 08:10	52.60	OK
7057	2026-09-15 08:11	53.27	OK	7058	2026-09-15 08:12	51.74	OK
7059	2026-09-15 08:13	53.47	OK	7060	2026-09-15 08:14	53.67	OK
7061	2026-09-15 08:15	52.66	OK	7062	2026-09-15 08:16	53.03	OK
7063	2026-09-15 08:17	52.70	OK	7064	2026-09-15 08:18	52.35	OK
7065	2026-09-15 08:19	51.18	OK	7066	2026-09-15 08:20	52.39	OK
7067	2026-09-15 08:21	53.44	OK	7068	2026-09-15 08:22	53.34	OK
7069	2026-09-15 08:23	52.63	OK	7070	2026-09-15 08:24	53.17	OK
7071	2026-09-15 08:25	51.02	OK	7072	2026-09-15 08:26	52.65	OK
7073	2026-09-15 08:27	53.91	OK	7074	2026-09-15 08:28	53.46	OK
7075	2026-09-15 08:29	54.36	OK	7076	2026-09-15 08:30	52.68	OK
7077	2026-09-15 08:31	52.27	OK	7078	2026-09-15 08:32	54.44	OK
7079	2026-09-15 08:33	53.13	OK	7080	2026-09-15 08:34	55.56	OK
7081	2026-09-15 08:35	51.73	OK	7082	2026-09-15 08:36	53.01	OK
7083	2026-09-15 08:37	52.41	OK	7084	2026-09-15 08:38	52.33	OK
7085	2026-09-15 08:39	52.14	OK	7086	2026-09-15 08:40	52.16	OK
7087	2026-09-15 08:41	51.41	OK	7088	2026-09-15 08:42	54.06	OK
7089	2026-09-15 08:43	53.24	OK	7090	2026-09-15 08:44	54.30	OK
7091	2026-09-15 08:45	52.52	OK	7092	2026-09-15 08:46	53.77	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7093	2026-09-15 08:47	53.79	OK	7094	2026-09-15 08:48	51.95	OK
7095	2026-09-15 08:49	53.42	OK	7096	2026-09-15 08:50	52.10	OK
7097	2026-09-15 08:51	53.79	OK	7098	2026-09-15 08:52	51.81	OK
7099	2026-09-15 08:53	55.49	OK	7100	2026-09-15 08:54	54.50	OK
7101	2026-09-15 08:55	55.73	OK	7102	2026-09-15 08:56	53.26	OK
7103	2026-09-15 08:57	52.37	OK	7104	2026-09-15 08:58	55.73	OK
7105	2026-09-15 08:59	52.17	OK	7106	2026-09-15 09:00	53.39	OK
7107	2026-09-15 09:01	51.44	OK	7108	2026-09-15 09:02	53.75	OK
7109	2026-09-15 09:03	55.01	OK	7110	2026-09-15 09:04	53.73	OK
7111	2026-09-15 09:05	53.87	OK	7112	2026-09-15 09:06	54.27	OK
7113	2026-09-15 09:07	54.49	OK	7114	2026-09-15 09:08	53.40	OK
7115	2026-09-15 09:09	53.06	OK	7116	2026-09-15 09:10	53.53	OK
7117	2026-09-15 09:11	55.04	OK	7118	2026-09-15 09:12	52.87	OK
7119	2026-09-15 09:13	51.24	OK	7120	2026-09-15 09:14	53.30	OK
7121	2026-09-15 09:15	52.72	OK	7122	2026-09-15 09:16	51.95	OK
7123	2026-09-15 09:17	52.92	OK	7124	2026-09-15 09:18	53.34	OK
7125	2026-09-15 09:19	52.55	OK	7126	2026-09-15 09:20	51.72	OK
7127	2026-09-15 09:21	52.61	OK	7128	2026-09-15 09:22	53.32	OK
7129	2026-09-15 09:23	55.35	OK	7130	2026-09-15 09:24	53.64	OK
7131	2026-09-15 09:25	54.13	OK	7132	2026-09-15 09:26	55.01	OK
7133	2026-09-15 09:27	52.57	OK	7134	2026-09-15 09:28	55.67	OK
7135	2026-09-15 09:29	51.09	OK	7136	2026-09-15 09:30	55.76	OK
7137	2026-09-15 09:31	55.38	OK	7138	2026-09-15 09:32	52.18	OK
7139	2026-09-15 09:33	52.65	OK	7140	2026-09-15 09:34	52.59	OK
7141	2026-09-15 09:35	54.53	OK	7142	2026-09-15 09:36	52.82	OK
7143	2026-09-15 09:37	54.43	OK	7144	2026-09-15 09:38	55.78	OK
7145	2026-09-15 09:39	52.70	OK	7146	2026-09-15 09:40	53.69	OK
7147	2026-09-15 09:41	54.08	OK	7148	2026-09-15 09:42	54.24	OK
7149	2026-09-15 09:43	53.50	OK	7150	2026-09-15 09:44	53.90	OK
7151	2026-09-15 09:45	56.31	OK	7152	2026-09-15 09:46	53.32	OK
7153	2026-09-15 09:47	53.69	OK	7154	2026-09-15 09:48	53.18	OK
7155	2026-09-15 09:49	53.73	OK	7156	2026-09-15 09:50	51.75	OK
7157	2026-09-15 09:51	55.16	OK	7158	2026-09-15 09:52	55.87	OK
7159	2026-09-15 09:53	55.82	OK	7160	2026-09-15 09:54	52.23	OK
7161	2026-09-15 09:55	53.08	OK	7162	2026-09-15 09:56	55.14	OK
7163	2026-09-15 09:57	55.15	OK	7164	2026-09-15 09:58	52.45	OK
7165	2026-09-15 09:59	52.48	OK	7166	2026-09-15 10:00	52.07	OK
7167	2026-09-15 10:01	54.35	OK	7168	2026-09-15 10:02	52.35	OK
7169	2026-09-15 10:03	52.27	OK	7170	2026-09-15 10:04	52.13	OK
7171	2026-09-15 10:05	54.04	OK	7172	2026-09-15 10:06	55.40	OK
7173	2026-09-15 10:07	54.08	OK	7174	2026-09-15 10:08	54.74	OK
7175	2026-09-15 10:09	54.23	OK	7176	2026-09-15 10:10	53.32	OK
7177	2026-09-15 10:11	51.83	OK	7178	2026-09-15 10:12	53.24	OK
7179	2026-09-15 10:13	53.80	OK	7180	2026-09-15 10:14	53.08	OK
7181	2026-09-15 10:15	51.89	OK	7182	2026-09-15 10:16	53.57	OK
7183	2026-09-15 10:17	53.99	OK	7184	2026-09-15 10:18	53.90	OK
7185	2026-09-15 10:19	52.50	OK	7186	2026-09-15 10:20	51.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7187	2026-09-15 10:21	53.74	OK	7188	2026-09-15 10:22	52.15	OK
7189	2026-09-15 10:23	53.11	OK	7190	2026-09-15 10:24	54.46	OK
7191	2026-09-15 10:25	54.66	OK	7192	2026-09-15 10:26	52.95	OK
7193	2026-09-15 10:27	54.24	OK	7194	2026-09-15 10:28	54.57	OK
7195	2026-09-15 10:29	54.27	OK	7196	2026-09-15 10:30	54.55	OK
7197	2026-09-15 10:31	54.05	OK	7198	2026-09-15 10:32	54.78	OK
7199	2026-09-15 10:33	55.45	OK	7200	2026-09-15 10:34	54.11	OK
7201	2026-09-15 10:35	54.33	OK	7202	2026-09-15 10:36	52.78	OK
7203	2026-09-15 10:37	53.44	OK	7204	2026-09-15 10:38	55.15	OK
7205	2026-09-15 10:39	55.20	OK	7206	2026-09-15 10:40	54.06	OK
7207	2026-09-15 10:41	55.16	OK	7208	2026-09-15 10:42	54.90	OK
7209	2026-09-15 10:43	56.56	OK	7210	2026-09-15 10:44	54.98	OK
7211	2026-09-15 10:45	55.43	OK	7212	2026-09-15 10:46	53.60	OK
7213	2026-09-15 10:47	53.62	OK	7214	2026-09-15 10:48	52.33	OK
7215	2026-09-15 10:49	56.06	OK	7216	2026-09-15 10:50	55.97	OK
7217	2026-09-15 10:51	53.36	OK	7218	2026-09-15 10:52	54.87	OK
7219	2026-09-15 10:53	53.83	OK	7220	2026-09-15 10:54	53.20	OK
7221	2026-09-15 10:55	55.32	OK	7222	2026-09-15 10:56	52.35	OK
7223	2026-09-15 10:57	54.48	OK	7224	2026-09-15 10:58	53.73	OK
7225	2026-09-15 10:59	53.88	OK	7226	2026-09-15 11:00	54.02	OK
7227	2026-09-15 11:01	54.02	OK	7228	2026-09-15 11:02	54.20	OK
7229	2026-09-15 11:03	55.26	OK	7230	2026-09-15 11:04	54.89	OK
7231	2026-09-15 11:05	52.86	OK	7232	2026-09-15 11:06	54.21	OK
7233	2026-09-15 11:07	52.91	OK	7234	2026-09-15 11:08	54.92	OK
7235	2026-09-15 11:09	54.73	OK	7236	2026-09-15 11:10	53.41	OK
7237	2026-09-15 11:11	53.71	OK	7238	2026-09-15 11:12	53.85	OK
7239	2026-09-15 11:13	55.17	OK	7240	2026-09-15 11:14	54.34	OK
7241	2026-09-15 11:15	53.71	OK	7242	2026-09-15 11:16	55.16	OK
7243	2026-09-15 11:17	53.11	OK	7244	2026-09-15 11:18	52.99	OK
7245	2026-09-15 11:19	55.59	OK	7246	2026-09-15 11:20	52.63	OK
7247	2026-09-15 11:21	53.49	OK	7248	2026-09-15 11:22	55.16	OK
7249	2026-09-15 11:23	54.15	OK	7250	2026-09-15 11:24	54.30	OK
7251	2026-09-15 11:25	54.61	OK	7252	2026-09-15 11:26	55.53	OK
7253	2026-09-15 11:27	54.96	OK	7254	2026-09-15 11:28	54.35	OK
7255	2026-09-15 11:29	55.20	OK	7256	2026-09-15 11:30	53.39	OK
7257	2026-09-15 11:31	54.42	OK	7258	2026-09-15 11:32	55.13	OK
7259	2026-09-15 11:33	53.32	OK	7260	2026-09-15 11:34	53.37	OK
7261	2026-09-15 11:35	55.73	OK	7262	2026-09-15 11:36	54.81	OK
7263	2026-09-15 11:37	52.26	OK	7264	2026-09-15 11:38	55.67	OK
7265	2026-09-15 11:39	55.85	OK	7266	2026-09-15 11:40	53.22	OK
7267	2026-09-15 11:41	52.77	OK	7268	2026-09-15 11:42	53.10	OK
7269	2026-09-15 11:43	54.11	OK	7270	2026-09-15 11:44	53.69	OK
7271	2026-09-15 11:45	56.06	OK	7272	2026-09-15 11:46	52.41	OK
7273	2026-09-15 11:47	55.40	OK	7274	2026-09-15 11:48	53.34	OK
7275	2026-09-15 11:49	54.15	OK	7276	2026-09-15 11:50	54.44	OK
7277	2026-09-15 11:51	56.47	OK	7278	2026-09-15 11:52	53.99	OK
7279	2026-09-15 11:53	53.04	OK	7280	2026-09-15 11:54	54.15	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7281	2026-09-15 11:55	54.51	OK	7282	2026-09-15 11:56	54.88	OK
7283	2026-09-15 11:57	52.76	OK	7284	2026-09-15 11:58	54.87	OK
7285	2026-09-15 11:59	55.21	OK	7286	2026-09-15 12:00	52.19	OK
7287	2026-09-15 12:01	54.56	OK	7288	2026-09-15 12:02	53.23	OK
7289	2026-09-15 12:03	54.73	OK	7290	2026-09-15 12:04	53.49	OK
7291	2026-09-15 12:05	54.15	OK	7292	2026-09-15 12:06	52.03	OK
7293	2026-09-15 12:07	54.96	OK	7294	2026-09-15 12:08	53.66	OK
7295	2026-09-15 12:09	54.13	OK	7296	2026-09-15 12:10	55.00	OK
7297	2026-09-15 12:11	56.18	OK	7298	2026-09-15 12:12	55.56	OK
7299	2026-09-15 12:13	55.56	OK	7300	2026-09-15 12:14	55.03	OK
7301	2026-09-15 12:15	54.20	OK	7302	2026-09-15 12:16	52.84	OK
7303	2026-09-15 12:17	55.10	OK	7304	2026-09-15 12:18	55.65	OK
7305	2026-09-15 12:19	52.58	OK	7306	2026-09-15 12:20	51.98	OK
7307	2026-09-15 12:21	55.96	OK	7308	2026-09-15 12:22	54.36	OK
7309	2026-09-15 12:23	55.43	OK	7310	2026-09-15 12:24	56.37	OK
7311	2026-09-15 12:25	55.19	OK	7312	2026-09-15 12:26	53.94	OK
7313	2026-09-15 12:27	54.48	OK	7314	2026-09-15 12:28	54.19	OK
7315	2026-09-15 12:29	55.48	OK	7316	2026-09-15 12:30	53.92	OK
7317	2026-09-15 12:31	54.50	OK	7318	2026-09-15 12:32	54.16	OK
7319	2026-09-15 12:33	54.08	OK	7320	2026-09-15 12:34	52.90	OK
7321	2026-09-15 12:35	54.68	OK	7322	2026-09-15 12:36	55.53	OK
7323	2026-09-15 12:37	53.05	OK	7324	2026-09-15 12:38	54.20	OK
7325	2026-09-15 12:39	52.95	OK	7326	2026-09-15 12:40	54.63	OK
7327	2026-09-15 12:41	51.67	OK	7328	2026-09-15 12:42	54.45	OK
7329	2026-09-15 12:43	54.40	OK	7330	2026-09-15 12:44	54.97	OK
7331	2026-09-15 12:45	54.72	OK	7332	2026-09-15 12:46	53.90	OK
7333	2026-09-15 12:47	54.64	OK	7334	2026-09-15 12:48	52.57	OK
7335	2026-09-15 12:49	52.41	OK	7336	2026-09-15 12:50	55.00	OK
7337	2026-09-15 12:51	52.97	OK	7338	2026-09-15 12:52	53.91	OK
7339	2026-09-15 12:53	52.31	OK	7340	2026-09-15 12:54	52.69	OK
7341	2026-09-15 12:55	53.81	OK	7342	2026-09-15 12:56	53.42	OK
7343	2026-09-15 12:57	53.51	OK	7344	2026-09-15 12:58	54.15	OK
7345	2026-09-15 12:59	54.38	OK	7346	2026-09-15 13:00	54.20	OK
7347	2026-09-15 13:01	54.28	OK	7348	2026-09-15 13:02	53.28	OK
7349	2026-09-15 13:03	52.55	OK	7350	2026-09-15 13:04	54.20	OK
7351	2026-09-15 13:05	53.13	OK	7352	2026-09-15 13:06	52.79	OK
7353	2026-09-15 13:07	52.49	OK	7354	2026-09-15 13:08	55.08	OK
7355	2026-09-15 13:09	51.93	OK	7356	2026-09-15 13:10	52.71	OK
7357	2026-09-15 13:11	53.57	OK	7358	2026-09-15 13:12	52.95	OK
7359	2026-09-15 13:13	52.61	OK	7360	2026-09-15 13:14	54.22	OK
7361	2026-09-15 13:15	53.56	OK	7362	2026-09-15 13:16	52.13	OK
7363	2026-09-15 13:17	51.65	OK	7364	2026-09-15 13:18	53.47	OK
7365	2026-09-15 13:19	53.80	OK	7366	2026-09-15 13:20	55.30	OK
7367	2026-09-15 13:21	54.58	OK	7368	2026-09-15 13:22	53.21	OK
7369	2026-09-15 13:23	54.63	OK	7370	2026-09-15 13:24	54.88	OK
7371	2026-09-15 13:25	52.37	OK	7372	2026-09-15 13:26	53.89	OK
7373	2026-09-15 13:27	52.08	OK	7374	2026-09-15 13:28	53.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7375	2026-09-15 13:29	51.67	OK	7376	2026-09-15 13:30	52.51	OK
7377	2026-09-15 13:31	52.72	OK	7378	2026-09-15 13:32	53.42	OK
7379	2026-09-15 13:33	54.30	OK	7380	2026-09-15 13:34	53.17	OK
7381	2026-09-15 13:35	55.64	OK	7382	2026-09-15 13:36	51.85	OK
7383	2026-09-15 13:37	54.54	OK	7384	2026-09-15 13:38	53.62	OK
7385	2026-09-15 13:39	54.20	OK	7386	2026-09-15 13:40	52.39	OK
7387	2026-09-15 13:41	54.12	OK	7388	2026-09-15 13:42	51.67	OK
7389	2026-09-15 13:43	51.68	OK	7390	2026-09-15 13:44	52.89	OK
7391	2026-09-15 13:45	54.46	OK	7392	2026-09-15 13:46	54.43	OK
7393	2026-09-15 13:47	51.61	OK	7394	2026-09-15 13:48	53.00	OK
7395	2026-09-15 13:49	52.53	OK	7396	2026-09-15 13:50	53.91	OK
7397	2026-09-15 13:51	53.51	OK	7398	2026-09-15 13:52	51.80	OK
7399	2026-09-15 13:53	52.31	OK	7400	2026-09-15 13:54	54.03	OK
7401	2026-09-15 13:55	52.23	OK	7402	2026-09-15 13:56	54.58	OK
7403	2026-09-15 13:57	52.90	OK	7404	2026-09-15 13:58	53.92	OK
7405	2026-09-15 13:59	53.14	OK	7406	2026-09-15 14:00	54.31	OK
7407	2026-09-15 14:01	53.99	OK	7408	2026-09-15 14:02	53.56	OK
7409	2026-09-15 14:03	54.94	OK	7410	2026-09-15 14:04	51.86	OK
7411	2026-09-15 14:05	51.96	OK	7412	2026-09-15 14:06	52.27	OK
7413	2026-09-15 14:07	55.16	OK	7414	2026-09-15 14:08	52.21	OK
7415	2026-09-15 14:09	53.00	OK	7416	2026-09-15 14:10	51.86	OK
7417	2026-09-15 14:11	52.63	OK	7418	2026-09-15 14:12	54.10	OK
7419	2026-09-15 14:13	54.81	OK	7420	2026-09-15 14:14	52.10	OK
7421	2026-09-15 14:15	54.53	OK	7422	2026-09-15 14:16	52.64	OK
7423	2026-09-15 14:17	53.92	OK	7424	2026-09-15 14:18	52.21	OK
7425	2026-09-15 14:19	53.84	OK	7426	2026-09-15 14:20	52.08	OK
7427	2026-09-15 14:21	51.42	OK	7428	2026-09-15 14:22	52.48	OK
7429	2026-09-15 14:23	51.85	OK	7430	2026-09-15 14:24	53.01	OK
7431	2026-09-15 14:25	52.42	OK	7432	2026-09-15 14:26	54.36	OK
7433	2026-09-15 14:27	52.12	OK	7434	2026-09-15 14:28	52.69	OK
7435	2026-09-15 14:29	52.26	OK	7436	2026-09-15 14:30	52.66	OK
7437	2026-09-15 14:31	51.81	OK	7438	2026-09-15 14:32	52.37	OK
7439	2026-09-15 14:33	53.64	OK	7440	2026-09-15 14:34	55.08	OK
7441	2026-09-15 14:35	51.76	OK	7442	2026-09-15 14:36	54.59	OK
7443	2026-09-15 14:37	50.70	OK	7444	2026-09-15 14:38	53.36	OK
7445	2026-09-15 14:39	53.68	OK	7446	2026-09-15 14:40	52.12	OK
7447	2026-09-15 14:41	52.73	OK	7448	2026-09-15 14:42	51.69	OK
7449	2026-09-15 14:43	54.39	OK	7450	2026-09-15 14:44	52.96	OK
7451	2026-09-15 14:45	52.26	OK	7452	2026-09-15 14:46	53.57	OK
7453	2026-09-15 14:47	53.25	OK	7454	2026-09-15 14:48	52.17	OK
7455	2026-09-15 14:49	53.07	OK	7456	2026-09-15 14:50	51.74	OK
7457	2026-09-15 14:51	51.71	OK	7458	2026-09-15 14:52	51.50	OK
7459	2026-09-15 14:53	51.21	OK	7460	2026-09-15 14:54	53.14	OK
7461	2026-09-15 14:55	51.26	OK	7462	2026-09-15 14:56	53.26	OK
7463	2026-09-15 14:57	51.68	OK	7464	2026-09-15 14:58	52.64	OK
7465	2026-09-15 14:59	53.44	OK	7466	2026-09-15 15:00	51.28	OK
7467	2026-09-15 15:01	50.48	OK	7468	2026-09-15 15:02	52.29	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7469	2026-09-15 15:03	52.19	OK	7470	2026-09-15 15:04	50.96	OK
7471	2026-09-15 15:05	51.36	OK	7472	2026-09-15 15:06	52.60	OK
7473	2026-09-15 15:07	50.69	OK	7474	2026-09-15 15:08	53.80	OK
7475	2026-09-15 15:09	54.07	OK	7476	2026-09-15 15:10	53.44	OK
7477	2026-09-15 15:11	54.57	OK	7478	2026-09-15 15:12	53.07	OK
7479	2026-09-15 15:13	52.20	OK	7480	2026-09-15 15:14	53.69	OK
7481	2026-09-15 15:15	51.85	OK	7482	2026-09-15 15:16	54.80	OK
7483	2026-09-15 15:17	51.30	OK	7484	2026-09-15 15:18	52.70	OK
7485	2026-09-15 15:19	52.69	OK	7486	2026-09-15 15:20	53.14	OK
7487	2026-09-15 15:21	50.98	OK	7488	2026-09-15 15:22	53.04	OK
7489	2026-09-15 15:23	51.30	OK	7490	2026-09-15 15:24	51.24	OK
7491	2026-09-15 15:25	53.57	OK	7492	2026-09-15 15:26	52.07	OK
7493	2026-09-15 15:27	52.64	OK	7494	2026-09-15 15:28	50.46	OK
7495	2026-09-15 15:29	51.61	OK	7496	2026-09-15 15:30	52.49	OK
7497	2026-09-15 15:31	50.60	OK	7498	2026-09-15 15:32	52.56	OK
7499	2026-09-15 15:33	52.39	OK	7500	2026-09-15 15:34	52.35	OK
7501	2026-09-15 15:35	49.48	OK	7502	2026-09-15 15:36	52.32	OK
7503	2026-09-15 15:37	51.45	OK	7504	2026-09-15 15:38	51.93	OK
7505	2026-09-15 15:39	52.13	OK	7506	2026-09-15 15:40	49.75	OK
7507	2026-09-15 15:41	52.09	OK	7508	2026-09-15 15:42	50.77	OK
7509	2026-09-15 15:43	51.94	OK	7510	2026-09-15 15:44	51.63	OK
7511	2026-09-15 15:45	51.04	OK	7512	2026-09-15 15:46	52.38	OK
7513	2026-09-15 15:47	51.53	OK	7514	2026-09-15 15:48	51.26	OK
7515	2026-09-15 15:49	53.04	OK	7516	2026-09-15 15:50	50.45	OK
7517	2026-09-15 15:51	50.70	OK	7518	2026-09-15 15:52	51.39	OK
7519	2026-09-15 15:53	52.16	OK	7520	2026-09-15 15:54	50.78	OK
7521	2026-09-15 15:55	51.20	OK	7522	2026-09-15 15:56	51.87	OK
7523	2026-09-15 15:57	52.47	OK	7524	2026-09-15 15:58	52.74	OK
7525	2026-09-15 15:59	51.21	OK	7526	2026-09-15 16:00	49.99	OK
7527	2026-09-15 16:01	52.55	OK	7528	2026-09-15 16:02	50.14	OK
7529	2026-09-15 16:03	51.01	OK	7530	2026-09-15 16:04	50.63	OK
7531	2026-09-15 16:05	51.14	OK	7532	2026-09-15 16:06	51.42	OK
7533	2026-09-15 16:07	51.01	OK	7534	2026-09-15 16:08	50.78	OK
7535	2026-09-15 16:09	52.85	OK	7536	2026-09-15 16:10	50.56	OK
7537	2026-09-15 16:11	51.63	OK	7538	2026-09-15 16:12	49.56	OK
7539	2026-09-15 16:13	49.63	OK	7540	2026-09-15 16:14	52.19	OK
7541	2026-09-15 16:15	52.96	OK	7542	2026-09-15 16:16	51.45	OK
7543	2026-09-15 16:17	50.82	OK	7544	2026-09-15 16:18	48.74	OK
7545	2026-09-15 16:19	50.60	OK	7546	2026-09-15 16:20	49.46	OK
7547	2026-09-15 16:21	53.43	OK	7548	2026-09-15 16:22	51.07	OK
7549	2026-09-15 16:23	48.22	OK	7550	2026-09-15 16:24	50.48	OK
7551	2026-09-15 16:25	47.82	OK	7552	2026-09-15 16:26	51.65	OK
7553	2026-09-15 16:27	52.00	OK	7554	2026-09-15 16:28	50.46	OK
7555	2026-09-15 16:29	50.82	OK	7556	2026-09-15 16:30	52.38	OK
7557	2026-09-15 16:31	50.10	OK	7558	2026-09-15 16:32	50.63	OK
7559	2026-09-15 16:33	52.15	OK	7560	2026-09-15 16:34	50.36	OK
7561	2026-09-15 16:35	53.10	OK	7562	2026-09-15 16:36	52.18	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7563	2026-09-15 16:37	51.76	OK	7564	2026-09-15 16:38	52.09	OK
7565	2026-09-15 16:39	50.29	OK	7566	2026-09-15 16:40	49.45	OK
7567	2026-09-15 16:41	49.64	OK	7568	2026-09-15 16:42	49.96	OK
7569	2026-09-15 16:43	51.52	OK	7570	2026-09-15 16:44	50.13	OK
7571	2026-09-15 16:45	50.38	OK	7572	2026-09-15 16:46	50.96	OK
7573	2026-09-15 16:47	49.01	OK	7574	2026-09-15 16:48	50.14	OK
7575	2026-09-15 16:49	51.39	OK	7576	2026-09-15 16:50	49.46	OK
7577	2026-09-15 16:51	50.88	OK	7578	2026-09-15 16:52	50.91	OK
7579	2026-09-15 16:53	49.39	OK	7580	2026-09-15 16:54	50.41	OK
7581	2026-09-15 16:55	51.52	OK	7582	2026-09-15 16:56	50.30	OK
7583	2026-09-15 16:57	51.73	OK	7584	2026-09-15 16:58	50.63	OK
7585	2026-09-15 16:59	49.23	OK	7586	2026-09-15 17:00	48.96	OK
7587	2026-09-15 17:01	52.61	OK	7588	2026-09-15 17:02	50.74	OK
7589	2026-09-15 17:03	51.80	OK	7590	2026-09-15 17:04	50.36	OK
7591	2026-09-15 17:05	50.70	OK	7592	2026-09-15 17:06	51.48	OK
7593	2026-09-15 17:07	50.77	OK	7594	2026-09-15 17:08	48.13	OK
7595	2026-09-15 17:09	48.54	OK	7596	2026-09-15 17:10	50.98	OK
7597	2026-09-15 17:11	49.87	OK	7598	2026-09-15 17:12	50.61	OK
7599	2026-09-15 17:13	52.14	OK	7600	2026-09-15 17:14	50.66	OK
7601	2026-09-15 17:15	49.88	OK	7602	2026-09-15 17:16	49.56	OK
7603	2026-09-15 17:17	47.67	OK	7604	2026-09-15 17:18	49.34	OK
7605	2026-09-15 17:19	48.80	OK	7606	2026-09-15 17:20	48.02	OK
7607	2026-09-15 17:21	48.36	OK	7608	2026-09-15 17:22	50.64	OK
7609	2026-09-15 17:23	49.09	OK	7610	2026-09-15 17:24	49.54	OK
7611	2026-09-15 17:25	50.95	OK	7612	2026-09-15 17:26	48.37	OK
7613	2026-09-15 17:27	46.54	OK	7614	2026-09-15 17:28	47.22	OK
7615	2026-09-15 17:29	48.74	OK	7616	2026-09-15 17:30	49.81	OK
7617	2026-09-15 17:31	48.65	OK	7618	2026-09-15 17:32	47.99	OK
7619	2026-09-15 17:33	50.19	OK	7620	2026-09-15 17:34	49.92	OK
7621	2026-09-15 17:35	48.29	OK	7622	2026-09-15 17:36	48.02	OK
7623	2026-09-15 17:37	50.22	OK	7624	2026-09-15 17:38	48.51	OK
7625	2026-09-15 17:39	50.80	OK	7626	2026-09-15 17:40	48.26	OK
7627	2026-09-15 17:41	50.19	OK	7628	2026-09-15 17:42	49.75	OK
7629	2026-09-15 17:43	49.12	OK	7630	2026-09-15 17:44	48.11	OK
7631	2026-09-15 17:45	48.44	OK	7632	2026-09-15 17:46	51.05	OK
7633	2026-09-15 17:47	48.10	OK	7634	2026-09-15 17:48	48.18	OK
7635	2026-09-15 17:49	50.49	OK	7636	2026-09-15 17:50	47.44	OK
7637	2026-09-15 17:51	47.37	OK	7638	2026-09-15 17:52	49.75	OK
7639	2026-09-15 17:53	49.16	OK	7640	2026-09-15 17:54	50.28	OK
7641	2026-09-15 17:55	48.77	OK	7642	2026-09-15 17:56	49.38	OK
7643	2026-09-15 17:57	48.61	OK	7644	2026-09-15 17:58	50.23	OK
7645	2026-09-15 17:59	46.23	OK	7646	2026-09-15 18:00	49.63	OK
7647	2026-09-15 18:01	47.46	OK	7648	2026-09-15 18:02	47.99	OK
7649	2026-09-15 18:03	48.42	OK	7650	2026-09-15 18:04	46.63	OK
7651	2026-09-15 18:05	48.13	OK	7652	2026-09-15 18:06	46.57	OK
7653	2026-09-15 18:07	48.67	OK	7654	2026-09-15 18:08	48.70	OK
7655	2026-09-15 18:09	47.09	OK	7656	2026-09-15 18:10	48.26	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7657	2026-09-15 18:11	48.90	OK	7658	2026-09-15 18:12	47.59	OK
7659	2026-09-15 18:13	48.94	OK	7660	2026-09-15 18:14	47.30	OK
7661	2026-09-15 18:15	48.28	OK	7662	2026-09-15 18:16	50.87	OK
7663	2026-09-15 18:17	49.86	OK	7664	2026-09-15 18:18	46.81	OK
7665	2026-09-15 18:19	50.47	OK	7666	2026-09-15 18:20	48.53	OK
7667	2026-09-15 18:21	48.81	OK	7668	2026-09-15 18:22	47.48	OK
7669	2026-09-15 18:23	49.12	OK	7670	2026-09-15 18:24	46.49	OK
7671	2026-09-15 18:25	47.29	OK	7672	2026-09-15 18:26	50.59	OK
7673	2026-09-15 18:27	47.05	OK	7674	2026-09-15 18:28	47.50	OK
7675	2026-09-15 18:29	49.17	OK	7676	2026-09-15 18:30	46.51	OK
7677	2026-09-15 18:31	50.09	OK	7678	2026-09-15 18:32	47.38	OK
7679	2026-09-15 18:33	50.33	OK	7680	2026-09-15 18:34	49.34	OK
7681	2026-09-15 18:35	46.91	OK	7682	2026-09-15 18:36	48.62	OK
7683	2026-09-15 18:37	47.92	OK	7684	2026-09-15 18:38	48.39	OK
7685	2026-09-15 18:39	46.99	OK	7686	2026-09-15 18:40	49.00	OK
7687	2026-09-15 18:41	48.81	OK	7688	2026-09-15 18:42	47.81	OK
7689	2026-09-15 18:43	47.87	OK	7690	2026-09-15 18:44	45.51	OK
7691	2026-09-15 18:45	48.72	OK	7692	2026-09-15 18:46	47.36	OK
7693	2026-09-15 18:47	47.57	OK	7694	2026-09-15 18:48	48.38	OK
7695	2026-09-15 18:49	47.27	OK	7696	2026-09-15 18:50	49.05	OK
7697	2026-09-15 18:51	49.41	OK	7698	2026-09-15 18:52	48.42	OK
7699	2026-09-15 18:53	47.13	OK	7700	2026-09-15 18:54	47.78	OK
7701	2026-09-15 18:55	46.48	OK	7702	2026-09-15 18:56	48.58	OK
7703	2026-09-15 18:57	46.41	OK	7704	2026-09-15 18:58	47.78	OK
7705	2026-09-15 18:59	48.24	OK	7706	2026-09-15 19:00	46.58	OK
7707	2026-09-15 19:01	45.87	OK	7708	2026-09-15 19:02	48.39	OK
7709	2026-09-15 19:03	47.73	OK	7710	2026-09-15 19:04	47.33	OK
7711	2026-09-15 19:05	47.29	OK	7712	2026-09-15 19:06	47.05	OK
7713	2026-09-15 19:07	48.93	OK	7714	2026-09-15 19:08	48.68	OK
7715	2026-09-15 19:09	47.22	OK	7716	2026-09-15 19:10	47.98	OK
7717	2026-09-15 19:11	45.62	OK	7718	2026-09-15 19:12	48.18	OK
7719	2026-09-15 19:13	47.39	OK	7720	2026-09-15 19:14	47.72	OK
7721	2026-09-15 19:15	47.43	OK	7722	2026-09-15 19:16	49.79	OK
7723	2026-09-15 19:17	46.34	OK	7724	2026-09-15 19:18	47.54	OK
7725	2026-09-15 19:19	49.41	OK	7726	2026-09-15 19:20	48.01	OK
7727	2026-09-15 19:21	47.99	OK	7728	2026-09-15 19:22	47.92	OK
7729	2026-09-15 19:23	47.37	OK	7730	2026-09-15 19:24	44.94	OK
7731	2026-09-15 19:25	48.36	OK	7732	2026-09-15 19:26	44.83	OK
7733	2026-09-15 19:27	49.03	OK	7734	2026-09-15 19:28	49.11	OK
7735	2026-09-15 19:29	47.26	OK	7736	2026-09-15 19:30	47.05	OK
7737	2026-09-15 19:31	48.02	OK	7738	2026-09-15 19:32	45.79	OK
7739	2026-09-15 19:33	44.63	OK	7740	2026-09-15 19:34	45.24	OK
7741	2026-09-15 19:35	47.63	OK	7742	2026-09-15 19:36	45.35	OK
7743	2026-09-15 19:37	44.60	OK	7744	2026-09-15 19:38	48.20	OK
7745	2026-09-15 19:39	46.70	OK	7746	2026-09-15 19:40	44.71	OK
7747	2026-09-15 19:41	49.46	OK	7748	2026-09-15 19:42	46.54	OK
7749	2026-09-15 19:43	46.90	OK	7750	2026-09-15 19:44	46.99	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7751	2026-09-15 19:45	46.67	OK	7752	2026-09-15 19:46	47.05	OK
7753	2026-09-15 19:47	46.69	OK	7754	2026-09-15 19:48	47.44	OK
7755	2026-09-15 19:49	46.36	OK	7756	2026-09-15 19:50	45.25	OK
7757	2026-09-15 19:51	45.04	OK	7758	2026-09-15 19:52	47.72	OK
7759	2026-09-15 19:53	45.28	OK	7760	2026-09-15 19:54	46.78	OK
7761	2026-09-15 19:55	48.45	OK	7762	2026-09-15 19:56	44.89	OK
7763	2026-09-15 19:57	46.61	OK	7764	2026-09-15 19:58	45.15	OK
7765	2026-09-15 19:59	46.31	OK	7766	2026-09-15 20:00	46.90	OK
7767	2026-09-15 20:01	46.22	OK	7768	2026-09-15 20:02	47.31	OK
7769	2026-09-15 20:03	46.29	OK	7770	2026-09-15 20:04	48.01	OK
7771	2026-09-15 20:05	49.28	OK	7772	2026-09-15 20:06	46.79	OK
7773	2026-09-15 20:07	46.72	OK	7774	2026-09-15 20:08	48.25	OK
7775	2026-09-15 20:09	45.57	OK	7776	2026-09-15 20:10	45.25	OK
7777	2026-09-15 20:11	46.09	OK	7778	2026-09-15 20:12	47.04	OK
7779	2026-09-15 20:13	45.79	OK	7780	2026-09-15 20:14	47.08	OK
7781	2026-09-15 20:15	44.97	OK	7782	2026-09-15 20:16	44.15	OK
7783	2026-09-15 20:17	45.36	OK	7784	2026-09-15 20:18	47.74	OK
7785	2026-09-15 20:19	47.76	OK	7786	2026-09-15 20:20	46.51	OK
7787	2026-09-15 20:21	46.50	OK	7788	2026-09-15 20:22	47.78	OK
7789	2026-09-15 20:23	45.86	OK	7790	2026-09-15 20:24	46.07	OK
7791	2026-09-15 20:25	46.93	OK	7792	2026-09-15 20:26	46.35	OK
7793	2026-09-15 20:27	47.35	OK	7794	2026-09-15 20:28	46.13	OK
7795	2026-09-15 20:29	47.14	OK	7796	2026-09-15 20:30	47.12	OK
7797	2026-09-15 20:31	44.53	OK	7798	2026-09-15 20:32	46.11	OK
7799	2026-09-15 20:33	46.72	OK	7800	2026-09-15 20:34	46.76	OK
7801	2026-09-15 20:35	47.01	OK	7802	2026-09-15 20:36	45.21	OK
7803	2026-09-15 20:37	45.28	OK	7804	2026-09-15 20:38	47.54	OK
7805	2026-09-15 20:39	45.53	OK	7806	2026-09-15 20:40	47.20	OK
7807	2026-09-15 20:41	46.36	OK	7808	2026-09-15 20:42	43.70	OK
7809	2026-09-15 20:43	45.02	OK	7810	2026-09-15 20:44	46.30	OK
7811	2026-09-15 20:45	45.65	OK	7812	2026-09-15 20:46	46.84	OK
7813	2026-09-15 20:47	46.21	OK	7814	2026-09-15 20:48	45.23	OK
7815	2026-09-15 20:49	44.37	OK	7816	2026-09-15 20:50	46.52	OK
7817	2026-09-15 20:51	45.55	OK	7818	2026-09-15 20:52	47.11	OK
7819	2026-09-15 20:53	47.14	OK	7820	2026-09-15 20:54	47.65	OK
7821	2026-09-15 20:55	43.14	OK	7822	2026-09-15 20:56	45.35	OK
7823	2026-09-15 20:57	47.06	OK	7824	2026-09-15 20:58	46.33	OK
7825	2026-09-15 20:59	45.73	OK	7826	2026-09-15 21:00	44.99	OK
7827	2026-09-15 21:01	43.71	OK	7828	2026-09-15 21:02	46.78	OK
7829	2026-09-15 21:03	47.19	OK	7830	2026-09-15 21:04	47.41	OK
7831	2026-09-15 21:05	45.37	OK	7832	2026-09-15 21:06	44.57	OK
7833	2026-09-15 21:07	46.01	OK	7834	2026-09-15 21:08	45.69	OK
7835	2026-09-15 21:09	44.23	OK	7836	2026-09-15 21:10	47.20	OK
7837	2026-09-15 21:11	45.73	OK	7838	2026-09-15 21:12	44.62	OK
7839	2026-09-15 21:13	46.18	OK	7840	2026-09-15 21:14	43.57	OK
7841	2026-09-15 21:15	46.12	OK	7842	2026-09-15 21:16	43.17	OK
7843	2026-09-15 21:17	45.26	OK	7844	2026-09-15 21:18	46.89	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7845	2026-09-15 21:19	45.50	OK	7846	2026-09-15 21:20	43.71	OK
7847	2026-09-15 21:21	46.41	OK	7848	2026-09-15 21:22	44.73	OK
7849	2026-09-15 21:23	45.08	OK	7850	2026-09-15 21:24	44.57	OK
7851	2026-09-15 21:25	45.28	OK	7852	2026-09-15 21:26	44.72	OK
7853	2026-09-15 21:27	43.78	OK	7854	2026-09-15 21:28	44.89	OK
7855	2026-09-15 21:29	46.59	OK	7856	2026-09-15 21:30	46.19	OK
7857	2026-09-15 21:31	46.13	OK	7858	2026-09-15 21:32	43.85	OK
7859	2026-09-15 21:33	43.40	OK	7860	2026-09-15 21:34	44.70	OK
7861	2026-09-15 21:35	44.52	OK	7862	2026-09-15 21:36	44.85	OK
7863	2026-09-15 21:37	43.66	OK	7864	2026-09-15 21:38	45.11	OK
7865	2026-09-15 21:39	45.39	OK	7866	2026-09-15 21:40	45.70	OK
7867	2026-09-15 21:41	45.50	OK	7868	2026-09-15 21:42	46.95	OK
7869	2026-09-15 21:43	47.28	OK	7870	2026-09-15 21:44	46.26	OK
7871	2026-09-15 21:45	46.16	OK	7872	2026-09-15 21:46	42.53	OK
7873	2026-09-15 21:47	46.54	OK	7874	2026-09-15 21:48	45.59	OK
7875	2026-09-15 21:49	44.45	OK	7876	2026-09-15 21:50	46.34	OK
7877	2026-09-15 21:51	43.98	OK	7878	2026-09-15 21:52	46.17	OK
7879	2026-09-15 21:53	45.98	OK	7880	2026-09-15 21:54	43.44	OK
7881	2026-09-15 21:55	43.15	OK	7882	2026-09-15 21:56	44.67	OK
7883	2026-09-15 21:57	45.54	OK	7884	2026-09-15 21:58	44.46	OK
7885	2026-09-15 21:59	45.71	OK	7886	2026-09-15 22:00	47.39	OK
7887	2026-09-15 22:01	45.46	OK	7888	2026-09-15 22:02	45.22	OK
7889	2026-09-15 22:03	45.63	OK	7890	2026-09-15 22:04	43.52	OK
7891	2026-09-15 22:05	45.42	OK	7892	2026-09-15 22:06	46.95	OK
7893	2026-09-15 22:07	45.69	OK	7894	2026-09-15 22:08	46.24	OK
7895	2026-09-15 22:09	44.85	OK	7896	2026-09-15 22:10	43.14	OK
7897	2026-09-15 22:11	46.84	OK	7898	2026-09-15 22:12	46.17	OK
7899	2026-09-15 22:13	44.98	OK	7900	2026-09-15 22:14	44.27	OK
7901	2026-09-15 22:15	46.07	OK	7902	2026-09-15 22:16	45.49	OK
7903	2026-09-15 22:17	45.78	OK	7904	2026-09-15 22:18	46.66	OK
7905	2026-09-15 22:19	46.75	OK	7906	2026-09-15 22:20	43.99	OK
7907	2026-09-15 22:21	43.78	OK	7908	2026-09-15 22:22	44.90	OK
7909	2026-09-15 22:23	44.23	OK	7910	2026-09-15 22:24	45.43	OK
7911	2026-09-15 22:25	46.88	OK	7912	2026-09-15 22:26	44.28	OK
7913	2026-09-15 22:27	45.29	OK	7914	2026-09-15 22:28	44.52	OK
7915	2026-09-15 22:29	43.63	OK	7916	2026-09-15 22:30	43.68	OK
7917	2026-09-15 22:31	45.12	OK	7918	2026-09-15 22:32	44.65	OK
7919	2026-09-15 22:33	44.60	OK	7920	2026-09-15 22:34	45.23	OK
7921	2026-09-15 22:35	45.39	OK	7922	2026-09-15 22:36	43.96	OK
7923	2026-09-15 22:37	42.45	OK	7924	2026-09-15 22:38	44.14	OK
7925	2026-09-15 22:39	46.26	OK	7926	2026-09-15 22:40	43.51	OK
7927	2026-09-15 22:41	46.30	OK	7928	2026-09-15 22:42	45.82	OK
7929	2026-09-15 22:43	43.86	OK	7930	2026-09-15 22:44	44.80	OK
7931	2026-09-15 22:45	44.98	OK	7932	2026-09-15 22:46	44.86	OK
7933	2026-09-15 22:47	46.72	OK	7934	2026-09-15 22:48	43.20	OK
7935	2026-09-15 22:49	45.07	OK	7936	2026-09-15 22:50	44.60	OK
7937	2026-09-15 22:51	45.16	OK	7938	2026-09-15 22:52	42.56	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7939	2026-09-15 22:53	46.94	OK	7940	2026-09-15 22:54	45.19	OK
7941	2026-09-15 22:55	45.72	OK	7942	2026-09-15 22:56	45.48	OK
7943	2026-09-15 22:57	45.32	OK	7944	2026-09-15 22:58	44.34	OK
7945	2026-09-15 22:59	45.53	OK	7946	2026-09-15 23:00	47.70	OK
7947	2026-09-15 23:01	45.76	OK	7948	2026-09-15 23:02	44.41	OK
7949	2026-09-15 23:03	44.69	OK	7950	2026-09-15 23:04	44.21	OK
7951	2026-09-15 23:05	44.91	OK	7952	2026-09-15 23:06	43.01	OK
7953	2026-09-15 23:07	44.14	OK	7954	2026-09-15 23:08	45.00	OK
7955	2026-09-15 23:09	43.15	OK	7956	2026-09-15 23:10	46.52	OK
7957	2026-09-15 23:11	43.97	OK	7958	2026-09-15 23:12	43.25	OK
7959	2026-09-15 23:13	45.63	OK	7960	2026-09-15 23:14	43.99	OK
7961	2026-09-15 23:15	44.46	OK	7962	2026-09-15 23:16	45.32	OK
7963	2026-09-15 23:17	43.94	OK	7964	2026-09-15 23:18	45.61	OK
7965	2026-09-15 23:19	45.85	OK	7966	2026-09-15 23:20	46.32	OK
7967	2026-09-15 23:21	44.67	OK	7968	2026-09-15 23:22	44.67	OK
7969	2026-09-15 23:23	44.85	OK	7970	2026-09-15 23:24	44.95	OK
7971	2026-09-15 23:25	45.10	OK	7972	2026-09-15 23:26	43.67	OK
7973	2026-09-15 23:27	43.89	OK	7974	2026-09-15 23:28	44.09	OK
7975	2026-09-15 23:29	44.84	OK	7976	2026-09-15 23:30	45.13	OK
7977	2026-09-15 23:31	46.02	OK	7978	2026-09-15 23:32	43.93	OK
7979	2026-09-15 23:33	44.20	OK	7980	2026-09-15 23:34	45.52	OK
7981	2026-09-15 23:35	45.93	OK	7982	2026-09-15 23:36	44.63	OK
7983	2026-09-15 23:37	41.86	OK	7984	2026-09-15 23:38	42.50	OK
7985	2026-09-15 23:39	46.98	OK	7986	2026-09-15 23:40	44.46	OK
7987	2026-09-15 23:41	44.12	OK	7988	2026-09-15 23:42	44.22	OK
7989	2026-09-15 23:43	46.07	OK	7990	2026-09-15 23:44	46.71	OK
7991	2026-09-15 23:45	43.71	OK	7992	2026-09-15 23:46	43.64	OK
7993	2026-09-15 23:47	45.60	OK	7994	2026-09-15 23:48	46.79	OK
7995	2026-09-15 23:49	45.63	OK	7996	2026-09-15 23:50	44.85	OK
7997	2026-09-15 23:51	43.17	OK	7998	2026-09-15 23:52	43.61	OK
7999	2026-09-15 23:53	43.02	OK	8000	2026-09-15 23:54	44.08	OK
8001	2026-09-15 23:55	45.20	OK	8002	2026-09-15 23:56	43.92	OK
8003	2026-09-15 23:57	44.60	OK	8004	2026-09-15 23:58	44.26	OK
8005	2026-09-15 23:59	45.60	OK	8006	2026-09-16 00:00	46.26	OK
8007	2026-09-16 00:01	46.09	OK	8008	2026-09-16 00:02	44.87	OK
8009	2026-09-16 00:03	42.64	OK	8010	2026-09-16 00:04	44.74	OK
8011	2026-09-16 00:05	44.18	OK	8012	2026-09-16 00:06	44.44	OK
8013	2026-09-16 00:07	45.55	OK	8014	2026-09-16 00:08	42.73	OK
8015	2026-09-16 00:09	45.81	OK	8016	2026-09-16 00:10	43.64	OK
8017	2026-09-16 00:11	44.95	OK	8018	2026-09-16 00:12	44.85	OK
8019	2026-09-16 00:13	42.34	OK	8020	2026-09-16 00:14	45.23	OK
8021	2026-09-16 00:15	45.83	OK	8022	2026-09-16 00:16	44.00	OK
8023	2026-09-16 00:17	43.36	OK	8024	2026-09-16 00:18	46.23	OK
8025	2026-09-16 00:19	45.10	OK	8026	2026-09-16 00:20	43.87	OK
8027	2026-09-16 00:21	45.35	OK	8028	2026-09-16 00:22	45.42	OK
8029	2026-09-16 00:23	43.35	OK	8030	2026-09-16 00:24	43.86	OK
8031	2026-09-16 00:25	44.98	OK	8032	2026-09-16 00:26	44.71	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8033	2026-09-16 00:27	44.10	OK	8034	2026-09-16 00:28	46.94	OK
8035	2026-09-16 00:29	45.92	OK	8036	2026-09-16 00:30	46.12	OK
8037	2026-09-16 00:31	45.16	OK	8038	2026-09-16 00:32	45.51	OK
8039	2026-09-16 00:33	44.76	OK	8040	2026-09-16 00:34	44.40	OK
8041	2026-09-16 00:35	43.41	OK	8042	2026-09-16 00:36	45.45	OK
8043	2026-09-16 00:37	45.21	OK	8044	2026-09-16 00:38	43.82	OK
8045	2026-09-16 00:39	44.76	OK	8046	2026-09-16 00:40	44.99	OK
8047	2026-09-16 00:41	44.97	OK	8048	2026-09-16 00:42	46.50	OK
8049	2026-09-16 00:43	43.01	OK	8050	2026-09-16 00:44	46.10	OK
8051	2026-09-16 00:45	45.74	OK	8052	2026-09-16 00:46	45.57	OK
8053	2026-09-16 00:47	46.06	OK	8054	2026-09-16 00:48	47.08	OK
8055	2026-09-16 00:49	42.85	OK	8056	2026-09-16 00:50	46.09	OK
8057	2026-09-16 00:51	46.56	OK	8058	2026-09-16 00:52	45.20	OK
8059	2026-09-16 00:53	44.41	OK	8060	2026-09-16 00:54	44.41	OK
8061	2026-09-16 00:55	46.19	OK	8062	2026-09-16 00:56	45.55	OK
8063	2026-09-16 00:57	44.77	OK	8064	2026-09-16 00:58	44.95	OK
8065	2026-09-16 00:59	45.51	OK	8066	2026-09-16 01:00	43.28	OK
8067	2026-09-16 01:01	45.60	OK	8068	2026-09-16 01:02	43.84	OK
8069	2026-09-16 01:03	46.21	OK	8070	2026-09-16 01:04	46.60	OK
8071	2026-09-16 01:05	45.91	OK	8072	2026-09-16 01:06	44.50	OK
8073	2026-09-16 01:07	45.98	OK	8074	2026-09-16 01:08	43.21	OK
8075	2026-09-16 01:09	43.45	OK	8076	2026-09-16 01:10	47.03	OK
8077	2026-09-16 01:11	43.70	OK	8078	2026-09-16 01:12	45.59	OK
8079	2026-09-16 01:13	47.92	OK	8080	2026-09-16 01:14	44.91	OK
8081	2026-09-16 01:15	45.38	OK	8082	2026-09-16 01:16	46.07	OK
8083	2026-09-16 01:17	44.88	OK	8084	2026-09-16 01:18	43.71	OK
8085	2026-09-16 01:19	44.63	OK	8086	2026-09-16 01:20	44.31	OK
8087	2026-09-16 01:21	44.75	OK	8088	2026-09-16 01:22	44.45	OK
8089	2026-09-16 01:23	46.36	OK	8090	2026-09-16 01:24	44.97	OK
8091	2026-09-16 01:25	43.06	OK	8092	2026-09-16 01:26	45.09	OK
8093	2026-09-16 01:27	45.67	OK	8094	2026-09-16 01:28	45.23	OK
8095	2026-09-16 01:29	45.47	OK	8096	2026-09-16 01:30	45.78	OK
8097	2026-09-16 01:31	42.84	OK	8098	2026-09-16 01:32	44.56	OK
8099	2026-09-16 01:33	45.62	OK	8100	2026-09-16 01:34	45.57	OK
8101	2026-09-16 01:35	44.39	OK	8102	2026-09-16 01:36	46.24	OK
8103	2026-09-16 01:37	46.64	OK	8104	2026-09-16 01:38	45.31	OK
8105	2026-09-16 01:39	44.31	OK	8106	2026-09-16 01:40	44.91	OK
8107	2026-09-16 01:41	44.66	OK	8108	2026-09-16 01:42	46.54	OK
8109	2026-09-16 01:43	44.52	OK	8110	2026-09-16 01:44	46.58	OK
8111	2026-09-16 01:45	46.63	OK	8112	2026-09-16 01:46	42.95	OK
8113	2026-09-16 01:47	47.51	OK	8114	2026-09-16 01:48	44.92	OK
8115	2026-09-16 01:49	44.66	OK	8116	2026-09-16 01:50	45.24	OK
8117	2026-09-16 01:51	45.57	OK	8118	2026-09-16 01:52	46.62	OK
8119	2026-09-16 01:53	46.01	OK	8120	2026-09-16 01:54	45.62	OK
8121	2026-09-16 01:55	45.69	OK	8122	2026-09-16 01:56	46.18	OK
8123	2026-09-16 01:57	45.74	OK	8124	2026-09-16 01:58	46.02	OK
8125	2026-09-16 01:59	46.35	OK	8126	2026-09-16 02:00	47.14	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8127	2026-09-16 02:01	46.01	OK	8128	2026-09-16 02:02	46.58	OK
8129	2026-09-16 02:03	46.80	OK	8130	2026-09-16 02:04	44.45	OK
8131	2026-09-16 02:05	45.28	OK	8132	2026-09-16 02:06	46.12	OK
8133	2026-09-16 02:07	46.65	OK	8134	2026-09-16 02:08	45.10	OK
8135	2026-09-16 02:09	47.90	OK	8136	2026-09-16 02:10	44.69	OK
8137	2026-09-16 02:11	45.45	OK	8138	2026-09-16 02:12	45.25	OK
8139	2026-09-16 02:13	45.08	OK	8140	2026-09-16 02:14	45.24	OK
8141	2026-09-16 02:15	45.44	OK	8142	2026-09-16 02:16	46.87	OK
8143	2026-09-16 02:17	46.87	OK	8144	2026-09-16 02:18	46.51	OK
8145	2026-09-16 02:19	44.48	OK	8146	2026-09-16 02:20	48.20	OK
8147	2026-09-16 02:21	46.16	OK	8148	2026-09-16 02:22	45.64	OK
8149	2026-09-16 02:23	46.72	OK	8150	2026-09-16 02:24	46.02	OK
8151	2026-09-16 02:25	45.06	OK	8152	2026-09-16 02:26	48.24	OK
8153	2026-09-16 02:27	45.73	OK	8154	2026-09-16 02:28	46.02	OK
8155	2026-09-16 02:29	46.45	OK	8156	2026-09-16 02:30	45.43	OK
8157	2026-09-16 02:31	45.64	OK	8158	2026-09-16 02:32	46.84	OK
8159	2026-09-16 02:33	46.28	OK	8160	2026-09-16 02:34	47.06	OK
8161	2026-09-16 02:35	45.27	OK	8162	2026-09-16 02:36	46.66	OK
8163	2026-09-16 02:37	47.36	OK	8164	2026-09-16 02:38	48.21	OK
8165	2026-09-16 02:39	47.91	OK	8166	2026-09-16 02:40	47.65	OK
8167	2026-09-16 02:41	45.99	OK	8168	2026-09-16 02:42	46.63	OK
8169	2026-09-16 02:43	47.72	OK	8170	2026-09-16 02:44	45.95	OK
8171	2026-09-16 02:45	47.62	OK	8172	2026-09-16 02:46	47.70	OK
8173	2026-09-16 02:47	47.49	OK	8174	2026-09-16 02:48	44.06	OK
8175	2026-09-16 02:49	47.20	OK	8176	2026-09-16 02:50	46.41	OK
8177	2026-09-16 02:51	46.39	OK	8178	2026-09-16 02:52	45.76	OK
8179	2026-09-16 02:53	43.79	OK	8180	2026-09-16 02:54	45.69	OK
8181	2026-09-16 02:55	45.56	OK	8182	2026-09-16 02:56	47.57	OK
8183	2026-09-16 02:57	46.94	OK	8184	2026-09-16 02:58	46.06	OK
8185	2026-09-16 02:59	46.51	OK	8186	2026-09-16 03:00	46.35	OK
8187	2026-09-16 03:01	47.72	OK	8188	2026-09-16 03:02	45.41	OK
8189	2026-09-16 03:03	45.74	OK	8190	2026-09-16 03:04	46.53	OK
8191	2026-09-16 03:05	46.54	OK	8192	2026-09-16 03:06	45.39	OK
8193	2026-09-16 03:07	46.81	OK	8194	2026-09-16 03:08	46.81	OK
8195	2026-09-16 03:09	45.60	OK	8196	2026-09-16 03:10	45.22	OK
8197	2026-09-16 03:11	46.68	OK	8198	2026-09-16 03:12	47.61	OK
8199	2026-09-16 03:13	48.68	OK	8200	2026-09-16 03:14	46.24	OK
8201	2026-09-16 03:15	47.43	OK	8202	2026-09-16 03:16	48.89	OK
8203	2026-09-16 03:17	46.65	OK	8204	2026-09-16 03:18	48.11	OK
8205	2026-09-16 03:19	46.24	OK	8206	2026-09-16 03:20	45.66	OK
8207	2026-09-16 03:21	46.53	OK	8208	2026-09-16 03:22	47.92	OK
8209	2026-09-16 03:23	46.07	OK	8210	2026-09-16 03:24	48.74	OK
8211	2026-09-16 03:25	47.19	OK	8212	2026-09-16 03:26	46.99	OK
8213	2026-09-16 03:27	46.15	OK	8214	2026-09-16 03:28	47.63	OK
8215	2026-09-16 03:29	48.05	OK	8216	2026-09-16 03:30	45.87	OK
8217	2026-09-16 03:31	45.49	OK	8218	2026-09-16 03:32	45.94	OK
8219	2026-09-16 03:33	45.25	OK	8220	2026-09-16 03:34	46.60	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8221	2026-09-16 03:35	45.78	OK	8222	2026-09-16 03:36	46.35	OK
8223	2026-09-16 03:37	46.68	OK	8224	2026-09-16 03:38	46.94	OK
8225	2026-09-16 03:39	45.62	OK	8226	2026-09-16 03:40	48.28	OK
8227	2026-09-16 03:41	45.93	OK	8228	2026-09-16 03:42	46.50	OK
8229	2026-09-16 03:43	49.24	OK	8230	2026-09-16 03:44	47.20	OK
8231	2026-09-16 03:45	46.64	OK	8232	2026-09-16 03:46	46.13	OK
8233	2026-09-16 03:47	47.76	OK	8234	2026-09-16 03:48	48.36	OK
8235	2026-09-16 03:49	46.32	OK	8236	2026-09-16 03:50	45.40	OK
8237	2026-09-16 03:51	47.97	OK	8238	2026-09-16 03:52	46.95	OK
8239	2026-09-16 03:53	47.96	OK	8240	2026-09-16 03:54	46.71	OK
8241	2026-09-16 03:55	45.63	OK	8242	2026-09-16 03:56	47.62	OK
8243	2026-09-16 03:57	46.06	OK	8244	2026-09-16 03:58	47.78	OK
8245	2026-09-16 03:59	47.90	OK	8246	2026-09-16 04:00	47.76	OK
8247	2026-09-16 04:01	45.92	OK	8248	2026-09-16 04:02	48.21	OK
8249	2026-09-16 04:03	48.94	OK	8250	2026-09-16 04:04	49.72	OK
8251	2026-09-16 04:05	47.50	OK	8252	2026-09-16 04:06	46.93	OK
8253	2026-09-16 04:07	47.23	OK	8254	2026-09-16 04:08	46.47	OK
8255	2026-09-16 04:09	46.49	OK	8256	2026-09-16 04:10	47.64	OK
8257	2026-09-16 04:11	47.31	OK	8258	2026-09-16 04:12	48.88	OK
8259	2026-09-16 04:13	47.04	OK	8260	2026-09-16 04:14	48.40	OK
8261	2026-09-16 04:15	49.36	OK	8262	2026-09-16 04:16	47.88	OK
8263	2026-09-16 04:17	47.02	OK	8264	2026-09-16 04:18	49.75	OK
8265	2026-09-16 04:19	48.26	OK	8266	2026-09-16 04:20	47.02	OK
8267	2026-09-16 04:21	47.33	OK	8268	2026-09-16 04:22	48.43	OK
8269	2026-09-16 04:23	45.78	OK	8270	2026-09-16 04:24	47.53	OK
8271	2026-09-16 04:25	47.93	OK	8272	2026-09-16 04:26	48.24	OK
8273	2026-09-16 04:27	48.68	OK	8274	2026-09-16 04:28	45.88	OK
8275	2026-09-16 04:29	48.32	OK	8276	2026-09-16 04:30	48.20	OK
8277	2026-09-16 04:31	49.00	OK	8278	2026-09-16 04:32	49.85	OK
8279	2026-09-16 04:33	46.18	OK	8280	2026-09-16 04:34	47.76	OK
8281	2026-09-16 04:35	46.42	OK	8282	2026-09-16 04:36	47.29	OK
8283	2026-09-16 04:37	46.45	OK	8284	2026-09-16 04:38	47.87	OK
8285	2026-09-16 04:39	48.03	OK	8286	2026-09-16 04:40	49.37	OK
8287	2026-09-16 04:41	47.31	OK	8288	2026-09-16 04:42	48.26	OK
8289	2026-09-16 04:43	46.10	OK	8290	2026-09-16 04:44	47.34	OK
8291	2026-09-16 04:45	46.93	OK	8292	2026-09-16 04:46	49.97	OK
8293	2026-09-16 04:47	49.17	OK	8294	2026-09-16 04:48	49.37	OK
8295	2026-09-16 04:49	47.13	OK	8296	2026-09-16 04:50	48.88	OK
8297	2026-09-16 04:51	51.46	OK	8298	2026-09-16 04:52	47.86	OK
8299	2026-09-16 04:53	48.99	OK	8300	2026-09-16 04:54	47.65	OK
8301	2026-09-16 04:55	47.77	OK	8302	2026-09-16 04:56	47.13	OK
8303	2026-09-16 04:57	47.34	OK	8304	2026-09-16 04:58	50.83	OK
8305	2026-09-16 04:59	49.24	OK	8306	2026-09-16 05:00	47.57	OK
8307	2026-09-16 05:01	50.34	OK	8308	2026-09-16 05:02	47.79	OK
8309	2026-09-16 05:03	48.62	OK	8310	2026-09-16 05:04	48.54	OK
8311	2026-09-16 05:05	47.03	OK	8312	2026-09-16 05:06	49.26	OK
8313	2026-09-16 05:07	48.98	OK	8314	2026-09-16 05:08	49.34	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8315	2026-09-16 05:09	47.56	OK	8316	2026-09-16 05:10	48.67	OK
8317	2026-09-16 05:11	48.26	OK	8318	2026-09-16 05:12	49.55	OK
8319	2026-09-16 05:13	48.60	OK	8320	2026-09-16 05:14	49.69	OK
8321	2026-09-16 05:15	48.80	OK	8322	2026-09-16 05:16	49.07	OK
8323	2026-09-16 05:17	50.58	OK	8324	2026-09-16 05:18	49.95	OK
8325	2026-09-16 05:19	49.63	OK	8326	2026-09-16 05:20	49.67	OK
8327	2026-09-16 05:21	50.26	OK	8328	2026-09-16 05:22	49.73	OK
8329	2026-09-16 05:23	48.16	OK	8330	2026-09-16 05:24	49.66	OK
8331	2026-09-16 05:25	46.53	OK	8332	2026-09-16 05:26	49.97	OK
8333	2026-09-16 05:27	47.83	OK	8334	2026-09-16 05:28	48.99	OK
8335	2026-09-16 05:29	49.26	OK	8336	2026-09-16 05:30	49.89	OK
8337	2026-09-16 05:31	49.43	OK	8338	2026-09-16 05:32	49.82	OK
8339	2026-09-16 05:33	49.56	OK	8340	2026-09-16 05:34	47.60	OK
8341	2026-09-16 05:35	49.36	OK	8342	2026-09-16 05:36	49.97	OK
8343	2026-09-16 05:37	51.41	OK	8344	2026-09-16 05:38	48.71	OK
8345	2026-09-16 05:39	49.23	OK	8346	2026-09-16 05:40	48.39	OK
8347	2026-09-16 05:41	50.71	OK	8348	2026-09-16 05:42	50.27	OK
8349	2026-09-16 05:43	50.26	OK	8350	2026-09-16 05:44	50.35	OK
8351	2026-09-16 05:45	48.98	OK	8352	2026-09-16 05:46	50.39	OK
8353	2026-09-16 05:47	49.79	OK	8354	2026-09-16 05:48	50.00	OK
8355	2026-09-16 05:49	50.88	OK	8356	2026-09-16 05:50	50.15	OK
8357	2026-09-16 05:51	51.33	OK	8358	2026-09-16 05:52	50.62	OK
8359	2026-09-16 05:53	50.32	OK	8360	2026-09-16 05:54	49.30	OK
8361	2026-09-16 05:55	50.21	OK	8362	2026-09-16 05:56	51.24	OK
8363	2026-09-16 05:57	51.51	OK	8364	2026-09-16 05:58	51.64	OK
8365	2026-09-16 05:59	51.08	OK	8366	2026-09-16 06:00	50.94	OK
8367	2026-09-16 06:01	49.53	OK	8368	2026-09-16 06:02	50.70	OK
8369	2026-09-16 06:03	52.14	OK	8370	2026-09-16 06:04	51.47	OK
8371	2026-09-16 06:05	51.17	OK	8372	2026-09-16 06:06	47.31	OK
8373	2026-09-16 06:07	48.98	OK	8374	2026-09-16 06:08	51.12	OK
8375	2026-09-16 06:09	50.38	OK	8376	2026-09-16 06:10	50.25	OK
8377	2026-09-16 06:11	50.49	OK	8378	2026-09-16 06:12	51.00	OK
8379	2026-09-16 06:13	50.65	OK	8380	2026-09-16 06:14	51.40	OK
8381	2026-09-16 06:15	49.55	OK	8382	2026-09-16 06:16	51.86	OK
8383	2026-09-16 06:17	49.70	OK	8384	2026-09-16 06:18	51.68	OK
8385	2026-09-16 06:19	49.45	OK	8386	2026-09-16 06:20	52.73	OK
8387	2026-09-16 06:21	50.33	OK	8388	2026-09-16 06:22	48.00	OK
8389	2026-09-16 06:23	50.38	OK	8390	2026-09-16 06:24	50.32	OK
8391	2026-09-16 06:25	50.61	OK	8392	2026-09-16 06:26	50.47	OK
8393	2026-09-16 06:27	48.89	OK	8394	2026-09-16 06:28	51.78	OK
8395	2026-09-16 06:29	50.44	OK	8396	2026-09-16 06:30	50.85	OK
8397	2026-09-16 06:31	51.23	OK	8398	2026-09-16 06:32	48.31	OK
8399	2026-09-16 06:33	52.18	OK	8400	2026-09-16 06:34	51.47	OK
8401	2026-09-16 06:35	51.45	OK	8402	2026-09-16 06:36	49.67	OK
8403	2026-09-16 06:37	50.15	OK	8404	2026-09-16 06:38	50.72	OK
8405	2026-09-16 06:39	49.95	OK	8406	2026-09-16 06:40	51.85	OK
8407	2026-09-16 06:41	52.63	OK	8408	2026-09-16 06:42	50.68	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8409	2026-09-16 06:43	50.77	OK	8410	2026-09-16 06:44	53.18	OK
8411	2026-09-16 06:45	52.54	OK	8412	2026-09-16 06:46	50.58	OK
8413	2026-09-16 06:47	50.08	OK	8414	2026-09-16 06:48	50.04	OK
8415	2026-09-16 06:49	51.25	OK	8416	2026-09-16 06:50	49.67	OK
8417	2026-09-16 06:51	50.91	OK	8418	2026-09-16 06:52	50.46	OK
8419	2026-09-16 06:53	52.09	OK	8420	2026-09-16 06:54	49.84	OK
8421	2026-09-16 06:55	50.74	OK	8422	2026-09-16 06:56	51.10	OK
8423	2026-09-16 06:57	51.79	OK	8424	2026-09-16 06:58	52.80	OK
8425	2026-09-16 06:59	51.24	OK	8426	2026-09-16 07:00	48.84	OK
8427	2026-09-16 07:01	50.64	OK	8428	2026-09-16 07:02	52.15	OK
8429	2026-09-16 07:03	51.74	OK	8430	2026-09-16 07:04	52.02	OK
8431	2026-09-16 07:05	50.76	OK	8432	2026-09-16 07:06	51.04	OK
8433	2026-09-16 07:07	50.37	OK	8434	2026-09-16 07:08	51.52	OK
8435	2026-09-16 07:09	50.80	OK	8436	2026-09-16 07:10	52.11	OK
8437	2026-09-16 07:11	52.63	OK	8438	2026-09-16 07:12	53.13	OK
8439	2026-09-16 07:13	50.87	OK	8440	2026-09-16 07:14	52.09	OK
8441	2026-09-16 07:15	49.54	OK	8442	2026-09-16 07:16	51.76	OK
8443	2026-09-16 07:17	49.09	OK	8444	2026-09-16 07:18	49.95	OK
8445	2026-09-16 07:19	50.16	OK	8446	2026-09-16 07:20	49.61	OK
8447	2026-09-16 07:21	51.36	OK	8448	2026-09-16 07:22	52.49	OK
8449	2026-09-16 07:23	52.50	OK	8450	2026-09-16 07:24	52.64	OK
8451	2026-09-16 07:25	52.47	OK	8452	2026-09-16 07:26	53.51	OK
8453	2026-09-16 07:27	51.26	OK	8454	2026-09-16 07:28	52.36	OK
8455	2026-09-16 07:29	52.58	OK	8456	2026-09-16 07:30	51.57	OK
8457	2026-09-16 07:31	51.88	OK	8458	2026-09-16 07:32	51.57	OK
8459	2026-09-16 07:33	52.32	OK	8460	2026-09-16 07:34	52.39	OK
8461	2026-09-16 07:35	50.64	OK	8462	2026-09-16 07:36	52.95	OK
8463	2026-09-16 07:37	53.57	OK	8464	2026-09-16 07:38	50.87	OK
8465	2026-09-16 07:39	50.06	OK	8466	2026-09-16 07:40	53.35	OK
8467	2026-09-16 07:41	53.56	OK	8468	2026-09-16 07:42	52.91	OK
8469	2026-09-16 07:43	52.27	OK	8470	2026-09-16 07:44	51.02	OK
8471	2026-09-16 07:45	53.43	OK	8472	2026-09-16 07:46	54.41	OK
8473	2026-09-16 07:47	52.58	OK	8474	2026-09-16 07:48	50.61	OK
8475	2026-09-16 07:49	52.52	OK	8476	2026-09-16 07:50	50.87	OK
8477	2026-09-16 07:51	52.06	OK	8478	2026-09-16 07:52	53.69	OK
8479	2026-09-16 07:53	52.98	OK	8480	2026-09-16 07:54	53.19	OK
8481	2026-09-16 07:55	51.36	OK	8482	2026-09-16 07:56	51.05	OK
8483	2026-09-16 07:57	52.39	OK	8484	2026-09-16 07:58	52.66	OK
8485	2026-09-16 07:59	53.58	OK	8486	2026-09-16 08:00	52.96	OK
8487	2026-09-16 08:01	54.73	OK	8488	2026-09-16 08:02	53.36	OK
8489	2026-09-16 08:03	52.06	OK	8490	2026-09-16 08:04	51.81	OK
8491	2026-09-16 08:05	51.68	OK	8492	2026-09-16 08:06	51.89	OK
8493	2026-09-16 08:07	52.17	OK	8494	2026-09-16 08:08	49.99	OK
8495	2026-09-16 08:09	52.36	OK	8496	2026-09-16 08:10	51.95	OK
8497	2026-09-16 08:11	51.77	OK	8498	2026-09-16 08:12	51.87	OK
8499	2026-09-16 08:13	53.22	OK	8500	2026-09-16 08:14	54.17	OK
8501	2026-09-16 08:15	52.45	OK	8502	2026-09-16 08:16	52.60	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8503	2026-09-16 08:17	51.45	OK	8504	2026-09-16 08:18	53.26	OK
8505	2026-09-16 08:19	52.03	OK	8506	2026-09-16 08:20	52.71	OK
8507	2026-09-16 08:21	52.00	OK	8508	2026-09-16 08:22	51.05	OK
8509	2026-09-16 08:23	51.87	OK	8510	2026-09-16 08:24	52.25	OK
8511	2026-09-16 08:25	53.09	OK	8512	2026-09-16 08:26	52.13	OK
8513	2026-09-16 08:27	52.64	OK	8514	2026-09-16 08:28	53.28	OK
8515	2026-09-16 08:29	52.37	OK	8516	2026-09-16 08:30	50.36	OK
8517	2026-09-16 08:31	53.12	OK	8518	2026-09-16 08:32	52.50	OK
8519	2026-09-16 08:33	50.99	OK	8520	2026-09-16 08:34	53.01	OK
8521	2026-09-16 08:35	54.87	OK	8522	2026-09-16 08:36	50.64	OK
8523	2026-09-16 08:37	54.58	OK	8524	2026-09-16 08:38	51.13	OK
8525	2026-09-16 08:39	51.01	OK	8526	2026-09-16 08:40	52.54	OK
8527	2026-09-16 08:41	52.66	OK	8528	2026-09-16 08:42	54.13	OK
8529	2026-09-16 08:43	51.61	OK	8530	2026-09-16 08:44	51.75	OK
8531	2026-09-16 08:45	53.33	OK	8532	2026-09-16 08:46	53.41	OK
8533	2026-09-16 08:47	51.93	OK	8534	2026-09-16 08:48	54.02	OK
8535	2026-09-16 08:49	51.83	OK	8536	2026-09-16 08:50	54.00	OK
8537	2026-09-16 08:51	53.63	OK	8538	2026-09-16 08:52	54.43	OK
8539	2026-09-16 08:53	52.73	OK	8540	2026-09-16 08:54	53.63	OK
8541	2026-09-16 08:55	54.14	OK	8542	2026-09-16 08:56	51.47	OK
8543	2026-09-16 08:57	52.13	OK	8544	2026-09-16 08:58	53.29	OK
8545	2026-09-16 08:59	52.25	OK	8546	2026-09-16 09:00	53.35	OK
8547	2026-09-16 09:01	53.78	OK	8548	2026-09-16 09:02	52.95	OK
8549	2026-09-16 09:03	54.69	OK	8550	2026-09-16 09:04	52.79	OK
8551	2026-09-16 09:05	54.07	OK	8552	2026-09-16 09:06	53.71	OK
8553	2026-09-16 09:07	53.26	OK	8554	2026-09-16 09:08	54.89	OK
8555	2026-09-16 09:09	51.89	OK	8556	2026-09-16 09:10	55.33	OK
8557	2026-09-16 09:11	52.96	OK	8558	2026-09-16 09:12	55.85	OK
8559	2026-09-16 09:13	51.90	OK	8560	2026-09-16 09:14	52.54	OK
8561	2026-09-16 09:15	51.91	OK	8562	2026-09-16 09:16	54.26	OK
8563	2026-09-16 09:17	54.04	OK	8564	2026-09-16 09:18	52.08	OK
8565	2026-09-16 09:19	52.65	OK	8566	2026-09-16 09:20	51.15	OK
8567	2026-09-16 09:21	52.33	OK	8568	2026-09-16 09:22	54.17	OK
8569	2026-09-16 09:23	53.38	OK	8570	2026-09-16 09:24	54.12	OK
8571	2026-09-16 09:25	54.82	OK	8572	2026-09-16 09:26	54.00	OK
8573	2026-09-16 09:27	55.39	OK	8574	2026-09-16 09:28	55.15	OK
8575	2026-09-16 09:29	53.53	OK	8576	2026-09-16 09:30	52.84	OK
8577	2026-09-16 09:31	53.69	OK	8578	2026-09-16 09:32	53.27	OK
8579	2026-09-16 09:33	55.25	OK	8580	2026-09-16 09:34	56.01	OK
8581	2026-09-16 09:35	52.80	OK	8582	2026-09-16 09:36	51.63	OK
8583	2026-09-16 09:37	55.89	OK	8584	2026-09-16 09:38	52.78	OK
8585	2026-09-16 09:39	53.03	OK	8586	2026-09-16 09:40	53.64	OK
8587	2026-09-16 09:41	53.19	OK	8588	2026-09-16 09:42	56.32	OK
8589	2026-09-16 09:43	53.70	OK	8590	2026-09-16 09:44	53.90	OK
8591	2026-09-16 09:45	53.96	OK	8592	2026-09-16 09:46	56.25	OK
8593	2026-09-16 09:47	54.75	OK	8594	2026-09-16 09:48	51.49	OK
8595	2026-09-16 09:49	54.08	OK	8596	2026-09-16 09:50	53.99	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8597	2026-09-16 09:51	55.05	OK	8598	2026-09-16 09:52	54.22	OK
8599	2026-09-16 09:53	56.35	OK	8600	2026-09-16 09:54	53.95	OK
8601	2026-09-16 09:55	53.35	OK	8602	2026-09-16 09:56	53.29	OK
8603	2026-09-16 09:57	52.55	OK	8604	2026-09-16 09:58	53.92	OK
8605	2026-09-16 09:59	54.66	OK	8606	2026-09-16 10:00	54.75	OK
8607	2026-09-16 10:01	51.44	OK	8608	2026-09-16 10:02	55.26	OK
8609	2026-09-16 10:03	54.06	OK	8610	2026-09-16 10:04	54.51	OK
8611	2026-09-16 10:05	53.95	OK	8612	2026-09-16 10:06	53.43	OK
8613	2026-09-16 10:07	52.39	OK	8614	2026-09-16 10:08	53.74	OK
8615	2026-09-16 10:09	52.79	OK	8616	2026-09-16 10:10	52.62	OK
8617	2026-09-16 10:11	55.25	OK	8618	2026-09-16 10:12	55.89	OK
8619	2026-09-16 10:13	55.14	OK	8620	2026-09-16 10:14	54.95	OK
8621	2026-09-16 10:15	54.51	OK	8622	2026-09-16 10:16	52.63	OK
8623	2026-09-16 10:17	51.91	OK	8624	2026-09-16 10:18	55.68	OK
8625	2026-09-16 10:19	53.40	OK	8626	2026-09-16 10:20	53.62	OK
8627	2026-09-16 10:21	53.96	OK	8628	2026-09-16 10:22	55.56	OK
8629	2026-09-16 10:23	55.21	OK	8630	2026-09-16 10:24	54.06	OK
8631	2026-09-16 10:25	53.49	OK	8632	2026-09-16 10:26	56.17	OK
8633	2026-09-16 10:27	53.27	OK	8634	2026-09-16 10:28	54.26	OK
8635	2026-09-16 10:29	54.30	OK	8636	2026-09-16 10:30	54.94	OK
8637	2026-09-16 10:31	54.55	OK	8638	2026-09-16 10:32	54.70	OK
8639	2026-09-16 10:33	56.18	OK	8640	2026-09-16 10:34	52.32	OK
8641	2026-09-16 10:35	53.04	OK	8642	2026-09-16 10:36	54.19	OK
8643	2026-09-16 10:37	54.62	OK	8644	2026-09-16 10:38	53.61	OK
8645	2026-09-16 10:39	53.82	OK	8646	2026-09-16 10:40	53.95	OK
8647	2026-09-16 10:41	53.94	OK	8648	2026-09-16 10:42	53.33	OK
8649	2026-09-16 10:43	54.60	OK	8650	2026-09-16 10:44	55.24	OK
8651	2026-09-16 10:45	53.46	OK	8652	2026-09-16 10:46	54.09	OK
8653	2026-09-16 10:47	53.97	OK	8654	2026-09-16 10:48	52.66	OK
8655	2026-09-16 10:49	54.37	OK	8656	2026-09-16 10:50	53.84	OK
8657	2026-09-16 10:51	53.13	OK	8658	2026-09-16 10:52	55.08	OK
8659	2026-09-16 10:53	55.15	OK	8660	2026-09-16 10:54	54.88	OK
8661	2026-09-16 10:55	55.51	OK	8662	2026-09-16 10:56	52.29	OK
8663	2026-09-16 10:57	53.63	OK	8664	2026-09-16 10:58	54.62	OK
8665	2026-09-16 10:59	54.78	OK	8666	2026-09-16 11:00	53.96	OK
8667	2026-09-16 11:01	53.96	OK	8668	2026-09-16 11:02	53.14	OK
8669	2026-09-16 11:03	51.12	OK	8670	2026-09-16 11:04	51.37	OK
8671	2026-09-16 11:05	51.80	OK	8672	2026-09-16 11:06	53.84	OK
8673	2026-09-16 11:07	52.89	OK	8674	2026-09-16 11:08	53.55	OK
8675	2026-09-16 11:09	56.89	OK	8676	2026-09-16 11:10	53.77	OK
8677	2026-09-16 11:11	54.68	OK	8678	2026-09-16 11:12	54.45	OK
8679	2026-09-16 11:13	54.07	OK	8680	2026-09-16 11:14	54.07	OK
8681	2026-09-16 11:15	55.95	OK	8682	2026-09-16 11:16	54.46	OK
8683	2026-09-16 11:17	56.29	OK	8684	2026-09-16 11:18	53.61	OK
8685	2026-09-16 11:19	53.34	OK	8686	2026-09-16 11:20	52.98	OK
8687	2026-09-16 11:21	54.21	OK	8688	2026-09-16 11:22	55.14	OK
8689	2026-09-16 11:23	54.09	OK	8690	2026-09-16 11:24	52.03	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8691	2026-09-16 11:25	52.32	OK	8692	2026-09-16 11:26	53.19	OK
8693	2026-09-16 11:27	55.73	OK	8694	2026-09-16 11:28	52.97	OK
8695	2026-09-16 11:29	56.12	OK	8696	2026-09-16 11:30	55.96	OK
8697	2026-09-16 11:31	53.72	OK	8698	2026-09-16 11:32	54.28	OK
8699	2026-09-16 11:33	53.69	OK	8700	2026-09-16 11:34	55.44	OK
8701	2026-09-16 11:35	55.44	OK	8702	2026-09-16 11:36	53.56	OK
8703	2026-09-16 11:37	53.82	OK	8704	2026-09-16 11:38	55.37	OK
8705	2026-09-16 11:39	53.14	OK	8706	2026-09-16 11:40	55.95	OK
8707	2026-09-16 11:41	53.25	OK	8708	2026-09-16 11:42	54.19	OK
8709	2026-09-16 11:43	52.03	OK	8710	2026-09-16 11:44	55.54	OK
8711	2026-09-16 11:45	54.03	OK	8712	2026-09-16 11:46	54.92	OK
8713	2026-09-16 11:47	52.61	OK	8714	2026-09-16 11:48	53.60	OK
8715	2026-09-16 11:49	54.71	OK	8716	2026-09-16 11:50	54.66	OK
8717	2026-09-16 11:51	52.38	OK	8718	2026-09-16 11:52	55.28	OK
8719	2026-09-16 11:53	55.33	OK	8720	2026-09-16 11:54	55.94	OK
8721	2026-09-16 11:55	52.75	OK	8722	2026-09-16 11:56	53.73	OK
8723	2026-09-16 11:57	56.11	OK	8724	2026-09-16 11:58	53.71	OK
8725	2026-09-16 11:59	56.13	OK	8726	2026-09-16 12:00	54.22	OK
8727	2026-09-16 12:01	55.02	OK	8728	2026-09-16 12:02	53.85	OK
8729	2026-09-16 12:03	52.79	OK	8730	2026-09-16 12:04	53.61	OK
8731	2026-09-16 12:05	54.72	OK	8732	2026-09-16 12:06	53.08	OK
8733	2026-09-16 12:07	55.45	OK	8734	2026-09-16 12:08	54.64	OK
8735	2026-09-16 12:09	55.10	OK	8736	2026-09-16 12:10	52.27	OK
8737	2026-09-16 12:11	54.59	OK	8738	2026-09-16 12:12	54.18	OK
8739	2026-09-16 12:13	53.94	OK	8740	2026-09-16 12:14	53.84	OK
8741	2026-09-16 12:15	54.50	OK	8742	2026-09-16 12:16	55.64	OK
8743	2026-09-16 12:17	53.51	OK	8744	2026-09-16 12:18	55.16	OK
8745	2026-09-16 12:19	54.10	OK	8746	2026-09-16 12:20	53.32	OK
8747	2026-09-16 12:21	55.75	OK	8748	2026-09-16 12:22	54.03	OK
8749	2026-09-16 12:23	54.53	OK	8750	2026-09-16 12:24	54.14	OK
8751	2026-09-16 12:25	53.28	OK	8752	2026-09-16 12:26	55.49	OK
8753	2026-09-16 12:27	54.33	OK	8754	2026-09-16 12:28	52.21	OK
8755	2026-09-16 12:29	55.82	OK	8756	2026-09-16 12:30	53.59	OK
8757	2026-09-16 12:31	52.03	OK	8758	2026-09-16 12:32	54.51	OK
8759	2026-09-16 12:33	52.65	OK	8760	2026-09-16 12:34	52.33	OK
8761	2026-09-16 12:35	54.39	OK	8762	2026-09-16 12:36	55.27	OK
8763	2026-09-16 12:37	53.38	OK	8764	2026-09-16 12:38	55.53	OK
8765	2026-09-16 12:39	53.62	OK	8766	2026-09-16 12:40	54.73	OK
8767	2026-09-16 12:41	53.55	OK	8768	2026-09-16 12:42	54.10	OK
8769	2026-09-16 12:43	54.22	OK	8770	2026-09-16 12:44	54.86	OK
8771	2026-09-16 12:45	52.24	OK	8772	2026-09-16 12:46	51.82	OK
8773	2026-09-16 12:47	52.78	OK	8774	2026-09-16 12:48	53.54	OK
8775	2026-09-16 12:49	53.08	OK	8776	2026-09-16 12:50	52.55	OK
8777	2026-09-16 12:51	54.56	OK	8778	2026-09-16 12:52	54.93	OK
8779	2026-09-16 12:53	52.81	OK	8780	2026-09-16 12:54	53.77	OK
8781	2026-09-16 12:55	53.72	OK	8782	2026-09-16 12:56	54.50	OK
8783	2026-09-16 12:57	54.54	OK	8784	2026-09-16 12:58	54.72	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8785	2026-09-16 12:59	55.29	OK	8786	2026-09-16 13:00	53.08	OK
8787	2026-09-16 13:01	51.07	OK	8788	2026-09-16 13:02	53.57	OK
8789	2026-09-16 13:03	55.28	OK	8790	2026-09-16 13:04	52.77	OK
8791	2026-09-16 13:05	52.75	OK	8792	2026-09-16 13:06	54.72	OK
8793	2026-09-16 13:07	55.29	OK	8794	2026-09-16 13:08	54.31	OK
8795	2026-09-16 13:09	52.39	OK	8796	2026-09-16 13:10	53.09	OK
8797	2026-09-16 13:11	53.05	OK	8798	2026-09-16 13:12	54.39	OK
8799	2026-09-16 13:13	54.00	OK	8800	2026-09-16 13:14	55.26	OK
8801	2026-09-16 13:15	53.10	OK	8802	2026-09-16 13:16	54.39	OK
8803	2026-09-16 13:17	52.32	OK	8804	2026-09-16 13:18	52.63	OK
8805	2026-09-16 13:19	53.63	OK	8806	2026-09-16 13:20	52.33	OK
8807	2026-09-16 13:21	54.49	OK	8808	2026-09-16 13:22	52.98	OK
8809	2026-09-16 13:23	51.92	OK	8810	2026-09-16 13:24	55.69	OK
8811	2026-09-16 13:25	53.15	OK	8812	2026-09-16 13:26	53.13	OK
8813	2026-09-16 13:27	52.57	OK	8814	2026-09-16 13:28	53.51	OK
8815	2026-09-16 13:29	52.63	OK	8816	2026-09-16 13:30	52.16	OK
8817	2026-09-16 13:31	53.58	OK	8818	2026-09-16 13:32	52.03	OK
8819	2026-09-16 13:33	52.33	OK	8820	2026-09-16 13:34	54.09	OK
8821	2026-09-16 13:35	55.56	OK	8822	2026-09-16 13:36	53.31	OK
8823	2026-09-16 13:37	52.42	OK	8824	2026-09-16 13:38	51.94	OK
8825	2026-09-16 13:39	52.03	OK	8826	2026-09-16 13:40	52.02	OK
8827	2026-09-16 13:41	52.59	OK	8828	2026-09-16 13:42	53.97	OK
8829	2026-09-16 13:43	53.31	OK	8830	2026-09-16 13:44	52.53	OK
8831	2026-09-16 13:45	54.96	OK	8832	2026-09-16 13:46	53.76	OK
8833	2026-09-16 13:47	54.81	OK	8834	2026-09-16 13:48	53.75	OK
8835	2026-09-16 13:49	54.26	OK	8836	2026-09-16 13:50	54.31	OK
8837	2026-09-16 13:51	52.75	OK	8838	2026-09-16 13:52	52.87	OK
8839	2026-09-16 13:53	52.05	OK	8840	2026-09-16 13:54	52.98	OK
8841	2026-09-16 13:55	53.19	OK	8842	2026-09-16 13:56	53.76	OK
8843	2026-09-16 13:57	53.88	OK	8844	2026-09-16 13:58	54.46	OK
8845	2026-09-16 13:59	52.78	OK	8846	2026-09-16 14:00	52.85	OK
8847	2026-09-16 14:01	52.70	OK	8848	2026-09-16 14:02	51.26	OK
8849	2026-09-16 14:03	52.80	OK	8850	2026-09-16 14:04	55.00	OK
8851	2026-09-16 14:05	54.20	OK	8852	2026-09-16 14:06	54.93	OK
8853	2026-09-16 14:07	53.07	OK	8854	2026-09-16 14:08	53.05	OK
8855	2026-09-16 14:09	52.41	OK	8856	2026-09-16 14:10	53.51	OK
8857	2026-09-16 14:11	53.43	OK	8858	2026-09-16 14:12	51.98	OK
8859	2026-09-16 14:13	52.04	OK	8860	2026-09-16 14:14	52.46	OK
8861	2026-09-16 14:15	51.50	OK	8862	2026-09-16 14:16	52.84	OK
8863	2026-09-16 14:17	52.11	OK	8864	2026-09-16 14:18	53.83	OK
8865	2026-09-16 14:19	54.29	OK	8866	2026-09-16 14:20	52.82	OK
8867	2026-09-16 14:21	50.72	OK	8868	2026-09-16 14:22	51.18	OK
8869	2026-09-16 14:23	52.83	OK	8870	2026-09-16 14:24	52.50	OK
8871	2026-09-16 14:25	52.44	OK	8872	2026-09-16 14:26	51.75	OK
8873	2026-09-16 14:27	54.14	OK	8874	2026-09-16 14:28	54.37	OK
8875	2026-09-16 14:29	51.92	OK	8876	2026-09-16 14:30	52.14	OK
8877	2026-09-16 14:31	55.21	OK	8878	2026-09-16 14:32	53.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8879	2026-09-16 14:33	52.58	OK	8880	2026-09-16 14:34	53.26	OK
8881	2026-09-16 14:35	53.39	OK	8882	2026-09-16 14:36	50.68	OK
8883	2026-09-16 14:37	53.83	OK	8884	2026-09-16 14:38	51.30	OK
8885	2026-09-16 14:39	51.80	OK	8886	2026-09-16 14:40	54.49	OK
8887	2026-09-16 14:41	52.83	OK	8888	2026-09-16 14:42	50.79	OK
8889	2026-09-16 14:43	53.86	OK	8890	2026-09-16 14:44	51.63	OK
8891	2026-09-16 14:45	53.15	OK	8892	2026-09-16 14:46	52.93	OK
8893	2026-09-16 14:47	51.21	OK	8894	2026-09-16 14:48	53.37	OK
8895	2026-09-16 14:49	52.61	OK	8896	2026-09-16 14:50	53.19	OK
8897	2026-09-16 14:51	52.25	OK	8898	2026-09-16 14:52	52.08	OK
8899	2026-09-16 14:53	53.68	OK	8900	2026-09-16 14:54	52.11	OK
8901	2026-09-16 14:55	52.88	OK	8902	2026-09-16 14:56	53.71	OK
8903	2026-09-16 14:57	51.74	OK	8904	2026-09-16 14:58	52.62	OK
8905	2026-09-16 14:59	52.66	OK	8906	2026-09-16 15:00	50.63	OK
8907	2026-09-16 15:01	50.12	OK	8908	2026-09-16 15:02	51.30	OK
8909	2026-09-16 15:03	53.45	OK	8910	2026-09-16 15:04	51.57	OK
8911	2026-09-16 15:05	52.07	OK	8912	2026-09-16 15:06	51.67	OK
8913	2026-09-16 15:07	52.33	OK	8914	2026-09-16 15:08	54.30	OK
8915	2026-09-16 15:09	52.82	OK	8916	2026-09-16 15:10	54.09	OK
8917	2026-09-16 15:11	52.19	OK	8918	2026-09-16 15:12	52.95	OK
8919	2026-09-16 15:13	52.17	OK	8920	2026-09-16 15:14	50.77	OK
8921	2026-09-16 15:15	53.02	OK	8922	2026-09-16 15:16	51.01	OK
8923	2026-09-16 15:17	52.22	OK	8924	2026-09-16 15:18	53.60	OK
8925	2026-09-16 15:19	53.89	OK	8926	2026-09-16 15:20	51.36	OK
8927	2026-09-16 15:21	50.97	OK	8928	2026-09-16 15:22	49.35	OK
8929	2026-09-16 15:23	51.84	OK	8930	2026-09-16 15:24	52.89	OK
8931	2026-09-16 15:25	51.33	OK	8932	2026-09-16 15:26	51.89	OK
8933	2026-09-16 15:27	50.68	OK	8934	2026-09-16 15:28	50.50	OK
8935	2026-09-16 15:29	51.14	OK	8936	2026-09-16 15:30	53.63	OK
8937	2026-09-16 15:31	52.02	OK	8938	2026-09-16 15:32	51.17	OK
8939	2026-09-16 15:33	51.28	OK	8940	2026-09-16 15:34	51.59	OK
8941	2026-09-16 15:35	52.94	OK	8942	2026-09-16 15:36	52.51	OK
8943	2026-09-16 15:37	52.60	OK	8944	2026-09-16 15:38	53.45	OK
8945	2026-09-16 15:39	49.13	OK	8946	2026-09-16 15:40	51.08	OK
8947	2026-09-16 15:41	50.63	OK	8948	2026-09-16 15:42	54.08	OK
8949	2026-09-16 15:43	50.96	OK	8950	2026-09-16 15:44	50.39	OK
8951	2026-09-16 15:45	51.21	OK	8952	2026-09-16 15:46	53.11	OK
8953	2026-09-16 15:47	48.92	OK	8954	2026-09-16 15:48	52.40	OK
8955	2026-09-16 15:49	50.64	OK	8956	2026-09-16 15:50	51.80	OK
8957	2026-09-16 15:51	52.51	OK	8958	2026-09-16 15:52	50.67	OK
8959	2026-09-16 15:53	51.52	OK	8960	2026-09-16 15:54	51.62	OK
8961	2026-09-16 15:55	51.03	OK	8962	2026-09-16 15:56	52.64	OK
8963	2026-09-16 15:57	48.88	OK	8964	2026-09-16 15:58	51.41	OK
8965	2026-09-16 15:59	50.97	OK	8966	2026-09-16 16:00	50.36	OK
8967	2026-09-16 16:01	49.75	OK	8968	2026-09-16 16:02	49.81	OK
8969	2026-09-16 16:03	49.53	OK	8970	2026-09-16 16:04	49.22	OK
8971	2026-09-16 16:05	52.82	OK	8972	2026-09-16 16:06	50.90	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8973	2026-09-16 16:07	50.77	OK	8974	2026-09-16 16:08	50.54	OK
8975	2026-09-16 16:09	50.20	OK	8976	2026-09-16 16:10	51.05	OK
8977	2026-09-16 16:11	49.04	OK	8978	2026-09-16 16:12	50.63	OK
8979	2026-09-16 16:13	50.19	OK	8980	2026-09-16 16:14	52.25	OK
8981	2026-09-16 16:15	49.73	OK	8982	2026-09-16 16:16	50.66	OK
8983	2026-09-16 16:17	48.69	OK	8984	2026-09-16 16:18	50.28	OK
8985	2026-09-16 16:19	51.20	OK	8986	2026-09-16 16:20	51.96	OK
8987	2026-09-16 16:21	50.76	OK	8988	2026-09-16 16:22	50.12	OK
8989	2026-09-16 16:23	52.27	OK	8990	2026-09-16 16:24	51.00	OK
8991	2026-09-16 16:25	51.02	OK	8992	2026-09-16 16:26	50.13	OK
8993	2026-09-16 16:27	50.03	OK	8994	2026-09-16 16:28	51.42	OK
8995	2026-09-16 16:29	51.02	OK	8996	2026-09-16 16:30	51.43	OK
8997	2026-09-16 16:31	50.23	OK	8998	2026-09-16 16:32	51.65	OK
8999	2026-09-16 16:33	51.33	OK	9000	2026-09-16 16:34	52.01	OK
9001	2026-09-16 16:35	49.74	OK	9002	2026-09-16 16:36	52.74	OK
9003	2026-09-16 16:37	50.96	OK	9004	2026-09-16 16:38	50.81	OK
9005	2026-09-16 16:39	49.83	OK	9006	2026-09-16 16:40	51.66	OK
9007	2026-09-16 16:41	49.87	OK	9008	2026-09-16 16:42	49.76	OK
9009	2026-09-16 16:43	51.18	OK	9010	2026-09-16 16:44	50.08	OK
9011	2026-09-16 16:45	48.91	OK	9012	2026-09-16 16:46	50.17	OK
9013	2026-09-16 16:47	51.10	OK	9014	2026-09-16 16:48	51.18	OK
9015	2026-09-16 16:49	49.08	OK	9016	2026-09-16 16:50	50.94	OK
9017	2026-09-16 16:51	49.82	OK	9018	2026-09-16 16:52	49.75	OK
9019	2026-09-16 16:53	49.35	OK	9020	2026-09-16 16:54	49.37	OK
9021	2026-09-16 16:55	48.96	OK	9022	2026-09-16 16:56	51.52	OK
9023	2026-09-16 16:57	50.45	OK	9024	2026-09-16 16:58	49.13	OK
9025	2026-09-16 16:59	49.48	OK	9026	2026-09-16 17:00	48.85	OK
9027	2026-09-16 17:01	51.67	OK	9028	2026-09-16 17:02	50.84	OK
9029	2026-09-16 17:03	49.78	OK	9030	2026-09-16 17:04	50.27	OK
9031	2026-09-16 17:05	49.21	OK	9032	2026-09-16 17:06	49.04	OK
9033	2026-09-16 17:07	51.27	OK	9034	2026-09-16 17:08	50.75	OK
9035	2026-09-16 17:09	49.18	OK	9036	2026-09-16 17:10	49.82	OK
9037	2026-09-16 17:11	50.63	OK	9038	2026-09-16 17:12	49.16	OK
9039	2026-09-16 17:13	50.03	OK	9040	2026-09-16 17:14	49.54	OK
9041	2026-09-16 17:15	50.65	OK	9042	2026-09-16 17:16	51.29	OK
9043	2026-09-16 17:17	52.21	OK	9044	2026-09-16 17:18	49.96	OK
9045	2026-09-16 17:19	49.38	OK	9046	2026-09-16 17:20	49.53	OK
9047	2026-09-16 17:21	50.43	OK	9048	2026-09-16 17:22	49.34	OK
9049	2026-09-16 17:23	49.61	OK	9050	2026-09-16 17:24	48.33	OK
9051	2026-09-16 17:25	48.72	OK	9052	2026-09-16 17:26	50.63	OK
9053	2026-09-16 17:27	49.73	OK	9054	2026-09-16 17:28	50.74	OK
9055	2026-09-16 17:29	48.92	OK	9056	2026-09-16 17:30	48.36	OK
9057	2026-09-16 17:31	49.17	OK	9058	2026-09-16 17:32	48.90	OK
9059	2026-09-16 17:33	48.55	OK	9060	2026-09-16 17:34	49.95	OK
9061	2026-09-16 17:35	49.08	OK	9062	2026-09-16 17:36	49.14	OK
9063	2026-09-16 17:37	47.83	OK	9064	2026-09-16 17:38	47.61	OK
9065	2026-09-16 17:39	48.36	OK	9066	2026-09-16 17:40	50.24	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9067	2026-09-16 17:41	48.26	OK	9068	2026-09-16 17:42	50.21	OK
9069	2026-09-16 17:43	48.44	OK	9070	2026-09-16 17:44	48.27	OK
9071	2026-09-16 17:45	48.98	OK	9072	2026-09-16 17:46	48.06	OK
9073	2026-09-16 17:47	47.19	OK	9074	2026-09-16 17:48	48.42	OK
9075	2026-09-16 17:49	49.89	OK	9076	2026-09-16 17:50	48.38	OK
9077	2026-09-16 17:51	49.87	OK	9078	2026-09-16 17:52	48.98	OK
9079	2026-09-16 17:53	49.27	OK	9080	2026-09-16 17:54	49.01	OK
9081	2026-09-16 17:55	47.15	OK	9082	2026-09-16 17:56	48.26	OK
9083	2026-09-16 17:57	48.64	OK	9084	2026-09-16 17:58	49.13	OK
9085	2026-09-16 17:59	48.40	OK	9086	2026-09-16 18:00	47.52	OK
9087	2026-09-16 18:01	49.46	OK	9088	2026-09-16 18:02	48.06	OK
9089	2026-09-16 18:03	48.13	OK	9090	2026-09-16 18:04	49.50	OK
9091	2026-09-16 18:05	47.13	OK	9092	2026-09-16 18:06	46.58	OK
9093	2026-09-16 18:07	48.60	OK	9094	2026-09-16 18:08	48.63	OK
9095	2026-09-16 18:09	47.58	OK	9096	2026-09-16 18:10	48.97	OK
9097	2026-09-16 18:11	48.93	OK	9098	2026-09-16 18:12	48.98	OK
9099	2026-09-16 18:13	48.35	OK	9100	2026-09-16 18:14	47.92	OK
9101	2026-09-16 18:15	48.52	OK	9102	2026-09-16 18:16	50.47	OK
9103	2026-09-16 18:17	47.42	OK	9104	2026-09-16 18:18	48.27	OK
9105	2026-09-16 18:19	49.84	OK	9106	2026-09-16 18:20	50.35	OK
9107	2026-09-16 18:21	49.20	OK	9108	2026-09-16 18:22	47.17	OK
9109	2026-09-16 18:23	47.88	OK	9110	2026-09-16 18:24	46.23	OK
9111	2026-09-16 18:25	48.07	OK	9112	2026-09-16 18:26	49.64	OK
9113	2026-09-16 18:27	47.71	OK	9114	2026-09-16 18:28	48.42	OK
9115	2026-09-16 18:29	49.45	OK	9116	2026-09-16 18:30	48.31	OK
9117	2026-09-16 18:31	46.05	OK	9118	2026-09-16 18:32	46.50	OK
9119	2026-09-16 18:33	50.31	OK	9120	2026-09-16 18:34	46.60	OK
9121	2026-09-16 18:35	47.35	OK	9122	2026-09-16 18:36	46.41	OK
9123	2026-09-16 18:37	49.91	OK	9124	2026-09-16 18:38	48.00	OK
9125	2026-09-16 18:39	48.12	OK	9126	2026-09-16 18:40	45.63	OK
9127	2026-09-16 18:41	49.53	OK	9128	2026-09-16 18:42	48.32	OK
9129	2026-09-16 18:43	48.47	OK	9130	2026-09-16 18:44	47.62	OK
9131	2026-09-16 18:45	46.55	OK	9132	2026-09-16 18:46	46.33	OK
9133	2026-09-16 18:47	47.72	OK	9134	2026-09-16 18:48	48.39	OK
9135	2026-09-16 18:49	49.33	OK	9136	2026-09-16 18:50	50.30	OK
9137	2026-09-16 18:51	47.05	OK	9138	2026-09-16 18:52	47.80	OK
9139	2026-09-16 18:53	48.79	OK	9140	2026-09-16 18:54	47.87	OK
9141	2026-09-16 18:55	48.13	OK	9142	2026-09-16 18:56	47.07	OK
9143	2026-09-16 18:57	46.98	OK	9144	2026-09-16 18:58	49.98	OK
9145	2026-09-16 18:59	47.72	OK	9146	2026-09-16 19:00	47.84	OK
9147	2026-09-16 19:01	47.43	OK	9148	2026-09-16 19:02	46.89	OK
9149	2026-09-16 19:03	44.60	OK	9150	2026-09-16 19:04	48.54	OK
9151	2026-09-16 19:05	47.75	OK	9152	2026-09-16 19:06	46.90	OK
9153	2026-09-16 19:07	49.10	OK	9154	2026-09-16 19:08	46.56	OK
9155	2026-09-16 19:09	47.94	OK	9156	2026-09-16 19:10	48.37	OK
9157	2026-09-16 19:11	47.99	OK	9158	2026-09-16 19:12	46.43	OK
9159	2026-09-16 19:13	47.76	OK	9160	2026-09-16 19:14	46.95	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9161	2026-09-16 19:15	46.39	OK	9162	2026-09-16 19:16	46.65	OK
9163	2026-09-16 19:17	47.44	OK	9164	2026-09-16 19:18	49.07	OK
9165	2026-09-16 19:19	47.60	OK	9166	2026-09-16 19:20	47.46	OK
9167	2026-09-16 19:21	48.70	OK	9168	2026-09-16 19:22	48.09	OK
9169	2026-09-16 19:23	45.35	OK	9170	2026-09-16 19:24	47.29	OK
9171	2026-09-16 19:25	46.13	OK	9172	2026-09-16 19:26	47.65	OK
9173	2026-09-16 19:27	47.50	OK	9174	2026-09-16 19:28	47.50	OK
9175	2026-09-16 19:29	46.99	OK	9176	2026-09-16 19:30	47.58	OK
9177	2026-09-16 19:31	45.58	OK	9178	2026-09-16 19:32	47.43	OK
9179	2026-09-16 19:33	45.01	OK	9180	2026-09-16 19:34	46.06	OK
9181	2026-09-16 19:35	46.90	OK	9182	2026-09-16 19:36	47.62	OK
9183	2026-09-16 19:37	49.09	OK	9184	2026-09-16 19:38	47.00	OK
9185	2026-09-16 19:39	48.10	OK	9186	2026-09-16 19:40	46.67	OK
9187	2026-09-16 19:41	47.86	OK	9188	2026-09-16 19:42	48.98	OK
9189	2026-09-16 19:43	47.89	OK	9190	2026-09-16 19:44	45.38	OK
9191	2026-09-16 19:45	47.68	OK	9192	2026-09-16 19:46	46.26	OK
9193	2026-09-16 19:47	46.58	OK	9194	2026-09-16 19:48	45.72	OK
9195	2026-09-16 19:49	47.95	OK	9196	2026-09-16 19:50	46.68	OK
9197	2026-09-16 19:51	43.82	OK	9198	2026-09-16 19:52	46.35	OK
9199	2026-09-16 19:53	46.05	OK	9200	2026-09-16 19:54	45.87	OK
9201	2026-09-16 19:55	48.19	OK	9202	2026-09-16 19:56	45.06	OK
9203	2026-09-16 19:57	46.74	OK	9204	2026-09-16 19:58	45.94	OK
9205	2026-09-16 19:59	46.03	OK	9206	2026-09-16 20:00	45.20	OK
9207	2026-09-16 20:01	45.97	OK	9208	2026-09-16 20:02	45.14	OK
9209	2026-09-16 20:03	47.80	OK	9210	2026-09-16 20:04	45.92	OK
9211	2026-09-16 20:05	47.47	OK	9212	2026-09-16 20:06	45.19	OK
9213	2026-09-16 20:07	46.79	OK	9214	2026-09-16 20:08	48.22	OK
9215	2026-09-16 20:09	44.98	OK	9216	2026-09-16 20:10	45.91	OK
9217	2026-09-16 20:11	46.58	OK	9218	2026-09-16 20:12	45.48	OK
9219	2026-09-16 20:13	45.71	OK	9220	2026-09-16 20:14	48.22	OK
9221	2026-09-16 20:15	44.73	OK	9222	2026-09-16 20:16	46.39	OK
9223	2026-09-16 20:17	45.15	OK	9224	2026-09-16 20:18	45.00	OK
9225	2026-09-16 20:19	47.03	OK	9226	2026-09-16 20:20	46.64	OK
9227	2026-09-16 20:21	46.91	OK	9228	2026-09-16 20:22	44.92	OK
9229	2026-09-16 20:23	45.69	OK	9230	2026-09-16 20:24	46.82	OK
9231	2026-09-16 20:25	45.31	OK	9232	2026-09-16 20:26	45.02	OK
9233	2026-09-16 20:27	47.52	OK	9234	2026-09-16 20:28	45.97	OK
9235	2026-09-16 20:29	46.80	OK	9236	2026-09-16 20:30	46.39	OK
9237	2026-09-16 20:31	43.17	OK	9238	2026-09-16 20:32	46.46	OK
9239	2026-09-16 20:33	47.47	OK	9240	2026-09-16 20:34	46.40	OK
9241	2026-09-16 20:35	46.95	OK	9242	2026-09-16 20:36	45.32	OK
9243	2026-09-16 20:37	46.56	OK	9244	2026-09-16 20:38	44.84	OK
9245	2026-09-16 20:39	45.06	OK	9246	2026-09-16 20:40	46.89	OK
9247	2026-09-16 20:41	46.13	OK	9248	2026-09-16 20:42	45.08	OK
9249	2026-09-16 20:43	46.10	OK	9250	2026-09-16 20:44	46.66	OK
9251	2026-09-16 20:45	45.92	OK	9252	2026-09-16 20:46	45.99	OK
9253	2026-09-16 20:47	44.01	OK	9254	2026-09-16 20:48	44.83	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9255	2026-09-16 20:49	43.75	OK	9256	2026-09-16 20:50	45.19	OK
9257	2026-09-16 20:51	46.35	OK	9258	2026-09-16 20:52	45.68	OK
9259	2026-09-16 20:53	44.87	OK	9260	2026-09-16 20:54	47.58	OK
9261	2026-09-16 20:55	44.11	OK	9262	2026-09-16 20:56	45.54	OK
9263	2026-09-16 20:57	44.03	OK	9264	2026-09-16 20:58	45.32	OK
9265	2026-09-16 20:59	47.27	OK	9266	2026-09-16 21:00	46.73	OK
9267	2026-09-16 21:01	47.20	OK	9268	2026-09-16 21:02	48.60	OK
9269	2026-09-16 21:03	45.02	OK	9270	2026-09-16 21:04	45.65	OK
9271	2026-09-16 21:05	45.76	OK	9272	2026-09-16 21:06	45.83	OK
9273	2026-09-16 21:07	47.03	OK	9274	2026-09-16 21:08	44.04	OK
9275	2026-09-16 21:09	44.72	OK	9276	2026-09-16 21:10	45.54	OK
9277	2026-09-16 21:11	46.11	OK	9278	2026-09-16 21:12	43.93	OK
9279	2026-09-16 21:13	45.16	OK	9280	2026-09-16 21:14	45.31	OK
9281	2026-09-16 21:15	46.01	OK	9282	2026-09-16 21:16	43.71	OK
9283	2026-09-16 21:17	45.36	OK	9284	2026-09-16 21:18	43.18	OK
9285	2026-09-16 21:19	45.12	OK	9286	2026-09-16 21:20	46.09	OK
9287	2026-09-16 21:21	44.37	OK	9288	2026-09-16 21:22	46.96	OK
9289	2026-09-16 21:23	45.93	OK	9290	2026-09-16 21:24	45.72	OK
9291	2026-09-16 21:25	45.09	OK	9292	2026-09-16 21:26	43.91	OK
9293	2026-09-16 21:27	45.74	OK	9294	2026-09-16 21:28	44.61	OK
9295	2026-09-16 21:29	44.44	OK	9296	2026-09-16 21:30	44.00	OK
9297	2026-09-16 21:31	46.57	OK	9298	2026-09-16 21:32	45.18	OK
9299	2026-09-16 21:33	45.66	OK	9300	2026-09-16 21:34	43.37	OK
9301	2026-09-16 21:35	45.42	OK	9302	2026-09-16 21:36	44.84	OK
9303	2026-09-16 21:37	46.06	OK	9304	2026-09-16 21:38	46.02	OK
9305	2026-09-16 21:39	45.71	OK	9306	2026-09-16 21:40	47.87	OK
9307	2026-09-16 21:41	45.56	OK	9308	2026-09-16 21:42	45.71	OK
9309	2026-09-16 21:43	45.47	OK	9310	2026-09-16 21:44	43.23	OK
9311	2026-09-16 21:45	45.99	OK	9312	2026-09-16 21:46	43.55	OK
9313	2026-09-16 21:47	45.29	OK	9314	2026-09-16 21:48	44.55	OK
9315	2026-09-16 21:49	44.50	OK	9316	2026-09-16 21:50	44.70	OK
9317	2026-09-16 21:51	45.25	OK	9318	2026-09-16 21:52	44.43	OK
9319	2026-09-16 21:53	45.48	OK	9320	2026-09-16 21:54	43.95	OK
9321	2026-09-16 21:55	44.59	OK	9322	2026-09-16 21:56	44.40	OK
9323	2026-09-16 21:57	45.13	OK	9324	2026-09-16 21:58	46.35	OK
9325	2026-09-16 21:59	46.94	OK	9326	2026-09-16 22:00	45.15	OK
9327	2026-09-16 22:01	45.52	OK	9328	2026-09-16 22:02	45.06	OK
9329	2026-09-16 22:03	42.65	OK	9330	2026-09-16 22:04	45.58	OK
9331	2026-09-16 22:05	45.48	OK	9332	2026-09-16 22:06	42.96	OK
9333	2026-09-16 22:07	45.47	OK	9334	2026-09-16 22:08	43.45	OK
9335	2026-09-16 22:09	44.03	OK	9336	2026-09-16 22:10	42.34	OK
9337	2026-09-16 22:11	44.38	OK	9338	2026-09-16 22:12	44.58	OK
9339	2026-09-16 22:13	44.64	OK	9340	2026-09-16 22:14	44.46	OK
9341	2026-09-16 22:15	43.03	OK	9342	2026-09-16 22:16	45.58	OK
9343	2026-09-16 22:17	44.61	OK	9344	2026-09-16 22:18	44.68	OK
9345	2026-09-16 22:19	44.10	OK	9346	2026-09-16 22:20	43.74	OK
9347	2026-09-16 22:21	46.30	OK	9348	2026-09-16 22:22	45.40	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9349	2026-09-16 22:23	45.02	OK	9350	2026-09-16 22:24	45.36	OK
9351	2026-09-16 22:25	45.22	OK	9352	2026-09-16 22:26	42.73	OK
9353	2026-09-16 22:27	44.61	OK	9354	2026-09-16 22:28	44.12	OK
9355	2026-09-16 22:29	44.73	OK	9356	2026-09-16 22:30	46.32	OK
9357	2026-09-16 22:31	43.56	OK	9358	2026-09-16 22:32	47.77	OK
9359	2026-09-16 22:33	43.15	OK	9360	2026-09-16 22:34	45.25	OK
9361	2026-09-16 22:35	43.91	OK	9362	2026-09-16 22:36	43.64	OK
9363	2026-09-16 22:37	44.66	OK	9364	2026-09-16 22:38	45.21	OK
9365	2026-09-16 22:39	44.10	OK	9366	2026-09-16 22:40	46.00	OK
9367	2026-09-16 22:41	46.30	OK	9368	2026-09-16 22:42	45.00	OK
9369	2026-09-16 22:43	44.08	OK	9370	2026-09-16 22:44	44.54	OK
9371	2026-09-16 22:45	43.55	OK	9372	2026-09-16 22:46	43.60	OK
9373	2026-09-16 22:47	44.03	OK	9374	2026-09-16 22:48	44.35	OK
9375	2026-09-16 22:49	46.02	OK	9376	2026-09-16 22:50	44.19	OK
9377	2026-09-16 22:51	46.06	OK	9378	2026-09-16 22:52	46.67	OK
9379	2026-09-16 22:53	45.40	OK	9380	2026-09-16 22:54	44.60	OK
9381	2026-09-16 22:55	44.83	OK	9382	2026-09-16 22:56	45.14	OK
9383	2026-09-16 22:57	44.66	OK	9384	2026-09-16 22:58	44.90	OK
9385	2026-09-16 22:59	46.55	OK	9386	2026-09-16 23:00	43.80	OK
9387	2026-09-16 23:01	44.17	OK	9388	2026-09-16 23:02	43.69	OK
9389	2026-09-16 23:03	44.50	OK	9390	2026-09-16 23:04	45.64	OK
9391	2026-09-16 23:05	45.29	OK	9392	2026-09-16 23:06	45.82	OK
9393	2026-09-16 23:07	44.22	OK	9394	2026-09-16 23:08	45.14	OK
9395	2026-09-16 23:09	45.25	OK	9396	2026-09-16 23:10	43.95	OK
9397	2026-09-16 23:11	43.87	OK	9398	2026-09-16 23:12	44.93	OK
9399	2026-09-16 23:13	45.27	OK	9400	2026-09-16 23:14	45.20	OK
9401	2026-09-16 23:15	43.79	OK	9402	2026-09-16 23:16	43.95	OK
9403	2026-09-16 23:17	44.42	OK	9404	2026-09-16 23:18	44.36	OK
9405	2026-09-16 23:19	45.54	OK	9406	2026-09-16 23:20	43.46	OK
9407	2026-09-16 23:21	44.00	OK	9408	2026-09-16 23:22	44.58	OK
9409	2026-09-16 23:23	47.57	OK	9410	2026-09-16 23:24	42.91	OK
9411	2026-09-16 23:25	43.61	OK	9412	2026-09-16 23:26	43.10	OK
9413	2026-09-16 23:27	44.43	OK	9414	2026-09-16 23:28	44.12	OK
9415	2026-09-16 23:29	45.42	OK	9416	2026-09-16 23:30	43.57	OK
9417	2026-09-16 23:31	44.92	OK	9418	2026-09-16 23:32	44.94	OK
9419	2026-09-16 23:33	44.81	OK	9420	2026-09-16 23:34	43.07	OK
9421	2026-09-16 23:35	44.88	OK	9422	2026-09-16 23:36	44.23	OK
9423	2026-09-16 23:37	42.46	OK	9424	2026-09-16 23:38	43.18	OK
9425	2026-09-16 23:39	45.06	OK	9426	2026-09-16 23:40	44.07	OK
9427	2026-09-16 23:41	42.49	OK	9428	2026-09-16 23:42	43.31	OK
9429	2026-09-16 23:43	43.67	OK	9430	2026-09-16 23:44	43.94	OK
9431	2026-09-16 23:45	42.89	OK	9432	2026-09-16 23:46	43.63	OK
9433	2026-09-16 23:47	43.96	OK	9434	2026-09-16 23:48	44.27	OK
9435	2026-09-16 23:49	43.84	OK	9436	2026-09-16 23:50	44.18	OK
9437	2026-09-16 23:51	46.45	OK	9438	2026-09-16 23:52	44.28	OK
9439	2026-09-16 23:53	43.40	OK	9440	2026-09-16 23:54	43.15	OK
9441	2026-09-16 23:55	45.38	OK	9442	2026-09-16 23:56	43.71	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9443	2026-09-16 23:57	44.24	OK	9444	2026-09-16 23:58	45.07	OK
9445	2026-09-16 23:59	43.45	OK	9446	2026-09-17 00:00	45.35	OK
9447	2026-09-17 00:01	44.88	OK	9448	2026-09-17 00:02	43.46	OK
9449	2026-09-17 00:03	44.70	OK	9450	2026-09-17 00:04	43.48	OK
9451	2026-09-17 00:05	45.21	OK	9452	2026-09-17 00:06	44.93	OK
9453	2026-09-17 00:07	44.43	OK	9454	2026-09-17 00:08	45.28	OK
9455	2026-09-17 00:09	45.51	OK	9456	2026-09-17 00:10	44.32	OK
9457	2026-09-17 00:11	45.92	OK	9458	2026-09-17 00:12	44.61	OK
9459	2026-09-17 00:13	45.17	OK	9460	2026-09-17 00:14	44.35	OK
9461	2026-09-17 00:15	46.20	OK	9462	2026-09-17 00:16	45.63	OK
9463	2026-09-17 00:17	44.99	OK	9464	2026-09-17 00:18	43.62	OK
9465	2026-09-17 00:19	43.75	OK	9466	2026-09-17 00:20	44.85	OK
9467	2026-09-17 00:21	42.74	OK	9468	2026-09-17 00:22	45.19	OK
9469	2026-09-17 00:23	45.70	OK	9470	2026-09-17 00:24	45.03	OK
9471	2026-09-17 00:25	45.09	OK	9472	2026-09-17 00:26	46.27	OK
9473	2026-09-17 00:27	45.45	OK	9474	2026-09-17 00:28	45.88	OK
9475	2026-09-17 00:29	44.21	OK	9476	2026-09-17 00:30	45.87	OK
9477	2026-09-17 00:31	44.45	OK	9478	2026-09-17 00:32	44.84	OK
9479	2026-09-17 00:33	44.34	OK	9480	2026-09-17 00:34	44.86	OK
9481	2026-09-17 00:35	45.63	OK	9482	2026-09-17 00:36	43.97	OK
9483	2026-09-17 00:37	44.84	OK	9484	2026-09-17 00:38	43.55	OK
9485	2026-09-17 00:39	44.46	OK	9486	2026-09-17 00:40	46.84	OK
9487	2026-09-17 00:41	45.38	OK	9488	2026-09-17 00:42	45.98	OK
9489	2026-09-17 00:43	45.05	OK	9490	2026-09-17 00:44	45.93	OK
9491	2026-09-17 00:45	42.57	OK	9492	2026-09-17 00:46	44.63	OK
9493	2026-09-17 00:47	42.37	OK	9494	2026-09-17 00:48	46.24	OK
9495	2026-09-17 00:49	45.10	OK	9496	2026-09-17 00:50	43.46	OK
9497	2026-09-17 00:51	46.19	OK	9498	2026-09-17 00:52	44.11	OK
9499	2026-09-17 00:53	45.51	OK	9500	2026-09-17 00:54	44.45	OK
9501	2026-09-17 00:55	45.51	OK	9502	2026-09-17 00:56	44.59	OK
9503	2026-09-17 00:57	43.64	OK	9504	2026-09-17 00:58	44.65	OK
9505	2026-09-17 00:59	44.58	OK	9506	2026-09-17 01:00	43.96	OK
9507	2026-09-17 01:01	44.27	OK	9508	2026-09-17 01:02	45.43	OK
9509	2026-09-17 01:03	42.24	OK	9510	2026-09-17 01:04	44.13	OK
9511	2026-09-17 01:05	43.12	OK	9512	2026-09-17 01:06	47.83	OK
9513	2026-09-17 01:07	45.45	OK	9514	2026-09-17 01:08	44.43	OK
9515	2026-09-17 01:09	46.09	OK	9516	2026-09-17 01:10	44.16	OK
9517	2026-09-17 01:11	43.82	OK	9518	2026-09-17 01:12	44.86	OK
9519	2026-09-17 01:13	45.91	OK	9520	2026-09-17 01:14	44.30	OK
9521	2026-09-17 01:15	42.80	OK	9522	2026-09-17 01:16	47.41	OK
9523	2026-09-17 01:17	45.02	OK	9524	2026-09-17 01:18	46.38	OK
9525	2026-09-17 01:19	45.84	OK	9526	2026-09-17 01:20	42.86	OK
9527	2026-09-17 01:21	45.16	OK	9528	2026-09-17 01:22	46.98	OK
9529	2026-09-17 01:23	44.93	OK	9530	2026-09-17 01:24	46.26	OK
9531	2026-09-17 01:25	46.38	OK	9532	2026-09-17 01:26	45.78	OK
9533	2026-09-17 01:27	44.09	OK	9534	2026-09-17 01:28	43.74	OK
9535	2026-09-17 01:29	45.16	OK	9536	2026-09-17 01:30	46.15	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9537	2026-09-17 01:31	45.21	OK	9538	2026-09-17 01:32	44.16	OK
9539	2026-09-17 01:33	45.20	OK	9540	2026-09-17 01:34	43.31	OK
9541	2026-09-17 01:35	46.20	OK	9542	2026-09-17 01:36	45.45	OK
9543	2026-09-17 01:37	47.16	OK	9544	2026-09-17 01:38	43.16	OK
9545	2026-09-17 01:39	45.86	OK	9546	2026-09-17 01:40	45.86	OK
9547	2026-09-17 01:41	46.90	OK	9548	2026-09-17 01:42	44.09	OK
9549	2026-09-17 01:43	46.40	OK	9550	2026-09-17 01:44	43.66	OK
9551	2026-09-17 01:45	44.09	OK	9552	2026-09-17 01:46	47.98	OK
9553	2026-09-17 01:47	45.96	OK	9554	2026-09-17 01:48	45.44	OK
9555	2026-09-17 01:49	45.18	OK	9556	2026-09-17 01:50	46.12	OK
9557	2026-09-17 01:51	47.15	OK	9558	2026-09-17 01:52	45.60	OK
9559	2026-09-17 01:53	47.33	OK	9560	2026-09-17 01:54	46.09	OK
9561	2026-09-17 01:55	45.03	OK	9562	2026-09-17 01:56	46.10	OK
9563	2026-09-17 01:57	44.52	OK	9564	2026-09-17 01:58	47.21	OK
9565	2026-09-17 01:59	45.96	OK	9566	2026-09-17 02:00	45.40	OK
9567	2026-09-17 02:01	48.06	OK	9568	2026-09-17 02:02	44.34	OK
9569	2026-09-17 02:03	46.63	OK	9570	2026-09-17 02:04	43.79	OK
9571	2026-09-17 02:05	44.71	OK	9572	2026-09-17 02:06	46.22	OK
9573	2026-09-17 02:07	45.26	OK	9574	2026-09-17 02:08	44.92	OK
9575	2026-09-17 02:09	45.08	OK	9576	2026-09-17 02:10	46.04	OK
9577	2026-09-17 02:11	47.39	OK	9578	2026-09-17 02:12	45.87	OK
9579	2026-09-17 02:13	45.78	OK	9580	2026-09-17 02:14	45.72	OK
9581	2026-09-17 02:15	44.51	OK	9582	2026-09-17 02:16	44.34	OK
9583	2026-09-17 02:17	44.43	OK	9584	2026-09-17 02:18	45.46	OK
9585	2026-09-17 02:19	47.05	OK	9586	2026-09-17 02:20	45.54	OK
9587	2026-09-17 02:21	45.80	OK	9588	2026-09-17 02:22	46.80	OK
9589	2026-09-17 02:23	45.98	OK	9590	2026-09-17 02:24	46.29	OK
9591	2026-09-17 02:25	47.05	OK	9592	2026-09-17 02:26	46.73	OK
9593	2026-09-17 02:27	44.81	OK	9594	2026-09-17 02:28	44.71	OK
9595	2026-09-17 02:29	47.62	OK	9596	2026-09-17 02:30	48.31	OK
9597	2026-09-17 02:31	43.87	OK	9598	2026-09-17 02:32	48.74	OK
9599	2026-09-17 02:33	46.51	OK	9600	2026-09-17 02:34	47.22	OK
9601	2026-09-17 02:35	46.36	OK	9602	2026-09-17 02:36	46.87	OK
9603	2026-09-17 02:37	46.21	OK	9604	2026-09-17 02:38	46.47	OK
9605	2026-09-17 02:39	48.71	OK	9606	2026-09-17 02:40	47.64	OK
9607	2026-09-17 02:41	44.05	OK	9608	2026-09-17 02:42	45.71	OK
9609	2026-09-17 02:43	47.14	OK	9610	2026-09-17 02:44	46.16	OK
9611	2026-09-17 02:45	47.51	OK	9612	2026-09-17 02:46	45.39	OK
9613	2026-09-17 02:47	46.17	OK	9614	2026-09-17 02:48	46.36	OK
9615	2026-09-17 02:49	47.32	OK	9616	2026-09-17 02:50	47.47	OK
9617	2026-09-17 02:51	47.36	OK	9618	2026-09-17 02:52	47.20	OK
9619	2026-09-17 02:53	47.28	OK	9620	2026-09-17 02:54	48.26	OK
9621	2026-09-17 02:55	45.77	OK	9622	2026-09-17 02:56	46.07	OK
9623	2026-09-17 02:57	48.35	OK	9624	2026-09-17 02:58	46.74	OK
9625	2026-09-17 02:59	46.29	OK	9626	2026-09-17 03:00	46.99	OK
9627	2026-09-17 03:01	49.07	OK	9628	2026-09-17 03:02	46.46	OK
9629	2026-09-17 03:03	45.16	OK	9630	2026-09-17 03:04	47.80	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9631	2026-09-17 03:05	47.07	OK	9632	2026-09-17 03:06	47.54	OK
9633	2026-09-17 03:07	47.89	OK	9634	2026-09-17 03:08	46.52	OK
9635	2026-09-17 03:09	46.18	OK	9636	2026-09-17 03:10	46.86	OK
9637	2026-09-17 03:11	47.63	OK	9638	2026-09-17 03:12	47.39	OK
9639	2026-09-17 03:13	47.72	OK	9640	2026-09-17 03:14	44.68	OK
9641	2026-09-17 03:15	45.31	OK	9642	2026-09-17 03:16	47.31	OK
9643	2026-09-17 03:17	45.04	OK	9644	2026-09-17 03:18	46.67	OK
9645	2026-09-17 03:19	47.34	OK	9646	2026-09-17 03:20	46.62	OK
9647	2026-09-17 03:21	45.14	OK	9648	2026-09-17 03:22	47.51	OK
9649	2026-09-17 03:23	46.04	OK	9650	2026-09-17 03:24	47.31	OK
9651	2026-09-17 03:25	46.90	OK	9652	2026-09-17 03:26	49.24	OK
9653	2026-09-17 03:27	47.28	OK	9654	2026-09-17 03:28	47.29	OK
9655	2026-09-17 03:29	47.73	OK	9656	2026-09-17 03:30	48.00	OK
9657	2026-09-17 03:31	48.44	OK	9658	2026-09-17 03:32	45.55	OK
9659	2026-09-17 03:33	45.72	OK	9660	2026-09-17 03:34	46.67	OK
9661	2026-09-17 03:35	46.85	OK	9662	2026-09-17 03:36	46.77	OK
9663	2026-09-17 03:37	47.81	OK	9664	2026-09-17 03:38	47.32	OK
9665	2026-09-17 03:39	47.01	OK	9666	2026-09-17 03:40	47.16	OK
9667	2026-09-17 03:41	47.92	OK	9668	2026-09-17 03:42	48.25	OK
9669	2026-09-17 03:43	46.75	OK	9670	2026-09-17 03:44	48.35	OK
9671	2026-09-17 03:45	47.29	OK	9672	2026-09-17 03:46	47.56	OK
9673	2026-09-17 03:47	45.23	OK	9674	2026-09-17 03:48	47.74	OK
9675	2026-09-17 03:49	46.67	OK	9676	2026-09-17 03:50	48.37	OK
9677	2026-09-17 03:51	45.89	OK	9678	2026-09-17 03:52	47.84	OK
9679	2026-09-17 03:53	46.17	OK	9680	2026-09-17 03:54	45.08	OK
9681	2026-09-17 03:55	47.74	OK	9682	2026-09-17 03:56	48.33	OK
9683	2026-09-17 03:57	47.94	OK	9684	2026-09-17 03:58	48.71	OK
9685	2026-09-17 03:59	48.08	OK	9686	2026-09-17 04:00	47.74	OK
9687	2026-09-17 04:01	47.23	OK	9688	2026-09-17 04:02	46.44	OK
9689	2026-09-17 04:03	47.63	OK	9690	2026-09-17 04:04	48.09	OK
9691	2026-09-17 04:05	47.29	OK	9692	2026-09-17 04:06	48.26	OK
9693	2026-09-17 04:07	47.05	OK	9694	2026-09-17 04:08	47.96	OK
9695	2026-09-17 04:09	48.96	OK	9696	2026-09-17 04:10	47.17	OK
9697	2026-09-17 04:11	48.44	OK	9698	2026-09-17 04:12	49.32	OK
9699	2026-09-17 04:13	48.80	OK	9700	2026-09-17 04:14	47.52	OK
9701	2026-09-17 04:15	48.40	OK	9702	2026-09-17 04:16	47.72	OK
9703	2026-09-17 04:17	49.03	OK	9704	2026-09-17 04:18	48.40	OK
9705	2026-09-17 04:19	47.03	OK	9706	2026-09-17 04:20	46.96	OK
9707	2026-09-17 04:21	47.71	OK	9708	2026-09-17 04:22	47.06	OK
9709	2026-09-17 04:23	48.67	OK	9710	2026-09-17 04:24	46.69	OK
9711	2026-09-17 04:25	48.19	OK	9712	2026-09-17 04:26	47.33	OK
9713	2026-09-17 04:27	48.65	OK	9714	2026-09-17 04:28	49.49	OK
9715	2026-09-17 04:29	49.01	OK	9716	2026-09-17 04:30	48.38	OK
9717	2026-09-17 04:31	47.98	OK	9718	2026-09-17 04:32	47.95	OK
9719	2026-09-17 04:33	45.83	OK	9720	2026-09-17 04:34	47.97	OK
9721	2026-09-17 04:35	51.03	OK	9722	2026-09-17 04:36	48.55	OK
9723	2026-09-17 04:37	48.18	OK	9724	2026-09-17 04:38	48.68	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9725	2026-09-17 04:39	47.20	OK	9726	2026-09-17 04:40	48.21	OK
9727	2026-09-17 04:41	50.17	OK	9728	2026-09-17 04:42	48.18	OK
9729	2026-09-17 04:43	45.84	OK	9730	2026-09-17 04:44	47.18	OK
9731	2026-09-17 04:45	48.22	OK	9732	2026-09-17 04:46	47.30	OK
9733	2026-09-17 04:47	47.85	OK	9734	2026-09-17 04:48	47.48	OK
9735	2026-09-17 04:49	47.21	OK	9736	2026-09-17 04:50	46.98	OK
9737	2026-09-17 04:51	46.11	OK	9738	2026-09-17 04:52	48.03	OK
9739	2026-09-17 04:53	48.93	OK	9740	2026-09-17 04:54	48.11	OK
9741	2026-09-17 04:55	48.86	OK	9742	2026-09-17 04:56	47.38	OK
9743	2026-09-17 04:57	47.05	OK	9744	2026-09-17 04:58	49.74	OK
9745	2026-09-17 04:59	49.64	OK	9746	2026-09-17 05:00	50.02	OK
9747	2026-09-17 05:01	48.76	OK	9748	2026-09-17 05:02	49.00	OK
9749	2026-09-17 05:03	47.09	OK	9750	2026-09-17 05:04	49.12	OK
9751	2026-09-17 05:05	48.16	OK	9752	2026-09-17 05:06	49.16	OK
9753	2026-09-17 05:07	49.36	OK	9754	2026-09-17 05:08	47.78	OK
9755	2026-09-17 05:09	50.35	OK	9756	2026-09-17 05:10	48.23	OK
9757	2026-09-17 05:11	47.67	OK	9758	2026-09-17 05:12	49.53	OK
9759	2026-09-17 05:13	49.51	OK	9760	2026-09-17 05:14	48.48	OK
9761	2026-09-17 05:15	48.95	OK	9762	2026-09-17 05:16	49.09	OK
9763	2026-09-17 05:17	48.04	OK	9764	2026-09-17 05:18	48.40	OK
9765	2026-09-17 05:19	48.13	OK	9766	2026-09-17 05:20	49.17	OK
9767	2026-09-17 05:21	49.28	OK	9768	2026-09-17 05:22	48.24	OK
9769	2026-09-17 05:23	50.46	OK	9770	2026-09-17 05:24	49.65	OK
9771	2026-09-17 05:25	49.18	OK	9772	2026-09-17 05:26	51.15	OK
9773	2026-09-17 05:27	49.32	OK	9774	2026-09-17 05:28	51.55	OK
9775	2026-09-17 05:29	48.80	OK	9776	2026-09-17 05:30	49.29	OK
9777	2026-09-17 05:31	50.19	OK	9778	2026-09-17 05:32	48.63	OK
9779	2026-09-17 05:33	49.02	OK	9780	2026-09-17 05:34	51.08	OK
9781	2026-09-17 05:35	50.68	OK	9782	2026-09-17 05:36	50.69	OK
9783	2026-09-17 05:37	49.75	OK	9784	2026-09-17 05:38	50.06	OK
9785	2026-09-17 05:39	48.56	OK	9786	2026-09-17 05:40	50.60	OK
9787	2026-09-17 05:41	50.57	OK	9788	2026-09-17 05:42	50.05	OK
9789	2026-09-17 05:43	49.61	OK	9790	2026-09-17 05:44	50.44	OK
9791	2026-09-17 05:45	50.17	OK	9792	2026-09-17 05:46	50.33	OK
9793	2026-09-17 05:47	49.75	OK	9794	2026-09-17 05:48	50.62	OK
9795	2026-09-17 05:49	50.55	OK	9796	2026-09-17 05:50	49.88	OK
9797	2026-09-17 05:51	48.48	OK	9798	2026-09-17 05:52	49.15	OK
9799	2026-09-17 05:53	51.25	OK	9800	2026-09-17 05:54	47.93	OK
9801	2026-09-17 05:55	48.96	OK	9802	2026-09-17 05:56	48.50	OK
9803	2026-09-17 05:57	48.81	OK	9804	2026-09-17 05:58	49.76	OK
9805	2026-09-17 05:59	49.52	OK	9806	2026-09-17 06:00	47.94	OK
9807	2026-09-17 06:01	49.70	OK	9808	2026-09-17 06:02	49.24	OK
9809	2026-09-17 06:03	49.81	OK	9810	2026-09-17 06:04	48.32	OK
9811	2026-09-17 06:05	48.45	OK	9812	2026-09-17 06:06	49.98	OK
9813	2026-09-17 06:07	48.61	OK	9814	2026-09-17 06:08	50.30	OK
9815	2026-09-17 06:09	48.89	OK	9816	2026-09-17 06:10	50.60	OK
9817	2026-09-17 06:11	50.87	OK	9818	2026-09-17 06:12	50.46	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9819	2026-09-17 06:13	49.75	OK	9820	2026-09-17 06:14	48.94	OK
9821	2026-09-17 06:15	49.54	OK	9822	2026-09-17 06:16	50.31	OK
9823	2026-09-17 06:17	50.58	OK	9824	2026-09-17 06:18	50.84	OK
9825	2026-09-17 06:19	51.14	OK	9826	2026-09-17 06:20	51.91	OK
9827	2026-09-17 06:21	52.30	OK	9828	2026-09-17 06:22	51.17	OK
9829	2026-09-17 06:23	50.10	OK	9830	2026-09-17 06:24	50.78	OK
9831	2026-09-17 06:25	51.60	OK	9832	2026-09-17 06:26	52.07	OK
9833	2026-09-17 06:27	50.78	OK	9834	2026-09-17 06:28	50.31	OK
9835	2026-09-17 06:29	51.00	OK	9836	2026-09-17 06:30	50.45	OK
9837	2026-09-17 06:31	47.89	OK	9838	2026-09-17 06:32	52.42	OK
9839	2026-09-17 06:33	51.97	OK	9840	2026-09-17 06:34	49.63	OK
9841	2026-09-17 06:35	50.62	OK	9842	2026-09-17 06:36	52.42	OK
9843	2026-09-17 06:37	49.42	OK	9844	2026-09-17 06:38	50.67	OK
9845	2026-09-17 06:39	49.28	OK	9846	2026-09-17 06:40	49.67	OK
9847	2026-09-17 06:41	52.35	OK	9848	2026-09-17 06:42	51.00	OK
9849	2026-09-17 06:43	51.36	OK	9850	2026-09-17 06:44	51.85	OK
9851	2026-09-17 06:45	50.06	OK	9852	2026-09-17 06:46	49.01	OK
9853	2026-09-17 06:47	50.73	OK	9854	2026-09-17 06:48	52.75	OK
9855	2026-09-17 06:49	51.50	OK	9856	2026-09-17 06:50	52.13	OK
9857	2026-09-17 06:51	49.91	OK	9858	2026-09-17 06:52	48.93	OK
9859	2026-09-17 06:53	52.00	OK	9860	2026-09-17 06:54	49.99	OK
9861	2026-09-17 06:55	53.05	OK	9862	2026-09-17 06:56	51.44	OK
9863	2026-09-17 06:57	51.07	OK	9864	2026-09-17 06:58	50.46	OK
9865	2026-09-17 06:59	49.55	OK	9866	2026-09-17 07:00	50.61	OK
9867	2026-09-17 07:01	51.12	OK	9868	2026-09-17 07:02	50.27	OK
9869	2026-09-17 07:03	51.13	OK	9870	2026-09-17 07:04	51.63	OK
9871	2026-09-17 07:05	51.27	OK	9872	2026-09-17 07:06	51.66	OK
9873	2026-09-17 07:07	52.67	OK	9874	2026-09-17 07:08	51.16	OK
9875	2026-09-17 07:09	50.86	OK	9876	2026-09-17 07:10	50.69	OK
9877	2026-09-17 07:11	51.31	OK	9878	2026-09-17 07:12	51.23	OK
9879	2026-09-17 07:13	53.36	OK	9880	2026-09-17 07:14	52.04	OK
9881	2026-09-17 07:15	51.04	OK	9882	2026-09-17 07:16	50.56	OK
9883	2026-09-17 07:17	52.01	OK	9884	2026-09-17 07:18	51.45	OK
9885	2026-09-17 07:19	49.37	OK	9886	2026-09-17 07:20	52.98	OK
9887	2026-09-17 07:21	50.57	OK	9888	2026-09-17 07:22	51.25	OK
9889	2026-09-17 07:23	51.49	OK	9890	2026-09-17 07:24	52.82	OK
9891	2026-09-17 07:25	52.38	OK	9892	2026-09-17 07:26	51.42	OK
9893	2026-09-17 07:27	52.45	OK	9894	2026-09-17 07:28	49.71	OK
9895	2026-09-17 07:29	51.28	OK	9896	2026-09-17 07:30	50.92	OK
9897	2026-09-17 07:31	52.36	OK	9898	2026-09-17 07:32	52.25	OK
9899	2026-09-17 07:33	52.61	OK	9900	2026-09-17 07:34	52.17	OK
9901	2026-09-17 07:35	51.81	OK	9902	2026-09-17 07:36	51.24	OK
9903	2026-09-17 07:37	52.84	OK	9904	2026-09-17 07:38	52.96	OK
9905	2026-09-17 07:39	51.93	OK	9906	2026-09-17 07:40	50.49	OK
9907	2026-09-17 07:41	51.08	OK	9908	2026-09-17 07:42	53.60	OK
9909	2026-09-17 07:43	50.49	OK	9910	2026-09-17 07:44	50.82	OK
9911	2026-09-17 07:45	53.33	OK	9912	2026-09-17 07:46	52.86	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9913	2026-09-17 07:47	52.13	OK	9914	2026-09-17 07:48	51.34	OK
9915	2026-09-17 07:49	51.27	OK	9916	2026-09-17 07:50	51.83	OK
9917	2026-09-17 07:51	53.58	OK	9918	2026-09-17 07:52	50.19	OK
9919	2026-09-17 07:53	52.43	OK	9920	2026-09-17 07:54	52.43	OK
9921	2026-09-17 07:55	52.94	OK	9922	2026-09-17 07:56	52.03	OK
9923	2026-09-17 07:57	54.19	OK	9924	2026-09-17 07:58	52.09	OK
9925	2026-09-17 07:59	53.17	OK	9926	2026-09-17 08:00	51.98	OK
9927	2026-09-17 08:01	52.27	OK	9928	2026-09-17 08:02	51.70	OK
9929	2026-09-17 08:03	53.03	OK	9930	2026-09-17 08:04	53.40	OK
9931	2026-09-17 08:05	52.72	OK	9932	2026-09-17 08:06	51.38	OK
9933	2026-09-17 08:07	53.90	OK	9934	2026-09-17 08:08	52.45	OK
9935	2026-09-17 08:09	51.94	OK	9936	2026-09-17 08:10	55.32	OK
9937	2026-09-17 08:11	51.79	OK	9938	2026-09-17 08:12	53.28	OK
9939	2026-09-17 08:13	52.39	OK	9940	2026-09-17 08:14	54.94	OK
9941	2026-09-17 08:15	50.91	OK	9942	2026-09-17 08:16	53.31	OK
9943	2026-09-17 08:17	54.42	OK	9944	2026-09-17 08:18	53.38	OK
9945	2026-09-17 08:19	55.05	OK	9946	2026-09-17 08:20	51.68	OK
9947	2026-09-17 08:21	51.98	OK	9948	2026-09-17 08:22	51.93	OK
9949	2026-09-17 08:23	54.54	OK	9950	2026-09-17 08:24	50.79	OK
9951	2026-09-17 08:25	52.53	OK	9952	2026-09-17 08:26	53.21	OK
9953	2026-09-17 08:27	52.01	OK	9954	2026-09-17 08:28	53.06	OK
9955	2026-09-17 08:29	53.86	OK	9956	2026-09-17 08:30	53.55	OK
9957	2026-09-17 08:31	51.83	OK	9958	2026-09-17 08:32	51.55	OK
9959	2026-09-17 08:33	51.09	OK	9960	2026-09-17 08:34	52.05	OK
9961	2026-09-17 08:35	52.03	OK	9962	2026-09-17 08:36	53.02	OK
9963	2026-09-17 08:37	54.46	OK	9964	2026-09-17 08:38	53.82	OK
9965	2026-09-17 08:39	54.39	OK	9966	2026-09-17 08:40	53.22	OK
9967	2026-09-17 08:41	52.82	OK	9968	2026-09-17 08:42	53.77	OK
9969	2026-09-17 08:43	51.19	OK	9970	2026-09-17 08:44	52.52	OK
9971	2026-09-17 08:45	54.48	OK	9972	2026-09-17 08:46	53.90	OK
9973	2026-09-17 08:47	53.32	OK	9974	2026-09-17 08:48	53.71	OK
9975	2026-09-17 08:49	52.58	OK	9976	2026-09-17 08:50	53.70	OK
9977	2026-09-17 08:51	52.59	OK	9978	2026-09-17 08:52	51.42	OK
9979	2026-09-17 08:53	52.87	OK	9980	2026-09-17 08:54	54.87	OK
9981	2026-09-17 08:55	53.15	OK	9982	2026-09-17 08:56	52.74	OK
9983	2026-09-17 08:57	53.92	OK	9984	2026-09-17 08:58	54.07	OK
9985	2026-09-17 08:59	53.50	OK	9986	2026-09-17 09:00	51.87	OK
9987	2026-09-17 09:01	53.28	OK	9988	2026-09-17 09:02	53.02	OK
9989	2026-09-17 09:03	52.66	OK	9990	2026-09-17 09:04	54.54	OK
9991	2026-09-17 09:05	52.42	OK	9992	2026-09-17 09:06	54.77	OK
9993	2026-09-17 09:07	54.42	OK	9994	2026-09-17 09:08	51.51	OK
9995	2026-09-17 09:09	52.97	OK	9996	2026-09-17 09:10	53.80	OK
9997	2026-09-17 09:11	53.71	OK	9998	2026-09-17 09:12	52.60	OK
9999	2026-09-17 09:13	52.12	OK	10000	2026-09-17 09:14	55.14	OK
10001	2026-09-17 09:15	53.12	OK	10002	2026-09-17 09:16	53.31	OK
1000	2026-09-17 09:17	52.73	OK	1000	2026-09-17 09:18	52.57	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
10005	2026-09-17 09:19	53.14	OK	10006	2026-09-17 09:20	53.61	OK
10007	2026-09-17 09:21	52.05	OK	10008	2026-09-17 09:22	53.94	OK
10009	2026-09-17 09:23	54.85	OK	10010	2026-09-17 09:24	52.80	OK
10011	2026-09-17 09:25	53.29	OK	10012	2026-09-17 09:26	54.48	OK
10013	2026-09-17 09:27	53.26	OK	10014	2026-09-17 09:28	54.50	OK
10015	2026-09-17 09:29	54.26	OK	10016	2026-09-17 09:30	52.80	OK
10017	2026-09-17 09:31	54.93	OK	10018	2026-09-17 09:32	51.61	OK
10019	2026-09-17 09:33	54.72	OK	10020	2026-09-17 09:34	52.27	OK
10021	2026-09-17 09:35	55.79	OK	10022	2026-09-17 09:36	53.37	OK
10023	2026-09-17 09:37	53.31	OK	10024	2026-09-17 09:38	53.33	OK
10025	2026-09-17 09:39	52.87	OK	10026	2026-09-17 09:40	54.97	OK
10027	2026-09-17 09:41	54.06	OK	10028	2026-09-17 09:42	54.17	OK
10029	2026-09-17 09:43	53.88	OK	10030	2026-09-17 09:44	52.97	OK
10031	2026-09-17 09:45	52.71	OK	10032	2026-09-17 09:46	53.71	OK
10033	2026-09-17 09:47	53.07	OK	10034	2026-09-17 09:48	55.06	OK
10035	2026-09-17 09:49	53.75	OK	10036	2026-09-17 09:50	54.67	OK
10037	2026-09-17 09:51	55.45	OK	10038	2026-09-17 09:52	53.79	OK
10039	2026-09-17 09:53	54.38	OK	10040	2026-09-17 09:54	53.85	OK
10041	2026-09-17 09:55	52.17	OK	10042	2026-09-17 09:56	52.34	OK
10043	2026-09-17 09:57	53.42	OK	10044	2026-09-17 09:58	52.17	OK
10045	2026-09-17 09:59	54.11	OK	10046	2026-09-17 10:00	53.27	OK
10047	2026-09-17 10:01	54.31	OK	10048	2026-09-17 10:02	52.37	OK
10049	2026-09-17 10:03	55.71	OK	10050	2026-09-17 10:04	52.51	OK
10051	2026-09-17 10:05	52.61	OK	10052	2026-09-17 10:06	52.37	OK
10053	2026-09-17 10:07	51.89	OK	10054	2026-09-17 10:08	54.11	OK
10055	2026-09-17 10:09	55.32	OK	10056	2026-09-17 10:10	53.21	OK
10057	2026-09-17 10:11	53.94	OK	10058	2026-09-17 10:12	55.95	OK
10059	2026-09-17 10:13	54.66	OK	10060	2026-09-17 10:14	53.48	OK
10061	2026-09-17 10:15	53.06	OK	10062	2026-09-17 10:16	53.04	OK
1006	2026-09-17 10:17	51.45	OK	1006	2026-09-17 10:18	54.67	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
10065	2026-09-17 10:19	54.38	OK	10066	2026-09-17 10:20	52.29	OK
10067	2026-09-17 10:21	54.44	OK	10068	2026-09-17 10:22	54.69	OK
10069	2026-09-17 10:23	55.23	OK	10070	2026-09-17 10:24	54.39	OK
10071	2026-09-17 10:25	53.19	OK	10072	2026-09-17 10:26	55.89	OK
10073	2026-09-17 10:27	53.47	OK	10074	2026-09-17 10:28	53.69	OK
10075	2026-09-17 10:29	52.56	OK	10076	2026-09-17 10:30	55.36	OK
10077	2026-09-17 10:31	54.51	OK	10078	2026-09-17 10:32	54.79	OK
10079	2026-09-17 10:33	53.54	OK	10080	2026-09-17 10:34	54.46	OK
10081	2026-09-17 10:35	53.52	OK	10082	2026-09-17 10:36	55.73	OK
10083	2026-09-17 10:37	52.23	OK	10084	2026-09-17 10:38	55.98	OK
10085	2026-09-17 10:39	55.07	OK	10086	2026-09-17 10:40	52.85	OK
10087	2026-09-17 10:41	54.16	OK	10088	2026-09-17 10:42	53.64	OK
10089	2026-09-17 10:43	53.56	OK	10090	2026-09-17 10:44	56.62	OK
10091	2026-09-17 10:45	52.19	OK	10092	2026-09-17 10:46	51.77	OK
10093	2026-09-17 10:47	55.06	OK	10094	2026-09-17 10:48	54.18	OK
10095	2026-09-17 10:49	54.68	OK	10096	2026-09-17 10:50	55.60	OK
10097	2026-09-17 10:51	56.79	OK	10098	2026-09-17 10:52	54.10	OK
10099	2026-09-17 10:53	53.45	OK	10100	2026-09-17 10:54	55.14	OK
10101	2026-09-17 10:55	56.47	OK	10102	2026-09-17 10:56	56.73	OK
10103	2026-09-17 10:57	53.96	OK	10104	2026-09-17 10:58	54.07	OK
10105	2026-09-17 10:59	55.10	OK	10106	2026-09-17 11:00	53.46	OK
10107	2026-09-17 11:01	53.15	OK	10108	2026-09-17 11:02	54.86	OK
10109	2026-09-17 11:03	55.73	OK	10110	2026-09-17 11:04	52.58	OK
10111	2026-09-17 11:05	52.89	OK	10112	2026-09-17 11:06	53.29	OK
10113	2026-09-17 11:07	53.19	OK	10114	2026-09-17 11:08	55.10	OK
10115	2026-09-17 11:09	52.03	OK	10116	2026-09-17 11:10	54.51	OK
10117	2026-09-17 11:11	55.11	OK	10118	2026-09-17 11:12	53.80	OK
10119	2026-09-17 11:13	54.31	OK	10120	2026-09-17 11:14	53.57	OK
10121	2026-09-17 11:15	53.56	OK	10122	2026-09-17 11:16	53.16	OK
1012	2026-09-17 11:17	53.90	OK	1012	2026-09-17 11:18	53.69	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
10125	2026-09-17 11:19	53.49	OK	10126	2026-09-17 11:20	55.97	OK
10127	2026-09-17 11:21	55.46	OK	10128	2026-09-17 11:22	53.34	OK
10129	2026-09-17 11:23	55.23	OK	10130	2026-09-17 11:24	55.05	OK
10131	2026-09-17 11:25	55.90	OK	10132	2026-09-17 11:26	53.56	OK
10133	2026-09-17 11:27	54.27	OK	10134	2026-09-17 11:28	56.01	OK
10135	2026-09-17 11:29	51.80	OK	10136	2026-09-17 11:30	55.54	OK
10137	2026-09-17 11:31	52.67	OK	10138	2026-09-17 11:32	53.92	OK
10139	2026-09-17 11:33	53.13	OK	10140	2026-09-17 11:34	55.33	OK
10141	2026-09-17 11:35	54.89	OK	10142	2026-09-17 11:36	52.93	OK
10143	2026-09-17 11:37	55.24	OK	10144	2026-09-17 11:38	55.87	OK
10145	2026-09-17 11:39	51.97	OK	10146	2026-09-17 11:40	53.19	OK
10147	2026-09-17 11:41	54.15	OK	10148	2026-09-17 11:42	53.80	OK
10149	2026-09-17 11:43	53.68	OK	10150	2026-09-17 11:44	52.92	OK
10151	2026-09-17 11:45	51.95	OK	10152	2026-09-17 11:46	52.06	OK
10153	2026-09-17 11:47	53.32	OK	10154	2026-09-17 11:48	54.26	OK
10155	2026-09-17 11:49	55.11	OK	10156	2026-09-17 11:50	53.23	OK
10157	2026-09-17 11:51	52.83	OK	10158	2026-09-17 11:52	54.63	OK
10159	2026-09-17 11:53	54.63	OK	10160	2026-09-17 11:54	55.65	OK
10161	2026-09-17 11:55	52.33	OK	10162	2026-09-17 11:56	55.49	OK
10163	2026-09-17 11:57	53.87	OK	10164	2026-09-17 11:58	55.02	OK
10165	2026-09-17 11:59	55.61	OK	10166	2026-09-17 12:00	55.76	OK
10167	2026-09-17 12:01	51.67	OK	10168	2026-09-17 12:02	53.96	OK
10169	2026-09-17 12:03	53.49	OK	10170	2026-09-17 12:04	53.82	OK
10171	2026-09-17 12:05	54.89	OK	10172	2026-09-17 12:06	55.39	OK
10173	2026-09-17 12:07	54.64	OK	10174	2026-09-17 12:08	54.91	OK
10175	2026-09-17 12:09	54.56	OK	10176	2026-09-17 12:10	53.90	OK
10177	2026-09-17 12:11	54.84	OK	10178	2026-09-17 12:12	53.95	OK
10179	2026-09-17 12:13	53.36	OK	10180	2026-09-17 12:14	54.94	OK
10181	2026-09-17 12:15	54.34	OK	10182	2026-09-17 12:16	52.98	OK
1018	2026-09-17 12:17	53.84	OK	1018	2026-09-17 12:18	52.26	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
10185	2026-09-17 12:19	54.71	OK	10186	2026-09-17 12:20	51.84	OK
10187	2026-09-17 12:21	54.95	OK	10188	2026-09-17 12:22	54.72	OK
10189	2026-09-17 12:23	53.76	OK	10190	2026-09-17 12:24	55.38	OK
10191	2026-09-17 12:25	55.18	OK	10192	2026-09-17 12:26	53.56	OK
10193	2026-09-17 12:27	54.22	OK	10194	2026-09-17 12:28	53.97	OK
10195	2026-09-17 12:29	53.61	OK	10196	2026-09-17 12:30	55.32	OK
10197	2026-09-17 12:31	55.26	OK	10198	2026-09-17 12:32	53.25	OK
10199	2026-09-17 12:33	52.77	OK	10200	2026-09-17 12:34	55.35	OK
10201	2026-09-17 12:35	54.81	OK	10202	2026-09-17 12:36	55.06	OK
10203	2026-09-17 12:37	54.59	OK	10204	2026-09-17 12:38	55.80	OK
10205	2026-09-17 12:39	53.68	OK	10206	2026-09-17 12:40	52.74	OK
10207	2026-09-17 12:41	53.53	OK	10208	2026-09-17 12:42	55.39	OK
10209	2026-09-17 12:43	52.56	OK	10210	2026-09-17 12:44	55.08	OK
10211	2026-09-17 12:45	51.49	OK	10212	2026-09-17 12:46	52.57	OK
10213	2026-09-17 12:47	53.79	OK	10214	2026-09-17 12:48	55.27	OK
10215	2026-09-17 12:49	54.18	OK	10216	2026-09-17 12:50	53.23	OK
10217	2026-09-17 12:51	52.95	OK	10218	2026-09-17 12:52	52.17	OK
10219	2026-09-17 12:53	55.03	OK	10220	2026-09-17 12:54	53.20	OK
10221	2026-09-17 12:55	54.92	OK	10222	2026-09-17 12:56	54.76	OK
10223	2026-09-17 12:57	54.08	OK	10224	2026-09-17 12:58	53.73	OK
10225	2026-09-17 12:59	51.47	OK	10226	2026-09-17 13:00	54.29	OK
10227	2026-09-17 13:01	53.82	OK	10228	2026-09-17 13:02	52.89	OK
10229	2026-09-17 13:03	53.27	OK	10230	2026-09-17 13:04	54.09	OK
10231	2026-09-17 13:05	51.35	OK	10232	2026-09-17 13:06	52.31	OK
10233	2026-09-17 13:07	52.86	OK	10234	2026-09-17 13:08	54.06	OK
10235	2026-09-17 13:09	54.55	OK	10236	2026-09-17 13:10	52.07	OK
10237	2026-09-17 13:11	54.96	OK	10238	2026-09-17 13:12	51.90	OK
10239	2026-09-17 13:13	51.30	OK	10240	2026-09-17 13:14	55.39	OK
10241	2026-09-17 13:15	53.27	OK	10242	2026-09-17 13:16	52.84	OK
1024	2026-09-17 13:17	54.80	OK	1024	2026-09-17 13:18	53.13	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
10245	2026-09-17 13:19	52.04	OK	10246	2026-09-17 13:20	55.16	OK
10247	2026-09-17 13:21	52.60	OK	10248	2026-09-17 13:22	53.85	OK
10249	2026-09-17 13:23	52.27	OK	10250	2026-09-17 13:24	52.61	OK
10251	2026-09-17 13:25	51.69	OK	10252	2026-09-17 13:26	54.38	OK
10253	2026-09-17 13:27	54.58	OK	10254	2026-09-17 13:28	53.06	OK
10255	2026-09-17 13:29	52.68	OK	10256	2026-09-17 13:30	54.26	OK
10257	2026-09-17 13:31	54.43	OK	10258	2026-09-17 13:32	52.88	OK
10259	2026-09-17 13:33	52.92	OK	10260	2026-09-17 13:34	55.22	OK
10261	2026-09-17 13:35	53.76	OK	10262	2026-09-17 13:36	54.63	OK
10263	2026-09-17 13:37	53.70	OK	10264	2026-09-17 13:38	51.23	OK
10265	2026-09-17 13:39	52.11	OK	10266	2026-09-17 13:40	53.56	OK
10267	2026-09-17 13:41	54.38	OK	10268	2026-09-17 13:42	53.59	OK
10269	2026-09-17 13:43	54.50	OK	10270	2026-09-17 13:44	53.92	OK
10271	2026-09-17 13:45	53.27	OK	10272	2026-09-17 13:46	54.21	OK
10273	2026-09-17 13:47	52.46	OK	10274	2026-09-17 13:48	54.54	OK
10275	2026-09-17 13:49	53.89	OK	10276	2026-09-17 13:50	53.38	OK
10277	2026-09-17 13:51	53.40	OK	10278	2026-09-17 13:52	52.15	OK
10279	2026-09-17 13:53	53.03	OK	10280	2026-09-17 13:54	53.82	OK
10281	2026-09-17 13:55	52.18	OK	10282	2026-09-17 13:56	53.89	OK
10283	2026-09-17 13:57	53.25	OK	10284	2026-09-17 13:58	52.67	OK
10285	2026-09-17 13:59	54.04	OK	10286	2026-09-17 14:00	54.12	OK
10287	2026-09-17 14:01	53.02	OK	10288	2026-09-17 14:02	54.15	OK
10289	2026-09-17 14:03	52.03	OK	10290	2026-09-17 14:04	53.34	OK
10291	2026-09-17 14:05	52.35	OK	10292	2026-09-17 14:06	52.90	OK
10293	2026-09-17 14:07	54.02	OK	10294	2026-09-17 14:08	54.26	OK
10295	2026-09-17 14:09	52.15	OK	10296	2026-09-17 14:10	53.14	OK
10297	2026-09-17 14:11	54.00	OK	10298	2026-09-17 14:12	53.14	OK
10299	2026-09-17 14:13	53.98	OK	10300	2026-09-17 14:14	54.09	OK
10301	2026-09-17 14:15	54.23	OK	10302	2026-09-17 14:16	52.61	OK
10303	2026-09-17 14:17	52.50	OK	10303	2026-09-17 14:18	51.70	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
10305	2026-09-17 14:19	52.96	OK	10306	2026-09-17 14:20	54.46	OK
10307	2026-09-17 14:21	52.57	OK	10308	2026-09-17 14:22	51.96	OK
10309	2026-09-17 14:23	54.34	OK	10310	2026-09-17 14:24	52.07	OK
10311	2026-09-17 14:25	52.26	OK	10312	2026-09-17 14:26	52.76	OK
10313	2026-09-17 14:27	54.10	OK	10314	2026-09-17 14:28	50.94	OK
10315	2026-09-17 14:29	52.57	OK	10316	2026-09-17 14:30	52.66	OK
10317	2026-09-17 14:31	53.43	OK	10318	2026-09-17 14:32	54.31	OK
10319	2026-09-17 14:33	54.02	OK	10320	2026-09-17 14:34	51.66	OK
10321	2026-09-17 14:35	52.62	OK	10322	2026-09-17 14:36	52.81	OK
10323	2026-09-17 14:37	52.13	OK	10324	2026-09-17 14:38	51.27	OK
10325	2026-09-17 14:39	52.82	OK	10326	2026-09-17 14:40	53.95	OK
10327	2026-09-17 14:41	51.48	OK	10328	2026-09-17 14:42	52.24	OK
10329	2026-09-17 14:43	51.77	OK	10330	2026-09-17 14:44	50.95	OK
10331	2026-09-17 14:45	52.93	OK	10332	2026-09-17 14:46	52.07	OK
10333	2026-09-17 14:47	53.82	OK	10334	2026-09-17 14:48	53.12	OK
10335	2026-09-17 14:49	51.47	OK	10336	2026-09-17 14:50	53.38	OK
10337	2026-09-17 14:51	49.97	OK	10338	2026-09-17 14:52	52.31	OK
10339	2026-09-17 14:53	51.20	OK	10340	2026-09-17 14:54	52.48	OK
10341	2026-09-17 14:55	51.93	OK	10342	2026-09-17 14:56	51.44	OK
10343	2026-09-17 14:57	52.93	OK	10344	2026-09-17 14:58	52.39	OK
10345	2026-09-17 14:59	53.06	OK	10346	2026-09-17 15:00	52.29	OK
10347	2026-09-17 15:01	51.77	OK	10348	2026-09-17 15:02	52.39	OK
10349	2026-09-17 15:03	51.75	OK	10350	2026-09-17 15:04	51.28	OK
10351	2026-09-17 15:05	51.74	OK	10352	2026-09-17 15:06	52.34	OK
10353	2026-09-17 15:07	53.28	OK	10354	2026-09-17 15:08	54.20	OK
10355	2026-09-17 15:09	53.15	OK	10356	2026-09-17 15:10	52.17	OK
10357	2026-09-17 15:11	51.65	OK	10358	2026-09-17 15:12	51.55	OK
10359	2026-09-17 15:13	51.72	OK	10360	2026-09-17 15:14	53.93	OK
10361	2026-09-17 15:15	51.15	OK	10362	2026-09-17 15:16	53.50	OK
1036	2026-09-17 15:17	51.02	OK	1036	2026-09-17 15:18	51.46	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
10365	2026-09-17 15:19	51.71	OK	10366	2026-09-17 15:20	51.82	OK
10367	2026-09-17 15:21	51.90	OK	10368	2026-09-17 15:22	50.04	OK
10369	2026-09-17 15:23	52.21	OK	10370	2026-09-17 15:24	50.07	OK
10371	2026-09-17 15:25	52.59	OK	10372	2026-09-17 15:26	52.67	OK
10373	2026-09-17 15:27	52.13	OK	10374	2026-09-17 15:28	51.35	OK
10375	2026-09-17 15:29	52.66	OK	10376	2026-09-17 15:30	51.31	OK
10377	2026-09-17 15:31	51.42	OK	10378	2026-09-17 15:32	52.15	OK
10379	2026-09-17 15:33	51.68	OK	10380	2026-09-17 15:34	50.36	OK
10381	2026-09-17 15:35	53.62	OK	10382	2026-09-17 15:36	52.36	OK
10383	2026-09-17 15:37	51.36	OK	10384	2026-09-17 15:38	51.02	OK
10385	2026-09-17 15:39	51.37	OK	10386	2026-09-17 15:40	49.74	OK
10387	2026-09-17 15:41	50.59	OK	10388	2026-09-17 15:42	49.80	OK
10389	2026-09-17 15:43	51.55	OK	10390	2026-09-17 15:44	50.86	OK
10391	2026-09-17 15:45	51.00	OK	10392	2026-09-17 15:46	53.16	OK
10393	2026-09-17 15:47	52.38	OK	10394	2026-09-17 15:48	52.75	OK
10395	2026-09-17 15:49	53.77	OK	10396	2026-09-17 15:50	49.49	OK
10397	2026-09-17 15:51	53.29	OK	10398	2026-09-17 15:52	50.99	OK
10399	2026-09-17 15:53	51.52	OK	10400	2026-09-17 15:54	52.94	OK
10401	2026-09-17 15:55	52.87	OK	10402	2026-09-17 15:56	49.41	OK
10403	2026-09-17 15:57	52.52	OK	10404	2026-09-17 15:58	50.23	OK
10405	2026-09-17 15:59	50.45	OK	10406	2026-09-17 16:00	51.58	OK
10407	2026-09-17 16:01	51.50	OK	10408	2026-09-17 16:02	50.09	OK
10409	2026-09-17 16:03	51.12	OK	10410	2026-09-17 16:04	50.52	OK
10411	2026-09-17 16:05	53.71	OK	10412	2026-09-17 16:06	51.58	OK
10413	2026-09-17 16:07	51.41	OK	10414	2026-09-17 16:08	50.52	OK
10415	2026-09-17 16:09	51.38	OK	10416	2026-09-17 16:10	50.69	OK
10417	2026-09-17 16:11	50.95	OK	10418	2026-09-17 16:12	53.44	OK
10419	2026-09-17 16:13	50.05	OK	10420	2026-09-17 16:14	51.59	OK
10421	2026-09-17 16:15	51.36	OK	10422	2026-09-17 16:16	51.96	OK
1042	2026-09-17 16:17	50.32	OK	1042	2026-09-17 16:18	51.56	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
10425	2026-09-17 16:19	52.41	OK	10426	2026-09-17 16:20	50.02	OK
10427	2026-09-17 16:21	52.30	OK	10428	2026-09-17 16:22	53.09	OK
10429	2026-09-17 16:23	49.53	OK	10430	2026-09-17 16:24	50.32	OK
10431	2026-09-17 16:25	50.43	OK	10432	2026-09-17 16:26	51.00	OK
10433	2026-09-17 16:27	50.73	OK	10434	2026-09-17 16:28	51.09	OK
10435	2026-09-17 16:29	49.72	OK	10436	2026-09-17 16:30	50.83	OK
10437	2026-09-17 16:31	50.11	OK	10438	2026-09-17 16:32	51.25	OK
10439	2026-09-17 16:33	51.77	OK	10440	2026-09-17 16:34	50.24	OK
10441	2026-09-17 16:35	49.96	OK	10442	2026-09-17 16:36	50.86	OK
10443	2026-09-17 16:37	51.21	OK	10444	2026-09-17 16:38	50.88	OK
10445	2026-09-17 16:39	52.17	OK	10446	2026-09-17 16:40	50.26	OK
10447	2026-09-17 16:41	51.24	OK	10448	2026-09-17 16:42	50.08	OK
10449	2026-09-17 16:43	51.20	OK	10450	2026-09-17 16:44	50.07	OK
10451	2026-09-17 16:45	49.85	OK	10452	2026-09-17 16:46	51.03	OK
10453	2026-09-17 16:47	48.36	OK	10454	2026-09-17 16:48	49.38	OK
10455	2026-09-17 16:49	49.09	OK	10456	2026-09-17 16:50	48.81	OK
10457	2026-09-17 16:51	50.58	OK	10458	2026-09-17 16:52	48.41	OK
10459	2026-09-17 16:53	51.76	OK	10460	2026-09-17 16:54	51.36	OK
10461	2026-09-17 16:55	47.94	OK	10462	2026-09-17 16:56	51.44	OK
10463	2026-09-17 16:57	50.09	OK	10464	2026-09-17 16:58	48.27	OK
10465	2026-09-17 16:59	49.67	OK	10466	2026-09-17 17:00	50.49	OK
10467	2026-09-17 17:01	48.22	OK	10468	2026-09-17 17:02	49.40	OK
10469	2026-09-17 17:03	49.30	OK	10470	2026-09-17 17:04	49.84	OK
10471	2026-09-17 17:05	50.51	OK	10472	2026-09-17 17:06	48.74	OK
10473	2026-09-17 17:07	49.39	OK	10474	2026-09-17 17:08	50.28	OK
10475	2026-09-17 17:09	49.04	OK	10476	2026-09-17 17:10	51.24	OK
10477	2026-09-17 17:11	49.75	OK	10478	2026-09-17 17:12	49.26	OK
10479	2026-09-17 17:13	49.02	OK	10480	2026-09-17 17:14	50.23	OK
10481	2026-09-17 17:15	49.67	OK	10482	2026-09-17 17:16	48.40	OK
1048	2026-09-17 17:17	49.57	OK	1048	2026-09-17 17:18	51.26	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
10485	2026-09-17 17:19	49.94	OK	10486	2026-09-17 17:20	49.15	OK
10487	2026-09-17 17:21	49.47	OK	10488	2026-09-17 17:22	48.30	OK
10489	2026-09-17 17:23	48.70	OK	10490	2026-09-17 17:24	50.92	OK
10491	2026-09-17 17:25	49.06	OK	10492	2026-09-17 17:26	49.02	OK
10493	2026-09-17 17:27	49.00	OK	10494	2026-09-17 17:28	47.99	OK
10495	2026-09-17 17:29	49.23	OK	10496	2026-09-17 17:30	51.01	OK
10497	2026-09-17 17:31	48.47	OK	10498	2026-09-17 17:32	49.48	OK
10499	2026-09-17 17:33	50.35	OK	10500	2026-09-17 17:34	47.11	OK
10501	2026-09-17 17:35	50.63	OK	10502	2026-09-17 17:36	49.72	OK
10503	2026-09-17 17:37	47.72	OK	10504	2026-09-17 17:38	48.46	OK
10505	2026-09-17 17:39	49.88	OK	10506	2026-09-17 17:40	49.13	OK
10507	2026-09-17 17:41	49.41	OK	10508	2026-09-17 17:42	48.79	OK
10509	2026-09-17 17:43	50.45	OK	10510	2026-09-17 17:44	50.24	OK
10511	2026-09-17 17:45	48.93	OK	10512	2026-09-17 17:46	47.77	OK
10513	2026-09-17 17:47	48.20	OK	10514	2026-09-17 17:48	48.64	OK
10515	2026-09-17 17:49	47.68	OK	10516	2026-09-17 17:50	48.60	OK
10517	2026-09-17 17:51	51.07	OK	10518	2026-09-17 17:52	51.10	OK
10519	2026-09-17 17:53	48.68	OK	10520	2026-09-17 17:54	48.85	OK
10521	2026-09-17 17:55	49.25	OK	10522	2026-09-17 17:56	48.97	OK
10523	2026-09-17 17:57	50.86	OK	10524	2026-09-17 17:58	48.79	OK
10525	2026-09-17 17:59	47.78	OK	10526	2026-09-17 18:00	48.87	OK
10527	2026-09-17 18:01	49.20	OK	10528	2026-09-17 18:02	48.29	OK
10529	2026-09-17 18:03	47.05	OK	10530	2026-09-17 18:04	49.44	OK
10531	2026-09-17 18:05	47.60	OK	10532	2026-09-17 18:06	48.17	OK
10533	2026-09-17 18:07	49.53	OK	10534	2026-09-17 18:08	48.81	OK
10535	2026-09-17 18:09	49.02	OK	10536	2026-09-17 18:10	48.46	OK
10537	2026-09-17 18:11	50.82	OK	10538	2026-09-17 18:12	50.07	OK
10539	2026-09-17 18:13	48.44	OK	10540	2026-09-17 18:14	50.35	OK
10541	2026-09-17 18:15	47.48	OK	10542	2026-09-17 18:16	47.46	OK
1054	2026-09-17 18:17	47.67	OK	1054	2026-09-17 18:18	48.88	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
10545	2026-09-17 18:19	48.19	OK	10546	2026-09-17 18:20	49.10	OK
10547	2026-09-17 18:21	49.68	OK	10548	2026-09-17 18:22	47.58	OK
10549	2026-09-17 18:23	49.98	OK	10550	2026-09-17 18:24	47.61	OK
10551	2026-09-17 18:25	46.69	OK	10552	2026-09-17 18:26	46.52	OK
10553	2026-09-17 18:27	48.48	OK	10554	2026-09-17 18:28	49.18	OK
10555	2026-09-17 18:29	46.94	OK	10556	2026-09-17 18:30	48.04	OK
10557	2026-09-17 18:31	49.99	OK	10558	2026-09-17 18:32	46.79	OK
10559	2026-09-17 18:33	48.41	OK	10560	2026-09-17 18:34	50.46	OK
10561	2026-09-17 18:35	47.04	OK	10562	2026-09-17 18:36	48.59	OK
10563	2026-09-17 18:37	47.08	OK	10564	2026-09-17 18:38	47.90	OK
10565	2026-09-17 18:39	48.00	OK	10566	2026-09-17 18:40	46.06	OK
10567	2026-09-17 18:41	47.69	OK	10568	2026-09-17 18:42	49.65	OK
10569	2026-09-17 18:43	47.69	OK	10570	2026-09-17 18:44	49.09	OK
10571	2026-09-17 18:45	47.24	OK	10572	2026-09-17 18:46	49.66	OK
10573	2026-09-17 18:47	47.43	OK	10574	2026-09-17 18:48	48.17	OK
10575	2026-09-17 18:49	46.23	OK	10576	2026-09-17 18:50	46.81	OK
10577	2026-09-17 18:51	46.29	OK	10578	2026-09-17 18:52	48.80	OK
10579	2026-09-17 18:53	47.38	OK	10580	2026-09-17 18:54	46.39	OK
10581	2026-09-17 18:55	48.70	OK	10582	2026-09-17 18:56	48.72	OK
10583	2026-09-17 18:57	48.51	OK	10584	2026-09-17 18:58	45.52	OK
10585	2026-09-17 18:59	45.46	OK	10586	2026-09-17 19:00	46.72	OK
10587	2026-09-17 19:01	45.30	OK	10588	2026-09-17 19:02	50.30	OK
10589	2026-09-17 19:03	47.21	OK	10590	2026-09-17 19:04	46.17	OK
10591	2026-09-17 19:05	48.05	OK	10592	2026-09-17 19:06	49.14	OK
10593	2026-09-17 19:07	46.81	OK	10594	2026-09-17 19:08	45.15	OK
10595	2026-09-17 19:09	47.55	OK	10596	2026-09-17 19:10	48.37	OK
10597	2026-09-17 19:11	45.60	OK	10598	2026-09-17 19:12	48.44	OK
10599	2026-09-17 19:13	48.87	OK	10600	2026-09-17 19:14	47.64	OK
10601	2026-09-17 19:15	48.45	OK	10602	2026-09-17 19:16	48.60	OK
1060	2026-09-17 19:17	47.25	OK	1060	2026-09-17 19:18	46.47	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
10605	2026-09-17 19:19	49.84	OK	10606	2026-09-17 19:20	46.49	OK
10607	2026-09-17 19:21	46.09	OK	10608	2026-09-17 19:22	47.90	OK
10609	2026-09-17 19:23	47.28	OK	10610	2026-09-17 19:24	46.58	OK
10611	2026-09-17 19:25	48.17	OK	10612	2026-09-17 19:26	49.52	OK
10613	2026-09-17 19:27	44.98	OK	10614	2026-09-17 19:28	48.00	OK
10615	2026-09-17 19:29	45.34	OK	10616	2026-09-17 19:30	47.11	OK
10617	2026-09-17 19:31	47.47	OK	10618	2026-09-17 19:32	47.55	OK
10619	2026-09-17 19:33	46.90	OK	10620	2026-09-17 19:34	44.85	OK
10621	2026-09-17 19:35	48.54	OK	10622	2026-09-17 19:36	47.03	OK
10623	2026-09-17 19:37	46.92	OK	10624	2026-09-17 19:38	45.92	OK
10625	2026-09-17 19:39	46.19	OK	10626	2026-09-17 19:40	47.07	OK
10627	2026-09-17 19:41	47.77	OK	10628	2026-09-17 19:42	47.47	OK
10629	2026-09-17 19:43	47.52	OK	10630	2026-09-17 19:44	45.79	OK
10631	2026-09-17 19:45	47.05	OK	10632	2026-09-17 19:46	46.44	OK
10633	2026-09-17 19:47	47.60	OK	10634	2026-09-17 19:48	45.09	OK
10635	2026-09-17 19:49	45.73	OK	10636	2026-09-17 19:50	46.26	OK
10637	2026-09-17 19:51	46.70	OK	10638	2026-09-17 19:52	46.06	OK
10639	2026-09-17 19:53	44.66	OK	10640	2026-09-17 19:54	46.15	OK
10641	2026-09-17 19:55	47.14	OK	10642	2026-09-17 19:56	45.50	OK
10643	2026-09-17 19:57	47.03	OK	10644	2026-09-17 19:58	44.72	OK
10645	2026-09-17 19:59	46.37	OK	10646	2026-09-17 20:00	46.86	OK
10647	2026-09-17 20:01	45.81	OK	10648	2026-09-17 20:02	45.10	OK
10649	2026-09-17 20:03	47.28	OK	10650	2026-09-17 20:04	46.93	OK
10651	2026-09-17 20:05	45.87	OK	10652	2026-09-17 20:06	47.46	OK
10653	2026-09-17 20:07	47.56	OK	10654	2026-09-17 20:08	45.79	OK
10655	2026-09-17 20:09	45.98	OK	10656	2026-09-17 20:10	46.99	OK
10657	2026-09-17 20:11	44.98	OK	10658	2026-09-17 20:12	48.18	OK
10659	2026-09-17 20:13	47.02	OK	10660	2026-09-17 20:14	46.97	OK
10661	2026-09-17 20:15	45.99	OK	10662	2026-09-17 20:16	47.68	OK
1066	2026-09-17 20:17	43.87	OK	1066	2026-09-17 20:18	46.80	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
10665	2026-09-17 20:19	45.05	OK	10666	2026-09-17 20:20	46.02	OK
10667	2026-09-17 20:21	47.03	OK	10668	2026-09-17 20:22	46.29	OK
10669	2026-09-17 20:23	46.50	OK	10670	2026-09-17 20:24	43.97	OK
10671	2026-09-17 20:25	46.88	OK	10672	2026-09-17 20:26	45.76	OK
10673	2026-09-17 20:27	46.34	OK	10674	2026-09-17 20:28	46.11	OK
10675	2026-09-17 20:29	46.75	OK	10676	2026-09-17 20:30	45.51	OK
10677	2026-09-17 20:31	45.24	OK	10678	2026-09-17 20:32	46.19	OK
10679	2026-09-17 20:33	45.79	OK	10680	2026-09-17 20:34	46.59	OK
10681	2026-09-17 20:35	45.43	OK	10682	2026-09-17 20:36	44.57	OK
10683	2026-09-17 20:37	47.93	OK	10684	2026-09-17 20:38	44.10	OK
10685	2026-09-17 20:39	46.83	OK	10686	2026-09-17 20:40	47.47	OK
10687	2026-09-17 20:41	46.93	OK	10688	2026-09-17 20:42	44.59	OK
10689	2026-09-17 20:43	45.62	OK	10690	2026-09-17 20:44	46.02	OK
10691	2026-09-17 20:45	44.64	OK	10692	2026-09-17 20:46	45.17	OK
10693	2026-09-17 20:47	45.72	OK	10694	2026-09-17 20:48	45.29	OK
10695	2026-09-17 20:49	46.47	OK	10696	2026-09-17 20:50	45.22	OK
10697	2026-09-17 20:51	47.35	OK	10698	2026-09-17 20:52	46.45	OK
10699	2026-09-17 20:53	44.81	OK	10700	2026-09-17 20:54	44.82	OK
10701	2026-09-17 20:55	45.75	OK	10702	2026-09-17 20:56	48.13	OK
10703	2026-09-17 20:57	45.57	OK	10704	2026-09-17 20:58	43.84	OK
10705	2026-09-17 20:59	45.27	OK	10706	2026-09-17 21:00	43.88	OK
10707	2026-09-17 21:01	45.70	OK	10708	2026-09-17 21:02	46.15	OK
10709	2026-09-17 21:03	44.57	OK	10710	2026-09-17 21:04	47.50	OK
10711	2026-09-17 21:05	45.87	OK	10712	2026-09-17 21:06	46.92	OK
10713	2026-09-17 21:07	45.18	OK	10714	2026-09-17 21:08	44.37	OK
10715	2026-09-17 21:09	46.23	OK	10716	2026-09-17 21:10	45.71	OK
10717	2026-09-17 21:11	43.14	OK	10718	2026-09-17 21:12	46.16	OK
10719	2026-09-17 21:13	46.08	OK	10720	2026-09-17 21:14	45.61	OK
10721	2026-09-17 21:15	45.18	OK	10722	2026-09-17 21:16	45.92	OK
1072	2026-09-17 21:17	45.59	OK	1072	2026-09-17 21:18	46.60	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
10725	2026-09-17 21:19	44.44	OK	10726	2026-09-17 21:20	44.93	OK
10727	2026-09-17 21:21	46.56	OK	10728	2026-09-17 21:22	44.41	OK
10729	2026-09-17 21:23	45.08	OK	10730	2026-09-17 21:24	45.80	OK
10731	2026-09-17 21:25	47.26	OK	10732	2026-09-17 21:26	43.83	OK
10733	2026-09-17 21:27	44.57	OK	10734	2026-09-17 21:28	46.45	OK
10735	2026-09-17 21:29	46.45	OK	10736	2026-09-17 21:30	44.43	OK
10737	2026-09-17 21:31	44.72	OK	10738	2026-09-17 21:32	44.44	OK
10739	2026-09-17 21:33	45.45	OK	10740	2026-09-17 21:34	46.49	OK
10741	2026-09-17 21:35	45.87	OK	10742	2026-09-17 21:36	43.15	OK
10743	2026-09-17 21:37	44.93	OK	10744	2026-09-17 21:38	44.27	OK
10745	2026-09-17 21:39	46.48	OK	10746	2026-09-17 21:40	44.75	OK
10747	2026-09-17 21:41	45.32	OK	10748	2026-09-17 21:42	44.78	OK
10749	2026-09-17 21:43	46.28	OK	10750	2026-09-17 21:44	43.88	OK
10751	2026-09-17 21:45	44.40	OK	10752	2026-09-17 21:46	47.12	OK
10753	2026-09-17 21:47	45.60	OK	10754	2026-09-17 21:48	44.34	OK
10755	2026-09-17 21:49	45.57	OK	10756	2026-09-17 21:50	45.99	OK
10757	2026-09-17 21:51	46.01	OK	10758	2026-09-17 21:52	45.48	OK
10759	2026-09-17 21:53	44.71	OK	10760	2026-09-17 21:54	42.88	OK
10761	2026-09-17 21:55	47.06	OK	10762	2026-09-17 21:56	46.14	OK
10763	2026-09-17 21:57	45.55	OK	10764	2026-09-17 21:58	44.31	OK
10765	2026-09-17 21:59	43.90	OK	10766	2026-09-17 22:00	44.41	OK
10767	2026-09-17 22:01	43.44	OK	10768	2026-09-17 22:02	43.41	OK
10769	2026-09-17 22:03	45.54	OK	10770	2026-09-17 22:04	44.92	OK
10771	2026-09-17 22:05	44.36	OK	10772	2026-09-17 22:06	43.51	OK
10773	2026-09-17 22:07	44.45	OK	10774	2026-09-17 22:08	46.11	OK
10775	2026-09-17 22:09	44.61	OK	10776	2026-09-17 22:10	45.84	OK
10777	2026-09-17 22:11	46.30	OK	10778	2026-09-17 22:12	44.14	OK
10779	2026-09-17 22:13	43.87	OK	10780	2026-09-17 22:14	43.80	OK
10781	2026-09-17 22:15	46.10	OK	10782	2026-09-17 22:16	44.40	OK
1078	2026-09-17 22:17	45.90	OK	1078	2026-09-17 22:18	45.31	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
10785	2026-09-17 22:19	45.24	OK	10786	2026-09-17 22:20	43.50	OK
10787	2026-09-17 22:21	46.37	OK	10788	2026-09-17 22:22	43.10	OK
10789	2026-09-17 22:23	45.30	OK	10790	2026-09-17 22:24	44.61	OK
10791	2026-09-17 22:25	45.56	OK	10792	2026-09-17 22:26	44.12	OK
10793	2026-09-17 22:27	44.72	OK	10794	2026-09-17 22:28	44.43	OK
10795	2026-09-17 22:29	43.97	OK	10796	2026-09-17 22:30	43.94	OK
10797	2026-09-17 22:31	47.29	OK	10798	2026-09-17 22:32	45.32	OK
10799	2026-09-17 22:33	43.11	OK	10800	2026-09-17 22:34	45.21	OK
10801	2026-09-17 22:35	44.11	OK	10802	2026-09-17 22:36	44.75	OK
10803	2026-09-17 22:37	43.96	OK	10804	2026-09-17 22:38	44.71	OK
10805	2026-09-17 22:39	46.30	OK	10806	2026-09-17 22:40	44.95	OK
10807	2026-09-17 22:41	46.65	OK	10808	2026-09-17 22:42	44.14	OK
10809	2026-09-17 22:43	44.91	OK	10810	2026-09-17 22:44	43.16	OK
10811	2026-09-17 22:45	43.54	OK	10812	2026-09-17 22:46	44.40	OK
10813	2026-09-17 22:47	44.14	OK	10814	2026-09-17 22:48	44.35	OK
10815	2026-09-17 22:49	45.48	OK	10816	2026-09-17 22:50	43.70	OK
10817	2026-09-17 22:51	44.30	OK	10818	2026-09-17 22:52	43.43	OK
10819	2026-09-17 22:53	44.57	OK	10820	2026-09-17 22:54	44.74	OK
10821	2026-09-17 22:55	43.95	OK	10822	2026-09-17 22:56	44.64	OK
10823	2026-09-17 22:57	43.79	OK	10824	2026-09-17 22:58	43.37	OK
10825	2026-09-17 22:59	43.75	OK	10826	2026-09-17 23:00	46.86	OK
10827	2026-09-17 23:01	44.04	OK	10828	2026-09-17 23:02	44.14	OK
10829	2026-09-17 23:03	44.41	OK	10830	2026-09-17 23:04	44.22	OK
10831	2026-09-17 23:05	44.51	OK	10832	2026-09-17 23:06	46.62	OK
10833	2026-09-17 23:07	42.76	OK	10834	2026-09-17 23:08	44.17	OK
10835	2026-09-17 23:09	46.81	OK	10836	2026-09-17 23:10	44.06	OK
10837	2026-09-17 23:11	44.70	OK	10838	2026-09-17 23:12	44.94	OK
10839	2026-09-17 23:13	44.07	OK	10840	2026-09-17 23:14	45.21	OK
10841	2026-09-17 23:15	44.83	OK	10842	2026-09-17 23:16	44.99	OK
1084	2026-09-17 23:17	44.33	OK	1084	2026-09-17 23:18	44.62	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
10845	2026-09-17 23:19	45.17	OK	10846	2026-09-17 23:20	44.06	OK
10847	2026-09-17 23:21	45.54	OK	10848	2026-09-17 23:22	45.42	OK
10849	2026-09-17 23:23	44.53	OK	10850	2026-09-17 23:24	44.72	OK
10851	2026-09-17 23:25	42.95	OK	10852	2026-09-17 23:26	45.62	OK
10853	2026-09-17 23:27	43.58	OK	10854	2026-09-17 23:28	46.25	OK
10855	2026-09-17 23:29	44.95	OK	10856	2026-09-17 23:30	45.37	OK
10857	2026-09-17 23:31	45.06	OK	10858	2026-09-17 23:32	45.58	OK
10859	2026-09-17 23:33	44.80	OK	10860	2026-09-17 23:34	43.16	OK
10861	2026-09-17 23:35	44.03	OK	10862	2026-09-17 23:36	44.15	OK
10863	2026-09-17 23:37	43.79	OK	10864	2026-09-17 23:38	45.45	OK
10865	2026-09-17 23:39	44.25	OK	10866	2026-09-17 23:40	44.71	OK
10867	2026-09-17 23:41	44.83	OK	10868	2026-09-17 23:42	44.08	OK
10869	2026-09-17 23:43	45.31	OK	10870	2026-09-17 23:44	43.91	OK
10871	2026-09-17 23:45	45.96	OK	10872	2026-09-17 23:46	43.75	OK
10873	2026-09-17 23:47	43.02	OK	10874	2026-09-17 23:48	43.92	OK
10875	2026-09-17 23:49	43.83	OK	10876	2026-09-17 23:50	44.56	OK
10877	2026-09-17 23:51	42.44	OK	10878	2026-09-17 23:52	44.13	OK
10879	2026-09-17 23:53	45.21	OK	10880	2026-09-17 23:54	44.62	OK
10881	2026-09-17 23:55	44.09	OK	10882	2026-09-17 23:56	42.12	OK
10883	2026-09-17 23:57	45.37	OK	10884	2026-09-17 23:58	44.65	OK
10885	2026-09-17 23:59	46.67	OK	10886	2026-09-18 00:00	42.71	OK
10887	2026-09-18 00:01	44.37	OK	10888	2026-09-18 00:02	41.96	OK
10889	2026-09-18 00:03	42.28	OK	10890	2026-09-18 00:04	43.71	OK
10891	2026-09-18 00:05	42.27	OK	10892	2026-09-18 00:06	44.08	OK
10893	2026-09-18 00:07	45.26	OK	10894	2026-09-18 00:08	44.84	OK
10895	2026-09-18 00:09	43.83	OK	10896	2026-09-18 00:10	43.97	OK
10897	2026-09-18 00:11	45.12	OK	10898	2026-09-18 00:12	44.74	OK
10899	2026-09-18 00:13	45.45	OK	10900	2026-09-18 00:14	46.17	OK
10901	2026-09-18 00:15	42.27	OK	10902	2026-09-18 00:16	46.21	OK
1090	2026-09-18 00:17	43.64	OK	1090	2026-09-18 00:18	46.54	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
10905	2026-09-18 00:19	43.00	OK	10906	2026-09-18 00:20	42.53	OK
10907	2026-09-18 00:21	42.71	OK	10908	2026-09-18 00:22	43.86	OK
10909	2026-09-18 00:23	45.16	OK	10910	2026-09-18 00:24	46.23	OK
10911	2026-09-18 00:25	44.62	OK	10912	2026-09-18 00:26	43.81	OK
10913	2026-09-18 00:27	45.01	OK	10914	2026-09-18 00:28	43.23	OK
10915	2026-09-18 00:29	44.51	OK	10916	2026-09-18 00:30	46.38	OK
10917	2026-09-18 00:31	45.90	OK	10918	2026-09-18 00:32	46.08	OK
10919	2026-09-18 00:33	45.73	OK	10920	2026-09-18 00:34	43.16	OK
10921	2026-09-18 00:35	45.28	OK	10922	2026-09-18 00:36	44.66	OK
10923	2026-09-18 00:37	44.99	OK	10924	2026-09-18 00:38	44.35	OK
10925	2026-09-18 00:39	44.08	OK	10926	2026-09-18 00:40	43.74	OK
10927	2026-09-18 00:41	45.12	OK	10928	2026-09-18 00:42	42.83	OK
10929	2026-09-18 00:43	44.74	OK	10930	2026-09-18 00:44	44.67	OK
10931	2026-09-18 00:45	45.39	OK	10932	2026-09-18 00:46	44.13	OK
10933	2026-09-18 00:47	45.59	OK	10934	2026-09-18 00:48	46.67	OK
10935	2026-09-18 00:49	43.31	OK	10936	2026-09-18 00:50	46.56	OK
10937	2026-09-18 00:51	45.41	OK	10938	2026-09-18 00:52	42.95	OK
10939	2026-09-18 00:53	45.62	OK	10940	2026-09-18 00:54	43.46	OK
10941	2026-09-18 00:55	46.44	OK	10942	2026-09-18 00:56	44.68	OK
10943	2026-09-18 00:57	43.49	OK	10944	2026-09-18 00:58	45.37	OK
10945	2026-09-18 00:59	44.80	OK	10946	2026-09-18 01:00	46.15	OK
10947	2026-09-18 01:01	45.92	OK	10948	2026-09-18 01:02	46.33	OK
10949	2026-09-18 01:03	42.61	OK	10950	2026-09-18 01:04	46.79	OK
10951	2026-09-18 01:05	44.08	OK	10952	2026-09-18 01:06	47.21	OK
10953	2026-09-18 01:07	45.20	OK	10954	2026-09-18 01:08	45.69	OK
10955	2026-09-18 01:09	44.84	OK	10956	2026-09-18 01:10	46.58	OK
10957	2026-09-18 01:11	46.93	OK	10958	2026-09-18 01:12	44.42	OK
10959	2026-09-18 01:13	43.36	OK	10960	2026-09-18 01:14	45.39	OK
10961	2026-09-18 01:15	46.29	OK	10962	2026-09-18 01:16	44.70	OK
1096	2026-09-18 01:17	45.30	OK	1096	2026-09-18 01:18	45.86	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
10965	2026-09-18 01:19	43.35	OK	10966	2026-09-18 01:20	45.43	OK
10967	2026-09-18 01:21	45.10	OK	10968	2026-09-18 01:22	44.79	OK
10969	2026-09-18 01:23	46.73	OK	10970	2026-09-18 01:24	44.08	OK
10971	2026-09-18 01:25	46.50	OK	10972	2026-09-18 01:26	46.22	OK
10973	2026-09-18 01:27	44.35	OK	10974	2026-09-18 01:28	45.79	OK
10975	2026-09-18 01:29	45.95	OK	10976	2026-09-18 01:30	45.94	OK
10977	2026-09-18 01:31	46.56	OK	10978	2026-09-18 01:32	42.91	OK
10979	2026-09-18 01:33	44.19	OK	10980	2026-09-18 01:34	45.80	OK
10981	2026-09-18 01:35	45.20	OK	10982	2026-09-18 01:36	46.02	OK
10983	2026-09-18 01:37	45.66	OK	10984	2026-09-18 01:38	47.24	OK
10985	2026-09-18 01:39	44.70	OK	10986	2026-09-18 01:40	45.64	OK
10987	2026-09-18 01:41	44.48	OK	10988	2026-09-18 01:42	44.52	OK
10989	2026-09-18 01:43	45.24	OK	10990	2026-09-18 01:44	45.18	OK
10991	2026-09-18 01:45	46.65	OK	10992	2026-09-18 01:46	45.27	OK
10993	2026-09-18 01:47	44.99	OK	10994	2026-09-18 01:48	45.21	OK
10995	2026-09-18 01:49	45.93	OK	10996	2026-09-18 01:50	46.67	OK
10997	2026-09-18 01:51	45.46	OK	10998	2026-09-18 01:52	44.75	OK
10999	2026-09-18 01:53	45.47	OK	11000	2026-09-18 01:54	43.88	OK
11001	2026-09-18 01:55	45.94	OK	11002	2026-09-18 01:56	46.78	OK
11003	2026-09-18 01:57	47.75	OK	11004	2026-09-18 01:58	42.65	OK
11005	2026-09-18 01:59	45.83	OK	11006	2026-09-18 02:00	45.23	OK
11007	2026-09-18 02:01	46.30	OK	11008	2026-09-18 02:02	46.82	OK
11009	2026-09-18 02:03	45.38	OK	11010	2026-09-18 02:04	45.76	OK
11011	2026-09-18 02:05	46.56	OK	11012	2026-09-18 02:06	44.44	OK
11013	2026-09-18 02:07	46.80	OK	11014	2026-09-18 02:08	45.12	OK
11015	2026-09-18 02:09	45.61	OK	11016	2026-09-18 02:10	45.90	OK
11017	2026-09-18 02:11	47.92	OK	11018	2026-09-18 02:12	44.97	OK
11019	2026-09-18 02:13	45.91	OK	11020	2026-09-18 02:14	46.38	OK
11021	2026-09-18 02:15	44.99	OK	11022	2026-09-18 02:16	46.56	OK
1102	2026-09-18 02:17	45.79	OK	1102	2026-09-18 02:18	45.60	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
11025	2026-09-18 02:19	47.57	OK	11026	2026-09-18 02:20	46.41	OK
11027	2026-09-18 02:21	45.53	OK	11028	2026-09-18 02:22	45.54	OK
11029	2026-09-18 02:23	46.58	OK	11030	2026-09-18 02:24	43.44	OK
11031	2026-09-18 02:25	47.27	OK	11032	2026-09-18 02:26	47.21	OK
11033	2026-09-18 02:27	44.83	OK	11034	2026-09-18 02:28	47.51	OK
11035	2026-09-18 02:29	47.28	OK	11036	2026-09-18 02:30	46.11	OK
11037	2026-09-18 02:31	47.16	OK	11038	2026-09-18 02:32	44.13	OK
11039	2026-09-18 02:33	46.34	OK	11040	2026-09-18 02:34	45.14	OK
11041	2026-09-18 02:35	48.50	OK	11042	2026-09-18 02:36	46.38	OK
11043	2026-09-18 02:37	45.14	OK	11044	2026-09-18 02:38	45.74	OK
11045	2026-09-18 02:39	44.38	OK	11046	2026-09-18 02:40	48.17	OK
11047	2026-09-18 02:41	44.63	OK	11048	2026-09-18 02:42	45.99	OK
11049	2026-09-18 02:43	44.97	OK	11050	2026-09-18 02:44	45.93	OK
11051	2026-09-18 02:45	45.38	OK	11052	2026-09-18 02:46	46.02	OK
11053	2026-09-18 02:47	47.52	OK	11054	2026-09-18 02:48	45.86	OK
11055	2026-09-18 02:49	46.42	OK	11056	2026-09-18 02:50	46.83	OK
11057	2026-09-18 02:51	46.89	OK	11058	2026-09-18 02:52	46.34	OK
11059	2026-09-18 02:53	46.12	OK	11060	2026-09-18 02:54	46.36	OK
11061	2026-09-18 02:55	46.88	OK	11062	2026-09-18 02:56	46.01	OK
11063	2026-09-18 02:57	46.04	OK	11064	2026-09-18 02:58	45.01	OK
11065	2026-09-18 02:59	45.61	OK	11066	2026-09-18 03:00	46.47	OK
11067	2026-09-18 03:01	45.04	OK	11068	2026-09-18 03:02	45.93	OK
11069	2026-09-18 03:03	47.47	OK	11070	2026-09-18 03:04	46.56	OK
11071	2026-09-18 03:05	46.07	OK	11072	2026-09-18 03:06	45.67	OK
11073	2026-09-18 03:07	48.08	OK	11074	2026-09-18 03:08	44.60	OK
11075	2026-09-18 03:09	48.06	OK	11076	2026-09-18 03:10	47.21	OK
11077	2026-09-18 03:11	46.74	OK	11078	2026-09-18 03:12	46.94	OK
11079	2026-09-18 03:13	45.53	OK	11080	2026-09-18 03:14	46.30	OK
11081	2026-09-18 03:15	46.96	OK	11082	2026-09-18 03:16	45.46	OK
1108	2026-09-18 03:17	46.12	OK	1108	2026-09-18 03:18	46.70	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
11085	2026-09-18 03:19	46.52	OK	11086	2026-09-18 03:20	49.46	OK
11087	2026-09-18 03:21	46.46	OK	11088	2026-09-18 03:22	47.44	OK
11089	2026-09-18 03:23	45.37	OK	11090	2026-09-18 03:24	47.44	OK
11091	2026-09-18 03:25	47.26	OK	11092	2026-09-18 03:26	48.16	OK
11093	2026-09-18 03:27	48.11	OK	11094	2026-09-18 03:28	46.60	OK
11095	2026-09-18 03:29	46.52	OK	11096	2026-09-18 03:30	46.61	OK
11097	2026-09-18 03:31	47.98	OK	11098	2026-09-18 03:32	47.14	OK
11099	2026-09-18 03:33	47.62	OK	11100	2026-09-18 03:34	47.44	OK
11101	2026-09-18 03:35	45.16	OK	11102	2026-09-18 03:36	46.95	OK
11103	2026-09-18 03:37	46.50	OK	11104	2026-09-18 03:38	46.59	OK
11105	2026-09-18 03:39	50.07	OK	11106	2026-09-18 03:40	48.49	OK
11107	2026-09-18 03:41	45.31	OK	11108	2026-09-18 03:42	47.76	OK
11109	2026-09-18 03:43	48.24	OK	11110	2026-09-18 03:44	47.10	OK
11111	2026-09-18 03:45	44.89	OK	11112	2026-09-18 03:46	47.97	OK
11113	2026-09-18 03:47	46.56	OK	11114	2026-09-18 03:48	47.17	OK
11115	2026-09-18 03:49	48.19	OK	11116	2026-09-18 03:50	46.91	OK
11117	2026-09-18 03:51	48.79	OK	11118	2026-09-18 03:52	46.48	OK
11119	2026-09-18 03:53	46.71	OK	11120	2026-09-18 03:54	48.48	OK
11121	2026-09-18 03:55	49.32	OK	11122	2026-09-18 03:56	47.50	OK
11123	2026-09-18 03:57	48.12	OK	11124	2026-09-18 03:58	48.34	OK
11125	2026-09-18 03:59	48.60	OK	11126	2026-09-18 04:00	49.28	OK
11127	2026-09-18 04:01	47.43	OK	11128	2026-09-18 04:02	48.40	OK
11129	2026-09-18 04:03	49.25	OK	11130	2026-09-18 04:04	46.55	OK
11131	2026-09-18 04:05	47.82	OK	11132	2026-09-18 04:06	47.27	OK
11133	2026-09-18 04:07	47.03	OK	11134	2026-09-18 04:08	48.81	OK
11135	2026-09-18 04:09	46.98	OK	11136	2026-09-18 04:10	47.39	OK
11137	2026-09-18 04:11	46.68	OK	11138	2026-09-18 04:12	48.71	OK
11139	2026-09-18 04:13	49.21	OK	11140	2026-09-18 04:14	47.75	OK
11141	2026-09-18 04:15	47.23	OK	11142	2026-09-18 04:16	46.44	OK
1114	2026-09-18 04:17	49.42	OK	1114	2026-09-18 04:18	49.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
11145	2026-09-18 04:19	49.04	OK	11146	2026-09-18 04:20	48.08	OK
11147	2026-09-18 04:21	49.05	OK	11148	2026-09-18 04:22	48.25	OK
11149	2026-09-18 04:23	48.75	OK	11150	2026-09-18 04:24	48.94	OK
11151	2026-09-18 04:25	48.80	OK	11152	2026-09-18 04:26	49.25	OK
11153	2026-09-18 04:27	46.89	OK	11154	2026-09-18 04:28	47.45	OK
11155	2026-09-18 04:29	47.45	OK	11156	2026-09-18 04:30	48.94	OK
11157	2026-09-18 04:31	48.80	OK	11158	2026-09-18 04:32	47.79	OK
11159	2026-09-18 04:33	49.04	OK	11160	2026-09-18 04:34	47.10	OK
11161	2026-09-18 04:35	48.09	OK	11162	2026-09-18 04:36	50.08	OK
11163	2026-09-18 04:37	49.67	OK	11164	2026-09-18 04:38	49.63	OK
11165	2026-09-18 04:39	49.51	OK	11166	2026-09-18 04:40	48.97	OK
11167	2026-09-18 04:41	49.86	OK	11168	2026-09-18 04:42	50.01	OK
11169	2026-09-18 04:43	48.27	OK	11170	2026-09-18 04:44	48.99	OK
11171	2026-09-18 04:45	47.37	OK	11172	2026-09-18 04:46	48.53	OK
11173	2026-09-18 04:47	49.98	OK	11174	2026-09-18 04:48	49.76	OK
11175	2026-09-18 04:49	48.92	OK	11176	2026-09-18 04:50	49.04	OK
11177	2026-09-18 04:51	48.47	OK	11178	2026-09-18 04:52	47.06	OK
11179	2026-09-18 04:53	48.28	OK	11180	2026-09-18 04:54	48.34	OK
11181	2026-09-18 04:55	49.12	OK	11182	2026-09-18 04:56	50.34	OK
11183	2026-09-18 04:57	48.24	OK	11184	2026-09-18 04:58	49.06	OK
11185	2026-09-18 04:59	49.37	OK	11186	2026-09-18 05:00	47.57	OK
11187	2026-09-18 05:01	47.44	OK	11188	2026-09-18 05:02	48.54	OK
11189	2026-09-18 05:03	48.99	OK	11190	2026-09-18 05:04	50.28	OK
11191	2026-09-18 05:05	49.85	OK	11192	2026-09-18 05:06	51.05	OK
11193	2026-09-18 05:07	48.48	OK	11194	2026-09-18 05:08	50.68	OK
11195	2026-09-18 05:09	48.08	OK	11196	2026-09-18 05:10	47.82	OK
11197	2026-09-18 05:11	47.60	OK	11198	2026-09-18 05:12	48.36	OK
11199	2026-09-18 05:13	49.39	OK	11200	2026-09-18 05:14	49.16	OK
11201	2026-09-18 05:15	49.25	OK	11202	2026-09-18 05:16	47.24	OK
1120	2026-09-18 05:17	49.00	OK	1120	2026-09-18 05:18	50.06	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
11205	2026-09-18 05:19	48.81	OK	11206	2026-09-18 05:20	49.38	OK
11207	2026-09-18 05:21	48.57	OK	11208	2026-09-18 05:22	50.53	OK
11209	2026-09-18 05:23	49.78	OK	11210	2026-09-18 05:24	49.24	OK
11211	2026-09-18 05:25	49.45	OK	11212	2026-09-18 05:26	48.37	OK
11213	2026-09-18 05:27	49.21	OK	11214	2026-09-18 05:28	49.50	OK
11215	2026-09-18 05:29	48.40	OK	11216	2026-09-18 05:30	50.20	OK
11217	2026-09-18 05:31	49.91	OK	11218	2026-09-18 05:32	50.71	OK
11219	2026-09-18 05:33	48.26	OK	11220	2026-09-18 05:34	50.51	OK
11221	2026-09-18 05:35	48.21	OK	11222	2026-09-18 05:36	48.21	OK
11223	2026-09-18 05:37	50.74	OK	11224	2026-09-18 05:38	50.90	OK
11225	2026-09-18 05:39	49.60	OK	11226	2026-09-18 05:40	50.94	OK
11227	2026-09-18 05:41	49.16	OK	11228	2026-09-18 05:42	50.83	OK
11229	2026-09-18 05:43	50.57	OK	11230	2026-09-18 05:44	50.02	OK
11231	2026-09-18 05:45	50.04	OK	11232	2026-09-18 05:46	49.11	OK
11233	2026-09-18 05:47	50.18	OK	11234	2026-09-18 05:48	49.69	OK
11235	2026-09-18 05:49	48.84	OK	11236	2026-09-18 05:50	47.98	OK
11237	2026-09-18 05:51	50.34	OK	11238	2026-09-18 05:52	50.82	OK
11239	2026-09-18 05:53	49.79	OK	11240	2026-09-18 05:54	50.97	OK
11241	2026-09-18 05:55	49.98	OK	11242	2026-09-18 05:56	49.90	OK
11243	2026-09-18 05:57	50.61	OK	11244	2026-09-18 05:58	48.53	OK
11245	2026-09-18 05:59	50.32	OK	11246	2026-09-18 06:00	48.94	OK
11247	2026-09-18 06:01	48.61	OK	11248	2026-09-18 06:02	49.26	OK
11249	2026-09-18 06:03	50.27	OK	11250	2026-09-18 06:04	49.62	OK
11251	2026-09-18 06:05	50.59	OK	11252	2026-09-18 06:06	49.19	OK
11253	2026-09-18 06:07	49.65	OK	11254	2026-09-18 06:08	50.37	OK
11255	2026-09-18 06:09	49.53	OK	11256	2026-09-18 06:10	50.99	OK
11257	2026-09-18 06:11	50.09	OK	11258	2026-09-18 06:12	49.23	OK
11259	2026-09-18 06:13	50.11	OK	11260	2026-09-18 06:14	50.98	OK
11261	2026-09-18 06:15	50.56	OK	11262	2026-09-18 06:16	50.51	OK
1126	2026-09-18 06:17	49.27	OK	1126	2026-09-18 06:18	49.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
11265	2026-09-18 06:19	49.11	OK	11266	2026-09-18 06:20	51.85	OK
11267	2026-09-18 06:21	48.85	OK	11268	2026-09-18 06:22	51.70	OK
11269	2026-09-18 06:23	48.85	OK	11270	2026-09-18 06:24	51.93	OK
11271	2026-09-18 06:25	50.93	OK	11272	2026-09-18 06:26	51.03	OK
11273	2026-09-18 06:27	49.65	OK	11274	2026-09-18 06:28	52.73	OK
11275	2026-09-18 06:29	51.91	OK	11276	2026-09-18 06:30	51.19	OK
11277	2026-09-18 06:31	49.84	OK	11278	2026-09-18 06:32	50.94	OK
11279	2026-09-18 06:33	51.33	OK	11280	2026-09-18 06:34	50.89	OK
11281	2026-09-18 06:35	49.62	OK	11282	2026-09-18 06:36	51.28	OK
11283	2026-09-18 06:37	51.21	OK	11284	2026-09-18 06:38	49.63	OK
11285	2026-09-18 06:39	50.26	OK	11286	2026-09-18 06:40	49.35	OK
11287	2026-09-18 06:41	51.24	OK	11288	2026-09-18 06:42	53.20	OK
11289	2026-09-18 06:43	50.73	OK	11290	2026-09-18 06:44	51.05	OK
11291	2026-09-18 06:45	50.80	OK	11292	2026-09-18 06:46	52.06	OK
11293	2026-09-18 06:47	51.12	OK	11294	2026-09-18 06:48	50.30	OK
11295	2026-09-18 06:49	51.03	OK	11296	2026-09-18 06:50	50.52	OK
11297	2026-09-18 06:51	52.48	OK	11298	2026-09-18 06:52	51.98	OK
11299	2026-09-18 06:53	50.52	OK	11300	2026-09-18 06:54	51.23	OK
11301	2026-09-18 06:55	52.14	OK	11302	2026-09-18 06:56	52.26	OK
11303	2026-09-18 06:57	50.35	OK	11304	2026-09-18 06:58	53.51	OK
11305	2026-09-18 06:59	50.85	OK	11306	2026-09-18 07:00	52.06	OK
11307	2026-09-18 07:01	51.00	OK	11308	2026-09-18 07:02	50.03	OK
11309	2026-09-18 07:03	53.15	OK	11310	2026-09-18 07:04	52.55	OK
11311	2026-09-18 07:05	52.00	OK	11312	2026-09-18 07:06	50.88	OK
11313	2026-09-18 07:07	51.42	OK	11314	2026-09-18 07:08	48.48	OK
11315	2026-09-18 07:09	53.23	OK	11316	2026-09-18 07:10	49.56	OK
11317	2026-09-18 07:11	52.84	OK	11318	2026-09-18 07:12	52.38	OK
11319	2026-09-18 07:13	53.46	OK	11320	2026-09-18 07:14	50.05	OK
11321	2026-09-18 07:15	50.49	OK	11322	2026-09-18 07:16	49.72	OK
1132	2026-09-18 07:17	51.98	OK	1132	2026-09-18 07:18	51.13	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
11325	2026-09-18 07:19	52.33	OK	11326	2026-09-18 07:20	51.27	OK
11327	2026-09-18 07:21	52.25	OK	11328	2026-09-18 07:22	50.32	OK
11329	2026-09-18 07:23	51.58	OK	11330	2026-09-18 07:24	51.78	OK
11331	2026-09-18 07:25	50.82	OK	11332	2026-09-18 07:26	51.93	OK
11333	2026-09-18 07:27	50.63	OK	11334	2026-09-18 07:28	50.28	OK
11335	2026-09-18 07:29	52.92	OK	11336	2026-09-18 07:30	50.44	OK
11337	2026-09-18 07:31	52.48	OK	11338	2026-09-18 07:32	51.33	OK
11339	2026-09-18 07:33	52.48	OK	11340	2026-09-18 07:34	52.26	OK
11341	2026-09-18 07:35	53.59	OK	11342	2026-09-18 07:36	50.70	OK
11343	2026-09-18 07:37	52.40	OK	11344	2026-09-18 07:38	53.49	OK
11345	2026-09-18 07:39	52.42	OK	11346	2026-09-18 07:40	52.24	OK
11347	2026-09-18 07:41	50.67	OK	11348	2026-09-18 07:42	51.69	OK
11349	2026-09-18 07:43	50.23	OK	11350	2026-09-18 07:44	53.88	OK
11351	2026-09-18 07:45	53.57	OK	11352	2026-09-18 07:46	51.77	OK
11353	2026-09-18 07:47	49.96	OK	11354	2026-09-18 07:48	52.10	OK
11355	2026-09-18 07:49	53.01	OK	11356	2026-09-18 07:50	52.41	OK
11357	2026-09-18 07:51	53.75	OK	11358	2026-09-18 07:52	51.55	OK
11359	2026-09-18 07:53	51.75	OK	11360	2026-09-18 07:54	51.24	OK
11361	2026-09-18 07:55	50.92	OK	11362	2026-09-18 07:56	51.23	OK
11363	2026-09-18 07:57	53.04	OK	11364	2026-09-18 07:58	52.11	OK
11365	2026-09-18 07:59	51.02	OK	11366	2026-09-18 08:00	51.02	OK
11367	2026-09-18 08:01	52.90	OK	11368	2026-09-18 08:02	51.31	OK
11369	2026-09-18 08:03	51.29	OK	11370	2026-09-18 08:04	54.72	OK
11371	2026-09-18 08:05	51.00	OK	11372	2026-09-18 08:06	51.63	OK
11373	2026-09-18 08:07	54.13	OK	11374	2026-09-18 08:08	54.28	OK
11375	2026-09-18 08:09	52.02	OK	11376	2026-09-18 08:10	52.86	OK
11377	2026-09-18 08:11	52.22	OK	11378	2026-09-18 08:12	53.64	OK
11379	2026-09-18 08:13	51.05	OK	11380	2026-09-18 08:14	52.78	OK
11381	2026-09-18 08:15	51.38	OK	11382	2026-09-18 08:16	55.18	OK
1138	2026-09-18 08:17	53.95	OK	1138	2026-09-18 08:18	54.13	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
11385	2026-09-18 08:19	51.14	OK	11386	2026-09-18 08:20	53.22	OK
11387	2026-09-18 08:21	54.35	OK	11388	2026-09-18 08:22	52.82	OK
11389	2026-09-18 08:23	53.76	OK	11390	2026-09-18 08:24	53.16	OK
11391	2026-09-18 08:25	50.72	OK	11392	2026-09-18 08:26	51.15	OK
11393	2026-09-18 08:27	53.11	OK	11394	2026-09-18 08:28	53.20	OK
11395	2026-09-18 08:29	51.55	OK	11396	2026-09-18 08:30	54.83	OK
11397	2026-09-18 08:31	53.88	OK	11398	2026-09-18 08:32	52.38	OK
11399	2026-09-18 08:33	51.75	OK	11400	2026-09-18 08:34	52.96	OK
11401	2026-09-18 08:35	52.95	OK	11402	2026-09-18 08:36	54.00	OK
11403	2026-09-18 08:37	52.02	OK	11404	2026-09-18 08:38	54.70	OK
11405	2026-09-18 08:39	53.39	OK	11406	2026-09-18 08:40	51.65	OK
11407	2026-09-18 08:41	51.09	OK	11408	2026-09-18 08:42	52.09	OK
11409	2026-09-18 08:43	52.47	OK	11410	2026-09-18 08:44	51.69	OK
11411	2026-09-18 08:45	53.47	OK	11412	2026-09-18 08:46	53.71	OK
11413	2026-09-18 08:47	52.18	OK	11414	2026-09-18 08:48	52.64	OK
11415	2026-09-18 08:49	52.32	OK	11416	2026-09-18 08:50	53.08	OK
11417	2026-09-18 08:51	52.66	OK	11418	2026-09-18 08:52	52.03	OK
11419	2026-09-18 08:53	52.50	OK	11420	2026-09-18 08:54	53.06	OK
11421	2026-09-18 08:55	54.36	OK	11422	2026-09-18 08:56	52.96	OK
11423	2026-09-18 08:57	52.65	OK	11424	2026-09-18 08:58	52.27	OK
11425	2026-09-18 08:59	51.22	OK	11426	2026-09-18 09:00	55.13	OK
11427	2026-09-18 09:01	55.06	OK	11428	2026-09-18 09:02	53.60	OK
11429	2026-09-18 09:03	54.02	OK	11430	2026-09-18 09:04	52.82	OK
11431	2026-09-18 09:05	55.63	OK	11432	2026-09-18 09:06	53.37	OK
11433	2026-09-18 09:07	55.35	OK	11434	2026-09-18 09:08	53.60	OK
11435	2026-09-18 09:09	54.04	OK	11436	2026-09-18 09:10	53.22	OK
11437	2026-09-18 09:11	54.97	OK	11438	2026-09-18 09:12	53.41	OK
11439	2026-09-18 09:13	53.01	OK	11440	2026-09-18 09:14	52.97	OK
11441	2026-09-18 09:15	54.25	OK	11442	2026-09-18 09:16	52.25	OK
1144	2026-09-18 09:17	54.11	OK	1144	2026-09-18 09:18	54.73	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
11445	2026-09-18 09:19	53.39	OK	11446	2026-09-18 09:20	54.79	OK
11447	2026-09-18 09:21	53.56	OK	11448	2026-09-18 09:22	54.45	OK
11449	2026-09-18 09:23	53.17	OK	11450	2026-09-18 09:24	53.48	OK
11451	2026-09-18 09:25	52.41	OK	11452	2026-09-18 09:26	52.53	OK
11453	2026-09-18 09:27	51.64	OK	11454	2026-09-18 09:28	52.70	OK
11455	2026-09-18 09:29	53.52	OK	11456	2026-09-18 09:30	52.82	OK
11457	2026-09-18 09:31	52.87	OK	11458	2026-09-18 09:32	51.61	OK
11459	2026-09-18 09:33	53.14	OK	11460	2026-09-18 09:34	51.36	OK
11461	2026-09-18 09:35	54.74	OK	11462	2026-09-18 09:36	53.69	OK
11463	2026-09-18 09:37	53.33	OK	11464	2026-09-18 09:38	54.21	OK
11465	2026-09-18 09:39	54.02	OK	11466	2026-09-18 09:40	53.54	OK
11467	2026-09-18 09:41	52.66	OK	11468	2026-09-18 09:42	53.48	OK
11469	2026-09-18 09:43	54.15	OK	11470	2026-09-18 09:44	53.14	OK
11471	2026-09-18 09:45	53.54	OK	11472	2026-09-18 09:46	53.74	OK
11473	2026-09-18 09:47	52.95	OK	11474	2026-09-18 09:48	53.37	OK
11475	2026-09-18 09:49	52.79	OK	11476	2026-09-18 09:50	55.11	OK
11477	2026-09-18 09:51	52.94	OK	11478	2026-09-18 09:52	52.68	OK
11479	2026-09-18 09:53	51.32	OK	11480	2026-09-18 09:54	53.34	OK
11481	2026-09-18 09:55	51.92	OK	11482	2026-09-18 09:56	52.37	OK
11483	2026-09-18 09:57	54.44	OK	11484	2026-09-18 09:58	53.21	OK
11485	2026-09-18 09:59	55.66	OK	11486	2026-09-18 10:00	55.55	OK
11487	2026-09-18 10:01	53.61	OK	11488	2026-09-18 10:02	54.62	OK
11489	2026-09-18 10:03	54.67	OK	11490	2026-09-18 10:04	53.51	OK
11491	2026-09-18 10:05	53.44	OK	11492	2026-09-18 10:06	53.56	OK
11493	2026-09-18 10:07	54.14	OK	11494	2026-09-18 10:08	51.53	OK
11495	2026-09-18 10:09	53.59	OK	11496	2026-09-18 10:10	53.93	OK
11497	2026-09-18 10:11	52.46	OK	11498	2026-09-18 10:12	56.38	OK
11499	2026-09-18 10:13	54.42	OK	11500	2026-09-18 10:14	51.88	OK
11501	2026-09-18 10:15	52.31	OK	11502	2026-09-18 10:16	52.24	OK
1150	2026-09-18 10:17	54.47	OK	1150	2026-09-18 10:18	54.00	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
11505	2026-09-18 10:19	52.01	OK	11506	2026-09-18 10:20	53.25	OK
11507	2026-09-18 10:21	54.59	OK	11508	2026-09-18 10:22	54.02	OK
11509	2026-09-18 10:23	53.92	OK	11510	2026-09-18 10:24	53.29	OK
11511	2026-09-18 10:25	54.07	OK	11512	2026-09-18 10:26	53.99	OK
11513	2026-09-18 10:27	53.77	OK	11514	2026-09-18 10:28	57.04	OK
11515	2026-09-18 10:29	52.55	OK	11516	2026-09-18 10:30	55.02	OK
11517	2026-09-18 10:31	53.50	OK	11518	2026-09-18 10:32	54.20	OK
11519	2026-09-18 10:33	54.59	OK	11520	2026-09-18 10:34	54.68	OK
11521	2026-09-18 10:35	54.95	OK	11522	2026-09-18 10:36	53.68	OK
11523	2026-09-18 10:37	54.82	OK	11524	2026-09-18 10:38	55.80	OK
11525	2026-09-18 10:39	53.31	OK	11526	2026-09-18 10:40	52.28	OK
11527	2026-09-18 10:41	53.24	OK	11528	2026-09-18 10:42	55.83	OK
11529	2026-09-18 10:43	55.12	OK	11530	2026-09-18 10:44	52.99	OK
11531	2026-09-18 10:45	55.05	OK	11532	2026-09-18 10:46	53.60	OK
11533	2026-09-18 10:47	53.11	OK	11534	2026-09-18 10:48	54.84	OK
11535	2026-09-18 10:49	53.44	OK	11536	2026-09-18 10:50	53.47	OK
11537	2026-09-18 10:51	53.74	OK	11538	2026-09-18 10:52	53.64	OK
11539	2026-09-18 10:53	54.16	OK	11540	2026-09-18 10:54	53.83	OK
11541	2026-09-18 10:55	55.09	OK	11542	2026-09-18 10:56	54.77	OK
11543	2026-09-18 10:57	54.23	OK	11544	2026-09-18 10:58	53.47	OK
11545	2026-09-18 10:59	54.16	OK	11546	2026-09-18 11:00	54.87	OK
11547	2026-09-18 11:01	52.97	OK	11548	2026-09-18 11:02	54.13	OK
11549	2026-09-18 11:03	53.59	OK	11550	2026-09-18 11:04	54.56	OK
11551	2026-09-18 11:05	54.74	OK	11552	2026-09-18 11:06	54.34	OK
11553	2026-09-18 11:07	54.54	OK	11554	2026-09-18 11:08	53.97	OK
11555	2026-09-18 11:09	52.85	OK	11556	2026-09-18 11:10	53.01	OK
11557	2026-09-18 11:11	55.52	OK	11558	2026-09-18 11:12	56.26	OK
11559	2026-09-18 11:13	53.94	OK	11560	2026-09-18 11:14	55.68	OK
11561	2026-09-18 11:15	54.32	OK	11562	2026-09-18 11:16	54.86	OK
1156	2026-09-18 11:17	53.56	OK	1156	2026-09-18 11:18	52.91	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
11565	2026-09-18 11:19	53.35	OK	11566	2026-09-18 11:20	52.62	OK
11567	2026-09-18 11:21	52.97	OK	11568	2026-09-18 11:22	54.39	OK
11569	2026-09-18 11:23	54.51	OK	11570	2026-09-18 11:24	52.97	OK
11571	2026-09-18 11:25	54.76	OK	11572	2026-09-18 11:26	56.07	OK
11573	2026-09-18 11:27	55.80	OK	11574	2026-09-18 11:28	54.67	OK
11575	2026-09-18 11:29	52.93	OK	11576	2026-09-18 11:30	54.22	OK
11577	2026-09-18 11:31	54.27	OK	11578	2026-09-18 11:32	54.03	OK
11579	2026-09-18 11:33	53.90	OK	11580	2026-09-18 11:34	54.77	OK
11581	2026-09-18 11:35	53.92	OK	11582	2026-09-18 11:36	54.46	OK
11583	2026-09-18 11:37	54.47	OK	11584	2026-09-18 11:38	54.41	OK
11585	2026-09-18 11:39	55.43	OK	11586	2026-09-18 11:40	55.37	OK
11587	2026-09-18 11:41	52.75	OK	11588	2026-09-18 11:42	53.36	OK
11589	2026-09-18 11:43	52.97	OK	11590	2026-09-18 11:44	54.05	OK
11591	2026-09-18 11:45	53.72	OK	11592	2026-09-18 11:46	54.67	OK
11593	2026-09-18 11:47	52.49	OK	11594	2026-09-18 11:48	53.92	OK
11595	2026-09-18 11:49	52.76	OK	11596	2026-09-18 11:50	55.15	OK
11597	2026-09-18 11:51	52.84	OK	11598	2026-09-18 11:52	55.50	OK
11599	2026-09-18 11:53	53.23	OK	11600	2026-09-18 11:54	54.67	OK
11601	2026-09-18 11:55	54.81	OK	11602	2026-09-18 11:56	53.59	OK
11603	2026-09-18 11:57	55.11	OK	11604	2026-09-18 11:58	54.32	OK
11605	2026-09-18 11:59	52.07	OK	11606	2026-09-18 12:00	55.03	OK
11607	2026-09-18 12:01	53.13	OK	11608	2026-09-18 12:02	54.33	OK
11609	2026-09-18 12:03	53.35	OK	11610	2026-09-18 12:04	53.63	OK
11611	2026-09-18 12:05	52.80	OK	11612	2026-09-18 12:06	55.46	OK
11613	2026-09-18 12:07	52.47	OK	11614	2026-09-18 12:08	53.16	OK
11615	2026-09-18 12:09	52.88	OK	11616	2026-09-18 12:10	55.02	OK
11617	2026-09-18 12:11	55.38	OK	11618	2026-09-18 12:12	54.69	OK
11619	2026-09-18 12:13	53.09	OK	11620	2026-09-18 12:14	55.87	OK
11621	2026-09-18 12:15	55.11	OK	11622	2026-09-18 12:16	55.76	OK
1162	2026-09-18 12:17	52.37	OK	1162	2026-09-18 12:18	54.99	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
11625	2026-09-18 12:19	51.83	OK	11626	2026-09-18 12:20	54.99	OK
11627	2026-09-18 12:21	54.93	OK	11628	2026-09-18 12:22	52.01	OK
11629	2026-09-18 12:23	53.15	OK	11630	2026-09-18 12:24	54.30	OK
11631	2026-09-18 12:25	55.24	OK	11632	2026-09-18 12:26	51.96	OK
11633	2026-09-18 12:27	54.09	OK	11634	2026-09-18 12:28	52.83	OK
11635	2026-09-18 12:29	53.34	OK	11636	2026-09-18 12:30	52.08	OK
11637	2026-09-18 12:31	54.26	OK	11638	2026-09-18 12:32	53.68	OK
11639	2026-09-18 12:33	53.63	OK	11640	2026-09-18 12:34	55.02	OK
11641	2026-09-18 12:35	54.83	OK	11642	2026-09-18 12:36	53.41	OK
11643	2026-09-18 12:37	55.03	OK	11644	2026-09-18 12:38	54.47	OK
11645	2026-09-18 12:39	55.30	OK	11646	2026-09-18 12:40	55.43	OK
11647	2026-09-18 12:41	52.39	OK	11648	2026-09-18 12:42	55.10	OK
11649	2026-09-18 12:43	54.14	OK	11650	2026-09-18 12:44	53.64	OK
11651	2026-09-18 12:45	56.01	OK	11652	2026-09-18 12:46	53.70	OK
11653	2026-09-18 12:47	56.22	OK	11654	2026-09-18 12:48	54.77	OK
11655	2026-09-18 12:49	53.18	OK	11656	2026-09-18 12:50	53.03	OK
11657	2026-09-18 12:51	52.59	OK	11658	2026-09-18 12:52	53.83	OK
11659	2026-09-18 12:53	56.14	OK	11660	2026-09-18 12:54	53.13	OK
11661	2026-09-18 12:55	55.00	OK	11662	2026-09-18 12:56	55.88	OK
11663	2026-09-18 12:57	52.96	OK	11664	2026-09-18 12:58	55.08	OK
11665	2026-09-18 12:59	51.80	OK	11666	2026-09-18 13:00	55.01	OK
11667	2026-09-18 13:01	53.84	OK	11668	2026-09-18 13:02	56.01	OK
11669	2026-09-18 13:03	55.08	OK	11670	2026-09-18 13:04	55.41	OK
11671	2026-09-18 13:05	55.14	OK	11672	2026-09-18 13:06	52.82	OK
11673	2026-09-18 13:07	52.97	OK	11674	2026-09-18 13:08	52.60	OK
11675	2026-09-18 13:09	52.13	OK	11676	2026-09-18 13:10	55.82	OK
11677	2026-09-18 13:11	54.37	OK	11678	2026-09-18 13:12	51.60	OK
11679	2026-09-18 13:13	53.14	OK	11680	2026-09-18 13:14	53.14	OK
11681	2026-09-18 13:15	55.16	OK	11682	2026-09-18 13:16	52.79	OK
1168	2026-09-18 13:17	53.96	OK	1168	2026-09-18 13:18	51.72	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
11685	2026-09-18 13:19	53.07	OK	11686	2026-09-18 13:20	52.98	OK
11687	2026-09-18 13:21	54.97	OK	11688	2026-09-18 13:22	53.04	OK
11689	2026-09-18 13:23	52.62	OK	11690	2026-09-18 13:24	53.03	OK
11691	2026-09-18 13:25	53.85	OK	11692	2026-09-18 13:26	53.91	OK
11693	2026-09-18 13:27	53.64	OK	11694	2026-09-18 13:28	53.94	OK
11695	2026-09-18 13:29	54.58	OK	11696	2026-09-18 13:30	54.55	OK
11697	2026-09-18 13:31	52.89	OK	11698	2026-09-18 13:32	53.83	OK
11699	2026-09-18 13:33	50.86	OK	11700	2026-09-18 13:34	55.35	OK
11701	2026-09-18 13:35	53.28	OK	11702	2026-09-18 13:36	53.25	OK
11703	2026-09-18 13:37	55.18	OK	11704	2026-09-18 13:38	55.26	OK
11705	2026-09-18 13:39	54.08	OK	11706	2026-09-18 13:40	52.42	OK
11707	2026-09-18 13:41	51.52	OK	11708	2026-09-18 13:42	53.87	OK
11709	2026-09-18 13:43	53.19	OK	11710	2026-09-18 13:44	54.50	OK
11711	2026-09-18 13:45	53.50	OK	11712	2026-09-18 13:46	52.61	OK
11713	2026-09-18 13:47	52.61	OK	11714	2026-09-18 13:48	51.87	OK
11715	2026-09-18 13:49	54.02	OK	11716	2026-09-18 13:50	53.13	OK
11717	2026-09-18 13:51	55.25	OK	11718	2026-09-18 13:52	54.03	OK
11719	2026-09-18 13:53	53.35	OK	11720	2026-09-18 13:54	53.22	OK
11721	2026-09-18 13:55	52.73	OK	11722	2026-09-18 13:56	53.46	OK
11723	2026-09-18 13:57	52.39	OK	11724	2026-09-18 13:58	54.42	OK
11725	2026-09-18 13:59	53.11	OK	11726	2026-09-18 14:00	53.27	OK
11727	2026-09-18 14:01	55.76	OK	11728	2026-09-18 14:02	54.07	OK
11729	2026-09-18 14:03	52.39	OK	11730	2026-09-18 14:04	53.23	OK
11731	2026-09-18 14:05	55.41	OK	11732	2026-09-18 14:06	52.72	OK
11733	2026-09-18 14:07	51.92	OK	11734	2026-09-18 14:08	52.75	OK
11735	2026-09-18 14:09	53.26	OK	11736	2026-09-18 14:10	55.26	OK
11737	2026-09-18 14:11	53.28	OK	11738	2026-09-18 14:12	51.81	OK
11739	2026-09-18 14:13	52.34	OK	11740	2026-09-18 14:14	53.25	OK
11741	2026-09-18 14:15	51.84	OK	11742	2026-09-18 14:16	51.97	OK
1174	2026-09-18 14:17	52.80	OK	1174	2026-09-18 14:18	54.61	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
11745	2026-09-18 14:19	53.24	OK	11746	2026-09-18 14:20	53.18	OK
11747	2026-09-18 14:21	54.27	OK	11748	2026-09-18 14:22	50.83	OK
11749	2026-09-18 14:23	52.47	OK	11750	2026-09-18 14:24	51.93	OK
11751	2026-09-18 14:25	53.38	OK	11752	2026-09-18 14:26	51.61	OK
11753	2026-09-18 14:27	53.33	OK	11754	2026-09-18 14:28	53.01	OK
11755	2026-09-18 14:29	52.20	OK	11756	2026-09-18 14:30	53.98	OK
11757	2026-09-18 14:31	53.67	OK	11758	2026-09-18 14:32	51.49	OK
11759	2026-09-18 14:33	52.26	OK	11760	2026-09-18 14:34	53.55	OK
11761	2026-09-18 14:35	51.23	OK	11762	2026-09-18 14:36	51.87	OK
11763	2026-09-18 14:37	51.00	OK	11764	2026-09-18 14:38	51.59	OK
11765	2026-09-18 14:39	54.71	OK	11766	2026-09-18 14:40	55.01	OK
11767	2026-09-18 14:41	53.19	OK	11768	2026-09-18 14:42	52.88	OK
11769	2026-09-18 14:43	52.55	OK	11770	2026-09-18 14:44	53.70	OK
11771	2026-09-18 14:45	52.09	OK	11772	2026-09-18 14:46	54.80	OK
11773	2026-09-18 14:47	51.82	OK	11774	2026-09-18 14:48	53.15	OK
11775	2026-09-18 14:49	53.77	OK	11776	2026-09-18 14:50	53.06	OK
11777	2026-09-18 14:51	50.14	OK	11778	2026-09-18 14:52	52.25	OK
11779	2026-09-18 14:53	53.10	OK	11780	2026-09-18 14:54	52.49	OK
11781	2026-09-18 14:55	51.47	OK	11782	2026-09-18 14:56	52.26	OK
11783	2026-09-18 14:57	54.08	OK	11784	2026-09-18 14:58	50.81	OK
11785	2026-09-18 14:59	52.33	OK	11786	2026-09-18 15:00	52.16	OK
11787	2026-09-18 15:01	49.50	OK	11788	2026-09-18 15:02	54.17	OK
11789	2026-09-18 15:03	53.12	OK	11790	2026-09-18 15:04	51.96	OK
11791	2026-09-18 15:05	53.05	OK	11792	2026-09-18 15:06	49.93	OK
11793	2026-09-18 15:07	52.23	OK	11794	2026-09-18 15:08	52.53	OK
11795	2026-09-18 15:09	52.91	OK	11796	2026-09-18 15:10	51.78	OK
11797	2026-09-18 15:11	53.68	OK	11798	2026-09-18 15:12	52.48	OK
11799	2026-09-18 15:13	52.26	OK	11800	2026-09-18 15:14	52.62	OK
11801	2026-09-18 15:15	52.92	OK	11802	2026-09-18 15:16	52.59	OK
1180	2026-09-18 15:17	52.83	OK	1180	2026-09-18 15:18	52.15	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
11805	2026-09-18 15:19	51.09	OK	11806	2026-09-18 15:20	51.53	OK
11807	2026-09-18 15:21	50.80	OK	11808	2026-09-18 15:22	51.96	OK
11809	2026-09-18 15:23	54.60	OK	11810	2026-09-18 15:24	50.82	OK
11811	2026-09-18 15:25	51.01	OK	11812	2026-09-18 15:26	51.50	OK
11813	2026-09-18 15:27	52.02	OK	11814	2026-09-18 15:28	51.17	OK
11815	2026-09-18 15:29	52.99	OK	11816	2026-09-18 15:30	50.75	OK
11817	2026-09-18 15:31	50.29	OK	11818	2026-09-18 15:32	51.50	OK
11819	2026-09-18 15:33	53.58	OK	11820	2026-09-18 15:34	49.99	OK
11821	2026-09-18 15:35	52.13	OK	11822	2026-09-18 15:36	51.20	OK
11823	2026-09-18 15:37	52.88	OK	11824	2026-09-18 15:38	51.22	OK
11825	2026-09-18 15:39	52.82	OK	11826	2026-09-18 15:40	52.47	OK
11827	2026-09-18 15:41	52.22	OK	11828	2026-09-18 15:42	51.33	OK
11829	2026-09-18 15:43	51.59	OK	11830	2026-09-18 15:44	52.51	OK
11831	2026-09-18 15:45	49.89	OK	11832	2026-09-18 15:46	50.70	OK
11833	2026-09-18 15:47	49.66	OK	11834	2026-09-18 15:48	51.93	OK
11835	2026-09-18 15:49	50.95	OK	11836	2026-09-18 15:50	51.02	OK
11837	2026-09-18 15:51	51.12	OK	11838	2026-09-18 15:52	49.80	OK
11839	2026-09-18 15:53	50.99	OK	11840	2026-09-18 15:54	51.89	OK
11841	2026-09-18 15:55	50.87	OK	11842	2026-09-18 15:56	51.07	OK
11843	2026-09-18 15:57	51.40	OK	11844	2026-09-18 15:58	49.75	OK
11845	2026-09-18 15:59	51.46	OK	11846	2026-09-18 16:00	51.17	OK
11847	2026-09-18 16:01	51.11	OK	11848	2026-09-18 16:02	53.00	OK
11849	2026-09-18 16:03	51.25	OK	11850	2026-09-18 16:04	52.42	OK
11851	2026-09-18 16:05	50.43	OK	11852	2026-09-18 16:06	51.15	OK
11853	2026-09-18 16:07	51.20	OK	11854	2026-09-18 16:08	52.30	OK
11855	2026-09-18 16:09	49.81	OK	11856	2026-09-18 16:10	49.38	OK
11857	2026-09-18 16:11	49.93	OK	11858	2026-09-18 16:12	51.19	OK
11859	2026-09-18 16:13	52.07	OK	11860	2026-09-18 16:14	51.83	OK
11861	2026-09-18 16:15	51.58	OK	11862	2026-09-18 16:16	49.52	OK
1186	2026-09-18 16:17	48.84	OK	1186	2026-09-18 16:18	50.28	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
11865	2026-09-18 16:19	51.20	OK	11866	2026-09-18 16:20	52.18	OK
11867	2026-09-18 16:21	52.31	OK	11868	2026-09-18 16:22	48.98	OK
11869	2026-09-18 16:23	48.57	OK	11870	2026-09-18 16:24	50.68	OK
11871	2026-09-18 16:25	50.27	OK	11872	2026-09-18 16:26	50.65	OK
11873	2026-09-18 16:27	49.82	OK	11874	2026-09-18 16:28	52.74	OK
11875	2026-09-18 16:29	51.50	OK	11876	2026-09-18 16:30	51.18	OK
11877	2026-09-18 16:31	50.94	OK	11878	2026-09-18 16:32	50.28	OK
11879	2026-09-18 16:33	49.21	OK	11880	2026-09-18 16:34	50.97	OK
11881	2026-09-18 16:35	51.09	OK	11882	2026-09-18 16:36	50.95	OK
11883	2026-09-18 16:37	49.34	OK	11884	2026-09-18 16:38	48.73	OK
11885	2026-09-18 16:39	51.48	OK	11886	2026-09-18 16:40	50.58	OK
11887	2026-09-18 16:41	48.89	OK	11888	2026-09-18 16:42	49.41	OK
11889	2026-09-18 16:43	50.72	OK	11890	2026-09-18 16:44	51.42	OK
11891	2026-09-18 16:45	51.70	OK	11892	2026-09-18 16:46	49.13	OK
11893	2026-09-18 16:47	48.95	OK	11894	2026-09-18 16:48	48.59	OK
11895	2026-09-18 16:49	49.61	OK	11896	2026-09-18 16:50	52.58	OK
11897	2026-09-18 16:51	50.70	OK	11898	2026-09-18 16:52	50.37	OK
11899	2026-09-18 16:53	50.54	OK	11900	2026-09-18 16:54	51.08	OK
11901	2026-09-18 16:55	48.95	OK	11902	2026-09-18 16:56	49.86	OK
11903	2026-09-18 16:57	51.32	OK	11904	2026-09-18 16:58	50.21	OK
11905	2026-09-18 16:59	49.57	OK	11906	2026-09-18 17:00	49.27	OK
11907	2026-09-18 17:01	50.82	OK	11908	2026-09-18 17:02	48.53	OK
11909	2026-09-18 17:03	48.29	OK	11910	2026-09-18 17:04	50.50	OK
11911	2026-09-18 17:05	48.67	OK	11912	2026-09-18 17:06	48.82	OK
11913	2026-09-18 17:07	51.28	OK	11914	2026-09-18 17:08	49.51	OK
11915	2026-09-18 17:09	48.98	OK	11916	2026-09-18 17:10	49.93	OK
11917	2026-09-18 17:11	50.66	OK	11918	2026-09-18 17:12	50.67	OK
11919	2026-09-18 17:13	49.38	OK	11920	2026-09-18 17:14	49.76	OK
11921	2026-09-18 17:15	48.61	OK	11922	2026-09-18 17:16	50.56	OK
1192	2026-09-18 17:17	50.69	OK	1192	2026-09-18 17:18	49.69	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
11925	2026-09-18 17:19	49.52	OK	11926	2026-09-18 17:20	49.64	OK
11927	2026-09-18 17:21	49.51	OK	11928	2026-09-18 17:22	49.46	OK
11929	2026-09-18 17:23	50.55	OK	11930	2026-09-18 17:24	50.25	OK
11931	2026-09-18 17:25	49.79	OK	11932	2026-09-18 17:26	50.69	OK
11933	2026-09-18 17:27	49.30	OK	11934	2026-09-18 17:28	49.40	OK
11935	2026-09-18 17:29	49.74	OK	11936	2026-09-18 17:30	48.98	OK
11937	2026-09-18 17:31	49.33	OK	11938	2026-09-18 17:32	47.25	OK
11939	2026-09-18 17:33	49.91	OK	11940	2026-09-18 17:34	48.47	OK
11941	2026-09-18 17:35	48.66	OK	11942	2026-09-18 17:36	51.51	OK
11943	2026-09-18 17:37	49.34	OK	11944	2026-09-18 17:38	48.64	OK
11945	2026-09-18 17:39	48.29	OK	11946	2026-09-18 17:40	51.49	OK
11947	2026-09-18 17:41	49.80	OK	11948	2026-09-18 17:42	51.59	OK
11949	2026-09-18 17:43	49.68	OK	11950	2026-09-18 17:44	48.27	OK
11951	2026-09-18 17:45	50.36	OK	11952	2026-09-18 17:46	49.70	OK
11953	2026-09-18 17:47	47.23	OK	11954	2026-09-18 17:48	51.36	OK
11955	2026-09-18 17:49	48.52	OK	11956	2026-09-18 17:50	49.47	OK
11957	2026-09-18 17:51	48.21	OK	11958	2026-09-18 17:52	49.30	OK
11959	2026-09-18 17:53	48.47	OK	11960	2026-09-18 17:54	48.29	OK
11961	2026-09-18 17:55	49.60	OK	11962	2026-09-18 17:56	48.47	OK
11963	2026-09-18 17:57	50.05	OK	11964	2026-09-18 17:58	49.20	OK
11965	2026-09-18 17:59	48.95	OK	11966	2026-09-18 18:00	49.97	OK
11967	2026-09-18 18:01	50.69	OK	11968	2026-09-18 18:02	48.37	OK
11969	2026-09-18 18:03	47.98	OK	11970	2026-09-18 18:04	50.30	OK
11971	2026-09-18 18:05	47.40	OK	11972	2026-09-18 18:06	49.21	OK
11973	2026-09-18 18:07	48.70	OK	11974	2026-09-18 18:08	49.36	OK
11975	2026-09-18 18:09	47.50	OK	11976	2026-09-18 18:10	49.79	OK
11977	2026-09-18 18:11	47.83	OK	11978	2026-09-18 18:12	48.01	OK
11979	2026-09-18 18:13	47.69	OK	11980	2026-09-18 18:14	50.58	OK
11981	2026-09-18 18:15	48.46	OK	11982	2026-09-18 18:16	50.12	OK
1198	2026-09-18 18:17	46.43	OK	1198	2026-09-18 18:18	49.67	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
11985	2026-09-18 18:19	48.22	OK	11986	2026-09-18 18:20	45.53	OK
11987	2026-09-18 18:21	48.92	OK	11988	2026-09-18 18:22	49.61	OK
11989	2026-09-18 18:23	47.60	OK	11990	2026-09-18 18:24	49.11	OK
11991	2026-09-18 18:25	47.18	OK	11992	2026-09-18 18:26	46.46	OK
11993	2026-09-18 18:27	49.46	OK	11994	2026-09-18 18:28	48.70	OK
11995	2026-09-18 18:29	50.41	OK	11996	2026-09-18 18:30	46.95	OK
11997	2026-09-18 18:31	49.05	OK	11998	2026-09-18 18:32	47.30	OK
11999	2026-09-18 18:33	46.77	OK	12000	2026-09-18 18:34	46.48	OK
12001	2026-09-18 18:35	47.41	OK	12002	2026-09-18 18:36	46.53	OK
12003	2026-09-18 18:37	47.22	OK	12004	2026-09-18 18:38	47.59	OK
12005	2026-09-18 18:39	49.66	OK	12006	2026-09-18 18:40	48.70	OK
12007	2026-09-18 18:41	48.36	OK	12008	2026-09-18 18:42	48.81	OK
12009	2026-09-18 18:43	47.23	OK	12010	2026-09-18 18:44	49.53	OK
12011	2026-09-18 18:45	46.94	OK	12012	2026-09-18 18:46	48.49	OK
12013	2026-09-18 18:47	49.09	OK	12014	2026-09-18 18:48	47.74	OK
12015	2026-09-18 18:49	48.73	OK	12016	2026-09-18 18:50	45.88	OK
12017	2026-09-18 18:51	48.00	OK	12018	2026-09-18 18:52	47.15	OK
12019	2026-09-18 18:53	49.07	OK	12020	2026-09-18 18:54	47.91	OK
12021	2026-09-18 18:55	49.76	OK	12022	2026-09-18 18:56	47.18	OK
12023	2026-09-18 18:57	48.01	OK	12024	2026-09-18 18:58	46.10	OK
12025	2026-09-18 18:59	48.17	OK	12026	2026-09-18 19:00	47.74	OK
12027	2026-09-18 19:01	47.64	OK	12028	2026-09-18 19:02	47.92	OK
12029	2026-09-18 19:03	46.49	OK	12030	2026-09-18 19:04	48.85	OK
12031	2026-09-18 19:05	45.68	OK	12032	2026-09-18 19:06	47.86	OK
12033	2026-09-18 19:07	46.87	OK	12034	2026-09-18 19:08	48.50	OK
12035	2026-09-18 19:09	49.60	OK	12036	2026-09-18 19:10	47.74	OK
12037	2026-09-18 19:11	46.12	OK	12038	2026-09-18 19:12	45.46	OK
12039	2026-09-18 19:13	47.34	OK	12040	2026-09-18 19:14	48.22	OK
12041	2026-09-18 19:15	48.35	OK	12042	2026-09-18 19:16	44.93	OK
1204	2026-09-18 19:17	48.61	OK	1204	2026-09-18 19:18	46.31	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
12045	2026-09-18 19:19	47.15	OK	12046	2026-09-18 19:20	46.44	OK
12047	2026-09-18 19:21	46.72	OK	12048	2026-09-18 19:22	45.60	OK
12049	2026-09-18 19:23	47.61	OK	12050	2026-09-18 19:24	45.71	OK
12051	2026-09-18 19:25	45.79	OK	12052	2026-09-18 19:26	48.46	OK
12053	2026-09-18 19:27	48.30	OK	12054	2026-09-18 19:28	47.51	OK
12055	2026-09-18 19:29	47.65	OK	12056	2026-09-18 19:30	47.37	OK
12057	2026-09-18 19:31	48.59	OK	12058	2026-09-18 19:32	47.35	OK
12059	2026-09-18 19:33	48.72	OK	12060	2026-09-18 19:34	45.39	OK
12061	2026-09-18 19:35	47.55	OK	12062	2026-09-18 19:36	46.63	OK
12063	2026-09-18 19:37	47.96	OK	12064	2026-09-18 19:38	46.58	OK
12065	2026-09-18 19:39	47.20	OK	12066	2026-09-18 19:40	46.07	OK
12067	2026-09-18 19:41	45.63	OK	12068	2026-09-18 19:42	46.49	OK
12069	2026-09-18 19:43	48.78	OK	12070	2026-09-18 19:44	45.93	OK
12071	2026-09-18 19:45	45.76	OK	12072	2026-09-18 19:46	46.89	OK
12073	2026-09-18 19:47	45.79	OK	12074	2026-09-18 19:48	47.11	OK
12075	2026-09-18 19:49	48.11	OK	12076	2026-09-18 19:50	47.29	OK
12077	2026-09-18 19:51	49.22	OK	12078	2026-09-18 19:52	45.70	OK
12079	2026-09-18 19:53	45.30	OK	12080	2026-09-18 19:54	46.71	OK
12081	2026-09-18 19:55	47.75	OK	12082	2026-09-18 19:56	48.57	OK
12083	2026-09-18 19:57	43.92	OK	12084	2026-09-18 19:58	47.70	OK
12085	2026-09-18 19:59	46.44	OK	12086	2026-09-18 20:00	48.24	OK
12087	2026-09-18 20:01	46.53	OK	12088	2026-09-18 20:02	45.70	OK
12089	2026-09-18 20:03	44.30	OK	12090	2026-09-18 20:04	47.64	OK
12091	2026-09-18 20:05	46.10	OK	12092	2026-09-18 20:06	45.95	OK
12093	2026-09-18 20:07	44.30	OK	12094	2026-09-18 20:08	47.64	OK
12095	2026-09-18 20:09	44.44	OK	12096	2026-09-18 20:10	45.12	OK
12097	2026-09-18 20:11	45.88	OK	12098	2026-09-18 20:12	48.54	OK
12099	2026-09-18 20:13	46.14	OK	12100	2026-09-18 20:14	44.94	OK
12101	2026-09-18 20:15	48.31	OK	12102	2026-09-18 20:16	46.33	OK
1210	2026-09-18 20:17	44.78	OK	1210	2026-09-18 20:18	45.93	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
12105	2026-09-18 20:19	45.54	OK	12106	2026-09-18 20:20	46.77	OK
12107	2026-09-18 20:21	44.03	OK	12108	2026-09-18 20:22	45.89	OK
12109	2026-09-18 20:23	44.92	OK	12110	2026-09-18 20:24	46.15	OK
12111	2026-09-18 20:25	47.77	OK	12112	2026-09-18 20:26	47.98	OK
12113	2026-09-18 20:27	46.02	OK	12114	2026-09-18 20:28	44.13	OK
12115	2026-09-18 20:29	46.35	OK	12116	2026-09-18 20:30	46.21	OK
12117	2026-09-18 20:31	48.12	OK	12118	2026-09-18 20:32	46.97	OK
12119	2026-09-18 20:33	45.43	OK	12120	2026-09-18 20:34	46.34	OK
12121	2026-09-18 20:35	43.83	OK	12122	2026-09-18 20:36	47.01	OK
12123	2026-09-18 20:37	47.13	OK	12124	2026-09-18 20:38	46.61	OK
12125	2026-09-18 20:39	43.85	OK	12126	2026-09-18 20:40	45.45	OK
12127	2026-09-18 20:41	45.94	OK	12128	2026-09-18 20:42	47.06	OK
12129	2026-09-18 20:43	43.58	OK	12130	2026-09-18 20:44	46.34	OK
12131	2026-09-18 20:45	46.22	OK	12132	2026-09-18 20:46	45.31	OK
12133	2026-09-18 20:47	44.28	OK	12134	2026-09-18 20:48	44.20	OK
12135	2026-09-18 20:49	45.72	OK	12136	2026-09-18 20:50	46.91	OK
12137	2026-09-18 20:51	46.51	OK	12138	2026-09-18 20:52	45.99	OK
12139	2026-09-18 20:53	45.65	OK	12140	2026-09-18 20:54	45.49	OK
12141	2026-09-18 20:55	47.55	OK	12142	2026-09-18 20:56	46.29	OK
12143	2026-09-18 20:57	44.25	OK	12144	2026-09-18 20:58	44.65	OK
12145	2026-09-18 20:59	45.01	OK	12146	2026-09-18 21:00	47.66	OK
12147	2026-09-18 21:01	45.57	OK	12148	2026-09-18 21:02	43.94	OK
12149	2026-09-18 21:03	46.16	OK	12150	2026-09-18 21:04	44.00	OK
12151	2026-09-18 21:05	45.59	OK	12152	2026-09-18 21:06	46.11	OK
12153	2026-09-18 21:07	45.46	OK	12154	2026-09-18 21:08	43.77	OK
12155	2026-09-18 21:09	43.42	OK	12156	2026-09-18 21:10	44.21	OK
12157	2026-09-18 21:11	44.90	OK	12158	2026-09-18 21:12	45.72	OK
12159	2026-09-18 21:13	43.65	OK	12160	2026-09-18 21:14	44.99	OK
12161	2026-09-18 21:15	46.19	OK	12162	2026-09-18 21:16	43.11	OK
1216	2026-09-18 21:17	42.93	OK	1216	2026-09-18 21:18	44.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
12165	2026-09-18 21:19	45.48	OK	12166	2026-09-18 21:20	44.44	OK
12167	2026-09-18 21:21	46.44	OK	12168	2026-09-18 21:22	46.18	OK
12169	2026-09-18 21:23	44.11	OK	12170	2026-09-18 21:24	46.90	OK
12171	2026-09-18 21:25	45.15	OK	12172	2026-09-18 21:26	45.07	OK
12173	2026-09-18 21:27	44.83	OK	12174	2026-09-18 21:28	43.86	OK
12175	2026-09-18 21:29	45.36	OK	12176	2026-09-18 21:30	46.80	OK
12177	2026-09-18 21:31	44.89	OK	12178	2026-09-18 21:32	44.62	OK
12179	2026-09-18 21:33	42.81	OK	12180	2026-09-18 21:34	45.89	OK
12181	2026-09-18 21:35	46.72	OK	12182	2026-09-18 21:36	45.08	OK
12183	2026-09-18 21:37	44.71	OK	12184	2026-09-18 21:38	45.14	OK
12185	2026-09-18 21:39	45.59	OK	12186	2026-09-18 21:40	46.29	OK
12187	2026-09-18 21:41	45.44	OK	12188	2026-09-18 21:42	46.52	OK
12189	2026-09-18 21:43	46.13	OK	12190	2026-09-18 21:44	44.87	OK
12191	2026-09-18 21:45	45.87	OK	12192	2026-09-18 21:46	43.90	OK
12193	2026-09-18 21:47	45.58	OK	12194	2026-09-18 21:48	42.78	OK
12195	2026-09-18 21:49	46.66	OK	12196	2026-09-18 21:50	46.20	OK
12197	2026-09-18 21:51	45.39	OK	12198	2026-09-18 21:52	43.15	OK
12199	2026-09-18 21:53	45.39	OK	12200	2026-09-18 21:54	46.22	OK
12201	2026-09-18 21:55	44.46	OK	12202	2026-09-18 21:56	44.67	OK
12203	2026-09-18 21:57	44.39	OK	12204	2026-09-18 21:58	45.34	OK
12205	2026-09-18 21:59	44.44	OK	12206	2026-09-18 22:00	44.22	OK
12207	2026-09-18 22:01	43.61	OK	12208	2026-09-18 22:02	46.19	OK
12209	2026-09-18 22:03	44.23	OK	12210	2026-09-18 22:04	44.72	OK
12211	2026-09-18 22:05	44.08	OK	12212	2026-09-18 22:06	46.40	OK
12213	2026-09-18 22:07	43.13	OK	12214	2026-09-18 22:08	45.24	OK
12215	2026-09-18 22:09	44.12	OK	12216	2026-09-18 22:10	45.97	OK
12217	2026-09-18 22:11	44.80	OK	12218	2026-09-18 22:12	44.96	OK
12219	2026-09-18 22:13	45.46	OK	12220	2026-09-18 22:14	45.71	OK
12221	2026-09-18 22:15	45.18	OK	12222	2026-09-18 22:16	42.86	OK
1222	2026-09-18 22:17	44.19	OK	1222	2026-09-18 22:18	46.21	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
12225	2026-09-18 22:19	44.81	OK	12226	2026-09-18 22:20	45.99	OK
12227	2026-09-18 22:21	43.42	OK	12228	2026-09-18 22:22	43.72	OK
12229	2026-09-18 22:23	46.31	OK	12230	2026-09-18 22:24	45.51	OK
12231	2026-09-18 22:25	44.48	OK	12232	2026-09-18 22:26	45.40	OK
12233	2026-09-18 22:27	43.50	OK	12234	2026-09-18 22:28	44.63	OK
12235	2026-09-18 22:29	44.68	OK	12236	2026-09-18 22:30	44.36	OK
12237	2026-09-18 22:31	44.34	OK	12238	2026-09-18 22:32	45.45	OK
12239	2026-09-18 22:33	43.56	OK	12240	2026-09-18 22:34	43.99	OK
12241	2026-09-18 22:35	44.33	OK	12242	2026-09-18 22:36	44.78	OK
12243	2026-09-18 22:37	46.17	OK	12244	2026-09-18 22:38	46.12	OK
12245	2026-09-18 22:39	43.31	OK	12246	2026-09-18 22:40	45.08	OK
12247	2026-09-18 22:41	44.66	OK	12248	2026-09-18 22:42	45.38	OK
12249	2026-09-18 22:43	44.99	OK	12250	2026-09-18 22:44	44.41	OK
12251	2026-09-18 22:45	45.16	OK	12252	2026-09-18 22:46	44.06	OK
12253	2026-09-18 22:47	41.94	OK	12254	2026-09-18 22:48	44.87	OK
12255	2026-09-18 22:49	45.46	OK	12256	2026-09-18 22:50	42.58	OK
12257	2026-09-18 22:51	43.76	OK	12258	2026-09-18 22:52	44.15	OK
12259	2026-09-18 22:53	46.35	OK	12260	2026-09-18 22:54	45.08	OK
12261	2026-09-18 22:55	45.81	OK	12262	2026-09-18 22:56	45.19	OK
12263	2026-09-18 22:57	44.00	OK	12264	2026-09-18 22:58	45.98	OK
12265	2026-09-18 22:59	44.61	OK	12266	2026-09-18 23:00	45.12	OK
12267	2026-09-18 23:01	42.21	OK	12268	2026-09-18 23:02	43.60	OK
12269	2026-09-18 23:03	45.51	OK	12270	2026-09-18 23:04	45.28	OK
12271	2026-09-18 23:05	44.84	OK	12272	2026-09-18 23:06	43.76	OK
12273	2026-09-18 23:07	45.13	OK	12274	2026-09-18 23:08	43.23	OK
12275	2026-09-18 23:09	44.73	OK	12276	2026-09-18 23:10	45.72	OK
12277	2026-09-18 23:11	44.34	OK	12278	2026-09-18 23:12	45.35	OK
12279	2026-09-18 23:13	45.26	OK	12280	2026-09-18 23:14	46.74	OK
12281	2026-09-18 23:15	43.95	OK	12282	2026-09-18 23:16	44.93	OK
1228	2026-09-18 23:17	46.54	OK	1228	2026-09-18 23:18	43.25	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
12285	2026-09-18 23:19	45.13	OK	12286	2026-09-18 23:20	45.61	OK
12287	2026-09-18 23:21	44.61	OK	12288	2026-09-18 23:22	46.02	OK
12289	2026-09-18 23:23	44.30	OK	12290	2026-09-18 23:24	44.61	OK
12291	2026-09-18 23:25	46.31	OK	12292	2026-09-18 23:26	45.28	OK
12293	2026-09-18 23:27	45.13	OK	12294	2026-09-18 23:28	44.21	OK
12295	2026-09-18 23:29	44.74	OK	12296	2026-09-18 23:30	45.13	OK
12297	2026-09-18 23:31	45.39	OK	12298	2026-09-18 23:32	43.29	OK
12299	2026-09-18 23:33	46.63	OK	12300	2026-09-18 23:34	44.39	OK
12301	2026-09-18 23:35	43.66	OK	12302	2026-09-18 23:36	43.86	OK
12303	2026-09-18 23:37	43.93	OK	12304	2026-09-18 23:38	45.59	OK
12305	2026-09-18 23:39	45.00	OK	12306	2026-09-18 23:40	42.86	OK
12307	2026-09-18 23:41	44.59	OK	12308	2026-09-18 23:42	46.61	OK
12309	2026-09-18 23:43	45.61	OK	12310	2026-09-18 23:44	44.96	OK
12311	2026-09-18 23:45	43.68	OK	12312	2026-09-18 23:46	44.74	OK
12313	2026-09-18 23:47	43.60	OK	12314	2026-09-18 23:48	44.95	OK
12315	2026-09-18 23:49	45.58	OK	12316	2026-09-18 23:50	44.59	OK
12317	2026-09-18 23:51	45.16	OK	12318	2026-09-18 23:52	43.04	OK
12319	2026-09-18 23:53	45.42	OK	12320	2026-09-18 23:54	45.07	OK
12321	2026-09-18 23:55	42.59	OK	12322	2026-09-18 23:56	43.07	OK
12323	2026-09-18 23:57	43.91	OK	12324	2026-09-18 23:58	43.47	OK
12325	2026-09-18 23:59	43.35	OK	12326	2026-09-19 00:00	44.75	OK
12327	2026-09-19 00:01	42.19	OK	12328	2026-09-19 00:02	43.61	OK
12329	2026-09-19 00:03	44.94	OK	12330	2026-09-19 00:04	45.09	OK
12331	2026-09-19 00:05	43.49	OK	12332	2026-09-19 00:06	44.09	OK
12333	2026-09-19 00:07	44.32	OK	12334	2026-09-19 00:08	44.03	OK
12335	2026-09-19 00:09	44.65	OK	12336	2026-09-19 00:10	43.18	OK
12337	2026-09-19 00:11	45.86	OK	12338	2026-09-19 00:12	46.04	OK
12339	2026-09-19 00:13	46.54	OK	12340	2026-09-19 00:14	45.45	OK
12341	2026-09-19 00:15	46.91	OK	12342	2026-09-19 00:16	44.60	OK
1234	2026-09-19 00:17	45.20	OK	1234	2026-09-19 00:18	44.02	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
12345	2026-09-19 00:19	43.95	OK	12346	2026-09-19 00:20	43.65	OK
12347	2026-09-19 00:21	45.27	OK	12348	2026-09-19 00:22	45.30	OK
12349	2026-09-19 00:23	44.26	OK	12350	2026-09-19 00:24	44.21	OK
12351	2026-09-19 00:25	44.80	OK	12352	2026-09-19 00:26	43.93	OK
12353	2026-09-19 00:27	46.45	OK	12354	2026-09-19 00:28	44.65	OK
12355	2026-09-19 00:29	45.38	OK	12356	2026-09-19 00:30	44.89	OK
12357	2026-09-19 00:31	46.52	OK	12358	2026-09-19 00:32	44.17	OK
12359	2026-09-19 00:33	43.20	OK	12360	2026-09-19 00:34	45.57	OK
12361	2026-09-19 00:35	44.02	OK	12362	2026-09-19 00:36	44.72	OK
12363	2026-09-19 00:37	43.92	OK	12364	2026-09-19 00:38	46.24	OK
12365	2026-09-19 00:39	45.46	OK	12366	2026-09-19 00:40	43.81	OK
12367	2026-09-19 00:41	43.75	OK	12368	2026-09-19 00:42	43.97	OK
12369	2026-09-19 00:43	44.12	OK	12370	2026-09-19 00:44	45.36	OK
12371	2026-09-19 00:45	44.09	OK	12372	2026-09-19 00:46	45.15	OK
12373	2026-09-19 00:47	44.10	OK	12374	2026-09-19 00:48	44.55	OK
12375	2026-09-19 00:49	46.14	OK	12376	2026-09-19 00:50	43.50	OK
12377	2026-09-19 00:51	45.62	OK	12378	2026-09-19 00:52	46.17	OK
12379	2026-09-19 00:53	44.63	OK	12380	2026-09-19 00:54	44.72	OK
12381	2026-09-19 00:55	41.98	OK	12382	2026-09-19 00:56	43.97	OK
12383	2026-09-19 00:57	45.35	OK	12384	2026-09-19 00:58	43.47	OK
12385	2026-09-19 00:59	45.25	OK	12386	2026-09-19 01:00	45.67	OK
12387	2026-09-19 01:01	45.77	OK	12388	2026-09-19 01:02	46.14	OK
12389	2026-09-19 01:03	43.76	OK	12390	2026-09-19 01:04	44.03	OK
12391	2026-09-19 01:05	45.17	OK	12392	2026-09-19 01:06	48.05	OK
12393	2026-09-19 01:07	43.72	OK	12394	2026-09-19 01:08	45.66	OK
12395	2026-09-19 01:09	45.16	OK	12396	2026-09-19 01:10	46.92	OK
12397	2026-09-19 01:11	45.77	OK	12398	2026-09-19 01:12	46.40	OK
12399	2026-09-19 01:13	46.84	OK	12400	2026-09-19 01:14	44.03	OK
12401	2026-09-19 01:15	45.54	OK	12402	2026-09-19 01:16	44.55	OK
1240	2026-09-19 01:17	43.53	OK	1240	2026-09-19 01:18	45.91	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
12405	2026-09-19 01:19	43.97	OK	12406	2026-09-19 01:20	42.77	OK
12407	2026-09-19 01:21	46.75	OK	12408	2026-09-19 01:22	45.30	OK
12409	2026-09-19 01:23	43.47	OK	12410	2026-09-19 01:24	45.07	OK
12411	2026-09-19 01:25	45.98	OK	12412	2026-09-19 01:26	43.60	OK
12413	2026-09-19 01:27	45.01	OK	12414	2026-09-19 01:28	44.42	OK
12415	2026-09-19 01:29	45.21	OK	12416	2026-09-19 01:30	45.49	OK
12417	2026-09-19 01:31	44.49	OK	12418	2026-09-19 01:32	45.01	OK
12419	2026-09-19 01:33	45.68	OK	12420	2026-09-19 01:34	45.56	OK
12421	2026-09-19 01:35	45.42	OK	12422	2026-09-19 01:36	45.30	OK
12423	2026-09-19 01:37	44.81	OK	12424	2026-09-19 01:38	43.35	OK
12425	2026-09-19 01:39	43.12	OK	12426	2026-09-19 01:40	44.28	OK
12427	2026-09-19 01:41	46.99	OK	12428	2026-09-19 01:42	46.98	OK
12429	2026-09-19 01:43	48.01	OK	12430	2026-09-19 01:44	43.38	OK
12431	2026-09-19 01:45	43.86	OK	12432	2026-09-19 01:46	47.53	OK
12433	2026-09-19 01:47	44.88	OK	12434	2026-09-19 01:48	46.56	OK
12435	2026-09-19 01:49	45.31	OK	12436	2026-09-19 01:50	45.11	OK
12437	2026-09-19 01:51	43.07	OK	12438	2026-09-19 01:52	45.71	OK
12439	2026-09-19 01:53	46.36	OK	12440	2026-09-19 01:54	45.50	OK
12441	2026-09-19 01:55	47.09	OK	12442	2026-09-19 01:56	45.36	OK
12443	2026-09-19 01:57	46.24	OK	12444	2026-09-19 01:58	45.41	OK
12445	2026-09-19 01:59	46.05	OK	12446	2026-09-19 02:00	45.93	OK
12447	2026-09-19 02:01	46.16	OK	12448	2026-09-19 02:02	45.84	OK
12449	2026-09-19 02:03	45.91	OK	12450	2026-09-19 02:04	45.09	OK
12451	2026-09-19 02:05	47.17	OK	12452	2026-09-19 02:06	43.82	OK
12453	2026-09-19 02:07	45.27	OK	12454	2026-09-19 02:08	46.51	OK
12455	2026-09-19 02:09	47.40	OK	12456	2026-09-19 02:10	46.38	OK
12457	2026-09-19 02:11	45.51	OK	12458	2026-09-19 02:12	44.70	OK
12459	2026-09-19 02:13	47.22	OK	12460	2026-09-19 02:14	46.17	OK
12461	2026-09-19 02:15	45.26	OK	12462	2026-09-19 02:16	47.72	OK
1246	2026-09-19 02:17	45.38	OK	1246	2026-09-19 02:18	46.73	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
12465	2026-09-19 02:19	47.47	OK	12466	2026-09-19 02:20	47.57	OK
12467	2026-09-19 02:21	45.62	OK	12468	2026-09-19 02:22	45.52	OK
12469	2026-09-19 02:23	47.03	OK	12470	2026-09-19 02:24	45.51	OK
12471	2026-09-19 02:25	46.47	OK	12472	2026-09-19 02:26	47.14	OK
12473	2026-09-19 02:27	45.34	OK	12474	2026-09-19 02:28	45.18	OK
12475	2026-09-19 02:29	47.47	OK	12476	2026-09-19 02:30	46.94	OK
12477	2026-09-19 02:31	45.75	OK	12478	2026-09-19 02:32	44.36	OK
12479	2026-09-19 02:33	44.47	OK	12480	2026-09-19 02:34	47.05	OK
12481	2026-09-19 02:35	45.90	OK	12482	2026-09-19 02:36	47.15	OK
12483	2026-09-19 02:37	45.83	OK	12484	2026-09-19 02:38	46.07	OK
12485	2026-09-19 02:39	46.36	OK	12486	2026-09-19 02:40	44.29	OK
12487	2026-09-19 02:41	45.61	OK	12488	2026-09-19 02:42	45.29	OK
12489	2026-09-19 02:43	47.12	OK	12490	2026-09-19 02:44	46.99	OK
12491	2026-09-19 02:45	46.13	OK	12492	2026-09-19 02:46	46.09	OK
12493	2026-09-19 02:47	45.30	OK	12494	2026-09-19 02:48	48.43	OK
12495	2026-09-19 02:49	47.41	OK	12496	2026-09-19 02:50	47.57	OK
12497	2026-09-19 02:51	47.11	OK	12498	2026-09-19 02:52	45.00	OK
12499	2026-09-19 02:53	47.04	OK	12500	2026-09-19 02:54	46.06	OK
12501	2026-09-19 02:55	44.64	OK	12502	2026-09-19 02:56	46.36	OK
12503	2026-09-19 02:57	46.77	OK	12504	2026-09-19 02:58	45.63	OK
12505	2026-09-19 02:59	46.78	OK	12506	2026-09-19 03:00	45.52	OK
12507	2026-09-19 03:01	47.36	OK	12508	2026-09-19 03:02	46.55	OK
12509	2026-09-19 03:03	47.98	OK	12510	2026-09-19 03:04	46.85	OK
12511	2026-09-19 03:05	47.94	OK	12512	2026-09-19 03:06	44.84	OK
12513	2026-09-19 03:07	47.38	OK	12514	2026-09-19 03:08	46.58	OK
12515	2026-09-19 03:09	44.99	OK	12516	2026-09-19 03:10	47.19	OK
12517	2026-09-19 03:11	45.19	OK	12518	2026-09-19 03:12	45.46	OK
12519	2026-09-19 03:13	47.20	OK	12520	2026-09-19 03:14	49.03	OK
12521	2026-09-19 03:15	46.19	OK	12522	2026-09-19 03:16	47.46	OK
1252	2026-09-19 03:17	47.09	OK	1252	2026-09-19 03:18	46.05	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
12525	2026-09-19 03:19	46.08	OK	12526	2026-09-19 03:20	46.98	OK
12527	2026-09-19 03:21	46.66	OK	12528	2026-09-19 03:22	46.13	OK
12529	2026-09-19 03:23	48.64	OK	12530	2026-09-19 03:24	45.61	OK
12531	2026-09-19 03:25	46.00	OK	12532	2026-09-19 03:26	46.76	OK
12533	2026-09-19 03:27	47.58	OK	12534	2026-09-19 03:28	46.00	OK
12535	2026-09-19 03:29	48.39	OK	12536	2026-09-19 03:30	46.52	OK
12537	2026-09-19 03:31	45.32	OK	12538	2026-09-19 03:32	46.51	OK
12539	2026-09-19 03:33	45.67	OK	12540	2026-09-19 03:34	46.31	OK
12541	2026-09-19 03:35	46.24	OK	12542	2026-09-19 03:36	48.35	OK
12543	2026-09-19 03:37	46.36	OK	12544	2026-09-19 03:38	47.12	OK
12545	2026-09-19 03:39	48.84	OK	12546	2026-09-19 03:40	50.20	OK
12547	2026-09-19 03:41	46.88	OK	12548	2026-09-19 03:42	49.60	OK
12549	2026-09-19 03:43	47.40	OK	12550	2026-09-19 03:44	47.03	OK
12551	2026-09-19 03:45	45.69	OK	12552	2026-09-19 03:46	45.41	OK
12553	2026-09-19 03:47	47.19	OK	12554	2026-09-19 03:48	49.41	OK
12555	2026-09-19 03:49	48.84	OK	12556	2026-09-19 03:50	46.20	OK
12557	2026-09-19 03:51	47.23	OK	12558	2026-09-19 03:52	50.45	OK
12559	2026-09-19 03:53	47.76	OK	12560	2026-09-19 03:54	46.43	OK
12561	2026-09-19 03:55	48.44	OK	12562	2026-09-19 03:56	47.51	OK
12563	2026-09-19 03:57	47.56	OK	12564	2026-09-19 03:58	47.38	OK
12565	2026-09-19 03:59	48.17	OK	12566	2026-09-19 04:00	46.94	OK
12567	2026-09-19 04:01	48.34	OK	12568	2026-09-19 04:02	47.90	OK
12569	2026-09-19 04:03	47.37	OK	12570	2026-09-19 04:04	47.44	OK
12571	2026-09-19 04:05	47.00	OK	12572	2026-09-19 04:06	48.05	OK
12573	2026-09-19 04:07	47.90	OK	12574	2026-09-19 04:08	48.04	OK
12575	2026-09-19 04:09	48.57	OK	12576	2026-09-19 04:10	46.60	OK
12577	2026-09-19 04:11	47.32	OK	12578	2026-09-19 04:12	48.60	OK
12579	2026-09-19 04:13	48.97	OK	12580	2026-09-19 04:14	46.95	OK
12581	2026-09-19 04:15	47.90	OK	12582	2026-09-19 04:16	48.93	OK
1258	2026-09-19 04:17	47.27	OK	1258	2026-09-19 04:18	46.03	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
12585	2026-09-19 04:19	48.79	OK	12586	2026-09-19 04:20	48.27	OK
12587	2026-09-19 04:21	47.17	OK	12588	2026-09-19 04:22	47.80	OK
12589	2026-09-19 04:23	47.82	OK	12590	2026-09-19 04:24	46.14	OK
12591	2026-09-19 04:25	47.80	OK	12592	2026-09-19 04:26	48.67	OK
12593	2026-09-19 04:27	50.04	OK	12594	2026-09-19 04:28	49.00	OK
12595	2026-09-19 04:29	48.71	OK	12596	2026-09-19 04:30	48.51	OK
12597	2026-09-19 04:31	47.21	OK	12598	2026-09-19 04:32	46.57	OK
12599	2026-09-19 04:33	47.35	OK	12600	2026-09-19 04:34	46.50	OK
12601	2026-09-19 04:35	49.63	OK	12602	2026-09-19 04:36	48.44	OK
12603	2026-09-19 04:37	49.25	OK	12604	2026-09-19 04:38	48.83	OK
12605	2026-09-19 04:39	49.94	OK	12606	2026-09-19 04:40	47.19	OK
12607	2026-09-19 04:41	47.88	OK	12608	2026-09-19 04:42	50.55	OK
12609	2026-09-19 04:43	47.76	OK	12610	2026-09-19 04:44	48.15	OK
12611	2026-09-19 04:45	47.76	OK	12612	2026-09-19 04:46	49.38	OK
12613	2026-09-19 04:47	48.79	OK	12614	2026-09-19 04:48	48.83	OK
12615	2026-09-19 04:49	48.80	OK	12616	2026-09-19 04:50	50.38	OK
12617	2026-09-19 04:51	49.65	OK	12618	2026-09-19 04:52	48.76	OK
12619	2026-09-19 04:53	49.58	OK	12620	2026-09-19 04:54	45.73	OK
12621	2026-09-19 04:55	49.21	OK	12622	2026-09-19 04:56	49.91	OK
12623	2026-09-19 04:57	46.75	OK	12624	2026-09-19 04:58	48.97	OK
12625	2026-09-19 04:59	49.05	OK	12626	2026-09-19 05:00	49.74	OK
12627	2026-09-19 05:01	49.46	OK	12628	2026-09-19 05:02	46.98	OK
12629	2026-09-19 05:03	49.93	OK	12630	2026-09-19 05:04	48.63	OK
12631	2026-09-19 05:05	49.05	OK	12632	2026-09-19 05:06	48.66	OK
12633	2026-09-19 05:07	48.94	OK	12634	2026-09-19 05:08	49.40	OK
12635	2026-09-19 05:09	49.78	OK	12636	2026-09-19 05:10	50.02	OK
12637	2026-09-19 05:11	47.69	OK	12638	2026-09-19 05:12	50.02	OK
12639	2026-09-19 05:13	50.14	OK	12640	2026-09-19 05:14	48.43	OK
12641	2026-09-19 05:15	51.14	OK	12642	2026-09-19 05:16	50.60	OK
1264	2026-09-19 05:17	49.71	OK	1264	2026-09-19 05:18	51.02	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
12645	2026-09-19 05:19	49.53	OK	12646	2026-09-19 05:20	49.95	OK
12647	2026-09-19 05:21	50.47	OK	12648	2026-09-19 05:22	49.48	OK
12649	2026-09-19 05:23	48.32	OK	12650	2026-09-19 05:24	48.80	OK
12651	2026-09-19 05:25	47.71	OK	12652	2026-09-19 05:26	49.07	OK
12653	2026-09-19 05:27	48.69	OK	12654	2026-09-19 05:28	47.13	OK
12655	2026-09-19 05:29	49.37	OK	12656	2026-09-19 05:30	48.86	OK
12657	2026-09-19 05:31	50.69	OK	12658	2026-09-19 05:32	51.19	OK
12659	2026-09-19 05:33	50.98	OK	12660	2026-09-19 05:34	49.29	OK
12661	2026-09-19 05:35	48.83	OK	12662	2026-09-19 05:36	50.38	OK
12663	2026-09-19 05:37	51.17	OK	12664	2026-09-19 05:38	50.11	OK
12665	2026-09-19 05:39	50.28	OK	12666	2026-09-19 05:40	49.27	OK
12667	2026-09-19 05:41	51.71	OK	12668	2026-09-19 05:42	49.28	OK
12669	2026-09-19 05:43	51.87	OK	12670	2026-09-19 05:44	50.44	OK
12671	2026-09-19 05:45	51.28	OK	12672	2026-09-19 05:46	47.14	OK
12673	2026-09-19 05:47	48.94	OK	12674	2026-09-19 05:48	49.02	OK
12675	2026-09-19 05:49	50.06	OK	12676	2026-09-19 05:50	49.68	OK
12677	2026-09-19 05:51	49.21	OK	12678	2026-09-19 05:52	49.96	OK
12679	2026-09-19 05:53	50.91	OK	12680	2026-09-19 05:54	49.88	OK
12681	2026-09-19 05:55	49.72	OK	12682	2026-09-19 05:56	51.38	OK
12683	2026-09-19 05:57	50.46	OK	12684	2026-09-19 05:58	49.35	OK
12685	2026-09-19 05:59	48.69	OK	12686	2026-09-19 06:00	51.20	OK
12687	2026-09-19 06:01	48.67	OK	12688	2026-09-19 06:02	49.53	OK
12689	2026-09-19 06:03	51.75	OK	12690	2026-09-19 06:04	49.61	OK
12691	2026-09-19 06:05	49.32	OK	12692	2026-09-19 06:06	50.83	OK
12693	2026-09-19 06:07	51.23	OK	12694	2026-09-19 06:08	50.74	OK
12695	2026-09-19 06:09	49.06	OK	12696	2026-09-19 06:10	51.91	OK
12697	2026-09-19 06:11	49.95	OK	12698	2026-09-19 06:12	52.01	OK
12699	2026-09-19 06:13	49.33	OK	12700	2026-09-19 06:14	50.96	OK
12701	2026-09-19 06:15	50.04	OK	12702	2026-09-19 06:16	51.42	OK
1270	2026-09-19 06:17	52.12	OK	1270	2026-09-19 06:18	51.93	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
12705	2026-09-19 06:19	50.20	OK	12706	2026-09-19 06:20	50.71	OK
12707	2026-09-19 06:21	51.41	OK	12708	2026-09-19 06:22	50.59	OK
12709	2026-09-19 06:23	50.63	OK	12710	2026-09-19 06:24	51.16	OK
12711	2026-09-19 06:25	49.97	OK	12712	2026-09-19 06:26	51.56	OK
12713	2026-09-19 06:27	50.42	OK	12714	2026-09-19 06:28	49.85	OK
12715	2026-09-19 06:29	48.62	OK	12716	2026-09-19 06:30	50.43	OK
12717	2026-09-19 06:31	52.61	OK	12718	2026-09-19 06:32	50.79	OK
12719	2026-09-19 06:33	51.81	OK	12720	2026-09-19 06:34	50.62	OK
12721	2026-09-19 06:35	50.38	OK	12722	2026-09-19 06:36	50.35	OK
12723	2026-09-19 06:37	50.92	OK	12724	2026-09-19 06:38	50.15	OK
12725	2026-09-19 06:39	51.72	OK	12726	2026-09-19 06:40	51.51	OK
12727	2026-09-19 06:41	50.56	OK	12728	2026-09-19 06:42	52.56	OK
12729	2026-09-19 06:43	51.50	OK	12730	2026-09-19 06:44	49.44	OK
12731	2026-09-19 06:45	52.15	OK	12732	2026-09-19 06:46	50.94	OK
12733	2026-09-19 06:47	51.44	OK	12734	2026-09-19 06:48	51.34	OK
12735	2026-09-19 06:49	50.16	OK	12736	2026-09-19 06:50	52.49	OK
12737	2026-09-19 06:51	51.73	OK	12738	2026-09-19 06:52	52.25	OK
12739	2026-09-19 06:53	51.19	OK	12740	2026-09-19 06:54	51.09	OK
12741	2026-09-19 06:55	50.07	OK	12742	2026-09-19 06:56	48.91	OK
12743	2026-09-19 06:57	49.29	OK	12744	2026-09-19 06:58	50.30	OK
12745	2026-09-19 06:59	52.27	OK	12746	2026-09-19 07:00	50.44	OK
12747	2026-09-19 07:01	54.25	OK	12748	2026-09-19 07:02	52.04	OK
12749	2026-09-19 07:03	49.61	OK	12750	2026-09-19 07:04	51.30	OK
12751	2026-09-19 07:05	50.25	OK	12752	2026-09-19 07:06	50.99	OK
12753	2026-09-19 07:07	51.16	OK	12754	2026-09-19 07:08	52.42	OK
12755	2026-09-19 07:09	50.00	OK	12756	2026-09-19 07:10	52.85	OK
12757	2026-09-19 07:11	50.26	OK	12758	2026-09-19 07:12	50.46	OK
12759	2026-09-19 07:13	52.08	OK	12760	2026-09-19 07:14	51.05	OK
12761	2026-09-19 07:15	51.52	OK	12762	2026-09-19 07:16	50.48	OK
1276	2026-09-19 07:17	52.39	OK	1276	2026-09-19 07:18	52.93	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
12765	2026-09-19 07:19	52.32	OK	12766	2026-09-19 07:20	51.21	OK
12767	2026-09-19 07:21	52.84	OK	12768	2026-09-19 07:22	49.54	OK
12769	2026-09-19 07:23	51.80	OK	12770	2026-09-19 07:24	50.30	OK
12771	2026-09-19 07:25	52.33	OK	12772	2026-09-19 07:26	51.68	OK
12773	2026-09-19 07:27	50.11	OK	12774	2026-09-19 07:28	51.31	OK
12775	2026-09-19 07:29	52.62	OK	12776	2026-09-19 07:30	51.91	OK
12777	2026-09-19 07:31	53.54	OK	12778	2026-09-19 07:32	50.90	OK
12779	2026-09-19 07:33	51.53	OK	12780	2026-09-19 07:34	51.27	OK
12781	2026-09-19 07:35	50.89	OK	12782	2026-09-19 07:36	51.01	OK
12783	2026-09-19 07:37	51.16	OK	12784	2026-09-19 07:38	53.57	OK
12785	2026-09-19 07:39	51.54	OK	12786	2026-09-19 07:40	52.20	OK
12787	2026-09-19 07:41	52.36	OK	12788	2026-09-19 07:42	53.28	OK
12789	2026-09-19 07:43	51.02	OK	12790	2026-09-19 07:44	51.56	OK
12791	2026-09-19 07:45	52.51	OK	12792	2026-09-19 07:46	50.81	OK
12793	2026-09-19 07:47	51.22	OK	12794	2026-09-19 07:48	52.96	OK
12795	2026-09-19 07:49	51.08	OK	12796	2026-09-19 07:50	50.61	OK
12797	2026-09-19 07:51	51.05	OK	12798	2026-09-19 07:52	52.72	OK
12799	2026-09-19 07:53	51.70	OK	12800	2026-09-19 07:54	52.10	OK
12801	2026-09-19 07:55	52.87	OK	12802	2026-09-19 07:56	50.65	OK
12803	2026-09-19 07:57	54.32	OK	12804	2026-09-19 07:58	52.91	OK
12805	2026-09-19 07:59	52.25	OK	12806	2026-09-19 08:00	50.94	OK
12807	2026-09-19 08:01	53.29	OK	12808	2026-09-19 08:02	52.08	OK
12809	2026-09-19 08:03	52.05	OK	12810	2026-09-19 08:04	53.47	OK
12811	2026-09-19 08:05	52.04	OK	12812	2026-09-19 08:06	54.01	OK
12813	2026-09-19 08:07	51.02	OK	12814	2026-09-19 08:08	50.52	OK
12815	2026-09-19 08:09	51.03	OK	12816	2026-09-19 08:10	54.80	OK
12817	2026-09-19 08:11	52.99	OK	12818	2026-09-19 08:12	52.80	OK
12819	2026-09-19 08:13	52.31	OK	12820	2026-09-19 08:14	52.25	OK
12821	2026-09-19 08:15	52.32	OK	12822	2026-09-19 08:16	53.79	OK
1282	2026-09-19 08:17	52.38	OK	1282	2026-09-19 08:18	52.60	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
12825	2026-09-19 08:19	53.25	OK	12826	2026-09-19 08:20	52.52	OK
12827	2026-09-19 08:21	52.92	OK	12828	2026-09-19 08:22	51.63	OK
12829	2026-09-19 08:23	52.72	OK	12830	2026-09-19 08:24	52.63	OK
12831	2026-09-19 08:25	52.68	OK	12832	2026-09-19 08:26	52.98	OK
12833	2026-09-19 08:27	52.34	OK	12834	2026-09-19 08:28	54.14	OK
12835	2026-09-19 08:29	52.79	OK	12836	2026-09-19 08:30	52.58	OK
12837	2026-09-19 08:31	51.67	OK	12838	2026-09-19 08:32	53.60	OK
12839	2026-09-19 08:33	52.09	OK	12840	2026-09-19 08:34	52.81	OK
12841	2026-09-19 08:35	54.52	OK	12842	2026-09-19 08:36	51.75	OK
12843	2026-09-19 08:37	51.82	OK	12844	2026-09-19 08:38	53.03	OK
12845	2026-09-19 08:39	54.39	OK	12846	2026-09-19 08:40	54.01	OK
12847	2026-09-19 08:41	53.74	OK	12848	2026-09-19 08:42	53.28	OK
12849	2026-09-19 08:43	52.47	OK	12850	2026-09-19 08:44	51.79	OK
12851	2026-09-19 08:45	52.68	OK	12852	2026-09-19 08:46	52.90	OK
12853	2026-09-19 08:47	52.83	OK	12854	2026-09-19 08:48	52.61	OK
12855	2026-09-19 08:49	52.77	OK	12856	2026-09-19 08:50	52.17	OK
12857	2026-09-19 08:51	53.21	OK	12858	2026-09-19 08:52	52.48	OK
12859	2026-09-19 08:53	53.03	OK	12860	2026-09-19 08:54	51.95	OK
12861	2026-09-19 08:55	51.65	OK	12862	2026-09-19 08:56	52.18	OK
12863	2026-09-19 08:57	52.56	OK	12864	2026-09-19 08:58	52.82	OK
12865	2026-09-19 08:59	53.81	OK	12866	2026-09-19 09:00	50.72	OK
12867	2026-09-19 09:01	53.40	OK	12868	2026-09-19 09:02	54.12	OK
12869	2026-09-19 09:03	52.65	OK	12870	2026-09-19 09:04	52.75	OK
12871	2026-09-19 09:05	53.18	OK	12872	2026-09-19 09:06	54.72	OK
12873	2026-09-19 09:07	54.10	OK	12874	2026-09-19 09:08	53.21	OK
12875	2026-09-19 09:09	51.31	OK	12876	2026-09-19 09:10	52.49	OK
12877	2026-09-19 09:11	51.18	OK	12878	2026-09-19 09:12	55.28	OK
12879	2026-09-19 09:13	54.83	OK	12880	2026-09-19 09:14	52.88	OK
12881	2026-09-19 09:15	53.11	OK	12882	2026-09-19 09:16	52.65	OK
1288	2026-09-19 09:17	51.75	OK	1288	2026-09-19 09:18	54.28	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
12885	2026-09-19 09:19	54.16	OK	12886	2026-09-19 09:20	54.91	OK
12887	2026-09-19 09:21	53.29	OK	12888	2026-09-19 09:22	54.73	OK
12889	2026-09-19 09:23	54.66	OK	12890	2026-09-19 09:24	53.97	OK
12891	2026-09-19 09:25	52.60	OK	12892	2026-09-19 09:26	53.38	OK
12893	2026-09-19 09:27	53.13	OK	12894	2026-09-19 09:28	52.82	OK
12895	2026-09-19 09:29	51.24	OK	12896	2026-09-19 09:30	52.13	OK
12897	2026-09-19 09:31	54.76	OK	12898	2026-09-19 09:32	54.18	OK
12899	2026-09-19 09:33	53.62	OK	12900	2026-09-19 09:34	52.73	OK
12901	2026-09-19 09:35	53.45	OK	12902	2026-09-19 09:36	54.31	OK
12903	2026-09-19 09:37	52.47	OK	12904	2026-09-19 09:38	51.96	OK
12905	2026-09-19 09:39	51.98	OK	12906	2026-09-19 09:40	55.15	OK
12907	2026-09-19 09:41	53.46	OK	12908	2026-09-19 09:42	54.07	OK
12909	2026-09-19 09:43	55.56	OK	12910	2026-09-19 09:44	51.85	OK
12911	2026-09-19 09:45	52.06	OK	12912	2026-09-19 09:46	53.51	OK
12913	2026-09-19 09:47	56.53	OK	12914	2026-09-19 09:48	51.63	OK
12915	2026-09-19 09:49	52.95	OK	12916	2026-09-19 09:50	54.54	OK
12917	2026-09-19 09:51	53.38	OK	12918	2026-09-19 09:52	54.55	OK
12919	2026-09-19 09:53	53.65	OK	12920	2026-09-19 09:54	53.82	OK
12921	2026-09-19 09:55	54.54	OK	12922	2026-09-19 09:56	55.69	OK
12923	2026-09-19 09:57	52.86	OK	12924	2026-09-19 09:58	54.46	OK
12925	2026-09-19 09:59	54.26	OK	12926	2026-09-19 10:00	53.20	OK
12927	2026-09-19 10:01	55.16	OK	12928	2026-09-19 10:02	56.14	OK
12929	2026-09-19 10:03	55.09	OK	12930	2026-09-19 10:04	55.97	OK
12931	2026-09-19 10:05	54.74	OK	12932	2026-09-19 10:06	52.70	OK
12933	2026-09-19 10:07	55.22	OK	12934	2026-09-19 10:08	55.59	OK
12935	2026-09-19 10:09	53.50	OK	12936	2026-09-19 10:10	53.11	OK
12937	2026-09-19 10:11	55.10	OK	12938	2026-09-19 10:12	54.52	OK
12939	2026-09-19 10:13	52.87	OK	12940	2026-09-19 10:14	55.77	OK
12941	2026-09-19 10:15	53.32	OK	12942	2026-09-19 10:16	53.68	OK
1294	2026-09-19 10:17	54.84	OK	1294	2026-09-19 10:18	54.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
12945	2026-09-19 10:19	53.89	OK	12946	2026-09-19 10:20	55.48	OK
12947	2026-09-19 10:21	54.41	OK	12948	2026-09-19 10:22	53.36	OK
12949	2026-09-19 10:23	53.07	OK	12950	2026-09-19 10:24	53.76	OK
12951	2026-09-19 10:25	54.87	OK	12952	2026-09-19 10:26	51.22	OK
12953	2026-09-19 10:27	54.35	OK	12954	2026-09-19 10:28	55.34	OK
12955	2026-09-19 10:29	54.19	OK	12956	2026-09-19 10:30	55.30	OK
12957	2026-09-19 10:31	52.95	OK	12958	2026-09-19 10:32	53.56	OK
12959	2026-09-19 10:33	53.04	OK	12960	2026-09-19 10:34	54.63	OK
12961	2026-09-19 10:35	56.11	OK	12962	2026-09-19 10:36	53.84	OK
12963	2026-09-19 10:37	52.99	OK	12964	2026-09-19 10:38	53.21	OK
12965	2026-09-19 10:39	56.27	OK	12966	2026-09-19 10:40	53.36	OK
12967	2026-09-19 10:41	52.93	OK	12968	2026-09-19 10:42	53.55	OK
12969	2026-09-19 10:43	53.21	OK	12970	2026-09-19 10:44	56.31	OK
12971	2026-09-19 10:45	54.53	OK	12972	2026-09-19 10:46	54.43	OK
12973	2026-09-19 10:47	56.98	OK	12974	2026-09-19 10:48	54.10	OK
12975	2026-09-19 10:49	52.69	OK	12976	2026-09-19 10:50	53.93	OK
12977	2026-09-19 10:51	52.94	OK	12978	2026-09-19 10:52	56.65	OK
12979	2026-09-19 10:53	53.88	OK	12980	2026-09-19 10:54	53.97	OK
12981	2026-09-19 10:55	53.91	OK	12982	2026-09-19 10:56	54.69	OK
12983	2026-09-19 10:57	52.88	OK	12984	2026-09-19 10:58	53.30	OK
12985	2026-09-19 10:59	55.01	OK	12986	2026-09-19 11:00	55.16	OK
12987	2026-09-19 11:01	56.60	OK	12988	2026-09-19 11:02	53.22	OK
12989	2026-09-19 11:03	53.33	OK	12990	2026-09-19 11:04	56.19	OK
12991	2026-09-19 11:05	51.56	OK	12992	2026-09-19 11:06	53.66	OK
12993	2026-09-19 11:07	55.55	OK	12994	2026-09-19 11:08	53.71	OK
12995	2026-09-19 11:09	55.39	OK	12996	2026-09-19 11:10	53.09	OK
12997	2026-09-19 11:11	53.81	OK	12998	2026-09-19 11:12	51.92	OK
12999	2026-09-19 11:13	52.76	OK	13000	2026-09-19 11:14	53.42	OK
13001	2026-09-19 11:15	53.51	OK	13002	2026-09-19 11:16	52.78	OK
1300	2026-09-19 11:17	54.70	OK	1300	2026-09-19 11:18	54.95	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
13005	2026-09-19 11:19	52.83	OK	13006	2026-09-19 11:20	54.39	OK
13007	2026-09-19 11:21	53.47	OK	13008	2026-09-19 11:22	55.94	OK
13009	2026-09-19 11:23	53.67	OK	13010	2026-09-19 11:24	54.18	OK
13011	2026-09-19 11:25	52.80	OK	13012	2026-09-19 11:26	52.21	OK
13013	2026-09-19 11:27	54.14	OK	13014	2026-09-19 11:28	52.15	OK
13015	2026-09-19 11:29	53.75	OK	13016	2026-09-19 11:30	53.03	OK
13017	2026-09-19 11:31	54.12	OK	13018	2026-09-19 11:32	53.04	OK
13019	2026-09-19 11:33	53.92	OK	13020	2026-09-19 11:34	53.44	OK
13021	2026-09-19 11:35	52.09	OK	13022	2026-09-19 11:36	54.41	OK
13023	2026-09-19 11:37	54.14	OK	13024	2026-09-19 11:38	55.17	OK
13025	2026-09-19 11:39	54.71	OK	13026	2026-09-19 11:40	54.92	OK
13027	2026-09-19 11:41	54.21	OK	13028	2026-09-19 11:42	51.93	OK
13029	2026-09-19 11:43	54.45	OK	13030	2026-09-19 11:44	54.51	OK
13031	2026-09-19 11:45	53.60	OK	13032	2026-09-19 11:46	53.37	OK
13033	2026-09-19 11:47	55.37	OK	13034	2026-09-19 11:48	52.81	OK
13035	2026-09-19 11:49	51.67	OK	13036	2026-09-19 11:50	54.11	OK
13037	2026-09-19 11:51	53.28	OK	13038	2026-09-19 11:52	54.12	OK
13039	2026-09-19 11:53	53.04	OK	13040	2026-09-19 11:54	54.90	OK
13041	2026-09-19 11:55	55.17	OK	13042	2026-09-19 11:56	55.44	OK
13043	2026-09-19 11:57	54.94	OK	13044	2026-09-19 11:58	52.79	OK
13045	2026-09-19 11:59	55.03	OK	13046	2026-09-19 12:00	53.92	OK
13047	2026-09-19 12:01	53.61	OK	13048	2026-09-19 12:02	54.59	OK
13049	2026-09-19 12:03	54.98	OK	13050	2026-09-19 12:04	54.85	OK
13051	2026-09-19 12:05	51.85	OK	13052	2026-09-19 12:06	54.88	OK
13053	2026-09-19 12:07	55.48	OK	13054	2026-09-19 12:08	55.54	OK
13055	2026-09-19 12:09	53.15	OK	13056	2026-09-19 12:10	53.96	OK
13057	2026-09-19 12:11	54.97	OK	13058	2026-09-19 12:12	54.17	OK
13059	2026-09-19 12:13	53.01	OK	13060	2026-09-19 12:14	52.56	OK
13061	2026-09-19 12:15	54.08	OK	13062	2026-09-19 12:16	52.57	OK
1306	2026-09-19 12:17	53.76	OK	1306	2026-09-19 12:18	54.91	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
13065	2026-09-19 12:19	53.50	OK	13066	2026-09-19 12:20	54.77	OK
13067	2026-09-19 12:21	52.74	OK	13068	2026-09-19 12:22	54.32	OK
13069	2026-09-19 12:23	52.77	OK	13070	2026-09-19 12:24	52.90	OK
13071	2026-09-19 12:25	53.95	OK	13072	2026-09-19 12:26	56.15	OK
13073	2026-09-19 12:27	53.41	OK	13074	2026-09-19 12:28	54.75	OK
13075	2026-09-19 12:29	55.54	OK	13076	2026-09-19 12:30	54.72	OK
13077	2026-09-19 12:31	54.28	OK	13078	2026-09-19 12:32	53.71	OK
13079	2026-09-19 12:33	55.44	OK	13080	2026-09-19 12:34	54.05	OK
13081	2026-09-19 12:35	55.02	OK	13082	2026-09-19 12:36	52.87	OK
13083	2026-09-19 12:37	53.41	OK	13084	2026-09-19 12:38	52.59	OK
13085	2026-09-19 12:39	54.35	OK	13086	2026-09-19 12:40	52.15	OK
13087	2026-09-19 12:41	53.91	OK	13088	2026-09-19 12:42	54.01	OK
13089	2026-09-19 12:43	53.66	OK	13090	2026-09-19 12:44	53.02	OK
13091	2026-09-19 12:45	54.35	OK	13092	2026-09-19 12:46	53.33	OK
13093	2026-09-19 12:47	53.81	OK	13094	2026-09-19 12:48	55.12	OK
13095	2026-09-19 12:49	51.83	OK	13096	2026-09-19 12:50	52.86	OK
13097	2026-09-19 12:51	53.81	OK	13098	2026-09-19 12:52	53.00	OK
13099	2026-09-19 12:53	52.76	OK	13100	2026-09-19 12:54	53.70	OK
13101	2026-09-19 12:55	53.27	OK	13102	2026-09-19 12:56	55.06	OK
13103	2026-09-19 12:57	54.90	OK	13104	2026-09-19 12:58	56.07	OK
13105	2026-09-19 12:59	53.62	OK	13106	2026-09-19 13:00	54.05	OK
13107	2026-09-19 13:01	54.86	OK	13108	2026-09-19 13:02	53.31	OK
13109	2026-09-19 13:03	52.85	OK	13110	2026-09-19 13:04	54.61	OK
13111	2026-09-19 13:05	52.77	OK	13112	2026-09-19 13:06	54.88	OK
13113	2026-09-19 13:07	52.91	OK	13114	2026-09-19 13:08	54.45	OK
13115	2026-09-19 13:09	53.36	OK	13116	2026-09-19 13:10	54.59	OK
13117	2026-09-19 13:11	53.60	OK	13118	2026-09-19 13:12	54.03	OK
13119	2026-09-19 13:13	52.79	OK	13120	2026-09-19 13:14	51.79	OK
13121	2026-09-19 13:15	54.06	OK	13122	2026-09-19 13:16	52.93	OK
1312	2026-09-19 13:17	51.13	OK	1312	2026-09-19 13:18	53.65	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
13125	2026-09-19 13:19	53.40	OK	13126	2026-09-19 13:20	55.75	OK
13127	2026-09-19 13:21	52.69	OK	13128	2026-09-19 13:22	51.72	OK
13129	2026-09-19 13:23	54.85	OK	13130	2026-09-19 13:24	52.34	OK
13131	2026-09-19 13:25	51.80	OK	13132	2026-09-19 13:26	54.01	OK
13133	2026-09-19 13:27	53.20	OK	13134	2026-09-19 13:28	53.11	OK
13135	2026-09-19 13:29	53.48	OK	13136	2026-09-19 13:30	53.34	OK
13137	2026-09-19 13:31	52.55	OK	13138	2026-09-19 13:32	52.40	OK
13139	2026-09-19 13:33	53.09	OK	13140	2026-09-19 13:34	54.28	OK
13141	2026-09-19 13:35	54.22	OK	13142	2026-09-19 13:36	51.85	OK
13143	2026-09-19 13:37	52.31	OK	13144	2026-09-19 13:38	52.09	OK
13145	2026-09-19 13:39	53.32	OK	13146	2026-09-19 13:40	53.34	OK
13147	2026-09-19 13:41	52.37	OK	13148	2026-09-19 13:42	54.15	OK
13149	2026-09-19 13:43	52.03	OK	13150	2026-09-19 13:44	54.90	OK
13151	2026-09-19 13:45	55.97	OK	13152	2026-09-19 13:46	54.29	OK
13153	2026-09-19 13:47	54.54	OK	13154	2026-09-19 13:48	54.31	OK
13155	2026-09-19 13:49	54.05	OK	13156	2026-09-19 13:50	52.97	OK
13157	2026-09-19 13:51	51.96	OK	13158	2026-09-19 13:52	53.21	OK
13159	2026-09-19 13:53	53.36	OK	13160	2026-09-19 13:54	53.25	OK
13161	2026-09-19 13:55	52.58	OK	13162	2026-09-19 13:56	52.21	OK
13163	2026-09-19 13:57	54.49	OK	13164	2026-09-19 13:58	53.63	OK
13165	2026-09-19 13:59	52.68	OK	13166	2026-09-19 14:00	53.47	OK
13167	2026-09-19 14:01	53.78	OK	13168	2026-09-19 14:02	53.64	OK
13169	2026-09-19 14:03	52.59	OK	13170	2026-09-19 14:04	54.32	OK
13171	2026-09-19 14:05	51.29	OK	13172	2026-09-19 14:06	52.68	OK
13173	2026-09-19 14:07	51.44	OK	13174	2026-09-19 14:08	53.37	OK
13175	2026-09-19 14:09	53.00	OK	13176	2026-09-19 14:10	52.29	OK
13177	2026-09-19 14:11	50.37	OK	13178	2026-09-19 14:12	53.89	OK
13179	2026-09-19 14:13	53.70	OK	13180	2026-09-19 14:14	53.97	OK
13181	2026-09-19 14:15	53.61	OK	13182	2026-09-19 14:16	54.00	OK
1318	2026-09-19 14:17	53.79	OK	1318	2026-09-19 14:18	53.40	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
13185	2026-09-19 14:19	52.83	OK	13186	2026-09-19 14:20	52.42	OK
13187	2026-09-19 14:21	54.74	OK	13188	2026-09-19 14:22	53.09	OK
13189	2026-09-19 14:23	53.08	OK	13190	2026-09-19 14:24	53.03	OK
13191	2026-09-19 14:25	52.78	OK	13192	2026-09-19 14:26	53.42	OK
13193	2026-09-19 14:27	51.68	OK	13194	2026-09-19 14:28	53.26	OK
13195	2026-09-19 14:29	51.35	OK	13196	2026-09-19 14:30	52.07	OK
13197	2026-09-19 14:31	50.86	OK	13198	2026-09-19 14:32	53.13	OK
13199	2026-09-19 14:33	52.88	OK	13200	2026-09-19 14:34	52.17	OK
13201	2026-09-19 14:35	51.55	OK	13202	2026-09-19 14:36	53.14	OK
13203	2026-09-19 14:37	51.22	OK	13204	2026-09-19 14:38	50.18	OK
13205	2026-09-19 14:39	51.01	OK	13206	2026-09-19 14:40	53.10	OK
13207	2026-09-19 14:41	54.10	OK	13208	2026-09-19 14:42	53.19	OK
13209	2026-09-19 14:43	53.19	OK	13210	2026-09-19 14:44	53.26	OK
13211	2026-09-19 14:45	52.94	OK	13212	2026-09-19 14:46	53.93	OK
13213	2026-09-19 14:47	51.97	OK	13214	2026-09-19 14:48	52.72	OK
13215	2026-09-19 14:49	52.10	OK	13216	2026-09-19 14:50	53.38	OK
13217	2026-09-19 14:51	51.06	OK	13218	2026-09-19 14:52	53.24	OK
13219	2026-09-19 14:53	53.08	OK	13220	2026-09-19 14:54	52.65	OK
13221	2026-09-19 14:55	51.08	OK	13222	2026-09-19 14:56	51.39	OK
13223	2026-09-19 14:57	52.49	OK	13224	2026-09-19 14:58	52.53	OK
13225	2026-09-19 14:59	53.04	OK	13226	2026-09-19 15:00	51.46	OK
13227	2026-09-19 15:01	53.04	OK	13228	2026-09-19 15:02	52.52	OK
13229	2026-09-19 15:03	52.26	OK	13230	2026-09-19 15:04	53.11	OK
13231	2026-09-19 15:05	52.31	OK	13232	2026-09-19 15:06	49.79	OK
13233	2026-09-19 15:07	51.44	OK	13234	2026-09-19 15:08	50.98	OK
13235	2026-09-19 15:09	52.88	OK	13236	2026-09-19 15:10	50.98	OK
13237	2026-09-19 15:11	51.27	OK	13238	2026-09-19 15:12	50.85	OK
13239	2026-09-19 15:13	53.28	OK	13240	2026-09-19 15:14	53.01	OK
13241	2026-09-19 15:15	50.49	OK	13242	2026-09-19 15:16	51.66	OK
1324	2026-09-19 15:17	50.56	OK	1324	2026-09-19 15:18	51.84	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
13245	2026-09-19 15:19	53.14	OK	13246	2026-09-19 15:20	51.67	OK
13247	2026-09-19 15:21	51.47	OK	13248	2026-09-19 15:22	51.53	OK
13249	2026-09-19 15:23	51.34	OK	13250	2026-09-19 15:24	52.50	OK
13251	2026-09-19 15:25	50.58	OK	13252	2026-09-19 15:26	53.20	OK
13253	2026-09-19 15:27	50.21	OK	13254	2026-09-19 15:28	52.02	OK
13255	2026-09-19 15:29	51.07	OK	13256	2026-09-19 15:30	51.15	OK
13257	2026-09-19 15:31	52.15	OK	13258	2026-09-19 15:32	53.55	OK
13259	2026-09-19 15:33	51.69	OK	13260	2026-09-19 15:34	48.77	OK
13261	2026-09-19 15:35	50.81	OK	13262	2026-09-19 15:36	52.09	OK
13263	2026-09-19 15:37	51.61	OK	13264	2026-09-19 15:38	50.56	OK
13265	2026-09-19 15:39	53.11	OK	13266	2026-09-19 15:40	53.10	OK
13267	2026-09-19 15:41	53.31	OK	13268	2026-09-19 15:42	51.69	OK
13269	2026-09-19 15:43	51.29	OK	13270	2026-09-19 15:44	51.01	OK
13271	2026-09-19 15:45	50.98	OK	13272	2026-09-19 15:46	49.68	OK
13273	2026-09-19 15:47	51.57	OK	13274	2026-09-19 15:48	52.35	OK
13275	2026-09-19 15:49	52.01	OK	13276	2026-09-19 15:50	50.95	OK
13277	2026-09-19 15:51	52.28	OK	13278	2026-09-19 15:52	51.84	OK
13279	2026-09-19 15:53	51.46	OK	13280	2026-09-19 15:54	51.27	OK
13281	2026-09-19 15:55	52.40	OK	13282	2026-09-19 15:56	49.56	OK
13283	2026-09-19 15:57	51.46	OK	13284	2026-09-19 15:58	52.26	OK
13285	2026-09-19 15:59	50.24	OK	13286	2026-09-19 16:00	49.65	OK
13287	2026-09-19 16:01	51.56	OK	13288	2026-09-19 16:02	53.35	OK
13289	2026-09-19 16:03	51.79	OK	13290	2026-09-19 16:04	49.73	OK
13291	2026-09-19 16:05	50.90	OK	13292	2026-09-19 16:06	50.76	OK
13293	2026-09-19 16:07	48.34	OK	13294	2026-09-19 16:08	52.21	OK
13295	2026-09-19 16:09	51.01	OK	13296	2026-09-19 16:10	50.44	OK
13297	2026-09-19 16:11	50.43	OK	13298	2026-09-19 16:12	51.26	OK
13299	2026-09-19 16:13	50.76	OK	13300	2026-09-19 16:14	50.25	OK
13301	2026-09-19 16:15	50.72	OK	13302	2026-09-19 16:16	52.43	OK
1330	2026-09-19 16:17	51.06	OK	1330	2026-09-19 16:18	53.04	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
13305	2026-09-19 16:19	52.17	OK	13306	2026-09-19 16:20	51.26	OK
13307	2026-09-19 16:21	50.83	OK	13308	2026-09-19 16:22	49.07	OK
13309	2026-09-19 16:23	51.92	OK	13310	2026-09-19 16:24	50.18	OK
13311	2026-09-19 16:25	49.58	OK	13312	2026-09-19 16:26	50.20	OK
13313	2026-09-19 16:27	48.59	OK	13314	2026-09-19 16:28	49.62	OK
13315	2026-09-19 16:29	50.26	OK	13316	2026-09-19 16:30	51.12	OK
13317	2026-09-19 16:31	49.12	OK	13318	2026-09-19 16:32	52.91	OK
13319	2026-09-19 16:33	50.29	OK	13320	2026-09-19 16:34	51.26	OK
13321	2026-09-19 16:35	50.76	OK	13322	2026-09-19 16:36	49.30	OK
13323	2026-09-19 16:37	50.23	OK	13324	2026-09-19 16:38	49.64	OK
13325	2026-09-19 16:39	50.77	OK	13326	2026-09-19 16:40	49.23	OK
13327	2026-09-19 16:41	48.21	OK	13328	2026-09-19 16:42	49.89	OK
13329	2026-09-19 16:43	50.40	OK	13330	2026-09-19 16:44	51.01	OK
13331	2026-09-19 16:45	52.28	OK	13332	2026-09-19 16:46	50.56	OK
13333	2026-09-19 16:47	51.72	OK	13334	2026-09-19 16:48	49.55	OK
13335	2026-09-19 16:49	51.52	OK	13336	2026-09-19 16:50	49.57	OK
13337	2026-09-19 16:51	49.71	OK	13338	2026-09-19 16:52	48.56	OK
13339	2026-09-19 16:53	49.84	OK	13340	2026-09-19 16:54	50.13	OK
13341	2026-09-19 16:55	50.06	OK	13342	2026-09-19 16:56	49.74	OK
13343	2026-09-19 16:57	48.55	OK	13344	2026-09-19 16:58	50.10	OK
13345	2026-09-19 16:59	51.10	OK	13346	2026-09-19 17:00	49.78	OK
13347	2026-09-19 17:01	48.60	OK	13348	2026-09-19 17:02	48.27	OK
13349	2026-09-19 17:03	48.99	OK	13350	2026-09-19 17:04	48.68	OK
13351	2026-09-19 17:05	52.23	OK	13352	2026-09-19 17:06	50.03	OK
13353	2026-09-19 17:07	51.21	OK	13354	2026-09-19 17:08	48.54	OK
13355	2026-09-19 17:09	47.35	OK	13356	2026-09-19 17:10	50.49	OK
13357	2026-09-19 17:11	51.12	OK	13358	2026-09-19 17:12	49.52	OK
13359	2026-09-19 17:13	49.31	OK	13360	2026-09-19 17:14	50.04	OK
13361	2026-09-19 17:15	49.36	OK	13362	2026-09-19 17:16	51.14	OK
1336	2026-09-19 17:17	51.32	OK	1336	2026-09-19 17:18	49.27	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
13365	2026-09-19 17:19	49.65	OK	13366	2026-09-19 17:20	50.12	OK
13367	2026-09-19 17:21	49.85	OK	13368	2026-09-19 17:22	50.11	OK
13369	2026-09-19 17:23	48.59	OK	13370	2026-09-19 17:24	49.79	OK
13371	2026-09-19 17:25	50.74	OK	13372	2026-09-19 17:26	51.31	OK
13373	2026-09-19 17:27	49.32	OK	13374	2026-09-19 17:28	50.82	OK
13375	2026-09-19 17:29	50.26	OK	13376	2026-09-19 17:30	48.79	OK
13377	2026-09-19 17:31	48.88	OK	13378	2026-09-19 17:32	48.98	OK
13379	2026-09-19 17:33	50.68	OK	13380	2026-09-19 17:34	47.88	OK
13381	2026-09-19 17:35	49.84	OK	13382	2026-09-19 17:36	51.67	OK
13383	2026-09-19 17:37	49.97	OK	13384	2026-09-19 17:38	49.44	OK
13385	2026-09-19 17:39	49.15	OK	13386	2026-09-19 17:40	49.73	OK
13387	2026-09-19 17:41	47.83	OK	13388	2026-09-19 17:42	50.37	OK
13389	2026-09-19 17:43	48.19	OK	13390	2026-09-19 17:44	49.88	OK
13391	2026-09-19 17:45	49.50	OK	13392	2026-09-19 17:46	49.19	OK
13393	2026-09-19 17:47	49.18	OK	13394	2026-09-19 17:48	50.21	OK
13395	2026-09-19 17:49	47.60	OK	13396	2026-09-19 17:50	50.65	OK
13397	2026-09-19 17:51	49.02	OK	13398	2026-09-19 17:52	47.77	OK
13399	2026-09-19 17:53	49.17	OK	13400	2026-09-19 17:54	48.40	OK
13401	2026-09-19 17:55	46.46	OK	13402	2026-09-19 17:56	48.40	OK
13403	2026-09-19 17:57	47.72	OK	13404	2026-09-19 17:58	50.93	OK
13405	2026-09-19 17:59	46.71	OK	13406	2026-09-19 18:00	50.78	OK
13407	2026-09-19 18:01	49.23	OK	13408	2026-09-19 18:02	49.89	OK
13409	2026-09-19 18:03	48.10	OK	13410	2026-09-19 18:04	48.80	OK
13411	2026-09-19 18:05	47.52	OK	13412	2026-09-19 18:06	48.44	OK
13413	2026-09-19 18:07	47.30	OK	13414	2026-09-19 18:08	48.46	OK
13415	2026-09-19 18:09	49.46	OK	13416	2026-09-19 18:10	49.64	OK
13417	2026-09-19 18:11	48.47	OK	13418	2026-09-19 18:12	48.21	OK
13419	2026-09-19 18:13	48.37	OK	13420	2026-09-19 18:14	48.22	OK
13421	2026-09-19 18:15	49.69	OK	13422	2026-09-19 18:16	48.04	OK
1342	2026-09-19 18:17	49.06	OK	1342	2026-09-19 18:18	48.97	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
13425	2026-09-19 18:19	47.28	OK	13426	2026-09-19 18:20	48.73	OK
13427	2026-09-19 18:21	46.13	OK	13428	2026-09-19 18:22	47.19	OK
13429	2026-09-19 18:23	47.64	OK	13430	2026-09-19 18:24	49.35	OK
13431	2026-09-19 18:25	47.66	OK	13432	2026-09-19 18:26	49.44	OK
13433	2026-09-19 18:27	46.88	OK	13434	2026-09-19 18:28	46.41	OK
13435	2026-09-19 18:29	50.34	OK	13436	2026-09-19 18:30	48.69	OK
13437	2026-09-19 18:31	48.57	OK	13438	2026-09-19 18:32	47.47	OK
13439	2026-09-19 18:33	49.43	OK	13440	2026-09-19 18:34	46.30	OK
13441	2026-09-19 18:35	48.45	OK	13442	2026-09-19 18:36	47.30	OK
13443	2026-09-19 18:37	48.58	OK	13444	2026-09-19 18:38	48.42	OK
13445	2026-09-19 18:39	49.04	OK	13446	2026-09-19 18:40	48.15	OK
13447	2026-09-19 18:41	46.50	OK	13448	2026-09-19 18:42	48.17	OK
13449	2026-09-19 18:43	46.53	OK	13450	2026-09-19 18:44	47.07	OK
13451	2026-09-19 18:45	46.11	OK	13452	2026-09-19 18:46	48.02	OK
13453	2026-09-19 18:47	47.72	OK	13454	2026-09-19 18:48	46.89	OK
13455	2026-09-19 18:49	48.01	OK	13456	2026-09-19 18:50	47.00	OK
13457	2026-09-19 18:51	47.41	OK	13458	2026-09-19 18:52	49.37	OK
13459	2026-09-19 18:53	49.44	OK	13460	2026-09-19 18:54	46.99	OK
13461	2026-09-19 18:55	46.67	OK	13462	2026-09-19 18:56	46.70	OK
13463	2026-09-19 18:57	47.64	OK	13464	2026-09-19 18:58	46.74	OK
13465	2026-09-19 18:59	47.22	OK	13466	2026-09-19 19:00	46.59	OK
13467	2026-09-19 19:01	49.64	OK	13468	2026-09-19 19:02	47.85	OK
13469	2026-09-19 19:03	48.43	OK	13470	2026-09-19 19:04	47.06	OK
13471	2026-09-19 19:05	46.69	OK	13472	2026-09-19 19:06	49.38	OK
13473	2026-09-19 19:07	46.54	OK	13474	2026-09-19 19:08	49.19	OK
13475	2026-09-19 19:09	50.01	OK	13476	2026-09-19 19:10	46.59	OK
13477	2026-09-19 19:11	45.47	OK	13478	2026-09-19 19:12	48.36	OK
13479	2026-09-19 19:13	48.45	OK	13480	2026-09-19 19:14	45.66	OK
13481	2026-09-19 19:15	48.06	OK	13482	2026-09-19 19:16	47.58	OK
1348	2026-09-19 19:17	47.88	OK	1348	2026-09-19 19:18	47.52	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
13485	2026-09-19 19:19	46.19	OK	13486	2026-09-19 19:20	47.44	OK
13487	2026-09-19 19:21	46.00	OK	13488	2026-09-19 19:22	46.25	OK
13489	2026-09-19 19:23	47.89	OK	13490	2026-09-19 19:24	48.58	OK
13491	2026-09-19 19:25	47.54	OK	13492	2026-09-19 19:26	48.82	OK
13493	2026-09-19 19:27	47.91	OK	13494	2026-09-19 19:28	46.84	OK
13495	2026-09-19 19:29	46.75	OK	13496	2026-09-19 19:30	46.91	OK
13497	2026-09-19 19:31	45.64	OK	13498	2026-09-19 19:32	46.64	OK
13499	2026-09-19 19:33	46.75	OK	13500	2026-09-19 19:34	44.26	OK
13501	2026-09-19 19:35	47.44	OK	13502	2026-09-19 19:36	48.42	OK
13503	2026-09-19 19:37	46.64	OK	13504	2026-09-19 19:38	46.88	OK
13505	2026-09-19 19:39	46.34	OK	13506	2026-09-19 19:40	45.49	OK
13507	2026-09-19 19:41	48.11	OK	13508	2026-09-19 19:42	46.99	OK
13509	2026-09-19 19:43	46.26	OK	13510	2026-09-19 19:44	47.02	OK
13511	2026-09-19 19:45	47.34	OK	13512	2026-09-19 19:46	46.40	OK
13513	2026-09-19 19:47	48.01	OK	13514	2026-09-19 19:48	45.98	OK
13515	2026-09-19 19:49	45.66	OK	13516	2026-09-19 19:50	46.90	OK
13517	2026-09-19 19:51	46.94	OK	13518	2026-09-19 19:52	45.83	OK
13519	2026-09-19 19:53	47.99	OK	13520	2026-09-19 19:54	48.05	OK
13521	2026-09-19 19:55	46.56	OK	13522	2026-09-19 19:56	48.53	OK
13523	2026-09-19 19:57	46.94	OK	13524	2026-09-19 19:58	45.67	OK
13525	2026-09-19 19:59	47.50	OK	13526	2026-09-19 20:00	46.15	OK
13527	2026-09-19 20:01	46.92	OK	13528	2026-09-19 20:02	48.36	OK
13529	2026-09-19 20:03	45.63	OK	13530	2026-09-19 20:04	46.81	OK
13531	2026-09-19 20:05	47.29	OK	13532	2026-09-19 20:06	47.04	OK
13533	2026-09-19 20:07	47.25	OK	13534	2026-09-19 20:08	46.89	OK
13535	2026-09-19 20:09	45.97	OK	13536	2026-09-19 20:10	47.12	OK
13537	2026-09-19 20:11	46.03	OK	13538	2026-09-19 20:12	45.28	OK
13539	2026-09-19 20:13	46.81	OK	13540	2026-09-19 20:14	45.51	OK
13541	2026-09-19 20:15	45.98	OK	13542	2026-09-19 20:16	46.13	OK
1354	2026-09-19 20:17	45.61	OK	1354	2026-09-19 20:18	44.48	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
13545	2026-09-19 20:19	44.62	OK	13546	2026-09-19 20:20	44.33	OK
13547	2026-09-19 20:21	46.19	OK	13548	2026-09-19 20:22	45.51	OK
13549	2026-09-19 20:23	46.34	OK	13550	2026-09-19 20:24	44.33	OK
13551	2026-09-19 20:25	46.81	OK	13552	2026-09-19 20:26	46.94	OK
13553	2026-09-19 20:27	45.95	OK	13554	2026-09-19 20:28	44.26	OK
13555	2026-09-19 20:29	44.16	OK	13556	2026-09-19 20:30	44.15	OK
13557	2026-09-19 20:31	46.36	OK	13558	2026-09-19 20:32	44.67	OK
13559	2026-09-19 20:33	46.89	OK	13560	2026-09-19 20:34	47.77	OK
13561	2026-09-19 20:35	45.89	OK	13562	2026-09-19 20:36	46.17	OK
13563	2026-09-19 20:37	44.09	OK	13564	2026-09-19 20:38	45.97	OK
13565	2026-09-19 20:39	47.35	OK	13566	2026-09-19 20:40	46.53	OK
13567	2026-09-19 20:41	45.17	OK	13568	2026-09-19 20:42	45.21	OK
13569	2026-09-19 20:43	44.89	OK	13570	2026-09-19 20:44	47.74	OK
13571	2026-09-19 20:45	47.15	OK	13572	2026-09-19 20:46	48.20	OK
13573	2026-09-19 20:47	43.63	OK	13574	2026-09-19 20:48	44.89	OK
13575	2026-09-19 20:49	46.29	OK	13576	2026-09-19 20:50	46.30	OK
13577	2026-09-19 20:51	45.54	OK	13578	2026-09-19 20:52	45.61	OK
13579	2026-09-19 20:53	45.79	OK	13580	2026-09-19 20:54	45.50	OK
13581	2026-09-19 20:55	44.31	OK	13582	2026-09-19 20:56	46.71	OK
13583	2026-09-19 20:57	45.85	OK	13584	2026-09-19 20:58	45.52	OK
13585	2026-09-19 20:59	44.83	OK	13586	2026-09-19 21:00	45.34	OK
13587	2026-09-19 21:01	46.11	OK	13588	2026-09-19 21:02	46.63	OK
13589	2026-09-19 21:03	44.48	OK	13590	2026-09-19 21:04	44.48	OK
13591	2026-09-19 21:05	42.80	OK	13592	2026-09-19 21:06	45.60	OK
13593	2026-09-19 21:07	45.84	OK	13594	2026-09-19 21:08	45.53	OK
13595	2026-09-19 21:09	46.20	OK	13596	2026-09-19 21:10	45.40	OK
13597	2026-09-19 21:11	45.14	OK	13598	2026-09-19 21:12	45.04	OK
13599	2026-09-19 21:13	45.43	OK	13600	2026-09-19 21:14	45.84	OK
13601	2026-09-19 21:15	44.12	OK	13602	2026-09-19 21:16	45.05	OK
1360	2026-09-19 21:17	44.98	OK	1360	2026-09-19 21:18	46.00	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
13605	2026-09-19 21:19	43.89	OK	13606	2026-09-19 21:20	45.11	OK
13607	2026-09-19 21:21	44.92	OK	13608	2026-09-19 21:22	45.99	OK
13609	2026-09-19 21:23	45.78	OK	13610	2026-09-19 21:24	46.24	OK
13611	2026-09-19 21:25	43.62	OK	13612	2026-09-19 21:26	45.78	OK
13613	2026-09-19 21:27	43.72	OK	13614	2026-09-19 21:28	43.14	OK
13615	2026-09-19 21:29	46.61	OK	13616	2026-09-19 21:30	45.28	OK
13617	2026-09-19 21:31	47.69	OK	13618	2026-09-19 21:32	44.02	OK
13619	2026-09-19 21:33	44.72	OK	13620	2026-09-19 21:34	43.03	OK
13621	2026-09-19 21:35	44.50	OK	13622	2026-09-19 21:36	45.41	OK
13623	2026-09-19 21:37	43.95	OK	13624	2026-09-19 21:38	47.14	OK
13625	2026-09-19 21:39	45.09	OK	13626	2026-09-19 21:40	43.98	OK
13627	2026-09-19 21:41	45.85	OK	13628	2026-09-19 21:42	44.92	OK
13629	2026-09-19 21:43	44.38	OK	13630	2026-09-19 21:44	43.92	OK
13631	2026-09-19 21:45	43.66	OK	13632	2026-09-19 21:46	45.28	OK
13633	2026-09-19 21:47	47.31	OK	13634	2026-09-19 21:48	46.28	OK
13635	2026-09-19 21:49	42.38	OK	13636	2026-09-19 21:50	47.30	OK
13637	2026-09-19 21:51	44.47	OK	13638	2026-09-19 21:52	43.58	OK
13639	2026-09-19 21:53	45.09	OK	13640	2026-09-19 21:54	46.46	OK
13641	2026-09-19 21:55	47.26	OK	13642	2026-09-19 21:56	44.33	OK
13643	2026-09-19 21:57	44.78	OK	13644	2026-09-19 21:58	45.84	OK
13645	2026-09-19 21:59	44.04	OK	13646	2026-09-19 22:00	44.87	OK
13647	2026-09-19 22:01	44.41	OK	13648	2026-09-19 22:02	42.83	OK
13649	2026-09-19 22:03	45.34	OK	13650	2026-09-19 22:04	43.48	OK
13651	2026-09-19 22:05	46.36	OK	13652	2026-09-19 22:06	43.14	OK
13653	2026-09-19 22:07	43.54	OK	13654	2026-09-19 22:08	44.47	OK
13655	2026-09-19 22:09	44.03	OK	13656	2026-09-19 22:10	45.25	OK
13657	2026-09-19 22:11	46.47	OK	13658	2026-09-19 22:12	43.75	OK
13659	2026-09-19 22:13	43.28	OK	13660	2026-09-19 22:14	44.49	OK
13661	2026-09-19 22:15	45.41	OK	13662	2026-09-19 22:16	44.95	OK
1366	2026-09-19 22:17	45.07	OK	1366	2026-09-19 22:18	45.50	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
13665	2026-09-19 22:19	44.83	OK	13666	2026-09-19 22:20	42.72	OK
13667	2026-09-19 22:21	44.06	OK	13668	2026-09-19 22:22	45.11	OK
13669	2026-09-19 22:23	47.09	OK	13670	2026-09-19 22:24	43.57	OK
13671	2026-09-19 22:25	43.19	OK	13672	2026-09-19 22:26	43.98	OK
13673	2026-09-19 22:27	44.97	OK	13674	2026-09-19 22:28	44.13	OK
13675	2026-09-19 22:29	47.37	OK	13676	2026-09-19 22:30	45.04	OK
13677	2026-09-19 22:31	43.78	OK	13678	2026-09-19 22:32	45.18	OK
13679	2026-09-19 22:33	46.00	OK	13680	2026-09-19 22:34	45.49	OK
13681	2026-09-19 22:35	45.99	OK	13682	2026-09-19 22:36	44.57	OK
13683	2026-09-19 22:37	45.87	OK	13684	2026-09-19 22:38	44.53	OK
13685	2026-09-19 22:39	46.15	OK	13686	2026-09-19 22:40	42.08	OK
13687	2026-09-19 22:41	43.92	OK	13688	2026-09-19 22:42	46.09	OK
13689	2026-09-19 22:43	45.76	OK	13690	2026-09-19 22:44	43.50	OK
13691	2026-09-19 22:45	45.07	OK	13692	2026-09-19 22:46	44.88	OK
13693	2026-09-19 22:47	45.67	OK	13694	2026-09-19 22:48	45.07	OK
13695	2026-09-19 22:49	45.73	OK	13696	2026-09-19 22:50	45.52	OK
13697	2026-09-19 22:51	45.81	OK	13698	2026-09-19 22:52	44.74	OK
13699	2026-09-19 22:53	44.70	OK	13700	2026-09-19 22:54	46.17	OK
13701	2026-09-19 22:55	43.96	OK	13702	2026-09-19 22:56	44.34	OK
13703	2026-09-19 22:57	43.49	OK	13704	2026-09-19 22:58	44.55	OK
13705	2026-09-19 22:59	42.49	OK	13706	2026-09-19 23:00	45.51	OK
13707	2026-09-19 23:01	43.64	OK	13708	2026-09-19 23:02	46.83	OK
13709	2026-09-19 23:03	43.65	OK	13710	2026-09-19 23:04	44.32	OK
13711	2026-09-19 23:05	45.24	OK	13712	2026-09-19 23:06	45.22	OK
13713	2026-09-19 23:07	45.88	OK	13714	2026-09-19 23:08	45.96	OK
13715	2026-09-19 23:09	45.66	OK	13716	2026-09-19 23:10	45.47	OK
13717	2026-09-19 23:11	47.09	OK	13718	2026-09-19 23:12	44.60	OK
13719	2026-09-19 23:13	44.31	OK	13720	2026-09-19 23:14	44.54	OK
13721	2026-09-19 23:15	42.59	OK	13722	2026-09-19 23:16	44.76	OK
1372	2026-09-19 23:17	42.99	OK	1372	2026-09-19 23:18	46.13	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
13725	2026-09-19 23:19	44.46	OK	13726	2026-09-19 23:20	44.01	OK
13727	2026-09-19 23:21	45.19	OK	13728	2026-09-19 23:22	43.59	OK
13729	2026-09-19 23:23	46.38	OK	13730	2026-09-19 23:24	42.65	OK
13731	2026-09-19 23:25	44.12	OK	13732	2026-09-19 23:26	47.24	OK
13733	2026-09-19 23:27	46.47	OK	13734	2026-09-19 23:28	44.81	OK
13735	2026-09-19 23:29	44.51	OK	13736	2026-09-19 23:30	43.14	OK
13737	2026-09-19 23:31	44.91	OK	13738	2026-09-19 23:32	45.03	OK
13739	2026-09-19 23:33	45.63	OK	13740	2026-09-19 23:34	46.74	OK
13741	2026-09-19 23:35	45.19	OK	13742	2026-09-19 23:36	44.77	OK
13743	2026-09-19 23:37	45.15	OK	13744	2026-09-19 23:38	44.60	OK
13745	2026-09-19 23:39	43.61	OK	13746	2026-09-19 23:40	43.22	OK
13747	2026-09-19 23:41	45.30	OK	13748	2026-09-19 23:42	43.43	OK
13749	2026-09-19 23:43	44.24	OK	13750	2026-09-19 23:44	45.45	OK
13751	2026-09-19 23:45	43.53	OK	13752	2026-09-19 23:46	45.01	OK
13753	2026-09-19 23:47	46.34	OK	13754	2026-09-19 23:48	44.11	OK
13755	2026-09-19 23:49	45.45	OK	13756	2026-09-19 23:50	42.73	OK
13757	2026-09-19 23:51	45.14	OK	13758	2026-09-19 23:52	46.45	OK
13759	2026-09-19 23:53	43.29	OK	13760	2026-09-19 23:54	44.17	OK
13761	2026-09-19 23:55	45.27	OK	13762	2026-09-19 23:56	46.68	OK
13763	2026-09-19 23:57	45.32	OK	13764	2026-09-19 23:58	44.34	OK
13765	2026-09-19 23:59	42.62	OK	13766	2026-09-20 00:00	44.12	OK
13767	2026-09-20 00:01	44.71	OK	13768	2026-09-20 00:02	46.11	OK
13769	2026-09-20 00:03	42.36	OK	13770	2026-09-20 00:04	44.07	OK
13771	2026-09-20 00:05	43.05	OK	13772	2026-09-20 00:06	42.41	OK
13773	2026-09-20 00:07	43.93	OK	13774	2026-09-20 00:08	43.59	OK
13775	2026-09-20 00:09	46.34	OK	13776	2026-09-20 00:10	45.95	OK
13777	2026-09-20 00:11	44.94	OK	13778	2026-09-20 00:12	45.12	OK
13779	2026-09-20 00:13	44.25	OK	13780	2026-09-20 00:14	46.38	OK
13781	2026-09-20 00:15	45.06	OK	13782	2026-09-20 00:16	42.32	OK
1378	2026-09-20 00:17	44.56	OK	1378	2026-09-20 00:18	44.97	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
13785	2026-09-20 00:19	44.75	OK	13786	2026-09-20 00:20	44.84	OK
13787	2026-09-20 00:21	45.55	OK	13788	2026-09-20 00:22	44.08	OK
13789	2026-09-20 00:23	45.10	OK	13790	2026-09-20 00:24	45.48	OK
13791	2026-09-20 00:25	45.62	OK	13792	2026-09-20 00:26	45.46	OK
13793	2026-09-20 00:27	45.31	OK	13794	2026-09-20 00:28	43.94	OK
13795	2026-09-20 00:29	44.25	OK	13796	2026-09-20 00:30	46.52	OK
13797	2026-09-20 00:31	44.14	OK	13798	2026-09-20 00:32	45.61	OK
13799	2026-09-20 00:33	43.76	OK	13800	2026-09-20 00:34	45.27	OK
13801	2026-09-20 00:35	44.36	OK	13802	2026-09-20 00:36	46.70	OK
13803	2026-09-20 00:37	45.27	OK	13804	2026-09-20 00:38	44.19	OK
13805	2026-09-20 00:39	45.13	OK	13806	2026-09-20 00:40	42.22	OK
13807	2026-09-20 00:41	46.07	OK	13808	2026-09-20 00:42	44.39	OK
13809	2026-09-20 00:43	45.78	OK	13810	2026-09-20 00:44	46.50	OK
13811	2026-09-20 00:45	44.52	OK	13812	2026-09-20 00:46	44.81	OK
13813	2026-09-20 00:47	42.75	OK	13814	2026-09-20 00:48	44.99	OK
13815	2026-09-20 00:49	43.70	OK	13816	2026-09-20 00:50	44.28	OK
13817	2026-09-20 00:51	46.55	OK	13818	2026-09-20 00:52	43.71	OK
13819	2026-09-20 00:53	44.31	OK	13820	2026-09-20 00:54	47.22	OK
13821	2026-09-20 00:55	44.31	OK	13822	2026-09-20 00:56	42.78	OK
13823	2026-09-20 00:57	43.06	OK	13824	2026-09-20 00:58	46.46	OK
13825	2026-09-20 00:59	42.87	OK	13826	2026-09-20 01:00	43.69	OK
13827	2026-09-20 01:01	44.07	OK	13828	2026-09-20 01:02	44.68	OK
13829	2026-09-20 01:03	44.17	OK	13830	2026-09-20 01:04	43.72	OK
13831	2026-09-20 01:05	44.07	OK	13832	2026-09-20 01:06	47.78	OK
13833	2026-09-20 01:07	43.87	OK	13834	2026-09-20 01:08	44.71	OK
13835	2026-09-20 01:09	45.31	OK	13836	2026-09-20 01:10	45.17	OK
13837	2026-09-20 01:11	45.21	OK	13838	2026-09-20 01:12	46.06	OK
13839	2026-09-20 01:13	45.55	OK	13840	2026-09-20 01:14	44.85	OK
13841	2026-09-20 01:15	45.39	OK	13842	2026-09-20 01:16	44.08	OK
1384	2026-09-20 01:17	46.32	OK	1384	2026-09-20 01:18	46.48	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
13845	2026-09-20 01:19	45.66	OK	13846	2026-09-20 01:20	45.21	OK
13847	2026-09-20 01:21	43.86	OK	13848	2026-09-20 01:22	43.94	OK
13849	2026-09-20 01:23	45.29	OK	13850	2026-09-20 01:24	45.65	OK
13851	2026-09-20 01:25	45.25	OK	13852	2026-09-20 01:26	42.87	OK
13853	2026-09-20 01:27	47.35	OK	13854	2026-09-20 01:28	42.80	OK
13855	2026-09-20 01:29	44.69	OK	13856	2026-09-20 01:30	47.36	OK
13857	2026-09-20 01:31	45.52	OK	13858	2026-09-20 01:32	46.00	OK
13859	2026-09-20 01:33	43.60	OK	13860	2026-09-20 01:34	46.97	OK
13861	2026-09-20 01:35	46.14	OK	13862	2026-09-20 01:36	45.06	OK
13863	2026-09-20 01:37	45.68	OK	13864	2026-09-20 01:38	44.78	OK
13865	2026-09-20 01:39	45.65	OK	13866	2026-09-20 01:40	47.90	OK
13867	2026-09-20 01:41	43.96	OK	13868	2026-09-20 01:42	45.97	OK
13869	2026-09-20 01:43	47.48	OK	13870	2026-09-20 01:44	45.03	OK
13871	2026-09-20 01:45	45.10	OK	13872	2026-09-20 01:46	45.62	OK
13873	2026-09-20 01:47	45.48	OK	13874	2026-09-20 01:48	45.21	OK
13875	2026-09-20 01:49	45.37	OK	13876	2026-09-20 01:50	46.66	OK
13877	2026-09-20 01:51	44.98	OK	13878	2026-09-20 01:52	43.35	OK
13879	2026-09-20 01:53	45.82	OK	13880	2026-09-20 01:54	43.25	OK
13881	2026-09-20 01:55	44.66	OK	13882	2026-09-20 01:56	47.24	OK
13883	2026-09-20 01:57	45.83	OK	13884	2026-09-20 01:58	46.29	OK
13885	2026-09-20 01:59	46.87	OK	13886	2026-09-20 02:00	45.76	OK
13887	2026-09-20 02:01	46.14	OK	13888	2026-09-20 02:02	44.24	OK
13889	2026-09-20 02:03	44.32	OK	13890	2026-09-20 02:04	43.41	OK
13891	2026-09-20 02:05	44.47	OK	13892	2026-09-20 02:06	44.81	OK
13893	2026-09-20 02:07	46.63	OK	13894	2026-09-20 02:08	44.54	OK
13895	2026-09-20 02:09	47.26	OK	13896	2026-09-20 02:10	46.64	OK
13897	2026-09-20 02:11	46.16	OK	13898	2026-09-20 02:12	46.33	OK
13899	2026-09-20 02:13	44.74	OK	13900	2026-09-20 02:14	46.76	OK
13901	2026-09-20 02:15	44.33	OK	13902	2026-09-20 02:16	45.94	OK
1390	2026-09-20 02:17	45.55	OK	1390	2026-09-20 02:18	45.96	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
13905	2026-09-20 02:19	47.11	OK	13906	2026-09-20 02:20	45.14	OK
13907	2026-09-20 02:21	47.04	OK	13908	2026-09-20 02:22	45.40	OK
13909	2026-09-20 02:23	46.47	OK	13910	2026-09-20 02:24	46.93	OK
13911	2026-09-20 02:25	43.59	OK	13912	2026-09-20 02:26	46.01	OK
13913	2026-09-20 02:27	45.91	OK	13914	2026-09-20 02:28	46.48	OK
13915	2026-09-20 02:29	46.98	OK	13916	2026-09-20 02:30	47.37	OK
13917	2026-09-20 02:31	45.80	OK	13918	2026-09-20 02:32	47.83	OK
13919	2026-09-20 02:33	46.39	OK	13920	2026-09-20 02:34	46.21	OK
13921	2026-09-20 02:35	45.82	OK	13922	2026-09-20 02:36	45.71	OK
13923	2026-09-20 02:37	46.05	OK	13924	2026-09-20 02:38	45.40	OK
13925	2026-09-20 02:39	45.22	OK	13926	2026-09-20 02:40	45.60	OK
13927	2026-09-20 02:41	44.86	OK	13928	2026-09-20 02:42	44.48	OK
13929	2026-09-20 02:43	48.02	OK	13930	2026-09-20 02:44	46.31	OK
13931	2026-09-20 02:45	46.37	OK	13932	2026-09-20 02:46	47.10	OK
13933	2026-09-20 02:47	45.56	OK	13934	2026-09-20 02:48	46.06	OK
13935	2026-09-20 02:49	47.02	OK	13936	2026-09-20 02:50	45.99	OK
13937	2026-09-20 02:51	46.82	OK	13938	2026-09-20 02:52	45.91	OK
13939	2026-09-20 02:53	47.29	OK	13940	2026-09-20 02:54	45.66	OK
13941	2026-09-20 02:55	45.62	OK	13942	2026-09-20 02:56	45.65	OK
13943	2026-09-20 02:57	45.71	OK	13944	2026-09-20 02:58	45.56	OK
13945	2026-09-20 02:59	46.58	OK	13946	2026-09-20 03:00	48.77	OK
13947	2026-09-20 03:01	47.70	OK	13948	2026-09-20 03:02	46.97	OK
13949	2026-09-20 03:03	47.04	OK	13950	2026-09-20 03:04	47.82	OK
13951	2026-09-20 03:05	46.38	OK	13952	2026-09-20 03:06	45.34	OK
13953	2026-09-20 03:07	48.33	OK	13954	2026-09-20 03:08	46.60	OK
13955	2026-09-20 03:09	46.30	OK	13956	2026-09-20 03:10	46.63	OK
13957	2026-09-20 03:11	47.28	OK	13958	2026-09-20 03:12	48.70	OK
13959	2026-09-20 03:13	46.97	OK	13960	2026-09-20 03:14	46.52	OK
13961	2026-09-20 03:15	46.06	OK	13962	2026-09-20 03:16	48.30	OK
1396	2026-09-20 03:17	47.75	OK	1396	2026-09-20 03:18	47.38	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
13965	2026-09-20 03:19	45.51	OK	13966	2026-09-20 03:20	46.81	OK
13967	2026-09-20 03:21	46.75	OK	13968	2026-09-20 03:22	48.21	OK
13969	2026-09-20 03:23	45.92	OK	13970	2026-09-20 03:24	44.75	OK
13971	2026-09-20 03:25	45.83	OK	13972	2026-09-20 03:26	48.30	OK
13973	2026-09-20 03:27	46.65	OK	13974	2026-09-20 03:28	46.48	OK
13975	2026-09-20 03:29	48.24	OK	13976	2026-09-20 03:30	47.27	OK
13977	2026-09-20 03:31	47.69	OK	13978	2026-09-20 03:32	45.46	OK
13979	2026-09-20 03:33	46.13	OK	13980	2026-09-20 03:34	46.96	OK
13981	2026-09-20 03:35	46.45	OK	13982	2026-09-20 03:36	46.52	OK
13983	2026-09-20 03:37	46.23	OK	13984	2026-09-20 03:38	46.55	OK
13985	2026-09-20 03:39	49.36	OK	13986	2026-09-20 03:40	48.59	OK
13987	2026-09-20 03:41	47.10	OK	13988	2026-09-20 03:42	46.50	OK
13989	2026-09-20 03:43	48.62	OK	13990	2026-09-20 03:44	46.45	OK
13991	2026-09-20 03:45	47.05	OK	13992	2026-09-20 03:46	46.38	OK
13993	2026-09-20 03:47	45.84	OK	13994	2026-09-20 03:48	46.01	OK
13995	2026-09-20 03:49	44.99	OK	13996	2026-09-20 03:50	46.17	OK
13997	2026-09-20 03:51	46.49	OK	13998	2026-09-20 03:52	48.30	OK
13999	2026-09-20 03:53	46.52	OK	14000	2026-09-20 03:54	46.80	OK
14001	2026-09-20 03:55	48.54	OK	14002	2026-09-20 03:56	46.71	OK
14003	2026-09-20 03:57	47.38	OK	14004	2026-09-20 03:58	47.46	OK
14005	2026-09-20 03:59	47.60	OK	14006	2026-09-20 04:00	49.23	OK
14007	2026-09-20 04:01	46.30	OK	14008	2026-09-20 04:02	47.02	OK
14009	2026-09-20 04:03	46.82	OK	14010	2026-09-20 04:04	48.65	OK
14011	2026-09-20 04:05	48.29	OK	14012	2026-09-20 04:06	47.70	OK
14013	2026-09-20 04:07	47.07	OK	14014	2026-09-20 04:08	48.79	OK
14015	2026-09-20 04:09	48.55	OK	14016	2026-09-20 04:10	48.16	OK
14017	2026-09-20 04:11	48.61	OK	14018	2026-09-20 04:12	47.14	OK
14019	2026-09-20 04:13	46.51	OK	14020	2026-09-20 04:14	47.13	OK
14021	2026-09-20 04:15	49.77	OK	14022	2026-09-20 04:16	49.19	OK
1402	2026-09-20 04:17	47.33	OK	1402	2026-09-20 04:18	50.04	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
14025	2026-09-20 04:19	48.53	OK	14026	2026-09-20 04:20	46.66	OK
14027	2026-09-20 04:21	47.31	OK	14028	2026-09-20 04:22	47.03	OK
14029	2026-09-20 04:23	48.89	OK	14030	2026-09-20 04:24	47.67	OK
14031	2026-09-20 04:25	49.00	OK	14032	2026-09-20 04:26	47.81	OK
14033	2026-09-20 04:27	48.19	OK	14034	2026-09-20 04:28	47.17	OK
14035	2026-09-20 04:29	47.32	OK	14036	2026-09-20 04:30	48.69	OK
14037	2026-09-20 04:31	48.54	OK	14038	2026-09-20 04:32	49.09	OK
14039	2026-09-20 04:33	49.72	OK	14040	2026-09-20 04:34	47.41	OK
14041	2026-09-20 04:35	48.38	OK	14042	2026-09-20 04:36	47.41	OK
14043	2026-09-20 04:37	48.00	OK	14044	2026-09-20 04:38	48.64	OK
14045	2026-09-20 04:39	50.43	OK	14046	2026-09-20 04:40	48.95	OK
14047	2026-09-20 04:41	46.66	OK	14048	2026-09-20 04:42	49.01	OK
14049	2026-09-20 04:43	49.50	OK	14050	2026-09-20 04:44	47.78	OK
14051	2026-09-20 04:45	48.98	OK	14052	2026-09-20 04:46	45.83	OK
14053	2026-09-20 04:47	48.52	OK	14054	2026-09-20 04:48	47.49	OK
14055	2026-09-20 04:49	48.14	OK	14056	2026-09-20 04:50	50.62	OK
14057	2026-09-20 04:51	48.03	OK	14058	2026-09-20 04:52	48.89	OK
14059	2026-09-20 04:53	48.30	OK	14060	2026-09-20 04:54	48.97	OK
14061	2026-09-20 04:55	50.43	OK	14062	2026-09-20 04:56	49.33	OK
14063	2026-09-20 04:57	47.83	OK	14064	2026-09-20 04:58	48.37	OK
14065	2026-09-20 04:59	48.73	OK	14066	2026-09-20 05:00	49.01	OK
14067	2026-09-20 05:01	49.21	OK	14068	2026-09-20 05:02	48.50	OK
14069	2026-09-20 05:03	48.29	OK	14070	2026-09-20 05:04	48.11	OK
14071	2026-09-20 05:05	49.27	OK	14072	2026-09-20 05:06	49.04	OK
14073	2026-09-20 05:07	49.50	OK	14074	2026-09-20 05:08	48.68	OK
14075	2026-09-20 05:09	47.89	OK	14076	2026-09-20 05:10	48.08	OK
14077	2026-09-20 05:11	47.82	OK	14078	2026-09-20 05:12	49.00	OK
14079	2026-09-20 05:13	50.34	OK	14080	2026-09-20 05:14	48.89	OK
14081	2026-09-20 05:15	49.12	OK	14082	2026-09-20 05:16	50.34	OK
1408	2026-09-20 05:17	50.45	OK	1408	2026-09-20 05:18	48.76	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
14085	2026-09-20 05:19	49.31	OK	14086	2026-09-20 05:20	48.05	OK
14087	2026-09-20 05:21	48.00	OK	14088	2026-09-20 05:22	47.84	OK
14089	2026-09-20 05:23	48.18	OK	14090	2026-09-20 05:24	49.58	OK
14091	2026-09-20 05:25	49.92	OK	14092	2026-09-20 05:26	47.73	OK
14093	2026-09-20 05:27	49.69	OK	14094	2026-09-20 05:28	50.27	OK
14095	2026-09-20 05:29	47.42	OK	14096	2026-09-20 05:30	49.01	OK
14097	2026-09-20 05:31	47.64	OK	14098	2026-09-20 05:32	50.97	OK
14099	2026-09-20 05:33	51.04	OK	14100	2026-09-20 05:34	49.25	OK
14101	2026-09-20 05:35	49.97	OK	14102	2026-09-20 05:36	52.01	OK
14103	2026-09-20 05:37	48.29	OK	14104	2026-09-20 05:38	50.04	OK
14105	2026-09-20 05:39	49.90	OK	14106	2026-09-20 05:40	51.91	OK
14107	2026-09-20 05:41	49.19	OK	14108	2026-09-20 05:42	50.71	OK
14109	2026-09-20 05:43	48.64	OK	14110	2026-09-20 05:44	50.27	OK
14111	2026-09-20 05:45	47.94	OK	14112	2026-09-20 05:46	51.01	OK
14113	2026-09-20 05:47	49.81	OK	14114	2026-09-20 05:48	49.59	OK
14115	2026-09-20 05:49	50.48	OK	14116	2026-09-20 05:50	49.55	OK
14117	2026-09-20 05:51	50.23	OK	14118	2026-09-20 05:52	49.48	OK
14119	2026-09-20 05:53	50.94	OK	14120	2026-09-20 05:54	48.73	OK
14121	2026-09-20 05:55	51.05	OK	14122	2026-09-20 05:56	51.28	OK
14123	2026-09-20 05:57	49.99	OK	14124	2026-09-20 05:58	47.92	OK
14125	2026-09-20 05:59	49.43	OK	14126	2026-09-20 06:00	48.28	OK
14127	2026-09-20 06:01	49.73	OK	14128	2026-09-20 06:02	49.13	OK
14129	2026-09-20 06:03	50.80	OK	14130	2026-09-20 06:04	51.47	OK
14131	2026-09-20 06:05	49.70	OK	14132	2026-09-20 06:06	49.04	OK
14133	2026-09-20 06:07	47.84	OK	14134	2026-09-20 06:08	50.35	OK
14135	2026-09-20 06:09	49.32	OK	14136	2026-09-20 06:10	51.72	OK
14137	2026-09-20 06:11	50.89	OK	14138	2026-09-20 06:12	52.56	OK
14139	2026-09-20 06:13	50.13	OK	14140	2026-09-20 06:14	50.88	OK
14141	2026-09-20 06:15	51.22	OK	14142	2026-09-20 06:16	51.14	OK
1414	2026-09-20 06:17	51.09	OK	1414	2026-09-20 06:18	49.58	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
14145	2026-09-20 06:19	51.64	OK	14146	2026-09-20 06:20	51.64	OK
14147	2026-09-20 06:21	50.89	OK	14148	2026-09-20 06:22	51.47	OK
14149	2026-09-20 06:23	51.15	OK	14150	2026-09-20 06:24	51.08	OK
14151	2026-09-20 06:25	49.21	OK	14152	2026-09-20 06:26	49.34	OK
14153	2026-09-20 06:27	49.73	OK	14154	2026-09-20 06:28	49.60	OK
14155	2026-09-20 06:29	51.23	OK	14156	2026-09-20 06:30	49.34	OK
14157	2026-09-20 06:31	48.47	OK	14158	2026-09-20 06:32	50.76	OK
14159	2026-09-20 06:33	49.28	OK	14160	2026-09-20 06:34	51.14	OK
14161	2026-09-20 06:35	51.34	OK	14162	2026-09-20 06:36	50.60	OK
14163	2026-09-20 06:37	50.41	OK	14164	2026-09-20 06:38	51.45	OK
14165	2026-09-20 06:39	52.25	OK	14166	2026-09-20 06:40	51.81	OK
14167	2026-09-20 06:41	49.14	OK	14168	2026-09-20 06:42	50.02	OK
14169	2026-09-20 06:43	51.45	OK	14170	2026-09-20 06:44	51.66	OK
14171	2026-09-20 06:45	52.69	OK	14172	2026-09-20 06:46	51.48	OK
14173	2026-09-20 06:47	50.58	OK	14174	2026-09-20 06:48	50.93	OK
14175	2026-09-20 06:49	51.30	OK	14176	2026-09-20 06:50	51.86	OK
14177	2026-09-20 06:51	50.48	OK	14178	2026-09-20 06:52	50.13	OK
14179	2026-09-20 06:53	50.92	OK	14180	2026-09-20 06:54	49.32	OK
14181	2026-09-20 06:55	51.36	OK	14182	2026-09-20 06:56	51.99	OK
14183	2026-09-20 06:57	51.95	OK	14184	2026-09-20 06:58	53.09	OK
14185	2026-09-20 06:59	51.44	OK	14186	2026-09-20 07:00	51.41	OK
14187	2026-09-20 07:01	50.81	OK	14188	2026-09-20 07:02	50.76	OK
14189	2026-09-20 07:03	49.68	OK	14190	2026-09-20 07:04	51.48	OK
14191	2026-09-20 07:05	51.35	OK	14192	2026-09-20 07:06	51.96	OK
14193	2026-09-20 07:07	49.93	OK	14194	2026-09-20 07:08	50.53	OK
14195	2026-09-20 07:09	52.06	OK	14196	2026-09-20 07:10	50.18	OK
14197	2026-09-20 07:11	50.05	OK	14198	2026-09-20 07:12	51.59	OK
14199	2026-09-20 07:13	50.13	OK	14200	2026-09-20 07:14	50.48	OK
14201	2026-09-20 07:15	51.38	OK	14202	2026-09-20 07:16	50.57	OK
1420	2026-09-20 07:17	51.10	OK	1420	2026-09-20 07:18	51.88	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
14205	2026-09-20 07:19	51.62	OK	14206	2026-09-20 07:20	50.10	OK
14207	2026-09-20 07:21	53.00	OK	14208	2026-09-20 07:22	50.58	OK
14209	2026-09-20 07:23	52.13	OK	14210	2026-09-20 07:24	52.95	OK
14211	2026-09-20 07:25	54.04	OK	14212	2026-09-20 07:26	53.83	OK
14213	2026-09-20 07:27	52.28	OK	14214	2026-09-20 07:28	53.15	OK
14215	2026-09-20 07:29	52.41	OK	14216	2026-09-20 07:30	52.25	OK
14217	2026-09-20 07:31	53.04	OK	14218	2026-09-20 07:32	52.75	OK
14219	2026-09-20 07:33	52.76	OK	14220	2026-09-20 07:34	52.56	OK
14221	2026-09-20 07:35	52.33	OK	14222	2026-09-20 07:36	50.43	OK
14223	2026-09-20 07:37	51.68	OK	14224	2026-09-20 07:38	50.12	OK
14225	2026-09-20 07:39	52.03	OK	14226	2026-09-20 07:40	50.18	OK
14227	2026-09-20 07:41	53.93	OK	14228	2026-09-20 07:42	54.03	OK
14229	2026-09-20 07:43	53.33	OK	14230	2026-09-20 07:44	51.01	OK
14231	2026-09-20 07:45	50.14	OK	14232	2026-09-20 07:46	52.70	OK
14233	2026-09-20 07:47	52.84	OK	14234	2026-09-20 07:48	52.10	OK
14235	2026-09-20 07:49	54.10	OK	14236	2026-09-20 07:50	53.64	OK
14237	2026-09-20 07:51	53.36	OK	14238	2026-09-20 07:52	52.81	OK
14239	2026-09-20 07:53	53.29	OK	14240	2026-09-20 07:54	51.27	OK
14241	2026-09-20 07:55	52.89	OK	14242	2026-09-20 07:56	53.94	OK
14243	2026-09-20 07:57	53.35	OK	14244	2026-09-20 07:58	51.39	OK
14245	2026-09-20 07:59	54.57	OK	14246	2026-09-20 08:00	52.73	OK
14247	2026-09-20 08:01	52.83	OK	14248	2026-09-20 08:02	50.82	OK
14249	2026-09-20 08:03	50.89	OK	14250	2026-09-20 08:04	53.43	OK
14251	2026-09-20 08:05	51.18	OK	14252	2026-09-20 08:06	50.10	OK
14253	2026-09-20 08:07	51.21	OK	14254	2026-09-20 08:08	52.07	OK
14255	2026-09-20 08:09	51.65	OK	14256	2026-09-20 08:10	52.16	OK
14257	2026-09-20 08:11	52.00	OK	14258	2026-09-20 08:12	52.83	OK
14259	2026-09-20 08:13	50.65	OK	14260	2026-09-20 08:14	52.32	OK
14261	2026-09-20 08:15	51.69	OK	14262	2026-09-20 08:16	50.65	OK
1426	2026-09-20 08:17	52.93	OK	1426	2026-09-20 08:18	53.84	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
14265	2026-09-20 08:19	53.09	OK	14266	2026-09-20 08:20	52.21	OK
14267	2026-09-20 08:21	52.85	OK	14268	2026-09-20 08:22	52.96	OK
14269	2026-09-20 08:23	52.09	OK	14270	2026-09-20 08:24	53.15	OK
14271	2026-09-20 08:25	51.35	OK	14272	2026-09-20 08:26	51.77	OK
14273	2026-09-20 08:27	52.65	OK	14274	2026-09-20 08:28	53.18	OK
14275	2026-09-20 08:29	50.64	OK	14276	2026-09-20 08:30	53.09	OK
14277	2026-09-20 08:31	51.76	OK	14278	2026-09-20 08:32	51.99	OK
14279	2026-09-20 08:33	55.35	OK	14280	2026-09-20 08:34	53.58	OK
14281	2026-09-20 08:35	51.81	OK	14282	2026-09-20 08:36	54.03	OK
14283	2026-09-20 08:37	51.89	OK	14284	2026-09-20 08:38	53.62	OK
14285	2026-09-20 08:39	53.12	OK	14286	2026-09-20 08:40	54.90	OK
14287	2026-09-20 08:41	53.72	OK	14288	2026-09-20 08:42	54.55	OK
14289	2026-09-20 08:43	51.75	OK	14290	2026-09-20 08:44	52.71	OK
14291	2026-09-20 08:45	52.58	OK	14292	2026-09-20 08:46	52.86	OK
14293	2026-09-20 08:47	52.59	OK	14294	2026-09-20 08:48	50.96	OK
14295	2026-09-20 08:49	52.37	OK	14296	2026-09-20 08:50	53.28	OK
14297	2026-09-20 08:51	53.38	OK	14298	2026-09-20 08:52	53.03	OK
14299	2026-09-20 08:53	53.69	OK	14300	2026-09-20 08:54	52.18	OK
14301	2026-09-20 08:55	54.35	OK	14302	2026-09-20 08:56	55.43	OK
14303	2026-09-20 08:57	51.71	OK	14304	2026-09-20 08:58	53.03	OK
14305	2026-09-20 08:59	52.01	OK	14306	2026-09-20 09:00	54.15	OK
14307	2026-09-20 09:01	52.39	OK	14308	2026-09-20 09:02	52.30	OK
14309	2026-09-20 09:03	51.50	OK	14310	2026-09-20 09:04	54.79	OK
14311	2026-09-20 09:05	51.74	OK	14312	2026-09-20 09:06	52.57	OK
14313	2026-09-20 09:07	52.02	OK	14314	2026-09-20 09:08	53.50	OK
14315	2026-09-20 09:09	52.70	OK	14316	2026-09-20 09:10	52.90	OK
14317	2026-09-20 09:11	52.88	OK	14318	2026-09-20 09:12	51.91	OK
14319	2026-09-20 09:13	53.47	OK	14320	2026-09-20 09:14	55.01	OK
14321	2026-09-20 09:15	54.70	OK	14322	2026-09-20 09:16	52.76	OK
1432	2026-09-20 09:17	53.03	OK	1432	2026-09-20 09:18	56.27	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
14325	2026-09-20 09:19	54.37	OK	14326	2026-09-20 09:20	54.82	OK
14327	2026-09-20 09:21	53.03	OK	14328	2026-09-20 09:22	53.69	OK
14329	2026-09-20 09:23	53.39	OK	14330	2026-09-20 09:24	54.49	OK
14331	2026-09-20 09:25	53.66	OK	14332	2026-09-20 09:26	52.95	OK
14333	2026-09-20 09:27	52.75	OK	14334	2026-09-20 09:28	52.44	OK
14335	2026-09-20 09:29	54.54	OK	14336	2026-09-20 09:30	52.42	OK
14337	2026-09-20 09:31	52.85	OK	14338	2026-09-20 09:32	52.48	OK
14339	2026-09-20 09:33	54.57	OK	14340	2026-09-20 09:34	55.04	OK
14341	2026-09-20 09:35	53.84	OK	14342	2026-09-20 09:36	54.80	OK
14343	2026-09-20 09:37	52.91	OK	14344	2026-09-20 09:38	54.96	OK
14345	2026-09-20 09:39	51.89	OK	14346	2026-09-20 09:40	54.49	OK
14347	2026-09-20 09:41	53.68	OK	14348	2026-09-20 09:42	54.51	OK
14349	2026-09-20 09:43	54.83	OK	14350	2026-09-20 09:44	53.45	OK
14351	2026-09-20 09:45	53.54	OK	14352	2026-09-20 09:46	54.33	OK
14353	2026-09-20 09:47	52.64	OK	14354	2026-09-20 09:48	52.33	OK
14355	2026-09-20 09:49	52.37	OK	14356	2026-09-20 09:50	52.85	OK
14357	2026-09-20 09:51	53.85	OK	14358	2026-09-20 09:52	53.72	OK
14359	2026-09-20 09:53	54.94	OK	14360	2026-09-20 09:54	52.52	OK
14361	2026-09-20 09:55	55.12	OK	14362	2026-09-20 09:56	54.26	OK
14363	2026-09-20 09:57	53.89	OK	14364	2026-09-20 09:58	53.82	OK
14365	2026-09-20 09:59	53.69	OK	14366	2026-09-20 10:00	54.60	OK
14367	2026-09-20 10:01	51.68	OK	14368	2026-09-20 10:02	54.20	OK
14369	2026-09-20 10:03	54.77	OK	14370	2026-09-20 10:04	55.59	OK
14371	2026-09-20 10:05	52.04	OK	14372	2026-09-20 10:06	52.19	OK
14373	2026-09-20 10:07	54.38	OK	14374	2026-09-20 10:08	52.61	OK
14375	2026-09-20 10:09	53.01	OK	14376	2026-09-20 10:10	53.50	OK
14377	2026-09-20 10:11	53.12	OK	14378	2026-09-20 10:12	54.99	OK
14379	2026-09-20 10:13	51.95	OK	14380	2026-09-20 10:14	53.08	OK
14381	2026-09-20 10:15	52.67	OK	14382	2026-09-20 10:16	53.90	OK
1438	2026-09-20 10:17	54.62	OK	1438	2026-09-20 10:18	53.44	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
14385	2026-09-20 10:19	53.91	OK	14386	2026-09-20 10:20	54.67	OK
14387	2026-09-20 10:21	53.96	OK	14388	2026-09-20 10:22	53.97	OK
14389	2026-09-20 10:23	55.29	OK	14390	2026-09-20 10:24	54.27	OK
14391	2026-09-20 10:25	54.11	OK	14392	2026-09-20 10:26	52.16	OK
14393	2026-09-20 10:27	52.17	OK	14394	2026-09-20 10:28	54.96	OK
14395	2026-09-20 10:29	54.39	OK	14396	2026-09-20 10:30	55.53	OK
14397	2026-09-20 10:31	53.23	OK	14398	2026-09-20 10:32	56.29	OK
14399	2026-09-20 10:33	54.69	OK	14400	2026-09-20 10:34	54.75	OK
14401	2026-09-20 10:35	52.96	OK	14402	2026-09-20 10:36	55.60	OK
14403	2026-09-20 10:37	54.32	OK	14404	2026-09-20 10:38	54.43	OK
14405	2026-09-20 10:39	51.78	OK	14406	2026-09-20 10:40	52.20	OK
14407	2026-09-20 10:41	55.00	OK	14408	2026-09-20 10:42	54.13	OK
14409	2026-09-20 10:43	52.40	OK	14410	2026-09-20 10:44	53.83	OK
14411	2026-09-20 10:45	55.91	OK	14412	2026-09-20 10:46	52.51	OK
14413	2026-09-20 10:47	53.36	OK	14414	2026-09-20 10:48	55.32	OK
14415	2026-09-20 10:49	55.01	OK	14416	2026-09-20 10:50	54.79	OK
14417	2026-09-20 10:51	54.50	OK	14418	2026-09-20 10:52	52.51	OK
14419	2026-09-20 10:53	53.08	OK	14420	2026-09-20 10:54	53.21	OK
14421	2026-09-20 10:55	53.77	OK	14422	2026-09-20 10:56	54.80	OK
14423	2026-09-20 10:57	55.77	OK	14424	2026-09-20 10:58	54.45	OK
14425	2026-09-20 10:59	54.90	OK	14426	2026-09-20 11:00	52.65	OK
14427	2026-09-20 11:01	55.63	OK	14428	2026-09-20 11:02	54.99	OK
14429	2026-09-20 11:03	54.75	OK	14430	2026-09-20 11:04	53.42	OK
14431	2026-09-20 11:05	52.67	OK	14432	2026-09-20 11:06	53.72	OK
14433	2026-09-20 11:07	54.67	OK	14434	2026-09-20 11:08	53.15	OK
14435	2026-09-20 11:09	51.99	OK	14436	2026-09-20 11:10	54.34	OK
14437	2026-09-20 11:11	53.92	OK	14438	2026-09-20 11:12	55.89	OK
14439	2026-09-20 11:13	54.36	OK	14440	2026-09-20 11:14	52.53	OK
14441	2026-09-20 11:15	54.03	OK	14442	2026-09-20 11:16	53.86	OK
1444	2026-09-20 11:17	53.89	OK	1444	2026-09-20 11:18	55.03	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
14445	2026-09-20 11:19	54.20	OK	14446	2026-09-20 11:20	55.75	OK
14447	2026-09-20 11:21	53.87	OK	14448	2026-09-20 11:22	56.17	OK
14449	2026-09-20 11:23	55.74	OK	14450	2026-09-20 11:24	55.82	OK
14451	2026-09-20 11:25	53.63	OK	14452	2026-09-20 11:26	53.60	OK
14453	2026-09-20 11:27	55.25	OK	14454	2026-09-20 11:28	53.72	OK
14455	2026-09-20 11:29	54.36	OK	14456	2026-09-20 11:30	55.26	OK
14457	2026-09-20 11:31	54.82	OK	14458	2026-09-20 11:32	53.55	OK
14459	2026-09-20 11:33	53.10	OK	14460	2026-09-20 11:34	55.64	OK
14461	2026-09-20 11:35	55.05	OK	14462	2026-09-20 11:36	54.70	OK
14463	2026-09-20 11:37	55.24	OK	14464	2026-09-20 11:38	55.79	OK
14465	2026-09-20 11:39	53.67	OK	14466	2026-09-20 11:40	53.75	OK
14467	2026-09-20 11:41	52.45	OK	14468	2026-09-20 11:42	54.99	OK
14469	2026-09-20 11:43	53.97	OK	14470	2026-09-20 11:44	54.36	OK
14471	2026-09-20 11:45	55.10	OK	14472	2026-09-20 11:46	54.07	OK
14473	2026-09-20 11:47	54.30	OK	14474	2026-09-20 11:48	54.75	OK
14475	2026-09-20 11:49	53.13	OK	14476	2026-09-20 11:50	54.40	OK
14477	2026-09-20 11:51	52.78	OK	14478	2026-09-20 11:52	53.98	OK
14479	2026-09-20 11:53	54.16	OK	14480	2026-09-20 11:54	52.60	OK
14481	2026-09-20 11:55	55.76	OK	14482	2026-09-20 11:56	53.88	OK
14483	2026-09-20 11:57	54.40	OK	14484	2026-09-20 11:58	52.68	OK
14485	2026-09-20 11:59	55.35	OK	14486	2026-09-20 12:00	52.43	OK
14487	2026-09-20 12:01	54.73	OK	14488	2026-09-20 12:02	52.97	OK
14489	2026-09-20 12:03	53.43	OK	14490	2026-09-20 12:04	54.93	OK
14491	2026-09-20 12:05	53.60	OK	14492	2026-09-20 12:06	53.80	OK
14493	2026-09-20 12:07	55.64	OK	14494	2026-09-20 12:08	54.94	OK
14495	2026-09-20 12:09	52.94	OK	14496	2026-09-20 12:10	53.14	OK
14497	2026-09-20 12:11	51.42	OK	14498	2026-09-20 12:12	54.52	OK
14499	2026-09-20 12:13	55.09	OK	14500	2026-09-20 12:14	53.08	OK
14501	2026-09-20 12:15	53.77	OK	14502	2026-09-20 12:16	54.77	OK
14503	2026-09-20 12:17	52.82	OK	14504	2026-09-20 12:18	54.75	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
14505	2026-09-20 12:19	54.83	OK	14506	2026-09-20 12:20	53.99	OK
14507	2026-09-20 12:21	56.84	OK	14508	2026-09-20 12:22	52.05	OK
14509	2026-09-20 12:23	54.59	OK	14510	2026-09-20 12:24	54.81	OK
14511	2026-09-20 12:25	54.00	OK	14512	2026-09-20 12:26	56.32	OK
14513	2026-09-20 12:27	54.13	OK	14514	2026-09-20 12:28	55.09	OK
14515	2026-09-20 12:29	56.42	OK	14516	2026-09-20 12:30	54.71	OK
14517	2026-09-20 12:31	56.14	OK	14518	2026-09-20 12:32	54.94	OK
14519	2026-09-20 12:33	55.40	OK	14520	2026-09-20 12:34	54.83	OK
14521	2026-09-20 12:35	52.27	OK	14522	2026-09-20 12:36	56.17	OK
14523	2026-09-20 12:37	54.50	OK	14524	2026-09-20 12:38	54.13	OK
14525	2026-09-20 12:39	53.93	OK	14526	2026-09-20 12:40	53.57	OK
14527	2026-09-20 12:41	52.49	OK	14528	2026-09-20 12:42	54.62	OK
14529	2026-09-20 12:43	52.19	OK	14530	2026-09-20 12:44	53.43	OK
14531	2026-09-20 12:45	55.10	OK	14532	2026-09-20 12:46	53.22	OK
14533	2026-09-20 12:47	54.64	OK	14534	2026-09-20 12:48	55.14	OK
14535	2026-09-20 12:49	54.35	OK	14536	2026-09-20 12:50	53.49	OK
14537	2026-09-20 12:51	53.50	OK	14538	2026-09-20 12:52	53.93	OK
14539	2026-09-20 12:53	53.92	OK	14540	2026-09-20 12:54	53.30	OK
14541	2026-09-20 12:55	52.08	OK	14542	2026-09-20 12:56	54.67	OK
14543	2026-09-20 12:57	54.20	OK	14544	2026-09-20 12:58	53.47	OK
14545	2026-09-20 12:59	54.45	OK	14546	2026-09-20 13:00	53.90	OK
14547	2026-09-20 13:01	54.83	OK	14548	2026-09-20 13:02	55.35	OK
14549	2026-09-20 13:03	54.62	OK	14550	2026-09-20 13:04	52.97	OK
14551	2026-09-20 13:05	55.15	OK	14552	2026-09-20 13:06	53.70	OK
14553	2026-09-20 13:07	54.76	OK	14554	2026-09-20 13:08	55.00	OK
14555	2026-09-20 13:09	51.28	OK	14556	2026-09-20 13:10	52.21	OK
14557	2026-09-20 13:11	55.75	OK	14558	2026-09-20 13:12	52.89	OK
14559	2026-09-20 13:13	52.55	OK	14560	2026-09-20 13:14	54.28	OK
14561	2026-09-20 13:15	52.84	OK	14562	2026-09-20 13:16	52.83	OK
1456	2026-09-20 13:17	54.78	OK	1456	2026-09-20 13:18	53.08	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
14565	2026-09-20 13:19	54.18	OK	14566	2026-09-20 13:20	55.42	OK
14567	2026-09-20 13:21	54.95	OK	14568	2026-09-20 13:22	53.75	OK
14569	2026-09-20 13:23	53.88	OK	14570	2026-09-20 13:24	53.24	OK
14571	2026-09-20 13:25	52.78	OK	14572	2026-09-20 13:26	53.54	OK
14573	2026-09-20 13:27	52.33	OK	14574	2026-09-20 13:28	53.07	OK
14575	2026-09-20 13:29	53.43	OK	14576	2026-09-20 13:30	51.26	OK
14577	2026-09-20 13:31	55.81	OK	14578	2026-09-20 13:32	52.78	OK
14579	2026-09-20 13:33	54.38	OK	14580	2026-09-20 13:34	53.77	OK
14581	2026-09-20 13:35	52.36	OK	14582	2026-09-20 13:36	52.54	OK
14583	2026-09-20 13:37	53.02	OK	14584	2026-09-20 13:38	52.64	OK
14585	2026-09-20 13:39	53.75	OK	14586	2026-09-20 13:40	53.31	OK
14587	2026-09-20 13:41	52.30	OK	14588	2026-09-20 13:42	54.44	OK
14589	2026-09-20 13:43	53.39	OK	14590	2026-09-20 13:44	53.79	OK
14591	2026-09-20 13:45	52.17	OK	14592	2026-09-20 13:46	55.75	OK
14593	2026-09-20 13:47	53.19	OK	14594	2026-09-20 13:48	52.40	OK
14595	2026-09-20 13:49	53.47	OK	14596	2026-09-20 13:50	51.39	OK
14597	2026-09-20 13:51	53.35	OK	14598	2026-09-20 13:52	52.68	OK
14599	2026-09-20 13:53	54.55	OK	14600	2026-09-20 13:54	52.42	OK
14601	2026-09-20 13:55	51.95	OK	14602	2026-09-20 13:56	52.22	OK
14603	2026-09-20 13:57	53.32	OK	14604	2026-09-20 13:58	53.51	OK
14605	2026-09-20 13:59	52.25	OK	14606	2026-09-20 14:00	53.07	OK
14607	2026-09-20 14:01	51.08	OK	14608	2026-09-20 14:02	51.41	OK
14609	2026-09-20 14:03	53.67	OK	14610	2026-09-20 14:04	52.83	OK
14611	2026-09-20 14:05	55.26	OK	14612	2026-09-20 14:06	53.12	OK
14613	2026-09-20 14:07	51.57	OK	14614	2026-09-20 14:08	52.24	OK
14615	2026-09-20 14:09	53.11	OK	14616	2026-09-20 14:10	52.31	OK
14617	2026-09-20 14:11	53.65	OK	14618	2026-09-20 14:12	54.73	OK
14619	2026-09-20 14:13	51.86	OK	14620	2026-09-20 14:14	53.94	OK
14621	2026-09-20 14:15	53.64	OK	14622	2026-09-20 14:16	54.62	OK
1462	2026-09-20 14:17	54.25	OK	1462	2026-09-20 14:18	51.89	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
14625	2026-09-20 14:19	51.06	OK	14626	2026-09-20 14:20	53.51	OK
14627	2026-09-20 14:21	52.45	OK	14628	2026-09-20 14:22	51.82	OK
14629	2026-09-20 14:23	52.31	OK	14630	2026-09-20 14:24	54.21	OK
14631	2026-09-20 14:25	51.44	OK	14632	2026-09-20 14:26	54.23	OK
14633	2026-09-20 14:27	52.13	OK	14634	2026-09-20 14:28	51.89	OK
14635	2026-09-20 14:29	53.37	OK	14636	2026-09-20 14:30	50.97	OK
14637	2026-09-20 14:31	52.65	OK	14638	2026-09-20 14:32	53.59	OK
14639	2026-09-20 14:33	53.20	OK	14640	2026-09-20 14:34	53.96	OK
14641	2026-09-20 14:35	53.99	OK	14642	2026-09-20 14:36	51.79	OK
14643	2026-09-20 14:37	53.35	OK	14644	2026-09-20 14:38	54.82	OK
14645	2026-09-20 14:39	53.54	OK	14646	2026-09-20 14:40	52.40	OK
14647	2026-09-20 14:41	51.63	OK	14648	2026-09-20 14:42	53.58	OK
14649	2026-09-20 14:43	54.09	OK	14650	2026-09-20 14:44	52.87	OK
14651	2026-09-20 14:45	53.29	OK	14652	2026-09-20 14:46	53.03	OK
14653	2026-09-20 14:47	53.57	OK	14654	2026-09-20 14:48	50.53	OK
14655	2026-09-20 14:49	54.90	OK	14656	2026-09-20 14:50	51.08	OK
14657	2026-09-20 14:51	50.64	OK	14658	2026-09-20 14:52	53.71	OK
14659	2026-09-20 14:53	52.80	OK	14660	2026-09-20 14:54	51.35	OK
14661	2026-09-20 14:55	53.52	OK	14662	2026-09-20 14:56	54.74	OK
14663	2026-09-20 14:57	51.72	OK	14664	2026-09-20 14:58	52.24	OK
14665	2026-09-20 14:59	51.86	OK	14666	2026-09-20 15:00	50.57	OK
14667	2026-09-20 15:01	51.28	OK	14668	2026-09-20 15:02	51.00	OK
14669	2026-09-20 15:03	52.89	OK	14670	2026-09-20 15:04	52.16	OK
14671	2026-09-20 15:05	53.76	OK	14672	2026-09-20 15:06	51.12	OK
14673	2026-09-20 15:07	51.67	OK	14674	2026-09-20 15:08	51.96	OK
14675	2026-09-20 15:09	51.68	OK	14676	2026-09-20 15:10	52.08	OK
14677	2026-09-20 15:11	53.30	OK	14678	2026-09-20 15:12	53.63	OK
14679	2026-09-20 15:13	52.04	OK	14680	2026-09-20 15:14	49.56	OK
14681	2026-09-20 15:15	53.24	OK	14682	2026-09-20 15:16	50.92	OK
1468	2026-09-20 15:17	53.60	OK	1468	2026-09-20 15:18	52.85	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
14685	2026-09-20 15:19	52.77	OK	14686	2026-09-20 15:20	51.39	OK
14687	2026-09-20 15:21	52.13	OK	14688	2026-09-20 15:22	52.24	OK
14689	2026-09-20 15:23	50.32	OK	14690	2026-09-20 15:24	50.47	OK
14691	2026-09-20 15:25	49.62	OK	14692	2026-09-20 15:26	50.92	OK
14693	2026-09-20 15:27	52.67	OK	14694	2026-09-20 15:28	51.92	OK
14695	2026-09-20 15:29	51.40	OK	14696	2026-09-20 15:30	51.76	OK
14697	2026-09-20 15:31	51.12	OK	14698	2026-09-20 15:32	53.34	OK
14699	2026-09-20 15:33	52.15	OK	14700	2026-09-20 15:34	51.71	OK
14701	2026-09-20 15:35	50.81	OK	14702	2026-09-20 15:36	52.34	OK
14703	2026-09-20 15:37	53.45	OK	14704	2026-09-20 15:38	50.35	OK
14705	2026-09-20 15:39	50.96	OK	14706	2026-09-20 15:40	51.92	OK
14707	2026-09-20 15:41	50.95	OK	14708	2026-09-20 15:42	51.57	OK
14709	2026-09-20 15:43	50.93	OK	14710	2026-09-20 15:44	50.83	OK
14711	2026-09-20 15:45	51.31	OK	14712	2026-09-20 15:46	50.95	OK
14713	2026-09-20 15:47	52.63	OK	14714	2026-09-20 15:48	51.44	OK
14715	2026-09-20 15:49	53.86	OK	14716	2026-09-20 15:50	51.81	OK
14717	2026-09-20 15:51	51.52	OK	14718	2026-09-20 15:52	51.07	OK
14719	2026-09-20 15:53	49.65	OK	14720	2026-09-20 15:54	51.63	OK
14721	2026-09-20 15:55	50.90	OK	14722	2026-09-20 15:56	51.94	OK
14723	2026-09-20 15:57	50.41	OK	14724	2026-09-20 15:58	51.13	OK
14725	2026-09-20 15:59	51.51	OK	14726	2026-09-20 16:00	51.69	OK
14727	2026-09-20 16:01	50.06	OK	14728	2026-09-20 16:02	51.75	OK
14729	2026-09-20 16:03	50.81	OK	14730	2026-09-20 16:04	51.71	OK
14731	2026-09-20 16:05	50.96	OK	14732	2026-09-20 16:06	50.21	OK
14733	2026-09-20 16:07	53.51	OK	14734	2026-09-20 16:08	50.97	OK
14735	2026-09-20 16:09	49.28	OK	14736	2026-09-20 16:10	51.89	OK
14737	2026-09-20 16:11	49.07	OK	14738	2026-09-20 16:12	50.93	OK
14739	2026-09-20 16:13	49.97	OK	14740	2026-09-20 16:14	50.03	OK
14741	2026-09-20 16:15	50.07	OK	14742	2026-09-20 16:16	51.01	OK
1474	2026-09-20 16:17	48.61	OK	1474	2026-09-20 16:18	50.50	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
14745	2026-09-20 16:19	50.37	OK	14746	2026-09-20 16:20	51.83	OK
14747	2026-09-20 16:21	51.01	OK	14748	2026-09-20 16:22	52.29	OK
14749	2026-09-20 16:23	53.02	OK	14750	2026-09-20 16:24	50.49	OK
14751	2026-09-20 16:25	50.57	OK	14752	2026-09-20 16:26	50.86	OK
14753	2026-09-20 16:27	51.18	OK	14754	2026-09-20 16:28	49.53	OK
14755	2026-09-20 16:29	51.92	OK	14756	2026-09-20 16:30	49.96	OK
14757	2026-09-20 16:31	52.41	OK	14758	2026-09-20 16:32	51.36	OK
14759	2026-09-20 16:33	49.21	OK	14760	2026-09-20 16:34	50.51	OK
14761	2026-09-20 16:35	49.06	OK	14762	2026-09-20 16:36	50.81	OK
14763	2026-09-20 16:37	49.45	OK	14764	2026-09-20 16:38	51.12	OK
14765	2026-09-20 16:39	50.35	OK	14766	2026-09-20 16:40	50.47	OK
14767	2026-09-20 16:41	49.95	OK	14768	2026-09-20 16:42	51.13	OK
14769	2026-09-20 16:43	49.82	OK	14770	2026-09-20 16:44	51.95	OK
14771	2026-09-20 16:45	49.81	OK	14772	2026-09-20 16:46	48.57	OK
14773	2026-09-20 16:47	50.33	OK	14774	2026-09-20 16:48	50.06	OK
14775	2026-09-20 16:49	48.08	OK	14776	2026-09-20 16:50	49.44	OK
14777	2026-09-20 16:51	49.47	OK	14778	2026-09-20 16:52	49.84	OK
14779	2026-09-20 16:53	51.09	OK	14780	2026-09-20 16:54	52.38	OK
14781	2026-09-20 16:55	50.92	OK	14782	2026-09-20 16:56	48.41	OK
14783	2026-09-20 16:57	50.02	OK	14784	2026-09-20 16:58	50.65	OK
14785	2026-09-20 16:59	50.31	OK	14786	2026-09-20 17:00	49.87	OK
14787	2026-09-20 17:01	49.48	OK	14788	2026-09-20 17:02	50.05	OK
14789	2026-09-20 17:03	50.99	OK	14790	2026-09-20 17:04	48.86	OK
14791	2026-09-20 17:05	51.95	OK	14792	2026-09-20 17:06	48.09	OK
14793	2026-09-20 17:07	51.64	OK	14794	2026-09-20 17:08	49.35	OK
14795	2026-09-20 17:09	48.92	OK	14796	2026-09-20 17:10	50.10	OK
14797	2026-09-20 17:11	49.87	OK	14798	2026-09-20 17:12	49.92	OK
14799	2026-09-20 17:13	48.45	OK	14800	2026-09-20 17:14	49.85	OK
14801	2026-09-20 17:15	48.24	OK	14802	2026-09-20 17:16	48.45	OK
1480	2026-09-20 17:17	50.57	OK	1480	2026-09-20 17:18	49.19	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
14805	2026-09-20 17:19	50.49	OK	14806	2026-09-20 17:20	50.53	OK
14807	2026-09-20 17:21	50.83	OK	14808	2026-09-20 17:22	49.02	OK
14809	2026-09-20 17:23	50.35	OK	14810	2026-09-20 17:24	49.19	OK
14811	2026-09-20 17:25	48.16	OK	14812	2026-09-20 17:26	48.61	OK
14813	2026-09-20 17:27	50.21	OK	14814	2026-09-20 17:28	50.79	OK
14815	2026-09-20 17:29	47.56	OK	14816	2026-09-20 17:30	49.27	OK
14817	2026-09-20 17:31	49.55	OK	14818	2026-09-20 17:32	49.19	OK
14819	2026-09-20 17:33	49.69	OK	14820	2026-09-20 17:34	49.67	OK
14821	2026-09-20 17:35	47.99	OK	14822	2026-09-20 17:36	47.55	OK
14823	2026-09-20 17:37	49.08	OK	14824	2026-09-20 17:38	50.43	OK
14825	2026-09-20 17:39	49.82	OK	14826	2026-09-20 17:40	51.00	OK
14827	2026-09-20 17:41	50.19	OK	14828	2026-09-20 17:42	48.98	OK
14829	2026-09-20 17:43	47.37	OK	14830	2026-09-20 17:44	47.93	OK
14831	2026-09-20 17:45	49.05	OK	14832	2026-09-20 17:46	49.45	OK
14833	2026-09-20 17:47	50.81	OK	14834	2026-09-20 17:48	48.84	OK
14835	2026-09-20 17:49	48.00	OK	14836	2026-09-20 17:50	50.39	OK
14837	2026-09-20 17:51	49.19	OK	14838	2026-09-20 17:52	49.02	OK
14839	2026-09-20 17:53	48.08	OK	14840	2026-09-20 17:54	48.97	OK
14841	2026-09-20 17:55	48.94	OK	14842	2026-09-20 17:56	49.48	OK
14843	2026-09-20 17:57	49.10	OK	14844	2026-09-20 17:58	50.31	OK
14845	2026-09-20 17:59	49.67	OK	14846	2026-09-20 18:00	49.90	OK
14847	2026-09-20 18:01	47.03	OK	14848	2026-09-20 18:02	47.90	OK
14849	2026-09-20 18:03	46.96	OK	14850	2026-09-20 18:04	50.29	OK
14851	2026-09-20 18:05	48.81	OK	14852	2026-09-20 18:06	49.02	OK
14853	2026-09-20 18:07	49.03	OK	14854	2026-09-20 18:08	48.54	OK
14855	2026-09-20 18:09	48.45	OK	14856	2026-09-20 18:10	49.07	OK
14857	2026-09-20 18:11	48.16	OK	14858	2026-09-20 18:12	48.98	OK
14859	2026-09-20 18:13	47.78	OK	14860	2026-09-20 18:14	48.62	OK
14861	2026-09-20 18:15	48.31	OK	14862	2026-09-20 18:16	48.13	OK
1486	2026-09-20 18:17	47.79	OK	1486	2026-09-20 18:18	46.89	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
14865	2026-09-20 18:19	49.32	OK	14866	2026-09-20 18:20	48.74	OK
14867	2026-09-20 18:21	48.72	OK	14868	2026-09-20 18:22	46.86	OK
14869	2026-09-20 18:23	48.57	OK	14870	2026-09-20 18:24	48.02	OK
14871	2026-09-20 18:25	49.69	OK	14872	2026-09-20 18:26	46.53	OK
14873	2026-09-20 18:27	48.77	OK	14874	2026-09-20 18:28	48.51	OK
14875	2026-09-20 18:29	49.12	OK	14876	2026-09-20 18:30	48.18	OK
14877	2026-09-20 18:31	49.77	OK	14878	2026-09-20 18:32	49.59	OK
14879	2026-09-20 18:33	47.47	OK	14880	2026-09-20 18:34	47.43	OK
14881	2026-09-20 18:35	48.25	OK	14882	2026-09-20 18:36	49.72	OK
14883	2026-09-20 18:37	47.74	OK	14884	2026-09-20 18:38	47.57	OK
14885	2026-09-20 18:39	48.58	OK	14886	2026-09-20 18:40	47.03	OK
14887	2026-09-20 18:41	49.21	OK	14888	2026-09-20 18:42	47.67	OK
14889	2026-09-20 18:43	48.52	OK	14890	2026-09-20 18:44	47.15	OK
14891	2026-09-20 18:45	45.61	OK	14892	2026-09-20 18:46	48.95	OK
14893	2026-09-20 18:47	47.76	OK	14894	2026-09-20 18:48	48.69	OK
14895	2026-09-20 18:49	49.18	OK	14896	2026-09-20 18:50	46.18	OK
14897	2026-09-20 18:51	50.36	OK	14898	2026-09-20 18:52	47.47	OK
14899	2026-09-20 18:53	48.10	OK	14900	2026-09-20 18:54	46.41	OK
14901	2026-09-20 18:55	48.26	OK	14902	2026-09-20 18:56	46.68	OK
14903	2026-09-20 18:57	46.81	OK	14904	2026-09-20 18:58	46.68	OK
14905	2026-09-20 18:59	46.57	OK	14906	2026-09-20 19:00	46.70	OK
14907	2026-09-20 19:01	46.41	OK	14908	2026-09-20 19:02	47.72	OK
14909	2026-09-20 19:03	46.57	OK	14910	2026-09-20 19:04	48.44	OK
14911	2026-09-20 19:05	48.07	OK	14912	2026-09-20 19:06	47.31	OK
14913	2026-09-20 19:07	46.33	OK	14914	2026-09-20 19:08	48.16	OK
14915	2026-09-20 19:09	45.73	OK	14916	2026-09-20 19:10	47.41	OK
14917	2026-09-20 19:11	44.84	OK	14918	2026-09-20 19:12	45.65	OK
14919	2026-09-20 19:13	48.05	OK	14920	2026-09-20 19:14	46.41	OK
14921	2026-09-20 19:15	45.81	OK	14922	2026-09-20 19:16	48.35	OK
1492	2026-09-20 19:17	46.38	OK	1492	2026-09-20 19:18	46.11	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
14925	2026-09-20 19:19	46.01	OK	14926	2026-09-20 19:20	47.85	OK
14927	2026-09-20 19:21	47.58	OK	14928	2026-09-20 19:22	48.19	OK
14929	2026-09-20 19:23	46.86	OK	14930	2026-09-20 19:24	46.81	OK
14931	2026-09-20 19:25	47.97	OK	14932	2026-09-20 19:26	46.75	OK
14933	2026-09-20 19:27	46.28	OK	14934	2026-09-20 19:28	49.04	OK
14935	2026-09-20 19:29	46.46	OK	14936	2026-09-20 19:30	46.33	OK
14937	2026-09-20 19:31	44.63	OK	14938	2026-09-20 19:32	47.85	OK
14939	2026-09-20 19:33	46.31	OK	14940	2026-09-20 19:34	46.72	OK
14941	2026-09-20 19:35	47.21	OK	14942	2026-09-20 19:36	48.03	OK
14943	2026-09-20 19:37	45.84	OK	14944	2026-09-20 19:38	45.45	OK
14945	2026-09-20 19:39	46.01	OK	14946	2026-09-20 19:40	47.96	OK
14947	2026-09-20 19:41	47.01	OK	14948	2026-09-20 19:42	49.30	OK
14949	2026-09-20 19:43	47.64	OK	14950	2026-09-20 19:44	48.00	OK
14951	2026-09-20 19:45	48.92	OK	14952	2026-09-20 19:46	45.52	OK
14953	2026-09-20 19:47	47.32	OK	14954	2026-09-20 19:48	45.95	OK
14955	2026-09-20 19:49	46.53	OK	14956	2026-09-20 19:50	45.53	OK
14957	2026-09-20 19:51	44.52	OK	14958	2026-09-20 19:52	44.92	OK
14959	2026-09-20 19:53	47.74	OK	14960	2026-09-20 19:54	46.64	OK
14961	2026-09-20 19:55	48.91	OK	14962	2026-09-20 19:56	44.78	OK
14963	2026-09-20 19:57	45.29	OK	14964	2026-09-20 19:58	46.15	OK
14965	2026-09-20 19:59	48.19	OK	14966	2026-09-20 20:00	46.71	OK
14967	2026-09-20 20:01	45.60	OK	14968	2026-09-20 20:02	45.30	OK
14969	2026-09-20 20:03	46.81	OK	14970	2026-09-20 20:04	46.12	OK
14971	2026-09-20 20:05	46.32	OK	14972	2026-09-20 20:06	45.44	OK
14973	2026-09-20 20:07	44.49	OK	14974	2026-09-20 20:08	48.90	OK
14975	2026-09-20 20:09	46.99	OK	14976	2026-09-20 20:10	46.76	OK
14977	2026-09-20 20:11	48.41	OK	14978	2026-09-20 20:12	46.46	OK
14979	2026-09-20 20:13	47.37	OK	14980	2026-09-20 20:14	46.57	OK
14981	2026-09-20 20:15	46.41	OK	14982	2026-09-20 20:16	45.68	OK
1498	2026-09-20 20:17	44.95	OK	1498	2026-09-20 20:18	46.25	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
14985	2026-09-20 20:19	45.44	OK	14986	2026-09-20 20:20	46.66	OK
14987	2026-09-20 20:21	44.31	OK	14988	2026-09-20 20:22	45.15	OK
14989	2026-09-20 20:23	46.00	OK	14990	2026-09-20 20:24	44.34	OK
14991	2026-09-20 20:25	45.87	OK	14992	2026-09-20 20:26	48.14	OK
14993	2026-09-20 20:27	45.32	OK	14994	2026-09-20 20:28	47.45	OK
14995	2026-09-20 20:29	44.62	OK	14996	2026-09-20 20:30	45.18	OK
14997	2026-09-20 20:31	46.03	OK	14998	2026-09-20 20:32	46.57	OK
14999	2026-09-20 20:33	45.83	OK	15000	2026-09-20 20:34	45.38	OK
15001	2026-09-20 20:35	46.26	OK	15002	2026-09-20 20:36	46.78	OK
15003	2026-09-20 20:37	45.68	OK	15004	2026-09-20 20:38	44.95	OK
15005	2026-09-20 20:39	44.45	OK	15006	2026-09-20 20:40	43.81	OK
15007	2026-09-20 20:41	46.58	OK	15008	2026-09-20 20:42	44.91	OK
15009	2026-09-20 20:43	46.49	OK	15010	2026-09-20 20:44	45.61	OK
15011	2026-09-20 20:45	45.68	OK	15012	2026-09-20 20:46	44.19	OK
15013	2026-09-20 20:47	46.17	OK	15014	2026-09-20 20:48	46.41	OK
15015	2026-09-20 20:49	46.29	OK	15016	2026-09-20 20:50	46.96	OK
15017	2026-09-20 20:51	44.83	OK	15018	2026-09-20 20:52	46.76	OK
15019	2026-09-20 20:53	46.48	OK	15020	2026-09-20 20:54	46.67	OK
15021	2026-09-20 20:55	44.38	OK	15022	2026-09-20 20:56	45.17	OK
15023	2026-09-20 20:57	46.68	OK	15024	2026-09-20 20:58	46.56	OK
15025	2026-09-20 20:59	44.58	OK	15026	2026-09-20 21:00	46.77	OK
15027	2026-09-20 21:01	45.90	OK	15028	2026-09-20 21:02	45.35	OK
15029	2026-09-20 21:03	45.37	OK	15030	2026-09-20 21:04	45.99	OK
15031	2026-09-20 21:05	43.55	OK	15032	2026-09-20 21:06	46.60	OK
15033	2026-09-20 21:07	46.55	OK	15034	2026-09-20 21:08	45.14	OK
15035	2026-09-20 21:09	45.14	OK	15036	2026-09-20 21:10	44.42	OK
15037	2026-09-20 21:11	46.70	OK	15038	2026-09-20 21:12	46.99	OK
15039	2026-09-20 21:13	44.97	OK	15040	2026-09-20 21:14	44.80	OK
15041	2026-09-20 21:15	46.61	OK	15042	2026-09-20 21:16	45.84	OK
1504	2026-09-20 21:17	43.56	OK	1504	2026-09-20 21:18	44.95	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
15045	2026-09-20 21:19	47.51	OK	15046	2026-09-20 21:20	47.30	OK
15047	2026-09-20 21:21	44.98	OK	15048	2026-09-20 21:22	44.25	OK
15049	2026-09-20 21:23	45.52	OK	15050	2026-09-20 21:24	45.25	OK
15051	2026-09-20 21:25	43.82	OK	15052	2026-09-20 21:26	45.69	OK
15053	2026-09-20 21:27	44.51	OK	15054	2026-09-20 21:28	43.64	OK
15055	2026-09-20 21:29	45.93	OK	15056	2026-09-20 21:30	45.90	OK
15057	2026-09-20 21:31	44.60	OK	15058	2026-09-20 21:32	44.69	OK
15059	2026-09-20 21:33	44.55	OK	15060	2026-09-20 21:34	43.74	OK
15061	2026-09-20 21:35	43.51	OK	15062	2026-09-20 21:36	44.06	OK
15063	2026-09-20 21:37	45.03	OK	15064	2026-09-20 21:38	45.14	OK
15065	2026-09-20 21:39	43.83	OK	15066	2026-09-20 21:40	42.81	OK
15067	2026-09-20 21:41	45.61	OK	15068	2026-09-20 21:42	45.78	OK
15069	2026-09-20 21:43	43.97	OK	15070	2026-09-20 21:44	46.48	OK
15071	2026-09-20 21:45	44.62	OK	15072	2026-09-20 21:46	45.54	OK
15073	2026-09-20 21:47	45.28	OK	15074	2026-09-20 21:48	44.97	OK
15075	2026-09-20 21:49	44.48	OK	15076	2026-09-20 21:50	45.83	OK
15077	2026-09-20 21:51	45.91	OK	15078	2026-09-20 21:52	46.86	OK
15079	2026-09-20 21:53	45.17	OK	15080	2026-09-20 21:54	42.93	OK
15081	2026-09-20 21:55	47.29	OK	15082	2026-09-20 21:56	46.33	OK
15083	2026-09-20 21:57	44.11	OK	15084	2026-09-20 21:58	44.20	OK
15085	2026-09-20 21:59	45.67	OK	15086	2026-09-20 22:00	44.28	OK
15087	2026-09-20 22:01	43.34	OK	15088	2026-09-20 22:02	45.33	OK
15089	2026-09-20 22:03	43.63	OK	15090	2026-09-20 22:04	44.33	OK
15091	2026-09-20 22:05	46.28	OK	15092	2026-09-20 22:06	43.96	OK
15093	2026-09-20 22:07	43.29	OK	15094	2026-09-20 22:08	45.00	OK
15095	2026-09-20 22:09	44.89	OK	15096	2026-09-20 22:10	45.32	OK
15097	2026-09-20 22:11	46.85	OK	15098	2026-09-20 22:12	47.66	OK
15099	2026-09-20 22:13	44.68	OK	15100	2026-09-20 22:14	45.16	OK
15101	2026-09-20 22:15	45.85	OK	15102	2026-09-20 22:16	43.89	OK
1510	2026-09-20 22:17	43.93	OK	1510	2026-09-20 22:18	44.13	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
15105	2026-09-20 22:19	45.23	OK	15106	2026-09-20 22:20	44.70	OK
15107	2026-09-20 22:21	44.64	OK	15108	2026-09-20 22:22	45.07	OK
15109	2026-09-20 22:23	44.80	OK	15110	2026-09-20 22:24	42.57	OK
15111	2026-09-20 22:25	45.42	OK	15112	2026-09-20 22:26	46.06	OK
15113	2026-09-20 22:27	43.46	OK	15114	2026-09-20 22:28	45.25	OK
15115	2026-09-20 22:29	45.99	OK	15116	2026-09-20 22:30	44.53	OK
15117	2026-09-20 22:31	44.29	OK	15118	2026-09-20 22:32	44.20	OK
15119	2026-09-20 22:33	46.28	OK	15120	2026-09-20 22:34	44.50	OK
15121	2026-09-20 22:35	44.71	OK	15122	2026-09-20 22:36	43.04	OK
15123	2026-09-20 22:37	44.56	OK	15124	2026-09-20 22:38	46.13	OK
15125	2026-09-20 22:39	43.40	OK	15126	2026-09-20 22:40	42.91	OK
15127	2026-09-20 22:41	44.10	OK	15128	2026-09-20 22:42	46.01	OK
15129	2026-09-20 22:43	42.81	OK	15130	2026-09-20 22:44	47.00	OK
15131	2026-09-20 22:45	44.73	OK	15132	2026-09-20 22:46	44.48	OK
15133	2026-09-20 22:47	42.95	OK	15134	2026-09-20 22:48	46.35	OK
15135	2026-09-20 22:49	44.72	OK	15136	2026-09-20 22:50	46.77	OK
15137	2026-09-20 22:51	45.03	OK	15138	2026-09-20 22:52	45.01	OK
15139	2026-09-20 22:53	43.54	OK	15140	2026-09-20 22:54	44.84	OK
15141	2026-09-20 22:55	42.94	OK	15142	2026-09-20 22:56	43.02	OK
15143	2026-09-20 22:57	44.89	OK	15144	2026-09-20 22:58	46.36	OK
15145	2026-09-20 22:59	44.90	OK	15146	2026-09-20 23:00	46.57	OK
15147	2026-09-20 23:01	44.76	OK	15148	2026-09-20 23:02	45.40	OK
15149	2026-09-20 23:03	44.59	OK	15150	2026-09-20 23:04	44.86	OK
15151	2026-09-20 23:05	44.68	OK	15152	2026-09-20 23:06	44.52	OK
15153	2026-09-20 23:07	45.03	OK	15154	2026-09-20 23:08	44.60	OK
15155	2026-09-20 23:09	45.91	OK	15156	2026-09-20 23:10	45.79	OK
15157	2026-09-20 23:11	44.79	OK	15158	2026-09-20 23:12	42.82	OK
15159	2026-09-20 23:13	45.96	OK	15160	2026-09-20 23:14	45.07	OK
15161	2026-09-20 23:15	44.18	OK	15162	2026-09-20 23:16	44.78	OK
1516	2026-09-20 23:17	45.94	OK	1516	2026-09-20 23:18	45.20	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
15165	2026-09-20 23:19	42.77	OK	15166	2026-09-20 23:20	44.38	OK
15167	2026-09-20 23:21	44.42	OK	15168	2026-09-20 23:22	45.56	OK
15169	2026-09-20 23:23	44.75	OK	15170	2026-09-20 23:24	44.62	OK
15171	2026-09-20 23:25	44.21	OK	15172	2026-09-20 23:26	44.49	OK
15173	2026-09-20 23:27	44.85	OK	15174	2026-09-20 23:28	43.11	OK
15175	2026-09-20 23:29	43.39	OK	15176	2026-09-20 23:30	45.28	OK
15177	2026-09-20 23:31	45.10	OK	15178	2026-09-20 23:32	45.46	OK
15179	2026-09-20 23:33	45.72	OK	15180	2026-09-20 23:34	45.44	OK
15181	2026-09-20 23:35	44.53	OK	15182	2026-09-20 23:36	45.43	OK
15183	2026-09-20 23:37	44.61	OK	15184	2026-09-20 23:38	43.79	OK
15185	2026-09-20 23:39	44.86	OK	15186	2026-09-20 23:40	45.20	OK
15187	2026-09-20 23:41	44.55	OK	15188	2026-09-20 23:42	43.69	OK
15189	2026-09-20 23:43	44.98	OK	15190	2026-09-20 23:44	43.97	OK
15191	2026-09-20 23:45	45.68	OK	15192	2026-09-20 23:46	44.54	OK
15193	2026-09-20 23:47	43.84	OK	15194	2026-09-20 23:48	44.68	OK
15195	2026-09-20 23:49	44.40	OK	15196	2026-09-20 23:50	45.10	OK
15197	2026-09-20 23:51	43.77	OK	15198	2026-09-20 23:52	43.40	OK
15199	2026-09-20 23:53	45.23	OK	15200	2026-09-20 23:54	45.19	OK
15201	2026-09-20 23:55	44.07	OK	15202	2026-09-20 23:56	44.05	OK
15203	2026-09-20 23:57	43.93	OK	15204	2026-09-20 23:58	42.91	OK
15205	2026-09-20 23:59	44.21	OK	15206	2026-09-21 00:00	43.23	OK
15207	2026-09-21 00:01	42.85	OK	15208	2026-09-21 00:02	44.91	OK
15209	2026-09-21 00:03	45.26	OK	15210	2026-09-21 00:04	44.63	OK
15211	2026-09-21 00:05	43.29	OK	15212	2026-09-21 00:06	46.79	OK
15213	2026-09-21 00:07	44.74	OK	15214	2026-09-21 00:08	44.90	OK
15215	2026-09-21 00:09	44.27	OK	15216	2026-09-21 00:10	45.02	OK
15217	2026-09-21 00:11	43.40	OK	15218	2026-09-21 00:12	45.92	OK
15219	2026-09-21 00:13	44.56	OK	15220	2026-09-21 00:14	43.19	OK
15221	2026-09-21 00:15	43.69	OK	15222	2026-09-21 00:16	44.74	OK
1522	2026-09-21 00:17	43.93	OK	1522	2026-09-21 00:18	43.81	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
15225	2026-09-21 00:19	44.49	OK	15226	2026-09-21 00:20	44.02	OK
15227	2026-09-21 00:21	44.71	OK	15228	2026-09-21 00:22	44.25	OK
15229	2026-09-21 00:23	44.52	OK	15230	2026-09-21 00:24	45.69	OK
15231	2026-09-21 00:25	44.89	OK	15232	2026-09-21 00:26	42.89	OK
15233	2026-09-21 00:27	45.02	OK	15234	2026-09-21 00:28	45.44	OK
15235	2026-09-21 00:29	45.41	OK	15236	2026-09-21 00:30	45.26	OK
15237	2026-09-21 00:31	43.79	OK	15238	2026-09-21 00:32	44.29	OK
15239	2026-09-21 00:33	43.07	OK	15240	2026-09-21 00:34	44.44	OK
15241	2026-09-21 00:35	44.45	OK	15242	2026-09-21 00:36	44.78	OK
15243	2026-09-21 00:37	44.95	OK	15244	2026-09-21 00:38	43.25	OK
15245	2026-09-21 00:39	44.58	OK	15246	2026-09-21 00:40	45.29	OK
15247	2026-09-21 00:41	43.41	OK	15248	2026-09-21 00:42	44.07	OK
15249	2026-09-21 00:43	45.34	OK	15250	2026-09-21 00:44	44.25	OK
15251	2026-09-21 00:45	45.87	OK	15252	2026-09-21 00:46	45.15	OK
15253	2026-09-21 00:47	43.67	OK	15254	2026-09-21 00:48	45.22	OK
15255	2026-09-21 00:49	46.03	OK	15256	2026-09-21 00:50	45.47	OK
15257	2026-09-21 00:51	44.30	OK	15258	2026-09-21 00:52	44.48	OK
15259	2026-09-21 00:53	45.39	OK	15260	2026-09-21 00:54	44.26	OK
15261	2026-09-21 00:55	43.28	OK	15262	2026-09-21 00:56	45.65	OK
15263	2026-09-21 00:57	44.21	OK	15264	2026-09-21 00:58	44.72	OK
15265	2026-09-21 00:59	44.08	OK	15266	2026-09-21 01:00	44.32	OK
15267	2026-09-21 01:01	44.80	OK	15268	2026-09-21 01:02	46.05	OK
15269	2026-09-21 01:03	44.95	OK	15270	2026-09-21 01:04	42.90	OK
15271	2026-09-21 01:05	46.86	OK	15272	2026-09-21 01:06	43.85	OK
15273	2026-09-21 01:07	45.31	OK	15274	2026-09-21 01:08	43.89	OK
15275	2026-09-21 01:09	45.49	OK	15276	2026-09-21 01:10	44.41	OK
15277	2026-09-21 01:11	45.78	OK	15278	2026-09-21 01:12	45.57	OK
15279	2026-09-21 01:13	43.92	OK	15280	2026-09-21 01:14	46.32	OK
15281	2026-09-21 01:15	45.81	OK	15282	2026-09-21 01:16	45.60	OK
1528	2026-09-21 01:17	44.90	OK	1528	2026-09-21 01:18	43.84	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
15285	2026-09-21 01:19	47.11	OK	15286	2026-09-21 01:20	43.88	OK
15287	2026-09-21 01:21	44.10	OK	15288	2026-09-21 01:22	46.60	OK
15289	2026-09-21 01:23	44.34	OK	15290	2026-09-21 01:24	46.88	OK
15291	2026-09-21 01:25	44.43	OK	15292	2026-09-21 01:26	43.79	OK
15293	2026-09-21 01:27	47.50	OK	15294	2026-09-21 01:28	45.88	OK
15295	2026-09-21 01:29	45.13	OK	15296	2026-09-21 01:30	44.41	OK
15297	2026-09-21 01:31	45.61	OK	15298	2026-09-21 01:32	45.64	OK
15299	2026-09-21 01:33	46.05	OK	15300	2026-09-21 01:34	45.32	OK
15301	2026-09-21 01:35	44.55	OK	15302	2026-09-21 01:36	44.76	OK
15303	2026-09-21 01:37	46.31	OK	15304	2026-09-21 01:38	45.38	OK
15305	2026-09-21 01:39	43.91	OK	15306	2026-09-21 01:40	46.17	OK
15307	2026-09-21 01:41	44.13	OK	15308	2026-09-21 01:42	46.58	OK
15309	2026-09-21 01:43	44.42	OK	15310	2026-09-21 01:44	46.32	OK
15311	2026-09-21 01:45	46.37	OK	15312	2026-09-21 01:46	45.73	OK
15313	2026-09-21 01:47	46.81	OK	15314	2026-09-21 01:48	47.10	OK
15315	2026-09-21 01:49	48.30	OK	15316	2026-09-21 01:50	45.75	OK
15317	2026-09-21 01:51	45.93	OK	15318	2026-09-21 01:52	47.35	OK
15319	2026-09-21 01:53	44.57	OK	15320	2026-09-21 01:54	45.85	OK
15321	2026-09-21 01:55	45.86	OK	15322	2026-09-21 01:56	46.39	OK
15323	2026-09-21 01:57	44.93	OK	15324	2026-09-21 01:58	46.41	OK
15325	2026-09-21 01:59	45.12	OK	15326	2026-09-21 02:00	45.93	OK
15327	2026-09-21 02:01	46.57	OK	15328	2026-09-21 02:02	44.46	OK
15329	2026-09-21 02:03	47.00	OK	15330	2026-09-21 02:04	47.03	OK
15331	2026-09-21 02:05	44.76	OK	15332	2026-09-21 02:06	46.13	OK
15333	2026-09-21 02:07	44.68	OK	15334	2026-09-21 02:08	43.81	OK
15335	2026-09-21 02:09	46.02	OK	15336	2026-09-21 02:10	45.53	OK
15337	2026-09-21 02:11	44.64	OK	15338	2026-09-21 02:12	47.32	OK
15339	2026-09-21 02:13	45.16	OK	15340	2026-09-21 02:14	45.03	OK
15341	2026-09-21 02:15	45.70	OK	15342	2026-09-21 02:16	45.03	OK
1534	2026-09-21 02:17	47.09	OK	1534	2026-09-21 02:18	43.76	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
15345	2026-09-21 02:19	44.95	OK	15346	2026-09-21 02:20	47.32	OK
15347	2026-09-21 02:21	46.80	OK	15348	2026-09-21 02:22	45.90	OK
15349	2026-09-21 02:23	47.92	OK	15350	2026-09-21 02:24	45.71	OK
15351	2026-09-21 02:25	45.91	OK	15352	2026-09-21 02:26	45.63	OK
15353	2026-09-21 02:27	46.01	OK	15354	2026-09-21 02:28	44.95	OK
15355	2026-09-21 02:29	47.56	OK	15356	2026-09-21 02:30	46.16	OK
15357	2026-09-21 02:31	45.71	OK	15358	2026-09-21 02:32	45.24	OK
15359	2026-09-21 02:33	45.03	OK	15360	2026-09-21 02:34	43.89	OK
15361	2026-09-21 02:35	46.58	OK	15362	2026-09-21 02:36	45.78	OK
15363	2026-09-21 02:37	47.00	OK	15364	2026-09-21 02:38	47.11	OK
15365	2026-09-21 02:39	46.03	OK	15366	2026-09-21 02:40	45.16	OK
15367	2026-09-21 02:41	45.97	OK	15368	2026-09-21 02:42	46.93	OK
15369	2026-09-21 02:43	47.20	OK	15370	2026-09-21 02:44	43.92	OK
15371	2026-09-21 02:45	47.28	OK	15372	2026-09-21 02:46	44.56	OK
15373	2026-09-21 02:47	44.62	OK	15374	2026-09-21 02:48	45.93	OK
15375	2026-09-21 02:49	47.52	OK	15376	2026-09-21 02:50	45.85	OK
15377	2026-09-21 02:51	45.12	OK	15378	2026-09-21 02:52	48.86	OK
15379	2026-09-21 02:53	45.64	OK	15380	2026-09-21 02:54	44.35	OK
15381	2026-09-21 02:55	45.77	OK	15382	2026-09-21 02:56	47.27	OK
15383	2026-09-21 02:57	45.07	OK	15384	2026-09-21 02:58	47.32	OK
15385	2026-09-21 02:59	46.81	OK	15386	2026-09-21 03:00	47.94	OK
15387	2026-09-21 03:01	45.48	OK	15388	2026-09-21 03:02	46.92	OK
15389	2026-09-21 03:03	48.03	OK	15390	2026-09-21 03:04	48.15	OK
15391	2026-09-21 03:05	45.46	OK	15392	2026-09-21 03:06	46.65	OK
15393	2026-09-21 03:07	44.77	OK	15394	2026-09-21 03:08	45.75	OK
15395	2026-09-21 03:09	45.96	OK	15396	2026-09-21 03:10	47.46	OK
15397	2026-09-21 03:11	45.11	OK	15398	2026-09-21 03:12	47.47	OK
15399	2026-09-21 03:13	46.45	OK	15400	2026-09-21 03:14	46.46	OK
15401	2026-09-21 03:15	48.33	OK	15402	2026-09-21 03:16	46.87	OK
1540	2026-09-21 03:17	47.63	OK	1540	2026-09-21 03:18	48.00	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
15405	2026-09-21 03:19	45.32	OK	15406	2026-09-21 03:20	47.87	OK
15407	2026-09-21 03:21	45.68	OK	15408	2026-09-21 03:22	45.55	OK
15409	2026-09-21 03:23	46.18	OK	15410	2026-09-21 03:24	47.99	OK
15411	2026-09-21 03:25	46.64	OK	15412	2026-09-21 03:26	46.62	OK
15413	2026-09-21 03:27	44.66	OK	15414	2026-09-21 03:28	47.57	OK
15415	2026-09-21 03:29	46.76	OK	15416	2026-09-21 03:30	48.88	OK
15417	2026-09-21 03:31	45.91	OK	15418	2026-09-21 03:32	48.12	OK
15419	2026-09-21 03:33	46.01	OK	15420	2026-09-21 03:34	46.44	OK
15421	2026-09-21 03:35	47.64	OK	15422	2026-09-21 03:36	45.51	OK
15423	2026-09-21 03:37	46.50	OK	15424	2026-09-21 03:38	48.62	OK
15425	2026-09-21 03:39	48.54	OK	15426	2026-09-21 03:40	45.78	OK
15427	2026-09-21 03:41	46.56	OK	15428	2026-09-21 03:42	47.65	OK
15429	2026-09-21 03:43	45.75	OK	15430	2026-09-21 03:44	47.36	OK
15431	2026-09-21 03:45	44.24	OK	15432	2026-09-21 03:46	47.33	OK
15433	2026-09-21 03:47	45.55	OK	15434	2026-09-21 03:48	47.05	OK
15435	2026-09-21 03:49	46.84	OK	15436	2026-09-21 03:50	49.17	OK
15437	2026-09-21 03:51	46.29	OK	15438	2026-09-21 03:52	47.61	OK
15439	2026-09-21 03:53	47.41	OK	15440	2026-09-21 03:54	45.93	OK
15441	2026-09-21 03:55	48.17	OK	15442	2026-09-21 03:56	49.25	OK
15443	2026-09-21 03:57	46.64	OK	15444	2026-09-21 03:58	47.26	OK
15445	2026-09-21 03:59	46.01	OK	15446	2026-09-21 04:00	48.03	OK
15447	2026-09-21 04:01	46.95	OK	15448	2026-09-21 04:02	47.05	OK
15449	2026-09-21 04:03	48.00	OK	15450	2026-09-21 04:04	46.57	OK
15451	2026-09-21 04:05	46.21	OK	15452	2026-09-21 04:06	48.46	OK
15453	2026-09-21 04:07	49.86	OK	15454	2026-09-21 04:08	47.41	OK
15455	2026-09-21 04:09	47.67	OK	15456	2026-09-21 04:10	48.18	OK
15457	2026-09-21 04:11	48.09	OK	15458	2026-09-21 04:12	49.01	OK
15459	2026-09-21 04:13	47.00	OK	15460	2026-09-21 04:14	47.80	OK
15461	2026-09-21 04:15	50.59	OK	15462	2026-09-21 04:16	47.53	OK
1546	2026-09-21 04:17	49.60	OK	1546	2026-09-21 04:18	47.31	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
15465	2026-09-21 04:19	46.18	OK	15466	2026-09-21 04:20	49.87	OK
15467	2026-09-21 04:21	48.80	OK	15468	2026-09-21 04:22	50.47	OK
15469	2026-09-21 04:23	48.27	OK	15470	2026-09-21 04:24	49.05	OK
15471	2026-09-21 04:25	46.94	OK	15472	2026-09-21 04:26	46.61	OK
15473	2026-09-21 04:27	47.32	OK	15474	2026-09-21 04:28	50.76	OK
15475	2026-09-21 04:29	47.54	OK	15476	2026-09-21 04:30	48.90	OK
15477	2026-09-21 04:31	48.07	OK	15478	2026-09-21 04:32	49.81	OK
15479	2026-09-21 04:33	48.22	OK	15480	2026-09-21 04:34	50.86	OK
15481	2026-09-21 04:35	47.17	OK	15482	2026-09-21 04:36	48.20	OK
15483	2026-09-21 04:37	48.31	OK	15484	2026-09-21 04:38	47.49	OK
15485	2026-09-21 04:39	47.93	OK	15486	2026-09-21 04:40	46.41	OK
15487	2026-09-21 04:41	48.98	OK	15488	2026-09-21 04:42	46.17	OK
15489	2026-09-21 04:43	48.74	OK	15490	2026-09-21 04:44	48.78	OK
15491	2026-09-21 04:45	46.75	OK	15492	2026-09-21 04:46	48.66	OK
15493	2026-09-21 04:47	48.80	OK	15494	2026-09-21 04:48	48.28	OK
15495	2026-09-21 04:49	48.53	OK	15496	2026-09-21 04:50	48.34	OK
15497	2026-09-21 04:51	46.18	OK	15498	2026-09-21 04:52	50.64	OK
15499	2026-09-21 04:53	48.04	OK	15500	2026-09-21 04:54	46.55	OK
15501	2026-09-21 04:55	48.74	OK	15502	2026-09-21 04:56	50.36	OK
15503	2026-09-21 04:57	48.13	OK	15504	2026-09-21 04:58	48.68	OK
15505	2026-09-21 04:59	50.00	OK	15506	2026-09-21 05:00	49.09	OK
15507	2026-09-21 05:01	50.52	OK	15508	2026-09-21 05:02	47.96	OK
15509	2026-09-21 05:03	48.15	OK	15510	2026-09-21 05:04	49.57	OK
15511	2026-09-21 05:05	49.30	OK	15512	2026-09-21 05:06	52.02	OK
15513	2026-09-21 05:07	49.17	OK	15514	2026-09-21 05:08	49.84	OK
15515	2026-09-21 05:09	46.96	OK	15516	2026-09-21 05:10	49.05	OK
15517	2026-09-21 05:11	49.24	OK	15518	2026-09-21 05:12	46.63	OK
15519	2026-09-21 05:13	51.16	OK	15520	2026-09-21 05:14	48.92	OK
15521	2026-09-21 05:15	49.55	OK	15522	2026-09-21 05:16	47.69	OK
1552	2026-09-21 05:17	50.36	OK	1552	2026-09-21 05:18	48.14	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
15525	2026-09-21 05:19	49.57	OK	15526	2026-09-21 05:20	47.81	OK
15527	2026-09-21 05:21	48.11	OK	15528	2026-09-21 05:22	49.20	OK
15529	2026-09-21 05:23	49.36	OK	15530	2026-09-21 05:24	49.62	OK
15531	2026-09-21 05:25	46.98	OK	15532	2026-09-21 05:26	51.20	OK
15533	2026-09-21 05:27	48.12	OK	15534	2026-09-21 05:28	48.81	OK
15535	2026-09-21 05:29	50.43	OK	15536	2026-09-21 05:30	50.00	OK
15537	2026-09-21 05:31	48.90	OK	15538	2026-09-21 05:32	49.04	OK
15539	2026-09-21 05:33	50.41	OK	15540	2026-09-21 05:34	48.31	OK
15541	2026-09-21 05:35	49.57	OK	15542	2026-09-21 05:36	50.75	OK
15543	2026-09-21 05:37	51.28	OK	15544	2026-09-21 05:38	48.27	OK
15545	2026-09-21 05:39	49.53	OK	15546	2026-09-21 05:40	49.55	OK
15547	2026-09-21 05:41	51.04	OK	15548	2026-09-21 05:42	50.01	OK
15549	2026-09-21 05:43	49.84	OK	15550	2026-09-21 05:44	49.44	OK
15551	2026-09-21 05:45	51.28	OK	15552	2026-09-21 05:46	51.60	OK
15553	2026-09-21 05:47	49.36	OK	15554	2026-09-21 05:48	48.54	OK
15555	2026-09-21 05:49	51.62	OK	15556	2026-09-21 05:50	49.38	OK
15557	2026-09-21 05:51	49.51	OK	15558	2026-09-21 05:52	48.86	OK
15559	2026-09-21 05:53	48.84	OK	15560	2026-09-21 05:54	49.45	OK
15561	2026-09-21 05:55	48.44	OK	15562	2026-09-21 05:56	50.10	OK
15563	2026-09-21 05:57	50.09	OK	15564	2026-09-21 05:58	47.79	OK
15565	2026-09-21 05:59	49.97	OK	15566	2026-09-21 06:00	48.44	OK
15567	2026-09-21 06:01	50.85	OK	15568	2026-09-21 06:02	50.72	OK
15569	2026-09-21 06:03	49.94	OK	15570	2026-09-21 06:04	50.12	OK
15571	2026-09-21 06:05	50.04	OK	15572	2026-09-21 06:06	48.18	OK
15573	2026-09-21 06:07	50.32	OK	15574	2026-09-21 06:08	50.66	OK
15575	2026-09-21 06:09	51.91	OK	15576	2026-09-21 06:10	51.14	OK
15577	2026-09-21 06:11	51.20	OK	15578	2026-09-21 06:12	50.94	OK
15579	2026-09-21 06:13	50.05	OK	15580	2026-09-21 06:14	50.03	OK
15581	2026-09-21 06:15	51.92	OK	15582	2026-09-21 06:16	52.11	OK
1558	2026-09-21 06:17	49.71	OK	1558	2026-09-21 06:18	48.88	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
15585	2026-09-21 06:19	49.29	OK	15586	2026-09-21 06:20	51.23	OK
15587	2026-09-21 06:21	50.30	OK	15588	2026-09-21 06:22	50.76	OK
15589	2026-09-21 06:23	49.77	OK	15590	2026-09-21 06:24	49.45	OK
15591	2026-09-21 06:25	49.81	OK	15592	2026-09-21 06:26	49.11	OK
15593	2026-09-21 06:27	51.53	OK	15594	2026-09-21 06:28	50.76	OK
15595	2026-09-21 06:29	51.13	OK	15596	2026-09-21 06:30	51.72	OK
15597	2026-09-21 06:31	50.09	OK	15598	2026-09-21 06:32	50.06	OK
15599	2026-09-21 06:33	49.25	OK	15600	2026-09-21 06:34	49.87	OK
15601	2026-09-21 06:35	49.22	OK	15602	2026-09-21 06:36	51.69	OK
15603	2026-09-21 06:37	49.34	OK	15604	2026-09-21 06:38	50.80	OK
15605	2026-09-21 06:39	50.08	OK	15606	2026-09-21 06:40	51.07	OK
15607	2026-09-21 06:41	50.39	OK	15608	2026-09-21 06:42	51.54	OK
15609	2026-09-21 06:43	50.90	OK	15610	2026-09-21 06:44	50.58	OK
15611	2026-09-21 06:45	51.95	OK	15612	2026-09-21 06:46	52.01	OK
15613	2026-09-21 06:47	51.27	OK	15614	2026-09-21 06:48	50.46	OK
15615	2026-09-21 06:49	52.65	OK	15616	2026-09-21 06:50	50.63	OK
15617	2026-09-21 06:51	50.46	OK	15618	2026-09-21 06:52	51.04	OK
15619	2026-09-21 06:53	51.75	OK	15620	2026-09-21 06:54	51.69	OK
15621	2026-09-21 06:55	50.82	OK	15622	2026-09-21 06:56	49.76	OK
15623	2026-09-21 06:57	51.40	OK	15624	2026-09-21 06:58	51.30	OK
15625	2026-09-21 06:59	50.84	OK	15626	2026-09-21 07:00	52.14	OK
15627	2026-09-21 07:01	52.26	OK	15628	2026-09-21 07:02	52.93	OK
15629	2026-09-21 07:03	49.27	OK	15630	2026-09-21 07:04	50.98	OK
15631	2026-09-21 07:05	52.60	OK	15632	2026-09-21 07:06	52.42	OK
15633	2026-09-21 07:07	53.38	OK	15634	2026-09-21 07:08	52.67	OK
15635	2026-09-21 07:09	52.59	OK	15636	2026-09-21 07:10	52.53	OK
15637	2026-09-21 07:11	50.78	OK	15638	2026-09-21 07:12	53.11	OK
15639	2026-09-21 07:13	50.93	OK	15640	2026-09-21 07:14	50.85	OK
15641	2026-09-21 07:15	52.33	OK	15642	2026-09-21 07:16	52.16	OK
1564	2026-09-21 07:17	51.96	OK	1564	2026-09-21 07:18	51.46	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
15645	2026-09-21 07:19	51.24	OK	15646	2026-09-21 07:20	51.51	OK
15647	2026-09-21 07:21	49.74	OK	15648	2026-09-21 07:22	49.51	OK
15649	2026-09-21 07:23	50.38	OK	15650	2026-09-21 07:24	51.95	OK
15651	2026-09-21 07:25	52.23	OK	15652	2026-09-21 07:26	52.15	OK
15653	2026-09-21 07:27	52.30	OK	15654	2026-09-21 07:28	50.82	OK
15655	2026-09-21 07:29	50.27	OK	15656	2026-09-21 07:30	49.66	OK
15657	2026-09-21 07:31	52.14	OK	15658	2026-09-21 07:32	52.86	OK
15659	2026-09-21 07:33	51.83	OK	15660	2026-09-21 07:34	50.77	OK
15661	2026-09-21 07:35	52.72	OK	15662	2026-09-21 07:36	52.27	OK
15663	2026-09-21 07:37	54.74	OK	15664	2026-09-21 07:38	51.22	OK
15665	2026-09-21 07:39	51.90	OK	15666	2026-09-21 07:40	52.63	OK
15667	2026-09-21 07:41	50.66	OK	15668	2026-09-21 07:42	52.43	OK
15669	2026-09-21 07:43	51.51	OK	15670	2026-09-21 07:44	52.61	OK
15671	2026-09-21 07:45	53.47	OK	15672	2026-09-21 07:46	53.00	OK
15673	2026-09-21 07:47	51.80	OK	15674	2026-09-21 07:48	52.91	OK
15675	2026-09-21 07:49	51.01	OK	15676	2026-09-21 07:50	52.30	OK
15677	2026-09-21 07:51	52.75	OK	15678	2026-09-21 07:52	52.28	OK
15679	2026-09-21 07:53	53.72	OK	15680	2026-09-21 07:54	53.31	OK
15681	2026-09-21 07:55	53.14	OK	15682	2026-09-21 07:56	52.31	OK
15683	2026-09-21 07:57	52.09	OK	15684	2026-09-21 07:58	52.91	OK
15685	2026-09-21 07:59	53.06	OK	15686	2026-09-21 08:00	53.34	OK
15687	2026-09-21 08:01	52.37	OK	15688	2026-09-21 08:02	51.06	OK
15689	2026-09-21 08:03	52.21	OK	15690	2026-09-21 08:04	55.03	OK
15691	2026-09-21 08:05	52.19	OK	15692	2026-09-21 08:06	53.53	OK
15693	2026-09-21 08:07	50.91	OK	15694	2026-09-21 08:08	52.49	OK
15695	2026-09-21 08:09	51.82	OK	15696	2026-09-21 08:10	54.04	OK
15697	2026-09-21 08:11	53.05	OK	15698	2026-09-21 08:12	52.71	OK
15699	2026-09-21 08:13	52.35	OK	15700	2026-09-21 08:14	51.25	OK
15701	2026-09-21 08:15	53.54	OK	15702	2026-09-21 08:16	51.62	OK
1570	2026-09-21 08:17	53.71	OK	1570	2026-09-21 08:18	53.00	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
15705	2026-09-21 08:19	51.26	OK	15706	2026-09-21 08:20	52.47	OK
15707	2026-09-21 08:21	54.02	OK	15708	2026-09-21 08:22	52.13	OK
15709	2026-09-21 08:23	51.21	OK	15710	2026-09-21 08:24	54.00	OK
15711	2026-09-21 08:25	51.27	OK	15712	2026-09-21 08:26	53.44	OK
15713	2026-09-21 08:27	53.43	OK	15714	2026-09-21 08:28	52.47	OK
15715	2026-09-21 08:29	53.27	OK	15716	2026-09-21 08:30	54.26	OK
15717	2026-09-21 08:31	52.99	OK	15718	2026-09-21 08:32	52.56	OK
15719	2026-09-21 08:33	52.99	OK	15720	2026-09-21 08:34	53.46	OK
15721	2026-09-21 08:35	53.27	OK	15722	2026-09-21 08:36	51.90	OK
15723	2026-09-21 08:37	54.76	OK	15724	2026-09-21 08:38	52.84	OK
15725	2026-09-21 08:39	54.91	OK	15726	2026-09-21 08:40	52.32	OK
15727	2026-09-21 08:41	54.41	OK	15728	2026-09-21 08:42	53.33	OK
15729	2026-09-21 08:43	51.85	OK	15730	2026-09-21 08:44	53.54	OK
15731	2026-09-21 08:45	52.06	OK	15732	2026-09-21 08:46	54.59	OK
15733	2026-09-21 08:47	52.33	OK	15734	2026-09-21 08:48	54.27	OK
15735	2026-09-21 08:49	51.94	OK	15736	2026-09-21 08:50	55.07	OK
15737	2026-09-21 08:51	51.84	OK	15738	2026-09-21 08:52	54.49	OK
15739	2026-09-21 08:53	54.70	OK	15740	2026-09-21 08:54	52.03	OK
15741	2026-09-21 08:55	55.07	OK	15742	2026-09-21 08:56	53.41	OK
15743	2026-09-21 08:57	53.64	OK	15744	2026-09-21 08:58	53.34	OK
15745	2026-09-21 08:59	53.73	OK	15746	2026-09-21 09:00	53.69	OK
15747	2026-09-21 09:01	55.47	OK	15748	2026-09-21 09:02	52.71	OK
15749	2026-09-21 09:03	53.61	OK	15750	2026-09-21 09:04	55.33	OK
15751	2026-09-21 09:05	51.92	OK	15752	2026-09-21 09:06	54.04	OK
15753	2026-09-21 09:07	52.46	OK	15754	2026-09-21 09:08	53.74	OK
15755	2026-09-21 09:09	53.08	OK	15756	2026-09-21 09:10	53.77	OK
15757	2026-09-21 09:11	52.74	OK	15758	2026-09-21 09:12	53.95	OK
15759	2026-09-21 09:13	52.35	OK	15760	2026-09-21 09:14	50.65	OK
15761	2026-09-21 09:15	51.48	OK	15762	2026-09-21 09:16	53.84	OK
1576	2026-09-21 09:17	51.96	OK	1576	2026-09-21 09:18	54.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
15765	2026-09-21 09:19	53.14	OK	15766	2026-09-21 09:20	53.99	OK
15767	2026-09-21 09:21	53.33	OK	15768	2026-09-21 09:22	54.35	OK
15769	2026-09-21 09:23	52.92	OK	15770	2026-09-21 09:24	54.89	OK
15771	2026-09-21 09:25	52.86	OK	15772	2026-09-21 09:26	51.89	OK
15773	2026-09-21 09:27	53.77	OK	15774	2026-09-21 09:28	51.66	OK
15775	2026-09-21 09:29	54.51	OK	15776	2026-09-21 09:30	53.05	OK
15777	2026-09-21 09:31	53.48	OK	15778	2026-09-21 09:32	53.72	OK
15779	2026-09-21 09:33	56.49	OK	15780	2026-09-21 09:34	55.73	OK
15781	2026-09-21 09:35	54.08	OK	15782	2026-09-21 09:36	52.15	OK
15783	2026-09-21 09:37	54.70	OK	15784	2026-09-21 09:38	54.47	OK
15785	2026-09-21 09:39	53.28	OK	15786	2026-09-21 09:40	53.96	OK
15787	2026-09-21 09:41	50.86	OK	15788	2026-09-21 09:42	53.47	OK
15789	2026-09-21 09:43	53.12	OK	15790	2026-09-21 09:44	52.95	OK
15791	2026-09-21 09:45	55.04	OK	15792	2026-09-21 09:46	53.03	OK
15793	2026-09-21 09:47	54.23	OK	15794	2026-09-21 09:48	54.84	OK
15795	2026-09-21 09:49	52.73	OK	15796	2026-09-21 09:50	53.66	OK
15797	2026-09-21 09:51	53.03	OK	15798	2026-09-21 09:52	53.10	OK
15799	2026-09-21 09:53	53.18	OK	15800	2026-09-21 09:54	54.99	OK
15801	2026-09-21 09:55	54.67	OK	15802	2026-09-21 09:56	52.23	OK
15803	2026-09-21 09:57	53.06	OK	15804	2026-09-21 09:58	53.22	OK
15805	2026-09-21 09:59	54.38	OK	15806	2026-09-21 10:00	51.70	OK
15807	2026-09-21 10:01	53.09	OK	15808	2026-09-21 10:02	54.44	OK
15809	2026-09-21 10:03	53.60	OK	15810	2026-09-21 10:04	53.09	OK
15811	2026-09-21 10:05	53.61	OK	15812	2026-09-21 10:06	55.86	OK
15813	2026-09-21 10:07	54.92	OK	15814	2026-09-21 10:08	54.19	OK
15815	2026-09-21 10:09	51.87	OK	15816	2026-09-21 10:10	53.78	OK
15817	2026-09-21 10:11	52.89	OK	15818	2026-09-21 10:12	55.13	OK
15819	2026-09-21 10:13	55.61	OK	15820	2026-09-21 10:14	53.28	OK
15821	2026-09-21 10:15	52.93	OK	15822	2026-09-21 10:16	56.66	OK
1582	2026-09-21 10:17	54.32	OK	1582	2026-09-21 10:18	54.20	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
15825	2026-09-21 10:19	54.82	OK	15826	2026-09-21 10:20	53.81	OK
15827	2026-09-21 10:21	55.02	OK	15828	2026-09-21 10:22	52.28	OK
15829	2026-09-21 10:23	53.94	OK	15830	2026-09-21 10:24	54.37	OK
15831	2026-09-21 10:25	51.11	OK	15832	2026-09-21 10:26	55.44	OK
15833	2026-09-21 10:27	53.30	OK	15834	2026-09-21 10:28	53.53	OK
15835	2026-09-21 10:29	55.19	OK	15836	2026-09-21 10:30	53.84	OK
15837	2026-09-21 10:31	54.88	OK	15838	2026-09-21 10:32	52.94	OK
15839	2026-09-21 10:33	52.86	OK	15840	2026-09-21 10:34	54.50	OK
15841	2026-09-21 10:35	54.91	OK	15842	2026-09-21 10:36	53.45	OK
15843	2026-09-21 10:37	53.74	OK	15844	2026-09-21 10:38	54.12	OK
15845	2026-09-21 10:39	55.29	OK	15846	2026-09-21 10:40	53.07	OK
15847	2026-09-21 10:41	53.59	OK	15848	2026-09-21 10:42	52.88	OK
15849	2026-09-21 10:43	56.43	OK	15850	2026-09-21 10:44	55.76	OK
15851	2026-09-21 10:45	55.26	OK	15852	2026-09-21 10:46	54.61	OK
15853	2026-09-21 10:47	55.25	OK	15854	2026-09-21 10:48	54.06	OK
15855	2026-09-21 10:49	52.90	OK	15856	2026-09-21 10:50	53.09	OK
15857	2026-09-21 10:51	54.37	OK	15858	2026-09-21 10:52	55.04	OK
15859	2026-09-21 10:53	54.20	OK	15860	2026-09-21 10:54	53.28	OK
15861	2026-09-21 10:55	54.99	OK	15862	2026-09-21 10:56	52.45	OK
15863	2026-09-21 10:57	56.72	OK	15864	2026-09-21 10:58	53.92	OK
15865	2026-09-21 10:59	53.67	OK	15866	2026-09-21 11:00	53.47	OK
15867	2026-09-21 11:01	55.31	OK	15868	2026-09-21 11:02	52.46	OK
15869	2026-09-21 11:03	56.56	OK	15870	2026-09-21 11:04	52.87	OK
15871	2026-09-21 11:05	53.27	OK	15872	2026-09-21 11:06	55.69	OK
15873	2026-09-21 11:07	54.03	OK	15874	2026-09-21 11:08	52.99	OK
15875	2026-09-21 11:09	53.29	OK	15876	2026-09-21 11:10	54.45	OK
15877	2026-09-21 11:11	53.54	OK	15878	2026-09-21 11:12	55.04	OK
15879	2026-09-21 11:13	54.23	OK	15880	2026-09-21 11:14	55.42	OK
15881	2026-09-21 11:15	54.68	OK	15882	2026-09-21 11:16	54.38	OK
1588	2026-09-21 11:17	54.85	OK	1588	2026-09-21 11:18	54.15	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
15885	2026-09-21 11:19	52.00	OK	15886	2026-09-21 11:20	51.88	OK
15887	2026-09-21 11:21	52.44	OK	15888	2026-09-21 11:22	53.16	OK
15889	2026-09-21 11:23	53.88	OK	15890	2026-09-21 11:24	56.50	OK
15891	2026-09-21 11:25	53.42	OK	15892	2026-09-21 11:26	55.32	OK
15893	2026-09-21 11:27	55.08	OK	15894	2026-09-21 11:28	55.21	OK
15895	2026-09-21 11:29	54.05	OK	15896	2026-09-21 11:30	52.84	OK
15897	2026-09-21 11:31	53.65	OK	15898	2026-09-21 11:32	55.30	OK
15899	2026-09-21 11:33	55.11	OK	15900	2026-09-21 11:34	53.84	OK
15901	2026-09-21 11:35	54.08	OK	15902	2026-09-21 11:36	56.39	OK
15903	2026-09-21 11:37	52.50	OK	15904	2026-09-21 11:38	53.63	OK
15905	2026-09-21 11:39	53.60	OK	15906	2026-09-21 11:40	54.38	OK
15907	2026-09-21 11:41	54.69	OK	15908	2026-09-21 11:42	55.05	OK
15909	2026-09-21 11:43	52.79	OK	15910	2026-09-21 11:44	52.72	OK
15911	2026-09-21 11:45	52.33	OK	15912	2026-09-21 11:46	52.93	OK
15913	2026-09-21 11:47	53.85	OK	15914	2026-09-21 11:48	53.61	OK
15915	2026-09-21 11:49	52.87	OK	15916	2026-09-21 11:50	54.93	OK
15917	2026-09-21 11:51	54.64	OK	15918	2026-09-21 11:52	53.20	OK
15919	2026-09-21 11:53	52.85	OK	15920	2026-09-21 11:54	53.73	OK
15921	2026-09-21 11:55	53.34	OK	15922	2026-09-21 11:56	54.80	OK
15923	2026-09-21 11:57	55.08	OK	15924	2026-09-21 11:58	53.80	OK
15925	2026-09-21 11:59	54.04	OK	15926	2026-09-21 12:00	54.48	OK
15927	2026-09-21 12:01	54.46	OK	15928	2026-09-21 12:02	54.29	OK
15929	2026-09-21 12:03	54.07	OK	15930	2026-09-21 12:04	56.31	OK
15931	2026-09-21 12:05	54.91	OK	15932	2026-09-21 12:06	55.32	OK
15933	2026-09-21 12:07	52.99	OK	15934	2026-09-21 12:08	54.44	OK
15935	2026-09-21 12:09	53.06	OK	15936	2026-09-21 12:10	53.51	OK
15937	2026-09-21 12:11	51.38	OK	15938	2026-09-21 12:12	54.73	OK
15939	2026-09-21 12:13	54.96	OK	15940	2026-09-21 12:14	54.34	OK
15941	2026-09-21 12:15	55.00	OK	15942	2026-09-21 12:16	54.75	OK
1594	2026-09-21 12:17	53.41	OK	1594	2026-09-21 12:18	55.77	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
15945	2026-09-21 12:19	55.53	OK	15946	2026-09-21 12:20	55.20	OK
15947	2026-09-21 12:21	53.41	OK	15948	2026-09-21 12:22	54.68	OK
15949	2026-09-21 12:23	53.62	OK	15950	2026-09-21 12:24	55.20	OK
15951	2026-09-21 12:25	53.02	OK	15952	2026-09-21 12:26	52.13	OK
15953	2026-09-21 12:27	53.89	OK	15954	2026-09-21 12:28	54.16	OK
15955	2026-09-21 12:29	51.94	OK	15956	2026-09-21 12:30	52.74	OK
15957	2026-09-21 12:31	53.92	OK	15958	2026-09-21 12:32	54.99	OK
15959	2026-09-21 12:33	53.43	OK	15960	2026-09-21 12:34	54.45	OK
15961	2026-09-21 12:35	53.58	OK	15962	2026-09-21 12:36	54.57	OK
15963	2026-09-21 12:37	54.79	OK	15964	2026-09-21 12:38	54.62	OK
15965	2026-09-21 12:39	54.65	OK	15966	2026-09-21 12:40	54.90	OK
15967	2026-09-21 12:41	53.64	OK	15968	2026-09-21 12:42	54.45	OK
15969	2026-09-21 12:43	54.85	OK	15970	2026-09-21 12:44	53.13	OK
15971	2026-09-21 12:45	52.19	OK	15972	2026-09-21 12:46	51.11	OK
15973	2026-09-21 12:47	52.52	OK	15974	2026-09-21 12:48	53.90	OK
15975	2026-09-21 12:49	55.29	OK	15976	2026-09-21 12:50	52.88	OK
15977	2026-09-21 12:51	54.96	OK	15978	2026-09-21 12:52	53.34	OK
15979	2026-09-21 12:53	54.28	OK	15980	2026-09-21 12:54	53.52	OK
15981	2026-09-21 12:55	55.24	OK	15982	2026-09-21 12:56	52.16	OK
15983	2026-09-21 12:57	55.07	OK	15984	2026-09-21 12:58	53.54	OK
15985	2026-09-21 12:59	52.73	OK	15986	2026-09-21 13:00	54.40	OK
15987	2026-09-21 13:01	53.65	OK	15988	2026-09-21 13:02	53.85	OK
15989	2026-09-21 13:03	55.23	OK	15990	2026-09-21 13:04	52.43	OK
15991	2026-09-21 13:05	55.81	OK	15992	2026-09-21 13:06	55.79	OK
15993	2026-09-21 13:07	54.25	OK	15994	2026-09-21 13:08	54.27	OK
15995	2026-09-21 13:09	53.34	OK	15996	2026-09-21 13:10	53.16	OK
15997	2026-09-21 13:11	53.93	OK	15998	2026-09-21 13:12	55.88	OK
15999	2026-09-21 13:13	55.19	OK	16000	2026-09-21 13:14	54.33	OK
16001	2026-09-21 13:15	52.51	OK	16002	2026-09-21 13:16	51.89	OK
1600	2026-09-21 13:17	53.28	OK	1600	2026-09-21 13:18	53.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
16005	2026-09-21 13:19	52.34	OK	16006	2026-09-21 13:20	52.97	OK
16007	2026-09-21 13:21	54.18	OK	16008	2026-09-21 13:22	53.59	OK
16009	2026-09-21 13:23	52.25	OK	16010	2026-09-21 13:24	53.38	OK
16011	2026-09-21 13:25	55.30	OK	16012	2026-09-21 13:26	52.30	OK
16013	2026-09-21 13:27	52.02	OK	16014	2026-09-21 13:28	53.35	OK
16015	2026-09-21 13:29	53.09	OK	16016	2026-09-21 13:30	54.61	OK
16017	2026-09-21 13:31	54.37	OK	16018	2026-09-21 13:32	54.89	OK
16019	2026-09-21 13:33	54.56	OK	16020	2026-09-21 13:34	54.77	OK
16021	2026-09-21 13:35	54.21	OK	16022	2026-09-21 13:36	55.86	OK
16023	2026-09-21 13:37	53.66	OK	16024	2026-09-21 13:38	53.61	OK
16025	2026-09-21 13:39	53.16	OK	16026	2026-09-21 13:40	54.25	OK
16027	2026-09-21 13:41	53.72	OK	16028	2026-09-21 13:42	53.07	OK
16029	2026-09-21 13:43	52.59	OK	16030	2026-09-21 13:44	53.91	OK
16031	2026-09-21 13:45	52.79	OK	16032	2026-09-21 13:46	54.29	OK
16033	2026-09-21 13:47	53.36	OK	16034	2026-09-21 13:48	53.36	OK
16035	2026-09-21 13:49	54.65	OK	16036	2026-09-21 13:50	53.09	OK
16037	2026-09-21 13:51	54.22	OK	16038	2026-09-21 13:52	51.15	OK
16039	2026-09-21 13:53	55.31	OK	16040	2026-09-21 13:54	52.36	OK
16041	2026-09-21 13:55	53.32	OK	16042	2026-09-21 13:56	52.54	OK
16043	2026-09-21 13:57	53.42	OK	16044	2026-09-21 13:58	54.24	OK
16045	2026-09-21 13:59	53.37	OK	16046	2026-09-21 14:00	52.29	OK
16047	2026-09-21 14:01	52.91	OK	16048	2026-09-21 14:02	54.76	OK
16049	2026-09-21 14:03	52.89	OK	16050	2026-09-21 14:04	54.33	OK
16051	2026-09-21 14:05	53.84	OK	16052	2026-09-21 14:06	53.07	OK
16053	2026-09-21 14:07	53.08	OK	16054	2026-09-21 14:08	52.53	OK
16055	2026-09-21 14:09	53.62	OK	16056	2026-09-21 14:10	53.42	OK
16057	2026-09-21 14:11	53.21	OK	16058	2026-09-21 14:12	53.47	OK
16059	2026-09-21 14:13	53.44	OK	16060	2026-09-21 14:14	51.33	OK
16061	2026-09-21 14:15	52.91	OK	16062	2026-09-21 14:16	53.84	OK
1606	2026-09-21 14:17	51.89	OK	1606	2026-09-21 14:18	53.99	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
16065	2026-09-21 14:19	53.23	OK	16066	2026-09-21 14:20	51.92	OK
16067	2026-09-21 14:21	55.01	OK	16068	2026-09-21 14:22	51.76	OK
16069	2026-09-21 14:23	52.38	OK	16070	2026-09-21 14:24	52.40	OK
16071	2026-09-21 14:25	51.19	OK	16072	2026-09-21 14:26	52.10	OK
16073	2026-09-21 14:27	54.10	OK	16074	2026-09-21 14:28	52.67	OK
16075	2026-09-21 14:29	52.10	OK	16076	2026-09-21 14:30	51.53	OK
16077	2026-09-21 14:31	52.42	OK	16078	2026-09-21 14:32	52.34	OK
16079	2026-09-21 14:33	51.67	OK	16080	2026-09-21 14:34	52.83	OK
16081	2026-09-21 14:35	52.71	OK	16082	2026-09-21 14:36	55.74	OK
16083	2026-09-21 14:37	52.42	OK	16084	2026-09-21 14:38	54.87	OK
16085	2026-09-21 14:39	53.03	OK	16086	2026-09-21 14:40	52.38	OK
16087	2026-09-21 14:41	52.52	OK	16088	2026-09-21 14:42	50.54	OK
16089	2026-09-21 14:43	55.17	OK	16090	2026-09-21 14:44	50.57	OK
16091	2026-09-21 14:45	51.46	OK	16092	2026-09-21 14:46	53.38	OK
16093	2026-09-21 14:47	53.01	OK	16094	2026-09-21 14:48	51.78	OK
16095	2026-09-21 14:49	51.95	OK	16096	2026-09-21 14:50	53.02	OK
16097	2026-09-21 14:51	54.68	OK	16098	2026-09-21 14:52	53.01	OK
16099	2026-09-21 14:53	53.47	OK	16100	2026-09-21 14:54	50.24	OK
16101	2026-09-21 14:55	52.92	OK	16102	2026-09-21 14:56	50.35	OK
16103	2026-09-21 14:57	54.25	OK	16104	2026-09-21 14:58	51.18	OK
16105	2026-09-21 14:59	52.56	OK	16106	2026-09-21 15:00	53.01	OK
16107	2026-09-21 15:01	53.54	OK	16108	2026-09-21 15:02	51.81	OK
16109	2026-09-21 15:03	51.64	OK	16110	2026-09-21 15:04	53.32	OK
16111	2026-09-21 15:05	51.77	OK	16112	2026-09-21 15:06	53.23	OK
16113	2026-09-21 15:07	51.71	OK	16114	2026-09-21 15:08	53.26	OK
16115	2026-09-21 15:09	53.94	OK	16116	2026-09-21 15:10	53.18	OK
16117	2026-09-21 15:11	51.05	OK	16118	2026-09-21 15:12	50.17	OK
16119	2026-09-21 15:13	51.61	OK	16120	2026-09-21 15:14	53.25	OK
16121	2026-09-21 15:15	52.17	OK	16122	2026-09-21 15:16	51.59	OK
1612	2026-09-21 15:17	51.81	OK	1612	2026-09-21 15:18	52.13	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
16125	2026-09-21 15:19	51.04	OK	16126	2026-09-21 15:20	53.14	OK
16127	2026-09-21 15:21	50.91	OK	16128	2026-09-21 15:22	52.36	OK
16129	2026-09-21 15:23	53.79	OK	16130	2026-09-21 15:24	53.03	OK
16131	2026-09-21 15:25	50.54	OK	16132	2026-09-21 15:26	52.37	OK
16133	2026-09-21 15:27	52.18	OK	16134	2026-09-21 15:28	51.04	OK
16135	2026-09-21 15:29	53.30	OK	16136	2026-09-21 15:30	50.86	OK
16137	2026-09-21 15:31	51.69	OK	16138	2026-09-21 15:32	52.08	OK
16139	2026-09-21 15:33	51.04	OK	16140	2026-09-21 15:34	52.01	OK
16141	2026-09-21 15:35	54.08	OK	16142	2026-09-21 15:36	51.01	OK
16143	2026-09-21 15:37	52.45	OK	16144	2026-09-21 15:38	50.75	OK
16145	2026-09-21 15:39	52.53	OK	16146	2026-09-21 15:40	49.59	OK
16147	2026-09-21 15:41	52.67	OK	16148	2026-09-21 15:42	53.26	OK
16149	2026-09-21 15:43	52.19	OK	16150	2026-09-21 15:44	51.06	OK
16151	2026-09-21 15:45	52.66	OK	16152	2026-09-21 15:46	51.74	OK
16153	2026-09-21 15:47	53.31	OK	16154	2026-09-21 15:48	50.74	OK
16155	2026-09-21 15:49	51.63	OK	16156	2026-09-21 15:50	50.90	OK
16157	2026-09-21 15:51	49.70	OK	16158	2026-09-21 15:52	52.71	OK
16159	2026-09-21 15:53	52.66	OK	16160	2026-09-21 15:54	51.22	OK
16161	2026-09-21 15:55	50.01	OK	16162	2026-09-21 15:56	52.09	OK
16163	2026-09-21 15:57	52.45	OK	16164	2026-09-21 15:58	51.96	OK
16165	2026-09-21 15:59	52.72	OK	16166	2026-09-21 16:00	51.50	OK
16167	2026-09-21 16:01	52.46	OK	16168	2026-09-21 16:02	50.70	OK
16169	2026-09-21 16:03	51.89	OK	16170	2026-09-21 16:04	48.91	OK
16171	2026-09-21 16:05	52.02	OK	16172	2026-09-21 16:06	50.74	OK
16173	2026-09-21 16:07	53.42	OK	16174	2026-09-21 16:08	51.02	OK
16175	2026-09-21 16:09	51.23	OK	16176	2026-09-21 16:10	50.23	OK
16177	2026-09-21 16:11	50.34	OK	16178	2026-09-21 16:12	52.66	OK
16179	2026-09-21 16:13	49.60	OK	16180	2026-09-21 16:14	50.66	OK
16181	2026-09-21 16:15	52.14	OK	16182	2026-09-21 16:16	50.52	OK
1618	2026-09-21 16:17	49.79	OK	1618	2026-09-21 16:18	51.44	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
16185	2026-09-21 16:19	51.91	OK	16186	2026-09-21 16:20	51.94	OK
16187	2026-09-21 16:21	51.12	OK	16188	2026-09-21 16:22	47.99	OK
16189	2026-09-21 16:23	50.79	OK	16190	2026-09-21 16:24	48.48	OK
16191	2026-09-21 16:25	51.27	OK	16192	2026-09-21 16:26	48.74	OK
16193	2026-09-21 16:27	50.13	OK	16194	2026-09-21 16:28	51.05	OK
16195	2026-09-21 16:29	50.40	OK	16196	2026-09-21 16:30	49.39	OK
16197	2026-09-21 16:31	50.50	OK	16198	2026-09-21 16:32	50.05	OK
16199	2026-09-21 16:33	49.80	OK	16200	2026-09-21 16:34	50.68	OK
16201	2026-09-21 16:35	48.83	OK	16202	2026-09-21 16:36	50.44	OK
16203	2026-09-21 16:37	50.81	OK	16204	2026-09-21 16:38	51.21	OK
16205	2026-09-21 16:39	49.96	OK	16206	2026-09-21 16:40	50.68	OK
16207	2026-09-21 16:41	50.83	OK	16208	2026-09-21 16:42	50.82	OK
16209	2026-09-21 16:43	51.55	OK	16210	2026-09-21 16:44	49.60	OK
16211	2026-09-21 16:45	49.70	OK	16212	2026-09-21 16:46	50.02	OK
16213	2026-09-21 16:47	49.43	OK	16214	2026-09-21 16:48	49.52	OK
16215	2026-09-21 16:49	51.16	OK	16216	2026-09-21 16:50	47.42	OK
16217	2026-09-21 16:51	50.54	OK	16218	2026-09-21 16:52	50.12	OK
16219	2026-09-21 16:53	49.70	OK	16220	2026-09-21 16:54	47.36	OK
16221	2026-09-21 16:55	49.33	OK	16222	2026-09-21 16:56	48.03	OK
16223	2026-09-21 16:57	51.04	OK	16224	2026-09-21 16:58	51.19	OK
16225	2026-09-21 16:59	49.48	OK	16226	2026-09-21 17:00	51.44	OK
16227	2026-09-21 17:01	49.71	OK	16228	2026-09-21 17:02	48.89	OK
16229	2026-09-21 17:03	50.22	OK	16230	2026-09-21 17:04	47.80	OK
16231	2026-09-21 17:05	48.90	OK	16232	2026-09-21 17:06	50.84	OK
16233	2026-09-21 17:07	51.77	OK	16234	2026-09-21 17:08	50.02	OK
16235	2026-09-21 17:09	50.35	OK	16236	2026-09-21 17:10	48.54	OK
16237	2026-09-21 17:11	51.40	OK	16238	2026-09-21 17:12	51.40	OK
16239	2026-09-21 17:13	49.43	OK	16240	2026-09-21 17:14	48.35	OK
16241	2026-09-21 17:15	51.20	OK	16242	2026-09-21 17:16	50.74	OK
1624	2026-09-21 17:17	50.43	OK	1624	2026-09-21 17:18	48.54	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
16245	2026-09-21 17:19	49.41	OK	16246	2026-09-21 17:20	48.59	OK
16247	2026-09-21 17:21	49.86	OK	16248	2026-09-21 17:22	49.38	OK
16249	2026-09-21 17:23	48.36	OK	16250	2026-09-21 17:24	49.94	OK
16251	2026-09-21 17:25	49.81	OK	16252	2026-09-21 17:26	51.19	OK
16253	2026-09-21 17:27	49.69	OK	16254	2026-09-21 17:28	49.27	OK
16255	2026-09-21 17:29	48.76	OK	16256	2026-09-21 17:30	49.19	OK
16257	2026-09-21 17:31	50.13	OK	16258	2026-09-21 17:32	49.89	OK
16259	2026-09-21 17:33	48.20	OK	16260	2026-09-21 17:34	49.27	OK
16261	2026-09-21 17:35	51.62	OK	16262	2026-09-21 17:36	50.14	OK
16263	2026-09-21 17:37	49.64	OK	16264	2026-09-21 17:38	49.06	OK
16265	2026-09-21 17:39	49.41	OK	16266	2026-09-21 17:40	48.25	OK
16267	2026-09-21 17:41	50.53	OK	16268	2026-09-21 17:42	47.52	OK
16269	2026-09-21 17:43	49.64	OK	16270	2026-09-21 17:44	48.58	OK
16271	2026-09-21 17:45	49.41	OK	16272	2026-09-21 17:46	50.08	OK
16273	2026-09-21 17:47	47.88	OK	16274	2026-09-21 17:48	49.38	OK
16275	2026-09-21 17:49	48.61	OK	16276	2026-09-21 17:50	47.99	OK
16277	2026-09-21 17:51	47.09	OK	16278	2026-09-21 17:52	49.05	OK
16279	2026-09-21 17:53	49.95	OK	16280	2026-09-21 17:54	49.50	OK
16281	2026-09-21 17:55	49.09	OK	16282	2026-09-21 17:56	49.18	OK
16283	2026-09-21 17:57	48.01	OK	16284	2026-09-21 17:58	50.88	OK
16285	2026-09-21 17:59	47.36	OK	16286	2026-09-21 18:00	46.69	OK
16287	2026-09-21 18:01	48.55	OK	16288	2026-09-21 18:02	48.30	OK
16289	2026-09-21 18:03	48.67	OK	16290	2026-09-21 18:04	50.05	OK
16291	2026-09-21 18:05	49.99	OK	16292	2026-09-21 18:06	49.73	OK
16293	2026-09-21 18:07	48.60	OK	16294	2026-09-21 18:08	48.82	OK
16295	2026-09-21 18:09	48.52	OK	16296	2026-09-21 18:10	48.77	OK
16297	2026-09-21 18:11	50.66	OK	16298	2026-09-21 18:12	49.66	OK
16299	2026-09-21 18:13	47.25	OK	16300	2026-09-21 18:14	49.19	OK
16301	2026-09-21 18:15	49.47	OK	16302	2026-09-21 18:16	50.12	OK
16303	2026-09-21 18:17	47.75	OK	16303	2026-09-21 18:18	46.92	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
16305	2026-09-21 18:19	49.27	OK	16306	2026-09-21 18:20	47.27	OK
16307	2026-09-21 18:21	48.28	OK	16308	2026-09-21 18:22	49.98	OK
16309	2026-09-21 18:23	48.50	OK	16310	2026-09-21 18:24	50.17	OK
16311	2026-09-21 18:25	46.34	OK	16312	2026-09-21 18:26	49.01	OK
16313	2026-09-21 18:27	47.25	OK	16314	2026-09-21 18:28	45.92	OK
16315	2026-09-21 18:29	46.43	OK	16316	2026-09-21 18:30	49.25	OK
16317	2026-09-21 18:31	48.81	OK	16318	2026-09-21 18:32	48.66	OK
16319	2026-09-21 18:33	48.08	OK	16320	2026-09-21 18:34	45.64	OK
16321	2026-09-21 18:35	46.40	OK	16322	2026-09-21 18:36	46.45	OK
16323	2026-09-21 18:37	49.00	OK	16324	2026-09-21 18:38	49.09	OK
16325	2026-09-21 18:39	48.88	OK	16326	2026-09-21 18:40	48.96	OK
16327	2026-09-21 18:41	48.16	OK	16328	2026-09-21 18:42	48.67	OK
16329	2026-09-21 18:43	48.69	OK	16330	2026-09-21 18:44	47.51	OK
16331	2026-09-21 18:45	47.23	OK	16332	2026-09-21 18:46	48.83	OK
16333	2026-09-21 18:47	49.45	OK	16334	2026-09-21 18:48	47.60	OK
16335	2026-09-21 18:49	47.26	OK	16336	2026-09-21 18:50	48.87	OK
16337	2026-09-21 18:51	47.42	OK	16338	2026-09-21 18:52	47.12	OK
16339	2026-09-21 18:53	46.03	OK	16340	2026-09-21 18:54	48.07	OK
16341	2026-09-21 18:55	46.23	OK	16342	2026-09-21 18:56	47.31	OK
16343	2026-09-21 18:57	48.26	OK	16344	2026-09-21 18:58	46.92	OK
16345	2026-09-21 18:59	48.38	OK	16346	2026-09-21 19:00	47.35	OK
16347	2026-09-21 19:01	49.60	OK	16348	2026-09-21 19:02	47.10	OK
16349	2026-09-21 19:03	49.48	OK	16350	2026-09-21 19:04	48.07	OK
16351	2026-09-21 19:05	47.95	OK	16352	2026-09-21 19:06	47.66	OK
16353	2026-09-21 19:07	45.56	OK	16354	2026-09-21 19:08	44.89	OK
16355	2026-09-21 19:09	48.00	OK	16356	2026-09-21 19:10	47.19	OK
16357	2026-09-21 19:11	47.93	OK	16358	2026-09-21 19:12	48.36	OK
16359	2026-09-21 19:13	48.24	OK	16360	2026-09-21 19:14	46.85	OK
16361	2026-09-21 19:15	47.37	OK	16362	2026-09-21 19:16	46.39	OK
1636	2026-09-21 19:17	46.41	OK	1636	2026-09-21 19:18	47.11	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
16365	2026-09-21 19:19	47.47	OK	16366	2026-09-21 19:20	48.10	OK
16367	2026-09-21 19:21	47.81	OK	16368	2026-09-21 19:22	48.54	OK
16369	2026-09-21 19:23	44.83	OK	16370	2026-09-21 19:24	47.85	OK
16371	2026-09-21 19:25	47.65	OK	16372	2026-09-21 19:26	45.97	OK
16373	2026-09-21 19:27	47.46	OK	16374	2026-09-21 19:28	48.25	OK
16375	2026-09-21 19:29	47.09	OK	16376	2026-09-21 19:30	48.07	OK
16377	2026-09-21 19:31	47.24	OK	16378	2026-09-21 19:32	45.71	OK
16379	2026-09-21 19:33	47.99	OK	16380	2026-09-21 19:34	46.99	OK
16381	2026-09-21 19:35	47.02	OK	16382	2026-09-21 19:36	47.73	OK
16383	2026-09-21 19:37	46.06	OK	16384	2026-09-21 19:38	46.37	OK
16385	2026-09-21 19:39	48.04	OK	16386	2026-09-21 19:40	46.51	OK
16387	2026-09-21 19:41	47.56	OK	16388	2026-09-21 19:42	46.11	OK
16389	2026-09-21 19:43	46.18	OK	16390	2026-09-21 19:44	46.03	OK
16391	2026-09-21 19:45	45.55	OK	16392	2026-09-21 19:46	47.36	OK
16393	2026-09-21 19:47	45.28	OK	16394	2026-09-21 19:48	47.29	OK
16395	2026-09-21 19:49	46.44	OK	16396	2026-09-21 19:50	46.55	OK
16397	2026-09-21 19:51	46.65	OK	16398	2026-09-21 19:52	44.65	OK
16399	2026-09-21 19:53	46.94	OK	16400	2026-09-21 19:54	46.94	OK
16401	2026-09-21 19:55	45.97	OK	16402	2026-09-21 19:56	48.44	OK
16403	2026-09-21 19:57	44.97	OK	16404	2026-09-21 19:58	45.82	OK
16405	2026-09-21 19:59	45.86	OK	16406	2026-09-21 20:00	44.74	OK
16407	2026-09-21 20:01	47.20	OK	16408	2026-09-21 20:02	46.65	OK
16409	2026-09-21 20:03	44.13	OK	16410	2026-09-21 20:04	45.30	OK
16411	2026-09-21 20:05	47.62	OK	16412	2026-09-21 20:06	48.17	OK
16413	2026-09-21 20:07	44.53	OK	16414	2026-09-21 20:08	46.50	OK
16415	2026-09-21 20:09	47.05	OK	16416	2026-09-21 20:10	45.92	OK
16417	2026-09-21 20:11	44.46	OK	16418	2026-09-21 20:12	46.52	OK
16419	2026-09-21 20:13	45.80	OK	16420	2026-09-21 20:14	45.20	OK
16421	2026-09-21 20:15	46.87	OK	16422	2026-09-21 20:16	47.35	OK
1642	2026-09-21 20:17	45.08	OK	1642	2026-09-21 20:18	47.23	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
16425	2026-09-21 20:19	46.78	OK	16426	2026-09-21 20:20	46.59	OK
16427	2026-09-21 20:21	45.69	OK	16428	2026-09-21 20:22	47.15	OK
16429	2026-09-21 20:23	47.63	OK	16430	2026-09-21 20:24	44.71	OK
16431	2026-09-21 20:25	45.76	OK	16432	2026-09-21 20:26	46.65	OK
16433	2026-09-21 20:27	45.58	OK	16434	2026-09-21 20:28	44.64	OK
16435	2026-09-21 20:29	48.72	OK	16436	2026-09-21 20:30	46.70	OK
16437	2026-09-21 20:31	43.86	OK	16438	2026-09-21 20:32	46.89	OK
16439	2026-09-21 20:33	46.96	OK	16440	2026-09-21 20:34	46.39	OK
16441	2026-09-21 20:35	44.88	OK	16442	2026-09-21 20:36	45.37	OK
16443	2026-09-21 20:37	46.03	OK	16444	2026-09-21 20:38	45.61	OK
16445	2026-09-21 20:39	47.05	OK	16446	2026-09-21 20:40	46.22	OK
16447	2026-09-21 20:41	43.29	OK	16448	2026-09-21 20:42	44.26	OK
16449	2026-09-21 20:43	46.00	OK	16450	2026-09-21 20:44	47.07	OK
16451	2026-09-21 20:45	43.43	OK	16452	2026-09-21 20:46	45.87	OK
16453	2026-09-21 20:47	44.91	OK	16454	2026-09-21 20:48	45.13	OK
16455	2026-09-21 20:49	44.88	OK	16456	2026-09-21 20:50	44.87	OK
16457	2026-09-21 20:51	46.29	OK	16458	2026-09-21 20:52	47.01	OK
16459	2026-09-21 20:53	43.52	OK	16460	2026-09-21 20:54	45.25	OK
16461	2026-09-21 20:55	44.17	OK	16462	2026-09-21 20:56	45.74	OK
16463	2026-09-21 20:57	45.04	OK	16464	2026-09-21 20:58	44.24	OK
16465	2026-09-21 20:59	44.32	OK	16466	2026-09-21 21:00	44.81	OK
16467	2026-09-21 21:01	47.12	OK	16468	2026-09-21 21:02	45.79	OK
16469	2026-09-21 21:03	45.69	OK	16470	2026-09-21 21:04	43.71	OK
16471	2026-09-21 21:05	44.45	OK	16472	2026-09-21 21:06	46.19	OK
16473	2026-09-21 21:07	43.21	OK	16474	2026-09-21 21:08	43.95	OK
16475	2026-09-21 21:09	44.92	OK	16476	2026-09-21 21:10	46.34	OK
16477	2026-09-21 21:11	45.30	OK	16478	2026-09-21 21:12	45.06	OK
16479	2026-09-21 21:13	45.63	OK	16480	2026-09-21 21:14	47.01	OK
16481	2026-09-21 21:15	44.43	OK	16482	2026-09-21 21:16	46.70	OK
1648	2026-09-21 21:17	44.60	OK	1648	2026-09-21 21:18	45.33	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
16485	2026-09-21 21:19	45.74	OK	16486	2026-09-21 21:20	45.74	OK
16487	2026-09-21 21:21	44.70	OK	16488	2026-09-21 21:22	46.14	OK
16489	2026-09-21 21:23	45.66	OK	16490	2026-09-21 21:24	46.02	OK
16491	2026-09-21 21:25	44.03	OK	16492	2026-09-21 21:26	46.00	OK
16493	2026-09-21 21:27	47.70	OK	16494	2026-09-21 21:28	45.81	OK
16495	2026-09-21 21:29	45.00	OK	16496	2026-09-21 21:30	44.82	OK
16497	2026-09-21 21:31	47.09	OK	16498	2026-09-21 21:32	45.43	OK
16499	2026-09-21 21:33	44.65	OK	16500	2026-09-21 21:34	44.86	OK
16501	2026-09-21 21:35	43.07	OK	16502	2026-09-21 21:36	45.39	OK
16503	2026-09-21 21:37	44.31	OK	16504	2026-09-21 21:38	45.69	OK
16505	2026-09-21 21:39	45.22	OK	16506	2026-09-21 21:40	44.88	OK
16507	2026-09-21 21:41	47.21	OK	16508	2026-09-21 21:42	43.51	OK
16509	2026-09-21 21:43	45.49	OK	16510	2026-09-21 21:44	48.32	OK
16511	2026-09-21 21:45	44.13	OK	16512	2026-09-21 21:46	44.86	OK
16513	2026-09-21 21:47	45.96	OK	16514	2026-09-21 21:48	45.61	OK
16515	2026-09-21 21:49	43.93	OK	16516	2026-09-21 21:50	44.44	OK
16517	2026-09-21 21:51	44.31	OK	16518	2026-09-21 21:52	44.39	OK
16519	2026-09-21 21:53	44.79	OK	16520	2026-09-21 21:54	45.49	OK
16521	2026-09-21 21:55	45.22	OK	16522	2026-09-21 21:56	46.78	OK
16523	2026-09-21 21:57	42.90	OK	16524	2026-09-21 21:58	45.19	OK
16525	2026-09-21 21:59	46.29	OK	16526	2026-09-21 22:00	44.69	OK
16527	2026-09-21 22:01	44.50	OK	16528	2026-09-21 22:02	46.20	OK
16529	2026-09-21 22:03	44.47	OK	16530	2026-09-21 22:04	44.44	OK
16531	2026-09-21 22:05	45.22	OK	16532	2026-09-21 22:06	45.42	OK
16533	2026-09-21 22:07	46.63	OK	16534	2026-09-21 22:08	46.21	OK
16535	2026-09-21 22:09	46.56	OK	16536	2026-09-21 22:10	45.00	OK
16537	2026-09-21 22:11	46.01	OK	16538	2026-09-21 22:12	44.17	OK
16539	2026-09-21 22:13	44.98	OK	16540	2026-09-21 22:14	43.93	OK
16541	2026-09-21 22:15	43.97	OK	16542	2026-09-21 22:16	43.92	OK
1654	2026-09-21 22:17	43.72	OK	1654	2026-09-21 22:18	44.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
16545	2026-09-21 22:19	45.84	OK	16546	2026-09-21 22:20	45.59	OK
16547	2026-09-21 22:21	44.25	OK	16548	2026-09-21 22:22	43.98	OK
16549	2026-09-21 22:23	45.94	OK	16550	2026-09-21 22:24	44.85	OK
16551	2026-09-21 22:25	44.51	OK	16552	2026-09-21 22:26	44.23	OK
16553	2026-09-21 22:27	44.48	OK	16554	2026-09-21 22:28	44.19	OK
16555	2026-09-21 22:29	44.81	OK	16556	2026-09-21 22:30	44.97	OK
16557	2026-09-21 22:31	45.80	OK	16558	2026-09-21 22:32	45.12	OK
16559	2026-09-21 22:33	45.89	OK	16560	2026-09-21 22:34	44.21	OK
16561	2026-09-21 22:35	45.67	OK	16562	2026-09-21 22:36	44.44	OK
16563	2026-09-21 22:37	44.83	OK	16564	2026-09-21 22:38	44.64	OK
16565	2026-09-21 22:39	45.53	OK	16566	2026-09-21 22:40	43.95	OK
16567	2026-09-21 22:41	45.30	OK	16568	2026-09-21 22:42	45.72	OK
16569	2026-09-21 22:43	43.31	OK	16570	2026-09-21 22:44	44.75	OK
16571	2026-09-21 22:45	42.73	OK	16572	2026-09-21 22:46	44.66	OK
16573	2026-09-21 22:47	45.59	OK	16574	2026-09-21 22:48	44.95	OK
16575	2026-09-21 22:49	46.17	OK	16576	2026-09-21 22:50	45.19	OK
16577	2026-09-21 22:51	44.96	OK	16578	2026-09-21 22:52	42.40	OK
16579	2026-09-21 22:53	43.79	OK	16580	2026-09-21 22:54	44.23	OK
16581	2026-09-21 22:55	44.87	OK	16582	2026-09-21 22:56	42.82	OK
16583	2026-09-21 22:57	43.06	OK	16584	2026-09-21 22:58	45.29	OK
16585	2026-09-21 22:59	45.31	OK	16586	2026-09-21 23:00	45.04	OK
16587	2026-09-21 23:01	43.64	OK	16588	2026-09-21 23:02	44.54	OK
16589	2026-09-21 23:03	47.35	OK	16590	2026-09-21 23:04	43.15	OK
16591	2026-09-21 23:05	45.83	OK	16592	2026-09-21 23:06	44.41	OK
16593	2026-09-21 23:07	43.64	OK	16594	2026-09-21 23:08	44.24	OK
16595	2026-09-21 23:09	44.23	OK	16596	2026-09-21 23:10	43.59	OK
16597	2026-09-21 23:11	46.40	OK	16598	2026-09-21 23:12	45.78	OK
16599	2026-09-21 23:13	44.11	OK	16600	2026-09-21 23:14	42.81	OK
16601	2026-09-21 23:15	43.75	OK	16602	2026-09-21 23:16	44.69	OK
1660	2026-09-21 23:17	44.34	OK	1660	2026-09-21 23:18	43.68	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
16605	2026-09-21 23:19	45.98	OK	16606	2026-09-21 23:20	44.46	OK
16607	2026-09-21 23:21	43.85	OK	16608	2026-09-21 23:22	43.63	OK
16609	2026-09-21 23:23	46.11	OK	16610	2026-09-21 23:24	45.29	OK
16611	2026-09-21 23:25	42.38	OK	16612	2026-09-21 23:26	44.35	OK
16613	2026-09-21 23:27	46.46	OK	16614	2026-09-21 23:28	44.68	OK
16615	2026-09-21 23:29	44.67	OK	16616	2026-09-21 23:30	43.64	OK
16617	2026-09-21 23:31	43.63	OK	16618	2026-09-21 23:32	43.47	OK
16619	2026-09-21 23:33	45.17	OK	16620	2026-09-21 23:34	42.74	OK
16621	2026-09-21 23:35	47.15	OK	16622	2026-09-21 23:36	44.14	OK
16623	2026-09-21 23:37	45.54	OK	16624	2026-09-21 23:38	44.96	OK
16625	2026-09-21 23:39	42.89	OK	16626	2026-09-21 23:40	43.69	OK
16627	2026-09-21 23:41	43.17	OK	16628	2026-09-21 23:42	43.89	OK
16629	2026-09-21 23:43	46.44	OK	16630	2026-09-21 23:44	45.39	OK
16631	2026-09-21 23:45	43.58	OK	16632	2026-09-21 23:46	43.62	OK
16633	2026-09-21 23:47	44.83	OK	16634	2026-09-21 23:48	44.11	OK
16635	2026-09-21 23:49	45.46	OK	16636	2026-09-21 23:50	45.56	OK
16637	2026-09-21 23:51	45.32	OK	16638	2026-09-21 23:52	44.34	OK
16639	2026-09-21 23:53	44.16	OK	16640	2026-09-21 23:54	42.25	OK
16641	2026-09-21 23:55	44.87	OK	16642	2026-09-21 23:56	43.84	OK
16643	2026-09-21 23:57	44.61	OK	16644	2026-09-21 23:58	45.81	OK
16645	2026-09-21 23:59	44.89	OK	16646	2026-09-22 00:00	42.91	OK
16647	2026-09-22 00:01	44.21	OK	16648	2026-09-22 00:02	43.57	OK
16649	2026-09-22 00:03	45.45	OK	16650	2026-09-22 00:04	45.29	OK
16651	2026-09-22 00:05	42.73	OK	16652	2026-09-22 00:06	46.16	OK
16653	2026-09-22 00:07	44.91	OK	16654	2026-09-22 00:08	45.38	OK
16655	2026-09-22 00:09	44.26	OK	16656	2026-09-22 00:10	46.15	OK
16657	2026-09-22 00:11	43.81	OK	16658	2026-09-22 00:12	43.07	OK
16659	2026-09-22 00:13	45.65	OK	16660	2026-09-22 00:14	42.47	OK
16661	2026-09-22 00:15	47.60	OK	16662	2026-09-22 00:16	46.66	OK
1666	2026-09-22 00:17	44.54	OK	1666	2026-09-22 00:18	45.93	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
16665	2026-09-22 00:19	45.35	OK	16666	2026-09-22 00:20	42.79	OK
16667	2026-09-22 00:21	44.67	OK	16668	2026-09-22 00:22	45.43	OK
16669	2026-09-22 00:23	45.08	OK	16670	2026-09-22 00:24	46.23	OK
16671	2026-09-22 00:25	43.95	OK	16672	2026-09-22 00:26	45.96	OK
16673	2026-09-22 00:27	44.76	OK	16674	2026-09-22 00:28	45.33	OK
16675	2026-09-22 00:29	44.39	OK	16676	2026-09-22 00:30	45.28	OK
16677	2026-09-22 00:31	46.80	OK	16678	2026-09-22 00:32	44.17	OK
16679	2026-09-22 00:33	45.05	OK	16680	2026-09-22 00:34	44.72	OK
16681	2026-09-22 00:35	44.71	OK	16682	2026-09-22 00:36	44.30	OK
16683	2026-09-22 00:37	44.12	OK	16684	2026-09-22 00:38	45.18	OK
16685	2026-09-22 00:39	44.57	OK	16686	2026-09-22 00:40	47.10	OK
16687	2026-09-22 00:41	45.54	OK	16688	2026-09-22 00:42	45.75	OK
16689	2026-09-22 00:43	45.85	OK	16690	2026-09-22 00:44	45.01	OK
16691	2026-09-22 00:45	46.22	OK	16692	2026-09-22 00:46	43.59	OK
16693	2026-09-22 00:47	43.62	OK	16694	2026-09-22 00:48	45.02	OK
16695	2026-09-22 00:49	45.10	OK	16696	2026-09-22 00:50	43.94	OK
16697	2026-09-22 00:51	44.36	OK	16698	2026-09-22 00:52	44.06	OK
16699	2026-09-22 00:53	45.21	OK	16700	2026-09-22 00:54	45.03	OK
16701	2026-09-22 00:55	42.80	OK	16702	2026-09-22 00:56	44.35	OK
16703	2026-09-22 00:57	45.69	OK	16704	2026-09-22 00:58	46.66	OK
16705	2026-09-22 00:59	45.02	OK	16706	2026-09-22 01:00	42.88	OK
16707	2026-09-22 01:01	44.39	OK	16708	2026-09-22 01:02	43.75	OK
16709	2026-09-22 01:03	43.69	OK	16710	2026-09-22 01:04	43.15	OK
16711	2026-09-22 01:05	44.21	OK	16712	2026-09-22 01:06	45.93	OK
16713	2026-09-22 01:07	42.81	OK	16714	2026-09-22 01:08	43.95	OK
16715	2026-09-22 01:09	45.94	OK	16716	2026-09-22 01:10	43.13	OK
16717	2026-09-22 01:11	44.37	OK	16718	2026-09-22 01:12	43.43	OK
16719	2026-09-22 01:13	46.60	OK	16720	2026-09-22 01:14	44.20	OK
16721	2026-09-22 01:15	44.60	OK	16722	2026-09-22 01:16	47.79	OK
1672	2026-09-22 01:17	47.59	OK	1672	2026-09-22 01:18	44.86	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
16725	2026-09-22 01:19	46.16	OK	16726	2026-09-22 01:20	46.01	OK
16727	2026-09-22 01:21	44.85	OK	16728	2026-09-22 01:22	47.70	OK
16729	2026-09-22 01:23	46.17	OK	16730	2026-09-22 01:24	45.24	OK
16731	2026-09-22 01:25	45.29	OK	16732	2026-09-22 01:26	44.66	OK
16733	2026-09-22 01:27	45.73	OK	16734	2026-09-22 01:28	46.29	OK
16735	2026-09-22 01:29	45.41	OK	16736	2026-09-22 01:30	45.02	OK
16737	2026-09-22 01:31	44.51	OK	16738	2026-09-22 01:32	43.97	OK
16739	2026-09-22 01:33	45.17	OK	16740	2026-09-22 01:34	45.24	OK
16741	2026-09-22 01:35	46.92	OK	16742	2026-09-22 01:36	45.54	OK
16743	2026-09-22 01:37	46.99	OK	16744	2026-09-22 01:38	44.18	OK
16745	2026-09-22 01:39	48.00	OK	16746	2026-09-22 01:40	45.89	OK
16747	2026-09-22 01:41	44.83	OK	16748	2026-09-22 01:42	46.34	OK
16749	2026-09-22 01:43	47.17	OK	16750	2026-09-22 01:44	44.09	OK
16751	2026-09-22 01:45	43.79	OK	16752	2026-09-22 01:46	46.29	OK
16753	2026-09-22 01:47	44.16	OK	16754	2026-09-22 01:48	46.14	OK
16755	2026-09-22 01:49	46.57	OK	16756	2026-09-22 01:50	48.18	OK
16757	2026-09-22 01:51	44.63	OK	16758	2026-09-22 01:52	45.58	OK
16759	2026-09-22 01:53	44.91	OK	16760	2026-09-22 01:54	45.57	OK
16761	2026-09-22 01:55	45.18	OK	16762	2026-09-22 01:56	47.22	OK
16763	2026-09-22 01:57	44.78	OK	16764	2026-09-22 01:58	44.88	OK
16765	2026-09-22 01:59	44.54	OK	16766	2026-09-22 02:00	46.67	OK
16767	2026-09-22 02:01	46.90	OK	16768	2026-09-22 02:02	44.67	OK
16769	2026-09-22 02:03	47.71	OK	16770	2026-09-22 02:04	47.85	OK
16771	2026-09-22 02:05	45.36	OK	16772	2026-09-22 02:06	44.74	OK
16773	2026-09-22 02:07	45.10	OK	16774	2026-09-22 02:08	46.70	OK
16775	2026-09-22 02:09	48.22	OK	16776	2026-09-22 02:10	43.25	OK
16777	2026-09-22 02:11	46.30	OK	16778	2026-09-22 02:12	45.62	OK
16779	2026-09-22 02:13	47.04	OK	16780	2026-09-22 02:14	45.18	OK
16781	2026-09-22 02:15	44.63	OK	16782	2026-09-22 02:16	44.43	OK
1678	2026-09-22 02:17	45.68	OK	1678	2026-09-22 02:18	46.27	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
16785	2026-09-22 02:19	45.53	OK	16786	2026-09-22 02:20	44.47	OK
16787	2026-09-22 02:21	45.49	OK	16788	2026-09-22 02:22	47.28	OK
16789	2026-09-22 02:23	46.65	OK	16790	2026-09-22 02:24	48.37	OK
16791	2026-09-22 02:25	46.39	OK	16792	2026-09-22 02:26	44.51	OK
16793	2026-09-22 02:27	44.78	OK	16794	2026-09-22 02:28	46.03	OK
16795	2026-09-22 02:29	46.24	OK	16796	2026-09-22 02:30	45.09	OK
16797	2026-09-22 02:31	45.89	OK	16798	2026-09-22 02:32	47.14	OK
16799	2026-09-22 02:33	45.45	OK	16800	2026-09-22 02:34	45.64	OK
16801	2026-09-22 02:35	46.19	OK	16802	2026-09-22 02:36	45.07	OK
16803	2026-09-22 02:37	45.01	OK	16804	2026-09-22 02:38	47.18	OK
16805	2026-09-22 02:39	46.49	OK	16806	2026-09-22 02:40	47.53	OK
16807	2026-09-22 02:41	46.42	OK	16808	2026-09-22 02:42	46.80	OK
16809	2026-09-22 02:43	45.60	OK	16810	2026-09-22 02:44	45.73	OK
16811	2026-09-22 02:45	46.48	OK	16812	2026-09-22 02:46	47.18	OK
16813	2026-09-22 02:47	48.00	OK	16814	2026-09-22 02:48	48.43	OK
16815	2026-09-22 02:49	44.97	OK	16816	2026-09-22 02:50	47.67	OK
16817	2026-09-22 02:51	44.28	OK	16818	2026-09-22 02:52	45.60	OK
16819	2026-09-22 02:53	48.19	OK	16820	2026-09-22 02:54	45.49	OK
16821	2026-09-22 02:55	45.89	OK	16822	2026-09-22 02:56	46.05	OK
16823	2026-09-22 02:57	45.36	OK	16824	2026-09-22 02:58	46.54	OK
16825	2026-09-22 02:59	45.04	OK	16826	2026-09-22 03:00	46.85	OK
16827	2026-09-22 03:01	46.68	OK	16828	2026-09-22 03:02	44.99	OK
16829	2026-09-22 03:03	46.66	OK	16830	2026-09-22 03:04	45.07	OK
16831	2026-09-22 03:05	47.57	OK	16832	2026-09-22 03:06	45.27	OK
16833	2026-09-22 03:07	46.46	OK	16834	2026-09-22 03:08	47.93	OK
16835	2026-09-22 03:09	46.47	OK	16836	2026-09-22 03:10	45.42	OK
16837	2026-09-22 03:11	48.06	OK	16838	2026-09-22 03:12	46.83	OK
16839	2026-09-22 03:13	47.82	OK	16840	2026-09-22 03:14	48.64	OK
16841	2026-09-22 03:15	47.63	OK	16842	2026-09-22 03:16	47.21	OK
1684	2026-09-22 03:17	47.55	OK	1684	2026-09-22 03:18	47.80	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
16845	2026-09-22 03:19	49.35	OK	16846	2026-09-22 03:20	47.98	OK
16847	2026-09-22 03:21	49.26	OK	16848	2026-09-22 03:22	46.29	OK
16849	2026-09-22 03:23	48.48	OK	16850	2026-09-22 03:24	46.19	OK
16851	2026-09-22 03:25	48.26	OK	16852	2026-09-22 03:26	47.31	OK
16853	2026-09-22 03:27	45.39	OK	16854	2026-09-22 03:28	45.69	OK
16855	2026-09-22 03:29	46.17	OK	16856	2026-09-22 03:30	46.82	OK
16857	2026-09-22 03:31	45.63	OK	16858	2026-09-22 03:32	46.62	OK
16859	2026-09-22 03:33	47.29	OK	16860	2026-09-22 03:34	45.84	OK
16861	2026-09-22 03:35	45.44	OK	16862	2026-09-22 03:36	47.74	OK
16863	2026-09-22 03:37	46.67	OK	16864	2026-09-22 03:38	45.41	OK
16865	2026-09-22 03:39	48.28	OK	16866	2026-09-22 03:40	47.01	OK
16867	2026-09-22 03:41	48.22	OK	16868	2026-09-22 03:42	48.68	OK
16869	2026-09-22 03:43	48.05	OK	16870	2026-09-22 03:44	46.97	OK
16871	2026-09-22 03:45	47.99	OK	16872	2026-09-22 03:46	48.33	OK
16873	2026-09-22 03:47	47.79	OK	16874	2026-09-22 03:48	50.30	OK
16875	2026-09-22 03:49	47.88	OK	16876	2026-09-22 03:50	49.09	OK
16877	2026-09-22 03:51	47.94	OK	16878	2026-09-22 03:52	46.87	OK
16879	2026-09-22 03:53	48.38	OK	16880	2026-09-22 03:54	48.47	OK
16881	2026-09-22 03:55	47.81	OK	16882	2026-09-22 03:56	46.26	OK
16883	2026-09-22 03:57	47.91	OK	16884	2026-09-22 03:58	47.70	OK
16885	2026-09-22 03:59	47.82	OK	16886	2026-09-22 04:00	46.99	OK
16887	2026-09-22 04:01	47.81	OK	16888	2026-09-22 04:02	47.03	OK
16889	2026-09-22 04:03	46.74	OK	16890	2026-09-22 04:04	48.99	OK
16891	2026-09-22 04:05	47.04	OK	16892	2026-09-22 04:06	48.24	OK
16893	2026-09-22 04:07	48.94	OK	16894	2026-09-22 04:08	47.23	OK
16895	2026-09-22 04:09	49.29	OK	16896	2026-09-22 04:10	48.24	OK
16897	2026-09-22 04:11	48.30	OK	16898	2026-09-22 04:12	46.41	OK
16899	2026-09-22 04:13	49.22	OK	16900	2026-09-22 04:14	49.72	OK
16901	2026-09-22 04:15	46.53	OK	16902	2026-09-22 04:16	45.65	OK
1690	2026-09-22 04:17	48.56	OK	1690	2026-09-22 04:18	47.79	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
16905	2026-09-22 04:19	47.44	OK	16906	2026-09-22 04:20	49.49	OK
16907	2026-09-22 04:21	47.31	OK	16908	2026-09-22 04:22	48.82	OK
16909	2026-09-22 04:23	47.71	OK	16910	2026-09-22 04:24	47.78	OK
16911	2026-09-22 04:25	48.15	OK	16912	2026-09-22 04:26	48.45	OK
16913	2026-09-22 04:27	46.94	OK	16914	2026-09-22 04:28	49.04	OK
16915	2026-09-22 04:29	48.83	OK	16916	2026-09-22 04:30	48.50	OK
16917	2026-09-22 04:31	49.12	OK	16918	2026-09-22 04:32	48.46	OK
16919	2026-09-22 04:33	48.24	OK	16920	2026-09-22 04:34	49.13	OK
16921	2026-09-22 04:35	47.67	OK	16922	2026-09-22 04:36	47.44	OK
16923	2026-09-22 04:37	48.28	OK	16924	2026-09-22 04:38	50.10	OK
16925	2026-09-22 04:39	48.30	OK	16926	2026-09-22 04:40	47.29	OK
16927	2026-09-22 04:41	48.18	OK	16928	2026-09-22 04:42	47.68	OK
16929	2026-09-22 04:43	46.73	OK	16930	2026-09-22 04:44	49.62	OK
16931	2026-09-22 04:45	49.63	OK	16932	2026-09-22 04:46	47.76	OK
16933	2026-09-22 04:47	49.12	OK	16934	2026-09-22 04:48	48.38	OK
16935	2026-09-22 04:49	48.17	OK	16936	2026-09-22 04:50	49.68	OK
16937	2026-09-22 04:51	49.76	OK	16938	2026-09-22 04:52	48.86	OK
16939	2026-09-22 04:53	49.06	OK	16940	2026-09-22 04:54	49.26	OK
16941	2026-09-22 04:55	49.10	OK	16942	2026-09-22 04:56	48.47	OK
16943	2026-09-22 04:57	49.59	OK	16944	2026-09-22 04:58	47.98	OK
16945	2026-09-22 04:59	47.85	OK	16946	2026-09-22 05:00	50.70	OK
16947	2026-09-22 05:01	48.52	OK	16948	2026-09-22 05:02	49.28	OK
16949	2026-09-22 05:03	47.80	OK	16950	2026-09-22 05:04	48.16	OK
16951	2026-09-22 05:05	47.93	OK	16952	2026-09-22 05:06	47.91	OK
16953	2026-09-22 05:07	49.25	OK	16954	2026-09-22 05:08	51.88	OK
16955	2026-09-22 05:09	46.74	OK	16956	2026-09-22 05:10	49.30	OK
16957	2026-09-22 05:11	48.98	OK	16958	2026-09-22 05:12	47.68	OK
16959	2026-09-22 05:13	49.89	OK	16960	2026-09-22 05:14	50.16	OK
16961	2026-09-22 05:15	47.85	OK	16962	2026-09-22 05:16	50.18	OK
1696	2026-09-22 05:17	49.28	OK	1696	2026-09-22 05:18	50.20	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
16965	2026-09-22 05:19	50.85	OK	16966	2026-09-22 05:20	49.20	OK
16967	2026-09-22 05:21	50.28	OK	16968	2026-09-22 05:22	48.12	OK
16969	2026-09-22 05:23	49.61	OK	16970	2026-09-22 05:24	49.92	OK
16971	2026-09-22 05:25	51.19	OK	16972	2026-09-22 05:26	50.33	OK
16973	2026-09-22 05:27	50.57	OK	16974	2026-09-22 05:28	48.29	OK
16975	2026-09-22 05:29	49.70	OK	16976	2026-09-22 05:30	51.17	OK
16977	2026-09-22 05:31	49.96	OK	16978	2026-09-22 05:32	50.11	OK
16979	2026-09-22 05:33	48.37	OK	16980	2026-09-22 05:34	48.78	OK
16981	2026-09-22 05:35	50.65	OK	16982	2026-09-22 05:36	49.45	OK
16983	2026-09-22 05:37	49.72	OK	16984	2026-09-22 05:38	50.47	OK
16985	2026-09-22 05:39	50.30	OK	16986	2026-09-22 05:40	50.91	OK
16987	2026-09-22 05:41	49.05	OK	16988	2026-09-22 05:42	49.36	OK
16989	2026-09-22 05:43	49.97	OK	16990	2026-09-22 05:44	51.14	OK
16991	2026-09-22 05:45	48.71	OK	16992	2026-09-22 05:46	50.86	OK
16993	2026-09-22 05:47	48.49	OK	16994	2026-09-22 05:48	48.95	OK
16995	2026-09-22 05:49	48.50	OK	16996	2026-09-22 05:50	50.21	OK
16997	2026-09-22 05:51	49.91	OK	16998	2026-09-22 05:52	49.15	OK
16999	2026-09-22 05:53	50.78	OK	17000	2026-09-22 05:54	51.99	OK
17001	2026-09-22 05:55	48.50	OK	17002	2026-09-22 05:56	50.21	OK
17003	2026-09-22 05:57	51.09	OK	17004	2026-09-22 05:58	50.35	OK
17005	2026-09-22 05:59	49.96	OK	17006	2026-09-22 06:00	51.17	OK
17007	2026-09-22 06:01	50.08	OK	17008	2026-09-22 06:02	49.32	OK
17009	2026-09-22 06:03	48.96	OK	17010	2026-09-22 06:04	49.60	OK
17011	2026-09-22 06:05	50.62	OK	17012	2026-09-22 06:06	50.90	OK
17013	2026-09-22 06:07	49.59	OK	17014	2026-09-22 06:08	48.97	OK
17015	2026-09-22 06:09	48.94	OK	17016	2026-09-22 06:10	52.60	OK
17017	2026-09-22 06:11	49.21	OK	17018	2026-09-22 06:12	49.54	OK
17019	2026-09-22 06:13	48.74	OK	17020	2026-09-22 06:14	50.01	OK
17021	2026-09-22 06:15	48.26	OK	17022	2026-09-22 06:16	48.55	OK
1702	2026-09-22 06:17	51.23	OK	1702	2026-09-22 06:18	49.22	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
17025	2026-09-22 06:19	51.17	OK	17026	2026-09-22 06:20	50.72	OK
17027	2026-09-22 06:21	50.58	OK	17028	2026-09-22 06:22	50.54	OK
17029	2026-09-22 06:23	52.22	OK	17030	2026-09-22 06:24	50.53	OK
17031	2026-09-22 06:25	52.87	OK	17032	2026-09-22 06:26	47.99	OK
17033	2026-09-22 06:27	49.73	OK	17034	2026-09-22 06:28	50.69	OK
17035	2026-09-22 06:29	49.34	OK	17036	2026-09-22 06:30	50.67	OK
17037	2026-09-22 06:31	51.28	OK	17038	2026-09-22 06:32	51.47	OK
17039	2026-09-22 06:33	49.54	OK	17040	2026-09-22 06:34	50.86	OK
17041	2026-09-22 06:35	52.14	OK	17042	2026-09-22 06:36	52.77	OK
17043	2026-09-22 06:37	51.25	OK	17044	2026-09-22 06:38	52.08	OK
17045	2026-09-22 06:39	49.31	OK	17046	2026-09-22 06:40	49.57	OK
17047	2026-09-22 06:41	51.22	OK	17048	2026-09-22 06:42	49.84	OK
17049	2026-09-22 06:43	51.68	OK	17050	2026-09-22 06:44	51.03	OK
17051	2026-09-22 06:45	50.42	OK	17052	2026-09-22 06:46	51.90	OK
17053	2026-09-22 06:47	51.07	OK	17054	2026-09-22 06:48	49.75	OK
17055	2026-09-22 06:49	51.94	OK	17056	2026-09-22 06:50	50.10	OK
17057	2026-09-22 06:51	49.83	OK	17058	2026-09-22 06:52	49.78	OK
17059	2026-09-22 06:53	51.25	OK	17060	2026-09-22 06:54	50.71	OK
17061	2026-09-22 06:55	50.23	OK	17062	2026-09-22 06:56	51.05	OK
17063	2026-09-22 06:57	50.06	OK	17064	2026-09-22 06:58	50.48	OK
17065	2026-09-22 06:59	51.97	OK	17066	2026-09-22 07:00	51.40	OK
17067	2026-09-22 07:01	50.18	OK	17068	2026-09-22 07:02	51.35	OK
17069	2026-09-22 07:03	50.32	OK	17070	2026-09-22 07:04	50.82	OK
17071	2026-09-22 07:05	50.71	OK	17072	2026-09-22 07:06	50.69	OK
17073	2026-09-22 07:07	51.62	OK	17074	2026-09-22 07:08	52.42	OK
17075	2026-09-22 07:09	52.09	OK	17076	2026-09-22 07:10	50.17	OK
17077	2026-09-22 07:11	50.86	OK	17078	2026-09-22 07:12	51.72	OK
17079	2026-09-22 07:13	51.33	OK	17080	2026-09-22 07:14	50.68	OK
17081	2026-09-22 07:15	50.96	OK	17082	2026-09-22 07:16	51.66	OK
1708	2026-09-22 07:17	52.49	OK	1708	2026-09-22 07:18	53.48	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
17085	2026-09-22 07:19	50.92	OK	17086	2026-09-22 07:20	52.05	OK
17087	2026-09-22 07:21	52.36	OK	17088	2026-09-22 07:22	51.69	OK
17089	2026-09-22 07:23	50.78	OK	17090	2026-09-22 07:24	51.38	OK
17091	2026-09-22 07:25	50.66	OK	17092	2026-09-22 07:26	50.42	OK
17093	2026-09-22 07:27	50.59	OK	17094	2026-09-22 07:28	50.73	OK
17095	2026-09-22 07:29	53.50	OK	17096	2026-09-22 07:30	52.46	OK
17097	2026-09-22 07:31	51.93	OK	17098	2026-09-22 07:32	52.32	OK
17099	2026-09-22 07:33	51.96	OK	17100	2026-09-22 07:34	50.38	OK
17101	2026-09-22 07:35	54.40	OK	17102	2026-09-22 07:36	51.28	OK
17103	2026-09-22 07:37	52.23	OK	17104	2026-09-22 07:38	50.56	OK
17105	2026-09-22 07:39	51.32	OK	17106	2026-09-22 07:40	50.89	OK
17107	2026-09-22 07:41	50.98	OK	17108	2026-09-22 07:42	52.40	OK
17109	2026-09-22 07:43	53.21	OK	17110	2026-09-22 07:44	52.43	OK
17111	2026-09-22 07:45	49.77	OK	17112	2026-09-22 07:46	53.03	OK
17113	2026-09-22 07:47	51.19	OK	17114	2026-09-22 07:48	54.99	OK
17115	2026-09-22 07:49	52.66	OK	17116	2026-09-22 07:50	52.40	OK
17117	2026-09-22 07:51	51.12	OK	17118	2026-09-22 07:52	52.15	OK
17119	2026-09-22 07:53	52.46	OK	17120	2026-09-22 07:54	51.92	OK
17121	2026-09-22 07:55	52.17	OK	17122	2026-09-22 07:56	51.89	OK
17123	2026-09-22 07:57	52.42	OK	17124	2026-09-22 07:58	51.92	OK
17125	2026-09-22 07:59	51.52	OK	17126	2026-09-22 08:00	52.32	OK
17127	2026-09-22 08:01	51.86	OK	17128	2026-09-22 08:02	54.19	OK
17129	2026-09-22 08:03	51.47	OK	17130	2026-09-22 08:04	50.09	OK
17131	2026-09-22 08:05	51.91	OK	17132	2026-09-22 08:06	53.58	OK
17133	2026-09-22 08:07	53.54	OK	17134	2026-09-22 08:08	51.32	OK
17135	2026-09-22 08:09	51.22	OK	17136	2026-09-22 08:10	52.15	OK
17137	2026-09-22 08:11	51.75	OK	17138	2026-09-22 08:12	52.37	OK
17139	2026-09-22 08:13	54.01	OK	17140	2026-09-22 08:14	51.22	OK
17141	2026-09-22 08:15	51.70	OK	17142	2026-09-22 08:16	52.06	OK
1714	2026-09-22 08:17	53.32	OK	1714	2026-09-22 08:18	52.44	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
17145	2026-09-22 08:19	52.45	OK	17146	2026-09-22 08:20	51.65	OK
17147	2026-09-22 08:21	51.56	OK	17148	2026-09-22 08:22	52.39	OK
17149	2026-09-22 08:23	52.85	OK	17150	2026-09-22 08:24	53.23	OK
17151	2026-09-22 08:25	52.55	OK	17152	2026-09-22 08:26	52.02	OK
17153	2026-09-22 08:27	52.47	OK	17154	2026-09-22 08:28	52.21	OK
17155	2026-09-22 08:29	50.40	OK	17156	2026-09-22 08:30	51.50	OK
17157	2026-09-22 08:31	52.68	OK	17158	2026-09-22 08:32	52.98	OK
17159	2026-09-22 08:33	54.14	OK	17160	2026-09-22 08:34	53.51	OK
17161	2026-09-22 08:35	54.85	OK	17162	2026-09-22 08:36	51.99	OK
17163	2026-09-22 08:37	53.77	OK	17164	2026-09-22 08:38	53.89	OK
17165	2026-09-22 08:39	53.10	OK	17166	2026-09-22 08:40	51.63	OK
17167	2026-09-22 08:41	52.72	OK	17168	2026-09-22 08:42	50.85	OK
17169	2026-09-22 08:43	53.65	OK	17170	2026-09-22 08:44	52.73	OK
17171	2026-09-22 08:45	52.53	OK	17172	2026-09-22 08:46	52.54	OK
17173	2026-09-22 08:47	52.15	OK	17174	2026-09-22 08:48	52.08	OK
17175	2026-09-22 08:49	53.09	OK	17176	2026-09-22 08:50	52.98	OK
17177	2026-09-22 08:51	55.77	OK	17178	2026-09-22 08:52	55.14	OK
17179	2026-09-22 08:53	54.83	OK	17180	2026-09-22 08:54	52.63	OK
17181	2026-09-22 08:55	53.96	OK	17182	2026-09-22 08:56	52.46	OK
17183	2026-09-22 08:57	54.79	OK	17184	2026-09-22 08:58	53.17	OK
17185	2026-09-22 08:59	52.76	OK	17186	2026-09-22 09:00	52.26	OK
17187	2026-09-22 09:01	52.64	OK	17188	2026-09-22 09:02	53.00	OK
17189	2026-09-22 09:03	55.81	OK	17190	2026-09-22 09:04	51.63	OK
17191	2026-09-22 09:05	52.16	OK	17192	2026-09-22 09:06	52.69	OK
17193	2026-09-22 09:07	52.81	OK	17194	2026-09-22 09:08	53.18	OK
17195	2026-09-22 09:09	53.16	OK	17196	2026-09-22 09:10	54.92	OK
17197	2026-09-22 09:11	52.83	OK	17198	2026-09-22 09:12	52.97	OK
17199	2026-09-22 09:13	55.06	OK	17200	2026-09-22 09:14	53.28	OK
17201	2026-09-22 09:15	52.60	OK	17202	2026-09-22 09:16	54.68	OK
1720	2026-09-22 09:17	51.51	OK	1720	2026-09-22 09:18	53.83	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
17205	2026-09-22 09:19	53.42	OK	17206	2026-09-22 09:20	53.99	OK
17207	2026-09-22 09:21	52.06	OK	17208	2026-09-22 09:22	53.80	OK
17209	2026-09-22 09:23	55.89	OK	17210	2026-09-22 09:24	53.05	OK
17211	2026-09-22 09:25	52.42	OK	17212	2026-09-22 09:26	55.19	OK
17213	2026-09-22 09:27	54.91	OK	17214	2026-09-22 09:28	53.60	OK
17215	2026-09-22 09:29	52.00	OK	17216	2026-09-22 09:30	51.76	OK
17217	2026-09-22 09:31	54.76	OK	17218	2026-09-22 09:32	53.06	OK
17219	2026-09-22 09:33	54.60	OK	17220	2026-09-22 09:34	53.99	OK
17221	2026-09-22 09:35	53.33	OK	17222	2026-09-22 09:36	55.73	OK
17223	2026-09-22 09:37	55.00	OK	17224	2026-09-22 09:38	53.36	OK
17225	2026-09-22 09:39	52.79	OK	17226	2026-09-22 09:40	53.54	OK
17227	2026-09-22 09:41	54.08	OK	17228	2026-09-22 09:42	51.73	OK
17229	2026-09-22 09:43	53.65	OK	17230	2026-09-22 09:44	53.86	OK
17231	2026-09-22 09:45	54.17	OK	17232	2026-09-22 09:46	52.85	OK
17233	2026-09-22 09:47	54.31	OK	17234	2026-09-22 09:48	52.67	OK
17235	2026-09-22 09:49	53.34	OK	17236	2026-09-22 09:50	52.26	OK
17237	2026-09-22 09:51	53.45	OK	17238	2026-09-22 09:52	52.59	OK
17239	2026-09-22 09:53	53.75	OK	17240	2026-09-22 09:54	53.09	OK
17241	2026-09-22 09:55	52.90	OK	17242	2026-09-22 09:56	54.44	OK
17243	2026-09-22 09:57	53.30	OK	17244	2026-09-22 09:58	55.68	OK
17245	2026-09-22 09:59	53.85	OK	17246	2026-09-22 10:00	54.02	OK
17247	2026-09-22 10:01	53.51	OK	17248	2026-09-22 10:02	53.83	OK
17249	2026-09-22 10:03	54.79	OK	17250	2026-09-22 10:04	52.39	OK
17251	2026-09-22 10:05	53.03	OK	17252	2026-09-22 10:06	54.68	OK
17253	2026-09-22 10:07	53.78	OK	17254	2026-09-22 10:08	54.58	OK
17255	2026-09-22 10:09	54.62	OK	17256	2026-09-22 10:10	53.91	OK
17257	2026-09-22 10:11	53.41	OK	17258	2026-09-22 10:12	53.69	OK
17259	2026-09-22 10:13	54.54	OK	17260	2026-09-22 10:14	52.95	OK
17261	2026-09-22 10:15	52.78	OK	17262	2026-09-22 10:16	54.76	OK
1726	2026-09-22 10:17	52.14	OK	1726	2026-09-22 10:18	53.11	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
17265	2026-09-22 10:19	53.08	OK	17266	2026-09-22 10:20	55.24	OK
17267	2026-09-22 10:21	52.34	OK	17268	2026-09-22 10:22	54.25	OK
17269	2026-09-22 10:23	52.78	OK	17270	2026-09-22 10:24	53.44	OK
17271	2026-09-22 10:25	52.92	OK	17272	2026-09-22 10:26	52.09	OK
17273	2026-09-22 10:27	52.97	OK	17274	2026-09-22 10:28	54.19	OK
17275	2026-09-22 10:29	53.85	OK	17276	2026-09-22 10:30	54.43	OK
17277	2026-09-22 10:31	51.97	OK	17278	2026-09-22 10:32	54.66	OK
17279	2026-09-22 10:33	53.70	OK	17280	2026-09-22 10:34	52.79	OK
17281	2026-09-22 10:35	54.80	OK	17282	2026-09-22 10:36	53.76	OK
17283	2026-09-22 10:37	54.75	OK	17284	2026-09-22 10:38	55.04	OK
17285	2026-09-22 10:39	54.34	OK	17286	2026-09-22 10:40	55.05	OK
17287	2026-09-22 10:41	52.35	OK	17288	2026-09-22 10:42	53.60	OK
17289	2026-09-22 10:43	54.68	OK	17290	2026-09-22 10:44	54.18	OK
17291	2026-09-22 10:45	55.41	OK	17292	2026-09-22 10:46	52.88	OK
17293	2026-09-22 10:47	54.06	OK	17294	2026-09-22 10:48	54.71	OK
17295	2026-09-22 10:49	55.65	OK	17296	2026-09-22 10:50	54.51	OK
17297	2026-09-22 10:51	54.92	OK	17298	2026-09-22 10:52	55.15	OK
17299	2026-09-22 10:53	54.32	OK	17300	2026-09-22 10:54	56.00	OK
17301	2026-09-22 10:55	54.28	OK	17302	2026-09-22 10:56	52.79	OK
17303	2026-09-22 10:57	54.57	OK	17304	2026-09-22 10:58	53.97	OK
17305	2026-09-22 10:59	53.39	OK	17306	2026-09-22 11:00	52.85	OK
17307	2026-09-22 11:01	52.83	OK	17308	2026-09-22 11:02	53.44	OK
17309	2026-09-22 11:03	54.47	OK	17310	2026-09-22 11:04	55.96	OK
17311	2026-09-22 11:05	53.68	OK	17312	2026-09-22 11:06	54.44	OK
17313	2026-09-22 11:07	51.46	OK	17314	2026-09-22 11:08	55.91	OK
17315	2026-09-22 11:09	52.97	OK	17316	2026-09-22 11:10	53.60	OK
17317	2026-09-22 11:11	55.19	OK	17318	2026-09-22 11:12	53.35	OK
17319	2026-09-22 11:13	54.45	OK	17320	2026-09-22 11:14	52.96	OK
17321	2026-09-22 11:15	55.31	OK	17322	2026-09-22 11:16	54.66	OK
1732	2026-09-22 11:17	54.55	OK	1732	2026-09-22 11:18	54.65	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
17325	2026-09-22 11:19	54.57	OK	17326	2026-09-22 11:20	52.32	OK
17327	2026-09-22 11:21	53.32	OK	17328	2026-09-22 11:22	54.72	OK
17329	2026-09-22 11:23	53.28	OK	17330	2026-09-22 11:24	53.53	OK
17331	2026-09-22 11:25	53.67	OK	17332	2026-09-22 11:26	52.92	OK
17333	2026-09-22 11:27	54.75	OK	17334	2026-09-22 11:28	55.17	OK
17335	2026-09-22 11:29	55.01	OK	17336	2026-09-22 11:30	56.05	OK
17337	2026-09-22 11:31	52.82	OK	17338	2026-09-22 11:32	53.96	OK
17339	2026-09-22 11:33	52.70	OK	17340	2026-09-22 11:34	55.69	OK
17341	2026-09-22 11:35	54.75	OK	17342	2026-09-22 11:36	54.94	OK
17343	2026-09-22 11:37	53.87	OK	17344	2026-09-22 11:38	52.95	OK
17345	2026-09-22 11:39	53.57	OK	17346	2026-09-22 11:40	54.66	OK
17347	2026-09-22 11:41	54.29	OK	17348	2026-09-22 11:42	52.71	OK
17349	2026-09-22 11:43	55.04	OK	17350	2026-09-22 11:44	54.17	OK
17351	2026-09-22 11:45	53.01	OK	17352	2026-09-22 11:46	52.96	OK
17353	2026-09-22 11:47	53.06	OK	17354	2026-09-22 11:48	54.22	OK
17355	2026-09-22 11:49	53.35	OK	17356	2026-09-22 11:50	53.30	OK
17357	2026-09-22 11:51	53.74	OK	17358	2026-09-22 11:52	54.58	OK
17359	2026-09-22 11:53	54.78	OK	17360	2026-09-22 11:54	54.42	OK
17361	2026-09-22 11:55	53.19	OK	17362	2026-09-22 11:56	54.01	OK
17363	2026-09-22 11:57	54.58	OK	17364	2026-09-22 11:58	55.22	OK
17365	2026-09-22 11:59	53.06	OK	17366	2026-09-22 12:00	53.29	OK
17367	2026-09-22 12:01	54.18	OK	17368	2026-09-22 12:02	55.03	OK
17369	2026-09-22 12:03	54.90	OK	17370	2026-09-22 12:04	54.48	OK
17371	2026-09-22 12:05	53.31	OK	17372	2026-09-22 12:06	54.58	OK
17373	2026-09-22 12:07	55.53	OK	17374	2026-09-22 12:08	54.08	OK
17375	2026-09-22 12:09	53.85	OK	17376	2026-09-22 12:10	51.93	OK
17377	2026-09-22 12:11	55.12	OK	17378	2026-09-22 12:12	53.52	OK
17379	2026-09-22 12:13	54.46	OK	17380	2026-09-22 12:14	52.14	OK
17381	2026-09-22 12:15	54.30	OK	17382	2026-09-22 12:16	55.24	OK
1738	2026-09-22 12:17	53.37	OK	1738	2026-09-22 12:18	55.57	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
17385	2026-09-22 12:19	53.63	OK	17386	2026-09-22 12:20	53.96	OK
17387	2026-09-22 12:21	53.28	OK	17388	2026-09-22 12:22	53.51	OK
17389	2026-09-22 12:23	53.13	OK	17390	2026-09-22 12:24	53.39	OK
17391	2026-09-22 12:25	53.73	OK	17392	2026-09-22 12:26	52.45	OK
17393	2026-09-22 12:27	54.68	OK	17394	2026-09-22 12:28	55.73	OK
17395	2026-09-22 12:29	54.80	OK	17396	2026-09-22 12:30	54.11	OK
17397	2026-09-22 12:31	53.34	OK	17398	2026-09-22 12:32	53.14	OK
17399	2026-09-22 12:33	55.04	OK	17400	2026-09-22 12:34	53.18	OK
17401	2026-09-22 12:35	54.81	OK	17402	2026-09-22 12:36	54.69	OK
17403	2026-09-22 12:37	54.66	OK	17404	2026-09-22 12:38	52.86	OK
17405	2026-09-22 12:39	54.25	OK	17406	2026-09-22 12:40	53.66	OK
17407	2026-09-22 12:41	52.93	OK	17408	2026-09-22 12:42	52.77	OK
17409	2026-09-22 12:43	53.60	OK	17410	2026-09-22 12:44	54.06	OK
17411	2026-09-22 12:45	54.74	OK	17412	2026-09-22 12:46	52.98	OK
17413	2026-09-22 12:47	51.79	OK	17414	2026-09-22 12:48	55.98	OK
17415	2026-09-22 12:49	52.60	OK	17416	2026-09-22 12:50	55.11	OK
17417	2026-09-22 12:51	53.31	OK	17418	2026-09-22 12:52	55.75	OK
17419	2026-09-22 12:53	55.68	OK	17420	2026-09-22 12:54	53.51	OK
17421	2026-09-22 12:55	54.05	OK	17422	2026-09-22 12:56	51.31	OK
17423	2026-09-22 12:57	53.84	OK	17424	2026-09-22 12:58	54.43	OK
17425	2026-09-22 12:59	52.82	OK	17426	2026-09-22 13:00	54.91	OK
17427	2026-09-22 13:01	54.87	OK	17428	2026-09-22 13:02	55.43	OK
17429	2026-09-22 13:03	55.39	OK	17430	2026-09-22 13:04	52.42	OK
17431	2026-09-22 13:05	53.35	OK	17432	2026-09-22 13:06	54.35	OK
17433	2026-09-22 13:07	55.13	OK	17434	2026-09-22 13:08	53.79	OK
17435	2026-09-22 13:09	52.04	OK	17436	2026-09-22 13:10	52.98	OK
17437	2026-09-22 13:11	54.50	OK	17438	2026-09-22 13:12	54.49	OK
17439	2026-09-22 13:13	56.62	OK	17440	2026-09-22 13:14	52.81	OK
17441	2026-09-22 13:15	54.99	OK	17442	2026-09-22 13:16	53.12	OK
1744	2026-09-22 13:17	52.95	OK	1744	2026-09-22 13:18	53.52	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
17445	2026-09-22 13:19	54.12	OK	17446	2026-09-22 13:20	54.75	OK
17447	2026-09-22 13:21	54.60	OK	17448	2026-09-22 13:22	52.99	OK
17449	2026-09-22 13:23	54.36	OK	17450	2026-09-22 13:24	54.56	OK
17451	2026-09-22 13:25	52.33	OK	17452	2026-09-22 13:26	54.81	OK
17453	2026-09-22 13:27	53.08	OK	17454	2026-09-22 13:28	53.05	OK
17455	2026-09-22 13:29	54.84	OK	17456	2026-09-22 13:30	53.36	OK
17457	2026-09-22 13:31	53.55	OK	17458	2026-09-22 13:32	52.91	OK
17459	2026-09-22 13:33	52.10	OK	17460	2026-09-22 13:34	54.74	OK
17461	2026-09-22 13:35	54.85	OK	17462	2026-09-22 13:36	51.86	OK
17463	2026-09-22 13:37	54.55	OK	17464	2026-09-22 13:38	53.03	OK
17465	2026-09-22 13:39	54.29	OK	17466	2026-09-22 13:40	54.37	OK
17467	2026-09-22 13:41	54.15	OK	17468	2026-09-22 13:42	53.92	OK
17469	2026-09-22 13:43	52.40	OK	17470	2026-09-22 13:44	54.39	OK
17471	2026-09-22 13:45	52.96	OK	17472	2026-09-22 13:46	51.76	OK
17473	2026-09-22 13:47	55.16	OK	17474	2026-09-22 13:48	51.46	OK
17475	2026-09-22 13:49	54.04	OK	17476	2026-09-22 13:50	51.60	OK
17477	2026-09-22 13:51	53.35	OK	17478	2026-09-22 13:52	53.69	OK
17479	2026-09-22 13:53	53.76	OK	17480	2026-09-22 13:54	53.61	OK
17481	2026-09-22 13:55	53.41	OK	17482	2026-09-22 13:56	53.97	OK
17483	2026-09-22 13:57	54.02	OK	17484	2026-09-22 13:58	52.10	OK
17485	2026-09-22 13:59	53.57	OK	17486	2026-09-22 14:00	51.90	OK
17487	2026-09-22 14:01	53.38	OK	17488	2026-09-22 14:02	52.84	OK
17489	2026-09-22 14:03	52.19	OK	17490	2026-09-22 14:04	53.14	OK
17491	2026-09-22 14:05	53.48	OK	17492	2026-09-22 14:06	52.41	OK
17493	2026-09-22 14:07	52.30	OK	17494	2026-09-22 14:08	52.21	OK
17495	2026-09-22 14:09	52.61	OK	17496	2026-09-22 14:10	54.20	OK
17497	2026-09-22 14:11	52.96	OK	17498	2026-09-22 14:12	53.73	OK
17499	2026-09-22 14:13	52.08	OK	17500	2026-09-22 14:14	54.06	OK
17501	2026-09-22 14:15	54.60	OK	17502	2026-09-22 14:16	54.26	OK
1750	2026-09-22 14:17	52.28	OK	1750	2026-09-22 14:18	54.52	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
17505	2026-09-22 14:19	52.29	OK	17506	2026-09-22 14:20	51.76	OK
17507	2026-09-22 14:21	52.44	OK	17508	2026-09-22 14:22	55.49	OK
17509	2026-09-22 14:23	52.55	OK	17510	2026-09-22 14:24	53.51	OK
17511	2026-09-22 14:25	52.35	OK	17512	2026-09-22 14:26	54.40	OK
17513	2026-09-22 14:27	53.09	OK	17514	2026-09-22 14:28	50.52	OK
17515	2026-09-22 14:29	53.54	OK	17516	2026-09-22 14:30	53.71	OK
17517	2026-09-22 14:31	51.79	OK	17518	2026-09-22 14:32	51.91	OK
17519	2026-09-22 14:33	53.07	OK	17520	2026-09-22 14:34	54.70	OK
17521	2026-09-22 14:35	51.38	OK	17522	2026-09-22 14:36	52.29	OK
17523	2026-09-22 14:37	54.29	OK	17524	2026-09-22 14:38	54.12	OK
17525	2026-09-22 14:39	53.18	OK	17526	2026-09-22 14:40	51.74	OK
17527	2026-09-22 14:41	51.48	OK	17528	2026-09-22 14:42	52.03	OK
17529	2026-09-22 14:43	52.59	OK	17530	2026-09-22 14:44	52.19	OK
17531	2026-09-22 14:45	50.28	OK	17532	2026-09-22 14:46	53.00	OK
17533	2026-09-22 14:47	51.72	OK	17534	2026-09-22 14:48	52.57	OK
17535	2026-09-22 14:49	51.27	OK	17536	2026-09-22 14:50	50.65	OK
17537	2026-09-22 14:51	54.10	OK	17538	2026-09-22 14:52	52.02	OK
17539	2026-09-22 14:53	53.57	OK	17540	2026-09-22 14:54	51.35	OK
17541	2026-09-22 14:55	50.26	OK	17542	2026-09-22 14:56	53.05	OK
17543	2026-09-22 14:57	52.04	OK	17544	2026-09-22 14:58	53.16	OK
17545	2026-09-22 14:59	53.59	OK	17546	2026-09-22 15:00	50.27	OK
17547	2026-09-22 15:01	51.95	OK	17548	2026-09-22 15:02	53.78	OK
17549	2026-09-22 15:03	49.43	OK	17550	2026-09-22 15:04	53.41	OK
17551	2026-09-22 15:05	52.22	OK	17552	2026-09-22 15:06	49.69	OK
17553	2026-09-22 15:07	52.86	OK	17554	2026-09-22 15:08	50.52	OK
17555	2026-09-22 15:09	51.63	OK	17556	2026-09-22 15:10	52.01	OK
17557	2026-09-22 15:11	52.09	OK	17558	2026-09-22 15:12	52.26	OK
17559	2026-09-22 15:13	51.95	OK	17560	2026-09-22 15:14	52.25	OK
17561	2026-09-22 15:15	51.98	OK	17562	2026-09-22 15:16	52.39	OK
1756	2026-09-22 15:17	53.22	OK	1756	2026-09-22 15:18	53.71	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
17565	2026-09-22 15:19	51.13	OK	17566	2026-09-22 15:20	50.69	OK
17567	2026-09-22 15:21	51.57	OK	17568	2026-09-22 15:22	51.23	OK
17569	2026-09-22 15:23	50.87	OK	17570	2026-09-22 15:24	50.35	OK
17571	2026-09-22 15:25	51.10	OK	17572	2026-09-22 15:26	51.31	OK
17573	2026-09-22 15:27	50.92	OK	17574	2026-09-22 15:28	52.16	OK
17575	2026-09-22 15:29	50.87	OK	17576	2026-09-22 15:30	54.66	OK
17577	2026-09-22 15:31	51.87	OK	17578	2026-09-22 15:32	51.85	OK
17579	2026-09-22 15:33	53.88	OK	17580	2026-09-22 15:34	51.77	OK
17581	2026-09-22 15:35	50.58	OK	17582	2026-09-22 15:36	49.96	OK
17583	2026-09-22 15:37	50.65	OK	17584	2026-09-22 15:38	51.42	OK
17585	2026-09-22 15:39	51.39	OK	17586	2026-09-22 15:40	52.37	OK
17587	2026-09-22 15:41	49.36	OK	17588	2026-09-22 15:42	52.96	OK
17589	2026-09-22 15:43	51.82	OK	17590	2026-09-22 15:44	49.48	OK
17591	2026-09-22 15:45	51.67	OK	17592	2026-09-22 15:46	49.97	OK
17593	2026-09-22 15:47	52.49	OK	17594	2026-09-22 15:48	50.91	OK
17595	2026-09-22 15:49	51.35	OK	17596	2026-09-22 15:50	51.45	OK
17597	2026-09-22 15:51	53.80	OK	17598	2026-09-22 15:52	51.11	OK
17599	2026-09-22 15:53	52.86	OK	17600	2026-09-22 15:54	51.55	OK
17601	2026-09-22 15:55	51.55	OK	17602	2026-09-22 15:56	50.97	OK
17603	2026-09-22 15:57	50.51	OK	17604	2026-09-22 15:58	53.48	OK
17605	2026-09-22 15:59	50.21	OK	17606	2026-09-22 16:00	49.50	OK
17607	2026-09-22 16:01	49.96	OK	17608	2026-09-22 16:02	50.69	OK
17609	2026-09-22 16:03	49.87	OK	17610	2026-09-22 16:04	53.35	OK
17611	2026-09-22 16:05	50.97	OK	17612	2026-09-22 16:06	51.39	OK
17613	2026-09-22 16:07	51.23	OK	17614	2026-09-22 16:08	50.98	OK
17615	2026-09-22 16:09	50.62	OK	17616	2026-09-22 16:10	51.69	OK
17617	2026-09-22 16:11	51.00	OK	17618	2026-09-22 16:12	51.87	OK
17619	2026-09-22 16:13	51.53	OK	17620	2026-09-22 16:14	51.00	OK
17621	2026-09-22 16:15	51.69	OK	17622	2026-09-22 16:16	50.05	OK
1762	2026-09-22 16:17	48.79	OK	1762	2026-09-22 16:18	51.40	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
17625	2026-09-22 16:19	49.49	OK	17626	2026-09-22 16:20	52.81	OK
17627	2026-09-22 16:21	51.43	OK	17628	2026-09-22 16:22	50.04	OK
17629	2026-09-22 16:23	52.05	OK	17630	2026-09-22 16:24	49.01	OK
17631	2026-09-22 16:25	51.04	OK	17632	2026-09-22 16:26	52.67	OK
17633	2026-09-22 16:27	52.40	OK	17634	2026-09-22 16:28	51.40	OK
17635	2026-09-22 16:29	49.32	OK	17636	2026-09-22 16:30	50.39	OK
17637	2026-09-22 16:31	51.15	OK	17638	2026-09-22 16:32	51.41	OK
17639	2026-09-22 16:33	51.01	OK	17640	2026-09-22 16:34	49.75	OK
17641	2026-09-22 16:35	50.22	OK	17642	2026-09-22 16:36	52.36	OK
17643	2026-09-22 16:37	51.64	OK	17644	2026-09-22 16:38	49.60	OK
17645	2026-09-22 16:39	50.43	OK	17646	2026-09-22 16:40	50.35	OK
17647	2026-09-22 16:41	49.17	OK	17648	2026-09-22 16:42	50.86	OK
17649	2026-09-22 16:43	49.08	OK	17650	2026-09-22 16:44	51.15	OK
17651	2026-09-22 16:45	49.08	OK	17652	2026-09-22 16:46	50.64	OK
17653	2026-09-22 16:47	49.14	OK	17654	2026-09-22 16:48	49.68	OK
17655	2026-09-22 16:49	50.56	OK	17656	2026-09-22 16:50	52.22	OK
17657	2026-09-22 16:51	50.48	OK	17658	2026-09-22 16:52	49.97	OK
17659	2026-09-22 16:53	49.33	OK	17660	2026-09-22 16:54	48.48	OK
17661	2026-09-22 16:55	51.03	OK	17662	2026-09-22 16:56	49.89	OK
17663	2026-09-22 16:57	52.00	OK	17664	2026-09-22 16:58	51.05	OK
17665	2026-09-22 16:59	49.61	OK	17666	2026-09-22 17:00	47.78	OK
17667	2026-09-22 17:01	51.78	OK	17668	2026-09-22 17:02	50.07	OK
17669	2026-09-22 17:03	51.04	OK	17670	2026-09-22 17:04	50.53	OK
17671	2026-09-22 17:05	49.41	OK	17672	2026-09-22 17:06	49.21	OK
17673	2026-09-22 17:07	52.65	OK	17674	2026-09-22 17:08	49.96	OK
17675	2026-09-22 17:09	49.00	OK	17676	2026-09-22 17:10	50.04	OK
17677	2026-09-22 17:11	49.28	OK	17678	2026-09-22 17:12	47.32	OK
17679	2026-09-22 17:13	49.87	OK	17680	2026-09-22 17:14	52.00	OK
17681	2026-09-22 17:15	49.85	OK	17682	2026-09-22 17:16	50.64	OK
1768	2026-09-22 17:17	51.09	OK	1768	2026-09-22 17:18	49.67	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
17685	2026-09-22 17:19	51.62	OK	17686	2026-09-22 17:20	49.52	OK
17687	2026-09-22 17:21	49.83	OK	17688	2026-09-22 17:22	51.17	OK
17689	2026-09-22 17:23	49.73	OK	17690	2026-09-22 17:24	49.36	OK
17691	2026-09-22 17:25	49.87	OK	17692	2026-09-22 17:26	51.39	OK
17693	2026-09-22 17:27	48.76	OK	17694	2026-09-22 17:28	50.03	OK
17695	2026-09-22 17:29	49.34	OK	17696	2026-09-22 17:30	50.16	OK
17697	2026-09-22 17:31	50.03	OK	17698	2026-09-22 17:32	50.72	OK
17699	2026-09-22 17:33	49.87	OK	17700	2026-09-22 17:34	48.35	OK
17701	2026-09-22 17:35	49.73	OK	17702	2026-09-22 17:36	49.47	OK
17703	2026-09-22 17:37	47.64	OK	17704	2026-09-22 17:38	50.95	OK
17705	2026-09-22 17:39	50.56	OK	17706	2026-09-22 17:40	48.39	OK
17707	2026-09-22 17:41	51.57	OK	17708	2026-09-22 17:42	48.59	OK
17709	2026-09-22 17:43	47.47	OK	17710	2026-09-22 17:44	48.32	OK
17711	2026-09-22 17:45	50.41	OK	17712	2026-09-22 17:46	49.56	OK
17713	2026-09-22 17:47	48.80	OK	17714	2026-09-22 17:48	49.94	OK
17715	2026-09-22 17:49	48.44	OK	17716	2026-09-22 17:50	48.73	OK
17717	2026-09-22 17:51	48.82	OK	17718	2026-09-22 17:52	47.20	OK
17719	2026-09-22 17:53	48.23	OK	17720	2026-09-22 17:54	49.54	OK
17721	2026-09-22 17:55	47.80	OK	17722	2026-09-22 17:56	49.56	OK
17723	2026-09-22 17:57	49.15	OK	17724	2026-09-22 17:58	50.73	OK
17725	2026-09-22 17:59	48.05	OK	17726	2026-09-22 18:00	49.04	OK
17727	2026-09-22 18:01	47.22	OK	17728	2026-09-22 18:02	47.25	OK
17729	2026-09-22 18:03	49.40	OK	17730	2026-09-22 18:04	48.72	OK
17731	2026-09-22 18:05	46.49	OK	17732	2026-09-22 18:06	48.13	OK
17733	2026-09-22 18:07	48.22	OK	17734	2026-09-22 18:08	49.38	OK
17735	2026-09-22 18:09	48.87	OK	17736	2026-09-22 18:10	48.79	OK
17737	2026-09-22 18:11	49.85	OK	17738	2026-09-22 18:12	46.52	OK
17739	2026-09-22 18:13	47.90	OK	17740	2026-09-22 18:14	48.25	OK
17741	2026-09-22 18:15	49.16	OK	17742	2026-09-22 18:16	49.07	OK
1774	2026-09-22 18:17	47.76	OK	1774	2026-09-22 18:18	48.92	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
17745	2026-09-22 18:19	47.65	OK	17746	2026-09-22 18:20	48.17	OK
17747	2026-09-22 18:21	49.06	OK	17748	2026-09-22 18:22	48.79	OK
17749	2026-09-22 18:23	47.12	OK	17750	2026-09-22 18:24	45.83	OK
17751	2026-09-22 18:25	46.78	OK	17752	2026-09-22 18:26	48.98	OK
17753	2026-09-22 18:27	48.59	OK	17754	2026-09-22 18:28	48.98	OK
17755	2026-09-22 18:29	46.50	OK	17756	2026-09-22 18:30	48.10	OK
17757	2026-09-22 18:31	49.08	OK	17758	2026-09-22 18:32	47.41	OK
17759	2026-09-22 18:33	47.96	OK	17760	2026-09-22 18:34	48.88	OK
17761	2026-09-22 18:35	48.22	OK	17762	2026-09-22 18:36	46.59	OK
17763	2026-09-22 18:37	46.05	OK	17764	2026-09-22 18:38	47.39	OK
17765	2026-09-22 18:39	47.33	OK	17766	2026-09-22 18:40	49.39	OK
17767	2026-09-22 18:41	49.03	OK	17768	2026-09-22 18:42	47.77	OK
17769	2026-09-22 18:43	46.00	OK	17770	2026-09-22 18:44	46.26	OK
17771	2026-09-22 18:45	46.91	OK	17772	2026-09-22 18:46	47.83	OK
17773	2026-09-22 18:47	47.53	OK	17774	2026-09-22 18:48	47.65	OK
17775	2026-09-22 18:49	48.51	OK	17776	2026-09-22 18:50	46.70	OK
17777	2026-09-22 18:51	47.38	OK	17778	2026-09-22 18:52	48.38	OK
17779	2026-09-22 18:53	47.38	OK	17780	2026-09-22 18:54	46.01	OK
17781	2026-09-22 18:55	46.69	OK	17782	2026-09-22 18:56	46.76	OK
17783	2026-09-22 18:57	47.30	OK	17784	2026-09-22 18:58	46.03	OK
17785	2026-09-22 18:59	49.14	OK	17786	2026-09-22 19:00	46.14	OK
17787	2026-09-22 19:01	49.56	OK	17788	2026-09-22 19:02	47.22	OK
17789	2026-09-22 19:03	45.65	OK	17790	2026-09-22 19:04	46.27	OK
17791	2026-09-22 19:05	48.67	OK	17792	2026-09-22 19:06	47.58	OK
17793	2026-09-22 19:07	48.45	OK	17794	2026-09-22 19:08	49.24	OK
17795	2026-09-22 19:09	46.85	OK	17796	2026-09-22 19:10	46.27	OK
17797	2026-09-22 19:11	49.24	OK	17798	2026-09-22 19:12	46.24	OK
17799	2026-09-22 19:13	47.61	OK	17800	2026-09-22 19:14	48.77	OK
17801	2026-09-22 19:15	47.79	OK	17802	2026-09-22 19:16	47.60	OK
1780	2026-09-22 19:17	48.74	OK	1780	2026-09-22 19:18	45.03	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
17805	2026-09-22 19:19	47.72	OK	17806	2026-09-22 19:20	45.90	OK
17807	2026-09-22 19:21	47.58	OK	17808	2026-09-22 19:22	47.09	OK
17809	2026-09-22 19:23	46.52	OK	17810	2026-09-22 19:24	48.18	OK
17811	2026-09-22 19:25	45.61	OK	17812	2026-09-22 19:26	48.96	OK
17813	2026-09-22 19:27	46.95	OK	17814	2026-09-22 19:28	48.83	OK
17815	2026-09-22 19:29	48.28	OK	17816	2026-09-22 19:30	45.81	OK
17817	2026-09-22 19:31	46.32	OK	17818	2026-09-22 19:32	47.03	OK
17819	2026-09-22 19:33	48.34	OK	17820	2026-09-22 19:34	47.35	OK
17821	2026-09-22 19:35	48.22	OK	17822	2026-09-22 19:36	47.13	OK
17823	2026-09-22 19:37	46.17	OK	17824	2026-09-22 19:38	45.79	OK
17825	2026-09-22 19:39	47.64	OK	17826	2026-09-22 19:40	46.67	OK
17827	2026-09-22 19:41	48.21	OK	17828	2026-09-22 19:42	46.78	OK
17829	2026-09-22 19:43	48.05	OK	17830	2026-09-22 19:44	46.25	OK
17831	2026-09-22 19:45	46.40	OK	17832	2026-09-22 19:46	48.40	OK
17833	2026-09-22 19:47	46.04	OK	17834	2026-09-22 19:48	46.61	OK
17835	2026-09-22 19:49	47.51	OK	17836	2026-09-22 19:50	44.75	OK
17837	2026-09-22 19:51	46.50	OK	17838	2026-09-22 19:52	45.21	OK
17839	2026-09-22 19:53	46.15	OK	17840	2026-09-22 19:54	49.11	OK
17841	2026-09-22 19:55	48.10	OK	17842	2026-09-22 19:56	44.85	OK
17843	2026-09-22 19:57	48.92	OK	17844	2026-09-22 19:58	47.16	OK
17845	2026-09-22 19:59	44.85	OK	17846	2026-09-22 20:00	47.17	OK
17847	2026-09-22 20:01	46.14	OK	17848	2026-09-22 20:02	47.28	OK
17849	2026-09-22 20:03	46.74	OK	17850	2026-09-22 20:04	47.60	OK
17851	2026-09-22 20:05	45.67	OK	17852	2026-09-22 20:06	47.44	OK
17853	2026-09-22 20:07	45.83	OK	17854	2026-09-22 20:08	45.14	OK
17855	2026-09-22 20:09	46.00	OK	17856	2026-09-22 20:10	45.95	OK
17857	2026-09-22 20:11	45.13	OK	17858	2026-09-22 20:12	48.58	OK
17859	2026-09-22 20:13	47.20	OK	17860	2026-09-22 20:14	46.28	OK
17861	2026-09-22 20:15	44.10	OK	17862	2026-09-22 20:16	46.07	OK
1786	2026-09-22 20:17	46.85	OK	1786	2026-09-22 20:18	47.23	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
17865	2026-09-22 20:19	45.22	OK	17866	2026-09-22 20:20	46.13	OK
17867	2026-09-22 20:21	45.27	OK	17868	2026-09-22 20:22	46.66	OK
17869	2026-09-22 20:23	46.04	OK	17870	2026-09-22 20:24	48.67	OK
17871	2026-09-22 20:25	44.89	OK	17872	2026-09-22 20:26	47.40	OK
17873	2026-09-22 20:27	44.62	OK	17874	2026-09-22 20:28	44.51	OK
17875	2026-09-22 20:29	47.66	OK	17876	2026-09-22 20:30	44.58	OK
17877	2026-09-22 20:31	44.76	OK	17878	2026-09-22 20:32	45.85	OK
17879	2026-09-22 20:33	47.27	OK	17880	2026-09-22 20:34	46.49	OK
17881	2026-09-22 20:35	45.55	OK	17882	2026-09-22 20:36	43.95	OK
17883	2026-09-22 20:37	47.35	OK	17884	2026-09-22 20:38	48.13	OK
17885	2026-09-22 20:39	46.29	OK	17886	2026-09-22 20:40	47.96	OK
17887	2026-09-22 20:41	45.49	OK	17888	2026-09-22 20:42	46.09	OK
17889	2026-09-22 20:43	45.56	OK	17890	2026-09-22 20:44	47.04	OK
17891	2026-09-22 20:45	47.16	OK	17892	2026-09-22 20:46	45.08	OK
17893	2026-09-22 20:47	44.89	OK	17894	2026-09-22 20:48	47.79	OK
17895	2026-09-22 20:49	45.38	OK	17896	2026-09-22 20:50	44.39	OK
17897	2026-09-22 20:51	45.66	OK	17898	2026-09-22 20:52	45.12	OK
17899	2026-09-22 20:53	44.02	OK	17900	2026-09-22 20:54	44.82	OK
17901	2026-09-22 20:55	42.95	OK	17902	2026-09-22 20:56	46.74	OK
17903	2026-09-22 20:57	46.25	OK	17904	2026-09-22 20:58	46.24	OK
17905	2026-09-22 20:59	46.38	OK	17906	2026-09-22 21:00	45.73	OK
17907	2026-09-22 21:01	45.49	OK	17908	2026-09-22 21:02	46.32	OK
17909	2026-09-22 21:03	44.61	OK	17910	2026-09-22 21:04	45.41	OK
17911	2026-09-22 21:05	43.86	OK	17912	2026-09-22 21:06	45.45	OK
17913	2026-09-22 21:07	45.93	OK	17914	2026-09-22 21:08	44.77	OK
17915	2026-09-22 21:09	45.64	OK	17916	2026-09-22 21:10	43.93	OK
17917	2026-09-22 21:11	45.20	OK	17918	2026-09-22 21:12	43.57	OK
17919	2026-09-22 21:13	44.76	OK	17920	2026-09-22 21:14	44.82	OK
17921	2026-09-22 21:15	46.35	OK	17922	2026-09-22 21:16	45.29	OK
1792	2026-09-22 21:17	46.03	OK	1792	2026-09-22 21:18	46.85	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
17925	2026-09-22 21:19	44.39	OK	17926	2026-09-22 21:20	46.68	OK
17927	2026-09-22 21:21	47.04	OK	17928	2026-09-22 21:22	46.73	OK
17929	2026-09-22 21:23	45.40	OK	17930	2026-09-22 21:24	45.15	OK
17931	2026-09-22 21:25	44.08	OK	17932	2026-09-22 21:26	44.98	OK
17933	2026-09-22 21:27	47.91	OK	17934	2026-09-22 21:28	46.43	OK
17935	2026-09-22 21:29	45.48	OK	17936	2026-09-22 21:30	44.09	OK
17937	2026-09-22 21:31	45.69	OK	17938	2026-09-22 21:32	45.05	OK
17939	2026-09-22 21:33	45.78	OK	17940	2026-09-22 21:34	46.22	OK
17941	2026-09-22 21:35	43.22	OK	17942	2026-09-22 21:36	45.94	OK
17943	2026-09-22 21:37	45.24	OK	17944	2026-09-22 21:38	43.16	OK
17945	2026-09-22 21:39	45.87	OK	17946	2026-09-22 21:40	44.31	OK
17947	2026-09-22 21:41	47.49	OK	17948	2026-09-22 21:42	44.53	OK
17949	2026-09-22 21:43	44.52	OK	17950	2026-09-22 21:44	45.47	OK
17951	2026-09-22 21:45	45.48	OK	17952	2026-09-22 21:46	45.84	OK
17953	2026-09-22 21:47	46.53	OK	17954	2026-09-22 21:48	45.05	OK
17955	2026-09-22 21:49	46.62	OK	17956	2026-09-22 21:50	44.38	OK
17957	2026-09-22 21:51	46.31	OK	17958	2026-09-22 21:52	44.40	OK
17959	2026-09-22 21:53	46.27	OK	17960	2026-09-22 21:54	43.91	OK
17961	2026-09-22 21:55	45.88	OK	17962	2026-09-22 21:56	45.73	OK
17963	2026-09-22 21:57	43.84	OK	17964	2026-09-22 21:58	45.03	OK
17965	2026-09-22 21:59	44.89	OK	17966	2026-09-22 22:00	46.33	OK
17967	2026-09-22 22:01	46.34	OK	17968	2026-09-22 22:02	46.46	OK
17969	2026-09-22 22:03	42.49	OK	17970	2026-09-22 22:04	46.47	OK
17971	2026-09-22 22:05	43.53	OK	17972	2026-09-22 22:06	44.83	OK
17973	2026-09-22 22:07	46.57	OK	17974	2026-09-22 22:08	44.96	OK
17975	2026-09-22 22:09	45.11	OK	17976	2026-09-22 22:10	47.31	OK
17977	2026-09-22 22:11	45.87	OK	17978	2026-09-22 22:12	45.66	OK
17979	2026-09-22 22:13	45.58	OK	17980	2026-09-22 22:14	44.03	OK
17981	2026-09-22 22:15	43.77	OK	17982	2026-09-22 22:16	43.01	OK
1798	2026-09-22 22:17	45.04	OK	1798	2026-09-22 22:18	45.38	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
17985	2026-09-22 22:19	46.06	OK	17986	2026-09-22 22:20	46.38	OK
17987	2026-09-22 22:21	44.83	OK	17988	2026-09-22 22:22	47.00	OK
17989	2026-09-22 22:23	45.79	OK	17990	2026-09-22 22:24	44.40	OK
17991	2026-09-22 22:25	45.34	OK	17992	2026-09-22 22:26	43.40	OK
17993	2026-09-22 22:27	43.89	OK	17994	2026-09-22 22:28	43.19	OK
17995	2026-09-22 22:29	44.45	OK	17996	2026-09-22 22:30	43.76	OK
17997	2026-09-22 22:31	46.29	OK	17998	2026-09-22 22:32	46.12	OK
17999	2026-09-22 22:33	44.09	OK	18000	2026-09-22 22:34	45.10	OK
18001	2026-09-22 22:35	45.94	OK	18002	2026-09-22 22:36	44.87	OK
18003	2026-09-22 22:37	44.94	OK	18004	2026-09-22 22:38	44.38	OK
18005	2026-09-22 22:39	46.82	OK	18006	2026-09-22 22:40	45.98	OK
18007	2026-09-22 22:41	42.47	OK	18008	2026-09-22 22:42	43.59	OK
18009	2026-09-22 22:43	44.38	OK	18010	2026-09-22 22:44	45.44	OK
18011	2026-09-22 22:45	45.57	OK	18012	2026-09-22 22:46	43.92	OK
18013	2026-09-22 22:47	46.99	OK	18014	2026-09-22 22:48	43.96	OK
18015	2026-09-22 22:49	44.98	OK	18016	2026-09-22 22:50	44.37	OK
18017	2026-09-22 22:51	44.80	OK	18018	2026-09-22 22:52	44.41	OK
18019	2026-09-22 22:53	45.17	OK	18020	2026-09-22 22:54	45.70	OK
18021	2026-09-22 22:55	45.67	OK	18022	2026-09-22 22:56	43.82	OK
18023	2026-09-22 22:57	43.84	OK	18024	2026-09-22 22:58	43.72	OK
18025	2026-09-22 22:59	44.85	OK	18026	2026-09-22 23:00	42.54	OK
18027	2026-09-22 23:01	44.04	OK	18028	2026-09-22 23:02	46.95	OK
18029	2026-09-22 23:03	45.14	OK	18030	2026-09-22 23:04	44.91	OK
18031	2026-09-22 23:05	44.63	OK	18032	2026-09-22 23:06	44.65	OK
18033	2026-09-22 23:07	43.54	OK	18034	2026-09-22 23:08	43.62	OK
18035	2026-09-22 23:09	45.21	OK	18036	2026-09-22 23:10	45.68	OK
18037	2026-09-22 23:11	45.70	OK	18038	2026-09-22 23:12	44.46	OK
18039	2026-09-22 23:13	46.60	OK	18040	2026-09-22 23:14	45.30	OK
18041	2026-09-22 23:15	43.64	OK	18042	2026-09-22 23:16	43.65	OK
1804	2026-09-22 23:17	43.14	OK	1804	2026-09-22 23:18	42.82	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
18045	2026-09-22 23:19	45.42	OK	18046	2026-09-22 23:20	44.60	OK
18047	2026-09-22 23:21	45.36	OK	18048	2026-09-22 23:22	44.17	OK
18049	2026-09-22 23:23	45.05	OK	18050	2026-09-22 23:24	43.08	OK
18051	2026-09-22 23:25	43.69	OK	18052	2026-09-22 23:26	45.01	OK
18053	2026-09-22 23:27	43.74	OK	18054	2026-09-22 23:28	44.30	OK
18055	2026-09-22 23:29	44.31	OK	18056	2026-09-22 23:30	45.97	OK
18057	2026-09-22 23:31	44.81	OK	18058	2026-09-22 23:32	43.44	OK
18059	2026-09-22 23:33	43.25	OK	18060	2026-09-22 23:34	44.21	OK
18061	2026-09-22 23:35	43.95	OK	18062	2026-09-22 23:36	43.79	OK
18063	2026-09-22 23:37	45.57	OK	18064	2026-09-22 23:38	42.38	OK
18065	2026-09-22 23:39	46.23	OK	18066	2026-09-22 23:40	44.93	OK
18067	2026-09-22 23:41	44.33	OK	18068	2026-09-22 23:42	45.04	OK
18069	2026-09-22 23:43	44.81	OK	18070	2026-09-22 23:44	45.81	OK
18071	2026-09-22 23:45	45.57	OK	18072	2026-09-22 23:46	43.15	OK
18073	2026-09-22 23:47	43.64	OK	18074	2026-09-22 23:48	44.80	OK
18075	2026-09-22 23:49	45.14	OK	18076	2026-09-22 23:50	44.40	OK
18077	2026-09-22 23:51	44.34	OK	18078	2026-09-22 23:52	46.64	OK
18079	2026-09-22 23:53	45.55	OK	18080	2026-09-22 23:54	44.13	OK
18081	2026-09-22 23:55	43.04	OK	18082	2026-09-22 23:56	42.39	OK
18083	2026-09-22 23:57	42.41	OK	18084	2026-09-22 23:58	45.81	OK
18085	2026-09-22 23:59	43.31	OK	18086	2026-09-23 00:00	45.63	OK
18087	2026-09-23 00:01	44.58	OK	18088	2026-09-23 00:02	45.22	OK
18089	2026-09-23 00:03	44.17	OK	18090	2026-09-23 00:04	42.77	OK
18091	2026-09-23 00:05	44.52	OK	18092	2026-09-23 00:06	43.67	OK
18093	2026-09-23 00:07	44.74	OK	18094	2026-09-23 00:08	44.90	OK
18095	2026-09-23 00:09	44.84	OK	18096	2026-09-23 00:10	43.97	OK
18097	2026-09-23 00:11	46.10	OK	18098	2026-09-23 00:12	45.70	OK
18099	2026-09-23 00:13	45.29	OK	18100	2026-09-23 00:14	44.98	OK
18101	2026-09-23 00:15	44.92	OK	18102	2026-09-23 00:16	44.77	OK
1810	2026-09-23 00:17	44.09	OK	1810	2026-09-23 00:18	43.28	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
18105	2026-09-23 00:19	43.92	OK	18106	2026-09-23 00:20	44.89	OK
18107	2026-09-23 00:21	43.46	OK	18108	2026-09-23 00:22	43.73	OK
18109	2026-09-23 00:23	46.61	OK	18110	2026-09-23 00:24	43.89	OK
18111	2026-09-23 00:25	45.50	OK	18112	2026-09-23 00:26	44.10	OK
18113	2026-09-23 00:27	44.57	OK	18114	2026-09-23 00:28	44.79	OK
18115	2026-09-23 00:29	43.14	OK	18116	2026-09-23 00:30	42.90	OK
18117	2026-09-23 00:31	44.96	OK	18118	2026-09-23 00:32	46.93	OK
18119	2026-09-23 00:33	44.78	OK	18120	2026-09-23 00:34	44.99	OK
18121	2026-09-23 00:35	46.97	OK	18122	2026-09-23 00:36	45.57	OK
18123	2026-09-23 00:37	45.87	OK	18124	2026-09-23 00:38	46.40	OK
18125	2026-09-23 00:39	44.95	OK	18126	2026-09-23 00:40	46.55	OK
18127	2026-09-23 00:41	43.63	OK	18128	2026-09-23 00:42	45.47	OK
18129	2026-09-23 00:43	43.65	OK	18130	2026-09-23 00:44	46.13	OK
18131	2026-09-23 00:45	45.39	OK	18132	2026-09-23 00:46	46.67	OK
18133	2026-09-23 00:47	45.30	OK	18134	2026-09-23 00:48	44.83	OK
18135	2026-09-23 00:49	44.01	OK	18136	2026-09-23 00:50	46.10	OK
18137	2026-09-23 00:51	45.08	OK	18138	2026-09-23 00:52	46.47	OK
18139	2026-09-23 00:53	46.40	OK	18140	2026-09-23 00:54	44.62	OK
18141	2026-09-23 00:55	45.40	OK	18142	2026-09-23 00:56	44.22	OK
18143	2026-09-23 00:57	47.16	OK	18144	2026-09-23 00:58	46.54	OK
18145	2026-09-23 00:59	45.74	OK	18146	2026-09-23 01:00	43.43	OK
18147	2026-09-23 01:01	44.94	OK	18148	2026-09-23 01:02	45.41	OK
18149	2026-09-23 01:03	47.16	OK	18150	2026-09-23 01:04	44.73	OK
18151	2026-09-23 01:05	44.22	OK	18152	2026-09-23 01:06	43.91	OK
18153	2026-09-23 01:07	45.29	OK	18154	2026-09-23 01:08	43.23	OK
18155	2026-09-23 01:09	44.92	OK	18156	2026-09-23 01:10	44.20	OK
18157	2026-09-23 01:11	44.31	OK	18158	2026-09-23 01:12	46.05	OK
18159	2026-09-23 01:13	45.11	OK	18160	2026-09-23 01:14	45.59	OK
18161	2026-09-23 01:15	45.77	OK	18162	2026-09-23 01:16	44.67	OK
1816	2026-09-23 01:17	45.00	OK	1816	2026-09-23 01:18	46.23	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
18165	2026-09-23 01:19	44.68	OK	18166	2026-09-23 01:20	43.07	OK
18167	2026-09-23 01:21	45.77	OK	18168	2026-09-23 01:22	47.05	OK
18169	2026-09-23 01:23	45.22	OK	18170	2026-09-23 01:24	45.45	OK
18171	2026-09-23 01:25	44.59	OK	18172	2026-09-23 01:26	46.75	OK
18173	2026-09-23 01:27	44.47	OK	18174	2026-09-23 01:28	43.57	OK
18175	2026-09-23 01:29	44.62	OK	18176	2026-09-23 01:30	43.96	OK
18177	2026-09-23 01:31	43.98	OK	18178	2026-09-23 01:32	44.78	OK
18179	2026-09-23 01:33	44.92	OK	18180	2026-09-23 01:34	45.32	OK
18181	2026-09-23 01:35	45.66	OK	18182	2026-09-23 01:36	45.80	OK
18183	2026-09-23 01:37	46.41	OK	18184	2026-09-23 01:38	46.05	OK
18185	2026-09-23 01:39	44.90	OK	18186	2026-09-23 01:40	45.20	OK
18187	2026-09-23 01:41	44.82	OK	18188	2026-09-23 01:42	44.84	OK
18189	2026-09-23 01:43	45.68	OK	18190	2026-09-23 01:44	43.07	OK
18191	2026-09-23 01:45	45.97	OK	18192	2026-09-23 01:46	44.74	OK
18193	2026-09-23 01:47	44.67	OK	18194	2026-09-23 01:48	44.94	OK
18195	2026-09-23 01:49	44.42	OK	18196	2026-09-23 01:50	45.12	OK
18197	2026-09-23 01:51	44.47	OK	18198	2026-09-23 01:52	46.24	OK
18199	2026-09-23 01:53	45.89	OK	18200	2026-09-23 01:54	44.27	OK
18201	2026-09-23 01:55	45.94	OK	18202	2026-09-23 01:56	47.70	OK
18203	2026-09-23 01:57	45.95	OK	18204	2026-09-23 01:58	44.59	OK
18205	2026-09-23 01:59	45.43	OK	18206	2026-09-23 02:00	45.97	OK
18207	2026-09-23 02:01	43.27	OK	18208	2026-09-23 02:02	45.15	OK
18209	2026-09-23 02:03	45.12	OK	18210	2026-09-23 02:04	45.90	OK
18211	2026-09-23 02:05	48.15	OK	18212	2026-09-23 02:06	45.53	OK
18213	2026-09-23 02:07	46.04	OK	18214	2026-09-23 02:08	44.88	OK
18215	2026-09-23 02:09	45.26	OK	18216	2026-09-23 02:10	46.20	OK
18217	2026-09-23 02:11	47.20	OK	18218	2026-09-23 02:12	45.45	OK
18219	2026-09-23 02:13	45.44	OK	18220	2026-09-23 02:14	45.76	OK
18221	2026-09-23 02:15	45.45	OK	18222	2026-09-23 02:16	46.76	OK
1822	2026-09-23 02:17	46.43	OK	1822	2026-09-23 02:18	45.63	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
18225	2026-09-23 02:19	46.44	OK	18226	2026-09-23 02:20	44.57	OK
18227	2026-09-23 02:21	46.19	OK	18228	2026-09-23 02:22	47.03	OK
18229	2026-09-23 02:23	44.65	OK	18230	2026-09-23 02:24	45.14	OK
18231	2026-09-23 02:25	47.45	OK	18232	2026-09-23 02:26	46.11	OK
18233	2026-09-23 02:27	43.37	OK	18234	2026-09-23 02:28	45.29	OK
18235	2026-09-23 02:29	46.17	OK	18236	2026-09-23 02:30	47.08	OK
18237	2026-09-23 02:31	46.06	OK	18238	2026-09-23 02:32	45.51	OK
18239	2026-09-23 02:33	45.75	OK	18240	2026-09-23 02:34	46.23	OK
18241	2026-09-23 02:35	47.31	OK	18242	2026-09-23 02:36	46.94	OK
18243	2026-09-23 02:37	44.55	OK	18244	2026-09-23 02:38	45.23	OK
18245	2026-09-23 02:39	48.55	OK	18246	2026-09-23 02:40	46.11	OK
18247	2026-09-23 02:41	45.84	OK	18248	2026-09-23 02:42	47.22	OK
18249	2026-09-23 02:43	45.00	OK	18250	2026-09-23 02:44	48.26	OK
18251	2026-09-23 02:45	44.74	OK	18252	2026-09-23 02:46	45.86	OK
18253	2026-09-23 02:47	48.11	OK	18254	2026-09-23 02:48	47.29	OK
18255	2026-09-23 02:49	44.39	OK	18256	2026-09-23 02:50	46.23	OK
18257	2026-09-23 02:51	47.82	OK	18258	2026-09-23 02:52	47.33	OK
18259	2026-09-23 02:53	44.15	OK	18260	2026-09-23 02:54	46.37	OK
18261	2026-09-23 02:55	46.24	OK	18262	2026-09-23 02:56	44.93	OK
18263	2026-09-23 02:57	46.54	OK	18264	2026-09-23 02:58	46.25	OK
18265	2026-09-23 02:59	46.42	OK	18266	2026-09-23 03:00	47.13	OK
18267	2026-09-23 03:01	45.48	OK	18268	2026-09-23 03:02	47.04	OK
18269	2026-09-23 03:03	47.03	OK	18270	2026-09-23 03:04	48.44	OK
18271	2026-09-23 03:05	46.36	OK	18272	2026-09-23 03:06	48.05	OK
18273	2026-09-23 03:07	46.72	OK	18274	2026-09-23 03:08	46.57	OK
18275	2026-09-23 03:09	45.18	OK	18276	2026-09-23 03:10	48.03	OK
18277	2026-09-23 03:11	47.22	OK	18278	2026-09-23 03:12	46.32	OK
18279	2026-09-23 03:13	47.04	OK	18280	2026-09-23 03:14	47.78	OK
18281	2026-09-23 03:15	47.15	OK	18282	2026-09-23 03:16	47.57	OK
1828	2026-09-23 03:17	45.84	OK	1828	2026-09-23 03:18	46.66	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
18285	2026-09-23 03:19	49.33	OK	18286	2026-09-23 03:20	48.12	OK
18287	2026-09-23 03:21	46.09	OK	18288	2026-09-23 03:22	46.87	OK
18289	2026-09-23 03:23	47.69	OK	18290	2026-09-23 03:24	47.05	OK
18291	2026-09-23 03:25	47.57	OK	18292	2026-09-23 03:26	48.20	OK
18293	2026-09-23 03:27	45.79	OK	18294	2026-09-23 03:28	45.46	OK
18295	2026-09-23 03:29	46.85	OK	18296	2026-09-23 03:30	48.52	OK
18297	2026-09-23 03:31	46.63	OK	18298	2026-09-23 03:32	45.32	OK
18299	2026-09-23 03:33	46.40	OK	18300	2026-09-23 03:34	46.71	OK
18301	2026-09-23 03:35	45.78	OK	18302	2026-09-23 03:36	47.25	OK
18303	2026-09-23 03:37	46.38	OK	18304	2026-09-23 03:38	45.76	OK
18305	2026-09-23 03:39	46.95	OK	18306	2026-09-23 03:40	47.03	OK
18307	2026-09-23 03:41	46.30	OK	18308	2026-09-23 03:42	47.73	OK
18309	2026-09-23 03:43	47.72	OK	18310	2026-09-23 03:44	48.13	OK
18311	2026-09-23 03:45	44.92	OK	18312	2026-09-23 03:46	47.33	OK
18313	2026-09-23 03:47	46.57	OK	18314	2026-09-23 03:48	46.66	OK
18315	2026-09-23 03:49	48.50	OK	18316	2026-09-23 03:50	49.19	OK
18317	2026-09-23 03:51	48.17	OK	18318	2026-09-23 03:52	49.48	OK
18319	2026-09-23 03:53	48.18	OK	18320	2026-09-23 03:54	49.23	OK
18321	2026-09-23 03:55	48.03	OK	18322	2026-09-23 03:56	48.00	OK
18323	2026-09-23 03:57	47.94	OK	18324	2026-09-23 03:58	45.73	OK
18325	2026-09-23 03:59	48.14	OK	18326	2026-09-23 04:00	47.13	OK
18327	2026-09-23 04:01	46.03	OK	18328	2026-09-23 04:02	48.85	OK
18329	2026-09-23 04:03	49.23	OK	18330	2026-09-23 04:04	47.76	OK
18331	2026-09-23 04:05	48.16	OK	18332	2026-09-23 04:06	48.80	OK
18333	2026-09-23 04:07	48.06	OK	18334	2026-09-23 04:08	47.40	OK
18335	2026-09-23 04:09	48.29	OK	18336	2026-09-23 04:10	48.47	OK
18337	2026-09-23 04:11	47.51	OK	18338	2026-09-23 04:12	49.40	OK
18339	2026-09-23 04:13	46.42	OK	18340	2026-09-23 04:14	48.14	OK
18341	2026-09-23 04:15	48.76	OK	18342	2026-09-23 04:16	50.21	OK
1834	2026-09-23 04:17	47.43	OK	1834	2026-09-23 04:18	48.01	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
18345	2026-09-23 04:19	46.20	OK	18346	2026-09-23 04:20	46.94	OK
18347	2026-09-23 04:21	46.49	OK	18348	2026-09-23 04:22	45.71	OK
18349	2026-09-23 04:23	48.47	OK	18350	2026-09-23 04:24	47.02	OK
18351	2026-09-23 04:25	47.88	OK	18352	2026-09-23 04:26	46.40	OK
18353	2026-09-23 04:27	46.68	OK	18354	2026-09-23 04:28	47.77	OK
18355	2026-09-23 04:29	47.01	OK	18356	2026-09-23 04:30	47.09	OK
18357	2026-09-23 04:31	48.40	OK	18358	2026-09-23 04:32	46.95	OK
18359	2026-09-23 04:33	47.99	OK	18360	2026-09-23 04:34	48.42	OK
18361	2026-09-23 04:35	50.10	OK	18362	2026-09-23 04:36	46.85	OK
18363	2026-09-23 04:37	49.92	OK	18364	2026-09-23 04:38	49.41	OK
18365	2026-09-23 04:39	48.56	OK	18366	2026-09-23 04:40	48.85	OK
18367	2026-09-23 04:41	48.96	OK	18368	2026-09-23 04:42	48.52	OK
18369	2026-09-23 04:43	49.19	OK	18370	2026-09-23 04:44	46.68	OK
18371	2026-09-23 04:45	50.12	OK	18372	2026-09-23 04:46	46.10	OK
18373	2026-09-23 04:47	48.18	OK	18374	2026-09-23 04:48	49.59	OK
18375	2026-09-23 04:49	48.44	OK	18376	2026-09-23 04:50	48.58	OK
18377	2026-09-23 04:51	49.32	OK	18378	2026-09-23 04:52	48.73	OK
18379	2026-09-23 04:53	48.23	OK	18380	2026-09-23 04:54	49.75	OK
18381	2026-09-23 04:55	49.02	OK	18382	2026-09-23 04:56	47.85	OK
18383	2026-09-23 04:57	47.07	OK	18384	2026-09-23 04:58	49.68	OK
18385	2026-09-23 04:59	51.40	OK	18386	2026-09-23 05:00	49.48	OK
18387	2026-09-23 05:01	47.22	OK	18388	2026-09-23 05:02	48.95	OK
18389	2026-09-23 05:03	49.94	OK	18390	2026-09-23 05:04	49.23	OK
18391	2026-09-23 05:05	49.56	OK	18392	2026-09-23 05:06	48.44	OK
18393	2026-09-23 05:07	48.85	OK	18394	2026-09-23 05:08	48.88	OK
18395	2026-09-23 05:09	48.76	OK	18396	2026-09-23 05:10	49.80	OK
18397	2026-09-23 05:11	49.19	OK	18398	2026-09-23 05:12	49.34	OK
18399	2026-09-23 05:13	47.62	OK	18400	2026-09-23 05:14	48.72	OK
18401	2026-09-23 05:15	46.50	OK	18402	2026-09-23 05:16	46.99	OK
1840	2026-09-23 05:17	48.05	OK	1840	2026-09-23 05:18	50.67	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
18405	2026-09-23 05:19	51.13	OK	18406	2026-09-23 05:20	48.97	OK
18407	2026-09-23 05:21	50.94	OK	18408	2026-09-23 05:22	49.02	OK
18409	2026-09-23 05:23	49.17	OK	18410	2026-09-23 05:24	48.88	OK
18411	2026-09-23 05:25	48.81	OK	18412	2026-09-23 05:26	49.77	OK
18413	2026-09-23 05:27	49.87	OK	18414	2026-09-23 05:28	46.73	OK
18415	2026-09-23 05:29	47.10	OK	18416	2026-09-23 05:30	49.58	OK
18417	2026-09-23 05:31	50.58	OK	18418	2026-09-23 05:32	49.24	OK
18419	2026-09-23 05:33	50.90	OK	18420	2026-09-23 05:34	52.24	OK
18421	2026-09-23 05:35	48.43	OK	18422	2026-09-23 05:36	50.68	OK
18423	2026-09-23 05:37	49.35	OK	18424	2026-09-23 05:38	48.87	OK
18425	2026-09-23 05:39	49.13	OK	18426	2026-09-23 05:40	50.57	OK
18427	2026-09-23 05:41	49.01	OK	18428	2026-09-23 05:42	49.82	OK
18429	2026-09-23 05:43	50.15	OK	18430	2026-09-23 05:44	50.92	OK
18431	2026-09-23 05:45	50.01	OK	18432	2026-09-23 05:46	49.73	OK
18433	2026-09-23 05:47	50.69	OK	18434	2026-09-23 05:48	49.83	OK
18435	2026-09-23 05:49	51.12	OK	18436	2026-09-23 05:50	51.98	OK
18437	2026-09-23 05:51	50.37	OK	18438	2026-09-23 05:52	52.02	OK
18439	2026-09-23 05:53	49.52	OK	18440	2026-09-23 05:54	50.27	OK
18441	2026-09-23 05:55	48.36	OK	18442	2026-09-23 05:56	49.29	OK
18443	2026-09-23 05:57	51.18	OK	18444	2026-09-23 05:58	51.46	OK
18445	2026-09-23 05:59	48.41	OK	18446	2026-09-23 06:00	47.92	OK
18447	2026-09-23 06:01	48.87	OK	18448	2026-09-23 06:02	51.57	OK
18449	2026-09-23 06:03	51.33	OK	18450	2026-09-23 06:04	48.73	OK
18451	2026-09-23 06:05	50.73	OK	18452	2026-09-23 06:06	49.62	OK
18453	2026-09-23 06:07	51.99	OK	18454	2026-09-23 06:08	51.01	OK
18455	2026-09-23 06:09	47.95	OK	18456	2026-09-23 06:10	49.02	OK
18457	2026-09-23 06:11	49.66	OK	18458	2026-09-23 06:12	51.26	OK
18459	2026-09-23 06:13	49.38	OK	18460	2026-09-23 06:14	48.95	OK
18461	2026-09-23 06:15	51.32	OK	18462	2026-09-23 06:16	50.08	OK
1846	2026-09-23 06:17	50.34	OK	1846	2026-09-23 06:18	49.50	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
18465	2026-09-23 06:19	52.91	OK	18466	2026-09-23 06:20	49.27	OK
18467	2026-09-23 06:21	51.33	OK	18468	2026-09-23 06:22	50.48	OK
18469	2026-09-23 06:23	49.26	OK	18470	2026-09-23 06:24	51.31	OK
18471	2026-09-23 06:25	50.67	OK	18472	2026-09-23 06:26	51.17	OK
18473	2026-09-23 06:27	50.19	OK	18474	2026-09-23 06:28	52.15	OK
18475	2026-09-23 06:29	50.77	OK	18476	2026-09-23 06:30	51.29	OK
18477	2026-09-23 06:31	51.07	OK	18478	2026-09-23 06:32	50.61	OK
18479	2026-09-23 06:33	52.15	OK	18480	2026-09-23 06:34	52.37	OK
18481	2026-09-23 06:35	51.40	OK	18482	2026-09-23 06:36	50.68	OK
18483	2026-09-23 06:37	50.60	OK	18484	2026-09-23 06:38	49.15	OK
18485	2026-09-23 06:39	52.42	OK	18486	2026-09-23 06:40	50.48	OK
18487	2026-09-23 06:41	48.59	OK	18488	2026-09-23 06:42	49.71	OK
18489	2026-09-23 06:43	52.21	OK	18490	2026-09-23 06:44	51.58	OK
18491	2026-09-23 06:45	51.23	OK	18492	2026-09-23 06:46	49.95	OK
18493	2026-09-23 06:47	53.44	OK	18494	2026-09-23 06:48	51.42	OK
18495	2026-09-23 06:49	52.20	OK	18496	2026-09-23 06:50	50.41	OK
18497	2026-09-23 06:51	50.35	OK	18498	2026-09-23 06:52	51.32	OK
18499	2026-09-23 06:53	51.00	OK	18500	2026-09-23 06:54	53.45	OK
18501	2026-09-23 06:55	52.80	OK	18502	2026-09-23 06:56	52.11	OK
18503	2026-09-23 06:57	51.11	OK	18504	2026-09-23 06:58	51.91	OK
18505	2026-09-23 06:59	50.78	OK	18506	2026-09-23 07:00	50.71	OK
18507	2026-09-23 07:01	53.64	OK	18508	2026-09-23 07:02	53.52	OK
18509	2026-09-23 07:03	51.60	OK	18510	2026-09-23 07:04	53.81	OK
18511	2026-09-23 07:05	51.38	OK	18512	2026-09-23 07:06	52.25	OK
18513	2026-09-23 07:07	51.45	OK	18514	2026-09-23 07:08	50.15	OK
18515	2026-09-23 07:09	51.39	OK	18516	2026-09-23 07:10	51.77	OK
18517	2026-09-23 07:11	52.25	OK	18518	2026-09-23 07:12	51.89	OK
18519	2026-09-23 07:13	51.62	OK	18520	2026-09-23 07:14	51.12	OK
18521	2026-09-23 07:15	50.17	OK	18522	2026-09-23 07:16	53.08	OK
1852	2026-09-23 07:17	51.08	OK	1852	2026-09-23 07:18	52.14	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
18525	2026-09-23 07:19	52.16	OK	18526	2026-09-23 07:20	52.56	OK
18527	2026-09-23 07:21	50.63	OK	18528	2026-09-23 07:22	52.78	OK
18529	2026-09-23 07:23	50.68	OK	18530	2026-09-23 07:24	50.85	OK
18531	2026-09-23 07:25	50.55	OK	18532	2026-09-23 07:26	49.41	OK
18533	2026-09-23 07:27	53.15	OK	18534	2026-09-23 07:28	51.64	OK
18535	2026-09-23 07:29	50.86	OK	18536	2026-09-23 07:30	51.46	OK
18537	2026-09-23 07:31	51.53	OK	18538	2026-09-23 07:32	50.18	OK
18539	2026-09-23 07:33	49.89	OK	18540	2026-09-23 07:34	53.18	OK
18541	2026-09-23 07:35	51.45	OK	18542	2026-09-23 07:36	53.26	OK
18543	2026-09-23 07:37	53.39	OK	18544	2026-09-23 07:38	51.42	OK
18545	2026-09-23 07:39	53.24	OK	18546	2026-09-23 07:40	54.00	OK
18547	2026-09-23 07:41	51.64	OK	18548	2026-09-23 07:42	50.25	OK
18549	2026-09-23 07:43	51.92	OK	18550	2026-09-23 07:44	51.80	OK
18551	2026-09-23 07:45	53.26	OK	18552	2026-09-23 07:46	52.19	OK
18553	2026-09-23 07:47	53.87	OK	18554	2026-09-23 07:48	52.27	OK
18555	2026-09-23 07:49	52.48	OK	18556	2026-09-23 07:50	52.55	OK
18557	2026-09-23 07:51	54.53	OK	18558	2026-09-23 07:52	55.06	OK
18559	2026-09-23 07:53	53.29	OK	18560	2026-09-23 07:54	51.90	OK
18561	2026-09-23 07:55	53.23	OK	18562	2026-09-23 07:56	51.59	OK
18563	2026-09-23 07:57	50.86	OK	18564	2026-09-23 07:58	52.97	OK
18565	2026-09-23 07:59	51.33	OK	18566	2026-09-23 08:00	51.34	OK
18567	2026-09-23 08:01	53.45	OK	18568	2026-09-23 08:02	53.46	OK
18569	2026-09-23 08:03	51.92	OK	18570	2026-09-23 08:04	52.76	OK
18571	2026-09-23 08:05	52.65	OK	18572	2026-09-23 08:06	50.55	OK
18573	2026-09-23 08:07	52.12	OK	18574	2026-09-23 08:08	51.74	OK
18575	2026-09-23 08:09	52.70	OK	18576	2026-09-23 08:10	53.68	OK
18577	2026-09-23 08:11	52.68	OK	18578	2026-09-23 08:12	51.90	OK
18579	2026-09-23 08:13	52.40	OK	18580	2026-09-23 08:14	54.39	OK
18581	2026-09-23 08:15	52.53	OK	18582	2026-09-23 08:16	51.60	OK
1858	2026-09-23 08:17	52.89	OK	1858	2026-09-23 08:18	54.02	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
18585	2026-09-23 08:19	54.27	OK	18586	2026-09-23 08:20	51.15	OK
18587	2026-09-23 08:21	51.15	OK	18588	2026-09-23 08:22	53.59	OK
18589	2026-09-23 08:23	52.92	OK	18590	2026-09-23 08:24	51.98	OK
18591	2026-09-23 08:25	53.80	OK	18592	2026-09-23 08:26	52.45	OK
18593	2026-09-23 08:27	53.69	OK	18594	2026-09-23 08:28	51.38	OK
18595	2026-09-23 08:29	53.57	OK	18596	2026-09-23 08:30	53.21	OK
18597	2026-09-23 08:31	53.95	OK	18598	2026-09-23 08:32	53.42	OK
18599	2026-09-23 08:33	53.51	OK	18600	2026-09-23 08:34	54.10	OK
18601	2026-09-23 08:35	53.70	OK	18602	2026-09-23 08:36	52.71	OK
18603	2026-09-23 08:37	53.92	OK	18604	2026-09-23 08:38	54.07	OK
18605	2026-09-23 08:39	54.33	OK	18606	2026-09-23 08:40	51.59	OK
18607	2026-09-23 08:41	51.87	OK	18608	2026-09-23 08:42	53.99	OK
18609	2026-09-23 08:43	53.25	OK	18610	2026-09-23 08:44	53.59	OK
18611	2026-09-23 08:45	52.66	OK	18612	2026-09-23 08:46	51.91	OK
18613	2026-09-23 08:47	54.25	OK	18614	2026-09-23 08:48	55.31	OK
18615	2026-09-23 08:49	54.32	OK	18616	2026-09-23 08:50	52.48	OK
18617	2026-09-23 08:51	54.94	OK	18618	2026-09-23 08:52	53.68	OK
18619	2026-09-23 08:53	52.11	OK	18620	2026-09-23 08:54	52.75	OK
18621	2026-09-23 08:55	53.53	OK	18622	2026-09-23 08:56	54.10	OK
18623	2026-09-23 08:57	51.42	OK	18624	2026-09-23 08:58	52.81	OK
18625	2026-09-23 08:59	53.15	OK	18626	2026-09-23 09:00	52.63	OK
18627	2026-09-23 09:01	53.10	OK	18628	2026-09-23 09:02	53.83	OK
18629	2026-09-23 09:03	55.99	OK	18630	2026-09-23 09:04	52.33	OK
18631	2026-09-23 09:05	54.12	OK	18632	2026-09-23 09:06	52.38	OK
18633	2026-09-23 09:07	54.83	OK	18634	2026-09-23 09:08	52.32	OK
18635	2026-09-23 09:09	55.10	OK	18636	2026-09-23 09:10	52.87	OK
18637	2026-09-23 09:11	54.84	OK	18638	2026-09-23 09:12	53.85	OK
18639	2026-09-23 09:13	53.80	OK	18640	2026-09-23 09:14	54.63	OK
18641	2026-09-23 09:15	55.54	OK	18642	2026-09-23 09:16	54.02	OK
1864	2026-09-23 09:17	53.35	OK	1864	2026-09-23 09:18	55.82	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
18645	2026-09-23 09:19	51.96	OK	18646	2026-09-23 09:20	54.87	OK
18647	2026-09-23 09:21	56.00	OK	18648	2026-09-23 09:22	52.27	OK
18649	2026-09-23 09:23	52.58	OK	18650	2026-09-23 09:24	52.00	OK
18651	2026-09-23 09:25	53.90	OK	18652	2026-09-23 09:26	53.09	OK
18653	2026-09-23 09:27	54.32	OK	18654	2026-09-23 09:28	51.49	OK
18655	2026-09-23 09:29	52.34	OK	18656	2026-09-23 09:30	54.06	OK
18657	2026-09-23 09:31	52.26	OK	18658	2026-09-23 09:32	53.40	OK
18659	2026-09-23 09:33	53.58	OK	18660	2026-09-23 09:34	53.52	OK
18661	2026-09-23 09:35	53.65	OK	18662	2026-09-23 09:36	52.33	OK
18663	2026-09-23 09:37	54.48	OK	18664	2026-09-23 09:38	51.13	OK
18665	2026-09-23 09:39	55.60	OK	18666	2026-09-23 09:40	53.27	OK
18667	2026-09-23 09:41	53.62	OK	18668	2026-09-23 09:42	53.95	OK
18669	2026-09-23 09:43	52.66	OK	18670	2026-09-23 09:44	55.18	OK
18671	2026-09-23 09:45	52.30	OK	18672	2026-09-23 09:46	55.16	OK
18673	2026-09-23 09:47	54.17	OK	18674	2026-09-23 09:48	54.13	OK
18675	2026-09-23 09:49	53.32	OK	18676	2026-09-23 09:50	53.78	OK
18677	2026-09-23 09:51	52.97	OK	18678	2026-09-23 09:52	54.58	OK
18679	2026-09-23 09:53	52.98	OK	18680	2026-09-23 09:54	54.00	OK
18681	2026-09-23 09:55	55.70	OK	18682	2026-09-23 09:56	54.14	OK
18683	2026-09-23 09:57	52.68	OK	18684	2026-09-23 09:58	55.43	OK
18685	2026-09-23 09:59	55.59	OK	18686	2026-09-23 10:00	53.14	OK
18687	2026-09-23 10:01	54.11	OK	18688	2026-09-23 10:02	53.90	OK
18689	2026-09-23 10:03	54.94	OK	18690	2026-09-23 10:04	54.46	OK
18691	2026-09-23 10:05	53.79	OK	18692	2026-09-23 10:06	53.61	OK
18693	2026-09-23 10:07	52.84	OK	18694	2026-09-23 10:08	53.67	OK
18695	2026-09-23 10:09	55.18	OK	18696	2026-09-23 10:10	54.44	OK
18697	2026-09-23 10:11	53.73	OK	18698	2026-09-23 10:12	55.02	OK
18699	2026-09-23 10:13	55.17	OK	18700	2026-09-23 10:14	51.57	OK
18701	2026-09-23 10:15	52.15	OK	18702	2026-09-23 10:16	53.84	OK
1870	2026-09-23 10:17	55.09	OK	1870	2026-09-23 10:18	54.58	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
18705	2026-09-23 10:19	54.39	OK	18706	2026-09-23 10:20	56.51	OK
18707	2026-09-23 10:21	54.99	OK	18708	2026-09-23 10:22	53.55	OK
18709	2026-09-23 10:23	54.99	OK	18710	2026-09-23 10:24	53.79	OK
18711	2026-09-23 10:25	54.28	OK	18712	2026-09-23 10:26	54.01	OK
18713	2026-09-23 10:27	54.22	OK	18714	2026-09-23 10:28	54.59	OK
18715	2026-09-23 10:29	51.52	OK	18716	2026-09-23 10:30	53.46	OK
18717	2026-09-23 10:31	54.57	OK	18718	2026-09-23 10:32	53.58	OK
18719	2026-09-23 10:33	55.33	OK	18720	2026-09-23 10:34	53.97	OK
18721	2026-09-23 10:35	54.80	OK	18722	2026-09-23 10:36	54.53	OK
18723	2026-09-23 10:37	55.55	OK	18724	2026-09-23 10:38	55.67	OK
18725	2026-09-23 10:39	54.02	OK	18726	2026-09-23 10:40	53.61	OK
18727	2026-09-23 10:41	54.23	OK	18728	2026-09-23 10:42	53.21	OK
18729	2026-09-23 10:43	53.56	OK	18730	2026-09-23 10:44	52.22	OK
18731	2026-09-23 10:45	52.55	OK	18732	2026-09-23 10:46	53.40	OK
18733	2026-09-23 10:47	53.40	OK	18734	2026-09-23 10:48	54.21	OK
18735	2026-09-23 10:49	54.33	OK	18736	2026-09-23 10:50	54.76	OK
18737	2026-09-23 10:51	54.73	OK	18738	2026-09-23 10:52	52.95	OK
18739	2026-09-23 10:53	54.32	OK	18740	2026-09-23 10:54	54.52	OK
18741	2026-09-23 10:55	54.90	OK	18742	2026-09-23 10:56	54.51	OK
18743	2026-09-23 10:57	52.88	OK	18744	2026-09-23 10:58	53.73	OK
18745	2026-09-23 10:59	54.19	OK	18746	2026-09-23 11:00	53.57	OK
18747	2026-09-23 11:01	56.23	OK	18748	2026-09-23 11:02	53.59	OK
18749	2026-09-23 11:03	54.51	OK	18750	2026-09-23 11:04	53.05	OK
18751	2026-09-23 11:05	54.35	OK	18752	2026-09-23 11:06	53.42	OK
18753	2026-09-23 11:07	54.87	OK	18754	2026-09-23 11:08	54.45	OK
18755	2026-09-23 11:09	52.87	OK	18756	2026-09-23 11:10	53.70	OK
18757	2026-09-23 11:11	54.03	OK	18758	2026-09-23 11:12	53.91	OK
18759	2026-09-23 11:13	53.84	OK	18760	2026-09-23 11:14	54.83	OK
18761	2026-09-23 11:15	53.17	OK	18762	2026-09-23 11:16	53.17	OK
1876	2026-09-23 11:17	52.47	OK	1876	2026-09-23 11:18	54.47	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
18765	2026-09-23 11:19	54.89	OK	18766	2026-09-23 11:20	54.21	OK
18767	2026-09-23 11:21	55.91	OK	18768	2026-09-23 11:22	53.01	OK
18769	2026-09-23 11:23	52.86	OK	18770	2026-09-23 11:24	54.84	OK
18771	2026-09-23 11:25	53.99	OK	18772	2026-09-23 11:26	53.80	OK
18773	2026-09-23 11:27	52.29	OK	18774	2026-09-23 11:28	54.00	OK
18775	2026-09-23 11:29	52.18	OK	18776	2026-09-23 11:30	54.63	OK
18777	2026-09-23 11:31	53.24	OK	18778	2026-09-23 11:32	53.68	OK
18779	2026-09-23 11:33	52.97	OK	18780	2026-09-23 11:34	55.34	OK
18781	2026-09-23 11:35	56.40	OK	18782	2026-09-23 11:36	54.64	OK
18783	2026-09-23 11:37	54.86	OK	18784	2026-09-23 11:38	53.95	OK
18785	2026-09-23 11:39	53.57	OK	18786	2026-09-23 11:40	56.35	OK
18787	2026-09-23 11:41	55.07	OK	18788	2026-09-23 11:42	53.19	OK
18789	2026-09-23 11:43	52.28	OK	18790	2026-09-23 11:44	55.94	OK
18791	2026-09-23 11:45	53.10	OK	18792	2026-09-23 11:46	54.30	OK
18793	2026-09-23 11:47	52.93	OK	18794	2026-09-23 11:48	52.53	OK
18795	2026-09-23 11:49	53.74	OK	18796	2026-09-23 11:50	56.36	OK
18797	2026-09-23 11:51	53.31	OK	18798	2026-09-23 11:52	53.56	OK
18799	2026-09-23 11:53	56.35	OK	18800	2026-09-23 11:54	53.01	OK
18801	2026-09-23 11:55	55.09	OK	18802	2026-09-23 11:56	54.28	OK
18803	2026-09-23 11:57	53.72	OK	18804	2026-09-23 11:58	52.60	OK
18805	2026-09-23 11:59	54.70	OK	18806	2026-09-23 12:00	54.21	OK
18807	2026-09-23 12:01	55.12	OK	18808	2026-09-23 12:02	56.15	OK
18809	2026-09-23 12:03	53.98	OK	18810	2026-09-23 12:04	52.90	OK
18811	2026-09-23 12:05	55.48	OK	18812	2026-09-23 12:06	53.94	OK
18813	2026-09-23 12:07	53.69	OK	18814	2026-09-23 12:08	54.28	OK
18815	2026-09-23 12:09	54.56	OK	18816	2026-09-23 12:10	54.52	OK
18817	2026-09-23 12:11	52.91	OK	18818	2026-09-23 12:12	55.24	OK
18819	2026-09-23 12:13	53.43	OK	18820	2026-09-23 12:14	54.22	OK
18821	2026-09-23 12:15	56.08	OK	18822	2026-09-23 12:16	52.53	OK
1882	2026-09-23 12:17	53.87	OK	1882	2026-09-23 12:18	55.63	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
18825	2026-09-23 12:19	54.08	OK	18826	2026-09-23 12:20	54.51	OK
18827	2026-09-23 12:21	53.45	OK	18828	2026-09-23 12:22	53.83	OK
18829	2026-09-23 12:23	54.49	OK	18830	2026-09-23 12:24	53.82	OK
18831	2026-09-23 12:25	54.73	OK	18832	2026-09-23 12:26	55.89	OK
18833	2026-09-23 12:27	55.46	OK	18834	2026-09-23 12:28	54.20	OK
18835	2026-09-23 12:29	56.11	OK	18836	2026-09-23 12:30	53.63	OK
18837	2026-09-23 12:31	54.73	OK	18838	2026-09-23 12:32	51.87	OK
18839	2026-09-23 12:33	53.64	OK	18840	2026-09-23 12:34	53.91	OK
18841	2026-09-23 12:35	53.00	OK	18842	2026-09-23 12:36	52.80	OK
18843	2026-09-23 12:37	51.91	OK	18844	2026-09-23 12:38	54.61	OK
18845	2026-09-23 12:39	54.43	OK	18846	2026-09-23 12:40	54.24	OK
18847	2026-09-23 12:41	53.37	OK	18848	2026-09-23 12:42	55.59	OK
18849	2026-09-23 12:43	56.15	OK	18850	2026-09-23 12:44	55.75	OK
18851	2026-09-23 12:45	52.00	OK	18852	2026-09-23 12:46	56.59	OK
18853	2026-09-23 12:47	53.34	OK	18854	2026-09-23 12:48	53.64	OK
18855	2026-09-23 12:49	54.65	OK	18856	2026-09-23 12:50	55.04	OK
18857	2026-09-23 12:51	55.30	OK	18858	2026-09-23 12:52	54.35	OK
18859	2026-09-23 12:53	53.99	OK	18860	2026-09-23 12:54	55.84	OK
18861	2026-09-23 12:55	53.00	OK	18862	2026-09-23 12:56	52.71	OK
18863	2026-09-23 12:57	54.58	OK	18864	2026-09-23 12:58	52.64	OK
18865	2026-09-23 12:59	53.20	OK	18866	2026-09-23 13:00	53.82	OK
18867	2026-09-23 13:01	53.96	OK	18868	2026-09-23 13:02	53.97	OK
18869	2026-09-23 13:03	54.69	OK	18870	2026-09-23 13:04	53.40	OK
18871	2026-09-23 13:05	53.59	OK	18872	2026-09-23 13:06	54.85	OK
18873	2026-09-23 13:07	51.59	OK	18874	2026-09-23 13:08	53.12	OK
18875	2026-09-23 13:09	52.37	OK	18876	2026-09-23 13:10	53.83	OK
18877	2026-09-23 13:11	54.28	OK	18878	2026-09-23 13:12	54.04	OK
18879	2026-09-23 13:13	54.90	OK	18880	2026-09-23 13:14	53.28	OK
18881	2026-09-23 13:15	53.95	OK	18882	2026-09-23 13:16	55.74	OK
1888	2026-09-23 13:17	56.18	OK	1888	2026-09-23 13:18	52.25	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
18885	2026-09-23 13:19	54.91	OK	18886	2026-09-23 13:20	52.96	OK
18887	2026-09-23 13:21	53.77	OK	18888	2026-09-23 13:22	52.95	OK
18889	2026-09-23 13:23	52.26	OK	18890	2026-09-23 13:24	54.82	OK
18891	2026-09-23 13:25	53.51	OK	18892	2026-09-23 13:26	52.49	OK
18893	2026-09-23 13:27	51.85	OK	18894	2026-09-23 13:28	53.36	OK
18895	2026-09-23 13:29	52.90	OK	18896	2026-09-23 13:30	53.90	OK
18897	2026-09-23 13:31	54.78	OK	18898	2026-09-23 13:32	53.79	OK
18899	2026-09-23 13:33	53.11	OK	18900	2026-09-23 13:34	53.05	OK
18901	2026-09-23 13:35	53.36	OK	18902	2026-09-23 13:36	52.65	OK
18903	2026-09-23 13:37	54.17	OK	18904	2026-09-23 13:38	51.96	OK
18905	2026-09-23 13:39	56.19	OK	18906	2026-09-23 13:40	54.86	OK
18907	2026-09-23 13:41	53.94	OK	18908	2026-09-23 13:42	55.05	OK
18909	2026-09-23 13:43	54.93	OK	18910	2026-09-23 13:44	54.20	OK
18911	2026-09-23 13:45	55.43	OK	18912	2026-09-23 13:46	52.51	OK
18913	2026-09-23 13:47	54.15	OK	18914	2026-09-23 13:48	55.45	OK
18915	2026-09-23 13:49	54.00	OK	18916	2026-09-23 13:50	52.59	OK
18917	2026-09-23 13:51	54.94	OK	18918	2026-09-23 13:52	52.44	OK
18919	2026-09-23 13:53	53.59	OK	18920	2026-09-23 13:54	53.55	OK
18921	2026-09-23 13:55	52.82	OK	18922	2026-09-23 13:56	52.41	OK
18923	2026-09-23 13:57	53.28	OK	18924	2026-09-23 13:58	53.58	OK
18925	2026-09-23 13:59	53.98	OK	18926	2026-09-23 14:00	54.48	OK
18927	2026-09-23 14:01	52.98	OK	18928	2026-09-23 14:02	51.74	OK
18929	2026-09-23 14:03	53.99	OK	18930	2026-09-23 14:04	55.02	OK
18931	2026-09-23 14:05	52.89	OK	18932	2026-09-23 14:06	51.29	OK
18933	2026-09-23 14:07	55.33	OK	18934	2026-09-23 14:08	53.02	OK
18935	2026-09-23 14:09	51.99	OK	18936	2026-09-23 14:10	53.66	OK
18937	2026-09-23 14:11	52.89	OK	18938	2026-09-23 14:12	54.06	OK
18939	2026-09-23 14:13	52.24	OK	18940	2026-09-23 14:14	51.14	OK
18941	2026-09-23 14:15	52.84	OK	18942	2026-09-23 14:16	50.01	OK
1894	2026-09-23 14:17	53.97	OK	1894	2026-09-23 14:18	55.10	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
18945	2026-09-23 14:19	53.62	OK	18946	2026-09-23 14:20	54.43	OK
18947	2026-09-23 14:21	52.97	OK	18948	2026-09-23 14:22	53.23	OK
18949	2026-09-23 14:23	52.64	OK	18950	2026-09-23 14:24	53.70	OK
18951	2026-09-23 14:25	53.00	OK	18952	2026-09-23 14:26	52.58	OK
18953	2026-09-23 14:27	54.08	OK	18954	2026-09-23 14:28	52.18	OK
18955	2026-09-23 14:29	52.07	OK	18956	2026-09-23 14:30	53.89	OK
18957	2026-09-23 14:31	52.68	OK	18958	2026-09-23 14:32	51.40	OK
18959	2026-09-23 14:33	52.64	OK	18960	2026-09-23 14:34	52.88	OK
18961	2026-09-23 14:35	51.84	OK	18962	2026-09-23 14:36	52.20	OK
18963	2026-09-23 14:37	51.51	OK	18964	2026-09-23 14:38	52.59	OK
18965	2026-09-23 14:39	52.92	OK	18966	2026-09-23 14:40	54.17	OK
18967	2026-09-23 14:41	53.23	OK	18968	2026-09-23 14:42	53.39	OK
18969	2026-09-23 14:43	51.50	OK	18970	2026-09-23 14:44	50.00	OK
18971	2026-09-23 14:45	54.38	OK	18972	2026-09-23 14:46	54.75	OK
18973	2026-09-23 14:47	52.29	OK	18974	2026-09-23 14:48	53.69	OK
18975	2026-09-23 14:49	53.24	OK	18976	2026-09-23 14:50	51.88	OK
18977	2026-09-23 14:51	53.25	OK	18978	2026-09-23 14:52	52.24	OK
18979	2026-09-23 14:53	51.79	OK	18980	2026-09-23 14:54	54.12	OK
18981	2026-09-23 14:55	51.44	OK	18982	2026-09-23 14:56	51.31	OK
18983	2026-09-23 14:57	53.10	OK	18984	2026-09-23 14:58	51.32	OK
18985	2026-09-23 14:59	54.57	OK	18986	2026-09-23 15:00	53.27	OK
18987	2026-09-23 15:01	52.29	OK	18988	2026-09-23 15:02	53.31	OK
18989	2026-09-23 15:03	52.73	OK	18990	2026-09-23 15:04	51.24	OK
18991	2026-09-23 15:05	52.41	OK	18992	2026-09-23 15:06	51.30	OK
18993	2026-09-23 15:07	51.64	OK	18994	2026-09-23 15:08	52.64	OK
18995	2026-09-23 15:09	53.18	OK	18996	2026-09-23 15:10	51.20	OK
18997	2026-09-23 15:11	53.88	OK	18998	2026-09-23 15:12	50.18	OK
18999	2026-09-23 15:13	51.26	OK	19000	2026-09-23 15:14	51.08	OK
19001	2026-09-23 15:15	52.30	OK	19002	2026-09-23 15:16	51.31	OK
1900	2026-09-23 15:17	52.76	OK	1900	2026-09-23 15:18	50.55	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
19005	2026-09-23 15:19	52.39	OK	19006	2026-09-23 15:20	51.36	OK
19007	2026-09-23 15:21	50.99	OK	19008	2026-09-23 15:22	52.16	OK
19009	2026-09-23 15:23	52.66	OK	19010	2026-09-23 15:24	51.98	OK
19011	2026-09-23 15:25	53.72	OK	19012	2026-09-23 15:26	50.63	OK
19013	2026-09-23 15:27	53.57	OK	19014	2026-09-23 15:28	50.35	OK
19015	2026-09-23 15:29	50.33	OK	19016	2026-09-23 15:30	54.17	OK
19017	2026-09-23 15:31	52.85	OK	19018	2026-09-23 15:32	51.87	OK
19019	2026-09-23 15:33	52.96	OK	19020	2026-09-23 15:34	51.29	OK
19021	2026-09-23 15:35	49.90	OK	19022	2026-09-23 15:36	52.56	OK
19023	2026-09-23 15:37	50.17	OK	19024	2026-09-23 15:38	51.40	OK
19025	2026-09-23 15:39	50.05	OK	19026	2026-09-23 15:40	51.20	OK
19027	2026-09-23 15:41	51.59	OK	19028	2026-09-23 15:42	51.65	OK
19029	2026-09-23 15:43	49.13	OK	19030	2026-09-23 15:44	53.06	OK
19031	2026-09-23 15:45	52.10	OK	19032	2026-09-23 15:46	50.93	OK
19033	2026-09-23 15:47	51.75	OK	19034	2026-09-23 15:48	50.57	OK
19035	2026-09-23 15:49	50.84	OK	19036	2026-09-23 15:50	51.94	OK
19037	2026-09-23 15:51	50.69	OK	19038	2026-09-23 15:52	53.30	OK
19039	2026-09-23 15:53	53.43	OK	19040	2026-09-23 15:54	51.25	OK
19041	2026-09-23 15:55	51.17	OK	19042	2026-09-23 15:56	51.74	OK
19043	2026-09-23 15:57	52.43	OK	19044	2026-09-23 15:58	51.58	OK
19045	2026-09-23 15:59	49.99	OK	19046	2026-09-23 16:00	50.34	OK
19047	2026-09-23 16:01	49.48	OK	19048	2026-09-23 16:02	51.77	OK
19049	2026-09-23 16:03	51.26	OK	19050	2026-09-23 16:04	52.65	OK
19051	2026-09-23 16:05	50.37	OK	19052	2026-09-23 16:06	51.67	OK
19053	2026-09-23 16:07	51.35	OK	19054	2026-09-23 16:08	50.73	OK
19055	2026-09-23 16:09	51.15	OK	19056	2026-09-23 16:10	50.72	OK
19057	2026-09-23 16:11	50.50	OK	19058	2026-09-23 16:12	52.63	OK
19059	2026-09-23 16:13	50.08	OK	19060	2026-09-23 16:14	49.12	OK
19061	2026-09-23 16:15	50.71	OK	19062	2026-09-23 16:16	48.81	OK
1906	2026-09-23 16:17	51.45	OK	1906	2026-09-23 16:18	48.79	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
19065	2026-09-23 16:19	49.53	OK	19066	2026-09-23 16:20	52.05	OK
19067	2026-09-23 16:21	51.58	OK	19068	2026-09-23 16:22	49.90	OK
19069	2026-09-23 16:23	49.67	OK	19070	2026-09-23 16:24	50.67	OK
19071	2026-09-23 16:25	50.45	OK	19072	2026-09-23 16:26	51.26	OK
19073	2026-09-23 16:27	49.93	OK	19074	2026-09-23 16:28	52.82	OK
19075	2026-09-23 16:29	50.61	OK	19076	2026-09-23 16:30	50.88	OK
19077	2026-09-23 16:31	48.60	OK	19078	2026-09-23 16:32	52.07	OK
19079	2026-09-23 16:33	49.41	OK	19080	2026-09-23 16:34	49.13	OK
19081	2026-09-23 16:35	49.90	OK	19082	2026-09-23 16:36	50.90	OK
19083	2026-09-23 16:37	50.56	OK	19084	2026-09-23 16:38	50.71	OK
19085	2026-09-23 16:39	50.36	OK	19086	2026-09-23 16:40	49.81	OK
19087	2026-09-23 16:41	51.84	OK	19088	2026-09-23 16:42	49.26	OK
19089	2026-09-23 16:43	48.65	OK	19090	2026-09-23 16:44	49.18	OK
19091	2026-09-23 16:45	50.41	OK	19092	2026-09-23 16:46	49.77	OK
19093	2026-09-23 16:47	50.98	OK	19094	2026-09-23 16:48	48.75	OK
19095	2026-09-23 16:49	49.98	OK	19096	2026-09-23 16:50	49.29	OK
19097	2026-09-23 16:51	51.28	OK	19098	2026-09-23 16:52	51.52	OK
19099	2026-09-23 16:53	50.44	OK	19100	2026-09-23 16:54	49.93	OK
19101	2026-09-23 16:55	49.97	OK	19102	2026-09-23 16:56	47.70	OK
19103	2026-09-23 16:57	50.31	OK	19104	2026-09-23 16:58	50.67	OK
19105	2026-09-23 16:59	49.49	OK	19106	2026-09-23 17:00	49.11	OK
19107	2026-09-23 17:01	52.66	OK	19108	2026-09-23 17:02	50.38	OK
19109	2026-09-23 17:03	48.83	OK	19110	2026-09-23 17:04	47.83	OK
19111	2026-09-23 17:05	48.28	OK	19112	2026-09-23 17:06	48.99	OK
19113	2026-09-23 17:07	50.50	OK	19114	2026-09-23 17:08	49.48	OK
19115	2026-09-23 17:09	50.53	OK	19116	2026-09-23 17:10	49.08	OK
19117	2026-09-23 17:11	49.12	OK	19118	2026-09-23 17:12	50.41	OK
19119	2026-09-23 17:13	48.86	OK	19120	2026-09-23 17:14	49.96	OK
19121	2026-09-23 17:15	47.85	OK	19122	2026-09-23 17:16	49.01	OK
1912	2026-09-23 17:17	50.49	OK	1912	2026-09-23 17:18	48.81	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
19125	2026-09-23 17:19	50.02	OK	19126	2026-09-23 17:20	47.14	OK
19127	2026-09-23 17:21	50.30	OK	19128	2026-09-23 17:22	48.99	OK
19129	2026-09-23 17:23	49.30	OK	19130	2026-09-23 17:24	49.05	OK
19131	2026-09-23 17:25	51.13	OK	19132	2026-09-23 17:26	49.71	OK
19133	2026-09-23 17:27	48.62	OK	19134	2026-09-23 17:28	49.85	OK
19135	2026-09-23 17:29	51.64	OK	19136	2026-09-23 17:30	49.12	OK
19137	2026-09-23 17:31	47.16	OK	19138	2026-09-23 17:32	50.76	OK
19139	2026-09-23 17:33	47.43	OK	19140	2026-09-23 17:34	48.97	OK
19141	2026-09-23 17:35	50.64	OK	19142	2026-09-23 17:36	48.05	OK
19143	2026-09-23 17:37	48.72	OK	19144	2026-09-23 17:38	49.12	OK
19145	2026-09-23 17:39	49.47	OK	19146	2026-09-23 17:40	49.21	OK
19147	2026-09-23 17:41	51.64	OK	19148	2026-09-23 17:42	49.12	OK
19149	2026-09-23 17:43	49.21	OK	19150	2026-09-23 17:44	49.67	OK
19151	2026-09-23 17:45	46.55	OK	19152	2026-09-23 17:46	49.82	OK
19153	2026-09-23 17:47	48.83	OK	19154	2026-09-23 17:48	48.96	OK
19155	2026-09-23 17:49	48.93	OK	19156	2026-09-23 17:50	49.90	OK
19157	2026-09-23 17:51	50.11	OK	19158	2026-09-23 17:52	47.01	OK
19159	2026-09-23 17:53	49.52	OK	19160	2026-09-23 17:54	48.78	OK
19161	2026-09-23 17:55	47.81	OK	19162	2026-09-23 17:56	50.23	OK
19163	2026-09-23 17:57	47.74	OK	19164	2026-09-23 17:58	50.93	OK
19165	2026-09-23 17:59	47.58	OK	19166	2026-09-23 18:00	49.72	OK
19167	2026-09-23 18:01	48.83	OK	19168	2026-09-23 18:02	49.39	OK
19169	2026-09-23 18:03	46.88	OK	19170	2026-09-23 18:04	48.63	OK
19171	2026-09-23 18:05	47.99	OK	19172	2026-09-23 18:06	49.97	OK
19173	2026-09-23 18:07	49.03	OK	19174	2026-09-23 18:08	47.00	OK
19175	2026-09-23 18:09	48.03	OK	19176	2026-09-23 18:10	49.36	OK
19177	2026-09-23 18:11	49.28	OK	19178	2026-09-23 18:12	48.81	OK
19179	2026-09-23 18:13	49.18	OK	19180	2026-09-23 18:14	50.27	OK
19181	2026-09-23 18:15	48.79	OK	19182	2026-09-23 18:16	50.42	OK
1918	2026-09-23 18:17	49.61	OK	1918	2026-09-23 18:18	48.34	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
19185	2026-09-23 18:19	48.32	OK	19186	2026-09-23 18:20	48.32	OK
19187	2026-09-23 18:21	46.85	OK	19188	2026-09-23 18:22	46.33	OK
19189	2026-09-23 18:23	48.68	OK	19190	2026-09-23 18:24	47.90	OK
19191	2026-09-23 18:25	46.19	OK	19192	2026-09-23 18:26	46.60	OK
19193	2026-09-23 18:27	50.27	OK	19194	2026-09-23 18:28	50.13	OK
19195	2026-09-23 18:29	47.63	OK	19196	2026-09-23 18:30	46.93	OK
19197	2026-09-23 18:31	49.15	OK	19198	2026-09-23 18:32	50.00	OK
19199	2026-09-23 18:33	49.01	OK	19200	2026-09-23 18:34	47.66	OK
19201	2026-09-23 18:35	49.58	OK	19202	2026-09-23 18:36	46.89	OK
19203	2026-09-23 18:37	49.14	OK	19204	2026-09-23 18:38	48.28	OK
19205	2026-09-23 18:39	48.38	OK	19206	2026-09-23 18:40	48.71	OK
19207	2026-09-23 18:41	46.92	OK	19208	2026-09-23 18:42	48.72	OK
19209	2026-09-23 18:43	47.92	OK	19210	2026-09-23 18:44	46.40	OK
19211	2026-09-23 18:45	47.02	OK	19212	2026-09-23 18:46	47.68	OK
19213	2026-09-23 18:47	46.69	OK	19214	2026-09-23 18:48	47.21	OK
19215	2026-09-23 18:49	48.59	OK	19216	2026-09-23 18:50	48.04	OK
19217	2026-09-23 18:51	47.72	OK	19218	2026-09-23 18:52	47.22	OK
19219	2026-09-23 18:53	47.80	OK	19220	2026-09-23 18:54	46.67	OK
19221	2026-09-23 18:55	46.52	OK	19222	2026-09-23 18:56	46.88	OK
19223	2026-09-23 18:57	47.42	OK	19224	2026-09-23 18:58	48.73	OK
19225	2026-09-23 18:59	47.68	OK	19226	2026-09-23 19:00	46.29	OK
19227	2026-09-23 19:01	49.25	OK	19228	2026-09-23 19:02	48.71	OK
19229	2026-09-23 19:03	48.03	OK	19230	2026-09-23 19:04	47.25	OK
19231	2026-09-23 19:05	48.77	OK	19232	2026-09-23 19:06	47.63	OK
19233	2026-09-23 19:07	46.15	OK	19234	2026-09-23 19:08	48.24	OK
19235	2026-09-23 19:09	47.73	OK	19236	2026-09-23 19:10	48.78	OK
19237	2026-09-23 19:11	49.02	OK	19238	2026-09-23 19:12	46.66	OK
19239	2026-09-23 19:13	48.49	OK	19240	2026-09-23 19:14	48.33	OK
19241	2026-09-23 19:15	47.08	OK	19242	2026-09-23 19:16	46.23	OK
1924	2026-09-23 19:17	48.91	OK	1924	2026-09-23 19:18	45.28	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
19245	2026-09-23 19:19	48.83	OK	19246	2026-09-23 19:20	46.47	OK
19247	2026-09-23 19:21	46.63	OK	19248	2026-09-23 19:22	47.95	OK
19249	2026-09-23 19:23	45.28	OK	19250	2026-09-23 19:24	45.40	OK
19251	2026-09-23 19:25	48.74	OK	19252	2026-09-23 19:26	47.22	OK
19253	2026-09-23 19:27	47.39	OK	19254	2026-09-23 19:28	49.27	OK
19255	2026-09-23 19:29	46.90	OK	19256	2026-09-23 19:30	46.53	OK
19257	2026-09-23 19:31	47.05	OK	19258	2026-09-23 19:32	47.35	OK
19259	2026-09-23 19:33	45.42	OK	19260	2026-09-23 19:34	47.77	OK
19261	2026-09-23 19:35	46.86	OK	19262	2026-09-23 19:36	46.05	OK
19263	2026-09-23 19:37	46.35	OK	19264	2026-09-23 19:38	46.90	OK
19265	2026-09-23 19:39	45.10	OK	19266	2026-09-23 19:40	48.84	OK
19267	2026-09-23 19:41	46.35	OK	19268	2026-09-23 19:42	48.75	OK
19269	2026-09-23 19:43	46.12	OK	19270	2026-09-23 19:44	47.33	OK
19271	2026-09-23 19:45	46.58	OK	19272	2026-09-23 19:46	46.32	OK
19273	2026-09-23 19:47	47.31	OK	19274	2026-09-23 19:48	48.87	OK
19275	2026-09-23 19:49	46.98	OK	19276	2026-09-23 19:50	48.27	OK
19277	2026-09-23 19:51	47.28	OK	19278	2026-09-23 19:52	47.07	OK
19279	2026-09-23 19:53	47.70	OK	19280	2026-09-23 19:54	47.37	OK
19281	2026-09-23 19:55	46.15	OK	19282	2026-09-23 19:56	45.52	OK
19283	2026-09-23 19:57	45.93	OK	19284	2026-09-23 19:58	47.96	OK
19285	2026-09-23 19:59	46.42	OK	19286	2026-09-23 20:00	46.12	OK
19287	2026-09-23 20:01	48.89	OK	19288	2026-09-23 20:02	46.97	OK
19289	2026-09-23 20:03	48.86	OK	19290	2026-09-23 20:04	47.76	OK
19291	2026-09-23 20:05	46.54	OK	19292	2026-09-23 20:06	45.12	OK
19293	2026-09-23 20:07	45.05	OK	19294	2026-09-23 20:08	46.38	OK
19295	2026-09-23 20:09	46.43	OK	19296	2026-09-23 20:10	47.19	OK
19297	2026-09-23 20:11	45.36	OK	19298	2026-09-23 20:12	46.49	OK
19299	2026-09-23 20:13	48.11	OK	19300	2026-09-23 20:14	46.07	OK
19301	2026-09-23 20:15	45.35	OK	19302	2026-09-23 20:16	46.83	OK
19303	2026-09-23 20:17	46.92	OK	19303	2026-09-23 20:18	47.75	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
19305	2026-09-23 20:19	47.71	OK	19306	2026-09-23 20:20	46.36	OK
19307	2026-09-23 20:21	45.02	OK	19308	2026-09-23 20:22	46.03	OK
19309	2026-09-23 20:23	47.92	OK	19310	2026-09-23 20:24	43.87	OK
19311	2026-09-23 20:25	45.92	OK	19312	2026-09-23 20:26	43.83	OK
19313	2026-09-23 20:27	44.94	OK	19314	2026-09-23 20:28	44.93	OK
19315	2026-09-23 20:29	47.36	OK	19316	2026-09-23 20:30	44.86	OK
19317	2026-09-23 20:31	45.43	OK	19318	2026-09-23 20:32	45.40	OK
19319	2026-09-23 20:33	46.97	OK	19320	2026-09-23 20:34	48.21	OK
19321	2026-09-23 20:35	45.68	OK	19322	2026-09-23 20:36	44.90	OK
19323	2026-09-23 20:37	46.40	OK	19324	2026-09-23 20:38	44.65	OK
19325	2026-09-23 20:39	47.65	OK	19326	2026-09-23 20:40	46.37	OK
19327	2026-09-23 20:41	45.90	OK	19328	2026-09-23 20:42	48.51	OK
19329	2026-09-23 20:43	45.03	OK	19330	2026-09-23 20:44	45.85	OK
19331	2026-09-23 20:45	45.12	OK	19332	2026-09-23 20:46	47.13	OK
19333	2026-09-23 20:47	45.32	OK	19334	2026-09-23 20:48	46.91	OK
19335	2026-09-23 20:49	44.58	OK	19336	2026-09-23 20:50	45.76	OK
19337	2026-09-23 20:51	46.67	OK	19338	2026-09-23 20:52	45.32	OK
19339	2026-09-23 20:53	45.54	OK	19340	2026-09-23 20:54	46.64	OK
19341	2026-09-23 20:55	44.13	OK	19342	2026-09-23 20:56	46.33	OK
19343	2026-09-23 20:57	44.29	OK	19344	2026-09-23 20:58	45.95	OK
19345	2026-09-23 20:59	44.54	OK	19346	2026-09-23 21:00	44.83	OK
19347	2026-09-23 21:01	46.09	OK	19348	2026-09-23 21:02	44.52	OK
19349	2026-09-23 21:03	44.07	OK	19350	2026-09-23 21:04	44.81	OK
19351	2026-09-23 21:05	44.97	OK	19352	2026-09-23 21:06	45.74	OK
19353	2026-09-23 21:07	44.31	OK	19354	2026-09-23 21:08	46.20	OK
19355	2026-09-23 21:09	46.56	OK	19356	2026-09-23 21:10	45.80	OK
19357	2026-09-23 21:11	47.03	OK	19358	2026-09-23 21:12	45.80	OK
19359	2026-09-23 21:13	46.04	OK	19360	2026-09-23 21:14	44.79	OK
19361	2026-09-23 21:15	43.79	OK	19362	2026-09-23 21:16	45.13	OK
1936	2026-09-23 21:17	43.89	OK	1936	2026-09-23 21:18	47.00	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
19365	2026-09-23 21:19	46.90	OK	19366	2026-09-23 21:20	45.50	OK
19367	2026-09-23 21:21	44.31	OK	19368	2026-09-23 21:22	47.37	OK
19369	2026-09-23 21:23	44.97	OK	19370	2026-09-23 21:24	44.08	OK
19371	2026-09-23 21:25	45.57	OK	19372	2026-09-23 21:26	44.21	OK
19373	2026-09-23 21:27	43.66	OK	19374	2026-09-23 21:28	44.97	OK
19375	2026-09-23 21:29	44.41	OK	19376	2026-09-23 21:30	45.79	OK
19377	2026-09-23 21:31	45.89	OK	19378	2026-09-23 21:32	44.09	OK
19379	2026-09-23 21:33	46.23	OK	19380	2026-09-23 21:34	45.25	OK
19381	2026-09-23 21:35	45.06	OK	19382	2026-09-23 21:36	46.72	OK
19383	2026-09-23 21:37	46.75	OK	19384	2026-09-23 21:38	46.56	OK
19385	2026-09-23 21:39	47.05	OK	19386	2026-09-23 21:40	46.76	OK
19387	2026-09-23 21:41	43.37	OK	19388	2026-09-23 21:42	46.19	OK
19389	2026-09-23 21:43	44.28	OK	19390	2026-09-23 21:44	45.88	OK
19391	2026-09-23 21:45	44.44	OK	19392	2026-09-23 21:46	47.39	OK
19393	2026-09-23 21:47	43.66	OK	19394	2026-09-23 21:48	43.90	OK
19395	2026-09-23 21:49	44.12	OK	19396	2026-09-23 21:50	46.08	OK
19397	2026-09-23 21:51	43.44	OK	19398	2026-09-23 21:52	43.69	OK
19399	2026-09-23 21:53	45.11	OK	19400	2026-09-23 21:54	46.40	OK
19401	2026-09-23 21:55	44.11	OK	19402	2026-09-23 21:56	46.29	OK
19403	2026-09-23 21:57	46.28	OK	19404	2026-09-23 21:58	44.70	OK
19405	2026-09-23 21:59	44.69	OK	19406	2026-09-23 22:00	46.07	OK
19407	2026-09-23 22:01	46.18	OK	19408	2026-09-23 22:02	45.09	OK
19409	2026-09-23 22:03	43.68	OK	19410	2026-09-23 22:04	45.42	OK
19411	2026-09-23 22:05	45.36	OK	19412	2026-09-23 22:06	45.52	OK
19413	2026-09-23 22:07	45.07	OK	19414	2026-09-23 22:08	45.75	OK
19415	2026-09-23 22:09	44.80	OK	19416	2026-09-23 22:10	45.36	OK
19417	2026-09-23 22:11	45.09	OK	19418	2026-09-23 22:12	45.93	OK
19419	2026-09-23 22:13	45.00	OK	19420	2026-09-23 22:14	43.79	OK
19421	2026-09-23 22:15	45.91	OK	19422	2026-09-23 22:16	45.32	OK
1942	2026-09-23 22:17	44.96	OK	1942	2026-09-23 22:18	46.09	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
19425	2026-09-23 22:19	45.48	OK	19426	2026-09-23 22:20	44.62	OK
19427	2026-09-23 22:21	44.89	OK	19428	2026-09-23 22:22	45.26	OK
19429	2026-09-23 22:23	46.26	OK	19430	2026-09-23 22:24	44.84	OK
19431	2026-09-23 22:25	44.53	OK	19432	2026-09-23 22:26	44.37	OK
19433	2026-09-23 22:27	43.95	OK	19434	2026-09-23 22:28	45.14	OK
19435	2026-09-23 22:29	43.46	OK	19436	2026-09-23 22:30	45.08	OK
19437	2026-09-23 22:31	44.96	OK	19438	2026-09-23 22:32	44.83	OK
19439	2026-09-23 22:33	45.46	OK	19440	2026-09-23 22:34	45.94	OK
19441	2026-09-23 22:35	46.37	OK	19442	2026-09-23 22:36	45.03	OK
19443	2026-09-23 22:37	44.05	OK	19444	2026-09-23 22:38	43.29	OK
19445	2026-09-23 22:39	45.51	OK	19446	2026-09-23 22:40	43.94	OK
19447	2026-09-23 22:41	44.35	OK	19448	2026-09-23 22:42	46.04	OK
19449	2026-09-23 22:43	46.33	OK	19450	2026-09-23 22:44	44.03	OK
19451	2026-09-23 22:45	45.43	OK	19452	2026-09-23 22:46	44.39	OK
19453	2026-09-23 22:47	44.34	OK	19454	2026-09-23 22:48	43.43	OK
19455	2026-09-23 22:49	44.34	OK	19456	2026-09-23 22:50	44.88	OK
19457	2026-09-23 22:51	44.76	OK	19458	2026-09-23 22:52	43.31	OK
19459	2026-09-23 22:53	44.76	OK	19460	2026-09-23 22:54	45.80	OK
19461	2026-09-23 22:55	43.23	OK	19462	2026-09-23 22:56	45.85	OK
19463	2026-09-23 22:57	46.37	OK	19464	2026-09-23 22:58	44.55	OK
19465	2026-09-23 22:59	45.04	OK	19466	2026-09-23 23:00	44.78	OK
19467	2026-09-23 23:01	44.22	OK	19468	2026-09-23 23:02	46.44	OK
19469	2026-09-23 23:03	43.31	OK	19470	2026-09-23 23:04	44.42	OK
19471	2026-09-23 23:05	44.60	OK	19472	2026-09-23 23:06	44.19	OK
19473	2026-09-23 23:07	42.56	OK	19474	2026-09-23 23:08	45.04	OK
19475	2026-09-23 23:09	46.82	OK	19476	2026-09-23 23:10	45.58	OK
19477	2026-09-23 23:11	45.04	OK	19478	2026-09-23 23:12	43.33	OK
19479	2026-09-23 23:13	43.21	OK	19480	2026-09-23 23:14	45.07	OK
19481	2026-09-23 23:15	43.97	OK	19482	2026-09-23 23:16	42.43	OK
1948	2026-09-23 23:17	44.70	OK	1948	2026-09-23 23:18	43.09	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
19485	2026-09-23 23:19	44.89	OK	19486	2026-09-23 23:20	44.52	OK
19487	2026-09-23 23:21	45.39	OK	19488	2026-09-23 23:22	43.86	OK
19489	2026-09-23 23:23	45.19	OK	19490	2026-09-23 23:24	43.22	OK
19491	2026-09-23 23:25	43.45	OK	19492	2026-09-23 23:26	45.41	OK
19493	2026-09-23 23:27	43.81	OK	19494	2026-09-23 23:28	45.01	OK
19495	2026-09-23 23:29	45.05	OK	19496	2026-09-23 23:30	44.65	OK
19497	2026-09-23 23:31	43.39	OK	19498	2026-09-23 23:32	46.46	OK
19499	2026-09-23 23:33	43.73	OK	19500	2026-09-23 23:34	45.20	OK
19501	2026-09-23 23:35	44.64	OK	19502	2026-09-23 23:36	44.29	OK
19503	2026-09-23 23:37	45.27	OK	19504	2026-09-23 23:38	44.94	OK
19505	2026-09-23 23:39	46.70	OK	19506	2026-09-23 23:40	44.38	OK
19507	2026-09-23 23:41	44.25	OK	19508	2026-09-23 23:42	44.86	OK
19509	2026-09-23 23:43	44.54	OK	19510	2026-09-23 23:44	43.10	OK
19511	2026-09-23 23:45	43.69	OK	19512	2026-09-23 23:46	43.57	OK
19513	2026-09-23 23:47	45.09	OK	19514	2026-09-23 23:48	44.72	OK
19515	2026-09-23 23:49	45.38	OK	19516	2026-09-23 23:50	43.42	OK
19517	2026-09-23 23:51	43.07	OK	19518	2026-09-23 23:52	46.17	OK
19519	2026-09-23 23:53	45.09	OK	19520	2026-09-23 23:54	45.24	OK
19521	2026-09-23 23:55	44.58	OK	19522	2026-09-23 23:56	45.67	OK
19523	2026-09-23 23:57	45.22	OK	19524	2026-09-23 23:58	44.95	OK
19525	2026-09-23 23:59	43.12	OK	19526	2026-09-24 00:00	44.85	OK
19527	2026-09-24 00:01	44.36	OK	19528	2026-09-24 00:02	44.19	OK
19529	2026-09-24 00:03	44.45	OK	19530	2026-09-24 00:04	44.00	OK
19531	2026-09-24 00:05	45.40	OK	19532	2026-09-24 00:06	44.85	OK
19533	2026-09-24 00:07	46.38	OK	19534	2026-09-24 00:08	44.84	OK
19535	2026-09-24 00:09	44.51	OK	19536	2026-09-24 00:10	46.83	OK
19537	2026-09-24 00:11	44.69	OK	19538	2026-09-24 00:12	44.54	OK
19539	2026-09-24 00:13	46.06	OK	19540	2026-09-24 00:14	45.85	OK
19541	2026-09-24 00:15	42.83	OK	19542	2026-09-24 00:16	45.92	OK
1954	2026-09-24 00:17	45.67	OK	1954	2026-09-24 00:18	44.05	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
19545	2026-09-24 00:19	45.18	OK	19546	2026-09-24 00:20	45.42	OK
19547	2026-09-24 00:21	43.91	OK	19548	2026-09-24 00:22	46.40	OK
19549	2026-09-24 00:23	46.47	OK	19550	2026-09-24 00:24	45.62	OK
19551	2026-09-24 00:25	46.23	OK	19552	2026-09-24 00:26	45.68	OK
19553	2026-09-24 00:27	45.04	OK	19554	2026-09-24 00:28	44.58	OK
19555	2026-09-24 00:29	43.83	OK	19556	2026-09-24 00:30	44.93	OK
19557	2026-09-24 00:31	44.64	OK	19558	2026-09-24 00:32	45.39	OK
19559	2026-09-24 00:33	45.79	OK	19560	2026-09-24 00:34	45.25	OK
19561	2026-09-24 00:35	46.59	OK	19562	2026-09-24 00:36	44.74	OK
19563	2026-09-24 00:37	45.33	OK	19564	2026-09-24 00:38	44.36	OK
19565	2026-09-24 00:39	43.51	OK	19566	2026-09-24 00:40	43.83	OK
19567	2026-09-24 00:41	43.71	OK	19568	2026-09-24 00:42	46.26	OK
19569	2026-09-24 00:43	44.41	OK	19570	2026-09-24 00:44	42.94	OK
19571	2026-09-24 00:45	44.59	OK	19572	2026-09-24 00:46	45.60	OK
19573	2026-09-24 00:47	45.17	OK	19574	2026-09-24 00:48	43.08	OK
19575	2026-09-24 00:49	43.42	OK	19576	2026-09-24 00:50	44.26	OK
19577	2026-09-24 00:51	45.33	OK	19578	2026-09-24 00:52	45.13	OK
19579	2026-09-24 00:53	43.61	OK	19580	2026-09-24 00:54	45.79	OK
19581	2026-09-24 00:55	45.73	OK	19582	2026-09-24 00:56	45.94	OK
19583	2026-09-24 00:57	44.65	OK	19584	2026-09-24 00:58	43.89	OK
19585	2026-09-24 00:59	44.72	OK	19586	2026-09-24 01:00	43.93	OK
19587	2026-09-24 01:01	44.96	OK	19588	2026-09-24 01:02	43.67	OK
19589	2026-09-24 01:03	44.12	OK	19590	2026-09-24 01:04	43.27	OK
19591	2026-09-24 01:05	44.38	OK	19592	2026-09-24 01:06	44.38	OK
19593	2026-09-24 01:07	44.20	OK	19594	2026-09-24 01:08	45.75	OK
19595	2026-09-24 01:09	42.96	OK	19596	2026-09-24 01:10	47.12	OK
19597	2026-09-24 01:11	43.54	OK	19598	2026-09-24 01:12	45.58	OK
19599	2026-09-24 01:13	46.20	OK	19600	2026-09-24 01:14	44.88	OK
19601	2026-09-24 01:15	45.09	OK	19602	2026-09-24 01:16	46.52	OK
1960	2026-09-24 01:17	44.78	OK	1960	2026-09-24 01:18	47.82	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
19605	2026-09-24 01:19	43.40	OK	19606	2026-09-24 01:20	45.96	OK
19607	2026-09-24 01:21	46.62	OK	19608	2026-09-24 01:22	45.15	OK
19609	2026-09-24 01:23	45.70	OK	19610	2026-09-24 01:24	43.64	OK
19611	2026-09-24 01:25	44.77	OK	19612	2026-09-24 01:26	46.44	OK
19613	2026-09-24 01:27	45.31	OK	19614	2026-09-24 01:28	46.66	OK
19615	2026-09-24 01:29	46.43	OK	19616	2026-09-24 01:30	45.16	OK
19617	2026-09-24 01:31	43.63	OK	19618	2026-09-24 01:32	45.54	OK
19619	2026-09-24 01:33	45.69	OK	19620	2026-09-24 01:34	46.66	OK
19621	2026-09-24 01:35	45.54	OK	19622	2026-09-24 01:36	45.40	OK
19623	2026-09-24 01:37	47.11	OK	19624	2026-09-24 01:38	45.14	OK
19625	2026-09-24 01:39	47.29	OK	19626	2026-09-24 01:40	45.28	OK
19627	2026-09-24 01:41	45.91	OK	19628	2026-09-24 01:42	45.30	OK
19629	2026-09-24 01:43	43.76	OK	19630	2026-09-24 01:44	44.31	OK
19631	2026-09-24 01:45	44.56	OK	19632	2026-09-24 01:46	47.77	OK
19633	2026-09-24 01:47	45.04	OK	19634	2026-09-24 01:48	45.11	OK
19635	2026-09-24 01:49	43.58	OK	19636	2026-09-24 01:50	44.16	OK
19637	2026-09-24 01:51	45.18	OK	19638	2026-09-24 01:52	46.22	OK
19639	2026-09-24 01:53	45.36	OK	19640	2026-09-24 01:54	44.13	OK
19641	2026-09-24 01:55	44.32	OK	19642	2026-09-24 01:56	43.06	OK
19643	2026-09-24 01:57	45.03	OK	19644	2026-09-24 01:58	45.17	OK
19645	2026-09-24 01:59	43.90	OK	19646	2026-09-24 02:00	45.96	OK
19647	2026-09-24 02:01	44.97	OK	19648	2026-09-24 02:02	46.92	OK
19649	2026-09-24 02:03	47.75	OK	19650	2026-09-24 02:04	44.67	OK
19651	2026-09-24 02:05	45.16	OK	19652	2026-09-24 02:06	46.36	OK
19653	2026-09-24 02:07	47.48	OK	19654	2026-09-24 02:08	47.29	OK
19655	2026-09-24 02:09	47.75	OK	19656	2026-09-24 02:10	45.99	OK
19657	2026-09-24 02:11	44.59	OK	19658	2026-09-24 02:12	44.52	OK
19659	2026-09-24 02:13	45.98	OK	19660	2026-09-24 02:14	44.65	OK
19661	2026-09-24 02:15	45.36	OK	19662	2026-09-24 02:16	43.96	OK
1966	2026-09-24 02:17	46.68	OK	1966	2026-09-24 02:18	44.25	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
19665	2026-09-24 02:19	47.10	OK	19666	2026-09-24 02:20	47.05	OK
19667	2026-09-24 02:21	45.70	OK	19668	2026-09-24 02:22	46.33	OK
19669	2026-09-24 02:23	45.42	OK	19670	2026-09-24 02:24	46.55	OK
19671	2026-09-24 02:25	44.27	OK	19672	2026-09-24 02:26	44.40	OK
19673	2026-09-24 02:27	44.05	OK	19674	2026-09-24 02:28	46.33	OK
19675	2026-09-24 02:29	44.89	OK	19676	2026-09-24 02:30	47.61	OK
19677	2026-09-24 02:31	45.95	OK	19678	2026-09-24 02:32	45.88	OK
19679	2026-09-24 02:33	47.05	OK	19680	2026-09-24 02:34	46.98	OK
19681	2026-09-24 02:35	45.77	OK	19682	2026-09-24 02:36	46.60	OK
19683	2026-09-24 02:37	45.88	OK	19684	2026-09-24 02:38	47.58	OK
19685	2026-09-24 02:39	46.68	OK	19686	2026-09-24 02:40	46.66	OK
19687	2026-09-24 02:41	45.87	OK	19688	2026-09-24 02:42	45.06	OK
19689	2026-09-24 02:43	45.40	OK	19690	2026-09-24 02:44	46.25	OK
19691	2026-09-24 02:45	48.11	OK	19692	2026-09-24 02:46	46.97	OK
19693	2026-09-24 02:47	45.80	OK	19694	2026-09-24 02:48	46.85	OK
19695	2026-09-24 02:49	44.53	OK	19696	2026-09-24 02:50	47.16	OK
19697	2026-09-24 02:51	47.09	OK	19698	2026-09-24 02:52	47.64	OK
19699	2026-09-24 02:53	48.42	OK	19700	2026-09-24 02:54	48.17	OK
19701	2026-09-24 02:55	47.41	OK	19702	2026-09-24 02:56	49.10	OK
19703	2026-09-24 02:57	46.19	OK	19704	2026-09-24 02:58	45.33	OK
19705	2026-09-24 02:59	46.09	OK	19706	2026-09-24 03:00	48.64	OK
19707	2026-09-24 03:01	47.30	OK	19708	2026-09-24 03:02	47.77	OK
19709	2026-09-24 03:03	46.00	OK	19710	2026-09-24 03:04	45.96	OK
19711	2026-09-24 03:05	44.63	OK	19712	2026-09-24 03:06	47.59	OK
19713	2026-09-24 03:07	46.32	OK	19714	2026-09-24 03:08	46.49	OK
19715	2026-09-24 03:09	45.34	OK	19716	2026-09-24 03:10	47.21	OK
19717	2026-09-24 03:11	47.27	OK	19718	2026-09-24 03:12	46.92	OK
19719	2026-09-24 03:13	46.26	OK	19720	2026-09-24 03:14	47.76	OK
19721	2026-09-24 03:15	45.91	OK	19722	2026-09-24 03:16	47.07	OK
19722	2026-09-24 03:17	47.27	OK	19722	2026-09-24 03:18	46.78	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
19725	2026-09-24 03:19	47.62	OK	19726	2026-09-24 03:20	47.14	OK
19727	2026-09-24 03:21	47.96	OK	19728	2026-09-24 03:22	47.60	OK
19729	2026-09-24 03:23	46.10	OK	19730	2026-09-24 03:24	46.83	OK
19731	2026-09-24 03:25	46.64	OK	19732	2026-09-24 03:26	47.40	OK
19733	2026-09-24 03:27	45.55	OK	19734	2026-09-24 03:28	44.82	OK
19735	2026-09-24 03:29	46.53	OK	19736	2026-09-24 03:30	46.05	OK
19737	2026-09-24 03:31	49.68	OK	19738	2026-09-24 03:32	46.82	OK
19739	2026-09-24 03:33	46.86	OK	19740	2026-09-24 03:34	47.65	OK
19741	2026-09-24 03:35	45.88	OK	19742	2026-09-24 03:36	46.21	OK
19743	2026-09-24 03:37	45.89	OK	19744	2026-09-24 03:38	46.11	OK
19745	2026-09-24 03:39	47.07	OK	19746	2026-09-24 03:40	49.15	OK
19747	2026-09-24 03:41	48.20	OK	19748	2026-09-24 03:42	47.97	OK
19749	2026-09-24 03:43	48.62	OK	19750	2026-09-24 03:44	47.23	OK
19751	2026-09-24 03:45	47.78	OK	19752	2026-09-24 03:46	46.99	OK
19753	2026-09-24 03:47	47.46	OK	19754	2026-09-24 03:48	47.00	OK
19755	2026-09-24 03:49	46.50	OK	19756	2026-09-24 03:50	46.92	OK
19757	2026-09-24 03:51	46.77	OK	19758	2026-09-24 03:52	49.14	OK
19759	2026-09-24 03:53	47.00	OK	19760	2026-09-24 03:54	47.01	OK
19761	2026-09-24 03:55	48.84	OK	19762	2026-09-24 03:56	50.41	OK
19763	2026-09-24 03:57	48.14	OK	19764	2026-09-24 03:58	45.66	OK
19765	2026-09-24 03:59	49.14	OK	19766	2026-09-24 04:00	45.83	OK
19767	2026-09-24 04:01	48.01	OK	19768	2026-09-24 04:02	46.92	OK
19769	2026-09-24 04:03	49.08	OK	19770	2026-09-24 04:04	47.04	OK
19771	2026-09-24 04:05	48.58	OK	19772	2026-09-24 04:06	48.14	OK
19773	2026-09-24 04:07	47.15	OK	19774	2026-09-24 04:08	45.94	OK
19775	2026-09-24 04:09	46.73	OK	19776	2026-09-24 04:10	49.02	OK
19777	2026-09-24 04:11	47.51	OK	19778	2026-09-24 04:12	47.72	OK
19779	2026-09-24 04:13	49.42	OK	19780	2026-09-24 04:14	48.32	OK
19781	2026-09-24 04:15	48.28	OK	19782	2026-09-24 04:16	50.16	OK
1978	2026-09-24 04:17	49.57	OK	1978	2026-09-24 04:18	47.83	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
19785	2026-09-24 04:19	47.57	OK	19786	2026-09-24 04:20	46.83	OK
19787	2026-09-24 04:21	47.75	OK	19788	2026-09-24 04:22	49.27	OK
19789	2026-09-24 04:23	48.31	OK	19790	2026-09-24 04:24	48.13	OK
19791	2026-09-24 04:25	48.26	OK	19792	2026-09-24 04:26	48.45	OK
19793	2026-09-24 04:27	48.62	OK	19794	2026-09-24 04:28	48.91	OK
19795	2026-09-24 04:29	48.90	OK	19796	2026-09-24 04:30	47.37	OK
19797	2026-09-24 04:31	47.61	OK	19798	2026-09-24 04:32	49.79	OK
19799	2026-09-24 04:33	48.02	OK	19800	2026-09-24 04:34	47.58	OK
19801	2026-09-24 04:35	48.68	OK	19802	2026-09-24 04:36	48.01	OK
19803	2026-09-24 04:37	48.53	OK	19804	2026-09-24 04:38	47.62	OK
19805	2026-09-24 04:39	48.31	OK	19806	2026-09-24 04:40	47.54	OK
19807	2026-09-24 04:41	49.07	OK	19808	2026-09-24 04:42	48.51	OK
19809	2026-09-24 04:43	49.15	OK	19810	2026-09-24 04:44	50.29	OK
19811	2026-09-24 04:45	50.47	OK	19812	2026-09-24 04:46	48.45	OK
19813	2026-09-24 04:47	47.98	OK	19814	2026-09-24 04:48	49.60	OK
19815	2026-09-24 04:49	48.92	OK	19816	2026-09-24 04:50	49.71	OK
19817	2026-09-24 04:51	48.59	OK	19818	2026-09-24 04:52	48.68	OK
19819	2026-09-24 04:53	49.20	OK	19820	2026-09-24 04:54	48.02	OK
19821	2026-09-24 04:55	49.78	OK	19822	2026-09-24 04:56	47.65	OK
19823	2026-09-24 04:57	48.47	OK	19824	2026-09-24 04:58	48.47	OK
19825	2026-09-24 04:59	49.98	OK	19826	2026-09-24 05:00	49.66	OK
19827	2026-09-24 05:01	48.68	OK	19828	2026-09-24 05:02	48.26	OK
19829	2026-09-24 05:03	49.66	OK	19830	2026-09-24 05:04	50.84	OK
19831	2026-09-24 05:05	48.76	OK	19832	2026-09-24 05:06	49.52	OK
19833	2026-09-24 05:07	48.45	OK	19834	2026-09-24 05:08	48.74	OK
19835	2026-09-24 05:09	50.50	OK	19836	2026-09-24 05:10	50.15	OK
19837	2026-09-24 05:11	47.67	OK	19838	2026-09-24 05:12	50.22	OK
19839	2026-09-24 05:13	48.57	OK	19840	2026-09-24 05:14	49.60	OK
19841	2026-09-24 05:15	50.36	OK	19842	2026-09-24 05:16	49.37	OK
1984	2026-09-24 05:17	49.65	OK	1984	2026-09-24 05:18	47.77	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
19845	2026-09-24 05:19	47.77	OK	19846	2026-09-24 05:20	50.88	OK
19847	2026-09-24 05:21	49.96	OK	19848	2026-09-24 05:22	48.56	OK
19849	2026-09-24 05:23	49.65	OK	19850	2026-09-24 05:24	48.64	OK
19851	2026-09-24 05:25	49.38	OK	19852	2026-09-24 05:26	50.43	OK
19853	2026-09-24 05:27	49.73	OK	19854	2026-09-24 05:28	48.58	OK
19855	2026-09-24 05:29	49.62	OK	19856	2026-09-24 05:30	50.28	OK
19857	2026-09-24 05:31	50.09	OK	19858	2026-09-24 05:32	50.07	OK
19859	2026-09-24 05:33	51.09	OK	19860	2026-09-24 05:34	48.77	OK
19861	2026-09-24 05:35	49.43	OK	19862	2026-09-24 05:36	47.62	OK
19863	2026-09-24 05:37	51.19	OK	19864	2026-09-24 05:38	51.35	OK
19865	2026-09-24 05:39	50.21	OK	19866	2026-09-24 05:40	48.96	OK
19867	2026-09-24 05:41	49.93	OK	19868	2026-09-24 05:42	49.44	OK
19869	2026-09-24 05:43	50.99	OK	19870	2026-09-24 05:44	50.03	OK
19871	2026-09-24 05:45	48.03	OK	19872	2026-09-24 05:46	49.70	OK
19873	2026-09-24 05:47	49.61	OK	19874	2026-09-24 05:48	49.56	OK
19875	2026-09-24 05:49	50.99	OK	19876	2026-09-24 05:50	48.91	OK
19877	2026-09-24 05:51	50.83	OK	19878	2026-09-24 05:52	49.62	OK
19879	2026-09-24 05:53	49.73	OK	19880	2026-09-24 05:54	49.39	OK
19881	2026-09-24 05:55	51.59	OK	19882	2026-09-24 05:56	49.24	OK
19883	2026-09-24 05:57	48.24	OK	19884	2026-09-24 05:58	49.49	OK
19885	2026-09-24 05:59	49.86	OK	19886	2026-09-24 06:00	50.28	OK
19887	2026-09-24 06:01	49.23	OK	19888	2026-09-24 06:02	49.55	OK
19889	2026-09-24 06:03	51.32	OK	19890	2026-09-24 06:04	49.85	OK
19891	2026-09-24 06:05	48.57	OK	19892	2026-09-24 06:06	52.15	OK
19893	2026-09-24 06:07	51.52	OK	19894	2026-09-24 06:08	50.21	OK
19895	2026-09-24 06:09	50.24	OK	19896	2026-09-24 06:10	51.64	OK
19897	2026-09-24 06:11	51.46	OK	19898	2026-09-24 06:12	49.86	OK
19899	2026-09-24 06:13	48.42	OK	19900	2026-09-24 06:14	48.45	OK
19901	2026-09-24 06:15	49.73	OK	19902	2026-09-24 06:16	49.41	OK
1990	2026-09-24 06:17	50.70	OK	1990	2026-09-24 06:18	49.89	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
19905	2026-09-24 06:19	49.14	OK	19906	2026-09-24 06:20	51.56	OK
19907	2026-09-24 06:21	52.05	OK	19908	2026-09-24 06:22	50.45	OK
19909	2026-09-24 06:23	49.55	OK	19910	2026-09-24 06:24	51.48	OK
19911	2026-09-24 06:25	50.75	OK	19912	2026-09-24 06:26	51.65	OK
19913	2026-09-24 06:27	49.72	OK	19914	2026-09-24 06:28	51.12	OK
19915	2026-09-24 06:29	50.90	OK	19916	2026-09-24 06:30	51.03	OK
19917	2026-09-24 06:31	50.86	OK	19918	2026-09-24 06:32	49.12	OK
19919	2026-09-24 06:33	52.39	OK	19920	2026-09-24 06:34	52.67	OK
19921	2026-09-24 06:35	48.81	OK	19922	2026-09-24 06:36	50.41	OK
19923	2026-09-24 06:37	49.17	OK	19924	2026-09-24 06:38	50.26	OK
19925	2026-09-24 06:39	49.45	OK	19926	2026-09-24 06:40	52.17	OK
19927	2026-09-24 06:41	51.18	OK	19928	2026-09-24 06:42	52.51	OK
19929	2026-09-24 06:43	50.87	OK	19930	2026-09-24 06:44	50.51	OK
19931	2026-09-24 06:45	50.62	OK	19932	2026-09-24 06:46	51.01	OK
19933	2026-09-24 06:47	50.77	OK	19934	2026-09-24 06:48	50.86	OK
19935	2026-09-24 06:49	50.75	OK	19936	2026-09-24 06:50	50.28	OK
19937	2026-09-24 06:51	50.09	OK	19938	2026-09-24 06:52	52.09	OK
19939	2026-09-24 06:53	51.34	OK	19940	2026-09-24 06:54	50.87	OK
19941	2026-09-24 06:55	50.52	OK	19942	2026-09-24 06:56	49.98	OK
19943	2026-09-24 06:57	51.89	OK	19944	2026-09-24 06:58	50.36	OK
19945	2026-09-24 06:59	51.38	OK	19946	2026-09-24 07:00	51.26	OK
19947	2026-09-24 07:01	49.49	OK	19948	2026-09-24 07:02	51.85	OK
19949	2026-09-24 07:03	51.72	OK	19950	2026-09-24 07:04	52.27	OK
19951	2026-09-24 07:05	52.10	OK	19952	2026-09-24 07:06	50.80	OK
19953	2026-09-24 07:07	51.41	OK	19954	2026-09-24 07:08	52.26	OK
19955	2026-09-24 07:09	51.67	OK	19956	2026-09-24 07:10	52.58	OK
19957	2026-09-24 07:11	51.31	OK	19958	2026-09-24 07:12	51.30	OK
19959	2026-09-24 07:13	53.95	OK	19960	2026-09-24 07:14	50.42	OK
19961	2026-09-24 07:15	51.48	OK	19962	2026-09-24 07:16	52.14	OK
1996	2026-09-24 07:17	49.73	OK	1996	2026-09-24 07:18	50.72	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
19965	2026-09-24 07:19	48.96	OK	19966	2026-09-24 07:20	51.12	OK
19967	2026-09-24 07:21	52.26	OK	19968	2026-09-24 07:22	50.86	OK
19969	2026-09-24 07:23	53.30	OK	19970	2026-09-24 07:24	52.66	OK
19971	2026-09-24 07:25	51.65	OK	19972	2026-09-24 07:26	53.19	OK
19973	2026-09-24 07:27	53.15	OK	19974	2026-09-24 07:28	52.08	OK
19975	2026-09-24 07:29	51.85	OK	19976	2026-09-24 07:30	51.04	OK
19977	2026-09-24 07:31	49.50	OK	19978	2026-09-24 07:32	53.53	OK
19979	2026-09-24 07:33	51.89	OK	19980	2026-09-24 07:34	50.10	OK
19981	2026-09-24 07:35	51.94	OK	19982	2026-09-24 07:36	51.81	OK
19983	2026-09-24 07:37	51.46	OK	19984	2026-09-24 07:38	51.58	OK
19985	2026-09-24 07:39	50.21	OK	19986	2026-09-24 07:40	53.05	OK
19987	2026-09-24 07:41	52.64	OK	19988	2026-09-24 07:42	52.77	OK
19989	2026-09-24 07:43	51.29	OK	19990	2026-09-24 07:44	52.90	OK
19991	2026-09-24 07:45	51.14	OK	19992	2026-09-24 07:46	52.21	OK
19993	2026-09-24 07:47	51.53	OK	19994	2026-09-24 07:48	50.93	OK
19995	2026-09-24 07:49	50.67	OK	19996	2026-09-24 07:50	51.71	OK
19997	2026-09-24 07:51	52.43	OK	19998	2026-09-24 07:52	51.08	OK
19999	2026-09-24 07:53	50.82	OK	20000	2026-09-24 07:54	51.86	OK
20001	2026-09-24 07:55	51.96	OK	20002	2026-09-24 07:56	52.71	OK
20003	2026-09-24 07:57	53.61	OK	20004	2026-09-24 07:58	50.25	OK
20005	2026-09-24 07:59	51.43	OK	20006	2026-09-24 08:00	51.90	OK
20007	2026-09-24 08:01	51.62	OK	20008	2026-09-24 08:02	50.99	OK
20009	2026-09-24 08:03	50.54	OK	20010	2026-09-24 08:04	52.49	OK
20011	2026-09-24 08:05	51.24	OK	20012	2026-09-24 08:06	53.95	OK
20013	2026-09-24 08:07	50.64	OK	20014	2026-09-24 08:08	53.53	OK
20015	2026-09-24 08:09	51.85	OK	20016	2026-09-24 08:10	52.76	OK
20017	2026-09-24 08:11	53.06	OK	20018	2026-09-24 08:12	53.52	OK
20019	2026-09-24 08:13	52.26	OK	20020	2026-09-24 08:14	52.96	OK
20021	2026-09-24 08:15	51.49	OK	20022	2026-09-24 08:16	52.46	OK
2002	2026-09-24 08:17	52.56	OK	2002	2026-09-24 08:18	53.26	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
20025	2026-09-24 08:19	52.90	OK	20026	2026-09-24 08:20	52.07	OK
20027	2026-09-24 08:21	51.62	OK	20028	2026-09-24 08:22	53.31	OK
20029	2026-09-24 08:23	52.16	OK	20030	2026-09-24 08:24	52.18	OK
20031	2026-09-24 08:25	51.49	OK	20032	2026-09-24 08:26	52.38	OK
20033	2026-09-24 08:27	51.45	OK	20034	2026-09-24 08:28	53.05	OK
20035	2026-09-24 08:29	52.07	OK	20036	2026-09-24 08:30	55.54	OK
20037	2026-09-24 08:31	51.38	OK	20038	2026-09-24 08:32	51.88	OK
20039	2026-09-24 08:33	54.46	OK	20040	2026-09-24 08:34	52.83	OK
20041	2026-09-24 08:35	53.11	OK	20042	2026-09-24 08:36	53.56	OK
20043	2026-09-24 08:37	52.95	OK	20044	2026-09-24 08:38	51.58	OK
20045	2026-09-24 08:39	52.47	OK	20046	2026-09-24 08:40	54.06	OK
20047	2026-09-24 08:41	52.39	OK	20048	2026-09-24 08:42	52.25	OK
20049	2026-09-24 08:43	53.47	OK	20050	2026-09-24 08:44	51.81	OK
20051	2026-09-24 08:45	54.91	OK	20052	2026-09-24 08:46	51.37	OK
20053	2026-09-24 08:47	53.16	OK	20054	2026-09-24 08:48	55.96	OK
20055	2026-09-24 08:49	55.07	OK	20056	2026-09-24 08:50	50.72	OK
20057	2026-09-24 08:51	51.95	OK	20058	2026-09-24 08:52	54.36	OK
20059	2026-09-24 08:53	53.79	OK	20060	2026-09-24 08:54	55.89	OK
20061	2026-09-24 08:55	53.92	OK	20062	2026-09-24 08:56	54.94	OK
20063	2026-09-24 08:57	51.92	OK	20064	2026-09-24 08:58	52.33	OK
20065	2026-09-24 08:59	53.13	OK	20066	2026-09-24 09:00	53.76	OK
20067	2026-09-24 09:01	53.18	OK	20068	2026-09-24 09:02	52.95	OK
20069	2026-09-24 09:03	52.97	OK	20070	2026-09-24 09:04	53.69	OK
20071	2026-09-24 09:05	55.48	OK	20072	2026-09-24 09:06	52.93	OK
20073	2026-09-24 09:07	54.00	OK	20074	2026-09-24 09:08	53.33	OK
20075	2026-09-24 09:09	54.40	OK	20076	2026-09-24 09:10	52.13	OK
20077	2026-09-24 09:11	52.87	OK	20078	2026-09-24 09:12	52.17	OK
20079	2026-09-24 09:13	55.97	OK	20080	2026-09-24 09:14	53.30	OK
20081	2026-09-24 09:15	53.59	OK	20082	2026-09-24 09:16	54.14	OK
2008	2026-09-24 09:17	54.47	OK	2008	2026-09-24 09:18	52.94	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
20085	2026-09-24 09:19	53.50	OK	20086	2026-09-24 09:20	55.08	OK
20087	2026-09-24 09:21	53.89	OK	20088	2026-09-24 09:22	53.37	OK
20089	2026-09-24 09:23	53.56	OK	20090	2026-09-24 09:24	55.23	OK
20091	2026-09-24 09:25	54.33	OK	20092	2026-09-24 09:26	55.67	OK
20093	2026-09-24 09:27	52.03	OK	20094	2026-09-24 09:28	53.57	OK
20095	2026-09-24 09:29	54.01	OK	20096	2026-09-24 09:30	53.53	OK
20097	2026-09-24 09:31	53.21	OK	20098	2026-09-24 09:32	54.16	OK
20099	2026-09-24 09:33	55.25	OK	20100	2026-09-24 09:34	54.00	OK
20101	2026-09-24 09:35	52.87	OK	20102	2026-09-24 09:36	51.34	OK
20103	2026-09-24 09:37	52.23	OK	20104	2026-09-24 09:38	53.53	OK
20105	2026-09-24 09:39	53.83	OK	20106	2026-09-24 09:40	52.83	OK
20107	2026-09-24 09:41	54.68	OK	20108	2026-09-24 09:42	52.18	OK
20109	2026-09-24 09:43	54.67	OK	20110	2026-09-24 09:44	53.09	OK
20111	2026-09-24 09:45	52.32	OK	20112	2026-09-24 09:46	53.25	OK
20113	2026-09-24 09:47	53.76	OK	20114	2026-09-24 09:48	54.89	OK
20115	2026-09-24 09:49	53.36	OK	20116	2026-09-24 09:50	55.68	OK
20117	2026-09-24 09:51	55.52	OK	20118	2026-09-24 09:52	53.43	OK
20119	2026-09-24 09:53	53.65	OK	20120	2026-09-24 09:54	55.45	OK
20121	2026-09-24 09:55	53.98	OK	20122	2026-09-24 09:56	54.76	OK
20123	2026-09-24 09:57	55.50	OK	20124	2026-09-24 09:58	52.95	OK
20125	2026-09-24 09:59	52.75	OK	20126	2026-09-24 10:00	54.43	OK
20127	2026-09-24 10:01	55.43	OK	20128	2026-09-24 10:02	55.16	OK
20129	2026-09-24 10:03	54.56	OK	20130	2026-09-24 10:04	53.57	OK
20131	2026-09-24 10:05	53.46	OK	20132	2026-09-24 10:06	54.28	OK
20133	2026-09-24 10:07	55.12	OK	20134	2026-09-24 10:08	53.68	OK
20135	2026-09-24 10:09	53.11	OK	20136	2026-09-24 10:10	55.45	OK
20137	2026-09-24 10:11	54.86	OK	20138	2026-09-24 10:12	52.97	OK
20139	2026-09-24 10:13	53.32	OK	20140	2026-09-24 10:14	52.86	OK
20141	2026-09-24 10:15	54.16	OK	20142	2026-09-24 10:16	51.66	OK
2014	2026-09-24 10:17	51.27	OK	2014	2026-09-24 10:18	53.71	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3				4			
20145	2026-09-24 10:19	55.20	OK	20146	2026-09-24 10:20	52.34	OK
20147	2026-09-24 10:21	51.53	OK	20148	2026-09-24 10:22	54.37	OK
20149	2026-09-24 10:23	53.78	OK	20150	2026-09-24 10:24	54.17	OK
20151	2026-09-24 10:25	55.21	OK	20152	2026-09-24 10:26	54.46	OK
20153	2026-09-24 10:27	55.11	OK	20154	2026-09-24 10:28	54.79	OK
20155	2026-09-24 10:29	53.09	OK	20156	2026-09-24 10:30	55.33	OK
20157	2026-09-24 10:31	53.92	OK	20158	2026-09-24 10:32	53.82	OK
20159	2026-09-24 10:33	53.83	OK	20160	2026-09-24 10:34	54.81	OK
20161	2026-09-24 10:35	54.84	OK				

Signal: Ambient_Temp (°C)

All 20,161 Raw Readings

Operating Limits: [0.0 to 50.0] • Observed: Min 23.47, Max 32.34, Mean 27.98

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1	2026-09-10 10:35	25.91	OK	2	2026-09-10 10:36	26.45	OK
3	2026-09-10 10:37	26.56	OK	4	2026-09-10 10:38	25.98	OK
5	2026-09-10 10:39	26.01	OK	6	2026-09-10 10:40	25.11	OK
7	2026-09-10 10:41	26.66	OK	8	2026-09-10 10:42	26.51	OK
9	2026-09-10 10:43	26.25	OK	10	2026-09-10 10:44	25.43	OK
11	2026-09-10 10:45	27.71	OK	12	2026-09-10 10:46	26.45	OK
13	2026-09-10 10:47	27.61	OK	14	2026-09-10 10:48	27.42	OK
15	2026-09-10 10:49	25.64	OK	16	2026-09-10 10:50	25.67	OK
17	2026-09-10 10:51	24.81	OK	18	2026-09-10 10:52	27.02	OK
19	2026-09-10 10:53	26.36	OK	20	2026-09-10 10:54	25.69	OK
21	2026-09-10 10:55	26.15	OK	22	2026-09-10 10:56	25.21	OK
23	2026-09-10 10:57	24.85	OK	24	2026-09-10 10:58	25.42	OK
25	2026-09-10 10:59	26.45	OK	26	2026-09-10 11:00	26.16	OK
27	2026-09-10 11:01	26.48	OK	28	2026-09-10 11:02	26.58	OK
29	2026-09-10 11:03	25.66	OK	30	2026-09-10 11:04	26.49	OK
31	2026-09-10 11:05	25.82	OK	32	2026-09-10 11:06	27.10	OK
33	2026-09-10 11:07	25.44	OK	34	2026-09-10 11:08	25.54	OK
35	2026-09-10 11:09	25.73	OK	36	2026-09-10 11:10	26.28	OK
37	2026-09-10 11:11	26.67	OK	38	2026-09-10 11:12	25.92	OK
39	2026-09-10 11:13	25.89	OK	40	2026-09-10 11:14	24.86	OK
41	2026-09-10 11:15	24.63	OK	42	2026-09-10 11:16	26.54	OK
43	2026-09-10 11:17	26.14	OK	44	2026-09-10 11:18	26.74	OK
45	2026-09-10 11:19	25.86	OK	46	2026-09-10 11:20	26.42	OK
47	2026-09-10 11:21	27.67	OK	48	2026-09-10 11:22	26.11	OK
49	2026-09-10 11:23	24.41	OK	50	2026-09-10 11:24	25.11	OK
51	2026-09-10 11:25	25.96	OK	52	2026-09-10 11:26	26.95	OK
53	2026-09-10 11:27	26.89	OK	54	2026-09-10 11:28	26.41	OK
55	2026-09-10 11:29	25.45	OK	56	2026-09-10 11:30	26.56	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
57	2026-09-10 11:31	26.68	OK	58	2026-09-10 11:32	26.35	OK
59	2026-09-10 11:33	25.85	OK	60	2026-09-10 11:34	25.05	OK
61	2026-09-10 11:35	25.30	OK	62	2026-09-10 11:36	25.74	OK
63	2026-09-10 11:37	25.96	OK	64	2026-09-10 11:38	27.07	OK
65	2026-09-10 11:39	24.92	OK	66	2026-09-10 11:40	26.02	OK
67	2026-09-10 11:41	25.66	OK	68	2026-09-10 11:42	25.83	OK
69	2026-09-10 11:43	25.94	OK	70	2026-09-10 11:44	25.76	OK
71	2026-09-10 11:45	26.51	OK	72	2026-09-10 11:46	24.22	OK
73	2026-09-10 11:47	26.54	OK	74	2026-09-10 11:48	24.46	OK
75	2026-09-10 11:49	24.97	OK	76	2026-09-10 11:50	26.76	OK
77	2026-09-10 11:51	26.10	OK	78	2026-09-10 11:52	26.66	OK
79	2026-09-10 11:53	26.34	OK	80	2026-09-10 11:54	24.66	OK
81	2026-09-10 11:55	27.55	OK	82	2026-09-10 11:56	26.26	OK
83	2026-09-10 11:57	25.49	OK	84	2026-09-10 11:58	26.46	OK
85	2026-09-10 11:59	26.04	OK	86	2026-09-10 12:00	25.11	OK
87	2026-09-10 12:01	26.27	OK	88	2026-09-10 12:02	24.65	OK
89	2026-09-10 12:03	26.05	OK	90	2026-09-10 12:04	25.36	OK
91	2026-09-10 12:05	26.88	OK	92	2026-09-10 12:06	26.09	OK
93	2026-09-10 12:07	26.06	OK	94	2026-09-10 12:08	25.92	OK
95	2026-09-10 12:09	25.68	OK	96	2026-09-10 12:10	24.94	OK
97	2026-09-10 12:11	25.16	OK	98	2026-09-10 12:12	26.40	OK
99	2026-09-10 12:13	25.27	OK	100	2026-09-10 12:14	26.66	OK
101	2026-09-10 12:15	26.70	OK	102	2026-09-10 12:16	24.61	OK
103	2026-09-10 12:17	27.16	OK	104	2026-09-10 12:18	25.35	OK
105	2026-09-10 12:19	27.01	OK	106	2026-09-10 12:20	24.78	OK
107	2026-09-10 12:21	25.74	OK	108	2026-09-10 12:22	24.40	OK
109	2026-09-10 12:23	25.76	OK	110	2026-09-10 12:24	26.35	OK
111	2026-09-10 12:25	26.95	OK	112	2026-09-10 12:26	27.40	OK
113	2026-09-10 12:27	24.83	OK	114	2026-09-10 12:28	25.10	OK
115	2026-09-10 12:29	25.63	OK	116	2026-09-10 12:30	25.79	OK
117	2026-09-10 12:31	24.48	OK	118	2026-09-10 12:32	24.40	OK
119	2026-09-10 12:33	26.66	OK	120	2026-09-10 12:34	25.67	OK
121	2026-09-10 12:35	25.44	OK	122	2026-09-10 12:36	24.70	OK
123	2026-09-10 12:37	26.03	OK	124	2026-09-10 12:38	25.32	OK
125	2026-09-10 12:39	24.71	OK	126	2026-09-10 12:40	25.27	OK
127	2026-09-10 12:41	25.51	OK	128	2026-09-10 12:42	25.46	OK
129	2026-09-10 12:43	25.46	OK	130	2026-09-10 12:44	27.31	OK
131	2026-09-10 12:45	26.95	OK	132	2026-09-10 12:46	26.67	OK
133	2026-09-10 12:47	25.61	OK	134	2026-09-10 12:48	25.78	OK
135	2026-09-10 12:49	25.69	OK	136	2026-09-10 12:50	25.96	OK
137	2026-09-10 12:51	26.18	OK	138	2026-09-10 12:52	25.00	OK
139	2026-09-10 12:53	26.85	OK	140	2026-09-10 12:54	26.25	OK
141	2026-09-10 12:55	25.24	OK	142	2026-09-10 12:56	26.14	OK
143	2026-09-10 12:57	24.54	OK	144	2026-09-10 12:58	24.87	OK
145	2026-09-10 12:59	26.71	OK	146	2026-09-10 13:00	26.57	OK
147	2026-09-10 13:01	24.89	OK	148	2026-09-10 13:02	24.92	OK
149	2026-09-10 13:03	25.88	OK	150	2026-09-10 13:04	25.53	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
151	2026-09-10 13:05	25.22	OK	152	2026-09-10 13:06	25.02	OK
153	2026-09-10 13:07	25.87	OK	154	2026-09-10 13:08	25.72	OK
155	2026-09-10 13:09	25.46	OK	156	2026-09-10 13:10	25.69	OK
157	2026-09-10 13:11	24.92	OK	158	2026-09-10 13:12	25.29	OK
159	2026-09-10 13:13	24.61	OK	160	2026-09-10 13:14	25.66	OK
161	2026-09-10 13:15	24.72	OK	162	2026-09-10 13:16	24.77	OK
163	2026-09-10 13:17	24.82	OK	164	2026-09-10 13:18	25.77	OK
165	2026-09-10 13:19	26.77	OK	166	2026-09-10 13:20	26.22	OK
167	2026-09-10 13:21	27.22	OK	168	2026-09-10 13:22	25.34	OK
169	2026-09-10 13:23	25.91	OK	170	2026-09-10 13:24	26.22	OK
171	2026-09-10 13:25	24.96	OK	172	2026-09-10 13:26	25.80	OK
173	2026-09-10 13:27	26.06	OK	174	2026-09-10 13:28	25.18	OK
175	2026-09-10 13:29	25.49	OK	176	2026-09-10 13:30	25.61	OK
177	2026-09-10 13:31	24.94	OK	178	2026-09-10 13:32	25.51	OK
179	2026-09-10 13:33	25.45	OK	180	2026-09-10 13:34	27.00	OK
181	2026-09-10 13:35	25.18	OK	182	2026-09-10 13:36	26.12	OK
183	2026-09-10 13:37	26.48	OK	184	2026-09-10 13:38	25.96	OK
185	2026-09-10 13:39	26.50	OK	186	2026-09-10 13:40	26.14	OK
187	2026-09-10 13:41	25.45	OK	188	2026-09-10 13:42	25.50	OK
189	2026-09-10 13:43	26.14	OK	190	2026-09-10 13:44	25.39	OK
191	2026-09-10 13:45	26.19	OK	192	2026-09-10 13:46	26.50	OK
193	2026-09-10 13:47	25.20	OK	194	2026-09-10 13:48	25.77	OK
195	2026-09-10 13:49	24.37	OK	196	2026-09-10 13:50	26.08	OK
197	2026-09-10 13:51	24.89	OK	198	2026-09-10 13:52	26.43	OK
199	2026-09-10 13:53	25.74	OK	200	2026-09-10 13:54	27.32	OK
201	2026-09-10 13:55	25.71	OK	202	2026-09-10 13:56	25.31	OK
203	2026-09-10 13:57	25.55	OK	204	2026-09-10 13:58	24.53	OK
205	2026-09-10 13:59	24.61	OK	206	2026-09-10 14:00	25.23	OK
207	2026-09-10 14:01	25.28	OK	208	2026-09-10 14:02	25.63	OK
209	2026-09-10 14:03	24.45	OK	210	2026-09-10 14:04	25.91	OK
211	2026-09-10 14:05	25.86	OK	212	2026-09-10 14:06	26.12	OK
213	2026-09-10 14:07	26.09	OK	214	2026-09-10 14:08	25.36	OK
215	2026-09-10 14:09	25.34	OK	216	2026-09-10 14:10	25.28	OK
217	2026-09-10 14:11	26.00	OK	218	2026-09-10 14:12	25.36	OK
219	2026-09-10 14:13	25.71	OK	220	2026-09-10 14:14	26.12	OK
221	2026-09-10 14:15	26.48	OK	222	2026-09-10 14:16	24.02	OK
223	2026-09-10 14:17	24.85	OK	224	2026-09-10 14:18	26.32	OK
225	2026-09-10 14:19	25.69	OK	226	2026-09-10 14:20	25.06	OK
227	2026-09-10 14:21	25.09	OK	228	2026-09-10 14:22	25.37	OK
229	2026-09-10 14:23	26.89	OK	230	2026-09-10 14:24	27.20	OK
231	2026-09-10 14:25	25.14	OK	232	2026-09-10 14:26	25.88	OK
233	2026-09-10 14:27	25.49	OK	234	2026-09-10 14:28	25.21	OK
235	2026-09-10 14:29	26.76	OK	236	2026-09-10 14:30	25.46	OK
237	2026-09-10 14:31	25.31	OK	238	2026-09-10 14:32	24.78	OK
239	2026-09-10 14:33	27.34	OK	240	2026-09-10 14:34	25.95	OK
241	2026-09-10 14:35	25.16	OK	242	2026-09-10 14:36	25.49	OK
243	2026-09-10 14:37	26.55	OK	244	2026-09-10 14:38	25.89	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
245	2026-09-10 14:39	23.98	OK	246	2026-09-10 14:40	26.08	OK
247	2026-09-10 14:41	25.87	OK	248	2026-09-10 14:42	26.67	OK
249	2026-09-10 14:43	25.37	OK	250	2026-09-10 14:44	26.61	OK
251	2026-09-10 14:45	25.36	OK	252	2026-09-10 14:46	25.98	OK
253	2026-09-10 14:47	26.21	OK	254	2026-09-10 14:48	25.98	OK
255	2026-09-10 14:49	26.58	OK	256	2026-09-10 14:50	25.61	OK
257	2026-09-10 14:51	25.77	OK	258	2026-09-10 14:52	24.89	OK
259	2026-09-10 14:53	26.56	OK	260	2026-09-10 14:54	26.57	OK
261	2026-09-10 14:55	25.44	OK	262	2026-09-10 14:56	26.52	OK
263	2026-09-10 14:57	25.96	OK	264	2026-09-10 14:58	26.36	OK
265	2026-09-10 14:59	25.33	OK	266	2026-09-10 15:00	25.68	OK
267	2026-09-10 15:01	25.20	OK	268	2026-09-10 15:02	25.77	OK
269	2026-09-10 15:03	25.90	OK	270	2026-09-10 15:04	25.69	OK
271	2026-09-10 15:05	26.92	OK	272	2026-09-10 15:06	26.78	OK
273	2026-09-10 15:07	25.94	OK	274	2026-09-10 15:08	25.22	OK
275	2026-09-10 15:09	25.55	OK	276	2026-09-10 15:10	24.97	OK
277	2026-09-10 15:11	24.16	OK	278	2026-09-10 15:12	25.26	OK
279	2026-09-10 15:13	25.86	OK	280	2026-09-10 15:14	26.24	OK
281	2026-09-10 15:15	26.44	OK	282	2026-09-10 15:16	24.55	OK
283	2026-09-10 15:17	25.78	OK	284	2026-09-10 15:18	24.96	OK
285	2026-09-10 15:19	24.31	OK	286	2026-09-10 15:20	26.52	OK
287	2026-09-10 15:21	25.44	OK	288	2026-09-10 15:22	25.91	OK
289	2026-09-10 15:23	26.69	OK	290	2026-09-10 15:24	26.31	OK
291	2026-09-10 15:25	26.54	OK	292	2026-09-10 15:26	26.11	OK
293	2026-09-10 15:27	25.91	OK	294	2026-09-10 15:28	26.41	OK
295	2026-09-10 15:29	27.10	OK	296	2026-09-10 15:30	26.08	OK
297	2026-09-10 15:31	26.63	OK	298	2026-09-10 15:32	25.84	OK
299	2026-09-10 15:33	26.03	OK	300	2026-09-10 15:34	25.89	OK
301	2026-09-10 15:35	24.77	OK	302	2026-09-10 15:36	24.98	OK
303	2026-09-10 15:37	26.43	OK	304	2026-09-10 15:38	27.06	OK
305	2026-09-10 15:39	26.18	OK	306	2026-09-10 15:40	26.28	OK
307	2026-09-10 15:41	26.29	OK	308	2026-09-10 15:42	25.08	OK
309	2026-09-10 15:43	26.13	OK	310	2026-09-10 15:44	25.99	OK
311	2026-09-10 15:45	25.14	OK	312	2026-09-10 15:46	26.55	OK
313	2026-09-10 15:47	25.81	OK	314	2026-09-10 15:48	25.03	OK
315	2026-09-10 15:49	26.72	OK	316	2026-09-10 15:50	25.75	OK
317	2026-09-10 15:51	26.86	OK	318	2026-09-10 15:52	25.64	OK
319	2026-09-10 15:53	26.37	OK	320	2026-09-10 15:54	27.33	OK
321	2026-09-10 15:55	25.90	OK	322	2026-09-10 15:56	25.68	OK
323	2026-09-10 15:57	27.05	OK	324	2026-09-10 15:58	24.76	OK
325	2026-09-10 15:59	25.81	OK	326	2026-09-10 16:00	26.21	OK
327	2026-09-10 16:01	25.77	OK	328	2026-09-10 16:02	25.91	OK
329	2026-09-10 16:03	26.49	OK	330	2026-09-10 16:04	27.42	OK
331	2026-09-10 16:05	26.77	OK	332	2026-09-10 16:06	26.67	OK
333	2026-09-10 16:07	26.88	OK	334	2026-09-10 16:08	25.18	OK
335	2026-09-10 16:09	26.11	OK	336	2026-09-10 16:10	26.16	OK
337	2026-09-10 16:11	27.13	OK	338	2026-09-10 16:12	27.13	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
339	2026-09-10 16:13	26.40	OK	340	2026-09-10 16:14	25.79	OK
341	2026-09-10 16:15	26.53	OK	342	2026-09-10 16:16	27.52	OK
343	2026-09-10 16:17	24.77	OK	344	2026-09-10 16:18	24.50	OK
345	2026-09-10 16:19	25.44	OK	346	2026-09-10 16:20	25.18	OK
347	2026-09-10 16:21	26.57	OK	348	2026-09-10 16:22	25.47	OK
349	2026-09-10 16:23	25.60	OK	350	2026-09-10 16:24	26.06	OK
351	2026-09-10 16:25	27.50	OK	352	2026-09-10 16:26	27.25	OK
353	2026-09-10 16:27	26.16	OK	354	2026-09-10 16:28	26.23	OK
355	2026-09-10 16:29	25.53	OK	356	2026-09-10 16:30	26.39	OK
357	2026-09-10 16:31	24.84	OK	358	2026-09-10 16:32	26.03	OK
359	2026-09-10 16:33	26.87	OK	360	2026-09-10 16:34	26.49	OK
361	2026-09-10 16:35	27.66	OK	362	2026-09-10 16:36	26.97	OK
363	2026-09-10 16:37	25.48	OK	364	2026-09-10 16:38	26.27	OK
365	2026-09-10 16:39	27.26	OK	366	2026-09-10 16:40	26.27	OK
367	2026-09-10 16:41	25.38	OK	368	2026-09-10 16:42	25.47	OK
369	2026-09-10 16:43	25.91	OK	370	2026-09-10 16:44	26.32	OK
371	2026-09-10 16:45	25.70	OK	372	2026-09-10 16:46	26.47	OK
373	2026-09-10 16:47	25.15	OK	374	2026-09-10 16:48	26.16	OK
375	2026-09-10 16:49	26.77	OK	376	2026-09-10 16:50	26.98	OK
377	2026-09-10 16:51	27.83	OK	378	2026-09-10 16:52	26.60	OK
379	2026-09-10 16:53	26.28	OK	380	2026-09-10 16:54	26.73	OK
381	2026-09-10 16:55	26.67	OK	382	2026-09-10 16:56	27.61	OK
383	2026-09-10 16:57	26.96	OK	384	2026-09-10 16:58	26.13	OK
385	2026-09-10 16:59	25.74	OK	386	2026-09-10 17:00	25.90	OK
387	2026-09-10 17:01	27.49	OK	388	2026-09-10 17:02	27.88	OK
389	2026-09-10 17:03	26.71	OK	390	2026-09-10 17:04	27.42	OK
391	2026-09-10 17:05	27.67	OK	392	2026-09-10 17:06	26.39	OK
393	2026-09-10 17:07	27.21	OK	394	2026-09-10 17:08	25.57	OK
395	2026-09-10 17:09	26.85	OK	396	2026-09-10 17:10	26.04	OK
397	2026-09-10 17:11	26.53	OK	398	2026-09-10 17:12	26.44	OK
399	2026-09-10 17:13	26.61	OK	400	2026-09-10 17:14	26.10	OK
401	2026-09-10 17:15	27.15	OK	402	2026-09-10 17:16	26.57	OK
403	2026-09-10 17:17	27.62	OK	404	2026-09-10 17:18	25.89	OK
405	2026-09-10 17:19	26.71	OK	406	2026-09-10 17:20	27.29	OK
407	2026-09-10 17:21	26.48	OK	408	2026-09-10 17:22	26.42	OK
409	2026-09-10 17:23	26.62	OK	410	2026-09-10 17:24	26.42	OK
411	2026-09-10 17:25	26.17	OK	412	2026-09-10 17:26	26.62	OK
413	2026-09-10 17:27	26.83	OK	414	2026-09-10 17:28	25.35	OK
415	2026-09-10 17:29	25.60	OK	416	2026-09-10 17:30	26.12	OK
417	2026-09-10 17:31	28.07	OK	418	2026-09-10 17:32	26.55	OK
419	2026-09-10 17:33	26.69	OK	420	2026-09-10 17:34	25.57	OK
421	2026-09-10 17:35	27.17	OK	422	2026-09-10 17:36	26.15	OK
423	2026-09-10 17:37	25.15	OK	424	2026-09-10 17:38	26.14	OK
425	2026-09-10 17:39	27.87	OK	426	2026-09-10 17:40	27.25	OK
427	2026-09-10 17:41	26.37	OK	428	2026-09-10 17:42	27.13	OK
429	2026-09-10 17:43	26.77	OK	430	2026-09-10 17:44	26.65	OK
431	2026-09-10 17:45	27.32	OK	432	2026-09-10 17:46	27.33	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
433	2026-09-10 17:47	26.83	OK	434	2026-09-10 17:48	26.56	OK
435	2026-09-10 17:49	26.90	OK	436	2026-09-10 17:50	26.55	OK
437	2026-09-10 17:51	27.09	OK	438	2026-09-10 17:52	26.71	OK
439	2026-09-10 17:53	26.84	OK	440	2026-09-10 17:54	27.60	OK
441	2026-09-10 17:55	26.58	OK	442	2026-09-10 17:56	26.13	OK
443	2026-09-10 17:57	27.25	OK	444	2026-09-10 17:58	26.83	OK
445	2026-09-10 17:59	27.14	OK	446	2026-09-10 18:00	26.51	OK
447	2026-09-10 18:01	27.59	OK	448	2026-09-10 18:02	26.85	OK
449	2026-09-10 18:03	26.27	OK	450	2026-09-10 18:04	27.00	OK
451	2026-09-10 18:05	28.56	OK	452	2026-09-10 18:06	28.14	OK
453	2026-09-10 18:07	27.35	OK	454	2026-09-10 18:08	27.79	OK
455	2026-09-10 18:09	26.41	OK	456	2026-09-10 18:10	27.53	OK
457	2026-09-10 18:11	27.11	OK	458	2026-09-10 18:12	26.31	OK
459	2026-09-10 18:13	27.22	OK	460	2026-09-10 18:14	26.63	OK
461	2026-09-10 18:15	26.33	OK	462	2026-09-10 18:16	27.41	OK
463	2026-09-10 18:17	27.16	OK	464	2026-09-10 18:18	26.17	OK
465	2026-09-10 18:19	27.52	OK	466	2026-09-10 18:20	27.77	OK
467	2026-09-10 18:21	27.97	OK	468	2026-09-10 18:22	26.99	OK
469	2026-09-10 18:23	27.68	OK	470	2026-09-10 18:24	27.09	OK
471	2026-09-10 18:25	26.62	OK	472	2026-09-10 18:26	26.54	OK
473	2026-09-10 18:27	27.16	OK	474	2026-09-10 18:28	26.19	OK
475	2026-09-10 18:29	28.37	OK	476	2026-09-10 18:30	27.39	OK
477	2026-09-10 18:31	26.99	OK	478	2026-09-10 18:32	28.19	OK
479	2026-09-10 18:33	27.74	OK	480	2026-09-10 18:34	26.57	OK
481	2026-09-10 18:35	26.25	OK	482	2026-09-10 18:36	27.70	OK
483	2026-09-10 18:37	26.39	OK	484	2026-09-10 18:38	27.43	OK
485	2026-09-10 18:39	27.71	OK	486	2026-09-10 18:40	27.50	OK
487	2026-09-10 18:41	27.12	OK	488	2026-09-10 18:42	27.19	OK
489	2026-09-10 18:43	26.06	OK	490	2026-09-10 18:44	26.66	OK
491	2026-09-10 18:45	26.56	OK	492	2026-09-10 18:46	27.58	OK
493	2026-09-10 18:47	27.01	OK	494	2026-09-10 18:48	28.29	OK
495	2026-09-10 18:49	27.91	OK	496	2026-09-10 18:50	27.90	OK
497	2026-09-10 18:51	27.35	OK	498	2026-09-10 18:52	25.93	OK
499	2026-09-10 18:53	27.68	OK	500	2026-09-10 18:54	27.79	OK
501	2026-09-10 18:55	28.21	OK	502	2026-09-10 18:56	27.01	OK
503	2026-09-10 18:57	25.77	OK	504	2026-09-10 18:58	28.50	OK
505	2026-09-10 18:59	29.42	OK	506	2026-09-10 19:00	28.79	OK
507	2026-09-10 19:01	27.04	OK	508	2026-09-10 19:02	27.48	OK
509	2026-09-10 19:03	28.37	OK	510	2026-09-10 19:04	27.54	OK
511	2026-09-10 19:05	26.69	OK	512	2026-09-10 19:06	27.24	OK
513	2026-09-10 19:07	27.77	OK	514	2026-09-10 19:08	29.25	OK
515	2026-09-10 19:09	28.36	OK	516	2026-09-10 19:10	28.48	OK
517	2026-09-10 19:11	28.30	OK	518	2026-09-10 19:12	29.11	OK
519	2026-09-10 19:13	28.13	OK	520	2026-09-10 19:14	28.13	OK
521	2026-09-10 19:15	28.10	OK	522	2026-09-10 19:16	28.52	OK
523	2026-09-10 19:17	27.24	OK	524	2026-09-10 19:18	28.30	OK
525	2026-09-10 19:19	27.06	OK	526	2026-09-10 19:20	28.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
527	2026-09-10 19:21	29.11	OK	528	2026-09-10 19:22	29.40	OK
529	2026-09-10 19:23	27.14	OK	530	2026-09-10 19:24	27.91	OK
531	2026-09-10 19:25	28.41	OK	532	2026-09-10 19:26	29.54	OK
533	2026-09-10 19:27	28.71	OK	534	2026-09-10 19:28	27.79	OK
535	2026-09-10 19:29	28.65	OK	536	2026-09-10 19:30	28.92	OK
537	2026-09-10 19:31	28.75	OK	538	2026-09-10 19:32	27.52	OK
539	2026-09-10 19:33	28.33	OK	540	2026-09-10 19:34	28.11	OK
541	2026-09-10 19:35	26.54	OK	542	2026-09-10 19:36	27.39	OK
543	2026-09-10 19:37	28.44	OK	544	2026-09-10 19:38	28.75	OK
545	2026-09-10 19:39	28.78	OK	546	2026-09-10 19:40	28.96	OK
547	2026-09-10 19:41	26.62	OK	548	2026-09-10 19:42	28.43	OK
549	2026-09-10 19:43	29.02	OK	550	2026-09-10 19:44	28.00	OK
551	2026-09-10 19:45	28.33	OK	552	2026-09-10 19:46	28.78	OK
553	2026-09-10 19:47	28.27	OK	554	2026-09-10 19:48	27.42	OK
555	2026-09-10 19:49	28.07	OK	556	2026-09-10 19:50	27.93	OK
557	2026-09-10 19:51	27.86	OK	558	2026-09-10 19:52	27.72	OK
559	2026-09-10 19:53	27.93	OK	560	2026-09-10 19:54	28.91	OK
561	2026-09-10 19:55	27.93	OK	562	2026-09-10 19:56	28.51	OK
563	2026-09-10 19:57	29.46	OK	564	2026-09-10 19:58	28.92	OK
565	2026-09-10 19:59	28.97	OK	566	2026-09-10 20:00	27.46	OK
567	2026-09-10 20:01	28.99	OK	568	2026-09-10 20:02	28.78	OK
569	2026-09-10 20:03	28.22	OK	570	2026-09-10 20:04	28.38	OK
571	2026-09-10 20:05	28.94	OK	572	2026-09-10 20:06	29.28	OK
573	2026-09-10 20:07	28.00	OK	574	2026-09-10 20:08	27.51	OK
575	2026-09-10 20:09	29.09	OK	576	2026-09-10 20:10	28.51	OK
577	2026-09-10 20:11	28.63	OK	578	2026-09-10 20:12	29.46	OK
579	2026-09-10 20:13	27.51	OK	580	2026-09-10 20:14	27.38	OK
581	2026-09-10 20:15	27.86	OK	582	2026-09-10 20:16	28.17	OK
583	2026-09-10 20:17	27.32	OK	584	2026-09-10 20:18	29.23	OK
585	2026-09-10 20:19	27.80	OK	586	2026-09-10 20:20	28.36	OK
587	2026-09-10 20:21	29.14	OK	588	2026-09-10 20:22	30.35	OK
589	2026-09-10 20:23	30.10	OK	590	2026-09-10 20:24	28.51	OK
591	2026-09-10 20:25	28.83	OK	592	2026-09-10 20:26	28.29	OK
593	2026-09-10 20:27	27.98	OK	594	2026-09-10 20:28	26.83	OK
595	2026-09-10 20:29	26.92	OK	596	2026-09-10 20:30	27.80	OK
597	2026-09-10 20:31	29.20	OK	598	2026-09-10 20:32	29.47	OK
599	2026-09-10 20:33	29.56	OK	600	2026-09-10 20:34	28.00	OK
601	2026-09-10 20:35	28.49	OK	602	2026-09-10 20:36	27.69	OK
603	2026-09-10 20:37	27.79	OK	604	2026-09-10 20:38	28.49	OK
605	2026-09-10 20:39	28.13	OK	606	2026-09-10 20:40	29.25	OK
607	2026-09-10 20:41	28.54	OK	608	2026-09-10 20:42	27.75	OK
609	2026-09-10 20:43	28.79	OK	610	2026-09-10 20:44	28.53	OK
611	2026-09-10 20:45	29.06	OK	612	2026-09-10 20:46	28.35	OK
613	2026-09-10 20:47	30.21	OK	614	2026-09-10 20:48	28.57	OK
615	2026-09-10 20:49	28.86	OK	616	2026-09-10 20:50	28.11	OK
617	2026-09-10 20:51	28.74	OK	618	2026-09-10 20:52	28.32	OK
619	2026-09-10 20:53	28.96	OK	620	2026-09-10 20:54	28.81	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
621	2026-09-10 20:55	28.74	OK	622	2026-09-10 20:56	27.82	OK
623	2026-09-10 20:57	29.73	OK	624	2026-09-10 20:58	28.48	OK
625	2026-09-10 20:59	28.76	OK	626	2026-09-10 21:00	27.96	OK
627	2026-09-10 21:01	29.63	OK	628	2026-09-10 21:02	28.67	OK
629	2026-09-10 21:03	29.02	OK	630	2026-09-10 21:04	28.34	OK
631	2026-09-10 21:05	30.14	OK	632	2026-09-10 21:06	28.02	OK
633	2026-09-10 21:07	28.47	OK	634	2026-09-10 21:08	29.83	OK
635	2026-09-10 21:09	29.50	OK	636	2026-09-10 21:10	27.95	OK
637	2026-09-10 21:11	29.61	OK	638	2026-09-10 21:12	28.94	OK
639	2026-09-10 21:13	29.47	OK	640	2026-09-10 21:14	29.37	OK
641	2026-09-10 21:15	27.52	OK	642	2026-09-10 21:16	30.37	OK
643	2026-09-10 21:17	29.52	OK	644	2026-09-10 21:18	28.27	OK
645	2026-09-10 21:19	29.11	OK	646	2026-09-10 21:20	28.95	OK
647	2026-09-10 21:21	28.84	OK	648	2026-09-10 21:22	28.59	OK
649	2026-09-10 21:23	28.03	OK	650	2026-09-10 21:24	27.13	OK
651	2026-09-10 21:25	30.03	OK	652	2026-09-10 21:26	28.74	OK
653	2026-09-10 21:27	29.22	OK	654	2026-09-10 21:28	29.70	OK
655	2026-09-10 21:29	29.07	OK	656	2026-09-10 21:30	28.68	OK
657	2026-09-10 21:31	28.97	OK	658	2026-09-10 21:32	29.42	OK
659	2026-09-10 21:33	27.74	OK	660	2026-09-10 21:34	29.04	OK
661	2026-09-10 21:35	29.26	OK	662	2026-09-10 21:36	28.91	OK
663	2026-09-10 21:37	28.93	OK	664	2026-09-10 21:38	31.04	OK
665	2026-09-10 21:39	28.59	OK	666	2026-09-10 21:40	28.23	OK
667	2026-09-10 21:41	27.32	OK	668	2026-09-10 21:42	28.12	OK
669	2026-09-10 21:43	29.79	OK	670	2026-09-10 21:44	29.27	OK
671	2026-09-10 21:45	28.50	OK	672	2026-09-10 21:46	28.17	OK
673	2026-09-10 21:47	29.76	OK	674	2026-09-10 21:48	30.15	OK
675	2026-09-10 21:49	28.13	OK	676	2026-09-10 21:50	30.52	OK
677	2026-09-10 21:51	29.25	OK	678	2026-09-10 21:52	29.01	OK
679	2026-09-10 21:53	28.67	OK	680	2026-09-10 21:54	29.28	OK
681	2026-09-10 21:55	29.95	OK	682	2026-09-10 21:56	29.25	OK
683	2026-09-10 21:57	27.78	OK	684	2026-09-10 21:58	28.61	OK
685	2026-09-10 21:59	29.67	OK	686	2026-09-10 22:00	30.06	OK
687	2026-09-10 22:01	28.85	OK	688	2026-09-10 22:02	29.98	OK
689	2026-09-10 22:03	29.68	OK	690	2026-09-10 22:04	29.73	OK
691	2026-09-10 22:05	30.10	OK	692	2026-09-10 22:06	30.16	OK
693	2026-09-10 22:07	29.64	OK	694	2026-09-10 22:08	30.53	OK
695	2026-09-10 22:09	29.21	OK	696	2026-09-10 22:10	27.43	OK
697	2026-09-10 22:11	29.15	OK	698	2026-09-10 22:12	30.30	OK
699	2026-09-10 22:13	29.83	OK	700	2026-09-10 22:14	29.84	OK
701	2026-09-10 22:15	30.43	OK	702	2026-09-10 22:16	29.03	OK
703	2026-09-10 22:17	28.55	OK	704	2026-09-10 22:18	29.06	OK
705	2026-09-10 22:19	28.95	OK	706	2026-09-10 22:20	29.47	OK
707	2026-09-10 22:21	29.33	OK	708	2026-09-10 22:22	29.49	OK
709	2026-09-10 22:23	30.36	OK	710	2026-09-10 22:24	31.03	OK
711	2026-09-10 22:25	31.06	OK	712	2026-09-10 22:26	30.05	OK
713	2026-09-10 22:27	28.99	OK	714	2026-09-10 22:28	28.95	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
715	2026-09-10 22:29	31.12	OK	716	2026-09-10 22:30	27.97	OK
717	2026-09-10 22:31	29.07	OK	718	2026-09-10 22:32	29.20	OK
719	2026-09-10 22:33	29.43	OK	720	2026-09-10 22:34	29.22	OK
721	2026-09-10 22:35	28.38	OK	722	2026-09-10 22:36	30.71	OK
723	2026-09-10 22:37	30.81	OK	724	2026-09-10 22:38	29.65	OK
725	2026-09-10 22:39	28.67	OK	726	2026-09-10 22:40	28.98	OK
727	2026-09-10 22:41	29.87	OK	728	2026-09-10 22:42	29.51	OK
729	2026-09-10 22:43	29.41	OK	730	2026-09-10 22:44	30.40	OK
731	2026-09-10 22:45	29.30	OK	732	2026-09-10 22:46	30.72	OK
733	2026-09-10 22:47	28.44	OK	734	2026-09-10 22:48	30.49	OK
735	2026-09-10 22:49	30.24	OK	736	2026-09-10 22:50	30.01	OK
737	2026-09-10 22:51	28.01	OK	738	2026-09-10 22:52	29.66	OK
739	2026-09-10 22:53	28.55	OK	740	2026-09-10 22:54	30.64	OK
741	2026-09-10 22:55	29.39	OK	742	2026-09-10 22:56	29.35	OK
743	2026-09-10 22:57	29.93	OK	744	2026-09-10 22:58	29.36	OK
745	2026-09-10 22:59	29.82	OK	746	2026-09-10 23:00	29.79	OK
747	2026-09-10 23:01	28.28	OK	748	2026-09-10 23:02	30.39	OK
749	2026-09-10 23:03	30.28	OK	750	2026-09-10 23:04	29.09	OK
751	2026-09-10 23:05	29.19	OK	752	2026-09-10 23:06	30.85	OK
753	2026-09-10 23:07	30.74	OK	754	2026-09-10 23:08	28.92	OK
755	2026-09-10 23:09	30.11	OK	756	2026-09-10 23:10	30.61	OK
757	2026-09-10 23:11	28.27	OK	758	2026-09-10 23:12	29.85	OK
759	2026-09-10 23:13	29.85	OK	760	2026-09-10 23:14	30.21	OK
761	2026-09-10 23:15	29.53	OK	762	2026-09-10 23:16	29.98	OK
763	2026-09-10 23:17	29.79	OK	764	2026-09-10 23:18	31.20	OK
765	2026-09-10 23:19	30.21	OK	766	2026-09-10 23:20	30.91	OK
767	2026-09-10 23:21	30.70	OK	768	2026-09-10 23:22	30.74	OK
769	2026-09-10 23:23	29.12	OK	770	2026-09-10 23:24	30.21	OK
771	2026-09-10 23:25	31.01	OK	772	2026-09-10 23:26	29.47	OK
773	2026-09-10 23:27	29.25	OK	774	2026-09-10 23:28	28.81	OK
775	2026-09-10 23:29	29.56	OK	776	2026-09-10 23:30	30.71	OK
777	2026-09-10 23:31	29.77	OK	778	2026-09-10 23:32	30.41	OK
779	2026-09-10 23:33	30.45	OK	780	2026-09-10 23:34	30.77	OK
781	2026-09-10 23:35	29.33	OK	782	2026-09-10 23:36	30.50	OK
783	2026-09-10 23:37	29.54	OK	784	2026-09-10 23:38	30.66	OK
785	2026-09-10 23:39	29.49	OK	786	2026-09-10 23:40	29.64	OK
787	2026-09-10 23:41	31.49	OK	788	2026-09-10 23:42	29.62	OK
789	2026-09-10 23:43	29.93	OK	790	2026-09-10 23:44	29.73	OK
791	2026-09-10 23:45	30.76	OK	792	2026-09-10 23:46	30.31	OK
793	2026-09-10 23:47	29.94	OK	794	2026-09-10 23:48	30.01	OK
795	2026-09-10 23:49	30.22	OK	796	2026-09-10 23:50	29.04	OK
797	2026-09-10 23:51	30.52	OK	798	2026-09-10 23:52	30.17	OK
799	2026-09-10 23:53	31.09	OK	800	2026-09-10 23:54	30.81	OK
801	2026-09-10 23:55	30.64	OK	802	2026-09-10 23:56	28.94	OK
803	2026-09-10 23:57	30.82	OK	804	2026-09-10 23:58	28.69	OK
805	2026-09-10 23:59	30.20	OK	806	2026-09-11 00:00	30.64	OK
807	2026-09-11 00:01	29.45	OK	808	2026-09-11 00:02	30.46	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
809	2026-09-11 00:03	29.00	OK	810	2026-09-11 00:04	31.06	OK
811	2026-09-11 00:05	29.88	OK	812	2026-09-11 00:06	30.14	OK
813	2026-09-11 00:07	29.49	OK	814	2026-09-11 00:08	29.51	OK
815	2026-09-11 00:09	30.44	OK	816	2026-09-11 00:10	30.61	OK
817	2026-09-11 00:11	29.27	OK	818	2026-09-11 00:12	30.13	OK
819	2026-09-11 00:13	30.35	OK	820	2026-09-11 00:14	29.59	OK
821	2026-09-11 00:15	29.48	OK	822	2026-09-11 00:16	28.92	OK
823	2026-09-11 00:17	30.60	OK	824	2026-09-11 00:18	30.41	OK
825	2026-09-11 00:19	29.80	OK	826	2026-09-11 00:20	30.76	OK
827	2026-09-11 00:21	30.02	OK	828	2026-09-11 00:22	29.99	OK
829	2026-09-11 00:23	29.68	OK	830	2026-09-11 00:24	31.29	OK
831	2026-09-11 00:25	31.49	OK	832	2026-09-11 00:26	29.50	OK
833	2026-09-11 00:27	29.31	OK	834	2026-09-11 00:28	30.10	OK
835	2026-09-11 00:29	29.84	OK	836	2026-09-11 00:30	31.73	OK
837	2026-09-11 00:31	29.87	OK	838	2026-09-11 00:32	30.03	OK
839	2026-09-11 00:33	31.19	OK	840	2026-09-11 00:34	29.97	OK
841	2026-09-11 00:35	30.54	OK	842	2026-09-11 00:36	30.13	OK
843	2026-09-11 00:37	28.89	OK	844	2026-09-11 00:38	31.80	OK
845	2026-09-11 00:39	30.31	OK	846	2026-09-11 00:40	29.48	OK
847	2026-09-11 00:41	30.58	OK	848	2026-09-11 00:42	29.40	OK
849	2026-09-11 00:43	29.73	OK	850	2026-09-11 00:44	31.04	OK
851	2026-09-11 00:45	29.92	OK	852	2026-09-11 00:46	30.55	OK
853	2026-09-11 00:47	30.25	OK	854	2026-09-11 00:48	30.02	OK
855	2026-09-11 00:49	29.60	OK	856	2026-09-11 00:50	31.60	OK
857	2026-09-11 00:51	29.81	OK	858	2026-09-11 00:52	30.79	OK
859	2026-09-11 00:53	29.76	OK	860	2026-09-11 00:54	28.53	OK
861	2026-09-11 00:55	29.61	OK	862	2026-09-11 00:56	29.30	OK
863	2026-09-11 00:57	30.93	OK	864	2026-09-11 00:58	29.35	OK
865	2026-09-11 00:59	30.64	OK	866	2026-09-11 01:00	29.99	OK
867	2026-09-11 01:01	30.60	OK	868	2026-09-11 01:02	29.49	OK
869	2026-09-11 01:03	29.71	OK	870	2026-09-11 01:04	30.17	OK
871	2026-09-11 01:05	30.12	OK	872	2026-09-11 01:06	31.18	OK
873	2026-09-11 01:07	29.30	OK	874	2026-09-11 01:08	30.00	OK
875	2026-09-11 01:09	29.61	OK	876	2026-09-11 01:10	29.68	OK
877	2026-09-11 01:11	29.59	OK	878	2026-09-11 01:12	31.57	OK
879	2026-09-11 01:13	30.03	OK	880	2026-09-11 01:14	31.55	OK
881	2026-09-11 01:15	30.49	OK	882	2026-09-11 01:16	29.78	OK
883	2026-09-11 01:17	30.04	OK	884	2026-09-11 01:18	30.40	OK
885	2026-09-11 01:19	30.45	OK	886	2026-09-11 01:20	30.34	OK
887	2026-09-11 01:21	29.39	OK	888	2026-09-11 01:22	30.11	OK
889	2026-09-11 01:23	29.89	OK	890	2026-09-11 01:24	30.86	OK
891	2026-09-11 01:25	31.29	OK	892	2026-09-11 01:26	30.46	OK
893	2026-09-11 01:27	30.95	OK	894	2026-09-11 01:28	28.33	OK
895	2026-09-11 01:29	28.85	OK	896	2026-09-11 01:30	31.39	OK
897	2026-09-11 01:31	29.77	OK	898	2026-09-11 01:32	30.68	OK
899	2026-09-11 01:33	30.28	OK	900	2026-09-11 01:34	30.92	OK
901	2026-09-11 01:35	30.57	OK	902	2026-09-11 01:36	29.71	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
903	2026-09-11 01:37	30.74	OK	904	2026-09-11 01:38	30.55	OK
905	2026-09-11 01:39	29.56	OK	906	2026-09-11 01:40	29.78	OK
907	2026-09-11 01:41	30.57	OK	908	2026-09-11 01:42	30.47	OK
909	2026-09-11 01:43	29.32	OK	910	2026-09-11 01:44	29.77	OK
911	2026-09-11 01:45	30.47	OK	912	2026-09-11 01:46	30.59	OK
913	2026-09-11 01:47	31.65	OK	914	2026-09-11 01:48	30.54	OK
915	2026-09-11 01:49	31.79	OK	916	2026-09-11 01:50	30.64	OK
917	2026-09-11 01:51	29.94	OK	918	2026-09-11 01:52	30.76	OK
919	2026-09-11 01:53	30.30	OK	920	2026-09-11 01:54	29.35	OK
921	2026-09-11 01:55	31.93	OK	922	2026-09-11 01:56	31.45	OK
923	2026-09-11 01:57	31.69	OK	924	2026-09-11 01:58	31.97	OK
925	2026-09-11 01:59	30.36	OK	926	2026-09-11 02:00	31.04	OK
927	2026-09-11 02:01	28.53	OK	928	2026-09-11 02:02	28.83	OK
929	2026-09-11 02:03	30.24	OK	930	2026-09-11 02:04	30.71	OK
931	2026-09-11 02:05	29.38	OK	932	2026-09-11 02:06	30.38	OK
933	2026-09-11 02:07	30.03	OK	934	2026-09-11 02:08	30.96	OK
935	2026-09-11 02:09	29.68	OK	936	2026-09-11 02:10	31.50	OK
937	2026-09-11 02:11	30.49	OK	938	2026-09-11 02:12	29.55	OK
939	2026-09-11 02:13	29.51	OK	940	2026-09-11 02:14	28.94	OK
941	2026-09-11 02:15	28.85	OK	942	2026-09-11 02:16	30.45	OK
943	2026-09-11 02:17	30.60	OK	944	2026-09-11 02:18	30.19	OK
945	2026-09-11 02:19	31.40	OK	946	2026-09-11 02:20	29.98	OK
947	2026-09-11 02:21	30.85	OK	948	2026-09-11 02:22	30.17	OK
949	2026-09-11 02:23	30.65	OK	950	2026-09-11 02:24	31.49	OK
951	2026-09-11 02:25	29.74	OK	952	2026-09-11 02:26	29.70	OK
953	2026-09-11 02:27	29.47	OK	954	2026-09-11 02:28	30.31	OK
955	2026-09-11 02:29	29.63	OK	956	2026-09-11 02:30	30.66	OK
957	2026-09-11 02:31	31.03	OK	958	2026-09-11 02:32	29.45	OK
959	2026-09-11 02:33	30.01	OK	960	2026-09-11 02:34	30.29	OK
961	2026-09-11 02:35	31.61	OK	962	2026-09-11 02:36	29.54	OK
963	2026-09-11 02:37	30.32	OK	964	2026-09-11 02:38	30.12	OK
965	2026-09-11 02:39	32.02	OK	966	2026-09-11 02:40	30.78	OK
967	2026-09-11 02:41	30.54	OK	968	2026-09-11 02:42	29.51	OK
969	2026-09-11 02:43	30.19	OK	970	2026-09-11 02:44	30.08	OK
971	2026-09-11 02:45	29.68	OK	972	2026-09-11 02:46	29.43	OK
973	2026-09-11 02:47	30.01	OK	974	2026-09-11 02:48	31.30	OK
975	2026-09-11 02:49	29.78	OK	976	2026-09-11 02:50	30.70	OK
977	2026-09-11 02:51	30.36	OK	978	2026-09-11 02:52	30.37	OK
979	2026-09-11 02:53	30.22	OK	980	2026-09-11 02:54	31.59	OK
981	2026-09-11 02:55	30.11	OK	982	2026-09-11 02:56	28.62	OK
983	2026-09-11 02:57	28.60	OK	984	2026-09-11 02:58	31.85	OK
985	2026-09-11 02:59	31.60	OK	986	2026-09-11 03:00	31.68	OK
987	2026-09-11 03:01	30.29	OK	988	2026-09-11 03:02	29.82	OK
989	2026-09-11 03:03	31.83	OK	990	2026-09-11 03:04	28.65	OK
991	2026-09-11 03:05	29.52	OK	992	2026-09-11 03:06	30.12	OK
993	2026-09-11 03:07	29.19	OK	994	2026-09-11 03:08	29.21	OK
995	2026-09-11 03:09	28.16	OK	996	2026-09-11 03:10	30.14	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
997	2026-09-11 03:11	30.14	OK	998	2026-09-11 03:12	30.40	OK
999	2026-09-11 03:13	29.50	OK	1000	2026-09-11 03:14	30.69	OK
1001	2026-09-11 03:15	29.85	OK	1002	2026-09-11 03:16	30.17	OK
1003	2026-09-11 03:17	29.73	OK	1004	2026-09-11 03:18	28.87	OK
1005	2026-09-11 03:19	29.91	OK	1006	2026-09-11 03:20	30.37	OK
1007	2026-09-11 03:21	29.81	OK	1008	2026-09-11 03:22	30.10	OK
1009	2026-09-11 03:23	31.20	OK	1010	2026-09-11 03:24	31.03	OK
1011	2026-09-11 03:25	29.80	OK	1012	2026-09-11 03:26	31.04	OK
1013	2026-09-11 03:27	28.52	OK	1014	2026-09-11 03:28	30.10	OK
1015	2026-09-11 03:29	29.43	OK	1016	2026-09-11 03:30	30.26	OK
1017	2026-09-11 03:31	29.31	OK	1018	2026-09-11 03:32	29.27	OK
1019	2026-09-11 03:33	28.90	OK	1020	2026-09-11 03:34	30.19	OK
1021	2026-09-11 03:35	30.15	OK	1022	2026-09-11 03:36	30.04	OK
1023	2026-09-11 03:37	29.50	OK	1024	2026-09-11 03:38	30.29	OK
1025	2026-09-11 03:39	29.91	OK	1026	2026-09-11 03:40	29.54	OK
1027	2026-09-11 03:41	28.02	OK	1028	2026-09-11 03:42	29.39	OK
1029	2026-09-11 03:43	29.53	OK	1030	2026-09-11 03:44	29.70	OK
1031	2026-09-11 03:45	30.90	OK	1032	2026-09-11 03:46	29.24	OK
1033	2026-09-11 03:47	30.05	OK	1034	2026-09-11 03:48	30.16	OK
1035	2026-09-11 03:49	28.87	OK	1036	2026-09-11 03:50	29.76	OK
1037	2026-09-11 03:51	29.68	OK	1038	2026-09-11 03:52	28.99	OK
1039	2026-09-11 03:53	29.64	OK	1040	2026-09-11 03:54	30.80	OK
1041	2026-09-11 03:55	30.01	OK	1042	2026-09-11 03:56	30.20	OK
1043	2026-09-11 03:57	29.55	OK	1044	2026-09-11 03:58	30.43	OK
1045	2026-09-11 03:59	29.20	OK	1046	2026-09-11 04:00	28.50	OK
1047	2026-09-11 04:01	30.63	OK	1048	2026-09-11 04:02	29.36	OK
1049	2026-09-11 04:03	29.65	OK	1050	2026-09-11 04:04	29.70	OK
1051	2026-09-11 04:05	29.25	OK	1052	2026-09-11 04:06	31.06	OK
1053	2026-09-11 04:07	28.26	OK	1054	2026-09-11 04:08	28.32	OK
1055	2026-09-11 04:09	28.80	OK	1056	2026-09-11 04:10	27.91	OK
1057	2026-09-11 04:11	29.35	OK	1058	2026-09-11 04:12	30.21	OK
1059	2026-09-11 04:13	30.22	OK	1060	2026-09-11 04:14	28.45	OK
1061	2026-09-11 04:15	31.24	OK	1062	2026-09-11 04:16	27.92	OK
1063	2026-09-11 04:17	29.38	OK	1064	2026-09-11 04:18	28.37	OK
1065	2026-09-11 04:19	29.94	OK	1066	2026-09-11 04:20	29.39	OK
1067	2026-09-11 04:21	30.35	OK	1068	2026-09-11 04:22	30.72	OK
1069	2026-09-11 04:23	30.43	OK	1070	2026-09-11 04:24	30.13	OK
1071	2026-09-11 04:25	29.33	OK	1072	2026-09-11 04:26	31.41	OK
1073	2026-09-11 04:27	30.19	OK	1074	2026-09-11 04:28	28.85	OK
1075	2026-09-11 04:29	27.92	OK	1076	2026-09-11 04:30	29.50	OK
1077	2026-09-11 04:31	29.70	OK	1078	2026-09-11 04:32	28.40	OK
1079	2026-09-11 04:33	29.07	OK	1080	2026-09-11 04:34	28.63	OK
1081	2026-09-11 04:35	29.58	OK	1082	2026-09-11 04:36	29.40	OK
1083	2026-09-11 04:37	30.23	OK	1084	2026-09-11 04:38	27.76	OK
1085	2026-09-11 04:39	30.24	OK	1086	2026-09-11 04:40	29.27	OK
1087	2026-09-11 04:41	30.45	OK	1088	2026-09-11 04:42	29.21	OK
1089	2026-09-11 04:43	28.83	OK	1090	2026-09-11 04:44	30.42	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1091	2026-09-11 04:45	29.45	OK	1092	2026-09-11 04:46	28.61	OK
1093	2026-09-11 04:47	30.96	OK	1094	2026-09-11 04:48	28.58	OK
1095	2026-09-11 04:49	29.08	OK	1096	2026-09-11 04:50	29.26	OK
1097	2026-09-11 04:51	30.68	OK	1098	2026-09-11 04:52	29.17	OK
1099	2026-09-11 04:53	28.86	OK	1100	2026-09-11 04:54	30.01	OK
1101	2026-09-11 04:55	29.30	OK	1102	2026-09-11 04:56	28.55	OK
1103	2026-09-11 04:57	30.00	OK	1104	2026-09-11 04:58	27.97	OK
1105	2026-09-11 04:59	29.34	OK	1106	2026-09-11 05:00	29.55	OK
1107	2026-09-11 05:01	30.62	OK	1108	2026-09-11 05:02	29.42	OK
1109	2026-09-11 05:03	29.11	OK	1110	2026-09-11 05:04	30.05	OK
1111	2026-09-11 05:05	30.48	OK	1112	2026-09-11 05:06	29.91	OK
1113	2026-09-11 05:07	28.31	OK	1114	2026-09-11 05:08	28.71	OK
1115	2026-09-11 05:09	29.86	OK	1116	2026-09-11 05:10	29.02	OK
1117	2026-09-11 05:11	30.01	OK	1118	2026-09-11 05:12	28.86	OK
1119	2026-09-11 05:13	28.73	OK	1120	2026-09-11 05:14	29.21	OK
1121	2026-09-11 05:15	30.05	OK	1122	2026-09-11 05:16	29.37	OK
1123	2026-09-11 05:17	28.09	OK	1124	2026-09-11 05:18	29.04	OK
1125	2026-09-11 05:19	29.02	OK	1126	2026-09-11 05:20	28.30	OK
1127	2026-09-11 05:21	30.52	OK	1128	2026-09-11 05:22	28.08	OK
1129	2026-09-11 05:23	28.23	OK	1130	2026-09-11 05:24	28.94	OK
1131	2026-09-11 05:25	29.69	OK	1132	2026-09-11 05:26	30.35	OK
1133	2026-09-11 05:27	28.74	OK	1134	2026-09-11 05:28	29.43	OK
1135	2026-09-11 05:29	29.77	OK	1136	2026-09-11 05:30	29.30	OK
1137	2026-09-11 05:31	29.41	OK	1138	2026-09-11 05:32	28.35	OK
1139	2026-09-11 05:33	29.44	OK	1140	2026-09-11 05:34	28.51	OK
1141	2026-09-11 05:35	27.99	OK	1142	2026-09-11 05:36	27.43	OK
1143	2026-09-11 05:37	29.07	OK	1144	2026-09-11 05:38	28.95	OK
1145	2026-09-11 05:39	29.01	OK	1146	2026-09-11 05:40	28.76	OK
1147	2026-09-11 05:41	28.39	OK	1148	2026-09-11 05:42	28.79	OK
1149	2026-09-11 05:43	28.68	OK	1150	2026-09-11 05:44	28.78	OK
1151	2026-09-11 05:45	28.28	OK	1152	2026-09-11 05:46	28.87	OK
1153	2026-09-11 05:47	29.64	OK	1154	2026-09-11 05:48	28.64	OK
1155	2026-09-11 05:49	30.45	OK	1156	2026-09-11 05:50	29.00	OK
1157	2026-09-11 05:51	28.16	OK	1158	2026-09-11 05:52	28.49	OK
1159	2026-09-11 05:53	29.61	OK	1160	2026-09-11 05:54	28.29	OK
1161	2026-09-11 05:55	28.85	OK	1162	2026-09-11 05:56	28.94	OK
1163	2026-09-11 05:57	29.83	OK	1164	2026-09-11 05:58	29.42	OK
1165	2026-09-11 05:59	30.67	OK	1166	2026-09-11 06:00	28.69	OK
1167	2026-09-11 06:01	28.15	OK	1168	2026-09-11 06:02	28.61	OK
1169	2026-09-11 06:03	27.90	OK	1170	2026-09-11 06:04	29.28	OK
1171	2026-09-11 06:05	27.99	OK	1172	2026-09-11 06:06	28.20	OK
1173	2026-09-11 06:07	28.37	OK	1174	2026-09-11 06:08	28.68	OK
1175	2026-09-11 06:09	29.57	OK	1176	2026-09-11 06:10	28.19	OK
1177	2026-09-11 06:11	27.91	OK	1178	2026-09-11 06:12	30.12	OK
1179	2026-09-11 06:13	29.70	OK	1180	2026-09-11 06:14	27.92	OK
1181	2026-09-11 06:15	28.57	OK	1182	2026-09-11 06:16	29.24	OK
1183	2026-09-11 06:17	28.20	OK	1184	2026-09-11 06:18	28.71	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1185	2026-09-11 06:19	28.31	OK	1186	2026-09-11 06:20	30.60	OK
1187	2026-09-11 06:21	29.48	OK	1188	2026-09-11 06:22	28.50	OK
1189	2026-09-11 06:23	28.13	OK	1190	2026-09-11 06:24	29.52	OK
1191	2026-09-11 06:25	28.32	OK	1192	2026-09-11 06:26	27.72	OK
1193	2026-09-11 06:27	29.79	OK	1194	2026-09-11 06:28	28.68	OK
1195	2026-09-11 06:29	29.52	OK	1196	2026-09-11 06:30	28.71	OK
1197	2026-09-11 06:31	27.80	OK	1198	2026-09-11 06:32	27.62	OK
1199	2026-09-11 06:33	29.26	OK	1200	2026-09-11 06:34	29.90	OK
1201	2026-09-11 06:35	30.37	OK	1202	2026-09-11 06:36	28.94	OK
1203	2026-09-11 06:37	28.70	OK	1204	2026-09-11 06:38	27.19	OK
1205	2026-09-11 06:39	28.78	OK	1206	2026-09-11 06:40	29.04	OK
1207	2026-09-11 06:41	29.88	OK	1208	2026-09-11 06:42	29.69	OK
1209	2026-09-11 06:43	29.07	OK	1210	2026-09-11 06:44	28.92	OK
1211	2026-09-11 06:45	29.86	OK	1212	2026-09-11 06:46	29.56	OK
1213	2026-09-11 06:47	29.05	OK	1214	2026-09-11 06:48	28.47	OK
1215	2026-09-11 06:49	28.10	OK	1216	2026-09-11 06:50	26.86	OK
1217	2026-09-11 06:51	27.52	OK	1218	2026-09-11 06:52	27.99	OK
1219	2026-09-11 06:53	27.22	OK	1220	2026-09-11 06:54	28.12	OK
1221	2026-09-11 06:55	29.61	OK	1222	2026-09-11 06:56	28.31	OK
1223	2026-09-11 06:57	28.31	OK	1224	2026-09-11 06:58	28.69	OK
1225	2026-09-11 06:59	27.64	OK	1226	2026-09-11 07:00	29.05	OK
1227	2026-09-11 07:01	28.94	OK	1228	2026-09-11 07:02	28.86	OK
1229	2026-09-11 07:03	27.15	OK	1230	2026-09-11 07:04	27.86	OK
1231	2026-09-11 07:05	27.96	OK	1232	2026-09-11 07:06	28.57	OK
1233	2026-09-11 07:07	29.07	OK	1234	2026-09-11 07:08	27.44	OK
1235	2026-09-11 07:09	27.74	OK	1236	2026-09-11 07:10	29.29	OK
1237	2026-09-11 07:11	29.60	OK	1238	2026-09-11 07:12	28.40	OK
1239	2026-09-11 07:13	29.22	OK	1240	2026-09-11 07:14	27.92	OK
1241	2026-09-11 07:15	27.97	OK	1242	2026-09-11 07:16	28.06	OK
1243	2026-09-11 07:17	27.36	OK	1244	2026-09-11 07:18	27.23	OK
1245	2026-09-11 07:19	28.37	OK	1246	2026-09-11 07:20	28.63	OK
1247	2026-09-11 07:21	28.73	OK	1248	2026-09-11 07:22	27.92	OK
1249	2026-09-11 07:23	28.59	OK	1250	2026-09-11 07:24	29.10	OK
1251	2026-09-11 07:25	28.59	OK	1252	2026-09-11 07:26	27.08	OK
1253	2026-09-11 07:27	29.83	OK	1254	2026-09-11 07:28	28.54	OK
1255	2026-09-11 07:29	26.85	OK	1256	2026-09-11 07:30	28.15	OK
1257	2026-09-11 07:31	27.62	OK	1258	2026-09-11 07:32	27.71	OK
1259	2026-09-11 07:33	27.49	OK	1260	2026-09-11 07:34	27.36	OK
1261	2026-09-11 07:35	26.99	OK	1262	2026-09-11 07:36	28.90	OK
1263	2026-09-11 07:37	28.36	OK	1264	2026-09-11 07:38	28.07	OK
1265	2026-09-11 07:39	28.54	OK	1266	2026-09-11 07:40	27.51	OK
1267	2026-09-11 07:41	27.58	OK	1268	2026-09-11 07:42	27.49	OK
1269	2026-09-11 07:43	27.95	OK	1270	2026-09-11 07:44	27.11	OK
1271	2026-09-11 07:45	26.94	OK	1272	2026-09-11 07:46	28.88	OK
1273	2026-09-11 07:47	26.38	OK	1274	2026-09-11 07:48	27.62	OK
1275	2026-09-11 07:49	27.85	OK	1276	2026-09-11 07:50	27.94	OK
1277	2026-09-11 07:51	27.64	OK	1278	2026-09-11 07:52	27.72	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1279	2026-09-11 07:53	26.50	OK	1280	2026-09-11 07:54	28.30	OK
1281	2026-09-11 07:55	27.93	OK	1282	2026-09-11 07:56	26.55	OK
1283	2026-09-11 07:57	26.89	OK	1284	2026-09-11 07:58	26.70	OK
1285	2026-09-11 07:59	29.01	OK	1286	2026-09-11 08:00	28.25	OK
1287	2026-09-11 08:01	27.37	OK	1288	2026-09-11 08:02	27.95	OK
1289	2026-09-11 08:03	28.20	OK	1290	2026-09-11 08:04	27.49	OK
1291	2026-09-11 08:05	26.80	OK	1292	2026-09-11 08:06	27.50	OK
1293	2026-09-11 08:07	28.43	OK	1294	2026-09-11 08:08	28.14	OK
1295	2026-09-11 08:09	28.11	OK	1296	2026-09-11 08:10	27.59	OK
1297	2026-09-11 08:11	27.97	OK	1298	2026-09-11 08:12	28.73	OK
1299	2026-09-11 08:13	27.18	OK	1300	2026-09-11 08:14	29.20	OK
1301	2026-09-11 08:15	27.99	OK	1302	2026-09-11 08:16	27.28	OK
1303	2026-09-11 08:17	27.72	OK	1304	2026-09-11 08:18	27.17	OK
1305	2026-09-11 08:19	27.72	OK	1306	2026-09-11 08:20	27.78	OK
1307	2026-09-11 08:21	27.82	OK	1308	2026-09-11 08:22	27.12	OK
1309	2026-09-11 08:23	26.76	OK	1310	2026-09-11 08:24	27.69	OK
1311	2026-09-11 08:25	27.98	OK	1312	2026-09-11 08:26	26.59	OK
1313	2026-09-11 08:27	26.57	OK	1314	2026-09-11 08:28	27.89	OK
1315	2026-09-11 08:29	28.46	OK	1316	2026-09-11 08:30	26.87	OK
1317	2026-09-11 08:31	28.08	OK	1318	2026-09-11 08:32	27.18	OK
1319	2026-09-11 08:33	27.52	OK	1320	2026-09-11 08:34	27.06	OK
1321	2026-09-11 08:35	27.41	OK	1322	2026-09-11 08:36	27.05	OK
1323	2026-09-11 08:37	27.30	OK	1324	2026-09-11 08:38	26.79	OK
1325	2026-09-11 08:39	27.63	OK	1326	2026-09-11 08:40	26.79	OK
1327	2026-09-11 08:41	27.98	OK	1328	2026-09-11 08:42	25.83	OK
1329	2026-09-11 08:43	27.64	OK	1330	2026-09-11 08:44	27.71	OK
1331	2026-09-11 08:45	27.26	OK	1332	2026-09-11 08:46	26.58	OK
1333	2026-09-11 08:47	26.42	OK	1334	2026-09-11 08:48	27.71	OK
1335	2026-09-11 08:49	26.68	OK	1336	2026-09-11 08:50	26.28	OK
1337	2026-09-11 08:51	27.51	OK	1338	2026-09-11 08:52	28.44	OK
1339	2026-09-11 08:53	26.14	OK	1340	2026-09-11 08:54	26.45	OK
1341	2026-09-11 08:55	28.68	OK	1342	2026-09-11 08:56	27.06	OK
1343	2026-09-11 08:57	26.01	OK	1344	2026-09-11 08:58	26.39	OK
1345	2026-09-11 08:59	26.57	OK	1346	2026-09-11 09:00	28.97	OK
1347	2026-09-11 09:01	27.39	OK	1348	2026-09-11 09:02	26.44	OK
1349	2026-09-11 09:03	28.01	OK	1350	2026-09-11 09:04	25.96	OK
1351	2026-09-11 09:05	26.20	OK	1352	2026-09-11 09:06	26.82	OK
1353	2026-09-11 09:07	25.63	OK	1354	2026-09-11 09:08	25.78	OK
1355	2026-09-11 09:09	27.14	OK	1356	2026-09-11 09:10	28.00	OK
1357	2026-09-11 09:11	25.77	OK	1358	2026-09-11 09:12	28.02	OK
1359	2026-09-11 09:13	27.19	OK	1360	2026-09-11 09:14	27.17	OK
1361	2026-09-11 09:15	28.58	OK	1362	2026-09-11 09:16	26.93	OK
1363	2026-09-11 09:17	25.78	OK	1364	2026-09-11 09:18	27.63	OK
1365	2026-09-11 09:19	26.12	OK	1366	2026-09-11 09:20	26.62	OK
1367	2026-09-11 09:21	25.56	OK	1368	2026-09-11 09:22	26.30	OK
1369	2026-09-11 09:23	26.04	OK	1370	2026-09-11 09:24	26.23	OK
1371	2026-09-11 09:25	26.07	OK	1372	2026-09-11 09:26	26.51	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1373	2026-09-11 09:27	26.13	OK	1374	2026-09-11 09:28	26.03	OK
1375	2026-09-11 09:29	27.22	OK	1376	2026-09-11 09:30	26.16	OK
1377	2026-09-11 09:31	26.49	OK	1378	2026-09-11 09:32	27.16	OK
1379	2026-09-11 09:33	26.98	OK	1380	2026-09-11 09:34	27.48	OK
1381	2026-09-11 09:35	26.49	OK	1382	2026-09-11 09:36	26.48	OK
1383	2026-09-11 09:37	25.53	OK	1384	2026-09-11 09:38	27.09	OK
1385	2026-09-11 09:39	25.37	OK	1386	2026-09-11 09:40	27.64	OK
1387	2026-09-11 09:41	26.78	OK	1388	2026-09-11 09:42	26.83	OK
1389	2026-09-11 09:43	27.56	OK	1390	2026-09-11 09:44	26.29	OK
1391	2026-09-11 09:45	26.87	OK	1392	2026-09-11 09:46	27.17	OK
1393	2026-09-11 09:47	26.14	OK	1394	2026-09-11 09:48	27.84	OK
1395	2026-09-11 09:49	26.04	OK	1396	2026-09-11 09:50	27.06	OK
1397	2026-09-11 09:51	26.40	OK	1398	2026-09-11 09:52	27.11	OK
1399	2026-09-11 09:53	25.58	OK	1400	2026-09-11 09:54	25.21	OK
1401	2026-09-11 09:55	26.28	OK	1402	2026-09-11 09:56	27.68	OK
1403	2026-09-11 09:57	26.96	OK	1404	2026-09-11 09:58	25.64	OK
1405	2026-09-11 09:59	28.24	OK	1406	2026-09-11 10:00	26.47	OK
1407	2026-09-11 10:01	26.82	OK	1408	2026-09-11 10:02	26.70	OK
1409	2026-09-11 10:03	27.05	OK	1410	2026-09-11 10:04	27.17	OK
1411	2026-09-11 10:05	26.64	OK	1412	2026-09-11 10:06	27.16	OK
1413	2026-09-11 10:07	27.24	OK	1414	2026-09-11 10:08	25.17	OK
1415	2026-09-11 10:09	25.40	OK	1416	2026-09-11 10:10	26.78	OK
1417	2026-09-11 10:11	26.68	OK	1418	2026-09-11 10:12	26.35	OK
1419	2026-09-11 10:13	25.29	OK	1420	2026-09-11 10:14	25.97	OK
1421	2026-09-11 10:15	25.45	OK	1422	2026-09-11 10:16	26.00	OK
1423	2026-09-11 10:17	25.89	OK	1424	2026-09-11 10:18	25.06	OK
1425	2026-09-11 10:19	26.52	OK	1426	2026-09-11 10:20	26.08	OK
1427	2026-09-11 10:21	26.22	OK	1428	2026-09-11 10:22	25.85	OK
1429	2026-09-11 10:23	26.54	OK	1430	2026-09-11 10:24	25.28	OK
1431	2026-09-11 10:25	26.44	OK	1432	2026-09-11 10:26	25.95	OK
1433	2026-09-11 10:27	25.85	OK	1434	2026-09-11 10:28	27.23	OK
1435	2026-09-11 10:29	27.22	OK	1436	2026-09-11 10:30	25.64	OK
1437	2026-09-11 10:31	27.13	OK	1438	2026-09-11 10:32	27.57	OK
1439	2026-09-11 10:33	26.69	OK	1440	2026-09-11 10:34	24.91	OK
1441	2026-09-11 10:35	26.58	OK	1442	2026-09-11 10:36	25.76	OK
1443	2026-09-11 10:37	26.09	OK	1444	2026-09-11 10:38	27.11	OK
1445	2026-09-11 10:39	27.11	OK	1446	2026-09-11 10:40	26.60	OK
1447	2026-09-11 10:41	26.25	OK	1448	2026-09-11 10:42	27.29	OK
1449	2026-09-11 10:43	27.06	OK	1450	2026-09-11 10:44	25.60	OK
1451	2026-09-11 10:45	27.02	OK	1452	2026-09-11 10:46	25.25	OK
1453	2026-09-11 10:47	26.69	OK	1454	2026-09-11 10:48	27.10	OK
1455	2026-09-11 10:49	24.87	OK	1456	2026-09-11 10:50	26.85	OK
1457	2026-09-11 10:51	26.10	OK	1458	2026-09-11 10:52	25.41	OK
1459	2026-09-11 10:53	26.54	OK	1460	2026-09-11 10:54	25.06	OK
1461	2026-09-11 10:55	26.76	OK	1462	2026-09-11 10:56	26.81	OK
1463	2026-09-11 10:57	27.00	OK	1464	2026-09-11 10:58	27.20	OK
1465	2026-09-11 10:59	26.10	OK	1466	2026-09-11 11:00	27.51	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1467	2026-09-11 11:01	26.90	OK	1468	2026-09-11 11:02	26.29	OK
1469	2026-09-11 11:03	26.16	OK	1470	2026-09-11 11:04	26.38	OK
1471	2026-09-11 11:05	25.92	OK	1472	2026-09-11 11:06	26.65	OK
1473	2026-09-11 11:07	24.29	OK	1474	2026-09-11 11:08	26.42	OK
1475	2026-09-11 11:09	24.82	OK	1476	2026-09-11 11:10	25.65	OK
1477	2026-09-11 11:11	25.25	OK	1478	2026-09-11 11:12	26.07	OK
1479	2026-09-11 11:13	26.36	OK	1480	2026-09-11 11:14	25.40	OK
1481	2026-09-11 11:15	25.63	OK	1482	2026-09-11 11:16	26.30	OK
1483	2026-09-11 11:17	26.45	OK	1484	2026-09-11 11:18	25.59	OK
1485	2026-09-11 11:19	26.97	OK	1486	2026-09-11 11:20	25.50	OK
1487	2026-09-11 11:21	26.02	OK	1488	2026-09-11 11:22	26.60	OK
1489	2026-09-11 11:23	25.44	OK	1490	2026-09-11 11:24	25.86	OK
1491	2026-09-11 11:25	25.35	OK	1492	2026-09-11 11:26	26.71	OK
1493	2026-09-11 11:27	25.79	OK	1494	2026-09-11 11:28	26.21	OK
1495	2026-09-11 11:29	26.43	OK	1496	2026-09-11 11:30	25.69	OK
1497	2026-09-11 11:31	26.68	OK	1498	2026-09-11 11:32	27.03	OK
1499	2026-09-11 11:33	25.56	OK	1500	2026-09-11 11:34	26.86	OK
1501	2026-09-11 11:35	24.74	OK	1502	2026-09-11 11:36	24.70	OK
1503	2026-09-11 11:37	25.91	OK	1504	2026-09-11 11:38	24.13	OK
1505	2026-09-11 11:39	24.85	OK	1506	2026-09-11 11:40	26.11	OK
1507	2026-09-11 11:41	25.37	OK	1508	2026-09-11 11:42	25.54	OK
1509	2026-09-11 11:43	26.77	OK	1510	2026-09-11 11:44	25.20	OK
1511	2026-09-11 11:45	25.93	OK	1512	2026-09-11 11:46	25.37	OK
1513	2026-09-11 11:47	26.59	OK	1514	2026-09-11 11:48	25.95	OK
1515	2026-09-11 11:49	26.78	OK	1516	2026-09-11 11:50	24.68	OK
1517	2026-09-11 11:51	25.11	OK	1518	2026-09-11 11:52	24.84	OK
1519	2026-09-11 11:53	25.60	OK	1520	2026-09-11 11:54	25.46	OK
1521	2026-09-11 11:55	24.86	OK	1522	2026-09-11 11:56	25.66	OK
1523	2026-09-11 11:57	26.73	OK	1524	2026-09-11 11:58	26.10	OK
1525	2026-09-11 11:59	24.26	OK	1526	2026-09-11 12:00	25.15	OK
1527	2026-09-11 12:01	25.84	OK	1528	2026-09-11 12:02	27.04	OK
1529	2026-09-11 12:03	26.11	OK	1530	2026-09-11 12:04	26.00	OK
1531	2026-09-11 12:05	25.65	OK	1532	2026-09-11 12:06	24.80	OK
1533	2026-09-11 12:07	25.71	OK	1534	2026-09-11 12:08	25.01	OK
1535	2026-09-11 12:09	25.48	OK	1536	2026-09-11 12:10	24.04	OK
1537	2026-09-11 12:11	26.39	OK	1538	2026-09-11 12:12	26.15	OK
1539	2026-09-11 12:13	25.80	OK	1540	2026-09-11 12:14	26.46	OK
1541	2026-09-11 12:15	25.98	OK	1542	2026-09-11 12:16	26.40	OK
1543	2026-09-11 12:17	24.52	OK	1544	2026-09-11 12:18	25.01	OK
1545	2026-09-11 12:19	25.29	OK	1546	2026-09-11 12:20	25.85	OK
1547	2026-09-11 12:21	27.09	OK	1548	2026-09-11 12:22	25.96	OK
1549	2026-09-11 12:23	24.49	OK	1550	2026-09-11 12:24	27.01	OK
1551	2026-09-11 12:25	25.86	OK	1552	2026-09-11 12:26	25.94	OK
1553	2026-09-11 12:27	26.89	OK	1554	2026-09-11 12:28	26.56	OK
1555	2026-09-11 12:29	25.07	OK	1556	2026-09-11 12:30	25.82	OK
1557	2026-09-11 12:31	25.78	OK	1558	2026-09-11 12:32	25.00	OK
1559	2026-09-11 12:33	26.49	OK	1560	2026-09-11 12:34	24.81	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1561	2026-09-11 12:35	26.57	OK	1562	2026-09-11 12:36	25.67	OK
1563	2026-09-11 12:37	24.86	OK	1564	2026-09-11 12:38	25.09	OK
1565	2026-09-11 12:39	25.76	OK	1566	2026-09-11 12:40	26.75	OK
1567	2026-09-11 12:41	25.93	OK	1568	2026-09-11 12:42	25.46	OK
1569	2026-09-11 12:43	27.31	OK	1570	2026-09-11 12:44	24.86	OK
1571	2026-09-11 12:45	26.01	OK	1572	2026-09-11 12:46	26.07	OK
1573	2026-09-11 12:47	26.41	OK	1574	2026-09-11 12:48	25.07	OK
1575	2026-09-11 12:49	25.77	OK	1576	2026-09-11 12:50	26.16	OK
1577	2026-09-11 12:51	25.74	OK	1578	2026-09-11 12:52	27.39	OK
1579	2026-09-11 12:53	24.84	OK	1580	2026-09-11 12:54	24.12	OK
1581	2026-09-11 12:55	25.13	OK	1582	2026-09-11 12:56	25.36	OK
1583	2026-09-11 12:57	24.87	OK	1584	2026-09-11 12:58	24.98	OK
1585	2026-09-11 12:59	25.73	OK	1586	2026-09-11 13:00	25.42	OK
1587	2026-09-11 13:01	24.45	OK	1588	2026-09-11 13:02	26.38	OK
1589	2026-09-11 13:03	25.76	OK	1590	2026-09-11 13:04	25.66	OK
1591	2026-09-11 13:05	26.59	OK	1592	2026-09-11 13:06	24.71	OK
1593	2026-09-11 13:07	26.45	OK	1594	2026-09-11 13:08	25.67	OK
1595	2026-09-11 13:09	25.93	OK	1596	2026-09-11 13:10	26.02	OK
1597	2026-09-11 13:11	24.99	OK	1598	2026-09-11 13:12	25.95	OK
1599	2026-09-11 13:13	26.58	OK	1600	2026-09-11 13:14	25.74	OK
1601	2026-09-11 13:15	25.15	OK	1602	2026-09-11 13:16	25.64	OK
1603	2026-09-11 13:17	26.49	OK	1604	2026-09-11 13:18	26.40	OK
1605	2026-09-11 13:19	25.88	OK	1606	2026-09-11 13:20	25.52	OK
1607	2026-09-11 13:21	25.93	OK	1608	2026-09-11 13:22	25.65	OK
1609	2026-09-11 13:23	25.67	OK	1610	2026-09-11 13:24	26.18	OK
1611	2026-09-11 13:25	25.23	OK	1612	2026-09-11 13:26	24.96	OK
1613	2026-09-11 13:27	25.29	OK	1614	2026-09-11 13:28	25.48	OK
1615	2026-09-11 13:29	26.47	OK	1616	2026-09-11 13:30	25.55	OK
1617	2026-09-11 13:31	25.28	OK	1618	2026-09-11 13:32	26.06	OK
1619	2026-09-11 13:33	25.89	OK	1620	2026-09-11 13:34	25.15	OK
1621	2026-09-11 13:35	24.51	OK	1622	2026-09-11 13:36	24.81	OK
1623	2026-09-11 13:37	26.42	OK	1624	2026-09-11 13:38	25.86	OK
1625	2026-09-11 13:39	25.68	OK	1626	2026-09-11 13:40	24.52	OK
1627	2026-09-11 13:41	25.33	OK	1628	2026-09-11 13:42	25.10	OK
1629	2026-09-11 13:43	25.88	OK	1630	2026-09-11 13:44	26.87	OK
1631	2026-09-11 13:45	27.16	OK	1632	2026-09-11 13:46	25.22	OK
1633	2026-09-11 13:47	25.77	OK	1634	2026-09-11 13:48	25.17	OK
1635	2026-09-11 13:49	26.17	OK	1636	2026-09-11 13:50	26.67	OK
1637	2026-09-11 13:51	25.80	OK	1638	2026-09-11 13:52	26.40	OK
1639	2026-09-11 13:53	25.75	OK	1640	2026-09-11 13:54	25.22	OK
1641	2026-09-11 13:55	25.53	OK	1642	2026-09-11 13:56	24.03	OK
1643	2026-09-11 13:57	24.78	OK	1644	2026-09-11 13:58	25.11	OK
1645	2026-09-11 13:59	25.81	OK	1646	2026-09-11 14:00	25.86	OK
1647	2026-09-11 14:01	25.01	OK	1648	2026-09-11 14:02	26.85	OK
1649	2026-09-11 14:03	25.84	OK	1650	2026-09-11 14:04	26.77	OK
1651	2026-09-11 14:05	26.30	OK	1652	2026-09-11 14:06	25.75	OK
1653	2026-09-11 14:07	25.77	OK	1654	2026-09-11 14:08	24.63	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1655	2026-09-11 14:09	26.43	OK	1656	2026-09-11 14:10	24.39	OK
1657	2026-09-11 14:11	25.19	OK	1658	2026-09-11 14:12	26.09	OK
1659	2026-09-11 14:13	25.78	OK	1660	2026-09-11 14:14	24.94	OK
1661	2026-09-11 14:15	24.86	OK	1662	2026-09-11 14:16	25.44	OK
1663	2026-09-11 14:17	26.19	OK	1664	2026-09-11 14:18	24.94	OK
1665	2026-09-11 14:19	25.87	OK	1666	2026-09-11 14:20	24.19	OK
1667	2026-09-11 14:21	25.11	OK	1668	2026-09-11 14:22	25.64	OK
1669	2026-09-11 14:23	25.28	OK	1670	2026-09-11 14:24	25.28	OK
1671	2026-09-11 14:25	26.50	OK	1672	2026-09-11 14:26	25.24	OK
1673	2026-09-11 14:27	24.48	OK	1674	2026-09-11 14:28	25.91	OK
1675	2026-09-11 14:29	25.02	OK	1676	2026-09-11 14:30	24.44	OK
1677	2026-09-11 14:31	25.66	OK	1678	2026-09-11 14:32	26.46	OK
1679	2026-09-11 14:33	26.55	OK	1680	2026-09-11 14:34	26.61	OK
1681	2026-09-11 14:35	25.81	OK	1682	2026-09-11 14:36	25.01	OK
1683	2026-09-11 14:37	27.38	OK	1684	2026-09-11 14:38	24.96	OK
1685	2026-09-11 14:39	26.32	OK	1686	2026-09-11 14:40	25.63	OK
1687	2026-09-11 14:41	27.19	OK	1688	2026-09-11 14:42	25.29	OK
1689	2026-09-11 14:43	24.36	OK	1690	2026-09-11 14:44	26.59	OK
1691	2026-09-11 14:45	26.18	OK	1692	2026-09-11 14:46	26.00	OK
1693	2026-09-11 14:47	27.00	OK	1694	2026-09-11 14:48	26.59	OK
1695	2026-09-11 14:49	27.46	OK	1696	2026-09-11 14:50	24.85	OK
1697	2026-09-11 14:51	25.74	OK	1698	2026-09-11 14:52	24.04	OK
1699	2026-09-11 14:53	25.88	OK	1700	2026-09-11 14:54	25.57	OK
1701	2026-09-11 14:55	25.72	OK	1702	2026-09-11 14:56	26.47	OK
1703	2026-09-11 14:57	25.70	OK	1704	2026-09-11 14:58	24.58	OK
1705	2026-09-11 14:59	25.56	OK	1706	2026-09-11 15:00	27.23	OK
1707	2026-09-11 15:01	25.25	OK	1708	2026-09-11 15:02	24.55	OK
1709	2026-09-11 15:03	25.12	OK	1710	2026-09-11 15:04	24.95	OK
1711	2026-09-11 15:05	26.18	OK	1712	2026-09-11 15:06	25.96	OK
1713	2026-09-11 15:07	26.92	OK	1714	2026-09-11 15:08	25.50	OK
1715	2026-09-11 15:09	26.00	OK	1716	2026-09-11 15:10	26.31	OK
1717	2026-09-11 15:11	27.72	OK	1718	2026-09-11 15:12	26.45	OK
1719	2026-09-11 15:13	25.54	OK	1720	2026-09-11 15:14	24.64	OK
1721	2026-09-11 15:15	25.76	OK	1722	2026-09-11 15:16	25.82	OK
1723	2026-09-11 15:17	24.02	OK	1724	2026-09-11 15:18	25.64	OK
1725	2026-09-11 15:19	26.02	OK	1726	2026-09-11 15:20	25.50	OK
1727	2026-09-11 15:21	26.06	OK	1728	2026-09-11 15:22	26.38	OK
1729	2026-09-11 15:23	25.80	OK	1730	2026-09-11 15:24	24.97	OK
1731	2026-09-11 15:25	27.06	OK	1732	2026-09-11 15:26	25.23	OK
1733	2026-09-11 15:27	25.98	OK	1734	2026-09-11 15:28	25.24	OK
1735	2026-09-11 15:29	25.28	OK	1736	2026-09-11 15:30	27.17	OK
1737	2026-09-11 15:31	26.04	OK	1738	2026-09-11 15:32	26.84	OK
1739	2026-09-11 15:33	27.10	OK	1740	2026-09-11 15:34	26.03	OK
1741	2026-09-11 15:35	26.57	OK	1742	2026-09-11 15:36	26.02	OK
1743	2026-09-11 15:37	25.26	OK	1744	2026-09-11 15:38	26.12	OK
1745	2026-09-11 15:39	24.68	OK	1746	2026-09-11 15:40	27.40	OK
1747	2026-09-11 15:41	26.53	OK	1748	2026-09-11 15:42	26.84	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1749	2026-09-11 15:43	26.26	OK	1750	2026-09-11 15:44	24.67	OK
1751	2026-09-11 15:45	27.21	OK	1752	2026-09-11 15:46	25.04	OK
1753	2026-09-11 15:47	24.73	OK	1754	2026-09-11 15:48	25.82	OK
1755	2026-09-11 15:49	26.22	OK	1756	2026-09-11 15:50	26.22	OK
1757	2026-09-11 15:51	25.73	OK	1758	2026-09-11 15:52	24.78	OK
1759	2026-09-11 15:53	25.51	OK	1760	2026-09-11 15:54	26.97	OK
1761	2026-09-11 15:55	26.05	OK	1762	2026-09-11 15:56	26.11	OK
1763	2026-09-11 15:57	25.72	OK	1764	2026-09-11 15:58	25.41	OK
1765	2026-09-11 15:59	26.45	OK	1766	2026-09-11 16:00	27.03	OK
1767	2026-09-11 16:01	25.46	OK	1768	2026-09-11 16:02	26.00	OK
1769	2026-09-11 16:03	25.87	OK	1770	2026-09-11 16:04	26.11	OK
1771	2026-09-11 16:05	24.81	OK	1772	2026-09-11 16:06	25.79	OK
1773	2026-09-11 16:07	26.22	OK	1774	2026-09-11 16:08	24.95	OK
1775	2026-09-11 16:09	27.35	OK	1776	2026-09-11 16:10	26.08	OK
1777	2026-09-11 16:11	26.20	OK	1778	2026-09-11 16:12	25.36	OK
1779	2026-09-11 16:13	26.73	OK	1780	2026-09-11 16:14	26.99	OK
1781	2026-09-11 16:15	26.29	OK	1782	2026-09-11 16:16	26.56	OK
1783	2026-09-11 16:17	26.32	OK	1784	2026-09-11 16:18	26.20	OK
1785	2026-09-11 16:19	26.82	OK	1786	2026-09-11 16:20	26.04	OK
1787	2026-09-11 16:21	25.13	OK	1788	2026-09-11 16:22	25.63	OK
1789	2026-09-11 16:23	25.03	OK	1790	2026-09-11 16:24	27.15	OK
1791	2026-09-11 16:25	26.92	OK	1792	2026-09-11 16:26	26.23	OK
1793	2026-09-11 16:27	25.47	OK	1794	2026-09-11 16:28	25.96	OK
1795	2026-09-11 16:29	24.89	OK	1796	2026-09-11 16:30	26.39	OK
1797	2026-09-11 16:31	25.52	OK	1798	2026-09-11 16:32	26.53	OK
1799	2026-09-11 16:33	26.86	OK	1800	2026-09-11 16:34	26.29	OK
1801	2026-09-11 16:35	27.52	OK	1802	2026-09-11 16:36	25.80	OK
1803	2026-09-11 16:37	26.60	OK	1804	2026-09-11 16:38	25.85	OK
1805	2026-09-11 16:39	26.69	OK	1806	2026-09-11 16:40	26.33	OK
1807	2026-09-11 16:41	26.60	OK	1808	2026-09-11 16:42	27.59	OK
1809	2026-09-11 16:43	26.98	OK	1810	2026-09-11 16:44	27.10	OK
1811	2026-09-11 16:45	27.07	OK	1812	2026-09-11 16:46	26.98	OK
1813	2026-09-11 16:47	26.60	OK	1814	2026-09-11 16:48	26.69	OK
1815	2026-09-11 16:49	27.02	OK	1816	2026-09-11 16:50	27.18	OK
1817	2026-09-11 16:51	26.03	OK	1818	2026-09-11 16:52	25.59	OK
1819	2026-09-11 16:53	25.74	OK	1820	2026-09-11 16:54	26.43	OK
1821	2026-09-11 16:55	26.66	OK	1822	2026-09-11 16:56	26.49	OK
1823	2026-09-11 16:57	27.38	OK	1824	2026-09-11 16:58	25.44	OK
1825	2026-09-11 16:59	26.48	OK	1826	2026-09-11 17:00	27.26	OK
1827	2026-09-11 17:01	25.21	OK	1828	2026-09-11 17:02	25.06	OK
1829	2026-09-11 17:03	26.54	OK	1830	2026-09-11 17:04	26.47	OK
1831	2026-09-11 17:05	24.99	OK	1832	2026-09-11 17:06	27.40	OK
1833	2026-09-11 17:07	28.58	OK	1834	2026-09-11 17:08	27.87	OK
1835	2026-09-11 17:09	27.63	OK	1836	2026-09-11 17:10	26.68	OK
1837	2026-09-11 17:11	25.89	OK	1838	2026-09-11 17:12	26.78	OK
1839	2026-09-11 17:13	27.79	OK	1840	2026-09-11 17:14	26.26	OK
1841	2026-09-11 17:15	26.76	OK	1842	2026-09-11 17:16	25.94	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1843	2026-09-11 17:17	25.89	OK	1844	2026-09-11 17:18	27.45	OK
1845	2026-09-11 17:19	25.72	OK	1846	2026-09-11 17:20	27.17	OK
1847	2026-09-11 17:21	26.17	OK	1848	2026-09-11 17:22	26.26	OK
1849	2026-09-11 17:23	26.08	OK	1850	2026-09-11 17:24	27.00	OK
1851	2026-09-11 17:25	27.72	OK	1852	2026-09-11 17:26	27.30	OK
1853	2026-09-11 17:27	26.67	OK	1854	2026-09-11 17:28	25.12	OK
1855	2026-09-11 17:29	26.06	OK	1856	2026-09-11 17:30	26.28	OK
1857	2026-09-11 17:31	27.79	OK	1858	2026-09-11 17:32	26.06	OK
1859	2026-09-11 17:33	25.35	OK	1860	2026-09-11 17:34	27.53	OK
1861	2026-09-11 17:35	26.66	OK	1862	2026-09-11 17:36	27.80	OK
1863	2026-09-11 17:37	28.35	OK	1864	2026-09-11 17:38	26.65	OK
1865	2026-09-11 17:39	26.11	OK	1866	2026-09-11 17:40	27.72	OK
1867	2026-09-11 17:41	27.49	OK	1868	2026-09-11 17:42	27.67	OK
1869	2026-09-11 17:43	27.35	OK	1870	2026-09-11 17:44	26.85	OK
1871	2026-09-11 17:45	26.79	OK	1872	2026-09-11 17:46	25.97	OK
1873	2026-09-11 17:47	27.87	OK	1874	2026-09-11 17:48	27.97	OK
1875	2026-09-11 17:49	27.10	OK	1876	2026-09-11 17:50	26.15	OK
1877	2026-09-11 17:51	25.70	OK	1878	2026-09-11 17:52	27.42	OK
1879	2026-09-11 17:53	27.91	OK	1880	2026-09-11 17:54	27.27	OK
1881	2026-09-11 17:55	27.84	OK	1882	2026-09-11 17:56	28.68	OK
1883	2026-09-11 17:57	26.86	OK	1884	2026-09-11 17:58	27.27	OK
1885	2026-09-11 17:59	27.67	OK	1886	2026-09-11 18:00	28.39	OK
1887	2026-09-11 18:01	25.98	OK	1888	2026-09-11 18:02	27.19	OK
1889	2026-09-11 18:03	26.55	OK	1890	2026-09-11 18:04	26.27	OK
1891	2026-09-11 18:05	27.24	OK	1892	2026-09-11 18:06	28.08	OK
1893	2026-09-11 18:07	27.17	OK	1894	2026-09-11 18:08	25.91	OK
1895	2026-09-11 18:09	26.74	OK	1896	2026-09-11 18:10	28.10	OK
1897	2026-09-11 18:11	27.29	OK	1898	2026-09-11 18:12	26.79	OK
1899	2026-09-11 18:13	26.98	OK	1900	2026-09-11 18:14	28.05	OK
1901	2026-09-11 18:15	28.94	OK	1902	2026-09-11 18:16	28.09	OK
1903	2026-09-11 18:17	28.61	OK	1904	2026-09-11 18:18	27.33	OK
1905	2026-09-11 18:19	27.04	OK	1906	2026-09-11 18:20	28.48	OK
1907	2026-09-11 18:21	26.35	OK	1908	2026-09-11 18:22	29.23	OK
1909	2026-09-11 18:23	26.00	OK	1910	2026-09-11 18:24	28.21	OK
1911	2026-09-11 18:25	27.53	OK	1912	2026-09-11 18:26	28.41	OK
1913	2026-09-11 18:27	28.63	OK	1914	2026-09-11 18:28	27.59	OK
1915	2026-09-11 18:29	26.73	OK	1916	2026-09-11 18:30	27.90	OK
1917	2026-09-11 18:31	26.31	OK	1918	2026-09-11 18:32	26.99	OK
1919	2026-09-11 18:33	27.39	OK	1920	2026-09-11 18:34	25.71	OK
1921	2026-09-11 18:35	28.83	OK	1922	2026-09-11 18:36	27.70	OK
1923	2026-09-11 18:37	28.51	OK	1924	2026-09-11 18:38	27.14	OK
1925	2026-09-11 18:39	28.10	OK	1926	2026-09-11 18:40	27.51	OK
1927	2026-09-11 18:41	27.05	OK	1928	2026-09-11 18:42	26.52	OK
1929	2026-09-11 18:43	27.98	OK	1930	2026-09-11 18:44	27.90	OK
1931	2026-09-11 18:45	26.02	OK	1932	2026-09-11 18:46	26.41	OK
1933	2026-09-11 18:47	26.78	OK	1934	2026-09-11 18:48	27.99	OK
1935	2026-09-11 18:49	27.63	OK	1936	2026-09-11 18:50	28.62	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
1937	2026-09-11 18:51	28.34	OK	1938	2026-09-11 18:52	27.23	OK
1939	2026-09-11 18:53	27.90	OK	1940	2026-09-11 18:54	28.07	OK
1941	2026-09-11 18:55	27.69	OK	1942	2026-09-11 18:56	26.49	OK
1943	2026-09-11 18:57	28.79	OK	1944	2026-09-11 18:58	28.07	OK
1945	2026-09-11 18:59	26.65	OK	1946	2026-09-11 19:00	26.76	OK
1947	2026-09-11 19:01	27.44	OK	1948	2026-09-11 19:02	27.56	OK
1949	2026-09-11 19:03	28.13	OK	1950	2026-09-11 19:04	27.71	OK
1951	2026-09-11 19:05	27.85	OK	1952	2026-09-11 19:06	26.83	OK
1953	2026-09-11 19:07	27.66	OK	1954	2026-09-11 19:08	28.00	OK
1955	2026-09-11 19:09	27.96	OK	1956	2026-09-11 19:10	27.11	OK
1957	2026-09-11 19:11	27.17	OK	1958	2026-09-11 19:12	27.51	OK
1959	2026-09-11 19:13	28.51	OK	1960	2026-09-11 19:14	28.25	OK
1961	2026-09-11 19:15	28.27	OK	1962	2026-09-11 19:16	27.63	OK
1963	2026-09-11 19:17	26.35	OK	1964	2026-09-11 19:18	27.87	OK
1965	2026-09-11 19:19	28.80	OK	1966	2026-09-11 19:20	27.21	OK
1967	2026-09-11 19:21	27.83	OK	1968	2026-09-11 19:22	28.21	OK
1969	2026-09-11 19:23	29.55	OK	1970	2026-09-11 19:24	28.12	OK
1971	2026-09-11 19:25	29.16	OK	1972	2026-09-11 19:26	28.31	OK
1973	2026-09-11 19:27	26.88	OK	1974	2026-09-11 19:28	27.29	OK
1975	2026-09-11 19:29	27.40	OK	1976	2026-09-11 19:30	27.75	OK
1977	2026-09-11 19:31	28.46	OK	1978	2026-09-11 19:32	27.21	OK
1979	2026-09-11 19:33	26.26	OK	1980	2026-09-11 19:34	27.50	OK
1981	2026-09-11 19:35	27.22	OK	1982	2026-09-11 19:36	26.83	OK
1983	2026-09-11 19:37	28.28	OK	1984	2026-09-11 19:38	28.69	OK
1985	2026-09-11 19:39	27.97	OK	1986	2026-09-11 19:40	28.30	OK
1987	2026-09-11 19:41	28.14	OK	1988	2026-09-11 19:42	27.91	OK
1989	2026-09-11 19:43	28.81	OK	1990	2026-09-11 19:44	27.86	OK
1991	2026-09-11 19:45	29.04	OK	1992	2026-09-11 19:46	28.81	OK
1993	2026-09-11 19:47	27.43	OK	1994	2026-09-11 19:48	27.50	OK
1995	2026-09-11 19:49	27.82	OK	1996	2026-09-11 19:50	28.59	OK
1997	2026-09-11 19:51	29.12	OK	1998	2026-09-11 19:52	29.43	OK
1999	2026-09-11 19:53	29.08	OK	2000	2026-09-11 19:54	26.38	OK
2001	2026-09-11 19:55	29.56	OK	2002	2026-09-11 19:56	27.36	OK
2003	2026-09-11 19:57	27.44	OK	2004	2026-09-11 19:58	28.00	OK
2005	2026-09-11 19:59	27.24	OK	2006	2026-09-11 20:00	27.64	OK
2007	2026-09-11 20:01	28.23	OK	2008	2026-09-11 20:02	28.08	OK
2009	2026-09-11 20:03	28.67	OK	2010	2026-09-11 20:04	27.92	OK
2011	2026-09-11 20:05	27.47	OK	2012	2026-09-11 20:06	27.91	OK
2013	2026-09-11 20:07	27.21	OK	2014	2026-09-11 20:08	29.83	OK
2015	2026-09-11 20:09	27.65	OK	2016	2026-09-11 20:10	29.05	OK
2017	2026-09-11 20:11	29.09	OK	2018	2026-09-11 20:12	27.62	OK
2019	2026-09-11 20:13	28.51	OK	2020	2026-09-11 20:14	30.00	OK
2021	2026-09-11 20:15	28.94	OK	2022	2026-09-11 20:16	28.85	OK
2023	2026-09-11 20:17	29.21	OK	2024	2026-09-11 20:18	28.40	OK
2025	2026-09-11 20:19	30.02	OK	2026	2026-09-11 20:20	28.76	OK
2027	2026-09-11 20:21	28.71	OK	2028	2026-09-11 20:22	28.24	OK
2029	2026-09-11 20:23	29.01	OK	2030	2026-09-11 20:24	29.28	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2031	2026-09-11 20:25	28.35	OK	2032	2026-09-11 20:26	28.22	OK
2033	2026-09-11 20:27	28.32	OK	2034	2026-09-11 20:28	27.42	OK
2035	2026-09-11 20:29	28.57	OK	2036	2026-09-11 20:30	28.41	OK
2037	2026-09-11 20:31	28.45	OK	2038	2026-09-11 20:32	27.84	OK
2039	2026-09-11 20:33	28.93	OK	2040	2026-09-11 20:34	28.33	OK
2041	2026-09-11 20:35	28.47	OK	2042	2026-09-11 20:36	30.21	OK
2043	2026-09-11 20:37	29.23	OK	2044	2026-09-11 20:38	30.00	OK
2045	2026-09-11 20:39	28.95	OK	2046	2026-09-11 20:40	28.12	OK
2047	2026-09-11 20:41	28.30	OK	2048	2026-09-11 20:42	27.52	OK
2049	2026-09-11 20:43	27.82	OK	2050	2026-09-11 20:44	29.22	OK
2051	2026-09-11 20:45	28.41	OK	2052	2026-09-11 20:46	28.63	OK
2053	2026-09-11 20:47	28.90	OK	2054	2026-09-11 20:48	28.43	OK
2055	2026-09-11 20:49	28.62	OK	2056	2026-09-11 20:50	27.82	OK
2057	2026-09-11 20:51	28.89	OK	2058	2026-09-11 20:52	28.51	OK
2059	2026-09-11 20:53	29.85	OK	2060	2026-09-11 20:54	28.45	OK
2061	2026-09-11 20:55	28.93	OK	2062	2026-09-11 20:56	29.35	OK
2063	2026-09-11 20:57	29.14	OK	2064	2026-09-11 20:58	29.87	OK
2065	2026-09-11 20:59	28.80	OK	2066	2026-09-11 21:00	28.68	OK
2067	2026-09-11 21:01	28.84	OK	2068	2026-09-11 21:02	27.47	OK
2069	2026-09-11 21:03	28.68	OK	2070	2026-09-11 21:04	29.72	OK
2071	2026-09-11 21:05	28.00	OK	2072	2026-09-11 21:06	27.89	OK
2073	2026-09-11 21:07	29.61	OK	2074	2026-09-11 21:08	28.47	OK
2075	2026-09-11 21:09	27.88	OK	2076	2026-09-11 21:10	30.77	OK
2077	2026-09-11 21:11	29.69	OK	2078	2026-09-11 21:12	27.71	OK
2079	2026-09-11 21:13	29.58	OK	2080	2026-09-11 21:14	29.17	OK
2081	2026-09-11 21:15	29.47	OK	2082	2026-09-11 21:16	28.40	OK
2083	2026-09-11 21:17	27.75	OK	2084	2026-09-11 21:18	27.85	OK
2085	2026-09-11 21:19	28.50	OK	2086	2026-09-11 21:20	28.26	OK
2087	2026-09-11 21:21	28.74	OK	2088	2026-09-11 21:22	29.42	OK
2089	2026-09-11 21:23	29.59	OK	2090	2026-09-11 21:24	28.51	OK
2091	2026-09-11 21:25	27.61	OK	2092	2026-09-11 21:26	29.40	OK
2093	2026-09-11 21:27	27.88	OK	2094	2026-09-11 21:28	28.02	OK
2095	2026-09-11 21:29	29.14	OK	2096	2026-09-11 21:30	28.09	OK
2097	2026-09-11 21:31	30.50	OK	2098	2026-09-11 21:32	29.58	OK
2099	2026-09-11 21:33	28.68	OK	2100	2026-09-11 21:34	29.66	OK
2101	2026-09-11 21:35	28.93	OK	2102	2026-09-11 21:36	29.07	OK
2103	2026-09-11 21:37	30.00	OK	2104	2026-09-11 21:38	30.19	OK
2105	2026-09-11 21:39	29.99	OK	2106	2026-09-11 21:40	30.50	OK
2107	2026-09-11 21:41	28.17	OK	2108	2026-09-11 21:42	29.16	OK
2109	2026-09-11 21:43	28.80	OK	2110	2026-09-11 21:44	27.83	OK
2111	2026-09-11 21:45	30.04	OK	2112	2026-09-11 21:46	30.25	OK
2113	2026-09-11 21:47	30.61	OK	2114	2026-09-11 21:48	29.72	OK
2115	2026-09-11 21:49	28.96	OK	2116	2026-09-11 21:50	29.77	OK
2117	2026-09-11 21:51	29.08	OK	2118	2026-09-11 21:52	28.24	OK
2119	2026-09-11 21:53	28.95	OK	2120	2026-09-11 21:54	29.08	OK
2121	2026-09-11 21:55	30.35	OK	2122	2026-09-11 21:56	29.54	OK
2123	2026-09-11 21:57	28.59	OK	2124	2026-09-11 21:58	29.73	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2125	2026-09-11 21:59	30.58	OK	2126	2026-09-11 22:00	29.78	OK
2127	2026-09-11 22:01	28.27	OK	2128	2026-09-11 22:02	29.75	OK
2129	2026-09-11 22:03	29.27	OK	2130	2026-09-11 22:04	29.10	OK
2131	2026-09-11 22:05	29.13	OK	2132	2026-09-11 22:06	28.17	OK
2133	2026-09-11 22:07	29.24	OK	2134	2026-09-11 22:08	28.20	OK
2135	2026-09-11 22:09	30.09	OK	2136	2026-09-11 22:10	30.60	OK
2137	2026-09-11 22:11	28.46	OK	2138	2026-09-11 22:12	30.68	OK
2139	2026-09-11 22:13	31.04	OK	2140	2026-09-11 22:14	30.13	OK
2141	2026-09-11 22:15	28.81	OK	2142	2026-09-11 22:16	29.29	OK
2143	2026-09-11 22:17	30.06	OK	2144	2026-09-11 22:18	29.45	OK
2145	2026-09-11 22:19	30.45	OK	2146	2026-09-11 22:20	29.82	OK
2147	2026-09-11 22:21	30.31	OK	2148	2026-09-11 22:22	28.84	OK
2149	2026-09-11 22:23	28.90	OK	2150	2026-09-11 22:24	30.33	OK
2151	2026-09-11 22:25	30.43	OK	2152	2026-09-11 22:26	28.41	OK
2153	2026-09-11 22:27	30.19	OK	2154	2026-09-11 22:28	29.75	OK
2155	2026-09-11 22:29	29.58	OK	2156	2026-09-11 22:30	29.93	OK
2157	2026-09-11 22:31	29.36	OK	2158	2026-09-11 22:32	29.87	OK
2159	2026-09-11 22:33	30.53	OK	2160	2026-09-11 22:34	30.42	OK
2161	2026-09-11 22:35	29.16	OK	2162	2026-09-11 22:36	28.30	OK
2163	2026-09-11 22:37	29.45	OK	2164	2026-09-11 22:38	29.42	OK
2165	2026-09-11 22:39	30.31	OK	2166	2026-09-11 22:40	29.22	OK
2167	2026-09-11 22:41	28.88	OK	2168	2026-09-11 22:42	30.72	OK
2169	2026-09-11 22:43	31.38	OK	2170	2026-09-11 22:44	30.96	OK
2171	2026-09-11 22:45	28.53	OK	2172	2026-09-11 22:46	28.60	OK
2173	2026-09-11 22:47	28.56	OK	2174	2026-09-11 22:48	28.21	OK
2175	2026-09-11 22:49	29.47	OK	2176	2026-09-11 22:50	30.19	OK
2177	2026-09-11 22:51	29.68	OK	2178	2026-09-11 22:52	28.58	OK
2179	2026-09-11 22:53	31.19	OK	2180	2026-09-11 22:54	28.74	OK
2181	2026-09-11 22:55	29.02	OK	2182	2026-09-11 22:56	31.23	OK
2183	2026-09-11 22:57	30.46	OK	2184	2026-09-11 22:58	31.44	OK
2185	2026-09-11 22:59	29.88	OK	2186	2026-09-11 23:00	28.98	OK
2187	2026-09-11 23:01	29.70	OK	2188	2026-09-11 23:02	28.92	OK
2189	2026-09-11 23:03	30.90	OK	2190	2026-09-11 23:04	30.00	OK
2191	2026-09-11 23:05	29.47	OK	2192	2026-09-11 23:06	29.91	OK
2193	2026-09-11 23:07	30.21	OK	2194	2026-09-11 23:08	29.75	OK
2195	2026-09-11 23:09	30.08	OK	2196	2026-09-11 23:10	28.91	OK
2197	2026-09-11 23:11	29.80	OK	2198	2026-09-11 23:12	30.52	OK
2199	2026-09-11 23:13	30.08	OK	2200	2026-09-11 23:14	31.05	OK
2201	2026-09-11 23:15	29.93	OK	2202	2026-09-11 23:16	28.69	OK
2203	2026-09-11 23:17	31.33	OK	2204	2026-09-11 23:18	28.19	OK
2205	2026-09-11 23:19	30.35	OK	2206	2026-09-11 23:20	29.30	OK
2207	2026-09-11 23:21	29.42	OK	2208	2026-09-11 23:22	30.70	OK
2209	2026-09-11 23:23	28.76	OK	2210	2026-09-11 23:24	30.32	OK
2211	2026-09-11 23:25	29.95	OK	2212	2026-09-11 23:26	29.77	OK
2213	2026-09-11 23:27	29.10	OK	2214	2026-09-11 23:28	29.17	OK
2215	2026-09-11 23:29	30.62	OK	2216	2026-09-11 23:30	30.10	OK
2217	2026-09-11 23:31	30.44	OK	2218	2026-09-11 23:32	29.41	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2219	2026-09-11 23:33	30.61	OK	2220	2026-09-11 23:34	31.22	OK
2221	2026-09-11 23:35	28.53	OK	2222	2026-09-11 23:36	30.26	OK
2223	2026-09-11 23:37	31.38	OK	2224	2026-09-11 23:38	29.16	OK
2225	2026-09-11 23:39	31.42	OK	2226	2026-09-11 23:40	30.73	OK
2227	2026-09-11 23:41	30.31	OK	2228	2026-09-11 23:42	30.65	OK
2229	2026-09-11 23:43	29.78	OK	2230	2026-09-11 23:44	29.02	OK
2231	2026-09-11 23:45	31.69	OK	2232	2026-09-11 23:46	30.89	OK
2233	2026-09-11 23:47	29.68	OK	2234	2026-09-11 23:48	30.44	OK
2235	2026-09-11 23:49	31.25	OK	2236	2026-09-11 23:50	31.40	OK
2237	2026-09-11 23:51	29.90	OK	2238	2026-09-11 23:52	30.68	OK
2239	2026-09-11 23:53	29.38	OK	2240	2026-09-11 23:54	30.22	OK
2241	2026-09-11 23:55	31.10	OK	2242	2026-09-11 23:56	30.46	OK
2243	2026-09-11 23:57	30.94	OK	2244	2026-09-11 23:58	29.25	OK
2245	2026-09-11 23:59	29.48	OK	2246	2026-09-12 00:00	29.23	OK
2247	2026-09-12 00:01	28.92	OK	2248	2026-09-12 00:02	30.46	OK
2249	2026-09-12 00:03	28.94	OK	2250	2026-09-12 00:04	29.06	OK
2251	2026-09-12 00:05	29.27	OK	2252	2026-09-12 00:06	29.34	OK
2253	2026-09-12 00:07	30.68	OK	2254	2026-09-12 00:08	30.66	OK
2255	2026-09-12 00:09	30.39	OK	2256	2026-09-12 00:10	30.23	OK
2257	2026-09-12 00:11	30.30	OK	2258	2026-09-12 00:12	28.28	OK
2259	2026-09-12 00:13	29.37	OK	2260	2026-09-12 00:14	29.57	OK
2261	2026-09-12 00:15	30.06	OK	2262	2026-09-12 00:16	29.73	OK
2263	2026-09-12 00:17	29.97	OK	2264	2026-09-12 00:18	29.68	OK
2265	2026-09-12 00:19	30.61	OK	2266	2026-09-12 00:20	29.89	OK
2267	2026-09-12 00:21	30.09	OK	2268	2026-09-12 00:22	30.89	OK
2269	2026-09-12 00:23	31.69	OK	2270	2026-09-12 00:24	30.46	OK
2271	2026-09-12 00:25	30.99	OK	2272	2026-09-12 00:26	29.77	OK
2273	2026-09-12 00:27	29.67	OK	2274	2026-09-12 00:28	30.19	OK
2275	2026-09-12 00:29	29.69	OK	2276	2026-09-12 00:30	29.94	OK
2277	2026-09-12 00:31	29.09	OK	2278	2026-09-12 00:32	29.56	OK
2279	2026-09-12 00:33	30.16	OK	2280	2026-09-12 00:34	30.25	OK
2281	2026-09-12 00:35	30.10	OK	2282	2026-09-12 00:36	31.03	OK
2283	2026-09-12 00:37	30.03	OK	2284	2026-09-12 00:38	29.36	OK
2285	2026-09-12 00:39	30.24	OK	2286	2026-09-12 00:40	29.13	OK
2287	2026-09-12 00:41	31.53	OK	2288	2026-09-12 00:42	30.99	OK
2289	2026-09-12 00:43	29.40	OK	2290	2026-09-12 00:44	29.80	OK
2291	2026-09-12 00:45	30.26	OK	2292	2026-09-12 00:46	29.51	OK
2293	2026-09-12 00:47	30.37	OK	2294	2026-09-12 00:48	30.25	OK
2295	2026-09-12 00:49	30.48	OK	2296	2026-09-12 00:50	31.43	OK
2297	2026-09-12 00:51	29.10	OK	2298	2026-09-12 00:52	30.25	OK
2299	2026-09-12 00:53	30.83	OK	2300	2026-09-12 00:54	31.17	OK
2301	2026-09-12 00:55	29.59	OK	2302	2026-09-12 00:56	30.33	OK
2303	2026-09-12 00:57	29.99	OK	2304	2026-09-12 00:58	29.44	OK
2305	2026-09-12 00:59	29.91	OK	2306	2026-09-12 01:00	30.83	OK
2307	2026-09-12 01:01	29.24	OK	2308	2026-09-12 01:02	30.35	OK
2309	2026-09-12 01:03	30.65	OK	2310	2026-09-12 01:04	29.88	OK
2311	2026-09-12 01:05	31.16	OK	2312	2026-09-12 01:06	29.60	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2313	2026-09-12 01:07	29.92	OK	2314	2026-09-12 01:08	30.44	OK
2315	2026-09-12 01:09	30.96	OK	2316	2026-09-12 01:10	30.28	OK
2317	2026-09-12 01:11	29.94	OK	2318	2026-09-12 01:12	30.23	OK
2319	2026-09-12 01:13	30.44	OK	2320	2026-09-12 01:14	29.59	OK
2321	2026-09-12 01:15	31.33	OK	2322	2026-09-12 01:16	30.03	OK
2323	2026-09-12 01:17	29.03	OK	2324	2026-09-12 01:18	29.70	OK
2325	2026-09-12 01:19	30.14	OK	2326	2026-09-12 01:20	31.38	OK
2327	2026-09-12 01:21	30.74	OK	2328	2026-09-12 01:22	30.42	OK
2329	2026-09-12 01:23	30.18	OK	2330	2026-09-12 01:24	30.23	OK
2331	2026-09-12 01:25	29.81	OK	2332	2026-09-12 01:26	29.35	OK
2333	2026-09-12 01:27	31.18	OK	2334	2026-09-12 01:28	29.76	OK
2335	2026-09-12 01:29	30.34	OK	2336	2026-09-12 01:30	30.96	OK
2337	2026-09-12 01:31	29.15	OK	2338	2026-09-12 01:32	30.30	OK
2339	2026-09-12 01:33	30.16	OK	2340	2026-09-12 01:34	30.54	OK
2341	2026-09-12 01:35	30.52	OK	2342	2026-09-12 01:36	31.31	OK
2343	2026-09-12 01:37	31.08	OK	2344	2026-09-12 01:38	29.73	OK
2345	2026-09-12 01:39	29.40	OK	2346	2026-09-12 01:40	29.25	OK
2347	2026-09-12 01:41	30.32	OK	2348	2026-09-12 01:42	30.35	OK
2349	2026-09-12 01:43	29.56	OK	2350	2026-09-12 01:44	30.24	OK
2351	2026-09-12 01:45	30.74	OK	2352	2026-09-12 01:46	29.88	OK
2353	2026-09-12 01:47	29.85	OK	2354	2026-09-12 01:48	30.26	OK
2355	2026-09-12 01:49	30.03	OK	2356	2026-09-12 01:50	29.62	OK
2357	2026-09-12 01:51	29.81	OK	2358	2026-09-12 01:52	30.88	OK
2359	2026-09-12 01:53	30.06	OK	2360	2026-09-12 01:54	30.67	OK
2361	2026-09-12 01:55	30.18	OK	2362	2026-09-12 01:56	29.10	OK
2363	2026-09-12 01:57	29.50	OK	2364	2026-09-12 01:58	30.46	OK
2365	2026-09-12 01:59	30.07	OK	2366	2026-09-12 02:00	29.69	OK
2367	2026-09-12 02:01	30.07	OK	2368	2026-09-12 02:02	30.01	OK
2369	2026-09-12 02:03	30.71	OK	2370	2026-09-12 02:04	31.57	OK
2371	2026-09-12 02:05	29.59	OK	2372	2026-09-12 02:06	30.87	OK
2373	2026-09-12 02:07	30.19	OK	2374	2026-09-12 02:08	30.85	OK
2375	2026-09-12 02:09	31.30	OK	2376	2026-09-12 02:10	29.91	OK
2377	2026-09-12 02:11	31.03	OK	2378	2026-09-12 02:12	30.53	OK
2379	2026-09-12 02:13	29.82	OK	2380	2026-09-12 02:14	30.04	OK
2381	2026-09-12 02:15	29.53	OK	2382	2026-09-12 02:16	30.06	OK
2383	2026-09-12 02:17	31.46	OK	2384	2026-09-12 02:18	29.21	OK
2385	2026-09-12 02:19	29.88	OK	2386	2026-09-12 02:20	30.04	OK
2387	2026-09-12 02:21	31.62	OK	2388	2026-09-12 02:22	30.66	OK
2389	2026-09-12 02:23	30.52	OK	2390	2026-09-12 02:24	30.70	OK
2391	2026-09-12 02:25	30.73	OK	2392	2026-09-12 02:26	30.92	OK
2393	2026-09-12 02:27	30.59	OK	2394	2026-09-12 02:28	30.14	OK
2395	2026-09-12 02:29	30.03	OK	2396	2026-09-12 02:30	30.59	OK
2397	2026-09-12 02:31	31.30	OK	2398	2026-09-12 02:32	30.28	OK
2399	2026-09-12 02:33	29.43	OK	2400	2026-09-12 02:34	31.13	OK
2401	2026-09-12 02:35	30.31	OK	2402	2026-09-12 02:36	30.99	OK
2403	2026-09-12 02:37	30.69	OK	2404	2026-09-12 02:38	30.59	OK
2405	2026-09-12 02:39	30.61	OK	2406	2026-09-12 02:40	29.71	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2407	2026-09-12 02:41	30.12	OK	2408	2026-09-12 02:42	29.90	OK
2409	2026-09-12 02:43	29.33	OK	2410	2026-09-12 02:44	30.41	OK
2411	2026-09-12 02:45	30.15	OK	2412	2026-09-12 02:46	30.35	OK
2413	2026-09-12 02:47	31.60	OK	2414	2026-09-12 02:48	29.97	OK
2415	2026-09-12 02:49	29.62	OK	2416	2026-09-12 02:50	31.07	OK
2417	2026-09-12 02:51	29.82	OK	2418	2026-09-12 02:52	30.92	OK
2419	2026-09-12 02:53	30.84	OK	2420	2026-09-12 02:54	31.00	OK
2421	2026-09-12 02:55	30.43	OK	2422	2026-09-12 02:56	29.31	OK
2423	2026-09-12 02:57	31.42	OK	2424	2026-09-12 02:58	28.53	OK
2425	2026-09-12 02:59	29.38	OK	2426	2026-09-12 03:00	29.49	OK
2427	2026-09-12 03:01	29.29	OK	2428	2026-09-12 03:02	30.33	OK
2429	2026-09-12 03:03	31.12	OK	2430	2026-09-12 03:04	30.41	OK
2431	2026-09-12 03:05	28.76	OK	2432	2026-09-12 03:06	29.19	OK
2433	2026-09-12 03:07	30.76	OK	2434	2026-09-12 03:08	31.03	OK
2435	2026-09-12 03:09	28.62	OK	2436	2026-09-12 03:10	30.37	OK
2437	2026-09-12 03:11	29.65	OK	2438	2026-09-12 03:12	31.28	OK
2439	2026-09-12 03:13	31.09	OK	2440	2026-09-12 03:14	30.56	OK
2441	2026-09-12 03:15	30.13	OK	2442	2026-09-12 03:16	30.05	OK
2443	2026-09-12 03:17	29.10	OK	2444	2026-09-12 03:18	31.42	OK
2445	2026-09-12 03:19	28.99	OK	2446	2026-09-12 03:20	31.34	OK
2447	2026-09-12 03:21	30.29	OK	2448	2026-09-12 03:22	29.59	OK
2449	2026-09-12 03:23	29.56	OK	2450	2026-09-12 03:24	29.67	OK
2451	2026-09-12 03:25	29.10	OK	2452	2026-09-12 03:26	30.26	OK
2453	2026-09-12 03:27	30.65	OK	2454	2026-09-12 03:28	30.33	OK
2455	2026-09-12 03:29	30.92	OK	2456	2026-09-12 03:30	31.12	OK
2457	2026-09-12 03:31	29.84	OK	2458	2026-09-12 03:32	30.57	OK
2459	2026-09-12 03:33	29.27	OK	2460	2026-09-12 03:34	28.84	OK
2461	2026-09-12 03:35	29.86	OK	2462	2026-09-12 03:36	29.08	OK
2463	2026-09-12 03:37	29.30	OK	2464	2026-09-12 03:38	29.24	OK
2465	2026-09-12 03:39	31.12	OK	2466	2026-09-12 03:40	30.38	OK
2467	2026-09-12 03:41	30.04	OK	2468	2026-09-12 03:42	27.87	OK
2469	2026-09-12 03:43	31.41	OK	2470	2026-09-12 03:44	29.09	OK
2471	2026-09-12 03:45	29.29	OK	2472	2026-09-12 03:46	29.64	OK
2473	2026-09-12 03:47	29.02	OK	2474	2026-09-12 03:48	29.66	OK
2475	2026-09-12 03:49	30.28	OK	2476	2026-09-12 03:50	29.03	OK
2477	2026-09-12 03:51	29.13	OK	2478	2026-09-12 03:52	30.47	OK
2479	2026-09-12 03:53	29.64	OK	2480	2026-09-12 03:54	29.66	OK
2481	2026-09-12 03:55	30.61	OK	2482	2026-09-12 03:56	30.57	OK
2483	2026-09-12 03:57	30.33	OK	2484	2026-09-12 03:58	28.82	OK
2485	2026-09-12 03:59	29.92	OK	2486	2026-09-12 04:00	30.69	OK
2487	2026-09-12 04:01	28.93	OK	2488	2026-09-12 04:02	30.11	OK
2489	2026-09-12 04:03	29.41	OK	2490	2026-09-12 04:04	30.35	OK
2491	2026-09-12 04:05	29.87	OK	2492	2026-09-12 04:06	29.25	OK
2493	2026-09-12 04:07	29.26	OK	2494	2026-09-12 04:08	30.94	OK
2495	2026-09-12 04:09	30.20	OK	2496	2026-09-12 04:10	28.78	OK
2497	2026-09-12 04:11	29.69	OK	2498	2026-09-12 04:12	28.09	OK
2499	2026-09-12 04:13	30.44	OK	2500	2026-09-12 04:14	29.89	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2501	2026-09-12 04:15	29.79	OK	2502	2026-09-12 04:16	30.04	OK
2503	2026-09-12 04:17	30.37	OK	2504	2026-09-12 04:18	29.47	OK
2505	2026-09-12 04:19	30.75	OK	2506	2026-09-12 04:20	28.94	OK
2507	2026-09-12 04:21	31.27	OK	2508	2026-09-12 04:22	29.26	OK
2509	2026-09-12 04:23	29.03	OK	2510	2026-09-12 04:24	30.16	OK
2511	2026-09-12 04:25	28.58	OK	2512	2026-09-12 04:26	28.94	OK
2513	2026-09-12 04:27	29.98	OK	2514	2026-09-12 04:28	29.72	OK
2515	2026-09-12 04:29	29.45	OK	2516	2026-09-12 04:30	30.15	OK
2517	2026-09-12 04:31	29.14	OK	2518	2026-09-12 04:32	29.77	OK
2519	2026-09-12 04:33	30.71	OK	2520	2026-09-12 04:34	30.50	OK
2521	2026-09-12 04:35	28.65	OK	2522	2026-09-12 04:36	29.83	OK
2523	2026-09-12 04:37	29.14	OK	2524	2026-09-12 04:38	29.45	OK
2525	2026-09-12 04:39	29.52	OK	2526	2026-09-12 04:40	29.00	OK
2527	2026-09-12 04:41	29.90	OK	2528	2026-09-12 04:42	28.81	OK
2529	2026-09-12 04:43	30.34	OK	2530	2026-09-12 04:44	29.61	OK
2531	2026-09-12 04:45	28.93	OK	2532	2026-09-12 04:46	29.77	OK
2533	2026-09-12 04:47	30.33	OK	2534	2026-09-12 04:48	28.63	OK
2535	2026-09-12 04:49	30.16	OK	2536	2026-09-12 04:50	29.33	OK
2537	2026-09-12 04:51	29.68	OK	2538	2026-09-12 04:52	29.16	OK
2539	2026-09-12 04:53	28.63	OK	2540	2026-09-12 04:54	28.13	OK
2541	2026-09-12 04:55	29.43	OK	2542	2026-09-12 04:56	29.21	OK
2543	2026-09-12 04:57	29.07	OK	2544	2026-09-12 04:58	28.81	OK
2545	2026-09-12 04:59	28.50	OK	2546	2026-09-12 05:00	27.56	OK
2547	2026-09-12 05:01	29.15	OK	2548	2026-09-12 05:02	30.12	OK
2549	2026-09-12 05:03	28.73	OK	2550	2026-09-12 05:04	28.32	OK
2551	2026-09-12 05:05	29.67	OK	2552	2026-09-12 05:06	28.96	OK
2553	2026-09-12 05:07	29.08	OK	2554	2026-09-12 05:08	28.93	OK
2555	2026-09-12 05:09	29.96	OK	2556	2026-09-12 05:10	29.22	OK
2557	2026-09-12 05:11	29.82	OK	2558	2026-09-12 05:12	28.66	OK
2559	2026-09-12 05:13	28.98	OK	2560	2026-09-12 05:14	29.49	OK
2561	2026-09-12 05:15	29.03	OK	2562	2026-09-12 05:16	30.11	OK
2563	2026-09-12 05:17	28.49	OK	2564	2026-09-12 05:18	29.25	OK
2565	2026-09-12 05:19	29.09	OK	2566	2026-09-12 05:20	28.79	OK
2567	2026-09-12 05:21	30.27	OK	2568	2026-09-12 05:22	28.33	OK
2569	2026-09-12 05:23	28.19	OK	2570	2026-09-12 05:24	28.87	OK
2571	2026-09-12 05:25	29.19	OK	2572	2026-09-12 05:26	29.72	OK
2573	2026-09-12 05:27	29.90	OK	2574	2026-09-12 05:28	28.83	OK
2575	2026-09-12 05:29	29.01	OK	2576	2026-09-12 05:30	28.85	OK
2577	2026-09-12 05:31	28.47	OK	2578	2026-09-12 05:32	28.90	OK
2579	2026-09-12 05:33	29.13	OK	2580	2026-09-12 05:34	27.94	OK
2581	2026-09-12 05:35	28.51	OK	2582	2026-09-12 05:36	29.71	OK
2583	2026-09-12 05:37	28.25	OK	2584	2026-09-12 05:38	28.79	OK
2585	2026-09-12 05:39	28.83	OK	2586	2026-09-12 05:40	28.66	OK
2587	2026-09-12 05:41	29.76	OK	2588	2026-09-12 05:42	29.09	OK
2589	2026-09-12 05:43	28.44	OK	2590	2026-09-12 05:44	28.76	OK
2591	2026-09-12 05:45	28.23	OK	2592	2026-09-12 05:46	28.76	OK
2593	2026-09-12 05:47	29.76	OK	2594	2026-09-12 05:48	29.80	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2595	2026-09-12 05:49	29.62	OK	2596	2026-09-12 05:50	29.55	OK
2597	2026-09-12 05:51	28.85	OK	2598	2026-09-12 05:52	27.90	OK
2599	2026-09-12 05:53	28.41	OK	2600	2026-09-12 05:54	26.83	OK
2601	2026-09-12 05:55	29.97	OK	2602	2026-09-12 05:56	28.67	OK
2603	2026-09-12 05:57	27.88	OK	2604	2026-09-12 05:58	28.84	OK
2605	2026-09-12 05:59	27.66	OK	2606	2026-09-12 06:00	28.99	OK
2607	2026-09-12 06:01	28.72	OK	2608	2026-09-12 06:02	28.30	OK
2609	2026-09-12 06:03	28.42	OK	2610	2026-09-12 06:04	28.20	OK
2611	2026-09-12 06:05	27.32	OK	2612	2026-09-12 06:06	27.65	OK
2613	2026-09-12 06:07	28.72	OK	2614	2026-09-12 06:08	29.01	OK
2615	2026-09-12 06:09	27.68	OK	2616	2026-09-12 06:10	27.81	OK
2617	2026-09-12 06:11	29.49	OK	2618	2026-09-12 06:12	29.21	OK
2619	2026-09-12 06:13	29.09	OK	2620	2026-09-12 06:14	28.71	OK
2621	2026-09-12 06:15	29.23	OK	2622	2026-09-12 06:16	27.26	OK
2623	2026-09-12 06:17	28.29	OK	2624	2026-09-12 06:18	27.55	OK
2625	2026-09-12 06:19	27.19	OK	2626	2026-09-12 06:20	28.83	OK
2627	2026-09-12 06:21	29.14	OK	2628	2026-09-12 06:22	28.62	OK
2629	2026-09-12 06:23	28.63	OK	2630	2026-09-12 06:24	28.27	OK
2631	2026-09-12 06:25	28.77	OK	2632	2026-09-12 06:26	28.95	OK
2633	2026-09-12 06:27	27.02	OK	2634	2026-09-12 06:28	27.98	OK
2635	2026-09-12 06:29	28.81	OK	2636	2026-09-12 06:30	29.30	OK
2637	2026-09-12 06:31	27.80	OK	2638	2026-09-12 06:32	27.75	OK
2639	2026-09-12 06:33	27.35	OK	2640	2026-09-12 06:34	29.43	OK
2641	2026-09-12 06:35	29.81	OK	2642	2026-09-12 06:36	27.86	OK
2643	2026-09-12 06:37	28.29	OK	2644	2026-09-12 06:38	29.08	OK
2645	2026-09-12 06:39	28.94	OK	2646	2026-09-12 06:40	28.13	OK
2647	2026-09-12 06:41	28.16	OK	2648	2026-09-12 06:42	29.62	OK
2649	2026-09-12 06:43	27.63	OK	2650	2026-09-12 06:44	28.41	OK
2651	2026-09-12 06:45	28.61	OK	2652	2026-09-12 06:46	28.81	OK
2653	2026-09-12 06:47	28.76	OK	2654	2026-09-12 06:48	28.06	OK
2655	2026-09-12 06:49	27.10	OK	2656	2026-09-12 06:50	29.03	OK
2657	2026-09-12 06:51	28.64	OK	2658	2026-09-12 06:52	29.19	OK
2659	2026-09-12 06:53	28.15	OK	2660	2026-09-12 06:54	28.35	OK
2661	2026-09-12 06:55	27.69	OK	2662	2026-09-12 06:56	28.70	OK
2663	2026-09-12 06:57	29.35	OK	2664	2026-09-12 06:58	28.72	OK
2665	2026-09-12 06:59	28.55	OK	2666	2026-09-12 07:00	28.59	OK
2667	2026-09-12 07:01	28.47	OK	2668	2026-09-12 07:02	27.84	OK
2669	2026-09-12 07:03	27.97	OK	2670	2026-09-12 07:04	27.71	OK
2671	2026-09-12 07:05	27.66	OK	2672	2026-09-12 07:06	29.19	OK
2673	2026-09-12 07:07	28.00	OK	2674	2026-09-12 07:08	28.80	OK
2675	2026-09-12 07:09	27.19	OK	2676	2026-09-12 07:10	26.44	OK
2677	2026-09-12 07:11	28.65	OK	2678	2026-09-12 07:12	27.23	OK
2679	2026-09-12 07:13	28.40	OK	2680	2026-09-12 07:14	28.38	OK
2681	2026-09-12 07:15	28.54	OK	2682	2026-09-12 07:16	27.51	OK
2683	2026-09-12 07:17	28.05	OK	2684	2026-09-12 07:18	26.47	OK
2685	2026-09-12 07:19	27.35	OK	2686	2026-09-12 07:20	27.84	OK
2687	2026-09-12 07:21	28.31	OK	2688	2026-09-12 07:22	27.82	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2689	2026-09-12 07:23	27.46	OK	2690	2026-09-12 07:24	28.42	OK
2691	2026-09-12 07:25	27.85	OK	2692	2026-09-12 07:26	28.72	OK
2693	2026-09-12 07:27	27.89	OK	2694	2026-09-12 07:28	27.42	OK
2695	2026-09-12 07:29	27.17	OK	2696	2026-09-12 07:30	27.94	OK
2697	2026-09-12 07:31	28.54	OK	2698	2026-09-12 07:32	28.88	OK
2699	2026-09-12 07:33	27.49	OK	2700	2026-09-12 07:34	28.22	OK
2701	2026-09-12 07:35	27.51	OK	2702	2026-09-12 07:36	29.07	OK
2703	2026-09-12 07:37	27.63	OK	2704	2026-09-12 07:38	29.38	OK
2705	2026-09-12 07:39	28.30	OK	2706	2026-09-12 07:40	27.03	OK
2707	2026-09-12 07:41	28.67	OK	2708	2026-09-12 07:42	27.57	OK
2709	2026-09-12 07:43	27.48	OK	2710	2026-09-12 07:44	26.93	OK
2711	2026-09-12 07:45	28.91	OK	2712	2026-09-12 07:46	27.52	OK
2713	2026-09-12 07:47	27.19	OK	2714	2026-09-12 07:48	28.06	OK
2715	2026-09-12 07:49	26.66	OK	2716	2026-09-12 07:50	28.75	OK
2717	2026-09-12 07:51	27.67	OK	2718	2026-09-12 07:52	28.61	OK
2719	2026-09-12 07:53	27.53	OK	2720	2026-09-12 07:54	26.96	OK
2721	2026-09-12 07:55	27.48	OK	2722	2026-09-12 07:56	28.49	OK
2723	2026-09-12 07:57	27.59	OK	2724	2026-09-12 07:58	26.82	OK
2725	2026-09-12 07:59	26.56	OK	2726	2026-09-12 08:00	26.31	OK
2727	2026-09-12 08:01	26.98	OK	2728	2026-09-12 08:02	27.04	OK
2729	2026-09-12 08:03	28.34	OK	2730	2026-09-12 08:04	28.06	OK
2731	2026-09-12 08:05	27.19	OK	2732	2026-09-12 08:06	26.12	OK
2733	2026-09-12 08:07	26.73	OK	2734	2026-09-12 08:08	28.79	OK
2735	2026-09-12 08:09	27.44	OK	2736	2026-09-12 08:10	27.86	OK
2737	2026-09-12 08:11	28.05	OK	2738	2026-09-12 08:12	26.54	OK
2739	2026-09-12 08:13	28.30	OK	2740	2026-09-12 08:14	27.56	OK
2741	2026-09-12 08:15	27.62	OK	2742	2026-09-12 08:16	27.95	OK
2743	2026-09-12 08:17	27.58	OK	2744	2026-09-12 08:18	26.68	OK
2745	2026-09-12 08:19	28.64	OK	2746	2026-09-12 08:20	27.59	OK
2747	2026-09-12 08:21	27.17	OK	2748	2026-09-12 08:22	26.84	OK
2749	2026-09-12 08:23	25.69	OK	2750	2026-09-12 08:24	27.28	OK
2751	2026-09-12 08:25	27.55	OK	2752	2026-09-12 08:26	26.48	OK
2753	2026-09-12 08:27	26.69	OK	2754	2026-09-12 08:28	28.16	OK
2755	2026-09-12 08:29	27.88	OK	2756	2026-09-12 08:30	27.04	OK
2757	2026-09-12 08:31	26.78	OK	2758	2026-09-12 08:32	27.75	OK
2759	2026-09-12 08:33	28.22	OK	2760	2026-09-12 08:34	26.05	OK
2761	2026-09-12 08:35	26.31	OK	2762	2026-09-12 08:36	27.73	OK
2763	2026-09-12 08:37	26.07	OK	2764	2026-09-12 08:38	25.86	OK
2765	2026-09-12 08:39	28.49	OK	2766	2026-09-12 08:40	27.96	OK
2767	2026-09-12 08:41	29.02	OK	2768	2026-09-12 08:42	27.97	OK
2769	2026-09-12 08:43	27.41	OK	2770	2026-09-12 08:44	28.45	OK
2771	2026-09-12 08:45	26.48	OK	2772	2026-09-12 08:46	26.32	OK
2773	2026-09-12 08:47	26.59	OK	2774	2026-09-12 08:48	26.14	OK
2775	2026-09-12 08:49	27.51	OK	2776	2026-09-12 08:50	28.11	OK
2777	2026-09-12 08:51	26.01	OK	2778	2026-09-12 08:52	27.42	OK
2779	2026-09-12 08:53	27.23	OK	2780	2026-09-12 08:54	27.35	OK
2781	2026-09-12 08:55	26.12	OK	2782	2026-09-12 08:56	26.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2783	2026-09-12 08:57	27.02	OK	2784	2026-09-12 08:58	27.44	OK
2785	2026-09-12 08:59	26.75	OK	2786	2026-09-12 09:00	27.50	OK
2787	2026-09-12 09:01	27.73	OK	2788	2026-09-12 09:02	28.20	OK
2789	2026-09-12 09:03	27.87	OK	2790	2026-09-12 09:04	27.24	OK
2791	2026-09-12 09:05	28.53	OK	2792	2026-09-12 09:06	25.80	OK
2793	2026-09-12 09:07	27.79	OK	2794	2026-09-12 09:08	25.88	OK
2795	2026-09-12 09:09	27.62	OK	2796	2026-09-12 09:10	27.50	OK
2797	2026-09-12 09:11	27.84	OK	2798	2026-09-12 09:12	26.93	OK
2799	2026-09-12 09:13	27.98	OK	2800	2026-09-12 09:14	27.94	OK
2801	2026-09-12 09:15	26.91	OK	2802	2026-09-12 09:16	27.05	OK
2803	2026-09-12 09:17	27.55	OK	2804	2026-09-12 09:18	27.24	OK
2805	2026-09-12 09:19	26.92	OK	2806	2026-09-12 09:20	26.97	OK
2807	2026-09-12 09:21	27.53	OK	2808	2026-09-12 09:22	27.40	OK
2809	2026-09-12 09:23	27.65	OK	2810	2026-09-12 09:24	26.95	OK
2811	2026-09-12 09:25	26.67	OK	2812	2026-09-12 09:26	25.48	OK
2813	2026-09-12 09:27	26.23	OK	2814	2026-09-12 09:28	25.40	OK
2815	2026-09-12 09:29	26.56	OK	2816	2026-09-12 09:30	27.69	OK
2817	2026-09-12 09:31	28.24	OK	2818	2026-09-12 09:32	26.31	OK
2819	2026-09-12 09:33	27.08	OK	2820	2026-09-12 09:34	26.56	OK
2821	2026-09-12 09:35	27.46	OK	2822	2026-09-12 09:36	28.04	OK
2823	2026-09-12 09:37	27.58	OK	2824	2026-09-12 09:38	25.21	OK
2825	2026-09-12 09:39	26.06	OK	2826	2026-09-12 09:40	26.57	OK
2827	2026-09-12 09:41	27.68	OK	2828	2026-09-12 09:42	28.78	OK
2829	2026-09-12 09:43	27.32	OK	2830	2026-09-12 09:44	25.77	OK
2831	2026-09-12 09:45	27.02	OK	2832	2026-09-12 09:46	26.65	OK
2833	2026-09-12 09:47	24.93	OK	2834	2026-09-12 09:48	28.33	OK
2835	2026-09-12 09:49	26.13	OK	2836	2026-09-12 09:50	27.20	OK
2837	2026-09-12 09:51	26.85	OK	2838	2026-09-12 09:52	26.63	OK
2839	2026-09-12 09:53	26.45	OK	2840	2026-09-12 09:54	27.69	OK
2841	2026-09-12 09:55	27.76	OK	2842	2026-09-12 09:56	25.79	OK
2843	2026-09-12 09:57	27.19	OK	2844	2026-09-12 09:58	26.87	OK
2845	2026-09-12 09:59	28.57	OK	2846	2026-09-12 10:00	27.36	OK
2847	2026-09-12 10:01	27.98	OK	2848	2026-09-12 10:02	27.11	OK
2849	2026-09-12 10:03	27.73	OK	2850	2026-09-12 10:04	26.85	OK
2851	2026-09-12 10:05	27.44	OK	2852	2026-09-12 10:06	26.21	OK
2853	2026-09-12 10:07	25.98	OK	2854	2026-09-12 10:08	26.88	OK
2855	2026-09-12 10:09	25.37	OK	2856	2026-09-12 10:10	26.07	OK
2857	2026-09-12 10:11	26.30	OK	2858	2026-09-12 10:12	26.27	OK
2859	2026-09-12 10:13	26.44	OK	2860	2026-09-12 10:14	25.62	OK
2861	2026-09-12 10:15	26.02	OK	2862	2026-09-12 10:16	27.27	OK
2863	2026-09-12 10:17	26.71	OK	2864	2026-09-12 10:18	25.89	OK
2865	2026-09-12 10:19	25.79	OK	2866	2026-09-12 10:20	26.43	OK
2867	2026-09-12 10:21	28.01	OK	2868	2026-09-12 10:22	26.10	OK
2869	2026-09-12 10:23	25.41	OK	2870	2026-09-12 10:24	26.34	OK
2871	2026-09-12 10:25	27.13	OK	2872	2026-09-12 10:26	28.05	OK
2873	2026-09-12 10:27	26.38	OK	2874	2026-09-12 10:28	25.97	OK
2875	2026-09-12 10:29	27.89	OK	2876	2026-09-12 10:30	26.72	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2877	2026-09-12 10:31	26.47	OK	2878	2026-09-12 10:32	27.83	OK
2879	2026-09-12 10:33	25.47	OK	2880	2026-09-12 10:34	26.07	OK
2881	2026-09-12 10:35	25.40	OK	2882	2026-09-12 10:36	27.53	OK
2883	2026-09-12 10:37	27.38	OK	2884	2026-09-12 10:38	27.20	OK
2885	2026-09-12 10:39	25.19	OK	2886	2026-09-12 10:40	27.15	OK
2887	2026-09-12 10:41	25.96	OK	2888	2026-09-12 10:42	26.43	OK
2889	2026-09-12 10:43	26.68	OK	2890	2026-09-12 10:44	26.54	OK
2891	2026-09-12 10:45	26.15	OK	2892	2026-09-12 10:46	26.16	OK
2893	2026-09-12 10:47	25.74	OK	2894	2026-09-12 10:48	26.34	OK
2895	2026-09-12 10:49	25.66	OK	2896	2026-09-12 10:50	26.48	OK
2897	2026-09-12 10:51	25.28	OK	2898	2026-09-12 10:52	26.35	OK
2899	2026-09-12 10:53	27.33	OK	2900	2026-09-12 10:54	26.87	OK
2901	2026-09-12 10:55	24.47	OK	2902	2026-09-12 10:56	27.59	OK
2903	2026-09-12 10:57	25.06	OK	2904	2026-09-12 10:58	25.21	OK
2905	2026-09-12 10:59	25.00	OK	2906	2026-09-12 11:00	24.89	OK
2907	2026-09-12 11:01	25.15	OK	2908	2026-09-12 11:02	27.10	OK
2909	2026-09-12 11:03	27.17	OK	2910	2026-09-12 11:04	26.47	OK
2911	2026-09-12 11:05	27.54	OK	2912	2026-09-12 11:06	25.53	OK
2913	2026-09-12 11:07	25.54	OK	2914	2026-09-12 11:08	26.07	OK
2915	2026-09-12 11:09	26.96	OK	2916	2026-09-12 11:10	25.39	OK
2917	2026-09-12 11:11	26.31	OK	2918	2026-09-12 11:12	26.33	OK
2919	2026-09-12 11:13	24.84	OK	2920	2026-09-12 11:14	25.52	OK
2921	2026-09-12 11:15	26.26	OK	2922	2026-09-12 11:16	25.55	OK
2923	2026-09-12 11:17	25.26	OK	2924	2026-09-12 11:18	25.55	OK
2925	2026-09-12 11:19	26.46	OK	2926	2026-09-12 11:20	27.03	OK
2927	2026-09-12 11:21	26.39	OK	2928	2026-09-12 11:22	27.34	OK
2929	2026-09-12 11:23	25.29	OK	2930	2026-09-12 11:24	25.29	OK
2931	2026-09-12 11:25	25.85	OK	2932	2026-09-12 11:26	24.98	OK
2933	2026-09-12 11:27	25.53	OK	2934	2026-09-12 11:28	26.24	OK
2935	2026-09-12 11:29	26.30	OK	2936	2026-09-12 11:30	26.56	OK
2937	2026-09-12 11:31	26.03	OK	2938	2026-09-12 11:32	24.87	OK
2939	2026-09-12 11:33	25.41	OK	2940	2026-09-12 11:34	25.81	OK
2941	2026-09-12 11:35	26.43	OK	2942	2026-09-12 11:36	25.34	OK
2943	2026-09-12 11:37	25.60	OK	2944	2026-09-12 11:38	24.66	OK
2945	2026-09-12 11:39	27.56	OK	2946	2026-09-12 11:40	24.49	OK
2947	2026-09-12 11:41	26.03	OK	2948	2026-09-12 11:42	25.18	OK
2949	2026-09-12 11:43	24.90	OK	2950	2026-09-12 11:44	26.05	OK
2951	2026-09-12 11:45	25.96	OK	2952	2026-09-12 11:46	24.75	OK
2953	2026-09-12 11:47	25.27	OK	2954	2026-09-12 11:48	26.69	OK
2955	2026-09-12 11:49	24.89	OK	2956	2026-09-12 11:50	26.48	OK
2957	2026-09-12 11:51	25.37	OK	2958	2026-09-12 11:52	26.33	OK
2959	2026-09-12 11:53	25.52	OK	2960	2026-09-12 11:54	25.24	OK
2961	2026-09-12 11:55	24.82	OK	2962	2026-09-12 11:56	26.23	OK
2963	2026-09-12 11:57	26.07	OK	2964	2026-09-12 11:58	27.33	OK
2965	2026-09-12 11:59	25.94	OK	2966	2026-09-12 12:00	26.32	OK
2967	2026-09-12 12:01	26.46	OK	2968	2026-09-12 12:02	25.34	OK
2969	2026-09-12 12:03	25.45	OK	2970	2026-09-12 12:04	25.75	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
2971	2026-09-12 12:05	25.34	OK	2972	2026-09-12 12:06	24.79	OK
2973	2026-09-12 12:07	26.18	OK	2974	2026-09-12 12:08	25.60	OK
2975	2026-09-12 12:09	25.05	OK	2976	2026-09-12 12:10	24.39	OK
2977	2026-09-12 12:11	24.79	OK	2978	2026-09-12 12:12	24.76	OK
2979	2026-09-12 12:13	25.33	OK	2980	2026-09-12 12:14	25.70	OK
2981	2026-09-12 12:15	24.84	OK	2982	2026-09-12 12:16	26.64	OK
2983	2026-09-12 12:17	25.79	OK	2984	2026-09-12 12:18	26.41	OK
2985	2026-09-12 12:19	26.60	OK	2986	2026-09-12 12:20	25.84	OK
2987	2026-09-12 12:21	24.87	OK	2988	2026-09-12 12:22	25.87	OK
2989	2026-09-12 12:23	25.08	OK	2990	2026-09-12 12:24	26.08	OK
2991	2026-09-12 12:25	24.91	OK	2992	2026-09-12 12:26	25.22	OK
2993	2026-09-12 12:27	25.58	OK	2994	2026-09-12 12:28	25.04	OK
2995	2026-09-12 12:29	26.22	OK	2996	2026-09-12 12:30	26.18	OK
2997	2026-09-12 12:31	25.73	OK	2998	2026-09-12 12:32	25.87	OK
2999	2026-09-12 12:33	26.07	OK	3000	2026-09-12 12:34	25.93	OK
3001	2026-09-12 12:35	24.84	OK	3002	2026-09-12 12:36	24.48	OK
3003	2026-09-12 12:37	25.77	OK	3004	2026-09-12 12:38	26.20	OK
3005	2026-09-12 12:39	27.10	OK	3006	2026-09-12 12:40	26.87	OK
3007	2026-09-12 12:41	26.53	OK	3008	2026-09-12 12:42	24.77	OK
3009	2026-09-12 12:43	25.56	OK	3010	2026-09-12 12:44	27.31	OK
3011	2026-09-12 12:45	24.72	OK	3012	2026-09-12 12:46	26.18	OK
3013	2026-09-12 12:47	24.49	OK	3014	2026-09-12 12:48	25.47	OK
3015	2026-09-12 12:49	25.33	OK	3016	2026-09-12 12:50	25.55	OK
3017	2026-09-12 12:51	26.83	OK	3018	2026-09-12 12:52	24.98	OK
3019	2026-09-12 12:53	25.01	OK	3020	2026-09-12 12:54	24.68	OK
3021	2026-09-12 12:55	25.58	OK	3022	2026-09-12 12:56	25.68	OK
3023	2026-09-12 12:57	26.19	OK	3024	2026-09-12 12:58	24.85	OK
3025	2026-09-12 12:59	25.44	OK	3026	2026-09-12 13:00	25.63	OK
3027	2026-09-12 13:01	25.12	OK	3028	2026-09-12 13:02	24.65	OK
3029	2026-09-12 13:03	25.09	OK	3030	2026-09-12 13:04	24.68	OK
3031	2026-09-12 13:05	24.94	OK	3032	2026-09-12 13:06	25.48	OK
3033	2026-09-12 13:07	26.57	OK	3034	2026-09-12 13:08	26.30	OK
3035	2026-09-12 13:09	24.84	OK	3036	2026-09-12 13:10	27.04	OK
3037	2026-09-12 13:11	26.93	OK	3038	2026-09-12 13:12	25.22	OK
3039	2026-09-12 13:13	25.05	OK	3040	2026-09-12 13:14	24.83	OK
3041	2026-09-12 13:15	24.40	OK	3042	2026-09-12 13:16	24.63	OK
3043	2026-09-12 13:17	25.20	OK	3044	2026-09-12 13:18	25.89	OK
3045	2026-09-12 13:19	25.43	OK	3046	2026-09-12 13:20	25.48	OK
3047	2026-09-12 13:21	25.31	OK	3048	2026-09-12 13:22	25.65	OK
3049	2026-09-12 13:23	25.57	OK	3050	2026-09-12 13:24	25.58	OK
3051	2026-09-12 13:25	25.45	OK	3052	2026-09-12 13:26	26.73	OK
3053	2026-09-12 13:27	25.06	OK	3054	2026-09-12 13:28	24.26	OK
3055	2026-09-12 13:29	25.54	OK	3056	2026-09-12 13:30	27.27	OK
3057	2026-09-12 13:31	26.09	OK	3058	2026-09-12 13:32	26.05	OK
3059	2026-09-12 13:33	26.18	OK	3060	2026-09-12 13:34	25.32	OK
3061	2026-09-12 13:35	24.23	OK	3062	2026-09-12 13:36	24.01	OK
3063	2026-09-12 13:37	26.35	OK	3064	2026-09-12 13:38	25.87	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3065	2026-09-12 13:39	25.23	OK	3066	2026-09-12 13:40	26.79	OK
3067	2026-09-12 13:41	25.17	OK	3068	2026-09-12 13:42	26.65	OK
3069	2026-09-12 13:43	23.90	OK	3070	2026-09-12 13:44	25.42	OK
3071	2026-09-12 13:45	26.15	OK	3072	2026-09-12 13:46	24.46	OK
3073	2026-09-12 13:47	27.49	OK	3074	2026-09-12 13:48	25.70	OK
3075	2026-09-12 13:49	26.74	OK	3076	2026-09-12 13:50	25.45	OK
3077	2026-09-12 13:51	27.13	OK	3078	2026-09-12 13:52	25.96	OK
3079	2026-09-12 13:53	26.17	OK	3080	2026-09-12 13:54	24.79	OK
3081	2026-09-12 13:55	25.99	OK	3082	2026-09-12 13:56	26.98	OK
3083	2026-09-12 13:57	26.75	OK	3084	2026-09-12 13:58	26.07	OK
3085	2026-09-12 13:59	25.01	OK	3086	2026-09-12 14:00	25.50	OK
3087	2026-09-12 14:01	24.88	OK	3088	2026-09-12 14:02	26.71	OK
3089	2026-09-12 14:03	26.29	OK	3090	2026-09-12 14:04	24.53	OK
3091	2026-09-12 14:05	26.40	OK	3092	2026-09-12 14:06	24.94	OK
3093	2026-09-12 14:07	25.86	OK	3094	2026-09-12 14:08	25.48	OK
3095	2026-09-12 14:09	26.18	OK	3096	2026-09-12 14:10	25.73	OK
3097	2026-09-12 14:11	27.35	OK	3098	2026-09-12 14:12	25.41	OK
3099	2026-09-12 14:13	25.35	OK	3100	2026-09-12 14:14	25.20	OK
3101	2026-09-12 14:15	27.74	OK	3102	2026-09-12 14:16	25.69	OK
3103	2026-09-12 14:17	26.59	OK	3104	2026-09-12 14:18	27.58	OK
3105	2026-09-12 14:19	26.61	OK	3106	2026-09-12 14:20	25.17	OK
3107	2026-09-12 14:21	24.98	OK	3108	2026-09-12 14:22	24.52	OK
3109	2026-09-12 14:23	25.54	OK	3110	2026-09-12 14:24	25.99	OK
3111	2026-09-12 14:25	25.97	OK	3112	2026-09-12 14:26	26.77	OK
3113	2026-09-12 14:27	25.34	OK	3114	2026-09-12 14:28	26.04	OK
3115	2026-09-12 14:29	26.11	OK	3116	2026-09-12 14:30	25.14	OK
3117	2026-09-12 14:31	26.03	OK	3118	2026-09-12 14:32	26.26	OK
3119	2026-09-12 14:33	24.65	OK	3120	2026-09-12 14:34	25.14	OK
3121	2026-09-12 14:35	24.30	OK	3122	2026-09-12 14:36	24.99	OK
3123	2026-09-12 14:37	24.52	OK	3124	2026-09-12 14:38	25.51	OK
3125	2026-09-12 14:39	25.82	OK	3126	2026-09-12 14:40	25.96	OK
3127	2026-09-12 14:41	26.18	OK	3128	2026-09-12 14:42	26.02	OK
3129	2026-09-12 14:43	26.02	OK	3130	2026-09-12 14:44	25.40	OK
3131	2026-09-12 14:45	24.98	OK	3132	2026-09-12 14:46	26.44	OK
3133	2026-09-12 14:47	25.77	OK	3134	2026-09-12 14:48	25.40	OK
3135	2026-09-12 14:49	25.39	OK	3136	2026-09-12 14:50	26.11	OK
3137	2026-09-12 14:51	24.91	OK	3138	2026-09-12 14:52	26.87	OK
3139	2026-09-12 14:53	26.44	OK	3140	2026-09-12 14:54	25.30	OK
3141	2026-09-12 14:55	26.21	OK	3142	2026-09-12 14:56	25.69	OK
3143	2026-09-12 14:57	25.93	OK	3144	2026-09-12 14:58	26.16	OK
3145	2026-09-12 14:59	24.88	OK	3146	2026-09-12 15:00	25.44	OK
3147	2026-09-12 15:01	26.83	OK	3148	2026-09-12 15:02	26.42	OK
3149	2026-09-12 15:03	25.01	OK	3150	2026-09-12 15:04	27.41	OK
3151	2026-09-12 15:05	26.12	OK	3152	2026-09-12 15:06	26.81	OK
3153	2026-09-12 15:07	25.73	OK	3154	2026-09-12 15:08	26.95	OK
3155	2026-09-12 15:09	25.15	OK	3156	2026-09-12 15:10	26.18	OK
3157	2026-09-12 15:11	25.78	OK	3158	2026-09-12 15:12	26.10	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3159	2026-09-12 15:13	26.46	OK	3160	2026-09-12 15:14	26.85	OK
3161	2026-09-12 15:15	24.93	OK	3162	2026-09-12 15:16	26.86	OK
3163	2026-09-12 15:17	26.19	OK	3164	2026-09-12 15:18	25.70	OK
3165	2026-09-12 15:19	25.31	OK	3166	2026-09-12 15:20	27.14	OK
3167	2026-09-12 15:21	26.30	OK	3168	2026-09-12 15:22	25.08	OK
3169	2026-09-12 15:23	27.05	OK	3170	2026-09-12 15:24	25.52	OK
3171	2026-09-12 15:25	27.03	OK	3172	2026-09-12 15:26	25.44	OK
3173	2026-09-12 15:27	27.30	OK	3174	2026-09-12 15:28	25.38	OK
3175	2026-09-12 15:29	25.16	OK	3176	2026-09-12 15:30	26.62	OK
3177	2026-09-12 15:31	25.31	OK	3178	2026-09-12 15:32	26.60	OK
3179	2026-09-12 15:33	24.91	OK	3180	2026-09-12 15:34	25.57	OK
3181	2026-09-12 15:35	26.24	OK	3182	2026-09-12 15:36	25.03	OK
3183	2026-09-12 15:37	26.63	OK	3184	2026-09-12 15:38	26.62	OK
3185	2026-09-12 15:39	25.37	OK	3186	2026-09-12 15:40	26.32	OK
3187	2026-09-12 15:41	25.46	OK	3188	2026-09-12 15:42	26.01	OK
3189	2026-09-12 15:43	25.76	OK	3190	2026-09-12 15:44	27.62	OK
3191	2026-09-12 15:45	25.67	OK	3192	2026-09-12 15:46	24.56	OK
3193	2026-09-12 15:47	25.52	OK	3194	2026-09-12 15:48	25.54	OK
3195	2026-09-12 15:49	26.90	OK	3196	2026-09-12 15:50	26.98	OK
3197	2026-09-12 15:51	25.73	OK	3198	2026-09-12 15:52	25.14	OK
3199	2026-09-12 15:53	25.37	OK	3200	2026-09-12 15:54	26.21	OK
3201	2026-09-12 15:55	24.93	OK	3202	2026-09-12 15:56	27.42	OK
3203	2026-09-12 15:57	26.03	OK	3204	2026-09-12 15:58	24.71	OK
3205	2026-09-12 15:59	25.75	OK	3206	2026-09-12 16:00	26.11	OK
3207	2026-09-12 16:01	24.96	OK	3208	2026-09-12 16:02	25.67	OK
3209	2026-09-12 16:03	27.39	OK	3210	2026-09-12 16:04	26.13	OK
3211	2026-09-12 16:05	27.36	OK	3212	2026-09-12 16:06	26.13	OK
3213	2026-09-12 16:07	25.67	OK	3214	2026-09-12 16:08	25.67	OK
3215	2026-09-12 16:09	25.71	OK	3216	2026-09-12 16:10	25.55	OK
3217	2026-09-12 16:11	26.94	OK	3218	2026-09-12 16:12	27.10	OK
3219	2026-09-12 16:13	26.45	OK	3220	2026-09-12 16:14	26.02	OK
3221	2026-09-12 16:15	27.64	OK	3222	2026-09-12 16:16	25.93	OK
3223	2026-09-12 16:17	25.78	OK	3224	2026-09-12 16:18	26.92	OK
3225	2026-09-12 16:19	26.61	OK	3226	2026-09-12 16:20	26.10	OK
3227	2026-09-12 16:21	27.74	OK	3228	2026-09-12 16:22	26.60	OK
3229	2026-09-12 16:23	25.50	OK	3230	2026-09-12 16:24	26.51	OK
3231	2026-09-12 16:25	26.11	OK	3232	2026-09-12 16:26	27.47	OK
3233	2026-09-12 16:27	26.79	OK	3234	2026-09-12 16:28	25.77	OK
3235	2026-09-12 16:29	25.44	OK	3236	2026-09-12 16:30	27.85	OK
3237	2026-09-12 16:31	26.57	OK	3238	2026-09-12 16:32	26.54	OK
3239	2026-09-12 16:33	24.97	OK	3240	2026-09-12 16:34	26.63	OK
3241	2026-09-12 16:35	26.49	OK	3242	2026-09-12 16:36	25.61	OK
3243	2026-09-12 16:37	26.03	OK	3244	2026-09-12 16:38	25.65	OK
3245	2026-09-12 16:39	25.13	OK	3246	2026-09-12 16:40	26.41	OK
3247	2026-09-12 16:41	27.73	OK	3248	2026-09-12 16:42	26.69	OK
3249	2026-09-12 16:43	27.11	OK	3250	2026-09-12 16:44	26.83	OK
3251	2026-09-12 16:45	25.99	OK	3252	2026-09-12 16:46	27.24	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3253	2026-09-12 16:47	24.67	OK	3254	2026-09-12 16:48	26.29	OK
3255	2026-09-12 16:49	26.52	OK	3256	2026-09-12 16:50	26.91	OK
3257	2026-09-12 16:51	27.26	OK	3258	2026-09-12 16:52	27.00	OK
3259	2026-09-12 16:53	24.88	OK	3260	2026-09-12 16:54	26.20	OK
3261	2026-09-12 16:55	25.54	OK	3262	2026-09-12 16:56	26.38	OK
3263	2026-09-12 16:57	26.69	OK	3264	2026-09-12 16:58	27.79	OK
3265	2026-09-12 16:59	26.77	OK	3266	2026-09-12 17:00	26.50	OK
3267	2026-09-12 17:01	28.00	OK	3268	2026-09-12 17:02	26.89	OK
3269	2026-09-12 17:03	27.88	OK	3270	2026-09-12 17:04	26.43	OK
3271	2026-09-12 17:05	26.59	OK	3272	2026-09-12 17:06	27.78	OK
3273	2026-09-12 17:07	25.37	OK	3274	2026-09-12 17:08	28.65	OK
3275	2026-09-12 17:09	26.68	OK	3276	2026-09-12 17:10	27.56	OK
3277	2026-09-12 17:11	26.38	OK	3278	2026-09-12 17:12	26.06	OK
3279	2026-09-12 17:13	25.79	OK	3280	2026-09-12 17:14	26.65	OK
3281	2026-09-12 17:15	27.76	OK	3282	2026-09-12 17:16	25.74	OK
3283	2026-09-12 17:17	26.14	OK	3284	2026-09-12 17:18	26.64	OK
3285	2026-09-12 17:19	26.35	OK	3286	2026-09-12 17:20	27.12	OK
3287	2026-09-12 17:21	28.02	OK	3288	2026-09-12 17:22	26.60	OK
3289	2026-09-12 17:23	27.31	OK	3290	2026-09-12 17:24	26.83	OK
3291	2026-09-12 17:25	26.42	OK	3292	2026-09-12 17:26	27.26	OK
3293	2026-09-12 17:27	27.81	OK	3294	2026-09-12 17:28	27.12	OK
3295	2026-09-12 17:29	25.51	OK	3296	2026-09-12 17:30	26.44	OK
3297	2026-09-12 17:31	26.21	OK	3298	2026-09-12 17:32	26.98	OK
3299	2026-09-12 17:33	26.27	OK	3300	2026-09-12 17:34	26.60	OK
3301	2026-09-12 17:35	25.40	OK	3302	2026-09-12 17:36	26.27	OK
3303	2026-09-12 17:37	25.99	OK	3304	2026-09-12 17:38	25.67	OK
3305	2026-09-12 17:39	26.42	OK	3306	2026-09-12 17:40	26.29	OK
3307	2026-09-12 17:41	27.20	OK	3308	2026-09-12 17:42	25.47	OK
3309	2026-09-12 17:43	26.30	OK	3310	2026-09-12 17:44	26.19	OK
3311	2026-09-12 17:45	27.40	OK	3312	2026-09-12 17:46	27.24	OK
3313	2026-09-12 17:47	26.22	OK	3314	2026-09-12 17:48	28.99	OK
3315	2026-09-12 17:49	26.42	OK	3316	2026-09-12 17:50	27.04	OK
3317	2026-09-12 17:51	26.88	OK	3318	2026-09-12 17:52	26.40	OK
3319	2026-09-12 17:53	27.04	OK	3320	2026-09-12 17:54	26.47	OK
3321	2026-09-12 17:55	28.41	OK	3322	2026-09-12 17:56	26.99	OK
3323	2026-09-12 17:57	27.24	OK	3324	2026-09-12 17:58	28.91	OK
3325	2026-09-12 17:59	27.38	OK	3326	2026-09-12 18:00	27.74	OK
3327	2026-09-12 18:01	27.38	OK	3328	2026-09-12 18:02	27.15	OK
3329	2026-09-12 18:03	27.64	OK	3330	2026-09-12 18:04	27.20	OK
3331	2026-09-12 18:05	27.36	OK	3332	2026-09-12 18:06	28.61	OK
3333	2026-09-12 18:07	25.48	OK	3334	2026-09-12 18:08	28.20	OK
3335	2026-09-12 18:09	25.86	OK	3336	2026-09-12 18:10	27.73	OK
3337	2026-09-12 18:11	26.03	OK	3338	2026-09-12 18:12	28.32	OK
3339	2026-09-12 18:13	26.77	OK	3340	2026-09-12 18:14	27.68	OK
3341	2026-09-12 18:15	26.23	OK	3342	2026-09-12 18:16	28.30	OK
3343	2026-09-12 18:17	26.29	OK	3344	2026-09-12 18:18	27.11	OK
3345	2026-09-12 18:19	26.64	OK	3346	2026-09-12 18:20	28.21	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3347	2026-09-12 18:21	27.04	OK	3348	2026-09-12 18:22	27.95	OK
3349	2026-09-12 18:23	26.83	OK	3350	2026-09-12 18:24	26.68	OK
3351	2026-09-12 18:25	26.73	OK	3352	2026-09-12 18:26	29.07	OK
3353	2026-09-12 18:27	28.78	OK	3354	2026-09-12 18:28	25.75	OK
3355	2026-09-12 18:29	28.11	OK	3356	2026-09-12 18:30	27.34	OK
3357	2026-09-12 18:31	26.65	OK	3358	2026-09-12 18:32	26.88	OK
3359	2026-09-12 18:33	28.18	OK	3360	2026-09-12 18:34	27.56	OK
3361	2026-09-12 18:35	27.57	OK	3362	2026-09-12 18:36	26.53	OK
3363	2026-09-12 18:37	27.61	OK	3364	2026-09-12 18:38	27.32	OK
3365	2026-09-12 18:39	26.52	OK	3366	2026-09-12 18:40	27.93	OK
3367	2026-09-12 18:41	26.48	OK	3368	2026-09-12 18:42	27.98	OK
3369	2026-09-12 18:43	26.70	OK	3370	2026-09-12 18:44	27.76	OK
3371	2026-09-12 18:45	27.74	OK	3372	2026-09-12 18:46	26.99	OK
3373	2026-09-12 18:47	27.49	OK	3374	2026-09-12 18:48	28.74	OK
3375	2026-09-12 18:49	27.49	OK	3376	2026-09-12 18:50	26.70	OK
3377	2026-09-12 18:51	27.67	OK	3378	2026-09-12 18:52	27.38	OK
3379	2026-09-12 18:53	26.89	OK	3380	2026-09-12 18:54	26.90	OK
3381	2026-09-12 18:55	29.15	OK	3382	2026-09-12 18:56	27.98	OK
3383	2026-09-12 18:57	28.01	OK	3384	2026-09-12 18:58	28.08	OK
3385	2026-09-12 18:59	28.69	OK	3386	2026-09-12 19:00	27.89	OK
3387	2026-09-12 19:01	27.57	OK	3388	2026-09-12 19:02	26.91	OK
3389	2026-09-12 19:03	27.23	OK	3390	2026-09-12 19:04	28.73	OK
3391	2026-09-12 19:05	29.34	OK	3392	2026-09-12 19:06	27.53	OK
3393	2026-09-12 19:07	29.22	OK	3394	2026-09-12 19:08	28.00	OK
3395	2026-09-12 19:09	28.31	OK	3396	2026-09-12 19:10	27.71	OK
3397	2026-09-12 19:11	28.93	OK	3398	2026-09-12 19:12	27.55	OK
3399	2026-09-12 19:13	27.68	OK	3400	2026-09-12 19:14	28.42	OK
3401	2026-09-12 19:15	26.50	OK	3402	2026-09-12 19:16	28.28	OK
3403	2026-09-12 19:17	27.02	OK	3404	2026-09-12 19:18	27.00	OK
3405	2026-09-12 19:19	26.91	OK	3406	2026-09-12 19:20	26.73	OK
3407	2026-09-12 19:21	28.02	OK	3408	2026-09-12 19:22	26.70	OK
3409	2026-09-12 19:23	28.65	OK	3410	2026-09-12 19:24	27.35	OK
3411	2026-09-12 19:25	29.20	OK	3412	2026-09-12 19:26	28.26	OK
3413	2026-09-12 19:27	27.65	OK	3414	2026-09-12 19:28	28.50	OK
3415	2026-09-12 19:29	27.00	OK	3416	2026-09-12 19:30	27.51	OK
3417	2026-09-12 19:31	28.98	OK	3418	2026-09-12 19:32	28.23	OK
3419	2026-09-12 19:33	27.51	OK	3420	2026-09-12 19:34	28.81	OK
3421	2026-09-12 19:35	27.47	OK	3422	2026-09-12 19:36	27.44	OK
3423	2026-09-12 19:37	27.27	OK	3424	2026-09-12 19:38	28.40	OK
3425	2026-09-12 19:39	26.85	OK	3426	2026-09-12 19:40	27.65	OK
3427	2026-09-12 19:41	29.03	OK	3428	2026-09-12 19:42	28.99	OK
3429	2026-09-12 19:43	29.79	OK	3430	2026-09-12 19:44	27.33	OK
3431	2026-09-12 19:45	27.54	OK	3432	2026-09-12 19:46	28.31	OK
3433	2026-09-12 19:47	27.96	OK	3434	2026-09-12 19:48	27.35	OK
3435	2026-09-12 19:49	28.07	OK	3436	2026-09-12 19:50	28.27	OK
3437	2026-09-12 19:51	28.58	OK	3438	2026-09-12 19:52	29.93	OK
3439	2026-09-12 19:53	28.68	OK	3440	2026-09-12 19:54	28.60	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3441	2026-09-12 19:55	26.62	OK	3442	2026-09-12 19:56	27.65	OK
3443	2026-09-12 19:57	28.99	OK	3444	2026-09-12 19:58	29.27	OK
3445	2026-09-12 19:59	29.08	OK	3446	2026-09-12 20:00	29.32	OK
3447	2026-09-12 20:01	27.12	OK	3448	2026-09-12 20:02	27.03	OK
3449	2026-09-12 20:03	28.40	OK	3450	2026-09-12 20:04	27.65	OK
3451	2026-09-12 20:05	29.56	OK	3452	2026-09-12 20:06	27.34	OK
3453	2026-09-12 20:07	28.27	OK	3454	2026-09-12 20:08	28.52	OK
3455	2026-09-12 20:09	26.72	OK	3456	2026-09-12 20:10	26.93	OK
3457	2026-09-12 20:11	28.90	OK	3458	2026-09-12 20:12	27.32	OK
3459	2026-09-12 20:13	30.14	OK	3460	2026-09-12 20:14	27.33	OK
3461	2026-09-12 20:15	28.79	OK	3462	2026-09-12 20:16	27.84	OK
3463	2026-09-12 20:17	27.33	OK	3464	2026-09-12 20:18	28.74	OK
3465	2026-09-12 20:19	27.78	OK	3466	2026-09-12 20:20	28.92	OK
3467	2026-09-12 20:21	28.86	OK	3468	2026-09-12 20:22	28.56	OK
3469	2026-09-12 20:23	28.89	OK	3470	2026-09-12 20:24	28.75	OK
3471	2026-09-12 20:25	28.84	OK	3472	2026-09-12 20:26	28.54	OK
3473	2026-09-12 20:27	28.48	OK	3474	2026-09-12 20:28	28.60	OK
3475	2026-09-12 20:29	29.82	OK	3476	2026-09-12 20:30	28.36	OK
3477	2026-09-12 20:31	29.20	OK	3478	2026-09-12 20:32	28.74	OK
3479	2026-09-12 20:33	29.27	OK	3480	2026-09-12 20:34	27.90	OK
3481	2026-09-12 20:35	28.54	OK	3482	2026-09-12 20:36	29.67	OK
3483	2026-09-12 20:37	29.74	OK	3484	2026-09-12 20:38	28.59	OK
3485	2026-09-12 20:39	28.67	OK	3486	2026-09-12 20:40	27.50	OK
3487	2026-09-12 20:41	28.28	OK	3488	2026-09-12 20:42	27.67	OK
3489	2026-09-12 20:43	30.06	OK	3490	2026-09-12 20:44	29.50	OK
3491	2026-09-12 20:45	27.99	OK	3492	2026-09-12 20:46	27.98	OK
3493	2026-09-12 20:47	27.23	OK	3494	2026-09-12 20:48	27.69	OK
3495	2026-09-12 20:49	28.98	OK	3496	2026-09-12 20:50	29.67	OK
3497	2026-09-12 20:51	29.56	OK	3498	2026-09-12 20:52	29.12	OK
3499	2026-09-12 20:53	28.60	OK	3500	2026-09-12 20:54	28.18	OK
3501	2026-09-12 20:55	29.63	OK	3502	2026-09-12 20:56	30.06	OK
3503	2026-09-12 20:57	29.76	OK	3504	2026-09-12 20:58	28.98	OK
3505	2026-09-12 20:59	29.70	OK	3506	2026-09-12 21:00	29.15	OK
3507	2026-09-12 21:01	27.57	OK	3508	2026-09-12 21:02	29.35	OK
3509	2026-09-12 21:03	30.21	OK	3510	2026-09-12 21:04	29.14	OK
3511	2026-09-12 21:05	28.15	OK	3512	2026-09-12 21:06	29.10	OK
3513	2026-09-12 21:07	28.95	OK	3514	2026-09-12 21:08	28.61	OK
3515	2026-09-12 21:09	29.86	OK	3516	2026-09-12 21:10	29.52	OK
3517	2026-09-12 21:11	29.16	OK	3518	2026-09-12 21:12	29.17	OK
3519	2026-09-12 21:13	27.91	OK	3520	2026-09-12 21:14	29.14	OK
3521	2026-09-12 21:15	29.37	OK	3522	2026-09-12 21:16	29.56	OK
3523	2026-09-12 21:17	30.53	OK	3524	2026-09-12 21:18	28.11	OK
3525	2026-09-12 21:19	29.28	OK	3526	2026-09-12 21:20	29.02	OK
3527	2026-09-12 21:21	28.44	OK	3528	2026-09-12 21:22	29.03	OK
3529	2026-09-12 21:23	29.04	OK	3530	2026-09-12 21:24	27.63	OK
3531	2026-09-12 21:25	27.58	OK	3532	2026-09-12 21:26	29.12	OK
3533	2026-09-12 21:27	29.45	OK	3534	2026-09-12 21:28	29.46	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3535	2026-09-12 21:29	29.27	OK	3536	2026-09-12 21:30	29.01	OK
3537	2026-09-12 21:31	29.27	OK	3538	2026-09-12 21:32	29.12	OK
3539	2026-09-12 21:33	29.04	OK	3540	2026-09-12 21:34	30.96	OK
3541	2026-09-12 21:35	28.22	OK	3542	2026-09-12 21:36	30.10	OK
3543	2026-09-12 21:37	28.47	OK	3544	2026-09-12 21:38	29.76	OK
3545	2026-09-12 21:39	29.04	OK	3546	2026-09-12 21:40	27.93	OK
3547	2026-09-12 21:41	27.27	OK	3548	2026-09-12 21:42	29.01	OK
3549	2026-09-12 21:43	29.77	OK	3550	2026-09-12 21:44	28.69	OK
3551	2026-09-12 21:45	29.87	OK	3552	2026-09-12 21:46	28.88	OK
3553	2026-09-12 21:47	29.36	OK	3554	2026-09-12 21:48	29.83	OK
3555	2026-09-12 21:49	29.17	OK	3556	2026-09-12 21:50	30.04	OK
3557	2026-09-12 21:51	29.75	OK	3558	2026-09-12 21:52	29.24	OK
3559	2026-09-12 21:53	29.23	OK	3560	2026-09-12 21:54	30.06	OK
3561	2026-09-12 21:55	28.78	OK	3562	2026-09-12 21:56	29.65	OK
3563	2026-09-12 21:57	29.43	OK	3564	2026-09-12 21:58	29.07	OK
3565	2026-09-12 21:59	28.21	OK	3566	2026-09-12 22:00	29.98	OK
3567	2026-09-12 22:01	29.87	OK	3568	2026-09-12 22:02	28.66	OK
3569	2026-09-12 22:03	28.28	OK	3570	2026-09-12 22:04	29.62	OK
3571	2026-09-12 22:05	28.87	OK	3572	2026-09-12 22:06	30.16	OK
3573	2026-09-12 22:07	29.42	OK	3574	2026-09-12 22:08	30.13	OK
3575	2026-09-12 22:09	29.11	OK	3576	2026-09-12 22:10	28.96	OK
3577	2026-09-12 22:11	29.98	OK	3578	2026-09-12 22:12	29.89	OK
3579	2026-09-12 22:13	29.89	OK	3580	2026-09-12 22:14	29.64	OK
3581	2026-09-12 22:15	29.39	OK	3582	2026-09-12 22:16	30.12	OK
3583	2026-09-12 22:17	28.51	OK	3584	2026-09-12 22:18	30.31	OK
3585	2026-09-12 22:19	30.08	OK	3586	2026-09-12 22:20	31.21	OK
3587	2026-09-12 22:21	29.65	OK	3588	2026-09-12 22:22	28.86	OK
3589	2026-09-12 22:23	29.73	OK	3590	2026-09-12 22:24	29.48	OK
3591	2026-09-12 22:25	28.41	OK	3592	2026-09-12 22:26	30.57	OK
3593	2026-09-12 22:27	28.79	OK	3594	2026-09-12 22:28	29.15	OK
3595	2026-09-12 22:29	29.18	OK	3596	2026-09-12 22:30	29.31	OK
3597	2026-09-12 22:31	28.75	OK	3598	2026-09-12 22:32	30.65	OK
3599	2026-09-12 22:33	28.94	OK	3600	2026-09-12 22:34	28.07	OK
3601	2026-09-12 22:35	29.20	OK	3602	2026-09-12 22:36	30.13	OK
3603	2026-09-12 22:37	29.15	OK	3604	2026-09-12 22:38	30.32	OK
3605	2026-09-12 22:39	30.09	OK	3606	2026-09-12 22:40	29.92	OK
3607	2026-09-12 22:41	30.43	OK	3608	2026-09-12 22:42	30.04	OK
3609	2026-09-12 22:43	28.85	OK	3610	2026-09-12 22:44	29.87	OK
3611	2026-09-12 22:45	29.76	OK	3612	2026-09-12 22:46	30.43	OK
3613	2026-09-12 22:47	29.68	OK	3614	2026-09-12 22:48	29.21	OK
3615	2026-09-12 22:49	29.14	OK	3616	2026-09-12 22:50	30.83	OK
3617	2026-09-12 22:51	29.19	OK	3618	2026-09-12 22:52	30.49	OK
3619	2026-09-12 22:53	28.91	OK	3620	2026-09-12 22:54	29.22	OK
3621	2026-09-12 22:55	30.29	OK	3622	2026-09-12 22:56	30.02	OK
3623	2026-09-12 22:57	29.63	OK	3624	2026-09-12 22:58	29.70	OK
3625	2026-09-12 22:59	30.10	OK	3626	2026-09-12 23:00	29.07	OK
3627	2026-09-12 23:01	30.56	OK	3628	2026-09-12 23:02	29.95	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3629	2026-09-12 23:03	28.14	OK	3630	2026-09-12 23:04	30.03	OK
3631	2026-09-12 23:05	30.74	OK	3632	2026-09-12 23:06	28.66	OK
3633	2026-09-12 23:07	29.23	OK	3634	2026-09-12 23:08	28.36	OK
3635	2026-09-12 23:09	29.02	OK	3636	2026-09-12 23:10	29.94	OK
3637	2026-09-12 23:11	30.45	OK	3638	2026-09-12 23:12	30.52	OK
3639	2026-09-12 23:13	28.93	OK	3640	2026-09-12 23:14	29.97	OK
3641	2026-09-12 23:15	28.58	OK	3642	2026-09-12 23:16	30.39	OK
3643	2026-09-12 23:17	30.65	OK	3644	2026-09-12 23:18	30.33	OK
3645	2026-09-12 23:19	29.93	OK	3646	2026-09-12 23:20	30.05	OK
3647	2026-09-12 23:21	29.95	OK	3648	2026-09-12 23:22	31.03	OK
3649	2026-09-12 23:23	29.52	OK	3650	2026-09-12 23:24	28.32	OK
3651	2026-09-12 23:25	30.88	OK	3652	2026-09-12 23:26	28.55	OK
3653	2026-09-12 23:27	31.09	OK	3654	2026-09-12 23:28	31.29	OK
3655	2026-09-12 23:29	29.48	OK	3656	2026-09-12 23:30	29.43	OK
3657	2026-09-12 23:31	29.87	OK	3658	2026-09-12 23:32	30.92	OK
3659	2026-09-12 23:33	31.11	OK	3660	2026-09-12 23:34	30.36	OK
3661	2026-09-12 23:35	30.02	OK	3662	2026-09-12 23:36	29.58	OK
3663	2026-09-12 23:37	28.68	OK	3664	2026-09-12 23:38	29.76	OK
3665	2026-09-12 23:39	30.61	OK	3666	2026-09-12 23:40	31.90	OK
3667	2026-09-12 23:41	31.53	OK	3668	2026-09-12 23:42	29.67	OK
3669	2026-09-12 23:43	29.01	OK	3670	2026-09-12 23:44	29.75	OK
3671	2026-09-12 23:45	30.38	OK	3672	2026-09-12 23:46	31.74	OK
3673	2026-09-12 23:47	29.74	OK	3674	2026-09-12 23:48	30.51	OK
3675	2026-09-12 23:49	29.55	OK	3676	2026-09-12 23:50	30.29	OK
3677	2026-09-12 23:51	30.73	OK	3678	2026-09-12 23:52	29.32	OK
3679	2026-09-12 23:53	29.57	OK	3680	2026-09-12 23:54	30.52	OK
3681	2026-09-12 23:55	29.00	OK	3682	2026-09-12 23:56	30.09	OK
3683	2026-09-12 23:57	30.56	OK	3684	2026-09-12 23:58	29.17	OK
3685	2026-09-12 23:59	29.26	OK	3686	2026-09-13 00:00	30.82	OK
3687	2026-09-13 00:01	29.62	OK	3688	2026-09-13 00:02	29.62	OK
3689	2026-09-13 00:03	31.14	OK	3690	2026-09-13 00:04	29.61	OK
3691	2026-09-13 00:05	31.21	OK	3692	2026-09-13 00:06	29.97	OK
3693	2026-09-13 00:07	30.08	OK	3694	2026-09-13 00:08	30.31	OK
3695	2026-09-13 00:09	29.56	OK	3696	2026-09-13 00:10	30.21	OK
3697	2026-09-13 00:11	30.50	OK	3698	2026-09-13 00:12	30.30	OK
3699	2026-09-13 00:13	29.56	OK	3700	2026-09-13 00:14	31.07	OK
3701	2026-09-13 00:15	28.50	OK	3702	2026-09-13 00:16	30.30	OK
3703	2026-09-13 00:17	30.18	OK	3704	2026-09-13 00:18	30.67	OK
3705	2026-09-13 00:19	31.32	OK	3706	2026-09-13 00:20	30.75	OK
3707	2026-09-13 00:21	31.23	OK	3708	2026-09-13 00:22	31.94	OK
3709	2026-09-13 00:23	30.67	OK	3710	2026-09-13 00:24	30.10	OK
3711	2026-09-13 00:25	29.91	OK	3712	2026-09-13 00:26	28.92	OK
3713	2026-09-13 00:27	30.39	OK	3714	2026-09-13 00:28	30.33	OK
3715	2026-09-13 00:29	31.55	OK	3716	2026-09-13 00:30	31.99	OK
3717	2026-09-13 00:31	30.91	OK	3718	2026-09-13 00:32	30.54	OK
3719	2026-09-13 00:33	30.54	OK	3720	2026-09-13 00:34	30.97	OK
3721	2026-09-13 00:35	30.07	OK	3722	2026-09-13 00:36	30.46	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3723	2026-09-13 00:37	30.70	OK	3724	2026-09-13 00:38	29.55	OK
3725	2026-09-13 00:39	29.89	OK	3726	2026-09-13 00:40	30.94	OK
3727	2026-09-13 00:41	30.16	OK	3728	2026-09-13 00:42	30.33	OK
3729	2026-09-13 00:43	29.24	OK	3730	2026-09-13 00:44	30.16	OK
3731	2026-09-13 00:45	30.14	OK	3732	2026-09-13 00:46	31.46	OK
3733	2026-09-13 00:47	30.82	OK	3734	2026-09-13 00:48	30.13	OK
3735	2026-09-13 00:49	31.55	OK	3736	2026-09-13 00:50	29.58	OK
3737	2026-09-13 00:51	30.50	OK	3738	2026-09-13 00:52	30.99	OK
3739	2026-09-13 00:53	32.01	OK	3740	2026-09-13 00:54	31.04	OK
3741	2026-09-13 00:55	29.34	OK	3742	2026-09-13 00:56	31.27	OK
3743	2026-09-13 00:57	29.17	OK	3744	2026-09-13 00:58	30.30	OK
3745	2026-09-13 00:59	30.18	OK	3746	2026-09-13 01:00	30.45	OK
3747	2026-09-13 01:01	29.75	OK	3748	2026-09-13 01:02	30.83	OK
3749	2026-09-13 01:03	30.94	OK	3750	2026-09-13 01:04	29.62	OK
3751	2026-09-13 01:05	31.77	OK	3752	2026-09-13 01:06	30.97	OK
3753	2026-09-13 01:07	29.87	OK	3754	2026-09-13 01:08	28.82	OK
3755	2026-09-13 01:09	29.24	OK	3756	2026-09-13 01:10	31.31	OK
3757	2026-09-13 01:11	30.78	OK	3758	2026-09-13 01:12	31.29	OK
3759	2026-09-13 01:13	29.09	OK	3760	2026-09-13 01:14	29.52	OK
3761	2026-09-13 01:15	29.21	OK	3762	2026-09-13 01:16	29.51	OK
3763	2026-09-13 01:17	30.93	OK	3764	2026-09-13 01:18	30.71	OK
3765	2026-09-13 01:19	28.97	OK	3766	2026-09-13 01:20	30.21	OK
3767	2026-09-13 01:21	31.28	OK	3768	2026-09-13 01:22	30.96	OK
3769	2026-09-13 01:23	29.48	OK	3770	2026-09-13 01:24	31.01	OK
3771	2026-09-13 01:25	29.24	OK	3772	2026-09-13 01:26	31.82	OK
3773	2026-09-13 01:27	30.03	OK	3774	2026-09-13 01:28	30.50	OK
3775	2026-09-13 01:29	30.74	OK	3776	2026-09-13 01:30	29.86	OK
3777	2026-09-13 01:31	30.37	OK	3778	2026-09-13 01:32	30.21	OK
3779	2026-09-13 01:33	29.92	OK	3780	2026-09-13 01:34	31.07	OK
3781	2026-09-13 01:35	30.50	OK	3782	2026-09-13 01:36	29.65	OK
3783	2026-09-13 01:37	31.64	OK	3784	2026-09-13 01:38	29.98	OK
3785	2026-09-13 01:39	31.73	OK	3786	2026-09-13 01:40	30.08	OK
3787	2026-09-13 01:41	29.25	OK	3788	2026-09-13 01:42	29.40	OK
3789	2026-09-13 01:43	30.45	OK	3790	2026-09-13 01:44	31.14	OK
3791	2026-09-13 01:45	30.94	OK	3792	2026-09-13 01:46	28.93	OK
3793	2026-09-13 01:47	30.99	OK	3794	2026-09-13 01:48	30.99	OK
3795	2026-09-13 01:49	31.17	OK	3796	2026-09-13 01:50	29.25	OK
3797	2026-09-13 01:51	28.89	OK	3798	2026-09-13 01:52	30.53	OK
3799	2026-09-13 01:53	30.71	OK	3800	2026-09-13 01:54	30.01	OK
3801	2026-09-13 01:55	29.78	OK	3802	2026-09-13 01:56	29.98	OK
3803	2026-09-13 01:57	29.96	OK	3804	2026-09-13 01:58	30.54	OK
3805	2026-09-13 01:59	30.39	OK	3806	2026-09-13 02:00	31.32	OK
3807	2026-09-13 02:01	31.38	OK	3808	2026-09-13 02:02	31.50	OK
3809	2026-09-13 02:03	29.41	OK	3810	2026-09-13 02:04	30.84	OK
3811	2026-09-13 02:05	31.00	OK	3812	2026-09-13 02:06	31.90	OK
3813	2026-09-13 02:07	31.66	OK	3814	2026-09-13 02:08	30.98	OK
3815	2026-09-13 02:09	29.64	OK	3816	2026-09-13 02:10	29.47	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3817	2026-09-13 02:11	30.31	OK	3818	2026-09-13 02:12	30.13	OK
3819	2026-09-13 02:13	28.55	OK	3820	2026-09-13 02:14	30.45	OK
3821	2026-09-13 02:15	29.65	OK	3822	2026-09-13 02:16	31.73	OK
3823	2026-09-13 02:17	29.81	OK	3824	2026-09-13 02:18	30.21	OK
3825	2026-09-13 02:19	30.59	OK	3826	2026-09-13 02:20	29.79	OK
3827	2026-09-13 02:21	31.01	OK	3828	2026-09-13 02:22	30.00	OK
3829	2026-09-13 02:23	29.56	OK	3830	2026-09-13 02:24	30.44	OK
3831	2026-09-13 02:25	30.04	OK	3832	2026-09-13 02:26	28.84	OK
3833	2026-09-13 02:27	31.49	OK	3834	2026-09-13 02:28	29.82	OK
3835	2026-09-13 02:29	31.95	OK	3836	2026-09-13 02:30	30.74	OK
3837	2026-09-13 02:31	30.41	OK	3838	2026-09-13 02:32	31.51	OK
3839	2026-09-13 02:33	30.02	OK	3840	2026-09-13 02:34	28.52	OK
3841	2026-09-13 02:35	30.29	OK	3842	2026-09-13 02:36	31.76	OK
3843	2026-09-13 02:37	30.22	OK	3844	2026-09-13 02:38	29.47	OK
3845	2026-09-13 02:39	31.11	OK	3846	2026-09-13 02:40	31.09	OK
3847	2026-09-13 02:41	31.36	OK	3848	2026-09-13 02:42	31.82	OK
3849	2026-09-13 02:43	32.33	OK	3850	2026-09-13 02:44	29.06	OK
3851	2026-09-13 02:45	29.98	OK	3852	2026-09-13 02:46	30.45	OK
3853	2026-09-13 02:47	30.47	OK	3854	2026-09-13 02:48	30.28	OK
3855	2026-09-13 02:49	30.61	OK	3856	2026-09-13 02:50	28.75	OK
3857	2026-09-13 02:51	30.29	OK	3858	2026-09-13 02:52	29.94	OK
3859	2026-09-13 02:53	29.85	OK	3860	2026-09-13 02:54	29.70	OK
3861	2026-09-13 02:55	29.96	OK	3862	2026-09-13 02:56	31.72	OK
3863	2026-09-13 02:57	30.88	OK	3864	2026-09-13 02:58	31.74	OK
3865	2026-09-13 02:59	31.60	OK	3866	2026-09-13 03:00	29.63	OK
3867	2026-09-13 03:01	29.62	OK	3868	2026-09-13 03:02	31.13	OK
3869	2026-09-13 03:03	29.57	OK	3870	2026-09-13 03:04	29.84	OK
3871	2026-09-13 03:05	29.08	OK	3872	2026-09-13 03:06	29.04	OK
3873	2026-09-13 03:07	30.32	OK	3874	2026-09-13 03:08	29.97	OK
3875	2026-09-13 03:09	30.57	OK	3876	2026-09-13 03:10	30.61	OK
3877	2026-09-13 03:11	29.40	OK	3878	2026-09-13 03:12	30.63	OK
3879	2026-09-13 03:13	29.46	OK	3880	2026-09-13 03:14	29.78	OK
3881	2026-09-13 03:15	29.95	OK	3882	2026-09-13 03:16	30.22	OK
3883	2026-09-13 03:17	30.34	OK	3884	2026-09-13 03:18	29.24	OK
3885	2026-09-13 03:19	28.88	OK	3886	2026-09-13 03:20	30.95	OK
3887	2026-09-13 03:21	30.74	OK	3888	2026-09-13 03:22	28.67	OK
3889	2026-09-13 03:23	30.12	OK	3890	2026-09-13 03:24	28.04	OK
3891	2026-09-13 03:25	28.47	OK	3892	2026-09-13 03:26	30.13	OK
3893	2026-09-13 03:27	29.48	OK	3894	2026-09-13 03:28	30.25	OK
3895	2026-09-13 03:29	29.71	OK	3896	2026-09-13 03:30	31.19	OK
3897	2026-09-13 03:31	28.69	OK	3898	2026-09-13 03:32	28.66	OK
3899	2026-09-13 03:33	31.53	OK	3900	2026-09-13 03:34	30.97	OK
3901	2026-09-13 03:35	29.06	OK	3902	2026-09-13 03:36	31.40	OK
3903	2026-09-13 03:37	31.20	OK	3904	2026-09-13 03:38	29.62	OK
3905	2026-09-13 03:39	29.70	OK	3906	2026-09-13 03:40	30.91	OK
3907	2026-09-13 03:41	30.48	OK	3908	2026-09-13 03:42	30.44	OK
3909	2026-09-13 03:43	29.79	OK	3910	2026-09-13 03:44	29.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
3911	2026-09-13 03:45	30.05	OK	3912	2026-09-13 03:46	29.27	OK
3913	2026-09-13 03:47	29.48	OK	3914	2026-09-13 03:48	29.08	OK
3915	2026-09-13 03:49	30.55	OK	3916	2026-09-13 03:50	29.06	OK
3917	2026-09-13 03:51	28.97	OK	3918	2026-09-13 03:52	30.49	OK
3919	2026-09-13 03:53	28.99	OK	3920	2026-09-13 03:54	29.46	OK
3921	2026-09-13 03:55	30.20	OK	3922	2026-09-13 03:56	30.95	OK
3923	2026-09-13 03:57	30.69	OK	3924	2026-09-13 03:58	29.55	OK
3925	2026-09-13 03:59	30.59	OK	3926	2026-09-13 04:00	29.61	OK
3927	2026-09-13 04:01	29.32	OK	3928	2026-09-13 04:02	28.46	OK
3929	2026-09-13 04:03	29.95	OK	3930	2026-09-13 04:04	30.66	OK
3931	2026-09-13 04:05	29.59	OK	3932	2026-09-13 04:06	28.96	OK
3933	2026-09-13 04:07	30.22	OK	3934	2026-09-13 04:08	29.94	OK
3935	2026-09-13 04:09	28.29	OK	3936	2026-09-13 04:10	29.84	OK
3937	2026-09-13 04:11	28.72	OK	3938	2026-09-13 04:12	28.67	OK
3939	2026-09-13 04:13	28.14	OK	3940	2026-09-13 04:14	29.42	OK
3941	2026-09-13 04:15	29.78	OK	3942	2026-09-13 04:16	30.37	OK
3943	2026-09-13 04:17	29.36	OK	3944	2026-09-13 04:18	29.05	OK
3945	2026-09-13 04:19	30.67	OK	3946	2026-09-13 04:20	29.35	OK
3947	2026-09-13 04:21	29.58	OK	3948	2026-09-13 04:22	30.00	OK
3949	2026-09-13 04:23	29.10	OK	3950	2026-09-13 04:24	29.36	OK
3951	2026-09-13 04:25	29.67	OK	3952	2026-09-13 04:26	29.72	OK
3953	2026-09-13 04:27	29.63	OK	3954	2026-09-13 04:28	30.73	OK
3955	2026-09-13 04:29	29.62	OK	3956	2026-09-13 04:30	29.50	OK
3957	2026-09-13 04:31	30.74	OK	3958	2026-09-13 04:32	30.25	OK
3959	2026-09-13 04:33	30.30	OK	3960	2026-09-13 04:34	28.57	OK
3961	2026-09-13 04:35	29.79	OK	3962	2026-09-13 04:36	30.08	OK
3963	2026-09-13 04:37	28.79	OK	3964	2026-09-13 04:38	30.02	OK
3965	2026-09-13 04:39	29.42	OK	3966	2026-09-13 04:40	29.08	OK
3967	2026-09-13 04:41	30.08	OK	3968	2026-09-13 04:42	28.88	OK
3969	2026-09-13 04:43	29.31	OK	3970	2026-09-13 04:44	29.42	OK
3971	2026-09-13 04:45	29.21	OK	3972	2026-09-13 04:46	28.10	OK
3973	2026-09-13 04:47	28.93	OK	3974	2026-09-13 04:48	29.95	OK
3975	2026-09-13 04:49	29.01	OK	3976	2026-09-13 04:50	29.64	OK
3977	2026-09-13 04:51	29.00	OK	3978	2026-09-13 04:52	29.41	OK
3979	2026-09-13 04:53	30.30	OK	3980	2026-09-13 04:54	29.34	OK
3981	2026-09-13 04:55	30.60	OK	3982	2026-09-13 04:56	28.85	OK
3983	2026-09-13 04:57	28.64	OK	3984	2026-09-13 04:58	29.49	OK
3985	2026-09-13 04:59	29.05	OK	3986	2026-09-13 05:00	28.73	OK
3987	2026-09-13 05:01	31.14	OK	3988	2026-09-13 05:02	30.36	OK
3989	2026-09-13 05:03	28.98	OK	3990	2026-09-13 05:04	30.69	OK
3991	2026-09-13 05:05	28.99	OK	3992	2026-09-13 05:06	29.79	OK
3993	2026-09-13 05:07	28.47	OK	3994	2026-09-13 05:08	28.73	OK
3995	2026-09-13 05:09	29.20	OK	3996	2026-09-13 05:10	29.78	OK
3997	2026-09-13 05:11	28.80	OK	3998	2026-09-13 05:12	28.60	OK
3999	2026-09-13 05:13	29.07	OK	4000	2026-09-13 05:14	29.95	OK
4001	2026-09-13 05:15	29.19	OK	4002	2026-09-13 05:16	29.48	OK
4003	2026-09-13 05:17	28.48	OK	4004	2026-09-13 05:18	27.42	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4005	2026-09-13 05:19	29.31	OK	4006	2026-09-13 05:20	29.77	OK
4007	2026-09-13 05:21	28.54	OK	4008	2026-09-13 05:22	30.63	OK
4009	2026-09-13 05:23	28.42	OK	4010	2026-09-13 05:24	28.21	OK
4011	2026-09-13 05:25	29.75	OK	4012	2026-09-13 05:26	30.25	OK
4013	2026-09-13 05:27	30.19	OK	4014	2026-09-13 05:28	29.16	OK
4015	2026-09-13 05:29	27.59	OK	4016	2026-09-13 05:30	29.80	OK
4017	2026-09-13 05:31	28.50	OK	4018	2026-09-13 05:32	28.11	OK
4019	2026-09-13 05:33	28.63	OK	4020	2026-09-13 05:34	29.85	OK
4021	2026-09-13 05:35	28.88	OK	4022	2026-09-13 05:36	28.45	OK
4023	2026-09-13 05:37	29.61	OK	4024	2026-09-13 05:38	28.99	OK
4025	2026-09-13 05:39	28.57	OK	4026	2026-09-13 05:40	30.86	OK
4027	2026-09-13 05:41	29.28	OK	4028	2026-09-13 05:42	28.16	OK
4029	2026-09-13 05:43	29.24	OK	4030	2026-09-13 05:44	28.72	OK
4031	2026-09-13 05:45	30.44	OK	4032	2026-09-13 05:46	29.85	OK
4033	2026-09-13 05:47	29.82	OK	4034	2026-09-13 05:48	28.72	OK
4035	2026-09-13 05:49	29.44	OK	4036	2026-09-13 05:50	28.26	OK
4037	2026-09-13 05:51	29.80	OK	4038	2026-09-13 05:52	29.98	OK
4039	2026-09-13 05:53	27.87	OK	4040	2026-09-13 05:54	28.78	OK
4041	2026-09-13 05:55	28.51	OK	4042	2026-09-13 05:56	30.22	OK
4043	2026-09-13 05:57	27.79	OK	4044	2026-09-13 05:58	29.40	OK
4045	2026-09-13 05:59	28.94	OK	4046	2026-09-13 06:00	29.27	OK
4047	2026-09-13 06:01	28.50	OK	4048	2026-09-13 06:02	29.61	OK
4049	2026-09-13 06:03	29.51	OK	4050	2026-09-13 06:04	28.87	OK
4051	2026-09-13 06:05	30.00	OK	4052	2026-09-13 06:06	27.73	OK
4053	2026-09-13 06:07	28.13	OK	4054	2026-09-13 06:08	27.93	OK
4055	2026-09-13 06:09	30.06	OK	4056	2026-09-13 06:10	29.15	OK
4057	2026-09-13 06:11	29.69	OK	4058	2026-09-13 06:12	29.19	OK
4059	2026-09-13 06:13	30.23	OK	4060	2026-09-13 06:14	29.67	OK
4061	2026-09-13 06:15	28.70	OK	4062	2026-09-13 06:16	28.95	OK
4063	2026-09-13 06:17	28.52	OK	4064	2026-09-13 06:18	27.72	OK
4065	2026-09-13 06:19	29.27	OK	4066	2026-09-13 06:20	28.95	OK
4067	2026-09-13 06:21	28.27	OK	4068	2026-09-13 06:22	28.61	OK
4069	2026-09-13 06:23	28.52	OK	4070	2026-09-13 06:24	28.17	OK
4071	2026-09-13 06:25	27.82	OK	4072	2026-09-13 06:26	28.75	OK
4073	2026-09-13 06:27	27.39	OK	4074	2026-09-13 06:28	28.39	OK
4075	2026-09-13 06:29	27.36	OK	4076	2026-09-13 06:30	29.04	OK
4077	2026-09-13 06:31	29.08	OK	4078	2026-09-13 06:32	28.98	OK
4079	2026-09-13 06:33	28.85	OK	4080	2026-09-13 06:34	28.61	OK
4081	2026-09-13 06:35	28.63	OK	4082	2026-09-13 06:36	29.02	OK
4083	2026-09-13 06:37	28.98	OK	4084	2026-09-13 06:38	27.81	OK
4085	2026-09-13 06:39	27.89	OK	4086	2026-09-13 06:40	29.73	OK
4087	2026-09-13 06:41	27.96	OK	4088	2026-09-13 06:42	29.39	OK
4089	2026-09-13 06:43	29.69	OK	4090	2026-09-13 06:44	28.32	OK
4091	2026-09-13 06:45	29.08	OK	4092	2026-09-13 06:46	28.66	OK
4093	2026-09-13 06:47	28.36	OK	4094	2026-09-13 06:48	29.01	OK
4095	2026-09-13 06:49	29.24	OK	4096	2026-09-13 06:50	28.55	OK
4097	2026-09-13 06:51	28.64	OK	4098	2026-09-13 06:52	28.13	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4099	2026-09-13 06:53	27.04	OK	4100	2026-09-13 06:54	27.25	OK
4101	2026-09-13 06:55	29.12	OK	4102	2026-09-13 06:56	28.37	OK
4103	2026-09-13 06:57	28.52	OK	4104	2026-09-13 06:58	29.10	OK
4105	2026-09-13 06:59	27.53	OK	4106	2026-09-13 07:00	27.69	OK
4107	2026-09-13 07:01	28.36	OK	4108	2026-09-13 07:02	27.73	OK
4109	2026-09-13 07:03	29.12	OK	4110	2026-09-13 07:04	28.45	OK
4111	2026-09-13 07:05	27.16	OK	4112	2026-09-13 07:06	27.78	OK
4113	2026-09-13 07:07	27.48	OK	4114	2026-09-13 07:08	27.55	OK
4115	2026-09-13 07:09	28.50	OK	4116	2026-09-13 07:10	29.64	OK
4117	2026-09-13 07:11	28.05	OK	4118	2026-09-13 07:12	29.38	OK
4119	2026-09-13 07:13	28.12	OK	4120	2026-09-13 07:14	26.64	OK
4121	2026-09-13 07:15	27.32	OK	4122	2026-09-13 07:16	27.58	OK
4123	2026-09-13 07:17	27.98	OK	4124	2026-09-13 07:18	27.87	OK
4125	2026-09-13 07:19	27.70	OK	4126	2026-09-13 07:20	26.71	OK
4127	2026-09-13 07:21	27.73	OK	4128	2026-09-13 07:22	28.36	OK
4129	2026-09-13 07:23	28.16	OK	4130	2026-09-13 07:24	29.14	OK
4131	2026-09-13 07:25	28.15	OK	4132	2026-09-13 07:26	26.69	OK
4133	2026-09-13 07:27	25.88	OK	4134	2026-09-13 07:28	28.38	OK
4135	2026-09-13 07:29	28.83	OK	4136	2026-09-13 07:30	28.67	OK
4137	2026-09-13 07:31	28.80	OK	4138	2026-09-13 07:32	27.47	OK
4139	2026-09-13 07:33	27.22	OK	4140	2026-09-13 07:34	27.87	OK
4141	2026-09-13 07:35	27.91	OK	4142	2026-09-13 07:36	27.59	OK
4143	2026-09-13 07:37	28.90	OK	4144	2026-09-13 07:38	27.88	OK
4145	2026-09-13 07:39	29.05	OK	4146	2026-09-13 07:40	27.18	OK
4147	2026-09-13 07:41	28.82	OK	4148	2026-09-13 07:42	27.95	OK
4149	2026-09-13 07:43	28.44	OK	4150	2026-09-13 07:44	28.41	OK
4151	2026-09-13 07:45	29.05	OK	4152	2026-09-13 07:46	27.83	OK
4153	2026-09-13 07:47	27.20	OK	4154	2026-09-13 07:48	27.59	OK
4155	2026-09-13 07:49	28.49	OK	4156	2026-09-13 07:50	28.44	OK
4157	2026-09-13 07:51	28.28	OK	4158	2026-09-13 07:52	27.93	OK
4159	2026-09-13 07:53	26.96	OK	4160	2026-09-13 07:54	27.08	OK
4161	2026-09-13 07:55	26.48	OK	4162	2026-09-13 07:56	28.32	OK
4163	2026-09-13 07:57	26.93	OK	4164	2026-09-13 07:58	28.06	OK
4165	2026-09-13 07:59	27.17	OK	4166	2026-09-13 08:00	28.52	OK
4167	2026-09-13 08:01	27.12	OK	4168	2026-09-13 08:02	27.93	OK
4169	2026-09-13 08:03	28.16	OK	4170	2026-09-13 08:04	26.20	OK
4171	2026-09-13 08:05	26.72	OK	4172	2026-09-13 08:06	26.07	OK
4173	2026-09-13 08:07	27.47	OK	4174	2026-09-13 08:08	28.28	OK
4175	2026-09-13 08:09	27.10	OK	4176	2026-09-13 08:10	28.12	OK
4177	2026-09-13 08:11	27.53	OK	4178	2026-09-13 08:12	27.27	OK
4179	2026-09-13 08:13	27.62	OK	4180	2026-09-13 08:14	28.17	OK
4181	2026-09-13 08:15	27.40	OK	4182	2026-09-13 08:16	26.65	OK
4183	2026-09-13 08:17	27.37	OK	4184	2026-09-13 08:18	28.75	OK
4185	2026-09-13 08:19	26.99	OK	4186	2026-09-13 08:20	27.72	OK
4187	2026-09-13 08:21	26.57	OK	4188	2026-09-13 08:22	26.74	OK
4189	2026-09-13 08:23	27.41	OK	4190	2026-09-13 08:24	26.30	OK
4191	2026-09-13 08:25	26.16	OK	4192	2026-09-13 08:26	27.25	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4193	2026-09-13 08:27	27.81	OK	4194	2026-09-13 08:28	28.23	OK
4195	2026-09-13 08:29	28.99	OK	4196	2026-09-13 08:30	27.83	OK
4197	2026-09-13 08:31	26.99	OK	4198	2026-09-13 08:32	27.35	OK
4199	2026-09-13 08:33	26.88	OK	4200	2026-09-13 08:34	28.46	OK
4201	2026-09-13 08:35	27.85	OK	4202	2026-09-13 08:36	27.77	OK
4203	2026-09-13 08:37	26.08	OK	4204	2026-09-13 08:38	26.53	OK
4205	2026-09-13 08:39	26.98	OK	4206	2026-09-13 08:40	27.59	OK
4207	2026-09-13 08:41	27.84	OK	4208	2026-09-13 08:42	26.61	OK
4209	2026-09-13 08:43	27.31	OK	4210	2026-09-13 08:44	28.53	OK
4211	2026-09-13 08:45	26.16	OK	4212	2026-09-13 08:46	27.85	OK
4213	2026-09-13 08:47	27.04	OK	4214	2026-09-13 08:48	25.99	OK
4215	2026-09-13 08:49	28.06	OK	4216	2026-09-13 08:50	27.95	OK
4217	2026-09-13 08:51	26.86	OK	4218	2026-09-13 08:52	27.71	OK
4219	2026-09-13 08:53	26.76	OK	4220	2026-09-13 08:54	26.50	OK
4221	2026-09-13 08:55	27.38	OK	4222	2026-09-13 08:56	27.78	OK
4223	2026-09-13 08:57	26.60	OK	4224	2026-09-13 08:58	26.31	OK
4225	2026-09-13 08:59	25.51	OK	4226	2026-09-13 09:00	27.09	OK
4227	2026-09-13 09:01	25.63	OK	4228	2026-09-13 09:02	26.69	OK
4229	2026-09-13 09:03	25.77	OK	4230	2026-09-13 09:04	27.79	OK
4231	2026-09-13 09:05	27.29	OK	4232	2026-09-13 09:06	27.12	OK
4233	2026-09-13 09:07	28.13	OK	4234	2026-09-13 09:08	26.97	OK
4235	2026-09-13 09:09	26.82	OK	4236	2026-09-13 09:10	26.63	OK
4237	2026-09-13 09:11	27.13	OK	4238	2026-09-13 09:12	27.02	OK
4239	2026-09-13 09:13	27.53	OK	4240	2026-09-13 09:14	26.50	OK
4241	2026-09-13 09:15	25.74	OK	4242	2026-09-13 09:16	26.93	OK
4243	2026-09-13 09:17	27.50	OK	4244	2026-09-13 09:18	25.96	OK
4245	2026-09-13 09:19	27.82	OK	4246	2026-09-13 09:20	26.55	OK
4247	2026-09-13 09:21	26.85	OK	4248	2026-09-13 09:22	26.67	OK
4249	2026-09-13 09:23	26.52	OK	4250	2026-09-13 09:24	26.75	OK
4251	2026-09-13 09:25	26.61	OK	4252	2026-09-13 09:26	26.22	OK
4253	2026-09-13 09:27	27.10	OK	4254	2026-09-13 09:28	26.87	OK
4255	2026-09-13 09:29	27.17	OK	4256	2026-09-13 09:30	28.56	OK
4257	2026-09-13 09:31	26.92	OK	4258	2026-09-13 09:32	26.08	OK
4259	2026-09-13 09:33	26.44	OK	4260	2026-09-13 09:34	25.15	OK
4261	2026-09-13 09:35	28.01	OK	4262	2026-09-13 09:36	26.90	OK
4263	2026-09-13 09:37	26.69	OK	4264	2026-09-13 09:38	25.28	OK
4265	2026-09-13 09:39	26.87	OK	4266	2026-09-13 09:40	27.01	OK
4267	2026-09-13 09:41	27.74	OK	4268	2026-09-13 09:42	26.49	OK
4269	2026-09-13 09:43	26.97	OK	4270	2026-09-13 09:44	27.97	OK
4271	2026-09-13 09:45	24.82	OK	4272	2026-09-13 09:46	26.43	OK
4273	2026-09-13 09:47	25.19	OK	4274	2026-09-13 09:48	26.54	OK
4275	2026-09-13 09:49	27.23	OK	4276	2026-09-13 09:50	26.10	OK
4277	2026-09-13 09:51	28.82	OK	4278	2026-09-13 09:52	26.82	OK
4279	2026-09-13 09:53	26.89	OK	4280	2026-09-13 09:54	27.49	OK
4281	2026-09-13 09:55	26.42	OK	4282	2026-09-13 09:56	27.47	OK
4283	2026-09-13 09:57	26.78	OK	4284	2026-09-13 09:58	26.08	OK
4285	2026-09-13 09:59	27.00	OK	4286	2026-09-13 10:00	26.42	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4287	2026-09-13 10:01	27.04	OK	4288	2026-09-13 10:02	26.67	OK
4289	2026-09-13 10:03	27.54	OK	4290	2026-09-13 10:04	27.86	OK
4291	2026-09-13 10:05	28.18	OK	4292	2026-09-13 10:06	27.00	OK
4293	2026-09-13 10:07	26.59	OK	4294	2026-09-13 10:08	26.65	OK
4295	2026-09-13 10:09	27.42	OK	4296	2026-09-13 10:10	26.97	OK
4297	2026-09-13 10:11	26.69	OK	4298	2026-09-13 10:12	27.55	OK
4299	2026-09-13 10:13	26.20	OK	4300	2026-09-13 10:14	24.68	OK
4301	2026-09-13 10:15	26.83	OK	4302	2026-09-13 10:16	26.26	OK
4303	2026-09-13 10:17	27.63	OK	4304	2026-09-13 10:18	25.87	OK
4305	2026-09-13 10:19	27.26	OK	4306	2026-09-13 10:20	25.99	OK
4307	2026-09-13 10:21	27.64	OK	4308	2026-09-13 10:22	25.21	OK
4309	2026-09-13 10:23	25.74	OK	4310	2026-09-13 10:24	26.61	OK
4311	2026-09-13 10:25	25.12	OK	4312	2026-09-13 10:26	27.34	OK
4313	2026-09-13 10:27	26.13	OK	4314	2026-09-13 10:28	24.76	OK
4315	2026-09-13 10:29	26.42	OK	4316	2026-09-13 10:30	26.70	OK
4317	2026-09-13 10:31	25.55	OK	4318	2026-09-13 10:32	26.44	OK
4319	2026-09-13 10:33	26.90	OK	4320	2026-09-13 10:34	26.17	OK
4321	2026-09-13 10:35	28.17	OK	4322	2026-09-13 10:36	26.42	OK
4323	2026-09-13 10:37	28.00	OK	4324	2026-09-13 10:38	27.22	OK
4325	2026-09-13 10:39	26.10	OK	4326	2026-09-13 10:40	26.00	OK
4327	2026-09-13 10:41	26.23	OK	4328	2026-09-13 10:42	25.99	OK
4329	2026-09-13 10:43	27.05	OK	4330	2026-09-13 10:44	26.06	OK
4331	2026-09-13 10:45	25.27	OK	4332	2026-09-13 10:46	25.88	OK
4333	2026-09-13 10:47	25.21	OK	4334	2026-09-13 10:48	26.01	OK
4335	2026-09-13 10:49	24.61	OK	4336	2026-09-13 10:50	25.73	OK
4337	2026-09-13 10:51	26.71	OK	4338	2026-09-13 10:52	25.22	OK
4339	2026-09-13 10:53	25.65	OK	4340	2026-09-13 10:54	26.11	OK
4341	2026-09-13 10:55	26.94	OK	4342	2026-09-13 10:56	26.48	OK
4343	2026-09-13 10:57	26.44	OK	4344	2026-09-13 10:58	25.40	OK
4345	2026-09-13 10:59	26.62	OK	4346	2026-09-13 11:00	25.72	OK
4347	2026-09-13 11:01	25.22	OK	4348	2026-09-13 11:02	25.44	OK
4349	2026-09-13 11:03	27.11	OK	4350	2026-09-13 11:04	24.97	OK
4351	2026-09-13 11:05	26.31	OK	4352	2026-09-13 11:06	25.76	OK
4353	2026-09-13 11:07	25.35	OK	4354	2026-09-13 11:08	25.22	OK
4355	2026-09-13 11:09	26.37	OK	4356	2026-09-13 11:10	26.00	OK
4357	2026-09-13 11:11	25.84	OK	4358	2026-09-13 11:12	25.64	OK
4359	2026-09-13 11:13	25.79	OK	4360	2026-09-13 11:14	25.43	OK
4361	2026-09-13 11:15	25.31	OK	4362	2026-09-13 11:16	25.21	OK
4363	2026-09-13 11:17	26.77	OK	4364	2026-09-13 11:18	25.77	OK
4365	2026-09-13 11:19	26.44	OK	4366	2026-09-13 11:20	26.84	OK
4367	2026-09-13 11:21	25.65	OK	4368	2026-09-13 11:22	25.70	OK
4369	2026-09-13 11:23	25.66	OK	4370	2026-09-13 11:24	25.36	OK
4371	2026-09-13 11:25	26.48	OK	4372	2026-09-13 11:26	25.13	OK
4373	2026-09-13 11:27	26.22	OK	4374	2026-09-13 11:28	26.36	OK
4375	2026-09-13 11:29	25.05	OK	4376	2026-09-13 11:30	25.46	OK
4377	2026-09-13 11:31	25.62	OK	4378	2026-09-13 11:32	26.71	OK
4379	2026-09-13 11:33	26.34	OK	4380	2026-09-13 11:34	26.92	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4381	2026-09-13 11:35	26.61	OK	4382	2026-09-13 11:36	25.78	OK
4383	2026-09-13 11:37	26.45	OK	4384	2026-09-13 11:38	26.52	OK
4385	2026-09-13 11:39	26.34	OK	4386	2026-09-13 11:40	26.49	OK
4387	2026-09-13 11:41	26.55	OK	4388	2026-09-13 11:42	25.25	OK
4389	2026-09-13 11:43	25.01	OK	4390	2026-09-13 11:44	25.71	OK
4391	2026-09-13 11:45	25.42	OK	4392	2026-09-13 11:46	26.60	OK
4393	2026-09-13 11:47	26.97	OK	4394	2026-09-13 11:48	26.12	OK
4395	2026-09-13 11:49	26.45	OK	4396	2026-09-13 11:50	25.82	OK
4397	2026-09-13 11:51	26.65	OK	4398	2026-09-13 11:52	25.74	OK
4399	2026-09-13 11:53	25.60	OK	4400	2026-09-13 11:54	25.89	OK
4401	2026-09-13 11:55	25.90	OK	4402	2026-09-13 11:56	26.47	OK
4403	2026-09-13 11:57	26.13	OK	4404	2026-09-13 11:58	25.94	OK
4405	2026-09-13 11:59	25.64	OK	4406	2026-09-13 12:00	25.76	OK
4407	2026-09-13 12:01	24.78	OK	4408	2026-09-13 12:02	25.25	OK
4409	2026-09-13 12:03	25.60	OK	4410	2026-09-13 12:04	27.37	OK
4411	2026-09-13 12:05	25.84	OK	4412	2026-09-13 12:06	25.54	OK
4413	2026-09-13 12:07	24.47	OK	4414	2026-09-13 12:08	25.97	OK
4415	2026-09-13 12:09	26.14	OK	4416	2026-09-13 12:10	25.32	OK
4417	2026-09-13 12:11	25.74	OK	4418	2026-09-13 12:12	25.86	OK
4419	2026-09-13 12:13	25.99	OK	4420	2026-09-13 12:14	25.59	OK
4421	2026-09-13 12:15	26.60	OK	4422	2026-09-13 12:16	26.31	OK
4423	2026-09-13 12:17	23.99	OK	4424	2026-09-13 12:18	26.73	OK
4425	2026-09-13 12:19	27.18	OK	4426	2026-09-13 12:20	26.63	OK
4427	2026-09-13 12:21	25.51	OK	4428	2026-09-13 12:22	25.91	OK
4429	2026-09-13 12:23	26.90	OK	4430	2026-09-13 12:24	25.38	OK
4431	2026-09-13 12:25	26.14	OK	4432	2026-09-13 12:26	24.77	OK
4433	2026-09-13 12:27	24.53	OK	4434	2026-09-13 12:28	26.26	OK
4435	2026-09-13 12:29	23.99	OK	4436	2026-09-13 12:30	25.22	OK
4437	2026-09-13 12:31	24.63	OK	4438	2026-09-13 12:32	26.19	OK
4439	2026-09-13 12:33	26.89	OK	4440	2026-09-13 12:34	26.40	OK
4441	2026-09-13 12:35	26.22	OK	4442	2026-09-13 12:36	25.38	OK
4443	2026-09-13 12:37	26.05	OK	4444	2026-09-13 12:38	26.31	OK
4445	2026-09-13 12:39	26.30	OK	4446	2026-09-13 12:40	24.69	OK
4447	2026-09-13 12:41	27.77	OK	4448	2026-09-13 12:42	25.92	OK
4449	2026-09-13 12:43	26.56	OK	4450	2026-09-13 12:44	26.34	OK
4451	2026-09-13 12:45	27.41	OK	4452	2026-09-13 12:46	25.16	OK
4453	2026-09-13 12:47	26.03	OK	4454	2026-09-13 12:48	25.23	OK
4455	2026-09-13 12:49	25.97	OK	4456	2026-09-13 12:50	25.19	OK
4457	2026-09-13 12:51	25.83	OK	4458	2026-09-13 12:52	25.53	OK
4459	2026-09-13 12:53	25.41	OK	4460	2026-09-13 12:54	26.11	OK
4461	2026-09-13 12:55	25.98	OK	4462	2026-09-13 12:56	23.90	OK
4463	2026-09-13 12:57	27.09	OK	4464	2026-09-13 12:58	25.05	OK
4465	2026-09-13 12:59	25.16	OK	4466	2026-09-13 13:00	25.59	OK
4467	2026-09-13 13:01	25.12	OK	4468	2026-09-13 13:02	25.86	OK
4469	2026-09-13 13:03	25.47	OK	4470	2026-09-13 13:04	26.29	OK
4471	2026-09-13 13:05	25.04	OK	4472	2026-09-13 13:06	25.11	OK
4473	2026-09-13 13:07	25.26	OK	4474	2026-09-13 13:08	25.79	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4475	2026-09-13 13:09	24.54	OK	4476	2026-09-13 13:10	25.79	OK
4477	2026-09-13 13:11	25.43	OK	4478	2026-09-13 13:12	24.48	OK
4479	2026-09-13 13:13	26.99	OK	4480	2026-09-13 13:14	26.40	OK
4481	2026-09-13 13:15	26.50	OK	4482	2026-09-13 13:16	24.92	OK
4483	2026-09-13 13:17	25.87	OK	4484	2026-09-13 13:18	25.52	OK
4485	2026-09-13 13:19	26.95	OK	4486	2026-09-13 13:20	25.47	OK
4487	2026-09-13 13:21	26.48	OK	4488	2026-09-13 13:22	25.63	OK
4489	2026-09-13 13:23	26.01	OK	4490	2026-09-13 13:24	26.13	OK
4491	2026-09-13 13:25	25.29	OK	4492	2026-09-13 13:26	25.93	OK
4493	2026-09-13 13:27	25.84	OK	4494	2026-09-13 13:28	25.18	OK
4495	2026-09-13 13:29	25.61	OK	4496	2026-09-13 13:30	26.20	OK
4497	2026-09-13 13:31	25.74	OK	4498	2026-09-13 13:32	25.88	OK
4499	2026-09-13 13:33	26.43	OK	4500	2026-09-13 13:34	25.11	OK
4501	2026-09-13 13:35	26.44	OK	4502	2026-09-13 13:36	25.35	OK
4503	2026-09-13 13:37	26.05	OK	4504	2026-09-13 13:38	25.47	OK
4505	2026-09-13 13:39	27.26	OK	4506	2026-09-13 13:40	27.20	OK
4507	2026-09-13 13:41	25.53	OK	4508	2026-09-13 13:42	26.91	OK
4509	2026-09-13 13:43	25.27	OK	4510	2026-09-13 13:44	27.17	OK
4511	2026-09-13 13:45	26.99	OK	4512	2026-09-13 13:46	26.74	OK
4513	2026-09-13 13:47	25.62	OK	4514	2026-09-13 13:48	24.91	OK
4515	2026-09-13 13:49	26.65	OK	4516	2026-09-13 13:50	26.29	OK
4517	2026-09-13 13:51	25.39	OK	4518	2026-09-13 13:52	26.78	OK
4519	2026-09-13 13:53	25.99	OK	4520	2026-09-13 13:54	25.11	OK
4521	2026-09-13 13:55	25.81	OK	4522	2026-09-13 13:56	26.75	OK
4523	2026-09-13 13:57	25.09	OK	4524	2026-09-13 13:58	24.88	OK
4525	2026-09-13 13:59	24.91	OK	4526	2026-09-13 14:00	26.59	OK
4527	2026-09-13 14:01	24.62	OK	4528	2026-09-13 14:02	26.82	OK
4529	2026-09-13 14:03	25.00	OK	4530	2026-09-13 14:04	25.73	OK
4531	2026-09-13 14:05	25.74	OK	4532	2026-09-13 14:06	26.29	OK
4533	2026-09-13 14:07	25.72	OK	4534	2026-09-13 14:08	25.23	OK
4535	2026-09-13 14:09	25.73	OK	4536	2026-09-13 14:10	25.93	OK
4537	2026-09-13 14:11	25.53	OK	4538	2026-09-13 14:12	26.32	OK
4539	2026-09-13 14:13	23.95	OK	4540	2026-09-13 14:14	25.79	OK
4541	2026-09-13 14:15	24.21	OK	4542	2026-09-13 14:16	24.87	OK
4543	2026-09-13 14:17	26.98	OK	4544	2026-09-13 14:18	25.57	OK
4545	2026-09-13 14:19	26.40	OK	4546	2026-09-13 14:20	25.25	OK
4547	2026-09-13 14:21	25.41	OK	4548	2026-09-13 14:22	25.63	OK
4549	2026-09-13 14:23	25.01	OK	4550	2026-09-13 14:24	26.20	OK
4551	2026-09-13 14:25	25.27	OK	4552	2026-09-13 14:26	25.93	OK
4553	2026-09-13 14:27	25.88	OK	4554	2026-09-13 14:28	26.92	OK
4555	2026-09-13 14:29	25.08	OK	4556	2026-09-13 14:30	24.97	OK
4557	2026-09-13 14:31	27.31	OK	4558	2026-09-13 14:32	25.71	OK
4559	2026-09-13 14:33	25.90	OK	4560	2026-09-13 14:34	26.13	OK
4561	2026-09-13 14:35	26.87	OK	4562	2026-09-13 14:36	25.61	OK
4563	2026-09-13 14:37	26.81	OK	4564	2026-09-13 14:38	25.45	OK
4565	2026-09-13 14:39	27.02	OK	4566	2026-09-13 14:40	26.38	OK
4567	2026-09-13 14:41	25.31	OK	4568	2026-09-13 14:42	25.09	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4569	2026-09-13 14:43	27.10	OK	4570	2026-09-13 14:44	23.95	OK
4571	2026-09-13 14:45	26.97	OK	4572	2026-09-13 14:46	26.18	OK
4573	2026-09-13 14:47	26.57	OK	4574	2026-09-13 14:48	24.67	OK
4575	2026-09-13 14:49	26.80	OK	4576	2026-09-13 14:50	25.00	OK
4577	2026-09-13 14:51	24.35	OK	4578	2026-09-13 14:52	25.53	OK
4579	2026-09-13 14:53	27.48	OK	4580	2026-09-13 14:54	25.65	OK
4581	2026-09-13 14:55	26.36	OK	4582	2026-09-13 14:56	25.62	OK
4583	2026-09-13 14:57	26.54	OK	4584	2026-09-13 14:58	25.18	OK
4585	2026-09-13 14:59	26.33	OK	4586	2026-09-13 15:00	24.41	OK
4587	2026-09-13 15:01	26.24	OK	4588	2026-09-13 15:02	25.29	OK
4589	2026-09-13 15:03	24.53	OK	4590	2026-09-13 15:04	27.09	OK
4591	2026-09-13 15:05	26.24	OK	4592	2026-09-13 15:06	24.50	OK
4593	2026-09-13 15:07	26.35	OK	4594	2026-09-13 15:08	26.68	OK
4595	2026-09-13 15:09	25.87	OK	4596	2026-09-13 15:10	25.87	OK
4597	2026-09-13 15:11	25.40	OK	4598	2026-09-13 15:12	24.98	OK
4599	2026-09-13 15:13	26.34	OK	4600	2026-09-13 15:14	26.17	OK
4601	2026-09-13 15:15	24.72	OK	4602	2026-09-13 15:16	25.35	OK
4603	2026-09-13 15:17	24.64	OK	4604	2026-09-13 15:18	25.87	OK
4605	2026-09-13 15:19	27.14	OK	4606	2026-09-13 15:20	26.29	OK
4607	2026-09-13 15:21	27.09	OK	4608	2026-09-13 15:22	28.08	OK
4609	2026-09-13 15:23	27.47	OK	4610	2026-09-13 15:24	27.60	OK
4611	2026-09-13 15:25	25.34	OK	4612	2026-09-13 15:26	27.06	OK
4613	2026-09-13 15:27	26.95	OK	4614	2026-09-13 15:28	26.47	OK
4615	2026-09-13 15:29	27.46	OK	4616	2026-09-13 15:30	25.18	OK
4617	2026-09-13 15:31	24.97	OK	4618	2026-09-13 15:32	27.45	OK
4619	2026-09-13 15:33	27.62	OK	4620	2026-09-13 15:34	27.08	OK
4621	2026-09-13 15:35	26.96	OK	4622	2026-09-13 15:36	24.95	OK
4623	2026-09-13 15:37	26.26	OK	4624	2026-09-13 15:38	24.68	OK
4625	2026-09-13 15:39	27.22	OK	4626	2026-09-13 15:40	27.30	OK
4627	2026-09-13 15:41	26.63	OK	4628	2026-09-13 15:42	24.51	OK
4629	2026-09-13 15:43	27.36	OK	4630	2026-09-13 15:44	26.34	OK
4631	2026-09-13 15:45	26.60	OK	4632	2026-09-13 15:46	27.13	OK
4633	2026-09-13 15:47	26.36	OK	4634	2026-09-13 15:48	26.69	OK
4635	2026-09-13 15:49	26.81	OK	4636	2026-09-13 15:50	26.15	OK
4637	2026-09-13 15:51	26.17	OK	4638	2026-09-13 15:52	25.87	OK
4639	2026-09-13 15:53	26.80	OK	4640	2026-09-13 15:54	25.61	OK
4641	2026-09-13 15:55	25.56	OK	4642	2026-09-13 15:56	25.95	OK
4643	2026-09-13 15:57	26.22	OK	4644	2026-09-13 15:58	25.38	OK
4645	2026-09-13 15:59	25.05	OK	4646	2026-09-13 16:00	27.23	OK
4647	2026-09-13 16:01	26.38	OK	4648	2026-09-13 16:02	25.50	OK
4649	2026-09-13 16:03	26.93	OK	4650	2026-09-13 16:04	26.36	OK
4651	2026-09-13 16:05	26.99	OK	4652	2026-09-13 16:06	26.04	OK
4653	2026-09-13 16:07	25.66	OK	4654	2026-09-13 16:08	25.41	OK
4655	2026-09-13 16:09	26.23	OK	4656	2026-09-13 16:10	24.73	OK
4657	2026-09-13 16:11	26.71	OK	4658	2026-09-13 16:12	25.94	OK
4659	2026-09-13 16:13	25.91	OK	4660	2026-09-13 16:14	26.86	OK
4661	2026-09-13 16:15	27.19	OK	4662	2026-09-13 16:16	26.88	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4663	2026-09-13 16:17	25.72	OK	4664	2026-09-13 16:18	25.69	OK
4665	2026-09-13 16:19	25.30	OK	4666	2026-09-13 16:20	27.20	OK
4667	2026-09-13 16:21	25.19	OK	4668	2026-09-13 16:22	25.59	OK
4669	2026-09-13 16:23	27.39	OK	4670	2026-09-13 16:24	26.72	OK
4671	2026-09-13 16:25	27.92	OK	4672	2026-09-13 16:26	25.64	OK
4673	2026-09-13 16:27	25.86	OK	4674	2026-09-13 16:28	24.97	OK
4675	2026-09-13 16:29	26.07	OK	4676	2026-09-13 16:30	25.43	OK
4677	2026-09-13 16:31	27.92	OK	4678	2026-09-13 16:32	26.76	OK
4679	2026-09-13 16:33	24.53	OK	4680	2026-09-13 16:34	26.14	OK
4681	2026-09-13 16:35	25.80	OK	4682	2026-09-13 16:36	26.96	OK
4683	2026-09-13 16:37	25.26	OK	4684	2026-09-13 16:38	27.75	OK
4685	2026-09-13 16:39	27.02	OK	4686	2026-09-13 16:40	26.75	OK
4687	2026-09-13 16:41	26.34	OK	4688	2026-09-13 16:42	26.73	OK
4689	2026-09-13 16:43	27.61	OK	4690	2026-09-13 16:44	26.84	OK
4691	2026-09-13 16:45	26.67	OK	4692	2026-09-13 16:46	26.59	OK
4693	2026-09-13 16:47	25.97	OK	4694	2026-09-13 16:48	26.10	OK
4695	2026-09-13 16:49	26.38	OK	4696	2026-09-13 16:50	26.17	OK
4697	2026-09-13 16:51	25.54	OK	4698	2026-09-13 16:52	25.31	OK
4699	2026-09-13 16:53	27.21	OK	4700	2026-09-13 16:54	25.63	OK
4701	2026-09-13 16:55	26.89	OK	4702	2026-09-13 16:56	25.56	OK
4703	2026-09-13 16:57	27.97	OK	4704	2026-09-13 16:58	26.85	OK
4705	2026-09-13 16:59	27.17	OK	4706	2026-09-13 17:00	26.36	OK
4707	2026-09-13 17:01	26.32	OK	4708	2026-09-13 17:02	26.77	OK
4709	2026-09-13 17:03	27.42	OK	4710	2026-09-13 17:04	26.98	OK
4711	2026-09-13 17:05	26.93	OK	4712	2026-09-13 17:06	26.33	OK
4713	2026-09-13 17:07	27.09	OK	4714	2026-09-13 17:08	27.14	OK
4715	2026-09-13 17:09	26.45	OK	4716	2026-09-13 17:10	26.23	OK
4717	2026-09-13 17:11	26.61	OK	4718	2026-09-13 17:12	26.99	OK
4719	2026-09-13 17:13	26.99	OK	4720	2026-09-13 17:14	25.67	OK
4721	2026-09-13 17:15	27.65	OK	4722	2026-09-13 17:16	27.11	OK
4723	2026-09-13 17:17	26.65	OK	4724	2026-09-13 17:18	26.98	OK
4725	2026-09-13 17:19	27.66	OK	4726	2026-09-13 17:20	26.45	OK
4727	2026-09-13 17:21	27.31	OK	4728	2026-09-13 17:22	27.39	OK
4729	2026-09-13 17:23	26.30	OK	4730	2026-09-13 17:24	27.02	OK
4731	2026-09-13 17:25	28.07	OK	4732	2026-09-13 17:26	25.69	OK
4733	2026-09-13 17:27	26.29	OK	4734	2026-09-13 17:28	25.50	OK
4735	2026-09-13 17:29	26.51	OK	4736	2026-09-13 17:30	26.58	OK
4737	2026-09-13 17:31	25.44	OK	4738	2026-09-13 17:32	26.82	OK
4739	2026-09-13 17:33	26.33	OK	4740	2026-09-13 17:34	27.97	OK
4741	2026-09-13 17:35	27.14	OK	4742	2026-09-13 17:36	28.53	OK
4743	2026-09-13 17:37	27.50	OK	4744	2026-09-13 17:38	26.64	OK
4745	2026-09-13 17:39	28.09	OK	4746	2026-09-13 17:40	27.13	OK
4747	2026-09-13 17:41	27.79	OK	4748	2026-09-13 17:42	27.50	OK
4749	2026-09-13 17:43	26.82	OK	4750	2026-09-13 17:44	28.67	OK
4751	2026-09-13 17:45	27.56	OK	4752	2026-09-13 17:46	27.58	OK
4753	2026-09-13 17:47	27.12	OK	4754	2026-09-13 17:48	26.58	OK
4755	2026-09-13 17:49	26.75	OK	4756	2026-09-13 17:50	26.65	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4757	2026-09-13 17:51	26.61	OK	4758	2026-09-13 17:52	26.01	OK
4759	2026-09-13 17:53	27.86	OK	4760	2026-09-13 17:54	26.25	OK
4761	2026-09-13 17:55	27.30	OK	4762	2026-09-13 17:56	27.87	OK
4763	2026-09-13 17:57	26.40	OK	4764	2026-09-13 17:58	26.45	OK
4765	2026-09-13 17:59	27.17	OK	4766	2026-09-13 18:00	26.52	OK
4767	2026-09-13 18:01	26.44	OK	4768	2026-09-13 18:02	26.69	OK
4769	2026-09-13 18:03	27.94	OK	4770	2026-09-13 18:04	28.37	OK
4771	2026-09-13 18:05	27.21	OK	4772	2026-09-13 18:06	26.48	OK
4773	2026-09-13 18:07	27.07	OK	4774	2026-09-13 18:08	26.71	OK
4775	2026-09-13 18:09	26.84	OK	4776	2026-09-13 18:10	27.77	OK
4777	2026-09-13 18:11	26.59	OK	4778	2026-09-13 18:12	27.56	OK
4779	2026-09-13 18:13	26.99	OK	4780	2026-09-13 18:14	26.81	OK
4781	2026-09-13 18:15	27.69	OK	4782	2026-09-13 18:16	25.59	OK
4783	2026-09-13 18:17	28.92	OK	4784	2026-09-13 18:18	28.27	OK
4785	2026-09-13 18:19	26.28	OK	4786	2026-09-13 18:20	26.52	OK
4787	2026-09-13 18:21	27.65	OK	4788	2026-09-13 18:22	27.41	OK
4789	2026-09-13 18:23	25.87	OK	4790	2026-09-13 18:24	28.43	OK
4791	2026-09-13 18:25	28.28	OK	4792	2026-09-13 18:26	26.51	OK
4793	2026-09-13 18:27	26.40	OK	4794	2026-09-13 18:28	28.77	OK
4795	2026-09-13 18:29	28.80	OK	4796	2026-09-13 18:30	26.74	OK
4797	2026-09-13 18:31	27.57	OK	4798	2026-09-13 18:32	28.04	OK
4799	2026-09-13 18:33	27.78	OK	4800	2026-09-13 18:34	28.63	OK
4801	2026-09-13 18:35	26.75	OK	4802	2026-09-13 18:36	28.04	OK
4803	2026-09-13 18:37	26.10	OK	4804	2026-09-13 18:38	28.14	OK
4805	2026-09-13 18:39	27.83	OK	4806	2026-09-13 18:40	27.44	OK
4807	2026-09-13 18:41	27.08	OK	4808	2026-09-13 18:42	26.87	OK
4809	2026-09-13 18:43	26.45	OK	4810	2026-09-13 18:44	28.05	OK
4811	2026-09-13 18:45	26.18	OK	4812	2026-09-13 18:46	26.68	OK
4813	2026-09-13 18:47	28.59	OK	4814	2026-09-13 18:48	27.13	OK
4815	2026-09-13 18:49	28.27	OK	4816	2026-09-13 18:50	26.19	OK
4817	2026-09-13 18:51	27.74	OK	4818	2026-09-13 18:52	28.22	OK
4819	2026-09-13 18:53	27.33	OK	4820	2026-09-13 18:54	28.15	OK
4821	2026-09-13 18:55	28.06	OK	4822	2026-09-13 18:56	26.64	OK
4823	2026-09-13 18:57	27.55	OK	4824	2026-09-13 18:58	27.21	OK
4825	2026-09-13 18:59	28.15	OK	4826	2026-09-13 19:00	28.57	OK
4827	2026-09-13 19:01	27.86	OK	4828	2026-09-13 19:02	26.87	OK
4829	2026-09-13 19:03	26.58	OK	4830	2026-09-13 19:04	28.52	OK
4831	2026-09-13 19:05	29.18	OK	4832	2026-09-13 19:06	27.67	OK
4833	2026-09-13 19:07	27.35	OK	4834	2026-09-13 19:08	27.60	OK
4835	2026-09-13 19:09	27.30	OK	4836	2026-09-13 19:10	27.60	OK
4837	2026-09-13 19:11	27.54	OK	4838	2026-09-13 19:12	26.96	OK
4839	2026-09-13 19:13	28.84	OK	4840	2026-09-13 19:14	28.59	OK
4841	2026-09-13 19:15	26.99	OK	4842	2026-09-13 19:16	28.69	OK
4843	2026-09-13 19:17	27.74	OK	4844	2026-09-13 19:18	28.51	OK
4845	2026-09-13 19:19	29.22	OK	4846	2026-09-13 19:20	27.11	OK
4847	2026-09-13 19:21	27.67	OK	4848	2026-09-13 19:22	27.68	OK
4849	2026-09-13 19:23	27.45	OK	4850	2026-09-13 19:24	29.22	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4851	2026-09-13 19:25	27.28	OK	4852	2026-09-13 19:26	27.94	OK
4853	2026-09-13 19:27	28.51	OK	4854	2026-09-13 19:28	27.43	OK
4855	2026-09-13 19:29	28.14	OK	4856	2026-09-13 19:30	28.29	OK
4857	2026-09-13 19:31	28.11	OK	4858	2026-09-13 19:32	28.62	OK
4859	2026-09-13 19:33	29.74	OK	4860	2026-09-13 19:34	28.18	OK
4861	2026-09-13 19:35	27.85	OK	4862	2026-09-13 19:36	27.99	OK
4863	2026-09-13 19:37	28.38	OK	4864	2026-09-13 19:38	29.03	OK
4865	2026-09-13 19:39	29.68	OK	4866	2026-09-13 19:40	29.32	OK
4867	2026-09-13 19:41	29.35	OK	4868	2026-09-13 19:42	28.16	OK
4869	2026-09-13 19:43	28.51	OK	4870	2026-09-13 19:44	28.48	OK
4871	2026-09-13 19:45	26.84	OK	4872	2026-09-13 19:46	28.37	OK
4873	2026-09-13 19:47	29.05	OK	4874	2026-09-13 19:48	28.69	OK
4875	2026-09-13 19:49	27.51	OK	4876	2026-09-13 19:50	27.90	OK
4877	2026-09-13 19:51	28.89	OK	4878	2026-09-13 19:52	27.03	OK
4879	2026-09-13 19:53	27.73	OK	4880	2026-09-13 19:54	29.83	OK
4881	2026-09-13 19:55	28.66	OK	4882	2026-09-13 19:56	29.75	OK
4883	2026-09-13 19:57	28.98	OK	4884	2026-09-13 19:58	29.17	OK
4885	2026-09-13 19:59	28.66	OK	4886	2026-09-13 20:00	28.70	OK
4887	2026-09-13 20:01	30.12	OK	4888	2026-09-13 20:02	27.56	OK
4889	2026-09-13 20:03	28.47	OK	4890	2026-09-13 20:04	28.59	OK
4891	2026-09-13 20:05	27.93	OK	4892	2026-09-13 20:06	28.44	OK
4893	2026-09-13 20:07	27.84	OK	4894	2026-09-13 20:08	28.01	OK
4895	2026-09-13 20:09	29.87	OK	4896	2026-09-13 20:10	28.68	OK
4897	2026-09-13 20:11	28.37	OK	4898	2026-09-13 20:12	27.20	OK
4899	2026-09-13 20:13	29.06	OK	4900	2026-09-13 20:14	29.18	OK
4901	2026-09-13 20:15	27.39	OK	4902	2026-09-13 20:16	26.55	OK
4903	2026-09-13 20:17	28.28	OK	4904	2026-09-13 20:18	28.85	OK
4905	2026-09-13 20:19	29.68	OK	4906	2026-09-13 20:20	29.01	OK
4907	2026-09-13 20:21	27.71	OK	4908	2026-09-13 20:22	27.72	OK
4909	2026-09-13 20:23	27.59	OK	4910	2026-09-13 20:24	27.58	OK
4911	2026-09-13 20:25	26.97	OK	4912	2026-09-13 20:26	28.20	OK
4913	2026-09-13 20:27	27.48	OK	4914	2026-09-13 20:28	27.66	OK
4915	2026-09-13 20:29	29.68	OK	4916	2026-09-13 20:30	28.88	OK
4917	2026-09-13 20:31	28.52	OK	4918	2026-09-13 20:32	28.91	OK
4919	2026-09-13 20:33	27.70	OK	4920	2026-09-13 20:34	27.80	OK
4921	2026-09-13 20:35	28.60	OK	4922	2026-09-13 20:36	28.38	OK
4923	2026-09-13 20:37	29.23	OK	4924	2026-09-13 20:38	28.74	OK
4925	2026-09-13 20:39	29.88	OK	4926	2026-09-13 20:40	29.26	OK
4927	2026-09-13 20:41	28.80	OK	4928	2026-09-13 20:42	27.73	OK
4929	2026-09-13 20:43	28.90	OK	4930	2026-09-13 20:44	30.65	OK
4931	2026-09-13 20:45	28.34	OK	4932	2026-09-13 20:46	27.12	OK
4933	2026-09-13 20:47	27.76	OK	4934	2026-09-13 20:48	29.17	OK
4935	2026-09-13 20:49	28.23	OK	4936	2026-09-13 20:50	29.50	OK
4937	2026-09-13 20:51	28.91	OK	4938	2026-09-13 20:52	30.41	OK
4939	2026-09-13 20:53	29.52	OK	4940	2026-09-13 20:54	28.90	OK
4941	2026-09-13 20:55	28.16	OK	4942	2026-09-13 20:56	27.97	OK
4943	2026-09-13 20:57	27.65	OK	4944	2026-09-13 20:58	29.00	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
4945	2026-09-13 20:59	28.39	OK	4946	2026-09-13 21:00	30.15	OK
4947	2026-09-13 21:01	29.17	OK	4948	2026-09-13 21:02	28.52	OK
4949	2026-09-13 21:03	28.16	OK	4950	2026-09-13 21:04	28.68	OK
4951	2026-09-13 21:05	30.32	OK	4952	2026-09-13 21:06	27.71	OK
4953	2026-09-13 21:07	28.71	OK	4954	2026-09-13 21:08	28.54	OK
4955	2026-09-13 21:09	28.23	OK	4956	2026-09-13 21:10	28.49	OK
4957	2026-09-13 21:11	29.01	OK	4958	2026-09-13 21:12	29.75	OK
4959	2026-09-13 21:13	29.96	OK	4960	2026-09-13 21:14	29.57	OK
4961	2026-09-13 21:15	29.28	OK	4962	2026-09-13 21:16	28.30	OK
4963	2026-09-13 21:17	29.53	OK	4964	2026-09-13 21:18	27.75	OK
4965	2026-09-13 21:19	28.54	OK	4966	2026-09-13 21:20	28.85	OK
4967	2026-09-13 21:21	30.20	OK	4968	2026-09-13 21:22	28.82	OK
4969	2026-09-13 21:23	30.44	OK	4970	2026-09-13 21:24	28.26	OK
4971	2026-09-13 21:25	30.34	OK	4972	2026-09-13 21:26	29.83	OK
4973	2026-09-13 21:27	29.02	OK	4974	2026-09-13 21:28	29.40	OK
4975	2026-09-13 21:29	29.22	OK	4976	2026-09-13 21:30	29.57	OK
4977	2026-09-13 21:31	29.82	OK	4978	2026-09-13 21:32	29.35	OK
4979	2026-09-13 21:33	29.55	OK	4980	2026-09-13 21:34	29.88	OK
4981	2026-09-13 21:35	29.12	OK	4982	2026-09-13 21:36	30.05	OK
4983	2026-09-13 21:37	29.59	OK	4984	2026-09-13 21:38	28.96	OK
4985	2026-09-13 21:39	29.79	OK	4986	2026-09-13 21:40	28.69	OK
4987	2026-09-13 21:41	28.61	OK	4988	2026-09-13 21:42	29.01	OK
4989	2026-09-13 21:43	30.51	OK	4990	2026-09-13 21:44	29.75	OK
4991	2026-09-13 21:45	29.18	OK	4992	2026-09-13 21:46	29.75	OK
4993	2026-09-13 21:47	29.24	OK	4994	2026-09-13 21:48	28.35	OK
4995	2026-09-13 21:49	28.77	OK	4996	2026-09-13 21:50	30.31	OK
4997	2026-09-13 21:51	28.60	OK	4998	2026-09-13 21:52	30.17	OK
4999	2026-09-13 21:53	30.30	OK	5000	2026-09-13 21:54	29.94	OK
5001	2026-09-13 21:55	29.15	OK	5002	2026-09-13 21:56	29.02	OK
5003	2026-09-13 21:57	29.39	OK	5004	2026-09-13 21:58	28.95	OK
5005	2026-09-13 21:59	29.44	OK	5006	2026-09-13 22:00	29.77	OK
5007	2026-09-13 22:01	28.52	OK	5008	2026-09-13 22:02	28.88	OK
5009	2026-09-13 22:03	29.70	OK	5010	2026-09-13 22:04	28.10	OK
5011	2026-09-13 22:05	28.50	OK	5012	2026-09-13 22:06	28.80	OK
5013	2026-09-13 22:07	30.19	OK	5014	2026-09-13 22:08	29.88	OK
5015	2026-09-13 22:09	28.06	OK	5016	2026-09-13 22:10	28.14	OK
5017	2026-09-13 22:11	29.75	OK	5018	2026-09-13 22:12	30.75	OK
5019	2026-09-13 22:13	29.27	OK	5020	2026-09-13 22:14	29.07	OK
5021	2026-09-13 22:15	29.55	OK	5022	2026-09-13 22:16	30.62	OK
5023	2026-09-13 22:17	30.60	OK	5024	2026-09-13 22:18	31.01	OK
5025	2026-09-13 22:19	28.86	OK	5026	2026-09-13 22:20	30.67	OK
5027	2026-09-13 22:21	30.08	OK	5028	2026-09-13 22:22	29.90	OK
5029	2026-09-13 22:23	30.19	OK	5030	2026-09-13 22:24	28.61	OK
5031	2026-09-13 22:25	30.27	OK	5032	2026-09-13 22:26	30.64	OK
5033	2026-09-13 22:27	29.69	OK	5034	2026-09-13 22:28	29.43	OK
5035	2026-09-13 22:29	29.79	OK	5036	2026-09-13 22:30	28.76	OK
5037	2026-09-13 22:31	28.85	OK	5038	2026-09-13 22:32	30.52	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5039	2026-09-13 22:33	29.01	OK	5040	2026-09-13 22:34	30.57	OK
5041	2026-09-13 22:35	30.64	OK	5042	2026-09-13 22:36	29.46	OK
5043	2026-09-13 22:37	29.78	OK	5044	2026-09-13 22:38	29.45	OK
5045	2026-09-13 22:39	29.64	OK	5046	2026-09-13 22:40	29.73	OK
5047	2026-09-13 22:41	29.18	OK	5048	2026-09-13 22:42	29.72	OK
5049	2026-09-13 22:43	29.83	OK	5050	2026-09-13 22:44	30.51	OK
5051	2026-09-13 22:45	31.10	OK	5052	2026-09-13 22:46	30.33	OK
5053	2026-09-13 22:47	28.99	OK	5054	2026-09-13 22:48	30.50	OK
5055	2026-09-13 22:49	28.83	OK	5056	2026-09-13 22:50	29.86	OK
5057	2026-09-13 22:51	28.34	OK	5058	2026-09-13 22:52	29.77	OK
5059	2026-09-13 22:53	30.03	OK	5060	2026-09-13 22:54	29.98	OK
5061	2026-09-13 22:55	29.03	OK	5062	2026-09-13 22:56	29.83	OK
5063	2026-09-13 22:57	29.36	OK	5064	2026-09-13 22:58	30.04	OK
5065	2026-09-13 22:59	29.18	OK	5066	2026-09-13 23:00	30.79	OK
5067	2026-09-13 23:01	30.38	OK	5068	2026-09-13 23:02	31.35	OK
5069	2026-09-13 23:03	30.64	OK	5070	2026-09-13 23:04	31.11	OK
5071	2026-09-13 23:05	31.19	OK	5072	2026-09-13 23:06	28.78	OK
5073	2026-09-13 23:07	30.05	OK	5074	2026-09-13 23:08	30.11	OK
5075	2026-09-13 23:09	30.92	OK	5076	2026-09-13 23:10	30.40	OK
5077	2026-09-13 23:11	30.01	OK	5078	2026-09-13 23:12	31.54	OK
5079	2026-09-13 23:13	30.75	OK	5080	2026-09-13 23:14	29.20	OK
5081	2026-09-13 23:15	30.25	OK	5082	2026-09-13 23:16	28.84	OK
5083	2026-09-13 23:17	31.20	OK	5084	2026-09-13 23:18	29.80	OK
5085	2026-09-13 23:19	30.29	OK	5086	2026-09-13 23:20	30.81	OK
5087	2026-09-13 23:21	30.94	OK	5088	2026-09-13 23:22	30.29	OK
5089	2026-09-13 23:23	30.70	OK	5090	2026-09-13 23:24	30.56	OK
5091	2026-09-13 23:25	30.09	OK	5092	2026-09-13 23:26	30.06	OK
5093	2026-09-13 23:27	28.18	OK	5094	2026-09-13 23:28	31.58	OK
5095	2026-09-13 23:29	30.11	OK	5096	2026-09-13 23:30	30.99	OK
5097	2026-09-13 23:31	29.84	OK	5098	2026-09-13 23:32	30.09	OK
5099	2026-09-13 23:33	30.53	OK	5100	2026-09-13 23:34	30.66	OK
5101	2026-09-13 23:35	29.65	OK	5102	2026-09-13 23:36	29.93	OK
5103	2026-09-13 23:37	28.97	OK	5104	2026-09-13 23:38	30.97	OK
5105	2026-09-13 23:39	29.82	OK	5106	2026-09-13 23:40	29.61	OK
5107	2026-09-13 23:41	29.40	OK	5108	2026-09-13 23:42	29.72	OK
5109	2026-09-13 23:43	31.57	OK	5110	2026-09-13 23:44	31.17	OK
5111	2026-09-13 23:45	29.77	OK	5112	2026-09-13 23:46	30.84	OK
5113	2026-09-13 23:47	29.58	OK	5114	2026-09-13 23:48	28.29	OK
5115	2026-09-13 23:49	29.93	OK	5116	2026-09-13 23:50	29.69	OK
5117	2026-09-13 23:51	30.16	OK	5118	2026-09-13 23:52	28.74	OK
5119	2026-09-13 23:53	31.13	OK	5120	2026-09-13 23:54	30.24	OK
5121	2026-09-13 23:55	28.50	OK	5122	2026-09-13 23:56	30.62	OK
5123	2026-09-13 23:57	30.25	OK	5124	2026-09-13 23:58	30.50	OK
5125	2026-09-13 23:59	29.52	OK	5126	2026-09-14 00:00	29.32	OK
5127	2026-09-14 00:01	30.05	OK	5128	2026-09-14 00:02	30.54	OK
5129	2026-09-14 00:03	30.73	OK	5130	2026-09-14 00:04	29.33	OK
5131	2026-09-14 00:05	29.03	OK	5132	2026-09-14 00:06	30.15	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5133	2026-09-14 00:07	29.04	OK	5134	2026-09-14 00:08	30.85	OK
5135	2026-09-14 00:09	28.86	OK	5136	2026-09-14 00:10	29.00	OK
5137	2026-09-14 00:11	29.78	OK	5138	2026-09-14 00:12	29.60	OK
5139	2026-09-14 00:13	29.56	OK	5140	2026-09-14 00:14	30.91	OK
5141	2026-09-14 00:15	30.66	OK	5142	2026-09-14 00:16	29.66	OK
5143	2026-09-14 00:17	30.36	OK	5144	2026-09-14 00:18	28.98	OK
5145	2026-09-14 00:19	30.48	OK	5146	2026-09-14 00:20	31.15	OK
5147	2026-09-14 00:21	31.16	OK	5148	2026-09-14 00:22	31.28	OK
5149	2026-09-14 00:23	30.16	OK	5150	2026-09-14 00:24	29.71	OK
5151	2026-09-14 00:25	30.33	OK	5152	2026-09-14 00:26	30.13	OK
5153	2026-09-14 00:27	29.19	OK	5154	2026-09-14 00:28	31.12	OK
5155	2026-09-14 00:29	30.22	OK	5156	2026-09-14 00:30	29.54	OK
5157	2026-09-14 00:31	31.73	OK	5158	2026-09-14 00:32	31.22	OK
5159	2026-09-14 00:33	31.12	OK	5160	2026-09-14 00:34	31.39	OK
5161	2026-09-14 00:35	30.47	OK	5162	2026-09-14 00:36	29.36	OK
5163	2026-09-14 00:37	32.22	OK	5164	2026-09-14 00:38	31.76	OK
5165	2026-09-14 00:39	30.44	OK	5166	2026-09-14 00:40	30.66	OK
5167	2026-09-14 00:41	29.27	OK	5168	2026-09-14 00:42	30.49	OK
5169	2026-09-14 00:43	29.03	OK	5170	2026-09-14 00:44	29.74	OK
5171	2026-09-14 00:45	29.90	OK	5172	2026-09-14 00:46	30.61	OK
5173	2026-09-14 00:47	30.71	OK	5174	2026-09-14 00:48	31.32	OK
5175	2026-09-14 00:49	29.76	OK	5176	2026-09-14 00:50	31.27	OK
5177	2026-09-14 00:51	31.93	OK	5178	2026-09-14 00:52	30.63	OK
5179	2026-09-14 00:53	29.64	OK	5180	2026-09-14 00:54	31.23	OK
5181	2026-09-14 00:55	29.55	OK	5182	2026-09-14 00:56	29.23	OK
5183	2026-09-14 00:57	31.35	OK	5184	2026-09-14 00:58	31.11	OK
5185	2026-09-14 00:59	30.91	OK	5186	2026-09-14 01:00	30.47	OK
5187	2026-09-14 01:01	30.14	OK	5188	2026-09-14 01:02	30.41	OK
5189	2026-09-14 01:03	29.18	OK	5190	2026-09-14 01:04	31.37	OK
5191	2026-09-14 01:05	30.08	OK	5192	2026-09-14 01:06	30.70	OK
5193	2026-09-14 01:07	30.49	OK	5194	2026-09-14 01:08	29.71	OK
5195	2026-09-14 01:09	29.91	OK	5196	2026-09-14 01:10	29.63	OK
5197	2026-09-14 01:11	30.13	OK	5198	2026-09-14 01:12	31.27	OK
5199	2026-09-14 01:13	31.45	OK	5200	2026-09-14 01:14	29.84	OK
5201	2026-09-14 01:15	30.42	OK	5202	2026-09-14 01:16	30.93	OK
5203	2026-09-14 01:17	30.40	OK	5204	2026-09-14 01:18	30.56	OK
5205	2026-09-14 01:19	29.83	OK	5206	2026-09-14 01:20	31.10	OK
5207	2026-09-14 01:21	29.66	OK	5208	2026-09-14 01:22	31.14	OK
5209	2026-09-14 01:23	30.67	OK	5210	2026-09-14 01:24	30.59	OK
5211	2026-09-14 01:25	30.86	OK	5212	2026-09-14 01:26	30.78	OK
5213	2026-09-14 01:27	30.99	OK	5214	2026-09-14 01:28	30.58	OK
5215	2026-09-14 01:29	29.79	OK	5216	2026-09-14 01:30	31.33	OK
5217	2026-09-14 01:31	29.64	OK	5218	2026-09-14 01:32	29.80	OK
5219	2026-09-14 01:33	31.09	OK	5220	2026-09-14 01:34	30.93	OK
5221	2026-09-14 01:35	32.21	OK	5222	2026-09-14 01:36	30.81	OK
5223	2026-09-14 01:37	30.14	OK	5224	2026-09-14 01:38	30.45	OK
5225	2026-09-14 01:39	29.23	OK	5226	2026-09-14 01:40	30.02	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5227	2026-09-14 01:41	29.68	OK	5228	2026-09-14 01:42	29.87	OK
5229	2026-09-14 01:43	30.55	OK	5230	2026-09-14 01:44	29.77	OK
5231	2026-09-14 01:45	30.98	OK	5232	2026-09-14 01:46	31.02	OK
5233	2026-09-14 01:47	30.90	OK	5234	2026-09-14 01:48	29.83	OK
5235	2026-09-14 01:49	31.24	OK	5236	2026-09-14 01:50	31.16	OK
5237	2026-09-14 01:51	30.45	OK	5238	2026-09-14 01:52	30.45	OK
5239	2026-09-14 01:53	31.65	OK	5240	2026-09-14 01:54	29.36	OK
5241	2026-09-14 01:55	29.91	OK	5242	2026-09-14 01:56	29.60	OK
5243	2026-09-14 01:57	29.52	OK	5244	2026-09-14 01:58	31.28	OK
5245	2026-09-14 01:59	30.36	OK	5246	2026-09-14 02:00	30.75	OK
5247	2026-09-14 02:01	29.56	OK	5248	2026-09-14 02:02	30.94	OK
5249	2026-09-14 02:03	30.24	OK	5250	2026-09-14 02:04	30.73	OK
5251	2026-09-14 02:05	30.29	OK	5252	2026-09-14 02:06	30.27	OK
5253	2026-09-14 02:07	30.81	OK	5254	2026-09-14 02:08	30.26	OK
5255	2026-09-14 02:09	30.11	OK	5256	2026-09-14 02:10	30.38	OK
5257	2026-09-14 02:11	30.01	OK	5258	2026-09-14 02:12	30.02	OK
5259	2026-09-14 02:13	30.70	OK	5260	2026-09-14 02:14	28.72	OK
5261	2026-09-14 02:15	30.93	OK	5262	2026-09-14 02:16	29.77	OK
5263	2026-09-14 02:17	30.47	OK	5264	2026-09-14 02:18	30.67	OK
5265	2026-09-14 02:19	30.31	OK	5266	2026-09-14 02:20	29.70	OK
5267	2026-09-14 02:21	30.63	OK	5268	2026-09-14 02:22	30.17	OK
5269	2026-09-14 02:23	30.56	OK	5270	2026-09-14 02:24	30.09	OK
5271	2026-09-14 02:25	30.59	OK	5272	2026-09-14 02:26	31.37	OK
5273	2026-09-14 02:27	30.66	OK	5274	2026-09-14 02:28	30.23	OK
5275	2026-09-14 02:29	29.26	OK	5276	2026-09-14 02:30	30.68	OK
5277	2026-09-14 02:31	30.80	OK	5278	2026-09-14 02:32	29.59	OK
5279	2026-09-14 02:33	31.39	OK	5280	2026-09-14 02:34	30.11	OK
5281	2026-09-14 02:35	31.25	OK	5282	2026-09-14 02:36	30.81	OK
5283	2026-09-14 02:37	29.13	OK	5284	2026-09-14 02:38	31.60	OK
5285	2026-09-14 02:39	29.84	OK	5286	2026-09-14 02:40	30.02	OK
5287	2026-09-14 02:41	29.95	OK	5288	2026-09-14 02:42	30.36	OK
5289	2026-09-14 02:43	29.60	OK	5290	2026-09-14 02:44	30.01	OK
5291	2026-09-14 02:45	29.48	OK	5292	2026-09-14 02:46	30.01	OK
5293	2026-09-14 02:47	31.72	OK	5294	2026-09-14 02:48	29.40	OK
5295	2026-09-14 02:49	29.41	OK	5296	2026-09-14 02:50	29.29	OK
5297	2026-09-14 02:51	31.09	OK	5298	2026-09-14 02:52	30.17	OK
5299	2026-09-14 02:53	30.13	OK	5300	2026-09-14 02:54	29.54	OK
5301	2026-09-14 02:55	30.27	OK	5302	2026-09-14 02:56	30.00	OK
5303	2026-09-14 02:57	31.08	OK	5304	2026-09-14 02:58	31.37	OK
5305	2026-09-14 02:59	30.64	OK	5306	2026-09-14 03:00	30.50	OK
5307	2026-09-14 03:01	29.68	OK	5308	2026-09-14 03:02	30.42	OK
5309	2026-09-14 03:03	30.47	OK	5310	2026-09-14 03:04	29.81	OK
5311	2026-09-14 03:05	30.07	OK	5312	2026-09-14 03:06	31.56	OK
5313	2026-09-14 03:07	30.24	OK	5314	2026-09-14 03:08	29.91	OK
5315	2026-09-14 03:09	30.48	OK	5316	2026-09-14 03:10	29.62	OK
5317	2026-09-14 03:11	30.41	OK	5318	2026-09-14 03:12	30.46	OK
5319	2026-09-14 03:13	29.72	OK	5320	2026-09-14 03:14	30.49	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5321	2026-09-14 03:15	30.26	OK	5322	2026-09-14 03:16	29.09	OK
5323	2026-09-14 03:17	30.29	OK	5324	2026-09-14 03:18	29.76	OK
5325	2026-09-14 03:19	30.90	OK	5326	2026-09-14 03:20	30.60	OK
5327	2026-09-14 03:21	31.08	OK	5328	2026-09-14 03:22	30.15	OK
5329	2026-09-14 03:23	30.01	OK	5330	2026-09-14 03:24	29.84	OK
5331	2026-09-14 03:25	29.83	OK	5332	2026-09-14 03:26	30.11	OK
5333	2026-09-14 03:27	29.72	OK	5334	2026-09-14 03:28	30.94	OK
5335	2026-09-14 03:29	29.08	OK	5336	2026-09-14 03:30	28.64	OK
5337	2026-09-14 03:31	30.55	OK	5338	2026-09-14 03:32	29.85	OK
5339	2026-09-14 03:33	28.34	OK	5340	2026-09-14 03:34	31.06	OK
5341	2026-09-14 03:35	31.08	OK	5342	2026-09-14 03:36	29.65	OK
5343	2026-09-14 03:37	31.11	OK	5344	2026-09-14 03:38	31.01	OK
5345	2026-09-14 03:39	30.50	OK	5346	2026-09-14 03:40	29.00	OK
5347	2026-09-14 03:41	30.73	OK	5348	2026-09-14 03:42	29.70	OK
5349	2026-09-14 03:43	30.72	OK	5350	2026-09-14 03:44	29.68	OK
5351	2026-09-14 03:45	30.20	OK	5352	2026-09-14 03:46	30.50	OK
5353	2026-09-14 03:47	28.38	OK	5354	2026-09-14 03:48	30.86	OK
5355	2026-09-14 03:49	30.19	OK	5356	2026-09-14 03:50	29.87	OK
5357	2026-09-14 03:51	30.19	OK	5358	2026-09-14 03:52	29.96	OK
5359	2026-09-14 03:53	29.91	OK	5360	2026-09-14 03:54	30.14	OK
5361	2026-09-14 03:55	28.86	OK	5362	2026-09-14 03:56	30.06	OK
5363	2026-09-14 03:57	29.14	OK	5364	2026-09-14 03:58	29.84	OK
5365	2026-09-14 03:59	30.72	OK	5366	2026-09-14 04:00	30.82	OK
5367	2026-09-14 04:01	29.05	OK	5368	2026-09-14 04:02	29.18	OK
5369	2026-09-14 04:03	30.20	OK	5370	2026-09-14 04:04	31.23	OK
5371	2026-09-14 04:05	31.20	OK	5372	2026-09-14 04:06	28.47	OK
5373	2026-09-14 04:07	29.53	OK	5374	2026-09-14 04:08	29.90	OK
5375	2026-09-14 04:09	30.29	OK	5376	2026-09-14 04:10	28.79	OK
5377	2026-09-14 04:11	29.71	OK	5378	2026-09-14 04:12	29.59	OK
5379	2026-09-14 04:13	29.34	OK	5380	2026-09-14 04:14	29.71	OK
5381	2026-09-14 04:15	31.03	OK	5382	2026-09-14 04:16	30.73	OK
5383	2026-09-14 04:17	29.48	OK	5384	2026-09-14 04:18	29.30	OK
5385	2026-09-14 04:19	29.98	OK	5386	2026-09-14 04:20	28.75	OK
5387	2026-09-14 04:21	29.33	OK	5388	2026-09-14 04:22	29.11	OK
5389	2026-09-14 04:23	29.85	OK	5390	2026-09-14 04:24	29.37	OK
5391	2026-09-14 04:25	30.40	OK	5392	2026-09-14 04:26	29.26	OK
5393	2026-09-14 04:27	28.16	OK	5394	2026-09-14 04:28	29.07	OK
5395	2026-09-14 04:29	29.56	OK	5396	2026-09-14 04:30	31.01	OK
5397	2026-09-14 04:31	30.39	OK	5398	2026-09-14 04:32	29.46	OK
5399	2026-09-14 04:33	28.67	OK	5400	2026-09-14 04:34	29.63	OK
5401	2026-09-14 04:35	28.92	OK	5402	2026-09-14 04:36	29.69	OK
5403	2026-09-14 04:37	29.75	OK	5404	2026-09-14 04:38	28.70	OK
5405	2026-09-14 04:39	30.17	OK	5406	2026-09-14 04:40	30.66	OK
5407	2026-09-14 04:41	29.50	OK	5408	2026-09-14 04:42	29.96	OK
5409	2026-09-14 04:43	29.77	OK	5410	2026-09-14 04:44	30.14	OK
5411	2026-09-14 04:45	29.29	OK	5412	2026-09-14 04:46	29.10	OK
5413	2026-09-14 04:47	28.48	OK	5414	2026-09-14 04:48	29.50	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5415	2026-09-14 04:49	28.80	OK	5416	2026-09-14 04:50	30.30	OK
5417	2026-09-14 04:51	29.53	OK	5418	2026-09-14 04:52	28.78	OK
5419	2026-09-14 04:53	29.17	OK	5420	2026-09-14 04:54	29.78	OK
5421	2026-09-14 04:55	28.02	OK	5422	2026-09-14 04:56	29.21	OK
5423	2026-09-14 04:57	28.74	OK	5424	2026-09-14 04:58	28.57	OK
5425	2026-09-14 04:59	29.01	OK	5426	2026-09-14 05:00	29.99	OK
5427	2026-09-14 05:01	28.36	OK	5428	2026-09-14 05:02	29.03	OK
5429	2026-09-14 05:03	28.65	OK	5430	2026-09-14 05:04	30.55	OK
5431	2026-09-14 05:05	28.34	OK	5432	2026-09-14 05:06	31.11	OK
5433	2026-09-14 05:07	28.23	OK	5434	2026-09-14 05:08	30.12	OK
5435	2026-09-14 05:09	30.21	OK	5436	2026-09-14 05:10	28.94	OK
5437	2026-09-14 05:11	29.98	OK	5438	2026-09-14 05:12	30.15	OK
5439	2026-09-14 05:13	29.00	OK	5440	2026-09-14 05:14	30.31	OK
5441	2026-09-14 05:15	29.64	OK	5442	2026-09-14 05:16	28.40	OK
5443	2026-09-14 05:17	27.63	OK	5444	2026-09-14 05:18	29.15	OK
5445	2026-09-14 05:19	29.66	OK	5446	2026-09-14 05:20	30.06	OK
5447	2026-09-14 05:21	29.18	OK	5448	2026-09-14 05:22	29.99	OK
5449	2026-09-14 05:23	27.32	OK	5450	2026-09-14 05:24	28.33	OK
5451	2026-09-14 05:25	28.21	OK	5452	2026-09-14 05:26	27.65	OK
5453	2026-09-14 05:27	30.23	OK	5454	2026-09-14 05:28	30.33	OK
5455	2026-09-14 05:29	29.70	OK	5456	2026-09-14 05:30	30.11	OK
5457	2026-09-14 05:31	28.69	OK	5458	2026-09-14 05:32	27.30	OK
5459	2026-09-14 05:33	28.04	OK	5460	2026-09-14 05:34	28.82	OK
5461	2026-09-14 05:35	29.64	OK	5462	2026-09-14 05:36	29.06	OK
5463	2026-09-14 05:37	29.81	OK	5464	2026-09-14 05:38	30.31	OK
5465	2026-09-14 05:39	29.69	OK	5466	2026-09-14 05:40	29.59	OK
5467	2026-09-14 05:41	30.38	OK	5468	2026-09-14 05:42	28.39	OK
5469	2026-09-14 05:43	29.27	OK	5470	2026-09-14 05:44	29.67	OK
5471	2026-09-14 05:45	29.95	OK	5472	2026-09-14 05:46	29.07	OK
5473	2026-09-14 05:47	27.62	OK	5474	2026-09-14 05:48	30.05	OK
5475	2026-09-14 05:49	27.89	OK	5476	2026-09-14 05:50	29.35	OK
5477	2026-09-14 05:51	27.49	OK	5478	2026-09-14 05:52	28.92	OK
5479	2026-09-14 05:53	29.59	OK	5480	2026-09-14 05:54	28.70	OK
5481	2026-09-14 05:55	28.63	OK	5482	2026-09-14 05:56	28.09	OK
5483	2026-09-14 05:57	29.39	OK	5484	2026-09-14 05:58	29.01	OK
5485	2026-09-14 05:59	28.18	OK	5486	2026-09-14 06:00	27.71	OK
5487	2026-09-14 06:01	28.66	OK	5488	2026-09-14 06:02	28.99	OK
5489	2026-09-14 06:03	29.45	OK	5490	2026-09-14 06:04	29.66	OK
5491	2026-09-14 06:05	28.84	OK	5492	2026-09-14 06:06	28.57	OK
5493	2026-09-14 06:07	28.43	OK	5494	2026-09-14 06:08	29.26	OK
5495	2026-09-14 06:09	28.68	OK	5496	2026-09-14 06:10	29.17	OK
5497	2026-09-14 06:11	28.51	OK	5498	2026-09-14 06:12	28.71	OK
5499	2026-09-14 06:13	29.51	OK	5500	2026-09-14 06:14	28.97	OK
5501	2026-09-14 06:15	28.52	OK	5502	2026-09-14 06:16	29.05	OK
5503	2026-09-14 06:17	28.30	OK	5504	2026-09-14 06:18	29.40	OK
5505	2026-09-14 06:19	28.14	OK	5506	2026-09-14 06:20	29.06	OK
5507	2026-09-14 06:21	29.39	OK	5508	2026-09-14 06:22	28.30	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5509	2026-09-14 06:23	28.90	OK	5510	2026-09-14 06:24	28.41	OK
5511	2026-09-14 06:25	28.90	OK	5512	2026-09-14 06:26	28.87	OK
5513	2026-09-14 06:27	28.85	OK	5514	2026-09-14 06:28	29.55	OK
5515	2026-09-14 06:29	29.28	OK	5516	2026-09-14 06:30	28.58	OK
5517	2026-09-14 06:31	29.11	OK	5518	2026-09-14 06:32	30.16	OK
5519	2026-09-14 06:33	28.89	OK	5520	2026-09-14 06:34	29.08	OK
5521	2026-09-14 06:35	28.34	OK	5522	2026-09-14 06:36	28.83	OK
5523	2026-09-14 06:37	29.04	OK	5524	2026-09-14 06:38	28.66	OK
5525	2026-09-14 06:39	28.53	OK	5526	2026-09-14 06:40	29.22	OK
5527	2026-09-14 06:41	27.07	OK	5528	2026-09-14 06:42	27.89	OK
5529	2026-09-14 06:43	28.09	OK	5530	2026-09-14 06:44	29.10	OK
5531	2026-09-14 06:45	27.23	OK	5532	2026-09-14 06:46	29.34	OK
5533	2026-09-14 06:47	27.82	OK	5534	2026-09-14 06:48	29.13	OK
5535	2026-09-14 06:49	27.46	OK	5536	2026-09-14 06:50	26.79	OK
5537	2026-09-14 06:51	28.77	OK	5538	2026-09-14 06:52	28.51	OK
5539	2026-09-14 06:53	28.53	OK	5540	2026-09-14 06:54	27.72	OK
5541	2026-09-14 06:55	28.04	OK	5542	2026-09-14 06:56	28.94	OK
5543	2026-09-14 06:57	29.31	OK	5544	2026-09-14 06:58	26.94	OK
5545	2026-09-14 06:59	28.90	OK	5546	2026-09-14 07:00	29.46	OK
5547	2026-09-14 07:01	29.87	OK	5548	2026-09-14 07:02	27.93	OK
5549	2026-09-14 07:03	27.94	OK	5550	2026-09-14 07:04	28.58	OK
5551	2026-09-14 07:05	28.88	OK	5552	2026-09-14 07:06	26.92	OK
5553	2026-09-14 07:07	28.59	OK	5554	2026-09-14 07:08	26.68	OK
5555	2026-09-14 07:09	28.35	OK	5556	2026-09-14 07:10	29.64	OK
5557	2026-09-14 07:11	27.64	OK	5558	2026-09-14 07:12	28.78	OK
5559	2026-09-14 07:13	26.70	OK	5560	2026-09-14 07:14	28.03	OK
5561	2026-09-14 07:15	27.71	OK	5562	2026-09-14 07:16	29.32	OK
5563	2026-09-14 07:17	26.99	OK	5564	2026-09-14 07:18	27.79	OK
5565	2026-09-14 07:19	28.87	OK	5566	2026-09-14 07:20	28.65	OK
5567	2026-09-14 07:21	27.54	OK	5568	2026-09-14 07:22	28.29	OK
5569	2026-09-14 07:23	26.91	OK	5570	2026-09-14 07:24	27.94	OK
5571	2026-09-14 07:25	27.65	OK	5572	2026-09-14 07:26	26.48	OK
5573	2026-09-14 07:27	27.51	OK	5574	2026-09-14 07:28	27.66	OK
5575	2026-09-14 07:29	28.37	OK	5576	2026-09-14 07:30	28.67	OK
5577	2026-09-14 07:31	27.41	OK	5578	2026-09-14 07:32	28.46	OK
5579	2026-09-14 07:33	29.32	OK	5580	2026-09-14 07:34	28.84	OK
5581	2026-09-14 07:35	26.93	OK	5582	2026-09-14 07:36	26.47	OK
5583	2026-09-14 07:37	29.27	OK	5584	2026-09-14 07:38	27.64	OK
5585	2026-09-14 07:39	27.53	OK	5586	2026-09-14 07:40	27.18	OK
5587	2026-09-14 07:41	27.47	OK	5588	2026-09-14 07:42	27.47	OK
5589	2026-09-14 07:43	26.85	OK	5590	2026-09-14 07:44	27.71	OK
5591	2026-09-14 07:45	28.43	OK	5592	2026-09-14 07:46	27.84	OK
5593	2026-09-14 07:47	29.12	OK	5594	2026-09-14 07:48	29.91	OK
5595	2026-09-14 07:49	27.09	OK	5596	2026-09-14 07:50	28.32	OK
5597	2026-09-14 07:51	28.34	OK	5598	2026-09-14 07:52	28.03	OK
5599	2026-09-14 07:53	27.85	OK	5600	2026-09-14 07:54	27.64	OK
5601	2026-09-14 07:55	28.89	OK	5602	2026-09-14 07:56	28.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5603	2026-09-14 07:57	27.77	OK	5604	2026-09-14 07:58	27.27	OK
5605	2026-09-14 07:59	27.56	OK	5606	2026-09-14 08:00	26.48	OK
5607	2026-09-14 08:01	28.13	OK	5608	2026-09-14 08:02	26.93	OK
5609	2026-09-14 08:03	26.45	OK	5610	2026-09-14 08:04	26.23	OK
5611	2026-09-14 08:05	27.17	OK	5612	2026-09-14 08:06	27.77	OK
5613	2026-09-14 08:07	27.69	OK	5614	2026-09-14 08:08	26.84	OK
5615	2026-09-14 08:09	27.06	OK	5616	2026-09-14 08:10	26.90	OK
5617	2026-09-14 08:11	27.30	OK	5618	2026-09-14 08:12	27.86	OK
5619	2026-09-14 08:13	26.48	OK	5620	2026-09-14 08:14	27.93	OK
5621	2026-09-14 08:15	27.79	OK	5622	2026-09-14 08:16	26.21	OK
5623	2026-09-14 08:17	27.35	OK	5624	2026-09-14 08:18	26.53	OK
5625	2026-09-14 08:19	28.12	OK	5626	2026-09-14 08:20	28.00	OK
5627	2026-09-14 08:21	27.92	OK	5628	2026-09-14 08:22	28.56	OK
5629	2026-09-14 08:23	27.98	OK	5630	2026-09-14 08:24	27.79	OK
5631	2026-09-14 08:25	27.04	OK	5632	2026-09-14 08:26	27.30	OK
5633	2026-09-14 08:27	27.99	OK	5634	2026-09-14 08:28	27.35	OK
5635	2026-09-14 08:29	26.88	OK	5636	2026-09-14 08:30	27.74	OK
5637	2026-09-14 08:31	26.48	OK	5638	2026-09-14 08:32	26.05	OK
5639	2026-09-14 08:33	26.82	OK	5640	2026-09-14 08:34	27.80	OK
5641	2026-09-14 08:35	27.10	OK	5642	2026-09-14 08:36	27.14	OK
5643	2026-09-14 08:37	27.98	OK	5644	2026-09-14 08:38	28.67	OK
5645	2026-09-14 08:39	27.95	OK	5646	2026-09-14 08:40	27.75	OK
5647	2026-09-14 08:41	26.60	OK	5648	2026-09-14 08:42	27.80	OK
5649	2026-09-14 08:43	27.57	OK	5650	2026-09-14 08:44	27.45	OK
5651	2026-09-14 08:45	27.78	OK	5652	2026-09-14 08:46	26.24	OK
5653	2026-09-14 08:47	26.38	OK	5654	2026-09-14 08:48	28.26	OK
5655	2026-09-14 08:49	28.91	OK	5656	2026-09-14 08:50	27.83	OK
5657	2026-09-14 08:51	27.50	OK	5658	2026-09-14 08:52	27.39	OK
5659	2026-09-14 08:53	27.43	OK	5660	2026-09-14 08:54	27.65	OK
5661	2026-09-14 08:55	28.34	OK	5662	2026-09-14 08:56	27.27	OK
5663	2026-09-14 08:57	27.52	OK	5664	2026-09-14 08:58	26.61	OK
5665	2026-09-14 08:59	28.04	OK	5666	2026-09-14 09:00	26.74	OK
5667	2026-09-14 09:01	27.24	OK	5668	2026-09-14 09:02	27.09	OK
5669	2026-09-14 09:03	26.88	OK	5670	2026-09-14 09:04	26.60	OK
5671	2026-09-14 09:05	25.43	OK	5672	2026-09-14 09:06	26.52	OK
5673	2026-09-14 09:07	27.04	OK	5674	2026-09-14 09:08	28.28	OK
5675	2026-09-14 09:09	26.60	OK	5676	2026-09-14 09:10	25.97	OK
5677	2026-09-14 09:11	27.68	OK	5678	2026-09-14 09:12	25.59	OK
5679	2026-09-14 09:13	26.42	OK	5680	2026-09-14 09:14	27.47	OK
5681	2026-09-14 09:15	27.32	OK	5682	2026-09-14 09:16	26.69	OK
5683	2026-09-14 09:17	26.02	OK	5684	2026-09-14 09:18	27.66	OK
5685	2026-09-14 09:19	26.26	OK	5686	2026-09-14 09:20	27.28	OK
5687	2026-09-14 09:21	25.50	OK	5688	2026-09-14 09:22	26.60	OK
5689	2026-09-14 09:23	28.01	OK	5690	2026-09-14 09:24	27.75	OK
5691	2026-09-14 09:25	27.44	OK	5692	2026-09-14 09:26	27.36	OK
5693	2026-09-14 09:27	25.82	OK	5694	2026-09-14 09:28	27.43	OK
5695	2026-09-14 09:29	26.43	OK	5696	2026-09-14 09:30	27.62	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5697	2026-09-14 09:31	24.98	OK	5698	2026-09-14 09:32	28.09	OK
5699	2026-09-14 09:33	27.46	OK	5700	2026-09-14 09:34	25.76	OK
5701	2026-09-14 09:35	27.90	OK	5702	2026-09-14 09:36	26.72	OK
5703	2026-09-14 09:37	28.06	OK	5704	2026-09-14 09:38	25.51	OK
5705	2026-09-14 09:39	26.26	OK	5706	2026-09-14 09:40	26.05	OK
5707	2026-09-14 09:41	24.96	OK	5708	2026-09-14 09:42	26.24	OK
5709	2026-09-14 09:43	27.01	OK	5710	2026-09-14 09:44	26.06	OK
5711	2026-09-14 09:45	27.07	OK	5712	2026-09-14 09:46	25.25	OK
5713	2026-09-14 09:47	26.03	OK	5714	2026-09-14 09:48	27.35	OK
5715	2026-09-14 09:49	27.04	OK	5716	2026-09-14 09:50	25.83	OK
5717	2026-09-14 09:51	25.89	OK	5718	2026-09-14 09:52	26.61	OK
5719	2026-09-14 09:53	26.93	OK	5720	2026-09-14 09:54	27.55	OK
5721	2026-09-14 09:55	26.39	OK	5722	2026-09-14 09:56	27.15	OK
5723	2026-09-14 09:57	27.19	OK	5724	2026-09-14 09:58	26.21	OK
5725	2026-09-14 09:59	26.55	OK	5726	2026-09-14 10:00	26.49	OK
5727	2026-09-14 10:01	26.66	OK	5728	2026-09-14 10:02	25.57	OK
5729	2026-09-14 10:03	27.17	OK	5730	2026-09-14 10:04	27.65	OK
5731	2026-09-14 10:05	26.44	OK	5732	2026-09-14 10:06	26.65	OK
5733	2026-09-14 10:07	26.57	OK	5734	2026-09-14 10:08	27.35	OK
5735	2026-09-14 10:09	27.14	OK	5736	2026-09-14 10:10	26.49	OK
5737	2026-09-14 10:11	26.54	OK	5738	2026-09-14 10:12	25.07	OK
5739	2026-09-14 10:13	26.10	OK	5740	2026-09-14 10:14	26.08	OK
5741	2026-09-14 10:15	25.98	OK	5742	2026-09-14 10:16	26.26	OK
5743	2026-09-14 10:17	25.72	OK	5744	2026-09-14 10:18	27.01	OK
5745	2026-09-14 10:19	27.89	OK	5746	2026-09-14 10:20	27.79	OK
5747	2026-09-14 10:21	26.16	OK	5748	2026-09-14 10:22	25.86	OK
5749	2026-09-14 10:23	27.04	OK	5750	2026-09-14 10:24	24.87	OK
5751	2026-09-14 10:25	26.75	OK	5752	2026-09-14 10:26	25.15	OK
5753	2026-09-14 10:27	25.75	OK	5754	2026-09-14 10:28	25.89	OK
5755	2026-09-14 10:29	26.69	OK	5756	2026-09-14 10:30	25.56	OK
5757	2026-09-14 10:31	26.84	OK	5758	2026-09-14 10:32	26.48	OK
5759	2026-09-14 10:33	25.87	OK	5760	2026-09-14 10:34	27.54	OK
5761	2026-09-14 10:35	26.68	OK	5762	2026-09-14 10:36	26.22	OK
5763	2026-09-14 10:37	26.50	OK	5764	2026-09-14 10:38	27.81	OK
5765	2026-09-14 10:39	26.14	OK	5766	2026-09-14 10:40	26.46	OK
5767	2026-09-14 10:41	26.55	OK	5768	2026-09-14 10:42	25.29	OK
5769	2026-09-14 10:43	25.59	OK	5770	2026-09-14 10:44	25.73	OK
5771	2026-09-14 10:45	27.96	OK	5772	2026-09-14 10:46	27.06	OK
5773	2026-09-14 10:47	26.91	OK	5774	2026-09-14 10:48	26.32	OK
5775	2026-09-14 10:49	25.33	OK	5776	2026-09-14 10:50	26.00	OK
5777	2026-09-14 10:51	27.72	OK	5778	2026-09-14 10:52	25.36	OK
5779	2026-09-14 10:53	25.76	OK	5780	2026-09-14 10:54	27.44	OK
5781	2026-09-14 10:55	25.21	OK	5782	2026-09-14 10:56	25.15	OK
5783	2026-09-14 10:57	25.90	OK	5784	2026-09-14 10:58	26.62	OK
5785	2026-09-14 10:59	26.30	OK	5786	2026-09-14 11:00	24.97	OK
5787	2026-09-14 11:01	27.65	OK	5788	2026-09-14 11:02	26.25	OK
5789	2026-09-14 11:03	25.39	OK	5790	2026-09-14 11:04	25.37	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5791	2026-09-14 11:05	25.96	OK	5792	2026-09-14 11:06	25.60	OK
5793	2026-09-14 11:07	25.30	OK	5794	2026-09-14 11:08	25.99	OK
5795	2026-09-14 11:09	24.83	OK	5796	2026-09-14 11:10	26.47	OK
5797	2026-09-14 11:11	25.98	OK	5798	2026-09-14 11:12	27.59	OK
5799	2026-09-14 11:13	26.14	OK	5800	2026-09-14 11:14	26.19	OK
5801	2026-09-14 11:15	25.74	OK	5802	2026-09-14 11:16	25.87	OK
5803	2026-09-14 11:17	26.24	OK	5804	2026-09-14 11:18	27.20	OK
5805	2026-09-14 11:19	24.93	OK	5806	2026-09-14 11:20	25.34	OK
5807	2026-09-14 11:21	25.10	OK	5808	2026-09-14 11:22	26.55	OK
5809	2026-09-14 11:23	25.99	OK	5810	2026-09-14 11:24	25.49	OK
5811	2026-09-14 11:25	26.59	OK	5812	2026-09-14 11:26	25.58	OK
5813	2026-09-14 11:27	24.78	OK	5814	2026-09-14 11:28	25.93	OK
5815	2026-09-14 11:29	26.42	OK	5816	2026-09-14 11:30	25.57	OK
5817	2026-09-14 11:31	25.69	OK	5818	2026-09-14 11:32	26.35	OK
5819	2026-09-14 11:33	24.53	OK	5820	2026-09-14 11:34	24.91	OK
5821	2026-09-14 11:35	27.00	OK	5822	2026-09-14 11:36	25.66	OK
5823	2026-09-14 11:37	26.72	OK	5824	2026-09-14 11:38	25.29	OK
5825	2026-09-14 11:39	25.96	OK	5826	2026-09-14 11:40	26.37	OK
5827	2026-09-14 11:41	26.88	OK	5828	2026-09-14 11:42	27.01	OK
5829	2026-09-14 11:43	24.65	OK	5830	2026-09-14 11:44	26.76	OK
5831	2026-09-14 11:45	27.03	OK	5832	2026-09-14 11:46	26.80	OK
5833	2026-09-14 11:47	25.89	OK	5834	2026-09-14 11:48	26.15	OK
5835	2026-09-14 11:49	24.96	OK	5836	2026-09-14 11:50	24.86	OK
5837	2026-09-14 11:51	24.73	OK	5838	2026-09-14 11:52	26.77	OK
5839	2026-09-14 11:53	26.76	OK	5840	2026-09-14 11:54	24.98	OK
5841	2026-09-14 11:55	26.33	OK	5842	2026-09-14 11:56	25.49	OK
5843	2026-09-14 11:57	26.58	OK	5844	2026-09-14 11:58	27.93	OK
5845	2026-09-14 11:59	25.49	OK	5846	2026-09-14 12:00	25.70	OK
5847	2026-09-14 12:01	25.53	OK	5848	2026-09-14 12:02	27.28	OK
5849	2026-09-14 12:03	26.35	OK	5850	2026-09-14 12:04	24.35	OK
5851	2026-09-14 12:05	24.73	OK	5852	2026-09-14 12:06	26.50	OK
5853	2026-09-14 12:07	25.31	OK	5854	2026-09-14 12:08	25.98	OK
5855	2026-09-14 12:09	26.87	OK	5856	2026-09-14 12:10	25.68	OK
5857	2026-09-14 12:11	26.99	OK	5858	2026-09-14 12:12	26.95	OK
5859	2026-09-14 12:13	26.76	OK	5860	2026-09-14 12:14	25.32	OK
5861	2026-09-14 12:15	24.88	OK	5862	2026-09-14 12:16	24.78	OK
5863	2026-09-14 12:17	27.11	OK	5864	2026-09-14 12:18	24.52	OK
5865	2026-09-14 12:19	25.31	OK	5866	2026-09-14 12:20	26.34	OK
5867	2026-09-14 12:21	25.41	OK	5868	2026-09-14 12:22	25.30	OK
5869	2026-09-14 12:23	26.86	OK	5870	2026-09-14 12:24	25.46	OK
5871	2026-09-14 12:25	25.76	OK	5872	2026-09-14 12:26	25.49	OK
5873	2026-09-14 12:27	25.26	OK	5874	2026-09-14 12:28	26.88	OK
5875	2026-09-14 12:29	24.21	OK	5876	2026-09-14 12:30	24.37	OK
5877	2026-09-14 12:31	25.92	OK	5878	2026-09-14 12:32	25.22	OK
5879	2026-09-14 12:33	26.30	OK	5880	2026-09-14 12:34	27.11	OK
5881	2026-09-14 12:35	25.75	OK	5882	2026-09-14 12:36	25.06	OK
5883	2026-09-14 12:37	26.17	OK	5884	2026-09-14 12:38	25.55	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5885	2026-09-14 12:39	23.97	OK	5886	2026-09-14 12:40	26.22	OK
5887	2026-09-14 12:41	25.72	OK	5888	2026-09-14 12:42	26.28	OK
5889	2026-09-14 12:43	24.10	OK	5890	2026-09-14 12:44	26.67	OK
5891	2026-09-14 12:45	25.75	OK	5892	2026-09-14 12:46	25.43	OK
5893	2026-09-14 12:47	25.04	OK	5894	2026-09-14 12:48	26.40	OK
5895	2026-09-14 12:49	26.15	OK	5896	2026-09-14 12:50	24.98	OK
5897	2026-09-14 12:51	24.83	OK	5898	2026-09-14 12:52	26.29	OK
5899	2026-09-14 12:53	25.41	OK	5900	2026-09-14 12:54	26.68	OK
5901	2026-09-14 12:55	27.04	OK	5902	2026-09-14 12:56	25.86	OK
5903	2026-09-14 12:57	25.20	OK	5904	2026-09-14 12:58	25.35	OK
5905	2026-09-14 12:59	25.74	OK	5906	2026-09-14 13:00	26.55	OK
5907	2026-09-14 13:01	25.52	OK	5908	2026-09-14 13:02	25.14	OK
5909	2026-09-14 13:03	24.63	OK	5910	2026-09-14 13:04	26.23	OK
5911	2026-09-14 13:05	25.47	OK	5912	2026-09-14 13:06	25.79	OK
5913	2026-09-14 13:07	25.11	OK	5914	2026-09-14 13:08	25.06	OK
5915	2026-09-14 13:09	25.59	OK	5916	2026-09-14 13:10	27.18	OK
5917	2026-09-14 13:11	25.46	OK	5918	2026-09-14 13:12	26.77	OK
5919	2026-09-14 13:13	27.33	OK	5920	2026-09-14 13:14	25.30	OK
5921	2026-09-14 13:15	25.19	OK	5922	2026-09-14 13:16	24.15	OK
5923	2026-09-14 13:17	26.21	OK	5924	2026-09-14 13:18	26.10	OK
5925	2026-09-14 13:19	24.77	OK	5926	2026-09-14 13:20	24.72	OK
5927	2026-09-14 13:21	25.81	OK	5928	2026-09-14 13:22	24.73	OK
5929	2026-09-14 13:23	25.96	OK	5930	2026-09-14 13:24	24.86	OK
5931	2026-09-14 13:25	26.50	OK	5932	2026-09-14 13:26	25.71	OK
5933	2026-09-14 13:27	24.29	OK	5934	2026-09-14 13:28	25.52	OK
5935	2026-09-14 13:29	26.40	OK	5936	2026-09-14 13:30	25.11	OK
5937	2026-09-14 13:31	26.44	OK	5938	2026-09-14 13:32	25.64	OK
5939	2026-09-14 13:33	24.84	OK	5940	2026-09-14 13:34	26.35	OK
5941	2026-09-14 13:35	26.33	OK	5942	2026-09-14 13:36	27.16	OK
5943	2026-09-14 13:37	26.50	OK	5944	2026-09-14 13:38	26.32	OK
5945	2026-09-14 13:39	25.80	OK	5946	2026-09-14 13:40	25.19	OK
5947	2026-09-14 13:41	25.62	OK	5948	2026-09-14 13:42	25.89	OK
5949	2026-09-14 13:43	25.99	OK	5950	2026-09-14 13:44	26.85	OK
5951	2026-09-14 13:45	25.04	OK	5952	2026-09-14 13:46	25.12	OK
5953	2026-09-14 13:47	25.61	OK	5954	2026-09-14 13:48	25.44	OK
5955	2026-09-14 13:49	26.76	OK	5956	2026-09-14 13:50	24.52	OK
5957	2026-09-14 13:51	25.31	OK	5958	2026-09-14 13:52	25.37	OK
5959	2026-09-14 13:53	25.81	OK	5960	2026-09-14 13:54	26.03	OK
5961	2026-09-14 13:55	26.70	OK	5962	2026-09-14 13:56	25.66	OK
5963	2026-09-14 13:57	25.17	OK	5964	2026-09-14 13:58	26.37	OK
5965	2026-09-14 13:59	25.75	OK	5966	2026-09-14 14:00	25.94	OK
5967	2026-09-14 14:01	26.04	OK	5968	2026-09-14 14:02	25.68	OK
5969	2026-09-14 14:03	26.01	OK	5970	2026-09-14 14:04	25.64	OK
5971	2026-09-14 14:05	25.95	OK	5972	2026-09-14 14:06	25.86	OK
5973	2026-09-14 14:07	25.79	OK	5974	2026-09-14 14:08	27.28	OK
5975	2026-09-14 14:09	25.44	OK	5976	2026-09-14 14:10	26.58	OK
5977	2026-09-14 14:11	26.09	OK	5978	2026-09-14 14:12	25.79	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
5979	2026-09-14 14:13	24.30	OK	5980	2026-09-14 14:14	26.63	OK
5981	2026-09-14 14:15	26.76	OK	5982	2026-09-14 14:16	26.13	OK
5983	2026-09-14 14:17	25.72	OK	5984	2026-09-14 14:18	24.91	OK
5985	2026-09-14 14:19	24.80	OK	5986	2026-09-14 14:20	24.38	OK
5987	2026-09-14 14:21	26.37	OK	5988	2026-09-14 14:22	25.80	OK
5989	2026-09-14 14:23	25.91	OK	5990	2026-09-14 14:24	25.86	OK
5991	2026-09-14 14:25	24.13	OK	5992	2026-09-14 14:26	24.98	OK
5993	2026-09-14 14:27	26.02	OK	5994	2026-09-14 14:28	25.84	OK
5995	2026-09-14 14:29	26.48	OK	5996	2026-09-14 14:30	25.63	OK
5997	2026-09-14 14:31	26.01	OK	5998	2026-09-14 14:32	26.79	OK
5999	2026-09-14 14:33	26.53	OK	6000	2026-09-14 14:34	26.49	OK
6001	2026-09-14 14:35	25.14	OK	6002	2026-09-14 14:36	25.49	OK
6003	2026-09-14 14:37	24.22	OK	6004	2026-09-14 14:38	25.12	OK
6005	2026-09-14 14:39	27.71	OK	6006	2026-09-14 14:40	25.99	OK
6007	2026-09-14 14:41	25.54	OK	6008	2026-09-14 14:42	26.57	OK
6009	2026-09-14 14:43	26.22	OK	6010	2026-09-14 14:44	25.49	OK
6011	2026-09-14 14:45	26.21	OK	6012	2026-09-14 14:46	25.67	OK
6013	2026-09-14 14:47	25.69	OK	6014	2026-09-14 14:48	25.06	OK
6015	2026-09-14 14:49	26.17	OK	6016	2026-09-14 14:50	25.85	OK
6017	2026-09-14 14:51	26.56	OK	6018	2026-09-14 14:52	26.09	OK
6019	2026-09-14 14:53	25.79	OK	6020	2026-09-14 14:54	25.57	OK
6021	2026-09-14 14:55	25.10	OK	6022	2026-09-14 14:56	25.87	OK
6023	2026-09-14 14:57	27.28	OK	6024	2026-09-14 14:58	23.98	OK
6025	2026-09-14 14:59	24.24	OK	6026	2026-09-14 15:00	26.80	OK
6027	2026-09-14 15:01	24.94	OK	6028	2026-09-14 15:02	26.86	OK
6029	2026-09-14 15:03	25.36	OK	6030	2026-09-14 15:04	24.36	OK
6031	2026-09-14 15:05	25.82	OK	6032	2026-09-14 15:06	25.95	OK
6033	2026-09-14 15:07	24.31	OK	6034	2026-09-14 15:08	25.73	OK
6035	2026-09-14 15:09	25.82	OK	6036	2026-09-14 15:10	27.25	OK
6037	2026-09-14 15:11	26.69	OK	6038	2026-09-14 15:12	24.45	OK
6039	2026-09-14 15:13	25.51	OK	6040	2026-09-14 15:14	24.66	OK
6041	2026-09-14 15:15	25.51	OK	6042	2026-09-14 15:16	26.68	OK
6043	2026-09-14 15:17	24.97	OK	6044	2026-09-14 15:18	26.70	OK
6045	2026-09-14 15:19	25.92	OK	6046	2026-09-14 15:20	26.60	OK
6047	2026-09-14 15:21	26.86	OK	6048	2026-09-14 15:22	25.86	OK
6049	2026-09-14 15:23	25.97	OK	6050	2026-09-14 15:24	25.61	OK
6051	2026-09-14 15:25	26.42	OK	6052	2026-09-14 15:26	26.92	OK
6053	2026-09-14 15:27	25.40	OK	6054	2026-09-14 15:28	26.33	OK
6055	2026-09-14 15:29	26.43	OK	6056	2026-09-14 15:30	25.74	OK
6057	2026-09-14 15:31	26.95	OK	6058	2026-09-14 15:32	26.11	OK
6059	2026-09-14 15:33	26.21	OK	6060	2026-09-14 15:34	25.94	OK
6061	2026-09-14 15:35	25.30	OK	6062	2026-09-14 15:36	24.45	OK
6063	2026-09-14 15:37	25.83	OK	6064	2026-09-14 15:38	25.39	OK
6065	2026-09-14 15:39	25.17	OK	6066	2026-09-14 15:40	24.81	OK
6067	2026-09-14 15:41	27.16	OK	6068	2026-09-14 15:42	25.01	OK
6069	2026-09-14 15:43	26.04	OK	6070	2026-09-14 15:44	25.22	OK
6071	2026-09-14 15:45	25.90	OK	6072	2026-09-14 15:46	25.01	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6073	2026-09-14 15:47	25.64	OK	6074	2026-09-14 15:48	26.23	OK
6075	2026-09-14 15:49	25.38	OK	6076	2026-09-14 15:50	26.32	OK
6077	2026-09-14 15:51	27.24	OK	6078	2026-09-14 15:52	24.69	OK
6079	2026-09-14 15:53	26.63	OK	6080	2026-09-14 15:54	27.01	OK
6081	2026-09-14 15:55	26.75	OK	6082	2026-09-14 15:56	26.51	OK
6083	2026-09-14 15:57	26.58	OK	6084	2026-09-14 15:58	26.92	OK
6085	2026-09-14 15:59	25.34	OK	6086	2026-09-14 16:00	26.85	OK
6087	2026-09-14 16:01	25.98	OK	6088	2026-09-14 16:02	27.09	OK
6089	2026-09-14 16:03	27.24	OK	6090	2026-09-14 16:04	26.85	OK
6091	2026-09-14 16:05	24.92	OK	6092	2026-09-14 16:06	26.02	OK
6093	2026-09-14 16:07	25.76	OK	6094	2026-09-14 16:08	25.91	OK
6095	2026-09-14 16:09	27.00	OK	6096	2026-09-14 16:10	27.21	OK
6097	2026-09-14 16:11	25.63	OK	6098	2026-09-14 16:12	26.64	OK
6099	2026-09-14 16:13	27.12	OK	6100	2026-09-14 16:14	25.92	OK
6101	2026-09-14 16:15	25.68	OK	6102	2026-09-14 16:16	26.19	OK
6103	2026-09-14 16:17	25.49	OK	6104	2026-09-14 16:18	27.25	OK
6105	2026-09-14 16:19	26.85	OK	6106	2026-09-14 16:20	25.73	OK
6107	2026-09-14 16:21	26.50	OK	6108	2026-09-14 16:22	26.33	OK
6109	2026-09-14 16:23	24.93	OK	6110	2026-09-14 16:24	26.25	OK
6111	2026-09-14 16:25	25.33	OK	6112	2026-09-14 16:26	26.02	OK
6113	2026-09-14 16:27	26.84	OK	6114	2026-09-14 16:28	28.40	OK
6115	2026-09-14 16:29	25.94	OK	6116	2026-09-14 16:30	25.67	OK
6117	2026-09-14 16:31	25.93	OK	6118	2026-09-14 16:32	27.03	OK
6119	2026-09-14 16:33	26.25	OK	6120	2026-09-14 16:34	26.52	OK
6121	2026-09-14 16:35	26.16	OK	6122	2026-09-14 16:36	27.51	OK
6123	2026-09-14 16:37	27.24	OK	6124	2026-09-14 16:38	25.26	OK
6125	2026-09-14 16:39	25.85	OK	6126	2026-09-14 16:40	26.67	OK
6127	2026-09-14 16:41	26.72	OK	6128	2026-09-14 16:42	25.86	OK
6129	2026-09-14 16:43	26.87	OK	6130	2026-09-14 16:44	25.11	OK
6131	2026-09-14 16:45	26.12	OK	6132	2026-09-14 16:46	27.19	OK
6133	2026-09-14 16:47	26.93	OK	6134	2026-09-14 16:48	25.41	OK
6135	2026-09-14 16:49	27.38	OK	6136	2026-09-14 16:50	25.88	OK
6137	2026-09-14 16:51	27.98	OK	6138	2026-09-14 16:52	25.80	OK
6139	2026-09-14 16:53	25.81	OK	6140	2026-09-14 16:54	26.45	OK
6141	2026-09-14 16:55	27.38	OK	6142	2026-09-14 16:56	25.76	OK
6143	2026-09-14 16:57	25.29	OK	6144	2026-09-14 16:58	25.71	OK
6145	2026-09-14 16:59	25.00	OK	6146	2026-09-14 17:00	27.74	OK
6147	2026-09-14 17:01	26.94	OK	6148	2026-09-14 17:02	27.35	OK
6149	2026-09-14 17:03	27.53	OK	6150	2026-09-14 17:04	27.29	OK
6151	2026-09-14 17:05	26.52	OK	6152	2026-09-14 17:06	25.95	OK
6153	2026-09-14 17:07	27.54	OK	6154	2026-09-14 17:08	25.94	OK
6155	2026-09-14 17:09	27.15	OK	6156	2026-09-14 17:10	26.88	OK
6157	2026-09-14 17:11	26.35	OK	6158	2026-09-14 17:12	26.63	OK
6159	2026-09-14 17:13	27.31	OK	6160	2026-09-14 17:14	27.40	OK
6161	2026-09-14 17:15	27.05	OK	6162	2026-09-14 17:16	25.84	OK
6163	2026-09-14 17:17	26.04	OK	6164	2026-09-14 17:18	27.27	OK
6165	2026-09-14 17:19	26.65	OK	6166	2026-09-14 17:20	26.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6167	2026-09-14 17:21	25.79	OK	6168	2026-09-14 17:22	26.13	OK
6169	2026-09-14 17:23	27.86	OK	6170	2026-09-14 17:24	26.49	OK
6171	2026-09-14 17:25	27.58	OK	6172	2026-09-14 17:26	27.53	OK
6173	2026-09-14 17:27	28.11	OK	6174	2026-09-14 17:28	27.36	OK
6175	2026-09-14 17:29	28.04	OK	6176	2026-09-14 17:30	26.84	OK
6177	2026-09-14 17:31	26.90	OK	6178	2026-09-14 17:32	27.14	OK
6179	2026-09-14 17:33	27.29	OK	6180	2026-09-14 17:34	27.81	OK
6181	2026-09-14 17:35	27.54	OK	6182	2026-09-14 17:36	26.76	OK
6183	2026-09-14 17:37	26.38	OK	6184	2026-09-14 17:38	26.35	OK
6185	2026-09-14 17:39	26.90	OK	6186	2026-09-14 17:40	26.42	OK
6187	2026-09-14 17:41	25.97	OK	6188	2026-09-14 17:42	26.70	OK
6189	2026-09-14 17:43	25.23	OK	6190	2026-09-14 17:44	26.53	OK
6191	2026-09-14 17:45	26.62	OK	6192	2026-09-14 17:46	27.81	OK
6193	2026-09-14 17:47	28.13	OK	6194	2026-09-14 17:48	27.73	OK
6195	2026-09-14 17:49	26.40	OK	6196	2026-09-14 17:50	28.25	OK
6197	2026-09-14 17:51	27.32	OK	6198	2026-09-14 17:52	27.29	OK
6199	2026-09-14 17:53	26.73	OK	6200	2026-09-14 17:54	26.89	OK
6201	2026-09-14 17:55	26.96	OK	6202	2026-09-14 17:56	27.86	OK
6203	2026-09-14 17:57	26.07	OK	6204	2026-09-14 17:58	27.07	OK
6205	2026-09-14 17:59	28.00	OK	6206	2026-09-14 18:00	28.22	OK
6207	2026-09-14 18:01	26.49	OK	6208	2026-09-14 18:02	25.63	OK
6209	2026-09-14 18:03	27.41	OK	6210	2026-09-14 18:04	27.28	OK
6211	2026-09-14 18:05	27.02	OK	6212	2026-09-14 18:06	26.60	OK
6213	2026-09-14 18:07	27.76	OK	6214	2026-09-14 18:08	28.84	OK
6215	2026-09-14 18:09	27.91	OK	6216	2026-09-14 18:10	26.90	OK
6217	2026-09-14 18:11	27.00	OK	6218	2026-09-14 18:12	26.62	OK
6219	2026-09-14 18:13	27.11	OK	6220	2026-09-14 18:14	28.08	OK
6221	2026-09-14 18:15	27.31	OK	6222	2026-09-14 18:16	26.91	OK
6223	2026-09-14 18:17	26.90	OK	6224	2026-09-14 18:18	26.76	OK
6225	2026-09-14 18:19	27.20	OK	6226	2026-09-14 18:20	25.28	OK
6227	2026-09-14 18:21	27.10	OK	6228	2026-09-14 18:22	26.52	OK
6229	2026-09-14 18:23	26.84	OK	6230	2026-09-14 18:24	26.73	OK
6231	2026-09-14 18:25	27.36	OK	6232	2026-09-14 18:26	29.18	OK
6233	2026-09-14 18:27	26.61	OK	6234	2026-09-14 18:28	27.52	OK
6235	2026-09-14 18:29	25.66	OK	6236	2026-09-14 18:30	27.30	OK
6237	2026-09-14 18:31	28.95	OK	6238	2026-09-14 18:32	27.95	OK
6239	2026-09-14 18:33	26.73	OK	6240	2026-09-14 18:34	27.43	OK
6241	2026-09-14 18:35	27.33	OK	6242	2026-09-14 18:36	28.25	OK
6243	2026-09-14 18:37	28.68	OK	6244	2026-09-14 18:38	27.37	OK
6245	2026-09-14 18:39	28.11	OK	6246	2026-09-14 18:40	29.15	OK
6247	2026-09-14 18:41	28.91	OK	6248	2026-09-14 18:42	27.65	OK
6249	2026-09-14 18:43	28.46	OK	6250	2026-09-14 18:44	26.57	OK
6251	2026-09-14 18:45	28.34	OK	6252	2026-09-14 18:46	27.99	OK
6253	2026-09-14 18:47	27.02	OK	6254	2026-09-14 18:48	26.75	OK
6255	2026-09-14 18:49	27.42	OK	6256	2026-09-14 18:50	27.26	OK
6257	2026-09-14 18:51	27.23	OK	6258	2026-09-14 18:52	28.23	OK
6259	2026-09-14 18:53	29.08	OK	6260	2026-09-14 18:54	28.04	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6261	2026-09-14 18:55	26.83	OK	6262	2026-09-14 18:56	27.19	OK
6263	2026-09-14 18:57	26.44	OK	6264	2026-09-14 18:58	25.99	OK
6265	2026-09-14 18:59	28.45	OK	6266	2026-09-14 19:00	28.17	OK
6267	2026-09-14 19:01	28.33	OK	6268	2026-09-14 19:02	27.25	OK
6269	2026-09-14 19:03	27.00	OK	6270	2026-09-14 19:04	27.59	OK
6271	2026-09-14 19:05	28.35	OK	6272	2026-09-14 19:06	27.83	OK
6273	2026-09-14 19:07	28.39	OK	6274	2026-09-14 19:08	28.13	OK
6275	2026-09-14 19:09	28.25	OK	6276	2026-09-14 19:10	27.81	OK
6277	2026-09-14 19:11	27.01	OK	6278	2026-09-14 19:12	26.49	OK
6279	2026-09-14 19:13	27.29	OK	6280	2026-09-14 19:14	28.51	OK
6281	2026-09-14 19:15	28.21	OK	6282	2026-09-14 19:16	27.47	OK
6283	2026-09-14 19:17	27.77	OK	6284	2026-09-14 19:18	27.53	OK
6285	2026-09-14 19:19	28.20	OK	6286	2026-09-14 19:20	27.28	OK
6287	2026-09-14 19:21	27.14	OK	6288	2026-09-14 19:22	28.01	OK
6289	2026-09-14 19:23	28.40	OK	6290	2026-09-14 19:24	27.36	OK
6291	2026-09-14 19:25	27.86	OK	6292	2026-09-14 19:26	27.47	OK
6293	2026-09-14 19:27	26.33	OK	6294	2026-09-14 19:28	27.46	OK
6295	2026-09-14 19:29	28.05	OK	6296	2026-09-14 19:30	27.61	OK
6297	2026-09-14 19:31	29.50	OK	6298	2026-09-14 19:32	28.54	OK
6299	2026-09-14 19:33	26.65	OK	6300	2026-09-14 19:34	28.76	OK
6301	2026-09-14 19:35	27.08	OK	6302	2026-09-14 19:36	27.57	OK
6303	2026-09-14 19:37	28.79	OK	6304	2026-09-14 19:38	28.31	OK
6305	2026-09-14 19:39	27.66	OK	6306	2026-09-14 19:40	28.00	OK
6307	2026-09-14 19:41	28.49	OK	6308	2026-09-14 19:42	27.11	OK
6309	2026-09-14 19:43	27.76	OK	6310	2026-09-14 19:44	27.76	OK
6311	2026-09-14 19:45	28.33	OK	6312	2026-09-14 19:46	29.63	OK
6313	2026-09-14 19:47	28.15	OK	6314	2026-09-14 19:48	29.06	OK
6315	2026-09-14 19:49	29.30	OK	6316	2026-09-14 19:50	28.11	OK
6317	2026-09-14 19:51	30.18	OK	6318	2026-09-14 19:52	27.89	OK
6319	2026-09-14 19:53	28.74	OK	6320	2026-09-14 19:54	28.38	OK
6321	2026-09-14 19:55	26.69	OK	6322	2026-09-14 19:56	27.92	OK
6323	2026-09-14 19:57	28.16	OK	6324	2026-09-14 19:58	29.62	OK
6325	2026-09-14 19:59	26.88	OK	6326	2026-09-14 20:00	27.81	OK
6327	2026-09-14 20:01	27.65	OK	6328	2026-09-14 20:02	27.06	OK
6329	2026-09-14 20:03	28.84	OK	6330	2026-09-14 20:04	28.22	OK
6331	2026-09-14 20:05	28.65	OK	6332	2026-09-14 20:06	28.66	OK
6333	2026-09-14 20:07	27.16	OK	6334	2026-09-14 20:08	28.37	OK
6335	2026-09-14 20:09	27.38	OK	6336	2026-09-14 20:10	28.42	OK
6337	2026-09-14 20:11	28.07	OK	6338	2026-09-14 20:12	28.04	OK
6339	2026-09-14 20:13	29.42	OK	6340	2026-09-14 20:14	27.87	OK
6341	2026-09-14 20:15	28.57	OK	6342	2026-09-14 20:16	27.58	OK
6343	2026-09-14 20:17	28.11	OK	6344	2026-09-14 20:18	27.58	OK
6345	2026-09-14 20:19	28.66	OK	6346	2026-09-14 20:20	28.18	OK
6347	2026-09-14 20:21	28.27	OK	6348	2026-09-14 20:22	29.81	OK
6349	2026-09-14 20:23	29.38	OK	6350	2026-09-14 20:24	28.56	OK
6351	2026-09-14 20:25	28.37	OK	6352	2026-09-14 20:26	27.78	OK
6353	2026-09-14 20:27	29.27	OK	6354	2026-09-14 20:28	27.88	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6355	2026-09-14 20:29	27.84	OK	6356	2026-09-14 20:30	28.88	OK
6357	2026-09-14 20:31	27.97	OK	6358	2026-09-14 20:32	27.92	OK
6359	2026-09-14 20:33	27.58	OK	6360	2026-09-14 20:34	28.67	OK
6361	2026-09-14 20:35	28.69	OK	6362	2026-09-14 20:36	28.97	OK
6363	2026-09-14 20:37	28.92	OK	6364	2026-09-14 20:38	29.32	OK
6365	2026-09-14 20:39	28.26	OK	6366	2026-09-14 20:40	28.99	OK
6367	2026-09-14 20:41	28.44	OK	6368	2026-09-14 20:42	28.61	OK
6369	2026-09-14 20:43	26.59	OK	6370	2026-09-14 20:44	27.84	OK
6371	2026-09-14 20:45	28.99	OK	6372	2026-09-14 20:46	29.60	OK
6373	2026-09-14 20:47	28.70	OK	6374	2026-09-14 20:48	29.41	OK
6375	2026-09-14 20:49	27.52	OK	6376	2026-09-14 20:50	29.37	OK
6377	2026-09-14 20:51	27.93	OK	6378	2026-09-14 20:52	28.98	OK
6379	2026-09-14 20:53	28.67	OK	6380	2026-09-14 20:54	29.31	OK
6381	2026-09-14 20:55	28.28	OK	6382	2026-09-14 20:56	28.52	OK
6383	2026-09-14 20:57	28.37	OK	6384	2026-09-14 20:58	28.69	OK
6385	2026-09-14 20:59	29.19	OK	6386	2026-09-14 21:00	30.21	OK
6387	2026-09-14 21:01	29.46	OK	6388	2026-09-14 21:02	28.49	OK
6389	2026-09-14 21:03	29.91	OK	6390	2026-09-14 21:04	28.43	OK
6391	2026-09-14 21:05	29.33	OK	6392	2026-09-14 21:06	28.68	OK
6393	2026-09-14 21:07	30.13	OK	6394	2026-09-14 21:08	28.07	OK
6395	2026-09-14 21:09	29.19	OK	6396	2026-09-14 21:10	28.48	OK
6397	2026-09-14 21:11	29.33	OK	6398	2026-09-14 21:12	28.18	OK
6399	2026-09-14 21:13	29.91	OK	6400	2026-09-14 21:14	28.47	OK
6401	2026-09-14 21:15	29.52	OK	6402	2026-09-14 21:16	28.65	OK
6403	2026-09-14 21:17	29.75	OK	6404	2026-09-14 21:18	29.62	OK
6405	2026-09-14 21:19	28.93	OK	6406	2026-09-14 21:20	28.85	OK
6407	2026-09-14 21:21	29.36	OK	6408	2026-09-14 21:22	28.04	OK
6409	2026-09-14 21:23	28.70	OK	6410	2026-09-14 21:24	29.45	OK
6411	2026-09-14 21:25	29.67	OK	6412	2026-09-14 21:26	29.87	OK
6413	2026-09-14 21:27	30.11	OK	6414	2026-09-14 21:28	30.00	OK
6415	2026-09-14 21:29	28.97	OK	6416	2026-09-14 21:30	28.88	OK
6417	2026-09-14 21:31	29.09	OK	6418	2026-09-14 21:32	29.77	OK
6419	2026-09-14 21:33	28.95	OK	6420	2026-09-14 21:34	28.21	OK
6421	2026-09-14 21:35	29.70	OK	6422	2026-09-14 21:36	29.24	OK
6423	2026-09-14 21:37	28.99	OK	6424	2026-09-14 21:38	29.70	OK
6425	2026-09-14 21:39	29.18	OK	6426	2026-09-14 21:40	29.53	OK
6427	2026-09-14 21:41	28.30	OK	6428	2026-09-14 21:42	28.98	OK
6429	2026-09-14 21:43	30.65	OK	6430	2026-09-14 21:44	29.97	OK
6431	2026-09-14 21:45	28.87	OK	6432	2026-09-14 21:46	28.96	OK
6433	2026-09-14 21:47	29.22	OK	6434	2026-09-14 21:48	29.18	OK
6435	2026-09-14 21:49	28.80	OK	6436	2026-09-14 21:50	28.92	OK
6437	2026-09-14 21:51	30.98	OK	6438	2026-09-14 21:52	29.25	OK
6439	2026-09-14 21:53	29.33	OK	6440	2026-09-14 21:54	29.18	OK
6441	2026-09-14 21:55	29.97	OK	6442	2026-09-14 21:56	28.18	OK
6443	2026-09-14 21:57	29.83	OK	6444	2026-09-14 21:58	29.19	OK
6445	2026-09-14 21:59	30.00	OK	6446	2026-09-14 22:00	28.70	OK
6447	2026-09-14 22:01	28.55	OK	6448	2026-09-14 22:02	30.40	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6449	2026-09-14 22:03	28.71	OK	6450	2026-09-14 22:04	28.34	OK
6451	2026-09-14 22:05	27.89	OK	6452	2026-09-14 22:06	29.65	OK
6453	2026-09-14 22:07	29.96	OK	6454	2026-09-14 22:08	29.17	OK
6455	2026-09-14 22:09	28.33	OK	6456	2026-09-14 22:10	28.60	OK
6457	2026-09-14 22:11	28.80	OK	6458	2026-09-14 22:12	30.41	OK
6459	2026-09-14 22:13	30.50	OK	6460	2026-09-14 22:14	30.35	OK
6461	2026-09-14 22:15	29.67	OK	6462	2026-09-14 22:16	28.86	OK
6463	2026-09-14 22:17	29.79	OK	6464	2026-09-14 22:18	30.93	OK
6465	2026-09-14 22:19	27.83	OK	6466	2026-09-14 22:20	29.49	OK
6467	2026-09-14 22:21	29.65	OK	6468	2026-09-14 22:22	31.24	OK
6469	2026-09-14 22:23	30.59	OK	6470	2026-09-14 22:24	30.88	OK
6471	2026-09-14 22:25	28.62	OK	6472	2026-09-14 22:26	29.25	OK
6473	2026-09-14 22:27	29.84	OK	6474	2026-09-14 22:28	29.18	OK
6475	2026-09-14 22:29	28.52	OK	6476	2026-09-14 22:30	29.50	OK
6477	2026-09-14 22:31	30.08	OK	6478	2026-09-14 22:32	30.62	OK
6479	2026-09-14 22:33	30.04	OK	6480	2026-09-14 22:34	28.80	OK
6481	2026-09-14 22:35	29.04	OK	6482	2026-09-14 22:36	29.55	OK
6483	2026-09-14 22:37	29.73	OK	6484	2026-09-14 22:38	31.05	OK
6485	2026-09-14 22:39	29.90	OK	6486	2026-09-14 22:40	29.70	OK
6487	2026-09-14 22:41	30.12	OK	6488	2026-09-14 22:42	29.05	OK
6489	2026-09-14 22:43	31.04	OK	6490	2026-09-14 22:44	29.58	OK
6491	2026-09-14 22:45	30.26	OK	6492	2026-09-14 22:46	30.06	OK
6493	2026-09-14 22:47	30.18	OK	6494	2026-09-14 22:48	29.74	OK
6495	2026-09-14 22:49	31.16	OK	6496	2026-09-14 22:50	29.97	OK
6497	2026-09-14 22:51	29.90	OK	6498	2026-09-14 22:52	28.38	OK
6499	2026-09-14 22:53	29.71	OK	6500	2026-09-14 22:54	30.50	OK
6501	2026-09-14 22:55	30.25	OK	6502	2026-09-14 22:56	31.02	OK
6503	2026-09-14 22:57	30.29	OK	6504	2026-09-14 22:58	30.96	OK
6505	2026-09-14 22:59	28.39	OK	6506	2026-09-14 23:00	28.65	OK
6507	2026-09-14 23:01	30.00	OK	6508	2026-09-14 23:02	31.46	OK
6509	2026-09-14 23:03	29.30	OK	6510	2026-09-14 23:04	29.08	OK
6511	2026-09-14 23:05	30.79	OK	6512	2026-09-14 23:06	28.81	OK
6513	2026-09-14 23:07	29.72	OK	6514	2026-09-14 23:08	29.76	OK
6515	2026-09-14 23:09	28.67	OK	6516	2026-09-14 23:10	29.84	OK
6517	2026-09-14 23:11	28.76	OK	6518	2026-09-14 23:12	29.10	OK
6519	2026-09-14 23:13	29.37	OK	6520	2026-09-14 23:14	30.94	OK
6521	2026-09-14 23:15	31.85	OK	6522	2026-09-14 23:16	29.99	OK
6523	2026-09-14 23:17	28.60	OK	6524	2026-09-14 23:18	30.49	OK
6525	2026-09-14 23:19	30.26	OK	6526	2026-09-14 23:20	29.97	OK
6527	2026-09-14 23:21	29.96	OK	6528	2026-09-14 23:22	29.80	OK
6529	2026-09-14 23:23	31.39	OK	6530	2026-09-14 23:24	30.17	OK
6531	2026-09-14 23:25	30.41	OK	6532	2026-09-14 23:26	31.09	OK
6533	2026-09-14 23:27	30.66	OK	6534	2026-09-14 23:28	29.39	OK
6535	2026-09-14 23:29	29.84	OK	6536	2026-09-14 23:30	30.26	OK
6537	2026-09-14 23:31	30.12	OK	6538	2026-09-14 23:32	29.51	OK
6539	2026-09-14 23:33	31.56	OK	6540	2026-09-14 23:34	28.80	OK
6541	2026-09-14 23:35	29.82	OK	6542	2026-09-14 23:36	29.53	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6543	2026-09-14 23:37	29.03	OK	6544	2026-09-14 23:38	30.56	OK
6545	2026-09-14 23:39	29.44	OK	6546	2026-09-14 23:40	30.70	OK
6547	2026-09-14 23:41	29.88	OK	6548	2026-09-14 23:42	30.51	OK
6549	2026-09-14 23:43	30.40	OK	6550	2026-09-14 23:44	29.94	OK
6551	2026-09-14 23:45	29.81	OK	6552	2026-09-14 23:46	28.87	OK
6553	2026-09-14 23:47	29.97	OK	6554	2026-09-14 23:48	30.28	OK
6555	2026-09-14 23:49	30.42	OK	6556	2026-09-14 23:50	31.13	OK
6557	2026-09-14 23:51	29.34	OK	6558	2026-09-14 23:52	29.57	OK
6559	2026-09-14 23:53	29.04	OK	6560	2026-09-14 23:54	30.15	OK
6561	2026-09-14 23:55	29.85	OK	6562	2026-09-14 23:56	30.25	OK
6563	2026-09-14 23:57	28.76	OK	6564	2026-09-14 23:58	30.11	OK
6565	2026-09-14 23:59	31.11	OK	6566	2026-09-15 00:00	28.94	OK
6567	2026-09-15 00:01	31.25	OK	6568	2026-09-15 00:02	30.14	OK
6569	2026-09-15 00:03	29.14	OK	6570	2026-09-15 00:04	28.70	OK
6571	2026-09-15 00:05	30.05	OK	6572	2026-09-15 00:06	30.10	OK
6573	2026-09-15 00:07	29.93	OK	6574	2026-09-15 00:08	29.86	OK
6575	2026-09-15 00:09	30.99	OK	6576	2026-09-15 00:10	30.86	OK
6577	2026-09-15 00:11	28.58	OK	6578	2026-09-15 00:12	30.12	OK
6579	2026-09-15 00:13	29.63	OK	6580	2026-09-15 00:14	30.56	OK
6581	2026-09-15 00:15	28.51	OK	6582	2026-09-15 00:16	29.52	OK
6583	2026-09-15 00:17	28.93	OK	6584	2026-09-15 00:18	30.96	OK
6585	2026-09-15 00:19	30.47	OK	6586	2026-09-15 00:20	30.29	OK
6587	2026-09-15 00:21	29.89	OK	6588	2026-09-15 00:22	30.24	OK
6589	2026-09-15 00:23	31.51	OK	6590	2026-09-15 00:24	29.16	OK
6591	2026-09-15 00:25	29.67	OK	6592	2026-09-15 00:26	29.63	OK
6593	2026-09-15 00:27	30.35	OK	6594	2026-09-15 00:28	29.57	OK
6595	2026-09-15 00:29	30.62	OK	6596	2026-09-15 00:30	30.88	OK
6597	2026-09-15 00:31	29.76	OK	6598	2026-09-15 00:32	29.69	OK
6599	2026-09-15 00:33	30.28	OK	6600	2026-09-15 00:34	30.13	OK
6601	2026-09-15 00:35	30.16	OK	6602	2026-09-15 00:36	30.99	OK
6603	2026-09-15 00:37	30.63	OK	6604	2026-09-15 00:38	31.07	OK
6605	2026-09-15 00:39	32.05	OK	6606	2026-09-15 00:40	28.85	OK
6607	2026-09-15 00:41	30.69	OK	6608	2026-09-15 00:42	30.18	OK
6609	2026-09-15 00:43	30.15	OK	6610	2026-09-15 00:44	29.00	OK
6611	2026-09-15 00:45	30.73	OK	6612	2026-09-15 00:46	29.73	OK
6613	2026-09-15 00:47	30.26	OK	6614	2026-09-15 00:48	29.92	OK
6615	2026-09-15 00:49	30.69	OK	6616	2026-09-15 00:50	30.63	OK
6617	2026-09-15 00:51	30.10	OK	6618	2026-09-15 00:52	29.88	OK
6619	2026-09-15 00:53	30.30	OK	6620	2026-09-15 00:54	31.37	OK
6621	2026-09-15 00:55	31.43	OK	6622	2026-09-15 00:56	30.33	OK
6623	2026-09-15 00:57	30.36	OK	6624	2026-09-15 00:58	30.67	OK
6625	2026-09-15 00:59	30.67	OK	6626	2026-09-15 01:00	28.58	OK
6627	2026-09-15 01:01	31.10	OK	6628	2026-09-15 01:02	30.51	OK
6629	2026-09-15 01:03	29.48	OK	6630	2026-09-15 01:04	30.80	OK
6631	2026-09-15 01:05	30.28	OK	6632	2026-09-15 01:06	29.72	OK
6633	2026-09-15 01:07	31.29	OK	6634	2026-09-15 01:08	30.30	OK
6635	2026-09-15 01:09	30.73	OK	6636	2026-09-15 01:10	30.58	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6637	2026-09-15 01:11	30.21	OK	6638	2026-09-15 01:12	31.05	OK
6639	2026-09-15 01:13	29.94	OK	6640	2026-09-15 01:14	30.37	OK
6641	2026-09-15 01:15	31.72	OK	6642	2026-09-15 01:16	30.79	OK
6643	2026-09-15 01:17	31.12	OK	6644	2026-09-15 01:18	29.58	OK
6645	2026-09-15 01:19	30.29	OK	6646	2026-09-15 01:20	30.48	OK
6647	2026-09-15 01:21	29.34	OK	6648	2026-09-15 01:22	30.49	OK
6649	2026-09-15 01:23	31.22	OK	6650	2026-09-15 01:24	29.81	OK
6651	2026-09-15 01:25	31.13	OK	6652	2026-09-15 01:26	30.03	OK
6653	2026-09-15 01:27	29.97	OK	6654	2026-09-15 01:28	30.23	OK
6655	2026-09-15 01:29	29.46	OK	6656	2026-09-15 01:30	30.88	OK
6657	2026-09-15 01:31	29.76	OK	6658	2026-09-15 01:32	30.49	OK
6659	2026-09-15 01:33	29.63	OK	6660	2026-09-15 01:34	30.43	OK
6661	2026-09-15 01:35	29.87	OK	6662	2026-09-15 01:36	30.31	OK
6663	2026-09-15 01:37	31.06	OK	6664	2026-09-15 01:38	28.52	OK
6665	2026-09-15 01:39	30.45	OK	6666	2026-09-15 01:40	28.96	OK
6667	2026-09-15 01:41	30.95	OK	6668	2026-09-15 01:42	30.04	OK
6669	2026-09-15 01:43	30.18	OK	6670	2026-09-15 01:44	31.01	OK
6671	2026-09-15 01:45	30.48	OK	6672	2026-09-15 01:46	30.15	OK
6673	2026-09-15 01:47	31.05	OK	6674	2026-09-15 01:48	30.48	OK
6675	2026-09-15 01:49	30.73	OK	6676	2026-09-15 01:50	30.51	OK
6677	2026-09-15 01:51	31.47	OK	6678	2026-09-15 01:52	31.45	OK
6679	2026-09-15 01:53	30.40	OK	6680	2026-09-15 01:54	29.82	OK
6681	2026-09-15 01:55	30.12	OK	6682	2026-09-15 01:56	29.97	OK
6683	2026-09-15 01:57	30.89	OK	6684	2026-09-15 01:58	29.57	OK
6685	2026-09-15 01:59	29.96	OK	6686	2026-09-15 02:00	31.21	OK
6687	2026-09-15 02:01	29.80	OK	6688	2026-09-15 02:02	29.92	OK
6689	2026-09-15 02:03	29.75	OK	6690	2026-09-15 02:04	32.01	OK
6691	2026-09-15 02:05	30.14	OK	6692	2026-09-15 02:06	30.09	OK
6693	2026-09-15 02:07	30.02	OK	6694	2026-09-15 02:08	29.70	OK
6695	2026-09-15 02:09	30.68	OK	6696	2026-09-15 02:10	29.87	OK
6697	2026-09-15 02:11	28.92	OK	6698	2026-09-15 02:12	29.92	OK
6699	2026-09-15 02:13	30.05	OK	6700	2026-09-15 02:14	30.22	OK
6701	2026-09-15 02:15	29.43	OK	6702	2026-09-15 02:16	30.09	OK
6703	2026-09-15 02:17	29.68	OK	6704	2026-09-15 02:18	30.03	OK
6705	2026-09-15 02:19	29.20	OK	6706	2026-09-15 02:20	29.41	OK
6707	2026-09-15 02:21	29.92	OK	6708	2026-09-15 02:22	30.72	OK
6709	2026-09-15 02:23	31.51	OK	6710	2026-09-15 02:24	27.98	OK
6711	2026-09-15 02:25	30.12	OK	6712	2026-09-15 02:26	28.94	OK
6713	2026-09-15 02:27	30.17	OK	6714	2026-09-15 02:28	29.53	OK
6715	2026-09-15 02:29	29.06	OK	6716	2026-09-15 02:30	31.46	OK
6717	2026-09-15 02:31	29.04	OK	6718	2026-09-15 02:32	29.70	OK
6719	2026-09-15 02:33	29.59	OK	6720	2026-09-15 02:34	30.35	OK
6721	2026-09-15 02:35	29.45	OK	6722	2026-09-15 02:36	30.18	OK
6723	2026-09-15 02:37	29.54	OK	6724	2026-09-15 02:38	31.13	OK
6725	2026-09-15 02:39	31.37	OK	6726	2026-09-15 02:40	30.09	OK
6727	2026-09-15 02:41	29.56	OK	6728	2026-09-15 02:42	30.32	OK
6729	2026-09-15 02:43	30.06	OK	6730	2026-09-15 02:44	31.21	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6731	2026-09-15 02:45	30.74	OK	6732	2026-09-15 02:46	31.77	OK
6733	2026-09-15 02:47	29.02	OK	6734	2026-09-15 02:48	30.70	OK
6735	2026-09-15 02:49	30.45	OK	6736	2026-09-15 02:50	29.46	OK
6737	2026-09-15 02:51	29.60	OK	6738	2026-09-15 02:52	30.10	OK
6739	2026-09-15 02:53	30.59	OK	6740	2026-09-15 02:54	30.12	OK
6741	2026-09-15 02:55	29.92	OK	6742	2026-09-15 02:56	28.47	OK
6743	2026-09-15 02:57	31.92	OK	6744	2026-09-15 02:58	29.36	OK
6745	2026-09-15 02:59	29.54	OK	6746	2026-09-15 03:00	30.51	OK
6747	2026-09-15 03:01	30.41	OK	6748	2026-09-15 03:02	30.36	OK
6749	2026-09-15 03:03	30.43	OK	6750	2026-09-15 03:04	31.07	OK
6751	2026-09-15 03:05	29.81	OK	6752	2026-09-15 03:06	29.66	OK
6753	2026-09-15 03:07	29.95	OK	6754	2026-09-15 03:08	29.22	OK
6755	2026-09-15 03:09	31.16	OK	6756	2026-09-15 03:10	30.80	OK
6757	2026-09-15 03:11	30.84	OK	6758	2026-09-15 03:12	30.67	OK
6759	2026-09-15 03:13	29.67	OK	6760	2026-09-15 03:14	30.34	OK
6761	2026-09-15 03:15	31.20	OK	6762	2026-09-15 03:16	29.40	OK
6763	2026-09-15 03:17	30.23	OK	6764	2026-09-15 03:18	30.56	OK
6765	2026-09-15 03:19	29.51	OK	6766	2026-09-15 03:20	29.94	OK
6767	2026-09-15 03:21	30.94	OK	6768	2026-09-15 03:22	31.18	OK
6769	2026-09-15 03:23	28.94	OK	6770	2026-09-15 03:24	29.07	OK
6771	2026-09-15 03:25	30.82	OK	6772	2026-09-15 03:26	29.92	OK
6773	2026-09-15 03:27	30.85	OK	6774	2026-09-15 03:28	30.37	OK
6775	2026-09-15 03:29	30.35	OK	6776	2026-09-15 03:30	29.34	OK
6777	2026-09-15 03:31	28.81	OK	6778	2026-09-15 03:32	29.65	OK
6779	2026-09-15 03:33	30.44	OK	6780	2026-09-15 03:34	29.77	OK
6781	2026-09-15 03:35	30.87	OK	6782	2026-09-15 03:36	30.45	OK
6783	2026-09-15 03:37	29.79	OK	6784	2026-09-15 03:38	30.25	OK
6785	2026-09-15 03:39	31.10	OK	6786	2026-09-15 03:40	31.42	OK
6787	2026-09-15 03:41	29.87	OK	6788	2026-09-15 03:42	29.28	OK
6789	2026-09-15 03:43	29.90	OK	6790	2026-09-15 03:44	29.96	OK
6791	2026-09-15 03:45	30.75	OK	6792	2026-09-15 03:46	30.73	OK
6793	2026-09-15 03:47	29.34	OK	6794	2026-09-15 03:48	28.00	OK
6795	2026-09-15 03:49	30.80	OK	6796	2026-09-15 03:50	29.53	OK
6797	2026-09-15 03:51	30.19	OK	6798	2026-09-15 03:52	29.08	OK
6799	2026-09-15 03:53	30.89	OK	6800	2026-09-15 03:54	30.29	OK
6801	2026-09-15 03:55	30.46	OK	6802	2026-09-15 03:56	30.80	OK
6803	2026-09-15 03:57	30.60	OK	6804	2026-09-15 03:58	29.82	OK
6805	2026-09-15 03:59	29.42	OK	6806	2026-09-15 04:00	29.27	OK
6807	2026-09-15 04:01	30.00	OK	6808	2026-09-15 04:02	28.79	OK
6809	2026-09-15 04:03	29.29	OK	6810	2026-09-15 04:04	29.33	OK
6811	2026-09-15 04:05	28.78	OK	6812	2026-09-15 04:06	30.38	OK
6813	2026-09-15 04:07	29.15	OK	6814	2026-09-15 04:08	29.08	OK
6815	2026-09-15 04:09	31.16	OK	6816	2026-09-15 04:10	30.05	OK
6817	2026-09-15 04:11	29.37	OK	6818	2026-09-15 04:12	28.77	OK
6819	2026-09-15 04:13	30.18	OK	6820	2026-09-15 04:14	29.90	OK
6821	2026-09-15 04:15	29.77	OK	6822	2026-09-15 04:16	30.50	OK
6823	2026-09-15 04:17	29.24	OK	6824	2026-09-15 04:18	31.14	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6825	2026-09-15 04:19	29.96	OK	6826	2026-09-15 04:20	29.02	OK
6827	2026-09-15 04:21	30.27	OK	6828	2026-09-15 04:22	28.32	OK
6829	2026-09-15 04:23	29.62	OK	6830	2026-09-15 04:24	28.50	OK
6831	2026-09-15 04:25	30.38	OK	6832	2026-09-15 04:26	29.52	OK
6833	2026-09-15 04:27	30.25	OK	6834	2026-09-15 04:28	28.58	OK
6835	2026-09-15 04:29	30.49	OK	6836	2026-09-15 04:30	30.12	OK
6837	2026-09-15 04:31	29.19	OK	6838	2026-09-15 04:32	29.30	OK
6839	2026-09-15 04:33	30.09	OK	6840	2026-09-15 04:34	29.30	OK
6841	2026-09-15 04:35	29.30	OK	6842	2026-09-15 04:36	28.70	OK
6843	2026-09-15 04:37	29.24	OK	6844	2026-09-15 04:38	30.17	OK
6845	2026-09-15 04:39	31.10	OK	6846	2026-09-15 04:40	29.26	OK
6847	2026-09-15 04:41	29.75	OK	6848	2026-09-15 04:42	29.32	OK
6849	2026-09-15 04:43	29.02	OK	6850	2026-09-15 04:44	29.62	OK
6851	2026-09-15 04:45	29.04	OK	6852	2026-09-15 04:46	29.34	OK
6853	2026-09-15 04:47	29.63	OK	6854	2026-09-15 04:48	28.38	OK
6855	2026-09-15 04:49	30.49	OK	6856	2026-09-15 04:50	30.79	OK
6857	2026-09-15 04:51	29.43	OK	6858	2026-09-15 04:52	29.92	OK
6859	2026-09-15 04:53	29.57	OK	6860	2026-09-15 04:54	29.15	OK
6861	2026-09-15 04:55	29.69	OK	6862	2026-09-15 04:56	28.58	OK
6863	2026-09-15 04:57	30.08	OK	6864	2026-09-15 04:58	29.75	OK
6865	2026-09-15 04:59	29.70	OK	6866	2026-09-15 05:00	29.86	OK
6867	2026-09-15 05:01	29.71	OK	6868	2026-09-15 05:02	29.49	OK
6869	2026-09-15 05:03	29.17	OK	6870	2026-09-15 05:04	29.97	OK
6871	2026-09-15 05:05	28.95	OK	6872	2026-09-15 05:06	27.89	OK
6873	2026-09-15 05:07	29.92	OK	6874	2026-09-15 05:08	28.86	OK
6875	2026-09-15 05:09	29.30	OK	6876	2026-09-15 05:10	28.89	OK
6877	2026-09-15 05:11	30.11	OK	6878	2026-09-15 05:12	30.01	OK
6879	2026-09-15 05:13	28.84	OK	6880	2026-09-15 05:14	30.44	OK
6881	2026-09-15 05:15	29.32	OK	6882	2026-09-15 05:16	29.58	OK
6883	2026-09-15 05:17	28.60	OK	6884	2026-09-15 05:18	29.49	OK
6885	2026-09-15 05:19	28.21	OK	6886	2026-09-15 05:20	28.27	OK
6887	2026-09-15 05:21	30.10	OK	6888	2026-09-15 05:22	28.80	OK
6889	2026-09-15 05:23	29.98	OK	6890	2026-09-15 05:24	28.68	OK
6891	2026-09-15 05:25	29.07	OK	6892	2026-09-15 05:26	28.40	OK
6893	2026-09-15 05:27	27.92	OK	6894	2026-09-15 05:28	28.34	OK
6895	2026-09-15 05:29	28.11	OK	6896	2026-09-15 05:30	29.38	OK
6897	2026-09-15 05:31	27.57	OK	6898	2026-09-15 05:32	28.85	OK
6899	2026-09-15 05:33	30.39	OK	6900	2026-09-15 05:34	28.09	OK
6901	2026-09-15 05:35	28.64	OK	6902	2026-09-15 05:36	29.91	OK
6903	2026-09-15 05:37	28.79	OK	6904	2026-09-15 05:38	28.02	OK
6905	2026-09-15 05:39	28.87	OK	6906	2026-09-15 05:40	27.86	OK
6907	2026-09-15 05:41	28.99	OK	6908	2026-09-15 05:42	28.98	OK
6909	2026-09-15 05:43	29.92	OK	6910	2026-09-15 05:44	29.33	OK
6911	2026-09-15 05:45	30.44	OK	6912	2026-09-15 05:46	29.82	OK
6913	2026-09-15 05:47	28.18	OK	6914	2026-09-15 05:48	29.23	OK
6915	2026-09-15 05:49	29.46	OK	6916	2026-09-15 05:50	29.56	OK
6917	2026-09-15 05:51	27.54	OK	6918	2026-09-15 05:52	28.22	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
6919	2026-09-15 05:53	29.34	OK	6920	2026-09-15 05:54	29.71	OK
6921	2026-09-15 05:55	28.62	OK	6922	2026-09-15 05:56	29.98	OK
6923	2026-09-15 05:57	29.40	OK	6924	2026-09-15 05:58	28.68	OK
6925	2026-09-15 05:59	29.62	OK	6926	2026-09-15 06:00	29.14	OK
6927	2026-09-15 06:01	28.21	OK	6928	2026-09-15 06:02	28.64	OK
6929	2026-09-15 06:03	28.57	OK	6930	2026-09-15 06:04	28.81	OK
6931	2026-09-15 06:05	28.31	OK	6932	2026-09-15 06:06	28.02	OK
6933	2026-09-15 06:07	27.85	OK	6934	2026-09-15 06:08	28.40	OK
6935	2026-09-15 06:09	28.40	OK	6936	2026-09-15 06:10	27.86	OK
6937	2026-09-15 06:11	28.54	OK	6938	2026-09-15 06:12	29.35	OK
6939	2026-09-15 06:13	27.68	OK	6940	2026-09-15 06:14	28.77	OK
6941	2026-09-15 06:15	27.28	OK	6942	2026-09-15 06:16	27.49	OK
6943	2026-09-15 06:17	29.82	OK	6944	2026-09-15 06:18	28.21	OK
6945	2026-09-15 06:19	27.85	OK	6946	2026-09-15 06:20	28.88	OK
6947	2026-09-15 06:21	28.28	OK	6948	2026-09-15 06:22	28.15	OK
6949	2026-09-15 06:23	29.73	OK	6950	2026-09-15 06:24	30.53	OK
6951	2026-09-15 06:25	28.22	OK	6952	2026-09-15 06:26	27.92	OK
6953	2026-09-15 06:27	28.95	OK	6954	2026-09-15 06:28	28.73	OK
6955	2026-09-15 06:29	27.28	OK	6956	2026-09-15 06:30	29.38	OK
6957	2026-09-15 06:31	28.89	OK	6958	2026-09-15 06:32	29.35	OK
6959	2026-09-15 06:33	26.63	OK	6960	2026-09-15 06:34	27.21	OK
6961	2026-09-15 06:35	28.42	OK	6962	2026-09-15 06:36	28.38	OK
6963	2026-09-15 06:37	28.92	OK	6964	2026-09-15 06:38	27.92	OK
6965	2026-09-15 06:39	28.35	OK	6966	2026-09-15 06:40	28.63	OK
6967	2026-09-15 06:41	28.42	OK	6968	2026-09-15 06:42	28.39	OK
6969	2026-09-15 06:43	28.04	OK	6970	2026-09-15 06:44	28.35	OK
6971	2026-09-15 06:45	28.88	OK	6972	2026-09-15 06:46	28.53	OK
6973	2026-09-15 06:47	28.43	OK	6974	2026-09-15 06:48	28.06	OK
6975	2026-09-15 06:49	29.48	OK	6976	2026-09-15 06:50	28.07	OK
6977	2026-09-15 06:51	29.73	OK	6978	2026-09-15 06:52	28.75	OK
6979	2026-09-15 06:53	30.05	OK	6980	2026-09-15 06:54	27.15	OK
6981	2026-09-15 06:55	27.25	OK	6982	2026-09-15 06:56	27.60	OK
6983	2026-09-15 06:57	28.54	OK	6984	2026-09-15 06:58	27.60	OK
6985	2026-09-15 06:59	28.18	OK	6986	2026-09-15 07:00	27.53	OK
6987	2026-09-15 07:01	29.04	OK	6988	2026-09-15 07:02	28.17	OK
6989	2026-09-15 07:03	28.23	OK	6990	2026-09-15 07:04	28.40	OK
6991	2026-09-15 07:05	29.15	OK	6992	2026-09-15 07:06	27.48	OK
6993	2026-09-15 07:07	27.79	OK	6994	2026-09-15 07:08	29.09	OK
6995	2026-09-15 07:09	27.57	OK	6996	2026-09-15 07:10	28.74	OK
6997	2026-09-15 07:11	27.99	OK	6998	2026-09-15 07:12	28.08	OK
6999	2026-09-15 07:13	29.11	OK	7000	2026-09-15 07:14	27.10	OK
7001	2026-09-15 07:15	28.16	OK	7002	2026-09-15 07:16	28.33	OK
7003	2026-09-15 07:17	28.67	OK	7004	2026-09-15 07:18	28.60	OK
7005	2026-09-15 07:19	27.17	OK	7006	2026-09-15 07:20	28.17	OK
7007	2026-09-15 07:21	27.69	OK	7008	2026-09-15 07:22	28.32	OK
7009	2026-09-15 07:23	28.15	OK	7010	2026-09-15 07:24	27.50	OK
7011	2026-09-15 07:25	27.73	OK	7012	2026-09-15 07:26	26.96	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7013	2026-09-15 07:27	27.83	OK	7014	2026-09-15 07:28	28.87	OK
7015	2026-09-15 07:29	28.05	OK	7016	2026-09-15 07:30	29.45	OK
7017	2026-09-15 07:31	29.05	OK	7018	2026-09-15 07:32	28.08	OK
7019	2026-09-15 07:33	27.21	OK	7020	2026-09-15 07:34	27.33	OK
7021	2026-09-15 07:35	26.82	OK	7022	2026-09-15 07:36	27.46	OK
7023	2026-09-15 07:37	27.51	OK	7024	2026-09-15 07:38	29.42	OK
7025	2026-09-15 07:39	27.42	OK	7026	2026-09-15 07:40	28.66	OK
7027	2026-09-15 07:41	27.42	OK	7028	2026-09-15 07:42	28.56	OK
7029	2026-09-15 07:43	28.31	OK	7030	2026-09-15 07:44	27.09	OK
7031	2026-09-15 07:45	28.68	OK	7032	2026-09-15 07:46	29.34	OK
7033	2026-09-15 07:47	28.95	OK	7034	2026-09-15 07:48	28.15	OK
7035	2026-09-15 07:49	28.14	OK	7036	2026-09-15 07:50	25.85	OK
7037	2026-09-15 07:51	27.69	OK	7038	2026-09-15 07:52	27.91	OK
7039	2026-09-15 07:53	27.41	OK	7040	2026-09-15 07:54	27.32	OK
7041	2026-09-15 07:55	26.85	OK	7042	2026-09-15 07:56	29.19	OK
7043	2026-09-15 07:57	27.42	OK	7044	2026-09-15 07:58	27.89	OK
7045	2026-09-15 07:59	27.62	OK	7046	2026-09-15 08:00	26.45	OK
7047	2026-09-15 08:01	28.62	OK	7048	2026-09-15 08:02	28.64	OK
7049	2026-09-15 08:03	26.22	OK	7050	2026-09-15 08:04	26.77	OK
7051	2026-09-15 08:05	27.68	OK	7052	2026-09-15 08:06	29.23	OK
7053	2026-09-15 08:07	27.52	OK	7054	2026-09-15 08:08	28.95	OK
7055	2026-09-15 08:09	27.99	OK	7056	2026-09-15 08:10	28.67	OK
7057	2026-09-15 08:11	27.80	OK	7058	2026-09-15 08:12	28.37	OK
7059	2026-09-15 08:13	27.39	OK	7060	2026-09-15 08:14	28.19	OK
7061	2026-09-15 08:15	26.70	OK	7062	2026-09-15 08:16	28.69	OK
7063	2026-09-15 08:17	27.37	OK	7064	2026-09-15 08:18	28.86	OK
7065	2026-09-15 08:19	27.48	OK	7066	2026-09-15 08:20	29.27	OK
7067	2026-09-15 08:21	28.03	OK	7068	2026-09-15 08:22	26.64	OK
7069	2026-09-15 08:23	28.53	OK	7070	2026-09-15 08:24	27.32	OK
7071	2026-09-15 08:25	27.40	OK	7072	2026-09-15 08:26	27.29	OK
7073	2026-09-15 08:27	27.84	OK	7074	2026-09-15 08:28	27.02	OK
7075	2026-09-15 08:29	26.34	OK	7076	2026-09-15 08:30	28.24	OK
7077	2026-09-15 08:31	27.69	OK	7078	2026-09-15 08:32	27.13	OK
7079	2026-09-15 08:33	27.36	OK	7080	2026-09-15 08:34	27.56	OK
7081	2026-09-15 08:35	26.98	OK	7082	2026-09-15 08:36	27.52	OK
7083	2026-09-15 08:37	27.68	OK	7084	2026-09-15 08:38	27.42	OK
7085	2026-09-15 08:39	26.45	OK	7086	2026-09-15 08:40	26.83	OK
7087	2026-09-15 08:41	28.96	OK	7088	2026-09-15 08:42	27.13	OK
7089	2026-09-15 08:43	25.75	OK	7090	2026-09-15 08:44	25.96	OK
7091	2026-09-15 08:45	28.33	OK	7092	2026-09-15 08:46	27.25	OK
7093	2026-09-15 08:47	28.47	OK	7094	2026-09-15 08:48	26.73	OK
7095	2026-09-15 08:49	27.67	OK	7096	2026-09-15 08:50	26.62	OK
7097	2026-09-15 08:51	26.13	OK	7098	2026-09-15 08:52	27.60	OK
7099	2026-09-15 08:53	27.35	OK	7100	2026-09-15 08:54	28.33	OK
7101	2026-09-15 08:55	27.14	OK	7102	2026-09-15 08:56	27.04	OK
7103	2026-09-15 08:57	26.23	OK	7104	2026-09-15 08:58	27.42	OK
7105	2026-09-15 08:59	25.50	OK	7106	2026-09-15 09:00	27.33	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7107	2026-09-15 09:01	27.47	OK	7108	2026-09-15 09:02	27.53	OK
7109	2026-09-15 09:03	26.47	OK	7110	2026-09-15 09:04	27.11	OK
7111	2026-09-15 09:05	26.09	OK	7112	2026-09-15 09:06	27.18	OK
7113	2026-09-15 09:07	27.99	OK	7114	2026-09-15 09:08	26.46	OK
7115	2026-09-15 09:09	27.80	OK	7116	2026-09-15 09:10	27.08	OK
7117	2026-09-15 09:11	28.08	OK	7118	2026-09-15 09:12	26.41	OK
7119	2026-09-15 09:13	27.23	OK	7120	2026-09-15 09:14	27.05	OK
7121	2026-09-15 09:15	26.73	OK	7122	2026-09-15 09:16	27.51	OK
7123	2026-09-15 09:17	27.38	OK	7124	2026-09-15 09:18	25.48	OK
7125	2026-09-15 09:19	27.13	OK	7126	2026-09-15 09:20	27.29	OK
7127	2026-09-15 09:21	26.74	OK	7128	2026-09-15 09:22	25.88	OK
7129	2026-09-15 09:23	26.26	OK	7130	2026-09-15 09:24	26.03	OK
7131	2026-09-15 09:25	26.13	OK	7132	2026-09-15 09:26	27.32	OK
7133	2026-09-15 09:27	26.47	OK	7134	2026-09-15 09:28	27.25	OK
7135	2026-09-15 09:29	25.72	OK	7136	2026-09-15 09:30	26.40	OK
7137	2026-09-15 09:31	25.62	OK	7138	2026-09-15 09:32	26.11	OK
7139	2026-09-15 09:33	27.91	OK	7140	2026-09-15 09:34	24.87	OK
7141	2026-09-15 09:35	27.05	OK	7142	2026-09-15 09:36	26.80	OK
7143	2026-09-15 09:37	25.95	OK	7144	2026-09-15 09:38	27.06	OK
7145	2026-09-15 09:39	27.22	OK	7146	2026-09-15 09:40	27.37	OK
7147	2026-09-15 09:41	27.41	OK	7148	2026-09-15 09:42	25.19	OK
7149	2026-09-15 09:43	25.80	OK	7150	2026-09-15 09:44	26.35	OK
7151	2026-09-15 09:45	26.67	OK	7152	2026-09-15 09:46	28.44	OK
7153	2026-09-15 09:47	26.42	OK	7154	2026-09-15 09:48	25.16	OK
7155	2026-09-15 09:49	26.57	OK	7156	2026-09-15 09:50	26.34	OK
7157	2026-09-15 09:51	28.35	OK	7158	2026-09-15 09:52	26.88	OK
7159	2026-09-15 09:53	26.12	OK	7160	2026-09-15 09:54	27.05	OK
7161	2026-09-15 09:55	26.25	OK	7162	2026-09-15 09:56	25.39	OK
7163	2026-09-15 09:57	25.59	OK	7164	2026-09-15 09:58	26.99	OK
7165	2026-09-15 09:59	27.50	OK	7166	2026-09-15 10:00	27.02	OK
7167	2026-09-15 10:01	26.85	OK	7168	2026-09-15 10:02	24.74	OK
7169	2026-09-15 10:03	27.09	OK	7170	2026-09-15 10:04	27.64	OK
7171	2026-09-15 10:05	26.50	OK	7172	2026-09-15 10:06	27.01	OK
7173	2026-09-15 10:07	26.80	OK	7174	2026-09-15 10:08	26.24	OK
7175	2026-09-15 10:09	26.20	OK	7176	2026-09-15 10:10	26.85	OK
7177	2026-09-15 10:11	26.21	OK	7178	2026-09-15 10:12	26.13	OK
7179	2026-09-15 10:13	26.63	OK	7180	2026-09-15 10:14	25.32	OK
7181	2026-09-15 10:15	27.90	OK	7182	2026-09-15 10:16	25.89	OK
7183	2026-09-15 10:17	25.98	OK	7184	2026-09-15 10:18	27.53	OK
7185	2026-09-15 10:19	27.56	OK	7186	2026-09-15 10:20	27.57	OK
7187	2026-09-15 10:21	25.92	OK	7188	2026-09-15 10:22	26.07	OK
7189	2026-09-15 10:23	24.50	OK	7190	2026-09-15 10:24	27.21	OK
7191	2026-09-15 10:25	24.87	OK	7192	2026-09-15 10:26	26.76	OK
7193	2026-09-15 10:27	25.36	OK	7194	2026-09-15 10:28	26.32	OK
7195	2026-09-15 10:29	26.13	OK	7196	2026-09-15 10:30	26.28	OK
7197	2026-09-15 10:31	24.52	OK	7198	2026-09-15 10:32	25.94	OK
7199	2026-09-15 10:33	26.04	OK	7200	2026-09-15 10:34	25.96	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7201	2026-09-15 10:35	25.43	OK	7202	2026-09-15 10:36	26.78	OK
7203	2026-09-15 10:37	26.53	OK	7204	2026-09-15 10:38	25.96	OK
7205	2026-09-15 10:39	26.55	OK	7206	2026-09-15 10:40	27.87	OK
7207	2026-09-15 10:41	25.25	OK	7208	2026-09-15 10:42	27.41	OK
7209	2026-09-15 10:43	24.98	OK	7210	2026-09-15 10:44	26.28	OK
7211	2026-09-15 10:45	27.04	OK	7212	2026-09-15 10:46	26.31	OK
7213	2026-09-15 10:47	25.46	OK	7214	2026-09-15 10:48	25.52	OK
7215	2026-09-15 10:49	25.71	OK	7216	2026-09-15 10:50	26.34	OK
7217	2026-09-15 10:51	25.65	OK	7218	2026-09-15 10:52	26.22	OK
7219	2026-09-15 10:53	25.54	OK	7220	2026-09-15 10:54	26.03	OK
7221	2026-09-15 10:55	25.55	OK	7222	2026-09-15 10:56	25.79	OK
7223	2026-09-15 10:57	25.99	OK	7224	2026-09-15 10:58	26.10	OK
7225	2026-09-15 10:59	25.79	OK	7226	2026-09-15 11:00	26.22	OK
7227	2026-09-15 11:01	25.79	OK	7228	2026-09-15 11:02	26.17	OK
7229	2026-09-15 11:03	27.75	OK	7230	2026-09-15 11:04	25.87	OK
7231	2026-09-15 11:05	24.56	OK	7232	2026-09-15 11:06	25.88	OK
7233	2026-09-15 11:07	25.53	OK	7234	2026-09-15 11:08	26.15	OK
7235	2026-09-15 11:09	26.42	OK	7236	2026-09-15 11:10	25.16	OK
7237	2026-09-15 11:11	27.55	OK	7238	2026-09-15 11:12	26.94	OK
7239	2026-09-15 11:13	25.70	OK	7240	2026-09-15 11:14	25.56	OK
7241	2026-09-15 11:15	26.43	OK	7242	2026-09-15 11:16	25.62	OK
7243	2026-09-15 11:17	25.46	OK	7244	2026-09-15 11:18	25.73	OK
7245	2026-09-15 11:19	25.62	OK	7246	2026-09-15 11:20	25.82	OK
7247	2026-09-15 11:21	26.01	OK	7248	2026-09-15 11:22	25.09	OK
7249	2026-09-15 11:23	24.26	OK	7250	2026-09-15 11:24	25.49	OK
7251	2026-09-15 11:25	25.90	OK	7252	2026-09-15 11:26	25.08	OK
7253	2026-09-15 11:27	25.08	OK	7254	2026-09-15 11:28	26.42	OK
7255	2026-09-15 11:29	25.39	OK	7256	2026-09-15 11:30	24.78	OK
7257	2026-09-15 11:31	25.46	OK	7258	2026-09-15 11:32	26.61	OK
7259	2026-09-15 11:33	26.98	OK	7260	2026-09-15 11:34	25.73	OK
7261	2026-09-15 11:35	26.16	OK	7262	2026-09-15 11:36	25.43	OK
7263	2026-09-15 11:37	25.51	OK	7264	2026-09-15 11:38	24.65	OK
7265	2026-09-15 11:39	25.79	OK	7266	2026-09-15 11:40	26.68	OK
7267	2026-09-15 11:41	24.95	OK	7268	2026-09-15 11:42	24.08	OK
7269	2026-09-15 11:43	26.51	OK	7270	2026-09-15 11:44	26.10	OK
7271	2026-09-15 11:45	27.15	OK	7272	2026-09-15 11:46	25.45	OK
7273	2026-09-15 11:47	25.56	OK	7274	2026-09-15 11:48	25.35	OK
7275	2026-09-15 11:49	26.82	OK	7276	2026-09-15 11:50	25.09	OK
7277	2026-09-15 11:51	25.78	OK	7278	2026-09-15 11:52	26.71	OK
7279	2026-09-15 11:53	26.11	OK	7280	2026-09-15 11:54	26.83	OK
7281	2026-09-15 11:55	25.60	OK	7282	2026-09-15 11:56	26.00	OK
7283	2026-09-15 11:57	26.11	OK	7284	2026-09-15 11:58	26.52	OK
7285	2026-09-15 11:59	27.73	OK	7286	2026-09-15 12:00	25.19	OK
7287	2026-09-15 12:01	26.68	OK	7288	2026-09-15 12:02	25.31	OK
7289	2026-09-15 12:03	25.80	OK	7290	2026-09-15 12:04	25.43	OK
7291	2026-09-15 12:05	26.59	OK	7292	2026-09-15 12:06	25.19	OK
7293	2026-09-15 12:07	25.57	OK	7294	2026-09-15 12:08	27.12	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7295	2026-09-15 12:09	24.23	OK	7296	2026-09-15 12:10	25.67	OK
7297	2026-09-15 12:11	25.82	OK	7298	2026-09-15 12:12	26.11	OK
7299	2026-09-15 12:13	25.20	OK	7300	2026-09-15 12:14	24.52	OK
7301	2026-09-15 12:15	25.35	OK	7302	2026-09-15 12:16	25.78	OK
7303	2026-09-15 12:17	25.46	OK	7304	2026-09-15 12:18	27.44	OK
7305	2026-09-15 12:19	26.05	OK	7306	2026-09-15 12:20	25.80	OK
7307	2026-09-15 12:21	25.49	OK	7308	2026-09-15 12:22	26.64	OK
7309	2026-09-15 12:23	25.76	OK	7310	2026-09-15 12:24	25.03	OK
7311	2026-09-15 12:25	27.33	OK	7312	2026-09-15 12:26	25.09	OK
7313	2026-09-15 12:27	25.75	OK	7314	2026-09-15 12:28	24.78	OK
7315	2026-09-15 12:29	26.13	OK	7316	2026-09-15 12:30	25.59	OK
7317	2026-09-15 12:31	24.92	OK	7318	2026-09-15 12:32	25.98	OK
7319	2026-09-15 12:33	26.08	OK	7320	2026-09-15 12:34	26.23	OK
7321	2026-09-15 12:35	26.51	OK	7322	2026-09-15 12:36	26.13	OK
7323	2026-09-15 12:37	27.15	OK	7324	2026-09-15 12:38	25.40	OK
7325	2026-09-15 12:39	24.65	OK	7326	2026-09-15 12:40	26.31	OK
7327	2026-09-15 12:41	26.34	OK	7328	2026-09-15 12:42	25.43	OK
7329	2026-09-15 12:43	26.98	OK	7330	2026-09-15 12:44	25.54	OK
7331	2026-09-15 12:45	25.67	OK	7332	2026-09-15 12:46	25.84	OK
7333	2026-09-15 12:47	26.11	OK	7334	2026-09-15 12:48	26.26	OK
7335	2026-09-15 12:49	25.44	OK	7336	2026-09-15 12:50	25.09	OK
7337	2026-09-15 12:51	24.79	OK	7338	2026-09-15 12:52	26.76	OK
7339	2026-09-15 12:53	26.53	OK	7340	2026-09-15 12:54	24.28	OK
7341	2026-09-15 12:55	26.82	OK	7342	2026-09-15 12:56	26.93	OK
7343	2026-09-15 12:57	27.29	OK	7344	2026-09-15 12:58	25.72	OK
7345	2026-09-15 12:59	25.54	OK	7346	2026-09-15 13:00	25.95	OK
7347	2026-09-15 13:01	25.61	OK	7348	2026-09-15 13:02	26.03	OK
7349	2026-09-15 13:03	25.63	OK	7350	2026-09-15 13:04	27.08	OK
7351	2026-09-15 13:05	24.59	OK	7352	2026-09-15 13:06	24.32	OK
7353	2026-09-15 13:07	25.25	OK	7354	2026-09-15 13:08	25.25	OK
7355	2026-09-15 13:09	26.76	OK	7356	2026-09-15 13:10	25.47	OK
7357	2026-09-15 13:11	26.59	OK	7358	2026-09-15 13:12	25.82	OK
7359	2026-09-15 13:13	25.45	OK	7360	2026-09-15 13:14	24.90	OK
7361	2026-09-15 13:15	25.28	OK	7362	2026-09-15 13:16	25.97	OK
7363	2026-09-15 13:17	25.41	OK	7364	2026-09-15 13:18	25.87	OK
7365	2026-09-15 13:19	25.82	OK	7366	2026-09-15 13:20	25.15	OK
7367	2026-09-15 13:21	26.05	OK	7368	2026-09-15 13:22	24.31	OK
7369	2026-09-15 13:23	25.58	OK	7370	2026-09-15 13:24	25.91	OK
7371	2026-09-15 13:25	24.70	OK	7372	2026-09-15 13:26	25.48	OK
7373	2026-09-15 13:27	24.99	OK	7374	2026-09-15 13:28	25.23	OK
7375	2026-09-15 13:29	24.46	OK	7376	2026-09-15 13:30	25.13	OK
7377	2026-09-15 13:31	24.69	OK	7378	2026-09-15 13:32	25.47	OK
7379	2026-09-15 13:33	25.18	OK	7380	2026-09-15 13:34	26.53	OK
7381	2026-09-15 13:35	27.10	OK	7382	2026-09-15 13:36	25.87	OK
7383	2026-09-15 13:37	24.60	OK	7384	2026-09-15 13:38	27.06	OK
7385	2026-09-15 13:39	24.65	OK	7386	2026-09-15 13:40	26.93	OK
7387	2026-09-15 13:41	25.90	OK	7388	2026-09-15 13:42	24.63	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7389	2026-09-15 13:43	25.66	OK	7390	2026-09-15 13:44	26.04	OK
7391	2026-09-15 13:45	24.12	OK	7392	2026-09-15 13:46	25.44	OK
7393	2026-09-15 13:47	26.77	OK	7394	2026-09-15 13:48	25.40	OK
7395	2026-09-15 13:49	25.05	OK	7396	2026-09-15 13:50	24.85	OK
7397	2026-09-15 13:51	26.36	OK	7398	2026-09-15 13:52	24.49	OK
7399	2026-09-15 13:53	25.26	OK	7400	2026-09-15 13:54	25.20	OK
7401	2026-09-15 13:55	26.63	OK	7402	2026-09-15 13:56	25.41	OK
7403	2026-09-15 13:57	25.47	OK	7404	2026-09-15 13:58	25.96	OK
7405	2026-09-15 13:59	26.36	OK	7406	2026-09-15 14:00	26.03	OK
7407	2026-09-15 14:01	25.19	OK	7408	2026-09-15 14:02	25.77	OK
7409	2026-09-15 14:03	24.17	OK	7410	2026-09-15 14:04	25.60	OK
7411	2026-09-15 14:05	25.45	OK	7412	2026-09-15 14:06	26.83	OK
7413	2026-09-15 14:07	26.40	OK	7414	2026-09-15 14:08	25.80	OK
7415	2026-09-15 14:09	26.24	OK	7416	2026-09-15 14:10	26.57	OK
7417	2026-09-15 14:11	26.48	OK	7418	2026-09-15 14:12	26.09	OK
7419	2026-09-15 14:13	25.11	OK	7420	2026-09-15 14:14	25.56	OK
7421	2026-09-15 14:15	25.43	OK	7422	2026-09-15 14:16	26.42	OK
7423	2026-09-15 14:17	25.19	OK	7424	2026-09-15 14:18	24.75	OK
7425	2026-09-15 14:19	26.63	OK	7426	2026-09-15 14:20	25.03	OK
7427	2026-09-15 14:21	25.47	OK	7428	2026-09-15 14:22	24.23	OK
7429	2026-09-15 14:23	24.87	OK	7430	2026-09-15 14:24	24.79	OK
7431	2026-09-15 14:25	26.69	OK	7432	2026-09-15 14:26	26.10	OK
7433	2026-09-15 14:27	25.26	OK	7434	2026-09-15 14:28	25.55	OK
7435	2026-09-15 14:29	25.35	OK	7436	2026-09-15 14:30	26.10	OK
7437	2026-09-15 14:31	24.97	OK	7438	2026-09-15 14:32	26.44	OK
7439	2026-09-15 14:33	24.87	OK	7440	2026-09-15 14:34	26.48	OK
7441	2026-09-15 14:35	26.98	OK	7442	2026-09-15 14:36	26.49	OK
7443	2026-09-15 14:37	25.78	OK	7444	2026-09-15 14:38	27.24	OK
7445	2026-09-15 14:39	25.68	OK	7446	2026-09-15 14:40	27.11	OK
7447	2026-09-15 14:41	26.63	OK	7448	2026-09-15 14:42	27.04	OK
7449	2026-09-15 14:43	26.13	OK	7450	2026-09-15 14:44	25.65	OK
7451	2026-09-15 14:45	24.82	OK	7452	2026-09-15 14:46	26.60	OK
7453	2026-09-15 14:47	24.20	OK	7454	2026-09-15 14:48	25.13	OK
7455	2026-09-15 14:49	25.64	OK	7456	2026-09-15 14:50	24.59	OK
7457	2026-09-15 14:51	26.02	OK	7458	2026-09-15 14:52	25.89	OK
7459	2026-09-15 14:53	26.05	OK	7460	2026-09-15 14:54	25.72	OK
7461	2026-09-15 14:55	25.70	OK	7462	2026-09-15 14:56	26.07	OK
7463	2026-09-15 14:57	27.41	OK	7464	2026-09-15 14:58	27.00	OK
7465	2026-09-15 14:59	27.42	OK	7466	2026-09-15 15:00	25.63	OK
7467	2026-09-15 15:01	24.73	OK	7468	2026-09-15 15:02	26.09	OK
7469	2026-09-15 15:03	25.55	OK	7470	2026-09-15 15:04	26.11	OK
7471	2026-09-15 15:05	25.43	OK	7472	2026-09-15 15:06	26.75	OK
7473	2026-09-15 15:07	26.36	OK	7474	2026-09-15 15:08	26.78	OK
7475	2026-09-15 15:09	27.13	OK	7476	2026-09-15 15:10	27.11	OK
7477	2026-09-15 15:11	26.14	OK	7478	2026-09-15 15:12	25.65	OK
7479	2026-09-15 15:13	27.61	OK	7480	2026-09-15 15:14	26.51	OK
7481	2026-09-15 15:15	26.54	OK	7482	2026-09-15 15:16	27.05	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7483	2026-09-15 15:17	27.88	OK	7484	2026-09-15 15:18	26.12	OK
7485	2026-09-15 15:19	24.62	OK	7486	2026-09-15 15:20	25.59	OK
7487	2026-09-15 15:21	26.10	OK	7488	2026-09-15 15:22	26.02	OK
7489	2026-09-15 15:23	27.34	OK	7490	2026-09-15 15:24	26.31	OK
7491	2026-09-15 15:25	25.81	OK	7492	2026-09-15 15:26	26.97	OK
7493	2026-09-15 15:27	25.66	OK	7494	2026-09-15 15:28	25.73	OK
7495	2026-09-15 15:29	25.34	OK	7496	2026-09-15 15:30	26.27	OK
7497	2026-09-15 15:31	26.39	OK	7498	2026-09-15 15:32	25.99	OK
7499	2026-09-15 15:33	27.61	OK	7500	2026-09-15 15:34	25.85	OK
7501	2026-09-15 15:35	25.56	OK	7502	2026-09-15 15:36	25.40	OK
7503	2026-09-15 15:37	25.32	OK	7504	2026-09-15 15:38	24.93	OK
7505	2026-09-15 15:39	26.26	OK	7506	2026-09-15 15:40	24.37	OK
7507	2026-09-15 15:41	25.42	OK	7508	2026-09-15 15:42	24.31	OK
7509	2026-09-15 15:43	25.56	OK	7510	2026-09-15 15:44	26.04	OK
7511	2026-09-15 15:45	26.76	OK	7512	2026-09-15 15:46	26.61	OK
7513	2026-09-15 15:47	25.41	OK	7514	2026-09-15 15:48	27.26	OK
7515	2026-09-15 15:49	27.21	OK	7516	2026-09-15 15:50	24.72	OK
7517	2026-09-15 15:51	26.71	OK	7518	2026-09-15 15:52	26.37	OK
7519	2026-09-15 15:53	24.89	OK	7520	2026-09-15 15:54	26.11	OK
7521	2026-09-15 15:55	27.90	OK	7522	2026-09-15 15:56	25.82	OK
7523	2026-09-15 15:57	26.12	OK	7524	2026-09-15 15:58	24.71	OK
7525	2026-09-15 15:59	25.84	OK	7526	2026-09-15 16:00	24.69	OK
7527	2026-09-15 16:01	26.18	OK	7528	2026-09-15 16:02	25.67	OK
7529	2026-09-15 16:03	26.02	OK	7530	2026-09-15 16:04	26.40	OK
7531	2026-09-15 16:05	25.78	OK	7532	2026-09-15 16:06	27.17	OK
7533	2026-09-15 16:07	25.30	OK	7534	2026-09-15 16:08	26.82	OK
7535	2026-09-15 16:09	27.01	OK	7536	2026-09-15 16:10	26.60	OK
7537	2026-09-15 16:11	25.49	OK	7538	2026-09-15 16:12	26.31	OK
7539	2026-09-15 16:13	27.04	OK	7540	2026-09-15 16:14	26.74	OK
7541	2026-09-15 16:15	27.59	OK	7542	2026-09-15 16:16	26.96	OK
7543	2026-09-15 16:17	26.43	OK	7544	2026-09-15 16:18	26.10	OK
7545	2026-09-15 16:19	26.51	OK	7546	2026-09-15 16:20	27.25	OK
7547	2026-09-15 16:21	27.23	OK	7548	2026-09-15 16:22	24.82	OK
7549	2026-09-15 16:23	26.75	OK	7550	2026-09-15 16:24	27.05	OK
7551	2026-09-15 16:25	26.30	OK	7552	2026-09-15 16:26	26.50	OK
7553	2026-09-15 16:27	24.23	OK	7554	2026-09-15 16:28	27.08	OK
7555	2026-09-15 16:29	26.29	OK	7556	2026-09-15 16:30	25.83	OK
7557	2026-09-15 16:31	27.36	OK	7558	2026-09-15 16:32	28.33	OK
7559	2026-09-15 16:33	26.39	OK	7560	2026-09-15 16:34	26.30	OK
7561	2026-09-15 16:35	25.35	OK	7562	2026-09-15 16:36	25.03	OK
7563	2026-09-15 16:37	26.24	OK	7564	2026-09-15 16:38	25.99	OK
7565	2026-09-15 16:39	27.91	OK	7566	2026-09-15 16:40	25.16	OK
7567	2026-09-15 16:41	26.37	OK	7568	2026-09-15 16:42	27.19	OK
7569	2026-09-15 16:43	26.17	OK	7570	2026-09-15 16:44	26.77	OK
7571	2026-09-15 16:45	27.13	OK	7572	2026-09-15 16:46	25.96	OK
7573	2026-09-15 16:47	25.62	OK	7574	2026-09-15 16:48	25.84	OK
7575	2026-09-15 16:49	27.95	OK	7576	2026-09-15 16:50	26.98	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7577	2026-09-15 16:51	25.71	OK	7578	2026-09-15 16:52	27.00	OK
7579	2026-09-15 16:53	26.52	OK	7580	2026-09-15 16:54	25.56	OK
7581	2026-09-15 16:55	24.90	OK	7582	2026-09-15 16:56	27.40	OK
7583	2026-09-15 16:57	28.12	OK	7584	2026-09-15 16:58	26.05	OK
7585	2026-09-15 16:59	27.21	OK	7586	2026-09-15 17:00	26.75	OK
7587	2026-09-15 17:01	25.52	OK	7588	2026-09-15 17:02	27.16	OK
7589	2026-09-15 17:03	27.00	OK	7590	2026-09-15 17:04	26.67	OK
7591	2026-09-15 17:05	25.54	OK	7592	2026-09-15 17:06	26.50	OK
7593	2026-09-15 17:07	25.90	OK	7594	2026-09-15 17:08	24.85	OK
7595	2026-09-15 17:09	27.08	OK	7596	2026-09-15 17:10	25.84	OK
7597	2026-09-15 17:11	24.62	OK	7598	2026-09-15 17:12	25.01	OK
7599	2026-09-15 17:13	26.65	OK	7600	2026-09-15 17:14	27.29	OK
7601	2026-09-15 17:15	26.00	OK	7602	2026-09-15 17:16	27.48	OK
7603	2026-09-15 17:17	25.39	OK	7604	2026-09-15 17:18	27.06	OK
7605	2026-09-15 17:19	27.46	OK	7606	2026-09-15 17:20	25.86	OK
7607	2026-09-15 17:21	27.11	OK	7608	2026-09-15 17:22	27.18	OK
7609	2026-09-15 17:23	28.32	OK	7610	2026-09-15 17:24	27.74	OK
7611	2026-09-15 17:25	27.65	OK	7612	2026-09-15 17:26	26.49	OK
7613	2026-09-15 17:27	26.97	OK	7614	2026-09-15 17:28	25.20	OK
7615	2026-09-15 17:29	26.18	OK	7616	2026-09-15 17:30	25.68	OK
7617	2026-09-15 17:31	25.79	OK	7618	2026-09-15 17:32	26.53	OK
7619	2026-09-15 17:33	27.37	OK	7620	2026-09-15 17:34	28.44	OK
7621	2026-09-15 17:35	25.60	OK	7622	2026-09-15 17:36	26.26	OK
7623	2026-09-15 17:37	27.66	OK	7624	2026-09-15 17:38	28.09	OK
7625	2026-09-15 17:39	27.41	OK	7626	2026-09-15 17:40	27.33	OK
7627	2026-09-15 17:41	27.31	OK	7628	2026-09-15 17:42	26.83	OK
7629	2026-09-15 17:43	27.96	OK	7630	2026-09-15 17:44	27.56	OK
7631	2026-09-15 17:45	28.20	OK	7632	2026-09-15 17:46	28.18	OK
7633	2026-09-15 17:47	26.63	OK	7634	2026-09-15 17:48	28.54	OK
7635	2026-09-15 17:49	26.54	OK	7636	2026-09-15 17:50	28.20	OK
7637	2026-09-15 17:51	27.83	OK	7638	2026-09-15 17:52	26.89	OK
7639	2026-09-15 17:53	26.58	OK	7640	2026-09-15 17:54	27.01	OK
7641	2026-09-15 17:55	25.39	OK	7642	2026-09-15 17:56	27.12	OK
7643	2026-09-15 17:57	26.91	OK	7644	2026-09-15 17:58	26.65	OK
7645	2026-09-15 17:59	26.36	OK	7646	2026-09-15 18:00	27.61	OK
7647	2026-09-15 18:01	27.77	OK	7648	2026-09-15 18:02	27.32	OK
7649	2026-09-15 18:03	26.41	OK	7650	2026-09-15 18:04	26.22	OK
7651	2026-09-15 18:05	26.63	OK	7652	2026-09-15 18:06	27.37	OK
7653	2026-09-15 18:07	28.19	OK	7654	2026-09-15 18:08	28.49	OK
7655	2026-09-15 18:09	27.31	OK	7656	2026-09-15 18:10	27.14	OK
7657	2026-09-15 18:11	26.70	OK	7658	2026-09-15 18:12	27.50	OK
7659	2026-09-15 18:13	26.77	OK	7660	2026-09-15 18:14	26.95	OK
7661	2026-09-15 18:15	27.03	OK	7662	2026-09-15 18:16	27.34	OK
7663	2026-09-15 18:17	25.21	OK	7664	2026-09-15 18:18	27.29	OK
7665	2026-09-15 18:19	27.66	OK	7666	2026-09-15 18:20	28.33	OK
7667	2026-09-15 18:21	27.70	OK	7668	2026-09-15 18:22	27.29	OK
7669	2026-09-15 18:23	26.61	OK	7670	2026-09-15 18:24	27.57	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7671	2026-09-15 18:25	29.27	OK	7672	2026-09-15 18:26	28.29	OK
7673	2026-09-15 18:27	26.34	OK	7674	2026-09-15 18:28	26.70	OK
7675	2026-09-15 18:29	27.82	OK	7676	2026-09-15 18:30	26.83	OK
7677	2026-09-15 18:31	27.26	OK	7678	2026-09-15 18:32	26.80	OK
7679	2026-09-15 18:33	27.63	OK	7680	2026-09-15 18:34	26.43	OK
7681	2026-09-15 18:35	27.32	OK	7682	2026-09-15 18:36	26.11	OK
7683	2026-09-15 18:37	26.38	OK	7684	2026-09-15 18:38	26.47	OK
7685	2026-09-15 18:39	27.44	OK	7686	2026-09-15 18:40	27.95	OK
7687	2026-09-15 18:41	28.47	OK	7688	2026-09-15 18:42	28.32	OK
7689	2026-09-15 18:43	27.20	OK	7690	2026-09-15 18:44	27.64	OK
7691	2026-09-15 18:45	26.70	OK	7692	2026-09-15 18:46	27.50	OK
7693	2026-09-15 18:47	29.36	OK	7694	2026-09-15 18:48	28.00	OK
7695	2026-09-15 18:49	28.82	OK	7696	2026-09-15 18:50	26.90	OK
7697	2026-09-15 18:51	27.06	OK	7698	2026-09-15 18:52	28.41	OK
7699	2026-09-15 18:53	29.14	OK	7700	2026-09-15 18:54	27.60	OK
7701	2026-09-15 18:55	27.47	OK	7702	2026-09-15 18:56	28.55	OK
7703	2026-09-15 18:57	28.14	OK	7704	2026-09-15 18:58	27.61	OK
7705	2026-09-15 18:59	26.35	OK	7706	2026-09-15 19:00	27.58	OK
7707	2026-09-15 19:01	26.35	OK	7708	2026-09-15 19:02	28.48	OK
7709	2026-09-15 19:03	27.92	OK	7710	2026-09-15 19:04	27.23	OK
7711	2026-09-15 19:05	26.76	OK	7712	2026-09-15 19:06	27.80	OK
7713	2026-09-15 19:07	27.57	OK	7714	2026-09-15 19:08	28.25	OK
7715	2026-09-15 19:09	27.30	OK	7716	2026-09-15 19:10	27.31	OK
7717	2026-09-15 19:11	27.10	OK	7718	2026-09-15 19:12	26.71	OK
7719	2026-09-15 19:13	27.63	OK	7720	2026-09-15 19:14	28.15	OK
7721	2026-09-15 19:15	27.06	OK	7722	2026-09-15 19:16	28.61	OK
7723	2026-09-15 19:17	26.66	OK	7724	2026-09-15 19:18	28.05	OK
7725	2026-09-15 19:19	28.50	OK	7726	2026-09-15 19:20	27.52	OK
7727	2026-09-15 19:21	28.11	OK	7728	2026-09-15 19:22	28.22	OK
7729	2026-09-15 19:23	27.52	OK	7730	2026-09-15 19:24	28.30	OK
7731	2026-09-15 19:25	27.83	OK	7732	2026-09-15 19:26	28.48	OK
7733	2026-09-15 19:27	27.45	OK	7734	2026-09-15 19:28	26.89	OK
7735	2026-09-15 19:29	28.51	OK	7736	2026-09-15 19:30	28.15	OK
7737	2026-09-15 19:31	27.76	OK	7738	2026-09-15 19:32	26.44	OK
7739	2026-09-15 19:33	29.19	OK	7740	2026-09-15 19:34	27.84	OK
7741	2026-09-15 19:35	27.63	OK	7742	2026-09-15 19:36	28.31	OK
7743	2026-09-15 19:37	27.29	OK	7744	2026-09-15 19:38	28.78	OK
7745	2026-09-15 19:39	28.90	OK	7746	2026-09-15 19:40	28.44	OK
7747	2026-09-15 19:41	28.52	OK	7748	2026-09-15 19:42	26.86	OK
7749	2026-09-15 19:43	28.74	OK	7750	2026-09-15 19:44	29.72	OK
7751	2026-09-15 19:45	27.71	OK	7752	2026-09-15 19:46	28.31	OK
7753	2026-09-15 19:47	27.71	OK	7754	2026-09-15 19:48	27.80	OK
7755	2026-09-15 19:49	29.13	OK	7756	2026-09-15 19:50	27.34	OK
7757	2026-09-15 19:51	28.74	OK	7758	2026-09-15 19:52	27.10	OK
7759	2026-09-15 19:53	28.53	OK	7760	2026-09-15 19:54	28.70	OK
7761	2026-09-15 19:55	27.08	OK	7762	2026-09-15 19:56	29.39	OK
7763	2026-09-15 19:57	27.93	OK	7764	2026-09-15 19:58	29.57	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7765	2026-09-15 19:59	30.09	OK	7766	2026-09-15 20:00	27.21	OK
7767	2026-09-15 20:01	27.58	OK	7768	2026-09-15 20:02	28.77	OK
7769	2026-09-15 20:03	28.17	OK	7770	2026-09-15 20:04	28.05	OK
7771	2026-09-15 20:05	27.66	OK	7772	2026-09-15 20:06	28.73	OK
7773	2026-09-15 20:07	28.96	OK	7774	2026-09-15 20:08	27.71	OK
7775	2026-09-15 20:09	28.46	OK	7776	2026-09-15 20:10	26.54	OK
7777	2026-09-15 20:11	27.69	OK	7778	2026-09-15 20:12	28.03	OK
7779	2026-09-15 20:13	28.65	OK	7780	2026-09-15 20:14	29.76	OK
7781	2026-09-15 20:15	28.80	OK	7782	2026-09-15 20:16	27.86	OK
7783	2026-09-15 20:17	28.64	OK	7784	2026-09-15 20:18	29.34	OK
7785	2026-09-15 20:19	27.55	OK	7786	2026-09-15 20:20	28.48	OK
7787	2026-09-15 20:21	28.29	OK	7788	2026-09-15 20:22	28.21	OK
7789	2026-09-15 20:23	28.64	OK	7790	2026-09-15 20:24	29.28	OK
7791	2026-09-15 20:25	29.03	OK	7792	2026-09-15 20:26	28.50	OK
7793	2026-09-15 20:27	28.47	OK	7794	2026-09-15 20:28	28.07	OK
7795	2026-09-15 20:29	28.86	OK	7796	2026-09-15 20:30	28.11	OK
7797	2026-09-15 20:31	27.49	OK	7798	2026-09-15 20:32	27.79	OK
7799	2026-09-15 20:33	28.23	OK	7800	2026-09-15 20:34	29.96	OK
7801	2026-09-15 20:35	30.45	OK	7802	2026-09-15 20:36	28.59	OK
7803	2026-09-15 20:37	28.37	OK	7804	2026-09-15 20:38	29.32	OK
7805	2026-09-15 20:39	29.17	OK	7806	2026-09-15 20:40	28.10	OK
7807	2026-09-15 20:41	30.18	OK	7808	2026-09-15 20:42	28.90	OK
7809	2026-09-15 20:43	28.98	OK	7810	2026-09-15 20:44	30.00	OK
7811	2026-09-15 20:45	28.37	OK	7812	2026-09-15 20:46	29.26	OK
7813	2026-09-15 20:47	28.64	OK	7814	2026-09-15 20:48	29.30	OK
7815	2026-09-15 20:49	29.53	OK	7816	2026-09-15 20:50	29.12	OK
7817	2026-09-15 20:51	28.18	OK	7818	2026-09-15 20:52	29.08	OK
7819	2026-09-15 20:53	28.77	OK	7820	2026-09-15 20:54	28.98	OK
7821	2026-09-15 20:55	27.58	OK	7822	2026-09-15 20:56	29.18	OK
7823	2026-09-15 20:57	29.51	OK	7824	2026-09-15 20:58	27.97	OK
7825	2026-09-15 20:59	28.23	OK	7826	2026-09-15 21:00	30.12	OK
7827	2026-09-15 21:01	29.29	OK	7828	2026-09-15 21:02	29.18	OK
7829	2026-09-15 21:03	28.49	OK	7830	2026-09-15 21:04	29.20	OK
7831	2026-09-15 21:05	29.34	OK	7832	2026-09-15 21:06	28.28	OK
7833	2026-09-15 21:07	29.57	OK	7834	2026-09-15 21:08	28.91	OK
7835	2026-09-15 21:09	29.38	OK	7836	2026-09-15 21:10	30.99	OK
7837	2026-09-15 21:11	29.59	OK	7838	2026-09-15 21:12	28.94	OK
7839	2026-09-15 21:13	28.48	OK	7840	2026-09-15 21:14	28.27	OK
7841	2026-09-15 21:15	28.45	OK	7842	2026-09-15 21:16	29.89	OK
7843	2026-09-15 21:17	28.76	OK	7844	2026-09-15 21:18	28.66	OK
7845	2026-09-15 21:19	28.98	OK	7846	2026-09-15 21:20	28.73	OK
7847	2026-09-15 21:21	28.31	OK	7848	2026-09-15 21:22	28.69	OK
7849	2026-09-15 21:23	29.79	OK	7850	2026-09-15 21:24	29.35	OK
7851	2026-09-15 21:25	29.30	OK	7852	2026-09-15 21:26	31.21	OK
7853	2026-09-15 21:27	27.49	OK	7854	2026-09-15 21:28	30.02	OK
7855	2026-09-15 21:29	28.41	OK	7856	2026-09-15 21:30	29.49	OK
7857	2026-09-15 21:31	28.27	OK	7858	2026-09-15 21:32	28.76	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7859	2026-09-15 21:33	29.73	OK	7860	2026-09-15 21:34	29.10	OK
7861	2026-09-15 21:35	29.42	OK	7862	2026-09-15 21:36	28.14	OK
7863	2026-09-15 21:37	28.57	OK	7864	2026-09-15 21:38	28.74	OK
7865	2026-09-15 21:39	28.96	OK	7866	2026-09-15 21:40	29.13	OK
7867	2026-09-15 21:41	28.60	OK	7868	2026-09-15 21:42	29.57	OK
7869	2026-09-15 21:43	29.07	OK	7870	2026-09-15 21:44	30.48	OK
7871	2026-09-15 21:45	30.73	OK	7872	2026-09-15 21:46	28.69	OK
7873	2026-09-15 21:47	28.98	OK	7874	2026-09-15 21:48	30.50	OK
7875	2026-09-15 21:49	29.91	OK	7876	2026-09-15 21:50	27.74	OK
7877	2026-09-15 21:51	29.69	OK	7878	2026-09-15 21:52	28.72	OK
7879	2026-09-15 21:53	29.50	OK	7880	2026-09-15 21:54	28.52	OK
7881	2026-09-15 21:55	30.15	OK	7882	2026-09-15 21:56	30.75	OK
7883	2026-09-15 21:57	28.69	OK	7884	2026-09-15 21:58	27.79	OK
7885	2026-09-15 21:59	28.82	OK	7886	2026-09-15 22:00	30.08	OK
7887	2026-09-15 22:01	31.20	OK	7888	2026-09-15 22:02	29.22	OK
7889	2026-09-15 22:03	28.43	OK	7890	2026-09-15 22:04	29.20	OK
7891	2026-09-15 22:05	29.84	OK	7892	2026-09-15 22:06	30.67	OK
7893	2026-09-15 22:07	29.37	OK	7894	2026-09-15 22:08	30.04	OK
7895	2026-09-15 22:09	28.90	OK	7896	2026-09-15 22:10	29.44	OK
7897	2026-09-15 22:11	29.41	OK	7898	2026-09-15 22:12	27.89	OK
7899	2026-09-15 22:13	30.04	OK	7900	2026-09-15 22:14	29.62	OK
7901	2026-09-15 22:15	30.04	OK	7902	2026-09-15 22:16	29.00	OK
7903	2026-09-15 22:17	29.44	OK	7904	2026-09-15 22:18	28.43	OK
7905	2026-09-15 22:19	28.83	OK	7906	2026-09-15 22:20	30.34	OK
7907	2026-09-15 22:21	29.92	OK	7908	2026-09-15 22:22	29.38	OK
7909	2026-09-15 22:23	30.57	OK	7910	2026-09-15 22:24	30.07	OK
7911	2026-09-15 22:25	30.65	OK	7912	2026-09-15 22:26	31.28	OK
7913	2026-09-15 22:27	27.52	OK	7914	2026-09-15 22:28	29.86	OK
7915	2026-09-15 22:29	28.83	OK	7916	2026-09-15 22:30	29.99	OK
7917	2026-09-15 22:31	29.08	OK	7918	2026-09-15 22:32	29.49	OK
7919	2026-09-15 22:33	29.21	OK	7920	2026-09-15 22:34	29.85	OK
7921	2026-09-15 22:35	30.22	OK	7922	2026-09-15 22:36	31.43	OK
7923	2026-09-15 22:37	29.11	OK	7924	2026-09-15 22:38	28.73	OK
7925	2026-09-15 22:39	29.71	OK	7926	2026-09-15 22:40	28.25	OK
7927	2026-09-15 22:41	30.20	OK	7928	2026-09-15 22:42	29.26	OK
7929	2026-09-15 22:43	29.61	OK	7930	2026-09-15 22:44	28.31	OK
7931	2026-09-15 22:45	30.10	OK	7932	2026-09-15 22:46	28.12	OK
7933	2026-09-15 22:47	28.06	OK	7934	2026-09-15 22:48	29.87	OK
7935	2026-09-15 22:49	29.73	OK	7936	2026-09-15 22:50	28.93	OK
7937	2026-09-15 22:51	28.87	OK	7938	2026-09-15 22:52	29.72	OK
7939	2026-09-15 22:53	28.94	OK	7940	2026-09-15 22:54	29.79	OK
7941	2026-09-15 22:55	29.25	OK	7942	2026-09-15 22:56	29.35	OK
7943	2026-09-15 22:57	30.52	OK	7944	2026-09-15 22:58	29.72	OK
7945	2026-09-15 22:59	30.78	OK	7946	2026-09-15 23:00	28.30	OK
7947	2026-09-15 23:01	30.28	OK	7948	2026-09-15 23:02	29.52	OK
7949	2026-09-15 23:03	30.17	OK	7950	2026-09-15 23:04	29.99	OK
7951	2026-09-15 23:05	29.90	OK	7952	2026-09-15 23:06	30.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
7953	2026-09-15 23:07	30.76	OK	7954	2026-09-15 23:08	29.10	OK
7955	2026-09-15 23:09	29.71	OK	7956	2026-09-15 23:10	29.52	OK
7957	2026-09-15 23:11	28.56	OK	7958	2026-09-15 23:12	30.33	OK
7959	2026-09-15 23:13	30.12	OK	7960	2026-09-15 23:14	29.30	OK
7961	2026-09-15 23:15	30.88	OK	7962	2026-09-15 23:16	29.94	OK
7963	2026-09-15 23:17	29.75	OK	7964	2026-09-15 23:18	30.20	OK
7965	2026-09-15 23:19	30.78	OK	7966	2026-09-15 23:20	29.20	OK
7967	2026-09-15 23:21	29.56	OK	7968	2026-09-15 23:22	28.94	OK
7969	2026-09-15 23:23	30.50	OK	7970	2026-09-15 23:24	30.01	OK
7971	2026-09-15 23:25	29.71	OK	7972	2026-09-15 23:26	29.04	OK
7973	2026-09-15 23:27	29.16	OK	7974	2026-09-15 23:28	30.55	OK
7975	2026-09-15 23:29	30.71	OK	7976	2026-09-15 23:30	31.65	OK
7977	2026-09-15 23:31	30.46	OK	7978	2026-09-15 23:32	29.90	OK
7979	2026-09-15 23:33	28.26	OK	7980	2026-09-15 23:34	30.72	OK
7981	2026-09-15 23:35	30.47	OK	7982	2026-09-15 23:36	30.43	OK
7983	2026-09-15 23:37	30.44	OK	7984	2026-09-15 23:38	29.94	OK
7985	2026-09-15 23:39	28.88	OK	7986	2026-09-15 23:40	30.71	OK
7987	2026-09-15 23:41	31.14	OK	7988	2026-09-15 23:42	30.27	OK
7989	2026-09-15 23:43	28.33	OK	7990	2026-09-15 23:44	29.47	OK
7991	2026-09-15 23:45	30.64	OK	7992	2026-09-15 23:46	29.64	OK
7993	2026-09-15 23:47	30.04	OK	7994	2026-09-15 23:48	30.02	OK
7995	2026-09-15 23:49	30.30	OK	7996	2026-09-15 23:50	30.76	OK
7997	2026-09-15 23:51	29.19	OK	7998	2026-09-15 23:52	29.87	OK
7999	2026-09-15 23:53	28.71	OK	8000	2026-09-15 23:54	30.45	OK
8001	2026-09-15 23:55	31.09	OK	8002	2026-09-15 23:56	31.14	OK
8003	2026-09-15 23:57	29.66	OK	8004	2026-09-15 23:58	30.12	OK
8005	2026-09-15 23:59	29.85	OK	8006	2026-09-16 00:00	28.59	OK
8007	2026-09-16 00:01	30.62	OK	8008	2026-09-16 00:02	29.87	OK
8009	2026-09-16 00:03	30.58	OK	8010	2026-09-16 00:04	30.51	OK
8011	2026-09-16 00:05	32.06	OK	8012	2026-09-16 00:06	30.70	OK
8013	2026-09-16 00:07	29.83	OK	8014	2026-09-16 00:08	30.43	OK
8015	2026-09-16 00:09	30.61	OK	8016	2026-09-16 00:10	30.74	OK
8017	2026-09-16 00:11	29.24	OK	8018	2026-09-16 00:12	30.29	OK
8019	2026-09-16 00:13	30.68	OK	8020	2026-09-16 00:14	29.32	OK
8021	2026-09-16 00:15	31.27	OK	8022	2026-09-16 00:16	28.42	OK
8023	2026-09-16 00:17	29.87	OK	8024	2026-09-16 00:18	30.69	OK
8025	2026-09-16 00:19	29.27	OK	8026	2026-09-16 00:20	30.84	OK
8027	2026-09-16 00:21	30.36	OK	8028	2026-09-16 00:22	30.23	OK
8029	2026-09-16 00:23	28.91	OK	8030	2026-09-16 00:24	30.54	OK
8031	2026-09-16 00:25	29.16	OK	8032	2026-09-16 00:26	29.32	OK
8033	2026-09-16 00:27	30.88	OK	8034	2026-09-16 00:28	30.75	OK
8035	2026-09-16 00:29	30.10	OK	8036	2026-09-16 00:30	29.79	OK
8037	2026-09-16 00:31	28.54	OK	8038	2026-09-16 00:32	30.88	OK
8039	2026-09-16 00:33	30.16	OK	8040	2026-09-16 00:34	31.24	OK
8041	2026-09-16 00:35	30.18	OK	8042	2026-09-16 00:36	30.07	OK
8043	2026-09-16 00:37	29.76	OK	8044	2026-09-16 00:38	29.55	OK
8045	2026-09-16 00:39	29.34	OK	8046	2026-09-16 00:40	30.85	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8047	2026-09-16 00:41	30.18	OK	8048	2026-09-16 00:42	29.88	OK
8049	2026-09-16 00:43	29.96	OK	8050	2026-09-16 00:44	29.80	OK
8051	2026-09-16 00:45	29.61	OK	8052	2026-09-16 00:46	31.29	OK
8053	2026-09-16 00:47	30.01	OK	8054	2026-09-16 00:48	29.65	OK
8055	2026-09-16 00:49	29.64	OK	8056	2026-09-16 00:50	32.09	OK
8057	2026-09-16 00:51	30.18	OK	8058	2026-09-16 00:52	29.38	OK
8059	2026-09-16 00:53	29.77	OK	8060	2026-09-16 00:54	29.11	OK
8061	2026-09-16 00:55	30.66	OK	8062	2026-09-16 00:56	30.64	OK
8063	2026-09-16 00:57	29.78	OK	8064	2026-09-16 00:58	30.80	OK
8065	2026-09-16 00:59	30.58	OK	8066	2026-09-16 01:00	30.42	OK
8067	2026-09-16 01:01	31.50	OK	8068	2026-09-16 01:02	29.81	OK
8069	2026-09-16 01:03	30.07	OK	8070	2026-09-16 01:04	29.64	OK
8071	2026-09-16 01:05	29.82	OK	8072	2026-09-16 01:06	29.85	OK
8073	2026-09-16 01:07	29.88	OK	8074	2026-09-16 01:08	30.59	OK
8075	2026-09-16 01:09	28.61	OK	8076	2026-09-16 01:10	29.79	OK
8077	2026-09-16 01:11	29.55	OK	8078	2026-09-16 01:12	29.72	OK
8079	2026-09-16 01:13	30.33	OK	8080	2026-09-16 01:14	31.48	OK
8081	2026-09-16 01:15	29.93	OK	8082	2026-09-16 01:16	30.99	OK
8083	2026-09-16 01:17	30.32	OK	8084	2026-09-16 01:18	31.18	OK
8085	2026-09-16 01:19	30.42	OK	8086	2026-09-16 01:20	29.73	OK
8087	2026-09-16 01:21	29.71	OK	8088	2026-09-16 01:22	30.32	OK
8089	2026-09-16 01:23	29.70	OK	8090	2026-09-16 01:24	29.58	OK
8091	2026-09-16 01:25	30.99	OK	8092	2026-09-16 01:26	28.67	OK
8093	2026-09-16 01:27	28.92	OK	8094	2026-09-16 01:28	31.04	OK
8095	2026-09-16 01:29	30.52	OK	8096	2026-09-16 01:30	30.94	OK
8097	2026-09-16 01:31	31.02	OK	8098	2026-09-16 01:32	29.37	OK
8099	2026-09-16 01:33	28.52	OK	8100	2026-09-16 01:34	31.97	OK
8101	2026-09-16 01:35	29.69	OK	8102	2026-09-16 01:36	29.32	OK
8103	2026-09-16 01:37	31.08	OK	8104	2026-09-16 01:38	30.15	OK
8105	2026-09-16 01:39	30.05	OK	8106	2026-09-16 01:40	31.32	OK
8107	2026-09-16 01:41	29.88	OK	8108	2026-09-16 01:42	28.64	OK
8109	2026-09-16 01:43	30.19	OK	8110	2026-09-16 01:44	31.02	OK
8111	2026-09-16 01:45	30.67	OK	8112	2026-09-16 01:46	29.79	OK
8113	2026-09-16 01:47	29.25	OK	8114	2026-09-16 01:48	29.15	OK
8115	2026-09-16 01:49	31.02	OK	8116	2026-09-16 01:50	29.14	OK
8117	2026-09-16 01:51	29.23	OK	8118	2026-09-16 01:52	29.69	OK
8119	2026-09-16 01:53	29.04	OK	8120	2026-09-16 01:54	29.83	OK
8121	2026-09-16 01:55	30.04	OK	8122	2026-09-16 01:56	30.66	OK
8123	2026-09-16 01:57	31.01	OK	8124	2026-09-16 01:58	29.52	OK
8125	2026-09-16 01:59	30.31	OK	8126	2026-09-16 02:00	29.36	OK
8127	2026-09-16 02:01	30.19	OK	8128	2026-09-16 02:02	29.29	OK
8129	2026-09-16 02:03	30.79	OK	8130	2026-09-16 02:04	30.89	OK
8131	2026-09-16 02:05	29.80	OK	8132	2026-09-16 02:06	30.39	OK
8133	2026-09-16 02:07	29.92	OK	8134	2026-09-16 02:08	29.56	OK
8135	2026-09-16 02:09	30.75	OK	8136	2026-09-16 02:10	30.44	OK
8137	2026-09-16 02:11	30.87	OK	8138	2026-09-16 02:12	29.83	OK
8139	2026-09-16 02:13	29.23	OK	8140	2026-09-16 02:14	31.31	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8141	2026-09-16 02:15	30.09	OK	8142	2026-09-16 02:16	30.62	OK
8143	2026-09-16 02:17	29.47	OK	8144	2026-09-16 02:18	31.37	OK
8145	2026-09-16 02:19	30.25	OK	8146	2026-09-16 02:20	30.75	OK
8147	2026-09-16 02:21	28.94	OK	8148	2026-09-16 02:22	29.91	OK
8149	2026-09-16 02:23	29.64	OK	8150	2026-09-16 02:24	30.50	OK
8151	2026-09-16 02:25	30.34	OK	8152	2026-09-16 02:26	29.30	OK
8153	2026-09-16 02:27	31.38	OK	8154	2026-09-16 02:28	29.72	OK
8155	2026-09-16 02:29	30.03	OK	8156	2026-09-16 02:30	30.40	OK
8157	2026-09-16 02:31	29.59	OK	8158	2026-09-16 02:32	29.60	OK
8159	2026-09-16 02:33	29.22	OK	8160	2026-09-16 02:34	31.06	OK
8161	2026-09-16 02:35	30.64	OK	8162	2026-09-16 02:36	29.63	OK
8163	2026-09-16 02:37	29.54	OK	8164	2026-09-16 02:38	30.92	OK
8165	2026-09-16 02:39	30.26	OK	8166	2026-09-16 02:40	30.22	OK
8167	2026-09-16 02:41	29.15	OK	8168	2026-09-16 02:42	31.26	OK
8169	2026-09-16 02:43	30.20	OK	8170	2026-09-16 02:44	29.05	OK
8171	2026-09-16 02:45	29.59	OK	8172	2026-09-16 02:46	30.13	OK
8173	2026-09-16 02:47	29.94	OK	8174	2026-09-16 02:48	29.69	OK
8175	2026-09-16 02:49	30.17	OK	8176	2026-09-16 02:50	31.81	OK
8177	2026-09-16 02:51	29.88	OK	8178	2026-09-16 02:52	29.68	OK
8179	2026-09-16 02:53	31.08	OK	8180	2026-09-16 02:54	30.75	OK
8181	2026-09-16 02:55	30.75	OK	8182	2026-09-16 02:56	29.07	OK
8183	2026-09-16 02:57	31.16	OK	8184	2026-09-16 02:58	30.27	OK
8185	2026-09-16 02:59	29.95	OK	8186	2026-09-16 03:00	29.20	OK
8187	2026-09-16 03:01	30.70	OK	8188	2026-09-16 03:02	30.50	OK
8189	2026-09-16 03:03	29.80	OK	8190	2026-09-16 03:04	31.47	OK
8191	2026-09-16 03:05	30.14	OK	8192	2026-09-16 03:06	29.56	OK
8193	2026-09-16 03:07	30.36	OK	8194	2026-09-16 03:08	31.34	OK
8195	2026-09-16 03:09	29.95	OK	8196	2026-09-16 03:10	30.00	OK
8197	2026-09-16 03:11	28.84	OK	8198	2026-09-16 03:12	29.52	OK
8199	2026-09-16 03:13	29.50	OK	8200	2026-09-16 03:14	29.98	OK
8201	2026-09-16 03:15	31.90	OK	8202	2026-09-16 03:16	31.26	OK
8203	2026-09-16 03:17	31.42	OK	8204	2026-09-16 03:18	28.92	OK
8205	2026-09-16 03:19	28.99	OK	8206	2026-09-16 03:20	29.94	OK
8207	2026-09-16 03:21	28.80	OK	8208	2026-09-16 03:22	30.07	OK
8209	2026-09-16 03:23	30.74	OK	8210	2026-09-16 03:24	28.54	OK
8211	2026-09-16 03:25	30.23	OK	8212	2026-09-16 03:26	29.64	OK
8213	2026-09-16 03:27	31.36	OK	8214	2026-09-16 03:28	29.91	OK
8215	2026-09-16 03:29	29.89	OK	8216	2026-09-16 03:30	30.26	OK
8217	2026-09-16 03:31	30.12	OK	8218	2026-09-16 03:32	30.48	OK
8219	2026-09-16 03:33	29.97	OK	8220	2026-09-16 03:34	29.26	OK
8221	2026-09-16 03:35	29.70	OK	8222	2026-09-16 03:36	29.24	OK
8223	2026-09-16 03:37	29.80	OK	8224	2026-09-16 03:38	30.66	OK
8225	2026-09-16 03:39	30.79	OK	8226	2026-09-16 03:40	30.02	OK
8227	2026-09-16 03:41	28.38	OK	8228	2026-09-16 03:42	30.24	OK
8229	2026-09-16 03:43	28.44	OK	8230	2026-09-16 03:44	31.05	OK
8231	2026-09-16 03:45	31.25	OK	8232	2026-09-16 03:46	30.18	OK
8233	2026-09-16 03:47	30.51	OK	8234	2026-09-16 03:48	29.68	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8235	2026-09-16 03:49	29.06	OK	8236	2026-09-16 03:50	30.49	OK
8237	2026-09-16 03:51	28.96	OK	8238	2026-09-16 03:52	30.59	OK
8239	2026-09-16 03:53	29.93	OK	8240	2026-09-16 03:54	29.15	OK
8241	2026-09-16 03:55	29.96	OK	8242	2026-09-16 03:56	28.47	OK
8243	2026-09-16 03:57	29.40	OK	8244	2026-09-16 03:58	31.72	OK
8245	2026-09-16 03:59	29.40	OK	8246	2026-09-16 04:00	30.73	OK
8247	2026-09-16 04:01	30.27	OK	8248	2026-09-16 04:02	29.92	OK
8249	2026-09-16 04:03	30.60	OK	8250	2026-09-16 04:04	29.28	OK
8251	2026-09-16 04:05	31.32	OK	8252	2026-09-16 04:06	31.14	OK
8253	2026-09-16 04:07	28.64	OK	8254	2026-09-16 04:08	28.78	OK
8255	2026-09-16 04:09	28.90	OK	8256	2026-09-16 04:10	29.86	OK
8257	2026-09-16 04:11	29.42	OK	8258	2026-09-16 04:12	30.41	OK
8259	2026-09-16 04:13	30.91	OK	8260	2026-09-16 04:14	29.02	OK
8261	2026-09-16 04:15	28.79	OK	8262	2026-09-16 04:16	28.93	OK
8263	2026-09-16 04:17	30.88	OK	8264	2026-09-16 04:18	29.23	OK
8265	2026-09-16 04:19	28.88	OK	8266	2026-09-16 04:20	29.81	OK
8267	2026-09-16 04:21	30.13	OK	8268	2026-09-16 04:22	30.71	OK
8269	2026-09-16 04:23	29.63	OK	8270	2026-09-16 04:24	29.11	OK
8271	2026-09-16 04:25	28.89	OK	8272	2026-09-16 04:26	30.36	OK
8273	2026-09-16 04:27	30.13	OK	8274	2026-09-16 04:28	30.37	OK
8275	2026-09-16 04:29	30.98	OK	8276	2026-09-16 04:30	30.58	OK
8277	2026-09-16 04:31	29.65	OK	8278	2026-09-16 04:32	30.11	OK
8279	2026-09-16 04:33	29.84	OK	8280	2026-09-16 04:34	29.64	OK
8281	2026-09-16 04:35	27.97	OK	8282	2026-09-16 04:36	29.42	OK
8283	2026-09-16 04:37	29.27	OK	8284	2026-09-16 04:38	29.65	OK
8285	2026-09-16 04:39	30.20	OK	8286	2026-09-16 04:40	29.72	OK
8287	2026-09-16 04:41	29.33	OK	8288	2026-09-16 04:42	29.35	OK
8289	2026-09-16 04:43	29.23	OK	8290	2026-09-16 04:44	29.93	OK
8291	2026-09-16 04:45	30.08	OK	8292	2026-09-16 04:46	29.34	OK
8293	2026-09-16 04:47	30.40	OK	8294	2026-09-16 04:48	28.66	OK
8295	2026-09-16 04:49	29.15	OK	8296	2026-09-16 04:50	29.97	OK
8297	2026-09-16 04:51	29.43	OK	8298	2026-09-16 04:52	29.47	OK
8299	2026-09-16 04:53	29.84	OK	8300	2026-09-16 04:54	28.86	OK
8301	2026-09-16 04:55	27.51	OK	8302	2026-09-16 04:56	30.08	OK
8303	2026-09-16 04:57	29.48	OK	8304	2026-09-16 04:58	29.30	OK
8305	2026-09-16 04:59	29.20	OK	8306	2026-09-16 05:00	29.51	OK
8307	2026-09-16 05:01	29.28	OK	8308	2026-09-16 05:02	29.85	OK
8309	2026-09-16 05:03	29.93	OK	8310	2026-09-16 05:04	28.47	OK
8311	2026-09-16 05:05	29.62	OK	8312	2026-09-16 05:06	29.90	OK
8313	2026-09-16 05:07	29.10	OK	8314	2026-09-16 05:08	29.28	OK
8315	2026-09-16 05:09	30.01	OK	8316	2026-09-16 05:10	27.26	OK
8317	2026-09-16 05:11	28.67	OK	8318	2026-09-16 05:12	30.10	OK
8319	2026-09-16 05:13	28.97	OK	8320	2026-09-16 05:14	29.78	OK
8321	2026-09-16 05:15	30.10	OK	8322	2026-09-16 05:16	29.37	OK
8323	2026-09-16 05:17	30.24	OK	8324	2026-09-16 05:18	30.02	OK
8325	2026-09-16 05:19	28.94	OK	8326	2026-09-16 05:20	27.60	OK
8327	2026-09-16 05:21	29.73	OK	8328	2026-09-16 05:22	28.40	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8329	2026-09-16 05:23	29.23	OK	8330	2026-09-16 05:24	30.03	OK
8331	2026-09-16 05:25	30.54	OK	8332	2026-09-16 05:26	30.11	OK
8333	2026-09-16 05:27	29.71	OK	8334	2026-09-16 05:28	30.46	OK
8335	2026-09-16 05:29	29.03	OK	8336	2026-09-16 05:30	28.57	OK
8337	2026-09-16 05:31	27.01	OK	8338	2026-09-16 05:32	28.63	OK
8339	2026-09-16 05:33	28.78	OK	8340	2026-09-16 05:34	29.53	OK
8341	2026-09-16 05:35	29.21	OK	8342	2026-09-16 05:36	30.10	OK
8343	2026-09-16 05:37	28.27	OK	8344	2026-09-16 05:38	28.75	OK
8345	2026-09-16 05:39	30.48	OK	8346	2026-09-16 05:40	29.31	OK
8347	2026-09-16 05:41	29.41	OK	8348	2026-09-16 05:42	29.29	OK
8349	2026-09-16 05:43	28.73	OK	8350	2026-09-16 05:44	28.17	OK
8351	2026-09-16 05:45	27.91	OK	8352	2026-09-16 05:46	29.25	OK
8353	2026-09-16 05:47	29.47	OK	8354	2026-09-16 05:48	29.73	OK
8355	2026-09-16 05:49	28.47	OK	8356	2026-09-16 05:50	27.75	OK
8357	2026-09-16 05:51	29.30	OK	8358	2026-09-16 05:52	28.18	OK
8359	2026-09-16 05:53	28.18	OK	8360	2026-09-16 05:54	28.72	OK
8361	2026-09-16 05:55	28.30	OK	8362	2026-09-16 05:56	28.50	OK
8363	2026-09-16 05:57	27.25	OK	8364	2026-09-16 05:58	28.29	OK
8365	2026-09-16 05:59	28.78	OK	8366	2026-09-16 06:00	29.98	OK
8367	2026-09-16 06:01	28.97	OK	8368	2026-09-16 06:02	28.85	OK
8369	2026-09-16 06:03	28.02	OK	8370	2026-09-16 06:04	28.67	OK
8371	2026-09-16 06:05	28.68	OK	8372	2026-09-16 06:06	27.27	OK
8373	2026-09-16 06:07	28.74	OK	8374	2026-09-16 06:08	29.58	OK
8375	2026-09-16 06:09	28.91	OK	8376	2026-09-16 06:10	29.28	OK
8377	2026-09-16 06:11	29.11	OK	8378	2026-09-16 06:12	30.30	OK
8379	2026-09-16 06:13	28.53	OK	8380	2026-09-16 06:14	27.60	OK
8381	2026-09-16 06:15	29.02	OK	8382	2026-09-16 06:16	29.24	OK
8383	2026-09-16 06:17	27.18	OK	8384	2026-09-16 06:18	29.12	OK
8385	2026-09-16 06:19	28.14	OK	8386	2026-09-16 06:20	28.17	OK
8387	2026-09-16 06:21	28.25	OK	8388	2026-09-16 06:22	27.72	OK
8389	2026-09-16 06:23	27.73	OK	8390	2026-09-16 06:24	27.64	OK
8391	2026-09-16 06:25	28.75	OK	8392	2026-09-16 06:26	28.45	OK
8393	2026-09-16 06:27	28.38	OK	8394	2026-09-16 06:28	28.41	OK
8395	2026-09-16 06:29	28.94	OK	8396	2026-09-16 06:30	27.97	OK
8397	2026-09-16 06:31	27.05	OK	8398	2026-09-16 06:32	27.88	OK
8399	2026-09-16 06:33	29.07	OK	8400	2026-09-16 06:34	28.42	OK
8401	2026-09-16 06:35	29.49	OK	8402	2026-09-16 06:36	29.59	OK
8403	2026-09-16 06:37	28.05	OK	8404	2026-09-16 06:38	27.35	OK
8405	2026-09-16 06:39	28.81	OK	8406	2026-09-16 06:40	28.14	OK
8407	2026-09-16 06:41	29.23	OK	8408	2026-09-16 06:42	29.05	OK
8409	2026-09-16 06:43	28.40	OK	8410	2026-09-16 06:44	28.56	OK
8411	2026-09-16 06:45	27.60	OK	8412	2026-09-16 06:46	28.09	OK
8413	2026-09-16 06:47	28.08	OK	8414	2026-09-16 06:48	28.14	OK
8415	2026-09-16 06:49	29.08	OK	8416	2026-09-16 06:50	27.63	OK
8417	2026-09-16 06:51	28.28	OK	8418	2026-09-16 06:52	28.05	OK
8419	2026-09-16 06:53	28.71	OK	8420	2026-09-16 06:54	26.73	OK
8421	2026-09-16 06:55	27.42	OK	8422	2026-09-16 06:56	27.64	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8423	2026-09-16 06:57	28.69	OK	8424	2026-09-16 06:58	29.69	OK
8425	2026-09-16 06:59	27.11	OK	8426	2026-09-16 07:00	27.88	OK
8427	2026-09-16 07:01	27.69	OK	8428	2026-09-16 07:02	28.32	OK
8429	2026-09-16 07:03	27.82	OK	8430	2026-09-16 07:04	26.91	OK
8431	2026-09-16 07:05	28.45	OK	8432	2026-09-16 07:06	29.38	OK
8433	2026-09-16 07:07	26.73	OK	8434	2026-09-16 07:08	28.44	OK
8435	2026-09-16 07:09	28.22	OK	8436	2026-09-16 07:10	28.57	OK
8437	2026-09-16 07:11	26.73	OK	8438	2026-09-16 07:12	27.66	OK
8439	2026-09-16 07:13	26.99	OK	8440	2026-09-16 07:14	28.63	OK
8441	2026-09-16 07:15	27.62	OK	8442	2026-09-16 07:16	27.55	OK
8443	2026-09-16 07:17	29.60	OK	8444	2026-09-16 07:18	28.43	OK
8445	2026-09-16 07:19	28.51	OK	8446	2026-09-16 07:20	28.54	OK
8447	2026-09-16 07:21	28.46	OK	8448	2026-09-16 07:22	26.81	OK
8449	2026-09-16 07:23	27.68	OK	8450	2026-09-16 07:24	27.09	OK
8451	2026-09-16 07:25	27.83	OK	8452	2026-09-16 07:26	28.84	OK
8453	2026-09-16 07:27	28.02	OK	8454	2026-09-16 07:28	28.24	OK
8455	2026-09-16 07:29	27.79	OK	8456	2026-09-16 07:30	27.62	OK
8457	2026-09-16 07:31	27.92	OK	8458	2026-09-16 07:32	29.16	OK
8459	2026-09-16 07:33	28.92	OK	8460	2026-09-16 07:34	28.39	OK
8461	2026-09-16 07:35	28.20	OK	8462	2026-09-16 07:36	27.42	OK
8463	2026-09-16 07:37	27.65	OK	8464	2026-09-16 07:38	27.25	OK
8465	2026-09-16 07:39	28.36	OK	8466	2026-09-16 07:40	28.13	OK
8467	2026-09-16 07:41	26.92	OK	8468	2026-09-16 07:42	27.27	OK
8469	2026-09-16 07:43	27.53	OK	8470	2026-09-16 07:44	27.30	OK
8471	2026-09-16 07:45	26.63	OK	8472	2026-09-16 07:46	28.18	OK
8473	2026-09-16 07:47	26.60	OK	8474	2026-09-16 07:48	29.18	OK
8475	2026-09-16 07:49	27.25	OK	8476	2026-09-16 07:50	28.56	OK
8477	2026-09-16 07:51	28.20	OK	8478	2026-09-16 07:52	29.10	OK
8479	2026-09-16 07:53	27.16	OK	8480	2026-09-16 07:54	27.65	OK
8481	2026-09-16 07:55	27.13	OK	8482	2026-09-16 07:56	26.93	OK
8483	2026-09-16 07:57	27.75	OK	8484	2026-09-16 07:58	26.47	OK
8485	2026-09-16 07:59	28.76	OK	8486	2026-09-16 08:00	28.35	OK
8487	2026-09-16 08:01	29.24	OK	8488	2026-09-16 08:02	28.97	OK
8489	2026-09-16 08:03	27.18	OK	8490	2026-09-16 08:04	27.19	OK
8491	2026-09-16 08:05	27.68	OK	8492	2026-09-16 08:06	26.44	OK
8493	2026-09-16 08:07	28.29	OK	8494	2026-09-16 08:08	27.21	OK
8495	2026-09-16 08:09	26.44	OK	8496	2026-09-16 08:10	26.71	OK
8497	2026-09-16 08:11	26.90	OK	8498	2026-09-16 08:12	27.18	OK
8499	2026-09-16 08:13	27.38	OK	8500	2026-09-16 08:14	27.60	OK
8501	2026-09-16 08:15	28.78	OK	8502	2026-09-16 08:16	27.52	OK
8503	2026-09-16 08:17	28.34	OK	8504	2026-09-16 08:18	28.64	OK
8505	2026-09-16 08:19	27.30	OK	8506	2026-09-16 08:20	28.61	OK
8507	2026-09-16 08:21	28.98	OK	8508	2026-09-16 08:22	26.74	OK
8509	2026-09-16 08:23	26.39	OK	8510	2026-09-16 08:24	28.41	OK
8511	2026-09-16 08:25	27.94	OK	8512	2026-09-16 08:26	26.78	OK
8513	2026-09-16 08:27	28.01	OK	8514	2026-09-16 08:28	28.26	OK
8515	2026-09-16 08:29	28.09	OK	8516	2026-09-16 08:30	28.97	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8517	2026-09-16 08:31	28.04	OK	8518	2026-09-16 08:32	26.18	OK
8519	2026-09-16 08:33	27.87	OK	8520	2026-09-16 08:34	28.08	OK
8521	2026-09-16 08:35	28.06	OK	8522	2026-09-16 08:36	25.32	OK
8523	2026-09-16 08:37	26.89	OK	8524	2026-09-16 08:38	28.35	OK
8525	2026-09-16 08:39	28.00	OK	8526	2026-09-16 08:40	27.32	OK
8527	2026-09-16 08:41	28.07	OK	8528	2026-09-16 08:42	27.20	OK
8529	2026-09-16 08:43	29.00	OK	8530	2026-09-16 08:44	26.73	OK
8531	2026-09-16 08:45	26.79	OK	8532	2026-09-16 08:46	27.76	OK
8533	2026-09-16 08:47	26.38	OK	8534	2026-09-16 08:48	28.24	OK
8535	2026-09-16 08:49	26.70	OK	8536	2026-09-16 08:50	27.63	OK
8537	2026-09-16 08:51	27.43	OK	8538	2026-09-16 08:52	27.60	OK
8539	2026-09-16 08:53	27.84	OK	8540	2026-09-16 08:54	28.09	OK
8541	2026-09-16 08:55	26.69	OK	8542	2026-09-16 08:56	27.10	OK
8543	2026-09-16 08:57	26.68	OK	8544	2026-09-16 08:58	26.48	OK
8545	2026-09-16 08:59	27.20	OK	8546	2026-09-16 09:00	25.41	OK
8547	2026-09-16 09:01	27.02	OK	8548	2026-09-16 09:02	26.17	OK
8549	2026-09-16 09:03	28.05	OK	8550	2026-09-16 09:04	26.38	OK
8551	2026-09-16 09:05	25.74	OK	8552	2026-09-16 09:06	26.80	OK
8553	2026-09-16 09:07	26.88	OK	8554	2026-09-16 09:08	24.93	OK
8555	2026-09-16 09:09	26.05	OK	8556	2026-09-16 09:10	26.56	OK
8557	2026-09-16 09:11	26.81	OK	8558	2026-09-16 09:12	27.86	OK
8559	2026-09-16 09:13	25.98	OK	8560	2026-09-16 09:14	27.08	OK
8561	2026-09-16 09:15	27.03	OK	8562	2026-09-16 09:16	26.09	OK
8563	2026-09-16 09:17	26.11	OK	8564	2026-09-16 09:18	27.70	OK
8565	2026-09-16 09:19	27.94	OK	8566	2026-09-16 09:20	26.64	OK
8567	2026-09-16 09:21	26.96	OK	8568	2026-09-16 09:22	28.08	OK
8569	2026-09-16 09:23	27.90	OK	8570	2026-09-16 09:24	28.47	OK
8571	2026-09-16 09:25	25.94	OK	8572	2026-09-16 09:26	27.13	OK
8573	2026-09-16 09:27	25.97	OK	8574	2026-09-16 09:28	28.48	OK
8575	2026-09-16 09:29	27.83	OK	8576	2026-09-16 09:30	27.00	OK
8577	2026-09-16 09:31	26.22	OK	8578	2026-09-16 09:32	27.90	OK
8579	2026-09-16 09:33	27.71	OK	8580	2026-09-16 09:34	25.95	OK
8581	2026-09-16 09:35	27.06	OK	8582	2026-09-16 09:36	27.09	OK
8583	2026-09-16 09:37	25.76	OK	8584	2026-09-16 09:38	26.79	OK
8585	2026-09-16 09:39	27.11	OK	8586	2026-09-16 09:40	27.00	OK
8587	2026-09-16 09:41	26.95	OK	8588	2026-09-16 09:42	27.07	OK
8589	2026-09-16 09:43	26.19	OK	8590	2026-09-16 09:44	26.94	OK
8591	2026-09-16 09:45	27.27	OK	8592	2026-09-16 09:46	28.06	OK
8593	2026-09-16 09:47	27.26	OK	8594	2026-09-16 09:48	27.21	OK
8595	2026-09-16 09:49	26.77	OK	8596	2026-09-16 09:50	26.48	OK
8597	2026-09-16 09:51	25.61	OK	8598	2026-09-16 09:52	26.37	OK
8599	2026-09-16 09:53	26.35	OK	8600	2026-09-16 09:54	25.91	OK
8601	2026-09-16 09:55	25.77	OK	8602	2026-09-16 09:56	25.25	OK
8603	2026-09-16 09:57	27.30	OK	8604	2026-09-16 09:58	27.49	OK
8605	2026-09-16 09:59	27.03	OK	8606	2026-09-16 10:00	26.70	OK
8607	2026-09-16 10:01	27.03	OK	8608	2026-09-16 10:02	26.39	OK
8609	2026-09-16 10:03	27.44	OK	8610	2026-09-16 10:04	26.81	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8611	2026-09-16 10:05	27.10	OK	8612	2026-09-16 10:06	26.34	OK
8613	2026-09-16 10:07	26.83	OK	8614	2026-09-16 10:08	26.15	OK
8615	2026-09-16 10:09	26.59	OK	8616	2026-09-16 10:10	26.34	OK
8617	2026-09-16 10:11	28.13	OK	8618	2026-09-16 10:12	25.12	OK
8619	2026-09-16 10:13	26.44	OK	8620	2026-09-16 10:14	25.02	OK
8621	2026-09-16 10:15	26.41	OK	8622	2026-09-16 10:16	26.79	OK
8623	2026-09-16 10:17	25.37	OK	8624	2026-09-16 10:18	24.97	OK
8625	2026-09-16 10:19	26.23	OK	8626	2026-09-16 10:20	24.34	OK
8627	2026-09-16 10:21	26.45	OK	8628	2026-09-16 10:22	27.31	OK
8629	2026-09-16 10:23	25.50	OK	8630	2026-09-16 10:24	25.43	OK
8631	2026-09-16 10:25	27.95	OK	8632	2026-09-16 10:26	26.40	OK
8633	2026-09-16 10:27	26.29	OK	8634	2026-09-16 10:28	25.64	OK
8635	2026-09-16 10:29	26.39	OK	8636	2026-09-16 10:30	26.85	OK
8637	2026-09-16 10:31	26.49	OK	8638	2026-09-16 10:32	26.62	OK
8639	2026-09-16 10:33	27.12	OK	8640	2026-09-16 10:34	25.76	OK
8641	2026-09-16 10:35	26.39	OK	8642	2026-09-16 10:36	26.65	OK
8643	2026-09-16 10:37	26.46	OK	8644	2026-09-16 10:38	25.79	OK
8645	2026-09-16 10:39	25.07	OK	8646	2026-09-16 10:40	26.72	OK
8647	2026-09-16 10:41	26.73	OK	8648	2026-09-16 10:42	25.05	OK
8649	2026-09-16 10:43	25.97	OK	8650	2026-09-16 10:44	25.60	OK
8651	2026-09-16 10:45	26.33	OK	8652	2026-09-16 10:46	27.20	OK
8653	2026-09-16 10:47	26.31	OK	8654	2026-09-16 10:48	26.20	OK
8655	2026-09-16 10:49	25.16	OK	8656	2026-09-16 10:50	26.40	OK
8657	2026-09-16 10:51	27.66	OK	8658	2026-09-16 10:52	27.02	OK
8659	2026-09-16 10:53	25.31	OK	8660	2026-09-16 10:54	26.45	OK
8661	2026-09-16 10:55	25.97	OK	8662	2026-09-16 10:56	25.36	OK
8663	2026-09-16 10:57	27.13	OK	8664	2026-09-16 10:58	24.89	OK
8665	2026-09-16 10:59	26.55	OK	8666	2026-09-16 11:00	26.50	OK
8667	2026-09-16 11:01	27.09	OK	8668	2026-09-16 11:02	24.95	OK
8669	2026-09-16 11:03	25.58	OK	8670	2026-09-16 11:04	25.32	OK
8671	2026-09-16 11:05	26.49	OK	8672	2026-09-16 11:06	26.36	OK
8673	2026-09-16 11:07	26.26	OK	8674	2026-09-16 11:08	25.34	OK
8675	2026-09-16 11:09	24.25	OK	8676	2026-09-16 11:10	26.09	OK
8677	2026-09-16 11:11	25.90	OK	8678	2026-09-16 11:12	26.82	OK
8679	2026-09-16 11:13	25.10	OK	8680	2026-09-16 11:14	26.51	OK
8681	2026-09-16 11:15	25.98	OK	8682	2026-09-16 11:16	26.94	OK
8683	2026-09-16 11:17	25.38	OK	8684	2026-09-16 11:18	27.86	OK
8685	2026-09-16 11:19	24.78	OK	8686	2026-09-16 11:20	25.50	OK
8687	2026-09-16 11:21	25.39	OK	8688	2026-09-16 11:22	26.61	OK
8689	2026-09-16 11:23	25.95	OK	8690	2026-09-16 11:24	27.27	OK
8691	2026-09-16 11:25	26.93	OK	8692	2026-09-16 11:26	25.80	OK
8693	2026-09-16 11:27	25.40	OK	8694	2026-09-16 11:28	26.24	OK
8695	2026-09-16 11:29	26.71	OK	8696	2026-09-16 11:30	23.87	OK
8697	2026-09-16 11:31	25.87	OK	8698	2026-09-16 11:32	26.79	OK
8699	2026-09-16 11:33	25.46	OK	8700	2026-09-16 11:34	25.56	OK
8701	2026-09-16 11:35	25.76	OK	8702	2026-09-16 11:36	26.54	OK
8703	2026-09-16 11:37	24.48	OK	8704	2026-09-16 11:38	24.87	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8705	2026-09-16 11:39	26.51	OK	8706	2026-09-16 11:40	26.77	OK
8707	2026-09-16 11:41	26.14	OK	8708	2026-09-16 11:42	25.56	OK
8709	2026-09-16 11:43	25.21	OK	8710	2026-09-16 11:44	25.21	OK
8711	2026-09-16 11:45	25.76	OK	8712	2026-09-16 11:46	26.95	OK
8713	2026-09-16 11:47	26.45	OK	8714	2026-09-16 11:48	26.93	OK
8715	2026-09-16 11:49	26.88	OK	8716	2026-09-16 11:50	25.87	OK
8717	2026-09-16 11:51	25.80	OK	8718	2026-09-16 11:52	25.13	OK
8719	2026-09-16 11:53	27.21	OK	8720	2026-09-16 11:54	26.41	OK
8721	2026-09-16 11:55	25.69	OK	8722	2026-09-16 11:56	25.10	OK
8723	2026-09-16 11:57	26.17	OK	8724	2026-09-16 11:58	24.45	OK
8725	2026-09-16 11:59	26.77	OK	8726	2026-09-16 12:00	26.00	OK
8727	2026-09-16 12:01	25.88	OK	8728	2026-09-16 12:02	24.59	OK
8729	2026-09-16 12:03	26.04	OK	8730	2026-09-16 12:04	26.79	OK
8731	2026-09-16 12:05	26.14	OK	8732	2026-09-16 12:06	26.33	OK
8733	2026-09-16 12:07	27.31	OK	8734	2026-09-16 12:08	24.97	OK
8735	2026-09-16 12:09	25.56	OK	8736	2026-09-16 12:10	24.96	OK
8737	2026-09-16 12:11	26.46	OK	8738	2026-09-16 12:12	27.02	OK
8739	2026-09-16 12:13	26.40	OK	8740	2026-09-16 12:14	26.27	OK
8741	2026-09-16 12:15	25.67	OK	8742	2026-09-16 12:16	25.12	OK
8743	2026-09-16 12:17	26.67	OK	8744	2026-09-16 12:18	26.77	OK
8745	2026-09-16 12:19	25.22	OK	8746	2026-09-16 12:20	26.52	OK
8747	2026-09-16 12:21	27.19	OK	8748	2026-09-16 12:22	25.73	OK
8749	2026-09-16 12:23	25.26	OK	8750	2026-09-16 12:24	26.24	OK
8751	2026-09-16 12:25	27.19	OK	8752	2026-09-16 12:26	26.57	OK
8753	2026-09-16 12:27	26.71	OK	8754	2026-09-16 12:28	26.03	OK
8755	2026-09-16 12:29	26.32	OK	8756	2026-09-16 12:30	24.87	OK
8757	2026-09-16 12:31	25.49	OK	8758	2026-09-16 12:32	26.61	OK
8759	2026-09-16 12:33	26.86	OK	8760	2026-09-16 12:34	25.04	OK
8761	2026-09-16 12:35	25.73	OK	8762	2026-09-16 12:36	26.82	OK
8763	2026-09-16 12:37	26.13	OK	8764	2026-09-16 12:38	25.87	OK
8765	2026-09-16 12:39	25.16	OK	8766	2026-09-16 12:40	27.51	OK
8767	2026-09-16 12:41	25.42	OK	8768	2026-09-16 12:42	24.83	OK
8769	2026-09-16 12:43	25.46	OK	8770	2026-09-16 12:44	27.03	OK
8771	2026-09-16 12:45	26.08	OK	8772	2026-09-16 12:46	24.76	OK
8773	2026-09-16 12:47	27.38	OK	8774	2026-09-16 12:48	24.96	OK
8775	2026-09-16 12:49	24.47	OK	8776	2026-09-16 12:50	25.66	OK
8777	2026-09-16 12:51	25.51	OK	8778	2026-09-16 12:52	25.62	OK
8779	2026-09-16 12:53	25.56	OK	8780	2026-09-16 12:54	25.52	OK
8781	2026-09-16 12:55	25.95	OK	8782	2026-09-16 12:56	25.31	OK
8783	2026-09-16 12:57	25.97	OK	8784	2026-09-16 12:58	24.82	OK
8785	2026-09-16 12:59	25.59	OK	8786	2026-09-16 13:00	27.45	OK
8787	2026-09-16 13:01	25.24	OK	8788	2026-09-16 13:02	26.90	OK
8789	2026-09-16 13:03	26.00	OK	8790	2026-09-16 13:04	26.03	OK
8791	2026-09-16 13:05	25.29	OK	8792	2026-09-16 13:06	25.54	OK
8793	2026-09-16 13:07	25.15	OK	8794	2026-09-16 13:08	25.84	OK
8795	2026-09-16 13:09	25.78	OK	8796	2026-09-16 13:10	26.88	OK
8797	2026-09-16 13:11	26.52	OK	8798	2026-09-16 13:12	27.12	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8799	2026-09-16 13:13	24.41	OK	8800	2026-09-16 13:14	25.73	OK
8801	2026-09-16 13:15	24.47	OK	8802	2026-09-16 13:16	27.06	OK
8803	2026-09-16 13:17	26.22	OK	8804	2026-09-16 13:18	24.82	OK
8805	2026-09-16 13:19	25.92	OK	8806	2026-09-16 13:20	26.16	OK
8807	2026-09-16 13:21	26.14	OK	8808	2026-09-16 13:22	26.42	OK
8809	2026-09-16 13:23	26.39	OK	8810	2026-09-16 13:24	25.86	OK
8811	2026-09-16 13:25	27.02	OK	8812	2026-09-16 13:26	26.03	OK
8813	2026-09-16 13:27	26.33	OK	8814	2026-09-16 13:28	24.92	OK
8815	2026-09-16 13:29	25.87	OK	8816	2026-09-16 13:30	25.16	OK
8817	2026-09-16 13:31	26.01	OK	8818	2026-09-16 13:32	25.22	OK
8819	2026-09-16 13:33	25.51	OK	8820	2026-09-16 13:34	26.13	OK
8821	2026-09-16 13:35	25.93	OK	8822	2026-09-16 13:36	24.87	OK
8823	2026-09-16 13:37	25.85	OK	8824	2026-09-16 13:38	26.38	OK
8825	2026-09-16 13:39	26.66	OK	8826	2026-09-16 13:40	25.31	OK
8827	2026-09-16 13:41	24.03	OK	8828	2026-09-16 13:42	25.28	OK
8829	2026-09-16 13:43	26.79	OK	8830	2026-09-16 13:44	27.22	OK
8831	2026-09-16 13:45	24.90	OK	8832	2026-09-16 13:46	25.28	OK
8833	2026-09-16 13:47	24.51	OK	8834	2026-09-16 13:48	26.41	OK
8835	2026-09-16 13:49	24.60	OK	8836	2026-09-16 13:50	26.94	OK
8837	2026-09-16 13:51	26.09	OK	8838	2026-09-16 13:52	24.85	OK
8839	2026-09-16 13:53	24.46	OK	8840	2026-09-16 13:54	26.79	OK
8841	2026-09-16 13:55	24.97	OK	8842	2026-09-16 13:56	26.86	OK
8843	2026-09-16 13:57	24.96	OK	8844	2026-09-16 13:58	26.09	OK
8845	2026-09-16 13:59	26.56	OK	8846	2026-09-16 14:00	26.41	OK
8847	2026-09-16 14:01	24.38	OK	8848	2026-09-16 14:02	24.56	OK
8849	2026-09-16 14:03	25.69	OK	8850	2026-09-16 14:04	25.14	OK
8851	2026-09-16 14:05	25.97	OK	8852	2026-09-16 14:06	24.41	OK
8853	2026-09-16 14:07	25.66	OK	8854	2026-09-16 14:08	25.39	OK
8855	2026-09-16 14:09	25.04	OK	8856	2026-09-16 14:10	24.84	OK
8857	2026-09-16 14:11	25.24	OK	8858	2026-09-16 14:12	25.80	OK
8859	2026-09-16 14:13	25.56	OK	8860	2026-09-16 14:14	26.05	OK
8861	2026-09-16 14:15	26.62	OK	8862	2026-09-16 14:16	24.52	OK
8863	2026-09-16 14:17	25.46	OK	8864	2026-09-16 14:18	25.15	OK
8865	2026-09-16 14:19	25.27	OK	8866	2026-09-16 14:20	25.60	OK
8867	2026-09-16 14:21	26.07	OK	8868	2026-09-16 14:22	25.99	OK
8869	2026-09-16 14:23	25.14	OK	8870	2026-09-16 14:24	26.96	OK
8871	2026-09-16 14:25	26.35	OK	8872	2026-09-16 14:26	24.63	OK
8873	2026-09-16 14:27	24.34	OK	8874	2026-09-16 14:28	25.70	OK
8875	2026-09-16 14:29	24.89	OK	8876	2026-09-16 14:30	26.77	OK
8877	2026-09-16 14:31	25.43	OK	8878	2026-09-16 14:32	26.27	OK
8879	2026-09-16 14:33	26.73	OK	8880	2026-09-16 14:34	24.87	OK
8881	2026-09-16 14:35	26.98	OK	8882	2026-09-16 14:36	24.90	OK
8883	2026-09-16 14:37	26.34	OK	8884	2026-09-16 14:38	25.91	OK
8885	2026-09-16 14:39	25.83	OK	8886	2026-09-16 14:40	26.45	OK
8887	2026-09-16 14:41	26.81	OK	8888	2026-09-16 14:42	26.21	OK
8889	2026-09-16 14:43	24.79	OK	8890	2026-09-16 14:44	25.83	OK
8891	2026-09-16 14:45	26.65	OK	8892	2026-09-16 14:46	26.63	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8893	2026-09-16 14:47	26.45	OK	8894	2026-09-16 14:48	24.79	OK
8895	2026-09-16 14:49	25.88	OK	8896	2026-09-16 14:50	26.35	OK
8897	2026-09-16 14:51	25.43	OK	8898	2026-09-16 14:52	25.47	OK
8899	2026-09-16 14:53	25.93	OK	8900	2026-09-16 14:54	25.96	OK
8901	2026-09-16 14:55	25.98	OK	8902	2026-09-16 14:56	27.13	OK
8903	2026-09-16 14:57	25.38	OK	8904	2026-09-16 14:58	26.39	OK
8905	2026-09-16 14:59	26.56	OK	8906	2026-09-16 15:00	26.26	OK
8907	2026-09-16 15:01	26.05	OK	8908	2026-09-16 15:02	25.40	OK
8909	2026-09-16 15:03	24.51	OK	8910	2026-09-16 15:04	25.79	OK
8911	2026-09-16 15:05	25.49	OK	8912	2026-09-16 15:06	25.62	OK
8913	2026-09-16 15:07	25.34	OK	8914	2026-09-16 15:08	25.48	OK
8915	2026-09-16 15:09	26.34	OK	8916	2026-09-16 15:10	25.38	OK
8917	2026-09-16 15:11	27.29	OK	8918	2026-09-16 15:12	25.61	OK
8919	2026-09-16 15:13	26.43	OK	8920	2026-09-16 15:14	25.98	OK
8921	2026-09-16 15:15	25.44	OK	8922	2026-09-16 15:16	25.18	OK
8923	2026-09-16 15:17	26.92	OK	8924	2026-09-16 15:18	25.70	OK
8925	2026-09-16 15:19	25.80	OK	8926	2026-09-16 15:20	24.87	OK
8927	2026-09-16 15:21	25.75	OK	8928	2026-09-16 15:22	26.11	OK
8929	2026-09-16 15:23	25.59	OK	8930	2026-09-16 15:24	27.55	OK
8931	2026-09-16 15:25	26.08	OK	8932	2026-09-16 15:26	26.76	OK
8933	2026-09-16 15:27	26.20	OK	8934	2026-09-16 15:28	26.31	OK
8935	2026-09-16 15:29	25.33	OK	8936	2026-09-16 15:30	25.46	OK
8937	2026-09-16 15:31	25.16	OK	8938	2026-09-16 15:32	25.71	OK
8939	2026-09-16 15:33	26.03	OK	8940	2026-09-16 15:34	24.96	OK
8941	2026-09-16 15:35	26.33	OK	8942	2026-09-16 15:36	24.13	OK
8943	2026-09-16 15:37	26.78	OK	8944	2026-09-16 15:38	25.79	OK
8945	2026-09-16 15:39	26.99	OK	8946	2026-09-16 15:40	26.57	OK
8947	2026-09-16 15:41	25.24	OK	8948	2026-09-16 15:42	26.05	OK
8949	2026-09-16 15:43	23.97	OK	8950	2026-09-16 15:44	25.56	OK
8951	2026-09-16 15:45	25.36	OK	8952	2026-09-16 15:46	25.70	OK
8953	2026-09-16 15:47	25.98	OK	8954	2026-09-16 15:48	25.82	OK
8955	2026-09-16 15:49	25.79	OK	8956	2026-09-16 15:50	27.65	OK
8957	2026-09-16 15:51	25.57	OK	8958	2026-09-16 15:52	26.40	OK
8959	2026-09-16 15:53	25.18	OK	8960	2026-09-16 15:54	27.13	OK
8961	2026-09-16 15:55	26.56	OK	8962	2026-09-16 15:56	25.95	OK
8963	2026-09-16 15:57	25.89	OK	8964	2026-09-16 15:58	26.82	OK
8965	2026-09-16 15:59	26.21	OK	8966	2026-09-16 16:00	27.00	OK
8967	2026-09-16 16:01	26.39	OK	8968	2026-09-16 16:02	25.97	OK
8969	2026-09-16 16:03	26.94	OK	8970	2026-09-16 16:04	26.21	OK
8971	2026-09-16 16:05	25.23	OK	8972	2026-09-16 16:06	27.08	OK
8973	2026-09-16 16:07	24.93	OK	8974	2026-09-16 16:08	24.71	OK
8975	2026-09-16 16:09	26.46	OK	8976	2026-09-16 16:10	24.98	OK
8977	2026-09-16 16:11	26.76	OK	8978	2026-09-16 16:12	24.71	OK
8979	2026-09-16 16:13	26.91	OK	8980	2026-09-16 16:14	26.20	OK
8981	2026-09-16 16:15	27.58	OK	8982	2026-09-16 16:16	25.86	OK
8983	2026-09-16 16:17	26.30	OK	8984	2026-09-16 16:18	25.15	OK
8985	2026-09-16 16:19	26.38	OK	8986	2026-09-16 16:20	24.96	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
8987	2026-09-16 16:21	26.70	OK	8988	2026-09-16 16:22	27.74	OK
8989	2026-09-16 16:23	26.50	OK	8990	2026-09-16 16:24	25.97	OK
8991	2026-09-16 16:25	27.23	OK	8992	2026-09-16 16:26	26.70	OK
8993	2026-09-16 16:27	26.35	OK	8994	2026-09-16 16:28	27.07	OK
8995	2026-09-16 16:29	25.99	OK	8996	2026-09-16 16:30	25.63	OK
8997	2026-09-16 16:31	26.98	OK	8998	2026-09-16 16:32	25.60	OK
8999	2026-09-16 16:33	26.08	OK	9000	2026-09-16 16:34	26.79	OK
9001	2026-09-16 16:35	27.76	OK	9002	2026-09-16 16:36	27.13	OK
9003	2026-09-16 16:37	27.77	OK	9004	2026-09-16 16:38	25.82	OK
9005	2026-09-16 16:39	25.32	OK	9006	2026-09-16 16:40	27.18	OK
9007	2026-09-16 16:41	25.97	OK	9008	2026-09-16 16:42	27.28	OK
9009	2026-09-16 16:43	25.31	OK	9010	2026-09-16 16:44	26.70	OK
9011	2026-09-16 16:45	26.90	OK	9012	2026-09-16 16:46	27.28	OK
9013	2026-09-16 16:47	24.99	OK	9014	2026-09-16 16:48	26.49	OK
9015	2026-09-16 16:49	26.32	OK	9016	2026-09-16 16:50	27.43	OK
9017	2026-09-16 16:51	27.15	OK	9018	2026-09-16 16:52	25.57	OK
9019	2026-09-16 16:53	26.43	OK	9020	2026-09-16 16:54	27.17	OK
9021	2026-09-16 16:55	27.16	OK	9022	2026-09-16 16:56	25.66	OK
9023	2026-09-16 16:57	25.49	OK	9024	2026-09-16 16:58	26.43	OK
9025	2026-09-16 16:59	26.06	OK	9026	2026-09-16 17:00	26.39	OK
9027	2026-09-16 17:01	27.11	OK	9028	2026-09-16 17:02	25.20	OK
9029	2026-09-16 17:03	26.24	OK	9030	2026-09-16 17:04	26.32	OK
9031	2026-09-16 17:05	27.15	OK	9032	2026-09-16 17:06	27.21	OK
9033	2026-09-16 17:07	26.14	OK	9034	2026-09-16 17:08	27.77	OK
9035	2026-09-16 17:09	26.25	OK	9036	2026-09-16 17:10	26.23	OK
9037	2026-09-16 17:11	26.10	OK	9038	2026-09-16 17:12	26.85	OK
9039	2026-09-16 17:13	26.89	OK	9040	2026-09-16 17:14	27.50	OK
9041	2026-09-16 17:15	26.85	OK	9042	2026-09-16 17:16	27.13	OK
9043	2026-09-16 17:17	27.12	OK	9044	2026-09-16 17:18	26.91	OK
9045	2026-09-16 17:19	25.97	OK	9046	2026-09-16 17:20	27.37	OK
9047	2026-09-16 17:21	27.99	OK	9048	2026-09-16 17:22	26.99	OK
9049	2026-09-16 17:23	26.56	OK	9050	2026-09-16 17:24	26.44	OK
9051	2026-09-16 17:25	27.55	OK	9052	2026-09-16 17:26	27.56	OK
9053	2026-09-16 17:27	26.08	OK	9054	2026-09-16 17:28	26.42	OK
9055	2026-09-16 17:29	25.77	OK	9056	2026-09-16 17:30	28.31	OK
9057	2026-09-16 17:31	26.73	OK	9058	2026-09-16 17:32	26.68	OK
9059	2026-09-16 17:33	26.94	OK	9060	2026-09-16 17:34	27.69	OK
9061	2026-09-16 17:35	25.87	OK	9062	2026-09-16 17:36	27.82	OK
9063	2026-09-16 17:37	26.44	OK	9064	2026-09-16 17:38	26.63	OK
9065	2026-09-16 17:39	26.39	OK	9066	2026-09-16 17:40	27.28	OK
9067	2026-09-16 17:41	27.10	OK	9068	2026-09-16 17:42	26.26	OK
9069	2026-09-16 17:43	26.41	OK	9070	2026-09-16 17:44	26.61	OK
9071	2026-09-16 17:45	27.65	OK	9072	2026-09-16 17:46	27.42	OK
9073	2026-09-16 17:47	26.10	OK	9074	2026-09-16 17:48	26.23	OK
9075	2026-09-16 17:49	27.68	OK	9076	2026-09-16 17:50	26.54	OK
9077	2026-09-16 17:51	27.38	OK	9078	2026-09-16 17:52	27.83	OK
9079	2026-09-16 17:53	26.88	OK	9080	2026-09-16 17:54	26.71	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9081	2026-09-16 17:55	26.55	OK	9082	2026-09-16 17:56	25.81	OK
9083	2026-09-16 17:57	25.63	OK	9084	2026-09-16 17:58	27.44	OK
9085	2026-09-16 17:59	28.31	OK	9086	2026-09-16 18:00	27.59	OK
9087	2026-09-16 18:01	27.66	OK	9088	2026-09-16 18:02	27.83	OK
9089	2026-09-16 18:03	26.19	OK	9090	2026-09-16 18:04	26.79	OK
9091	2026-09-16 18:05	26.84	OK	9092	2026-09-16 18:06	27.74	OK
9093	2026-09-16 18:07	26.80	OK	9094	2026-09-16 18:08	26.80	OK
9095	2026-09-16 18:09	26.53	OK	9096	2026-09-16 18:10	28.90	OK
9097	2026-09-16 18:11	28.08	OK	9098	2026-09-16 18:12	26.52	OK
9099	2026-09-16 18:13	26.94	OK	9100	2026-09-16 18:14	26.69	OK
9101	2026-09-16 18:15	26.76	OK	9102	2026-09-16 18:16	26.83	OK
9103	2026-09-16 18:17	27.92	OK	9104	2026-09-16 18:18	26.17	OK
9105	2026-09-16 18:19	28.04	OK	9106	2026-09-16 18:20	26.91	OK
9107	2026-09-16 18:21	26.58	OK	9108	2026-09-16 18:22	27.04	OK
9109	2026-09-16 18:23	27.01	OK	9110	2026-09-16 18:24	27.30	OK
9111	2026-09-16 18:25	26.21	OK	9112	2026-09-16 18:26	28.48	OK
9113	2026-09-16 18:27	26.60	OK	9114	2026-09-16 18:28	28.23	OK
9115	2026-09-16 18:29	27.19	OK	9116	2026-09-16 18:30	27.01	OK
9117	2026-09-16 18:31	26.22	OK	9118	2026-09-16 18:32	27.84	OK
9119	2026-09-16 18:33	28.60	OK	9120	2026-09-16 18:34	27.33	OK
9121	2026-09-16 18:35	28.31	OK	9122	2026-09-16 18:36	27.26	OK
9123	2026-09-16 18:37	28.42	OK	9124	2026-09-16 18:38	27.23	OK
9125	2026-09-16 18:39	28.01	OK	9126	2026-09-16 18:40	28.03	OK
9127	2026-09-16 18:41	28.23	OK	9128	2026-09-16 18:42	27.95	OK
9129	2026-09-16 18:43	28.58	OK	9130	2026-09-16 18:44	27.67	OK
9131	2026-09-16 18:45	28.13	OK	9132	2026-09-16 18:46	27.83	OK
9133	2026-09-16 18:47	26.77	OK	9134	2026-09-16 18:48	27.96	OK
9135	2026-09-16 18:49	28.67	OK	9136	2026-09-16 18:50	28.11	OK
9137	2026-09-16 18:51	27.88	OK	9138	2026-09-16 18:52	25.94	OK
9139	2026-09-16 18:53	27.35	OK	9140	2026-09-16 18:54	27.28	OK
9141	2026-09-16 18:55	27.24	OK	9142	2026-09-16 18:56	27.47	OK
9143	2026-09-16 18:57	27.57	OK	9144	2026-09-16 18:58	26.56	OK
9145	2026-09-16 18:59	27.68	OK	9146	2026-09-16 19:00	27.89	OK
9147	2026-09-16 19:01	28.97	OK	9148	2026-09-16 19:02	27.87	OK
9149	2026-09-16 19:03	27.41	OK	9150	2026-09-16 19:04	27.21	OK
9151	2026-09-16 19:05	28.51	OK	9152	2026-09-16 19:06	26.92	OK
9153	2026-09-16 19:07	27.14	OK	9154	2026-09-16 19:08	27.95	OK
9155	2026-09-16 19:09	27.87	OK	9156	2026-09-16 19:10	26.51	OK
9157	2026-09-16 19:11	28.44	OK	9158	2026-09-16 19:12	27.37	OK
9159	2026-09-16 19:13	28.29	OK	9160	2026-09-16 19:14	26.96	OK
9161	2026-09-16 19:15	27.49	OK	9162	2026-09-16 19:16	27.44	OK
9163	2026-09-16 19:17	27.80	OK	9164	2026-09-16 19:18	28.10	OK
9165	2026-09-16 19:19	28.01	OK	9166	2026-09-16 19:20	27.42	OK
9167	2026-09-16 19:21	27.11	OK	9168	2026-09-16 19:22	27.12	OK
9169	2026-09-16 19:23	27.63	OK	9170	2026-09-16 19:24	27.99	OK
9171	2026-09-16 19:25	26.99	OK	9172	2026-09-16 19:26	29.13	OK
9173	2026-09-16 19:27	28.76	OK	9174	2026-09-16 19:28	29.16	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9175	2026-09-16 19:29	28.42	OK	9176	2026-09-16 19:30	26.89	OK
9177	2026-09-16 19:31	26.92	OK	9178	2026-09-16 19:32	28.29	OK
9179	2026-09-16 19:33	28.08	OK	9180	2026-09-16 19:34	27.54	OK
9181	2026-09-16 19:35	28.40	OK	9182	2026-09-16 19:36	28.74	OK
9183	2026-09-16 19:37	28.76	OK	9184	2026-09-16 19:38	28.13	OK
9185	2026-09-16 19:39	29.38	OK	9186	2026-09-16 19:40	28.44	OK
9187	2026-09-16 19:41	29.14	OK	9188	2026-09-16 19:42	28.28	OK
9189	2026-09-16 19:43	27.83	OK	9190	2026-09-16 19:44	27.73	OK
9191	2026-09-16 19:45	28.79	OK	9192	2026-09-16 19:46	26.75	OK
9193	2026-09-16 19:47	27.17	OK	9194	2026-09-16 19:48	28.69	OK
9195	2026-09-16 19:49	29.23	OK	9196	2026-09-16 19:50	28.48	OK
9197	2026-09-16 19:51	27.39	OK	9198	2026-09-16 19:52	28.07	OK
9199	2026-09-16 19:53	27.23	OK	9200	2026-09-16 19:54	28.23	OK
9201	2026-09-16 19:55	27.67	OK	9202	2026-09-16 19:56	28.48	OK
9203	2026-09-16 19:57	29.57	OK	9204	2026-09-16 19:58	27.87	OK
9205	2026-09-16 19:59	27.83	OK	9206	2026-09-16 20:00	27.86	OK
9207	2026-09-16 20:01	29.82	OK	9208	2026-09-16 20:02	26.84	OK
9209	2026-09-16 20:03	27.52	OK	9210	2026-09-16 20:04	28.76	OK
9211	2026-09-16 20:05	27.54	OK	9212	2026-09-16 20:06	27.76	OK
9213	2026-09-16 20:07	28.86	OK	9214	2026-09-16 20:08	29.59	OK
9215	2026-09-16 20:09	29.04	OK	9216	2026-09-16 20:10	30.06	OK
9217	2026-09-16 20:11	29.19	OK	9218	2026-09-16 20:12	26.70	OK
9219	2026-09-16 20:13	29.34	OK	9220	2026-09-16 20:14	28.15	OK
9221	2026-09-16 20:15	27.75	OK	9222	2026-09-16 20:16	28.19	OK
9223	2026-09-16 20:17	29.25	OK	9224	2026-09-16 20:18	29.15	OK
9225	2026-09-16 20:19	28.76	OK	9226	2026-09-16 20:20	30.13	OK
9227	2026-09-16 20:21	29.10	OK	9228	2026-09-16 20:22	28.41	OK
9229	2026-09-16 20:23	28.79	OK	9230	2026-09-16 20:24	29.09	OK
9231	2026-09-16 20:25	28.06	OK	9232	2026-09-16 20:26	28.63	OK
9233	2026-09-16 20:27	29.24	OK	9234	2026-09-16 20:28	27.39	OK
9235	2026-09-16 20:29	29.08	OK	9236	2026-09-16 20:30	29.23	OK
9237	2026-09-16 20:31	28.83	OK	9238	2026-09-16 20:32	28.12	OK
9239	2026-09-16 20:33	28.05	OK	9240	2026-09-16 20:34	28.88	OK
9241	2026-09-16 20:35	29.97	OK	9242	2026-09-16 20:36	29.26	OK
9243	2026-09-16 20:37	29.17	OK	9244	2026-09-16 20:38	28.13	OK
9245	2026-09-16 20:39	27.70	OK	9246	2026-09-16 20:40	28.12	OK
9247	2026-09-16 20:41	29.09	OK	9248	2026-09-16 20:42	28.54	OK
9249	2026-09-16 20:43	28.20	OK	9250	2026-09-16 20:44	29.40	OK
9251	2026-09-16 20:45	29.37	OK	9252	2026-09-16 20:46	28.01	OK
9253	2026-09-16 20:47	27.86	OK	9254	2026-09-16 20:48	28.32	OK
9255	2026-09-16 20:49	27.73	OK	9256	2026-09-16 20:50	28.46	OK
9257	2026-09-16 20:51	29.57	OK	9258	2026-09-16 20:52	29.06	OK
9259	2026-09-16 20:53	29.85	OK	9260	2026-09-16 20:54	28.48	OK
9261	2026-09-16 20:55	27.17	OK	9262	2026-09-16 20:56	28.11	OK
9263	2026-09-16 20:57	29.16	OK	9264	2026-09-16 20:58	28.82	OK
9265	2026-09-16 20:59	29.16	OK	9266	2026-09-16 21:00	29.84	OK
9267	2026-09-16 21:01	29.75	OK	9268	2026-09-16 21:02	29.44	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9269	2026-09-16 21:03	30.71	OK	9270	2026-09-16 21:04	29.41	OK
9271	2026-09-16 21:05	30.10	OK	9272	2026-09-16 21:06	29.80	OK
9273	2026-09-16 21:07	28.31	OK	9274	2026-09-16 21:08	28.90	OK
9275	2026-09-16 21:09	29.38	OK	9276	2026-09-16 21:10	28.51	OK
9277	2026-09-16 21:11	28.29	OK	9278	2026-09-16 21:12	28.78	OK
9279	2026-09-16 21:13	29.36	OK	9280	2026-09-16 21:14	28.78	OK
9281	2026-09-16 21:15	27.28	OK	9282	2026-09-16 21:16	28.71	OK
9283	2026-09-16 21:17	28.53	OK	9284	2026-09-16 21:18	30.10	OK
9285	2026-09-16 21:19	29.50	OK	9286	2026-09-16 21:20	29.15	OK
9287	2026-09-16 21:21	29.31	OK	9288	2026-09-16 21:22	30.03	OK
9289	2026-09-16 21:23	30.42	OK	9290	2026-09-16 21:24	28.39	OK
9291	2026-09-16 21:25	30.09	OK	9292	2026-09-16 21:26	28.43	OK
9293	2026-09-16 21:27	28.65	OK	9294	2026-09-16 21:28	30.62	OK
9295	2026-09-16 21:29	29.64	OK	9296	2026-09-16 21:30	30.00	OK
9297	2026-09-16 21:31	29.65	OK	9298	2026-09-16 21:32	27.52	OK
9299	2026-09-16 21:33	28.98	OK	9300	2026-09-16 21:34	28.83	OK
9301	2026-09-16 21:35	28.56	OK	9302	2026-09-16 21:36	29.50	OK
9303	2026-09-16 21:37	29.58	OK	9304	2026-09-16 21:38	29.04	OK
9305	2026-09-16 21:39	29.75	OK	9306	2026-09-16 21:40	29.96	OK
9307	2026-09-16 21:41	28.53	OK	9308	2026-09-16 21:42	29.13	OK
9309	2026-09-16 21:43	28.23	OK	9310	2026-09-16 21:44	29.98	OK
9311	2026-09-16 21:45	29.09	OK	9312	2026-09-16 21:46	30.33	OK
9313	2026-09-16 21:47	29.34	OK	9314	2026-09-16 21:48	30.54	OK
9315	2026-09-16 21:49	29.83	OK	9316	2026-09-16 21:50	30.50	OK
9317	2026-09-16 21:51	28.82	OK	9318	2026-09-16 21:52	29.94	OK
9319	2026-09-16 21:53	29.95	OK	9320	2026-09-16 21:54	29.99	OK
9321	2026-09-16 21:55	29.54	OK	9322	2026-09-16 21:56	30.33	OK
9323	2026-09-16 21:57	29.60	OK	9324	2026-09-16 21:58	29.82	OK
9325	2026-09-16 21:59	29.89	OK	9326	2026-09-16 22:00	30.37	OK
9327	2026-09-16 22:01	29.58	OK	9328	2026-09-16 22:02	28.05	OK
9329	2026-09-16 22:03	29.42	OK	9330	2026-09-16 22:04	29.68	OK
9331	2026-09-16 22:05	29.18	OK	9332	2026-09-16 22:06	29.75	OK
9333	2026-09-16 22:07	29.93	OK	9334	2026-09-16 22:08	27.98	OK
9335	2026-09-16 22:09	28.93	OK	9336	2026-09-16 22:10	29.95	OK
9337	2026-09-16 22:11	29.36	OK	9338	2026-09-16 22:12	29.05	OK
9339	2026-09-16 22:13	28.53	OK	9340	2026-09-16 22:14	29.99	OK
9341	2026-09-16 22:15	29.52	OK	9342	2026-09-16 22:16	30.09	OK
9343	2026-09-16 22:17	31.12	OK	9344	2026-09-16 22:18	28.52	OK
9345	2026-09-16 22:19	28.09	OK	9346	2026-09-16 22:20	29.60	OK
9347	2026-09-16 22:21	27.72	OK	9348	2026-09-16 22:22	28.81	OK
9349	2026-09-16 22:23	29.91	OK	9350	2026-09-16 22:24	30.08	OK
9351	2026-09-16 22:25	29.90	OK	9352	2026-09-16 22:26	30.19	OK
9353	2026-09-16 22:27	29.80	OK	9354	2026-09-16 22:28	29.52	OK
9355	2026-09-16 22:29	28.15	OK	9356	2026-09-16 22:30	28.32	OK
9357	2026-09-16 22:31	31.34	OK	9358	2026-09-16 22:32	31.87	OK
9359	2026-09-16 22:33	28.53	OK	9360	2026-09-16 22:34	29.91	OK
9361	2026-09-16 22:35	30.49	OK	9362	2026-09-16 22:36	28.31	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9363	2026-09-16 22:37	30.05	OK	9364	2026-09-16 22:38	31.45	OK
9365	2026-09-16 22:39	30.20	OK	9366	2026-09-16 22:40	30.95	OK
9367	2026-09-16 22:41	30.18	OK	9368	2026-09-16 22:42	29.24	OK
9369	2026-09-16 22:43	30.84	OK	9370	2026-09-16 22:44	29.12	OK
9371	2026-09-16 22:45	30.82	OK	9372	2026-09-16 22:46	30.60	OK
9373	2026-09-16 22:47	28.47	OK	9374	2026-09-16 22:48	28.51	OK
9375	2026-09-16 22:49	30.32	OK	9376	2026-09-16 22:50	29.53	OK
9377	2026-09-16 22:51	29.92	OK	9378	2026-09-16 22:52	29.00	OK
9379	2026-09-16 22:53	29.48	OK	9380	2026-09-16 22:54	31.00	OK
9381	2026-09-16 22:55	29.93	OK	9382	2026-09-16 22:56	29.08	OK
9383	2026-09-16 22:57	29.61	OK	9384	2026-09-16 22:58	31.13	OK
9385	2026-09-16 22:59	29.93	OK	9386	2026-09-16 23:00	28.33	OK
9387	2026-09-16 23:01	29.36	OK	9388	2026-09-16 23:02	29.43	OK
9389	2026-09-16 23:03	30.79	OK	9390	2026-09-16 23:04	31.68	OK
9391	2026-09-16 23:05	30.93	OK	9392	2026-09-16 23:06	30.13	OK
9393	2026-09-16 23:07	31.31	OK	9394	2026-09-16 23:08	29.07	OK
9395	2026-09-16 23:09	29.89	OK	9396	2026-09-16 23:10	29.77	OK
9397	2026-09-16 23:11	30.07	OK	9398	2026-09-16 23:12	28.09	OK
9399	2026-09-16 23:13	29.15	OK	9400	2026-09-16 23:14	30.97	OK
9401	2026-09-16 23:15	29.35	OK	9402	2026-09-16 23:16	29.62	OK
9403	2026-09-16 23:17	29.87	OK	9404	2026-09-16 23:18	29.60	OK
9405	2026-09-16 23:19	29.84	OK	9406	2026-09-16 23:20	28.99	OK
9407	2026-09-16 23:21	30.46	OK	9408	2026-09-16 23:22	30.82	OK
9409	2026-09-16 23:23	30.16	OK	9410	2026-09-16 23:24	30.15	OK
9411	2026-09-16 23:25	29.95	OK	9412	2026-09-16 23:26	30.65	OK
9413	2026-09-16 23:27	30.41	OK	9414	2026-09-16 23:28	30.29	OK
9415	2026-09-16 23:29	30.39	OK	9416	2026-09-16 23:30	30.73	OK
9417	2026-09-16 23:31	30.90	OK	9418	2026-09-16 23:32	30.42	OK
9419	2026-09-16 23:33	29.66	OK	9420	2026-09-16 23:34	29.36	OK
9421	2026-09-16 23:35	30.44	OK	9422	2026-09-16 23:36	31.22	OK
9423	2026-09-16 23:37	29.94	OK	9424	2026-09-16 23:38	29.86	OK
9425	2026-09-16 23:39	31.02	OK	9426	2026-09-16 23:40	31.60	OK
9427	2026-09-16 23:41	29.38	OK	9428	2026-09-16 23:42	28.86	OK
9429	2026-09-16 23:43	30.30	OK	9430	2026-09-16 23:44	30.30	OK
9431	2026-09-16 23:45	29.64	OK	9432	2026-09-16 23:46	29.13	OK
9433	2026-09-16 23:47	29.50	OK	9434	2026-09-16 23:48	29.59	OK
9435	2026-09-16 23:49	28.98	OK	9436	2026-09-16 23:50	29.25	OK
9437	2026-09-16 23:51	28.61	OK	9438	2026-09-16 23:52	30.47	OK
9439	2026-09-16 23:53	29.18	OK	9440	2026-09-16 23:54	28.95	OK
9441	2026-09-16 23:55	30.26	OK	9442	2026-09-16 23:56	30.83	OK
9443	2026-09-16 23:57	28.65	OK	9444	2026-09-16 23:58	31.15	OK
9445	2026-09-16 23:59	29.15	OK	9446	2026-09-17 00:00	29.90	OK
9447	2026-09-17 00:01	28.59	OK	9448	2026-09-17 00:02	31.17	OK
9449	2026-09-17 00:03	29.64	OK	9450	2026-09-17 00:04	30.58	OK
9451	2026-09-17 00:05	29.92	OK	9452	2026-09-17 00:06	30.00	OK
9453	2026-09-17 00:07	29.00	OK	9454	2026-09-17 00:08	31.15	OK
9455	2026-09-17 00:09	30.24	OK	9456	2026-09-17 00:10	30.64	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9457	2026-09-17 00:11	30.16	OK	9458	2026-09-17 00:12	31.27	OK
9459	2026-09-17 00:13	28.80	OK	9460	2026-09-17 00:14	28.92	OK
9461	2026-09-17 00:15	29.72	OK	9462	2026-09-17 00:16	31.77	OK
9463	2026-09-17 00:17	29.19	OK	9464	2026-09-17 00:18	30.18	OK
9465	2026-09-17 00:19	29.83	OK	9466	2026-09-17 00:20	30.85	OK
9467	2026-09-17 00:21	30.14	OK	9468	2026-09-17 00:22	30.12	OK
9469	2026-09-17 00:23	30.97	OK	9470	2026-09-17 00:24	30.63	OK
9471	2026-09-17 00:25	30.30	OK	9472	2026-09-17 00:26	30.21	OK
9473	2026-09-17 00:27	30.47	OK	9474	2026-09-17 00:28	29.82	OK
9475	2026-09-17 00:29	29.28	OK	9476	2026-09-17 00:30	31.64	OK
9477	2026-09-17 00:31	30.14	OK	9478	2026-09-17 00:32	29.26	OK
9479	2026-09-17 00:33	31.27	OK	9480	2026-09-17 00:34	30.50	OK
9481	2026-09-17 00:35	30.74	OK	9482	2026-09-17 00:36	30.10	OK
9483	2026-09-17 00:37	31.10	OK	9484	2026-09-17 00:38	29.72	OK
9485	2026-09-17 00:39	30.48	OK	9486	2026-09-17 00:40	29.00	OK
9487	2026-09-17 00:41	30.08	OK	9488	2026-09-17 00:42	29.74	OK
9489	2026-09-17 00:43	30.15	OK	9490	2026-09-17 00:44	30.88	OK
9491	2026-09-17 00:45	29.83	OK	9492	2026-09-17 00:46	30.05	OK
9493	2026-09-17 00:47	31.13	OK	9494	2026-09-17 00:48	30.37	OK
9495	2026-09-17 00:49	30.60	OK	9496	2026-09-17 00:50	29.17	OK
9497	2026-09-17 00:51	30.99	OK	9498	2026-09-17 00:52	29.24	OK
9499	2026-09-17 00:53	29.84	OK	9500	2026-09-17 00:54	28.59	OK
9501	2026-09-17 00:55	31.26	OK	9502	2026-09-17 00:56	30.13	OK
9503	2026-09-17 00:57	28.30	OK	9504	2026-09-17 00:58	30.74	OK
9505	2026-09-17 00:59	30.77	OK	9506	2026-09-17 01:00	30.56	OK
9507	2026-09-17 01:01	31.30	OK	9508	2026-09-17 01:02	29.68	OK
9509	2026-09-17 01:03	30.34	OK	9510	2026-09-17 01:04	32.34	OK
9511	2026-09-17 01:05	29.99	OK	9512	2026-09-17 01:06	30.59	OK
9513	2026-09-17 01:07	29.88	OK	9514	2026-09-17 01:08	30.49	OK
9515	2026-09-17 01:09	30.44	OK	9516	2026-09-17 01:10	30.96	OK
9517	2026-09-17 01:11	30.11	OK	9518	2026-09-17 01:12	30.95	OK
9519	2026-09-17 01:13	30.51	OK	9520	2026-09-17 01:14	30.52	OK
9521	2026-09-17 01:15	29.14	OK	9522	2026-09-17 01:16	29.93	OK
9523	2026-09-17 01:17	30.09	OK	9524	2026-09-17 01:18	29.73	OK
9525	2026-09-17 01:19	29.73	OK	9526	2026-09-17 01:20	30.63	OK
9527	2026-09-17 01:21	30.33	OK	9528	2026-09-17 01:22	30.46	OK
9529	2026-09-17 01:23	31.03	OK	9530	2026-09-17 01:24	30.68	OK
9531	2026-09-17 01:25	28.83	OK	9532	2026-09-17 01:26	31.12	OK
9533	2026-09-17 01:27	30.27	OK	9534	2026-09-17 01:28	31.40	OK
9535	2026-09-17 01:29	30.71	OK	9536	2026-09-17 01:30	29.82	OK
9537	2026-09-17 01:31	30.18	OK	9538	2026-09-17 01:32	29.22	OK
9539	2026-09-17 01:33	28.69	OK	9540	2026-09-17 01:34	30.53	OK
9541	2026-09-17 01:35	29.85	OK	9542	2026-09-17 01:36	29.74	OK
9543	2026-09-17 01:37	30.72	OK	9544	2026-09-17 01:38	30.25	OK
9545	2026-09-17 01:39	30.75	OK	9546	2026-09-17 01:40	30.95	OK
9547	2026-09-17 01:41	30.25	OK	9548	2026-09-17 01:42	29.54	OK
9549	2026-09-17 01:43	30.97	OK	9550	2026-09-17 01:44	29.85	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9551	2026-09-17 01:45	29.98	OK	9552	2026-09-17 01:46	29.46	OK
9553	2026-09-17 01:47	31.13	OK	9554	2026-09-17 01:48	29.33	OK
9555	2026-09-17 01:49	30.69	OK	9556	2026-09-17 01:50	30.14	OK
9557	2026-09-17 01:51	29.48	OK	9558	2026-09-17 01:52	30.55	OK
9559	2026-09-17 01:53	31.13	OK	9560	2026-09-17 01:54	30.31	OK
9561	2026-09-17 01:55	30.27	OK	9562	2026-09-17 01:56	31.22	OK
9563	2026-09-17 01:57	29.93	OK	9564	2026-09-17 01:58	30.16	OK
9565	2026-09-17 01:59	31.27	OK	9566	2026-09-17 02:00	30.10	OK
9567	2026-09-17 02:01	29.91	OK	9568	2026-09-17 02:02	29.76	OK
9569	2026-09-17 02:03	30.15	OK	9570	2026-09-17 02:04	29.75	OK
9571	2026-09-17 02:05	30.50	OK	9572	2026-09-17 02:06	29.13	OK
9573	2026-09-17 02:07	29.18	OK	9574	2026-09-17 02:08	29.35	OK
9575	2026-09-17 02:09	30.68	OK	9576	2026-09-17 02:10	30.96	OK
9577	2026-09-17 02:11	31.42	OK	9578	2026-09-17 02:12	31.48	OK
9579	2026-09-17 02:13	32.12	OK	9580	2026-09-17 02:14	30.11	OK
9581	2026-09-17 02:15	31.04	OK	9582	2026-09-17 02:16	28.76	OK
9583	2026-09-17 02:17	30.23	OK	9584	2026-09-17 02:18	31.03	OK
9585	2026-09-17 02:19	29.07	OK	9586	2026-09-17 02:20	28.54	OK
9587	2026-09-17 02:21	28.98	OK	9588	2026-09-17 02:22	31.44	OK
9589	2026-09-17 02:23	31.87	OK	9590	2026-09-17 02:24	28.34	OK
9591	2026-09-17 02:25	30.98	OK	9592	2026-09-17 02:26	30.50	OK
9593	2026-09-17 02:27	29.73	OK	9594	2026-09-17 02:28	30.06	OK
9595	2026-09-17 02:29	30.52	OK	9596	2026-09-17 02:30	31.13	OK
9597	2026-09-17 02:31	30.97	OK	9598	2026-09-17 02:32	30.57	OK
9599	2026-09-17 02:33	30.93	OK	9600	2026-09-17 02:34	29.71	OK
9601	2026-09-17 02:35	28.69	OK	9602	2026-09-17 02:36	30.75	OK
9603	2026-09-17 02:37	31.32	OK	9604	2026-09-17 02:38	31.08	OK
9605	2026-09-17 02:39	29.89	OK	9606	2026-09-17 02:40	29.06	OK
9607	2026-09-17 02:41	29.34	OK	9608	2026-09-17 02:42	30.43	OK
9609	2026-09-17 02:43	29.52	OK	9610	2026-09-17 02:44	30.43	OK
9611	2026-09-17 02:45	29.78	OK	9612	2026-09-17 02:46	29.86	OK
9613	2026-09-17 02:47	29.71	OK	9614	2026-09-17 02:48	30.56	OK
9615	2026-09-17 02:49	31.28	OK	9616	2026-09-17 02:50	30.76	OK
9617	2026-09-17 02:51	30.17	OK	9618	2026-09-17 02:52	29.80	OK
9619	2026-09-17 02:53	29.64	OK	9620	2026-09-17 02:54	30.56	OK
9621	2026-09-17 02:55	30.34	OK	9622	2026-09-17 02:56	29.30	OK
9623	2026-09-17 02:57	30.17	OK	9624	2026-09-17 02:58	29.47	OK
9625	2026-09-17 02:59	30.89	OK	9626	2026-09-17 03:00	30.41	OK
9627	2026-09-17 03:01	29.17	OK	9628	2026-09-17 03:02	30.20	OK
9629	2026-09-17 03:03	28.70	OK	9630	2026-09-17 03:04	29.93	OK
9631	2026-09-17 03:05	29.20	OK	9632	2026-09-17 03:06	30.52	OK
9633	2026-09-17 03:07	30.88	OK	9634	2026-09-17 03:08	30.34	OK
9635	2026-09-17 03:09	30.83	OK	9636	2026-09-17 03:10	28.99	OK
9637	2026-09-17 03:11	30.90	OK	9638	2026-09-17 03:12	30.47	OK
9639	2026-09-17 03:13	29.05	OK	9640	2026-09-17 03:14	29.75	OK
9641	2026-09-17 03:15	29.07	OK	9642	2026-09-17 03:16	30.30	OK
9643	2026-09-17 03:17	29.78	OK	9644	2026-09-17 03:18	29.82	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9645	2026-09-17 03:19	29.77	OK	9646	2026-09-17 03:20	30.43	OK
9647	2026-09-17 03:21	30.16	OK	9648	2026-09-17 03:22	28.49	OK
9649	2026-09-17 03:23	29.48	OK	9650	2026-09-17 03:24	29.77	OK
9651	2026-09-17 03:25	29.97	OK	9652	2026-09-17 03:26	29.80	OK
9653	2026-09-17 03:27	29.57	OK	9654	2026-09-17 03:28	31.23	OK
9655	2026-09-17 03:29	28.87	OK	9656	2026-09-17 03:30	30.47	OK
9657	2026-09-17 03:31	29.94	OK	9658	2026-09-17 03:32	28.74	OK
9659	2026-09-17 03:33	30.23	OK	9660	2026-09-17 03:34	28.13	OK
9661	2026-09-17 03:35	31.08	OK	9662	2026-09-17 03:36	30.17	OK
9663	2026-09-17 03:37	29.76	OK	9664	2026-09-17 03:38	29.39	OK
9665	2026-09-17 03:39	30.18	OK	9666	2026-09-17 03:40	31.55	OK
9667	2026-09-17 03:41	29.63	OK	9668	2026-09-17 03:42	30.10	OK
9669	2026-09-17 03:43	29.97	OK	9670	2026-09-17 03:44	30.02	OK
9671	2026-09-17 03:45	29.79	OK	9672	2026-09-17 03:46	29.37	OK
9673	2026-09-17 03:47	30.57	OK	9674	2026-09-17 03:48	30.58	OK
9675	2026-09-17 03:49	30.19	OK	9676	2026-09-17 03:50	29.49	OK
9677	2026-09-17 03:51	30.83	OK	9678	2026-09-17 03:52	31.21	OK
9679	2026-09-17 03:53	29.72	OK	9680	2026-09-17 03:54	29.28	OK
9681	2026-09-17 03:55	30.05	OK	9682	2026-09-17 03:56	30.14	OK
9683	2026-09-17 03:57	29.22	OK	9684	2026-09-17 03:58	29.83	OK
9685	2026-09-17 03:59	30.37	OK	9686	2026-09-17 04:00	29.95	OK
9687	2026-09-17 04:01	27.96	OK	9688	2026-09-17 04:02	29.77	OK
9689	2026-09-17 04:03	29.92	OK	9690	2026-09-17 04:04	28.88	OK
9691	2026-09-17 04:05	30.35	OK	9692	2026-09-17 04:06	29.85	OK
9693	2026-09-17 04:07	29.39	OK	9694	2026-09-17 04:08	30.34	OK
9695	2026-09-17 04:09	29.88	OK	9696	2026-09-17 04:10	30.82	OK
9697	2026-09-17 04:11	29.68	OK	9698	2026-09-17 04:12	28.68	OK
9699	2026-09-17 04:13	28.70	OK	9700	2026-09-17 04:14	30.08	OK
9701	2026-09-17 04:15	29.78	OK	9702	2026-09-17 04:16	29.87	OK
9703	2026-09-17 04:17	29.51	OK	9704	2026-09-17 04:18	28.97	OK
9705	2026-09-17 04:19	29.46	OK	9706	2026-09-17 04:20	28.25	OK
9707	2026-09-17 04:21	28.61	OK	9708	2026-09-17 04:22	29.25	OK
9709	2026-09-17 04:23	28.61	OK	9710	2026-09-17 04:24	29.79	OK
9711	2026-09-17 04:25	31.44	OK	9712	2026-09-17 04:26	28.84	OK
9713	2026-09-17 04:27	29.81	OK	9714	2026-09-17 04:28	30.07	OK
9715	2026-09-17 04:29	29.18	OK	9716	2026-09-17 04:30	31.39	OK
9717	2026-09-17 04:31	31.52	OK	9718	2026-09-17 04:32	30.51	OK
9719	2026-09-17 04:33	29.43	OK	9720	2026-09-17 04:34	29.32	OK
9721	2026-09-17 04:35	30.65	OK	9722	2026-09-17 04:36	30.35	OK
9723	2026-09-17 04:37	28.37	OK	9724	2026-09-17 04:38	30.12	OK
9725	2026-09-17 04:39	28.87	OK	9726	2026-09-17 04:40	29.13	OK
9727	2026-09-17 04:41	29.66	OK	9728	2026-09-17 04:42	29.28	OK
9729	2026-09-17 04:43	29.76	OK	9730	2026-09-17 04:44	29.29	OK
9731	2026-09-17 04:45	29.53	OK	9732	2026-09-17 04:46	30.11	OK
9733	2026-09-17 04:47	28.49	OK	9734	2026-09-17 04:48	29.14	OK
9735	2026-09-17 04:49	29.36	OK	9736	2026-09-17 04:50	30.19	OK
9737	2026-09-17 04:51	29.80	OK	9738	2026-09-17 04:52	29.72	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9739	2026-09-17 04:53	28.29	OK	9740	2026-09-17 04:54	29.81	OK
9741	2026-09-17 04:55	28.93	OK	9742	2026-09-17 04:56	29.00	OK
9743	2026-09-17 04:57	30.17	OK	9744	2026-09-17 04:58	29.84	OK
9745	2026-09-17 04:59	28.87	OK	9746	2026-09-17 05:00	28.75	OK
9747	2026-09-17 05:01	29.71	OK	9748	2026-09-17 05:02	30.41	OK
9749	2026-09-17 05:03	30.64	OK	9750	2026-09-17 05:04	29.89	OK
9751	2026-09-17 05:05	29.63	OK	9752	2026-09-17 05:06	29.00	OK
9753	2026-09-17 05:07	29.65	OK	9754	2026-09-17 05:08	28.96	OK
9755	2026-09-17 05:09	28.22	OK	9756	2026-09-17 05:10	29.60	OK
9757	2026-09-17 05:11	30.09	OK	9758	2026-09-17 05:12	27.81	OK
9759	2026-09-17 05:13	30.77	OK	9760	2026-09-17 05:14	27.84	OK
9761	2026-09-17 05:15	29.60	OK	9762	2026-09-17 05:16	28.71	OK
9763	2026-09-17 05:17	30.37	OK	9764	2026-09-17 05:18	29.15	OK
9765	2026-09-17 05:19	28.72	OK	9766	2026-09-17 05:20	29.14	OK
9767	2026-09-17 05:21	29.42	OK	9768	2026-09-17 05:22	29.13	OK
9769	2026-09-17 05:23	29.35	OK	9770	2026-09-17 05:24	29.10	OK
9771	2026-09-17 05:25	28.60	OK	9772	2026-09-17 05:26	28.74	OK
9773	2026-09-17 05:27	30.01	OK	9774	2026-09-17 05:28	29.78	OK
9775	2026-09-17 05:29	29.51	OK	9776	2026-09-17 05:30	29.01	OK
9777	2026-09-17 05:31	29.15	OK	9778	2026-09-17 05:32	29.66	OK
9779	2026-09-17 05:33	29.59	OK	9780	2026-09-17 05:34	28.13	OK
9781	2026-09-17 05:35	29.05	OK	9782	2026-09-17 05:36	28.67	OK
9783	2026-09-17 05:37	29.93	OK	9784	2026-09-17 05:38	28.37	OK
9785	2026-09-17 05:39	28.71	OK	9786	2026-09-17 05:40	28.52	OK
9787	2026-09-17 05:41	29.15	OK	9788	2026-09-17 05:42	28.45	OK
9789	2026-09-17 05:43	27.89	OK	9790	2026-09-17 05:44	28.89	OK
9791	2026-09-17 05:45	27.80	OK	9792	2026-09-17 05:46	29.44	OK
9793	2026-09-17 05:47	29.59	OK	9794	2026-09-17 05:48	28.14	OK
9795	2026-09-17 05:49	29.24	OK	9796	2026-09-17 05:50	29.47	OK
9797	2026-09-17 05:51	28.79	OK	9798	2026-09-17 05:52	27.73	OK
9799	2026-09-17 05:53	29.83	OK	9800	2026-09-17 05:54	28.21	OK
9801	2026-09-17 05:55	29.77	OK	9802	2026-09-17 05:56	26.84	OK
9803	2026-09-17 05:57	29.82	OK	9804	2026-09-17 05:58	28.74	OK
9805	2026-09-17 05:59	27.93	OK	9806	2026-09-17 06:00	27.22	OK
9807	2026-09-17 06:01	28.69	OK	9808	2026-09-17 06:02	29.41	OK
9809	2026-09-17 06:03	27.58	OK	9810	2026-09-17 06:04	27.70	OK
9811	2026-09-17 06:05	28.80	OK	9812	2026-09-17 06:06	29.56	OK
9813	2026-09-17 06:07	27.38	OK	9814	2026-09-17 06:08	28.25	OK
9815	2026-09-17 06:09	28.93	OK	9816	2026-09-17 06:10	29.79	OK
9817	2026-09-17 06:11	29.10	OK	9818	2026-09-17 06:12	29.79	OK
9819	2026-09-17 06:13	28.35	OK	9820	2026-09-17 06:14	28.27	OK
9821	2026-09-17 06:15	30.17	OK	9822	2026-09-17 06:16	28.40	OK
9823	2026-09-17 06:17	28.93	OK	9824	2026-09-17 06:18	28.27	OK
9825	2026-09-17 06:19	30.36	OK	9826	2026-09-17 06:20	28.15	OK
9827	2026-09-17 06:21	29.08	OK	9828	2026-09-17 06:22	27.63	OK
9829	2026-09-17 06:23	30.14	OK	9830	2026-09-17 06:24	29.68	OK
9831	2026-09-17 06:25	28.83	OK	9832	2026-09-17 06:26	28.83	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9833	2026-09-17 06:27	27.91	OK	9834	2026-09-17 06:28	29.10	OK
9835	2026-09-17 06:29	29.58	OK	9836	2026-09-17 06:30	29.49	OK
9837	2026-09-17 06:31	29.03	OK	9838	2026-09-17 06:32	28.49	OK
9839	2026-09-17 06:33	27.84	OK	9840	2026-09-17 06:34	29.12	OK
9841	2026-09-17 06:35	28.62	OK	9842	2026-09-17 06:36	28.04	OK
9843	2026-09-17 06:37	28.46	OK	9844	2026-09-17 06:38	27.88	OK
9845	2026-09-17 06:39	28.09	OK	9846	2026-09-17 06:40	28.66	OK
9847	2026-09-17 06:41	29.09	OK	9848	2026-09-17 06:42	27.21	OK
9849	2026-09-17 06:43	28.95	OK	9850	2026-09-17 06:44	29.72	OK
9851	2026-09-17 06:45	27.94	OK	9852	2026-09-17 06:46	29.49	OK
9853	2026-09-17 06:47	27.09	OK	9854	2026-09-17 06:48	28.71	OK
9855	2026-09-17 06:49	28.41	OK	9856	2026-09-17 06:50	28.82	OK
9857	2026-09-17 06:51	28.51	OK	9858	2026-09-17 06:52	27.74	OK
9859	2026-09-17 06:53	29.07	OK	9860	2026-09-17 06:54	27.67	OK
9861	2026-09-17 06:55	29.08	OK	9862	2026-09-17 06:56	29.48	OK
9863	2026-09-17 06:57	27.56	OK	9864	2026-09-17 06:58	28.70	OK
9865	2026-09-17 06:59	28.14	OK	9866	2026-09-17 07:00	27.85	OK
9867	2026-09-17 07:01	27.28	OK	9868	2026-09-17 07:02	26.88	OK
9869	2026-09-17 07:03	27.26	OK	9870	2026-09-17 07:04	26.97	OK
9871	2026-09-17 07:05	27.66	OK	9872	2026-09-17 07:06	29.29	OK
9873	2026-09-17 07:07	27.27	OK	9874	2026-09-17 07:08	28.97	OK
9875	2026-09-17 07:09	27.27	OK	9876	2026-09-17 07:10	29.82	OK
9877	2026-09-17 07:11	29.19	OK	9878	2026-09-17 07:12	27.75	OK
9879	2026-09-17 07:13	27.67	OK	9880	2026-09-17 07:14	28.31	OK
9881	2026-09-17 07:15	28.10	OK	9882	2026-09-17 07:16	27.51	OK
9883	2026-09-17 07:17	28.98	OK	9884	2026-09-17 07:18	29.08	OK
9885	2026-09-17 07:19	28.76	OK	9886	2026-09-17 07:20	29.00	OK
9887	2026-09-17 07:21	27.61	OK	9888	2026-09-17 07:22	27.88	OK
9889	2026-09-17 07:23	29.31	OK	9890	2026-09-17 07:24	28.99	OK
9891	2026-09-17 07:25	27.57	OK	9892	2026-09-17 07:26	26.94	OK
9893	2026-09-17 07:27	26.47	OK	9894	2026-09-17 07:28	26.71	OK
9895	2026-09-17 07:29	27.19	OK	9896	2026-09-17 07:30	28.21	OK
9897	2026-09-17 07:31	28.53	OK	9898	2026-09-17 07:32	27.97	OK
9899	2026-09-17 07:33	26.06	OK	9900	2026-09-17 07:34	27.89	OK
9901	2026-09-17 07:35	29.16	OK	9902	2026-09-17 07:36	28.06	OK
9903	2026-09-17 07:37	26.99	OK	9904	2026-09-17 07:38	28.14	OK
9905	2026-09-17 07:39	27.93	OK	9906	2026-09-17 07:40	27.84	OK
9907	2026-09-17 07:41	29.13	OK	9908	2026-09-17 07:42	29.23	OK
9909	2026-09-17 07:43	27.79	OK	9910	2026-09-17 07:44	26.84	OK
9911	2026-09-17 07:45	27.99	OK	9912	2026-09-17 07:46	27.73	OK
9913	2026-09-17 07:47	27.99	OK	9914	2026-09-17 07:48	28.03	OK
9915	2026-09-17 07:49	29.18	OK	9916	2026-09-17 07:50	28.07	OK
9917	2026-09-17 07:51	27.64	OK	9918	2026-09-17 07:52	28.59	OK
9919	2026-09-17 07:53	29.07	OK	9920	2026-09-17 07:54	26.72	OK
9921	2026-09-17 07:55	28.33	OK	9922	2026-09-17 07:56	28.40	OK
9923	2026-09-17 07:57	26.83	OK	9924	2026-09-17 07:58	27.46	OK
9925	2026-09-17 07:59	26.26	OK	9926	2026-09-17 08:00	28.33	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
9927	2026-09-17 08:01	28.32	OK	9928	2026-09-17 08:02	28.77	OK
9929	2026-09-17 08:03	27.97	OK	9930	2026-09-17 08:04	27.64	OK
9931	2026-09-17 08:05	27.53	OK	9932	2026-09-17 08:06	27.62	OK
9933	2026-09-17 08:07	27.57	OK	9934	2026-09-17 08:08	26.40	OK
9935	2026-09-17 08:09	26.83	OK	9936	2026-09-17 08:10	27.67	OK
9937	2026-09-17 08:11	28.03	OK	9938	2026-09-17 08:12	27.07	OK
9939	2026-09-17 08:13	27.76	OK	9940	2026-09-17 08:14	27.07	OK
9941	2026-09-17 08:15	26.94	OK	9942	2026-09-17 08:16	27.77	OK
9943	2026-09-17 08:17	27.34	OK	9944	2026-09-17 08:18	28.14	OK
9945	2026-09-17 08:19	27.19	OK	9946	2026-09-17 08:20	26.37	OK
9947	2026-09-17 08:21	27.48	OK	9948	2026-09-17 08:22	26.05	OK
9949	2026-09-17 08:23	27.67	OK	9950	2026-09-17 08:24	27.39	OK
9951	2026-09-17 08:25	27.78	OK	9952	2026-09-17 08:26	26.12	OK
9953	2026-09-17 08:27	27.86	OK	9954	2026-09-17 08:28	28.55	OK
9955	2026-09-17 08:29	28.32	OK	9956	2026-09-17 08:30	28.50	OK
9957	2026-09-17 08:31	27.59	OK	9958	2026-09-17 08:32	26.88	OK
9959	2026-09-17 08:33	27.67	OK	9960	2026-09-17 08:34	26.90	OK
9961	2026-09-17 08:35	27.06	OK	9962	2026-09-17 08:36	27.58	OK
9963	2026-09-17 08:37	27.75	OK	9964	2026-09-17 08:38	27.22	OK
9965	2026-09-17 08:39	26.80	OK	9966	2026-09-17 08:40	26.60	OK
9967	2026-09-17 08:41	27.09	OK	9968	2026-09-17 08:42	27.60	OK
9969	2026-09-17 08:43	27.50	OK	9970	2026-09-17 08:44	28.40	OK
9971	2026-09-17 08:45	27.08	OK	9972	2026-09-17 08:46	27.39	OK
9973	2026-09-17 08:47	25.63	OK	9974	2026-09-17 08:48	28.24	OK
9975	2026-09-17 08:49	27.52	OK	9976	2026-09-17 08:50	27.48	OK
9977	2026-09-17 08:51	27.12	OK	9978	2026-09-17 08:52	28.06	OK
9979	2026-09-17 08:53	26.63	OK	9980	2026-09-17 08:54	27.15	OK
9981	2026-09-17 08:55	25.74	OK	9982	2026-09-17 08:56	26.93	OK
9983	2026-09-17 08:57	27.00	OK	9984	2026-09-17 08:58	27.69	OK
9985	2026-09-17 08:59	27.04	OK	9986	2026-09-17 09:00	28.62	OK
9987	2026-09-17 09:01	27.45	OK	9988	2026-09-17 09:02	27.43	OK
9989	2026-09-17 09:03	27.98	OK	9990	2026-09-17 09:04	26.96	OK
9991	2026-09-17 09:05	26.16	OK	9992	2026-09-17 09:06	26.82	OK
9993	2026-09-17 09:07	26.60	OK	9994	2026-09-17 09:08	28.05	OK
9995	2026-09-17 09:09	28.32	OK	9996	2026-09-17 09:10	27.30	OK
9997	2026-09-17 09:11	27.80	OK	9998	2026-09-17 09:12	27.00	OK
9999	2026-09-17 09:13	26.29	OK	1000	2026-09-17 09:14	27.65	OK
1000	2026-09-17 09:15	27.17	OK	0			
1000	2026-09-17 09:17	26.54	OK	1000	2026-09-17 09:16	26.88	OK
3				2			
1000	2026-09-17 09:19	27.19	OK	1000	2026-09-17 09:18	26.31	OK
5				4			
1000	2026-09-17 09:21	27.91	OK	1000	2026-09-17 09:20	26.32	OK
7				6			
1000	2026-09-17 09:23	26.19	OK	1000	2026-09-17 09:22	26.29	OK
9				8			
1001	2026-09-17 09:25	25.44	OK	1001	2026-09-17 09:24	27.18	OK
1				0			
				1001	2026-09-17 09:26	26.24	OK
				2			

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10013	2026-09-17 09:27	27.42	OK	10014	2026-09-17 09:28	27.04	OK
10015	2026-09-17 09:29	27.11	OK	10016	2026-09-17 09:30	26.64	OK
10017	2026-09-17 09:31	26.30	OK	10018	2026-09-17 09:32	26.91	OK
10019	2026-09-17 09:33	26.25	OK	10020	2026-09-17 09:34	26.28	OK
10021	2026-09-17 09:35	26.02	OK	10022	2026-09-17 09:36	27.17	OK
10023	2026-09-17 09:37	28.79	OK	10024	2026-09-17 09:38	25.29	OK
10025	2026-09-17 09:39	26.15	OK	10026	2026-09-17 09:40	25.70	OK
10027	2026-09-17 09:41	25.44	OK	10028	2026-09-17 09:42	27.34	OK
10029	2026-09-17 09:43	27.03	OK	10030	2026-09-17 09:44	28.04	OK
10031	2026-09-17 09:45	26.79	OK	10032	2026-09-17 09:46	25.18	OK
10033	2026-09-17 09:47	26.59	OK	10034	2026-09-17 09:48	28.04	OK
10035	2026-09-17 09:49	27.46	OK	10036	2026-09-17 09:50	26.88	OK
10037	2026-09-17 09:51	27.48	OK	10038	2026-09-17 09:52	25.77	OK
10039	2026-09-17 09:53	27.37	OK	10040	2026-09-17 09:54	25.95	OK
10041	2026-09-17 09:55	25.62	OK	10042	2026-09-17 09:56	26.84	OK
10043	2026-09-17 09:57	24.89	OK	10044	2026-09-17 09:58	26.01	OK
10045	2026-09-17 09:59	26.31	OK	10046	2026-09-17 10:00	25.88	OK
10047	2026-09-17 10:01	27.08	OK	10048	2026-09-17 10:02	26.41	OK
10049	2026-09-17 10:03	27.57	OK	10050	2026-09-17 10:04	26.25	OK
10051	2026-09-17 10:05	25.10	OK	10052	2026-09-17 10:06	27.00	OK
10053	2026-09-17 10:07	27.20	OK	10054	2026-09-17 10:08	26.90	OK
10055	2026-09-17 10:09	27.24	OK	10056	2026-09-17 10:10	25.18	OK
10057	2026-09-17 10:11	26.39	OK	10058	2026-09-17 10:12	26.31	OK
10059	2026-09-17 10:13	26.91	OK	10060	2026-09-17 10:14	27.22	OK
10061	2026-09-17 10:15	26.85	OK	10062	2026-09-17 10:16	25.54	OK
10063	2026-09-17 10:17	25.38	OK	10064	2026-09-17 10:18	26.95	OK
10065	2026-09-17 10:19	27.44	OK	10066	2026-09-17 10:20	26.14	OK
10067	2026-09-17 10:21	26.78	OK	10068	2026-09-17 10:22	26.77	OK
10069	2026-09-17 10:23	28.30	OK	10070	2026-09-17 10:24	26.76	OK
10071	2026-09-17 10:25	26.18	OK	10072	2026-09-17 10:26	24.90	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10073	2026-09-17 10:27	26.29	OK	10074	2026-09-17 10:28	26.70	OK
10075	2026-09-17 10:29	26.80	OK	10076	2026-09-17 10:30	26.03	OK
10077	2026-09-17 10:31	26.46	OK	10078	2026-09-17 10:32	25.66	OK
10079	2026-09-17 10:33	27.39	OK	10080	2026-09-17 10:34	26.81	OK
10081	2026-09-17 10:35	24.98	OK	10082	2026-09-17 10:36	25.76	OK
10083	2026-09-17 10:37	25.73	OK	10084	2026-09-17 10:38	27.28	OK
10085	2026-09-17 10:39	26.57	OK	10086	2026-09-17 10:40	25.61	OK
10087	2026-09-17 10:41	25.53	OK	10088	2026-09-17 10:42	26.95	OK
10089	2026-09-17 10:43	26.98	OK	10090	2026-09-17 10:44	26.93	OK
10091	2026-09-17 10:45	25.68	OK	10092	2026-09-17 10:46	26.11	OK
10093	2026-09-17 10:47	27.52	OK	10094	2026-09-17 10:48	26.01	OK
10095	2026-09-17 10:49	26.74	OK	10096	2026-09-17 10:50	25.71	OK
10097	2026-09-17 10:51	25.79	OK	10098	2026-09-17 10:52	27.01	OK
10099	2026-09-17 10:53	26.42	OK	10100	2026-09-17 10:54	25.89	OK
10101	2026-09-17 10:55	25.06	OK	10102	2026-09-17 10:56	26.72	OK
10103	2026-09-17 10:57	24.79	OK	10104	2026-09-17 10:58	26.10	OK
10105	2026-09-17 10:59	27.38	OK	10106	2026-09-17 11:00	26.43	OK
10107	2026-09-17 11:01	26.47	OK	10108	2026-09-17 11:02	27.24	OK
10109	2026-09-17 11:03	26.05	OK	10110	2026-09-17 11:04	25.53	OK
10111	2026-09-17 11:05	26.23	OK	10112	2026-09-17 11:06	25.59	OK
10113	2026-09-17 11:07	26.48	OK	10114	2026-09-17 11:08	25.90	OK
10115	2026-09-17 11:09	25.82	OK	10116	2026-09-17 11:10	25.01	OK
10117	2026-09-17 11:11	25.24	OK	10118	2026-09-17 11:12	26.32	OK
10119	2026-09-17 11:13	27.73	OK	10120	2026-09-17 11:14	26.88	OK
10121	2026-09-17 11:15	27.04	OK	10122	2026-09-17 11:16	25.81	OK
10123	2026-09-17 11:17	26.26	OK	10124	2026-09-17 11:18	25.43	OK
10125	2026-09-17 11:19	26.32	OK	10126	2026-09-17 11:20	27.15	OK
10127	2026-09-17 11:21	26.34	OK	10128	2026-09-17 11:22	26.07	OK
10129	2026-09-17 11:23	26.01	OK	10130	2026-09-17 11:24	25.07	OK
10131	2026-09-17 11:25	26.19	OK	10132	2026-09-17 11:26	25.35	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10133	2026-09-17 11:27	26.53	OK	10134	2026-09-17 11:28	26.54	OK
10135	2026-09-17 11:29	25.47	OK	10136	2026-09-17 11:30	26.72	OK
10137	2026-09-17 11:31	25.57	OK	10138	2026-09-17 11:32	26.26	OK
10139	2026-09-17 11:33	25.84	OK	10140	2026-09-17 11:34	26.56	OK
10141	2026-09-17 11:35	25.28	OK	10142	2026-09-17 11:36	26.36	OK
10143	2026-09-17 11:37	25.34	OK	10144	2026-09-17 11:38	26.08	OK
10145	2026-09-17 11:39	26.36	OK	10146	2026-09-17 11:40	26.15	OK
10147	2026-09-17 11:41	24.61	OK	10148	2026-09-17 11:42	25.68	OK
10149	2026-09-17 11:43	25.37	OK	10150	2026-09-17 11:44	26.38	OK
10151	2026-09-17 11:45	26.54	OK	10152	2026-09-17 11:46	26.48	OK
10153	2026-09-17 11:47	25.01	OK	10154	2026-09-17 11:48	27.14	OK
10155	2026-09-17 11:49	25.33	OK	10156	2026-09-17 11:50	26.31	OK
10157	2026-09-17 11:51	27.02	OK	10158	2026-09-17 11:52	26.69	OK
10159	2026-09-17 11:53	26.17	OK	10160	2026-09-17 11:54	25.26	OK
10161	2026-09-17 11:55	25.54	OK	10162	2026-09-17 11:56	26.50	OK
10163	2026-09-17 11:57	26.04	OK	10164	2026-09-17 11:58	25.85	OK
10165	2026-09-17 11:59	26.20	OK	10166	2026-09-17 12:00	26.01	OK
10167	2026-09-17 12:01	25.62	OK	10168	2026-09-17 12:02	25.04	OK
10169	2026-09-17 12:03	26.13	OK	10170	2026-09-17 12:04	24.84	OK
10171	2026-09-17 12:05	25.95	OK	10172	2026-09-17 12:06	26.50	OK
10173	2026-09-17 12:07	26.04	OK	10174	2026-09-17 12:08	26.69	OK
10175	2026-09-17 12:09	25.21	OK	10176	2026-09-17 12:10	24.92	OK
10177	2026-09-17 12:11	26.50	OK	10178	2026-09-17 12:12	25.26	OK
10179	2026-09-17 12:13	26.43	OK	10180	2026-09-17 12:14	25.45	OK
10181	2026-09-17 12:15	25.07	OK	10182	2026-09-17 12:16	26.20	OK
10183	2026-09-17 12:17	26.00	OK	10184	2026-09-17 12:18	25.45	OK
10185	2026-09-17 12:19	25.06	OK	10186	2026-09-17 12:20	26.60	OK
10187	2026-09-17 12:21	25.35	OK	10188	2026-09-17 12:22	27.07	OK
10189	2026-09-17 12:23	25.56	OK	10190	2026-09-17 12:24	26.68	OK
10191	2026-09-17 12:25	26.42	OK	10192	2026-09-17 12:26	25.64	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10193	2026-09-17 12:27	25.95	OK	10194	2026-09-17 12:28	24.12	OK
10195	2026-09-17 12:29	25.09	OK	10196	2026-09-17 12:30	25.32	OK
10197	2026-09-17 12:31	24.23	OK	10198	2026-09-17 12:32	24.69	OK
10199	2026-09-17 12:33	23.99	OK	10200	2026-09-17 12:34	26.65	OK
10201	2026-09-17 12:35	26.02	OK	10202	2026-09-17 12:36	25.71	OK
10203	2026-09-17 12:37	25.69	OK	10204	2026-09-17 12:38	25.69	OK
10205	2026-09-17 12:39	24.86	OK	10206	2026-09-17 12:40	24.90	OK
10207	2026-09-17 12:41	24.30	OK	10208	2026-09-17 12:42	25.97	OK
10209	2026-09-17 12:43	26.14	OK	10210	2026-09-17 12:44	24.92	OK
10211	2026-09-17 12:45	26.41	OK	10212	2026-09-17 12:46	25.52	OK
10213	2026-09-17 12:47	24.22	OK	10214	2026-09-17 12:48	25.28	OK
10215	2026-09-17 12:49	26.20	OK	10216	2026-09-17 12:50	26.79	OK
10217	2026-09-17 12:51	25.06	OK	10218	2026-09-17 12:52	25.47	OK
10219	2026-09-17 12:53	25.09	OK	10220	2026-09-17 12:54	25.01	OK
10221	2026-09-17 12:55	24.79	OK	10222	2026-09-17 12:56	25.54	OK
10223	2026-09-17 12:57	25.04	OK	10224	2026-09-17 12:58	25.30	OK
10225	2026-09-17 12:59	27.32	OK	10226	2026-09-17 13:00	24.74	OK
10227	2026-09-17 13:01	25.29	OK	10228	2026-09-17 13:02	25.20	OK
10229	2026-09-17 13:03	24.59	OK	10230	2026-09-17 13:04	26.84	OK
10231	2026-09-17 13:05	26.07	OK	10232	2026-09-17 13:06	26.59	OK
10233	2026-09-17 13:07	26.78	OK	10234	2026-09-17 13:08	25.67	OK
10235	2026-09-17 13:09	25.16	OK	10236	2026-09-17 13:10	25.41	OK
10237	2026-09-17 13:11	24.71	OK	10238	2026-09-17 13:12	27.07	OK
10239	2026-09-17 13:13	24.94	OK	10240	2026-09-17 13:14	25.28	OK
10241	2026-09-17 13:15	26.02	OK	10242	2026-09-17 13:16	26.79	OK
10243	2026-09-17 13:17	25.77	OK	10244	2026-09-17 13:18	24.73	OK
10245	2026-09-17 13:19	26.65	OK	10246	2026-09-17 13:20	25.66	OK
10247	2026-09-17 13:21	26.25	OK	10248	2026-09-17 13:22	25.89	OK
10249	2026-09-17 13:23	25.58	OK	10250	2026-09-17 13:24	26.15	OK
10251	2026-09-17 13:25	25.74	OK	10252	2026-09-17 13:26	25.57	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10253	2026-09-17 13:27	26.65	OK	10254	2026-09-17 13:28	26.23	OK
10255	2026-09-17 13:29	26.42	OK	10256	2026-09-17 13:30	24.88	OK
10257	2026-09-17 13:31	25.77	OK	10258	2026-09-17 13:32	25.01	OK
10259	2026-09-17 13:33	25.82	OK	10260	2026-09-17 13:34	24.98	OK
10261	2026-09-17 13:35	26.85	OK	10262	2026-09-17 13:36	25.73	OK
10263	2026-09-17 13:37	24.81	OK	10264	2026-09-17 13:38	25.82	OK
10265	2026-09-17 13:39	25.60	OK	10266	2026-09-17 13:40	25.80	OK
10267	2026-09-17 13:41	26.15	OK	10268	2026-09-17 13:42	25.27	OK
10269	2026-09-17 13:43	26.19	OK	10270	2026-09-17 13:44	25.76	OK
10271	2026-09-17 13:45	25.86	OK	10272	2026-09-17 13:46	24.64	OK
10273	2026-09-17 13:47	27.39	OK	10274	2026-09-17 13:48	26.49	OK
10275	2026-09-17 13:49	25.97	OK	10276	2026-09-17 13:50	26.46	OK
10277	2026-09-17 13:51	25.99	OK	10278	2026-09-17 13:52	25.55	OK
10279	2026-09-17 13:53	25.14	OK	10280	2026-09-17 13:54	26.20	OK
10281	2026-09-17 13:55	25.38	OK	10282	2026-09-17 13:56	26.66	OK
10283	2026-09-17 13:57	26.69	OK	10284	2026-09-17 13:58	26.21	OK
10285	2026-09-17 13:59	25.56	OK	10286	2026-09-17 14:00	25.21	OK
10287	2026-09-17 14:01	24.13	OK	10288	2026-09-17 14:02	25.60	OK
10289	2026-09-17 14:03	26.66	OK	10290	2026-09-17 14:04	24.49	OK
10291	2026-09-17 14:05	26.03	OK	10292	2026-09-17 14:06	25.12	OK
10293	2026-09-17 14:07	25.08	OK	10294	2026-09-17 14:08	27.14	OK
10295	2026-09-17 14:09	25.83	OK	10296	2026-09-17 14:10	26.44	OK
10297	2026-09-17 14:11	25.67	OK	10298	2026-09-17 14:12	26.23	OK
10299	2026-09-17 14:13	25.72	OK	10300	2026-09-17 14:14	27.62	OK
10301	2026-09-17 14:15	25.26	OK	10302	2026-09-17 14:16	26.87	OK
10303	2026-09-17 14:17	25.68	OK	10304	2026-09-17 14:18	25.80	OK
10305	2026-09-17 14:19	24.65	OK	10306	2026-09-17 14:20	25.52	OK
10307	2026-09-17 14:21	25.84	OK	10308	2026-09-17 14:22	24.98	OK
10309	2026-09-17 14:23	25.88	OK	10310	2026-09-17 14:24	25.78	OK
10311	2026-09-17 14:25	25.76	OK	10312	2026-09-17 14:26	24.91	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10313	2026-09-17 14:27	27.39	OK	10314	2026-09-17 14:28	26.64	OK
10315	2026-09-17 14:29	24.90	OK	10316	2026-09-17 14:30	24.93	OK
10317	2026-09-17 14:31	25.73	OK	10318	2026-09-17 14:32	27.07	OK
10319	2026-09-17 14:33	26.65	OK	10320	2026-09-17 14:34	24.72	OK
10321	2026-09-17 14:35	26.97	OK	10322	2026-09-17 14:36	25.80	OK
10323	2026-09-17 14:37	26.88	OK	10324	2026-09-17 14:38	25.67	OK
10325	2026-09-17 14:39	26.05	OK	10326	2026-09-17 14:40	26.69	OK
10327	2026-09-17 14:41	25.78	OK	10328	2026-09-17 14:42	25.53	OK
10329	2026-09-17 14:43	26.08	OK	10330	2026-09-17 14:44	24.99	OK
10331	2026-09-17 14:45	23.77	OK	10332	2026-09-17 14:46	25.39	OK
10333	2026-09-17 14:47	26.37	OK	10334	2026-09-17 14:48	26.21	OK
10335	2026-09-17 14:49	25.48	OK	10336	2026-09-17 14:50	25.89	OK
10337	2026-09-17 14:51	26.50	OK	10338	2026-09-17 14:52	26.40	OK
10339	2026-09-17 14:53	24.78	OK	10340	2026-09-17 14:54	25.46	OK
10341	2026-09-17 14:55	25.02	OK	10342	2026-09-17 14:56	27.39	OK
10343	2026-09-17 14:57	26.24	OK	10344	2026-09-17 14:58	27.09	OK
10345	2026-09-17 14:59	26.44	OK	10346	2026-09-17 15:00	24.76	OK
10347	2026-09-17 15:01	25.66	OK	10348	2026-09-17 15:02	26.53	OK
10349	2026-09-17 15:03	25.15	OK	10350	2026-09-17 15:04	27.50	OK
10351	2026-09-17 15:05	24.78	OK	10352	2026-09-17 15:06	25.26	OK
10353	2026-09-17 15:07	25.86	OK	10354	2026-09-17 15:08	26.79	OK
10355	2026-09-17 15:09	25.96	OK	10356	2026-09-17 15:10	25.00	OK
10357	2026-09-17 15:11	25.87	OK	10358	2026-09-17 15:12	25.80	OK
10359	2026-09-17 15:13	27.87	OK	10360	2026-09-17 15:14	27.83	OK
10361	2026-09-17 15:15	25.11	OK	10362	2026-09-17 15:16	26.11	OK
10363	2026-09-17 15:17	26.08	OK	10364	2026-09-17 15:18	24.90	OK
10365	2026-09-17 15:19	26.01	OK	10366	2026-09-17 15:20	26.51	OK
10367	2026-09-17 15:21	25.30	OK	10368	2026-09-17 15:22	24.42	OK
10369	2026-09-17 15:23	25.52	OK	10370	2026-09-17 15:24	25.63	OK
10371	2026-09-17 15:25	26.09	OK	10372	2026-09-17 15:26	25.57	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10373	2026-09-17 15:27	24.93	OK	10374	2026-09-17 15:28	26.29	OK
10375	2026-09-17 15:29	26.16	OK	10376	2026-09-17 15:30	26.31	OK
10377	2026-09-17 15:31	25.27	OK	10378	2026-09-17 15:32	26.34	OK
10379	2026-09-17 15:33	26.36	OK	10380	2026-09-17 15:34	26.88	OK
10381	2026-09-17 15:35	25.10	OK	10382	2026-09-17 15:36	25.20	OK
10383	2026-09-17 15:37	25.48	OK	10384	2026-09-17 15:38	25.42	OK
10385	2026-09-17 15:39	25.59	OK	10386	2026-09-17 15:40	25.59	OK
10387	2026-09-17 15:41	26.07	OK	10388	2026-09-17 15:42	25.19	OK
10389	2026-09-17 15:43	25.93	OK	10390	2026-09-17 15:44	26.04	OK
10391	2026-09-17 15:45	27.38	OK	10392	2026-09-17 15:46	25.16	OK
10393	2026-09-17 15:47	26.09	OK	10394	2026-09-17 15:48	25.68	OK
10395	2026-09-17 15:49	26.77	OK	10396	2026-09-17 15:50	25.68	OK
10397	2026-09-17 15:51	25.12	OK	10398	2026-09-17 15:52	26.54	OK
10399	2026-09-17 15:53	26.66	OK	10400	2026-09-17 15:54	25.58	OK
10401	2026-09-17 15:55	24.20	OK	10402	2026-09-17 15:56	27.29	OK
10403	2026-09-17 15:57	25.06	OK	10404	2026-09-17 15:58	25.37	OK
10405	2026-09-17 15:59	25.28	OK	10406	2026-09-17 16:00	26.35	OK
10407	2026-09-17 16:01	27.25	OK	10408	2026-09-17 16:02	25.97	OK
10409	2026-09-17 16:03	25.33	OK	10410	2026-09-17 16:04	25.41	OK
10411	2026-09-17 16:05	26.41	OK	10412	2026-09-17 16:06	24.77	OK
10413	2026-09-17 16:07	25.67	OK	10414	2026-09-17 16:08	26.11	OK
10415	2026-09-17 16:09	26.07	OK	10416	2026-09-17 16:10	25.75	OK
10417	2026-09-17 16:11	25.64	OK	10418	2026-09-17 16:12	25.55	OK
10419	2026-09-17 16:13	25.35	OK	10420	2026-09-17 16:14	25.23	OK
10421	2026-09-17 16:15	25.93	OK	10422	2026-09-17 16:16	26.52	OK
10423	2026-09-17 16:17	26.40	OK	10424	2026-09-17 16:18	26.62	OK
10425	2026-09-17 16:19	26.60	OK	10426	2026-09-17 16:20	27.88	OK
10427	2026-09-17 16:21	25.46	OK	10428	2026-09-17 16:22	25.85	OK
10429	2026-09-17 16:23	26.44	OK	10430	2026-09-17 16:24	26.85	OK
10431	2026-09-17 16:25	26.50	OK	10432	2026-09-17 16:26	26.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10433	2026-09-17 16:27	26.46	OK	10434	2026-09-17 16:28	26.21	OK
10435	2026-09-17 16:29	26.44	OK	10436	2026-09-17 16:30	26.34	OK
10437	2026-09-17 16:31	25.54	OK	10438	2026-09-17 16:32	26.14	OK
10439	2026-09-17 16:33	25.80	OK	10440	2026-09-17 16:34	24.90	OK
10441	2026-09-17 16:35	27.72	OK	10442	2026-09-17 16:36	27.96	OK
10443	2026-09-17 16:37	27.14	OK	10444	2026-09-17 16:38	26.04	OK
10445	2026-09-17 16:39	26.25	OK	10446	2026-09-17 16:40	25.51	OK
10447	2026-09-17 16:41	27.22	OK	10448	2026-09-17 16:42	26.28	OK
10449	2026-09-17 16:43	26.83	OK	10450	2026-09-17 16:44	26.23	OK
10451	2026-09-17 16:45	26.32	OK	10452	2026-09-17 16:46	26.36	OK
10453	2026-09-17 16:47	25.68	OK	10454	2026-09-17 16:48	26.22	OK
10455	2026-09-17 16:49	26.58	OK	10456	2026-09-17 16:50	26.25	OK
10457	2026-09-17 16:51	25.51	OK	10458	2026-09-17 16:52	26.26	OK
10459	2026-09-17 16:53	26.67	OK	10460	2026-09-17 16:54	26.71	OK
10461	2026-09-17 16:55	27.02	OK	10462	2026-09-17 16:56	27.40	OK
10463	2026-09-17 16:57	26.63	OK	10464	2026-09-17 16:58	26.07	OK
10465	2026-09-17 16:59	25.98	OK	10466	2026-09-17 17:00	26.02	OK
10467	2026-09-17 17:01	25.84	OK	10468	2026-09-17 17:02	27.12	OK
10469	2026-09-17 17:03	26.87	OK	10470	2026-09-17 17:04	27.15	OK
10471	2026-09-17 17:05	27.94	OK	10472	2026-09-17 17:06	27.18	OK
10473	2026-09-17 17:07	26.07	OK	10474	2026-09-17 17:08	26.58	OK
10475	2026-09-17 17:09	26.48	OK	10476	2026-09-17 17:10	26.55	OK
10477	2026-09-17 17:11	27.23	OK	10478	2026-09-17 17:12	25.85	OK
10479	2026-09-17 17:13	27.35	OK	10480	2026-09-17 17:14	26.48	OK
10481	2026-09-17 17:15	26.23	OK	10482	2026-09-17 17:16	26.52	OK
10483	2026-09-17 17:17	26.97	OK	10484	2026-09-17 17:18	25.41	OK
10485	2026-09-17 17:19	26.30	OK	10486	2026-09-17 17:20	27.40	OK
10487	2026-09-17 17:21	26.12	OK	10488	2026-09-17 17:22	26.33	OK
10489	2026-09-17 17:23	28.23	OK	10490	2026-09-17 17:24	26.10	OK
10491	2026-09-17 17:25	27.73	OK	10492	2026-09-17 17:26	25.92	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10493	2026-09-17 17:27	25.98	OK	10494	2026-09-17 17:28	27.60	OK
10495	2026-09-17 17:29	26.68	OK	10496	2026-09-17 17:30	27.80	OK
10497	2026-09-17 17:31	28.17	OK	10498	2026-09-17 17:32	27.24	OK
10499	2026-09-17 17:33	27.03	OK	10500	2026-09-17 17:34	27.55	OK
10501	2026-09-17 17:35	26.66	OK	10502	2026-09-17 17:36	27.21	OK
10503	2026-09-17 17:37	27.87	OK	10504	2026-09-17 17:38	26.98	OK
10505	2026-09-17 17:39	26.83	OK	10506	2026-09-17 17:40	27.01	OK
10507	2026-09-17 17:41	25.17	OK	10508	2026-09-17 17:42	26.48	OK
10509	2026-09-17 17:43	27.82	OK	10510	2026-09-17 17:44	26.39	OK
10511	2026-09-17 17:45	27.67	OK	10512	2026-09-17 17:46	26.70	OK
10513	2026-09-17 17:47	27.31	OK	10514	2026-09-17 17:48	27.22	OK
10515	2026-09-17 17:49	27.30	OK	10516	2026-09-17 17:50	26.34	OK
10517	2026-09-17 17:51	27.62	OK	10518	2026-09-17 17:52	27.60	OK
10519	2026-09-17 17:53	27.19	OK	10520	2026-09-17 17:54	26.03	OK
10521	2026-09-17 17:55	25.69	OK	10522	2026-09-17 17:56	25.84	OK
10523	2026-09-17 17:57	27.85	OK	10524	2026-09-17 17:58	26.62	OK
10525	2026-09-17 17:59	27.53	OK	10526	2026-09-17 18:00	27.30	OK
10527	2026-09-17 18:01	26.75	OK	10528	2026-09-17 18:02	27.36	OK
10529	2026-09-17 18:03	25.67	OK	10530	2026-09-17 18:04	27.91	OK
10531	2026-09-17 18:05	27.97	OK	10532	2026-09-17 18:06	27.65	OK
10533	2026-09-17 18:07	28.51	OK	10534	2026-09-17 18:08	26.56	OK
10535	2026-09-17 18:09	27.44	OK	10536	2026-09-17 18:10	26.33	OK
10537	2026-09-17 18:11	27.55	OK	10538	2026-09-17 18:12	26.73	OK
10539	2026-09-17 18:13	28.41	OK	10540	2026-09-17 18:14	26.11	OK
10541	2026-09-17 18:15	26.27	OK	10542	2026-09-17 18:16	27.70	OK
10543	2026-09-17 18:17	26.01	OK	10544	2026-09-17 18:18	28.31	OK
10545	2026-09-17 18:19	27.77	OK	10546	2026-09-17 18:20	27.53	OK
10547	2026-09-17 18:21	27.66	OK	10548	2026-09-17 18:22	27.22	OK
10549	2026-09-17 18:23	27.06	OK	10550	2026-09-17 18:24	28.29	OK
10551	2026-09-17 18:25	28.36	OK	10552	2026-09-17 18:26	27.24	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10553	2026-09-17 18:27	27.27	OK	10554	2026-09-17 18:28	28.25	OK
10555	2026-09-17 18:29	28.35	OK	10556	2026-09-17 18:30	27.74	OK
10557	2026-09-17 18:31	26.22	OK	10558	2026-09-17 18:32	27.74	OK
10559	2026-09-17 18:33	27.61	OK	10560	2026-09-17 18:34	26.90	OK
10561	2026-09-17 18:35	26.54	OK	10562	2026-09-17 18:36	26.38	OK
10563	2026-09-17 18:37	27.08	OK	10564	2026-09-17 18:38	26.75	OK
10565	2026-09-17 18:39	29.17	OK	10566	2026-09-17 18:40	26.46	OK
10567	2026-09-17 18:41	28.48	OK	10568	2026-09-17 18:42	28.74	OK
10569	2026-09-17 18:43	27.86	OK	10570	2026-09-17 18:44	28.47	OK
10571	2026-09-17 18:45	27.28	OK	10572	2026-09-17 18:46	26.23	OK
10573	2026-09-17 18:47	28.17	OK	10574	2026-09-17 18:48	26.67	OK
10575	2026-09-17 18:49	28.10	OK	10576	2026-09-17 18:50	26.79	OK
10577	2026-09-17 18:51	28.00	OK	10578	2026-09-17 18:52	28.57	OK
10579	2026-09-17 18:53	29.02	OK	10580	2026-09-17 18:54	28.90	OK
10581	2026-09-17 18:55	27.33	OK	10582	2026-09-17 18:56	27.95	OK
10583	2026-09-17 18:57	27.76	OK	10584	2026-09-17 18:58	28.50	OK
10585	2026-09-17 18:59	27.77	OK	10586	2026-09-17 19:00	28.36	OK
10587	2026-09-17 19:01	28.32	OK	10588	2026-09-17 19:02	27.80	OK
10589	2026-09-17 19:03	27.05	OK	10590	2026-09-17 19:04	28.44	OK
10591	2026-09-17 19:05	27.11	OK	10592	2026-09-17 19:06	27.46	OK
10593	2026-09-17 19:07	27.83	OK	10594	2026-09-17 19:08	29.27	OK
10595	2026-09-17 19:09	26.45	OK	10596	2026-09-17 19:10	28.05	OK
10597	2026-09-17 19:11	28.72	OK	10598	2026-09-17 19:12	28.49	OK
10599	2026-09-17 19:13	29.33	OK	10600	2026-09-17 19:14	28.62	OK
10601	2026-09-17 19:15	28.66	OK	10602	2026-09-17 19:16	28.72	OK
10603	2026-09-17 19:17	28.53	OK	10604	2026-09-17 19:18	27.04	OK
10605	2026-09-17 19:19	28.29	OK	10606	2026-09-17 19:20	28.09	OK
10607	2026-09-17 19:21	26.94	OK	10608	2026-09-17 19:22	28.60	OK
10609	2026-09-17 19:23	29.33	OK	10610	2026-09-17 19:24	28.03	OK
10611	2026-09-17 19:25	27.97	OK	10612	2026-09-17 19:26	26.09	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10613	2026-09-17 19:27	29.26	OK	10614	2026-09-17 19:28	27.67	OK
10615	2026-09-17 19:29	27.40	OK	10616	2026-09-17 19:30	27.07	OK
10617	2026-09-17 19:31	28.97	OK	10618	2026-09-17 19:32	27.06	OK
10619	2026-09-17 19:33	27.48	OK	10620	2026-09-17 19:34	27.89	OK
10621	2026-09-17 19:35	26.43	OK	10622	2026-09-17 19:36	28.27	OK
10623	2026-09-17 19:37	26.91	OK	10624	2026-09-17 19:38	28.41	OK
10625	2026-09-17 19:39	28.02	OK	10626	2026-09-17 19:40	28.06	OK
10627	2026-09-17 19:41	28.92	OK	10628	2026-09-17 19:42	27.36	OK
10629	2026-09-17 19:43	28.88	OK	10630	2026-09-17 19:44	28.99	OK
10631	2026-09-17 19:45	28.55	OK	10632	2026-09-17 19:46	27.28	OK
10633	2026-09-17 19:47	29.05	OK	10634	2026-09-17 19:48	28.74	OK
10635	2026-09-17 19:49	28.49	OK	10636	2026-09-17 19:50	28.93	OK
10637	2026-09-17 19:51	28.23	OK	10638	2026-09-17 19:52	28.21	OK
10639	2026-09-17 19:53	28.35	OK	10640	2026-09-17 19:54	28.53	OK
10641	2026-09-17 19:55	27.19	OK	10642	2026-09-17 19:56	29.48	OK
10643	2026-09-17 19:57	27.99	OK	10644	2026-09-17 19:58	26.44	OK
10645	2026-09-17 19:59	27.00	OK	10646	2026-09-17 20:00	29.00	OK
10647	2026-09-17 20:01	29.92	OK	10648	2026-09-17 20:02	27.76	OK
10649	2026-09-17 20:03	27.68	OK	10650	2026-09-17 20:04	29.84	OK
10651	2026-09-17 20:05	28.24	OK	10652	2026-09-17 20:06	28.11	OK
10653	2026-09-17 20:07	27.58	OK	10654	2026-09-17 20:08	27.86	OK
10655	2026-09-17 20:09	28.76	OK	10656	2026-09-17 20:10	27.97	OK
10657	2026-09-17 20:11	27.97	OK	10658	2026-09-17 20:12	28.68	OK
10659	2026-09-17 20:13	28.81	OK	10660	2026-09-17 20:14	28.60	OK
10661	2026-09-17 20:15	28.96	OK	10662	2026-09-17 20:16	27.96	OK
10663	2026-09-17 20:17	26.84	OK	10664	2026-09-17 20:18	29.47	OK
10665	2026-09-17 20:19	27.85	OK	10666	2026-09-17 20:20	26.78	OK
10667	2026-09-17 20:21	28.89	OK	10668	2026-09-17 20:22	28.86	OK
10669	2026-09-17 20:23	28.75	OK	10670	2026-09-17 20:24	27.45	OK
10671	2026-09-17 20:25	28.89	OK	10672	2026-09-17 20:26	27.94	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10673	2026-09-17 20:27	29.81	OK	10674	2026-09-17 20:28	28.92	OK
10675	2026-09-17 20:29	28.93	OK	10676	2026-09-17 20:30	28.32	OK
10677	2026-09-17 20:31	28.96	OK	10678	2026-09-17 20:32	29.45	OK
10679	2026-09-17 20:33	28.83	OK	10680	2026-09-17 20:34	27.51	OK
10681	2026-09-17 20:35	29.57	OK	10682	2026-09-17 20:36	27.33	OK
10683	2026-09-17 20:37	28.81	OK	10684	2026-09-17 20:38	28.03	OK
10685	2026-09-17 20:39	28.86	OK	10686	2026-09-17 20:40	29.47	OK
10687	2026-09-17 20:41	29.06	OK	10688	2026-09-17 20:42	29.23	OK
10689	2026-09-17 20:43	29.50	OK	10690	2026-09-17 20:44	28.17	OK
10691	2026-09-17 20:45	30.32	OK	10692	2026-09-17 20:46	28.12	OK
10693	2026-09-17 20:47	27.65	OK	10694	2026-09-17 20:48	28.29	OK
10695	2026-09-17 20:49	28.41	OK	10696	2026-09-17 20:50	29.98	OK
10697	2026-09-17 20:51	27.78	OK	10698	2026-09-17 20:52	28.82	OK
10699	2026-09-17 20:53	27.13	OK	10700	2026-09-17 20:54	27.39	OK
10701	2026-09-17 20:55	27.16	OK	10702	2026-09-17 20:56	28.89	OK
10703	2026-09-17 20:57	29.52	OK	10704	2026-09-17 20:58	29.66	OK
10705	2026-09-17 20:59	28.27	OK	10706	2026-09-17 21:00	29.12	OK
10707	2026-09-17 21:01	28.20	OK	10708	2026-09-17 21:02	29.27	OK
10709	2026-09-17 21:03	28.86	OK	10710	2026-09-17 21:04	29.70	OK
10711	2026-09-17 21:05	28.92	OK	10712	2026-09-17 21:06	29.32	OK
10713	2026-09-17 21:07	28.41	OK	10714	2026-09-17 21:08	28.15	OK
10715	2026-09-17 21:09	27.93	OK	10716	2026-09-17 21:10	29.28	OK
10717	2026-09-17 21:11	28.59	OK	10718	2026-09-17 21:12	27.96	OK
10719	2026-09-17 21:13	29.28	OK	10720	2026-09-17 21:14	28.53	OK
10721	2026-09-17 21:15	29.36	OK	10722	2026-09-17 21:16	29.11	OK
10723	2026-09-17 21:17	29.85	OK	10724	2026-09-17 21:18	28.84	OK
10725	2026-09-17 21:19	28.72	OK	10726	2026-09-17 21:20	29.40	OK
10727	2026-09-17 21:21	29.35	OK	10728	2026-09-17 21:22	28.72	OK
10729	2026-09-17 21:23	29.37	OK	10730	2026-09-17 21:24	28.68	OK
10731	2026-09-17 21:25	29.44	OK	10732	2026-09-17 21:26	30.61	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10733	2026-09-17 21:27	28.97	OK	10734	2026-09-17 21:28	29.71	OK
10735	2026-09-17 21:29	29.67	OK	10736	2026-09-17 21:30	27.79	OK
10737	2026-09-17 21:31	29.25	OK	10738	2026-09-17 21:32	29.36	OK
10739	2026-09-17 21:33	27.97	OK	10740	2026-09-17 21:34	29.09	OK
10741	2026-09-17 21:35	29.89	OK	10742	2026-09-17 21:36	29.17	OK
10743	2026-09-17 21:37	29.18	OK	10744	2026-09-17 21:38	28.82	OK
10745	2026-09-17 21:39	30.21	OK	10746	2026-09-17 21:40	29.37	OK
10747	2026-09-17 21:41	28.62	OK	10748	2026-09-17 21:42	29.04	OK
10749	2026-09-17 21:43	31.37	OK	10750	2026-09-17 21:44	28.90	OK
10751	2026-09-17 21:45	29.86	OK	10752	2026-09-17 21:46	28.28	OK
10753	2026-09-17 21:47	29.33	OK	10754	2026-09-17 21:48	28.76	OK
10755	2026-09-17 21:49	30.39	OK	10756	2026-09-17 21:50	28.59	OK
10757	2026-09-17 21:51	29.93	OK	10758	2026-09-17 21:52	29.70	OK
10759	2026-09-17 21:53	31.01	OK	10760	2026-09-17 21:54	29.85	OK
10761	2026-09-17 21:55	28.90	OK	10762	2026-09-17 21:56	28.50	OK
10763	2026-09-17 21:57	30.07	OK	10764	2026-09-17 21:58	30.36	OK
10765	2026-09-17 21:59	29.81	OK	10766	2026-09-17 22:00	28.87	OK
10767	2026-09-17 22:01	29.80	OK	10768	2026-09-17 22:02	29.79	OK
10769	2026-09-17 22:03	29.78	OK	10770	2026-09-17 22:04	30.91	OK
10771	2026-09-17 22:05	28.79	OK	10772	2026-09-17 22:06	29.68	OK
10773	2026-09-17 22:07	29.58	OK	10774	2026-09-17 22:08	30.73	OK
10775	2026-09-17 22:09	28.20	OK	10776	2026-09-17 22:10	29.26	OK
10777	2026-09-17 22:11	27.79	OK	10778	2026-09-17 22:12	29.35	OK
10779	2026-09-17 22:13	29.40	OK	10780	2026-09-17 22:14	27.43	OK
10781	2026-09-17 22:15	30.12	OK	10782	2026-09-17 22:16	30.77	OK
10783	2026-09-17 22:17	29.34	OK	10784	2026-09-17 22:18	30.92	OK
10785	2026-09-17 22:19	30.59	OK	10786	2026-09-17 22:20	29.44	OK
10787	2026-09-17 22:21	29.63	OK	10788	2026-09-17 22:22	29.74	OK
10789	2026-09-17 22:23	30.24	OK	10790	2026-09-17 22:24	29.59	OK
10791	2026-09-17 22:25	29.74	OK	10792	2026-09-17 22:26	31.21	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10793	2026-09-17 22:27	31.23	OK	10794	2026-09-17 22:28	29.34	OK
10795	2026-09-17 22:29	30.32	OK	10796	2026-09-17 22:30	30.08	OK
10797	2026-09-17 22:31	29.82	OK	10798	2026-09-17 22:32	29.06	OK
10799	2026-09-17 22:33	28.79	OK	10800	2026-09-17 22:34	29.43	OK
10801	2026-09-17 22:35	28.98	OK	10802	2026-09-17 22:36	30.16	OK
10803	2026-09-17 22:37	29.73	OK	10804	2026-09-17 22:38	28.85	OK
10805	2026-09-17 22:39	28.48	OK	10806	2026-09-17 22:40	29.78	OK
10807	2026-09-17 22:41	29.56	OK	10808	2026-09-17 22:42	29.85	OK
10809	2026-09-17 22:43	29.50	OK	10810	2026-09-17 22:44	28.84	OK
10811	2026-09-17 22:45	29.49	OK	10812	2026-09-17 22:46	30.27	OK
10813	2026-09-17 22:47	30.10	OK	10814	2026-09-17 22:48	29.21	OK
10815	2026-09-17 22:49	30.83	OK	10816	2026-09-17 22:50	28.46	OK
10817	2026-09-17 22:51	29.81	OK	10818	2026-09-17 22:52	30.18	OK
10819	2026-09-17 22:53	28.32	OK	10820	2026-09-17 22:54	29.19	OK
10821	2026-09-17 22:55	30.42	OK	10822	2026-09-17 22:56	29.60	OK
10823	2026-09-17 22:57	30.10	OK	10824	2026-09-17 22:58	30.54	OK
10825	2026-09-17 22:59	29.53	OK	10826	2026-09-17 23:00	30.72	OK
10827	2026-09-17 23:01	29.63	OK	10828	2026-09-17 23:02	29.12	OK
10829	2026-09-17 23:03	30.36	OK	10830	2026-09-17 23:04	29.56	OK
10831	2026-09-17 23:05	29.27	OK	10832	2026-09-17 23:06	28.97	OK
10833	2026-09-17 23:07	29.27	OK	10834	2026-09-17 23:08	28.61	OK
10835	2026-09-17 23:09	30.61	OK	10836	2026-09-17 23:10	30.30	OK
10837	2026-09-17 23:11	30.32	OK	10838	2026-09-17 23:12	29.03	OK
10839	2026-09-17 23:13	30.18	OK	10840	2026-09-17 23:14	30.87	OK
10841	2026-09-17 23:15	30.26	OK	10842	2026-09-17 23:16	31.12	OK
10843	2026-09-17 23:17	30.55	OK	10844	2026-09-17 23:18	29.75	OK
10845	2026-09-17 23:19	30.53	OK	10846	2026-09-17 23:20	30.22	OK
10847	2026-09-17 23:21	29.08	OK	10848	2026-09-17 23:22	30.34	OK
10849	2026-09-17 23:23	29.10	OK	10850	2026-09-17 23:24	30.00	OK
10851	2026-09-17 23:25	31.29	OK	10852	2026-09-17 23:26	30.82	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10853	2026-09-17 23:27	29.83	OK	10854	2026-09-17 23:28	30.31	OK
10855	2026-09-17 23:29	30.45	OK	10856	2026-09-17 23:30	30.41	OK
10857	2026-09-17 23:31	28.10	OK	10858	2026-09-17 23:32	30.35	OK
10859	2026-09-17 23:33	29.16	OK	10860	2026-09-17 23:34	30.20	OK
10861	2026-09-17 23:35	30.26	OK	10862	2026-09-17 23:36	29.47	OK
10863	2026-09-17 23:37	30.29	OK	10864	2026-09-17 23:38	30.59	OK
10865	2026-09-17 23:39	31.79	OK	10866	2026-09-17 23:40	28.44	OK
10867	2026-09-17 23:41	30.83	OK	10868	2026-09-17 23:42	30.78	OK
10869	2026-09-17 23:43	31.41	OK	10870	2026-09-17 23:44	31.74	OK
10871	2026-09-17 23:45	30.02	OK	10872	2026-09-17 23:46	31.83	OK
10873	2026-09-17 23:47	28.96	OK	10874	2026-09-17 23:48	29.15	OK
10875	2026-09-17 23:49	30.35	OK	10876	2026-09-17 23:50	29.62	OK
10877	2026-09-17 23:51	29.38	OK	10878	2026-09-17 23:52	29.79	OK
10879	2026-09-17 23:53	29.38	OK	10880	2026-09-17 23:54	30.13	OK
10881	2026-09-17 23:55	29.46	OK	10882	2026-09-17 23:56	30.72	OK
10883	2026-09-17 23:57	28.12	OK	10884	2026-09-17 23:58	32.14	OK
10885	2026-09-17 23:59	30.62	OK	10886	2026-09-18 00:00	29.50	OK
10887	2026-09-18 00:01	30.51	OK	10888	2026-09-18 00:02	29.60	OK
10889	2026-09-18 00:03	29.99	OK	10890	2026-09-18 00:04	29.49	OK
10891	2026-09-18 00:05	28.92	OK	10892	2026-09-18 00:06	30.49	OK
10893	2026-09-18 00:07	30.51	OK	10894	2026-09-18 00:08	30.01	OK
10895	2026-09-18 00:09	28.92	OK	10896	2026-09-18 00:10	30.96	OK
10897	2026-09-18 00:11	30.03	OK	10898	2026-09-18 00:12	30.68	OK
10899	2026-09-18 00:13	29.47	OK	10900	2026-09-18 00:14	29.20	OK
10901	2026-09-18 00:15	30.46	OK	10902	2026-09-18 00:16	30.99	OK
10903	2026-09-18 00:17	31.38	OK	10904	2026-09-18 00:18	29.53	OK
10905	2026-09-18 00:19	31.05	OK	10906	2026-09-18 00:20	30.82	OK
10907	2026-09-18 00:21	28.57	OK	10908	2026-09-18 00:22	29.58	OK
10909	2026-09-18 00:23	31.68	OK	10910	2026-09-18 00:24	29.22	OK
10911	2026-09-18 00:25	30.23	OK	10912	2026-09-18 00:26	29.71	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10913	2026-09-18 00:27	30.91	OK	10914	2026-09-18 00:28	31.15	OK
10915	2026-09-18 00:29	30.73	OK	10916	2026-09-18 00:30	29.92	OK
10917	2026-09-18 00:31	29.95	OK	10918	2026-09-18 00:32	30.33	OK
10919	2026-09-18 00:33	29.32	OK	10920	2026-09-18 00:34	29.66	OK
10921	2026-09-18 00:35	29.67	OK	10922	2026-09-18 00:36	30.01	OK
10923	2026-09-18 00:37	30.22	OK	10924	2026-09-18 00:38	30.50	OK
10925	2026-09-18 00:39	31.74	OK	10926	2026-09-18 00:40	30.51	OK
10927	2026-09-18 00:41	28.75	OK	10928	2026-09-18 00:42	29.45	OK
10929	2026-09-18 00:43	30.58	OK	10930	2026-09-18 00:44	28.67	OK
10931	2026-09-18 00:45	30.93	OK	10932	2026-09-18 00:46	30.58	OK
10933	2026-09-18 00:47	31.50	OK	10934	2026-09-18 00:48	31.04	OK
10935	2026-09-18 00:49	30.71	OK	10936	2026-09-18 00:50	29.17	OK
10937	2026-09-18 00:51	30.10	OK	10938	2026-09-18 00:52	30.27	OK
10939	2026-09-18 00:53	32.00	OK	10940	2026-09-18 00:54	30.57	OK
10941	2026-09-18 00:55	29.54	OK	10942	2026-09-18 00:56	29.83	OK
10943	2026-09-18 00:57	32.06	OK	10944	2026-09-18 00:58	31.36	OK
10945	2026-09-18 00:59	29.24	OK	10946	2026-09-18 01:00	30.38	OK
10947	2026-09-18 01:01	29.75	OK	10948	2026-09-18 01:02	30.02	OK
10949	2026-09-18 01:03	32.04	OK	10950	2026-09-18 01:04	30.79	OK
10951	2026-09-18 01:05	31.12	OK	10952	2026-09-18 01:06	31.39	OK
10953	2026-09-18 01:07	30.25	OK	10954	2026-09-18 01:08	30.23	OK
10955	2026-09-18 01:09	30.96	OK	10956	2026-09-18 01:10	30.35	OK
10957	2026-09-18 01:11	29.65	OK	10958	2026-09-18 01:12	29.91	OK
10959	2026-09-18 01:13	30.75	OK	10960	2026-09-18 01:14	29.29	OK
10961	2026-09-18 01:15	29.25	OK	10962	2026-09-18 01:16	29.40	OK
10963	2026-09-18 01:17	30.16	OK	10964	2026-09-18 01:18	31.28	OK
10965	2026-09-18 01:19	29.70	OK	10966	2026-09-18 01:20	30.21	OK
10967	2026-09-18 01:21	31.35	OK	10968	2026-09-18 01:22	30.24	OK
10969	2026-09-18 01:23	29.34	OK	10970	2026-09-18 01:24	31.07	OK
10971	2026-09-18 01:25	30.00	OK	10972	2026-09-18 01:26	29.01	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
10973	2026-09-18 01:27	31.17	OK	10974	2026-09-18 01:28	31.07	OK
10975	2026-09-18 01:29	30.14	OK	10976	2026-09-18 01:30	29.24	OK
10977	2026-09-18 01:31	30.49	OK	10978	2026-09-18 01:32	31.02	OK
10979	2026-09-18 01:33	31.92	OK	10980	2026-09-18 01:34	29.95	OK
10981	2026-09-18 01:35	30.93	OK	10982	2026-09-18 01:36	30.39	OK
10983	2026-09-18 01:37	30.18	OK	10984	2026-09-18 01:38	30.49	OK
10985	2026-09-18 01:39	31.27	OK	10986	2026-09-18 01:40	32.04	OK
10987	2026-09-18 01:41	31.21	OK	10988	2026-09-18 01:42	31.62	OK
10989	2026-09-18 01:43	29.54	OK	10990	2026-09-18 01:44	30.69	OK
10991	2026-09-18 01:45	30.88	OK	10992	2026-09-18 01:46	29.94	OK
10993	2026-09-18 01:47	29.76	OK	10994	2026-09-18 01:48	31.34	OK
10995	2026-09-18 01:49	30.08	OK	10996	2026-09-18 01:50	30.08	OK
10997	2026-09-18 01:51	31.81	OK	10998	2026-09-18 01:52	30.65	OK
10999	2026-09-18 01:53	29.65	OK	11000	2026-09-18 01:54	29.37	OK
11001	2026-09-18 01:55	29.99	OK	11002	2026-09-18 01:56	30.47	OK
11003	2026-09-18 01:57	31.08	OK	11004	2026-09-18 01:58	30.56	OK
11005	2026-09-18 01:59	30.51	OK	11006	2026-09-18 02:00	29.80	OK
11007	2026-09-18 02:01	30.97	OK	11008	2026-09-18 02:02	30.42	OK
11009	2026-09-18 02:03	29.50	OK	11010	2026-09-18 02:04	30.66	OK
11011	2026-09-18 02:05	30.91	OK	11012	2026-09-18 02:06	30.68	OK
11013	2026-09-18 02:07	30.86	OK	11014	2026-09-18 02:08	29.24	OK
11015	2026-09-18 02:09	31.37	OK	11016	2026-09-18 02:10	30.87	OK
11017	2026-09-18 02:11	30.48	OK	11018	2026-09-18 02:12	29.79	OK
11019	2026-09-18 02:13	30.57	OK	11020	2026-09-18 02:14	31.25	OK
11021	2026-09-18 02:15	30.78	OK	11022	2026-09-18 02:16	29.03	OK
11023	2026-09-18 02:17	30.13	OK	11024	2026-09-18 02:18	29.78	OK
11025	2026-09-18 02:19	30.21	OK	11026	2026-09-18 02:20	31.43	OK
11027	2026-09-18 02:21	29.49	OK	11028	2026-09-18 02:22	30.44	OK
11029	2026-09-18 02:23	29.49	OK	11030	2026-09-18 02:24	31.24	OK
11031	2026-09-18 02:25	28.99	OK	11032	2026-09-18 02:26	31.02	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11033	2026-09-18 02:27	30.38	OK	11034	2026-09-18 02:28	30.74	OK
11035	2026-09-18 02:29	31.42	OK	11036	2026-09-18 02:30	29.69	OK
11037	2026-09-18 02:31	31.11	OK	11038	2026-09-18 02:32	30.53	OK
11039	2026-09-18 02:33	29.63	OK	11040	2026-09-18 02:34	31.43	OK
11041	2026-09-18 02:35	29.58	OK	11042	2026-09-18 02:36	29.75	OK
11043	2026-09-18 02:37	29.94	OK	11044	2026-09-18 02:38	31.42	OK
11045	2026-09-18 02:39	29.51	OK	11046	2026-09-18 02:40	29.52	OK
11047	2026-09-18 02:41	30.92	OK	11048	2026-09-18 02:42	29.91	OK
11049	2026-09-18 02:43	31.21	OK	11050	2026-09-18 02:44	29.76	OK
11051	2026-09-18 02:45	28.73	OK	11052	2026-09-18 02:46	30.48	OK
11053	2026-09-18 02:47	29.28	OK	11054	2026-09-18 02:48	30.76	OK
11055	2026-09-18 02:49	29.16	OK	11056	2026-09-18 02:50	30.03	OK
11057	2026-09-18 02:51	29.35	OK	11058	2026-09-18 02:52	28.38	OK
11059	2026-09-18 02:53	29.02	OK	11060	2026-09-18 02:54	30.30	OK
11061	2026-09-18 02:55	30.85	OK	11062	2026-09-18 02:56	30.20	OK
11063	2026-09-18 02:57	30.11	OK	11064	2026-09-18 02:58	30.82	OK
11065	2026-09-18 02:59	29.78	OK	11066	2026-09-18 03:00	30.16	OK
11067	2026-09-18 03:01	31.03	OK	11068	2026-09-18 03:02	29.60	OK
11069	2026-09-18 03:03	29.78	OK	11070	2026-09-18 03:04	31.31	OK
11071	2026-09-18 03:05	29.27	OK	11072	2026-09-18 03:06	30.76	OK
11073	2026-09-18 03:07	31.12	OK	11074	2026-09-18 03:08	31.14	OK
11075	2026-09-18 03:09	30.63	OK	11076	2026-09-18 03:10	29.00	OK
11077	2026-09-18 03:11	30.04	OK	11078	2026-09-18 03:12	30.42	OK
11079	2026-09-18 03:13	31.27	OK	11080	2026-09-18 03:14	30.90	OK
11081	2026-09-18 03:15	30.56	OK	11082	2026-09-18 03:16	30.70	OK
11083	2026-09-18 03:17	29.30	OK	11084	2026-09-18 03:18	30.53	OK
11085	2026-09-18 03:19	31.04	OK	11086	2026-09-18 03:20	31.20	OK
11087	2026-09-18 03:21	29.03	OK	11088	2026-09-18 03:22	30.07	OK
11089	2026-09-18 03:23	29.26	OK	11090	2026-09-18 03:24	30.41	OK
11091	2026-09-18 03:25	29.90	OK	11092	2026-09-18 03:26	31.05	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11093	2026-09-18 03:27	29.66	OK	11094	2026-09-18 03:28	30.56	OK
11095	2026-09-18 03:29	29.43	OK	11096	2026-09-18 03:30	28.10	OK
11097	2026-09-18 03:31	31.47	OK	11098	2026-09-18 03:32	30.70	OK
11099	2026-09-18 03:33	29.55	OK	11100	2026-09-18 03:34	30.90	OK
11101	2026-09-18 03:35	31.15	OK	11102	2026-09-18 03:36	30.85	OK
11103	2026-09-18 03:37	30.34	OK	11104	2026-09-18 03:38	29.33	OK
11105	2026-09-18 03:39	30.32	OK	11106	2026-09-18 03:40	29.98	OK
11107	2026-09-18 03:41	30.03	OK	11108	2026-09-18 03:42	30.08	OK
11109	2026-09-18 03:43	30.26	OK	11110	2026-09-18 03:44	29.16	OK
11111	2026-09-18 03:45	29.42	OK	11112	2026-09-18 03:46	29.20	OK
11113	2026-09-18 03:47	28.89	OK	11114	2026-09-18 03:48	29.75	OK
11115	2026-09-18 03:49	29.61	OK	11116	2026-09-18 03:50	29.29	OK
11117	2026-09-18 03:51	29.52	OK	11118	2026-09-18 03:52	31.14	OK
11119	2026-09-18 03:53	29.59	OK	11120	2026-09-18 03:54	30.29	OK
11121	2026-09-18 03:55	30.15	OK	11122	2026-09-18 03:56	29.82	OK
11123	2026-09-18 03:57	30.63	OK	11124	2026-09-18 03:58	30.17	OK
11125	2026-09-18 03:59	28.75	OK	11126	2026-09-18 04:00	30.05	OK
11127	2026-09-18 04:01	28.85	OK	11128	2026-09-18 04:02	29.08	OK
11129	2026-09-18 04:03	29.74	OK	11130	2026-09-18 04:04	29.57	OK
11131	2026-09-18 04:05	30.14	OK	11132	2026-09-18 04:06	29.39	OK
11133	2026-09-18 04:07	29.06	OK	11134	2026-09-18 04:08	29.18	OK
11135	2026-09-18 04:09	29.53	OK	11136	2026-09-18 04:10	28.41	OK
11137	2026-09-18 04:11	28.52	OK	11138	2026-09-18 04:12	30.24	OK
11139	2026-09-18 04:13	29.94	OK	11140	2026-09-18 04:14	30.92	OK
11141	2026-09-18 04:15	30.43	OK	11142	2026-09-18 04:16	29.88	OK
11143	2026-09-18 04:17	30.38	OK	11144	2026-09-18 04:18	29.57	OK
11145	2026-09-18 04:19	30.16	OK	11146	2026-09-18 04:20	29.68	OK
11147	2026-09-18 04:21	28.63	OK	11148	2026-09-18 04:22	30.42	OK
11149	2026-09-18 04:23	30.34	OK	11150	2026-09-18 04:24	29.45	OK
11151	2026-09-18 04:25	28.65	OK	11152	2026-09-18 04:26	29.91	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11153	2026-09-18 04:27	30.18	OK	11154	2026-09-18 04:28	29.95	OK
11155	2026-09-18 04:29	28.30	OK	11156	2026-09-18 04:30	29.59	OK
11157	2026-09-18 04:31	29.96	OK	11158	2026-09-18 04:32	29.04	OK
11159	2026-09-18 04:33	28.04	OK	11160	2026-09-18 04:34	29.30	OK
11161	2026-09-18 04:35	30.09	OK	11162	2026-09-18 04:36	28.79	OK
11163	2026-09-18 04:37	29.38	OK	11164	2026-09-18 04:38	29.16	OK
11165	2026-09-18 04:39	29.11	OK	11166	2026-09-18 04:40	30.67	OK
11167	2026-09-18 04:41	30.28	OK	11168	2026-09-18 04:42	30.61	OK
11169	2026-09-18 04:43	29.16	OK	11170	2026-09-18 04:44	30.85	OK
11171	2026-09-18 04:45	28.71	OK	11172	2026-09-18 04:46	27.80	OK
11173	2026-09-18 04:47	30.23	OK	11174	2026-09-18 04:48	29.38	OK
11175	2026-09-18 04:49	28.65	OK	11176	2026-09-18 04:50	29.15	OK
11177	2026-09-18 04:51	30.17	OK	11178	2026-09-18 04:52	28.87	OK
11179	2026-09-18 04:53	29.50	OK	11180	2026-09-18 04:54	30.01	OK
11181	2026-09-18 04:55	29.26	OK	11182	2026-09-18 04:56	29.82	OK
11183	2026-09-18 04:57	28.12	OK	11184	2026-09-18 04:58	29.88	OK
11185	2026-09-18 04:59	28.80	OK	11186	2026-09-18 05:00	29.12	OK
11187	2026-09-18 05:01	30.26	OK	11188	2026-09-18 05:02	30.13	OK
11189	2026-09-18 05:03	30.55	OK	11190	2026-09-18 05:04	28.22	OK
11191	2026-09-18 05:05	29.21	OK	11192	2026-09-18 05:06	29.25	OK
11193	2026-09-18 05:07	30.21	OK	11194	2026-09-18 05:08	29.16	OK
11195	2026-09-18 05:09	29.98	OK	11196	2026-09-18 05:10	29.90	OK
11197	2026-09-18 05:11	29.13	OK	11198	2026-09-18 05:12	30.99	OK
11199	2026-09-18 05:13	29.21	OK	11200	2026-09-18 05:14	28.28	OK
11201	2026-09-18 05:15	28.91	OK	11202	2026-09-18 05:16	29.44	OK
11203	2026-09-18 05:17	28.87	OK	11204	2026-09-18 05:18	29.50	OK
11205	2026-09-18 05:19	29.60	OK	11206	2026-09-18 05:20	28.64	OK
11207	2026-09-18 05:21	27.98	OK	11208	2026-09-18 05:22	30.83	OK
11209	2026-09-18 05:23	28.66	OK	11210	2026-09-18 05:24	28.95	OK
11211	2026-09-18 05:25	30.33	OK	11212	2026-09-18 05:26	28.36	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11213	2026-09-18 05:27	29.47	OK	11214	2026-09-18 05:28	28.63	OK
11215	2026-09-18 05:29	28.38	OK	11216	2026-09-18 05:30	28.93	OK
11217	2026-09-18 05:31	30.39	OK	11218	2026-09-18 05:32	28.65	OK
11219	2026-09-18 05:33	28.44	OK	11220	2026-09-18 05:34	28.97	OK
11221	2026-09-18 05:35	29.81	OK	11222	2026-09-18 05:36	29.62	OK
11223	2026-09-18 05:37	28.90	OK	11224	2026-09-18 05:38	30.38	OK
11225	2026-09-18 05:39	28.03	OK	11226	2026-09-18 05:40	30.31	OK
11227	2026-09-18 05:41	28.10	OK	11228	2026-09-18 05:42	29.27	OK
11229	2026-09-18 05:43	29.49	OK	11230	2026-09-18 05:44	27.46	OK
11231	2026-09-18 05:45	29.47	OK	11232	2026-09-18 05:46	27.64	OK
11233	2026-09-18 05:47	29.96	OK	11234	2026-09-18 05:48	28.29	OK
11235	2026-09-18 05:49	29.05	OK	11236	2026-09-18 05:50	29.64	OK
11237	2026-09-18 05:51	29.61	OK	11238	2026-09-18 05:52	28.59	OK
11239	2026-09-18 05:53	28.29	OK	11240	2026-09-18 05:54	28.75	OK
11241	2026-09-18 05:55	27.20	OK	11242	2026-09-18 05:56	29.02	OK
11243	2026-09-18 05:57	28.75	OK	11244	2026-09-18 05:58	29.54	OK
11245	2026-09-18 05:59	30.11	OK	11246	2026-09-18 06:00	28.57	OK
11247	2026-09-18 06:01	28.83	OK	11248	2026-09-18 06:02	28.82	OK
11249	2026-09-18 06:03	29.71	OK	11250	2026-09-18 06:04	28.09	OK
11251	2026-09-18 06:05	28.21	OK	11252	2026-09-18 06:06	29.23	OK
11253	2026-09-18 06:07	28.92	OK	11254	2026-09-18 06:08	28.95	OK
11255	2026-09-18 06:09	28.28	OK	11256	2026-09-18 06:10	28.63	OK
11257	2026-09-18 06:11	28.07	OK	11258	2026-09-18 06:12	28.50	OK
11259	2026-09-18 06:13	30.67	OK	11260	2026-09-18 06:14	29.11	OK
11261	2026-09-18 06:15	28.95	OK	11262	2026-09-18 06:16	28.54	OK
11263	2026-09-18 06:17	27.32	OK	11264	2026-09-18 06:18	28.39	OK
11265	2026-09-18 06:19	29.07	OK	11266	2026-09-18 06:20	29.76	OK
11267	2026-09-18 06:21	28.15	OK	11268	2026-09-18 06:22	28.52	OK
11269	2026-09-18 06:23	29.18	OK	11270	2026-09-18 06:24	28.37	OK
11271	2026-09-18 06:25	27.36	OK	11272	2026-09-18 06:26	29.84	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11273	2026-09-18 06:27	27.83	OK	11274	2026-09-18 06:28	28.06	OK
11275	2026-09-18 06:29	29.56	OK	11276	2026-09-18 06:30	28.00	OK
11277	2026-09-18 06:31	28.69	OK	11278	2026-09-18 06:32	28.44	OK
11279	2026-09-18 06:33	27.62	OK	11280	2026-09-18 06:34	27.13	OK
11281	2026-09-18 06:35	28.73	OK	11282	2026-09-18 06:36	27.69	OK
11283	2026-09-18 06:37	28.93	OK	11284	2026-09-18 06:38	27.86	OK
11285	2026-09-18 06:39	27.55	OK	11286	2026-09-18 06:40	27.24	OK
11287	2026-09-18 06:41	29.81	OK	11288	2026-09-18 06:42	29.08	OK
11289	2026-09-18 06:43	27.93	OK	11290	2026-09-18 06:44	27.84	OK
11291	2026-09-18 06:45	28.22	OK	11292	2026-09-18 06:46	28.01	OK
11293	2026-09-18 06:47	28.67	OK	11294	2026-09-18 06:48	28.39	OK
11295	2026-09-18 06:49	27.29	OK	11296	2026-09-18 06:50	29.69	OK
11297	2026-09-18 06:51	28.73	OK	11298	2026-09-18 06:52	28.43	OK
11299	2026-09-18 06:53	28.41	OK	11300	2026-09-18 06:54	28.31	OK
11301	2026-09-18 06:55	27.86	OK	11302	2026-09-18 06:56	28.82	OK
11303	2026-09-18 06:57	26.89	OK	11304	2026-09-18 06:58	27.10	OK
11305	2026-09-18 06:59	27.26	OK	11306	2026-09-18 07:00	28.48	OK
11307	2026-09-18 07:01	27.98	OK	11308	2026-09-18 07:02	27.38	OK
11309	2026-09-18 07:03	28.36	OK	11310	2026-09-18 07:04	27.40	OK
11311	2026-09-18 07:05	27.10	OK	11312	2026-09-18 07:06	28.74	OK
11313	2026-09-18 07:07	27.49	OK	11314	2026-09-18 07:08	28.52	OK
11315	2026-09-18 07:09	29.03	OK	11316	2026-09-18 07:10	28.09	OK
11317	2026-09-18 07:11	28.35	OK	11318	2026-09-18 07:12	27.81	OK
11319	2026-09-18 07:13	29.59	OK	11320	2026-09-18 07:14	29.03	OK
11321	2026-09-18 07:15	29.27	OK	11322	2026-09-18 07:16	27.98	OK
11323	2026-09-18 07:17	29.41	OK	11324	2026-09-18 07:18	27.36	OK
11325	2026-09-18 07:19	28.20	OK	11326	2026-09-18 07:20	28.00	OK
11327	2026-09-18 07:21	26.53	OK	11328	2026-09-18 07:22	27.58	OK
11329	2026-09-18 07:23	27.73	OK	11330	2026-09-18 07:24	27.25	OK
11331	2026-09-18 07:25	27.74	OK	11332	2026-09-18 07:26	28.30	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11333	2026-09-18 07:27	27.93	OK	11334	2026-09-18 07:28	27.54	OK
11335	2026-09-18 07:29	29.54	OK	11336	2026-09-18 07:30	27.58	OK
11337	2026-09-18 07:31	26.91	OK	11338	2026-09-18 07:32	26.51	OK
11339	2026-09-18 07:33	27.63	OK	11340	2026-09-18 07:34	27.48	OK
11341	2026-09-18 07:35	28.61	OK	11342	2026-09-18 07:36	28.34	OK
11343	2026-09-18 07:37	27.28	OK	11344	2026-09-18 07:38	28.72	OK
11345	2026-09-18 07:39	28.34	OK	11346	2026-09-18 07:40	27.81	OK
11347	2026-09-18 07:41	29.05	OK	11348	2026-09-18 07:42	27.96	OK
11349	2026-09-18 07:43	28.28	OK	11350	2026-09-18 07:44	27.79	OK
11351	2026-09-18 07:45	26.75	OK	11352	2026-09-18 07:46	27.68	OK
11353	2026-09-18 07:47	28.59	OK	11354	2026-09-18 07:48	28.58	OK
11355	2026-09-18 07:49	28.05	OK	11356	2026-09-18 07:50	27.38	OK
11357	2026-09-18 07:51	29.20	OK	11358	2026-09-18 07:52	28.03	OK
11359	2026-09-18 07:53	26.86	OK	11360	2026-09-18 07:54	28.06	OK
11361	2026-09-18 07:55	28.41	OK	11362	2026-09-18 07:56	28.58	OK
11363	2026-09-18 07:57	27.44	OK	11364	2026-09-18 07:58	27.54	OK
11365	2026-09-18 07:59	28.97	OK	11366	2026-09-18 08:00	26.56	OK
11367	2026-09-18 08:01	27.96	OK	11368	2026-09-18 08:02	26.90	OK
11369	2026-09-18 08:03	28.15	OK	11370	2026-09-18 08:04	26.78	OK
11371	2026-09-18 08:05	27.62	OK	11372	2026-09-18 08:06	28.48	OK
11373	2026-09-18 08:07	28.22	OK	11374	2026-09-18 08:08	28.60	OK
11375	2026-09-18 08:09	27.43	OK	11376	2026-09-18 08:10	27.27	OK
11377	2026-09-18 08:11	27.68	OK	11378	2026-09-18 08:12	28.16	OK
11379	2026-09-18 08:13	26.92	OK	11380	2026-09-18 08:14	27.75	OK
11381	2026-09-18 08:15	26.43	OK	11382	2026-09-18 08:16	27.61	OK
11383	2026-09-18 08:17	27.77	OK	11384	2026-09-18 08:18	27.29	OK
11385	2026-09-18 08:19	27.88	OK	11386	2026-09-18 08:20	27.28	OK
11387	2026-09-18 08:21	25.50	OK	11388	2026-09-18 08:22	26.69	OK
11389	2026-09-18 08:23	28.27	OK	11390	2026-09-18 08:24	27.62	OK
11391	2026-09-18 08:25	27.64	OK	11392	2026-09-18 08:26	27.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11393	2026-09-18 08:27	26.26	OK	11394	2026-09-18 08:28	27.64	OK
11395	2026-09-18 08:29	26.57	OK	11396	2026-09-18 08:30	27.00	OK
11397	2026-09-18 08:31	28.02	OK	11398	2026-09-18 08:32	27.80	OK
11399	2026-09-18 08:33	29.12	OK	11400	2026-09-18 08:34	26.38	OK
11401	2026-09-18 08:35	26.49	OK	11402	2026-09-18 08:36	27.95	OK
11403	2026-09-18 08:37	27.78	OK	11404	2026-09-18 08:38	29.14	OK
11405	2026-09-18 08:39	26.73	OK	11406	2026-09-18 08:40	27.53	OK
11407	2026-09-18 08:41	28.00	OK	11408	2026-09-18 08:42	26.22	OK
11409	2026-09-18 08:43	26.35	OK	11410	2026-09-18 08:44	27.46	OK
11411	2026-09-18 08:45	27.17	OK	11412	2026-09-18 08:46	26.92	OK
11413	2026-09-18 08:47	28.16	OK	11414	2026-09-18 08:48	27.98	OK
11415	2026-09-18 08:49	26.05	OK	11416	2026-09-18 08:50	26.95	OK
11417	2026-09-18 08:51	28.30	OK	11418	2026-09-18 08:52	25.52	OK
11419	2026-09-18 08:53	26.98	OK	11420	2026-09-18 08:54	27.15	OK
11421	2026-09-18 08:55	25.52	OK	11422	2026-09-18 08:56	26.42	OK
11423	2026-09-18 08:57	27.92	OK	11424	2026-09-18 08:58	26.70	OK
11425	2026-09-18 08:59	28.42	OK	11426	2026-09-18 09:00	26.92	OK
11427	2026-09-18 09:01	27.38	OK	11428	2026-09-18 09:02	26.83	OK
11429	2026-09-18 09:03	27.94	OK	11430	2026-09-18 09:04	27.48	OK
11431	2026-09-18 09:05	26.75	OK	11432	2026-09-18 09:06	26.10	OK
11433	2026-09-18 09:07	26.35	OK	11434	2026-09-18 09:08	27.25	OK
11435	2026-09-18 09:09	27.58	OK	11436	2026-09-18 09:10	27.68	OK
11437	2026-09-18 09:11	27.74	OK	11438	2026-09-18 09:12	26.28	OK
11439	2026-09-18 09:13	27.20	OK	11440	2026-09-18 09:14	27.02	OK
11441	2026-09-18 09:15	26.84	OK	11442	2026-09-18 09:16	27.17	OK
11443	2026-09-18 09:17	27.73	OK	11444	2026-09-18 09:18	26.28	OK
11445	2026-09-18 09:19	26.98	OK	11446	2026-09-18 09:20	27.68	OK
11447	2026-09-18 09:21	25.83	OK	11448	2026-09-18 09:22	26.16	OK
11449	2026-09-18 09:23	26.60	OK	11450	2026-09-18 09:24	26.47	OK
11451	2026-09-18 09:25	27.30	OK	11452	2026-09-18 09:26	26.99	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11453	2026-09-18 09:27	27.08	OK	11454	2026-09-18 09:28	27.53	OK
11455	2026-09-18 09:29	26.01	OK	11456	2026-09-18 09:30	27.95	OK
11457	2026-09-18 09:31	27.29	OK	11458	2026-09-18 09:32	27.15	OK
11459	2026-09-18 09:33	26.32	OK	11460	2026-09-18 09:34	27.78	OK
11461	2026-09-18 09:35	27.94	OK	11462	2026-09-18 09:36	26.14	OK
11463	2026-09-18 09:37	26.80	OK	11464	2026-09-18 09:38	26.71	OK
11465	2026-09-18 09:39	25.74	OK	11466	2026-09-18 09:40	26.22	OK
11467	2026-09-18 09:41	26.34	OK	11468	2026-09-18 09:42	27.81	OK
11469	2026-09-18 09:43	26.58	OK	11470	2026-09-18 09:44	26.03	OK
11471	2026-09-18 09:45	26.40	OK	11472	2026-09-18 09:46	28.20	OK
11473	2026-09-18 09:47	26.59	OK	11474	2026-09-18 09:48	26.78	OK
11475	2026-09-18 09:49	26.10	OK	11476	2026-09-18 09:50	26.69	OK
11477	2026-09-18 09:51	26.83	OK	11478	2026-09-18 09:52	27.08	OK
11479	2026-09-18 09:53	26.80	OK	11480	2026-09-18 09:54	27.23	OK
11481	2026-09-18 09:55	26.86	OK	11482	2026-09-18 09:56	25.78	OK
11483	2026-09-18 09:57	26.06	OK	11484	2026-09-18 09:58	26.20	OK
11485	2026-09-18 09:59	27.36	OK	11486	2026-09-18 10:00	26.06	OK
11487	2026-09-18 10:01	27.79	OK	11488	2026-09-18 10:02	26.65	OK
11489	2026-09-18 10:03	26.72	OK	11490	2026-09-18 10:04	27.77	OK
11491	2026-09-18 10:05	27.29	OK	11492	2026-09-18 10:06	27.96	OK
11493	2026-09-18 10:07	26.93	OK	11494	2026-09-18 10:08	26.81	OK
11495	2026-09-18 10:09	27.41	OK	11496	2026-09-18 10:10	26.39	OK
11497	2026-09-18 10:11	26.32	OK	11498	2026-09-18 10:12	25.58	OK
11499	2026-09-18 10:13	25.96	OK	11500	2026-09-18 10:14	27.07	OK
11501	2026-09-18 10:15	26.77	OK	11502	2026-09-18 10:16	25.43	OK
11503	2026-09-18 10:17	25.94	OK	11504	2026-09-18 10:18	27.09	OK
11505	2026-09-18 10:19	27.38	OK	11506	2026-09-18 10:20	27.74	OK
11507	2026-09-18 10:21	27.02	OK	11508	2026-09-18 10:22	28.60	OK
11509	2026-09-18 10:23	25.49	OK	11510	2026-09-18 10:24	26.59	OK
11511	2026-09-18 10:25	26.39	OK	11512	2026-09-18 10:26	25.93	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11513	2026-09-18 10:27	25.74	OK	11514	2026-09-18 10:28	26.19	OK
11515	2026-09-18 10:29	25.36	OK	11516	2026-09-18 10:30	27.27	OK
11517	2026-09-18 10:31	25.97	OK	11518	2026-09-18 10:32	25.17	OK
11519	2026-09-18 10:33	26.18	OK	11520	2026-09-18 10:34	25.70	OK
11521	2026-09-18 10:35	26.53	OK	11522	2026-09-18 10:36	25.61	OK
11523	2026-09-18 10:37	27.45	OK	11524	2026-09-18 10:38	24.59	OK
11525	2026-09-18 10:39	25.50	OK	11526	2026-09-18 10:40	25.72	OK
11527	2026-09-18 10:41	25.76	OK	11528	2026-09-18 10:42	26.99	OK
11529	2026-09-18 10:43	25.91	OK	11530	2026-09-18 10:44	26.53	OK
11531	2026-09-18 10:45	26.32	OK	11532	2026-09-18 10:46	26.08	OK
11533	2026-09-18 10:47	25.68	OK	11534	2026-09-18 10:48	26.38	OK
11535	2026-09-18 10:49	26.54	OK	11536	2026-09-18 10:50	26.44	OK
11537	2026-09-18 10:51	26.70	OK	11538	2026-09-18 10:52	26.96	OK
11539	2026-09-18 10:53	26.03	OK	11540	2026-09-18 10:54	26.04	OK
11541	2026-09-18 10:55	26.67	OK	11542	2026-09-18 10:56	25.67	OK
11543	2026-09-18 10:57	26.54	OK	11544	2026-09-18 10:58	27.09	OK
11545	2026-09-18 10:59	26.48	OK	11546	2026-09-18 11:00	25.50	OK
11547	2026-09-18 11:01	26.65	OK	11548	2026-09-18 11:02	25.13	OK
11549	2026-09-18 11:03	26.36	OK	11550	2026-09-18 11:04	25.32	OK
11551	2026-09-18 11:05	26.59	OK	11552	2026-09-18 11:06	26.80	OK
11553	2026-09-18 11:07	24.83	OK	11554	2026-09-18 11:08	25.90	OK
11555	2026-09-18 11:09	26.05	OK	11556	2026-09-18 11:10	25.71	OK
11557	2026-09-18 11:11	24.97	OK	11558	2026-09-18 11:12	27.05	OK
11559	2026-09-18 11:13	25.86	OK	11560	2026-09-18 11:14	24.99	OK
11561	2026-09-18 11:15	26.81	OK	11562	2026-09-18 11:16	24.97	OK
11563	2026-09-18 11:17	26.61	OK	11564	2026-09-18 11:18	27.18	OK
11565	2026-09-18 11:19	25.61	OK	11566	2026-09-18 11:20	25.53	OK
11567	2026-09-18 11:21	24.57	OK	11568	2026-09-18 11:22	26.03	OK
11569	2026-09-18 11:23	25.61	OK	11570	2026-09-18 11:24	24.99	OK
11571	2026-09-18 11:25	26.53	OK	11572	2026-09-18 11:26	26.41	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11573	2026-09-18 11:27	25.54	OK	11574	2026-09-18 11:28	26.36	OK
11575	2026-09-18 11:29	25.91	OK	11576	2026-09-18 11:30	25.21	OK
11577	2026-09-18 11:31	25.18	OK	11578	2026-09-18 11:32	26.34	OK
11579	2026-09-18 11:33	24.63	OK	11580	2026-09-18 11:34	27.53	OK
11581	2026-09-18 11:35	25.23	OK	11582	2026-09-18 11:36	25.82	OK
11583	2026-09-18 11:37	25.68	OK	11584	2026-09-18 11:38	25.51	OK
11585	2026-09-18 11:39	27.33	OK	11586	2026-09-18 11:40	24.89	OK
11587	2026-09-18 11:41	26.71	OK	11588	2026-09-18 11:42	26.21	OK
11589	2026-09-18 11:43	24.42	OK	11590	2026-09-18 11:44	26.43	OK
11591	2026-09-18 11:45	26.42	OK	11592	2026-09-18 11:46	26.89	OK
11593	2026-09-18 11:47	23.99	OK	11594	2026-09-18 11:48	25.06	OK
11595	2026-09-18 11:49	24.86	OK	11596	2026-09-18 11:50	25.53	OK
11597	2026-09-18 11:51	26.97	OK	11598	2026-09-18 11:52	25.87	OK
11599	2026-09-18 11:53	25.24	OK	11600	2026-09-18 11:54	25.10	OK
11601	2026-09-18 11:55	25.96	OK	11602	2026-09-18 11:56	25.23	OK
11603	2026-09-18 11:57	26.61	OK	11604	2026-09-18 11:58	26.19	OK
11605	2026-09-18 11:59	26.66	OK	11606	2026-09-18 12:00	25.28	OK
11607	2026-09-18 12:01	25.76	OK	11608	2026-09-18 12:02	25.83	OK
11609	2026-09-18 12:03	26.20	OK	11610	2026-09-18 12:04	26.30	OK
11611	2026-09-18 12:05	24.66	OK	11612	2026-09-18 12:06	26.24	OK
11613	2026-09-18 12:07	24.74	OK	11614	2026-09-18 12:08	26.10	OK
11615	2026-09-18 12:09	26.70	OK	11616	2026-09-18 12:10	24.57	OK
11617	2026-09-18 12:11	26.14	OK	11618	2026-09-18 12:12	25.91	OK
11619	2026-09-18 12:13	24.09	OK	11620	2026-09-18 12:14	25.41	OK
11621	2026-09-18 12:15	26.26	OK	11622	2026-09-18 12:16	24.03	OK
11623	2026-09-18 12:17	26.20	OK	11624	2026-09-18 12:18	25.39	OK
11625	2026-09-18 12:19	25.87	OK	11626	2026-09-18 12:20	25.55	OK
11627	2026-09-18 12:21	26.91	OK	11628	2026-09-18 12:22	26.55	OK
11629	2026-09-18 12:23	25.52	OK	11630	2026-09-18 12:24	26.09	OK
11631	2026-09-18 12:25	25.14	OK	11632	2026-09-18 12:26	26.46	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11633	2026-09-18 12:27	26.53	OK	11634	2026-09-18 12:28	25.20	OK
11635	2026-09-18 12:29	25.18	OK	11636	2026-09-18 12:30	25.43	OK
11637	2026-09-18 12:31	26.74	OK	11638	2026-09-18 12:32	25.85	OK
11639	2026-09-18 12:33	26.21	OK	11640	2026-09-18 12:34	25.37	OK
11641	2026-09-18 12:35	25.98	OK	11642	2026-09-18 12:36	25.18	OK
11643	2026-09-18 12:37	25.69	OK	11644	2026-09-18 12:38	25.97	OK
11645	2026-09-18 12:39	23.85	OK	11646	2026-09-18 12:40	26.00	OK
11647	2026-09-18 12:41	26.60	OK	11648	2026-09-18 12:42	25.40	OK
11649	2026-09-18 12:43	24.32	OK	11650	2026-09-18 12:44	25.61	OK
11651	2026-09-18 12:45	26.58	OK	11652	2026-09-18 12:46	27.40	OK
11653	2026-09-18 12:47	26.74	OK	11654	2026-09-18 12:48	26.86	OK
11655	2026-09-18 12:49	25.46	OK	11656	2026-09-18 12:50	26.28	OK
11657	2026-09-18 12:51	24.91	OK	11658	2026-09-18 12:52	26.01	OK
11659	2026-09-18 12:53	26.07	OK	11660	2026-09-18 12:54	26.38	OK
11661	2026-09-18 12:55	25.76	OK	11662	2026-09-18 12:56	25.65	OK
11663	2026-09-18 12:57	25.45	OK	11664	2026-09-18 12:58	27.15	OK
11665	2026-09-18 12:59	27.19	OK	11666	2026-09-18 13:00	24.96	OK
11667	2026-09-18 13:01	24.00	OK	11668	2026-09-18 13:02	26.09	OK
11669	2026-09-18 13:03	25.86	OK	11670	2026-09-18 13:04	25.82	OK
11671	2026-09-18 13:05	26.49	OK	11672	2026-09-18 13:06	27.08	OK
11673	2026-09-18 13:07	25.27	OK	11674	2026-09-18 13:08	25.10	OK
11675	2026-09-18 13:09	24.88	OK	11676	2026-09-18 13:10	26.91	OK
11677	2026-09-18 13:11	26.19	OK	11678	2026-09-18 13:12	25.47	OK
11679	2026-09-18 13:13	25.33	OK	11680	2026-09-18 13:14	25.05	OK
11681	2026-09-18 13:15	26.95	OK	11682	2026-09-18 13:16	26.06	OK
11683	2026-09-18 13:17	24.83	OK	11684	2026-09-18 13:18	24.96	OK
11685	2026-09-18 13:19	24.35	OK	11686	2026-09-18 13:20	25.27	OK
11687	2026-09-18 13:21	25.76	OK	11688	2026-09-18 13:22	26.16	OK
11689	2026-09-18 13:23	25.19	OK	11690	2026-09-18 13:24	26.31	OK
11691	2026-09-18 13:25	25.60	OK	11692	2026-09-18 13:26	25.67	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11693	2026-09-18 13:27	25.69	OK	11694	2026-09-18 13:28	27.20	OK
11695	2026-09-18 13:29	24.83	OK	11696	2026-09-18 13:30	26.02	OK
11697	2026-09-18 13:31	26.14	OK	11698	2026-09-18 13:32	25.43	OK
11699	2026-09-18 13:33	25.48	OK	11700	2026-09-18 13:34	26.04	OK
11701	2026-09-18 13:35	26.35	OK	11702	2026-09-18 13:36	25.29	OK
11703	2026-09-18 13:37	25.23	OK	11704	2026-09-18 13:38	25.23	OK
11705	2026-09-18 13:39	24.28	OK	11706	2026-09-18 13:40	26.74	OK
11707	2026-09-18 13:41	25.71	OK	11708	2026-09-18 13:42	26.72	OK
11709	2026-09-18 13:43	25.35	OK	11710	2026-09-18 13:44	25.28	OK
11711	2026-09-18 13:45	25.37	OK	11712	2026-09-18 13:46	25.72	OK
11713	2026-09-18 13:47	24.80	OK	11714	2026-09-18 13:48	26.37	OK
11715	2026-09-18 13:49	27.25	OK	11716	2026-09-18 13:50	25.60	OK
11717	2026-09-18 13:51	25.15	OK	11718	2026-09-18 13:52	25.66	OK
11719	2026-09-18 13:53	26.38	OK	11720	2026-09-18 13:54	25.66	OK
11721	2026-09-18 13:55	24.05	OK	11722	2026-09-18 13:56	24.97	OK
11723	2026-09-18 13:57	26.67	OK	11724	2026-09-18 13:58	24.40	OK
11725	2026-09-18 13:59	25.64	OK	11726	2026-09-18 14:00	25.78	OK
11727	2026-09-18 14:01	25.17	OK	11728	2026-09-18 14:02	27.06	OK
11729	2026-09-18 14:03	25.28	OK	11730	2026-09-18 14:04	26.54	OK
11731	2026-09-18 14:05	25.62	OK	11732	2026-09-18 14:06	25.71	OK
11733	2026-09-18 14:07	26.40	OK	11734	2026-09-18 14:08	25.57	OK
11735	2026-09-18 14:09	27.15	OK	11736	2026-09-18 14:10	25.10	OK
11737	2026-09-18 14:11	25.78	OK	11738	2026-09-18 14:12	27.19	OK
11739	2026-09-18 14:13	27.40	OK	11740	2026-09-18 14:14	25.21	OK
11741	2026-09-18 14:15	24.91	OK	11742	2026-09-18 14:16	25.24	OK
11743	2026-09-18 14:17	26.56	OK	11744	2026-09-18 14:18	26.41	OK
11745	2026-09-18 14:19	24.61	OK	11746	2026-09-18 14:20	25.26	OK
11747	2026-09-18 14:21	25.67	OK	11748	2026-09-18 14:22	27.69	OK
11749	2026-09-18 14:23	25.65	OK	11750	2026-09-18 14:24	26.88	OK
11751	2026-09-18 14:25	25.53	OK	11752	2026-09-18 14:26	25.65	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11753	2026-09-18 14:27	24.38	OK	11754	2026-09-18 14:28	25.24	OK
11755	2026-09-18 14:29	23.94	OK	11756	2026-09-18 14:30	25.01	OK
11757	2026-09-18 14:31	26.34	OK	11758	2026-09-18 14:32	25.80	OK
11759	2026-09-18 14:33	25.08	OK	11760	2026-09-18 14:34	25.85	OK
11761	2026-09-18 14:35	26.38	OK	11762	2026-09-18 14:36	25.59	OK
11763	2026-09-18 14:37	24.71	OK	11764	2026-09-18 14:38	24.63	OK
11765	2026-09-18 14:39	25.77	OK	11766	2026-09-18 14:40	26.32	OK
11767	2026-09-18 14:41	25.51	OK	11768	2026-09-18 14:42	25.59	OK
11769	2026-09-18 14:43	24.33	OK	11770	2026-09-18 14:44	26.61	OK
11771	2026-09-18 14:45	26.67	OK	11772	2026-09-18 14:46	25.27	OK
11773	2026-09-18 14:47	26.55	OK	11774	2026-09-18 14:48	25.79	OK
11775	2026-09-18 14:49	26.43	OK	11776	2026-09-18 14:50	26.40	OK
11777	2026-09-18 14:51	24.66	OK	11778	2026-09-18 14:52	24.79	OK
11779	2026-09-18 14:53	26.55	OK	11780	2026-09-18 14:54	26.03	OK
11781	2026-09-18 14:55	27.13	OK	11782	2026-09-18 14:56	26.88	OK
11783	2026-09-18 14:57	27.32	OK	11784	2026-09-18 14:58	25.76	OK
11785	2026-09-18 14:59	25.70	OK	11786	2026-09-18 15:00	24.77	OK
11787	2026-09-18 15:01	25.40	OK	11788	2026-09-18 15:02	26.07	OK
11789	2026-09-18 15:03	25.59	OK	11790	2026-09-18 15:04	26.37	OK
11791	2026-09-18 15:05	25.51	OK	11792	2026-09-18 15:06	26.58	OK
11793	2026-09-18 15:07	25.58	OK	11794	2026-09-18 15:08	27.59	OK
11795	2026-09-18 15:09	27.69	OK	11796	2026-09-18 15:10	25.54	OK
11797	2026-09-18 15:11	26.74	OK	11798	2026-09-18 15:12	27.01	OK
11799	2026-09-18 15:13	25.77	OK	11800	2026-09-18 15:14	25.37	OK
11801	2026-09-18 15:15	27.19	OK	11802	2026-09-18 15:16	26.50	OK
11803	2026-09-18 15:17	25.36	OK	11804	2026-09-18 15:18	25.47	OK
11805	2026-09-18 15:19	25.75	OK	11806	2026-09-18 15:20	25.65	OK
11807	2026-09-18 15:21	26.02	OK	11808	2026-09-18 15:22	27.05	OK
11809	2026-09-18 15:23	26.18	OK	11810	2026-09-18 15:24	26.81	OK
11811	2026-09-18 15:25	26.16	OK	11812	2026-09-18 15:26	27.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11813	2026-09-18 15:27	25.60	OK	11814	2026-09-18 15:28	24.77	OK
11815	2026-09-18 15:29	24.49	OK	11816	2026-09-18 15:30	26.28	OK
11817	2026-09-18 15:31	26.03	OK	11818	2026-09-18 15:32	24.92	OK
11819	2026-09-18 15:33	26.57	OK	11820	2026-09-18 15:34	25.93	OK
11821	2026-09-18 15:35	25.87	OK	11822	2026-09-18 15:36	26.94	OK
11823	2026-09-18 15:37	27.18	OK	11824	2026-09-18 15:38	26.96	OK
11825	2026-09-18 15:39	27.14	OK	11826	2026-09-18 15:40	26.60	OK
11827	2026-09-18 15:41	25.66	OK	11828	2026-09-18 15:42	27.11	OK
11829	2026-09-18 15:43	27.53	OK	11830	2026-09-18 15:44	25.50	OK
11831	2026-09-18 15:45	25.68	OK	11832	2026-09-18 15:46	25.87	OK
11833	2026-09-18 15:47	26.40	OK	11834	2026-09-18 15:48	25.43	OK
11835	2026-09-18 15:49	25.12	OK	11836	2026-09-18 15:50	25.72	OK
11837	2026-09-18 15:51	25.96	OK	11838	2026-09-18 15:52	26.65	OK
11839	2026-09-18 15:53	25.86	OK	11840	2026-09-18 15:54	25.42	OK
11841	2026-09-18 15:55	26.21	OK	11842	2026-09-18 15:56	27.22	OK
11843	2026-09-18 15:57	26.32	OK	11844	2026-09-18 15:58	25.73	OK
11845	2026-09-18 15:59	26.06	OK	11846	2026-09-18 16:00	25.01	OK
11847	2026-09-18 16:01	26.10	OK	11848	2026-09-18 16:02	26.28	OK
11849	2026-09-18 16:03	26.36	OK	11850	2026-09-18 16:04	25.32	OK
11851	2026-09-18 16:05	25.60	OK	11852	2026-09-18 16:06	26.40	OK
11853	2026-09-18 16:07	26.16	OK	11854	2026-09-18 16:08	27.13	OK
11855	2026-09-18 16:09	26.15	OK	11856	2026-09-18 16:10	26.63	OK
11857	2026-09-18 16:11	26.66	OK	11858	2026-09-18 16:12	25.68	OK
11859	2026-09-18 16:13	27.25	OK	11860	2026-09-18 16:14	26.32	OK
11861	2026-09-18 16:15	26.85	OK	11862	2026-09-18 16:16	26.56	OK
11863	2026-09-18 16:17	25.39	OK	11864	2026-09-18 16:18	26.09	OK
11865	2026-09-18 16:19	26.59	OK	11866	2026-09-18 16:20	26.38	OK
11867	2026-09-18 16:21	27.07	OK	11868	2026-09-18 16:22	26.18	OK
11869	2026-09-18 16:23	26.24	OK	11870	2026-09-18 16:24	25.25	OK
11871	2026-09-18 16:25	25.64	OK	11872	2026-09-18 16:26	25.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11873	2026-09-18 16:27	26.23	OK	11874	2026-09-18 16:28	27.16	OK
11875	2026-09-18 16:29	27.72	OK	11876	2026-09-18 16:30	26.82	OK
11877	2026-09-18 16:31	26.27	OK	11878	2026-09-18 16:32	26.24	OK
11879	2026-09-18 16:33	27.19	OK	11880	2026-09-18 16:34	25.24	OK
11881	2026-09-18 16:35	26.80	OK	11882	2026-09-18 16:36	24.88	OK
11883	2026-09-18 16:37	27.63	OK	11884	2026-09-18 16:38	27.03	OK
11885	2026-09-18 16:39	26.62	OK	11886	2026-09-18 16:40	26.08	OK
11887	2026-09-18 16:41	25.77	OK	11888	2026-09-18 16:42	25.21	OK
11889	2026-09-18 16:43	25.75	OK	11890	2026-09-18 16:44	27.34	OK
11891	2026-09-18 16:45	25.79	OK	11892	2026-09-18 16:46	26.96	OK
11893	2026-09-18 16:47	25.48	OK	11894	2026-09-18 16:48	25.81	OK
11895	2026-09-18 16:49	26.56	OK	11896	2026-09-18 16:50	27.63	OK
11897	2026-09-18 16:51	25.78	OK	11898	2026-09-18 16:52	26.63	OK
11899	2026-09-18 16:53	25.18	OK	11900	2026-09-18 16:54	26.61	OK
11901	2026-09-18 16:55	25.97	OK	11902	2026-09-18 16:56	27.08	OK
11903	2026-09-18 16:57	27.61	OK	11904	2026-09-18 16:58	26.63	OK
11905	2026-09-18 16:59	26.43	OK	11906	2026-09-18 17:00	26.52	OK
11907	2026-09-18 17:01	26.09	OK	11908	2026-09-18 17:02	27.34	OK
11909	2026-09-18 17:03	25.95	OK	11910	2026-09-18 17:04	26.39	OK
11911	2026-09-18 17:05	27.36	OK	11912	2026-09-18 17:06	25.25	OK
11913	2026-09-18 17:07	26.70	OK	11914	2026-09-18 17:08	27.49	OK
11915	2026-09-18 17:09	26.68	OK	11916	2026-09-18 17:10	25.85	OK
11917	2026-09-18 17:11	26.52	OK	11918	2026-09-18 17:12	26.18	OK
11919	2026-09-18 17:13	25.84	OK	11920	2026-09-18 17:14	27.85	OK
11921	2026-09-18 17:15	28.07	OK	11922	2026-09-18 17:16	25.37	OK
11923	2026-09-18 17:17	25.83	OK	11924	2026-09-18 17:18	27.65	OK
11925	2026-09-18 17:19	25.70	OK	11926	2026-09-18 17:20	25.52	OK
11927	2026-09-18 17:21	27.50	OK	11928	2026-09-18 17:22	25.20	OK
11929	2026-09-18 17:23	25.66	OK	11930	2026-09-18 17:24	27.98	OK
11931	2026-09-18 17:25	26.86	OK	11932	2026-09-18 17:26	27.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11933	2026-09-18 17:27	26.65	OK	11934	2026-09-18 17:28	26.66	OK
11935	2026-09-18 17:29	27.82	OK	11936	2026-09-18 17:30	27.20	OK
11937	2026-09-18 17:31	26.76	OK	11938	2026-09-18 17:32	26.18	OK
11939	2026-09-18 17:33	25.64	OK	11940	2026-09-18 17:34	26.08	OK
11941	2026-09-18 17:35	27.33	OK	11942	2026-09-18 17:36	26.79	OK
11943	2026-09-18 17:37	26.92	OK	11944	2026-09-18 17:38	26.83	OK
11945	2026-09-18 17:39	27.50	OK	11946	2026-09-18 17:40	26.83	OK
11947	2026-09-18 17:41	25.42	OK	11948	2026-09-18 17:42	25.97	OK
11949	2026-09-18 17:43	28.12	OK	11950	2026-09-18 17:44	27.48	OK
11951	2026-09-18 17:45	26.93	OK	11952	2026-09-18 17:46	27.30	OK
11953	2026-09-18 17:47	26.48	OK	11954	2026-09-18 17:48	27.32	OK
11955	2026-09-18 17:49	26.06	OK	11956	2026-09-18 17:50	25.57	OK
11957	2026-09-18 17:51	26.54	OK	11958	2026-09-18 17:52	26.72	OK
11959	2026-09-18 17:53	27.64	OK	11960	2026-09-18 17:54	26.72	OK
11961	2026-09-18 17:55	28.13	OK	11962	2026-09-18 17:56	25.38	OK
11963	2026-09-18 17:57	27.74	OK	11964	2026-09-18 17:58	26.96	OK
11965	2026-09-18 17:59	27.19	OK	11966	2026-09-18 18:00	26.47	OK
11967	2026-09-18 18:01	27.11	OK	11968	2026-09-18 18:02	28.04	OK
11969	2026-09-18 18:03	28.77	OK	11970	2026-09-18 18:04	26.63	OK
11971	2026-09-18 18:05	27.92	OK	11972	2026-09-18 18:06	26.68	OK
11973	2026-09-18 18:07	26.00	OK	11974	2026-09-18 18:08	28.03	OK
11975	2026-09-18 18:09	26.30	OK	11976	2026-09-18 18:10	27.61	OK
11977	2026-09-18 18:11	25.87	OK	11978	2026-09-18 18:12	26.55	OK
11979	2026-09-18 18:13	26.78	OK	11980	2026-09-18 18:14	26.98	OK
11981	2026-09-18 18:15	26.24	OK	11982	2026-09-18 18:16	26.55	OK
11983	2026-09-18 18:17	27.75	OK	11984	2026-09-18 18:18	28.12	OK
11985	2026-09-18 18:19	26.66	OK	11986	2026-09-18 18:20	27.78	OK
11987	2026-09-18 18:21	26.54	OK	11988	2026-09-18 18:22	28.74	OK
11989	2026-09-18 18:23	25.82	OK	11990	2026-09-18 18:24	26.64	OK
11991	2026-09-18 18:25	27.48	OK	11992	2026-09-18 18:26	26.86	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
11993	2026-09-18 18:27	28.25	OK	11994	2026-09-18 18:28	27.29	OK
11995	2026-09-18 18:29	27.24	OK	11996	2026-09-18 18:30	25.86	OK
11997	2026-09-18 18:31	27.54	OK	11998	2026-09-18 18:32	27.25	OK
11999	2026-09-18 18:33	26.26	OK	12000	2026-09-18 18:34	26.19	OK
12001	2026-09-18 18:35	26.76	OK	12002	2026-09-18 18:36	27.43	OK
12003	2026-09-18 18:37	28.45	OK	12004	2026-09-18 18:38	26.37	OK
12005	2026-09-18 18:39	26.89	OK	12006	2026-09-18 18:40	27.12	OK
12007	2026-09-18 18:41	28.79	OK	12008	2026-09-18 18:42	27.42	OK
12009	2026-09-18 18:43	28.60	OK	12010	2026-09-18 18:44	25.95	OK
12011	2026-09-18 18:45	27.63	OK	12012	2026-09-18 18:46	26.35	OK
12013	2026-09-18 18:47	27.77	OK	12014	2026-09-18 18:48	27.71	OK
12015	2026-09-18 18:49	26.48	OK	12016	2026-09-18 18:50	27.11	OK
12017	2026-09-18 18:51	26.93	OK	12018	2026-09-18 18:52	28.97	OK
12019	2026-09-18 18:53	28.07	OK	12020	2026-09-18 18:54	27.89	OK
12021	2026-09-18 18:55	26.78	OK	12022	2026-09-18 18:56	28.50	OK
12023	2026-09-18 18:57	27.09	OK	12024	2026-09-18 18:58	26.61	OK
12025	2026-09-18 18:59	27.64	OK	12026	2026-09-18 19:00	27.24	OK
12027	2026-09-18 19:01	27.72	OK	12028	2026-09-18 19:02	29.08	OK
12029	2026-09-18 19:03	28.67	OK	12030	2026-09-18 19:04	28.72	OK
12031	2026-09-18 19:05	27.53	OK	12032	2026-09-18 19:06	26.57	OK
12033	2026-09-18 19:07	26.60	OK	12034	2026-09-18 19:08	26.11	OK
12035	2026-09-18 19:09	29.66	OK	12036	2026-09-18 19:10	28.55	OK
12037	2026-09-18 19:11	28.52	OK	12038	2026-09-18 19:12	26.66	OK
12039	2026-09-18 19:13	27.30	OK	12040	2026-09-18 19:14	27.78	OK
12041	2026-09-18 19:15	28.23	OK	12042	2026-09-18 19:16	27.54	OK
12043	2026-09-18 19:17	27.32	OK	12044	2026-09-18 19:18	28.33	OK
12045	2026-09-18 19:19	28.71	OK	12046	2026-09-18 19:20	29.44	OK
12047	2026-09-18 19:21	28.58	OK	12048	2026-09-18 19:22	27.47	OK
12049	2026-09-18 19:23	27.51	OK	12050	2026-09-18 19:24	27.64	OK
12051	2026-09-18 19:25	28.49	OK	12052	2026-09-18 19:26	28.14	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12053	2026-09-18 19:27	29.66	OK	12054	2026-09-18 19:28	28.16	OK
12055	2026-09-18 19:29	28.76	OK	12056	2026-09-18 19:30	27.67	OK
12057	2026-09-18 19:31	26.66	OK	12058	2026-09-18 19:32	28.29	OK
12059	2026-09-18 19:33	28.71	OK	12060	2026-09-18 19:34	28.25	OK
12061	2026-09-18 19:35	28.90	OK	12062	2026-09-18 19:36	27.86	OK
12063	2026-09-18 19:37	27.72	OK	12064	2026-09-18 19:38	26.86	OK
12065	2026-09-18 19:39	27.07	OK	12066	2026-09-18 19:40	28.63	OK
12067	2026-09-18 19:41	27.52	OK	12068	2026-09-18 19:42	28.80	OK
12069	2026-09-18 19:43	27.98	OK	12070	2026-09-18 19:44	27.72	OK
12071	2026-09-18 19:45	29.48	OK	12072	2026-09-18 19:46	27.81	OK
12073	2026-09-18 19:47	28.16	OK	12074	2026-09-18 19:48	27.69	OK
12075	2026-09-18 19:49	29.86	OK	12076	2026-09-18 19:50	27.94	OK
12077	2026-09-18 19:51	27.84	OK	12078	2026-09-18 19:52	28.22	OK
12079	2026-09-18 19:53	28.65	OK	12080	2026-09-18 19:54	26.94	OK
12081	2026-09-18 19:55	28.58	OK	12082	2026-09-18 19:56	28.16	OK
12083	2026-09-18 19:57	28.18	OK	12084	2026-09-18 19:58	28.39	OK
12085	2026-09-18 19:59	28.50	OK	12086	2026-09-18 20:00	29.00	OK
12087	2026-09-18 20:01	28.94	OK	12088	2026-09-18 20:02	28.33	OK
12089	2026-09-18 20:03	28.04	OK	12090	2026-09-18 20:04	28.21	OK
12091	2026-09-18 20:05	27.65	OK	12092	2026-09-18 20:06	28.46	OK
12093	2026-09-18 20:07	28.99	OK	12094	2026-09-18 20:08	30.00	OK
12095	2026-09-18 20:09	29.75	OK	12096	2026-09-18 20:10	27.65	OK
12097	2026-09-18 20:11	29.06	OK	12098	2026-09-18 20:12	28.28	OK
12099	2026-09-18 20:13	28.98	OK	12100	2026-09-18 20:14	29.40	OK
12101	2026-09-18 20:15	28.09	OK	12102	2026-09-18 20:16	28.81	OK
12103	2026-09-18 20:17	28.31	OK	12104	2026-09-18 20:18	29.31	OK
12105	2026-09-18 20:19	28.65	OK	12106	2026-09-18 20:20	28.13	OK
12107	2026-09-18 20:21	27.58	OK	12108	2026-09-18 20:22	28.92	OK
12109	2026-09-18 20:23	28.00	OK	12110	2026-09-18 20:24	27.80	OK
12111	2026-09-18 20:25	28.53	OK	12112	2026-09-18 20:26	29.93	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12113	2026-09-18 20:27	29.90	OK	12114	2026-09-18 20:28	29.34	OK
12115	2026-09-18 20:29	29.03	OK	12116	2026-09-18 20:30	28.52	OK
12117	2026-09-18 20:31	30.87	OK	12118	2026-09-18 20:32	27.95	OK
12119	2026-09-18 20:33	27.87	OK	12120	2026-09-18 20:34	27.95	OK
12121	2026-09-18 20:35	27.77	OK	12122	2026-09-18 20:36	28.38	OK
12123	2026-09-18 20:37	28.88	OK	12124	2026-09-18 20:38	28.20	OK
12125	2026-09-18 20:39	28.88	OK	12126	2026-09-18 20:40	28.45	OK
12127	2026-09-18 20:41	27.75	OK	12128	2026-09-18 20:42	27.40	OK
12129	2026-09-18 20:43	29.26	OK	12130	2026-09-18 20:44	28.77	OK
12131	2026-09-18 20:45	28.63	OK	12132	2026-09-18 20:46	29.31	OK
12133	2026-09-18 20:47	30.55	OK	12134	2026-09-18 20:48	29.72	OK
12135	2026-09-18 20:49	29.85	OK	12136	2026-09-18 20:50	28.24	OK
12137	2026-09-18 20:51	27.72	OK	12138	2026-09-18 20:52	28.99	OK
12139	2026-09-18 20:53	29.03	OK	12140	2026-09-18 20:54	28.72	OK
12141	2026-09-18 20:55	28.21	OK	12142	2026-09-18 20:56	29.20	OK
12143	2026-09-18 20:57	29.56	OK	12144	2026-09-18 20:58	27.76	OK
12145	2026-09-18 20:59	29.34	OK	12146	2026-09-18 21:00	27.69	OK
12147	2026-09-18 21:01	28.20	OK	12148	2026-09-18 21:02	29.47	OK
12149	2026-09-18 21:03	29.91	OK	12150	2026-09-18 21:04	30.22	OK
12151	2026-09-18 21:05	29.43	OK	12152	2026-09-18 21:06	28.27	OK
12153	2026-09-18 21:07	30.28	OK	12154	2026-09-18 21:08	28.99	OK
12155	2026-09-18 21:09	29.93	OK	12156	2026-09-18 21:10	28.15	OK
12157	2026-09-18 21:11	30.53	OK	12158	2026-09-18 21:12	29.09	OK
12159	2026-09-18 21:13	28.98	OK	12160	2026-09-18 21:14	28.30	OK
12161	2026-09-18 21:15	27.65	OK	12162	2026-09-18 21:16	29.24	OK
12163	2026-09-18 21:17	27.67	OK	12164	2026-09-18 21:18	30.20	OK
12165	2026-09-18 21:19	28.19	OK	12166	2026-09-18 21:20	29.55	OK
12167	2026-09-18 21:21	27.70	OK	12168	2026-09-18 21:22	28.33	OK
12169	2026-09-18 21:23	28.61	OK	12170	2026-09-18 21:24	28.44	OK
12171	2026-09-18 21:25	29.53	OK	12172	2026-09-18 21:26	29.35	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12173	2026-09-18 21:27	27.90	OK	12174	2026-09-18 21:28	29.82	OK
12175	2026-09-18 21:29	27.92	OK	12176	2026-09-18 21:30	28.29	OK
12177	2026-09-18 21:31	28.71	OK	12178	2026-09-18 21:32	30.07	OK
12179	2026-09-18 21:33	29.60	OK	12180	2026-09-18 21:34	29.63	OK
12181	2026-09-18 21:35	29.16	OK	12182	2026-09-18 21:36	29.45	OK
12183	2026-09-18 21:37	30.50	OK	12184	2026-09-18 21:38	30.21	OK
12185	2026-09-18 21:39	30.28	OK	12186	2026-09-18 21:40	28.61	OK
12187	2026-09-18 21:41	29.69	OK	12188	2026-09-18 21:42	30.22	OK
12189	2026-09-18 21:43	28.64	OK	12190	2026-09-18 21:44	29.41	OK
12191	2026-09-18 21:45	28.68	OK	12192	2026-09-18 21:46	28.49	OK
12193	2026-09-18 21:47	29.79	OK	12194	2026-09-18 21:48	28.49	OK
12195	2026-09-18 21:49	29.98	OK	12196	2026-09-18 21:50	29.06	OK
12197	2026-09-18 21:51	29.01	OK	12198	2026-09-18 21:52	31.12	OK
12199	2026-09-18 21:53	29.82	OK	12200	2026-09-18 21:54	28.35	OK
12201	2026-09-18 21:55	29.72	OK	12202	2026-09-18 21:56	29.18	OK
12203	2026-09-18 21:57	29.00	OK	12204	2026-09-18 21:58	27.28	OK
12205	2026-09-18 21:59	30.16	OK	12206	2026-09-18 22:00	29.43	OK
12207	2026-09-18 22:01	29.27	OK	12208	2026-09-18 22:02	29.90	OK
12209	2026-09-18 22:03	30.29	OK	12210	2026-09-18 22:04	30.26	OK
12211	2026-09-18 22:05	29.17	OK	12212	2026-09-18 22:06	30.41	OK
12213	2026-09-18 22:07	29.99	OK	12214	2026-09-18 22:08	28.67	OK
12215	2026-09-18 22:09	30.67	OK	12216	2026-09-18 22:10	30.15	OK
12217	2026-09-18 22:11	28.84	OK	12218	2026-09-18 22:12	29.74	OK
12219	2026-09-18 22:13	29.41	OK	12220	2026-09-18 22:14	29.44	OK
12221	2026-09-18 22:15	29.13	OK	12222	2026-09-18 22:16	28.61	OK
12223	2026-09-18 22:17	28.41	OK	12224	2026-09-18 22:18	29.41	OK
12225	2026-09-18 22:19	30.24	OK	12226	2026-09-18 22:20	30.55	OK
12227	2026-09-18 22:21	30.19	OK	12228	2026-09-18 22:22	29.76	OK
12229	2026-09-18 22:23	30.15	OK	12230	2026-09-18 22:24	30.56	OK
12231	2026-09-18 22:25	28.71	OK	12232	2026-09-18 22:26	30.02	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12233	2026-09-18 22:27	30.37	OK	12234	2026-09-18 22:28	29.40	OK
12235	2026-09-18 22:29	30.35	OK	12236	2026-09-18 22:30	28.61	OK
12237	2026-09-18 22:31	28.21	OK	12238	2026-09-18 22:32	29.98	OK
12239	2026-09-18 22:33	30.10	OK	12240	2026-09-18 22:34	29.51	OK
12241	2026-09-18 22:35	30.56	OK	12242	2026-09-18 22:36	28.91	OK
12243	2026-09-18 22:37	29.55	OK	12244	2026-09-18 22:38	30.22	OK
12245	2026-09-18 22:39	28.94	OK	12246	2026-09-18 22:40	28.97	OK
12247	2026-09-18 22:41	28.58	OK	12248	2026-09-18 22:42	30.09	OK
12249	2026-09-18 22:43	29.76	OK	12250	2026-09-18 22:44	30.11	OK
12251	2026-09-18 22:45	30.13	OK	12252	2026-09-18 22:46	29.26	OK
12253	2026-09-18 22:47	29.14	OK	12254	2026-09-18 22:48	31.14	OK
12255	2026-09-18 22:49	28.99	OK	12256	2026-09-18 22:50	28.71	OK
12257	2026-09-18 22:51	30.49	OK	12258	2026-09-18 22:52	30.80	OK
12259	2026-09-18 22:53	29.18	OK	12260	2026-09-18 22:54	29.90	OK
12261	2026-09-18 22:55	30.40	OK	12262	2026-09-18 22:56	30.37	OK
12263	2026-09-18 22:57	29.97	OK	12264	2026-09-18 22:58	28.34	OK
12265	2026-09-18 22:59	30.60	OK	12266	2026-09-18 23:00	29.79	OK
12267	2026-09-18 23:01	28.48	OK	12268	2026-09-18 23:02	29.67	OK
12269	2026-09-18 23:03	31.12	OK	12270	2026-09-18 23:04	30.41	OK
12271	2026-09-18 23:05	29.21	OK	12272	2026-09-18 23:06	29.71	OK
12273	2026-09-18 23:07	29.64	OK	12274	2026-09-18 23:08	29.46	OK
12275	2026-09-18 23:09	29.65	OK	12276	2026-09-18 23:10	28.82	OK
12277	2026-09-18 23:11	29.05	OK	12278	2026-09-18 23:12	30.36	OK
12279	2026-09-18 23:13	30.65	OK	12280	2026-09-18 23:14	30.68	OK
12281	2026-09-18 23:15	29.11	OK	12282	2026-09-18 23:16	29.44	OK
12283	2026-09-18 23:17	29.29	OK	12284	2026-09-18 23:18	30.34	OK
12285	2026-09-18 23:19	29.60	OK	12286	2026-09-18 23:20	29.89	OK
12287	2026-09-18 23:21	30.27	OK	12288	2026-09-18 23:22	29.92	OK
12289	2026-09-18 23:23	28.98	OK	12290	2026-09-18 23:24	30.29	OK
12291	2026-09-18 23:25	28.89	OK	12292	2026-09-18 23:26	31.60	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12293	2026-09-18 23:27	29.97	OK	12294	2026-09-18 23:28	29.76	OK
12295	2026-09-18 23:29	30.59	OK	12296	2026-09-18 23:30	28.78	OK
12297	2026-09-18 23:31	30.20	OK	12298	2026-09-18 23:32	29.19	OK
12299	2026-09-18 23:33	30.29	OK	12300	2026-09-18 23:34	31.07	OK
12301	2026-09-18 23:35	28.91	OK	12302	2026-09-18 23:36	30.57	OK
12303	2026-09-18 23:37	30.13	OK	12304	2026-09-18 23:38	30.00	OK
12305	2026-09-18 23:39	29.56	OK	12306	2026-09-18 23:40	31.37	OK
12307	2026-09-18 23:41	29.51	OK	12308	2026-09-18 23:42	29.96	OK
12309	2026-09-18 23:43	28.46	OK	12310	2026-09-18 23:44	29.47	OK
12311	2026-09-18 23:45	30.56	OK	12312	2026-09-18 23:46	29.21	OK
12313	2026-09-18 23:47	30.36	OK	12314	2026-09-18 23:48	29.43	OK
12315	2026-09-18 23:49	30.38	OK	12316	2026-09-18 23:50	29.63	OK
12317	2026-09-18 23:51	29.43	OK	12318	2026-09-18 23:52	30.04	OK
12319	2026-09-18 23:53	29.84	OK	12320	2026-09-18 23:54	30.78	OK
12321	2026-09-18 23:55	30.00	OK	12322	2026-09-18 23:56	28.81	OK
12323	2026-09-18 23:57	30.65	OK	12324	2026-09-18 23:58	31.23	OK
12325	2026-09-18 23:59	29.95	OK	12326	2026-09-19 00:00	29.02	OK
12327	2026-09-19 00:01	30.33	OK	12328	2026-09-19 00:02	29.70	OK
12329	2026-09-19 00:03	28.79	OK	12330	2026-09-19 00:04	30.14	OK
12331	2026-09-19 00:05	30.09	OK	12332	2026-09-19 00:06	30.99	OK
12333	2026-09-19 00:07	30.29	OK	12334	2026-09-19 00:08	30.07	OK
12335	2026-09-19 00:09	30.22	OK	12336	2026-09-19 00:10	29.38	OK
12337	2026-09-19 00:11	28.98	OK	12338	2026-09-19 00:12	30.53	OK
12339	2026-09-19 00:13	28.60	OK	12340	2026-09-19 00:14	31.25	OK
12341	2026-09-19 00:15	30.39	OK	12342	2026-09-19 00:16	29.62	OK
12343	2026-09-19 00:17	29.64	OK	12344	2026-09-19 00:18	29.78	OK
12345	2026-09-19 00:19	30.16	OK	12346	2026-09-19 00:20	30.21	OK
12347	2026-09-19 00:21	30.34	OK	12348	2026-09-19 00:22	29.23	OK
12349	2026-09-19 00:23	29.83	OK	12350	2026-09-19 00:24	30.07	OK
12351	2026-09-19 00:25	29.80	OK	12352	2026-09-19 00:26	30.84	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12353	2026-09-19 00:27	30.47	OK	12354	2026-09-19 00:28	31.28	OK
12355	2026-09-19 00:29	30.38	OK	12356	2026-09-19 00:30	31.12	OK
12357	2026-09-19 00:31	30.09	OK	12358	2026-09-19 00:32	30.74	OK
12359	2026-09-19 00:33	29.97	OK	12360	2026-09-19 00:34	30.79	OK
12361	2026-09-19 00:35	31.24	OK	12362	2026-09-19 00:36	30.68	OK
12363	2026-09-19 00:37	31.21	OK	12364	2026-09-19 00:38	30.49	OK
12365	2026-09-19 00:39	30.81	OK	12366	2026-09-19 00:40	30.61	OK
12367	2026-09-19 00:41	29.44	OK	12368	2026-09-19 00:42	30.46	OK
12369	2026-09-19 00:43	31.01	OK	12370	2026-09-19 00:44	31.14	OK
12371	2026-09-19 00:45	29.82	OK	12372	2026-09-19 00:46	28.93	OK
12373	2026-09-19 00:47	29.93	OK	12374	2026-09-19 00:48	29.80	OK
12375	2026-09-19 00:49	31.34	OK	12376	2026-09-19 00:50	29.88	OK
12377	2026-09-19 00:51	30.17	OK	12378	2026-09-19 00:52	30.15	OK
12379	2026-09-19 00:53	29.60	OK	12380	2026-09-19 00:54	30.32	OK
12381	2026-09-19 00:55	30.34	OK	12382	2026-09-19 00:56	30.46	OK
12383	2026-09-19 00:57	30.85	OK	12384	2026-09-19 00:58	29.81	OK
12385	2026-09-19 00:59	29.63	OK	12386	2026-09-19 01:00	29.89	OK
12387	2026-09-19 01:01	30.14	OK	12388	2026-09-19 01:02	29.98	OK
12389	2026-09-19 01:03	29.72	OK	12390	2026-09-19 01:04	30.68	OK
12391	2026-09-19 01:05	30.64	OK	12392	2026-09-19 01:06	30.00	OK
12393	2026-09-19 01:07	29.90	OK	12394	2026-09-19 01:08	30.09	OK
12395	2026-09-19 01:09	29.99	OK	12396	2026-09-19 01:10	31.24	OK
12397	2026-09-19 01:11	31.61	OK	12398	2026-09-19 01:12	30.60	OK
12399	2026-09-19 01:13	30.25	OK	12400	2026-09-19 01:14	31.38	OK
12401	2026-09-19 01:15	29.60	OK	12402	2026-09-19 01:16	31.66	OK
12403	2026-09-19 01:17	30.33	OK	12404	2026-09-19 01:18	30.83	OK
12405	2026-09-19 01:19	30.10	OK	12406	2026-09-19 01:20	29.85	OK
12407	2026-09-19 01:21	30.29	OK	12408	2026-09-19 01:22	31.42	OK
12409	2026-09-19 01:23	30.87	OK	12410	2026-09-19 01:24	29.77	OK
12411	2026-09-19 01:25	29.11	OK	12412	2026-09-19 01:26	29.12	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12413	2026-09-19 01:27	29.81	OK	12414	2026-09-19 01:28	30.67	OK
12415	2026-09-19 01:29	32.25	OK	12416	2026-09-19 01:30	28.92	OK
12417	2026-09-19 01:31	29.57	OK	12418	2026-09-19 01:32	31.80	OK
12419	2026-09-19 01:33	29.13	OK	12420	2026-09-19 01:34	31.18	OK
12421	2026-09-19 01:35	31.00	OK	12422	2026-09-19 01:36	29.50	OK
12423	2026-09-19 01:37	29.55	OK	12424	2026-09-19 01:38	31.09	OK
12425	2026-09-19 01:39	30.36	OK	12426	2026-09-19 01:40	29.89	OK
12427	2026-09-19 01:41	29.44	OK	12428	2026-09-19 01:42	28.80	OK
12429	2026-09-19 01:43	30.38	OK	12430	2026-09-19 01:44	30.91	OK
12431	2026-09-19 01:45	29.29	OK	12432	2026-09-19 01:46	30.85	OK
12433	2026-09-19 01:47	30.22	OK	12434	2026-09-19 01:48	30.00	OK
12435	2026-09-19 01:49	30.71	OK	12436	2026-09-19 01:50	30.93	OK
12437	2026-09-19 01:51	30.60	OK	12438	2026-09-19 01:52	30.26	OK
12439	2026-09-19 01:53	29.62	OK	12440	2026-09-19 01:54	31.18	OK
12441	2026-09-19 01:55	30.66	OK	12442	2026-09-19 01:56	30.28	OK
12443	2026-09-19 01:57	31.00	OK	12444	2026-09-19 01:58	31.48	OK
12445	2026-09-19 01:59	31.37	OK	12446	2026-09-19 02:00	30.86	OK
12447	2026-09-19 02:01	29.69	OK	12448	2026-09-19 02:02	29.68	OK
12449	2026-09-19 02:03	30.86	OK	12450	2026-09-19 02:04	31.33	OK
12451	2026-09-19 02:05	30.46	OK	12452	2026-09-19 02:06	30.41	OK
12453	2026-09-19 02:07	29.75	OK	12454	2026-09-19 02:08	31.22	OK
12455	2026-09-19 02:09	29.35	OK	12456	2026-09-19 02:10	29.28	OK
12457	2026-09-19 02:11	29.54	OK	12458	2026-09-19 02:12	29.91	OK
12459	2026-09-19 02:13	29.69	OK	12460	2026-09-19 02:14	29.45	OK
12461	2026-09-19 02:15	30.88	OK	12462	2026-09-19 02:16	30.81	OK
12463	2026-09-19 02:17	30.06	OK	12464	2026-09-19 02:18	29.97	OK
12465	2026-09-19 02:19	31.00	OK	12466	2026-09-19 02:20	30.99	OK
12467	2026-09-19 02:21	30.56	OK	12468	2026-09-19 02:22	31.01	OK
12469	2026-09-19 02:23	31.13	OK	12470	2026-09-19 02:24	29.64	OK
12471	2026-09-19 02:25	30.58	OK	12472	2026-09-19 02:26	29.64	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12473	2026-09-19 02:27	30.90	OK	12474	2026-09-19 02:28	29.75	OK
12475	2026-09-19 02:29	30.56	OK	12476	2026-09-19 02:30	29.57	OK
12477	2026-09-19 02:31	31.01	OK	12478	2026-09-19 02:32	30.90	OK
12479	2026-09-19 02:33	29.57	OK	12480	2026-09-19 02:34	29.22	OK
12481	2026-09-19 02:35	29.48	OK	12482	2026-09-19 02:36	30.41	OK
12483	2026-09-19 02:37	29.50	OK	12484	2026-09-19 02:38	29.68	OK
12485	2026-09-19 02:39	31.28	OK	12486	2026-09-19 02:40	30.04	OK
12487	2026-09-19 02:41	29.08	OK	12488	2026-09-19 02:42	31.75	OK
12489	2026-09-19 02:43	28.70	OK	12490	2026-09-19 02:44	29.44	OK
12491	2026-09-19 02:45	29.33	OK	12492	2026-09-19 02:46	29.42	OK
12493	2026-09-19 02:47	30.03	OK	12494	2026-09-19 02:48	30.47	OK
12495	2026-09-19 02:49	29.67	OK	12496	2026-09-19 02:50	30.52	OK
12497	2026-09-19 02:51	29.75	OK	12498	2026-09-19 02:52	30.80	OK
12499	2026-09-19 02:53	30.28	OK	12500	2026-09-19 02:54	29.60	OK
12501	2026-09-19 02:55	29.91	OK	12502	2026-09-19 02:56	28.33	OK
12503	2026-09-19 02:57	30.84	OK	12504	2026-09-19 02:58	30.97	OK
12505	2026-09-19 02:59	31.01	OK	12506	2026-09-19 03:00	31.06	OK
12507	2026-09-19 03:01	31.08	OK	12508	2026-09-19 03:02	30.77	OK
12509	2026-09-19 03:03	30.61	OK	12510	2026-09-19 03:04	29.86	OK
12511	2026-09-19 03:05	29.89	OK	12512	2026-09-19 03:06	30.55	OK
12513	2026-09-19 03:07	30.33	OK	12514	2026-09-19 03:08	30.97	OK
12515	2026-09-19 03:09	31.17	OK	12516	2026-09-19 03:10	30.25	OK
12517	2026-09-19 03:11	30.00	OK	12518	2026-09-19 03:12	30.63	OK
12519	2026-09-19 03:13	28.57	OK	12520	2026-09-19 03:14	31.26	OK
12521	2026-09-19 03:15	29.39	OK	12522	2026-09-19 03:16	30.05	OK
12523	2026-09-19 03:17	30.75	OK	12524	2026-09-19 03:18	28.53	OK
12525	2026-09-19 03:19	30.29	OK	12526	2026-09-19 03:20	30.78	OK
12527	2026-09-19 03:21	29.82	OK	12528	2026-09-19 03:22	29.20	OK
12529	2026-09-19 03:23	28.90	OK	12530	2026-09-19 03:24	28.96	OK
12531	2026-09-19 03:25	30.24	OK	12532	2026-09-19 03:26	31.92	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12533	2026-09-19 03:27	31.00	OK	12534	2026-09-19 03:28	29.64	OK
12535	2026-09-19 03:29	29.46	OK	12536	2026-09-19 03:30	30.61	OK
12537	2026-09-19 03:31	29.72	OK	12538	2026-09-19 03:32	29.32	OK
12539	2026-09-19 03:33	29.61	OK	12540	2026-09-19 03:34	31.04	OK
12541	2026-09-19 03:35	29.11	OK	12542	2026-09-19 03:36	31.43	OK
12543	2026-09-19 03:37	29.56	OK	12544	2026-09-19 03:38	29.62	OK
12545	2026-09-19 03:39	31.51	OK	12546	2026-09-19 03:40	30.90	OK
12547	2026-09-19 03:41	30.19	OK	12548	2026-09-19 03:42	29.51	OK
12549	2026-09-19 03:43	29.38	OK	12550	2026-09-19 03:44	30.58	OK
12551	2026-09-19 03:45	29.81	OK	12552	2026-09-19 03:46	30.02	OK
12553	2026-09-19 03:47	30.61	OK	12554	2026-09-19 03:48	31.16	OK
12555	2026-09-19 03:49	28.97	OK	12556	2026-09-19 03:50	29.60	OK
12557	2026-09-19 03:51	30.72	OK	12558	2026-09-19 03:52	30.31	OK
12559	2026-09-19 03:53	28.63	OK	12560	2026-09-19 03:54	28.18	OK
12561	2026-09-19 03:55	29.86	OK	12562	2026-09-19 03:56	28.47	OK
12563	2026-09-19 03:57	29.92	OK	12564	2026-09-19 03:58	29.71	OK
12565	2026-09-19 03:59	29.56	OK	12566	2026-09-19 04:00	30.70	OK
12567	2026-09-19 04:01	29.27	OK	12568	2026-09-19 04:02	29.98	OK
12569	2026-09-19 04:03	28.54	OK	12570	2026-09-19 04:04	28.59	OK
12571	2026-09-19 04:05	28.17	OK	12572	2026-09-19 04:06	29.48	OK
12573	2026-09-19 04:07	29.77	OK	12574	2026-09-19 04:08	30.71	OK
12575	2026-09-19 04:09	29.63	OK	12576	2026-09-19 04:10	29.29	OK
12577	2026-09-19 04:11	28.66	OK	12578	2026-09-19 04:12	29.90	OK
12579	2026-09-19 04:13	29.42	OK	12580	2026-09-19 04:14	29.46	OK
12581	2026-09-19 04:15	29.32	OK	12582	2026-09-19 04:16	28.99	OK
12583	2026-09-19 04:17	29.74	OK	12584	2026-09-19 04:18	28.69	OK
12585	2026-09-19 04:19	30.09	OK	12586	2026-09-19 04:20	29.93	OK
12587	2026-09-19 04:21	28.42	OK	12588	2026-09-19 04:22	30.30	OK
12589	2026-09-19 04:23	30.35	OK	12590	2026-09-19 04:24	29.63	OK
12591	2026-09-19 04:25	29.85	OK	12592	2026-09-19 04:26	28.46	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12593	2026-09-19 04:27	28.79	OK	12594	2026-09-19 04:28	30.00	OK
12595	2026-09-19 04:29	28.91	OK	12596	2026-09-19 04:30	28.24	OK
12597	2026-09-19 04:31	29.54	OK	12598	2026-09-19 04:32	30.06	OK
12599	2026-09-19 04:33	29.78	OK	12600	2026-09-19 04:34	30.92	OK
12601	2026-09-19 04:35	30.84	OK	12602	2026-09-19 04:36	28.74	OK
12603	2026-09-19 04:37	27.57	OK	12604	2026-09-19 04:38	29.80	OK
12605	2026-09-19 04:39	30.61	OK	12606	2026-09-19 04:40	29.85	OK
12607	2026-09-19 04:41	28.89	OK	12608	2026-09-19 04:42	28.21	OK
12609	2026-09-19 04:43	28.39	OK	12610	2026-09-19 04:44	28.66	OK
12611	2026-09-19 04:45	30.26	OK	12612	2026-09-19 04:46	29.56	OK
12613	2026-09-19 04:47	29.07	OK	12614	2026-09-19 04:48	28.27	OK
12615	2026-09-19 04:49	29.49	OK	12616	2026-09-19 04:50	28.46	OK
12617	2026-09-19 04:51	30.42	OK	12618	2026-09-19 04:52	29.51	OK
12619	2026-09-19 04:53	28.74	OK	12620	2026-09-19 04:54	28.62	OK
12621	2026-09-19 04:55	29.40	OK	12622	2026-09-19 04:56	28.44	OK
12623	2026-09-19 04:57	29.96	OK	12624	2026-09-19 04:58	28.48	OK
12625	2026-09-19 04:59	29.92	OK	12626	2026-09-19 05:00	29.26	OK
12627	2026-09-19 05:01	29.60	OK	12628	2026-09-19 05:02	27.96	OK
12629	2026-09-19 05:03	29.35	OK	12630	2026-09-19 05:04	29.95	OK
12631	2026-09-19 05:05	29.91	OK	12632	2026-09-19 05:06	28.82	OK
12633	2026-09-19 05:07	28.20	OK	12634	2026-09-19 05:08	30.46	OK
12635	2026-09-19 05:09	28.42	OK	12636	2026-09-19 05:10	29.89	OK
12637	2026-09-19 05:11	30.60	OK	12638	2026-09-19 05:12	28.21	OK
12639	2026-09-19 05:13	28.89	OK	12640	2026-09-19 05:14	29.19	OK
12641	2026-09-19 05:15	30.11	OK	12642	2026-09-19 05:16	27.40	OK
12643	2026-09-19 05:17	28.04	OK	12644	2026-09-19 05:18	29.53	OK
12645	2026-09-19 05:19	29.35	OK	12646	2026-09-19 05:20	29.45	OK
12647	2026-09-19 05:21	27.70	OK	12648	2026-09-19 05:22	28.67	OK
12649	2026-09-19 05:23	28.05	OK	12650	2026-09-19 05:24	28.98	OK
12651	2026-09-19 05:25	29.15	OK	12652	2026-09-19 05:26	29.42	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12653	2026-09-19 05:27	29.38	OK	12654	2026-09-19 05:28	29.34	OK
12655	2026-09-19 05:29	29.68	OK	12656	2026-09-19 05:30	30.30	OK
12657	2026-09-19 05:31	28.80	OK	12658	2026-09-19 05:32	29.83	OK
12659	2026-09-19 05:33	28.43	OK	12660	2026-09-19 05:34	30.79	OK
12661	2026-09-19 05:35	29.57	OK	12662	2026-09-19 05:36	28.88	OK
12663	2026-09-19 05:37	29.23	OK	12664	2026-09-19 05:38	28.14	OK
12665	2026-09-19 05:39	29.16	OK	12666	2026-09-19 05:40	29.43	OK
12667	2026-09-19 05:41	28.67	OK	12668	2026-09-19 05:42	28.61	OK
12669	2026-09-19 05:43	29.47	OK	12670	2026-09-19 05:44	30.77	OK
12671	2026-09-19 05:45	30.34	OK	12672	2026-09-19 05:46	29.93	OK
12673	2026-09-19 05:47	27.66	OK	12674	2026-09-19 05:48	29.71	OK
12675	2026-09-19 05:49	28.70	OK	12676	2026-09-19 05:50	29.61	OK
12677	2026-09-19 05:51	28.44	OK	12678	2026-09-19 05:52	28.79	OK
12679	2026-09-19 05:53	28.61	OK	12680	2026-09-19 05:54	28.31	OK
12681	2026-09-19 05:55	28.09	OK	12682	2026-09-19 05:56	28.06	OK
12683	2026-09-19 05:57	28.96	OK	12684	2026-09-19 05:58	30.36	OK
12685	2026-09-19 05:59	28.56	OK	12686	2026-09-19 06:00	28.42	OK
12687	2026-09-19 06:01	30.01	OK	12688	2026-09-19 06:02	29.34	OK
12689	2026-09-19 06:03	28.96	OK	12690	2026-09-19 06:04	28.97	OK
12691	2026-09-19 06:05	29.26	OK	12692	2026-09-19 06:06	29.33	OK
12693	2026-09-19 06:07	28.99	OK	12694	2026-09-19 06:08	28.87	OK
12695	2026-09-19 06:09	28.45	OK	12696	2026-09-19 06:10	28.75	OK
12697	2026-09-19 06:11	27.82	OK	12698	2026-09-19 06:12	29.37	OK
12699	2026-09-19 06:13	28.49	OK	12700	2026-09-19 06:14	29.61	OK
12701	2026-09-19 06:15	28.17	OK	12702	2026-09-19 06:16	28.83	OK
12703	2026-09-19 06:17	29.26	OK	12704	2026-09-19 06:18	27.18	OK
12705	2026-09-19 06:19	28.43	OK	12706	2026-09-19 06:20	27.46	OK
12707	2026-09-19 06:21	28.84	OK	12708	2026-09-19 06:22	27.01	OK
12709	2026-09-19 06:23	28.49	OK	12710	2026-09-19 06:24	30.04	OK
12711	2026-09-19 06:25	28.21	OK	12712	2026-09-19 06:26	28.87	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12713	2026-09-19 06:27	28.90	OK	12714	2026-09-19 06:28	28.66	OK
12715	2026-09-19 06:29	30.38	OK	12716	2026-09-19 06:30	29.91	OK
12717	2026-09-19 06:31	29.00	OK	12718	2026-09-19 06:32	28.33	OK
12719	2026-09-19 06:33	28.06	OK	12720	2026-09-19 06:34	28.07	OK
12721	2026-09-19 06:35	29.27	OK	12722	2026-09-19 06:36	28.23	OK
12723	2026-09-19 06:37	29.46	OK	12724	2026-09-19 06:38	27.91	OK
12725	2026-09-19 06:39	27.06	OK	12726	2026-09-19 06:40	28.07	OK
12727	2026-09-19 06:41	29.49	OK	12728	2026-09-19 06:42	27.83	OK
12729	2026-09-19 06:43	29.01	OK	12730	2026-09-19 06:44	27.92	OK
12731	2026-09-19 06:45	28.38	OK	12732	2026-09-19 06:46	28.05	OK
12733	2026-09-19 06:47	27.66	OK	12734	2026-09-19 06:48	28.35	OK
12735	2026-09-19 06:49	29.08	OK	12736	2026-09-19 06:50	28.76	OK
12737	2026-09-19 06:51	28.01	OK	12738	2026-09-19 06:52	28.88	OK
12739	2026-09-19 06:53	28.04	OK	12740	2026-09-19 06:54	27.69	OK
12741	2026-09-19 06:55	28.00	OK	12742	2026-09-19 06:56	27.74	OK
12743	2026-09-19 06:57	27.29	OK	12744	2026-09-19 06:58	29.02	OK
12745	2026-09-19 06:59	28.46	OK	12746	2026-09-19 07:00	28.96	OK
12747	2026-09-19 07:01	28.96	OK	12748	2026-09-19 07:02	27.79	OK
12749	2026-09-19 07:03	29.62	OK	12750	2026-09-19 07:04	29.05	OK
12751	2026-09-19 07:05	27.21	OK	12752	2026-09-19 07:06	28.52	OK
12753	2026-09-19 07:07	27.89	OK	12754	2026-09-19 07:08	27.82	OK
12755	2026-09-19 07:09	28.69	OK	12756	2026-09-19 07:10	27.98	OK
12757	2026-09-19 07:11	28.62	OK	12758	2026-09-19 07:12	27.85	OK
12759	2026-09-19 07:13	27.07	OK	12760	2026-09-19 07:14	26.71	OK
12761	2026-09-19 07:15	27.62	OK	12762	2026-09-19 07:16	27.38	OK
12763	2026-09-19 07:17	28.62	OK	12764	2026-09-19 07:18	26.60	OK
12765	2026-09-19 07:19	28.33	OK	12766	2026-09-19 07:20	29.78	OK
12767	2026-09-19 07:21	28.13	OK	12768	2026-09-19 07:22	28.07	OK
12769	2026-09-19 07:23	27.22	OK	12770	2026-09-19 07:24	28.21	OK
12771	2026-09-19 07:25	27.22	OK	12772	2026-09-19 07:26	28.06	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12773	2026-09-19 07:27	26.60	OK	12774	2026-09-19 07:28	28.77	OK
12775	2026-09-19 07:29	27.54	OK	12776	2026-09-19 07:30	28.58	OK
12777	2026-09-19 07:31	28.50	OK	12778	2026-09-19 07:32	28.83	OK
12779	2026-09-19 07:33	29.00	OK	12780	2026-09-19 07:34	26.72	OK
12781	2026-09-19 07:35	29.51	OK	12782	2026-09-19 07:36	26.13	OK
12783	2026-09-19 07:37	28.62	OK	12784	2026-09-19 07:38	28.80	OK
12785	2026-09-19 07:39	28.81	OK	12786	2026-09-19 07:40	26.62	OK
12787	2026-09-19 07:41	28.63	OK	12788	2026-09-19 07:42	29.39	OK
12789	2026-09-19 07:43	28.09	OK	12790	2026-09-19 07:44	26.75	OK
12791	2026-09-19 07:45	28.02	OK	12792	2026-09-19 07:46	27.06	OK
12793	2026-09-19 07:47	28.69	OK	12794	2026-09-19 07:48	28.38	OK
12795	2026-09-19 07:49	27.45	OK	12796	2026-09-19 07:50	26.83	OK
12797	2026-09-19 07:51	28.63	OK	12798	2026-09-19 07:52	26.17	OK
12799	2026-09-19 07:53	26.73	OK	12800	2026-09-19 07:54	28.42	OK
12801	2026-09-19 07:55	27.96	OK	12802	2026-09-19 07:56	27.13	OK
12803	2026-09-19 07:57	27.50	OK	12804	2026-09-19 07:58	28.94	OK
12805	2026-09-19 07:59	27.98	OK	12806	2026-09-19 08:00	28.41	OK
12807	2026-09-19 08:01	27.00	OK	12808	2026-09-19 08:02	27.44	OK
12809	2026-09-19 08:03	27.54	OK	12810	2026-09-19 08:04	26.53	OK
12811	2026-09-19 08:05	29.28	OK	12812	2026-09-19 08:06	27.33	OK
12813	2026-09-19 08:07	29.18	OK	12814	2026-09-19 08:08	27.42	OK
12815	2026-09-19 08:09	27.35	OK	12816	2026-09-19 08:10	27.55	OK
12817	2026-09-19 08:11	28.24	OK	12818	2026-09-19 08:12	26.84	OK
12819	2026-09-19 08:13	27.40	OK	12820	2026-09-19 08:14	26.84	OK
12821	2026-09-19 08:15	28.38	OK	12822	2026-09-19 08:16	26.58	OK
12823	2026-09-19 08:17	27.88	OK	12824	2026-09-19 08:18	26.72	OK
12825	2026-09-19 08:19	26.40	OK	12826	2026-09-19 08:20	27.63	OK
12827	2026-09-19 08:21	26.42	OK	12828	2026-09-19 08:22	26.61	OK
12829	2026-09-19 08:23	26.85	OK	12830	2026-09-19 08:24	26.94	OK
12831	2026-09-19 08:25	27.74	OK	12832	2026-09-19 08:26	27.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12833	2026-09-19 08:27	26.75	OK	12834	2026-09-19 08:28	28.18	OK
12835	2026-09-19 08:29	26.47	OK	12836	2026-09-19 08:30	27.13	OK
12837	2026-09-19 08:31	27.40	OK	12838	2026-09-19 08:32	27.11	OK
12839	2026-09-19 08:33	26.75	OK	12840	2026-09-19 08:34	28.33	OK
12841	2026-09-19 08:35	28.47	OK	12842	2026-09-19 08:36	28.36	OK
12843	2026-09-19 08:37	27.15	OK	12844	2026-09-19 08:38	27.11	OK
12845	2026-09-19 08:39	27.97	OK	12846	2026-09-19 08:40	27.33	OK
12847	2026-09-19 08:41	27.57	OK	12848	2026-09-19 08:42	26.23	OK
12849	2026-09-19 08:43	28.40	OK	12850	2026-09-19 08:44	28.97	OK
12851	2026-09-19 08:45	26.84	OK	12852	2026-09-19 08:46	27.50	OK
12853	2026-09-19 08:47	26.36	OK	12854	2026-09-19 08:48	28.67	OK
12855	2026-09-19 08:49	26.48	OK	12856	2026-09-19 08:50	28.76	OK
12857	2026-09-19 08:51	27.73	OK	12858	2026-09-19 08:52	27.59	OK
12859	2026-09-19 08:53	26.19	OK	12860	2026-09-19 08:54	27.01	OK
12861	2026-09-19 08:55	25.85	OK	12862	2026-09-19 08:56	26.29	OK
12863	2026-09-19 08:57	27.29	OK	12864	2026-09-19 08:58	27.36	OK
12865	2026-09-19 08:59	29.00	OK	12866	2026-09-19 09:00	27.64	OK
12867	2026-09-19 09:01	26.91	OK	12868	2026-09-19 09:02	27.68	OK
12869	2026-09-19 09:03	26.07	OK	12870	2026-09-19 09:04	26.37	OK
12871	2026-09-19 09:05	27.47	OK	12872	2026-09-19 09:06	26.78	OK
12873	2026-09-19 09:07	27.42	OK	12874	2026-09-19 09:08	26.02	OK
12875	2026-09-19 09:09	26.91	OK	12876	2026-09-19 09:10	27.46	OK
12877	2026-09-19 09:11	28.09	OK	12878	2026-09-19 09:12	27.52	OK
12879	2026-09-19 09:13	26.82	OK	12880	2026-09-19 09:14	25.74	OK
12881	2026-09-19 09:15	26.71	OK	12882	2026-09-19 09:16	26.90	OK
12883	2026-09-19 09:17	25.50	OK	12884	2026-09-19 09:18	27.57	OK
12885	2026-09-19 09:19	26.95	OK	12886	2026-09-19 09:20	26.89	OK
12887	2026-09-19 09:21	26.05	OK	12888	2026-09-19 09:22	26.21	OK
12889	2026-09-19 09:23	26.81	OK	12890	2026-09-19 09:24	25.24	OK
12891	2026-09-19 09:25	26.31	OK	12892	2026-09-19 09:26	27.54	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12893	2026-09-19 09:27	27.57	OK	12894	2026-09-19 09:28	26.52	OK
12895	2026-09-19 09:29	27.51	OK	12896	2026-09-19 09:30	27.67	OK
12897	2026-09-19 09:31	28.08	OK	12898	2026-09-19 09:32	26.01	OK
12899	2026-09-19 09:33	27.50	OK	12900	2026-09-19 09:34	26.28	OK
12901	2026-09-19 09:35	26.42	OK	12902	2026-09-19 09:36	27.83	OK
12903	2026-09-19 09:37	27.46	OK	12904	2026-09-19 09:38	26.72	OK
12905	2026-09-19 09:39	26.58	OK	12906	2026-09-19 09:40	26.69	OK
12907	2026-09-19 09:41	26.91	OK	12908	2026-09-19 09:42	25.59	OK
12909	2026-09-19 09:43	25.39	OK	12910	2026-09-19 09:44	26.68	OK
12911	2026-09-19 09:45	26.31	OK	12912	2026-09-19 09:46	27.08	OK
12913	2026-09-19 09:47	27.72	OK	12914	2026-09-19 09:48	26.40	OK
12915	2026-09-19 09:49	26.55	OK	12916	2026-09-19 09:50	27.16	OK
12917	2026-09-19 09:51	25.20	OK	12918	2026-09-19 09:52	25.85	OK
12919	2026-09-19 09:53	25.56	OK	12920	2026-09-19 09:54	26.89	OK
12921	2026-09-19 09:55	25.97	OK	12922	2026-09-19 09:56	26.41	OK
12923	2026-09-19 09:57	27.59	OK	12924	2026-09-19 09:58	26.91	OK
12925	2026-09-19 09:59	26.46	OK	12926	2026-09-19 10:00	27.19	OK
12927	2026-09-19 10:01	26.00	OK	12928	2026-09-19 10:02	25.85	OK
12929	2026-09-19 10:03	25.29	OK	12930	2026-09-19 10:04	26.18	OK
12931	2026-09-19 10:05	26.91	OK	12932	2026-09-19 10:06	27.94	OK
12933	2026-09-19 10:07	26.38	OK	12934	2026-09-19 10:08	26.98	OK
12935	2026-09-19 10:09	27.48	OK	12936	2026-09-19 10:10	26.66	OK
12937	2026-09-19 10:11	26.87	OK	12938	2026-09-19 10:12	27.02	OK
12939	2026-09-19 10:13	26.80	OK	12940	2026-09-19 10:14	27.71	OK
12941	2026-09-19 10:15	24.98	OK	12942	2026-09-19 10:16	25.89	OK
12943	2026-09-19 10:17	27.96	OK	12944	2026-09-19 10:18	26.97	OK
12945	2026-09-19 10:19	26.15	OK	12946	2026-09-19 10:20	26.26	OK
12947	2026-09-19 10:21	26.23	OK	12948	2026-09-19 10:22	25.16	OK
12949	2026-09-19 10:23	25.80	OK	12950	2026-09-19 10:24	26.26	OK
12951	2026-09-19 10:25	26.14	OK	12952	2026-09-19 10:26	26.16	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
12953	2026-09-19 10:27	26.52	OK	12954	2026-09-19 10:28	26.16	OK
12955	2026-09-19 10:29	26.80	OK	12956	2026-09-19 10:30	25.91	OK
12957	2026-09-19 10:31	27.37	OK	12958	2026-09-19 10:32	25.20	OK
12959	2026-09-19 10:33	25.20	OK	12960	2026-09-19 10:34	25.89	OK
12961	2026-09-19 10:35	25.78	OK	12962	2026-09-19 10:36	26.91	OK
12963	2026-09-19 10:37	24.98	OK	12964	2026-09-19 10:38	27.64	OK
12965	2026-09-19 10:39	26.15	OK	12966	2026-09-19 10:40	27.64	OK
12967	2026-09-19 10:41	26.90	OK	12968	2026-09-19 10:42	25.68	OK
12969	2026-09-19 10:43	28.10	OK	12970	2026-09-19 10:44	27.29	OK
12971	2026-09-19 10:45	25.94	OK	12972	2026-09-19 10:46	25.80	OK
12973	2026-09-19 10:47	26.15	OK	12974	2026-09-19 10:48	27.11	OK
12975	2026-09-19 10:49	26.48	OK	12976	2026-09-19 10:50	26.59	OK
12977	2026-09-19 10:51	27.28	OK	12978	2026-09-19 10:52	26.04	OK
12979	2026-09-19 10:53	25.98	OK	12980	2026-09-19 10:54	24.81	OK
12981	2026-09-19 10:55	26.83	OK	12982	2026-09-19 10:56	26.77	OK
12983	2026-09-19 10:57	27.43	OK	12984	2026-09-19 10:58	24.80	OK
12985	2026-09-19 10:59	25.99	OK	12986	2026-09-19 11:00	26.13	OK
12987	2026-09-19 11:01	26.47	OK	12988	2026-09-19 11:02	26.19	OK
12989	2026-09-19 11:03	25.80	OK	12990	2026-09-19 11:04	27.71	OK
12991	2026-09-19 11:05	24.89	OK	12992	2026-09-19 11:06	25.79	OK
12993	2026-09-19 11:07	26.42	OK	12994	2026-09-19 11:08	26.37	OK
12995	2026-09-19 11:09	26.51	OK	12996	2026-09-19 11:10	26.37	OK
12997	2026-09-19 11:11	26.31	OK	12998	2026-09-19 11:12	26.16	OK
12999	2026-09-19 11:13	25.95	OK	13000	2026-09-19 11:14	26.41	OK
13001	2026-09-19 11:15	26.54	OK	13002	2026-09-19 11:16	26.33	OK
13003	2026-09-19 11:17	24.99	OK	13004	2026-09-19 11:18	26.66	OK
13005	2026-09-19 11:19	25.29	OK	13006	2026-09-19 11:20	26.46	OK
13007	2026-09-19 11:21	26.83	OK	13008	2026-09-19 11:22	25.52	OK
13009	2026-09-19 11:23	27.48	OK	13010	2026-09-19 11:24	25.25	OK
13011	2026-09-19 11:25	24.58	OK	13012	2026-09-19 11:26	25.82	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13013	2026-09-19 11:27	25.18	OK	13014	2026-09-19 11:28	25.12	OK
13015	2026-09-19 11:29	25.92	OK	13016	2026-09-19 11:30	26.51	OK
13017	2026-09-19 11:31	27.03	OK	13018	2026-09-19 11:32	26.69	OK
13019	2026-09-19 11:33	26.64	OK	13020	2026-09-19 11:34	25.91	OK
13021	2026-09-19 11:35	24.16	OK	13022	2026-09-19 11:36	26.65	OK
13023	2026-09-19 11:37	24.04	OK	13024	2026-09-19 11:38	23.99	OK
13025	2026-09-19 11:39	25.19	OK	13026	2026-09-19 11:40	24.74	OK
13027	2026-09-19 11:41	27.76	OK	13028	2026-09-19 11:42	25.82	OK
13029	2026-09-19 11:43	25.38	OK	13030	2026-09-19 11:44	26.23	OK
13031	2026-09-19 11:45	24.63	OK	13032	2026-09-19 11:46	24.54	OK
13033	2026-09-19 11:47	25.73	OK	13034	2026-09-19 11:48	25.89	OK
13035	2026-09-19 11:49	26.25	OK	13036	2026-09-19 11:50	26.03	OK
13037	2026-09-19 11:51	26.06	OK	13038	2026-09-19 11:52	24.83	OK
13039	2026-09-19 11:53	25.46	OK	13040	2026-09-19 11:54	25.73	OK
13041	2026-09-19 11:55	26.80	OK	13042	2026-09-19 11:56	26.46	OK
13043	2026-09-19 11:57	25.34	OK	13044	2026-09-19 11:58	26.17	OK
13045	2026-09-19 11:59	26.79	OK	13046	2026-09-19 12:00	26.42	OK
13047	2026-09-19 12:01	25.32	OK	13048	2026-09-19 12:02	26.10	OK
13049	2026-09-19 12:03	26.81	OK	13050	2026-09-19 12:04	26.03	OK
13051	2026-09-19 12:05	26.57	OK	13052	2026-09-19 12:06	25.92	OK
13053	2026-09-19 12:07	25.59	OK	13054	2026-09-19 12:08	24.82	OK
13055	2026-09-19 12:09	25.70	OK	13056	2026-09-19 12:10	25.25	OK
13057	2026-09-19 12:11	26.02	OK	13058	2026-09-19 12:12	25.42	OK
13059	2026-09-19 12:13	27.15	OK	13060	2026-09-19 12:14	25.97	OK
13061	2026-09-19 12:15	25.67	OK	13062	2026-09-19 12:16	24.86	OK
13063	2026-09-19 12:17	25.62	OK	13064	2026-09-19 12:18	25.51	OK
13065	2026-09-19 12:19	26.44	OK	13066	2026-09-19 12:20	25.78	OK
13067	2026-09-19 12:21	25.23	OK	13068	2026-09-19 12:22	25.00	OK
13069	2026-09-19 12:23	26.63	OK	13070	2026-09-19 12:24	24.53	OK
13071	2026-09-19 12:25	25.88	OK	13072	2026-09-19 12:26	26.61	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13073	2026-09-19 12:27	25.34	OK	13074	2026-09-19 12:28	25.64	OK
13075	2026-09-19 12:29	24.90	OK	13076	2026-09-19 12:30	25.61	OK
13077	2026-09-19 12:31	26.51	OK	13078	2026-09-19 12:32	25.43	OK
13079	2026-09-19 12:33	24.94	OK	13080	2026-09-19 12:34	25.07	OK
13081	2026-09-19 12:35	26.43	OK	13082	2026-09-19 12:36	24.71	OK
13083	2026-09-19 12:37	26.36	OK	13084	2026-09-19 12:38	25.99	OK
13085	2026-09-19 12:39	24.83	OK	13086	2026-09-19 12:40	24.74	OK
13087	2026-09-19 12:41	25.82	OK	13088	2026-09-19 12:42	24.64	OK
13089	2026-09-19 12:43	24.80	OK	13090	2026-09-19 12:44	27.51	OK
13091	2026-09-19 12:45	24.17	OK	13092	2026-09-19 12:46	25.97	OK
13093	2026-09-19 12:47	24.91	OK	13094	2026-09-19 12:48	24.95	OK
13095	2026-09-19 12:49	25.42	OK	13096	2026-09-19 12:50	26.18	OK
13097	2026-09-19 12:51	25.16	OK	13098	2026-09-19 12:52	25.37	OK
13099	2026-09-19 12:53	25.72	OK	13100	2026-09-19 12:54	24.13	OK
13101	2026-09-19 12:55	24.65	OK	13102	2026-09-19 12:56	23.97	OK
13103	2026-09-19 12:57	25.95	OK	13104	2026-09-19 12:58	26.56	OK
13105	2026-09-19 12:59	26.99	OK	13106	2026-09-19 13:00	25.55	OK
13107	2026-09-19 13:01	24.49	OK	13108	2026-09-19 13:02	25.12	OK
13109	2026-09-19 13:03	26.52	OK	13110	2026-09-19 13:04	26.74	OK
13111	2026-09-19 13:05	26.47	OK	13112	2026-09-19 13:06	27.19	OK
13113	2026-09-19 13:07	26.18	OK	13114	2026-09-19 13:08	24.77	OK
13115	2026-09-19 13:09	26.28	OK	13116	2026-09-19 13:10	25.53	OK
13117	2026-09-19 13:11	26.21	OK	13118	2026-09-19 13:12	25.16	OK
13119	2026-09-19 13:13	26.91	OK	13120	2026-09-19 13:14	26.65	OK
13121	2026-09-19 13:15	27.12	OK	13122	2026-09-19 13:16	26.69	OK
13123	2026-09-19 13:17	26.70	OK	13124	2026-09-19 13:18	25.29	OK
13125	2026-09-19 13:19	25.00	OK	13126	2026-09-19 13:20	27.17	OK
13127	2026-09-19 13:21	25.66	OK	13128	2026-09-19 13:22	25.56	OK
13129	2026-09-19 13:23	27.54	OK	13130	2026-09-19 13:24	25.03	OK
13131	2026-09-19 13:25	26.27	OK	13132	2026-09-19 13:26	26.00	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13133	2026-09-19 13:27	24.03	OK	13134	2026-09-19 13:28	26.45	OK
13135	2026-09-19 13:29	25.58	OK	13136	2026-09-19 13:30	24.08	OK
13137	2026-09-19 13:31	25.37	OK	13138	2026-09-19 13:32	26.54	OK
13139	2026-09-19 13:33	25.00	OK	13140	2026-09-19 13:34	26.11	OK
13141	2026-09-19 13:35	26.88	OK	13142	2026-09-19 13:36	25.01	OK
13143	2026-09-19 13:37	25.43	OK	13144	2026-09-19 13:38	26.38	OK
13145	2026-09-19 13:39	24.50	OK	13146	2026-09-19 13:40	26.12	OK
13147	2026-09-19 13:41	26.05	OK	13148	2026-09-19 13:42	24.84	OK
13149	2026-09-19 13:43	26.41	OK	13150	2026-09-19 13:44	24.95	OK
13151	2026-09-19 13:45	25.03	OK	13152	2026-09-19 13:46	24.64	OK
13153	2026-09-19 13:47	24.92	OK	13154	2026-09-19 13:48	25.62	OK
13155	2026-09-19 13:49	27.14	OK	13156	2026-09-19 13:50	27.00	OK
13157	2026-09-19 13:51	26.96	OK	13158	2026-09-19 13:52	25.70	OK
13159	2026-09-19 13:53	25.71	OK	13160	2026-09-19 13:54	25.53	OK
13161	2026-09-19 13:55	25.78	OK	13162	2026-09-19 13:56	26.28	OK
13163	2026-09-19 13:57	25.06	OK	13164	2026-09-19 13:58	25.58	OK
13165	2026-09-19 13:59	24.33	OK	13166	2026-09-19 14:00	25.32	OK
13167	2026-09-19 14:01	25.46	OK	13168	2026-09-19 14:02	26.93	OK
13169	2026-09-19 14:03	26.92	OK	13170	2026-09-19 14:04	26.24	OK
13171	2026-09-19 14:05	24.78	OK	13172	2026-09-19 14:06	26.45	OK
13173	2026-09-19 14:07	26.75	OK	13174	2026-09-19 14:08	26.03	OK
13175	2026-09-19 14:09	26.03	OK	13176	2026-09-19 14:10	25.86	OK
13177	2026-09-19 14:11	25.91	OK	13178	2026-09-19 14:12	25.37	OK
13179	2026-09-19 14:13	26.45	OK	13180	2026-09-19 14:14	25.26	OK
13181	2026-09-19 14:15	25.86	OK	13182	2026-09-19 14:16	25.65	OK
13183	2026-09-19 14:17	26.07	OK	13184	2026-09-19 14:18	25.18	OK
13185	2026-09-19 14:19	26.17	OK	13186	2026-09-19 14:20	25.22	OK
13187	2026-09-19 14:21	26.06	OK	13188	2026-09-19 14:22	27.79	OK
13189	2026-09-19 14:23	26.35	OK	13190	2026-09-19 14:24	26.36	OK
13191	2026-09-19 14:25	26.30	OK	13192	2026-09-19 14:26	25.19	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13193	2026-09-19 14:27	26.03	OK	13194	2026-09-19 14:28	27.00	OK
13195	2026-09-19 14:29	26.16	OK	13196	2026-09-19 14:30	24.79	OK
13197	2026-09-19 14:31	25.92	OK	13198	2026-09-19 14:32	26.86	OK
13199	2026-09-19 14:33	25.32	OK	13200	2026-09-19 14:34	27.18	OK
13201	2026-09-19 14:35	24.75	OK	13202	2026-09-19 14:36	24.93	OK
13203	2026-09-19 14:37	26.74	OK	13204	2026-09-19 14:38	26.48	OK
13205	2026-09-19 14:39	25.43	OK	13206	2026-09-19 14:40	26.92	OK
13207	2026-09-19 14:41	25.70	OK	13208	2026-09-19 14:42	24.76	OK
13209	2026-09-19 14:43	25.04	OK	13210	2026-09-19 14:44	26.07	OK
13211	2026-09-19 14:45	26.45	OK	13212	2026-09-19 14:46	25.44	OK
13213	2026-09-19 14:47	26.73	OK	13214	2026-09-19 14:48	25.63	OK
13215	2026-09-19 14:49	26.88	OK	13216	2026-09-19 14:50	25.17	OK
13217	2026-09-19 14:51	25.43	OK	13218	2026-09-19 14:52	25.24	OK
13219	2026-09-19 14:53	26.90	OK	13220	2026-09-19 14:54	24.63	OK
13221	2026-09-19 14:55	25.28	OK	13222	2026-09-19 14:56	26.65	OK
13223	2026-09-19 14:57	26.11	OK	13224	2026-09-19 14:58	26.79	OK
13225	2026-09-19 14:59	26.64	OK	13226	2026-09-19 15:00	25.39	OK
13227	2026-09-19 15:01	26.51	OK	13228	2026-09-19 15:02	25.27	OK
13229	2026-09-19 15:03	24.82	OK	13230	2026-09-19 15:04	24.72	OK
13231	2026-09-19 15:05	27.29	OK	13232	2026-09-19 15:06	26.28	OK
13233	2026-09-19 15:07	25.99	OK	13234	2026-09-19 15:08	25.13	OK
13235	2026-09-19 15:09	27.79	OK	13236	2026-09-19 15:10	25.35	OK
13237	2026-09-19 15:11	25.31	OK	13238	2026-09-19 15:12	25.43	OK
13239	2026-09-19 15:13	24.88	OK	13240	2026-09-19 15:14	26.50	OK
13241	2026-09-19 15:15	26.23	OK	13242	2026-09-19 15:16	26.11	OK
13243	2026-09-19 15:17	26.54	OK	13244	2026-09-19 15:18	25.43	OK
13245	2026-09-19 15:19	27.63	OK	13246	2026-09-19 15:20	27.65	OK
13247	2026-09-19 15:21	26.97	OK	13248	2026-09-19 15:22	26.78	OK
13249	2026-09-19 15:23	25.92	OK	13250	2026-09-19 15:24	26.83	OK
13251	2026-09-19 15:25	24.34	OK	13252	2026-09-19 15:26	26.01	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13253	2026-09-19 15:27	25.76	OK	13254	2026-09-19 15:28	26.24	OK
13255	2026-09-19 15:29	26.87	OK	13256	2026-09-19 15:30	26.71	OK
13257	2026-09-19 15:31	25.55	OK	13258	2026-09-19 15:32	25.95	OK
13259	2026-09-19 15:33	25.84	OK	13260	2026-09-19 15:34	26.86	OK
13261	2026-09-19 15:35	25.48	OK	13262	2026-09-19 15:36	26.84	OK
13263	2026-09-19 15:37	26.34	OK	13264	2026-09-19 15:38	25.72	OK
13265	2026-09-19 15:39	25.73	OK	13266	2026-09-19 15:40	25.43	OK
13267	2026-09-19 15:41	26.68	OK	13268	2026-09-19 15:42	24.98	OK
13269	2026-09-19 15:43	25.77	OK	13270	2026-09-19 15:44	26.78	OK
13271	2026-09-19 15:45	26.76	OK	13272	2026-09-19 15:46	26.65	OK
13273	2026-09-19 15:47	24.99	OK	13274	2026-09-19 15:48	27.11	OK
13275	2026-09-19 15:49	27.61	OK	13276	2026-09-19 15:50	26.99	OK
13277	2026-09-19 15:51	26.67	OK	13278	2026-09-19 15:52	26.93	OK
13279	2026-09-19 15:53	26.21	OK	13280	2026-09-19 15:54	26.84	OK
13281	2026-09-19 15:55	27.38	OK	13282	2026-09-19 15:56	26.11	OK
13283	2026-09-19 15:57	27.20	OK	13284	2026-09-19 15:58	26.29	OK
13285	2026-09-19 15:59	27.26	OK	13286	2026-09-19 16:00	27.19	OK
13287	2026-09-19 16:01	27.14	OK	13288	2026-09-19 16:02	26.03	OK
13289	2026-09-19 16:03	25.36	OK	13290	2026-09-19 16:04	25.44	OK
13291	2026-09-19 16:05	25.57	OK	13292	2026-09-19 16:06	26.54	OK
13293	2026-09-19 16:07	25.84	OK	13294	2026-09-19 16:08	25.04	OK
13295	2026-09-19 16:09	25.97	OK	13296	2026-09-19 16:10	26.09	OK
13297	2026-09-19 16:11	25.14	OK	13298	2026-09-19 16:12	27.57	OK
13299	2026-09-19 16:13	26.27	OK	13300	2026-09-19 16:14	25.01	OK
13301	2026-09-19 16:15	27.29	OK	13302	2026-09-19 16:16	25.56	OK
13303	2026-09-19 16:17	27.13	OK	13304	2026-09-19 16:18	26.26	OK
13305	2026-09-19 16:19	25.66	OK	13306	2026-09-19 16:20	25.89	OK
13307	2026-09-19 16:21	28.09	OK	13308	2026-09-19 16:22	24.98	OK
13309	2026-09-19 16:23	26.09	OK	13310	2026-09-19 16:24	26.26	OK
13311	2026-09-19 16:25	26.87	OK	13312	2026-09-19 16:26	27.24	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13313	2026-09-19 16:27	26.21	OK	13314	2026-09-19 16:28	25.61	OK
13315	2026-09-19 16:29	25.45	OK	13316	2026-09-19 16:30	24.57	OK
13317	2026-09-19 16:31	24.91	OK	13318	2026-09-19 16:32	26.46	OK
13319	2026-09-19 16:33	26.58	OK	13320	2026-09-19 16:34	26.33	OK
13321	2026-09-19 16:35	26.28	OK	13322	2026-09-19 16:36	27.09	OK
13323	2026-09-19 16:37	25.17	OK	13324	2026-09-19 16:38	26.68	OK
13325	2026-09-19 16:39	25.43	OK	13326	2026-09-19 16:40	26.60	OK
13327	2026-09-19 16:41	25.95	OK	13328	2026-09-19 16:42	26.19	OK
13329	2026-09-19 16:43	26.26	OK	13330	2026-09-19 16:44	26.00	OK
13331	2026-09-19 16:45	26.59	OK	13332	2026-09-19 16:46	25.71	OK
13333	2026-09-19 16:47	27.97	OK	13334	2026-09-19 16:48	26.31	OK
13335	2026-09-19 16:49	26.20	OK	13336	2026-09-19 16:50	26.49	OK
13337	2026-09-19 16:51	26.08	OK	13338	2026-09-19 16:52	25.57	OK
13339	2026-09-19 16:53	26.87	OK	13340	2026-09-19 16:54	26.29	OK
13341	2026-09-19 16:55	26.28	OK	13342	2026-09-19 16:56	26.40	OK
13343	2026-09-19 16:57	25.66	OK	13344	2026-09-19 16:58	25.89	OK
13345	2026-09-19 16:59	26.62	OK	13346	2026-09-19 17:00	25.98	OK
13347	2026-09-19 17:01	26.03	OK	13348	2026-09-19 17:02	26.69	OK
13349	2026-09-19 17:03	28.37	OK	13350	2026-09-19 17:04	27.06	OK
13351	2026-09-19 17:05	27.10	OK	13352	2026-09-19 17:06	26.60	OK
13353	2026-09-19 17:07	26.72	OK	13354	2026-09-19 17:08	26.86	OK
13355	2026-09-19 17:09	26.61	OK	13356	2026-09-19 17:10	25.39	OK
13357	2026-09-19 17:11	26.55	OK	13358	2026-09-19 17:12	26.04	OK
13359	2026-09-19 17:13	26.28	OK	13360	2026-09-19 17:14	26.89	OK
13361	2026-09-19 17:15	27.48	OK	13362	2026-09-19 17:16	26.81	OK
13363	2026-09-19 17:17	25.84	OK	13364	2026-09-19 17:18	25.44	OK
13365	2026-09-19 17:19	27.40	OK	13366	2026-09-19 17:20	27.20	OK
13367	2026-09-19 17:21	26.05	OK	13368	2026-09-19 17:22	27.92	OK
13369	2026-09-19 17:23	26.67	OK	13370	2026-09-19 17:24	26.00	OK
13371	2026-09-19 17:25	25.88	OK	13372	2026-09-19 17:26	27.74	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13373	2026-09-19 17:27	26.23	OK	13374	2026-09-19 17:28	25.88	OK
13375	2026-09-19 17:29	27.50	OK	13376	2026-09-19 17:30	27.16	OK
13377	2026-09-19 17:31	26.87	OK	13378	2026-09-19 17:32	28.11	OK
13379	2026-09-19 17:33	26.84	OK	13380	2026-09-19 17:34	28.65	OK
13381	2026-09-19 17:35	27.51	OK	13382	2026-09-19 17:36	26.65	OK
13383	2026-09-19 17:37	26.23	OK	13384	2026-09-19 17:38	25.78	OK
13385	2026-09-19 17:39	27.63	OK	13386	2026-09-19 17:40	27.76	OK
13387	2026-09-19 17:41	26.94	OK	13388	2026-09-19 17:42	25.76	OK
13389	2026-09-19 17:43	26.41	OK	13390	2026-09-19 17:44	25.77	OK
13391	2026-09-19 17:45	25.77	OK	13392	2026-09-19 17:46	25.47	OK
13393	2026-09-19 17:47	28.21	OK	13394	2026-09-19 17:48	27.45	OK
13395	2026-09-19 17:49	25.26	OK	13396	2026-09-19 17:50	25.83	OK
13397	2026-09-19 17:51	26.83	OK	13398	2026-09-19 17:52	26.51	OK
13399	2026-09-19 17:53	27.34	OK	13400	2026-09-19 17:54	28.72	OK
13401	2026-09-19 17:55	27.97	OK	13402	2026-09-19 17:56	27.16	OK
13403	2026-09-19 17:57	27.31	OK	13404	2026-09-19 17:58	26.58	OK
13405	2026-09-19 17:59	27.13	OK	13406	2026-09-19 18:00	27.85	OK
13407	2026-09-19 18:01	28.03	OK	13408	2026-09-19 18:02	27.08	OK
13409	2026-09-19 18:03	26.39	OK	13410	2026-09-19 18:04	27.44	OK
13411	2026-09-19 18:05	26.67	OK	13412	2026-09-19 18:06	26.73	OK
13413	2026-09-19 18:07	27.34	OK	13414	2026-09-19 18:08	27.12	OK
13415	2026-09-19 18:09	27.25	OK	13416	2026-09-19 18:10	27.03	OK
13417	2026-09-19 18:11	26.75	OK	13418	2026-09-19 18:12	26.29	OK
13419	2026-09-19 18:13	26.24	OK	13420	2026-09-19 18:14	27.17	OK
13421	2026-09-19 18:15	28.11	OK	13422	2026-09-19 18:16	25.99	OK
13423	2026-09-19 18:17	27.23	OK	13424	2026-09-19 18:18	28.40	OK
13425	2026-09-19 18:19	26.37	OK	13426	2026-09-19 18:20	26.61	OK
13427	2026-09-19 18:21	28.69	OK	13428	2026-09-19 18:22	26.80	OK
13429	2026-09-19 18:23	27.73	OK	13430	2026-09-19 18:24	26.70	OK
13431	2026-09-19 18:25	27.46	OK	13432	2026-09-19 18:26	26.69	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13433	2026-09-19 18:27	28.14	OK	13434	2026-09-19 18:28	26.49	OK
13435	2026-09-19 18:29	27.38	OK	13436	2026-09-19 18:30	27.04	OK
13437	2026-09-19 18:31	27.82	OK	13438	2026-09-19 18:32	27.63	OK
13439	2026-09-19 18:33	28.35	OK	13440	2026-09-19 18:34	27.00	OK
13441	2026-09-19 18:35	28.36	OK	13442	2026-09-19 18:36	25.70	OK
13443	2026-09-19 18:37	28.30	OK	13444	2026-09-19 18:38	29.05	OK
13445	2026-09-19 18:39	27.15	OK	13446	2026-09-19 18:40	28.43	OK
13447	2026-09-19 18:41	27.92	OK	13448	2026-09-19 18:42	27.37	OK
13449	2026-09-19 18:43	26.76	OK	13450	2026-09-19 18:44	28.35	OK
13451	2026-09-19 18:45	28.17	OK	13452	2026-09-19 18:46	28.21	OK
13453	2026-09-19 18:47	27.67	OK	13454	2026-09-19 18:48	28.46	OK
13455	2026-09-19 18:49	28.21	OK	13456	2026-09-19 18:50	27.36	OK
13457	2026-09-19 18:51	27.05	OK	13458	2026-09-19 18:52	27.87	OK
13459	2026-09-19 18:53	27.28	OK	13460	2026-09-19 18:54	28.91	OK
13461	2026-09-19 18:55	27.79	OK	13462	2026-09-19 18:56	27.62	OK
13463	2026-09-19 18:57	28.23	OK	13464	2026-09-19 18:58	27.03	OK
13465	2026-09-19 18:59	26.78	OK	13466	2026-09-19 19:00	27.63	OK
13467	2026-09-19 19:01	26.69	OK	13468	2026-09-19 19:02	28.04	OK
13469	2026-09-19 19:03	26.99	OK	13470	2026-09-19 19:04	27.64	OK
13471	2026-09-19 19:05	28.32	OK	13472	2026-09-19 19:06	26.66	OK
13473	2026-09-19 19:07	27.53	OK	13474	2026-09-19 19:08	27.01	OK
13475	2026-09-19 19:09	28.11	OK	13476	2026-09-19 19:10	27.97	OK
13477	2026-09-19 19:11	28.77	OK	13478	2026-09-19 19:12	28.24	OK
13479	2026-09-19 19:13	28.44	OK	13480	2026-09-19 19:14	26.81	OK
13481	2026-09-19 19:15	28.00	OK	13482	2026-09-19 19:16	28.42	OK
13483	2026-09-19 19:17	27.84	OK	13484	2026-09-19 19:18	27.09	OK
13485	2026-09-19 19:19	28.86	OK	13486	2026-09-19 19:20	29.36	OK
13487	2026-09-19 19:21	26.74	OK	13488	2026-09-19 19:22	28.21	OK
13489	2026-09-19 19:23	27.84	OK	13490	2026-09-19 19:24	28.86	OK
13491	2026-09-19 19:25	28.37	OK	13492	2026-09-19 19:26	28.41	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13493	2026-09-19 19:27	28.34	OK	13494	2026-09-19 19:28	27.57	OK
13495	2026-09-19 19:29	27.54	OK	13496	2026-09-19 19:30	26.91	OK
13497	2026-09-19 19:31	27.19	OK	13498	2026-09-19 19:32	28.03	OK
13499	2026-09-19 19:33	26.81	OK	13500	2026-09-19 19:34	28.30	OK
13501	2026-09-19 19:35	28.37	OK	13502	2026-09-19 19:36	27.00	OK
13503	2026-09-19 19:37	28.04	OK	13504	2026-09-19 19:38	27.76	OK
13505	2026-09-19 19:39	28.02	OK	13506	2026-09-19 19:40	28.74	OK
13507	2026-09-19 19:41	28.49	OK	13508	2026-09-19 19:42	26.88	OK
13509	2026-09-19 19:43	26.99	OK	13510	2026-09-19 19:44	29.17	OK
13511	2026-09-19 19:45	27.83	OK	13512	2026-09-19 19:46	28.89	OK
13513	2026-09-19 19:47	27.19	OK	13514	2026-09-19 19:48	28.55	OK
13515	2026-09-19 19:49	28.05	OK	13516	2026-09-19 19:50	29.05	OK
13517	2026-09-19 19:51	28.01	OK	13518	2026-09-19 19:52	27.39	OK
13519	2026-09-19 19:53	27.86	OK	13520	2026-09-19 19:54	28.54	OK
13521	2026-09-19 19:55	26.81	OK	13522	2026-09-19 19:56	28.50	OK
13523	2026-09-19 19:57	28.83	OK	13524	2026-09-19 19:58	27.63	OK
13525	2026-09-19 19:59	29.17	OK	13526	2026-09-19 20:00	29.17	OK
13527	2026-09-19 20:01	27.37	OK	13528	2026-09-19 20:02	27.53	OK
13529	2026-09-19 20:03	28.55	OK	13530	2026-09-19 20:04	28.06	OK
13531	2026-09-19 20:05	29.35	OK	13532	2026-09-19 20:06	28.16	OK
13533	2026-09-19 20:07	28.83	OK	13534	2026-09-19 20:08	26.82	OK
13535	2026-09-19 20:09	27.56	OK	13536	2026-09-19 20:10	29.54	OK
13537	2026-09-19 20:11	28.18	OK	13538	2026-09-19 20:12	27.42	OK
13539	2026-09-19 20:13	28.56	OK	13540	2026-09-19 20:14	29.29	OK
13541	2026-09-19 20:15	29.03	OK	13542	2026-09-19 20:16	29.92	OK
13543	2026-09-19 20:17	29.05	OK	13544	2026-09-19 20:18	28.36	OK
13545	2026-09-19 20:19	28.52	OK	13546	2026-09-19 20:20	26.77	OK
13547	2026-09-19 20:21	27.60	OK	13548	2026-09-19 20:22	27.68	OK
13549	2026-09-19 20:23	27.95	OK	13550	2026-09-19 20:24	29.34	OK
13551	2026-09-19 20:25	28.66	OK	13552	2026-09-19 20:26	29.55	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13553	2026-09-19 20:27	28.07	OK	13554	2026-09-19 20:28	28.06	OK
13555	2026-09-19 20:29	26.95	OK	13556	2026-09-19 20:30	28.77	OK
13557	2026-09-19 20:31	28.59	OK	13558	2026-09-19 20:32	30.54	OK
13559	2026-09-19 20:33	30.07	OK	13560	2026-09-19 20:34	28.05	OK
13561	2026-09-19 20:35	29.04	OK	13562	2026-09-19 20:36	27.68	OK
13563	2026-09-19 20:37	28.82	OK	13564	2026-09-19 20:38	28.05	OK
13565	2026-09-19 20:39	28.35	OK	13566	2026-09-19 20:40	28.36	OK
13567	2026-09-19 20:41	27.49	OK	13568	2026-09-19 20:42	28.37	OK
13569	2026-09-19 20:43	28.06	OK	13570	2026-09-19 20:44	29.48	OK
13571	2026-09-19 20:45	28.03	OK	13572	2026-09-19 20:46	27.93	OK
13573	2026-09-19 20:47	28.75	OK	13574	2026-09-19 20:48	26.87	OK
13575	2026-09-19 20:49	28.82	OK	13576	2026-09-19 20:50	27.31	OK
13577	2026-09-19 20:51	29.41	OK	13578	2026-09-19 20:52	28.26	OK
13579	2026-09-19 20:53	28.43	OK	13580	2026-09-19 20:54	28.06	OK
13581	2026-09-19 20:55	28.73	OK	13582	2026-09-19 20:56	30.08	OK
13583	2026-09-19 20:57	30.43	OK	13584	2026-09-19 20:58	28.51	OK
13585	2026-09-19 20:59	28.95	OK	13586	2026-09-19 21:00	28.53	OK
13587	2026-09-19 21:01	27.35	OK	13588	2026-09-19 21:02	28.13	OK
13589	2026-09-19 21:03	28.22	OK	13590	2026-09-19 21:04	28.84	OK
13591	2026-09-19 21:05	30.47	OK	13592	2026-09-19 21:06	28.95	OK
13593	2026-09-19 21:07	27.76	OK	13594	2026-09-19 21:08	28.22	OK
13595	2026-09-19 21:09	28.14	OK	13596	2026-09-19 21:10	28.54	OK
13597	2026-09-19 21:11	29.73	OK	13598	2026-09-19 21:12	29.32	OK
13599	2026-09-19 21:13	29.24	OK	13600	2026-09-19 21:14	28.66	OK
13601	2026-09-19 21:15	30.12	OK	13602	2026-09-19 21:16	27.14	OK
13603	2026-09-19 21:17	29.82	OK	13604	2026-09-19 21:18	28.56	OK
13605	2026-09-19 21:19	28.27	OK	13606	2026-09-19 21:20	29.79	OK
13607	2026-09-19 21:21	29.89	OK	13608	2026-09-19 21:22	28.76	OK
13609	2026-09-19 21:23	29.88	OK	13610	2026-09-19 21:24	30.12	OK
13611	2026-09-19 21:25	28.52	OK	13612	2026-09-19 21:26	28.79	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13613	2026-09-19 21:27	29.35	OK	13614	2026-09-19 21:28	29.74	OK
13615	2026-09-19 21:29	27.67	OK	13616	2026-09-19 21:30	29.48	OK
13617	2026-09-19 21:31	30.53	OK	13618	2026-09-19 21:32	28.32	OK
13619	2026-09-19 21:33	29.45	OK	13620	2026-09-19 21:34	27.97	OK
13621	2026-09-19 21:35	28.35	OK	13622	2026-09-19 21:36	29.86	OK
13623	2026-09-19 21:37	30.60	OK	13624	2026-09-19 21:38	30.59	OK
13625	2026-09-19 21:39	28.23	OK	13626	2026-09-19 21:40	29.26	OK
13627	2026-09-19 21:41	28.97	OK	13628	2026-09-19 21:42	27.56	OK
13629	2026-09-19 21:43	28.19	OK	13630	2026-09-19 21:44	28.74	OK
13631	2026-09-19 21:45	28.83	OK	13632	2026-09-19 21:46	29.02	OK
13633	2026-09-19 21:47	28.66	OK	13634	2026-09-19 21:48	29.01	OK
13635	2026-09-19 21:49	28.71	OK	13636	2026-09-19 21:50	29.37	OK
13637	2026-09-19 21:51	29.42	OK	13638	2026-09-19 21:52	29.71	OK
13639	2026-09-19 21:53	29.55	OK	13640	2026-09-19 21:54	30.17	OK
13641	2026-09-19 21:55	28.33	OK	13642	2026-09-19 21:56	29.20	OK
13643	2026-09-19 21:57	28.73	OK	13644	2026-09-19 21:58	28.92	OK
13645	2026-09-19 21:59	28.26	OK	13646	2026-09-19 22:00	30.60	OK
13647	2026-09-19 22:01	29.65	OK	13648	2026-09-19 22:02	29.70	OK
13649	2026-09-19 22:03	29.89	OK	13650	2026-09-19 22:04	29.31	OK
13651	2026-09-19 22:05	29.10	OK	13652	2026-09-19 22:06	30.08	OK
13653	2026-09-19 22:07	30.42	OK	13654	2026-09-19 22:08	29.49	OK
13655	2026-09-19 22:09	30.06	OK	13656	2026-09-19 22:10	29.30	OK
13657	2026-09-19 22:11	30.22	OK	13658	2026-09-19 22:12	29.67	OK
13659	2026-09-19 22:13	29.35	OK	13660	2026-09-19 22:14	28.50	OK
13661	2026-09-19 22:15	29.53	OK	13662	2026-09-19 22:16	30.25	OK
13663	2026-09-19 22:17	29.82	OK	13664	2026-09-19 22:18	28.94	OK
13665	2026-09-19 22:19	29.31	OK	13666	2026-09-19 22:20	28.88	OK
13667	2026-09-19 22:21	29.51	OK	13668	2026-09-19 22:22	30.12	OK
13669	2026-09-19 22:23	31.07	OK	13670	2026-09-19 22:24	30.03	OK
13671	2026-09-19 22:25	29.15	OK	13672	2026-09-19 22:26	29.07	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13673	2026-09-19 22:27	29.95	OK	13674	2026-09-19 22:28	28.22	OK
13675	2026-09-19 22:29	30.05	OK	13676	2026-09-19 22:30	28.94	OK
13677	2026-09-19 22:31	28.89	OK	13678	2026-09-19 22:32	29.07	OK
13679	2026-09-19 22:33	30.19	OK	13680	2026-09-19 22:34	30.68	OK
13681	2026-09-19 22:35	29.58	OK	13682	2026-09-19 22:36	30.00	OK
13683	2026-09-19 22:37	29.91	OK	13684	2026-09-19 22:38	29.35	OK
13685	2026-09-19 22:39	29.18	OK	13686	2026-09-19 22:40	30.18	OK
13687	2026-09-19 22:41	30.20	OK	13688	2026-09-19 22:42	28.97	OK
13689	2026-09-19 22:43	29.82	OK	13690	2026-09-19 22:44	30.62	OK
13691	2026-09-19 22:45	29.49	OK	13692	2026-09-19 22:46	28.03	OK
13693	2026-09-19 22:47	29.38	OK	13694	2026-09-19 22:48	30.35	OK
13695	2026-09-19 22:49	28.16	OK	13696	2026-09-19 22:50	29.91	OK
13697	2026-09-19 22:51	28.62	OK	13698	2026-09-19 22:52	29.43	OK
13699	2026-09-19 22:53	29.25	OK	13700	2026-09-19 22:54	29.89	OK
13701	2026-09-19 22:55	29.03	OK	13702	2026-09-19 22:56	29.28	OK
13703	2026-09-19 22:57	28.94	OK	13704	2026-09-19 22:58	30.22	OK
13705	2026-09-19 22:59	30.53	OK	13706	2026-09-19 23:00	29.37	OK
13707	2026-09-19 23:01	29.35	OK	13708	2026-09-19 23:02	30.43	OK
13709	2026-09-19 23:03	28.18	OK	13710	2026-09-19 23:04	29.57	OK
13711	2026-09-19 23:05	30.39	OK	13712	2026-09-19 23:06	29.83	OK
13713	2026-09-19 23:07	29.89	OK	13714	2026-09-19 23:08	29.32	OK
13715	2026-09-19 23:09	29.75	OK	13716	2026-09-19 23:10	29.79	OK
13717	2026-09-19 23:11	29.79	OK	13718	2026-09-19 23:12	28.99	OK
13719	2026-09-19 23:13	30.82	OK	13720	2026-09-19 23:14	30.31	OK
13721	2026-09-19 23:15	29.31	OK	13722	2026-09-19 23:16	30.71	OK
13723	2026-09-19 23:17	27.96	OK	13724	2026-09-19 23:18	29.96	OK
13725	2026-09-19 23:19	30.95	OK	13726	2026-09-19 23:20	30.36	OK
13727	2026-09-19 23:21	29.83	OK	13728	2026-09-19 23:22	29.45	OK
13729	2026-09-19 23:23	29.62	OK	13730	2026-09-19 23:24	29.63	OK
13731	2026-09-19 23:25	29.33	OK	13732	2026-09-19 23:26	29.96	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13733	2026-09-19 23:27	28.67	OK	13734	2026-09-19 23:28	30.77	OK
13735	2026-09-19 23:29	29.03	OK	13736	2026-09-19 23:30	28.05	OK
13737	2026-09-19 23:31	29.77	OK	13738	2026-09-19 23:32	29.22	OK
13739	2026-09-19 23:33	28.53	OK	13740	2026-09-19 23:34	30.67	OK
13741	2026-09-19 23:35	29.96	OK	13742	2026-09-19 23:36	28.35	OK
13743	2026-09-19 23:37	30.56	OK	13744	2026-09-19 23:38	29.69	OK
13745	2026-09-19 23:39	31.00	OK	13746	2026-09-19 23:40	30.67	OK
13747	2026-09-19 23:41	28.92	OK	13748	2026-09-19 23:42	31.27	OK
13749	2026-09-19 23:43	30.95	OK	13750	2026-09-19 23:44	31.13	OK
13751	2026-09-19 23:45	29.87	OK	13752	2026-09-19 23:46	30.41	OK
13753	2026-09-19 23:47	29.67	OK	13754	2026-09-19 23:48	29.82	OK
13755	2026-09-19 23:49	30.27	OK	13756	2026-09-19 23:50	29.36	OK
13757	2026-09-19 23:51	29.32	OK	13758	2026-09-19 23:52	30.95	OK
13759	2026-09-19 23:53	29.85	OK	13760	2026-09-19 23:54	29.55	OK
13761	2026-09-19 23:55	30.20	OK	13762	2026-09-19 23:56	31.07	OK
13763	2026-09-19 23:57	29.49	OK	13764	2026-09-19 23:58	31.69	OK
13765	2026-09-19 23:59	28.93	OK	13766	2026-09-20 00:00	30.12	OK
13767	2026-09-20 00:01	29.91	OK	13768	2026-09-20 00:02	29.47	OK
13769	2026-09-20 00:03	29.65	OK	13770	2026-09-20 00:04	31.37	OK
13771	2026-09-20 00:05	30.47	OK	13772	2026-09-20 00:06	29.39	OK
13773	2026-09-20 00:07	30.78	OK	13774	2026-09-20 00:08	31.28	OK
13775	2026-09-20 00:09	30.62	OK	13776	2026-09-20 00:10	29.95	OK
13777	2026-09-20 00:11	31.36	OK	13778	2026-09-20 00:12	29.47	OK
13779	2026-09-20 00:13	30.38	OK	13780	2026-09-20 00:14	29.82	OK
13781	2026-09-20 00:15	29.83	OK	13782	2026-09-20 00:16	30.63	OK
13783	2026-09-20 00:17	30.26	OK	13784	2026-09-20 00:18	30.21	OK
13785	2026-09-20 00:19	30.18	OK	13786	2026-09-20 00:20	29.24	OK
13787	2026-09-20 00:21	29.79	OK	13788	2026-09-20 00:22	29.24	OK
13789	2026-09-20 00:23	31.74	OK	13790	2026-09-20 00:24	30.15	OK
13791	2026-09-20 00:25	29.67	OK	13792	2026-09-20 00:26	30.33	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13793	2026-09-20 00:27	28.75	OK	13794	2026-09-20 00:28	30.66	OK
13795	2026-09-20 00:29	31.21	OK	13796	2026-09-20 00:30	30.50	OK
13797	2026-09-20 00:31	29.27	OK	13798	2026-09-20 00:32	30.01	OK
13799	2026-09-20 00:33	31.24	OK	13800	2026-09-20 00:34	29.71	OK
13801	2026-09-20 00:35	29.91	OK	13802	2026-09-20 00:36	30.41	OK
13803	2026-09-20 00:37	31.58	OK	13804	2026-09-20 00:38	30.78	OK
13805	2026-09-20 00:39	30.52	OK	13806	2026-09-20 00:40	30.25	OK
13807	2026-09-20 00:41	30.68	OK	13808	2026-09-20 00:42	29.87	OK
13809	2026-09-20 00:43	29.58	OK	13810	2026-09-20 00:44	28.89	OK
13811	2026-09-20 00:45	30.25	OK	13812	2026-09-20 00:46	30.17	OK
13813	2026-09-20 00:47	29.93	OK	13814	2026-09-20 00:48	31.07	OK
13815	2026-09-20 00:49	29.30	OK	13816	2026-09-20 00:50	29.71	OK
13817	2026-09-20 00:51	30.81	OK	13818	2026-09-20 00:52	29.23	OK
13819	2026-09-20 00:53	30.57	OK	13820	2026-09-20 00:54	30.09	OK
13821	2026-09-20 00:55	30.25	OK	13822	2026-09-20 00:56	29.97	OK
13823	2026-09-20 00:57	30.07	OK	13824	2026-09-20 00:58	29.70	OK
13825	2026-09-20 00:59	29.77	OK	13826	2026-09-20 01:00	30.52	OK
13827	2026-09-20 01:01	30.84	OK	13828	2026-09-20 01:02	29.60	OK
13829	2026-09-20 01:03	29.07	OK	13830	2026-09-20 01:04	30.23	OK
13831	2026-09-20 01:05	29.68	OK	13832	2026-09-20 01:06	30.00	OK
13833	2026-09-20 01:07	29.03	OK	13834	2026-09-20 01:08	30.06	OK
13835	2026-09-20 01:09	30.63	OK	13836	2026-09-20 01:10	29.20	OK
13837	2026-09-20 01:11	30.51	OK	13838	2026-09-20 01:12	32.00	OK
13839	2026-09-20 01:13	30.39	OK	13840	2026-09-20 01:14	30.11	OK
13841	2026-09-20 01:15	31.23	OK	13842	2026-09-20 01:16	31.26	OK
13843	2026-09-20 01:17	30.26	OK	13844	2026-09-20 01:18	30.50	OK
13845	2026-09-20 01:19	28.87	OK	13846	2026-09-20 01:20	31.50	OK
13847	2026-09-20 01:21	29.82	OK	13848	2026-09-20 01:22	30.46	OK
13849	2026-09-20 01:23	30.49	OK	13850	2026-09-20 01:24	30.57	OK
13851	2026-09-20 01:25	29.47	OK	13852	2026-09-20 01:26	31.66	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13853	2026-09-20 01:27	31.02	OK	13854	2026-09-20 01:28	29.63	OK
13855	2026-09-20 01:29	30.71	OK	13856	2026-09-20 01:30	31.36	OK
13857	2026-09-20 01:31	29.57	OK	13858	2026-09-20 01:32	30.30	OK
13859	2026-09-20 01:33	29.91	OK	13860	2026-09-20 01:34	30.27	OK
13861	2026-09-20 01:35	31.63	OK	13862	2026-09-20 01:36	30.75	OK
13863	2026-09-20 01:37	30.01	OK	13864	2026-09-20 01:38	30.12	OK
13865	2026-09-20 01:39	31.86	OK	13866	2026-09-20 01:40	30.57	OK
13867	2026-09-20 01:41	30.34	OK	13868	2026-09-20 01:42	30.89	OK
13869	2026-09-20 01:43	31.16	OK	13870	2026-09-20 01:44	29.09	OK
13871	2026-09-20 01:45	30.56	OK	13872	2026-09-20 01:46	29.93	OK
13873	2026-09-20 01:47	31.32	OK	13874	2026-09-20 01:48	28.51	OK
13875	2026-09-20 01:49	30.73	OK	13876	2026-09-20 01:50	30.19	OK
13877	2026-09-20 01:51	30.49	OK	13878	2026-09-20 01:52	31.21	OK
13879	2026-09-20 01:53	29.54	OK	13880	2026-09-20 01:54	29.54	OK
13881	2026-09-20 01:55	31.21	OK	13882	2026-09-20 01:56	30.13	OK
13883	2026-09-20 01:57	29.32	OK	13884	2026-09-20 01:58	29.78	OK
13885	2026-09-20 01:59	30.01	OK	13886	2026-09-20 02:00	28.77	OK
13887	2026-09-20 02:01	29.76	OK	13888	2026-09-20 02:02	30.80	OK
13889	2026-09-20 02:03	29.61	OK	13890	2026-09-20 02:04	29.64	OK
13891	2026-09-20 02:05	30.22	OK	13892	2026-09-20 02:06	29.94	OK
13893	2026-09-20 02:07	30.84	OK	13894	2026-09-20 02:08	30.67	OK
13895	2026-09-20 02:09	30.56	OK	13896	2026-09-20 02:10	30.25	OK
13897	2026-09-20 02:11	30.79	OK	13898	2026-09-20 02:12	28.86	OK
13899	2026-09-20 02:13	30.97	OK	13900	2026-09-20 02:14	30.80	OK
13901	2026-09-20 02:15	30.22	OK	13902	2026-09-20 02:16	30.87	OK
13903	2026-09-20 02:17	31.02	OK	13904	2026-09-20 02:18	29.49	OK
13905	2026-09-20 02:19	29.20	OK	13906	2026-09-20 02:20	30.05	OK
13907	2026-09-20 02:21	30.21	OK	13908	2026-09-20 02:22	29.52	OK
13909	2026-09-20 02:23	30.12	OK	13910	2026-09-20 02:24	31.92	OK
13911	2026-09-20 02:25	29.78	OK	13912	2026-09-20 02:26	29.46	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13913	2026-09-20 02:27	29.25	OK	13914	2026-09-20 02:28	29.42	OK
13915	2026-09-20 02:29	30.46	OK	13916	2026-09-20 02:30	29.07	OK
13917	2026-09-20 02:31	29.95	OK	13918	2026-09-20 02:32	28.76	OK
13919	2026-09-20 02:33	30.72	OK	13920	2026-09-20 02:34	30.76	OK
13921	2026-09-20 02:35	31.03	OK	13922	2026-09-20 02:36	29.89	OK
13923	2026-09-20 02:37	29.24	OK	13924	2026-09-20 02:38	30.27	OK
13925	2026-09-20 02:39	30.62	OK	13926	2026-09-20 02:40	30.74	OK
13927	2026-09-20 02:41	30.49	OK	13928	2026-09-20 02:42	30.68	OK
13929	2026-09-20 02:43	28.90	OK	13930	2026-09-20 02:44	30.99	OK
13931	2026-09-20 02:45	29.79	OK	13932	2026-09-20 02:46	30.27	OK
13933	2026-09-20 02:47	30.05	OK	13934	2026-09-20 02:48	29.37	OK
13935	2026-09-20 02:49	28.86	OK	13936	2026-09-20 02:50	29.49	OK
13937	2026-09-20 02:51	30.55	OK	13938	2026-09-20 02:52	30.16	OK
13939	2026-09-20 02:53	28.96	OK	13940	2026-09-20 02:54	31.10	OK
13941	2026-09-20 02:55	29.79	OK	13942	2026-09-20 02:56	29.45	OK
13943	2026-09-20 02:57	31.70	OK	13944	2026-09-20 02:58	29.63	OK
13945	2026-09-20 02:59	29.70	OK	13946	2026-09-20 03:00	30.06	OK
13947	2026-09-20 03:01	29.98	OK	13948	2026-09-20 03:02	30.91	OK
13949	2026-09-20 03:03	29.74	OK	13950	2026-09-20 03:04	30.64	OK
13951	2026-09-20 03:05	29.68	OK	13952	2026-09-20 03:06	29.48	OK
13953	2026-09-20 03:07	29.66	OK	13954	2026-09-20 03:08	29.22	OK
13955	2026-09-20 03:09	29.85	OK	13956	2026-09-20 03:10	31.08	OK
13957	2026-09-20 03:11	30.30	OK	13958	2026-09-20 03:12	30.57	OK
13959	2026-09-20 03:13	31.20	OK	13960	2026-09-20 03:14	29.49	OK
13961	2026-09-20 03:15	28.07	OK	13962	2026-09-20 03:16	29.92	OK
13963	2026-09-20 03:17	30.05	OK	13964	2026-09-20 03:18	30.84	OK
13965	2026-09-20 03:19	28.93	OK	13966	2026-09-20 03:20	28.25	OK
13967	2026-09-20 03:21	30.43	OK	13968	2026-09-20 03:22	30.21	OK
13969	2026-09-20 03:23	30.39	OK	13970	2026-09-20 03:24	30.24	OK
13971	2026-09-20 03:25	30.43	OK	13972	2026-09-20 03:26	30.19	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
13973	2026-09-20 03:27	29.99	OK	13974	2026-09-20 03:28	30.24	OK
13975	2026-09-20 03:29	29.53	OK	13976	2026-09-20 03:30	28.46	OK
13977	2026-09-20 03:31	30.37	OK	13978	2026-09-20 03:32	29.43	OK
13979	2026-09-20 03:33	28.18	OK	13980	2026-09-20 03:34	30.05	OK
13981	2026-09-20 03:35	30.82	OK	13982	2026-09-20 03:36	29.75	OK
13983	2026-09-20 03:37	29.92	OK	13984	2026-09-20 03:38	30.62	OK
13985	2026-09-20 03:39	29.18	OK	13986	2026-09-20 03:40	29.95	OK
13987	2026-09-20 03:41	28.59	OK	13988	2026-09-20 03:42	29.76	OK
13989	2026-09-20 03:43	28.70	OK	13990	2026-09-20 03:44	29.74	OK
13991	2026-09-20 03:45	28.73	OK	13992	2026-09-20 03:46	29.25	OK
13993	2026-09-20 03:47	30.14	OK	13994	2026-09-20 03:48	29.48	OK
13995	2026-09-20 03:49	30.62	OK	13996	2026-09-20 03:50	29.74	OK
13997	2026-09-20 03:51	28.68	OK	13998	2026-09-20 03:52	29.89	OK
13999	2026-09-20 03:53	30.03	OK	14000	2026-09-20 03:54	31.28	OK
14001	2026-09-20 03:55	31.02	OK	14002	2026-09-20 03:56	31.15	OK
14003	2026-09-20 03:57	29.67	OK	14004	2026-09-20 03:58	30.17	OK
14005	2026-09-20 03:59	29.25	OK	14006	2026-09-20 04:00	31.11	OK
14007	2026-09-20 04:01	28.00	OK	14008	2026-09-20 04:02	29.30	OK
14009	2026-09-20 04:03	29.96	OK	14010	2026-09-20 04:04	30.22	OK
14011	2026-09-20 04:05	30.66	OK	14012	2026-09-20 04:06	29.85	OK
14013	2026-09-20 04:07	28.84	OK	14014	2026-09-20 04:08	29.57	OK
14015	2026-09-20 04:09	29.57	OK	14016	2026-09-20 04:10	28.31	OK
14017	2026-09-20 04:11	30.95	OK	14018	2026-09-20 04:12	30.04	OK
14019	2026-09-20 04:13	29.26	OK	14020	2026-09-20 04:14	29.67	OK
14021	2026-09-20 04:15	28.18	OK	14022	2026-09-20 04:16	29.79	OK
14023	2026-09-20 04:17	30.76	OK	14024	2026-09-20 04:18	29.61	OK
14025	2026-09-20 04:19	29.04	OK	14026	2026-09-20 04:20	30.38	OK
14027	2026-09-20 04:21	29.18	OK	14028	2026-09-20 04:22	29.79	OK
14029	2026-09-20 04:23	29.94	OK	14030	2026-09-20 04:24	29.36	OK
14031	2026-09-20 04:25	28.93	OK	14032	2026-09-20 04:26	29.44	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14033	2026-09-20 04:27	29.51	OK	14034	2026-09-20 04:28	30.72	OK
14035	2026-09-20 04:29	28.69	OK	14036	2026-09-20 04:30	29.56	OK
14037	2026-09-20 04:31	30.72	OK	14038	2026-09-20 04:32	28.10	OK
14039	2026-09-20 04:33	30.10	OK	14040	2026-09-20 04:34	30.29	OK
14041	2026-09-20 04:35	30.55	OK	14042	2026-09-20 04:36	30.58	OK
14043	2026-09-20 04:37	30.88	OK	14044	2026-09-20 04:38	29.36	OK
14045	2026-09-20 04:39	28.80	OK	14046	2026-09-20 04:40	29.86	OK
14047	2026-09-20 04:41	29.87	OK	14048	2026-09-20 04:42	28.48	OK
14049	2026-09-20 04:43	28.84	OK	14050	2026-09-20 04:44	30.37	OK
14051	2026-09-20 04:45	28.22	OK	14052	2026-09-20 04:46	30.82	OK
14053	2026-09-20 04:47	31.00	OK	14054	2026-09-20 04:48	29.80	OK
14055	2026-09-20 04:49	31.36	OK	14056	2026-09-20 04:50	29.45	OK
14057	2026-09-20 04:51	29.11	OK	14058	2026-09-20 04:52	29.97	OK
14059	2026-09-20 04:53	28.55	OK	14060	2026-09-20 04:54	29.15	OK
14061	2026-09-20 04:55	28.95	OK	14062	2026-09-20 04:56	31.03	OK
14063	2026-09-20 04:57	29.39	OK	14064	2026-09-20 04:58	28.60	OK
14065	2026-09-20 04:59	29.04	OK	14066	2026-09-20 05:00	29.67	OK
14067	2026-09-20 05:01	29.73	OK	14068	2026-09-20 05:02	30.40	OK
14069	2026-09-20 05:03	29.92	OK	14070	2026-09-20 05:04	29.07	OK
14071	2026-09-20 05:05	28.79	OK	14072	2026-09-20 05:06	31.22	OK
14073	2026-09-20 05:07	29.09	OK	14074	2026-09-20 05:08	29.64	OK
14075	2026-09-20 05:09	27.93	OK	14076	2026-09-20 05:10	28.46	OK
14077	2026-09-20 05:11	29.34	OK	14078	2026-09-20 05:12	29.70	OK
14079	2026-09-20 05:13	30.69	OK	14080	2026-09-20 05:14	29.40	OK
14081	2026-09-20 05:15	29.23	OK	14082	2026-09-20 05:16	28.45	OK
14083	2026-09-20 05:17	28.97	OK	14084	2026-09-20 05:18	29.31	OK
14085	2026-09-20 05:19	29.04	OK	14086	2026-09-20 05:20	30.00	OK
14087	2026-09-20 05:21	28.68	OK	14088	2026-09-20 05:22	28.50	OK
14089	2026-09-20 05:23	30.61	OK	14090	2026-09-20 05:24	29.77	OK
14091	2026-09-20 05:25	29.84	OK	14092	2026-09-20 05:26	27.91	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14093	2026-09-20 05:27	28.63	OK	14094	2026-09-20 05:28	28.38	OK
14095	2026-09-20 05:29	28.93	OK	14096	2026-09-20 05:30	27.93	OK
14097	2026-09-20 05:31	29.95	OK	14098	2026-09-20 05:32	27.27	OK
14099	2026-09-20 05:33	28.05	OK	14100	2026-09-20 05:34	28.00	OK
14101	2026-09-20 05:35	28.05	OK	14102	2026-09-20 05:36	28.06	OK
14103	2026-09-20 05:37	28.98	OK	14104	2026-09-20 05:38	28.81	OK
14105	2026-09-20 05:39	29.34	OK	14106	2026-09-20 05:40	28.50	OK
14107	2026-09-20 05:41	28.30	OK	14108	2026-09-20 05:42	29.34	OK
14109	2026-09-20 05:43	29.12	OK	14110	2026-09-20 05:44	29.37	OK
14111	2026-09-20 05:45	29.18	OK	14112	2026-09-20 05:46	28.48	OK
14113	2026-09-20 05:47	29.85	OK	14114	2026-09-20 05:48	28.44	OK
14115	2026-09-20 05:49	28.07	OK	14116	2026-09-20 05:50	29.38	OK
14117	2026-09-20 05:51	28.24	OK	14118	2026-09-20 05:52	28.27	OK
14119	2026-09-20 05:53	28.06	OK	14120	2026-09-20 05:54	28.27	OK
14121	2026-09-20 05:55	29.06	OK	14122	2026-09-20 05:56	28.49	OK
14123	2026-09-20 05:57	28.23	OK	14124	2026-09-20 05:58	28.49	OK
14125	2026-09-20 05:59	29.35	OK	14126	2026-09-20 06:00	29.03	OK
14127	2026-09-20 06:01	28.20	OK	14128	2026-09-20 06:02	29.07	OK
14129	2026-09-20 06:03	27.23	OK	14130	2026-09-20 06:04	29.13	OK
14131	2026-09-20 06:05	27.27	OK	14132	2026-09-20 06:06	27.19	OK
14133	2026-09-20 06:07	28.88	OK	14134	2026-09-20 06:08	28.46	OK
14135	2026-09-20 06:09	29.72	OK	14136	2026-09-20 06:10	28.31	OK
14137	2026-09-20 06:11	30.02	OK	14138	2026-09-20 06:12	29.63	OK
14139	2026-09-20 06:13	28.93	OK	14140	2026-09-20 06:14	28.58	OK
14141	2026-09-20 06:15	28.94	OK	14142	2026-09-20 06:16	29.27	OK
14143	2026-09-20 06:17	28.64	OK	14144	2026-09-20 06:18	29.93	OK
14145	2026-09-20 06:19	28.37	OK	14146	2026-09-20 06:20	28.24	OK
14147	2026-09-20 06:21	28.89	OK	14148	2026-09-20 06:22	28.84	OK
14149	2026-09-20 06:23	29.95	OK	14150	2026-09-20 06:24	27.36	OK
14151	2026-09-20 06:25	29.07	OK	14152	2026-09-20 06:26	28.15	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14153	2026-09-20 06:27	28.42	OK	14154	2026-09-20 06:28	28.54	OK
14155	2026-09-20 06:29	27.37	OK	14156	2026-09-20 06:30	29.46	OK
14157	2026-09-20 06:31	29.21	OK	14158	2026-09-20 06:32	28.00	OK
14159	2026-09-20 06:33	28.60	OK	14160	2026-09-20 06:34	29.34	OK
14161	2026-09-20 06:35	29.08	OK	14162	2026-09-20 06:36	29.89	OK
14163	2026-09-20 06:37	28.97	OK	14164	2026-09-20 06:38	28.16	OK
14165	2026-09-20 06:39	30.19	OK	14166	2026-09-20 06:40	29.27	OK
14167	2026-09-20 06:41	27.55	OK	14168	2026-09-20 06:42	29.53	OK
14169	2026-09-20 06:43	27.68	OK	14170	2026-09-20 06:44	29.81	OK
14171	2026-09-20 06:45	28.74	OK	14172	2026-09-20 06:46	27.29	OK
14173	2026-09-20 06:47	28.21	OK	14174	2026-09-20 06:48	28.39	OK
14175	2026-09-20 06:49	28.77	OK	14176	2026-09-20 06:50	26.71	OK
14177	2026-09-20 06:51	29.42	OK	14178	2026-09-20 06:52	26.95	OK
14179	2026-09-20 06:53	28.18	OK	14180	2026-09-20 06:54	28.20	OK
14181	2026-09-20 06:55	28.67	OK	14182	2026-09-20 06:56	28.00	OK
14183	2026-09-20 06:57	27.84	OK	14184	2026-09-20 06:58	26.79	OK
14185	2026-09-20 06:59	26.53	OK	14186	2026-09-20 07:00	29.27	OK
14187	2026-09-20 07:01	27.64	OK	14188	2026-09-20 07:02	28.38	OK
14189	2026-09-20 07:03	28.64	OK	14190	2026-09-20 07:04	26.56	OK
14191	2026-09-20 07:05	28.93	OK	14192	2026-09-20 07:06	28.95	OK
14193	2026-09-20 07:07	29.29	OK	14194	2026-09-20 07:08	28.79	OK
14195	2026-09-20 07:09	27.35	OK	14196	2026-09-20 07:10	29.10	OK
14197	2026-09-20 07:11	28.18	OK	14198	2026-09-20 07:12	27.59	OK
14199	2026-09-20 07:13	28.41	OK	14200	2026-09-20 07:14	26.57	OK
14201	2026-09-20 07:15	27.78	OK	14202	2026-09-20 07:16	28.20	OK
14203	2026-09-20 07:17	28.36	OK	14204	2026-09-20 07:18	29.27	OK
14205	2026-09-20 07:19	27.70	OK	14206	2026-09-20 07:20	27.01	OK
14207	2026-09-20 07:21	28.27	OK	14208	2026-09-20 07:22	27.59	OK
14209	2026-09-20 07:23	28.38	OK	14210	2026-09-20 07:24	29.27	OK
14211	2026-09-20 07:25	28.05	OK	14212	2026-09-20 07:26	26.99	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14213	2026-09-20 07:27	29.12	OK	14214	2026-09-20 07:28	28.05	OK
14215	2026-09-20 07:29	28.40	OK	14216	2026-09-20 07:30	26.47	OK
14217	2026-09-20 07:31	27.89	OK	14218	2026-09-20 07:32	29.41	OK
14219	2026-09-20 07:33	28.19	OK	14220	2026-09-20 07:34	27.62	OK
14221	2026-09-20 07:35	27.36	OK	14222	2026-09-20 07:36	27.81	OK
14223	2026-09-20 07:37	28.30	OK	14224	2026-09-20 07:38	27.17	OK
14225	2026-09-20 07:39	27.51	OK	14226	2026-09-20 07:40	27.79	OK
14227	2026-09-20 07:41	28.41	OK	14228	2026-09-20 07:42	27.37	OK
14229	2026-09-20 07:43	28.21	OK	14230	2026-09-20 07:44	28.71	OK
14231	2026-09-20 07:45	28.88	OK	14232	2026-09-20 07:46	28.37	OK
14233	2026-09-20 07:47	28.17	OK	14234	2026-09-20 07:48	27.20	OK
14235	2026-09-20 07:49	27.68	OK	14236	2026-09-20 07:50	27.12	OK
14237	2026-09-20 07:51	26.49	OK	14238	2026-09-20 07:52	27.95	OK
14239	2026-09-20 07:53	27.24	OK	14240	2026-09-20 07:54	28.36	OK
14241	2026-09-20 07:55	27.87	OK	14242	2026-09-20 07:56	27.44	OK
14243	2026-09-20 07:57	26.23	OK	14244	2026-09-20 07:58	28.23	OK
14245	2026-09-20 07:59	27.29	OK	14246	2026-09-20 08:00	27.66	OK
14247	2026-09-20 08:01	27.78	OK	14248	2026-09-20 08:02	27.82	OK
14249	2026-09-20 08:03	28.17	OK	14250	2026-09-20 08:04	27.02	OK
14251	2026-09-20 08:05	27.68	OK	14252	2026-09-20 08:06	28.08	OK
14253	2026-09-20 08:07	28.94	OK	14254	2026-09-20 08:08	26.80	OK
14255	2026-09-20 08:09	27.84	OK	14256	2026-09-20 08:10	26.80	OK
14257	2026-09-20 08:11	26.76	OK	14258	2026-09-20 08:12	26.23	OK
14259	2026-09-20 08:13	27.84	OK	14260	2026-09-20 08:14	27.16	OK
14261	2026-09-20 08:15	27.85	OK	14262	2026-09-20 08:16	26.95	OK
14263	2026-09-20 08:17	27.01	OK	14264	2026-09-20 08:18	28.09	OK
14265	2026-09-20 08:19	26.84	OK	14266	2026-09-20 08:20	27.53	OK
14267	2026-09-20 08:21	26.19	OK	14268	2026-09-20 08:22	27.57	OK
14269	2026-09-20 08:23	26.78	OK	14270	2026-09-20 08:24	27.46	OK
14271	2026-09-20 08:25	27.22	OK	14272	2026-09-20 08:26	27.26	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14273	2026-09-20 08:27	27.41	OK	14274	2026-09-20 08:28	27.74	OK
14275	2026-09-20 08:29	27.05	OK	14276	2026-09-20 08:30	28.46	OK
14277	2026-09-20 08:31	27.03	OK	14278	2026-09-20 08:32	28.12	OK
14279	2026-09-20 08:33	26.42	OK	14280	2026-09-20 08:34	28.37	OK
14281	2026-09-20 08:35	26.90	OK	14282	2026-09-20 08:36	27.53	OK
14283	2026-09-20 08:37	26.59	OK	14284	2026-09-20 08:38	26.01	OK
14285	2026-09-20 08:39	27.00	OK	14286	2026-09-20 08:40	27.75	OK
14287	2026-09-20 08:41	28.14	OK	14288	2026-09-20 08:42	27.52	OK
14289	2026-09-20 08:43	27.44	OK	14290	2026-09-20 08:44	27.26	OK
14291	2026-09-20 08:45	26.44	OK	14292	2026-09-20 08:46	27.07	OK
14293	2026-09-20 08:47	26.55	OK	14294	2026-09-20 08:48	28.21	OK
14295	2026-09-20 08:49	26.42	OK	14296	2026-09-20 08:50	26.13	OK
14297	2026-09-20 08:51	26.01	OK	14298	2026-09-20 08:52	26.38	OK
14299	2026-09-20 08:53	26.95	OK	14300	2026-09-20 08:54	27.13	OK
14301	2026-09-20 08:55	28.06	OK	14302	2026-09-20 08:56	27.63	OK
14303	2026-09-20 08:57	28.19	OK	14304	2026-09-20 08:58	27.03	OK
14305	2026-09-20 08:59	25.50	OK	14306	2026-09-20 09:00	27.01	OK
14307	2026-09-20 09:01	25.83	OK	14308	2026-09-20 09:02	26.16	OK
14309	2026-09-20 09:03	27.48	OK	14310	2026-09-20 09:04	28.42	OK
14311	2026-09-20 09:05	26.16	OK	14312	2026-09-20 09:06	28.64	OK
14313	2026-09-20 09:07	26.20	OK	14314	2026-09-20 09:08	28.00	OK
14315	2026-09-20 09:09	27.82	OK	14316	2026-09-20 09:10	26.67	OK
14317	2026-09-20 09:11	27.71	OK	14318	2026-09-20 09:12	27.89	OK
14319	2026-09-20 09:13	28.07	OK	14320	2026-09-20 09:14	26.70	OK
14321	2026-09-20 09:15	26.41	OK	14322	2026-09-20 09:16	25.91	OK
14323	2026-09-20 09:17	26.85	OK	14324	2026-09-20 09:18	25.36	OK
14325	2026-09-20 09:19	26.51	OK	14326	2026-09-20 09:20	26.35	OK
14327	2026-09-20 09:21	26.25	OK	14328	2026-09-20 09:22	26.22	OK
14329	2026-09-20 09:23	27.95	OK	14330	2026-09-20 09:24	26.01	OK
14331	2026-09-20 09:25	26.27	OK	14332	2026-09-20 09:26	28.46	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14333	2026-09-20 09:27	26.06	OK	14334	2026-09-20 09:28	26.86	OK
14335	2026-09-20 09:29	26.95	OK	14336	2026-09-20 09:30	27.47	OK
14337	2026-09-20 09:31	27.57	OK	14338	2026-09-20 09:32	25.88	OK
14339	2026-09-20 09:33	24.79	OK	14340	2026-09-20 09:34	26.09	OK
14341	2026-09-20 09:35	27.87	OK	14342	2026-09-20 09:36	27.36	OK
14343	2026-09-20 09:37	26.71	OK	14344	2026-09-20 09:38	26.95	OK
14345	2026-09-20 09:39	28.46	OK	14346	2026-09-20 09:40	26.68	OK
14347	2026-09-20 09:41	25.69	OK	14348	2026-09-20 09:42	27.55	OK
14349	2026-09-20 09:43	27.00	OK	14350	2026-09-20 09:44	26.56	OK
14351	2026-09-20 09:45	26.50	OK	14352	2026-09-20 09:46	27.62	OK
14353	2026-09-20 09:47	26.54	OK	14354	2026-09-20 09:48	26.48	OK
14355	2026-09-20 09:49	27.95	OK	14356	2026-09-20 09:50	26.23	OK
14357	2026-09-20 09:51	27.75	OK	14358	2026-09-20 09:52	28.67	OK
14359	2026-09-20 09:53	26.64	OK	14360	2026-09-20 09:54	27.47	OK
14361	2026-09-20 09:55	26.97	OK	14362	2026-09-20 09:56	26.14	OK
14363	2026-09-20 09:57	25.66	OK	14364	2026-09-20 09:58	26.87	OK
14365	2026-09-20 09:59	26.37	OK	14366	2026-09-20 10:00	26.12	OK
14367	2026-09-20 10:01	25.59	OK	14368	2026-09-20 10:02	25.74	OK
14369	2026-09-20 10:03	26.90	OK	14370	2026-09-20 10:04	27.68	OK
14371	2026-09-20 10:05	26.16	OK	14372	2026-09-20 10:06	26.54	OK
14373	2026-09-20 10:07	26.58	OK	14374	2026-09-20 10:08	26.37	OK
14375	2026-09-20 10:09	26.73	OK	14376	2026-09-20 10:10	26.64	OK
14377	2026-09-20 10:11	25.91	OK	14378	2026-09-20 10:12	26.23	OK
14379	2026-09-20 10:13	26.50	OK	14380	2026-09-20 10:14	25.01	OK
14381	2026-09-20 10:15	27.20	OK	14382	2026-09-20 10:16	25.32	OK
14383	2026-09-20 10:17	26.94	OK	14384	2026-09-20 10:18	26.81	OK
14385	2026-09-20 10:19	27.24	OK	14386	2026-09-20 10:20	26.88	OK
14387	2026-09-20 10:21	26.79	OK	14388	2026-09-20 10:22	26.88	OK
14389	2026-09-20 10:23	26.20	OK	14390	2026-09-20 10:24	25.32	OK
14391	2026-09-20 10:25	26.21	OK	14392	2026-09-20 10:26	26.42	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14393	2026-09-20 10:27	27.59	OK	14394	2026-09-20 10:28	26.95	OK
14395	2026-09-20 10:29	25.86	OK	14396	2026-09-20 10:30	26.32	OK
14397	2026-09-20 10:31	25.17	OK	14398	2026-09-20 10:32	26.96	OK
14399	2026-09-20 10:33	26.86	OK	14400	2026-09-20 10:34	24.52	OK
14401	2026-09-20 10:35	26.99	OK	14402	2026-09-20 10:36	25.85	OK
14403	2026-09-20 10:37	27.29	OK	14404	2026-09-20 10:38	25.54	OK
14405	2026-09-20 10:39	25.26	OK	14406	2026-09-20 10:40	25.05	OK
14407	2026-09-20 10:41	27.63	OK	14408	2026-09-20 10:42	25.09	OK
14409	2026-09-20 10:43	25.90	OK	14410	2026-09-20 10:44	27.63	OK
14411	2026-09-20 10:45	25.85	OK	14412	2026-09-20 10:46	25.87	OK
14413	2026-09-20 10:47	25.37	OK	14414	2026-09-20 10:48	26.80	OK
14415	2026-09-20 10:49	26.85	OK	14416	2026-09-20 10:50	24.99	OK
14417	2026-09-20 10:51	26.63	OK	14418	2026-09-20 10:52	26.59	OK
14419	2026-09-20 10:53	27.02	OK	14420	2026-09-20 10:54	26.22	OK
14421	2026-09-20 10:55	26.45	OK	14422	2026-09-20 10:56	25.53	OK
14423	2026-09-20 10:57	25.83	OK	14424	2026-09-20 10:58	26.98	OK
14425	2026-09-20 10:59	27.15	OK	14426	2026-09-20 11:00	25.50	OK
14427	2026-09-20 11:01	25.60	OK	14428	2026-09-20 11:02	27.17	OK
14429	2026-09-20 11:03	26.52	OK	14430	2026-09-20 11:04	25.74	OK
14431	2026-09-20 11:05	25.03	OK	14432	2026-09-20 11:06	25.63	OK
14433	2026-09-20 11:07	26.35	OK	14434	2026-09-20 11:08	26.05	OK
14435	2026-09-20 11:09	25.42	OK	14436	2026-09-20 11:10	27.68	OK
14437	2026-09-20 11:11	24.00	OK	14438	2026-09-20 11:12	25.49	OK
14439	2026-09-20 11:13	26.22	OK	14440	2026-09-20 11:14	25.27	OK
14441	2026-09-20 11:15	26.86	OK	14442	2026-09-20 11:16	25.77	OK
14443	2026-09-20 11:17	26.65	OK	14444	2026-09-20 11:18	25.83	OK
14445	2026-09-20 11:19	25.96	OK	14446	2026-09-20 11:20	25.66	OK
14447	2026-09-20 11:21	26.04	OK	14448	2026-09-20 11:22	26.51	OK
14449	2026-09-20 11:23	26.48	OK	14450	2026-09-20 11:24	25.80	OK
14451	2026-09-20 11:25	26.92	OK	14452	2026-09-20 11:26	24.83	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14453	2026-09-20 11:27	25.09	OK	14454	2026-09-20 11:28	26.08	OK
14455	2026-09-20 11:29	26.73	OK	14456	2026-09-20 11:30	26.13	OK
14457	2026-09-20 11:31	26.24	OK	14458	2026-09-20 11:32	25.10	OK
14459	2026-09-20 11:33	26.52	OK	14460	2026-09-20 11:34	26.00	OK
14461	2026-09-20 11:35	27.09	OK	14462	2026-09-20 11:36	26.59	OK
14463	2026-09-20 11:37	24.53	OK	14464	2026-09-20 11:38	27.25	OK
14465	2026-09-20 11:39	27.62	OK	14466	2026-09-20 11:40	26.10	OK
14467	2026-09-20 11:41	27.26	OK	14468	2026-09-20 11:42	25.58	OK
14469	2026-09-20 11:43	25.01	OK	14470	2026-09-20 11:44	25.89	OK
14471	2026-09-20 11:45	26.84	OK	14472	2026-09-20 11:46	26.31	OK
14473	2026-09-20 11:47	25.05	OK	14474	2026-09-20 11:48	26.21	OK
14475	2026-09-20 11:49	25.59	OK	14476	2026-09-20 11:50	25.79	OK
14477	2026-09-20 11:51	25.18	OK	14478	2026-09-20 11:52	25.18	OK
14479	2026-09-20 11:53	25.29	OK	14480	2026-09-20 11:54	26.77	OK
14481	2026-09-20 11:55	25.93	OK	14482	2026-09-20 11:56	26.38	OK
14483	2026-09-20 11:57	25.89	OK	14484	2026-09-20 11:58	26.57	OK
14485	2026-09-20 11:59	25.78	OK	14486	2026-09-20 12:00	25.45	OK
14487	2026-09-20 12:01	25.84	OK	14488	2026-09-20 12:02	26.75	OK
14489	2026-09-20 12:03	24.89	OK	14490	2026-09-20 12:04	24.54	OK
14491	2026-09-20 12:05	26.53	OK	14492	2026-09-20 12:06	24.69	OK
14493	2026-09-20 12:07	26.81	OK	14494	2026-09-20 12:08	26.17	OK
14495	2026-09-20 12:09	24.93	OK	14496	2026-09-20 12:10	24.99	OK
14497	2026-09-20 12:11	24.05	OK	14498	2026-09-20 12:12	26.25	OK
14499	2026-09-20 12:13	24.90	OK	14500	2026-09-20 12:14	26.90	OK
14501	2026-09-20 12:15	27.80	OK	14502	2026-09-20 12:16	26.01	OK
14503	2026-09-20 12:17	25.43	OK	14504	2026-09-20 12:18	25.20	OK
14505	2026-09-20 12:19	25.15	OK	14506	2026-09-20 12:20	25.25	OK
14507	2026-09-20 12:21	26.89	OK	14508	2026-09-20 12:22	25.81	OK
14509	2026-09-20 12:23	25.96	OK	14510	2026-09-20 12:24	26.75	OK
14511	2026-09-20 12:25	25.90	OK	14512	2026-09-20 12:26	26.25	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14513	2026-09-20 12:27	25.28	OK	14514	2026-09-20 12:28	24.42	OK
14515	2026-09-20 12:29	25.42	OK	14516	2026-09-20 12:30	24.49	OK
14517	2026-09-20 12:31	27.06	OK	14518	2026-09-20 12:32	25.35	OK
14519	2026-09-20 12:33	26.49	OK	14520	2026-09-20 12:34	25.87	OK
14521	2026-09-20 12:35	24.48	OK	14522	2026-09-20 12:36	26.45	OK
14523	2026-09-20 12:37	26.78	OK	14524	2026-09-20 12:38	26.50	OK
14525	2026-09-20 12:39	25.83	OK	14526	2026-09-20 12:40	24.92	OK
14527	2026-09-20 12:41	24.80	OK	14528	2026-09-20 12:42	26.07	OK
14529	2026-09-20 12:43	26.07	OK	14530	2026-09-20 12:44	26.50	OK
14531	2026-09-20 12:45	25.19	OK	14532	2026-09-20 12:46	26.56	OK
14533	2026-09-20 12:47	24.91	OK	14534	2026-09-20 12:48	26.69	OK
14535	2026-09-20 12:49	24.87	OK	14536	2026-09-20 12:50	26.69	OK
14537	2026-09-20 12:51	25.58	OK	14538	2026-09-20 12:52	25.75	OK
14539	2026-09-20 12:53	26.84	OK	14540	2026-09-20 12:54	25.68	OK
14541	2026-09-20 12:55	25.77	OK	14542	2026-09-20 12:56	25.91	OK
14543	2026-09-20 12:57	25.84	OK	14544	2026-09-20 12:58	25.83	OK
14545	2026-09-20 12:59	24.99	OK	14546	2026-09-20 13:00	25.59	OK
14547	2026-09-20 13:01	26.05	OK	14548	2026-09-20 13:02	25.77	OK
14549	2026-09-20 13:03	25.09	OK	14550	2026-09-20 13:04	25.58	OK
14551	2026-09-20 13:05	26.56	OK	14552	2026-09-20 13:06	25.17	OK
14553	2026-09-20 13:07	25.09	OK	14554	2026-09-20 13:08	26.67	OK
14555	2026-09-20 13:09	26.21	OK	14556	2026-09-20 13:10	25.07	OK
14557	2026-09-20 13:11	25.10	OK	14558	2026-09-20 13:12	24.87	OK
14559	2026-09-20 13:13	25.80	OK	14560	2026-09-20 13:14	25.64	OK
14561	2026-09-20 13:15	26.22	OK	14562	2026-09-20 13:16	25.42	OK
14563	2026-09-20 13:17	25.16	OK	14564	2026-09-20 13:18	26.64	OK
14565	2026-09-20 13:19	26.02	OK	14566	2026-09-20 13:20	26.80	OK
14567	2026-09-20 13:21	25.95	OK	14568	2026-09-20 13:22	24.73	OK
14569	2026-09-20 13:23	26.37	OK	14570	2026-09-20 13:24	25.08	OK
14571	2026-09-20 13:25	25.91	OK	14572	2026-09-20 13:26	25.25	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14573	2026-09-20 13:27	26.33	OK	14574	2026-09-20 13:28	24.14	OK
14575	2026-09-20 13:29	25.80	OK	14576	2026-09-20 13:30	25.93	OK
14577	2026-09-20 13:31	24.87	OK	14578	2026-09-20 13:32	26.65	OK
14579	2026-09-20 13:33	25.89	OK	14580	2026-09-20 13:34	26.55	OK
14581	2026-09-20 13:35	24.37	OK	14582	2026-09-20 13:36	24.68	OK
14583	2026-09-20 13:37	25.15	OK	14584	2026-09-20 13:38	26.36	OK
14585	2026-09-20 13:39	25.57	OK	14586	2026-09-20 13:40	24.60	OK
14587	2026-09-20 13:41	24.96	OK	14588	2026-09-20 13:42	25.59	OK
14589	2026-09-20 13:43	25.31	OK	14590	2026-09-20 13:44	26.31	OK
14591	2026-09-20 13:45	26.08	OK	14592	2026-09-20 13:46	26.51	OK
14593	2026-09-20 13:47	27.09	OK	14594	2026-09-20 13:48	25.78	OK
14595	2026-09-20 13:49	25.36	OK	14596	2026-09-20 13:50	25.29	OK
14597	2026-09-20 13:51	23.91	OK	14598	2026-09-20 13:52	26.96	OK
14599	2026-09-20 13:53	25.79	OK	14600	2026-09-20 13:54	26.06	OK
14601	2026-09-20 13:55	24.65	OK	14602	2026-09-20 13:56	23.82	OK
14603	2026-09-20 13:57	26.75	OK	14604	2026-09-20 13:58	25.06	OK
14605	2026-09-20 13:59	26.17	OK	14606	2026-09-20 14:00	25.58	OK
14607	2026-09-20 14:01	24.98	OK	14608	2026-09-20 14:02	25.36	OK
14609	2026-09-20 14:03	24.75	OK	14610	2026-09-20 14:04	26.70	OK
14611	2026-09-20 14:05	25.49	OK	14612	2026-09-20 14:06	26.19	OK
14613	2026-09-20 14:07	26.12	OK	14614	2026-09-20 14:08	26.11	OK
14615	2026-09-20 14:09	25.62	OK	14616	2026-09-20 14:10	25.95	OK
14617	2026-09-20 14:11	26.74	OK	14618	2026-09-20 14:12	25.03	OK
14619	2026-09-20 14:13	26.15	OK	14620	2026-09-20 14:14	24.71	OK
14621	2026-09-20 14:15	24.99	OK	14622	2026-09-20 14:16	27.06	OK
14623	2026-09-20 14:17	26.68	OK	14624	2026-09-20 14:18	26.82	OK
14625	2026-09-20 14:19	26.16	OK	14626	2026-09-20 14:20	27.35	OK
14627	2026-09-20 14:21	26.07	OK	14628	2026-09-20 14:22	26.54	OK
14629	2026-09-20 14:23	25.41	OK	14630	2026-09-20 14:24	25.98	OK
14631	2026-09-20 14:25	26.83	OK	14632	2026-09-20 14:26	25.85	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14633	2026-09-20 14:27	25.46	OK	14634	2026-09-20 14:28	25.25	OK
14635	2026-09-20 14:29	26.12	OK	14636	2026-09-20 14:30	24.36	OK
14637	2026-09-20 14:31	26.27	OK	14638	2026-09-20 14:32	25.12	OK
14639	2026-09-20 14:33	25.48	OK	14640	2026-09-20 14:34	25.60	OK
14641	2026-09-20 14:35	25.05	OK	14642	2026-09-20 14:36	26.13	OK
14643	2026-09-20 14:37	24.35	OK	14644	2026-09-20 14:38	25.32	OK
14645	2026-09-20 14:39	24.96	OK	14646	2026-09-20 14:40	25.96	OK
14647	2026-09-20 14:41	26.17	OK	14648	2026-09-20 14:42	26.04	OK
14649	2026-09-20 14:43	26.30	OK	14650	2026-09-20 14:44	25.65	OK
14651	2026-09-20 14:45	26.74	OK	14652	2026-09-20 14:46	25.90	OK
14653	2026-09-20 14:47	26.73	OK	14654	2026-09-20 14:48	24.90	OK
14655	2026-09-20 14:49	27.04	OK	14656	2026-09-20 14:50	25.33	OK
14657	2026-09-20 14:51	26.09	OK	14658	2026-09-20 14:52	25.46	OK
14659	2026-09-20 14:53	27.08	OK	14660	2026-09-20 14:54	27.30	OK
14661	2026-09-20 14:55	26.67	OK	14662	2026-09-20 14:56	27.13	OK
14663	2026-09-20 14:57	26.28	OK	14664	2026-09-20 14:58	25.04	OK
14665	2026-09-20 14:59	26.07	OK	14666	2026-09-20 15:00	26.58	OK
14667	2026-09-20 15:01	25.74	OK	14668	2026-09-20 15:02	25.95	OK
14669	2026-09-20 15:03	24.54	OK	14670	2026-09-20 15:04	24.42	OK
14671	2026-09-20 15:05	24.83	OK	14672	2026-09-20 15:06	26.08	OK
14673	2026-09-20 15:07	24.27	OK	14674	2026-09-20 15:08	27.59	OK
14675	2026-09-20 15:09	27.74	OK	14676	2026-09-20 15:10	26.97	OK
14677	2026-09-20 15:11	24.35	OK	14678	2026-09-20 15:12	26.61	OK
14679	2026-09-20 15:13	24.47	OK	14680	2026-09-20 15:14	25.55	OK
14681	2026-09-20 15:15	26.00	OK	14682	2026-09-20 15:16	24.88	OK
14683	2026-09-20 15:17	25.35	OK	14684	2026-09-20 15:18	25.36	OK
14685	2026-09-20 15:19	25.98	OK	14686	2026-09-20 15:20	24.48	OK
14687	2026-09-20 15:21	25.46	OK	14688	2026-09-20 15:22	25.18	OK
14689	2026-09-20 15:23	26.70	OK	14690	2026-09-20 15:24	25.47	OK
14691	2026-09-20 15:25	25.15	OK	14692	2026-09-20 15:26	26.53	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14693	2026-09-20 15:27	24.41	OK	14694	2026-09-20 15:28	25.53	OK
14695	2026-09-20 15:29	26.15	OK	14696	2026-09-20 15:30	26.77	OK
14697	2026-09-20 15:31	26.76	OK	14698	2026-09-20 15:32	26.97	OK
14699	2026-09-20 15:33	25.61	OK	14700	2026-09-20 15:34	25.82	OK
14701	2026-09-20 15:35	26.20	OK	14702	2026-09-20 15:36	26.62	OK
14703	2026-09-20 15:37	26.50	OK	14704	2026-09-20 15:38	24.92	OK
14705	2026-09-20 15:39	25.43	OK	14706	2026-09-20 15:40	26.29	OK
14707	2026-09-20 15:41	27.06	OK	14708	2026-09-20 15:42	25.74	OK
14709	2026-09-20 15:43	27.13	OK	14710	2026-09-20 15:44	25.39	OK
14711	2026-09-20 15:45	26.40	OK	14712	2026-09-20 15:46	26.43	OK
14713	2026-09-20 15:47	27.14	OK	14714	2026-09-20 15:48	26.41	OK
14715	2026-09-20 15:49	25.61	OK	14716	2026-09-20 15:50	26.65	OK
14717	2026-09-20 15:51	25.19	OK	14718	2026-09-20 15:52	26.46	OK
14719	2026-09-20 15:53	26.39	OK	14720	2026-09-20 15:54	27.50	OK
14721	2026-09-20 15:55	25.56	OK	14722	2026-09-20 15:56	26.61	OK
14723	2026-09-20 15:57	26.80	OK	14724	2026-09-20 15:58	27.42	OK
14725	2026-09-20 15:59	25.58	OK	14726	2026-09-20 16:00	25.91	OK
14727	2026-09-20 16:01	25.36	OK	14728	2026-09-20 16:02	25.68	OK
14729	2026-09-20 16:03	25.51	OK	14730	2026-09-20 16:04	25.79	OK
14731	2026-09-20 16:05	27.18	OK	14732	2026-09-20 16:06	26.49	OK
14733	2026-09-20 16:07	25.92	OK	14734	2026-09-20 16:08	27.04	OK
14735	2026-09-20 16:09	25.12	OK	14736	2026-09-20 16:10	26.86	OK
14737	2026-09-20 16:11	26.69	OK	14738	2026-09-20 16:12	25.70	OK
14739	2026-09-20 16:13	26.08	OK	14740	2026-09-20 16:14	25.76	OK
14741	2026-09-20 16:15	26.84	OK	14742	2026-09-20 16:16	25.94	OK
14743	2026-09-20 16:17	25.35	OK	14744	2026-09-20 16:18	26.41	OK
14745	2026-09-20 16:19	26.06	OK	14746	2026-09-20 16:20	27.50	OK
14747	2026-09-20 16:21	26.93	OK	14748	2026-09-20 16:22	27.30	OK
14749	2026-09-20 16:23	25.02	OK	14750	2026-09-20 16:24	26.14	OK
14751	2026-09-20 16:25	26.38	OK	14752	2026-09-20 16:26	27.87	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14753	2026-09-20 16:27	26.52	OK	14754	2026-09-20 16:28	26.08	OK
14755	2026-09-20 16:29	26.06	OK	14756	2026-09-20 16:30	27.49	OK
14757	2026-09-20 16:31	26.43	OK	14758	2026-09-20 16:32	26.42	OK
14759	2026-09-20 16:33	27.19	OK	14760	2026-09-20 16:34	25.71	OK
14761	2026-09-20 16:35	26.40	OK	14762	2026-09-20 16:36	28.16	OK
14763	2026-09-20 16:37	25.32	OK	14764	2026-09-20 16:38	26.50	OK
14765	2026-09-20 16:39	26.68	OK	14766	2026-09-20 16:40	27.11	OK
14767	2026-09-20 16:41	24.93	OK	14768	2026-09-20 16:42	26.28	OK
14769	2026-09-20 16:43	25.18	OK	14770	2026-09-20 16:44	26.04	OK
14771	2026-09-20 16:45	26.23	OK	14772	2026-09-20 16:46	25.84	OK
14773	2026-09-20 16:47	28.17	OK	14774	2026-09-20 16:48	26.99	OK
14775	2026-09-20 16:49	27.18	OK	14776	2026-09-20 16:50	28.13	OK
14777	2026-09-20 16:51	28.12	OK	14778	2026-09-20 16:52	25.93	OK
14779	2026-09-20 16:53	26.18	OK	14780	2026-09-20 16:54	26.59	OK
14781	2026-09-20 16:55	27.83	OK	14782	2026-09-20 16:56	26.17	OK
14783	2026-09-20 16:57	26.52	OK	14784	2026-09-20 16:58	26.70	OK
14785	2026-09-20 16:59	26.24	OK	14786	2026-09-20 17:00	26.57	OK
14787	2026-09-20 17:01	26.44	OK	14788	2026-09-20 17:02	26.46	OK
14789	2026-09-20 17:03	27.24	OK	14790	2026-09-20 17:04	27.93	OK
14791	2026-09-20 17:05	26.73	OK	14792	2026-09-20 17:06	26.67	OK
14793	2026-09-20 17:07	26.06	OK	14794	2026-09-20 17:08	26.96	OK
14795	2026-09-20 17:09	26.00	OK	14796	2026-09-20 17:10	25.27	OK
14797	2026-09-20 17:11	27.90	OK	14798	2026-09-20 17:12	26.85	OK
14799	2026-09-20 17:13	27.81	OK	14800	2026-09-20 17:14	27.01	OK
14801	2026-09-20 17:15	26.54	OK	14802	2026-09-20 17:16	25.97	OK
14803	2026-09-20 17:17	27.46	OK	14804	2026-09-20 17:18	28.10	OK
14805	2026-09-20 17:19	27.74	OK	14806	2026-09-20 17:20	26.86	OK
14807	2026-09-20 17:21	27.38	OK	14808	2026-09-20 17:22	26.65	OK
14809	2026-09-20 17:23	27.25	OK	14810	2026-09-20 17:24	25.89	OK
14811	2026-09-20 17:25	26.57	OK	14812	2026-09-20 17:26	28.26	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14813	2026-09-20 17:27	26.53	OK	14814	2026-09-20 17:28	26.66	OK
14815	2026-09-20 17:29	27.38	OK	14816	2026-09-20 17:30	28.02	OK
14817	2026-09-20 17:31	26.35	OK	14818	2026-09-20 17:32	26.35	OK
14819	2026-09-20 17:33	26.95	OK	14820	2026-09-20 17:34	27.39	OK
14821	2026-09-20 17:35	28.18	OK	14822	2026-09-20 17:36	27.49	OK
14823	2026-09-20 17:37	26.09	OK	14824	2026-09-20 17:38	27.05	OK
14825	2026-09-20 17:39	27.03	OK	14826	2026-09-20 17:40	27.67	OK
14827	2026-09-20 17:41	26.43	OK	14828	2026-09-20 17:42	26.72	OK
14829	2026-09-20 17:43	27.36	OK	14830	2026-09-20 17:44	27.61	OK
14831	2026-09-20 17:45	26.62	OK	14832	2026-09-20 17:46	27.51	OK
14833	2026-09-20 17:47	28.49	OK	14834	2026-09-20 17:48	27.40	OK
14835	2026-09-20 17:49	26.44	OK	14836	2026-09-20 17:50	26.04	OK
14837	2026-09-20 17:51	25.93	OK	14838	2026-09-20 17:52	27.30	OK
14839	2026-09-20 17:53	28.03	OK	14840	2026-09-20 17:54	25.79	OK
14841	2026-09-20 17:55	27.66	OK	14842	2026-09-20 17:56	27.16	OK
14843	2026-09-20 17:57	27.90	OK	14844	2026-09-20 17:58	28.24	OK
14845	2026-09-20 17:59	28.22	OK	14846	2026-09-20 18:00	27.80	OK
14847	2026-09-20 18:01	26.89	OK	14848	2026-09-20 18:02	26.69	OK
14849	2026-09-20 18:03	26.90	OK	14850	2026-09-20 18:04	25.85	OK
14851	2026-09-20 18:05	27.89	OK	14852	2026-09-20 18:06	27.61	OK
14853	2026-09-20 18:07	27.89	OK	14854	2026-09-20 18:08	28.41	OK
14855	2026-09-20 18:09	27.20	OK	14856	2026-09-20 18:10	26.92	OK
14857	2026-09-20 18:11	27.36	OK	14858	2026-09-20 18:12	27.91	OK
14859	2026-09-20 18:13	27.27	OK	14860	2026-09-20 18:14	27.39	OK
14861	2026-09-20 18:15	26.74	OK	14862	2026-09-20 18:16	25.79	OK
14863	2026-09-20 18:17	27.33	OK	14864	2026-09-20 18:18	27.20	OK
14865	2026-09-20 18:19	27.64	OK	14866	2026-09-20 18:20	27.04	OK
14867	2026-09-20 18:21	27.98	OK	14868	2026-09-20 18:22	27.47	OK
14869	2026-09-20 18:23	27.01	OK	14870	2026-09-20 18:24	26.27	OK
14871	2026-09-20 18:25	27.32	OK	14872	2026-09-20 18:26	27.81	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14873	2026-09-20 18:27	27.46	OK	14874	2026-09-20 18:28	27.91	OK
14875	2026-09-20 18:29	27.95	OK	14876	2026-09-20 18:30	26.82	OK
14877	2026-09-20 18:31	26.82	OK	14878	2026-09-20 18:32	28.75	OK
14879	2026-09-20 18:33	25.98	OK	14880	2026-09-20 18:34	26.72	OK
14881	2026-09-20 18:35	27.15	OK	14882	2026-09-20 18:36	28.87	OK
14883	2026-09-20 18:37	27.57	OK	14884	2026-09-20 18:38	26.36	OK
14885	2026-09-20 18:39	26.90	OK	14886	2026-09-20 18:40	28.62	OK
14887	2026-09-20 18:41	27.53	OK	14888	2026-09-20 18:42	25.87	OK
14889	2026-09-20 18:43	27.66	OK	14890	2026-09-20 18:44	27.20	OK
14891	2026-09-20 18:45	26.83	OK	14892	2026-09-20 18:46	27.96	OK
14893	2026-09-20 18:47	28.13	OK	14894	2026-09-20 18:48	26.69	OK
14895	2026-09-20 18:49	26.80	OK	14896	2026-09-20 18:50	28.29	OK
14897	2026-09-20 18:51	27.11	OK	14898	2026-09-20 18:52	27.92	OK
14899	2026-09-20 18:53	28.44	OK	14900	2026-09-20 18:54	27.15	OK
14901	2026-09-20 18:55	28.27	OK	14902	2026-09-20 18:56	29.89	OK
14903	2026-09-20 18:57	27.53	OK	14904	2026-09-20 18:58	27.65	OK
14905	2026-09-20 18:59	28.35	OK	14906	2026-09-20 19:00	26.54	OK
14907	2026-09-20 19:01	28.24	OK	14908	2026-09-20 19:02	26.07	OK
14909	2026-09-20 19:03	28.29	OK	14910	2026-09-20 19:04	26.15	OK
14911	2026-09-20 19:05	27.35	OK	14912	2026-09-20 19:06	27.28	OK
14913	2026-09-20 19:07	27.14	OK	14914	2026-09-20 19:08	26.31	OK
14915	2026-09-20 19:09	28.00	OK	14916	2026-09-20 19:10	28.15	OK
14917	2026-09-20 19:11	27.58	OK	14918	2026-09-20 19:12	26.53	OK
14919	2026-09-20 19:13	28.41	OK	14920	2026-09-20 19:14	27.27	OK
14921	2026-09-20 19:15	26.79	OK	14922	2026-09-20 19:16	29.40	OK
14923	2026-09-20 19:17	28.87	OK	14924	2026-09-20 19:18	27.62	OK
14925	2026-09-20 19:19	28.21	OK	14926	2026-09-20 19:20	26.98	OK
14927	2026-09-20 19:21	26.56	OK	14928	2026-09-20 19:22	27.10	OK
14929	2026-09-20 19:23	28.38	OK	14930	2026-09-20 19:24	28.33	OK
14931	2026-09-20 19:25	27.74	OK	14932	2026-09-20 19:26	28.68	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14933	2026-09-20 19:27	27.88	OK	14934	2026-09-20 19:28	27.58	OK
14935	2026-09-20 19:29	26.12	OK	14936	2026-09-20 19:30	27.52	OK
14937	2026-09-20 19:31	27.94	OK	14938	2026-09-20 19:32	28.07	OK
14939	2026-09-20 19:33	27.33	OK	14940	2026-09-20 19:34	28.13	OK
14941	2026-09-20 19:35	27.34	OK	14942	2026-09-20 19:36	28.26	OK
14943	2026-09-20 19:37	28.14	OK	14944	2026-09-20 19:38	28.15	OK
14945	2026-09-20 19:39	28.17	OK	14946	2026-09-20 19:40	27.09	OK
14947	2026-09-20 19:41	28.33	OK	14948	2026-09-20 19:42	27.35	OK
14949	2026-09-20 19:43	29.51	OK	14950	2026-09-20 19:44	28.26	OK
14951	2026-09-20 19:45	29.61	OK	14952	2026-09-20 19:46	28.69	OK
14953	2026-09-20 19:47	28.08	OK	14954	2026-09-20 19:48	27.85	OK
14955	2026-09-20 19:49	28.41	OK	14956	2026-09-20 19:50	28.85	OK
14957	2026-09-20 19:51	28.66	OK	14958	2026-09-20 19:52	27.87	OK
14959	2026-09-20 19:53	27.80	OK	14960	2026-09-20 19:54	28.85	OK
14961	2026-09-20 19:55	27.26	OK	14962	2026-09-20 19:56	28.72	OK
14963	2026-09-20 19:57	28.50	OK	14964	2026-09-20 19:58	27.65	OK
14965	2026-09-20 19:59	29.42	OK	14966	2026-09-20 20:00	27.51	OK
14967	2026-09-20 20:01	28.44	OK	14968	2026-09-20 20:02	28.71	OK
14969	2026-09-20 20:03	29.26	OK	14970	2026-09-20 20:04	29.14	OK
14971	2026-09-20 20:05	26.62	OK	14972	2026-09-20 20:06	28.27	OK
14973	2026-09-20 20:07	28.57	OK	14974	2026-09-20 20:08	27.78	OK
14975	2026-09-20 20:09	27.63	OK	14976	2026-09-20 20:10	27.09	OK
14977	2026-09-20 20:11	27.96	OK	14978	2026-09-20 20:12	28.27	OK
14979	2026-09-20 20:13	27.90	OK	14980	2026-09-20 20:14	30.22	OK
14981	2026-09-20 20:15	28.66	OK	14982	2026-09-20 20:16	28.54	OK
14983	2026-09-20 20:17	28.33	OK	14984	2026-09-20 20:18	29.20	OK
14985	2026-09-20 20:19	28.38	OK	14986	2026-09-20 20:20	28.08	OK
14987	2026-09-20 20:21	27.45	OK	14988	2026-09-20 20:22	29.48	OK
14989	2026-09-20 20:23	29.35	OK	14990	2026-09-20 20:24	28.11	OK
14991	2026-09-20 20:25	28.17	OK	14992	2026-09-20 20:26	27.75	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
14993	2026-09-20 20:27	29.76	OK	14994	2026-09-20 20:28	28.73	OK
14995	2026-09-20 20:29	29.36	OK	14996	2026-09-20 20:30	27.77	OK
14997	2026-09-20 20:31	28.11	OK	14998	2026-09-20 20:32	28.32	OK
14999	2026-09-20 20:33	28.99	OK	15000	2026-09-20 20:34	29.24	OK
15001	2026-09-20 20:35	27.97	OK	15002	2026-09-20 20:36	28.19	OK
15003	2026-09-20 20:37	29.37	OK	15004	2026-09-20 20:38	27.33	OK
15005	2026-09-20 20:39	28.43	OK	15006	2026-09-20 20:40	28.82	OK
15007	2026-09-20 20:41	27.85	OK	15008	2026-09-20 20:42	27.44	OK
15009	2026-09-20 20:43	28.48	OK	15010	2026-09-20 20:44	30.21	OK
15011	2026-09-20 20:45	28.38	OK	15012	2026-09-20 20:46	28.25	OK
15013	2026-09-20 20:47	28.47	OK	15014	2026-09-20 20:48	28.36	OK
15015	2026-09-20 20:49	29.40	OK	15016	2026-09-20 20:50	29.00	OK
15017	2026-09-20 20:51	28.58	OK	15018	2026-09-20 20:52	28.95	OK
15019	2026-09-20 20:53	27.66	OK	15020	2026-09-20 20:54	30.06	OK
15021	2026-09-20 20:55	28.68	OK	15022	2026-09-20 20:56	28.64	OK
15023	2026-09-20 20:57	28.71	OK	15024	2026-09-20 20:58	29.23	OK
15025	2026-09-20 20:59	27.40	OK	15026	2026-09-20 21:00	27.85	OK
15027	2026-09-20 21:01	28.64	OK	15028	2026-09-20 21:02	28.98	OK
15029	2026-09-20 21:03	29.01	OK	15030	2026-09-20 21:04	29.52	OK
15031	2026-09-20 21:05	28.00	OK	15032	2026-09-20 21:06	29.16	OK
15033	2026-09-20 21:07	28.09	OK	15034	2026-09-20 21:08	29.18	OK
15035	2026-09-20 21:09	29.41	OK	15036	2026-09-20 21:10	28.59	OK
15037	2026-09-20 21:11	26.99	OK	15038	2026-09-20 21:12	28.06	OK
15039	2026-09-20 21:13	28.54	OK	15040	2026-09-20 21:14	29.28	OK
15041	2026-09-20 21:15	28.79	OK	15042	2026-09-20 21:16	28.90	OK
15043	2026-09-20 21:17	29.87	OK	15044	2026-09-20 21:18	30.35	OK
15045	2026-09-20 21:19	28.68	OK	15046	2026-09-20 21:20	29.74	OK
15047	2026-09-20 21:21	29.91	OK	15048	2026-09-20 21:22	28.98	OK
15049	2026-09-20 21:23	27.81	OK	15050	2026-09-20 21:24	28.64	OK
15051	2026-09-20 21:25	30.01	OK	15052	2026-09-20 21:26	28.78	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15053	2026-09-20 21:27	28.43	OK	15054	2026-09-20 21:28	28.94	OK
15055	2026-09-20 21:29	28.85	OK	15056	2026-09-20 21:30	29.65	OK
15057	2026-09-20 21:31	29.09	OK	15058	2026-09-20 21:32	29.31	OK
15059	2026-09-20 21:33	30.03	OK	15060	2026-09-20 21:34	30.42	OK
15061	2026-09-20 21:35	30.26	OK	15062	2026-09-20 21:36	27.92	OK
15063	2026-09-20 21:37	29.20	OK	15064	2026-09-20 21:38	29.89	OK
15065	2026-09-20 21:39	27.72	OK	15066	2026-09-20 21:40	28.88	OK
15067	2026-09-20 21:41	29.29	OK	15068	2026-09-20 21:42	30.07	OK
15069	2026-09-20 21:43	29.68	OK	15070	2026-09-20 21:44	28.48	OK
15071	2026-09-20 21:45	30.92	OK	15072	2026-09-20 21:46	28.60	OK
15073	2026-09-20 21:47	28.36	OK	15074	2026-09-20 21:48	29.32	OK
15075	2026-09-20 21:49	29.88	OK	15076	2026-09-20 21:50	27.45	OK
15077	2026-09-20 21:51	29.41	OK	15078	2026-09-20 21:52	28.75	OK
15079	2026-09-20 21:53	30.85	OK	15080	2026-09-20 21:54	30.17	OK
15081	2026-09-20 21:55	30.18	OK	15082	2026-09-20 21:56	28.58	OK
15083	2026-09-20 21:57	28.55	OK	15084	2026-09-20 21:58	29.25	OK
15085	2026-09-20 21:59	28.72	OK	15086	2026-09-20 22:00	29.95	OK
15087	2026-09-20 22:01	30.63	OK	15088	2026-09-20 22:02	28.05	OK
15089	2026-09-20 22:03	29.59	OK	15090	2026-09-20 22:04	29.33	OK
15091	2026-09-20 22:05	30.47	OK	15092	2026-09-20 22:06	27.63	OK
15093	2026-09-20 22:07	29.46	OK	15094	2026-09-20 22:08	28.78	OK
15095	2026-09-20 22:09	28.72	OK	15096	2026-09-20 22:10	29.70	OK
15097	2026-09-20 22:11	28.39	OK	15098	2026-09-20 22:12	29.28	OK
15099	2026-09-20 22:13	30.02	OK	15100	2026-09-20 22:14	29.78	OK
15101	2026-09-20 22:15	29.86	OK	15102	2026-09-20 22:16	29.35	OK
15103	2026-09-20 22:17	29.47	OK	15104	2026-09-20 22:18	28.70	OK
15105	2026-09-20 22:19	30.53	OK	15106	2026-09-20 22:20	28.58	OK
15107	2026-09-20 22:21	29.90	OK	15108	2026-09-20 22:22	30.57	OK
15109	2026-09-20 22:23	29.39	OK	15110	2026-09-20 22:24	30.17	OK
15111	2026-09-20 22:25	29.40	OK	15112	2026-09-20 22:26	29.37	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15113	2026-09-20 22:27	30.12	OK	15114	2026-09-20 22:28	29.67	OK
15115	2026-09-20 22:29	29.49	OK	15116	2026-09-20 22:30	28.93	OK
15117	2026-09-20 22:31	29.75	OK	15118	2026-09-20 22:32	29.37	OK
15119	2026-09-20 22:33	28.86	OK	15120	2026-09-20 22:34	29.69	OK
15121	2026-09-20 22:35	28.33	OK	15122	2026-09-20 22:36	29.27	OK
15123	2026-09-20 22:37	29.14	OK	15124	2026-09-20 22:38	30.37	OK
15125	2026-09-20 22:39	29.15	OK	15126	2026-09-20 22:40	30.16	OK
15127	2026-09-20 22:41	29.11	OK	15128	2026-09-20 22:42	29.34	OK
15129	2026-09-20 22:43	30.60	OK	15130	2026-09-20 22:44	29.74	OK
15131	2026-09-20 22:45	28.90	OK	15132	2026-09-20 22:46	30.33	OK
15133	2026-09-20 22:47	30.33	OK	15134	2026-09-20 22:48	29.86	OK
15135	2026-09-20 22:49	29.64	OK	15136	2026-09-20 22:50	30.01	OK
15137	2026-09-20 22:51	29.93	OK	15138	2026-09-20 22:52	29.97	OK
15139	2026-09-20 22:53	28.63	OK	15140	2026-09-20 22:54	29.90	OK
15141	2026-09-20 22:55	30.32	OK	15142	2026-09-20 22:56	30.00	OK
15143	2026-09-20 22:57	28.39	OK	15144	2026-09-20 22:58	29.42	OK
15145	2026-09-20 22:59	29.41	OK	15146	2026-09-20 23:00	30.71	OK
15147	2026-09-20 23:01	30.05	OK	15148	2026-09-20 23:02	28.84	OK
15149	2026-09-20 23:03	29.97	OK	15150	2026-09-20 23:04	30.18	OK
15151	2026-09-20 23:05	30.05	OK	15152	2026-09-20 23:06	29.51	OK
15153	2026-09-20 23:07	30.37	OK	15154	2026-09-20 23:08	30.26	OK
15155	2026-09-20 23:09	30.46	OK	15156	2026-09-20 23:10	30.73	OK
15157	2026-09-20 23:11	30.36	OK	15158	2026-09-20 23:12	29.33	OK
15159	2026-09-20 23:13	28.24	OK	15160	2026-09-20 23:14	29.25	OK
15161	2026-09-20 23:15	30.29	OK	15162	2026-09-20 23:16	29.21	OK
15163	2026-09-20 23:17	29.62	OK	15164	2026-09-20 23:18	29.77	OK
15165	2026-09-20 23:19	29.39	OK	15166	2026-09-20 23:20	29.86	OK
15167	2026-09-20 23:21	29.69	OK	15168	2026-09-20 23:22	29.68	OK
15169	2026-09-20 23:23	29.67	OK	15170	2026-09-20 23:24	29.52	OK
15171	2026-09-20 23:25	29.06	OK	15172	2026-09-20 23:26	28.66	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15173	2026-09-20 23:27	29.83	OK	15174	2026-09-20 23:28	29.64	OK
15175	2026-09-20 23:29	28.61	OK	15176	2026-09-20 23:30	30.23	OK
15177	2026-09-20 23:31	30.65	OK	15178	2026-09-20 23:32	30.51	OK
15179	2026-09-20 23:33	29.04	OK	15180	2026-09-20 23:34	30.98	OK
15181	2026-09-20 23:35	30.57	OK	15182	2026-09-20 23:36	31.57	OK
15183	2026-09-20 23:37	29.46	OK	15184	2026-09-20 23:38	30.80	OK
15185	2026-09-20 23:39	31.56	OK	15186	2026-09-20 23:40	29.97	OK
15187	2026-09-20 23:41	30.54	OK	15188	2026-09-20 23:42	30.48	OK
15189	2026-09-20 23:43	30.53	OK	15190	2026-09-20 23:44	28.70	OK
15191	2026-09-20 23:45	31.11	OK	15192	2026-09-20 23:46	30.33	OK
15193	2026-09-20 23:47	30.94	OK	15194	2026-09-20 23:48	28.50	OK
15195	2026-09-20 23:49	30.19	OK	15196	2026-09-20 23:50	30.26	OK
15197	2026-09-20 23:51	30.97	OK	15198	2026-09-20 23:52	31.17	OK
15199	2026-09-20 23:53	30.20	OK	15200	2026-09-20 23:54	30.73	OK
15201	2026-09-20 23:55	30.71	OK	15202	2026-09-20 23:56	30.10	OK
15203	2026-09-20 23:57	28.79	OK	15204	2026-09-20 23:58	30.05	OK
15205	2026-09-20 23:59	30.22	OK	15206	2026-09-21 00:00	31.00	OK
15207	2026-09-21 00:01	31.12	OK	15208	2026-09-21 00:02	30.04	OK
15209	2026-09-21 00:03	29.55	OK	15210	2026-09-21 00:04	29.09	OK
15211	2026-09-21 00:05	29.14	OK	15212	2026-09-21 00:06	29.44	OK
15213	2026-09-21 00:07	30.55	OK	15214	2026-09-21 00:08	30.19	OK
15215	2026-09-21 00:09	29.49	OK	15216	2026-09-21 00:10	30.61	OK
15217	2026-09-21 00:11	30.52	OK	15218	2026-09-21 00:12	29.61	OK
15219	2026-09-21 00:13	29.87	OK	15220	2026-09-21 00:14	29.66	OK
15221	2026-09-21 00:15	28.23	OK	15222	2026-09-21 00:16	30.90	OK
15223	2026-09-21 00:17	30.61	OK	15224	2026-09-21 00:18	28.95	OK
15225	2026-09-21 00:19	29.68	OK	15226	2026-09-21 00:20	29.83	OK
15227	2026-09-21 00:21	29.11	OK	15228	2026-09-21 00:22	31.42	OK
15229	2026-09-21 00:23	29.65	OK	15230	2026-09-21 00:24	30.86	OK
15231	2026-09-21 00:25	30.36	OK	15232	2026-09-21 00:26	29.60	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15233	2026-09-21 00:27	30.92	OK	15234	2026-09-21 00:28	29.97	OK
15235	2026-09-21 00:29	30.54	OK	15236	2026-09-21 00:30	29.33	OK
15237	2026-09-21 00:31	29.61	OK	15238	2026-09-21 00:32	30.96	OK
15239	2026-09-21 00:33	29.09	OK	15240	2026-09-21 00:34	29.59	OK
15241	2026-09-21 00:35	30.12	OK	15242	2026-09-21 00:36	29.60	OK
15243	2026-09-21 00:37	31.40	OK	15244	2026-09-21 00:38	29.89	OK
15245	2026-09-21 00:39	30.25	OK	15246	2026-09-21 00:40	30.79	OK
15247	2026-09-21 00:41	30.91	OK	15248	2026-09-21 00:42	31.35	OK
15249	2026-09-21 00:43	30.44	OK	15250	2026-09-21 00:44	31.06	OK
15251	2026-09-21 00:45	29.49	OK	15252	2026-09-21 00:46	29.96	OK
15253	2026-09-21 00:47	30.48	OK	15254	2026-09-21 00:48	30.43	OK
15255	2026-09-21 00:49	31.36	OK	15256	2026-09-21 00:50	31.04	OK
15257	2026-09-21 00:51	29.84	OK	15258	2026-09-21 00:52	30.81	OK
15259	2026-09-21 00:53	28.44	OK	15260	2026-09-21 00:54	30.98	OK
15261	2026-09-21 00:55	31.10	OK	15262	2026-09-21 00:56	30.84	OK
15263	2026-09-21 00:57	29.77	OK	15264	2026-09-21 00:58	29.94	OK
15265	2026-09-21 00:59	29.87	OK	15266	2026-09-21 01:00	30.73	OK
15267	2026-09-21 01:01	31.58	OK	15268	2026-09-21 01:02	30.63	OK
15269	2026-09-21 01:03	31.38	OK	15270	2026-09-21 01:04	31.78	OK
15271	2026-09-21 01:05	29.81	OK	15272	2026-09-21 01:06	30.59	OK
15273	2026-09-21 01:07	29.81	OK	15274	2026-09-21 01:08	30.66	OK
15275	2026-09-21 01:09	30.08	OK	15276	2026-09-21 01:10	31.33	OK
15277	2026-09-21 01:11	30.56	OK	15278	2026-09-21 01:12	30.48	OK
15279	2026-09-21 01:13	30.10	OK	15280	2026-09-21 01:14	30.23	OK
15281	2026-09-21 01:15	31.31	OK	15282	2026-09-21 01:16	29.53	OK
15283	2026-09-21 01:17	30.55	OK	15284	2026-09-21 01:18	30.19	OK
15285	2026-09-21 01:19	29.30	OK	15286	2026-09-21 01:20	30.05	OK
15287	2026-09-21 01:21	30.96	OK	15288	2026-09-21 01:22	30.42	OK
15289	2026-09-21 01:23	30.52	OK	15290	2026-09-21 01:24	31.34	OK
15291	2026-09-21 01:25	28.77	OK	15292	2026-09-21 01:26	28.36	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15293	2026-09-21 01:27	30.63	OK	15294	2026-09-21 01:28	30.98	OK
15295	2026-09-21 01:29	30.57	OK	15296	2026-09-21 01:30	29.28	OK
15297	2026-09-21 01:31	30.35	OK	15298	2026-09-21 01:32	32.12	OK
15299	2026-09-21 01:33	30.54	OK	15300	2026-09-21 01:34	30.74	OK
15301	2026-09-21 01:35	31.01	OK	15302	2026-09-21 01:36	30.27	OK
15303	2026-09-21 01:37	30.74	OK	15304	2026-09-21 01:38	30.55	OK
15305	2026-09-21 01:39	29.46	OK	15306	2026-09-21 01:40	31.83	OK
15307	2026-09-21 01:41	29.72	OK	15308	2026-09-21 01:42	29.88	OK
15309	2026-09-21 01:43	30.00	OK	15310	2026-09-21 01:44	30.46	OK
15311	2026-09-21 01:45	29.23	OK	15312	2026-09-21 01:46	31.16	OK
15313	2026-09-21 01:47	28.75	OK	15314	2026-09-21 01:48	31.93	OK
15315	2026-09-21 01:49	31.09	OK	15316	2026-09-21 01:50	30.46	OK
15317	2026-09-21 01:51	29.24	OK	15318	2026-09-21 01:52	31.20	OK
15319	2026-09-21 01:53	29.71	OK	15320	2026-09-21 01:54	28.69	OK
15321	2026-09-21 01:55	30.52	OK	15322	2026-09-21 01:56	30.10	OK
15323	2026-09-21 01:57	30.94	OK	15324	2026-09-21 01:58	30.40	OK
15325	2026-09-21 01:59	28.98	OK	15326	2026-09-21 02:00	30.54	OK
15327	2026-09-21 02:01	29.17	OK	15328	2026-09-21 02:02	30.12	OK
15329	2026-09-21 02:03	29.54	OK	15330	2026-09-21 02:04	29.98	OK
15331	2026-09-21 02:05	31.15	OK	15332	2026-09-21 02:06	31.50	OK
15333	2026-09-21 02:07	30.82	OK	15334	2026-09-21 02:08	30.30	OK
15335	2026-09-21 02:09	30.40	OK	15336	2026-09-21 02:10	29.99	OK
15337	2026-09-21 02:11	28.77	OK	15338	2026-09-21 02:12	30.50	OK
15339	2026-09-21 02:13	30.52	OK	15340	2026-09-21 02:14	30.45	OK
15341	2026-09-21 02:15	30.72	OK	15342	2026-09-21 02:16	30.57	OK
15343	2026-09-21 02:17	30.84	OK	15344	2026-09-21 02:18	31.26	OK
15345	2026-09-21 02:19	30.62	OK	15346	2026-09-21 02:20	30.88	OK
15347	2026-09-21 02:21	31.27	OK	15348	2026-09-21 02:22	30.33	OK
15349	2026-09-21 02:23	29.88	OK	15350	2026-09-21 02:24	29.91	OK
15351	2026-09-21 02:25	30.02	OK	15352	2026-09-21 02:26	30.45	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15353	2026-09-21 02:27	30.09	OK	15354	2026-09-21 02:28	29.20	OK
15355	2026-09-21 02:29	31.08	OK	15356	2026-09-21 02:30	28.74	OK
15357	2026-09-21 02:31	30.00	OK	15358	2026-09-21 02:32	31.12	OK
15359	2026-09-21 02:33	29.82	OK	15360	2026-09-21 02:34	29.62	OK
15361	2026-09-21 02:35	29.22	OK	15362	2026-09-21 02:36	30.23	OK
15363	2026-09-21 02:37	30.53	OK	15364	2026-09-21 02:38	29.15	OK
15365	2026-09-21 02:39	30.94	OK	15366	2026-09-21 02:40	29.72	OK
15367	2026-09-21 02:41	30.30	OK	15368	2026-09-21 02:42	30.84	OK
15369	2026-09-21 02:43	30.02	OK	15370	2026-09-21 02:44	30.01	OK
15371	2026-09-21 02:45	29.76	OK	15372	2026-09-21 02:46	31.19	OK
15373	2026-09-21 02:47	30.19	OK	15374	2026-09-21 02:48	29.30	OK
15375	2026-09-21 02:49	30.90	OK	15376	2026-09-21 02:50	29.60	OK
15377	2026-09-21 02:51	31.55	OK	15378	2026-09-21 02:52	30.78	OK
15379	2026-09-21 02:53	30.48	OK	15380	2026-09-21 02:54	31.07	OK
15381	2026-09-21 02:55	31.18	OK	15382	2026-09-21 02:56	29.77	OK
15383	2026-09-21 02:57	28.29	OK	15384	2026-09-21 02:58	29.10	OK
15385	2026-09-21 02:59	30.23	OK	15386	2026-09-21 03:00	30.51	OK
15387	2026-09-21 03:01	31.84	OK	15388	2026-09-21 03:02	29.69	OK
15389	2026-09-21 03:03	30.85	OK	15390	2026-09-21 03:04	29.97	OK
15391	2026-09-21 03:05	30.49	OK	15392	2026-09-21 03:06	29.26	OK
15393	2026-09-21 03:07	31.92	OK	15394	2026-09-21 03:08	29.67	OK
15395	2026-09-21 03:09	30.02	OK	15396	2026-09-21 03:10	29.86	OK
15397	2026-09-21 03:11	29.36	OK	15398	2026-09-21 03:12	31.51	OK
15399	2026-09-21 03:13	30.89	OK	15400	2026-09-21 03:14	30.90	OK
15401	2026-09-21 03:15	29.80	OK	15402	2026-09-21 03:16	29.75	OK
15403	2026-09-21 03:17	29.01	OK	15404	2026-09-21 03:18	30.45	OK
15405	2026-09-21 03:19	28.95	OK	15406	2026-09-21 03:20	30.95	OK
15407	2026-09-21 03:21	29.09	OK	15408	2026-09-21 03:22	29.88	OK
15409	2026-09-21 03:23	30.25	OK	15410	2026-09-21 03:24	32.07	OK
15411	2026-09-21 03:25	29.78	OK	15412	2026-09-21 03:26	28.82	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15413	2026-09-21 03:27	29.05	OK	15414	2026-09-21 03:28	30.41	OK
15415	2026-09-21 03:29	29.21	OK	15416	2026-09-21 03:30	31.34	OK
15417	2026-09-21 03:31	30.00	OK	15418	2026-09-21 03:32	29.52	OK
15419	2026-09-21 03:33	29.85	OK	15420	2026-09-21 03:34	30.45	OK
15421	2026-09-21 03:35	30.74	OK	15422	2026-09-21 03:36	30.94	OK
15423	2026-09-21 03:37	29.13	OK	15424	2026-09-21 03:38	28.01	OK
15425	2026-09-21 03:39	30.46	OK	15426	2026-09-21 03:40	30.31	OK
15427	2026-09-21 03:41	28.20	OK	15428	2026-09-21 03:42	31.17	OK
15429	2026-09-21 03:43	29.61	OK	15430	2026-09-21 03:44	29.83	OK
15431	2026-09-21 03:45	29.78	OK	15432	2026-09-21 03:46	30.33	OK
15433	2026-09-21 03:47	29.61	OK	15434	2026-09-21 03:48	29.26	OK
15435	2026-09-21 03:49	30.52	OK	15436	2026-09-21 03:50	31.08	OK
15437	2026-09-21 03:51	32.06	OK	15438	2026-09-21 03:52	29.67	OK
15439	2026-09-21 03:53	29.60	OK	15440	2026-09-21 03:54	29.99	OK
15441	2026-09-21 03:55	29.65	OK	15442	2026-09-21 03:56	29.40	OK
15443	2026-09-21 03:57	30.02	OK	15444	2026-09-21 03:58	30.31	OK
15445	2026-09-21 03:59	31.20	OK	15446	2026-09-21 04:00	29.60	OK
15447	2026-09-21 04:01	30.00	OK	15448	2026-09-21 04:02	29.00	OK
15449	2026-09-21 04:03	29.52	OK	15450	2026-09-21 04:04	28.90	OK
15451	2026-09-21 04:05	31.18	OK	15452	2026-09-21 04:06	29.88	OK
15453	2026-09-21 04:07	29.48	OK	15454	2026-09-21 04:08	29.56	OK
15455	2026-09-21 04:09	29.64	OK	15456	2026-09-21 04:10	29.11	OK
15457	2026-09-21 04:11	29.53	OK	15458	2026-09-21 04:12	29.68	OK
15459	2026-09-21 04:13	29.77	OK	15460	2026-09-21 04:14	29.12	OK
15461	2026-09-21 04:15	28.97	OK	15462	2026-09-21 04:16	29.86	OK
15463	2026-09-21 04:17	30.72	OK	15464	2026-09-21 04:18	29.65	OK
15465	2026-09-21 04:19	29.90	OK	15466	2026-09-21 04:20	30.39	OK
15467	2026-09-21 04:21	29.18	OK	15468	2026-09-21 04:22	30.30	OK
15469	2026-09-21 04:23	29.72	OK	15470	2026-09-21 04:24	29.94	OK
15471	2026-09-21 04:25	29.08	OK	15472	2026-09-21 04:26	28.81	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15473	2026-09-21 04:27	28.99	OK	15474	2026-09-21 04:28	30.59	OK
15475	2026-09-21 04:29	29.01	OK	15476	2026-09-21 04:30	28.93	OK
15477	2026-09-21 04:31	29.05	OK	15478	2026-09-21 04:32	29.26	OK
15479	2026-09-21 04:33	30.17	OK	15480	2026-09-21 04:34	29.72	OK
15481	2026-09-21 04:35	30.24	OK	15482	2026-09-21 04:36	28.07	OK
15483	2026-09-21 04:37	29.19	OK	15484	2026-09-21 04:38	29.34	OK
15485	2026-09-21 04:39	30.00	OK	15486	2026-09-21 04:40	29.76	OK
15487	2026-09-21 04:41	30.10	OK	15488	2026-09-21 04:42	28.89	OK
15489	2026-09-21 04:43	29.15	OK	15490	2026-09-21 04:44	29.17	OK
15491	2026-09-21 04:45	29.59	OK	15492	2026-09-21 04:46	29.73	OK
15493	2026-09-21 04:47	30.01	OK	15494	2026-09-21 04:48	30.40	OK
15495	2026-09-21 04:49	29.63	OK	15496	2026-09-21 04:50	29.30	OK
15497	2026-09-21 04:51	29.55	OK	15498	2026-09-21 04:52	29.49	OK
15499	2026-09-21 04:53	28.42	OK	15500	2026-09-21 04:54	30.69	OK
15501	2026-09-21 04:55	30.11	OK	15502	2026-09-21 04:56	28.45	OK
15503	2026-09-21 04:57	28.83	OK	15504	2026-09-21 04:58	28.22	OK
15505	2026-09-21 04:59	30.22	OK	15506	2026-09-21 05:00	30.75	OK
15507	2026-09-21 05:01	29.57	OK	15508	2026-09-21 05:02	28.51	OK
15509	2026-09-21 05:03	27.92	OK	15510	2026-09-21 05:04	28.67	OK
15511	2026-09-21 05:05	28.57	OK	15512	2026-09-21 05:06	28.97	OK
15513	2026-09-21 05:07	30.44	OK	15514	2026-09-21 05:08	27.96	OK
15515	2026-09-21 05:09	28.70	OK	15516	2026-09-21 05:10	29.93	OK
15517	2026-09-21 05:11	30.11	OK	15518	2026-09-21 05:12	29.45	OK
15519	2026-09-21 05:13	29.75	OK	15520	2026-09-21 05:14	29.47	OK
15521	2026-09-21 05:15	29.81	OK	15522	2026-09-21 05:16	28.93	OK
15523	2026-09-21 05:17	28.72	OK	15524	2026-09-21 05:18	29.07	OK
15525	2026-09-21 05:19	28.96	OK	15526	2026-09-21 05:20	29.99	OK
15527	2026-09-21 05:21	29.38	OK	15528	2026-09-21 05:22	30.09	OK
15529	2026-09-21 05:23	29.52	OK	15530	2026-09-21 05:24	31.00	OK
15531	2026-09-21 05:25	28.62	OK	15532	2026-09-21 05:26	28.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15533	2026-09-21 05:27	30.60	OK	15534	2026-09-21 05:28	30.15	OK
15535	2026-09-21 05:29	29.69	OK	15536	2026-09-21 05:30	28.07	OK
15537	2026-09-21 05:31	27.58	OK	15538	2026-09-21 05:32	29.38	OK
15539	2026-09-21 05:33	28.91	OK	15540	2026-09-21 05:34	29.23	OK
15541	2026-09-21 05:35	27.97	OK	15542	2026-09-21 05:36	29.36	OK
15543	2026-09-21 05:37	29.46	OK	15544	2026-09-21 05:38	27.47	OK
15545	2026-09-21 05:39	29.64	OK	15546	2026-09-21 05:40	29.08	OK
15547	2026-09-21 05:41	30.59	OK	15548	2026-09-21 05:42	28.27	OK
15549	2026-09-21 05:43	29.37	OK	15550	2026-09-21 05:44	28.61	OK
15551	2026-09-21 05:45	29.30	OK	15552	2026-09-21 05:46	29.60	OK
15553	2026-09-21 05:47	28.93	OK	15554	2026-09-21 05:48	30.62	OK
15555	2026-09-21 05:49	29.12	OK	15556	2026-09-21 05:50	29.89	OK
15557	2026-09-21 05:51	29.66	OK	15558	2026-09-21 05:52	29.40	OK
15559	2026-09-21 05:53	29.06	OK	15560	2026-09-21 05:54	28.28	OK
15561	2026-09-21 05:55	28.62	OK	15562	2026-09-21 05:56	29.29	OK
15563	2026-09-21 05:57	29.27	OK	15564	2026-09-21 05:58	28.49	OK
15565	2026-09-21 05:59	29.44	OK	15566	2026-09-21 06:00	30.48	OK
15567	2026-09-21 06:01	29.16	OK	15568	2026-09-21 06:02	29.74	OK
15569	2026-09-21 06:03	28.53	OK	15570	2026-09-21 06:04	28.52	OK
15571	2026-09-21 06:05	29.22	OK	15572	2026-09-21 06:06	28.87	OK
15573	2026-09-21 06:07	29.74	OK	15574	2026-09-21 06:08	27.20	OK
15575	2026-09-21 06:09	28.38	OK	15576	2026-09-21 06:10	28.05	OK
15577	2026-09-21 06:11	29.84	OK	15578	2026-09-21 06:12	28.86	OK
15579	2026-09-21 06:13	28.84	OK	15580	2026-09-21 06:14	27.55	OK
15581	2026-09-21 06:15	27.37	OK	15582	2026-09-21 06:16	28.12	OK
15583	2026-09-21 06:17	28.75	OK	15584	2026-09-21 06:18	28.83	OK
15585	2026-09-21 06:19	28.25	OK	15586	2026-09-21 06:20	28.12	OK
15587	2026-09-21 06:21	28.11	OK	15588	2026-09-21 06:22	29.10	OK
15589	2026-09-21 06:23	29.80	OK	15590	2026-09-21 06:24	29.42	OK
15591	2026-09-21 06:25	30.31	OK	15592	2026-09-21 06:26	28.85	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15593	2026-09-21 06:27	28.64	OK	15594	2026-09-21 06:28	29.66	OK
15595	2026-09-21 06:29	28.53	OK	15596	2026-09-21 06:30	28.35	OK
15597	2026-09-21 06:31	28.29	OK	15598	2026-09-21 06:32	29.84	OK
15599	2026-09-21 06:33	29.99	OK	15600	2026-09-21 06:34	27.80	OK
15601	2026-09-21 06:35	27.53	OK	15602	2026-09-21 06:36	27.70	OK
15603	2026-09-21 06:37	28.90	OK	15604	2026-09-21 06:38	28.30	OK
15605	2026-09-21 06:39	28.70	OK	15606	2026-09-21 06:40	27.46	OK
15607	2026-09-21 06:41	29.62	OK	15608	2026-09-21 06:42	27.55	OK
15609	2026-09-21 06:43	27.97	OK	15610	2026-09-21 06:44	28.53	OK
15611	2026-09-21 06:45	27.56	OK	15612	2026-09-21 06:46	29.09	OK
15613	2026-09-21 06:47	28.45	OK	15614	2026-09-21 06:48	28.64	OK
15615	2026-09-21 06:49	27.87	OK	15616	2026-09-21 06:50	28.48	OK
15617	2026-09-21 06:51	28.71	OK	15618	2026-09-21 06:52	27.57	OK
15619	2026-09-21 06:53	29.77	OK	15620	2026-09-21 06:54	27.71	OK
15621	2026-09-21 06:55	29.44	OK	15622	2026-09-21 06:56	27.80	OK
15623	2026-09-21 06:57	28.86	OK	15624	2026-09-21 06:58	29.00	OK
15625	2026-09-21 06:59	28.56	OK	15626	2026-09-21 07:00	27.85	OK
15627	2026-09-21 07:01	28.06	OK	15628	2026-09-21 07:02	28.21	OK
15629	2026-09-21 07:03	28.65	OK	15630	2026-09-21 07:04	27.53	OK
15631	2026-09-21 07:05	28.54	OK	15632	2026-09-21 07:06	27.32	OK
15633	2026-09-21 07:07	27.82	OK	15634	2026-09-21 07:08	28.38	OK
15635	2026-09-21 07:09	27.65	OK	15636	2026-09-21 07:10	28.66	OK
15637	2026-09-21 07:11	27.83	OK	15638	2026-09-21 07:12	29.47	OK
15639	2026-09-21 07:13	26.65	OK	15640	2026-09-21 07:14	29.02	OK
15641	2026-09-21 07:15	27.54	OK	15642	2026-09-21 07:16	26.94	OK
15643	2026-09-21 07:17	27.60	OK	15644	2026-09-21 07:18	26.52	OK
15645	2026-09-21 07:19	27.96	OK	15646	2026-09-21 07:20	28.35	OK
15647	2026-09-21 07:21	28.99	OK	15648	2026-09-21 07:22	29.10	OK
15649	2026-09-21 07:23	26.79	OK	15650	2026-09-21 07:24	27.47	OK
15651	2026-09-21 07:25	27.32	OK	15652	2026-09-21 07:26	28.76	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15653	2026-09-21 07:27	28.97	OK	15654	2026-09-21 07:28	28.31	OK
15655	2026-09-21 07:29	28.75	OK	15656	2026-09-21 07:30	26.70	OK
15657	2026-09-21 07:31	27.69	OK	15658	2026-09-21 07:32	28.59	OK
15659	2026-09-21 07:33	28.19	OK	15660	2026-09-21 07:34	29.49	OK
15661	2026-09-21 07:35	28.63	OK	15662	2026-09-21 07:36	27.68	OK
15663	2026-09-21 07:37	29.27	OK	15664	2026-09-21 07:38	26.56	OK
15665	2026-09-21 07:39	28.73	OK	15666	2026-09-21 07:40	26.70	OK
15667	2026-09-21 07:41	29.14	OK	15668	2026-09-21 07:42	26.70	OK
15669	2026-09-21 07:43	26.85	OK	15670	2026-09-21 07:44	25.96	OK
15671	2026-09-21 07:45	28.05	OK	15672	2026-09-21 07:46	28.60	OK
15673	2026-09-21 07:47	28.70	OK	15674	2026-09-21 07:48	27.95	OK
15675	2026-09-21 07:49	28.36	OK	15676	2026-09-21 07:50	28.80	OK
15677	2026-09-21 07:51	27.74	OK	15678	2026-09-21 07:52	28.64	OK
15679	2026-09-21 07:53	28.99	OK	15680	2026-09-21 07:54	27.54	OK
15681	2026-09-21 07:55	27.25	OK	15682	2026-09-21 07:56	29.08	OK
15683	2026-09-21 07:57	28.44	OK	15684	2026-09-21 07:58	28.67	OK
15685	2026-09-21 07:59	27.02	OK	15686	2026-09-21 08:00	28.53	OK
15687	2026-09-21 08:01	26.89	OK	15688	2026-09-21 08:02	28.14	OK
15689	2026-09-21 08:03	28.72	OK	15690	2026-09-21 08:04	28.17	OK
15691	2026-09-21 08:05	27.51	OK	15692	2026-09-21 08:06	28.30	OK
15693	2026-09-21 08:07	28.33	OK	15694	2026-09-21 08:08	27.91	OK
15695	2026-09-21 08:09	27.57	OK	15696	2026-09-21 08:10	29.01	OK
15697	2026-09-21 08:11	27.86	OK	15698	2026-09-21 08:12	27.24	OK
15699	2026-09-21 08:13	25.63	OK	15700	2026-09-21 08:14	26.62	OK
15701	2026-09-21 08:15	28.03	OK	15702	2026-09-21 08:16	27.84	OK
15703	2026-09-21 08:17	28.41	OK	15704	2026-09-21 08:18	26.33	OK
15705	2026-09-21 08:19	27.15	OK	15706	2026-09-21 08:20	28.78	OK
15707	2026-09-21 08:21	27.96	OK	15708	2026-09-21 08:22	26.96	OK
15709	2026-09-21 08:23	26.75	OK	15710	2026-09-21 08:24	26.64	OK
15711	2026-09-21 08:25	27.85	OK	15712	2026-09-21 08:26	27.24	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15713	2026-09-21 08:27	26.97	OK	15714	2026-09-21 08:28	27.99	OK
15715	2026-09-21 08:29	27.57	OK	15716	2026-09-21 08:30	27.50	OK
15717	2026-09-21 08:31	27.21	OK	15718	2026-09-21 08:32	27.32	OK
15719	2026-09-21 08:33	27.19	OK	15720	2026-09-21 08:34	27.95	OK
15721	2026-09-21 08:35	28.08	OK	15722	2026-09-21 08:36	27.42	OK
15723	2026-09-21 08:37	27.76	OK	15724	2026-09-21 08:38	27.74	OK
15725	2026-09-21 08:39	27.73	OK	15726	2026-09-21 08:40	27.50	OK
15727	2026-09-21 08:41	28.00	OK	15728	2026-09-21 08:42	27.68	OK
15729	2026-09-21 08:43	27.01	OK	15730	2026-09-21 08:44	26.72	OK
15731	2026-09-21 08:45	26.26	OK	15732	2026-09-21 08:46	26.99	OK
15733	2026-09-21 08:47	26.14	OK	15734	2026-09-21 08:48	29.00	OK
15735	2026-09-21 08:49	27.74	OK	15736	2026-09-21 08:50	26.73	OK
15737	2026-09-21 08:51	25.90	OK	15738	2026-09-21 08:52	27.89	OK
15739	2026-09-21 08:53	25.64	OK	15740	2026-09-21 08:54	28.24	OK
15741	2026-09-21 08:55	26.97	OK	15742	2026-09-21 08:56	26.26	OK
15743	2026-09-21 08:57	28.05	OK	15744	2026-09-21 08:58	27.63	OK
15745	2026-09-21 08:59	28.19	OK	15746	2026-09-21 09:00	26.85	OK
15747	2026-09-21 09:01	27.13	OK	15748	2026-09-21 09:02	26.56	OK
15749	2026-09-21 09:03	26.02	OK	15750	2026-09-21 09:04	28.67	OK
15751	2026-09-21 09:05	26.51	OK	15752	2026-09-21 09:06	26.01	OK
15753	2026-09-21 09:07	26.56	OK	15754	2026-09-21 09:08	26.14	OK
15755	2026-09-21 09:09	26.77	OK	15756	2026-09-21 09:10	26.11	OK
15757	2026-09-21 09:11	27.61	OK	15758	2026-09-21 09:12	28.29	OK
15759	2026-09-21 09:13	26.33	OK	15760	2026-09-21 09:14	26.38	OK
15761	2026-09-21 09:15	27.86	OK	15762	2026-09-21 09:16	26.63	OK
15763	2026-09-21 09:17	28.88	OK	15764	2026-09-21 09:18	25.49	OK
15765	2026-09-21 09:19	27.35	OK	15766	2026-09-21 09:20	25.92	OK
15767	2026-09-21 09:21	26.33	OK	15768	2026-09-21 09:22	26.57	OK
15769	2026-09-21 09:23	26.68	OK	15770	2026-09-21 09:24	26.29	OK
15771	2026-09-21 09:25	27.04	OK	15772	2026-09-21 09:26	26.78	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15773	2026-09-21 09:27	27.44	OK	15774	2026-09-21 09:28	27.19	OK
15775	2026-09-21 09:29	28.65	OK	15776	2026-09-21 09:30	26.95	OK
15777	2026-09-21 09:31	26.64	OK	15778	2026-09-21 09:32	26.92	OK
15779	2026-09-21 09:33	25.54	OK	15780	2026-09-21 09:34	26.86	OK
15781	2026-09-21 09:35	26.21	OK	15782	2026-09-21 09:36	26.15	OK
15783	2026-09-21 09:37	25.11	OK	15784	2026-09-21 09:38	25.67	OK
15785	2026-09-21 09:39	27.50	OK	15786	2026-09-21 09:40	26.88	OK
15787	2026-09-21 09:41	26.65	OK	15788	2026-09-21 09:42	25.31	OK
15789	2026-09-21 09:43	25.91	OK	15790	2026-09-21 09:44	27.34	OK
15791	2026-09-21 09:45	27.37	OK	15792	2026-09-21 09:46	26.46	OK
15793	2026-09-21 09:47	27.07	OK	15794	2026-09-21 09:48	26.78	OK
15795	2026-09-21 09:49	26.45	OK	15796	2026-09-21 09:50	26.18	OK
15797	2026-09-21 09:51	27.12	OK	15798	2026-09-21 09:52	26.20	OK
15799	2026-09-21 09:53	27.66	OK	15800	2026-09-21 09:54	26.66	OK
15801	2026-09-21 09:55	26.78	OK	15802	2026-09-21 09:56	26.35	OK
15803	2026-09-21 09:57	25.02	OK	15804	2026-09-21 09:58	26.66	OK
15805	2026-09-21 09:59	24.82	OK	15806	2026-09-21 10:00	27.93	OK
15807	2026-09-21 10:01	27.49	OK	15808	2026-09-21 10:02	27.04	OK
15809	2026-09-21 10:03	26.49	OK	15810	2026-09-21 10:04	25.40	OK
15811	2026-09-21 10:05	26.18	OK	15812	2026-09-21 10:06	25.61	OK
15813	2026-09-21 10:07	27.48	OK	15814	2026-09-21 10:08	27.70	OK
15815	2026-09-21 10:09	27.30	OK	15816	2026-09-21 10:10	26.87	OK
15817	2026-09-21 10:11	26.63	OK	15818	2026-09-21 10:12	26.96	OK
15819	2026-09-21 10:13	27.45	OK	15820	2026-09-21 10:14	25.43	OK
15821	2026-09-21 10:15	26.18	OK	15822	2026-09-21 10:16	25.03	OK
15823	2026-09-21 10:17	26.01	OK	15824	2026-09-21 10:18	26.83	OK
15825	2026-09-21 10:19	26.81	OK	15826	2026-09-21 10:20	26.14	OK
15827	2026-09-21 10:21	26.59	OK	15828	2026-09-21 10:22	26.62	OK
15829	2026-09-21 10:23	25.17	OK	15830	2026-09-21 10:24	26.71	OK
15831	2026-09-21 10:25	26.63	OK	15832	2026-09-21 10:26	26.01	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15833	2026-09-21 10:27	27.38	OK	15834	2026-09-21 10:28	26.16	OK
15835	2026-09-21 10:29	25.08	OK	15836	2026-09-21 10:30	24.48	OK
15837	2026-09-21 10:31	26.00	OK	15838	2026-09-21 10:32	25.90	OK
15839	2026-09-21 10:33	25.63	OK	15840	2026-09-21 10:34	25.20	OK
15841	2026-09-21 10:35	26.25	OK	15842	2026-09-21 10:36	26.43	OK
15843	2026-09-21 10:37	24.98	OK	15844	2026-09-21 10:38	25.86	OK
15845	2026-09-21 10:39	25.50	OK	15846	2026-09-21 10:40	27.79	OK
15847	2026-09-21 10:41	24.08	OK	15848	2026-09-21 10:42	26.05	OK
15849	2026-09-21 10:43	24.96	OK	15850	2026-09-21 10:44	24.97	OK
15851	2026-09-21 10:45	26.20	OK	15852	2026-09-21 10:46	26.10	OK
15853	2026-09-21 10:47	26.85	OK	15854	2026-09-21 10:48	27.45	OK
15855	2026-09-21 10:49	25.90	OK	15856	2026-09-21 10:50	27.46	OK
15857	2026-09-21 10:51	26.45	OK	15858	2026-09-21 10:52	26.45	OK
15859	2026-09-21 10:53	26.64	OK	15860	2026-09-21 10:54	24.14	OK
15861	2026-09-21 10:55	27.38	OK	15862	2026-09-21 10:56	25.38	OK
15863	2026-09-21 10:57	25.24	OK	15864	2026-09-21 10:58	26.52	OK
15865	2026-09-21 10:59	26.94	OK	15866	2026-09-21 11:00	25.54	OK
15867	2026-09-21 11:01	27.19	OK	15868	2026-09-21 11:02	24.90	OK
15869	2026-09-21 11:03	26.23	OK	15870	2026-09-21 11:04	26.25	OK
15871	2026-09-21 11:05	26.94	OK	15872	2026-09-21 11:06	25.08	OK
15873	2026-09-21 11:07	27.30	OK	15874	2026-09-21 11:08	25.93	OK
15875	2026-09-21 11:09	26.02	OK	15876	2026-09-21 11:10	26.22	OK
15877	2026-09-21 11:11	27.07	OK	15878	2026-09-21 11:12	25.27	OK
15879	2026-09-21 11:13	24.92	OK	15880	2026-09-21 11:14	25.97	OK
15881	2026-09-21 11:15	25.31	OK	15882	2026-09-21 11:16	24.97	OK
15883	2026-09-21 11:17	25.27	OK	15884	2026-09-21 11:18	24.92	OK
15885	2026-09-21 11:19	26.52	OK	15886	2026-09-21 11:20	26.86	OK
15887	2026-09-21 11:21	26.86	OK	15888	2026-09-21 11:22	26.45	OK
15889	2026-09-21 11:23	26.08	OK	15890	2026-09-21 11:24	27.06	OK
15891	2026-09-21 11:25	25.04	OK	15892	2026-09-21 11:26	24.30	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15893	2026-09-21 11:27	26.46	OK	15894	2026-09-21 11:28	25.49	OK
15895	2026-09-21 11:29	26.31	OK	15896	2026-09-21 11:30	27.54	OK
15897	2026-09-21 11:31	25.93	OK	15898	2026-09-21 11:32	26.42	OK
15899	2026-09-21 11:33	27.32	OK	15900	2026-09-21 11:34	24.95	OK
15901	2026-09-21 11:35	26.31	OK	15902	2026-09-21 11:36	26.20	OK
15903	2026-09-21 11:37	26.92	OK	15904	2026-09-21 11:38	26.12	OK
15905	2026-09-21 11:39	25.79	OK	15906	2026-09-21 11:40	25.75	OK
15907	2026-09-21 11:41	26.48	OK	15908	2026-09-21 11:42	26.65	OK
15909	2026-09-21 11:43	25.13	OK	15910	2026-09-21 11:44	26.86	OK
15911	2026-09-21 11:45	26.19	OK	15912	2026-09-21 11:46	25.11	OK
15913	2026-09-21 11:47	26.89	OK	15914	2026-09-21 11:48	26.02	OK
15915	2026-09-21 11:49	26.91	OK	15916	2026-09-21 11:50	26.70	OK
15917	2026-09-21 11:51	25.51	OK	15918	2026-09-21 11:52	26.92	OK
15919	2026-09-21 11:53	25.28	OK	15920	2026-09-21 11:54	26.21	OK
15921	2026-09-21 11:55	26.61	OK	15922	2026-09-21 11:56	26.44	OK
15923	2026-09-21 11:57	24.92	OK	15924	2026-09-21 11:58	24.63	OK
15925	2026-09-21 11:59	25.61	OK	15926	2026-09-21 12:00	26.08	OK
15927	2026-09-21 12:01	25.33	OK	15928	2026-09-21 12:02	25.98	OK
15929	2026-09-21 12:03	25.68	OK	15930	2026-09-21 12:04	24.29	OK
15931	2026-09-21 12:05	24.97	OK	15932	2026-09-21 12:06	26.77	OK
15933	2026-09-21 12:07	26.64	OK	15934	2026-09-21 12:08	25.46	OK
15935	2026-09-21 12:09	26.60	OK	15936	2026-09-21 12:10	26.52	OK
15937	2026-09-21 12:11	25.60	OK	15938	2026-09-21 12:12	27.14	OK
15939	2026-09-21 12:13	25.52	OK	15940	2026-09-21 12:14	25.80	OK
15941	2026-09-21 12:15	25.41	OK	15942	2026-09-21 12:16	25.89	OK
15943	2026-09-21 12:17	25.31	OK	15944	2026-09-21 12:18	26.32	OK
15945	2026-09-21 12:19	25.75	OK	15946	2026-09-21 12:20	26.67	OK
15947	2026-09-21 12:21	25.78	OK	15948	2026-09-21 12:22	25.85	OK
15949	2026-09-21 12:23	24.18	OK	15950	2026-09-21 12:24	26.82	OK
15951	2026-09-21 12:25	25.36	OK	15952	2026-09-21 12:26	26.51	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
15953	2026-09-21 12:27	26.61	OK	15954	2026-09-21 12:28	25.01	OK
15955	2026-09-21 12:29	26.36	OK	15956	2026-09-21 12:30	24.31	OK
15957	2026-09-21 12:31	25.64	OK	15958	2026-09-21 12:32	25.44	OK
15959	2026-09-21 12:33	25.98	OK	15960	2026-09-21 12:34	26.17	OK
15961	2026-09-21 12:35	26.37	OK	15962	2026-09-21 12:36	27.77	OK
15963	2026-09-21 12:37	25.56	OK	15964	2026-09-21 12:38	25.97	OK
15965	2026-09-21 12:39	25.85	OK	15966	2026-09-21 12:40	24.91	OK
15967	2026-09-21 12:41	26.13	OK	15968	2026-09-21 12:42	27.32	OK
15969	2026-09-21 12:43	25.69	OK	15970	2026-09-21 12:44	25.33	OK
15971	2026-09-21 12:45	25.83	OK	15972	2026-09-21 12:46	26.29	OK
15973	2026-09-21 12:47	25.90	OK	15974	2026-09-21 12:48	25.45	OK
15975	2026-09-21 12:49	25.22	OK	15976	2026-09-21 12:50	25.71	OK
15977	2026-09-21 12:51	24.32	OK	15978	2026-09-21 12:52	26.15	OK
15979	2026-09-21 12:53	25.33	OK	15980	2026-09-21 12:54	25.48	OK
15981	2026-09-21 12:55	26.90	OK	15982	2026-09-21 12:56	26.08	OK
15983	2026-09-21 12:57	26.61	OK	15984	2026-09-21 12:58	25.92	OK
15985	2026-09-21 12:59	24.36	OK	15986	2026-09-21 13:00	26.74	OK
15987	2026-09-21 13:01	25.80	OK	15988	2026-09-21 13:02	25.85	OK
15989	2026-09-21 13:03	26.39	OK	15990	2026-09-21 13:04	26.25	OK
15991	2026-09-21 13:05	27.34	OK	15992	2026-09-21 13:06	24.49	OK
15993	2026-09-21 13:07	24.66	OK	15994	2026-09-21 13:08	26.65	OK
15995	2026-09-21 13:09	25.89	OK	15996	2026-09-21 13:10	25.81	OK
15997	2026-09-21 13:11	25.80	OK	15998	2026-09-21 13:12	26.47	OK
15999	2026-09-21 13:13	25.59	OK	16000	2026-09-21 13:14	26.18	OK
16001	2026-09-21 13:15	25.78	OK	16002	2026-09-21 13:16	26.71	OK
16003	2026-09-21 13:17	26.21	OK	16004	2026-09-21 13:18	25.86	OK
16005	2026-09-21 13:19	26.18	OK	16006	2026-09-21 13:20	25.24	OK
16007	2026-09-21 13:21	25.26	OK	16008	2026-09-21 13:22	25.64	OK
16009	2026-09-21 13:23	25.42	OK	16010	2026-09-21 13:24	25.85	OK
16011	2026-09-21 13:25	24.04	OK	16012	2026-09-21 13:26	26.35	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16013	2026-09-21 13:27	26.88	OK	16014	2026-09-21 13:28	25.48	OK
16015	2026-09-21 13:29	25.49	OK	16016	2026-09-21 13:30	25.57	OK
16017	2026-09-21 13:31	24.98	OK	16018	2026-09-21 13:32	25.78	OK
16019	2026-09-21 13:33	26.96	OK	16020	2026-09-21 13:34	26.42	OK
16021	2026-09-21 13:35	26.37	OK	16022	2026-09-21 13:36	25.27	OK
16023	2026-09-21 13:37	25.65	OK	16024	2026-09-21 13:38	25.43	OK
16025	2026-09-21 13:39	25.99	OK	16026	2026-09-21 13:40	26.00	OK
16027	2026-09-21 13:41	24.28	OK	16028	2026-09-21 13:42	25.86	OK
16029	2026-09-21 13:43	26.95	OK	16030	2026-09-21 13:44	24.69	OK
16031	2026-09-21 13:45	25.62	OK	16032	2026-09-21 13:46	25.96	OK
16033	2026-09-21 13:47	26.30	OK	16034	2026-09-21 13:48	26.26	OK
16035	2026-09-21 13:49	26.14	OK	16036	2026-09-21 13:50	24.89	OK
16037	2026-09-21 13:51	25.96	OK	16038	2026-09-21 13:52	25.81	OK
16039	2026-09-21 13:53	25.50	OK	16040	2026-09-21 13:54	25.24	OK
16041	2026-09-21 13:55	26.71	OK	16042	2026-09-21 13:56	25.32	OK
16043	2026-09-21 13:57	25.68	OK	16044	2026-09-21 13:58	26.00	OK
16045	2026-09-21 13:59	26.16	OK	16046	2026-09-21 14:00	26.30	OK
16047	2026-09-21 14:01	25.48	OK	16048	2026-09-21 14:02	26.97	OK
16049	2026-09-21 14:03	24.56	OK	16050	2026-09-21 14:04	26.73	OK
16051	2026-09-21 14:05	25.53	OK	16052	2026-09-21 14:06	25.09	OK
16053	2026-09-21 14:07	26.02	OK	16054	2026-09-21 14:08	26.30	OK
16055	2026-09-21 14:09	24.71	OK	16056	2026-09-21 14:10	27.06	OK
16057	2026-09-21 14:11	25.45	OK	16058	2026-09-21 14:12	25.16	OK
16059	2026-09-21 14:13	26.35	OK	16060	2026-09-21 14:14	26.86	OK
16061	2026-09-21 14:15	25.18	OK	16062	2026-09-21 14:16	26.95	OK
16063	2026-09-21 14:17	25.00	OK	16064	2026-09-21 14:18	26.12	OK
16065	2026-09-21 14:19	26.57	OK	16066	2026-09-21 14:20	26.47	OK
16067	2026-09-21 14:21	25.72	OK	16068	2026-09-21 14:22	25.95	OK
16069	2026-09-21 14:23	26.26	OK	16070	2026-09-21 14:24	24.48	OK
16071	2026-09-21 14:25	27.35	OK	16072	2026-09-21 14:26	26.04	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16073	2026-09-21 14:27	26.54	OK	16074	2026-09-21 14:28	26.15	OK
16075	2026-09-21 14:29	26.48	OK	16076	2026-09-21 14:30	25.62	OK
16077	2026-09-21 14:31	25.04	OK	16078	2026-09-21 14:32	26.27	OK
16079	2026-09-21 14:33	26.17	OK	16080	2026-09-21 14:34	25.93	OK
16081	2026-09-21 14:35	25.87	OK	16082	2026-09-21 14:36	24.45	OK
16083	2026-09-21 14:37	26.05	OK	16084	2026-09-21 14:38	26.42	OK
16085	2026-09-21 14:39	25.79	OK	16086	2026-09-21 14:40	25.80	OK
16087	2026-09-21 14:41	26.34	OK	16088	2026-09-21 14:42	26.52	OK
16089	2026-09-21 14:43	25.58	OK	16090	2026-09-21 14:44	25.25	OK
16091	2026-09-21 14:45	24.68	OK	16092	2026-09-21 14:46	25.96	OK
16093	2026-09-21 14:47	24.57	OK	16094	2026-09-21 14:48	26.07	OK
16095	2026-09-21 14:49	25.65	OK	16096	2026-09-21 14:50	26.09	OK
16097	2026-09-21 14:51	25.73	OK	16098	2026-09-21 14:52	25.68	OK
16099	2026-09-21 14:53	26.07	OK	16100	2026-09-21 14:54	25.88	OK
16101	2026-09-21 14:55	25.97	OK	16102	2026-09-21 14:56	26.44	OK
16103	2026-09-21 14:57	24.71	OK	16104	2026-09-21 14:58	26.17	OK
16105	2026-09-21 14:59	25.13	OK	16106	2026-09-21 15:00	25.58	OK
16107	2026-09-21 15:01	25.35	OK	16108	2026-09-21 15:02	25.72	OK
16109	2026-09-21 15:03	26.55	OK	16110	2026-09-21 15:04	25.55	OK
16111	2026-09-21 15:05	26.03	OK	16112	2026-09-21 15:06	26.09	OK
16113	2026-09-21 15:07	25.30	OK	16114	2026-09-21 15:08	26.46	OK
16115	2026-09-21 15:09	25.88	OK	16116	2026-09-21 15:10	26.30	OK
16117	2026-09-21 15:11	24.28	OK	16118	2026-09-21 15:12	27.51	OK
16119	2026-09-21 15:13	26.75	OK	16120	2026-09-21 15:14	25.56	OK
16121	2026-09-21 15:15	26.45	OK	16122	2026-09-21 15:16	24.16	OK
16123	2026-09-21 15:17	28.05	OK	16124	2026-09-21 15:18	25.25	OK
16125	2026-09-21 15:19	24.32	OK	16126	2026-09-21 15:20	25.47	OK
16127	2026-09-21 15:21	26.05	OK	16128	2026-09-21 15:22	26.59	OK
16129	2026-09-21 15:23	24.80	OK	16130	2026-09-21 15:24	26.22	OK
16131	2026-09-21 15:25	27.68	OK	16132	2026-09-21 15:26	26.22	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16133	2026-09-21 15:27	24.79	OK	16134	2026-09-21 15:28	25.54	OK
16135	2026-09-21 15:29	24.42	OK	16136	2026-09-21 15:30	25.36	OK
16137	2026-09-21 15:31	27.21	OK	16138	2026-09-21 15:32	25.99	OK
16139	2026-09-21 15:33	25.31	OK	16140	2026-09-21 15:34	27.92	OK
16141	2026-09-21 15:35	24.45	OK	16142	2026-09-21 15:36	26.81	OK
16143	2026-09-21 15:37	26.80	OK	16144	2026-09-21 15:38	26.25	OK
16145	2026-09-21 15:39	27.23	OK	16146	2026-09-21 15:40	25.62	OK
16147	2026-09-21 15:41	26.26	OK	16148	2026-09-21 15:42	25.98	OK
16149	2026-09-21 15:43	26.06	OK	16150	2026-09-21 15:44	26.50	OK
16151	2026-09-21 15:45	25.67	OK	16152	2026-09-21 15:46	26.12	OK
16153	2026-09-21 15:47	25.07	OK	16154	2026-09-21 15:48	25.49	OK
16155	2026-09-21 15:49	26.65	OK	16156	2026-09-21 15:50	27.44	OK
16157	2026-09-21 15:51	25.69	OK	16158	2026-09-21 15:52	25.98	OK
16159	2026-09-21 15:53	25.90	OK	16160	2026-09-21 15:54	26.94	OK
16161	2026-09-21 15:55	27.62	OK	16162	2026-09-21 15:56	27.61	OK
16163	2026-09-21 15:57	26.24	OK	16164	2026-09-21 15:58	26.53	OK
16165	2026-09-21 15:59	27.62	OK	16166	2026-09-21 16:00	27.20	OK
16167	2026-09-21 16:01	27.45	OK	16168	2026-09-21 16:02	24.91	OK
16169	2026-09-21 16:03	26.58	OK	16170	2026-09-21 16:04	27.43	OK
16171	2026-09-21 16:05	25.53	OK	16172	2026-09-21 16:06	25.86	OK
16173	2026-09-21 16:07	25.34	OK	16174	2026-09-21 16:08	27.33	OK
16175	2026-09-21 16:09	27.46	OK	16176	2026-09-21 16:10	26.04	OK
16177	2026-09-21 16:11	26.39	OK	16178	2026-09-21 16:12	25.90	OK
16179	2026-09-21 16:13	25.46	OK	16180	2026-09-21 16:14	26.08	OK
16181	2026-09-21 16:15	25.43	OK	16182	2026-09-21 16:16	24.91	OK
16183	2026-09-21 16:17	26.24	OK	16184	2026-09-21 16:18	24.72	OK
16185	2026-09-21 16:19	26.12	OK	16186	2026-09-21 16:20	25.99	OK
16187	2026-09-21 16:21	27.19	OK	16188	2026-09-21 16:22	25.12	OK
16189	2026-09-21 16:23	25.12	OK	16190	2026-09-21 16:24	27.15	OK
16191	2026-09-21 16:25	27.54	OK	16192	2026-09-21 16:26	25.22	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16193	2026-09-21 16:27	26.26	OK	16194	2026-09-21 16:28	27.01	OK
16195	2026-09-21 16:29	26.36	OK	16196	2026-09-21 16:30	25.98	OK
16197	2026-09-21 16:31	26.65	OK	16198	2026-09-21 16:32	25.48	OK
16199	2026-09-21 16:33	26.95	OK	16200	2026-09-21 16:34	27.12	OK
16201	2026-09-21 16:35	25.71	OK	16202	2026-09-21 16:36	26.59	OK
16203	2026-09-21 16:37	25.66	OK	16204	2026-09-21 16:38	26.44	OK
16205	2026-09-21 16:39	24.88	OK	16206	2026-09-21 16:40	24.81	OK
16207	2026-09-21 16:41	27.74	OK	16208	2026-09-21 16:42	26.08	OK
16209	2026-09-21 16:43	26.70	OK	16210	2026-09-21 16:44	25.01	OK
16211	2026-09-21 16:45	25.74	OK	16212	2026-09-21 16:46	27.67	OK
16213	2026-09-21 16:47	26.22	OK	16214	2026-09-21 16:48	27.03	OK
16215	2026-09-21 16:49	27.05	OK	16216	2026-09-21 16:50	26.65	OK
16217	2026-09-21 16:51	27.81	OK	16218	2026-09-21 16:52	27.09	OK
16219	2026-09-21 16:53	25.96	OK	16220	2026-09-21 16:54	25.53	OK
16221	2026-09-21 16:55	25.50	OK	16222	2026-09-21 16:56	26.86	OK
16223	2026-09-21 16:57	26.60	OK	16224	2026-09-21 16:58	25.74	OK
16225	2026-09-21 16:59	25.73	OK	16226	2026-09-21 17:00	26.66	OK
16227	2026-09-21 17:01	26.54	OK	16228	2026-09-21 17:02	25.63	OK
16229	2026-09-21 17:03	26.23	OK	16230	2026-09-21 17:04	26.43	OK
16231	2026-09-21 17:05	24.96	OK	16232	2026-09-21 17:06	28.11	OK
16233	2026-09-21 17:07	27.98	OK	16234	2026-09-21 17:08	26.14	OK
16235	2026-09-21 17:09	27.42	OK	16236	2026-09-21 17:10	26.43	OK
16237	2026-09-21 17:11	27.34	OK	16238	2026-09-21 17:12	26.75	OK
16239	2026-09-21 17:13	27.57	OK	16240	2026-09-21 17:14	27.45	OK
16241	2026-09-21 17:15	27.07	OK	16242	2026-09-21 17:16	28.17	OK
16243	2026-09-21 17:17	25.29	OK	16244	2026-09-21 17:18	27.37	OK
16245	2026-09-21 17:19	27.49	OK	16246	2026-09-21 17:20	26.36	OK
16247	2026-09-21 17:21	26.19	OK	16248	2026-09-21 17:22	26.20	OK
16249	2026-09-21 17:23	26.50	OK	16250	2026-09-21 17:24	26.62	OK
16251	2026-09-21 17:25	26.10	OK	16252	2026-09-21 17:26	26.90	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16253	2026-09-21 17:27	25.96	OK	16254	2026-09-21 17:28	26.26	OK
16255	2026-09-21 17:29	26.70	OK	16256	2026-09-21 17:30	27.20	OK
16257	2026-09-21 17:31	26.98	OK	16258	2026-09-21 17:32	28.45	OK
16259	2026-09-21 17:33	26.63	OK	16260	2026-09-21 17:34	26.09	OK
16261	2026-09-21 17:35	27.44	OK	16262	2026-09-21 17:36	28.80	OK
16263	2026-09-21 17:37	26.42	OK	16264	2026-09-21 17:38	26.87	OK
16265	2026-09-21 17:39	25.47	OK	16266	2026-09-21 17:40	28.41	OK
16267	2026-09-21 17:41	26.00	OK	16268	2026-09-21 17:42	26.99	OK
16269	2026-09-21 17:43	27.28	OK	16270	2026-09-21 17:44	26.81	OK
16271	2026-09-21 17:45	26.74	OK	16272	2026-09-21 17:46	26.81	OK
16273	2026-09-21 17:47	27.46	OK	16274	2026-09-21 17:48	26.77	OK
16275	2026-09-21 17:49	27.34	OK	16276	2026-09-21 17:50	27.07	OK
16277	2026-09-21 17:51	25.96	OK	16278	2026-09-21 17:52	27.61	OK
16279	2026-09-21 17:53	27.36	OK	16280	2026-09-21 17:54	26.60	OK
16281	2026-09-21 17:55	27.48	OK	16282	2026-09-21 17:56	27.18	OK
16283	2026-09-21 17:57	26.39	OK	16284	2026-09-21 17:58	27.28	OK
16285	2026-09-21 17:59	25.54	OK	16286	2026-09-21 18:00	25.92	OK
16287	2026-09-21 18:01	26.11	OK	16288	2026-09-21 18:02	27.81	OK
16289	2026-09-21 18:03	27.12	OK	16290	2026-09-21 18:04	27.08	OK
16291	2026-09-21 18:05	26.92	OK	16292	2026-09-21 18:06	25.86	OK
16293	2026-09-21 18:07	25.88	OK	16294	2026-09-21 18:08	27.78	OK
16295	2026-09-21 18:09	27.79	OK	16296	2026-09-21 18:10	27.41	OK
16297	2026-09-21 18:11	27.20	OK	16298	2026-09-21 18:12	28.36	OK
16299	2026-09-21 18:13	27.89	OK	16300	2026-09-21 18:14	27.07	OK
16301	2026-09-21 18:15	28.47	OK	16302	2026-09-21 18:16	27.17	OK
16303	2026-09-21 18:17	28.14	OK	16304	2026-09-21 18:18	28.35	OK
16305	2026-09-21 18:19	27.26	OK	16306	2026-09-21 18:20	27.55	OK
16307	2026-09-21 18:21	26.92	OK	16308	2026-09-21 18:22	26.40	OK
16309	2026-09-21 18:23	26.68	OK	16310	2026-09-21 18:24	27.70	OK
16311	2026-09-21 18:25	27.20	OK	16312	2026-09-21 18:26	26.78	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16313	2026-09-21 18:27	26.28	OK	16314	2026-09-21 18:28	26.69	OK
16315	2026-09-21 18:29	27.83	OK	16316	2026-09-21 18:30	27.16	OK
16317	2026-09-21 18:31	26.08	OK	16318	2026-09-21 18:32	27.95	OK
16319	2026-09-21 18:33	27.75	OK	16320	2026-09-21 18:34	26.68	OK
16321	2026-09-21 18:35	27.24	OK	16322	2026-09-21 18:36	27.53	OK
16323	2026-09-21 18:37	27.51	OK	16324	2026-09-21 18:38	27.69	OK
16325	2026-09-21 18:39	29.08	OK	16326	2026-09-21 18:40	27.21	OK
16327	2026-09-21 18:41	28.46	OK	16328	2026-09-21 18:42	28.50	OK
16329	2026-09-21 18:43	26.76	OK	16330	2026-09-21 18:44	25.95	OK
16331	2026-09-21 18:45	27.50	OK	16332	2026-09-21 18:46	26.93	OK
16333	2026-09-21 18:47	28.59	OK	16334	2026-09-21 18:48	29.39	OK
16335	2026-09-21 18:49	27.42	OK	16336	2026-09-21 18:50	27.22	OK
16337	2026-09-21 18:51	26.81	OK	16338	2026-09-21 18:52	27.84	OK
16339	2026-09-21 18:53	27.38	OK	16340	2026-09-21 18:54	26.60	OK
16341	2026-09-21 18:55	28.20	OK	16342	2026-09-21 18:56	26.79	OK
16343	2026-09-21 18:57	27.32	OK	16344	2026-09-21 18:58	25.89	OK
16345	2026-09-21 18:59	26.96	OK	16346	2026-09-21 19:00	28.47	OK
16347	2026-09-21 19:01	27.41	OK	16348	2026-09-21 19:02	27.61	OK
16349	2026-09-21 19:03	27.45	OK	16350	2026-09-21 19:04	29.25	OK
16351	2026-09-21 19:05	28.61	OK	16352	2026-09-21 19:06	26.10	OK
16353	2026-09-21 19:07	27.46	OK	16354	2026-09-21 19:08	28.34	OK
16355	2026-09-21 19:09	28.30	OK	16356	2026-09-21 19:10	28.50	OK
16357	2026-09-21 19:11	27.66	OK	16358	2026-09-21 19:12	28.02	OK
16359	2026-09-21 19:13	27.16	OK	16360	2026-09-21 19:14	26.66	OK
16361	2026-09-21 19:15	28.32	OK	16362	2026-09-21 19:16	27.54	OK
16363	2026-09-21 19:17	28.40	OK	16364	2026-09-21 19:18	28.13	OK
16365	2026-09-21 19:19	29.05	OK	16366	2026-09-21 19:20	27.75	OK
16367	2026-09-21 19:21	28.88	OK	16368	2026-09-21 19:22	27.06	OK
16369	2026-09-21 19:23	28.34	OK	16370	2026-09-21 19:24	28.70	OK
16371	2026-09-21 19:25	27.99	OK	16372	2026-09-21 19:26	28.33	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16373	2026-09-21 19:27	28.54	OK	16374	2026-09-21 19:28	28.45	OK
16375	2026-09-21 19:29	27.46	OK	16376	2026-09-21 19:30	28.22	OK
16377	2026-09-21 19:31	27.52	OK	16378	2026-09-21 19:32	27.65	OK
16379	2026-09-21 19:33	27.71	OK	16380	2026-09-21 19:34	28.03	OK
16381	2026-09-21 19:35	28.77	OK	16382	2026-09-21 19:36	28.97	OK
16383	2026-09-21 19:37	28.17	OK	16384	2026-09-21 19:38	27.90	OK
16385	2026-09-21 19:39	28.88	OK	16386	2026-09-21 19:40	27.58	OK
16387	2026-09-21 19:41	27.99	OK	16388	2026-09-21 19:42	27.23	OK
16389	2026-09-21 19:43	29.22	OK	16390	2026-09-21 19:44	27.78	OK
16391	2026-09-21 19:45	28.30	OK	16392	2026-09-21 19:46	26.75	OK
16393	2026-09-21 19:47	27.76	OK	16394	2026-09-21 19:48	27.14	OK
16395	2026-09-21 19:49	28.29	OK	16396	2026-09-21 19:50	27.03	OK
16397	2026-09-21 19:51	28.76	OK	16398	2026-09-21 19:52	28.82	OK
16399	2026-09-21 19:53	28.67	OK	16400	2026-09-21 19:54	27.59	OK
16401	2026-09-21 19:55	28.63	OK	16402	2026-09-21 19:56	28.74	OK
16403	2026-09-21 19:57	28.20	OK	16404	2026-09-21 19:58	28.90	OK
16405	2026-09-21 19:59	29.33	OK	16406	2026-09-21 20:00	30.04	OK
16407	2026-09-21 20:01	29.03	OK	16408	2026-09-21 20:02	28.21	OK
16409	2026-09-21 20:03	28.31	OK	16410	2026-09-21 20:04	28.54	OK
16411	2026-09-21 20:05	28.45	OK	16412	2026-09-21 20:06	27.53	OK
16413	2026-09-21 20:07	27.99	OK	16414	2026-09-21 20:08	28.57	OK
16415	2026-09-21 20:09	28.37	OK	16416	2026-09-21 20:10	28.15	OK
16417	2026-09-21 20:11	27.97	OK	16418	2026-09-21 20:12	28.44	OK
16419	2026-09-21 20:13	28.57	OK	16420	2026-09-21 20:14	28.14	OK
16421	2026-09-21 20:15	28.65	OK	16422	2026-09-21 20:16	28.78	OK
16423	2026-09-21 20:17	27.39	OK	16424	2026-09-21 20:18	28.33	OK
16425	2026-09-21 20:19	27.83	OK	16426	2026-09-21 20:20	28.81	OK
16427	2026-09-21 20:21	29.71	OK	16428	2026-09-21 20:22	28.03	OK
16429	2026-09-21 20:23	28.83	OK	16430	2026-09-21 20:24	29.18	OK
16431	2026-09-21 20:25	28.39	OK	16432	2026-09-21 20:26	27.90	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16433	2026-09-21 20:27	29.51	OK	16434	2026-09-21 20:28	30.19	OK
16435	2026-09-21 20:29	27.08	OK	16436	2026-09-21 20:30	28.10	OK
16437	2026-09-21 20:31	28.77	OK	16438	2026-09-21 20:32	28.70	OK
16439	2026-09-21 20:33	28.74	OK	16440	2026-09-21 20:34	29.26	OK
16441	2026-09-21 20:35	27.45	OK	16442	2026-09-21 20:36	28.83	OK
16443	2026-09-21 20:37	29.36	OK	16444	2026-09-21 20:38	27.60	OK
16445	2026-09-21 20:39	29.40	OK	16446	2026-09-21 20:40	30.16	OK
16447	2026-09-21 20:41	28.40	OK	16448	2026-09-21 20:42	28.30	OK
16449	2026-09-21 20:43	29.72	OK	16450	2026-09-21 20:44	28.70	OK
16451	2026-09-21 20:45	28.28	OK	16452	2026-09-21 20:46	29.16	OK
16453	2026-09-21 20:47	27.89	OK	16454	2026-09-21 20:48	29.29	OK
16455	2026-09-21 20:49	29.40	OK	16456	2026-09-21 20:50	29.87	OK
16457	2026-09-21 20:51	29.24	OK	16458	2026-09-21 20:52	28.84	OK
16459	2026-09-21 20:53	28.03	OK	16460	2026-09-21 20:54	30.07	OK
16461	2026-09-21 20:55	29.49	OK	16462	2026-09-21 20:56	29.38	OK
16463	2026-09-21 20:57	29.72	OK	16464	2026-09-21 20:58	27.03	OK
16465	2026-09-21 20:59	29.38	OK	16466	2026-09-21 21:00	29.91	OK
16467	2026-09-21 21:01	29.95	OK	16468	2026-09-21 21:02	29.11	OK
16469	2026-09-21 21:03	28.79	OK	16470	2026-09-21 21:04	29.24	OK
16471	2026-09-21 21:05	28.97	OK	16472	2026-09-21 21:06	27.40	OK
16473	2026-09-21 21:07	29.34	OK	16474	2026-09-21 21:08	28.09	OK
16475	2026-09-21 21:09	29.64	OK	16476	2026-09-21 21:10	29.79	OK
16477	2026-09-21 21:11	27.59	OK	16478	2026-09-21 21:12	28.33	OK
16479	2026-09-21 21:13	29.72	OK	16480	2026-09-21 21:14	29.48	OK
16481	2026-09-21 21:15	29.33	OK	16482	2026-09-21 21:16	29.72	OK
16483	2026-09-21 21:17	30.60	OK	16484	2026-09-21 21:18	28.84	OK
16485	2026-09-21 21:19	28.90	OK	16486	2026-09-21 21:20	29.96	OK
16487	2026-09-21 21:21	29.30	OK	16488	2026-09-21 21:22	27.60	OK
16489	2026-09-21 21:23	29.95	OK	16490	2026-09-21 21:24	29.82	OK
16491	2026-09-21 21:25	28.75	OK	16492	2026-09-21 21:26	28.81	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16493	2026-09-21 21:27	28.42	OK	16494	2026-09-21 21:28	28.21	OK
16495	2026-09-21 21:29	28.83	OK	16496	2026-09-21 21:30	27.61	OK
16497	2026-09-21 21:31	29.30	OK	16498	2026-09-21 21:32	29.60	OK
16499	2026-09-21 21:33	29.47	OK	16500	2026-09-21 21:34	28.73	OK
16501	2026-09-21 21:35	28.27	OK	16502	2026-09-21 21:36	29.90	OK
16503	2026-09-21 21:37	27.58	OK	16504	2026-09-21 21:38	30.65	OK
16505	2026-09-21 21:39	28.61	OK	16506	2026-09-21 21:40	30.68	OK
16507	2026-09-21 21:41	29.78	OK	16508	2026-09-21 21:42	29.19	OK
16509	2026-09-21 21:43	27.90	OK	16510	2026-09-21 21:44	29.07	OK
16511	2026-09-21 21:45	29.05	OK	16512	2026-09-21 21:46	29.25	OK
16513	2026-09-21 21:47	28.69	OK	16514	2026-09-21 21:48	28.68	OK
16515	2026-09-21 21:49	27.66	OK	16516	2026-09-21 21:50	27.70	OK
16517	2026-09-21 21:51	30.06	OK	16518	2026-09-21 21:52	28.79	OK
16519	2026-09-21 21:53	29.93	OK	16520	2026-09-21 21:54	29.72	OK
16521	2026-09-21 21:55	29.15	OK	16522	2026-09-21 21:56	29.04	OK
16523	2026-09-21 21:57	29.63	OK	16524	2026-09-21 21:58	30.25	OK
16525	2026-09-21 21:59	28.77	OK	16526	2026-09-21 22:00	27.87	OK
16527	2026-09-21 22:01	29.59	OK	16528	2026-09-21 22:02	28.82	OK
16529	2026-09-21 22:03	29.32	OK	16530	2026-09-21 22:04	29.36	OK
16531	2026-09-21 22:05	30.19	OK	16532	2026-09-21 22:06	29.26	OK
16533	2026-09-21 22:07	29.63	OK	16534	2026-09-21 22:08	29.86	OK
16535	2026-09-21 22:09	30.81	OK	16536	2026-09-21 22:10	30.61	OK
16537	2026-09-21 22:11	29.26	OK	16538	2026-09-21 22:12	29.32	OK
16539	2026-09-21 22:13	30.55	OK	16540	2026-09-21 22:14	29.69	OK
16541	2026-09-21 22:15	29.47	OK	16542	2026-09-21 22:16	29.80	OK
16543	2026-09-21 22:17	30.40	OK	16544	2026-09-21 22:18	29.27	OK
16545	2026-09-21 22:19	29.43	OK	16546	2026-09-21 22:20	29.32	OK
16547	2026-09-21 22:21	29.30	OK	16548	2026-09-21 22:22	29.68	OK
16549	2026-09-21 22:23	28.69	OK	16550	2026-09-21 22:24	30.06	OK
16551	2026-09-21 22:25	30.26	OK	16552	2026-09-21 22:26	29.22	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16553	2026-09-21 22:27	30.83	OK	16554	2026-09-21 22:28	30.04	OK
16555	2026-09-21 22:29	29.82	OK	16556	2026-09-21 22:30	30.29	OK
16557	2026-09-21 22:31	29.57	OK	16558	2026-09-21 22:32	30.50	OK
16559	2026-09-21 22:33	29.92	OK	16560	2026-09-21 22:34	28.63	OK
16561	2026-09-21 22:35	31.03	OK	16562	2026-09-21 22:36	29.75	OK
16563	2026-09-21 22:37	30.13	OK	16564	2026-09-21 22:38	29.17	OK
16565	2026-09-21 22:39	29.97	OK	16566	2026-09-21 22:40	29.21	OK
16567	2026-09-21 22:41	29.81	OK	16568	2026-09-21 22:42	29.04	OK
16569	2026-09-21 22:43	28.99	OK	16570	2026-09-21 22:44	29.78	OK
16571	2026-09-21 22:45	29.69	OK	16572	2026-09-21 22:46	30.47	OK
16573	2026-09-21 22:47	29.07	OK	16574	2026-09-21 22:48	29.72	OK
16575	2026-09-21 22:49	29.60	OK	16576	2026-09-21 22:50	28.88	OK
16577	2026-09-21 22:51	30.54	OK	16578	2026-09-21 22:52	29.52	OK
16579	2026-09-21 22:53	28.29	OK	16580	2026-09-21 22:54	30.31	OK
16581	2026-09-21 22:55	29.05	OK	16582	2026-09-21 22:56	29.64	OK
16583	2026-09-21 22:57	30.03	OK	16584	2026-09-21 22:58	28.91	OK
16585	2026-09-21 22:59	28.18	OK	16586	2026-09-21 23:00	28.90	OK
16587	2026-09-21 23:01	28.85	OK	16588	2026-09-21 23:02	29.57	OK
16589	2026-09-21 23:03	29.04	OK	16590	2026-09-21 23:04	29.57	OK
16591	2026-09-21 23:05	29.90	OK	16592	2026-09-21 23:06	28.88	OK
16593	2026-09-21 23:07	29.65	OK	16594	2026-09-21 23:08	29.26	OK
16595	2026-09-21 23:09	28.56	OK	16596	2026-09-21 23:10	29.98	OK
16597	2026-09-21 23:11	28.59	OK	16598	2026-09-21 23:12	28.24	OK
16599	2026-09-21 23:13	30.11	OK	16600	2026-09-21 23:14	29.58	OK
16601	2026-09-21 23:15	31.08	OK	16602	2026-09-21 23:16	30.98	OK
16603	2026-09-21 23:17	31.16	OK	16604	2026-09-21 23:18	30.25	OK
16605	2026-09-21 23:19	29.18	OK	16606	2026-09-21 23:20	29.97	OK
16607	2026-09-21 23:21	29.85	OK	16608	2026-09-21 23:22	30.28	OK
16609	2026-09-21 23:23	29.04	OK	16610	2026-09-21 23:24	28.79	OK
16611	2026-09-21 23:25	30.62	OK	16612	2026-09-21 23:26	30.10	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16613	2026-09-21 23:27	30.50	OK	16614	2026-09-21 23:28	28.90	OK
16615	2026-09-21 23:29	30.10	OK	16616	2026-09-21 23:30	31.49	OK
16617	2026-09-21 23:31	29.85	OK	16618	2026-09-21 23:32	28.27	OK
16619	2026-09-21 23:33	30.73	OK	16620	2026-09-21 23:34	29.25	OK
16621	2026-09-21 23:35	28.46	OK	16622	2026-09-21 23:36	28.74	OK
16623	2026-09-21 23:37	30.07	OK	16624	2026-09-21 23:38	28.77	OK
16625	2026-09-21 23:39	30.31	OK	16626	2026-09-21 23:40	30.45	OK
16627	2026-09-21 23:41	28.62	OK	16628	2026-09-21 23:42	30.58	OK
16629	2026-09-21 23:43	30.81	OK	16630	2026-09-21 23:44	30.56	OK
16631	2026-09-21 23:45	30.54	OK	16632	2026-09-21 23:46	30.53	OK
16633	2026-09-21 23:47	29.98	OK	16634	2026-09-21 23:48	29.67	OK
16635	2026-09-21 23:49	30.71	OK	16636	2026-09-21 23:50	29.34	OK
16637	2026-09-21 23:51	29.60	OK	16638	2026-09-21 23:52	30.22	OK
16639	2026-09-21 23:53	29.73	OK	16640	2026-09-21 23:54	28.87	OK
16641	2026-09-21 23:55	30.21	OK	16642	2026-09-21 23:56	30.20	OK
16643	2026-09-21 23:57	29.44	OK	16644	2026-09-21 23:58	30.50	OK
16645	2026-09-21 23:59	30.62	OK	16646	2026-09-22 00:00	29.42	OK
16647	2026-09-22 00:01	30.45	OK	16648	2026-09-22 00:02	29.17	OK
16649	2026-09-22 00:03	29.99	OK	16650	2026-09-22 00:04	29.06	OK
16651	2026-09-22 00:05	30.10	OK	16652	2026-09-22 00:06	29.86	OK
16653	2026-09-22 00:07	29.41	OK	16654	2026-09-22 00:08	31.38	OK
16655	2026-09-22 00:09	28.61	OK	16656	2026-09-22 00:10	30.71	OK
16657	2026-09-22 00:11	29.29	OK	16658	2026-09-22 00:12	29.85	OK
16659	2026-09-22 00:13	31.54	OK	16660	2026-09-22 00:14	30.54	OK
16661	2026-09-22 00:15	30.73	OK	16662	2026-09-22 00:16	29.85	OK
16663	2026-09-22 00:17	30.12	OK	16664	2026-09-22 00:18	30.04	OK
16665	2026-09-22 00:19	29.42	OK	16666	2026-09-22 00:20	29.48	OK
16667	2026-09-22 00:21	30.25	OK	16668	2026-09-22 00:22	30.52	OK
16669	2026-09-22 00:23	30.37	OK	16670	2026-09-22 00:24	31.77	OK
16671	2026-09-22 00:25	31.97	OK	16672	2026-09-22 00:26	31.17	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16673	2026-09-22 00:27	31.09	OK	16674	2026-09-22 00:28	30.59	OK
16675	2026-09-22 00:29	30.93	OK	16676	2026-09-22 00:30	31.52	OK
16677	2026-09-22 00:31	31.10	OK	16678	2026-09-22 00:32	31.48	OK
16679	2026-09-22 00:33	31.46	OK	16680	2026-09-22 00:34	30.26	OK
16681	2026-09-22 00:35	30.53	OK	16682	2026-09-22 00:36	29.36	OK
16683	2026-09-22 00:37	30.14	OK	16684	2026-09-22 00:38	29.98	OK
16685	2026-09-22 00:39	29.62	OK	16686	2026-09-22 00:40	31.04	OK
16687	2026-09-22 00:41	30.97	OK	16688	2026-09-22 00:42	30.09	OK
16689	2026-09-22 00:43	30.69	OK	16690	2026-09-22 00:44	31.26	OK
16691	2026-09-22 00:45	31.71	OK	16692	2026-09-22 00:46	31.67	OK
16693	2026-09-22 00:47	30.60	OK	16694	2026-09-22 00:48	29.53	OK
16695	2026-09-22 00:49	29.62	OK	16696	2026-09-22 00:50	30.64	OK
16697	2026-09-22 00:51	30.64	OK	16698	2026-09-22 00:52	29.32	OK
16699	2026-09-22 00:53	29.13	OK	16700	2026-09-22 00:54	29.05	OK
16701	2026-09-22 00:55	29.15	OK	16702	2026-09-22 00:56	30.69	OK
16703	2026-09-22 00:57	30.60	OK	16704	2026-09-22 00:58	30.28	OK
16705	2026-09-22 00:59	30.16	OK	16706	2026-09-22 01:00	30.71	OK
16707	2026-09-22 01:01	29.63	OK	16708	2026-09-22 01:02	30.30	OK
16709	2026-09-22 01:03	29.72	OK	16710	2026-09-22 01:04	31.33	OK
16711	2026-09-22 01:05	30.65	OK	16712	2026-09-22 01:06	29.74	OK
16713	2026-09-22 01:07	29.96	OK	16714	2026-09-22 01:08	31.11	OK
16715	2026-09-22 01:09	31.68	OK	16716	2026-09-22 01:10	29.51	OK
16717	2026-09-22 01:11	28.39	OK	16718	2026-09-22 01:12	30.70	OK
16719	2026-09-22 01:13	30.28	OK	16720	2026-09-22 01:14	31.57	OK
16721	2026-09-22 01:15	31.52	OK	16722	2026-09-22 01:16	31.44	OK
16723	2026-09-22 01:17	29.59	OK	16724	2026-09-22 01:18	30.20	OK
16725	2026-09-22 01:19	28.72	OK	16726	2026-09-22 01:20	30.96	OK
16727	2026-09-22 01:21	31.12	OK	16728	2026-09-22 01:22	29.05	OK
16729	2026-09-22 01:23	30.34	OK	16730	2026-09-22 01:24	30.30	OK
16731	2026-09-22 01:25	30.03	OK	16732	2026-09-22 01:26	30.80	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16733	2026-09-22 01:27	29.86	OK	16734	2026-09-22 01:28	30.78	OK
16735	2026-09-22 01:29	30.68	OK	16736	2026-09-22 01:30	30.99	OK
16737	2026-09-22 01:31	31.54	OK	16738	2026-09-22 01:32	30.20	OK
16739	2026-09-22 01:33	29.27	OK	16740	2026-09-22 01:34	29.64	OK
16741	2026-09-22 01:35	30.37	OK	16742	2026-09-22 01:36	30.74	OK
16743	2026-09-22 01:37	30.63	OK	16744	2026-09-22 01:38	29.19	OK
16745	2026-09-22 01:39	30.78	OK	16746	2026-09-22 01:40	30.24	OK
16747	2026-09-22 01:41	29.79	OK	16748	2026-09-22 01:42	29.44	OK
16749	2026-09-22 01:43	31.26	OK	16750	2026-09-22 01:44	30.17	OK
16751	2026-09-22 01:45	30.81	OK	16752	2026-09-22 01:46	29.99	OK
16753	2026-09-22 01:47	28.98	OK	16754	2026-09-22 01:48	29.41	OK
16755	2026-09-22 01:49	30.11	OK	16756	2026-09-22 01:50	31.15	OK
16757	2026-09-22 01:51	30.23	OK	16758	2026-09-22 01:52	30.06	OK
16759	2026-09-22 01:53	30.13	OK	16760	2026-09-22 01:54	30.20	OK
16761	2026-09-22 01:55	31.80	OK	16762	2026-09-22 01:56	30.28	OK
16763	2026-09-22 01:57	30.50	OK	16764	2026-09-22 01:58	30.37	OK
16765	2026-09-22 01:59	29.85	OK	16766	2026-09-22 02:00	29.00	OK
16767	2026-09-22 02:01	31.27	OK	16768	2026-09-22 02:02	29.72	OK
16769	2026-09-22 02:03	30.35	OK	16770	2026-09-22 02:04	30.50	OK
16771	2026-09-22 02:05	31.60	OK	16772	2026-09-22 02:06	30.19	OK
16773	2026-09-22 02:07	28.48	OK	16774	2026-09-22 02:08	30.52	OK
16775	2026-09-22 02:09	30.85	OK	16776	2026-09-22 02:10	31.11	OK
16777	2026-09-22 02:11	30.35	OK	16778	2026-09-22 02:12	31.07	OK
16779	2026-09-22 02:13	30.91	OK	16780	2026-09-22 02:14	29.88	OK
16781	2026-09-22 02:15	31.43	OK	16782	2026-09-22 02:16	29.99	OK
16783	2026-09-22 02:17	28.54	OK	16784	2026-09-22 02:18	30.73	OK
16785	2026-09-22 02:19	28.72	OK	16786	2026-09-22 02:20	31.42	OK
16787	2026-09-22 02:21	30.87	OK	16788	2026-09-22 02:22	29.33	OK
16789	2026-09-22 02:23	32.10	OK	16790	2026-09-22 02:24	30.07	OK
16791	2026-09-22 02:25	30.44	OK	16792	2026-09-22 02:26	28.72	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16793	2026-09-22 02:27	31.34	OK	16794	2026-09-22 02:28	29.07	OK
16795	2026-09-22 02:29	29.66	OK	16796	2026-09-22 02:30	30.00	OK
16797	2026-09-22 02:31	29.66	OK	16798	2026-09-22 02:32	29.41	OK
16799	2026-09-22 02:33	29.79	OK	16800	2026-09-22 02:34	30.76	OK
16801	2026-09-22 02:35	28.30	OK	16802	2026-09-22 02:36	30.27	OK
16803	2026-09-22 02:37	29.75	OK	16804	2026-09-22 02:38	30.50	OK
16805	2026-09-22 02:39	30.21	OK	16806	2026-09-22 02:40	29.07	OK
16807	2026-09-22 02:41	30.13	OK	16808	2026-09-22 02:42	30.13	OK
16809	2026-09-22 02:43	29.36	OK	16810	2026-09-22 02:44	28.68	OK
16811	2026-09-22 02:45	30.72	OK	16812	2026-09-22 02:46	29.26	OK
16813	2026-09-22 02:47	28.68	OK	16814	2026-09-22 02:48	29.88	OK
16815	2026-09-22 02:49	29.10	OK	16816	2026-09-22 02:50	30.09	OK
16817	2026-09-22 02:51	31.34	OK	16818	2026-09-22 02:52	30.69	OK
16819	2026-09-22 02:53	29.96	OK	16820	2026-09-22 02:54	28.27	OK
16821	2026-09-22 02:55	28.93	OK	16822	2026-09-22 02:56	31.38	OK
16823	2026-09-22 02:57	29.35	OK	16824	2026-09-22 02:58	31.70	OK
16825	2026-09-22 02:59	29.26	OK	16826	2026-09-22 03:00	31.29	OK
16827	2026-09-22 03:01	29.48	OK	16828	2026-09-22 03:02	29.26	OK
16829	2026-09-22 03:03	30.19	OK	16830	2026-09-22 03:04	30.98	OK
16831	2026-09-22 03:05	29.27	OK	16832	2026-09-22 03:06	30.57	OK
16833	2026-09-22 03:07	29.58	OK	16834	2026-09-22 03:08	30.33	OK
16835	2026-09-22 03:09	30.61	OK	16836	2026-09-22 03:10	30.90	OK
16837	2026-09-22 03:11	31.17	OK	16838	2026-09-22 03:12	30.00	OK
16839	2026-09-22 03:13	28.74	OK	16840	2026-09-22 03:14	28.70	OK
16841	2026-09-22 03:15	29.31	OK	16842	2026-09-22 03:16	29.98	OK
16843	2026-09-22 03:17	30.64	OK	16844	2026-09-22 03:18	31.56	OK
16845	2026-09-22 03:19	30.08	OK	16846	2026-09-22 03:20	29.29	OK
16847	2026-09-22 03:21	31.00	OK	16848	2026-09-22 03:22	29.37	OK
16849	2026-09-22 03:23	29.89	OK	16850	2026-09-22 03:24	29.61	OK
16851	2026-09-22 03:25	29.56	OK	16852	2026-09-22 03:26	30.13	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16853	2026-09-22 03:27	30.42	OK	16854	2026-09-22 03:28	29.10	OK
16855	2026-09-22 03:29	29.32	OK	16856	2026-09-22 03:30	29.68	OK
16857	2026-09-22 03:31	29.81	OK	16858	2026-09-22 03:32	30.15	OK
16859	2026-09-22 03:33	28.40	OK	16860	2026-09-22 03:34	30.62	OK
16861	2026-09-22 03:35	29.73	OK	16862	2026-09-22 03:36	29.60	OK
16863	2026-09-22 03:37	29.68	OK	16864	2026-09-22 03:38	30.13	OK
16865	2026-09-22 03:39	29.30	OK	16866	2026-09-22 03:40	30.01	OK
16867	2026-09-22 03:41	29.83	OK	16868	2026-09-22 03:42	29.29	OK
16869	2026-09-22 03:43	29.33	OK	16870	2026-09-22 03:44	30.69	OK
16871	2026-09-22 03:45	30.01	OK	16872	2026-09-22 03:46	29.98	OK
16873	2026-09-22 03:47	29.78	OK	16874	2026-09-22 03:48	29.04	OK
16875	2026-09-22 03:49	29.97	OK	16876	2026-09-22 03:50	28.89	OK
16877	2026-09-22 03:51	28.98	OK	16878	2026-09-22 03:52	31.28	OK
16879	2026-09-22 03:53	30.86	OK	16880	2026-09-22 03:54	29.40	OK
16881	2026-09-22 03:55	29.44	OK	16882	2026-09-22 03:56	29.28	OK
16883	2026-09-22 03:57	30.84	OK	16884	2026-09-22 03:58	29.52	OK
16885	2026-09-22 03:59	30.28	OK	16886	2026-09-22 04:00	28.77	OK
16887	2026-09-22 04:01	30.22	OK	16888	2026-09-22 04:02	29.04	OK
16889	2026-09-22 04:03	30.20	OK	16890	2026-09-22 04:04	28.57	OK
16891	2026-09-22 04:05	31.02	OK	16892	2026-09-22 04:06	29.50	OK
16893	2026-09-22 04:07	28.39	OK	16894	2026-09-22 04:08	29.33	OK
16895	2026-09-22 04:09	29.61	OK	16896	2026-09-22 04:10	29.09	OK
16897	2026-09-22 04:11	28.98	OK	16898	2026-09-22 04:12	30.03	OK
16899	2026-09-22 04:13	29.08	OK	16900	2026-09-22 04:14	28.75	OK
16901	2026-09-22 04:15	29.44	OK	16902	2026-09-22 04:16	30.92	OK
16903	2026-09-22 04:17	30.74	OK	16904	2026-09-22 04:18	28.96	OK
16905	2026-09-22 04:19	29.59	OK	16906	2026-09-22 04:20	29.92	OK
16907	2026-09-22 04:21	30.26	OK	16908	2026-09-22 04:22	31.00	OK
16909	2026-09-22 04:23	28.80	OK	16910	2026-09-22 04:24	28.36	OK
16911	2026-09-22 04:25	28.77	OK	16912	2026-09-22 04:26	31.01	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16913	2026-09-22 04:27	29.83	OK	16914	2026-09-22 04:28	28.65	OK
16915	2026-09-22 04:29	29.03	OK	16916	2026-09-22 04:30	28.30	OK
16917	2026-09-22 04:31	29.45	OK	16918	2026-09-22 04:32	28.68	OK
16919	2026-09-22 04:33	29.91	OK	16920	2026-09-22 04:34	28.24	OK
16921	2026-09-22 04:35	29.31	OK	16922	2026-09-22 04:36	28.70	OK
16923	2026-09-22 04:37	28.97	OK	16924	2026-09-22 04:38	28.71	OK
16925	2026-09-22 04:39	29.64	OK	16926	2026-09-22 04:40	29.18	OK
16927	2026-09-22 04:41	29.76	OK	16928	2026-09-22 04:42	29.14	OK
16929	2026-09-22 04:43	28.55	OK	16930	2026-09-22 04:44	29.37	OK
16931	2026-09-22 04:45	29.88	OK	16932	2026-09-22 04:46	28.15	OK
16933	2026-09-22 04:47	28.99	OK	16934	2026-09-22 04:48	28.63	OK
16935	2026-09-22 04:49	28.99	OK	16936	2026-09-22 04:50	31.03	OK
16937	2026-09-22 04:51	29.32	OK	16938	2026-09-22 04:52	29.30	OK
16939	2026-09-22 04:53	28.95	OK	16940	2026-09-22 04:54	28.66	OK
16941	2026-09-22 04:55	29.26	OK	16942	2026-09-22 04:56	29.17	OK
16943	2026-09-22 04:57	28.24	OK	16944	2026-09-22 04:58	28.90	OK
16945	2026-09-22 04:59	29.23	OK	16946	2026-09-22 05:00	31.03	OK
16947	2026-09-22 05:01	30.36	OK	16948	2026-09-22 05:02	29.55	OK
16949	2026-09-22 05:03	30.06	OK	16950	2026-09-22 05:04	28.55	OK
16951	2026-09-22 05:05	28.06	OK	16952	2026-09-22 05:06	28.16	OK
16953	2026-09-22 05:07	28.73	OK	16954	2026-09-22 05:08	28.04	OK
16955	2026-09-22 05:09	29.84	OK	16956	2026-09-22 05:10	29.97	OK
16957	2026-09-22 05:11	28.86	OK	16958	2026-09-22 05:12	29.24	OK
16959	2026-09-22 05:13	31.04	OK	16960	2026-09-22 05:14	29.23	OK
16961	2026-09-22 05:15	28.42	OK	16962	2026-09-22 05:16	29.23	OK
16963	2026-09-22 05:17	28.06	OK	16964	2026-09-22 05:18	28.77	OK
16965	2026-09-22 05:19	28.58	OK	16966	2026-09-22 05:20	29.95	OK
16967	2026-09-22 05:21	29.89	OK	16968	2026-09-22 05:22	28.87	OK
16969	2026-09-22 05:23	28.81	OK	16970	2026-09-22 05:24	29.41	OK
16971	2026-09-22 05:25	28.57	OK	16972	2026-09-22 05:26	29.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
16973	2026-09-22 05:27	28.73	OK	16974	2026-09-22 05:28	29.72	OK
16975	2026-09-22 05:29	29.46	OK	16976	2026-09-22 05:30	27.99	OK
16977	2026-09-22 05:31	28.01	OK	16978	2026-09-22 05:32	28.68	OK
16979	2026-09-22 05:33	29.00	OK	16980	2026-09-22 05:34	28.21	OK
16981	2026-09-22 05:35	29.30	OK	16982	2026-09-22 05:36	29.27	OK
16983	2026-09-22 05:37	29.21	OK	16984	2026-09-22 05:38	28.68	OK
16985	2026-09-22 05:39	30.11	OK	16986	2026-09-22 05:40	29.57	OK
16987	2026-09-22 05:41	28.46	OK	16988	2026-09-22 05:42	29.97	OK
16989	2026-09-22 05:43	28.79	OK	16990	2026-09-22 05:44	28.78	OK
16991	2026-09-22 05:45	28.37	OK	16992	2026-09-22 05:46	27.62	OK
16993	2026-09-22 05:47	29.46	OK	16994	2026-09-22 05:48	29.93	OK
16995	2026-09-22 05:49	28.90	OK	16996	2026-09-22 05:50	28.87	OK
16997	2026-09-22 05:51	29.94	OK	16998	2026-09-22 05:52	30.93	OK
16999	2026-09-22 05:53	28.41	OK	17000	2026-09-22 05:54	28.31	OK
17001	2026-09-22 05:55	28.18	OK	17002	2026-09-22 05:56	29.14	OK
17003	2026-09-22 05:57	27.89	OK	17004	2026-09-22 05:58	26.88	OK
17005	2026-09-22 05:59	28.61	OK	17006	2026-09-22 06:00	28.24	OK
17007	2026-09-22 06:01	27.65	OK	17008	2026-09-22 06:02	30.05	OK
17009	2026-09-22 06:03	28.52	OK	17010	2026-09-22 06:04	28.81	OK
17011	2026-09-22 06:05	27.34	OK	17012	2026-09-22 06:06	27.79	OK
17013	2026-09-22 06:07	29.21	OK	17014	2026-09-22 06:08	28.44	OK
17015	2026-09-22 06:09	28.76	OK	17016	2026-09-22 06:10	29.27	OK
17017	2026-09-22 06:11	29.40	OK	17018	2026-09-22 06:12	28.60	OK
17019	2026-09-22 06:13	27.65	OK	17020	2026-09-22 06:14	28.89	OK
17021	2026-09-22 06:15	29.20	OK	17022	2026-09-22 06:16	27.62	OK
17023	2026-09-22 06:17	28.44	OK	17024	2026-09-22 06:18	29.60	OK
17025	2026-09-22 06:19	28.95	OK	17026	2026-09-22 06:20	27.98	OK
17027	2026-09-22 06:21	29.67	OK	17028	2026-09-22 06:22	27.40	OK
17029	2026-09-22 06:23	29.70	OK	17030	2026-09-22 06:24	28.79	OK
17031	2026-09-22 06:25	28.63	OK	17032	2026-09-22 06:26	28.18	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17033	2026-09-22 06:27	28.88	OK	17034	2026-09-22 06:28	27.84	OK
17035	2026-09-22 06:29	29.77	OK	17036	2026-09-22 06:30	29.14	OK
17037	2026-09-22 06:31	29.58	OK	17038	2026-09-22 06:32	28.35	OK
17039	2026-09-22 06:33	28.78	OK	17040	2026-09-22 06:34	28.89	OK
17041	2026-09-22 06:35	28.89	OK	17042	2026-09-22 06:36	29.12	OK
17043	2026-09-22 06:37	29.34	OK	17044	2026-09-22 06:38	28.36	OK
17045	2026-09-22 06:39	28.81	OK	17046	2026-09-22 06:40	28.34	OK
17047	2026-09-22 06:41	26.54	OK	17048	2026-09-22 06:42	28.69	OK
17049	2026-09-22 06:43	29.14	OK	17050	2026-09-22 06:44	28.14	OK
17051	2026-09-22 06:45	28.21	OK	17052	2026-09-22 06:46	28.96	OK
17053	2026-09-22 06:47	28.45	OK	17054	2026-09-22 06:48	29.40	OK
17055	2026-09-22 06:49	28.73	OK	17056	2026-09-22 06:50	28.90	OK
17057	2026-09-22 06:51	28.98	OK	17058	2026-09-22 06:52	29.58	OK
17059	2026-09-22 06:53	29.14	OK	17060	2026-09-22 06:54	27.90	OK
17061	2026-09-22 06:55	27.72	OK	17062	2026-09-22 06:56	28.13	OK
17063	2026-09-22 06:57	28.57	OK	17064	2026-09-22 06:58	28.66	OK
17065	2026-09-22 06:59	28.37	OK	17066	2026-09-22 07:00	29.49	OK
17067	2026-09-22 07:01	28.22	OK	17068	2026-09-22 07:02	27.66	OK
17069	2026-09-22 07:03	27.64	OK	17070	2026-09-22 07:04	28.07	OK
17071	2026-09-22 07:05	28.00	OK	17072	2026-09-22 07:06	27.39	OK
17073	2026-09-22 07:07	28.41	OK	17074	2026-09-22 07:08	28.53	OK
17075	2026-09-22 07:09	27.77	OK	17076	2026-09-22 07:10	29.78	OK
17077	2026-09-22 07:11	28.43	OK	17078	2026-09-22 07:12	27.92	OK
17079	2026-09-22 07:13	27.91	OK	17080	2026-09-22 07:14	28.41	OK
17081	2026-09-22 07:15	27.69	OK	17082	2026-09-22 07:16	27.68	OK
17083	2026-09-22 07:17	28.32	OK	17084	2026-09-22 07:18	27.90	OK
17085	2026-09-22 07:19	27.70	OK	17086	2026-09-22 07:20	28.32	OK
17087	2026-09-22 07:21	29.51	OK	17088	2026-09-22 07:22	28.82	OK
17089	2026-09-22 07:23	28.37	OK	17090	2026-09-22 07:24	28.11	OK
17091	2026-09-22 07:25	28.08	OK	17092	2026-09-22 07:26	26.29	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17093	2026-09-22 07:27	27.71	OK	17094	2026-09-22 07:28	27.70	OK
17095	2026-09-22 07:29	28.14	OK	17096	2026-09-22 07:30	28.12	OK
17097	2026-09-22 07:31	28.83	OK	17098	2026-09-22 07:32	27.87	OK
17099	2026-09-22 07:33	28.14	OK	17100	2026-09-22 07:34	27.02	OK
17101	2026-09-22 07:35	27.25	OK	17102	2026-09-22 07:36	27.17	OK
17103	2026-09-22 07:37	29.83	OK	17104	2026-09-22 07:38	27.93	OK
17105	2026-09-22 07:39	28.13	OK	17106	2026-09-22 07:40	27.71	OK
17107	2026-09-22 07:41	27.87	OK	17108	2026-09-22 07:42	28.56	OK
17109	2026-09-22 07:43	27.62	OK	17110	2026-09-22 07:44	27.98	OK
17111	2026-09-22 07:45	25.98	OK	17112	2026-09-22 07:46	27.63	OK
17113	2026-09-22 07:47	27.35	OK	17114	2026-09-22 07:48	27.82	OK
17115	2026-09-22 07:49	28.85	OK	17116	2026-09-22 07:50	27.25	OK
17117	2026-09-22 07:51	27.96	OK	17118	2026-09-22 07:52	28.05	OK
17119	2026-09-22 07:53	26.70	OK	17120	2026-09-22 07:54	26.30	OK
17121	2026-09-22 07:55	28.11	OK	17122	2026-09-22 07:56	27.16	OK
17123	2026-09-22 07:57	28.83	OK	17124	2026-09-22 07:58	28.99	OK
17125	2026-09-22 07:59	28.06	OK	17126	2026-09-22 08:00	27.62	OK
17127	2026-09-22 08:01	27.86	OK	17128	2026-09-22 08:02	28.01	OK
17129	2026-09-22 08:03	26.50	OK	17130	2026-09-22 08:04	26.42	OK
17131	2026-09-22 08:05	27.26	OK	17132	2026-09-22 08:06	27.33	OK
17133	2026-09-22 08:07	26.40	OK	17134	2026-09-22 08:08	27.63	OK
17135	2026-09-22 08:09	29.35	OK	17136	2026-09-22 08:10	28.65	OK
17137	2026-09-22 08:11	27.22	OK	17138	2026-09-22 08:12	28.48	OK
17139	2026-09-22 08:13	28.78	OK	17140	2026-09-22 08:14	27.43	OK
17141	2026-09-22 08:15	27.39	OK	17142	2026-09-22 08:16	26.65	OK
17143	2026-09-22 08:17	27.19	OK	17144	2026-09-22 08:18	27.73	OK
17145	2026-09-22 08:19	27.32	OK	17146	2026-09-22 08:20	28.71	OK
17147	2026-09-22 08:21	27.85	OK	17148	2026-09-22 08:22	27.32	OK
17149	2026-09-22 08:23	27.63	OK	17150	2026-09-22 08:24	28.54	OK
17151	2026-09-22 08:25	26.47	OK	17152	2026-09-22 08:26	27.08	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17153	2026-09-22 08:27	25.80	OK	17154	2026-09-22 08:28	27.05	OK
17155	2026-09-22 08:29	28.29	OK	17156	2026-09-22 08:30	26.77	OK
17157	2026-09-22 08:31	26.67	OK	17158	2026-09-22 08:32	28.80	OK
17159	2026-09-22 08:33	26.70	OK	17160	2026-09-22 08:34	27.59	OK
17161	2026-09-22 08:35	28.08	OK	17162	2026-09-22 08:36	28.04	OK
17163	2026-09-22 08:37	27.26	OK	17164	2026-09-22 08:38	27.62	OK
17165	2026-09-22 08:39	27.03	OK	17166	2026-09-22 08:40	26.91	OK
17167	2026-09-22 08:41	27.15	OK	17168	2026-09-22 08:42	26.99	OK
17169	2026-09-22 08:43	26.92	OK	17170	2026-09-22 08:44	28.11	OK
17171	2026-09-22 08:45	25.92	OK	17172	2026-09-22 08:46	27.32	OK
17173	2026-09-22 08:47	28.82	OK	17174	2026-09-22 08:48	26.84	OK
17175	2026-09-22 08:49	27.44	OK	17176	2026-09-22 08:50	27.16	OK
17177	2026-09-22 08:51	27.28	OK	17178	2026-09-22 08:52	27.97	OK
17179	2026-09-22 08:53	27.19	OK	17180	2026-09-22 08:54	26.38	OK
17181	2026-09-22 08:55	26.53	OK	17182	2026-09-22 08:56	27.14	OK
17183	2026-09-22 08:57	26.53	OK	17184	2026-09-22 08:58	25.55	OK
17185	2026-09-22 08:59	26.49	OK	17186	2026-09-22 09:00	26.41	OK
17187	2026-09-22 09:01	28.04	OK	17188	2026-09-22 09:02	26.71	OK
17189	2026-09-22 09:03	26.24	OK	17190	2026-09-22 09:04	27.06	OK
17191	2026-09-22 09:05	26.59	OK	17192	2026-09-22 09:06	27.36	OK
17193	2026-09-22 09:07	28.39	OK	17194	2026-09-22 09:08	25.40	OK
17195	2026-09-22 09:09	27.46	OK	17196	2026-09-22 09:10	26.57	OK
17197	2026-09-22 09:11	26.92	OK	17198	2026-09-22 09:12	27.47	OK
17199	2026-09-22 09:13	26.36	OK	17200	2026-09-22 09:14	27.49	OK
17201	2026-09-22 09:15	26.87	OK	17202	2026-09-22 09:16	26.24	OK
17203	2026-09-22 09:17	27.12	OK	17204	2026-09-22 09:18	27.91	OK
17205	2026-09-22 09:19	27.66	OK	17206	2026-09-22 09:20	27.90	OK
17207	2026-09-22 09:21	26.78	OK	17208	2026-09-22 09:22	26.45	OK
17209	2026-09-22 09:23	25.79	OK	17210	2026-09-22 09:24	25.63	OK
17211	2026-09-22 09:25	26.20	OK	17212	2026-09-22 09:26	26.23	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17213	2026-09-22 09:27	26.12	OK	17214	2026-09-22 09:28	26.76	OK
17215	2026-09-22 09:29	26.14	OK	17216	2026-09-22 09:30	27.45	OK
17217	2026-09-22 09:31	25.98	OK	17218	2026-09-22 09:32	26.99	OK
17219	2026-09-22 09:33	26.36	OK	17220	2026-09-22 09:34	26.12	OK
17221	2026-09-22 09:35	27.63	OK	17222	2026-09-22 09:36	26.39	OK
17223	2026-09-22 09:37	26.12	OK	17224	2026-09-22 09:38	26.03	OK
17225	2026-09-22 09:39	25.84	OK	17226	2026-09-22 09:40	26.72	OK
17227	2026-09-22 09:41	27.59	OK	17228	2026-09-22 09:42	25.45	OK
17229	2026-09-22 09:43	27.90	OK	17230	2026-09-22 09:44	27.64	OK
17231	2026-09-22 09:45	26.69	OK	17232	2026-09-22 09:46	25.34	OK
17233	2026-09-22 09:47	26.87	OK	17234	2026-09-22 09:48	26.29	OK
17235	2026-09-22 09:49	25.33	OK	17236	2026-09-22 09:50	25.61	OK
17237	2026-09-22 09:51	27.34	OK	17238	2026-09-22 09:52	25.72	OK
17239	2026-09-22 09:53	26.29	OK	17240	2026-09-22 09:54	25.79	OK
17241	2026-09-22 09:55	26.31	OK	17242	2026-09-22 09:56	26.38	OK
17243	2026-09-22 09:57	26.15	OK	17244	2026-09-22 09:58	24.86	OK
17245	2026-09-22 09:59	26.04	OK	17246	2026-09-22 10:00	26.04	OK
17247	2026-09-22 10:01	26.57	OK	17248	2026-09-22 10:02	26.97	OK
17249	2026-09-22 10:03	25.65	OK	17250	2026-09-22 10:04	27.63	OK
17251	2026-09-22 10:05	27.37	OK	17252	2026-09-22 10:06	27.17	OK
17253	2026-09-22 10:07	25.76	OK	17254	2026-09-22 10:08	25.53	OK
17255	2026-09-22 10:09	26.72	OK	17256	2026-09-22 10:10	25.30	OK
17257	2026-09-22 10:11	28.16	OK	17258	2026-09-22 10:12	26.32	OK
17259	2026-09-22 10:13	26.84	OK	17260	2026-09-22 10:14	26.02	OK
17261	2026-09-22 10:15	25.54	OK	17262	2026-09-22 10:16	25.77	OK
17263	2026-09-22 10:17	26.23	OK	17264	2026-09-22 10:18	26.54	OK
17265	2026-09-22 10:19	24.99	OK	17266	2026-09-22 10:20	25.77	OK
17267	2026-09-22 10:21	25.49	OK	17268	2026-09-22 10:22	27.16	OK
17269	2026-09-22 10:23	26.46	OK	17270	2026-09-22 10:24	26.70	OK
17271	2026-09-22 10:25	26.72	OK	17272	2026-09-22 10:26	25.72	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17273	2026-09-22 10:27	26.09	OK	17274	2026-09-22 10:28	25.33	OK
17275	2026-09-22 10:29	27.08	OK	17276	2026-09-22 10:30	26.80	OK
17277	2026-09-22 10:31	25.45	OK	17278	2026-09-22 10:32	27.54	OK
17279	2026-09-22 10:33	24.40	OK	17280	2026-09-22 10:34	25.63	OK
17281	2026-09-22 10:35	24.72	OK	17282	2026-09-22 10:36	26.54	OK
17283	2026-09-22 10:37	26.42	OK	17284	2026-09-22 10:38	26.22	OK
17285	2026-09-22 10:39	26.93	OK	17286	2026-09-22 10:40	26.02	OK
17287	2026-09-22 10:41	25.36	OK	17288	2026-09-22 10:42	26.65	OK
17289	2026-09-22 10:43	24.84	OK	17290	2026-09-22 10:44	26.66	OK
17291	2026-09-22 10:45	26.37	OK	17292	2026-09-22 10:46	26.43	OK
17293	2026-09-22 10:47	27.40	OK	17294	2026-09-22 10:48	26.87	OK
17295	2026-09-22 10:49	27.29	OK	17296	2026-09-22 10:50	26.59	OK
17297	2026-09-22 10:51	24.99	OK	17298	2026-09-22 10:52	27.39	OK
17299	2026-09-22 10:53	26.27	OK	17300	2026-09-22 10:54	26.21	OK
17301	2026-09-22 10:55	27.20	OK	17302	2026-09-22 10:56	26.03	OK
17303	2026-09-22 10:57	26.51	OK	17304	2026-09-22 10:58	26.59	OK
17305	2026-09-22 10:59	27.05	OK	17306	2026-09-22 11:00	25.92	OK
17307	2026-09-22 11:01	26.42	OK	17308	2026-09-22 11:02	25.66	OK
17309	2026-09-22 11:03	26.97	OK	17310	2026-09-22 11:04	25.76	OK
17311	2026-09-22 11:05	26.89	OK	17312	2026-09-22 11:06	25.31	OK
17313	2026-09-22 11:07	26.66	OK	17314	2026-09-22 11:08	26.60	OK
17315	2026-09-22 11:09	25.85	OK	17316	2026-09-22 11:10	25.95	OK
17317	2026-09-22 11:11	25.56	OK	17318	2026-09-22 11:12	25.41	OK
17319	2026-09-22 11:13	24.85	OK	17320	2026-09-22 11:14	25.96	OK
17321	2026-09-22 11:15	25.44	OK	17322	2026-09-22 11:16	26.35	OK
17323	2026-09-22 11:17	27.45	OK	17324	2026-09-22 11:18	25.99	OK
17325	2026-09-22 11:19	26.43	OK	17326	2026-09-22 11:20	25.96	OK
17327	2026-09-22 11:21	26.29	OK	17328	2026-09-22 11:22	27.68	OK
17329	2026-09-22 11:23	26.63	OK	17330	2026-09-22 11:24	26.55	OK
17331	2026-09-22 11:25	26.41	OK	17332	2026-09-22 11:26	25.96	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17333	2026-09-22 11:27	25.67	OK	17334	2026-09-22 11:28	26.51	OK
17335	2026-09-22 11:29	27.00	OK	17336	2026-09-22 11:30	26.19	OK
17337	2026-09-22 11:31	25.90	OK	17338	2026-09-22 11:32	25.47	OK
17339	2026-09-22 11:33	26.50	OK	17340	2026-09-22 11:34	26.69	OK
17341	2026-09-22 11:35	26.08	OK	17342	2026-09-22 11:36	25.95	OK
17343	2026-09-22 11:37	25.72	OK	17344	2026-09-22 11:38	25.39	OK
17345	2026-09-22 11:39	25.50	OK	17346	2026-09-22 11:40	24.68	OK
17347	2026-09-22 11:41	25.68	OK	17348	2026-09-22 11:42	25.14	OK
17349	2026-09-22 11:43	25.60	OK	17350	2026-09-22 11:44	25.94	OK
17351	2026-09-22 11:45	25.75	OK	17352	2026-09-22 11:46	25.87	OK
17353	2026-09-22 11:47	26.81	OK	17354	2026-09-22 11:48	27.29	OK
17355	2026-09-22 11:49	27.32	OK	17356	2026-09-22 11:50	24.94	OK
17357	2026-09-22 11:51	25.92	OK	17358	2026-09-22 11:52	25.34	OK
17359	2026-09-22 11:53	26.46	OK	17360	2026-09-22 11:54	24.79	OK
17361	2026-09-22 11:55	25.94	OK	17362	2026-09-22 11:56	26.65	OK
17363	2026-09-22 11:57	25.23	OK	17364	2026-09-22 11:58	25.37	OK
17365	2026-09-22 11:59	27.34	OK	17366	2026-09-22 12:00	25.17	OK
17367	2026-09-22 12:01	25.18	OK	17368	2026-09-22 12:02	25.93	OK
17369	2026-09-22 12:03	26.89	OK	17370	2026-09-22 12:04	27.48	OK
17371	2026-09-22 12:05	25.74	OK	17372	2026-09-22 12:06	24.87	OK
17373	2026-09-22 12:07	26.10	OK	17374	2026-09-22 12:08	25.59	OK
17375	2026-09-22 12:09	26.36	OK	17376	2026-09-22 12:10	25.25	OK
17377	2026-09-22 12:11	25.86	OK	17378	2026-09-22 12:12	26.60	OK
17379	2026-09-22 12:13	26.74	OK	17380	2026-09-22 12:14	25.75	OK
17381	2026-09-22 12:15	25.34	OK	17382	2026-09-22 12:16	26.54	OK
17383	2026-09-22 12:17	25.64	OK	17384	2026-09-22 12:18	25.07	OK
17385	2026-09-22 12:19	26.51	OK	17386	2026-09-22 12:20	24.58	OK
17387	2026-09-22 12:21	24.28	OK	17388	2026-09-22 12:22	24.74	OK
17389	2026-09-22 12:23	25.97	OK	17390	2026-09-22 12:24	26.70	OK
17391	2026-09-22 12:25	26.00	OK	17392	2026-09-22 12:26	24.65	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17393	2026-09-22 12:27	25.29	OK	17394	2026-09-22 12:28	24.73	OK
17395	2026-09-22 12:29	24.71	OK	17396	2026-09-22 12:30	26.61	OK
17397	2026-09-22 12:31	25.19	OK	17398	2026-09-22 12:32	24.93	OK
17399	2026-09-22 12:33	25.29	OK	17400	2026-09-22 12:34	25.90	OK
17401	2026-09-22 12:35	26.63	OK	17402	2026-09-22 12:36	26.13	OK
17403	2026-09-22 12:37	25.43	OK	17404	2026-09-22 12:38	26.55	OK
17405	2026-09-22 12:39	26.58	OK	17406	2026-09-22 12:40	24.81	OK
17407	2026-09-22 12:41	25.74	OK	17408	2026-09-22 12:42	24.79	OK
17409	2026-09-22 12:43	24.74	OK	17410	2026-09-22 12:44	25.04	OK
17411	2026-09-22 12:45	25.13	OK	17412	2026-09-22 12:46	25.57	OK
17413	2026-09-22 12:47	25.66	OK	17414	2026-09-22 12:48	25.41	OK
17415	2026-09-22 12:49	25.87	OK	17416	2026-09-22 12:50	26.79	OK
17417	2026-09-22 12:51	26.17	OK	17418	2026-09-22 12:52	25.92	OK
17419	2026-09-22 12:53	25.97	OK	17420	2026-09-22 12:54	26.43	OK
17421	2026-09-22 12:55	25.77	OK	17422	2026-09-22 12:56	26.26	OK
17423	2026-09-22 12:57	24.89	OK	17424	2026-09-22 12:58	26.25	OK
17425	2026-09-22 12:59	25.12	OK	17426	2026-09-22 13:00	24.23	OK
17427	2026-09-22 13:01	24.28	OK	17428	2026-09-22 13:02	25.86	OK
17429	2026-09-22 13:03	25.11	OK	17430	2026-09-22 13:04	27.16	OK
17431	2026-09-22 13:05	24.95	OK	17432	2026-09-22 13:06	25.89	OK
17433	2026-09-22 13:07	25.31	OK	17434	2026-09-22 13:08	26.46	OK
17435	2026-09-22 13:09	26.64	OK	17436	2026-09-22 13:10	26.86	OK
17437	2026-09-22 13:11	25.53	OK	17438	2026-09-22 13:12	25.48	OK
17439	2026-09-22 13:13	25.69	OK	17440	2026-09-22 13:14	27.51	OK
17441	2026-09-22 13:15	25.34	OK	17442	2026-09-22 13:16	26.02	OK
17443	2026-09-22 13:17	25.51	OK	17444	2026-09-22 13:18	25.86	OK
17445	2026-09-22 13:19	25.34	OK	17446	2026-09-22 13:20	26.92	OK
17447	2026-09-22 13:21	25.06	OK	17448	2026-09-22 13:22	26.42	OK
17449	2026-09-22 13:23	27.19	OK	17450	2026-09-22 13:24	25.49	OK
17451	2026-09-22 13:25	26.44	OK	17452	2026-09-22 13:26	25.22	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17453	2026-09-22 13:27	26.54	OK	17454	2026-09-22 13:28	25.87	OK
17455	2026-09-22 13:29	25.99	OK	17456	2026-09-22 13:30	26.64	OK
17457	2026-09-22 13:31	27.38	OK	17458	2026-09-22 13:32	25.65	OK
17459	2026-09-22 13:33	26.87	OK	17460	2026-09-22 13:34	24.96	OK
17461	2026-09-22 13:35	24.25	OK	17462	2026-09-22 13:36	25.19	OK
17463	2026-09-22 13:37	25.83	OK	17464	2026-09-22 13:38	24.83	OK
17465	2026-09-22 13:39	25.82	OK	17466	2026-09-22 13:40	24.74	OK
17467	2026-09-22 13:41	25.93	OK	17468	2026-09-22 13:42	25.79	OK
17469	2026-09-22 13:43	24.03	OK	17470	2026-09-22 13:44	24.99	OK
17471	2026-09-22 13:45	26.65	OK	17472	2026-09-22 13:46	25.87	OK
17473	2026-09-22 13:47	25.08	OK	17474	2026-09-22 13:48	25.20	OK
17475	2026-09-22 13:49	27.09	OK	17476	2026-09-22 13:50	24.74	OK
17477	2026-09-22 13:51	26.07	OK	17478	2026-09-22 13:52	26.02	OK
17479	2026-09-22 13:53	26.05	OK	17480	2026-09-22 13:54	26.87	OK
17481	2026-09-22 13:55	23.72	OK	17482	2026-09-22 13:56	26.01	OK
17483	2026-09-22 13:57	26.83	OK	17484	2026-09-22 13:58	25.34	OK
17485	2026-09-22 13:59	25.62	OK	17486	2026-09-22 14:00	26.88	OK
17487	2026-09-22 14:01	24.95	OK	17488	2026-09-22 14:02	24.25	OK
17489	2026-09-22 14:03	26.19	OK	17490	2026-09-22 14:04	26.15	OK
17491	2026-09-22 14:05	25.19	OK	17492	2026-09-22 14:06	26.49	OK
17493	2026-09-22 14:07	26.10	OK	17494	2026-09-22 14:08	25.85	OK
17495	2026-09-22 14:09	24.80	OK	17496	2026-09-22 14:10	26.84	OK
17497	2026-09-22 14:11	26.07	OK	17498	2026-09-22 14:12	26.32	OK
17499	2026-09-22 14:13	25.35	OK	17500	2026-09-22 14:14	25.27	OK
17501	2026-09-22 14:15	26.24	OK	17502	2026-09-22 14:16	25.54	OK
17503	2026-09-22 14:17	25.72	OK	17504	2026-09-22 14:18	25.10	OK
17505	2026-09-22 14:19	26.04	OK	17506	2026-09-22 14:20	24.43	OK
17507	2026-09-22 14:21	24.70	OK	17508	2026-09-22 14:22	24.59	OK
17509	2026-09-22 14:23	25.41	OK	17510	2026-09-22 14:24	26.02	OK
17511	2026-09-22 14:25	26.26	OK	17512	2026-09-22 14:26	24.64	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17513	2026-09-22 14:27	27.20	OK	17514	2026-09-22 14:28	26.65	OK
17515	2026-09-22 14:29	26.78	OK	17516	2026-09-22 14:30	25.86	OK
17517	2026-09-22 14:31	24.79	OK	17518	2026-09-22 14:32	26.20	OK
17519	2026-09-22 14:33	25.01	OK	17520	2026-09-22 14:34	26.29	OK
17521	2026-09-22 14:35	26.03	OK	17522	2026-09-22 14:36	26.22	OK
17523	2026-09-22 14:37	24.31	OK	17524	2026-09-22 14:38	23.93	OK
17525	2026-09-22 14:39	25.87	OK	17526	2026-09-22 14:40	25.69	OK
17527	2026-09-22 14:41	25.61	OK	17528	2026-09-22 14:42	26.41	OK
17529	2026-09-22 14:43	26.09	OK	17530	2026-09-22 14:44	26.33	OK
17531	2026-09-22 14:45	25.65	OK	17532	2026-09-22 14:46	25.70	OK
17533	2026-09-22 14:47	25.79	OK	17534	2026-09-22 14:48	25.17	OK
17535	2026-09-22 14:49	25.18	OK	17536	2026-09-22 14:50	24.73	OK
17537	2026-09-22 14:51	25.50	OK	17538	2026-09-22 14:52	25.05	OK
17539	2026-09-22 14:53	26.02	OK	17540	2026-09-22 14:54	25.70	OK
17541	2026-09-22 14:55	25.99	OK	17542	2026-09-22 14:56	25.31	OK
17543	2026-09-22 14:57	26.23	OK	17544	2026-09-22 14:58	24.39	OK
17545	2026-09-22 14:59	25.26	OK	17546	2026-09-22 15:00	25.51	OK
17547	2026-09-22 15:01	24.32	OK	17548	2026-09-22 15:02	26.80	OK
17549	2026-09-22 15:03	25.97	OK	17550	2026-09-22 15:04	26.89	OK
17551	2026-09-22 15:05	23.85	OK	17552	2026-09-22 15:06	24.78	OK
17553	2026-09-22 15:07	25.95	OK	17554	2026-09-22 15:08	26.36	OK
17555	2026-09-22 15:09	26.22	OK	17556	2026-09-22 15:10	26.72	OK
17557	2026-09-22 15:11	26.68	OK	17558	2026-09-22 15:12	27.87	OK
17559	2026-09-22 15:13	26.19	OK	17560	2026-09-22 15:14	25.69	OK
17561	2026-09-22 15:15	27.00	OK	17562	2026-09-22 15:16	27.07	OK
17563	2026-09-22 15:17	27.10	OK	17564	2026-09-22 15:18	27.20	OK
17565	2026-09-22 15:19	25.49	OK	17566	2026-09-22 15:20	25.91	OK
17567	2026-09-22 15:21	25.96	OK	17568	2026-09-22 15:22	24.94	OK
17569	2026-09-22 15:23	26.65	OK	17570	2026-09-22 15:24	25.12	OK
17571	2026-09-22 15:25	26.27	OK	17572	2026-09-22 15:26	27.54	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17573	2026-09-22 15:27	25.59	OK	17574	2026-09-22 15:28	25.36	OK
17575	2026-09-22 15:29	26.49	OK	17576	2026-09-22 15:30	26.33	OK
17577	2026-09-22 15:31	25.66	OK	17578	2026-09-22 15:32	26.77	OK
17579	2026-09-22 15:33	24.46	OK	17580	2026-09-22 15:34	24.80	OK
17581	2026-09-22 15:35	27.63	OK	17582	2026-09-22 15:36	27.72	OK
17583	2026-09-22 15:37	26.15	OK	17584	2026-09-22 15:38	26.68	OK
17585	2026-09-22 15:39	25.63	OK	17586	2026-09-22 15:40	26.04	OK
17587	2026-09-22 15:41	27.84	OK	17588	2026-09-22 15:42	25.15	OK
17589	2026-09-22 15:43	25.28	OK	17590	2026-09-22 15:44	24.76	OK
17591	2026-09-22 15:45	27.38	OK	17592	2026-09-22 15:46	26.75	OK
17593	2026-09-22 15:47	24.87	OK	17594	2026-09-22 15:48	25.09	OK
17595	2026-09-22 15:49	25.77	OK	17596	2026-09-22 15:50	27.69	OK
17597	2026-09-22 15:51	26.02	OK	17598	2026-09-22 15:52	25.95	OK
17599	2026-09-22 15:53	25.73	OK	17600	2026-09-22 15:54	25.90	OK
17601	2026-09-22 15:55	25.11	OK	17602	2026-09-22 15:56	26.00	OK
17603	2026-09-22 15:57	26.13	OK	17604	2026-09-22 15:58	25.86	OK
17605	2026-09-22 15:59	25.57	OK	17606	2026-09-22 16:00	25.92	OK
17607	2026-09-22 16:01	26.86	OK	17608	2026-09-22 16:02	26.60	OK
17609	2026-09-22 16:03	26.03	OK	17610	2026-09-22 16:04	25.42	OK
17611	2026-09-22 16:05	25.60	OK	17612	2026-09-22 16:06	26.55	OK
17613	2026-09-22 16:07	25.14	OK	17614	2026-09-22 16:08	26.62	OK
17615	2026-09-22 16:09	25.86	OK	17616	2026-09-22 16:10	26.28	OK
17617	2026-09-22 16:11	25.35	OK	17618	2026-09-22 16:12	26.09	OK
17619	2026-09-22 16:13	26.45	OK	17620	2026-09-22 16:14	25.86	OK
17621	2026-09-22 16:15	26.08	OK	17622	2026-09-22 16:16	26.00	OK
17623	2026-09-22 16:17	26.47	OK	17624	2026-09-22 16:18	27.38	OK
17625	2026-09-22 16:19	25.45	OK	17626	2026-09-22 16:20	26.68	OK
17627	2026-09-22 16:21	27.04	OK	17628	2026-09-22 16:22	26.64	OK
17629	2026-09-22 16:23	26.13	OK	17630	2026-09-22 16:24	25.29	OK
17631	2026-09-22 16:25	26.22	OK	17632	2026-09-22 16:26	25.97	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17633	2026-09-22 16:27	25.83	OK	17634	2026-09-22 16:28	25.18	OK
17635	2026-09-22 16:29	26.13	OK	17636	2026-09-22 16:30	26.62	OK
17637	2026-09-22 16:31	26.11	OK	17638	2026-09-22 16:32	27.79	OK
17639	2026-09-22 16:33	26.08	OK	17640	2026-09-22 16:34	26.47	OK
17641	2026-09-22 16:35	24.44	OK	17642	2026-09-22 16:36	26.57	OK
17643	2026-09-22 16:37	26.18	OK	17644	2026-09-22 16:38	26.20	OK
17645	2026-09-22 16:39	26.09	OK	17646	2026-09-22 16:40	26.09	OK
17647	2026-09-22 16:41	25.58	OK	17648	2026-09-22 16:42	26.68	OK
17649	2026-09-22 16:43	25.93	OK	17650	2026-09-22 16:44	25.27	OK
17651	2026-09-22 16:45	27.72	OK	17652	2026-09-22 16:46	24.64	OK
17653	2026-09-22 16:47	26.42	OK	17654	2026-09-22 16:48	26.91	OK
17655	2026-09-22 16:49	26.83	OK	17656	2026-09-22 16:50	26.38	OK
17657	2026-09-22 16:51	26.75	OK	17658	2026-09-22 16:52	26.29	OK
17659	2026-09-22 16:53	25.84	OK	17660	2026-09-22 16:54	26.60	OK
17661	2026-09-22 16:55	27.55	OK	17662	2026-09-22 16:56	25.67	OK
17663	2026-09-22 16:57	26.69	OK	17664	2026-09-22 16:58	26.71	OK
17665	2026-09-22 16:59	27.29	OK	17666	2026-09-22 17:00	25.65	OK
17667	2026-09-22 17:01	26.56	OK	17668	2026-09-22 17:02	26.80	OK
17669	2026-09-22 17:03	27.41	OK	17670	2026-09-22 17:04	27.31	OK
17671	2026-09-22 17:05	27.06	OK	17672	2026-09-22 17:06	26.35	OK
17673	2026-09-22 17:07	26.60	OK	17674	2026-09-22 17:08	26.08	OK
17675	2026-09-22 17:09	25.36	OK	17676	2026-09-22 17:10	25.99	OK
17677	2026-09-22 17:11	28.23	OK	17678	2026-09-22 17:12	26.26	OK
17679	2026-09-22 17:13	28.22	OK	17680	2026-09-22 17:14	26.00	OK
17681	2026-09-22 17:15	27.08	OK	17682	2026-09-22 17:16	26.35	OK
17683	2026-09-22 17:17	27.38	OK	17684	2026-09-22 17:18	27.66	OK
17685	2026-09-22 17:19	26.90	OK	17686	2026-09-22 17:20	26.60	OK
17687	2026-09-22 17:21	27.08	OK	17688	2026-09-22 17:22	27.79	OK
17689	2026-09-22 17:23	26.72	OK	17690	2026-09-22 17:24	26.73	OK
17691	2026-09-22 17:25	27.30	OK	17692	2026-09-22 17:26	26.90	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17693	2026-09-22 17:27	28.05	OK	17694	2026-09-22 17:28	28.07	OK
17695	2026-09-22 17:29	26.74	OK	17696	2026-09-22 17:30	27.15	OK
17697	2026-09-22 17:31	26.22	OK	17698	2026-09-22 17:32	27.80	OK
17699	2026-09-22 17:33	25.41	OK	17700	2026-09-22 17:34	25.75	OK
17701	2026-09-22 17:35	27.63	OK	17702	2026-09-22 17:36	25.92	OK
17703	2026-09-22 17:37	25.90	OK	17704	2026-09-22 17:38	25.67	OK
17705	2026-09-22 17:39	27.61	OK	17706	2026-09-22 17:40	26.59	OK
17707	2026-09-22 17:41	26.82	OK	17708	2026-09-22 17:42	26.62	OK
17709	2026-09-22 17:43	26.36	OK	17710	2026-09-22 17:44	28.18	OK
17711	2026-09-22 17:45	27.69	OK	17712	2026-09-22 17:46	27.29	OK
17713	2026-09-22 17:47	26.62	OK	17714	2026-09-22 17:48	25.89	OK
17715	2026-09-22 17:49	27.39	OK	17716	2026-09-22 17:50	26.83	OK
17717	2026-09-22 17:51	27.20	OK	17718	2026-09-22 17:52	27.49	OK
17719	2026-09-22 17:53	27.11	OK	17720	2026-09-22 17:54	28.46	OK
17721	2026-09-22 17:55	28.25	OK	17722	2026-09-22 17:56	26.98	OK
17723	2026-09-22 17:57	27.10	OK	17724	2026-09-22 17:58	27.41	OK
17725	2026-09-22 17:59	26.93	OK	17726	2026-09-22 18:00	26.93	OK
17727	2026-09-22 18:01	26.05	OK	17728	2026-09-22 18:02	27.29	OK
17729	2026-09-22 18:03	26.89	OK	17730	2026-09-22 18:04	27.39	OK
17731	2026-09-22 18:05	27.11	OK	17732	2026-09-22 18:06	26.41	OK
17733	2026-09-22 18:07	28.26	OK	17734	2026-09-22 18:08	26.84	OK
17735	2026-09-22 18:09	26.33	OK	17736	2026-09-22 18:10	28.38	OK
17737	2026-09-22 18:11	25.17	OK	17738	2026-09-22 18:12	28.26	OK
17739	2026-09-22 18:13	25.39	OK	17740	2026-09-22 18:14	27.39	OK
17741	2026-09-22 18:15	27.38	OK	17742	2026-09-22 18:16	25.85	OK
17743	2026-09-22 18:17	27.43	OK	17744	2026-09-22 18:18	26.79	OK
17745	2026-09-22 18:19	27.26	OK	17746	2026-09-22 18:20	27.44	OK
17747	2026-09-22 18:21	27.38	OK	17748	2026-09-22 18:22	27.77	OK
17749	2026-09-22 18:23	26.69	OK	17750	2026-09-22 18:24	27.37	OK
17751	2026-09-22 18:25	27.80	OK	17752	2026-09-22 18:26	27.21	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17753	2026-09-22 18:27	27.01	OK	17754	2026-09-22 18:28	27.16	OK
17755	2026-09-22 18:29	27.95	OK	17756	2026-09-22 18:30	27.60	OK
17757	2026-09-22 18:31	26.82	OK	17758	2026-09-22 18:32	26.86	OK
17759	2026-09-22 18:33	27.29	OK	17760	2026-09-22 18:34	26.06	OK
17761	2026-09-22 18:35	26.91	OK	17762	2026-09-22 18:36	27.85	OK
17763	2026-09-22 18:37	27.14	OK	17764	2026-09-22 18:38	26.41	OK
17765	2026-09-22 18:39	27.53	OK	17766	2026-09-22 18:40	27.23	OK
17767	2026-09-22 18:41	28.41	OK	17768	2026-09-22 18:42	29.25	OK
17769	2026-09-22 18:43	27.21	OK	17770	2026-09-22 18:44	27.82	OK
17771	2026-09-22 18:45	27.30	OK	17772	2026-09-22 18:46	27.41	OK
17773	2026-09-22 18:47	28.07	OK	17774	2026-09-22 18:48	28.77	OK
17775	2026-09-22 18:49	26.59	OK	17776	2026-09-22 18:50	26.06	OK
17777	2026-09-22 18:51	26.27	OK	17778	2026-09-22 18:52	27.77	OK
17779	2026-09-22 18:53	27.86	OK	17780	2026-09-22 18:54	26.29	OK
17781	2026-09-22 18:55	27.95	OK	17782	2026-09-22 18:56	28.03	OK
17783	2026-09-22 18:57	27.47	OK	17784	2026-09-22 18:58	28.07	OK
17785	2026-09-22 18:59	27.46	OK	17786	2026-09-22 19:00	26.89	OK
17787	2026-09-22 19:01	28.51	OK	17788	2026-09-22 19:02	27.49	OK
17789	2026-09-22 19:03	27.36	OK	17790	2026-09-22 19:04	28.12	OK
17791	2026-09-22 19:05	28.44	OK	17792	2026-09-22 19:06	26.00	OK
17793	2026-09-22 19:07	27.82	OK	17794	2026-09-22 19:08	27.34	OK
17795	2026-09-22 19:09	28.61	OK	17796	2026-09-22 19:10	26.86	OK
17797	2026-09-22 19:11	28.58	OK	17798	2026-09-22 19:12	26.81	OK
17799	2026-09-22 19:13	27.03	OK	17800	2026-09-22 19:14	26.90	OK
17801	2026-09-22 19:15	27.78	OK	17802	2026-09-22 19:16	27.84	OK
17803	2026-09-22 19:17	27.94	OK	17804	2026-09-22 19:18	27.94	OK
17805	2026-09-22 19:19	29.07	OK	17806	2026-09-22 19:20	27.18	OK
17807	2026-09-22 19:21	29.00	OK	17808	2026-09-22 19:22	28.52	OK
17809	2026-09-22 19:23	27.88	OK	17810	2026-09-22 19:24	29.11	OK
17811	2026-09-22 19:25	27.52	OK	17812	2026-09-22 19:26	28.36	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17813	2026-09-22 19:27	28.63	OK	17814	2026-09-22 19:28	27.02	OK
17815	2026-09-22 19:29	28.83	OK	17816	2026-09-22 19:30	26.27	OK
17817	2026-09-22 19:31	27.99	OK	17818	2026-09-22 19:32	28.07	OK
17819	2026-09-22 19:33	27.53	OK	17820	2026-09-22 19:34	26.64	OK
17821	2026-09-22 19:35	26.39	OK	17822	2026-09-22 19:36	27.26	OK
17823	2026-09-22 19:37	27.10	OK	17824	2026-09-22 19:38	27.94	OK
17825	2026-09-22 19:39	27.46	OK	17826	2026-09-22 19:40	28.16	OK
17827	2026-09-22 19:41	28.86	OK	17828	2026-09-22 19:42	28.80	OK
17829	2026-09-22 19:43	26.96	OK	17830	2026-09-22 19:44	28.62	OK
17831	2026-09-22 19:45	29.76	OK	17832	2026-09-22 19:46	28.75	OK
17833	2026-09-22 19:47	28.91	OK	17834	2026-09-22 19:48	26.49	OK
17835	2026-09-22 19:49	28.85	OK	17836	2026-09-22 19:50	28.45	OK
17837	2026-09-22 19:51	29.25	OK	17838	2026-09-22 19:52	28.44	OK
17839	2026-09-22 19:53	28.15	OK	17840	2026-09-22 19:54	27.16	OK
17841	2026-09-22 19:55	28.82	OK	17842	2026-09-22 19:56	28.80	OK
17843	2026-09-22 19:57	28.90	OK	17844	2026-09-22 19:58	28.08	OK
17845	2026-09-22 19:59	27.87	OK	17846	2026-09-22 20:00	28.34	OK
17847	2026-09-22 20:01	29.92	OK	17848	2026-09-22 20:02	28.73	OK
17849	2026-09-22 20:03	28.26	OK	17850	2026-09-22 20:04	28.36	OK
17851	2026-09-22 20:05	28.06	OK	17852	2026-09-22 20:06	28.53	OK
17853	2026-09-22 20:07	27.76	OK	17854	2026-09-22 20:08	28.36	OK
17855	2026-09-22 20:09	27.64	OK	17856	2026-09-22 20:10	29.83	OK
17857	2026-09-22 20:11	27.91	OK	17858	2026-09-22 20:12	30.48	OK
17859	2026-09-22 20:13	29.48	OK	17860	2026-09-22 20:14	28.38	OK
17861	2026-09-22 20:15	28.10	OK	17862	2026-09-22 20:16	27.79	OK
17863	2026-09-22 20:17	28.20	OK	17864	2026-09-22 20:18	27.34	OK
17865	2026-09-22 20:19	29.51	OK	17866	2026-09-22 20:20	29.31	OK
17867	2026-09-22 20:21	27.41	OK	17868	2026-09-22 20:22	28.37	OK
17869	2026-09-22 20:23	28.41	OK	17870	2026-09-22 20:24	28.23	OK
17871	2026-09-22 20:25	29.06	OK	17872	2026-09-22 20:26	28.85	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17873	2026-09-22 20:27	28.14	OK	17874	2026-09-22 20:28	27.34	OK
17875	2026-09-22 20:29	27.30	OK	17876	2026-09-22 20:30	29.90	OK
17877	2026-09-22 20:31	27.97	OK	17878	2026-09-22 20:32	27.18	OK
17879	2026-09-22 20:33	27.27	OK	17880	2026-09-22 20:34	29.95	OK
17881	2026-09-22 20:35	28.56	OK	17882	2026-09-22 20:36	28.12	OK
17883	2026-09-22 20:37	29.59	OK	17884	2026-09-22 20:38	28.18	OK
17885	2026-09-22 20:39	28.95	OK	17886	2026-09-22 20:40	28.79	OK
17887	2026-09-22 20:41	27.81	OK	17888	2026-09-22 20:42	28.87	OK
17889	2026-09-22 20:43	29.35	OK	17890	2026-09-22 20:44	28.17	OK
17891	2026-09-22 20:45	28.65	OK	17892	2026-09-22 20:46	30.07	OK
17893	2026-09-22 20:47	28.78	OK	17894	2026-09-22 20:48	29.24	OK
17895	2026-09-22 20:49	29.18	OK	17896	2026-09-22 20:50	27.99	OK
17897	2026-09-22 20:51	28.83	OK	17898	2026-09-22 20:52	28.23	OK
17899	2026-09-22 20:53	27.85	OK	17900	2026-09-22 20:54	28.67	OK
17901	2026-09-22 20:55	28.44	OK	17902	2026-09-22 20:56	29.66	OK
17903	2026-09-22 20:57	29.29	OK	17904	2026-09-22 20:58	28.83	OK
17905	2026-09-22 20:59	28.29	OK	17906	2026-09-22 21:00	29.34	OK
17907	2026-09-22 21:01	30.02	OK	17908	2026-09-22 21:02	29.73	OK
17909	2026-09-22 21:03	29.77	OK	17910	2026-09-22 21:04	29.49	OK
17911	2026-09-22 21:05	28.80	OK	17912	2026-09-22 21:06	29.80	OK
17913	2026-09-22 21:07	29.51	OK	17914	2026-09-22 21:08	28.34	OK
17915	2026-09-22 21:09	28.51	OK	17916	2026-09-22 21:10	29.54	OK
17917	2026-09-22 21:11	28.52	OK	17918	2026-09-22 21:12	27.61	OK
17919	2026-09-22 21:13	28.55	OK	17920	2026-09-22 21:14	28.03	OK
17921	2026-09-22 21:15	29.78	OK	17922	2026-09-22 21:16	28.98	OK
17923	2026-09-22 21:17	28.49	OK	17924	2026-09-22 21:18	28.30	OK
17925	2026-09-22 21:19	28.97	OK	17926	2026-09-22 21:20	28.59	OK
17927	2026-09-22 21:21	29.14	OK	17928	2026-09-22 21:22	28.45	OK
17929	2026-09-22 21:23	28.01	OK	17930	2026-09-22 21:24	29.03	OK
17931	2026-09-22 21:25	28.97	OK	17932	2026-09-22 21:26	27.58	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17933	2026-09-22 21:27	29.56	OK	17934	2026-09-22 21:28	28.19	OK
17935	2026-09-22 21:29	29.34	OK	17936	2026-09-22 21:30	29.97	OK
17937	2026-09-22 21:31	29.10	OK	17938	2026-09-22 21:32	28.77	OK
17939	2026-09-22 21:33	28.55	OK	17940	2026-09-22 21:34	29.65	OK
17941	2026-09-22 21:35	30.51	OK	17942	2026-09-22 21:36	28.97	OK
17943	2026-09-22 21:37	30.20	OK	17944	2026-09-22 21:38	28.46	OK
17945	2026-09-22 21:39	28.87	OK	17946	2026-09-22 21:40	28.30	OK
17947	2026-09-22 21:41	28.18	OK	17948	2026-09-22 21:42	28.78	OK
17949	2026-09-22 21:43	29.45	OK	17950	2026-09-22 21:44	30.88	OK
17951	2026-09-22 21:45	29.09	OK	17952	2026-09-22 21:46	28.88	OK
17953	2026-09-22 21:47	28.01	OK	17954	2026-09-22 21:48	29.34	OK
17955	2026-09-22 21:49	29.03	OK	17956	2026-09-22 21:50	28.66	OK
17957	2026-09-22 21:51	29.15	OK	17958	2026-09-22 21:52	28.86	OK
17959	2026-09-22 21:53	29.41	OK	17960	2026-09-22 21:54	29.77	OK
17961	2026-09-22 21:55	27.86	OK	17962	2026-09-22 21:56	30.96	OK
17963	2026-09-22 21:57	28.11	OK	17964	2026-09-22 21:58	28.62	OK
17965	2026-09-22 21:59	29.81	OK	17966	2026-09-22 22:00	28.56	OK
17967	2026-09-22 22:01	29.09	OK	17968	2026-09-22 22:02	29.31	OK
17969	2026-09-22 22:03	28.97	OK	17970	2026-09-22 22:04	28.91	OK
17971	2026-09-22 22:05	30.42	OK	17972	2026-09-22 22:06	30.46	OK
17973	2026-09-22 22:07	30.01	OK	17974	2026-09-22 22:08	30.73	OK
17975	2026-09-22 22:09	30.62	OK	17976	2026-09-22 22:10	29.74	OK
17977	2026-09-22 22:11	30.57	OK	17978	2026-09-22 22:12	29.32	OK
17979	2026-09-22 22:13	28.49	OK	17980	2026-09-22 22:14	29.05	OK
17981	2026-09-22 22:15	30.64	OK	17982	2026-09-22 22:16	29.94	OK
17983	2026-09-22 22:17	28.43	OK	17984	2026-09-22 22:18	30.26	OK
17985	2026-09-22 22:19	28.25	OK	17986	2026-09-22 22:20	31.16	OK
17987	2026-09-22 22:21	29.21	OK	17988	2026-09-22 22:22	28.43	OK
17989	2026-09-22 22:23	31.26	OK	17990	2026-09-22 22:24	30.96	OK
17991	2026-09-22 22:25	30.29	OK	17992	2026-09-22 22:26	28.86	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
17993	2026-09-22 22:27	29.37	OK	17994	2026-09-22 22:28	28.94	OK
17995	2026-09-22 22:29	30.64	OK	17996	2026-09-22 22:30	30.01	OK
17997	2026-09-22 22:31	30.70	OK	17998	2026-09-22 22:32	29.74	OK
17999	2026-09-22 22:33	29.00	OK	18000	2026-09-22 22:34	30.95	OK
18001	2026-09-22 22:35	28.22	OK	18002	2026-09-22 22:36	30.37	OK
18003	2026-09-22 22:37	30.77	OK	18004	2026-09-22 22:38	28.44	OK
18005	2026-09-22 22:39	30.88	OK	18006	2026-09-22 22:40	29.55	OK
18007	2026-09-22 22:41	30.95	OK	18008	2026-09-22 22:42	31.23	OK
18009	2026-09-22 22:43	29.97	OK	18010	2026-09-22 22:44	29.77	OK
18011	2026-09-22 22:45	29.85	OK	18012	2026-09-22 22:46	29.36	OK
18013	2026-09-22 22:47	31.17	OK	18014	2026-09-22 22:48	30.21	OK
18015	2026-09-22 22:49	29.69	OK	18016	2026-09-22 22:50	31.43	OK
18017	2026-09-22 22:51	30.00	OK	18018	2026-09-22 22:52	30.38	OK
18019	2026-09-22 22:53	30.38	OK	18020	2026-09-22 22:54	31.06	OK
18021	2026-09-22 22:55	30.11	OK	18022	2026-09-22 22:56	28.49	OK
18023	2026-09-22 22:57	29.42	OK	18024	2026-09-22 22:58	28.90	OK
18025	2026-09-22 22:59	29.57	OK	18026	2026-09-22 23:00	31.02	OK
18027	2026-09-22 23:01	30.70	OK	18028	2026-09-22 23:02	30.54	OK
18029	2026-09-22 23:03	30.14	OK	18030	2026-09-22 23:04	31.16	OK
18031	2026-09-22 23:05	31.09	OK	18032	2026-09-22 23:06	30.74	OK
18033	2026-09-22 23:07	29.68	OK	18034	2026-09-22 23:08	30.06	OK
18035	2026-09-22 23:09	30.55	OK	18036	2026-09-22 23:10	29.80	OK
18037	2026-09-22 23:11	29.33	OK	18038	2026-09-22 23:12	30.35	OK
18039	2026-09-22 23:13	29.69	OK	18040	2026-09-22 23:14	29.70	OK
18041	2026-09-22 23:15	30.15	OK	18042	2026-09-22 23:16	29.47	OK
18043	2026-09-22 23:17	30.88	OK	18044	2026-09-22 23:18	30.49	OK
18045	2026-09-22 23:19	28.79	OK	18046	2026-09-22 23:20	29.68	OK
18047	2026-09-22 23:21	29.98	OK	18048	2026-09-22 23:22	29.94	OK
18049	2026-09-22 23:23	30.58	OK	18050	2026-09-22 23:24	28.69	OK
18051	2026-09-22 23:25	28.80	OK	18052	2026-09-22 23:26	29.51	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18053	2026-09-22 23:27	29.78	OK	18054	2026-09-22 23:28	29.18	OK
18055	2026-09-22 23:29	29.39	OK	18056	2026-09-22 23:30	30.13	OK
18057	2026-09-22 23:31	30.51	OK	18058	2026-09-22 23:32	29.96	OK
18059	2026-09-22 23:33	28.37	OK	18060	2026-09-22 23:34	28.59	OK
18061	2026-09-22 23:35	31.71	OK	18062	2026-09-22 23:36	30.89	OK
18063	2026-09-22 23:37	29.81	OK	18064	2026-09-22 23:38	30.01	OK
18065	2026-09-22 23:39	29.70	OK	18066	2026-09-22 23:40	32.18	OK
18067	2026-09-22 23:41	30.88	OK	18068	2026-09-22 23:42	31.10	OK
18069	2026-09-22 23:43	31.11	OK	18070	2026-09-22 23:44	31.37	OK
18071	2026-09-22 23:45	30.78	OK	18072	2026-09-22 23:46	30.37	OK
18073	2026-09-22 23:47	29.78	OK	18074	2026-09-22 23:48	30.02	OK
18075	2026-09-22 23:49	31.08	OK	18076	2026-09-22 23:50	29.44	OK
18077	2026-09-22 23:51	30.71	OK	18078	2026-09-22 23:52	30.44	OK
18079	2026-09-22 23:53	30.66	OK	18080	2026-09-22 23:54	29.84	OK
18081	2026-09-22 23:55	30.01	OK	18082	2026-09-22 23:56	30.53	OK
18083	2026-09-22 23:57	29.95	OK	18084	2026-09-22 23:58	30.87	OK
18085	2026-09-22 23:59	29.48	OK	18086	2026-09-23 00:00	30.59	OK
18087	2026-09-23 00:01	29.87	OK	18088	2026-09-23 00:02	30.16	OK
18089	2026-09-23 00:03	29.22	OK	18090	2026-09-23 00:04	31.98	OK
18091	2026-09-23 00:05	29.80	OK	18092	2026-09-23 00:06	28.18	OK
18093	2026-09-23 00:07	30.12	OK	18094	2026-09-23 00:08	30.87	OK
18095	2026-09-23 00:09	28.96	OK	18096	2026-09-23 00:10	30.14	OK
18097	2026-09-23 00:11	31.64	OK	18098	2026-09-23 00:12	29.49	OK
18099	2026-09-23 00:13	31.11	OK	18100	2026-09-23 00:14	30.03	OK
18101	2026-09-23 00:15	30.36	OK	18102	2026-09-23 00:16	30.42	OK
18103	2026-09-23 00:17	30.94	OK	18104	2026-09-23 00:18	28.98	OK
18105	2026-09-23 00:19	30.23	OK	18106	2026-09-23 00:20	30.93	OK
18107	2026-09-23 00:21	29.71	OK	18108	2026-09-23 00:22	30.53	OK
18109	2026-09-23 00:23	30.34	OK	18110	2026-09-23 00:24	31.93	OK
18111	2026-09-23 00:25	29.64	OK	18112	2026-09-23 00:26	30.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18113	2026-09-23 00:27	30.75	OK	18114	2026-09-23 00:28	30.68	OK
18115	2026-09-23 00:29	29.50	OK	18116	2026-09-23 00:30	29.98	OK
18117	2026-09-23 00:31	30.20	OK	18118	2026-09-23 00:32	30.90	OK
18119	2026-09-23 00:33	30.69	OK	18120	2026-09-23 00:34	29.74	OK
18121	2026-09-23 00:35	29.12	OK	18122	2026-09-23 00:36	30.70	OK
18123	2026-09-23 00:37	31.50	OK	18124	2026-09-23 00:38	29.08	OK
18125	2026-09-23 00:39	31.23	OK	18126	2026-09-23 00:40	29.57	OK
18127	2026-09-23 00:41	29.42	OK	18128	2026-09-23 00:42	30.37	OK
18129	2026-09-23 00:43	29.46	OK	18130	2026-09-23 00:44	31.07	OK
18131	2026-09-23 00:45	30.58	OK	18132	2026-09-23 00:46	31.39	OK
18133	2026-09-23 00:47	29.07	OK	18134	2026-09-23 00:48	29.12	OK
18135	2026-09-23 00:49	30.78	OK	18136	2026-09-23 00:50	30.92	OK
18137	2026-09-23 00:51	28.91	OK	18138	2026-09-23 00:52	30.47	OK
18139	2026-09-23 00:53	31.53	OK	18140	2026-09-23 00:54	31.32	OK
18141	2026-09-23 00:55	31.69	OK	18142	2026-09-23 00:56	29.78	OK
18143	2026-09-23 00:57	30.14	OK	18144	2026-09-23 00:58	30.20	OK
18145	2026-09-23 00:59	30.50	OK	18146	2026-09-23 01:00	31.08	OK
18147	2026-09-23 01:01	31.09	OK	18148	2026-09-23 01:02	30.22	OK
18149	2026-09-23 01:03	30.46	OK	18150	2026-09-23 01:04	30.14	OK
18151	2026-09-23 01:05	30.38	OK	18152	2026-09-23 01:06	31.31	OK
18153	2026-09-23 01:07	31.77	OK	18154	2026-09-23 01:08	29.77	OK
18155	2026-09-23 01:09	29.21	OK	18156	2026-09-23 01:10	29.91	OK
18157	2026-09-23 01:11	30.23	OK	18158	2026-09-23 01:12	30.03	OK
18159	2026-09-23 01:13	30.39	OK	18160	2026-09-23 01:14	29.71	OK
18161	2026-09-23 01:15	30.80	OK	18162	2026-09-23 01:16	30.39	OK
18163	2026-09-23 01:17	31.20	OK	18164	2026-09-23 01:18	30.29	OK
18165	2026-09-23 01:19	31.23	OK	18166	2026-09-23 01:20	30.84	OK
18167	2026-09-23 01:21	29.65	OK	18168	2026-09-23 01:22	30.81	OK
18169	2026-09-23 01:23	30.56	OK	18170	2026-09-23 01:24	30.29	OK
18171	2026-09-23 01:25	29.22	OK	18172	2026-09-23 01:26	29.79	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18173	2026-09-23 01:27	30.21	OK	18174	2026-09-23 01:28	29.68	OK
18175	2026-09-23 01:29	31.03	OK	18176	2026-09-23 01:30	30.79	OK
18177	2026-09-23 01:31	30.52	OK	18178	2026-09-23 01:32	29.25	OK
18179	2026-09-23 01:33	31.23	OK	18180	2026-09-23 01:34	29.31	OK
18181	2026-09-23 01:35	29.62	OK	18182	2026-09-23 01:36	30.11	OK
18183	2026-09-23 01:37	31.97	OK	18184	2026-09-23 01:38	29.31	OK
18185	2026-09-23 01:39	31.59	OK	18186	2026-09-23 01:40	30.03	OK
18187	2026-09-23 01:41	30.54	OK	18188	2026-09-23 01:42	31.03	OK
18189	2026-09-23 01:43	29.45	OK	18190	2026-09-23 01:44	30.97	OK
18191	2026-09-23 01:45	32.03	OK	18192	2026-09-23 01:46	29.89	OK
18193	2026-09-23 01:47	29.60	OK	18194	2026-09-23 01:48	31.04	OK
18195	2026-09-23 01:49	31.27	OK	18196	2026-09-23 01:50	31.45	OK
18197	2026-09-23 01:51	30.05	OK	18198	2026-09-23 01:52	31.07	OK
18199	2026-09-23 01:53	30.70	OK	18200	2026-09-23 01:54	30.25	OK
18201	2026-09-23 01:55	30.35	OK	18202	2026-09-23 01:56	30.73	OK
18203	2026-09-23 01:57	29.42	OK	18204	2026-09-23 01:58	29.85	OK
18205	2026-09-23 01:59	28.83	OK	18206	2026-09-23 02:00	30.94	OK
18207	2026-09-23 02:01	30.79	OK	18208	2026-09-23 02:02	31.98	OK
18209	2026-09-23 02:03	30.36	OK	18210	2026-09-23 02:04	30.93	OK
18211	2026-09-23 02:05	30.09	OK	18212	2026-09-23 02:06	30.02	OK
18213	2026-09-23 02:07	29.67	OK	18214	2026-09-23 02:08	30.52	OK
18215	2026-09-23 02:09	30.25	OK	18216	2026-09-23 02:10	30.88	OK
18217	2026-09-23 02:11	31.26	OK	18218	2026-09-23 02:12	30.22	OK
18219	2026-09-23 02:13	30.27	OK	18220	2026-09-23 02:14	29.79	OK
18221	2026-09-23 02:15	31.02	OK	18222	2026-09-23 02:16	30.45	OK
18223	2026-09-23 02:17	31.10	OK	18224	2026-09-23 02:18	29.64	OK
18225	2026-09-23 02:19	30.07	OK	18226	2026-09-23 02:20	29.05	OK
18227	2026-09-23 02:21	30.23	OK	18228	2026-09-23 02:22	29.92	OK
18229	2026-09-23 02:23	28.64	OK	18230	2026-09-23 02:24	29.34	OK
18231	2026-09-23 02:25	30.76	OK	18232	2026-09-23 02:26	30.23	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18233	2026-09-23 02:27	31.49	OK	18234	2026-09-23 02:28	29.91	OK
18235	2026-09-23 02:29	29.50	OK	18236	2026-09-23 02:30	30.06	OK
18237	2026-09-23 02:31	29.23	OK	18238	2026-09-23 02:32	29.67	OK
18239	2026-09-23 02:33	31.46	OK	18240	2026-09-23 02:34	28.51	OK
18241	2026-09-23 02:35	29.12	OK	18242	2026-09-23 02:36	31.02	OK
18243	2026-09-23 02:37	30.07	OK	18244	2026-09-23 02:38	29.00	OK
18245	2026-09-23 02:39	29.75	OK	18246	2026-09-23 02:40	31.67	OK
18247	2026-09-23 02:41	30.34	OK	18248	2026-09-23 02:42	30.58	OK
18249	2026-09-23 02:43	31.70	OK	18250	2026-09-23 02:44	30.42	OK
18251	2026-09-23 02:45	29.42	OK	18252	2026-09-23 02:46	31.11	OK
18253	2026-09-23 02:47	29.09	OK	18254	2026-09-23 02:48	31.48	OK
18255	2026-09-23 02:49	29.85	OK	18256	2026-09-23 02:50	31.33	OK
18257	2026-09-23 02:51	30.63	OK	18258	2026-09-23 02:52	29.76	OK
18259	2026-09-23 02:53	30.21	OK	18260	2026-09-23 02:54	29.49	OK
18261	2026-09-23 02:55	30.39	OK	18262	2026-09-23 02:56	31.67	OK
18263	2026-09-23 02:57	31.67	OK	18264	2026-09-23 02:58	30.99	OK
18265	2026-09-23 02:59	29.90	OK	18266	2026-09-23 03:00	30.20	OK
18267	2026-09-23 03:01	30.07	OK	18268	2026-09-23 03:02	29.50	OK
18269	2026-09-23 03:03	29.74	OK	18270	2026-09-23 03:04	30.72	OK
18271	2026-09-23 03:05	29.40	OK	18272	2026-09-23 03:06	30.77	OK
18273	2026-09-23 03:07	30.59	OK	18274	2026-09-23 03:08	30.89	OK
18275	2026-09-23 03:09	29.45	OK	18276	2026-09-23 03:10	30.27	OK
18277	2026-09-23 03:11	30.67	OK	18278	2026-09-23 03:12	31.47	OK
18279	2026-09-23 03:13	28.87	OK	18280	2026-09-23 03:14	30.27	OK
18281	2026-09-23 03:15	29.95	OK	18282	2026-09-23 03:16	29.68	OK
18283	2026-09-23 03:17	31.11	OK	18284	2026-09-23 03:18	30.16	OK
18285	2026-09-23 03:19	30.01	OK	18286	2026-09-23 03:20	29.67	OK
18287	2026-09-23 03:21	29.34	OK	18288	2026-09-23 03:22	29.07	OK
18289	2026-09-23 03:23	28.60	OK	18290	2026-09-23 03:24	30.42	OK
18291	2026-09-23 03:25	29.74	OK	18292	2026-09-23 03:26	30.12	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18293	2026-09-23 03:27	28.48	OK	18294	2026-09-23 03:28	29.71	OK
18295	2026-09-23 03:29	29.80	OK	18296	2026-09-23 03:30	30.37	OK
18297	2026-09-23 03:31	29.48	OK	18298	2026-09-23 03:32	31.25	OK
18299	2026-09-23 03:33	29.41	OK	18300	2026-09-23 03:34	29.78	OK
18301	2026-09-23 03:35	30.77	OK	18302	2026-09-23 03:36	29.22	OK
18303	2026-09-23 03:37	30.21	OK	18304	2026-09-23 03:38	28.77	OK
18305	2026-09-23 03:39	30.10	OK	18306	2026-09-23 03:40	30.11	OK
18307	2026-09-23 03:41	30.11	OK	18308	2026-09-23 03:42	30.31	OK
18309	2026-09-23 03:43	29.18	OK	18310	2026-09-23 03:44	30.08	OK
18311	2026-09-23 03:45	29.70	OK	18312	2026-09-23 03:46	29.21	OK
18313	2026-09-23 03:47	28.40	OK	18314	2026-09-23 03:48	28.84	OK
18315	2026-09-23 03:49	30.01	OK	18316	2026-09-23 03:50	29.36	OK
18317	2026-09-23 03:51	31.08	OK	18318	2026-09-23 03:52	30.70	OK
18319	2026-09-23 03:53	29.13	OK	18320	2026-09-23 03:54	28.91	OK
18321	2026-09-23 03:55	30.98	OK	18322	2026-09-23 03:56	31.30	OK
18323	2026-09-23 03:57	29.50	OK	18324	2026-09-23 03:58	30.56	OK
18325	2026-09-23 03:59	31.08	OK	18326	2026-09-23 04:00	29.30	OK
18327	2026-09-23 04:01	30.58	OK	18328	2026-09-23 04:02	30.55	OK
18329	2026-09-23 04:03	29.82	OK	18330	2026-09-23 04:04	30.79	OK
18331	2026-09-23 04:05	29.49	OK	18332	2026-09-23 04:06	29.76	OK
18333	2026-09-23 04:07	28.87	OK	18334	2026-09-23 04:08	30.17	OK
18335	2026-09-23 04:09	29.26	OK	18336	2026-09-23 04:10	30.13	OK
18337	2026-09-23 04:11	29.17	OK	18338	2026-09-23 04:12	28.66	OK
18339	2026-09-23 04:13	28.07	OK	18340	2026-09-23 04:14	30.64	OK
18341	2026-09-23 04:15	29.68	OK	18342	2026-09-23 04:16	29.73	OK
18343	2026-09-23 04:17	29.49	OK	18344	2026-09-23 04:18	28.47	OK
18345	2026-09-23 04:19	30.09	OK	18346	2026-09-23 04:20	29.00	OK
18347	2026-09-23 04:21	29.66	OK	18348	2026-09-23 04:22	29.27	OK
18349	2026-09-23 04:23	29.42	OK	18350	2026-09-23 04:24	30.21	OK
18351	2026-09-23 04:25	30.27	OK	18352	2026-09-23 04:26	30.48	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18353	2026-09-23 04:27	29.27	OK	18354	2026-09-23 04:28	30.34	OK
18355	2026-09-23 04:29	29.04	OK	18356	2026-09-23 04:30	29.74	OK
18357	2026-09-23 04:31	30.04	OK	18358	2026-09-23 04:32	28.98	OK
18359	2026-09-23 04:33	29.57	OK	18360	2026-09-23 04:34	29.47	OK
18361	2026-09-23 04:35	27.97	OK	18362	2026-09-23 04:36	29.28	OK
18363	2026-09-23 04:37	30.31	OK	18364	2026-09-23 04:38	29.97	OK
18365	2026-09-23 04:39	29.26	OK	18366	2026-09-23 04:40	29.69	OK
18367	2026-09-23 04:41	28.83	OK	18368	2026-09-23 04:42	28.73	OK
18369	2026-09-23 04:43	28.77	OK	18370	2026-09-23 04:44	29.50	OK
18371	2026-09-23 04:45	28.59	OK	18372	2026-09-23 04:46	29.50	OK
18373	2026-09-23 04:47	30.72	OK	18374	2026-09-23 04:48	30.64	OK
18375	2026-09-23 04:49	29.25	OK	18376	2026-09-23 04:50	31.07	OK
18377	2026-09-23 04:51	29.56	OK	18378	2026-09-23 04:52	28.64	OK
18379	2026-09-23 04:53	28.05	OK	18380	2026-09-23 04:54	29.31	OK
18381	2026-09-23 04:55	29.25	OK	18382	2026-09-23 04:56	29.95	OK
18383	2026-09-23 04:57	29.17	OK	18384	2026-09-23 04:58	30.69	OK
18385	2026-09-23 04:59	28.92	OK	18386	2026-09-23 05:00	30.03	OK
18387	2026-09-23 05:01	28.83	OK	18388	2026-09-23 05:02	28.98	OK
18389	2026-09-23 05:03	29.68	OK	18390	2026-09-23 05:04	29.72	OK
18391	2026-09-23 05:05	29.46	OK	18392	2026-09-23 05:06	27.49	OK
18393	2026-09-23 05:07	31.34	OK	18394	2026-09-23 05:08	28.95	OK
18395	2026-09-23 05:09	29.82	OK	18396	2026-09-23 05:10	29.11	OK
18397	2026-09-23 05:11	29.48	OK	18398	2026-09-23 05:12	29.81	OK
18399	2026-09-23 05:13	30.14	OK	18400	2026-09-23 05:14	29.19	OK
18401	2026-09-23 05:15	28.54	OK	18402	2026-09-23 05:16	28.04	OK
18403	2026-09-23 05:17	29.22	OK	18404	2026-09-23 05:18	29.72	OK
18405	2026-09-23 05:19	27.79	OK	18406	2026-09-23 05:20	29.96	OK
18407	2026-09-23 05:21	28.51	OK	18408	2026-09-23 05:22	28.60	OK
18409	2026-09-23 05:23	29.13	OK	18410	2026-09-23 05:24	29.30	OK
18411	2026-09-23 05:25	30.20	OK	18412	2026-09-23 05:26	28.31	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18413	2026-09-23 05:27	28.54	OK	18414	2026-09-23 05:28	27.78	OK
18415	2026-09-23 05:29	28.05	OK	18416	2026-09-23 05:30	27.28	OK
18417	2026-09-23 05:31	29.77	OK	18418	2026-09-23 05:32	29.06	OK
18419	2026-09-23 05:33	29.58	OK	18420	2026-09-23 05:34	29.42	OK
18421	2026-09-23 05:35	29.62	OK	18422	2026-09-23 05:36	28.32	OK
18423	2026-09-23 05:37	28.72	OK	18424	2026-09-23 05:38	29.25	OK
18425	2026-09-23 05:39	27.48	OK	18426	2026-09-23 05:40	29.63	OK
18427	2026-09-23 05:41	29.23	OK	18428	2026-09-23 05:42	28.31	OK
18429	2026-09-23 05:43	28.36	OK	18430	2026-09-23 05:44	29.53	OK
18431	2026-09-23 05:45	29.17	OK	18432	2026-09-23 05:46	29.43	OK
18433	2026-09-23 05:47	28.98	OK	18434	2026-09-23 05:48	28.09	OK
18435	2026-09-23 05:49	29.36	OK	18436	2026-09-23 05:50	28.12	OK
18437	2026-09-23 05:51	28.93	OK	18438	2026-09-23 05:52	29.50	OK
18439	2026-09-23 05:53	27.87	OK	18440	2026-09-23 05:54	28.29	OK
18441	2026-09-23 05:55	29.61	OK	18442	2026-09-23 05:56	27.37	OK
18443	2026-09-23 05:57	28.62	OK	18444	2026-09-23 05:58	30.10	OK
18445	2026-09-23 05:59	28.06	OK	18446	2026-09-23 06:00	27.49	OK
18447	2026-09-23 06:01	28.72	OK	18448	2026-09-23 06:02	28.06	OK
18449	2026-09-23 06:03	29.67	OK	18450	2026-09-23 06:04	29.27	OK
18451	2026-09-23 06:05	28.34	OK	18452	2026-09-23 06:06	28.84	OK
18453	2026-09-23 06:07	29.27	OK	18454	2026-09-23 06:08	28.63	OK
18455	2026-09-23 06:09	27.87	OK	18456	2026-09-23 06:10	29.57	OK
18457	2026-09-23 06:11	29.16	OK	18458	2026-09-23 06:12	28.18	OK
18459	2026-09-23 06:13	28.93	OK	18460	2026-09-23 06:14	30.35	OK
18461	2026-09-23 06:15	29.07	OK	18462	2026-09-23 06:16	27.61	OK
18463	2026-09-23 06:17	27.39	OK	18464	2026-09-23 06:18	27.12	OK
18465	2026-09-23 06:19	28.28	OK	18466	2026-09-23 06:20	29.52	OK
18467	2026-09-23 06:21	28.88	OK	18468	2026-09-23 06:22	28.64	OK
18469	2026-09-23 06:23	29.26	OK	18470	2026-09-23 06:24	27.69	OK
18471	2026-09-23 06:25	29.68	OK	18472	2026-09-23 06:26	28.01	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18473	2026-09-23 06:27	28.93	OK	18474	2026-09-23 06:28	30.25	OK
18475	2026-09-23 06:29	26.99	OK	18476	2026-09-23 06:30	29.90	OK
18477	2026-09-23 06:31	27.93	OK	18478	2026-09-23 06:32	28.90	OK
18479	2026-09-23 06:33	29.20	OK	18480	2026-09-23 06:34	28.28	OK
18481	2026-09-23 06:35	27.33	OK	18482	2026-09-23 06:36	27.85	OK
18483	2026-09-23 06:37	30.05	OK	18484	2026-09-23 06:38	29.68	OK
18485	2026-09-23 06:39	27.30	OK	18486	2026-09-23 06:40	28.20	OK
18487	2026-09-23 06:41	27.92	OK	18488	2026-09-23 06:42	28.04	OK
18489	2026-09-23 06:43	28.81	OK	18490	2026-09-23 06:44	28.49	OK
18491	2026-09-23 06:45	28.34	OK	18492	2026-09-23 06:46	28.32	OK
18493	2026-09-23 06:47	30.41	OK	18494	2026-09-23 06:48	27.84	OK
18495	2026-09-23 06:49	28.37	OK	18496	2026-09-23 06:50	28.60	OK
18497	2026-09-23 06:51	27.88	OK	18498	2026-09-23 06:52	29.41	OK
18499	2026-09-23 06:53	30.21	OK	18500	2026-09-23 06:54	29.28	OK
18501	2026-09-23 06:55	28.75	OK	18502	2026-09-23 06:56	29.08	OK
18503	2026-09-23 06:57	28.53	OK	18504	2026-09-23 06:58	28.81	OK
18505	2026-09-23 06:59	27.54	OK	18506	2026-09-23 07:00	29.10	OK
18507	2026-09-23 07:01	27.75	OK	18508	2026-09-23 07:02	27.62	OK
18509	2026-09-23 07:03	29.31	OK	18510	2026-09-23 07:04	29.65	OK
18511	2026-09-23 07:05	29.10	OK	18512	2026-09-23 07:06	28.85	OK
18513	2026-09-23 07:07	28.16	OK	18514	2026-09-23 07:08	27.59	OK
18515	2026-09-23 07:09	27.96	OK	18516	2026-09-23 07:10	28.10	OK
18517	2026-09-23 07:11	28.24	OK	18518	2026-09-23 07:12	28.00	OK
18519	2026-09-23 07:13	27.83	OK	18520	2026-09-23 07:14	27.92	OK
18521	2026-09-23 07:15	27.98	OK	18522	2026-09-23 07:16	29.56	OK
18523	2026-09-23 07:17	26.60	OK	18524	2026-09-23 07:18	28.42	OK
18525	2026-09-23 07:19	27.58	OK	18526	2026-09-23 07:20	28.65	OK
18527	2026-09-23 07:21	27.67	OK	18528	2026-09-23 07:22	27.15	OK
18529	2026-09-23 07:23	28.81	OK	18530	2026-09-23 07:24	27.68	OK
18531	2026-09-23 07:25	28.11	OK	18532	2026-09-23 07:26	27.11	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18533	2026-09-23 07:27	28.24	OK	18534	2026-09-23 07:28	26.47	OK
18535	2026-09-23 07:29	28.93	OK	18536	2026-09-23 07:30	28.11	OK
18537	2026-09-23 07:31	28.86	OK	18538	2026-09-23 07:32	28.69	OK
18539	2026-09-23 07:33	28.04	OK	18540	2026-09-23 07:34	27.44	OK
18541	2026-09-23 07:35	26.79	OK	18542	2026-09-23 07:36	28.28	OK
18543	2026-09-23 07:37	28.28	OK	18544	2026-09-23 07:38	28.33	OK
18545	2026-09-23 07:39	28.35	OK	18546	2026-09-23 07:40	27.50	OK
18547	2026-09-23 07:41	27.83	OK	18548	2026-09-23 07:42	27.17	OK
18549	2026-09-23 07:43	27.88	OK	18550	2026-09-23 07:44	28.10	OK
18551	2026-09-23 07:45	27.32	OK	18552	2026-09-23 07:46	29.18	OK
18553	2026-09-23 07:47	29.43	OK	18554	2026-09-23 07:48	28.09	OK
18555	2026-09-23 07:49	28.32	OK	18556	2026-09-23 07:50	27.38	OK
18557	2026-09-23 07:51	29.13	OK	18558	2026-09-23 07:52	27.95	OK
18559	2026-09-23 07:53	27.28	OK	18560	2026-09-23 07:54	28.36	OK
18561	2026-09-23 07:55	29.13	OK	18562	2026-09-23 07:56	27.79	OK
18563	2026-09-23 07:57	28.42	OK	18564	2026-09-23 07:58	26.72	OK
18565	2026-09-23 07:59	27.79	OK	18566	2026-09-23 08:00	27.31	OK
18567	2026-09-23 08:01	28.93	OK	18568	2026-09-23 08:02	27.99	OK
18569	2026-09-23 08:03	27.42	OK	18570	2026-09-23 08:04	27.29	OK
18571	2026-09-23 08:05	29.21	OK	18572	2026-09-23 08:06	27.97	OK
18573	2026-09-23 08:07	27.00	OK	18574	2026-09-23 08:08	27.34	OK
18575	2026-09-23 08:09	27.33	OK	18576	2026-09-23 08:10	27.30	OK
18577	2026-09-23 08:11	27.46	OK	18578	2026-09-23 08:12	26.74	OK
18579	2026-09-23 08:13	26.76	OK	18580	2026-09-23 08:14	26.36	OK
18581	2026-09-23 08:15	28.00	OK	18582	2026-09-23 08:16	27.78	OK
18583	2026-09-23 08:17	25.79	OK	18584	2026-09-23 08:18	28.83	OK
18585	2026-09-23 08:19	27.09	OK	18586	2026-09-23 08:20	26.45	OK
18587	2026-09-23 08:21	26.35	OK	18588	2026-09-23 08:22	27.52	OK
18589	2026-09-23 08:23	27.50	OK	18590	2026-09-23 08:24	28.89	OK
18591	2026-09-23 08:25	25.52	OK	18592	2026-09-23 08:26	25.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18593	2026-09-23 08:27	27.36	OK	18594	2026-09-23 08:28	28.15	OK
18595	2026-09-23 08:29	27.24	OK	18596	2026-09-23 08:30	27.86	OK
18597	2026-09-23 08:31	26.53	OK	18598	2026-09-23 08:32	26.66	OK
18599	2026-09-23 08:33	26.86	OK	18600	2026-09-23 08:34	28.18	OK
18601	2026-09-23 08:35	28.42	OK	18602	2026-09-23 08:36	28.26	OK
18603	2026-09-23 08:37	27.05	OK	18604	2026-09-23 08:38	26.60	OK
18605	2026-09-23 08:39	27.89	OK	18606	2026-09-23 08:40	28.27	OK
18607	2026-09-23 08:41	28.38	OK	18608	2026-09-23 08:42	26.89	OK
18609	2026-09-23 08:43	26.90	OK	18610	2026-09-23 08:44	26.89	OK
18611	2026-09-23 08:45	27.87	OK	18612	2026-09-23 08:46	27.83	OK
18613	2026-09-23 08:47	27.23	OK	18614	2026-09-23 08:48	27.04	OK
18615	2026-09-23 08:49	27.42	OK	18616	2026-09-23 08:50	26.02	OK
18617	2026-09-23 08:51	26.07	OK	18618	2026-09-23 08:52	28.05	OK
18619	2026-09-23 08:53	27.60	OK	18620	2026-09-23 08:54	27.39	OK
18621	2026-09-23 08:55	25.95	OK	18622	2026-09-23 08:56	27.21	OK
18623	2026-09-23 08:57	26.48	OK	18624	2026-09-23 08:58	27.27	OK
18625	2026-09-23 08:59	27.98	OK	18626	2026-09-23 09:00	26.90	OK
18627	2026-09-23 09:01	27.79	OK	18628	2026-09-23 09:02	25.83	OK
18629	2026-09-23 09:03	26.65	OK	18630	2026-09-23 09:04	27.35	OK
18631	2026-09-23 09:05	26.17	OK	18632	2026-09-23 09:06	26.59	OK
18633	2026-09-23 09:07	26.41	OK	18634	2026-09-23 09:08	28.35	OK
18635	2026-09-23 09:09	28.10	OK	18636	2026-09-23 09:10	27.09	OK
18637	2026-09-23 09:11	27.20	OK	18638	2026-09-23 09:12	28.10	OK
18639	2026-09-23 09:13	28.07	OK	18640	2026-09-23 09:14	27.93	OK
18641	2026-09-23 09:15	27.13	OK	18642	2026-09-23 09:16	27.60	OK
18643	2026-09-23 09:17	27.42	OK	18644	2026-09-23 09:18	25.86	OK
18645	2026-09-23 09:19	27.39	OK	18646	2026-09-23 09:20	26.40	OK
18647	2026-09-23 09:21	27.76	OK	18648	2026-09-23 09:22	27.15	OK
18649	2026-09-23 09:23	25.60	OK	18650	2026-09-23 09:24	25.75	OK
18651	2026-09-23 09:25	26.95	OK	18652	2026-09-23 09:26	26.51	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18653	2026-09-23 09:27	25.18	OK	18654	2026-09-23 09:28	25.63	OK
18655	2026-09-23 09:29	27.27	OK	18656	2026-09-23 09:30	25.32	OK
18657	2026-09-23 09:31	28.11	OK	18658	2026-09-23 09:32	27.16	OK
18659	2026-09-23 09:33	26.23	OK	18660	2026-09-23 09:34	26.55	OK
18661	2026-09-23 09:35	28.15	OK	18662	2026-09-23 09:36	25.94	OK
18663	2026-09-23 09:37	27.08	OK	18664	2026-09-23 09:38	26.46	OK
18665	2026-09-23 09:39	25.99	OK	18666	2026-09-23 09:40	26.74	OK
18667	2026-09-23 09:41	27.49	OK	18668	2026-09-23 09:42	26.79	OK
18669	2026-09-23 09:43	27.70	OK	18670	2026-09-23 09:44	27.39	OK
18671	2026-09-23 09:45	26.15	OK	18672	2026-09-23 09:46	27.58	OK
18673	2026-09-23 09:47	26.99	OK	18674	2026-09-23 09:48	27.62	OK
18675	2026-09-23 09:49	25.50	OK	18676	2026-09-23 09:50	26.07	OK
18677	2026-09-23 09:51	26.89	OK	18678	2026-09-23 09:52	26.66	OK
18679	2026-09-23 09:53	27.36	OK	18680	2026-09-23 09:54	27.29	OK
18681	2026-09-23 09:55	26.02	OK	18682	2026-09-23 09:56	25.70	OK
18683	2026-09-23 09:57	26.69	OK	18684	2026-09-23 09:58	24.75	OK
18685	2026-09-23 09:59	26.97	OK	18686	2026-09-23 10:00	26.20	OK
18687	2026-09-23 10:01	27.03	OK	18688	2026-09-23 10:02	27.57	OK
18689	2026-09-23 10:03	26.15	OK	18690	2026-09-23 10:04	26.08	OK
18691	2026-09-23 10:05	25.92	OK	18692	2026-09-23 10:06	25.34	OK
18693	2026-09-23 10:07	26.30	OK	18694	2026-09-23 10:08	26.02	OK
18695	2026-09-23 10:09	25.69	OK	18696	2026-09-23 10:10	25.48	OK
18697	2026-09-23 10:11	27.71	OK	18698	2026-09-23 10:12	27.59	OK
18699	2026-09-23 10:13	27.79	OK	18700	2026-09-23 10:14	26.34	OK
18701	2026-09-23 10:15	26.04	OK	18702	2026-09-23 10:16	27.09	OK
18703	2026-09-23 10:17	27.62	OK	18704	2026-09-23 10:18	27.34	OK
18705	2026-09-23 10:19	26.24	OK	18706	2026-09-23 10:20	26.41	OK
18707	2026-09-23 10:21	25.65	OK	18708	2026-09-23 10:22	26.63	OK
18709	2026-09-23 10:23	27.22	OK	18710	2026-09-23 10:24	26.58	OK
18711	2026-09-23 10:25	26.67	OK	18712	2026-09-23 10:26	25.97	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18713	2026-09-23 10:27	27.21	OK	18714	2026-09-23 10:28	25.51	OK
18715	2026-09-23 10:29	28.46	OK	18716	2026-09-23 10:30	26.22	OK
18717	2026-09-23 10:31	24.76	OK	18718	2026-09-23 10:32	25.79	OK
18719	2026-09-23 10:33	26.34	OK	18720	2026-09-23 10:34	26.30	OK
18721	2026-09-23 10:35	27.27	OK	18722	2026-09-23 10:36	26.60	OK
18723	2026-09-23 10:37	25.27	OK	18724	2026-09-23 10:38	26.81	OK
18725	2026-09-23 10:39	25.93	OK	18726	2026-09-23 10:40	25.88	OK
18727	2026-09-23 10:41	24.87	OK	18728	2026-09-23 10:42	25.77	OK
18729	2026-09-23 10:43	28.08	OK	18730	2026-09-23 10:44	26.61	OK
18731	2026-09-23 10:45	27.07	OK	18732	2026-09-23 10:46	25.56	OK
18733	2026-09-23 10:47	25.51	OK	18734	2026-09-23 10:48	25.99	OK
18735	2026-09-23 10:49	26.48	OK	18736	2026-09-23 10:50	25.75	OK
18737	2026-09-23 10:51	27.60	OK	18738	2026-09-23 10:52	25.95	OK
18739	2026-09-23 10:53	25.78	OK	18740	2026-09-23 10:54	25.69	OK
18741	2026-09-23 10:55	26.50	OK	18742	2026-09-23 10:56	27.10	OK
18743	2026-09-23 10:57	26.40	OK	18744	2026-09-23 10:58	26.16	OK
18745	2026-09-23 10:59	26.51	OK	18746	2026-09-23 11:00	24.63	OK
18747	2026-09-23 11:01	26.01	OK	18748	2026-09-23 11:02	25.71	OK
18749	2026-09-23 11:03	26.56	OK	18750	2026-09-23 11:04	25.95	OK
18751	2026-09-23 11:05	27.65	OK	18752	2026-09-23 11:06	26.30	OK
18753	2026-09-23 11:07	26.40	OK	18754	2026-09-23 11:08	25.78	OK
18755	2026-09-23 11:09	27.17	OK	18756	2026-09-23 11:10	26.03	OK
18757	2026-09-23 11:11	26.87	OK	18758	2026-09-23 11:12	27.27	OK
18759	2026-09-23 11:13	26.31	OK	18760	2026-09-23 11:14	25.63	OK
18761	2026-09-23 11:15	26.04	OK	18762	2026-09-23 11:16	26.17	OK
18763	2026-09-23 11:17	27.06	OK	18764	2026-09-23 11:18	25.77	OK
18765	2026-09-23 11:19	25.43	OK	18766	2026-09-23 11:20	27.35	OK
18767	2026-09-23 11:21	25.74	OK	18768	2026-09-23 11:22	27.15	OK
18769	2026-09-23 11:23	26.20	OK	18770	2026-09-23 11:24	24.72	OK
18771	2026-09-23 11:25	26.40	OK	18772	2026-09-23 11:26	25.91	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18773	2026-09-23 11:27	27.16	OK	18774	2026-09-23 11:28	26.62	OK
18775	2026-09-23 11:29	26.24	OK	18776	2026-09-23 11:30	26.42	OK
18777	2026-09-23 11:31	25.19	OK	18778	2026-09-23 11:32	27.18	OK
18779	2026-09-23 11:33	25.64	OK	18780	2026-09-23 11:34	25.72	OK
18781	2026-09-23 11:35	27.02	OK	18782	2026-09-23 11:36	26.49	OK
18783	2026-09-23 11:37	27.85	OK	18784	2026-09-23 11:38	26.31	OK
18785	2026-09-23 11:39	25.92	OK	18786	2026-09-23 11:40	25.44	OK
18787	2026-09-23 11:41	26.34	OK	18788	2026-09-23 11:42	25.27	OK
18789	2026-09-23 11:43	27.23	OK	18790	2026-09-23 11:44	26.76	OK
18791	2026-09-23 11:45	26.25	OK	18792	2026-09-23 11:46	25.16	OK
18793	2026-09-23 11:47	26.92	OK	18794	2026-09-23 11:48	26.59	OK
18795	2026-09-23 11:49	25.77	OK	18796	2026-09-23 11:50	25.71	OK
18797	2026-09-23 11:51	25.61	OK	18798	2026-09-23 11:52	26.13	OK
18799	2026-09-23 11:53	25.23	OK	18800	2026-09-23 11:54	25.79	OK
18801	2026-09-23 11:55	26.67	OK	18802	2026-09-23 11:56	25.14	OK
18803	2026-09-23 11:57	25.28	OK	18804	2026-09-23 11:58	27.40	OK
18805	2026-09-23 11:59	26.06	OK	18806	2026-09-23 12:00	26.30	OK
18807	2026-09-23 12:01	26.93	OK	18808	2026-09-23 12:02	25.47	OK
18809	2026-09-23 12:03	26.38	OK	18810	2026-09-23 12:04	25.59	OK
18811	2026-09-23 12:05	25.39	OK	18812	2026-09-23 12:06	25.04	OK
18813	2026-09-23 12:07	24.60	OK	18814	2026-09-23 12:08	26.14	OK
18815	2026-09-23 12:09	26.25	OK	18816	2026-09-23 12:10	26.00	OK
18817	2026-09-23 12:11	25.98	OK	18818	2026-09-23 12:12	25.91	OK
18819	2026-09-23 12:13	25.53	OK	18820	2026-09-23 12:14	25.55	OK
18821	2026-09-23 12:15	25.67	OK	18822	2026-09-23 12:16	25.94	OK
18823	2026-09-23 12:17	26.02	OK	18824	2026-09-23 12:18	26.50	OK
18825	2026-09-23 12:19	24.59	OK	18826	2026-09-23 12:20	25.18	OK
18827	2026-09-23 12:21	25.64	OK	18828	2026-09-23 12:22	27.39	OK
18829	2026-09-23 12:23	25.85	OK	18830	2026-09-23 12:24	25.19	OK
18831	2026-09-23 12:25	26.55	OK	18832	2026-09-23 12:26	25.19	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18833	2026-09-23 12:27	26.12	OK	18834	2026-09-23 12:28	26.22	OK
18835	2026-09-23 12:29	25.74	OK	18836	2026-09-23 12:30	25.25	OK
18837	2026-09-23 12:31	25.46	OK	18838	2026-09-23 12:32	25.34	OK
18839	2026-09-23 12:33	26.44	OK	18840	2026-09-23 12:34	26.23	OK
18841	2026-09-23 12:35	24.92	OK	18842	2026-09-23 12:36	24.38	OK
18843	2026-09-23 12:37	27.49	OK	18844	2026-09-23 12:38	26.83	OK
18845	2026-09-23 12:39	25.34	OK	18846	2026-09-23 12:40	25.80	OK
18847	2026-09-23 12:41	25.33	OK	18848	2026-09-23 12:42	25.45	OK
18849	2026-09-23 12:43	25.55	OK	18850	2026-09-23 12:44	24.75	OK
18851	2026-09-23 12:45	24.98	OK	18852	2026-09-23 12:46	26.00	OK
18853	2026-09-23 12:47	25.41	OK	18854	2026-09-23 12:48	26.10	OK
18855	2026-09-23 12:49	25.43	OK	18856	2026-09-23 12:50	26.52	OK
18857	2026-09-23 12:51	27.66	OK	18858	2026-09-23 12:52	25.69	OK
18859	2026-09-23 12:53	27.11	OK	18860	2026-09-23 12:54	26.15	OK
18861	2026-09-23 12:55	27.20	OK	18862	2026-09-23 12:56	26.68	OK
18863	2026-09-23 12:57	24.35	OK	18864	2026-09-23 12:58	25.19	OK
18865	2026-09-23 12:59	23.65	OK	18866	2026-09-23 13:00	27.16	OK
18867	2026-09-23 13:01	25.77	OK	18868	2026-09-23 13:02	26.55	OK
18869	2026-09-23 13:03	24.86	OK	18870	2026-09-23 13:04	26.54	OK
18871	2026-09-23 13:05	24.56	OK	18872	2026-09-23 13:06	26.74	OK
18873	2026-09-23 13:07	27.15	OK	18874	2026-09-23 13:08	25.11	OK
18875	2026-09-23 13:09	25.24	OK	18876	2026-09-23 13:10	26.69	OK
18877	2026-09-23 13:11	25.54	OK	18878	2026-09-23 13:12	25.69	OK
18879	2026-09-23 13:13	25.63	OK	18880	2026-09-23 13:14	24.31	OK
18881	2026-09-23 13:15	25.14	OK	18882	2026-09-23 13:16	24.21	OK
18883	2026-09-23 13:17	23.86	OK	18884	2026-09-23 13:18	25.57	OK
18885	2026-09-23 13:19	25.53	OK	18886	2026-09-23 13:20	25.62	OK
18887	2026-09-23 13:21	24.86	OK	18888	2026-09-23 13:22	25.48	OK
18889	2026-09-23 13:23	26.12	OK	18890	2026-09-23 13:24	26.58	OK
18891	2026-09-23 13:25	25.71	OK	18892	2026-09-23 13:26	25.82	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18893	2026-09-23 13:27	25.59	OK	18894	2026-09-23 13:28	24.81	OK
18895	2026-09-23 13:29	25.95	OK	18896	2026-09-23 13:30	24.13	OK
18897	2026-09-23 13:31	25.60	OK	18898	2026-09-23 13:32	26.04	OK
18899	2026-09-23 13:33	24.36	OK	18900	2026-09-23 13:34	24.95	OK
18901	2026-09-23 13:35	23.81	OK	18902	2026-09-23 13:36	25.20	OK
18903	2026-09-23 13:37	25.52	OK	18904	2026-09-23 13:38	23.47	OK
18905	2026-09-23 13:39	24.92	OK	18906	2026-09-23 13:40	26.35	OK
18907	2026-09-23 13:41	24.00	OK	18908	2026-09-23 13:42	26.57	OK
18909	2026-09-23 13:43	26.37	OK	18910	2026-09-23 13:44	26.05	OK
18911	2026-09-23 13:45	25.07	OK	18912	2026-09-23 13:46	27.17	OK
18913	2026-09-23 13:47	25.56	OK	18914	2026-09-23 13:48	25.61	OK
18915	2026-09-23 13:49	25.31	OK	18916	2026-09-23 13:50	26.72	OK
18917	2026-09-23 13:51	25.21	OK	18918	2026-09-23 13:52	25.75	OK
18919	2026-09-23 13:53	26.40	OK	18920	2026-09-23 13:54	25.87	OK
18921	2026-09-23 13:55	26.40	OK	18922	2026-09-23 13:56	26.38	OK
18923	2026-09-23 13:57	26.34	OK	18924	2026-09-23 13:58	26.75	OK
18925	2026-09-23 13:59	25.12	OK	18926	2026-09-23 14:00	24.96	OK
18927	2026-09-23 14:01	25.96	OK	18928	2026-09-23 14:02	24.94	OK
18929	2026-09-23 14:03	24.21	OK	18930	2026-09-23 14:04	25.98	OK
18931	2026-09-23 14:05	26.16	OK	18932	2026-09-23 14:06	26.66	OK
18933	2026-09-23 14:07	25.74	OK	18934	2026-09-23 14:08	25.55	OK
18935	2026-09-23 14:09	25.36	OK	18936	2026-09-23 14:10	25.38	OK
18937	2026-09-23 14:11	26.21	OK	18938	2026-09-23 14:12	27.30	OK
18939	2026-09-23 14:13	27.10	OK	18940	2026-09-23 14:14	24.74	OK
18941	2026-09-23 14:15	26.28	OK	18942	2026-09-23 14:16	26.54	OK
18943	2026-09-23 14:17	26.23	OK	18944	2026-09-23 14:18	26.49	OK
18945	2026-09-23 14:19	25.30	OK	18946	2026-09-23 14:20	25.97	OK
18947	2026-09-23 14:21	27.38	OK	18948	2026-09-23 14:22	24.51	OK
18949	2026-09-23 14:23	24.80	OK	18950	2026-09-23 14:24	25.35	OK
18951	2026-09-23 14:25	25.37	OK	18952	2026-09-23 14:26	25.05	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
18953	2026-09-23 14:27	26.22	OK	18954	2026-09-23 14:28	26.22	OK
18955	2026-09-23 14:29	27.06	OK	18956	2026-09-23 14:30	25.44	OK
18957	2026-09-23 14:31	26.72	OK	18958	2026-09-23 14:32	26.25	OK
18959	2026-09-23 14:33	25.71	OK	18960	2026-09-23 14:34	26.97	OK
18961	2026-09-23 14:35	26.03	OK	18962	2026-09-23 14:36	25.60	OK
18963	2026-09-23 14:37	25.73	OK	18964	2026-09-23 14:38	25.20	OK
18965	2026-09-23 14:39	25.63	OK	18966	2026-09-23 14:40	26.50	OK
18967	2026-09-23 14:41	25.74	OK	18968	2026-09-23 14:42	25.45	OK
18969	2026-09-23 14:43	24.85	OK	18970	2026-09-23 14:44	26.34	OK
18971	2026-09-23 14:45	26.16	OK	18972	2026-09-23 14:46	26.34	OK
18973	2026-09-23 14:47	24.88	OK	18974	2026-09-23 14:48	25.02	OK
18975	2026-09-23 14:49	26.12	OK	18976	2026-09-23 14:50	24.69	OK
18977	2026-09-23 14:51	26.45	OK	18978	2026-09-23 14:52	26.25	OK
18979	2026-09-23 14:53	25.43	OK	18980	2026-09-23 14:54	25.73	OK
18981	2026-09-23 14:55	26.36	OK	18982	2026-09-23 14:56	24.63	OK
18983	2026-09-23 14:57	26.83	OK	18984	2026-09-23 14:58	25.39	OK
18985	2026-09-23 14:59	26.02	OK	18986	2026-09-23 15:00	26.77	OK
18987	2026-09-23 15:01	26.51	OK	18988	2026-09-23 15:02	26.31	OK
18989	2026-09-23 15:03	25.94	OK	18990	2026-09-23 15:04	25.82	OK
18991	2026-09-23 15:05	25.60	OK	18992	2026-09-23 15:06	26.00	OK
18993	2026-09-23 15:07	25.72	OK	18994	2026-09-23 15:08	25.99	OK
18995	2026-09-23 15:09	26.32	OK	18996	2026-09-23 15:10	25.67	OK
18997	2026-09-23 15:11	24.14	OK	18998	2026-09-23 15:12	26.86	OK
18999	2026-09-23 15:13	25.14	OK	19000	2026-09-23 15:14	25.68	OK
19001	2026-09-23 15:15	26.00	OK	19002	2026-09-23 15:16	26.48	OK
19003	2026-09-23 15:17	27.79	OK	19004	2026-09-23 15:18	24.28	OK
19005	2026-09-23 15:19	25.56	OK	19006	2026-09-23 15:20	24.59	OK
19007	2026-09-23 15:21	26.25	OK	19008	2026-09-23 15:22	27.10	OK
19009	2026-09-23 15:23	27.23	OK	19010	2026-09-23 15:24	25.81	OK
19011	2026-09-23 15:25	25.71	OK	19012	2026-09-23 15:26	25.72	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19013	2026-09-23 15:27	26.36	OK	19014	2026-09-23 15:28	26.70	OK
19015	2026-09-23 15:29	24.48	OK	19016	2026-09-23 15:30	26.86	OK
19017	2026-09-23 15:31	25.67	OK	19018	2026-09-23 15:32	26.92	OK
19019	2026-09-23 15:33	26.08	OK	19020	2026-09-23 15:34	25.49	OK
19021	2026-09-23 15:35	26.10	OK	19022	2026-09-23 15:36	26.67	OK
19023	2026-09-23 15:37	26.60	OK	19024	2026-09-23 15:38	25.92	OK
19025	2026-09-23 15:39	27.01	OK	19026	2026-09-23 15:40	25.33	OK
19027	2026-09-23 15:41	26.02	OK	19028	2026-09-23 15:42	24.97	OK
19029	2026-09-23 15:43	26.11	OK	19030	2026-09-23 15:44	25.29	OK
19031	2026-09-23 15:45	26.31	OK	19032	2026-09-23 15:46	25.51	OK
19033	2026-09-23 15:47	25.73	OK	19034	2026-09-23 15:48	26.10	OK
19035	2026-09-23 15:49	25.16	OK	19036	2026-09-23 15:50	25.13	OK
19037	2026-09-23 15:51	26.70	OK	19038	2026-09-23 15:52	25.44	OK
19039	2026-09-23 15:53	25.08	OK	19040	2026-09-23 15:54	25.94	OK
19041	2026-09-23 15:55	25.42	OK	19042	2026-09-23 15:56	27.38	OK
19043	2026-09-23 15:57	26.64	OK	19044	2026-09-23 15:58	25.93	OK
19045	2026-09-23 15:59	26.08	OK	19046	2026-09-23 16:00	24.87	OK
19047	2026-09-23 16:01	27.27	OK	19048	2026-09-23 16:02	26.61	OK
19049	2026-09-23 16:03	26.17	OK	19050	2026-09-23 16:04	26.61	OK
19051	2026-09-23 16:05	26.09	OK	19052	2026-09-23 16:06	26.17	OK
19053	2026-09-23 16:07	27.30	OK	19054	2026-09-23 16:08	25.86	OK
19055	2026-09-23 16:09	25.83	OK	19056	2026-09-23 16:10	25.13	OK
19057	2026-09-23 16:11	25.72	OK	19058	2026-09-23 16:12	27.00	OK
19059	2026-09-23 16:13	25.48	OK	19060	2026-09-23 16:14	26.89	OK
19061	2026-09-23 16:15	25.89	OK	19062	2026-09-23 16:16	25.92	OK
19063	2026-09-23 16:17	26.24	OK	19064	2026-09-23 16:18	25.41	OK
19065	2026-09-23 16:19	26.86	OK	19066	2026-09-23 16:20	26.73	OK
19067	2026-09-23 16:21	26.65	OK	19068	2026-09-23 16:22	26.49	OK
19069	2026-09-23 16:23	27.66	OK	19070	2026-09-23 16:24	25.88	OK
19071	2026-09-23 16:25	26.87	OK	19072	2026-09-23 16:26	26.56	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19073	2026-09-23 16:27	27.25	OK	19074	2026-09-23 16:28	27.55	OK
19075	2026-09-23 16:29	27.29	OK	19076	2026-09-23 16:30	26.13	OK
19077	2026-09-23 16:31	25.38	OK	19078	2026-09-23 16:32	26.72	OK
19079	2026-09-23 16:33	27.16	OK	19080	2026-09-23 16:34	25.82	OK
19081	2026-09-23 16:35	26.22	OK	19082	2026-09-23 16:36	26.74	OK
19083	2026-09-23 16:37	27.42	OK	19084	2026-09-23 16:38	25.36	OK
19085	2026-09-23 16:39	25.49	OK	19086	2026-09-23 16:40	26.06	OK
19087	2026-09-23 16:41	26.96	OK	19088	2026-09-23 16:42	27.39	OK
19089	2026-09-23 16:43	27.12	OK	19090	2026-09-23 16:44	26.40	OK
19091	2026-09-23 16:45	26.02	OK	19092	2026-09-23 16:46	26.57	OK
19093	2026-09-23 16:47	26.09	OK	19094	2026-09-23 16:48	26.73	OK
19095	2026-09-23 16:49	27.69	OK	19096	2026-09-23 16:50	25.51	OK
19097	2026-09-23 16:51	26.17	OK	19098	2026-09-23 16:52	26.88	OK
19099	2026-09-23 16:53	25.18	OK	19100	2026-09-23 16:54	25.13	OK
19101	2026-09-23 16:55	27.15	OK	19102	2026-09-23 16:56	26.72	OK
19103	2026-09-23 16:57	27.21	OK	19104	2026-09-23 16:58	26.83	OK
19105	2026-09-23 16:59	26.48	OK	19106	2026-09-23 17:00	27.76	OK
19107	2026-09-23 17:01	27.85	OK	19108	2026-09-23 17:02	25.75	OK
19109	2026-09-23 17:03	27.09	OK	19110	2026-09-23 17:04	27.51	OK
19111	2026-09-23 17:05	26.78	OK	19112	2026-09-23 17:06	26.51	OK
19113	2026-09-23 17:07	26.10	OK	19114	2026-09-23 17:08	25.00	OK
19115	2026-09-23 17:09	27.05	OK	19116	2026-09-23 17:10	26.76	OK
19117	2026-09-23 17:11	27.65	OK	19118	2026-09-23 17:12	27.01	OK
19119	2026-09-23 17:13	27.42	OK	19120	2026-09-23 17:14	26.80	OK
19121	2026-09-23 17:15	26.53	OK	19122	2026-09-23 17:16	26.22	OK
19123	2026-09-23 17:17	26.27	OK	19124	2026-09-23 17:18	26.77	OK
19125	2026-09-23 17:19	26.64	OK	19126	2026-09-23 17:20	26.15	OK
19127	2026-09-23 17:21	26.99	OK	19128	2026-09-23 17:22	25.55	OK
19129	2026-09-23 17:23	27.06	OK	19130	2026-09-23 17:24	26.78	OK
19131	2026-09-23 17:25	26.21	OK	19132	2026-09-23 17:26	26.52	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19133	2026-09-23 17:27	27.54	OK	19134	2026-09-23 17:28	27.52	OK
19135	2026-09-23 17:29	27.19	OK	19136	2026-09-23 17:30	26.80	OK
19137	2026-09-23 17:31	26.26	OK	19138	2026-09-23 17:32	26.64	OK
19139	2026-09-23 17:33	25.53	OK	19140	2026-09-23 17:34	26.37	OK
19141	2026-09-23 17:35	26.80	OK	19142	2026-09-23 17:36	26.60	OK
19143	2026-09-23 17:37	27.19	OK	19144	2026-09-23 17:38	27.24	OK
19145	2026-09-23 17:39	26.14	OK	19146	2026-09-23 17:40	26.87	OK
19147	2026-09-23 17:41	27.60	OK	19148	2026-09-23 17:42	28.41	OK
19149	2026-09-23 17:43	27.48	OK	19150	2026-09-23 17:44	25.44	OK
19151	2026-09-23 17:45	27.87	OK	19152	2026-09-23 17:46	26.61	OK
19153	2026-09-23 17:47	25.58	OK	19154	2026-09-23 17:48	27.54	OK
19155	2026-09-23 17:49	27.68	OK	19156	2026-09-23 17:50	26.93	OK
19157	2026-09-23 17:51	28.82	OK	19158	2026-09-23 17:52	27.41	OK
19159	2026-09-23 17:53	28.11	OK	19160	2026-09-23 17:54	27.32	OK
19161	2026-09-23 17:55	26.34	OK	19162	2026-09-23 17:56	26.69	OK
19163	2026-09-23 17:57	26.97	OK	19164	2026-09-23 17:58	26.47	OK
19165	2026-09-23 17:59	27.57	OK	19166	2026-09-23 18:00	26.33	OK
19167	2026-09-23 18:01	27.88	OK	19168	2026-09-23 18:02	27.61	OK
19169	2026-09-23 18:03	27.77	OK	19170	2026-09-23 18:04	26.15	OK
19171	2026-09-23 18:05	27.11	OK	19172	2026-09-23 18:06	29.17	OK
19173	2026-09-23 18:07	26.73	OK	19174	2026-09-23 18:08	26.67	OK
19175	2026-09-23 18:09	27.08	OK	19176	2026-09-23 18:10	27.24	OK
19177	2026-09-23 18:11	26.60	OK	19178	2026-09-23 18:12	27.24	OK
19179	2026-09-23 18:13	27.10	OK	19180	2026-09-23 18:14	27.04	OK
19181	2026-09-23 18:15	26.70	OK	19182	2026-09-23 18:16	27.81	OK
19183	2026-09-23 18:17	28.09	OK	19184	2026-09-23 18:18	27.67	OK
19185	2026-09-23 18:19	27.19	OK	19186	2026-09-23 18:20	27.78	OK
19187	2026-09-23 18:21	27.34	OK	19188	2026-09-23 18:22	29.14	OK
19189	2026-09-23 18:23	28.50	OK	19190	2026-09-23 18:24	27.62	OK
19191	2026-09-23 18:25	28.67	OK	19192	2026-09-23 18:26	28.14	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19193	2026-09-23 18:27	28.11	OK	19194	2026-09-23 18:28	26.54	OK
19195	2026-09-23 18:29	28.28	OK	19196	2026-09-23 18:30	27.09	OK
19197	2026-09-23 18:31	26.96	OK	19198	2026-09-23 18:32	28.74	OK
19199	2026-09-23 18:33	28.37	OK	19200	2026-09-23 18:34	29.11	OK
19201	2026-09-23 18:35	27.24	OK	19202	2026-09-23 18:36	27.77	OK
19203	2026-09-23 18:37	28.49	OK	19204	2026-09-23 18:38	28.31	OK
19205	2026-09-23 18:39	27.03	OK	19206	2026-09-23 18:40	27.60	OK
19207	2026-09-23 18:41	27.37	OK	19208	2026-09-23 18:42	27.15	OK
19209	2026-09-23 18:43	28.17	OK	19210	2026-09-23 18:44	27.61	OK
19211	2026-09-23 18:45	27.94	OK	19212	2026-09-23 18:46	28.02	OK
19213	2026-09-23 18:47	28.16	OK	19214	2026-09-23 18:48	26.67	OK
19215	2026-09-23 18:49	27.80	OK	19216	2026-09-23 18:50	27.22	OK
19217	2026-09-23 18:51	27.67	OK	19218	2026-09-23 18:52	28.34	OK
19219	2026-09-23 18:53	27.87	OK	19220	2026-09-23 18:54	27.54	OK
19221	2026-09-23 18:55	29.42	OK	19222	2026-09-23 18:56	28.68	OK
19223	2026-09-23 18:57	26.50	OK	19224	2026-09-23 18:58	28.28	OK
19225	2026-09-23 18:59	29.41	OK	19226	2026-09-23 19:00	28.24	OK
19227	2026-09-23 19:01	27.25	OK	19228	2026-09-23 19:02	27.01	OK
19229	2026-09-23 19:03	27.41	OK	19230	2026-09-23 19:04	26.61	OK
19231	2026-09-23 19:05	28.08	OK	19232	2026-09-23 19:06	28.60	OK
19233	2026-09-23 19:07	27.28	OK	19234	2026-09-23 19:08	27.55	OK
19235	2026-09-23 19:09	27.31	OK	19236	2026-09-23 19:10	27.18	OK
19237	2026-09-23 19:11	27.87	OK	19238	2026-09-23 19:12	28.56	OK
19239	2026-09-23 19:13	27.63	OK	19240	2026-09-23 19:14	28.29	OK
19241	2026-09-23 19:15	26.99	OK	19242	2026-09-23 19:16	28.12	OK
19243	2026-09-23 19:17	28.18	OK	19244	2026-09-23 19:18	28.13	OK
19245	2026-09-23 19:19	29.04	OK	19246	2026-09-23 19:20	28.42	OK
19247	2026-09-23 19:21	28.66	OK	19248	2026-09-23 19:22	29.36	OK
19249	2026-09-23 19:23	29.43	OK	19250	2026-09-23 19:24	27.98	OK
19251	2026-09-23 19:25	28.61	OK	19252	2026-09-23 19:26	27.71	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19253	2026-09-23 19:27	28.59	OK	19254	2026-09-23 19:28	27.90	OK
19255	2026-09-23 19:29	27.69	OK	19256	2026-09-23 19:30	27.06	OK
19257	2026-09-23 19:31	28.84	OK	19258	2026-09-23 19:32	28.72	OK
19259	2026-09-23 19:33	28.39	OK	19260	2026-09-23 19:34	26.49	OK
19261	2026-09-23 19:35	27.11	OK	19262	2026-09-23 19:36	27.01	OK
19263	2026-09-23 19:37	28.27	OK	19264	2026-09-23 19:38	28.79	OK
19265	2026-09-23 19:39	28.72	OK	19266	2026-09-23 19:40	28.51	OK
19267	2026-09-23 19:41	29.20	OK	19268	2026-09-23 19:42	28.88	OK
19269	2026-09-23 19:43	26.47	OK	19270	2026-09-23 19:44	27.35	OK
19271	2026-09-23 19:45	29.57	OK	19272	2026-09-23 19:46	27.29	OK
19273	2026-09-23 19:47	28.76	OK	19274	2026-09-23 19:48	28.95	OK
19275	2026-09-23 19:49	29.00	OK	19276	2026-09-23 19:50	28.32	OK
19277	2026-09-23 19:51	28.33	OK	19278	2026-09-23 19:52	27.45	OK
19279	2026-09-23 19:53	27.84	OK	19280	2026-09-23 19:54	27.60	OK
19281	2026-09-23 19:55	29.08	OK	19282	2026-09-23 19:56	27.63	OK
19283	2026-09-23 19:57	28.65	OK	19284	2026-09-23 19:58	28.50	OK
19285	2026-09-23 19:59	27.99	OK	19286	2026-09-23 20:00	28.47	OK
19287	2026-09-23 20:01	26.62	OK	19288	2026-09-23 20:02	27.74	OK
19289	2026-09-23 20:03	28.25	OK	19290	2026-09-23 20:04	27.96	OK
19291	2026-09-23 20:05	27.97	OK	19292	2026-09-23 20:06	27.42	OK
19293	2026-09-23 20:07	28.30	OK	19294	2026-09-23 20:08	27.14	OK
19295	2026-09-23 20:09	28.70	OK	19296	2026-09-23 20:10	29.54	OK
19297	2026-09-23 20:11	29.23	OK	19298	2026-09-23 20:12	28.21	OK
19299	2026-09-23 20:13	28.41	OK	19300	2026-09-23 20:14	29.41	OK
19301	2026-09-23 20:15	27.94	OK	19302	2026-09-23 20:16	29.28	OK
19303	2026-09-23 20:17	28.82	OK	19304	2026-09-23 20:18	28.94	OK
19305	2026-09-23 20:19	29.29	OK	19306	2026-09-23 20:20	28.92	OK
19307	2026-09-23 20:21	27.88	OK	19308	2026-09-23 20:22	30.54	OK
19309	2026-09-23 20:23	27.67	OK	19310	2026-09-23 20:24	28.60	OK
19311	2026-09-23 20:25	28.07	OK	19312	2026-09-23 20:26	28.45	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19313	2026-09-23 20:27	27.67	OK	19314	2026-09-23 20:28	29.06	OK
19315	2026-09-23 20:29	28.28	OK	19316	2026-09-23 20:30	29.91	OK
19317	2026-09-23 20:31	27.89	OK	19318	2026-09-23 20:32	29.81	OK
19319	2026-09-23 20:33	29.62	OK	19320	2026-09-23 20:34	27.55	OK
19321	2026-09-23 20:35	28.50	OK	19322	2026-09-23 20:36	29.58	OK
19323	2026-09-23 20:37	27.34	OK	19324	2026-09-23 20:38	28.28	OK
19325	2026-09-23 20:39	28.76	OK	19326	2026-09-23 20:40	28.06	OK
19327	2026-09-23 20:41	29.58	OK	19328	2026-09-23 20:42	28.56	OK
19329	2026-09-23 20:43	29.00	OK	19330	2026-09-23 20:44	28.28	OK
19331	2026-09-23 20:45	28.10	OK	19332	2026-09-23 20:46	28.13	OK
19333	2026-09-23 20:47	29.07	OK	19334	2026-09-23 20:48	27.79	OK
19335	2026-09-23 20:49	28.14	OK	19336	2026-09-23 20:50	28.56	OK
19337	2026-09-23 20:51	28.82	OK	19338	2026-09-23 20:52	28.42	OK
19339	2026-09-23 20:53	28.82	OK	19340	2026-09-23 20:54	28.40	OK
19341	2026-09-23 20:55	27.58	OK	19342	2026-09-23 20:56	28.05	OK
19343	2026-09-23 20:57	29.30	OK	19344	2026-09-23 20:58	28.99	OK
19345	2026-09-23 20:59	29.02	OK	19346	2026-09-23 21:00	29.47	OK
19347	2026-09-23 21:01	28.99	OK	19348	2026-09-23 21:02	30.08	OK
19349	2026-09-23 21:03	28.93	OK	19350	2026-09-23 21:04	30.36	OK
19351	2026-09-23 21:05	28.79	OK	19352	2026-09-23 21:06	27.29	OK
19353	2026-09-23 21:07	28.82	OK	19354	2026-09-23 21:08	29.54	OK
19355	2026-09-23 21:09	29.18	OK	19356	2026-09-23 21:10	28.04	OK
19357	2026-09-23 21:11	30.45	OK	19358	2026-09-23 21:12	30.34	OK
19359	2026-09-23 21:13	29.40	OK	19360	2026-09-23 21:14	29.60	OK
19361	2026-09-23 21:15	29.60	OK	19362	2026-09-23 21:16	29.41	OK
19363	2026-09-23 21:17	28.69	OK	19364	2026-09-23 21:18	28.80	OK
19365	2026-09-23 21:19	29.00	OK	19366	2026-09-23 21:20	30.34	OK
19367	2026-09-23 21:21	29.50	OK	19368	2026-09-23 21:22	29.37	OK
19369	2026-09-23 21:23	29.03	OK	19370	2026-09-23 21:24	29.83	OK
19371	2026-09-23 21:25	28.01	OK	19372	2026-09-23 21:26	29.41	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19373	2026-09-23 21:27	30.68	OK	19374	2026-09-23 21:28	29.62	OK
19375	2026-09-23 21:29	30.10	OK	19376	2026-09-23 21:30	29.59	OK
19377	2026-09-23 21:31	29.65	OK	19378	2026-09-23 21:32	30.26	OK
19379	2026-09-23 21:33	29.14	OK	19380	2026-09-23 21:34	30.79	OK
19381	2026-09-23 21:35	29.82	OK	19382	2026-09-23 21:36	30.90	OK
19383	2026-09-23 21:37	28.27	OK	19384	2026-09-23 21:38	29.75	OK
19385	2026-09-23 21:39	29.98	OK	19386	2026-09-23 21:40	29.73	OK
19387	2026-09-23 21:41	29.94	OK	19388	2026-09-23 21:42	29.06	OK
19389	2026-09-23 21:43	29.52	OK	19390	2026-09-23 21:44	30.48	OK
19391	2026-09-23 21:45	29.60	OK	19392	2026-09-23 21:46	29.60	OK
19393	2026-09-23 21:47	30.10	OK	19394	2026-09-23 21:48	29.50	OK
19395	2026-09-23 21:49	29.21	OK	19396	2026-09-23 21:50	28.89	OK
19397	2026-09-23 21:51	28.22	OK	19398	2026-09-23 21:52	29.45	OK
19399	2026-09-23 21:53	27.21	OK	19400	2026-09-23 21:54	28.59	OK
19401	2026-09-23 21:55	29.58	OK	19402	2026-09-23 21:56	29.31	OK
19403	2026-09-23 21:57	28.41	OK	19404	2026-09-23 21:58	28.99	OK
19405	2026-09-23 21:59	30.68	OK	19406	2026-09-23 22:00	27.70	OK
19407	2026-09-23 22:01	30.44	OK	19408	2026-09-23 22:02	29.16	OK
19409	2026-09-23 22:03	29.79	OK	19410	2026-09-23 22:04	28.82	OK
19411	2026-09-23 22:05	28.42	OK	19412	2026-09-23 22:06	30.07	OK
19413	2026-09-23 22:07	29.06	OK	19414	2026-09-23 22:08	29.51	OK
19415	2026-09-23 22:09	29.20	OK	19416	2026-09-23 22:10	30.24	OK
19417	2026-09-23 22:11	30.03	OK	19418	2026-09-23 22:12	29.16	OK
19419	2026-09-23 22:13	29.54	OK	19420	2026-09-23 22:14	29.95	OK
19421	2026-09-23 22:15	29.07	OK	19422	2026-09-23 22:16	30.18	OK
19423	2026-09-23 22:17	29.25	OK	19424	2026-09-23 22:18	28.16	OK
19425	2026-09-23 22:19	28.21	OK	19426	2026-09-23 22:20	29.85	OK
19427	2026-09-23 22:21	29.23	OK	19428	2026-09-23 22:22	31.02	OK
19429	2026-09-23 22:23	30.48	OK	19430	2026-09-23 22:24	29.54	OK
19431	2026-09-23 22:25	30.37	OK	19432	2026-09-23 22:26	30.67	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19433	2026-09-23 22:27	31.18	OK	19434	2026-09-23 22:28	29.71	OK
19435	2026-09-23 22:29	28.19	OK	19436	2026-09-23 22:30	29.78	OK
19437	2026-09-23 22:31	28.76	OK	19438	2026-09-23 22:32	29.74	OK
19439	2026-09-23 22:33	29.04	OK	19440	2026-09-23 22:34	29.03	OK
19441	2026-09-23 22:35	31.02	OK	19442	2026-09-23 22:36	30.68	OK
19443	2026-09-23 22:37	29.69	OK	19444	2026-09-23 22:38	29.00	OK
19445	2026-09-23 22:39	30.29	OK	19446	2026-09-23 22:40	29.89	OK
19447	2026-09-23 22:41	29.75	OK	19448	2026-09-23 22:42	30.67	OK
19449	2026-09-23 22:43	29.79	OK	19450	2026-09-23 22:44	29.86	OK
19451	2026-09-23 22:45	30.03	OK	19452	2026-09-23 22:46	30.21	OK
19453	2026-09-23 22:47	28.44	OK	19454	2026-09-23 22:48	30.97	OK
19455	2026-09-23 22:49	29.85	OK	19456	2026-09-23 22:50	30.12	OK
19457	2026-09-23 22:51	29.08	OK	19458	2026-09-23 22:52	29.89	OK
19459	2026-09-23 22:53	30.58	OK	19460	2026-09-23 22:54	29.63	OK
19461	2026-09-23 22:55	29.33	OK	19462	2026-09-23 22:56	31.49	OK
19463	2026-09-23 22:57	28.78	OK	19464	2026-09-23 22:58	29.71	OK
19465	2026-09-23 22:59	30.03	OK	19466	2026-09-23 23:00	30.60	OK
19467	2026-09-23 23:01	28.90	OK	19468	2026-09-23 23:02	30.26	OK
19469	2026-09-23 23:03	28.50	OK	19470	2026-09-23 23:04	31.33	OK
19471	2026-09-23 23:05	29.15	OK	19472	2026-09-23 23:06	29.25	OK
19473	2026-09-23 23:07	30.20	OK	19474	2026-09-23 23:08	30.35	OK
19475	2026-09-23 23:09	28.57	OK	19476	2026-09-23 23:10	29.16	OK
19477	2026-09-23 23:11	30.01	OK	19478	2026-09-23 23:12	30.00	OK
19479	2026-09-23 23:13	28.73	OK	19480	2026-09-23 23:14	30.83	OK
19481	2026-09-23 23:15	29.27	OK	19482	2026-09-23 23:16	28.88	OK
19483	2026-09-23 23:17	29.33	OK	19484	2026-09-23 23:18	29.83	OK
19485	2026-09-23 23:19	30.04	OK	19486	2026-09-23 23:20	30.74	OK
19487	2026-09-23 23:21	28.89	OK	19488	2026-09-23 23:22	31.15	OK
19489	2026-09-23 23:23	30.92	OK	19490	2026-09-23 23:24	30.54	OK
19491	2026-09-23 23:25	30.21	OK	19492	2026-09-23 23:26	29.96	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19493	2026-09-23 23:27	30.47	OK	19494	2026-09-23 23:28	29.57	OK
19495	2026-09-23 23:29	30.23	OK	19496	2026-09-23 23:30	30.85	OK
19497	2026-09-23 23:31	30.21	OK	19498	2026-09-23 23:32	29.76	OK
19499	2026-09-23 23:33	31.68	OK	19500	2026-09-23 23:34	29.50	OK
19501	2026-09-23 23:35	31.13	OK	19502	2026-09-23 23:36	30.63	OK
19503	2026-09-23 23:37	29.65	OK	19504	2026-09-23 23:38	30.09	OK
19505	2026-09-23 23:39	29.74	OK	19506	2026-09-23 23:40	30.06	OK
19507	2026-09-23 23:41	30.36	OK	19508	2026-09-23 23:42	30.60	OK
19509	2026-09-23 23:43	29.57	OK	19510	2026-09-23 23:44	30.83	OK
19511	2026-09-23 23:45	29.78	OK	19512	2026-09-23 23:46	30.41	OK
19513	2026-09-23 23:47	30.47	OK	19514	2026-09-23 23:48	29.89	OK
19515	2026-09-23 23:49	31.17	OK	19516	2026-09-23 23:50	29.50	OK
19517	2026-09-23 23:51	29.76	OK	19518	2026-09-23 23:52	30.12	OK
19519	2026-09-23 23:53	30.64	OK	19520	2026-09-23 23:54	31.09	OK
19521	2026-09-23 23:55	29.73	OK	19522	2026-09-23 23:56	31.27	OK
19523	2026-09-23 23:57	29.05	OK	19524	2026-09-23 23:58	31.74	OK
19525	2026-09-23 23:59	29.12	OK	19526	2026-09-24 00:00	30.76	OK
19527	2026-09-24 00:01	30.75	OK	19528	2026-09-24 00:02	29.15	OK
19529	2026-09-24 00:03	30.99	OK	19530	2026-09-24 00:04	30.20	OK
19531	2026-09-24 00:05	30.42	OK	19532	2026-09-24 00:06	30.10	OK
19533	2026-09-24 00:07	30.73	OK	19534	2026-09-24 00:08	28.93	OK
19535	2026-09-24 00:09	31.29	OK	19536	2026-09-24 00:10	29.93	OK
19537	2026-09-24 00:11	30.77	OK	19538	2026-09-24 00:12	29.91	OK
19539	2026-09-24 00:13	30.46	OK	19540	2026-09-24 00:14	29.66	OK
19541	2026-09-24 00:15	28.51	OK	19542	2026-09-24 00:16	29.39	OK
19543	2026-09-24 00:17	30.56	OK	19544	2026-09-24 00:18	30.06	OK
19545	2026-09-24 00:19	30.26	OK	19546	2026-09-24 00:20	30.46	OK
19547	2026-09-24 00:21	30.35	OK	19548	2026-09-24 00:22	30.10	OK
19549	2026-09-24 00:23	30.99	OK	19550	2026-09-24 00:24	30.78	OK
19551	2026-09-24 00:25	30.61	OK	19552	2026-09-24 00:26	28.93	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19553	2026-09-24 00:27	31.85	OK	19554	2026-09-24 00:28	30.89	OK
19555	2026-09-24 00:29	30.23	OK	19556	2026-09-24 00:30	30.67	OK
19557	2026-09-24 00:31	30.95	OK	19558	2026-09-24 00:32	29.05	OK
19559	2026-09-24 00:33	30.23	OK	19560	2026-09-24 00:34	29.60	OK
19561	2026-09-24 00:35	28.80	OK	19562	2026-09-24 00:36	29.89	OK
19563	2026-09-24 00:37	31.44	OK	19564	2026-09-24 00:38	31.23	OK
19565	2026-09-24 00:39	31.59	OK	19566	2026-09-24 00:40	31.55	OK
19567	2026-09-24 00:41	31.20	OK	19568	2026-09-24 00:42	31.08	OK
19569	2026-09-24 00:43	31.19	OK	19570	2026-09-24 00:44	30.14	OK
19571	2026-09-24 00:45	28.80	OK	19572	2026-09-24 00:46	30.59	OK
19573	2026-09-24 00:47	29.74	OK	19574	2026-09-24 00:48	29.58	OK
19575	2026-09-24 00:49	29.87	OK	19576	2026-09-24 00:50	29.27	OK
19577	2026-09-24 00:51	30.70	OK	19578	2026-09-24 00:52	30.72	OK
19579	2026-09-24 00:53	30.26	OK	19580	2026-09-24 00:54	28.83	OK
19581	2026-09-24 00:55	30.73	OK	19582	2026-09-24 00:56	29.65	OK
19583	2026-09-24 00:57	30.29	OK	19584	2026-09-24 00:58	29.64	OK
19585	2026-09-24 00:59	29.89	OK	19586	2026-09-24 01:00	29.81	OK
19587	2026-09-24 01:01	30.50	OK	19588	2026-09-24 01:02	30.59	OK
19589	2026-09-24 01:03	29.92	OK	19590	2026-09-24 01:04	29.50	OK
19591	2026-09-24 01:05	29.53	OK	19592	2026-09-24 01:06	29.12	OK
19593	2026-09-24 01:07	30.65	OK	19594	2026-09-24 01:08	30.82	OK
19595	2026-09-24 01:09	31.18	OK	19596	2026-09-24 01:10	30.40	OK
19597	2026-09-24 01:11	29.85	OK	19598	2026-09-24 01:12	30.94	OK
19599	2026-09-24 01:13	30.97	OK	19600	2026-09-24 01:14	30.56	OK
19601	2026-09-24 01:15	30.21	OK	19602	2026-09-24 01:16	30.24	OK
19603	2026-09-24 01:17	30.66	OK	19604	2026-09-24 01:18	30.79	OK
19605	2026-09-24 01:19	30.34	OK	19606	2026-09-24 01:20	31.31	OK
19607	2026-09-24 01:21	30.71	OK	19608	2026-09-24 01:22	29.29	OK
19609	2026-09-24 01:23	31.57	OK	19610	2026-09-24 01:24	30.84	OK
19611	2026-09-24 01:25	29.77	OK	19612	2026-09-24 01:26	30.52	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19613	2026-09-24 01:27	30.02	OK	19614	2026-09-24 01:28	30.05	OK
19615	2026-09-24 01:29	31.70	OK	19616	2026-09-24 01:30	29.32	OK
19617	2026-09-24 01:31	28.35	OK	19618	2026-09-24 01:32	31.47	OK
19619	2026-09-24 01:33	30.48	OK	19620	2026-09-24 01:34	30.51	OK
19621	2026-09-24 01:35	31.92	OK	19622	2026-09-24 01:36	29.45	OK
19623	2026-09-24 01:37	29.61	OK	19624	2026-09-24 01:38	30.27	OK
19625	2026-09-24 01:39	31.45	OK	19626	2026-09-24 01:40	28.88	OK
19627	2026-09-24 01:41	29.58	OK	19628	2026-09-24 01:42	29.13	OK
19629	2026-09-24 01:43	31.28	OK	19630	2026-09-24 01:44	29.57	OK
19631	2026-09-24 01:45	29.38	OK	19632	2026-09-24 01:46	29.45	OK
19633	2026-09-24 01:47	29.95	OK	19634	2026-09-24 01:48	29.58	OK
19635	2026-09-24 01:49	30.36	OK	19636	2026-09-24 01:50	29.64	OK
19637	2026-09-24 01:51	29.93	OK	19638	2026-09-24 01:52	31.01	OK
19639	2026-09-24 01:53	29.92	OK	19640	2026-09-24 01:54	30.57	OK
19641	2026-09-24 01:55	31.03	OK	19642	2026-09-24 01:56	31.44	OK
19643	2026-09-24 01:57	30.27	OK	19644	2026-09-24 01:58	30.88	OK
19645	2026-09-24 01:59	30.95	OK	19646	2026-09-24 02:00	29.62	OK
19647	2026-09-24 02:01	30.81	OK	19648	2026-09-24 02:02	30.31	OK
19649	2026-09-24 02:03	29.96	OK	19650	2026-09-24 02:04	31.91	OK
19651	2026-09-24 02:05	29.17	OK	19652	2026-09-24 02:06	29.10	OK
19653	2026-09-24 02:07	28.80	OK	19654	2026-09-24 02:08	29.83	OK
19655	2026-09-24 02:09	30.49	OK	19656	2026-09-24 02:10	29.94	OK
19657	2026-09-24 02:11	29.24	OK	19658	2026-09-24 02:12	30.75	OK
19659	2026-09-24 02:13	30.34	OK	19660	2026-09-24 02:14	29.39	OK
19661	2026-09-24 02:15	29.93	OK	19662	2026-09-24 02:16	30.74	OK
19663	2026-09-24 02:17	29.95	OK	19664	2026-09-24 02:18	30.32	OK
19665	2026-09-24 02:19	29.85	OK	19666	2026-09-24 02:20	29.79	OK
19667	2026-09-24 02:21	29.16	OK	19668	2026-09-24 02:22	30.34	OK
19669	2026-09-24 02:23	30.31	OK	19670	2026-09-24 02:24	29.90	OK
19671	2026-09-24 02:25	29.11	OK	19672	2026-09-24 02:26	30.26	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19673	2026-09-24 02:27	29.82	OK	19674	2026-09-24 02:28	31.20	OK
19675	2026-09-24 02:29	29.52	OK	19676	2026-09-24 02:30	30.61	OK
19677	2026-09-24 02:31	29.24	OK	19678	2026-09-24 02:32	29.98	OK
19679	2026-09-24 02:33	29.29	OK	19680	2026-09-24 02:34	29.31	OK
19681	2026-09-24 02:35	29.81	OK	19682	2026-09-24 02:36	29.97	OK
19683	2026-09-24 02:37	30.48	OK	19684	2026-09-24 02:38	30.50	OK
19685	2026-09-24 02:39	30.73	OK	19686	2026-09-24 02:40	30.38	OK
19687	2026-09-24 02:41	30.64	OK	19688	2026-09-24 02:42	30.30	OK
19689	2026-09-24 02:43	31.12	OK	19690	2026-09-24 02:44	29.08	OK
19691	2026-09-24 02:45	29.72	OK	19692	2026-09-24 02:46	29.63	OK
19693	2026-09-24 02:47	30.30	OK	19694	2026-09-24 02:48	30.05	OK
19695	2026-09-24 02:49	29.75	OK	19696	2026-09-24 02:50	31.17	OK
19697	2026-09-24 02:51	31.14	OK	19698	2026-09-24 02:52	29.88	OK
19699	2026-09-24 02:53	29.72	OK	19700	2026-09-24 02:54	29.59	OK
19701	2026-09-24 02:55	30.10	OK	19702	2026-09-24 02:56	28.85	OK
19703	2026-09-24 02:57	27.99	OK	19704	2026-09-24 02:58	29.36	OK
19705	2026-09-24 02:59	30.48	OK	19706	2026-09-24 03:00	28.62	OK
19707	2026-09-24 03:01	31.28	OK	19708	2026-09-24 03:02	29.23	OK
19709	2026-09-24 03:03	30.14	OK	19710	2026-09-24 03:04	28.49	OK
19711	2026-09-24 03:05	31.35	OK	19712	2026-09-24 03:06	30.78	OK
19713	2026-09-24 03:07	28.99	OK	19714	2026-09-24 03:08	30.97	OK
19715	2026-09-24 03:09	29.88	OK	19716	2026-09-24 03:10	28.65	OK
19717	2026-09-24 03:11	30.45	OK	19718	2026-09-24 03:12	29.56	OK
19719	2026-09-24 03:13	31.08	OK	19720	2026-09-24 03:14	31.28	OK
19721	2026-09-24 03:15	30.95	OK	19722	2026-09-24 03:16	30.76	OK
19723	2026-09-24 03:17	30.07	OK	19724	2026-09-24 03:18	30.36	OK
19725	2026-09-24 03:19	29.55	OK	19726	2026-09-24 03:20	30.91	OK
19727	2026-09-24 03:21	29.68	OK	19728	2026-09-24 03:22	28.86	OK
19729	2026-09-24 03:23	31.08	OK	19730	2026-09-24 03:24	31.08	OK
19731	2026-09-24 03:25	30.46	OK	19732	2026-09-24 03:26	30.89	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19733	2026-09-24 03:27	30.17	OK	19734	2026-09-24 03:28	29.41	OK
19735	2026-09-24 03:29	30.97	OK	19736	2026-09-24 03:30	30.46	OK
19737	2026-09-24 03:31	30.93	OK	19738	2026-09-24 03:32	29.61	OK
19739	2026-09-24 03:33	29.65	OK	19740	2026-09-24 03:34	29.17	OK
19741	2026-09-24 03:35	30.34	OK	19742	2026-09-24 03:36	31.13	OK
19743	2026-09-24 03:37	30.08	OK	19744	2026-09-24 03:38	30.80	OK
19745	2026-09-24 03:39	29.61	OK	19746	2026-09-24 03:40	29.09	OK
19747	2026-09-24 03:41	28.15	OK	19748	2026-09-24 03:42	30.64	OK
19749	2026-09-24 03:43	29.77	OK	19750	2026-09-24 03:44	30.29	OK
19751	2026-09-24 03:45	30.67	OK	19752	2026-09-24 03:46	29.68	OK
19753	2026-09-24 03:47	29.29	OK	19754	2026-09-24 03:48	29.48	OK
19755	2026-09-24 03:49	30.37	OK	19756	2026-09-24 03:50	29.87	OK
19757	2026-09-24 03:51	28.18	OK	19758	2026-09-24 03:52	29.30	OK
19759	2026-09-24 03:53	27.99	OK	19760	2026-09-24 03:54	30.54	OK
19761	2026-09-24 03:55	29.73	OK	19762	2026-09-24 03:56	30.12	OK
19763	2026-09-24 03:57	30.36	OK	19764	2026-09-24 03:58	30.06	OK
19765	2026-09-24 03:59	30.39	OK	19766	2026-09-24 04:00	31.30	OK
19767	2026-09-24 04:01	29.86	OK	19768	2026-09-24 04:02	30.49	OK
19769	2026-09-24 04:03	29.54	OK	19770	2026-09-24 04:04	30.04	OK
19771	2026-09-24 04:05	29.74	OK	19772	2026-09-24 04:06	29.66	OK
19773	2026-09-24 04:07	29.80	OK	19774	2026-09-24 04:08	30.22	OK
19775	2026-09-24 04:09	30.77	OK	19776	2026-09-24 04:10	31.01	OK
19777	2026-09-24 04:11	29.29	OK	19778	2026-09-24 04:12	30.55	OK
19779	2026-09-24 04:13	29.56	OK	19780	2026-09-24 04:14	30.21	OK
19781	2026-09-24 04:15	30.57	OK	19782	2026-09-24 04:16	28.90	OK
19783	2026-09-24 04:17	29.40	OK	19784	2026-09-24 04:18	29.52	OK
19785	2026-09-24 04:19	30.64	OK	19786	2026-09-24 04:20	29.61	OK
19787	2026-09-24 04:21	30.37	OK	19788	2026-09-24 04:22	29.09	OK
19789	2026-09-24 04:23	30.35	OK	19790	2026-09-24 04:24	30.52	OK
19791	2026-09-24 04:25	28.61	OK	19792	2026-09-24 04:26	29.32	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19793	2026-09-24 04:27	30.61	OK	19794	2026-09-24 04:28	30.39	OK
19795	2026-09-24 04:29	30.42	OK	19796	2026-09-24 04:30	30.42	OK
19797	2026-09-24 04:31	29.48	OK	19798	2026-09-24 04:32	30.96	OK
19799	2026-09-24 04:33	30.53	OK	19800	2026-09-24 04:34	28.93	OK
19801	2026-09-24 04:35	31.42	OK	19802	2026-09-24 04:36	28.97	OK
19803	2026-09-24 04:37	30.37	OK	19804	2026-09-24 04:38	28.94	OK
19805	2026-09-24 04:39	29.85	OK	19806	2026-09-24 04:40	29.44	OK
19807	2026-09-24 04:41	30.80	OK	19808	2026-09-24 04:42	29.41	OK
19809	2026-09-24 04:43	28.80	OK	19810	2026-09-24 04:44	30.75	OK
19811	2026-09-24 04:45	28.31	OK	19812	2026-09-24 04:46	29.48	OK
19813	2026-09-24 04:47	29.53	OK	19814	2026-09-24 04:48	30.90	OK
19815	2026-09-24 04:49	28.34	OK	19816	2026-09-24 04:50	29.03	OK
19817	2026-09-24 04:51	30.59	OK	19818	2026-09-24 04:52	30.18	OK
19819	2026-09-24 04:53	29.70	OK	19820	2026-09-24 04:54	30.59	OK
19821	2026-09-24 04:55	28.49	OK	19822	2026-09-24 04:56	29.55	OK
19823	2026-09-24 04:57	28.26	OK	19824	2026-09-24 04:58	28.69	OK
19825	2026-09-24 04:59	28.86	OK	19826	2026-09-24 05:00	30.06	OK
19827	2026-09-24 05:01	30.10	OK	19828	2026-09-24 05:02	28.55	OK
19829	2026-09-24 05:03	29.33	OK	19830	2026-09-24 05:04	29.81	OK
19831	2026-09-24 05:05	29.96	OK	19832	2026-09-24 05:06	29.49	OK
19833	2026-09-24 05:07	28.67	OK	19834	2026-09-24 05:08	29.55	OK
19835	2026-09-24 05:09	30.33	OK	19836	2026-09-24 05:10	29.28	OK
19837	2026-09-24 05:11	29.20	OK	19838	2026-09-24 05:12	28.48	OK
19839	2026-09-24 05:13	28.39	OK	19840	2026-09-24 05:14	29.50	OK
19841	2026-09-24 05:15	29.14	OK	19842	2026-09-24 05:16	29.83	OK
19843	2026-09-24 05:17	28.34	OK	19844	2026-09-24 05:18	27.57	OK
19845	2026-09-24 05:19	27.78	OK	19846	2026-09-24 05:20	27.29	OK
19847	2026-09-24 05:21	29.18	OK	19848	2026-09-24 05:22	29.53	OK
19849	2026-09-24 05:23	29.45	OK	19850	2026-09-24 05:24	29.56	OK
19851	2026-09-24 05:25	30.04	OK	19852	2026-09-24 05:26	28.44	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19853	2026-09-24 05:27	29.67	OK	19854	2026-09-24 05:28	29.30	OK
19855	2026-09-24 05:29	29.57	OK	19856	2026-09-24 05:30	28.08	OK
19857	2026-09-24 05:31	31.10	OK	19858	2026-09-24 05:32	28.95	OK
19859	2026-09-24 05:33	29.32	OK	19860	2026-09-24 05:34	28.08	OK
19861	2026-09-24 05:35	29.24	OK	19862	2026-09-24 05:36	27.68	OK
19863	2026-09-24 05:37	30.37	OK	19864	2026-09-24 05:38	29.91	OK
19865	2026-09-24 05:39	29.25	OK	19866	2026-09-24 05:40	28.28	OK
19867	2026-09-24 05:41	28.06	OK	19868	2026-09-24 05:42	29.44	OK
19869	2026-09-24 05:43	28.38	OK	19870	2026-09-24 05:44	29.87	OK
19871	2026-09-24 05:45	29.60	OK	19872	2026-09-24 05:46	29.33	OK
19873	2026-09-24 05:47	28.99	OK	19874	2026-09-24 05:48	29.01	OK
19875	2026-09-24 05:49	29.02	OK	19876	2026-09-24 05:50	28.82	OK
19877	2026-09-24 05:51	27.88	OK	19878	2026-09-24 05:52	27.90	OK
19879	2026-09-24 05:53	28.61	OK	19880	2026-09-24 05:54	28.40	OK
19881	2026-09-24 05:55	29.29	OK	19882	2026-09-24 05:56	29.71	OK
19883	2026-09-24 05:57	29.06	OK	19884	2026-09-24 05:58	28.58	OK
19885	2026-09-24 05:59	28.22	OK	19886	2026-09-24 06:00	29.99	OK
19887	2026-09-24 06:01	28.03	OK	19888	2026-09-24 06:02	28.41	OK
19889	2026-09-24 06:03	28.31	OK	19890	2026-09-24 06:04	29.01	OK
19891	2026-09-24 06:05	30.07	OK	19892	2026-09-24 06:06	29.01	OK
19893	2026-09-24 06:07	28.03	OK	19894	2026-09-24 06:08	28.75	OK
19895	2026-09-24 06:09	29.22	OK	19896	2026-09-24 06:10	30.05	OK
19897	2026-09-24 06:11	28.56	OK	19898	2026-09-24 06:12	28.76	OK
19899	2026-09-24 06:13	28.88	OK	19900	2026-09-24 06:14	28.49	OK
19901	2026-09-24 06:15	28.44	OK	19902	2026-09-24 06:16	29.37	OK
19903	2026-09-24 06:17	28.41	OK	19904	2026-09-24 06:18	28.50	OK
19905	2026-09-24 06:19	27.91	OK	19906	2026-09-24 06:20	30.49	OK
19907	2026-09-24 06:21	30.04	OK	19908	2026-09-24 06:22	27.39	OK
19909	2026-09-24 06:23	28.42	OK	19910	2026-09-24 06:24	29.23	OK
19911	2026-09-24 06:25	29.38	OK	19912	2026-09-24 06:26	28.06	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19913	2026-09-24 06:27	29.09	OK	19914	2026-09-24 06:28	27.99	OK
19915	2026-09-24 06:29	27.83	OK	19916	2026-09-24 06:30	28.35	OK
19917	2026-09-24 06:31	29.18	OK	19918	2026-09-24 06:32	29.04	OK
19919	2026-09-24 06:33	28.24	OK	19920	2026-09-24 06:34	27.89	OK
19921	2026-09-24 06:35	28.63	OK	19922	2026-09-24 06:36	28.90	OK
19923	2026-09-24 06:37	29.15	OK	19924	2026-09-24 06:38	29.55	OK
19925	2026-09-24 06:39	28.88	OK	19926	2026-09-24 06:40	29.55	OK
19927	2026-09-24 06:41	27.56	OK	19928	2026-09-24 06:42	28.59	OK
19929	2026-09-24 06:43	27.89	OK	19930	2026-09-24 06:44	28.92	OK
19931	2026-09-24 06:45	29.02	OK	19932	2026-09-24 06:46	28.39	OK
19933	2026-09-24 06:47	27.21	OK	19934	2026-09-24 06:48	28.57	OK
19935	2026-09-24 06:49	28.37	OK	19936	2026-09-24 06:50	28.07	OK
19937	2026-09-24 06:51	29.56	OK	19938	2026-09-24 06:52	27.73	OK
19939	2026-09-24 06:53	28.40	OK	19940	2026-09-24 06:54	28.40	OK
19941	2026-09-24 06:55	28.59	OK	19942	2026-09-24 06:56	27.88	OK
19943	2026-09-24 06:57	27.48	OK	19944	2026-09-24 06:58	27.55	OK
19945	2026-09-24 06:59	28.52	OK	19946	2026-09-24 07:00	27.78	OK
19947	2026-09-24 07:01	28.53	OK	19948	2026-09-24 07:02	27.73	OK
19949	2026-09-24 07:03	27.91	OK	19950	2026-09-24 07:04	29.14	OK
19951	2026-09-24 07:05	27.60	OK	19952	2026-09-24 07:06	27.65	OK
19953	2026-09-24 07:07	29.10	OK	19954	2026-09-24 07:08	28.23	OK
19955	2026-09-24 07:09	27.04	OK	19956	2026-09-24 07:10	29.03	OK
19957	2026-09-24 07:11	28.51	OK	19958	2026-09-24 07:12	28.25	OK
19959	2026-09-24 07:13	27.85	OK	19960	2026-09-24 07:14	28.93	OK
19961	2026-09-24 07:15	28.65	OK	19962	2026-09-24 07:16	27.40	OK
19963	2026-09-24 07:17	27.66	OK	19964	2026-09-24 07:18	26.52	OK
19965	2026-09-24 07:19	27.17	OK	19966	2026-09-24 07:20	27.47	OK
19967	2026-09-24 07:21	28.53	OK	19968	2026-09-24 07:22	27.62	OK
19969	2026-09-24 07:23	28.83	OK	19970	2026-09-24 07:24	25.99	OK
19971	2026-09-24 07:25	28.21	OK	19972	2026-09-24 07:26	27.68	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
19973	2026-09-24 07:27	27.55	OK	19974	2026-09-24 07:28	26.50	OK
19975	2026-09-24 07:29	27.44	OK	19976	2026-09-24 07:30	27.42	OK
19977	2026-09-24 07:31	29.18	OK	19978	2026-09-24 07:32	29.21	OK
19979	2026-09-24 07:33	26.72	OK	19980	2026-09-24 07:34	28.46	OK
19981	2026-09-24 07:35	28.05	OK	19982	2026-09-24 07:36	27.32	OK
19983	2026-09-24 07:37	27.23	OK	19984	2026-09-24 07:38	28.04	OK
19985	2026-09-24 07:39	28.95	OK	19986	2026-09-24 07:40	27.44	OK
19987	2026-09-24 07:41	29.00	OK	19988	2026-09-24 07:42	28.41	OK
19989	2026-09-24 07:43	28.84	OK	19990	2026-09-24 07:44	27.60	OK
19991	2026-09-24 07:45	28.09	OK	19992	2026-09-24 07:46	26.95	OK
19993	2026-09-24 07:47	27.53	OK	19994	2026-09-24 07:48	26.49	OK
19995	2026-09-24 07:49	26.08	OK	19996	2026-09-24 07:50	27.91	OK
19997	2026-09-24 07:51	28.53	OK	19998	2026-09-24 07:52	27.39	OK
19999	2026-09-24 07:53	27.35	OK	20000	2026-09-24 07:54	28.36	OK
20001	2026-09-24 07:55	27.02	OK	20002	2026-09-24 07:56	26.52	OK
20003	2026-09-24 07:57	29.11	OK	20004	2026-09-24 07:58	27.90	OK
20005	2026-09-24 07:59	28.26	OK	20006	2026-09-24 08:00	27.41	OK
20007	2026-09-24 08:01	26.34	OK	20008	2026-09-24 08:02	28.44	OK
20009	2026-09-24 08:03	27.46	OK	20010	2026-09-24 08:04	26.82	OK
20011	2026-09-24 08:05	26.84	OK	20012	2026-09-24 08:06	27.83	OK
20013	2026-09-24 08:07	27.87	OK	20014	2026-09-24 08:08	28.07	OK
20015	2026-09-24 08:09	26.79	OK	20016	2026-09-24 08:10	26.90	OK
20017	2026-09-24 08:11	27.71	OK	20018	2026-09-24 08:12	28.57	OK
20019	2026-09-24 08:13	27.12	OK	20020	2026-09-24 08:14	27.95	OK
20021	2026-09-24 08:15	27.07	OK	20022	2026-09-24 08:16	27.02	OK
20023	2026-09-24 08:17	27.81	OK	20024	2026-09-24 08:18	27.15	OK
20025	2026-09-24 08:19	27.44	OK	20026	2026-09-24 08:20	27.17	OK
20027	2026-09-24 08:21	26.05	OK	20028	2026-09-24 08:22	28.45	OK
20029	2026-09-24 08:23	27.96	OK	20030	2026-09-24 08:24	27.57	OK
20031	2026-09-24 08:25	27.77	OK	20032	2026-09-24 08:26	27.34	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
20033	2026-09-24 08:27	28.89	OK	20034	2026-09-24 08:28	27.63	OK
20035	2026-09-24 08:29	27.87	OK	20036	2026-09-24 08:30	27.26	OK
20037	2026-09-24 08:31	26.65	OK	20038	2026-09-24 08:32	28.42	OK
20039	2026-09-24 08:33	26.64	OK	20040	2026-09-24 08:34	27.81	OK
20041	2026-09-24 08:35	26.87	OK	20042	2026-09-24 08:36	26.79	OK
20043	2026-09-24 08:37	27.10	OK	20044	2026-09-24 08:38	27.12	OK
20045	2026-09-24 08:39	28.05	OK	20046	2026-09-24 08:40	26.30	OK
20047	2026-09-24 08:41	27.43	OK	20048	2026-09-24 08:42	28.68	OK
20049	2026-09-24 08:43	27.45	OK	20050	2026-09-24 08:44	27.51	OK
20051	2026-09-24 08:45	28.33	OK	20052	2026-09-24 08:46	27.22	OK
20053	2026-09-24 08:47	27.17	OK	20054	2026-09-24 08:48	27.56	OK
20055	2026-09-24 08:49	28.70	OK	20056	2026-09-24 08:50	27.43	OK
20057	2026-09-24 08:51	25.55	OK	20058	2026-09-24 08:52	26.21	OK
20059	2026-09-24 08:53	27.44	OK	20060	2026-09-24 08:54	26.01	OK
20061	2026-09-24 08:55	26.87	OK	20062	2026-09-24 08:56	26.15	OK
20063	2026-09-24 08:57	27.17	OK	20064	2026-09-24 08:58	27.33	OK
20065	2026-09-24 08:59	27.30	OK	20066	2026-09-24 09:00	26.91	OK
20067	2026-09-24 09:01	28.13	OK	20068	2026-09-24 09:02	27.37	OK
20069	2026-09-24 09:03	27.41	OK	20070	2026-09-24 09:04	27.09	OK
20071	2026-09-24 09:05	27.00	OK	20072	2026-09-24 09:06	27.71	OK
20073	2026-09-24 09:07	26.62	OK	20074	2026-09-24 09:08	25.98	OK
20075	2026-09-24 09:09	27.28	OK	20076	2026-09-24 09:10	25.45	OK
20077	2026-09-24 09:11	27.06	OK	20078	2026-09-24 09:12	26.49	OK
20079	2026-09-24 09:13	27.02	OK	20080	2026-09-24 09:14	27.26	OK
20081	2026-09-24 09:15	26.67	OK	20082	2026-09-24 09:16	27.44	OK
20083	2026-09-24 09:17	26.86	OK	20084	2026-09-24 09:18	26.28	OK
20085	2026-09-24 09:19	27.13	OK	20086	2026-09-24 09:20	25.84	OK
20087	2026-09-24 09:21	27.53	OK	20088	2026-09-24 09:22	27.45	OK
20089	2026-09-24 09:23	26.32	OK	20090	2026-09-24 09:24	25.49	OK
20091	2026-09-24 09:25	26.93	OK	20092	2026-09-24 09:26	26.46	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
20093	2026-09-24 09:27	27.52	OK	20094	2026-09-24 09:28	26.57	OK
20095	2026-09-24 09:29	26.86	OK	20096	2026-09-24 09:30	28.32	OK
20097	2026-09-24 09:31	25.91	OK	20098	2026-09-24 09:32	28.63	OK
20099	2026-09-24 09:33	25.34	OK	20100	2026-09-24 09:34	25.42	OK
20101	2026-09-24 09:35	26.33	OK	20102	2026-09-24 09:36	26.32	OK
20103	2026-09-24 09:37	25.22	OK	20104	2026-09-24 09:38	26.52	OK
20105	2026-09-24 09:39	26.29	OK	20106	2026-09-24 09:40	28.12	OK
20107	2026-09-24 09:41	25.31	OK	20108	2026-09-24 09:42	27.35	OK
20109	2026-09-24 09:43	27.40	OK	20110	2026-09-24 09:44	26.08	OK
20111	2026-09-24 09:45	27.16	OK	20112	2026-09-24 09:46	25.36	OK
20113	2026-09-24 09:47	26.36	OK	20114	2026-09-24 09:48	27.79	OK
20115	2026-09-24 09:49	26.78	OK	20116	2026-09-24 09:50	26.56	OK
20117	2026-09-24 09:51	26.81	OK	20118	2026-09-24 09:52	26.25	OK
20119	2026-09-24 09:53	26.67	OK	20120	2026-09-24 09:54	24.56	OK
20121	2026-09-24 09:55	26.28	OK	20122	2026-09-24 09:56	27.18	OK
20123	2026-09-24 09:57	26.03	OK	20124	2026-09-24 09:58	25.83	OK
20125	2026-09-24 09:59	27.18	OK	20126	2026-09-24 10:00	26.84	OK
20127	2026-09-24 10:01	25.96	OK	20128	2026-09-24 10:02	27.20	OK
20129	2026-09-24 10:03	27.56	OK	20130	2026-09-24 10:04	26.73	OK
20131	2026-09-24 10:05	26.33	OK	20132	2026-09-24 10:06	25.82	OK
20133	2026-09-24 10:07	27.19	OK	20134	2026-09-24 10:08	26.48	OK
20135	2026-09-24 10:09	25.93	OK	20136	2026-09-24 10:10	26.92	OK
20137	2026-09-24 10:11	27.05	OK	20138	2026-09-24 10:12	25.73	OK
20139	2026-09-24 10:13	25.36	OK	20140	2026-09-24 10:14	26.68	OK
20141	2026-09-24 10:15	25.28	OK	20142	2026-09-24 10:16	27.62	OK
20143	2026-09-24 10:17	25.01	OK	20144	2026-09-24 10:18	27.19	OK
20145	2026-09-24 10:19	26.13	OK	20146	2026-09-24 10:20	25.67	OK
20147	2026-09-24 10:21	27.28	OK	20148	2026-09-24 10:22	27.22	OK
20149	2026-09-24 10:23	26.62	OK	20150	2026-09-24 10:24	26.80	OK
20151	2026-09-24 10:25	26.53	OK	20152	2026-09-24 10:26	27.11	OK

INDUSTRIAL ASSET TELEMETRY REPORT

Report ID: REP-815738

79% HEALTH (GOOD)

Cooling Tower Fan Motor • Utility Yard

Timeframe: 2026-09-10 10:35 to 2026-09-24 10:35 (UTC)

#	Time (UTC)	Value (°C)	Status	#	Time (UTC)	Value (°C)	Status
20153	2026-09-24 10:27	27.83	OK	20154	2026-09-24 10:28	26.07	OK
20155	2026-09-24 10:29	27.40	OK	20156	2026-09-24 10:30	24.90	OK
20157	2026-09-24 10:31	26.06	OK	20158	2026-09-24 10:32	27.94	OK
20159	2026-09-24 10:33	26.81	OK	20160	2026-09-24 10:34	26.06	OK
20161	2026-09-24 10:35	26.33	OK				