


FIGURE L-28. FILTER SCREEN

NOTES:

- (1) MATERIAL IS 302 OR 304 STAINLESS
(FULL OR HALF HARD)
- (2) 1.530 DIA. AREA IS PERFORATED IN
HOLE PATTERN SHOWN




HOLE PATTERN

0.003 $\begin{matrix} + 0.002 \\ - 0.002 \end{matrix}$

0.004 TYP.

0.004 DIA. TYP.
 $\begin{matrix} + 0.002 \\ - 0.000 \end{matrix}$



TOLERANCES

2 PLCS	3 PLCS	FRAC.	ANGLE
± 0.010	± 0.003	$\pm 1/64$	$\pm 15'$

ALL DIMENSIONS ARE INCHES