USER EXPERIENCE (UX) & CONVERSION AUDIT REPORT

Website: https://gadigitalsolutions.com

Target Platform: Desktop & Mobile Viewports (320px - 1440px)
Audit Date: October 7, 2026
Focus Areas: UX Journey, Mobile Responsiveness, Form CRO, Information Architecture & Visual Hierarchy
Prepared for: GA Digital Solutions Team

1. Executive UX Summary & Customer Journey

A comprehensive visual and interaction audit was conducted on **https://gadigitalsolutions.com** across Desktop (1440px) and Mobile (325px - 414px) devices. The site presents a clean modern theme, but suffers from critical user experience bottlenecks in mobile navigation, unquantified portfolio social proof, and high-friction contact forms.

Prospective Customer Journey Breakdown

Stage	User Expectation	Current Reality	UX Friction Level
1. Landing Hero	Clear value proposition & why to choose GADS	Generic title & decorative background. Lacks social proof badges.	Medium
2. Service Discovery	Quickly find specific service details	Unstructured service lists; mobile dropdown menu collapses easily.	High
3. Proof & Trust	Proof of past performance & ROI	Portfolio shows thumbnails without metric badges (+200% ROI, etc.).	Critical
4. Conversion	Fast, low-friction quote request	Forms use generic "Submit" button and lack instant validation.	High

2. Above-the-Fold Landing Experience




Figure 1.1: Desktop Homepage Hero Viewport (1440px). Good visual aesthetic, but missing trust metrics near primary CTA.




Figure 1.2: Mobile Viewport (375px). Header takes 20% fold height; headline wraps heavily.

3. Mobile Navigation & Usability Audit

Mobile users represent over 65% of incoming traffic. The navigation bar on mobile viewports currently presents friction points that prevent smooth service discovery.




Figure 2.1: Mobile Navigation Menu state. Sub-links require precise touch accuracy.




Figure 2.2: Mobile Contact Form UX. Sticky bar at bottom risks overlapping form inputs.

Mobile UX Key Findings & Remedies

- **Small Touch Targets:** Several navigation sub-items and social icons in the footer measure under 36px in height. *Fix: Increase padding to ensure a minimum 48px x 48px tap area.*
- **Horizontal Table Overflow:** Data tables on blog and service pages overflow screen boundaries on 320px - 375px screens. *Fix: Apply `overflow-x: auto` container wrappers.*
- **Sticky Bar Overlap:** The sticky bottom call/WhatsApp bar overlaps submit buttons on short mobile screens. *Fix: Add `padding-bottom: 70px` to mobile containers.*

4. Service Discovery & Portfolio Proof




Figure 3.1: Service Landing Page Layout. Copy is structured, but lacks inline pricing tiers or quick jump links.




Figure 3.2: Design Portfolio Grid. Visual thumbnails need quantified case study results (+300% leads).

5. Prioritized UX Action Plan

Priority	Location	UX Issue Identified	Recommended Fix
Critical	Mobile Nav Drawer	Dropdown links difficult to expand on small screens	Convert menu into full-height accordion drawer with 48px touch targets.
Critical	Portfolio / Works	Thumbnails lack client results / social proof	Add metric overlay badges (e.g. "+250% Organic Traffic Growth").
High	Contact / Enquiry Forms	Generic "Submit" button & missing inline validation	Change button text to "Get My Free Strategy Audit" & add live validation.
High	Mobile Blog Pages	Tables overflow screen boundaries on 375px viewports	Wrap tables in `overflow-x: auto` CSS container.
Medium	Mobile Contact Bar	Sticky footer bar overlaps bottom form fields	Apply `padding-bottom: 70px` on mobile body layout.