



Pore pressure at the injector -- the overshoot past sigma_{mainit} survives the fix



Effective normal stress at the injector



Permeability at the injector: pinned at k_{pmax} throughout, in both runs

