
Mantle: Strata Float v3, rear plate, wiring and earth, rating (round 48; no light since 2026-11-10)


mm. A proposal until the owner signs it. The audit's Strata items (ENGINEERING-AUDIT.md, r46-owner-notes): no rear panel, no wiring or earth drawing, no rating label; an 8 mm strip in a 5 mm slot with 2 mm corners; a 25 W supply. No light since 2026-11-10.

A Rear plate, seen from behind (2:1 on the sheet), 2 mm lead-free brass, brushed; legends and rating engraved and filled black




Two M3 × 10 button screws into brass inserts bonded in the base's edge (4.6, 10 deep). Holes from the CAD (mantle_strata_v3.REAR_HW); rating 2 mm caps, 3 lines, between the screws. No compliance mark until tested; the supplies carry their own.

B Section on the 4PDT (1:1): the plate under the overhang



C Signal, earth and power (one channel drawn; the other the same)



Rules: one earth point (the post), no loops; the S2's 18 V and the motor's lead never share a ground with signal, and run along the base's far side from the arm's lead (40 or more apart, crossing at right angles); shielded leads, shields earthed at the S2 end only. The DC jack is insulated from the plate (the S2's 0 V reaches the star only through its GND terminal).

D No light (2026-11-10)

The owner: "Forget the lights on mantle." Mantle has no light of any kind: no strip, channel or groove, no 24 V adapter, no switch or inlet for it on the plate, no light wiring. The base is the signed solid Smoke 2074; the deck's underside is bead-blasted satin as its edge (the day win from the light proposals).
The light's fit as drawn until now is in this file's history (before 2026-11-10).

First-sample checks: hum and noise at the out in both switch positions, into an outside phono stage, with the motor running (A-weighted, against the S2's own figure); the 2M's frequency response in bypass, into 47k, against the stage position (no droop above 10 kHz); continuity and isolation of the DC jack from the plate.