

STATEMENT OF WORK
Paving Contractor
Asphalt Patch R&R on Auto Tour Route South at Rocky Mountain Arsenal NWR
NAICS: 237310 - Highway Street and Bridge Const.

1. General:

This project aims to repair all asphalt surfaces within the identified project area on the Auto Tour Route South east of the Lower Derby Lake parking lot.

This Statement of Work (SOW) describes the general performance of the project and does not attempt to show the exact construction of the work in complete detail. The Contractor is responsible for providing high-quality completed work that maintains the performance intent established by this document.

Overview – The U.S. Fish and Wildlife Service (FWS) needs the Contractor to complete a concrete asphalt patch remove and replace (R&R) on approximately 170 feet of the south lane on the Auto Tour Route South (FWS 012AZ) (also known as “E. 64th Avenue”) directly east of the Lower Derby Lake parking lot. This patch is approximately 170 feet long and 11 feet wide (the width of the south lane of this two-lane roadway).

Specifically, the contractor will reconstruct the roadway in areas where the road was damaged (approximately 208 square yards of surface area):

- The contractor will excavate to a depth of 6” in failed areas
- The contractor will compact and prep subgrade
- The contractor will apply tack coat
- The contractor will pave 6” of compacted full-depth asphalt
- The contractor will dispose of excess materials

The USFWS will be responsible for traffic control and signage on this project.

2. Place of Performance and Period of Performance

Rocky Mountain Arsenal NWR, 6550 Gateway Road, Commerce City, CO 80022

Auto Tour Route South (FWS 012AZ) (also known as “E. 64th Avenue”) directly east of the Lower Derby Lake parking lot. This patch is approximately 170 feet long and 11 feet wide (the width of the south lane of this two-lane roadway).

Period of Performance: Work must not begin until the official Notice to Proceed (NTP) is

received from the Contracting Officer.

Performance Start: November 1, 2026

Performance End: March 31, 2027

Normal duty hours Monday thru Friday 7:00 a.m. - 4:30 p.m. In the event of emergencies, Contractor shall provide contact information.

Non-duty hours include week nights, weekends, and Government holidays (New Year's Day, Martin Luther King JR.s's Birthday, Memorial Day, Independence Day, Labor Day, Columbus Day, Veteran's Day, Thanksgiving Day, Christmas Day).


3. Scope

ROCKY MOUNTAIN ARSENAL NATIONAL WILDLIFE REFUGE

ROUTE 012AZ: Auto Tour Route South

From Entrance A Rd (Route 010AZ)
To Auto Tour Route One-Way (Route 012BZ)

RPI Number	Collect Method	Inspection Date	Surface	Func Class	Tier	Length (mi)
10024546	Automated	9/13/2020	Asphalt	1	1	2.5



Project Description / Scope of Work

RT#012AZ, AUTO TOUR ROUTE SOUTH

Asphalt patch remove and replace (R&R) approximately 170 feet of the south lane on the Auto Tour Route South (FWS 012AZ) directly east of the Lower Derby Lake parking lot.

Reference specifications within SECTION 321216 - ASPHALT PAVING attached.

It will not be necessary to close the road for this repair and the repair area is small. Contractor is responsible for coordinating traffic control with the USFWS to ensure contractor and public safety during operations.

See Photos and Spec sheet (attachment 1) for additional information/requirements

5. Government-Furnished Equipment (GFE) / Government-Furnished Information (GFI)

NA

6. Evaluation and Acceptance

The contractor will be evaluated as detailed herein. Government acceptance is contingent upon: All of the items listed with the State of Work are completed and are operational following state and federal codes.

7. Quality Control/Quality Assurance:

QC will be maintained according to industry standards and made available to the agency with the contractor's proposal.

8. Technical Coordinator:

The U.S. Fish and Wildlife Service Project Lead (PL) for this requirement is:

David Lucas

Refuge Manager

Rocky Mountain Arsenal NWR, 6550 Gateway Road, Commerce City, CO 80022

303.289.0232

david_c_lucas@fws.gov

The U.S. Fish and Wildlife Service Contracting Officer Representative (COR) for this requirement is:

Tom Ronning

Refuge Operations Specialist

Rocky Mountain Arsenal NWR, 6550 Gateway Road, Commerce City, CO 80022

303.289.0232

tom_ronning@fws.gov

Photographs:



Figure 1. Auto Tour Route South looking east. Project bounds are south lane as identified with yellow spray paint.



Figure 2. Sample of "alligator" cracking and subsistence of the road within the project area.



Figure 3. Auto Tour Route South looking west. Project bounds are south lane as identified with yellow spray paint.