



4/29/25 10:40 NFLECK C:\USERS\NFLECK\ONE DRIVE - DO\DESKTOP\NPS PROJECTS\NPS DRAWINGS\PMIS\BUOY DRAWINGS\PMIS\BUOY ANCHOR CROSS SECTION 2018 LIDAR SURFACE DATA.DWG XREFS:



Depths for seven buoys surveyed at Mean Sea Level (MSL), adjusted for tidal variations using NOAA Tides & Currents data from **Observed Water Levels at 8776139, S. Bird Island TX** and a rare 3' storm surge. Tidal datums: MHHW (+1.25 ft), MLLW (-0.66 ft) relative to (0 ft) MSL. All depths in feet, rounded to two decimal places.

Buoy Depth Table Adjusted for Tidal Variations and Storm Surge

Buoy	Latitude	Longitude	Date	Time	Surveyed Depth	MLLW	MSL	MHHW	MSL + 3' Surge
1	27°28'25.5810"N	97°18'46.7202"W	10/17/2024	15:49:48	4	2.13	2.75	5.37	5.75
2	27°28'29.8941"N	97°18'59.4414"W	10/17/2024	15:51:48	4.5	2.63	3.25	5.87	6.25
3	27°28'08.4927"N	97°19'11.1323"W	10/17/2024	16:06:10	4.5	2.63	3.25	5.87	6.25
4	27°27'47.4049"N	97°19'21.9064"W	10/17/2024	15:57:07	5.5	3.63	4.25	6.87	7.25
5	27°27'39.3744"N	97°19'08.0406"W	10/17/2024	15:03:54	2.5	0.63	1.25	3.87	4.25
6	27°28'27.7018"N	97°18'52.8081"W	4/15/2025	16:30:22	4	3.91	4.57	7.19	7.57



DESIGNED:
X
FLECK N.
TECH. REVIEW:
X
DATE:
25APR2025

SUB SHEET NO.
C2

TITLE OF SHEET
BIRD ISLAND BASIN
BUOY PROFILE
PADRE ISLAND NATIONAL SEASHORE
PAIS

DRAWING NO.
X
PMIS/PKG NO.
X
SHEET
2 OF 2