

Annual Asbestos Surveillance Report

Eau Claire Federal Courthouse
500 S. Barstow St. Eau Claire, WI
WI0016ZZ
September 27th 2024

The Eau Claire Federal Courthouse has asbestos in interstitial spaces between the basement and the first floor, presumed remnants of ACM in roofing materials, and in piping insulation. The purpose of this annual surveillance is to ascertain if any of the encapsulated areas, ACM materials, or PACM materials have been damaged or degraded and to advise corrective actions.

Observations


Location	Material	Description/Location of Damage	Recommended Corrective Action
Roof - Upper	Remnant Asphalt Roofing Materials	Roof is in good condition. Concealed materials were unable to be viewed	No Corrective Actions Required
Roof - Lower	Remnant Asphalt Roofing Materials	Roof is in good condition. Concealed materials were unable to be viewed	No Corrective Actions Required
Roof - Dock	Remnant Asphalt Roofing Materials	Roof is in good condition. Concealed materials were unable to be viewed	No Corrective Actions Required
Basement – Room 2A	Aircell Thermal System Insulation	Fully Encapsulated in good condition.	No Corrective Actions Required
Basement – East Side (No Room Number)	Aircell Thermal System Insulation	Fully Encapsulated in good condition.	No Corrective Actions Required
Basement – Room B4	Aircell Thermal System Insulation	Fully Encapsulated in good condition.	No Corrective Actions Required
Basement – Room B9	Abated	Abated	No Corrective Actions Required

Photographs of various ACM locations throughout the buildings included in Appendix A

A copy of the Asbestos Inspector's Certificate and License included in Appendix B

For any questions or concerns please call: 228-357-0300

Or email: Jonathan.Nissen@cmimgmt.com


Jonathan Nissen
Facility Manager
Licensed Asbestos Inspector

Appendix A

Photographs

Photographic Log


Site Name: Eau Claire Federal Courthouse	Site Location: 500 S. Barstow St. Eau Claire, WI
Photograph ID: 1 Location: Upper Roof Survey Date: 09/17/2024 Comments: Roof was recently replaced, awaiting documentation to confirm no asbestos. As PACM, Roof is in good condition.	
Photograph ID: 2 Location: Lower Roof Survey Date: 09/17/2024 Comments: Roof was recently replaced, awaiting documentation to confirm no asbestos. As PACM, Roof is in good condition.	

Site Name: Eau Claire Federal Courthouse	Site Location: 500 S. Barstow St. Eau Claire, WI
Photograph ID: 3 Location: Loading Dock Roof Survey Date: 09/17/2024 Comments: Roof was recently replaced, awaiting documentation to confirm no asbestos. As PACM, Roof is in good condition.	
Photograph ID: 4 Location: Basement East Side Survey Date: 09/17/2024 Comments: Aircell TSI encapsulated. Structurally intact, no damage.	

Site Name: Eau Claire Federal Courthouse	Site Location: 500 S. Barstow St. Eau Claire, WI	
Photograph ID: 5 Location: Basement East Side Survey Date: 09/17/2024 Comments: Aircell TSI encapsulated. Structurally intact, no damage.		 A photograph showing a basement wall made of light-colored concrete blocks. A white PVC pipe runs vertically along the wall. A small, cylindrical, metallic-looking object (the Aircell TSI) is attached to the wall, partially covered by a white, irregularly shaped encapsulation material. A white electrical box is mounted on the wall below the pipe. The lighting is dim, and the wall shows some signs of wear and discoloration.
Photograph ID: 6 Location: Basement East Side Survey Date: 09/17/2024 Comments: Aircell TSI encapsulated. Structurally intact, no damage.		 A photograph showing a basement wall made of light-colored concrete blocks. A white PVC pipe runs horizontally along the wall. A small, cylindrical, metallic-looking object (the Aircell TSI) is attached to the wall, partially covered by a white, irregularly shaped encapsulation material. The lighting is dim, and the wall shows some signs of wear and discoloration.

Site Name: Eau Claire Federal Courthouse	Site Location: 500 S. Barstow St. Eau Claire, WI		
Photograph ID: 7 Location: Basement Room B9 Survey Date: 09/17/2024 Comments: Aircell TSI and Mudded Fittings Removed from piping.			
Photograph ID: 8 Location: Basement Room B9 Survey Date: 09/17/2024 Comments: Aircell TSI and Mudded Fittings Removed from piping.			

Site Name: Eau Claire Federal Courthouse	Site Location: 500 S. Barstow St. Eau Claire, WI	
Photograph ID: 9 Location: Basement Room B9 Survey Date: 09/17/2024 Comments: Aircell TSI and Mudded Fittings Removed from piping.		
Photograph ID: 10 Location: Basement Room B4 Survey Date: 09/17/2024 Comments: Aircell TSI encapsulated. Structurally intact, no damage.		

Site Name: Eau Claire Federal Courthouse	Site Location: 500 S. Barstow St. Eau Claire, WI	
Photograph ID: 11 Location: Basement Room B4 Survey Date: 09/17/2024 Comments: Aircell TSI encapsulated. Structurally intact, no damage.		
Photograph ID: 12 Location: Basement Room 2A Survey Date: 09/17/2024 Comments: Aircell TSI encapsulated. Structurally intact, no damage.		

Appendix B

Asbestos Inspector Certificate and License

(Jonathan Nissen)

Certificate No: 5LM06122409II

Expiration Date: June 12, 2025

This is to certify that
Jonathan P. Nissen
has attended and successfully completed an
ASBESTOS INSPECTOR
INITIAL TRAINING COURSE

permitted by
the State of Minnesota under Minnesota Rules 4620.3702 to 4620.3722
and meets the requirements of
Section 206 of Title II of the Toxic Substances Control Act (TSCA)
conducted by


Lake States Environmental, Ltd.

in

White Bear Lake, MN on June 10-12, 2024

Examination Date: June 12, 2024

Lake States Environmental, Ltd.
P. O. Box 645, Rice Lake, WI 54868
www.lakestates.com
(800) 254-9811



Training Instructor



Jonathan P Nissen

Director, Env. Health Div.



DEPARTMENT
OF HEALTH

**ASBESTOS
INSPECTOR**

Certified by:

State of Minnesota
Department of Health

Expires: 06/12/2025

Jonathan P Nissen
3166 Countryside Ave #A
Woodbury, MN 55129


No. AI15777

Issued: 07/02/2024

Certificate No: 5LW07312410IR

Issue Date: July 31, 2024

Expiration Date: July 31, 2025



This diploma is awarded to

Jonathan P. Nissen

For successfully completing and passing the examination for the

ASBESTOS INSPECTOR

REFRESHER TRAINING COURSE

*This training course complies with the requirements of TSCA Title II
and is accredited by the State of Wisconsin, Department of Health Services,
under chapter DHS 159, Wis. Admin. Code,
conducted by*

Lake States Environmental, Ltd.

Attended Remotely on July 31, 2024

Examination Date: July 31, 2024

Lake States Environmental, Ltd.

P. O. Box 645, Rice Lake, WI 54868

www.lakestates.com

(800) 254-9811

Grant Grassle - Training Instructor

Wisconsin Asbestos Inspector Provisional Certification

Once you submit your **individual** application for certification, you can work under provisional certification until your card is issued. Note: There is no provisional company certification.

To work under provisional certification, you must:

- Meet all requirements for certification,
- Apply for certification, and
- Keep a copy of your training diploma with you while doing regulated work. An electronic or printed copy is fine.

For additional background information, see our publication on [provisional certification for individuals, P-03614](#) (in English and Spanish) or [the official memo on asbestos provisional certification \(PDF\)](#) issued by the Department of Health Services.