UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Coles ROAA	**Date:**	20th September
Site Address:	54 Templar Rd, Erskine Park NSW 2759	**Site Contact:**	Alan Villa
		Phone:	0410 556 153
Customer PO #:		**Internal Job #:**	1349

Subject:

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Trave 590	A17A-11614	Line 4
Platformer	A17A-11614	Line 4

Equipment condition:

Service forming pick and place 9x8 Platformer tooling

Work Performed:

Wednesday 20th

- *Started to pull apart all the forming plates for the pick and place*
- *All the dampers needed to be removed and replaced*
- *All the forming plates were bent and we had to replace the lot.*





- *Replaced all the bushings in the forming plate*
- *Inspect the suction cups and all okay*
- *The diffuser were inspected which are damaged, this is caused by damage dampers and can be prevented.*
- *Cleaned all contamination from diffusers.*
- *The changeover troller needs some work as the back stoppers are bend and need to be welded.*

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

TECHNICIAN HOURS					
Marc Ashford	**Wednesday 20th**			**Date**	
Time	**Start**	**Finish**		**Start**	**Finish**
Travel To Site:	06:30	07:30			
Onsite:	07:30	15:30			
Travel From Site:	15:30	16:30			

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:		X _____	20th September
Technician:	Marc Ashford		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au