UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Coles	**Date:**	23/08/2022
Site Address:	72 Templar Road Erskine Park NSW	**Site Contact:**	Trent Cleminson
		Phone:	
Customer PO #:		**Internal Job #:**	3653

Subject:

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Bottom tool 11x9 DOT		

Equipment condition:

Work Performed:

Serviced bottom tool 11x9

- Disassembled bottom tool for inspection and replacing the service kits.
  Cleaned and washed the tool, it was dirty with grease and products.

- 1x side of tray lifter was welded and have sign of cracked.
  The other side was just being replaced by customer but it has no threaded insert insert for height adjustment. This issue has been informed to Mondini to avoid mistake on future order.

- 3x tray lifter stopper were damage, this is one of the cause of cracking tray lifter. Replaced the Teflon using customer spare

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

GENERAL SERVICE REPORT

- Replaced T-seal for bottom counter tool because they were worn out.
- Replaced 2x tray lifter shaft. The other 2 were just being replaced by customer, they have little worn out.

- Replaced 6x punches because they were broken, bent and dull. The height was adjusted between 36-26.5mm

- Replaced 3x broken vacuum gauge and its o-ring at the same time

- Inspected bellows are in good condition, replaced the o-rings

GENERAL SERVICE REPORT

- Replaced all o-rings for shafts

- 1x plastic for middle bar stopper was came out. Fixed and glued the plastic back into its place

- Replaced 6x springs for shaft
- Replaced new blue springs
- Condition of base plate after cleaning



- Pumped grease to all bushings.

Bottom tool was tested run in the next day without issue.

** end of report**

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

SPARE PARTS USED				
Part Number:	**Description:**	**Qty:**	**Chargeable?**	
			Yes ☐	No☐
			Yes☐	No☐
			Yes☐	No☐

STATUS		
Machine Tested?	Yes☐	No☐
Comments:		
Revisit Required?	Yes☐	No☐
Comments:		

RECOMMENDATIONS
Comments:

RECOMMENDED SPARE PARTS		
Part Number:	**Description:**	**Qty:**

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

GENERAL SERVICE REPORT

Benni Wijaya

TECHNICIAN HOURS					
Time	**Start**	**Finish**		**Start**	**Finish**
Travel To Site:	06:45	07:30			
Onsite:	07:30	16:00			
Travel From Site:	16:00	16:45			

Vlad Smagin

TECHNICIAN HOURS					
Time	**Start**	**Finish**		**Start**	**Finish**
Travel To Site:	07:00	07:30			
Onsite:	07:30	16:00			
Travel From Site:	16:00	16:30			

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:	Trent	X _____	23/08/2022
Technician:	Benni/Vlad		