

Comprehensive

# Car Inspection Report



Thorough inspection with  
**140+ quality checks**



Precise insights from  
**experienced technicians**



Trusted by  
**over 600,000 customers**



## MARUTI SUZUKI BREZZA

VXI | 2025 | MT | Petrol

Inspection location: Ghaziabad

Report generated on: 04 Oct, 2025



**10M +**  
Cars Inspected

**200 +**  
Cities Present

**1M +**  
Cars Sold

## Content of report



### 01 Your report at a glance

Overview of your overall car condition



### 02 Inspection summary

Category wise ratings and condition



### 03 Detailed Evaluation of each category

1. Exterior & Tyres
2. Engine & Transmission
3. Electricals & Interiors
4. Steering, Suspension & Brakes
5. Air Condition
6. Other Details



### 04 OEM installed features & specs

1. Safety
2. Fuel & Performance
3. Entertainment & Communication
4. Dimensions & Capacity
5. Engine, Transmission & Brakes
6. Comfort & Convenience



UP TO ZERO DOWN PAYMENT

05

Loan offer up to ₹8,69,413

Interest starts 10.99% | Tenure up to 72 months





## MARUTI SUZUKI BREZZA

VXI | 2025 | Manual | Petrol

Overall Rating

**4.6 / 5** Excellent

Odometer reading  
**7 kms**

Estimated Value  
**₹7.9 L - ₹8.7 L**

No Challan on  
this vehicle

Get this car with loan  
up to **₹8.7 L**

[Apply now >>](#)



Ownership no.  
**01**



Blacklisted  
**NA**



Hypothecation  
**No**

## Health report summary

At CARS24, we conduct a 140-point inspection to ensure quality. Your car has passed the basic checks. Here is a summary of its condition:

- The car's AC, heater, climate control, power windows, airbags, music system, and steering mounted controls are functional.
- Engine, transmission, steering, suspension, and brakes are in good condition. No blow-by or unusual engine sounds were detected.
- The car has surface rust on the right rear door, damaged headlights and taillights, and a scratched right side mirror.

Overall, the car is in acceptable condition, with some minor issues noted in the exterior and lights.

## Ownership and validity details

Owner: **Customer**

Registration date: **NA**

Ownership number: **1**

Registration place: **Delhi, Delhi NCR**

Ownership type: **NA**

Fitness validity: **NA**

Estimated kms/year: **0 Kms**

PUCC validity: **NA**

## Transferability details

Blacklisted: **NA**

RTO NOC Issued: **NA**

Party Peshi applicability at RTO: **NA**

Hypothecation & Financier Name: **No**

## Vehicle modification

Converted (Commercial ownership to private): **NA**

Migration (Re-registered in another state): **NA**

Adapted for Special Use (Example differently abled): **NA**

## Legal history details

Criminal cases: **None reported**

Civil cases: **None reported**

Road accidents: **None reported**

Compensation cases: **None reported**

Other cases: **None reported**

 **No legal cases**

Clean legal history reflects your commitment as a responsible citizen, paving the way for better drives, better lives and brighter roads ahead.

# ★ Inspection Summary



This section provides a comprehensive evaluation of the most recent car assessment, meticulously divided into five key categories to offer an in-depth and accurate overview.

## ⌚ Exterior & Tyres

Okay, here's a summary of your car's exterior and tyre condition: Most of the exterior parts are in good shape. However, there's some surface rust on the right rear door, one headlight is damaged, ORVM has scratches, and tyres are in good condition.

**4.4/5****Excellent**

## 📸 Engine & Transmission

Okay, here's a summary of your car's engine condition: The engine seems to be in acceptable condition. There's no blow-by, and there's no unusual engine sound.

**4.8/5****Excellent**

## 🌐 Steering, Suspension & Brakes

Okay, so the steering, suspension, and brakes are all in acceptable shape according to our inspection. They seem to be functioning as expected.

**4.8/5****Excellent**

## 🌡️ Air Conditioning

The car's air conditioning system, including the cooling, heater, and climate control, is functioning properly. All components are in good working order.

**4.8/5****Excellent**

## 💻 Electricals & Interiors

Your car has 4 power windows and airbags. It also features a music system, fabric seats and steering mounted audio controls. ABS and rear defogger are working. Overall electricals and interior are in acceptable condition.

**4.6/5****Excellent**

 Vehicle Images car-image-4

## 01. Exterior & Tyres

Perfect parts: 42 | Imperfect parts: 04



Parameters	Perfect	Imperfect
Roof		
Bonnet/Hood		
Dicky Door / Boot Door		
Boot Floor		
Quarter Panel LHS		
Quarter Panel RHS		
Fender LHS		
Fender RHS		
Pillar LHS A		
Pillar LHS B		
Pillar LHS C		
Pillar RHS A		
Pillar RHS B		
Pillar RHS C		
Apron LHS		
Apron RHS		
Apron LHS LEG		

Exterior & Tyres    Engine & Transmission    Electricals & Interiors    Steering, Suspension & Brakes    Air Condition    Other Details

Parameters	Perfect	Imperfect
Apron RHS LEG		
Firewall		
Cowl Top		
Upper Cross Member (Bonnet Patti)		
Lower Cross Member		
Radiator Support		
Head Light Support		
Running Border LHS		
Running Border RHS		
Door LHS Front		
Door LHS Rear		
Door RHS Front		
Windshield Front		
Windshield Rear		
Light RHS Headlight		
Light LHS Taillight		
Bumper Front		
Bumper Rear		
ORVM - Manual / Electrical LHS		
Is the Car Waterlogged?		

[Exterior & Tyres](#) — [Engine & Transmission](#) — [Electricals & Interiors](#) — [Steering, Suspension & Brakes](#) — [Air Condition](#) — [Other Details](#)

Parameters	Perfect	Imperfect
LHS Front Tyre		
LHS Rear Tyre		
RHS Front Tyre		
LHS Rear Tyre		
Spare Tyre		
Door RHS Rear		
Light LHS Headlight		
Light RHS Taillight		
ORVM - Manual / Electrical RHS		

### Exterior & Tyres imperfect parts images



Door RHS Rear: Surface Rust



Light LHS Headlight: Damaged



Exterior & Tyres   Engine & Transmission   Electricals & Interiors   Steering, Suspension & Brakes   Air Condition   Other Details



Light RHS Taillight: Damaged



ORVM - Manual / Electrical RHS: Scratched



## 02. Engine & Transmission

Perfect parts: 11 | Imperfect parts: 0



Parameters	Perfect	Imperfect
Engine	✓	
Engine Sound	✓	
Exhaust Smoke	✓	
Engine Mounting	✓	
Clutch	✓	
Gear Shifting	✓	
Engine Oil	✓	
Engine Oil Level Dipstick	✓	
Battery	✓	
Coolant	✓	
Sump	✓	

[Exterior & Tyres](#) [Engine & Transmission](#) [Electricals & Interiors](#) [Steering, Suspension & Brakes](#) [Air Condition](#) [Other Details](#)

## 03. Electricals & Interiors

Perfect parts: 13 | Imperfect parts: 0



Parameters	Perfect	Imperfect
4 Power Windows LHS Front		
4 Power Windows LHS Rear		
4 Power Windows RHS Front		
4 Power Windows RHS Rear		
Airbag Feature Driver Side		
Airbag Feature Co-Driver Side		
Music System		
Fabric Seat		
Steering Mounted Audio Control		
ABS		
Rear Defogger		
Electrical		
Interior		

Parameters	Number
No. Of Airbags	4
No. Of Power Windows	4

Exterior & Tyres   Engine & Transmission   Electricals & Interiors   Steering, Suspension & Brakes   Air Condition   Other Details



## 04. Steering, Suspension & Brakes

Perfect parts: 03 | Imperfect parts: 0



Parameters	Perfect	Imperfect
Steering		
Suspension		
Brake		



## 05. Air Conditioning

Perfect parts: 03 | Imperfect parts: 0




Parameters	Perfect	Imperfect
AC Cooling		
Heater		
Climate Control AC		



## 06. Other Details

Available : 02 | Not Available: 02



[Exterior & Tyres](#) — [Engine & Transmission](#) — [Electricals & Interiors](#) — [Steering, Suspension & Brakes](#) — [Air Condition](#) — [Other Details](#)**Parameters****Available****Not available**Chassis Embossing RC Availability Insurance Image Duplicate Key 

Chassis Embossing: Ok



Duplicate Key: Yes

## ⭐️ OEM installed features & specs

Understanding the features and specifications of the **MARUTI SUZUKI BREZZA** is essential to ensure it aligns with your preferences, needs, and lifestyle, helping you find the perfect automotive match.

	Airbags 2		Seating Capacity 5		Transmission Type <b>Manual</b>
---	--------------	---	-----------------------	---	------------------------------------

### 🛡 Safety

Parameters	Metric
Front Fog Lights	No
ISOFIX - Child Seat Anchor Points	Yes
ABS - Anti-lock Braking System	Yes
Central Locking	Yes
Rear Defogger	Yes
Airbags	2

### ⚡ Fuel & Performance

Parameters	Metric
Max Power (bhp)	103
Max Torque (Nm)	137
Fueltank Capacity (litres)	48
Emission Standard	BSVI


## Entertainment & Communication

Instrument Panel Type


**Analogue & Digital**

360° 3D Surround View Camera System

**No**




## Interior & Exterior



## ↗ Dimensions & Capacity

Body Type

**SUV**

## ⚙ Engine, Transmission & Brakes

Parameters	Metric
Gear Box - Number Of Gears	5
Displacement (cc)	1462
Transmission Type	Manual
Cylinders	4
Number Of Disc Brakes	2
Number Of Disc Brakes	2

 **Comfort & Convenience**

Parameters	Metric
Seat Upholstery	Upgraded Cloth/Velour
Steering Wheel Material	Plastic
Steering Adjustment	
Yes	
Air Conditioner	
Yes	
Push Button Start	
No	



# Loan offer for your car

Exclusive loan offer tailored to your car's value and condition.

Get this car with a loan up to

**₹8,69,413**

Down payment up to <b>Zero</b>	Interest starts <b>10.99%</b>	Tenure up to <b>72 months</b>
-----------------------------------	----------------------------------	----------------------------------

Get **FREE** extended warranty worth ₹10k. T&C apply\*

[Apply now →](#)

## Thank you for choosing us!

We truly appreciate your decision to prioritize the safety and maintenance of your vehicle. By opting for a thorough inspection, you're ensuring not only the longevity of your car but also peace of mind for you and your loved ones.

Should you have any questions about the inspection report or need further assistance, please don't hesitate to reach out. We're here to help and ensure your vehicle remains in top condition.

Thank you once again for your trust and patronage.

### Other services by

[CHALLAN ↗](#)

[SERVICE HISTORY ↗](#)

[PRE- DELIVERY INSPECTION ↗](#)

[PERSONAL LOAN ↗](#)





Buying, selling, and financing pre-owned cars is now easier than ever!

4.5 ★★★★★

194K ratings • 

4.5 ★★★★★

24.1K ratings • 

4.5 ★★★★★

1K ratings • 

Experience CARS24 App on mobile



## Keep in touch

 care@cars24.com



Disclaimer: Service provided by Cars24 is conducted to the best of our ability and knowledge at the time of inspection. Cars24 shall not be liable for any direct, indirect, incidental or consequential damages rising in connection with any defect, damages, or misrepresentation related to the inspected vehicle. For further details, please refer to our T&Cs.