

106-01 101st Ave., Ozone Park, NY 11416 Tel: 718-850-0900 | Fax: 914-462-4764

PATIENT: CHOUDHURY, ABDUS EXAM DATE: 02/04/2022 6:43 PM

STUDY DESCRIPTION: MRI KNEE WITHOUT CONTRAST (JOINT) MRN: CHOA55009

DOB: 05/03/1975 REFERRING PHYSICIAN: Smith, Tara

**GENDER** 

M

## RIGHT KNEE MRI WITHOUT CONTRAST

HISTORY: Right knee pain status post motor vehicle accident

pt c/o right knee and calf pain, h/o trauma

**TECHNIQUE**: Multiplanar, multi-sequence MRI of the right knee was obtained without intravenous contrast.

COMPARISON: None available.

## FINDINGS:

CLINICAL

**HISTORY** 

LIGAMENTS: There is hyperintense PD signal about the anterior cruciate ligament consistent with sprain sequelae. The posterior cruciate ligament is intact. The collateral ligaments are preserved.


MEDIAL COMPARTMENT: Intact medial meniscus and articular cartilage.

LATERAL COMPARTMENT: Intact lateral meniscus and articular cartilage.

PATELLOFEMORAL COMPARTMENT: Intact articular cartilage.

MARROW: Normal marrow signal.

SYNOVIUM/ JOINT FLUID: There is a joint effusion.



106-01 101st Ave., Ozone Park, NY 11416 Tel: 718-850-0900 | Fax: 914-462-4764

PATIENT: CHOUDHURY, ABDUS EXAM DATE:

02/04/2022 6:43 PM

STUDY DESCRIPTION: MRI KNEE WITHOUT CONTRAST (JOINT) | MRN:

CHOA55009

DOB:

05/03/1975

REFERRING PHYSICIAN:

Smith, Tara

**CLINICAL** HISTORY

pt c/o right knee and calf pain, h/o trauma

**GENDER** 

М

MUSCLES: No muscle edema or fatty muscle atrophy.

NEUROVASCULAR STRUCTURES: Normal in course and caliber.

EXTENSOR MECHANISM: The quadriceps tendon is intact. There is edema surrounding the patellar tendon consistent with paratenonitis.

PERIPHERAL SOFT TISSUES: Normal.

## IMPRESSION:

Anterior cruciate ligament sprain sequelae. Joint effusion.

Patellar paratenonitis.

Digitally Signed By: Borukhov, David Digitally Signed Date: 02/08/2022 2:25 PM