

18885260483

106-01 101st Ave., Ozone Park, NY 11416 Tel: 718-850-0900 | Fax: 914-462-4764

EXAM DATE: 03/10/2022 11:14 AM GONZALEZ, CESAR PATIENT: MRI KNEE WITHOUT CONTRAST (JOINT) MRN: GONC57204 **STUDY** DESCRIPTION: DOB: 06/17/1983 REFERRING Smith, Tara PHYSICIAN: Μ **GENDER CLINICAL** RT KNEE PAIN **HISTORY** 

## RIGHT KNEE MRI WITHOUT CONTRAST

HISTORY: Right knee pain status post motor vehicle accident

TECHNIQUE: Multiplanar, multi-sequence MRI of the right knee was obtained without intravenous contrast.

**COMPARISON**: None available.

## FINDINGS:

LIGAMENTS: The cruciate and collateral ligaments are intact

MEDIAL COMPARTMENT: There is edema within the posterior medial meniscocapsular junction consistent with meniscal capsular junction sprain. Intact articular cartilage.

LATERAL COMPARTMENT: Intact lateral meniscus and articular cartilage.


PATELLOFEMORAL COMPARTMENT: Intact articular cartilage.

MARROW: There are osseous contusions at the anterior aspect of lateral femoral condyle and the inferior pole of the patella.

SYNOVIUM JOINT FLUID: No joint effusion or synovial thickening. There is a small popliteal cyst.

Page 2 of 2

18885260483



106-01 101st Ave., Ozone Park, NY 11416 Tel: 718-850-0900 | Fax: 914-462-4764

PATIENT:	GONZALEZ, CESAR	EXAM DATE:	03/10/2022 11:14 AM
STUDY DESCRIPTION:	MRI KNEE WITHOUT CONTRAST (JOINT)	MRN:	GONC57204
DOB:	06/17/1983	REFERRING PHYSICIAN:	Smith, Tara
CLINICAL HISTORY	RT KNEE PAIN	GENDER	м

MUSCLES: No muscle edema or fatty muscle atrophy.

NEUROVASCULAR STRUCTURES: Normal in course and caliber.

EXTENSOR MECHANISM: The quadriceps tendon is intact. The patella tendon is preserved.

PERIPHERAL SOFT TISSUES: Normal.

## IMPRESSION:

Osseous contusions at the anterior aspect of lateral femoral condyle and the inferior pole of the patella.

Posterior medial meniscocapsular junction sprain.

Digitally Signed By: Borukhov, David Digitally Signed Date: 03/11/2022 3:21 PM