AI-Assisted Web Testing & Bug Explanation Report

Flipkart Web Application – Testim Test Execution

Project	smvdu
Application	Flipkart Web
Test Type	AI-assisted UI / functional test automation
Execution Result	FAILED
Primary Failure	Element not found / element not visible at the Remove-cart step
Test Run	07 Oct 2026, 23:40:02–23:41:11 UTC
Environment	Windows; Chrome; 1024 × 680 shown in the execution UI

Purpose of this report

This report explains the AI-assisted UI test execution shown in the supplied Testim screenshots, documents the observed failure, and converts the evidence into a QA-style defect report. The report is based on the uploaded screenshots and the exported Test Run Report.

Source evidence

The exported report identifies the project as smvdu, project type as Web, branch as master, runner as NISHANK MISHRA, and records a Failed execution. It records a 1:09 duration and one warning in the overall summary. The Base URL is the Flipkart login/account URL.

1. Test Objective

The apparent objective of the recorded test is to navigate through the Flipkart web application, interact with category/product/cart elements, and verify that a cart item can be removed. The screenshots show a sequence of AI-recorded/replayed UI actions followed by a failure at the Remove action.

2. Observed Test Flow

Step	Observed action	Evidence / observation
1	Setup / open Flipkart login-account URL	Testim execution begins from the Flipkart account/login URL.
2–6	Navigate/click through Flipkart categories	Screenshots show clicks involving Flipkart navigation, Fashion, Mobiles, Electronics and Beauty.
7–10	Continue category/product interaction	The execution contains Click steps including Appliances and Image-related interaction.
11	Click “GO TO CART”	Cart workflow is reached.
12	Click “Remove”	Execution screenshot indicates the element is not visible at this point.
13	Click “Remove”	Execution fails with “Element not found.”
14–15	Subsequent recorded steps	The run does not successfully complete the intended Remove interaction; a later Flipkart click and resize are visible in the recorded sequence.

3. What the Failure Means

The failure is an automation/object-recognition failure rather than proof that the Remove feature itself is broken. The screenshot shows a visible “Remove” control in the cart page, while Testim reports that the element could not be found. A second execution view reports “Element is not visible.” Therefore, the immediate defect to investigate is the test's ability to reliably identify and interact with the Remove element under the recorded browser/viewport state.

Important distinction

Observed: the automated test failed at the Remove interaction. Not established by the evidence: that Flipkart's Remove functionality is functionally broken. A manual click or a corrected locator/re-recorded step is needed to determine whether the application feature itself fails.

4. AI Testing Explanation

• The test uses AI-assisted UI automation to record/replay interactions against the web application.

• The execution interface displays captured screenshots for individual steps, which helps compare the expected/baseline visual state with the result.

• The failed step reports an element-recognition/visibility problem. This is useful in AI testing because the framework can flag that the target element was not reliably actionable in the current page state.

• The test run also shows warnings during the flow, including a resize-related warning in the setup area. This suggests that the execution environment/viewport should be stabilized before relying on visual or element-based interactions.

• AI-assisted automation can reduce manual locator maintenance, but dynamic e-commerce pages can still require stable targeting, waits, and re-recording when page structure or visibility changes.

5. Defect / Bug Report

Field	Value
Bug ID	AI-FLP-001
Title	Remove button cannot be reliably identified/clicked by AI test
Module	Shopping Cart
Feature	Remove cart item
Environment	Chrome on Windows; execution UI shows 1024 × 680
Test	AI-assisted Flipkart UI test
Severity	Medium – functional cart action is blocked in automation
Priority	High – test case cannot complete the cart validation
Status	Open / Requires investigation
Observed error	“Element not found”; another execution view shows “Element is not visible”

6. Steps to Reproduce

1. Open the Flipkart web application using the recorded account/login URL.

2. Execute the recorded navigation through the category/product pages.

3. Navigate to the shopping cart using “GO TO CART”.

4. Locate the cart item and the “Remove” action.

5. Run the AI-recorded Remove step.

6. Observe that the automation reports either “Element is not visible” or “Element not found”, and the test run becomes Failed.

7. Expected vs Actual Result

Expected Result	Actual Result
The automation should identify the Remove button, click it, and continue to the next validation step.	The automation cannot reliably identify/act on the Remove button. The run fails at the Remove step.
The cart item should be removed if the application is functioning correctly.	The supplied evidence does not prove whether the item is actually removed by the application because the automated click does not complete successfully.

8. Likely Technical Causes to Investigate

• Dynamic DOM: the cart/Remove element may be recreated after navigation, making a previously captured target stale.

• Visibility/state: the element may exist in the DOM but not be actionable because of overlays, scrolling, loading, or a transient page state.

• Viewport/resolution: the execution includes a resize warning and a fixed 1024 × 680 environment; responsive layout changes can move or hide controls.

• Timing: the Remove control may appear after asynchronous cart content loads, requiring an explicit wait for visibility/clickability.

• Locator/AI target drift: the recorded visual target may no longer match the current page structure or rendered element.

• Multiple matching elements: if more than one Remove-like control exists, the automation may be targeting the wrong instance.

9. Recommended Fix / Retest Plan

1. Re-record Step 13 after opening the cart in a clean session and confirm the Remove target is correctly recognized.

2. Add a wait for the cart item and Remove control to become visible/clickable before the click.

3. Use a stable element attribute or unique text/container relationship where the tool permits locator editing.

4. Keep browser size/resolution consistent across baseline and execution; remove unnecessary resize steps.

5. Scroll the Remove control into the viewport before clicking if the tool supports an explicit scroll/wait action.

6. If an overlay, popup, or sticky element blocks the control, close the overlay before the Remove action.


7. Run the test three times after correction to check for stability and eliminate intermittent failures.

8. Perform one manual validation of Remove to separate an application defect from an automation defect.


10. QA Conclusion

The supplied evidence demonstrates a failed AI-assisted UI test during the Flipkart cart workflow. The failure is concentrated on the Remove interaction, with messages indicating that the target was not visible or could not be found. The most appropriate first action is to treat this as an automation stability/element-targeting defect, reproduce it manually, then re-record or stabilize the target with appropriate waits and a consistent viewport. Only after manual verification should it be classified as a confirmed application defect.


11. Evidence Screenshots



Evidence 1 – Failed execution: Step 13 “Click Remove” reports “Element not found”.



Evidence 2 – Failed execution view showing “Element is not visible” around the Remove step.



Evidence 3 – Side-by-side baseline/result comparison for the Remove interaction.

12. Test Execution Record

The exported Test Run Report records the project as smvdu, branch master, Windows OS, runner NISHANK MISHRA, result ID eUL4V65ajRNljXqg, and a run from 23:40:02 to 23:41:11 UTC. The result is marked Failed. The report's overall summary shows 0 passed, 0 failed, 0 skipped and 1 warning, while the visual execution screen contains a larger recorded step sequence. This difference should be treated as an export/reporting detail rather than silently reconciled.

Final defect statement for Jira

AI-FLP-001 – Remove button not reliably identified by AI automation: During the Flipkart cart test, the automation reaches the Remove action but fails because the target is reported as not visible/not found. The test cannot complete the cart-removal validation. Re-record the target, stabilize the viewport, add appropriate visibility/clickability waits, and manually verify the Remove feature before classifying the issue as an application defect.