

Task 1

QA Debug Report

RealWorld Conduit Demo Application

Nitesh Kushwaha

June 1, 2026

1 Test Environment

- **Application Tested:** RealWorld Conduit Demo Application
- **Application URL:** <https://demo.realworld.show/>
- **Test Profile:** <https://demo.realworld.show/profile/nitesh>
- **Testing Method:** Manual exploratory testing of registration, login, article creation, article editing, article deletion, commenting, profile settings, and session management.

2 Bug Report Summary

#	Title / Summary	Steps to Reproduce	Expected vs Actual	Severity	Suspected Cause
1	Invalid email format accepted during registration	• Open Sign Up page • Enter username • Enter invalid email: abc • Enter password • Click Sign Up	Expected: Application should reject invalid email formats and display a validation message. Actual: Account was successfully created and user was authenticated using an invalid email address.	Medium	Missing frontend and/or backend email format validation.
2	Article deletion occurs without confirmation dialog	• Create a new article • Open the article • Click Delete Article	Expected: Application should display a confirmation dialog before deleting the article. Actual: Article was deleted immediately without any confirmation prompt.	High	Missing confirmation modal for destructive actions.

Figure 1. User account was successfully created and authenticated despite providing an invalid email format during the registration process. The application failed to validate the email structure before account creation.

3.2 Issue 2 - Article Deletion Without Confirmation Dialog




Figure 2. The article page displays a *Delete Article* action without presenting any warning, confirmation dialog, or safeguard against accidental deletion.




Figure 3. After clicking *Delete Article*, the content was immediately removed from the system without requiring user confirmation, increasing the risk of unintended data loss.

3.3 Issue 3 - Article Published Without Content Validation




Figure 4. The application allows users to publish an article even when the primary content/body field is empty. No validation message is displayed before publishing.

3.4 Issue 4 - Invalid Special-Character Tags Accepted




Figure 5. Special-character values such as commas, periods, and slashes were entered into the tag field without validation.




Figure 6. The application successfully published and displayed special-character values as article tags.

3.5 Issue 5 - Invalid Profile Image URL Accepted

Conduit

Home [New Article](#) [Settings](#)  nitesh

Your Settings

123

nitesh

Short bio about you


nitesh123

New Password

[Update Settings](#)

[Or click here to logout.](#)

Figure 7. An invalid value (123) was entered into the Profile Picture URL field and accepted by the application.



4 Root Cause Analysis

Selected Issue: Invalid Profile Image URL Accepted in User Settings

During testing, the application accepted an invalid value (123) in the Profile Picture URL field without showing any validation error. After saving the settings, the invalid value resulted in a broken profile image.

This issue appears to be caused by missing URL validation in the profile settings form. Both the frontend and backend allow invalid values to be stored without verification.

To fix this issue, the application should validate image URLs before saving them and display an error message when an invalid URL is entered. A default profile image should also be shown if the provided image cannot be loaded.

5 Conclusion

A total of five issues were identified during testing of the RealWorld Conduit demo application. These findings highlight gaps in input validation, content management, and user experience safeguards.

Addressing these issues would improve application reliability, data quality, and overall user experience before production deployment.