SK-ZF-004 Stockroom: every piece starts where the next ends; every print a decal



Rules (tools/sakura-surface-audit.mjs STRICT_RULES; tests/sakura-surfaces.test.mjs):
- no two faces within 2 mm of one plane over 0.1 cm2,
  even of one colour: two pieces overlapping are still two faces;
- nothing within 10 mm of another face over 0.05 m2,
  unless it is a decal (polygon offset) or clear glazing (no depth write).
Red circles: what the audit found on main, sized by area.

Zone	before: close / wide	after
stockroom	18 / 4	0 / 0
stair foot	2 / 0	0 / 0

Found on main, and the correction

Beer crates
was: long walls ran past the end walls, rims overhung into the next crate,
now: long walls between the end walls; rims exactly one crate wide; end wal

Beer crate label
was: paper 2.5 mm off the crate wall, 0.27 m2
now: a decal (polygon offset) on the wall

Exit sign
was: face 2 mm off its housing, 0.14 m2
now: a decal on the housing

Found on main, and the correction

Shrink film on the trays
was: film 2.5-5 mm over the tray, writing depth
now: clear film: glazing that writes no depth

Stockroom door frame
was: jambs ran up into the head
now: jambs stop under the head

Step ladder
was: steps flush with the rails' outer faces
now: steps between the rails

Found on main, and the correction

Parcel twine
was: the two cross loops in one plane
now: the cross loop 3 mm wider

Daisha handle
was: bar and uprights' facets in one plane
now: bar turned half a facet

SK-ZF-004 rev A 27 October 2026

Sakura Shoten, Minato - stockroom and staircase surfaces
Stockroom plan 1:30, findings and corrections
Virtual-environment drawing, not a construction approval.

SK-ZF-005 Staircase: a passage into the dark, both ends built without a shared plane



Zone	before: close / wide	after
stair foot	2 / 0	0 / 0
stair head	3 / 0	0 / 0
upper stores	5 / 1	0 / 0

Found on main, and the correction

Stairwell walls (stair head)
was: end walls and ceiling ran into the back wall, 0.45 m2 at 0 m
now: end walls and ceiling start at the back wall's face

Futon cupboard (upper stores)
was: frame members overlapping; shelf 3 mm off its battens, 0.08
now: frame members butt; shelf on the battens

Store walls (upper)
was: the long wall ran into its end wall, their faces in one plan
now: the long wall starts at the end wall's face

Cans on the stock trays
was: base bead closed above, a face inside the can 6 mm over the
now: base bead open above, the bottom a disc

Stair head, plan 1:60 (office frame): end walls between the back wall and the hall



SK-ZF-005 rev A 27 October 2026

Sakura Shoten, Minato - stockroom and staircase surfaces

Staircase: section looking north and the stair head, 1:40

Virtual-environment drawing, not a construction approval.