



Test Report

Report №.: ZOL250324Y8079-1RC

Date: Mar.24,2025

Page 1 of 20

Applicant	:	Wenzhou Yi Xiang Electronic Technology Co., Ltd.
Address	:	B17-7 Mechanical Industrial Park, Wanquan Light Industry Production Base, Pingyang County, Wenzhou City, Zhejiang Province, China
Manufacturer	:	Wenzhou Yi Xiang Electronic Technology Co., Ltd.
Address	:	B17-7 Mechanical Industrial Park, Wanquan Light Industry Production Base, Pingyang County, Wenzhou City, Zhejiang Province, China

The following samples were submitted and identified on behalf of the clients as:

Trade Name	:	NA	
Sample Name	:	FASCIAL GUN MASSAGE	
Style No.	:	KK-26	
Series No.	:	N/A	
Customer Statement	:	All models are same as the samples except model name and appearance,they have the same structure/circuit.	
Sample Received Date	:	Mar.19,2025	
Testing Period	:	Mar.19,2025 to Mar.24,2025	
Test Results	:	For details refer to attached page(s).	
Test Requested	:	ROHS Directive 2011/65/EU and its subsequent amendments & Directive (EU)2015/863	Conclusion
TM		1. To determine Lead(Pb), Cadmium(Cd), Mercury(Hg), Hexavalent Chromium(Cr(VI)), Polybrominated Biphenyls(PBBs) and Polybrominated Diphenyl Ethers(PBDEs) content by screening test and chemical test.	Pass
		2.To determine Phthalates (DBP,BBP,DEHP,DIBP) content by chemical test.	Pass

REMARKS:Selected test (s) in the selected parts as requested by client with the RoHS Directive 2011/65/EU Annex II (EU)2015/863 as last amended by Directive(EU) 2017/2102.

Authorized By:



Rae Chen

Lab Manager

This test report is issued by the company subject to its General Conditions of Services printed overleaf or available on request and accessible at www.zo-lab.com. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. Unless otherwise stated the results shown in this report refer only to the sample(s) tested. Without prior written permission of the company, this test report cannot be reproduced, except in full.

Ningbo Zhengou Testing Technology Co., Ltd.

Add: 1st Floor, Building 041, Building B, No. 188 Jinghua Road, Ningbo High tech Zone, Zhejiang Province, China.

Certificate Search: <http://www.zo-lab.com>, Tel: 0574-2788 0858, E-mail: verification@zo-lab.com

Test Report

Report №.: ZOL250324Y8079-1RC

Date: Mar.24,2025

Page 2 of 20

Sample Information:

Sample identity	Sample description	NOTICE
1	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
2	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
3	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
4	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
5	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
6	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
7	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
8	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
9	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
10	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
11	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
12	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
13	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
14	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
15	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
16	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
17	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
18	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
19	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
20	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal

Remark:

1.The tested parts were designated by client.

(To be continued)

This test report is issued by the company subject to its General Conditions of Services printed overleaf or available on request and accessible at www.zo-lab.com. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. Unless otherwise stated the results shown in this report refer only to the sample(s) tested. Without prior written permission of the company, this test report cannot be reproduced, except in full.

Ningbo Zhengou Testing Technology Co., Ltd.

Add: 1st Floor, Building 041, Building B, No. 188 Jinghua Road, Ningbo High tech Zone, Zhejiang Province, China.

Certificate Search: <http://www.zo-lab.com>, Tel: 0574-2788 0858, E-mail: verification@zo-lab.com

Test Report

Report №.: ZOL250324Y8079-1RC

Date: Mar.24,2025

Page 3 of 20

Sample identity	Sample description	NOTICE
21	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
22	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
23	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
24	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
25	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
26	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
27	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
28	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
29	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal
30	For detailed information, please refer to the image at the end of the report (describing the testing points)	Normal

Remark:

1.The tested parts were designated by client.

(To be continued)

This test report is issued by the company subject to its General Conditions of Services printed overleaf or available on request and accessible at www.zo-lab.com. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. Unless otherwise stated the results shown in this report refer only to the sample(s) tested. Without prior written permission of the company, this test report cannot be reproduced, except in full.

Ningbo Zhengou Testing Technology Co., Ltd.

Add: 1st Floor, Building 041, Building B, No. 188 Jinghua Road, Ningbo High tech Zone, Zhejiang Province, China.

Certificate Search: <http://www.zo-lab.com>, Tel: 0574-2788 0858, E-mail: verification@zo-lab.com

Test Report

Report №.: ZOL250324Y8079-1RC

Date: Mar.24,2025

Page 4 of 20

Testing Results:

Test Method:

- (1) To refer to the standard IEC 62321-3-1:2013, screening by XRF Spectroscopy;
- (2) Wet Chemical test:
 - (a) Refer to IEC 62321-4:2013+AMD1:2017,determine the Mercury content by ICP-OES;
 - (b)Refer to IEC 62321-5:2013,determine the Cadmium,Lead content by ICP-OES;
 - (c)Refer to IEC 62321-7-2:2017,determine the Hexavalent Chromium content by UV-VIS;
 - (d)Refer to IEC 62321-6:2015,determine the Polybrominated Biphenyls and Polybrominated Diphenyl Ethers by GC-MS;
 - (e) Refer to IEC 62321-8:2017,determine the Phthalatescontent by GC-MS;

Reporting Limit and Limit:

Test items	Pb	Hg	Cd	Cr ⁶⁺ (metal)	Cr ⁶⁺ (Non-metal)	PBBs	PBDEs	DIBP	DBP	DEHP	BBP
Unit	mg/kg	mg/kg	mg/kg	N/A	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg
RL	5	5	5	N/A	5	10	10	30	30	30	30
Limit	1000	1000	100	Negative	1000	1000	1000	1000	1000	1000	1000

Remark:

(1)mg/kg= ppm =0.0001%, N/A=Not Applicable.

(2)RL=Report Limit.

(3)According to IEC 62321-7-1:2015, result on Cr⁶⁺ for metal sample is shown as Positive/Negative. Negative=Absence of Cr⁶⁺ coating, Positive=Presence of Cr⁶⁺ coating.

Storage condition and production date of the tested sample are unavailable and thus results of Cr⁶⁺ represent status of the sample at the time of testing.

(To be continued)

This test report is issued by the company subject to its General Conditions of Services printed overleaf or available on request and accessible at www.zo-lab.com. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. Unless otherwise stated the results shown in this report refer only to the sample(s) tested. Without prior written permission of the company, this test report cannot be reproduced, except in full.

Ningbo Zhengou Testing Technology Co., Ltd.

Add: 1st Floor, Building 041, Building B, No. 188 Jinghua Road, Ningbo High tech Zone, Zhejiang Province, China.

Certificate Search: <http://www.zo-lab.com>, Tel: 0574-2788 0858, E-mail: verification@zo-lab.com

Test Report

Report №.: ZOL250324Y8079-1RC

Date: Mar.24,2025

Page 5 of 20

1. XRF Screening test or(and) Chemical test

NO.	Restricted substances	Results of EDXRF(a)	Results of Chemical Testing(b)(mg/kg)	Remark
1	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
2	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
3	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
4	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
5	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
6	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		

(To be continued)

This test report is issued by the company subject to its General Conditions of Services printed overleaf or available on request and accessible at www.zo-lab.com. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. Unless otherwise stated the results shown in this report refer only to the sample(s) tested. Without prior written permission of the company, this test report cannot be reproduced, except in full.

Ningbo Zhengou Testing Technology Co., Ltd.

Add: 1st Floor, Building 041, Building B, No. 188 Jinghua Road, Ningbo High tech Zone, Zhejiang Province, China.

Certificate Search: <http://www.zo-lab.com>, Tel: 0574-2788 0858, E-mail: verification@zo-lab.com

Test Report

Report №.: ZOL250324Y8079-1RC

Date: Mar.24,2025

Page 6 of 20

NO.	Restricted substances	Results of EDXRF(a)	Results of Chemical Testing(b)(mg/kg)	Remark
7	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
8	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
9	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
10	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
11	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
12	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		

(To be continued)

This test report is issued by the company subject to its General Conditions of Services printed overleaf or available on request and accessible at www.zo-lab.com. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. Unless otherwise stated the results shown in this report refer only to the sample(s) tested. Without prior written permission of the company, this test report cannot be reproduced, except in full.

Ningbo Zhengou Testing Technology Co., Ltd.

Add: 1st Floor, Building 041, Building B, No. 188 Jinghua Road, Ningbo High tech Zone, Zhejiang Province, China.

Certificate Search: <http://www.zo-lab.com>, Tel: 0574-2788 0858, E-mail: verification@zo-lab.com

Test Report

Report №.: ZOL250324Y8079-1RC

Date: Mar.24,2025

Page 7 of 20

NO.	Restricted substances	Results of EDXRF(a)	Results of Chemical Testing(b)(mg/kg)	Remark
13	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
14	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
15	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
16	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
17	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
18	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		

(To be continued)

This test report is issued by the company subject to its General Conditions of Services printed overleaf or available on request and accessible at www.zo-lab.com. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. Unless otherwise stated the results shown in this report refer only to the sample(s) tested. Without prior written permission of the company, this test report cannot be reproduced, except in full.

Ningbo Zhengou Testing Technology Co., Ltd.

Add: 1st Floor, Building 041, Building B, No. 188 Jinghua Road, Ningbo High tech Zone, Zhejiang Province, China.

Certificate Search: <http://www.zo-lab.com>, Tel: 0574-2788 0858, E-mail: verification@zo-lab.com

Test Report

Report №.: ZOL250324Y8079-1RC

Date: Mar.24,2025

Page 8 of 20

NO.	Restricted substances	Results of EDXRF(a)	Results of Chemical Testing(b)(mg/kg)	Remark
19	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
20	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
21	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
22	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
23	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
24	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		

(To be continued)

This test report is issued by the company subject to its General Conditions of Services printed overleaf or available on request and accessible at www.zo-lab.com. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. Unless otherwise stated the results shown in this report refer only to the sample(s) tested. Without prior written permission of the company, this test report cannot be reproduced, except in full.

Ningbo Zhengou Testing Technology Co., Ltd.

Add: 1st Floor, Building 041, Building B, No. 188 Jinghua Road, Ningbo High tech Zone, Zhejiang Province, China.

Certificate Search: <http://www.zo-lab.com>, Tel: 0574-2788 0858, E-mail: verification@zo-lab.com

Test Report

Report №.: ZOL250324Y8079-1RC

Date: Mar.24,2025

Page 9 of 20

NO.	Restricted substances	Results of EDXRF(a)	Results of Chemical Testing(b)(mg/kg)	Remark
25	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
26	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
27	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
28	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
29	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		
30	Pb	BL	Not Tested	Non comment
	Cd	BL		
	Hg	BL		
	Cr	BL		
	Br	BL		

(To be continued)

This test report is issued by the company subject to its General Conditions of Services printed overleaf or available on request and accessible at www.zo-lab.com. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. Unless otherwise stated the results shown in this report refer only to the sample(s) tested. Without prior written permission of the company, this test report cannot be reproduced, except in full.

Ningbo Zhengou Testing Technology Co., Ltd.

Add: 1st Floor, Building 041, Building B, No. 188 Jinghua Road, Ningbo High tech Zone, Zhejiang Province, China.

Certificate Search: <http://www.zo-lab.com>, Tel: 0574-2788 0858, E-mail: verification@zo-lab.com

Test Report

Report №.: ZOL250324Y8079-1RC

Date: Mar.24,2025

Page 10 of 20

Remark : (a)

① Results are obtained by XRF for primary screening, and further wet chemical testing by ICP-OES/AAS(for Cd,Pb,Hg), UV-VIS (for Cr(VI)and GC/MS(for PBBs, PBDEs)is recommended to be performed, if an inconclusive result was found (as "X" in below table) (unit: mg/kg).

②OL=Over Limit, BL=Below Limit, X=Inconclusive, N/A =Not Applicable,
LOD=3σ=limit of detection.

③The XRF screening test for ROHS elements-The reading may be different to the actual content in the sample be of non-uniformity composition.

④σ=The standard deviation of the results of multiple determinations using a blank material.

Element	Polymer	Metal	Composite Materials
Pb	$BL \leq (700-3\sigma) < X < (1300+3\sigma)$ $\leq OL$	$BL \leq (700-3\sigma) < X < (1300+3\sigma)$ $\leq OL$	$BL \leq (500-3\sigma) < X < (1500+3\sigma)$ $\leq OL$
Hg	$BL \leq (700-3\sigma) < X < (1300+3\sigma)$ $\leq OL$	$BL \leq (700-3\sigma) < X < (1300+3\sigma)$ $\leq OL$	$BL \leq (500-3\sigma) < X < (1500+3\sigma)$ $\leq OL$
Cd	$BL \leq (70-3\sigma) < X < (130+3\sigma) \leq OL$	$BL \leq (70-3\sigma) < X < (130+3\sigma) \leq OL$	$LOD < X < (150+3\sigma) \leq OL$
Cr	$BL \leq (700-3\sigma) < X$	$BL \leq (700-3\sigma) < X$	$BL \leq (500-3\sigma) < X$
Br	$BL \leq (300-3\sigma) < X$	N/A	$BL \leq (250-3\sigma) < X$

Remark: (b)

①mg/kg=ppm=0.0001%, N.D.=Not Detected(Less than reporting limit value).

②Unit, Reporting Limit (RL) and Requirement limit in wet chemical test.

(To be continued)

This test report is issued by the company subject to its General Conditions of Services printed overleaf or available on request and accessible at www.zo-lab.com. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. Unless otherwise stated the results shown in this report refer only to the sample(s) tested. Without prior written permission of the company, this test report cannot be reproduced, except in full.

Ningbo Zhengou Testing Technology Co., Ltd.

Add: 1st Floor, Building 041, Building B, No. 188 Jinghua Road, Ningbo High tech Zone, Zhejiang Province, China.

Certificate Search: <http://www.zo-lab.com>, Tel: 0574-2788 0858, E-mail: verification@zo-lab.com

Test Report

Report №.: ZOL250324Y8079-1RC

Date: Mar.24,2025

Page 11 of 20

2. Phthalates and PBBs&PBBs Contents

Refer to IEC 62321-6:2015&IEC 62321-8:2017,determine the Phthalates and PBBs&PBBscontent by GC-MS.

Test item	CAS No.	Test Result (mg/kg)						RL (mg/kg)	Requirement (mg/kg)
		1	2	3	4	5	6		
DIBP	84-69-5	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	1000
DBP	84-74-2	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	1000
BBP	85-68-7	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	1000
DEHP	117-81-7	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	1000
PBBs	Sum	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	1000
Monobromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Dibromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Tribromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Tetrabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Pentabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Hexabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Heptabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Octabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Nonabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Decabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
PBDEs	Sum	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	1000
Monobromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Dibromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Tribromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Tetrabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Pentabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Hexabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Heptabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Octabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Nonabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Decabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--

(To be continued)

This test report is issued by the company subject to its General Conditions of Services printed overleaf or available on request and accessible at www.zo-lab.com. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. Unless otherwise stated the results shown in this report refer only to the sample(s) tested. Without prior written permission of the company, this test report cannot be reproduced, except in full.

Ningbo Zhengou Testing Technology Co., Ltd.

Add: 1st Floor, Building 041, Building B, No. 188 Jinghua Road, Ningbo High tech Zone, Zhejiang Province, China.

Certificate Search: <http://www.zo-lab.com>, Tel: 0574-2788 0858, E-mail: verification@zo-lab.com

Test Report

Report №.: ZOL250324Y8079-1RC

Date: Mar.24,2025

Page 12 of 20

Refer to IEC 62321-6:2015&IEC 62321-8:2017,determine the Phthalates and PBBs&PBBscontent by GC-MS.

Test item	CAS No.	Test Result (mg/kg)						RL (mg/kg)	Requirement (mg/kg)
		7	8	9	10	11	12		
DIBP	84-69-5	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	1000
DBP	84-74-2	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	1000
BBP	85-68-7	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	1000
DEHP	117-81-7	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	1000
PBBs	Sum	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	1000
Monobromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Dibromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Tribromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Tetrabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Pentabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Hexabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Heptabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Octabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Nonabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Decabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
PBDEs	Sum	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	1000
Monobromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Dibromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Tribromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Tetrabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Pentabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Hexabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Heptabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Octabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Nonabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Decabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--

(To be continued)

This test report is issued by the company subject to its General Conditions of Services printed overleaf or available on request and accessible at www.zo-lab.com. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. Unless otherwise stated the results shown in this report refer only to the sample(s) tested. Without prior written permission of the company, this test report cannot be reproduced, except in full.

Ningbo Zhengou Testing Technology Co., Ltd.

Add: 1st Floor, Building 041, Building B, No. 188 Jinghua Road, Ningbo High tech Zone, Zhejiang Province, China.

Certificate Search: <http://www.zo-lab.com>, Tel: 0574-2788 0858, E-mail: verification@zo-lab.com

Test Report

Report №.: ZOL250324Y8079-1RC

Date: Mar.24,2025

Page 13 of 20

Refer to IEC 62321-6:2015&IEC 62321-8:2017,determine the Phthalates and PBBs&PBBscontent by GC-MS.

Test item	CAS No.	Test Result (mg/kg)						RL (mg/kg)	Requirement (mg/kg)
		13	14	15	16	17	18		
DIBP	84-69-5	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	1000
DBP	84-74-2	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	1000
BBP	85-68-7	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	1000
DEHP	117-81-7	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	1000
PBBs	Sum	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	1000
Monobromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Dibromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Tribromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Tetrabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Pentabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Hexabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Heptabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Octabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Nonabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Decabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
PBDEs	Sum	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	1000
Monobromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Dibromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Tribromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Tetrabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Pentabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Hexabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Heptabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Octabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Nonabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--
Decabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	30	--

(To be continued)

This test report is issued by the company subject to its General Conditions of Services printed overleaf or available on request and accessible at www.zo-lab.com. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. Unless otherwise stated the results shown in this report refer only to the sample(s) tested. Without prior written permission of the company, this test report cannot be reproduced, except in full.

Ningbo Zhengou Testing Technology Co., Ltd.

Add: 1st Floor, Building 041, Building B, No. 188 Jinghua Road, Ningbo High tech Zone, Zhejiang Province, China.

Certificate Search: <http://www.zo-lab.com>, Tel: 0574-2788 0858, E-mail: verification@zo-lab.com

Test Report

Report №.: ZOL250324Y8079-1RC

Date: Mar.24,2025

Page 14 of 20

Refer to IEC 62321-6:2015&IEC 62321-8:2017,determine the Phthalates and PBBs&PBBscontent by GC-MS.

Test item	CAS No.	Test Result (mg/kg)						RL (mg/kg)	Requirement (mg/kg)
		19	20	21	22	23			
DIBP	84-69-5	N.D.	N.D.	N.D.	N.D.	N.D.		30	1000
DBP	84-74-2	N.D.	N.D.	N.D.	N.D.	N.D.		30	1000
BBP	85-68-7	N.D.	N.D.	N.D.	N.D.	N.D.		30	1000
DEHP	117-81-7	N.D.	N.D.	N.D.	N.D.	N.D.		30	1000
PBBs	Sum	N.D.	N.D.	N.D.	N.D.	N.D.		30	1000
Monobromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.		30	--
Dibromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.		30	--
Tribromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.		30	--
Tetrabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.		30	--
Pentabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.		30	--
Hexabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.		30	--
Heptabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.		30	--
Octabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.		30	--
Nonabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.		30	--
Decabromobiphenyl		N.D.	N.D.	N.D.	N.D.	N.D.		30	--
PBDEs	Sum	N.D.	N.D.	N.D.	N.D.	N.D.		30	1000
Monobromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.		30	--
Dibromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.		30	--
Tribromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.		30	--
Tetrabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.		30	--
Pentabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.		30	--
Hexabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.		30	--
Heptabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.		30	--
Octabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.		30	--
Nonabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.		30	--
Decabromobiphenyl ether		N.D.	N.D.	N.D.	N.D.	N.D.	.	30	--

(To be continued)

This test report is issued by the company subject to its General Conditions of Services printed overleaf or available on request and accessible at www.zo-lab.com. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. Unless otherwise stated the results shown in this report refer only to the sample(s) tested. Without prior written permission of the company, this test report cannot be reproduced, except in full.

Ningbo Zhengou Testing Technology Co., Ltd.

Add: 1st Floor, Building 041, Building B, No. 188 Jinghua Road, Ningbo High tech Zone, Zhejiang Province, China.

Certificate Search: <http://www.zo-lab.com>, Tel: 0574-2788 0858, E-mail: verification@zo-lab.com

Test Report


Report №.: ZOL250324Y8079-1RC

Date: Mar.24,2025


Page 15 of 20

Test Process:

1. Test for Cd/Pb Content



2. Test for Hg Content



(To be continued)

This test report is issued by the company subject to its General Conditions of Services printed overleaf or available on request and accessible at www.zo-lab.com. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. Unless otherwise stated the results shown in this report refer only to the sample(s) tested. Without prior written permission of the company, this test report cannot be reproduced, except in full.

Ningbo Zhengou Testing Technology Co., Ltd.

Add: 1st Floor, Building 041, Building B, No. 188 Jinghua Road, Ningbo High tech Zone, Zhejiang Province, China.

Certificate Search: <http://www.zo-lab.com>, Tel: 0574-2788 0858, E-mail: verification@zo-lab.com

Test Report


Report №.: ZOL250324Y8079-1RC

Date: Mar.24,2025


Page 16 of 20

3. Test for Chromium (VI) Content


Nonmetal material



Metal material



4. Test for DBP, BBP, DEHP, DIBP, PBB, PBDE Content



(To be continued)

This test report is issued by the company subject to its General Conditions of Services printed overleaf or available on request and accessible at www.zo-lab.com. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. Unless otherwise stated the results shown in this report refer only to the sample(s) tested. Without prior written permission of the company, this test report cannot be reproduced, except in full.

Ningbo Zhengou Testing Technology Co., Ltd.

Add: 1st Floor, Building 041, Building B, No. 188 Jinghua Road, Ningbo High tech Zone, Zhejiang Province, China.

Certificate Search: <http://www.zo-lab.com>, Tel: 0574-2788 0858, E-mail: verification@zo-lab.com

Test Report

Report №.: ZOL250324Y8079-1RC

Date: Mar.24,2025

Page 17 of 20

Photo(s):



(To be continued)

This test report is issued by the company subject to its General Conditions of Services printed overleaf or available on request and accessible at www.zo-lab.com. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. Unless otherwise stated the results shown in this report refer only to the sample(s) tested. Without prior written permission of the company, this test report cannot be reproduced, except in full.

Ningbo Zhengou Testing Technology Co., Ltd.

Add: 1st Floor, Building 041, Building B, No. 188 Jinghua Road, Ningbo High tech Zone, Zhejiang Province, China.

Certificate Search: <http://www.zo-lab.com>, Tel: 0574-2788 0858, E-mail: verification@zo-lab.com

Test Report

Report №.: ZOL250324Y8079-1RC

Date: Mar.24,2025

Page 18 of 20

Photo(s):



(To be continued)

This test report is issued by the company subject to its General Conditions of Services printed overleaf or available on request and accessible at www.zo-lab.com. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. Unless otherwise stated the results shown in this report refer only to the sample(s) tested. Without prior written permission of the company, this test report cannot be reproduced, except in full.

Ningbo Zhengou Testing Technology Co., Ltd.

Add: 1st Floor, Building 041, Building B, No. 188 Jinghua Road, Ningbo High tech Zone, Zhejiang Province, China.

Certificate Search: <http://www.zo-lab.com>, Tel: 0574-2788 0858, E-mail: verification@zo-lab.com

Test Report

Report №.: ZOL250324Y8079-1RC

Date: Mar.24,2025

Page 19 of 20

Photo(s):



Confirmed by the customer, the unspecified sample is a series of products tested in this report. The series product pictures are provided by the customer, and product photos are added according to customer requirements.

(End of report)

This test report is issued by the company subject to its General Conditions of Services printed overleaf or available on request and accessible at www.zo-lab.com. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. Unless otherwise stated the results shown in this report refer only to the sample(s) tested. Without prior written permission of the company, this test report cannot be reproduced, except in full.

Ningbo Zhengou Testing Technology Co., Ltd.

Add: 1st Floor, Building 041, Building B, No. 188 Jinghua Road, Ningbo High tech Zone, Zhejiang Province, China.

Certificate Search: <http://www.zo-lab.com>, Tel: 0574-2788 0858, E-mail: verification@zo-lab.com

Test Report

Report №.: ZOL250324Y8079-1RC

Date: Mar.24,2025

Page 20 of 20

Photo(s):



Confirmed by the customer, the unspecified sample is a series of products tested in this report. The series product pictures are provided by the customer, and product photos are added according to customer requirements.

(End of report)

This test report is issued by the company subject to its General Conditions of Services printed overleaf or available on request and accessible at www.zo-lab.com. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. Unless otherwise stated the results shown in this report refer only to the sample(s) tested. Without prior written permission of the company, this test report cannot be reproduced, except in full.

Ningbo Zhengou Testing Technology Co., Ltd.

Add: 1st Floor, Building 041, Building B, No. 188 Jinghua Road, Ningbo High tech Zone, Zhejiang Province, China.

Certificate Search: <http://www.zo-lab.com>, Tel: 0574-2788 0858, E-mail: verification@zo-lab.com