Automation for AOI – E/T Correlation

SCK R&D


Jun. 26th ’26




Automation for AOI – E/T Correlation

- Wafer Map & Defect Information


-. Wafer Map



-. Die#11 Map



-. Defect Image (Defect 13 in Klaf file)



-. Die Number:11


-. Defect Coordination (x,y): (12478.370, 13377.791)

```
DefectList
 13 -58994.628 88367.090 12478.370 13377.791 -3 3 3.880 5.180 20.120000 5.180 0 3 0 25 1 1 0 3014 0 1 1 1 69;
TiffFileName XD074.01_-3_3_25_14.jpg;
```


Automation for AOI – E/T Correlation

- Correlation Information


-. Die#11 Map under CAD Map



-. GDS layout for ASIC COREDC5 region



Ver. 1 Requirements
-. Verify whether the defect information, including coordinates, from the AOI KLARF file matches the bump and/or RDL routing locations within the daisy chain in the GDS CAD file.
-. If there is a match, provide the exact bump and/or RDL location information.



Die#	Resistance (Open) Fail Chain	Manual Inspection	TBDB AOI	UPD AOI	ASICDC RES Manual AOI-ET Correlation
7	ASIC_EDGEDC_L1_FH	-	UPD Residue	-	No
11	ASIC_EDGEDC_L1_FH	UPD Residue	UPD Residue	-	No
11	ASIC_COREDC5_P_FH	UPD Residue	UPD Residue	-	Yes
11	ASIC_COREDC5_N_FH	UPD Residue	UPD Residue	-	Yes

Thank you

