



# Life-Cycle Cost Analysis of Pavement Preservation Techniques in Texas

Presented at the 96th Annual Meeting the Transportation Research Board, Washington, DC, January 2017.

Wilfrido Martínez-Alonso – [wilfrido.martinez@utexas.edu](mailto:wilfrido.martinez@utexas.edu)

Natalia Zuñiga-García – [nzuniga@utexas.edu](mailto:nzuniga@utexas.edu)

Andre Smit, Ph.D. – [asmit@utexas.edu](mailto:asmit@utexas.edu)

Jorge A. Prozzi, Ph.D. – [prozzi@utexas.edu](mailto:prozzi@utexas.edu)

Cite as:

Zuniga-Garcia, N., W. Martinez-Alonso, A. de Fortier Smit, F. Hong, and J.A. Prozzi. (2018). Economic Analysis of Pavement Preservation Techniques. *Transportation Research Record*, 2672(12), 10–19. <https://doi.org/10.1177/0361198118768515>.



# Presentation Outline

- Introduction
- Case Study
- Life-Cycle Cost Analysis
- Conclusions



# Introduction

## Objective

- Develop a probabilistic life-cycle cost analysis framework to evaluate and compare pavement maintenance treatments
- Study the effect of facility type, as well as traffic volume and loads

## Justification

- Timely maintenance
- Hardly any data
- Methodology to quantify the benefits

## Assumptions

- Same treatment
- Pavement condition




# Introduction

## Pavement Preservation

1. Routine maintenance
2. Preventive maintenance
3. Minor rehabilitation

## Preventive Maintenance

- Chip Seal
- Microsurfacing
- Thin Overlay





# Chip Seal

- Improve surface friction
- Reduce permeability
- Seal small cracks
- Used as a wearing course




Dave Hein


Power broom  
or sweeper




Rubber-tired  
rollers



Cover aggregate



Self-propelled  
aggregate spreader



Asphalt  
distributor






# Microsurfacing

- Improve surface friction
- Reduce permeability
- Correct surface irregularities
- Prevent raveling



<http://www.genevarock.com/>






# Thin Overlays

Less than 2 in. of hot mix asphalt (HMA).

- Improve surface friction
- Reduce permeability
- Correct surface irregularities



<http://www.pavementinteractive.org/>





# Case Study: Database

- Design and Construction Information System (DCIS)
- 14,372 PM treatment projects from 1994 to 2015
- PM treatments: chip seal, microsurfacing and thin overlays
- Censored and uncensored data


## Traffic Information of Projects

- Pavement Management Information Systems (PMIS) Database




# Case Study: Effective Life

Effective life: life between two consecutive treatments applications.






# Case Study: Cost




# Life-Cycle Cost Analysis

- Consecutive application of PM treatment
- Probabilistic approach: net present value





# Life-Cycle Cost Analysis





# Cost Probabilities

Probability that	is more cost-effective than	(%)
Chip Seal	Microsurfacing	70
Chip Seal	Thin Overlay	85
Microsurfacing	Thin Overlay	75




# Life-Cycle Cost Analysis

- Facility type:
  - Interstate Highways (IH)
  - US Highways (US)
  - State Highways (SH)
  - Farm to Market Highways (FM)
- Traffic volume: Annual Average Daily Traffic (AADT)
- Traffic load: Equivalent Single Axle Load (ESAL)




# Effect of Facility Type






# Effect of Traffic Volume





# Effect of Traffic Loads





# Conclusions

- Based on actual data
- Chip Seal emerges as most cost-effective PM treatment
- Microsurfacing for higher traffic volumes
- Thin overlay use evaluated in a case-by-case basis
- Include other variables such as climate, district practices, materials type and pavement condition



# Thank you!

## Any questions?

[wilfrido.martinez@utexas.edu](mailto:wilfrido.martinez@utexas.edu)