
DTC	13	EVAPORATOR TEMPERATURE SENSOR CIRCUIT

CIRCUIT DESCRIPTION

This sensor detects the temperature inside the cooling unit and sends the appropriate signals to the A/C amplifier.


DTC No.	Detection Item	Trouble Area	
13	Open or short in evaporator temperature sensor circuit.	Evaporator temperature sensor Harness or connector between evaporator temperature sensor and A/C amplifier A/C amplifier	


WIRING DIAGRAM



INSPECTION PROCEDURE

1 INSPECT HEATER CONTROL HOUSING SUB-ASSY(TE, SG)





- (a) Remove A/C amplifier with connector.
- (b) Turn the ignition switch to the ON position.
- (c) 1MZ-FE:

Measure voltage according to the value(s) in the table below.

Standard

Terminal No.	Condition	Specified Condition
A13-23 (TE) - A13-21 (SG)	at 25°C (77°F)	2.0 to 2.4 V
A13-23 (TE) - A13-21 (SG)	at 40°C (104°F)	1.4 to 1.8 V

HINT:

As the temperature increases, the voltage decreases.

(d) 2AZ-FE:

Measure voltage according to the value(s) in the table below.

Standard

Terminal No.	Condition	Specified Condition
A39-5 (TE) - A39-20 (SG-TE)	at 25°C (77°F)	2.0 to 2.4 V
A39-5 (TE) - A39-20 (SG-TE)	at 40°C (104°F)	1.4 to 1.8 V

HINT:

As the temperature increases, the voltage decreases.

А	NG
В	OK (when checking from the PROBLEM SYMPTOM TABLE)
С	OK (Checking from the DTC)

в`


PROCEED TO NEXT CIRCUIT INSPECTION SHOWN IN PROBLEM SYMPTOMS TABLE

С

CHECK AND REPLACE HEATER CONTROL HOUSING SUB-ASSY

Α

2 INSPECT COOLER THERMISTOR NO.1



- (a) Remove cooler thermistor No.1.
- (b) Check resistance between terminals 1 and 2 of cooler thermistor No.1 at each temperature, as shown in the chart.

Standard:


Tester connection	Condition	Specified condition
A16-1 - A16-2	–10°C (14°F)	8.00 to 10.00 kΩ
A16-1 - A16-2	−5°C (23°F)	6.15 to 7.65 kΩ
A16-1 - A16-2	0°C (32°F)	4.75 to 5.85 kΩ
A16-1 - A16-2	5°C (41°F)	3.70 to 4.55 kΩ
A16-1 - A16-2	10°C (50°F)	2.91 to 3.55 kΩ
A16-1 - A16-2	15°C (59°F)	2.32 to 2.80 kΩ
A16-1 - A16-2	20°C (68°F)	1.85 to 2.22 kΩ
A16-1 - A16-2	25°C (77°F)	1.48 to 1.77 kΩ
A16-1 - A16-2	30°C (86°F)	1.20 to 1.43 kΩ

NOTICE:

Even slightly touching the sensor may change the resistance value.Be sure to hold the connector of the sensor.

HINT:

As the temperature increases, the resistance decreases (see the chart below).



NG > REPLACE COOLER THERMISTOR NO.1

3 CHECK HARNESS AND CONNECTOR(COOLER THERMISTOR NO.1 – HEATER CONTROL HOUSING SUB-ASSY)

NG REPAIR OR REPLACE HARNESS OR CONNECTOR

OK

CHECK AND REPLACE HEATER CONTROL HOUSING SUB-ASSY