ROUTE CANNOT BE CALCULATED

INSPECTION PROCEDURE

1	CHECK THE MAP DISC

I38584

(a) Check that the map disc is not deformed or cracked.
Standard: No deformations or cracks appear on the map disc.

NG ▷ | REPLACE THE MAP DISC |

OK

2	SET DESTINATION

(a) Set another destination and check if the system can calculate the route correctly.
Standard: Route can be correctly calculated.

OK ▷ | NORMAL OPERATION |

NG

| PROCEED TO NEXT CIRCUIT INSPECTION SHOWN IN PROBLEM SYMPTOMS TABLE (SEE PAGE 05−46) |