

ROOFING PROPOSAL

Roof Replacement — Smith Residence, Pataua South

Prepared for Smith Residence · 14 Pataua South Rd, Whangarei

REFERENCE
FR-2026-051

PREPARED
22 May 2026

VALID
30 days

FLOOD ROOFING · AT A GLANCE

YEARS ON TOOLS
15+
Owner-operated

MAXAM WARRANTY
25 yr
Backed by NZ Steel

WORKMANSHIP
10 yr
Every roof installed

LICENSED BUILDING
LBP
NZ certified

Flood Roofing is a Northland-based roofing specialist established in 2016. Owner Aron Flood has 15+ years on the tools — from high-end architectural homes through to large commercial re-roofs — and only hires the best team along the way. We install premium NZ-made Colorsteel® Maxam and Endura products only, and back every roof with a written 10-year workmanship warranty.



Premium NZ materials

Colorsteel® Maxam, Endura and top-tier NZ Steel products only.



15+ years on the tools

Every job supervised on-site by an experienced lead roofer.



10-yr workmanship

Written warranty on every roof, in addition to manufacturer cover.



LBP & insured

Licensed Building Practitioner. PL + contract works insured.

OUR TEAM STRUCTURE



Owner / Project Lead

Aron Flood

Quoting, site supervision, sign-off



Lead Roofer

Sam Whittaker

On-site lead, installation, QC



Roofers (x2)

Jase + Mason

Strip-out + install crew



Apprentice

Tane Mahuta

Materials handling, supervised work


The existing roof is original ~1995 Colorsteel corrugate showing significant paint film failure on the north and west faces, with rust beginning at fixing points. Ridge cap is flat-bar fixed (now superseded) and has lifted in three places on the western run. Spouting on the south elevation is sagging and undersized for the catchment. We recommend a full strip-and-replace rather than overcoat — the underlying steel has begun to perforate in isolated areas.

OBSERVATIONS

- Paint film failure 60-70% on north + west faces (chalk + flake)
- Surface rust at all fixing points, perforation starting at 4 fixings
- Ridge cap lifted in 3 locations — flat-bar fixings outdated
- Underlay has degraded (visible from inside ceiling space)
- 6m of south-elevation spouting sagging; downpipe undersized
- No identified asbestos products in the existing roof structure


SITE PHOTOS

Site overview



Site overview

Existing ridge cap



Existing ridge cap — flat-bar fixings


Upload site photo here


Upload site photo here


Upload site photo here


Upload site photo here

OPTION A

Standard Re-Roof — Colorsteel® Endura

Strip and replace using NZ Steel's standard Endura corrugate — proven NZ-made pre-painted steel with a 15-year manufacturer's warranty.

TOTAL INCL. GST

\$20,297.50

Sub \$17,650.00 · GST \$2,647.50

✔ WHAT'S INCLUDED

- ✔ Strip existing roof + safe disposal
- ✔ Install Endura corrugated sheet (0.55mm)
- ✔ New ridge, apron, and barge flashings
- ✔ Re-flash 1× chimney + 2× pipe penetrations
- ✔ Underlay (foil + breathable)
- ✔ Site clean-up + magnet sweep

🔗 ITEMISED PRICING

DESCRIPTION	QTY	UNIT	TOTAL
Endura corrugate sheet (0.55mm)	78	\$78.50	\$6,123.00
Ridge & apron flashings — Endura	32	\$36.00	\$1,152.00
Underlay + barge fixings	1	\$1,240.00	\$1,240.00
Penetrations + chimney flashing kit	3	\$285.00	\$855.00
Labour — strip, install, sign-off	1	\$7,800.00	\$7,800.00
Skip hire + disposal	1	\$480.00	\$480.00
Total incl. GST			\$20,297.50

OPTIONAL UPGRADES

Upgrade to 0.55mm Heavy-duty fixings — Stainless tek screws + EPDM washers throughout. Recommended on coastal sites.

+\$437.00

OPTION B

Premium Maxam Re-Roof — coastal-grade

Upgraded to Colorsteel® Maxam — thicker zinc-aluminium coating and a tougher paint film, engineered for Severe Marine zones. Best long-term value within 100m of the surf.

TOTAL INCL. GST

\$23,362.48

Sub \$20,315.20 · GST \$3,047.28

✔ WHAT'S INCLUDED

- ✔ Strip existing roof + safe disposal
- ✔ Install Maxam corrugated sheet (0.55mm)
- ✔ Stainless screws + EPDM washers
- ✔ Maxam ridge, apron, barge & gutter flashings
- ✔ Re-flash 1× chimney + 2× pipe penetrations
- ✔ Premium foil + breathable underlay
- ✔ Annual wash-down reminder service

🔗 ITEMISED PRICING

DESCRIPTION	QTY	UNIT	TOTAL
Maxam corrugate sheet (0.55mm)	78	\$92.40	\$7,207.20
Maxam ridge & apron flashings	32	\$44.00	\$1,408.00
Stainless tek screws + EPDM washers	1	\$620.00	\$620.00
Underlay + barge fixings	1	\$1,240.00	\$1,240.00
Penetrations + chimney flashing kit	3	\$320.00	\$960.00
Labour — strip, install, sign-off	1	\$8,400.00	\$8,400.00
Skip hire + disposal	1	\$480.00	\$480.00
Total incl. GST			\$23,362.48

OPTIONAL UPGRADES

Re-line existing spouting in Maxam — Replace 6m of south-elevation spouting in matching Maxam colour.

+\$814.20

PREMIUM NZ-MADE STEEL

Colorsteel® Endura & Maxam

Colorsteel® is NZ Steel's pre-painted roofing and cladding range — manufactured in Glenbrook from New Zealand iron sand. **Endura** is the standard grade (AZ150 substrate, 15-year paint film warranty), **Maxam** is the premium coastal grade (AZ200 substrate, 25-year severe-marine perforation cover). Both come in the same recognisable Colorsteel® colour family.

MANUFACTURER'S WARRANTY

Up to 25 years*

Maxam: 25-yr perforation in Severe Marine. Endura: 15-yr in Marine zone. Paint film & weather-side cover included. *Subject to NZ Steel published exposure zones & install / wash requirements.

WHY COLORSTEEL?

- **Made in NZ** for NZ conditions
- **Galvalloy® coating** — zinc-aluminium alloy substrate
- **Baked enamel paint** — UV-stable for decades
- **Transferable warranty** to next owner
- **Profiles** — Corrugate, Trimrib, T-Rib, Five-Rib, Standing Seam

ENDURA VS MAXAM


	Endura AZ150	Maxam AZ200
Substrate		
Severe Marine	N/A	25 yr
Marine zone	20 yr	30 yr
Paint film	12 yr	15 yr

STANDARD COLORSTEEL® COLOURS



Approximate colour rendering — final selection from NZ Steel's physical Colorsteel® chip card.

RECENT COLORSTEEL PROJECTS



Marley is New Zealand's most-installed PVC spouting brand — UV-stabilised, light, doesn't corrode, won't dent in hail. Choice of profile suits both modern and heritage homes. A **15-year manufacturer's warranty** on the spouting, downpipes and fittings.

 AVAILABLE PROFILES



Marley Stratus Design®

Modern square-front profile, 125mm width — most popular new-build choice.




Marley Stratus Classic®

Rounded shoulders, 125mm — softens architectural lines, great on heritage homes.



Marley Typhoon®

High-capacity 145mm — engineered for steep roofs / large catchments.



Marley Magnum®


Deep 150mm rectangular — maximum flow rate, commercial-grade.




Marley RP80®

Compact 80mm rectangular — sheds, garages, low-flow applications.

 MARLEY COLOUR PALETTE




White



Black




Karaka




Ironsand



Titanium




Grey Friars®



New Denim Blue®



Permanent Green®




Sandstone Grey®



Pioneer Red®



Lichen®



Slate®

Marley range matches the Colorsteel® colour family — easy match to your new roof. White and Black are universal stock colours; coloured profiles are made-to-order.

Continuous spouting — also called *seamless* — is rolled on-site from coil-stock Colorsteel® in 0.55bmt steel. No factory joins, far stiffer than PVC, and finished in the same Colorsteel® colour family as your roof. Made by Roofing Industries (Whangarei) for our Northland jobs. **15-year paint film warranty** on top of the substrate cover.

AVAILABLE PROFILES



Continuous Quad
Square-fronted, the New Zealand standard — bold lines, sharp edges.



Smoothline
Internal bracketing for a fully concealed look — modern architectural choice.



Half Round
Traditional rounded profile — heritage homes, country cottages.




Box Gutter
Deep capacity gutter, often used internally / behind parapets on commercial roofs.




Colonial Quad
Ogee-shouldered profile — period properties, character villas.


MATCHED TO YOUR ROOF — COLORSTEEL® COLOUR RANGE



Ironsand®



FlaxPod®




Lignite®




Karaka®




Grey Friars®




Sandstone Grey®




Windsor Grey®



Titania®




New Denim Blue®



Permanent Green®



Mist Green®



Ebony®

 **Coastal-grade**
AZ150 / AZ200 Galvalloy® substrate stands up to salt spray.

 **Stiffer profile**
Steel doesn't sag like PVC — long runs without intermediate sag.

 **Matches the roof**
Same Colorsteel® colour family — fully coordinated finish.

ROOF AREA

148.6

square metres

PITCH

22°

degrees

SHEETS


78

corrugated

ON-SITE

8 days

estimated duration



- SCOPE SUMMARY
- Strip existing corrugated steel roof + dispose to landfill
 - Inspect, replace damaged purlins (PC sum allowed)
 - Install new Maxam corrugate, all flashings, ridge caps
 - Re-flash chimney + 2x plumbing vents
 - 6m of new spouting on the south elevation

PROJECT TIMELINE (8 WORKING DAYS ON-SITE)



ESTIMATED START DATE

Mid-June 2026 (week of 15 June)

Subject to deposit clearance, materials supply and weather. We'll confirm the start date in writing once the deposit is paid.

- WHAT YOU DO
- Sign & return acceptance page
 - Pay 25% deposit — locks in start
 - Clear roof access (gardens, vehicles)
 - Pick your colour from page 5

1. Quote validity

This quote is valid for 30 days from the date issued. After that date materials and labour rates may be re-quoted.

2. Acceptance

The contract is formed when the client signs the acceptance page (or confirms in writing) AND the 25% deposit has cleared into our account. Verbal acceptance does not bind either party.

3. Materials & products

All materials are NZ-made unless explicitly noted. Colorsteel® Endura/Maxam carry NZ Steel's manufacturer warranty. Marley spouting carries Marley's 15-year warranty. Manufacturer documentation handed over at sign-off.

4. Workmanship warranty

We warrant the workmanship of the installed roof for 10 years from the date of practical completion. This covers fixing, lapping, flashing penetration of weather. It does not cover: damage by other trades, modifications by others, storm or impact damage, or normal wear of paint film (covered separately by manufacturer).

5. Payment terms

25% deposit on acceptance (materials ordered). 50% progress payment due on completion of roof and gutters. 25% final due on practical completion. Invoices payable by the 20th of the month following invoice date. 2.5% per month interest applies to overdue balances. We reserve the right to suspend work for non-payment.

6. Variations & provisional sums

Any change to the agreed scope must be authorised in writing (email is fine). Variations are billed at quoted rates or current trade rates if not pre-quoted. Provisional Cost (PC) items — typically rotten battens or hidden flashings — are charged at cost + 15% on inspection during strip-out.

7. Hidden defects / latent conditions

The quote is based on visible roof condition only. Concealed defects (rotten purlins, asbestos sheeting, structural sag, etc.) discovered during strip-out will be raised with the client immediately, priced, and treated as a variation.

8. Weather & programme

Outdoor roofing work is weather-dependent. Heavy rain or sustained high winds (over 40 km/h) will halt work for safety. We will catch the building up overnight if a strip is incomplete. Re-scheduled days do not attract additional cost unless the client cancels access.

9. Site access & health and safety

Client to provide reasonable site access, water and power. We follow WorkSafe / SiteSafe procedures including edge protection, harness anchors and exclusion zones. Children, pets and visitors must stay out of the active work zone. The client is responsible for moving valuable garden items / parked vehicles clear of the building line.

10. Insurance

We carry \$2 million Public Liability + Contract Works insurance. Sub-trades engaged by us carry their own insurance. Client's building insurance must remain in force during the work.

11. Waste & disposal

All stripped roofing, underlay and packaging is removed from site and disposed of legally. Old metal is recycled where possible. Client may keep salvaged sheets on request, advised before strip-out.

12. Ownership of materials

Title in materials remains with us until paid for in full. Materials installed before payment may be removed at our cost in the event of cancellation, subject to the Construction Contracts Act 2002.

13. Cancellation

Cancellation after deposit but before materials ordered: deposit refunded less a \$250 admin fee. Cancellation after materials are ordered: client pays for all materials ordered + 10% restocking fee where applicable. Cancellation after work has commenced: client pays for all work done to date + materials.

14. Photographs

We typically take before/during/after photographs for our records. We may use anonymised photographs for marketing (website, social media). Tell us in writing if you don't want photos used externally.

15. Dispute resolution

Any dispute will first be raised in writing and we will attempt to resolve it within 14 days. Unresolved disputes go to mediation under the Construction Contracts Act 2002. Disputes governed by New Zealand law, jurisdiction Whangarei District Court.

16. GST

All prices in this quote are exclusive of GST unless explicitly marked "incl. GST". 15% GST is added at invoice. We are GST-registered.

STAGE 1 25% Deposit Materials ordered	STAGE 2 50% Progress Roof & gutters complete	STAGE 3 25% Final Practical completion
---	--	--

I, **Smith Residence**, accept the option(s) ticked above and the terms set out in this proposal. Total payable will be confirmed in the variation invoice once option / upgrade selections are finalised.

Client signature

Date (22 May 2026)

FLOOD ROOFING representative

Date