



Vision Property Inspections
2029 N Main St Suite 103
Sunset, UT 84015
VisionPropertyInspections@Gmail.com

Property Inspection Report

Client Name Tysen and Chantel Gough

Address of Inspection 1428 Ridgeline Dr
Ogden, UT 84403, NH

Date of Inspection 09/28/2026

Real Estate Agent Cyndi Farrais

Name of Inspector Jeremy K. Heath **License #** FL-HI9921



This inspection report is the property of
Vision Property Inspections.
Any reproduction or distribution without
written consent is prohibited.

PROPERTY INSPECTION REPORT FORM

Name of Client

Tysen and Chantel Gough

Date of Inspection

09/28/2026

Address of Inspected Property

1428 Ridgeline Dr, Ogden, UT 84403, NH

Name of Inspector

Jeremy K. Heath

TREC License #

FL-HI9921

Name of Sponsor (if applicable)

TREC License #

PURPOSE OF INSPECTION

A real estate inspection is a visual survey of a structure and a basic performance evaluation of the systems and components of a building. It provides information regarding the general condition of a residence at the time the inspection was conducted. It is important that you carefully read ALL of this information. Ask the inspector to clarify any items or comments that are unclear.

RESPONSIBILITY OF THE INSPECTOR

This inspection is governed by the Texas Real Estate Commission (TREC) Standards of Practice (SOPs), which dictates the minimum requirements for a real estate inspection.

The inspector IS required to:

- use this Property Inspection Report form for the inspection;
- inspect only those components and conditions that are present, visible, and accessible at the time of the inspection;
- indicate whether each item was inspected, not inspected, or not present;
- indicate an item as Deficient (D) if a condition exists that adversely and materially affects the performance of a system or component OR constitutes a hazard to life, limb or property as specified by the SOPs; and
- explain the inspector's findings in the corresponding section in the body of the report form.

The inspector IS NOT required to:

- identify all potential hazards;
- turn on decommissioned equipment, systems, utilities, or apply an open flame or light a pilot to operate any appliance;
- climb over obstacles, move furnishings or stored items;
- prioritize or emphasize the importance of one deficiency over another;
- provide follow-up services to verify that proper repairs have been made; or
- inspect system or component listed under the optional section of the SOPs (22 TAC 535.233).

RESPONSIBILITY OF THE CLIENT

While items identified as Deficient (D) in an inspection report DO NOT obligate any party to make repairs or take other actions, in the event that any further evaluations are needed, it is the responsibility of the client to obtain further evaluations and/or cost estimates from qualified service professionals regarding any items reported as Deficient (D). It is recommended that any further evaluations and/or cost estimates take place prior to the expiration of any contractual time limitations, such as option periods.

Please Note: Evaluations performed by service professionals in response to items reported as Deficient (D) on the report may lead to the discovery of additional deficiencies that were not present, visible, or accessible at the time of the inspection. Any repairs made after the date of the inspection may render information contained in this report obsolete or invalid.

REPORT LIMITATIONS

This report is provided for the benefit of the named client and is based on observations made by the named inspector on the date the inspection was performed (indicated above). ONLY those items specifically noted as being inspected on the report were inspected. This inspection IS NOT:

- a technically exhaustive inspection of the structure, its systems, or its components and may not reveal all deficiencies;
- an inspection to verify compliance with any building codes;
- an inspection to verify compliance with manufacturer's installation instructions for any system or component and DOES NOT imply insurability or warrantability of the structure or its components.

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

LANDSCAPING

				Fence Type: Reviewed
				Front Gate: Concerns
				Other Gate: Reviewed
				Grading: Reviewed
				Landscaping: Reviewed
				Vegetation: Reviewed
				Water Feature: Reviewed
				Brush Fire Defensible Space: Reviewed
				Surface Drainage: Reviewed
				Wall: Reviewed
				Retaining Wall: Reviewed
				Driveway: Reviewed
				Walk Ways: Reviewed
				Bushes: Reviewed
				Trees: Reviewed
				Electrical Receptacles: Reviewed
				Sprinkler System: Reviewed
				Comments:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

ROOF

				Did the inspector walk the roof?: Yes Reason (if not walked): Roof Type: Roof Material: Parapet: Saddles Condition: Roof Install Workmanship: Roof Age: Chimney: Cricket in Place: Roof Penetrations: Roof Vents: Sky Light: Roof Flashing: Ice Dam Potential Areas: Fascia: Dormer(s): Tree in Contact: Moss / Mold or Mildew: Swamp Cooler: Solar Panels: Comments:
--	--	--	--	---

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

EXTERIOR WALLS

				Siding Material: Reviewed
				Soffits: Reviewed
				Trim: Reviewed
				Rain Gutters: Reviewed
				Water Down Spouts: Reviewed
				Windows: Reviewed
				Lintels: Reviewed
				Concrete Sidewalk: Reviewed
				Front Steps: Reviewed
				Front Porch: Reviewed
				Doorbell: Reviewed
				Exterior Doors: Reviewed
				Chimney: Reviewed
				Foundation Type: Reviewed
				Exterior Foundation: Reviewed
				Dryer Exhaust Vent: Reviewed
				Hose Bib(s): Reviewed
				Lighting: Reviewed
				Electrical Receptacles: Reviewed
				Mail Box: Reviewed
				Comments:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

OUTSIDE UTILITIES

				Cooling System Cooling system: Swamp Cooler Podium: Vegetation: Fan: Fins: Coolant Lines: Cut Off: Compressor Size: Comments:
				Electricity Electric meter condition: Meter & brackets secure: Electric Service: Electric Service Drop: Power Cut Off: Over-current Protection: AMP Rating: Solar Panel Breakers: Comments:
				Natural Gas Gas Meter: Gas Cut Off: Comments:
				Water Water Meter: Rain Water Collection: Comments:
				Sewer Outdoor Sewer Access: Sewer Main: Sewer: Comments:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

DECK

				Deck Size:
				Deck Material:
				Awning:
				Railing:
				Steps:
				Posts:
				Beams:
				Header / Ledger:
				Flashing:
				Skirt:
				Under-Deck Storage:
				Ground Surface:
				Under-Deck Drainage:
				Any Sign of Pests:
				Electrical Receptacles:
				Comments:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

GARAGE

				Garage type: None
				Foundation Type: Reviewed
				Roof Type: Reviewed
				Exterior Walls: Reviewed
				Electrical: Reviewed
				Hose Bib(s): Reviewed
				Door(s): Reviewed
				Floor Surfacing: Reviewed
				Visible Foundation: Reviewed
				Trusses: Reviewed
				Connector Plates: Reviewed
				Ceiling: Reviewed
				Attic (secondary): Reviewed
				Windows: Reviewed
				Thermal Imaging: Reviewed
				Garage Door(s): Reviewed
				Lintels: Reviewed
				Interior Walls: Reviewed
				Lighting: Reviewed
				Wiring Type: Reviewed
				Electrical Receptacles: Reviewed
				EV Charging: Reviewed
				Mold: Reviewed
				Heated: Reviewed
				Comments:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

ATTIC

				Access:
				Access Structure:
				Roof Sheathing:
				Plumbing Vents:
				Trusses:
				Connector Plates:
				Ventilation:
				Insulation:
				Chimney Area:
				Lighting:
				Wiring:
				Wiring Connections:
				Electrical Receptacles:
				Mildew Present:
				Signs of Pests:
				Thermal Imaging:
				Comments:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

BATHROOM 1

				Type: Level: Remodel: Door(s): Ceiling: Floor: Sub Floor: Interior Walls: Windows: Thermal Anomalies: Counters: Sink: Plumbing: Bathtub / Shower: Toilet: Lighting: Electrical Receptacles: Ventilation: HVAC: Comments:
--	--	--	--	---

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

BATHROOM 2

				Type: Level: Remodel: Door(s): Ceiling: Floor: Sub Floor: Interior Walls: Windows: Thermal Anomalies: Counters: Sink: Plumbing: Bathtub / Shower: Toilet: Lighting: Electrical Receptacles: Ventilation: HVAC: Comments:
--	--	--	--	---

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

BATHROOM 3

				Type: Level: Remodel: Door(s): Ceiling: Floor: Sub Floor: Interior Walls: Windows: Thermal Anomalies: Counters: Sink: Plumbing: Bathtub / Shower: Toilet: Lighting: Electrical Receptacles: Ventilation: HVAC: Comments:
--	--	--	--	---

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

BEDROOM 1

				Type: Master Bed Level: Main Floor Door(s): Reviewed Ceiling: Reviewed Floor: Reviewed Sub Floor: Reviewed Interior Walls: Reviewed Windows: Reviewed Thermal Anomalies: Reviewed Closet: Reviewed Lighting: Reviewed Shelves: Reviewed Electrical Receptacles: Reviewed Ceiling Fan: Reviewed HVAC: Reviewed Thermostat: Reviewed Alarms: Reviewed Comments:
--	--	--	--	--

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

BEDROOM 2

				Type: Level: Door(s): Ceiling: Floor: Sub Floor: Interior Walls: Windows: Thermal Anomalies: Closet: Lighting: Shelves: Electrical Receptacles: Ceiling Fan: HVAC: Thermostat: Alarms: Comments:
--	--	--	--	---

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

BEDROOM 3

				Type: Level: Door(s): Ceiling: Floor: Sub Floor: Interior Walls: Windows: Thermal Anomalies: Closet: Lighting: Shelves: Electrical Receptacles: Ceiling Fan: HVAC: Thermostat: Alarms: Comments:
--	--	--	--	---

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

BEDROOM 4

				Type: Level: Door(s): Ceiling: Floor: Sub Floor: Interior Walls: Windows: Thermal Anomalies: Closet: Lighting: Shelves: Electrical Receptacles: Ceiling Fan: HVAC: Thermostat: Alarms: Comments:
--	--	--	--	---

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

HALLWAY 1

				Level:
				Door(s):
				Ceiling:
				Floor:
				Sub Floor:
				Interior Walls:
				Windows:
				Thermal Anomalies:
				Closet:
				Lighting:
				Shelves:
				Electrical Receptacles:
				Ceiling Fan:
				HVAC:
				Alarms:
				Comments:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

HALLWAY 2

				Level:
				Door(s):
				Ceiling:
				Floor:
				Sub Floor:
				Interior Walls:
				Windows:
				Thermal Anomalies:
				Closet:
				Lighting:
				Shelves:
				Electrical Receptacles:
				Ceiling Fan:
				HVAC:
				Alarms:
				Comments:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

LIVING ROOM

				Door(s): Reviewed
				Ceiling: Reviewed
				Floor: Reviewed
				Sub Floor: Reviewed
				Stairways: Reviewed
				Railing: Reviewed
				Interior Walls: Reviewed
				Windows: Reviewed
				Thermal Anomalies: Reviewed
				Lighting: Reviewed
				Electrical Receptacles: Reviewed
				Ceiling Fans: Reviewed
				Fireplace: Reviewed
				HVAC: Reviewed
				Alarms: Reviewed
				Comments:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

DEN / HOME OFFICE

				Door(s):
				Ceiling:
				Floor:
				Sub Floor:
				Interior Walls:
				Windows:
				Thermal Anomalies:
				Lighting:
				Electrical Receptacles:
				Ceiling Fans:
				Fireplace:
				HVAC:
				Alarms:
				Comments:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

FAMILY ROOM

				Door(s):
				Ceiling:
				Floor:
				Sub Floor:
				Interior Walls:
				Windows:
				Thermal Anomalies:
				Lighting:
				Electrical Receptacles:
				Ceiling Fans:
				Fireplace:
				Kitchenette / Wet Bar:
				Counter:
				Sink:
				Plumbing:
				Refrigerator:
				HVAC:
				Alarms:
				Comments:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

KITCHEN

				Remodel: Reviewed
				Door(s): Reviewed
				Ceiling: Reviewed
				Floor: Reviewed
				Sub Floor: Reviewed
				Interior Walls: Reviewed
				Windows: Reviewed
				Thermal Anomalies: Reviewed
				Counters: Reviewed
				Cupboards: Reviewed
				Cabinets: Reviewed
				Island: Reviewed
				Pantry: Reviewed
				Sink: Reviewed
				Plumbing: Reviewed
				Dishwasher: Reviewed
				Stove & Oven: Reviewed
				Exhaust Hood: Reviewed
				Refrigerator: Reviewed
				Lighting: Reviewed
				Electrical Receptacles: Reviewed
				HVAC: Reviewed
				Comments:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

DINING ROOM

				Door(s):
				Ceiling:
				Floor:
				Sub Floor:
				Interior Walls:
				Windows:
				Lintels:
				Thermal Anomalies:
				Lighting:
				Electrical Receptacles:
				Ceiling Fans:
				Fireplace:
				HVAC:
				Alarms:
				Comments:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

LAUNDRY ROOM

				Location:
				Door(s):
				Ceiling:
				Floor:
				Sub Floor:
				Interior Walls:
				Windows:
				Thermal Anomalies:
				Lighting:
				Electrical Receptacles:
				Ventilation:
				Sink:
				Plumbing:
				Cabinets:
				Counters:
				Washer Hook-ups:
				Hot Connection:
				Cold Connection:
				Drain Line:
				Pan:
				Floor Drain:
				Dryer:
				HVAC:
				Alarms:
				Comments:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

STORAGE ROOM

				Door(s):
				Ceiling:
				Floor:
				Sub Floor:
				Interior Walls:
				Windows:
				Thermal Anomalies:
				Lighting:
				Electrical Receptacles:
				Shelves:
				Signs of Pests:
				Mildew Present:
				HVAC:
				Stairs:
				Alarms:
				Comments:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

UTILITY ROOM

--	--	--	--

Contents:
Condition: Concerns
Ventilation:
Electrical Receptacles:
Lighting:
Comments:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

ELECTRICAL

				Panel: Primary Panel Wiring type: Any hot breakers: Breakers in good repair: Breakers labeled: Empty slots covered: Any double taps: Wires with broken / stripped insulation: Any charred / cracking areas: Amp load: Panel brand: Panel recalled: Alarms: Comments:
--	--	--	--	---

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

HVAC MECHANICAL

				Furnace type:
				Location:
				Heating operation:
				Gas Valve:
				Gas Line:
				Intake:
				Venting:
				Ductwork:
				Flame Color:
				Combustion Chamber:
				Computer Board:
				Air Filter Access:
				Thermostat type:
				Cooling system:
				Cooling operates normally:
				Any abnormal sounds:
				Condensation tube in place:
				Comments:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

WATER HEATER

				Number of units:
				Fuel:
				Type:
				Capacity:
				Pilot:
				Staining / rust on tank:
				Tank leaking:
				Gas valve:
				Gas line:
				Securing straps in place:
				Expansion tank:
				Pressure relief valve:
				Relief pipe terminates 6" from floor:
				Venting:
				Comments:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

PLUMBING

				Distribution system: Pipe type: Water main valve: Reverse flow preventer in place: Sewer outflow pipe: Sewer cleanout: Any corrosion visible: Any leaking visible: Water softener: Hydronic floor heating: Comments:
--	--	--	--	--

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

FOUNDATION / CRAWL SPACE

				Foundation visibility: <10% Water infiltration present: Mold or mildew: Foundation Type: Exterior Foundation: Basement: Crawl Space: Floor Joists: Sub Floor: Underside of Subfloor: Vapor Barrier in Place: Sump Pump & Pit: Any Pests / Mud Tubes: Ventilation: Alarms: Comments:
--	--	--	--	--

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

RADON

--	--	--	--

Test performed:
Date of testing:
Time of testing:
Measured level (pCi/L):
Comments:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

THERMAL AUDIT

				Scan performed: Comments:
				Areas scanned Outside HVAC compressor: Front of house: Back of house: Living room: Kitchen: Bathrooms: Water heater: Inside HVAC unit: Electrical panel: Anomalies found: Comments:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

TERMITE

--	--	--	--

Areas inspected:
Insects / pests observed:
Findings:
Evidence type:
Comments:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I	NI	NP	D
---	----	----	---

CHIMNEY

				Material (outside): Chimney is plumb: Properly attached to structure: Condition: Crown condition: Clearance: Rain caps: Flue lining: Flue condition: Flashing type: Mantle (inside): Doors: Lintel over firebox: Damper: Comments:
--	--	--	--	--



Pictures




Roof · North Side




Roof · North Side — Recommend further evaluation by a qualified professional



Landscaping · Front Yard



Landscaping · Concerns — Safety concern - address immediately



Exterior Walls · Front



Exterior Walls · Left Side



Pictures (continued)



Kitchen · General Area



Roof · North Side

Summary of Findings

Findings grouped by category

1

Category 1 · Safety

Address before closing

4

- 1** No power to exterior receptacle — wiring damaged at housing (back of property). (Landscaping)
- 2** Tree branches in contact with the structure. (Landscaping)
- 3** Front Gate: Latch does not catch (Landscaping)
- 4** Rail required for stairs down to basement back door. (Exterior Walls)

2

Category 2 · Functional

Address in the first few months after closing

2

- 1** No diverter; water going into foundation causing settling. (Roof)
- 2** Section of concrete is lifting — trip hazard. (Exterior Walls)

3

Category 3 · Items to monitor

Monitor and address over time

1

- 1** Residue of ivy on the front of the house. (Exterior Walls)