PENETRATION TESTING REPORT

FOOTPRINTING & NETWORK SCANNING PHASES

W2-PM-FINAL | CYBERSECURITY | NETWORKWALKS

Pentester Name (Cybersecurity Professional)	Abdulkadiri Adaranijo
Program / Batch	B084 - Networkwalks
Report Date	11 November 2026
Modules Completed	W2-PM1 - Footprinting with multiple Kali tools W2-PM2 - Footprinting with the Google Hacking Database (GHDB) W2-PM3 - Footprinting with Maltego W2-PM4 - Footprinting with theHarvester W2-PM5 - Network scanning with Zenmap
Client / Target	1. Networkwalks - networkwalks.com (letter of authorization held) 2. microsoft.com - lab-designated public example (passive OSINT only) 3. Publicly indexed internet-exposed devices and directories (passive viewing) 4. My own local LAN network
Permission secured from client?	Yes
Phases covered	Phase 1: Reconnaissance & Footprinting Phase 2: Scanning & Network Discovery Phase 3-5: In Progress

1. Liability Disclaimer

I performed these activities only on systems where I held written permission (networkwalks.com), on lab-designated public targets using passive methods, or on devices and networks that I own. For exercises involving third-party public information (Google Dorking and the microsoft.com OSINT lab) I only viewed publicly accessible content: I did not log in, guess credentials, control or change any device, or download third-party material. IP addresses, MAC addresses, session tokens and live camera imagery have been masked in this report.

All material is for education and research purposes only. Do not use anything from here to break the law. The instructor, the author and Networkwalks are not responsible for what you do with this knowledge; every action you take is your own responsibility. Misuse can lead to criminal charges, heavy fines, loss of your job and a permanent record. In most countries unauthorised access is a crime even when nothing is damaged.

2. Executive Summary

During Week 2 of my Cybersecurity & Ethical Hacking internship I completed five practical modules covering Phase 1 (Reconnaissance & Footprinting) and Phase 2 (Scanning & Network Discovery). No exploitation or vulnerability validation was performed; every finding is an observation that would need authorized follow-up testing to confirm.

Authorized target (networkwalks.com). Six Kali tools and a Maltego transform produced a clear picture of the public footprint: shared HostGator/cPanel hosting (192.232.216.135), a WordPress 7.1.4 site with the WP Download Manager plugin, a ModSecurity WAF, privacy-protected registration and one public role mailbox. The most notable observations are missing browser security headers, soft-fail SPF, unsigned DNSSEC and BIND version disclosure on the name servers.

Search-engine exposure (GHDB). Dorks from the Exploit-DB database surfaced ten internet-exposed camera interfaces that showed live feeds without any login, and ten open directory listings. This is the highest-rated observation in the report because it affects the privacy of real premises.

OSINT at scale (theHarvester, microsoft.com). A passive run returned 9,967 hostnames, 55 IPs and 8 ASNs with no direct contact with the target, and showed how much coverage depends on API keys (32 sources were unavailable).

Local network (Zenmap). A ping scan of my own /24 found five live hosts in 6.74 seconds, one of them using a randomized MAC address.

Result: 13 observations - 1 High, 4 Medium, 5 Low and 3 Informational. The priorities are to add security headers, tighten email authentication (SPF/DMARC/DNSSEC), keep CMS components patched, never expose cameras or directory listings directly to the internet, and keep a current inventory of devices on the network.

3. Scope, Authorization & Methodology

Module	Target	Authorization basis	Technique	Date
1	networkwalks.com	Letter of authorization from Networkwalks	Public registry lookups plus light active requests (HTTP, DNS)	8 Nov 2026
2	Publicly indexed search results (Exploit-DB GHDB, Google)	Lab-designated exercise; passive viewing only	Search-engine queries; viewing pages	8 Nov 2026
3	networkwalks.com	Letter of authorization from Networkwalks	Passive OSINT (search-engine transform in Maltego CE)	8 Nov 2026
4	microsoft.com	Lab-designated public example; public sources only	Passive OSINT with theHarvester	9 Nov 2026
5	192.168.100.0/24 (my own LAN)	Own network	Nmap ping scan via Zenmap	10 Nov 2026

Environment

Modules 1-4 ran on a Kali Linux virtual machine; Module 5 ran on a Windows PC with Zenmap installed. Tool versions as shown in the evidence: WAFW00F 2.4.2, Maltego CE 4.13.0 (Kali package, OpenJDK 11), theHarvester 4.10.1 and Nmap 7.993 (Zenmap).

Method

For each activity I ran the tool, captured the output as a numbered figure, recorded what it showed, assessed why it matters from an attacker's point of view and noted how a defender would reduce the risk. Observations are rated Critical, High, Medium, Low or Info based on likely impact if the information were abused, not on confirmed exploitability.

Conduct on third-party material (Modules 2 and 4)

- Passive viewing only: no login attempts, credential guessing, brute force, pan/tilt/zoom control, setting changes or downloads.
- No footage was recorded beyond two reference screenshots, whose thumbnails are blurred in this report. The premises shown were not identified and no owner was contacted.
- Host names and IPs of exposed devices are masked; open directories are described generically and are not linked.

4. Tools Used

Tool	Module	Purpose
Kali Linux / Windows	1-5	Operating systems used for reconnaissance and scanning
WHOIS	1	Domain registration details (registrar, dates, name servers, status)
whatweb	1	Fingerprint web technologies (server, CMS, plugins, IP, email)
nslookup	1	Resolve the domain name to its IP address
curl -I	1	Read HTTP response headers
wafw00f	1	Detect a Web Application Firewall
dnsrecon	1	Enumerate DNS records (SOA, NS, MX, A, TXT/SPF, SRV)
Exploit-DB GHDB + Google	2	Find dorks and run them to locate exposed cameras and open directories
Maltego CE	3	Graph-based OSINT; email harvesting from the target domain
theHarvester	4	Passive harvesting of hosts, IPs, ASNs, emails and URLs from public sources
Zenmap (Nmap GUI)	5	Ping scan to find live hosts; MAC addresses; topology graph
Windows CMD (ipconfig)	5	Identify local IP address, subnet mask and gateway

5. Activities Performed & Observations

5.1 Module 1 - Footprinting with Multiple Kali Tools (networkwalks.com)

Six tools were run against the authorized target, each collecting a different layer of information. All commands completed without errors.

Tool	Command	Key observations
WHOIS (Figs 1.1–1.2)	`whois networkwalks.com`	Registrar GoDaddy; created 6 Nov 2019, expires 6 Nov 2027. Registrant hidden behind a privacy proxy. Transfer, update, renew and delete locks set. DNSSEC unsigned. Name servers NS6135/NS6136.HOSTGATOR.COM, plus NS29/NS30.DOMAINCONTROL.COM in the registrar record (a delegation mismatch worth reviewing).
WhatWeb (Fig 1.3)	`whatweb networkwalks.com`	HTTP 301 to HTTPS, then 200 OK. Apache, WordPress 7.1.4, WP Download Manager 3.3.76, jQuery 3.7.1, Google Tag Manager, title “Networkwalks Academy”, IP 192.232.216.135 and the email info@networkwalks.com.
nslookup (Fig 1.4)	`nslookup networkwalks.com`	Non-authoritative answer via Google DNS (8.8.8.8): 192.232.216.135.
curl (Fig 1.5)	`curl -I https://networkwalks.com`	HTTP/2 200, server Apache. The Link header exposes the REST API (/wp-json/); caching headers x-nginx-cache and x-endurance-cache-level are visible. The cookie is Secure and HttpOnly; referrer-policy and permissions-policy are set. No HSTS, CSP, X-Frame-Options or X-Content-Type-Options header was observed.
wafw00f (Fig 1.6)	`wafw00f networkwalks.com`	Site is behind a ModSecurity (SpiderLabs) WAF, identified in 2 requests.
DNSRecon (Fig 1.7)	`dnsrecon -d networkwalks.com`	8 records. SOA/NS at HostGator (ns6135: 50.87.144.87, ns6136: 192.232.216.131), both reporting BIND 9.16.23-RH. A and MX (mail.networkwalks.com) both resolve to 192.232.216.135. SPF: `v=spf1 +a +mx +ip4:50.87.144.87 +include:websitewelcome.com ~all`. Google site-verification TXT record. Eight cPanel autodiscover SRV records. No answer to the DNSSEC query.

Analysis. Together the results show a shared HostGator/cPanel environment hosting a WordPress site and its mail on the same IP. An attacker would use this to choose tools and exploits (WordPress plugin issues), to craft convincing emails (soft-fail SPF) and to understand the shared-hosting dependency. The WAF and the registration privacy are good controls; the missing security headers and the version disclosures are the main gaps.

5.2 Module 2 - Footprinting with the Google Hacking Database (GHDB)

Objective. Use Exploit-DB’s GHDB to find Google dorks, then (1) locate ten live security-camera interfaces exposed to the internet and (2) locate ten listings that contain downloadable mathematics PDF books.

Method. On Exploit-DB’s GHDB page I searched the term `cam` (Fig 2.3), which returned dorks in the categories Various Online Devices, Pages Containing Login Portals and Files Containing Juicy Info. I ran selected dorks in Google (for example `intitle:"webcamXP" inurl:8080`, Fig 2.4) and opened the results to check whether each page was reachable without authentication. For Task 2 I used `intitle:index.of "parent directory" mathematics pdf` (Figs 2.8–2.9) and opened the listings.

Task 1 observations. All ten links were checked at the time. Eight were self-hosted webcamXP/Webcam-style servers or guest image pages that served live, multi-angle feeds with “Not logged in” shown, meaning guest access was open. Two were hosted ipcamlive.com streams that showed private premises, so they appear to be unintended exposures, although owner intent could not be verified. Screenshots were kept for two representative servers (Figs 2.5 and 2.7); the version banners (webcamXP 5 v5.9.8.7, Webcam 7 v1.5.3.0) were visible on the pages. No credentials were used or attempted.

No.	Host (masked)	Dork used	Observation
1	109.233.xxx.xxx:8080	`intitle:"webcamXP" inurl:8080`	webcamXP 5 multi-view; 7 camera tiles, live; “Not logged in” (Fig 2.5)
2	Dynamic-DNS host (hopto.org) :8080/multi.html	`intitle:"my webcamXP server!" inurl:":8080"`	Live feed, no login
3	109.164.xxx.xxx /cgi-bin/guestimage.html	`"Camera Live Image" inurl:"guestimage.html"`	Guest image page, live, no login
4	185.186.xxx.xxx:10082 /cgi-bin/guestimage.html	`"Camera Live Image" inurl:"guestimage.html"`	Guest image page, live, no login
5	173.69.xxx.xxx:9001 /cgi-bin/guestimage.html	`"Camera Live Image" inurl:"guestimage.html"`	Guest image page, live, no login
6	95.255.xxx.xxx:8080/multi.html	`intitle:webcam 7 inurl:8080 -intext:8080`	Live feed, no login
7	109.206.xxx.xxx:8080/multi.html	`intitle:webcam 7 inurl:8080 -intext:8080`	Live feed, no login
8	99.114.xxx.xxx:8080/multi.html	`"Active Webcam Page" inurl:8080`	Webcam 7; 2 camera tiles; “Not logged in” (Fig 2.7)
9	ipcamlive.com hosted stream (ID withheld)	`"Active Webcam Page" inurl:8080`	Hosted stream; private premises appeared; probable unintended exposure
10	ipcamlive.com hosted stream (ID withheld)	`"Active Webcam Page" inurl:8080`	Hosted stream; private premises appeared; probable unintended exposure

Table 2.1 - Exposed camera interfaces. No username or password was attempted for any entry. Fig 2.6 shows the Webcam 7 server surfacing through a related dork (`intitle:"Webcam" inurl:WebCam.htm`).

Task 2 observations. Ten open directory listings were opened and browsed; none was logged into and nothing was downloaded. They were indexed because directory listing was enabled with no access control. Most look intentionally public (academic and organizational resources), but one was a large library of commercial textbooks that likely involves copyright infringement. Copyright status was not verified for individual files.

No.	Host type	Content observed	Note
1	University web server	Directory of mathematics PDFs	Academic
2	Educational project site	Archive of ZIP and PDF course files	Fig 2.11
3	Personal server	Large library of mathematics textbooks (PDF, DJVU)	Likely copyrighted; not named (Fig 2.12)
4	University department page	Graduate-level mathematics materials	Academic
5	Academic software repository	Documentation PDFs	Intentionally public
6	Personal server	Mathematics book library	Not verified
7	School / education body	Curriculum and syllabus PDFs	Fig 2.10
8	University faculty page	Publications (PDF)	Academic
9	Personal site	Mathematics notes	Not verified
10	Non-profit organization site	Education resource PDFs	Not verified

Table 2.2 - Open directory listings (dork: `intitle:index.of "parent directory" mathematics pdf`). Classification is based on host name and listing content only. The full link list is held in my working notes and is intentionally not republished.

Impact. The same two weaknesses (a device or folder reachable without authentication, plus search-engine indexing) turn a private misconfiguration into something findable in seconds. Defenders can run these dorks against their own domains and addresses to find accidental exposure before an attacker does.

5.3 Module 3 - Footprinting with Maltego (networkwalks.com)

Maltego CE 4.13.0 was installed from the Kali package (`apt install maltego`, Figs 3.1-3.2) and launched from the terminal (Fig 3.3). I created a free Maltego ID, completed activation in the browser and downloaded the data sources: 238 transforms, 245 entities and 14 machines (Fig 3.10). Setup screenshots are in Appendix A.

I created a blank graph, dragged a Domain entity onto it and renamed it networkwalks.com (Fig 3.14), the authorized target. I searched the transform list for “email” (Fig 3.15) and ran **[Utilities] To Emails @domain [Search Engine]**, which queries a search engine (Google) and does not contact the target’s servers. I ran it a second time with “Extract URLs” ticked (Fig 3.16).

Result (Fig 3.17). One address, **info@networkwalks.com**, linked to a public page titled “How to login & study your course - Networkwalks Academy”. WhatWeb found the same address in Module 1, so two independent tools agree. No personal staff emails or names surfaced, which is a good outcome for the organization. The scope was limited to email harvesting on networkwalks.com for ethical reasons, so one result is expected.

Impact. A generic role mailbox is a normal public contact, but it is a phishing and spam target, and the login-help page offers an attacker a credible pretext. Combined with the soft-fail SPF record from Module 1, a spoofed message from the domain would be easier to deliver.

5.4 Module 4 - Footprinting with theHarvester (microsoft.com)

The lab designated microsoft.com as the target. All sources are public and passive; one fallback module also made light DNS lookups.

Task	Command	Result
Task 1 (Fig 4.1)	`theHarvester -d microsoft.com -l 1000 -b baidu`	No IPs, emails, people or hosts found. The cause could not be verified (possible blocking or no indexed content).
Task 2 (Figs 4.2-4.4)	`theHarvester -d microsoft.com -l 50 -b all`	9,967 hosts, 55 IPs, 8 ASNs, 7 interesting URLs, 3 emails (role/bot addresses: dotnet-docker-bot@, opencode@, secure@microsoft.com), no people and no LinkedIn data. Output saved to a text file.

- **Coverage.** 32 sources failed on missing API keys (for example Shodan, Censys, VirusTotal, Hunter); Fofa and LeakIX rejected invalid keys. The result is therefore a lower bound.
- **Hosts.** Several hundred of the hostnames carry pre-production markers such as ppe, int, dev, uat and canary, and 21 are wildcard entries. Names like these reveal environments and naming conventions.
- **ASNs and IPs.** 8 ASNs (AS8075, AS13335, AS16509, AS16625, AS20940, AS40034, AS133618, AS206834) show the infrastructure is spread across several providers.
- **Hudson Rock.** The module reported aggregate infostealer statistics for the domain (621,624 compromised records, of which 16,598 employee and 600,241 user) and returned no emails or credentials. These are unverified third-party numbers; no credential-level data was retrieved or viewed.

Impact. An attacker can build a detailed asset map of a large organization without sending a single packet to it. Defenders should expect this and treat hostname hygiene, certificate transparency monitoring and credential-theft monitoring as part of normal security work.

5.5 Module 5 - Network Scanning with Zenmap (my own network)

I used `ipconfig` to identify my adapter: IPv4 192.168.100.9, mask 255.255.255.0 and gateway 192.168.100.1 (Fig 5.1), so the LAN is 192.168.100.0/24. A second adapter, 192.168.56.1, is in the range typically used by VirtualBox host-only networks, and the Surfshark VPN adapter was disconnected during the test. In Zenmap I entered the subnet with the **Ping scan** profile (`nmap -sn 192.168.100.1/24`). Nmap reported **5 hosts up out of 256 addresses in 6.74 seconds** on 10 November 2026 (Fig 5.2). I then opened the Topology tab, enabled the legend (Fig 5.3) and saved the graphic as a PDF (Fig 5.4).

Host	MAC (masked)	Vendor	Notes
192.168.100.1 (dev.opt)	34:66:79:xx:xx:xx	Huawei Technologies	Default gateway; latency 0.004 s
192.168.100.3	Not reported	- - -	No MAC or latency shown, typical of an address local to the scanning machine; identified
192.168.100.5	BA:6F:D7:xx:xx:xx	Unknown	Latency 0.082 s. Locally administered bit set, consistent with a randomized (private) MAC; identification under way
192.168.100.6	B0:A4:60:xx:xx:xx	Intel Corporate	Latency 0.076 s
192.168.100.9	Not reported	- - -	The scanning PC itself

Analysis. Any device on the LAN could discover the same five hosts in seconds. Randomized MAC addresses are a privacy feature of modern phones and laptops, but they defeat vendor lookup, so an inventory based on DHCP leases and device names is more reliable than relying on MAC prefixes. The topology shows a flat network with no traceroute data; the green markers only mean fewer than three open ports, and since a ping scan does not test ports, they indicate no port data.

6. Risk Analysis / Impact

The table below consolidates the observations from all five modules.

#	Finding	Evidence / Observation	Potential impact	Risk level
1	Web technology and version disclosure	WhatWeb (Fig 1.3): Apache, WordPress 7.1.4, WP Download Manager 3.3.76, jQuery 3.7.1	Lets an attacker match software to known issues. Risk rises if versions are outdated (not validated here).	● **Low**
2	Missing HTTP security headers; REST API and cache details exposed	curl -I (Fig 1.5): no HSTS, CSP, X-Frame-Options or X-Content-Type-Options seen; /wp-json/ and x-nginx-cache headers disclosed	Weaker browser-side protection (clickjacking, MIME sniffing, downgrade) and easier CMS enumeration.	● **Medium**
3	DNS server version disclosure	DNSRecon (Fig 1.7): both name servers report BIND 9.16.23-RH	Enables version-targeted attacks. DNS is provider-managed, so remediation depends on the host.	● **Low**
4	Email-authentication and DNS-integrity gaps	DNSRecon / WHOIS (Figs 1.1, 1.7): SPF ends in ~all (soft fail); DNSSEC unsigned	Easier spoofing of the domain in phishing mail; DNS tampering would not be cryptographically detectable.	● **Medium**
5	Domain registration and hosting profile	WHOIS, nslookup, DNSRecon: privacy proxy and registrar locks set (good); shared HostGator/cPanel hosting; web and mail on one IP	Aids infrastructure mapping and shows shared-host dependency. Registration privacy is a positive control.	● **Info**
6	WAF present and fingerprintable	wafw00f (Fig 1.6): ModSecurity (SpiderLabs), 2 requests	Positive control; knowing the product helps an attacker plan evasion.	● **Info**
7	Public role mailbox discoverable	WhatWeb (Fig 1.3) and Maltego (Fig 3.17): info@networkwalks.com	Target for phishing and spam; the linked login-help page gives an attacker a ready pretext.	● **Low**
8	Internet-exposed cameras reachable without authentication	GHDB (Figs 2.4–2.7, Table 2.1): 10 links showed live feeds with no login; 2 probably unintended hosted streams	Loss of privacy, surveillance of premises and a possible foothold into the owner's network.	● **High**
9	Indexed open directory listings	GHDB (Figs 2.8–2.12, Table 2.2): 10 browsable directories of PDF files	Information exposure and redistribution of copyrighted material; the same flaw can expose sensitive files.	● **Medium**
10	Large passive attack surface of a public domain (lab example)	theHarvester (Figs 4.2–4.4): 9,967 hostnames, 55 IPs, 8 ASNs, many pre-production names (ppe, int, dev, uat)	Reveals environments and naming conventions and helps find forgotten assets, all without touching the target.	● **Low**
11	Infostealer-exposure statistics from a third-party source	theHarvester / Hudson Rock (Fig 4.3): 621,624 compromised records (16,598 employee, 600,241 user)	Indicates credential and session-theft risk. Aggregate, unverified; no credentials were retrieved or viewed.	● **Medium**
12	Reduced OSINT coverage without API keys	theHarvester (Figs 4.2–4.3): 32 sources unavailable (missing or invalid keys); Baidu returned nothing	Results are a lower bound; absence of data is not proof of absence of exposure.	● **Info**
13	Local network hosts easily discoverable; one device unidentified	Zenmap (Fig 5.2): 5 live hosts found in 6.74 s on a flat /24; 192.168.100.5 uses a randomized MAC (vendor unknown)	A rogue device could blend in, and there is no visible segmentation.	● **Low**

Risk level key: Critical • High • Medium • Low • Info (Critical = immediate compromise likely; High = direct exposure; Medium = meaningful weakness; Low = minor disclosure; Info = context or positive control).

Most items above are observations from footprinting and scanning, not confirmed vulnerabilities. The presence of a software version, IP address or DNS record does not by itself mean a system is vulnerable. The exceptions are findings 8 and 9, where unauthenticated access was directly observed (viewing only, no interaction). Any real vulnerability would need to be confirmed by further, authorized testing.

7. Recommendations

1. **Reduce technology disclosure and patch.** Limit version banners and generator tags, keep WordPress core and WP Download Manager updated, and review them against current advisories.
2. **Add HTTP security headers.** Set HSTS, a Content-Security-Policy, X-Frame-Options (or frame-ancestors) and X-Content-Type-Options, and restrict unneeded REST API endpoints.
3. **Harden DNS and email authentication.** Move SPF to a hard fail (`-all`) once all senders are listed, publish DKIM and an enforced DMARC policy, enable DNSSEC where the DNS host supports it, and ask the provider to hide the BIND version.
4. **Keep the WAF enabled and tuned,** with an up-to-date ruleset, since it already blocks naive attacks.
5. **Limit mailbox exposure.** Prefer a contact form for public enquiries, keep strong mail filtering and train staff to spot phishing that uses the public address.
6. **Secure internet-facing cameras.** Require authentication, change default credentials, disable guest viewing, remove port forwarding, use a VPN or reverse proxy, update firmware, and review privacy settings on hosted streams. Report exposed feeds to the provider or the national CERT.
7. **Disable directory listing** (for example `Options -Indexes`), add noindex and robots rules, and regularly dork your own domains (`site:`) for accidental exposure.
8. **Practise OSINT hygiene.** Keep an asset inventory, avoid descriptive hostnames for internal or pre-production systems, monitor certificate transparency, enforce MFA and rotate credentials quickly, watch for infostealer exposure, and run these same tools against your own domains under authorization.
9. **Manage the local network.** Keep a device inventory built from DHCP leases, investigate unknown devices, segment guest and IoT devices, scan periodically and keep the topology documented.
10. **Test only with authorization.** Hold written authorization and scope for every engagement, store evidence securely, and mask third-party data in reports.

8. Limitations

- All work was passive or light-touch reconnaissance; no exploitation, brute force or vulnerability validation was done.
- Module 2 captured screenshots for two of the ten camera links; the rest were checked at the time but not saved. Copyright status of the listed PDFs was not verified.
- Maltego CE (credit-limited) was used with a single search-engine transform, and theHarvester ran without API keys for 32 sources, so results are a lower bound.
- Zenmap used a ping scan only, so ports and services on the five hosts were not assessed. One host had not been identified at the time of writing.
- Third-party statistics (for example Hudson Rock) are unverified, and microsoft.com was a lab example with no authorization letter, so only passive sources were used.

9. Conclusion

During Week 2 of my Cybersecurity & Ethical Hacking internship I completed five practical modules covering footprinting, reconnaissance and network scanning. I learned that WHOIS, WhatWeb, nslookup, curl, wafw00f and DNSRecon each reveal a different layer of a target; that Google dorking and Maltego show how far public data can go before any packet reaches the target; that theHarvester can map a very large organization passively, and how API keys change its coverage; and that Zenmap can map a local network in seconds.

The exercises showed me that information gathering is an important part of cybersecurity. Even before attempting to exploit a system, a security professional can learn a great deal from public information and network responses. I also learned that a good report explains what was done, what was found, why it matters, how risky it is and how to reduce that risk.

10. Evidences Collected

Module 1 - Multiple Kali tools (networkwalks.com)




Figure 1.1 - *WHOIS lookup - registry record*




Figure 1.2 - *WHOIS lookup - registrar record (privacy proxy, name servers)*



Figure 1.3 - *WhatWeb fingerprint of networkwalks.com*



Figure 1.4 - *nslookup resolution of networkwalks.com*



Figure 1.5 - *curl -I HTTP response headers*




Figure 1.6 - *wafw00f detecting ModSecurity (SpiderLabs)*




Figure 1.7 - *dnsrecon -d networkwalks.com*

Module 2 - Google Hacking Database (GHDB)




Figure 2.1 - *Exploit-DB home page (earlier session)*




Figure 2.2 - *Navigating to the GHDB section (earlier session)*




Figure 2.3 - *GHDB quick search for "cam"*




Figure 2.4 - *Google dork intitle:"webcamXP" inurl:8080 (IP masked)*




Figure 2.5 - *Exposed webcamXP 5 server, “Not logged in” (IP masked, live thumbnails blurred)*




Figure 2.6 - *Google results for a related dork, intitle:"Webcam" inurl:WebCam.htm (IP masked)*




Figure 2.7 - *Exposed Webcam 7 server, “Not logged in” (IP masked, feed blurred)*




Figure 2.8 - *Open-directory dork entered in Google*




Figure 2.9 - *Search results for the open-directory dork (right-hand panel blurred)*




Figure 2.10 - *Open directory 1 - school curriculum PDFs (URL masked)*




Figure 2.11 - *Open directory 2 - course archive (URL masked)*




Figure 2.12 - *Open directory 3 - book library (URL masked, file names blurred)*

Module 3 - Maltego CE



Figure 3.3 - *Maltego CE (Kali build) starting from the terminal*



Figure 3.10 - *Data sources downloaded: 238 transforms, 245 entities, 14 machines*




Figure 3.14 - *Domain entity renamed to the authorized target, networkwalks.com*




Figure 3.15 - *Transform search "email" - To Emails @domain [Search Engine] (Google-powered)*




Figure 3.16 - *Transform input dialog (Extract URLs option)*




Figure 3.17 - *Result graph: info@networkwalks.com and a linked Academy page, with transform output*

Module 4 - theHarvester (microsoft.com)



Figure 4.1 - *Task 1: -b baidu, limit 1000 - no results*




Figure 4.2 - *Task 2: -b all, limit 50 - command and first missing-API-key errors*




Figure 4.3 - *Task 2: sources searched, Hudson Rock output, Fofa and LeakIX key errors*




Figure 4.4 - *Task 2: summary of ASNs, interesting URLs and IP count (long OAuth URL truncated)*

Module 5 - Zenmap (own network)




Figure 5.1 - *ipconfig: adapter 192.168.100.9/24, gateway 192.168.100.1 (IPv6 masked)*




Figure 5.2 - *Ping scan results: 5 hosts up (MAC suffixes masked)*




Figure 5.3 - *Topology view with legend*




Figure 5.4 - *Topology exported to PDF and rendered as an image*

Appendix A - Additional Screenshots

Maltego installation and activation steps, and the Zenmap launch state. Tokens in browser address bars are masked.

Figure 3.1 - apt install maltego




Figure 3.2 - Install complete




Figure 3.4 - Activation options




Figure 3.5 - Browser login prompt




Figure 3.6 - Create Maltego ID





Figure 3.7 - Complete profile



Appendix A.1 - *Maltego installation, activation and profile set-up (Figures 3.1-3.7)*

Figure 3.8 - Authentication complete




Figure 3.9 - Activation successful




Figure 3.11 - Client ready




Figure 3.12 - Blank graph



Figure 3.13 - Domain entity placed




Figure 5.5 - Zenmap launch state (default profile)



Appendix A.2 - *Maltego authentication, readiness and first graph (Figures 3.8-3.13), and the Zenmap launch state (Figure 5.5)*

-End-

Author
Abdulkadiri Adaranijo
Cybersecurity Professional B084
LinkedIn: https://www.linkedin.com/in/tj-adaranijo-02183a191/

Project Information
Program Name: Cybersecurity program at Networkwalks | **Week:** 02 | **Repository:** GitHub