


# 2000 A - Phase L1

Fehlerverlauf L1



- Klassengrenzen 1,0
- MBS ASK101.4 | PAC2 | 8,1 Ω | Parallel
- Celsa ALO 8030 K | 2000 A | 8,1 Ω | Parallel
- Redur 13A1030.3ffp | 2000 A | 8,1 Ω | Parallel
- Celsa ALO 10030 | 2000 A | 1,35 Ω | Parallel
- ▲— Celsa ALO 10030 | 2000 A | 1,35 Ω | Dreieck
- ▲— Celsa ALO 8030 K | 2000 A | 8,1 Ω | Dreieck
- ▲— MBS ASK101.4 | 2000 A | 8,1 Ω | Dreieck
- ▲— Redur 13A1030.3ffp | 2000 A | 8,1 Ω | Dreieck