




# 5000 A | Fehlerkurve | Parallel und Dreieck



—▲— Redur 20A1456.5vffp | 5000 A | 8,1 Ω | Dreieck    —▲— MBS ASK129.10 | 5000 A | 10,8 Ω | Dreieck    —△— Celsa ALO 20060 | 5000 A | 0,0 Ω | Dreieck  
—●— Celsa ALO 20060 | 5000 A | 0,0 Ω | Parallel    —●— Redur 20A1456.5vffp | 5000 A | 0,0 Ω | Parallel