




2000 A | Fehlerkurve | Parallel und Dreieck



● MBS ASK101.4 | PAC2 | 8,1 Ω | Parallel ● Celsa ALO 8030 K | 2000 A | 8,1 Ω | Parallel ● Redur 13A1030.3ffp | 2000 A | 8,1 Ω | Parallel
● Celsa ALO 10030 | 2000 A | 1,35 Ω | Parallel ▲ Celsa ALO 10030 | 2000 A | 1,35 Ω | Dreieck ▲ Celsa ALO 8030 K | 2000 A | 8,1 Ω | Dreieck
▲ MBS ASK101.4 | 2000 A | 8,1 Ω | Dreieck ▲ Redur 13A1030.3ffp | 2000 A | 8,1 Ω | Dreieck