




2000 A | Fehlerkurve | Parallel und Dreieck



- MBS ASK101.4 | 2000 A | 8,1 Ω | Parallel
- Redur 13A1030.3ffp | 2000 A | 8,1 Ω | Parallel
- ▲ Celsa ALO 10030 | 2000 A | 1,35 Ω | Parallel
- Celsa ALO 8030 K | 2000 A | 8,1 Ω | Parallel
- ▲ Celsa ALO 10030 | 2000 A | 1,35 Ω | Dreieck
- ▲ Celsa ALO 8030 K | 2000 A | 8,1 Ω | Dreieck
- ▲ MBS ASK101.4 | 2000 A | 8,1 Ω | Dreieck
- ▲ Redur 13A1030.3ffp | 2000 A | 8,1 Ω | Dreieck