

Vehicle Damage Assessment Report

Report Date: 2025-08-23 14:52:26

Name	John
Surname	Doe
Make	kia
Model	sportage
Year	2022
VIN	IT12345

AI-Generated Detailed Report:

Vehicle Damage Assessment Report Report Date: 2025-08-23 Prepared for: John Doe


Vehicle Information: - Make: Kia - Model: Sportage - Year: 2022 - VIN: IT12345

Detected Damages: - Dent in front door (conf=0.94, IoU=0.40) — Estimated Cost: \$427.58. See attached image. - Scratch in front door (conf=0.48, IoU=0.09) — Estimated Cost: \$428.62. See attached image.


Summary of Estimated Repair Costs: * Front door dent repair: \$427.58 * Front door scratch repair: \$428.62 Total Estimated Repair Cost: \$856.20

Annotated Images:






YOLO Predictions + Masks







huf

Inspector Signature