



# Honda City 2012




# Car Detail

Customer/Dealer Name Malik	Engine Capacity 1300 cc	Mileage 96256 km	Transmission Type  Manual
Inspection Date 06 Aug 2022	Chassis No NFBGM1542CR126763	<ul><li>Engine Type</li><li>L13Z13431043</li></ul>	Registration No LEC-12-3956
Fuel Type Petrol	Color Silver	Location Lahore	Registered City  Lahore

ENGINE/TRANSMISSION/CLUTCH	100%	BRAKES	100%
SUSPENSION/STEERING	95%	INTERIOR	86%
AC/HEATER	100%	ELECTRICAL & ELECTRONICS	100%
EXTERIOR & BODY	72%	TYRES	71%

# **Exterior Condition**



## Legend

**B3**: Big Dent with scratch (size like elbow)

**B1:**Small dent with scratch (size like a thumb)

A1:Small Scratch

**S1:** Rust


**B2:** Dent with scratch (size like flat of the hand)

P: Paint marked

A2:Scratch

•: Minor Scratches/Dents

Body Frame Accident Checklist	
Radiator Core Support	Non-Accidented
Right Strut Tower Apron   Output  Description:	Non-Accidented
Left Strut Tower Apron <b>●</b>	Non-Accidented
Right Front Rail <b>9</b>	Non-Accidented
Left Front Rail <b>●</b>	Non-Accidented
Cowl Panel Firewall <b>9</b>	Non-Accidented
Right A Pillar <b>9</b>	Non-Accidented
Left A Pillar <b>●</b>	Non-Accidented
Right B Pillar <b>①</b>	Non-Accidented
Left B Pillar <b>9</b>	Non-Accidented
Right C Pillar <b> </b>	Non-Accidented
Left C Pillar <b>●</b>	Non-Accidented
Boot Floor <b>●</b>	Non-Accidented
Boot Lock Pillar	Non-Accidented
Rear Sub Frame <b>9</b>	Non-Accidented
Front Sub Frame <b>①</b>	Non-Accidented



Parking / Hand Brake

Suspension/Steering

Ok

95%

Front suspension	
Steering Wheel Play	Play
Right Ball Joint	Ok
Left Ball Joint	Ok
Right Z Links	Boot Damage or Play
Left Z Links	Boot Damage or Play
Right Tie Rod End	Ok
Left Tie Rod End	Ok
Front Right Boots	Ok
Front Left Boots	Ok
Front Right Bushes	Ok
Front Left Bushes	Ok
Front Right Shock	Ok
Front Left Shock	Ok

Rear suspension	
Rear Right Bushes	No Damage Found
Rear Left Bushes	No Damage Found
Rear Right Shock	Ok
Rear Left Shock	Ok

	i		
<b>L</b> Interior			86%
Steering controls		Seats	
Steering Wheel Condition	Torn	Right Seat Adjuster Recliner	Working
Horn	Working	Left Seat Adjuster Recliner	Working
Lights Lever / Switch (High / Low	Working	Right Seat Adjuster Lear Track	Working
Beams , Indicators)	-	Left Seat Adjuster Lear Track	Working
Wiper / Washer Lever (Washer, Speeds)	Working	Right Seat Belt	Working
		Left Seat Belt	Working
Mirrors		Rear Seat Belts	Working
Right Side Mirror	Working	Glove Box	Working
Left Side Mirror	Working		
Rear View Mirror Dimmer	Showing Reflection		

Power / manual windows & central locking		
Front Right Power Window/Manual Lever	Working Properly	
Fornt Left Power Window/Manual Lever	Working Properly	
Rear Right Power Window/Manual Lever	Working Properly	
Rear Left Power Window/Manual Lever	Working Properly	
Window Safety Lock	Working	

Poshish		
Roof Poshish	Dirty	
Floor Mat	Perfect	
Front Right Seat Poshish	Not Checked due to Market Cover	
Front Left Seat Poshish	Not Checked due to Market Cover	
Rear Seat Poshish	Not Checked due to Market Cover	
Dashboard Condition	Minor Spots	

Dash / roof controls		
Interior Lightings	Working	
Dash Controls - A/C	Working	
Dash Controls - De-Fog	Working	
Dash Controls - Hazzard Lights	Working	
Dash Controls - Others	Working	
Audio/Video	Working	
Rear View Camera	Working	
Trunk Release Lever / Button	Working	
Fuel Cap Release Lever / Button	Working	
Bonnet Release Lever / Button	Working	

Equipment	
Spare Tire	Present
Tools	Complete
Jack	Not Present or Not Working

Ac/Heater 100%

Ac / heater check up	
AC Fitted	Yes
AC Operational	Yes
Blower	Excellent Air Throw
Cooling	Excellent
Heating	Excellent



Computer check up	
Computer Check up / Malfunction Check •	No Error
Battery Warning Light	Not Present
Oil Pressure Low Warning Light	Not Present
Temperature Warning Light / Gauge	Not Present
Power Steering Warning Light	Not Present
ABS Warning Light	Not Present

Battery		
Voltage <b>€</b>	12	
Terminals Condition	Ok	
Charging	Ok	
Alternator Operation	Ok	

Instrument cluster	
Gauges	Working

Exterior & Body			72%
Car frame		Exterior lights	
Trunk Lock	Ok	Right Headlight (Working)	Working
Front Windshield Condition	Chip	Left Headlight (Working)	Working
Rear Windshield Condition	Ok	Right Headlight (Condition)	Perfect
Front Right Door Window	Ok	Left Headlight (Condition)	Scratches
Front Left Door Window	Ok	Right Taillight (Working)	Working
Rear Right Door Window	Ok	Left Taillight (Working)	Working
Rear Left Door Window	Ok	Right Taillight (Condition)	Cracked or Broken
Windscreen Wiper	Cleaning Properly	Left Taillight (Condition)	Cracked or Broken

Tyres	
Front Right Tyre <b>①</b>	5.2mm (remaining tread)
Front Left Tyre <b>9</b>	5.7mm (remaining tread)
Rear Right Tyre <b>①</b>	5.9mm (remaining tread)
Rear Left Tyre $oldsymbol{\Theta}$	5.8mm (remaining tread)
Tyre Size	195/65/R15
Rims	Normal
Wheel Caps	Present



Test Drive

71%

Engine Pick	Ok
Clutch Operation (While Driving)	Smooth
Gear Shifting (Manual)	Smooth
Drive Shaft Noise	No Noise
Brake Pedal Operation	Timely Response
ABS Operation	Timely Response
Front Suspension (While Driving)	No Noise
Rear Suspension (While Driving)	No Noise
Steering Operation (While Driving)	Smooth
Steering Wheel Alignment (While Driving)	Centered
AC Operation (While Driving)	Perfect
Heater Operation (While Driving)	Perfect
Speedometer (While Driving)	Working
Test Drive Done By	Seller







Front View

Oblique Front -Right





Oblique Rear - Right

Rear View







Oblique Rear – Left

Oblique Front - Left





Chassis No Engine No







Odometer

**Engine Compartment** 





Chassis Plate Front Interior







Rear Interior



Tool kit/Spare tyre



Trunk Open 4 Way Switch

 $2nd\ Floor, Saeed\ Alam\ Tower, 37\ Commercial\ Zone, \\ Liberty\ Market, Lahore.$ 

www.pakwheels.com, info@pakeventures.com 042 111 WHEELS (943 357) /pakwheels








Key/Remote Tyre



Rear Package Tray



www.pakwheels.com, info@pakeventures.com 042 111 WHEELS (943 357) /pakwheels

#### **Comments**

Gari ki left rail p rust ha.Gari ki body p nishan han.Normal rims ki wjha se disc pads and disc plates check krna mumkin nhi.

#### Disclaimer:

In case of any query or concern regarding inspection please call 042 - 111 WHEELS (042- 111 943 357).

This report is based on the condition of the vehicle on the date of certification and provides an approximate estimate of the condition on that date. Except where indicated, the parts were in working condition - this report does not take into account the condition of parts not visible or not inspected. PakWheels.com has relied on the odometer reading for kms driven as seen at the time of inspection and is not responsible for verifying its genuineness. The report is in no way a commitment on the condition of the car. All reports are subjective and PakWheels.com and its associates cannot be held liable in any way due to the use of this report.

Unless mentioned by the dealer, cars with W1 grade paint cannot be detected by the human eye, hence it can be possible for such paint to go undetected.