# Audit Report for Audit ID - AU00133-2 <u>Housekeeping Audit</u>

Audit Score 84/100

### **Details**

Audit	AU00133
Scheduled Audit	AU00133-2
Location	Chennai
Hotel	GreenPark Hotel- GPC
Department	House Keeping
Checklist	Housekeeping Audit
Audit Type	Internal
Auditor	Uday Bhasker Reddy
Start Date	01-09-2018
End Date	30-09-2018
Submitted Date	01-11-2018
Status	Completed
Assigned By	Administrator Account
Non-Compliance	181
Chronic Issues	22

### Comparison

## GREENPARK HOTEL- GPC HOUSEKEEPING AUDIT

HOUSEKEEPING AUDIT		Dec 2017	Sep 2018	VARIANCE	% of Increase		
S.No	Sections	SCORE OBTAINED	SCORE OBTAINED		/ Decrease (-/ +)		
1	Public Area	88	78	-10	-11.36%		
2	Procedures	83	84	1	1.2%		
3	Rest Rooms	90	79	-11	-12.22%		
4	Linen and Laundry	79	94	15	18.99%		
5	Contractual Service	87	88	1	1.15%		
6	Records	82	97	15	18.29%		
7	Floors - Guest Rooms	66	78	12	18.18%		
8	Gloss Level		77				
Audit Score		82	<b>8</b> 4	2	2.44%		

•	80-100 = Green	Good / Excellent
<b></b>	61-79 = Yellow	Average
-	60 below is Red	Poor / Fair

### Non-Compliance

**Section:** Public Area **Subsection:** LOBBY

1: Ceiling. NC



Attachments:

QUE4\_IMG\_20181030\_092821.jpg QUE4\_IMG\_20181030\_092849.jpg

Observation Text:

Fond cobwebs and painy peeling off

2: Lights / TV NC



Attachments:

QUE5\_IMG\_20181030\_102954.jpg

Observation Text:

Cobwebs hanging on chandelliers

3: Furniture. NC



Attachments:

QUE14\_IMG\_20181030\_093111.jpg

Observation Text:

All sofas in lobby and upper lobbyto be shampooed as they are became dirty

4: Upholstery. NC



Observation Text:

Sofa upholstery not in good condition

5: Polishing. NC



Attachments:

QUE16\_IMG\_20181030\_093233.jpg

Observation Text:

Side tables to be polished, and legs are wiping after marble polishing done

6: Accessories. NC



Attachments:

QUE17\_IMG\_20181030\_093353.jpg

Observation Text:

Lotus flowers in pond to be changed as they are colour faded

Green Park Corporate Audit Team. Section: Public Area Subsection: OUT 1: Carpet. NC No Observation Text: Bkack spots on red carpet 2: Panels. NC No Observation Text: Polishing to he wherever scratches arw there 3: Dusting. NC No Observation Text: Chairs dusting is poor 4: Furniture. NC No Attachments: QUE34\_IMG\_20181030\_120010.jpg Observation Text: Stains on sofas and to be shampooed 5: Upholstery. NC No Section: Public Area Subsection: TULIPS 1: Walls. NC No Observation Text: Stain on wall behind buffet counter 2: Fabric. NC 3: Dusting. NC Observation Text:

Chairs cleaning should improve

4: Furniture. NC No Attachments:

QUE54\_IMG\_20181030\_115046.jpg

Observation Text:

Chairs cleaning should improve

5: Upholstery. NC



Attachments:

QUE55\_IMG\_20181030\_115120.jpg

Observation Text:

Chsir cushions to be shampooed as they looking dirty

6: Banquet/Tables. NC



Attachments:

QUE58\_IMG\_20181030\_115240.jpg

Observation Text:

Sofas to be shampooed

Section: Public Area

Subsection: MUSTANG BAR

1: Ceiling. NC



Attachments:

QUE64\_IMG\_20181030\_110652.jpg

Observation Text:

Ceiling seepage

2: Floor. NC



Attachments:

QUE71\_IMG\_20181030\_110955.jpg

Observation Text:

Damaged wooden floor planks to be changed

Section: Public Area
Subsection: PALLAVI

1: Doors NC



Observation Text:

To be polished

2: Carpet. NC



Attachments:

QUE103\_IMG\_20181030\_102422.jpg

Carpet shampooing to be done

3: Panels. NC



Observation Text:

Scratch marks on wooden panels

4: Upholstery. NC



Attachments:

QUE115\_IMG\_20181030\_102625.jpg

Observation Text:

Chair covers condition not up to the mark

5: Polishing. NC



Observation Text:

Required for wooden panles amd doors

**Section:** Public Area **Subsection:** BHARINI

1: Doors NC



Observation Text:

to be polished

2: Dusting. NC



Attachments:

QUE132\_IMG\_20181029\_160846.jpg

Observation Text:

Table base to be cleaned

3: Polishing. NC



Observation Text:

Entire wall panels bottom to be polished

Section: Public Area

Subsection: BOARD ROOM 1

1: Doors NC



Observation Text:

Door edges to be polished

2: Polishing. NC



Observation Text:

wall panels to be polished

3: Banquet/Tables. NC



Attachments:

QUE158\_IMG\_20181029\_160039.jpg

Observation Text:

To be polished

Section: Public Area
Subsection: VAUHINI

1: Doors NC



Observation Text:

To be polished

2: Banquet/Tables. NC



Observation Text:

Banquet tables to keep neat and clean

Section: Public Area

Subsection: BOARD ROOM 2

1: Doors NC



Observation Text:

Door bottom to be cleaned

2: Ceiling. NC



Attachments:

QUE184\_IMG\_20181029\_160339.jpg

Observation Text:

Paint peeling off

3: Banquet/Tables. NC



Attachments:

QUE198\_IMG\_20181029\_160530.jpg

Observation Text:

Stained chair covers

Section: Public Area

Subsection: CONVENTION HALL

1: Floor. NC



Observation Text:

Entrance floor and steps to be Scrubbed and cleaned

Section: Public Area
Subsection: SESHMAHAL

1: Doors NC



Observation Text:

Door edges to be polished

2: Carpet. NC



Observation Text:

Totally worn out

3: Ceiling. NC



Attachments:

QUE224\_IMG\_20181029\_154702.jpg

Observation Text:

Ceiling seepage

4: Panels. NC



Attachments:

QUE229\_IMG\_20181029\_154812.jpg

Observation Text:

Panel fabric faded

5: Fabric. NC



Observation Text:

Panel fabric faded

6: Polishing. NC



Observation Text : Polishing required

**Section:** Public Area **Subsection:** RNG

1: Dusting. NC

**●** No

Observation Text:

To be done

Section: Procedures

Subsection: GUEST ROOMS

1: Bathroom linen standardization. NC

Rating: 6

Observation Text:

Softness of bath linen is poor and to be taken out from circulation and put new linen, whiteness of towels also poor.

2: Housekeeping - Machines. NC

Rating: 4

Observation Text:

Only 7 vacuum machines are available - Vacuum is not being happened in every room.

3: Housekeeping - Turndown service. NC

Rating: 7

Observation Text:

Only for

4: Carpets. NC

Rating: 0

Observation Text:

Looking shabby - Need attention to maintain in guest rooms properly

5: Sleep quality comfort. NC

Rating: 6

Observation Text:

Comfort levels of mattresses are poor

Section: Rest Rooms

Subsection: GENTS TOILET

1: Smell. NC



Observation Text:

Not smelling fresh

2: Door /Walls / Ceiling NC



Observation Text:

Door paint peeling off

3: Exhaust NC



Observation Text : Exhaust to be cleaned

Section: Rest Rooms

Subsection: LADIES LOCKER

1: Door /Walls / Ceiling NC



Observation Text: ceiling paint peeling off

2: Exhaust NC



3: Mattress / Other things NC



Attachments:

QUE305\_IMG\_20181030\_155201.jpg

Observation Text:

Chairs shampooing to be done

Section: Rest Rooms

Subsection: LOBBY GENTS REST ROOM

1: Maintenance. NC



Observation Text:

Toilet roll holders loose, Drain cover to be fixed in middle cubicle

2: Tiles. NC



Attachments:

QUE310\_IMG\_20181030\_093918.jpg

Observation Text:

Damaged

3: Door /Walls / Ceiling NC



Attachments:

QUE315\_IMG\_20181030\_094145.jpg

Observation Text:

Ceiling paint peeling off

Section: Rest Rooms

Subsection: LOBBY LADIES REST ROOM

1: Door /Walls / Ceiling NC



Attachments:

QUE328\_IMG\_20181030\_094350.jpg

Observation Text:

Door frames and door bottoms to be polished

Section: Rest Rooms

Subsection: BANQUET GENTS REST ROOM

1: Maintenance. NC



Attachments:

QUE333\_IMG\_20181030\_101516.jpg

Observation Text:

WC flush pad to change

2: Basin. NC



Observation Text:

Scratches in wash basin

3: Door /Walls / Ceiling NC



Observation Text:

Ceiling undulations

Section: Rest Rooms

Subsection: BANQUET LADIES REST ROOM

1: Maintenance. NC



Observation Text:

Wash basin cracked

2: W/C NC



Attachments:

QUE350\_IMG\_20181030\_101806.jpg

Observation Text:

Flush pad to change

3: Basin. NC



Attachments:

QUE351\_IMG\_20181030\_101843.jpg

Wash basin cracked

4: Door /Walls / Ceiling NC



Observation Text:

Doors and door frames bottoms to be polished and ceiling undulations

5: Exhaust NC



Attachments:

QUE355\_IMG\_20181030\_101942.jpg

Observation Text:

To be painted

Section: Rest Rooms

Subsection: EXECUTIVES GENTS LOCKER

1: Smell. NC



Observation Text:

Not smelling fresh

2: Exhaust NC



Observation Text:

Exhausts to be cleaned

Section: Rest Rooms

Subsection: EXECUTIVES LADIES LOCKER

1: Maintenance. NC



Observation Text:

Smelling not fresh - Drain smell

2: Smell. NC



Observation Text:

Not smelling fresh

3: Door /Walls / Ceiling NC



Observation Text:

Door paint peeling off

4: Exhaust NC



Observation Text : Exhaust to be cleaned

Section: Rest Rooms

Subsection: STAFF GENTS LOCKER

1: Mirror NC No

Observation Text:

Mirror frame to be painted

2: Mattress / Other things NC



Section: Rest Rooms

Subsection: POOL SIDE MENS REST ROOM

1: Maintenance. NC



Attachments:

QUE398\_IMG\_20181030\_112750.jpg

Observation Text:

Light to be fixed properly in front of mirror

2: Smell. NC



Observation Text:

Not smelling fresh

3: Door /Walls / Ceiling NC



Attachments:

QUE406\_IMG\_20181030\_112843.jpg

Observation Text:

Damaged door veneer to be changed

4: Exhaust NC



Attachments:

QUE407\_IMG\_20181030\_112923.jpg

5: Mattress / Other things NC



Attachments:

QUE409\_IMG\_20181030\_112950.jpg

Observation Text:

Table to he polished

Section: Rest Rooms

Subsection: POOL SIDE LADIES REST ROOM

1: Door /Walls / Ceiling NC



Attachments:

QUE419\_IMG\_20181030\_112420.jpg QUE419\_IMG\_20181030\_112501.jpg

Observation Text:

Damaged door bottom veneer to be changed

Section: Rest Rooms
Subsection: BAR LADIES

1: Door /Walls / Ceiling NC



Attachments:

QUE432\_IMG\_20181030\_111952.jpg

Observation Text : Door bottom damaged

Section: Rest Rooms
Subsection: BAR GENTS

1: Tiles. NC



Attachments:

QUE440\_IMG\_20181030\_111724.jpg

Observation Text : Incomplete work

Section: Floors - Guest Rooms

Subsection: 329

1: FLOORS. NC



Attachments:

QUE564\_IMG\_20181029\_091907.jpg

Observation Text:

Carpets are very dirty - To be shampooed

2: MIRRORS. NC



Attachments:

QUE567\_IMG\_20181029\_091623.jpg

Observation Text:

Mirror tarnished

Section: Floors - Guest Rooms

Subsection: 333

1: Ceiling NC



Attachments:

QUE571\_IMG\_20181029\_092329.jpg

Observation Text:

Ceiling seepage at spot light above bed

2: WINDOW PANE \ LEDGES NC



Attachments:

QUE574\_IMG\_20181029\_092522.jpg

Observation Text:

To be cleaned and polish

3: BED LINEN. NC



Attachments:

QUE575\_IMG\_20181029\_092636.jpg

Observation Text:

Stains on duvet cover

4: UPHOLSTRY\CURTAINS NC



Attachments:

QUE576\_IMG\_20181029\_092721.jpg

Observation Text:

Black out badly damaged

5: SUPP\STATIONERY. NC



Attachments:

QUE578\_IMG\_20181029\_092843.jpg

Observation Text:

Coffee mugs not cleaned properly

6: GUEST BATHROOMS. NC



Attachments:

QUE583\_IMG\_20181029\_093034.jpg

Observation Text:

Bath room ceiling seepage

7: BATHTUB\WC. NC



Attachments:

QUE585\_IMG\_20181029\_093239.jpg

Observation Text:

Water scales on shower cubicle glasses

Section: Floors - Guest Rooms

Subsection: 318

1: Ceiling NC



Attachments:

QUE591\_IMG\_20181029\_093645.jpg QUE591\_IMG\_20181029\_093707.jpg

2: WINDOW PANE \ LEDGES NC



Attachments:

QUE594\_IMG\_20181029\_093846.jpg

Observation Text:

Window sill belched

3: GUEST BATHROOMS. NC



Attachments:

QUE603\_IMG\_20181029\_094246.jpg QUE603\_IMG\_20181029\_094328.jpg

Observation Text:

Bathroom ceiling seepage, Head shower rusted

Section: Floors - Guest Rooms

Subsection: 316

1: Floor NC



Observation Text:

Wooden profile to be polished

2: MAINTENANCE NC



Attachments:

QUE619\_IMG\_20181029\_095000.jpg

Observation Text:

Safety latch is not working

3: BATHTUB\WC. NC



Attachments :

QUE625\_IMG\_20181029\_095156.jpg

Water scales on shower cubicle glasses

Section: Floors - Guest Rooms

Subsection: 234

1: Ceiling NC



Attachments:

QUE631\_IMG\_20181029\_095618.jpg

Observation Text:

Ceiling seepage

2: DUSTING NC



Observation Text:

Dust on study chair, skirtings

3: TIDINESS. NC



Attachments:

QUE641\_IMG\_20181029\_100018.jpg

Observation Text:

Dressing mirror not cleaned

4: FURNITURE. NC



Attachments:

QUE642\_IMG\_20181029\_095916.jpg

Observation Text:

Coffee table legs tp be dusted

5: GUEST BATHROOMS. NC



Attachments:

QUE643\_IMG\_20181029\_100116.jpg

Observation Text:

Bathroom Ceiling seepage

6: BATHTUB\WC. NC



Attachments:

QUE645\_IMG\_20181029\_100247.jpg

Observation Text:

To be cleaned

Section: Floors - Guest Rooms

Subsection: 237

1: DUSTING NC



Observation Text:

Dust on windows and skirting

2: GUEST BATHROOMS. NC



Attachments:

QUE663\_IMG\_20181029\_100936.jpg

Observation Text:

Bathroom ceiling seepage

Section: Floors - Guest Rooms

Subsection: 2111

1: Floor NC



Observation Text:

Carpet is dirty

2: WINDOW PANE \ LEDGES NC



Attachments:

QUE674\_IMG\_20181029\_101424.jpg

Observation Text:

To be polished

3: DUSTING NC



Attachments:

QUE680\_IMG\_20181029\_101814.jpg

Observation Text:

Dust on coffee table legs

4: GUEST BATHROOMS. NC



Attachments:

QUE683\_IMG\_20181029\_101946.jpg QUE683\_IMG\_20181029\_102057.jpg

Observation Text:

Picture frame to be replaced, Bathroom ceiling paint peeling off

Section: Floors - Guest Rooms

Subsection: 414

1: Walls/ Photo Frames NC



Attachments:

QUE692\_IMG\_20181029\_112737.jpg

Observation Text:

Alignment not proper

2: Floor NC



Observation Text:

Stains and scratches on floor, Carpet is dirty

3: WINDOW PANE \ LEDGES NC



Attachments:

QUE694\_IMG\_20181029\_112849.jpg

Observation Text:

To be polished

4: UPHOLSTRY\CURTAINS NC



Observation Text:

Only one sheer curtain is there

5: TIDINESS. NC



Observation Text:

Minibar cabinet door to be cleaned properly

6: BATHTUB\WC. NC



Attachments:

QUE705\_IMG\_20181029\_113106.jpg

Observation Text:

WC hinges caps to be fixed

7: SUPP\STATIONERY\BATHLINEN NC



Attachments:

QUE710\_IMG\_20181101\_093857.jpeg

Observation Text:

Threads on bath towels

Section: Floors - Guest Rooms

Subsection: 510

1: Floor NC



Wooden floor gaps to be closed

2: BED LINEN. NC



Attachments:

QUE715\_IMG\_20181029\_113705.jpg

Observation Text:

Stain bed sheet placed and stain covered with talcum powder

3: FURNITURE. NC



Attachments:

QUE722\_IMG\_20181029\_113908.jpg

Observation Text:

Coffee table legs damaged

4: FLOORS. NC



Attachments:

QUE724\_IMG\_20181029\_114017.jpg

Observation Text:

Hair on Floor

Section: Floors - Guest Rooms

Subsection: 517

1: Walls/ Photo Frames NC



Attachments:

QUE732\_IMG\_20181029\_114506.jpg

Observation Text:

Fungus on wall

2: DUSTING NC



Attachments:

QUE740\_IMG\_20181029\_114632.jpg

Observation Text:

Dust on coffee table legs

3: FURNITURE. NC



Attachments:

QUE742\_IMG\_20181029\_114710.jpg

Coffee table legs damaged

4: BATHTUB\WC. NC



Attachments:

QUE745\_IMG\_20181029\_114850.jpg

Observation Text:

Stains on WC

Section: Floors - Guest Rooms

Subsection: 533

1: Ceiling NC



Attachments :

QUE751\_IMG\_20181029\_115509.jpg

Observation Text:

Ceiling seepage

2: UPHOLSTRY\CURTAINS NC



Observation Text:

Black out to be pasted

3: SUPP\STATIONERY. NC



Observation Text:

Drinking glasses not wiped

4: FURNITURE. NC



Attachments:

QUE762\_IMG\_20181029\_115831.jpg

Observation Text:

To be polished

5: GUEST BATHROOMS. NC



Observation Text:

Bathroom ceiling seepage

6: FLOORS. NC



Attachments:

QUE764\_IMG\_20181029\_120007.jpg

Bathroom floor to be scrubbed and clean

7: WASHBASIN \ COUNTER NC



Attachments:

QUE766\_IMG\_20181029\_120110.jpg

Observation Text:

White scales around wash basin tap

8: DUSTING. NC



Attachments:

QUE768\_IMG\_20181029\_120208.jpg

Observation Text:

Toilet roll holders stained

Section: Floors - Guest Rooms

Subsection: 537

1: Ceiling NC



Observation Text:

Room ceiling seepage

2: WINDOW PANE \ LEDGES NC



Attachments:

QUE774\_IMG\_20181029\_120726.jpg

Observation Text:

To be cleaned

3: FLOORS. NC



Attachments:

QUE784\_IMG\_20181029\_121000.jpg

Observation Text:

Patches on floor

4: MAINTENANCE. NC



Section: Floors - Guest Rooms

Subsection: 633

1: Walls/ Photo Frames NC



QUE792\_IMG\_20181029\_121437.jpg

Observation Text:

Stains on wall

2: TIDINESS. NC



Observation Text:

Wardrobe doors and bathroom doors to be wiped

3: FURNITURE. NC



Attachments:

QUE802\_IMG\_20181029\_121628.jpg

QUE802\_IMG\_20181029\_122135.jpg

Observation Text:

Coffee table top polishing to be done, Writing table top also to be polished

4: GUEST BATHROOMS. NC



Attachments:

QUE803\_IMG\_20181029\_121827.jpg

5: FLOORS. NC



Attachments:

QUE804\_IMG\_20181029\_121739.jpg

Observation Text:

Patches on floor

Section: Floors - Guest Rooms

Subsection: 629

1: WINDOW PANE \ LEDGES NC



Attachments:

QUE814\_IMG\_20181029\_123632.jpg

Observation Text:

window glass not cleaned

2: BED LINEN. NC



Attachments:

QUE815\_IMG\_20181029\_123520.jpg

Observation Text:

Hair on bed

3: FURNITURE. NC



Attachments:

QUE822\_IMG\_20181029\_123720.jpg QUE822\_IMG\_20181029\_123740.jpg

Observation Text:

Table tops tp be polished

4: GUEST BATHROOMS. NC



Attachments:

QUE823\_IMG\_20181029\_123826.jpg QUE823\_IMG\_20181029\_124113.jpg

Observation Text:

Door corners to be cleaned, Drain flies are in bathroom

5: FLOORS. NC



Attachments:

QUE824\_IMG\_20181029\_123950.jpg

Observation Text : Stains on floor

Section: Floors - Guest Rooms

Subsection: 610

1: WINDOW PANE \ LEDGES NC



Attachments:

QUE834\_IMG\_20181029\_124752.jpg

Observation Text:

Window sill to be polished

2: BED LINEN. NC



Attachments:

QUE835\_IMG\_20181029\_125148.jpg

Observation Text:

Mattress bent

3: TIDINESS. NC



Attachments:

QUE841\_IMG\_20181029\_125626.jpg

Observation Text:

Stains on luggage rack

4: FURNITURE. NC



Attachments:

QUE842\_IMG\_20181029\_125316.jpg QUE842\_IMG\_20181029\_125332.jpg

Observation Text:

Table tops to be polished

5: GUEST BATHROOMS. NC



Attachments:

QUE843\_IMG\_20181029\_125756.jpg QUE843\_IMG\_20181029\_125811.jpg

Observation Text:

Water scLes on glass doors

6: FLOORS. NC



Observation Text:

Stains on floor

Section: Floors - Guest Rooms

Subsection: 430

1: Walls/ Photo Frames NC



Attachments:

QUE852\_IMG\_20181029\_130706.jpg

Observation Text:

No alignment

2: FLOORS. NC



Attachments:

QUE864\_IMG\_20181029\_130832.jpg

Section: Floors - Guest Rooms

Subsection: 532

1: Ceiling NC



Observation Text:

Seepage stains on ceiling

2: UPHOLSTRY\CURTAINS NC



Observation Text:

Black out to be pasted properly

Green Park Corporate Audit Team. 3: GUEST BATHROOMS. NC No Observation Text: Seepage stains on ceiling 4: DUSTING. NC No Observation Text: Soap rack and shower cubicle glasses to be cleaned Section: Floors - Guest Rooms Subsection: 437 1: WINDOW PANE \ LEDGES NC ( No Observation Text: To be cleaned 2: SUPP\STATIONERY. NC No Observation Text: Supplies tray not dusted 3: TIDINESS. NC No Observation Text: Stains on luggage rack 4: GUEST BATHROOMS. NC No Attachments: QUE903\_IMG\_20181029\_151213.jpg Observation Text: Bathroom ceiling seepage anf fungus 5: FLOORS. NC No No Observation Text: Patches on floor 6: BATHTUB\WC. NC No Attachments: QUE905\_IMG\_20181029\_151337.jpg

Observation Text:

Fungus on flush pad

Section: Floors - Guest Rooms

Subsection: 332

1: UPHOLSTRY\CURTAINS NC



Attachments:

QUE916\_IMG\_20181029\_151947.jpg

Observation Text : Sheer Curtain torn

2: GUEST BATHROOMS. NC



Observation Text : Ceiling seepage

3: SUPP\STATIONERY\BATHLINEN NC



Observation Text :
Towel rack has stains

Section: Floors - Guest Rooms

Subsection: 201

1: Ceiling NC



Observation Text : Ceiling seepage

2: Floor NC



Observation Text : Carpet to be shampooed

3: GUEST BATHROOMS. NC



Observation Text : Ceiling seepage

**Section:** Gloss Level **Subsection:** Marble Floor

1: Reception. NC Rating: 6

2: Lobby lounge NC

Rating: 7

3: Lobby Entrance NC Rating: 7

Ü

4: Tulips NC Rating: 7

5: Gardenia entrance NC

Rating: 7

Observation Text : Pallavi hall entrance

Section: Linen and Laundry

Subsection: Linen, Laundry & Guest Laundry

1: Quality of uniforms NC

Rating: 7

Observation Text:

Whiteness of executive shirts and chef coats not up to the mark

2: Quality of linen NC

Rating: 6

Observation Text:

Discarded bath linen to be removed from circulation - Still being placed in guest rooms.

3: Awareness of snow white initiatives NC

Rating: 7
Attachments:

QUE515\_IMG\_20181030\_170506.jpg

Observation Text:

According to report given by JD whiteness is low than standard

**Section:** Contractual Service **Subsection:** Contractual Service

1: Effectiveness NC

Rating: 5

Observation Text:

Found drin flies on bathroom ceiling in 629, Cobwebs found in upper lobby, rats issues are there.

Section: Records

Subsection: Records & Reports

1: Lost and found records NC

Rating: 7

2: L&F issues to the claimant NC

Rating: 7

Observation Text:

Filing should be done properly and Valid signatures to be must

#### Chronic

**Section:** Public Area **Subsection:** LOBBY

1: Lights / TV NC



Attachments:

QUE5\_IMG\_20181030\_102954.jpg

Observation Text:

Cobwebs hanging on chandelliers

**Section:** Public Area **Subsection:** OUT

1: Carpet. NC



Observation Text:

Bkack spots on red carpet

2: Dusting. NC



Observation Text : Chairs dusting is poor

**Section:** Public Area **Subsection:** TULIPS

1: Furniture. NC



Attachments:

QUE54\_IMG\_20181030\_115046.jpg

Observation Text:

Chairs cleaning should improve

Section: Public Area

Subsection: MUSTANG BAR

1: Floor. NC

No No

Attachments :

QUE71\_IMG\_20181030\_110955.jpg

Observation Text:

Damaged wooden floor planks to be changed

**Section:** Public Area **Subsection:** PALLAVI

1: Doors NC No

Observation Text :

To be polished

Section: Public Area
Subsection: VAUHINI

1: Doors NC No

Observation Text : To be polished

Section: Public Area
Subsection: SESHMAHAL

1: Carpet. NC No

Observation Text : Totally worn out

2: Fabric. NC No

Observation Text : Panel fabric faded

Section: Procedures

Subsection: GUEST ROOMS

 Housekeeping - Machines. NC Rating: 4

Observation Text:

Only 7 vacuum machines are available - Vacuum is not being happened in every room.

2: Carpets. NC Rating: 0

Observation Text:

Looking shabby - Need attention to maintain in guest rooms properly

Section: Rest Rooms

Subsection: LOBBY GENTS REST ROOM

1: Maintenance. NC

No

Observation Text:

Toilet roll holders loose, Drain cover to be fixed in middle cubicle

Section: Rest Rooms

Subsection: LOBBY LADIES REST ROOM

1: Door /Walls / Ceiling NC

No

Attachments:

QUE328\_IMG\_20181030\_094350.jpg

Observation Text:

Door frames and door bottoms to be polished

Section: Rest Rooms

Subsection: BANQUET GENTS REST ROOM

1: Maintenance. NC

No

Attachments:

QUE333\_IMG\_20181030\_101516.jpg

Observation Text:

WC flush pad to change

2: Door /Walls / Ceiling NC



Observation Text:
Ceiling undulations

Section: Rest Rooms

Subsection: EXECUTIVES GENTS LOCKER

1: Smell. NC



Observation Text :

Not smelling fresh

Section: Rest Rooms

Subsection: EXECUTIVES LADIES LOCKER

1: Maintenance. NC



Observation Text:

Smelling not fresh - Drain smell

Section: Rest Rooms

Subsection: POOL SIDE MENS REST ROOM

1: Maintenance. NC



Attachments :

QUE398\_IMG\_20181030\_112750.jpg

Light to be fixed properly in front of mirror

Section: Floors - Guest Rooms

Subsection: 537

1: Ceiling NC



Observation Text : Room ceiling seepage

2: FLOORS. NC



Attachments:

QUE784\_IMG\_20181029\_121000.jpg

Observation Text :

Patches on floor

3: MAINTENANCE. NC



Section: Linen and Laundry

Subsection: Linen, Laundry & Guest Laundry

1: Quality of linen NC

Rating: 6

Observation Text:

Discarded bath linen to be removed from circulation - Still being placed in guest rooms.

### **Audit Questionnaire**

**Section:** Public Area **Subsection:** LOBBY

1: Doors



2: Signage's



4: Ceiling. NC



Attachments:

QUE4\_IMG\_20181030\_092821.jpg QUE4\_IMG\_20181030\_092849.jpg

Observation Text:

Fond cobwebs and painy peeling off

5: Lights / TV NC



Attachments:

QUE5\_IMG\_20181030\_102954.jpg

Observation Text:

Cobwebs hanging on chandelliers

6: AC grills/Exhaust.



7: Walls.



8: Paintings.



9: Panels.



10: Fabric.



11: Floor.



12: Dusting.



Green Fank Corporate Audit Tea
13: Skirting.  Yes
14: Furniture. NC  No  Attachments:  QUE14_IMG_20181030_093111.jpg
Observation Text : All sofas in lobby and upper lobbyto be shampooed as they are became dirty
15: Upholstery. NC No
Observation Text : Sofa upholstery not in good condition
16: Polishing. NC  No  Attachments:  QUE16_IMG_20181030_093233.jpg
Observation Text : Side tables to be polished, and legs are wiping after marble polishing done
17: Accessories. NC
Observation Text : Lotus flowers in pond to be changed as they are colour faded
18: Banquet/Tables.   Not Applicable
19: Brass/Copper.  Yes
20: Window panes/Ledges.  Yes
Section: Public Area Subsection: OUT
1: Doors  Yes
2: Signage's  Yes
3: Carpet. NC No

	Green Park Corporate	Audit Team
Observation Text : Bkack spots on red carpet		
4: Ceiling.  Yes		
5: Lights / TV  Yes		
6: AC grills/Exhaust.  Yes		
7: Walls.  Yes		
8: Paintings.  Yes		
9: Panels. NC No		
Observation Text : Polishing to he wherever scratches arw there		
10: Fabric.  Yes		
11: Floor.  Yes		
12: Dusting. NC No		
Observation Text : Chairs dusting is poor		
13: Skirting.  Yes		
14: Furniture. NC		
Observation Text : Stains on sofas and to be shampooed		
15: Upholstery. NC No		
16: Polishing.  Yes		

17: Accessories.  Yes
18: Banquet/Tables.  Yes
19: Brass/Copper.  Yes
20: Window panes/Ledges.  Yes
Section: Public Area Subsection: TULIPS
1: Doors  Yes
2: Signage's  Yes
3: Carpet.  Not Applicable
4: Ceiling.  Yes
5: Lights / TV  Yes
6: AC grills/Exhaust.  Yes
7: Walls. NC No
Observation Text : Stain on wall behind buffet counter
8: Paintings.  Yes
9: Panels.  Yes
10: Fabric. NC No
11: Floor.  Yes
12: Dusting. NC



Observation Text:

Chairs cleaning should improve

13: Skirting.



14: Furniture. NC



Attachments:

QUE54\_IMG\_20181030\_115046.jpg

Observation Text:

Chairs cleaning should improve

15: Upholstery. NC



Attachments:

QUE55\_IMG\_20181030\_115120.jpg

Observation Text:

Chsir cushions to be shampooed as they looking dirty

16: Polishing.



17: Accessories.



18: Banquet/Tables. NC



Attachments:

QUE58\_IMG\_20181030\_115240.jpg

Observation Text:

Sofas to be shampooed

19: Brass/Copper.



20: Window panes/Ledges.



Section: Public Area

Subsection: MUSTANG BAR

1: Doors



2: Signage's




	Green Park Corporate Audit Team
3: Carpet.   Not Applicable	
4: Ceiling. NC  No	
Attachments :	
QUE64_IMG_20181030_110652.jpg	
Q0E04_IWC_20101000_110002.jpg	
Observation Text :	
Ceiling seepage	
5: Lights / TV	
Yes	
6: AC grillo/Exhaust	
6: AC grills/Exhaust.  Yes	
Yes	
7: Walls.	
Yes	
0 163	
8: Paintings.	
Yes	
9: Panels.	
Yes	
10: Fabric.	
Yes	
11: Floor. NC	
<b>◎</b> No	
Attachments:	
QUE71_IMG_20181030_110955.jpg	
Observation Text :	
Damaged wooden floor planks to be changed	
Damaged wooden noor planks to be changed	
12: Dusting.	
Yes	
13: Skirting.	
Yes	
4.4. Euroituro	
14: Furniture.	
Yes	
15: Upholstery.	
Yes	
16: Polishing.	
Yes	

17: Accessories.  Yes
18: Banquet/Tables.  Yes
19: Brass/Copper.  Not Applicable
20: Window panes/Ledges.  Yes
Section: Public Area Subsection: VIJAYA
1: Doors  Not Applicable
2: Signage's 🕢 Not Applicable
3: Carpet.  Not Applicable
4: Ceiling.   Not Applicable
5: Lights / TV 🕢 Not Applicable
6: AC grills/Exhaust.   Not Applicable
7: Walls.  Not Applicable
8: Paintings.   Not Applicable
9: Panels.   Not Applicable
10: Fabric.  Not Applicable
11: Floor.  Not Applicable
12: Dusting.  Not Applicable
13: Skirting.   Not Applicable
14: Furniture.  Not Applicable
15: Upholstery.  Vot Applicable
16: Polishing.  Not Applicable
17: Accessories.  Not Applicable
18: Banquet/Tables.    Not Applicable

•
19: Brass/Copper.  Not Applicable
20: Window panes/Ledges.   Not Applicable
Section: Public Area Subsection: PALLAVI
1: Doors NC No
Observation Text : To be polished
2: Signage's  Yes
3: Carpet. NC
Observation Text : Carpet shampooing to be done
4: Ceiling.  Yes
5: Lights / TV  Yes
6: AC grills/Exhaust.  Yes
7: Walls.  Yes
8: Paintings.   Not Applicable
9: Panels. NC No
Observation Text : Scratch marks on wooden panels
10: Fabric.  Yes
11: Floor.  Yes
12: Dusting.  Yes

	Green Park Corporate Audit Team
13: Skirting.  Yes	
14: Furniture.  Yes	
15: Upholstery. NC  No  Attachments:  QUE115_IMG_20181030_102625.jpg	
Observation Text : Chair covers condition not up to the mark	
16: Polishing. NC No	
Observation Text : Required for wooden panles amd doors	
17: Accessories.  Yes	
18: Banquet/Tables.  Yes	
19: Brass/Copper.  Not Applicable	
20: Window panes/Ledges.   Not Applicable	
Section: Public Area Subsection: BHARINI	
1: Doors NC No	
Observation Text : to be polished	
2: Signage's  Yes	
3: Carpet.  Yes	
4: Ceiling.  Yes	
5: Lights / TV  Yes	
6: AC grills/Exhaust.	



19: Brass/Copper. Yes

20:	Window panes/Ledges.  Yes
	tion: Public Area section: BOARD ROOM 1
1:	Doors NC No
	bservation Text : oor edges to be polished
2: 3	Signage's  Yes
3: (	Carpet. Not Applicable
4: (	Ceiling.  Yes
5:	Lights / TV  Yes
6: 7	AC grills/Exhaust.  Yes
7: \	Walls.  Yes
8:	Paintings.  Yes
9:	Panels.  Yes
10:	Fabric. Not Applicable
11:	Floor.  Yes
12:	Dusting.  Yes
13:	Skirting.  Yes
14:	Furniture.  Yes
15:	Upholstery.  Yes

16: Polishing. NC		Green Fark Corporate Audit Team
wall panels to be polished  17: Accessories.		
<ul> <li>Yes</li> <li>18: Banquet/Tables. NC</li></ul>		
Attachments:  QUE158_IMG_20181029_160039.jpg  Observation Text: To be polished  19: Brass/Copper.  Not Applicable  20: Window panes/Ledges.   Yes  Section: Public Area Subsection: VAUHINI  1: Doors NC   NC   NO Observation Text: To be polished  2: Signage's   Yes  3: Carpet.  Not Applicable  4: Ceiling.   Yes  5: Lights / TV   Yes  6: AC grills/Exhaust.   Yes  7: Walls.   Yes  8: Paintings.  Not Applicable  9: Panels.		
Observation Text: To be polished  19: Brass/Copper.  Not Applicable  20: Window panes/Ledges.   Yes  Section: Public Area Subsection: VAUHINI  1: Doors NC   NO   NO Observation Text: To be polished  2: Signage's   Yes  3: Carpet.  Not Applicable  4: Ceiling.   Yes  5: Lights / TV   Yes  6: AC grills/Exhaust.   Yes  7: Walls.   Yes  8: Paintings.  Not Applicable  9: Panels.	No Attachments :	
19: Brass/Copper.  Not Applicable  20: Window panes/Ledges.   Yes  Section: Public Area Subsection: VAUHINI  1: Doors NC   NO   Observation Text:   To be polished  2: Signage's   Yes  3: Carpet.  Not Applicable  4: Ceiling.   Yes  5: Lights / TV   Yes  6: AC grills/Exhaust.   Yes  7: Walls.   Yes  8: Paintings.  Not Applicable  9: Panels.	Observation Text :	
Section: Public Area Subsection: VAUHINI  1: Doors NC  No Observation Text: To be polished  2: Signage's Yes  3: Carpet. Not Applicable  4: Ceiling. Yes  5: Lights / TV Yes  6: AC grills/Exhaust. Yes  7: Walls. Yes  8: Paintings. Not Applicable  9: Panels.	<u>_</u>	
Subsection: VAUHINI  1: Doors NC  NO  Observation Text: To be polished  2: Signage's Yes  3: Carpet. Not Applicable  4: Ceiling. Yes  5: Lights / TV Yes  6: AC grills/Exhaust. Yes  7: Walls. Yes  8: Paintings. Not Applicable  9: Panels.		
<ul> <li>No</li> <li>Observation Text:         <ul> <li>To be polished</li> </ul> </li> <li>2: Signage's</li></ul>		
To be polished  2: Signage's		
<ul> <li>Yes</li> <li>3: Carpet. ✓ Not Applicable</li> <li>4: Ceiling.</li></ul>		
<ul> <li>4: Ceiling.</li></ul>		
<ul> <li>Yes</li> <li>5: Lights / TV</li></ul>	3: Carpet.  Not Applicable	
<ul> <li>Yes</li> <li>6: AC grills/Exhaust.</li> <li>Yes</li> <li>7: Walls.</li> <li>Yes</li> <li>8: Paintings.</li> <li>Not Applicable</li> <li>9: Panels.</li> </ul>		
<ul> <li>Yes</li> <li>7: Walls.</li> <li>Yes</li> <li>8: Paintings.</li> <li>Not Applicable</li> <li>9: Panels.</li> </ul>		
Yes  8: Paintings.  Not Applicable  9: Panels.		
9: Panels.	_	
	8: Paintings.   Not Applicable	

10:	Fabric. Not Applicable
	Floor.  Yes
	Dusting.  Yes
	Skirting.  Yes
14:	Furniture.  Yes
15:	Upholstery.   Not Applicable
	Polishing.  Yes
17:	Accessories.  Yes
18:	Banquet/Tables. NC  No
	oservation Text : inquet tables to keep neat and clean
19:	Brass/Copper.   Not Applicable
20:	Window panes/Ledges.    Not Applicable
	ion: Public Area section: BOARD ROOM 2
	Ooors NC No
	oservation Text : oor bottom to be cleaned
	ignage's Yes
3: C	Carpet. Not Applicable
Att	Ceiling. NC  No tachments:  QUE184_IMG_20181029_160339.jpg

Observation Text : Paint peeling off
5: Lights / TV  Yes
6: AC grills/Exhaust.  Yes
7: Walls.  Yes
8: Paintings.   Not Applicable
9: Panels.  Yes
10: Fabric. Not Applicable
11: Floor.  Yes
12: Dusting.  Yes
13: Skirting.  Yes
14: Furniture.  Yes
15: Upholstery.  Yes
16: Polishing.  Yes
17: Accessories.  Yes
18: Banquet/Tables. NC  No  Attachments:  QUE198_IMG_20181029_160530.jpg
Observation Text : Stained chair covers
19: Brass/Copper.  Not Applicable
20: Window panes/Ledges.



Section: Public Area

Subsection: CONVENTION HALL

1: Doors



2: Signage's



4: Ceiling.



5: Lights / TV



6: AC grills/Exhaust.



7: Walls.



11: Floor. NC



Observation Text:

Entrance floor and steps to be Scrubbed and cleaned

12: Dusting.



13: Skirting.



14: Furniture. Not Applicable

15: Upholstery.



17: Accessories.



7: Walls. Yes

9: Panels. NC ( No Attachments: QUE229\_IMG\_20181029\_154812.jpg

	Green Park Co	porate Audit	i eaiii.
Observation Text : Panel fabric faded			
10: Fabric. NC No			
Observation Text : Panel fabric faded			
11: Floor.  Yes			
12: Dusting.  Yes			
13: Skirting.  Yes			
14: Furniture.  Yes			
15: Upholstery.  Yes			
16: Polishing. NC No			
Observation Text : Polishing required			
17: Accessories.  Yes			
18: Banquet/Tables.  Yes			
19: Brass/Copper.  Yes			
20: Window panes/Ledges.  Yes			
Section: Public Area Subsection: RNG			
1: Doors  Not Applicable			
2: Signage's  Yes			
3: Carpet. Not Applicable			

4: Ceiling.   Not Applicable
5: Lights / TV  Yes
6: AC grills/Exhaust.   Not Applicable
7: Walls.   Not Applicable
8: Paintings.   Not Applicable
9: Panels.  Not Applicable
10: Fabric.  Vot Applicable
11: Floor.  Yes
12: Dusting. NC  No
Observation Text : To be done
13: Skirting.  Not Applicable
14: Furniture.  Yes
15: Upholstery.  Yes
16: Polishing.  Yes
17: Accessories.  Yes
18: Banquet/Tables.  Yes
19: Brass/Copper.  Not Applicable
20: Window panes/Ledges.    Not Applicable
Section: Procedures Subsection: GUEST ROOMS
1: Bathroom linen standardization. NC Rating: 6

Observation Text:

Softness of bath linen is poor and to be taken out from circulation and put new linen, whiteness of towels also poor.

2: Tea /coffee making facility in the room.

Rating: 10

3: Room history maintenance.

Rating: 10

Observation Text:

Being followed

4: Table / wardrobe drawers in guest rooms.

Rating: 10

5: Housekeeping - Machines. NC

Rating: 4

Observation Text:

Only 7 vacuum machines are available - Vacuum is not being happened in every room.

6: Housekeeping - Turndown service. NC

Rating: 7

Observation Text:

Only for

7: Bathroom amenities for double occupancy rooms.

Rating: 10

Observation Text:

Being followed

8: Suite bathroom amenities .

Rating: 10

Observation Text:

Being followed

9: Magazines provided to guest rooms.

Rating: 10

Observation Text:

Outlook, Business

10: Laundry - garment finishing standards.

Rating: 10

11: Carpets. NC

Rating: 0

Observation Text:

Looking shabby - Need attention to maintain in guest rooms properly

12: Care and maintenance of runners.

Rating: 10

13: Standardized in room items.

Rating: 8

Observation Text:

Found leather stationery box in writing table draw in 301

14: Sleep quality comfort. NC

Rating: 6

Observation Text:

Comfort levels of mattresses are poor

15: Specification of cleaning chemicals.

Rating: 10

Observation Text:

JD

16: Standardized bed linen / mattress / foundation.

Rating: 10

Observation Text:

Being followed

17: Standardization of par levels for room linen and table linen.

Rating: 8

18: Measurable instruments for quality / standards measurements.

Rating: 10

19: Guest-laundry pickup.

Rating: 10

Observation Text:

Being followed

Section: Rest Rooms

Subsection: GENTS TOILET

1: Taps.



2: Maintenance.



3: Smell. NC



	Green Park Corporate Audit Tean
Observation Text : Not smelling fresh	
4: Floor.  Yes	
5: Tiles.  Yes	
6: W/C Yes	
7: Basin.  Yes	
8: Mirror  Yes	
9: Soap /Supplies  Yes	
10: Door /Walls / Ceiling NC  No	
Observation Text : Door paint peeling off	
11: Exhaust NC No	
Observation Text : Exhaust to be cleaned	
12: Urinal.  Yes	
13: Mattress / Other things  Yes	
Section: Rest Rooms Subsection: LADIES LOCKER	
1: Taps.  Yes	
2: Maintenance.  Yes	
3: Smell.  Yes	
4: Floor.	

	Green Park Corporate Audit Team
Yes	
5: Tiles.  Yes	
6: W/C  Yes	
7: Basin.  Yes	
8: Mirror  Yes	
9: Soap /Supplies  Yes	
10: Door /Walls / Ceiling NC  No	
Observation Text : ceiling paint peeling off	
11: Exhaust NC No	
12: Urinal.	
13: Mattress / Other things NC	
No Attachments: QUE305_IMG_20181030_155201.jpg	
Observation Text : Chairs shampooing to be done	
Section: Rest Rooms Subsection: LOBBY GENTS REST ROOM	
1: Taps.  Yes	
2: Maintenance. NC No	
Observation Text : Toilet roll holders loose, Drain cover to be fixed in middle cubicle	
3: Smell.  Yes	
4: Floor.	



5: Tiles. NC

Attachments:

QUE310\_IMG\_20181030\_093918.jpg

Observation Text:

Damaged

6: W/C



7: Basin.



8: Mirror



9: Soap /Supplies



10: Door /Walls / Ceiling NC



Attachments:

QUE315\_IMG\_20181030\_094145.jpg

Observation Text:

Ceiling paint peeling off

11: Exhaust



12: Urinal.



13: Mattress / Other things



Section: Rest Rooms

Subsection: LOBBY LADIES REST ROOM

1: Taps.



2: Maintenance.



3: Smell.



4: Floor.  Yes
5: Tiles.  Yes
6: W/C Yes
7: Basin.  Yes
8: Mirror  Yes
9: Soap /Supplies  Yes
10: Door /Walls / Ceiling NC  No  Attachments:  QUE328_IMG_20181030_094350.jpg
Observation Text: Door frames and door bottoms to be polished
11: Exhaust  Yes
12: Urinal.  Not Applicable
13: Mattress / Other things  Yes
Section: Rest Rooms Subsection: BANQUET GENTS REST ROOM
1: Taps.  Yes
2: Maintenance. NC  No  Attachments:  QUE333_IMG_20181030_101516.jpg
Observation Text : WC flush pad to change
3: Smell.  Yes

	•
4: Floor.  Yes	
5: Tiles.  Yes	
6: W/C  Yes	
7: Basin. NC No	
Observation Text : Scratches in wash basin	
8: Mirror  Yes	
9: Soap /Supplies  Yes	
10: Door /Walls / Ceiling NC No	
Observation Text : Ceiling undulations	
11: Exhaust  Yes	
12: Urinal.  Yes	
13: Mattress / Other things  Yes	
Section: Rest Rooms Subsection: BANQUET LADIES REST ROOM	
1: Taps.  Yes	
2: Maintenance. NC No	
Observation Text : Wash basin cracked	
3: Smell.  Yes	
4: Floor.	



6: W/C NC



Attachments:

QUE350\_IMG\_20181030\_101806.jpg

Observation Text:

Flush pad to change

7: Basin. NC



Attachments:

QUE351\_IMG\_20181030\_101843.jpg

Observation Text : Wash basin cracked

8: Mirror



9: Soap /Supplies



10: Door /Walls / Ceiling NC



Observation Text:

Doors and door frames bottoms to be polished and ceiling undulations

11: Exhaust NC



Attachments:

QUE355\_IMG\_20181030\_101942.jpg

Observation Text:

To be painted

12: Urinal. Not Applicable

13: Mattress / Other things



Section: Rest Rooms

Subsection: EXECUTIVES GENTS LOCKER

1: Taps.

	Groom and Gorporato Maant Toan
2: Maintenance.  Yes	
3: Smell. NC No	
Observation Text : Not smelling fresh	
4: Floor.  Yes	
5: Tiles.  Yes	
6: W/C Yes	
7: Basin.  Yes	
8: Mirror  Yes	
9: Soap /Supplies Yes	
10: Door /Walls / Ceiling Yes	
11: Exhaust NC No	
Observation Text : Exhausts to be cleaned	
12: Urinal.  Yes	
13: Mattress / Other things  Yes	
Section: Rest Rooms Subsection: EXECUTIVES LADIES LOCKER	
1: Taps.  Yes	
2: Maintenance. NC  No	

Observation Text: Smelling not fresh - Drain smell 3: Smell. NC No Observation Text: Not smelling fresh 4: Floor. Yes 5: Tiles. Yes 6: W/C Yes 7: Basin. Yes 8: Mirror Yes 9: Soap /Supplies Yes 10: Door /Walls / Ceiling NC No Observation Text: Door paint peeling off 11: Exhaust NC No Observation Text: Exhaust to be cleaned 13: Mattress / Other things ( Yes Section: Rest Rooms Subsection: STAFF GENTS LOCKER 1: Taps. Yes 2: Maintenance. Yes

	Green Park Corporate Audi	l rear
3: Smell.  Yes		
4: Floor.  Yes		
5: Tiles.  Yes		
6: W/C Yes		
7: Basin.  Yes		
8: Mirror NC No		
Observation Text : Mirror frame to be painted		
9: Soap /Supplies  Yes		
10: Door /Walls / Ceiling  Yes		
11: Exhaust  Yes		
12: Urinal.  Yes		
13: Mattress / Other things NC No		
Section: Rest Rooms Subsection: POOL SIDE MENS REST ROOM		
1: Taps.  Yes		
2: Maintenance. NC  No  Attachments:  QUE398_IMG_20181030_112750.jpg		
Observation Text: Light to be fixed properly in front of mirror		
3: Smell. NC		



Observation Text: Not smelling fresh

4: Floor.



5: Tiles.



6: W/C



7: Basin.



8: Mirror



9: Soap /Supplies



10: Door /Walls / Ceiling NC



Attachments:

QUE406\_IMG\_20181030\_112843.jpg

Observation Text:

Damaged door veneer to be changed

11: Exhaust NC



Attachments:

QUE407\_IMG\_20181030\_112923.jpg

12: Urinal.



13: Mattress / Other things NC



Attachments:

QUE409\_IMG\_20181030\_112950.jpg

Observation Text: Table to he polished

Section: Rest Rooms

Subsection: POOL SIDE LADIES REST ROOM

1: Taps.



	Green Park Corporate Audit Team
2: Maintenance.  Yes	
3: Smell.  Yes	
4: Floor.  Yes	
5: Tiles.  Yes	
6: W/C  Yes	
7: Basin.  Yes	
8: Mirror  Yes	
9: Soap /Supplies  Yes	
10: Door /Walls / Ceiling NC  No  Attachments:  QUE419_IMG_20181030_112420.jpg  QUE419_IMG_20181030_112501.jpg  Observation Text:	
Damaged door bottom veneer to be changed  11: Exhaust	
Yes  12: Urinal.  Not Applicable	
13: Mattress / Other things  Yes	
Section: Rest Rooms Subsection: BAR LADIES	
1: Taps.  Yes	
2: Maintenance.  Yes	
3: Smell.	

	Green Park Corporate Audit Team.
Yes	
4: Floor.	
Yes	
5: Tiles.	
Yes	
6: W/C	
Yes	
7: Basin.	
Yes	
8: Mirror	
Yes	
9: Soap /Supplies	
Yes	
10: Door /Walls / Ceiling NC	
No Attachments:	
QUE432_IMG_20181030_111952.jpg	
Observation Text :	
Door bottom damaged	
11: Exhaust	
Yes	
12: Urinal.   Not Applicable	
13: Mattress / Other things	
Yes	
Section: Rest Rooms	
Subsection: BAR GENTS	
1: Taps.	
Yes	
2: Maintenance.	
Yes	
3: Smell.	
Yes	

4: Floor.

Yes

5: Tiles. NC No Attachments: QUE440\_IMG\_20181030\_111724.jpg Observation Text: Incomplete work 6: W/C Yes 7: Basin. Yes 8: Mirror Yes 9: Soap /Supplies Yes 10: Door /Walls / Ceiling Yes 11: Exhaust Yes 13: Mattress / Other things Yes Section: Floors - Guest Rooms Subsection: 329 1: Ceiling Yes 2: Walls/ Photo Frames Yes 3: Floor Yes 4: WINDOW PANE \ LEDGES ( Yes 5: BED LINEN. ( Yes 6: UPHOLSTRY\CURTAINS Yes

	Croom and Corporato maan	
7: TV\TEL\AC.  Yes		
8: SUPP\STATIONERY.  O Yes		
9: MAINTENANCE  Yes		
10: DUSTING  Yes		
11: TIDINESS.  Yes		
12: FURNITURE.  Yes		
13: GUEST BATHROOMS.  Yes		
14: FLOORS. NC  No  Attachments:  QUE564_IMG_20181029_091907.jpg		
Observation Text : Carpets are very dirty - To be shampooed		
15: BATHTUB\WC.  Yes		
16: WASHBASIN \ COUNTER  Yes		
17: MIRRORS. NC  No  Attachments:  QUE567_IMG_20181029_091623.jpg		
Observation Text : Mirror tarnished		
18: DUSTING.  Yes		
19: MAINTENANCE.  Yes		
20: SUPP\STATIONERY\BATH LINEN  Yes		

Section: Floors - Guest Rooms Subsection: 333 1: Ceiling NC No Attachments: QUE571\_IMG\_20181029\_092329.jpg Observation Text: Ceiling seepage at spot light above bed 2: Walls/ Photo Frames Yes 3: Floor Yes 4: WINDOW PANE \ LEDGES NC No Attachments: QUE574\_IMG\_20181029\_092522.jpg Observation Text: To be cleaned and polish

5: BED LINEN. NC



Attachments:

QUE575\_IMG\_20181029\_092636.jpg

Observation Text:

Stains on duvet cover

6: UPHOLSTRY \ CURTAINS NC



Attachments:

QUE576\_IMG\_20181029\_092721.jpg

Observation Text:

Black out badly damaged

7: TV\TEL\AC.



8: SUPP\STATIONERY. NC




Attachments:

QUE578\_IMG\_20181029\_092843.jpg

Observation Text:

Coffee mugs not cleaned properly

9: MAINTENANCE



Section: Floors - Guest Rooms
Subsection: 318

1: Ceiling NC No Attachments :

QUE591\_IMG\_20181029\_093645.jpg QUE591\_IMG\_20181029\_093707.jpg

2: Walls/ Photo Frames



3: Floor



4: WINDOW PANE \ LEDGES NC



Attachments:

QUE594\_IMG\_20181029\_093846.jpg

Observation Text:

Window sill belched

5: BED LINEN.



6: UPHOLSTRY\CURTAINS



7: TV\TEL\AC.



8: SUPP\STATIONERY.



9: MAINTENANCE



10: DUSTING



11: TIDINESS.



12: FURNITURE.



13: GUEST BATHROOMS. NC




Attachments:

QUE603\_IMG\_20181029\_094246.jpg QUE603\_IMG\_20181029\_094328.jpg

Observation Text:

Bathroom ceiling seepage, Head shower rusted

14: FLOORS.



- 5: BED LINEN.
  - Yes
- 6: UPHOLSTRY\CURTAINS
  - Yes
- 7: TV\TEL\AC.
  - Yes
- 8: SUPP\STATIONERY.
  - Yes
- 9: MAINTENANCE NC

	Green Park Corporate Audit Team
<b>○</b> No	
Attachments:	
QUE619_IMG_20181029_095000.jpg	
Observation Text :	
Safety latch is not working	
10: DUSTING	
Yes	
11: TIDINESS.	
Yes	
12: FURNITURE.	
Yes	
13: GUEST BATHROOMS.	
Yes	
14: FLOORS.	
Yes	
15: BATHTUB\WC. NC	
No	
Attachments :	
QUE625_IMG_20181029_095156.jpg	
Observation Text :	
Water scales on shower cubicle glasses	
16: WASHBASIN \ COUNTER	
Yes	
17: MIRRORS.	
Yes	
18: DUSTING.	
Yes	
19: MAINTENANCE.	
Yes	
20: SUPP\STATIONERY\BATHLINEN	
Yes	
Section: Floors - Guest Rooms	
Subsection: 234	
1: Ceiling NC	
<b>◎</b> No	

Attachments:

QUE631\_IMG\_20181029\_095618.jpg Observation Text: Ceiling seepage 2: Walls/ Photo Frames Yes 3: Floor Yes 4: WINDOW PANE \ LEDGES Yes 5: BED LINEN. Yes 6: UPHOLSTRY\CURTAINS Yes 7: TV\TEL\AC. Yes 8: SUPP \ STATIONERY. Yes 9: MAINTENANCE Yes 10: DUSTING NC No Observation Text: Dust on study chair, skirtings 11: TIDINESS. NC No Attachments: QUE641\_IMG\_20181029\_100018.jpg Observation Text: Dressing mirror not cleaned 12: FURNITURE. NC No Attachments: QUE642\_IMG\_20181029\_095916.jpg Observation Text:

Coffee table legs tp be dusted

13: GUEST BATHROOMS. NC

73

	Green Park Corporate Au
<b>●</b> No	
Attachments:	
QUE643_IMG_20181029_100116.jpg	
Observation Text :	
Bathroom Ceiling seepage	
14: FLOORS.	
Yes	
15: BATHTUB\WC. NC	
No No	
Attachments:	
QUE645_IMG_20181029_100247.jpg	
Observation Text :	
To be cleaned	
16: WASHBASIN \ COUNTER	
Yes	
17: MIRRORS.	
Yes	
18: DUSTING.	
Yes	
19: MAINTENANCE.	
Yes	
20: SUPP\STATIONERY\BATH LINEN	
Yes	
Section: Floors - Guest Rooms	
Subsection: 237	
1: Ceiling	
Yes	
2: Walls/ Photo Frames	
Yes	
3: Floor	
Yes	

4: WINDOW PANE \ LEDGES

Yes

5: BED LINEN. Yes

74

6: UPHOLSTRY\CURTAINS  Yes
7: TV\TEL\AC.  Yes
8: SUPP\STATIONERY.  O Yes
9: MAINTENANCE  Yes
10: DUSTING NC No
Observation Text : Dust on windows and skirting
11: TIDINESS.  Yes
12: FURNITURE.  Yes
13: GUEST BATHROOMS. NC  No  Attachments:  QUE663_IMG_20181029_100936.jpg
Observation Text : Bathroom ceiling seepage
14: FLOORS.  Yes
15: BATHTUB\WC.  Yes
16: WASHBASIN \ COUNTER  Yes
17: MIRRORS.  Yes
18: DUSTING.  Yes
19: MAINTENANCE.  Yes
20: SUPP\STATIONERY\BATH LINEN



Section: Floors - Guest Rooms

Subsection: 2111

1: Ceiling



2: Walls/ Photo Frames



3: Floor NC



Observation Text:

Carpet is dirty

4: WINDOW PANE \ LEDGES NC



Attachments:

QUE674\_IMG\_20181029\_101424.jpg

Observation Text:

To be polished

5: BED LINEN.



6: UPHOLSTRY \ CURTAINS



7: TV\TEL\AC.



8: SUPP\STATIONERY.



9: MAINTENANCE



10: DUSTING NC



Attachments:

QUE680\_IMG\_20181029\_101814.jpg

Observation Text:

Dust on coffee table legs

11: TIDINESS.



12: FURNITURE.



13: GUEST BATHROOMS. NC



Attachments:

QUE683\_IMG\_20181029\_101946.jpg QUE683\_IMG\_20181029\_102057.jpg

Observation Text:

Picture frame to be replaced, Bathroom ceiling paint peeling off

14: FLOORS.



15: BATHTUB\WC.



16: WASHBASIN \ COUNTER



17: MIRRORS.



18: DUSTING.



19: MAINTENANCE.



20: SUPP \ STATIONERY \ BATH LINEN



Section: Floors - Guest Rooms

Subsection: 414

1: Ceiling



2: Walls/ Photo Frames NC



Attachments:

QUE692\_IMG\_20181029\_112737.jpg

Observation Text:

Alignment not proper

3: Floor NC



Observation Text:

Stains and scratches on floor, Carpet is dirty

	WINDOW PANE \ LEDGES NC  No  Attachments:
	QUE694_IMG_20181029_112849.jpg
	Observation Text : To be polished
5:	BED LINEN.  Yes
6:	UPHOLSTRY \ CURTAINS NC No
	Observation Text : Only one sheer curtain is there
7:	TV \ TEL \ AC.  Yes
8:	SUPP\STATIONERY.  Yes
9:	MAINTENANCE  Yes
10	: DUSTING  Yes
11	: TIDINESS. NC  No
	Observation Text : Minibar cabinet door to be cleaned properly
12	: FURNITURE.  O Yes
13	: GUEST BATHROOMS.  OYes
14	: FLOORS.  Yes
15	: BATHTUB\WC. NC
,	Attachments : QUE705_IMG_20181029_113106.jpg
	Observation Text : WC hinges caps to be fixed

16: WASHBASIN \ COUNTER  Yes	
17: MIRRORS.  Yes	
18: DUSTING.  Yes	
19: MAINTENANCE.  Yes	
20: SUPP \ STATIONERY \ BATH LINEN NC  No Attachments: QUE710_IMG_20181101_093857.jpeg  Observation Text:	
Threads on bath towels	
Section: Floors - Guest Rooms Subsection: 510	
1: Ceiling  Yes	
2: Walls/ Photo Frames  Yes	
3: Floor NC No	
Observation Text: Wooden floor gaps to be closed	
4: WINDOW PANE \ LEDGES  Yes	
5: BED LINEN. NC  No  Attachments:  QUE715_IMG_20181029_113705.jpg	
Observation Text : Stain bed sheet placed and stain covered with talcum powder	
6: UPHOLSTRY \ CURTAINS  Yes	
7: TV\TEL\AC.  Yes	

8: S	Yes
	MAINTENANCE  Yes
	DUSTING  Yes
	TIDINESS.  Yes
Att	FURNITURE. NC  No Pachments:  QUE722_IMG_20181029_113908.jpg
	servation Text :  ffee table legs damaged
	GUEST BATHROOMS.  Yes
Att	FLOORS. NC  No achments: QUE724_IMG_20181029_114017.jpg
	eservation Text : air on Floor
15:	BATHTUB \ WC.  Yes
	WASHBASIN \ COUNTER  Yes
	MIRRORS.  Yes
	DUSTING.  Yes
	MAINTENANCE.  Yes
20:	SUPP \ STATIONERY \ BATH LINEN  Yes
	ion: Floors - Guest Rooms section: 517

1:	Ceiling  Yes
	Walls/ Photo Frames NC  No  Attachments:  QUE732_IMG_20181029_114506.jpg
	Observation Text : Fungus on wall
3:	Floor  Yes
4:	WINDOW PANE \ LEDGES  Yes
5:	BED LINEN.  Yes
6:	UPHOLSTRY \ CURTAINS  Yes
7:	TV \ TEL \ AC.  Yes
8:	SUPP \ STATIONERY.  Yes
9:	MAINTENANCE  Yes
	: DUSTING NC  No  Attachments :  QUE740_IMG_20181029_114632.jpg
	Observation Text : Dust on coffee table legs
11	: TIDINESS.  Yes
	: FURNITURE. <b>NC</b> No  Attachments:  QUE742_IMG_20181029_114710.jpg
	Observation Text : Coffee table legs damaged

13:	GUEST BATHROOMS.  Yes
14:	FLOORS.  Yes
	BATHTUB \ WC. NC  No  ttachments:  QUE745_IMG_20181029_114850.jpg
	bservation Text : tains on WC
16:	WASHBASIN \ COUNTER  Yes
17:	MIRRORS.  Yes
18:	DUSTING.  Yes
19:	MAINTENANCE.  Yes
20:	SUPP \ STATIONERY \ BATH LINEN  Yes
	tion: Floors - Guest Rooms esection: 533
	Ceiling NC  No  ttachments:  QUE751_IMG_20181029_115509.jpg
	bservation Text : eiling seepage
2:	Walls/ Photo Frames  Yes
3:	Floor Yes
4:	WINDOW PANE \ LEDGES  Yes
5:	BED LINEN.  Yes

	_•
6: UPHOLSTRY\CURTAINS NC  No	
Observation Text : Black out to be pasted	
7: TV\TEL\AC.  Yes	
8: SUPP\STATIONERY. NC  No	
Observation Text : Drinking glasses not wiped	
9: MAINTENANCE  Yes	
10: DUSTING  Yes	
11: TIDINESS.  Yes	
12: FURNITURE. NC  No  Attachments:  QUE762_IMG_20181029_115831.jpg	
Observation Text : To be polished	
13: GUEST BATHROOMS. NC No	
Observation Text : Bathroom ceiling seepage	
14: FLOORS. NC  No  Attachments:  QUE764_IMG_20181029_120007.jpg	
Observation Text : Bathroom floor to be scrubbed and clean	
15: BATHTUB\WC.  Yes	
16: WASHBASIN \ COUNTER NC  No  Attachments:	

Green Park Corporate Audit Team. QUE766\_IMG\_20181029\_120110.jpg Observation Text: White scales around wash basin tap 17: MIRRORS. Yes 18: DUSTING. NC No Attachments: QUE768\_IMG\_20181029\_120208.jpg Observation Text: Toilet roll holders stained 19: MAINTENANCE. Yes 20: SUPP\STATIONERY\BATHLINEN Yes Section: Floors - Guest Rooms Subsection: 537 1: Ceiling NC No Observation Text: Room ceiling seepage 2: Walls/ Photo Frames Yes 3: Floor Yes 4: WINDOW PANE \ LEDGES NC No Attachments: QUE774\_IMG\_20181029\_120726.jpg Observation Text: To be cleaned 5: BED LINEN. Yes

6: UPHOLSTRY\CURTAINS

Yes

7: TV\TEL\AC.



19: MAINTENANCE. NC

No

20: SUPP\STATIONERY\BATH LINEN

Yes

Section: Floors - Guest Rooms Subsection: 633 1: Ceiling Yes 2: Walls/ Photo Frames NC No Attachments: QUE792\_IMG\_20181029\_121437.jpg Observation Text: Stains on wall 3: Floor Yes 4: WINDOW PANE \ LEDGES Yes 5: BED LINEN. Yes 6: UPHOLSTRY\CURTAINS Yes 7: TV\TEL\AC. Yes 8: SUPP\STATIONERY. Yes 9: MAINTENANCE Yes 10: DUSTING Yes 11: TIDINESS. NC No Observation Text: Wardrobe doors and bathroom doors to be wiped 12: FURNITURE. NC No Attachments: QUE802\_IMG\_20181029\_121628.jpg QUE802\_IMG\_20181029\_122135.jpg Observation Text:

Green Park Corporate Audit Team. Coffee table top polishing to be done, Writing table top also to be polished 13: GUEST BATHROOMS. NC No Attachments: QUE803\_IMG\_20181029\_121827.jpg 14: FLOORS. NC No Attachments: QUE804\_IMG\_20181029\_121739.jpg Observation Text: Patches on floor 15: BATHTUB\WC. Yes 16: WASHBASIN \ COUNTER Yes 17: MIRRORS. Yes 18: DUSTING. Yes 19: MAINTENANCE. Yes 20: SUPP\STATIONERY\BATHLINEN Yes Section: Floors - Guest Rooms Subsection: 629 1: Ceiling ( Yes 2: Walls/ Photo Frames ( Yes 3: Floor ( Yes 4: WINDOW PANE \ LEDGES NC No Attachments: QUE814\_IMG\_20181029\_123632.jpg

Observation Text:

window glass not cleaned

5: BED LINEN. NC



Attachments :

QUE815\_IMG\_20181029\_123520.jpg

Observation Text:

Hair on bed

6: UPHOLSTRY\CURTAINS



7: TV \ TEL \ AC.



8: SUPP \ STATIONERY.



9: MAINTENANCE



10: DUSTING



11: TIDINESS.



12: FURNITURE. NC



Attachments:

QUE822\_IMG\_20181029\_123720.jpg QUE822\_IMG\_20181029\_123740.jpg

Observation Text:

Table tops tp be polished

13: GUEST BATHROOMS. NC



Attachments:

QUE823\_IMG\_20181029\_123826.jpg QUE823\_IMG\_20181029\_124113.jpg

Observation Text:

Door corners to be cleaned, Drain flies are in bathroom

14: FLOORS. NC



Attachments:

QUE824\_IMG\_20181029\_123950.jpg

Observation Text:

Green Park Corporate Audit Team. Stains on floor 15: BATHTUB\WC. Yes 16: WASHBASIN \ COUNTER Yes 17: MIRRORS. Yes 18: DUSTING. Yes 19: MAINTENANCE. Yes 20: SUPP\STATIONERY\BATH LINEN Yes Section: Floors - Guest Rooms Subsection: 610 1: Ceiling Yes 2: Walls/ Photo Frames Yes 3: Floor Yes 4: WINDOW PANE \ LEDGES NC No Attachments: QUE834\_IMG\_20181029\_124752.jpg Observation Text: Window sill to be polished 5: BED LINEN. NC No Attachments: QUE835\_IMG\_20181029\_125148.jpg Observation Text:

7: TV \ TEL \ AC.

Yes

Mattress bent

6: UPHOLSTRY \ CURTAINS



8: SUPP\STATIONERY.



9: MAINTENANCE



10: DUSTING



11: TIDINESS. NC



Attachments:

QUE841\_IMG\_20181029\_125626.jpg

Observation Text:

Stains on luggage rack

12: FURNITURE. NC



Attachments:

QUE842\_IMG\_20181029\_125316.jpg QUE842\_IMG\_20181029\_125332.jpg

Observation Text:

Table tops to be polished

13: GUEST BATHROOMS. NC



Attachments:

QUE843\_IMG\_20181029\_125756.jpg QUE843\_IMG\_20181029\_125811.jpg

Observation Text:

Water scLes on glass doors

14: FLOORS. NC



Observation Text:

Stains on floor

15: BATHTUB\WC.




16: WASHBASIN \ COUNTER



17: MIRRORS.



•	
18: DUSTING.  Yes	
19: MAINTENANCE.  Yes	
20: SUPP\STATIONERY\BATH LINEN  Yes	
Section: Floors - Guest Rooms Subsection: 430	
1: Ceiling  Yes	
2: Walls/ Photo Frames NC  No Attachments: QUE852_IMG_20181029_130706.jpg	
Observation Text : No alignment	
3: Floor  Yes	
4: WINDOW PANE \ LEDGES  Yes	
5: BED LINEN.  Yes	
6: UPHOLSTRY\CURTAINS  Yes	
7: TV\TEL\AC.  Yes	
8: SUPP\STATIONERY.  Yes	
9: MAINTENANCE  Yes	
10: DUSTING  Yes	
11: TIDINESS.  Yes	
12: FURNITURE.	





- Yes
- 18: DUSTING. Yes
- 19: MAINTENANCE. Yes
- 20: SUPP \ STATIONERY \ BATH LINEN Yes

Section: Floors - Guest Rooms

Subsection: 532 1: Ceiling NC

No

Observation Text: Seepage stains on ceiling

- 2: Walls/ Photo Frames ( Yes
- 3: Floor Yes
- 4: WINDOW PANE \ LEDGES Yes
- 5: BED LINEN. Yes
- 6: UPHOLSTRY \ CURTAINS NC No

		Green Park Corporate Audit Team
	Observation Text : Black out to be pasted properly	
7:	TV \ TEL \ AC.  Yes	
8:	SUPP\STATIONERY.  Yes	
9:	MAINTENANCE  Yes	
10:	DUSTING  Yes	
11:	TIDINESS.  Yes	
12:	FURNITURE.  Yes	
13:	GUEST BATHROOMS. NC No	
	Observation Text : Seepage stains on ceiling	
14:	FLOORS.  Yes	
15:	BATHTUB \ WC.  Yes	
16:	WASHBASIN \ COUNTER  Yes	
17:	MIRRORS.  Yes	
18:	DUSTING. NC  No	
	Observation Text : Soap rack and shower cubicle glasses to be cleaned	
19:	MAINTENANCE.  Yes	
20:	SUPP \ STATIONERY \ BATH LINEN  Yes	

Section: Floors - Guest Rooms Subsection: 437	
1: Ceiling  Yes	
2: Walls/ Photo Frames  Yes	
3: Floor  Yes	
4: WINDOW PANE \ LEDGES NC No	
Observation Text : To be cleaned	
5: BED LINEN.  Yes	
6: UPHOLSTRY\CURTAINS  Yes	
7: TV\TEL\AC.  Yes	
8: SUPP\STATIONERY. NC  No	
Observation Text : Supplies tray not dusted	
9: MAINTENANCE  Yes	
10: DUSTING  Yes	
11: TIDINESS. NC No	
Observation Text : Stains on luggage rack	
12: FURNITURE.  Yes	
13: GUEST BATHROOMS. NC  No  Attachments:  QUE903_IMG_20181029_151213.jpg	

Observation Text: Bathroom ceiling seepage anf fungus 14: FLOORS. NC No Observation Text: Patches on floor 15: BATHTUB\WC. NC No Attachments: QUE905\_IMG\_20181029\_151337.jpg Observation Text: Fungus on flush pad 16: WASHBASIN \ COUNTER Yes 17: MIRRORS. Yes 18: DUSTING. Yes 19: MAINTENANCE. Yes 20: SUPP\STATIONERY\BATHLINEN Yes Section: Floors - Guest Rooms Subsection: 332 1: Ceiling Yes 2: Walls/ Photo Frames ( Yes 3: Floor Yes 4: WINDOW PANE \ LEDGES Yes 5: BED LINEN. ( Yes 6: UPHOLSTRY \ CURTAINS NC No

	Green Park Corporate Audit Team
Attachments : QUE916_IMG_20181029_151947.jpg	
Observation Text : Sheer Curtain torn	
7: TV\TEL\AC.  Yes	
8: SUPP\STATIONERY.  Yes	
9: MAINTENANCE  Yes	
10: DUSTING  Yes	
11: TIDINESS.  Yes	
12: FURNITURE.  Yes	
13: GUEST BATHROOMS. NC  No	
Observation Text : Ceiling seepage	
14: FLOORS.  Yes	
15: BATHTUB\WC.  Yes	
16: WASHBASIN \ COUNTER  Yes	
17: MIRRORS.  Yes	
18: DUSTING.  Yes	
19: MAINTENANCE.  Yes	
20: SUPP\STATIONERY\BATHLINEN NC  No	

	Green Fark Corporate Audit Team
Observation Text : Towel rack has stains	
Section: Floors - Guest Rooms Subsection: 201	
1: Ceiling NC No	
Observation Text : Ceiling seepage	
2: Walls/ Photo Frames  Yes	
3: Floor NC No	
Observation Text : Carpet to be shampooed	
4: WINDOW PANE \ LEDGES  Yes	
5: BED LINEN.  Yes	
6: UPHOLSTRY\CURTAINS  Yes	
7: TV\TEL\AC. Yes	
8: SUPP\STATIONERY.  Yes	
9: MAINTENANCE  Yes	
10: DUSTING Yes	
11: TIDINESS.  Yes	
12: FURNITURE.  Yes	
13: GUEST BATHROOMS. NC No	
Observation Text :	

	Croon run Corporato na	iait ioaii
Ceiling seepage		
14: FLOORS.		
Yes		
15: BATHTUB\WC.		
Yes		
16: WASHBASIN \ COUNTER		
Yes		
17: MIRRORS.		
Yes		
18: DUSTING.		
Yes		
19: MAINTENANCE.		
Yes		
20: SUPP\STATIONERY\BATH LINEN		
Yes		
Section: Gloss Level		
Subsection: Marble Floor		
1: Lobby Rating: 8		
Observation Text : Upper lobby		
2: Reception. NC		
Rating: 6		
3: Travel desk.		
Rating: 8		
Observation Text :		
1st floor 1st corridor		
4: OUT Entrance.		
Rating: 8		
5: Bell Desk  Not Applicable		
6: Lobby lounge NC		
Rating: 7		
7: Lobby Entrance NC		
Rating: 7		

- 8: Guest elevator opposite Rating: 8
- 9: Opposite to banquet office Rating: 8
- 10: Gardenia entrance Not Applicable
- 11: Senate Rating: 9

Observation Text:

1st floor 2nd corridor

12: Prefunction of Residency Rating: 8

Observation Text : Vijaya hall entrance

13: Gardenia entranceRating: 8

Observation Text : Vahuni hall entrance

- 14: Tulips NC Rating: 7
- 15: Lobby Gents rest room Rating: 8
- 16: Lobby Ladies rest room Rating: 8
- 17: Banquets Gents rest room Rating: 8

Observation Text : Mustang Bar rest rooms

18: Banquets Ladies rest room Rating: 8

Observation Text : Mustang Bar rest rooms

19: Gardenia entrance NC Rating: 7

Observation Text : Pallavi hall entrance

Section: Linen and Laundry

Subsection: Linen, Laundry & Guest Laundry

1: Linen room stacking

Rating: 10

2: Par stocks

Rating: 10

Observation Text:

Being followed

3: Annual indent

Rating: 10

Observation Text:

Done

4: Discards

Rating: 10

5: Quality of uniforms NC

Rating: 7

Observation Text:

Whiteness of executive shirts and chef coats not up to the mark

6: Quality of linen NC

Rating: 6

Observation Text:

Discarded bath linen to be removed from circulation - Still being placed in guest rooms.

7: Uniform calendar

Rating: 9

Observation Text:

Being followed

8: Exchange timing

Rating: 10

Observation Text:

As per mentioned

9: Uniform exchange system

Rating: 10

Observation Text:

Soil to fresh

10: Inventory of F&B Linen

Rating: 10

Observation Text: Monthly 11: Inventory of Room linen Rating: 10 Observation Text: Monthly 12: Inventory of uniforms Rating: 10 Observation Text: Monthly 13: Pick up collection standards Rating: 10 Observation Text: Being followed 14: Sorting & Checking Rating: 10 Observation Text: Being followed 15: Marking & Tagging Rating: 10 Observation Text: Being followed 16: Processing Rating: 10 Observation Text: Being followed 17: Finishing Rating: 8 Observation Text: Uniform pressing quality should improve 18: Packing Rating: 10 Observation Text: being followed 19: Billing

Rating: 10

Green Park Corporate Audit Team. Observation Text: Being followed 20: Delivery Rating: 10 Observation Text: Being followed 21: Condition of machines Rating: 10 Observation Text: Good 22: Equipment, Preventive maintenance Rating: 10 Observation Text: Being followed fortnightly 23: Standardized chemicals Rating: 10 Observation Text: JD 24: Sorting standards Rating: 10 25: Washing standards Rating: 10 Observation Text: Being followed 26: Finishing standards Rating: 10 27: Stacking standards Rating: 8 Observation Text: Staking of linen and other chair covers should maintain properly 28: Awareness of snow white initiatives NC Rating: 7 Attachments: QUE515\_IMG\_20181030\_170506.jpg Observation Text: According to report given by JD whiteness is low than standard

29: Comfortable temperature in laundry

Rating: 8

Observation Text:

Normal

30: Safe work practices

Rating: 10

Observation Text:

Being followed

31: Use of safety equipment

Rating: 8

Observation Text:

No PPE is being used

32: Quality of processed articles

Rating: 10

Observation Text:

being followed

**Section:** Contractual Service **Subsection:** Contractual Service

1: Schedule of treatment for rooms

Rating: 8

Observation Text:

Rgular spray is happening in rooms

2: Schedule of treatment for kitchen

Rating: 9

Observation Text:

Every Monday and Tuesday happening

3: Schedule of treatment for F&B outlets

Rating: 9

Observation Text:

Every Monday and Tuesday happening

4: Standards of chemicals

Rating: 10

Observation Text:

Byer chemicals are using

5: Staff uniform and grooming

Rating: 10

Observation Text:

## Being followed

6: Effectiveness NC

Rating: 5

Observation Text:

Found drin flies on bathroom ceiling in 629, Cobwebs found in upper lobby, rats issues are there.

7: Quality of flowers & flower vase

Rating: 8

Observation Text:

Good

8: Costing

Rating: 10

Observation Text:

Within budget

9: Skill knowledge

Rating: 10

Observation Text:

Good

10: Maintenance of plants

Rating: 9

Observation Text:

Good

11: Quality of landscaping

Rating: 10

Observation Text:

Good

12: Overall impression

Rating: 9

13: Periphery of the hotel

Rating: 8

Observation Text:

Cleaning should be improved at plants areas

Section: Records

Subsection: Records & Reports

1: Guest supplies

Rating: 10

2: Cleaning supplies

Rating: 10

Observation Text:

Within budget

3: Linen

Rating: 10

4: Uniforms

Rating: 10

5: Lost and found records NC

Rating: 7

6: L&F issues to the claimant NC

Rating: 7

Observation Text:

Filing should be done properly and Valid signatures to be must

7: L&F storage

Rating: 10

8: L&F Letters to guests

Rating: 10

Observation Text:

Auto generated mails are going to guests

9: L&F Disposals

Rating: 10

Observation Text:

Up to date

10: Room history

Rating: 10

11: Duty roaster & allocation register

Rating: 10

12: Attendance record

Rating: 10

13: Log book messages and follow up

Rating: 10

14: Occupancy report (Twice a day)

Rating: 10

15: Under repair status

Rating: 10

16: DND List Rating: 10

17: Property upkeep Report

Rating: 10

18: Monthly meeting reports

Rating: 10