

Second Chance Replacement


Memory Split	Page Frames Page Size		Page Faults	<u>Disk Writes</u>
1:1	8	4KB	103539	63206
1:3	8	4KB	163510	81767
3:1	8	4KB	93875	51215
3:5	8	4KB	130174	71222
5:3	8	4KB	84408	54757



Memory Split	Page Frames Page Si	<u>ze</u> <u>F</u>	age Faults	Disk Writes
1:1	1024	4KB	40168	39342
1:3	1024	4KB	40169	39090
3:1	1024	4KB	40168	39598
3:5	1024	4KB	40168	39214
5:3	1024	4KB	40168	39470
7:9	1024	4KB	40168	39278
9:7	1024	4KB	40168	39406



Memory Split	Page Frames	<u>Page Size</u>		Page Faults	<u>Disk Writes</u>
1:1	8		4MB	988	606
1:3	8		4MB	23592	12927
3:1	8		4MB	400	237
3:5	8		4MB	3350	1827
5:3	8		4MB	458	270



Memory Split	Page Frames	Page Size	Page Faults	Disk Writes
1:1	1024	4MB	58	0
1:3	1024	4MB	58	0
3:1	1024	4MB	58	0
3:5	1024	4MB	58	0
5:3	1024	4MB	58	0
7:9	1024	4MB	58	0
9:7	1024	4MB	58	0

