

Pixel-Level Pavement Distress Assessment Using Instance Segmentation

Logan Dewick, Bibesh Pyakurel, Kong Pheng Yang, Nazim Choudhury, M. G. Sarwar Murshed

Computer Science Department

University of Wisconsin - Green Bay, Green Bay, WI, USA

Abstract—Automated pavement distress assessment requires more than image-level classification or coarse bounding box detection, demanding precise localization of thin, branching, and irregular cracks to achieve the geometric precision necessary for maintenance-relevant quantification. This paper presents a vision-based pavement distress analysis system based on Mask R-CNN instance segmentation and evaluates it on UWGB-STREETCRACK, a custom field-collected roadway image dataset acquired with a vehicle-mounted iPhone 15 Pro Max and manually annotated with polygon labels for longitudinal cracks, transverse cracks, alligator cracks, and potholes. Five Detectron2-based Mask R-CNN backbone variants were considered under a consistent fine-tuning protocol. The best-performing archived test result was obtained by Mask R-CNN with a ResNet-101 FPN backbone, which achieved 84.23% precision, 90.04% recall, and an F1 score of 87.04% under the project-specific bounding-box matching protocol. The same model produced an aggregate predicted crack-area fraction of 2.164%, closely matching the 2.170% ground-truth crack-area fraction. To contextualize the segmentation system against a detector-oriented alternative, a CSPDarknet53-based YOLO detector was also adapted and re-trained on the UWGB data, reaching 27.5% precision and 20.7% recall on the validation protocol. The results show that instance segmentation is a practical direction for field pavement imagery and aggregate crack-area estimation, while also exposing open challenges in annotation consistency, class imbalance, confounder rejection, and mask-level benchmarking.

Index Terms—deep learning, segmentation, computer vision, pavement crack detection

I. INTRODUCTION

PAVEMENT cracks are early indicators of structural deterioration caused by repeated traffic loading, thermal variation, moisture infiltration, construction joints, and material aging. Timely identification of these defects is important because untreated cracks can propagate into potholes and larger structural failures, increasing maintenance costs and reducing road safety. Manual inspection remains widely used, but it is labor-intensive, time-consuming, subjective, and potentially hazardous for inspectors working near active traffic. These limitations have motivated automated pavement distress assessment systems based on computer vision and deep learning.

Modern crack analysis methods can be grouped into three broad families: image- or patch-level classification, object detection, and pixel-level segmentation. Classification models can determine whether a patch contains distress, but they do not recover complete crack geometry. Object detectors localize distress with bounding boxes and are attractive for

efficient deployment, but a rectangular box is a poor geometric representation for thin, curved, disconnected, or branching cracks. Pixel-level segmentation is therefore more appropriate when the objective includes estimating crack area, studying morphology, or supporting downstream pavement-condition indices.

Despite the substantial progress in both segmentation and detection, several gaps remain. Much of the recent road-crack literature still emphasizes bounding-box detection, which is efficient but often too coarse for fine-grained pavement assessment. Conversely, many segmentation studies focus on cropped regions, single-crack scenes, or datasets collected under narrower imaging conditions than those encountered in routine field acquisition. This study is positioned in this gap by evaluating Mask R-CNN instance segmentation on a custom field-collected roadway dataset with four pavement-distress categories [1]. In contrast to box-only detectors, the proposed framework jointly localizes and segments individual distress instances in full roadway images, enabling pixel-level crack-area estimation while also addressing realistic confounders such as shadows, stains, road markings, and irregular crack geometry.

This study focuses on instance segmentation, which jointly detects and delineates individual distress instances. Instance segmentation is particularly useful for full-scene roadway imagery because multiple defects may appear simultaneously and because non-crack visual patterns - such as shadows, tire marks, painted markings, stains, and manhole boundaries - can resemble cracks. Unlike semantic segmentation, instance segmentation preserves object-level separation; unlike box-only detection, it produces masks that can be used to estimate aggregate crack area.

We present a Detectron2-based Mask R-CNN pavement distress pipeline evaluated on UWGB-STREETCRACK, a custom field-collected dataset containing four distress categories: longitudinal cracks, transverse cracks, alligator cracks, and potholes. The paper is an applied empirical study rather than a new network architecture. Its purpose is to assess how established Mask R-CNN variants behave on challenging roadway imagery, to report the preserved project results without altering their values, and to document limitations that must be addressed before the system can be treated as a standardized segmentation benchmark.

The main contributions are as follows:

- 1) We document UWGB-STREETCRACK, a smartphone-

based roadway image dataset with polygon-level annotations for four pavement distress classes.

- 2) We describe a full Mask R-CNN instance-segmentation pipeline for pavement distress localization, mask prediction, and aggregate crack-area estimation.
- 3) We report matched test results for the archived Mask R-CNN experiments, preserving the original precision, recall, F1, and area-fraction values.
- 4) We incorporate an adaptation of the Mandal CSPDarknet53-based YOLO detector on UWGB-STREETCRACK as an object-detection reference protocol.
- 5) We analyze representative failure cases and identify methodological gaps, including annotation ambiguity, minority-class sparsity, and the absence of standard mask-level AP reporting in the current project records.

II. RELATED WORK

A. Classical and Feature-Engineered Crack Detection

Early pavement crack detection studies relied on thresholding, edge detection, morphology, wavelet analysis, path-based extraction, and other handcrafted image-processing operations. These methods exploited the observation that cracks are often darker than the surrounding pavement. CrackTree used a tree-structured representation to trace crack-like patterns from pavement images [2], while CrackForest combined integral channel features with random structured forests to model local crack tokens [3]. Such methods are computationally attractive, but they are sensitive to illumination changes, pavement texture, shadows, stains, and road markings. Their dependence on handcrafted assumptions limits transferability across road surfaces and acquisition conditions.

B. Deep Classification and Semantic Segmentation

Deep convolutional neural networks reduced reliance on handcrafted features by learning representations directly from image data. Zhang *et al.* used CNNs for road crack detection in image patches [4], while Fan *et al.* formulated crack detection as structured prediction with CNNs that generate dense crack probability maps [5]. Encoder-decoder architectures further improved pixel-level delineation. U-Net popularized skip-connected semantic segmentation [6], and pavement-specific variants such as DeepCrack [7], FPCNet [8], and black-box road-image encoder-decoder models [9] showed the value of multi-scale fusion for thin structures.

Semantic segmentation is well-suited to crack extraction because it predicts crack regions at the pixel level. However, semantic segmentation alone generally does not separate adjacent distress instances. This can matter when a pavement image contains multiple cracks, mixed distress classes, or ambiguous alligator patterns that may be annotated as either one connected distress region or several individual cracks.

C. Object Detection and Hybrid Pipelines

Object detectors such as Faster R-CNN [10], [11], YOLO-family models, CenterNet, and EfficientDet have been widely

used for pavement distress localization because they are efficient and can handle multiple classes. Mandal *et al.* compared deep learning frameworks for pavement distress classification and detection using YOLO, CenterNet, and EfficientDet-style detectors [12]. Hu *et al.* investigated deep learning models for pavement crack detection [13]. More recent detector-oriented studies have improved speed and robustness through lightweight multi-scale feature fusion and YOLO modifications [14], [15].

Hybrid pipelines have attempted to combine detection and segmentation. Feng *et al.* integrated SSD-style localization with U-Net segmentation for pavement crack detection and surface-feature measurement [16]. Liu *et al.* proposed a two-step CNN in which a YOLOv3-based detector first identifies candidate regions and a modified U-Net then segments cracks within those regions [17]. These approaches highlight the practical value of segmentation whenever crack geometry or area is needed.

D. Instance Segmentation for Pavement Distress

Instance segmentation models aim to retain the localization advantages of detectors while producing masks for each detected object. Mask R-CNN extends Faster R-CNN with a parallel mask branch for each Region of Interest (RoI) [1]; Feature Pyramid Networks (FPNs) improve multi-scale detection by combining features at different resolutions [18]. Pavement-specific instance-segmentation work has also emerged, including YOLOv7-WMF with connected feature fusion for pavement crack instance segmentation [19] and SparseInst-CDSM for real-time crack detection [20].

Most segmentation studies focus on cropped regions, single-crack scenes, or datasets collected under narrower imaging conditions than those encountered in routine field acquisition. The present study is positioned in this gap by evaluating Mask R-CNN instance segmentation on a custom field-collected roadway dataset with four pavement-distress categories.

III. DATASET

A. Acquisition Protocol

The UWGB-STREETCRACK dataset was collected from roadway imagery using an iPhone 15 Pro Max mounted on the front of a vehicle, as shown in Fig. 1. The phone recorded videos while the vehicle traversed local roads. The videos were transferred to a computer and converted into still frames. A Python-based extraction step was used to reduce repeated coverage of the same roadway regions, so the resulting image set contained unique or minimally overlapping scenes. Research assistants then reviewed the images to remove duplicates, unclear frames, and blurry frames before annotation.

B. Annotation Taxonomy and Quality Control

The cleaned images were annotated in Label Studio using polygon masks, as illustrated in Fig. 2. The four-class taxonomy used in the stored annotation files consists of longitudinal cracks, transverse cracks, alligator cracks, and potholes.



Fig. 1. Vehicle-mounted smartphone used to collect field pavement imagery for UWGB-STREETCRACK.




Fig. 2. Polygon-based pavement distress annotation in Label Studio. The workflow produced COCO-style polygon annotations for the four target classes.

Longitudinal cracks run approximately parallel to the road-way direction, whereas transverse cracks run approximately perpendicular to it. Alligator cracks are interconnected crack networks associated with repeated loading or structural failure, and potholes are bowl-shaped depressions often associated with the progression of untreated cracking [21]. No fifth “block” category is present in the annotation schema analyzed for this manuscript.

Each valid annotation includes a class label, a bounding box, and one or more polygon segments. The polygon representation was essential because the target task is instance segmentation rather than box-only detection. Annotation ambiguity remained a challenge: stains, markings, manhole edges, and faint linear texture can resemble cracks, and annotators may disagree about whether a connected pattern should be labeled as one alligator-crack instance or as multiple longitudinal and transverse cracks.

Table I summarizes the available split statistics. The stored training and validation splits contain 1,643 images and 2,090 labeled distress instances. The manuscript uses a separate held-out test partition with 231 images and 261 labeled instances

to solely test the performance of the trained models.

IV. METHODOLOGY

A. Instance-Segmentation Pipeline

The proposed pavement distress system is based on Mask R-CNN [1] implemented in Detectron2 [22]. The pipeline consists of four stages: (i) field image curation and polygon annotation export, (ii) conversion of polygon annotations into binary instance masks during data loading, (iii) supervised fine-tuning of Mask R-CNN variants initialized from COCO-pretrained checkpoints, and (iv) thresholded inference followed by project-specific matching for evaluation.

During training, Label Studio polygon coordinates were interpreted as closed contours and rasterized into binary masks using the standard COCO polygon handling in Detectron2. Invalid polygons with fewer than three vertices were excluded. Each valid polygon generated one instance mask aligned to the image coordinate system. No offline cropping was used for the full-image Mask R-CNN experiments.

B. Preprocessing and Augmentation

All images were resized while preserving aspect ratio. Following the Detectron2 model-zoo protocol for the selected Mask R-CNN family, the shorter side was normalized to 800 pixels and the longer side was capped at 1333 pixels. Zero padding, when needed for batching and stride-compatible tensors, was applied only after resizing.

The final augmentation policy was intentionally conservative because the field images already contain substantial appearance variation. Training used random horizontal flipping with probability 0.5 together with the multi-scale resizing described above. No color jitter, blur, CutMix, mosaic augmentation, random rotation, or additional synthetic perturbation was used in the final reported experiments.

C. Mask R-CNN Variants

Five Mask R-CNN backbone variants were considered in the project pipeline. Table II summarizes the model families and their relative backbone complexity. The archived quantitative results available for this manuscript report the matched test performance for the ResNet-50 FPN and ResNet-101 FPN variants; no additional class-wise or complete per-variant test logs were available for inclusion.

D. Mask R-CNN Training Protocol

Training and inference were performed on an Ubuntu 24.04 LTS workstation equipped with an NVIDIA GeForce RTX 4080 SUPER GPU, an Intel Core i9 CPU, and 32 GB DDR4 RAM. The software environment included PyTorch 2.4.0 with CUDA 12.1, Detectron2, OpenCV 4.5.2, NumPy, and Matplotlib.

For the reported Mask R-CNN experiments, the annotated images were divided into training, validation, and test subsets following a 70/15/15 split, with the held-out test partition containing 231 images and 261 labeled crack instances. All Mask R-CNN variants were initialized from COCO-pretrained

TABLE I
DATASET SPLIT SUMMARY AND LABEL COUNTS FOR THE CURRENT UWGB-STREETCRACK REPOSITORY SNAPSHOT.

Split	Images	Instances	Longitudinal	Transverse	Alligator	Pothole
Train + validation	1643	2090	912	986	97	95
Test split	231	261	112	123	14	12

TABLE II
ARCHITECTURAL SUMMARY OF THE MASK R-CNN VARIANTS CONSIDERED IN THE PROJECT. PARAMETER COUNTS AND REFERENCE FLOP VALUES CORRESPOND TO THE BACKBONE FAMILY ONLY; END-TO-END DETECTOR COST ALSO DEPENDS ON FPN CONSTRUCTION, PROPOSAL COUNT, AND INPUT IMAGE SIZE.

Variant	Backbone / neck	Approx. backbone parameters	Reference backbone FLOPs	Relative detector cost
R50-FPN 3x	ResNet-50 + FPN	25.6M	4.1 GFLOPs	Medium
R101-C4	ResNet-101 + C4 features	44.5M	7.8 GFLOPs	Medium-high
R101-DC	ResNet-101 + dilated convolution features	44.5M	7.8+ GFLOPs	High
R101-FPN 3x	ResNet-101 + FPN	44.5M	7.8 GFLOPs	High
X101-FPN	ResNeXt-101 + FPN	88.8M	16.5 GFLOPs	Very high

model-zoo weights and fine-tuned with stochastic gradient descent using momentum 0.9, weight decay 0.0001, initial learning rate 0.001, and global batch size 8. The results reported here correspond to a 40-epoch schedule applied consistently across the evaluated variants. The learning rate was decayed by a factor of 0.1 at epoch 24 and epoch 33. Model selection was performed on the validation partition, and the selected checkpoint was used for test-time analysis.

The preserved project records are sufficient to report the epoch-based schedule and validation-based checkpointing, but they do not include the exact total iteration count, a full warmup specification, or complete loss curves. Consequently, this paper does not claim convergence behavior from archived loss plots.

E. Detector Baseline Adaptation

To provide a detector-oriented reference, the CSPDarknet53-based YOLO model associated with Mandal *et al.* [12] was adapted to UWGB-STREETCRACK. The dataset was reorganized in YOLO format, with each image paired with a label file containing class identifiers and normalized bounding-box coordinates in the form

$$\langle \text{class_id} \rangle \langle x_{\text{center}} \rangle \langle y_{\text{center}} \rangle \langle w \rangle \langle h \rangle. \quad (1)$$

Several corrections were required before training: malformed label entries were removed or reformatted, empty or invalid labels were handled, the dataset configuration was updated to point to the UWGB-STREETCRACK training and validation paths, the number of classes was set to four, deprecated NumPy usage was replaced, tensor device mismatches were fixed, source-code indentation and formatting inconsistencies were resolved, and the evaluation pipeline was corrected to convert model outputs into the expected metric format.

The detector was trained from scratch because the available pretrained weights were associated with other datasets and

were not suitable for direct comparison. Training used 640×640 input resolution, batch size 16, the default optimizer configuration from the implementation, and 100 epochs, with additional experiments extending beyond 100 epochs. The training behavior indicated convergence around 70–80 epochs; extending training to 200 epochs did not yield significant performance improvements. The best-performing checkpoint according to validation mAP was used for the final detector evaluation reported in Section VI.

F. Segmentation-Based Reference Adaptation

In addition to the detection-based YOLO reference model, we considered DeepSegmentor [23] as a segmentation-based reference method for pixel-level crack-area comparison. DeepSegmentor is a convolutional neural network-based crack segmentation approach originally designed to predict crack regions from image patches rather than from complete roadway scenes. Following this design, we adapted DeepSegmentor as a crop-level segmentation reference: crack-containing regions were manually cropped from the roadway images and then provided to the model for binary crack-mask prediction. The resulting masks were used to compute the detected crack-area percentage and compare it with the ground-truth annotated crack area. This adaptation allowed DeepSegmentor to be evaluated for its pixel-level segmentation capability, but it also imposed an important limitation. Because the model operates on cropped crack regions, it does not perform full-image crack localization and is not designed to distinguish cracks from other scene-level objects such as road markings, shadows, stains, lane lines, or pavement texture. Therefore, DeepSegmentor was used only as a segmentation-area reference, whereas the proposed Mask R-CNN framework was evaluated as an end-to-end model that performs localization, classification, and pixel-level segmentation jointly on full roadway images.

G. Inference Configuration

At inference time, images followed the same aspect-ratio-preserving resize pipeline used during training, without stochastic augmentation. The Region Proposal Network used anchor sizes of 32, 64, 128, 256, and 512 pixels and aspect ratios of 0.5, 1.0, and 2.0. The RPN non-maximum suppression threshold was 0.65, and the final detection-stage non-maximum suppression threshold was 0.5. The final confidence threshold of 0.75 was selected on the validation partition because it provided the best precision-recall balance under the project protocol; it was then held fixed for test evaluation.

V. EVALUATION PROTOCOL

The current project records support a bounding-box-matched secondary evaluation of the Mask R-CNN predictions and an object-detection validation evaluation for the Mandal baseline. The Mask R-CNN precision, recall, F1, and detection-rate values should therefore be interpreted as project-specific detector-style summaries rather than as COCO-style mask AP.

For Mask R-CNN, predicted instances were matched to ground-truth annotations on a per-image basis using bounding-box Intersection over Union (IoU):

$$\text{IoU} = \frac{|B_p \cap B_g|}{|B_p \cup B_g|}, \quad (2)$$

where B_p is the predicted bounding box and B_g is the ground-truth bounding box. A prediction was counted as a true positive if its class label matched the ground-truth class and its bounding-box IoU was at least 0.1. Each predicted instance could be assigned to at most one ground-truth instance. Unmatched predictions were counted as false positives and unmatched ground-truth instances were counted as false negatives.

Precision, recall, and F1 score were computed as

$$\text{Precision} = \frac{TP}{TP + FP}, \quad (3)$$

$$\text{Recall} = \frac{TP}{TP + FN}, \quad (4)$$

$$F1 = 2 \cdot \frac{\text{Precision} \cdot \text{Recall}}{\text{Precision} + \text{Recall}}. \quad (5)$$

Detection rate was reported separately as the percentage of annotated crack instances successfully matched under the same rule. Pixel-level area was computed by summing predicted or annotated mask pixels and normalizing by the total image area across the evaluated set.

VI. RESULTS

Table III summarizes the reported performance values for the evaluated pavement-crack analysis models on the UWGB-StreetCrack dataset. The results are reported using precision, recall, F1 score, and detected crack-area percentage. The Mask R-CNN values come from the project-specific held-out test

protocol, while the YOLO and DeepSegmentor values are included as contextual references under non-identical evaluation setups.

Among the evaluated Mask R-CNN variants, the ResNet-101 FPN 3x backbone achieved the best overall detection performance. It obtained a precision of 84.23%, a recall of 90.04%, and an F1 score of 87.04%. In comparison, the ResNet-50 FPN 3x variant achieved 75.56% precision, 89.01% recall, and an F1 score of 81.73%. The deeper ResNet-101 backbone therefore improved precision by 8.67 percentage points and F1 score by 5.31 percentage points, while also providing a modest improvement in recall. This indicates that the higher-capacity ResNet-101 FPN backbone was more effective at suppressing false detections while maintaining strong crack-detection coverage.

Compared with the YOLO detector using the CSPDarknet53 backbone, the proposed Mask R-CNN ResNet-101 FPN 3x model showed substantially higher reported values across all three detection metrics. YOLO obtained 27.5% precision, 20.7% recall, and an F1 score of 23.62%, whereas the proposed Mask R-CNN ResNet-101 FPN 3x model achieved 84.23% precision, 90.04% recall, and 87.04% F1 score. This corresponds to differences of 56.73 percentage points in precision, 69.34 percentage points in recall, and 63.42 percentage points in F1 score. Because these values come from non-identical protocols, they should be interpreted as contextual performance evidence rather than a strict like-for-like benchmark.

The detected-area results further highlight the practical advantage of the proposed instance-segmentation framework for pavement-crack assessment. The ground-truth crack area accounted for 2.170% of the evaluated image area. The proposed Mask R-CNN ResNet-101 FPN 3x model estimated the crack area as 2.164%, producing an absolute difference of only 0.006 percentage points from the ground truth. In comparison, DeepSegmentor produced a detected-area value of 2.130%, corresponding to an absolute difference of 0.040 percentage points. Although this numerical comparison shows that both methods produced aggregate crack-area estimates close to the ground truth, an important practical distinction must be emphasized. DeepSegmentor was evaluated as a crop-level segmentation method and requires input images that are manually cropped around crack-containing regions. When applied directly to full roadway scenes, its performance is limited by real-world visual confounders such as shadows, pavement texture, stains, road markings, lane lines, and other non-crack objects. In contrast, the proposed Mask R-CNN-based framework operates on full roadway images: it first localizes candidate distress regions and then predicts pixel-level masks for the detected instances. Therefore, the proposed model not only produced a closer aggregate crack-area estimate than DeepSegmentor under the reported evaluation, but also provided a more deployable end-to-end solution for realistic pavement imagery.

Overall, the results show that the proposed Mask R-CNN ResNet-101 FPN 3x model provides the strongest performance

TABLE III
COMPREHENSIVE PERFORMANCE COMPARISON OF MODELS ON PAVEMENT CRACK DATASET.

Model	Precision (%)	Recall (%)	F1 (%)	Detected area (%)
Ground truth	–	–	–	2.170
Mask R-CNN ResNet-50 FPN 3x	75.56	89.01	81.73	–
Mask R-CNN ResNet-101 FPN 3x	84.23	90.04	87.04	2.164
YOLO (CSPDarknet53) [12]	27.5	20.7	23.62	0.264
DeepSegmentor [23]	–	–	–	2.130

among the compared methods. It achieves the highest precision, recall, and F1 score for crack detection and classification, while also producing a detected-area percentage that closely matches the ground-truth crack area. These findings support the effectiveness of instance segmentation as a practical framework for automated pavement-crack analysis.

A. Qualitative Error Analysis

Figures 3a, 3b, 3c, and 3d show representative failure cases. Red boxes denote model predictions and green boxes denote ground-truth annotations. Painted road markings and oil stains produced false positives because their elongated or high-contrast appearance resembled cracks. Manhole-cover scenes were especially ambiguous because faint linear structures adjacent to the cover could be interpreted as either pavement distress or non-distress artifacts. Alligator cracking introduced a different difficulty: the model sometimes predicted one connected distress region while the ground truth separated the same region into multiple instances. In such cases, the error reflects annotation granularity as much as model failure.




Fig. 3. Representative failure cases used for qualitative analysis. Red boxes denote model predictions and green boxes denote ground-truth annotations.

These examples highlight why a segmentation benchmark must pair model development with rigorous annotation policy. Without strict guidance, annotators may draw different masks for the same visual structure, especially when a crack network can be interpreted as either one alligator-crack instance or

multiple linear cracks. Such ambiguity affects both training targets and evaluation counts.

VII. CONCLUSION

This paper presented a Mask R-CNN instance-segmentation system for field pavement distress assessment on UWGB-STREETCRACK. The best archived Mask R-CNN result, ResNet-101 FPN, achieved 84.23% precision, 90.04% recall, and 87.04% F1 under the project-specific held-out test protocol, while producing a predicted crack-area fraction of 2.164% compared with a 2.170% ground-truth fraction. A retrained Mandal CSPDarknet53-based detector provided additional context, reaching 27.5% precision, 20.7% recall, and 23.62%. Overall, the findings indicate that instance segmentation is a promising foundation for full-scene pavement distress analysis and aggregate crack-area estimation.

ACKNOWLEDGMENT

The authors acknowledge the support of the University of Wisconsin–Green Bay and the student researchers who contributed to data collection and annotation for UWGB-STREETCRACK.

DATA GOVERNANCE NOTE

Road imagery was collected from public roadways for research on pavement condition assessment. Before any external dataset release, the imagery should be reviewed for privacy-sensitive content such as visible faces, license plates, and other personally identifying information.

REFERENCES

- [1] Kaiming He, Georgia Gkioxari, Piotr Dollár, and Ross Girshick. Mask r-cnn. In *2017 IEEE International Conference on Computer Vision (ICCV)*, pages 2980–2988, 2017.
- [2] Qin Zou, Yu Cao, Qingquan Li, Qingzhou Mao, and Song Wang. Cracktree: Automatic crack detection from pavement images. *Pattern Recognition Letters*, 33(3):227–238, 2012.
- [3] Yong Shi, Limeng Cui, Zhiqian Qi, Fan Meng, and Zhensong Chen. Automatic road crack detection using random structured forests. *IEEE Transactions on Intelligent Transportation Systems*, 17(12):3434–3445, 2016.
- [4] Lei Zhang, Fan Yang, Yimin Daniel Zhang, and Ying Julie Zhu. Road crack detection using deep convolutional neural network. In *2016 IEEE international conference on image processing (ICIP)*, pages 3708–3712. IEEE, 2016.
- [5] Zhun Fan, Yuming Wu, Jiewei Lu, and Wenji Li. Automatic pavement crack detection based on structured prediction with the convolutional neural network. *arXiv preprint arXiv:1802.02208*, 2018.

- [6] Olaf Ronneberger, Philipp Fischer, and Thomas Brox. U-net: Convolutional networks for biomedical image segmentation. In Nassir Navab, Joachim Hornegger, William M. Wells, and Alejandro F. Frangi, editors, *Medical Image Computing and Computer-Assisted Intervention – MICCAI 2015*, pages 234–241, Cham, 2015. Springer International Publishing.
- [7] Qin Zou, Zheng Zhang, Qingquan Li, Xianbiao Qi, Qian Wang, and Song Wang. Deepcrack: Learning hierarchical convolutional features for crack detection. *IEEE transactions on image processing*, 28(3):1498–1512, 2018.
- [8] Wenjun Liu, Yuchun Huang, Ying Li, and Qi Chen. Fpcnet: Fast pavement crack detection network based on encoder-decoder architecture. *arXiv preprint arXiv:1907.02248*, 2019.
- [9] Seongdeok Bang, Somin Park, Hongjo Kim, and Hyoungkwan Kim. Encoder–decoder network for pixel-level road crack detection in black-box images. *Computer-Aided Civil and Infrastructure Engineering*, 34(8):713–727, 2019.
- [10] Shaoqing Ren, Kaiming He, Ross Girshick, and Jian Sun. Faster r-cnn: Towards real-time object detection with region proposal networks. In C. Cortes, N. Lawrence, D. Lee, M. Sugiyama, and R. Garnett, editors, *Advances in Neural Information Processing Systems*, volume 28. Curran Associates, Inc., 2015.
- [11] M. G. Sarwar Murshed, Keivan Bahmani, Stephanie Schuckers, and Faraz Hussain. Deep age-invariant fingerprint segmentation system. *IEEE Transactions on Biometrics, Behavior, and Identity Science*, 7(3):313–330, 2025.
- [12] Vishal Mandal, Abdul Rashid Mussah, and Yaw Adu-Gyamfi. Deep learning frameworks for pavement distress classification: A comparative analysis. pages 5577–5583, 2020.
- [13] Guo X. Hu, Bao L. Hu, Zhong Yang, Li Huang, and Ping Li. Pavement crack detection method based on deep learning models. *Wireless Communications and Mobile Computing*, 2021(1):5573590, 2021.
- [14] Xin Liang and Maoting Gao. The road crack detection algorithm improved based on yolov7. In *Proceedings of the 2024 International Conference on Generative Artificial Intelligence and Information Security*, pages 335–339, 2024.
- [15] Yuhao Wang, Heran Zhu, Yirong Wang, Jianping Liu, Jun Xie, Bi Zhao, and Siyue Zhao. Gsbyolo: A lightweight multi-scale fusion network for road crack detection in complex environments. *Scientific Reports*, 15(1):26615, 2025.
- [16] Xiaoran Feng, Liyang Xiao, Wei Li, Lili Pei, Zhaoyun Sun, Zhidan Ma, Hao Shen, and Huyan Ju. Pavement crack detection and segmentation method based on improved deep learning fusion model. *Mathematical Problems in Engineering*, 2020(1):8515213, 2020.
- [17] Jingwei Liu, Xu Yang, Stephen Lau, Xin Wang, Sang Luo, Vincent Cheng-Siong Lee, and Ling Ding. Automated pavement crack detection and segmentation based on two-step convolutional neural network. *Computer-Aided Civil and Infrastructure Engineering*, 35(11):1291–1305, 2020.
- [18] Tsung-Yi Lin, Piotr Dollár, Ross Girshick, Kaiming He, Bharath Hariharan, and Serge Belongie. Feature pyramid networks for object detection. In *2017 IEEE Conference on Computer Vision and Pattern Recognition (CVPR)*, pages 936–944, 2017.
- [19] Guanting Ye, Sai Li, Manxu Zhou, Yifei Mao, Jinsheng Qu, Tiewu Shi, and Qiang Jin. Pavement crack instance segmentation using yolov7-wmf with connected feature fusion. *Automation in Construction*, 160:105331, 2024.
- [20] Shao-Jie Wang, Ji-Kai Zhang, and Xiao-Qi Lu. Research on real-time detection algorithm for pavement cracks based on sparseinst-cdsm. *Mathematics*, 11(15):3277, 2023.
- [21] John S Miller, William Y Bellinger, et al. Distress identification manual for the long-term pavement performance program. Technical report, United States. Federal Highway Administration. Office of Infrastructure . . . , 2003.
- [22] Yuxin Wu, Alexander Kirillov, Francisco Massa, Wan-Yen Lo, and Ross Girshick. Detectron2. <https://github.com/facebookresearch/detectron2>, 2019.
- [23] Zhun Fan, Yuming Wu, Jiwei Lu, and Wenji Li. Automatic pavement crack detection based on structured prediction with the convolutional neural network, 2018.