

"identification only"

Naples Campus

Facility Condition Assessment Report



CAMPUS SUMMARY

Year Built ¹	1996-2013
GSF ²	267,305
Date of Assessment	07-Jan-2020

¹ Indicates range of dates of construction present on campus

² Only permanent and semi-permanent facilities are included

SCHOOL SUMMARY

School	Assessed Condition		Annual Condition Report (June 2019)		2009 Congressional	Starting Grade	Ending Grade	Students
	Q-Rating	FCI	Q-Rating	FCI	Q-Rating			
Naples Elementary School	Q-2	88	Q-2	82	Q-2	Sure Start	Sixth	724
Naples Middle/High School	Q-2	87	Q-2	80	Q-2	Seventh	Twelfth	529

BUILDING SUMMARY

Building/School	Year Built	GSF	Naples ES (%Occupied)	Naples MS/HS (%Occupied)	Type
Naples ES Bldg 2057	1996-2013	135,268	100%	0%	PERM
Naples MS/HS Bldg 2058	1996	111,107	0%	100%	PERM
Naples MS/HS Bldg 2059	1996	20,930	50%	50%	PERM

I. INTRODUCTION

The Naples Campus is part of Support Site, Naval Support Activity Naples, Italy. This report provides a summary of findings for the physical condition assessment of buildings at this campus. The physical condition assessment includes a general description of typical building systems found and includes conditions present at the time of the site visit.

"identification only"

II. SCHOOL PHYSICAL DESCRIPTION

The summary below provides a physical description of the campus. When multiple systems or materials are present, the predominant system or material observed during the facility condition assessment is shown.

- a. **STRUCTURAL/EXTERIOR ENCLOSURE:** The building exterior is stucco. Roof coverings are modified bitumen. Exterior doors are pre-finished aluminum with glazing. Window systems are pre-finished aluminum with double-glazing.
- b. **INTERIORS:** Floor finishes used include ceramic tile and carpet. Walls are painted hard surfaces. Ceilings are acoustical lay-in tiles.
- c. **MECHANICAL:** Campus facilities have heating, which is provided by boilers and package units. Most campus facilities have air conditioning, which is provided by chilled water. The campus has two elevators.
- d. **ELECTRICAL:** Some electrical upgrades have been completed at Building 2057 to support the computer network, but most wiring appears to be original. There were no electrical upgrades completed at the remaining facilities. Lighting is typically lay-in fixtures with fluorescent lamps. Ground-fault circuit interrupter (GFCI) receptacles appear to be present in required locations. The campus has two intercom systems. There are security systems, and security cameras are present.
- e. **PLUMBING:** Plumbing fixtures have been partially upgraded, but piping appears to be original. Domestic hot water is provided by indirect water heaters and gas-fired storage water heaters.
- f. **SITE:** The campus has parking for approximately 166 privately owned vehicles. In addition, Naples Elementary School has four playgrounds.
- g. **LIFE SAFETY:** Fire safety inspection reports were not available for review.

"identification only"

III. OBSERVATIONS

The following observations were made: Exterior door security was not reported to be a problem. However, assessment findings noted most sample tested double-leaf door coordinators were nonfunctional, specifically the door coordinators do not close consecutively as intended if the inactive door is opened before the active door resulting in unsecured doors. This malfunction is possibly caused by misalignment of the field maintenance repairs to locksets, missing hardware components, and closers in need of manual set adjustment. Overall the exterior enclosures systems at the main Naples Campus are at the end of their expected service life but are of good quality with various levels of deterioration.

In Building 2057, Art Room and Information Center, there are some isolated areas of ceramic flooring that are in poor condition which are deficient because of major cracking and upheaving files. In both Buildings 2057 and 2058, acoustical ceiling tiles and the suspension system around the newly installed cabinetry have been damaged. In Building 2057 the cabinetry and countertops in the Kitchenette Room 111C, which is shared between Rooms 111 and 113, are in particularly poor condition. The staff reported the next phase of cabinetry replacement has been scheduled. In Building 2058 it was observed and reported in Room 109, the partition (plaster) has failed due to a domestic piping leak from the adjacent restroom. The wall covering is significantly deteriorated with both water surface damage and failed paint finish.

Overall the mechanical, electrical, and plumbing systems were observed in fair condition with some maintenance updates noted since the last facility condition assessment throughout the campus. It appears outside air is being introduced into the HVAC system at the main campus. At Building 2057, the rooftop air handling units are corroded, have major fin damage, and corrosion on the vents. The chillers are operational but have severe fin damage and corrosion to the units as well as the piping. In Building 2059, Room M102, the piping of the hot and chilled water distribution pumps had calcium build-up and were corroded. Several radiators throughout Building 2058 are broken and/or reported by staff to not generate enough heat for a comfortable work environment. Additionally, in Building 2058, the ductwork over the Gym has extensive damage with holes, missing screws, and a large piece of protruding metal. In Buildings 2058 and 2057, new toilets, urinals, and sinks in the common areas were observed and reported. The transformer in Building 2057, Room M104, has excess noise and signs of a previous failure were observed during the assessment.

The Facility Utilization Survey (FUS) drawings have been updated to reflect the assessment findings, including room-use and room number changes observed throughout the campus. No buildings were added or removed from the site since the time of the previous assessment. It was observed at Naples ES Building 2057, Room 3 (967 SF), is being used by the Naples Community Superintendent's Office. Naples MS/HS Bldg 2059 is shared equally between Naples Elementary School and Naples Middle School/High School. Finally, the assessment team observed some damage to the site work surrounding the campus; the new epoxy/gravel coating on sidewalks appears to be too thin and is failing prematurely.

Building 2057 remained a Q-2.

Building 2058 remained a Q-2.

Building 2059 remained a Q-2.

"identification only"

IV. QUALITY / CONDITION RATINGS

Table 1 shows building-specific information to include Real Property Unique Identifier (RPUID), type of construction, year built, gross area, Facility Condition Index (FCI), and Q-Rating. Table 2 shows buildings that are classified as temporary (TEMP) or relocatable (RELO) and therefore, by definition, are not included in Quality/Condition calculations.

TABLE 1: QUALITY / CONDITION RATINGS								
Photo	Building	RPUID	Type	Year Built	GSF	Assessed		Plant Replacement Value ³
						FCI	Q-Rating	
	2057	139073	PERM	1996	135,268	88	Q 2	██████████
	2058	10603	PERM	1996	111,107	87	Q 2	██████████
	2059	10605	PERM	1996	20,930	86	Q 2	██████████


³ The Plant Replacement Value is calculated according to the DoD Facility Pricing Guide


TABLE 2: TEMPORARY / RELOCATABLE BUILDINGS					
Photo	Building	Type	Year Built	GSF	Current Use
	X2057A	RELO	2000	74	Storage Shed
	X2059A	RELO	1985	158	Container
	X2059B	RELO	1985	158	Container
	X2059C	RELO	1991	316	Container

Appendix A

"identification only"

Site Plan





Appendix B

"identification only"

Overview of Sustainment Management System (SMS) and BUILDER™ Engineered Management System (EMS)

"identification only"

Overview of Sustainment Management System (SMS) and BUILDER™ Engineered Management System (EMS)

Sustainment Management System (SMS)

The Sustainment Management System (SMS) is a suite of web-based software applications developed by the United States Army Corps of Engineers - Engineer Research Development Center - Construction Engineering Research Laboratory (USACE-ERDC-CERL) to help facility engineers, technicians, and managers decide when, where, and how to best maintain the built environment. The SMS modules include BUILDER™ and ROOFER™ for assessing building conditions, PAVER™ for pavements, and RAILER™ for railroad infrastructure.

Because real property assets are so vast and diverse, a "knowledge-based" philosophy drives the SMS process. The process starts with the automated download of real property data, and then more detailed system inventory is modeled and/or collected which identifies components and their key life cycle attributes such as the age and material.

From this inventory, Condition Index (CI) measures for each component are predicted based on its expected stage in the life cycle. Objective and repeatable inspections can then be performed on various components to verify their condition with respect to the expected life cycle deterioration. The level of detail and frequency of these inspections are not fixed like other processes; they are dependent on knowledge of component criticality, the expected and measured condition and rate of deterioration, and remaining maintenance and service life. This "knowledge-based" inspection focuses attention to the most critical components at the time. In addition to these condition assessments, functionality assessments can be performed to evaluate user requirement changes, compliance and obsolescence issues. This provides a comprehensive picture of the overall performance of real property assets and their key components.

BUILDER Engineered Management System (EMS)

In September 2013, the Under Secretary of Defense, Frank Kendall, issued a memo indicating the Department of Defense requires a standardized process for facility condition assessments to ensure consistent and reliable data necessary for sound strategic investment decisions in managing the Department's built environment.

Establishing a DoD-wide facility condition assessment process will contribute to a more credible DoD asset management program and will support better buying power by allowing Department leadership to better target fiscal resources to those facilities most in need of investment. Further, adopting a standard process will help ensure that condition data will be audit-ready in accordance with the Under Secretary of Defense (Comptroller)'s "Financial Improvement and Readiness Guidance" issued in March 2013.

The facility condition assessment process used to generate this report is based on BUILDER Engineered Management System (EMS) Version 3. BUILDER EMS was developed by the Engineer Research and Development Center.

The facility condition assessment process addresses the requirements necessary for routine building facility management activities, including long range budgeting and sustainment/restoration/modernization (SRM) planning. This assessment approach provides an objective and generalized framework to help to identify problem areas that will require more investigation through detailed or specialized assessments. There may be times when detailed engineering assessments may be required to diagnose specific problems.

BUILDER is a software application for building asset life cycle management. The primary focus of BUILDER is work plan development. BUILDER stores real property building information and more detailed system inventory is modeled and/or collected which identifies building components and their key life cycle attributes such as the age, material and capacity. Inspections are then performed on the various components to

"identification only"

determine an objective and repeatable Condition Index (CI) measure, which relates the general physical health of the asset.

With information about condition and remaining service life, BUILDER guides the development of short- and long-range work plans based on sound investment strategies, prioritization criteria, and budget constraints. BUILDER consolidates a variety of building-related management issues into a single decision-support package.

The system gives functional managers and decision-makers instant access to building inventory, current building condition indices, and probabilities condition prediction models. It also employs a patented knowledge-based inspection scheduling process. BUILDER improves the allocation process and return of building life cycle investments by directing resources to the most condition critical components to avoid costly repair penalty costs, as well as, the most mission critical components to manage risks of failure.

BUILDER Facility Condition Assessment Process

Facility Condition Assessment (FCA) is one of the primary processes of a facility life cycle asset management program. The FCA process results in a better understanding of the physical condition and readiness of an organization's buildings along with the reliability of its systems and components. It also facilitates the identification of work candidates for facility SRM repair projects. It is a critical aspect of the shift towards a proactive versus reactive facility management strategy. Instead of keeping facilities operational by relying primarily on corrective repairs (after a system or component has failed due to significant loss of function), it focuses on condition-based repairs which can be planned prior to failure. A condition-based approach can result in higher performing facilities at lower life cycle costs.

Prior to an assessment, knowledge of the building systems and components present is necessary, since assessments are done against these components, not against the building as a whole. This information about the systems and components that make up a building is called the BUILDER Inventory. BUILDER has a vast library of predefined components which an assessor will select from, and the inventory collection process involves identifying the type, quantity, and year installed for all pertinent components. These components are also organized into systems and sub-systems according to the UNIFORMAT classification hierarchy. When a specific instance of a component is recorded, this is called a component-section in BUILDER, and represents a single component assembly or collection of like components to be managed as a single unit. The BUILDER facility condition assessment process directly supports the computation of a condition index for building component-sections, known as the Component-Section Condition Index (CSCI), which is the fundamental metric used in BUILDER. The CSCI is aggregated to compute a condition index metric at the system (SCI), building (BCI), and site/organizational levels.

A condition-based facility repair strategy requires condition information be collected at a component level, and that this condition information relate to loss of component function. Every component of a building has a primary function that it performs. This function is the reason that the component was constructed or installed in the building. It may also serve a number of secondary or tertiary functions. For example, for a door component, the primary function is to provide safe entry/egress of authorized movements while limiting unwanted movements of people (security), or other objects (water or moisture). The secondary functions would relate to aesthetics and thermal and air control, among others.

The condition assessment process in BUILDER uses the Direct Rating method.

1. The **Direct Rating** method uses a single qualitative rating for each component based on condition observations. This also results in a condition index metric, which relates to the level of deterioration and the loss of function. This abbreviated Direct Rating approach is often better suited to initial baseline assessments where the components are inventoried, and data is initially loaded into BUILDER.

"identification only"

The following figure illustrates the Direct Rating criteria used in this assessment.

RATING	SRM NEEDS	RATING DEFINITION
Green (+)	Sustainment consisting of possible preventive maintenance (where applicable)	Entire component-section or component-section sample is free of observable or known distress.
Green	Sustainment consisting of possible preventive maintenance (where applicable) and minor repairs (corrective maintenance) to possibly few or some subcomponents.	No component-section or sample serviceability* or reliability* reduction. Some, but not all minor (non-critical) subcomponents may suffer from slight degradation or few major (critical) subcomponents may suffer from slight degradation.
Green (-)		Slight or no serviceability or reliability or reliability reduction overall to the component-section or sample. Some, but not all minor (non-critical) subcomponents may suffer from slight degradation or more than one major (critical) subcomponents may suffer from slight degradation.
Amber (+)	Sustainment or restoration to any of the following: Minor repairs to several sub-components; or Significant repair, rehabilitation or replacement of one or more subcomponents, but not enough to encompass the component-section as a whole; or Combinations thereof.	Component-section or sample serviceability or reliability is degraded, but adequate. A very few major (critical) subcomponents may suffer from moderate deterioration with perhaps a few minor (non-critical) subcomponents suffering from severe deterioration.
Amber		Component-section or sample serviceability or reliability is definitely impaired. Some, but not a majority of major (critical) subcomponents may suffer from moderate deterioration with perhaps many minor (non-critical) subcomponents suffering from severe deterioration.
Amber (-)		Component-section or sample has significant serviceability or reliability loss. Most subcomponents may suffer from moderate degradation or a few major (critical) subcomponents may suffer from severe degradation.
Red (+)	Sustainment or restoration required consisting of major repair, rehabilitation or replacement to the component-section as a whole.	Significant serviceability or reliability reduction in component-section or sample. A majority of subcomponents are severely degraded, and others may have varying degrees of degradation.
Red		Severe serviceability or reliability reduction to the component-section or sample such that it is barely able to perform. Most subcomponents are severely degraded.
Red (-)		Overall component-section degradation is total. Few, if any subcomponents are salvageable. Complete loss of component-section or sample serviceability.

"identification only"

Once the component-sections have been rated with a Direct Rating, BUILDER calculates the Component-Section Condition Index (CSCI) of the component-section. The next step in the process is to create a work plan, which will list the component-sections that need repair or replacement and the estimated cost of the repair or replacement.

To create a work plan, condition standards, policies and a policy sequence are created. The standards serve as thresholds for CSCI and remaining service life. Policies link standards to component-sections and policy sequences link standards and policies together.

The table below summarizes the DoDEA standards and how they are applied to the component-sections for this assessment.

Standard and Component-section Cross-Reference		
Standard	CI Threshold	Component-section
Amber +	80	D4010 FIRE ALARM AND DETECTION SYSTEMS
Amber	71	B3010 ROOF COVERINGS D1010 ELEVATORS AND LIFTS D2010 PLUMBING FIXTURES D3020 HEAT GENERATING SYSTEMS D3030 COOLING GENERATING SYSTEMS D3040 DISTRIBUTION SYSTEMS (A) D3050 TERMINAL & PACKAGE UNITS D3060 CONTROLS & INSTRUMENTATION D3090 OTHER HVAC SYSTEMS AND EQUIPMENT D4020 FIRE SUPP WATER SUPPLY / EQUIP D4030 STANDPIPE SYSTEMS D4040 SPRINKLERS D4050 FIRE PROTECTION SPECIALTIES D4090 OTHER FIRE PROTECTION SYSTEMS D5010 ELECTRICAL SERVICE & DISTRIBUTION D5020 LIGHTING & BRANCH WIRING D5030 COMMUNICATIONS & SECURITY D5090 OTHER ELECTRICAL SERVICES
Amber -	61	B2030 EXTERIOR DOORS C1020 INTERIOR DOORS C3010 WALL FINISHES C3020 FLOOR FINISHES C3030 CEILING FINISHES C3040 INT COATINGS / SPECIAL FINISHES D3010 ENERGY SUPPLY
Red +	50	B2010 EXTERIOR WALLS B2020 EXTERIOR WINDOWS C1030 SPECIALTIES D1020 WEIGHT HANDLING EQUIPMENT D1030 ESCALATORS AND MOVING WALKS D1090 OTHER CONVEYING SYSTEMS D2020 DOMESTIC WATER DISTRIBUTION D2030 SANITARY WASTE D2040 RAIN WATER DRAINAGE D2090 OTHER PLUMBING SYSTEMS D3070 SYSTEMS TESTING & BALANCING
Service Life	40	Paint

"identification only"

For this project, the following building components are not included in the BUILDER Inventory and are not evaluated during the assessment unless significant damage or deterioration was observed or reported.

- A1010 STANDARD FOUNDATIONS
- A1020 SPECIAL FOUNDATIONS
- A1030 SLAB ON GRADE
- A2010 BASEMENT EXCAVATION
- A2020 BASEMENT WALLS
- B1010 FLOOR CONSTRUCTION
- B1020 ROOF CONSTRUCTION
- B2010 EXTERIOR WALLS
- C1010 PARTITIONS
- C2010 STAIR CONSTRUCTION

Damage that is not visible or that is unknown will not be reflected in facility condition index calculations. It is anticipated that unknown damage or deterioration is more likely to be present in older facilities than more modern facilities.

In addition, some building components are concealed or inaccessible. In accordance with BUILDER guidelines, quantities for concealed and inaccessible components have been estimated and recorded in the BUILDER Inventory but have not been rated. When concealed or inaccessible components are encountered, life cycle data contained within BUILDER is used to predict renewal requirements, which are included in facility condition index calculations. Components that are often concealed or inaccessible include:

- D2020 DOMESTIC WATER PIPING
- D2030 SANITARY WASTE PIPING
- D3040 HVAC DISTRIBUTION
- D4010 FIRE ALARM DISTRIBUTION
- D5020 ELECTRICAL BRANCH WIRING

In addition to the building components noted above, if a building component is concealed or inaccessible, life cycle data contained within BUILDER is used to predict renewal requirements.

When a work plan is created, the CSCI of a component-section is compared to its associated standard. If the CSCI is less than or equal to the threshold in the standard, the remaining service life is evaluated. If the service life is less than the standard's remaining service life, BUILDER will add this section to the work plan and generate dollars to estimate a cost for the replacement.

If the CSCI is less than or equal to the threshold in the standard and the service life is greater than the standard's remaining service life, BUILDER will conduct a cost benefit analysis. The cost benefit analysis will determine whether the component-section should be repaired or left to expire at the end of its service life. When BUILDER determines a repair is the correct action, BUILDER will add this section to the work plan and generate dollars to estimate a cost for the repair.

When BUILDER determines taking no action is more cost effective, BUILDER will not add the component-section to the work plan. For example, if the CSCI for an external door component-section is 50 with a remaining service life of five years, BUILDER will compare the CSCI of 50 to the CI Threshold set by DoDEA and determine that 50 is less than the threshold of 61. BUILDER will compare the five years of remaining services life against the zero years of the threshold and determine a cost benefit analysis is required. The results of the cost benefit analysis will typically suggest to take no action and let the component-section run until the end of its service life before generating an item in the work plan.

A typical life cycle of a component-section is explained below.

Condition	Work Plan
CSCI > threshold	Work plan does not generate an item for the component-section
CSCI = threshold or just below it	Work plan will generate a repair item for the component-section
CSCI < threshold and the remaining service life > service life threshold	Work plan will remove the repair item for the component-section. It is too costly to repair so it is better to wait to replace it.
Remaining service life < service life threshold	Work plan will generate a replace item for the component-section

"identification only"

Facility Condition Assessment Data Analysis

In multiple building portfolios and especially with widespread geographic portfolios, it is important to know how building conditions compare. The Condition Index (CI) and Quality Ratings (Q-Ratings) are determined for each building assessed using guidelines shown below.

Condition Index (CI) – A measure of the constructed asset's condition at a specific point in time with respect to physical condition and ability to support the current occupant or mission. CI is calculated as the ratio of estimated cost of maintenance and repair requirements to Plant Replacement Value (PRV). Maintenance and repair requirements consist of that work necessary to ensure that a constructed asset is restored to a condition substantially equivalent to the originally intended and designed capacity, efficiency or capability. The formula for Condition Index is:

$$CI = 1 - \left(\frac{\text{Requirements}}{\text{PRV}} \right) \times 100$$

Q-Rating Bands – Bands allow OSD, Military Services, and Defense Agencies/Activities to group facilities by condition for the purposes of developing investment strategies.

TABLE 1: Q-RATING DESCRIPTIONS		
Rating Band	Calculated Rating (Condition Index)	General Description
Q-1	100 to 90	Facility new or well-maintained (Good Condition)
Q-2	89 to 80	Facility is satisfactorily maintained (Fair Condition)
Q-3	79 to 60	Facility is under maintained (Poor Condition)
Q-4	59 to 0	Facility should be considered for replacement (Failing Condition)

Requirements – Sum of the work items from BUILDER.

Plant Replacement Value – Cost to design and construct a notional facility to current standards to replace an existing facility on the same site, (reference United Facilities Criteria UFC 3-701-01 23 May 2018, Change 3, 29 July 2019).

"identification only"

BUILDER Report Overview

Outlined below is a summary and description of the reports that are included.

Appendix C - Facility Summary Report – Provides a summation of FCA results. A Building Summary Report is included for each building that is considered permanent or semi-permanent construction and receives a Q-Rating. The purpose of this report is to provide a general overview of the building including key performance indicators. This report was generated using DoDEA's calculated Replacement Cost overwriting the data populated from real property records. This provides a more accurate Replacement Cost due to the inconsistencies with real property reconciliation between DoDEA and the Services. The DoD Facility Pricing Guide and DoDEA measurements for building square footage were used to calculate the Replacement Cost.

Appendix D - System Summary Report – Provides an overview of inspected systems and their condition index rating. A Building System Condition Index (SCI) By System Report is included for each building that is considered permanent or semi-permanent construction and receives a Q-Rating.

Appendix E - Work Items By Building – Provides a list of work items requiring repair or replacement of system/components, including budgets, for project planning purposes. A Work Plan Detail by Year Report is included for each building that is considered permanent or semi-permanent construction and receives a Q-Rating.

Appendix F - Remaining Service Life (RSL) Detail Report – Provides a detailed overview of systems/components, including descriptions, and their respective age, remaining service life and remaining paint life.

Appendix G - Direct Condition Rating Inspection By Section Report – Provides a summary of direct condition ratings for each component-section collected within each facility.

Appendix H - System Inventory Report – Provides a list of details for each component-section collected within each facility.

Appendix I - Fire Inspection Safety Report – This appendix is only applicable when a Fire Inspection Safety Report is provided at the time of the assessment for inclusion in the Facility Condition Assessment Report. The report provides a summary of the recent Fire Inspection to include any deficiencies.

Note: All reports are generated from the DoDEA BUILDER database. In the event line items within a report are compressed and difficult to read, this is a result of how BUILDER generates the report. It is our understanding that CERL is working to update the report format.

Summary of Terms

Acronyms	Description
BCI	Building Condition Index - Measures the condition of the building as a whole. The higher the BCI, the better.
BFI	Building Functionality Index - Measures the functionality of a building as a whole. The higher the BFI, the better.
BPI	Building Performance Index - Measures the overall performance of a building. The higher the BPI, the better.
EA	Each
ESC	Emergency Service Call
FCI	Facility Condition Index - The current maintenance, repair, and replacement deficiencies of the facility divided by the current replacement value of the facility, derives the FCI of a facility. The higher the FCI, the better.
GSF	Gross Square Foot
ISR	Installation Status Report - Measures installation condition against Army-wide standards.
LF	Linear Feet
MBH	Thousands of BTU per hour.
MDI	Mission Dependency Index - Measures how critical a facility is to the overall mission of its owner. The higher the MDI, the more critical.
PERM	Permanent
RELO	Relocatable
RPL	Remaining Paint Life - Displays the remaining paint life, in years, of a section.
RPUID	Real Property Unique Identifier - The unique identification number assigned to each asset.
RSL	Remaining Service Life - Displays the remaining service life, in years, of a section.
SCI	System Condition Index - Measures the condition of a system as a whole. The higher the SCI, the better.
SF	Square Foot
TEMP	Temporary
UM	Unit of Measure

Appendix C

"identification only"

Facility Summary Report

2057 - Naples ES Bldg 2057

Support Site - Naples ES



YEAR BUILT: 1996

AREA (SF): 135,268

PLANT REPLACEMENT COST:

SURVEY DATE: January 2020

TOTAL DEFICIENCIES:

BUILDER(TM) METRIC		SCORE
Facility Condition Index	FCI:	88

"identification only"

VS20160115 - Cplx

2058 - Naples MS/HS Bldg 2058

Support Site - Naples MS/HS



YEAR BUILT: 1996

AREA (SF): 111,107

PLANT REPLACEMENT COST: [REDACTED]

SURVEY DATE: January 2020

TOTAL DEFICIENCIES: [REDACTED]

BUILDER(TM) METRIC		SCORE
Facility Condition Index	FCI:	87

2059 - Naples MS/HS Bldg 2059

Support Site - Unassigned



YEAR BUILT: 1996

AREA (SF): 20,930

PLANT REPLACEMENT COST: [REDACTED]

SURVEY DATE: January 2020

TOTAL DEFICIENCIES: [REDACTED]

BUILDER(TM) METRIC		SCORE
Facility Condition Index	FCI:	86

Appendix D

"identification only"

System Summary Report

DoDEA SYSTEM SUMMARY

Support Site

Complex	Building #	Building Name	A10	A20	B10	B20	B30	C10	C20	C30	D10	D20	D30	D40	D50	E10	E20	F10	F20	G10	G20	G30	G40	G90
Naples ES	2057	Naples ES Bldg 2057				72	74	85	81	74	80	85	40	71	68									

A10 - Foundations

A20 -Basement Construction

B10 - Superstructure

B20 - Exterior Enclosure

B30 - Roofing

C10 - Interior Construction

C20 - Stairs

C30 - Interior Finishes

D10 - Conveying

D20 - Plumbing

D30 - HVAC

D40 - Fire Protection

D50 - Electrical

E10 - Equipment

E20 - Furnishings

F10 - Special Construction

F20 - Selective Building Demo

G10 - Site Preparations

G20 - Site Improvements

G30 - Site Civil / Mech Utilities

G40 - Site Electrical Utilities

G50 - Other Site Construction

DoDEA SYSTEM SUMMARY

Support Site

Complex	Building #	Building Name	A10	A20	B10	B20	B30	C10	C20	C30	D10	D20	D30	D40	D50	E10	E20	F10	F20	G10	G20	G30	G40	G90
Naples MS/HS	2058	Naples MS/HS Bldg 2058				70	68	80	79	70	79	82	41	68	68									

A10 - Foundations

A20 -Basement Construction

B10 - Superstructure

B20 - Exterior Enclosure

B30 - Roofing

C10 - Interior Construction

C20 - Stairs

C30 - Interior Finishes

D10 - Conveying

D20 - Plumbing

D30 - HVAC

D40 - Fire Protection

D50 - Electrical

E10 - Equipment

E20 - Furnishings

F10 - Special Construction

F20 - Selective Building Demo

G10 - Site Preparations

G20 - Site Improvements

G30 - Site Civil / Mech Utilities

G40 - Site Electrical Utilities

G50 - Other Site Construction

DoDEA SYSTEM SUMMARY

Support Site

Complex	Building #	Building Name	A10	A20	B10	B20	B30	C10	C20	C30	D10	D20	D30	D40	D50	E10	E20	F10	F20	G10	G20	G30	G40	G90
Unassigned	2059	Naples MS/HS Bldg 2059				64	73	80	79	79		78	55	68	68	95								

A10 - Foundations

A20 -Basement Construction

B10 - Superstructure

B20 - Exterior Enclosure

B30 - Roofing

C10 - Interior Construction

C20 - Stairs

C30 - Interior Finishes

D10 - Conveying

D20 - Plumbing

D30 - HVAC

D40 - Fire Protection

D50 - Electrical

E10 - Equipment

E20 - Furnishings

F10 - Special Construction

F20 - Selective Building Demo

G10 - Site Preparations

G20 - Site Improvements

G30 - Site Civil / Mech Utilities

G40 - Site Electrical Utilities

G50 - Other Site Construction

Appendix E

"identification only"

Work Items By Building



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
2015	B20 EXTERIOR ENCLOSURE						
	B2010 EXTERIOR WALLS	1,738 (LF)	Replace				0.00
	1996 B201004 PARAPETS General						
	-- Replace B2010 EXTERIOR WALLS 1996 B201004 PARAPETS General						
	B2010 EXTERIOR WALLS	325 (LF)	Replace				0.00
	2004 B B201004 PARAPETS General						
	-- Replace B2010 EXTERIOR WALLS 2004b B201004 PARAPETS General						
2015	B30 ROOFING						
	B3010 ROOF COVERINGS	60,131 (SF)	Replace				0.00
	1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen						
	-- Replace B3010 ROOF COVERINGS 1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen						
	B3010 ROOF COVERINGS	60,131 (SF)	Replace				0.00
	1996 B301003 ROOF INSULATION & FILL General						
	-- Replace B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL Unknown						
	B3010 ROOF COVERINGS	3,655 (LF)	Replace				0.00
	1996 B301004 FLASHINGS & TRIM Flashings - Base						
	-- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Base						
	B3010 ROOF COVERINGS	3,371 (LF)	Replace				0.00
	1996 B301004 FLASHINGS & TRIM Flashings - Cap						
	-- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Cap						
	B3010 ROOF COVERINGS	76 (EA)	Replace				0.00
	1996 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations						
	-- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations						
	B3010 ROOF COVERINGS	248 (LF)	Replace				0.00
	1996 A B301004 FLASHINGS & TRIM Flashings - Apron						
	-- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Apron						



Work Items by Building Report



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	B3010 ROOF COVERINGS 1996 A B301004 FLASHINGS & TRIM General -- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM General	749 (LF)	Replace				0.00
	B3010 ROOF COVERINGS 2004 B301004 FLASHINGS & TRIM Flashings - Cap -- Replace B3010 ROOF COVERINGS 2004 B301004 FLASHINGS & TRIM Flashings - Cap	506 (LF)	Replace				0.00
	B3010 ROOF COVERINGS 2004 B301090 OTHER ROOFING Walkway Protection -- Repair B3010 ROOF COVERINGS 2004 B301090 OTHER ROOFING Walkway Protection	222 (SF)	Repair				0.00
	B3010 ROOF COVERINGS 2004 A B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations -- Replace B3010 ROOF COVERINGS 2004a B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	19 (EA)	Replace				0.00
	B3010 ROOF COVERINGS 2004 B B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen -- Replace B3010 ROOF COVERINGS 2004b B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	6,640 (SF)	Replace				0.00
	B3010 ROOF COVERINGS 2004 B B301004 FLASHINGS & TRIM Flashings - Base -- Replace B3010 ROOF COVERINGS 2004b B301004 FLASHINGS & TRIM Flashings - Base	326 (LF)	Replace				0.00
2015	C10 INTERIOR CONSTRUCTION						
	C1010 PARTITIONS 2004 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing -- Paint C1010 PARTITIONS 2004 C101001 FIXED PARTITIONS General	15,474 (SF)	Paint				0.00
2015	C30 INTERIOR FINISHES						
	C3020 FLOOR FINISHES 1996 C302005 CARPETING General -- Replace C3020 FLOOR FINISHES 1996 C302005 CARPETING General	17,701 (SF)	Replace				0.00



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	C3030 CEILING FINISHES 1996 C303001 ACOUSTICAL CEILING TILES & PANELS General -- Replace C3030 CEILING FINISHES 1996 C303001 ACOUSTICAL CEILING TILES & PANELS General	88,900 (SF)	Replace				0.00
	C3030 CEILING FINISHES 1996 C303005 SUSPENSION SYSTEMS General -- Replace C3030 CEILING FINISHES 1996 C303005 SUSPENSION SYSTEMS General	90,176 (SF)	Replace				0.00
2015	D20 PLUMBING						
	D2010 PLUMBING FIXTURES 1996 D201006 DRINKING FOUNTAINS AND COOLERS Drinking Fountain -- Repair D2010 PLUMBING FIXTURES D201006 DRINKING FOUNTAINS AND COOLERS General	8 (EA)	Repair				0.00
	D2030 SANITARY WASTE 1996 D203002 VENT PIPE & FITTINGS General -- Replace D2030 SANITARY WASTE D203002 VENT PIPE & FITTINGS General	1,340 (EA)	Replace				0.00
	D2040 RAIN WATER DRAINAGE 1996 D204002 ROOF DRAINS Other -- Replace D2040 RAIN WATER DRAINAGE 1996 3 inch D204002 ROOF DRAINS Other	67 (EA)	Replace				0.00
2015	D30 HVAC						
	D3040 DISTRIBUTION SYSTEMS 1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS D304003 HOT WATER DISTRIBUTION SYSTEMS General	1,000 (MBH)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	200 (TON)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-055 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS AHU-055 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	Section Description						
	-- Description						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 AHU-061 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS AHU-061 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 AHU-1 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS AHU-1 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 AHU-2 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS AHU-2 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 AHU-3 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS AHU-3 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 AHU-4 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS AHU-4 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3060 CONTROLS & INSTRUMENTATION	128 (EA)	Replace				0.00
	1996 D306002 ELECTRONIC CONTROLS General						
	-- Replace D3060 CONTROLS & INSTRUMENTATION D306001 HVAC CONTROLS General						
2015	D40 FIRE PROTECTION						
	D4010 FIRE ALARM AND DETECTION SYSTEMS	108,693 (SF)	Replace				0.00
	1996 D401001 FIRE ALARM DISTRIBUTION Other						
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS D401001 FIRE ALARM DISTRIBUTION General						
2016	B20 EXTERIOR ENCLOSURE						
	B2010 EXTERIOR WALLS	1,738 (LF)	Replace				0.00
	1996 B201004 PARAPETS General						
	-- Replace B2010 EXTERIOR WALLS 1996 B201004 PARAPETS General						



Work Items by Building Report



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	B2010 EXTERIOR WALLS 2004 B B201004 PARAPETS General -- Replace B2010 EXTERIOR WALLS 2004b B201004 PARAPETS General	325 (LF)	Replace				0.00
2016	B30 ROOFING						
	B3010 ROOF COVERINGS 1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen -- Replace B3010 ROOF COVERINGS 1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	60,131 (SF)	Replace				0.00
	B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL General -- Replace B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL Unknown	60,131 (SF)	Replace				0.00
	B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Base -- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Base	3,655 (LF)	Replace				0.00
	B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Cap -- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Cap	3,371 (LF)	Replace				0.00
	B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations -- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	76 (EA)	Replace				0.00
	B3010 ROOF COVERINGS 1996 A B301004 FLASHINGS & TRIM Flashings - Apron -- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Apron	248 (LF)	Replace				0.00
	B3010 ROOF COVERINGS 1996 A B301004 FLASHINGS & TRIM General -- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM General	749 (LF)	Replace				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	B3010 ROOF COVERINGS	506 (LF)	Replace				0.00
	2004 B301004 FLASHINGS & TRIM Flashings - Cap						
	-- Replace B3010 ROOF COVERINGS 2004 B301004 FLASHINGS & TRIM Flashings - Cap						
	B3010 ROOF COVERINGS	19 (EA)	Replace				0.00
	2004 A B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations						
	-- Replace B3010 ROOF COVERINGS 2004a B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations						
	B3010 ROOF COVERINGS	6,640 (SF)	Replace				0.00
	2004 B B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen						
	-- Replace B3010 ROOF COVERINGS 2004b B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen						
	B3010 ROOF COVERINGS	326 (LF)	Replace				0.00
	2004 B B301004 FLASHINGS & TRIM Flashings - Base						
	-- Replace B3010 ROOF COVERINGS 2004b B301004 FLASHINGS & TRIM Flashings - Base						
2016	C10 INTERIOR CONSTRUCTION						
	C1010 PARTITIONS	15,474 (SF)	Paint				0.00
	2004 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing						
	-- Paint C1010 PARTITIONS 2004 C101001 FIXED PARTITIONS General						
2016	C30 INTERIOR FINISHES						
	C3020 FLOOR FINISHES	17,701 (SF)	Replace				0.00
	1996 C302005 CARPETING General						
	-- Replace C3020 FLOOR FINISHES 1996 C302005 CARPETING General						
	C3030 CEILING FINISHES	88,900 (SF)	Replace				0.00
	1996 C303001 ACOUSTICAL CEILING TILES & PANELS General						
	-- Replace C3030 CEILING FINISHES 1996 C303001 ACOUSTICAL CEILING TILES & PANELS General						
	C3030 CEILING FINISHES	90,176 (SF)	Replace				0.00
	1996 C303005 SUSPENSION SYSTEMS General						
	-- Replace C3030 CEILING FINISHES 1996 C303005 SUSPENSION SYSTEMS General						



Work Items by Building Report



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
2016	D20 PLUMBING						
	D2030 SANITARY WASTE	1,340 (EA)	Replace				0.00
	1996 D203002 VENT PIPE & FITTINGS General						
	-- Replace D2030 SANITARY WASTE D203002 VENT PIPE & FITTINGS General						
	D2040 RAIN WATER DRAINAGE	67 (EA)	Replace				0.00
	1996 D204002 ROOF DRAINS Other						
	-- Replace D2040 RAIN WATER DRAINAGE 1996 3 inch D204002 ROOF DRAINS Other						
2016	D30 HVAC						
	D3040 DISTRIBUTION SYSTEMS	1,000 (MBH)	Replace				0.00
	1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	D3040 DISTRIBUTION SYSTEMS	200 (TON)	Replace				0.00
	1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS D304006 CHILLED WATER DISTRIBUTION SYSTEMS General						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 AHU-055 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS AHU-055 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 AHU-061 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS AHU-061 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 AHU-1 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS AHU-1 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 AHU-2 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS AHU-2 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						



Work Items by Building Report



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 AHU-3 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS AHU-3 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 AHU-4 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS AHU-4 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3050 TERMINAL & PACKAGE UNITS	57 (EA)	Repair				0.00
	1996 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 2 ton						
	-- Repair D3050 TERMINAL & PACKAGE UNITS Duct mount units D305003 FAN COIL UNITS Cab Mount, Two Pipe - 2 ton						
	D3060 CONTROLS & INSTRUMENTATION	128 (EA)	Replace				0.00
	1996 D306002 ELECTRONIC CONTROLS General						
	-- Replace D3060 CONTROLS & INSTRUMENTATION D306001 HVAC CONTROLS General						
2016	D40 FIRE PROTECTION						
	D4010 FIRE ALARM AND DETECTION SYSTEMS	108,693 (SF)	Replace				0.00
	1996 D401001 FIRE ALARM DISTRIBUTION Other						
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS D401001 FIRE ALARM DISTRIBUTION General						
	D4010 FIRE ALARM AND DETECTION SYSTEMS	11,612 (SF)	Repair				0.00
	2004 D401001 FIRE ALARM DISTRIBUTION Other						
	-- Repair D4010 FIRE ALARM AND DETECTION SYSTEMS 2004 D401001 FIRE ALARM DISTRIBUTION General						
2017	B20 EXTERIOR ENCLOSURE						
	B2010 EXTERIOR WALLS	21,900 (SF)	Paint				0.00
	1996 B201001 EXTERIOR CLOSURE Stucco						
	-- Paint B2010 EXTERIOR WALLS 1996 B201001 EXTERIOR CLOSURE Stucco						
	B2010 EXTERIOR WALLS	1,738 (LF)	Replace				0.00
	1996 B201004 PARAPETS General						
	-- Replace B2010 EXTERIOR WALLS 1996 B201004 PARAPETS General						



Work Items by Building Report



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	B2010 EXTERIOR WALLS	174 (LF)	Paint				0.00
	1996 B201006 BALCONY WALLS & HANDRAILS Handrailing						
	-- Paint B2010 EXTERIOR WALLS 1996 B201006 BALCONY WALLS & HANDRAILS Handrailing						
	B2010 EXTERIOR WALLS	6,136 (SF)	Paint				0.00
	2004 B201001 EXTERIOR CLOSURE Stucco						
	-- Paint B2010 EXTERIOR WALLS 2004 B201001 EXTERIOR CLOSURE Stucco						
	B2010 EXTERIOR WALLS	75 (LF)	Paint				0.00
	2004 B201006 BALCONY WALLS & HANDRAILS Handrailing						
	-- Paint B2010 EXTERIOR WALLS 2004 B201006 BALCONY WALLS & HANDRAILS Handrailing						
	B2010 EXTERIOR WALLS	774 (SF)	Paint				0.00
	2004 B201007 EXTERIOR SOFFITS General						
	-- Paint B2010 EXTERIOR WALLS 2004 B201007 EXTERIOR SOFFITS General						
	B2010 EXTERIOR WALLS	325 (LF)	Replace				0.00
	2004 B B201004 PARAPETS General						
	-- Replace B2010 EXTERIOR WALLS 2004b B201004 PARAPETS General						
	B2010 EXTERIOR WALLS	6,765 (SF)	Paint				0.00
	2013 B201001 EXTERIOR CLOSURE Stucco						
	-- Paint B2010 EXTERIOR WALLS 2013 B201001 EXTERIOR CLOSURE Stucco						
	B2010 EXTERIOR WALLS	1 (SF)	Paint				0.00
	2013 B201005 EXTERIOR LOUVERS & SCREENS General						
	-- Paint B2010 EXTERIOR WALLS 2013 B201005 EXTERIOR LOUVERS & SCREENS General						
	B2010 EXTERIOR WALLS	51 (LF)	Paint				0.00
	2013 B201006 BALCONY WALLS & HANDRAILS Handrailing						
	-- Paint B2010 EXTERIOR WALLS 2013 B201006 BALCONY WALLS & HANDRAILS Handrailing						
	B2010 EXTERIOR WALLS	607 (SF)	Paint				0.00
	2013 B201007 EXTERIOR SOFFITS General						
	-- Paint B2010 EXTERIOR WALLS 2013 B201007 EXTERIOR SOFFITS General						



Work Items by Building Report



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	B2030 EXTERIOR DOORS	35 (EA)	Replace				0.00
	1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door						
	-- Replace B2030 EXTERIOR DOORS 1996 B203002 GLAZED DOORS General						
2017	B30 ROOFING						
	B3010 ROOF COVERINGS	60,131 (SF)	Replace				0.00
	1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen						
	-- Replace B3010 ROOF COVERINGS 1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen						
	B3010 ROOF COVERINGS	60,131 (SF)	Replace				0.00
	1996 B301003 ROOF INSULATION & FILL General						
	-- Replace B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL Unknown						
	B3010 ROOF COVERINGS	3,655 (LF)	Replace				0.00
	1996 B301004 FLASHINGS & TRIM Flashings - Base						
	-- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Base						
	B3010 ROOF COVERINGS	3,371 (LF)	Replace				0.00
	1996 B301004 FLASHINGS & TRIM Flashings - Cap						
	-- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Cap						
	B3010 ROOF COVERINGS	76 (EA)	Replace				0.00
	1996 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations						
	-- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations						
	B3010 ROOF COVERINGS	552 (SF)	Replace				0.00
	1996 B301090 OTHER ROOFING Walkway Protection						
	-- Replace B3010 ROOF COVERINGS 1996 B301090 OTHER ROOFING Walkway Protection						
	B3010 ROOF COVERINGS	248 (LF)	Replace				0.00
	1996 A B301004 FLASHINGS & TRIM Flashings - Apron						
	-- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Apron						



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	B3010 ROOF COVERINGS 1996 A B301004 FLASHINGS & TRIM General -- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM General	749 (LF)	Replace				0.00
	B3010 ROOF COVERINGS 1996 B B301004 FLASHINGS & TRIM General -- Paint B3010 ROOF COVERINGS 1996 Stucco Fascia B301004 FLASHINGS & TRIM Other	746 (LF)	Paint				0.00
	B3010 ROOF COVERINGS 2004 B301004 FLASHINGS & TRIM Flashings - Cap -- Replace B3010 ROOF COVERINGS 2004 B301004 FLASHINGS & TRIM Flashings - Cap	506 (LF)	Replace				0.00
	B3010 ROOF COVERINGS 2004 B301004 FLASHINGS & TRIM General -- Paint B3010 ROOF COVERINGS 2004 Stucco Fascia B301004 FLASHINGS & TRIM Other	170 (LF)	Paint				0.00
	B3010 ROOF COVERINGS 2004 B301005 GUTTERS & DOWNSPOUTS Downspouts -- Paint B3010 ROOF COVERINGS 2004 B301005 GUTTERS & DOWNSPOUTS Downspouts	159 (LF)	Paint				0.00
	B3010 ROOF COVERINGS 2004 B301090 OTHER ROOFING Walkway Protection -- Replace B3010 ROOF COVERINGS 2004 B301090 OTHER ROOFING Walkway Protection	222 (SF)	Replace				0.00
	B3010 ROOF COVERINGS 2004 A B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations -- Replace B3010 ROOF COVERINGS 2004a B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	19 (EA)	Replace				0.00
	B3010 ROOF COVERINGS 2004 B B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen -- Replace B3010 ROOF COVERINGS 2004b B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	6,640 (SF)	Replace				0.00
	B3010 ROOF COVERINGS 2004 B B301004 FLASHINGS & TRIM Flashings - Base -- Replace B3010 ROOF COVERINGS 2004b B301004 FLASHINGS & TRIM Flashings - Base	326 (LF)	Replace				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	B3010 ROOF COVERINGS	121 (LF)	Paint				0.00
	2013 B B301004 FLASHINGS & TRIM General						
	-- Paint B3010 ROOF COVERINGS 2013 Stucco Fascia B301004 FLASHINGS & TRIM Other						
2017	C10 INTERIOR CONSTRUCTION						
	C1010 PARTITIONS	109,077 (SF)	Paint				0.00
	1996 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing						
	-- Paint C1010 PARTITIONS 1996 C101001 FIXED PARTITIONS General						
	C1010 PARTITIONS	15,474 (SF)	Paint				0.00
	2004 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing						
	-- Paint C1010 PARTITIONS 2004 C101001 FIXED PARTITIONS General						
	C1030 SPECIALTIES	52 (EA)	Replace				0.00
	1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions						
	-- Replace C1030 SPECIALTIES 1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions						
	C1030 SPECIALTIES	882 (EA)	Replace				0.00
	1996 C103005 LOCKERS General						
	-- Replace C1030 SPECIALTIES 1996 C103005 LOCKERS General						
	C1030 SPECIALTIES	327 (LF)	Replace				0.00
	1996 C103008 COUNTERS Laminated Plastic						
	-- Replace C1030 SPECIALTIES 1996 C103008 COUNTERS General						
2017	C20 STAIRS						
	C2010 STAIR CONSTRUCTION	227 (LF)	Paint				0.00
	1996 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
	-- Paint C2010 STAIR CONSTRUCTION 1996 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
	C2010 STAIR CONSTRUCTION	115 (LF)	Paint				0.00
	2004 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
	-- Paint C2010 STAIR CONSTRUCTION 2004 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						



Work Items by Building Report



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
2017	C30 INTERIOR FINISHES						
	C3020 FLOOR FINISHES	17,701 (SF)	Replace				0.00
	1996 C302005 CARPETING General						
	-- Replace C3020 FLOOR FINISHES 1996 C302005 CARPETING General						
	C3030 CEILING FINISHES	88,900 (SF)	Replace				0.00
	1996 C303001 ACOUSTICAL CEILING TILES & PANELS General						
	-- Replace C3030 CEILING FINISHES 1996 C303001 ACOUSTICAL CEILING TILES & PANELS General						
	C3030 CEILING FINISHES	90,176 (SF)	Replace				0.00
	1996 C303005 SUSPENSION SYSTEMS General						
	-- Replace C3030 CEILING FINISHES 1996 C303005 SUSPENSION SYSTEMS General						
2017	D20 PLUMBING						
	D2010 PLUMBING FIXTURES	8 (EA)	Replace				0.00
	1996 D201006 DRINKING FOUNTAINS AND COOLERS Drinking Fountain						
	-- Replace D2010 PLUMBING FIXTURES D201006 DRINKING FOUNTAINS AND COOLERS General						
	D2010 PLUMBING FIXTURES	73 (EA)	Replace				0.00
	1996 A D201001 WATERCLOSETS General						
	-- Replace D2010 PLUMBING FIXTURES D201001 WATERCLOSETS General						
	D2030 SANITARY WASTE	1,340 (EA)	Replace				0.00
	1996 D203002 VENT PIPE & FITTINGS General						
	-- Replace D2030 SANITARY WASTE D203002 VENT PIPE & FITTINGS General						
	D2040 RAIN WATER DRAINAGE	67 (EA)	Replace				0.00
	1996 D204002 ROOF DRAINS Other						
	-- Replace D2040 RAIN WATER DRAINAGE 1996 3 inch D204002 ROOF DRAINS Other						
2017	D30 HVAC						



Work Items by Building Report



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	D3040 DISTRIBUTION SYSTEMS 1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS D304003 HOT WATER DISTRIBUTION SYSTEMS General	1,000 (MBH)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	200 (TON)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-055 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS AHU-055 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-061 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS AHU-061 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-1 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS AHU-1 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-2 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS AHU-2 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-3 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS AHU-3 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-4 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS AHU-4 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00
	D3050 TERMINAL & PACKAGE UNITS 1996 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton -- Replace D3050 TERMINAL & PACKAGE UNITS Hallway wall units D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton	24 (EA)	Replace				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
	D3050	TERMINAL & PACKAGE UNITS	8 (EA)	Repair				0.00
	2004	D305003 FAN COIL UNITS Duct Mount, 2 Pipe - 1 ton						
	-- Repair D3050 TERMINAL & PACKAGE UNITS 2004 Duct mount units D305003 FAN COIL UNITS General							
	D3060	CONTROLS & INSTRUMENTATION	128 (EA)	Replace				0.00
	1996	D306002 ELECTRONIC CONTROLS General						
	-- Replace D3060 CONTROLS & INSTRUMENTATION D306001 HVAC CONTROLS General							
2017	D40 FIRE PROTECTION							
	D4010	FIRE ALARM AND DETECTION SYSTEMS	108,693 (SF)	Replace				0.00
	1996	D401001 FIRE ALARM DISTRIBUTION Other						
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS D401001 FIRE ALARM DISTRIBUTION General							
	D4010	FIRE ALARM AND DETECTION SYSTEMS	11,612 (SF)	Repair				0.00
	2004	D401001 FIRE ALARM DISTRIBUTION Other						
	-- Repair D4010 FIRE ALARM AND DETECTION SYSTEMS 2004 D401001 FIRE ALARM DISTRIBUTION General							
2017	D50 ELECTRICAL							
	D5030	COMMUNICATIONS & SECURITY	1 (EA)	Repair				0.00
	2004	D503003 INTERCOMMUNICATIONS SYSTEMS 6 stations						
	-- Repair D5030 COMMUNICATIONS & SECURITY 2004 D503003 INTERCOMMUNICATIONS SYSTEMS 6 stations							
	D5090	OTHER ELECTRICAL SERVICES	1 (EA)	Repair				0.00
	2004	D509002 EMERGENCY LIGHTING & POWER Uninterruptible Power Supply - 1.0 kVA						
	-- Repair D5090 OTHER ELECTRICAL SERVICES 2004 D509002 EMERGENCY LIGHTING & POWER Uninterruptible Power Supply							
2018	B20 EXTERIOR ENCLOSURE							
	B2010	EXTERIOR WALLS	75 (LF)	Paint				0.00
	2004	B201006 BALCONY WALLS & HANDRAILS Handrailing						
	-- Paint B2010 EXTERIOR WALLS 2004 B201006 BALCONY WALLS & HANDRAILS Handrailing							



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
B2010	EXTERIOR WALLS 2004 B201007 EXTERIOR SOFFITS General -- Paint B2010 EXTERIOR WALLS 2004 B201007 EXTERIOR SOFFITS General	774 (SF)	Paint				0.00
B2010	EXTERIOR WALLS 2013 B201006 BALCONY WALLS & HANDRAILS Handrailing -- Paint B2010 EXTERIOR WALLS 2013 B201006 BALCONY WALLS & HANDRAILS Handrailing	51 (LF)	Paint				0.00
B2010	EXTERIOR WALLS 2013 B201007 EXTERIOR SOFFITS General -- Paint B2010 EXTERIOR WALLS 2013 B201007 EXTERIOR SOFFITS General	607 (SF)	Paint				0.00
B2030	EXTERIOR DOORS 1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door -- Replace B2030 EXTERIOR DOORS 1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door	34 (EA)	Replace				0.00
2018 B30 ROOFING							
B3010	ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL General -- Replace B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL General	60,664 (SF)	Replace				0.00
B3010	ROOF COVERINGS 1996 B301006 ROOF OPENINGS AND SUPPORTS Skylights -- Replace B3010 ROOF COVERINGS 1996 B301006 ROOF OPENINGS AND SUPPORTS Skylights	180 (SF)	Replace				0.00
B3010	ROOF COVERINGS 1996 B301090 OTHER ROOFING Walkway Protection -- Replace B3010 ROOF COVERINGS 1996 B301090 OTHER ROOFING Walkway Protection	552 (SF)	Replace				0.00
2018 C10 INTERIOR CONSTRUCTION							
C1030	SPECIALTIES 1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions -- Replace C1030 SPECIALTIES 1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions	52 (EA)	Replace				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	C1030 SPECIALTIES 1996 C103005 LOCKERS General -- Replace C1030 SPECIALTIES 1996 C103005 LOCKERS General	882 (EA)	Replace				0.00
	C1030 SPECIALTIES 1996 C103008 COUNTERS Laminated Plastic -- Replace C1030 SPECIALTIES 1996 C103008 COUNTERS Laminated Plastic	327 (LF)	Replace				0.00
2018	C30 INTERIOR FINISHES						
	C3020 FLOOR FINISHES 1996 C302005 CARPETING General -- Replace C3020 FLOOR FINISHES 1996 C302005 CARPETING Carpet Tile	17,701 (SF)	Replace				0.00
	C3030 CEILING FINISHES 1996 C303001 ACOUSTICAL CEILING TILES & PANELS General -- Replace C3030 CEILING FINISHES 1996 C303001 ACOUSTICAL CEILING TILES & PANELS General	88,843 (SF)	Replace				0.00
	C3030 CEILING FINISHES 1996 C303005 SUSPENSION SYSTEMS General -- Replace C3030 CEILING FINISHES 1996 C303005 SUSPENSION SYSTEMS General	90,176 (SF)	Replace				0.00
	C3030 CEILING FINISHES 1996 C303006 METAL STRIP CEILINGS General -- Replace C3030 CEILING FINISHES 1996 C303006 METAL STRIP CEILINGS General	1,333 (SF)	Replace				0.00
2018	D20 PLUMBING						
	D2010 PLUMBING FIXTURES 1996 D201004 SINKS Service Sink -- Repair D2010 PLUMBING FIXTURES 1996 D201004 SINKS Service Sink	3 (EA)	Repair				0.00
	D2030 SANITARY WASTE 1996 D203002 VENT PIPE & FITTINGS General -- Replace D2030 SANITARY WASTE 1996 D203002 VENT PIPE & FITTINGS General	3,861 (EA)	Replace				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
2057	D2040 RAIN WATER DRAINAGE 1996 D204001 PIPE & FITTINGS General -- Replace D2040 RAIN WATER DRAINAGE 1996 D204001 PIPE & FITTINGS General	1,005 (LF)	Replace				0.00
2057	D2040 RAIN WATER DRAINAGE 1996 D204002 ROOF DRAINS Other -- Replace D2040 RAIN WATER DRAINAGE 1996 D204002 ROOF DRAINS Other	67 (EA)	Replace				0.00
2057	D2040 RAIN WATER DRAINAGE 2004 D204001 PIPE & FITTINGS General -- Replace D2040 RAIN WATER DRAINAGE 2004 D204001 PIPE & FITTINGS General	135 (LF)	Replace				0.00
2018	D30 HVAC						
2018	D3040 DISTRIBUTION SYSTEMS 1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General	4,382 (MBH)	Replace				0.00
2018	D3040 DISTRIBUTION SYSTEMS 1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	438 (TON)	Replace				0.00
2018	D3040 DISTRIBUTION SYSTEMS 1996 AHU-055 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS 1996 C D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00
2018	D3040 DISTRIBUTION SYSTEMS 1996 AHU-061 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS 1996 D D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00
2018	D3040 DISTRIBUTION SYSTEMS 1996 AHU-1 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-2 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS 1996 B D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-3 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-4 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS 1996 A D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 ROOFTOP D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 1500 CFM -- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 1500 CFM	2 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 2013 D304003 HOT WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS 2013 D304003 HOT WATER DISTRIBUTION SYSTEMS General	37 (MBH)	Replace				0.00
	D3060 CONTROLS & INSTRUMENTATION 1996 D306002 ELECTRONIC CONTROLS General -- Replace D3060 CONTROLS & INSTRUMENTATION 1996 D306002 ELECTRONIC CONTROLS General	6 (EA)	Replace				0.00
2018	D40 FIRE PROTECTION						
	D4010 FIRE ALARM AND DETECTION SYSTEMS 1996 D401001 FIRE ALARM DISTRIBUTION Other -- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1996 D401001 FIRE ALARM DISTRIBUTION Other	108,693 (SF)	Replace				0.00
2018	D50 ELECTRICAL						
	D5010 ELECTRICAL SERVICE & DISTRIBUTION 1996 D501004 PANELBOARDS Main lugs, 50 amp -- Repair D5010 ELECTRICAL SERVICE & DISTRIBUTION 1996 D501004 PANELBOARDS Main lugs, 50 amp	8 (EA)	Repair				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	D5010 ELECTRICAL SERVICE & DISTRIBUTION 1996 D501004 PANELBOARDS Main lugs, 125 amp -- Repair D5010 ELECTRICAL SERVICE & DISTRIBUTION 1996 D501004 PANELBOARDS Main lugs, 125 amp	4 (EA)	Repair				0.00
	D5010 ELECTRICAL SERVICE & DISTRIBUTION 1996 ROOM 117 D501004 PANELBOARDS Main lugs, 200 amp -- Repair D5010 ELECTRICAL SERVICE & DISTRIBUTION 1996 D501004 PANELBOARDS Main lugs, 200 amp	1 (EA)	Repair				0.00
	D5030 COMMUNICATIONS & SECURITY 1996 D503001 TELECOMMUNICATIONS SYSTEMS General -- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503001 TELECOMMUNICATIONS SYSTEMS General	1 (EA)	Replace				0.00
	D5030 COMMUNICATIONS & SECURITY 1996 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets -- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets	1 (EA)	Replace				0.00
	D5030 COMMUNICATIONS & SECURITY 1996 D503003 INTERCOMMUNICATIONS SYSTEMS 100 stations -- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503003 INTERCOMMUNICATIONS SYSTEMS 100 stations	1 (EA)	Replace				0.00
2019	B20 EXTERIOR ENCLOSURE						
	B2030 EXTERIOR DOORS 1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door -- Replace B2030 EXTERIOR DOORS 1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door	34 (EA)	Replace				0.00
2019	B30 ROOFING						
	B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL General -- Replace B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL General	60,664 (SF)	Replace				0.00
	B3010 ROOF COVERINGS 1996 B301006 ROOF OPENINGS AND SUPPORTS Skylights -- Replace B3010 ROOF COVERINGS 1996 B301006 ROOF OPENINGS AND SUPPORTS Skylights	180 (SF)	Replace				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	B3010 ROOF COVERINGS	552 (SF)	Replace				0.00
	1996 B301090 OTHER ROOFING Walkway Protection						
	-- Replace B3010 ROOF COVERINGS 1996 B301090 OTHER ROOFING Walkway Protection						
2019	C10 INTERIOR CONSTRUCTION						
	C1030 SPECIALTIES	52 (EA)	Replace				0.00
	1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions						
	-- Replace C1030 SPECIALTIES 1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions						
	C1030 SPECIALTIES	882 (EA)	Replace				0.00
	1996 C103005 LOCKERS General						
	-- Replace C1030 SPECIALTIES 1996 C103005 LOCKERS General						
	C1030 SPECIALTIES	327 (LF)	Replace				0.00
	1996 C103008 COUNTERS Laminated Plastic						
	-- Replace C1030 SPECIALTIES 1996 C103008 COUNTERS Laminated Plastic						
2019	C30 INTERIOR FINISHES						
	C3020 FLOOR FINISHES	17,701 (SF)	Replace				0.00
	1996 C302005 CARPETING General						
	-- Replace C3020 FLOOR FINISHES 1996 C302005 CARPETING Carpet Tile						
	C3030 CEILING FINISHES	88,843 (SF)	Replace				0.00
	1996 C303001 ACOUSTICAL CEILING TILES & PANELS General						
	-- Replace C3030 CEILING FINISHES 1996 C303001 ACOUSTICAL CEILING TILES & PANELS General						
	C3030 CEILING FINISHES	90,176 (SF)	Replace				0.00
	1996 C303005 SUSPENSION SYSTEMS General						
	-- Replace C3030 CEILING FINISHES 1996 C303005 SUSPENSION SYSTEMS General						
	C3030 CEILING FINISHES	1,333 (SF)	Replace				0.00
	1996 C303006 METAL STRIP CEILINGS General						
	-- Replace C3030 CEILING FINISHES 1996 C303006 METAL STRIP CEILINGS General						



Work Items by Building Report



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
2019	D20 PLUMBING						
	D2030 SANITARY WASTE	3,861 (EA)	Replace				0.00
	1996 D203002 VENT PIPE & FITTINGS General						
	-- Replace D2030 SANITARY WASTE 1996 D203002 VENT PIPE & FITTINGS General						
	D2040 RAIN WATER DRAINAGE	1,005 (LF)	Replace				0.00
	1996 D204001 PIPE & FITTINGS General						
	-- Replace D2040 RAIN WATER DRAINAGE 1996 D204001 PIPE & FITTINGS General						
	D2040 RAIN WATER DRAINAGE	67 (EA)	Replace				0.00
	1996 D204002 ROOF DRAINS Other						
	-- Replace D2040 RAIN WATER DRAINAGE 1996 D204002 ROOF DRAINS Other						
	D2040 RAIN WATER DRAINAGE	135 (LF)	Replace				0.00
	2004 D204001 PIPE & FITTINGS General						
	-- Replace D2040 RAIN WATER DRAINAGE 2004 D204001 PIPE & FITTINGS General						
2019	D30 HVAC						
	D3040 DISTRIBUTION SYSTEMS	4,382 (MBH)	Replace				0.00
	1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	D3040 DISTRIBUTION SYSTEMS	438 (TON)	Replace				0.00
	1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 AHU-055 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 C D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 AHU-061 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 D D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						



Work Items by Building Report



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-1 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-2 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS 1996 B D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-3 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-4 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS 1996 A D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 ROOFTOP D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 1500 CFM -- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 1500 CFM	2 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 2013 D304003 HOT WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS 2013 D304003 HOT WATER DISTRIBUTION SYSTEMS General	37 (MBH)	Replace				0.00
	D3060 CONTROLS & INSTRUMENTATION 1996 D306002 ELECTRONIC CONTROLS General -- Replace D3060 CONTROLS & INSTRUMENTATION 1996 D306002 ELECTRONIC CONTROLS General	6 (EA)	Replace				0.00
2019	D40 FIRE PROTECTION						
	D4010 FIRE ALARM AND DETECTION SYSTEMS 1996 D401001 FIRE ALARM DISTRIBUTION Other -- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1996 D401001 FIRE ALARM DISTRIBUTION Other	108,693 (SF)	Replace				0.00

2019 D50 ELECTRICAL



Work Items by Building Report



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	D5030 COMMUNICATIONS & SECURITY 1996 D503001 TELECOMMUNICATIONS SYSTEMS General -- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503001 TELECOMMUNICATIONS SYSTEMS General	1 (EA)	Replace				0.00
	D5030 COMMUNICATIONS & SECURITY 1996 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets -- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets	1 (EA)	Replace				0.00
	D5030 COMMUNICATIONS & SECURITY 1996 D503003 INTERCOMMUNICATIONS SYSTEMS 100 stations -- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503003 INTERCOMMUNICATIONS SYSTEMS 100 stations	1 (EA)	Replace				0.00
2020	B20 EXTERIOR ENCLOSURE						
	B2030 EXTERIOR DOORS 1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door -- Replace B2030 EXTERIOR DOORS 1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door	34 (EA)	Replace				0.00
2020	B30 ROOFING						
	B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL General -- Replace B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL General	62,507 (SF)	Replace				0.00
	B3010 ROOF COVERINGS 1996 B301006 ROOF OPENINGS AND SUPPORTS Skylights -- Replace B3010 ROOF COVERINGS 1996 B301006 ROOF OPENINGS AND SUPPORTS Skylights	180 (SF)	Replace				0.00
2020	C10 INTERIOR CONSTRUCTION						
	C1030 SPECIALTIES 1996 C103008 COUNTERS Laminated Plastic -- Replace C1030 SPECIALTIES 1996 C103008 COUNTERS Laminated Plastic	183 (LF)	Replace				0.00
2020	C30 INTERIOR FINISHES						



Work Items by Building Report



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	C3020 FLOOR FINISHES 1996 C302005 CARPETING General -- Replace C3020 FLOOR FINISHES 1996 C302005 CARPETING General	4,800 (SF)	Replace				0.00
	C3030 CEILING FINISHES 1996 C303001 ACOUSTICAL CEILING TILES & PANELS General -- Replace C3030 CEILING FINISHES 1996 C303001 ACOUSTICAL CEILING TILES & PANELS General	84,000 (SF)	Replace				0.00
	C3030 CEILING FINISHES 1996 C303005 SUSPENSION SYSTEMS General -- Replace C3030 CEILING FINISHES 1996 C303005 SUSPENSION SYSTEMS General	84,000 (SF)	Replace				0.00
	C3030 CEILING FINISHES 1996 C303006 METAL STRIP CEILINGS General -- Replace C3030 CEILING FINISHES 1996 C303006 METAL STRIP CEILINGS General	1,700 (SF)	Replace				0.00
2020	D20 PLUMBING						
	D2030 SANITARY WASTE 1996 D203002 VENT PIPE & FITTINGS General -- Replace D2030 SANITARY WASTE 1996 D203002 VENT PIPE & FITTINGS General	3,861 (EA)	Replace				0.00
	D2040 RAIN WATER DRAINAGE 1996 D204001 PIPE & FITTINGS General -- Replace D2040 RAIN WATER DRAINAGE 1996 D204001 PIPE & FITTINGS General	1,005 (LF)	Replace				0.00
	D2040 RAIN WATER DRAINAGE 1996 D204002 ROOF DRAINS Other -- Replace D2040 RAIN WATER DRAINAGE 1996 D204002 ROOF DRAINS Other	67 (EA)	Replace				0.00
	D2040 RAIN WATER DRAINAGE 2004 D204001 PIPE & FITTINGS General -- Replace D2040 RAIN WATER DRAINAGE 2004 D204001 PIPE & FITTINGS General	135 (LF)	Replace				0.00
2020	D30 HVAC						



Work Items by Building Report



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	D3030 COOLING GENERATING SYSTEMS	1 (EA)	Replace				0.00
	2004 CH-435 D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 60 TN						
	-- Replace D3030 COOLING GENERATING SYSTEMS 2004 CH-435 D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 60 TN						
	D3030 COOLING GENERATING SYSTEMS	1 (EA)	Replace				0.00
	2013 CHILLER 788 D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 60 TN						
	-- Replace D3030 COOLING GENERATING SYSTEMS 2013 CHILLER 788 D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 60 TN						
	D3040 DISTRIBUTION SYSTEMS	4,382 (MBH)	Replace				0.00
	1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	D3040 DISTRIBUTION SYSTEMS	438 (TON)	Replace				0.00
	1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 AHU-055 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 AHU-055 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 AHU-061 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 AHU-061 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 AHU-1 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 AHU-1 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 AHU-2 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 AHU-2 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 AHU-3 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 AHU-3 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM						



Work Items by Building Report



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 AHU-4 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 AHU-4 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	2 (EA)	Replace				0.00
	1996 ROOFTOP D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 1500 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 ROOFTOP D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 1500 CFM						
	D3040 DISTRIBUTION SYSTEMS	37 (MBH)	Replace				0.00
	2013 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS 2013 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	2013 AHU-292 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 2013 AHU-292 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3050 TERMINAL & PACKAGE UNITS	3 (EA)	Replace				0.00
	1996 A D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton						
	-- Replace D3050 TERMINAL & PACKAGE UNITS 1996 A D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton						
	D3060 CONTROLS & INSTRUMENTATION	6 (EA)	Replace				0.00
	1996 D306002 ELECTRONIC CONTROLS General						
	-- Replace D3060 CONTROLS & INSTRUMENTATION 1996 D306002 ELECTRONIC CONTROLS General						
2020	D40 FIRE PROTECTION						
	D4010 FIRE ALARM AND DETECTION SYSTEMS	108,693 (SF)	Replace				0.00
	1996 D401001 FIRE ALARM DISTRIBUTION Other						
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1996 D401001 FIRE ALARM DISTRIBUTION Other						
2020	D50 ELECTRICAL						
	D5030 COMMUNICATIONS & SECURITY	1 (EA)	Replace				0.00
	1996 D503001 TELECOMMUNICATIONS SYSTEMS General						
	-- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503001 TELECOMMUNICATIONS SYSTEMS General						



Work Items by Building Report



Support Site

Cost Book: Reference

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	D5030 COMMUNICATIONS & SECURITY 1996 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets -- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets	1 (EA)	Replace				0.00
	D5030 COMMUNICATIONS & SECURITY 1996 D503003 INTERCOMMUNICATIONS SYSTEMS 100 stations -- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503003 INTERCOMMUNICATIONS SYSTEMS 100 stations	1 (EA)	Replace				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
2015	B20 EXTERIOR ENCLOSURE						
	B2010 EXTERIOR WALLS	3,900 (LF)	Replace				0.00
	1996 B201004 PARAPETS General						
	-- Replace B2010 EXTERIOR WALLS 1996 B201004 PARAPETS Unknown						
2015	B30 ROOFING						
	B3010 ROOF COVERINGS	58,000 (SF)	Replace				0.00
	1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen						
	-- Replace B3010 ROOF COVERINGS 1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen						
	B3010 ROOF COVERINGS	58,000 (SF)	Replace				0.00
	1996 B301003 ROOF INSULATION & FILL General						
	-- Replace B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL Unknown						
	B3010 ROOF COVERINGS	3,500 (LF)	Replace				0.00
	1996 B301004 FLASHINGS & TRIM Flashings - Base						
	-- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Base						
	B3010 ROOF COVERINGS	3,900 (LF)	Replace				0.00
	1996 B301004 FLASHINGS & TRIM Flashings - Cap						
	-- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Cap						
	B3010 ROOF COVERINGS	103 (EA)	Replace				0.00
	1996 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations						
	-- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations						
	B3010 ROOF COVERINGS	11,778 (SF)	Repair				0.00
	1996 A B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen						
	-- Critical repair work for B3010 ROOF COVERINGS 2012 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen						
	B3010 ROOF COVERINGS	10 (EA)	Replace				0.00
	1996 B B301004 FLASHINGS & TRIM Flashings - Pitch Pans						
	-- Replace B3010 ROOF COVERINGS 1996b B301004 FLASHINGS & TRIM Flashings - Pitch Pans						



Work Items by Building Report



Support Site

Cost Book: Reference

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
2015	C10 INTERIOR CONSTRUCTION						
	C1030 SPECIALTIES	8 (EA)	Replace				0.00
	1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Shower Compartment						
	-- Replace C1030 SPECIALTIES 1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Shower Compartment						
	C1030 SPECIALTIES	29 (EA)	Replace				0.00
	1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions - Coated Steel						
	-- Replace C1030 SPECIALTIES 1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions						
	C1030 SPECIALTIES	611 (LF)	Replace				0.00
	1996 C103010 CASEWORK General						
	-- Replace C1030 SPECIALTIES 1996 C103010 CASEWORK General						
2015	C20 STAIRS						
	C2010 STAIR CONSTRUCTION	145 (LF)	Paint				0.00
	1996 A C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
	-- Paint C2010 STAIR CONSTRUCTION 1996 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
	C2010 STAIR CONSTRUCTION	615 (LF)	Paint				0.00
	1996 B C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
	-- Paint C2010 STAIR CONSTRUCTION 1996 Exterior C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
2015	C30 INTERIOR FINISHES						
	C3010 WALL FINISHES	2,117 (SF)	Replace				0.00
	1996 C301006 ACOUSTICAL PANELS ADHERED TO WALLS General						
	-- Replace C3010 WALL FINISHES 1996 C301006 ACOUSTICAL PANELS ADHERED TO WALLS General						
	C3030 CEILING FINISHES	99,967 (SF)	Replace				0.00
	1996 C303001 ACOUSTICAL CEILING TILES & PANELS General						
	-- Replace C3030 CEILING FINISHES 1996 C303001 ACOUSTICAL CEILING TILES & PANELS General						



Work Items by Building Report



Support Site

Cost Book: Reference

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	C3030 CEILING FINISHES 1996 C303005 SUSPENSION SYSTEMS General -- Replace C3030 CEILING FINISHES 1996 C303005 SUSPENSION SYSTEMS General	99,967 (SF)	Replace				0.00
2015	D20 PLUMBING						
	D2010 PLUMBING FIXTURES 1996 A D201001 WATERCLOSETS General -- Repair D2010 PLUMBING FIXTURES D201001 WATERCLOSETS General	26 (EA)	Repair				0.00
	D2030 SANITARY WASTE 1996 D203002 VENT PIPE & FITTINGS General -- Replace D2030 SANITARY WASTE D203002 VENT PIPE & FITTINGS General	2,119 (EA)	Replace				0.00
	D2040 RAIN WATER DRAINAGE 1996 D204002 ROOF DRAINS Other -- Replace D2040 RAIN WATER DRAINAGE 1996 3 inch D204002 ROOF DRAINS Other	69 (EA)	Replace				0.00
2015	D30 HVAC						
	D3040 DISTRIBUTION SYSTEMS 1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS D304003 HOT WATER DISTRIBUTION SYSTEMS General	1,000 (MBH)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	200 (TON)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 UTA-1 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS AHU-1 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 UTA-2 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS AHU-2 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 UTA-3 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS AHU-3 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 UTA-4 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS AHU-4 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3050 TERMINAL & PACKAGE UNITS	11 (EA)	Replace				0.00
	1996 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton						
	-- Replace D3050 TERMINAL & PACKAGE UNITS FCU cabinet floor mount D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton						
2015	D40 FIRE PROTECTION						
	D4010 FIRE ALARM AND DETECTION SYSTEMS	111,107 (SF)	Replace				0.00
	1996 D401001 FIRE ALARM DISTRIBUTION Other						
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS D401001 FIRE ALARM DISTRIBUTION General						
2016	B20 EXTERIOR ENCLOSURE						
	B2010 EXTERIOR WALLS	3,900 (LF)	Replace				0.00
	1996 B201004 PARAPETS General						
	-- Replace B2010 EXTERIOR WALLS 1996 B201004 PARAPETS Unknown						
2016	B30 ROOFING						
	B3010 ROOF COVERINGS	58,000 (SF)	Replace				0.00
	1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen						
	-- Replace B3010 ROOF COVERINGS 1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen						
	B3010 ROOF COVERINGS	58,000 (SF)	Replace				0.00
	1996 B301003 ROOF INSULATION & FILL General						
	-- Replace B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL Unknown						



Work Items by Building Report



Support Site

Cost Book: Reference

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Base -- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Base	3,500 (LF)	Replace				0.00
	B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Cap -- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Cap	3,900 (LF)	Replace				0.00
	B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations -- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	103 (EA)	Replace				0.00
	B3010 ROOF COVERINGS 1996 A B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen -- Replace B3010 ROOF COVERINGS 2012 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	11,778 (SF)	Replace				0.00
	B3010 ROOF COVERINGS 1996 B B301004 FLASHINGS & TRIM Flashings - Pitch Pans -- Replace B3010 ROOF COVERINGS 1996b B301004 FLASHINGS & TRIM Flashings - Pitch Pans	10 (EA)	Replace				0.00
2016	C10 INTERIOR CONSTRUCTION						
	C1030 SPECIALTIES 1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Shower Compartment -- Replace C1030 SPECIALTIES 1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Shower Compartment	8 (EA)	Replace				0.00
	C1030 SPECIALTIES 1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions - Coated Steel -- Replace C1030 SPECIALTIES 1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions	29 (EA)	Replace				0.00
	C1030 SPECIALTIES 1996 C103010 CASEWORK General -- Replace C1030 SPECIALTIES 1996 C103010 CASEWORK General	611 (LF)	Replace				0.00
2016	C20 STAIRS						



Work Items by Building Report



Support Site

Cost Book: Reference

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	C2010 STAIR CONSTRUCTION	145 (LF)	Paint				0.00
	1996 A C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
	-- Paint C2010 STAIR CONSTRUCTION 1996 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
	C2010 STAIR CONSTRUCTION	615 (LF)	Paint				0.00
	1996 B C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
	-- Paint C2010 STAIR CONSTRUCTION 1996 Exterior C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
2016	C30 INTERIOR FINISHES						
	C3010 WALL FINISHES	2,117 (SF)	Replace				0.00
	1996 C301006 ACOUSTICAL PANELS ADHERED TO WALLS General						
	-- Replace C3010 WALL FINISHES 1996 C301006 ACOUSTICAL PANELS ADHERED TO WALLS General						
	C3030 CEILING FINISHES	99,967 (SF)	Replace				0.00
	1996 C303001 ACOUSTICAL CEILING TILES & PANELS General						
	-- Replace C3030 CEILING FINISHES 1996 C303001 ACOUSTICAL CEILING TILES & PANELS General						
	C3030 CEILING FINISHES	99,967 (SF)	Replace				0.00
	1996 C303005 SUSPENSION SYSTEMS General						
	-- Replace C3030 CEILING FINISHES 1996 C303005 SUSPENSION SYSTEMS General						
2016	D20 PLUMBING						
	D2010 PLUMBING FIXTURES	26 (EA)	Repair				0.00
	1996 A D201001 WATERCLOSETS General						
	-- Repair D2010 PLUMBING FIXTURES D201001 WATERCLOSETS General						
	D2030 SANITARY WASTE	2,119 (EA)	Replace				0.00
	1996 D203002 VENT PIPE & FITTINGS General						
	-- Replace D2030 SANITARY WASTE D203002 VENT PIPE & FITTINGS General						
	D2040 RAIN WATER DRAINAGE	69 (EA)	Replace				0.00
	1996 D204002 ROOF DRAINS Other						
	-- Replace D2040 RAIN WATER DRAINAGE 1996 3 inch D204002 ROOF DRAINS Other						



Work Items by Building Report



Support Site

Cost Book: Reference

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Year	System Component	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
Section Description – Description							
2016	D30 HVAC						
	D3040 DISTRIBUTION SYSTEMS	1,000 (MBH)	Replace				0.00
	1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	– Replace D3040 DISTRIBUTION SYSTEMS D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	D3040 DISTRIBUTION SYSTEMS	200 (TON)	Replace				0.00
	1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General						
	– Replace D3040 DISTRIBUTION SYSTEMS D304006 CHILLED WATER DISTRIBUTION SYSTEMS General						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 UTA-1 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	– Replace D3040 DISTRIBUTION SYSTEMS AHU-1 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 UTA-2 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	– Replace D3040 DISTRIBUTION SYSTEMS AHU-2 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 UTA-3 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	– Replace D3040 DISTRIBUTION SYSTEMS AHU-3 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 UTA-4 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	– Replace D3040 DISTRIBUTION SYSTEMS AHU-4 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3050 TERMINAL & PACKAGE UNITS	11 (EA)	Replace				0.00
	1996 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton						
	– Replace D3050 TERMINAL & PACKAGE UNITS FCU cabinet floor mount D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton						
	D3050 TERMINAL & PACKAGE UNITS	57 (EA)	Repair				0.00
	1996 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 2 ton						
	– Repair D3050 TERMINAL & PACKAGE UNITS FCU duct mount D305003 FAN COIL UNITS Cab Mount, Two Pipe - 2 ton						
2016	D40 FIRE PROTECTION						



Work Items by Building Report



Support Site

Cost Book: Reference

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	D4010 FIRE ALARM AND DETECTION SYSTEMS 1996 D401001 FIRE ALARM DISTRIBUTION Other -- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS D401001 FIRE ALARM DISTRIBUTION General	111,107 (SF)	Replace				0.00
2017	B20 EXTERIOR ENCLOSURE						
	B2010 EXTERIOR WALLS 1996 B201001 EXTERIOR CLOSURE Stucco -- Paint B2010 EXTERIOR WALLS 1996 B201001 EXTERIOR CLOSURE Stucco	33,610 (SF)	Paint				0.00
	B2010 EXTERIOR WALLS 1996 B201004 PARAPETS General -- Replace B2010 EXTERIOR WALLS 1996 B201004 PARAPETS Unknown	3,900 (LF)	Replace				0.00
	B2010 EXTERIOR WALLS 1996 B201007 EXTERIOR SOFFITS General -- Paint B2010 EXTERIOR WALLS 1996 B201007 EXTERIOR SOFFITS General	5,588 (SF)	Paint				0.00
	B2030 EXTERIOR DOORS 1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door -- Replace B2030 EXTERIOR DOORS 1996 B203002 GLAZED DOORS General	37 (EA)	Replace				0.00
2017	B30 ROOFING						
	B3010 ROOF COVERINGS 1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen -- Replace B3010 ROOF COVERINGS 1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	58,000 (SF)	Replace				0.00
	B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL General -- Replace B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL Unknown	58,000 (SF)	Replace				0.00
	B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Base -- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Base	3,500 (LF)	Replace				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Cap -- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Cap	3,900 (LF)	Replace				0.00
	B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations -- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	103 (EA)	Replace				0.00
	B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM General -- Paint B3010 ROOF COVERINGS 1996 Stucco Fascia B301004 FLASHINGS & TRIM Other	1,124 (LF)	Paint				0.00
	B3010 ROOF COVERINGS 1996 B301005 GUTTERS & DOWNSPOUTS Downspouts -- Paint B3010 ROOF COVERINGS 1996 B301005 GUTTERS & DOWNSPOUTS Downspouts	1,200 (LF)	Paint				0.00
	B3010 ROOF COVERINGS 1996 B301090 OTHER ROOFING Walkway Protection -- Replace B3010 ROOF COVERINGS 1996 B301090 OTHER ROOFING Walkway Protection	862 (SF)	Replace				0.00
	B3010 ROOF COVERINGS 1996 B B301004 FLASHINGS & TRIM Flashings - Pitch Pans -- Replace B3010 ROOF COVERINGS 1996b B301004 FLASHINGS & TRIM Flashings - Pitch Pans	10 (EA)	Replace				0.00
2017	C10 INTERIOR CONSTRUCTION						
	C1010 PARTITIONS 1996 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing -- Paint C1010 PARTITIONS 1996 C101001 FIXED PARTITIONS General	109,513 (SF)	Paint				0.00
	C1030 SPECIALTIES 1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Shower Compartment -- Replace C1030 SPECIALTIES 1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Shower Compartment	8 (EA)	Replace				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	C1030 SPECIALTIES	29 (EA)	Replace				0.00
	1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions - Coated Steel						
	-- Replace C1030 SPECIALTIES 1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions						
	C1030 SPECIALTIES	297 (LF)	Replace				0.00
	1996 C103008 COUNTERS Laminated Plastic						
	-- Replace C1030 SPECIALTIES 1996 C103008 COUNTERS General						
	C1030 SPECIALTIES	611 (LF)	Replace				0.00
	1996 C103010 CASEWORK General						
	-- Replace C1030 SPECIALTIES 1996 C103010 CASEWORK General						
2017	C20 STAIRS						
	C2010 STAIR CONSTRUCTION	145 (LF)	Paint				0.00
	1996 A C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
	-- Paint C2010 STAIR CONSTRUCTION 1996 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
	C2010 STAIR CONSTRUCTION	615 (LF)	Paint				0.00
	1996 B C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
	-- Paint C2010 STAIR CONSTRUCTION 1996 Exterior C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
2017	C30 INTERIOR FINISHES						
	C3010 WALL FINISHES	2,117 (SF)	Replace				0.00
	1996 C301006 ACOUSTICAL PANELS ADHERED TO WALLS General						
	-- Replace C3010 WALL FINISHES 1996 C301006 ACOUSTICAL PANELS ADHERED TO WALLS General						
	C3020 FLOOR FINISHES	5,652 (SF)	Replace				0.00
	1996 C302005 CARPETING General						
	-- Replace C3020 FLOOR FINISHES 1996 C302005 CARPETING General						
	C3030 CEILING FINISHES	99,967 (SF)	Replace				0.00
	1996 C303001 ACOUSTICAL CEILING TILES & PANELS General						
	-- Replace C3030 CEILING FINISHES 1996 C303001 ACOUSTICAL CEILING TILES & PANELS General						



Work Items by Building Report



Support Site

Cost Book: Reference

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	C3030 CEILING FINISHES 1996 C303005 SUSPENSION SYSTEMS General -- Replace C3030 CEILING FINISHES 1996 C303005 SUSPENSION SYSTEMS General	99,967 (SF)	Replace				0.00
2017	D20 PLUMBING						
	D2030 SANITARY WASTE 1996 D203002 VENT PIPE & FITTINGS General -- Replace D2030 SANITARY WASTE D203002 VENT PIPE & FITTINGS General	2,119 (EA)	Replace				0.00
	D2040 RAIN WATER DRAINAGE 1996 D204002 ROOF DRAINS Other -- Replace D2040 RAIN WATER DRAINAGE 1996 3 inch D204002 ROOF DRAINS Other	69 (EA)	Replace				0.00
2017	D30 HVAC						
	D3040 DISTRIBUTION SYSTEMS 1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS D304003 HOT WATER DISTRIBUTION SYSTEMS General	1,000 (MBH)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	200 (TON)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 ROOFTOP A D304007 EXHAUST SYSTEMS Fume Hood Exhaust System - 3', 1000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS Science fume hood fans D304007 EXHAUST SYSTEMS Fume Hood Exhaust System - 3', 1000 CFM	5 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 UTA-1 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS AHU-1 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 UTA-2 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS AHU-2 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	D3040 DISTRIBUTION SYSTEMS 1996 UTA-3 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS AHU-3 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 UTA-4 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS AHU-4 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00
	D3050 TERMINAL & PACKAGE UNITS 1996 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton -- Replace D3050 TERMINAL & PACKAGE UNITS FCU cabinet floor mount D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton	11 (EA)	Replace				0.00
2017	D40 FIRE PROTECTION						
	D4010 FIRE ALARM AND DETECTION SYSTEMS 1996 D401001 FIRE ALARM DISTRIBUTION Other -- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS D401001 FIRE ALARM DISTRIBUTION General	111,107 (SF)	Replace				0.00
2018	B20 EXTERIOR ENCLOSURE						
	B2030 EXTERIOR DOORS 1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door -- Replace B2030 EXTERIOR DOORS 1996 B203002 GLAZED DOORS General	37 (EA)	Replace				0.00
2018	B30 ROOFING						
	B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL General -- Replace B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL General	67,200 (SF)	Replace				0.00
	B3010 ROOF COVERINGS 1996 B301005 GUTTERS & DOWNSPOUTS Downspouts -- Paint B3010 ROOF COVERINGS 1996 B301005 GUTTERS & DOWNSPOUTS Downspouts	1,200 (LF)	Paint				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	B3010 ROOF COVERINGS	862 (SF)	Replace				0.00
	1996 B301090 OTHER ROOFING Walkway Protection						
	-- Replace B3010 ROOF COVERINGS 1996 B301090 OTHER ROOFING Walkway Protection						
2018	C10 INTERIOR CONSTRUCTION						
	C1030 SPECIALTIES	8 (EA)	Replace				0.00
	1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Shower Compartment						
	-- Replace C1030 SPECIALTIES 1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Shower Compartment						
	C1030 SPECIALTIES	29 (EA)	Replace				0.00
	1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions - Coated Steel						
	-- Replace C1030 SPECIALTIES 1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions - Coated Steel						
	C1030 SPECIALTIES	1,273 (EA)	Replace				0.00
	1996 C103005 LOCKERS General						
	-- Replace C1030 SPECIALTIES 1996 C103005 LOCKERS General						
2018	C20 STAIRS						
	C2010 STAIR CONSTRUCTION	145 (LF)	Paint				0.00
	1996 A C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
	-- Paint C2010 STAIR CONSTRUCTION 1996 A C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
	C2010 STAIR CONSTRUCTION	165 (LF)	Paint				0.00
	1996 B C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
	-- Paint C2010 STAIR CONSTRUCTION 1996 B C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
2018	C30 INTERIOR FINISHES						
	C3010 WALL FINISHES	2,117 (SF)	Replace				0.00
	1996 C301006 ACOUSTICAL PANELS ADHERED TO WALLS General						
	-- Replace C3010 WALL FINISHES 1996 C301006 ACOUSTICAL PANELS ADHERED TO WALLS General						



Work Items by Building Report



Support Site

Cost Book: Reference

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
	C3030 CEILING FINISHES	1996 C303001 ACOUSTICAL CEILING TILES & PANELS General	99,967 (SF)	Replace				0.00
-- Replace C3030 CEILING FINISHES 1996 C303001 ACOUSTICAL CEILING TILES & PANELS General								
	C3030 CEILING FINISHES	1996 C303005 SUSPENSION SYSTEMS General	99,967 (SF)	Replace				0.00
-- Replace C3030 CEILING FINISHES 1996 C303005 SUSPENSION SYSTEMS General								
2018 D20 PLUMBING								
	D2010 PLUMBING FIXTURES	1996 D201004 SINKS Stainless	7 (EA)	Repair				0.00
-- Repair D2010 PLUMBING FIXTURES 1996 D201004 SINKS Stainless								
	D2030 SANITARY WASTE	1996 D203002 VENT PIPE & FITTINGS General	3,947 (EA)	Replace				0.00
-- Replace D2030 SANITARY WASTE 1996 D203002 VENT PIPE & FITTINGS General								
	D2040 RAIN WATER DRAINAGE	1996 D204001 PIPE & FITTINGS General	2,070 (LF)	Replace				0.00
-- Replace D2040 RAIN WATER DRAINAGE 1996 D204001 PIPE & FITTINGS General								
	D2040 RAIN WATER DRAINAGE	1996 D204002 ROOF DRAINS Other	69 (EA)	Replace				0.00
-- Replace D2040 RAIN WATER DRAINAGE 1996 D204002 ROOF DRAINS Other								
2018 D30 HVAC								
	D3040 DISTRIBUTION SYSTEMS	1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General	3,778 (MBH)	Replace				0.00
-- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General								
	D3040 DISTRIBUTION SYSTEMS	1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	378 (TON)	Replace				0.00
-- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General								



Work Items by Building Report



Support Site

Cost Book: Reference

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	D3040 DISTRIBUTION SYSTEMS	5 (EA)	Replace				0.00
	1996 ROOFTOP A D304007 EXHAUST SYSTEMS Fume Hood Exhaust System - 3', 1000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304007 EXHAUST SYSTEMS Fume Hood Exhaust System - 3', 1000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 UTA-1 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 UTA-2 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 A D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 UTA-3 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 B D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 UTA-4 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 C D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3050 TERMINAL & PACKAGE UNITS	11 (EA)	Replace				0.00
	1996 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton						
	-- Replace D3050 TERMINAL & PACKAGE UNITS 1996 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton						
2018	D40 FIRE PROTECTION						
	D4010 FIRE ALARM AND DETECTION SYSTEMS	111,107 (SF)	Replace				0.00
	1996 D401001 FIRE ALARM DISTRIBUTION Other						
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1996 D401001 FIRE ALARM DISTRIBUTION Other						
2018	D50 ELECTRICAL						
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	7 (EA)	Repair				0.00
	1996 D501004 PANELBOARDS Main lugs, 125 amp						
	-- Repair D5010 ELECTRICAL SERVICE & DISTRIBUTION 1996 D501004 PANELBOARDS Main lugs, 125 amp						



Work Items by Building Report



Support Site

Cost Book: Reference

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	D5010 ELECTRICAL SERVICE & DISTRIBUTION 1996 ROOM 226 D501004 PANELBOARDS Main lugs, 200 amp -- Repair D5010 ELECTRICAL SERVICE & DISTRIBUTION 1996 D501004 PANELBOARDS Main lugs, 200 amp	2 (EA)	Repair				0.00
	D5030 COMMUNICATIONS & SECURITY 1996 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets -- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets	1 (EA)	Replace				0.00
	D5030 COMMUNICATIONS & SECURITY 1996 D503003 INTERCOMMUNICATIONS SYSTEMS 50 stations -- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503003 INTERCOMMUNICATIONS SYSTEMS 50 stations	1 (EA)	Replace				0.00
	D5030 COMMUNICATIONS & SECURITY 1996 D503005 SECURITY SYSTEMS General -- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503005 SECURITY SYSTEMS General	1 (EA)	Replace				0.00
	D5030 COMMUNICATIONS & SECURITY 1996 D503007 CLOCK & PROGRAM SYSTEMS General -- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503007 CLOCK & PROGRAM SYSTEMS General	1 (EA)	Replace				0.00
2019	B20 EXTERIOR ENCLOSURE						
	B2010 EXTERIOR WALLS 1996 A B201010 EXTERIOR JOINT SEALANT General -- Replace B2010 EXTERIOR WALLS 1996 A B201010 EXTERIOR JOINT SEALANT General	1,500 (LF)	Replace				0.00
	B2010 EXTERIOR WALLS 1996 B B201010 EXTERIOR JOINT SEALANT General -- Replace B2010 EXTERIOR WALLS 1996 B B201010 EXTERIOR JOINT SEALANT General	5,000 (LF)	Replace				0.00
	B2010 EXTERIOR WALLS 1996 C B201010 EXTERIOR JOINT SEALANT General -- Replace B2010 EXTERIOR WALLS 1996 C B201010 EXTERIOR JOINT SEALANT General	167 (LF)	Replace				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	B2030 EXTERIOR DOORS	37 (EA)	Replace				0.00
	1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door						
	-- Replace B2030 EXTERIOR DOORS 1996 B203002 GLAZED DOORS General						
2019	B30 ROOFING						
	B3010 ROOF COVERINGS	67,200 (SF)	Replace				0.00
	1996 B301003 ROOF INSULATION & FILL General						
	-- Replace B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL General						
	B3010 ROOF COVERINGS	862 (SF)	Replace				0.00
	1996 B301090 OTHER ROOFING Walkway Protection						
	-- Replace B3010 ROOF COVERINGS 1996 B301090 OTHER ROOFING Walkway Protection						
2019	C10 INTERIOR CONSTRUCTION						
	C1030 SPECIALTIES	8 (EA)	Replace				0.00
	1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Shower Compartment						
	-- Replace C1030 SPECIALTIES 1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Shower Compartment						
	C1030 SPECIALTIES	29 (EA)	Replace				0.00
	1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions - Coated Steel						
	-- Replace C1030 SPECIALTIES 1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions - Coated Steel						
	C1030 SPECIALTIES	1,273 (EA)	Replace				0.00
	1996 C103005 LOCKERS General						
	-- Replace C1030 SPECIALTIES 1996 C103005 LOCKERS General						
2019	C30 INTERIOR FINISHES						
	C3010 WALL FINISHES	2,117 (SF)	Replace				0.00
	1996 C301006 ACOUSTICAL PANELS ADHERED TO WALLS General						
	-- Replace C3010 WALL FINISHES 1996 C301006 ACOUSTICAL PANELS ADHERED TO WALLS General						



Work Items by Building Report



Support Site

Cost Book: Reference

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	C3020 FLOOR FINISHES 1996 C302005 CARPETING General -- Replace C3020 FLOOR FINISHES 1996 C302005 CARPETING Carpet Tile	5,652 (SF)	Replace				0.00
	C3030 CEILING FINISHES 1996 C303001 ACOUSTICAL CEILING TILES & PANELS General -- Replace C3030 CEILING FINISHES 1996 C303001 ACOUSTICAL CEILING TILES & PANELS General	99,967 (SF)	Replace				0.00
	C3030 CEILING FINISHES 1996 C303005 SUSPENSION SYSTEMS General -- Replace C3030 CEILING FINISHES 1996 C303005 SUSPENSION SYSTEMS General	99,967 (SF)	Replace				0.00
2019	D20 PLUMBING						
	D2030 SANITARY WASTE 1996 D203002 VENT PIPE & FITTINGS General -- Replace D2030 SANITARY WASTE 1996 D203002 VENT PIPE & FITTINGS General	3,947 (EA)	Replace				0.00
	D2040 RAIN WATER DRAINAGE 1996 D204001 PIPE & FITTINGS General -- Replace D2040 RAIN WATER DRAINAGE 1996 D204001 PIPE & FITTINGS General	2,070 (LF)	Replace				0.00
	D2040 RAIN WATER DRAINAGE 1996 D204002 ROOF DRAINS Other -- Replace D2040 RAIN WATER DRAINAGE 1996 D204002 ROOF DRAINS Other	69 (EA)	Replace				0.00
2019	D30 HVAC						
	D3040 DISTRIBUTION SYSTEMS 1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General	3,778 (MBH)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	378 (TON)	Replace				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	D3040 DISTRIBUTION SYSTEMS	5 (EA)	Replace				0.00
	1996 ROOFTOP A D304007 EXHAUST SYSTEMS Fume Hood Exhaust System - 3', 1000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304007 EXHAUST SYSTEMS Fume Hood Exhaust System - 3', 1000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 UTA-1 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 UTA-2 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 A D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 UTA-3 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 B D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 UTA-4 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 C D304008 AIR HANDLING UNITS Rooftop - 5000 CFM						
	D3050 TERMINAL & PACKAGE UNITS	11 (EA)	Replace				0.00
	1996 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton						
	-- Replace D3050 TERMINAL & PACKAGE UNITS 1996 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton						
2019	D40 FIRE PROTECTION						
	D4010 FIRE ALARM AND DETECTION SYSTEMS	111,107 (SF)	Replace				0.00
	1996 D401001 FIRE ALARM DISTRIBUTION Other						
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1996 D401001 FIRE ALARM DISTRIBUTION Other						
2019	D50 ELECTRICAL						
	D5030 COMMUNICATIONS & SECURITY	1 (EA)	Replace				0.00
	1996 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets						
	-- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets						



Work Items by Building Report



Support Site

Cost Book: Reference

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	D5030 COMMUNICATIONS & SECURITY 1996 D503003 INTERCOMMUNICATIONS SYSTEMS 50 stations -- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503003 INTERCOMMUNICATIONS SYSTEMS 50 stations	1 (EA)	Replace				0.00
	D5030 COMMUNICATIONS & SECURITY 1996 D503005 SECURITY SYSTEMS General -- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503005 SECURITY SYSTEMS General	1 (EA)	Replace				0.00
	D5030 COMMUNICATIONS & SECURITY 1996 D503007 CLOCK & PROGRAM SYSTEMS General -- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503007 CLOCK & PROGRAM SYSTEMS General	1 (EA)	Replace				0.00
2020	B20 EXTERIOR ENCLOSURE						
	B2030 EXTERIOR DOORS 1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door -- Replace B2030 EXTERIOR DOORS 1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door	37 (EA)	Replace				0.00
2020	B30 ROOFING						
	B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL General -- Replace B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL General	67,200 (SF)	Replace				0.00
	B3010 ROOF COVERINGS 1996 B301006 ROOF OPENINGS AND SUPPORTS Skylights -- Replace B3010 ROOF COVERINGS 1996 B301006 ROOF OPENINGS AND SUPPORTS Skylights	180 (SF)	Replace				0.00
2020	C10 INTERIOR CONSTRUCTION						
	C1030 SPECIALTIES 1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Shower Compartment -- Replace C1030 SPECIALTIES 1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Shower Compartment	6 (EA)	Replace				0.00
2020	C30 INTERIOR FINISHES						



Work Items by Building Report



Support Site

Cost Book: Reference

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	C3010 WALL FINISHES 1996 C301006 ACOUSTICAL PANELS ADHERED TO WALLS General -- Replace C3010 WALL FINISHES 1996 C301006 ACOUSTICAL PANELS ADHERED TO WALLS General	2,558 (SF)	Replace				0.00
	C3020 FLOOR FINISHES 1996 C302005 CARPETING General -- Replace C3020 FLOOR FINISHES 1996 C302005 CARPETING General	5,652 (SF)	Replace				0.00
	C3030 CEILING FINISHES 1996 C303001 ACOUSTICAL CEILING TILES & PANELS General -- Replace C3030 CEILING FINISHES 1996 C303001 ACOUSTICAL CEILING TILES & PANELS General	85,811 (SF)	Replace				0.00
	C3030 CEILING FINISHES 1996 C303005 SUSPENSION SYSTEMS General -- Replace C3030 CEILING FINISHES 1996 C303005 SUSPENSION SYSTEMS General	85,811 (SF)	Replace				0.00
2020	D20 PLUMBING						
	D2030 SANITARY WASTE 1996 D203002 VENT PIPE & FITTINGS General -- Replace D2030 SANITARY WASTE 1996 D203002 VENT PIPE & FITTINGS General	3,947 (EA)	Replace				0.00
	D2040 RAIN WATER DRAINAGE 1996 D204001 PIPE & FITTINGS General -- Replace D2040 RAIN WATER DRAINAGE 1996 D204001 PIPE & FITTINGS General	2,070 (LF)	Replace				0.00
	D2040 RAIN WATER DRAINAGE 1996 D204002 ROOF DRAINS Other -- Replace D2040 RAIN WATER DRAINAGE 1996 D204002 ROOF DRAINS Other	69 (EA)	Replace				0.00
2020	D30 HVAC						
	D3040 DISTRIBUTION SYSTEMS 1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General	3,778 (MBH)	Replace				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	D3040 DISTRIBUTION SYSTEMS 1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	378 (TON)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 ROOFTOP A D304007 EXHAUST SYSTEMS Fume Hood Exhaust System - 3', 1000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS 1996 ROOFTOP A D304007 EXHAUST SYSTEMS Fume Hood Exhaust System - 3', 1000 CFM	2 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 UTA-1 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS 1996 UTA-1 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 UTA-2 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS 1996 UTA-2 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 UTA-3 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS 1996 UTA-3 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 UTA-4 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS 1996 UTA-4 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	Replace				0.00
	D3050 TERMINAL & PACKAGE UNITS 1996 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton -- Replace D3050 TERMINAL & PACKAGE UNITS 1996 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton	11 (EA)	Replace				0.00
2020	D40 FIRE PROTECTION						
	D4010 FIRE ALARM AND DETECTION SYSTEMS 1996 D401001 FIRE ALARM DISTRIBUTION Other -- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1996 D401001 FIRE ALARM DISTRIBUTION Other	111,107 (SF)	Replace				0.00

2020 D50 ELECTRICAL



Work Items by Building Report



Support Site

Cost Book: Reference

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	D5030 COMMUNICATIONS & SECURITY 1996 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets -- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets	1 (EA)	Replace				0.00
	D5030 COMMUNICATIONS & SECURITY 1996 D503003 INTERCOMMUNICATIONS SYSTEMS 50 stations -- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503003 INTERCOMMUNICATIONS SYSTEMS 50 stations	1 (EA)	Replace				0.00
	D5030 COMMUNICATIONS & SECURITY 1996 D503005 SECURITY SYSTEMS General -- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503005 SECURITY SYSTEMS General	1 (EA)	Replace				0.00
	D5030 COMMUNICATIONS & SECURITY 1996 D503007 CLOCK & PROGRAM SYSTEMS General -- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503007 CLOCK & PROGRAM SYSTEMS General	1 (EA)	Replace				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2059 - Naples MS/HS Bldg 2059

Unassigned

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
2015	B20 EXTERIOR ENCLOSURE						
	B2010 EXTERIOR WALLS	240 (LF)	Paint				0.00
	1996 B201006 BALCONY WALLS & HANDRAILS Handrailing						
	-- Paint B2010 EXTERIOR WALLS 1996 B201006 BALCONY WALLS & HANDRAILS Handrailing						
2015	B30 ROOFING						
	B3010 ROOF COVERINGS	20,000 (SF)	Replace				0.00
	1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen						
	-- Replace B3010 ROOF COVERINGS 1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen						
	B3010 ROOF COVERINGS	20,000 (SF)	Replace				0.00
	1996 B301003 ROOF INSULATION & FILL General						
	-- Replace B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL Unknown						
	B3010 ROOF COVERINGS	1,846 (LF)	Replace				0.00
	1996 B301004 FLASHINGS & TRIM Flashings - Base						
	-- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Base						
	B3010 ROOF COVERINGS	1,522 (LF)	Replace				0.00
	1996 B301004 FLASHINGS & TRIM Flashings - Cap						
	-- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Cap						
	B3010 ROOF COVERINGS	231 (EA)	Replace				0.00
	1996 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations						
	-- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations						
	B3010 ROOF COVERINGS	153 (LF)	Replace				0.00
	1996 B B301004 FLASHINGS & TRIM Flashings - Apron						
	-- Replace B3010 ROOF COVERINGS 1996b B301004 FLASHINGS & TRIM Flashings - Apron						
2015	C30 INTERIOR FINISHES						



Work Items by Building Report



Support Site

Cost Book: Reference

2059 - Naples MS/HS Bldg 2059

Unassigned

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	C3020 FLOOR FINISHES 1996 C302004 RESILIENT FLOOR FINISHES Composition Sheet -- Replace C3020 FLOOR FINISHES 1996 C302004 RESILIENT FLOOR FINISHES General	1,888 (SF)	Replace				0.00
2015	D20 PLUMBING						
	D2010 PLUMBING FIXTURES 1996 D201002 URINALS General -- Repair D2010 PLUMBING FIXTURES D201002 URINALS General	6 (EA)	Repair				0.00
	D2010 PLUMBING FIXTURES 1996 A D201001 WATERCLOSETS General -- Replace D2010 PLUMBING FIXTURES D201001 WATERCLOSETS General	23 (EA)	Replace				0.00
	D2030 SANITARY WASTE 1996 D203002 VENT PIPE & FITTINGS General -- Replace D2030 SANITARY WASTE D203002 VENT PIPE & FITTINGS General	201 (EA)	Replace				0.00
	D2040 RAIN WATER DRAINAGE 1996 D204002 ROOF DRAINS Other -- Replace D2040 RAIN WATER DRAINAGE 1996 3 inch D204002 ROOF DRAINS Other	26 (EA)	Replace				0.00
2015	D30 HVAC						
	D3040 DISTRIBUTION SYSTEMS 1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS D304003 HOT WATER DISTRIBUTION SYSTEMS General	250 (MBH)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	50 (TON)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-056 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS AHU-056 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM	1 (EA)	Replace				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2059 - Naples MS/HS Bldg 2059

Unassigned

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
	D3040 DISTRIBUTION SYSTEMS		1 (EA)	Replace				0.00
	1996 AHU-061 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM							
	-- Replace D3040 DISTRIBUTION SYSTEMS AHU-061 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM							
	D3040 DISTRIBUTION SYSTEMS		1 (EA)	Replace				0.00
	1996 AHU-062 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM							
	-- Replace D3040 DISTRIBUTION SYSTEMS AHU-062 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM							
2015	D40 FIRE PROTECTION							
	D4010 FIRE ALARM AND DETECTION SYSTEMS		20,258 (SF)	Replace				0.00
	1996 D401001 FIRE ALARM DISTRIBUTION Other							
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS D401001 FIRE ALARM DISTRIBUTION General							
2016	B20 EXTERIOR ENCLOSURE							
	B2010 EXTERIOR WALLS		240 (LF)	Paint				0.00
	1996 B201006 BALCONY WALLS & HANDRAILS Handrailing							
	-- Paint B2010 EXTERIOR WALLS 1996 B201006 BALCONY WALLS & HANDRAILS Handrailing							
2016	B30 ROOFING							
	B3010 ROOF COVERINGS		20,000 (SF)	Replace				0.00
	1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen							
	-- Replace B3010 ROOF COVERINGS 1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen							
	B3010 ROOF COVERINGS		20,000 (SF)	Replace				0.00
	1996 B301003 ROOF INSULATION & FILL General							
	-- Replace B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL Unknown							
	B3010 ROOF COVERINGS		1,846 (LF)	Replace				0.00
	1996 B301004 FLASHINGS & TRIM Flashings - Base							
	-- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Base							



Work Items by Building Report



Support Site

Cost Book: Reference

2059 - Naples MS/HS Bldg 2059

Unassigned

Year	System Component Section Description – Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	B3010 ROOF COVERINGS	1,522 (LF)	Replace				0.00
	1996 B301004 FLASHINGS & TRIM Flashings - Cap						
	– Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Cap						
	B3010 ROOF COVERINGS	231 (EA)	Replace				0.00
	1996 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations						
	– Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations						
	B3010 ROOF COVERINGS	153 (LF)	Replace				0.00
	1996 B B301004 FLASHINGS & TRIM Flashings - Apron						
	– Replace B3010 ROOF COVERINGS 1996b B301004 FLASHINGS & TRIM Flashings - Apron						
2016	C30 INTERIOR FINISHES						
	C3020 FLOOR FINISHES	1,888 (SF)	Replace				0.00
	1996 C302004 RESILIENT FLOOR FINISHES Composition Sheet						
	– Replace C3020 FLOOR FINISHES 1996 C302004 RESILIENT FLOOR FINISHES General						
2016	D20 PLUMBING						
	D2010 PLUMBING FIXTURES	23 (EA)	Replace				0.00
	1996 A D201001 WATERCLOSETS General						
	– Replace D2010 PLUMBING FIXTURES D201001 WATERCLOSETS General						
	D2030 SANITARY WASTE	201 (EA)	Replace				0.00
	1996 D203002 VENT PIPE & FITTINGS General						
	– Replace D2030 SANITARY WASTE D203002 VENT PIPE & FITTINGS General						
	D2040 RAIN WATER DRAINAGE	26 (EA)	Replace				0.00
	1996 D204002 ROOF DRAINS Other						
	– Replace D2040 RAIN WATER DRAINAGE 1996 3 inch D204002 ROOF DRAINS Other						
2016	D30 HVAC						



Work Items by Building Report



Support Site

Cost Book: Reference

2059 - Naples MS/HS Bldg 2059

Unassigned

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	D3040 DISTRIBUTION SYSTEMS 1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS D304003 HOT WATER DISTRIBUTION SYSTEMS General	250 (MBH)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	50 (TON)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-056 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS AHU-056 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-061 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS AHU-061 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-062 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS AHU-062 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM	1 (EA)	Replace				0.00
2016	D40 FIRE PROTECTION						
	D4010 FIRE ALARM AND DETECTION SYSTEMS 1996 D401001 FIRE ALARM DISTRIBUTION Other -- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS D401001 FIRE ALARM DISTRIBUTION General	20,258 (SF)	Replace				0.00
2017	B20 EXTERIOR ENCLOSURE						
	B2010 EXTERIOR WALLS 1996 B201001 EXTERIOR CLOSURE Stucco -- Paint B2010 EXTERIOR WALLS 1996 B201001 EXTERIOR CLOSURE Stucco	4,844 (SF)	Paint				0.00
	B2010 EXTERIOR WALLS 1996 B201007 EXTERIOR SOFFITS General -- Paint B2010 EXTERIOR WALLS 1996 B201007 EXTERIOR SOFFITS General	623 (SF)	Paint				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2059 - Naples MS/HS Bldg 2059

Unassigned

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	B2030 EXTERIOR DOORS	12 (EA)	Replace				0.00
	1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door						
	-- Replace B2030 EXTERIOR DOORS 1996 B203002 GLAZED DOORS General						
2017	B30 ROOFING						
	B3010 ROOF COVERINGS	20,000 (SF)	Replace				0.00
	1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen						
	-- Replace B3010 ROOF COVERINGS 1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen						
	B3010 ROOF COVERINGS	20,000 (SF)	Replace				0.00
	1996 B301003 ROOF INSULATION & FILL General						
	-- Replace B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL Unknown						
	B3010 ROOF COVERINGS	1,846 (LF)	Replace				0.00
	1996 B301004 FLASHINGS & TRIM Flashings - Base						
	-- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Base						
	B3010 ROOF COVERINGS	1,522 (LF)	Replace				0.00
	1996 B301004 FLASHINGS & TRIM Flashings - Cap						
	-- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Cap						
	B3010 ROOF COVERINGS	231 (EA)	Replace				0.00
	1996 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations						
	-- Replace B3010 ROOF COVERINGS 1996 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations						
	B3010 ROOF COVERINGS	214 (LF)	Paint				0.00
	1996 B301004 FLASHINGS & TRIM General						
	-- Paint B3010 ROOF COVERINGS 1996 Stucco Fascia B301004 FLASHINGS & TRIM Other						
	B3010 ROOF COVERINGS	304 (LF)	Paint				0.00
	1996 B301005 GUTTERS & DOWNSPOUTS Downspouts						
	-- Paint B3010 ROOF COVERINGS 1996 B301005 GUTTERS & DOWNSPOUTS Downspouts						



Work Items by Building Report



Support Site

Cost Book: Reference

2059 - Naples MS/HS Bldg 2059

Unassigned

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
		-- Description						
	B3010	ROOF COVERINGS	153 (LF)	Replace				0.00
	1996 B	B301004 FLASHINGS & TRIM Flashings - Apron						
		-- Replace B3010 ROOF COVERINGS 1996b B301004 FLASHINGS & TRIM Flashings - Apron						
2017	C10	INTERIOR CONSTRUCTION						
	C1010	PARTITIONS	22,781 (SF)	Paint				0.00
	1996 C101001	FIXED PARTITIONS Wall - Plaster w/Stud Framing						
		-- Paint C1010 PARTITIONS 1996 C101001 FIXED PARTITIONS General						
2017	C30	INTERIOR FINISHES						
	C3010	WALL FINISHES	22,781 (SF)	Paint				0.00
	1996 C301002	PLASTER WALL FINISHES General						
		-- Paint C3010 WALL FINISHES 1996 C301002 PLASTER WALL FINISHES General						
	C3020	FLOOR FINISHES	1,888 (SF)	Replace				0.00
	1996 C302004	RESILIENT FLOOR FINISHES Composition Sheet						
		-- Replace C3020 FLOOR FINISHES 1996 C302004 RESILIENT FLOOR FINISHES General						
	C3030	CEILING FINISHES	3,195 (SF)	Paint				0.00
	1996 C303003	PLASTER CEILING FINISHES General						
		-- Paint C3030 CEILING FINISHES 1996 C303003 PLASTER CEILING FINISHES General						
	C3030	CEILING FINISHES	13,802 (SF)	Replace				0.00
	1996 C303005	SUSPENSION SYSTEMS General						
		-- Replace C3030 CEILING FINISHES 1996 C303005 SUSPENSION SYSTEMS General						
2017	D20	PLUMBING						
	D2010	PLUMBING FIXTURES	23 (EA)	Replace				0.00
	1996 A	D201001 WATERCLOSETS General						
		-- Replace D2010 PLUMBING FIXTURES D201001 WATERCLOSETS General						



Work Items by Building Report



Support Site

Cost Book: Reference

2059 - Naples MS/HS Bldg 2059

Unassigned

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	D2030 SANITARY WASTE 1996 D203002 VENT PIPE & FITTINGS General -- Replace D2030 SANITARY WASTE D203002 VENT PIPE & FITTINGS General	201 (EA)	Replace				0.00
	D2040 RAIN WATER DRAINAGE 1996 D204002 ROOF DRAINS Other -- Replace D2040 RAIN WATER DRAINAGE 1996 3 inch D204002 ROOF DRAINS Other	26 (EA)	Replace				0.00
2017	D30 HVAC						
	D3040 DISTRIBUTION SYSTEMS 1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS D304003 HOT WATER DISTRIBUTION SYSTEMS General	250 (MBH)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	50 (TON)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-056 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS AHU-056 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-061 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS AHU-061 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-062 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS AHU-062 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM	1 (EA)	Replace				0.00
2017	D40 FIRE PROTECTION						
	D4010 FIRE ALARM AND DETECTION SYSTEMS 1996 D401001 FIRE ALARM DISTRIBUTION Other -- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS D401001 FIRE ALARM DISTRIBUTION General	20,258 (SF)	Replace				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2059 - Naples MS/HS Bldg 2059

Unassigned

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
2017	D50 ELECTRICAL						
	D5090 OTHER ELECTRICAL SERVICES	20,258 (SF)	Replace				0.00
	1996 D509002 EMERGENCY LIGHTING & POWER General						
	-- Replace D5090 OTHER ELECTRICAL SERVICES D509002 EMERGENCY LIGHTING & POWER General						
2018	B20 EXTERIOR ENCLOSURE						
	B2010 EXTERIOR WALLS	7,912 (SF)	Paint				0.00
	1996 B201001 EXTERIOR CLOSURE Stucco						
	-- Paint B2010 EXTERIOR WALLS 1996 B201001 EXTERIOR CLOSURE Stucco						
	B2030 EXTERIOR DOORS	12 (EA)	Replace				0.00
	1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door						
	-- Replace B2030 EXTERIOR DOORS 1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door						
2018	B30 ROOFING						
	B3010 ROOF COVERINGS	20,930 (SF)	Replace				0.00
	1996 B301003 ROOF INSULATION & FILL General						
	-- Replace B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL General						
2018	C10 INTERIOR CONSTRUCTION						
	C1010 PARTITIONS	32 (SF)	Replace				0.00
	1996 C101005 INTERIOR WINDOWS Metal Rollup / Coiling Grille						
	-- Replace C1010 PARTITIONS 1996 C101005 INTERIOR WINDOWS Metal Rollup / Coiling Grille						
2018	C20 STAIRS						
	C2010 STAIR CONSTRUCTION	90 (LF)	Paint				0.00
	1996 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
	-- Paint C2010 STAIR CONSTRUCTION 1996 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						



Work Items by Building Report



Support Site

Cost Book: Reference

2059 - Naples MS/HS Bldg 2059

Unassigned

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
2018	C30 INTERIOR FINISHES						
	C3010 WALL FINISHES	22,781 (SF)	Paint				0.00
	1996 C301002 PLASTER WALL FINISHES General						
	-- Paint C3010 WALL FINISHES 1996 C301002 PLASTER WALL FINISHES General						
	C3020 FLOOR FINISHES	1,888 (SF)	Replace				0.00
	1996 C302004 RESILIENT FLOOR FINISHES Composition Sheet						
	-- Replace C3020 FLOOR FINISHES 1996 C302004 RESILIENT FLOOR FINISHES Composition Sheet						
	C3030 CEILING FINISHES	13,802 (SF)	Replace				0.00
	1996 C303001 ACOUSTICAL CEILING TILES & PANELS General						
	-- Replace C3030 CEILING FINISHES 1996 C303001 ACOUSTICAL CEILING TILES & PANELS General						
	C3030 CEILING FINISHES	13,802 (SF)	Replace				0.00
	1996 C303005 SUSPENSION SYSTEMS General						
	-- Replace C3030 CEILING FINISHES 1996 C303005 SUSPENSION SYSTEMS General						
2018	D20 PLUMBING						
	D2030 SANITARY WASTE	743 (EA)	Replace				0.00
	1996 D203002 VENT PIPE & FITTINGS General						
	-- Replace D2030 SANITARY WASTE 1996 D203002 VENT PIPE & FITTINGS General						
	D2040 RAIN WATER DRAINAGE	390 (LF)	Replace				0.00
	1996 D204001 PIPE & FITTINGS General						
	-- Replace D2040 RAIN WATER DRAINAGE 1996 D204001 PIPE & FITTINGS General						
2018	D30 HVAC						
	D3040 DISTRIBUTION SYSTEMS	523 (MBH)	Replace				0.00
	1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General						



Work Items by Building Report



Support Site

Cost Book: Reference

2059 - Naples MS/HS Bldg 2059

Unassigned

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	D3040 DISTRIBUTION SYSTEMS 1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	52 (TON)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-056 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS 1996 B D304008 AIR HANDLING UNITS Rooftop - 10000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-061 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS 1996 A D304008 AIR HANDLING UNITS Rooftop - 10000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-062 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 ROOFTOP D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 800 CFM -- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 800 CFM	1 (EA)	Replace				0.00
2018	D40 FIRE PROTECTION						
	D4010 FIRE ALARM AND DETECTION SYSTEMS 1996 D401001 FIRE ALARM DISTRIBUTION Other -- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1996 D401001 FIRE ALARM DISTRIBUTION Other	20,930 (SF)	Replace				0.00
2018	D50 ELECTRICAL						
	D5010 ELECTRICAL SERVICE & DISTRIBUTION 1996 ROOM 138B D501004 PANELBOARDS Main lugs, 200 amp -- Repair D5010 ELECTRICAL SERVICE & DISTRIBUTION 1996 D501004 PANELBOARDS Main lugs, 200 amp	2 (EA)	Repair				0.00
	D5030 COMMUNICATIONS & SECURITY 1996 D503002 PUBLIC ADDRESS SYSTEMS 6 outlets -- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503002 PUBLIC ADDRESS SYSTEMS 6 outlets	1 (EA)	Replace				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2059 - Naples MS/HS Bldg 2059

Unassigned

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	D5030 COMMUNICATIONS & SECURITY 1996 D503003 INTERCOMMUNICATIONS SYSTEMS 6 stations -- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503003 INTERCOMMUNICATIONS SYSTEMS 6 stations	1 (EA)	Replace				0.00
	D5030 COMMUNICATIONS & SECURITY 1996 D503007 CLOCK & PROGRAM SYSTEMS General -- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503007 CLOCK & PROGRAM SYSTEMS General	1 (EA)	Replace				0.00
2019	B20 EXTERIOR ENCLOSURE						
	B2030 EXTERIOR DOORS 1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door -- Replace B2030 EXTERIOR DOORS 1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door	12 (EA)	Replace				0.00
2019	B30 ROOFING						
	B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL General -- Replace B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL General	20,930 (SF)	Replace				0.00
2019	C10 INTERIOR CONSTRUCTION						
	C1010 PARTITIONS 1996 C101005 INTERIOR WINDOWS Metal Rollup / Coiling Grille -- Replace C1010 PARTITIONS 1996 C101005 INTERIOR WINDOWS Metal Rollup / Coiling Grille	32 (SF)	Replace				0.00
2019	C30 INTERIOR FINISHES						
	C3020 FLOOR FINISHES 1996 C302004 RESILIENT FLOOR FINISHES Composition Sheet -- Replace C3020 FLOOR FINISHES 1996 C302004 RESILIENT FLOOR FINISHES Composition Sheet	1,888 (SF)	Replace				0.00
	C3030 CEILING FINISHES 1996 C303001 ACOUSTICAL CEILING TILES & PANELS General -- Replace C3030 CEILING FINISHES 1996 C303001 ACOUSTICAL CEILING TILES & PANELS General	13,802 (SF)	Replace				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2059 - Naples MS/HS Bldg 2059

Unassigned

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	C3030 CEILING FINISHES 1996 C303005 SUSPENSION SYSTEMS General -- Replace C3030 CEILING FINISHES 1996 C303005 SUSPENSION SYSTEMS General	13,802 (SF)	Replace				0.00
2019	D20 PLUMBING						
	D2030 SANITARY WASTE 1996 D203002 VENT PIPE & FITTINGS General -- Replace D2030 SANITARY WASTE 1996 D203002 VENT PIPE & FITTINGS General	743 (EA)	Replace				0.00
	D2040 RAIN WATER DRAINAGE 1996 D204001 PIPE & FITTINGS General -- Replace D2040 RAIN WATER DRAINAGE 1996 D204001 PIPE & FITTINGS General	390 (LF)	Replace				0.00
2019	D30 HVAC						
	D3040 DISTRIBUTION SYSTEMS 1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General	523 (MBH)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General -- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	52 (TON)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-056 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS 1996 B D304008 AIR HANDLING UNITS Rooftop - 10000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-061 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS 1996 A D304008 AIR HANDLING UNITS Rooftop - 10000 CFM	1 (EA)	Replace				0.00
	D3040 DISTRIBUTION SYSTEMS 1996 AHU-062 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM -- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM	1 (EA)	Replace				0.00



Work Items by Building Report



Support Site

Cost Book: Reference

2059 - Naples MS/HS Bldg 2059

Unassigned

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 ROOFTOP D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 800 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 800 CFM						
2019	D40 FIRE PROTECTION						
	D4010 FIRE ALARM AND DETECTION SYSTEMS	20,930 (SF)	Replace				0.00
	1996 D401001 FIRE ALARM DISTRIBUTION Other						
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1996 D401001 FIRE ALARM DISTRIBUTION Other						
2019	D50 ELECTRICAL						
	D5030 COMMUNICATIONS & SECURITY	1 (EA)	Replace				0.00
	1996 D503002 PUBLIC ADDRESS SYSTEMS 6 outlets						
	-- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503002 PUBLIC ADDRESS SYSTEMS 6 outlets						
	D5030 COMMUNICATIONS & SECURITY	1 (EA)	Replace				0.00
	1996 D503003 INTERCOMMUNICATIONS SYSTEMS 6 stations						
	-- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503003 INTERCOMMUNICATIONS SYSTEMS 6 stations						
	D5030 COMMUNICATIONS & SECURITY	1 (EA)	Replace				0.00
	1996 D503007 CLOCK & PROGRAM SYSTEMS General						
	-- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503007 CLOCK & PROGRAM SYSTEMS General						
2020	B20 EXTERIOR ENCLOSURE						
	B2030 EXTERIOR DOORS	12 (EA)	Replace				0.00
	1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door						
	-- Replace B2030 EXTERIOR DOORS 1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door						
2020	B30 ROOFING						
	B3010 ROOF COVERINGS	20,930 (SF)	Replace				0.00
	1996 B301003 ROOF INSULATION & FILL General						
	-- Replace B3010 ROOF COVERINGS 1996 B301003 ROOF INSULATION & FILL General						



Work Items by Building Report



Support Site

Cost Book: Reference

2059 - Naples MS/HS Bldg 2059

Unassigned

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
2020	C10 INTERIOR CONSTRUCTION						
	C1010 PARTITIONS	32 (SF)	Replace				0.00
	1996 C101005 INTERIOR WINDOWS Metal Rollup / Coiling Grille						
	-- Replace C1010 PARTITIONS 1996 C101005 INTERIOR WINDOWS Metal Rollup / Coiling Grille						
2020	C30 INTERIOR FINISHES						
	C3010 WALL FINISHES	22,781 (SF)	Paint				0.00
	1996 C301002 PLASTER WALL FINISHES General						
	-- Paint C3010 WALL FINISHES 1996 C301002 PLASTER WALL FINISHES General						
	C3020 FLOOR FINISHES	1,900 (SF)	Replace				0.00
	1996 C302004 RESILIENT FLOOR FINISHES Composition Sheet						
	-- Replace C3020 FLOOR FINISHES 1996 C302004 RESILIENT FLOOR FINISHES Composition Sheet						
	C3030 CEILING FINISHES	13,802 (SF)	Replace				0.00
	1996 C303001 ACOUSTICAL CEILING TILES & PANELS General						
	-- Replace C3030 CEILING FINISHES 1996 C303001 ACOUSTICAL CEILING TILES & PANELS General						
	C3030 CEILING FINISHES	13,802 (SF)	Replace				0.00
	1996 C303005 SUSPENSION SYSTEMS General						
	-- Replace C3030 CEILING FINISHES 1996 C303005 SUSPENSION SYSTEMS General						
2020	D20 PLUMBING						
	D2030 SANITARY WASTE	743 (EA)	Replace				0.00
	1996 D203002 VENT PIPE & FITTINGS General						
	-- Replace D2030 SANITARY WASTE 1996 D203002 VENT PIPE & FITTINGS General						
	D2040 RAIN WATER DRAINAGE	390 (LF)	Replace				0.00
	1996 D204001 PIPE & FITTINGS General						
	-- Replace D2040 RAIN WATER DRAINAGE 1996 D204001 PIPE & FITTINGS General						
2020	D30 HVAC						



Work Items by Building Report



Support Site

Cost Book: Reference

2059 - Naples MS/HS Bldg 2059

Unassigned

Year	System Component	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	Section Description						
	-- Description						
	D3040 DISTRIBUTION SYSTEMS	523 (MBH)	Replace				0.00
	1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	D3040 DISTRIBUTION SYSTEMS	52 (TON)	Replace				0.00
	1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 AHU-056 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 AHU-056 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 AHU-061 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 AHU-061 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 AHU-062 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 AHU-062 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1996 ROOFTOP D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 800 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1996 ROOFTOP D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 800 CFM						
2020	D40 FIRE PROTECTION						
	D4010 FIRE ALARM AND DETECTION SYSTEMS	20,930 (SF)	Replace				0.00
	1996 D401001 FIRE ALARM DISTRIBUTION Other						
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1996 D401001 FIRE ALARM DISTRIBUTION Other						
2020	D50 ELECTRICAL						
	D5030 COMMUNICATIONS & SECURITY	1 (EA)	Replace				0.00
	1996 D503002 PUBLIC ADDRESS SYSTEMS 6 outlets						
	-- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503002 PUBLIC ADDRESS SYSTEMS 6 outlets						



"identification only"

Work Items by Building Report



Support Site

Cost Book: Reference

2059 - Naples MS/HS Bldg 2059

Unassigned

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
	D5030 COMMUNICATIONS & SECURITY 1996 D503003 INTERCOMMUNICATIONS SYSTEMS 6 stations -- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503003 INTERCOMMUNICATIONS SYSTEMS 6 stations	1 (EA)	Replace				0.00
	D5030 COMMUNICATIONS & SECURITY 1996 D503007 CLOCK & PROGRAM SYSTEMS General -- Replace D5030 COMMUNICATIONS & SECURITY 1996 D503007 CLOCK & PROGRAM SYSTEMS General	1 (EA)	Replace				0.00

Appendix F

"identification only"

Remaining Service Life (RSL) Detail Report



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1996 B201001 EXTERIOR CLOSURE Brick Veneer w/CMU Backup	24	31	
	B2010 EXTERIOR WALLS	1996 B201001 EXTERIOR CLOSURE Stucco	24	12	4
	B2010 EXTERIOR WALLS	1996 B201004 PARAPETS General	4	8	
	B2010 EXTERIOR WALLS	1996 B201006 BALCONY WALLS & HANDRAILS Handrailing	24	4	4
	B2010 EXTERIOR WALLS	1996 B201007 EXTERIOR SOFFITS General	24	6	
	B2010 EXTERIOR WALLS	1996 A B201001 EXTERIOR CLOSURE Stone Veneer w/CMU Backup	24	31	8
	B2010 EXTERIOR WALLS	1996 A B201010 EXTERIOR JOINT SEALANT General	24	8	
	B2010 EXTERIOR WALLS	1996 B B201001 EXTERIOR CLOSURE Stone Veneer w/CMU Backup	24	31	
	B2010 EXTERIOR WALLS	1996 B B201010 EXTERIOR JOINT SEALANT General	24	6	
	B2010 EXTERIOR WALLS	2004 B201001 EXTERIOR CLOSURE Brick Veneer w/CMU Backup	16	31	
	B2010 EXTERIOR WALLS	2004 B201001 EXTERIOR CLOSURE Stone Veneer w/CMU Backup	16	39	
	B2010 EXTERIOR WALLS	2004 B201001 EXTERIOR CLOSURE Stucco	16	16	4
	B2010 EXTERIOR WALLS	2004 B201006 BALCONY WALLS & HANDRAILS Handrailing	16	4	4
	B2010 EXTERIOR WALLS	2004 B201007 EXTERIOR SOFFITS General	16	8	3
	B2010 EXTERIOR WALLS	2004 B201010 EXTERIOR JOINT SEALANT General	24	8	
	B2010 EXTERIOR WALLS	2004 A B201004 PARAPETS General	4	10	
	B2010 EXTERIOR WALLS	2004 B B201004 PARAPETS General	4	10	
	B2010 EXTERIOR WALLS	2013 B201001 EXTERIOR CLOSURE Stone Veneer w/CMU Backup	7	39	
	B2010 EXTERIOR WALLS	2013 B201001 EXTERIOR CLOSURE Stucco	7	21	5
	B2010 EXTERIOR WALLS	2013 B201005 EXTERIOR LOUVERS & SCREENS General	7	10	4
	B2010 EXTERIOR WALLS	2013 B201006 BALCONY WALLS & HANDRAILS Handrailing	7	6	4
	B2010 EXTERIOR WALLS	2013 B201007 EXTERIOR SOFFITS General	24	10	3
	B2010 EXTERIOR WALLS	2013 B201010 EXTERIOR JOINT SEALANT General	7	10	
	B2010 EXTERIOR WALLS	2013 A B201004 PARAPETS General	7	8	
	B2020 EXTERIOR WINDOWS	1996 A B202001 WINDOWS Steel Windows	24	20	
	B2020 EXTERIOR WINDOWS	1996 B B202001 WINDOWS Steel Windows	24	20	
	B2020 EXTERIOR WINDOWS	2004 B202001 WINDOWS Steel Windows	16	20	
	B2020 EXTERIOR WINDOWS	2013 B202001 WINDOWS Steel Windows	7	20	
	B2030 EXTERIOR DOORS	1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress	24	0	
	B2030 EXTERIOR DOORS	2004 B203001 SOLID DOORS Steel	16	6	
	B2030 EXTERIOR DOORS	2004 B203002 GLAZED DOORS General	16	12	
	B2030 EXTERIOR DOORS	2004 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress	16	4	



Remaining Service Life (RSL) Detail Report



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	B2030 EXTERIOR DOORS	2013 B203001 SOLID DOORS Steel	7	8	
	B2030 EXTERIOR DOORS	2013 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress	7	8	
B30 ROOFING	B3010 ROOF COVERINGS	1996 B301001 STEEP SLOPE ROOF SYSTEMS Clay Tile	24	29	
	B3010 ROOF COVERINGS	1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	4	10	
	B3010 ROOF COVERINGS	1996 B301003 ROOF INSULATION & FILL General	24	0	
	B3010 ROOF COVERINGS	1996 B301004 FLASHINGS & TRIM Flashings - Base	4	13	
	B3010 ROOF COVERINGS	1996 B301004 FLASHINGS & TRIM Flashings - Cap	4	10	
	B3010 ROOF COVERINGS	1996 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	4	13	
	B3010 ROOF COVERINGS	1996 B301005 GUTTERS & DOWNSPOUTS Downspouts	24	8	
	B3010 ROOF COVERINGS	1996 B301006 ROOF OPENINGS AND SUPPORTS Skylights	24	0	
	B3010 ROOF COVERINGS	1996 B301090 OTHER ROOFING Walkway Protection	4	4	
	B3010 ROOF COVERINGS	1996 A B301004 FLASHINGS & TRIM Flashings - Apron	4	13	
	B3010 ROOF COVERINGS	1996 A B301004 FLASHINGS & TRIM General	4	13	
	B3010 ROOF COVERINGS	1996 B B301004 FLASHINGS & TRIM Flashings - Apron	24	13	
	B3010 ROOF COVERINGS	1996 B B301004 FLASHINGS & TRIM General	24	7	4
	B3010 ROOF COVERINGS	2004 B301003 ROOF INSULATION & FILL General	16	4	
	B3010 ROOF COVERINGS	2004 B301004 FLASHINGS & TRIM Flashings - Cap	16	10	
	B3010 ROOF COVERINGS	2004 B301004 FLASHINGS & TRIM General	16	7	4
	B3010 ROOF COVERINGS	2004 B301005 GUTTERS & DOWNSPOUTS Downspouts	16	8	4
	B3010 ROOF COVERINGS	2004 B301005 GUTTERS & DOWNSPOUTS Gutters	24	8	
	B3010 ROOF COVERINGS	2004 B301006 ROOF OPENINGS AND SUPPORTS Skylights	16	31	
	B3010 ROOF COVERINGS	2004 B301090 OTHER ROOFING Walkway Protection	16	4	
	B3010 ROOF COVERINGS	2004 A B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	16	8	
	B3010 ROOF COVERINGS	2004 A B301004 FLASHINGS & TRIM Flashings - Base	16	10	
	B3010 ROOF COVERINGS	2004 A B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	16	10	
	B3010 ROOF COVERINGS	2004 B B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	16	8	
	B3010 ROOF COVERINGS	2004 B B301004 FLASHINGS & TRIM Flashings - Base	16	10	
	B3010 ROOF COVERINGS	2004 B B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	16	10	
	B3010 ROOF COVERINGS	2013 B301001 STEEP SLOPE ROOF SYSTEMS Clay Tile	7	37	
	B3010 ROOF COVERINGS	2013 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	7	8	
	B3010 ROOF COVERINGS	2013 B301003 ROOF INSULATION & FILL General	7	13	
	B3010 ROOF COVERINGS	2013 B301004 FLASHINGS & TRIM Flashings - Base	7	10	



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	B3010 ROOF COVERINGS	2013 B301004 FLASHINGS & TRIM Flashings - Cap	7	10	
	B3010 ROOF COVERINGS	2013 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	7	10	
	B3010 ROOF COVERINGS	2013 B301005 GUTTERS & DOWNSPOUTS Downspouts	7	8	
	B3010 ROOF COVERINGS	2013 A B301004 FLASHINGS & TRIM General	7	10	
	B3010 ROOF COVERINGS	2013 B B301004 FLASHINGS & TRIM General	7	10	5
C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	1996 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing	24	65	21
	C1010 PARTITIONS	1996 C101005 INTERIOR WINDOWS Interior Windows	24	26	
	C1010 PARTITIONS	2004 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing	16	65	0
	C1010 PARTITIONS	2013 C101001 FIXED PARTITIONS Wall - Drywall w/Stud Framing	7	26	29
	C1010 PARTITIONS	2013 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing	24	65	Unknown
	C1020 INTERIOR DOORS	1996 C102001 STANDARD INTERIOR DOORS Metal Door	24	20	
	C1020 INTERIOR DOORS	1996 C102003 FIRE DOORS Fire Door - Swinging	24	16	
	C1020 INTERIOR DOORS	1996 C102006 INTERIOR GATES General	24	10	
	C1020 INTERIOR DOORS	2004 C102001 STANDARD INTERIOR DOORS Metal Door	16	20	
	C1020 INTERIOR DOORS	2004 C102002 GLAZED INTERIOR DOORS General	24	16	
	C1020 INTERIOR DOORS	2004 C102003 FIRE DOORS Fire Door - Swinging	16	16	
	C1020 INTERIOR DOORS	2013 C102001 STANDARD INTERIOR DOORS Metal Door	7	26	
	C1020 INTERIOR DOORS	2013 C102003 FIRE DOORS Fire Door - Swinging	7	21	
	C1030 SPECIALTIES	1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet	24	8	
	C1030 SPECIALTIES	1996 C103002 TOILET & BATH ACCESSORIES General	24	6	
	C1030 SPECIALTIES	1996 C103003 MARKER BOARDS & TACK BOARDS General	24	6	
	C1030 SPECIALTIES	1996 C103005 LOCKERS General	2	20	
	C1030 SPECIALTIES	1996 C103006 SHELIVING General	24	26	
	C1030 SPECIALTIES	1996 C103008 COUNTERS Laminated Plastic	24	0	
	C1030 SPECIALTIES	1996 C103009 CABINETS Other	24	4	
	C1030 SPECIALTIES	1996 C103010 CASEWORK General	2	13	
	C1030 SPECIALTIES	1996 A C103008 COUNTERS Laminated Plastic	2	20	
	C1030 SPECIALTIES	1996 A C103009 CABINETS Other	2	13	
	C1030 SPECIALTIES	2004 C103002 TOILET & BATH ACCESSORIES General	16	10	
	C1030 SPECIALTIES	2004 C103003 MARKER BOARDS & TACK BOARDS General	16	10	
	C1030 SPECIALTIES	2004 C103005 LOCKERS General	16	15	
	C1030 SPECIALTIES	2004 C103008 COUNTERS Wood	16	12	



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	C1030 SPECIALTIES	2004 C103009 CABINETS Other	16	8	
	C1030 SPECIALTIES	2004 C103010 CASEWORK General	16	8	
	C1030 SPECIALTIES	2013 C103002 TOILET & BATH ACCESSORIES General	7	8	
	C1030 SPECIALTIES	2013 C103003 MARKER BOARDS & TACK BOARDS General	7	8	
	C1030 SPECIALTIES	2013 C103008 COUNTERS Wood	7	15	
	C1030 SPECIALTIES	2013 C103009 CABINETS Other	7	10	
	C1030 SPECIALTIES	2013 C103010 CASEWORK General	7	10	
C20 STAIRS	C2010 STAIR CONSTRUCTION	1996 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Concrete	24	39	
	C2010 STAIR CONSTRUCTION	1996 C201001 INTERIOR AND EXTERIOR STAIRS Interior Stairs	24	41	
	C2010 STAIR CONSTRUCTION	1996 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES	24	8	3
	C2010 STAIR CONSTRUCTION	2004 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Concrete	16	51	
	C2010 STAIR CONSTRUCTION	2004 C201001 INTERIOR AND EXTERIOR STAIRS Interior Stairs	16	52	
	C2010 STAIR CONSTRUCTION	2004 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES	16	10	3
	C2010 STAIR CONSTRUCTION	2013 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Concrete	7	51	
	C2010 STAIR CONSTRUCTION	2013 C201001 INTERIOR AND EXTERIOR STAIRS Interior Stairs	7	52	
	C2010 STAIR CONSTRUCTION	2013 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES	7	10	4
C30 INTERIOR FINISHES	C3010 WALL FINISHES	1996 C301004 TILE & TERRAZZO WALL FINISHES General	24	31	
	C3010 WALL FINISHES	2004 C301004 TILE & TERRAZZO WALL FINISHES General	16	39	
	C3010 WALL FINISHES	2013 C301004 TILE & TERRAZZO WALL FINISHES General	7	39	
	C3020 FLOOR FINISHES	1996 C302001 TILE FLOOR FINISHES Ceramic Tile	15	39	
	C3020 FLOOR FINISHES	1996 C302005 CARPETING General	24	0	
	C3020 FLOOR FINISHES	1999 C302001 TILE FLOOR FINISHES Marble Tile	15	39	
	C3020 FLOOR FINISHES	1999 C302004 RESILIENT FLOOR FINISHES Rubber Sheet	2	26	
	C3020 FLOOR FINISHES	2004 C302001 TILE FLOOR FINISHES Ceramic Tile	16	39	
	C3020 FLOOR FINISHES	2013 C302001 TILE FLOOR FINISHES Ceramic Tile	7	39	
	C3020 FLOOR FINISHES	2013 C302004 RESILIENT FLOOR FINISHES Composition Sheet	7	9	
	C3030 CEILING FINISHES	1996 C303001 ACOUSTICAL CEILING TILES & PANELS General	24	0	
	C3030 CEILING FINISHES	1996 C303005 SUSPENSION SYSTEMS General	24	0	
	C3030 CEILING FINISHES	1996 C303006 METAL STRIP CEILINGS General	24	0	
	C3030 CEILING FINISHES	2004 C303001 ACOUSTICAL CEILING TILES & PANELS General	16	21	
	C3030 CEILING FINISHES	2004 C303005 SUSPENSION SYSTEMS General	16	6	



Remaining Service Life (RSL) Detail Report



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	C3030 CEILING FINISHES	2013 C303001 ACOUSTICAL CEILING TILES & PANELS General	7	37	Unknown
	C3030 CEILING FINISHES	2013 C303002 GYPSUM WALLBOARD CEILING FINISHES General	7	65	
	C3030 CEILING FINISHES	2013 C303005 SUSPENSION SYSTEMS General	7	10	
D10 CONVEYING	D1010 ELEVATORS AND LIFTS	1996 LE101 D101002 PASSENGER ELEVATORS Hydraulic Elevators - 1500 b,	24	7	
	D1010 ELEVATORS AND LIFTS	2004 D101004 WHEELCHAIR LIFT General	9	10	
	D1010 ELEVATORS AND LIFTS	2013 D101002 PASSENGER ELEVATORS Hydraulic Elevators - 1500 lb, 2 floors	7	13	
D20 PLUMBING	D2010 PLUMBING FIXTURES	1996 D201002 URINALS General	2	13	
	D2010 PLUMBING FIXTURES	1996 D201004 SINKS Service Sink	24	4	
	D2010 PLUMBING FIXTURES	1996 D201004 SINKS Stainless	24	6	
	D2010 PLUMBING FIXTURES	1996 D201005 SHOWERS/TUBS Shower	24	4	
	D2010 PLUMBING FIXTURES	1996 D201006 DRINKING FOUNTAINS AND COOLERS Drinking Fountain	24	2	
	D2010 PLUMBING FIXTURES	1996 A D201001 WATERCLOSETS General	24	4	
	D2010 PLUMBING FIXTURES	1996 A D201004 SINKS General	24	2	
	D2010 PLUMBING FIXTURES	1996 B D201001 WATERCLOSETS General	2	13	
	D2010 PLUMBING FIXTURES	1996 B D201004 SINKS General	1	13	
	D2010 PLUMBING FIXTURES	2004 D201001 WATERCLOSETS General	16	6	
	D2010 PLUMBING FIXTURES	2004 D201004 SINKS General	16	6	
	D2010 PLUMBING FIXTURES	2004 D201004 SINKS Stainless	16	6	
	D2010 PLUMBING FIXTURES	2004 D201006 DRINKING FOUNTAINS AND COOLERS Drinking Fountain	16	6	
	D2010 PLUMBING FIXTURES	2013 D201001 WATERCLOSETS General	7	10	
	D2010 PLUMBING FIXTURES	2013 D201004 SINKS General	7	10	
	D2010 PLUMBING FIXTURES	2013 D201004 SINKS Stainless	7	10	
	D2010 PLUMBING FIXTURES	2013 D201005 SHOWERS/TUBS Shower	7	10	
	D2010 PLUMBING FIXTURES	2013 D201006 DRINKING FOUNTAINS AND COOLERS Drinking Fountain	7	10	
	D2020 DOMESTIC WATER	1996 D202001 PIPES & FITTINGS General	24	26	
	D2020 DOMESTIC WATER	2004 D202001 PIPES & FITTINGS General	16	34	
	D2020 DOMESTIC WATER	2013 D202001 PIPES & FITTINGS General	7	43	
	D2020 DOMESTIC WATER	2013 D202003 DOMESTIC WATER EQUIPMENT Booster Pump - 1 HP	7	6	
	D2020 DOMESTIC WATER	2013 ROOM MECH 5 D202003 DOMESTIC WATER EQUIPMENT Booster Pump	7	13	
	D2020 DOMESTIC WATER	2013 ROOM MECH 5 D202003 DOMESTIC WATER EQUIPMENT Storage Tank	7	12	
	D2030 SANITARY WASTE	1996 D203001 WASTE PIPE & FITTINGS General	24	26	



Remaining Service Life (RSL) Detail Report



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	D2030 SANITARY WASTE	1996 D203002 VENT PIPE & FITTINGS General	24	0	
	D2030 SANITARY WASTE	1996 D203003 FLOOR DRAINS General	24	6	
	D2030 SANITARY WASTE	2004 D203001 WASTE PIPE & FITTINGS General	16	34	
	D2030 SANITARY WASTE	2004 D203002 VENT PIPE & FITTINGS General	16	4	
	D2030 SANITARY WASTE	2013 D203001 WASTE PIPE & FITTINGS General	7	43	
	D2030 SANITARY WASTE	2013 D203002 VENT PIPE & FITTINGS General	7	13	
	D2040 RAIN WATER DRAINAGE	1996 D204001 PIPE & FITTINGS General	24	0	
	D2040 RAIN WATER DRAINAGE	1996 D204002 ROOF DRAINS Other	24	0	
	D2040 RAIN WATER DRAINAGE	2004 D204001 PIPE & FITTINGS General	24	0	
	D2040 RAIN WATER DRAINAGE	2004 D204002 ROOF DRAINS Other	16	8	
	D2040 RAIN WATER DRAINAGE	2013 D204001 PIPE & FITTINGS General	7	13	
	D2040 RAIN WATER DRAINAGE	2013 D204002 ROOF DRAINS Other	7	10	
D30 HVAC	D3020 HEAT GENERATING SYSTEMS	2013 D302004 AUXILIARY EQUIPMENT Expansion Tank - 15 gal	7	15	
	D3030 COOLING GENERATING SYSTEMS	2004 CH-435 D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air	16	0	
	D3030 COOLING GENERATING SYSTEMS	2013 CHILLER 788 D303001 CHILLED WATER SYSTEMS Chiller,	7	0	
	D3040 DISTRIBUTION SYSTEMS	1996 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	24	16	
	D3040 DISTRIBUTION SYSTEMS	1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General	24	0	
	D3040 DISTRIBUTION SYSTEMS	1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	24	0	
	D3040 DISTRIBUTION SYSTEMS	1996 AHU-055 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	24	0	
	D3040 DISTRIBUTION SYSTEMS	1996 AHU-061 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	24	0	
	D3040 DISTRIBUTION SYSTEMS	1996 AHU-1 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	24	0	
	D3040 DISTRIBUTION SYSTEMS	1996 AHU-2 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	24	0	
	D3040 DISTRIBUTION SYSTEMS	1996 AHU-3 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM	24	0	
	D3040 DISTRIBUTION SYSTEMS	1996 AHU-4 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	24	0	
	D3040 DISTRIBUTION SYSTEMS	1996 ROOFTOP D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust -	24	0	
	D3040 DISTRIBUTION SYSTEMS	2004 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	16	24	
	D3040 DISTRIBUTION SYSTEMS	2004 D304003 HOT WATER DISTRIBUTION SYSTEMS General	16	4	
	D3040 DISTRIBUTION SYSTEMS	2004 EF-190 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 1500	16	3	
	D3040 DISTRIBUTION SYSTEMS	2013 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	7	33	
	D3040 DISTRIBUTION SYSTEMS	2013 D304003 HOT WATER DISTRIBUTION SYSTEMS General	24	0	
	D3040 DISTRIBUTION SYSTEMS	2013 D304003 HOT WATER DISTRIBUTION SYSTEMS Heat Exchanger, Plate	7	10	
	D3040 DISTRIBUTION SYSTEMS	2013 AHU-292 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	7	0	



Remaining Service Life (RSL) Detail Report



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	D3050 TERMINAL & PACKAGE UNITS	1996 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton	24	3	
	D3050 TERMINAL & PACKAGE UNITS	1996 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 2 ton	24	4	
	D3050 TERMINAL & PACKAGE UNITS	1996 A D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton	24	1	
	D3050 TERMINAL & PACKAGE UNITS	1996 A D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged	15	4	
	D3050 TERMINAL & PACKAGE UNITS	1996 B D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged	10	6	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 119A D305006 PACKAGE UNITS A/C Unit, Package Terminal -	15	8	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 132 D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air	4	8	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 132 A D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air	3	10	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 134 D305002 UNIT HEATERS Hydronic - 20 MBH	24	9	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 134 D305006 PACKAGE UNITS A/C Unit, Package Terminal -	15	4	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 134 B D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air	2	13	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 203 D305006 PACKAGE UNITS A/C Unit, Package Terminal -	15	6	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 203 D305006 PACKAGE UNITS A/C Unit, Package Terminal -	24	4	
	D3050 TERMINAL & PACKAGE UNITS	1996 S103.2 D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air Cooled	15	6	
	D3050 TERMINAL & PACKAGE UNITS	2004 D305003 FAN COIL UNITS Duct Mount, 2 Pipe - 1 ton	16	4	
	D3050 TERMINAL & PACKAGE UNITS	2004 D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged	16	8	
	D3050 TERMINAL & PACKAGE UNITS	2013 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton	7	8	
	D3050 TERMINAL & PACKAGE UNITS	2013 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 2 ton	7	4	
	D3050 TERMINAL & PACKAGE UNITS	2013 D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged	7	10	
	D3060 CONTROLS & DISTRIBUTION	1996 D306002 ELECTRONIC CONTROLS General	24	0	
	D3060 CONTROLS & DISTRIBUTION	2004 D306002 ELECTRONIC CONTROLS General	24	3	
	D3060 CONTROLS & DISTRIBUTION	2013 D306002 ELECTRONIC CONTROLS General	7	4	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION	1996 D401001 FIRE ALARM DISTRIBUTION Other	24	0	
	D4010 FIRE ALARM AND DETECTION	2004 D401001 FIRE ALARM DISTRIBUTION Other	16	4	
	D4010 FIRE ALARM AND DETECTION	2013 D401001 FIRE ALARM DISTRIBUTION Other	7	13	
	D4040 SPRINKLERS	1996 D404001 SPRINKLERS AND RELEASING DEVICES Wet Pipe Systems	24	51	
	D4040 SPRINKLERS	2004 D404001 SPRINKLERS AND RELEASING DEVICES Wet Pipe Systems	16	59	
	D4040 SPRINKLERS	2013 D404001 SPRINKLERS AND RELEASING DEVICES Wet Pipe Systems	24	51	
D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 D501003 INTERIOR DISTRIBUTION TRANSFORMERS dry-type, 480 V	24	15	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 D501003 INTERIOR DISTRIBUTION TRANSFORMERS dry-type, 480 V	24	5	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 D501004 PANELBOARDS Main lugs, 50 amp	24	6	



Remaining Service Life (RSL) Detail Report



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp, NQOD	24	6	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 D501004 PANELBOARDS Main lugs, 125 amp	24	6	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 D501004 PANELBOARDS Safety Switch, 30-100 Amp	24	9	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 ROOM 104 D501002 SERVICE ENTRANCE EQUIPMENT Electrical	24	6	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 ROOM 104 D501002 SERVICE ENTRANCE EQUIPMENT Electrical	24	6	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 ROOM 104 D501004 PANELBOARDS Main lugs, 277/480 V, 100 amp,	24	9	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 ROOM 117 D501002 SERVICE ENTRANCE EQUIPMENT Electrical	24	6	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 ROOM 117 D501004 PANELBOARDS Main lugs, 200 amp	24	6	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 ROOM 141 D501004 PANELBOARDS Main lugs, 200 amp	16	6	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 ROOM 202 D501004 PANELBOARDS Main lugs, 120/240 V, 225 amp,	24	9	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 ROOM 202 D501004 PANELBOARDS Switchgear - 400 Amp	23	15	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2004 ROOM 145 D501004 PANELBOARDS Main lugs, 120/240 V, 225 amp,	16	3	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2013 D501002 SERVICE ENTRANCE EQUIPMENT Electrical Service - 3 Phase,	7	10	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2013 ROOM 18 D501003 INTERIOR DISTRIBUTION TRANSFORMERS dry-	7	26	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2013 ROOM 18 D501004 PANELBOARDS Main lugs, 120/240 V, 225 amp,	7	15	
	D5020 LIGHTING & BRANCH WIRING	1996 D502001 BRANCH WIRING General	24	36	
	D5020 LIGHTING & BRANCH WIRING	1996 D502002 LIGHTING EQUIPMENT Exit Lighting	24	8	
	D5020 LIGHTING & BRANCH WIRING	1996 D502002 LIGHTING EQUIPMENT General	24	4	
	D5020 LIGHTING & BRANCH WIRING	1996 A D502002 LIGHTING EQUIPMENT Exterior Lighting	24	6	
	D5020 LIGHTING & BRANCH WIRING	1996 B D502002 LIGHTING EQUIPMENT Exterior Lighting	24	8	
	D5020 LIGHTING & BRANCH WIRING	2004 D502001 BRANCH WIRING General	16	44	
	D5020 LIGHTING & BRANCH WIRING	2004 D502002 LIGHTING EQUIPMENT Exit Lighting	24	8	
	D5020 LIGHTING & BRANCH WIRING	2004 D502002 LIGHTING EQUIPMENT Exterior Lighting	24	6	
	D5020 LIGHTING & BRANCH WIRING	2004 D502002 LIGHTING EQUIPMENT General	16	6	
	D5020 LIGHTING & BRANCH WIRING	2013 D502001 BRANCH WIRING General	7	53	
	D5020 LIGHTING & BRANCH WIRING	2013 D502002 LIGHTING EQUIPMENT Exit Lighting	24	10	
	D5020 LIGHTING & BRANCH WIRING	2013 D502002 LIGHTING EQUIPMENT Exterior Lighting	7	10	
	D5020 LIGHTING & BRANCH WIRING	2013 D502002 LIGHTING EQUIPMENT General	7	10	
	D5030 COMMUNICATIONS & SECURITY	1996 D503001 TELECOMMUNICATIONS SYSTEMS General	24	0	
	D5030 COMMUNICATIONS & SECURITY	1996 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets	24	0	
	D5030 COMMUNICATIONS & SECURITY	1996 D503003 INTERCOMMUNICATIONS SYSTEMS 100 stations	24	0	
	D5030 COMMUNICATIONS & SECURITY	1996 D503005 SECURITY SYSTEMS General	24	6	



Remaining Service Life (RSL) Detail Report



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	D5030 COMMUNICATIONS & 2501 10000	1996 D503007 CLOCK & PROGRAM SYSTEMS General	24	8	
	D5030 COMMUNICATIONS & 2501 10000	2004 D503002 PUBLIC ADDRESS SYSTEMS 6 outlets	16	6	
	D5030 COMMUNICATIONS & 2501 10000	2004 D503003 INTERCOMMUNICATIONS SYSTEMS 6 stations	16	4	
	D5030 COMMUNICATIONS & 2501 10000	2013 D503002 PUBLIC ADDRESS SYSTEMS 6 outlets	7	10	
	D5030 COMMUNICATIONS & 2501 10000	2013 D503003 INTERCOMMUNICATIONS SYSTEMS 6 stations	7	8	
	D5090 OTHER ELECTRICAL 2501 10000	1996 D509002 EMERGENCY LIGHTING & POWER General	24	2	
	D5090 OTHER ELECTRICAL 2501 10000	1996 D509002 EMERGENCY LIGHTING & POWER Uninterruptible Power	24	2	
	D5090 OTHER ELECTRICAL 2501 10000	1996 D509003 GROUNDING SYSTEMS General	24	26	
	D5090 OTHER ELECTRICAL 2501 10000	2004 D509002 EMERGENCY LIGHTING & POWER General	16	6	
	D5090 OTHER ELECTRICAL 2501 10000	2004 D509002 EMERGENCY LIGHTING & POWER Uninterruptible Power	16	10	
	D5090 OTHER ELECTRICAL 2501 10000	2004 D509003 GROUNDING SYSTEMS General	24	26	
	D5090 OTHER ELECTRICAL 2501 10000	2013 D509002 EMERGENCY LIGHTING & POWER General	7	8	
	D5090 OTHER ELECTRICAL 2501 10000	2013 D509003 GROUNDING SYSTEMS General	24	26	



Remaining Service Life (RSL) Detail Report



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1996 B201001 EXTERIOR CLOSURE Brick Veneer w/CMU Backup	24	39	
	B2010 EXTERIOR WALLS	1996 B201001 EXTERIOR CLOSURE Stone Veneer w/CMU Backup	24	39	
	B2010 EXTERIOR WALLS	1996 B201001 EXTERIOR CLOSURE Stucco	24	12	4
	B2010 EXTERIOR WALLS	1996 B201004 PARAPETS General	4	8	
	B2010 EXTERIOR WALLS	1996 B201007 EXTERIOR SOFFITS General	24	8	3
	B2010 EXTERIOR WALLS	1996 A B201010 EXTERIOR JOINT SEALANT General	24	2	
	B2010 EXTERIOR WALLS	1996 B B201010 EXTERIOR JOINT SEALANT General	24	2	
	B2010 EXTERIOR WALLS	1996 C B201010 EXTERIOR JOINT SEALANT General	24	2	
	B2020 EXTERIOR WINDOWS	1996 B202001 WINDOWS Aluminum Windows	24	15	
	B2030 EXTERIOR DOORS	1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress	24	0	
B30 ROOFING	B3010 ROOF COVERINGS	1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	4	8	
	B3010 ROOF COVERINGS	1996 B301003 ROOF INSULATION & FILL General	24	0	
	B3010 ROOF COVERINGS	1996 B301004 FLASHINGS & TRIM Flashings - Apron	4	10	
	B3010 ROOF COVERINGS	1996 B301004 FLASHINGS & TRIM Flashings - Base	4	10	
	B3010 ROOF COVERINGS	1996 B301004 FLASHINGS & TRIM Flashings - Cap	24	5	
	B3010 ROOF COVERINGS	1996 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	4	10	
	B3010 ROOF COVERINGS	1996 B301004 FLASHINGS & TRIM General	24	10	8
	B3010 ROOF COVERINGS	1996 B301005 GUTTERS & DOWNSPOUTS Downspouts	24	8	4
	B3010 ROOF COVERINGS	1996 B301006 ROOF OPENINGS AND SUPPORTS Skylights	24	0	
	B3010 ROOF COVERINGS	1996 B301090 OTHER ROOFING Walkway Protection	24	2	
	B3010 ROOF COVERINGS	1996 A B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	8	8	
	B3010 ROOF COVERINGS	1996 A B301003 ROOF INSULATION & FILL General	8	12	
	B3010 ROOF COVERINGS	1996 A B301004 FLASHINGS & TRIM Flashings - Base	8	10	
	B3010 ROOF COVERINGS	1996 A B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	8	10	
	B3010 ROOF COVERINGS	1996 A B301004 FLASHINGS & TRIM Flashings - Pitch Pans	4	13	
	B3010 ROOF COVERINGS	1996 B B301004 FLASHINGS & TRIM Flashings - Pitch Pans	4	13	
C10 INTERIOR	C1010 PARTITIONS	1996 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing	24	65	21
	C1010 PARTITIONS	1996 C101005 INTERIOR WINDOWS General	24	10	
	C1020 INTERIOR DOORS	1996 C102001 STANDARD INTERIOR DOORS Metal Door	24	20	
	C1020 INTERIOR DOORS	1996 C102003 FIRE DOORS Fire Door - Swinging, Metal	24	12	
	C1020 INTERIOR DOORS	1996 C102006 INTERIOR GATES General	24	8	



Remaining Service Life (RSL) Detail Report



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	C1030 SPECIALTIES	1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Shower	24	0	
	C1030 SPECIALTIES	1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet	24	21	
	C1030 SPECIALTIES	1996 C103002 TOILET & BATH ACCESSORIES General	24	6	
	C1030 SPECIALTIES	1996 C103003 MARKER BOARDS & TACK BOARDS General	24	6	
	C1030 SPECIALTIES	1996 C103005 LOCKERS General	2	20	
	C1030 SPECIALTIES	1996 C103006 SHELVING General	24	26	
	C1030 SPECIALTIES	1996 C103008 COUNTERS Laminated Plastic	24	3	
	C1030 SPECIALTIES	1996 C103009 CABINETS Other	24	2	
	C1030 SPECIALTIES	1996 C103010 CASEWORK General	24	4	
	C1030 SPECIALTIES	1996 C103014 ENTRANCE FLOOR GRILLES AND MATS General	24	14	
	C1030 SPECIALTIES	1996 A C103008 COUNTERS Laminated Plastic	2	20	
	C1030 SPECIALTIES	1999 A C103009 CABINETS Other	24	13	
C20 STAIRS	C2010 STAIR CONSTRUCTION	1996 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Concrete	24	52	
	C2010 STAIR CONSTRUCTION	1996 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Metal (12	24	27	
	C2010 STAIR CONSTRUCTION	1996 C201001 INTERIOR AND EXTERIOR STAIRS Interior Stairs	24	41	
	C2010 STAIR CONSTRUCTION	1996 A C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES	24	8	3
	C2010 STAIR CONSTRUCTION	1996 B C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES	24	8	3
C30 INTERIOR FINISHES	C3010 WALL FINISHES	1996 C301004 TILE & TERRAZZO WALL FINISHES General	24	31	
	C3010 WALL FINISHES	1996 C301006 ACOUSTICAL PANELS ADHERED TO WALLS General	24	0	
	C3020 FLOOR FINISHES	1996 C302001 TILE FLOOR FINISHES Ceramic Tile	15	39	
	C3020 FLOOR FINISHES	1996 C302003 WOOD FLOORING General	7	16	
	C3020 FLOOR FINISHES	1996 C302004 RESILIENT FLOOR FINISHES Composition Sheet	9	9	
	C3020 FLOOR FINISHES	1996 C302005 CARPETING General	15	1	
	C3020 FLOOR FINISHES	1999 C302001 TILE FLOOR FINISHES Marble Tile	15	39	
	C3030 CEILING FINISHES	1996 C303001 ACOUSTICAL CEILING TILES & PANELS General	24	0	
	C3030 CEILING FINISHES	1996 C303005 SUSPENSION SYSTEMS General	24	0	
D10 CONVEYING	D1010 ELEVATORS AND LIFTS	1996 ROOM M101 D101002 PASSENGER ELEVATORS Hydraulic Elevators -	24	10	
D20 PLUMBING	D2010 PLUMBING FIXTURES	1996 D201002 URINALS General	2	13	
	D2010 PLUMBING FIXTURES	1996 D201004 SINKS Kitchen Sink	24	7	
	D2010 PLUMBING FIXTURES	1996 D201004 SINKS Laboratory Sink	24	4	



Remaining Service Life (RSL) Detail Report



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	D2010 PLUMBING FIXTURES	1996 D201004 SINKS Service Sink	24	4	
	D2010 PLUMBING FIXTURES	1996 D201004 SINKS Stainless	24	6	
	D2010 PLUMBING FIXTURES	1996 D201005 SHOWERS/TUBS Shower	24	4	
	D2010 PLUMBING FIXTURES	1996 D201006 DRINKING FOUNTAINS AND COOLERS Drinking Fountain	24	4	
	D2010 PLUMBING FIXTURES	1996 D201090 OTHER PLUMBING FIXTURES Emergency Eye Wash	24	5	
	D2010 PLUMBING FIXTURES	1996 D201090 OTHER PLUMBING FIXTURES Emergency Shower	24	5	
	D2010 PLUMBING FIXTURES	1996 A D201001 WATERCLOSETS General	24	4	
	D2010 PLUMBING FIXTURES	1996 A D201004 SINKS General	24	4	
	D2010 PLUMBING FIXTURES	1996 B D201001 WATERCLOSETS General	2	13	
	D2010 PLUMBING FIXTURES	1996 B D201004 SINKS General	2	13	
	D2020 DOMESTIC WATER	1996 D202001 PIPES & FITTINGS General	24	26	
	D2020 DOMESTIC WATER	1996 ROOM 234/235 D202003 DOMESTIC WATER EQUIPMENT Water	10	10	
	D2030 SANITARY WASTE	1996 D203001 WASTE PIPE & FITTINGS General	24	26	
	D2030 SANITARY WASTE	1996 D203002 VENT PIPE & FITTINGS General	24	0	
	D2030 SANITARY WASTE	1996 D203003 FLOOR DRAINS General	24	4	
	D2040 RAIN WATER DRAINAGE	1996 D204001 PIPE & FITTINGS General	24	0	
	D2040 RAIN WATER DRAINAGE	1996 D204002 ROOF DRAINS Other	24	0	
D30 HVAC	D3030 COOLING GENERATING	1996 OUTSIDE D303002 DIRECT EXPANSION SYSTEMS Packaged DX	9	6	
	D3040 DISTRIBUTION SYSTEMS	1996 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	24	16	
	D3040 DISTRIBUTION SYSTEMS	1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General	24	0	
	D3040 DISTRIBUTION SYSTEMS	1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	24	0	
	D3040 DISTRIBUTION SYSTEMS	1996 ROOFTOP A D304007 EXHAUST SYSTEMS Fume Hood Exhaust System -	24	0	
	D3040 DISTRIBUTION SYSTEMS	1996 ROOFTOP B D304007 EXHAUST SYSTEMS Fume Hood Exhaust System	2	6	
	D3040 DISTRIBUTION SYSTEMS	1996 UTA-1 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	24	0	
	D3040 DISTRIBUTION SYSTEMS	1996 UTA-2 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	24	0	
	D3040 DISTRIBUTION SYSTEMS	1996 UTA-3 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	24	0	
	D3040 DISTRIBUTION SYSTEMS	1996 UTA-4 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	24	0	
	D3050 TERMINAL & PACKAGE UNITS	1996 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton	24	0	
	D3050 TERMINAL & PACKAGE UNITS	1996 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 2 ton	24	6	
	D3050 TERMINAL & PACKAGE UNITS	1996 D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged	15	8	
	D3050 TERMINAL & PACKAGE UNITS	1996 A D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton	24	4	
	D3050 TERMINAL & PACKAGE UNITS	1996 PAC-012 D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air Cooled	15	2	



Remaining Service Life (RSL) Detail Report



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOFTOP D305006 PACKAGE UNITS A/C Unit, Package Terminal -	9	2	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOFTOP D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air	15	2	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 107 D305006 PACKAGE UNITS A/C Unit, Package Terminal -	15	6	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 112D D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air	3	8	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 115 D305006 PACKAGE UNITS A/C Unit, Package Terminal -	15	6	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 122D D305006 PACKAGE UNITS A/C Unit, Package Terminal -	15	6	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 124 D305006 PACKAGE UNITS A/C Unit, Package Terminal -	5	10	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 225 D305006 PACKAGE UNITS A/C Unit, Package Terminal -	8	6	
	D3050 TERMINAL & PACKAGE UNITS	1996 SS-046 D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged	15	6	
	D3050 TERMINAL & PACKAGE UNITS	1996 SS-605 D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged	11	6	
	D3060 CONTROLS &	1996 D306002 ELECTRONIC CONTROLS General	24	3	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION	1996 D401001 FIRE ALARM DISTRIBUTION Other	24	0	
	D4040 SPRINKLERS	1996 D404001 SPRINKLERS AND RELEASING DEVICES Wet Pipe Systems	24	51	
D50 ELECTRICAL	D5010 ELECTRICAL SERVICE &	1996 D501004 PANELBOARDS Main lugs, 50 amp	24	4	
	D5010 ELECTRICAL SERVICE &	1996 D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp, NQOD	24	6	
	D5010 ELECTRICAL SERVICE &	1996 D501004 PANELBOARDS Main lugs, 120/240 V, 225 amp, NQOD	24	9	
	D5010 ELECTRICAL SERVICE &	1996 D501004 PANELBOARDS Main lugs, 125 amp	24	4	
	D5010 ELECTRICAL SERVICE &	1996 ROOM 123 D501002 SERVICE ENTRANCE EQUIPMENT Electrical	24	6	
	D5010 ELECTRICAL SERVICE &	1996 ROOM 123 D501003 INTERIOR DISTRIBUTION TRANSFORMERS dry-	24	10	
	D5010 ELECTRICAL SERVICE &	1996 ROOM 123 D501003 INTERIOR DISTRIBUTION TRANSFORMERS dry-	24	10	
	D5010 ELECTRICAL SERVICE &	1996 ROOM 123 D501004 PANELBOARDS Main lugs, 200 amp	24	13	
	D5010 ELECTRICAL SERVICE &	1996 ROOM 226 D501003 INTERIOR DISTRIBUTION TRANSFORMERS dry-	24	5	
	D5010 ELECTRICAL SERVICE &	1996 ROOM 226 D501004 PANELBOARDS Main lugs, 200 amp	24	4	
	D5020 LIGHTING & BRANCH WIRING	1996 D502001 BRANCH WIRING General	24	36	
	D5020 LIGHTING & BRANCH WIRING	1996 D502002 LIGHTING EQUIPMENT Exit Lighting	24	6	
	D5020 LIGHTING & BRANCH WIRING	1996 D502002 LIGHTING EQUIPMENT Exterior Lighting	24	6	
	D5020 LIGHTING & BRANCH WIRING	1996 D502002 LIGHTING EQUIPMENT General	24	4	
	D5030 COMMUNICATIONS &	1996 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets	24	0	
	D5030 COMMUNICATIONS &	1996 D503003 INTERCOMMUNICATIONS SYSTEMS 50 stations	24	0	
	D5030 COMMUNICATIONS &	1996 D503005 SECURITY SYSTEMS General	15	0	
	D5030 COMMUNICATIONS &	1996 D503007 CLOCK & PROGRAM SYSTEMS General	24	0	



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	D5090 OTHER ELECTRICAL	1996 D509002 EMERGENCY LIGHTING & POWER General	24	4	
	D5090 OTHER ELECTRICAL	1996 D509002 EMERGENCY LIGHTING & POWER Uninterruptible Power	24	7	
	D5090 OTHER ELECTRICAL	1996 D509003 GROUNDING SYSTEMS General	24	26	



Remaining Service Life (RSL) Detail Report



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1996 B201001 EXTERIOR CLOSURE Brick Veneer w/CMU Backup	24	23	
	B2010 EXTERIOR WALLS	1996 B201001 EXTERIOR CLOSURE Stone Veneer w/CMU Backup	24	23	
	B2010 EXTERIOR WALLS	1996 B201001 EXTERIOR CLOSURE Stucco	24	12	4
	B2010 EXTERIOR WALLS	1996 B201004 PARAPETS General	24	6	
	B2010 EXTERIOR WALLS	1996 B201006 BALCONY WALLS & HANDRAILS Handrailing	24	3	5
	B2010 EXTERIOR WALLS	1996 B201007 EXTERIOR SOFFITS General	24	6	3
	B2010 EXTERIOR WALLS	1996 A B201010 EXTERIOR JOINT SEALANT General	24	4	
	B2010 EXTERIOR WALLS	1996 B B201010 EXTERIOR JOINT SEALANT General	24	4	
	B2020 EXTERIOR WINDOWS	1996 B202001 WINDOWS Steel Windows	24	15	
	B2030 EXTERIOR DOORS	1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress	24	0	
B30 ROOFING	B3010 ROOF COVERINGS	1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	4	8	
	B3010 ROOF COVERINGS	1996 B301003 ROOF INSULATION & FILL General	24	0	
	B3010 ROOF COVERINGS	1996 B301004 FLASHINGS & TRIM Flashings - Base	4	13	
	B3010 ROOF COVERINGS	1996 B301004 FLASHINGS & TRIM Flashings - Cap	4	13	
	B3010 ROOF COVERINGS	1996 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	4	13	
	B3010 ROOF COVERINGS	1996 B301004 FLASHINGS & TRIM General	24	10	5
	B3010 ROOF COVERINGS	1996 B301005 GUTTERS & DOWNSPOUTS Downspouts	24	6	4
	B3010 ROOF COVERINGS	1996 A B301004 FLASHINGS & TRIM Flashings - Apron	4	10	
	B3010 ROOF COVERINGS	1996 B B301004 FLASHINGS & TRIM Flashings - Apron	4	10	
C10 INTERIOR	C1010 PARTITIONS	1996 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing	24	65	4
	C1010 PARTITIONS	1996 C101005 INTERIOR WINDOWS Interior Windows	24	26	
	C1010 PARTITIONS	1996 C101005 INTERIOR WINDOWS Metal Rollup / Coiling Grille	24	0	
	C1020 INTERIOR DOORS	1996 C102001 STANDARD INTERIOR DOORS Metal Door	24	15	
	C1020 INTERIOR DOORS	1996 C102005 INTERIOR OVERHEAD DOORS Metal	24	11	
	C1020 INTERIOR DOORS	1996 C102090 OTHER INTERIOR SPECIALTY DOORS Cold Storage	24	8	
	C1030 SPECIALTIES	1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet	24	21	
	C1030 SPECIALTIES	1996 C103002 TOILET & BATH ACCESSORIES General	24	6	
	C1030 SPECIALTIES	1996 C103003 MARKER BOARDS & TACK BOARDS General	24	6	
	C1030 SPECIALTIES	1996 C103005 LOCKERS General	24	12	
	C1030 SPECIALTIES	1996 C103006 SHELVEING General	24	26	
C20 STAIRS	C2010 STAIR CONSTRUCTION	1996 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES	24	8	3



Remaining Service Life (RSL) Detail Report



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
C30 INTERIOR FINISHES	C3010 WALL FINISHES	1996 C301002 PLASTER WALL FINISHES General	24	65	0
	C3010 WALL FINISHES	1996 C301004 TILE & TERRAZZO WALL FINISHES General	24	39	
	C3020 FLOOR FINISHES	1996 C302001 TILE FLOOR FINISHES Ceramic Tile	24	39	
	C3020 FLOOR FINISHES	1996 C302004 RESILIENT FLOOR FINISHES Composition Sheet	24	0	
	C3020 FLOOR FINISHES	1996 C302006 MASONRY & STONE FLOORING Quarry Tile	24	26	
	C3030 CEILING FINISHES	1996 C303001 ACOUSTICAL CEILING TILES & PANELS General	24	0	
	C3030 CEILING FINISHES	1996 C303003 PLASTER CEILING FINISHES General	24	65	4
	C3030 CEILING FINISHES	1996 C303005 SUSPENSION SYSTEMS General	24	0	
D20 PLUMBING	D2010 PLUMBING FIXTURES	1996 D201002 URINALS General	24	4	
	D2010 PLUMBING FIXTURES	1996 D201004 SINKS Kitchen Sink	24	11	
	D2010 PLUMBING FIXTURES	1996 D201006 DRINKING FOUNTAINS AND COOLERS Drinking Fountain	24	4	
	D2010 PLUMBING FIXTURES	1996 A D201001 WATERCLOSETS General	24	2	
	D2010 PLUMBING FIXTURES	1996 A D201004 SINKS General	24	2	
	D2010 PLUMBING FIXTURES	1996 B D201001 WATERCLOSETS General	2	13	
	D2010 PLUMBING FIXTURES	1996 B D201004 SINKS General	2	13	
	D2020 DOMESTIC WATER	1996 D202001 PIPES & FITTINGS General	24	26	
	D2020 DOMESTIC WATER	1996 D202002 VALVES & HYDRANTS Backflow Preventer - 3" pipe	24	4	
	D2020 DOMESTIC WATER	1996 D202003 DOMESTIC WATER EQUIPMENT Storage Tank - Glass lined, PE	24	9	
	D2020 DOMESTIC WATER	1996 ROOM M101 D202003 DOMESTIC WATER EQUIPMENT Booster Pump -	24	4	
	D2020 DOMESTIC WATER	1996 ROOM M101 D202003 DOMESTIC WATER EQUIPMENT Storage Tank -	24	9	
	D2020 DOMESTIC WATER	1996 ROOM M101 D202003 DOMESTIC WATER EQUIPMENT Water Softener	24	4	
	D2020 DOMESTIC WATER	1996 ROOM M102 D202003 DOMESTIC WATER EQUIPMENT Water Softener	24	4	
	D2030 SANITARY WASTE	1996 D203001 WASTE PIPE & FITTINGS General	24	26	
	D2030 SANITARY WASTE	1996 D203002 VENT PIPE & FITTINGS General	24	0	
	D2030 SANITARY WASTE	1996 D203003 FLOOR DRAINS General	24	4	
	D2040 RAIN WATER DRAINAGE	1996 D204001 PIPE & FITTINGS General	24	0	
	D2040 RAIN WATER DRAINAGE	1996 D204002 ROOF DRAINS Other	24	4	
D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1996 A D302004 AUXILIARY EQUIPMENT Expansion Tank - 40 gal	24	9	
	D3020 HEAT GENERATING SYSTEMS	1996 B D302004 AUXILIARY EQUIPMENT Expansion Tank - 40 gal	13	12	
	D3020 HEAT GENERATING SYSTEMS	1996 ROOM M101 A D302004 AUXILIARY EQUIPMENT Expansion Tank - 15 gal	23	9	
	D3020 HEAT GENERATING SYSTEMS	1996 ROOM M101 B D302004 AUXILIARY EQUIPMENT Expansion Tank - 15 gal	13	15	



Remaining Service Life (RSL) Detail Report



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	D3020 HEAT GENERATING SYSTEMS	1996 ROOM M101 BOILER 1 D302001 BOILERS Gas, Hot Water - 500-650	24	3	
	D3020 HEAT GENERATING SYSTEMS	1996 ROOM M101 BOILER 2 D302001 BOILERS Gas, Hot Water - 500-650	24	3	
	D3020 HEAT GENERATING SYSTEMS	1996 ROOM M101 C D302004 AUXILIARY EQUIPMENT Expansion Tank - 15 gal	4	15	
	D3020 HEAT GENERATING SYSTEMS	1996 ROOM M102 D302004 AUXILIARY EQUIPMENT Expansion Tank - 30 gal	14	12	
	D3020 HEAT GENERATING SYSTEMS	1996 ROOM M102 A D302004 AUXILIARY EQUIPMENT Expansion Tank - 15 gal	8	15	
	D3020 HEAT GENERATING SYSTEMS	1996 ROOM M102 B D302004 AUXILIARY EQUIPMENT Expansion Tank - 15 gal	24	9	
	D3020 HEAT GENERATING SYSTEMS	1996 ROOM M102 BOILER-2058A D302001 BOILERS Gas, Hot Water - 500-	24	3	
	D3020 HEAT GENERATING SYSTEMS	1996 ROOM M102 BOILER-2058B D302001 BOILERS Gas, Hot Water - 500-	24	3	
	D3030 COOLING GENERATING	1996 ROOFTOP A D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating,	3	4	
	D3030 COOLING GENERATING	1996 ROOFTOP B D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating,	3	6	
	D3030 COOLING GENERATING	1996 ROOFTOP C D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating,	3	4	
	D3030 COOLING GENERATING	1996 ROOFTOP D D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating,	3	4	
	D3040 DISTRIBUTION SYSTEMS	1996 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	24	16	
	D3040 DISTRIBUTION SYSTEMS	1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General	24	0	
	D3040 DISTRIBUTION SYSTEMS	1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	24	0	
	D3040 DISTRIBUTION SYSTEMS	1996 A D304006 CHILLED WATER DISTRIBUTION SYSTEMS Circulating Pump	24	2	
	D3040 DISTRIBUTION SYSTEMS	1996 AHU-056 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM	24	0	
	D3040 DISTRIBUTION SYSTEMS	1996 AHU-061 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM	24	0	
	D3040 DISTRIBUTION SYSTEMS	1996 AHU-062 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM	24	0	
	D3040 DISTRIBUTION SYSTEMS	1996 B D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating Pump, End	8	8	
	D3040 DISTRIBUTION SYSTEMS	1996 B D304006 CHILLED WATER DISTRIBUTION SYSTEMS Circulating	15	4	
	D3040 DISTRIBUTION SYSTEMS	1996 C D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating Pump,	15	6	
	D3040 DISTRIBUTION SYSTEMS	1996 C D304006 CHILLED WATER DISTRIBUTION SYSTEMS Circulating	24	4	
	D3040 DISTRIBUTION SYSTEMS	1996 EF-121/97 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 800	24	2	
	D3040 DISTRIBUTION SYSTEMS	1996 ROOFTOP D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust -	24	0	
	D3040 DISTRIBUTION SYSTEMS	1996 ROOFTOP D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust -	24	2	
	D3040 DISTRIBUTION SYSTEMS	1996 ROOM M101 D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating	2	13	
	D3040 DISTRIBUTION SYSTEMS	1996 ROOM M101 D304006 CHILLED WATER DISTRIBUTION SYSTEMS	2	10	
	D3040 DISTRIBUTION SYSTEMS	1996 ROOM M102 D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating	17	6	
	D3040 DISTRIBUTION SYSTEMS	1996 ROOM M102 B D304003 HOT WATER DISTRIBUTION SYSTEMS	24	6	
	D3050 TERMINAL & PACKAGE UNITS	1996 A D305001 UNIT VENTILATORS Air Curtain	24	4	
	D3050 TERMINAL & PACKAGE UNITS	1996 B D305001 UNIT VENTILATORS Air Curtain	24	4	



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 128 D305006 PACKAGE UNITS A/C Unit, Package Terminal -	15	6	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 137D D305006 PACKAGE UNITS A/C Unit, Package Terminal -	15	6	
	D3060 CONTROLS & DISTRIBUTION	1996 D306002 ELECTRONIC CONTROLS General	24	3	
	D3060 CONTROLS & DISTRIBUTION	1996 ROOFTOP D306002 ELECTRONIC CONTROLS General	24	2	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SYSTEMS	1996 D401001 FIRE ALARM DISTRIBUTION Other	24	0	
	D4040 SPRINKLERS	1996 D404001 SPRINKLERS AND RELEASING DEVICES Wet Pipe Systems	24	51	
	D4090 OTHER FIRE PROTECTION SYSTEMS	1996 D409004 HOOD & DUCT FIRE PROTECTION General	24	7	
D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp, NQOD	24	6	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 D501004 PANELBOARDS Switchgear - 800 Amp	24	5	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 ROOM 138B D501004 PANELBOARDS Main lugs, 200 amp	24	6	
	D5020 LIGHTING & BRANCH WIRING	1996 D502001 BRANCH WIRING General	24	36	
	D5020 LIGHTING & BRANCH WIRING	1996 D502002 LIGHTING EQUIPMENT Exit Lighting	24	6	
	D5020 LIGHTING & BRANCH WIRING	1996 D502002 LIGHTING EQUIPMENT Exterior Lighting	24	6	
	D5020 LIGHTING & BRANCH WIRING	1996 D502002 LIGHTING EQUIPMENT General	24	6	
	D5030 COMMUNICATIONS & DISTRIBUTION	1996 D503002 PUBLIC ADDRESS SYSTEMS 6 outlets	24	0	
	D5030 COMMUNICATIONS & DISTRIBUTION	1996 D503003 INTERCOMMUNICATIONS SYSTEMS 6 stations	24	0	
	D5030 COMMUNICATIONS & DISTRIBUTION	1996 D503007 CLOCK & PROGRAM SYSTEMS General	24	0	
	D5090 OTHER ELECTRICAL SYSTEMS	1996 D509002 EMERGENCY LIGHTING & POWER General	24	4	
	D5090 OTHER ELECTRICAL SYSTEMS	1996 D509003 GROUNDING SYSTEMS General	24	26	
E10 EQUIPMENT	E1090 OTHER EQUIPMENT	*BRAISING PAN A E109002 FOOD SERVICE EQUIPMENT General	24	13	
	E1090 OTHER EQUIPMENT	*BRAISING PAN B E109002 FOOD SERVICE EQUIPMENT General	24	13	
	E1090 OTHER EQUIPMENT	*COLD PAN SINGLE BASIN A E109002 FOOD SERVICE EQUIPMENT General	24	13	
	E1090 OTHER EQUIPMENT	*COLD PAN SINGLE BASIN B E109002 FOOD SERVICE EQUIPMENT General	24	13	
	E1090 OTHER EQUIPMENT	*COLD PAN SINGLE BASIN C E109002 FOOD SERVICE EQUIPMENT General	24	13	
	E1090 OTHER EQUIPMENT	*COLD PAN SINGLE BASIN D E109002 FOOD SERVICE EQUIPMENT General	24	13	
	E1090 OTHER EQUIPMENT	*DEEP FRYER A E109002 FOOD SERVICE EQUIPMENT General	24	13	
	E1090 OTHER EQUIPMENT	*DEEP FRYER B E109002 FOOD SERVICE EQUIPMENT General	24	13	
	E1090 OTHER EQUIPMENT	*DISH MACHINE A E109002 FOOD SERVICE EQUIPMENT General	24	13	
	E1090 OTHER EQUIPMENT	*DISH MACHINE B E109002 FOOD SERVICE EQUIPMENT General	24	13	
	E1090 OTHER EQUIPMENT	*GRIDDLE A E109002 FOOD SERVICE EQUIPMENT General	24	13	
	E1090 OTHER EQUIPMENT	*GRIDDLE B E109002 FOOD SERVICE EQUIPMENT General	24	13	



Remaining Service Life (RSL) Detail Report



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	E1090 OTHER EQUIPMENT	*GRIDDLE C E109002 FOOD SERVICE EQUIPMENT General	24	13	
	E1090 OTHER EQUIPMENT	*GRIDDLE D E109002 FOOD SERVICE EQUIPMENT General	24	13	
	E1090 OTHER EQUIPMENT	*GRIDDLE E E109002 FOOD SERVICE EQUIPMENT General	24	13	
	E1090 OTHER EQUIPMENT	*HOT CABINET REACH IN 2DR A E109002 FOOD SERVICE EQUIPMENT	24	13	
	E1090 OTHER EQUIPMENT	*HOT CABINET REACH IN 2DR B E109002 FOOD SERVICE EQUIPMENT	24	13	
	E1090 OTHER EQUIPMENT	*KETTLE ELECTRIC A E109002 FOOD SERVICE EQUIPMENT General	24	13	
	E1090 OTHER EQUIPMENT	*KETTLE ELECTRIC B E109002 FOOD SERVICE EQUIPMENT General	24	13	
	E1090 OTHER EQUIPMENT	*KETTLE ELECTRIC C E109002 FOOD SERVICE EQUIPMENT General	24	13	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2DR A E109002 FOOD SERVICE EQUIPMENT	24	13	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2DR B E109002 FOOD SERVICE EQUIPMENT	24	13	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN A E109002 FOOD SERVICE EQUIPMENT	24	13	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN B E109002 FOOD SERVICE EQUIPMENT	24	13	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN C E109002 FOOD SERVICE EQUIPMENT	24	13	
	E1090 OTHER EQUIPMENT	*STEAMER 1 DOOR A E109002 FOOD SERVICE EQUIPMENT General	24	13	
	E1090 OTHER EQUIPMENT	*STEAMER 1 DOOR B E109002 FOOD SERVICE EQUIPMENT General	24	13	
	E1090 OTHER EQUIPMENT	*STEAMER 1 DOOR C E109002 FOOD SERVICE EQUIPMENT General	24	13	
	E1090 OTHER EQUIPMENT	*WALK IN COOLER E109002 FOOD SERVICE EQUIPMENT General	24	13	
	E1090 OTHER EQUIPMENT	*WALK IN FREEZER E109002 FOOD SERVICE EQUIPMENT General	24	13	

Appendix G

"identification only"

Direct Condition Rating Inspection By Section Report



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
1996 B201001 EXTERIOR CLOSURE Brick Veneer w/CMU	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	3,800 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 B201001 EXTERIOR CLOSURE Stucco	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	21,900 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 B201004 PARAPETS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1,738 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 B201006 BALCONY WALLS & HANDRAILS Handrailing	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	174 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 B201007 EXTERIOR SOFFITS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	2,177 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 B203090 OTHER EXTERIOR SPECIALTY DOORS	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	34 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments: Several of the double leaf egress doors do not coordinate closure properly.	Condition Rating: R-	Used Sampling? No Inspection Source: Inspection	
1996 B301001 STEEP SLOPE ROOF SYSTEMS Clay Tile	B30 ROOFING	B3010 ROOF COVERINGS	2,376 (SF)



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	B30 ROOFING	B3010 ROOF COVERINGS	60,131 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1996 B301003 ROOF INSULATION & FILL General	B30 ROOFING	B3010 ROOF COVERINGS	62,507 (SF)
Last Inspection Date: 01-Jan-1996 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1996 B301004 FLASHINGS & TRIM Flashings - Base	B30 ROOFING	B3010 ROOF COVERINGS	3,655 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1996 B301004 FLASHINGS & TRIM Flashings - Cap	B30 ROOFING	B3010 ROOF COVERINGS	3,371 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 B301004 FLASHINGS & TRIM Flashings - Flashing	B30 ROOFING	B3010 ROOF COVERINGS	76 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1996 B301005 GUTTERS & DOWNSPOUTS Downspouts	B30 ROOFING	B3010 ROOF COVERINGS	1,141 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
1996 B301006 ROOF OPENINGS AND SUPPORTS Skylights	B30 ROOFING	B3010 ROOF COVERINGS	180 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments: The skylight is corroded, with brittle or missing sealant and evidence of patches.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	
1996 B301090 OTHER ROOFING Walkway Protection	B30 ROOFING	B3010 ROOF COVERINGS	552 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments: The damage from hailstorms appears to have been repaired.	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 C101001 FIXED PARTITIONS Wall - Plaster w/Stud	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	107,200 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G- Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 C101005 INTERIOR WINDOWS Interior Windows	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	56 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1996 C102001 STANDARD INTERIOR DOORS Metal Door	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	148 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 C102003 FIRE DOORS Fire Door - Swinging	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	16 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 C102006 INTERIOR GATES General	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	2 (EA)



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1996 C103001 COMPARTMENTS, CUBICLES & TOILET	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	58 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: New hardware was observed and reported.	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 C103002 TOILET & BATH ACCESSORIES General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	221 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 C103003 MARKER BOARDS & TACK BOARDS General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	182 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 C103005 LOCKERS General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	884 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1996 C103006 SHELVING General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	108 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1996 C103008 COUNTERS Laminated Plastic	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	183 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The laminated countertops are stained and damaged.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
1996 C103009 CABINETS Other	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	473 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments: Several of the cabinets are misaligned and missing hardware.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 C103010 CASEWORK General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	1,228 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1996 C201001 INTERIOR AND EXTERIOR STAIRS Exterior	C20 STAIRS	C2010 STAIR CONSTRUCTION	4 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 C201001 INTERIOR AND EXTERIOR STAIRS Interior	C20 STAIRS	C2010 STAIR CONSTRUCTION	3 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 C201090 STAIR HANDRAILS, GUARDRAILS AND	C20 STAIRS	C2010 STAIR CONSTRUCTION	227 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+ Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 C301004 TILE & TERRAZZO WALL FINISHES General	C30 INTERIOR FINISHES	C3010 WALL FINISHES	18,100 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 C302001 TILE FLOOR FINISHES Ceramic Tile	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	72,800 (SF)



Direct Condition Rating Inspection Report by Section



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1996 C302005 CARPETING General	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	4,800 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The carpet is worn and deteriorated.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	
1996 C303001 ACOUSTICAL CEILING TILES & PANELS	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	84,000 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: A large portion of ceiling tiles are stained and damaged.	Condition Rating: R-	Used Sampling? No Inspection Source: Inspection	
1996 C303005 SUSPENSION SYSTEMS General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	84,000 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The grid system around the new cabinetry is heavily damaged.	Condition Rating: R-	Used Sampling? No Inspection Source: Inspection	
1996 C303006 METAL STRIP CEILINGS General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	1,700 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The metal strip ceiling is displaced in some areas.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	
1996 D201002 URINALS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	24 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1996 D201004 SINKS Service Sink	D20 PLUMBING	D2010 PLUMBING FIXTURES	3 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
Inspection Comments: The service sinks are discolored.			
1996 D201004 SINKS Stainless	D20 PLUMBING	D2010 PLUMBING FIXTURES	53 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 D201005 SHOWERS/TUBS Shower	D20 PLUMBING	D2010 PLUMBING FIXTURES	3 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The showers and shower heads are corroded.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 D201006 DRINKING FOUNTAINS AND COOLERS	D20 PLUMBING	D2010 PLUMBING FIXTURES	12 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The drinking fountains are discolored and corroded on the piping.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1996 D202001 PIPES & FITTINGS General	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	31,744 (LF)
Last Inspection Date: 01-Jan-1996 Inspector: XXXXXXXXXX Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1996 D203001 WASTE PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	52,073 (LF)
Last Inspection Date: 01-Jan-1996 Inspector: XXXXXXXXXX Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1996 D203002 VENT PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	3,861 (EA)
Last Inspection Date: 01-Jan-1996 Inspector: XXXXXXXXXX Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1996 D203003 FLOOR DRAINS General	D20 PLUMBING	D2030 SANITARY WASTE	16 (EA)



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 D204001 PIPE & FITTINGS General	D20 PLUMBING	D2040 RAIN WATER DRAINAGE	1,005 (LF)
Last Inspection Date: 01-Jan-1996 Inspector: XXXXXXXXXX Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1996 D204002 ROOF DRAINS Other	D20 PLUMBING	D2040 RAIN WATER DRAINAGE	67 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: Many roof drains have damaged drain strainers and are clogged with debris.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	
1996 D304001 AIR DISTRIBUTION, HEATING & COOLING	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	30,251 (LF)
Last Inspection Date: 01-Jan-1996 Inspector: XXXXXXXXXX Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	4,382 (MBH)
Last Inspection Date: 01-Jan-1996 Inspector: XXXXXXXXXX Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	438 (TON)
Last Inspection Date: 01-Jan-1996 Inspector: XXXXXXXXXX Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1996 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	24 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The fin coil units are approaching the end of their statistical lives.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
1996 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 2 ton	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	57 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 D306002 ELECTRONIC CONTROLS General	D30 HVAC	D3060 CONTROLS & INSTRUMENTATION	6 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments: The electronic controls are corroded and approaching the end of their service lives.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	
1996 D401001 FIRE ALARM DISTRIBUTION Other	D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SY\$	108,693 (SF)
Last Inspection Date: 01-Jan-1996 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1996 D404001 SPRINKLERS AND RELEASING DEVICES Wet	D40 FIRE PROTECTION	D4040 SPRINKLERS	108,693 (SF)
Last Inspection Date: 01-Jan-1996 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1996 D501003 INTERIOR DISTRIBUTION TRANSFORMERS	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	2 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 D501003 INTERIOR DISTRIBUTION TRANSFORMERS	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	2 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments: The transformers have corrosion and excess noise.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1996 D501004 PANELBOARDS Main lugs, 50 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	8 (EA)



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp,	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	5 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The panelboards are approaching the end of their statistical lives.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 D501004 PANELBOARDS Main lugs, 125 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	4 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 D501004 PANELBOARDS Safety Switch, 30-100 Amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 D502001 BRANCH WIRING General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	108,693 (SF)
Last Inspection Date: 01-Jan-1996 Inspector: XXXXXXXXXX Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1996 D502002 LIGHTING EQUIPMENT Exit Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	47 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 D502002 LIGHTING EQUIPMENT General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	108,693 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: It was reported that the bulbs and ballasts sometimes fail. The fixtures are corroded.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
1996 D503001 TELECOMMUNICATIONS SYSTEMS General	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments: The telecommunications system is beyond its statistical life.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	
1996 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments: It was reported that the public address system does not work correctly.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	
1996 D503003 INTERCOMMUNICATIONS SYSTEMS 100	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments: The intercommunication system was reported to have issues.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	
1996 D503005 SECURITY SYSTEMS General	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 D503007 CLOCK & PROGRAM SYSTEMS General	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 D509002 EMERGENCY LIGHTING & POWER General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	108,693 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments: The emergency lighting is beyond its statistical life.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1996 D509002 EMERGENCY LIGHTING & POWER	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	4 (EA)



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 07-Jan-2020 Condition Rating: R+ Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments: The uninterruptible power supplies are approaching the end of their service life.			
1996 D509003 GROUNDING SYSTEMS General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	1 (EA)
Last Inspection Date: 01-Jan-1996 Condition Rating: G+ Used Sampling? No Inspector: [REDACTED] Inspection Source: InstallDate Inspection Comments: Original Inspection			
1996 A B201001 EXTERIOR CLOSURE Stone Veneer w/CMU	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	805 (SF)
Last Inspection Date: 07-Jan-2020 Condition Rating: A+ Used Sampling? No Inspector: [REDACTED] Paint Rating: G Inspection Source: Inspection Inspection Comments:			
1996 A B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	92 (LF)
Last Inspection Date: 07-Jan-2020 Condition Rating: A+ Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
1996 A B202001 WINDOWS Steel Windows	B20 EXTERIOR ENCLOSURE	B2020 EXTERIOR WINDOWS	149 (EA)
Last Inspection Date: 07-Jan-2020 Condition Rating: A+ Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
1996 A B301004 FLASHINGS & TRIM Flashings - Apron	B30 ROOFING	B3010 ROOF COVERINGS	248 (LF)
Last Inspection Date: 07-Jan-2020 Condition Rating: G- Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
1996 A B301004 FLASHINGS & TRIM General	B30 ROOFING	B3010 ROOF COVERINGS	749 (LF)
Last Inspection Date: 07-Jan-2020 Condition Rating: G- Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
1996 A C103008 COUNTERS Laminated Plastic	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	220 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1996 A C103009 CABINETS Other	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	1,343 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1996 A D201001 WATERCLOSETS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	30 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments: The waterclosets are discolored and corroded.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 A D201004 SINKS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	39 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments: The sinks are corroded on the faucets and piping.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1996 A D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	3 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments: The fin coil units are corroded.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1996 A D305006 PACKAGE UNITS A/C Unit, Package Terminal -	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	3 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments: The split units are approaching the end of their statistical lives. The outside splits have fin damage.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 A D502002 LIGHTING EQUIPMENT Exterior Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	12 (EA)



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? Inspection Source:	No Inspection
1996 AHU-055 D304008 AIR HANDLING UNITS Rooftop - 5000	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The air handling unit is heavily corroded.	Condition Rating: R	Used Sampling? Inspection Source:	No Inspection
1996 AHU-061 D304008 AIR HANDLING UNITS Rooftop - 5000	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The air handling unit is heavily corroded.	Condition Rating: R	Used Sampling? Inspection Source:	No Inspection
1996 AHU-1 D304008 AIR HANDLING UNITS Rooftop - 5000	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The air handling unit is heavily corroded.	Condition Rating: R	Used Sampling? Inspection Source:	No Inspection
1996 AHU-2 D304008 AIR HANDLING UNITS Rooftop - 5000	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The air handling unit is heavily corroded.	Condition Rating: R	Used Sampling? Inspection Source:	No Inspection
1996 AHU-3 D304008 AIR HANDLING UNITS Rooftop - 10000	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The air handling unit is heavily corroded.	Condition Rating: R	Used Sampling? Inspection Source:	No Inspection
1996 AHU-4 D304008 AIR HANDLING UNITS Rooftop - 5000	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The air handling unit is heavily corroded.	Condition Rating: R	Used Sampling? Inspection Source:	No Inspection



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
1996 B B201001 EXTERIOR CLOSURE Stone Veneer w/CMU	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	148 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 B B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	5,000 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 B B202001 WINDOWS Steel Windows	B20 EXTERIOR ENCLOSURE	B2020 EXTERIOR WINDOWS	29 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 B B301004 FLASHINGS & TRIM Flashings - Apron	B30 ROOFING	B3010 ROOF COVERINGS	248 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1996 B B301004 FLASHINGS & TRIM General	B30 ROOFING	B3010 ROOF COVERINGS	746 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 B D201001 WATERCLOSETS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	43 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1996 B D201004 SINKS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	58 (EA)



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1996 B D305006 PACKAGE UNITS A/C Unit, Package Terminal	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	2 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 B D502002 LIGHTING EQUIPMENT Exterior Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	11 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 LE101 D101002 PASSENGER ELEVATORS Hydraulic	D10 CONVEYING	D1010 ELEVATORS AND LIFTS	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOFTOP D304007 EXHAUST SYSTEMS Fan System,	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The rooftop exhaust fans are corroded.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 104 D501002 SERVICE ENTRANCE EQUIPMENT	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 104 D501002 SERVICE ENTRANCE EQUIPMENT	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	3 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
1996 ROOM 104 D501004 PANELBOARDS Main lugs, 277/480	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	2 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 117 D501002 SERVICE ENTRANCE EQUIPMENT	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	2 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 117 D501004 PANELBOARDS Main lugs, 200 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 119A D305006 PACKAGE UNITS A/C Unit,	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 132 D305006 PACKAGE UNITS A/C Unit, Split	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	2 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 132 A D305006 PACKAGE UNITS A/C Unit, Split	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 134 D305002 UNIT HEATERS Hydronic - 20 MBH	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)



Direct Condition Rating Inspection Report by Section



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 134 D305006 PACKAGE UNITS A/C Unit, Package	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	3 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The split units are approaching the end of their statistical lives and the outside units have minor fin damage.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 134 B D305006 PACKAGE UNITS A/C Unit, Split	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 141 D501004 PANELBOARDS Main lugs, 200 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 202 D501004 PANELBOARDS Main lugs, 120/240	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 202 D501004 PANELBOARDS Switchgear - 400	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 203 D305006 PACKAGE UNITS A/C Unit, Package	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	2 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
1996 ROOM 203 D305006 PACKAGE UNITS A/C Unit, Package	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments: The exterior unit has fin damage and corrosion.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 S103.2 D305006 PACKAGE UNITS A/C Unit, Split	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	2 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 C302001 TILE FLOOR FINISHES Marble Tile	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	3,500 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1999 C302004 RESILIENT FLOOR FINISHES Rubber Sheet	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	4,019 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
2004 B201001 EXTERIOR CLOSURE Brick Veneer w/CMU	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1,216 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2004 B201001 EXTERIOR CLOSURE Stone Veneer w/CMU	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	288 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2004 B201001 EXTERIOR CLOSURE Stucco	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	6,136 (SF)



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:		Condition Rating: A+ Paint Rating: A	Used Sampling? No Inspection Source: Inspection
2004 B201006 BALCONY WALLS & HANDRAILS Handrailing	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	75 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:		Condition Rating: A Paint Rating: A	Used Sampling? No Inspection Source: Inspection
2004 B201007 EXTERIOR SOFFITS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	774 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:		Condition Rating: A+ Paint Rating: A	Used Sampling? No Inspection Source: Inspection
2004 B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1,500 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:		Condition Rating: A+	Used Sampling? No Inspection Source: Inspection
2004 B202001 WINDOWS Steel Windows	B20 EXTERIOR ENCLOSURE	B2020 EXTERIOR WINDOWS	27 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:		Condition Rating: A+	Used Sampling? No Inspection Source: Inspection
2004 B203001 SOLID DOORS Steel	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:		Condition Rating: A	Used Sampling? No Inspection Source: Inspection
2004 B203002 GLAZED DOORS General	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	2 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:		Condition Rating: A	Used Sampling? No Inspection Source: Inspection



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
2004 B203090 OTHER EXTERIOR SPECIALTY DOORS	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	10 (EA)
Last Inspection Date: 07-Jan-2020 Condition Rating: A- Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments: Several doors do not coordinate closure properly, due to deteriorated or missing hardware and field repairs.			
2004 B301003 ROOF INSULATION & FILL General	B30 ROOFING	B3010 ROOF COVERINGS	13,665 (SF)
Last Inspection Date: 01-Jan-2004 Condition Rating: G+ Used Sampling? No Inspector: [REDACTED] Inspection Source: InstallDate Inspection Comments: Original Inspection			
2004 B301004 FLASHINGS & TRIM Flashings - Cap	B30 ROOFING	B3010 ROOF COVERINGS	506 (LF)
Last Inspection Date: 07-Jan-2020 Condition Rating: A+ Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
2004 B301004 FLASHINGS & TRIM General	B30 ROOFING	B3010 ROOF COVERINGS	170 (LF)
Last Inspection Date: 07-Jan-2020 Condition Rating: A Used Sampling? No Inspector: [REDACTED] Paint Rating: A Inspection Source: Inspection Inspection Comments:			
2004 B301005 GUTTERS & DOWNSPOUTS Downspouts	B30 ROOFING	B3010 ROOF COVERINGS	159 (LF)
Last Inspection Date: 07-Jan-2020 Condition Rating: A+ Used Sampling? No Inspector: [REDACTED] Paint Rating: A Inspection Source: Inspection Inspection Comments:			
2004 B301005 GUTTERS & DOWNSPOUTS Gutters	B30 ROOFING	B3010 ROOF COVERINGS	83 (LF)
Last Inspection Date: 07-Jan-2020 Condition Rating: A+ Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
2004 B301006 ROOF OPENINGS AND SUPPORTS Skylights	B30 ROOFING	B3010 ROOF COVERINGS	600 (SF)



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? Inspection Source:	No Inspection
2004 B301090 OTHER ROOFING Walkway Protection	B30 ROOFING	B3010 ROOF COVERINGS	222 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? Inspection Source:	No Inspection
2004 C101001 FIXED PARTITIONS Wall - Plaster w/Stud	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	16,400 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G- Paint Rating: A	Used Sampling? Inspection Source:	No Inspection
2004 C102001 STANDARD INTERIOR DOORS Metal Door	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	17 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? Inspection Source:	No Inspection
2004 C102002 GLAZED INTERIOR DOORS General	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	2 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? Inspection Source:	No Inspection
2004 C102003 FIRE DOORS Fire Door - Swinging	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	2 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? Inspection Source:	No Inspection
2004 C103002 TOILET & BATH ACCESSORIES General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	6 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? Inspection Source:	No Inspection



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
2004 C103003 MARKER BOARDS & TACK BOARDS General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	29 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2004 C103005 LOCKERS General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	110 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2004 C103008 COUNTERS Wood	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	77 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2004 C103009 CABINETS Other	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	345 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2004 C103010 CASEWORK General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	78 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2004 C201001 INTERIOR AND EXTERIOR STAIRS Exterior	C20 STAIRS	C2010 STAIR CONSTRUCTION	2 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2004 C201001 INTERIOR AND EXTERIOR STAIRS Interior	C20 STAIRS	C2010 STAIR CONSTRUCTION	1 (EA)



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2004 C201090 STAIR HANDRAILS, GUARDRAILS AND	C20 STAIRS	C2010 STAIR CONSTRUCTION	135 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G- Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
2004 C301004 TILE & TERRAZZO WALL FINISHES General	C30 INTERIOR FINISHES	C3010 WALL FINISHES	3,457 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2004 C302001 TILE FLOOR FINISHES Ceramic Tile	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	12,843 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2004 C303001 ACOUSTICAL CEILING TILES & PANELS	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	12,843 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2004 C303005 SUSPENSION SYSTEMS General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	12,843 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2004 D101004 WHEELCHAIR LIFT General	D10 CONVEYING	D1010 ELEVATORS AND LIFTS	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
2004 D201001 WATERCLOSETS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	3 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? Inspection Source:	No Inspection
2004 D201004 SINKS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	2 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? Inspection Source:	No Inspection
2004 D201004 SINKS Stainless	D20 PLUMBING	D2010 PLUMBING FIXTURES	9 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? Inspection Source:	No Inspection
2004 D201006 DRINKING FOUNTAINS AND COOLERS	D20 PLUMBING	D2010 PLUMBING FIXTURES	2 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? Inspection Source:	No Inspection
2004 D202001 PIPES & FITTINGS General	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	3,391 (LF)
Last Inspection Date: 01-Jan-2004 Inspector: XXXXXXXXXX Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? Inspection Source:	No InstallDate
2004 D203001 WASTE PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	5,564 (LF)
Last Inspection Date: 01-Jan-2004 Inspector: XXXXXXXXXX Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? Inspection Source:	No InstallDate
2004 D203002 VENT PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	412 (EA)



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 01-Jan-2004 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? Inspection Source:	No InstallDate
2004 D204001 PIPE & FITTINGS General	D20 PLUMBING	D2040 RAIN WATER DRAINAGE	135 (LF)
Last Inspection Date: 01-Jan-1996 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? Inspection Source:	No InstallDate
2004 D204002 ROOF DRAINS Other	D20 PLUMBING	D2040 RAIN WATER DRAINAGE	9 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? Inspection Source:	No Inspection
2004 D304001 AIR DISTRIBUTION, HEATING & COOLING	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2,163 (LF)
Last Inspection Date: 01-Jan-2004 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? Inspection Source:	No InstallDate
2004 D304003 HOT WATER DISTRIBUTION SYSTEMS General	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	290 (MBH)
Last Inspection Date: 01-Jan-2004 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? Inspection Source:	No InstallDate
2004 D305003 FAN COIL UNITS Duct Mount, 2 Pipe - 1 ton	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	8 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? Inspection Source:	No Inspection
2004 D305006 PACKAGE UNITS A/C Unit, Package Terminal -	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	4 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The units in the ceilings are corroded and noisy.	Condition Rating: A+	Used Sampling? Inspection Source:	No Inspection



Direct Condition Rating Inspection Report by Section



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
2004 D306002 ELECTRONIC CONTROLS General	D30 HVAC	D3060 CONTROLS & INSTRUMENTATION	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2004 D401001 FIRE ALARM DISTRIBUTION Other	D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SYS	11,612 (SF)
Last Inspection Date: 01-Jan-2004 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2004 D404001 SPRINKLERS AND RELEASING DEVICES Wet	D40 FIRE PROTECTION	D4040 SPRINKLERS	12,612 (SF)
Last Inspection Date: 01-Jan-2004 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2004 D502001 BRANCH WIRING General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	11,612 (SF)
Last Inspection Date: 01-Jan-2004 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2004 D502002 LIGHTING EQUIPMENT Exit Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	5 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2004 D502002 LIGHTING EQUIPMENT Exterior Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	8 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2004 D502002 LIGHTING EQUIPMENT General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	11,612 (SF)



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2004 D503002 PUBLIC ADDRESS SYSTEMS 6 outlets	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2004 D503003 INTERCOMMUNICATIONS SYSTEMS 6 stations	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2004 D509002 EMERGENCY LIGHTING & POWER General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	11,612 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2004 D509002 EMERGENCY LIGHTING & POWER	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2004 D509003 GROUNDING SYSTEMS General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	1 (EA)
Last Inspection Date: 01-Jan-1996 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2004 A B201004 PARAPETS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	616 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
2004 A B301002 LOW SLOPE ROOF SYSTEMS Modified	B30 ROOFING	B3010 ROOF COVERINGS	7,025 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2004 A B301004 FLASHINGS & TRIM Flashings - Base	B30 ROOFING	B3010 ROOF COVERINGS	180 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2004 A B301004 FLASHINGS & TRIM Flashings - Flashing	B30 ROOFING	B3010 ROOF COVERINGS	19 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2004 B B201004 PARAPETS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	325 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2004 B B301002 LOW SLOPE ROOF SYSTEMS Modified	B30 ROOFING	B3010 ROOF COVERINGS	6,640 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2004 B B301004 FLASHINGS & TRIM Flashings - Base	B30 ROOFING	B3010 ROOF COVERINGS	326 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2004 B B301004 FLASHINGS & TRIM Flashings - Flashing	B30 ROOFING	B3010 ROOF COVERINGS	5 (EA)



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 07-Jan-2020 Condition Rating: A+ Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
2004 CH-435 D303001 CHILLED WATER SYSTEMS Chiller,	D30 HVAC	D3030 COOLING GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 07-Jan-2020 Condition Rating: R Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments: The chiller has severe fin damage and corrosion.			
2004 EF-190 D304007 EXHAUST SYSTEMS Fan System, Roof	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 07-Jan-2020 Condition Rating: A Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
2004 ROOM 145 D501004 PANELBOARDS Main lugs, 120/240	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1 (EA)
Last Inspection Date: 07-Jan-2020 Condition Rating: R+ Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments: The panelboard is discolored and has minor corrosion on the switches.			
2013 B201001 EXTERIOR CLOSURE Stone Veneer w/CMU	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	265 (SF)
Last Inspection Date: 07-Jan-2020 Condition Rating: G- Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
2013 B201001 EXTERIOR CLOSURE Stucco	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	8,112 (SF)
Last Inspection Date: [REDACTED] Condition Rating: G- Used Sampling? No Inspector: [REDACTED] Paint Rating: A+ Inspection Source: Inspection Inspection Comments:			
2013 B201005 EXTERIOR LOUVERS & SCREENS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	10 (SF)
Last Inspection Date: 07-Jan-2020 Condition Rating: G- Used Sampling? No Inspector: [REDACTED] Paint Rating: G- Inspection Source: Inspection Inspection Comments:			



Direct Condition Rating Inspection Report by Section



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
2013 B201006 BALCONY WALLS & HANDRAILS Handrailing	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	51 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+ Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
2013 B201007 EXTERIOR SOFFITS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	607 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G- Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
2013 B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1,500 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 B202001 WINDOWS Steel Windows	B20 EXTERIOR ENCLOSURE	B2020 EXTERIOR WINDOWS	15 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2013 B203001 SOLID DOORS Steel	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2013 B203090 OTHER EXTERIOR SPECIALTY DOORS	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	10 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2013 B301001 STEEP SLOPE ROOF SYSTEMS Clay Tile	B30 ROOFING	B3010 ROOF COVERINGS	1,032 (SF)



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	B30 ROOFING	B3010 ROOF COVERINGS	7,125 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2013 B301003 ROOF INSULATION & FILL General	B30 ROOFING	B3010 ROOF COVERINGS	8,157 (SF)
Last Inspection Date: 01-Jan-2013 Inspector: XXXXXXXXXX Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2013 B301004 FLASHINGS & TRIM Flashings - Base	B30 ROOFING	B3010 ROOF COVERINGS	340 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2013 B301004 FLASHINGS & TRIM Flashings - Cap	B30 ROOFING	B3010 ROOF COVERINGS	340 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2013 B301004 FLASHINGS & TRIM Flashings - Flashing	B30 ROOFING	B3010 ROOF COVERINGS	23 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2013 B301005 GUTTERS & DOWNSPOUTS Downspouts	B30 ROOFING	B3010 ROOF COVERINGS	212 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
2013 C101001 FIXED PARTITIONS Wall - Drywall w/Stud	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	1,050 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G- Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
2013 C101001 FIXED PARTITIONS Wall - Plaster w/Stud	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	12,500 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G- Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
2013 C102001 STANDARD INTERIOR DOORS Metal Door	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	22 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 C102003 FIRE DOORS Fire Door - Swinging	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	17 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 C103002 TOILET & BATH ACCESSORIES General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	11 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2013 C103003 MARKER BOARDS & TACK BOARDS General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	11 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2013 C103008 COUNTERS Wood	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	35 (LF)



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 C103009 CABINETS Other	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	39 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 C103010 CASEWORK General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	110 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 C201001 INTERIOR AND EXTERIOR STAIRS Exterior	C20 STAIRS	C2010 STAIR CONSTRUCTION	2 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2013 C201001 INTERIOR AND EXTERIOR STAIRS Interior	C20 STAIRS	C2010 STAIR CONSTRUCTION	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 C201090 STAIR HANDRAILS, GUARDRAILS AND	C20 STAIRS	C2010 STAIR CONSTRUCTION	135 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G- Paint Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 C301004 TILE & TERRAZZO WALL FINISHES General	C30 INTERIOR FINISHES	C3010 WALL FINISHES	1,940 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
2013 C302001 TILE FLOOR FINISHES Ceramic Tile	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	7,111 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 C302004 RESILIENT FLOOR FINISHES Composition	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	2,800 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 C303001 ACOUSTICAL CEILING TILES & PANELS	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	7,805 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 C303002 GYPSUM WALLBOARD CEILING FINISHES	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	200 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G- Paint Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 C303005 SUSPENSION SYSTEMS General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	7,805 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 D101002 PASSENGER ELEVATORS Hydraulic Elevators -	D10 CONVEYING	D1010 ELEVATORS AND LIFTS	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 D201001 WATERCLOSETS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	6 (EA)



Direct Condition Rating Inspection Report by Section



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 D201004 SINKS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	5 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 D201004 SINKS Stainless	D20 PLUMBING	D2010 PLUMBING FIXTURES	2 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 D201005 SHOWERS/TUBS Shower	D20 PLUMBING	D2010 PLUMBING FIXTURES	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 D201006 DRINKING FOUNTAINS AND COOLERS	D20 PLUMBING	D2010 PLUMBING FIXTURES	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 D202001 PIPES & FITTINGS General	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	4,370 (LF)
Last Inspection Date: 01-Jan-2013 Inspector: XXXXXXXXXX Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2013 D202003 DOMESTIC WATER EQUIPMENT Booster Pump	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
2013 D203001 WASTE PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	7,169 (LF)
Last Inspection Date: 01-Jan-2013 Condition Rating: G+ Used Sampling? No Inspector: Inspection Source: InstallDate Inspection Comments: Original Inspection			
2013 D203002 VENT PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	531 (EA)
Last Inspection Date: 01-Jan-2013 Condition Rating: G+ Used Sampling? No Inspector: Inspection Source: InstallDate Inspection Comments: Original Inspection			
2013 D204001 PIPE & FITTINGS General	D20 PLUMBING	D2040 RAIN WATER DRAINAGE	90 (LF)
Last Inspection Date: 01-Jan-2013 Condition Rating: G+ Used Sampling? No Inspector: Inspection Source: InstallDate Inspection Comments: Original Inspection			
2013 D204002 ROOF DRAINS Other	D20 PLUMBING	D2040 RAIN WATER DRAINAGE	6 (EA)
Last Inspection Date: 07-Jan-2020 Condition Rating: G- Used Sampling? No Inspector: Inspection Source: Inspection Inspection Comments:			
2013 D302004 AUXILIARY EQUIPMENT Expansion Tank - 15	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	3 (EA)
Last Inspection Date: 07-Jan-2020 Condition Rating: G- Used Sampling? No Inspector: Inspection Source: Inspection Inspection Comments:			
2013 D304001 AIR DISTRIBUTION, HEATING & COOLING	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	374 (LF)
Last Inspection Date: 01-Jan-2013 Condition Rating: G+ Used Sampling? No Inspector: Inspection Source: InstallDate Inspection Comments: Original Inspection			
2013 D304003 HOT WATER DISTRIBUTION SYSTEMS General	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	37 (MBH)



Direct Condition Rating Inspection Report by Section



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 01-Jan-1996 Inspector: Inspection Comments: Original Inspection		Condition Rating: G+ Used Sampling? No Inspection Source: InstallDate	
2013 D304003 HOT WATER DISTRIBUTION SYSTEMS Heat	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:		Condition Rating: G- Used Sampling? No Inspection Source: Inspection	
2013 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	6 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:		Condition Rating: G- Used Sampling? No Inspection Source: Inspection	
2013 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 2 ton	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	5 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:		Condition Rating: A Used Sampling? No Inspection Source: Inspection	
2013 D305006 PACKAGE UNITS A/C Unit, Package Terminal -	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	4 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:		Condition Rating: G- Used Sampling? No Inspection Source: Inspection	
2013 D306002 ELECTRONIC CONTROLS General	D30 HVAC	D3060 CONTROLS & INSTRUMENTATION	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:		Condition Rating: A+ Used Sampling? No Inspection Source: Inspection	
2013 D401001 FIRE ALARM DISTRIBUTION Other	D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SY\$	14,963 (SF)
Last Inspection Date: 01-Jan-2013 Inspector: Inspection Comments: Original Inspection		Condition Rating: G+ Used Sampling? No Inspection Source: InstallDate	



Direct Condition Rating Inspection Report by Section



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
2013 D404001 SPRINKLERS AND RELEASING DEVICES Wet	D40 FIRE PROTECTION	D4040 SPRINKLERS	904 (SF)
Last Inspection Date: 01-Jan-1996 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2013 D501002 SERVICE ENTRANCE EQUIPMENT Electrical	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 D502001 BRANCH WIRING General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	14,963 (SF)
Last Inspection Date: 01-Jan-2013 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2013 D502002 LIGHTING EQUIPMENT Exit Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	10 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 D502002 LIGHTING EQUIPMENT Exterior Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	2 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 D502002 LIGHTING EQUIPMENT General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	12,100 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 D503002 PUBLIC ADDRESS SYSTEMS 6 outlets	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)



Direct Condition Rating Inspection Report by Section



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 D503003 INTERCOMMUNICATIONS SYSTEMS 6 stations	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 D509002 EMERGENCY LIGHTING & POWER General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	14,963 (SF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2013 D509003 GROUNDING SYSTEMS General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	1 (EA)
Last Inspection Date: 01-Jan-1996 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2013 A B201004 PARAPETS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	440 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2013 A B301004 FLASHINGS & TRIM General	B30 ROOFING	B3010 ROOF COVERINGS	124 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2013 AHU-292 D304008 AIR HANDLING UNITS Rooftop - 5000	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments: The air handling unit is corroded.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

Section Description	System	Component	Quantity (UM)
2013 B B301004 FLASHINGS & TRIM General	B30 ROOFING	B3010 ROOF COVERINGS	121 (LF)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+ Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
2013 CHILLER 788 D303001 CHILLED WATER SYSTEMS	D30 HVAC	D3030 COOLING GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments: The chiller has severe fin damage and corrosion.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	
2013 ROOM 18 D501003 INTERIOR DISTRIBUTION	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 ROOM 18 D501004 PANELBOARDS Main lugs, 120/240 V, 400A	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	3 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2013 ROOM MECH 5 D202003 DOMESTIC WATER EQUIPMENT	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
2013 ROOM MECH 5 D202003 DOMESTIC WATER EQUIPMENT	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)
Last Inspection Date: 07-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Section Description	System	Component	Quantity (UM)
1996 B201001 EXTERIOR CLOSURE Brick Veneer w/CMU	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	6,799 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1996 B201001 EXTERIOR CLOSURE Stone Veneer w/CMU	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1,570 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1996 B201001 EXTERIOR CLOSURE Stucco	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	33,610 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 B201004 PARAPETS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	3,900 (LF)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 B201007 EXTERIOR SOFFITS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	5,588 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+ Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 B202001 WINDOWS Aluminum Windows	B20 EXTERIOR ENCLOSURE	B2020 EXTERIOR WINDOWS	214 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments: The windows are at the end of their expected service life. However, they only have minor deterioration of the frame finish, glass and glazing.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 B203090 OTHER EXTERIOR SPECIALTY DOORS	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	37 (EA)



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 10-Jan-2020 Condition Rating: R Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments: Several of the double leaf doors do not coordinate closure if both doors are opened simultaneously, leaving the opening unsecured.			
1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	B30 ROOFING	B3010 ROOF COVERINGS	67,200 (SF)
Last Inspection Date: 10-Jan-2020 Condition Rating: A+ Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
1996 B301003 ROOF INSULATION & FILL General	B30 ROOFING	B3010 ROOF COVERINGS	67,200 (SF)
Last Inspection Date: 01-Jan-1996 Condition Rating: G+ Used Sampling? No Inspector: [REDACTED] Inspection Source: InstallDate Inspection Comments: Original Inspection			
1996 B301004 FLASHINGS & TRIM Flashings - Apron	B30 ROOFING	B3010 ROOF COVERINGS	645 (LF)
Last Inspection Date: 10-Jan-2020 Condition Rating: A+ Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
1996 B301004 FLASHINGS & TRIM Flashings - Base	B30 ROOFING	B3010 ROOF COVERINGS	3,500 (LF)
Last Inspection Date: 10-Jan-2020 Condition Rating: A+ Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
1996 B301004 FLASHINGS & TRIM Flashings - Cap	B30 ROOFING	B3010 ROOF COVERINGS	3,900 (LF)
Last Inspection Date: 10-Jan-2020 Condition Rating: A- Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments: The metal cap flashing is severely corroded at some locations.			
1996 B301004 FLASHINGS & TRIM Flashings - Flashing	B30 ROOFING	B3010 ROOF COVERINGS	72 (EA)
Last Inspection Date: 10-Jan-2020 Condition Rating: A+ Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Section Description	System	Component	Quantity (UM)
1996 B301004 FLASHINGS & TRIM General	B30 ROOFING	B3010 ROOF COVERINGS	3,688 (LF)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+ Paint Rating: G	Used Sampling? No Inspection Source: Inspection	
1996 B301005 GUTTERS & DOWNSPOUTS Downspouts	B30 ROOFING	B3010 ROOF COVERINGS	1,200 (LF)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+ Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 B301006 ROOF OPENINGS AND SUPPORTS Skylights	B30 ROOFING	B3010 ROOF COVERINGS	180 (SF)
Last Inspection Date: [REDACTED] Inspector: [REDACTED] Inspection Comments: The skylight has field application of sealant, evidence of leaks and is generally deteriorated.	Condition Rating: R-	Used Sampling? No Inspection Source: Inspection	
1996 B301090 OTHER ROOFING Walkway Protection	B30 ROOFING	B3010 ROOF COVERINGS	862 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments: The walkway roof panels appear to have been replaced, however, the frame components are heavily corroded.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 C101001 FIXED PARTITIONS Wall - Plaster w/Stud	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	123,500 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G- Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 C101005 INTERIOR WINDOWS General	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	49 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1996 C102001 STANDARD INTERIOR DOORS Metal Door	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	151 (EA)



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 C102003 FIRE DOORS Fire Door - Swinging, Metal	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	24 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 C102006 INTERIOR GATES General	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	6 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 C103001 COMPARTMENTS, CUBICLES & TOILET	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	6 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments: Shower compartments show signs of major staining.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	
1996 C103001 COMPARTMENTS, CUBICLES & TOILET	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	29 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1996 C103002 TOILET & BATH ACCESSORIES General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	129 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 C103003 MARKER BOARDS & TACK BOARDS General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	178 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Section Description	System	Component	Quantity (UM)
1996 C103005 LOCKERS General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	1,237 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
1996 C103006 SHELVING General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	20 (LF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? Inspection Source:	No Inspection
1996 C103008 COUNTERS Laminated Plastic	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	652 (LF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The laminated counter tops are damaged and stained.	Condition Rating: R+	Used Sampling? Inspection Source:	No Inspection
1996 C103009 CABINETS Other	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	1,023 (LF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The cabinets are damaged and deteriorated. Several of the cabinets hardware is missing or malfunctioning.	Condition Rating: R+	Used Sampling? Inspection Source:	No Inspection
1996 C103010 CASEWORK General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	37 (LF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The casework is damaged and is showing signs of deterioration.	Condition Rating: A-	Used Sampling? Inspection Source:	No Inspection
1996 C103014 ENTRANCE FLOOR GRILLES AND MATS	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	115 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? Inspection Source:	No Inspection
1996 C201001 INTERIOR AND EXTERIOR STAIRS Exterior	C20 STAIRS	C2010 STAIR CONSTRUCTION	2 (EA)



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 C201001 INTERIOR AND EXTERIOR STAIRS Exterior	C20 STAIRS	C2010 STAIR CONSTRUCTION	2 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 C201001 INTERIOR AND EXTERIOR STAIRS Interior	C20 STAIRS	C2010 STAIR CONSTRUCTION	2 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 C301004 TILE & TERRAZZO WALL FINISHES General	C30 INTERIOR FINISHES	C3010 WALL FINISHES	14,346 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 C301006 ACOUSTICAL PANELS ADHERED TO WALLS	C30 INTERIOR FINISHES	C3010 WALL FINISHES	2,558 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments: The acoustic wall panels are worn and discolored.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	
1996 C302001 TILE FLOOR FINISHES Ceramic Tile	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	74,602 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1996 C302003 WOOD FLOORING General	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	14,706 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Section Description	System	Component	Quantity (UM)
1996 C302004 RESILIENT FLOOR FINISHES Composition	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	2,176 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? Inspection Source:	No Inspection
1996 C302005 CARPETING General	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	5,652 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The carpet is worn and is stained in some areas.	Condition Rating: A-	Used Sampling? Inspection Source:	No Inspection
1996 C303001 ACOUSTICAL CEILING TILES & PANELS	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	85,811 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: A large portion of the acoustical ceiling tiles are mismatched, dirty, stained and in poor condition.	Condition Rating: R-	Used Sampling? Inspection Source:	No Inspection
1996 C303005 SUSPENSION SYSTEMS General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	85,811 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The suspension system is misaligned and dirty.	Condition Rating: R-	Used Sampling? Inspection Source:	No Inspection
1996 D201002 URINALS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	14 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
1996 D201004 SINKS Kitchen Sink	D20 PLUMBING	D2010 PLUMBING FIXTURES	7 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The kitchen sinks have minor corrosion.	Condition Rating: A-	Used Sampling? Inspection Source:	No Inspection
1996 D201004 SINKS Laboratory Sink	D20 PLUMBING	D2010 PLUMBING FIXTURES	38 (EA)



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The laboratory sinks are discolored.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 D201004 SINKS Service Sink	D20 PLUMBING	D2010 PLUMBING FIXTURES	4 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The service sinks are corroded and discolored.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 D201004 SINKS Stainless	D20 PLUMBING	D2010 PLUMBING FIXTURES	7 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 D201005 SHOWERS/TUBS Shower	D20 PLUMBING	D2010 PLUMBING FIXTURES	20 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The shower heads and handles have corrosion.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 D201006 DRINKING FOUNTAINS AND COOLERS	D20 PLUMBING	D2010 PLUMBING FIXTURES	7 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The drinking fountains are past their statistical lives and the bubblers are corroded.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 D201090 OTHER PLUMBING FIXTURES Emergency Eye	D20 PLUMBING	D2010 PLUMBING FIXTURES	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The emergency eye wash station is corroded and covered in debris.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 D201090 OTHER PLUMBING FIXTURES Emergency	D20 PLUMBING	D2010 PLUMBING FIXTURES	5 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The emergency showers have minor corrosion.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Section Description	System	Component	Quantity (UM)
1996 D202001 PIPES & FITTINGS General	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	32,449 (LF)
Last Inspection Date: 01-Jan-1996 Condition Rating: G+ Used Sampling? No Inspector: Inspection Source: InstallDate Inspection Comments: Original Inspection			
1996 D203001 WASTE PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	53,232 (LF)
Last Inspection Date: 01-Jan-1996 Condition Rating: G+ Used Sampling? No Inspector: Inspection Source: InstallDate Inspection Comments: Original Inspection			
1996 D203002 VENT PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	3,947 (EA)
Last Inspection Date: 01-Jan-1996 Condition Rating: G+ Used Sampling? No Inspector: Inspection Source: InstallDate Inspection Comments: Original Inspection			
1996 D203003 FLOOR DRAINS General	D20 PLUMBING	D2030 SANITARY WASTE	30 (EA)
Last Inspection Date: 10-Jan-2020 Condition Rating: A- Used Sampling? No Inspector: Inspection Source: Inspection Inspection Comments: The floor drains have minor corrosion.			
1996 D204001 PIPE & FITTINGS General	D20 PLUMBING	D2040 RAIN WATER DRAINAGE	2,070 (LF)
Last Inspection Date: 01-Jan-1996 Condition Rating: G+ Used Sampling? No Inspector: Inspection Source: InstallDate Inspection Comments: Original Inspection			
1996 D204002 ROOF DRAINS Other	D20 PLUMBING	D2040 RAIN WATER DRAINAGE	69 (EA)
Last Inspection Date: 10-Jan-2020 Condition Rating: R Used Sampling? No Inspector: Inspection Source: Inspection Inspection Comments: The roof drains are missing scuppers, clogged, and approaching the end of their statistical lives.			
1996 D304001 AIR DISTRIBUTION, HEATING & COOLING	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	25,700 (LF)



Direct Condition Rating Inspection Report by Section



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 01-Jan-1996 Inspector: Inspection Comments: Original Inspection		Condition Rating: G+ Used Sampling? No Inspection Source: InstallDate	
1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	3,778 (MBH)
Last Inspection Date: 01-Jan-1996 Inspector: Inspection Comments: Original Inspection		Condition Rating: G+ Used Sampling? No Inspection Source: InstallDate	
1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	378 (TON)
Last Inspection Date: 01-Jan-1996 Inspector: Inspection Comments: Original Inspection		Condition Rating: G+ Used Sampling? No Inspection Source: InstallDate	
1996 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	11 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: Inspection Comments: The units were reported as regularly failing and requiring repair.		Condition Rating: R Used Sampling? No Inspection Source: Inspection	
1996 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 2 ton	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	57 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: Inspection Comments:		Condition Rating: A+ Used Sampling? No Inspection Source: Inspection	
1996 D305006 PACKAGE UNITS A/C Unit, Package Terminal -	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: Inspection Comments:		Condition Rating: A+ Used Sampling? No Inspection Source: Inspection	
1996 D306002 ELECTRONIC CONTROLS General	D30 HVAC	D3060 CONTROLS & INSTRUMENTATION	4 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: Inspection Comments:		Condition Rating: A Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Section Description	System	Component	Quantity (UM)
1996 D401001 FIRE ALARM DISTRIBUTION Other	D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SY\$	111,107 (SF)
Last Inspection Date: 01-Jan-1996 Condition Rating: G+ Used Sampling? No Inspector: Inspection Source: InstallDate Inspection Comments: Original Inspection			
1996 D404001 SPRINKLERS AND RELEASING DEVICES Wet	D40 FIRE PROTECTION	D4040 SPRINKLERS	111,107 (SF)
Last Inspection Date: 01-Jan-1996 Condition Rating: G+ Used Sampling? No Inspector: Inspection Source: InstallDate Inspection Comments: Original Inspection			
1996 D501004 PANELBOARDS Main lugs, 50 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	9 (EA)
Last Inspection Date: 10-Jan-2020 Condition Rating: A- Used Sampling? No Inspector: Inspection Source: Inspection Inspection Comments: The panelboards are approaching the end of their service lives and several are discolored.			
1996 D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp,	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	25 (EA)
Last Inspection Date: 10-Jan-2020 Condition Rating: A- Used Sampling? No Inspector: Inspection Source: Inspection Inspection Comments: The panelboards are approaching the end of their statistical lives.			
1996 D501004 PANELBOARDS Main lugs, 120/240 V, 225 amp,	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	2 (EA)
Last Inspection Date: 10-Jan-2020 Condition Rating: A Used Sampling? No Inspector: Inspection Source: Inspection Inspection Comments:			
1996 D501004 PANELBOARDS Main lugs, 125 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	7 (EA)
Last Inspection Date: 10-Jan-2020 Condition Rating: A- Used Sampling? No Inspector: Inspection Source: Inspection Inspection Comments: The panelboards have debris on the switches and are approaching the end of their service lives.			
1996 D502001 BRANCH WIRING General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	111,107 (SF)



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 01-Jan-1996 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? Inspection Source:	No InstallDate
1996 D502002 LIGHTING EQUIPMENT Exit Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	24 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A	Used Sampling? Inspection Source:	No Inspection
1996 D502002 LIGHTING EQUIPMENT Exterior Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	6 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A	Used Sampling? Inspection Source:	No Inspection
1996 D502002 LIGHTING EQUIPMENT General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	111,107 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: Inspection Comments: The lighting equipment is discolored.	Condition Rating: A-	Used Sampling? Inspection Source:	No Inspection
1996 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: Inspection Comments: The public address system is reported to intermittently fail.	Condition Rating: R	Used Sampling? Inspection Source:	No Inspection
1996 D503003 INTERCOMMUNICATIONS SYSTEMS 50 stations	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: Inspection Comments: The age of the intercommunication system is estimated to be at the end of its service life.	Condition Rating: R	Used Sampling? Inspection Source:	No Inspection
1996 D503005 SECURITY SYSTEMS General	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: Inspection Comments: The age of the system is estimated to be at the end of its service life.	Condition Rating: R	Used Sampling? Inspection Source:	No Inspection



Direct Condition Rating Inspection Report by Section



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Section Description	System	Component	Quantity (UM)
1996 D503007 CLOCK & PROGRAM SYSTEMS General	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments: The age of the system is estimated to be at end of its service life.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	
1996 D509002 EMERGENCY LIGHTING & POWER General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	111,107 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments: The emergency lighting is approaching the end of its statistical life.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 D509002 EMERGENCY LIGHTING & POWER	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	3 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 D509003 GROUNDING SYSTEMS General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	1 (EA)
Last Inspection Date: 01-Jan-1996 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1996 A B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1,500 (LF)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments: The sealant caulk is brittle or missing at several locations.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1996 A B301002 LOW SLOPE ROOF SYSTEMS Modified	B30 ROOFING	B3010 ROOF COVERINGS	12,612 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 A B301003 ROOF INSULATION & FILL General	B30 ROOFING	B3010 ROOF COVERINGS	12,612 (SF)



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 01-Jan-2012 Inspector: Inspection Comments: Original Inspection		Condition Rating: G+ Used Sampling? No Inspection Source: InstallDate	
1996 A B301004 FLASHINGS & TRIM Flashings - Base	B30 ROOFING	B3010 ROOF COVERINGS	450 (LF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:		Condition Rating: A+ Used Sampling? No Inspection Source: Inspection	
1996 A B301004 FLASHINGS & TRIM Flashings - Flashing	B30 ROOFING	B3010 ROOF COVERINGS	18 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:		Condition Rating: A+ Used Sampling? No Inspection Source: Inspection	
1996 A B301004 FLASHINGS & TRIM Flashings - Pitch Pans	B30 ROOFING	B3010 ROOF COVERINGS	15 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:		Condition Rating: G- Used Sampling? No Inspection Source: Inspection	
1996 A C103008 COUNTERS Laminated Plastic	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	117 (LF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:		Condition Rating: G Used Sampling? No Inspection Source: Inspection	
1996 A C201090 STAIR HANDRAILS, GUARDRAILS AND	C20 STAIRS	C2010 STAIR CONSTRUCTION	145 (LF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The paint coating on handrails appears to have been refinished since the last visit.		Condition Rating: A+ Paint Rating: A+ Used Sampling? No Inspection Source: Inspection	
1996 A D201001 WATERCLOSETS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	9 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The waterclosets are discolored and have minor corrosion.		Condition Rating: A- Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Section Description	System	Component	Quantity (UM)
1996 A D201004 SINKS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	15 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments: The sinks have minor corrosion on the faucets and piping.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 A D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	23 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 B B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	5,000 (LF)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments: The sealant caulk is brittle or missing at several locations.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1996 B B301004 FLASHINGS & TRIM Flashings - Pitch Pans	B30 ROOFING	B3010 ROOF COVERINGS	10 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1996 B C201090 STAIR HANDRAILS, GUARDRAILS AND	C20 STAIRS	C2010 STAIR CONSTRUCTION	165 (LF)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments: The paint coating on handrails appears to have been refinished since the last visit.	Condition Rating: A+ Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 B D201001 WATERCLOSETS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	31 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1996 B D201004 SINKS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	39 (EA)



Direct Condition Rating Inspection Report by Section



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1996 C B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	167 (LF)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments: The sealant caulk at wall surfaces is brittle or missing.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1996 OUTSIDE D303002 DIRECT EXPANSION SYSTEMS	D30 HVAC	D3030 COOLING GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 PAC-012 D305006 PACKAGE UNITS A/C Unit, Split	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments: The condenser is deteriorated and has severe fin damage.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1996 ROOFTOP D305006 PACKAGE UNITS A/C Unit, Package	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments: The split unit has severe fin damage.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1996 ROOFTOP D305006 PACKAGE UNITS A/C Unit, Split	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments: The condenser has fin damage and corrosion on the unit.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1996 ROOFTOP A D304007 EXHAUST SYSTEMS Fume Hood	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments: The motor of the fume hoods are corroded and the ductwork is cracked.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Section Description	System	Component	Quantity (UM)
1996 ROOFTOP B D304007 EXHAUST SYSTEMS Fume Hood	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	3 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 107 D305006 PACKAGE UNITS A/C Unit, Package	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 112D D305006 PACKAGE UNITS A/C Unit, Split	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 115 D305006 PACKAGE UNITS A/C Unit, Package	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 122D D305006 PACKAGE UNITS A/C Unit,	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 123 D501002 SERVICE ENTRANCE EQUIPMENT	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	4 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 123 D501003 INTERIOR DISTRIBUTION	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	2 (EA)



Direct Condition Rating Inspection Report by Section



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The transformers are approaching the end of their statistical lives.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 123 D501003 INTERIOR DISTRIBUTION	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The transformer is approaching the end of its statistical life.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 123 D501004 PANELBOARDS Main lugs, 200 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 124 D305006 PACKAGE UNITS A/C Unit, Package	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 225 D305006 PACKAGE UNITS A/C Unit, Package	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 226 D501003 INTERIOR DISTRIBUTION	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The transformer shows signs of previous failure.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 226 D501004 PANELBOARDS Main lugs, 200 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The panelboard is approaching the end of its statistical life.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Section Description	System	Component	Quantity (UM)
1996 ROOM 234/235 D202003 DOMESTIC WATER EQUIPMENT	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1996 ROOM M101 D101002 PASSENGER ELEVATORS	D10 CONVEYING	D1010 ELEVATORS AND LIFTS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 SS-046 D305006 PACKAGE UNITS A/C Unit, Package	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 SS-605 D305006 PACKAGE UNITS A/C Unit, Package	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 UTA-1 D304008 AIR HANDLING UNITS Rooftop - 5000	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments: The motor and enclosure of the rooftop unit is deteriorating.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	
1996 UTA-2 D304008 AIR HANDLING UNITS Rooftop - 5000	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments: The motor and enclosure of the rooftop unit is deteriorating.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	
1996 UTA-3 D304008 AIR HANDLING UNITS Rooftop - 5000	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)



Direct Condition Rating Inspection Report by Section



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 10-Jan-2020 Condition Rating: R Used Sampling? No Inspector: Inspection Source: Inspection Inspection Comments: The motor and enclosure of the rooftop unit is deteriorated.			
1996 UTA-4 D304008 AIR HANDLING UNITS Rooftop - 5000	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 10-Jan-2020 Condition Rating: R Used Sampling? No Inspector: Inspection Source: Inspection Inspection Comments: Air handling unit UTA-4 is corroded on the enclosure and the motor.			
1999 C302001 TILE FLOOR FINISHES Marble Tile	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	2,888 (SF)
Last Inspection Date: 10-Jan-2020 Condition Rating: G- Used Sampling? No Inspector: Inspection Source: Inspection Inspection Comments:			
1999 A C103009 CABINETS Other	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	967 (LF)
Last Inspection Date: 10-Jan-2020 Condition Rating: G Used Sampling? No Inspector: Inspection Source: Inspection Inspection Comments:			



Direct Condition Rating Inspection Report by Section



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

Section Description	System	Component	Quantity (UM)
*BRAISING PAN A E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
*BRAISING PAN B E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
*COLD PAN SINGLE BASIN A E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
*COLD PAN SINGLE BASIN B E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
*COLD PAN SINGLE BASIN C E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
*COLD PAN SINGLE BASIN D E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
*DEEP FRYER A E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)



Direct Condition Rating Inspection Report by Section



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
*DEEP FRYER B E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
*DISH MACHINE A E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
*DISH MACHINE B E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
*GRIDDLE A E109002 FOOD SERVICE EQUIPMENT General	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
*GRIDDLE B E109002 FOOD SERVICE EQUIPMENT General	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
*GRIDDLE C E109002 FOOD SERVICE EQUIPMENT General	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection



Direct Condition Rating Inspection Report by Section



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

Section Description	System	Component	Quantity (UM)
*GRIDDLE D E109002 FOOD SERVICE EQUIPMENT General	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
*GRIDDLE E E109002 FOOD SERVICE EQUIPMENT General	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
*HOT CABINET REACH IN 2DR A E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
*HOT CABINET REACH IN 2DR A E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
*HOT CABINET REACH IN 2DR B E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
*KETTLE ELECTRIC A E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
*KETTLE ELECTRIC B E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)



Direct Condition Rating Inspection Report by Section



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
*KETTLE ELECTRIC C E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
*REFRIGERATOR REACH IN 2DR A E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
*REFRIGERATOR REACH IN 2DR B E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
*STEAM COUNTER ELECTRIC MULTI BASIN A E109002 FOOD	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
*STEAM COUNTER ELECTRIC MULTI BASIN B E109002 FOOD	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
*STEAM COUNTER ELECTRIC MULTI BASIN C E109002 FOOD	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection



Direct Condition Rating Inspection Report by Section



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

Section Description	System	Component	Quantity (UM)
*STEAMER 1 DOOR A E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
*STEAMER 1 DOOR B E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: [REDACTED]	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
*STEAMER 1 DOOR C E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
*WALK IN COOLER E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
*WALK IN FREEZER E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 10-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1996 B201001 EXTERIOR CLOSURE Brick Veneer w/CMU	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	4,440 (SF)
Last Inspection Date: 10-Jan-2020	Condition Rating: A	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1996 B201001 EXTERIOR CLOSURE Stone Veneer w/CMU	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	548 (SF)



Direct Condition Rating Inspection Report by Section



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 B201001 EXTERIOR CLOSURE Stucco	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	7,912 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 B201004 PARAPETS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1,500 (LF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 B201006 BALCONY WALLS & HANDRAILS Handrailing	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	240 (LF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The paint coating has been refinished since the last visit.	Condition Rating: A- Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 B201007 EXTERIOR SOFFITS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	623 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 B202001 WINDOWS Steel Windows	B20 EXTERIOR ENCLOSURE	B2020 EXTERIOR WINDOWS	14 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 B203090 OTHER EXTERIOR SPECIALTY DOORS	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	12 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The double leaf door sets do not coordinate closure properly and jam when both doors are opened simultaneously.	Condition Rating: R-	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

Section Description	System	Component	Quantity (UM)
1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	B30 ROOFING	B3010 ROOF COVERINGS	20,930 (SF)
Last Inspection Date: 10-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1996 B301003 ROOF INSULATION & FILL General	B30 ROOFING	B3010 ROOF COVERINGS	20,930 (SF)
Last Inspection Date: 01-Jan-1996	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
Inspector: [REDACTED]			
Inspection Comments: Original Inspection			
1996 B301004 FLASHINGS & TRIM Flashings - Base	B30 ROOFING	B3010 ROOF COVERINGS	1,846 (LF)
Last Inspection Date: 10-Jan-2020	Condition Rating: G-	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1996 B301004 FLASHINGS & TRIM Flashings - Cap	B30 ROOFING	B3010 ROOF COVERINGS	1,522 (LF)
Last Inspection Date: 10-Jan-2020	Condition Rating: G-	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1996 B301004 FLASHINGS & TRIM Flashings - Flashing	B30 ROOFING	B3010 ROOF COVERINGS	231 (EA)
Last Inspection Date: 10-Jan-2020	Condition Rating: G-	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1996 B301004 FLASHINGS & TRIM General	B30 ROOFING	B3010 ROOF COVERINGS	214 (LF)
Last Inspection Date: 10-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]	Paint Rating: A+		
Inspection Comments:			
1996 B301005 GUTTERS & DOWNSPOUTS Downspouts	B30 ROOFING	B3010 ROOF COVERINGS	304 (LF)



Direct Condition Rating Inspection Report by Section



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 C101001 FIXED PARTITIONS Wall - Plaster w/Stud	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	20,140 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G- Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 C101005 INTERIOR WINDOWS Interior Windows	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1996 C101005 INTERIOR WINDOWS Metal Rollup / Coiling	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	32 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The metal roll up windows have areas of rust and discoloration.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	
1996 C102001 STANDARD INTERIOR DOORS Metal Door	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	29 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 C102005 INTERIOR OVERHEAD DOORS Metal	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	2 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 C102090 OTHER INTERIOR SPECIALTY DOORS Cold	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	4 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Support Site

2059 - Naples MS/HS Bldg 2059	Unassigned
-------------------------------	------------

Section Description	System	Component	Quantity (UM)
1996 C103001 COMPARTMENTS, CUBICLES & TOILET	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	14 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? Inspection Source:	No Inspection
1996 C103002 TOILET & BATH ACCESSORIES General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	59 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? Inspection Source:	No Inspection
1996 C103003 MARKER BOARDS & TACK BOARDS General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	3 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? Inspection Source:	No Inspection
1996 C103005 LOCKERS General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	6 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? Inspection Source:	No Inspection
1996 C103006 SHELVING General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	52 (LF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? Inspection Source:	No Inspection
1996 C201090 STAIR HANDRAILS, GUARDRAILS AND	C20 STAIRS	C2010 STAIR CONSTRUCTION	90 (LF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The metal ladders have minor deterioration.	Condition Rating: A+ Paint Rating: A	Used Sampling? Inspection Source:	No Inspection
1996 C301002 PLASTER WALL FINISHES General	C30 INTERIOR FINISHES	C3010 WALL FINISHES	22,781 (SF)



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The interior wall finishes show signs of stains and damage.		Condition Rating: G- Paint Rating: R	Used Sampling? No Inspection Source: Inspection
1996 C301004 TILE & TERRAZZO WALL FINISHES General	C30 INTERIOR FINISHES	C3010 WALL FINISHES	9,060 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:		Condition Rating: G- Paint Rating:	Used Sampling? No Inspection Source: Inspection
1996 C302001 TILE FLOOR FINISHES Ceramic Tile	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	11,335 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:		Condition Rating: G- Paint Rating:	Used Sampling? No Inspection Source: Inspection
1996 C302004 RESILIENT FLOOR FINISHES Composition	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	1,900 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The resilient sheeting is badly stained and damaged near the stage.		Condition Rating: R- Paint Rating:	Used Sampling? No Inspection Source: Inspection
1996 C302006 MASONRY & STONE FLOORING Quarry Tile	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	3,200 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:		Condition Rating: G- Paint Rating:	Used Sampling? No Inspection Source: Inspection
1996 C303001 ACOUSTICAL CEILING TILES & PANELS	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	13,802 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The acoustical tiles are stained and dirty.		Condition Rating: R Paint Rating:	Used Sampling? No Inspection Source: Inspection
1996 C303003 PLASTER CEILING FINISHES General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	3,797 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:		Condition Rating: G- Paint Rating: A	Used Sampling? No Inspection Source: Inspection



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

Section Description	System	Component	Quantity (UM)
1996 C303005 SUSPENSION SYSTEMS General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	13,802 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The suspension system is bent and dirty.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	
1996 D201002 URINALS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	6 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The urinals are approaching the end of their statistical lives.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 D201004 SINKS Kitchen Sink	D20 PLUMBING	D2010 PLUMBING FIXTURES	2 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 D201006 DRINKING FOUNTAINS AND COOLERS	D20 PLUMBING	D2010 PLUMBING FIXTURES	3 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The drinking fountains have corrosion on the piping and mouthpieces.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 D202001 PIPES & FITTINGS General	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	6,113 (LF)
Last Inspection Date: 01-Jan-1996 Inspector: XXXXXXXXXX Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1996 D202002 VALVES & HYDRANTS Backflow Preventer - 3"	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	2 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The backflow preventer is deteriorated.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 D202003 DOMESTIC WATER EQUIPMENT Storage Tank -	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	2 (EA)



Direct Condition Rating Inspection Report by Section



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 D203001 WASTE PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	3,056 (LF)
Last Inspection Date: 01-Jan-1996 Inspector: XXXXXXXXXX Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1996 D203002 VENT PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	743 (EA)
Last Inspection Date: 01-Jan-1996 Inspector: XXXXXXXXXX Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1996 D203003 FLOOR DRAINS General	D20 PLUMBING	D2030 SANITARY WASTE	18 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The floor drains and drain grates are corroded.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 D204001 PIPE & FITTINGS General	D20 PLUMBING	D2040 RAIN WATER DRAINAGE	390 (LF)
Last Inspection Date: 01-Jan-1996 Inspector: XXXXXXXXXX Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1996 D204002 ROOF DRAINS Other	D20 PLUMBING	D2040 RAIN WATER DRAINAGE	26 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The roof drains are corroded and clogged.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 D304001 AIR DISTRIBUTION, HEATING & COOLING	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	3,899 (LF)
Last Inspection Date: 01-Jan-1996 Inspector: XXXXXXXXXX Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	



Direct Condition Rating Inspection Report by Section



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

Section Description	System	Component	Quantity (UM)
1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	523 (MBH)
Last Inspection Date: 01-Jan-1996 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	52 (TON)
Last Inspection Date: 01-Jan-1996 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1996 D306002 ELECTRONIC CONTROLS General	D30 HVAC	D3060 CONTROLS & INSTRUMENTATION	11 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 D401001 FIRE ALARM DISTRIBUTION Other	D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SY	20,930 (SF)
Last Inspection Date: 01-Jan-1996 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1996 D404001 SPRINKLERS AND RELEASING DEVICES Wet	D40 FIRE PROTECTION	D4040 SPRINKLERS	20,930 (SF)
Last Inspection Date: 01-Jan-1996 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1996 D409004 HOOD & DUCT FIRE PROTECTION General	D40 FIRE PROTECTION	D4090 OTHER FIRE PROTECTION SYSTEI	2 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp,	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	2 (EA)



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The panelboards are approaching the end of their statistical lives.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 D501004 PANELBOARDS Switchgear - 800 Amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The panelboards show signs of failure.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1996 D502001 BRANCH WIRING General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	20,930 (SF)
Last Inspection Date: 01-Jan-1996 Inspector: XXXXXXXXXX Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1996 D502002 LIGHTING EQUIPMENT Exit Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	6 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 D502002 LIGHTING EQUIPMENT Exterior Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	3 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 D502002 LIGHTING EQUIPMENT General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	20,930 (SF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 D503002 PUBLIC ADDRESS SYSTEMS 6 outlets	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The age of the system is estimated to be at the end of its service life. It was reported that the public address system is working intermittently.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

Section Description	System	Component	Quantity (UM)
1996 D503003 INTERCOMMUNICATIONS SYSTEMS 6 stations	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 10-Jan-2020 Condition Rating: R Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments: The age of the system is estimated to be at the end of its service life. It was reported that the intercommunication system is working intermittently.			
1996 D503007 CLOCK & PROGRAM SYSTEMS General	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 10-Jan-2020 Condition Rating: R Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments: The age of the system is estimated to be at the end of its service life.			
1996 D509002 EMERGENCY LIGHTING & POWER General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	20,930 (SF)
Last Inspection Date: 10-Jan-2020 Condition Rating: A- Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments: The emergency lights are approaching the end of their statistical lives.			
1996 D509003 GROUNDING SYSTEMS General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	1 (EA)
Last Inspection Date: 01-Jan-1996 Condition Rating: G+ Used Sampling? No Inspector: [REDACTED] Inspection Source: InstallDate Inspection Comments: Original Inspection			
1996 A B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	350 (LF)
Last Inspection Date: 10-Jan-2020 Condition Rating: A- Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments: The sealant caulk at door and window perimeters is brittle or missing.			
1996 A B301004 FLASHINGS & TRIM Flashings - Apron	B30 ROOFING	B3010 ROOF COVERINGS	308 (LF)
Last Inspection Date: 10-Jan-2020 Condition Rating: A+ Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
1996 A D201001 WATERCLOSETS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	9 (EA)



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The waterclosets are approaching the end of their service lives and have minor corrosion.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1996 A D201004 SINKS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	11 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The sinks have corrosion on the piping and faucets.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1996 A D302004 AUXILIARY EQUIPMENT Expansion Tank - 40	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	3 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 A D304006 CHILLED WATER DISTRIBUTION SYSTEMS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	3 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The pumps are beyond their service life and are corroded.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1996 A D305001 UNIT VENTILATORS Air Curtain	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	3 (LF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The air curtain is beyond its statistical life.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 AHU-056 D304008 AIR HANDLING UNITS Rooftop - 10000	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The air handling unit is deteriorating on the motor, belt, and enclosure.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	
1996 AHU-061 D304008 AIR HANDLING UNITS Rooftop - 10000	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The air handling unit has corrosion on the piping and enclosure.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

Section Description	System	Component	Quantity (UM)
1996 AHU-062 D304008 AIR HANDLING UNITS Rooftop - 10000	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 10-Jan-2020 Condition Rating: R Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments: The air handling unit has corrosion on the piping and enclosure.			
1996 B B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	250 (LF)
Last Inspection Date: 10-Jan-2020 Condition Rating: A- Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments: The sealant caulk at door and window perimeters is brittle or missing.			
1996 B B301004 FLASHINGS & TRIM Flashings - Apron	B30 ROOFING	B3010 ROOF COVERINGS	153 (LF)
Last Inspection Date: 10-Jan-2020 Condition Rating: A+ Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
1996 B D201001 WATERCLOSETS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	14 (EA)
Last Inspection Date: 10-Jan-2020 Condition Rating: G Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
1996 B D201004 SINKS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	16 (EA)
Last Inspection Date: 10-Jan-2020 Condition Rating: G Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
1996 B D302004 AUXILIARY EQUIPMENT Expansion Tank - 40	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	2 (EA)
Last Inspection Date: 10-Jan-2020 Condition Rating: A+ Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
1996 B D304003 HOT WATER DISTRIBUTION SYSTEMS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	6 (EA)



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 B D304006 CHILLED WATER DISTRIBUTION SYSTEMS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	6 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The pumps are approaching the end of their statistical lives and have minor corrosion on the piping.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 B D305001 UNIT VENTILATORS Air Curtain	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	3 (LF)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The air curtain is beyond its statistical life.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 C D304003 HOT WATER DISTRIBUTION SYSTEMS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	4 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 C D304006 CHILLED WATER DISTRIBUTION SYSTEMS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	3 (EA)
Last Inspection Date: 10-Jan- XXXX Inspector: XXXXXXXXXX Inspection Comments: The circulating pumps are corroded on the piping and motors.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 EF-121/97 D304007 EXHAUST SYSTEMS Fan System,	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The exhaust fan is corroded on the enclosure and ductwork.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1996 ROOFTOP D304007 EXHAUST SYSTEMS Fan System,	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The exhaust fan is corroded.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

Section Description	System	Component	Quantity (UM)
1996 ROOFTOP D304007 EXHAUST SYSTEMS Fan System,	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments: The exhaust fans are beyond their service life and the units are corroded.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1996 ROOFTOP D306002 ELECTRONIC CONTROLS General	D30 HVAC	D3060 CONTROLS & INSTRUMENTATION	5 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments: The electronic controls are corroded.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 ROOFTOP A D303001 CHILLED WATER SYSTEMS Chiller,	D30 HVAC	D3030 COOLING GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments: The chiller has fin damage and minor corrosion.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 ROOFTOP B D303001 CHILLED WATER SYSTEMS	D30 HVAC	D3030 COOLING GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOFTOP C D303001 CHILLED WATER SYSTEMS	D30 HVAC	D3030 COOLING GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments: The chiller has fin damage and minor corrosion.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 ROOFTOP D D303001 CHILLED WATER SYSTEMS	D30 HVAC	D3030 COOLING GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments: The chiller has fin damage and minor corrosion.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 128 D305006 PACKAGE UNITS A/C Unit, Package	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	2 (EA)



Direct Condition Rating Inspection Report by Section



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 137D D305006 PACKAGE UNITS A/C Unit,	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOM 138B D501004 PANELBOARDS Main lugs, 200	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	2 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOM M101 D202003 DOMESTIC WATER EQUIPMENT	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	2 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The water pumps are deteriorating.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1996 ROOM M101 D202003 DOMESTIC WATER EQUIPMENT	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOM M101 D202003 DOMESTIC WATER EQUIPMENT	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOM M101 D304003 HOT WATER DISTRIBUTION	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

Section Description	System	Component	Quantity (UM)
1996 ROOM M101 D304006 CHILLED WATER DISTRIBUTION	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	3 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1996 ROOM M101 A D302004 AUXILIARY EQUIPMENT	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	5 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOM M101 B D302004 AUXILIARY EQUIPMENT	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	2 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1996 ROOM M101 BOILER 1 D302001 BOILERS Gas, Hot Water	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments: The boiler is beyond its statistical life and has severe corrosion on the unit.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1996 ROOM M101 BOILER 2 D302001 BOILERS Gas, Hot Water	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments: The boiler is beyond its statistical life and has severe corrosion on the unit.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1996 ROOM M101 C D302004 AUXILIARY EQUIPMENT	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1996 ROOM M102 D202003 DOMESTIC WATER EQUIPMENT	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOM M102 D302004 AUXILIARY EQUIPMENT	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	3 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1996 ROOM M102 D304003 HOT WATER DISTRIBUTION	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOM M102 A D302004 AUXILIARY EQUIPMENT	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	2 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1996 ROOM M102 B D302004 AUXILIARY EQUIPMENT	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	4 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOM M102 B D304003 HOT WATER DISTRIBUTION	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1996 ROOM M102 BOILER-2058A D302001 BOILERS Gas, Hot	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 10-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The boiler has corrosion on the unit and piping.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	



"identification only"

Direct Condition Rating Inspection Report by Section



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

Section Description	System	Component	Quantity (UM)
---------------------	--------	-----------	---------------

1996 ROOM M102 BOILER-2058B D302001 BOILERS Gas, Hot	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1 (EA)
--	----------	-------------------------------	--------

Last Inspection Date: 10-Jan-2020

Condition Rating: R+

Used Sampling?

No

Inspector:



Inspection Source:

Inspection

Inspection Comments: The boiler is beyond its service life and is deteriorated.

Appendix H

"identification only"

System Inventory Report



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1996 B201001 EXTERIOR CLOSURE Brick Veneer w/CMU Backup	3,800 (SF)	1996	
	B2010 EXTERIOR WALLS	1996 B201001 EXTERIOR CLOSURE Stucco	21,900 (SF)	1996	2013
	B2010 EXTERIOR WALLS	1996 B201004 PARAPETS General	1,738 (LF)	2016	
	B2010 EXTERIOR WALLS	1996 B201006 BALCONY WALLS & HANDRAILS Handrailing	174 (LF)	1996	2013
	B2010 EXTERIOR WALLS	1996 B201007 EXTERIOR SOFFITS General	2,177 (SF)	1996	
	B2010 EXTERIOR WALLS	1996 A B201001 EXTERIOR CLOSURE Stone Veneer w/CMU Backup	805 (SF)	1996	2013
	B2010 EXTERIOR WALLS	1996 A B201010 EXTERIOR JOINT SEALANT General	92 (LF)	1996	
	B2010 EXTERIOR WALLS	1996 B B201001 EXTERIOR CLOSURE Stone Veneer w/CMU Backup	148 (SF)	1996	
	B2010 EXTERIOR WALLS	1996 B B201010 EXTERIOR JOINT SEALANT General	5,000 (LF)	1996	
	B2010 EXTERIOR WALLS	2004 B201001 EXTERIOR CLOSURE Brick Veneer w/CMU Backup	1,216 (SF)	2004	
	B2010 EXTERIOR WALLS	2004 B201001 EXTERIOR CLOSURE Stone Veneer w/CMU Backup	288 (SF)	2004	
	B2010 EXTERIOR WALLS	2004 B201001 EXTERIOR CLOSURE Stucco	6,136 (SF)	2004	2013
	B2010 EXTERIOR WALLS	2004 B201006 BALCONY WALLS & HANDRAILS Handrailing	75 (LF)	2004	2013
	B2010 EXTERIOR WALLS	2004 B201007 EXTERIOR SOFFITS General	774 (SF)	2004	2013
	B2010 EXTERIOR WALLS	2004 B201010 EXTERIOR JOINT SEALANT General	1,500 (LF)	1996	
	B2010 EXTERIOR WALLS	2004 A B201004 PARAPETS General	616 (LF)	2016	
	B2010 EXTERIOR WALLS	2004 B B201004 PARAPETS General	325 (LF)	2016	
	B2010 EXTERIOR WALLS	2013 B201001 EXTERIOR CLOSURE Stone Veneer w/CMU Backup	265 (SF)	2013	
	B2010 EXTERIOR WALLS	2013 B201001 EXTERIOR CLOSURE Stucco	8,112 (SF)	2013	2013
	B2010 EXTERIOR WALLS	2013 B201005 EXTERIOR LOUVERS & SCREENS General	10 (SF)	2013	2013
	B2010 EXTERIOR WALLS	2013 B201006 BALCONY WALLS & HANDRAILS Handrailing	51 (LF)	2013	2013
	B2010 EXTERIOR WALLS	2013 B201007 EXTERIOR SOFFITS General	607 (SF)	1996	2013
	B2010 EXTERIOR WALLS	2013 B201010 EXTERIOR JOINT SEALANT General	1,500 (LF)	2013	
	B2010 EXTERIOR WALLS	2013 A B201004 PARAPETS General	440 (LF)	2013	
	B2020 EXTERIOR WINDOWS	1996 A B202001 WINDOWS Steel Windows	149 (EA)	1996	
	B2020 EXTERIOR WINDOWS	1996 B B202001 WINDOWS Steel Windows	29 (EA)	1996	
	B2020 EXTERIOR WINDOWS	2004 B202001 WINDOWS Steel Windows	27 (EA)	2004	
	B2020 EXTERIOR WINDOWS	2013 B202001 WINDOWS Steel Windows	15 (EA)	2013	
	B2030 EXTERIOR DOORS	1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door	34 (EA)	1996	
	B2030 EXTERIOR DOORS	2004 B203001 SOLID DOORS Steel	1 (EA)	2004	
	B2030 EXTERIOR DOORS	2004 B203002 GLAZED DOORS General	2 (EA)	2004	
	B2030 EXTERIOR DOORS	2004 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door	10 (EA)	2004	
	B2030 EXTERIOR DOORS	2013 B203001 SOLID DOORS Steel	1 (EA)	2013	
	B2030 EXTERIOR DOORS	2013 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door	10 (EA)	2013	



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
B30 ROOFING	B3010 ROOF COVERINGS	1996 B301001 STEEP SLOPE ROOF SYSTEMS Clay Tile	2,376 (SF)	1996	
	B3010 ROOF COVERINGS	1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	60,131 (SF)	2016	
	B3010 ROOF COVERINGS	1996 B301003 ROOF INSULATION & FILL General	62,507 (SF)	1996	
	B3010 ROOF COVERINGS	1996 B301004 FLASHINGS & TRIM Flashings - Base	3,655 (LF)	2016	
	B3010 ROOF COVERINGS	1996 B301004 FLASHINGS & TRIM Flashings - Cap	3,371 (LF)	2016	
	B3010 ROOF COVERINGS	1996 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	76 (EA)	2016	
	B3010 ROOF COVERINGS	1996 B301005 GUTTERS & DOWNSPOUTS Downspouts	1,141 (LF)	1996	
	B3010 ROOF COVERINGS	1996 B301006 ROOF OPENINGS AND SUPPORTS Skylights	180 (SF)	1996	
	B3010 ROOF COVERINGS	1996 B301090 OTHER ROOFING Walkway Protection	552 (SF)	2016	
	B3010 ROOF COVERINGS	1996 A B301004 FLASHINGS & TRIM Flashings - Apron	248 (LF)	2016	
	B3010 ROOF COVERINGS	1996 A B301004 FLASHINGS & TRIM General	749 (LF)	2016	
	B3010 ROOF COVERINGS	1996 B B301004 FLASHINGS & TRIM Flashings - Apron	248 (LF)	1996	
	B3010 ROOF COVERINGS	1996 B B301004 FLASHINGS & TRIM General	746 (LF)	1996	2013
	B3010 ROOF COVERINGS	2004 B301003 ROOF INSULATION & FILL General	13,665 (SF)	2004	
	B3010 ROOF COVERINGS	2004 B301004 FLASHINGS & TRIM Flashings - Cap	506 (LF)	2004	
	B3010 ROOF COVERINGS	2004 B301004 FLASHINGS & TRIM General	170 (LF)	2004	2013
	B3010 ROOF COVERINGS	2004 B301005 GUTTERS & DOWNSPOUTS Downspouts	159 (LF)	2004	2013
	B3010 ROOF COVERINGS	2004 B301005 GUTTERS & DOWNSPOUTS Gutters	83 (LF)	1996	
	B3010 ROOF COVERINGS	2004 B301006 ROOF OPENINGS AND SUPPORTS Skylights	600 (SF)	2004	
	B3010 ROOF COVERINGS	2004 B301090 OTHER ROOFING Walkway Protection	222 (SF)	2004	
	B3010 ROOF COVERINGS	2004 A B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	7,025 (SF)	2004	
	B3010 ROOF COVERINGS	2004 A B301004 FLASHINGS & TRIM Flashings - Base	180 (LF)	2004	
	B3010 ROOF COVERINGS	2004 A B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	19 (EA)	2004	
	B3010 ROOF COVERINGS	2004 B B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	6,640 (SF)	2004	
	B3010 ROOF COVERINGS	2004 B B301004 FLASHINGS & TRIM Flashings - Base	326 (LF)	2004	
	B3010 ROOF COVERINGS	2004 B B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	5 (EA)	2004	
	B3010 ROOF COVERINGS	2013 B301001 STEEP SLOPE ROOF SYSTEMS Clay Tile	1,032 (SF)	2013	
	B3010 ROOF COVERINGS	2013 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	7,125 (SF)	2013	
	B3010 ROOF COVERINGS	2013 B301003 ROOF INSULATION & FILL General	8,157 (SF)	2013	
	B3010 ROOF COVERINGS	2013 B301004 FLASHINGS & TRIM Flashings - Base	340 (LF)	2013	
	B3010 ROOF COVERINGS	2013 B301004 FLASHINGS & TRIM Flashings - Cap	340 (LF)	2013	
	B3010 ROOF COVERINGS	2013 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	23 (EA)	2013	
	B3010 ROOF COVERINGS	2013 B301005 GUTTERS & DOWNSPOUTS Downspouts	212 (LF)	2013	
	B3010 ROOF COVERINGS	2013 A B301004 FLASHINGS & TRIM General	124 (LF)	2013	



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	B3010 ROOF COVERINGS	2013 B B301004 FLASHINGS & TRIM General	121 (LF)	2013	2013
C10 INTERIOR	C1010 PARTITIONS	1996 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing	107,200 (SF)	1996	2014
	C1010 PARTITIONS	1996 C101005 INTERIOR WINDOWS Interior Windows	56 (EA)	1996	
	C1010 PARTITIONS	2004 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing	16,400 (SF)	2004	2016
	C1010 PARTITIONS	2013 C101001 FIXED PARTITIONS Wall - Drywall w/Stud Framing	1,050 (SF)	2013	2013
	C1010 PARTITIONS	2013 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing	12,500 (SF)	1996	2013
	C1020 INTERIOR DOORS	1996 C102001 STANDARD INTERIOR DOORS Metal Door	148 (EA)	1996	
	C1020 INTERIOR DOORS	1996 C102003 FIRE DOORS Fire Door - Swinging	16 (EA)	1996	
	C1020 INTERIOR DOORS	1996 C102006 INTERIOR GATES General	2 (EA)	1996	
	C1020 INTERIOR DOORS	2004 C102001 STANDARD INTERIOR DOORS Metal Door	17 (EA)	2004	
	C1020 INTERIOR DOORS	2004 C102002 GLAZED INTERIOR DOORS General	2 (EA)	1996	
	C1020 INTERIOR DOORS	2004 C102003 FIRE DOORS Fire Door - Swinging	2 (EA)	2004	
	C1020 INTERIOR DOORS	2013 C102001 STANDARD INTERIOR DOORS Metal Door	22 (EA)	2013	
	C1020 INTERIOR DOORS	2013 C102003 FIRE DOORS Fire Door - Swinging	17 (EA)	2013	
	C1030 SPECIALTIES	1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions	58 (EA)	1996	
	C1030 SPECIALTIES	1996 C103002 TOILET & BATH ACCESSORIES General	221 (EA)	1996	
	C1030 SPECIALTIES	1996 C103003 MARKER BOARDS & TACK BOARDS General	182 (EA)	1996	
	C1030 SPECIALTIES	1996 C103005 LOCKERS General	884 (EA)	2018	
	C1030 SPECIALTIES	1996 C103006 SHELVING General	108 (LF)	1996	
	C1030 SPECIALTIES	1996 C103008 COUNTERS Laminated Plastic	183 (LF)	1996	
	C1030 SPECIALTIES	1996 C103009 CABINETS Other	473 (LF)	1996	
	C1030 SPECIALTIES	1996 C103010 CASEWORK General	1,228 (LF)	2018	
	C1030 SPECIALTIES	1996 A C103008 COUNTERS Laminated Plastic	220 (LF)	2018	
	C1030 SPECIALTIES	1996 A C103009 CABINETS Other	1,343 (LF)	2018	
	C1030 SPECIALTIES	2004 C103002 TOILET & BATH ACCESSORIES General	6 (EA)	2004	
	C1030 SPECIALTIES	2004 C103003 MARKER BOARDS & TACK BOARDS General	29 (EA)	2004	
	C1030 SPECIALTIES	2004 C103005 LOCKERS General	110 (EA)	2004	
	C1030 SPECIALTIES	2004 C103008 COUNTERS Wood	77 (LF)	2004	
	C1030 SPECIALTIES	2004 C103009 CABINETS Other	345 (LF)	2004	
	C1030 SPECIALTIES	2004 C103010 CASEWORK General	78 (LF)	2004	
	C1030 SPECIALTIES	2013 C103002 TOILET & BATH ACCESSORIES General	11 (EA)	2013	
	C1030 SPECIALTIES	2013 C103003 MARKER BOARDS & TACK BOARDS General	11 (EA)	2013	
	C1030 SPECIALTIES	2013 C103008 COUNTERS Wood	35 (LF)	2013	
	C1030 SPECIALTIES	2013 C103009 CABINETS Other	39 (LF)	2013	
	C1030 SPECIALTIES	2013 C103010 CASEWORK General	110 (LF)	2013	

C20 STAIRS



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	C2010 STAIR CONSTRUCTION	1996 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Concrete (12 Riser Flight)	4 (EA)	1996	
	C2010 STAIR CONSTRUCTION	1996 C201001 INTERIOR AND EXTERIOR STAIRS Interior Stairs	3 (EA)	1996	
	C2010 STAIR CONSTRUCTION	1996 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General	227 (LF)	1996	2011
	C2010 STAIR CONSTRUCTION	2004 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Concrete (12 Riser Flight)	2 (EA)	2004	
	C2010 STAIR CONSTRUCTION	2004 C201001 INTERIOR AND EXTERIOR STAIRS Interior Stairs	1 (EA)	2004	
	C2010 STAIR CONSTRUCTION	2004 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General	135 (LF)	2004	2013
	C2010 STAIR CONSTRUCTION	2013 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Concrete (12 Riser Flight)	2 (EA)	2013	
	C2010 STAIR CONSTRUCTION	2013 C201001 INTERIOR AND EXTERIOR STAIRS Interior Stairs	1 (EA)	2013	
	C2010 STAIR CONSTRUCTION	2013 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General	135 (LF)	2013	2013
C30 INTERIOR FINISHES	C3010 WALL FINISHES	1996 C301004 TILE & TERRAZZO WALL FINISHES General	18,100 (SF)	1996	
	C3010 WALL FINISHES	2004 C301004 TILE & TERRAZZO WALL FINISHES General	3,457 (SF)	2004	
	C3010 WALL FINISHES	2013 C301004 TILE & TERRAZZO WALL FINISHES General	1,940 (SF)	2013	
	C3020 FLOOR FINISHES	1996 C302001 TILE FLOOR FINISHES Ceramic Tile	72,800 (SF)	2005	
	C3020 FLOOR FINISHES	1996 C302005 CARPETING General	4,800 (SF)	1996	
	C3020 FLOOR FINISHES	1999 C302001 TILE FLOOR FINISHES Marble Tile	3,500 (SF)	2005	
	C3020 FLOOR FINISHES	1999 C302004 RESILIENT FLOOR FINISHES Rubber Sheet	4,019 (SF)	2018	
	C3020 FLOOR FINISHES	2004 C302001 TILE FLOOR FINISHES Ceramic Tile	12,843 (SF)	2004	
	C3020 FLOOR FINISHES	2013 C302001 TILE FLOOR FINISHES Ceramic Tile	7,111 (SF)	2013	
	C3020 FLOOR FINISHES	2013 C302004 RESILIENT FLOOR FINISHES Composition Sheet	2,800 (SF)	2013	
	C3030 CEILING FINISHES	1996 C303001 ACOUSTICAL CEILING TILES & PANELS General	84,000 (SF)	1996	
	C3030 CEILING FINISHES	1996 C303005 SUSPENSION SYSTEMS General	84,000 (SF)	1996	
	C3030 CEILING FINISHES	1996 C303006 METAL STRIP CEILINGS General	1,700 (SF)	1996	
	C3030 CEILING FINISHES	2004 C303001 ACOUSTICAL CEILING TILES & PANELS General	12,843 (SF)	2004	
	C3030 CEILING FINISHES	2004 C303005 SUSPENSION SYSTEMS General	12,843 (SF)	2004	
	C3030 CEILING FINISHES	2013 C303001 ACOUSTICAL CEILING TILES & PANELS General	7,805 (SF)	2013	
	C3030 CEILING FINISHES	2013 C303002 GYPSUM WALLBOARD CEILING FINISHES General	200 (SF)	2013	2013
	C3030 CEILING FINISHES	2013 C303005 SUSPENSION SYSTEMS General	7,805 (SF)	2013	
D10 CONVEYING	D1010 ELEVATORS AND LIFTS	1996 LE101 D101002 PASSENGER ELEVATORS Hydraulic Elevators - 1500 lb, 2 floors	1 (EA)	1996	
	D1010 ELEVATORS AND LIFTS	2004 D101004 WHEELCHAIR LIFT General	1 (EA)	2011	



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D1010 ELEVATORS AND LIFTS	2013 D101002 PASSENGER ELEVATORS Hydraulic Elevators - 1500 lb, 2 floors	1 (EA)	2013	
D20 PLUMBING	D2010 PLUMBING FIXTURES	1996 D201002 URINALS General	24 (EA)	2018	
	D2010 PLUMBING FIXTURES	1996 D201004 SINKS Service Sink	3 (EA)	1996	
	D2010 PLUMBING FIXTURES	1996 D201004 SINKS Stainless	53 (EA)	1996	
	D2010 PLUMBING FIXTURES	1996 D201005 SHOWERS/TUBS Shower	3 (EA)	1996	
	D2010 PLUMBING FIXTURES	1996 D201006 DRINKING FOUNTAINS AND COOLERS Drinking Fountain	12 (EA)	1996	
	D2010 PLUMBING FIXTURES	1996 A D201001 WATERCLOSETS General	30 (EA)	1996	
	D2010 PLUMBING FIXTURES	1996 A D201004 SINKS General	39 (EA)	1996	
	D2010 PLUMBING FIXTURES	1996 B D201001 WATERCLOSETS General	43 (EA)	2018	
	D2010 PLUMBING FIXTURES	1996 B D201004 SINKS General	58 (EA)	2019	
	D2010 PLUMBING FIXTURES	2004 D201001 WATERCLOSETS General	3 (EA)	2004	
	D2010 PLUMBING FIXTURES	2004 D201004 SINKS General	2 (EA)	2004	
	D2010 PLUMBING FIXTURES	2004 D201004 SINKS Stainless	9 (EA)	2004	
	D2010 PLUMBING FIXTURES	2004 D201006 DRINKING FOUNTAINS AND COOLERS Drinking Fountain	2 (EA)	2004	
	D2010 PLUMBING FIXTURES	2013 D201001 WATERCLOSETS General	6 (EA)	2013	
	D2010 PLUMBING FIXTURES	2013 D201004 SINKS General	5 (EA)	2013	
	D2010 PLUMBING FIXTURES	2013 D201004 SINKS Stainless	2 (EA)	2013	
	D2010 PLUMBING FIXTURES	2013 D201005 SHOWERS/TUBS Shower	1 (EA)	2013	
	D2010 PLUMBING FIXTURES	2013 D201006 DRINKING FOUNTAINS AND COOLERS Drinking Fountain	1 (EA)	2013	
	D2020 DOMESTIC WATER DISTRIBUTION	1996 D202001 PIPES & FITTINGS General	31,744 (LF)	1996	
	D2020 DOMESTIC WATER DISTRIBUTION	2004 D202001 PIPES & FITTINGS General	3,391 (LF)	2004	
	D2020 DOMESTIC WATER DISTRIBUTION	2013 D202001 PIPES & FITTINGS General	4,370 (LF)	2013	
	D2020 DOMESTIC WATER DISTRIBUTION	2013 D202003 DOMESTIC WATER EQUIPMENT Booster Pump - 1 HP	1 (EA)	2013	
	D2020 DOMESTIC WATER DISTRIBUTION	2013 ROOM MECH 5 D202003 DOMESTIC WATER EQUIPMENT Booster Pump - 1 HP	1 (EA)	2013	
	D2020 DOMESTIC WATER DISTRIBUTION	2013 ROOM MECH 5 D202003 DOMESTIC WATER EQUIPMENT Storage Tank - Glass lined, PE, 140 gallon, 24" diameter, 80" L.O.A.	1 (EA)	2013	
	D2030 SANITARY WASTE	1996 D203001 WASTE PIPE & FITTINGS General	52,073 (LF)	1996	
	D2030 SANITARY WASTE	1996 D203002 VENT PIPE & FITTINGS General	3,861 (EA)	1996	
	D2030 SANITARY WASTE	1996 D203003 FLOOR DRAINS General	16 (EA)	1996	
	D2030 SANITARY WASTE	2004 D203001 WASTE PIPE & FITTINGS General	5,564 (LF)	2004	



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D2030 SANITARY WASTE	2004 D203002 VENT PIPE & FITTINGS General	412 (EA)	2004	
	D2030 SANITARY WASTE	2013 D203001 WASTE PIPE & FITTINGS General	7,169 (LF)	2013	
	D2030 SANITARY WASTE	2013 D203002 VENT PIPE & FITTINGS General	531 (EA)	2013	
	D2040 RAIN WATER DRAINAGE	1996 D204001 PIPE & FITTINGS General	1,005 (LF)	1996	
	D2040 RAIN WATER DRAINAGE	1996 D204002 ROOF DRAINS Other	67 (EA)	1996	
	D2040 RAIN WATER DRAINAGE	2004 D204001 PIPE & FITTINGS General	135 (LF)	1996	
	D2040 RAIN WATER DRAINAGE	2004 D204002 ROOF DRAINS Other	9 (EA)	2004	
	D2040 RAIN WATER DRAINAGE	2013 D204001 PIPE & FITTINGS General	90 (LF)	2013	
	D2040 RAIN WATER DRAINAGE	2013 D204002 ROOF DRAINS Other	6 (EA)	2013	
D30 HVAC	D3020 HEAT GENERATING SYSTEMS	2013 D302004 AUXILIARY EQUIPMENT Expansion Tank - 15 gal	3 (EA)	2013	
	D3030 COOLING GENERATING SYSTEMS	2004 CH-435 D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 60 TN	1 (EA)	2004	
	D3030 COOLING GENERATING SYSTEMS	2013 CHILLER 788 D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 60 TN	1 (EA)	2013	
	D3040 DISTRIBUTION SYSTEMS	1996 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	30,251 (LF)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General	4,382 (MBH)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	438 (TON)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 AHU-055 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 AHU-061 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 AHU-1 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 AHU-2 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 AHU-3 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM	1 (EA)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 AHU-4 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 ROOFTOP D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 1500 CFM	2 (EA)	1996	
	D3040 DISTRIBUTION SYSTEMS	2004 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	2,163 (LF)	2004	
	D3040 DISTRIBUTION SYSTEMS	2004 D304003 HOT WATER DISTRIBUTION SYSTEMS General	290 (MBH)	2004	
	D3040 DISTRIBUTION SYSTEMS	2004 EF-190 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 1500 CFM	1 (EA)	2004	
	D3040 DISTRIBUTION SYSTEMS	2013 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	374 (LF)	2013	
	D3040 DISTRIBUTION SYSTEMS	2013 D304003 HOT WATER DISTRIBUTION SYSTEMS General	37 (MBH)	1996	
	D3040 DISTRIBUTION SYSTEMS	2013 D304003 HOT WATER DISTRIBUTION SYSTEMS Heat Exchanger, Plate Type - 400 GPM	1 (EA)	2013	



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D3040 DISTRIBUTION SYSTEMS	2013 AHU-292 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	2013	
	D3050 TERMINAL & PACKAGE UNITS	1996 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton	24 (EA)	1996	
	D3050 TERMINAL & PACKAGE UNITS	1996 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 2 ton	57 (EA)	1996	
	D3050 TERMINAL & PACKAGE UNITS	1996 A D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton	3 (EA)	1996	
	D3050 TERMINAL & PACKAGE UNITS	1996 A D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged Terminal AC, 18,000 BTUH, 10 kw	3 (EA)	2005	
	D3050 TERMINAL & PACKAGE UNITS	1996 B D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged Terminal AC, 12,000 BTUH cooling, 13,900 BTUH heat	2 (EA)	2010	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 119A D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged Terminal AC, 24,000 BTUH, 10 kw	1 (EA)	2005	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 132 D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air Cooled Condenser - 2 TN	2 (EA)	2016	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 132 A D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air Cooled Condenser - 2 TN	1 (EA)	2017	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 134 D305002 UNIT HEATERS Hydronic - 20 MBH	1 (EA)	1996	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 134 D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged Terminal AC, 18,000 BTUH, 10 kw	3 (EA)	2005	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 134 B D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air Cooled Condenser - 2 TN	1 (EA)	2018	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 203 D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged Terminal AC, 12,000 BTUH cooling, 13,900 BTUH heat	2 (EA)	2005	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 203 D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged Terminal AC, 18,000 BTUH, 10 kw	1 (EA)	1996	
	D3050 TERMINAL & PACKAGE UNITS	1996 S103.2 D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air Cooled Condenser - 2 TN	2 (EA)	2005	
	D3050 TERMINAL & PACKAGE UNITS	2004 D305003 FAN COIL UNITS Duct Mount, 2 Pipe - 1 ton	8 (EA)	2004	
	D3050 TERMINAL & PACKAGE UNITS	2004 D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged Terminal AC, 12,000 BTUH cooling, 13,900 BTUH heat	4 (EA)	2004	
	D3050 TERMINAL & PACKAGE UNITS	2013 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton	6 (EA)	2013	
	D3050 TERMINAL & PACKAGE UNITS	2013 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 2 ton	5 (EA)	2013	
	D3050 TERMINAL & PACKAGE UNITS	2013 D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged Terminal AC, 18,000 BTUH, 10 kw	4 (EA)	2013	
	D3060 CONTROLS & INSTRUMENTATION	1996 D306002 ELECTRONIC CONTROLS General	6 (EA)	1996	
	D3060 CONTROLS & INSTRUMENTATION	2004 D306002 ELECTRONIC CONTROLS General	1 (EA)	1996	
	D3060 CONTROLS & INSTRUMENTATION	2013 D306002 ELECTRONIC CONTROLS General	1 (EA)	2013	



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SYSTEMS	1996 D401001 FIRE ALARM DISTRIBUTION Other	108,693 (SF)	1996	
	D4010 FIRE ALARM AND DETECTION SYSTEMS	2004 D401001 FIRE ALARM DISTRIBUTION Other	11,612 (SF)	2004	
	D4010 FIRE ALARM AND DETECTION SYSTEMS	2013 D401001 FIRE ALARM DISTRIBUTION Other	14,963 (SF)	2013	
	D4040 SPRINKLERS	1996 D404001 SPRINKLERS AND RELEASING DEVICES Wet Pipe Systems	108,693 (SF)	1996	
	D4040 SPRINKLERS	2004 D404001 SPRINKLERS AND RELEASING DEVICES Wet Pipe Systems	12,612 (SF)	2004	
	D4040 SPRINKLERS	2013 D404001 SPRINKLERS AND RELEASING DEVICES Wet Pipe Systems	904 (SF)	1996	
D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 D501003 INTERIOR DISTRIBUTION TRANSFORMERS dry-type, 480 V primary 120/208 V secondary, 15 kVA	2 (EA)	1996	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 D501003 INTERIOR DISTRIBUTION TRANSFORMERS dry-type, 480 V primary 120/208 V secondary, 75 kVA	2 (EA)	1996	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 D501004 PANELBOARDS Main lugs, 50 amp	8 (EA)	1996	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp, NQOD	5 (EA)	1996	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 D501004 PANELBOARDS Main lugs, 125 amp	4 (EA)	1996	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 D501004 PANELBOARDS Safety Switch, 30-100 Amp	1 (EA)	1996	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 ROOM 104 D501002 SERVICE ENTRANCE EQUIPMENT Electrical Service - 3 Phase, 120/208 V, 1000 A	2 (EA)	1996	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 ROOM 104 D501002 SERVICE ENTRANCE EQUIPMENT Electrical Service - 3 Phase, 120/208 V, 1200 A	3 (EA)	1996	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 ROOM 104 D501004 PANELBOARDS Main lugs, 277/480 V, 100 amp, NEHB	2 (EA)	1996	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 ROOM 117 D501002 SERVICE ENTRANCE EQUIPMENT Electrical Service - 3 Phase, 120/208 V, 800 A	2 (EA)	1996	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 ROOM 117 D501004 PANELBOARDS Main lugs, 200 amp	1 (EA)	1996	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 ROOM 141 D501004 PANELBOARDS Main lugs, 200 amp	1 (EA)	2004	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 ROOM 202 D501004 PANELBOARDS Main lugs, 120/240 V, 225 amp, NQOD	1 (EA)	1996	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 ROOM 202 D501004 PANELBOARDS Switchgear - 400 Amp	1 (EA)	1997	



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2004 ROOM 145 D501004 PANELBOARDS Main lugs, 120/240 V, 225 amp, NQOD	1 (EA)	2004	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2013 D501002 SERVICE ENTRANCE EQUIPMENT Electrical Service - 3 Phase, 120/208 V, 2000 A	1 (EA)	2013	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2013 ROOM 18 D501003 INTERIOR DISTRIBUTION TRANSFORMERS dry-type, 240/480 V primary 120/240 V secondary, 75 kVA	1 (EA)	2013	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2013 ROOM 18 D501004 PANELBOARDS Main lugs, 120/240 V, 225 amp, NQOD	3 (EA)	2013	
	D5020 LIGHTING & BRANCH WIRING	1996 D502001 BRANCH WIRING General	108,693 (SF)	1996	
	D5020 LIGHTING & BRANCH WIRING	1996 D502002 LIGHTING EQUIPMENT Exit Lighting	47 (EA)	1996	
	D5020 LIGHTING & BRANCH WIRING	1996 D502002 LIGHTING EQUIPMENT General	108,693 (SF)	1996	
	D5020 LIGHTING & BRANCH WIRING	1996 A D502002 LIGHTING EQUIPMENT Exterior Lighting	12 (EA)	1996	
	D5020 LIGHTING & BRANCH WIRING	1996 B D502002 LIGHTING EQUIPMENT Exterior Lighting	11 (EA)	1996	
	D5020 LIGHTING & BRANCH WIRING	2004 D502001 BRANCH WIRING General	11,612 (SF)	2004	
	D5020 LIGHTING & BRANCH WIRING	2004 D502002 LIGHTING EQUIPMENT Exit Lighting	5 (EA)	1996	
	D5020 LIGHTING & BRANCH WIRING	2004 D502002 LIGHTING EQUIPMENT Exterior Lighting	8 (EA)	1996	
	D5020 LIGHTING & BRANCH WIRING	2004 D502002 LIGHTING EQUIPMENT General	11,612 (SF)	2004	
	D5020 LIGHTING & BRANCH WIRING	2013 D502001 BRANCH WIRING General	14,963 (SF)	2013	
	D5020 LIGHTING & BRANCH WIRING	2013 D502002 LIGHTING EQUIPMENT Exit Lighting	10 (EA)	1996	
	D5020 LIGHTING & BRANCH WIRING	2013 D502002 LIGHTING EQUIPMENT Exterior Lighting	2 (EA)	2013	
	D5020 LIGHTING & BRANCH WIRING	2013 D502002 LIGHTING EQUIPMENT General	12,100 (SF)	2013	
	D5030 COMMUNICATIONS & SECURITY	1996 D503001 TELECOMMUNICATIONS SYSTEMS General	1 (EA)	1996	
	D5030 COMMUNICATIONS & SECURITY	1996 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets	1 (EA)	1996	
	D5030 COMMUNICATIONS & SECURITY	1996 D503003 INTERCOMMUNICATIONS SYSTEMS 100 stations	1 (EA)	1996	
	D5030 COMMUNICATIONS & SECURITY	1996 D503005 SECURITY SYSTEMS General	1 (EA)	1996	
	D5030 COMMUNICATIONS & SECURITY	1996 D503007 CLOCK & PROGRAM SYSTEMS General	1 (EA)	1996	
	D5030 COMMUNICATIONS & SECURITY	2004 D503002 PUBLIC ADDRESS SYSTEMS 6 outlets	1 (EA)	2004	
	D5030 COMMUNICATIONS & SECURITY	2004 D503003 INTERCOMMUNICATIONS SYSTEMS 6 stations	1 (EA)	2004	
	D5030 COMMUNICATIONS & SECURITY	2013 D503002 PUBLIC ADDRESS SYSTEMS 6 outlets	1 (EA)	2013	
	D5030 COMMUNICATIONS & SECURITY	2013 D503003 INTERCOMMUNICATIONS SYSTEMS 6 stations	1 (EA)	2013	



Support Site

2057 - Naples ES Bldg 2057

Naples ES (HE5549)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D5090 OTHER ELECTRICAL SERVICES	1996 D509002 EMERGENCY LIGHTING & POWER General	108,693 (SF)	1996	
	D5090 OTHER ELECTRICAL SERVICES	1996 D509002 EMERGENCY LIGHTING & POWER Uninterruptible Power Supply - 1.0 kVA	4 (EA)	1996	
	D5090 OTHER ELECTRICAL SERVICES	1996 D509003 GROUNDING SYSTEMS General	1 (EA)	1996	
	D5090 OTHER ELECTRICAL SERVICES	2004 D509002 EMERGENCY LIGHTING & POWER General	11,612 (SF)	2004	
	D5090 OTHER ELECTRICAL SERVICES	2004 D509002 EMERGENCY LIGHTING & POWER Uninterruptible Power Supply - 1.0 kVA	1 (EA)	2004	
	D5090 OTHER ELECTRICAL SERVICES	2004 D509003 GROUNDING SYSTEMS General	1 (EA)	1996	
	D5090 OTHER ELECTRICAL SERVICES	2013 D509002 EMERGENCY LIGHTING & POWER General	14,963 (SF)	2013	
	D5090 OTHER ELECTRICAL SERVICES	2013 D509003 GROUNDING SYSTEMS General	1 (EA)	1996	



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1996 B201001 EXTERIOR CLOSURE Brick Veneer w/CMU Backup	6,799 (SF)	1996	
	B2010 EXTERIOR WALLS	1996 B201001 EXTERIOR CLOSURE Stone Veneer w/CMU Backup	1,570 (SF)	1996	
	B2010 EXTERIOR WALLS	1996 B201001 EXTERIOR CLOSURE Stucco	33,610 (SF)	1996	2013
	B2010 EXTERIOR WALLS	1996 B201004 PARAPETS General	3,900 (LF)	2016	
	B2010 EXTERIOR WALLS	1996 B201007 EXTERIOR SOFFITS General	5,588 (SF)	1996	1996
	B2010 EXTERIOR WALLS	1996 A B201010 EXTERIOR JOINT SEALANT General	1,500 (LF)	1996	
	B2010 EXTERIOR WALLS	1996 B B201010 EXTERIOR JOINT SEALANT General	5,000 (LF)	1996	
	B2010 EXTERIOR WALLS	1996 C B201010 EXTERIOR JOINT SEALANT General	167 (LF)	1996	
	B2020 EXTERIOR WINDOWS	1996 B202001 WINDOWS Aluminum Windows	214 (EA)	1996	
	B2030 EXTERIOR DOORS	1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door	37 (EA)	1996	
B30 ROOFING	B3010 ROOF COVERINGS	1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	67,200 (SF)	2016	
	B3010 ROOF COVERINGS	1996 B301003 ROOF INSULATION & FILL General	67,200 (SF)	1996	
	B3010 ROOF COVERINGS	1996 B301004 FLASHINGS & TRIM Flashings - Apron	645 (LF)	2016	
	B3010 ROOF COVERINGS	1996 B301004 FLASHINGS & TRIM Flashings - Base	3,500 (LF)	2016	
	B3010 ROOF COVERINGS	1996 B301004 FLASHINGS & TRIM Flashings - Cap	3,900 (LF)	1996	
	B3010 ROOF COVERINGS	1996 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	72 (EA)	2016	
	B3010 ROOF COVERINGS	1996 B301004 FLASHINGS & TRIM General	3,688 (LF)	1996	1996
	B3010 ROOF COVERINGS	1996 B301005 GUTTERS & DOWNSPOUTS Downspouts	1,200 (LF)	1996	2013
	B3010 ROOF COVERINGS	1996 B301006 ROOF OPENINGS AND SUPPORTS Skylights	180 (SF)	1996	
	B3010 ROOF COVERINGS	1996 B301090 OTHER ROOFING Walkway Protection	862 (SF)	1996	
	B3010 ROOF COVERINGS	1996 A B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	12,612 (SF)	2012	
	B3010 ROOF COVERINGS	1996 A B301003 ROOF INSULATION & FILL General	12,612 (SF)	2012	
	B3010 ROOF COVERINGS	1996 A B301004 FLASHINGS & TRIM Flashings - Base	450 (LF)	2012	
	B3010 ROOF COVERINGS	1996 A B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	18 (EA)	2012	
	B3010 ROOF COVERINGS	1996 A B301004 FLASHINGS & TRIM Flashings - Pitch Pans	15 (EA)	2016	
	B3010 ROOF COVERINGS	1996 B B301004 FLASHINGS & TRIM Flashings - Pitch Pans	10 (EA)	2016	
C10 INTERIOR	C1010 PARTITIONS	1996 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing	123,500 (SF)	1996	2014
	C1010 PARTITIONS	1996 C101005 INTERIOR WINDOWS General	49 (SF)	1996	
	C1020 INTERIOR DOORS	1996 C102001 STANDARD INTERIOR DOORS Metal Door	151 (EA)	1996	
	C1020 INTERIOR DOORS	1996 C102003 FIRE DOORS Fire Door - Swinging, Metal	24 (EA)	1996	
	C1020 INTERIOR DOORS	1996 C102006 INTERIOR GATES General	6 (EA)	1996	
	C1030 SPECIALTIES	1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Shower Compartment	6 (EA)	1996	
	C1030 SPECIALTIES	1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions - Coated Steel	29 (EA)	1996	



System Inventory Report



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	C1030 SPECIALTIES	1996 C103002 TOILET & BATH ACCESSORIES General	129 (EA)	1996	
	C1030 SPECIALTIES	1996 C103003 MARKER BOARDS & TACK BOARDS General	178 (EA)	1996	
	C1030 SPECIALTIES	1996 C103005 LOCKERS General	1,237 (EA)	2018	
	C1030 SPECIALTIES	1996 C103006 SHELVING General	20 (LF)	1996	
	C1030 SPECIALTIES	1996 C103008 COUNTERS Laminated Plastic	652 (LF)	1996	
	C1030 SPECIALTIES	1996 C103009 CABINETS Other	1,023 (LF)	1996	
	C1030 SPECIALTIES	1996 C103010 CASEWORK General	37 (LF)	1996	
	C1030 SPECIALTIES	1996 C103014 ENTRANCE FLOOR GRILLES AND MATS General	115 (SF)	1996	
	C1030 SPECIALTIES	1996 A C103008 COUNTERS Laminated Plastic	117 (LF)	2018	
	C1030 SPECIALTIES	1999 A C103009 CABINETS Other	967 (LF)	1996	
C20 STAIRS	C2010 STAIR CONSTRUCTION	1996 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Concrete (12 Riser Flight)	2 (EA)	1996	
	C2010 STAIR CONSTRUCTION	1996 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Metal (12 Riser Flight)	2 (EA)	1996	
	C2010 STAIR CONSTRUCTION	1996 C201001 INTERIOR AND EXTERIOR STAIRS Interior Stairs	2 (EA)	1996	
	C2010 STAIR CONSTRUCTION	1996 A C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General	145 (LF)	1996	1996
	C2010 STAIR CONSTRUCTION	1996 B C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General	165 (LF)	1996	1996
C30 INTERIOR FINISHES	C3010 WALL FINISHES	1996 C301004 TILE & TERRAZZO WALL FINISHES General	14,346 (SF)	1996	
	C3010 WALL FINISHES	1996 C301006 ACOUSTICAL PANELS ADHERED TO WALLS General	2,558 (SF)	1996	
	C3020 FLOOR FINISHES	1996 C302001 TILE FLOOR FINISHES Ceramic Tile	74,602 (SF)	2005	
	C3020 FLOOR FINISHES	1996 C302003 WOOD FLOORING General	14,706 (SF)	2013	
	C3020 FLOOR FINISHES	1996 C302004 RESILIENT FLOOR FINISHES Composition Sheet	2,176 (SF)	2011	
	C3020 FLOOR FINISHES	1996 C302005 CARPETING General	5,652 (SF)	2005	
	C3020 FLOOR FINISHES	1999 C302001 TILE FLOOR FINISHES Marble Tile	2,888 (SF)	2005	
	C3030 CEILING FINISHES	1996 C303001 ACOUSTICAL CEILING TILES & PANELS General	85,811 (SF)	1996	
	C3030 CEILING FINISHES	1996 C303005 SUSPENSION SYSTEMS General	85,811 (SF)	1996	
D10 CONVEYING	D1010 ELEVATORS AND LIFTS	1996 ROOM M101 D101002 PASSENGER ELEVATORS Hydraulic Elevators - 1500 lb, 2 floors	1 (EA)	1996	
D20 PLUMBING	D2010 PLUMBING FIXTURES	1996 D201002 URINALS General	14 (EA)	2018	
	D2010 PLUMBING FIXTURES	1996 D201004 SINKS Kitchen Sink	7 (EA)	1996	
	D2010 PLUMBING FIXTURES	1996 D201004 SINKS Laboratory Sink	38 (EA)	1996	
	D2010 PLUMBING FIXTURES	1996 D201004 SINKS Service Sink	4 (EA)	1996	
	D2010 PLUMBING FIXTURES	1996 D201004 SINKS Stainless	7 (EA)	1996	



System Inventory Report



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D2010 PLUMBING FIXTURES	1996 D201005 SHOWERS/TUBS Shower	20 (EA)	1996	
	D2010 PLUMBING FIXTURES	1996 D201006 DRINKING FOUNTAINS AND COOLERS Drinking Fountain	7 (EA)	1996	
	D2010 PLUMBING FIXTURES	1996 D201090 OTHER PLUMBING FIXTURES Emergency Eye Wash	1 (EA)	1996	
	D2010 PLUMBING FIXTURES	1996 D201090 OTHER PLUMBING FIXTURES Emergency Shower	5 (EA)	1996	
	D2010 PLUMBING FIXTURES	1996 A D201001 WATERCLOSETS General	9 (EA)	1996	
	D2010 PLUMBING FIXTURES	1996 A D201004 SINKS General	15 (EA)	1996	
	D2010 PLUMBING FIXTURES	1996 B D201001 WATERCLOSETS General	31 (EA)	2018	
	D2010 PLUMBING FIXTURES	1996 B D201004 SINKS General	39 (EA)	2018	
	D2020 DOMESTIC WATER DISTRIBUTION	1996 D202001 PIPES & FITTINGS General	32,449 (LF)	1996	
	D2020 DOMESTIC WATER DISTRIBUTION	1996 ROOM 234/235 D202003 DOMESTIC WATER EQUIPMENT Water Heaters, Residential, Electric	1 (EA)	2010	
	D2030 SANITARY WASTE	1996 D203001 WASTE PIPE & FITTINGS General	53,232 (LF)	1996	
	D2030 SANITARY WASTE	1996 D203002 VENT PIPE & FITTINGS General	3,947 (EA)	1996	
	D2030 SANITARY WASTE	1996 D203003 FLOOR DRAINS General	30 (EA)	1996	
	D2040 RAIN WATER DRAINAGE	1996 D204001 PIPE & FITTINGS General	2,070 (LF)	1996	
	D2040 RAIN WATER DRAINAGE	1996 D204002 ROOF DRAINS Other	69 (EA)	1996	
D30 HVAC	D3030 COOLING GENERATING SYSTEMS	1996 OUTSIDE D303002 DIRECT EXPANSION SYSTEMS Packaged DX Refrigerant System - Air Cooled, 75 ton	1 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	1996 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	25,700 (LF)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General	3,778 (MBH)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	378 (TON)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 ROOFTOP A D304007 EXHAUST SYSTEMS Fume Hood Exhaust System - 3', 1000 CFM	2 (EA)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 ROOFTOP B D304007 EXHAUST SYSTEMS Fume Hood Exhaust System - 3', 1000 CFM	3 (EA)	2018	
	D3040 DISTRIBUTION SYSTEMS	1996 UTA-1 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 UTA-2 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 UTA-3 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 UTA-4 D304008 AIR HANDLING UNITS Rooftop - 5000 CFM	1 (EA)	1996	
	D3050 TERMINAL & PACKAGE UNITS	1996 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton	11 (EA)	1996	
	D3050 TERMINAL & PACKAGE UNITS	1996 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 2 ton	57 (EA)	1996	
	D3050 TERMINAL & PACKAGE UNITS	1996 D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged Terminal AC, 24,000 BTUH, 10 kw	1 (EA)	2005	
	D3050 TERMINAL & PACKAGE UNITS	1996 A D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton	23 (EA)	1996	



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D3050 TERMINAL & PACKAGE UNITS	1996 PAC-012 D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air Cooled Condenser - 5 TN	1 (EA)	2005	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOFTOP D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged Terminal AC, 12,000 BTUH cooling, 13,900 BTUH heat	1 (EA)	2011	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOFTOP D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air Cooled Condenser - 5 TN	1 (EA)	2005	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 107 D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged Terminal AC, 9,000 BTUH cooling, 13,900 BTUH heat	1 (EA)	2005	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 112D D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air Cooled Condenser - 2 TN	1 (EA)	2017	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 115 D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged Terminal AC, 12,000 BTUH cooling, 13,900 BTUH heat	1 (EA)	2005	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 122D D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged Terminal AC, 24,000 BTUH, 10 kw	1 (EA)	2005	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 124 D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged Terminal AC, 24,000 BTUH, 10 kw	1 (EA)	2015	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 225 D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged Terminal AC, 30,000 BTUH, 10 kw	1 (EA)	2012	
	D3050 TERMINAL & PACKAGE UNITS	1996 SS-046 D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged Terminal AC, 6,000 BTUH cooling, 8,800 BTUH heat	1 (EA)	2005	
	D3050 TERMINAL & PACKAGE UNITS	1996 SS-605 D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged Terminal AC, 6,000 BTUH cooling, 8,800 BTUH heat	1 (EA)	2009	
	D3060 CONTROLS & INSTRUMENTATION	1996 D306002 ELECTRONIC CONTROLS General	4 (EA)	1996	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SYSTEMS	1996 D401001 FIRE ALARM DISTRIBUTION Other	111,107 (SF)	1996	
	D4040 SPRINKLERS	1996 D404001 SPRINKLERS AND RELEASING DEVICES Wet Pipe Systems	111,107 (SF)	1996	
D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 D501004 PANELBOARDS Main lugs, 50 amp	9 (EA)	1996	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp, NQOD	25 (EA)	1996	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 D501004 PANELBOARDS Main lugs, 120/240 V, 225 amp, NQOD	2 (EA)	1996	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 D501004 PANELBOARDS Main lugs, 125 amp	7 (EA)	1996	



Support Site

2058 - Naples MS/HS Bldg 2058

Naples MS/HS (HE5509)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 ROOM 123 D501002 SERVICE ENTRANCE EQUIPMENT Electrical Service - 3 Phase, 120/208 V, 800 A	4 (EA)	1996	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 ROOM 123 D501003 INTERIOR DISTRIBUTION TRANSFORMERS dry-type, 240/480 V primary 120/240 V secondary, 10 kVA	2 (EA)	1996	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 ROOM 123 D501003 INTERIOR DISTRIBUTION TRANSFORMERS dry-type, 240/480 V primary 120/240 V secondary, 50 kVA	1 (EA)	1996	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 ROOM 123 D501004 PANELBOARDS Main lugs, 200 amp	1 (EA)	1996	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 ROOM 226 D501003 INTERIOR DISTRIBUTION TRANSFORMERS dry-type, 240/480 V primary 120/240 V secondary, 50 kVA	1 (EA)	1996	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 ROOM 226 D501004 PANELBOARDS Main lugs, 200 amp	1 (EA)	1996	
	D5020 LIGHTING & BRANCH WIRING	1996 D502001 BRANCH WIRING General	111,107 (SF)	1996	
	D5020 LIGHTING & BRANCH WIRING	1996 D502002 LIGHTING EQUIPMENT Exit Lighting	24 (EA)	1996	
	D5020 LIGHTING & BRANCH WIRING	1996 D502002 LIGHTING EQUIPMENT Exterior Lighting	6 (EA)	1996	
	D5020 LIGHTING & BRANCH WIRING	1996 D502002 LIGHTING EQUIPMENT General	111,107 (SF)	1996	
	D5030 COMMUNICATIONS & SECURITY	1996 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets	1 (EA)	1996	
	D5030 COMMUNICATIONS & SECURITY	1996 D503003 INTERCOMMUNICATIONS SYSTEMS 50 stations	1 (EA)	1996	
	D5030 COMMUNICATIONS & SECURITY	1996 D503005 SECURITY SYSTEMS General	1 (EA)	2005	
	D5030 COMMUNICATIONS & SECURITY	1996 D503007 CLOCK & PROGRAM SYSTEMS General	1 (EA)	1996	
	D5090 OTHER ELECTRICAL SERVICES	1996 D509002 EMERGENCY LIGHTING & POWER General	111,107 (SF)	1996	
	D5090 OTHER ELECTRICAL SERVICES	1996 D509002 EMERGENCY LIGHTING & POWER Uninterruptible Power Supply - 1.0 kVA	3 (EA)	1996	
	D5090 OTHER ELECTRICAL SERVICES	1996 D509003 GROUNDING SYSTEMS General	1 (EA)	1996	



System Inventory Report



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1996 B201001 EXTERIOR CLOSURE Brick Veneer w/CMU Backup	4,440 (SF)	1996	
	B2010 EXTERIOR WALLS	1996 B201001 EXTERIOR CLOSURE Stone Veneer w/CMU Backup	548 (SF)	1996	
	B2010 EXTERIOR WALLS	1996 B201001 EXTERIOR CLOSURE Stucco	7,912 (SF)	1996	2013
	B2010 EXTERIOR WALLS	1996 B201004 PARAPETS General	1,500 (LF)	1996	
	B2010 EXTERIOR WALLS	1996 B201006 BALCONY WALLS & HANDRAILS Handrailing	240 (LF)	1996	1996
	B2010 EXTERIOR WALLS	1996 B201007 EXTERIOR SOFFITS General	623 (SF)	1996	2013
	B2010 EXTERIOR WALLS	1996 A B201010 EXTERIOR JOINT SEALANT General	350 (LF)	1996	
	B2010 EXTERIOR WALLS	1996 B B201010 EXTERIOR JOINT SEALANT General	250 (LF)	1996	
	B2020 EXTERIOR WINDOWS	1996 B202001 WINDOWS Steel Windows	14 (EA)	1996	
	B2030 EXTERIOR DOORS	1996 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door	12 (EA)	1996	
B30 ROOFING	B3010 ROOF COVERINGS	1996 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	20,930 (SF)	2016	
	B3010 ROOF COVERINGS	1996 B301003 ROOF INSULATION & FILL General	20,930 (SF)	1996	
	B3010 ROOF COVERINGS	1996 B301004 FLASHINGS & TRIM Flashings - Base	1,846 (LF)	2016	
	B3010 ROOF COVERINGS	1996 B301004 FLASHINGS & TRIM Flashings - Cap	1,522 (LF)	2016	
	B3010 ROOF COVERINGS	1996 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	231 (EA)	2016	
	B3010 ROOF COVERINGS	1996 B301004 FLASHINGS & TRIM General	214 (LF)	1996	1996
	B3010 ROOF COVERINGS	1996 B301005 GUTTERS & DOWNSPOUTS Downspouts	304 (LF)	1996	1996
	B3010 ROOF COVERINGS	1996 A B301004 FLASHINGS & TRIM Flashings - Apron	308 (LF)	2016	
	B3010 ROOF COVERINGS	1996 B B301004 FLASHINGS & TRIM Flashings - Apron	153 (LF)	2016	
C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	1996 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing	20,140 (SF)	1996	2013
	C1010 PARTITIONS	1996 C101005 INTERIOR WINDOWS Interior Windows	1 (EA)	1996	
	C1010 PARTITIONS	1996 C101005 INTERIOR WINDOWS Metal Rollup / Coiling Grille	32 (SF)	1996	
	C1020 INTERIOR DOORS	1996 C102001 STANDARD INTERIOR DOORS Metal Door	29 (EA)	1996	
	C1020 INTERIOR DOORS	1996 C102005 INTERIOR OVERHEAD DOORS Metal	2 (EA)	1996	
	C1020 INTERIOR DOORS	1996 C102090 OTHER INTERIOR SPECIALTY DOORS Cold Storage	4 (EA)	1996	
	C1030 SPECIALTIES	1996 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions - Coated Steel	14 (EA)	1996	
	C1030 SPECIALTIES	1996 C103002 TOILET & BATH ACCESSORIES General	59 (EA)	1996	
	C1030 SPECIALTIES	1996 C103003 MARKER BOARDS & TACK BOARDS General	3 (EA)	1996	
	C1030 SPECIALTIES	1996 C103005 LOCKERS General	6 (EA)	1996	
	C1030 SPECIALTIES	1996 C103006 SHELVING General	52 (LF)	1996	
C20 STAIRS	C2010 STAIR CONSTRUCTION	1996 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General	90 (LF)	1996	1996



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
C30 INTERIOR FINISHES	C3010 WALL FINISHES	1996 C301002 PLASTER WALL FINISHES General	22,781 (SF)	1996	2014
	C3010 WALL FINISHES	1996 C301004 TILE & TERRAZZO WALL FINISHES General	9,060 (SF)	1996	
	C3020 FLOOR FINISHES	1996 C302001 TILE FLOOR FINISHES Ceramic Tile	11,335 (SF)	1996	
	C3020 FLOOR FINISHES	1996 C302004 RESILIENT FLOOR FINISHES Composition Sheet	1,900 (SF)	1996	
	C3020 FLOOR FINISHES	1996 C302006 MASONRY & STONE FLOORING Quarry Tile	3,200 (SF)	1996	
	C3030 CEILING FINISHES	1996 C303001 ACOUSTICAL CEILING TILES & PANELS General	13,802 (SF)	1996	
	C3030 CEILING FINISHES	1996 C303003 PLASTER CEILING FINISHES General	3,797 (SF)	1996	2012
	C3030 CEILING FINISHES	1996 C303005 SUSPENSION SYSTEMS General	13,802 (SF)	1996	
D20 PLUMBING	D2010 PLUMBING FIXTURES	1996 D201002 URINALS General	6 (EA)	1996	
	D2010 PLUMBING FIXTURES	1996 D201004 SINKS Kitchen Sink	2 (EA)	1996	
	D2010 PLUMBING FIXTURES	1996 D201006 DRINKING FOUNTAINS AND COOLERS Drinking Fountain	3 (EA)	1996	
	D2010 PLUMBING FIXTURES	1996 A D201001 WATERCLOSETS General	9 (EA)	1996	
	D2010 PLUMBING FIXTURES	1996 A D201004 SINKS General	11 (EA)	1996	
	D2010 PLUMBING FIXTURES	1996 B D201001 WATERCLOSETS General	14 (EA)	2018	
	D2010 PLUMBING FIXTURES	1996 B D201004 SINKS General	16 (EA)	2018	
	D2020 DOMESTIC WATER DISTRIBUTION	1996 D202001 PIPES & FITTINGS General	6,113 (LF)	1996	
	D2020 DOMESTIC WATER DISTRIBUTION	1996 D202002 VALVES & HYDRANTS Backflow Preventer - 3" pipe	2 (EA)	1996	
	D2020 DOMESTIC WATER DISTRIBUTION	1996 D202003 DOMESTIC WATER EQUIPMENT Storage Tank - Glass lined, PE, 460 gallon, 42" diameter, 84" L.O.A.	2 (EA)	1996	
	D2020 DOMESTIC WATER DISTRIBUTION	1996 ROOM M101 D202003 DOMESTIC WATER EQUIPMENT Booster Pump - 1.5 HP	2 (EA)	1996	
	D2020 DOMESTIC WATER DISTRIBUTION	1996 ROOM M101 D202003 DOMESTIC WATER EQUIPMENT Storage Tank - Glass lined, PE, 325 gallon, 36" diameter, 81" L.O.A.	1 (EA)	1996	
	D2020 DOMESTIC WATER DISTRIBUTION	1996 ROOM M101 D202003 DOMESTIC WATER EQUIPMENT Water Softener	1 (EA)	1996	
	D2020 DOMESTIC WATER DISTRIBUTION	1996 ROOM M102 D202003 DOMESTIC WATER EQUIPMENT Water Softener	1 (EA)	1996	
	D2030 SANITARY WASTE	1996 D203001 WASTE PIPE & FITTINGS General	3,056 (LF)	1996	
	D2030 SANITARY WASTE	1996 D203002 VENT PIPE & FITTINGS General	743 (EA)	1996	
	D2030 SANITARY WASTE	1996 D203003 FLOOR DRAINS General	18 (EA)	1996	
	D2040 RAIN WATER DRAINAGE	1996 D204001 PIPE & FITTINGS General	390 (LF)	1996	
	D2040 RAIN WATER DRAINAGE	1996 D204002 ROOF DRAINS Other	26 (EA)	1996	
D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1996 A D302004 AUXILIARY EQUIPMENT Expansion Tank - 40 gal	3 (EA)	1996	
	D3020 HEAT GENERATING SYSTEMS	1996 B D302004 AUXILIARY EQUIPMENT Expansion Tank - 40 gal	2 (EA)	2007	



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D3020 HEAT GENERATING SYSTEMS	1996 ROOM M101 A D302004 AUXILIARY EQUIPMENT Expansion Tank - 15 gal	5 (EA)	1997	
	D3020 HEAT GENERATING SYSTEMS	1996 ROOM M101 B D302004 AUXILIARY EQUIPMENT Expansion Tank - 15 gal	2 (EA)	2007	
	D3020 HEAT GENERATING SYSTEMS	1996 ROOM M101 BOILER 1 D302001 BOILERS Gas, Hot Water - 500-650 MBH	1 (EA)	1996	
	D3020 HEAT GENERATING SYSTEMS	1996 ROOM M101 BOILER 2 D302001 BOILERS Gas, Hot Water - 500-650 MBH	1 (EA)	1996	
	D3020 HEAT GENERATING SYSTEMS	1996 ROOM M101 C D302004 AUXILIARY EQUIPMENT Expansion Tank - 15 gal	1 (EA)	2016	
	D3020 HEAT GENERATING SYSTEMS	1996 ROOM M102 D302004 AUXILIARY EQUIPMENT Expansion Tank - 30 gal	3 (EA)	2006	
	D3020 HEAT GENERATING SYSTEMS	1996 ROOM M102 A D302004 AUXILIARY EQUIPMENT Expansion Tank - 15 gal	2 (EA)	2012	
	D3020 HEAT GENERATING SYSTEMS	1996 ROOM M102 B D302004 AUXILIARY EQUIPMENT Expansion Tank - 15 gal	4 (EA)	1996	
	D3020 HEAT GENERATING SYSTEMS	1996 ROOM M102 BOILER-2058A D302001 BOILERS Gas, Hot Water - 500-650 MBH	1 (EA)	1996	
	D3020 HEAT GENERATING SYSTEMS	1996 ROOM M102 BOILER-2058B D302001 BOILERS Gas, Hot Water - 500-650 MBH	1 (EA)	1996	
	D3030 COOLING GENERATING SYSTEMS	1996 ROOFTOP A D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 100 TN	1 (EA)	2017	
	D3030 COOLING GENERATING SYSTEMS	1996 ROOFTOP B D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 100 TN	1 (EA)	2017	
	D3030 COOLING GENERATING SYSTEMS	1996 ROOFTOP C D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 100 TN	1 (EA)	2017	
	D3030 COOLING GENERATING SYSTEMS	1996 ROOFTOP D D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 100 TN	1 (EA)	2017	
	D3040 DISTRIBUTION SYSTEMS	1996 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	3,899 (LF)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 D304003 HOT WATER DISTRIBUTION SYSTEMS General	523 (MBH)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	52 (TON)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 A D304006 CHILLED WATER DISTRIBUTION SYSTEMS Circulating Pump, End Suction - 2-1/2" size, 3 HP, to 150 GPM	3 (EA)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 AHU-056 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM	1 (EA)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 AHU-061 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM	1 (EA)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 AHU-062 D304008 AIR HANDLING UNITS Rooftop - 10000 CFM	1 (EA)	1996	



System Inventory Report



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D3040 DISTRIBUTION SYSTEMS	1996 B D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating Pump, End Suction - 2-1/2" size, 3 HP, to 150 GPM	6 (EA)	2012	
	D3040 DISTRIBUTION SYSTEMS	1996 B D304006 CHILLED WATER DISTRIBUTION SYSTEMS Circulating Pump, End Suction - 2-1/2" size, 3 HP, to 150 GPM	6 (EA)	2005	
	D3040 DISTRIBUTION SYSTEMS	1996 C D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating Pump, End Suction - 2-1/2" size, 3 HP, to 150 GPM	4 (EA)	2005	
	D3040 DISTRIBUTION SYSTEMS	1996 C D304006 CHILLED WATER DISTRIBUTION SYSTEMS Circulating Pump, End Suction - 2-1/2" size, 3 HP, to 150 GPM	3 (EA)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 EF-121/97 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 800 CFM	1 (EA)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 ROOFTOP D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 800 CFM	1 (EA)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 ROOFTOP D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 8500 CFM	2 (EA)	1996	
	D3040 DISTRIBUTION SYSTEMS	1996 ROOM M101 D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating Pump, End Suction - 2-1/2" size, 3 HP, to 150 GPM	2 (EA)	2018	
	D3040 DISTRIBUTION SYSTEMS	1996 ROOM M101 D304006 CHILLED WATER DISTRIBUTION SYSTEMS Circulating Pump, End Suction - 2-1/2" size, 3 HP, to 150 GPM	3 (EA)	2018	
	D3040 DISTRIBUTION SYSTEMS	1996 ROOM M102 D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating Pump, End Suction - 2-1/2" size, 3 HP, to 150 GPM	2 (EA)	2003	
	D3040 DISTRIBUTION SYSTEMS	1996 ROOM M102 B D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating Pump, End Suction - 3" size, 5 HP, to 225 GPM	2 (EA)	1996	
	D3050 TERMINAL & PACKAGE UNITS	1996 A D305001 UNIT VENTILATORS Air Curtain	3 (LF)	1996	
	D3050 TERMINAL & PACKAGE UNITS	1996 B D305001 UNIT VENTILATORS Air Curtain	3 (LF)	1996	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 128 D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged Terminal AC, 24,000 BTUH, 10 kw	2 (EA)	2005	
	D3050 TERMINAL & PACKAGE UNITS	1996 ROOM 137D D305006 PACKAGE UNITS A/C Unit, Package Terminal - Packaged Terminal AC, 24,000 BTUH, 10 kw	1 (EA)	2005	
	D3060 CONTROLS & INSTRUMENTATION	1996 D306002 ELECTRONIC CONTROLS General	11 (EA)	1996	
	D3060 CONTROLS & INSTRUMENTATION	1996 ROOFTOP D306002 ELECTRONIC CONTROLS General	5 (EA)	1996	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SYSTEMS	1996 D401001 FIRE ALARM DISTRIBUTION Other	20,930 (SF)	1996	
	D4040 SPRINKLERS	1996 D404001 SPRINKLERS AND RELEASING DEVICES Wet Pipe Systems	20,930 (SF)	1996	



System Inventory Report



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D4090 OTHER FIRE PROTECTION SYSTEMS	1996 D409004 HOOD & DUCT FIRE PROTECTION General	2 (EA)	1996	
D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp, NQOD	2 (EA)	1996	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 D501004 PANELBOARDS Switchgear - 800 Amp	2 (EA)	1996	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1996 ROOM 138B D501004 PANELBOARDS Main lugs, 200 amp	2 (EA)	1996	
	D5020 LIGHTING & BRANCH WIRING	1996 D502001 BRANCH WIRING General	20,930 (SF)	1996	
	D5020 LIGHTING & BRANCH WIRING	1996 D502002 LIGHTING EQUIPMENT Exit Lighting	6 (EA)	1996	
	D5020 LIGHTING & BRANCH WIRING	1996 D502002 LIGHTING EQUIPMENT Exterior Lighting	3 (EA)	1996	
	D5020 LIGHTING & BRANCH WIRING	1996 D502002 LIGHTING EQUIPMENT General	20,930 (SF)	1996	
	D5030 COMMUNICATIONS & SECURITY	1996 D503002 PUBLIC ADDRESS SYSTEMS 6 outlets	1 (EA)	1996	
	D5030 COMMUNICATIONS & SECURITY	1996 D503003 INTERCOMMUNICATIONS SYSTEMS 6 stations	1 (EA)	1996	
	D5030 COMMUNICATIONS & SECURITY	1996 D503007 CLOCK & PROGRAM SYSTEMS General	1 (EA)	1996	
	D5090 OTHER ELECTRICAL SERVICES	1996 D509002 EMERGENCY LIGHTING & POWER General	20,930 (SF)	1996	
	D5090 OTHER ELECTRICAL SERVICES	1996 D509003 GROUNDING SYSTEMS General	1 (EA)	1996	
E10 EQUIPMENT	E1090 OTHER EQUIPMENT	*BRAISING PAN A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*BRAISING PAN B E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*COLD PAN SINGLE BASIN A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*COLD PAN SINGLE BASIN B E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*COLD PAN SINGLE BASIN C E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*COLD PAN SINGLE BASIN D E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*DEEP FRYER A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*DEEP FRYER B E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*DISH MACHINE A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*DISH MACHINE B E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*GRIDDLE A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*GRIDDLE B E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	



System Inventory Report



Support Site

2059 - Naples MS/HS Bldg 2059

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	E1090 OTHER EQUIPMENT	*GRIDDLE C E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*GRIDDLE D E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*GRIDDLE E E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*HOT CABINET REACH IN 2DR A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*HOT CABINET REACH IN 2DR B E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*KETTLE ELECTRIC A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*KETTLE ELECTRIC B E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*KETTLE ELECTRIC C E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2DR A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2DR B E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN B E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN C E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*STEAMER 1 DOOR A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*STEAMER 1 DOOR B E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*STEAMER 1 DOOR C E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*WALK IN COOLER E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	
	E1090 OTHER EQUIPMENT	*WALK IN FREEZER E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1996	