

Sigonella Campus

Facility Condition Assessment Report



CAMPUS SUMMARY

Year Built ¹	1999-2008
GSF ²	208,853
Date of Assessment	16-Jan-2020

¹ Indicates range of dates of construction present on campus

² Only permanent and semi-permanent facilities are included

SCHOOL SUMMARY

School	Assessed Condition		Annual Condition Report (June 2019)		2009 Congressional	Starting Grade	Ending Grade	Students
	Q-Rating	FCI	Q-Rating	FCI	Q-Rating			
Sigonella Elementary School	Q-1	98	Q-1	95	Q-2	Sure Start	Fifth	394
Sigonella Middle/High School	Q-1	94	Q-1	94	Q-2	Sixth	Twelfth	317

BUILDING SUMMARY

Building/School	Year Built	GSF	Sigonella ES (%Occupied)	Sigonella MS/HS (%Occupied)	Type
Sigonella MS/HS Bldg 211	2008	28,780	22%	78%	PERM
Sigonella ES Bldg 213	1999	12,792	100%	0%	PERM
Sigonella MS/HS Bldg 216	1999	62,613	0%	100%	PERM
Sigonella ES Bldg 218	2008	56,606	100%	0%	PERM
Sigonella MS/HS Bldg 220	2008	48,062	0%	100%	PERM

I. INTRODUCTION

The Sigonella Campus is part of Naval Air Station #1 Support Area, Naval Air Station Sigonella, Italy. This report provides a summary of findings for the physical condition assessment of buildings at this campus. The physical condition assessment includes a general description of typical building systems found and includes conditions present at the time of the site visit.

II. SCHOOL PHYSICAL DESCRIPTION

The summary below provides a physical description of the campus. When multiple systems or materials are present, the predominant system or material observed during the facility condition assessment is shown.

- a. STRUCTURAL/EXTERIOR ENCLOSURE: The building exterior is stucco. Roof coverings are clay tiles. Exterior doors are pre-finished aluminum with glazing. Window systems are pre-finished aluminum with double-glazing.
- b. INTERIORS: Floor finishes used include ceramic tile and carpet. Walls are painted hard surfaces. Ceilings are acoustical lay-in tiles.
- c. MECHANICAL: Campus facilities have heating, which is provided by package boilers. All campus facilities have air conditioning, which is provided by chilled water. The campus has four elevators.
- d. ELECTRICAL: No electrical upgrades have been completed and most wiring appears to be original. Lighting is typically surface mounted fixtures with fluorescent lamps. Ground-fault circuit interrupter (GFCI) receptacles appear to be present in required locations. The campus has an intercom system. There is a security system, and security cameras are present.
- e. PLUMBING: Plumbing fixtures have been partially upgraded and piping appears to be original. Domestic hot water is provided by gas-fired storage water heaters.
- f. SITE: The Sigonella Campus does not have dedicated parking for privately owned vehicles. In addition, Sigonella Elementary School has four playgrounds.
- g. LIFE SAFETY: A fire safety inspection report was not available for review.

III. OBSERVATIONS

The following observations were made: Exterior door security was not reported to be a problem. However, in Building 218, some of the second-floor egress doors have conflicting hardware installation as well as the egress doors at the second-floor elevated catwalk adjoining Buildings 216 and 220. This has resulted in some corridors having keyed entry locksets installed next to panic hardware, that can allow unrestricted entry. The roof flashing and drainage systems at Buildings 211, 216, 218, and 220, appear to have installation issues and several maintenance repairs are evident of previous and possibly current roof covering leaks. The exterior walls (stucco) at Buildings 211, 218, and 220, appear to have the following installation issues: general exposure corrosion of metal edge trim, crumbled wall stucco areas, and blistered paint finish at numerous locations.

Overall, the interior construction systems throughout the campus are of various ages and in good to fair condition. The only major deficiencies observed in Building 218, Room 129, were upheaving carpet and significant water damage of the partitions. It was reported, all damaged carpet throughout the campus is going to be phased out and replaced with ceramic tile. On A-Floor of Building 211, there are major sections of wall tile missing; and it was reported, the hallway wall tile is being used to repair other sections of broken tile. In Building 211, Stairwell S102.2, there are major areas of surface cracking of the partition wall finish. In Building 216, there are a total of 29 missing doors on the lockers. Also, in Building 216, there is moderate water damage below the sink in the Central Supply Room. It was reported there is an active work order submitted to fix it; however, the direct condition rating will reflect the field findings.

It appears outside air is being introduced into the HVAC system. The distribution pump motors and connected distribution piping were found moderately corroded in Building 213. The campus is reported to have regular power outages, these power surges significantly affect the major systems on-site, specifically the fire suspension system, VAV units in classrooms to switch off, and the fan coil units, which are also corroded. In Building 216, in Rooms 10 and 22, new circulating pumps were installed in FY2018. The air separators in Building 216, Room 10 and Room 22, are severely corroded on the units and piping. In addition, the air handling units in Building 216 are deteriorated on the intake pipes with minor fin corrosion inside the units. The plumbing fixtures in most restrooms are corroded underneath the handles and on the faucets.

The Facility Utilization Survey (FUS) drawings have been updated to reflect the assessment findings, including room-use and room number changes observed throughout the campus. No buildings were added or removed from the site since the time of the previous assessment. Sigonella MS/HS Building 211 is shared between Sigonella Elementary School and Sigonella Middle/High School. Finally, it was observed that one of the concrete stairwells leading down to the track has a large chunk of concrete that had broken off underneath the initial landing which could pose a potential safety hazard.

Building 211 remained a Q-1.

Building 213 remained a Q-1.

Building 216 remained a Q-2.

Building 218 remained a Q-1.

Building 220 remained a Q-1.

IV. QUALITY / CONDITION RATINGS

Table 1 shows building-specific information to include Real Property Unique Identifier (RPUID), type of construction, year built, gross area, Facility Condition Index (FCI), and Q-Rating. Table 2 shows buildings that are classified as temporary (TEMP) or relocatable (RELO) and therefore, by definition, are not included in Quality/Condition calculations.

TABLE 1: QUALITY / CONDITION RATINGS								
Photo	Building	RPUID	Type	Year Built	GSF	Assessed		Plant Replacement Value ³
						FCI	Q-Rating	
	211	10374	PERM	2008	28,780	100	Q 1	████████
	213	10376	PERM	1999	12,792	91	Q 1	████████
	216	10379	PERM	1999	62,613	87	Q 2	████████
	218	1027276	PERM	2008	56,606	100	Q 1	████████
	220	10382	PERM	2008	48,062	100	Q 1	████████

³ The Plant Replacement Value is calculated according to the DoD Facility Pricing Guide

TABLE 2: TEMPORARY / RELOCATABLE BUILDINGS					
Photo	Building	Type	Year Built	GSF	Current Use
	X213A	RELO	2000	26	Storage Shed
	X213B	RELO	2013	58	Storage Shed


TABLE 2: TEMPORARY / RELOCATABLE BUILDINGS					
Photo	Building	Type	Year Built	GSF	Current Use
	X213C	RELO	2013	58	Storage Shed
	X213D	RELO	2013	28	Storage Shed

"identification only"

Appendix A

Site Plan

"identification only"



Appendix B

Overview of Sustainment Management System (SMS) and
BUILDER™ Engineered Management System (EMS)

"identification only"

Overview of Sustainment Management System (SMS) and BUILDER™ Engineered Management System (EMS)

Sustainment Management System (SMS)

The Sustainment Management System (SMS) is a suite of web-based software applications developed by the United States Army Corps of Engineers - Engineer Research Development Center - Construction Engineering Research Laboratory (USACE-ERDC-CERL) to help facility engineers, technicians, and managers decide when, where, and how to best maintain the built environment. The SMS modules include BUILDER™ and ROOFER™ for assessing building conditions, PAVER™ for pavements, and RAILER™ for railroad infrastructure.

Because real property assets are so vast and diverse, a "knowledge-based" philosophy drives the SMS process. The process starts with the automated download of real property data, and then more detailed system inventory is modeled and/or collected which identifies components and their key life cycle attributes such as the age and material.

From this inventory, Condition Index (CI) measures for each component are predicted based on its expected stage in the life cycle. Objective and repeatable inspections can then be performed on various components to verify their condition with respect to the expected life cycle deterioration. The level of detail and frequency of these inspections are not fixed like other processes; they are dependent on knowledge of component criticality, the expected and measured condition and rate of deterioration, and remaining maintenance and service life. This "knowledge-based" inspection focuses attention to the most critical components at the time. In addition to these condition assessments, functionality assessments can be performed to evaluate user requirement changes, compliance and obsolescence issues. This provides a comprehensive picture of the overall performance of real property assets and their key components.

BUILDER Engineered Management System (EMS)

In September 2013, the Under Secretary of Defense, Frank Kendall, issued a memo indicating the Department of Defense requires a standardized process for facility condition assessments to ensure consistent and reliable data necessary for sound strategic investment decisions in managing the Department's built environment.

Establishing a DoD-wide facility condition assessment process will contribute to a more credible DoD asset management program and will support better buying power by allowing Department leadership to better target fiscal resources to those facilities most in need of investment. Further, adopting a standard process will help ensure that condition data will be audit-ready in accordance with the Under Secretary of Defense (Comptroller)'s "Financial Improvement and Readiness Guidance" issued in March 2013.

The facility condition assessment process used to generate this report is based on BUILDER Engineered Management System (EMS) Version 3. BUILDER EMS was developed by the Engineer Research and Development Center.

The facility condition assessment process addresses the requirements necessary for routine building facility management activities, including long range budgeting and sustainment/restoration/modernization (SRM) planning. This assessment approach provides an objective and generalized framework to help to identify problem areas that will require more investigation through detailed or specialized assessments. There may be times when detailed engineering assessments may be required to diagnose specific problems.

BUILDER is a software application for building asset life cycle management. The primary focus of BUILDER is work plan development. BUILDER stores real property building information and more detailed system inventory is modeled and/or collected which identifies building components and their key life cycle attributes such as the age, material and capacity. Inspections are then performed on the various components to

determine an objective and repeatable Condition Index (CI) measure, which relates the general physical health of the asset.

With information about condition and remaining service life, BUILDER guides the development of short- and long-range work plans based on sound investment strategies, prioritization criteria, and budget constraints. BUILDER consolidates a variety of building-related management issues into a single decision-support package.

The system gives functional managers and decision-makers instant access to building inventory, current building condition indices, and probabilities condition prediction models. It also employs a patented knowledge-based inspection scheduling process. BUILDER improves the allocation process and return of building life cycle investments by directing resources to the most condition critical components to avoid costly repair penalty costs, as well as, the most mission critical components to manage risks of failure.

BUILDER Facility Condition Assessment Process

Facility Condition Assessment (FCA) is one of the primary processes of a facility life cycle asset management program. The FCA process results in a better understanding of the physical condition and readiness of an organization's buildings along with the reliability of its systems and components. It also facilitates the identification of work candidates for facility SRM repair projects. It is a critical aspect of the shift towards a proactive versus reactive facility management strategy. Instead of keeping facilities operational by relying primarily on corrective repairs (after a system or component has failed due to significant loss of function), it focuses on condition-based repairs which can be planned prior to failure. A condition-based approach can result in higher performing facilities at lower life cycle costs.

Prior to an assessment, knowledge of the building systems and components present is necessary, since assessments are done against these components, not against the building as a whole. This information about the systems and components that make up a building is called the BUILDER Inventory. BUILDER has a vast library of predefined components which all assessors will select from, and the inventory collection process involves identifying the type, quantity, and year installed for all pertinent components. These components are also organized into systems and sub-systems according to the UNIFORMAT classification hierarchy. When a specific instance of a component is recorded, this is called a component-section in BUILDER, and represents a single component assembly or collection of like components to be managed as a single unit. The BUILDER facility condition assessment process directly supports the computation of a condition index for building component-sections, known as the Component-Section Condition Index (CSCI), which is the fundamental metric used in BUILDER. The CSCI is aggregated to compute a condition index metric at the system (SCI), building (BCI), and site/organizational level.

A condition-based facility repair strategy requires condition information be collected at a component level, and that this condition information relate to loss of component function. Every component of a building has a primary function that it performs. This function is the reason that the component was constructed or installed in the building. It may also serve a number of secondary or tertiary functions. For example, for a door component, the primary function is to provide safe entry/egress of authorized movements while limiting unwanted movements of people (security), or other objects (water or moisture). The secondary functions would relate to aesthetics and thermal and air control, among others.

The condition assessment process in BUILDER uses the Direct Rating method.

1. The **Direct Rating** method uses a single qualitative rating for each component based on condition observations. This also results in a condition index metric, which relates to the level of deterioration and the loss of function. This abbreviated Direct Rating approach is often better suited to initial baseline assessments where the components are inventoried, and data is initially loaded into BUILDER.

The following figure illustrates the Direct Rating criteria used in this assessment.

RATING	SRM NEEDS	RATING DEFINITION
Green (+)	Sustainment consisting of possible preventive maintenance (where applicable)	Entire component-section or component-section sample is free of observable or known distress.
Green	Sustainment consisting of possible preventive maintenance (where applicable) and minor repairs (corrective maintenance) to possibly few or some subcomponents.	No component-section or sample serviceability* or reliability* reduction. Some, but not all minor (non-critical) subcomponents may suffer from slight degradation or few major (critical) subcomponents may suffer from slight degradation.
Green (-)		Slight or no serviceability or reliability or reliability reduction overall to the component-section or sample. Some, but not all minor (non-critical) subcomponents may suffer from slight degradation or more than one major (critical) subcomponents may suffer from slight degradation.
Amber (+)	Sustainment or restoration to any of the following: Minor repairs to several sub-components; or Significant repair, rehabilitation or replacement of one or more subcomponents, but not enough to encompass the component-section as a whole; or Combinations thereof.	Component-section or sample serviceability or reliability is degraded, but adequate. A very few major (critical) subcomponents may suffer from moderate deterioration with perhaps a few minor (non-critical) subcomponents suffering from severe deterioration.
Amber		Component-section or sample serviceability or reliability is definitely impaired. Some, but not a majority of major (critical) subcomponents may suffer from moderate deterioration with perhaps many minor (non-critical) subcomponents suffering from severe deterioration.
Amber (-)		Component-section or sample has significant serviceability or reliability loss. Most subcomponents may suffer from moderate degradation or a few major (critical) subcomponents may suffer from severe degradation.
Red (+)	Sustainment or restoration required consisting of major repair, rehabilitation or replacement to the component-section as a whole.	Significant serviceability or reliability reduction in component-section or sample. A majority of subcomponents are severely degraded, and others may have varying degrees of degradation.
Red		Severe serviceability or reliability reduction to the component-section or sample such that it is barely able to perform. Most subcomponents are severely degraded.
Red (-)		Overall component-section degradation is total. Few, if any subcomponents are salvageable. Complete loss of component-section or sample serviceability.

Once the component-sections have been rated with a Direct Rating, BUILDER calculates the Component-Section Condition Index (CSCI) of the component-section. The next step in the process is to create a work plan, which will list the component-sections that need repair or replacement and the estimated cost of the repair or replacement.

To create a work plan, condition standards, policies and a policy sequence are created. The standards serve as thresholds for CSCI and remaining service life. Policies link standards to component-sections and policy sequences link standards and policies together.

The table below summarizes the DoDEA standards and how they are applied to the component-sections for this assessment.

Standard and Component-section Cross-Reference		
Standard	CI Threshold	Component-section
Amber +	80	D4010 FIRE ALARM AND DETECTION SYSTEMS
Amber	71	B3010 ROOF COVERINGS D1010 ELEVATORS AND LIFTS D2010 PLUMBING FIXTURES D3020 HEAT GENERATING SYSTEMS D3030 COOLING GENERATING SYSTEMS D3040 DISTRIBUTION SYSTEMS (A) D3050 TERMINAL & PACKAGE UNITS D3060 CONTROLS & INSTRUMENTATION D3090 OTHER HVAC SYSTEMS AND EQUIPMENT D4020 FIRE SUPP WATER SUPPLY / EQUIP D4030 STANDPIPE SYSTEMS D4040 SPRINKLERS D4050 FIRE PROTECTION SPECIALTIES D4090 OTHER FIRE PROTECTION SYSTEMS D5010 ELECTRICAL SERVICE & DISTRIBUTION D5020 LIGHTING & BRANCH WIRING D5030 COMMUNICATIONS & SECURITY D5090 OTHER ELECTRICAL SERVICES
Amber -	61	B2030 EXTERIOR DOORS C1020 INTERIOR DOORS C3010 WALL FINISHES C3020 FLOOR FINISHES C3030 CEILING FINISHES C3040 INT COATINGS / SPECIAL FINISHES D3010 ENERGY SUPPLY
Red +	50	B2010 EXTERIOR WALLS B2020 EXTERIOR WINDOWS C1030 SPECIALTIES D1020 WEIGHT HANDLING EQUIPMENT D1030 ESCALATORS AND MOVING WALKS D1090 OTHER CONVEYING SYSTEMS D2020 DOMESTIC WATER DISTRIBUTION D2030 SANITARY WASTE D2040 RAIN WATER DRAINAGE D2090 OTHER PLUMBING SYSTEMS D3070 SYSTEMS TESTING & BALANCING
Service Life	40	Paint

For this project, the following building components are not included in the BUILDER Inventory and are not evaluated during the assessment unless significant damage or deterioration was observed or reported.

- A1010 STANDARD FOUNDATIONS
- A1020 SPECIAL FOUNDATIONS
- A1030 SLAB ON GRADE
- A2010 BASEMENT EXCAVATION
- A2020 BASEMENT WALLS
- B1010 FLOOR CONSTRUCTION
- B1020 ROOF CONSTRUCTION
- B2010 EXTERIOR WALLS
- C1010 PARTITIONS
- C2010 STAIR CONSTRUCTION

Damage that is not visible or that is unknown will not be reflected in facility condition index calculations. It is anticipated that unknown damage or deterioration is more likely to be present in older facilities than more modern facilities.

In addition, some building components are concealed or inaccessible. In accordance with BUILDER guidelines, quantities for concealed and inaccessible components have been estimated and recorded in the BUILDER Inventory but have not been rated. When concealed or inaccessible components are encountered, life cycle data contained within BUILDER is used to predict renewal requirements, which are included in facility condition index calculations. Components that are often concealed or inaccessible include:

- D2020 DOMESTIC WATER PIPING
- D2030 SANITARY WASTE PIPING
- D3040 HVAC DISTRIBUTION
- D4010 FIRE ALARM DISTRIBUTION
- D5020 ELECTRICAL BRANCH CIRCUITS

In addition to the building components noted above, if a building component is concealed or inaccessible, life cycle data contained within BUILDER is used to predict renewal requirements.

When a work plan is created, the CSCI of a component-section is compared to its associated standard. If the CSCI is less than or equal to the threshold in the standard, the remaining service life is evaluated. If the service life is less than the standard's remaining service life, BUILDER will add this section to the work plan and generate dollars to estimate a cost for the replacement.

If the CSCI is less than or equal to the threshold in the standard and the service life is greater than the standard's remaining service life, BUILDER will conduct a cost benefit analysis. The cost benefit analysis will determine whether the component-section should be repaired or left to expire at the end of its service life. When BUILDER determines a repair is the correct action, BUILDER will add this section to the work plan and generate dollars to estimate a cost for the repair.

When BUILDER determines taking no action is more cost effective, BUILDER will not add the component-section to the work plan. For example, if the CSCI for an external door component-section is 50 with a remaining service life of five years, BUILDER will compare the CSCI of 50 to the CI Threshold set by DoDEA and determine that 50 is less than the threshold of 61. BUILDER will compare the five years of remaining service life against the zero years of the threshold and determine a cost benefit analysis is required. The results of the cost benefit analysis will typically suggest to take no action and let the component-section run until the end of its service life before generating an item in the work plan.

A typical life cycle of a component-section is explained below.

Condition	Work Plan
CSCI > threshold	Work plan does not generate an item for the component-section
CSCI = threshold or just below it	Work plan will generate a repair item for the component-section
CSCI < threshold and the remaining service life > service life threshold	Work plan will remove the repair item for the component-section. It is too costly to repair so it is better to wait to replace it.
Remaining service life < service life threshold	Work plan will generate a replace item for the component-section

Facility Condition Assessment Data Analysis

In multiple building portfolios and especially with widespread geographic portfolios, it is important to know how building conditions compare. The Condition Index (CI) and Quality Ratings (Q-Ratings) are determined for each building assessed using guidelines shown below.

Condition Index (CI) – A measure of the constructed asset's condition at a specific point in time with respect to physical condition and ability to support the current occupant or mission. CI is calculated as the ratio of estimated cost of maintenance and repair requirements to Plant Replacement Value (PRV). Maintenance and repair requirements consist of that work necessary to ensure that a constructed asset is restored to a condition substantially equivalent to the originally intended and designed capacity, efficiency or capability. The formula for Condition Index is:

$$CI = 1 - \left(\frac{\text{Requirements}}{\text{PRV}} \right) \times 100$$

Q-Rating Bands – Bands allow OSD, Military Services, and Defense Agencies/Activities to group facilities by condition for the purposes of developing investment strategies.

TABLE 1: Q-RATING DESCRIPTIONS		
Rating Band	Calculated Rating (Condition Index)	General Description
Q-1	100 to 90	Facility is new or well-maintained (Good Condition)
Q-2	89 to 80	Facility is satisfactorily maintained (Fair Condition)
Q-3	79 to 60	Facility is under maintained (Poor Condition)
Q-4	59 to 0	Facility should be considered for replacement (Failing Condition)

Requirements – Sum of the work items from BUILDER.

Plant Replacement Value – Cost to design and construct a notional facility to current standards to replace an existing facility on the same site, (reference United Facilities Criteria UFC 3-701-01 23 May 2018, Change 3, 29 July 2019).

BUILDER Report Overview

Outlined below is a summary and description of the reports that are included.

Appendix C - Facility Summary Report – Provides a summation of FCA results. A Building Summary Report is included for each building that is considered permanent or semi-permanent construction and receives a Q-Rating. The purpose of this report is to provide a general overview of the building including key performance indicators. This report was generated using DoDEA's calculated Replacement Cost overwriting the data populated from real property records. This provides a more accurate Replacement Cost due to the inconsistencies with real property reconciliation between DoDEA and the Services. The DoD Facility Pricing Guide and DoDEA measurements for building square footage were used to calculate the Replacement Cost.

Appendix D - System Summary Report – Provides an overview of inspected systems and their condition index rating. A Building System Condition Index (SCI) By System Report is included for each building that is considered permanent or semi-permanent construction and receives a Q-Rating.

Appendix E - Work Items By Building – Provides a list of work items requiring repair or replacement of system/components, including budgets, for project planning purposes. A Work Plan Detail by Year Report is included for each building that is considered permanent or semi-permanent construction and receives a Q-Rating.

Appendix F - Remaining Service Life (RSL) Detail Report – Provides a detailed overview of systems/components, including descriptions, and their respective age, remaining service life and remaining paint life.

Appendix G - Direct Condition Rating Inspection By Section Report – Provides a summary of direct condition ratings for each component-section collected within each facility.

Appendix H - System Inventory Report – Provides a list of details for each component-section collected within each facility.

Appendix I - Fire Inspection Safety Report – This appendix is only applicable when a Fire Inspection Safety Report is provided at the time of the assessment for inclusion in the Facility Condition Assessment Report. The report provides a summary of the recent Fire Inspection to include any deficiencies.

Note: All reports are generated from the DoDEA BUILDER database. In the event line items within a report are compressed and difficult to read, this is a result of how BUILDER generates the report. It is our understanding that CERL is working to update the report format.

Summary of Terms

Acronyms	Description
BCI	Building Condition Index - Measures the condition of the building as a whole. The higher the BCI, the better.
BFI	Building Functionality Index - Measures the functionality of a building as a whole. The higher the BFI, the better.
BPI	Building Performance Index - Measures the overall performance of a building. The higher the BPI, the better.
EA	Each
ESC	Emergency Service Call
FCI	Facility Condition Index - The current maintenance, repair, and replacement deficiencies of the facility divided by the current replacement value of the facility, derives the FCI of a facility. The higher the FCI, the better.
GSF	Gross Square Foot
ISR	Installation Status Report - Measures installation condition against Army-wide standards.
LF	Linear Feet
MBH	Thousands of BTU per hour.
MDI	Mission Dependency Index - Measures how critical a facility is to the overall mission of its owner. The higher the MDI, the more critical.
PERM	Permanent
RELO	Relocatable
RPL	Remaining Paint Life - Displays the remaining paint life, in years, of a section.
RPUID	Real Property Unique Identifier - The unique identification number assigned to each asset.
RSL	Remaining Service Life - Displays the remaining service life, in years, of a section.
SCI	System Condition Index - Measures the condition of a system as a whole. The higher the SCI, the better.
SF	Square Foot
TEMP	Temporary
UM	Unit of Measure

Appendix C

Facility Summary Report

"identification only"

213 - Sigonella ES Bldg 213

NAS1 Support Area - Sigonella ES



YEAR BUILT: 1999

AREA (SF): 12,792

PLANT REPLACEMENT COST: [REDACTED]

SURVEY DATE: January 2020

TOTAL DEFICIENCIES: [REDACTED]

BUILDER(TM) METRIC		SCORE
Facility Condition Index	FCl:	91

218 - Sigonella ES Bldg 218

NAS1 Support Area - Sigonella ES



YEAR BUILT: 2008

AREA (SF): 56,606

PLANT REPLACEMENT COST: [REDACTED]

SURVEY DATE: January 2020

TOTAL DEFICIENCIES: [REDACTED]

BUILDER(TM) METRIC		SCORE
Facility Condition Index	FCI:	100

216 - Sigonella MS/HS Bldg 216

NAS1 Support Area - Sigonella MS/HS



YEAR BUILT: 1999

AREA (SF): 62,613

PLANT REPLACEMENT COST: [REDACTED]

SURVEY DATE: January 2020

TOTAL DEFICIENCIES: [REDACTED]

BUILDER(TM) METRIC		SCORE
Facility Condition Index	FCI:	87

220 - Sigonella MS/HS Bldg 220

NAS1 Support Area - Sigonella MS/HS



YEAR BUILT: 2008

AREA (SF): 48,063

PLANT REPLACEMENT COST: [REDACTED]

SURVEY DATE: January 2020

TOTAL DEFICIENCIES: [REDACTED]

BUILDER(TM) METRIC		SCORE
Facility Condition Index	FCI:	100

211 - Sigonella MS/HS Bldg 211

NAS1 Support Area - Unassigned



YEAR BUILT: 2008

AREA (SF): 28,780

PLANT REPLACEMENT COST: [REDACTED]

SURVEY DATE: January 2020

TOTAL DEFICIENCIES: [REDACTED]

BUILDER(TM) METRIC		SCORE
Facility Condition Index	FCI:	100

Appendix D

System Summary Report

"identification only"

DoDEA SYSTEM SUMMARY

NAS1 Support Area

Complex	Building #	Building Name	A10	A20	B10	B20	B30	C10	C20	C30	D10	D20	D30	D40	D50	E10	E20	F10	F20	G10	G20	G30	G40	G90
Sigonella ES	213	Sigonella ES Bldg 213			84	86	76	81	87	75		83	62	74	76									
Sigonella ES	218	Sigonella ES Bldg 218				68	67	84	79	84		94	76	91	84									
Sigonella MS/HS	216	Sigonella MS/HS Bldg 216				83	68	69	86	84	79	83	46	74	78	94								
Sigonella MS/HS	220	Sigonella MS/HS Bldg 220				65	70	81	72	82	79	93	80	91	84									
Unassigned	211	Sigonella MS/HS Bldg 211			88	64	67	85	84	79	85	94	69	91	82	95								

A10 - Foundations

A20 - Basement Construction

B10 - Superstructure

B20 - Exterior Enclosure

B30 - Roofing

C10 - Interior Construction

C20 - Stairs

C30 - Interior Finishes

D10 - Conveying

D20 - Plumbing

D30 - HVAC

D40 - Fire Protection

D50 - Electrical

E10 - Equipment

F20 - Furnishings

F10 - Special Construction

F20 - Selective Building Demo

G10 - Site Preparations

G20 - Site Improvements

G30 - Site Civil / Mech Utilities

G40 - Site Electrical Utilities

G50 - Other Site Construction

Appendix E

Work Items By Building

"identification only"

NAS1 Support Area

Cost Book: Reference

211 - Sigonella MS/HS Bldg 211

Unassigned

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
2015	B20 EXTERIOR ENCLOSURE							
	B2010 EXTERIOR WALLS	20,305 (SF)	Paint					0.00
	2008 B201001 EXTERIOR CLOSURE Stucco							
	-- Paint B2010 EXTERIOR WALLS 2008 B201001 EXTERIOR CLOSURE Stucco							
	B2010 EXTERIOR WALLS	351 (SF)	Paint					0.00
	2008 B201005 EXTERIOR LOUVERS & SCREENS General							
	-- Paint B2010 EXTERIOR WALLS 2008 B201005 EXTERIOR LOUVERS & SCREENS General							
	B2010 EXTERIOR WALLS	3,790 (SF)	Paint					0.00
	2008 B201007 EXTERIOR SOFFITS General							
	-- Paint B2010 EXTERIOR WALLS 2008 B201007 EXTERIOR SOFFITS General							
	B2010 EXTERIOR WALLS	600 (LF)	Replace					0.00
	2008 A B201010 EXTERIOR JOINT SEALANT General							
	-- Replace B2010 EXTERIOR WALLS 2008 B201010 EXTERIOR JOINT SEALANT General							
2015	B30 ROOFING							
	B3010 ROOF COVERINGS	511 (LF)	Paint					0.00
	2008 B301005 GUTTERS & DOWNSPOUTS Downspouts							
	-- Paint B3010 ROOF COVERINGS 2008 B301005 GUTTERS & DOWNSPOUTS Downspouts							
2015	C30 INTERIOR FINISHES							
	C3020 FLOOR FINISHES	1,695 (SF)	Replace					0.00
	2008 C302005 CARPETING General							
	-- Replace C3020 FLOOR FINISHES 2008 C302005 CARPETING General							
2016	B20 EXTERIOR ENCLOSURE							
	B2010 EXTERIOR WALLS	20,305 (SF)	Paint					0.00
	2008 B201001 EXTERIOR CLOSURE Stucco							
	-- Paint B2010 EXTERIOR WALLS 2008 B201001 EXTERIOR CLOSURE Stucco							

NAS1 Support Area

Cost Book: Reference

211 - Sigonella MS/HS Bldg 211

Unassigned

Year	System	Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score
			-- Description				Completion Date		
B2010	EXTERIOR WALLS	351 (SF)	Paint						0.00
2008	B201005 EXTERIOR LOUVERS & SCREENS	General							
-- Paint B2010 EXTERIOR WALLS 2008 B201005 EXTERIOR LOUVERS & SCREENS General									
B2010	EXTERIOR WALLS	3,790 (SF)	Paint						0.00
2008	B201007 EXTERIOR SOFFITS	General							
-- Paint B2010 EXTERIOR WALLS 2008 B201007 EXTERIOR SOFFITS General									
B2010	EXTERIOR WALLS	600 (LF)	Replace						0.00
2008	A B201010 EXTERIOR JOINT SEALANT	General							
-- Replace B2010 EXTERIOR WALLS 2008 B201010 EXTERIOR JOINT SEALANT General									
2016	B30 ROOFING								
B3010	ROOF COVERINGS	511 (LF)	Paint						0.00
2008	B301005 GUTTERS & DOWNSPOUTS	Downspouts							
-- Paint B3010 ROOF COVERINGS 2008 B301005 GUTTERS & DOWNSPOUTS Downspouts									
2016	C30 INTERIOR FINISHES								
C3020	FLOOR FINISHES	1,695 (SF)	Replace						0.00
2008	C302005 CARPETING	General							
-- Replace C3020 FLOOR FINISHES 2008 C302005 CARPETING General									
2017	B20 EXTERIOR ENCLOSURE								
B2010	EXTERIOR WALLS	20,305 (SF)	Paint						0.00
2008	B201001 EXTERIOR CLOSURE	Stucco							
-- Paint B2010 EXTERIOR WALLS 2008 B201001 EXTERIOR CLOSURE Stucco									
B2010	EXTERIOR WALLS	351 (SF)	Paint						0.00
2008	B201005 EXTERIOR LOUVERS & SCREENS	General							
-- Paint B2010 EXTERIOR WALLS 2008 B201005 EXTERIOR LOUVERS & SCREENS General									



Work Items by Building Report



NAS1 Support Area

Cost Book: Reference

211 - Sigonella MS/HS Bldg 211

Unassigned

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
	B2010 EXTERIOR WALLS		3,700 (SF)	Paint				0.00
	2008 B201007 EXTERIOR SOFFITS General							
	-- Paint B2010 EXTERIOR WALLS 2008 B201007 EXTERIOR SOFFITS General							
	B2010 EXTERIOR WALLS		600 (LF)	Replace				0.00
	2008 A B201010 EXTERIOR JOINT SEALANT General							
	-- Replace B2010 EXTERIOR WALLS 2008 B201010 EXTERIOR JOINT SEALANT General							
2017	B30 ROOFING							
	B3010 ROOF COVERINGS		511 (LF)	Paint				0.00
	2008 B301005 GUTTERS & DOWNSPOUTS Downspouts							
	-- Paint B3010 ROOF COVERINGS 2008 B301005 GUTTERS & DOWNSPOUTS Downspouts							
2017	C10 INTERIOR CONSTRUCTION							
	C1010 PARTITIONS		41,597 (SF)	Paint				0.00
	2008 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing							
	-- Paint C1010 PARTITIONS 2008 C101001 FIXED PARTITIONS General							
	C1030 SPECIALTIES		37 (LF)	Replace				0.00
	2008 C103008 COUNTERS Laminated Plastic							
	-- Replace C1030 SPECIALTIES 2008 C103008 COUNTERS General							
2017	C30 INTERIOR FINISHES							
	C3020 FLOOR FINISHES		1,695 (SF)	Replace				0.00
	2008 C302005 CARPETING General							
	-- Replace C3020 FLOOR FINISHES 2008 C302005 CARPETING General							
2018	B20 EXTERIOR ENCLOSURE							
	B2010 EXTERIOR WALLS		30,536 (SF)	Paint				0.00
	2008 B201001 EXTERIOR CLOSURE Stucco							
	-- Paint B2010 EXTERIOR WALLS 2008 B201001 EXTERIOR CLOSURE Stucco							

NAS1 Support Area

Cost Book: Reference

211 - Sigonella MS/HS Bldg 211

Unassigned

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score	Completion Date
-- Description									
B2010	EXTERIOR WALLS	351 (SF)	Paint					0.00	
2008	B201005 EXTERIOR LOUVERS & SCREENS General								
-- Paint B2010 EXTERIOR WALLS 2008 B201005 EXTERIOR LOUVERS & SCREENS General									
B2010	EXTERIOR WALLS	3,790 (SF)	Paint					0.00	
2008	B201007 EXTERIOR SOFFITS General								
-- Paint B2010 EXTERIOR WALLS 2008 B201007 EXTERIOR SOFFITS General									
B2010	EXTERIOR WALLS	600 (LF)	Replace					0.00	
2008	A B201010 EXTERIOR JOINT SEALANT General								
-- Replace B2010 EXTERIOR WALLS 2008 A B201010 EXTERIOR JOINT SEALANT General									
B2010	EXTERIOR WALLS	600 (LF)	Replace					0.00	
2008	A B201010 EXTERIOR JOINT SEALANT General								
-- Replace B2010 EXTERIOR WALLS 2008 A B201010 EXTERIOR JOINT SEALANT General									
2019 C30 INTERIOR FINISHES									
C3020	FLOOR FINISHES	1,695 (SF)	Replace					0.00	
2008	C302005 CARPETING General								
-- Replace C3020 FLOOR FINISHES 2008 C302005 CARPETING Carpet Tile									
2020 B20 EXTERIOR ENCLOSURE									
B2010	EXTERIOR WALLS	600 (LF)	Replace					0.00	
2008	A B201010 EXTERIOR JOINT SEALANT General								
-- Replace B2010 EXTERIOR WALLS 2008 A B201010 EXTERIOR JOINT SEALANT General									
2020 C30 INTERIOR FINISHES									
C3020	FLOOR FINISHES	1,662 (SF)	Replace					0.00	
2008	C302005 CARPETING General								
-- Replace C3020 FLOOR FINISHES 2008 C302005 CARPETING General									

NAS1 Support Area

Cost Book: Reference

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Year	System	Component	Qty (UM)	Activity	Project	Cost	Status	Score
Section Description								
-- Description								
2015	B20 EXTERIOR ENCLOSURE							
	B2010 EXTERIOR WALLS	105 (SF)	Paint					0.00
	1999 B201005 EXTERIOR LOUVERS & SCREENS General							
	-- Paint B2010 EXTERIOR WALLS 1999 B201005 EXTERIOR LOUVERS & SCREENS General							
	B2010 EXTERIOR WALLS	161 (LF)	Paint					0.00
	1999 B201006 BALCONY WALLS & HANDRAILS Handrailing							
	-- Paint B2010 EXTERIOR WALLS 1999 B201006 BALCONY WALLS & HANDRAILS Handrailing							
	B2010 EXTERIOR WALLS	2,127 (SF)	Paint					0.00
	1999 B201007 EXTERIOR SOFFITS General							
	-- Paint B2010 EXTERIOR WALLS 1999 B201007 EXTERIOR SOFFITS General							
	B2010 EXTERIOR WALLS	5,113 (SF)	Paint					0.00
	1999 A B201001 EXTERIOR CLOSURE Stucco							
	-- Paint B2010 EXTERIOR WALLS 1999 B201001 EXTERIOR CLOSURE Stucco							
	B2010 EXTERIOR WALLS	488 (LF)	Replace					0.00
	1999 A B201010 EXTERIOR JOINT SEALANT General							
	-- Replace B2010 EXTERIOR WALLS 1999 B201010 EXTERIOR JOINT SEALANT General							
	B2010 EXTERIOR WALLS	390 (SF)	Paint					0.00
	1999 B B201001 EXTERIOR CLOSURE Stucco							
	-- Paint B2010 EXTERIOR WALLS 1999 Grey B201001 EXTERIOR CLOSURE Stucco							
2015	B30 ROOFING							
	B3010 ROOF COVERINGS	989 (LF)	Paint					0.00
	1999 B301005 GUTTERS & DOWNSPOUTS Downspouts							
	-- Paint B3010 ROOF COVERINGS 1999 B301005 GUTTERS & DOWNSPOUTS Downspouts							
2015	C20 STAIRS							

NAS1 Support Area

Cost Book: Reference

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Year	System	Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score	Completion Date
-- Description										
			C2010 STAIR CONSTRUCTION	30 (LF)	Paint				0.00	
			1999 B C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General							
			-- Paint C2010 STAIR CONSTRUCTION 1999 Exterior C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General							
2015	D30	HVAC								
			D3030 COOLING GENERATING SYSTEMS	1 (EA)	Replace				0.00	
			1999 OUTSIDE D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 60 TN							
			-- Replace D3030 COOLING GENERATING SYSTEMS CH York D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 60 TN							
2016	B20	EXTERIOR ENCLOSURE								
			B2010 EXTERIOR WALLS	102 (SF)	Paint				0.00	
			1999 B201005 EXTERIOR LOUVERS & SCREENS General							
			-- Paint B2010 EXTERIOR WALLS 1999 B201005 EXTERIOR LOUVERS & SCREENS General							
			B2010 EXTERIOR WALLS	2,127 (SF)	Paint				0.00	
			1999 B201007 EXTERIOR SOFFITS General							
			-- Paint B2010 EXTERIOR WALLS 1999 B201007 EXTERIOR SOFFITS General							
			B2010 EXTERIOR WALLS	5,113 (SF)	Paint				0.00	
			1999 A B201001 EXTERIOR CLOSURE Stucco							
			-- Paint B2010 EXTERIOR WALLS 1999 B201001 EXTERIOR CLOSURE Stucco							
			B2010 EXTERIOR WALLS	488 (LF)	Replace				0.00	
			1999 A B201010 EXTERIOR JOINT SEALANT General							
			-- Replace B2010 EXTERIOR WALLS 1999 B201010 EXTERIOR JOINT SEALANT General							
			B2010 EXTERIOR WALLS	390 (SF)	Paint				0.00	
			1999 B B201001 EXTERIOR CLOSURE Stucco							
			-- Paint B2010 EXTERIOR WALLS 1999 Grey B201001 EXTERIOR CLOSURE Stucco							
2016	B30	ROOFING								

NAS1 Support Area

Cost Book: Reference

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
	B3010 ROOF COVERINGS	1999 B301005 GUTTERS & DOWNSPOUTS Downspouts	983 (LF)	Paint				0.00
-- Paint B3010 ROOF COVERINGS 1999 B301005 GUTTERS & DOWNSPOUTS Downspouts								
2016	C20 STAIRS							
	C2010 STAIR CONSTRUCTION	1999 B C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General	30 (LF)	Paint				0.00
-- Paint C2010 STAIR CONSTRUCTION 1999 Exterior C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General								
2016	D20 PLUMBING							
	D2010 PLUMBING FIXTURES	1999 D201002 URINALS General	7 (EA)	Repair				0.00
-- Repair D2010 PLUMBING FIXTURES D201002 URINALS General								
2016	D30 HVAC							
	D3030 COOLING GENERATING SYSTEMS	1999 OUTSIDE D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 60 TN	1 (EA)	Replace				0.00
-- Replace D3030 COOLING GENERATING SYSTEMS CH York D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 60 TN								
2017	B20 EXTERIOR ENCLOSURE							
	B2010 EXTERIOR WALLS	1999 B201005 EXTERIOR LOUVERS & SCREENS General	102 (SF)	Paint				0.00
-- Paint B2010 EXTERIOR WALLS 1999 B201005 EXTERIOR LOUVERS & SCREENS General								
	B2010 EXTERIOR WALLS	1999 B201006 BALCONY WALLS & HANDRAILS Handrailing	161 (LF)	Replace				0.00
-- Replace B2010 EXTERIOR WALLS 1999 B201006 BALCONY WALLS & HANDRAILS Handrailing								
	B2010 EXTERIOR WALLS	1999 B201007 EXTERIOR SOFFITS General	2,127 (SF)	Paint				0.00
-- Paint B2010 EXTERIOR WALLS 1999 B201007 EXTERIOR SOFFITS General								

NAS1 Support Area

Cost Book: Reference

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Year	System Component	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
Section Description							
-- Description							
B2010	EXTERIOR WALLS	5,143 (SF)	Paint				0.00
1999 A	B201001 EXTERIOR CLOSURE Stucco						
-- Paint B2010 EXTERIOR WALLS 1999 B201001 EXTERIOR CLOSURE Stucco							
B2010	EXTERIOR WALLS	488 (LF)	Replace				0.00
1999 A	B201010 EXTERIOR JOINT SEALANT General						
-- Replace B2010 EXTERIOR WALLS 1999 B201010 EXTERIOR JOINT SEALANT General							
B2010	EXTERIOR WALLS	390 (SF)	Paint				0.00
1999 B	B201001 EXTERIOR CLOSURE Stucco						
-- Paint B2010 EXTERIOR WALLS 1999 Grey B201001 EXTERIOR CLOSURE Stucco							
2017	C10 INTERIOR CONSTRUCTION						
C1010	PARTITIONS	57,948 (SF)	Paint				0.00
1999	C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing						
-- Paint C1010 PARTITIONS 1999 C101001 FIXED PARTITIONS General							
C1030	SPECIALTIES	1,548 (LF)	Replace				0.00
1999	C103010 CASEWORK General						
-- Replace C1030 SPECIALTIES 1999 C103010 CASEWORK General							
2017	C20 STAIRS						
C2010	STAIR CONSTRUCTION	790 (LF)	Paint				0.00
1999 A	C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
-- Paint C2010 STAIR CONSTRUCTION 1999 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General							
C2010	STAIR CONSTRUCTION	30 (LF)	Paint				0.00
1999 B	C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
-- Paint C2010 STAIR CONSTRUCTION 1999 Exterior C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General							
2017	C30 INTERIOR FINISHES						



Work Items by Building Report



NAS1 Support Area

Cost Book: Reference

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Year	System Component	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description							
	C3030 CEILING FINISHES	8,831 (SF)	Paint				0.00
	1999 C303002 GYPSUM WALLBOARD CEILING FINISHES General						
	-- Paint C3030 CEILING FINISHES 1999 C303002 GYPSUM WALLBOARD CEILING FINISHES General						
	C3030 CEILING FINISHES	15,437 (SF)	Paint				0.00
	1999 C303003 PLASTER CEILING FINISHES General						
	-- Paint C3030 CEILING FINISHES 1999 C303003 PLASTER CEILING FINISHES General						
2017	D30 HVAC						
	D3030 COOLING GENERATING SYSTEMS	1 (EA)	Replace				0.00
	1999 OUTSIDE D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 60 TN						
	-- Replace D3030 COOLING GENERATING SYSTEMS CH York D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 60 TN						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Repair				0.00
	1999 ATTIC D304008 AIR HANDLING UNITS Central Station - 2000 CFM						
	-- Repair D3040 DISTRIBUTION SYSTEMS AHU/6A D304008 AIR HANDLING UNITS Central Station - 2000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Repair				0.00
	1999 ATTIC AHU-5 D304008 AIR HANDLING UNITS Central Station - 2000 CFM						
	-- Repair D3040 DISTRIBUTION SYSTEMS AHU/5 D304008 AIR HANDLING UNITS Central Station - 2000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Repair				0.00
	1999 ATTIC MAU-6 D304008 AIR HANDLING UNITS Central Station - 10000 CFM						
	-- Repair D3040 DISTRIBUTION SYSTEMS MAHU/6 D304008 AIR HANDLING UNITS Central Station - 10000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Repair				0.00
	1999 ROOM 22 D304008 AIR HANDLING UNITS Central Station - 2000 CFM						
	-- Repair D3040 DISTRIBUTION SYSTEMS AHU/1 D304008 AIR HANDLING UNITS Central Station - 2000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Repair				0.00
	1999 ROOM G61 AHU 2 D304008 AIR HANDLING UNITS Central Station - 5000 CFM						
	-- Repair D3040 DISTRIBUTION SYSTEMS AHU/2 D304008 AIR HANDLING UNITS Central Station - 5000 CFM						

NAS1 Support Area

Cost Book: Reference

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Year	System Component	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description							
	D3040 DISTRIBUTION SYSTEMS	2 (EA)	Repair				0.00
	1999 ROOM G61 AHU 3 D304008 AIR HANDLING UNITS Central Station - 5000 CFM						
	-- Repair D3040 DISTRIBUTION SYSTEMS AHU/3 D304008 AIR HANDLING UNITS Central Station - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Repair				0.00
	1999 ROOM G61 AHU 4 D304008 AIR HANDLING UNITS Central Station - 2000 CFM						
	-- Repair D3040 DISTRIBUTION SYSTEMS AHU/4 D304008 AIR HANDLING UNITS Central Station - 2000 CFM						
	D3050 TERMINAL & PACKAGE UNITS	24 (EA)	Repair				0.00
	1999 D305003 FAN COIL UNITS Cab Mount, Four Pipe - 3 ton						
	-- Repair D3050 TERMINAL & PACKAGE UNITS Classroom FCUs D305003 FAN COIL UNITS Cab Mount, Four Pipe - 3 ton						
	D3050 TERMINAL & PACKAGE UNITS	15 (EA)	Repair				0.00
	1999 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton						
	-- Repair D3050 TERMINAL & PACKAGE UNITS Ceiling unit heaters D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton						
	D3060 CONTROLS & INSTRUMENTATION	58 (EA)	Repair				0.00
	1999 D306002 ELECTRONIC CONTROLS General						
	-- Repair D3060 CONTROLS & INSTRUMENTATION D306001 HVAC CONTROLS General						
2017	D50 ELECTRICAL						
	D5030 COMMUNICATIONS & SECURITY	1 (EA)	Repair				0.00
	1999 D503003 INTERCOMMUNICATIONS SYSTEMS 25 stations						
	-- Repair D5030 COMMUNICATIONS & SECURITY D503003 INTERCOMMUNICATIONS SYSTEMS 25 stations						
	D5090 OTHER ELECTRICAL SERVICES	3 (EA)	Repair				0.00
	1999 D509002 EMERGENCY LIGHTING & POWER Uninterruptible Power Supply - 0.5 kVA						
	-- Repair D5090 OTHER ELECTRICAL SERVICES D509002 EMERGENCY LIGHTING & POWER Uninterruptible Power Supply						
2018	B20 EXTERIOR ENCLOSURE						
	B2010 EXTERIOR WALLS	2,127 (SF)	Paint				0.00
	1999 B201007 EXTERIOR SOFFITS General						
	-- Paint B2010 EXTERIOR WALLS 1999 B201007 EXTERIOR SOFFITS General						

NAS1 Support Area

Cost Book: Reference

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
	B2010 EXTERIOR WALLS	488 (LF)	Replace					0.00
	1999 A B201010 EXTERIOR JOINT SEALANT General							
	-- Replace B2010 EXTERIOR WALLS 1999 A B201010 EXTERIOR JOINT SEALANT General							
	B2010 EXTERIOR WALLS	390 (SF)	Paint					0.00
	1999 B B201001 EXTERIOR CLOSURE Stucco							
	-- Paint B2010 EXTERIOR WALLS 1999 B B201001 EXTERIOR CLOSURE Stucco							
2018	B30 ROOFING							
	B3010 ROOF COVERINGS	12,475 (SF)	Replace					0.00
	1999 B301003 ROOF INSULATION & FILL General							
	-- Replace B3010 ROOF COVERINGS 1999 B301003 ROOF INSULATION & FILL General							
2018	C20 STAIRS							
	C2010 STAIR CONSTRUCTION	790 (LF)	Paint					0.00
	1999 A C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General							
	-- Paint C2010 STAIR CONSTRUCTION 1999 A C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General							
2018	D20 PLUMBING							
	D2030 SANITARY WASTE	2,365 (EA)	Replace					0.00
	1999 D203002 VENT PIPE & FITTINGS General							
	-- Replace D2030 SANITARY WASTE 1999 D203002 VENT PIPE & FITTINGS General							
2018	D30 HVAC							
	D3030 COOLING GENERATING SYSTEMS	1 (EA)	Replace					0.00
	1999 OUTSIDE D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 60 TN							
	-- Replace D3030 COOLING GENERATING SYSTEMS 1999 D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 60 TN							
	D3040 DISTRIBUTION SYSTEMS	1,565 (MBH)	Replace					0.00
	1999 D304003 HOT WATER DISTRIBUTION SYSTEMS General							
	-- Replace D3040 DISTRIBUTION SYSTEMS 1999 D304003 HOT WATER DISTRIBUTION SYSTEMS General							

NAS1 Support Area

Cost Book: Reference

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Year	System Component	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description							
	D3040 DISTRIBUTION SYSTEMS	157 (TON)	Replace				0.00
	1999 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1999 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General						
	D3060 CONTROLS & INSTRUMENTATION	58 (EA)	Replace				0.00
	1999 D306002 ELECTRONIC CONTROLS General						
	-- Replace D3060 CONTROLS & INSTRUMENTATION 1999 D306002 ELECTRONIC CONTROLS General						
2018	D40 FIRE PROTECTION						
	D4010 FIRE ALARM AND DETECTION SYSTEMS	62,613 (SF)	Replace				0.00
	1999 D401001 FIRE ALARM DISTRIBUTION Other						
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1999 D401001 FIRE ALARM DISTRIBUTION Other						
2018	D50 ELECTRICAL						
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	3 (EA)	Repair				0.00
	1999 D501004 PANELBOARDS Main lugs, 200 amp						
	-- Repair D5010 ELECTRICAL SERVICE & DISTRIBUTION 1999 D501004 PANELBOARDS Main lugs, 200 amp						
	D5090 OTHER ELECTRICAL SERVICES	62,613 (SF)	Replace				0.00
	1999 D509006 ENERGY MANAGEMENT CONTROL SYSTEM General						
	-- Replace D5090 OTHER ELECTRICAL SERVICES 1999 D509006 ENERGY MANAGEMENT CONTROL SYSTEM General						
2019	B20 EXTERIOR ENCLOSURE						
	B2010 EXTERIOR WALLS	488 (LF)	Replace				0.00
	1999 A B201010 EXTERIOR JOINT SEALANT General						
	-- Replace B2010 EXTERIOR WALLS 1999 A B201010 EXTERIOR JOINT SEALANT General						
2019	B30 ROOFING						
	B3010 ROOF COVERINGS	12,475 (SF)	Replace				0.00
	1999 B301003 ROOF INSULATION & FILL General						
	-- Replace B3010 ROOF COVERINGS 1999 B301003 ROOF INSULATION & FILL General						

NAS1 Support Area

Cost Book: Reference

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
2019	D20 PLUMBING							
	D2030	SANITARY WASTE	2,395 (EA)	Replace				0.00
	1999	D203002 VENT PIPE & FITTINGS General						
	-- Replace D2030 SANITARY WASTE 1999 D203002 VENT PIPE & FITTINGS General							
2019	D30 HVAC							
	D3030	COOLING GENERATING SYSTEMS	1 (EA)	Replace				0.00
	1999	OUTSIDE D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 60 TN						
	-- Replace D3030 COOLING GENERATING SYSTEMS 1999 D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 60 TN							
	D3040	DISTRIBUTION SYSTEMS	1,565 (MBH)	Replace				0.00
	1999	D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1999 D304003 HOT WATER DISTRIBUTION SYSTEMS General							
	D3040	DISTRIBUTION SYSTEMS	157 (TON)	Replace				0.00
	1999	D304006 CHILLED WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1999 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General							
	D3060	CONTROLS & INSTRUMENTATION	58 (EA)	Replace				0.00
	1999	D306002 ELECTRONIC CONTROLS General						
	-- Replace D3060 CONTROLS & INSTRUMENTATION 1999 D306002 ELECTRONIC CONTROLS General							
2019	D40 FIRE PROTECTION							
	D4010	FIRE ALARM AND DETECTION SYSTEMS	62,613 (SF)	Replace				0.00
	1999	D401001 FIRE ALARM DISTRIBUTION Other						
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1999 D401001 FIRE ALARM DISTRIBUTION Other							
2019	D50 ELECTRICAL							
	D5090	OTHER ELECTRICAL SERVICES	62,613 (SF)	Replace				0.00
	1999	D509006 ENERGY MANAGEMENT CONTROL SYSTEM General						
	-- Replace D5090 OTHER ELECTRICAL SERVICES 1999 D509006 ENERGY MANAGEMENT CONTROL SYSTEM General							



Work Items by Building Report



NAS1 Support Area

Cost Book: Reference

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Year	System Component Section Description -- Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
2020	B20 EXTERIOR ENCLOSURE						
	B2010 EXTERIOR WALLS	2,127 (SF)	Paint				0.00
	1999 B201007 EXTERIOR SOFFITS General						
	-- Paint B2010 EXTERIOR WALLS 1999 B201007 EXTERIOR SOFFITS General						
	B2010 EXTERIOR WALLS	488 (LF)	Replace				0.00
	1999 A B201010 EXTERIOR JOINT SEALANT General						
	-- Replace B2010 EXTERIOR WALLS 1999 A B201010 EXTERIOR JOINT SEALANT General						
	B2010 EXTERIOR WALLS	390 (SF)	Paint				0.00
	1999 B B201001 EXTERIOR CLOSURE Stucco						
	-- Paint B2010 EXTERIOR WALLS 1999 B B201001 EXTERIOR CLOSURE Stucco						
2020	B30 ROOFING						
	B3010 ROOF COVERINGS	12,475 (SF)	Replace				0.00
	1999 B301003 ROOF INSULATION & FILL General						
	-- Replace B3010 ROOF COVERINGS 1999 B301003 ROOF INSULATION & FILL General						
2020	D20 PLUMBING						
	D2030 SANITARY WASTE	2,365 (EA)	Replace				0.00
	1999 D203002 VENT PIPE & FITTINGS General						
	-- Replace D2030 SANITARY WASTE 1999 D203002 VENT PIPE & FITTINGS General						
2020	D30 HVAC						
	D3020 HEAT GENERATING SYSTEMS	2 (EA)	Replace				0.00
	1999 D302004 AUXILIARY EQUIPMENT Chemical Feedwater - 150 lb., 5 gallon, ASME						
	-- Replace D3020 HEAT GENERATING SYSTEMS 1999 D302004 AUXILIARY EQUIPMENT Chemical Feedwater - 150 lb., 5 gallon, ASME						
	D3030 COOLING GENERATING SYSTEMS	1 (EA)	Replace				0.00
	1999 OUTSIDE D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 60 TN						
	-- Replace D3030 COOLING GENERATING SYSTEMS 1999 OUTSIDE D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 60 TN						

NAS1 Support Area

Cost Book: Reference

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Year	System Component	Qty (UM)	Activity	Project	Cost	Status	Score
	Section Description						Completion Date
	-- Description						
	D3040 DISTRIBUTION SYSTEMS	2 (EA)	Replace				0.00
	1999 D304001 AIR DISTRIBUTION, HEATING & COOLING Air Separator - Air control, air separator, 4" diameter, includes strainer						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1999 D304001 AIR DISTRIBUTION, HEATING & COOLING Air Separator - Air control, air separator, 4" diameter, includes strainer						
	D3040 DISTRIBUTION SYSTEMS	1,565 (MBN)	Replace				0.00
	1999 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1999 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	D3040 DISTRIBUTION SYSTEMS	157 (TON)	Replace				0.00
	1999 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1999 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1999 ROOM 22 D304008 AIR HANDLING UNITS Central Station - 2000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1999 ROOM 22 D304008 AIR HANDLING UNITS Central Station - 2000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1999 ROOM G61 AHU 2 D304008 AIR HANDLING UNITS Central Station - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1999 ROOM G61 AHU 2 D304008 AIR HANDLING UNITS Central Station - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1999 ROOM G61 AHU 3 D304008 AIR HANDLING UNITS Central Station - 5000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1999 ROOM G61 AHU 3 D304008 AIR HANDLING UNITS Central Station - 5000 CFM						
	D3040 DISTRIBUTION SYSTEMS	1 (EA)	Replace				0.00
	1999 ROOM G61 AHU 4 D304008 AIR HANDLING UNITS Central Station - 2000 CFM						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1999 ROOM G61 AHU 4 D304008 AIR HANDLING UNITS Central Station - 2000 CFM						
	D3060 CONTROLS & INSTRUMENTATION	58 (EA)	Replace				0.00
	1999 D306002 ELECTRONIC CONTROLS General						
	-- Replace D3060 CONTROLS & INSTRUMENTATION 1999 D306002 ELECTRONIC CONTROLS General						
2020	D40 FIRE PROTECTION						

NAS1 Support Area

Cost Book: Reference

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Year	System	Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score	Completion Date
-- Description										
			D4010 FIRE ALARM AND DETECTION SYSTEMS	62,613 (SF)	Replace				0.00	
			1999 D401001 FIRE ALARM DISTRIBUTION Other							
			-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS							
			1999 D401001 FIRE ALARM DISTRIBUTION Other							
2020	D50 ELECTRICAL									
			D5090 OTHER ELECTRICAL SERVICES	62,613 (SF)	Replace				0.00	
			1999 D509006 ENERGY MANAGEMENT CONTROL SYSTEM General							
			-- Replace D5090 OTHER ELECTRICAL SERVICES							
			1999 D509006 ENERGY MANAGEMENT CONTROL SYSTEM General							

"Identification only"

NAS1 Support Area

Cost Book: Reference

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
2015	B20 EXTERIOR ENCLOSURE							
	B2010 EXTERIOR WALLS	31,466 (SF)	Paint					0.00
	2008 B201001 EXTERIOR CLOSURE Stucco							
	-- Paint B2010 EXTERIOR WALLS 2008 B201001 EXTERIOR CLOSURE Stucco							
	B2010 EXTERIOR WALLS	3,898 (SF)	Paint					0.00
	2008 B201007 EXTERIOR SOFFITS General							
	-- Paint B2010 EXTERIOR WALLS 2008 B201007 EXTERIOR SOFFITS General							
	B2010 EXTERIOR WALLS	826 (LF)	Replace					0.00
	2008 A B201010 EXTERIOR JOINT SEALANT General							
	-- Replace B2010 EXTERIOR WALLS 2008 B201010 EXTERIOR JOINT SEALANT General							
2015	C20 STAIRS							
	C2010 STAIR CONSTRUCTION	100 (LF)	Paint					0.00
	2008 A C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General							
	-- Paint C2010 STAIR CONSTRUCTION 2008 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General							
2016	B20 EXTERIOR ENCLOSURE							
	B2010 EXTERIOR WALLS	31,466 (SF)	Paint					0.00
	2008 B201001 EXTERIOR CLOSURE Stucco							
	-- Paint B2010 EXTERIOR WALLS 2008 B201001 EXTERIOR CLOSURE Stucco							
	B2010 EXTERIOR WALLS	3,898 (SF)	Paint					0.00
	2008 B201007 EXTERIOR SOFFITS General							
	-- Paint B2010 EXTERIOR WALLS 2008 B201007 EXTERIOR SOFFITS General							
	B2010 EXTERIOR WALLS	826 (LF)	Replace					0.00
	2008 A B201010 EXTERIOR JOINT SEALANT General							
	-- Replace B2010 EXTERIOR WALLS 2008 B201010 EXTERIOR JOINT SEALANT General							
2016	C20 STAIRS							

NAS1 Support Area

Cost Book: Reference

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

Year	System Component	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
Section Description							
-- Description							
	C2010 STAIR CONSTRUCTION	100 (LF)	Paint				0.00
	2008 A C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
	-- Paint C2010 STAIR CONSTRUCTION 2008 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
2017	B20 EXTERIOR ENCLOSURE						
	B2010 EXTERIOR WALLS	31,466 (SF)	Paint				0.00
	2008 B201001 EXTERIOR CLOSURE Stucco						
	-- Paint B2010 EXTERIOR WALLS 2008 B201001 EXTERIOR CLOSURE Stucco						
	B2010 EXTERIOR WALLS	159 (SF)	Paint				0.00
	2008 B201001 EXTERIOR CLOSURE Wall Louver						
	-- Paint B2010 EXTERIOR WALLS 2008 B201001 EXTERIOR CLOSURE Wall Louver						
	B2010 EXTERIOR WALLS	826 (LF)	Replace				0.00
	2008 A B201010 EXTERIOR JOINT SEALANT General						
	-- Replace B2010 EXTERIOR WALLS 2008 B201010 EXTERIOR JOINT SEALANT General						
2017	B30 ROOFING						
	B3010 ROOF COVERINGS	529 (LF)	Paint				0.00
	2008 B301005 GUTTERS & DOWNSPOUTS Downspouts						
	-- Paint B3010 ROOF COVERINGS 2008 B301005 GUTTERS & DOWNSPOUTS Downspouts						
	B3010 ROOF COVERINGS	262 (LF)	Paint				0.00
	2008 B B301004 FLASHINGS & TRIM General						
	-- Paint B3010 ROOF COVERINGS 2008 Stucco Fascia B301004 FLASHINGS & TRIM Other						
2017	C10 INTERIOR CONSTRUCTION						
	C1010 PARTITIONS	58,932 (SF)	Paint				0.00
	2008 C101001 FIXED PARTITIONS Wall - Drywall w/Stud Framing						
	-- Paint C1010 PARTITIONS 2008 C101001 FIXED PARTITIONS General						
2017	C20 STAIRS						

NAS1 Support Area

Cost Book: Reference

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
	C2010 STAIR CONSTRUCTION	100 (LF)	Paint					0.00
	2008 A C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General							
	-- Paint C2010 STAIR CONSTRUCTION 2008 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General							
	C2010 STAIR CONSTRUCTION	442 (LF)	Paint					0.00
	2008 B C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General							
	-- Paint C2010 STAIR CONSTRUCTION 2008 - Interior C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General							
2017	C30 INTERIOR FINISHES							
	C3020 FLOOR FINISHES	13,122 (SF)	Replace					0.00
	2008 C302005 CARPETING Carpet Tile							
	-- Replace C3020 FLOOR FINISHES 2008 C302005 CARPETING General							
2018	B20 EXTERIOR ENCLOSURE							
	B2010 EXTERIOR WALLS	31,466 (SF)	Paint					0.00
	2008 B201001 EXTERIOR CLOSURE Stucco							
	-- Paint B2010 EXTERIOR WALLS 2008 B201001 EXTERIOR CLOSURE Stucco							
	B2010 EXTERIOR WALLS	3,898 (SF)	Paint					0.00
	2008 B201007 EXTERIOR SOFFITS General							
	-- Paint B2010 EXTERIOR WALLS 2008 B201007 EXTERIOR SOFFITS General							
	B2010 EXTERIOR WALLS	826 (LF)	Replace					0.00
	2008 A B201010 EXTERIOR JOINT SEALANT General							
	-- Replace B2010 EXTERIOR WALLS 2008 A B201010 EXTERIOR JOINT SEALANT General							
2018	C20 STAIRS							
	C2010 STAIR CONSTRUCTION	680 (LF)	Paint					0.00
	2008 A C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General							
	-- Paint C2010 STAIR CONSTRUCTION 2008 A C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General							
2019	B20 EXTERIOR ENCLOSURE							

NAS1 Support Area

Cost Book: Reference

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

Year	System	Qty (UM)	Activity	Project	Cost	Status	Score
Component	Section Description						Completion Date
	-- Description						
B2010	EXTERIOR WALLS	826 (LF)	Replace				0.00
2008 A B201010	EXTERIOR JOINT SEALANT General						
	-- Replace B2010 EXTERIOR WALLS 2008 A B201010 EXTERIOR JOINT SEALANT General						
B2010	EXTERIOR WALLS	31,466 (SF)	Paint				0.00
2008 B201001	EXTERIOR CLOSURE Stucco						
	-- Paint B2010 EXTERIOR WALLS 2008 B201001 EXTERIOR CLOSURE Stucco						
B2010	EXTERIOR WALLS	826 (LF)	Replace				0.00
2008 A B201010	EXTERIOR JOINT SEALANT General						
	-- Replace B2010 EXTERIOR WALLS 2008 A B201010 EXTERIOR JOINT SEALANT General						

"Identification only"

NAS1 Support Area

Cost Book: Reference

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
2015	B20 EXTERIOR ENCLOSURE							
	B2010 EXTERIOR WALLS		10,524 (SF)	Paint				0.00
	1999 B201001 EXTERIOR CLOSURE Stucco							
	-- Paint B2010 EXTERIOR WALLS 1999 B201001 EXTERIOR CLOSURE Stucco							
	B2010 EXTERIOR WALLS		133 (SF)	Paint				0.00
	1999 B201001 EXTERIOR CLOSURE Wall Louver							
	-- Paint B2010 EXTERIOR WALLS 1999 B201001 EXTERIOR CLOSURE Wall Louver							
	B2010 EXTERIOR WALLS		144 (LF)	Paint				0.00
	1999 B201006 BALCONY WALLS & HANDRAILS Handrailing							
	-- Paint B2010 EXTERIOR WALLS 1999 Courtyard B201006 BALCONY WALLS & HANDRAILS Handrailing							
	B2010 EXTERIOR WALLS		2,442 (SF)	Paint				0.00
	1999 B201007 EXTERIOR SOFFITS General							
	-- Paint B2010 EXTERIOR WALLS 1999 B201007 EXTERIOR SOFFITS General							
	B2010 EXTERIOR WALLS		550 (LF)	Replace				0.00
	1999 A B201010 EXTERIOR JOINT SEALANT General							
	-- Replace B2010 EXTERIOR WALLS 1999 B201010 EXTERIOR JOINT SEALANT General							
	B2010 EXTERIOR WALLS		300 (SF)	Paint				0.00
	1999 A B201011 SUN CONTROL DEVICES General							
	-- Paint B2010 EXTERIOR WALLS 1999 OHD Area B201011 SUN CONTROL DEVICES General							
	B2010 EXTERIOR WALLS		312 (SF)	Paint				0.00
	1999 B B201011 SUN CONTROL DEVICES General							
	-- Paint B2010 EXTERIOR WALLS 1999 Window Awning B201011 SUN CONTROL DEVICES General							
2015	B30 ROOFING							
	B3010 ROOF COVERINGS		1,184 (LF)	Replace				0.00
	1999 B301004 FLASHINGS & TRIM Flashings - Base							
	-- Replace B3010 ROOF COVERINGS 1999 B301004 FLASHINGS & TRIM Flashings - Base							

NAS1 Support Area

Cost Book: Reference

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
	B3010 ROOF COVERINGS	3,534 (SF)	Replace					0.00
	1999 B301090 OTHER ROOFING Walkway Protection							
	-- Replace B3010 ROOF COVERINGS 1999 B301092 LOW SLOPE ROOF SYSTEMS Modified Bitumen							
	B3010 ROOF COVERINGS	3 (EA)	Replace					0.00
	1999 B B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations							
	-- Replace B3010 ROOF COVERINGS 1999b B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations							
2016	B20 EXTERIOR ENCLOSURE							
	B2010 EXTERIOR WALLS	16,594 (SF)	Paint					0.00
	1999 B201001 EXTERIOR CLOSURE Stucco							
	-- Paint B2010 EXTERIOR WALLS 1999 B201001 EXTERIOR CLOSURE Stucco							
	B2010 EXTERIOR WALLS	133 (SF)	Paint					0.00
	1999 B201001 EXTERIOR CLOSURE Wall Louver							
	-- Paint B2010 EXTERIOR WALLS 1999 B201001 EXTERIOR CLOSURE Wall Louver							
	B2010 EXTERIOR WALLS	144 (LF)	Paint					0.00
	1999 B201006 BALCONY WALLS & HANDRAILS Handrailing							
	-- Paint B2010 EXTERIOR WALLS 1999 Courtyard B201006 BALCONY WALLS & HANDRAILS Handrailing							
	B2010 EXTERIOR WALLS	2,442 (SF)	Paint					0.00
	1999 B201007 EXTERIOR SOFFITS General							
	-- Paint B2010 EXTERIOR WALLS 1999 B201007 EXTERIOR SOFFITS General							
	B2010 EXTERIOR WALLS	550 (LF)	Replace					0.00
	1999 A B201010 EXTERIOR JOINT SEALANT General							
	-- Replace B2010 EXTERIOR WALLS 1999 B201010 EXTERIOR JOINT SEALANT General							
	B2010 EXTERIOR WALLS	300 (SF)	Paint					0.00
	1999 A B201011 SUN CONTROL DEVICES General							
	-- Paint B2010 EXTERIOR WALLS 1999 OHD Area B201011 SUN CONTROL DEVICES General							

NAS1 Support Area

Cost Book: Reference

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
	B2010 EXTERIOR WALLS	322 (SF)	Paint					0.00
	1999 B B201011 SUN CONTROL DEVICES General							
	-- Paint B2010 EXTERIOR WALLS 1999 Window Awnings B201011 SUN CONTROL DEVICES General							
2016	B30 ROOFING							
	B3010 ROOF COVERINGS	1,184 (LF)	Replace					0.00
	1999 B301004 FLASHINGS & TRIM Flashings - Base							
	-- Replace B3010 ROOF COVERINGS 1999 B301004 FLASHINGS & TRIM Flashings - Base							
	B3010 ROOF COVERINGS	3,534 (SF)	Replace					0.00
	1999 B301090 OTHER ROOFING Walkway Protection							
	-- Replace B3010 ROOF COVERINGS 1999 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen							
	B3010 ROOF COVERINGS	3 (EA)	Replace					0.00
	1999 B B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations							
	-- Replace B3010 ROOF COVERINGS 1999b B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations							
2017	B20 EXTERIOR ENCLOSURE							
	B2010 EXTERIOR WALLS	16,594 (SF)	Paint					0.00
	1999 B201001 EXTERIOR CLOSURE Stucco							
	-- Paint B2010 EXTERIOR WALLS 1999 B201001 EXTERIOR CLOSURE Stucco							
	B2010 EXTERIOR WALLS	133 (SF)	Paint					0.00
	1999 B201001 EXTERIOR CLOSURE Wall Louver							
	-- Paint B2010 EXTERIOR WALLS 1999 B201001 EXTERIOR CLOSURE Wall Louver							
	B2010 EXTERIOR WALLS	144 (LF)	Paint					0.00
	1999 B201006 BALCONY WALLS & HANDRAILS Handrailing							
	-- Paint B2010 EXTERIOR WALLS 1999 Courtyard B201006 BALCONY WALLS & HANDRAILS Handrailing							
	B2010 EXTERIOR WALLS	2,442 (SF)	Paint					0.00
	1999 B201007 EXTERIOR SOFFITS General							
	-- Paint B2010 EXTERIOR WALLS 1999 B201007 EXTERIOR SOFFITS General							

NAS1 Support Area

Cost Book: Reference

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

Year	System	Component	Qty (UM)	Activity	Project	Cost	Status	Score
Section Description								
– Description						Completion Date		
B2010	EXTERIOR WALLS	520 (LF)	Replace					0.00
1999 A	B201010 EXTERIOR JOINT SEALANT General							
– Replace B2010 EXTERIOR WALLS 1999 B201010 EXTERIOR JOINT SEALANT General								
B2010	EXTERIOR WALLS	300 (SF)	Paint					0.00
1999 A	B201011 SUN CONTROL DEVICES General							
– Paint B2010 EXTERIOR WALLS 1999 OHD Area B201011 SUN CONTROL DEVICES General								
B2010	EXTERIOR WALLS	312 (SF)	Paint					0.00
1999 B	B201011 SUN CONTROL DEVICES General							
– Paint B2010 EXTERIOR WALLS 1999 Window Awning B201011 SUN CONTROL DEVICES General								
B2030	EXTERIOR DOORS	400 (SF)	Paint					0.00
1999	B203007 GATES General							
– Paint B2030 EXTERIOR DOORS 1999 B203007 GATES General								
2017 B30 ROOFING								
B3010	ROOF COVERINGS	1,184 (LF)	Replace					0.00
1999	B301004 FLASHINGS & TRIM Flashings - Base							
– Replace B3010 ROOF COVERINGS 1999 B301004 FLASHINGS & TRIM Flashings - Base								
B3010	ROOF COVERINGS	423 (LF)	Paint					0.00
1999	B301004 FLASHINGS & TRIM General							
– Paint B3010 ROOF COVERINGS 1999 Stucco Fascia B301004 FLASHINGS & TRIM Other								
B3010	ROOF COVERINGS	3,534 (SF)	Replace					0.00
1999	B301090 OTHER ROOFING Walkway Protection							
– Replace B3010 ROOF COVERINGS 1999 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen								
B3010	ROOF COVERINGS	3 (EA)	Replace					0.00
1999 B	B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations							
– Replace B3010 ROOF COVERINGS 1999b B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations								

2017 C10 INTERIOR CONSTRUCTION

NAS1 Support Area

Cost Book: Reference

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

Year	System	Component	Qty (UM)	Activity	Project	Cost	Status	Score
Section Description								
-- Description								
	C1010	PARTITIONS	14,001 (SF)	Paint				0.00
	1999 C101001	FIXED PARTITIONS Wall - Drywall w/Std Framing						
	-- Paint C1010 PARTITIONS 1999 C101001 FIXED PARTITIONS General							
2017	C30 INTERIOR FINISHES							
	C3030	CEILING FINISHES	3,664 (SF)	Paint				0.00
	1999 C303002	GYPSUM WALLBOARD CEILING FINISHES General						
	-- Paint C3030 CEILING FINISHES 1999 C303002 GYPSUM WALLBOARD CEILING FINISHES General							
	C3030	CEILING FINISHES	5,952 (SF)	Replace				0.00
	1999 C303005	SUSPENSION SYSTEMS General						
	-- Replace C3030 CEILING FINISHES 1999 C303005 SUSPENSION SYSTEMS General							
2017	D30 HVAC							
	D3050	TERMINAL & PACKAGE UNITS	11 (EA)	Repair				0.00
	1999 D305003	FAN COIL UNITS Duct Mount, 4 Pipe - 2 ton						
	-- Repair D3050 TERMINAL & PACKAGE UNITS D305003 FAN COIL UNITS Duct Mount, 4 Pipe - 2 ton							
	D3050	TERMINAL & PACKAGE UNITS	7 (EA)	Repair				0.00
	1999 D305003	FAN COIL UNITS Duct Mount, 4 Pipe - 5 ton						
	-- Repair D3050 TERMINAL & PACKAGE UNITS D305003 FAN COIL UNITS Duct Mount, 4 Pipe - 5 ton							
2017	D40 FIRE PROTECTION							
	D4010	FIRE ALARM AND DETECTION SYSTEMS	12,750 (SF)	Repair				0.00
	1999 D401001	FIRE ALARM DISTRIBUTION Other						
	-- Repair D4010 FIRE ALARM AND DETECTION SYSTEMS D401001 FIRE ALARM DISTRIBUTION General							
2017	D50 ELECTRICAL							
	D5030	COMMUNICATIONS & SECURITY	1 (EA)	Repair				0.00
	1999 D503003	INTERCOMMUNICATIONS SYSTEMS 6 stations						
	-- Repair D5030 COMMUNICATIONS & SECURITY D503003 INTERCOMMUNICATIONS SYSTEMS 6 stations							



Work Items by Building Report



NAS1 Support Area

Cost Book: Reference

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
2018	B30 ROOFING							
	B3010 ROOF COVERINGS	16,637 (SF)	Replace					0.00
	1999 B301003 ROOF INSULATION & FILL General							
	-- Replace B3010 ROOF COVERINGS 1999 B301003 ROOF INSULATION & FILL General							
2018	C30 INTERIOR FINISHES							
	C3030 CEILING FINISHES	5,952 (SF)	Replace					0.00
	1999 C303001 ACOUSTICAL CEILING TILES & PANELS General							
	-- Replace C3030 CEILING FINISHES 1999 C303001 ACOUSTICAL CEILING TILES & PANELS General							
	C3030 CEILING FINISHES	5,952 (SF)	Replace					0.00
	1999 C303005 SUSPENSION SYSTEMS General							
	-- Replace C3030 CEILING FINISHES 1999 C303005 SUSPENSION SYSTEMS General							
2018	D20 PLUMBING							
	D2010 PLUMBING FIXTURES	8 (EA)	Repair					0.00
	1999 D201001 WATERCLOSETS General							
	-- Repair D2010 PLUMBING FIXTURES 1999 D201001 WATERCLOSETS General							
	D2030 SANITARY WASTE	483 (EA)	Replace					0.00
	1999 D203002 VENT PIPE & FITTINGS General							
	-- Replace D2030 SANITARY WASTE 1999 D203002 VENT PIPE & FITTINGS General							
2018	D30 HVAC							
	D3040 DISTRIBUTION SYSTEMS	320 (MBH)	Replace					0.00
	1999 D304003 HOT WATER DISTRIBUTION SYSTEMS General							
	-- Replace D3040 DISTRIBUTION SYSTEMS 1999 D304003 HOT WATER DISTRIBUTION SYSTEMS General							
	D3040 DISTRIBUTION SYSTEMS	32 (TON)	Replace					0.00
	1999 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General							
	-- Replace D3040 DISTRIBUTION SYSTEMS 1999 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General							

NAS1 Support Area

Cost Book: Reference

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
2018	D40 FIRE PROTECTION							
	D4010 FIRE ALARM AND DETECTION SYSTEMS	12,742 (SF)	Replace					0.00
	1999 D401001 FIRE ALARM DISTRIBUTION Other							
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1999 D401001 FIRE ALARM DISTRIBUTION Other							
2019	B30 ROOFING							
	B3010 ROOF COVERINGS	13,687 (SF)	Replace					0.00
	1999 B301003 ROOF INSULATION & FILL General							
	-- Replace B3010 ROOF COVERINGS 1999 B301003 ROOF INSULATION & FILL General							
2019	C30 INTERIOR FINISHES							
	C3030 CEILING FINISHES	5,952 (SF)	Replace					0.00
	1999 C303001 ACOUSTICAL CEILING TILES & PANELS General							
	-- Replace C3030 CEILING FINISHES 1999 C303001 ACOUSTICAL CEILING TILES & PANELS General							
	C3030 CEILING FINISHES	5,952 (SF)	Replace					0.00
	1999 C303005 SUSPENSION SYSTEMS General							
	-- Replace C3030 CEILING FINISHES 1999 C303005 SUSPENSION SYSTEMS General							
2019	D20 PLUMBING							
	D2030 SANITARY WASTE	483 (EA)	Replace					0.00
	1999 D203002 VENT PIPE & FITTINGS General							
	-- Replace D2030 SANITARY WASTE 1999 D203002 VENT PIPE & FITTINGS General							
2019	D30 HVAC							
	D3040 DISTRIBUTION SYSTEMS	320 (MBH)	Replace					0.00
	1999 D304003 HOT WATER DISTRIBUTION SYSTEMS General							
	-- Replace D3040 DISTRIBUTION SYSTEMS 1999 D304003 HOT WATER DISTRIBUTION SYSTEMS General							

NAS1 Support Area

Cost Book: Reference

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

Year	System Component	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description							
	D3040 DISTRIBUTION SYSTEMS	32 (TON)	Replace				0.00
	1999 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1999 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General						
2019	D40 FIRE PROTECTION						
	D4010 FIRE ALARM AND DETECTION SYSTEMS	12,792 (SF)	Replace				0.00
	1999 D401001 FIRE ALARM DISTRIBUTION Other						
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1999 D401001 FIRE ALARM DISTRIBUTION Other						
2020	B30 ROOFING						
	B3010 ROOF COVERINGS	13,687 (SF)	Replace				0.00
	1999 B301003 ROOF INSULATION & FILL General						
	-- Replace B3010 ROOF COVERINGS 1999 B301003 ROOF INSULATION & FILL General						
2020	C30 INTERIOR FINISHES						
	C3030 CEILING FINISHES	5,952 (SF)	Replace				0.00
	1999 C303001 ACOUSTICAL CEILING TILES & PANELS General						
	-- Replace C3030 CEILING FINISHES 1999 C303001 ACOUSTICAL CEILING TILES & PANELS General						
	C3030 CEILING FINISHES	5,952 (SF)	Replace				0.00
	1999 C303005 SUSPENSION SYSTEMS General						
	-- Replace C3030 CEILING FINISHES 1999 C303005 SUSPENSION SYSTEMS General						
2020	D20 PLUMBING						
	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)	Replace				0.00
	1999 ROOM 17 D202003 DOMESTIC WATER EQUIPMENT Water Softener						
	-- Replace D2020 DOMESTIC WATER DISTRIBUTION 1999 ROOM 17 D202003 DOMESTIC WATER EQUIPMENT Water Softener						
	D2030 SANITARY WASTE	483 (EA)	Replace				0.00
	1999 D203002 VENT PIPE & FITTINGS General						
	-- Replace D2030 SANITARY WASTE 1999 D203002 VENT PIPE & FITTINGS General						

NAS1 Support Area

Cost Book: Reference

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

Year	System Component	Qty (UM)	Activity	Project	Cost	Status	Score
Section Description							Completion Date
-- Description							
2020	D30 HVAC						
	D3040 DISTRIBUTION SYSTEMS	120 (MBH)	Replace				0.00
	1999 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1999 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	D3040 DISTRIBUTION SYSTEMS	32 (TON)	Replace				0.00
	1999 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1999 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General						
2020	D40 FIRE PROTECTION						
	D4010 FIRE ALARM AND DETECTION SYSTEMS	12,792 (SF)	Replace				0.00
	1999 D401001 FIRE ALARM DISTRIBUTION Other						
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1999 D401001 FIRE ALARM DISTRIBUTION Other						

NAS1 Support Area

Cost Book: Reference

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

Year	System	Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score	Completion Date
-- Description										
2015	B20	EXTERIOR ENCLOSURE								
	B2010	EXTERIOR WALLS	32,828 (SF)	Paint					0.00	
	2008 B201001	EXTERIOR CLOSURE Stucco								
		-- Paint B2010 EXTERIOR WALLS 2008 B201001 EXTERIOR CLOSURE Stucco								
	B2010	EXTERIOR WALLS	8 (SF)	Paint					0.00	
	2008 B201011	SUN CONTROL DEVICES General								
		-- Paint B2010 EXTERIOR WALLS 2008 B201011 SUN CONTROL DEVICES General								
	B2010	EXTERIOR WALLS	1,095 (LF)	Replace					0.00	
	2008 A B201010	EXTERIOR JOINT SEALANT General								
		-- Replace B2010 EXTERIOR WALLS 2008 B201010 EXTERIOR JOINT SEALANT General								
	B2010	EXTERIOR WALLS	32,828 (SF)	Paint					0.00	
	2008 B201001	EXTERIOR CLOSURE Stucco								
		-- Paint B2010 EXTERIOR WALLS 2008 B201001 EXTERIOR CLOSURE Stucco								
	B2010	EXTERIOR WALLS	8 (SF)	Paint					0.00	
	2008 B201011	SUN CONTROL DEVICES General								
		-- Paint B2010 EXTERIOR WALLS 2008 B201011 SUN CONTROL DEVICES General								
	B2010	EXTERIOR WALLS	1,095 (LF)	Replace					0.00	
	2008 A B201010	EXTERIOR JOINT SEALANT General								
		-- Replace B2010 EXTERIOR WALLS 2008 B201010 EXTERIOR JOINT SEALANT General								
	B2010	EXTERIOR WALLS	32,828 (SF)	Paint					0.00	
	2008 B201001	EXTERIOR CLOSURE Stucco								
		-- Paint B2010 EXTERIOR WALLS 2008 B201001 EXTERIOR CLOSURE Stucco								
	B2010	EXTERIOR WALLS	234 (SF)	Paint					0.00	
	2008 B201001	EXTERIOR CLOSURE Wall Louver								
		-- Paint B2010 EXTERIOR WALLS 2008 B201001 EXTERIOR CLOSURE Wall Louver								

NAS1 Support Area

Cost Book: Reference

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

Year	System Component	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description							
	B2010 EXTERIOR WALLS	1,305 (SF)	Paint				0.00
	2008 B201007 EXTERIOR SOFFITS General						
	-- Paint B2010 EXTERIOR WALLS 2008 B201007 EXTERIOR SOFFITS General						
	B2010 EXTERIOR WALLS	8 (SF)	Paint				0.00
	2008 B201011 SUN CONTROL DEVICES General						
	-- Paint B2010 EXTERIOR WALLS 2008 B201011 SUN CONTROL DEVICES General						
	B2010 EXTERIOR WALLS	1,095 (LF)	Replace				0.00
	2008 A B201010 EXTERIOR JOINT SEALANT General						
	-- Replace B2010 EXTERIOR WALLS 2008 B201010 EXTERIOR JOINT SEALANT General						
2017	B30 ROOFING						
	B3010 ROOF COVERINGS	179 (LF)	Paint				0.00
	2008 B B301004 FLASHINGS & TRIM General						
	-- Paint B3010 ROOF COVERINGS 2008 Stucco Fascia B301004 FLASHINGS & TRIM Other						
2017	C10 INTERIOR CONSTRUCTION						
	C1010 PARTITIONS	69,111 (SF)	Paint				0.00
	2008 C101001 FIXED PARTITIONS Wall - Drywall w/Stud Framing						
	-- Paint C1010 PARTITIONS 2008 C101001 FIXED PARTITIONS General						
2017	C20 STAIRS						
	C2010 STAIR CONSTRUCTION	65 (LF)	Paint				0.00
	2008 A C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
	-- Paint C2010 STAIR CONSTRUCTION 2008 - Exterior C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General						
2017	C30 INTERIOR FINISHES						
	C3020 FLOOR FINISHES	31,939 (SF)	Replace				0.00
	2008 C302005 CARPETING General						
	-- Replace C3020 FLOOR FINISHES 2008 C302005 CARPETING General						

NAS1 Support Area

Cost Book: Reference

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
2018	B20 EXTERIOR ENCLOSURE							
	B2010 EXTERIOR WALLS	32,828 (SF)	Paint					0.00
	2008 B201001 EXTERIOR CLOSURE Stucco							
	-- Paint B2010 EXTERIOR WALLS 2008 B201001 EXTERIOR CLOSURE Stucco							
	B2010 EXTERIOR WALLS	1,305 (SF)	Paint					0.00
	2008 B201007 EXTERIOR SOFFITS General							
	-- Paint B2010 EXTERIOR WALLS 2008 B201007 EXTERIOR SOFFITS General							
	B2010 EXTERIOR WALLS	8 (SF)	Paint					0.00
	2008 B201011 SUN CONTROL DEVICES General							
	-- Paint B2010 EXTERIOR WALLS 2008 B201011 SUN CONTROL DEVICES General							
	B2010 EXTERIOR WALLS	1,095 (LF)	Replace					0.00
	2008 A B201010 EXTERIOR JOINT SEALANT General							
	-- Replace B2010 EXTERIOR WALLS 2008 A B201010 EXTERIOR JOINT SEALANT General							
2018	B30 ROOFING							
	B3010 ROOF COVERINGS	985 (LF)	Paint					0.00
	2008 B301005 GUTTERS & DOWNSPOUTS Downspouts							
	-- Paint B3010 ROOF COVERINGS 2008 B301005 GUTTERS & DOWNSPOUTS Downspouts							
2018	C20 STAIRS							
	C2010 STAIR CONSTRUCTION	65 (LF)	Paint					0.00
	2008 A C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General							
	-- Paint C2010 STAIR CONSTRUCTION 2008 A C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General							
2018	D30 HVAC							
	D3060 CONTROLS & INSTRUMENTATION	65 (EA)	Replace					0.00
	2008 D306002 ELECTRONIC CONTROLS General							
	-- Replace D3060 CONTROLS & INSTRUMENTATION 2008 D306002 ELECTRONIC CONTROLS General							

NAS1 Support Area

Cost Book: Reference

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

Year	System	Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score	Completion Date
-- Description										
2019	B20	EXTERIOR ENCLOSURE								
		B2010	EXTERIOR WALLS	1,095 (LF)	Replace				0.00	
		2008 A B201010	EXTERIOR JOINT SEALANT General							
		-- Replace B2010 EXTERIOR WALLS 2008 A B201010 EXTERIOR JOINT SEALANT General								
2019	D30	HVAC								
		D3060	CONTROLS & INSTRUMENTATION	65 (EA)	Replace				0.00	
		2008 D306002	ELECTRONIC CONTROLS General							
		-- Replace D3060 CONTROLS & INSTRUMENTATION 2008 D306002 ELECTRONIC CONTROLS General								
2020	B20	EXTERIOR ENCLOSURE								
		B2010	EXTERIOR WALLS	32,828 (SF)	Paint				0.00	
		2008 B201001	EXTERIOR CLOSURE Stucco							
		-- Paint B2010 EXTERIOR WALLS 2008 B201001 EXTERIOR CLOSURE Stucco								
		B2010	EXTERIOR WALLS	1,095 (LF)	Replace				0.00	
		2008 A B201010	EXTERIOR JOINT SEALANT General							
		-- Replace B2010 EXTERIOR WALLS 2008 A B201010 EXTERIOR JOINT SEALANT General								

Appendix F

Remaining Service Life (RSL) Detail Report

"identification only"

NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
B10 SUPERSTRUCTURE	B1020 ROOF CONSTRUCTION	2008 B102003 ROOF DECKS AND SLABS Deck - Steel	12	52	
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	2008 B201001 EXTERIOR CLOSURE Stucco	12	8	3
	B2010 EXTERIOR WALLS	2008 B201005 EXTERIOR LOUVERS & SCREENS General	12	8	3
	B2010 EXTERIOR WALLS	2008 B201007 EXTERIOR SOFFITS General	12	6	3
	B2010 EXTERIOR WALLS	2008 A B201010 EXTERIOR JOINT SEALANT General	12	0	
	B2010 EXTERIOR WALLS	2008 B B201010 EXTERIOR JOINT SEALANT General	12	6	
	B2020 EXTERIOR WINDOWS	2008 B202001 WINDOWS Aluminum Windows	12	31	
	B2030 EXTERIOR DOORS	2008 B203001 SOLID DOORS Steel	12	6	
	B2030 EXTERIOR DOORS	2008 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress	12	6	
B30 ROOFING	B3010 ROOF COVERINGS	2008 B301001 STEEP SLOPE ROOF SYSTEMS Clay Tile	12	14	
	B3010 ROOF COVERINGS	2008 B301001 ROOF INSULATION & FILL General	12	8	
	B3010 ROOF COVERINGS	2008 B301004 FLASHINGS & TRIM Flashings - Apron	12	8	
	B3010 ROOF COVERINGS	2008 B301004 FLASHINGS & TRIM Flashings - Cap	12	8	
	B3010 ROOF COVERINGS	2008 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	12	5	
	B3010 ROOF COVERINGS	2008 B301004 FLASHINGS & TRIM Flashings - Valley	12	8	
	B3010 ROOF COVERINGS	2008 B301004 FLASHINGS & TRIM General	12	5	3
	B3010 ROOF COVERINGS	2008 B301005 GUTTERS & DOWNSPOUTS Downspouts	12	4	3
	B3010 ROOF COVERINGS	2008 B301005 GUTTERS & DOWNSPOUTS Gutters	12	6	
	B3010 ROOF COVERINGS	2008 B301006 ROOF OPENINGS AND SUPPORTS Hatches	12	23	
C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	2008 C101001 FIXED PARTITIONS Wall - Plaster on Stud Framing	12	65	Unknown
	C1020 INTERIOR DOORS	2008 C102001 STANDARD INTERIOR DOORS Metal Door	12	26	
	C1020 INTERIOR DOORS	2008 C102001 STANDARD INTERIOR DOORS Wood Door/Metal Frame	12	21	
	C1020 INTERIOR DOORS	2008 C102003 FIRE DOORS Fire Door - Swinging	12	21	
	C1030 SPECIALTIES	2008 C103002 TOILET & BATH ACCESSORIES General	12	8	
	C1030 SPECIALTIES	2008 C103003 MARKER BOARDS & TACK BOARDS General	12	8	
	C1030 SPECIALTIES	2008 C103005 LOCKERS General	12	12	
	C1030 SPECIALTIES	2008 C103008 COUNTERS Laminated Plastic	12	9	
	C1030 SPECIALTIES	2008 C103008 COUNTERS Wood	12	12	
	C1030 SPECIALTIES	2008 C103009 CABINETS Other	12	8	
C20 STAIRS	C2010 STAIR CONSTRUCTION	2008 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Concrete	12	26	

NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	C2010 STAIR CONSTRUCTION	2008 C201001 INTERIOR AND EXTERIOR STAIRS Interior Stairs	12	52	
	C2010 STAIR CONSTRUCTION	2008 A C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES	12	10	
	C2010 STAIR CONSTRUCTION	2008 B C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES	12	10	4
C30 INTERIOR FINISHES	C3010 WALL FINISHES	2008 C301004 TILE & TERRAZZO WALL FINISHES Tile	12	23	
	C3020 FLOOR FINISHES	2008 C302001 TILE FLOOR FINISHES Ceramic Tile	12	31	
	C3020 FLOOR FINISHES	2008 C302004 RESILIENT FLOOR FINISHES Composition Sheet	12	7	
	C3020 FLOOR FINISHES	2008 C302005 CARPETING General	12	0	
	C3030 CEILING FINISHES	2008 C303001 ACOUSTICAL CEILING TILES & PANELS General	12	29	
	C3030 CEILING FINISHES	2008 C303002 GYPSUM WALLBOARD CEILING FINISHES General	12	65	Unknown
	C3030 CEILING FINISHES	2008 C303003 PLASTER CEILING FINISHES General	12	65	Unknown
	C3030 CEILING FINISHES	2008 C303005 SUSPENSION SYSTEMS General	12	8	
D10 CONVEYING	D1010 ELEVATORS AND LIFTS	2008 ROOM 151E101004 WHEELCHAIR LIFT Inclined, stair lift	12	6	
	D1010 ELEVATORS AND LIFTS	2008 ROOM E101 D101002 PASSENGER ELEVATORS Hydraulic Elevators -	12	10	
	D1010 ELEVATORS AND LIFTS	2008 ROOM E102.1 D101002 PASSENGER ELEVATORS Hydraulic Elevators -	12	16	
D20 PLUMBING	D2010 PLUMBING FIXTURES	2008 D201001 WATERCLOSERS General	12	8	
	D2010 PLUMBING FIXTURES	2008 D201004 SINKS General	12	8	
	D2010 PLUMBING FIXTURES	2008 D201004 SINKS Kitchen Sink	12	14	
	D2010 PLUMBING FIXTURES	2008 D201004 SINKS Service Sink	12	8	
	D2010 PLUMBING FIXTURES	2008 D201006 DRINKING FOUNTAINS AND COOLERS Water Cooler	5	10	
	D2020 DOMESTIC WATER	2008 D202001 PIPES & FITTINGS General	12	38	
	D2020 DOMESTIC WATER	2008 D202002 VALVES & HYDRANTS Backflow Preventer - 6" pipe	3	8	
	D2020 DOMESTIC WATER	2008 ROOM 59 D202003 DOMESTIC WATER EQUIPMENT Booster Pump - 3	12	10	
	D2020 DOMESTIC WATER	2008 ROOM 59 D202003 DOMESTIC WATER EQUIPMENT Booster Pump - 5	12	2	
	D2020 DOMESTIC WATER	2008 ROOM 59 D202003 DOMESTIC WATER EQUIPMENT Storage Tank -	12	26	
	D2020 DOMESTIC WATER	2008 ROOM 59 D202003 DOMESTIC WATER EQUIPMENT Water Heaters,	4	5	
	D2030 SANITARY WASTE	2008 D203001 WASTE PIPE & FITTINGS General	12	38	
	D2030 SANITARY WASTE	2008 D203002 VENT PIPE & FITTINGS General	12	8	
	D2030 SANITARY WASTE	2008 D203003 FLOOR DRAINS General	12	6	
D30 HVAC	D3020 HEAT GENERATING SYSTEMS	2008 D302004 AUXILIARY EQUIPMENT Expansion Tank - 24 gal	3	20	
	D3020 HEAT GENERATING SYSTEMS	2008 ROOM 56 D302004 AUXILIARY EQUIPMENT Expansion Tank - 100 gal	12	12	



Remaining Service Life (RSL) Detail Report



NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	D3020 HEAT GENERATING SYSTEMS	2008 ROOM 56 D302004 AUXILIARY EQUIPMENT Expansion Tank - 60 gal	4	20	
	D3020 HEAT GENERATING SYSTEMS	2008 ROOM 59 D302004 AUXILIARY EQUIPMENT Expansion Tank - 60 gal	3	16	
	D3030 COOLING GENERATING SYSTEMS	2008 CHILLER 1 D303001 CHILLED WATER SYSTEMS Chiller, Rotary Screw - 1100 CFM	12	4	
	D3030 COOLING GENERATING SYSTEMS	2008 CHILLER 2 D303001 CHILLED WATER SYSTEMS Chiller, Rotary Screw - 1100 CFM	12	4	
	D3030 COOLING GENERATING SYSTEMS	2008 CHILLER 3 D303001 CHILLED WATER SYSTEMS Chiller, Rotary Screw - 1100 CFM	12	4	
	D3030 COOLING GENERATING SYSTEMS	2008 CHILLER 4 D303001 CHILLED WATER SYSTEMS Chiller, Rotary Screw - 1100 CFM	12	4	
	D3040 DISTRIBUTION SYSTEMS	2008 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	12	28	
	D3040 DISTRIBUTION SYSTEMS	2008 D304001 AIR DISTRIBUTION, HEATING & COOLING VAV Terminal	12	9	
	D3040 DISTRIBUTION SYSTEMS	2008 D304003 HOT WATER DISTRIBUTION SYSTEMS General	12	8	
	D3040 DISTRIBUTION SYSTEMS	2008 D304005 CHILLED WATER DISTRIBUTION SYSTEMS General	12	8	
	D3040 DISTRIBUTION SYSTEMS	2008 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 500 CFM	12	4	
	D3040 DISTRIBUTION SYSTEMS	2008 ROOM 253 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 500 CFM	12	3	
	D3040 DISTRIBUTION SYSTEMS	2008 ROOM 350 D304008 AIR HANDLING UNITS Central Station - 10000 CFM	12	6	
	D3040 DISTRIBUTION SYSTEMS	2008 ROOM 350 D304008 AIR HANDLING UNITS Central Station - 15000 CFM,	12	6	
	D3040 DISTRIBUTION SYSTEMS	2008 ROOM 56 D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating	5	10	
	D3040 DISTRIBUTION SYSTEMS	2008 ROOM 56 D304006 CHILLED WATER DISTRIBUTION SYSTEMS	12	4	
	D3040 DISTRIBUTION SYSTEMS	2008 ROOM 56 D304006 CHILLED WATER DISTRIBUTION SYSTEMS	12	6	
	D3040 DISTRIBUTION SYSTEMS	2008 ROOM 57 D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating	12	4	
	D3040 DISTRIBUTION SYSTEMS	2008 ROOM 57 D304008 AIR HANDLING UNITS Central Station - 10000 CFM,	12	3	
	D3050 TERMINAL & PACKAGE UNITS	2008 D305001 UNIT VENTILATORS Fan System, Centrifugal In-Line - 500 CFM	12	6	
	D3050 TERMINAL & PACKAGE UNITS	2008 ROOM 252 D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air	4	10	
	D3050 TERMINAL & PACKAGE UNITS	2008 ROOM 56 D305002 UNIT HEATERS Hydronic - 70 MBH	12	9	
	D3060 CONTROLS & INSTRUMENTATION	2008 D306002 ELECTRONIC CONTROLS General	12	3	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION	2008 D401001 FIRE ALARM DISTRIBUTION Other	12	8	
	D4020 FIRE SUPP WATER SUPPLY / EQUIPMENT	2008 D402001 FIRE PROTECTION WATER PIPING AND EQUIPMENT Backflow	12	21	
	D4040 SPRINKLERS	2008 D404001 SPRINKLERS AND RELEASING DEVICES Wet Pipe Systems	12	63	
D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 D501004 PANELBOARDS Main lugs, 50 amp	12	6	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp, NQOD	12	9	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 D501004 PANELBOARDS Main lugs, 120/240 V, 225 amp, NQOD	12	9	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 D501004 PANELBOARDS Main lugs, 125 amp	12	6	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 D501004 PANELBOARDS Safety Switch, 30-100 Amp	12	9	

NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 D501006 MOTOR CONTROL CENTERS Motor Control Center - Size 3, 50	12	12	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 ROOM 59 D501002 SERVICE ENTRANCE EQUIPMENT Electrical Service	12	8	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 ROOM 59 D501004 PANELBOARDS Main lugs, 400 amp	12	8	
	D5020 LIGHTING & BRANCH WIRING	2008 D502001 BRANCH WIRING General	12	48	
	D5020 LIGHTING & BRANCH WIRING	2008 D502002 LIGHTING EQUIPMENT Exit Lighting	12	8	
	D5020 LIGHTING & BRANCH WIRING	2008 D502002 LIGHTING EQUIPMENT Exterior Lighting	12	8	
	D5020 LIGHTING & BRANCH WIRING	2008 D502002 LIGHTING EQUIPMENT General	12	8	
	D5030 COMMUNICATIONS & EQUIPMENT	2008 D503001 TELECOMMUNICATIONS SYSTEMS General	12	6	
	D5030 COMMUNICATIONS & EQUIPMENT	2008 D503002 PUBLIC ADDRESS SYSTEMS 30 outlets	12	6	
	D5030 COMMUNICATIONS & EQUIPMENT	2008 D503003 INTERCOMMUNICATIONS SYSTEMS 12 stations	12	4	
	D5030 COMMUNICATIONS & EQUIPMENT	2008 D503004 SECURITY SYSTEMS General	6	8	
	D5090 OTHER ELECTRICAL	2008 D509001 EMERGENCY LIGHTING & POWER General	12	8	
	D5090 OTHER ELECTRICAL	2008 D509002 EMERGENCY LIGHTING & POWER Uninterruptible Power	12	10	
	D5090 OTHER ELECTRICAL	2008 D509003 GROUNDING SYSTEMS General	12	38	
	D5090 OTHER ELECTRICAL	2008 D509006 ENERGY MANAGEMENT CONTROL SYSTEM General	12	8	
E10 EQUIPMENT	E1090 OTHER EQUIPMENT	*COLD PAN SINGLE BASIN E109001 FOOD SERVICE EQUIPMENT General	12	13	
	E1090 OTHER EQUIPMENT	*DISH MACHINE E109002 FOOD SERVICE EQUIPMENT General	12	13	
	E1090 OTHER EQUIPMENT	*HOT CABINET REACH IN 2 DR A E109003 FOOD SERVICE EQUIPMENT	12	13	
	E1090 OTHER EQUIPMENT	*HOT CABINET REACH IN 2 DR B E109002 FOOD SERVICE EQUIPMENT	12	13	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2DR A E109002 FOOD SERVICE EQUIPMENT	12	13	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2DR B E109002 FOOD SERVICE EQUIPMENT	12	13	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN E109003 FOOD SERVICE EQUIPMENT	12	13	

NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1999 B201005 EXTERIOR LOUVERS & SCREENS General	21	8	3
	B2010 EXTERIOR WALLS	1999 B201006 BALCONY WALLS & HANDRAILS Handrailing	21	8	6
	B2010 EXTERIOR WALLS	1999 B201007 EXTERIOR SOFFITS General	21	4	0
	B2010 EXTERIOR WALLS	1999 A B201001 EXTERIOR CLOSURE Brick Veneer w/CMU Backup	21	39	
	B2010 EXTERIOR WALLS	1999 A B201001 EXTERIOR CLOSURE Stucco	21	12	4
	B2010 EXTERIOR WALLS	1999 A B201010 EXTERIOR JOINT SEALANT General	21	0	
	B2010 EXTERIOR WALLS	1999 B B201001 EXTERIOR CLOSURE Brick Veneer w/CMU Backup	21	39	
	B2010 EXTERIOR WALLS	1999 B B201001 EXTERIOR CLOSURE Stucco	21	8	0
	B2010 EXTERIOR WALLS	1999 B B201010 EXTERIOR JOINT SEALANT General	21	8	
	B2020 EXTERIOR WINDOWS	1999 B202001 EXTERIOR WINDOWS Aluminum Windows	21	31	
	B2020 EXTERIOR WINDOWS	1999 B202001 STOREFRONTS General	21	6	
	B2030 EXTERIOR DOORS	1999 B203001 SOLID DOORS Steel	21	6	
	B2030 EXTERIOR DOORS	1999 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress	21	6	
B30 ROOFING	B3010 ROOF COVERINGS	1999 B301001 STEEP SLOPE ROOF SYSTEMS Clay Tile	21	22	
	B3010 ROOF COVERINGS	1999 B301003 ROOF INSULATION & FILL General	21	0	
	B3010 ROOF COVERINGS	1999 B301004 FLASHINGS & TRIM Flashings - Apron	21	8	
	B3010 ROOF COVERINGS	1999 B301004 FLASHINGS & TRIM Flashings - Cap	21	8	
	B3010 ROOF COVERINGS	1999 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	21	5	
	B3010 ROOF COVERINGS	1999 B301004 FLASHINGS & TRIM Flashings - Valley	21	8	
	B3010 ROOF COVERINGS	1999 B301004 FLASHINGS & TRIM General	21	8	
	B3010 ROOF COVERINGS	1999 B301005 GUTTERS & DOWNSPOUTS Downspouts	21	8	5
	B3010 ROOF COVERINGS	1999 B301005 GUTTERS & DOWNSPOUTS Gutters	21	8	
C10 INTERIOR	C1010 PARTITIONS	1999 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing	21	65	Unknown
	C1010 PARTITIONS	1999 C101005 INTERIOR WINDOWS Metal Rollup / Coiling Grille	21	6	
	C1020 INTERIOR DOORS	1999 C102001 STANDARD INTERIOR DOORS Wood Door/Metal Frame	21	12	
	C1020 INTERIOR DOORS	1999 C102003 FIRE DOORS Fire Door - Swinging, Metal	21	12	
	C1020 INTERIOR DOORS	1999 C102003 FIRE DOORS Fire Door - Swinging, Wood	21	12	
	C1020 INTERIOR DOORS	1999 C102006 INTERIOR GATES General	21	6	
	C1020 INTERIOR DOORS	1999 C102090 OTHER INTERIOR SPECIALTY DOORS Cold Storage	21	8	
	C1030 SPECIALTIES	1999 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet	21	15	
	C1030 SPECIALTIES	1999 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Urinal	21	8	

NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	C1030 SPECIALTIES	1999 C103002 TOILET & BATH ACCESSORIES General	21	6	
	C1030 SPECIALTIES	1999 C103003 MARKER BOARDS & TACK BOARDS General	21	8	
	C1030 SPECIALTIES	1999 C103005 LOCKERS General	21	12	
	C1030 SPECIALTIES	1999 C103008 COUNTERS Laminated Plastic	21	12	
	C1030 SPECIALTIES	1999 C103009 CABINETS Other	21	4	
	C1030 SPECIALTIES	1999 C103010 CASEWORK General	21	4	
C20 STAIRS	C2010 STAIR CONSTRUCTION	1999 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Concrete	21	26	
	C2010 STAIR CONSTRUCTION	1999 C201001 INTERIOR AND EXTERIOR STAIRS Interior Stairs	21	52	
	C2010 STAIR CONSTRUCTION	1999 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES	21	10	2
	C2010 STAIR CONSTRUCTION	1999 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES	21	10	4
C30 INTERIOR FINISHES	C3010 WALL FINISHES	1999 C301001 TILE & TERRAZZO WALL FINISHES Tile	21	39	
	C3020 FLOOR FINISHES	1999 C302001 TILE FLOOR FINISHES Ceramic Tile	21	39	
	C3020 FLOOR FINISHES	1999 C302004 RESIN FLOOR FINISHES Composition Sheet	21	7	
	C3020 FLOOR FINISHES	1999 C302005 CARPETING General	10	3	
	C3030 CEILING FINISHES	1999 C303001 ACOUSTICAL CEILING TILES & PANELS General	21	22	
	C3030 CEILING FINISHES	1999 C303002 GYPSUM WALLBOARD CEILING FINISHES General	21	65	Unknown
	C3030 CEILING FINISHES	1999 C303003 PLASTER CEILING FINISHES General	21	65	5
	C3030 CEILING FINISHES	1999 C303005 SUSPENSION SYSTEMS General	21	6	
D10 CONVEYING	D1010 ELEVATORS AND LIFTS	1999 ROOM 63 D101002 PASSENGER ELEVATORS Hydraulic Elevators - 1500	21	10	
D20 PLUMBING	D2010 PLUMBING FIXTURES	1999 D201001 WATERCLOSETS General	21	4	
	D2010 PLUMBING FIXTURES	1999 D201002 URINALS General	21	6	
	D2010 PLUMBING FIXTURES	1999 D201004 SINKS General	21	4	
	D2010 PLUMBING FIXTURES	1999 D201004 SINKS Kitchen Sink	21	11	
	D2010 PLUMBING FIXTURES	1999 D201004 SINKS Service Sink	21	6	
	D2010 PLUMBING FIXTURES	1999 D201004 SINKS Stainless	21	6	
	D2010 PLUMBING FIXTURES	1999 D201006 DRINKING FOUNTAINS AND COOLERS Water Cooler	21	4	
	D2010 PLUMBING FIXTURES	1999 D201090 OTHER PLUMBING FIXTURES Stainless Steel Combo Unit	21	4	
	D2020 DOMESTIC WATER	1999 D202001 PIPES & FITTINGS General	21	29	
	D2020 DOMESTIC WATER	1999 D202002 VALVES & HYDRANTS Backflow Preventer - 4" pipe	21	8	
	D2020 DOMESTIC WATER	1999 D202003 DOMESTIC WATER EQUIPMENT Water Treatment Equipment	1	13	

NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	D2020 DOMESTIC WATER	1999 ROOM 10 D202003 DOMESTIC WATER EQUIPMENT Booster Pump - 2	10	8	
	D2020 DOMESTIC WATER	1999 ROOM 10 D202003 DOMESTIC WATER EQUIPMENT Storage Tank -	10	20	
	D2020 DOMESTIC WATER	1999 ROOM 10 D202003 DOMESTIC WATER EQUIPMENT Water Softener	21	6	
	D2030 SANITARY WASTE	1999 D203001 WASTE PIPE & FITTINGS General	21	29	
	D2030 SANITARY WASTE	1999 D203002 VENT PIPE & FITTINGS General	21	0	
	D2030 SANITARY WASTE	1999 A D203003 FLOOR DRAINS General	21	6	
	D2030 SANITARY WASTE	1999 B D203003 FLOOR DRAINS General	21	4	
D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1999 B-1 D302001 BOILERS Oil, HW - 700-1300 MBH	21	3	
	D3020 HEAT GENERATING SYSTEMS	1999 B-2 D302004 AUXILIARY EQUIPMENT Chemical Feedwater - 150 lb., 5 gallon,	21	0	
	D3020 HEAT GENERATING SYSTEMS	1999 B-2 D302001 BOILERS Oil, HW - 700-1300 MBH	21	3	
	D3020 HEAT GENERATING SYSTEMS	1999 B-3 D302001 BOILERS Oil, HW - 700-1300 MBH	21	3	
	D3020 HEAT GENERATING SYSTEMS	1999 ROOM 10 D302004 AUXILIARY EQUIPMENT Expansion Tank - 15 gal	9	16	
	D3020 HEAT GENERATING SYSTEMS	1999 ROOM 10 D302004 AUXILIARY EQUIPMENT Expansion Tank - 60 gal	21	6	
	D3020 HEAT GENERATING SYSTEMS	1999 ROOM 22 D302004 AUXILIARY EQUIPMENT Expansion Tank - 30 gal	21	12	
	D3030 COOLING GENERATING	1999 OUTSIDE D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air	21	2	
	D3030 COOLING GENERATING	1999 OUTSIDE D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air	21	0	
	D3040 DISTRIBUTION SYSTEMS	1999 D304001 AIR DISTRIBUTION, HEATING & COOLING Air Separator - Air	21	0	
	D3040 DISTRIBUTION SYSTEMS	1999 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	21	19	
	D3040 DISTRIBUTION SYSTEMS	1999 D304003 HOT WATER DISTRIBUTION SYSTEMS General	21	0	
	D3040 DISTRIBUTION SYSTEMS	1999 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	21	0	
	D3040 DISTRIBUTION SYSTEMS	1999 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 1500 CFM	21	2	
	D3040 DISTRIBUTION SYSTEMS	1999 ATTIC D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 1500	21	2	
	D3040 DISTRIBUTION SYSTEMS	1999 ATTIC D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 3500	21	2	
	D3040 DISTRIBUTION SYSTEMS	1999 ATTIC D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 800	21	4	
	D3040 DISTRIBUTION SYSTEMS	1999 ATTIC D304008 AIR HANDLING UNITS Central Station - 2000 CFM	14	6	
	D3040 DISTRIBUTION SYSTEMS	1999 ATTIC AHU-5 D304008 AIR HANDLING UNITS Central Station - 2000 CFM	21	3	
	D3040 DISTRIBUTION SYSTEMS	1999 ATTIC MAU-6 D304008 AIR HANDLING UNITS Central Station - 10000	21	3	
	D3040 DISTRIBUTION SYSTEMS	1999 EF 6A2 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 800	21	4	
	D3040 DISTRIBUTION SYSTEMS	1999 OUTSIDE KITCHEN D304007 EXHAUST SYSTEMS Fan System, Roof	21	4	
	D3040 DISTRIBUTION SYSTEMS	1999 ROOM 10 D304001 AIR DISTRIBUTION, HEATING & COOLING Air	21	11	
	D3040 DISTRIBUTION SYSTEMS	1999 ROOM 10 D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating	10	10	
	D3040 DISTRIBUTION SYSTEMS	1999 ROOM 165A D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust -	21	6	



Remaining Service Life (RSL) Detail Report



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
D3040 DISTRIBUTION SYSTEMS	D3040 DISTRIBUTION SYSTEMS	1999 ROOM 22 D304008 AIR HANDLING UNITS Central Station - 2000 CFM	21	1	
	D3040 DISTRIBUTION SYSTEMS	1999 ROOM G61 AHU 2 D304008 AIR HANDLING UNITS Central Station - 5000	21	1	
	D3040 DISTRIBUTION SYSTEMS	1999 ROOM G61 AHU 3 D304008 AIR HANDLING UNITS Central Station - 5000	21	1	
	D3040 DISTRIBUTION SYSTEMS	1999 ROOM G61 AHU 4 D304008 AIR HANDLING UNITS Central Station - 2000	21	1	
	D3040 DISTRIBUTION SYSTEMS	1999 ROOM M22 D304006 CHILLED WATER DISTRIBUTION SYSTEMS	2	13	
	D3050 TERMINAL & PACKAGE UNITS	1999 D305001 UNIT VENTILATORS Air Curtain	21	2	
	D3050 TERMINAL & PACKAGE UNITS	1999 D305001 UNIT VENTILATORS Fan System, Centrifugal In-Line - 500 CFM	21	6	
	D3050 TERMINAL & PACKAGE UNITS	1999 D305002 UNIT HEATERS Hydronic - 20 MBH	21	9	
	D3050 TERMINAL & PACKAGE UNITS	1999 D305003 FAN COIL UNITS Cab Mount, Four Pipe - 3 ton	21	3	
	D3050 TERMINAL & PACKAGE UNITS	1999 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton	21	3	
	D3050 TERMINAL & PACKAGE UNITS	1999 D305004 PACKAGE UNITS A/C Unit, Split Systems w/ Air Cooled	4	13	
	D3050 TERMINAL & PACKAGE UNITS	1999 OUTSIDE ROOM 10 D305006 PACKAGE UNITS Heat Pump, Air Source,	4	13	
	D3060 CONTROLS & INSTRUMENTATION	1999 D306002 ELECTRONIC CONTROLS General	21	0	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION	1999 D401001 FIRE ALARM DISTRIBUTION Other	21	0	
	D4020 FIRE SUPP WATER SUPPLY / EQUIP	1999 ROOM G61A D402002 FIRE PUMP 5" pump, 40 HP, 1000 GPM	21	6	
	D4040 SPRINKLERS	1999 D404001 SPRINKLERS AND RELEASING DEVICES Wet Pipe Systems	21	54	
	D4090 OTHER FIRE PROTECTION	1999 D409004 HOOD & DUCT FIRE PROTECTION General	21	10	
D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 D501002 SERVICE ENTRANCE EQUIPMENT Electrical Service - 3 Phase,	21	6	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 D501003 INTERIOR DISTRIBUTION TRANSFORMERS dry-type, 240/480	21	20	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 D501004 PANELBOARDS Main lugs, 50 amp	21	8	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp, NQOD	21	12	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 D501004 PANELBOARDS Main lugs, 200 amp	21	6	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 A D501004 PANELBOARDS Main lugs, 125 amp	21	6	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 PANEL KA D501004 PANELBOARDS Main lugs, 120/240 V, 225 amp,	21	9	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 ROOM 009 D501002 SERVICE ENTRANCE EQUIPMENT Electrical	21	6	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 ROOM 12A D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp,	14	12	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 ROOM 13 D501004 PANELBOARDS Main lugs, 125 amp	4	6	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 ROOM 21A D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp,	4	12	
	D5020 LIGHTING & BRANCH WIRING	1999 D502001 BRANCH WIRING General	21	39	
	D5020 LIGHTING & BRANCH WIRING	1999 D502002 LIGHTING EQUIPMENT Exit Lighting	21	6	
	D5020 LIGHTING & BRANCH WIRING	1999 D502002 LIGHTING EQUIPMENT Exterior Lighting	21	8	

NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	D5020 LIGHTING & BRANCH WIRING	1999 D502002 LIGHTING EQUIPMENT General	21	8	
	D5030 COMMUNICATIONS &	1999 D503001 TELECOMMUNICATIONS SYSTEMS General	21	6	
	D5030 COMMUNICATIONS &	1999 D503002 PUBLIC ADDRESS SYSTEMS 30 outlets	21	2	
	D5030 COMMUNICATIONS &	1999 D503003 INTERCOMMUNICATIONS SYSTEMS 25 stations	21	4	
	D5090 OTHER ELECTRICAL	1999 D509002 EMERGENCY LIGHTING & POWER General	21	6	
	D5090 OTHER ELECTRICAL	1999 D509002 EMERGENCY LIGHTING & POWER Uninterruptible Power	21	8	
	D5090 OTHER ELECTRICAL	1999 D509003 GROUNDING SYSTEMS General	21	29	
	D5090 OTHER ELECTRICAL	1999 D509006 ENERGY MANAGEMENT CONTROL SYSTEM General	21	0	
E10 EQUIPMENT	E1090 OTHER EQUIPMENT	*COOL PAN SINGLE BASIN E109002 FOOD SERVICE EQUIPMENT General	21	13	
	E1090 OTHER EQUIPMENT	*DISH MACHINE E109002 FOOD SERVICE EQUIPMENT General	21	13	
	E1090 OTHER EQUIPMENT	*GRIDDLE A E109002 FOOD SERVICE EQUIPMENT General	21	13	
	E1090 OTHER EQUIPMENT	*GRIDDLE B E109002 FOOD SERVICE EQUIPMENT General	21	13	
	E1090 OTHER EQUIPMENT	*HOT CABINET REACH IN DR E109002 FOOD SERVICE EQUIPMENT	21	13	
	E1090 OTHER EQUIPMENT	*HOT CABINET REACH IN DR E109002 FOOD SERVICE EQUIPMENT	21	13	
	E1090 OTHER EQUIPMENT	*ICE MACHINE E109002 FOOD SERVICE EQUIPMENT General	21	13	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN DR E109002 FOOD SERVICE EQUIPMENT	21	13	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN A E109002 FOOD SERVICE	21	13	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN B E109002 FOOD SERVICE	21	13	
	E1090 OTHER EQUIPMENT	*STEAMER 1 DOOR A E109002 FOOD SERVICE EQUIPMENT General	21	13	
	E1090 OTHER EQUIPMENT	*STEAMER 1 DOOR B E109002 FOOD SERVICE EQUIPMENT General	21	13	
	E1090 OTHER EQUIPMENT	*STEAMER 1 DOOR C E109002 FOOD SERVICE EQUIPMENT General	21	13	
	E1090 OTHER EQUIPMENT	*STEAMER 1 DOOR D E109002 FOOD SERVICE EQUIPMENT General	21	8	
	E1090 OTHER EQUIPMENT	*WALK IN COOLER A E109002 FOOD SERVICE EQUIPMENT General	21	13	
	E1090 OTHER EQUIPMENT	*WALK IN COOLER B E109002 FOOD SERVICE EQUIPMENT General	21	13	
	E1090 OTHER EQUIPMENT	*WALK IN FREEZER E109002 FOOD SERVICE EQUIPMENT General	21	13	

NAS1 Support Area

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	2008 B201001 EXTERIOR CLOSURE Stucco	12	8	0
	B2010 EXTERIOR WALLS	2008 B201001 EXTERIOR CLOSURE Wall Louver	12	16	6
	B2010 EXTERIOR WALLS	2008 B201007 EXTERIOR SOFFITS General	12	4	2
	B2010 EXTERIOR WALLS	2008 A B201010 EXTERIOR JOINT SEALANT General	12	0	
	B2010 EXTERIOR WALLS	2008 B B201010 EXTERIOR JOINT SEALANT General	12	8	
	B2010 EXTERIOR WALLS	2008 C B201010 EXTERIOR JOINT SEALANT General	12	8	
	B2020 EXTERIOR WINDOWS	2008 B202001 WINDOWS Aluminum Windows	12	23	
	B2030 EXTERIOR DOORS	2008 B203001 SOLID DOORS Steel	12	6	
	B2030 EXTERIOR DOORS	2008 B203007 GATES General	12	6	
	B2030 EXTERIOR DOORS	2008 B203009 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress	12	6	
B30 ROOFING	B3010 ROOF COVERINGS	2008 B301001 STEEP SLOPE ROOF SYSTEMS Clay Tile	12	14	
	B3010 ROOF COVERINGS	2008 B301003 ROOF INSULATION & FILL General	12	8	
	B3010 ROOF COVERINGS	2008 B301004 FLASHINGS & TRIM Flashings - Apron	12	10	
	B3010 ROOF COVERINGS	2008 B301004 FLASHINGS & TRIM Flashings - Base	12	10	
	B3010 ROOF COVERINGS	2008 B301004 FLASHINGS & TRIM Flashings - Cap	12	10	
	B3010 ROOF COVERINGS	2008 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	12	10	
	B3010 ROOF COVERINGS	2008 B301004 FLASHINGS & TRIM Flashings - Valley	12	10	
	B3010 ROOF COVERINGS	2008 B301005 GUTTERS & DOWNSPOUTS Downspouts	12	6	4
	B3010 ROOF COVERINGS	2008 B301005 GUTTERS & DOWNSPOUTS Gutters	12	4	
	B3010 ROOF COVERINGS	2008 B301006 ROOF OPENINGS AND SUPPORTS Hatches	12	31	
	B3010 ROOF COVERINGS	2008 B301090 OTHER ROOFING Walkway Protection	12	4	
	B3010 ROOF COVERINGS	2008 A B301004 FLASHINGS & TRIM General	12	10	
	B3010 ROOF COVERINGS	2008 B B301004 FLASHINGS & TRIM General	12	10	5
C10 INTERIOR	C1010 PARTITIONS	2008 C101001 FIXED PARTITIONS Wall - Drywall w/Stud Framing	12	26	Unknown
	C1010 PARTITIONS	2008 C101005 INTERIOR WINDOWS Interior Windows	12	26	
	C1020 INTERIOR DOORS	2008 C102001 STANDARD INTERIOR DOORS Wood Door/Metal Frame	12	21	
	C1020 INTERIOR DOORS	2008 C102002 GLAZED INTERIOR DOORS General	12	21	
	C1020 INTERIOR DOORS	2008 C102003 FIRE DOORS Fire Door - Swinging, Metal	12	16	
	C1030 SPECIALTIES	2008 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Shower	12	8	
	C1030 SPECIALTIES	2008 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet	12	8	
	C1030 SPECIALTIES	2008 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Urinal	12	8	

NAS1 Support Area

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	C1030 SPECIALTIES	2008 C103002 TOILET & BATH ACCESSORIES General	12	6	
	C1030 SPECIALTIES	2008 C103003 MARKER BOARDS & TACK BOARDS General	12	8	
	C1030 SPECIALTIES	2008 C103005 LOCKERS General	12	9	
	C1030 SPECIALTIES	2008 C103006 SHELIVING General	12	26	
	C1030 SPECIALTIES	2008 C103008 COUNTERS Laminated Plastic	12	12	
	C1030 SPECIALTIES	2008 C103009 CABINETS Other	12	8	
	C1030 SPECIALTIES	2008 C103010 CASEWORK General	12	8	
C20 STAIRS	C2010 STAIR CONSTRUCTION	2008 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Concrete	12	39	
	C2010 STAIR CONSTRUCTION	2008 C201001 INTERIOR AND EXTERIOR STAIRS Interior Stairs	12	31	
	C2010 STAIR CONSTRUCTION	2008 A C201000 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES	12	6	3
	C2010 STAIR CONSTRUCTION	2008 B C201000 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES	12	6	3
C30 INTERIOR FINISHES	C3010 WALL FINISHES	2008 C301004 TILE & TERRAZZO WALL FINISHES Tile	12	23	
	C3020 FLOOR FINISHES	2008 C302001 TILE FLOOR FINISHES Ceramic Tile	12	39	
	C3020 FLOOR FINISHES	2008 C302003 WOOD FLOORING General	12	21	
	C3020 FLOOR FINISHES	2008 C302004 RESILIENT FLOOR FINISHES Composition Sheet	12	7	
	C3020 FLOOR FINISHES	2008 C302005 CARPETING Carpet Tile	12	4	
	C3030 CEILING FINISHES	2008 C303001 ACOUSTICAL CEILING TILES & PANELS General	12	29	
	C3030 CEILING FINISHES	2008 C303002 GYPSUM WALLBOARD CEILING FINISHES General	12	65	Unknown
	C3030 CEILING FINISHES	2008 C303005 SUSPENSION SYSTEMS General	12	8	
D10 CONVEYING	D1010 ELEVATORS AND LIFTS	2008 ELEV #2 D101002 PASSENGER ELEVATORS Hydraulic Elevators - 1500	12	10	
D20 PLUMBING	D2010 PLUMBING FIXTURES	2008 D201001 WATERCLOSETS General	12	6	
	D2010 PLUMBING FIXTURES	2008 D201002 URINALS General	12	6	
	D2010 PLUMBING FIXTURES	2008 D201004 SINKS General	12	4	
	D2010 PLUMBING FIXTURES	2008 D201004 SINKS Kitchen Sink	12	7	
	D2010 PLUMBING FIXTURES	2008 D201004 SINKS Laboratory Sink	12	8	
	D2010 PLUMBING FIXTURES	2008 D201004 SINKS Service Sink	12	4	
	D2010 PLUMBING FIXTURES	2008 D201005 SHOWERS/TUBS Shower	12	8	
	D2010 PLUMBING FIXTURES	2008 D201006 DRINKING FOUNTAINS AND COOLERS Water Cooler	12	8	
	D2010 PLUMBING FIXTURES	2008 D201090 OTHER PLUMBING FIXTURES Emergency Eye Wash	12	5	
	D2010 PLUMBING FIXTURES	2008 D201090 OTHER PLUMBING FIXTURES Emergency Shower	12	10	

NAS1 Support Area

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	D2010 PLUMBING FIXTURES	2008 D201090 OTHER PLUMBING FIXTURES Washer / Dryer Hookup	12	8	
	D2020 DOMESTIC WATER	2008 D202001 PIPES & FITTINGS General	12	38	
	D2030 SANITARY WASTE	2008 D203001 WASTE PIPE & FITTINGS General	12	38	
	D2030 SANITARY WASTE	2008 D203002 VENT PIPE & FITTINGS General	12	8	
	D2030 SANITARY WASTE	2008 A D203003 FLOOR DRAINS General	12	8	
	D2030 SANITARY WASTE	2008 B D203003 FLOOR DRAINS General	12	2	
D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2008 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	12	28	
	D3040 DISTRIBUTION SYSTEMS	2008 D304001 AIR DISTRIBUTION, HEATING & COOLING VAV Terminal	12	16	
	D3040 DISTRIBUTION SYSTEMS	2008 D304003 HOT WATER DISTRIBUTION SYSTEMS General	12	8	
	D3040 DISTRIBUTION SYSTEMS	2008 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	12	8	
	D3040 DISTRIBUTION SYSTEMS	2008 AHU/2 D304008 AIR HANDLING UNITS Central Station - 20000 CFM, VAV	12	8	
	D3040 DISTRIBUTION SYSTEMS	2008 AHU/4 D304008 AIR HANDLING UNITS Central Station - 20000 CFM, VAV	12	8	
	D3040 DISTRIBUTION SYSTEMS	2008 AHU/5 D304008 AIR HANDLING UNITS Central Station - 30000 CFM, VAV	12	18	
	D3040 DISTRIBUTION SYSTEMS	2008 HRU/3 D304008 AIR HANDLING UNITS Central Station - 10000 CFM	12	8	
	D3040 DISTRIBUTION SYSTEMS	2008 HRU/4 D304008 AIR HANDLING UNITS Central Station - 10000 CFM	12	8	
	D3040 DISTRIBUTION SYSTEMS	2008 ROOM 320 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 2000 CFM	12	6	
	D3040 DISTRIBUTION SYSTEMS	2008 ROOM 320 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 2000 CFM	12	4	
	D3040 DISTRIBUTION SYSTEMS	2008 ROOM 320 D304007 EXHAUST SYSTEMS Fume Hood Exhaust System - 2000 CFM	12	4	
	D3050 TERMINAL & PACKAGE UNITS	2008 D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air Cooled	4	10	
	D3060 CONTROLS & INSTRUMENTATION	2008 D306002 ELECTRONIC CONTROLS General	12	3	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION	2008 D401001 FIRE ALARM DISTRIBUTION Other	12	8	
	D4040 SPRINKLERS	2008 D404001 SPRINKLERS AND RELEASING DEVICES Wet Pipe Systems	12	63	
D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 D501004 PANELBOARDS Main lugs, 50 amp	12	10	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp, NQOD	12	12	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 D501004 PANELBOARDS Safety Switch, 30-100 Amp	12	12	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 ROOM 035 D501002 SERVICE ENTRANCE EQUIPMENT Electrical	12	10	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 ROOM 320 D501004 PANELBOARDS Main lugs, 120/240 V, 225 amp,	12	12	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 ROOM 41 D501004 PANELBOARDS Main lugs, 50 amp	12	8	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 ROOM 41 D501004 PANELBOARDS Main lugs, 125 amp	12	8	
	D5020 LIGHTING & BRANCH WIRING	2008 D502001 BRANCH WIRING General	12	48	
	D5020 LIGHTING & BRANCH WIRING	2008 D502002 LIGHTING EQUIPMENT Exit Lighting	12	8	

NAS1 Support Area

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	D5020 LIGHTING & BRANCH WIRING	2008 D502002 LIGHTING EQUIPMENT Exterior Lighting	12	6	
	D5020 LIGHTING & BRANCH WIRING	2008 D502002 LIGHTING EQUIPMENT General	12	8	
	D5030 COMMUNICATIONS & SECURITY SYSTEMS	2008 D503001 TELECOMMUNICATIONS SYSTEMS General	12	4	
	D5030 COMMUNICATIONS & SECURITY SYSTEMS	2008 D503002 PUBLIC ADDRESS SYSTEMS 30 outlets	12	4	
	D5030 COMMUNICATIONS & SECURITY SYSTEMS	2008 D503003 INTERCOMMUNICATIONS SYSTEMS 25 stations	12	4	
	D5030 COMMUNICATIONS & SECURITY SYSTEMS	2008 D503005 SECURITY SYSTEMS General	12	6	
	D5030 COMMUNICATIONS & SECURITY SYSTEMS	2008 D503007 CLOCK & PROGRAM SYSTEMS General	12	6	
	D5090 OTHER ELECTRICAL	2008 D509002 EMERGENCY LIGHTING & POWER General	12	8	
	D5090 OTHER ELECTRICAL	2008 D509003 GROUNDING SYSTEMS General	12	38	
	D5090 OTHER ELECTRICAL	2008 D509006 ENERGY MANAGEMENT CONTROL SYSTEM General	12	10	

"Identification only"

NAS1 Support Area

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
B10 SUPERSTRUCTURE	B1020 ROOF CONSTRUCTION	1999 B102003 ROOF DECKS AND SLABS Unknown	21	19	
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1999 B201001 EXTERIOR CLOSURE Stone Veneer w/CMU Backup	21	39	
	B2010 EXTERIOR WALLS	1999 B201001 EXTERIOR CLOSURE Stucco	21	21	6
	B2010 EXTERIOR WALLS	1999 B201001 EXTERIOR CLOSURE Tile Veneer w/CMU Backup	21	39	
	B2010 EXTERIOR WALLS	1999 B201001 EXTERIOR CLOSURE Wall Louver	21	16	6
	B2010 EXTERIOR WALLS	1999 B201006 BALCONY WALLS & HANDRAILS Handrailing	21	8	6
	B2010 EXTERIOR WALLS	1999 B201007 EXTERIOR SOFFITS General	21	10	4
	B2010 EXTERIOR WALLS	1999 A B201010 EXTERIOR JOINT SEALANT General	21	10	
	B2010 EXTERIOR WALLS	1999 A B201011 SUN CONTROL DEVICES General	21	10	4
	B2010 EXTERIOR WALLS	1999 B B201010 EXTERIOR JOINT SEALANT General	21	10	
	B2010 EXTERIOR WALLS	1999 B B201011 SUN CONTROL DEVICES General	21	10	4
	B2010 EXTERIOR WALLS	1999 C B201010 EXTERIOR JOINT SEALANT General	21	10	
	B2020 EXTERIOR WINDOWS	1999 B202001 WINDOWS Aluminum Windows	21	39	
	B2030 EXTERIOR DOORS	1999 B203001 SOLID DOORS Steel	21	10	6
	B2030 EXTERIOR DOORS	1999 B203002 GLAZED DOORS General	21	16	5
	B2030 EXTERIOR DOORS	1999 B203004 OVERHEAD AND ROLL-UP DOORS Steel Rolling, Manual, 8'x8'	21	8	
	B2030 EXTERIOR DOORS	1999 B203007 GATES General	21	8	3
	B2030 EXTERIOR DOORS	1999 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress	21	8	
B30 ROOFING	B3010 ROOF COVERINGS	1999 B301001 STEEP SLOPE ROOF SYSTEMS Clay Tile	21	29	
	B3010 ROOF COVERINGS	1999 B301003 ROOF INSULATION & FILL General	21	0	
	B3010 ROOF COVERINGS	1999 B301004 FLASHINGS & TRIM Flashings - Apron	4	10	
	B3010 ROOF COVERINGS	1999 B301004 FLASHINGS & TRIM Flashings - Base	4	10	
	B3010 ROOF COVERINGS	1999 B301004 FLASHINGS & TRIM General	21	10	5
	B3010 ROOF COVERINGS	1999 B301005 GUTTERS & DOWNSPOUTS Downspouts	21	6	4
	B3010 ROOF COVERINGS	1999 B301005 GUTTERS & DOWNSPOUTS Gutters	21	6	
	B3010 ROOF COVERINGS	1999 B301090 OTHER ROOFING Walkway Protection	4	5	
	B3010 ROOF COVERINGS	1999 A B301004 FLASHINGS & TRIM Flashings - Cap	21	10	
	B3010 ROOF COVERINGS	1999 A B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	4	10	
	B3010 ROOF COVERINGS	1999 B B301004 FLASHINGS & TRIM Flashings - Cap	21	10	
	B3010 ROOF COVERINGS	1999 B B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	4	10	
C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	1999 C101001 FIXED PARTITIONS Wall - Drywall w/Stud Framing	21	26	Unknown

NAS1 Support Area

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	C1010 PARTITIONS	1999 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing	21	65	Unknown
	C1020 INTERIOR DOORS	1999 C102001 STANDARD INTERIOR DOORS Wood Door/Wood Frame	21	16	
	C1030 SPECIALTIES	1999 C103002 TOILET & BATH ACCESSORIES General	21	6	
	C1030 SPECIALTIES	1999 C103003 MARKER BOARDS & TACK BOARDS General	21	8	
	C1030 SPECIALTIES	1999 C103008 COUNTERS Laminated Plastic	21	12	
	C1030 SPECIALTIES	1999 C103008 COUNTERS Metal	21	12	
	C1030 SPECIALTIES	1999 C103009 CABINETS Other	21	8	
	C1030 SPECIALTIES	1999 C103010 CASEWORK General	21	8	
C20 STAIRS	C2010 STAIR CONSTRUCTION	2020 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Steps - Concrete	21	10	
C30 INTERIOR FINISHES	C3010 WALL FINISHES	1999 C301001 TILE & TERRAZZO WALL FINISHES General	21	31	Unknown
	C3020 FLOOR FINISHES	1999 C302001 TILE FLOOR FINISHES Ceramic Tile	21	31	
	C3030 CEILING FINISHES	1999 C303001 ACoustical CEILING TILES & PANELS General	21	0	
	C3030 CEILING FINISHES	1999 C303002 GYPsUM WALLBOARD CEILING FINISHES General	21	65	
	C3030 CEILING FINISHES	1999 C303005 SUSPENSION SYSTEMS General	21	0	
D20 PLUMBING	D2010 PLUMBING FIXTURES	1999 D201001 WATERCLOSERS General	21	4	
	D2010 PLUMBING FIXTURES	1999 D201004 SINKS General	21	4	
	D2010 PLUMBING FIXTURES	1999 D201004 SINKS Kitchen Sink	21	14	
	D2010 PLUMBING FIXTURES	1999 D201004 SINKS Service Sink	21	8	
	D2010 PLUMBING FIXTURES	1999 D201005 SHOWERS/TUBS Shower	21	10	
	D2020 DOMESTIC WATER	1999 D202001 PIPES & FITTINGS General	21	29	
	D2020 DOMESTIC WATER	1999 D202003 DOMESTIC WATER EQUIPMENT Water Heaters, Commercial,	21	3	
	D2020 DOMESTIC WATER	1999 ROOM 17 D202002 VALVES & HYDRANTS Backflow Preventer - 1.5" pipe	21	6	
	D2020 DOMESTIC WATER	1999 ROOM 17 D202003 DOMESTIC WATER EQUIPMENT Storage Tank -	21	3	
	D2020 DOMESTIC WATER	1999 ROOM 17 D202003 DOMESTIC WATER EQUIPMENT Water Softener	21	1	
	D2030 SANITARY WASTE	1999 D203001 WASTE PIPE & FITTINGS General	21	29	
	D2030 SANITARY WASTE	1999 D203002 VENT PIPE & FITTINGS General	21	0	
	D2030 SANITARY WASTE	1999 D203003 FLOOR DRAINS General	21	8	
D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1999 ROOM 17 D302001 BOILERS Gas, Hot Water - 250-400 MBH	18	6	
	D3020 HEAT GENERATING SYSTEMS	1999 ROOM 17 D302004 AUXILIARY EQUIPMENT Expansion Tank - 15 gal	18	16	
	D3020 HEAT GENERATING SYSTEMS	1999 ROOM 17 D302004 AUXILIARY EQUIPMENT Expansion Tank - 30 gal	9	12	

NAS1 Support Area

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
D3040 DISTRIBUTION SYSTEMS	D3040 DISTRIBUTION SYSTEMS	1999 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	21	19	
	D3040 DISTRIBUTION SYSTEMS	1999 D304003 HOT WATER DISTRIBUTION SYSTEMS General	21	0	
	D3040 DISTRIBUTION SYSTEMS	1999 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	21	0	
	D3040 DISTRIBUTION SYSTEMS	1999 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 800 CFM	21	6	
	D3040 DISTRIBUTION SYSTEMS	1999 ROOM 17 D304001 AIR DISTRIBUTION, HEATING & COOLING Air	21	18	
	D3040 DISTRIBUTION SYSTEMS	1999 ROOM 17 D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating	21	4	
	D3040 DISTRIBUTION SYSTEMS	1999 ROOM 17 D304006 CHILLED WATER DISTRIBUTION SYSTEMS	21	2	
	D3050 TERMINAL & PACKAGE UNITS	1999 D305003 FAN COIL UNITS Duct Mount, 4 Pipe - 2 ton	21	4	
	D3050 TERMINAL & PACKAGE UNITS	1999 D305003 FAN COIL UNITS Duct Mount, 4 Pipe - 5 ton	21	4	
	D3050 TERMINAL & PACKAGE UNITS	1999 D305006 FIN TUBE RADIATION Other	21	12	
	D3050 TERMINAL & PACKAGE UNITS	1999 ROOM 17 D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air	21	6	
	D3060 CONTROLS & INSTRUMENTATION	1999 D306007 ELECTRONIC CONTROLS General	21	3	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION	1999 D401001 FIRE ALARM DISTRIBUTION Other	21	0	
	D4040 SPRINKLERS	1999 D404001 SPRINKLERS AND RELEASING DEVICES Wet Pipe Systems	21	54	
D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 D501006 MOTOR CONTROL CENTERS Motor Control Center - Size 4, 100	18	16	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 ROOM 15 D501002 SERVICE ENTRANCE EQUIPMENT Electrical Service	18	6	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 ROOM 15 D501003 INTERIOR DISTRIBUTION TRANSFORMERS dry-	21	15	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 ROOM 15 D501004 PANELBOARDS Main lugs, 50 amp	21	8	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 ROOM 17 D501004 PANELBOARDS Main lugs, 120/240 V, 225 amp,	21	9	
	D5020 LIGHTING & BRANCH WIRING	1999 D502001 BRANCH WIRING General	21	39	
	D5020 LIGHTING & BRANCH WIRING	1999 D502002 LIGHTING EQUIPMENT Exit Lighting	21	4	
	D5020 LIGHTING & BRANCH WIRING	1999 D502002 LIGHTING EQUIPMENT Exterior Lighting	21	4	
	D5020 LIGHTING & BRANCH WIRING	1999 D502002 LIGHTING EQUIPMENT General	21	6	
	D5030 COMMUNICATIONS & DISTRIBUTION	1999 D503001 TELECOMMUNICATIONS SYSTEMS General	5	10	
	D5030 COMMUNICATIONS & DISTRIBUTION	1999 D503002 PUBLIC ADDRESS SYSTEMS 12 outlets	6	8	
	D5030 COMMUNICATIONS & DISTRIBUTION	1999 D503003 INTERCOMMUNICATIONS SYSTEMS 6 stations	21	6	
	D5030 COMMUNICATIONS & DISTRIBUTION	1999 D503007 CLOCK & PROGRAM SYSTEMS General	12	6	
	D5090 OTHER ELECTRICAL	1999 D509002 EMERGENCY LIGHTING & POWER General	21	6	
	D5090 OTHER ELECTRICAL	1999 D509002 EMERGENCY LIGHTING & POWER Uninterruptible Power	21	10	
	D5090 OTHER ELECTRICAL	1999 D509003 GROUNDING SYSTEMS General	21	29	

NAS1 Support Area

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	2008 B201001 EXTERIOR CLOSURE Stucco	12	8	0
	B2010 EXTERIOR WALLS	2008 B201001 EXTERIOR CLOSURE Wall Louver	12	12	5
	B2010 EXTERIOR WALLS	2008 B201007 EXTERIOR SOFFITS General	12	8	3
	B2010 EXTERIOR WALLS	2008 B201011 SUN CONTROL DEVICES General	12	8	3
	B2010 EXTERIOR WALLS	2008 A B201010 EXTERIOR JOINT SEALANT General	12	0	
	B2010 EXTERIOR WALLS	2008 B B201010 EXTERIOR JOINT SEALANT General	12	8	
	B2010 EXTERIOR WALLS	2008 C B201010 EXTERIOR JOINT SEALANT General	12	8	
	B2020 EXTERIOR WINDOWS	2008 B202001 WINDOWS Aluminum Windows	12	31	
	B2020 EXTERIOR WINDOWS	2008 B202002 STOREFRONTS General	12	8	
	B2030 EXTERIOR DOORS	2008 B203000 SOLID DOORS Steel	12	8	
	B2030 EXTERIOR DOORS	2008 B203000 GLAZED DOORS General	12	16	
	B2030 EXTERIOR DOORS	2008 B203007 GATES General	12	8	3
	B2030 EXTERIOR DOORS	2008 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress	12	8	
B30 ROOFING	B3010 ROOF COVERINGS	2008 B301001 STEEP SLOPE ROOF SYSTEMS Clay Tile	12	14	
	B3010 ROOF COVERINGS	2008 B301003 ROOF INSULATION & FILL General	12	8	
	B3010 ROOF COVERINGS	2008 B301004 FLASHINGS & TRIM Flashings - Cap	12	10	
	B3010 ROOF COVERINGS	2008 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	12	5	
	B3010 ROOF COVERINGS	2008 B301005 GUTTERS & DOWNSPOUTS Downspouts	12	4	3
	B3010 ROOF COVERINGS	2008 B301005 GUTTERS & DOWNSPOUTS Gutters	12	4	
	B3010 ROOF COVERINGS	2008 B301006 ROOF OPENINGS AND SUPPORTS Hatches	12	31	
	B3010 ROOF COVERINGS	2008 A B301004 FLASHINGS & TRIM General	12	5	
	B3010 ROOF COVERINGS	2008 B B301004 FLASHINGS & TRIM General	12	8	4
C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	2008 C101001 FIXED PARTITIONS Wall - Drywall w/Stud Framing	12	26	5
	C1010 PARTITIONS	2008 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing	12	65	5
	C1010 PARTITIONS	2008 C101005 INTERIOR WINDOWS Interior Windows	12	26	
	C1020 INTERIOR DOORS	2008 C102001 STANDARD INTERIOR DOORS Wood Door/Metal Frame	12	21	
	C1020 INTERIOR DOORS	2008 C102003 FIRE DOORS Fire Door - Swinging, Metal	12	16	
	C1020 INTERIOR DOORS	2008 C102003 FIRE DOORS Fire Door - Swinging, Wood	12	16	
	C1030 SPECIALTIES	2008 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet	12	10	
	C1030 SPECIALTIES	2008 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Urinal	12	10	
	C1030 SPECIALTIES	2008 C103002 TOILET & BATH ACCESSORIES General	12	10	

NAS1 Support Area

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	C1030 SPECIALTIES	2008 C103003 MARKER BOARDS & TACK BOARDS General	12	10	
	C1030 SPECIALTIES	2008 C103006 SHELIVING General	12	26	
	C1030 SPECIALTIES	2008 C103008 COUNTERS Laminated Plastic	12	16	
	C1030 SPECIALTIES	2008 C103009 CABINETS Other	12	8	
	C1030 SPECIALTIES	2008 C103010 CASEWORK General	12	8	
C20 STAIRS	C2010 STAIR CONSTRUCTION	2008 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Concrete	12	26	
	C2010 STAIR CONSTRUCTION	2008 C201001 INTERIOR AND EXTERIOR STAIRS Interior Stairs	12	41	
	C2010 STAIR CONSTRUCTION	2008 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES	12	6	3
	C2010 STAIR CONSTRUCTION	2008 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES	12	8	3
C30 INTERIOR FINISHES	C3010 WALL FINISHES	2008 C301001 TILE & TERRAZZO WALL FINISHES General	12	39	
	C3020 FLOOR FINISHES	2008 C302001 TILE FLOOR FINISHES Ceramic Tile	12	39	
	C3020 FLOOR FINISHES	2008 C302001 TILE FLOOR FINISHES Marble Tile	12	39	
	C3020 FLOOR FINISHES	2008 C302004 RESIN FLOOR FINISHES Composition Sheet	12	7	
	C3020 FLOOR FINISHES	2008 C302005 CARPETING General	12	3	
	C3030 CEILING FINISHES	2008 C303001 ACOUSTICAL CEILING TILES & PANELS General	12	29	
	C3030 CEILING FINISHES	2008 C303002 GYPSUM WALLBOARD CEILING FINISHES General	12	65	Unknown
	C3030 CEILING FINISHES	2008 C303003 PLASTER CEILING FINISHES General	12	65	Unknown
	C3030 CEILING FINISHES	2008 C303005 SUSPENSION SYSTEMS General	12	8	
D20 PLUMBING	D2010 PLUMBING FIXTURES	2008 D201001 WATERCLOSETS General	12	8	
	D2010 PLUMBING FIXTURES	2008 D201002 URINALS General	12	10	
	D2010 PLUMBING FIXTURES	2008 D201004 SINKS General	12	10	
	D2010 PLUMBING FIXTURES	2008 D201004 SINKS Kitchen Sink	12	14	
	D2010 PLUMBING FIXTURES	2008 D201004 SINKS Service Sink	12	8	
	D2010 PLUMBING FIXTURES	2008 D201005 SHOWERS/TUBS Shower	12	10	
	D2010 PLUMBING FIXTURES	2008 D201006 DRINKING FOUNTAINS AND COOLERS Water Cooler	12	10	
	D2020 DOMESTIC WATER DISTRIBUTION	2008 D202001 PIPES & FITTINGS General	12	38	
	D2030 SANITARY WASTE	2008 D203001 WASTE PIPE & FITTINGS General	12	38	
	D2030 SANITARY WASTE	2008 D203002 VENT PIPE & FITTINGS General	12	8	
	D2030 SANITARY WASTE	2008 D203003 FLOOR DRAINS General	12	10	
D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2008 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	12	28	

NAS1 Support Area

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	D3040 DISTRIBUTION SYSTEMS	2008 D304001 AIR DISTRIBUTION, HEATING & COOLING VAV Terminal	12	6	
	D3040 DISTRIBUTION SYSTEMS	2008 D304003 HOT WATER DISTRIBUTION SYSTEMS General	12	8	
	D3040 DISTRIBUTION SYSTEMS	2008 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	12	8	
	D3040 DISTRIBUTION SYSTEMS	2008 AHU 8 D304008 AIR HANDLING UNITS Central Station - 5000 CFM, VAV	12	6	
	D3040 DISTRIBUTION SYSTEMS	2008 AHU-6 D304008 AIR HANDLING UNITS Central Station - 30000 CFM, VAV	12	14	
	D3040 DISTRIBUTION SYSTEMS	2008 AHU-7 D304008 AIR HANDLING UNITS Central Station - 30000 CFM, VAV	12	14	
	D3040 DISTRIBUTION SYSTEMS	2008 HRU 6 D304008 AIR HANDLING UNITS Central Station - 10000 CFM, VAV	12	6	
	D3040 DISTRIBUTION SYSTEMS	2008 HRU 7 D304008 AIR HANDLING UNITS Central Station - 15000 CFM, VAV	12	6	
	D3040 DISTRIBUTION SYSTEMS	2008 ROOM 318 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust -	12	6	
	D3050 TERMINAL & PACKAGE UNITS	2008 D305001 PACKAGE UNITS A/C Unit, Split Systems w/ Air Cooled	4	10	
	D3060 CONTROLS & INSTRUMENTATION	2008 D306001 ELECTRONIC CONTROLS General	12	3	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SYSTEMS	2008 D401001 FIRE ALARM DISTRIBUTION Other	12	8	
	D4040 SPRINKLERS	2008 D404001 SPRINKLERS AND RELEASING DEVICES Wet Pipe Systems	12	63	
D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp, NQOD	12	9	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 D501004 PANELBOARDS Switchgear - 800 Amp	12	20	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 ROOM 318 D501004 PANELBOARDS Main lugs, 400 amp	12	8	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 ROOM 318 D501004 PANELBOARDS Main lugs, 600 amp	12	8	
	D5020 LIGHTING & BRANCH WIRING	2008 D502001 BRANCH WIRING General	12	48	
	D5020 LIGHTING & BRANCH WIRING	2008 D502002 LIGHTING EQUIPMENT Exit Lighting	12	10	
	D5020 LIGHTING & BRANCH WIRING	2008 D502002 LIGHTING EQUIPMENT Exterior Lighting	12	8	
	D5020 LIGHTING & BRANCH WIRING	2008 D502002 LIGHTING EQUIPMENT General	12	8	
	D5030 COMMUNICATIONS & TELEVISION	2008 D503001 TELECOMMUNICATIONS SYSTEMS General	12	8	
	D5030 COMMUNICATIONS & TELEVISION	2008 D503002 PUBLIC ADDRESS SYSTEMS 12 outlets	4	8	
	D5030 COMMUNICATIONS & TELEVISION	2008 D503003 INTERCOMMUNICATIONS SYSTEMS 50 stations	12	4	
	D5030 COMMUNICATIONS & TELEVISION	2008 D503007 CLOCK & PROGRAM SYSTEMS General	12	8	
	D5090 OTHER ELECTRICAL	2008 D509002 EMERGENCY LIGHTING & POWER General	12	8	
	D5090 OTHER ELECTRICAL	2008 D509002 EMERGENCY LIGHTING & POWER Uninterruptible Power	12	13	
	D5090 OTHER ELECTRICAL	2008 D509003 GROUNDING SYSTEMS General	12	38	
	D5090 OTHER ELECTRICAL	2008 D509004 LIGHTNING PROTECTION Unknown	12	26	
	D5090 OTHER ELECTRICAL	2008 D509006 ENERGY MANAGEMENT CONTROL SYSTEM General	12	8	

Appendix G

Direct Condition Rating Inspection By Section Report

"identification only"



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

Section Description	System	Component	Quantity (UM)
*COLD PAN SINGLE BASIN E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
*DISH MACHINE E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
*HOT CABINET REACH IN 2 DR A E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
*HOT CABINET REACH IN 2 DR B E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
*REFRIGERATOR REACH IN 2DR A E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
*REFRIGERATOR REACH IN 2DR B E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
*STEAM COUNTER ELECTRIC MULTI BASIN E109002 FOOD	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
2008 B102003 ROOF DECKS AND SLABS Deck - Steel	B10 SUPERSTRUCTURE	B1020 ROOF CONSTRUCTION	12,873 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 B201001 EXTERIOR CLOSURE Stucco	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	30,536 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The wall wainscot is severely deteriorated at several locations, with crumbling stucco and failed paint coating.	Condition Rating: A- Paint Rating: A-	Used Sampling? No Inspection Source: Inspection	
2008 B201005 EXTERIOR LOUVERS & SCREENS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	351 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+ Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 B201007 EXTERIOR SOFFITS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	3,790 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 B202001 WINDOWS Aluminum Windows	B20 EXTERIOR ENCLOSURE	B2020 EXTERIOR WINDOWS	62 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 B203001 SOLID DOORS Steel	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	12 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

Section Description	System	Component	Quantity (UM)
2008 B203090 OTHER EXTERIOR SPECIALTY DOORS	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	18 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 B301001 STEEP SLOPE ROOF SYSTEMS Clay Tile	B30 ROOFING	B3010 ROOF COVERINGS	12,873 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The tile roofing components appear to have minor deterioration, however, several active leaks were observed in the middle of the roof spans.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
2008 B301003 ROOF INSULATION & FILL General	B30 ROOFING	B3010 ROOF COVERINGS	12,873 (SF)
Last Inspection Date: 01-Jan-2008 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2008 B301004 FLASHINGS & TRIM Flashings - Apron	B30 ROOFING	B3010 ROOF COVERINGS	800 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 B301004 FLASHINGS & TRIM Flashings - Cap	B30 ROOFING	B3010 ROOF COVERINGS	154 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 B301004 FLASHINGS & TRIM Flashings - Cap	B30 ROOFING	B3010 ROOF COVERINGS	154 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 B301004 FLASHINGS & TRIM Flashings - Flashing	B30 ROOFING	B3010 ROOF COVERINGS	3 (EA)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: Several pipe vents and other penetrations appear to be leaking, with resulting damage to rooms below.		Condition Rating: A- Used Sampling? No Inspection Source: Inspection	
2008 B301004 FLASHINGS & TRIM Flashings - Valley	B30 ROOFING	B3010 ROOF COVERINGS	32 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:		Condition Rating: A Used Sampling? No Inspection Source: Inspection	
2008 B301004 FLASHINGS & TRIM General	B30 ROOFING	B3010 ROOF COVERINGS	200 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The flashings are generally deteriorated, with several active leaks observed.		Condition Rating: A- Paint Rating: A- Used Sampling? No Inspection Source: Inspection	
2008 B301005 GUTTERS & DOWNSPOUTS Downspouts	B30 ROOFING	B3010 ROOF COVERINGS	511 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The downspouts are discharging directly onto roof penetrations and lower roofs. Active leaks were observed at rooms below.		Condition Rating: A- Paint Rating: A- Used Sampling? No Inspection Source: Inspection	
2008 B301005 GUTTERS & DOWNSPOUTS Gutters	B30 ROOFING	B3010 ROOF COVERINGS	575 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:		Condition Rating: A Used Sampling? No Inspection Source: Inspection	
2008 B301006 ROOF OPENINGS AND SUPPORTS Hatches	B30 ROOFING	B3010 ROOF COVERINGS	2 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:		Condition Rating: A Used Sampling? No Inspection Source: Inspection	
2008 C101001 FIXED PARTITIONS Wall - Plaster w/Stud	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	37,941 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:		Condition Rating: G- Paint Rating: A Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

Section Description	System	Component	Quantity (UM)
2008 C102001 STANDARD INTERIOR DOORS Metal Door	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	6 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 C102001 STANDARD INTERIOR DOORS Wood	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	42 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 C102003 FIRE DOORS Fire Door - Swinging	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	15 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 C103002 TOILET & BATH ACCESSORIES General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	18 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C103003 MARKER BOARDS & TACK BOARDS General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	12 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C103005 LOCKERS General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	91 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C103008 COUNTERS Laminated Plastic	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	55 (LF)



NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 C103008 COUNTERS Wood	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	21 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C103009 CABINETS Other	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	146 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C201001 INTERIOR AND EXTERIOR STAIRS Exterior	C20 STAIRS	C2010 STAIR CONSTRUCTION	3 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The three stairs at Building 211 have minor deterioration of the tile steps. However, the stucco sides have severe damage, with exposed and heavily corroded metal corner beads.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
2008 C201001 INTERIOR AND EXTERIOR STAIRS Interior	C20 STAIRS	C2010 STAIR CONSTRUCTION	2 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 C301004 TILE & TERRAZZO WALL FINISHES Tile	C30 INTERIOR FINISHES	C3010 WALL FINISHES	4,469 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 C302001 TILE FLOOR FINISHES Ceramic Tile	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	5,404 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED]	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

Section Description	System	Component	Quantity (UM)
Inspection Comments:			
2008 C302004 RESILIENT FLOOR FINISHES Composition	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	10,973 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C302005 CARPETING General	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	1,662 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The carpet is worn and is tearing.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
2008 C303001 ACOUSTICAL CEILING TILES & PANELS	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	11,640 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C303002 GYPSUM WALLBOARD CEILING FINISHES	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	3,159 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G- Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C303003 PLASTER CEILING FINISHES General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	3,086 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G- Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C303005 SUSPENSION SYSTEMS General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	11,640 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 D201001 WATERCLOSETS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	6 (EA)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 D201004 SINKS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	6 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 D201004 SINKS Kitchen Sink	D20 PLUMBING	D2010 PLUMBING FIXTURES	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 D201004 SINKS Service Sink	D20 PLUMBING	D2010 PLUMBING FIXTURES	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 D201006 DRINKING FOUNTAINS AND COOLERS Water	D20 PLUMBING	D2010 PLUMBING FIXTURES	6 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 D202001 PIPES & FITTINGS General	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	8,398 (LF)
Last Inspection Date: 01-Jan-2008 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2008 D202002 VALVES & HYDRANTS Backflow Preventer - 6"	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

Section Description	System	Component	Quantity (UM)
2008 D203001 WASTE PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	4,199 (LF)
Last Inspection Date: 01-Jan-2008	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
Inspector:			
Inspection Comments: Original Inspection			
2008 D203002 VENT PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	1,021 (EA)
Last Inspection Date: 01-Jan-2008	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
Inspector:			
Inspection Comments: Original Inspection			
2008 D203003 FLOOR DRAINS General	D20 PLUMBING	D2030 SANITARY WASTE	8 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: A	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
2008 D302004 AUXILIARY EQUIPMENT Expansion Tank - 24	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	3 (EA)
Last Inspection Date: [REDACTED]	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
2008 D304001 AIR DISTRIBUTION, HEATING & COOLING	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	5,362 (LF)
Last Inspection Date: 01-Jan-2008	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
Inspector:			
Inspection Comments: Original Inspection			
2008 D304001 AIR DISTRIBUTION, HEATING & COOLING VAV	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	15 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: A	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
2008 D304003 HOT WATER DISTRIBUTION SYSTEMS General	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	720 (MBH)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 01-Jan-2008 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
2008 D304006 CHILLED WATER DISTRIBUTION SYSTEMS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	72 (TON)
Last Inspection Date: 01-Jan-2008 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
2008 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The exhaust fans are approaching the end of their statistical lives and show signs of minor corrosion.	Condition Rating: A-	Used Sampling? No	Inspection Source: Inspection
2008 D305001 UNIT VENTILATORS Fan System, Centrifugal In-	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No	Inspection Source: Inspection
2008 D306002 ELECTRONIC CONTROLS General	D30 HVAC	D3060 CONTROLS & INSTRUMENTATION	30 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No	Inspection Source: Inspection
2008 D401001 FIRE ALARM DISTRIBUTION Other	D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SY\$	28,780 (SF)
Last Inspection Date: 01-Jan-2008 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
2008 D402001 FIRE PROTECTION WATER PIPING AND	D40 FIRE PROTECTION	D4020 FIRE SUPP WATER SUPPLY / EQU	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No	Inspection Source: Inspection



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

Section Description	System	Component	Quantity (UM)
2008 D404001 SPRINKLERS AND RELEASING DEVICES Wet	D40 FIRE PROTECTION	D4040 SPRINKLERS	28,780 (SF)
Last Inspection Date: 01-Jan-2008 Condition Rating: G+ Used Sampling? No Inspector: Inspection Source: InstallDate Inspection Comments: Original Inspection			
2008 D501004 PANELBOARDS Main lugs, 50 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	4 (EA)
Last Inspection Date: 20-Jan-2020 Condition Rating: A Used Sampling? No Inspector: Inspection Source: Inspection Inspection Comments:			
2008 D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp,	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	16 (EA)
Last Inspection Date: 20-Jan-2020 Condition Rating: A Used Sampling? No Inspector: Inspection Source: Inspection Inspection Comments:			
2008 D501004 PANELBOARDS Main lugs, 120/240 V, 225 amp,	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	3 (EA)
Last Inspection Date: 20-Jan-2020 Condition Rating: A Used Sampling? No Inspector: Inspection Source: Inspection Inspection Comments:			
2008 D501004 PANELBOARDS Main lugs, 125 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	2 (EA)
Last Inspection Date: 20-Jan-2020 Condition Rating: A Used Sampling? No Inspector: Inspection Source: Inspection Inspection Comments:			
2008 D501004 PANELBOARDS Safety Switch, 30-100 Amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	12 (EA)
Last Inspection Date: 20-Jan-2020 Condition Rating: A Used Sampling? No Inspector: Inspection Source: Inspection Inspection Comments:			
2008 D501006 MOTOR CONTROL CENTERS Motor Control	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	2 (EA)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 D502001 BRANCH WIRING General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	28,780 (SF)
Last Inspection Date: 01-Jan-2008 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2008 D502002 LIGHTING EQUIPMENT Exit Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	22 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 D502002 LIGHTING EQUIPMENT Exterior Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	42 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 D502002 LIGHTING EQUIPMENT General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	28,780 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 D503001 TELECOMMUNICATIONS SYSTEMS General	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 D503002 PUBLIC ADDRESS SYSTEMS 30 outlets	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

Section Description	System	Component	Quantity (UM)
2008 D503003 INTERCOMMUNICATIONS SYSTEMS 12 stations	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	3 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 D503005 SECURITY SYSTEMS General	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 D509002 EMERGENCY LIGHTING & POWER General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	28,780 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 D509002 EMERGENCY LIGHTING & POWER	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	2 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 D509003 GROUNDING SYSTEMS General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	1 (EA)
Last Inspection Date: 01-Jan-2008 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2008 D509006 ENERGY MANAGEMENT CONTROL SYSTEM	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	28,780 (SF)
Last Inspection Date: 01-Jan-2008 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2008 A B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	600 (LF)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The sealant caulk is brittle or missing at several locations.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	
2008 A C201090 STAIR HANDRAILS, GUARDRAILS AND	C20 STAIRS	C2010 STAIR CONSTRUCTION	367 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 B B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1,000 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 B C201090 STAIR HANDRAILS, GUARDRAILS AND	C20 STAIRS	C2010 STAIR CONSTRUCTION	149 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G- Paint Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 CHILLER 1 D303001 CHILLED WATER SYSTEMS Chiller,	D30 HVAC	D3030 COOLING GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: Chiller 1 has minor corrosion and fin damage.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
2008 CHILLER 2 D303001 CHILLED WATER SYSTEMS Chiller,	D30 HVAC	D3030 COOLING GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: Chiller 2 has minor corrosion and fin damage.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
2008 CHILLER 3 D303001 CHILLED WATER SYSTEMS Chiller,	D30 HVAC	D3030 COOLING GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: Chiller 3 has minor corrosion and fin damage.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	



NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

Section Description	System	Component	Quantity (UM)
2008 CHILLER 4 D303001 CHILLED WATER SYSTEMS Chiller,	D30 HVAC	D3030 COOLING GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: Chiller 4 has minor corrosion and fin damage.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
2008 ROOM 151B D101004 WHEELCHAIR LIFT Inclined, rail	D10 CONVEYING	D1010 ELEVATORS AND LIFTS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 ROOM 252 D305006 PACKAGE UNITS A/C Unit, Split	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 ROOM 253 D304007 EXHAUST SYSTEMS Fan System,	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 ROOM 350 D304008 AIR HANDLING UNITS Central	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 ROOM 350 D304008 AIR HANDLING UNITS Central	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 ROOM 56 D302004 AUXILIARY EQUIPMENT Expansion	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1 (EA)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 ROOM 56 D302004 AUXILIARY EQUIPMENT Expansion	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	2 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
2008 ROOM 56 D304003 HOT WATER DISTRIBUTION	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 ROOM 56 D304006 CHILLED WATER DISTRIBUTION	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	4 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The chilled water circulating pumps are approaching the end of their statistical lives. Pump 1 is moderately corroded.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
2008 ROOM 56 D304006 CHILLED WATER DISTRIBUTION	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	3 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 ROOM 56 D305002 UNIT HEATERS Hydronic - 20 MBH	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	3 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 ROOM 57 D304003 HOT WATER DISTRIBUTION	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The circulating pumps are corroded on the motors and drive shafts.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	



NAS1 Support Area

211 - Sigonella MS/HS Bldg 211 Unassigned

Section Description	System	Component	Quantity (UM)
2008 ROOM 57 D304008 AIR HANDLING UNITS Central Station	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Condition Rating: A- Used Sampling? No Inspector: XXXXXXXXXX Inspection Source: Inspection Inspection Comments: Air handler 1 has corrosion on the inside of the unit.			
2008 ROOM 59 D202003 DOMESTIC WATER EQUIPMENT	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)
Last Inspection Date: 20-Jan-2020 Condition Rating: G- Used Sampling? No Inspector: XXXXXXXXXX Inspection Source: Inspection Inspection Comments:			
2008 ROOM 59 D202003 DOMESTIC WATER EQUIPMENT	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)
Last Inspection Date: 20-Jan-2020 Condition Rating: R+ Used Sampling? No Inspector: XXXXXXXXXX Inspection Source: Inspection Inspection Comments: The booster pump is severely corroded.			
2008 ROOM 59 D202003 DOMESTIC WATER EQUIPMENT	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)
Last Inspection Date: 20-Jan-2020 Condition Rating: G- Used Sampling? No Inspector: XXXXXXXXXX Inspection Source: Inspection Inspection Comments:			
2008 ROOM 59 D202003 DOMESTIC WATER EQUIPMENT	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	2 (EA)
Last Inspection Date: 20-Jan-2020 Condition Rating: G- Used Sampling? No Inspector: XXXXXXXXXX Inspection Source: Inspection Inspection Comments:			
2008 ROOM 59 D302004 AUXILIARY EQUIPMENT Expansion	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	2 (EA)
Last Inspection Date: 20-Jan-2020 Condition Rating: G- Used Sampling? No Inspector: XXXXXXXXXX Inspection Source: Inspection Inspection Comments:			
2008 ROOM 59 D501002 SERVICE ENTRANCE EQUIPMENT	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	3 (EA)



NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 ROOM 59 D501004 PANELBOARDS Main lugs, 400 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 ROOM E101 D101002 PASSENGER ELEVATORS	D10 CONVEYING	D1010 ELEVATORS AND LIFTS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 ROOM E102.1 D101002 PASSENGER ELEVATORS	D10 CONVEYING	D1010 ELEVATORS AND LIFTS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	

"Identification only"



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
*COLD PAN SINGLE BASIN E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
*DISH MACHINE E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
*GRIDDLE A E109002 FOOD SERVICE EQUIPMENT General	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
*GRIDDLE B E109002 FOOD SERVICE EQUIPMENT General	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
*HOT CABINET REACH IN 2 DR E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
*HOT CABINET REACH IN 4 DR E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
*ICE MACHINE E109002 FOOD SERVICE EQUIPMENT General	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
*REFRIGERATOR REACH IN 8 DR E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
*STEAM COUNTER ELECTRIC MULTI BASIN A E109002 FOOD	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
*STEAM COUNTER ELECTRIC MULTI BASIN B E109002 FOOD	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
*STEAMER 1 DOOR A E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
*STEAMER 1 DOOR B E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection
*STEAMER 1 DOOR C E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? Inspection Source:	No Inspection



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
*STEAMER 1 DOOR D E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: A+	Used Sampling? No	
Inspector: [REDACTED]		Inspection Source: Inspection	
Inspection Comments:			
*WALK IN COOLER A E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: G	Used Sampling? No	
Inspector: [REDACTED]		Inspection Source: Inspection	
Inspection Comments:			
*WALK IN COOLER B E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: G	Used Sampling? No	
Inspector: [REDACTED]		Inspection Source: Inspection	
Inspection Comments:			
*WALK IN FREEZER E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: G	Used Sampling? No	
Inspector: [REDACTED]		Inspection Source: Inspection	
Inspection Comments:			
1991 B-1 D302001 BOILERS Oil, HW - 700-1300 MBH	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: R+	Used Sampling? No	
Inspector: [REDACTED]		Inspection Source: Inspection	
Inspection Comments: The boiler is deteriorated.			
1999 B201005 EXTERIOR LOUVERS & SCREENS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	102 (SF)
Last Inspection Date: 20-Jan-2020	Condition Rating: A+	Used Sampling? No	
Inspector: [REDACTED]	Paint Rating: A+	Inspection Source: Inspection	
Inspection Comments:			
1999 B201006 BALCONY WALLS & HANDRAILS Handrailing	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	161 (LF)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G- Paint Rating: G-	Used Sampling? No Inspection Source: Inspection	
1999 B201007 EXTERIOR SOFFITS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	2,127 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The walkway soffit is deteriorated with spalled stucco and failed paint coating.	Condition Rating: A- Paint Rating: R	Used Sampling? No Inspection Source: Inspection	
1999 B202001 WINDOWS Aluminum Windows	B20 EXTERIOR ENCLOSURE	B2020 EXTERIOR WINDOWS	100 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 B202002 STOREFRONTS General	B20 EXTERIOR ENCLOSURE	B2020 EXTERIOR WINDOWS	1,495 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 B203001 SOLID DOORS Steel	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	12 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 B203090 OTHER EXTERIOR SPECIALTY DOORS	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	23 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 B301001 STEEP SLOPE ROOF SYSTEMS Clay Tile	B30 ROOFING	B3010 ROOF COVERINGS	12,475 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
1999 B301003 ROOF INSULATION & FILL General	B30 ROOFING	B3010 ROOF COVERINGS	12,475 (SF)
Last Inspection Date: 01-Jan-1999	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
Inspector:			
Inspection Comments: Original Inspection			
1999 B301004 FLASHINGS & TRIM Flashings - Apron	B30 ROOFING	B3010 ROOF COVERINGS	658 (LF)
Last Inspection Date: 20-Jan-2020	Condition Rating: A	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1999 B301004 FLASHINGS & TRIM Flashings - Cap	B30 ROOFING	B3010 ROOF COVERINGS	402 (LF)
Last Inspection Date: 20-Jan-2020	Condition Rating: A	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1999 B301004 FLASHINGS & TRIM Flashings - Flashing	B30 ROOFING	B3010 ROOF COVERINGS	8 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: A-	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments: The clay barrel tile roofing system has active leaks occurring at mid span areas, where pipe vents are located.			
1999 B301004 FLASHINGS & TRIM Flashings - Valley	B30 ROOFING	B3010 ROOF COVERINGS	85 (LF)
Last Inspection Date: 20-Jan-2020	Condition Rating: A	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1999 B301004 FLASHINGS & TRIM General	B30 ROOFING	B3010 ROOF COVERINGS	517 (LF)
Last Inspection Date: 20-Jan-2020	Condition Rating: A	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1999 B301005 GUTTERS & DOWNSPOUTS Downspouts	B30 ROOFING	B3010 ROOF COVERINGS	989 (LF)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+ Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 B301005 GUTTERS & DOWNSPOUTS Gutters	B30 ROOFING	B3010 ROOF COVERINGS	666 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 C101001 FIXED PARTITIONS Wall - Plaster w/Stud	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	59,168 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G- Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 C101005 INTERIOR WINDOWS Metal Rollup / Coiling	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	16 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 C102001 STANDARD INTERIOR DOORS Wood	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	46 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 C102003 FIRE DOORS Fire Door - Swinging, Metal	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	13 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 C102003 FIRE DOORS Fire Door - Swinging, Wood	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	28 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	

NAS1 Support Area

216 - Sigonella MS/HS Bldg 216	Sigonella MS/HS (HE5515)
--------------------------------	--------------------------

Section Description	System	Component	Quantity (UM)
1999 C102006 INTERIOR GATES General	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	2 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? Inspection Source:	No Inspection
1999 C102090 OTHER INTERIOR SPECIALTY DOORS CUB	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	3 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? Inspection Source:	No Inspection
1999 C103001 COMPARTMENTS, CUBICLES & TOILET	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	26 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? Inspection Source:	No Inspection
1999 C103001 COMPARTMENTS, CUBICLES & TOILET	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	6 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? Inspection Source:	No Inspection
1999 C103002 TOILET & BATH ACCESSORIES General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	81 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? Inspection Source:	No Inspection
1999 C103003 MARKER BOARDS & TACK BOARDS General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	133 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? Inspection Source:	No Inspection
1999 C103005 LOCKERS General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	264 (EA)

NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 C103008 COUNTERS Laminated Plastic	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	948 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 C103009 CABINETS Other	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	1,536 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The cabinets are worn and show signs of damage throughout the school.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1999 C103010 CASEWORK General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	1,284 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The casework is worn and shows signs of damage throughout the school.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1999 C201001 INTERIOR AND EXTERIOR STAIRS Exterior	C20 STAIRS	C2010 STAIR CONSTRUCTION	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The clay tile and cast concrete stairs have some areas of deterioration, with cracked tiles and spalled concrete.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1999 C201001 INTERIOR AND EXTERIOR STAIRS Interior	C20 STAIRS	C2010 STAIR CONSTRUCTION	3 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1999 C301004 TILE & TERRAZZO WALL FINISHES Tile	C30 INTERIOR FINISHES	C3010 WALL FINISHES	22,757 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
1999 C302001 TILE FLOOR FINISHES Ceramic Tile	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	24,000 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1999 C302004 RESILIENT FLOOR FINISHES Composition	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	782 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 C302005 CARPETING General	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	14,900 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 C303001 ACOUSTICAL CEILING TILES & PANELS	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	31,900 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 C303002 GYPSUM WALLBOARD CEILING FINISHES	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	4,700 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G- Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 C303003 PLASTER CEILING FINISHES General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	15,437 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G- Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 C303005 SUSPENSION SYSTEMS General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	31,900 (SF)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 D201001 WATERCLOSETS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	30 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The waterclosets have stains and minor corrosion on the piping.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1999 D201002 URINALS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	10 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 D201004 SINKS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	29 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The sinks have corrosion on the piping and drains.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1999 D201004 SINKS Kitchen Sink	D20 PLUMBING	D2010 PLUMBING FIXTURES	5 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 D201004 SINKS Service Sink	D20 PLUMBING	D2010 PLUMBING FIXTURES	5 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 D201004 SINKS Stainless	D20 PLUMBING	D2010 PLUMBING FIXTURES	6 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
1999 D201006 DRINKING FOUNTAINS AND COOLERS Water	D20 PLUMBING	D2010 PLUMBING FIXTURES	8 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: A-	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments: The water cooler units are damaged.			
1999 D201090 OTHER PLUMBING FIXTURES Stainless Steel	D20 PLUMBING	D2010 PLUMBING FIXTURES	21 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: A-	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments: The stainless sinks are corroded on the handles and faucets.			
1999 D202001 PIPES & FITTINGS General	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	19,447 (LF)
Last Inspection Date: 01-Jan-1999	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
Inspector: [REDACTED]			
Inspection Comments: Original Inspection			
1999 D202002 VALVES & HYDRANTS Backflow Preventer - 4"	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1999 D202003 DOMESTIC WATER EQUIPMENT Water	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1999 D203001 WASTE PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	9,725 (LF)
Last Inspection Date: 01-Jan-1999	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
Inspector: [REDACTED]			
Inspection Comments: Original Inspection			
1999 D203002 VENT PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	2,365 (EA)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 01-Jan-1999 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? Inspection Source:	No InstallDate
1999 D302004 AUXILIARY EQUIPMENT Chemical Feedwater -	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	2 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: Inspection Comments: The chemical feed water units are severely corroded.	Condition Rating: R	Used Sampling? Inspection Source:	No Inspection
1999 D304001 AIR DISTRIBUTION, HEATING & COOLING Air	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: Inspection Comments: The air separators are corroded on the piping and tanks.	Condition Rating: R	Used Sampling? Inspection Source:	No Inspection
1999 D304001 AIR DISTRIBUTION, HEATING & COOLING	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	11,665 (LF)
Last Inspection Date: 01-Jan-1999 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? Inspection Source:	No InstallDate
1999 D304003 HOT WATER DISTRIBUTION SYSTEMS General	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1,565 (MBH)
Last Inspection Date: 01-Jan-1999 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? Inspection Source:	No InstallDate
1999 D304006 CHILLED WATER DISTRIBUTION SYSTEMS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	157 (TON)
Last Inspection Date: 01-Jan-1999 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? Inspection Source:	No InstallDate
1999 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: Inspection Comments: The exhaust fans are approaching the end of their statistical lives.	Condition Rating: A-	Used Sampling? Inspection Source:	No Inspection

NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
1999 D305001 UNIT VENTILATORS Air Curtain	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	10 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The air curtain is deteriorated.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1999 D305001 UNIT VENTILATORS Fan System, Centrifugal	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 D305002 UNIT HEATERS Hydronic - 20 MBH	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	2 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 D305003 FAN COIL UNITS Cab Mount, Four Pipe - 3 ton	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	24 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The fan coil units were reported to have failures, debris, and minor corrosion.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1999 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	15 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The fan coil units are corroded and approaching the end of their statistical lives.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1999 D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	3 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1999 D306002 ELECTRONIC CONTROLS General	D30 HVAC	D3060 CONTROLS & INSTRUMENTATION	58 (EA)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The electronic controls were reported to have failures.	Condition Rating: R	Used Sampling? No	Inspection Source: Inspection
1999 D401001 FIRE ALARM DISTRIBUTION Other	D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SYSE	62,613 (SF)
Last Inspection Date: 01-Jan-1999 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
1999 D404001 SPRINKLERS AND RELEASING DEVICES Wet	D40 FIRE PROTECTION	D4040 SPRINKLERS	62,613 (SF)
Last Inspection Date: 01-Jan-1999 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
1999 D409004 HOOD & DUCT FIRE PROTECTION General	D40 FIRE PROTECTION	D4090 OTHER FIRE PROTECTION SYSTEI	2 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
1999 D501002 SERVICE ENTRANCE EQUIPMENT Electrical	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	2 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No	Inspection Source: Inspection
1999 D501003 INTERIOR DISTRIBUTION TRANSFORMERS	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	4 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
1999 D501004 PANELBOARDS Main lugs, 50 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	2 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
1999 D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp,	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	21 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1999 D501004 PANELBOARDS Main lugs, 200 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	3 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: A	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1999 D502001 BRANCH WIRING General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	62,613 (SF)
Last Inspection Date: 01-Jan-1999	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
Inspector:			
Inspection Comments: Original Inspection			
1999 D502002 LIGHTING EQUIPMENT Exit Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	25 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: A	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1999 D502002 LIGHTING EQUIPMENT Exterior Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	3 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1999 D502002 LIGHTING EQUIPMENT General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	62,613 (SF)
Last Inspection Date: 20-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1999 D503001 TELECOMMUNICATIONS SYSTEMS General	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 D503002 PUBLIC ADDRESS SYSTEMS 30 outlets	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: Inspection Comments: It was reported that the public address system does not reach all classrooms and is failing.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1999 D503003 INTERCOMMUNICATIONS SYSTEMS 25 stations	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 D509002 EMERGENCY LIGHTING & POWER General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	62,613 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 D509002 EMERGENCY LIGHTING & POWER	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	3 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 D509003 GROUNDING SYSTEMS General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	1 (EA)
Last Inspection Date: 01-Jan-1999 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1999 D509006 ENERGY MANAGEMENT CONTROL SYSTEM	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	62,613 (SF)
Last Inspection Date: 01-Jan-1999 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
1999 A B201001 EXTERIOR CLOSURE Brick Veneer w/CMU	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	6,820 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1999 A B201001 EXTERIOR CLOSURE Stucco	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	5,113 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 A B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	488 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The sealant caulk is brittle or missing at several locations	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	
1999 A C201090 STAIR HANDRAILS, GUARDRAILS AND	C20 STAIRS	C2010 STAIR CONSTRUCTION	790 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The paint finish on metal guardrails, is deteriorated at several locations.	Condition Rating: G- Paint Rating: A-	Used Sampling? No Inspection Source: Inspection	
1999 A D203003 FLOOR DRAINS General	D20 PLUMBING	D2030 SANITARY WASTE	12 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 A D501004 PANELBOARDS Main lugs, 125 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	9 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 ATTIC D304007 EXHAUST SYSTEMS Fan System, Roof	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2 (EA)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The exhaust fans are functional although beyond their statistical lives.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1999 ATTIC D304007 EXHAUST SYSTEMS Fan System, Roof	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	3 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The exhaust fans are functional although beyond their statistical lives.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1999 ATTIC D304007 EXHAUST SYSTEMS Fan System, Roof	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The exhaust fan is functional although beyond its statistical life.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1999 ATTIC D304008 AIR HANDLING UNITS Central Station -	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 ATTIC AHU-5 D304008 AIR HANDLING UNITS Central	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The air handler unit is corroded on the enclosure, seals, and piping.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1999 ATTIC MAU-6 D304008 AIR HANDLING UNITS Central	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The air handler unit is corroded on the enclosure, seals, and piping.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1999 B B201001 EXTERIOR CLOSURE Brick Veneer w/CMU	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	19,462 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
1999 B B201001 EXTERIOR CLOSURE Stucco	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	390 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The stucco system has several deteriorated areas, with spalled stucco and failed paint coating.	Condition Rating: A- Paint Rating: R	Used Sampling? No Inspection Source: Inspection	
1999 B B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	2,000 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 B C201090 STAIR HANDRAILS, GUARDRAILS AND	C20 STAIRS	C2010 STAIR CONSTRUCTION	60 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G- Paint Rating: G-	Used Sampling? No Inspection Source: Inspection	
1999 B D203003 FLOOR DRAINS General	D20 PLUMBING	D2030 SANITARY WASTE	5 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The floor drains have corrosion on the piping and grates.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1999 B-2 D302001 BOILERS Oil, HW - 700-1300 MBH	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The boiler is deteriorated on the enclosure and piping.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1999 B-3 D302001 BOILERS Oil, HW - 700-1300 MBH	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The boiler is deteriorated on the enclosure and piping.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1999 EF 6A2 D304007 EXHAUST SYSTEMS Fan System, Roof	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The exhaust fan is functional although beyond its statistical life.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1999 OUTSIDE D303001 CHILLED WATER SYSTEMS Chiller,	D30 HVAC	D3030 COOLING GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The chiller is deteriorating on the piping and exterior of the unit.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1999 OUTSIDE D303001 CHILLED WATER SYSTEMS Chiller,	D30 HVAC	D3030 COOLING GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The chiller is deteriorated on the piping and exterior of the unit. The chiller has fin damage.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	
1999 OUTSIDE KITCHEN D304007 EXHAUST SYSTEMS Fan	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The exhaust fans are beyond their statistical lives and are damaged.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1999 OUTSIDE ROOM 10 D305006 PACKAGE UNITS Heat	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1999 PANEL KA D501004 PANELBOARDS Main lugs, 120/240	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 ROOM 009 D501002 SERVICE ENTRANCE EQUIPMENT	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	3 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
1999 ROOM 10 D202003 DOMESTIC WATER EQUIPMENT	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 ROOM 10 D202003 DOMESTIC WATER EQUIPMENT	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 ROOM 10 D202003 DOMESTIC WATER EQUIPMENT	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 ROOM 10 D302004 AUXILIARY EQUIPMENT Expansion	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1999 ROOM 10 D302004 AUXILIARY EQUIPMENT Expansion	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The expansion tank is corroded.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1999 ROOM 10 D304001 AIR DISTRIBUTION, HEATING &	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 ROOM 10 D304003 HOT WATER DISTRIBUTION	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1999 ROOM 12A D501004 PANELBOARDS Main lugs, 120/240	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 ROOM 13 D501004 PANELBOARDS Main lugs, 125 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 ROOM 165A D304007 EXHAUST SYSTEMS Fan System,	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 ROOM 21A D501004 PANELBOARDS Main lugs, 120/240	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 ROOM 22 D302004 AUXILIARY EQUIPMENT Expansion	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 ROOM 22 D304008 AIR HANDLING UNITS Central Station	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The air handler unit is corroded.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
1999 ROOM 63 D101002 PASSENGER ELEVATORS Hydraulic	D10 CONVEYING	D1010 ELEVATORS AND LIFTS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 ROOM G61 AHU 2 D304008 AIR HANDLING UNITS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The air handler unit is corroded on the piping and seals.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1999 ROOM G61 AHU 3 D304008 AIR HANDLING UNITS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The air handler unit is corroded.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1999 ROOM G61 AHU 4 D304008 AIR HANDLING UNITS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The air handler unit is corroded on the enclosure and piping.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1999 ROOM G61A D402002 FIRE PUMP 5" pump, 40 HP, 1000	D40 FIRE PROTECTION	D4020 FIRE SUPP WATER SUPPLY / EQU	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 ROOM M22 D304006 CHILLED WATER DISTRIBUTION	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
2008 B201001 EXTERIOR CLOSURE Stucco	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	31,466 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The stucco wall system is severely deteriorated, with spalling stucco, exposed and corroded metal corner trim and failed paint coating at several locations.	Condition Rating: A- Paint Rating: R	Used Sampling? No Inspection Source: Inspection	
2008 B201001 EXTERIOR CLOSURE Wall Louver	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	159 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G- Paint Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 B201007 EXTERIOR SOFFITS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	3,898 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The exterior soffits under walkways, have some areas of deteriorated stucco and paint coating.	Condition Rating: A- Paint Rating: A-	Used Sampling? No Inspection Source: Inspection	
2008 B202001 WINDOWS Aluminum Windows	B20 EXTERIOR ENCLOSURE	B2020 EXTERIOR WINDOWS	347 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 B203001 SOLID DOORS Steel	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	10 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 B203007 GATES General	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	144 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 B203090 OTHER EXTERIOR SPECIALTY DOORS	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	16 (EA)



NAS1 Support Area

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No	Inspection Source: Inspection
2008 B301001 STEEP SLOPE ROOF SYSTEMS Clay Tile	B30 ROOFING	B3010 ROOF COVERINGS	14,237 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The clay barrel tile roofing system appears to be deteriorated, with active leaks at several areas.	Condition Rating: A-	Used Sampling? No	Inspection Source: Inspection
2008 B301003 ROOF INSULATION & FILL General	B30 ROOFING	B3010 ROOF COVERINGS	14,237 (SF)
Last Inspection Date: 01-Jan-2008 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
2008 B301004 FLASHINGS & TRIM Flashings - Apron	B30 ROOFING	B3010 ROOF COVERINGS	603 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
2008 B301004 FLASHINGS & TRIM Flashings - Base	B30 ROOFING	B3010 ROOF COVERINGS	125 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
2008 B301004 FLASHINGS & TRIM Flashings - Base	B30 ROOFING	B3010 ROOF COVERINGS	125 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
2008 B301004 FLASHINGS & TRIM Flashings - Cap	B30 ROOFING	B3010 ROOF COVERINGS	466 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
2008 B301004 FLASHINGS & TRIM Flashings - Flashing	B30 ROOFING	B3010 ROOF COVERINGS	7 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 B301004 FLASHINGS & TRIM Flashings - Valley	B30 ROOFING	B3010 ROOF COVERINGS	102 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 B301005 GUTTERS & DOWNSPOUTS Downspouts	B30 ROOFING	B3010 ROOF COVERINGS	529 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 B301005 GUTTERS & DOWNSPOUTS Gutters	B30 ROOFING	B3010 ROOF COVERINGS	448 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The gutter system appears deteriorated, with loose sections.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
2008 B301006 ROOF OPENINGS AND SUPPORTS Hatches	B30 ROOFING	B3010 ROOF COVERINGS	2 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 B301090 OTHER ROOFING Walkway Protection	B30 ROOFING	B3010 ROOF COVERINGS	6,600 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C101001 FIXED PARTITIONS Wall - Drywall w/Stud	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	53,000 (SF)



NAS1 Support Area

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G- Paint Rating: A	Used Sampling? Inspection Source:	No Inspection
2008 C101005 INTERIOR WINDOWS Interior Windows	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	21 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? Inspection Source:	No Inspection
2008 C102001 STANDARD INTERIOR DOORS Wood	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	80 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? Inspection Source:	No Inspection
2008 C102002 GLAZED INTERIOR DOORS General	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? Inspection Source:	No Inspection
2008 C102003 FIRE DOORS Fire Door - Swinging, Metal	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	19 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? Inspection Source:	No Inspection
2008 C103001 COMPARTMENTS, CUBICLES & TOILET	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	18 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? Inspection Source:	No Inspection
2008 C103001 COMPARTMENTS, CUBICLES & TOILET	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	12 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? Inspection Source:	No Inspection



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
2008 C103001 COMPARTMENTS, CUBICLES & TOILET	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	3 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C103002 TOILET & BATH ACCESSORIES General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	35 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 C103003 MARKER BOARDS & TACK BOARDS General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	53 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C103005 LOCKERS General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	304 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 C103006 SHELVING General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	28 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 C103008 COUNTERS Laminated Plastic	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	833 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C103009 CABINETS Other	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	1,137 (LF)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C103010 CASEWORK General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	87 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C201001 INTERIOR AND EXTERIOR STAIRS Exterior	C20 STAIRS	C2010 STAIR CONSTRUCTION	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 C201001 INTERIOR AND EXTERIOR STAIRS Interior	C20 STAIRS	C2010 STAIR CONSTRUCTION	2 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 C301004 TILE & TERRAZZO WALL FINISHES Tile	C30 INTERIOR FINISHES	C3010 WALL FINISHES	10,306 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 C302001 TILE FLOOR FINISHES Ceramic Tile	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	9,105 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 C302003 WOOD FLOORING General	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	6,855 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
2008 C302004 RESILIENT FLOOR FINISHES Composition	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	7,449 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C302005 CARPETING Carpet Tile	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	13,005 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C303001 ACOUSTICAL CEILING TILES & PANELS	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	22,942 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C303002 GYPSUM WALLBOARD CEILING FINISHES	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	4,286 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G- Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C303005 SUSPENSION SYSTEMS General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	22,942 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 D201001 WATERCLOSETS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	19 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 D201002 URINALS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	5 (EA)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: Condition Rating: A Used Sampling? No Inspection Source: Inspection			
2008 D201004 SINKS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	20 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The sinks have minor corrosion on the piping. Condition Rating: A- Used Sampling? No Inspection Source: Inspection			
2008 D201004 SINKS Kitchen Sink	D20 PLUMBING	D2010 PLUMBING FIXTURES	10 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The kitchen sinks have corrosion on the piping and faucets. Condition Rating: A- Used Sampling? No Inspection Source: Inspection			
2008 D201004 SINKS Laboratory Sink	D20 PLUMBING	D2010 PLUMBING FIXTURES	26 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: Condition Rating: A+ Used Sampling? No Inspection Source: Inspection			
2008 D201004 SINKS Service Sink	D20 PLUMBING	D2010 PLUMBING FIXTURES	4 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The service sinks have corrosion on the basins and faucets. Condition Rating: A- Used Sampling? No Inspection Source: Inspection			
2008 D201005 SHOWERS/TUBS Shower	D20 PLUMBING	D2010 PLUMBING FIXTURES	18 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: Condition Rating: A+ Used Sampling? No Inspection Source: Inspection			
2008 D201006 DRINKING FOUNTAINS AND COOLERS Water	D20 PLUMBING	D2010 PLUMBING FIXTURES	12 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: Condition Rating: A+ Used Sampling? No Inspection Source: Inspection			



NAS1 Support Area

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
2008 D201090 OTHER PLUMBING FIXTURES Emergency Eye	D20 PLUMBING	D2010 PLUMBING FIXTURES	3 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The emergency eye wash stations are covered in debris.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
2008 D201090 OTHER PLUMBING FIXTURES Emergency	D20 PLUMBING	D2010 PLUMBING FIXTURES	3 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 D201090 OTHER PLUMBING FIXTURES Washer / Dryer	D20 PLUMBING	D2010 PLUMBING FIXTURES	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 D202001 PIPES & FITTINGS General	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	14,928 (LF)
Last Inspection Date: 01-Jan-2008 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2008 D203001 WASTE PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	7,470 (LF)
Last Inspection Date: 01-Jan-2008 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2008 D203002 VENT PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	1,816 (EA)
Last Inspection Date: 01-Jan-2008 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2008 D304001 AIR DISTRIBUTION, HEATING & COOLING	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1,500 (LF)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 01-Jan-2008 Inspector: Inspection Comments: Original Inspection Condition Rating: G+ Used Sampling? No Inspection Source: InstallDate			
2008 D304001 AIR DISTRIBUTION, HEATING & COOLING VAV	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	30 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: Condition Rating: G- Used Sampling? No Inspection Source: Inspection			
2008 D304003 HOT WATER DISTRIBUTION SYSTEMS General	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1,200 (MBH)
Last Inspection Date: 01-Jan-2008 Inspector: Inspection Comments: Original Inspection Condition Rating: G+ Used Sampling? No Inspection Source: InstallDate			
2008 D304006 CHILLED WATER DISTRIBUTION SYSTEMS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	125 (TON)
Last Inspection Date: 01-Jan-2008 Inspector: Inspection Comments: Original Inspection Condition Rating: G+ Used Sampling? No Inspection Source: InstallDate			
2008 D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	4 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: Condition Rating: G- Used Sampling? No Inspection Source: Inspection			
2008 D306002 ELECTRONIC CONTROLS General	D30 HVAC	D3060 CONTROLS & INSTRUMENTATION	23 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: Condition Rating: A Used Sampling? No Inspection Source: Inspection			
2008 D401001 FIRE ALARM DISTRIBUTION Other	D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SY\$	48,062 (SF)
Last Inspection Date: 01-Jan-2008 Inspector: Inspection Comments: Original Inspection Condition Rating: G+ Used Sampling? No Inspection Source: InstallDate			



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
2008 D404001 SPRINKLERS AND RELEASING DEVICES Wet	D40 FIRE PROTECTION	D4040 SPRINKLERS	48,062 (SF)
Last Inspection Date: 01-Jan-2008	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
Inspector:			
Inspection Comments: Original Inspection			
2008 D501004 PANELBOARDS Main lugs, 50 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	6 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: G-	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
2008 D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp,	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	11 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
2008 D501004 PANELBOARDS Safety Switch, 30-100 Amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	3 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
2008 D502001 BRANCH WIRING General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	48,062 (SF)
Last Inspection Date: 01-Jan-2008	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
Inspector:			
Inspection Comments: Original Inspection			
2008 D502002 LIGHTING EQUIPMENT Exit Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	22 (EA)
Last Inspection Date: 20-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
2008 D502002 LIGHTING EQUIPMENT Exterior Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	79 (EA)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 D502002 LIGHTING EQUIPMENT General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	48,062 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 D503001 TELECOMMUNICATIONS SYSTEMS General	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The telecommunications system was reported to have failures throughout Building 220.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
2008 D503002 PUBLIC ADDRESS SYSTEMS 30 outlets	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The public address system is reported to have failures.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
2008 D503003 INTERCOMMUNICATIONS SYSTEMS 25 stations	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 D503005 SECURITY SYSTEMS General	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 D503007 CLOCK & PROGRAM SYSTEMS General	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	



NAS1 Support Area

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
2008 D509002 EMERGENCY LIGHTING & POWER General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	48,062 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 D509003 GROUNDING SYSTEMS General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	1 (EA)
Last Inspection Date: 01-Jan-2008 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2008 D509006 ENERGY MANAGEMENT CONTROL SYSTEM	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	48,062 (SF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 A B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	826 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The sealant caulk is brittle or missing at several locations.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	
2008 A B301004 FLASHINGS & TRIM General	B30 ROOFING	B3010 ROOF COVERINGS	82 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 A C201090 STAIR HANDRAILS, GUARDRAILS AND	C20 STAIRS	C2010 STAIR CONSTRUCTION	680 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 A D203003 FLOOR DRAINS General	D20 PLUMBING	D2030 SANITARY WASTE	18 (EA)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 AHU/3 D304008 AIR HANDLING UNITS Central Station -	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 AHU/4 D304008 AIR HANDLING UNITS Central Station -	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 AHU/5 D304008 AIR HANDLING UNITS Central Station -	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 B B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	5,000 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 B B301004 FLASHINGS & TRIM General	B30 ROOFING	B3010 ROOF COVERINGS	262 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+ Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 B C201090 STAIR HANDRAILS, GUARDRAILS AND	C20 STAIRS	C2010 STAIR CONSTRUCTION	125 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A Paint Rating: A	Used Sampling? No Inspection Source: Inspection	



NAS1 Support Area

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
2008 B D203003 FLOOR DRAINS General	D20 PLUMBING	D2030 SANITARY WASTE	3 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments: The floor drains and grates are severely corroded.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
2008 C B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	366 (LF)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 ELEV #2 D101002 PASSENGER ELEVATORS Hydraulic	D10 CONVEYING	D1010 ELEVATORS AND LIFTS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 HRU/3 D304008 AIR HANDLING UNITS Central Station -	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 HRU/4 D304008 AIR HANDLING UNITS Central Station -	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 ROOM 035 D501002 SERVICE ENTRANCE EQUIPMENT	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 ROOM 320 D304007 EXHAUST SYSTEMS Fan System,	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)



NAS1 Support Area

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 ROOM 320 D304007 EXHAUST SYSTEMS Fan System,	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 ROOM 320 D304007 EXHAUST SYSTEMS Fume Hood	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	3 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 ROOM 320 D501004 PANELBOARDS Main lugs, 120/240	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 ROOM 41 D501004 PANELBOARDS Main lugs, 50 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 ROOM 41 D501004 PANELBOARDS Main lugs, 125 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1 (EA)
Last Inspection Date: 20-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
1999 B102003 ROOF DECKS AND SLABS Unknown	B10 SUPERSTRUCTURE	B1020 ROOF CONSTRUCTION	15,154 (SF)
Last Inspection Date: 01-Jan-1999 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1999 B201001 EXTERIOR CLOSURE Stone Veneer w/CMU	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	974 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1999 B201001 EXTERIOR CLOSURE Stucco	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	16,594 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G- Paint Rating: G-	Used Sampling? No Inspection Source: Inspection	
1999 B201001 EXTERIOR CLOSURE Tile Veneer w/CMU	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	314 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1999 B201001 EXTERIOR CLOSURE Wall Louver	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	133 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G- Paint Rating: G-	Used Sampling? No Inspection Source: Inspection	
1999 B201006 BALCONY WALLS & HANDRAILS Handrailing	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	144 (LF)
Last Inspection Date: 16-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G- Paint Rating: G-	Used Sampling? No Inspection Source: Inspection	
1999 B201007 EXTERIOR SOFFITS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	2,442 (SF)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 16-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G- Paint Rating: G-	Used Sampling? No Inspection Source: Inspection	
1999 B202001 WINDOWS Aluminum Windows	B20 EXTERIOR ENCLOSURE	B2020 EXTERIOR WINDOWS	120 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1999 B203001 SOLID DOORS Steel	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	7 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G- Paint Rating: G-	Used Sampling? No Inspection Source: Inspection	
1999 B203002 GLAZED DOORS General	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	10 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A+ Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 B203004 OVERHEAD AND ROLL-UP DOORS Steel	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	2 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 B203007 GATES General	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	400 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A+ Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 B203090 OTHER EXTERIOR SPECIALTY DOORS	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	10 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
1999 B301001 STEEP SLOPE ROOF SYSTEMS Clay Tile	B30 ROOFING	B3010 ROOF COVERINGS	13,687 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 B301003 ROOF INSULATION & FILL General	B30 ROOFING	B3010 ROOF COVERINGS	13,687 (SF)
Last Inspection Date: 01-Jan-1999 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1999 B301004 FLASHINGS & TRIM Flashings - Apron	B30 ROOFING	B3010 ROOF COVERINGS	1,228 (LF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 B301004 FLASHINGS & TRIM Flashings - Base	B30 ROOFING	B3010 ROOF COVERINGS	1,184 (LF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 B301004 FLASHINGS & TRIM General	B30 ROOFING	B3010 ROOF COVERINGS	423 (LF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+ Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 B301005 GUTTERS & DOWNSPOUTS Downspouts	B30 ROOFING	B3010 ROOF COVERINGS	226 (LF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 B301005 GUTTERS & DOWNSPOUTS Gutters	B30 ROOFING	B3010 ROOF COVERINGS	741 (LF)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 B301090 OTHER ROOFING Walkway Protection	B30 ROOFING	B3010 ROOF COVERINGS	3,534 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1999 C101001 FIXED PARTITIONS Wall - Drywall w/Stud	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	14,400 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G- Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 C101001 FIXED PARTITIONS Wall - Plaster w/Stud	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	1,662 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G- Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 C102001 STANDARD INTERIOR DOORS Wood	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	23 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 C103002 TOILET & BATH ACCESSORIES General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	24 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 C103003 MARKER BOARDS & TACK BOARDS General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	17 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
1999 C103008 COUNTERS Laminated Plastic	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	66 (LF)
Last Inspection Date: 16-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1999 C103008 COUNTERS Metal	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	73 (LF)
Last Inspection Date: 16-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1999 C103009 CABINETS Other	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	361 (LF)
Last Inspection Date: 16-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1999 C103010 CASEWORK General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	75 (LF)
Last Inspection Date: 16-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1999 C301004 TILE & TERRAZZO WALL FINISHES General	C30 INTERIOR FINISHES	C3010 WALL FINISHES	3,700 (SF)
Last Inspection Date: 16-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1999 C302001 TILE FLOOR FINISHES Ceramic Tile	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	9,389 (SF)
Last Inspection Date: 16-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1999 C303001 ACOUSTICAL CEILING TILES & PANELS	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	5,952 (SF)



NAS1 Support Area

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 16-Jan-2020 Condition Rating: R Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments: The acoustical ceiling tiles are stained and damaged in several areas.			
1999 C303002 GYPSUM WALLBOARD CEILING FINISHES	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	3,664 (SF)
Last Inspection Date: 16-Jan-2020 Condition Rating: G- Used Sampling? No Inspector: [REDACTED] Paint Rating: A+ Inspection Source: Inspection Inspection Comments:			
1999 C303005 SUSPENSION SYSTEMS General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	5,952 (SF)
Last Inspection Date: 16-Jan-2020 Condition Rating: R Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments: The ceiling suspension grid is bent and broken in some areas.			
1999 D201001 WATERCLOSETS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	8 (EA)
Last Inspection Date: 16-Jan-2020 Condition Rating: A- Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments: The waterclosets are approaching the end of their service lives and are discolored.			
1999 D201004 SINKS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	15 (EA)
Last Inspection Date: 16-Jan-2020 Condition Rating: A- Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments: The sinks have corrosion on the piping.			
1999 D201004 SINKS Kitchen Sink	D20 PLUMBING	D2010 PLUMBING FIXTURES	4 (EA)
Last Inspection Date: 16-Jan-2020 Condition Rating: A+ Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
1999 D201004 SINKS Service Sink	D20 PLUMBING	D2010 PLUMBING FIXTURES	1 (EA)
Last Inspection Date: 16-Jan-2020 Condition Rating: A+ Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
1999 D201005 SHOWERS/TUBS Shower	D20 PLUMBING	D2010 PLUMBING FIXTURES	1 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1999 D202001 PIPES & FITTINGS General	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	3,973 (LF)
Last Inspection Date: 01-Jan-1999 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1999 D202003 DOMESTIC WATER EQUIPMENT Water Heaters,	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	4 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 D203001 WASTE PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	1,990 (LF)
Last Inspection Date: 01-Jan-1999 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1999 D203002 VENT PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	483 (EA)
Last Inspection Date: 01-Jan-1999 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1999 D203003 FLOOR DRAINS General	D20 PLUMBING	D2030 SANITARY WASTE	2 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 D304001 AIR DISTRIBUTION, HEATING & COOLING	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2,383 (LF)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 01-Jan-1999 Inspector: Inspection Comments: Original Inspection Condition Rating: G+ Used Sampling? No Inspection Source: InstallDate			
1999 D304003 HOT WATER DISTRIBUTION SYSTEMS General	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	320 (MBH)
Last Inspection Date: 01-Jan-1999 Inspector: Inspection Comments: Original Inspection Condition Rating: G+ Used Sampling? No Inspection Source: InstallDate			
1999 D304006 CHILLED WATER DISTRIBUTION SYSTEMS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	32 (TON)
Last Inspection Date: 01-Jan-1999 Inspector: Inspection Comments: Original Inspection Condition Rating: G+ Used Sampling? No Inspection Source: InstallDate			
1999 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	9 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: Condition Rating: A Used Sampling? No Inspection Source: Inspection			
1999 D305003 FAN COIL UNITS Duct Mount, 4 Pipe - 2 ton	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	11 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: Condition Rating: A Used Sampling? No Inspection Source: Inspection			
1999 D305003 FAN COIL UNITS Duct Mount, 4 Pipe - 5 ton	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	7 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: Condition Rating: A Used Sampling? No Inspection Source: Inspection			
1999 D305004 FIN TUBE RADIATION Other	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	8 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: Condition Rating: A+ Used Sampling? No Inspection Source: Inspection			



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
1999 D306002 ELECTRONIC CONTROLS General	D30 HVAC	D3060 CONTROLS & INSTRUMENTATION	18 (EA)
Last Inspection Date: 16-Jan-2020	Condition Rating: A	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1999 D401001 FIRE ALARM DISTRIBUTION Other	D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SYS	12,792 (SF)
Last Inspection Date: 01-Jan-1999	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
Inspector:			
Inspection Comments: Original Inspection			
1999 D404001 SPRINKLERS AND RELEASING DEVICES Wet	D40 FIRE PROTECTION	D4040 SPRINKLERS	12,792 (SF)
Last Inspection Date: 01-Jan-1999	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
Inspector:			
Inspection Comments: Original Inspection			
1999 D501006 MOTOR CONTROL CENTERS Motor Control	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	1 (EA)
Last Inspection Date: 16-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1999 D502001 BRANCH WIRING General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	12,792 (SF)
Last Inspection Date: 01-Jan-1999	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
Inspector:			
Inspection Comments: Original Inspection			
1999 D502002 LIGHTING EQUIPMENT Exit Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	17 (EA)
Last Inspection Date: 16-Jan-2020	Condition Rating: A-	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments: The exit lights are approaching the end of their service lives and have minor corrosion.			
1999 D502002 LIGHTING EQUIPMENT Exterior Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	55 (EA)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments: The exterior lights are discolored and corroded.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1999 D502002 LIGHTING EQUIPMENT General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	12,792 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 D503001 TELECOMMUNICATIONS SYSTEMS General	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1999 D503002 PUBLIC ADDRESS SYSTEMS 12 outlets	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 D503003 INTERCOMMUNICATIONS SYSTEMS 6 stations	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 D503007 CLOCK & PROGRAM SYSTEMS General	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 D509002 EMERGENCY LIGHTING & POWER General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	12,792 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
1999 D509002 EMERGENCY LIGHTING & POWER	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	1 (EA)
Last Inspection Date: 16-Jan-2020	Condition Rating: A+	Used Sampling? No	
Inspector: [REDACTED]		Inspection Source: Inspection	
Inspection Comments:			
1999 D509003 GROUNDING SYSTEMS General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	1 (EA)
Last Inspection Date: 01-Jan-1999	Condition Rating: G+	Used Sampling? No	
Inspector: [REDACTED]		Inspection Source: InstallDate	
Inspection Comments: Original Inspection			
1999 A B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	550 (LF)
Last Inspection Date: 16-Jan-2020	Condition Rating: G-	Used Sampling? No	
Inspector: [REDACTED]		Inspection Source: Inspection	
Inspection Comments:			
1999 A B201011 SUN CONTROL DEVICES General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	390 (SF)
Last Inspection Date: 16-Jan-2020	Condition Rating: G-	Used Sampling? No	
Inspector: [REDACTED]	Paint Rating: G-	Inspection Source: Inspection	
Inspection Comments:			
1999 A B301004 FLASHINGS & TRIM Flashings - Cap	B30 ROOFING	B3010 ROOF COVERINGS	350 (LF)
Last Inspection Date: 16-Jan-2020	Condition Rating: A+	Used Sampling? No	
Inspector: [REDACTED]		Inspection Source: Inspection	
Inspection Comments:			
1999 A B301004 FLASHINGS & TRIM Flashings - Flashing	B30 ROOFING	B3010 ROOF COVERINGS	4 (EA)
Last Inspection Date: 16-Jan-2020	Condition Rating: A+	Used Sampling? No	
Inspector: [REDACTED]		Inspection Source: Inspection	
Inspection Comments:			
1999 B B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	20,000 (LF)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1999 B B201011 SUN CONTROL DEVICES General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	312 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G- Paint Rating: G-	Used Sampling? No Inspection Source: Inspection	
1999 B B301004 FLASHINGS & TRIM Flashings - Cap	B30 ROOFING	B3010 ROOF COVERINGS	516 (LF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 B B301004 FLASHINGS & TRIM Flashings - Flashing	B30 ROOFING	B3010 ROOF COVERINGS	3 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 C B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	75 (LF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1999 ROOM 15 D501002 SERVICE ENTRANCE EQUIPMENT	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 ROOM 15 D501003 INTERIOR DISTRIBUTION	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
1999 ROOM 15 D501004 PANELBOARDS Main lugs, 50 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	3 (EA)
Last Inspection Date: 16-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1999 ROOM 17 D202002 VALVES & HYDRANTS Backflow	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)
Last Inspection Date: 16-Jan-2020	Condition Rating: A	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1999 ROOM 17 D202003 DOMESTIC WATER EQUIPMENT	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)
Last Inspection Date: 16-Jan-2020	Condition Rating: R+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments: The storage tank is beyond its statistical life and the piping is corroded.			
1999 ROOM 17 D202003 DOMESTIC WATER EQUIPMENT	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)
Last Inspection Date: 16-Jan-2020	Condition Rating: R+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments: The water softener is at the end of its statistical life.			
1999 ROOM 17 D302001 BOILERS Gas, Hot Water - 250-400	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 16-Jan-2020	Condition Rating: A-	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments: The boiler has minor corrosion.			
1999 ROOM 17 D302004 AUXILIARY EQUIPMENT Expansion	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 16-Jan-2020	Condition Rating: G-	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1999 ROOM 17 D302004 AUXILIARY EQUIPMENT Expansion	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1 (EA)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1999 ROOM 17 D304001 AIR DISTRIBUTION, HEATING	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1999 ROOM 17 D304003 HOT WATER DISTRIBUTION	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The hot water circulating pumps have minor corrosion.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
1999 ROOM 17 D304006 CHILLED WATER DISTRIBUTION	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments: The chilled water pumps are corroded on the motors and piping.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1999 ROOM 17 D501004 PANELBOARDS Main lugs, 120/240 V,	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIB	2 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1999 ROOM 19 D305006 PACKAGE UNITS A/C Unit, Split	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2020 C201001 INTERIOR AND EXTERIOR STAIRS Exterior	C20 STAIRS	C2010 STAIR CONSTRUCTION	3 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	



NAS1 Support Area

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

Section Description

System

Component

Quantity (UM)

"identification only"



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
2008 B201001 EXTERIOR CLOSURE Stucco	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	32,828 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments: The stucco system at wall areas and especially the wainscot, is generally deteriorated. There is spalled stucco and failed paint coating at numerous locations, with exposed and severely corroded metal corner bead trim.	Condition Rating: A- Paint Rating: R	Used Sampling? No Inspection Source: Inspection	
2008 B201001 EXTERIOR CLOSURE Wall Louver	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	234 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+ Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 B201007 EXTERIOR SOFFITS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1,305 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+ Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 B201011 SUN CONTROL DEVICES General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	8 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+ Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 B202001 WINDOWS Aluminum Windows	B20 EXTERIOR ENCLOSURE	B2020 EXTERIOR WINDOWS	258 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 B202002 STOREFRONTS General	B20 EXTERIOR ENCLOSURE	B2020 EXTERIOR WINDOWS	192 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 B203001 SOLID DOORS Steel	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	3 (EA)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 16-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 B203002 GLAZED DOORS General	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	15 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 B203002 GLAZED DOORS General	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	15 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 B203007 GATES General	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	168 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A+ Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 B203090 OTHER EXTERIOR SPECIALTY DOORS	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	19 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 B301001 STEEP SLOPE ROOF SYSTEMS Clay Tile	B30 ROOFING	B3010 ROOF COVERINGS	45,000 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: Inspection Comments: The clay barrel tile roof system appears to have minor deterioration. However, several active leaks were observed at roof mid spans.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
2008 B301003 ROOF INSULATION & FILL General	B30 ROOFING	B3010 ROOF COVERINGS	45,000 (SF)
Last Inspection Date: 01-Jan-2008 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
2008 B301004 FLASHINGS & TRIM Flashings - Cap	B30 ROOFING	B3010 ROOF COVERINGS	530 (LF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 B301004 FLASHINGS & TRIM Flashings - Flashing	B30 ROOFING	B3010 ROOF COVERINGS	7 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments: The pipe vents and other roof penetrations appear to have deteriorated flashings at the joint with roofing tiles. Several active leaks were observed.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
2008 B301005 GUTTERS & DOWNSPOUTS Downspouts	B30 ROOFING	B3010 ROOF COVERINGS	985 (LF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments: The downspouts are damaged and deteriorated at several drain openings.	Condition Rating: A- Paint Rating: A-	Used Sampling? No Inspection Source: Inspection	
2008 B301005 GUTTERS & DOWNSPOUTS Gutters	B30 ROOFING	B3010 ROOF COVERINGS	800 (LF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments: The gutters mounting brackets and joints appear to be loose.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
2008 B301006 ROOF OPENINGS AND SUPPORTS Hatches	B30 ROOFING	B3010 ROOF COVERINGS	4 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C101001 FIXED PARTITIONS Wall - Drywall w/Stud	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	54,000 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G- Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C101001 FIXED PARTITIONS Wall - Plaster w/Stud	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	39,300 (SF)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G- Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C101005 INTERIOR WINDOWS Interior Windows	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	14 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 C102001 STANDARD INTERIOR DOORS Wood	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	128 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 C102003 FIRE DOORS Fire Door - Swinging, Metal	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	6 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 C102003 FIRE DOORS Fire Door - Swinging, Wood	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	13 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 C103001 COMPARTMENTS, CUBICLES & TOILET	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	30 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 C103001 COMPARTMENTS, CUBICLES & TOILET	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	8 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
2008 C103002 TOILET & BATH ACCESSORIES General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	58 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 C103003 MARKER BOARDS & TACK BOARDS General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	251 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 C103006 SHELIVING General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	13 (LF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 C103008 COUNTERS Laminated Plastic	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	717 (LF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 C103009 CABINETS Other	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	1,532 (LF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C103010 CASEWORK General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	350 (LF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C201001 INTERIOR AND EXTERIOR STAIRS Exterior	C20 STAIRS	C2010 STAIR CONSTRUCTION	1 (EA)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments: The clay tile treads and risers only have minor deterioration. However, the stucco sides have severe deterioration, with spalling stucco, corrosion on exposed metal reinforcing and failed paint finish.	Condition Rating: A-	Used Sampling? No	Inspection Source: Inspection
2008 C201001 INTERIOR AND EXTERIOR STAIRS Interior	C20 STAIRS	C2010 STAIR CONSTRUCTION	4 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
2008 C301004 TILE & TERRAZZO WALL FINISHES General	C30 INTERIOR FINISHES	C3010 WALL FINISHES	17,545 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No	Inspection Source: Inspection
2008 C302001 TILE FLOOR FINISHES Ceramic Tile	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	13,400 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No	Inspection Source: Inspection
2008 C302001 TILE FLOOR FINISHES Marble Tile	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	2,120 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No	Inspection Source: Inspection
2008 C302004 RESILIENT FLOOR FINISHES Composition	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	7,000 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
2008 C302005 CARPETING General	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	25,500 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED]	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
Inspection Comments:			
2008 C303001 ACOUSTICAL CEILING TILES & PANELS	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	37,700 (SF)
Last Inspection Date: 16-Jan-2020	Condition Rating: A+	Used Sampling? No	
Inspector: [REDACTED]		Inspection Source: Inspection	
Inspection Comments:			
2008 C303002 GYPSUM WALLBOARD CEILING FINISHES	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	5,790 (SF)
Last Inspection Date: 16-Jan-2020	Condition Rating: G-	Used Sampling? No	
Inspector: [REDACTED]	Paint Rating: A+	Inspection Source: Inspection	
Inspection Comments:			
2008 C303003 PLASTER CEILING FINISHES General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	2,885 (SF)
Last Inspection Date: 16-Jan-2020	Condition Rating: G-	Used Sampling? No	
Inspector: [REDACTED]	Paint Rating: A+	Inspection Source: Inspection	
Inspection Comments:			
2008 C303005 SUSPENSION SYSTEMS General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	37,700 (SF)
Last Inspection Date: 16-Jan-2020	Condition Rating: A+	Used Sampling? No	
Inspector: [REDACTED]		Inspection Source: Inspection	
Inspection Comments:			
2008 D201001 WATERCLOSETS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	40 (EA)
Last Inspection Date: 16-Jan-2020	Condition Rating: A+	Used Sampling? No	
Inspector: [REDACTED]		Inspection Source: Inspection	
Inspection Comments:			
2008 D201002 URINALS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	10 (EA)
Last Inspection Date: 16-Jan-2020	Condition Rating: G-	Used Sampling? No	
Inspector: [REDACTED]		Inspection Source: Inspection	
Inspection Comments:			
2008 D201004 SINKS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	32 (EA)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 D201004 SINKS Kitchen Sink	D20 PLUMBING	D2010 PLUMBING FIXTURES	30 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 D201004 SINKS Service Sink	D20 PLUMBING	D2010 PLUMBING FIXTURES	4 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 D201005 SHOWERS/TUBS Shower	D20 PLUMBING	D2010 PLUMBING FIXTURES	1 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 D201006 DRINKING FOUNTAINS AND COOLERS Water	D20 PLUMBING	D2010 PLUMBING FIXTURES	8 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 D202001 PIPES & FITTINGS General	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	17,582 (LF)
Last Inspection Date: 01-Jan-2008 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2008 D203001 WASTE PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	8,044 (LF)
Last Inspection Date: 01-Jan-2008 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
2008 D203002 VENT PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	2,138 (EA)
Last Inspection Date: 01-Jan-2008	Condition Rating: G+	Used Sampling? No	Inspector: [REDACTED]
Inspection Source: Original Inspection		InstallDate	
2008 D203003 FLOOR DRAINS General	D20 PLUMBING	D2030 SANITARY WASTE	18 (EA)
Last Inspection Date: 16-Jan-2020	Condition Rating: G-	Used Sampling? No	Inspector: [REDACTED]
Inspection Source: [REDACTED]		InstallDate	
2008 D304001 AIR DISTRIBUTION, HEATING & COOLING	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	10,546 (LF)
Last Inspection Date: 01-Jan-2008	Condition Rating: G+	Used Sampling? No	Inspector: [REDACTED]
Inspection Source: Original Inspection		InstallDate	
2008 D304001 AIR DISTRIBUTION, HEATING & COOLING VAV	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	59 (EA)
Last Inspection Date: 16-Jan-2020	Condition Rating: A-	Used Sampling? No	Inspector: [REDACTED]
Inspection Source: The VAVs in the ceilings were reported to fail throughout the building.		InstallDate	
2008 D304003 HOT WATER DISTRIBUTION SYSTEMS General	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1,415 (MBH)
Last Inspection Date: 01-Jan-2008	Condition Rating: G+	Used Sampling? No	Inspector: [REDACTED]
Inspection Source: Original Inspection		InstallDate	
2008 D304006 CHILLED WATER DISTRIBUTION SYSTEMS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	142 (TON)
Last Inspection Date: 01-Jan-2008	Condition Rating: G+	Used Sampling? No	Inspector: [REDACTED]
Inspection Source: Original Inspection		InstallDate	
2008 D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	4 (EA)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 16-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 D306002 ELECTRONIC CONTROLS General	D30 HVAC	D3060 CONTROLS & INSTRUMENTATION	65 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 D401001 FIRE ALARM DISTRIBUTION Other	D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SY\$	56,606 (SF)
Last Inspection Date: 01-Jan-2008 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2008 D404001 SPRINKLERS AND RELEASING DEVICES Wet	D40 FIRE PROTECTION	D4040 SPRINKLERS	56,606 (SF)
Last Inspection Date: 01-Jan-2008 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2008 D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp,	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	21 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 D501004 PANELBOARDS Switchgear - 800 Amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	2 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 D502001 BRANCH WIRING General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	56,606 (SF)
Last Inspection Date: 01-Jan-2008 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
2008 D502002 LIGHTING EQUIPMENT Exit Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	38 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 D502002 LIGHTING EQUIPMENT Exterior Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	117 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 D502002 LIGHTING EQUIPMENT General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	56,606 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 D503001 TELECOMMUNICATIONS SYSTEMS General	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 D503002 PUBLIC ADDRESS SYSTEMS 12 outlets	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	6 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 D503003 INTERCOMMUNICATIONS SYSTEMS 50 stations	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 D503007 CLOCK & PROGRAM SYSTEMS General	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 D509002 EMERGENCY LIGHTING & POWER General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	56,606 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 D509002 EMERGENCY LIGHTING & POWER	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	4 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 D509003 GROUNDING SYSTEMS General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	1 (EA)
Last Inspection Date: 01-Jan-2008 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2008 D509004 LIGHTNING PROTECTION Unknown	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	56,606 (SF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2008 D509006 ENERGY MANAGEMENT CONTROL SYSTEM	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	56,606 (SF)
Last Inspection Date: 01-Jan-2008 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2008 A B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1,095 (LF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments: The sealant caulk is brittle or missing at several locations.	Condition Rating: R	Used Sampling? No Inspection Source: Inspection	



NAS1 Support Area

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
2008 A B301004 FLASHINGS & TRIM General	B30 ROOFING	B3010 ROOF COVERINGS	1,612 (LF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments: The metal apron and base flashings appear to be deteriorated, with active leaks observed at several areas.	Condition Rating: A-	Used Sampling? No Inspection Source: Inspection	
2008 A C201090 STAIR HANDRAILS, GUARDRAILS AND	C20 STAIRS	C2010 STAIR CONSTRUCTION	65 (LF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 AHU 8 D304008 AIR HANDLING UNITS Central Station -	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 AHU-6 D304008 AIR HANDLING UNITS Central Station -	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 AHU-7 D304008 AIR HANDLING UNITS Central Station -	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 B B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	5,000 (LF)
Last Inspection Date: 16-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 B B301004 FLASHINGS & TRIM General	B30 ROOFING	B3010 ROOF COVERINGS	179 (LF)



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 B C201090 STAIR HANDRAILS, GUARDRAILS AND	C20 STAIRS	C2010 STAIR CONSTRUCTION	256 (LF)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+ Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 C B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	150 (LF)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 HRU 6 D304008 AIR HANDLING UNITS Central Station -	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 HRU 7 D304008 AIR HANDLING UNITS Central Station -	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2008 ROOM 318 D304007 EXHAUST SYSTEMS Fan System,	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
2008 ROOM 318 D501004 PANELBOARDS Main lugs, 400 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	1 (EA)
Last Inspection Date: 16-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



NAS1 Support Area

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

Section Description	System	Component	Quantity (UM)
2008 ROOM 318 D501004 PANELBOARDS Main lugs, 600 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	1 (EA)

Last Inspection Date: 16-Jan-2020

Inspector: [REDACTED]

Inspection Comments:

Condition Rating: A+

Used Sampling?

No

Inspection Source:

Inspection

"identification only"

Appendix H

System Inventory Report

"identification only"



System Inventory Report



NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
B10 SUPERSTRUCTURE	B1020 ROOF CONSTRUCTION	2008 B102003 ROOF DECKS AND SLABS Deck - Steel	12,873 (SF)	2008	
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	2008 B201001 EXTERIOR CLOSURE Stucco	30,536 (SF)	2008	2008
	B2010 EXTERIOR WALLS	2008 B201005 EXTERIOR LOUVERS & SCREENS General	351 (SF)	2008	2008
	B2010 EXTERIOR WALLS	2008 B201007 EXTERIOR SOFFITS General	3,790 (SF)	2008	2008
	B2010 EXTERIOR WALLS	2008 A B201010 EXTERIOR JOINT SEALANT General	600 (LF)	2008	
	B2010 EXTERIOR WALLS	2008 B B201010 EXTERIOR JOINT SEALANT General	1,000 (LF)	2008	
	B2020 EXTERIOR WINDOWS	2008 B202001 WINDOWS Aluminum Windows	62 (EA)	2008	
	B2030 EXTERIOR DOORS	2008 B203001 SOLID DOORS Steel	12 (EA)	2008	
	B2030 EXTERIOR DOORS	2008 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door	18 (EA)	2008	
B30 ROOFING	B3010 ROOF COVERINGS	2008 B301001 STEEP SLOPE ROOF SYSTEMS Clay Tile	12,873 (SF)	2008	
	B3010 ROOF COVERINGS	2008 B301002 ROOF INSULATION & FILL General	12,873 (SF)	2008	
	B3010 ROOF COVERINGS	2008 B301003 FLASHINGS & TRIM Flashings - Apron	800 (LF)	2008	
	B3010 ROOF COVERINGS	2008 B301004 FLASHINGS & TRIM Flashings - Cap	154 (LF)	2008	
	B3010 ROOF COVERINGS	2008 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	3 (EA)	2008	
	B3010 ROOF COVERINGS	2008 B301004 FLASHINGS & TRIM Flashings - Valley	32 (LF)	2008	
	B3010 ROOF COVERINGS	2008 B301004 FLASHINGS & TRIM General	200 (LF)	2008	2008
	B3010 ROOF COVERINGS	2008 B301005 GUTTERS & DOWNSPOUTS Downspouts	511 (LF)	2008	2008
	B3010 ROOF COVERINGS	2008 B301005 GUTTERS & DOWNSPOUTS Gutters	575 (LF)	2008	
	B3010 ROOF COVERINGS	2008 B301006 ROOF OPENINGS AND SUPPORTS Hatches	2 (EA)	2008	
C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	2008 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing	37,941 (SF)	2008	2014
	C1020 INTERIOR DOORS	2008 C102001 STANDARD INTERIOR DOORS Metal Door	6 (EA)	2008	
	C1020 INTERIOR DOORS	2008 C102001 STANDARD INTERIOR DOORS Wood Door/Metal Frame	42 (EA)	2008	
	C1020 INTERIOR DOORS	2008 C102003 FIRE DOORS Fire Door - Swinging	15 (EA)	2008	
	C1030 SPECIALTIES	2008 C103002 TOILET & BATH ACCESSORIES General	18 (EA)	2008	
	C1030 SPECIALTIES	2008 C103003 MARKER BOARDS & TACK BOARDS General	12 (EA)	2008	
	C1030 SPECIALTIES	2008 C103005 LOCKERS General	91 (EA)	2008	
	C1030 SPECIALTIES	2008 C103008 COUNTERS Laminated Plastic	55 (LF)	2008	
	C1030 SPECIALTIES	2008 C103008 COUNTERS Wood	21 (LF)	2008	
	C1030 SPECIALTIES	2008 C103009 CABINETS Other	146 (LF)	2008	
C20 STAIRS	C2010 STAIR CONSTRUCTION	2008 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Concrete (12 Riser Flight)	3 (EA)	2008	
	C2010 STAIR CONSTRUCTION	2008 C201001 INTERIOR AND EXTERIOR STAIRS Interior Stairs	2 (EA)	2008	



System Inventory Report



NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	C2010 STAIR CONSTRUCTION	2008 A C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General	367 (LF)	2008	
	C2010 STAIR CONSTRUCTION	2008 B C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General	149 (LF)	2008	2008
C30 INTERIOR FINISHES	C3010 WALL FINISHES	2008 C301004 TILE & TERRAZZO WALL FINISHES Tile	4,469 (SF)	2008	
	C3020 FLOOR FINISHES	2008 C302001 TILE FLOOR FINISHES Ceramic Tile	5,404 (SF)	2008	
	C3020 FLOOR FINISHES	2008 C302004 RESILIENT FLOOR FINISHES Composition Sheet	10,973 (SF)	2008	
	C3020 FLOOR FINISHES	2008 C302005 CARPETING General	1,662 (SF)	2008	
	C3030 CEILING FINISHES	2008 C303001 ACOUSTICAL CEILING TILES & PANELS General	11,640 (SF)	2008	
	C3030 CEILING FINISHES	2008 C303002 GYPSUM WALLBOARD CEILING FINISHES General	3,159 (SF)	2008	2008
	C3030 CEILING FINISHES	2008 C303003 PLASTER CEILING FINISHES General	3,086 (SF)	2008	2008
	C3030 CEILING FINISHES	2008 C303004 SUSPENSION SYSTEMS General	11,640 (SF)	2008	
D10 CONVEYING	D1010 ELEVATORS AND LIFTS	2008 ROOM 151E D101004 WHEELCHAIR LIFT Inclined, stair lift	1 (EA)	2008	
	D1010 ELEVATORS AND LIFTS	2008 ROOM E102.1 D101002 PASSENGER ELEVATORS Hydraulic Elevators - 1500 lb, 5 floors	1 (EA)	2008	
	D1010 ELEVATORS AND LIFTS	2008 RROM E102.1 D101002 PASSENGER ELEVATORS Hydraulic Elevators - 1500 lb, 5 floors	1 (EA)	2008	
D20 PLUMBING	D2010 PLUMBING FIXTURES	2008 D201001 WATERCLOSURES General	6 (EA)	2008	
	D2010 PLUMBING FIXTURES	2008 D201004 SINKS General	6 (EA)	2008	
	D2010 PLUMBING FIXTURES	2008 D201004 SINKS Kitchen Sink	1 (EA)	2008	
	D2010 PLUMBING FIXTURES	2008 D201004 SINKS Service Sink	1 (EA)	2008	
	D2010 PLUMBING FIXTURES	2008 D201006 DRINKING FOUNTAINS AND COOLERS Water Cooler	6 (EA)	2015	
	D2020 DOMESTIC WATER DISTRIBUTION	2008 D202001 PIPES & FITTINGS General	8,398 (LF)	2008	
	D2020 DOMESTIC WATER DISTRIBUTION	2008 D202002 VALVES & HYDRANTS Backflow Preventer - 6" pipe	1 (EA)	2017	
	D2020 DOMESTIC WATER DISTRIBUTION	2008 ROOM 59 D202003 DOMESTIC WATER EQUIPMENT Booster Pump - 3 HP	1 (EA)	2008	
	D2020 DOMESTIC WATER DISTRIBUTION	2008 ROOM 59 D202003 DOMESTIC WATER EQUIPMENT Booster Pump - 5 HP	1 (EA)	2008	
	D2020 DOMESTIC WATER DISTRIBUTION	2008 ROOM 59 D202003 DOMESTIC WATER EQUIPMENT Storage Tank - Galvanized steel, 30 gallon, 14" diameter, 49" L.O.A.	1 (EA)	2008	
	D2020 DOMESTIC WATER DISTRIBUTION	2008 ROOM 59 D202003 DOMESTIC WATER EQUIPMENT Water Heaters, Commercial, Gas - 240 MBH input, 230 GPH	2 (EA)	2016	
	D2030 SANITARY WASTE	2008 D203001 WASTE PIPE & FITTINGS General	4,199 (LF)	2008	
	D2030 SANITARY WASTE	2008 D203002 VENT PIPE & FITTINGS General	1,021 (EA)	2008	



System Inventory Report



NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D2030 SANITARY WASTE	2008 D203003 FLOOR DRAINS General	8 (EA)	2008	
D30 HVAC	D3020 HEAT GENERATING SYSTEMS	2008 D302004 AUXILIARY EQUIPMENT Expansion Tank - 24 gal	3 (EA)	2017	
	D3020 HEAT GENERATING SYSTEMS	2008 ROOM 56 D302004 AUXILIARY EQUIPMENT Expansion Tank - 100 gal	1 (EA)	2008	
	D3020 HEAT GENERATING SYSTEMS	2008 ROOM 56 D302004 AUXILIARY EQUIPMENT Expansion Tank - 60 gal	2 (EA)	2016	
	D3020 HEAT GENERATING SYSTEMS	2008 ROOM 59 D302004 AUXILIARY EQUIPMENT Expansion Tank - 60 gal	2 (EA)	2017	
	D3030 COOLING GENERATING SYSTEMS	2008 CHILLER 1 D303001 CHILLED WATER SYSTEMS Chiller, Rotary Screw - 210 TN, Air Cooled Screw Liquid Chiller	1 (EA)	2008	
	D3030 COOLING GENERATING SYSTEMS	2008 CHILLER 2 D303001 CHILLED WATER SYSTEMS Chiller, Rotary Screw - 210 TN, Air Cooled Screw Liquid Chiller	1 (EA)	2008	
	D3030 COOLING GENERATING SYSTEMS	2008 CHILLER 3 D303001 CHILLED WATER SYSTEMS Chiller, Rotary Screw - 210 TN, Air Cooled Screw Liquid Chiller	1 (EA)	2008	
	D3030 COOLING GENERATING SYSTEMS	2008 CHILLER 4 D303001 CHILLED WATER SYSTEMS Chiller, Rotary Screw - 210 TN, Air Cooled Screw Liquid Chiller	1 (EA)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	5,362 (LF)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 D304001 AIR DISTRIBUTION, HEATING & COOLING VAV Terminal	15 (EA)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 D304003 HOT WATER DISTRIBUTION SYSTEMS General	720 (MBH)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	72 (TON)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 500 CFM	2 (EA)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 ROOM 253 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 1500 CFM	2 (EA)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 ROOM 350 D304008 AIR HANDLING UNITS Central Station - 10000 CFM	1 (EA)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 ROOM 350 D304008 AIR HANDLING UNITS Central Station - 15000 CFM, VAV	1 (EA)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 ROOM 56 D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating Pump, End Suction - 4" size, 7-1/2 HP, to 350 GPM	2 (EA)	2015	
	D3040 DISTRIBUTION SYSTEMS	2008 ROOM 56 D304006 CHILLED WATER DISTRIBUTION SYSTEMS Circulating Pump, End Suction - 4" size, 7-1/2 HP, to 350 GPM	4 (EA)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 ROOM 56 D304006 CHILLED WATER DISTRIBUTION SYSTEMS Circulating Pump, End Suction - 6" size, 25 HP, to 1550 GPM	3 (EA)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 ROOM 57 D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating Pump, End Suction - 4" size, 7-1/2 HP, to 350 GPM	2 (EA)	2008	



System Inventory Report



NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D3040 DISTRIBUTION SYSTEMS	2008 ROOM 57 D304008 AIR HANDLING UNITS Central Station - 10000 CFM, VAV	1 (EA)	2008	
	D3050 TERMINAL & PACKAGE UNITS	2008 D305001 UNIT VENTILATORS Fan System, Centrifugal In-Line - 500 CFM	1 (EA)	2008	
	D3050 TERMINAL & PACKAGE UNITS	2008 ROOM 252 D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air Cooled Condenser - 2 TN	1 (EA)	2016	
	D3050 TERMINAL & PACKAGE UNITS	2008 ROOM 56 D305002 UNIT HEATERS Hydronic - 20 MBH	3 (EA)	2008	
	D3060 CONTROLS & INSTRUMENTATION	2008 D306002 ELECTRONIC CONTROLS General	30 (EA)	2008	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SYSTEMS	2008 D401001 FIRE ALARM DISTRIBUTION Other	28,780 (SF)	2008	
	D4020 FIRE SUPP WATER SUPPLY / EQUIP	2008 D402001 FIRE PROTECTION WATER PIPING AND EQUIPMENT Backflow Preventer - 8"	1 (EA)	2008	
	D4040 SPRINKLERS	2008 D404001 SPRINKLERS AND RELEASING DEVICES Wet Pipe Systems	28,780 (SF)	2008	
D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 D501004 PANELBOARDS Main lugs, 50 amp	4 (EA)	2008	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp, NQOD	16 (EA)	2008	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 D501004 PANELBOARDS Main lugs, 120/240 V, 225 amp, NQOD	3 (EA)	2008	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 D501004 PANELBOARDS Main lugs, 125 amp	2 (EA)	2008	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 D501004 PANELBOARDS Safety Switch, 30-100 Amp	12 (EA)	2008	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 D501006 MOTOR CONTROL CENTERS Motor Control Center - Size 3, 50 HP, 24" high	2 (EA)	2008	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 ROOM 59 D501002 SERVICE ENTRANCE EQUIPMENT Electrical Service - 3 Phase, 120/208 V, 2000 A	3 (EA)	2008	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 ROOM 59 D501004 PANELBOARDS Main lugs, 400 amp	1 (EA)	2008	
	D5020 LIGHTING & BRANCH WIRING	2008 D502001 BRANCH WIRING General	28,780 (SF)	2008	
	D5020 LIGHTING & BRANCH WIRING	2008 D502002 LIGHTING EQUIPMENT Exit Lighting	22 (EA)	2008	
	D5020 LIGHTING & BRANCH WIRING	2008 D502002 LIGHTING EQUIPMENT Exterior Lighting	42 (EA)	2008	
	D5020 LIGHTING & BRANCH WIRING	2008 D502002 LIGHTING EQUIPMENT General	28,780 (SF)	2008	
	D5030 COMMUNICATIONS & SECURITY	2008 D503001 TELECOMMUNICATIONS SYSTEMS General	1 (EA)	2008	
	D5030 COMMUNICATIONS & SECURITY	2008 D503002 PUBLIC ADDRESS SYSTEMS 30 outlets	1 (EA)	2008	



System Inventory Report



NAS1 Support Area

211 - Sigonella MS/HS Bldg 211

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D5030 COMMUNICATIONS & SECURITY	2008 D503003 INTERCOMMUNICATIONS SYSTEMS 12 stations	3 (EA)	2008	
	D5030 COMMUNICATIONS & SECURITY	2008 D503005 SECURITY SYSTEMS General	1 (EA)	2014	
	D5090 OTHER ELECTRICAL SERVICES	2008 D509002 EMERGENCY LIGHTING & POWER General	28,780 (SF)	2008	
	D5090 OTHER ELECTRICAL SERVICES	2008 D509002 EMERGENCY LIGHTING & POWER Uninterruptible Power Supply - 1.0 kVA	2 (EA)	2008	
	D5090 OTHER ELECTRICAL SERVICES	2008 D509003 GROUNDING SYSTEMS General	1 (EA)	2008	
	D5090 OTHER ELECTRICAL SERVICES	2008 D509006 ENERGY MANAGEMENT CONTROL SYSTEM General	28,780 (SF)	2008	
E10 EQUIPMENT	E1090 OTHER EQUIPMENT	*COLD PAK SINGLE BASIN E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2008	
	E1090 OTHER EQUIPMENT	*DISH MACHINE E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2008	
	E1090 OTHER EQUIPMENT	*HOT CABINET REACH IN 2 DR A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2008	
	E1090 OTHER EQUIPMENT	*HOT CABINET REACH IN 2 DR B E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2008	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2 DR A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2008	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2 DR B E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2008	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTIBASIN E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2008	



System Inventory Report



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1999 B201005 EXTERIOR LOUVERS & SCREENS General	102 (SF)	1999	1999
	B2010 EXTERIOR WALLS	1999 B201006 BALCONY WALLS & HANDRAILS Handrailing	161 (LF)	1999	1999
	B2010 EXTERIOR WALLS	1999 B201007 EXTERIOR SOFFITS General	2,127 (SF)	1999	1999
	B2010 EXTERIOR WALLS	1999 A B201001 EXTERIOR CLOSURE Brick Veneer w/CMU Backup	6,820 (SF)	1999	
	B2010 EXTERIOR WALLS	1999 A B201001 EXTERIOR CLOSURE Stucco	5,113 (SF)	1999	1999
	B2010 EXTERIOR WALLS	1999 A B201010 EXTERIOR JOINT SEALANT General	488 (LF)	1999	
	B2010 EXTERIOR WALLS	1999 B B201001 EXTERIOR CLOSURE Brick Veneer w/CMU Backup	19,462 (SF)	1999	
	B2010 EXTERIOR WALLS	1999 B B201001 EXTERIOR CLOSURE Stucco	390 (SF)	1999	1999
	B2010 EXTERIOR WALLS	1999 B B201010 EXTERIOR JOINT SEALANT General	2,000 (LF)	1999	
	B2020 EXTERIOR WINDOWS	1999 B202001 WINDOWS Aluminum Windows	100 (EA)	1999	
	B2020 EXTERIOR WINDOWS	1999 B202002 STOREFRONTS General	1,495 (SF)	1999	
	B2030 EXTERIOR DOORS	1999 B203001 SOLID DOORS Steel	12 (EA)	1999	
	B2030 EXTERIOR DOORS	1999 B203000 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door	23 (EA)	1999	
B30 ROOFING	B3010 ROOF COVERINGS	1999 B301001 STEEP SLOPE ROOF SYSTEMS Clay Tile	12,475 (SF)	1999	
	B3010 ROOF COVERINGS	1999 B301003 ROOF INSULATION & FILL General	12,475 (SF)	1999	
	B3010 ROOF COVERINGS	1999 B301004 FLASHINGS & TRIM Flashings - Apron	658 (LF)	1999	
	B3010 ROOF COVERINGS	1999 B301004 FLASHINGS & TRIM Flashings - Cap	402 (LF)	1999	
	B3010 ROOF COVERINGS	1999 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	8 (EA)	1999	
	B3010 ROOF COVERINGS	1999 B301004 FLASHINGS & TRIM Flashings - Valley	85 (LF)	1999	
	B3010 ROOF COVERINGS	1999 B301004 FLASHINGS & TRIM General	517 (LF)	1999	
	B3010 ROOF COVERINGS	1999 B301005 GUTTERS & DOWNSPOUTS Downspouts	989 (LF)	1999	1999
	B3010 ROOF COVERINGS	1999 B301005 GUTTERS & DOWNSPOUTS Gutters	666 (LF)	1999	
C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	1999 C101001 FIXED PARTITIONS Wall - Plaster w/ Stud Framing	59,168 (SF)	1999	2014
	C1010 PARTITIONS	1999 C101005 INTERIOR WINDOWS Metal Rollup / Coiling Grille	16 (SF)	1999	
	C1020 INTERIOR DOORS	1999 C102001 STANDARD INTERIOR DOORS Wood Door/Metal Frame	46 (EA)	1999	
	C1020 INTERIOR DOORS	1999 C102003 FIRE DOORS Fire Door - Swinging, Metal	13 (EA)	1999	
	C1020 INTERIOR DOORS	1999 C102003 FIRE DOORS Fire Door - Swinging, Wood	28 (EA)	1999	
	C1020 INTERIOR DOORS	1999 C102006 INTERIOR GATES General	2 (EA)	1999	
	C1020 INTERIOR DOORS	1999 C102090 OTHER INTERIOR SPECIALTY DOORS Cold Storage	3 (EA)	1999	
	C1030 SPECIALTIES	1999 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions - Stone	26 (EA)	1999	



System Inventory Report



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	C1030 SPECIALTIES	1999 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Urinal Screen	6 (EA)	1999	
	C1030 SPECIALTIES	1999 C103002 TOILET & BATH ACCESSORIES General	81 (EA)	1999	
	C1030 SPECIALTIES	1999 C103003 MARKER BOARDS & TACK BOARDS General	133 (EA)	1999	
	C1030 SPECIALTIES	1999 C103005 LOCKERS General	264 (EA)	1999	
	C1030 SPECIALTIES	1999 C103008 COUNTERS Laminated Plastic	948 (LF)	1999	
	C1030 SPECIALTIES	1999 C103009 CABINETS Other	1,536 (LF)	1999	
	C1030 SPECIALTIES	1999 C103010 CASEWORK General	1,284 (LF)	1999	
C20 STAIRS	C2010 STAIR CONSTRUCTION	1999 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Concrete (12 Riser Flight)	1 (EA)	1999	
	C2010 STAIR CONSTRUCTION	1999 C201001 INTERIOR AND EXTERIOR STAIRS Interior Stairs	3 (EA)	1999	
	C2010 STAIR CONSTRUCTION	1999 A C201000 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General	790 (LF)	1999	1999
	C2010 STAIR CONSTRUCTION	1999 B C201000 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General	60 (LF)	1999	1999
C30 INTERIOR FINISHES	C3010 WALL FINISHES	1999 C301004 TILE & TERRAZZO WALL FINISHES Tile	22,757 (SF)	1999	
	C3020 FLOOR FINISHES	1999 C302001 TILE FLOOR FINISHES Ceramic Tile	24,000 (SF)	1999	
	C3020 FLOOR FINISHES	1999 C302004 RESILIENT FLOOR FINISHES Composition Sheet	782 (SF)	1999	
	C3020 FLOOR FINISHES	1999 C302005 CARPETING General	14,900 (SF)	2010	
	C3030 CEILING FINISHES	1999 C303001 ACOUSTICAL CEILING TILES & PANELS General	31,900 (SF)	1999	
	C3030 CEILING FINISHES	1999 C303002 GYPSUM WALLBOARD CEILING FINISHES General	4,700 (SF)	1999	2014
	C3030 CEILING FINISHES	1999 C303003 PLASTER CEILING FINISHES General	15,437 (SF)	1999	2014
	C3030 CEILING FINISHES	1999 C303005 SUSPENSION SYSTEMS General	31,900 (SF)	1999	
D10 CONVEYING	D1010 ELEVATORS AND LIFTS	1999 ROOM 63 D101002 PASSENGER ELEVATORS Hydraulic Elevators - 1500 lb, 5 floors	1 (EA)	1999	
D20 PLUMBING	D2010 PLUMBING FIXTURES	1999 D201001 WATERCLOSETS General	30 (EA)	1999	
	D2010 PLUMBING FIXTURES	1999 D201002 URINALS General	10 (EA)	1999	
	D2010 PLUMBING FIXTURES	1999 D201004 SINKS General	29 (EA)	1999	
	D2010 PLUMBING FIXTURES	1999 D201004 SINKS Kitchen Sink	5 (EA)	1999	
	D2010 PLUMBING FIXTURES	1999 D201004 SINKS Service Sink	5 (EA)	1999	
	D2010 PLUMBING FIXTURES	1999 D201004 SINKS Stainless	6 (EA)	1999	
	D2010 PLUMBING FIXTURES	1999 D201006 DRINKING FOUNTAINS AND COOLERS Water Cooler	8 (EA)	1999	
	D2010 PLUMBING FIXTURES	1999 D201090 OTHER PLUMBING FIXTURES Stainless Steel Combo Unit (WC/Sink)	21 (EA)	1999	



System Inventory Report



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D2020 DOMESTIC WATER DISTRIBUTION	1999 D202001 PIPES & FITTINGS General	19,447 (LF)	1999	
	D2020 DOMESTIC WATER DISTRIBUTION	1999 D202002 VALVES & HYDRANTS Backflow Preventer - 4" pipe	1 (EA)	1999	
	D2020 DOMESTIC WATER DISTRIBUTION	1999 D202003 DOMESTIC WATER EQUIPMENT Water Treatment Equipment	1 (EA)	2019	
	D2020 DOMESTIC WATER DISTRIBUTION	1999 ROOM 10 D202003 DOMESTIC WATER EQUIPMENT Booster Pump - 2 HP	1 (EA)	2010	
	D2020 DOMESTIC WATER DISTRIBUTION	1999 ROOM 10 D202003 DOMESTIC WATER EQUIPMENT Storage Tank - Glass lined, PE, 940 gallon, 60" diameter, 93" L.O.A.	1 (EA)	2010	
	D2020 DOMESTIC WATER DISTRIBUTION	1999 ROOM 10 D202003 DOMESTIC WATER EQUIPMENT Water Screen	1 (EA)	1999	
	D2030 SANITARY WASTE	1999 D203001 WASTE PIPE & FITTINGS General	9,725 (LF)	1999	
	D2030 SANITARY WASTE	1999 D203002 VENT PIPE & FITTINGS General	2,365 (EA)	1999	
	D2030 SANITARY WASTE	1999 A D203003 FLOOR DRAINS General	12 (EA)	1999	
	D2030 SANITARY WASTE	1999 B D203003 FLOOR DRAINS General	5 (EA)	1999	
D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1991 B-1 D302001 BOILERS Oil, HW - 700-1300 MBH	1 (EA)	1999	
	D3020 HEAT GENERATING SYSTEMS	1999 D302004 AUXILIARY EQUIPMENT Chemical Feedwater - 150 lb., 5 gallon, ASME	2 (EA)	1999	
	D3020 HEAT GENERATING SYSTEMS	1999 B-2 D302001 BOILERS Oil, HW - 700-1300 MBH	1 (EA)	1999	
	D3020 HEAT GENERATING SYSTEMS	1999 B-3 D302001 BOILERS Oil, HW - 700-1300 MBH	1 (EA)	1999	
	D3020 HEAT GENERATING SYSTEMS	1999 ROOM 10 D302004 AUXILIARY EQUIPMENT Expansion Tank - 15 gal	1 (EA)	2011	
	D3020 HEAT GENERATING SYSTEMS	1999 ROOM 10 D302004 AUXILIARY EQUIPMENT Expansion Tank - 60 gal	1 (EA)	1999	
	D3020 HEAT GENERATING SYSTEMS	1999 ROOM 22 D302004 AUXILIARY EQUIPMENT Expansion Tank - 30 gal	1 (EA)	1999	
	D3030 COOLING GENERATING SYSTEMS	1999 OUTSIDE D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 40 TN	1 (EA)	1999	
	D3030 COOLING GENERATING SYSTEMS	1999 OUTSIDE D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 60 TN	1 (EA)	1999	
	D3040 DISTRIBUTION SYSTEMS	1999 D304001 AIR DISTRIBUTION, HEATING & COOLING Air Separator - Air control, air separator, 4" diameter, includes strainer	2 (EA)	1999	
	D3040 DISTRIBUTION SYSTEMS	1999 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	11,665 (LF)	1999	
	D3040 DISTRIBUTION SYSTEMS	1999 D304003 HOT WATER DISTRIBUTION SYSTEMS General	1,565 (MBH)	1999	
	D3040 DISTRIBUTION SYSTEMS	1999 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	157 (TON)	1999	
	D3040 DISTRIBUTION SYSTEMS	1999 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 1500 CFM	2 (EA)	1999	



System Inventory Report



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D3040 DISTRIBUTION SYSTEMS	1999 ATTIC D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 1500 CFM	2 (EA)	1999	
	D3040 DISTRIBUTION SYSTEMS	1999 ATTIC D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 3500 CFM	3 (EA)	1999	
	D3040 DISTRIBUTION SYSTEMS	1999 ATTIC D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 800 CFM	1 (EA)	1999	
	D3040 DISTRIBUTION SYSTEMS	1999 ATTIC D304008 AIR HANDLING UNITS Central Station - 2000 CFM	1 (EA)	2006	
	D3040 DISTRIBUTION SYSTEMS	1999 ATTIC AHU-5 D304008 AIR HANDLING UNITS Central Station - 2000 CFM	1 (EA)	1999	
	D3040 DISTRIBUTION SYSTEMS	1999 ATTIC MAU-6 D304008 AIR HANDLING UNITS Central Station - 1700 CFM	1 (EA)	1999	
	D3040 DISTRIBUTION SYSTEMS	1999 EF 3A2 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 500 CFM	1 (EA)	1999	
	D3040 DISTRIBUTION SYSTEMS	1999 OUTSIDE KITCHEN D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 500 CFM	2 (EA)	1999	
	D3040 DISTRIBUTION SYSTEMS	1999 ROOM 10 D304001 AIR DISTRIBUTION, HEATING & COOLING Air Separator - Air control, air separator, 3" diameter, includes strainer	1 (EA)	1999	
	D3040 DISTRIBUTION SYSTEMS	1999 ROOM 10 D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating Pump, Double Suction - 10" size, 150 HP, to 4000 GPM	1 (EA)	2010	
	D3040 DISTRIBUTION SYSTEMS	1999 ROOM 165A D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 500 CFM	1 (EA)	1999	
	D3040 DISTRIBUTION SYSTEMS	1999 ROOM 22 D304008 AIR HANDLING UNITS Central Station - 2000 CFM	1 (EA)	1999	
	D3040 DISTRIBUTION SYSTEMS	1999 ROOM G61 AHU 2 D304008 AIR HANDLING UNITS Central Station - 5000 CFM	1 (EA)	1999	
	D3040 DISTRIBUTION SYSTEMS	1999 ROOM G61 AHU 3 D304008 AIR HANDLING UNITS Central Station - 5000 CFM	1 (EA)	1999	
	D3040 DISTRIBUTION SYSTEMS	1999 ROOM G61 AHU 4 D304008 AIR HANDLING UNITS Central Station - 2000 CFM	1 (EA)	1999	
	D3040 DISTRIBUTION SYSTEMS	1999 ROOM M22 D304006 CHILLED WATER DISTRIBUTION SYSTEMS Circulating Pump, End Suction - 4" size, 7-1/2 HP, to 350 GPM	1 (EA)	2018	
	D3050 TERMINAL & PACKAGE UNITS	1999 D305001 UNIT VENTILATORS Air Curtain	10 (LF)	1999	
	D3050 TERMINAL & PACKAGE UNITS	1999 D305001 UNIT VENTILATORS Fan System, Centrifugal In-Line - 500 CFM	1 (EA)	1999	
	D3050 TERMINAL & PACKAGE UNITS	1999 D305002 UNIT HEATERS Hydronic - 20 MBH	2 (EA)	1999	
	D3050 TERMINAL & PACKAGE UNITS	1999 D305003 FAN COIL UNITS Cab Mount, Four Pipe - 3 ton	24 (EA)	1999	
	D3050 TERMINAL & PACKAGE UNITS	1999 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton	15 (EA)	1999	
	D3050 TERMINAL & PACKAGE UNITS	1999 D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air Cooled Condenser - 3 TN	3 (EA)	2016	



System Inventory Report



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D3050 TERMINAL & PACKAGE UNITS	1999 OUTSIDE ROOM 10 D305006 PACKAGE UNITS Heat Pump, Air Source, Roof Top - 10 ton	1 (EA)	2016	
	D3060 CONTROLS & INSTRUMENTATION	1999 D306002 ELECTRONIC CONTROLS General	58 (EA)	1999	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SYSTEMS	1999 D401001 FIRE ALARM DISTRIBUTION Other	62,613 (SF)	1999	
	D4020 FIRE SUPP WATER SUPPLY / EQUIP	1999 ROOM G61A D402002 FIRE PUMP 5" pump, 40 HP, 1000 GPM	1 (EA)	1999	
	D4040 SPRINKLERS	1999 D404001 SPRINKLERS AND RELEASING DEVICES Wet Pipe systems	62,613 (SF)	1999	
	D4090 OTHER FIRE PROTECTION SYSTEMS	1999 D409004 HOOD & DUCT FIRE PROTECTION General	2 (EA)	1999	
D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 D501002 SERVICE ENTRANCE EQUIPMENT Electrical Service - 3 Phase, 120/208 V, 800 A	2 (EA)	1999	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 D501003 INTERIOR DISTRIBUTION TRANSFORMERS dry-type, 240/480 V primary, 120/240 V secondary, 15 kVA	4 (EA)	1999	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 D501004 PANELBOARDS Main lugs, 50 amp	2 (EA)	1999	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp, NQOD	21 (EA)	1999	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 D501004 PANELBOARDS Main lugs, 200 amp	3 (EA)	1999	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 A D501004 PANELBOARDS Main lugs, 125 amp	9 (EA)	1999	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 PANEL KA D501004 PANELBOARDS Main lugs, 120/240 V, 225 amp, NQOD	1 (EA)	1999	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 ROOM 009 D501002 SERVICE ENTRANCE EQUIPMENT Electrical Service - 3 Phase, 120/208 V, 1200 A	3 (EA)	1999	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 ROOM 12A D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp, NQOD	1 (EA)	2006	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 ROOM 13 D501004 PANELBOARDS Main lugs, 125 amp	1 (EA)	2016	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 ROOM 21A D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp, NQOD	2 (EA)	2016	
	D5020 LIGHTING & BRANCH WIRING	1999 D502001 BRANCH WIRING General	62,613 (SF)	1999	
	D5020 LIGHTING & BRANCH WIRING	1999 D502002 LIGHTING EQUIPMENT Exit Lighting	25 (EA)	1999	
	D5020 LIGHTING & BRANCH WIRING	1999 D502002 LIGHTING EQUIPMENT Exterior Lighting	3 (EA)	1999	
	D5020 LIGHTING & BRANCH WIRING	1999 D502002 LIGHTING EQUIPMENT General	62,613 (SF)	1999	
	D5030 COMMUNICATIONS & SECURITY	1999 D503001 TELECOMMUNICATIONS SYSTEMS General	1 (EA)	1999	



System Inventory Report



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216

Sigonella MS/HS (HE5515)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D5030 COMMUNICATIONS & SECURITY	1999 D503002 PUBLIC ADDRESS SYSTEMS 30 outlets	1 (EA)	1999	
	D5030 COMMUNICATIONS & SECURITY	1999 D503003 INTERCOMMUNICATIONS SYSTEMS 25 stations	1 (EA)	1999	
	D5090 OTHER ELECTRICAL SERVICES	1999 D509002 EMERGENCY LIGHTING & POWER General	62,613 (SF)	1999	
	D5090 OTHER ELECTRICAL SERVICES	1999 D509002 EMERGENCY LIGHTING & POWER Uninterruptible Power Supply - 0.5 kVA	3 (EA)	1999	
	D5090 OTHER ELECTRICAL SERVICES	1999 D509003 GROUNDING SYSTEMS General	1 (EA)	1999	
	D5090 OTHER ELECTRICAL SERVICES	1999 D509006 ENERGY MANAGEMENT CONTROL SYSTEM General	62,613 (SF)	1999	
E10 EQUIPMENT	E1090 OTHER EQUIPMENT	*COLE PAK SINGLE BASIN E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1999	
	E1090 OTHER EQUIPMENT	*DISH MACHINE E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1999	
	E1090 OTHER EQUIPMENT	*GRIDDLE A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1999	
	E1090 OTHER EQUIPMENT	*GRIDDLE B E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1999	
	E1090 OTHER EQUIPMENT	*HOT CABINET REACH IN 2 DR E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1999	
	E1090 OTHER EQUIPMENT	*HOT CABINET REACH IN 4 DR E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1999	
	E1090 OTHER EQUIPMENT	*ICE MACHINE E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1999	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 8 DR E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1999	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1999	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN B E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1999	
	E1090 OTHER EQUIPMENT	*STEAMER 1 DOOR A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1999	
	E1090 OTHER EQUIPMENT	*STEAMER 1 DOOR B E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1999	
	E1090 OTHER EQUIPMENT	*STEAMER 1 DOOR C E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1999	
	E1090 OTHER EQUIPMENT	*STEAMER 1 DOOR D E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1999	
	E1090 OTHER EQUIPMENT	*WALK IN COOLER A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1999	
	E1090 OTHER EQUIPMENT	*WALK IN COOLER B E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1999	



NAS1 Support Area

216 - Sigonella MS/HS Bldg 216	Sigonella MS/HS (HE5515)
--------------------------------	--------------------------

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	E1090 OTHER EQUIPMENT	*WALK IN FREEZER E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	1999	

"identification only"



System Inventory Report



NAS1 Support Area

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	2008 B201001 EXTERIOR CLOSURE Stucco	31,466 (SF)	2008	2008
	B2010 EXTERIOR WALLS	2008 B201001 EXTERIOR CLOSURE Wall Louver	159 (SF)	2008	2008
	B2010 EXTERIOR WALLS	2008 B201007 EXTERIOR SOFFITS General	3,898 (SF)	2008	2008
	B2010 EXTERIOR WALLS	2008 A B201010 EXTERIOR JOINT SEALANT General	826 (LF)	2008	
	B2010 EXTERIOR WALLS	2008 B B201010 EXTERIOR JOINT SEALANT General	5,000 (LF)	2008	
	B2010 EXTERIOR WALLS	2008 C B201010 EXTERIOR JOINT SEALANT General	366 (LF)	2008	
	B2020 EXTERIOR WINDOWS	2008 B202001 WINDOWS Aluminum Windows	347 (EA)	2008	
	B2030 EXTERIOR DOORS	2008 B203001 SOLID DOORS Steel	10 (EA)	2008	
	B2030 EXTERIOR DOORS	2008 B203007 GATES General	144 (SF)	2008	
	B2030 EXTERIOR DOORS	2008 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door	16 (EA)	2008	
B30 ROOFING	B3010 ROOF COVERINGS	2008 B301001 STEEP SLOPE ROOF SYSTEMS Clay Tile	14,237 (SF)	2008	
	B3010 ROOF COVERINGS	2008 B301003 ROOF INSULATION & FILL General	14,237 (SF)	2008	
	B3010 ROOF COVERINGS	2008 B301004 FLASHINGS & TRIM Flashings - Apron	603 (LF)	2008	
	B3010 ROOF COVERINGS	2008 B301004 FLASHINGS & TRIM Flashings - Base	125 (LF)	2008	
	B3010 ROOF COVERINGS	2008 B301004 FLASHINGS & TRIM Flashings - Cap	466 (LF)	2008	
	B3010 ROOF COVERINGS	2008 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	7 (EA)	2008	
	B3010 ROOF COVERINGS	2008 B301004 FLASHINGS & TRIM Flashings - Valley	102 (LF)	2008	
	B3010 ROOF COVERINGS	2008 B301005 GUTTERS & DOWNSPOUTS Downspouts	529 (LF)	2008	2008
	B3010 ROOF COVERINGS	2008 B301005 GUTTERS & DOWNSPOUTS Gutters	448 (LF)	2008	
	B3010 ROOF COVERINGS	2008 B301006 ROOF OPENINGS AND SUPPORTS Hatches	2 (EA)	2008	
	B3010 ROOF COVERINGS	2008 B301090 OTHER ROOFING Wall/Way Protection	6,600 (SF)	2008	
	B3010 ROOF COVERINGS	2008 A B301004 FLASHINGS & TRIM General	82 (LF)	2008	
	B3010 ROOF COVERINGS	2008 B B301004 FLASHINGS & TRIM General	262 (LF)	2008	2008
C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	2008 C101001 FIXED PARTITIONS Wall - Drywall w/Steel Framing	53,000 (SF)	2008	2014
	C1010 PARTITIONS	2008 C101005 INTERIOR WINDOWS Interior Windows	21 (EA)	2008	
	C1020 INTERIOR DOORS	2008 C102001 STANDARD INTERIOR DOORS Wood Door/Metal Frame	80 (EA)	2008	
	C1020 INTERIOR DOORS	2008 C102002 GLAZED INTERIOR DOORS General	1 (EA)	2008	
	C1020 INTERIOR DOORS	2008 C102003 FIRE DOORS Fire Door - Swinging, Metal	19 (EA)	2008	
	C1030 SPECIALTIES	2008 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Shower Compartment	18 (EA)	2008	
	C1030 SPECIALTIES	2008 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions	12 (EA)	2008	
	C1030 SPECIALTIES	2008 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Urinal Screen	3 (EA)	2008	
	C1030 SPECIALTIES	2008 C103002 TOILET & BATH ACCESSORIES General	35 (EA)	2008	



System Inventory Report



NAS1 Support Area

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	C1030 SPECIALTIES	2008 C103003 MARKER BOARDS & TACK BOARDS General	53 (EA)	2008	
	C1030 SPECIALTIES	2008 C103005 LOCKERS General	304 (EA)	2008	
	C1030 SPECIALTIES	2008 C103006 SHELVING General	28 (LF)	2008	
	C1030 SPECIALTIES	2008 C103008 COUNTERS Laminated Plastic	833 (LF)	2008	
	C1030 SPECIALTIES	2008 C103009 CABINETS Other	1,137 (LF)	2008	
	C1030 SPECIALTIES	2008 C103010 CASEWORK General	87 (LF)	2008	
C20 STAIRS	C2010 STAIR CONSTRUCTION	2008 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Concrete (12 Riser Flight)	1 (EA)	2008	
	C2010 STAIR CONSTRUCTION	2008 C201001 INTERIOR AND EXTERIOR STAIRS Interior Stairs	2 (EA)	2008	
	C2010 STAIR CONSTRUCTION	2008 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General	680 (LF)	2008	2008
	C2010 STAIR CONSTRUCTION	2008 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General	125 (LF)	2008	2008
C30 INTERIOR FINISHES	C3010 WALL FINISHES	2008 C301004 TILE & TERRAZZO WALL FINISHES Tile	10,306 (SF)	2008	
	C3020 FLOOR FINISHES	2008 C302001 TILE FLOOR FINISHES Ceramic Tile	9,105 (SF)	2008	
	C3020 FLOOR FINISHES	2008 C302003 WOOD FLOORING General	6,855 (SF)	2008	
	C3020 FLOOR FINISHES	2008 C302004 RESILIENT FLOOR FINISHES Composition Sheet	7,449 (SF)	2008	
	C3020 FLOOR FINISHES	2008 C302005 CARPETING Carpet Tile	13,005 (SF)	2008	
	C3030 CEILING FINISHES	2008 C303001 ACOUSTICAL CEILING TILES & PANELS General	22,942 (SF)	2008	
	C3030 CEILING FINISHES	2008 C303002 GYPSUM WALLBOARD CEILING FINISHES General	4,286 (SF)	2008	2014
	C3030 CEILING FINISHES	2008 C303005 SUSPENSION SYSTEMS General	22,942 (SF)	2008	
D10 CONVEYING	D1010 ELEVATORS AND LIFTS	2008 ELEV #2 D101002 PASSENGER ELEVATORS Hydraulic Elevators - 1500 lb, 5 floors	1 (EA)	2008	
D20 PLUMBING	D2010 PLUMBING FIXTURES	2008 D201001 WATERCLOSETS General	19 (EA)	2008	
	D2010 PLUMBING FIXTURES	2008 D201002 URINALS General	5 (EA)	2008	
	D2010 PLUMBING FIXTURES	2008 D201004 SINKS General	20 (EA)	2008	
	D2010 PLUMBING FIXTURES	2008 D201004 SINKS Kitchen Sink	10 (EA)	2008	
	D2010 PLUMBING FIXTURES	2008 D201004 SINKS Laboratory Sink	26 (EA)	2008	
	D2010 PLUMBING FIXTURES	2008 D201004 SINKS Service Sink	4 (EA)	2008	
	D2010 PLUMBING FIXTURES	2008 D201005 SHOWERS/TUBS Shower	18 (EA)	2008	
	D2010 PLUMBING FIXTURES	2008 D201006 DRINKING FOUNTAINS AND COOLERS Water Cooler	12 (EA)	2008	
	D2010 PLUMBING FIXTURES	2008 D201090 OTHER PLUMBING FIXTURES Emergency Eye Wash	3 (EA)	2008	
	D2010 PLUMBING FIXTURES	2008 D201090 OTHER PLUMBING FIXTURES Emergency Shower	3 (EA)	2008	



System Inventory Report



NAS1 Support Area

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D2010 PLUMBING FIXTURES	2008 D201090 OTHER PLUMBING FIXTURES Washer / Dryer Hookup	1 (EA)	2008	
	D2020 DOMESTIC WATER DISTRIBUTION	2008 D202001 PIPES & FITTINGS General	14,928 (LF)	2008	
	D2030 SANITARY WASTE	2008 D203001 WASTE PIPE & FITTINGS General	7,470 (LF)	2008	
	D2030 SANITARY WASTE	2008 D203002 VENT PIPE & FITTINGS General	1,816 (EA)	2008	
	D2030 SANITARY WASTE	2008 A D203003 FLOOR DRAINS General	18 (EA)	2008	
	D2030 SANITARY WASTE	2008 B D203003 FLOOR DRAINS General	3 (EA)	2008	
D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2008 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	1,500 (LF)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 D304001 AIR DISTRIBUTION, HEATING & COOLING VAV Terminals	30 (EA)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 D304002 HOT WATER DISTRIBUTION SYSTEMS General	1,200 (MBH)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	125 (TON)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 AHU/3 D304008 AIR HANDLING UNITS Central Station - 20000 CFM, VAV	1 (EA)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 AHU/4 D304008 AIR HANDLING UNITS Central Station - 20000 CFM, VAV	1 (EA)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 AHU/5 D304008 AIR HANDLING UNITS Central Station - 30000 CFM, VAV	1 (EA)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 HRU/3 D304008 AIR HANDLING UNITS Central Station - 10000 CFM	1 (EA)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 HRU/4 D304008 AIR HANDLING UNITS Central Station - 10000 CFM	1 (EA)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 ROOM 320 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 500 CFM	1 (EA)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 ROOM 320 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 5000 CFM	1 (EA)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 ROOM 320 D304007 EXHAUST SYSTEMS Fume Hood Exhaust System - 3', 1000 CFM	3 (EA)	2008	
	D3050 TERMINAL & PACKAGE UNITS	2008 D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air Cooled Condenser - 3 TN	4 (EA)	2016	
	D3060 CONTROLS & INSTRUMENTATION	2008 D306002 ELECTRONIC CONTROLS General	23 (EA)	2008	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SYSTEMS	2008 D401001 FIRE ALARM DISTRIBUTION Other	48,062 (SF)	2008	
	D4040 SPRINKLERS	2008 D404001 SPRINKLERS AND RELEASING DEVICES Wet Pipe Systems	48,062 (SF)	2008	



System Inventory Report



NAS1 Support Area

220 - Sigonella MS/HS Bldg 220

Sigonella MS/HS (HE5515)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 D501004 PANELBOARDS Main lugs, 50 amp	6 (EA)	2008	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp, NQOD	11 (EA)	2008	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 D501004 PANELBOARDS Safety Switch, 30-100 Amp	3 (EA)	2008	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 ROOM 035 D501002 SERVICE ENTRANCE EQUIPMENT Electrical Service - 3 Phase, 120/208 V, 800 A	1 (EA)	2008	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 ROOM 320 D501004 PANELBOARDS Main lugs, 120/240 V, 225 amp, NQOD	1 (EA)	2008	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 ROOM 41 D501004 PANELBOARDS Main lugs, 50 amp	1 (EA)	2008	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 ROOM 41 D501004 PANELBOARDS Main lugs, 125 amp	1 (EA)	2008	
	D5020 LIGHTING & BRANCH WIRING	2008 D502001 BRANCH WIRING General	48,062 (SF)	2008	
	D5020 LIGHTING & BRANCH WIRING	2008 D502002 LIGHTING EQUIPMENT Exit Lighting	22 (EA)	2008	
	D5020 LIGHTING & BRANCH WIRING	2008 D502002 LIGHTING EQUIPMENT Exterior Lighting	79 (EA)	2008	
	D5020 LIGHTING & BRANCH WIRING	2008 D502002 LIGHTING EQUIPMENT General	48,062 (SF)	2008	
	D5030 COMMUNICATIONS & SECURITY	2008 D503001 TELECOMMUNICATIONS SYSTEMS General	1 (EA)	2008	
	D5030 COMMUNICATIONS & SECURITY	2008 D503002 PUBLIC ADDRESS SYSTEMS 30 outlets	1 (EA)	2008	
	D5030 COMMUNICATIONS & SECURITY	2008 D503003 INTERCOMMUNICATIONS SYSTEMS 25 stations	1 (EA)	2008	
	D5030 COMMUNICATIONS & SECURITY	2008 D503005 SECURITY SYSTEMS General	1 (EA)	2008	
	D5030 COMMUNICATIONS & SECURITY	2008 D503007 CLOCK & PROGRAM SYSTEMS General	1 (EA)	2008	
	D5090 OTHER ELECTRICAL SERVICES	2008 D509002 EMERGENCY LIGHTING & POWER General	48,062 (SF)	2008	
	D5090 OTHER ELECTRICAL SERVICES	2008 D509003 GROUNDING SYSTEMS General	1 (EA)	2008	
	D5090 OTHER ELECTRICAL SERVICES	2008 D509006 ENERGY MANAGEMENT CONTROL SYSTEM General	48,062 (SF)	2008	



System Inventory Report



NAS1 Support Area

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
B10 SUPERSTRUCTURE	B1020 ROOF CONSTRUCTION	1999 B102003 ROOF DECKS AND SLABS Unknown	15,154 (SF)	1999	
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1999 B201001 EXTERIOR CLOSURE Stone Veneer w/CMU Backup	974 (SF)	1999	
	B2010 EXTERIOR WALLS	1999 B201001 EXTERIOR CLOSURE Stucco	16,594 (SF)	1999	2016
	B2010 EXTERIOR WALLS	1999 B201001 EXTERIOR CLOSURE Tile Veneer w/CMU Backup	314 (SF)	1999	
	B2010 EXTERIOR WALLS	1999 B201001 EXTERIOR CLOSURE Wall Louver	133 (SF)	1999	2016
	B2010 EXTERIOR WALLS	1999 B201006 BALCONY WALLS & HANDRAILS Handrailing	144 (LF)	1999	2016
	B2010 EXTERIOR WALLS	1999 B201007 EXTERIOR SOFFITS General	2,442 (SF)	1999	2016
	B2010 EXTERIOR WALLS	1999 A B201010 EXTERIOR JOINT SEALANT General	550 (LF)	1999	
	B2010 EXTERIOR WALLS	1999 A B201011 SUN CONTROL DEVICES General	390 (SF)	1999	2016
	B2010 EXTERIOR WALLS	1999 B B201010 EXTERIOR JOINT SEALANT General	20,000 (LF)	1999	
	B2010 EXTERIOR WALLS	1999 B B201011 SUN CONTROL DEVICES General	312 (SF)	1999	2016
	B2010 EXTERIOR WALLS	1999 B B201010 EXTERIOR JOINT SEALANT General	75 (LF)	1999	
	B2020 EXTERIOR WINDOWS	1999 B202001 WINDOWS Aluminum Windows	120 (EA)	1999	
	B2030 EXTERIOR DOORS	1999 B203001 SOLID DOORS Steel	7 (EA)	1999	2016
	B2030 EXTERIOR DOORS	1999 B203002 GLAZED DOORS General	10 (EA)	1999	2016
	B2030 EXTERIOR DOORS	1999 B203004 OVERHEAD AND ROLL-UP DOORS Steel Rolling, Manual, 8'x8'	2 (EA)	1999	
	B2030 EXTERIOR DOORS	1999 B203007 GATES General	400 (SF)	1999	2016
	B2030 EXTERIOR DOORS	1999 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door	10 (EA)	1999	
B30 ROOFING	B3010 ROOF COVERINGS	1999 B301001 STEEP SLOPE ROOF SYSTEMS Clay Tile	13,687 (SF)	1999	
	B3010 ROOF COVERINGS	1999 B301003 ROOF INSULATION & FILL General	13,687 (SF)	1999	
	B3010 ROOF COVERINGS	1999 B301004 FLASHINGS & TRIM Flashings - Apron	1,228 (LF)	2016	
	B3010 ROOF COVERINGS	1999 B301004 FLASHINGS & TRIM Flashings - Base	1,184 (LF)	2016	
	B3010 ROOF COVERINGS	1999 B301004 FLASHINGS & TRIM General	423 (LF)	1999	2016
	B3010 ROOF COVERINGS	1999 B301005 GUTTERS & DOWNSPOUTS Downspouts	226 (LF)	1999	1999
	B3010 ROOF COVERINGS	1999 B301005 GUTTERS & DOWNSPOUTS Gutters	741 (LF)	1999	
	B3010 ROOF COVERINGS	1999 B301090 OTHER ROOFING Walkway Protection	3,534 (SF)	2016	
	B3010 ROOF COVERINGS	1999 A B301004 FLASHINGS & TRIM Flashings - Cap	350 (LF)	1999	
	B3010 ROOF COVERINGS	1999 A B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	4 (EA)	2016	
	B3010 ROOF COVERINGS	1999 B B301004 FLASHINGS & TRIM Flashings - Cap	516 (LF)	1999	
	B3010 ROOF COVERINGS	1999 B B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	3 (EA)	2016	
C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	1999 C101001 FIXED PARTITIONS Wall - Drywall w/Stud Framing	14,400 (SF)	1999	2014
	C1010 PARTITIONS	1999 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing	1,662 (SF)	1999	2014



System Inventory Report



NAS1 Support Area

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	C1020 INTERIOR DOORS	1999 C102001 STANDARD INTERIOR DOORS Wood Door/Wood Frame	23 (EA)	1999	
	C1030 SPECIALTIES	1999 C103002 TOILET & BATH ACCESSORIES General	24 (EA)	1999	
	C1030 SPECIALTIES	1999 C103003 MARKER BOARDS & TACK BOARDS General	17 (EA)	1999	
	C1030 SPECIALTIES	1999 C103008 COUNTERS Laminated Plastic	66 (LF)	1999	
	C1030 SPECIALTIES	1999 C103008 COUNTERS Metal	73 (LF)	1999	
	C1030 SPECIALTIES	1999 C103009 CABINETS Other	361 (LF)	1999	
	C1030 SPECIALTIES	1999 C103010 CASEWORK General	75 (LF)	1999	
C20 STAIRS	C2010 STAIR CONSTRUCTION	1999 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Steps - Concrete	3 (EA)	1999	
C30 INTERIOR FINISHES	C3010 WALL FINISHES	1999 C301001 TILE & TERRAZZO WALL FINISHES General	3,700 (SF)	1999	
	C3020 FLOOR FINISHES	1999 C302001 TILE FLOOR FINISHES Ceramic Tile	9,389 (SF)	1999	
	C3030 CEILING FINISHES	1999 C303001 ACOUSTICAL CEILING TILES & PANELS General	5,952 (SF)	1999	
	C3030 CEILING FINISHES	1999 C303002 GYPSUM WALLBOARD CEILING FINISHES General	3,664 (SF)	1999	2014
	C3030 CEILING FINISHES	1999 C303005 SUSPENSION SYSTEMS General	5,952 (SF)	1999	
D20 PLUMBING	D2010 PLUMBING FIXTURES	1999 D201001 WATER CLOSURES General	8 (EA)	1999	
	D2010 PLUMBING FIXTURES	1999 D201004 SINKS General	15 (EA)	1999	
	D2010 PLUMBING FIXTURES	1999 D201004 SINKS Kitchen Sink	4 (EA)	1999	
	D2010 PLUMBING FIXTURES	1999 D201004 SINKS Service Sink	1 (EA)	1999	
	D2010 PLUMBING FIXTURES	1999 D201005 SHOWERS/TUBS Showers	1 (EA)	1999	
	D2020 DOMESTIC WATER DISTRIBUTION	1999 D202001 PIPES & FITTINGS General	3,973 (LF)	1999	
	D2020 DOMESTIC WATER DISTRIBUTION	1999 D202003 DOMESTIC WATER EQUIPMENT Water Heaters, Commercial, Electric - 50 gal, 9 KW, 37 GPH	4 (EA)	1999	
	D2020 DOMESTIC WATER DISTRIBUTION	1999 ROOM 17 D202002 VALVES & HYDRANTS Backflow Preventer - 1.5" pipe	1 (EA)	1999	
	D2020 DOMESTIC WATER DISTRIBUTION	1999 ROOM 17 D202003 DOMESTIC WATER EQUIPMENT Storage Tank - Galvanized steel, 135 gallon, 24" diameter, 75" L.O.A.	1 (EA)	1999	
	D2020 DOMESTIC WATER DISTRIBUTION	1999 ROOM 17 D202003 DOMESTIC WATER EQUIPMENT Water Softener	1 (EA)	1999	
	D2030 SANITARY WASTE	1999 D203001 WASTE PIPE & FITTINGS General	1,990 (LF)	1999	
	D2030 SANITARY WASTE	1999 D203002 VENT PIPE & FITTINGS General	483 (EA)	1999	
	D2030 SANITARY WASTE	1999 D203003 FLOOR DRAINS General	2 (EA)	1999	
D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1999 ROOM 17 D302001 BOILERS Gas, Hot Water - 250-400 MBH	1 (EA)	2002	



System Inventory Report



NAS1 Support Area

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D3020 HEAT GENERATING SYSTEMS	1999 ROOM 17 D302004 AUXILIARY EQUIPMENT Expansion Tank - 15 gal	1 (EA)	2002	
	D3020 HEAT GENERATING SYSTEMS	1999 ROOM 17 D302004 AUXILIARY EQUIPMENT Expansion Tank - 30 gal	1 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	1999 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	2,383 (LF)	1999	
	D3040 DISTRIBUTION SYSTEMS	1999 D304003 HOT WATER DISTRIBUTION SYSTEMS General	320 (MBH)	1999	
	D3040 DISTRIBUTION SYSTEMS	1999 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	32 (TON)	1999	
	D3040 DISTRIBUTION SYSTEMS	1999 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 300 CFM	9 (EA)	1999	
	D3040 DISTRIBUTION SYSTEMS	1999 ROOM 17 D304001 AIR DISTRIBUTION, HEATING & COOLING Air Separator - Air control, air separator, 3" diameter, includes strainer	2 (EA)	1999	
	D3040 DISTRIBUTION SYSTEMS	1999 ROOM 17 D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating Pump, End Suction - 2-1/2" size, 3 HP, to 150 GPM	2 (EA)	1999	
	D3040 DISTRIBUTION SYSTEMS	1999 ROOM 17 D304006 CHILLED WATER DISTRIBUTION SYSTEMS Circulating Pump, End Suction - 2-1/2" size, 3 HP, to 150 GPM	2 (EA)	1999	
	D3050 TERMINAL & PACKAGE UNITS	1999 D305003 FAN COIL UNITS Duct Mount, 4 Pipe - 2 ton	11 (EA)	1999	
	D3050 TERMINAL & PACKAGE UNITS	1999 D305003 FAN COIL UNITS Duct Mount, 4 Pipe - 5 ton	7 (EA)	1999	
	D3050 TERMINAL & PACKAGE UNITS	1999 D305004 FIN TUBE RADIATION Other	8 (EA)	1999	
	D3050 TERMINAL & PACKAGE UNITS	1999 ROOM 19 D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air Cooled Condenser - 2 TN	1 (EA)	1999	
	D3060 CONTROLS & INSTRUMENTATION	1999 D306002 ELECTRONIC CONTROLS General	18 (EA)	1999	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SYSTEMS	1999 D401001 FIRE ALARM DISTRIBUTION Other	12,792 (SF)	1999	
	D4040 SPRINKLERS	1999 D404001 SPRINKLERS AND RELEASING DEVICES Wet Pipe Systems	12,792 (SF)	1999	
D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 D501006 MOTOR CONTROL CENTERS Motor Control Center - Size 4, 100 HP, 30" high	1 (EA)	2002	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 ROOM 15 D501002 SERVICE ENTRANCE EQUIPMENT Electrical Service - 3 Phase, 120/208 V, 400 A	2 (EA)	2002	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 ROOM 15 D501003 INTERIOR DISTRIBUTION TRANSFORMERS dry-type, 480 V primary 120/208 V secondary, 15 kVA	1 (EA)	1999	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 ROOM 15 D501004 PANELBOARDS Main lugs, 50 amp	3 (EA)	1999	



System Inventory Report



NAS1 Support Area

213 - Sigonella ES Bldg 213

Sigonella ES (HE5555)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1999 ROOM 17 D501004 PANELBOARDS Main lugs, 120/240 V, 225 amp, NQOD	2 (EA)	1999	
	D5020 LIGHTING & BRANCH WIRING	1999 D502001 BRANCH WIRING General	12,792 (SF)	1999	
	D5020 LIGHTING & BRANCH WIRING	1999 D502002 LIGHTING EQUIPMENT Exit Lighting	17 (EA)	1999	
	D5020 LIGHTING & BRANCH WIRING	1999 D502002 LIGHTING EQUIPMENT Exterior Lighting	55 (EA)	1999	
	D5020 LIGHTING & BRANCH WIRING	1999 D502002 LIGHTING EQUIPMENT General	12,792 (SF)	1999	
	D5030 COMMUNICATIONS & SECURITY	1999 D503001 TELECOMMUNICATIONS SYSTEMS General	1 (EA)	2015	
	D5030 COMMUNICATIONS & SECURITY	1999 D503002 PUBLIC ADDRESS SYSTEMS 12 outlets	1 (EA)	2014	
	D5030 COMMUNICATIONS & SECURITY	1999 D503003 INTERCOMMUNICATIONS SYSTEMS 6 stations	1 (EA)	1999	
	D5030 COMMUNICATIONS & SECURITY	1999 D503007 CLOCK & PROGRAM SYSTEMS General	1 (EA)	2008	
	D5090 OTHER ELECTRICAL SERVICES	1999 D509002 EMERGENCY LIGHTING & POWER General	12,792 (SF)	1999	
	D5090 OTHER ELECTRICAL SERVICES	1999 D509002 EMERGENCY LIGHTING & POWER Uninterruptible Power Supply - 0.5 kVA	1 (EA)	1999	
	D5090 OTHER ELECTRICAL SERVICES	1999 D509003 GROUNDING SYSTEMS General	1 (EA)	1999	



System Inventory Report



NAS1 Support Area

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	2008 B201001 EXTERIOR CLOSURE Stucco	32,828 (SF)	2008	2008
	B2010 EXTERIOR WALLS	2008 B201001 EXTERIOR CLOSURE Wall Louver	234 (SF)	2008	2008
	B2010 EXTERIOR WALLS	2008 B201007 EXTERIOR SOFFITS General	1,305 (SF)	2008	2008
	B2010 EXTERIOR WALLS	2008 B201011 SUN CONTROL DEVICES General	8 (SF)	2008	2008
	B2010 EXTERIOR WALLS	2008 A B201010 EXTERIOR JOINT SEALANT General	1,095 (LF)	2008	
	B2010 EXTERIOR WALLS	2008 B B201010 EXTERIOR JOINT SEALANT General	5,000 (LF)	2008	
	B2010 EXTERIOR WALLS	2008 C B201010 EXTERIOR JOINT SEALANT General	150 (LF)	2008	
	B2020 EXTERIOR WINDOWS	2008 B202001 WINDOWS Aluminum Windows	258 (EA)	2008	
	B2020 EXTERIOR WINDOWS	2008 B202002 STOREFRONTS General	192 (SF)	2008	
	B2030 EXTERIOR DOORS	2008 B203001 SOLID DOORS Steel	3 (EA)	2008	
	B2030 EXTERIOR DOORS	2008 B203002 GLAZED DOORS General	15 (EA)	2008	
	B2030 EXTERIOR DOORS	2008 B203003 GATES General	168 (SF)	2008	2008
	B2030 EXTERIOR DOORS	2008 B203004 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door	19 (EA)	2008	
B30 ROOFING	B3010 ROOF COVERINGS	2008 B301001 STEEL SLOPE ROOF SYSTEMS Clay Tile	45,000 (SF)	2008	
	B3010 ROOF COVERINGS	2008 B301003 ROOF INSULATION & FILL General	45,000 (SF)	2008	
	B3010 ROOF COVERINGS	2008 B301004 FLASHINGS & TRIM Flashings - Cap	530 (LF)	2008	
	B3010 ROOF COVERINGS	2008 B301004 FLASHINGS & TRIM Flashings - Flashing Penetrations	7 (EA)	2008	
	B3010 ROOF COVERINGS	2008 B301005 GUTTERS & DOWNSPOUTS Downspouts	985 (LF)	2008	2008
	B3010 ROOF COVERINGS	2008 B301005 GUTTERS & DOWNSPOUTS Gutters	800 (LF)	2008	
	B3010 ROOF COVERINGS	2008 B301006 ROOF OPENINGS AND SUPPORTS Hatches	4 (EA)	2008	
	B3010 ROOF COVERINGS	2008 A B301004 FLASHINGS & TRIM General	1,612 (LF)	2008	
	B3010 ROOF COVERINGS	2008 B B301004 FLASHINGS & TRIM General	179 (LF)	2008	2008
C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	2008 C101001 FIXED PARTITIONS Wall - Drywall w/ Stud Framing	54,000 (SF)	2008	2015
	C1010 PARTITIONS	2008 C101001 FIXED PARTITIONS Wall - Plaster w/ Stud Framing	39,300 (SF)	2008	2015
	C1010 PARTITIONS	2008 C101005 INTERIOR WINDOWS Interior Windows	14 (EA)	2008	
	C1020 INTERIOR DOORS	2008 C102001 STANDARD INTERIOR DOORS Wood Door/Metal Frame	128 (EA)	2008	
	C1020 INTERIOR DOORS	2008 C102003 FIRE DOORS Fire Door - Swinging, Metal	6 (EA)	2008	
	C1020 INTERIOR DOORS	2008 C102003 FIRE DOORS Fire Door - Swinging, Wood	13 (EA)	2008	
	C1030 SPECIALTIES	2008 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions	30 (EA)	2008	
	C1030 SPECIALTIES	2008 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Urinal Screen	8 (EA)	2008	
	C1030 SPECIALTIES	2008 C103002 TOILET & BATH ACCESSORIES General	58 (EA)	2008	
	C1030 SPECIALTIES	2008 C103003 MARKER BOARDS & TACK BOARDS General	251 (EA)	2008	
	C1030 SPECIALTIES	2008 C103006 SHELVING General	13 (LF)	2008	



System Inventory Report



NAS1 Support Area

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	C1030 SPECIALTIES	2008 C103008 COUNTERS Laminated Plastic	717 (LF)	2008	
	C1030 SPECIALTIES	2008 C103009 CABINETS Other	1,532 (LF)	2008	
	C1030 SPECIALTIES	2008 C103010 CASEWORK General	350 (LF)	2008	
C20 STAIRS	C2010 STAIR CONSTRUCTION	2008 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Concrete (12 Riser Flight)	1 (EA)	2008	
	C2010 STAIR CONSTRUCTION	2008 C201001 INTERIOR AND EXTERIOR STAIRS Interior Stairs	4 (EA)	2008	
	C2010 STAIR CONSTRUCTION	2008 A C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General	65 (LF)	2008	2008
	C2010 STAIR CONSTRUCTION	2008 B C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General	256 (LF)	2008	2008
C30 INTERIOR FINISHES	C3010 WALL FINISHES	2008 C301001 TILE & TERRAZZO WALL FINISHES General	17,545 (SF)	2008	
	C3020 FLOOR FINISHES	2008 C302001 TILE FLOOR FINISHES Ceramic Tile	13,400 (SF)	2008	
	C3020 FLOOR FINISHES	2008 C302001 TILE FLOOR FINISHES Marble Tile	2,120 (SF)	2008	
	C3020 FLOOR FINISHES	2008 C302004 RESILIENT FLOOR FINISHES Composition Sheet	7,000 (SF)	2008	
	C3020 FLOOR FINISHES	2008 C302005 CARPETING General	25,500 (SF)	2008	
	C3030 CEILING FINISHES	2008 C303001 ACoustical CEILING TILES & PANELS General	37,700 (SF)	2008	
	C3030 CEILING FINISHES	2008 C303002 GYPSUM WALLBOARD CEILING FINISHES General	5,790 (SF)	2008	2015
	C3030 CEILING FINISHES	2008 C303003 PLASTER CEILING FINISHES General	2,885 (SF)	2008	2015
	C3030 CEILING FINISHES	2008 C303005 SUSPENSION SYSTEMS General	37,700 (SF)	2008	
D20 PLUMBING	D2010 PLUMBING FIXTURES	2008 D201001 WATERCLOSETS General	40 (EA)	2008	
	D2010 PLUMBING FIXTURES	2008 D201002 URINALS General	10 (EA)	2008	
	D2010 PLUMBING FIXTURES	2008 D201004 SINKS General	32 (EA)	2008	
	D2010 PLUMBING FIXTURES	2008 D201004 SINKS Kitchen Sink	30 (EA)	2008	
	D2010 PLUMBING FIXTURES	2008 D201004 SINKS Service Sink	4 (EA)	2008	
	D2010 PLUMBING FIXTURES	2008 D201005 SHOWERS/TUBS Shower	1 (EA)	2008	
	D2010 PLUMBING FIXTURES	2008 D201006 DRINKING FOUNTAINS AND COOLERS Water Cooler	8 (EA)	2008	
	D2020 DOMESTIC WATER DISTRIBUTION	2008 D202001 PIPES & FITTINGS General	17,582 (LF)	2008	
	D2030 SANITARY WASTE	2008 D203001 WASTE PIPE & FITTINGS General	8,044 (LF)	2008	
	D2030 SANITARY WASTE	2008 D203002 VENT PIPE & FITTINGS General	2,138 (EA)	2008	
	D2030 SANITARY WASTE	2008 D203003 FLOOR DRAINS General	18 (EA)	2008	
D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2008 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	10,546 (LF)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 D304001 AIR DISTRIBUTION, HEATING & COOLING VAV Terminal	59 (EA)	2008	



System Inventory Report



NAS1 Support Area

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D3040 DISTRIBUTION SYSTEMS	2008 D304003 HOT WATER DISTRIBUTION SYSTEMS General	1,415 (MBH)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	142 (TON)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 AHU 8 D304008 AIR HANDLING UNITS Central Station - 5000 CFM, VAV	1 (EA)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 AHU-6 D304008 AIR HANDLING UNITS Central Station - 30000 CFM, VAV	1 (EA)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 AHU-7 D304008 AIR HANDLING UNITS Central Station - 30000 CFM, VAV	1 (EA)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 HRU 6 D304008 AIR HANDLING UNITS Central Station - 10000 CFM, VAV	1 (EA)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 D304007 D304008 AIR HANDLING UNITS Central Station - 15000 CFM, VAV	1 (EA)	2008	
	D3040 DISTRIBUTION SYSTEMS	2008 ROOM 318 D304007 EXHAUST SYSTEMS Fan System, Roof Exhaust - 2730 CFM	1 (EA)	2008	
	D3050 TERMINAL & PACKAGE UNITS	2008 D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air Cooled Condenser - 2 TN	4 (EA)	2016	
	D3060 CONTROLS & INSTRUMENTATION	2008 D306002 ELECTRONIC CONTROLS General	65 (EA)	2008	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SYSTEMS	2008 D401001 FIRE ALARM DISTRIBUTION Other	56,606 (SF)	2008	
	D4040 SPRINKLERS	2008 D404001 SPRINKLERS AND RELEASING DEVICES Wet Pipe Systems	56,606 (SF)	2008	
D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 D501004 PANELBOARDS Main lugs, 120/240 V, 100 amp, NQOD	21 (EA)	2008	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 D501004 PANELBOARDS Switchgear - 800 Amp	2 (EA)	2008	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 ROOM 318 D501004 PANELBOARDS Main lugs, 400 amp	1 (EA)	2008	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2008 ROOM 318 D501004 PANELBOARDS Main lugs, 600 amp	1 (EA)	2008	
	D5020 LIGHTING & BRANCH WIRING	2008 D502001 BRANCH WIRING General	56,606 (SF)	2008	
	D5020 LIGHTING & BRANCH WIRING	2008 D502002 LIGHTING EQUIPMENT Exit Lighting	38 (EA)	2008	
	D5020 LIGHTING & BRANCH WIRING	2008 D502002 LIGHTING EQUIPMENT Exterior Lighting	117 (EA)	2008	
	D5020 LIGHTING & BRANCH WIRING	2008 D502002 LIGHTING EQUIPMENT General	56,606 (SF)	2008	
	D5030 COMMUNICATIONS & SECURITY	2008 D503001 TELECOMMUNICATIONS SYSTEMS General	1 (EA)	2008	
	D5030 COMMUNICATIONS & SECURITY	2008 D503002 PUBLIC ADDRESS SYSTEMS 12 outlets	6 (EA)	2016	



System Inventory Report



NAS1 Support Area

218 - Sigonella ES Bldg 218

Sigonella ES (HE5555)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D5030 COMMUNICATIONS & SECURITY	2008 D503003 INTERCOMMUNICATIONS SYSTEMS 50 stations	1 (EA)	2008	
	D5030 COMMUNICATIONS & SECURITY	2008 D503007 CLOCK & PROGRAM SYSTEMS General	1 (EA)	2008	
	D5090 OTHER ELECTRICAL SERVICES	2008 D509002 EMERGENCY LIGHTING & POWER General	56,606 (SF)	2008	
	D5090 OTHER ELECTRICAL SERVICES	2008 D509002 EMERGENCY LIGHTING & POWER Uninterruptible Power Supply - 0.5 kVA	4 (EA)	2008	
	D5090 OTHER ELECTRICAL SERVICES	2008 D509003 GROUNDING SYSTEMS General	1 (EA)	2008	
	D5090 OTHER ELECTRICAL SERVICES	2008 D509004 LIGHTNING PROTECTION Unknown	56,606 (SF)	2008	
	D5090 OTHER ELECTRICAL SERVICES	2008 D509006 ENERGY MANAGEMENT CONTROL SYSTEM General	56,606 (SF)	2008	