

a
Representative Go1 trajectory on the X–Z plane
Ground truth
SPF
LPF
SAPF-Pred
outage
outage
SPF lags on the stairs
stairs
1.5 m climb
Z position (m)
X position (m)
b
Time-aligned terrain readout
Representative run: 90.3%
Three-run mean: 90.1 ± 1.0%
Ground-truth schedule
Online readout Ĉt
Tactile
Obstacle
Stairs
Flat
Terrain label Ct
red ticks: misclassified frames
Time (s)