V

Δ

to 10 AUG 2023


NC-1, 13 JUL 2023

WAAS CH 58030 W14A APP CRS Rwy Idg 3999 TDZE 1034 Apt Elev 1034

RNAV (GPS) RWY 14 MONTEVIDEO-CHIPPEWA COUNTY (MVE)

Baro-VNAV NA when using Granite Falls altimeter setting. For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -30°C (-22°F) or above 54°C (130°F). When local altimeter setting not received, use Granite Falls altimeter setting and increase LPV DA to 1320 feet; increase LNAV/VNAV DA to 1320 feet; increase all MDAs 40 feet and LNAV visibility Cats C/D $\frac{1}{8}$ SM and Circling visibility Cats C/D $\frac{1}{8}$ SM. DME/DME RNP-0.3 NA. Helicopter visibility reduction below 1 SM NA. When VGSI inop, Straight-in and Circling Rwy 14 procedures NA at night. Circling to Rwy 3-21 NA.

MISSED APPROACH: Climb to 3300 direct YIBUG and hold.



MONTEVIDEO, MINNESOTA Orig-B 07OCT21 MONTEVIDEO-CHIPPEWA COUNTY (MVE)

RNAV (GPS) RWY 14