V

Δ

SW-1, 13 JUL 2023

ō

10 AUG 2023

**፠** -26°C



## RNAV (RNP) RWY 6 GUNNISON-CRESTED BUTTE RGNL (GUC)


MALSF

RF and GPS required. When local altimeter setting not received,

RF and GPS required. When local altimeter setting not received, procedure NA. For uncompensated Baro-VNAV systems, procedure NA below -29°C [-20°F] or above 54°C [130°F]. When VGSI inoperative, procedure NA at night. Visibility reduction by helicopters NA. Missed approach requires RNP less than 1.0.

\* Missed approach requires minimum climb of 310 feet per NM to 9000. # Missed approach requires minimum climb of 260 feet per NM to 9000. For inoperative MALSF, increase RNP 0.11\* visibility to 1½, RNP 0.20 # to 1¾, RNP 0.26 † to 2, and RNP 0.30 to 2¼.

MISSED APPROACH: (Do not exceed 240 KIAS until RNGLE) Climb to 13000 via track 062° to POSLY, and via right turn to JENRO, and via right turn to TIPOC, and via right turn to RNGLE, and via track 306° to HBU VOR/DME and hold.



GUNNISON, COLORADO Orig-A 30JUN11

NA

8354-2

AUTHORIZATION REQUIRED

RNP 0.30 DA

GUNNISON-CRESTED BUTTE RGNL (GUC) RNAV (RNP) RWY 6

HIRL Rwy 6-24

REIL Rwy 24

NA

687 (700-2)