V

Δ

W

Ŗ

15 JUN 2023

ಠ

10 AUG 2023


RNAV (GPS) RWY 27

MERLE K (MUDHOLE) SMITH (CDV)(PACV)

Baro-VNAV NA. VDP NA with Valdez altimeter setting. For inoperative MALSR, increase LPV all Cats visibility to RVR 4500, LNAV/VNAV all Cats visibility to 11/2, LNAV Cats A/B visibility to RVR 5500, Cats C/D visibility to RVR 6000. When local altimeter setting not received use Valdez altimeter setting and increase all DA 113 feet and all MDA 120 feet, and increase LPV all Cats visibility to RVR 4000, increase LNAV/VNAV all Cats visibility to 1½, increase LNAV Cats C/D visibility to RVR 5500 For inoperative MALSR when using Valdez altimeter setting, increase LPV all Cats visibility to RVR 6000, LNAV Cats A/B visibility to RVR 5500, and LNAV Cats C/D visibility to $1\frac{1}{2}$.

Circling to Rwy 16/34 NA at night. Circling NA north of Rwy 9/27.

MISSED APPROACH: MALSR Climb to 600 then climbing left turn to 3000 direct CORVA and hold.



HIRL Rwy 9-27 0 CORDOVA, ALASKA Amdt 2B 12AUG21

466 (500-11/2) MERLE K (MUDHOLE) SMITH (CDV)(PACV)

520-11/5

460/40 407 (500-3/4)

1500-3

1446 (1500-3)

520-1

466 (500-1)

328/24 275 (300-1/2)

523/56 470 (500-11/4)

460-1

406 (500-1)

460/24 407 (500-1/2)

CATEGORY

DA

LPV

LNAV/ DA

VNAV

LNAV MDA

CIRCLING

275° to

RW27