



Creek Residences North Tower 2

Unit 777 · Apartment



DATE OF INSPECTION
19 July 2026



PROPERTY TYPE
Apartment



CONTRACT START
20 April 2026



CONTRACT END
19 April 2027

STATUS
Furnished

GK

LANDLORD

G [REDACTED] K [REDACTED] V [REDACTED]
p [REDACTED]@m [REDACTED].com

PE

TENANT

P [REDACTED] E [REDACTED] V [REDACTED] A [REDACTED]
[REDACTED]@gmail.com

TENANCY DETAILS

REPORT ID

SNF-CO-2026-2720740D

BASELINE REPORT

SNF-CI-2026-811A4BC8 · 19 July 2026

ANNUAL RENT

AED 118,000

TENANCY TYPE

Standard

CONTRACT STATUS

Completed

EJARI REFERENCE

042026-042027

BASELINE INTEGRITY

SHA-256 2ad14644...800b163c · Signed by all parties

SECURITY DEPOSIT

AED 5,900

FURNISHED

Yes

● EXECUTIVE SUMMARY

Check-out inspection of Creek Residences North Tower 2, Unit 777 conducted 19 July 2026 — 5 rooms, 10 photos, 6 photos recording issues. New damage since check-in is present in 3 rooms: Bathroom 1 shows 2 worsened stains (upper-centre approximately 3 cm and lower-centre approximately 2 cm); the Living Room has a new damp-related defect at the window sill with paint chipped and peeling approximately 5 cm exposing the white base coat; and Bedroom 1 has a new crack on the upper-left wall approximately 30 cm and a new stain on the lower-left wall approximately 10 cm, with pre-existing cracks on the ceiling and upper mid-section wall unchanged from check-in. The Entrance is clear of findings and the Kitchen scratch to the wall surface is unchanged from check-in. Of the 10 furnished inventory items, 3 have degraded or are missing since check-in — 1 item is missing and 2 have sustained new damage. Of the 5 keys issued at check-in, 1 access card was not returned. This report closes the tenancy record for the contract period 20 April 2026 – 19 April 2027.

Check-out Comparison

Dubai Creek Harbour · 19 July 2026



5

ROOMS INSPECTED



10

PHOTOS CAPTURED
vs check-in: 9



6

FINDINGS FLAGGED
vs check-in: 3

EVOLUTION SINCE CHECK-IN

Degraded

New 3	Damp · Living Room · Crack · Bedroom 1 · Stain · Bedroom 1
Worsened 1	Stain · Bathroom 1
Unchanged 2	Scratch · Kitchen · Crack · Bedroom 1
Resolved 0	—
Inventory 3	3 changes: Coffee table (Good ' Damaged) · Microwave (Good ' Damaged) · Mattress (Missing)
Keys 1	1 not returned: Access Card ×1

ROOM COMPARISON

Room	Check-in Photos	Check-out Photos	Findings (inbut)	Verdict
Entrance	1	1	0 -> 0	No change
Living Room	2	3	0 -> 1	Degraded
Kitchen	2	2	1 -> 1	No change
Bedroom 1	2	2	1 -> 3	Degraded
New: Crack, Stain				
Bathroom 1	2	2	1 -> 1	Degraded
Worsened: Stain				

FURNITURE

3
ITEMS DEGRADED OR MISSING

KEY RETURN

ITEM	GIVEN	RETURNED	STATUS
Door Keys	x2	x2	Returned
Parking Card	x1	x1	Returned
Access Card	x2	x1	Missing x1

● Access Card: missing x1

Entrance

1 photos captured

0 findings flagged

No change

CHECK-IN



CHECK-IN NOTE

ceiling clean · no cracks · walls clean · no stains · doors intact · door frames intact · floor tiles clean · no cracks · no stains

CHECK-OUT



CHECK-OUT NOTE

ceiling clean · walls clean · doors intact · door frames intact · floor tiles clean · no cracks · no stains

Living Room

3 photos captured 1 finding flagged

Degraded

CHECK-IN



CHECK-IN NOTE
ceiling clean · walls clean · floor tiles clean · no visible cracks · no stains · fixtures intact

CHECK-OUT



CHECK-OUT NOTE
ceiling clean · walls clean · floor tiles clean · no visible cracks · no stains · fixtures intact

CHECK-IN



CHECK-IN NOTE
ceiling clean · no cracks · walls clean · no stains · floor tiles clean · no defects · fixtures intact

CHECK-OUT



CHECK-OUT NOTE
ceiling clean · walls clean · floor tiles clean · fixtures intact · no defects

Living Room

3 photos captured

1 finding flagged

NEW DAMAGE



19 July 2026 at 15:25

DAMP

CHECK-OUT NOTE

living room window sill · paint chipped/peeling ~5cm · white base exposed

Kitchen

2 photos captured 1 finding flagged

No change

CHECK-IN



19 July 2026 at 15:13

CHECK-IN NOTE
ceiling clean · no visible cracks · walls clean · floor tiles clean · countertops intact · fixtures operational · no defects visible

CHECK-OUT



19 July 2026 at 15:23

CHECK-OUT NOTE
ceiling clean · no cracks · walls clean · floor tiles clean · countertops intact · fixtures operational · no defects visible

CHECK-IN



19 July 2026 at 15:13

SCRATCH
CHECK-IN NOTE
wall surface clean · multiple fine scratches scattered across wall · no cracks · no stains

CHECK-OUT



19 July 2026 at 15:23

SCRATCH
CHECK-OUT NOTE
multiple fine scratches scattered across wall unchanged · wall surface clean · no cracks · no stains

Bedroom 1

2 photos captured

3 findings flagged

CHECK-IN



19 July 2026 at 15:13

CHECK-IN NOTE

walls clean · no cracks · no stains · floor tiles clean · no defects · window frame intact

CHECK-OUT



19 July 2026 at 15:24

CRACK **STAIN**

CHECK-OUT NOTE

NEW crack on wall upper left ~30cm · NEW stain on wall lower left ~10cm

CHECK-IN



19 July 2026 at 15:13

CRACK

CHECK-IN NOTE

crack on ceiling near wall junction ~80cm · crack on upper wall mid-section ~60cm · ceiling-wall joint separation visible

CHECK-OUT



19 July 2026 at 15:24

CRACK

CHECK-OUT NOTE

crack on ceiling near wall junction ~80cm unchanged since check-in · crack on upper wall mid-section ~60cm unchanged since check-in · ceiling-wall joint separation visible unchanged since check-in

Bathroom 1

2 photos captured 1 finding flagged

CHECK-IN



CHECK-IN NOTE
ceiling clean · walls clean · floor tiles clean · bathtub intact · toilet intact · vanity
countertop clean · mirror intact · fixtures operational · no visible defects

CHECK-OUT



CHECK-OUT NOTE
ceiling clean · walls clean · floor tiles clean · bathtub intact · toilet intact · vanity
countertop clean · mirror intact · fixtures operational · no visible defects

CHECK-IN



STAIN

CHECK-IN NOTE
ceiling clean · two minor stains upper-center and lower-center · no cracks · no structural
defects

CHECK-OUT



STAIN

Worsened since check-in: stain

CHECK-OUT NOTE
stain upper-center ~3cm worsened since check-in · stain lower-center ~2cm worsened
since check-in

Check-in vs Check-out

10 items

LIVING ROOM

Coffee table

Furniture

Check-in: Good → Check-out: Damaged

NEW DAMAGE

CHECK - IN



CHECK - OUT



CHECK - OUT NOTE
Scratches on table

LIVING ROOM


Sofa

Furniture


Check-in: Fair → Check-out: Fair

NO CHANGE

CHECK - IN



CHECK - OUT



LIVING ROOM

TV

Electronics


Check-in: Good → Check-out: Good

● NO CHANGE

CHECK - IN



CHECK - OUT



LIVING ROOM


TV unit

Furniture


Check-in: New → Check-out: New

● NO CHANGE

CHECK - IN



CHECK - OUT



KITCHEN


Fridge

Appliances


Check-in: Good → Check-out: Good

● NO CHANGE

CHECK - IN



CHECK - OUT



KITCHEN

Microwave

Appliances

Check-in: Good → Check-out: Damaged

● NEW DAMAGE

CHECK - IN



CHECK - OUT



CHECK - OUT NOTE
Not working anymore

BEDROOM 1


Bed frame

Furniture


Check-in: Good → Check-out: Good

• NO CHANGE

CHECK - IN



CHECK - OUT



BEDROOM 1


Bedside lamp x2

Electronics


Check-in: Good → Check-out: Good

• NO CHANGE

CHECK - IN



CHECK - OUT



Check-in vs Check-out

10 items

BEDROOM 1


Bedside table x2

Furniture


Check-in: Good → Check-out: Good

• NO CHANGE

CHECK - IN



CHECK - OUT



BEDROOM 1


Mattress

Furniture


Check-in: Good → Check-out: Missing

• MISSING

CHECK - IN



CHECK - OUT



CHECK - OUT NOTE
Mattress gone



**This report has been reviewed
and agreed upon by all parties.**

Creek Residences North Tower 2 · 19 July 2026



Scan to verify this report

View the original online version, verify document authenticity, and access the full digital record. This QR code links directly to the inspection report on www.horizon-agency.ae.

LANDLORD

G [REDACTED] K [REDACTED] V [REDACTED]

● Signed on 19 July 2026 at 15:32

TENANT

P [REDACTED] E [REDACTED] V [REDACTED] A [REDACTED]

● Signed on 19 July 2026 at 15:33

INSPECTOR

Ahmed Agent

Horizon Properties · RERA #123489

● Signed on 19 July 2026 at 15:33

DOCUMENT INTEGRITY — SHA-256 HASH



d1cecbd8396084be5dae1c745baf476a977b522bea82b2d59672886b9b187c84

This report documents the condition of the property as observed at the time of inspection. It is based on a visual assessment only and does not constitute a structural, electrical, or plumbing survey. All parties are advised to review this report carefully. By signing, each party acknowledges the findings recorded herein.

This document is generated electronically and verified by SHA-256 hash.