
QA TEST 1 Example Road, QA1 1AA

Project Reference: QA-SAMPLE | NC Reference: NC-01

NON-COMPLIANCE

There are non-compliances regarding a minimum of 250mm clearance above the gas pipe entry tee. This is located towards the front of the side elevation.

ORIGINAL TRUSTMARK DEFECT PHOTOGRAPHS



REMEDIAL WORKS CARRIED OUT

Clearance above the gas entry tee was restored and a vent cover fitted.

BEFORE REMEDIATION



DURING REMEDIATION



COMPLETED WORK



MEASUREMENT / TEST EVIDENCE



Clearance measurement