Quality Report


Processed with ODX version 3.8.4

Dataset Summary

Date	27/10/2026 at 03:50:23
Area Covered	0.017080 km²
Processing Time	3.0m:42.0s
Capture Start	19/07/2019 at 10:12:55
Capture End	19/07/2019 at 10:26:05

Processing Summary

Reconstructed Images	36 over 36 shots (100.0%)
Reconstructed Points (Sparse)	8028 over 8238 points (97.5%)
Reconstructed Points (Dense)	729,054 points
Average Ground Sampling Distance	8.23 cm
Detected Features	1,649 features
Reconstructed Features	808 features
Geographic Reference	GPS
GPS errors	0.18 m




Previews



Orthophoto

Survey Data




GPS/GCP/3D Details

GPS	Mean	Standard Deviation	RMS Error
X Error (m)	-0.000	0.141	0.141
Y Error (m)	0.000	0.092	0.092
Z Error (m)	0.000	0.114	0.114
Total			0.180

3D	Mean	Standard Deviation	RMS Error
X Error (m)	0.079	0.148	0.168
Y Error (m)	0.094	0.149	0.176
Z Error (m)	0.279	0.468	0.545
Total			0.321

Accuracy	Absolute	Relative
Horizontal CE90 (m)	0.258	0.304
Vertical LE90 (m)	0.198	0.715


Features Details




	Min.	Max.	Mean	Median
Detected	1281	1903	1629	1649
Reconstructed	328	1121	749	808

Reconstruction Details

Average Reprojection Error (norm / pixels / angular)	0.15 / 0.82 / 0.00058
Average Track Length	3.36 images
Average Track Length (> 2)	4.77 images



Tracks Details



Length	2	3	4	5	6	7	8	9	10
Count	4075	1593	876	519	325	172	131	98	75

Camera Models Details

v2 sensefly s.o.d.a. 1600 1067 brown 0.7777

	k1	k2	k3	p1	p2	focal	aspect	cx	cy
Initial	0.0000	0.0000	0.0000	0.0000	0.0000	0.7778	1.0000	0.0000	0.0000
Optimized	-0.0068	0.0010	0.0106	-0.0020	0.0023	0.7913	1.0000	0.0058	-0.0135

