


profile # 5 receiver orientation # 3




profile # 5 receiver orientation # 3




2nd EQ simulator test problem






Uniform stress loading (0.1 MPa/yr) => non-uniform long-term slip

First event





Maximum rupture extent

