


Section of GIGW 3.0 and the requirement	Observations	Compliance Status (Yes/No)
5.1.24-Websites/apps must provide integration with popular social media.	<p>Social media handles present in the website are correctly pointed to requisite URLs</p> <p>There is no content present in the website wherein two way integration is implemented i.e. push content from website to social media platform and fetch content from social media into the website.</p>	NO
5.1.25-The language is free from spelling and grammatical errors.	<p>Few Spelling errors were found in the website.</p> <p>For e.g. Refer screenshot 4</p>	No
5.1.18-Minimum content as prescribed in the guidelines is present on the homepage/home screen and all subsequent pages/screens.	<p>Terms and conditions are not provided on the home page.</p> <p>For e.g. Refer Screenshot 1</p>	NO
5.1.6: Complete information including title, size, format and usage instructions is provided for all downloadable material.	<p>File size and file language are not mentioned. The size must be mentioned for all downloadable material.</p> <p>for e.g. Refer screenshot 3</p>	NO
5.1.2- Ownership information is displayed on the homepage/ home screen and on all important entry pages/screens of the website/app and each subsequent page/screen is a standalone entity in terms of ownership, navigation and context of content.	<p>Ownership information is not displayed.</p> <p>for e.g. refer screenshot 13</p>	NO
5.1.17-Proper page title and language attribute along with metadata for page like keywords and description are appropriately included.	<p>All the necessary metadata is not provided.</p> <p>for e.g. refer screenshot 05</p>	NO

Section of GIGW 3.0 and the requirement	Observations	Compliance Status (Yes/No)
Accessibility Guidelines		
5.2.38-The default human language of each Web page can be programmatically determined.	<p>The language of the page is not indicated programmatically using the lang attribute. For e.g. Refer screenshot 6</p>	NO
5.2.39-The human language of each passage or phrase in the content can be programmatically determined except for proper names, technical terms, words of indeterminate language and words or phrases that have become part of the vernacular of the immediately surrounding text.	<p>The PDF is not tagged, so it is not accessible to screen readers and similar assistive technologies. All the documents must be tagged. For e.g. Refer Screenshot 7(a) and 7 (b)</p>	NO
5.2.46-If an input error is automatically detected and suggestions for correction are known, then the suggestions are provided to the user, unless it would jeopardize the security or purpose of the content.	<p>The error message only says “valid email”. It does not explain the required format. For e.g Refer screenshot 08</p>	No
5.2.32-Headings and labels describe topic or purpose.	<p>Heading tags (H1–H6) are not in the proper hierarchy. For e.g. Refer Screenshot 09 (a) and 09(b)</p>	NO
5.2.1-All non-text content that is presented to the user has a text alternative that serves the equivalent purpose, except for the situations listed below.	<p>Self-explanatory text alternatives are not provided for many images. Every image must have a clear, self-explanatory text alternative on all pages of the website. For e.g. refer screenshot 02</p>	NO
5.2.7-Information, structure and relationships conveyed through presentation can be programmatically determined or are available in text.	<p>After disabling CSS, the same content is rendered twice on the page. For e.g. Refer screenshot 10</p>	NO
5.1.15-Website uses Cascading Style Sheets (CSS) to control layouts/styles and incorporates responsive design features to ensure that the interface displays well on different screen size	<p>Website has CSS errors for e.g. refer Screenshot 11</p>	NO

5.2.33-Any keyboard operable user interface has a mode of operation where the keyboard focus indicator is visible	Focus is not clearly visible For e.g. refer screenshot 12	NO
---	---	----

Screenshots

Screenshot 01- Terms and conditions are not provided on the home page.




The screenshot shows the footer section of the tcil.net.in website. The footer is divided into several sections:

- About Us:** Company Profile, Mission & Vision, Joint Ventures & Subsidiaries, Organisation, Board of Directors, Awards & Achievements, Our Presence.
- Services:** Telecom, Information Technology, Architecture & Civil Division, Global Presence.
- Other Links:** Website Policies, Accessibility Statement.
- Contact Us (Corporate Office):** TCIL Bhawan, Greater Kailash-1, New Delhi, +91-11-26202020, +91-11-26242266, CIN : U74999DL1978GOI008911, tcil@tcil.net.in. It also includes a note: "for any queries or grievances, please visit [Contact Us](#)".
- Social Links:** Facebook, Twitter, Instagram.


At the bottom of the footer, there is a small disclaimer: "Disclaimer | Site Map". Copyright information states: "Copyright © 2024. All rights reserved by Telecommunications consultants India Limited, a Public Sector Undertaking of Government of India under Department of Telecommunication, Ministry of Communication. Last Updated: January 01 2026 05:58:42. You are visitor No.: 9362133".

Screenshot 2 - Text alternative is not provided.



The screenshot shows a web browser displaying the homepage of Telecommunications Consultants India Limited (TCIL). The URL in the address bar is `tcl.net.in/e-waste.management.php`. The page features a red header bar with the TCIL logo and the text "Telecommunications Consultants India Limited (A Government of India Enterprise)". Below the header is a navigation menu with links to "About Us", "Services", "Business Information", "Tender", "Career", and "Contact Us". A search bar is located in the top right corner. A red box highlights the `alt="e-waste recycling"` attribute of an image on the left side of the page. The main content area has a blue background image of a telecommunications tower and a hand holding a device. To the right, there is a sidebar titled "Services" with categories: Telecom, IT, Training, and e-Waste Management, where "e-Waste Management" is highlighted in blue.

Screenshot 3 - File size and file language are not mentioned. The size must be mentioned for all downloadable material.



The screenshot shows a web browser displaying the "List of Banned Suppliers" page from the TCIL website. The URL in the address bar is `tcl.net.in/list_of_banned_suppliers.php`. The page title is "List of Banned Suppliers". The main content is a table with four columns: "BANNED SUPPLIER", "BANNED DATE", "BANNED BY", and "BANNING PERIOD". The table contains five rows of data, each listing a supplier name, their address, the date they were banned, the division that banned them, and the duration of the ban. A red box highlights the first row of the table. To the right of the table is a sidebar titled "Tender" with options: "Tenders (NIT)", "Integrity Pact", and "List of Banned Suppliers", where "List of Banned Suppliers" is highlighted in blue.

BANNED SUPPLIER	BANNED DATE	BANNED BY	BANNING PERIOD
1. M/s. Paramount Communications Ltd., C-125, Naraina Industrial Area, Phase-I New Delhi - 110028	08-February-2022	IT & BD Division	5 Years
2. M/s. Colleen Lalsangpuii, A-57, Lower Zarkawt, Aizawl Aizawl,Mizoram - 796001	29-March-2022	MM-Civil Division	5 Years
3. M/s. J.R. Construction, Zarkawt, Aizawl Mizoram - 796001	29-March-2022	MM-Civil Division	5 Years
4. M/s. Kislay Enterprises, Flat No. 201, Block F, Kashyap Green City, Kothwan, Rupaspur Nahar, Bailey Road, Patna - 801105 (Bihar)	29-March-2022	MM-Civil Division	5 Years
5. M/s. M L Enterprises,	29-March-2022	MM-Civil Division	5 Years

Screenshot 4 - Few Spelling errors were found in the website.

Spelling Errors	
Spelling	URL
1. commissoning	https://www.tcil.net.in/telecom_services.php
2.initatives	https://www.tcil.net.in/business_and_social_vision.php
3.specifc	https://www.tcil.net.in/business_and_social_vision.php
4.ofsatellitenetworks	https://www.tcil.net.in/satcom_services.php
5.inthe	https://www.tcil.net.in/satcom_services.php

Screenshot 5 - All the necessary metadata is not provided.

Web Developer chrome-extension://bfbameneiokkgbdmiekjhnmfkcnldhhm/generated/view-meta-tag-information.html

Web Developer Meta Tags

<https://www.tcil.net.in/index.php>

3 meta tags

Name	Content
charset	utf-8
description	Website of Telecommunications Consultants India Limited https://www.tcil.net.in
viewport	width=device-width, initial-scale=1.0, shrink-to-fit=no

Web Developer is free, but your donation allows me to continue my development and any amount is greatly appreciated.

Donate

Collapse all Expand all

https://www.tcil.net.in/index.php

3 meta tags

Screenshot 6 – The language of the page is not indicated programmatically using the lang attribute.


The screenshot shows a web browser window with the URL tcil.net.in/contact_us.php?lan=hi. The page itself is in Hindi, with text like "संपर्क करें" and "मुख्य पृष्ठ / संपर्क करें". However, the browser's developer tools (Elements tab) reveal that the page is actually rendered from English HTML code. The code includes elements like "fontawesome-i2svg-active fontawesome-i2svg-complete" and "body" with various CSS styles applied. This indicates a lack of proper language declaration (lang attribute) in the HTML, which is required for screen readers and other assistive technologies to correctly interpret the content.

Screenshot 7 (a)– The PDF is not tagged, so it is not accessible to screen readers and similar assistive technologies

The screenshot shows a web browser window with the URL tcil.net.in/current_opening.php. The main content area displays a table titled "वर्तमान अवसर" (Current Vacancies). One row in the table is highlighted with a red box, specifically the row for "Advertisement for Recruitment of Manpower For Bihar State Wide Area Network, Version 3.0 (BSWAN 3.0) on Contract Basis (551.65 KB, EN)". To the right of the table, there is a sidebar with the heading "कैरियर" (Career) and a sub-section "वर्तमान अवसर" (Current Vacancies) containing the text "आकर्षित अवसर देखने के लिए यहां बिलकु करें". The browser's developer tools are visible on the right side, showing the underlying HTML structure of the page.

हमारे बारे में	सेवाएं	अग्र लिंक	संपर्क करें (कर्मचारी कार्यालय)
कंपनी प्रोफाइल लक्ष्य एवं दाखिला प्रक्रिया	दूरसंचार सूचना प्रौद्योगिकी	वेबसाइट नीतियां अभिगम्यता कथन	टीचीआईएल भवन, घेटोर केलाशा-1, नई दिल्ली +91-11-26202020

Screenshot 7(b)-



Screenshot 08 – The error message only says “valid email”. It does not explain the required format.

A screenshot of a web browser displaying a feedback form. The URL in the address bar is "tail.net.in/tcl_feedback.php". The form has several fields: "Name:" (mandatory), "Email:" (mandatory), "Your Feedback:", and "Captcha (enter the text shown below):". The "Email:" field is highlighted with a red border and contains the error message "Email is required.". The "Captcha" field shows the text "4EM6TY" with a speaker icon. The "Feedback" button is located in a blue header bar. The "Preview" button is at the bottom left of the form area.


Screenshot 09(a) – Heading tags (H1–H6) are not in the proper hierarchy.

The screenshot shows a web page with a sidebar on the left containing a 'Structure' tool from WAVE. The sidebar lists various sections: Header, Navigation, Navigation, Main, Information about TCIL, Vision of TCIL, Mission of TCIL, CMDs Address to TCILians, and Info Center. The main content area features several boxes with headings. Three specific boxes are highlighted with red borders: 'About TCIL' (h1), 'Vision' (h1), and 'CMDs Address to TCILians' (h1). Below these, another box contains 'Mission' (h1). The 'Info Center' section (h2) is also highlighted with a red border. The 'Global Presence' section (h2) is at the bottom right. A banner at the top states: 'TCIL honoured with the "COMPANY OF THE YEAR" award at the Asia Business Leader 2025, held in Singapore on 11th Aug 2025.'

Screenshot 09 (b) –

This screenshot shows the same website layout as above, but with different content in the main sections. The 'Structure' tool in the sidebar remains the same. The main content area now includes a box for 'Info Center' (h2), which is highlighted with a red border. Below it are boxes for 'News & Events' (h3), 'Photo Gallery' (h3), 'TCIL e-Magazines' (h3), and 'Right to Information' (h3). To the right, there is a 'Global Presence' section (h2) with a world map showing locations like KUWAIT, SAUDI ARABIA, OMAN, NEPAL, and NEW DELHI HEADQUARTER, which is also highlighted with a red border. At the bottom right, there is an 'Employee Section' (h3) highlighted with a red border. Navigation links at the bottom include 'TCIL Information System(TIS)', 'TAPAS ERP', and 'E-mail Login'. A banner at the top right states: 'Recent years has been one of resilience, transformation, and sustained growth—and each one of you has been an integral part of this progress. [Read More...](#)'.

Screenshot 10 – After disabling CSS, the same content is rendered twice on the page.



Screenshot 11- Website has CSS errors.

A screenshot of the W3C CSS Validator service at 'jigsaw.w3.org/css-validator/validator?profile=css3&warning=0&uri=https%3A%2F%2Fwww.tcl.net.in%2Fboard_of_directors.php'. The page title is 'The W3C CSS Validation Service'. It shows validation results for the URL 'https://www.tcl.net.in/board_of_directors.php' (CSS level 3). A red banner at the top states 'Sorry! We found the following errors (37)'. Below this, a table lists 37 errors, each with a link to the specific CSS rule. The errors include issues like 'Property pointer-events doesn't exist : none' and 'Property clip-path doesn't exist : inset(50%)'. The browser's address bar shows the URL 'https://www.tcl.net.in/board_of_directors.php'.

Screenshot 12 - Focus is not clearly visible.

The screenshot shows the homepage of the TCIL website. The layout includes several sections: 'About TCIL' (describing TCIL as a prime engineering and consultancy company), 'Vision' (stating the goal of excelling in providing solutions in Information and Communication Technology, Power and Infrastructure Sectors globally), 'Mission' (describing the mission to excel and maintain leadership in various sectors), 'CMDs Address to TCILians' (a message from the CMD), 'Info Center' (with a 'News & Events' section showing a recent event on 13-11-2025), and 'Global Presence' (a world map showing TCIL's offices in India, Africa, and Asia). A red box highlights the 'View All' button in the News & Events section.

Screenshot 13- Ownership information is not displayed properly.

The screenshot shows the footer section of the TCIL website. It contains four main columns: 'About Us' (links to Company Profile, Mission & Vision, Joint Ventures & Subsidiaries, Organisation, Board of Directors, Awards & Achievements, and Our Presence); 'Services' (links to Telecom, Information Technology, Architecture & Civil Division, and Global Presence); 'Other Links' (links to Website Policies and Accessibility Statement); and 'Contact Us (Corporate Office)' (information about the office location, phone numbers, CIN number, email address, and social media links). A red box highlights the 'Contact Us' link in the footer.